

DISTRICT 7 REPORT
JUNE 2015

STATEWIDE
**Airfield
Pavement
Management**
PROGRAM



TABLE OF CONTENTS

| | |
|---|----|
| Executive Summary | 1 |
| 1. Introduction..... | 15 |
| 2. Airfield Pavement System Inventory and Network Update..... | 25 |
| 3. Airfield Pavement Condition Analysis and Evaluation | 29 |
| 4. Pavement Performance Modeling | 39 |
| 5. Maintenance Level Activities..... | 45 |
| 6. Major Rehabilitation Needs..... | 53 |
| 7. Conclusion..... | 57 |

LIST OF TABLES

| | |
|---|----|
| Table I: Condition Summary by Airport | 2 |
| Table II: Runway Condition Summary by Airport..... | 3 |
| Table III: District Summary of Area by Use by Airport..... | 5 |
| Table IV: Summary of Year 1 Major Rehabilitation Needs | 8 |
| Table V: Summary of 10-Year Major Rehabilitation Costs by Airport..... | 10 |
| Table VI: Major Rehabilitation by Condition | 11 |
| Table 2-1: Summary of Area by Facility Use by Airport | 27 |
| Table 3-1: Distress Updates to Reflect ASTM D 5340-12..... | 31 |
| Table 3-1: Airfield Pavement Distresses for Asphalt Concrete | 32 |
| Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete | 33 |
| Table 3-3: District Condition Summary by Airport | 35 |
| Table 4-1: Overall Airport Area-Weighted PCI..... | 42 |
| Table 4-2: Airport Runway Area-Weighted PCI..... | 43 |
| Table 4-3: Airport Taxiway Area-Weighted PCI | 43 |
| Table 4-4: Airport Apron Area-Weighted PCI..... | 44 |
| Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy | 45 |
| Table 5-2: Recommended PCC Maintenance and Repair Policy | 46 |
| Table 5-3: Critical PCI and FDOT Minimum Level PCI..... | 49 |

Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI..... 49

Table 5-5: Flexible Asphalt Concrete Maintenance Unit Costs 51

Table 5-6: Rigid Portland Cement Concrete Maintenance Unit Costs..... 51

Table 5-7: Major Rehabilitation Activities and Unit Costs by Condition 52

Table 5-8: District 10-Year Maintenance and Preservation Needs by Airport 52

Table 6-1: Summary of District Year-1 Major Rehabilitation Needs..... 54

Table 6-2: Summary of District 10-Year Major Rehabilitation Needs..... 55

Table 6-3: Summary of District 10-Year Major Rehabilitation Needs by Airport..... 55

LIST OF FIGURES

Figure I: Runway Condition 3

Figure II: Runway Pavement Condition Index Comparison to FDOT Minimum PCI 4

Figure III: PCI by Pavement Facility Use by Airport..... 6

Figure IV: Visual Representation of PCI Ratings and Field Conditions Flexible
Asphalt Concrete Pavement 7

Figure V: Visual Representation of PCI Ratings and Field Conditions Rigid Portland
Cement Concrete Pavement..... 7

Figure 1-1: Pavement Condition Life Cycle..... 21

Figure 1-2: Flexible Pavement, Asphalt Concrete 24

Figure 1-3: Rigid Pavement, Portland Cement Concrete 24

Figure 2-1: District Pavement Area by Use 27

Figure 2-2: Pavement Area Use by Airport 28

Figure 3-1: Pavement Condition Index Rating Scale 34

Figure 3-2: PCI by Pavement Facility Use by Airport..... 36

Figure 3-3: PCI by Pavement Facility Use 37

Figure 3-4: PCI by Pavement Surface Type 38

Figure 4-1: Example Pavement Performance Model..... 41

APPENDICES

| | |
|------------|---|
| Appendix A | Glossary of Terms |
| Appendix B | District Branch Condition Report District Section Condition Report |
| Appendix C | District Airfield Pavement Condition Index Rating Exhibits |
| Appendix D | District 10- Year Major Rehabilitation Needs |
| Appendix E | District Airfield Pavement 10-Year Major Rehabilitation Exhibits |

EXECUTIVE SUMMARY

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2012, the Florida Department of Transportation Aviation and Spaceport Office selected a Consultant team consisting of Kimley-Horn and Associates, Inc. and their Subconsultants Penuel Consulting, LLC. And Roy D. McQueen and Associates, LTD. To provide services in support to FDOT in the continuing evaluation and updating of the existing Statewide Airfield Pavement Management Program (SAPMP) to be completed over fiscal year 2013 through 2015. Pavement Condition Index surveys were performed for airfield pavement facilities for the following airports located in District 7.

- BKV, Brooksville – Tampa Bay Regional Airport
- CGC, Crystal River Airport
- CLW, Clearwater Air Park
- INF, Inverness Airport
- PCM, Plant City Airport
- PIE, St. Petersburg-Clearwater International Airport
- SPG, Albert Whitted Airport
- TPF, Peter O. Knight Airport
- VDF, Tampa Executive Airport
- ZPH, Zephyrhills Municipal Airport

Tampa International Airport (TPA), which is managed by the Hillsborough County Aviation Authority, declined to participate in the FDOT SAPMP update and therefore was not included in the inspection efforts as part of this program update.

Since the previous update performed in 2012, significant updates to the ASTM D 5340 Standard Test Method for Airport Pavement Condition Index Surveys have affected the analysis of the program. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reaction distress for rigid pavement distresses. Additionally, the deterioration associated with the rigid pavement distress Scaling/Map Cracking has been modified. The change in distress classification, as described in ASTM D

5340-12, may result in small variances in the PCI values from the previous inspection analysis. The update included changes in distress deduction values that may be less than the previous analysis.

District 7’s overall area-weighted Pavement Condition Index (PCI) is at a 69.95, a condition rating of “Fair”. Table I: Condition Summary by Airport below represents of the results of the PCI inspection at each airport within the District. The overall area-weighted average PCI values for the participating airport facilities in District 7 ranged from 56 (Fair) to 95 (Good). Specific individual airport results are identified in the individual Airport Pavement Evaluation Reports provided to each airport. Table II: Runway Condition Summary by Airport indicates the PCI value for every runway within the District, grouped by Airport. Figure I: Runway Condition graphically depicts the percentage of the District’s Runways below the FDOT Minimum PCI of 75 and Figure II: Runway Pavement Condition Comparison to FDOT Minimum PCI conveys the PCI’s of the District’s runway facilities in comparison to the FDOT Minimum PCI of 75.

Table I: Condition Summary by Airport

| Network ID | Airport Type | Area-Weighted Pavement Condition Index (PCI) | | | | | | | |
|------------|--------------|--|--------------|---------|--------------|-------|--------------|------------------|--------------|
| | | Runway | | Taxiway | | Apron | | Overall Airfield | |
| | | PCI | PCI Rating | PCI | PCI Rating | PCI | PCI Rating | PCI | PCI Rating |
| BKV | GA | 54 | POOR | 52 | POOR | 68 | FAIR | 56 | FAIR |
| CGC | GA | 68 | FAIR | 87 | GOOD | 57 | FAIR | 71 | SATISFACTORY |
| CLW | RL | 100 | GOOD | 93 | GOOD | 57 | FAIR | 87 | GOOD |
| INF | GA | 97 | GOOD | 94 | GOOD | 93 | GOOD | 95 | GOOD |
| PCM | GA | 60 | FAIR | 71 | SATISFACTORY | 81 | SATISFACTORY | 71 | SATISFACTORY |
| PIE | PR | 71 | SATISFACTORY | 73 | SATISFACTORY | 63 | FAIR | 70 | FAIR |
| SPG | RL | 61 | FAIR | 60 | FAIR | 74 | SATISFACTORY | 65 | FAIR |
| TPF | RL | 70 | FAIR | 75 | SATISFACTORY | 82 | SATISFACTORY | 74 | SATISFACTORY |
| VDF | RL | 70 | FAIR | 71 | SATISFACTORY | 77 | SATISFACTORY | 73 | SATISFACTORY |
| ZPH | GA | 83 | SATISFACTORY | 55 | POOR | 67 | FAIR | 70 | FAIR |
| DISTRICT | | 69 | FAIR | 68 | FAIR | 71 | SATISFACTORY | 69 | FAIR |

Table II: Runway Condition Summary by Airport

| Network ID | Airport Type | Branch ID | Branch Name | Length (Feet) | Width (Feet) | Area-Weighted PCI | PCI Rating | Below FDOT Minimum PCI of 75 |
|------------|--------------|------------|----------------|---------------|--------------|-------------------|--------------|------------------------------|
| BKV | GA | RW 3-21 | RUNWAY 3-21 | 5,015 | 150 | 54 | POOR | X |
| BKV | GA | RW 9-27 | RUNWAY 9-27 | 7,002 | 150 | 54 | POOR | X |
| CGC | GA | RW 9-27 | RUNWAY 9-27 | 4,557 | 75 | 68 | FAIR | X |
| CLW | RL | RW 16-34 | RUNWAY 16-34 | 4,108 | 75 | 100 | GOOD | |
| INF | GA | RW 1-19 | RUNWAY 1-19 | 5,001 | 75 | 97 | GOOD | |
| PCM | GA | RW 10-28 | RUNWAY 10-28 | 3,948 | 75 | 60 | FAIR | X |
| PIE | PR | RW 18L-36R | RUNWAY 18L-36R | 9,730 | 150 | 68 | FAIR | X |
| PIE | PR | RW 4-22 | RUNWAY 4-22 | 5,903 | 150 | 96 | GOOD | |
| PIE | PR | RW 9-27 | RUNWAY 9-27 | 4,712 | 150 | 44 | POOR | X |
| SPG | RL | RW 18-36 | RUNWAY 18-36 | 2,864 | 150 | 60 | FAIR | X |
| SPG | RL | RW 7-25 | RUNWAY 7-25 | 3,677 | 75 | 62 | FAIR | X |
| TPF | RL | RW 18-36 | RUNWAY 18-36 | 2,687 | 75 | 85 | SATISFACTORY | |
| TPF | RL | RW 4-22 | RUNWAY 4-22 | 3,580 | 100 | 62 | FAIR | X |
| VDF | RL | RW 18-36 | RUNWAY 18-36 | 5,000 | 100 | 70 | FAIR | X |
| VDF | RL | RW 5-23 | RUNWAY 5-23 | 3,259 | 75 | 71 | SATISFACTORY | X |
| ZPH | GA | RW 18-36 | RUNWAY 18-36 | 4,694 | 100 | 67 | FAIR | X |
| ZPH | GA | RW 5-23 | RUNWAY 5-23 | 4,999 | 100 | 100 | GOOD | |

Figure I: Runway Condition





Figure II: Runway Pavement Condition Index Comparison to FDOT Minimum PCI



Pavement use has an influence on the pavement condition of each facility. For example, the amount and type of distresses observed on a primary runway can vary from a crosswind runway based on the frequency and variety of traffic loads experienced due to the aircraft fleet mix. In this example, the crosswind runway would be exposed to less aircraft operational traffic due to wind coverage. In many cases, the crosswind runway is also shorter than the primary

runway which may cause heavier aircraft traffic, larger jets, to prefer the primary runway in all but the most severe wind conditions. This would result in the primary runway experiencing a larger percentage of aircraft passes in frequency and heavy load applications. Table III: District Summary of Area Use by Airport provides a breakdown of the airport pavement areas by its facility use. Figure III: PCI by Pavement Use by Airport graphically depicts the PCI for each pavement facility use at each airport.

Table III: District Summary of Area by Use by Airport

| Network ID | Airport Type | Pavement Area (Square Feet) | | | |
|------------|--------------|-----------------------------|-----------|-----------|------------|
| | | Runway | Taxiway | Apron | Overall |
| BKV | GA | 1,802,250 | 1,259,981 | 784,074 | 3,846,305 |
| CGC | GA | 341,775 | 310,310 | 248,870 | 900,955 |
| CLW | RL | 308,025 | 198,238 | 161,828 | 668,091 |
| INF | GA | 375,075 | 260,434 | 337,924 | 973,432 |
| PCM | GA | 296,402 | 296,714 | 313,605 | 906,721 |
| PIE | PR | 3,000,650 | 2,158,954 | 1,222,641 | 6,382,245 |
| SPG | RL | 693,066 | 603,488 | 688,195 | 1,984,748 |
| TPF | RL | 551,817 | 518,638 | 189,710 | 1,260,164 |
| VDF | RL | 743,145 | 609,551 | 1,177,905 | 2,530,601 |
| ZPH | GA | 974,437 | 808,864 | 515,159 | 2,298,460 |
| DISTRICT | | 9,086,641 | 7,025,172 | 5,639,911 | 21,751,724 |

Figure III: PCI by Pavement Facility Use by Airport




Figure IV: Visual Representation of PCI Ratings and Field Conditions Flexible Asphalt Concrete Pavement and Figure V: Visual Representation of PCI Ratings and Field Conditions Rigid Portland Cement Concrete Pavement below provides a graphical reference of pavement surface characteristics associated with various ranges of PCIs and Ratings with the FDOT repair activities associated with each range.

Figure IV: Visual Representation of PCI Ratings and Field Conditions Flexible Asphalt Concrete Pavement

| | PCI | PCI | REPRESENTATIVE PAVEMENT SURFACE | REPAIR ACTIVITIES |
|-----------------------|----------|-----|---------------------------------|---|
| ROUTINE MAINTENANCE | 86 - 100 | 90 | | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching. |
| PAVEMENT PRESERVATION | 65 - 85 | 70 | | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing. |
| MAJOR REHABILITATION | 40 - 64 | 40 | | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as pavement mill and overlay or PCC restoration activity. |
| MAJOR RECONSTRUCTION | 0 - 39 | 15 | | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction. |

Figure V: Visual Representation of PCI Ratings and Field Conditions Rigid Portland Cement Concrete Pavement

| | PCI | PCI | REPRESENTATIVE PAVEMENT SURFACE | REPAIR ACTIVITIES |
|-----------------------|----------|-----|---------------------------------|---|
| ROUTINE MAINTENANCE | 86 - 100 | 90 | | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching. |
| PAVEMENT PRESERVATION | 65 - 85 | 70 | | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments, patches, and/or joint/crack sealing. |
| MAJOR REHABILITATION | 40 - 64 | 40 | | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as Slab replacement and PCC restoration activity. |
| MAJOR RECONSTRUCTION | 0 - 39 | 15 | | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction. |

The immediate Year 1 Major Rehabilitation needs, or repair needs that have been programmed to be completed in the first year of the 10-year Major Rehabilitation plan based on an unlimited budget for each airport in the District are summarized in Table IV: Summary of Year 1 Major Rehabilitation Needs. It is recommended that each airport put a priority on these pavement facilities, defined by each Section, as the condition determined from the latest inspection have been identified to be at or below the Critical PCI of 65. Pavement Sections with PCI's at or below the Critical PCI will be at or below the recommended FDOT Minimum PCI's. Additional details, such as the identification of the specific pavement Sections below the Critical PCI or MicroPAVER Minimum PCI, are provided in each individual report and in Appendix B of this District summary report.

Table IV: Summary of Year 1 Major Rehabilitation Needs

| Network ID | Airport Type | Weighted-Average PCI | Average Rating | Year-1 Major Rehabilitation |
|------------|--------------|----------------------|----------------|-----------------------------|
| BKV | GA | 56 | FAIR | \$ 33,039,230.56 |
| CGC | GA | 71 | SATISFACTORY | \$ 3,471,524.86 |
| CLW | RL | 87 | GOOD | \$ 2,601,035.00 |
| INF | GA | 95 | GOOD | \$ 756,724.76 |
| PCM | GA | 71 | SATISFACTORY | \$ 5,053,100.34 |
| PIE | PR | 70 | FAIR | \$ 63,848,112.00 |
| SPG | RL | 65 | FAIR | \$ 19,284,698.00 |
| TPF | RL | 74 | SATISFACTORY | \$ 8,097,320.00 |
| VDF | RL | 73 | SATISFACTORY | \$ 983,780.00 |
| ZPH | GA | 70 | FAIR | \$ 9,940,949.42 |
| | DISTRICT | 69 | FAIR | \$ 147,076,474.94 |

The identified major rehabilitation project planning costs summarized above are further explained in each individual airport pavement evaluation report. The projects, defined at the Section Level, have been identified based on the Critical PCI (alternatively MicroPAVER Minimum PCI. The criteria establishes the recommended action based on the pavement Section's determined PCI as compared to the Critical PCI of 65. In reviewing the FDOT SAPMP pavement performance trends and analysis of pavement performance models (by Airport Type, Facility Use, and Pavement Composition) from historic records it is recommended that pavement facilities should be considered for major rehabilitation planning once at or below the Critical PCI of 65.

The FDOT has recommended minimum service level PCI for airports based on pavement facility use, airport type, and expected loading frequency. This

minimum service level PCI is recommended to ensure the pavement provides a safe operational surface and efficiently uses maintenance and rehabilitation budgets. Separately, the Critical PCI is a value based on historic pavement performance trends and costs. It is at a PCI value of 65 at which major rehabilitation is recommended over maintenance level efforts.

A forecast of major rehabilitation needs for a 10-year period was developed for each participating airport based on an assumed 'Unlimited Budget Scenario'. The analysis identified both maintenance level activities and major rehabilitation planning needs during the 10-year period based on the most recent field inspection results. Maintenance level activities, which are direct extrapolation of distress quantities and associated maintenance efforts, were developed as a means to provide a basis for airport planning should major rehabilitation work not be feasible.

Maintenance level activities refers to the repair and preservation-type activities that are applied locally to specific distress types on the pavement. These activities for the SAPMP are considered preventative and corrective in nature and are highly recommended to help improve pavement performance and extend pavement life. The SAPMP maintenance policies are based on the FAA Advisory Circular 150/5380-6C and guidance provided in the FDOT Airfield Pavement Repair Manual.

The resulting major rehabilitation needs, excluding maintenance level activities, by airport are provided in Table V: Summary of 10-Year Major Rehabilitation Costs by Airport. See Table 5-8: District 10-Year Maintenance and Preservation Needs by Airport for maintenance level activities identified for the 10-Year Program based on PCI deterioration.

Table V: Summary of 10-Year Major Rehabilitation Costs by Airport

| Network ID | Airport Type | Weighted-Average PCI | Average Rating | 10-Year Major Rehabilitation |
|------------|--------------|----------------------|----------------|------------------------------|
| BKV | GA | 56 | FAIR | \$ 39,477,474.42 |
| CGC | GA | 71 | SATISFACTORY | \$ 7,093,535.63 |
| CLW | RL | 87 | GOOD | \$ 3,006,532.62 |
| INF | GA | 95 | GOOD | \$ 756,724.76 |
| PCM | GA | 71 | SATISFACTORY | \$ 7,019,282.82 |
| PIE | PR | 70 | FAIR | \$ 76,042,870.35 |
| SPG | RL | 65 | FAIR | \$ 26,106,272.15 |
| TPF | RL | 74 | SATISFACTORY | \$ 8,624,162.92 |
| VDF | RL | 73 | SATISFACTORY | \$ 35,822,534.77 |
| ZPH | GA | 70 | FAIR | \$ 14,963,643.46 |
| | DISTRICT | 69 | FAIR | \$ 218,913,033.90 |

The development of the aforementioned planning level costs are based on planning level assumptions based on the type of rehabilitation being performed and historic Florida average bid costs for each type of construction.

FDOT recognizes that although pavement mill and overlay is recommended for flexible asphalt concrete pavement within a PCI range from 40 to 74, it is conceivable that airports may not have adequate funding to perform this type of major rehabilitation. A comprehensive surface treatment as described in FAA AC 150/5370-10G Standards for Specifying Construction of Airports used as a maintenance rehabilitation activity can be used in lieu of asphalt concrete pavement mill and overlay. However, it should be understood that these measures provide only a short term extension of pavement life. While the cost of surface treatments are significantly lower than that of pavement mill and overlay, it is not intended or implied to be a full rehabilitative measure providing the same long term life as a major rehabilitation.

The objective of the major pavement rehabilitation needs analysis is to provide planning level projects within an airport’s airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value from a functionality perspective. In addition, major rehabilitation is also recommended when the Section PCI is above the Critical PCI but the Section has load-related PCI distresses. This is the point when maintenance and repair level activities are not considered to be cost effective.

Major rehabilitation is identified within the SAPMP as major construction activity that would result in an improvement or “resetting” of the pavement section’s PCI to a value of 100. Such activities could include; mill and hot-mix asphalt overlay and re-construction. This analysis was conducted with no constraints to budgets as a means to identify all pavement projects based on Critical PCI for a 10-year duration. It is recommended that this be used as a planning tool for future project development and prioritization. Table VI: Major Rehabilitation by Condition summarizes the planning level activities by the associated PCI values, as established by the FDOT Aviation and Spaceport Office.

Table VI: Major Rehabilitation by Condition

| Category | Majority Activity | PCI Range | Cost/SqFt By Airport Type | | |
|-------------------------|--|-----------|------------------------------|----------------------|---------------------|
| | | | Primary | Regional Reliever | General Aviation |
| Major Rehabilitation | ▪ Mill and Overlay (AC) | 40 - 74 | \$13.00 | \$10.00 | \$8.00 |
| | ▪ Concrete Pavement Restoration (PCC) | | \$18.00 | \$15.00 | \$10.00 |
| | ▪ Full Depth Pavement Reconstruction | 0 - 39 | \$23.00 | \$20.00 | \$15.00 |

Additional design level investigation in accordance to the FAA Advisory Circulars will be required to identify specific areas within each section that are subject to reconstruction, mill and overlay, and PCC restoration. The work and budgets identified are intended for the planning level not the design level. Areas identified as mill and overlay may in fact require select areas of reconstruction should load-based distresses observed warrant it. It is important to state that the project specific design level efforts are necessary in determining the final rehabilitative construction activity and project limits. In certain cases, adjacent or nearby Sections may not have deteriorated to a PCI level that would warrant “major rehabilitation” but are deteriorated enough to be considered for inclusion as a combined project.

Runway projects, based on pavement conditions below the FDOT recommended minimum service level PCI of 75 and have reached or are below the Critical PCI of 65, which the District should consider as immediate needs are listed as follows. These are not all the needs at each participating airport within the District and may not be the individual airport’s priority, but should be considered in development of funding programs based on functional PCI.

Brooksville – Tampa Bay International Airport (BKV)

- J Runway 3-21 (Sections 6205 and 6210)
 - o Major Rehabilitation
 - o \$7,522,499.64
- J Runway 9-27 (6105, 6110)
 - o Major Rehabilitation
 - o \$11,205,250.19

Crystal River Airport (CGC)

- J Runway 9-27 (6120)
 - o Major Rehabilitation
 - o \$97,500.00

Clearwater Airpark (CLW)

- J No Immediate Runway Major Rehabilitation

Inverness Airport (INF)

- J No Immediate Runway Major Rehabilitation

Plant City Airport (PCM)

- J Runway 10-28 (6103, 6115, 6120)
 - o Major Rehabilitation
 - o \$2,964,017.36

St. Petersburg-Clearwater International Airport (PIE)

- J Runway 18L-36R (6155, 6175, 6185, 6197)
 - o Major Rehabilitation – Structural Distress / Primary Runway
 - o \$13,912,200.00
- J Runway 9-27 (6315, 6320, 6325, 6335, 6340, 6345, 6350, 6355, 6360, 6365, 6370)
 - o Major Rehabilitation – Structural Distress
 - o \$14,385,802.00
- J Runway 4-22 (6230)
 - o Major Rehabilitation
 - o \$463,450.00

Albert Whitted Airport (SPG)

- J Runway 7-25 (6210, 6207, 6205)
 - o Major Rehabilitation
 - o \$3,291,991.00

- J Runway 18-36 (6105, 6110)
 - o Major Rehabilitation
 - o \$6,444,002.00

Peter O. Knight Airport (TPF)

- J Runway 4-22 (6105)
 - o Major Rehabilitation
 - o \$4,657,501.00

Tampa Executive Airport (VDF)

- J No Immediate Runway Major Rehabilitation


Zephyrhills Municipal Airport (ZPH)

- J Runway 18-36 (6205)
 - o Major Rehabilitation
 - o \$5,022,694.06

1. INTRODUCTION

Project Background

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. The aviation system in Florida allows the State to capitalize on an increasingly global marketplace. Florida’s system of commercial service and general aviation airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida’s number one industry.



There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance

repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

Pavement Condition Index surveys were performed for airfield pavement facilities for the following participating airports located in District 7.

- BKV, Brooksville – Tampa Bay Regional Airport
- CGC, Crystal River Airport
- CLW, Clearwater Air Park
- INF, Inverness Airport
- PCM, Plant City Airport
- PIE, St. Petersburg-Clearwater International Airport
- SPG, Albert Whitted Airport
- TPF, Peter O. Knight Airport
- VDF, Tampa Executive Airport
- ZPH, Zephyrhills Municipal Airport

Tampa International Airport (TPA), which is managed by the Hillsborough County Aviation Authority, declined to participate in the FDOT SAPMP update and therefore was not included in the inspection efforts as part of this program update.

1.1 Purpose of District Pavement Evaluation Report

The primary goal of the FDOT Statewide Airfield Pavement Management Program (SAPMP) Update is to assist the Florida Airport System airports to be in compliance with Public Law 103-305 Section 107 with the implementation of an effective airport pavement maintenance-management program as defined by the Federal Aviation Administration Advisory Circular *150/5380-7B Airport Pavement Management Program* and provide maintenance recommendations based on Advisory Circular *150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements*. The FDOT SAPMP provides individual airports with pavement condition ratings as well as recommendations for maintenance level activities and major rehabilitation planning. The overall goal is to minimize costs by performing timely pavement projects prior to deteriorating to a level at which costs increase significantly.

This document is intended to serve as a summary of the District’s participating airports airfield pavement facility condition and long-term major rehabilitation needs. Furthermore, the purpose of this District Summary document is to provide:

- Information on the pavement management principles, objectives, and methods used to update the existing program;

- Provide the average results of the PCI survey and analysis at each District's participating airport.
- Provide the results of the maintenance level activities and major rehabilitation analysis identified for the immediate Year-1 needs and long-term 10-Year project needs on an airport and District-wide basis.

1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the Florida Airports System, identify maintenance and rehabilitation needs at each airport, automate pavement infrastructure information management, and establish standards to address future needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.

During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation (M&R) policies, M&R budget costs, and the development of recommendations for performing routine pavement preservation maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER was selected for implementation of the system update. MicroPAVER was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for the purpose of pavement management. Data from the 1998-1999 FDOT SAPMP update, which built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER system. This data conversion included all documented pavement facility, classification, type, history, geometry, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually

depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In 2006-2008, the SAPMP was updated again with continued use of the MicroPAVER system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In 2010-2012, the SAPMP was updated using new GPS integrated technology to digitally collect pavement distress data. Interactive GIS map files were developed from updated Airfield Pavement Network Definition Maps to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the Federal Aviation Administration (FAA) to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year or every three years, if the pavement is inspected in accordance to the PCI survey procedure (such as ASTM International D 5340 Standard Test Method for Airport Pavement Condition Index Surveys). The previous 2010-2012 SAPMP update utilized the ASTM D 5340-04 released in 2004, in lieu of the 2010/2011 edition, in order to maintain consistent database integrity and benefit of pavement performance models from previous inspections.

1.3 Organization

FDOT Central Aviation and Spaceport Office Program Manager

The FDOT Central Office Airport Engineering Manager serves as the Aviation and Spaceport Office Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the Consultant. The ASO-PM has review and

approval authority for each program task and manages the day-to-day details of the SAPMP and the pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceport Manager and Development Administrator.

Consultant

The Consultant, Kimley-Horn and Associates, Inc. and their team consisting of Penuel Consulting, LLC and Roy D. McQueen & Associates, LTD, provides technical and administrative assistance to the ASO-PM during the execution of the update to the SAPMP. The efforts include updating the airport pavement inventory data, performing the condition survey inspections, evaluating the airfield pavement conditions and updating the SAPMP based upon procedures outlined in the FAA Advisory Circular 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements and ASTM D 5340.

Airport Role

The airports are the ultimate beneficiary for each condition survey inspection performed at their respective airfields as part of the SAPMP. The individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the ASO-PM. The airport should have provided a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP, indicate any construction activity that was performed since the previous inspections.

FDOT District Offices

The seven FDOT District Offices, specifically the Aviation Representatives, provide vital support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing representative construction trend costs and practices through the Florida Airports System. Each District Office receives copies of individual Airfield Pavement Evaluation Reports for the airport facilities located within their respective districts, as well as this summary District specific Report.

1.4 Introduction to Pavement Types and Pavement Management

Pavement Basics

A pavement is a prepared surface designed to provide a continuous smooth ride at all taxi, takeoff, and landing speeds and to support an estimated amount of traffic loading for a certain number of years. Pavements are composed of a

combination of constructed layers of subgrade soils, subbases, base course material, and surface level courses. There are two primary types of pavements:

- Flexible Pavement, composed of bituminous asphalt concrete (AC) surface, base, and subbase layers.
- Rigid Pavement, composed of Portland Cement Concrete (PCC) surface, base, and subbase layers.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads (both magnitude and repeated application) and protect the underlying subgrade soil. Flexible pavements dissipate applied loads from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements, the PCC layer supports the majority of the structural load applied, and the base or subbase layer is constructed to provide a smooth, level, and continuous platform that provides uniform support for PCC slabs.

A small percentage of airfield pavements within the Florida Airports System are composed of hybrid 'composite pavement' sections that may include both AC pavement and PCC pavement. The two known composite pavements are AC surface over PCC (APC) and PCC over AC (White Topping).

Due to the different nature of the pavement types, construction, and their materials; flexible and rigid pavements have different modes of failure and fatigue. This results in varying deterioration and distress development. Understanding the mechanics and modes of failure of the pavement types assists the engineers in making timely, adequate and consistent observations, and in recommending economical maintenance repairs and major rehabilitation to the pavement structures at each airfield.


The Concept of an Airfield Pavement Management System

The SAPMP is a program that provides the Florida Airports System an opportunity to implement and/or maintain a proactive Airfield Pavement Management System (APMS) in a consistent manner at a regular schedule. The SAPMP Airfield Pavement Management System consists of pavement inventory, pavement construction and history, condition survey inspections, pavement performance modeling, maintenance recommendations, and major rehabilitation planning. The various elements of the APMS are used by experienced engineers to identify critical pavements, make pavement preservation or rehabilitation recommendations, and approximate pavement performance. The APMS as a whole is used by an airport's stakeholders, managing agencies, engineers, and

planners as a tool in decision making for future project planning, budgeting, and scheduling of activities for its airfield pavement infrastructure.

A benefit of an active APMS is it provides an understanding of an airport's pavement performance trends for the purpose of project planning. Based on the performance trend of their pavements, an airport can schedule pavement maintenance and rehabilitation prior to when the pavement section has deteriorated to a condition that would require reconstruction. The use of pavement performance trends will help airports and the local FDOT District program managers plan maintenance level activities and major rehabilitation projects in a manner and sequence that maximizes benefit and minimizes costs. Figure 1-1: Pavement Condition Life Cycle, which is based upon the FAA Advisory Circular 150/5380-7B *Airport Pavement Management Program*, illustrates how pavement generally deteriorates over time and the relative cost of rehabilitation and reconstruction throughout its life.

Figure 1-1: Pavement Condition Life Cycle



Source: FAA Advisory Circular 150 5380-7B *Airport Pavement Management Program*

Note that during approximately the first 75% of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in 'Good' and 'Satisfactory' conditions depends on how well it is proactively maintained. As the Figure 1-1 demonstrates, the cost of maintaining the pavement above critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Pavements tend to deteriorate at an accelerated rate when actual traffic loading exceeds the original design assumptions and when limited resources are available for maintenance and repair (M&R) efforts. Planned maintenance and rehabilitation, essentially preserving pavements and delaying condition deterioration, help airport managers, agencies, and engineers maximize the use of their budgets and prolong the life of their pavements. An APMS provides a tool to schedule planned maintenance and major rehabilitation efforts based on a consistent methodology of condition assessment. This consistent methodology of pavement condition assessment allows for the development of pavement performance models to help forecast future pavement conditions.

Part of the implementation of the APMS is the clear identification and inventorying of pavement infrastructure that needs to be managed specifically within the airport owner, manager, and agency responsibility. Another aspect of the APMS is development of maintenance, repair, and major rehabilitation policies that align with the expectations of pavement performance and are based on ability to fund the types of work identified. Once there is an understanding of the cause and extent of pavement distresses, appropriate maintenance and rehabilitation can be planned. By using representative construction costs based on historic bid trends; planning level budget costs can be developed on a multiyear duration.

Airfield Pavement Inspection Methodology for the SAPMP

Pavement condition assessment requires the application of professional judgments regarding the condition of the pavement. The SAPMP airfield pavement condition survey inspections assess pavement, comparing it to a set of standards in *ASTM D 5340-12 Standard Test Method for Airport Pavement Condition Index Surveys*.

The pavement condition surveys assess the functional condition of the pavement surface based on surface distresses as defined by the ASTM D 5340-12. Typically, deficiencies within a pavement structure will eventually reflect to the pavement surface as distresses described within ASTM D 5340-12. The SAPMP is specifically a visual evaluation and analysis based on the ASTM D 5340-12. The structural condition and relative support of the pavement layers can be directly quantified using non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the SAPMP update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine design level

rehabilitation and/or reconstruction needs should the airport proceed to the design process.

In preparation for the PCI survey inspections, the airfield pavements for each airport are divided into branches, sections, and sample units as established by FAA Advisory Circular 150/5380-7B and ASTM D 5340. An *Airfield Pavement Network Definition Exhibit* has been prepared for each participating airport that depicts the inventory system reflected in the SAPMP database system. Each network definition depicts the latest branch, section, and sample unit definition used for the PCI surveys.

The sample units to be inspected were determined through a systematic random sampling technique to provide an unbiased representation of sample units for each pavement facility. The sample unit locations had been determined in such a way that they are distributed evenly throughout each defined pavement section area. In certain cases when no representative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from each inspected sample unit are used to compute the PCI value and rating for each Section using the ASTM D 5340-12 and MicroPAVER (also known currently as PAVER) software. Figures 1-2 and 1-3 depict graphical representations of the color ranges associated with PCI values and ranges with a photograph of airfield pavement that exhibited the conditions for both flexible and rigid pavements respectively.

Figure 1-2: Flexible Pavement, Asphalt Concrete

| | PCI | PCI | REPRESENTATIVE PAVEMENT SURFACE | REPAIR ACTIVITIES |
|-----------------------|----------|-----|---------------------------------|---|
| ROUTINE MAINTENANCE | 86 - 100 | 90 | | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching. |
| PAVEMENT PRESERVATION | 65 - 85 | 70 | | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing. |
| MAJOR REHABILITATION | 40 - 64 | 40 | | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as pavement mill and overlay or PCC restoration activity. |
| MAJOR RECONSTRUCTION | 0 - 39 | 15 | | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction. |

Figure 1-3: Rigid Pavement, Portland Cement Concrete

| | PCI | PCI | REPRESENTATIVE PAVEMENT SURFACE | REPAIR ACTIVITIES |
|-----------------------|----------|-----|---------------------------------|---|
| ROUTINE MAINTENANCE | 86 - 100 | 90 | | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching. |
| PAVEMENT PRESERVATION | 65 - 85 | 70 | | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments, patches, and/or joint/crack sealing. |
| MAJOR REHABILITATION | 40 - 64 | 40 | | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as Slab replacement and PCC restoration activity. |
| MAJOR RECONSTRUCTION | 0 - 39 | 15 | | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction. |

2. AIRFIELD PAVEMENT SYSTEM INVENTORY AND NETWORK UPDATE

2.1 System Inventory Update

A significant element to the development and update of the SAPMP has been to identify recent and anticipated construction activity that affects the pavement composition and performance. With cooperation from the airport personnel, the project team was able to gather airport specific information that included changes in pavement geometry, new or reconstructed pavements since the last inspection and anticipated pavement rehabilitation that would negate the findings of a visual inspection done in the short term. At the beginning of each phase for this update, FDOT SAPMP participants responded to the Aviation and Spaceport Office with project specific information on the recent and anticipated work. In addition to the construction activity, updates to pavement facility designators (i.e. re-designation, magnetic declination, and/or decommissioning) were reported. Lastly, the project team leaders performing field inspections confirm with airport staff on site previous, recent, and anticipated construction projects that may affect the airfield pavement facilities.

This information was considered in conjunction with aerial imagery provided by FDOT during the updating of pavement section areas on each airport's *Airfield Pavement Network Definition Exhibit*. The previous, recent, and anticipated construction activity information provided by airport staff has been graphically depicted relative to the branch, section, and sample unit definition on the *Airfield Pavement System Inventory Exhibit* for each participating airport. This information was also included in the MicroPAVER database updates for the SAPMP.

2.2 Network Definition Update

Branch and Section Identification

Each airport's airfield pavement network is generally subdivided into separate Branches (runways, taxiways, aprons/ramps, or others) that have distinctly different functional identifications and uses. Each Branch is further subdivided into Sections as defined by pavement location, composition, and construction history. A Section is typically understood to be a project level subdivision within a Branch feature. Sections are manageable units to organize data collection and are treated individually during the maintenance and major rehabilitation planning process. A pavement rank (primary, secondary, or tertiary) is assigned

to each Section based on its importance and type of use to airport operations. The pavement rankings designated for each section at the participating airports were defined by the previous SAPMP, unless changes were communicated by the airport. These Sections are further subdivided into condition survey sample units based on the methodology described in ASTM D 5340.

The *Airfield Pavement System Inventory* and *Airfield Pavement Network Definition* Exhibits are developed individually for each participating airport. Based on information requested of and provided by the airport, the airfield pavements are evaluated on designation updates, and recent or anticipated pavement construction activity. As mentioned previously, a Section is defined partially by its construction history of which is factored in the performance and condition of the pavement section.

Construction activities identified include maintenance and repair activity, major rehabilitation, and new airfield pavement construction. Maintenance and repair activity may include; surface treatments, crack sealing, patching, slab replacement, and others. Both maintenance and rehabilitation activities are identified at the pavement section level. This type of work may result in an increase in overall Section PCI since the last inspection. Major rehabilitation efforts may include; asphalt milling and overlay, and full depth pavement reconstruction. This type of effort will result in a resetting of the pavement section PCI value to 100 due to the nature of the work. Lastly, new airfield pavement construction are accounted for as new inventory and assigned a section PCI of 100. Typically the new pavement sections are not inspected due to its condition; however these pavements are incorporated into the SAPMP pavement database.

Due to recent and anticipated construction efforts; pavement area sections may have been consolidated or created which will affect the total number of sample units to be inspected based upon the methods described in ASTM D 5340 and from the sampling rate schedule.

Airfield Pavement Network Definition & Geographic Information System (GIS)

As part of this SAPMP update, geographic information system (GIS), global positioning system (GPS), and digital data collection were integrated into the Pavement Inspection Methodology at each airport. Using AutoCAD Civil 3D, ArcMap, ArcPad, and FDOT Survey and Mapping Office Aerial Photography; digital navigation maps have been developed for each airport to represent the SAPMP pavement inventory attributes. These navigation maps were used with field data tablets to assist survey teams as they performed condition inspections

by navigating pavement infrastructure and collecting distress data. Additionally, this information was utilized to develop updates to geometry characteristics for each of the identified pavement facilities.

The updated areas for the District airports by facility Use are summarized in Table 2-1: Summary of Area by Facility Use by Airport. Separately, Figure 2-1: District Pavement Area by Use depicts the district airfield pavement areas by facility use, and Figure 2-2: Pavement Area Use by Airport provides a breakdown of airfield pavement area by facility use at each participating airport for the District.

Table 2-1: Summary of Area by Facility Use by Airport

| Network ID | Airport Type | Pavement Area (Square Feet) | | | |
|------------|--------------|-----------------------------|-----------|-----------|------------|
| | | Runway | Taxiway | Apron | Overall |
| BKV | GA | 1,802,250 | 1,259,981 | 784,074 | 3,846,305 |
| CGC | GA | 341,775 | 310,310 | 248,870 | 900,955 |
| CLW | RL | 308,025 | 198,238 | 161,828 | 668,091 |
| INF | GA | 375,075 | 260,434 | 337,924 | 973,432 |
| PCM | GA | 296,402 | 296,714 | 313,605 | 906,721 |
| PIE | PR | 3,000,650 | 2,158,954 | 1,222,641 | 6,382,245 |
| SPG | RL | 693,066 | 603,488 | 688,195 | 1,984,748 |
| TPF | RL | 551,817 | 518,638 | 189,710 | 1,260,164 |
| VDF | RL | 743,145 | 609,551 | 1,177,905 | 2,530,601 |
| ZPH | GA | 974,437 | 808,864 | 515,159 | 2,298,460 |
| DISTRICT | | 9,086,641 | 7,025,172 | 5,639,911 | 21,751,724 |

Figure 2-1: District Pavement Area by Use





Figure 2-2: Pavement Area Use by Airport



3. AIRFIELD PAVEMENT CONDITION ANALYSIS AND EVALUATION

Airfield pavement distresses and condition were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D 5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating.

3.1 Updates to the ASTM D 5340

As part of this program update, the SAPMP has adopted the changes made in updates to ASTM D 5340-12 as the previous program had used the ASTM D 5340-04. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reaction distress for rigid pavement distresses. Additionally, the deterioration associated with the rigid pavement distress Scaling/Map Cracking has been modified which results in moving Map Cracking from Scaling to ASR. In the newest version of ASTM D 5340-12, there are two kinds of Shrinkage Cracking, Drying Shrinkage and Plastic Shrinkage. The difference between these two is that the depth of first one may extend through the entire depth of the slab while the thickness of the latter one normally does not extend very deep into the pavement's surface. Furthermore, the Plastic Shrinkage consists of two subcategories: Plastic shrinkage (caused by atmosphere) and Plastic shrinkage (caused by construction). Another kind of Map Cracking is listed under Plastic shrinkage that is caused by construction, as well as Cracking. This additional type of Shrinkage change in distress classification, as described in ASTM D 5340-12, may result in small variances in the PCI values from the previous inspection analysis. Increases in PCI values in pavement Sections comparison to the previous program update, that have not been subject to repairs since the last inspection, may be a result from the updates to the analysis methodology.

Below is a brief description of the changes to the distresses presented in the ASTM D 5340 methodology and a table summarizing the deduction affected.

- a) Flexible Asphalt Concrete Pavement distresses for airfield pavements: The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering". Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling", the PCI

deduction is not as high as the former “Weathering and Raveling”. Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling”, may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

- b) Rigid Portland Cement Concrete Pavement distresses for airfield pavements: The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included Alkali-Silica Reaction, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR”. As a result the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling”, and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, (73) Shrinkage Cracks has been redefined as (73) Shrinkage Cracking. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.

Table 3-1: Distress Updates to Reflect ASTM D 5340-12 provides a summary of the changes due to the update.

Table 3-1: Distress Updates to Reflect ASTM D 5340-12

| Distress Updates to Reflect ASTM D 5340-12 | | | |
|--|-------------------------------------|--------------------------------------|--------------|
| Use and Surface Type | Old 5340-04 Distress | New Distress | Deduct Curve |
| AC/AAC/APC Airfield | (52) Weathering & Raveling - Low | (52) Raveling - Low | No Change |
| | (52) Weathering & Raveling - Medium | (52) Raveling - Medium | No Change |
| | (52) Weathering & Raveling - High | (52) Raveling - High | No Change |
| | N/A | (57) Weathering - Low | New |
| | N/A | (57) Weathering - Medium | New |
| | N/A | (57) Weathering - High | New |
| PCC Airfield | (70) Scaling - Low | (70) Scaling - Low | New |
| | (70) Scaling - Medium | (70) Scaling - Medium | New |
| | (70) Scaling - High | (70) Scaling - High | New |
| | N/A | (76) Alkali Silica Reaction – Low | New |
| | N/A | (76) Alkali Silica Reaction – Medium | New |
| | N/A | (76) Alkali Silica Reaction – High | New |

3.2 Inspection Methodology

A pavement condition survey inspection is performed by measuring the amount and severity of defined pavement distresses observed within the boundaries of sample units. These distresses, as defined by ASTM D 5340, are generally caused by traffic fatigue loading, exposure to climate and elements, and other airfield specific factors. This data is collected by field personnel experienced in pavement condition survey inspection. Data collection is then transferred into the FDOT MicroPAVER database system. MicroPAVER (also known as PAVER) is used to calculate PCI values using the methodology described in ASTM D 5340-12. The values are calculated for each sample and extrapolated on a Section level to determine an area-weighted PCI value ranging from 0 to 100 and one of seven condition ratings. Tables 3-2 and 3-3 describe the distresses as defined by the ASTM D 5340-12 and adopted for the SAPMP procedures.

Table 3-1: Airfield Pavement Distresses for Asphalt Concrete

| Code | Distress | Primary Mechanisms |
|------|----------------------------------|----------------------------------|
| 41 | Alligator Cracking | Load / Fatigue Failure |
| 42 | Bleeding | Construction Quality/ Mix Design |
| 43 | Block Cracking | Climate / Age |
| 44 | Corrugation | Load / Construction Quality |
| 45 | Depression | Subgrade Quality |
| 46 | Jet Blast | Aircraft |
| 47 | Joint Reflection - Cracking | Climate / Prior Pavement |
| 48 | Longitudinal/Transverse Cracking | Climate / Age |
| 49 | Oil Spillage | Aircraft / Vehicle |
| 50 | Patching | Utility / Pavement Repair |
| 51 | Polished Aggregate | Repeated Traffic Loading |
| 52 | Raveling | Climate / Load |
| 53 | Rutting | Repeated Traffic Loading |
| 54 | Shoving | PCC Pavement Growth / Movement |
| 55 | Slippage Cracking | Load / Pavement Bond |
| 56 | Swelling | Climate / Subgrade Quality |
| 57 | Weathering | Climate |

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete

| Code | Distress | Primary Mechanisms |
|------|-------------------------|---|
| 61 | Blow-up | Climate / Alkali Silica Reaction |
| 62 | Corner Break | Load Repetition / Curling Stresses |
| 63 | Linear Cracking | Load Repetition / Curling Stresses / Shrinkage Stresses |
| 64 | Durability Cracking | Freeze-Thaw Cycling |
| 65 | Joint Seal Damage | Material Deterioration / Construction Quality |
| 66 | Small Patch | Pavement Repair |
| 67 | Large Patch/Utility Cut | Utility / Pavement Repair |
| 68 | Popout | Freeze-Thaw Cycling |
| 69 | Pumping | Load Repetition / Poor Joint Sealant |
| 70 | Scaling/Crazing | Construction Quality / Freeze-Thaw Cycling |
| 71 | Faulting | Load Repetition / Subgrade Quality |
| 72 | Shattered Slab | Overloading |
| 73 | Shrinkage Cracking | Construction Quality / Load |
| 74 | Joint Spalling | Load Repetition / Infiltration of Incompressible Material |
| 75 | Corner Spalling | Load Repetition / Infiltration of Incompressible Material |
| 76 | Alkali-Silica Reaction | Construction Quality / Climate |

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

3.3 Airfield Pavement Condition Index Analysis Results

The Pavement Condition Index (PCI) results based on the ASTM D 5340 have been developed by analyzing the specific distress data collection from field inspections using the U.S. Army Corps of Engineers MicroPAVER 6.5 Software (also known as PAVER). In adherence to the ASTM D 5340-12, the software package analyzes the distinct pavement distress data in both quantity and severity in calculating a PCI that ranges from 100 to 0, with corresponding condition ratings of “Good” to “Failed” respectively. Figure 3-1: Pavement Condition Index Rating Scale depicts the seven ranges of index and the associated rating used in the SAPMP.

Figure 3-1: Pavement Condition Index Rating Scale

| PCI Range | Pavement Condition Rating |
|-----------|---------------------------|
| 86 - 100 | Good |
| 71 - 85 | Satisfactory |
| 56 - 70 | Fair |
| 41 - 55 | Poor |
| 26 - 40 | Very Poor |
| 11 - 25 | Serious |
| 0 - 10 | Failed |


The District’s overall PCI is at 69.95, which corresponds to a ‘Fair’ condition. Table 3-3: District Condition Summary by Airport below represents the results of the PCI inspection at each airport within the District. Specific individual airport results and evaluation discussions are documented in each individual airport pavement evaluation report.

Table 3-3: District Condition Summary by Airport

| Network ID | Airport Type | Area-Weighted Pavement Condition Index (PCI) | | | | | | | |
|------------|--------------|--|--------------|---------|--------------|-------|--------------|------------------|--------------|
| | | Runway | | Taxiway | | Apron | | Overall Airfield | |
| | | PCI | PCI Rating | PCI | PCI Rating | PCI | PCI Rating | PCI | PCI Rating |
| BKV | GA | 54 | POOR | 52 | POOR | 68 | FAIR | 56 | FAIR |
| CGC | GA | 68 | FAIR | 87 | GOOD | 57 | FAIR | 71 | SATISFACTORY |
| CLW | RL | 100 | GOOD | 93 | GOOD | 57 | FAIR | 87 | GOOD |
| INF | GA | 97 | GOOD | 94 | GOOD | 93 | GOOD | 95 | GOOD |
| PCM | GA | 60 | FAIR | 71 | SATISFACTORY | 81 | SATISFACTORY | 71 | SATISFACTORY |
| PIE | PR | 71 | SATISFACTORY | 73 | SATISFACTORY | 63 | FAIR | 70 | FAIR |
| SPG | RL | 61 | FAIR | 60 | FAIR | 74 | SATISFACTORY | 65 | FAIR |
| TPF | RL | 70 | FAIR | 75 | SATISFACTORY | 82 | SATISFACTORY | 74 | SATISFACTORY |
| VDF | RL | 70 | FAIR | 71 | SATISFACTORY | 77 | SATISFACTORY | 73 | SATISFACTORY |
| ZPH | GA | 83 | SATISFACTORY | 55 | POOR | 67 | FAIR | 70 | FAIR |
| DISTRICT | | 69 | FAIR | 68 | FAIR | 71 | SATISFACTORY | 69 | FAIR |


Pavement Facility Use has an influence on the pavement condition each facility. For example, the amount and type of distresses observed on a primary runway can vary from a maintenance apron based on frequency and variety of traffic loads experienced. Figure 3-2: PCI by Pavement Facility Use by Airport graphically depicts the PCI for each pavement facility use (Runway, Taxiway, and Apron) at each participating airport within the District.

Figure 3-2: PCI by Pavement Facility Use by Airport




A summary of the District’s area-weighted PCI for each pavement facility use for all airfield pavement sections throughout the participating airports are shown below in Figure 3-3: PCI by Pavement Facility Use.

Figure 3-3: PCI by Pavement Facility Use



Pavement facility surface types considered for the SAPMP update consist of the four common types within the Florida Airport System: Portland Cement Concrete (PCC), Asphalt Concrete Overlayed on Portland Cement Concrete Pavement (APC), Asphalt Concrete Pavement (AC), and Asphalt Concrete Overlayed on Asphalt Concrete (AAC). Figure 3-4: PCI by Pavement Surface Type summarizes the PCI determined based on the various pavement types within the participating District airports. Whitetopping, a composite pavement type that consists of a thin concrete overlay on asphalt concrete pavement exists at certain airports within the Florida Airport System and are discussed at the specific individual airport pavement evaluation report document for those airports.

Figure 3-4: PCI by Pavement Surface Type



4. PAVEMENT PERFORMANCE MODELING

4.1 Pavement Performance Model Concept

As part of the FDOT SAPMP update, pavement performance models are developed from the distress data collected at each participating airport facility within the Florida Airports System. This data is consolidated in a database and organized by inspection date, pavement type, age, pavement use, and airport category.

The consolidation of the Florida Airports System’s pavement infrastructure within the FDOT SAPMP is based on data that has been collected in a consistent method of measurement. The historic pavement condition, or performance trend, has been compiled throughout the system with data from the inception of the SAPMP. This data is processed into models that have been analyzed and developed into prediction curves based upon pavement characteristics. These characteristics include; climate, construction material, and operations. Each model has been developed based on the following criteria:

- AIRPORT TYPE (Primary, Regional Reliever, or General Aviation)
- >FACILITY USE (Runway, Taxiway, or Apron)
- >>FACILITY SURFACE TYPE (AC, AAC, APC, or PCC)

The historic trends of pavement performance at Florida airport facilities for all performance models are consolidated within the program database. This information is utilized in the prediction of pavement performance based on the current PCI determined from the inspections that took place between 2013 and 2015. Major rehabilitation is planned based on the predicted PCI. The intent of this is for both the individual airport and the FDOT District personnel to be aware of anticipated major rehabilitation work based on condition.

Each airport’s airfield pavement section condition, for a given inspection year, is one data point that was used as the basis of each performance trend using a performance model based on pavements of similar background.

4.2 Performance Model Update

The performance models are developed from the current update data at the aforementioned facilities combined with the historic FDOT SAPMP Florida Airports System Database. This data is consolidated in a database system using MicroPAVER (also known as PAVER) and organized by specific attributes defined


by the pavement system inventory. The pavement system inventory includes inspection data, pavement type, age, pavement use, airport category, FDOT District and pavement ranking. The pavement performance models are used to develop broad prediction models, also known as pavement condition deterioration curves or “Prediction Curves”.

The consolidation of the Florida Airports System’s pavement infrastructure within the FDOT SAPMP is based on data that has been systematically collected in a manner consistent with the ASTM D5340 Standard Test Method for Airport Pavement Condition Surveys. It should be noted that since the inception of the program, the ASTM D5340 has undergone updates that have modified the method of inspection based on research.

Example: Taxiways constructed from Asphalt Concrete at a Primary Airport
 AIRPORT TYPE (Primary, Regional Reliever, or General Aviation)
 >FACILITY USE (Runway, Taxiway, or Apron)
 >>FACILITY SURFACE TYPE (AC, AAC, APC, or PCC)
 FDOT-SAPMP-PR-TW-AC

A most recent change was observed in ASTM D5340-10 which updated the methods of identifying and rating the following distresses” Weathering (AC), Raveling (AC), and Scaling (PCC). The historic pavement condition, or performance trend, has been compiled based on condition data collected from the inception of the SAPMP. This data is processed into performance models that have been analyzed and developed into prediction curves based upon pavement characteristics. Figure 4-1: Example Pavement Performance Model depicts an example of a performance model and data points comprised of historic construction milestones provided by the airports and inspection data in accordance with the ASTM D 5340.

Figure 4-1: Example Pavement Performance Model



- × PCI Data included in Model
- △ PCI Data excluded in Model

4.3 Prediction Curve Development

The historic trends of pavement performance at Florida airport facilities for all performance models are consolidated within the program database. This information is utilized in the prediction of pavement performance based on the current PCI determined from the inspections that take place between 2013 and 2015. Major rehabilitation is planned based on the predicted PCI. The intent of this is for both the individual airport and the FDOT District personnel to be aware of recommended major rehabilitation work based on condition.

The performance models are further refined based on the engineering judgment of pavement performance and data integrity using statistical filters and boundaries. The prediction modeling process identifies and groups pavement sections of similar construction (airport type and pavement type), that are subjected to similar aircraft fleet mix traffic patterns (airport type and branch use), weather and other factors that affect pavement performance and deterioration. The historical data on pavement condition, as entered in the Work History module of the database, is used to predict the future performance of a group of pavement sections with similar attributes.

Each pavement section is assigned to a “family” or model grouping. When predictions about future performance of a pavement are desired, its family

model is used to predict future condition. The input of current age of pavement is applied on the performance model family equation.

The following factors influence the life of a pavement within the performance model; original construction type/date, maintenance, weather, and traffic. The performance model and prediction curve process is designed to allow users to blend unique knowledge about their pavements and measured local condition information to plan for project development.

There are multiple types of boundaries that can be applied to a performance mode; Statistical Boundary and Envelope Boundaries. The Envelope Boundaries filter data based on Age and PCI performance factors. Statistical Boundaries, red lines, indicate the standard deviation of data points based on the SAPMP historic records. When these types of boundaries are applied, outlying points are not considered when the predicted condition function curve is estimated. This ability within MicroPAVER allows for the filtering of suspicious data points. The data filtering procedure is used to remove obvious errors in the data using Envelope Boundaries and Statistical Boundaries. This is critical as pavements with an unusual performance can have a substantial impact on how the model, or family, performs. Table 4-1: Overall Airport Area-Weighted PCI summarizes the area-weighted average PCI for each participating airport’s airfield pavement performance within the District from 2015 to 2024. The following Tables 4-2 through 4-4 summarize each airport’s airfield pavement performance by pavement facility use from 2015 to 2024.

Table 4-1: Overall Airport Area-Weighted PCI

| Network ID | Program Year | | | | | | | | | |
|------------|--------------|------|------|------|------|------|------|------|------|------|
| | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| BKV | 54 | 53 | 53 | 52 | 51 | 51 | 51 | 50 | 50 | 50 |
| CGC | 69 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 |
| CLW | 84 | 82 | 80 | 78 | 76 | 74 | 73 | 71 | 69 | 67 |
| INF | 88 | 86 | 83 | 81 | 79 | 77 | 76 | 74 | 72 | 71 |
| PCM | 68 | 66 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 |
| PIE | 68 | 67 | 64 | 62 | 60 | 58 | 56 | 54 | 52 | 50 |
| SPG | 64 | 62 | 60 | 58 | 57 | 55 | 53 | 51 | 49 | 48 |
| TPF | 73 | 71 | 69 | 67 | 65 | 64 | 62 | 60 | 58 | 56 |
| VDF | 73 | 71 | 70 | 68 | 66 | 65 | 63 | 62 | 60 | 58 |
| ZPH | 66 | 64 | 63 | 62 | 60 | 59 | 58 | 57 | 56 | 55 |
| DISTRICT | 67 | 66 | 64 | 62 | 61 | 59 | 58 | 56 | 55 | 54 |

Table 4-2: Airport Runway Area-Weighted PCI

| Network ID | Program Year | | | | | | | | | |
|------------|---|------|------|------|------|------|------|------|------|------|
| | Overall Runway Branch Area-Weighted PCI | | | | | | | | | |
| | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| BKV | 51 | 50 | 50 | 50 | 49 | 49 | 49 | 49 | 48 | 48 |
| CGC | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 |
| CLW | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 75 | 73 |
| INF | 89 | 87 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 71 |
| PCM | 68 | 66 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 |
| PIE | 73 | 71 | 69 | 67 | 65 | 63 | 61 | 60 | 58 | 56 |
| SPG | 59 | 58 | 56 | 54 | 53 | 51 | 49 | 48 | 46 | 45 |
| TPF | 74 | 72 | 71 | 69 | 68 | 66 | 64 | 63 | 61 | 59 |
| VDF | 70 | 69 | 67 | 66 | 65 | 63 | 62 | 61 | 59 | 58 |
| ZPH | 52 | 51 | 50 | 49 | 48 | 47 | 46 | 45 | 44 | 44 |
| DISTRICT | 66 | 65 | 63 | 62 | 61 | 59 | 58 | 57 | 55 | 54 |

Table 4-3: Airport Taxiway Area-Weighted PCI

| Network ID | Program Year | | | | | | | | | |
|------------|--|------|------|------|------|------|------|------|------|------|
| | Overall Taxiway Branch Area-Weighted PCI | | | | | | | | | |
| | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| BKV | 51 | 50 | 50 | 50 | 49 | 49 | 49 | 49 | 48 | 48 |
| CGC | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 |
| CLW | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 75 | 73 |
| INF | 89 | 87 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 71 |
| PCM | 68 | 66 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 |
| PIE | 73 | 71 | 69 | 67 | 65 | 63 | 61 | 60 | 58 | 56 |
| SPG | 59 | 58 | 56 | 54 | 53 | 51 | 49 | 48 | 46 | 45 |
| TPF | 74 | 72 | 71 | 69 | 68 | 66 | 64 | 63 | 61 | 59 |
| VDF | 70 | 69 | 67 | 66 | 65 | 63 | 62 | 61 | 59 | 58 |
| ZPH | 52 | 51 | 50 | 49 | 48 | 47 | 46 | 45 | 44 | 44 |
| DISTRICT | 66 | 65 | 63 | 62 | 61 | 59 | 58 | 57 | 55 | 54 |

Table 4-4: Airport Apron Area-Weighted PCI

| Network ID | Program Year | | | | | | | | | |
|------------|--|------|------|------|------|------|------|------|------|------|
| | Overall Apron Branch Area-Weighted PCI | | | | | | | | | |
| | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| BKV | 65 | 64 | 63 | 61 | 60 | 60 | 59 | 58 | 57 | 56 |
| CGC | 56 | 56 | 55 | 54 | 53 | 52 | 51 | 50 | 49 | 48 |
| CLW | 56 | 54 | 52 | 50 | 48 | 46 | 44 | 42 | 40 | 38 |
| INF | 83 | 80 | 77 | 75 | 73 | 71 | 69 | 68 | 67 | 66 |
| PCM | 75 | 73 | 71 | 70 | 68 | 67 | 66 | 65 | 64 | 63 |
| PIE | 61 | 59 | 56 | 54 | 51 | 49 | 46 | 44 | 41 | 38 |
| SPG | 72 | 70 | 68 | 66 | 64 | 62 | 60 | 58 | 56 | 54 |
| TPF | 81 | 79 | 77 | 75 | 72 | 70 | 68 | 66 | 64 | 62 |
| VDF | 76 | 74 | 72 | 70 | 68 | 66 | 64 | 62 | 60 | 59 |
| ZPH | 63 | 62 | 60 | 59 | 58 | 57 | 56 | 55 | 55 | 54 |
| DISTRICT | 69 | 67 | 65 | 63 | 61 | 59 | 58 | 56 | 54 | 53 |

5. MAINTENANCE LEVEL ACTIVITIES

5.1 Policies

Airfield Pavement Maintenance policies are guidance on pavement construction methods used to develop, maintain, repair, and rehabilitate pavement infrastructure based on distresses encountered during the condition surveys.

Maintenance refers to the repair and preservation-type activities that are applied locally to specific distress types on the pavement. These activities for the SAPMP are considered preventative and corrective in nature and are highly recommended to help improve pavement performance and extend pavement life. The SAPMP maintenance policies are based on the FAA Advisory Circular 150/5380-6C and guidance provided in the FDOT Airfield Pavement Repair Manual.

For the purpose of the SAPMP; the maintenance repair needs that are identified and quantified are based solely on the pavement distresses observed and recorded at the time of the inspection. Based on a specific distress type and severity observed, a particular repair work type is recommended and quantified based on the extrapolated section distresses. The repair program identified is specific to the current distresses. Future maintenance planning budgets are based on this initial determination. Tables 5-1 and 5-2 provide the list of maintenance activities incorporated into the SAPMP MicroPAVER database to treat specific distress types and severities.

Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|---|---------------|--------------------|----------|------------------------------|-------------|
| Flexible Asphalt Concrete (AC, AAC, APC) | 41 | Alligator Cracking | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 42 | Bleeding | N/A | Partial Depth Pavement Patch | Square Feet |
| | 43 | Block Cracking | L | Seal Coat Treatment | Square Feet |
| | 43 | Block Cracking | M, H | Full Depth Pavement Patch | Square Feet |
| | 44 | Corrugation | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 45 | Depression | L, M, H | Full Depth Pavement Patch | Square Feet |

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|--------------|---------------|----------------------------------|----------|------------------------------|-------------|
| | 46 | Jet Blast Erosion | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 47 | Joint Reflection Cracking | L | Crack Sealing | Linear Feet |
| | 47 | Joint Reflection Cracking | M, H | Full Depth Pavement Patch | Square Feet |
| | 48 | Longitudinal/Transverse Cracking | L, M, H | Crack Sealing | Linear Feet |
| | 49 | Oil Spillage | L, M | Seal Coat Treatment | Square Feet |
| | 49 | Oil Spillage | H | Full Depth Pavement Patch | Square Feet |
| | 50 | Patch and Utility Patching | M | Full Depth Pavement Patch | Square Feet |
| | 50 | Patch and Utility Patching | H | Full Depth Pavement Patch | Square Feet |
| | 51 | Polished Aggregate | L, M, H | Slurry Seal Coat Treatment | Square Feet |
| | 52 | Raveling | L, M | Slurry Seal Coat Treatment | Square Feet |
| | 52 | Raveling | H | Partial Depth Pavement Patch | Square Feet |
| | 53 | Rutting | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 54 | Shoving | L, M, H | Grinding / Removal | Square Feet |
| | 55 | Slippage Cracking | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 56 | Swelling | M, H | Full Depth Pavement Patch | Square Feet |
| | 57 | Weathering | M, H | Seal Coat Treatment | Square Feet |

Table 5-2: Recommended PCC Maintenance and Repair Policy

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|----------------------|---------------|---------------|----------|-------------------------------------|-------------|
| Rigid Pavement (PCC) | 61 | Blowup | L, M, H | Slab Replacement / Full Depth Patch | Square Feet |
| | 62 | Corner Break | L, M, H | Partial Slab Full Depth Patch - PCC | Square Feet |

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|--------------|---------------|---|----------|-------------------------------------|-------------|
| | 63 | Longitudinal/Transverse/Diagonal Cracking | H | Crack Sealing - PCC | Linear Feet |
| | 64 | Durability Cracking | M, H | Slab Replacement / Full Depth Patch | Square Feet |
| | 65 | Joint Seal Damage | L, M, H | Joint Seal Repair (Local) | Linear Feet |
| | 66 | Patching, Small | M, H | Partial Slab Full Depth Patch - PCC | Square Feet |
| | 67 | Patching, Large | M, H | Partial Slab Full Depth Patch - PCC | Square Feet |
| | 69 | Pumping | L, M, H | Slab Stabilization / Slab Jacking | Square Feet |
| | 70 | Scaling/Map Cracking/Crazing | L, M | Micro-mill and Seal - PCC | Square Feet |
| | 70 | Scaling/Map Cracking/Crazing | H | Slab Replacement / Full Depth Patch | Square Feet |
| | 71 | Settlement / Faulting | L | Micro-mill and Seal - PCC | Square Feet |
| | 71 | Settlement / Faulting | M, H | Slab Stabilization / Slab Jacking | Square Feet |
| | 72 | Shattered Slab | L, M, H | Slab Replacement / Full Depth Patch | Square Feet |
| | 73 | Shrinkage Cracks | N/A | Crack Sealing - PCC | Linear Feet |
| | 74 | Longitudinal/Transverse Joint Spalling | L, M, H | Partial Patch - PCC | Square Feet |
| | 75 | Corner Spalling | L, M, H | Partial Patch - PCC | Square Feet |
| | 76 | Alkali-Silica Reaction | L | Seal Coat Treatment | Square Feet |

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|--------------|---------------|------------------------|----------|-------------------------------------|-------------|
| | 76 | Alkali-Silica Reaction | M | Micro-mill and Seal - PCC | Square Feet |
| | 76 | Alkali-Silica Reaction | H | Slab Replacement / Full Depth Patch | Square Feet |

Though proactive pavement maintenance and preservation is highly recommended in an APMS; it is recognized that pavement that has deteriorated below a certain PCI would benefit more from major rehabilitation rather than localized maintenance and repair work. Major rehabilitation is recommended when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that maintenance repair efforts are no longer cost-efficient. This critical point is called “Critical PCI”. The critical PCI levels for different pavement and branch types were established by the FDOT and were used in this update to develop a maintenance and major rehabilitation plan for the airport. Sections that are above the “Critical PCI” levels will be recommended for maintenance, repair, and preservation treatments, assuming there are no significant load-related distresses. For those Sections below the Critical PCI, the recommended action will consist of major rehabilitation work. This approach is used for the Section’s Current PCI value and the predicted PCI value for future rehabilitation.

The FDOT has recommended minimum service level PCI for airports based on pavement facility use, airport type, and expected loading frequency. This minimum service level PCI is recommended to ensure the pavement provides a safe operational surface and efficiently uses maintenance and rehabilitation budgets. Separately, the Critical PCI is a value based on historic pavement performance trends and costs. It is at a PCI value of 65 at which major rehabilitation is recommended over maintenance level efforts. Table 5-3 identifies the FDOT recommended PCI by use and the critical PCI value for the most important pavements at the airport. This is due to the condition of the pavement and the cost effectiveness of the work. A very important concept of a good pavement management system is the proactive preservation of pavements that are above Critical PCI condition. Conversely, allowing pavement to deteriorate beyond maintenance and performing “worst first” major rehabilitation may cost much more over the life of a pavement.

Table 5-3: Critical PCI and FDOT Minimum Level PCI

| Use | FDOT Recommended Minimum Level PCI | | | Critical PCI |
|---------|------------------------------------|----------------------------|---------------------------|--------------|
| | Primary Airports | Regional Reliever Airports | General Aviation Airports | |
| Runway | 75 | 75 | 75 | 65 |
| Taxiway | 70 | 65 | 65 | 65 |
| Apron | 65 | 65 | 60 | 65 |

Based on historic trends of pavement performance and industry standard practices in pavement maintenance and rehabilitation, the SAPMP included general guidance on construction activity based on condition PCI, as shown on Table 5-4. It is recommended that further investigation of underlying pavement conditions is performed at the design phase.

Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI

| Category | Activity | PCI Range |
|----------------|---------------------------------------|-----------|
| Maintenance | ▪ Crack Sealing (AC/PCC) | 75 - 90 |
| | ▪ Partial Depth Patching (AC) | |
| | ▪ Full Depth Patching (AC/PCC) | |
| | ▪ Surface Treatment (AC) | |
| Rehabilitation | ▪ Mill and Overlay (AC) | 40 - 74 |
| | ▪ Concrete Pavement Restoration (PCC) | |
| | ▪ Full Depth Pavement Reconstruction | 0 - 39 |

The PCI standard scale ranges from a value of 0, typically representing a pavement in a failed condition, to a value of 100 which typically represents a pavement in new or good condition. Generally, airfield pavement sections with a PCI of 75 or higher that are not exhibiting distresses due to aircraft loading will benefit from maintenance activities such as crack sealing, patching, and surface treatments. Pavement sections with PCI values within the range of 40 to 74 may require major rehabilitation, such as a mill and overlay. Lastly, pavement sections with a PCI value of 40 or less are recommended to undergo pavement reconstruction. Generally pavement reconstruction is the only practical means of restoration due to the substantial distresses observed in the pavement structure. Since PCI values are based solely on the visual determination of

pavement distresses and deterioration, this method does not provide a direct measure of structural integrity.

5.2 Planning Level Unit Costs

The FDOT SAPMP developed and updated the maintenance and major rehabilitation costs based on public cost databases for airport and highway pavement construction. Additionally, cost data collected from FDOT and FAA sponsored projects in the Florida Airports System were utilized to identify construction cost trends across the state.

The maintenance, repair, and preservation activity costs have been updated and developed using readily available construction cost data at the time of this update. The costs depicted in this report for both maintenance and major rehabilitation are intended for planning purposes.

FDOT has no control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable costs provided herein are based on the information known to FDOT at this time and represent only the standard judgment as a design professional familiar with the construction industry. FDOT cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable costs.

5.3 Maintenance, Repair, and Major Rehabilitation

FDOT recognizes that although pavement mill and overlay is recommended for flexible asphalt concrete pavement within a PCI range from 40 to 74, it is conceivable that airports may not have adequate funding to perform this type of major rehabilitation. A comprehensive surface treatment as described in *FAA AC 150/5370-10G Standards for Specifying Construction of Airports* used as a maintenance rehabilitation activity can be used in lieu of asphalt concrete pavement mill and overlay. However, it should be understood that these measures provide only a short term extension of pavement life. While the cost of surface treatments are significantly lower than that of pavement mill and overlay, it is not intended or implied to be a full rehabilitative measure for long term benefit. Table 5-5 and Table 5-6 provide budget costs associated with the work types shown in the table.

Table 5-5: Flexible Asphalt Concrete Maintenance Unit Costs

| Surface Type | Maintenance Work Type | Cost | Work Unit |
|---|------------------------------|--------|-------------|
| Flexible Asphalt Concrete (AC, AAC, APC) | Full Depth Pavement Patch | \$5.00 | Square Feet |
| | Partial Depth Pavement Patch | \$3.00 | Square Feet |
| | Seal Coat Treatment | \$0.55 | Square Feet |
| | Crack Sealing | \$2.75 | Linear Feet |
| | Slurry Seal Coat Treatment | \$0.55 | Square Feet |
| | Grinding / Removal | \$2.10 | Square Feet |

Table 5-6: Rigid Portland Cement Concrete Maintenance Unit Costs

| Surface Type | Maintenance Work Type | Cost | Work Unit |
|-------------------------|-------------------------------------|---------|-------------|
| Rigid Pavement (PCC) | Slab Replacement / Full Depth Patch | \$45.00 | Square Feet |
| | Partial Patch - PCC | \$19.10 | Square Feet |
| | Crack Sealing - PCC | \$4.25 | Linear Feet |
| | Joint Seal Repair (Local) | \$3.00 | Linear Feet |
| | Slab Stabilization / Slab Jacking | \$45.00 | Square Feet |
| | Micro-mill and Seal - PCC | \$1.00 | Square Feet |
| | Seal Coat Treatment | \$1.00 | Square Feet |

As part of the SAPMP update, the distress data observed at each airport during the inspection is extrapolated on a section basis to make maintenance recommendations. These recommendations are a direct result of the distress types, severities, and quantities observed at the time of inspection. The maintenance recommendations and planning costs are correlated with the airport’s airfield pavement network’s overall area weighted PCI and used to plan future maintenance costs. Future maintenance costs are planning budgets

that are not specific to a pavement section, but are estimates for the entire airfield. Table 5-7 provides budget costs associated with the rehabilitation activities.

Table 5-7: Major Rehabilitation Activities and Unit Costs by Condition

| Category | Majority Activity | PCI Range | Cost/SqFt By Airport Type | | |
|----------------------|---------------------------------------|-----------|------------------------------|-------------------|------------------|
| | | | Primary | Regional Reliever | General Aviation |
| Major Rehabilitation | ▪ Mill and Overlay (AC) | 40 - 74 | \$13.00 | \$10.00 | \$8.00 |
| | ▪ Concrete Pavement Restoration (PCC) | | \$18.00 | \$15.00 | \$10.00 |
| | ▪ Full Depth Pavement Reconstruction | 0 - 39 | \$23.00 | \$20.00 | \$15.00 |

NOTE: VALUES ARE ROUNDED FOR PLANNING PURPOSES AT THE STATEWIDE LEVEL

A cost scale has been developed based on PCI to develop planning level budgets for the airfield pavements. The cost scale is adjusted by project year based on an assumed inflation rate of 3%.

Table 5-8: District 10-Year Maintenance and Preservation Needs by Airport depicts the predicted pavement preservation needs based on the overall airport area-weighted PCI.

Table 5-8: District 10-Year Maintenance and Preservation Needs by Airport

| Maintenance and Preservation (\$ in Millions) | | | | | | | | | | | |
|---|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Network ID | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| BKV | 0.21M | 0.22M | 0.18M | 0.19M | 0.24M | 0.50M | 0.74M | 1.00M | 1.26M | 1.27M | - |
| CGC | 0.12M | 0.13M | 0.14M | 0.02M | 0.06M | 0.10M | 0.14M | 0.18M | 0.23M | 0.27M | - |
| CLW | - | 0.01M | 0.01M | 0.01M | 0.01M | 0.03M | 0.05M | 0.08M | 0.11M | 0.14M | 0.18M |
| INF | 0.00M | 0.01M | 0.04M | 0.07M | 0.13M | 0.18M | 0.23M | 0.28M | 0.33M | 0.37M | - |
| PCM | 0.07M | 0.08M | 0.09M | 0.09M | 0.12M | 0.13M | 0.18M | 0.20M | 0.26M | 0.30M | - |
| PIE | - | 0.23M | 0.26M | 0.29M | 0.39M | 0.49M | 0.65M | 0.85M | 1.11M | 1.30M | 1.57M |
| SPG | - | 0.16M | 0.13M | 0.06M | 0.07M | 0.08M | 0.09M | 0.12M | 0.19M | 0.27M | 0.37M |
| TPF | - | 0.08M | 0.11M | 0.13M | 0.15M | 0.18M | 0.20M | 0.25M | 0.29M | 0.35M | 0.40M |
| VDF | - | 0.76M | 0.76M | 0.82M | 0.61M | 0.46M | 0.13M | 0.14M | 0.16M | 0.19M | 0.18M |
| ZPH | 0.23M | 0.26M | 0.09M | 0.15M | 0.24M | 0.35M | 0.47M | 0.60M | 0.72M | 0.83M | - |
| District | 0.64M | 1.94M | 1.82M | 1.83M | 2.03M | 2.51M | 2.89M | 3.72M | 4.66M | 5.28M | 2.70M |

NOTE: VALUES ARE ROUNDED FOR SUMMARY PURPOSES

6. MAJOR REHABILITATION NEEDS

6.1 Major Rehabilitation Planning

As part of the SAPMP, major pavement rehabilitation planning is developed based on current and predicted PCI in comparison with the Critical PCI. The Critical PCI has been determined based on the historic trends of pavement condition relative to the benefit of maintenance and repair activities. Pavement sections determined to have a PCI less than that of the Critical PCI are assumed to have deteriorated to a point at which maintenance and repair level activity would provide little benefit. Depending on which Phase an airport was inspected, the program year assumed would be end of FY2013 or end of FY2015 for Phase I and Phase II, respectively.

The development of major rehabilitation projects at the planning level expressed in this District Summary and in the individual airport pavement evaluation reports were based on an 'Unlimited Budget' or unconstrained budget scenario. This scenario has been utilized in the SAPMP as a means to identify project activity based on the condition need. This information is intended to be utilized as a planning tool to support project determination and selection based on airport priority, facility use, traffic demand, budget constraints, and other factors.

The objective of the major pavement rehabilitation needs analysis is to provide planning level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value from a functionality perspective. In addition, major rehabilitation is also recommended when the Section PCI is above the Critical PCI but the Section has load-related PCI distresses. However, most major rehabilitation work is recommended when the Section PCI is below the Critical PCI, which is when maintenance and repair level activities are not considered to be cost effective.

Major rehabilitation is identified within the SAPMP as major construction activity that would result in an improvement or "resetting" of the pavement section's PCI to a value of 100. Such activities could include; mill and hot-mix asphalt overlay and re-construction. This analysis was conducted with no constraints to budgets as a means to identify all pavement projects based on Critical PCI for a 10-year duration. It is recommended that the airport use this as a planning tool for future project development and prioritization.

Airports should consider the major rehabilitation work types of mill and overlay, PCC restoration, and reconstruction planning level classifications only. Additional design level investigation in accordance to the FAA Advisory Circulars will be required to identify specific areas within each section that are subject to reconstruction, mill and overlay, and PCC restoration. The work and budgets identified are intended for the planning level not the design level. Areas identified as mill and overlay may in fact require select areas of reconstruction should load-based distresses observed warrant it. Table 6-1: Summary of District Year-1 Major Rehabilitation Needs identifies the overall planning level costs for each airport based on the total sections requiring major rehabilitation due to its PCI being below the Critical PCI of 65 or having substantial load based distresses.

Table 6-1: Summary of District Year-1 Major Rehabilitation Needs

| Network ID | Airport Type | Weighted-Average PCI | Average Rating | Year-1 Major Rehabilitation |
|------------|--------------|----------------------|----------------|-----------------------------|
| BKV | GA | 56 | FAIR | \$ 33,039,230.56 |
| CGC | GA | 71 | SATISFACTORY | \$ 3,471,524.86 |
| CLW | RL | 87 | GOOD | \$ 2,601,035.00 |
| INF | GA | 95 | GOOD | \$ 756,724.76 |
| PCM | GA | 71 | SATISFACTORY | \$ 5,053,100.34 |
| PIE | PR | 70 | FAIR | \$ 63,848,112.00 |
| SPG | RL | 65 | FAIR | \$ 19,284,698.00 |
| TPF | RL | 74 | SATISFACTORY | \$ 8,097,320.00 |
| VDF | RL | 73 | SATISFACTORY | \$ 983,780.00 |
| ZPH | GA | 70 | FAIR | \$ 9,940,949.42 |
| | DISTRICT | 69 | FAIR | \$ 147,076,474.94 |

NOTE: VALUES ARE ROUNDED FOR SUMMARY PURPOSES AND INFLATION APPLIED AT 3% ANNUALLY

Table 6-2: Summary of District 10-Year Major Rehabilitation Needs identifies the overall planning level costs for each airport based on the total sections requiring major rehabilitation due to its PCI being below the Critical PCI of 65 as well as the pavement sections deteriorating below the Critical PCI over the 10-Year program planning period.

Table 6-2: Summary of District 10-Year Major Rehabilitation Needs

| Network ID | Airport Type | Weighted-Average PCI | Average Rating | 10-Year Major Rehabilitation |
|------------|--------------|----------------------|----------------|------------------------------|
| BKV | GA | 56 | FAIR | \$ 39,477,474.42 |
| CGC | GA | 71 | SATISFACTORY | \$ 7,093,535.63 |
| CLW | RL | 87 | GOOD | \$ 3,006,532.62 |
| INF | GA | 95 | GOOD | \$ 756,724.76 |
| PCM | GA | 71 | SATISFACTORY | \$ 7,019,282.82 |
| PIE | PR | 70 | FAIR | \$ 76,042,870.35 |
| SPG | RL | 65 | FAIR | \$ 26,106,272.15 |
| TPF | RL | 74 | SATISFACTORY | \$ 8,624,162.92 |
| VDF | RL | 73 | SATISFACTORY | \$ 35,822,534.77 |
| ZPH | GA | 70 | FAIR | \$ 14,963,643.46 |
| | DISTRICT | 69 | FAIR | \$ 218,913,033.90 |

NOTE: VALUES ARE ROUNDED FOR SUMMARY PURPOSES AND INFLATION APPLIED AT 3% ANNUALLY

Table 6-3: Summary of District 10-Year Major Rehabilitation Needs by Airport

| Major Rehabilitation (\$ in Millions) | | | | | | | | | | | |
|---------------------------------------|--------|--------|--------|-------|--------|--------|--------|-------|-------|-------|-------|
| Network ID | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| BKV | 33.04M | 0.00M | 1.60M | 0.89M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 3.95M | - |
| CGC | 3.47M | 0.10M | 0.00M | 3.52M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | - |
| CLW | - | 2.60M | 0.00M | 0.00M | 0.41M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M |
| INF | 0.76M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | - |
| PCM | 5.05M | 0.00M | 0.00M | 0.50M | 0.00M | 0.90M | 0.00M | 0.57M | 0.00M | 0.00M | - |
| PIE | - | 63.85M | 0.07M | 0.77M | 0.00M | 3.04M | 1.50M | 2.72M | 0.22M | 3.88M | 0.00M |
| SPG | - | 19.28M | 1.75M | 3.24M | 0.12M | 0.57M | 0.22M | 0.92M | 0.00M | 0.00M | 0.00M |
| TPF | - | 8.10M | 0.00M | 0.20M | 0.00M | 0.00M | 0.08M | 0.00M | 0.13M | 0.00M | 0.12M |
| VDF | - | 0.98M | 1.86M | 0.04M | 9.75M | 6.79M | 13.55M | 0.46M | 0.08M | 0.00M | 2.30M |
| ZPH | 9.94M | 0.00M | 5.02M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | 0.00M | - |
| District | 52.26M | 94.92M | 10.30M | 9.16M | 10.28M | 11.30M | 15.35M | 4.67M | 0.44M | 7.83M | 2.41M |

NOTE: VALUES ARE ROUNDED FOR SUMMARY PURPOSES AND INFLATION APPLIED AT 3% ANNUALLY

7. CONCLUSION

The FDOT Aviation and Spaceport Office has updated the Statewide Airfield Pavement Management Program through the pavement condition surveys performed at each participating airport and preparation of M&R planning information using guidance provided by the FAA Advisory Circular 150/5380-6C. MicroPAVER software was utilized to determine pavement conditions in accordance with ASTM D 5340-12 and develop maintenance and rehabilitation policies consistent with the FDOT Aviation and Spaceport Office policies. These policies were used to identify pavement rehabilitation projects based on the condition of the pavement over a 10-year period that are detailed in the individual airport reports and in Appendix D District 10-Year Major Rehabilitation Needs and Appendix E District Airfield Pavement 10-Year Major Rehabilitation Exhibits.

This study was focused on identifying current pavement condition and using a condition based tool to assist in the evaluation of pavement performance and identify and prioritize maintenance and rehabilitation needs and costs to maximize useful pavement life. The methods used to determine pavement condition for this program update, as with previous updates, have been performed in accordance with ASTM D 5340 (current version 5340-12). The process is intended to provide airport sponsors with guidance in planning pavement maintenance and rehabilitation projects and funding agencies with planning tools for allocation of funds.

A detailed breakdown of pavement condition for each airport is included in Appendix B District Branch and Section Condition Reports and Appendix C District Airfield Pavement Condition Index Rating Exhibits. As can be seen in this report and by comparing pavement conditions on an airport by airport basis, there is a wide variation in pavement conditions between airports. Recommended major rehabilitation recommendations for each airport are also included in Appendix D District 10-Year Major Rehabilitation Needs and Appendix E District Airfield Pavement 10-Year Major Rehabilitation Exhibits.

7.1 Major Rehabilitation for Runways in District

Runway projects, based on pavement conditions below the FDOT recommended minimum service level PCI of 75 and have reached or are below the Critical PCI of 65, which the District should consider as immediate needs are listed below. These are not all the needs at each participating airport within the

District and may not be the individual airport's priority, but should be considered in development of funding programs based on functional PCI.

Brooksville – Tampa Bay International Airport (BKV)

- J Runway 3-21 (Sections 6205 and 6210)
 - o Major Rehabilitation
 - o \$7,522,499.64
- J Runway 9-27 (6105, 6110)
 - o Major Rehabilitation
 - o \$11,205,250.19

Crystal River Airport (CGC)

- J Runway 9-27 (6120)
 - o Major Rehabilitation
 - o \$97,500.00

Clearwater Airpark (CLW)

- J No Immediate Runway Major Rehabilitation

Inverness Airport (INF)

- J No Immediate Runway Major Rehabilitation

Plant City Airport (PCM)

- J Runway 10-28 (6103, 6115, 6120)
 - o Major Rehabilitation
 - o \$2,964,017.36

St. Petersburg-Clearwater International Airport (PIE)

- J Runway 18L-36R (6155, 6175, 6185, 6197)
 - o Major Rehabilitation – Structural Distress / Primary Runway
 - o \$13,912,200.00
- J Runway 9-27 (6315, 6320, 6325, 6335, 6340, 6345, 6350, 6355, 6360, 6365, 6370)
 - o Major Rehabilitation – Structural Distress
 - o \$14,385,802.00
- J Runway 4-22 (6230)
 - o Major Rehabilitation
 - o \$463,450.00

Albert Whitted Airport (SPG)

- J Runway 7-25 (6210, 6207, 6205)
 - o Major Rehabilitation
 - o \$3,291,991.00
- J Runway 18-36 (6105, 6110)
 - o Major Rehabilitation
 - o \$6,444,002.00

Peter O. Knight Airport (TPF)

- J Runway 4-22 (6105)
 - o Major Rehabilitation
 - o \$4,657,501.00

Tampa Executive Airport (VDF)

- J No Immediate Runway Major Rehabilitation

Zephyrhills Municipal Airport (ZPH)

- J Runway 18-36 (6205)
 - o Major Rehabilitation
 - o \$5,022,694.06

APPENDIX A

© GLOSSARY OF TERMS

GLOSSARY OF TERMS

ASTM D 5340-12

The ASTM D 5340-12 Standard Test Method for Airport Pavement Condition Index Surveys by the ASTM International. This test method covers the determination of airport pavement condition through visual surveys of asphalt-surfaced pavements, including porous friction course, and plain or reinforced jointed Portland Cement Concrete pavements, using the Pavement Condition Index (PCI) method of quantifying pavement condition. The PCI for airport pavements was developed by the U.S. Army Corps of Engineers through the funding provided by the U.S. Air Force. It is further verified and adopted by the FAA, and the U.S. Naval Facilities Engineering Command.

Aviation and Spaceport Office

The Florida Department of Transportation Aviation and Spaceport Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office Program Manager (ASO-PM) has review and approval authority for each program task of the SAPMP.

Branch

A Branch (pavement branch) designates pavements that have common usage and functionality, such as an entire runway, taxiway, or apron. A pavement branch is an identifiable part of the pavement network that a single entity and has a distinct function.

Category

The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- J *GA – for general aviation or community airports;*
- J *RL – for regional relievers or small hubs;*
- J *PR – for primary and/or commercial service airports*

The airport Category has been the attribute to aid in the refinement and differentiation of airport infrastructure as it relates to aircraft fleet mix (type, frequency, and pavement requirements).

Critical PCI

The PCI value considered to be the threshold for M&R decisions, it is alternatively known as MicroPAVER Minimum PCI. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than

Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

Distress Type

A distress type, alternatively pavement distress, is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. Distresses are external indicators of pavement deterioration caused by loading, environmental factors, or construction deficiencies, or combination thereof. Typical distresses are cracks, rutting, and weathering of the pavement surface. Specific distress types as defined by the ASTM D 5340-12 are required to obtain an accurate PCI value.

FAA

The Federal Aviation Administration. The FDOT Statewide Airfield Pavement Management Program is sponsored by the FAA. The program has been established and updated in accordance with FAA Advisory Circulars 150/5380-7B Airport Pavement Management Program and 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements.

FDOT

The Florida Department of Transportation. Florida Department of Transportation was represented in this project by the Aviation and Space Port Office of the Office of Freight, Logistics and Passenger Operations.

Localized M&R (Maintenance and Repair)

Alternatively, known as Maintenance or Preservation activities, Localized M&R is a temporary activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

Major M&R or Major Rehabilitation (e.g. Rehabilitation)

Activities performed over the entire area of a pavement Section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays. For the purpose of the FDOT Statewide Airfield Pavement Management Program, Major M&R or Major Rehabilitation, as indicated by Mill and Overlay, PCC Restoration, and/or Reconstruction are planning level categories. It is recommended that project level investigation and design in accordance with the FAA Advisory Circulars be performed.

MicroPAVER (PAVER)

Alternatively known as PAVER, a commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered

management of pavement assets using a condition based approach. This software has the functionality such that, if properly implemented, maintained, and operated, it meets the pavement management program requirements described by the FAA in Advisory Circular 150/5380-7B.

Minimum Condition Level

A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

Network Definition

A Network Definition is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline with pavement Branch and pavement Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. Each Network Definition for the participating airports were developed utilizing information provided by the airport staff, field conditions, record drawings, schematics, and aerial imagery provided by the FDOT Surveying and Mapping Office. The Airfield Pavement Network Definition Exhibits are not intended for construction or design level geometry.

Pavement Condition Index (PCI)

The Pavement Condition Index is a number which represents the condition of a pavement segment at a specific point in time. It is a numerical rating of the pavement condition that ranges from 0 to 100, with 0 being the worst possible condition and 100 being the best possible condition. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340, published by ASTM International.

Pavement Condition Rating (PCR)

A verbal description of pavement condition as a function of the PCI value. The SAPMP utilizes the following Pavement Condition Rating.

| PCI Range | Pavement Condition Rating |
|-----------|---------------------------|
| 86 - 100 | Good |
| 71 - 85 | Satisfactory |
| 56 - 70 | Fair |
| 41 - 55 | Poor |
| 26 - 40 | Very Poor |
| 11 - 25 | Serious |
| 0 - 10 | Failed |

The SAPMP considers seven (7) ranges of condition rating based on the PCI ranges shown above.

Pavement Evaluation

A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

Pavement Management System (PMS)

A Pavement Management System is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

Pavement Surface Type

The surface of pavement is identified as one of four types:

- AC – for asphalt concrete surface pavements(Hot-Mix Asphalt, Bituminous Surface Courses);
- PCC – for Portland Cement Concrete pavements;
- AAC – for asphalt surface pavements that have had an asphalt overlay at some point in their construction history;
- APC – for composite pavements, which consist of asphalt over Portland Cement Concrete pavement.
- PAC – for composite pavements, which consist of Portland Cement Concrete over asphalt concrete pavement.
- WHT – for composite whitetopping pavements, which typically consists of thin concrete overlay over asphalt concrete pavement.

Random Sample

A sample unit of the pavement section selected for inspection by random sampling techniques, such as a random number table or systematic random procedure. For the purpose of the SAPMP, random samples were determined by previous iterations of the SAMP Update and are maintained as inspection sample units unless substantial changes to section limits have been made due to construction work.

Reconstruction

Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

Rehabilitation

Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

Sample Unit

Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are $5,000 \pm 2,000$ square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements.

Section

Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition, and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

Statewide Airfield Pavement Management Program (SAPMP)

The Statewide Airfield Pavement Management Program is a program implemented in 1992 by the Florida Department of Transportation to plan, schedule, and design the maintenance and rehabilitation activities necessary for the airfield pavement on Florida's public airports to allow the airports to operate efficiently, economically, and without excessive down time.

System Inventory

A System Inventory is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline and identifies airfield construction activities since the last inspection.

Use

In MicroPAVER, Use is the term for the function of the pavement area, alternatively Branch Use, Pavement Use, or Pavement Facility Use. For the SAPMP the facility use consists of the following: Runway, Taxiway, or Apron for purposes of the SAPMP program planning.

APPENDIX B

- DISTRICT BRANCH CONDITION REPORT
- DISTRICT SECTION CONDITION REPORT

Date: 5 /15/2015

Branch Condition Report

1 of 14

Pavement Database: FDOT NetworkID: BKV

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|-----------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP NE (NE APRON) | 11 | 4,850.50 | 133.82 | 552,138.02 | APRON | 55.18 | 8.81 | 62.22 |
| AP S (SOUTH APRON) | 5 | 3,161.00 | 68.40 | 231,936.40 | APRON | 74.40 | 13.22 | 84.24 |
| RW 3-21 (RUNWAY 3-21) | 2 | 15,000.00 | 62.50 | 752,250.00 | RUNWAY | 54.00 | 1.00 | 54.33 |
| RW 9-27 (RUNWAY 9-27) | 2 | 21,000.00 | 62.50 | 1,050,000.00 | RUNWAY | 52.00 | 6.00 | 54.00 |
| TW A (TAXIWAY A) | 1 | 8,650.00 | 75.00 | 648,306.61 | TAXIWAY | 50.00 | 0.00 | 50.00 |
| TW A1 (TAXIWAY A1) | 3 | 1,650.00 | 51.67 | 92,918.14 | TAXIWAY | 58.00 | 13.93 | 55.86 |
| TW A3 (TAXIWAY A3) | 2 | 813.00 | 39.00 | 37,158.85 | TAXIWAY | 30.50 | 10.50 | 26.12 |
| TW A5 (TAXIWAY A5) | 1 | 430.00 | 75.00 | 33,046.02 | TAXIWAY | 59.00 | 0.00 | 59.00 |
| TW A6 (TAXIWAY A6) | 1 | 418.00 | 53.00 | 31,613.91 | TAXIWAY | 20.00 | 0.00 | 20.00 |
| TW A9 (TAXIWAY A9) | 1 | 440.00 | 75.00 | 31,973.01 | TAXIWAY | 69.00 | 0.00 | 69.00 |
| TW B (TAXIWAY B) | 2 | 4,965.00 | 35.00 | 173,973.00 | TAXIWAY | 52.00 | 14.00 | 57.06 |
| TW B1 (TAXIWAY B1) | 3 | 2,545.00 | 67.00 | 190,128.02 | TAXIWAY | 62.67 | 6.60 | 63.96 |
| TW B2 (TAXIWAY B2) | 1 | 150.00 | 35.00 | 7,308.52 | TAXIWAY | 38.00 | 0.00 | 38.00 |
| TW B3 (TAXIWAY B3) | 1 | 150.00 | 35.00 | 7,308.52 | TAXIWAY | 59.00 | 0.00 | 59.00 |
| TW B4 (TAXIWAY B4) | 1 | 150.00 | 35.00 | 6,246.24 | TAXIWAY | 62.00 | 0.00 | 62.00 |

Date: 5 /15/2015

Branch Condition Report

2 of 14

Pavement Database: FDOT NetworkID: CGC

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|-----------------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP MAIN (MAIN APRON) | 2 | 680.00 | 256.00 | 169,476.00 | APRON | 58.00 | 4.00 | 56.47 |
| AP T-HANG (T-HANGARS APRON) | 1 | 405.00 | 200.00 | 79,394.00 | APRON | 61.00 | 0.00 | 61.00 |
| RW 9-27 (RUNWAY 9-27) | 4 | 4,555.00 | 75.00 | 341,775.00 | RUNWAY | 66.75 | 1.92 | 68.49 |
| TW A (TAXIWAY A) | 9 | 3,861.00 | 49.44 | 217,112.00 | TAXIWAY | 76.89 | 21.33 | 92.61 |
| TW CONN (CONNECTOR TAXIWAY TO AP) | 2 | 2,000.00 | 26.00 | 56,619.00 | TAXIWAY | 57.00 | 2.00 | 57.37 |
| TW HANG (TAXIWAY TO HANGAR) | 1 | 500.00 | 25.00 | 36,579.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |

Date: 5 /15/2015

Branch Condition Report

3 of 14

Pavement Database: FDOT NetworkID: CLW

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|---|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP CENTER (CENTER APRON) | 2 | 745.00 | 62.50 | 33,672.74 | APRON | 46.50 | 7.50 | 46.65 |
| AP N (NORTH APRON) | 2 | 250.00 | 75.00 | 21,509.00 | APRON | 77.00 | 23.00 | 58.52 |
| AP T-HAN 1 (APRON AT T-HANGARS 1) | 2 | 1,700.00 | 35.00 | 44,575.77 | APRON | 46.50 | 10.50 | 51.09 |
| AP T-HAN 2 (APRON AT T-HANGARS 2) | 1 | 1,800.00 | 20.00 | 37,331.32 | APRON | 65.00 | 0.00 | 65.00 |
| AP T-HAN 3 (APRON AT T-HANGARS 3) | 1 | 1,200.00 | 20.00 | 24,739.20 | APRON | 71.00 | 0.00 | 71.00 |
| RW 16-34 (RUNWAY 16-34) | 4 | 4,097.00 | 75.00 | 308,025.00 | RUNWAY | 100.00 | 0.00 | 100.00 |
| TW A (TAXIWAY A) | 8 | 8,850.00 | 30.00 | 176,330.89 | TAXIWAY | 94.00 | 15.87 | 92.57 |
| TW A-1 (TAXIWAY A-1) | 1 | 100.00 | 50.00 | 6,927.79 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A-2 (TAXIWAY A-2) | 1 | 100.00 | 50.00 | 6,566.58 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A-3 (TAXIWAY A-3) | 1 | 100.00 | 50.00 | 6,967.15 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW CONN 34 (TAXIWAY CONNECTOR TO RUNWAY 34) | 1 | 50.00 | 30.00 | 1,445.90 | TAXIWAY | 51.00 | 0.00 | 51.00 |

Date: 5 /15/2015

Branch Condition Report

4 of 14

Pavement Database: FDOT NetworkID: INF

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP FBO (FBO APRON) | 2 | 700.00 | 250.00 | 203,792.78 | APRON | 100.00 | 0.00 | 100.00 |
| AP GA (GA APRON) | 3 | 1,052.00 | 131.00 | 134,130.81 | APRON | 82.33 | 16.50 | 84.86 |
| RW 1-19 (RUNWAY 1-19) | 1 | 5,000.00 | 75.00 | 375,074.96 | RUNWAY | 97.00 | 0.00 | 97.00 |
| TW A (TAXIWAY ALPHA) | 3 | 5,354.00 | 35.00 | 192,590.46 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A1 (TAXIWAY A1) | 1 | 180.00 | 35.00 | 9,071.68 | TAXIWAY | 94.00 | 0.00 | 94.00 |
| TW A2 (TAXIWAY A2) | 1 | 180.00 | 35.00 | 9,071.68 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A3 (TAXIWAY A3) | 1 | 180.00 | 35.00 | 9,071.68 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW GA AP (TAXIWAY TO GA APRON) | 1 | 1,500.00 | 30.00 | 40,628.23 | TAXIWAY | 63.00 | 0.00 | 63.00 |

Date: 5 /15/2015

Branch Condition Report

5 of 14

Pavement Database: FDOT NetworkID: PCM

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|-------------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP (APRON) | 6 | 1,635.00 | 165.33 | 313,605.04 | APRON | 79.17 | 11.67 | 81.36 |
| RW 10-28 (RUNWAY 10-28) | 3 | 4,000.61 | 75.00 | 296,401.75 | RUNWAY | 57.67 | 4.71 | 60.49 |
| TW A (TAXIWAY A) | 9 | 6,305.00 | 38.89 | 194,037.92 | TAXIWAY | 80.00 | 21.49 | 65.54 |
| TW HANG (TAXIWAY TO HANGAR) | 1 | 1,000.00 | 60.00 | 53,871.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW T-HANG (T-HANGARS TAXIWAY) | 4 | 1,658.00 | 22.50 | 48,804.98 | TAXIWAY | 56.75 | 12.70 | 61.19 |

Date: 5 /15/2015

Branch Condition Report

6 of 14

Pavement Database: FDOT NetworkID: PIE

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP HOLD (HOLDING APRON AT TWS M & F) | 1 | 100.00 | 150.00 | 15,819.38 | APRON | 41.00 | 0.00 | 41.00 |
| AP MAIN (APRON) | 18 | 12,608.00 | 151.22 | 1,170,126.00 | APRON | 66.28 | 37.11 | 63.49 |
| AP RU RW22 (RUN-UP APRON AT RW 22) | 1 | 150.00 | 100.00 | 14,458.50 | APRON | 37.00 | 0.00 | 37.00 |
| FBO CONN (FBO CONNECTOR) | 2 | 977.00 | 137.50 | 22,237.00 | APRON | 100.00 | 0.00 | 100.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 18 | 29,187.00 | 62.50 | 1,459,350.00 | RUNWAY | 74.78 | 12.08 | 68.65 |
| RW 4-22 (RUNWAY 4-22) | 6 | 16,875.00 | 62.50 | 855,366.81 | RUNWAY | 81.67 | 28.87 | 96.63 |
| RW 9-27 (RUNWAY 9-27) | 12 | 13,742.45 | 62.50 | 685,933.00 | RUNWAY | 48.17 | 11.58 | 44.87 |
| TW A (TAXIWAY A) | 12 | 11,791.00 | 76.50 | 834,495.29 | TAXIWAY | 76.75 | 28.68 | 88.03 |
| TW A2 (TAXIWAY A2) | 1 | 600.00 | 100.00 | 60,458.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A3 (TAXIWAY A3) | 1 | 400.00 | 100.00 | 60,311.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A4 (TAXIWAY A4) | 1 | 400.00 | 100.00 | 58,588.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A5 (TAXIWAY A5) | 1 | 400.00 | 100.00 | 56,987.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A6 (TAXIWAY A6) | 1 | 400.00 | 100.00 | 58,658.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW B (TAXIWAY B) | 4 | 1,480.00 | 50.00 | 75,911.14 | TAXIWAY | 62.00 | 25.69 | 50.34 |
| TW C (TAXIWAY C) | 1 | 530.00 | 75.00 | 42,705.81 | TAXIWAY | 36.00 | 0.00 | 36.00 |
| TW D (TAXIWAY D) | 3 | 545.00 | 75.00 | 47,262.41 | TAXIWAY | 50.00 | 2.83 | 49.94 |

Date: 5 /15/2015

Branch Condition Report

7 of 14

Pavement Database: FDOT NetworkID: PIE

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| TW F (TAXIWAY F) | 7 | 1,770.00 | 50.00 | 99,340.14 | TAXIWAY | 76.29 | 27.90 | 76.27 |
| TW H (TAXIWAY H) | 2 | 1,700.00 | 87.50 | 122,270.00 | TAXIWAY | 53.00 | 47.00 | 50.42 |
| TW J (TAXIWAY J) | 2 | 520.00 | 60.00 | 20,009.00 | TAXIWAY | 73.00 | 27.00 | 68.59 |
| TW K (TAXIWAY K) | 5 | 1,015.00 | 32.00 | 47,406.70 | TAXIWAY | 61.20 | 12.95 | 72.15 |
| TW L (TAXIWAY L) | 4 | 2,300.00 | 75.00 | 86,607.00 | TAXIWAY | 83.00 | 29.44 | 85.33 |
| TW M (TAXIWAY M) | 3 | 4,640.00 | 60.00 | 231,669.00 | TAXIWAY | 58.33 | 29.69 | 44.26 |
| TW P (TAXIWAY P) | 2 | 1,515.00 | 50.00 | 80,974.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW T (APRON TAXIWAY SOUTH OF MAIN APRON) | 1 | 1,550.00 | 100.00 | 175,302.00 | TAXIWAY | 22.00 | 0.00 | 22.00 |

Date: 5 /15/2015

Branch Condition Report

8 of 14

Pavement Database: FDOT NetworkID: SPG

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|-------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP (APRON) | 6 | 5,650.00 | 126.67 | 364,794.56 | APRON | 64.00 | 6.61 | 62.40 |
| AP MID (APRON MIDFIELD) | 3 | 750.00 | 116.67 | 107,927.00 | APRON | 100.00 | 0.00 | 100.00 |
| AP NW (APRON NORTHWEST) | 2 | 565.00 | 225.00 | 140,852.15 | APRON | 89.50 | 0.50 | 89.23 |
| AP W (WEST APRON) | 1 | 1,300.00 | 55.00 | 74,621.08 | APRON | 67.00 | 0.00 | 67.00 |
| RW 18-36 (RUNWAY 18-36) | 2 | 8,592.00 | 62.50 | 429,600.00 | RUNWAY | 60.00 | 1.00 | 60.33 |
| RW 7-25 (RUNWAY 7-25) | 5 | 3,437.00 | 75.00 | 263,465.55 | RUNWAY | 66.40 | 20.14 | 62.87 |
| TW A (TAXIWAY A) | 3 | 2,450.00 | 40.00 | 99,616.68 | TAXIWAY | 59.00 | 4.08 | 61.44 |
| TW A1 (TAXIWAY ALPHA 1) | 2 | 400.00 | 55.00 | 22,163.00 | TAXIWAY | 63.50 | 36.50 | 63.73 |
| TW A2 (TAXIWAY A2) | 1 | 100.00 | 50.00 | 5,039.47 | TAXIWAY | 60.00 | 0.00 | 60.00 |
| TW B (TAXIWAY B) | 9 | 2,995.00 | 45.56 | 129,999.96 | TAXIWAY | 55.22 | 15.42 | 65.04 |
| TW C (TAXIWAY C) | 5 | 2,150.00 | 47.00 | 165,996.03 | TAXIWAY | 44.40 | 19.64 | 45.12 |
| TW D (TAXIWAY DELTA) | 6 | 3,110.00 | 28.33 | 82,574.10 | TAXIWAY | 74.67 | 11.46 | 77.07 |
| TW D1 (TAXIWAY D1) | 1 | 75.00 | 70.00 | 5,505.23 | TAXIWAY | 66.00 | 0.00 | 66.00 |
| TW N (NORTH TAXIWAY) | 4 | 2,050.00 | 42.50 | 92,593.53 | TAXIWAY | 66.00 | 4.85 | 66.61 |

Date: 5 /15/2015

Branch Condition Report

9 of 14

Pavement Database: FDOT NetworkID: TPF

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|-------------------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP (APRON) | 2 | 1,700.00 | 87.50 | 165,919.16 | APRON | 73.50 | 10.50 | 82.11 |
| AP RU (APRON) | 3 | 247.00 | 157.67 | 23,790.53 | APRON | 79.67 | 10.34 | 87.32 |
| RW 18-36 (RUNWAY 18-36) | 1 | 2,500.00 | 75.00 | 191,016.57 | RUNWAY | 85.00 | 0.00 | 85.00 |
| RW 4-22 (RUNWAY 4-22) | 3 | 3,608.00 | 100.00 | 360,800.00 | RUNWAY | 80.67 | 16.05 | 62.78 |
| T/L HANG (TAXILANE TO EAST HANGARS) | 1 | 600.00 | 25.00 | 29,573.00 | TAXIWAY | 94.00 | 0.00 | 94.00 |
| TW A (TAXIWAY A) | 6 | 3,372.00 | 40.83 | 139,742.93 | TAXIWAY | 81.00 | 10.57 | 66.49 |
| TW B (TAXIWAY B) | 2 | 340.00 | 45.00 | 16,466.45 | TAXIWAY | 75.00 | 18.00 | 82.78 |
| TW C (TAXIWAY C) | 2 | 575.00 | 40.00 | 24,005.00 | TAXIWAY | 66.00 | 11.00 | 61.57 |
| TW CENTER (TAXIWAY CENTER) | 3 | 1,200.00 | 48.33 | 55,839.67 | TAXIWAY | 86.33 | 4.50 | 87.42 |
| TW D (TAXIWAY D) | 2 | 1,075.00 | 40.00 | 46,607.85 | TAXIWAY | 69.50 | 24.50 | 88.39 |
| TW E (TAXIWAY E) | 4 | 525.00 | 45.00 | 23,901.82 | TAXIWAY | 81.25 | 12.89 | 75.07 |
| TW F (TAXIWAY F) | 2 | 2,600.00 | 35.00 | 98,144.00 | TAXIWAY | 79.00 | 10.00 | 87.04 |
| TW G (TAXIWAY G) | 1 | 300.00 | 30.00 | 12,333.00 | TAXIWAY | 94.00 | 0.00 | 94.00 |
| TW T-HANG (TAXIWAY TO T-HANGARS) | 1 | 3,500.00 | 20.00 | 72,024.05 | TAXIWAY | 53.00 | 0.00 | 53.00 |

Date: 5 /15/2015

Branch Condition Report

10 of 14

Pavement Database: FDOT NetworkID: VDF

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|-----------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP A - S (SOUTH APRON "A") | 3 | 1,015.00 | 160.00 | 196,718.08 | APRON | 72.67 | 2.49 | 71.30 |
| AP B - N (NORTH APRON "B") | 2 | 775.00 | 300.00 | 232,479.97 | APRON | 86.50 | 13.50 | 84.71 |
| AP C (APRON C) | 2 | 1,112.00 | 377.50 | 495,031.70 | APRON | 71.50 | 1.50 | 70.43 |
| AP RU (RUN-UP APRON) | 2 | 350.00 | 65.00 | 28,331.73 | APRON | 70.00 | 5.00 | 73.82 |
| AP T-HANG (T-HANGARS APRON) | 2 | 1,035.00 | 120.00 | 159,945.37 | APRON | 91.50 | 8.50 | 98.72 |
| AP W (APRON WEST) | 2 | 1,350.00 | 106.00 | 65,398.11 | APRON | 69.50 | 4.50 | 70.10 |
| RW 18-36 (RUNWAY 18-36) | 1 | 3,259.00 | 75.00 | 243,145.00 | RUNWAY | 70.00 | 0.00 | 70.00 |
| RW 5-23 (RUNWAY 5-23) | 1 | 5,000.00 | 100.00 | 500,000.00 | RUNWAY | 71.00 | 0.00 | 71.00 |
| TW A (TAXIWAY A) | 6 | 3,615.00 | 36.67 | 132,329.36 | TAXIWAY | 68.67 | 2.56 | 66.41 |
| TW B (TAXIWAY B) | 2 | 705.00 | 30.00 | 22,553.94 | TAXIWAY | 33.00 | 1.00 | 32.65 |
| TW C (TAXIWAY C) | 1 | 575.00 | 35.00 | 21,766.85 | TAXIWAY | 72.00 | 0.00 | 72.00 |
| TW D (TAXIWAY D) | 2 | 975.00 | 35.00 | 36,473.64 | TAXIWAY | 68.00 | 2.00 | 69.44 |
| TW E (TW E) | 1 | 4,156.00 | 35.00 | 145,753.06 | TAXIWAY | 79.00 | 0.00 | 79.00 |
| TW E1 (TW E-1) | 1 | 235.00 | 37.00 | 9,577.05 | TAXIWAY | 76.00 | 0.00 | 76.00 |
| TW E2 (TW E-2) | 1 | 235.00 | 35.00 | 9,510.95 | TAXIWAY | 76.00 | 0.00 | 76.00 |
| TW E3 (TW E3) | 1 | 235.00 | 35.00 | 9,875.77 | TAXIWAY | 80.00 | 0.00 | 80.00 |

Date: 5 /15/2015

Branch Condition Report

11 of 14

Pavement Database: FDOT NetworkID: VDF

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|----------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| TW E4 (TW E-4) | 1 | 235.00 | 35.00 | 8,961.31 | TAXIWAY | 80.00 | 0.00 | 80.00 |
| TW F (TW F) | 3 | 2,870.00 | 41.67 | 107,660.43 | TAXIWAY | 72.67 | 2.49 | 75.57 |
| TW J (TW J) | 3 | 2,835.00 | 35.00 | 105,088.91 | TAXIWAY | 69.67 | 0.94 | 69.23 |

Date: 5 /15/2015

Branch Condition Report

12 of 14

Pavement Database: FDOT NetworkID: ZPH

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP E (EAST APRON) | 1 | 600.00 | 50.00 | 34,097.36 | APRON | 12.00 | 0.00 | 12.00 |
| AP NE (NORTHEAST APRON) | 1 | 475.00 | 27.00 | 27,750.00 | APRON | 40.00 | 0.00 | 40.00 |
| AP NW (NORTHWEST APRON) | 3 | 265.00 | 66.00 | 19,802.71 | APRON | 73.33 | 16.86 | 84.36 |
| AP RU 22 (APRON RUN-UP 22) | 1 | 400.00 | 200.00 | 47,922.50 | APRON | 100.00 | 0.00 | 100.00 |
| AP T-HANG (APRON T-HANGARS) | 1 | 800.00 | 30.00 | 108,938.27 | APRON | 46.00 | 0.00 | 46.00 |
| AP T-HANG2 (APRON T-HANG 2) | 1 | 250.00 | 300.00 | 85,817.46 | APRON | 80.00 | 0.00 | 80.00 |
| AP T-HANG3 (APRON T-HANG 3) | 1 | 650.00 | 250.00 | 164,471.32 | APRON | 84.00 | 0.00 | 84.00 |
| AP TW D (APRON AT END OF TW D) | 1 | 430.00 | 60.00 | 26,359.62 | APRON | 51.00 | 0.00 | 51.00 |
| RW 18-36 (RUNWAY 18-36) | 1 | 4,750.00 | 100.00 | 473,437.11 | RUNWAY | 67.00 | 0.00 | 67.00 |
| RW 5-23 (RUNWAY 5-23) | 5 | 10,376.00 | 70.00 | 501,000.00 | RUNWAY | 100.00 | 0.00 | 100.00 |
| TW A (TAXIWAY A) | 5 | 7,400.00 | 50.00 | 290,360.50 | TAXIWAY | 77.20 | 18.66 | 64.08 |
| TW A-1 (TAXIWAY A-1) | 2 | 650.00 | 45.00 | 32,504.00 | TAXIWAY | 82.00 | 18.00 | 80.59 |
| TW A-2 (TAXIWAY A-2) | 2 | 447.00 | 50.00 | 35,760.00 | TAXIWAY | 77.00 | 23.00 | 80.28 |
| TW B (TAXIWAY B) | 10 | 8,290.00 | 52.00 | 288,040.46 | TAXIWAY | 51.60 | 35.27 | 26.28 |
| TW C (TAXIWAY C) | 1 | 1,200.00 | 50.00 | 69,379.41 | TAXIWAY | 90.00 | 0.00 | 90.00 |
| TW C-1 (TAXIWAY C-1) | 2 | 300.00 | 30.00 | 10,443.84 | TAXIWAY | 77.50 | 15.50 | 75.19 |

Date: 5 /15/2015

Branch Condition Report

13 of 14

Pavement Database: FDOT NetworkID: ZPH

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| TW D (TAXIWAY D) | 1 | 700.00 | 35.00 | 25,063.48 | TAXIWAY | 54.00 | 0.00 | 54.00 |
| TW E (TAXIWAY E) | 1 | 900.00 | 35.00 | 32,964.38 | TAXIWAY | 95.00 | 0.00 | 95.00 |
| TW F (TAXIWAY F) | 1 | 665.00 | 35.00 | 24,348.01 | TAXIWAY | 65.00 | 0.00 | 65.00 |

| Use Category | Number of Sections | Total Area (SqFt) | Arithmetic Average PCI | Average PCI STD. | Weighted Average PCI |
|---------------------|---------------------------|--------------------------|-------------------------------|-------------------------|-----------------------------|
| APRON | 100 | 5,639,910.64 | 69.70 | 23.60 | 71.89 |
| RUNWAY | 71 | 9,086,640.75 | 71.13 | 20.69 | 69.93 |
| TAXIWAY | 215 | 7,025,172.39 | 70.73 | 24.47 | 68.41 |
| All | 386 | 21,751,723.78 | 70.54 | 23.59 | 69.95 |

Date: 5 /15/2015

Section Condition Report

1 of 20

Pavement Database: FDOT NetworkID: BKV

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-----------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP NE (NE APRON) | 4105 | 01/01/1975 | AC | APRON | P | 0 | 29,443.85 | 06/10/2013 | 38 | 48.00 |
| AP NE (NE APRON) | 4110 | 01/01/1975 | AC | APRON | P | 0 | 14,591.81 | 06/10/2013 | 38 | 52.00 |
| AP NE (NE APRON) | 4115 | 01/01/1975 | AC | APRON | P | 0 | 35,799.62 | 06/10/2013 | 38 | 52.00 |
| AP NE (NE APRON) | 4120 | 01/01/1964 | AC | APRON | P | 0 | 53,057.62 | 06/10/2013 | 49 | 53.00 |
| AP NE (NE APRON) | 4125 | 01/01/1975 | AAC | APRON | P | 0 | 23,739.53 | 06/10/2013 | 38 | 63.00 |
| AP NE (NE APRON) | 4130 | 01/01/1942 | PCC | APRON | P | 0 | 6,146.47 | 06/10/2013 | 71 | 36.00 |
| AP NE (NE APRON) | 4135 | 01/01/1983 | AC | APRON | P | 0 | 59,122.43 | 06/10/2013 | 30 | 63.00 |
| AP NE (NE APRON) | 4140 | 01/01/1991 | AC | APRON | P | 0 | 222,039.30 | 06/10/2013 | 22 | 72.00 |
| AP NE (NE APRON) | 4145 | 01/01/1991 | AC | APRON | P | 0 | 72,809.18 | 06/10/2013 | 22 | 56.00 |
| AP NE (NE APRON) | 4147 | 01/01/1989 | AAC | APRON | P | 0 | 7,370.90 | 06/10/2013 | 24 | 55.00 |
| AP NE (NE APRON) | 4150 | 01/01/1991 | PCC | APRON | P | 0 | 28,017.31 | 06/10/2013 | 22 | 57.00 |
| AP S (SOUTH APRON) | 4205 | 01/01/1991 | AC | APRON | P | 0 | 3,398.47 | 06/10/2013 | 22 | 64.00 |
| AP S (SOUTH APRON) | 4210 | 12/25/1999 | AC | APRON | P | 0 | 52,540.81 | 06/10/2013 | 14 | 67.00 |
| AP S (SOUTH APRON) | 4215 | 12/25/1999 | AC | APRON | P | 0 | 32,595.35 | 06/10/2013 | 14 | 74.00 |
| AP S (SOUTH APRON) | 4220 | 12/25/1999 | AC | APRON | P | 0 | 28,845.35 | 06/10/2013 | 14 | 67.00 |
| AP S (SOUTH APRON) | 4225 | 01/01/2009 | AC | APRON | P | 0 | 114,556.42 | 06/10/2013 | 4 | 100.00 |
| RW 3-21 (RUNWAY 3-21) | 6205 | 01/01/1942 | PCC | RUNWAY | S | 0 | 250,750.00 | 06/10/2013 | 71 | 53.00 |
| RW 3-21 (RUNWAY 3-21) | 6210 | 01/01/1942 | PCC | RUNWAY | S | 0 | 501,500.00 | 06/10/2013 | 71 | 55.00 |
| RW 9-27 (RUNWAY 9-27) | 6105 | 01/01/1942 | PCC | RUNWAY | P | 0 | 350,000.00 | 06/10/2013 | 71 | 46.00 |
| RW 9-27 (RUNWAY 9-27) | 6110 | 01/01/1942 | PCC | RUNWAY | P | 0 | 700,000.00 | 06/10/2013 | 71 | 58.00 |
| TW A (TAXIWAY A) | 105 | 01/01/1942 | PCC | TAXIWAY | P | 0 | 648,306.61 | 06/10/2013 | 71 | 50.00 |
| TW A1 (TAXIWAY A1) | 110 | 01/01/1942 | PCC | TAXIWAY | P | 0 | 56,894.07 | 06/10/2013 | 71 | 53.00 |
| TW A1 (TAXIWAY A1) | 111 | 01/01/1991 | AAC | TAXIWAY | P | 0 | 17,869.99 | 06/10/2013 | 22 | 77.00 |
| TW A1 (TAXIWAY A1) | 112 | 01/01/1964 | AC | TAXIWAY | P | 0 | 18,154.08 | 06/10/2013 | 49 | 44.00 |
| TW A3 (TAXIWAY A3) | 120 | 01/01/1942 | PCC | TAXIWAY | P | 0 | 10,836.50 | 06/10/2013 | 71 | 41.00 |
| TW A3 (TAXIWAY A3) | 125 | 01/01/1986 | AC | TAXIWAY | P | 0 | 26,322.35 | 06/10/2013 | 27 | 20.00 |

Date: 5 /15/2015

Section Condition Report

2 of 20

Pavement Database: FDOT NetworkID: BKV

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|--------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| TW A5 (TAXIWAY A5) | 130 | 01/01/1942 | PCC | TAXIWAY | P | 0 | 33,046.02 | 06/10/2013 | 71 | 59.00 |
| TW A6 (TAXIWAY A6) | 135 | 01/01/1986 | AC | TAXIWAY | P | 0 | 31,613.91 | 06/10/2013 | 27 | 20.00 |
| TW A9 (TAXIWAY A9) | 140 | 01/01/1942 | PCC | TAXIWAY | P | 0 | 31,973.01 | 06/10/2013 | 71 | 69.00 |
| TW B (TAXIWAY B) | 205 | 01/01/1990 | AC | TAXIWAY | P | 0 | 55,550.48 | 06/10/2013 | 23 | 38.00 |
| TW B (TAXIWAY B) | 210 | 01/01/1991 | AC | TAXIWAY | P | 0 | 118,422.52 | 06/10/2013 | 22 | 66.00 |
| TW B1 (TAXIWAY B1) | 145 | 01/01/1998 | AC | TAXIWAY | P | 0 | 80,953.55 | 06/10/2013 | 15 | 72.00 |
| TW B1 (TAXIWAY B1) | 215 | 01/01/1942 | PCC | TAXIWAY | P | 0 | 63,745.26 | 06/10/2013 | 71 | 58.00 |
| TW B1 (TAXIWAY B1) | 216 | 01/01/1991 | AC | TAXIWAY | P | 0 | 45,429.21 | 06/10/2013 | 22 | 58.00 |
| TW B2 (TAXIWAY B2) | 220 | 01/01/1990 | AC | TAXIWAY | P | 0 | 7,308.52 | 06/10/2013 | 23 | 38.00 |
| TW B3 (TAXIWAY B3) | 225 | 01/01/1991 | AC | TAXIWAY | P | 0 | 7,308.52 | 06/10/2013 | 22 | 59.00 |
| TW B4 (TAXIWAY B4) | 230 | 01/01/1991 | AC | TAXIWAY | P | 0 | 6,246.24 | 06/10/2013 | 22 | 62.00 |

Date: 5 /15/2015

Section Condition Report

3 of 20

Pavement Database: FDOT NetworkID: CGC

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-----------------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP MAIN (MAIN APRON) | 4105 | 01/01/1998 | AAC | APRON | P | 0 | 117,143.00 | 09/12/2013 | 15 | 54.00 |
| AP MAIN (MAIN APRON) | 4120 | 01/01/2005 | AC | APRON | P | 0 | 52,333.00 | 09/12/2013 | 8 | 62.00 |
| AP T-HANG (T-HANGARS APRON) | 4205 | 01/01/1998 | AC | APRON | T | 0 | 79,394.00 | 09/12/2013 | 15 | 61.00 |
| RW 9-27 (RUNWAY 9-27) | 6105 | 01/01/2001 | AAC | RUNWAY | P | 0 | 225,000.00 | 09/12/2013 | 12 | 69.00 |
| RW 9-27 (RUNWAY 9-27) | 6110 | 01/01/2001 | AC | RUNWAY | P | 0 | 97,275.00 | 09/12/2013 | 12 | 68.00 |
| RW 9-27 (RUNWAY 9-27) | 6115 | 01/01/2001 | AC | RUNWAY | P | 0 | 9,750.00 | 09/12/2013 | 12 | 66.00 |
| RW 9-27 (RUNWAY 9-27) | 6120 | 01/01/2001 | AC | RUNWAY | P | 0 | 9,750.00 | 09/12/2013 | 12 | 64.00 |
| TW A (TAXIWAY A) | 105 | 01/01/2009 | AC | TAXIWAY | T | 0 | 157,438.00 | 09/12/2013 | 4 | 99.00 |
| TW A (TAXIWAY A) | 109 | 01/01/2001 | AC | TAXIWAY | P | 0 | 13,883.00 | 09/12/2013 | 12 | 60.00 |
| TW A (TAXIWAY A) | 115 | 01/01/1965 | AC | TAXIWAY | P | 0 | 4,473.00 | 09/12/2013 | 48 | 56.00 |
| TW A (TAXIWAY A) | 116 | 01/01/2009 | AC | TAXIWAY | T | 0 | 8,548.00 | 09/12/2013 | 4 | 99.00 |
| TW A (TAXIWAY A) | 117 | 01/01/2001 | AC | TAXIWAY | P | 0 | 7,839.00 | 09/12/2013 | 12 | 89.00 |
| TW A (TAXIWAY A) | 118 | 01/01/2001 | AC | TAXIWAY | P | 0 | 4,473.00 | 09/12/2013 | 12 | 40.00 |
| TW A (TAXIWAY A) | 119 | 01/01/2009 | AC | TAXIWAY | P | 0 | 5,073.00 | 09/12/2013 | 4 | 89.00 |
| TW A (TAXIWAY A) | 130 | 01/01/2001 | AC | TAXIWAY | P | 0 | 6,848.00 | 09/12/2013 | 12 | 61.00 |
| TW A (TAXIWAY A) | 131 | 01/01/2009 | AC | TAXIWAY | P | 0 | 8,537.00 | 09/12/2013 | 4 | 99.00 |
| TW CONN (CONNECTOR TAXIWAY TO AP) | 205 | 01/01/1965 | AC | TAXIWAY | P | 0 | 33,566.00 | 09/12/2013 | 48 | 59.00 |
| TW CONN (CONNECTOR TAXIWAY TO AP) | 210 | 01/01/1997 | AC | TAXIWAY | P | 0 | 23,053.00 | 09/12/2013 | 16 | 55.00 |
| TW HANG (TAXIWAY TO HANGAR) | 215 | 01/01/2011 | AC | TAXIWAY | P | 0 | 36,579.00 | 01/01/2011 | 0 | 100.00 |

Date: 5/15/2015

Section Condition Report

4 of 20

Pavement Database: FDOT NetworkID: CLW

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|---|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP CENTER (CENTER APRON) | 4405 | 12/25/1999 | AC | APRON | P | 0 | 16,498.05 | 10/06/2014 | 15 | 39.00 |
| AP CENTER (CENTER APRON) | 4410 | 12/15/1999 | AC | APRON | P | 0 | 17,174.69 | 10/06/2014 | 15 | 54.00 |
| AP N (NORTH APRON) | 4505 | 01/01/2003 | AC | APRON | P | 0 | 19,396.00 | 10/06/2014 | 11 | 54.00 |
| AP N (NORTH APRON) | 4605 | 01/01/2012 | AC | APRON | P | 0 | 2,113.00 | 01/01/2012 | 0 | 100.00 |
| AP T-HAN 1 (APRON AT T-HANGARS 1) | 4305 | 12/25/1999 | AC | APRON | P | 0 | 32,026.11 | 10/06/2014 | 15 | 57.00 |
| AP T-HAN 1 (APRON AT T-HANGARS 1) | 4310 | 12/25/1999 | AC | APRON | P | 0 | 12,549.66 | 10/06/2014 | 15 | 36.00 |
| AP T-HAN 2 (APRON AT T-HANGARS 2) | 4105 | 01/01/1996 | AC | APRON | P | 0 | 37,331.32 | 10/06/2014 | 18 | 65.00 |
| AP T-HAN 3 (APRON AT T-HANGARS 3) | 4205 | 01/01/1996 | AC | APRON | P | 0 | 24,739.20 | 10/06/2014 | 18 | 71.00 |
| RW 16-34 (RUNWAY 16-34) | 6105 | 01/01/2013 | AAC | RUNWAY | P | 0 | 15,000.00 | 01/01/2013 | 0 | 100.00 |
| RW 16-34 (RUNWAY 16-34) | 6110 | 01/01/2013 | AAC | RUNWAY | P | 0 | 224,775.00 | 01/01/2013 | 0 | 100.00 |
| RW 16-34 (RUNWAY 16-34) | 6120 | 01/01/2013 | AAC | RUNWAY | P | 0 | 22,500.00 | 01/01/2013 | 0 | 100.00 |
| RW 16-34 (RUNWAY 16-34) | 6130 | 01/01/2013 | AC | RUNWAY | P | 0 | 45,750.00 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 105 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 63,329.00 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 107 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 5,097.00 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 110 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 7,086.00 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 130 | 01/01/1996 | AC | TAXIWAY | P | 0 | 27,297.98 | 10/06/2014 | 18 | 52.00 |
| TW A (TAXIWAY A) | 135 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 22,264.83 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 140 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 12,540.08 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 145 | 01/01/2013 | AC | TAXIWAY | P | 0 | 23,716.00 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 150 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 15,000.00 | 01/01/2013 | 0 | 100.00 |
| TW A-1 (TAXIWAY A-1) | 115 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 6,927.79 | 01/01/2013 | 0 | 100.00 |
| TW A-2 (TAXIWAY A-2) | 120 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 6,566.58 | 01/01/2013 | 0 | 100.00 |
| TW A-3 (TAXIWAY A-3) | 125 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 6,967.15 | 01/01/2013 | 0 | 100.00 |
| TW CONN 34 (TAXIWAY CONNECTOR TO RUNWAY 34) | 5105 | 01/01/1991 | AC | TAXIWAY | P | 0 | 1,445.90 | 10/06/2014 | 23 | 51.00 |

Date: 5/15/2015

Section Condition Report

5 of 20

Pavement Database: FDOT NetworkID: INF

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|--------------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP FBO (FBO APRON) | 4205 | 01/01/2013 | AC | APRON | P | 0 | 74,783.03 | 01/01/2013 | 0 | 100.00 |
| AP FBO (FBO APRON) | 4210 | 01/01/2013 | AC | APRON | P | 0 | 129,009.75 | 01/01/2013 | 0 | 100.00 |
| AP GA (GA APRON) | 4005 | 01/01/1997 | AC | APRON | P | 0 | 35,044.25 | 06/12/2013 | 16 | 59.00 |
| AP GA (GA APRON) | 4015 | 01/01/2011 | AC | APRON | P | 0 | 26,879.89 | 06/12/2013 | 2 | 94.00 |
| AP GA (GA APRON) | 4020 | 01/01/2011 | AC | APRON | P | 0 | 72,206.67 | 06/12/2013 | 2 | 94.00 |
| RW 1-19 (RUNWAY 1-19) | 6105 | 01/01/2010 | AC | RUNWAY | P | 0 | 375,074.96 | 06/12/2013 | 3 | 97.00 |
| TW A (TAXIWAY ALPHA) | 105 | 01/01/2010 | AC | TAXIWAY | P | 0 | 173,772.53 | 06/12/2013 | 3 | 100.00 |
| TW A (TAXIWAY ALPHA) | 110 | 01/01/2010 | AC | TAXIWAY | P | 0 | 7,297.51 | 06/12/2013 | 3 | 100.00 |
| TW A (TAXIWAY ALPHA) | 130 | 01/01/2010 | AC | TAXIWAY | P | 0 | 11,520.42 | 06/12/2013 | 3 | 100.00 |
| TW A1 (TAXIWAY A1) | 115 | 01/01/2010 | AC | TAXIWAY | P | 0 | 9,071.68 | 06/12/2013 | 3 | 94.00 |
| TW A2 (TAXIWAY A2) | 120 | 01/01/2010 | AC | TAXIWAY | P | 0 | 9,071.68 | 06/12/2013 | 3 | 100.00 |
| TW A3 (TAXIWAY A3) | 125 | 01/01/2010 | AC | TAXIWAY | P | 0 | 9,071.68 | 06/12/2013 | 3 | 100.00 |
| TW GA AP (TAXIWAY TO GA APRON) | 205 | 01/01/1997 | AC | TAXIWAY | P | 0 | 40,628.23 | 06/12/2013 | 16 | 63.00 |

Date: 5 /15/2015

Section Condition Report

6 of 20

Pavement Database: FDOT NetworkID: PCM

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-------------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP (APRON) | 4105 | 03/01/2013 | AC | APRON | P | 0 | 112,145.00 | 03/01/2013 | 0 | 100.00 |
| AP (APRON) | 4110 | 01/01/1992 | AAC | APRON | P | 0 | 45,436.72 | 09/11/2013 | 21 | 68.00 |
| AP (APRON) | 4120 | 01/01/1992 | AAC | APRON | P | 0 | 46,434.32 | 09/11/2013 | 21 | 76.00 |
| AP (APRON) | 4130 | 01/01/1986 | AC | APRON | P | 0 | 77,514.00 | 09/11/2013 | 27 | 68.00 |
| AP (APRON) | 4135 | 01/01/2008 | AC | APRON | P | 0 | 29,575.00 | 09/11/2013 | 5 | 74.00 |
| AP (APRON) | 4140 | 01/01/2010 | PCC | APRON | P | 0 | 2,500.00 | 09/11/2013 | 3 | 89.00 |
| RW 10-28 (RUNWAY 10-28) | 6103 | 01/01/2002 | AAC | RUNWAY | P | 0 | 15,106.00 | 09/11/2013 | 11 | 51.00 |
| RW 10-28 (RUNWAY 10-28) | 6115 | 01/01/1983 | AAC | RUNWAY | P | 0 | 228,795.75 | 09/11/2013 | 30 | 61.00 |
| RW 10-28 (RUNWAY 10-28) | 6120 | 01/01/2002 | AC | RUNWAY | P | 0 | 52,500.00 | 09/11/2013 | 11 | 61.00 |
| TW A (TAXIWAY A) | 110 | 01/01/2001 | AAC | TAXIWAY | P | 0 | 125,294.35 | 09/11/2013 | 12 | 62.00 |
| TW A (TAXIWAY A) | 115 | 01/01/2001 | AC | TAXIWAY | P | 0 | 34,041.02 | 09/11/2013 | 12 | 58.00 |
| TW A (TAXIWAY A) | 120 | 08/01/2013 | AAC | TAXIWAY | P | 0 | 6,040.00 | 08/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 150 | 01/01/2001 | AAC | TAXIWAY | P | 0 | 4,772.66 | 09/11/2013 | 12 | 50.00 |
| TW A (TAXIWAY A) | 160 | 01/01/2001 | AAC | TAXIWAY | P | 0 | 5,382.81 | 09/11/2013 | 12 | 55.00 |
| TW A (TAXIWAY A) | 165 | 03/01/2013 | AAC | TAXIWAY | P | 0 | 6,228.00 | 03/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 170 | 08/01/2013 | AAC | TAXIWAY | P | 0 | 4,869.58 | 08/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 174 | 08/01/2013 | AAC | TAXIWAY | P | 0 | 4,273.00 | 08/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 175 | 01/01/2001 | AAC | TAXIWAY | P | 0 | 3,136.50 | 09/11/2013 | 12 | 95.00 |
| TW HANG (TAXIWAY TO HANGAR) | 750 | 01/01/2011 | AC | TAXIWAY | P | 0 | 53,871.00 | 09/11/2013 | 2 | 100.00 |
| TW T-HANG (T-HANGARS TAXIWAY) | 705 | 01/01/1992 | AAC | TAXIWAY | P | 0 | 13,043.23 | 09/11/2013 | 21 | 75.00 |
| TW T-HANG (T-HANGARS TAXIWAY) | 710 | 01/01/1986 | AAC | TAXIWAY | P | 0 | 5,895.13 | 09/11/2013 | 27 | 43.00 |
| TW T-HANG (T-HANGARS TAXIWAY) | 720 | 01/01/1986 | AC | TAXIWAY | P | 0 | 6,460.00 | 09/11/2013 | 27 | 47.00 |
| TW T-HANG (T-HANGARS TAXIWAY) | 725 | 01/01/1997 | AAC | TAXIWAY | P | 0 | 23,406.62 | 09/11/2013 | 16 | 62.00 |

Date: 5/15/2015

Section Condition Report

7 of 20

Pavement Database: FDOT NetworkID: PIE

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|--------------------------------------|------------|------------------|---------|--------|------|-------|------------------|----------------------|-------------------|--------|
| AP HOLD (HOLDING APRON AT TWS M & F) | 4205 | 01/01/1984 | AC | APRON | P | 0 | 15,819.38 | 01/30/2015 | 31 | 41.00 |
| AP MAIN (APRON) | 4105 | 01/02/2003 | APC | APRON | P | 0 | 396,234.00 | 01/30/2015 | 12 | 55.00 |
| AP MAIN (APRON) | 4123 | 01/02/2003 | APC | APRON | P | 0 | 43,739.00 | 01/30/2015 | 12 | 53.00 |
| AP MAIN (APRON) | 4130 | 12/25/2015 | APC | APRON | P | 0 | 9,563.00 | 12/25/2015 | 0 | 100.00 |
| AP MAIN (APRON) | 4155 | 01/02/2003 | AAC | APRON | P | 0 | 80,944.00 | 01/30/2015 | 12 | 62.00 |
| AP MAIN (APRON) | 4157 | 12/25/2015 | AAC | APRON | P | 0 | 84,447.00 | 12/25/2015 | 0 | 100.00 |
| AP MAIN (APRON) | 4165 | 01/01/2012 | PCC | APRON | P | 0 | 66,409.00 | 01/01/2012 | 0 | 100.00 |
| AP MAIN (APRON) | 4170 | 12/25/2015 | AAC | APRON | P | 0 | 18,816.00 | 12/25/2015 | 0 | 100.00 |
| AP MAIN (APRON) | 4175 | 01/01/1942 | PCC | APRON | P | 0 | 31,006.00 | 01/30/2015 | 73 | 3.00 |
| AP MAIN (APRON) | 4176 | 12/25/1955 | AC | APRON | P | 0 | 10,965.00 | 01/30/2015 | 60 | 4.00 |
| AP MAIN (APRON) | 4177 | 12/25/2015 | APC | APRON | P | 0 | 20,605.00 | 12/25/2015 | 0 | 100.00 |
| AP MAIN (APRON) | 4178 | 01/01/2013 | APC | APRON | P | 0 | 49,146.00 | 01/01/2013 | 0 | 100.00 |
| AP MAIN (APRON) | 4179 | 10/01/2011 | APC | APRON | P | 0 | 70,111.00 | 10/01/2011 | 0 | 100.00 |
| AP MAIN (APRON) | 4180 | 01/01/1968 | AC | APRON | P | 0 | 126,695.00 | 01/30/2015 | 47 | 25.00 |
| AP MAIN (APRON) | 4183 | 01/01/2013 | AAC | APRON | P | 0 | 39,947.00 | 01/01/2013 | 0 | 100.00 |
| AP MAIN (APRON) | 4185 | 01/01/2013 | APC | APRON | P | 0 | 12,820.00 | 01/01/2013 | 0 | 100.00 |
| AP MAIN (APRON) | 4190 | 01/01/1942 | PCC | APRON | P | 0 | 18,650.00 | 01/30/2015 | 73 | 28.00 |
| AP MAIN (APRON) | 4195 | 01/01/1942 | PCC | APRON | P | 0 | 11,250.00 | 01/30/2015 | 73 | 12.00 |
| AP MAIN (APRON) | 4199 | 01/01/2003 | PCC | APRON | P | 0 | 78,779.00 | 01/30/2015 | 12 | 51.00 |
| AP RU RW22 (RUN-UP APRON AT RW 22) | 4305 | 01/01/1984 | AC | APRON | P | 0 | 14,458.50 | 01/30/2015 | 31 | 37.00 |
| FBO CONN (FBO CONNECTOR) | 125 | 12/25/2015 | APC | APRON | P | 0 | 9,856.00 | 12/25/2015 | 0 | 100.00 |
| FBO CONN (FBO CONNECTOR) | 127 | 12/25/2015 | APC | APRON | P | 0 | 12,381.00 | 12/25/2015 | 0 | 100.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6115 | 01/02/2003 | AAC | RUNWAY | P | 0 | 50,000.00 | 01/30/2015 | 12 | 72.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6120 | 01/02/2003 | AAC | RUNWAY | P | 0 | 25,000.00 | 01/30/2015 | 12 | 78.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6135 | 01/02/2003 | AAC | RUNWAY | P | 0 | 20,000.00 | 01/30/2015 | 12 | 74.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6140 | 01/02/2003 | AAC | RUNWAY | P | 0 | 10,000.00 | 01/30/2015 | 12 | 77.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6145 | 01/02/2003 | AAC | RUNWAY | P | 0 | 30,000.00 | 01/30/2015 | 12 | 71.00 |

Date: 5 /15/2015

Section Condition Report

8 of 20

Pavement Database: FDOT NetworkID: PIE

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-----------------------------|------------|------------------|---------|--------|------|-------|------------------|----------------------|-------------------|--------|
| RW 18L-36R (RUNWAY 18L-36R) | 6150 | 01/02/2003 | AAC | RUNWAY | P | 0 | 15,000.00 | 01/30/2015 | 12 | 76.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6155 | 01/02/2003 | AAC | RUNWAY | P | 0 | 180,000.00 | 01/30/2015 | 12 | 63.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6160 | 01/02/2003 | AAC | RUNWAY | P | 0 | 90,000.00 | 01/30/2015 | 12 | 75.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6165 | 01/02/2003 | AAC | RUNWAY | P | 0 | 70,000.00 | 01/30/2015 | 12 | 72.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6170 | 01/02/2003 | AAC | RUNWAY | P | 0 | 35,000.00 | 01/30/2015 | 12 | 74.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6175 | 01/02/2003 | AAC | RUNWAY | P | 0 | 290,000.00 | 01/30/2015 | 12 | 65.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6180 | 01/02/2003 | AAC | RUNWAY | P | 0 | 145,000.00 | 01/30/2015 | 12 | 79.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6185 | 01/02/2003 | AAC | RUNWAY | P | 0 | 210,000.00 | 01/30/2015 | 12 | 54.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6190 | 01/02/2003 | AAC | RUNWAY | P | 0 | 105,000.00 | 01/30/2015 | 12 | 82.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6195 | 01/01/2013 | AAC | RUNWAY | P | 0 | 30,000.00 | 01/01/2013 | 0 | 100.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6196 | 01/01/2013 | AAC | RUNWAY | P | 0 | 15,000.00 | 01/01/2013 | 0 | 100.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6197 | 01/01/2006 | AC | RUNWAY | P | 0 | 92,900.00 | 01/30/2015 | 9 | 52.00 |
| RW 18L-36R (RUNWAY 18L-36R) | 6198 | 01/01/2006 | AC | RUNWAY | P | 0 | 46,450.00 | 01/30/2015 | 9 | 82.00 |
| RW 4-22 (RUNWAY 4-22) | 6205 | 01/01/2012 | AAC | RUNWAY | P | 0 | 474,872.96 | 11/01/2012 | 0 | 100.00 |
| RW 4-22 (RUNWAY 4-22) | 6210 | 01/01/2012 | AAC | RUNWAY | P | 0 | 237,436.49 | 01/01/2012 | 0 | 100.00 |
| RW 4-22 (RUNWAY 4-22) | 6215 | 01/01/2012 | AAC | RUNWAY | P | 0 | 55,071.57 | 01/01/2012 | 0 | 100.00 |
| RW 4-22 (RUNWAY 4-22) | 6220 | 01/01/2012 | AAC | RUNWAY | P | 0 | 27,535.79 | 01/01/2012 | 0 | 100.00 |
| RW 4-22 (RUNWAY 4-22) | 6225 | 01/01/2006 | AC | RUNWAY | P | 0 | 40,300.00 | 01/30/2015 | 9 | 67.00 |
| RW 4-22 (RUNWAY 4-22) | 6230 | 01/01/2006 | AC | RUNWAY | P | 0 | 20,150.00 | 01/30/2015 | 9 | 23.00 |
| RW 9-27 (RUNWAY 9-27) | 6315 | 01/01/1994 | AAC | RUNWAY | P | 0 | 211,743.00 | 01/30/2015 | 21 | 42.00 |
| RW 9-27 (RUNWAY 9-27) | 6320 | 01/01/1994 | AAC | RUNWAY | P | 0 | 105,872.00 | 01/30/2015 | 21 | 43.00 |
| RW 9-27 (RUNWAY 9-27) | 6325 | 01/02/2003 | AAC | RUNWAY | P | 0 | 34,045.00 | 01/30/2015 | 12 | 49.00 |
| RW 9-27 (RUNWAY 9-27) | 6330 | 01/02/2003 | AAC | RUNWAY | P | 0 | 17,023.00 | 01/30/2015 | 12 | 74.00 |
| RW 9-27 (RUNWAY 9-27) | 6335 | 01/01/1992 | AAC | RUNWAY | P | 0 | 35,000.00 | 01/30/2015 | 23 | 44.00 |
| RW 9-27 (RUNWAY 9-27) | 6340 | 01/01/1992 | AAC | RUNWAY | P | 0 | 17,500.00 | 01/30/2015 | 23 | 32.00 |
| RW 9-27 (RUNWAY 9-27) | 6345 | 01/01/1992 | AAC | RUNWAY | P | 0 | 45,000.00 | 01/30/2015 | 23 | 40.00 |
| RW 9-27 (RUNWAY 9-27) | 6350 | 01/01/1992 | AAC | RUNWAY | P | 0 | 22,500.00 | 01/30/2015 | 23 | 47.00 |

Date: 5/15/2015

Section Condition Report

9 of 20

Pavement Database: FDOT NetworkID: PIE

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-----------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| RW 9-27 (RUNWAY 9-27) | 6355 | 01/01/1994 | AAC | RUNWAY | P | 0 | 80,000.00 | 01/30/2015 | 21 | 37.00 |
| RW 9-27 (RUNWAY 9-27) | 6360 | 01/01/1994 | AAC | RUNWAY | P | 0 | 40,000.00 | 01/30/2015 | 21 | 65.00 |
| RW 9-27 (RUNWAY 9-27) | 6365 | 01/01/1994 | AAC | RUNWAY | P | 0 | 51,500.00 | 01/30/2015 | 21 | 46.00 |
| RW 9-27 (RUNWAY 9-27) | 6370 | 01/01/1994 | AAC | RUNWAY | P | 0 | 25,750.00 | 01/30/2015 | 21 | 59.00 |
| TW A (TAXIWAY A) | 112 | 01/01/1990 | AAC | TAXIWAY | P | 0 | 3,582.70 | 01/30/2015 | 25 | 66.00 |
| TW A (TAXIWAY A) | 114 | 01/01/1968 | AC | TAXIWAY | P | 0 | 2,360.73 | 01/30/2015 | 47 | 33.00 |
| TW A (TAXIWAY A) | 115 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 203,420.00 | 12/25/2015 | 0 | 100.00 |
| TW A (TAXIWAY A) | 117 | 01/01/1990 | AAC | TAXIWAY | P | 0 | 3,109.00 | 01/30/2015 | 25 | 50.00 |
| TW A (TAXIWAY A) | 119 | 01/01/1968 | AC | TAXIWAY | P | 0 | 3,423.86 | 01/30/2015 | 47 | 33.00 |
| TW A (TAXIWAY A) | 130 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 361,676.00 | 12/25/2015 | 0 | 100.00 |
| TW A (TAXIWAY A) | 135 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 40,056.00 | 12/25/2015 | 0 | 100.00 |
| TW A (TAXIWAY A) | 140 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 17,486.00 | 12/25/2015 | 0 | 100.00 |
| TW A (TAXIWAY A) | 150 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 21,882.00 | 12/25/2015 | 0 | 100.00 |
| TW A (TAXIWAY A) | 155 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 7,969.00 | 12/25/2015 | 0 | 100.00 |
| TW A (TAXIWAY A) | 158 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 16,692.00 | 12/25/2015 | 0 | 100.00 |
| TW A (TAXIWAY A) | 160 | 01/01/2006 | AC | TAXIWAY | P | 0 | 152,838.00 | 01/30/2015 | 9 | 39.00 |
| TW A2 (TAXIWAY A2) | 165 | 12/25/2015 | AC | TAXIWAY | P | 0 | 60,458.00 | 12/25/2015 | 0 | 100.00 |
| TW A3 (TAXIWAY A3) | 168 | 12/25/2015 | AC | TAXIWAY | P | 0 | 60,311.00 | 12/25/2015 | 0 | 100.00 |
| TW A4 (TAXIWAY A4) | 170 | 12/25/2015 | AC | TAXIWAY | P | 0 | 58,588.00 | 12/25/2015 | 0 | 100.00 |
| TW A5 (TAXIWAY A5) | 175 | 12/25/2015 | AC | TAXIWAY | P | 0 | 56,987.00 | 12/25/2015 | 0 | 100.00 |
| TW A6 (TAXIWAY A6) | 180 | 12/25/2015 | AC | TAXIWAY | P | 0 | 58,658.00 | 12/25/2015 | 0 | 100.00 |
| TW B (TAXIWAY B) | 205 | 01/01/1958 | AC | TAXIWAY | P | 0 | 13,950.00 | 01/30/2015 | 57 | 56.00 |
| TW B (TAXIWAY B) | 210 | 01/01/1992 | AAC | TAXIWAY | P | 0 | 6,353.14 | 01/30/2015 | 23 | 64.00 |
| TW B (TAXIWAY B) | 215 | 01/01/2012 | AC | TAXIWAY | P | 0 | 14,952.00 | 01/01/2012 | 0 | 100.00 |
| TW B (TAXIWAY B) | 220 | 01/01/1965 | AC | TAXIWAY | P | 0 | 40,656.00 | 01/30/2015 | 50 | 28.00 |
| TW C (TAXIWAY C) | 305 | 01/01/1992 | AAC | TAXIWAY | P | 0 | 42,705.81 | 01/30/2015 | 23 | 36.00 |

Date: 5/15/2015

Section Condition Report

10 of 20

Pavement Database: FDOT NetworkID: PIE

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| TW D (TAXIWAY D) | 405 | 01/01/1990 | AAC | TAXIWAY | P | 0 | 5,250.00 | 01/30/2015 | 25 | 52.00 |
| TW D (TAXIWAY D) | 407 | 01/01/1996 | AAC | TAXIWAY | P | 0 | 25,816.41 | 01/30/2015 | 19 | 52.00 |
| TW D (TAXIWAY D) | 410 | 01/01/1992 | AAC | TAXIWAY | P | 0 | 16,196.00 | 01/30/2015 | 23 | 46.00 |
| TW F (TAXIWAY F) | 605 | 01/01/1984 | AAC | TAXIWAY | P | 0 | 12,798.00 | 01/30/2015 | 31 | 37.00 |
| TW F (TAXIWAY F) | 607 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 8,127.00 | 01/01/2012 | 0 | 100.00 |
| TW F (TAXIWAY F) | 610 | 01/01/1989 | AAC | TAXIWAY | P | 0 | 7,653.56 | 01/30/2015 | 26 | 41.00 |
| TW F (TAXIWAY F) | 615 | 01/01/1989 | AAC | TAXIWAY | P | 0 | 25,000.00 | 01/30/2015 | 26 | 56.00 |
| TW F (TAXIWAY F) | 620 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 7,752.98 | 12/25/2015 | 0 | 100.00 |
| TW F (TAXIWAY F) | 626 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 10,413.60 | 12/25/2015 | 0 | 100.00 |
| TW F (TAXIWAY F) | 630 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 27,595.00 | 12/25/2015 | 0 | 100.00 |
| TW H (TAXIWAY H) | 810 | 01/01/1965 | AC | TAXIWAY | P | 0 | 64,486.00 | 01/30/2015 | 50 | 6.00 |
| TW H (TAXIWAY H) | 815 | 01/01/2015 | AC | TAXIWAY | P | 0 | 57,784.00 | 01/01/2015 | 0 | 100.00 |
| TW J (TAXIWAY J) | 1005 | 01/01/1984 | AC | TAXIWAY | P | 0 | 11,640.00 | 01/30/2015 | 31 | 46.00 |
| TW J (TAXIWAY J) | 1010 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 8,369.00 | 01/01/2012 | 0 | 100.00 |
| TW K (TAXIWAY K) | 1105 | 01/01/1970 | AC | TAXIWAY | P | 0 | 21,520.15 | 01/30/2015 | 45 | 73.00 |
| TW K (TAXIWAY K) | 1110 | 01/01/1984 | AAC | TAXIWAY | P | 0 | 19,512.49 | 01/30/2015 | 31 | 78.00 |
| TW K (TAXIWAY K) | 1120 | 01/01/1984 | AC | TAXIWAY | P | 0 | 1,969.32 | 01/30/2015 | 31 | 55.00 |
| TW K (TAXIWAY K) | 1125 | 01/01/1984 | AC | TAXIWAY | P | 0 | 2,136.50 | 01/30/2015 | 31 | 58.00 |
| TW K (TAXIWAY K) | 1130 | 01/01/1984 | AC | TAXIWAY | P | 0 | 2,268.24 | 01/30/2015 | 31 | 42.00 |
| TW L (TAXIWAY L) | 1205 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 20,812.00 | 12/25/2015 | 0 | 100.00 |
| TW L (TAXIWAY L) | 1215 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 13,483.00 | 12/25/2015 | 0 | 100.00 |
| TW L (TAXIWAY L) | 1245 | 01/01/1986 | AAC | TAXIWAY | P | 0 | 18,679.00 | 01/30/2015 | 29 | 32.00 |
| TW L (TAXIWAY L) | 1247 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 33,633.00 | 12/25/2015 | 0 | 100.00 |
| TW M (TAXIWAY M) | 1325 | 01/01/1984 | AC | TAXIWAY | P | 0 | 213,248.00 | 01/30/2015 | 31 | 42.00 |
| TW M (TAXIWAY M) | 1330 | 01/01/1984 | AC | TAXIWAY | P | 0 | 8,134.00 | 01/30/2015 | 31 | 33.00 |
| TW M (TAXIWAY M) | 1335 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 10,287.00 | 01/01/2012 | 0 | 100.00 |

Date: 5 /15/2015

Section Condition Report

11 of 20

Pavement Database: FDOT NetworkID: PIE

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|--|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| TW P (TAXIWAY P) | 1250 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 28,635.00 | 12/25/2015 | 0 | 100.00 |
| TW P (TAXIWAY P) | 1255 | 12/25/2015 | AAC | TAXIWAY | P | 0 | 52,339.00 | 12/25/2015 | 0 | 100.00 |
| TW T (APRON TAXIWAY SOUTH OF MAIN APRON) | 2050 | 01/01/1997 | AC | TAXIWAY | P | 0 | 175,302.00 | 01/30/2015 | 18 | 22.00 |

Date: 5/15/2015

Section Condition Report

12 of 20

Pavement Database: FDOT NetworkID: SPG

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP (APRON) | 4105 | 01/01/1991 | AC | APRON | T | 0 | 44,489.04 | 10/08/2014 | 23 | 69.00 |
| AP (APRON) | 4110 | 01/01/1993 | AC | APRON | P | 0 | 128,902.35 | 10/08/2014 | 21 | 61.00 |
| AP (APRON) | 4120 | 01/01/2002 | AAC | APRON | P | 0 | 73,715.58 | 10/08/2014 | 12 | 55.00 |
| AP (APRON) | 4135 | 01/01/2002 | AAC | APRON | P | 0 | 82,247.00 | 10/08/2014 | 12 | 65.00 |
| AP (APRON) | 4140 | 01/01/2006 | AC | APRON | T | 0 | 21,254.96 | 10/08/2014 | 8 | 75.00 |
| AP (APRON) | 4145 | 01/01/1965 | AC | APRON | P | 0 | 14,185.63 | 10/08/2014 | 49 | 59.00 |
| AP MID (APRON MIDFIELD) | 4405 | 01/01/2013 | AC | APRON | P | 0 | 85,370.00 | 01/01/2013 | 0 | 100.00 |
| AP MID (APRON MIDFIELD) | 4410 | 01/01/2013 | AC | APRON | P | 0 | 15,790.00 | 01/01/2013 | 0 | 100.00 |
| AP MID (APRON MIDFIELD) | 4415 | 01/01/2013 | AC | APRON | P | 0 | 6,767.00 | 01/01/2013 | 0 | 100.00 |
| AP NW (APRON NORTHWEST) | 4310 | 01/01/2006 | AC | APRON | P | 0 | 108,494.77 | 10/08/2014 | 8 | 89.00 |
| AP NW (APRON NORTHWEST) | 4315 | 01/01/2011 | AC | APRON | P | 0 | 32,357.38 | 10/08/2014 | 3 | 90.00 |
| AP W (WEST APRON) | 4210 | 11/01/2002 | AC | APRON | T | 0 | 74,621.08 | 10/08/2014 | 12 | 67.00 |
| RW 18-36 (RUNWAY 18-36) | 6105 | 01/01/1992 | AAC | RUNWAY | P | 0 | 286,400.00 | 10/08/2014 | 22 | 61.00 |
| RW 18-36 (RUNWAY 18-36) | 6110 | 01/01/1992 | AAC | RUNWAY | P | 0 | 143,200.00 | 10/08/2014 | 22 | 59.00 |
| RW 7-25 (RUNWAY 7-25) | 6205 | 01/01/1991 | AC | RUNWAY | P | 0 | 18,750.00 | 10/08/2014 | 23 | 62.00 |
| RW 7-25 (RUNWAY 7-25) | 6207 | 01/01/1965 | AC | RUNWAY | P | 0 | 22,950.00 | 10/08/2014 | 49 | 38.00 |
| RW 7-25 (RUNWAY 7-25) | 6208 | 01/01/2012 | AAC | RUNWAY | P | 0 | 21,525.00 | 01/01/2012 | 0 | 100.00 |
| RW 7-25 (RUNWAY 7-25) | 6210 | 01/01/1965 | AC | RUNWAY | P | 0 | 170,116.00 | 10/08/2014 | 49 | 60.00 |
| RW 7-25 (RUNWAY 7-25) | 6215 | 01/01/1991 | AC | RUNWAY | P | 0 | 30,124.55 | 10/08/2014 | 23 | 72.00 |
| TW A (TAXIWAY A) | 105 | 01/01/1987 | AAC | TAXIWAY | P | 0 | 15,000.00 | 10/08/2014 | 27 | 54.00 |
| TW A (TAXIWAY A) | 110 | 01/01/1987 | AAC | TAXIWAY | P | 0 | 21,000.00 | 10/08/2014 | 27 | 59.00 |
| TW A (TAXIWAY A) | 115 | 01/01/1987 | AAC | TAXIWAY | P | 0 | 63,616.68 | 10/08/2014 | 27 | 64.00 |
| TW A1 (TAXIWAY ALPHA 1) | 610 | 01/01/1987 | AAC | TAXIWAY | P | 0 | 11,013.00 | 10/08/2014 | 27 | 27.00 |
| TW A1 (TAXIWAY ALPHA 1) | 620 | 01/01/2013 | AC | TAXIWAY | P | 0 | 11,150.00 | 01/01/2013 | 0 | 100.00 |
| TW A2 (TAXIWAY A2) | 410 | 01/01/1991 | AC | TAXIWAY | P | 0 | 5,039.47 | 10/08/2014 | 23 | 60.00 |
| TW B (TAXIWAY B) | 205 | 01/01/1988 | AAC | TAXIWAY | P | 0 | 87,561.00 | 10/08/2014 | 26 | 69.00 |

Date: 5/15/2015

Section Condition Report

13 of 20

Pavement Database: FDOT NetworkID: SPG

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|----------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| TW B (TAXIWAY B) | 210 | 01/01/1988 | AAC | TAXIWAY | P | 0 | 17,315.07 | 10/08/2014 | 26 | 64.00 |
| TW B (TAXIWAY B) | 215 | 01/01/1965 | AC | TAXIWAY | P | 0 | 3,064.65 | 10/08/2014 | 49 | 41.00 |
| TW B (TAXIWAY B) | 250 | 01/01/1984 | AAC | TAXIWAY | P | 0 | 2,578.25 | 10/08/2014 | 30 | 70.00 |
| TW B (TAXIWAY B) | 251 | 01/01/1989 | APC | TAXIWAY | P | 0 | 3,286.50 | 10/08/2014 | 25 | 37.00 |
| TW B (TAXIWAY B) | 252 | 01/01/1989 | AAC | TAXIWAY | P | 0 | 6,613.30 | 10/08/2014 | 25 | 59.00 |
| TW B (TAXIWAY B) | 253 | 01/01/1987 | AAC | TAXIWAY | P | 0 | 3,405.49 | 10/08/2014 | 27 | 26.00 |
| TW B (TAXIWAY B) | 254 | 01/01/1979 | AC | TAXIWAY | P | 0 | 3,707.45 | 10/08/2014 | 35 | 61.00 |
| TW B (TAXIWAY B) | 256 | 01/01/1989 | AAC | TAXIWAY | P | 0 | 2,468.25 | 10/08/2014 | 25 | 70.00 |
| TW C (TAXIWAY C) | 301 | 01/01/1989 | AAC | TAXIWAY | P | 0 | 3,886.03 | 10/08/2014 | 25 | 21.00 |
| TW C (TAXIWAY C) | 305 | 01/01/1950 | AC | TAXIWAY | P | 0 | 61,204.00 | 10/08/2014 | 64 | 21.00 |
| TW C (TAXIWAY C) | 307 | 01/01/1991 | AAC | TAXIWAY | P | 0 | 34,987.00 | 10/08/2014 | 23 | 58.00 |
| TW C (TAXIWAY C) | 308 | 01/01/1991 | AAC | TAXIWAY | P | 0 | 38,125.00 | 10/08/2014 | 23 | 68.00 |
| TW C (TAXIWAY C) | 310 | 01/01/1987 | AAC | TAXIWAY | P | 0 | 27,794.00 | 10/08/2014 | 27 | 54.00 |
| TW D (TAXIWAY DELTA) | 150 | 01/01/1991 | AC | TAXIWAY | P | 0 | 7,347.96 | 10/08/2014 | 23 | 64.00 |
| TW D (TAXIWAY DELTA) | 155 | 01/01/1991 | AC | TAXIWAY | P | 0 | 7,303.60 | 10/08/2014 | 23 | 64.00 |
| TW D (TAXIWAY DELTA) | 160 | 01/01/1991 | AC | TAXIWAY | P | 0 | 2,171.50 | 10/08/2014 | 23 | 69.00 |
| TW D (TAXIWAY DELTA) | 505 | 01/01/2011 | AC | TAXIWAY | P | 0 | 8,728.78 | 10/08/2014 | 3 | 89.00 |
| TW D (TAXIWAY DELTA) | 510 | 01/01/2002 | AC | TAXIWAY | P | 0 | 33,920.07 | 10/08/2014 | 12 | 70.00 |
| TW D (TAXIWAY DELTA) | 515 | 01/01/2011 | AC | TAXIWAY | P | 0 | 23,102.19 | 10/08/2014 | 3 | 92.00 |
| TW D1 (TAXIWAY D1) | 615 | 01/01/2011 | AC | TAXIWAY | P | 0 | 5,505.23 | 10/08/2014 | 3 | 66.00 |
| TW N (NORTH TAXIWAY) | 710 | 01/01/2002 | AC | TAXIWAY | P | 0 | 33,564.14 | 10/08/2014 | 12 | 68.00 |
| TW N (NORTH TAXIWAY) | 720 | 01/01/2002 | AC | TAXIWAY | P | 0 | 13,336.78 | 10/08/2014 | 12 | 58.00 |
| TW N (NORTH TAXIWAY) | 730 | 01/01/2002 | AC | TAXIWAY | P | 0 | 12,506.24 | 10/08/2014 | 12 | 71.00 |
| TW N (NORTH TAXIWAY) | 740 | 01/01/2002 | AC | TAXIWAY | P | 0 | 33,186.37 | 10/08/2014 | 12 | 67.00 |

Date: 5/15/2015

Section Condition Report

14 of 20

Pavement Database: FDOT NetworkID: TPF

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-------------------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| AP (APRON) | 4110 | 01/01/2011 | AAC | APRON | P | 0 | 150,952.39 | 10/06/2014 | 3 | 84.00 |
| AP (APRON) | 4140 | 01/01/1986 | AC | APRON | P | 0 | 14,966.77 | 10/06/2014 | 28 | 63.00 |
| AP RU (APRON) | 5105 | 01/01/2008 | AAC | APRON | P | 0 | 3,153.64 | 10/06/2014 | 6 | 70.00 |
| AP RU (APRON) | 5110 | 01/01/2008 | AAC | APRON | P | 0 | 4,385.84 | 10/06/2014 | 6 | 75.00 |
| AP RU (APRON) | 5115 | 01/01/2007 | AC | APRON | P | 0 | 16,251.05 | 10/06/2014 | 7 | 94.00 |
| RW 18-36 (RUNWAY 18-36) | 6205 | 01/01/2008 | AAC | RUNWAY | S | 0 | 191,016.57 | 10/06/2014 | 6 | 85.00 |
| RW 4-22 (RUNWAY 4-22) | 6103 | 01/01/2007 | AC | RUNWAY | P | 0 | 32,500.00 | 10/06/2014 | 7 | 93.00 |
| RW 4-22 (RUNWAY 4-22) | 6105 | 01/01/2001 | AAC | RUNWAY | P | 0 | 310,500.00 | 10/06/2014 | 13 | 58.00 |
| RW 4-22 (RUNWAY 4-22) | 6110 | 01/01/2007 | AAC | RUNWAY | P | 0 | 17,800.00 | 10/06/2014 | 7 | 91.00 |
| T/L HANG (TAXILANE TO EAST HANGARS) | 800 | 01/01/2011 | AC | TAXIWAY | P | 0 | 29,573.00 | 10/06/2014 | 3 | 94.00 |
| TW A (TAXIWAY A) | 103 | 01/01/2007 | AC | TAXIWAY | P | 0 | 5,615.69 | 10/06/2014 | 7 | 84.00 |
| TW A (TAXIWAY A) | 104 | 01/01/2007 | AC | TAXIWAY | P | 0 | 9,170.00 | 10/06/2014 | 7 | 80.00 |
| TW A (TAXIWAY A) | 105 | 01/01/1992 | AAC | TAXIWAY | P | 0 | 103,252.19 | 10/06/2014 | 22 | 60.00 |
| TW A (TAXIWAY A) | 115 | 01/01/2008 | AAC | TAXIWAY | P | 0 | 11,155.15 | 10/06/2014 | 6 | 88.00 |
| TW A (TAXIWAY A) | 120 | 01/01/2008 | AAC | TAXIWAY | P | 0 | 5,876.45 | 10/06/2014 | 6 | 80.00 |
| TW A (TAXIWAY A) | 630 | 01/01/2007 | AC | TAXIWAY | P | 0 | 4,673.45 | 10/06/2014 | 7 | 94.00 |
| TW B (TAXIWAY B) | 150 | 01/01/1992 | AAC | TAXIWAY | P | 0 | 4,673.00 | 10/06/2014 | 22 | 57.00 |
| TW B (TAXIWAY B) | 205 | 01/01/2011 | AAC | TAXIWAY | P | 0 | 11,793.45 | 10/06/2014 | 3 | 93.00 |
| TW C (TAXIWAY C) | 305 | 01/01/2010 | AAC | TAXIWAY | P | 0 | 7,165.00 | 10/06/2014 | 4 | 77.00 |
| TW C (TAXIWAY C) | 310 | 01/01/1965 | AC | TAXIWAY | P | 0 | 16,840.00 | 10/06/2014 | 49 | 55.00 |
| TW CENTER (TAXIWAY CENTER) | 315 | 01/01/2008 | AC | TAXIWAY | P | 0 | 11,056.09 | 10/06/2014 | 6 | 80.00 |
| TW CENTER (TAXIWAY CENTER) | 320 | 01/01/2008 | AC | TAXIWAY | P | 0 | 11,536.12 | 10/06/2014 | 6 | 90.00 |
| TW CENTER (TAXIWAY CENTER) | 325 | 01/01/2008 | AC | TAXIWAY | P | 0 | 33,247.46 | 10/06/2014 | 6 | 89.00 |
| TW D (TAXIWAY D) | 420 | 01/01/2011 | AAC | TAXIWAY | P | 0 | 41,269.85 | 10/06/2014 | 3 | 94.00 |
| TW D (TAXIWAY D) | 425 | 01/01/1992 | AAC | TAXIWAY | P | 0 | 5,338.00 | 10/06/2014 | 22 | 45.00 |
| TW E (TAXIWAY E) | 505 | 01/01/2005 | AAC | TAXIWAY | P | 0 | 2,353.21 | 10/06/2014 | 9 | 87.00 |

Date: 5 /15/2015

Section Condition Report

15 of 20

Pavement Database: FDOT NetworkID: TPF

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|----------------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| TW E (TAXIWAY E) | 510 | 01/01/1965 | AC | TAXIWAY | P | 0 | 11,125.79 | 10/06/2014 | 49 | 59.00 |
| TW E (TAXIWAY E) | 515 | 01/01/2011 | AC | TAXIWAY | P | 0 | 4,952.00 | 10/06/2014 | 3 | 89.00 |
| TW E (TAXIWAY E) | 650 | 01/01/2008 | AAC | TAXIWAY | P | 0 | 5,470.82 | 10/06/2014 | 6 | 90.00 |
| TW F (TAXIWAY F) | 605 | 01/01/2008 | AAC | TAXIWAY | P | 0 | 88,517.00 | 10/06/2014 | 6 | 89.00 |
| TW F (TAXIWAY F) | 610 | 01/01/2008 | AAC | TAXIWAY | P | 0 | 9,627.00 | 10/06/2014 | 6 | 69.00 |
| TW G (TAXIWAY G) | 750 | 01/01/2011 | AC | TAXIWAY | P | 0 | 12,333.00 | 10/06/2014 | 3 | 94.00 |
| TW T-HANG (TAXIWAY TO T-HANGARS) | 705 | 01/01/1964 | AC | TAXIWAY | P | 0 | 72,024.05 | 10/06/2014 | 50 | 53.00 |

Date: 5 /15/2015

Section Condition Report

16 of 20

Pavement Database: FDOT NetworkID: VDF

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-----------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP A - S (SOUTH APRON "A") | 4105 | 01/01/1986 | AC | APRON | P | 0 | 77,867.94 | 12/10/2014 | 28 | 70.00 |
| AP A - S (SOUTH APRON "A") | 4110 | 01/01/1986 | AC | APRON | P | 0 | 114,380.62 | 12/10/2014 | 28 | 72.00 |
| AP A - S (SOUTH APRON "A") | 4115 | 01/01/1986 | AC | APRON | P | 0 | 4,469.52 | 12/10/2014 | 28 | 76.00 |
| AP B - N (NORTH APRON "B") | 4205 | 01/01/1991 | AC | APRON | P | 0 | 131,692.43 | 12/10/2014 | 23 | 73.00 |
| AP B - N (NORTH APRON "B") | 4210 | 01/01/1986 | AC | APRON | P | 0 | 100,787.54 | 12/10/2014 | 28 | 100.00 |
| AP C (APRON C) | 4305 | 01/01/1999 | AC | APRON | T | 0 | 424,105.21 | 12/10/2014 | 15 | 70.00 |
| AP C (APRON C) | 4405 | 01/01/1999 | AC | APRON | P | 0 | 70,926.49 | 12/10/2014 | 15 | 73.00 |
| AP RU (RUN-UP APRON) | 5105 | 01/01/1986 | AAC | APRON | P | 0 | 24,993.73 | 12/10/2014 | 28 | 75.00 |
| AP RU (RUN-UP APRON) | 5110 | 01/01/1986 | AC | APRON | P | 0 | 3,338.00 | 12/10/2014 | 28 | 65.00 |
| AP T-HANG (T-HANGARS APRON) | 4310 | 01/01/1974 | AC | APRON | P | 0 | 147,914.37 | 12/10/2014 | 40 | 100.00 |
| AP T-HANG (T-HANGARS APRON) | 4315 | 12/25/2009 | AC | APRON | P | 0 | 12,031.00 | 12/10/2014 | 5 | 83.00 |
| AP W (APRON WEST) | 4505 | 01/01/1999 | AC | APRON | P | 0 | 28,314.42 | 12/10/2014 | 15 | 65.00 |
| AP W (APRON WEST) | 4510 | 01/01/1999 | AC | APRON | P | 0 | 37,083.69 | 12/10/2014 | 15 | 74.00 |
| RW 18-36 (RUNWAY 18-36) | 6105 | 01/01/1986 | AC | RUNWAY | P | 0 | 243,145.00 | 12/10/2014 | 28 | 70.00 |
| RW 5-23 (RUNWAY 5-23) | 6205 | 01/01/1999 | AC | RUNWAY | P | 0 | 500,000.00 | 12/10/2014 | 15 | 71.00 |
| TW A (TAXIWAY A) | 105 | 01/01/1986 | AC | TAXIWAY | P | 0 | 115,430.00 | 12/10/2014 | 28 | 66.00 |
| TW A (TAXIWAY A) | 120 | 01/01/1986 | AC | TAXIWAY | P | 0 | 2,772.00 | 12/10/2014 | 28 | 71.00 |
| TW A (TAXIWAY A) | 140 | 01/01/1986 | AC | TAXIWAY | P | 0 | 3,862.00 | 12/10/2014 | 28 | 70.00 |
| TW A (TAXIWAY A) | 160 | 01/01/1986 | AC | TAXIWAY | P | 0 | 3,861.00 | 12/10/2014 | 28 | 65.00 |
| TW A (TAXIWAY A) | 180 | 01/01/1986 | AC | TAXIWAY | P | 0 | 4,111.00 | 12/10/2014 | 28 | 72.00 |
| TW A (TAXIWAY A) | 205 | 01/01/1986 | AC | TAXIWAY | P | 0 | 2,293.36 | 12/10/2014 | 28 | 68.00 |
| TW B (TAXIWAY B) | 210 | 01/01/1989 | AC | TAXIWAY | P | 0 | 15,267.65 | 12/10/2014 | 25 | 32.00 |
| TW B (TAXIWAY B) | 250 | 01/01/1989 | AC | TAXIWAY | P | 0 | 7,286.29 | 12/10/2014 | 25 | 34.00 |
| TW C (TAXIWAY C) | 405 | 01/01/2001 | AC | TAXIWAY | S | 0 | 21,766.85 | 12/10/2014 | 13 | 72.00 |
| TW D (TAXIWAY D) | 170 | 01/01/1986 | AC | TAXIWAY | P | 0 | 5,063.00 | 12/10/2014 | 28 | 66.00 |
| TW D (TAXIWAY D) | 305 | 01/01/2001 | AC | TAXIWAY | T | 0 | 31,410.64 | 12/10/2014 | 13 | 70.00 |

Date: 5 /15/2015

Section Condition Report

17 of 20

Pavement Database: FDOT NetworkID: VDF

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|----------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| TW E (TW E) | 505 | 01/01/1999 | AC | TAXIWAY | P | 0 | 145,753.06 | 12/10/2014 | 15 | 79.00 |
| TW E1 (TW E-1) | 510 | 01/01/1999 | AC | TAXIWAY | P | 0 | 9,577.05 | 12/10/2014 | 15 | 76.00 |
| TW E2 (TW E-2) | 515 | 01/01/1999 | AC | TAXIWAY | P | 0 | 9,510.95 | 12/10/2014 | 15 | 76.00 |
| TW E3 (TW E3) | 520 | 01/01/1999 | AC | TAXIWAY | P | 0 | 9,875.77 | 12/10/2014 | 15 | 80.00 |
| TW E4 (TW E-4) | 525 | 01/01/1999 | AC | TAXIWAY | P | 0 | 8,961.31 | 12/10/2014 | 15 | 80.00 |
| TW F (TW F) | 605 | 01/01/1999 | AC | TAXIWAY | P | 0 | 98,237.43 | 12/10/2014 | 15 | 76.00 |
| TW F (TW F) | 610 | 01/01/1999 | AAC | TAXIWAY | P | 0 | 4,871.00 | 12/10/2014 | 15 | 72.00 |
| TW F (TW F) | 615 | 01/01/1999 | AC | TAXIWAY | P | 0 | 4,552.00 | 12/10/2014 | 15 | 70.00 |
| TW J (TW J) | 705 | 01/01/1999 | AC | TAXIWAY | P | 0 | 61,282.28 | 12/10/2014 | 15 | 69.00 |
| TW J (TW J) | 710 | 01/01/1999 | AC | TAXIWAY | P | 0 | 31,786.25 | 12/10/2014 | 15 | 69.00 |
| TW J (TW J) | 715 | 01/01/1999 | AC | TAXIWAY | P | 0 | 12,020.38 | 12/10/2014 | 15 | 71.00 |

Date: 5/15/2015

Section Condition Report

18 of 20

Pavement Database: FDOT NetworkID: ZPH

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|--------------------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| AP E (EAST APRON) | 5405 | 12/25/1999 | PCC | APRON | P | 0 | 34,097.36 | 09/09/2013 | 14 | 12.00 |
| AP NE (NORTHEAST APRON) | 5105 | 01/01/1942 | AC | APRON | P | 0 | 27,750.00 | 09/09/2013 | 71 | 40.00 |
| AP NW (NORTHWEST APRON) | 4105 | 01/01/1970 | PCC | APRON | P | 0 | 2,160.00 | 09/09/2013 | 43 | 59.00 |
| AP NW (NORTHWEST APRON) | 4110 | 01/01/1982 | AC | APRON | P | 0 | 5,095.36 | 09/09/2013 | 31 | 64.00 |
| AP NW (NORTHWEST APRON) | 4115 | 01/01/2004 | AC | APRON | P | 0 | 12,547.35 | 09/09/2013 | 9 | 97.00 |
| AP RU 22 (APRON RUN-UP 22) | 5115 | 01/01/2013 | AC | APRON | P | 0 | 47,922.50 | 01/01/2013 | 0 | 100.00 |
| AP T-HANG (APRON T-HANGARS) | 5305 | 12/25/1999 | AC | APRON | P | 0 | 108,938.27 | 09/09/2013 | 14 | 46.00 |
| AP T-HANG2 (APRON T-HANG 2) | 5505 | 01/01/2008 | AC | APRON | P | 0 | 85,817.46 | 09/09/2013 | 5 | 80.00 |
| AP T-HANG3 (APRON T-HANG 3) | 5510 | 01/01/2008 | AC | APRON | P | 0 | 164,471.32 | 09/09/2013 | 5 | 84.00 |
| AP TW D (APRON AT END OF TW D) | 5205 | 12/25/1999 | AC | APRON | P | 0 | 26,359.62 | 09/09/2013 | 14 | 51.00 |
| RW 18-36 (RUNWAY 18-36) | 6205 | 01/01/2002 | AAC | RUNWAY | P | 0 | 473,437.11 | 09/09/2013 | 11 | 67.00 |
| RW 5-23 (RUNWAY 5-23) | 6105 | 01/01/2013 | AAC | RUNWAY | P | 0 | 229,400.00 | 01/01/2013 | 0 | 100.00 |
| RW 5-23 (RUNWAY 5-23) | 6107 | 01/01/2013 | AAC | RUNWAY | P | 0 | 229,400.00 | 01/01/2013 | 0 | 100.00 |
| RW 5-23 (RUNWAY 5-23) | 6110 | 01/01/2013 | AC | RUNWAY | P | 0 | 20,600.00 | 01/01/2013 | 0 | 100.00 |
| RW 5-23 (RUNWAY 5-23) | 6115 | 01/01/2013 | AC | RUNWAY | P | 0 | 20,600.00 | 01/01/2013 | 0 | 100.00 |
| RW 5-23 (RUNWAY 5-23) | 6219 | 01/01/2013 | AC | RUNWAY | P | 0 | 1,000.00 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 105 | 01/01/1990 | AAC | TAXIWAY | P | 0 | 72,269.00 | 09/09/2013 | 23 | 60.00 |
| TW A (TAXIWAY A) | 106 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 11,603.00 | 01/01/2013 | 0 | 100.00 |
| TW A (TAXIWAY A) | 107 | 01/01/1990 | AAC | TAXIWAY | P | 0 | 10,000.00 | 09/09/2013 | 23 | 64.00 |
| TW A (TAXIWAY A) | 110 | 01/01/1989 | AC | TAXIWAY | P | 0 | 188,930.00 | 09/09/2013 | 24 | 62.00 |
| TW A (TAXIWAY A) | 120 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 7,558.50 | 01/01/2013 | 0 | 100.00 |
| TW A-1 (TAXIWAY A-1) | 115 | 01/01/1996 | AC | TAXIWAY | P | 0 | 17,528.00 | 09/09/2013 | 17 | 64.00 |
| TW A-1 (TAXIWAY A-1) | 117 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 14,976.00 | 01/01/2013 | 0 | 100.00 |
| TW A-2 (TAXIWAY A-2) | 305 | 01/01/2013 | AAC | TAXIWAY | T | 0 | 20,430.00 | 01/01/2013 | 0 | 100.00 |
| TW A-2 (TAXIWAY A-2) | 310 | 01/01/1990 | AAC | TAXIWAY | P | 0 | 15,330.00 | 09/09/2013 | 23 | 54.00 |
| TW B (TAXIWAY B) | 205 | 01/01/1942 | AC | TAXIWAY | T | 0 | 49,464.00 | 09/09/2013 | 71 | 25.00 |

Date: 5 /15/2015

Section Condition Report

19 of 20

Pavement Database: FDOT NetworkID: ZPH



| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|----------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| TW B (TAXIWAY B) | 210 | 01/01/1989 | AAC | TAXIWAY | P | 0 | 17,898.00 | 09/09/2013 | 24 | 33.00 |
| TW B (TAXIWAY B) | 212 | 01/01/1990 | AAC | TAXIWAY | P | 0 | 17,871.46 | 09/09/2013 | 23 | 59.00 |
| TW B (TAXIWAY B) | 215 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 11,738.00 | 01/01/2013 | 0 | 100.00 |
| TW B (TAXIWAY B) | 220 | 01/01/1989 | AAC | TAXIWAY | P | 0 | 133,310.00 | 09/09/2013 | 24 | 5.00 |
| TW B (TAXIWAY B) | 225 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 6,848.00 | 01/01/2013 | 0 | 100.00 |
| TW B (TAXIWAY B) | 230 | 01/01/1942 | PCC | TAXIWAY | P | 0 | 15,000.00 | 09/09/2013 | 71 | 12.00 |
| TW B (TAXIWAY B) | 235 | 01/01/2013 | AAC | TAXIWAY | P | 0 | 2,233.36 | 01/01/2013 | 0 | 100.00 |
| TW B (TAXIWAY B) | 240 | 01/01/2002 | AAC | TAXIWAY | P | 0 | 31,377.52 | 09/09/2013 | 11 | 54.00 |
| TW B (TAXIWAY B) | 245 | 01/01/2002 | AAC | TAXIWAY | P | 0 | 2,300.12 | 09/09/2013 | 11 | 28.00 |
| TW C (TAXIWAY C) | 320 | 01/01/2010 | AAC | TAXIWAY | P | 0 | 69,379.41 | 09/09/2013 | 3 | 90.00 |
| TW C-1 (TAXIWAY C-1) | 505 | 01/01/1982 | AC | TAXIWAY | P | 0 | 6,000.00 | 09/09/2013 | 31 | 62.00 |
| TW C-1 (TAXIWAY C-1) | 510 | 01/01/2010 | AAC | TAXIWAY | P | 0 | 4,443.84 | 09/09/2013 | 3 | 93.00 |
| TW D (TAXIWAY D) | 405 | 12/25/1999 | AC | TAXIWAY | P | 0 | 25,063.48 | 09/09/2013 | 14 | 54.00 |
| TW E (TAXIWAY E) | 610 | 01/01/2002 | AC | TAXIWAY | P | 0 | 32,964.38 | 09/09/2013 | 11 | 95.00 |
| TW F (TAXIWAY F) | 630 | 01/01/2002 | AC | TAXIWAY | P | 0 | 24,348.01 | 09/09/2013 | 11 | 65.00 |

Section Condition Report*Pavement Database: FDOT*

| Age Category | Average Age At Inspection | Total Area (SqFt) | Number of Sections | Arithmetic Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------|---------------------------|----------------------|--------------------|------------------------|------------------------|----------------------|
| 0-02 | 0.07 | 4,263,812.10 | 86 | 99.86 | 0.91 | 99.86 |
| 03-05 | 3.47 | 1,584,983.18 | 30 | 91.07 | 8.65 | 92.75 |
| 06-10 | 7.22 | 1,010,673.62 | 27 | 78.30 | 17.51 | 72.87 |
| 11-15 | 12.95 | 5,966,449.82 | 82 | 64.68 | 13.46 | 65.17 |
| 16-20 | 17.20 | 430,147.01 | 10 | 56.50 | 13.54 | 44.80 |
| 21-25 | 22.80 | 2,896,405.03 | 61 | 54.64 | 14.48 | 55.25 |
| 26-30 | 27.65 | 1,457,681.10 | 34 | 59.03 | 17.73 | 65.58 |
| 31-35 | 31.31 | 316,787.24 | 13 | 50.46 | 13.49 | 44.80 |
| 36-40 | 38.40 | 251,489.18 | 5 | 63.00 | 21.42 | 80.80 |
| over 40 | 59.50 | 3,573,295.50 | 38 | 42.45 | 18.71 | 49.47 |
| All | 17.44 | 21,751,723.78 | 386 | 70.54 | 23.63 | 69.95 |

APPENDIX C

- ◎ DISTRICT AIRFIELD PAVEMENT CONDITION INDEX
RATING EXHIBITS



LEGEND



- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

SECTION NO. "PCI NO."

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|---------------|------------|--------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA |
| DATE: 2013 | | |





LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TWA TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

SECTION NO. "PCI NO."



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2013 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
CRYSTAL RIVER AIRPORT
CITRUS COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

"SECTION NO."
"PCI NO."



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2015 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
CLEARWATER AIRPARK
PINELLAS COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

"SECTION NO."
"PCI NO."





RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2013 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
INVERNESS AIRPORT
CITRUS COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

| | |
|--|------------------------|
| | PCI 86-100 GOOD |
| | PCI 71-85 SATISFACTORY |
| | PCI 56-70 FAIR |
| | PCI 41-55 POOR |
| | PCI 26-40 VERY POOR |
| | PCI 11-25 SERIOUS |
| | PCI 0-10 FAILED |

SECTION NO. / PCI NO.



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2013 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
PLANT CITY AIRPORT
HILLSBOROUGH COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



RUNWAYS

| | | | | | | |
|-------------------|------------------|------------------|-------------------|-------------------|-------------------|-------------------|
| 6115 PCI = 72 | 6120 PCI = 78 | 6135 PCI = 74 | 6140 PCI = 77 | 6145 PCI = 71 | 6150 PCI = 76 | 6155 PCI = 63 |
| 6160 PCI = 75 | 6165 PCI = 72 | 6170 PCI = 74 | 6175 PCI = 65 | 6180 PCI = 79 | 6185 PCI = 54 | 6190 PCI = 82 |
| 6196 PCI = 100 | 6197 PCI = 52 | 6198 PCI = 82 | 6205 PCI = 100 | 6210 PCI = 100 | 6215 PCI = 100 | 6220 PCI = 100 |
| 6230 PCI = 23 | 6315 PCI = 42 | 6320 PCI = 43 | 6325 PCI = 49 | 6330 PCI = 74 | 6335 PCI = 44 | 6340 PCI = 32 |
| 6350 PCI = 47 | 6355 PCI = 37 | 6360 PCI = 65 | 6365 PCI = 46 | 6370 PCI = 59 | | |

TAXIWAYS

| | | | | | | | | | | | |
|-------------------|-------------------|------------------|-------------------|------------------|------------------|------------------|-------------------|-------------------|------------------|-------------------|-------------------|
| 112 PCI = 66 | 114 PCI = 33 | 115 PCI = 100 | 117 PCI = 50 | 119 PCI = 33 | 125 PCI = 100 | 127 PCI = 100 | 130 PCI = 100 | 135 PCI = 100 | 140 PCI = 100 | 160 PCI = 100 | 165 PCI = 100 |
| 158 PCI = 100 | 160 PCI = 39 | 165 PCI = 100 | 168 PCI = 100 | 170 PCI = 100 | 175 PCI = 100 | 180 PCI = 100 | 205 PCI = 56 | 210 PCI = 64 | 215 PCI = 100 | 220 PCI = 28 | 305 PCI = 36 |
| 405 PCI = 52 | 407 PCI = 52 | 410 PCI = 46 | 605 PCI = 37 | 607 PCI = 100 | 610 PCI = 41 | 615 PCI = 56 | 620 PCI = 100 | 626 PCI = 100 | 630 PCI = 100 | 810 PCI = 6 | 815 PCI = 100 |
| 1005 PCI = 46 | 1010 PCI = 100 | 1105 PCI = 73 | 1110 PCI = 78 | 1120 PCI = 55 | 1125 PCI = 58 | 1130 PCI = 42 | 1205 PCI = 100 | 1215 PCI = 100 | 1245 PCI = 32 | 1247 PCI = 100 | 1250 PCI = 100 |
| 1255 PCI = 100 | 1325 PCI = 42 | 1330 PCI = 33 | 1335 PCI = 100 | 2050 PCI = 22 | | | | | | | |

OTHERS

| | | | | | | |
|-------------------|------------------|-------------------|-------------------|-------------------|-------------------|-------------------|
| 4105 PCI = 55 | 4123 PCI = 53 | 4130 PCI = 100 | 4155 PCI = 62 | 4157 PCI = 100 | 4165 PCI = 100 | 4170 PCI = 100 |
| 4175 PCI = 3 | 4176 PCI = 4 | 4177 PCI = 100 | 4178 PCI = 100 | 4179 PCI = 100 | 4180 PCI = 25 | 4183 PCI = 100 |
| 4185 PCI = 100 | 4190 PCI = 28 | 4195 PCI = 12 | 4199 PCI = 51 | 4205 PCI = 41 | 4305 PCI = 37 | |

LEGEND



- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

"SECTION NO."
"PCI NO."

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |





- TAXIWAYS**
- 110 PCI = 59
 - 115 PCI = 64
 - 308 PCI = 68
 - 505 PCI = 89
 - 620 PCI = 100
- OTHERS**
- 4315 PCI = 90
 - 4405 PCI = 100
 - 4410 PCI = 100

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED


SECTION NO. "PCI NO."

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |


| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2015 |
|---------------|------------|--------------|------------|





TAXIWAYS

| | | | | | |
|-----------------|-----------------|-----------------|-----------------|-----------------|-----------------|
| 115 PCI = 88 | 205 PCI = 93 | 305 PCI = 77 | 310 PCI = 55 | 315 PCI = 80 | 320 PCI = 90 |
| 325 PCI = 89 | 420 PCI = 94 | 505 PCI = 87 | 510 PCI = 59 | 705 PCI = 53 | |



LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED



SECTION NO. "PCI NO."

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--|------|-----------|
| | | |
| | | |
| DESIGNED: | KHA | DRAWN: |
| CHECKED: | KHA | DATE: |
| PLOTTED: May 1, 2015 - 10:47 AM BY: BMM, M | | |



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
 PETER O. KNIGHT AIRPORT
 HILLSBOROUGH COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



| TAXIWAYS | | | | | |
|------------------|-------------------|-------------------|------------------|------------------|-----------------|
| 140 PCI = 70 | 160 PCI = 65 | 170 PCI = 66 | 180 PCI = 72 | 205 PCI = 68 | 510 PCI = 76 |
| OTHERS | | | | | |
| 4115 PCI = 76 | 4210 PCI = 100 | 4310 PCI = 100 | 4315 PCI = 83 | 4405 PCI = 73 | |

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

SECTION NO. "PCI NO."


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |


| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2015 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
TAMPA EXECUTIVE AIRPORT
HILLSBOROUGH COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



| TAXIWAYS | | | | OTHERS | | |
|-----------------|------------------|------------------|-----------------|------------------|------------------|------------------|
| 105 PCI = 60 | 107 PCI = 64 | 205 PCI = 25 | 210 PCI = 33 | 4105 PCI = 59 | 4110 PCI = 64 | 5105 PCI = 40 |
| 212 PCI = 59 | 215 PCI = 100 | 305 PCI = 100 | 310 PCI = 54 | 5205 PCI = 51 | 5305 PCI = 46 | |
| 320 PCI = 90 | 405 PCI = 54 | 505 PCI = 62 | 510 PCI = 93 | | | |



LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

SECTION NO.
PCI NO.

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

DESIGNED: KHA DRAWN: KHA CHECKED: KHA DATE: 2013



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
ZEPHYRHILLS MUNICIPAL AIRPORT
PASCO COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE

APPENDIX D

● DISTRICT 10-YEAR MAJOR REHABILITATION NEEDS



BKV – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch Name | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|------|-------------|------------|------------------|----------------|------------------|---------------|
| 2014 | AP NE | 4135 | \$ 591,224.27 | 63 | Mill and Overlay | 100 |
| 2014 | AP NE | 4145 | \$ 728,091.77 | 55 | Mill and Overlay | 100 |
| 2014 | AP NE | 4147 | \$ 73,709.00 | 55 | Mill and Overlay | 100 |
| 2014 | AP NE | 4150 | \$ 280,173.09 | 56 | PCC Restoration | 100 |
| 2014 | AP NE | 4125 | \$ 237,395.29 | 62 | Mill and Overlay | 100 |
| 2014 | AP NE | 4110 | \$ 145,918.09 | 51 | Mill and Overlay | 100 |
| 2014 | AP NE | 4130 | \$ 92,197.07 | 35 | Reconstruction | 100 |
| 2014 | AP NE | 4115 | \$ 357,996.18 | 51 | Mill and Overlay | 100 |
| 2014 | AP NE | 4105 | \$ 330,801.57 | 48 | Mill and Overlay | 100 |
| 2014 | AP NE | 4120 | \$ 530,576.18 | 52 | Mill and Overlay | 100 |
| 2014 | AP S | 4205 | \$ 33,984.70 | 64 | Mill and Overlay | 100 |
| 2014 | RW 3-21 | 6210 | \$ 5,014,999.76 | 54 | PCC Restoration | 100 |
| 2014 | RW 3-21 | 6205 | \$ 2,507,499.88 | 52 | PCC Restoration | 100 |
| 2014 | RW 9-27 | 6105 | \$ 4,205,250.52 | 46 | PCC Restoration | 100 |
| 2014 | RW 9-27 | 6110 | \$ 6,999,999.67 | 57 | PCC Restoration | 100 |
| 2014 | TW A3 | 125 | \$ 394,835.34 | 20 | Reconstruction | 100 |
| 2014 | TW A | 105 | \$ 6,570,585.63 | 50 | PCC Restoration | 100 |
| 2014 | TW A6 | 135 | \$ 474,208.76 | 20 | Reconstruction | 100 |
| 2014 | TW B | 205 | \$ 833,257.40 | 38 | Reconstruction | 100 |
| 2014 | TW A1 | 110 | \$ 568,940.67 | 52 | PCC Restoration | 100 |
| 2014 | TW A1 | 112 | \$ 241,721.64 | 43 | Mill and Overlay | 100 |
| 2014 | TW A3 | 120 | \$ 158,483.82 | 41 | PCC Restoration | 100 |
| 2014 | TW A5 | 130 | \$ 330,460.18 | 58 | PCC Restoration | 100 |
| 2014 | TW B1 | 215 | \$ 637,452.57 | 57 | PCC Restoration | 100 |
| 2014 | TW B1 | 216 | \$ 454,292.08 | 58 | Mill and Overlay | 100 |
| 2014 | TW B2 | 220 | \$ 109,627.83 | 38 | Reconstruction | 100 |
| 2014 | TW B3 | 225 | \$ 73,085.20 | 59 | Mill and Overlay | 100 |
| 2014 | TW B4 | 230 | \$ 62,462.40 | 62 | Mill and Overlay | 100 |
| 2016 | TW A9 | 140 | \$ 339,201.65 | 64 | PCC Restoration | 100 |
| 2016 | TW B | 210 | \$ 1,256,344.46 | 65 | Mill and Overlay | 100 |
| 2017 | AP S | 4210 | \$ 574,127.59 | 65 | Mill and Overlay | 100 |
| 2017 | AP S | 4220 | \$ 315,200.91 | 65 | Mill and Overlay | 100 |
| 2023 | TW B1 | 145 | \$ 1,056,260.16 | 65 | Mill and Overlay | 100 |



| Year | Branch Name | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-------------|------------|------------------|----------------|------------------|---------------|
| 2023 | AP NE | 4140 | \$ 2,897,109.11 | 65 | Mill and Overlay | 100 |
| Total = | | | \$39,477,474.44 | | | |

* Costs are adjusted for inflation at 3%



CGC – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2014 | RW 9-27 | 6120 | \$ 97,500.00 | 64 | Mill and Overlay | 100 |
| 2014 | AP T-HANG | 4205 | \$ 793,939.96 | 61 | Mill and Overlay | 100 |
| 2014 | AP MAIN | 4120 | \$ 523,329.98 | 62 | Mill and Overlay | 100 |
| 2014 | AP MAIN | 4105 | \$ 1,171,429.94 | 54 | Mill and Overlay | 100 |
| 2014 | TW CONN | 210 | \$ 230,529.99 | 55 | Mill and Overlay | 100 |
| 2014 | TW CONN | 205 | \$ 335,659.98 | 59 | Mill and Overlay | 100 |
| 2014 | TW A | 130 | \$ 68,480.00 | 61 | Mill and Overlay | 100 |
| 2014 | TW A | 118 | \$ 67,095.02 | 40 | Reconstruction | 100 |
| 2014 | TW A | 115 | \$ 44,730.00 | 56 | Mill and Overlay | 100 |
| 2014 | TW A | 109 | \$ 138,829.99 | 60 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6115 | \$ 100,425.00 | 64 | Mill and Overlay | 100 |
| 2017 | RW 9-27 | 6110 | \$ 1,062,950.14 | 64 | Mill and Overlay | 100 |
| 2017 | RW 9-27 | 6105 | \$ 2,458,635.63 | 65 | Mill and Overlay | 100 |
| Total = | | | \$ 7,093,535.63 | | | |

* Costs are adjusted for inflation at 3%



CLW – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|------------|------------|------------------|----------------|------------------|---------------|
| 2015 | AP CENTER | 4405 | \$ 329,961.00 | 38 | Reconstruction | 100 |
| 2015 | AP CENTER | 4410 | \$ 257,620.00 | 53 | Mill and Overlay | 100 |
| 2015 | AP N | 4505 | \$ 290,940.00 | 53 | Mill and Overlay | 100 |
| 2015 | AP T-HAN 1 | 4305 | \$ 480,392.00 | 56 | Mill and Overlay | 100 |
| 2015 | AP T-HAN 1 | 4310 | \$ 250,993.00 | 35 | Reconstruction | 100 |
| 2015 | AP T-HAN 2 | 4105 | \$ 559,970.00 | 64 | Mill and Overlay | 100 |
| 2015 | TW A | 130 | \$ 409,470.00 | 51 | Mill and Overlay | 100 |
| 2015 | TW CONN 34 | 5105 | \$ 21,689.00 | 50 | Mill and Overlay | 100 |
| 2018 | AP T-HAN 3 | 4205 | \$ 405,498.00 | 65 | Mill and Overlay | 100 |
| Total = | | | \$ 3,006,533.00 | | | |

* Costs are adjusted for inflation at 3%



INF – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2014 | AP GA | 4005 | \$ 350,442.48 | 59 | Mill and Overlay | 100 |
| 2014 | TW GA AP | 205 | \$ 406,282.28 | 63 | Mill and Overlay | 100 |
| Total = | | | \$ 756,724.76 | | | |

* Costs are adjusted for inflation at 3%



PCM – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2014 | RW 10-28 | 6120 | \$ 524,999.98 | 61 | Mill and Overlay | 100 |
| 2014 | RW 10-28 | 6115 | \$ 2,287,957.39 | 61 | Mill and Overlay | 100 |
| 2014 | RW 10-28 | 6103 | \$ 151,059.99 | 51 | Mill and Overlay | 100 |
| 2014 | TW T-HANG | 725 | \$ 234,066.19 | 62 | Mill and Overlay | 100 |
| 2014 | TW T-HANG | 720 | \$ 75,452.82 | 47 | Mill and Overlay | 100 |
| 2014 | TW T-HANG | 710 | \$ 83,032.92 | 42 | Mill and Overlay | 100 |
| 2014 | TW A | 160 | \$ 53,828.10 | 55 | Mill and Overlay | 100 |
| 2014 | TW A | 150 | \$ 49,349.33 | 49 | Mill and Overlay | 100 |
| 2014 | TW A | 115 | \$ 340,410.18 | 58 | Mill and Overlay | 100 |
| 2014 | TW A | 110 | \$ 1,252,943.44 | 62 | Mill and Overlay | 100 |
| 2017 | AP | 4110 | \$ 496,499.28 | 64 | Mill and Overlay | 100 |
| 2019 | AP | 4130 | \$ 898,599.66 | 65 | Mill and Overlay | 100 |
| 2021 | AP | 4120 | \$ 571,083.54 | 65 | Mill and Overlay | 100 |
| Total = | | | \$ 7,019,282.82 | | | |

* Costs are adjusted for inflation at 3%



PIE- 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|------|------------|------------|------------------|----------------|------------------|---------------|
| 2015 | AP HOLD | 4205 | \$ 360,919.00 | 40 | Reconstruction | 100 |
| 2015 | AP MAIN | 4105 | \$ 7,132,212.00 | 54 | Mill and Overlay | 100 |
| 2015 | AP MAIN | 4123 | \$ 787,302.00 | 52 | Mill and Overlay | 100 |
| 2015 | AP MAIN | 4155 | \$ 1,456,992.00 | 62 | Mill and Overlay | 100 |
| 2015 | AP MAIN | 4175 | \$ 713,138.00 | 3 | Reconstruction | 100 |
| 2015 | AP MAIN | 4176 | \$ 252,195.00 | 3 | Reconstruction | 100 |
| 2015 | AP MAIN | 4180 | \$ 2,913,985.00 | 24 | Reconstruction | 100 |
| 2015 | AP MAIN | 4190 | \$ 428,950.00 | 28 | Reconstruction | 100 |
| 2015 | AP MAIN | 4195 | \$ 258,750.00 | 12 | Reconstruction | 100 |
| 2015 | AP MAIN | 4199 | \$ 1,418,022.00 | 51 | PCC Restoration | 100 |
| 2015 | AP RU RW22 | 4305 | \$ 332,545.00 | 36 | Reconstruction | 100 |
| 2015 | RW 18L-36R | 6155 | \$ 3,240,000.00 | 62 | Mill and Overlay | 100 |
| 2015 | RW 18L-36R | 6175 | \$ 5,220,000.00 | 64 | Mill and Overlay | 100 |
| 2015 | RW 18L-36R | 6185 | \$ 3,780,000.00 | 53 | Mill and Overlay | 100 |
| 2015 | RW 18L-36R | 6197 | \$ 1,672,200.00 | 52 | Mill and Overlay | 100 |
| 2015 | RW 4-22 | 6230 | \$ 463,450.00 | 23 | Reconstruction | 100 |
| 2015 | RW 9-27 | 6315 | \$ 4,730,340.00 | 41 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6320 | \$ 2,312,244.00 | 42 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6325 | \$ 641,408.00 | 48 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6335 | \$ 746,900.00 | 43 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6340 | \$ 402,500.00 | 31 | Reconstruction | 100 |
| 2015 | RW 9-27 | 6345 | \$ 1,035,000.00 | 39 | Reconstruction | 100 |
| 2015 | RW 9-27 | 6350 | \$ 446,400.00 | 46 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6355 | \$ 1,840,000.00 | 36 | Reconstruction | 100 |
| 2015 | RW 9-27 | 6360 | \$ 720,000.00 | 64 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6365 | \$ 1,047,510.00 | 45 | Mill and Overlay | 100 |
| 2015 | RW 9-27 | 6370 | \$ 463,500.00 | 58 | Mill and Overlay | 100 |
| 2015 | TW A | 114 | \$ 54,297.00 | 33 | Reconstruction | 100 |
| 2015 | TW A | 117 | \$ 57,112.00 | 49 | Mill and Overlay | 100 |
| 2015 | TW A | 119 | \$ 78,749.00 | 33 | Reconstruction | 100 |
| 2015 | TW A | 160 | \$ 3,515,273.00 | 39 | Reconstruction | 100 |
| 2015 | TW B | 205 | \$ 251,100.00 | 56 | Mill and Overlay | 100 |
| 2015 | TW B | 210 | \$ 114,357.00 | 64 | Mill and Overlay | 100 |



| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|------------|------------|------------------|----------------|------------------|---------------|
| 2015 | TW B | 220 | \$ 935,088.00 | 28 | Reconstruction | 100 |
| 2015 | TW C | 305 | \$ 982,233.00 | 36 | Reconstruction | 100 |
| 2015 | TW D | 405 | \$ 94,500.00 | 51 | Mill and Overlay | 100 |
| 2015 | TW D | 407 | \$ 464,695.00 | 51 | Mill and Overlay | 100 |
| 2015 | TW D | 410 | \$ 329,751.00 | 45 | Mill and Overlay | 100 |
| 2015 | TW F | 605 | \$ 294,354.00 | 37 | Reconstruction | 100 |
| 2015 | TW F | 610 | \$ 173,468.00 | 41 | Mill and Overlay | 100 |
| 2015 | TW F | 615 | \$ 450,000.00 | 55 | Mill and Overlay | 100 |
| 2015 | TW H | 810 | \$ 1,483,178.00 | 6 | Reconstruction | 100 |
| 2015 | TW J | 1005 | \$ 235,710.00 | 46 | Mill and Overlay | 100 |
| 2015 | TW K | 1120 | \$ 35,448.00 | 55 | Mill and Overlay | 100 |
| 2015 | TW K | 1125 | \$ 38,457.00 | 58 | Mill and Overlay | 100 |
| 2015 | TW K | 1130 | \$ 50,468.00 | 42 | Mill and Overlay | 100 |
| 2015 | TW L | 1245 | \$ 429,617.00 | 32 | Reconstruction | 100 |
| 2015 | TW M | 1325 | \$ 4,744,768.00 | 42 | Mill and Overlay | 100 |
| 2015 | TW M | 1330 | \$ 187,082.00 | 33 | Reconstruction | 100 |
| 2015 | TW T | 2050 | \$ 4,031,945.00 | 22 | Reconstruction | 100 |
| 2016 | TW A | 112 | \$ 66,423.00 | 65 | Mill and Overlay | 100 |
| 2017 | RW 4-22 | 6225 | \$ 769,577.00 | 64 | Mill and Overlay | 100 |
| 2019 | RW 18L-36R | 6115 | \$ 1,012,958.00 | 64 | Mill and Overlay | 100 |
| 2019 | RW 18L-36R | 6145 | \$ 607,775.00 | 63 | Mill and Overlay | 100 |
| 2019 | RW 18L-36R | 6165 | \$ 1,418,141.00 | 64 | Mill and Overlay | 100 |
| 2020 | RW 18L-36R | 6135 | \$ 417,339.00 | 65 | Mill and Overlay | 100 |
| 2020 | RW 18L-36R | 6170 | \$ 730,343.00 | 65 | Mill and Overlay | 100 |
| 2020 | RW 9-27 | 6330 | \$ 355,218.00 | 65 | Mill and Overlay | 100 |
| 2021 | RW 18L-36R | 6150 | \$ 322,394.00 | 65 | Mill and Overlay | 100 |
| 2021 | RW 18L-36R | 6160 | \$ 1,934,365.00 | 64 | Mill and Overlay | 100 |
| 2021 | TW K | 1105 | \$ 462,531.00 | 65 | Mill and Overlay | 100 |
| 2022 | RW 18L-36R | 6140 | \$ 221,377.00 | 64 | Mill and Overlay | 100 |
| 2023 | RW 18L-36R | 6120 | \$ 570,047.00 | 63 | Mill and Overlay | 100 |
| 2023 | RW 18L-36R | 6180 | \$ 3,306,270.00 | 64 | Mill and Overlay | 100 |
| Total = | | | \$ 76,042,870.00 | | | |

* Costs are adjusted for inflation at 3%

SPG – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|------|-----------|------------|------------------|----------------|------------------|---------------|
| 2015 | AP | 4110 | \$ 1,933,536.00 | 60 | Mill and Overlay | 100 |
| 2015 | AP | 4120 | \$ 1,105,734.00 | 54 | Mill and Overlay | 100 |
| 2015 | AP | 4135 | \$ 1,233,705.00 | 64 | Mill and Overlay | 100 |
| 2015 | AP | 4145 | \$ 212,785.00 | 58 | Mill and Overlay | 100 |
| 2015 | RW 18-36 | 6105 | \$ 4,296,001.00 | 60 | Mill and Overlay | 100 |
| 2015 | RW 18-36 | 6110 | \$ 2,148,001.00 | 58 | Mill and Overlay | 100 |
| 2015 | RW 7-25 | 6205 | \$ 281,250.00 | 61 | Mill and Overlay | 100 |
| 2015 | RW 7-25 | 6207 | \$ 459,000.00 | 37 | Reconstruction | 100 |
| 2015 | RW 7-25 | 6210 | \$ 2,551,741.00 | 59 | Mill and Overlay | 100 |
| 2015 | TW A | 105 | \$ 225,000.00 | 53 | Mill and Overlay | 100 |
| 2015 | TW A | 110 | \$ 315,000.00 | 58 | Mill and Overlay | 100 |
| 2015 | TW A | 115 | \$ 954,250.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW A1 | 610 | \$ 220,260.00 | 26 | Reconstruction | 100 |
| 2015 | TW A2 | 410 | \$ 75,592.00 | 59 | Mill and Overlay | 100 |
| 2015 | TW B | 210 | \$ 259,726.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW B | 215 | \$ 61,124.00 | 40 | Mill and Overlay | 100 |
| 2015 | TW B | 251 | \$ 65,730.00 | 36 | Reconstruction | 100 |
| 2015 | TW B | 252 | \$ 99,200.00 | 58 | Mill and Overlay | 100 |
| 2015 | TW B | 253 | \$ 68,110.00 | 25 | Reconstruction | 100 |
| 2015 | TW B | 254 | \$ 55,612.00 | 60 | Mill and Overlay | 100 |
| 2015 | TW C | 301 | \$ 77,721.00 | 20 | Reconstruction | 100 |
| 2015 | TW C | 305 | \$ 1,224,080.00 | 20 | Reconstruction | 100 |
| 2015 | TW C | 307 | \$ 524,805.00 | 57 | Mill and Overlay | 100 |
| 2015 | TW C | 310 | \$ 416,910.00 | 53 | Mill and Overlay | 100 |
| 2015 | TW D | 150 | \$ 110,219.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW D | 155 | \$ 109,554.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW N | 720 | \$ 200,052.00 | 57 | Mill and Overlay | 100 |
| 2016 | AP W | 4210 | \$ 1,152,896.00 | 64 | Mill and Overlay | 100 |
| 2016 | TW D1 | 615 | \$ 85,056.00 | 64 | Mill and Overlay | 100 |
| 2016 | TW N | 740 | \$ 512,730.00 | 65 | Mill and Overlay | 100 |
| 2017 | AP | 4105 | \$ 707,977.00 | 64 | Mill and Overlay | 100 |
| 2017 | TW B | 205 | \$ 1,393,402.00 | 65 | Mill and Overlay | 100 |
| 2017 | TW C | 308 | \$ 606,702.00 | 64 | Mill and Overlay | 100 |



| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2017 | TW N | 710 | \$ 534,123.00 | 65 | Mill and Overlay | 100 |
| 2018 | TW B | 250 | \$ 42,260.00 | 64 | Mill and Overlay | 100 |
| 2018 | TW B | 256 | \$ 40,457.00 | 64 | Mill and Overlay | 100 |
| 2018 | TW D | 160 | \$ 35,593.00 | 64 | Mill and Overlay | 100 |
| 2019 | TW D | 510 | \$ 572,660.00 | 64 | Mill and Overlay | 100 |
| 2020 | TW N | 730 | \$ 217,472.00 | 64 | Mill and Overlay | 100 |
| 2021 | AP | 4140 | \$ 380,693.00 | 64 | Mill and Overlay | 100 |
| 2021 | RW 7-25 | 6215 | \$ 539,554.00 | 65 | Mill and Overlay | 100 |
| Total = | | | \$26,106,273.00 | | | |

* Costs are adjusted for inflation at 3%

TPF – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2015 | AP | 4140 | \$ 224,502.00 | 62 | Mill and Overlay | 100 |
| 2015 | RW 4-22 | 6105 | \$ 4,657,501.00 | 57 | Mill and Overlay | 100 |
| 2015 | TW A | 105 | \$ 1,548,783.00 | 59 | Mill and Overlay | 100 |
| 2015 | TW B | 150 | \$ 70,095.00 | 56 | Mill and Overlay | 100 |
| 2015 | TW C | 310 | \$ 252,600.00 | 54 | Mill and Overlay | 100 |
| 2015 | TW D | 425 | \$ 96,591.00 | 44 | Mill and Overlay | 100 |
| 2015 | TW E | 510 | \$ 166,887.00 | 58 | Mill and Overlay | 100 |
| 2015 | TW T-HANG | 705 | \$ 1,080,361.00 | 52 | Mill and Overlay | 100 |
| 2017 | AP RU | 5105 | \$ 50,185.00 | 65 | Mill and Overlay | 100 |
| 2017 | TW F | 610 | \$ 153,199.00 | 65 | Mill and Overlay | 100 |
| 2020 | AP RU | 5110 | \$ 76,266.00 | 64 | Mill and Overlay | 100 |
| 2022 | TW C | 305 | \$ 132,181.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW A | 120 | \$ 115,012.00 | 65 | Mill and Overlay | 100 |
| Total = | | | \$ 8,624,163.00 | | | |

* Costs are adjusted for inflation at 3%

VDF – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2015 | AP RU | 5110 | \$ 50,070.00 | 64 | Mill and Overlay | 100 |
| 2015 | AP W | 4505 | \$ 424,716.00 | 64 | Mill and Overlay | 100 |
| 2015 | TW A | 160 | \$ 57,915.00 | 64 | Mill and Overlay | 100 |
| 2015 | TW B | 210 | \$ 305,353.00 | 31 | Reconstruction | 100 |
| 2015 | TW B | 250 | \$ 145,726.00 | 33 | Reconstruction | 100 |
| 2016 | TW A | 105 | \$ 1,783,394.00 | 64 | Mill and Overlay | 100 |
| 2016 | TW D | 170 | \$ 78,223.00 | 64 | Mill and Overlay | 100 |
| 2017 | TW A | 205 | \$ 36,495.00 | 65 | Mill and Overlay | 100 |
| 2018 | AP A - S | 4105 | \$ 1,276,326.00 | 64 | Mill and Overlay | 100 |
| 2018 | AP C | 4305 | \$ 6,951,470.00 | 64 | Mill and Overlay | 100 |
| 2018 | TW J | 705 | \$ 1,004,472.00 | 65 | Mill and Overlay | 100 |
| 2018 | TW J | 710 | \$ 521,006.00 | 65 | Mill and Overlay | 100 |
| 2019 | AP A - S | 4110 | \$ 1,931,046.00 | 64 | Mill and Overlay | 100 |
| 2019 | RW 18-36 | 6105 | \$ 4,104,929.00 | 65 | Mill and Overlay | 100 |
| 2019 | TW A | 140 | \$ 65,201.00 | 64 | Mill and Overlay | 100 |
| 2019 | TW D | 305 | \$ 530,294.00 | 64 | Mill and Overlay | 100 |
| 2019 | TW F | 610 | \$ 82,235.00 | 65 | Mill and Overlay | 100 |
| 2019 | TW F | 615 | \$ 76,850.00 | 64 | Mill and Overlay | 100 |
| 2020 | AP B - N | 4205 | \$ 2,290,015.00 | 64 | Mill and Overlay | 100 |
| 2020 | AP C | 4405 | \$ 1,233,349.00 | 64 | Mill and Overlay | 100 |
| 2020 | AP RU | 5105 | \$ 434,619.00 | 65 | Mill and Overlay | 100 |
| 2020 | AP W | 4510 | \$ 644,853.00 | 65 | Mill and Overlay | 100 |
| 2020 | RW 5-23 | 6205 | \$ 8,694,558.00 | 65 | Mill and Overlay | 100 |
| 2020 | TW A | 120 | \$ 48,203.00 | 64 | Mill and Overlay | 100 |
| 2020 | TW J | 715 | \$ 209,024.00 | 64 | Mill and Overlay | 100 |
| 2021 | TW A | 180 | \$ 73,631.00 | 64 | Mill and Overlay | 100 |
| 2021 | TW C | 405 | \$ 389,861.00 | 64 | Mill and Overlay | 100 |
| 2022 | AP A - S | 4115 | \$ 82,454.00 | 63 | Mill and Overlay | 100 |
| 2024 | TW E1 | 510 | \$ 187,438.00 | 64 | Mill and Overlay | 100 |
| 2024 | TW E2 | 515 | \$ 186,145.00 | 64 | Mill and Overlay | 100 |
| 2024 | TW F | 605 | \$ 1,922,664.00 | 64 | Mill and Overlay | 100 |
| Total = | | | \$35,822,535.00 | | | |



* Costs are adjusted for inflation at 3%


ZPH – 10-YEAR MAJOR REHABILITATION NEEDS

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2014 | AP E | 5405 | \$ 511,460.52 | 12 | Reconstruction | 100 |
| 2014 | AP T-HANG | 5305 | \$ 1,320,331.92 | 46 | Mill and Overlay | 100 |
| 2014 | AP TW D | 5205 | \$ 263,596.19 | 51 | Mill and Overlay | 100 |
| 2014 | AP NE | 5105 | \$ 416,250.10 | 40 | Reconstruction | 100 |
| 2014 | AP NW | 4110 | \$ 50,953.60 | 64 | Mill and Overlay | 100 |
| 2014 | AP NW | 4105 | \$ 21,600.00 | 59 | PCC Restoration | 100 |
| 2014 | TW F | 630 | \$ 243,480.09 | 65 | Mill and Overlay | 100 |
| 2014 | TW C-1 | 505 | \$ 60,000.00 | 62 | Mill and Overlay | 100 |
| 2014 | TW D | 405 | \$ 250,634.79 | 54 | Mill and Overlay | 100 |
| 2014 | TW A-2 | 310 | \$ 153,299.99 | 54 | Mill and Overlay | 100 |
| 2014 | TW B | 245 | \$ 34,501.81 | 27 | Reconstruction | 100 |
| 2014 | TW B | 240 | \$ 313,775.19 | 54 | Mill and Overlay | 100 |
| 2014 | TW B | 230 | \$ 225,000.05 | 12 | Reconstruction | 100 |
| 2014 | TW B | 220 | \$ 1,999,650.47 | 4 | Reconstruction | 100 |
| 2014 | TW B | 212 | \$ 178,714.59 | 59 | Mill and Overlay | 100 |
| 2014 | TW B | 210 | \$ 268,470.06 | 32 | Reconstruction | 100 |
| 2014 | TW B | 205 | \$ 741,960.18 | 25 | Reconstruction | 100 |
| 2014 | TW A-1 | 115 | \$ 175,279.99 | 64 | Mill and Overlay | 100 |
| 2014 | TW A | 110 | \$ 1,889,299.91 | 62 | Mill and Overlay | 100 |
| 2014 | TW A | 107 | \$ 100,000.00 | 64 | Mill and Overlay | 100 |
| 2014 | TW A | 105 | \$ 722,689.97 | 60 | Mill and Overlay | 100 |
| 2016 | RW 18-36 | 6205 | \$ 5,022,694.06 | 64 | Mill and Overlay | 100 |
| Total = | | | \$14,963,643.48 | | | |

* Costs are adjusted for inflation at 3%

APPENDIX E

- ◎ DISTRICT AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBITS



LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID

PROGRAM YEAR

| | |
|------|------|
| 2014 | 2019 |
| 2015 | 2020 |
| 2016 | 2021 |
| 2017 | 2022 |
| 2018 | 2023 |

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

DESIGNED: KHA DRAWN: KHA CHECKED: KHA DATE: 2013

K:\WP_Airport\107022\ADVISORY\AIRPORT - HERNANDO COUNTY AIRPORT\2013-09-10\107022.dwg PLOTTED: May 15, 2013 - 3:10 PM BY: Baha, M





- LEGEND**
- RW 13-31 TYPICAL RUNWAY BRANCH ID
 - TW A TYPICAL TAXIWAY BRANCH ID
 - AP S TYPICAL APRON BRANCH ID

- PROGRAM YEAR**
- | | | | |
|--|------|--|------|
| | 2014 | | 2019 |
| | 2015 | | 2020 |
| | 2016 | | 2021 |
| | 2017 | | 2022 |
| | 2018 | | 2023 |



"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

DESIGNED: KHA DRAWN: KHA CHECKED: KHA DATE: 2013





LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

- | | | | |
|--|------|--|------|
| | 2015 | | 2020 |
| | 2016 | | 2021 |
| | 2017 | | 2022 |
| | 2018 | | 2023 |
| | 2019 | | 2024 |

"PROGRAM YEAR"
 "BRANCH"/"SECTION"
 "REHAB ACTIVITY"
 "EST. COST"



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2015 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
CLEARWATER AIRPARK
PINELLAS COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



- LEGEND**
- RW 13-31 — TYPICAL RUNWAY BRANCH ID
 - TWA — TYPICAL TAXIWAY BRANCH ID
 - AP S — TYPICAL APRON BRANCH ID

- PROGRAM YEAR**
- | | | | |
|--|------|--|------|
| | 2014 | | 2019 |
| | 2015 | | 2020 |
| | 2016 | | 2021 |
| | 2017 | | 2022 |
| | 2018 | | 2023 |

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | | | | | |
|-----------|-----|--------|-----|----------|-----|-------|------|
| DESIGNED: | KHA | DRAWN: | KHA | CHECKED: | KHA | DATE: | 2013 |
|-----------|-----|--------|-----|----------|-----|-------|------|



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
INVERNESS AIRPORT
CITRUS COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



- LEGEND**
- RW 13-31 — TYPICAL RUNWAY BRANCH ID
 - TW A — TYPICAL TAXIWAY BRANCH ID
 - AP S — TYPICAL APRON BRANCH ID

- PROGRAM YEAR**
- | | |
|------|------|
| 2014 | 2019 |
| 2015 | 2020 |
| 2016 | 2021 |
| 2017 | 2022 |
| 2018 | 2023 |

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2013 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
PLANT CITY AIRPORT
HILLSBOROUGH COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



| | | | | | | | | | | | | |
|--|--|--|---|---|---|---|---|---|---|---|---|---|
| SECTION: 114 FY 2015 TW A: 114 RECONSTRUCTION \$0.05M | SECTION: 117 FY 2015 TW A: 117 MILL AND OVERLAY \$0.06M | SECTION: 119 FY 2015 TW A: 119 RECONSTRUCTION \$0.08M | SECTION: 4190 FY 2015 AP MAIN: 4190 RECONSTRUCTION \$0.43M | SECTION: 4195 FY 2015 AP MAIN: 4195 RECONSTRUCTION \$0.26M | SECTION: 4199 FY 2015 AP MAIN: 4199 PCC RESTORATION \$1.42M | SECTION: 4205 FY 2015 AP HOLD: 4205 RECONSTRUCTION \$0.36M | SECTION: 4305 FY 2015 AP RU RW 22: 4305 RECONSTRUCTION \$0.33M | SECTION: 6155 FY 2015 RW 18L-36R: 6155 MILL AND OVERLAY \$3.24M | SECTION: 6175 FY 2015 RW 18L-36R: 6175 MILL AND OVERLAY \$5.22M | SECTION: 6185 FY 2015 RW 18L-36R: 6185 MILL AND OVERLAY \$3.78M | | |
| SECTION: 160 FY 2015 TW A: 160 RECONSTRUCTION \$3.52M | SECTION: 205 FY 2015 TW B: 205 MILL AND OVERLAY \$0.25M | SECTION: 210 FY 2015 TW B: 210 MILL AND OVERLAY \$0.11M | SECTION: 6197 FY 2015 RW 18L-36R: 6197 MILL AND OVERLAY \$1.67M | SECTION: 6230 FY 2015 RW 4-22: 6230 RECONSTRUCTION \$0.46M | SECTION: 6315 FY 2015 RW 9-27: 6315 MILL AND OVERLAY \$4.73M | SECTION: 6320 FY 2015 RW 9-27: 6320 MILL AND OVERLAY \$2.31M | SECTION: 6325 FY 2015 RW 9-27: 6325 MILL AND OVERLAY \$0.64M | SECTION: 6335 FY 2015 RW 9-27: 6335 MILL AND OVERLAY \$0.75M | SECTION: 6340 FY 2015 RW 9-27: 6340 RECONSTRUCTION \$0.40M | SECTION: 6345 FY 2015 RW 9-27: 6345 RECONSTRUCTION \$1.04M | | |
| SECTION: 220 FY 2015 TW B: 220 RECONSTRUCTION \$0.94M | SECTION: 305 FY 2015 TW C: 305 RECONSTRUCTION \$0.98M | SECTION: 405 FY 2015 TW D: 405 MILL AND OVERLAY \$0.09M | SECTION: 407 FY 2015 TW D: 407 MILL AND OVERLAY \$0.46M | SECTION: 6350 FY 2015 RW 9-27: 6350 MILL AND OVERLAY \$0.45M | SECTION: 6355 FY 2015 RW 9-27: 6355 RECONSTRUCTION \$1.84M | SECTION: 6360 FY 2015 RW 9-27: 6360 MILL AND OVERLAY \$0.72M | SECTION: 6365 FY 2015 RW 9-27: 6365 MILL AND OVERLAY \$1.05M | SECTION: 6370 FY 2015 RW 9-27: 6370 MILL AND OVERLAY \$0.46M | SECTION: 112 FY 2016 RW 4-22: 112 MILL AND OVERLAY \$0.07M | SECTION: 6225 FY 2017 RW 4-22: 6225 MILL AND OVERLAY \$0.77M | SECTION: 6115 FY 2019 RW 18L-36R: 6115 MILL AND OVERLAY \$1.01M | SECTION: 6145 FY 2019 RW 18L-36R: 6145 MILL AND OVERLAY \$0.61M |
| SECTION: 410 FY 2015 TW D: 410 MILL AND OVERLAY \$0.33M | SECTION: 605 FY 2015 TW F: 605 RECONSTRUCTION \$0.29M | SECTION: 610 FY 2015 TW F: 610 MILL AND OVERLAY \$0.17M | SECTION: 615 FY 2015 TW F: 615 MILL AND OVERLAY \$0.45M | SECTION: 6165 FY 2019 RW 18L-36R: 6165 MILL AND OVERLAY \$1.42M | SECTION: 6135 FY 2020 RW 18L-36R: 6135 MILL AND OVERLAY \$0.42M | SECTION: 6170 FY 2020 RW 18L-36R: 6170 MILL AND OVERLAY \$0.73M | SECTION: 6330 FY 2020 RW 9-27: 6330 MILL AND OVERLAY \$0.36M | SECTION: 1105 FY 2021 TW K: 1105 MILL AND OVERLAY \$0.46M | SECTION: 6150 FY 2021 RW 18L-36R: 6150 MILL AND OVERLAY \$0.32M | SECTION: 6160 FY 2021 RW 18L-36R: 6160 MILL AND OVERLAY \$1.93M | | |
| SECTION: 810 FY 2015 TW H: 810 RECONSTRUCTION \$1.48M | SECTION: 1005 FY 2015 TW J: 1005 MILL AND OVERLAY \$0.24M | SECTION: 1120 FY 2015 TW K: 1120 MILL AND OVERLAY \$0.04M | SECTION: 1125 FY 2015 TW K: 1125 MILL AND OVERLAY \$0.04M | SECTION: 1130 FY 2015 TW K: 1130 MILL AND OVERLAY \$0.05M | SECTION: 1105 FY 2021 TW K: 1105 MILL AND OVERLAY \$0.46M | SECTION: 6150 FY 2021 RW 18L-36R: 6150 MILL AND OVERLAY \$0.32M | SECTION: 6160 FY 2021 RW 18L-36R: 6160 MILL AND OVERLAY \$1.93M | SECTION: 1245 FY 2015 TW L: 1245 RECONSTRUCTION \$0.43M | SECTION: 1325 FY 2015 TW M: 1325 MILL AND OVERLAY \$4.74M | SECTION: 1330 FY 2015 TW M: 1330 RECONSTRUCTION \$0.19M | SECTION: 2050 FY 2015 TW T: 2050 RECONSTRUCTION \$4.03M | SECTION: 4105 FY 2015 AP MAIN: 4105 MILL AND OVERLAY \$7.13M |
| SECTION: 4123 FY 2015 AP MAIN: 4123 MILL AND OVERLAY \$0.79M | SECTION: 4155 FY 2015 AP MAIN: 4155 MILL AND OVERLAY \$1.46M | SECTION: 4175 FY 2015 AP MAIN: 4175 RECONSTRUCTION \$0.71M | SECTION: 4176 FY 2015 AP MAIN: 4176 RECONSTRUCTION \$0.25M | SECTION: 4180 FY 2015 AP MAIN: 4180 RECONSTRUCTION \$2.91M | SECTION: 6140 FY 2022 RW 18L-36R: 6140 MILL AND OVERLAY \$0.22M | SECTION: 6120 FY 2023 RW 18L-36R: 6120 MILL AND OVERLAY \$0.57M | SECTION: 6180 FY 2023 RW 18L-36R: 6180 MILL AND OVERLAY \$3.31M | | | | | |

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

| | |
|------|------|
| 2015 | 2020 |
| 2016 | 2021 |
| 2017 | 2022 |
| 2018 | 2023 |
| 2019 | 2024 |



"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |
| | | |



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
ST. PETE-CLEARWATER INTERNATIONAL AIRPORT
 PINELLAS COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



| | | | |
|--|--|---|---|
| SECTION: 105 FY 2015 TW A: 105 MILL AND OVERLAY \$0.23M | SECTION: 110 FY 2015 TW A: 110 MILL AND OVERLAY \$0.32M | SECTION: 115 FY 2015 TW A: 115 MILL AND OVERLAY \$0.95M | SECTION: 253 FY 2015 TW B: 253 RECONSTRUCTION \$0.07M |
| SECTION: 410 FY 2015 TW A2: 410 MILL AND OVERLAY \$0.08M | SECTION: 615 FY 2016 TW D1: 615 MILL AND OVERLAY \$0.09M | SECTION: 308 FY 2017 TW C: 308 MILL AND OVERLAY \$0.61M | SECTION: 510 FY 2019 TW D: 510 MILL AND OVERLAY \$0.57M |

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

| | | | |
|--|------|--|------|
| | 2015 | | 2020 |
| | 2016 | | 2021 |
| | 2017 | | 2022 |
| | 2018 | | 2023 |
| | 2019 | | 2024 |

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |
| | | |
| | | |

DESIGNED: KHA DRAWN: KHA CHECKED: KHA DATE: 2015
© 2015 Florida Department of Transportation - Aviation and Spaceport Office



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
ALBERT WHITTED AIRPORT
PINELLAS COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

| | |
|------|------|
| 2015 | 2020 |
| 2016 | 2021 |
| 2017 | 2022 |
| 2018 | 2023 |
| 2019 | 2024 |

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2015 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
PETER O. KNIGHT AIRPORT
HILLSBOROUGH COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

| | | | |
|--|------|--|------|
| | 2015 | | 2020 |
| | 2016 | | 2021 |
| | 2017 | | 2022 |
| | 2018 | | 2023 |
| | 2019 | | 2024 |

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| | | | | |
|---|---|---|--|---|
| SECTION: 160 FY 2015 TW A: 160 MILL AND OVERLAY \$0.06M | SECTION: 170 FY 2016 TW D: 170 MILL AND OVERLAY \$0.08M | SECTION: 205 FY 2017 TW A: 205 MILL AND OVERLAY \$0.04M | SECTION: 140 FY 2019 TW A: 140 MILL AND OVERLAY \$0.07M | SECTION: 305 FY 2019 TW D: 305 MILL AND OVERLAY \$0.53M |
| SECTION: 615 FY 2019 TW F: 615 MILL AND OVERLAY \$0.08M | SECTION: 4405 FY 2020 AP C: 4405 MILL AND OVERLAY \$1.23M | SECTION: 180 FY 2021 TW A: 180 MILL AND OVERLAY \$0.07M | SECTION: 510 FY 2024 TW E1: 510 MILL AND OVERLAY \$0.19M | |

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2015 |
|---------------|------------|--------------|------------|





LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

- 2014
- 2015
- 2016
- 2017
- 2018
- 2019
- 2020
- 2021
- 2022
- 2023

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|--------|------|-----------|
| | | |
| | | |
| | | |

| | | | |
|---------------|------------|--------------|------------|
| DESIGNED: KHA | DRAWN: KHA | CHECKED: KHA | DATE: 2013 |
|---------------|------------|--------------|------------|



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
ZEPHYRHILLS MUNICIPAL AIRPORT
PASCO COUNTY, FLORIDA
 FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



FLORIDA DEPARTMENT OF TRANSPORTATION
AVIATION AND SPACEPORT OFFICE

