

**STATE OF FLORIDA
DEPARTMENT OF TRANSPORTATION
AVIATION OFFICE**

**Statewide Airfield Pavement
Management Program**

**Immokalee Regional Airport– IMM
(General Aviation)
Immokalee, Florida
(District 1)**



May 2011

TABLE OF CONTENTS

SECTION	PAGE NO.
Executive Summary	iii
1. Introduction.....	1
2. Network Definition and Pavement Inventory	10
3. Pavement Condition.....	15
4. Pavement Condition Prediction	22
5. Maintenance Policies and costs	23
6. Pavement Rehabilitation Needs Analysis	29
7. Maintenance and Rehabilitation Plan	33
8. Visual Aids.....	35
9. Recommendations.....	36

LIST OF FIGURES

Figure 1-1: Pavement Life Cycle.....	4
Figure 1-2: PCI Rating Scale	6
Figure 2-1: Pavement Area by Surface Type.....	12
Figure 3-1: Network PCI Distribution by Rating Category.....	18
Figure 3-1a: Condition Rating Summary.....	18
Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use.....	19
Figure 4-1: Predicted PCI by Pavement Use	22
Figure 6-1: Budget Scenario Analysis	32

LIST OF TABLES:

Table I: Condition Summary by Branch.....	iv
Table II: Condition Summary by Pavement Use	iv
Table III: Condition Summary by Pavement Rank.....	iv
Table IV: Immediate Major M&R Needs	vi
Table V: 10-Year M&R Costs under Unlimited Funding Scenario	vii
Table 1-1: Sampling Rate for FDOT Condition Surveys	5
Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity	11
Table 2-2: Pavement Area by Pavement Use	11
Table 2-3: Branch and Section Inventory	13
Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces.....	15
Table 3-2: Pavement Distresses for Portland Cement Concrete Surfaces	16
Table 3-3: Condition by Pavement Use	19
Table 5-1: Routine Maintenance Activities for Airfield Pavements	24
Table 5-2: Critical PCI for General Aviation Airports	25
Table 5-3: FDOT Minimum Service Level PCI for General Aviation Airports.....	25
Table 5-4: M&R Activities for General Aviation Airports	26
Table 5-5: Maintenance Unit Costs for FDOT	27
Table 5-6: M&R Activities and Unit Costs by Condition for General Aviation Airports.....	28
Table 6-1: Summary of Immediate Major M&R Needs.....	30

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE NO.</u>
-----------------------	------------------------

Table 6-2: Summary of Year 1 Maintenance Activities	31
Table 7-1: M&R Costs under Unlimited Funding Scenario	33

APPENDICES

Appendix A	Network Definition Map
	System Inventory Map
	Pavement Inventory Table
	Work History Report
Appendix B	2011 Condition Map
	Pavement Condition Index Table
Appendix C	Branch Condition Report
	Section Condition Report
Appendix D	Pavement Condition Prediction Table
	Predicted PCI by Pavement Use Graph
Appendix E	Year 1 Maintenance Activities Table
Appendix F	Major M&R Plan by Year under Unlimited Funding Scenario Table
Appendix G	10-Year M&R Map
Appendix H	Photographs
Appendix I	PCI Re-inspection Report

EXECUTIVE SUMMARY

In 2010, the Florida Department of Transportation (FDOT) Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing Statewide Airfield Pavement Management Program (SAPMP) to be completed over fiscal years 2011 and 2012.

The tasks required to achieve this objective at Immokalee Regional Airport included:

- Obtain recent construction history from the Airport to update the Pavement Inventory CADD drawings from the previous SAPMP update,
- Perform a visual Pavement Condition Index (PCI) survey of the airfield pavements at the Airport,
- Update the MicroPAVER database to analyze the PCI field data and determine the current condition of the airfield pavements,
- Predict the future deterioration of the pavements,
- Develop a 10-year M&R plan to address the pavement needs at Immokalee Regional Airport, and
- Provide the estimated costs associated with the suggested immediate and future M&R activities

During March 2011, the PCI survey was performed at Immokalee Regional Airport. The results of the survey indicate that, based on a numerical scale of 0 to 100, the overall area-weighted average PCI of the airfield pavements in 2011 is 36, representing a Very Poor overall network condition.

Table I below summarizes the overall condition summary by network branch.

Table I: Condition Summary by Branch

Branch Name	Area Weighted PCI	Condition Rating	FDOT Minimum Service Level	MicroPAVER Minimum PCI	Action Required
Apron to Hangars	93	Good	60	65	
Apron Run-Up at RW 36	87	Good	60	65	
South Apron and Fueling Ramp	88	Good	60	65	
Crop Apron	39	Very Poor	60	65	X
Runway 18-36	28	Very Poor	75	65	X
Runway 4-22 (Former)	34	Very Poor	75	65	X
Runway 9-27	27	Very Poor	75	65	X
Taxiway Alpha	25	Serious	65	65	X
Taxiway Bravo	30	Very Poor	65	65	X
Taxiway Bravo 1	30	Very Poor	65	65	X
Taxiway Charlie	91	Good	65	65	
Taxiway to Crop Apron	67	Fair	65	65	

Tables II and III below illustrate the area-weighted PCI computed individually for each pavement use and rank, respectively.

Table II: Condition Summary by Pavement Use

Use	Average Area-Weighted PCI	Condition Rating
Runway	28	Very Poor
Taxiway	37	Very Poor
Apron	86	Good
All (Weighted)	36	Very Poor

Table III: Condition Summary by Pavement Rank

Rank*	Average Area-Weighted PCI	Condition Rating
Primary	36	Very Poor
Secondary	36	Very Poor
Tertiary	73	Satisfactory
All (Weighted)	36	Very Poor

*The pavement rank for the airport pavement network is listed on Table 2-3.

The immediate M&R needs, or needs that have been programmed to be completed in the first year of the 10-year M&R plan based on an unlimited budget at Immokalee Regional Airport, include: Runway 9-27, Runway 18-36, Taxiway Alpha, and Taxiway Bravo. Runways 9-27 and 18-36 exhibited low to medium severity distresses of block cracking, weathering, and raveling that attributed to the age of the pavement. Both runways, based on the determined PCI will benefit from a full depth pavement reconstruction. Similarly, Taxiway Alpha and Taxiway Bravo exhibited the same range of distresses that would benefit from pavement section reconstruction. The immediate needs are summarized in Table IV below.

Table IV: Immediate Major M&R Needs

Project Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	Crop Apron	4105	AC	10,000	\$70,230.01	39	Reconstruction	100
2011	Runway 18-36	6105	PCC	30,000	\$408,600.13	27	Reconstruction	100
2011	Runway 18-36	6110	PCC	15,000	\$204,300.07	30	Reconstruction	100
2011	Runway 18-36	6115	AC	422,500	\$5,754,451.87	28	Reconstruction	100
2011	Runway 18-36	6120	AC	211,250	\$2,877,225.93	29	Reconstruction	100
2011	Runway 18-36	6125	PCC	30,000	\$408,600.13	17	Reconstruction	100
2011	Runway 18-36	6130	PCC	15,000	\$204,300.07	23	Reconstruction	100
2011	Runway 4-22	6305	PCC	15,000	\$138,330.04	36	Reconstruction	100
2011	Runway 4-22	6310	PCC	35,000	\$348,425.09	35	Reconstruction	100
2011	Runway 4-22	6325	PCC	35,000	\$476,700.15	30	Reconstruction	100
2011	Runway 4-22	6330	PCC	15,000	\$171,315.06	33	Reconstruction	100
2011	Runway 9-27	6205	PCC	15,000	\$204,300.07	28	Reconstruction	100
2011	Runway 9-27	6210	PCC	7,500	\$102,150.03	25	Reconstruction	100
2011	Runway 9-27	6215	AC	420,500	\$5,727,211.86	28	Reconstruction	100
2011	Runway 9-27	6220	AC	210,250	\$2,863,605.93	28	Reconstruction	100
2011	Runway 9-27	6225	PCC	30,000	\$408,600.13	26	Reconstruction	100
2011	Runway 9-27	6230	PCC	15,000	\$204,300.07	4	Reconstruction	100
2011	Taxiway Alpha	205	AC	277,550	\$3,780,232.23	25	Reconstruction	100
2011	Taxiway Alpha 1	210	AC	23,450	\$319,389.10	26	Reconstruction	100
2011	Taxiway Alpha 2	220	AC	23,450	\$319,389.10	22	Reconstruction	100
2011	Taxiway Bravo	105	AC	117,050	\$1,594,221.52	26	Reconstruction	100
2011	Taxiway Bravo	110	AC	132,650	\$1,417,763.62	34	Reconstruction	100
2011	Taxiway Bravo	115	AC	10,000	\$114,210.04	33	Reconstruction	100
2011	Taxiway Bravo 1	405	AC	33,000	\$352,704.10	34	Reconstruction	100
2011	Taxiway Bravo 1	410	AC	69,493	\$946,494.97	28	Reconstruction	100
Total					\$29,417,051.32	28		100

* Costs are adjusted for inflation.

A forecast of Major M&R needs for a 10-year period, starting from 2011, was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval. The results of this analysis are provided in Table V below.

Table V: 10-Year M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$20,957.69	\$29,417,051.31	\$29,438,009.00
2012	\$29,447.90	\$0.00	\$29,447.90
2013	\$26,966.46	\$86,921.18	\$113,887.64
2014	\$35,170.20	\$0.00	\$35,170.20
2015	\$42,660.34	\$0.00	\$42,660.34
2016	\$43,064.93	\$171,691.73	\$214,756.66
2017	\$56,853.78	\$0.00	\$56,853.78
2018	\$89,850.10	\$0.00	\$89,850.10
2019	\$153,829.30	\$0.00	\$153,829.30
2020	\$195,910.68	\$0.00	\$195,910.68
Total	\$694,711.38	\$29,675,664.22	\$30,370,375.60

Note: Costs are adjusted for inflation.

The implementation of the 10-Year Major M&R Plan is expected to provide an improvement in the overall condition of the airfield pavement, where the area-weighted PCI would increase from 36 in 2011 to 84 in 2020. Appendix F lists the Major M&R for the 10-Year program. Appendix G graphically depicts the program activity.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all Immokalee Regional Airport pavements in 2020 may remain near 84. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for Immokalee Regional Airport is conducted at some point in the 10-year plan.

1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. There are millions of square yards of pavement for the runways, taxiways, aprons and other areas of these airports that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time.

In order to support the planning, scheduling, and design of the M&R activities based on pavement evaluation and pavement management performance trends, the Florida Department of Transportation (FDOT) Aviation Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992.

In 2010, the FDOT Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

This report discusses the work performed, a summary of the findings, results, and recommendations for M&R planning associated with the update to the SAPMP. It also describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented during the performance of the SAPMP.

1.1 Purpose

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the SAPMP and the roles and responsibilities of the program's participants;
- Provide background information on pavement management principles, objectives, and benefits to this airport;
- Outline the procedures used to collect, evaluate and report pavement inspection results at this airport;
- Present the findings from the pavement inspection;
- Analyze and discuss the needs for Maintenance and Rehabilitation (M&R) activities and associated costs for this airport.

1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The 1992 SAPMP provided valuable information for establishing and performing pavement M&R.

In 1992/1993, and 1998/1999, the FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement maintenance. This system, AIRPAV, was implemented, and initial condition surveys were

performed in 1992 and 1993. The SAPMP was updated with additional surveys in 1998 and 1999.

In 2004, the FDOT Aviation Office undertook a project to update the pavement management system software utilized for the SAPMP. This project involved a review of the AIRPAV software and other available pavement management system software. As a result of this review, MicroPAVER was selected as the software for the update project. Data from the 1998/1999 condition surveys were converted to the MicroPAVER system, and the inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999. The pavements were inspected between 2006 and 2008, and an updated M&R program was developed based on the new condition of the airfield pavements. As part of the update, procedures for the inspection and collection of pavement data were developed, and a website (www.floridaairportpavement.com) was created for the input of data under secure procedures.

Currently, airports using the AIP Grant Program are required by the Federal Aviation Administration (FAA) to develop a pavement maintenance program (FAA/AC 150/5380-6B “Guidelines and Procedures for Maintenance of Airport Pavements”) using trained personnel to perform a detailed inspection of airfield pavements. The inspections are required to be performed at least once a year or every 3 years if pavement inspection is characterized in the form of a Pavement Condition Index (PCI) survey (such as ASTM D 5340 “Standard Test Method for Airport Pavement Condition Index Surveys”, (2004 edition)). The 2004 edition was utilized in lieu of the 2010 edition to maintain database integrity and benefit of pavement performance curves from the previous inspections.

In 2010, the FDOT Aviation Office selected a team consisting of the Consultant and their Subconsultants to provided services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

1.3 Organization

1.3.1 Aviation Office Program Manager Role

The Aviation Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) monitoring the work of the Consultant. The AO-PM has review and approval authority for each program task and also manages the day-to-day details of the SAPMP and the updates.

1.3.2 Consultant Role

The Consultant (Kimley-Horn and Associates, Inc.) and their Subconsultants (MACTEC Engineering and Consulting and All About Pavements, Inc.) provide technical and administrative assistance to the AO-PM during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the SAPMP based upon procedures outlined in FAA Advisory Circular 150/5380-6B “Guidelines and Procedures for Maintenance of Airport Pavements” and ASTM D 5340 “Standard Test Method for Airport Pavement Condition Index Surveys” (2004).

1.3.3 Airport Role

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP update, indicate any construction activity that has been performed since the previous inspections.

1.4 Pavement Types and Pavement Management

1.4.1 Pavement basics

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of an asphalt concrete (AC) surface, and
- Rigid pavement composed of a Portland Cement Concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying natural subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland Cement Concrete supports most of the load, and the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the construction of the concrete surface.


A small percentage of the airport pavements in Florida are composed of asphalt concrete surface over Portland Cement Concrete (APC). This pavement type is known as “composite” pavement.

Due to the different nature of the pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

1.4.2 Pavement Management System Concept

The SAPMP utilized a Pavement Management System (PMS) to develop the M&R recommendations discussed in this report. A PMS is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1 below, taken from FAA/AC 5380-7A “Airport Pavement Management Program”, illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement’s life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in “good” condition depends on how well it is maintained. As the illustration demonstrates, the cost of maintaining the pavement above a critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Figure 1-1: Pavement Life Cycle



Source: FAA/AC 150/5380-7A "Airport Pavement Management Program"
 *Modified to reflect current construction costs.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi-year M&R plan can be determined.

1.4.3 Pavement Inspection Methodology for the SAPMP

Pavement condition assessment is one of the primary decision variables in any airport PMS. Pavement condition assessments generally include visual surveys in accordance with ASTM D 5340, "Standard Test Method for Airport Pavement Condition Index Surveys" and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the Statewide Aviation Pavement Management Program update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine the appropriate rehabilitation methods during the design process.

In preparation of the PCI surveys, the airfield pavements are divided into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Further discussion of how the airport pavements are divided and subdivided into units by construction and use can be found in Section 2 “Network Definition and Pavement Inventory” of this report.

Sample unit sizes are approximately 5000 ± 2000 square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements. Prior to conducting the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of Branches, Sections, use patterns, construction types and history. The sampling rate used for the FDOT Statewide Airfield Pavement Management Program is provided in Table 1-1 below.

Table 1-1: Sampling Rate for FDOT Condition Surveys

AC Pavements			PCC Pavements		
N	n		N	n	
	Runway	Others		Runway	Others
1-4	1	1	1-3	1	1
5-10	2	1	4-6	2	1
11-15	3	2	7-10	3	2
16-30	5	3	11-15	4	2
31-40	7	4	16-20	5	3
41-50	8	5	21-30	7	3
≥51	20% but ≤20	10% but ≤10	31-40	8	4
			41-50	10	5
			≥51	20% but ≤20	10% but ≤10

Where N = total number of sample units in Section
 n = number of sample units to inspect

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the Section. In the case when nonrepresentative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each Section. PCI values range from 0 to 100. As Figure 1-2 below indicates, MicroPAVER provides a rating scale that relates PCI to pavement condition. A PCI between 0 and 10 is considered ‘Failed’ pavement, and a PCI between 86 and 100 is considered ‘Good’ pavement, with five other conditions for PCI values between 11 and 85.

Figure 1-2: PCI Rating Scale

	PCI	Condition Rating
	86 – 100	Good
	71 – 85	Satisfactory
	56 – 70	Fair
	41 – 55	Poor
	26 – 40	Very Poor
	11 – 25	Serious
	0 – 10	Failed

1.5 Definitions

Aviation Office - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office Program Manager (AO-PM) has review and approval authority for each program task of the SAPMP.

Base Course - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

Branch - A Branch designates pavements that have common usage and functionality, such as an entire runway, taxiway, or apron.

Branch ID - A short form identification for the pavement Branch. In this report, Branch includes the common designation for the item e.g. RW 18-36.

Category - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA – for general aviation or community airports;
- RL – for regional relievers or small hubs;
- PR – for primary (certified under Part 139 requirements).

Critical PCI - The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

Distress Type - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland Cement Concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

Florida DOT (FDOT) - Florida Department of Transportation was represented in this project by the Office of Aviation.

Global M&R - Global M&R is defined as activities applied to entire pavement Sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

Localized M&R (Maintenance and Repair) - Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

Major M&R (e.g. Rehabilitation) - Activities performed over the entire area of a pavement Section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

MicroPAVER - A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that, if properly implemented, maintained, and operated, it meets the pavement management program requirements described by the FAA in Advisory Circular 150/5380-7A.

Minimum Condition Level - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

Network Definition - A Network Definition is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport is in Appendix A along with a table of inventory data.

Pavement Condition Index (PCI) - The Pavement Condition Index is a number which represents the condition of a pavement segment at a specific point in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340, published by ASTM International.

Pavement Evaluation - A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

Pavement Management System (PMS) - A Pavement Management System is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

Pavement Surface Type - The surface of pavement is identified as one of four types:

- AC – for asphalt surface pavements;
- PCC – for Portland Cement Concrete pavements;
- AAC – for asphalt surface pavements that have had an asphalt overlay at some point in their construction history;
- APC – for composite pavements, which consist of asphalt over Portland Cement Concrete pavement.
- PAC – for composite pavements, which consist of Portland Cement Concrete over asphalt pavement.

Rank - Pavement rank in MicroPAVER determines the priority to be assigned to a pavement Section when developing an M&R plan. Pavement Sections are ranked as follows according to their use:

- P – for Primary pavements, such as primary runways, primary taxiways, and primary aprons;
- S – or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons;
- T – for Tertiary pavements such as “T” hangars and slightly used aprons.

Reconstruction - Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

Rehabilitation - Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

Sample Unit - Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are $5,000 \pm 2,000$ square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements.

Section - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition, and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

Section ID - A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series Sections are taxiways, 4000 and 5000 series Sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series Sections are runways.

Statewide Airfield Pavement Management Program (SAPMP) – The Statewide Airfield Pavement Management Program is a program implemented in 1992 by the Florida Department of Transportation to plan, schedule, and design the maintenance and rehabilitation activities

necessary for the airfield pavement on Florida's public airports to allow the airports to operate efficiently, economically, and without excessive down time.

System Inventory - A System Inventory is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline and identifies airfield construction activities since the last inspection. The System Inventory for the airport is included in Appendix A.

Use - In MicroPAVER, Use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

2. NETWORK DEFINITION AND PAVEMENT INVENTORY

Immokalee Regional Airport (IMM), consists of two runways; RW 18-36, which is 150-ft wide by 5,000-ft long and RW 9-27, which is 150-ft wide by 5,000-ft long. Inactive RW 4-22 is currently fenced off from the rest of the airfield and being used as a drag strip. Taxiways Alpha and Bravo are each 50-ft wide and are used to direct traffic to and from the active runways. Currently the airport has multiple T-Hangar facilities located on the south east side of the airport and tie-down spaces located throughout the apron. The runways are mostly constructed out of Asphalt Concrete pavement with exception to 300-ft sections of Portland Cement Concrete located at each end of all of the runways. All of the pavement throughout the taxiways, hangars and apron is constructed out of Asphalt Concrete pavement.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric dimensions may vary slightly from the geometry used in the condition and M&R analysis based on field measurements.

Established as Immokalee Army Airfield and activated in 1942, Immokalee Regional Airport was assigned to the US Army Air Forces East Coast Training Center. IMM was an auxiliary to Hendricks Army Airfield and was an AAF Specialized Pilot Training School. With the drawdown to the pilot training program in 1944, the airfield was transferred to the Third Air Force. Immokalee Regional Airport was turned over to the Army Corps of Engineers in 1945 and eventually discharged to the War Assets Administration. From there Immokalee Regional Airport became a civil which is currently owned and operated by Collier County.

This airport is designated as a General Aviation airport and is located in District 1 of the Florida Department of Transportation.

2.1 Network Definition

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units.

2.1.1 Branch Section Identification

The airport pavement network is subdivided into separate Branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then further divided into Sections with similar pavement construction and performance that may share other common attributes.

Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage. A pavement rank, consisting of primary, secondary, and tertiary levels, is assigned to each Section based on their level and type of use. The pavement rankings that were designated for each Section in the previous SAPMP update were again used for this update.

As discussed in Section 1.4.3 “Pavement Inspection Methodology for the SAPMP”, the sections are sub-divided into sample units, which are the smallest subdivision in a pavement network, only for the purpose of conducting the pavement condition survey.

2.1.2 System Inventory and Network Definition Update

The System Inventory and Network Definition drawings are used to identify changes in the network since the most recent update from the 2006/2008 inspections and also to plan the field inspection activities for the 2011 survey. Prior to the field inspection process, the System Inventory drawing was updated from the previous inspection with notes indicating recent construction projects on the various Sections of pavement throughout the airfield. This System Inventory drawing is used to update the Network Definition drawing.

The Network Definition drawing shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The previous airport configuration and history was compared with the current airport configuration, and the existing network branch, section and sample unit designations were revised to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important historical record.

The updated System Inventory and Network Definition drawings for Immokalee Regional Airport are provided in Appendix A. Table 2-1 below lists the recent construction projects at the airport.

Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity

Construction Year	Location	Work Type / Pavement Section
2006	Apron	Expansion
2006	Taxiway Charlie	Pavement Rehabilitation

2.2 Pavement Inventory

The detailed pavement inventory was updated to reflect the network definition update and field inspection results.


The total airfield pavement area in 2011 at Immokalee Regional Airport is 2,593,597 square feet. The breakdown of pavement area for each pavement use is provided in Table 2-2.

Table 2-2: Pavement Area by Pavement Use

Use	Area (ft²)	% of Total Area
Runway	1,522,000	59%
Taxiway	824,018	32%
Apron	247,579	10%
All (Weighted)	2,593,597	100%

Figure 2-1 presents the breakdown of the pavement area at Immokalee Regional Airport by surface type.

Figure 2-1: Pavement Area by Surface Type



Details of pavement Branch and Section information including Branch name (which indicates pavement use), Branch ID, Section ID, section area, rank, surface type, last construction date, number of samples inspected, and number of samples in each Section are given in Table 2-3 below. A more detailed Pavement Inventory Table may be found in Appendix A of this report.

Table 2-3: Branch and Section Inventory

Branch Name	Branch ID	Section ID	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
Apron to Hangars	AP HANG	4405	22,500	P	AC	1/1/1998	1	4
Apron Run-up RW 36	AP RU RW36	4305	8,000	P	AC	1/1/1998	1	1
Apron Run-up RW 36	AP RU RW36	4310	6,309	P	AC	1/1/2001	0	1
Apron Run-up RW 36	AP RU RW36	4315	18,752	N	AC	1/1/2002	1	1
South Apron and Fueling Ramps	AP S	4205	28,000	P	AC	1/1/1997	1	5
South Apron and Fueling Ramps	AP S	4210	63,618	P	AC	1/1/1998	2	5
South Apron and Fueling Ramps	AP S	4215	54,400	P	AC	7/31/2007	0	11
South Apron and Fueling Ramps	AP S	4220	36,000	P	AC	7/31/2007	0	7
Crop Apron	CROP AP	4105	10,000	P	AC	1/1/1987	1	2
Runway 18-36	RW 18-36	6105	30,000	P	PCC	1/1/1942	2	6
Runway 18-36	RW 18-36	6110	15,000	P	PCC	1/1/1942	1	3
Runway 18-36	RW 18-36	6115	422,500	P	AC	1/1/1942	17	106
Runway 18-36	RW 18-36	6120	211,250	P	AC	1/1/1942	8	53
Runway 18-36	RW 18-36	6125	30,000	P	PCC	1/1/1942	2	6
Runway 18-36	RW 18-36	6130	15,000	P	PCC	1/1/1942	1	3
Runway 4-22	RW 4-22	6305	15,000	S	PCC	1/1/1942	1	1
Runway 4-22	RW 4-22	6310	35,000	S	PCC	1/1/1942	2	3
Runway 4-22	RW 4-22	6325	35,000	S	PCC	1/1/1942	2	3
Runway 4-22	RW 4-22	6330	15,000	S	PCC	1/1/1942	1	1
Runway 9-27	RW 9-27	6205	15,000	S	PCC	1/1/1942	1	3
Runway 9-27	RW 9-27	6210	7,500	S	PCC	1/1/1942	1	1
Runway 9-27	RW 9-27	6215	420,500	S	AC	1/1/1942	17	105
Runway 9-27	RW 9-27	6220	210,250	S	AC	1/1/1942	8	53
Runway 9-27	RW 9-27	6225	30,000	S	PCC	1/1/1942	2	6
Runway 9-27	RW 9-27	6230	15,000	S	PCC	1/1/1942	1	3
Taxiway Alpha	TW A	205	277,550	P	AC	1/1/1942	6	69
Taxiway Alpha 1	TW A	210	23,450	P	AC	1/1/1942	1	6
Taxiway Alpha 2	TW A	220	23,450	P	AC	1/1/1942	1	6
Taxiway Bravo	TW B	105	117,050	P	AC	1/1/1942	4	29
Taxiway Bravo	TW B	110	132,650	P	AC	1/1/1942	4	33
Taxiway Bravo	TW B	115	10,000	P	AC	1/1/1942	1	3
Taxiway Bravo 1	TW B1	405	33,000	P	AC	1/1/1942	2	4
Taxiway Bravo 1	TW B1	410	69,493	P	AC	1/1/1942	1	1
Taxiway Charlie	TW C	310	56,000	S	AC	1/1/1998	2	14

Table 2-3: Branch and Section Inventory (Continued)

Branch Name	Branch ID	Section ID	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
Taxiway Charlie	TW C	315	49,875	S	AC	1/1/2007	3	18
Taxiway to Crop Apron	TW TO AP	305	31,500	T	AC	1/1/1987	2	8

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Section 4310 was not inspected due to obstruction.

3. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340-04 “Standard Practice for Airport Pavement Condition Index Surveys.” These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

3.1 Inspection Methodology

A PCI survey is performed by measuring the amount and severity of pavement distresses, which are caused by traffic load, climate, and other factors, observed within a sample unit. This data is imported into MicroPAVER, which calculates PCI values for the pavement sections. Tables 3-1 and 3-2 below list the pavement distress types and related causes for asphalt concrete (AC) and Portland Cement Concrete (PCC), respectively.

Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces

Code	Distress	Mechanism
41	Alligator Cracking	Load
42	Bleeding	Construction Quality / Mix Design
43	Block Cracking	Climate / Age
44	Corrugation	Load / Construction Quality
45	Depression	Subgrade Quality
46	Jet Blast	Aircraft
47	Joint Reflection - Cracking	Climate / Prior Pavement
48	Longitudinal/Transverse Cracking	Climate / Age
49	Oil Spillage	Aircraft / Vehicle
50	Patching	Utility / Pavement Repair
51	Polished Aggregate	Load
52	Weathering/Raveling	Climate / Load
53	Rutting	Load
54	Shoving	Pavement Growth
55	Slippage Cracking	Load / Pavement Bond
56	Swelling	Climate / Subgrade Quality
<i>Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual</i>		

Table 3-2: Pavement Distresses for Portland Cement Concrete Surfaces

Code	Distress	Mechanism
61	Blow-up	Climate
62	Corner Break	Load
63	Linear Cracking	Load
64	Durability Cracking	Climate
65	Joint Seal Damage	Climate
66	Small Patch	Pavement Repair
67	Large Patch/Utility Cut	Utility / Pavement Repair
68	Popout	Climate
69	Pumping	Load
70	Scaling/Crazing	Construction Quality
71	Faulting	Subgrade Quality
72	Shattered Slab	Load
73	Shrinkage Cracking	Construction Quality / Load
74	Joint Spalling	Load
75	Corner Spalling	Load
<i>Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual</i>		

Prior to conducting the inspections, Global Positioning System (GPS) coordinates were recorded using CADD at the centroid of each sample unit. The centroid is usually the geometric center of the area, but in cases where sample units are irregular in shape, this is the center of mass. These data are presented in a table on the updated Network Definition Map in Appendix A of this report.

Pavement condition inspections at Immokalee Regional Airport were performed in March 2011. Data were recorded in the field in accordance with FAA Advisory Circular 150/5380-6B “Guidelines and Procedures for Maintenance of Airport Pavements” and ASTM D 5340 “Standard Test Method for Airport Pavement Condition Index Surveys” (2004).

After the completion of data collection, the data was imported into MicroPAVER, and PCI values were calculated for the pavement sections.

3.2 Pavement Condition Index Results

According to the 2011 survey, the overall area-weighted PCI at Immokalee Regional Airport is 36, representing a Very Poor overall network condition.

Overall the airport exhibited pavement distresses associated with climate and age distresses. Asphalt Concrete pavement distresses include; weathering, raveling, longitudinal and transverse cracking, and block cracking distresses of which are common of pavements of similar age. The Portland Cement Concrete pavement also exhibited distresses associated with climate and age such as; corner breaks, LTD cracking, joint seal damage, scaling/map cracking, shrinkage cracks, joint and corner spalling.

The Asphalt Concrete pavement on RW 9-27 exhibited low and medium severity block cracking along with medium severity weathering and raveling. Portland Cement Concrete pavement distresses were very similar throughout the airport and consisted of; corner breaks, LTD cracking, joint seal damage, scaling/map cracking, shrinkage cracks, joint and corner spalling. All of these distresses were typically of low to medium severity.

RW 18-36 exhibited low and medium severity block cracking along with medium severity weathering and raveling. Low and medium severity longitudinal and transverse cracking was also observed throughout the runway pavement section.

Taxiways Alpha and Bravo exhibited very similar distresses to the runways, with low and medium severity longitudinal and transverse cracking in addition to medium severity weathering and raveling. Block cracking with low and medium severity was also a very prevalent distress throughout the two main taxiways. Taxiway Charlie was recently reconstructed in 2006 and appeared to be in a good overall condition. Small amounts of low severity longitudinal cracking were observed along the pavement joints which is a common distress due to the pavement being the weakest at this location.

A large portion of the apron pavement was recently reconstructed in 2006 and was not inspected due to its new condition. The recently constructed pavement section was assumed to have a PCI of 100. The remaining older pavement sections of the apron exhibited low severity longitudinal and transverse cracking with low severity weathering and raveling.

Appendix B contains a table and a Condition Map which depicts the PCI results by Section, and Appendix C contains a table of PCI results by Branch. Appendix I includes detailed distress data generated by MicroPAVER for each inspected sample unit.

Figure 3-1 provides the PCI distribution by rating category for Immokalee Regional Airport.

Figure 3-1: Network PCI Distribution by Rating Category




Figure 3-1a: Condition Rating Summary

Condition Rating	Total Area (ft ²)	Percent
Good	253,084	10%
Satisfactory	90,370	3%
Fair	31,500	1%
Poor	0	0%
Very Poor	1,857,643	72%
Serious	346,000	13%
Failed	15,000	1%


Approximately 13% of the network is in Good and Satisfactory condition while 14% of the network is in Serious and Failed condition. Table 3-3 illustrates the area-weighted PCI computed individually for each pavement use.

Table 3-3: Condition by Pavement Use


Use	Area-Weighted PCI	Condition Rating
Runway	28	Very Poor
Taxiway	37	Very Poor
Apron	86	Good
All (Weighted)	36	Very Poor

Figure 3-2 presents the breakdown of PCI by range for each pavement use.


Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use



(b) Taxiway




(c) Apron



4. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 4-1 illustrates the predicted performance of pavements at Immokalee Regional Airport based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum service level for General Aviation (GA) airports.

Figure 4-1: Predicted PCI by Pavement Use



Appendix D presents the tabular summary of the predicted Section PCI for each year from 2011 to 2020.

5. MAINTENANCE POLICIES AND COSTS

5.1 Policies

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature and are recommended to help achieve the performance goal.

Table 5-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules. These repairs are used only in the first year of an analysis.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called “Critical PCI.” The critical PCI levels for different pavement and branch types established in the previous SAPMP update were used in this update for the development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 5-2 gives the critical PCI levels for General Aviation Airports.

The maintenance rehabilitation policy and activity costs have been updated based on the study of readily available construction cost data at the time of this study. The costs depicted in this report are intended for planning purposes.

Table 5-1: Routine Maintenance Activities for Airfield Pavements

Surface	Distress	Severity*	Work Type	Code	Work Unit
AC	Alligator Crack	M, H	Patching - AC Deep	PA-AD	SqFt
	Bleeding	N/A	No Localized M&R	NONE	N/A
	Block Crack	M, H	Crack Sealing – AC	CS-AC	SqFt
	Corrugation	L, M, H	Patching - AC Deep	PA-AD	SqFt
	Depression	M, H	Patching - AC Deep	PA-AD	SqFt
	Jet Blast	N/A	Patching - AC Deep	PA-AD	SqFt
	Joint Ref. Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	L & T Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	Oil Spillage	N/A	Patching - AC Shallow	PA-AS	SqFt
	Patching	M, H	Patching - AC Deep	PA-AD	SqFt
	Polished Agg.	N/A	No Localized M&R	NONE	N/A
	Raveling and Weathering	L	Surface Sealing - Rejuvenating	SS-RE	SqFt
		M	Surface Seal - Coal Tar	SS-CT	SqFt
		H	Microsurfacing	MI-AC	SqFt
	Rutting	M, H	Patching - AC Deep	PA-AD	SqFt
	Shoving	M, H	Grinding (Localized)	GR-LL	SqFt
	Slippage Crack	N/A	Patching - AC Shallow	PA-AS	SqFt
	Swelling	M, H	Patching - AC Deep	PA-AD	SqFt
PCC	Blow-Up	L, M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Corner Break	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Linear Crack	M, H	Crack Sealing – PCC	CS-PC	Ft
	Durability Crack	H	Slab Replacement – PCC	SL-PC	SqFt
		M	Patching - PCC Full Depth	PA-PF	SqFt
	Jt. Seal Damage	M, H	Joint Seal (Localized)	JS-LC	Ft
	Small Patch	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Large Patch	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Popouts	N/A	No Localized M&R	NONE	N/A
	Pumping	N/A	No Localized M&R	NONE	N/A
	Scaling	H	Slab Replacement – PCC	SL-PC	SqFt
	Faulting	M, H	Grinding (Localized)	GR-PP	Ft
	Shattered Slab	M, H	Slab Replacement – PCC	SL-PC	SqFt
	Shrinkage Crack	N/A	No Localized M&R	NONE	N/A
	Joint Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Corner Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt

*L = Low, M = Medium, H = High

Table 5-2: Critical PCI for General Aviation Airports

Use	Critical PCI
Runway	65
Taxiway	65
Apron	65

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 5-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of General Aviation Airports.

Table 5-3: FDOT Minimum Service Level PCI for General Aviation Airports

Minimum PCI		
Runway	Taxiway	Apron
75	65	60

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 5-2 the PCI trigger range when the likely activity would be a mill and resurface was 40 to 79 and reconstruction at a PCI of 39 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 5-4 summarizes the M&R activities for General Aviation Airports based on PCI value.

Table 5-4: M&R Activities for General Aviation Airports

	Activity	PCI Range
Maintenance	Crack Sealing and Full-Depth Patching	80 and 90
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	40 to 79
	Reconstruction	39 and less

5.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were updated from the previous SAPMP study based on current construction cost trends in order to determine meaningful costs for the program. Table 5-5 presents the unit costs summary.

5.3 M&R Activities

FDOT recognizes that although Mill and Overlay work is recommended for asphalt pavements within a PCI range from 40 to 79, it is conceivable that airports may not have adequate funding to perform this type of rehabilitation. Microsurfacing treatment is a maintenance/rehabilitation measure that can be used in lieu of asphalt pavement mill and overlay; however it should be understood that this measure is intended for short term pavement life extension. While the cost of microsurfacing is significantly lower than that of pavement mill and overlay, it is not intended to be a full rehabilitative measure for long term benefit.

Table 5-5: Maintenance Unit Costs for FDOT

Code	Name	Cost	Unit
GR-LL	Grinding (Localized for AC)	\$2.10	SqFt
PA-AL	Patching – AC Leveling	\$2.30	SqFt
PA-AS	Patching – AC Shallow	\$2.90	SqFt
PA-PF	Patching – PCC Full Depth	\$38.11	SqFt
PA-PP	Patching – PCC Partial Depth	\$19.06	SqFt
SL-PC	Slab Replacement – PCC	\$39.11	SqFt
CS-PC	Crack Sealing – PCC	\$4.24	Ft
UN-PC	Undersealing – PCC	\$3.40	Ft
CS-AC	Crack Sealing – AC	\$2.25	Ft
GR-PP	Grinding (Localized for PCC)	\$22.51	Ft
JS-LC	Joint Seal (Localized)	\$2.00	Ft
SH-LE	Shoulder Leveling	\$2.81	Ft
JS-SI	Joint Seal – Silicon	\$2.81	Ft
PA-AD	Patching – AC Deep	\$4.90	SqFt
OL-AT	Overlay – AC Thin	\$2.80	SqFt
SS-CT	Surface Seal – Coal Tar	\$0.40	SqFt
SS-FS	Surface Seal – Fog Seal	\$0.40	SqFt
SS-RE	Surface Seal – Rejuvenating	\$0.40	SqFt
ST-SB	Surface Treatment – Single Bitum.	\$0.30	SqFt
ST-SS	Surface Treatment – Slurry Seal	\$0.55	SqFt
ST-ST	Surface Treatment – Sand Tar	\$0.28	SqFt
MI-AC	Microsurfacing - AC	\$0.65	SqFt

The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection was performed recently and only in the first year of the M&R analysis. In subsequent years, MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCIs. That is, for low PCI, it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly.

Using available unit cost data, the Major M&R Cost by Condition table was set up as shown in Table 5-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

**Table 5-6: M&R Activities and Unit Costs by Condition for
General Aviation Airports**

	Activity	PCI Trigger	Cost/SqFt
Maintenance	Crack Sealing and Full-Depth Patching	90	\$0.06
		80	\$0.24
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	70	\$3.00
		60	\$3.42
		50	\$6.29
		40	\$6.29
	Reconstruction	30	\$13.62
		20	\$13.62

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

6. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years, starting from 2011. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Table 6-1 presents the M&R list of immediate needs for Major M&R, i.e. Year 1 of the forecast. The importance of this listing is that it points out the major activities triggered by the current condition of the pavements.

Table 6-1: Summary of Immediate Major M&R Needs

Project Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	Crop Apron	4105	AC	10,000	\$70,230.01	39	Reconstruction	100
2011	Runway 18-36	6105	PCC	30,000	\$408,600.13	27	Reconstruction	100
2011	Runway 18-36	6110	PCC	15,000	\$204,300.07	30	Reconstruction	100
2011	Runway 18-36	6115	AC	422,500	\$5,754,451.87	28	Reconstruction	100
2011	Runway 18-36	6120	AC	211,250	\$2,877,225.93	29	Reconstruction	100
2011	Runway 18-36	6125	PCC	30,000	\$408,600.13	17	Reconstruction	100
2011	Runway 18-36	6130	PCC	15,000	\$204,300.07	23	Reconstruction	100
2011	Runway 4-22	6305	PCC	15,000	\$138,330.04	36	Reconstruction	100
2011	Runway 4-22	6310	PCC	35,000	\$348,425.09	35	Reconstruction	100
2011	Runway 4-22	6325	PCC	35,000	\$476,700.15	30	Reconstruction	100
2011	Runway 4-22	6330	PCC	15,000	\$171,315.06	33	Reconstruction	100
2011	Runway 9-27	6205	PCC	15,000	\$204,300.07	28	Reconstruction	100
2011	Runway 9-27	6210	PCC	7,500	\$102,150.03	25	Reconstruction	100
2011	Runway 9-27	6215	AC	420,500	\$5,727,211.86	28	Reconstruction	100
2011	Runway 9-27	6220	AC	210,250	\$2,863,605.93	28	Reconstruction	100
2011	Runway 9-27	6225	PCC	30,000	\$408,600.13	26	Reconstruction	100
2011	Runway 9-27	6230	PCC	15,000	\$204,300.07	4	Reconstruction	100
2011	Taxiway Alpha	205	AC	277,550	\$3,780,232.23	25	Reconstruction	100
2011	Taxiway Alpha 1	210	AC	23,450	\$319,389.10	26	Reconstruction	100
2011	Taxiway Alpha 2	220	AC	23,450	\$319,389.10	22	Reconstruction	100
2011	Taxiway Bravo	105	AC	117,050	\$1,594,221.52	26	Reconstruction	100
2011	Taxiway Bravo	110	AC	132,650	\$1,417,763.62	34	Reconstruction	100
2011	Taxiway Bravo	115	AC	10,000	\$114,210.04	33	Reconstruction	100
2011	Taxiway Bravo 1	405	AC	33,000	\$352,704.10	34	Reconstruction	100
2011	Taxiway Bravo 1	410	AC	69,493	\$946,494.97	28	Reconstruction	100
Total					\$29,417,051.32	28		100

* Costs are adjusted for inflation.


In addition to the immediate Major M&R needs, maintenance activities for pavement areas above critical PCI have been recommended by MicroPAVER for Year 1 and are shown in Table 6-2 below. The costs provided in Table 5-5 were used to calculate the costs associated with this work, which is intended to treat specific distress types. A more detailed table is provided in Appendix E.

Table 6-2: Summary of Year 1 Maintenance Activities

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Apron to Hangars	AP HANG	4405	WEATH/RAVEL	L	Surface Seal - Rejuvenating	300.00	SqFt	\$0.40	\$120.00
Apron Run-up RW 36	AP RU RW36	4305	OIL SPILLAGE	N	Patching - AC Shallow	48.10	SqFt	\$2.90	\$139.37
Apron Run-up RW 36	AP RU RW36	4305	WEATH/RAVEL	L	Surface Seal - Rejuvenating	484.80	SqFt	\$0.40	\$193.94
Apron Run-up RW 36	AP RU RW36	4315	WEATH/RAVEL	L	Surface Seal - Rejuvenating	2,812.80	SqFt	\$0.40	\$1,125.12
Apron Run-up RW 36	AP RU RW36	4315	OIL SPILLAGE	N	Patching - AC Shallow	38.30	SqFt	\$2.90	\$110.94
South Apron and Fueling Ramps	AP S	4205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	2,800.00	SqFt	\$0.40	\$1,120.00
South Apron and Fueling Ramps	AP S	4210	L & T CR	M	Crack Sealing - AC	559.00	Ft	\$2.25	\$1,257.71
South Apron and Fueling Ramps	AP S	4210	WEATH/RAVEL	L	Surface Seal - Rejuvenating	19,045.00	SqFt	\$0.40	\$7,618.07
Taxiway Charlie	TW C	310	WEATH/RAVEL	L	Surface Seal - Rejuvenating	569.90	SqFt	\$0.40	\$227.96
Taxiway Charlie	TW C	315	WEATH/RAVEL	L	Surface Seal - Rejuvenating	47.50	SqFt	\$0.40	\$19.00
Taxiway to Crop Apron	TW TO AP	305	WEATH/RAVEL	L	Surface Seal - Rejuvenating	22,049.80	SqFt	\$0.40	\$8,820.00
Taxiway to Crop Apron	TW TO AP	305	L & T CR	M	Crack Sealing - AC	91.40	Ft	\$2.25	\$205.59
Total =									\$20,957.70

The 10 year forecast results are shown in Figure 6-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.

Figure 6-1: Budget Scenario Analysis



The following network level observations can be made from the figure above:

- The PCI will deteriorate from 36 in 2011 to 21 in ten years if no M&R activities are performed.
- The PCI will remain at or above 84 through the 10-year analysis period under the unlimited budget scenario. A 2020 PCI of 84 with this scenario is 63 PCI points higher than a “No M&R” scenario. The total cost for Major M&R over this 10-year period is about \$29.7 million.

7. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels, the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCIs less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 7-1 provides the summary results under the critical PCI unlimited funding scenario.

Table 7-1: M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$20,957.69	\$29,417,051.31	\$29,438,009.00
2012	\$29,447.90	\$0.00	\$29,447.90
2013	\$26,966.46	\$86,921.18	\$113,887.64
2014	\$35,170.20	\$0.00	\$35,170.20
2015	\$42,660.34	\$0.00	\$42,660.34
2016	\$43,064.93	\$171,691.73	\$214,756.66
2017	\$56,853.78	\$0.00	\$56,853.78
2018	\$89,850.10	\$0.00	\$89,850.10
2019	\$153,829.30	\$0.00	\$153,829.30
2020	\$195,910.68	\$0.00	\$195,910.68
Total	\$694,711.38	\$29,675,664.22	\$30,370,375.60

Note: Costs are adjusted for inflation.

Approximately 99% of the total Major M&R cost is required in the first year (2011). According to the 2011 inspections, the following pavement sections were in immediate need of Major M&R Activity:

- **Crop Apron** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Runway 18-36** – Reconstruction of PCC pavement per the FAA P-501 Specification and Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Runway 4-22** – Reconstruction of PCC pavement per the FAA P-501 Specification.
- **Runway 9-27** – Reconstruction of PCC pavement per the FAA P-501 Specification and Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Alpha** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.

- **Taxiway Alpha 1** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Alpha 2** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Bravo** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Bravo 1** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.

The unlimited budget scenario provides the basis for estimating the total repair cost.

Appendix F provides details of M&R plan by year under the unlimited funding scenario, and the map of the 10-year M&R plan is provided in Appendix G. It is important to understand that the SAPMP is a network level tool and the M&R costs provided in this report are only for planning purposes.

8. VISUAL AIDS

8.1 System Inventory and Network Definition Drawings

The System Inventory and Network Definition CADD drawings, which show the airport pavement outline with Branch and Section boundaries and identify changes in the network pavement since the last inspection and the sampling plan, respectively, are included in Appendix A of this report.

8.2 Condition Map

A Condition Map that has been prepared based on data linked to the airport's shape file is included in Appendix B. The Condition Map graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

8.3 10-Year M&R Map

A 10-Year M&R Map that shows the summary of the M&R plan is attached in Appendix G.

8.4 Photographs

Selected digital photographs taken during the pavement inspection are provided in Appendix H to provide visual support to special pavement conditions or distress observed during the inspection of the airport.

9. RECOMMENDATIONS

Pavement condition inspections were performed at Immokalee Regional Airport, and a 10-year M&R plan was developed based on the unlimited funding scenario.

The following recommendations were made based on the 2011 condition inspection and M&R analysis results:

- **Crop Apron** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Runway 18-36** – Reconstruction of PCC pavement per the FAA P-501 Specification and Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Runway 4-22** – Reconstruction of PCC pavement per the FAA P-501 Specification.
- **Runway 9-27** – Reconstruction of PCC pavement per the FAA P-501 Specification and Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Alpha** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Alpha 1** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Alpha 2** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Bravo** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Bravo 1** – Asphalt Pavement reconstruction activity per the FAA P-401 Specification.

Further evaluation of these features is necessary in order to develop repair plans and timing for future budgets since these needs cannot be addressed with typical annual expenditures.

APPENDIX A

NETWORK DEFINITION MAP


SYSTEM INVENTORY MAP

PAVEMENT INVENTORY TABLE

WORK HISTORY REPORT

GPS COORDINATES - IMMOKALEE REGIONAL AIRPORT				
LOCATION	SECTION	SAMPLE	LATITUDE	LONGITUDE
RW 4-22	6330	195	26.43720341	-81.39620496
RW 4-22	6325	395	26.4368444	-81.39626248
RW 4-22	6325	398	26.43734313	-81.39585521
RW 4-22	6310	301	26.42641908	-81.40477496
RW 4-22	6310	303	26.42675159	-81.40450349
RW 4-22	6305	100	26.42674322	-81.4047452
RW 9-27	6230	186	26.43766676	-81.39063222
RW 9-27	6225	386	26.4374843	-81.39096926
RW 9-27	6225	388	26.43749845	-81.39051114
RW 9-27	6220	106	26.43726542	-81.40360624
RW 9-27	6220	126	26.43736	-81.4005521
RW 9-27	6220	142	26.43743562	-81.39810879
RW 9-27	6220	168	26.437579	-81.39347258
RW 9-27	6220	510	26.43694065	-81.40298228
RW 9-27	6220	534	26.43705413	-81.39931732
RW 9-27	6220	560	26.43719754	-81.39468113
RW 9-27	6220	576	26.43727306	-81.39223782
RW 9-27	6215	304	26.43707701	-81.40413415
RW 9-27	6215	306	26.43708647	-81.40382873
RW 9-27	6215	311	26.43711013	-81.4030652
RW 9-27	6215	316	26.43713378	-81.40230167
RW 9-27	6215	321	26.43715742	-81.40153813
RW 9-27	6215	326	26.43718106	-81.4007746
RW 9-27	6215	331	26.4372047	-81.40001107
RW 9-27	6215	336	26.43722833	-81.39924753
RW 9-27	6215	342	26.43725669	-81.39833129
RW 9-27	6215	346	26.43727559	-81.39772046
RW 9-27	6215	351	26.43729921	-81.39695693
RW 9-27	6215	360	26.4373623	-81.39491675
RW 9-27	6215	365	26.43738591	-81.39415321
RW 9-27	6215	371	26.43741423	-81.39323697
RW 9-27	6215	377	26.43744255	-81.39232072
RW 9-27	6215	380	26.4374567	-81.3918626
RW 9-27	6215	383	26.43747086	-81.39140448
RW 9-27	6210	100	26.43722993	-81.40475154
RW 9-27	6205	301	26.43706163	-81.40463044
RW 18-36	6130	100	26.43683176	-81.40538609
RW 18-36	6125	390	26.43652835	-81.40518338
RW 18-36	6125	392	26.43694078	-81.40519915
RW 18-36	6120	108	26.4251463	-81.40493929
RW 18-36	6120	118	26.42679682	-81.40500477
RW 18-36	6120	150	26.43123649	-81.40517214
RW 18-36	6120	182	26.43563572	-81.40534035
RW 18-36	6120	504	26.42460823	-81.40453654
RW 18-36	6120	534	26.42904871	-81.4047063
RW 18-36	6120	542	26.43014851	-81.40474834
RW 18-36	6120	566	26.43344794	-81.40487449
RW 18-36	6115	305	26.42453358	-81.40472478
RW 18-36	6115	311	26.42535843	-81.40475631
RW 18-36	6115	316	26.42604581	-81.40478259
RW 18-36	6115	320	26.42691482	-81.40482236
RW 18-36	6115	324	26.42746182	-81.40483672
RW 18-36	6115	327	26.42787424	-81.40485249
RW 18-36	6115	333	26.4286991	-81.40488403
RW 18-36	6115	339	26.42952396	-81.40491556
RW 18-36	6115	345	26.43034881	-81.4049471
RW 18-36	6115	351	26.43117367	-81.40497864
RW 18-36	6115	357	26.43199852	-81.40501017
RW 18-36	6115	363	26.43282338	-81.40504171
RW 18-36	6115	369	26.43364823	-81.40507325
RW 18-36	6115	375	26.43447309	-81.40510479
RW 18-36	6115	378	26.43488552	-81.40512056
RW 18-36	6115	383	26.4355729	-81.40514684
RW 18-36	6115	387	26.4361228	-81.40516787
RW 18-36	6110	100	26.42390902	-81.40489199
RW 18-36	6105	301	26.42381183	-81.40469719
RW 18-36	6105	303	26.42422425	-81.40471295
AP HANG	4405	200	26.42268415	-81.40301142
AP RU RW36	4315	101	26.42368902	-81.40289286
AP RU RW36	4305	201	26.42332916	-81.403249

NOTE: GEODETICS REPRESENT DECIMAL DEGREES (NAD 83 FLORIDA STATE PLANES, EAST ZONE, US FOOT). ALL GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNITS.



GPS COORDINATES - IMMOKALEE REGIONAL AIRPORT				
LOCATION	SECTION	SAMPLE	LATITUDE	LONGITUDE
AP S	4220	600	26.42048033	-81.403032
AP S	4215	503	26.4212562	-81.40291102
AP S	4215	703	26.42124961	-81.4032203
AP S	4210	104	26.42181143	-81.40286253
AP S	4210	203	26.42153515	-81.4027342
AP S	4205	300	26.42071388	-81.4025323
CROP AP	4105	201	26.41988	-81.40521328
TW B1	410	187	26.4362886	-81.39690599
TW B1	405	101	26.43642879	-81.39660187
TW B1	405	104	26.4357638	-81.3971449
TW C	315	102	26.42432562	-81.40344036
TW C	315	107	26.42570039	-81.4034929
TW C	315	201	26.42642003	-81.40403253
TW C	310	102	26.42358139	-81.40368407
TW C	310	109	26.4217638	-81.40337322
TW TO AP	305	100	26.4226582	-81.40528128
TW TO AP	305	103	26.42100849	-81.4052182
TW A2	220	301	26.43489034	-81.40580872
TW A1	210	201	26.42637508	-81.40548311
TW A	205	103	26.42395756	-81.40578318
TW A	205	113	26.42648416	-81.40640452
TW A	205	123	26.42923368	-81.40650967
TW A	205	133	26.43198319	-81.40661483
TW A	205	143	26.43473271	-81.40672
TW A	205	152	26.43695541	-81.40630592
TW B	115	124	26.43514097	-81.39771542
TW B	110	104	26.43531025	-81.39607393
TW B	110	110	26.43578298	-81.39431718
TW B	110	116	26.43625568	-81.39256042
TW B	110	122	26.43672836	-81.39080365
TW B	105	102	26.4349424	-81.40412899
TW B	105	108	26.43499916	-81.40229654
TW B	105	114	26.4350559	-81.40046409
TW B	105	120	26.43511262	-81.39863164

NOTE: GEODETICS REPRESENT DECIMAL DEGREES (NAD 83 FLORIDA STATE PLANES, EAST ZONE, US FOOT). ALL GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNITS.

LEGEND

- RW 13-31** — TYPICAL RUNWAY BRANCH ID
- TW A** — TYPICAL TAXIWAY BRANCH ID
- AP S** — TYPICAL APRON BRANCH ID
- 4105** — SECTION NUMBER
AC — PAVEMENT TYPE
12.5' X 25' — TYPICAL SAMPLE UNIT INFORMATION
2 4 — FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH
1 2 — RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE
- 605** — NUMBER OF SAMPLE UNITS IN SECTION
1 8 — NUMBER OF SAMPLE UNITS TO BE INSPECTED
- 605** — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100** — INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 104



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS
DESIGNED:	ELT	DRAWN: BAL
CHECKED:	DRB	DATE: APRIL 2011
PLOTTER: July 14, 2011 - 8:30 AM, BY: Tawing, Glen		



NETWORK DEFINITION MAP
IMMOKALEE REGIONAL AIRPORT
COLLIER COUNTY, FLORIDA
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER
IMM
FOOT DISTRICT
1



CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2006	APRON	EXPANSION
2006	TAXIWAY CHARLIE	PAVEMENT REHABILITATION

LEGEND

- PROJECTS YEAR 2006
- PROJECTS YEAR 2007
- PROJECTS YEAR 2008
- PROJECTS YEAR 2009
- PROJECTS YEAR 2010
- PROJECTS YEAR 2011
- PROJECTS YEAR 2012
- PROJECTS YEAR 2013
- PROJECTS YEAR 2014
- PROJECTS YEAR 2015
- PROJECTS YEAR 2016
- PROJECTS YEAR 2017

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT
MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS
DESIGNED: ELT	DRAWN: BAL	CHECKED: DRB
DATE: APRIL 2011		



SYSTEM INVENTORY MAP
IMMOKALEE REGIONAL AIRPORT
COLLIER COUNTY, FLORIDA
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER
IMM
FOOT DISTRICT
1

Table A-1: Pavement Inventory

Branch Name	Branch ID	Branch Use	Section ID	Length (ft)	Width (ft)	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
Apron to Hangars	AP HANG	APRON	4405	900	25	22,500	P	AC	1/1/1998	3/28/2011	4
Apron Run-up RW 36	AP RU RW36	APRON	4305	150	50	8,000	P	AC	1/1/1998	3/28/2011	1
Apron Run-up RW 36	AP RU RW36	APRON	4310	80	66	6,309	P	AC	1/1/2001	3/28/2011	1
Apron Run-up RW 36	AP RU RW36	APRON	4315	185	86	18,752	N	AC	1/1/2002	3/28/2011	1
South Apron and Fueling Ramps	AP S	APRON	4205	140	200	28,000	P	AC	1/1/1997	3/28/2011	5
South Apron and Fueling Ramps	AP S	APRON	4210	216	355	63,618	P	AC	1/1/1998	3/28/2011	5
South Apron and Fueling Ramps	AP S	APRON	4215	340	160	54,400	P	AC	7/31/2007	3/28/2011	11
South Apron and Fueling Ramps	AP S	APRON	4220	180	200	36,000	P	AC	7/31/2007	3/28/2011	7
Crop Apron	CROP AP	APRON	4105	100	100	10,000	P	AC	1/1/1987	3/28/2011	2
Runway 18-36	RW 18-36	RUNWAY	6105	300	100	30,000	P	PCC	1/1/1942	3/28/2011	6
Runway 18-36	RW 18-36	RUNWAY	6110	600	25	15,000	P	PCC	1/1/1942	3/28/2011	3
Runway 18-36	RW 18-36	RUNWAY	6115	4,225	100	422,500	P	AC	1/1/1942	3/28/2011	106
Runway 18-36	RW 18-36	RUNWAY	6120	8,450	25	211,250	P	AC	1/1/1942	3/28/2011	53
Runway 18-36	RW 18-36	RUNWAY	6125	300	100	30,000	P	PCC	1/1/1942	3/28/2011	6
Runway 18-36	RW 18-36	RUNWAY	6130	600	25	15,000	P	PCC	1/1/1942	3/28/2011	3
Runway 4-22	RW 4-22	RUNWAY	6305	600	25	15,000	S	PCC	1/1/1942	3/28/2011	1
Runway 4-22	RW 4-22	RUNWAY	6310	350	100	35,000	S	PCC	1/1/1942	3/28/2011	3
Runway 4-22	RW 4-22	RUNWAY	6325	350	100	35,000	S	PCC	1/1/1942	3/28/2011	3
Runway 4-22	RW 4-22	RUNWAY	6330	600	25	15,000	S	PCC	1/1/1942	3/28/2011	1
Runway 9-27	RW 9-27	RUNWAY	6205	150	100	15,000	S	PCC	1/1/1942	3/28/2011	3
Runway 9-27	RW 9-27	RUNWAY	6210	300	25	7,500	S	PCC	1/1/1942	3/28/2011	1
Runway 9-27	RW 9-27	RUNWAY	6215	4,205	100	420,500	S	AC	1/1/1942	3/28/2011	105
Runway 9-27	RW 9-27	RUNWAY	6220	8,410	25	210,250	S	AC	1/1/1942	3/28/2011	53

Table A-1: Pavement Inventory (Continued)

Branch Name	Branch ID	Branch Use	Section ID	Length (ft)	Width (ft)	True Area (ft ²)	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
Runway 9-27	RW 9-27	RUNWAY	6225	300	100	30,000	S	PCC	1/1/1942	3/28/2011	6
Runway 9-27	RW 9-27	RUNWAY	6230	600	25	15,000	S	PCC	1/1/1942	3/28/2011	3
Taxiway Alpha	TW A	TAXIWAY	205	5,551	50	277,550	P	AC	1/1/1942	3/28/2011	69
Taxiway Alpha 1	TW A1	TAXIWAY	210	469	50	23,450	P	AC	1/1/1942	3/28/2011	6
Taxiway Alpha 2	TW A2	TAXIWAY	220	469	50	23,450	P	AC	1/1/1942	3/28/2011	6
Taxiway Bravo	TW B	TAXIWAY	105	2,341	50	117,050	P	AC	1/1/1942	3/28/2011	29
Taxiway Bravo	TW B	TAXIWAY	110	2,653	50	132,650	P	AC	1/1/1942	3/28/2011	33
Taxiway Bravo	TW B	TAXIWAY	115	200	50	10,000	P	AC	1/1/1942	3/28/2011	3
Taxiway Bravo 1	TW B1	TAXIWAY	405	660	50	33,000	P	AC	1/1/1942	3/28/2011	4
Taxiway Bravo 1	TW B1	TAXIWAY	410	1,270	50	69,493	P	AC	1/1/1942	3/28/2011	1
Taxiway Charlie	TW C	TAXIWAY	310	1,600	35	56,000	S	AC	1/1/1998	3/28/2011	14
Taxiway Charlie	TW C	TAXIWAY	315	1,425	35	49,875	S	AC	1/1/2007	3/28/2011	18
Taxiway to Crop Apron	TW TO AP	TAXIWAY	305	1,260	25	31,500	T	AC	1/1/1987	3/28/2011	8

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Section 4310 was not inspected due to obstruction.

Date:05/17/2011

Work History Report

1 of 6

Pavement Database:

Network: IMM Branch: AP HANG (APRON TO HANGARS) Section: 4405 Surface: AC
 L.C.D.: 01/01/1998 Use: APRON Rank:P Length: 900.00 Ft Width: 25.00 Ft True Area: 22.500.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1998	IMPORTED	BUILT			True	1998 AC PAVEMENT

Network: IMM Branch: AP RU RW36 (APRON RUN-UP RW 36) Section: 4305 Surface: AC
 L.C.D.: 01/01/1998 Use: APRON Rank:P Length: 150.00 Ft Width: 50.00 Ft True Area: 8.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1998	IMPORTED	BUILT			True	1998 AC PAVEMENT

Network: IMM Branch: AP RU RW36 (APRON RUN-UP RW 36) Section: 4310 Surface: AC
 L.C.D.: 01/01/2001 Use: APRON Rank:P Length: 80.00 Ft Width: 66.00 Ft True Area: 6.309.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2001	NC-AC	New Construction - AC	\$0	0.00	True	

Network: IMM Branch: AP RU RW36 (APRON RUN-UP RW 36) Section: 4315 Surface: AC
 L.C.D.: 01/01/2002 Use: APRON Rank:N Length: 185.00 Ft Width: 86.00 Ft True Area: 18.752.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2002	NC-AC	New Construction - AC	\$0	0.00	True	

Network: IMM Branch: AP S (SOUTH APRON AND FUELING RAMPS) Section: 4205 Surface: AC
 L.C.D.: 01/01/1997 Use: APRON Rank:P Length: 140.00 Ft Width: 200.00 Ft True Area: 28.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1997	IMPORTED	BUILT			True	1997 AC PAVEMENT

Network: IMM Branch: AP S (SOUTH APRON AND FUELING RAMPS) Section: 4210 Surface: AC
 L.C.D.: 01/01/1998 Use: APRON Rank:P Length: 216.00 Ft Width: 355.00 Ft True Area: 63.618.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1998	IMPORTED	BUILT			True	1998 AC PAVEMENT

Network: IMM Branch: AP S (SOUTH APRON AND FUELING RAMPS) Section: 4215 Surface: AC
 L.C.D.: 07/31/2007 Use: APRON Rank:P Length: 340.00 Ft Width: 160.00 Ft True Area: 54.400.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
07/31/2007	INITIAL	Initial Construction	\$0	0.00	True	

Network: IMM Branch: AP S (SOUTH APRON AND FUELING RAMPS) Section: 4220 Surface: AC
 L.C.D.: 07/31/2007 Use: APRON Rank:P Length: 180.00 Ft Width: 200.00 Ft True Area: 36.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
07/31/2007	INITIAL	Initial Construction	\$0	0.00	True	

Network: IMM Branch: AP SW (SOUTHWEST APRON) Section: 4105 Surface: AC
 L.C.D.: 01/01/1987 Use: APRON Rank:P Length: 100.00 Ft Width: 100.00 Ft True Area: 10.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1987	IMPORTED	BUILT			True	ESTIMATE 1987 AC PAVEMENT

Date:05/17/2011

Work History Report

2 of 6

Pavement Database:

Network: IMM Branch: RW 18-36 (RUNWAY 18-36) Section: 6105 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:P Length: 300.00 Ft Width: 100.00 Ft True Area: 30.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 18-36 (RUNWAY 18-36) Section: 6110 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:P Length: 600.00 Ft Width: 25.00 Ft True Area: 15.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 18-36 (RUNWAY 18-36) Section: 6115 Surface: AC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:P Length: 4.225.00 Ft Width: 100.00 Ft True Area: 422.500.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY		2.00	True	? PAVEMENT SECTION IS 2" AC ON 8" BASE?
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC PAVEMENT
01/01/1942	IMPORTED	BUILT			True	EMULSION SEAL - RECENT SEAL - REDUCES SEVERITY OF RAVELING

Network: IMM Branch: RW 18-36 (RUNWAY 18-36) Section: 6120 Surface: AC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:P Length: 8.450.00 Ft Width: 25.00 Ft True Area: 211.250.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC PAVEMENT
01/01/1942	IMPORTED	BUILT		2.00	True	? PAVEMENT SECTION IS 2" AC ON 8" BASE?

Network: IMM Branch: RW 18-36 (RUNWAY 18-36) Section: 6125 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:P Length: 300.00 Ft Width: 100.00 Ft True Area: 30.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 18-36 (RUNWAY 18-36) Section: 6130 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:P Length: 600.00 Ft Width: 25.00 Ft True Area: 15.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 4-22 (RUNWAY 4-22) Section: 6305 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 600.00 Ft Width: 25.00 Ft True Area: 15.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 4-22 (RUNWAY 4-22) Section: 6310 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 350.00 Ft Width: 100.00 Ft True Area: 35.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Date:05/17/2011

Work History Report

3 of 6

Pavement Database:

Network: IMM Branch: RW 4-22 (RUNWAY 4-22) Section: 6325 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 350.00 Ft Width: 100.00 Ft True Area: 35.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 4-22 (RUNWAY 4-22) Section: 6330 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 600.00 Ft Width: 25.00 Ft True Area: 15.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 9-27 (RUNWAY 9-27) Section: 6205 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 150.00 Ft Width: 100.00 Ft True Area: 15.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 9-27 (RUNWAY 9-27) Section: 6210 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 300.00 Ft Width: 25.00 Ft True Area: 7.500.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC

Network: IMM Branch: RW 9-27 (RUNWAY 9-27) Section: 6215 Surface: AC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 4.205.00 Ft Width: 100.00 Ft True Area: 420.500.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC PAVEMENT
01/01/1942	IMPORTED	BUILT		2.00	True	? PAVEMENT SECTION IS 2" AC ON 8" BASE?
01/01/1942	IMPORTED	OVERLAY			True	EMULSION SEAL - RECENT SEAL - REDUCES SEVERITY OF RAVELING RECORDED

Network: IMM Branch: RW 9-27 (RUNWAY 9-27) Section: 6220 Surface: AC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 8.410.00 Ft Width: 25.00 Ft True Area: 210.250.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		2.00	True	? PAVEMENT SECTION IS 2" AC ON 8" BASE?
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC PAVEMENT

Network: IMM Branch: RW 9-27 (RUNWAY 9-27) Section: 6225 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 300.00 Ft Width: 100.00 Ft True Area: 30.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC PAVEMENT

Network: IMM Branch: RW 9-27 (RUNWAY 9-27) Section: 6230 Surface: PCC
 L.C.D.: 01/01/1942 Use: RUNWAY Rank:S Length: 600.00 Ft Width: 25.00 Ft True Area: 15.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 PCC PAVEMENT

Date:05/17/2011

Work History Report

4 of 6

Pavement Database:

Network: IMM Branch: TW A (TAXIWAY A) Section: 205 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 5,551.00 Ft Width: 50.00 Ft True Area: 277,550.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		2.00	True	? PAVEMENT SECTION IS 2" AC ON 8" BASE?
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC PAVEMENT

Network: IMM Branch: TW A (TAXIWAY A) Section: 210 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 469.00 Ft Width: 50.00 Ft True Area: 23,450.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT			True	ESTIMATE 1942 AC PAVEMENT
01/01/1942	IMPORTED	OVERLAY		2.00	True	PAVEMENT SECTION IS 2" AC ON 8" BASE?

Network: IMM Branch: TW A (TAXIWAY A) Section: 220 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 469.00 Ft Width: 50.00 Ft True Area: 23,450.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC PAVEMENT
01/01/1942	IMPORTED	BUILT		2.00	True	? PAVEMENT SECTION IS 2" AC ON 8" BASE?

Network: IMM Branch: TW B (TAXIWAY B) Section: 105 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 2,341.00 Ft Width: 50.00 Ft True Area: 117,050.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC
01/01/1942	IMPORTED	BUILT		2.00	True	? PAVEMENT SECTION IS 2" AC ON 8" BASE?

Network: IMM Branch: TW B (TAXIWAY B) Section: 110 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 2,653.00 Ft Width: 50.00 Ft True Area: 132,650.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY			True	ESTIMATE 1942 AC PAVEMENT
01/01/1942	IMPORTED	BUILT		2.00	True	? 2" AC ON 8" BASE?

Network: IMM Branch: TW B (TAXIWAY B) Section: 115 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 200.00 Ft Width: 50.00 Ft True Area: 10,000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		2.00	True	EST 1942 2" AC SURFACE ON 8" AGG BASE

Network: IMM Branch: TW B1 (TAXIWAY B) Section: 405 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 660.00 Ft Width: 50.00 Ft True Area: 33,000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		2.00	True	EST 1942 2" AC SURFACE ON 8" AGG BASE

Network: IMM Branch: TW B1 (TAXIWAY B) Section: 410 Surface: AC
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank:P Length: 1,270.00 Ft Width: 50.00 Ft True Area: 69,493.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	INITIAL	Initial Construction	\$0	0.00	True	

Date:05/17/2011

Work History Report

5 of 6

Pavement Database:

Network: IMM **Branch:** TW C (TAXIWAY C) **Section:** 310 **Surface:** AC
L.C.D.: 01/01/1998 **Use:** TAXIWAY **Rank:**S **Length:** 1.600.00 Ft **Width:** 35.00 Ft **True Area:** 56.000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1998	INITIAL	Initial Construction	\$0	0.00	True	

Network: IMM **Branch:** TW C (TAXIWAY C) **Section:** 315 **Surface:** AC
L.C.D.: 01/01/2007 **Use:** TAXIWAY **Rank:**S **Length:** 1.425.00 Ft **Width:** 35.00 Ft **True Area:** 49.875.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2007	INITIAL	Initial Construction	\$0	0.00	True	

Network: IMM **Branch:** TW TO AP (TAXIWAY TO CROP AP) **Section:** 305 **Surface:** AC
L.C.D.: 01/01/1987 **Use:** TAXIWAY **Rank:**T **Length:** 1.260.00 Ft **Width:** 25.00 Ft **True Area:** 31.500.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1987	IMPORTED	BUILT			True	ESTIMATE 1987 AC PAVEMENT



Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	29	2,302,768.00	2.00	.00
Initial Construction	5	265,768.00	.00	.00
New Construction - AC	2	25,061.00	.00	.00
OVERLAY	11	2,681,650.00	2.00	.00

STD = Standard Deviation

APPENDIX B

2011 CONDITION MAP PAVEMENT CONDITION INDEX TABLE



- LEGEND**
- RW 13-31 TYPICAL RUNWAY BRANCH ID
 - TW A TYPICAL TAXIWAY BRANCH ID
 - AP S TYPICAL APRON BRANCH ID
 - PCI 86-100 GOOD
 - PCI 71-85 SATISFACTORY
 - PCI 56-70 FAIR
 - PCI 41-55 POOR
 - PCI 26-40 VERY POOR
 - PCI 11-25 SERIOUS
 - PCI 0-10 FAILED

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS
DESIGNED: ELT	DRAWN: BAL	CHECKED: DRB
DATE: APRIL 2011		



2011 CONDITION MAP
IMMOKALEE REGIONAL AIRPORT
COLLIER COUNTY, FLORIDA
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER
IMM
FOOT DISTRICT
1

Table B-1: Pavement Condition Index

Branch Name	Branch ID	Branch Use	Section ID	True Area (ft ²)	Section Rank	Surface Type	Total Samples Inspected	Total Samples	PCI	PCI Category
Apron to Hangars	AP HANG	APRON	4405	22,500	P	AC	1	4	93	Good
Apron Run-up RW 36	AP RU RW36	APRON	4305	8,000	P	AC	1	1	85	Satisfactory
Apron Run-up RW 36	AP RU RW36	APRON	4310	6,309	P	AC	0	1	100	Good
Apron Run-up RW 36	AP RU RW36	APRON	4315	18,752	N	AC	1	1	84	Satisfactory
South Apron and Fueling Ramps	AP S	APRON	4205	28,000	P	AC	1	5	87	Good
South Apron and Fueling Ramps	AP S	APRON	4210	63,618	P	AC	2	5	72	Satisfactory
South Apron and Fueling Ramps	AP S	APRON	4215	54,400	P	AC	0	11	100	Good
South Apron and Fueling Ramps	AP S	APRON	4220	36,000	P	AC	0	7	100	Good
Crop Apron	CROP AP	APRON	4105	10,000	P	AC	1	2	39	Very Poor
Runway 18-36	RW 18-36	RUNWAY	6105	30,000	P	PCC	2	6	28	Very Poor
Runway 18-36	RW 18-36	RUNWAY	6110	15,000	P	PCC	1	3	31	Very Poor
Runway 18-36	RW 18-36	RUNWAY	6115	422,500	P	AC	17	106	28	Very Poor
Runway 18-36	RW 18-36	RUNWAY	6120	211,250	P	AC	8	53	29	Very Poor
Runway 18-36	RW 18-36	RUNWAY	6125	30,000	P	PCC	2	6	18	Serious
Runway 18-36	RW 18-36	RUNWAY	6130	15,000	P	PCC	1	3	24	Serious
Runway 4-22	RW 4-22	RUNWAY	6305	15,000	S	PCC	1	1	37	Very Poor
Runway 4-22	RW 4-22	RUNWAY	6310	35,000	S	PCC	2	3	36	Very Poor
Runway 4-22	RW 4-22	RUNWAY	6325	35,000	S	PCC	2	3	31	Very Poor
Runway 4-22	RW 4-22	RUNWAY	6330	15,000	S	PCC	1	1	34	Very Poor
Runway 9-27	RW 9-27	RUNWAY	6205	15,000	S	PCC	1	3	29	Very Poor
Runway 9-27	RW 9-27	RUNWAY	6210	7,500	S	PCC	1	1	26	Very Poor
Runway 9-27	RW 9-27	RUNWAY	6215	420,500	S	AC	17	105	28	Very Poor
Runway 9-27	RW 9-27	RUNWAY	6220	210,250	S	AC	8	53	28	Very Poor

Table B-1: Pavement Condition Index (Continued)

Branch Name	Branch ID	Branch Use	Section ID	True Area (ft ²)	Section Rank	Surface Type	Total Samples Inspected	Total Samples	PCI	PCI Category
Runway 9-27	RW 9-27	RUNWAY	6225	30,000	S	PCC	2	6	27	Very Poor
Runway 9-27	RW 9-27	RUNWAY	6230	15,000	S	PCC	1	3	5	Failed
Taxiway Alpha	TW A	TAXIWAY	205	277,550	P	AC	6	69	25	Serious
Taxiway Alpha 1	TW A1	TAXIWAY	210	23,450	P	AC	1	6	26	Very Poor
Taxiway Alpha 2	TW A2	TAXIWAY	220	23,450	P	AC	1	6	22	Serious
Taxiway Bravo	TW B	TAXIWAY	105	117,050	P	AC	4	29	26	Very Poor
Taxiway Bravo	TW B	TAXIWAY	110	132,650	P	AC	4	33	34	Very Poor
Taxiway Bravo	TW B	TAXIWAY	115	10,000	P	AC	1	3	33	Very Poor
Taxiway Bravo 1	TW B1	TAXIWAY	405	33,000	P	AC	2	4	34	Very Poor
Taxiway Bravo 1	TW B1	TAXIWAY	410	69,493	P	AC	1	1	28	Very Poor
Taxiway Charlie	TW C	TAXIWAY	310	56,000	S	AC	2	14	89	Good
Taxiway Charlie	TW C	TAXIWAY	315	49,875	S	AC	3	18	94	Good
Taxiway to Crop Apron	TW TO AP	TAXIWAY	305	31,500	T	AC	2	8	67	Fair

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Section 4310 was not inspected due to obstruction.

APPENDIX C

**BRANCH CONDITION REPORT
SECTION CONDITION REPORT**

Date: 5 /17/2011

Branch Condition Report

1 of 2

Pavement Database: NetworkID: IMM

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	PCI Standard Deviation	Weighted Average PCI
AP HANG (APRON TO HANGARS)	1	900.00	25.00	22,500.00	APRON	93.00	0.00	93.00
AP RU RW36 (APRON RUN-UP RW 36)	3	415.00	67.33	33,061.00	APRON	89.67	7.32	87.30
AP S (SOUTH APRON AND FUELING RAMPS)	4	876.00	228.75	182,018.00	APRON	89.75	11.54	88.21
AP SW (SOUTHWEST APRON)	1	100.00	100.00	10,000.00	APRON	39.00	0.00	39.00
RW 18-36 (RUNWAY 18-36)	6	14,475.00	62.50	723,750.00	RUNWAY	26.33	4.27	27.86
RW 4-22 (RUNWAY 4-22)	4	1,900.00	62.50	100,000.00	RUNWAY	34.50	2.29	34.10
RW 9-27 (RUNWAY 9-27)	6	13,965.00	62.50	698,250.00	RUNWAY	23.83	8.47	27.46
TW A (TAXIWAY A)	3	6,489.00	50.00	324,450.00	TAXIWAY	24.33	1.70	24.86
TW B (TAXIWAY B)	3	5,194.00	50.00	259,700.00	TAXIWAY	31.00	3.56	30.36
TW B1 (TAXIWAY B)	2	1,930.00	50.00	102,493.00	TAXIWAY	31.00	3.00	29.93
TW C (TAXIWAY C)	2	3,025.00	35.00	105,875.00	TAXIWAY	91.50	2.50	91.36
TW TO AP (TAXIWAY TO CROP AP)	1	1,260.00	25.00	31,500.00	TAXIWAY	67.00	0.00	67.00

Date: 5 /17/2011

Branch Condition Report

2 of 2

Pavement Database:

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	9	247,579.00	84.44	18.34	86.54
RUNWAY	16	1,522,000.00	27.44	7.27	28.09
TAXIWAY	11	824,018.00	43.45	25.44	37.38
All	36	2,593,597.00	46.58	28.80	36.62

STD = Standard Deviation

Date: 5 /17/2011

Section Condition Report

1 of 3

Pavement Database: NetworkID: IMM

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP HANG (APRON TO HANGARS)	4405	01/01/1998	AC	APRON	P	0	22,500.00	03/28/2011	13	93.00
AP RU RW36 (APRON RUN-UP RW 36)	4305	01/01/1998	AC	APRON	P	0	8,000.00	03/28/2011	13	85.00
AP RU RW36 (APRON RUN-UP RW 36)	4310	01/01/2001	AC	APRON	P	0	6,309.00	01/01/2001	0	100.00
AP RU RW36 (APRON RUN-UP RW 36)	4315	01/01/2002	AC	APRON	N	0	18,752.00	03/28/2011	9	84.00
AP S (SOUTH APRON AND FUELING RAMPS)	4205	01/01/1997	AC	APRON	P	0	28,000.00	03/28/2011	14	87.00
AP S (SOUTH APRON AND FUELING RAMPS)	4210	01/01/1998	AC	APRON	P	0	63,618.00	03/28/2011	13	72.00
AP S (SOUTH APRON AND FUELING RAMPS)	4215	07/31/2007	AC	APRON	P	0	54,400.00	07/31/2007	0	100.00
AP S (SOUTH APRON AND FUELING RAMPS)	4220	07/31/2007	AC	APRON	P	0	36,000.00	07/31/2007	0	100.00
AP SW (SOUTHWEST APRON)	4105	01/01/1987	AC	APRON	P	0	10,000.00	03/28/2011	24	39.00
RW 18-36 (RUNWAY 18-36)	6105	01/01/1942	PCC	RUNWAY	P	0	30,000.00	03/28/2011	69	28.00
RW 18-36 (RUNWAY 18-36)	6110	01/01/1942	PCC	RUNWAY	P	0	15,000.00	03/28/2011	69	31.00
RW 18-36 (RUNWAY 18-36)	6115	01/01/1942	AC	RUNWAY	P	0	422,500.00	03/28/2011	69	28.00
RW 18-36 (RUNWAY 18-36)	6120	01/01/1942	AC	RUNWAY	P	0	211,250.00	03/28/2011	69	29.00
RW 18-36 (RUNWAY 18-36)	6125	01/01/1942	PCC	RUNWAY	P	0	30,000.00	03/28/2011	69	18.00
RW 18-36 (RUNWAY 18-36)	6130	01/01/1942	PCC	RUNWAY	P	0	15,000.00	03/28/2011	69	24.00
RW 4-22 (RUNWAY 4-22)	6305	01/01/1942	PCC	RUNWAY	S	0	15,000.00	03/28/2011	69	37.00
RW 4-22 (RUNWAY 4-22)	6310	01/01/1942	PCC	RUNWAY	S	0	35,000.00	03/28/2011	69	36.00
RW 4-22 (RUNWAY 4-22)	6325	01/01/1942	PCC	RUNWAY	S	0	35,000.00	03/28/2011	69	31.00
RW 4-22 (RUNWAY 4-22)	6330	01/01/1942	PCC	RUNWAY	S	0	15,000.00	03/28/2011	69	34.00
RW 9-27 (RUNWAY 9-27)	6205	01/01/1942	PCC	RUNWAY	S	0	15,000.00	03/28/2011	69	29.00
RW 9-27 (RUNWAY 9-27)	6210	01/01/1942	PCC	RUNWAY	S	0	7,500.00	03/28/2011	69	26.00
RW 9-27 (RUNWAY 9-27)	6215	01/01/1942	AC	RUNWAY	S	0	420,500.00	03/28/2011	69	28.00
RW 9-27 (RUNWAY 9-27)	6220	01/01/1942	AC	RUNWAY	S	0	210,250.00	03/28/2011	69	28.00
RW 9-27 (RUNWAY 9-27)	6225	01/01/1942	PCC	RUNWAY	S	0	30,000.00	03/28/2011	69	27.00
RW 9-27 (RUNWAY 9-27)	6230	01/01/1942	PCC	RUNWAY	S	0	15,000.00	03/28/2011	69	5.00

Date: 5 /17/2011

Section Condition Report

2 of 3

Pavement Database: NetworkID: IMM

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
TW A (TAXIWAY A)	205	01/01/1942	AC	TAXIWAY	P	0	277,550.00	03/28/2011	69	25.00
TW A (TAXIWAY A)	210	01/01/1942	AC	TAXIWAY	P	0	23,450.00	03/28/2011	69	26.00
TW A (TAXIWAY A)	220	01/01/1942	AC	TAXIWAY	P	0	23,450.00	03/28/2011	69	22.00
TW B (TAXIWAY B)	105	01/01/1942	AC	TAXIWAY	P	0	117,050.00	03/28/2011	69	26.00
TW B (TAXIWAY B)	110	01/01/1942	AC	TAXIWAY	P	0	132,650.00	03/28/2011	69	34.00
TW B (TAXIWAY B)	115	01/01/1942	AC	TAXIWAY	P	0	10,000.00	03/28/2011	69	33.00
TW B1 (TAXIWAY B)	405	01/01/1942	AC	TAXIWAY	P	0	33,000.00	03/28/2011	69	34.00
TW B1 (TAXIWAY B)	410	01/01/1942	AC	TAXIWAY	P	0	69,493.00	03/28/2011	69	28.00
TW C (TAXIWAY C)	310	01/01/1998	AC	TAXIWAY	S	0	56,000.00	03/28/2011	13	89.00
TW C (TAXIWAY C)	315	01/01/2007	AC	TAXIWAY	S	0	49,875.00	03/28/2011	4	94.00
TW TO AP (TAXIWAY TO CROP AP)	305	01/01/1987	AC	TAXIWAY	T	0	31,500.00	03/28/2011	24	67.00

Date: 5 /17/2011

Section Condition Report

3 of 3

Pavement Database:

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
0-02	0.00	96,709.00	3	100.00	0.00	100.00
03-05	4.00	49,875.00	1	94.00	0.00	94.00
06-10	9.00	18,752.00	1	84.00	0.00	84.00
11-15	13.20	178,118.00	5	85.20	7.11	82.94
21-25	24.00	41,500.00	2	53.00	14.00	60.25
over 40	69.00	2,208,643.00	24	27.79	6.45	27.96
All	49.53	2,593,597.00	36	46.58	28.80	36.62

APPENDIX D

PAVEMENT CONDITION PREDICTION TABLE PREDICTED PCI BY PAVEMENT USE GRAPH

Table D-1: Pavement Condition Prediction

Branch Name	Branch ID	Section ID	Current PCI	PCI Forecast									
				2011	2012	2013	2014	2015	2016	2017	2018	2019	2020
Apron to Hangars	AP HANG	4405	93	93	91	90	88	87	85	84	82	81	80
Apron Run-up RW 36	AP RU RW36	4305	85	85	83	82	80	79	77	76	74	73	72
Apron Run-up RW 36	AP RU RW36	4310	100	85	83	82	80	79	78	76	75	73	72
Apron Run-up RW 36	AP RU RW36	4315	84	84	82	81	79	78	76	75	73	72	71
South Apron and Fueling Ramps	AP S	4205	87	87	85	84	82	81	79	78	76	75	74
South Apron and Fueling Ramps	AP S	4210	72	72	70	69	67	66	64	63	61	60	59
South Apron and Fueling Ramps	AP S	4215	100	94	93	91	90	89	87	86	84	83	81
South Apron and Fueling Ramps	AP S	4220	100	94	93	91	90	89	87	86	84	83	81
Crop Apron	CROP AP	4105	39	39	37	36	34	33	31	30	28	27	26
Runway 18-36	RW 18-36	6105	28	27	25	22	20	17	14	12	9	7	4
Runway 18-36	RW 18-36	6110	31	30	28	25	23	20	17	15	12	10	7
Runway 18-36	RW 18-36	6115	28	28	26	25	23	22	20	19	17	16	14
Runway 18-36	RW 18-36	6120	29	29	27	26	24	23	21	20	18	17	15
Runway 18-36	RW 18-36	6125	18	17	15	12	10	7	4	2	0	0	0
Runway 18-36	RW 18-36	6130	24	23	21	18	16	13	10	8	5	3	0
Runway 4-22	RW 4-22	6305	37	36	34	31	29	26	23	21	18	16	13
Runway 4-22	RW 4-22	6310	36	35	33	30	28	25	22	20	17	15	12
Runway 4-22	RW 4-22	6325	31	30	28	25	23	20	17	15	12	10	7
Runway 4-22	RW 4-22	6330	34	33	31	28	26	23	20	18	15	13	10
Runway 9-27	RW 9-27	6205	29	28	26	23	21	18	15	13	10	8	5
Runway 9-27	RW 9-27	6210	26	25	23	20	18	15	12	10	7	5	2
Runway 9-27	RW 9-27	6215	28	28	26	25	23	22	20	19	17	16	14
Runway 9-27	RW 9-27	6220	28	28	26	25	23	22	20	19	17	16	14
Runway 9-27	RW 9-27	6225	27	26	24	21	19	16	13	11	8	6	3

Table D-1: Pavement Condition Prediction (Continued)

Branch Name	Branch ID	Section ID	Current PCI	PCI Forecast									
				2011	2012	2013	2014	2015	2016	2017	2018	2019	2020
Runway 9-27	RW 9-27	6230	5	4	2	0	0	0	0	0	0	0	0
Taxiway Alpha	TW A	205	25	25	23	21	19	18	16	14	13	11	9
Taxiway Alpha 1	TW A1	210	26	26	24	22	20	19	17	15	14	12	10
Taxiway Alpha 2	TW A2	220	22	22	20	18	16	15	13	11	10	8	6
Taxiway Bravo	TW B	105	26	26	24	22	20	19	17	15	14	12	10
Taxiway Bravo	TW B	110	34	34	32	30	28	27	25	23	22	20	18
Taxiway Bravo	TW B	115	33	33	31	29	27	26	24	22	21	19	17
Taxiway Bravo 1	TW B1	405	34	34	32	30	28	27	25	23	22	20	18
Taxiway Bravo 1	TW B1	410	28	28	26	24	22	21	19	17	16	14	12
Taxiway Charlie	TW C	310	89	89	87	85	83	82	80	78	77	75	73
Taxiway Charlie	TW C	315	94	94	92	90	88	87	85	83	82	80	78
Taxiway to Crop Apron	TW TO AP	305	67	67	65	63	61	60	58	56	55	53	51

Figure D-1: Predicted PCI by Pavement Use



APPENDIX E

YEAR 1 MAINTENANCE ACTIVITIES TABLE

Table E-1: Year 1 Maintenance Activities

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Apron to Hangars	AP HANG	4405	WEATH/RAVEL	L	Surface Seal - Rejuvenating	300.00	SqFt	\$0.40	\$120.00
Apron Run-up RW 36	AP RU RW36	4305	OIL SPILLAGE	N	Patching - AC Shallow	48.10	SqFt	\$2.90	\$139.37
Apron Run-up RW 36	AP RU RW36	4305	WEATH/RAVEL	L	Surface Seal - Rejuvenating	484.80	SqFt	\$0.40	\$193.94
Apron Run-up RW 36	AP RU RW36	4315	WEATH/RAVEL	L	Surface Seal - Rejuvenating	2,812.80	SqFt	\$0.40	\$1,125.12
Apron Run-up RW 36	AP RU RW36	4315	OIL SPILLAGE	N	Patching - AC Shallow	38.30	SqFt	\$2.90	\$110.94
South Apron and Fueling Ramps	AP S	4205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	2,800.00	SqFt	\$0.40	\$1,120.00
South Apron and Fueling Ramps	AP S	4210	L & T CR	M	Crack Sealing - AC	559.00	Ft	\$2.25	\$1,257.71
South Apron and Fueling Ramps	AP S	4210	WEATH/RAVEL	L	Surface Seal - Rejuvenating	19,045.00	SqFt	\$0.40	\$7,618.07
Taxiway Charlie	TW C	310	WEATH/RAVEL	L	Surface Seal - Rejuvenating	569.90	SqFt	\$0.40	\$227.96
Taxiway Charlie	TW C	315	WEATH/RAVEL	L	Surface Seal - Rejuvenating	47.50	SqFt	\$0.40	\$19.00
Taxiway to Crop Apron	TW TO AP	305	WEATH/RAVEL	L	Surface Seal - Rejuvenating	22,049.80	SqFt	\$0.40	\$8,820.00
Taxiway to Crop Apron	TW TO AP	305	L & T CR	M	Crack Sealing - AC	91.40	Ft	\$2.25	\$205.59
Total =									\$20,957.70

APPENDIX F

MAJOR M&R PLAN BY YEAR UNDER UNLIMITED FUNDING SCENARIO TABLE

Table F-1: Major M&R Plan by Year under Unlimited Funding Scenario

Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	Crop Apron	4105	AC	10,000. SqFt	\$ 70,230.01	39	Reconstruction	100
2011	Runway 18-36	6105	PCC	30,000. SqFt	\$ 408,600.13	27	Reconstruction	100
2011	Runway 18-36	6110	PCC	15,000. SqFt	\$ 204,300.07	30	Reconstruction	100
2011	Runway 18-36	6115	AC	422,500. SqFt	\$ 5,754,451.87	28	Reconstruction	100
2011	Runway 18-36	6120	AC	211,250. SqFt	\$ 2,877,225.93	29	Reconstruction	100
2011	Runway 18-36	6125	PCC	30,000. SqFt	\$ 408,600.13	17	Reconstruction	100
2011	Runway 18-36	6130	PCC	15,000. SqFt	\$ 204,300.07	23	Reconstruction	100
2011	Runway 4-22	6305	PCC	15,000. SqFt	\$ 138,330.04	36	Reconstruction	100
2011	Runway 4-22	6310	PCC	35,000. SqFt	\$ 348,425.09	35	Reconstruction	100
2011	Runway 4-22	6325	PCC	35,000. SqFt	\$ 476,700.15	30	Reconstruction	100
2011	Runway 4-22	6330	PCC	15,000. SqFt	\$ 171,315.06	33	Reconstruction	100
2011	Runway 9-27	6205	PCC	15,000. SqFt	\$ 204,300.07	28	Reconstruction	100
2011	Runway 9-27	6210	PCC	7,500. SqFt	\$ 102,150.03	25	Reconstruction	100
2011	Runway 9-27	6215	AC	420,500. SqFt	\$ 5,727,211.86	28	Reconstruction	100
2011	Runway 9-27	6220	AC	210,250. SqFt	\$ 2,863,605.93	28	Reconstruction	100
2011	Runway 9-27	6225	PCC	30,000. SqFt	\$ 408,600.13	26	Reconstruction	100
2011	Runway 9-27	6230	PCC	15,000. SqFt	\$ 204,300.07	4	Reconstruction	100
2011	Taxiway Alpha	205	AC	277,550. SqFt	\$ 3,780,232.23	25	Reconstruction	100
2011	Taxiway Alpha 1	210	AC	23,450. SqFt	\$ 319,389.10	26	Reconstruction	100
2011	Taxiway Alpha 2	220	AC	23,450. SqFt	\$ 319,389.10	22	Reconstruction	100
2011	Taxiway Bravo	105	AC	117,050. SqFt	\$ 1,594,221.52	26	Reconstruction	100
2011	Taxiway Bravo	110	AC	132,650. SqFt	\$ 1,417,763.62	34	Reconstruction	100
2011	Taxiway Bravo	115	AC	10,000. SqFt	\$ 114,210.04	33	Reconstruction	100



Table F-1: Major M&R Plan by Year under Unlimited Funding Scenario (Continued)

Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	Taxiway Bravo 1	405	AC	33,000. SqFt	\$ 352,704.10	34	Reconstruction	100
2011	Taxiway Bravo 1	410	AC	69,493. SqFt	\$ 946,494.97	28	Reconstruction	100
2013	Taxiway to Crop Apron	305	AC	31,500. SqFt	\$ 86,921.18	63	Mill and Overlay	100
2016	South Apron and Fueling Ramps	4210	AC	63,618. SqFt	\$ 171,691.73	64	Mill and Overlay	100
Total					\$29,675,664.23	30		100

* Costs are adjusted for inflation.

APPENDIX G

10-YEAR M&R MAP



LEGEND

- RW 13-3 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

YEAR

- 2011
- 2012
- 2013
- 2014
- 2015
- 2016
- 2017
- 2018
- 2019
- 2020

ACTIVITY

- MICROSURFACING
- MILL AND OVERLAY
- RECONSTRUCTION
- CONCRETE PAVEMENT RESTORATION

"PLAN YEAR"
"BRANCH"; "SECTION"
"M AND R ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS
DESIGNED: ELT	DRAWN: BAL	CHECKED: DRB
DATE: APRIL 2011		



APPENDIX H

PHOTOGRAPHS



Runway 9-27, Section 6225, Sample Unit 388 – Low, medium and high severity (62) Corner Break, (63) LTD Cracking, (65) Joint Seal Damage, (70) Scaling/Map Cracking, (72) Shattered Slabs, (73) Shrinkage Cracks, (74) Joint Spalling, (75) Corner Spalling



Runway 9-27, Section 6225, Sample Unit 388 – Low, medium and high severity (62) Corner Break, (63) LTD Cracking, (65) Joint Seal Damage, (70) Scaling/Map Cracking, (72) Shattered Slabs, (73) Shrinkage Cracks, (74) Joint Spalling, (75) Corner Spalling



Runway 9-27, Section 6215, Sample Unit 380 – Low and medium severity (43) Block Cracking, medium severity (52) Weathering and Raveling



Runway 9-27, Section 6215, Sample Unit 380 – Low and medium severity (43) Block Cracking, medium severity (52) Weathering and Raveling



Runway 18-36, Section 6125, Sample Unit 392 – Low, medium and high severity (62) Corner Break, (63) LTD Cracking, (65) Joint Seal Damage, (70) Scaling/Map Cracking, (72) Shattered Slabs, (73) Shrinkage Cracks, (74) Joint Spalling, (75) Corner Spalling



Runway 18-36, Section 6125, Sample Unit 392 – Low, medium and high severity (62) Corner Break, (63) LTD Cracking, (65) Joint Seal Damage, (70) Scaling/Map Cracking, (72) Shattered Slabs, (73) Shrinkage Cracks, (74) Joint Spalling, (75) Corner Spalling



Runway 18-36, Section 6115, Sample Unit 383 – Medium severity (43) Block Cracking, medium severity (48) Longitudinal and Transverse Cracking, medium severity (52) Weathering and Raveling



Runway 18-36, Section 6115, Sample Unit 383 – Medium severity (43) Block Cracking, medium severity (48) Longitudinal and Transverse Cracking, medium severity (52) Weathering and Raveling



Taxiway A-1, Section 210, Sample Unit 201 – Medium severity (43) Block Cracking, medium severity (50) Patch, medium severity (52) Weathering and Raveling



Taxiway A-1, Section 210, Sample Unit 201 – Medium severity (43) Block Cracking, medium severity (50) Patch, medium severity (52) Weathering and Raveling



Taxiway Bravo, Section 105, Sample Unit 108 – Low and medium severity (43) Block Cracking, medium severity (52) Weathering and Raveling



Taxiway Bravo, Section 105, Sample Unit 108 – Low and medium severity (43) Block Cracking, medium severity (52) Weathering and Raveling



Apron, Section 4210, Sample Unit 203 – Low severity (48) Longitudinal and Transverse Cracking, low severity (50) Patch ,low severity (52) Weathering and Raveling

APPENDIX I

PCI RE-INSPECTION REPORT

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP HANG Name: APRON TO HANGARS Use: APRON Area: 22,500.00SqFt

Section: 4405 of 1 From: - To: - Last Const.: 1/1/1998
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 22,500.00SqFt Length: 900.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 4 Surveyed: 1
Conditions: PCI:93.00 |
Inspection Comments:

Sample Number: 200 Type: R Area: 7,500.00SqFt PCI = 93

Sample Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 39.01 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP RU RW36 Name: APRON RUN-UP RW 36 Use: APRON Area: 33,061.00SqFt

Section: 4305 of 3 From: - To: - Last Const.: 1/1/1998
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 8,000.00SqFt Length: 150.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 1 Surveyed: 1
Conditions: PCI:85.00 |
Inspection Comments:

Sample Number: 201 Type: R Area: 6,600.00SqFt PCI = 85

Sample Comments:

52 WEATHERING/RAVELING	L	400.00 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	130.03 Ft	Comments:
49 OIL SPILLAGE	N	20.00 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP RU RW36 Name: APRON RUN-UP RW 36 Use: APRON Area: 33,061.00SqFt

Section: 4310 of 3 From: - To: - Last Const.: 1/1/2001
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 6,309.00SqFt Length: 80.00Ft Width: 66.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 1/1/2001 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00
<NO SAMPLE RECORDS>

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP RU RW36 Name: APRON RUN-UP RW 36 Use: APRON Area: 33,061.00SqFt

Section: 4315 of 3 From: - To: - Last Const.: 1/1/2002
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: N
Area: 18,752.00SqFt Length: 185.00Ft Width: 86.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 1 Surveyed: 1
Conditions: PCI:84.00 |
Inspection Comments:

Sample Number:	101	Type:	R	Area:	4,300.00SqFt	PCI = 84
Sample Comments:						
49	OIL SPILLAGE		N	4.00	SqFt	Comments:
52	WEATHERING/RAVELING		L	644.99	SqFt	Comments:
50	PATCHING		L	1.00	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP S Name: SOUTH APRON AND FUELING R Use: APRON Area: 182,018.00SqFt

Section: 4205 of 4 From: - To: - Last Const.: 1/1/1997
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 28,000.00SqFt Length: 140.00Ft Width: 200.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 5 Surveyed: 1

Conditions: PCI:87.00 |

Inspection Comments:

Sample Number: 300 Type: R Area: 5,000.00SqFt PCI = 87

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 9.00 Ft Comments:
52 WEATHERING/RAVELING L 500.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP S Name: SOUTH APRON AND FUELING R Use: APRON Area: 182,018.00SqFt

Section: 4210 of 4 From: - To: - Last Const.: 1/1/1998
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 63,618.00SqFt Length: 216.00Ft Width: 355.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 5 Surveyed: 2

Conditions: PCI: 72.00 |

Inspection Comments:

Sample Number: 104 Type: R Area: 4,584.00SqFt PCI = 69

Sample Comments:

52 WEATHERING/RAVELING	L	687.99 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	100.03 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	210.05 Ft	Comments:
43 BLOCK CRACKING	L	108.00 SqFt	Comments:

Sample Number: 203 Type: R Area: 6,800.00SqFt PCI = 74

Sample Comments:

50 PATCHING	L	1.50 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	100.03 Ft	Comments:
52 WEATHERING/RAVELING	L	2,719.98 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP S Name: SOUTH APRON AND FUELING R Use: APRON Area: 182,018.00SqFt

Section: 4215 of 4 From: - To: - Last Const.: 7/31/2007
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 54,400.00SqFt Length: 340.00Ft Width: 160.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 7/31/2007 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00
<NO SAMPLE RECORDS>

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP S Name: SOUTH APRON AND FUELING R Use: APRON Area: 182,018.00SqFt

Section: 4220 of 4 From: - To: - Last Const.: 7/31/2007
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 36,000.00SqFt Length: 180.00Ft Width: 200.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 7/31/2007 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00
<NO SAMPLE RECORDS>

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: AP SW Name: SOUTHWEST APRON Use: APRON Area: 10,000.00SqFt

Section: 4105 of 1 From: - To: - Last Const.: 1/1/1987
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 10,000.00SqFt Length: 100.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 2 Surveyed: 1
Conditions: PCI:39.00 |
Inspection Comments:

Sample Number: 201 Type: R Area: 5,000.00SqFt PCI = 39

Sample Comments:

52 WEATHERING/RAVELING M 4,999.96 SqFt Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 30.01 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 18-36 Name: RUNWAY 18-36 Use: RUNWAY Area: 723,750.00SqFt

Section: 6105 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: P
Area: 30,000.00SqFt Length: 300.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 6 Surveyed: 2

Conditions: PCI:28.00 |

Inspection Comments:

Sample Number: 301 Type: R Area: 24.00Slabs PCI = 28

Sample Comments:

65	JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
75	CORNER SPALLING	L	12.00	Slabs	Comments:
70	SCALING/CRAZING	L	12.00	Slabs	Comments:
63	LINEAR CRACKING	M	3.00	Slabs	Comments:
74	JOINT SPALLING	L	9.00	Slabs	Comments:
74	JOINT SPALLING	M	3.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	9.00	Slabs	Comments:
63	LINEAR CRACKING	L	2.00	Slabs	Comments:
70	SCALING/CRAZING	M	11.00	Slabs	Comments:

Sample Number: 303 Type: R Area: 24.00Slabs PCI = 28

Sample Comments:

65	JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
70	SCALING/CRAZING	L	23.00	Slabs	Comments:
74	JOINT SPALLING	L	22.00	Slabs	Comments:
63	LINEAR CRACKING	L	8.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	22.00	Slabs	Comments:
75	CORNER SPALLING	L	8.00	Slabs	Comments:
63	LINEAR CRACKING	M	9.00	Slabs	Comments:
62	CORNER BREAK	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 18-36 Name: RUNWAY 18-36 Use: RUNWAY Area: 723,750.00SqFt

Section: 6110 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: P
Area: 15,000.00SqFt Length: 600.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 3 Surveyed: 1

Conditions: PCI:31.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 24.00Slabs PCI = 31

Sample Comments:

65	JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
74	JOINT SPALLING	L	17.00	Slabs	Comments:
63	LINEAR CRACKING	M	11.00	Slabs	Comments:
70	SCALING/CRAZING	L	24.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	8.00	Slabs	Comments:
75	CORNER SPALLING	L	3.00	Slabs	Comments:
63	LINEAR CRACKING	L	6.00	Slabs	Comments:
62	CORNER BREAK	L	1.00	Slabs	Comments:
62	CORNER BREAK	M	1.00	Slabs	Comments:
75	CORNER SPALLING	M	1.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 18-36 Name: RUNWAY 18-36 Use: RUNWAY Area: 723,750.00SqFt

Section: 6115 of 6 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-RW-AC Zone: Category: Rank: P
Area: 422,500.00SqFt Length: 4,225.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 106 Surveyed: 17

Conditions: PCI:28.00 |

Inspection Comments:

Sample Number: 305 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	1,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	1,999.98 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 311 Type: R Area: 5,000.00SqFt PCI = 29

Sample Comments:

43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	500.00 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 316 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	999.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 320 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	2,799.98 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	153.04 Ft	Comments:
52 WEATHERING/RAVELING	M	4,346.96 SqFt	Comments:

Sample Number: 324 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,855.98 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	50.01 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	16.00 Ft	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 327 Type: R Area: 5,000.00SqFt PCI = 37

Sample Comments:

43 BLOCK CRACKING	M	1,949.98 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 333 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	1,549.99 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	362.09 Ft	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 339 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	M	314.08 Ft	Comments:
-------------------------------------	---	-----------	-----------

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	22.01	Ft	Comments:
43	BLOCK CRACKING	M	1,599.99	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 345 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	293.08	Ft	Comments:
43	BLOCK CRACKING	M	2,499.98	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 351 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	251.06	Ft	Comments:
43	BLOCK CRACKING	M	2,599.98	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 357 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43	BLOCK CRACKING	M	2,699.98	SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	150.04	Ft	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 363 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	402.10	Ft	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:
43	BLOCK CRACKING	M	1,049.99	SqFt	Comments:

Sample Number: 369 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43	BLOCK CRACKING	M	2,599.98	SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	196.05	Ft	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 375 Type: R Area: 5,000.00SqFt PCI = 24

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	316.08	Ft	Comments:
43	BLOCK CRACKING	M	2,049.98	SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	80.02	Ft	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 378 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	374.10	Ft	Comments:
43	BLOCK CRACKING	M	1,499.99	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 383 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	172.04	Ft	Comments:
43	BLOCK CRACKING	M	2,549.98	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 387 Type: R Area: 5,000.00SqFt PCI = 34

Sample Comments:

52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	198.05	Ft	Comments:
43	BLOCK CRACKING	M	954.99	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 18-36 Name: RUNWAY 18-36 Use: RUNWAY Area: 723,750.00SqFt

Section: 6120 of 6 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-RW-AC Zone: Category: Rank: P
Area: 211,250.00SqFt Length: 8,450.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 53 Surveyed: 8

Conditions: PCI:29.00 |

Inspection Comments:

Sample Number: 108 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	3,999.97 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	12.00 Ft	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 118 Type: R Area: 5,000.00SqFt PCI = 21

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	M	642.16 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	53.01 Ft	Comments:
43 BLOCK CRACKING	M	999.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,987.96 SqFt	Comments:

Sample Number: 150 Type: R Area: 5,000.00SqFt PCI = 29

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	50.01 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	787.20 Ft	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 182 Type: R Area: 5,000.00SqFt PCI = 30

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	M	700.18 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	62.02 Ft	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 504 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	18.00 Ft	Comments:
43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	999.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 534 Type: R Area: 5,000.00SqFt PCI = 30

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	111.03 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	725.19 Ft	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 542 Type: R Area: 5,000.00SqFt PCI = 33

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	M	570.15 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	16.00 Ft	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Sample Number: 566	Type: R	Area:	5,000.00SqFt	PCI = 35
Sample Comments:				
48 LONGITUDINAL/TRANSVERSE CRACKING	M	628.16 Ft	Comments:	
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:	

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 18-36 Name: RUNWAY 18-36 Use: RUNWAY Area: 723,750.00SqFt

Section: 6125 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: P
Area: 30,000.00SqFt Length: 300.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 6 Surveyed: 2

Conditions: PCI:18.00 |

Inspection Comments:

Sample Number: 390 Type: R Area: 24.00Slabs PCI = 16

Sample Comments:

65 JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
63 LINEAR CRACKING	M	20.00	Slabs	Comments:
75 CORNER SPALLING	L	4.00	Slabs	Comments:
74 JOINT SPALLING	L	10.00	Slabs	Comments:
75 CORNER SPALLING	M	6.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	7.00	Slabs	Comments:
62 CORNER BREAK	M	4.00	Slabs	Comments:
74 JOINT SPALLING	M	9.00	Slabs	Comments:
63 LINEAR CRACKING	L	5.00	Slabs	Comments:
74 JOINT SPALLING	H	1.00	Slabs	Comments:
75 CORNER SPALLING	H	1.00	Slabs	Comments:
74 JOINT SPALLING	M	2.00	Slabs	Comments:
70 SCALING/CRAZING	L	21.00	Slabs	Comments:

Sample Number: 392 Type: R Area: 24.00Slabs PCI = 21

Sample Comments: SAMPLE UNIT RENAMED ON 6/20/05

65 JOINT SEAL DAMAGE	H	24.00	Slabs	Comments:
71 FAULTING	L	2.00	Slabs	Comments:
74 JOINT SPALLING	L	16.00	Slabs	Comments:
75 CORNER SPALLING	L	6.00	Slabs	Comments:
74 JOINT SPALLING	M	4.00	Slabs	Comments:
75 CORNER SPALLING	M	4.00	Slabs	Comments:
63 LINEAR CRACKING	M	16.00	Slabs	Comments:
70 SCALING/CRAZING	L	9.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	4.00	Slabs	Comments:
63 LINEAR CRACKING	L	6.00	Slabs	Comments:
74 JOINT SPALLING	H	1.00	Slabs	Comments:
74 JOINT SPALLING	H	2.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 18-36 Name: RUNWAY 18-36 Use: RUNWAY Area: 723,750.00SqFt

Section: 6130 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: P
Area: 15,000.00SqFt Length: 600.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 3 Surveyed: 1
Conditions: PCI: 24.00 |
Inspection Comments:

Sample Number: 100 Type: R Area: 24.00Slabs PCI = 24

Sample Comments:

65	JOINT SEAL DAMAGE	H	24.00	Slabs	Comments:
63	LINEAR CRACKING	M	20.00	Slabs	Comments:
74	JOINT SPALLING	L	24.00	Slabs	Comments:
75	CORNER SPALLING	L	11.00	Slabs	Comments:
70	SCALING/CRAZING	L	17.00	Slabs	Comments:
63	LINEAR CRACKING	L	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	3.00	Slabs	Comments:
74	JOINT SPALLING	M	2.00	Slabs	Comments:
75	CORNER SPALLING	M	3.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 4-22 Name: RUNWAY 4-22 Use: RUNWAY Area: 100,000.00SqFt

Section: 6305 of 4 From: - To: - Last Const.: 1/1/1942

Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s

Area: 15,000.00SqFt Length: 600.00Ft Width: 25.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 1 Surveyed: 1

Conditions: PCI: 37.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 25.00Slabs PCI = 37

Sample Comments:

65	JOINT SEAL DAMAGE	M	25.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	9.00	Slabs	Comments:
70	SCALING/CRAZING	M	6.00	Slabs	Comments:
63	LINEAR CRACKING	L	10.00	Slabs	Comments:
74	JOINT SPALLING	L	12.00	Slabs	Comments:
75	CORNER SPALLING	L	8.00	Slabs	Comments:
62	CORNER BREAK	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	2.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 4-22 Name: RUNWAY 4-22 Use: RUNWAY Area: 100,000.00SqFt

Section: 6310 of 4 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s
Area: 35,000.00SqFt Length: 350.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 3 Surveyed: 2

Conditions: PCI:36.00 |

Inspection Comments:

Sample Number: 301 Type: R Area: 24.00Slabs PCI = 30

Sample Comments:

65	JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
70	SCALING/CRAZING	M	13.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	11.00	Slabs	Comments:
74	JOINT SPALLING	L	12.00	Slabs	Comments:
63	LINEAR CRACKING	L	8.00	Slabs	Comments:
70	SCALING/CRAZING	L	11.00	Slabs	Comments:
75	CORNER SPALLING	L	11.00	Slabs	Comments:

Sample Number: 303 Type: R Area: 24.00Slabs PCI = 43

Sample Comments:

65	JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
74	JOINT SPALLING	L	11.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
75	CORNER SPALLING	L	15.00	Slabs	Comments:
63	LINEAR CRACKING	L	5.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 4-22 Name: RUNWAY 4-22 Use: RUNWAY Area: 100,000.00SqFt

Section: 6325 of 4 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s
Area: 35,000.00SqFt Length: 350.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 3 Surveyed: 2

Conditions: PCI:31.00 |

Inspection Comments:

Sample Number: 395 Type: R Area: 24.00Slabs PCI = 31

Sample Comments:

65	JOINT SEAL DAMAGE	H	24.00	Slabs	Comments:
74	JOINT SPALLING	L	17.00	Slabs	Comments:
63	LINEAR CRACKING	M	5.00	Slabs	Comments:
70	SCALING/CRAZING	L	18.00	Slabs	Comments:
75	CORNER SPALLING	M	4.00	Slabs	Comments:
63	LINEAR CRACKING	L	6.00	Slabs	Comments:
62	CORNER BREAK	L	3.00	Slabs	Comments:
74	JOINT SPALLING	M	5.00	Slabs	Comments:
75	CORNER SPALLING	L	6.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	1.00	Slabs	Comments:

Sample Number: 398 Type: R Area: 24.00Slabs PCI = 30

Sample Comments:

65	JOINT SEAL DAMAGE	H	24.00	Slabs	Comments:
74	JOINT SPALLING	L	15.00	Slabs	Comments:
70	SCALING/CRAZING	L	22.00	Slabs	Comments:
75	CORNER SPALLING	L	2.00	Slabs	Comments:
74	JOINT SPALLING	M	6.00	Slabs	Comments:
63	LINEAR CRACKING	M	11.00	Slabs	Comments:
75	CORNER SPALLING	M	3.00	Slabs	Comments:
63	LINEAR CRACKING	L	1.00	Slabs	Comments:
62	CORNER BREAK	L	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	3.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 4-22 Name: RUNWAY 4-22 Use: RUNWAY Area: 100,000.00SqFt

Section: 6330 of 4 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s
Area: 15,000.00SqFt Length: 600.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 1 Surveyed: 1
Conditions: PCI: 34.00 |
Inspection Comments:

Sample Number: 195 Type: R Area: 24.00Slabs PCI = 34

Sample Comments:

65	JOINT SEAL DAMAGE	H	24.00	Slabs	Comments:
74	JOINT SPALLING	L	24.00	Slabs	Comments:
70	SCALING/CRAZING	L	20.00	Slabs	Comments:
63	LINEAR CRACKING	M	7.00	Slabs	Comments:
75	CORNER SPALLING	L	8.00	Slabs	Comments:
63	LINEAR CRACKING	L	7.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 698,250.00SqFt

Section: 6205 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s
Area: 15,000.00SqFt Length: 150.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 3 Surveyed: 1

Conditions: PCI:29.00 |

Inspection Comments:

Sample Number: 301 Type: R Area: 24.00Slabs PCI = 29

Sample Comments:

65	JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
74	JOINT SPALLING	L	8.00	Slabs	Comments:
63	LINEAR CRACKING	L	11.00	Slabs	Comments:
63	LINEAR CRACKING	M	10.00	Slabs	Comments:
75	CORNER SPALLING	L	3.00	Slabs	Comments:
75	CORNER SPALLING	M	4.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:
70	SCALING/CRAZING	L	2.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 698,250.00SqFt

Section: 6210 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s
Area: 7,500.00SqFt Length: 300.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 1 Surveyed: 1

Conditions: PCI: 26.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 12.00Slabs PCI = 26

Sample Comments:

65 JOINT SEAL DAMAGE	M	12.00 Slabs	Comments:
63 LINEAR CRACKING	M	8.00 Slabs	Comments:
74 JOINT SPALLING	L	4.00 Slabs	Comments:
75 CORNER SPALLING	L	2.00 Slabs	Comments:
70 SCALING/CRAZING	L	2.00 Slabs	Comments:
66 SMALL PATCH	L	2.00 Slabs	Comments:
63 LINEAR CRACKING	L	4.00 Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 698,250.00SqFt

Section: 6215 of 6 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-RW-AC Zone: Category: Rank: s
Area: 420,500.00SqFt Length: 4,205.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 105 Surveyed: 17

Conditions: PCI:28.00 |

Inspection Comments:

Sample Number: 304 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	2,499.98 SqFt	Comments:
43 BLOCK CRACKING	L	999.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 306 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	3,249.97 SqFt	Comments:
43 BLOCK CRACKING	L	500.00 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 311 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	749.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 316 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	749.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 321 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	749.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 326 Type: R Area: 5,000.00SqFt PCI = 36

Sample Comments:

43 BLOCK CRACKING	M	300.00 SqFt	Comments:
43 BLOCK CRACKING	L	999.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 331 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
43 BLOCK CRACKING	L	999.99 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:

Sample Number: 336 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98 SqFt	Comments:
-------------------	---	---------------	-----------

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 342 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98	SqFt	Comments:
43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 346 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	3,499.97	SqFt	Comments:
43 BLOCK CRACKING	L	500.00	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 351 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98	SqFt	Comments:
43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 360 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98	SqFt	Comments:
43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 365 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98	SqFt	Comments:
43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 371 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

43 BLOCK CRACKING	M	3,749.97	SqFt	Comments:
43 BLOCK CRACKING	L	749.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 377 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

43 BLOCK CRACKING	M	3,999.97	SqFt	Comments:
43 BLOCK CRACKING	L	500.00	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 380 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

43 BLOCK CRACKING	M	3,999.97	SqFt	Comments:
43 BLOCK CRACKING	L	500.00	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 383 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

43 BLOCK CRACKING	M	3,999.97	SqFt	Comments:
43 BLOCK CRACKING	L	500.00	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 698,250.00SqFt

Section: 6220 of 6 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-RW-AC Zone: Category: Rank: s
Area: 210,250.00SqFt Length: 8,410.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 53 Surveyed: 8

Conditions: PCI:28.00 |

Inspection Comments:

Sample Number: 106 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	3,249.97	SqFt	Comments:
43 BLOCK CRACKING	L	500.00	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 126 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98	SqFt	Comments:
43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 142 Type: R Area: 5,000.00SqFt PCI = 33

Sample Comments:

43 BLOCK CRACKING	M	500.00	SqFt	Comments:
43 BLOCK CRACKING	L	3,249.97	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 168 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,499.98	SqFt	Comments:
43 BLOCK CRACKING	L	1,499.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 510 Type: R Area: 5,000.00SqFt PCI = 33

Sample Comments:

43 BLOCK CRACKING	M	500.00	SqFt	Comments:
43 BLOCK CRACKING	L	2,999.98	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 534 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98	SqFt	Comments:
43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 560 Type: R Area: 5,000.00SqFt PCI = 27

Sample Comments:

43 BLOCK CRACKING	M	2,999.98	SqFt	Comments:
43 BLOCK CRACKING	L	999.99	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Sample Number: 576 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

43 BLOCK CRACKING	M	2,499.98	SqFt	Comments:
-------------------	---	----------	------	-----------

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

43	BLOCK CRACKING	L	1,999.98	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 698,250.00SqFt

Section: 6225 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s
Area: 30,000.00SqFt Length: 300.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Dat3/28/2011 Total Samples: 6 Surveyed: 2

Conditions: PCI:27.00 |

Inspection Comments:

Sample Number: 386 Type: R Area: 24.00Slabs PCI = 29

Sample Comments:

65 JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
74 JOINT SPALLING	L	17.00	Slabs	Comments:
70 SCALING/CRAZING	L	12.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	8.00	Slabs	Comments:
75 CORNER SPALLING	L	10.00	Slabs	Comments:
63 LINEAR CRACKING	L	5.00	Slabs	Comments:
75 CORNER SPALLING	M	4.00	Slabs	Comments:
74 JOINT SPALLING	M	7.00	Slabs	Comments:
63 LINEAR CRACKING	M	7.00	Slabs	Comments:
62 CORNER BREAK	L	1.00	Slabs	Comments:
75 CORNER SPALLING	H	1.00	Slabs	Comments:

Sample Number: 388 Type: R Area: 24.00Slabs PCI = 25

Sample Comments:

65 JOINT SEAL DAMAGE	H	24.00	Slabs	Comments:
70 SCALING/CRAZING	L	10.00	Slabs	Comments:
74 JOINT SPALLING	L	18.00	Slabs	Comments:
75 CORNER SPALLING	L	10.00	Slabs	Comments:
63 LINEAR CRACKING	H	2.00	Slabs	Comments:
74 JOINT SPALLING	M	7.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	7.00	Slabs	Comments:
63 LINEAR CRACKING	M	5.00	Slabs	Comments:
63 LINEAR CRACKING	L	4.00	Slabs	Comments:
62 CORNER BREAK	M	2.00	Slabs	Comments:
75 CORNER SPALLING	M	4.00	Slabs	Comments:
62 CORNER BREAK	L	1.00	Slabs	Comments:
75 CORNER SPALLING	L	1.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 698,250.00SqFt

Section: 6230 of 6 From: - To: - Last Const.: 1/1/1942
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: s
Area: 15,000.00SqFt Length: 600.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 3 Surveyed: 1

Conditions: PCI: 5.00 |

Inspection Comments:

Sample Number: 186 Type: R Area: 24.00Slabs PCI = 5

Sample Comments:

65 JOINT SEAL DAMAGE	M	24.00	Slabs	Comments:
75 CORNER SPALLING	L	4.00	Slabs	Comments:
63 LINEAR CRACKING	M	13.00	Slabs	Comments:
74 JOINT SPALLING	M	3.00	Slabs	Comments:
74 JOINT SPALLING	L	19.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
70 SCALING/CRAZING	L	5.00	Slabs	Comments:
63 LINEAR CRACKING	H	7.00	Slabs	Comments:
62 CORNER BREAK	L	1.00	Slabs	Comments:
63 LINEAR CRACKING	L	1.00	Slabs	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 324,450.00SqFt

Section: 205 of 3 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 277,550.00SqFt Length: 5,551.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 69 Surveyed: 6

Conditions: PCI: 25.00 |

Inspection Comments:

Sample Number: 103 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

43 BLOCK CRACKING	M	3,999.97 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,499.96 SqFt	Comments:
50 PATCHING	L	6.00 SqFt	Comments:

Sample Number: 113 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

43 BLOCK CRACKING	M	4,999.96 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Sample Number: 123 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

43 BLOCK CRACKING	M	4,999.96 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Sample Number: 133 Type: R Area: 5,000.00SqFt PCI = 23

Sample Comments:

43 BLOCK CRACKING	M	3,499.97 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	55.01 Ft	Comments:
50 PATCHING	M	4.00 SqFt	Comments:

Sample Number: 143 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

43 BLOCK CRACKING	M	4,999.96 SqFt	Comments:
52 WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Sample Number: 152 Type: R Area: 5,000.00SqFt PCI = 22

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	M	490.13 Ft	Comments:
52 WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:
43 BLOCK CRACKING	M	1,499.99 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	20.01 Ft	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 324,450.00SqFt

Section: 210 of 3 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 23,450.00SqFt Length: 469.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 6 Surveyed: 1
Conditions: PCI:26.00 |
Inspection Comments:

Sample Number: 201 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

50	PATCHING	M	150.00	SqFt	Comments:
43	BLOCK CRACKING	M	3,999.97	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,499.96	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 324,450.00SqFt

Section: 220 of 3 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 23,450.00SqFt Length: 469.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 6 Surveyed: 1
Conditions: PCI:22.00 |
Inspection Comments:

Sample Number: 301 Type: R Area: 5,000.00SqFt PCI = 22

Sample Comments:

50	PATCHING	M	150.00	SqFt	Comments:
43	BLOCK CRACKING	M	4,999.96	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,999.96	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 259,700.00SqFt

Section: 105 of 3 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 117,050.00SqFt Length: 2,341.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 29 Surveyed: 4

Conditions: PCI:26.00 |

Inspection Comments:

Sample Number: 102 Type: R Area: 5,000.00SqFt PCI = 32

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	500.13 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	63.02 Ft	Comments:
52	WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Sample Number: 108 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

43	BLOCK CRACKING	M	2,499.98 SqFt	Comments:
43	BLOCK CRACKING	L	1,999.98 SqFt	Comments:
52	WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Sample Number: 114 Type: R Area: 5,000.00SqFt PCI = 24

Sample Comments:

43	BLOCK CRACKING	M	3,499.97 SqFt	Comments:
43	BLOCK CRACKING	L	1,199.99 SqFt	Comments:
52	WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Sample Number: 120 Type: R Area: 5,000.00SqFt PCI = 21

Sample Comments:

43	BLOCK CRACKING	L	1,199.99 SqFt	Comments:
43	BLOCK CRACKING	M	3,599.97 SqFt	Comments:
52	WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:
50	PATCHING	M	3.00 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 259,700.00SqFt

Section: 110 of 3 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 132,650.00SqFt Length: 2,653.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 33 Surveyed: 4

Conditions: PCI:34.00 |

Inspection Comments:

Sample Number: 104 Type: R Area: 5,000.00SqFt PCI = 33

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	320.08	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	143.04	Ft	Comments:
52	WEATHERING/RAVELING	M	4,999.96	SqFt	Comments:

Sample Number: 110 Type: R Area: 5,000.00SqFt PCI = 43

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	12.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	150.04	Ft	Comments:
43	BLOCK CRACKING	M	2,399.98	SqFt	Comments:
52	WEATHERING/RAVELING	L	4,999.92	SqFt	Comments:

Sample Number: 116 Type: R Area: 5,000.00SqFt PCI = 24

Sample Comments:

43	BLOCK CRACKING	L	1,999.98	SqFt	Comments:
43	BLOCK CRACKING	M	2,599.98	SqFt	Comments:
52	WEATHERING/RAVELING	M	4,999.96	SqFt	Comments:

Sample Number: 122 Type: R Area: 5,000.00SqFt PCI = 33

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	249.06	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	200.05	Ft	Comments:
52	WEATHERING/RAVELING	M	4,999.96	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 259,700.00SqFt

Section: 115 of 3 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 10,000.00SqFt Length: 200.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 3 Surveyed: 1
Conditions: PCI:33.00 |
Inspection Comments:

Sample Number: 123 Type: R Area: 5,000.00SqFt PCI = 33

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	500.13 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	31.01 Ft	Comments:
52	WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW B1 Name: TAXIWAY B Use: TAXIWAY Area: 102,493.00SqFt

Section: 405 of 2 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 33,000.00SqFt Length: 660.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 4 Surveyed: 2

Conditions: PCI:34.00 |

Inspection Comments:

Sample Number: 101 Type: R Area: 5,000.00SqFt PCI = 34

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	400.10 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	320.08 Ft	Comments:
52	WEATHERING/RAVELING	M	4,799.96 SqFt	Comments:

Sample Number: 104 Type: R Area: 5,000.00SqFt PCI = 33

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	281.07 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	470.12 Ft	Comments:
52	WEATHERING/RAVELING	M	4,999.96 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW B1 Name: TAXIWAY B Use: TAXIWAY Area: 102,493.00SqFt

Section: 410 of 2 From: - To: - Last Const.: 1/1/1942
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 69,493.00SqFt Length: 1,270.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 1 Surveyed: 1
Conditions: PCI:28.00 |
Inspection Comments:

Sample Number: 187 Type: R Area: 10,000.00SqFt PCI = 28

Sample Comments:

50	PATCHING	M	6.00 SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	950.24 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	376.10 Ft	Comments:
52	WEATHERING/RAVELING	M	9,999.92 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TWC Name: TAXIWAY C Use: TAXIWAY Area: 105,875.00SqFt

Section: 310 of 2 From: 1+00 To: 17+00 Last Const.: 1/1/1998
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: s
Area: 56,000.00SqFt Length: 1,600.00Ft Width: 35.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 14 Surveyed: 2
Conditions: PCI: 89.00 |
Inspection Comments:

Sample Number: 102 Type: R Area: 3,724.00SqFt PCI = 98
Sample Comments:
52 WEATHERING/RAVELING L 30.00 SqFt Comments:

Sample Number: 109 Type: R Area: 4,137.00SqFt PCI = 82
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 219.06 Ft Comments:
52 WEATHERING/RAVELING L 50.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TWC Name: TAXIWAY C Use: TAXIWAY Area: 105,875.00SqFt

Section: 315 of 2 From: 1+00 To: 15+25 Last Const.: 1/1/2007
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: s
Area: 49,875.00SqFt Length: 1,425.00Ft Width: 35.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 18 Surveyed: 3
Conditions: PCI:94.00 |
Inspection Comments:

Sample Number: 102 Type: R Area: 3,500.00SqFt PCI = 95
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 40.01 Ft Comments:

Sample Number: 107 Type: R Area: 3,500.00SqFt PCI = 95
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 37.01 Ft Comments:

Sample Number: 201 Type: R Area: 3,500.00SqFt PCI = 91
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 70.02 Ft Comments:
52 WEATHERING/RAVELING L 10.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 5/17/2011

Site Name:

Network: IMM Name: IMMOKALEE AIRPORT

Branch: TW TO AP Name: TAXIWAY TO CROP AP Use: TAXIWAY Area: 31,500.00SqFt

Section: 305 of 1 From: - To: - Last Const.: 1/1/1987
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: T
Area: 31,500.00SqFt Length: 1,260.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 3/28/2011 Total Samples: 8 Surveyed: 2

Conditions: PCI:67.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 5,000.00SqFt PCI = 67

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	174.04 Ft	Comments:
52	WEATHERING/RAVELING	L	3,499.97 SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	29.01 Ft	Comments:

Sample Number: 103 Type: R Area: 5,000.00SqFt PCI = 67

Sample Comments:

43	BLOCK CRACKING	L	562.50 SqFt	Comments:
52	WEATHERING/RAVELING	L	3,499.97 SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	189.05 Ft	Comments: