

STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION OFFICE

Statewide Airfield Pavement Management Program

Kendall-Tamiami Executive Airport- TMB
(Regional Reliever)
Miami, Florida
(District 6)



TABLE OF CONTENTS

| | | PAGE NO. |
|-------|---|----------|
| _ | | ••• |
| | cutive Summary | |
| 1. | Introduction | |
| 2. | Network Definition and Pavement Inventory | |
| 3. | Pavement Condition | |
| 4. | Pavement Condition Prediction | |
| 5. | Maintenance Policies and costs | |
| 6. | Pavement Rehabilitation Needs Analysis | |
| 7. | Maintenance and Rehabilitation Plan | |
| 8. | Visual Aids | |
| 9. | Recommendations | 38 |
| LIST | Γ OF FIGURES | |
| Figu | re 1-1: Pavement Life Cycle | 4 |
| Figu | re 1-2: PCI Rating Scale | 6 |
| Figu | re 2-1: Pavement Area by Surface Type | 12 |
| | re 3-1: Network PCI Distribution by Rating Category | |
| | re 3-1a: Condition Rating Summary | |
| | re 3-2: Percentage of Pavement Area within Each PCI Range by Pavemen | |
| | re 4-1: Predicted PCI by Pavement Use | |
| _ | re 6-1: Budget Scenario Analysis | |
| LIST | Γ OF TABLES | |
| Table | e I: Condition Summary by Branch | iv |
| | e I: Condition Summary by Branch (Continued) | |
| | e II: Condition Summary by Pavement Use | |
| | e III: Condition Summary by Pavement Rank | |
| | e IV: Immediate Major M&R Needs | |
| | e V: 10-Year M&R Costs under Unlimited Funding Scenario | |
| Table | e 1-1: Sampling Rate for FDOT Condition Surveys | 5 |
| | e 2-1: Construction Since Last Inspection & Anticipated Construction Acti | |
| | e 2-2: Pavement Area by Pavement Use | • |
| | e 2-3: Branch and Section Inventory | |
| | e 2-3: Branch and Section Inventory (Continued) | |
| | e 2-3: Branch and Section Inventory (Continued) | |
| | e 3-1: Pavement Distresses for Asphalt Concrete Surfaces | |
| | e 3-2: Pavement Distresses for Portland Cement Concrete Surfaces | |
| | e 3-3: Condition by Pavement Use | |
| | e 5-1: Routine Maintenance Activities for Airfield Pavements | |
| | | |
| | e 5-2: Critical PCI for Regional Reliever Airports | |
| | e 5-3: FDOT Minimum Service Level PCI for Regional Reliever Airports. | |
| 1 aul | e 5-4: M&R Activities for Regional Reliever Airports | 20 |

TABLE OF CONTENTS

| | | PAGE NO. |
|---------------|--|----------|
| Table 5-5: Ma | aintenance Unit Costs for FDOT | 27 |
| | &R Activities and Unit Costs by Condition for Regional Relieve | |
| | mmary of Immediate Major M&R Needs Option No. 1 | - |
| | mmary of Immediate Major M&R Needs Option No. 2 | |
| | mmary of Year 1 Maintenance Activities | |
| | mmary of Year 1 Maintenance Activities (Continued) | |
| | mmary of Year 1 Maintenance Activities (Continued) | |
| | mmary of Year 1 Maintenance Activities (Continued) | |
| | &R Costs under Unlimited Funding Scenario | |
| 10010 / 11111 | | |
| APPENDIC | ES | |
| Appendix A | Network Definition Map | |
| | System Inventory Map | |
| | Pavement Inventory Table | |
| | Work History Report | |
| Appendix B | 2012 Condition Map | |
| | Pavement Condition Index Table | |
| Appendix C | Branch Condition Report | |
| | Section Condition Report | |
| Appendix D | Pavement Condition Prediction Table | |
| | Predicted PCI by Pavement Use Graph | |
| Appendix E | Year 1 Maintenance Activities Table | |
| Appendix F | Major M&R Plan by Year under Unlimited Funding Scenario | Γable |
| Appendix G | 10-Year M&R Map | |
| Appendix H | Photographs | |
| Appendix I | PCI Re-inspection Report | |

EXECUTIVE SUMMARY

In 2010, the Florida Department of Transportation (FDOT) Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, AMEC and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing Statewide Airfield Pavement Management Program (SAPMP) to be completed over fiscal years 2011 and 2012.

The tasks required to achieve this objective at Kendall-Tamiami Executive Airport included:

- ➤ Obtain recent construction history from the Airport to update the Pavement Inventory CADD drawings from the previous SAPMP update,
- ➤ Perform a visual Pavement Condition Index (PCI) survey of the airfield pavements at the Airport,
- ➤ Update the MicroPAVER database to analyze the PCI field data and determine the current condition of the airfield pavements,
- > Predict the future deterioration of the pavements,
- ➤ Develop a 10-year M&R plan to address the pavement needs at Kendall-Tamiami Executive Airport, and
- ➤ Provide the estimated costs associated with the suggested immediate and future M&R activities

During March 2012, the PCI survey was performed at Kendall-Tamiami Executive Airport. The results of the survey indicate that, based on a numerical scale of 0 to 100, the overall area-weighted average PCI of the airfield pavements in 2012 is 86, representing a Good overall network condition.

Table I below summarizes the overall condition summary by network branch.

Table I: Condition Summary by Branch

| Branch Name | Area Weighted PCI | PCI Range | Condition Rating | FDOT Minimum Service Level | MicroPAVER Minimum PCI | Action Required |
|----------------------------|-------------------------|--------------|---------------------|----------------------------------|------------------------------|--------------------|
| North Apron | 86 | 64 - 91 | Good | 65 | 65 | X |
| Northeast Apron | 86 | 81 - 95 | Good | 65 | 65 | |
| South Apron | 81 | 35 - 86 | Satisfactory | 65 | 65 | X |
| Southeast Apron | 65 | 65 | Fair | 65 | 65 | |
| Runway 13-31 | 90 | 90 - 91 | Good | 75 | 65 | |
| Runway 9L-27R | 91 | 90 - 96 | Good | 75 | 65 | |
| Runway 9R-27L | 90 | 86 - 100 | Good | 75 | 65 | |
| Taxiway 1 | 94 | 94 | Good | 65 | 65 | |
| Taxiway 2 | 91 | 91 | Good | 65 | 65 | |
| Taxiway 3 | 96 | 96 | Good | 65 | 65 | |
| Taxiway 4 | 94 | 94 | Good | 65 | 65 | |
| Taxiway 5 | 89 | 89 | Good | 65 | 65 | |
| Taxiway 6 | 91 | 91 | Good | 65 | 65 | |
| Taxiway 7 | 92 | 92 | Good | 65 | 65 | |
| Taxiway Alpha | 93 | 79 - 100 | Good | 65 | 65 | |
| Taxiway A-1 | 97 | 97 | Good | 65 | 65 | |
| Taxiway A-2 | 95 | 95 | Good | 65 | 65 | |
| Taxiway A-3 | 92 | 92 - 93 | Good | 65 | 65 | |
| Taxiway to Northeast Apron | 78 | 78 | Satisfactory | 65 | 65 | |
| Taxiway to Southeast Apron | 89 | 89 | Good | 65 | 65 | |
| Taxiway Charlie | 86 | 86 | Good | 65 | 65 | |
| Taxiway C-1 | 72 | 72 | Satisfactory | 65 | 65 | |
| Taxiway C-2 | 78 | 78 | Satisfactory | 65 | 65 | |
| Taxiway CC | 78 | 78 | Satisfactory | 65 | 65 | |
| Taxiway Delta | 58 | 47 - 94 | Fair | 65 | 65 | X |
| Taxiway D-1 | 56 | 56 | Fair | 65 | 65 | X |
| Taxiway D-2 | 53 | 53 | Poor | 65 | 65 | X |
| Taxiway Echo | 96 | 91 - 100 | Good | 65 | 65 | |
| Taxiway E-1 | 94 | 91 - 100 | Good | 65 | 65 | |
| Taxiway E-2 | 83 | 83 | Satisfactory | 65 | 65 | |
| Taxiway E-3 | 83 | 83 | Satisfactory | 65 | 65 | |
| Taxiway E-4 | 87 | 87 | Good | 65 | 65 | |

Table I: Condition Summary by Branch (Continued)

| Branch Name | Area Weighted PCI | PCI Range | Condition Rating | FDOT Minimum Service Level | MicroPAVER Minimum PCI | Action Required |
|-----------------|-------------------------|--------------|---------------------|----------------------------------|------------------------------|--------------------|
| Taxiway E-5 | 92 | 92 - 93 | Good | 65 | 65 | |
| Taxiway Foxtrot | 93 | 93 | Good | 65 | 65 | |
| Taxiway Golf | 94 | 91 - 96 | Good | 65 | 65 | |
| Taxiway Hotel | 91 | 91 | Good | 65 | 65 | |
| Taxiway H-1 | 91 | 91 | Good | 65 | 65 | |
| Taxiway H-2 | 85 | 85 | Satisfactory | 65 | 65 | |
| Taxiway H-3 | 88 | 88 | Good | 65 | 65 | |
| Taxiway H-4 | 100 | 100 | Good | 65 | 65 | |
| Taxiway H-5 | 91 | 91 | Good | 65 | 65 | |
| Taxiway H-6 | 93 | 93 | Good | 65 | 65 | |
| Taxiway H-7 | 94 | 94 | Good | 65 | 65 | |

Tables II and III below illustrate the area-weighted PCI computed individually for each pavement use and rank, respectively.

Table II: Condition Summary by Pavement Use

| Use | Average Area- Weighted PCI | Condition Rating |
|----------------|-------------------------------|------------------|
| Runway | 90 | Good |
| Taxiway | 86 | Good |
| Apron | 83 | Satisfactory |
| All (Weighted) | 86 | Good |

Table III: Condition Summary by Pavement Rank

| Rank* | Average Area- Weighted PCI | Condition Rating |
|----------------|-------------------------------|------------------|
| Primary | 86 | Satisfactory |
| Tertiary | 62 | Fair |
| All (Weighted) | 86 | Good |

^{*}The pavement rank for the airport pavement network is listed on Table 2-3.

The immediate M&R needs, or needs that have been programmed to be completed in the first year of the 10-year M&R plan based on an unlimited budget at Kendall-Tamiami Executive Airport, include: Taxiway Delta and portions of the North and South Aprons within the T-Hangar areas. The immediate needs are summarized in Table IV below.

Table IV: Immediate Major M&R Needs

| Branch Name | Section ID | Surface Type | Section Area (ft²) | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------------|---------------|-----------------|-----------------------|---------------------|----------------------|------------------|------------------|
| North Apron | 4225 | AC | 69,490 | \$178,450.31 | 64 | Mill and Overlay | 100 |
| South Apron | 4125 | AC | 35,371 | \$110,498.16 | 62 | Mill and Overlay | 100 |
| South Apron | 4130 | AC | 19,714 | \$258,061.25 | 35 | Reconstruction | 100 |
| South Apron | 4135 | AC | 29,788 | \$121,327.74 | 59 | Mill and Overlay | 100 |
| Taxiway Delta | 405 | AC | 210,898 | \$1,604,932.90 | 47 | Mill and Overlay | 100 |
| Taxiway D-1 | 415 | AC | 50,475 | \$265,094.71 | 56 | Mill and Overlay | 100 |
| Taxiway D-2 | 420 | AC | 50,463 | \$324,527.06 | 53 | Mill and Overlay | 100 |
| | | | Total | \$2,862,892.13 | 54 | | 100 |

^{*} Costs are adjusted for inflation.

A forecast of Major M&R needs for a 10-year period, starting from 2012, was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval. The results of this analysis are provided in Table V below.

Table V: 10-Year M&R Costs under Unlimited Funding Scenario

| Year | Preventative | Major M&R | Total Year Cost |
|-------|----------------|----------------|-----------------|
| 2012 | \$227,635.95 | \$2,862,892.13 | \$3,090,528.08 |
| 2013 | \$317,033.06 | \$119,608.70 | \$436,641.76 |
| 2014 | \$442,042.84 | \$189,216.97 | \$631,259.81 |
| 2015 | \$580,827.62 | \$0.00 | \$580,827.62 |
| 2016 | \$723,255.67 | \$0.00 | \$723,255.67 |
| 2017 | \$883,425.04 | \$0.00 | \$883,425.04 |
| 2018 | \$1,036,746.05 | \$0.00 | \$1,036,746.05 |
| 2019 | \$1,206,371.41 | \$0.00 | \$1,206,371.41 |
| 2020 | \$1,384,189.92 | \$0.00 | \$1,384,189.92 |
| 2021 | \$1,518,954.53 | \$366,896.97 | \$1,885,851.50 |
| Total | \$8,320,482.09 | \$3,538,614.77 | \$11,859,096.86 |

Note: Costs are adjusted for inflation.

The implementation of the 10-Year Major M&R Plan is expected to provide an improvement in the overall condition of the airfield pavement, where the area-weighted PCI would only decrease from 86 in 2012 to 73 in 2021. Appendix F lists the Major M&R for the 10-Year program. Appendix G graphically depicts the program activity.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all Kendall-Tamiami Executive Airport pavements in 2021 may remain near 73. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for Kendall-Tamiami Executive Airport is conducted at some point in the 10-year plan.

1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. There are millions of square yards of pavement for the runways, taxiways, aprons and other areas of these airports that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time.

In order to support the planning, scheduling, and design of the M&R activities based on pavement evaluation and pavement management performance trends, the Florida Department of Transportation (FDOT) Aviation Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992.

In 2010, the FDOT Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

This report discusses the work performed, a summary of the findings, results, and recommendations for M&R planning associated with the update to the SAPMP. It also describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented during the performance of the SAPMP.

1.1 Purpose

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the SAPMP and the roles and responsibilities of the program's participants;
- Provide background information on pavement management principles, objectives, and benefits to this airport;
- Outline the procedures used to collect, evaluate and report pavement inspection results at this airport;
- Present the findings from the pavement inspection;
- Analyze and discuss the needs for Maintenance and Rehabilitation (M&R) activities and associated costs for this airport.

1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The 1992 SAPMP provided valuable information for establishing and performing pavement M&R.

In 1992/1993, and 1998/1999, the FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement

maintenance. This system, AIRPAV, was implemented, and initial condition surveys were performed in 1992 and 1993. The SAPMP was updated with additional surveys in 1998 and 1999.

In 2004, the FDOT Aviation Office undertook a project to update the pavement management system software utilized for the SAPMP. This project involved a review of the AIRPAV software and other available pavement management system software. As a result of this review, MicroPAVER was selected as the software for the update project. Data from the 1998/1999 condition surveys were converted to the MicroPAVER system, and the inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999. The pavements were inspected between 2006 and 2008, and an updated M&R program was developed based on the new condition of the airfield pavements. As part of the update, procedures for the inspection and collection of pavement data were developed, and a website (www.floridaairportpavement.com) was created for the input of data under secure procedures.

Currently, airports using the AIP Grant Program are required by the Federal Aviation Administration (FAA) to develop a pavement maintenance program (FAA/AC 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements") using trained personnel to perform a detailed inspection of airfield pavements. The inspections are required to be performed at least once a year or every 3 years if pavement inspection is characterized in the form of a Pavement Condition Index (PCI) survey (such as ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys", (2004 edition)). The 2004 edition was utilized in lieu of the 2010 edition to maintain database integrity and benefit of pavement performance curves from the previous inspections.

In 2010, the FDOT Aviation Office selected a team consisting of the Consultant and their Subconsultants to provided services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

1.3 Organization

1.3.1 Aviation Office Program Manager Role

The Aviation Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) monitoring the work of the Consultant. The AO-PM has review and approval authority for each program task and also manages the day-to-day details of the SAPMP and the updates.

1.3.2 Consultant Role

The Consultant (Kimley-Horn and Associates, Inc.) and their Subconsultants (AMEC Engineering and Consulting and All About Pavements, Inc.) provide technical and administrative assistance to the AO-PM during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the SAPMP based upon procedures outlined in FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

1.3.3 Airport Role

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP update, indicate any construction activity that has been performed since the previous inspections.

1.4 Pavement Types and Pavement Management

1.4.1 Pavement basics

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of an asphalt concrete (AC) surface, and
- Rigid pavement composed of a Portland Cement Concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying natural subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland Cement Concrete supports most of the load, and the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the construction of the concrete surface.

A small percentage of the airport pavements in Florida are composed of asphalt concrete surface over Portland Cement Concrete (APC). This pavement type is known as "composite" pavement.

Due to the different nature of the pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

1.4.2 Pavement Management System Concept

The SAPMP utilized a Pavement Management System (PMS) to develop the M&R recommendations discussed in this report. A PMS is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1 below, taken from FAA/AC 5380-7A "Airport Pavement Management Program", illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in "good" condition depends on how well it is maintained. As the illustration demonstrates, the cost of maintaining the pavement above a critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.




Figure 1-1: Pavement Life Cycle

Source: FAA/AC 150/5380-7A "Airport Pavement Management Program" *Modified to reflect current construction costs.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi-year M&R plan can be determined.

1.4.3 Pavement Inspection Methodology for the SAPMP

Pavement condition assessment is one of the primary decision variables in any airport PMS. Pavement condition assessments generally include visual surveys in accordance with ASTM D 5340, "Standard Test Method for Airport Pavement Condition Index Surveys" and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the Statewide Aviation Pavement Management Program update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine the appropriate rehabilitation methods during the design process.

In preparation of the PCI surveys, the airfield pavements are divided into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Further discussion of how the airport pavements are divided and subdivided into units by construction and use can be found in Section 2 "Network Definition and Pavement Inventory" of this report.

Sample unit sizes are approximately 5000 ± 2000 square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements. Prior to conducting the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of Branches, Sections, use patterns, construction types and history. The sampling rate used for the FDOT Statewide Airfield Pavement Management Program is provided in Table 1-1 below.

Table 1-1: Sampling Rate for FDOT Condition Surveys

| | AC Pavemen | ts | | PCC Paveme | ents | |
|-------|------------------------|-------------|-------------|------------------------|-------------|--|
| NI | n | | 7.4 | n | | |
| N | Runway | Others | N | Runway | Others | |
| 1-4 | 1 | 1 | 1-3 | 1 | 1 | |
| 5-10 | 2 | 1 | 4-6 | 2 | 1 | |
| 11-15 | 3 | 2 | 7-10 | 3 | 2 | |
| 16-30 | 5 | 3 | 11-15 | 4 | 2 | |
| 31-40 | 7 | 4 | 16-20 | 5 | 3 | |
| 41-50 | 8 | 5 | 21-30 | 7 | 3 | |
| ≥51 | 20% but <u><</u> 20 | 10% but ≤10 | 31-40 | 8 | 4 | |
| | | | 41-50 | 10 | 5 | |
| | | | <u>≥</u> 51 | 20% but <u><</u> 20 | 10% but ≤10 | |

Where

N = total number of sample units in Section

n = number of sample units to inspect

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the Section. In the case when nonrepresentive distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each Section. PCI values range from 0 to 100. As Figure 1-2 below indicates, MicroPAVER provides a rating scale that relates PCI to pavement condition. A PCI between 0 and 10 is considered 'Failed' pavement, and a PCI between 86 and 100 is considered 'Good' pavement, with five other conditions for PCI values between 11 and 85.

Figure 1-2: PCI Rating Scale

| PCI | Condition Rating |
|----------|------------------|
| 86 – 100 | Good |
| 71 – 85 | Satisfactory |
| 56 – 70 | Fair |
| 41 – 55 | Poor |
| 26 - 40 | Very Poor |
| 11 – 25 | Serious |
| 0 – 10 | Failed |

1.5 Definitions

<u>Aviation Office</u> - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office Program Manager (AO-PM) has review and approval authority for each program task of the SAPMP.

<u>Base Course</u> - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

<u>Branch</u> - A Branch designates pavements that have common usage and functionality, such as an entire runway, taxiway, or apron.

<u>Branch ID</u> - A short form identification for the pavement Branch. In this report, Branch includes the common designation for the item e.g. RW 18-36.

<u>Category</u> - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA for general aviation or community airports;
- RL for regional relievers or small hubs;
- PR for primary (certified under Part 139 requirements).

<u>Critical PCI</u> - The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

<u>Distress Type</u> - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland Cement Concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

<u>Florida DOT (FDOT)</u> - Florida Department of Transportation was represented in this project by the Office of Aviation.

<u>Global M&R</u> - Global M&R is defined as activities applied to entire pavement Sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

<u>Localized M&R (Maintenance and Repair)</u> - Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

<u>Major M&R (e.g. Rehabilitation)</u> - Activities performed over the entire area of a pavement Section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

<u>MicroPAVER</u> - A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that, if properly implemented, maintained, and operated, it meets the pavement management program requirements described by the FAA in Advisory Circular 150/5380-7A.

<u>Minimum Condition Level</u> - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

<u>Network Definition</u> - A Network Definition is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport is in Appendix A along with a table of inventory data.

<u>Pavement Condition Index (PCI)</u> - The Pavement Condition Index is a number which represents the condition of a pavement segment at a specific point in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340, published by ASTM International.

<u>Pavement Evaluation</u> - A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

<u>Pavement Management System (PMS)</u> - A Pavement Management System is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

<u>Pavement Surface Type</u> - The surface of pavement is identified as one of four types:

- AC for asphalt surface pavements;
- PCC for Portland Cement Concrete pavements;
- AAC for asphalt surface pavements that have had an asphalt overlay at some point in their construction history;
- APC for composite pavements, which consist of asphalt over Portland Cement Concrete pavement.
- PAC for composite pavements, which consist of Portland Cement Concrete over asphalt pavement.

<u>Rank</u> - Pavement rank in MicroPAVER determines the priority to be assigned to a pavement Section when developing an M&R plan. Pavement Sections are ranked as follows according to their use:

- P for Primary pavements, such as primary runways, primary taxiways, and primary aprons;
- S or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons;
- T for Tertiary pavements such as "T" hangars and slightly used aprons.

<u>Reconstruction</u> - Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

<u>Rehabilitation</u> - Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

<u>Sample Unit</u> - Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are $5,000 \pm 2,000$ square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements.

<u>Section</u> - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition, and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

<u>Section ID</u> - A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series Sections are taxiways, 4000 and 5000 series Sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series Sections are runways.

<u>Statewide Airfield Pavement Management Program (SAPMP)</u> – The Statewide Airfield Pavement Management Program is a program implemented in 1992 by the Florida Department of Transportation to plan, schedule, and design the maintenance and rehabilitation activities

necessary for the airfield pavement on Florida's public airports to allow the airports to operate efficiently, economically, and without excessive down time.

<u>System Inventory</u> - A System Inventory is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline and identifies airfield construction activities since the last inspection. The System Inventory for the airport is included in Appendix A.

<u>Use</u> - In MicroPAVER, Use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

2. NETWORK DEFINITION AND PAVEMENT INVENTORY

Kendall-Tamiami Executive Airport (TMB) consists of three runways; Runway 9R-27L which is 150-ft wide by 5,999-ft long, Runway 9L-27R which is 150-ft wide by 5,003-ft long, and Runway 13-31 which is 150-ft wide by 4,001-ft long. The western 1,200-ft of Runway 9R-27L was not inspected due to recent construction. Parallel taxiways Alpha, Delta and Echo area all 50-ft in width and are used to navigate throughout the airfield along with their associated taxiway connectors. The aprons are situated between Runways 9R-27L and 9L-27R. All of the runways and taxiways are constructed out of asphalt concrete pavement, with the only portland cement concrete pavement sections being located within the aprons. This airport is designated as a Regional Reliever airport and is located in District 6 of the Florida Department of Transportation.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric dimensions may vary slightly from the geometry used in the condition and M & R analysis based on field measurements.

Kendall-Tamiami Executive Airport was established in 1967. It is owned and operated by Miami-Dade County. The airport is one of the busiest general aviation airports in Florida. It acts as a reliever to Miami International Airport and serves corporate and recreational needs in South Florida.

2.1 Network Definition

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units.

2.1.1 Branch Section Identification

The airport pavement network is subdivided into separate Branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then further divided into Sections with similar pavement construction and performance that may share other common attributes.

Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage. A pavement rank, consisting of primary, secondary, and tertiary levels, is assigned to each Section based on their level and type of use. The pavement rankings that were designated for each Section in the previous SAPMP update were again used for this update.

As discussed in Section 1.4.3 "Pavement Inspection Methodology for the SAPMP", the sections are sub-divided into sample units, which are the smallest subdivision in a pavement network, only for the purpose of conducting the pavement condition survey.

2.1.2 System Inventory and Network Definition Update

The System Inventory and Network Definition drawings are used to identify changes in the network since the most recent update from the 2006/2008 inspections and also to plan the field inspection activities for the 2012 survey. Prior to the field inspection process, the System Inventory drawing was updated from the previous inspection with notes indicating recent

construction projects on the various Sections of pavement throughout the airfield. This System Inventory drawing is used to update the Network Definition drawing.

The Network Definition drawing shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The previous airport configuration and history was compared with the current airport configuration, and the existing network branch, section and sample unit designations were revised to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important historical record.

Due to recent and anticipate construction history; pavement area sections may have been consolidated or created which will affect the total number of sample units to be inspected based on the ASTM 5340 criteria.

The updated System Inventory and Network Definition drawings for Kendall-Tamiami Executive Airport are provided in Appendix A. Table 2-1 below lists the recent construction projects at the airport.

Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity

| Construction Year | Location | Work Type/Pavement Section |
|----------------------|------------------------------|-------------------------------------|
| 2011 | Runway 9R-27L & Taxiway Echo | 1,000' Runway and Taxiway Extension |

2.2 Pavement Inventory

The detailed pavement inventory was updated to reflect the network definition update and field inspection results. The total number of sample units designated to be inspected at the airport is 238 sample units.


The total airfield pavement area in 2012 at Kendall-Tamiami Executive Airport is 7,217,438 square feet. The breakdown of pavement area for each pavement use is provided in Table 2-2.

Table 2-2: Pavement Area by Pavement Use

| Use | Area (ft ²) | % of Total Area |
|----------------|-------------------------|-----------------|
| Runway | 2,250,750 | 31% |
| Taxiway | 2,299,565 | 32% |
| Apron | 2,667,123 | 37% |
| All (Weighted) | 7,217,438 | 100% |

Figure 2-1 presents the breakdown of the pavement area at Kendall-Tamiami Executive Airport by surface type.

Figure 2-1: Pavement Area by Surface Type



Details of pavement Branch and Section information including Branch name (which indicates pavement use), Branch ID, Section ID, section area, rank, surface type, last construction date, number of samples inspected, and number of samples in each Section are given in Table 2-3 below. A more detailed Pavement Inventory Table may be found in Appendix A of this report.

Table 2-3: Branch and Section Inventory

| Branch Name | Branch ID | Section ID | True Area (ft²) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Sample Units in Section |
|-----------------|-----------|---------------|-----------------------|-----------------|-----------------|------------------------|-------------------------------|-------------------------------|
| North Apron | AP N | 4205 | 840,000 | P | AAC | 1/1/2006 | 16 | 168 |
| North Apron | AP N | 4215 | 60,000 | P | AAC | 1/1/2006 | 2 | 12 |
| North Apron | AP N | 4220 | 109,500 | P | AAC | 1/1/1994 | 3 | 24 |
| North Apron | AP N | 4225 | 69,490 | P | AC | 12/25/1999 | 3 | 20 |
| North Apron | AP N | 4230 | 18,795 | P | AC | 12/25/1999 | 1 | 3 |
| Northeast Apron | AP NE | 4305 | 9,600 | P | PCC | 12/25/1999 | 1 | 3 |
| Northeast Apron | AP NE | 4310 | 19,797 | P | AC | 12/25/1999 | 1 | 5 |
| Northeast Apron | AP NE | 4315 | 21,176 | P | AC | 12/25/1999 | 1 | 5 |
| Northeast Apron | AP NE | 4320 | 9,216 | P | PCC | 12/25/1999 | 1 | 3 |
| Northeast Apron | AP NE | 4325 | 49,524 | P | AC | 12/25/1999 | 2 | 12 |
| Northeast Apron | AP NE | 4330 | 2,700 | P | PCC | 12/25/1999 | 1 | 1 |
| South Apron | AP S | 4105 | 210,000 | P | AC | 1/1/1998 | 5 | 42 |
| South Apron | AP S | 4110 | 240,843 | P | AAC | 1/1/1998 | 5 | 48 |
| South Apron | AP S | 4115 | 832,515 | P | AAC | 1/1/1998 | 10 | 168 |
| South Apron | AP S | 4125 | 35,371 | T | AC | 12/25/1999 | 1 | 7 |
| South Apron | AP S | 4130 | 19,714 | P | AC | 12/25/1999 | 1 | 6 |
| South Apron | AP S | 4135 | 29,788 | P | AC | 12/25/1999 | 1 | 8 |
| South Apron | AP S | 4140 | 43,874 | P | AC | 12/25/1999 | 3 | 16 |
| Southeast Apron | AP SE | 4410 | 45,220 | P | AC | 12/25/1999 | 2 | 8 |
| Runway 13-31 | RW 13-31 | 6205 | 400,200 | P | AAC | 1/1/2004 | 16 | 80 |
| Runway 13-31 | RW 13-31 | 6210 | 200,100 | P | AAC | 1/1/2004 | 7 | 40 |
| Runway 9L-27R | RW 9L-27R | 6104 | 20,000 | P | AC | 1/1/2001 | 1 | 4 |
| Runway 9L-27R | RW 9L-27R | 6105 | 460,000 | P | AC | 1/1/2001 | 19 | 92 |
| Runway 9L-27R | RW 9L-27R | 6109 | 10,000 | P | AC | 1/1/2001 | 1 | 2 |
| Runway 9L-27R | RW 9L-27R | 6110 | 230,000 | P | AC | 1/1/2001 | 8 | 46 |
| Runway 9L-27R | RW 9L-27R | 6126 | 10,100 | P | AC | 1/1/2001 | 1 | 2 |
| Runway 9L-27R | RW 9L-27R | 6131 | 20,200 | P | AC | 1/1/2001 | 1 | 4 |
| Runway 9R-27L | RW 9R-27L | 6302 | 100,000 | P | AC | 1/1/2012 | 5 | 20 |
| Runway 9R-27L | RW 9R-27L | 6304 | 20,000 | P | AAC | 1/1/2012 | 1 | 4 |
| Runway 9R-27L | RW 9R-27L | 6305 | 460,000 | P | AAC | 1/1/1997 | 19 | 92 |
| Runway 9R-27L | RW 9R-27L | 6306 | 20,100 | P | AC | 1/1/1997 | 1 | 4 |
| Runway 9R-27L | RW 9R-27L | 6307 | 50,000 | P | AC | 1/1/2012 | 2 | 10 |

Table 2-3: Branch and Section Inventory (Continued)

| Branch Name | Branch ID | Section ID | True Area (ft²) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Sample Units in Section |
|---------------------|-----------|---------------|-----------------------|-----------------|-----------------|------------------------|-------------------------------|-------------------------------|
| Runway 9R-27L | RW 9R-27L | 6309 | 10,000 | P | AAC | 1/1/2012 | 1 | 2 |
| Runway 9R-27L | RW 9R-27L | 6310 | 230,000 | P | AAC | 1/1/1997 | 8 | 46 |
| Runway 9R-27L | RW 9R-27L | 6311 | 10,050 | P | AC | 1/1/1997 | 1 | 2 |
| Taxiway 1 | TW 1 | 270 | 12,843 | P | AAC | 1/1/2006 | 1 | 2 |
| Taxiway 2 | TW 2 | 260 | 19,697 | P | AAC | 1/1/2006 | 1 | 4 |
| Taxiway 3 | TW 3 | 250 | 19,697 | P | AAC | 1/1/2006 | 1 | 4 |
| Taxiway 4 | TW 4 | 240 | 19,697 | P | AAC | 1/1/2006 | 1 | 4 |
| Taxiway 5 | TW 5 | 230 | 19,697 | P | AAC | 1/1/2006 | 1 | 4 |
| Taxiway 6 | TW 6 | 220 | 19,697 | P | AAC | 1/1/2006 | 1 | 4 |
| Taxiway 7 | TW 7 | 210 | 18,557 | P | AAC | 1/1/2005 | 1 | 4 |
| Taxiway Alpha | TW A | 105 | 279,576 | P | AAC | 1/1/2005 | 10 | 56 |
| Taxiway Alpha | TW A | 108 | 18,500 | P | AAC | 1/1/2005 | 1 | 4 |
| Taxiway Alpha | TW A | 110 | 36,180 | P | AC | 1/1/2001 | 1 | 7 |
| Taxiway Alpha | TW A | 111 | 27,392 | P | AC | 12/25/1999 | 1 | 6 |
| Taxiway A-1 | TW A1 | 115 | 50,475 | P | AC | 1/1/2001 | 2 | 14 |
| Taxiway A-2 | TW A2 | 120 | 50,475 | P | AC | 1/1/2001 | 2 | 14 |
| Taxiway A-3 | TW A3 | 124 | 26,792 | P | AC | 12/25/1999 | 1 | 6 |
| Taxiway A-3 | TW A3 | 125 | 32,146 | P | AC | 1/1/2001 | 2 | 6 |
| Taxiway to NE Apron | TW AP NE | 1005 | 44,691 | P | AC | 12/25/1999 | 2 | 13 |
| Taxiway to SE Apron | TW AP SE | 1105 | 42,727 | P | AC | 12/25/1999 | 1 | 10 |
| Taxiway Charlie | TW C | 910 | 138,069 | P | AC | 1/1/1998 | 3 | 27 |
| Taxiway C-1 | TW C1 | 310 | 17,644 | P | AAC | 1/1/1997 | 1 | 5 |
| Taxiway C-2 | TW C2 | 320 | 17,567 | P | AAC | 1/1/1997 | 1 | 5 |
| Taxiway CC | TW CC | 905 | 7,838 | P | AC | 1/1/1998 | 1 | 2 |
| Taxiway Delta | TW D | 405 | 210,898 | P | AC | 1/1/2001 | 5 | 43 |
| Taxiway Delta | TW D | 410 | 36,142 | P | AC | 1/1/2001 | 1 | 7 |
| Taxiway Delta | TW D | 411 | 27,092 | P | AC | 1/1/2001 | 1 | 6 |
| Taxiway Delta | TW D | 412 | 10,004 | P | AC | 1/1/2001 | 1 | 2 |
| Taxiway D-1 | TW D1 | 415 | 50,475 | P | AC | 1/1/2001 | 2 | 14 |
| Taxiway D-2 | TW D2 | 420 | 50,463 | P | AC | 1/1/2001 | 2 | 14 |
| Taxiway Echo | TW E | 503 | 56,119 | P | AC | 1/1/2012 | 1 | 11 |
| Taxiway Echo | TW E | 505 | 238,386 | P | AAC | 1/1/2007 | 5 | 47 |

Table 2-3: Branch and Section Inventory (Continued)

| Branch Name | Branch ID | Section ID | True Area (ft²) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Sample Units in Section |
|-----------------|-----------|---------------|-----------------------|-----------------|-----------------|------------------------|-------------------------------|-------------------------------|
| Taxiway Echo | TW E | 507 | 30,930 | P | AAC | 1/1/2007 | 1 | 7 |
| Taxiway Echo | TW E | 510 | 32,263 | P | AAC | 1/1/2007 | 1 | 7 |
| Taxiway Echo | TW E | 513 | 54,092 | P | AC | 1/1/2012 | 2 | 12 |
| Taxiway E-1 | TW E1 | 515 | 21,049 | P | AAC | 1/1/2012 | 1 | 4 |
| Taxiway E-1 | TW E1 | 516 | 38,835 | P | AC | 12/25/1999 | 1 | 8 |
| Taxiway E-2 | TW E2 | 520 | 50,474 | P | AAC | 1/1/2007 | 3 | 14 |
| Taxiway E-3 | TW E3 | 525 | 41,823 | P | AAC | 1/1/2007 | 3 | 11 |
| Taxiway E-4 | TW E4 | 527 | 26,267 | P | AC | 1/1/1996 | 1 | 7 |
| Taxiway E-5 | TW E5 | 529 | 26,192 | P | AC | 12/25/1999 | 1 | 6 |
| Taxiway E-5 | TW E5 | 530 | 32,146 | P | AAC | 1/1/1999 | 2 | 6 |
| Taxiway Foxtrot | TW F | 605 | 57,730 | P | AAC | 1/1/1998 | 3 | 12 |
| Taxiway Golf | TW G | 705 | 51,622 | P | AAC | 1/1/2006 | 2 | 10 |
| Taxiway Golf | TW G | 710 | 17,106 | P | AC | 1/1/1997 | 1 | 3 |
| Taxiway Hotel | TW H | 815 | 119,042 | P | AAC | 1/1/2007 | 3 | 25 |
| Taxiway H-1 | TW H1 | 805 | 4,802 | P | AC | 1/1/1998 | 1 | 1 |
| Taxiway H-2 | TW H2 | 810 | 7,744 | P | AC | 1/1/1998 | 1 | 2 |
| Taxiway H-3 | TW H3 | 330 | 18,456 | P | AAC | 1/1/2007 | 1 | 4 |
| Taxiway H-4 | TW H4 | 340 | 17,255 | P | AAC | 1/1/2007 | 1 | 4 |
| Taxiway H-5 | TW H5 | 350 | 19,697 | P | AAC | 1/1/2007 | 1 | 4 |
| Taxiway H-6 | TW H6 | 360 | 19,697 | P | AAC | 1/1/2007 | 1 | 4 |
| Taxiway H-7 | TW H7 | 370 | 12,809 | P | AAC | 1/1/2007 | 1 | 2 |

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

3. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340-04 "Standard Practice for Airport Pavement Condition Index Surveys." These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

3.1 Inspection Methodology

A PCI survey is performed by measuring the amount and severity of pavement distresses, which are caused by traffic load, climate, and other factors, observed within a sample unit. This data is imported into MicroPAVER, which calculates PCI values for the pavement sections. Tables 3-1 and 3-2 below list the pavement distress types and related causes for asphalt concrete (AC) and Portland Cement Concrete (PCC), respectively.

Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces

| Code | Distress | Mechanism | | | | |
|-------------|---|----------------------------------|--|--|--|--|
| 41 | Alligator Cracking | Load | | | | |
| 42 | Bleeding | Construction Quality/ Mix Design | | | | |
| 43 | Block Cracking | Climate / Age | | | | |
| 44 | Corrugation | Load / Construction Quality | | | | |
| 45 | Depression | Subgrade Quality | | | | |
| 46 | Jet Blast | Aircraft | | | | |
| 47 | Joint Reflection - Cracking | Climate / Prior Pavement | | | | |
| 48 | Longitudinal/Transverse Cracking | Climate / Age | | | | |
| 49 | Oil Spillage | Aircraft / Vehicle | | | | |
| 50 | Patching | Utility / Pavement Repair | | | | |
| 51 | Polished Aggregate | Load | | | | |
| 52 | Weathering/Raveling | Climate / Load | | | | |
| 53 | Rutting | Load | | | | |
| 54 | Shoving | Pavement Growth | | | | |
| 55 | Slippage Cracking | Load / Pavement Bond | | | | |
| 56 | Swelling | Climate / Subgrade Quality | | | | |
| Source: U.S | Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual | | | | | |

Table 3-2: Pavement Distresses for Portland Cement Concrete Surfaces

| Code | Distress | Mechanism |
|--------------|-------------------------------|-----------------------------|
| 61 | Blow-up | Climate |
| 62 | Corner Break | Load |
| 63 | Linear Cracking | Load |
| 64 | Durability Cracking | Climate |
| 65 | Joint Seal Damage | Climate |
| 66 | Small Patch | Pavement Repair |
| 67 | Large Patch/Utility Cut | Utility / Pavement Repair |
| 68 | Popout | Climate |
| 69 | Pumping | Load |
| 70 | Scaling/Crazing | Construction Quality |
| 71 | Faulting | Subgrade Quality |
| 72 | Shattered Slab | Load |
| 73 | Shrinkage Cracking | Construction Quality / Load |
| 74 | Joint Spalling | Load |
| 75 | Corner Spalling | Load |
| Source: U.S. | . Army CERL, FDOT Airfield In | spection Reference Manual |

Prior to conducting the inspections, Global Positioning System (GPS) coordinates were recorded using CADD at the centroid of each sample unit. The centroid is usually the geometric center of the area, but in cases where sample units are irregular in shape, this is the center of mass. These data are presented in a table on the updated Network Definition Map in Appendix A of this report.

Pavement condition inspections at Kendall-Tamiami Executive Airport were performed in March 2012. Data was recorded in the field in accordance with FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

After the completion of data collection, the data was imported into MicroPAVER, and PCI values were calculated for the pavement sections.

3.2 Pavement Condition Index Results

According to the 2012 survey, the overall area-weighted PCI at Kendall-Tamiami Executive Airport is 86, representing a Good overall network condition.

Overall, the Airport exhibited pavement distresses associated with climate and age. Asphalt concrete pavement distresses included: weathering and raveling, longitudinal and transverse cracking, block cracking, swelling, oil spillage, bleeding, and patching. Depressions, which are a structural distress caused by repeated traffic loading, inadequate subgrade, or poor construction methods, were observed in isolated areas. Portland cement concrete pavements, which are located only on the Northeast Apron, were in Good condition and exhibited only joint spalling pavement distresses.

Runways 13-31, 9L-27R, and 9R-27L are all surfaced with asphalt concrete and exhibited frequent occurrences of low severity weathering and raveling and longitudinal and transverse cracking. Medium severity weathering and raveling, low severity patching, bleeding, and oil spillage were also observed on the runways. The runways are in Good condition with PCI values ranging from 90 to 91, which is above the FDOT and FAA minimum PCI levels.

The taxiways are all surfaced with asphalt concrete and exhibited low to medium severity weathering and raveling; low severity longitudinal and transverse cracking; low severity swelling; low to medium severity patching; low severity block cracking; and oil spillage. One small low severity depression, located on Taxiway E-5, was also observed. The taxiways are typically in Good to Fair condition, although there are sections on Taxiways Delta and its connectors that are in Poor condition. This is mainly due to the large areas of medium severity weathering and raveling present on those sections, causing a greater FOD potential.

The majority of the apron pavements are surfaced with asphalt concrete; the only portland cement concrete pavements are located on the Northeast Apron. The asphalt concrete pavement distresses were typically of low severity and included weathering and raveling, longitudinal and transverse cracking, swelling, block cracking, patching, and oil spillage. Medium to high severity weathering and raveling were also observed on the North Apron and South Apron, and a relatively large low severity depression was identified on the North Apron. The only portland cement concrete pavement distress observed was low severity joint spalling.

The aprons are typically in Good to Fair condition, with one section on the South Apron located within an area of T-Hangars in Very Poor condition. This area exhibited large expanses of medium severity weathering and raveling as well as low severity block cracking.

Appendix B contains a table and a Condition Map which depicts the PCI results by Section, and Appendix C contains a table of PCI results by Branch. Appendix I includes detailed distress data generated by MicroPAVER for each inspected sample unit.

Figure 3-1 provides the PCI distribution by rating category for Kendall-Tamiami Executive Airport.

Figure 3-1: Network PCI Distribution by Rating Category




Figure 3-1a: Condition Rating Summary

| Condition Rating | Total Area (ft²) | Percent |
|------------------|------------------|---------|
| Good | 5,827,202 | 80% |
| Satisfactory | 816,149 | 11% |
| Fair | 293,012 | 4% |
| Poor | 261,360 | 4% |
| Very Poor | 19,714 | 1% |
| Serious | 0 | 0% |
| Failed | 0 | 0% |


Approximately 91% of the network is in Good and Satisfactory condition while 5% of the network is in Poor and Very Poor condition. Table 3-3 illustrates the area-weighted PCI computed individually for each pavement use.

Table 3-3: Condition by Pavement Use


| Use | Average Area- Weighted PCI | Condition Rating |
|----------------|-------------------------------|-------------------------|
| Runway | 90 | Good |
| Taxiway | 86 | Good |
| Apron | 83 | Satisfactory |
| All (Weighted) | 86 | Good |

Figure 3-2 presents the breakdown of PCI by range for each pavement use.

Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use




(b) Taxiway





(c) Apron



4. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 4-1 illustrates the predicted performance of pavements at Kendall-Tamiami Executive Airport based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum service level for Regional Reliever (RL) airports.




Figure 4-1: Predicted PCI by Pavement Use

Appendix D presents the tabular summary of the predicted Section PCI for each year from 2012 to 2021.

5. MAINTENANCE POLICIES AND COSTS

5.1 Policies

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature and are recommended to help achieve the performance goal.

Table 5-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules. These repairs are used only in the first year of an analysis.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called "Critical PCI." The critical PCI levels for different pavement and branch types established in the previous SAPMP update were used in this update for the development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 5-2 gives the critical PCI levels for Regional Reliever Airports.

The maintenance rehabilitation policy and activity costs have been updated based on the study of readily available construction cost data at the time of this study. The costs depicted in this report are intended for planning purposes.

Table 5-1: Routine Maintenance Activities for Airfield Pavements

| Surface | Distress | Severity* | Work Type | Code | Work Unit |
|---------|-----------------------|-----------|--------------------------------|-------|-----------|
| | Alligator Crack | M, H | Patching - AC Deep | PA-AD | SqFt |
| | Bleeding | N/A | No Localized M&R | NONE | N/A |
| | Block Crack | M, H | Crack Sealing – AC | CS-AC | SqFt |
| | Corrugation | L, M, H | Patching - AC Deep | PA-AD | SqFt |
| | Depression | M, H | Patching - AC Deep | PA-AD | SqFt |
| | Jet Blast | N/A | Patching - AC Deep | PA-AD | SqFt |
| | Joint Ref. Crack | M, H | Crack Sealing – AC | CS-AC | Ft |
| | L & T Crack | M, H | Crack Sealing – AC | CS-AC | Ft |
| AC | Oil Spillage | N/A | Patching - AC Shallow | PA-AS | SqFt |
| AC | Patching | M, H | Patching - AC Deep | PA-AD | SqFt |
| | Polished Agg. | N/A | No Localized M&R | NONE | N/A |
| | Danalina / | L | Surface Sealing - Rejuvenating | SS-RE | SqFt |
| | Raveling / Weathering | M | Surface Seal - Coal Tar | SS-CT | SqFt |
| | weathering | Н | Microsurfacing | MI-AC | SqFt |
| | Rutting | M, H | Patching - AC Deep | PA-AD | SqFt |
| | Shoving | M, H | Grinding (Localized) | GR-LL | SqFt |
| | Slippage Crack | N/A | Patching - AC Shallow | PA-AS | SqFt |
| | Swelling | M, H | Patching - AC Deep | PA-AD | SqFt |
| | Blow-Up | L, M, H | Patching - PCC Full Depth | PA-PF | SqFt |
| | Corner Break | M, H | Patching - PCC Full Depth | PA-PF | SqFt |
| | Linear Crack | M, H | Crack Sealing – PCC | CS-PC | Ft |
| | Durability Crack | Н | Slab Replacement – PCC | SL-PC | SqFt |
| | Durability Crack | M | Patching - PCC Full Depth | PA-PF | SqFt |
| | Jt. Seal Damage | M, H | Joint Seal (Localized) | JS-LC | Ft |
| | Small Patch | M, H | Patching - PCC Partial Depth | PA-PP | SqFt |
| PCC | Large Patch | M, H | Patching - PCC Full Depth | PA-PF | SqFt |
| PCC | Popouts | N/A | No Localized M&R | NONE | N/A |
| | Pumping | N/A | No Localized M&R | NONE | N/A |
| | Scaling | Н | Slab Replacement – PCC | SL-PC | SqFt |
| | Faulting | M, H | Grinding (Localized) | GR-PP | Ft |
| | Shattered Slab | M, H | Slab Replacement – PCC | SL-PC | SqFt |
| | Shrinkage Crack | N/A | No Localized M&R | NONE | N/A |
| | Joint Spall | M, H | Patching - PCC Partial Depth | PA-PP | SqFt |
| | Corner Spall | M, H | Patching - PCC Partial Depth | PA-PP | SqFt |

^{*}L = Low, M = Medium, H = High

Table 5-2: Critical PCI for Regional Reliever Airports

| Use | Critical PCI |
|---------|--------------|
| Runway | 65 |
| Taxiway | 65 |
| Apron | 65 |

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 5-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of Regional Reliever Airports.

Table 5-3: FDOT Minimum Service Level PCI for Regional Reliever Airports

| Minimum PCI | | | | |
|----------------------|----|----|--|--|
| Runway Taxiway Apron | | | | |
| 75 | 65 | 65 | | |

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 5-2 the PCI trigger range when the likely activity would be a mill and resurface was 40 to 79 and reconstruction at a PCI of 39 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 5-4 summarizes the M&R activities for Regional Reliever Airports based on PCI value.

Table 5-4: M&R Activities for Regional Reliever Airports

| | Activity | PCI Range |
|----------------|---|-------------|
| Maintenance | Crack Sealing and Full-Depth Patching | 80 and 90 |
| Rehabilitation | Mill and Overlay (AC) or Concrete Pavement Restoration (PCC) | 40 to 79 |
| | Reconstruction | 39 and less |

5.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were updated from the previous SAPMP study based on current construction cost trends in order to determine meaningful costs for the program. Table 5-5 presents the unit costs summary.

5.3 M&R Activities

FDOT recognizes that although Mill and Overlay work is recommended for asphalt pavements within a PCI range from 40 to 79, it is conceivable that airports may not have adequate funding to perform this type of rehabilitation. Microsurfacing treatment is a maintenance/rehabilitation measure that can be used in lieu of asphalt pavement mill and overlay; however it should be understood that this measure is intended for short term pavement life extension. While the cost of microsurfacing is significantly lower than that of pavement mill and overlay, it is not intended to be a full rehabilitative measure for long term benefit.

Table 5-5: Maintenance Unit Costs for FDOT

| Code | Name | Cost | Unit |
|-------|-----------------------------------|---------|------|
| GR-LL | Grinding (Localized for AC) | \$2.10 | SqFt |
| PA-AL | Patching – AC Leveling | \$2.30 | SqFt |
| PA-AS | Patching – AC Shallow | \$2.90 | SqFt |
| PA-PF | Patching – PCC Full Depth | \$38.11 | SqFt |
| PA-PP | Patching – PCC Partial Depth | \$19.06 | SqFt |
| SL-PC | Slab Replacement – PCC | \$39.11 | SqFt |
| CS-PC | Crack Sealing – PCC | \$4.24 | Ft |
| UN-PC | Undersealing – PCC | \$3.40 | Ft |
| CS-AC | Crack Sealing – AC | \$2.25 | Ft |
| GR-PP | Grinding (Localized for PCC) | \$22.51 | Ft |
| JS-LC | Joint Seal (Localized) | \$2.00 | Ft |
| SH-LE | Shoulder Leveling | \$2.81 | Ft |
| JS-SI | Joint Seal – Silicon | \$2.81 | Ft |
| PA-AD | Patching – AC Deep | \$4.90 | SqFt |
| OL-AT | Overlay – AC Thin | \$2.80 | SqFt |
| SS-CT | Surface Seal – Coal Tar | \$0.40 | SqFt |
| SS-FS | Surface Seal – Fog Seal | \$0.40 | SqFt |
| SS-RE | Surface Seal – Rejuvenating | \$0.40 | SqFt |
| ST-SB | Surface Treatment – Single Bitum. | \$0.30 | SqFt |
| ST-SS | Surface Treatment – Slurry Seal | \$0.55 | SqFt |
| ST-ST | Surface Treatment – Sand Tar | \$0.28 | SqFt |
| MI-AC | Microsurfacing - AC | \$0.65 | SqFt |

The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection was performed recently and only in the first year of the M&R analysis. In subsequent years, MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCIs. That is, for low PCI, it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly.

Using available unit cost data, the Major M&R Cost by Condition table was set up as shown in Table 5-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

Table 5-6: M&R Activities and Unit Costs by Condition for Regional Reliever Airports

| | Activity | PCI Trigger | Cost/SqFt |
|----------------|---|-------------|-----------|
| Maintenance | Crack Sealing and Full-Depth Patching | 90 | \$0.10 |
| | | 80 | \$0.40 |
| Rehabilitation | Mill and Overlay (AC) or Concrete Pavement Restoration (PCC) | 70 | \$0.90 |
| | | 60 | \$3.68 |
| | | 50 | \$7.61 |
| | | 40 | \$18.57 |
| | Reconstruction | 30 | \$18.57 |
| | | 20 | \$18.57 |

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

6. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years, starting from 2012. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Table 6-1 presents the M&R list of immediate needs for Major M&R, i.e. Year 1 of the forecast. The importance of this listing is that it points out the major activities triggered by the current condition of the pavements.

Table 6-1: Summary of Immediate Major M&R Needs Option No. 1

| Branch Name | Section ID | Surface Type | Section Area (ft²) | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------------|---------------|-----------------|-----------------------|---------------------|----------------------|------------------|---------------------|
| North Apron | 4225 | AC | 69,490 | \$178,450.31 | 64 | Mill and Overlay | 100 |
| South Apron | 4125 | AC | 35,371 | \$110,498.16 | 62 | Mill and Overlay | 100 |
| South Apron | 4130 | AC | 19,714 | \$258,061.25 | 35 | Reconstruction | 100 |
| South Apron | 4135 | AC | 29,788 | \$121,327.74 | 59 | Mill and Overlay | 100 |
| Taxiway Delta | 405 | AC | 210,898 | \$1,604,932.90 | 47 | Mill and Overlay | 100 |
| Taxiway D-1 | 415 | AC | 50,475 | \$265,094.71 | 56 | Mill and Overlay | 100 |
| Taxiway D-2 | 420 | AC | 50,463 | \$324,527.06 | 53 | Mill and Overlay | 100 |
| | | | Total | \$2,862,892.13 | 54 | | 100 |

^{*} Costs are adjusted for inflation.

FDOT recognizes that the costs attributed to the aforementioned 'Major Activity' of performing a pavement 'Mill and Overlay' may conflict with budgetary constraints. Table 6-2 presents an alternative minor rehabilitative activity to the mid-range performing pavements. The alternative activity is performing a 'Microsurfacing/Slurry Seal' to the pavement to retard the degradation of the facility until funding is available for a 'Mill and Overlay' activity.

Table 6-2: Summary of Immediate Major M&R Needs Option No. 2

| Branch Name | Section ID | Surface Type | Section Area (ft²) | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------------|---------------|-----------------|-----------------------|---------------------|----------------------|----------------|---------------------|
| North Apron | 4225 | AC | 69,490 | \$45,168.50 | 64 | Microsurfacing | 100 |
| South Apron | 4125 | AC | 35,371 | \$22,990.97 | 62 | Microsurfacing | 100 |
| South Apron | 4130 | AC | 19,714 | \$258,061.25 | 35 | Reconstruction | 100 |
| South Apron | 4135 | AC | 29,788 | \$19,362.39 | 59 | Microsurfacing | 100 |
| Taxiway Delta | 405 | AC | 210,898 | \$137,083.56 | 47 | Microsurfacing | 100 |
| Taxiway D-1 | 415 | AC | 50,475 | \$32,808.74 | 56 | Microsurfacing | 100 |
| Taxiway D-2 | 420 | AC | 50,463 | \$32,800.89 | 53 | Microsurfacing | 100 |
| | | | Total | \$548,276.29 | 54 | | 100 |

^{*} Costs are adjusted for inflation.

In addition to the immediate Major M&R needs, maintenance activities for pavement areas above critical PCI have been recommended by MicroPAVER for Year 1 and are shown in Table 6-3 below. The costs provided in Table 5-5 were used to calculate the costs associated with this work, which is intended to treat specific distress types. A more detailed table is provided in Appendix E.

Table 6-3: Summary of Year 1 Maintenance Activities

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| North Apron | AP N | 4205 | OIL SPILLAGE | N | Patching - AC Shallow | 1,782.80 | SqFt | \$2.90 | \$5,170.22 |
| North Apron | AP N | 4205 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 24,779.80 | SqFt | \$0.40 | \$9,912.00 |
| North Apron | AP N | 4205 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 31.50 | SqFt | \$0.40 | \$12.60 |
| North Apron | AP N | 4215 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,200.00 | SqFt | \$0.40 | \$480.00 |
| North Apron | AP N | 4220 | OIL SPILLAGE | N | Patching - AC Shallow | 36.90 | SqFt | \$2.90 | \$106.98 |
| North Apron | AP N | 4220 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 7,437.70 | SqFt | \$0.40 | \$2,975.09 |
| North Apron | AP N | 4230 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 628.30 | SqFt | \$0.40 | \$251.32 |
| Northeast Apron | AP NE | 4310 | OIL SPILLAGE | N | Patching - AC Shallow | 80.40 | SqFt | \$2.90 | \$233.14 |
| Northeast Apron | AP NE | 4310 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 769.90 | SqFt | \$0.40 | \$307.96 |
| Northeast Apron | AP NE | 4315 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 486.80 | SqFt | \$0.40 | \$194.73 |
| Northeast Apron | AP NE | 4315 | OIL SPILLAGE | N | Patching - AC Shallow | 55.00 | SqFt | \$2.90 | \$159.39 |
| Northeast Apron | AP NE | 4325 | OIL SPILLAGE | N | Patching - AC Shallow | 786.40 | SqFt | \$2.90 | \$2,280.52 |
| Northeast Apron | AP NE | 4325 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 15,266.90 | SqFt | \$0.40 | \$6,106.82 |
| South Apron | AP S | 4105 | OIL SPILLAGE | N | Patching - AC Shallow | 37.30 | SqFt | \$2.90 | \$108.16 |
| South Apron | AP S | 4105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 65,754.70 | SqFt | \$0.40 | \$26,302.08 |
| South Apron | AP S | 4105 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 1,948.80 | SqFt | \$0.40 | \$779.52 |
| South Apron | AP S | 4110 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 2,234.60 | SqFt | \$0.40 | \$893.85 |
| South Apron | AP S | 4110 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 23,805.80 | SqFt | \$0.40 | \$9,522.39 |
| South Apron | AP S | 4110 | OIL SPILLAGE | N | Patching - AC Shallow | 2,410.10 | SqFt | \$2.90 | \$6,989.23 |
| South Apron | AP S | 4115 | OIL SPILLAGE | N | Patching - AC Shallow | 12,653.20 | SqFt | \$2.90 | \$36,694.29 |
| South Apron | AP S | 4115 | WEATH/RAVEL | Н | Microsurfacing - AC | 249.80 | SqFt | \$0.65 | \$162.34 |
| South Apron | AP S | 4115 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 48,751.70 | SqFt | \$0.40 | \$19,500.83 |
| South Apron | AP S | 4115 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 6,460.30 | SqFt | \$0.40 | \$2,584.13 |

Table 6-3: Summary of Year 1 Maintenance Activities (Continued)

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| South Apron | AP S | 4140 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 43,873.60 | SqFt | \$0.40 | \$17,549.58 |
| Southeast Apron | AP SE | 4410 | OIL SPILLAGE | N | Patching - AC Shallow | 346.90 | SqFt | \$2.90 | \$1,005.91 |
| Southeast Apron | AP SE | 4410 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 45,219.60 | SqFt | \$0.40 | \$18,088.00 |
| Runway 13-31 | RW 13-31 | 6205 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 11,875.80 | SqFt | \$0.40 | \$4,750.37 |
| Runway 13-31 | RW 13-31 | 6210 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,002.00 | SqFt | \$0.40 | \$1,600.80 |
| Runway 9L-27R | RW 9L-27R | 6104 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 400.00 | SqFt | \$0.40 | \$160.00 |
| Runway 9L-27R | RW 9L-27R | 6105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 12,618.40 | SqFt | \$0.40 | \$5,047.41 |
| Runway 9L-27R | RW 9L-27R | 6109 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 200.00 | SqFt | \$0.40 | \$80.00 |
| Runway 9L-27R | RW 9L-27R | 6110 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,600.00 | SqFt | \$0.40 | \$1,840.00 |
| Runway 9L-27R | RW 9L-27R | 6126 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 200.00 | SqFt | \$0.40 | \$80.00 |
| Runway 9L-27R | RW 9L-27R | 6131 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 404.00 | SqFt | \$0.40 | \$161.60 |
| Runway 9R-27L | RW 9R-27L | 6305 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 8,217.00 | SqFt | \$0.40 | \$3,286.82 |
| Runway 9R-27L | RW 9R-27L | 6305 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 9,914.10 | SqFt | \$0.40 | \$3,965.68 |
| Runway 9R-27L | RW 9R-27L | 6310 | OIL SPILLAGE | N | Patching - AC Shallow | 46.30 | SqFt | \$2.90 | \$134.28 |
| Runway 9R-27L | RW 9R-27L | 6310 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,571.20 | SqFt | \$0.40 | \$1,828.50 |
| Runway 9R-27L | RW 9R-27L | 6310 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 8,348.90 | SqFt | \$0.40 | \$3,339.60 |
| Runway 9R-27L | RW 9R-27L | 6311 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 336.00 | SqFt | \$0.40 | \$134.40 |
| Taxiway 1 | TW 1 | 270 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 252.50 | SqFt | \$0.40 | \$101.00 |
| Taxiway 2 | TW 2 | 260 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 41.40 | SqFt | \$0.40 | \$16.55 |
| Taxiway 2 | TW 2 | 260 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 413.70 | SqFt | \$0.40 | \$165.47 |
| Taxiway 3 | TW 3 | 250 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 359.90 | SqFt | \$0.40 | \$143.96 |
| Taxiway 4 | TW 4 | 240 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 865.30 | SqFt | \$0.40 | \$346.11 |
| Taxiway 5 | TW 5 | 230 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 2,585.50 | SqFt | \$0.40 | \$1,034.22 |

Table 6-3: Summary of Year 1 Maintenance Activities (Continued)

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|---------------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| Taxiway 6 | TW 6 | 220 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,802.70 | SqFt | \$0.40 | \$721.09 |
| Taxiway 7 | TW 7 | 210 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,308.20 | SqFt | \$0.40 | \$523.26 |
| Taxiway Alpha | TW A | 105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,684.90 | SqFt | \$0.40 | \$1,873.97 |
| Taxiway Alpha | TW A | 108 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 5,550.00 | SqFt | \$0.40 | \$2,220.00 |
| Taxiway Alpha | TW A | 110 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 101.30 | SqFt | \$0.40 | \$40.52 |
| Taxiway A-1 | TW A1 | 115 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 857.10 | SqFt | \$0.40 | \$342.83 |
| Taxiway A-2 | TW A2 | 120 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 914.20 | SqFt | \$0.40 | \$365.68 |
| Taxiway A-3 | TW A3 | 124 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 810.50 | SqFt | \$0.40 | \$324.18 |
| Taxiway A-3 | TW A3 | 125 | OIL SPILLAGE | N | Patching - AC Shallow | 20.40 | SqFt | \$2.90 | \$59.13 |
| Taxiway A-3 | TW A3 | 125 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 31.50 | SqFt | \$0.40 | \$12.59 |
| Taxiway to NE Apron | TW AP NE | 1005 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 9,576.50 | SqFt | \$0.40 | \$3,830.65 |
| Taxiway to SE Apron | TW AP SE | 1105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 805.00 | SqFt | \$0.40 | \$322.02 |
| Taxiway Charlie | TW C | 910 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 2,761.30 | SqFt | \$0.40 | \$1,104.55 |
| Taxiway C-1 | TW C1 | 310 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,762.30 | SqFt | \$0.40 | \$704.93 |
| Taxiway C-1 | TW C1 | 310 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 65.90 | SqFt | \$0.40 | \$26.35 |
| Taxiway C-2 | TW C2 | 320 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,753.80 | SqFt | \$0.40 | \$701.53 |
| Taxiway CC | TW CC | 905 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,174.50 | SqFt | \$0.40 | \$469.79 |
| Taxiway Delta | TW D | 410 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 289.10 | SqFt | \$0.40 | \$115.65 |
| Taxiway Delta | TW D | 411 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,425.90 | SqFt | \$0.40 | \$570.36 |
| Taxiway Delta | TW D | 412 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 199.10 | SqFt | \$0.40 | \$79.63 |
| Taxiway Echo | TW E | 505 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 99.30 | SqFt | \$0.40 | \$39.70 |
| Taxiway Echo | TW E | 505 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,893.10 | SqFt | \$0.40 | \$1,957.27 |
| Taxiway Echo | TW E | 507 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 618.60 | SqFt | \$0.40 | \$247.44 |

Pavement Evaluation Report –Kendall-Tamiami Executive Airport Florida Statewide Airfield Pavement Management Program May 2012

Table 6-3: Summary of Year 1 Maintenance Activities (Continued)

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| Taxiway Echo | TW E | 510 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 806.60 | SqFt | \$0.40 | \$322.63 |
| Taxiway E-1 | TW E1 | 516 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,618.20 | SqFt | \$0.40 | \$647.29 |
| Taxiway E-2 | TW E2 | 520 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 12,613.30 | SqFt | \$0.40 | \$5,045.35 |
| Taxiway E-3 | TW E3 | 525 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 9,121.50 | SqFt | \$0.40 | \$3,648.61 |
| Taxiway E-4 | TW E4 | 527 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 2,101.30 | SqFt | \$0.40 | \$840.53 |
| Taxiway E-5 | TW E5 | 529 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 516.40 | SqFt | \$0.40 | \$206.57 |
| Taxiway E-5 | TW E5 | 530 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 742.50 | SqFt | \$0.40 | \$297.02 |
| Taxiway Foxtrot | TW F | 605 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 800.50 | SqFt | \$0.40 | \$320.22 |
| Taxiway Golf | TW G | 710 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 244.40 | SqFt | \$0.40 | \$97.75 |
| Taxiway Hotel | TW H | 815 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 5,513.90 | SqFt | \$0.40 | \$2,205.59 |
| Taxiway H-1 | TW H1 | 805 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 70.00 | SqFt | \$0.40 | \$28.00 |
| Taxiway H-2 | TW H2 | 810 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 437.90 | SqFt | \$0.40 | \$175.16 |
| Taxiway H-3 | TW H3 | 330 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 324.40 | SqFt | \$0.40 | \$129.77 |
| Taxiway H-5 | TW H5 | 350 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 413.70 | SqFt | \$0.40 | \$165.47 |
| Taxiway H-6 | TW H6 | 360 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 413.70 | SqFt | \$0.40 | \$165.47 |
| Taxiway H-7 | TW H7 | 370 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 248.80 | SqFt | \$0.40 | \$99.53 |
| | | | | | | | | Total = | \$227,635.93 |

The 10 year forecast results are shown in Figure 6-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.

Pavement Evaluation Report –Kendall-Tamiami Executive Airport Florida Statewide Airfield Pavement Management Program May 2012




Figure 6-1: Budget Scenario Analysis

The following network level observations can be made from the figure above:

- The PCI will deteriorate from an average of 86 in 2012 to an average of 70 in ten years if no M&R activities are performed. Specific pavement sections may be closer to critical condition as identified by the immediate needs in Table IV. Estimated PCI ratings are presented in Appendix D.
- The PCI will remain at or above an average of 73 through the 10-year analysis period under the unlimited budget scenario. A 2021 PCI average of 73 with this scenario is 3 PCI points higher than a "No M&R" scenario. The total cost for Major M&R over this 10-year period is about \$3.5 million.

7. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels, the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCIs less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 7-1 provides the summary results under the critical PCI unlimited funding scenario.

Table 7-1: M&R Costs under Unlimited Funding Scenario

| Year | Preventative | Major M&R | Total Year Cost |
|-------|----------------|----------------|------------------------|
| 2012 | \$227,635.95 | \$2,862,892.13 | \$3,090,528.08 |
| 2013 | \$317,033.06 | \$119,608.70 | \$436,641.76 |
| 2014 | \$442,042.84 | \$189,216.97 | \$631,259.81 |
| 2015 | \$580,827.62 | \$0.00 | \$580,827.62 |
| 2016 | \$723,255.67 | \$0.00 | \$723,255.67 |
| 2017 | \$883,425.04 | \$0.00 | \$883,425.04 |
| 2018 | \$1,036,746.05 | \$0.00 | \$1,036,746.05 |
| 2019 | \$1,206,371.41 | \$0.00 | \$1,206,371.41 |
| 2020 | \$1,384,189.92 | \$0.00 | \$1,384,189.92 |
| 2021 | \$1,518,954.53 | \$366,896.97 | \$1,885,851.50 |
| Total | \$8,320,482.09 | \$3,538,614.77 | \$11,859,096.86 |

Note: Costs are adjusted for inflation.

Approximately 81% of the total Major M&R cost is required in the first year (2012). According to the 2012 inspections, the following pavement sections were in immediate need of Major M&R Activity:

- North Apron Asphalt pavement mill and overlay
- **South Apron** Asphalt pavement mill and overlay or reconstruction
- Taxiways Delta/D-1/D-2 Asphalt pavement mill and overlay

The unlimited budget scenario provides the basis for estimating the total repair cost.

Appendix F provides details of M&R plan by year under the unlimited funding scenario, and the map of the 10-year M&R plan is provided in Appendix G. It is important to understand that the SAPMP is a network level tool and the M&R costs provided in this report are only for planning purposes.

Pavement Evaluation Report –Kendall-Tamiami Executive Airport Florida Statewide Airfield Pavement Management Program May 2012

8. VISUAL AIDS

8.1 System Inventory and Network Definition Drawings

The System Inventory and Network Definition CADD drawings, which show the airport pavement outline with Branch and Section boundaries and identify changes in the network pavement since the last inspection and the sampling plan, respectively, are included in Appendix A of this report.

8.2 Condition Map

A Condition Map that has been prepared based on data linked to the airport's shape file is included in Appendix B. The Condition Map graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

8.3 10-Year M&R Map

A 10-Year M&R Map that shows the summary of the M&R plan is attached in Appendix G.

8.4 Photographs

Selected digital photographs taken during the pavement inspection are provided in Appendix H to provide visual support to special pavement conditions or distress observed during the inspection of the airport.

Pavement Evaluation Report –Kendall-Tamiami Executive Airport Florida Statewide Airfield Pavement Management Program May 2012

9. RECOMMENDATIONS

Pavement condition inspections were performed at Kendall-Tamiami Executive Airport, and a 10-year M&R plan was developed based on the unlimited funding scenario.


The following recommendations were made based on the 2012 condition inspection and M&R analysis results:

- North Apron Asphalt pavement mill and overlay
- **South Apron** Asphalt pavement mill and overlay or reconstruction
- **Taxiways Delta/D-1/D-2** Asphalt pavement mill and overlay

Further evaluation of these features is necessary in order to develop repair plans and timing for future budgets since these needs cannot be addressed with typical annual expenditures.

APPENDIX A

NETWORK DEFINITION MAP SYSTEM INVENTORY MAP PAVEMENT INVENTORY TABLE WORK HISTORY REPORT



| Branch | Section | Sample | Latitude | Longitude |
|-----------|---------|--------|-------------|--------------|
| RW 9R-27L | 6311 | 216 | 25.64383376 | -80.42321791 |
| RW 9R-27L | 6310 | 128 | 25.64327061 | -80.43656063 |
| RW 9R-27L | 6310 | 152 | 25.64342430 | -80.43292213 |
| RW 9R-27L | 6310 | 176 | 25.64357790 | -80.42928362 |
| RW 9R-27L | 6310 | 204 | 25.64375698 | -80.42503869 |
| RW 9R-27L | 6310 | 528 | 25.64292706 | -80.43654296 |
| RW 9R-27L | 6310 | 544 | 25.64302953 | -80.43411731 |
| RW 9R-27L | 6310 | 568 | 25.64318316 | -80.43047881 |
| RW 9R-27L | 6310 | 596 | 25.64336228 | -80.42623389 |
| RW 9R-27L | 6309 | 520 | 25.64287581 | -80.43775579 |
| RW 9R-27L | 6307 | 104 | 25.64311683 | -80.44019912 |
| RW 9R-27L | 6307 | 508 | 25.64279891 | -80.43957503 |
| RW 9R-27L | 6306 | 418 | 25.64366512 | -80.42313481 |
| RW 9R-27L | 6305 | 325 | 25.64307001 | -80.43723401 |
| RW 9R-27L | 6305 | 336 | 25.64314047 | -80.43556637 |
| RW 9R-27L | 6305 | 342 | 25.64317889 | -80.43465675 |
| RW 9R-27L | 6305 | 348 | 25.64321731 | -80.43374713 |
| RW 9R-27L | 6305 | 352 | 25.64324292 | -80.43314071 |
| RW 9R-27L | 6305 | 356 | 25.64326853 | -80.43253429 |
| RW 9R-27L | 6305 | 362 | 25.64330693 | -80.43162467 |
| RW 9R-27L | 6305 | 365 | 25.64332613 | -80.43116986 |
| RW 9R-27L | 6305 | 370 | 25.64335813 | -80.43041183 |
| RW 9R-27L | 6305 | 377 | 25.64340292 | -80.42935060 |
| RW 9R-27L | 6305 | 384 | 25.64344771 | -80.42828937 |
| RW 9R-27L | 6305 | 391 | 25.64349248 | -80.42722814 |
| RW 9R-27L | 6305 | 395 | 25.64351806 | -80.42662172 |
| RW 9R-27L | 6305 | 398 | 25.64353725 | -80.42616691 |
| RW 9R-27L | 6305 | 403 | 25.64356922 | -80.42540888 |
| RW 9R-27L | 6305 | 407 | 25.64359480 | -80.42480247 |
| RW 9R-27L | 6305 | 412 | 25.64362676 | -80.42404444 |
| RW 9R-27L | 6305 | 415 | 25.64364594 | -80.42358963 |
| RW 9R-27L | 6304 | 321 | 25.64304438 | -80.43784043 |
| RW 9R-27L | 6302 | 300 | 25.64290980 | -80.44102410 |
| RW 9R-27L | 6302 | 304 | 25.64293544 | -80.44041769 |
| RW 9R-27L | 6302 | 308 | 25.64296107 | -80.43981128 |
| RW 9R-27L | 6302 | 314 | 25.64299953 | -80.43890166 |
| RW 9R-27L | 6302 | 318 | 25.64302516 | -80.43829524 |

| Branch | Section | Sample | Latitude | Longitude |
|-----------|---------|--------|-------------|--------------|
| RW 13-31 | 6210 | 100 | 25.64419743 | -80.43126713 |
| RW 13-31 | 6210 | 120 | 25.64586675 | -80.43368003 |
| RW 13-31 | 6210 | 128 | 25.64653447 | -80.43464521 |
| RW 13-31 | 6210 | 172 | 25.65020680 | -80.43995389 |
| RW 13-31 | 6210 | 508 | 25.64459177 | -80.43246249 |
| RW 13-31 | 6210 | 556 | 25.64859803 | -80.43825362 |
| RW 13-31 | 6210 | 572 | 25.64993340 | -80.44018409 |
| RW 13-31 | 6205 | 301 | 25.64401900 | -80.43132191 |
| RW 13-31 | 6205 | 305 | 25.64435287 | -80.43180449 |
| RW 13-31 | 6205 | 312 | 25.64493713 | -80.43264900 |
| RW 13-31 | 6205 | 317 | 25.64535446 | -80.43325223 |
| RW 13-31 | 6205 | 322 | 25.64577179 | -80.43385546 |
| RW 13-31 | 6205 | 326 | 25.64610565 | -80.43433805 |
| RW 13-31 | 6205 | 330 | 25.64643950 | -80.43482064 |
| RW 13-31 | 6205 | 334 | 25.64677336 | -80.43530323 |
| RW 13-31 | 6205 | 338 | 25.64710721 | -80.43578583 |
| RW 13-31 | 6205 | 343 | 25.64752453 | -80.43638908 |
| RW 13-31 | 6205 | 348 | 25.64794184 | -80.43699233 |
| RW 13-31 | 6205 | 353 | 25.64835915 | -80.43759559 |
| RW 13-31 | 6205 | 358 | 25.64877646 | -80.43819885 |
| RW 13-31 | 6205 | 364 | 25.64927723 | -80.43892277 |
| RW 13-31 | 6205 | 372 | 25.64994491 | -80.43988801 |
| RW 13-31 | 6205 | 378 | 25.65044567 | -80.44061194 |
| RW 9L-27R | 6131 | 396 | 25.65325710 | -80.42545576 |
| RW 9L-27R | 6126 | 596 | 25.65309504 | -80.42521649 |
| RW 9L-27R | 6110 | 116 | 25.65292647 | -80.43736649 |
| RW 9L-27R | 6110 | 144 | 25.65310578 | -80.43312123 |
| RW 9L-27R | 6110 | 168 | 25.65325938 | -80.42948243 |
| RW 9L-27R | 6110 | 184 | 25.65336173 | -80.42705656 |
| RW 9L-27R | 6110 | 504 | 25.65250603 | -80.43916821 |
| RW 9L-27R | 6110 | 520 | 25.65260854 | -80.43674236 |
| RW 9L-27R | 6110 | 580 | 25.65299260 | -80.42764538 |
| RW 9L-27R | 6110 | 592 | 25.65306934 | -80.42582598 |
| RW 9L-27R | 6109 | 100 | 25.65282395 | -80.43979235 |
| RW 9L-27R | 6105 | 306 | 25.65268101 | -80.43910124 |
| RW 9L-27R | 6105 | 309 | 25.65270023 | -80.43864639 |
| RW 9L-27R | 6105 | 312 | 25.65271946 | -80.43819154 |


| Branch | Section | Sample | Latitude | Longitude |
|-----------|---------|--------|-------------|--------------|
| RW 9L-27R | 6105 | 316 | 25.65274508 | -80.43758508 |
| RW 9L-27R | 6105 | 322 | 25.65278352 | -80.43667538 |
| RW 9L-27R | 6105 | 328 | 25.65282195 | -80.43576569 |
| RW 9L-27R | 6105 | 331 | 25.65284116 | -80.43531084 |
| RW 9L-27R | 6105 | 334 | 25.65286038 | -80.43485599 |
| RW 9L-27R | 6105 | 340 | 25.65289880 | -80.43394629 |
| RW 9L-27R | 6105 | 347 | 25.65294361 | -80.43288498 |
| RW 9L-27R | 6105 | 352 | 25.65297562 | -80.43212690 |
| RW 9L-27R | 6105 | 358 | 25.65301402 | -80.43121720 |
| RW 9L-27R | 6105 | 364 | 25.65305242 | -80.43030750 |
| RW 9L-27R | 6105 | 367 | 25.65307161 | -80.42985265 |
| RW 9L-27R | 6105 | 370 | 25.65309081 | -80.42939780 |
| RW 9L-27R | 6105 | 376 | 25.65312919 | -80.42848810 |
| RW 9L-27R | 6105 | 383 | 25.65317397 | -80.42742678 |
| RW 9L-27R | 6105 | 388 | 25.65320594 | -80.42666870 |
| RW 9L-27R | 6105 | 391 | 25.65322513 | -80.42621385 |
| RW 9L-27R | 6104 | 301 | 25.65264897 | -80.43985932 |
| AP SE | 4410 | 201 | 25.64612498 | -80.41943734 |
| AP SE | 4410 | 501 | 25.64761737 | -80.41951387 |
| AP SE | 4405 | 302 | 25.64662803 | -80.41933019 |
| AP NE | 4325 | 10 | 25.64893486 | -80.42089753 |
| AP NE | 4325 | 13 | 25.64892272 | -80.42118559 |
| AP NE | 4325 | 14 | 25.64891058 | -80.42147366 |
| AP NE | 4325 | 101 | 25.64919778 | -80.42043482 |
| AP NE | 4325 | 108 | 25.64908290 | -80.42156758 |
| AP NE | 4320 | 201 | 25.64906005 | -80.41956081 |
| AP NE | 4315 | 103 | 25.64925668 | -80.41930652 |
| AP NE | 4310 | 103 | 25.65043521 | -80.41954321 |
| AP NE | 4305 | 201 | 25.65061649 | -80.41981688 |
| AP N | 4230 | 101 | 25.65033930 | -80.43098240 |
| AP N | 4225 | 101 | 25.65019922 | -80.42285557 |
| AP N | 4225 | 302 | 25.65051311 | -80.42194332 |
| AP N | 4225 | 500 | 25.65001097 | -80.42098312 |
| AP N | 4220 | 133 | 25.65129748 | -80.43110013 |
| AP N | 4220 | 231 | 25.65118342 | -80.43053968 |
| AP N | 4220 | 532 | 25.65075836 | -80.43082172 |
| AP N | 4215 | 228 | 25.65122181 | -80.42962999 |

| Branch | Section | Sample | Latitude | Longitude |
|--------|---------|--------|-------------|--------------|
| AP N | 4215 | 529 | 25.65079675 | -80.42991204 |
| AP N | 4205 | 104 | 25.65166617 | -80.42235954 |
| AP N | 4205 | 114 | 25.65153832 | -80.42539184 |
| AP N | 4205 | 207 | 25.65149040 | -80.42326218 |
| AP N | 4205 | 217 | 25.65136253 | -80.42629447 |
| AP N | 4205 | 221 | 25.65131137 | -80.42750739 |
| AP N | 4205 | 227 | 25.65123460 | -80.42932676 |
| AP N | 4205 | 312 | 25.65128905 | -80.42477127 |
| AP N | 4205 | 325 | 25.65112277 | -80.42871325 |
| AP N | 4205 | 402 | 25.65127946 | -80.42173193 |
| AP N | 4205 | 508 | 25.65106535 | -80.42354425 |
| AP N | 4205 | 516 | 25.65096306 | -80.42597008 |
| AP N | 4205 | 523 | 25.65087352 | -80.42809267 |
| AP N | 4205 | 604 | 25.65097906 | -80.42232429 |
| AP N | 4205 | 610 | 25.65090236 | -80.42414366 |
| AP N | 4205 | 619 | 25.65078727 | -80.42687271 |
| AP N | 4205 | 627 | 25.65068492 | -80.42929853 |
| AP S | 4140 | 103 | 25.64696709 | -80.42631465 |
| AP S | 4140 | 301 | 25.64645472 | -80.42556513 |
| AP S | 4140 | 402 | 25.64674426 | -80.42523054 |
| AP S | 4135 | 101 | 25.64666519 | -80.42989364 |
| AP S | 4130 | 101 | 25.64771046 | -80.43140200 |
| AP S | 4125 | 103 | 25.64642116 | -80.42799287 |
| AP S | 4115 | 227 | 25.64544253 | -80.42507423 |
| AP S | 4115 | 230 | 25.64548089 | -80.42416459 |
| AP S | 4115 | 235 | 25.64554481 | -80.42264851 |
| AP S | 4115 | 317 | 25.64545205 | -80.42811343 |
| AP S | 4115 | 322 | 25.64551601 | -80.42659735 |
| AP S | 4115 | 342 | 25.64577169 | -80.42053306 |
| AP S | 4115 | 534 | 25.64594429 | -80.42297288 |
| AP S | 4115 | 539 | 25.64600820 | -80.42145680 |
| AP S | 4115 | 619 | 25.64588990 | -80.42752817 |
| AP S | 4115 | 626 | 25.64597943 | -80.42540566 |
| AP S | 4110 | 107 | 25.64584752 | -80.43083803 |
| AP S | 4110 | 111 | 25.64518026 | -80.42988142 |
| AP S | 4110 | 213 | 25.64526345 | -80.42931922 |
| AP S | 4110 | 510 | 25.64576248 | -80.42972114 |

| Branch | Section | Sample | Latitude | Longitude |
|----------|---------|--------|-------------|--------------|
| AP S | 4110 | 515 | 25.64570130 | -80.42873397 |
| AP S | 4105 | 200 | 25.64712541 | -80.43243499 |
| AP S | 4105 | 205 | 25.64629074 | -80.43122853 |
| AP S | 4105 | 302 | 25.64690090 | -80.43186032 |
| AP S | 4105 | 504 | 25.64678574 | -80.43119357 |
| AP S | 4105 | 606 | 25.64656123 | -80.43061890 |
| TW AP SE | 1105 | 104 | 25.64608408 | -80.41978620 |
| TW AP NE | 1005 | 503 | 25.65148095 | -80.42016434 |
| TW AP NE | 1005 | 509 | 25.64983147 | -80.42007898 |
| TW C | 910 | 103 | 25.64545937 | -80.43077729 |
| TW C | 910 | 109 | 25.64646097 | -80.43222503 |
| TW C | 910 | 118 | 25.64796335 | -80.43439670 |
| TW C-C | 905 | 101 | 25.64777223 | -80.43387028 |
| TW H | 815 | 103 | 25.64470612 | -80.43296895 |
| TW H | 815 | 111 | 25.64482689 | -80.43086190 |
| TW H | 815 | 120 | 25.64489887 | -80.42816797 |
| TW H-2 | 810 | 101 | 25.64472487 | -80.42966960 |
| TW H-1 | 805 | 100 | 25.64450439 | -80.43343497 |
| TW G | 710 | 201 | 25.64908749 | -80.43574387 |
| TW G | 705 | 205 | 25.65008555 | -80.43540024 |
| TW G | 705 | 209 | 25.65113614 | -80.43503852 |
| TW F | 605 | 100 | 25.64923043 | -80.43659331 |
| TW F | 605 | 104 | 25.65030730 | -80.43627787 |
| TW F | 605 | 108 | 25.65135789 | -80.43591615 |
| TW E-4 | 530 | 402 | 25.64421812 | -80.42308418 |
| TW E-4 | 530 | 404 | 25.64449660 | -80.42308776 |
| TW E-4 | 529 | 100 | 25.64390735 | -80.42345361 |
| TW E-3 | 527 | 101 | 25.64414765 | -80.42638816 |
| TW E-2 | 525 | 298 | 25.64366311 | -80.42971190 |
| TW E-2 | 525 | 301 | 25.64379094 | -80.42994636 |
| TW E-2 | 525 | 303 | 25.64406625 | -80.42996165 |
| TW E-1 | 520 | 196 | 25.64349226 | -80.43368127 |
| TW E-1 | 520 | 203 | 25.64392036 | -80.43340495 |
| TW E-1 | 520 | 205 | 25.64419520 | -80.43341907 |
| TW E-0 | 516 | 303 | 25.64373923 | -80.43769233 |
| TW E-0 | 515 | 202 | 25.64359086 | -80.43794451 |
| TW E | 513 | 100 | 25.64318784 | -80.44096245 |

| Branch | Section | Sample | Latitude | Longitude |
|--------|---------|--------|-------------|--------------|
| TW E | 513 | 152 | 25.64347358 | -80.44071886 |
| TW E | 510 | 163 | 25.64483159 | -80.42159936 |
| TW E | 507 | 224 | 25.64431048 | -80.43068866 |
| TW E | 505 | 120 | 25.64428146 | -80.43463746 |
| TW E | 505 | 124 | 25.64433268 | -80.43342462 |
| TW E | 505 | 144 | 25.64458865 | -80.42736039 |
| TW E | 505 | 155 | 25.64472933 | -80.42402506 |
| TW E | 505 | 159 | 25.64478046 | -80.42281221 |
| TW E | 503 | 106 | 25.64410209 | -80.43888241 |
| TW D-2 | 420 | 203 | 25.64621674 | -80.43324786 |
| TW D-2 | 420 | 205 | 25.64643546 | -80.43306369 |
| TW D-1 | 415 | 101 | 25.64810466 | -80.43647720 |
| TW D-1 | 415 | 103 | 25.64832338 | -80.43629304 |
| TW D | 412 | 101 | 25.65144737 | -80.43948795 |
| TW D | 411 | 103 | 25.65089066 | -80.44000434 |
| TW D | 410 | 108 | 25.65125627 | -80.44003254 |
| TW D | 405 | 103 | 25.65069795 | -80.43897521 |
| TW D | 405 | 108 | 25.64986333 | -80.43776867 |
| TW D | 405 | 116 | 25.64852793 | -80.43583823 |
| TW D | 405 | 127 | 25.64669171 | -80.43318395 |
| TW D | 405 | 133 | 25.64569012 | -80.43173619 |
| TW H-7 | 370 | 700 | 25.64502882 | -80.42069433 |
| TW H-5 | 350 | 502 | 25.64513504 | -80.42449409 |
| TW H-4 | 340 | 402 | 25.64507053 | -80.42649235 |
| TW H-3 | 330 | 300 | 25.64463774 | -80.42864454 |
| TW C-3 | 320 | 203 | 25.64615751 | -80.43160949 |
| TW C-1 | 310 | 103 | 25.64687456 | -80.43264622 |
| TW 1 | 270 | 700 | 25.65215770 | -80.42161913 |
| TW 2 | 260 | 602 | 25.65183493 | -80.42296382 |
| TW 3 | 250 | 502 | 25.65175100 | -80.42495452 |
| TW 4 | 240 | 400 | 25.65200673 | -80.42637465 |
| TW 5 | 230 | 302 | 25.65163039 | -80.42781398 |
| TW 7 | 210 | 102 | 25.65149836 | -80.43107122 |
| TW A-3 | 125 | 302 | 25.65272366 | -80.42504244 |
| TW A-3 | 125 | 304 | 25.65244608 | -80.42501747 |
| TW A-3 | 124 | 101 | 25.65285323 | -80.42532547 |
| TW A-2 | 120 | 201 | 25.65265314 | -80.42997854 |

| h | | | | |
|--------|---------|--------|-------------|--------------|
| Branch | Section | Sample | Latitude | Longitude |
| TW A-2 | 120 | 203 | 25.65237830 | -80.42996442 |
| TW A-1 | 115 | 101 | 25.65244177 | -80.43498489 |
| TW A-1 | 115 | 103 | 25.65216693 | -80.43497076 |
| TW A | 111 | 103 | 25.65197001 | -80.43963141 |
| TW A | 110 | 105 | 25.65168382 | -80.43988563 |
| TW A | 108 | 148 | 25.65217372 | -80.42502029 |
| TW A | 105 | 105 | 25.65162330 | -80.43805918 |
| TW A | 105 | 113 | 25.65172579 | -80.43563335 |
| TW A | 105 | 121 | 25.65182824 | -80.43320751 |
| TW A | 105 | 129 | 25.65193065 | -80.43078167 |
| TW A | 105 | 133 | 25.65198184 | -80.42956875 |
| TW A | 105 | 137 | 25.65203303 | -80.42835583 |
| TW A | 105 | 145 | 25.65213727 | -80.42588450 |
| TW A | 105 | 150 | 25.65219929 | -80.42441382 |
| TW A | 105 | 154 | 25.65225043 | -80.42320090 |
| TW A | 105 | 158 | 25.65230139 | -80.42198826 |
| TW 6 | 22 | 200 | 25.65186207 | -80.42977973 |



DESIGNED: KHA DRAWN: KHA CHECKED: KHA DATE:



KENDALL-TAMIAMI EXECUTIVE AIRPORT MIAMI-DADE COUNTY, FLORIDA FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

6

Table A-1: Pavement Inventory

| Branch Name | Branch ID | Branch Use | Section ID | Length (ft) | Width (ft) | True Area (ft2) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Sample Units in Section |
|-----------------|-----------|---------------|---------------|-------------|------------|-----------------------|-----------------|-----------------|------------------------|-----------------------|-------------------------------|
| North Apron | AP N | APRON | 4205 | 2800 | 300 | 840,000 | P | AAC | 1/1/2006 | 3/26/2012 | 168 |
| North Apron | AP N | APRON | 4215 | 200 | 300 | 60,000 | P | AAC | 1/1/2006 | 3/26/2012 | 12 |
| North Apron | AP N | APRON | 4220 | 365 | 300 | 109,500 | P | AAC | 1/1/1994 | 3/26/2012 | 24 |
| North Apron | AP N | APRON | 4225 | 2300 | 30 | 69,490 | P | AC | 12/25/1999 | 3/26/2012 | 20 |
| North Apron | AP N | APRON | 4230 | 150 | 100 | 18,795 | P | AC | 12/25/1999 | 3/26/2012 | 3 |
| Northeast Apron | AP NE | APRON | 4305 | 190 | 50 | 9,600 | P | PCC | 12/25/1999 | 3/26/2012 | 3 |
| Northeast Apron | AP NE | APRON | 4310 | 200 | 90 | 19,797 | P | AC | 12/25/1999 | 3/26/2012 | 5 |
| Northeast Apron | AP NE | APRON | 4315 | 200 | 85 | 21,176 | P | AC | 12/25/1999 | 3/26/2012 | 5 |
| Northeast Apron | AP NE | APRON | 4320 | 180 | 50 | 9,216 | P | PCC | 12/25/1999 | 3/26/2012 | 3 |
| Northeast Apron | AP NE | APRON | 4325 | 495 | 100 | 49,524 | P | AC | 12/25/1999 | 3/26/2012 | 12 |
| Northeast Apron | AP NE | APRON | 4330 | 60 | 45 | 2,700 | P | PCC | 12/25/1999 | 3/26/2012 | 1 |
| South Apron | AP S | APRON | 4105 | 700 | 300 | 210,000 | P | AC | 1/1/1998 | 3/26/2012 | 42 |
| South Apron | AP S | APRON | 4110 | 800 | 300 | 240,843 | P | AAC | 1/1/1998 | 3/26/2012 | 48 |
| South Apron | AP S | APRON | 4115 | 2775 | 300 | 832,515 | P | AAC | 1/1/1998 | 3/26/2012 | 168 |
| South Apron | AP S | APRON | 4125 | 230 | 150 | 35,371 | T | AC | 12/25/1999 | 3/26/2012 | 7 |
| South Apron | AP S | APRON | 4130 | 264 | 50 | 19,714 | P | AC | 12/25/1999 | 3/26/2012 | 6 |
| South Apron | AP S | APRON | 4135 | 750 | 36 | 29,788 | P | AC | 12/25/1999 | 3/26/2012 | 8 |
| South Apron | AP S | APRON | 4140 | 1400 | 30 | 43,874 | P | AC | 12/25/1999 | 3/26/2012 | 16 |
| Southeast Apron | AP SE | APRON | 4410 | 400 | 100 | 45,220 | P | AC | 12/25/1999 | 3/26/2012 | 8 |
| Runway 13-31 | RW 13-31 | RUNWAY | 6205 | 4002 | 100 | 400,200 | P | AAC | 1/1/2004 | 3/26/2012 | 80 |
| Runway 13-31 | RW 13-31 | RUNWAY | 6210 | 8004 | 25 | 200,100 | P | AAC | 1/1/2004 | 3/26/2012 | 40 |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6104 | 200 | 100 | 20,000 | P | AC | 1/1/2001 | 3/26/2012 | 4 |

Table A-1: Pavement Inventory (Continued)

| Branch Name | Branch ID | Branch Use | Section ID | Length (ft) | Width (ft) | True Area (ft2) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Sample Units in Section |
|---------------|-----------|---------------|---------------|-------------|------------|-----------------------|-----------------|-----------------|------------------------|-----------------------|-------------------------------|
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6105 | 4600 | 100 | 460,000 | P | AC | 1/1/2001 | 3/26/2012 | 92 |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6109 | 400 | 25 | 10,000 | P | AC | 1/1/2001 | 3/26/2012 | 2 |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6110 | 9200 | 25 | 230,000 | P | AC | 1/1/2001 | 3/26/2012 | 46 |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6126 | 404 | 25 | 10,100 | P | AC | 1/1/2001 | 3/26/2012 | 2 |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6131 | 202 | 100 | 20,200 | P | AC | 1/1/2001 | 3/26/2012 | 4 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6302 | 1000 | 100 | 100,000 | P | AC | 1/1/2012 | 1/1/2012 | 20 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6304 | 200 | 100 | 20,000 | P | AAC | 1/1/2012 | 1/1/2012 | 4 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6305 | 4600 | 100 | 460,000 | P | AAC | 1/1/1997 | 3/26/2012 | 92 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6306 | 201 | 100 | 20,100 | P | AC | 1/1/1997 | 3/26/2012 | 4 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6307 | 2000 | 25 | 50,000 | P | AC | 1/1/2012 | 1/1/2012 | 10 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6309 | 400 | 25 | 10,000 | P | AAC | 1/1/2012 | 1/1/2012 | 2 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6310 | 9200 | 25 | 230,000 | P | AAC | 1/1/1997 | 3/26/2012 | 46 |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6311 | 402 | 25 | 10,050 | P | AC | 1/1/1997 | 3/26/2012 | 2 |
| Taxiway 1 | TW 1 | TAXIWAY | 270 | 200 | 50 | 12,843 | P | AAC | 1/1/2006 | 3/26/2012 | 2 |
| Taxiway 2 | TW 2 | TAXIWAY | 260 | 200 | 90 | 19,697 | P | AAC | 1/1/2006 | 3/26/2012 | 4 |
| Taxiway 3 | TW 3 | TAXIWAY | 250 | 200 | 90 | 19,697 | P | AAC | 1/1/2006 | 3/26/2012 | 4 |
| Taxiway 4 | TW 4 | TAXIWAY | 240 | 200 | 90 | 19,697 | P | AAC | 1/1/2006 | 3/26/2012 | 4 |
| Taxiway 5 | TW 5 | TAXIWAY | 230 | 200 | 90 | 19,697 | P | AAC | 1/1/2006 | 3/26/2012 | 4 |
| Taxiway 6 | TW 6 | TAXIWAY | 220 | 200 | 90 | 19,697 | P | AAC | 1/1/2006 | 3/26/2012 | 4 |
| Taxiway 7 | TW 7 | TAXIWAY | 210 | 200 | 90 | 18,557 | P | AAC | 1/1/2005 | 3/26/2012 | 4 |
| Taxiway Alpha | TW A | TAXIWAY | 105 | 5500 | 50 | 279,576 | P | AAC | 1/1/2005 | 3/26/2012 | 56 |
| Taxiway Alpha | TW A | TAXIWAY | 108 | 370 | 50 | 18,500 | P | AAC | 1/1/2005 | 3/26/2012 | 4 |

Table A-1: Pavement Inventory (Continued)

| Branch Name | Branch ID | Branch Use | Section ID | Length (ft) | Width (ft) | True Area (ft2) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Sample Units in Section |
|---------------------|-----------|---------------|---------------|-------------|---------------|-----------------------|-----------------|-----------------|------------------------|-----------------------|-------------------------------|
| Taxiway Alpha | TW A | TAXIWAY | 110 | 360 | 100 | 36,180 | P | AC | 1/1/2001 | 3/26/2012 | 7 |
| Taxiway Alpha | TW A | TAXIWAY | 111 | 300 | 75 | 27,392 | P | AC | 12/25/1999 | 3/26/2012 | 6 |
| Taxiway A-1 | TW A1 | TAXIWAY | 115 | 300 | 75 | 50,475 | P | AC | 1/1/2001 | 3/26/2012 | 14 |
| Taxiway A-2 | TW A2 | TAXIWAY | 120 | 300 | 75 | 50,475 | P | AC | 1/1/2001 | 3/26/2012 | 14 |
| Taxiway A-3 | TW A3 | TAXIWAY | 124 | 300 | 75 | 26,792 | P | AC | 12/25/1999 | 3/26/2012 | 6 |
| Taxiway A-3 | TW A3 | TAXIWAY | 125 | 320 | 100 | 32,146 | P | AC | 1/1/2001 | 3/26/2012 | 6 |
| Taxiway to NE Apron | TW AP NE | TAXIWAY | 1005 | 1200 | 35 | 44,691 | P | AC | 12/25/1999 | 3/26/2012 | 13 |
| Taxiway to SE Apron | TW AP SE | TAXIWAY | 1105 | 1400 | 30 | 42,727 | P | AC | 12/25/1999 | 3/26/2012 | 10 |
| Taxiway Charlie | TW C | TAXIWAY | 910 | 2600 | 50 | 138,069 | P | AC | 1/1/1998 | 3/26/2012 | 27 |
| Taxiway C-1 | TW C1 | TAXIWAY | 310 | 190 | 90 | 17,644 | P | AAC | 1/1/1997 | 3/26/2012 | 5 |
| Taxiway C-2 | TW C2 | TAXIWAY | 320 | 190 | 90 | 17,567 | P | AAC | 1/1/1997 | 3/26/2012 | 5 |
| Taxiway CC | TW CC | TAXIWAY | 905 | 125 | 50 | 7,838 | P | AC | 1/1/1998 | 3/26/2012 | 2 |
| Taxiway Delta | TW D | TAXIWAY | 405 | 4200 | 50 | 210,898 | P | AC | 1/1/2001 | 3/26/2012 | 43 |
| Taxiway Delta | TW D | TAXIWAY | 410 | 361 | 100 | 36,142 | P | AC | 1/1/2001 | 3/26/2012 | 7 |
| Taxiway Delta | TW D | TAXIWAY | 411 | 300 | 75 | 27,092 | P | AC | 1/1/2001 | 3/26/2012 | 6 |
| Taxiway Delta | TW D | TAXIWAY | 412 | 100 | 100 | 10,004 | P | AC | 1/1/2001 | 3/26/2012 | 2 |
| Taxiway D-1 | TW D1 | TAXIWAY | 415 | 500 | 100 | 50,475 | P | AC | 1/1/2001 | 3/26/2012 | 14 |
| Taxiway D-2 | TW D2 | TAXIWAY | 420 | 300 | 75 | 50,463 | P | AC | 1/1/2001 | 3/26/2012 | 14 |
| Taxiway Echo | TW E | TAXIWAY | 503 | 1120 | 50 | 56,119 | P | AC | 1/1/2012 | 1/1/2012 | 11 |
| Taxiway Echo | TW E | TAXIWAY | 505 | 4700 | 50 | 238,386 | P | AAC | 1/1/2007 | 3/26/2012 | 47 |
| Taxiway Echo | TW E | TAXIWAY | 507 | 200 | 150 | 30,930 | P | AAC | 1/1/2007 | 3/26/2012 | 7 |
| Taxiway Echo | TW E | TAXIWAY | 510 | 600 | 50 | 32,263 | P | AAC | 1/1/2007 | 3/26/2012 | 7 |

Pavement Evaluation Report –Kendall-Tamiami Executive Airport Florida Statewide Airfield Pavement Management Program May 2012

Table A-1: Pavement Inventory (Continued)

| Branch Name | Branch ID | Branch Use | Section ID | Length (ft) | Width (ft) | True Area (ft2) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Sample Units in Section |
|-----------------|-----------|---------------|---------------|-------------|------------|-----------------------|-----------------|-----------------|------------------------|-----------------------|-------------------------------|
| Taxiway Echo | TW E | TAXIWAY | 513 | 300 | 170 | 54,092 | P | AC | 1/1/2012 | 1/1/2012 | 12 |
| Taxiway E-1 | TW E1 | TAXIWAY | 515 | 210 | 100 | 21,049 | P | AAC | 1/1/2012 | 1/1/2012 | 4 |
| Taxiway E-1 | TW E1 | TAXIWAY | 516 | 388 | 100 | 38,835 | P | AC | 12/25/1999 | 3/26/2012 | 8 |
| Taxiway E-2 | TW E2 | TAXIWAY | 520 | 300 | 75 | 50,474 | P | AAC | 1/1/2007 | 3/26/2012 | 14 |
| Taxiway E-3 | TW E3 | TAXIWAY | 525 | 300 | 75 | 41,823 | P | AAC | 1/1/2007 | 3/26/2012 | 11 |
| Taxiway E-4 | TW E4 | TAXIWAY | 527 | 300 | 50 | 26,267 | P | AC | 1/1/1996 | 3/26/2012 | 7 |
| Taxiway E-5 | TW E5 | TAXIWAY | 529 | 300 | 75 | 26,192 | P | AC | 12/25/1999 | 3/26/2012 | 6 |
| Taxiway E-5 | TW E5 | TAXIWAY | 530 | 300 | 90 | 32,146 | P | AAC | 1/1/1999 | 3/26/2012 | 6 |
| Taxiway Foxtrot | TW F | TAXIWAY | 605 | 1050 | 50 | 57,730 | P | AAC | 1/1/1998 | 3/26/2012 | 12 |
| Taxiway Golf | TW G | TAXIWAY | 705 | 1000 | 50 | 51,622 | P | AAC | 1/1/2006 | 3/26/2012 | 10 |
| Taxiway Golf | TW G | TAXIWAY | 710 | 340 | 50 | 17,106 | P | AC | 1/1/1997 | 3/26/2012 | 3 |
| Taxiway Hotel | TW H | TAXIWAY | 815 | 2200 | 50 | 119,042 | P | AAC | 1/1/2007 | 3/26/2012 | 25 |
| Taxiway H-1 | TW H1 | TAXIWAY | 805 | 90 | 50 | 4,802 | P | AC | 1/1/1998 | 3/26/2012 | 1 |
| Taxiway H-2 | TW H2 | TAXIWAY | 810 | 75 | 100 | 7,744 | P | AC | 1/1/1998 | 3/26/2012 | 2 |
| Taxiway H-3 | TW H3 | TAXIWAY | 330 | 200 | 90 | 18,456 | P | AAC | 1/1/2007 | 3/26/2012 | 4 |
| Taxiway H-4 | TW H4 | TAXIWAY | 340 | 190 | 90 | 17,255 | P | AAC | 1/1/2007 | 3/26/2012 | 4 |
| Taxiway H-5 | TW H5 | TAXIWAY | 350 | 200 | 90 | 19,697 | P | AAC | 1/1/2007 | 3/26/2012 | 4 |
| Taxiway H-6 | TW H6 | TAXIWAY | 360 | 200 | 90 | 19,697 | P | AAC | 1/1/2007 | 3/26/2012 | 4 |
| Taxiway H-7 | TW H7 | TAXIWAY | 370 | 190 | 50 | 12,809 | P | AAC | 1/1/2007 | 3/26/2012 | 2 |

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

L.C.D.: 01/01/2006 Use: APRON

Branch: AP N

Network: TMB

Work History Report

Pavement Database:

Rank P Length:

(NORTH APRON) Section: 4205 Surface: AAC

Width:

300.00 Ft

1 of 12

True Area:840,000.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|--------------|--------------|---------------------|------|--------------------|--------------|--|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1967 | IMPORTED | BUILT | | 2.00 | True | 1967: 2" P-401 ON 8" P-401 |
| 01/01/1967 | IMPORTED | OVERLAY | | | | PART OF THIS FEATURE HAS AN EMULSION SEAL |

2,800.00 Ft

 Network:
 TMB
 Branch:
 AP N
 (NORTH APRON)
 Section:
 4215
 Surface:
 AAC

 L.C.D.:
 01/01/2006
 Use:
 APRON
 Rank P Length:
 200.00 Ft
 Width:
 300.00 Ft
 True Area:
 60,000.00 SqF

| Work Date | Work Code | Work Description | Cost | Cost Thickness Maj | | Comments |
|--------------|--------------|---------------------|------|--------------------|------|----------------------------|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1965 | IMPORTED | BUILT | | 2.00 | True | 1965: 2" P-401 ON 8" P-211 |

 Network:
 TMB
 Branch:
 AP N
 (NORTH APRON)
 Section:
 4220
 Surface:
 AAC

 L.C.D.:
 01/01/1994
 Use:
 APRON
 Rank P Length:
 365.00 Ft
 Width:
 300.00 Ft
 True Area;109,500.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|--------------|--------------|---------------------|------|--------------------|--------------|--|
| 01/01/1994 | IMPORTED | OVERLAY | | | | THIS FEATURE WAS <= 2 YRS OLD AT TIME OF SURVEY AND WAS NOT NSPECTED |
| 01/01/1994 | IMPORTED | OVERLAY | | 1.50 | True | 1994: 1.5" - 2" P-401 OVERLAY |
| 01/01/1965 | IMPORTED | BUILT | | 2.00 | True | 1965: 2" P-401 ON 8" P-211 |

 Network:
 TMB
 Branch:
 AP N
 (NORTH APRON)
 Section:
 4225
 Surface:
 AC

 L.C.D.:
 12/25/1999
 Use:
 APRON
 Rank P Length:
 2,300.00 Ft
 Width:
 30.00 Ft
 True Area:
 69,490.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|--------------|--------------|----------------------|------|-------------------|--------------|----------|
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

 Network:
 TMB
 Branch:
 AP N
 (NORTH APRON)
 Section:
 4230
 Surface:
 AC

 L.C.D.:
 12/25/1999
 Use:
 APRON
 Rank P Length:
 150.00 Ft
 Width:
 100.00 Ft
 True Area:
 18,794.76
 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|--------------|--------------|----------------------|------|--------------------|--------------|----------|
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

 Network:
 TMB
 Branch:
 AP NE
 (NORTHEAST APRON)
 Section:
 4305
 Surface:
 PCC

 L.C.D.:
 12/25/1999
 Use:
 APRON
 Rank P Length:
 190.00 Ft
 Width:
 50.00 Ft
 True Area:
 9,600.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|--------------|--------------|----------------------|------|--------------------|--------------|----------|
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

 Network:
 TMB
 Branch:
 AP NE
 (NORTHEAST APRON)
 Section:
 4310
 Surface:
 AC

 L.C.D.:
 12/25/1999
 Use:
 APRON
 Rank P Length:
 200.00 Ft
 Width:
 90.00 Ft
 True Area:
 19.797.46 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | | Comments |
|--------------|--------------|----------------------|------|----------------|------|----------|
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

 Network:
 TMB
 Branch:
 AP NE
 (NORTHEAST APRON)
 Section:
 4315
 Surface:
 AC

 L.C.D.:
 12/25/1999
 Use:
 APRON
 Rank P Length:
 200.00 Ft
 Width:
 85.00 Ft
 True Area:
 21.176.35 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|--------------|--------------|----------------------|------|--------------------|--------------|----------|
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Date

Code

Description

Work History Report

2 of 12 Pavement Database: Network: TMB Branch: AP NE (NORTHEAST APRON) Section: 4320 Surface: PCC L.C.D.: 12/25/1999 Use: APRON 50.00 Ft Rank P Length: 180.00 Ft Width: True Area: 9,216.00 SqF Work Work Work Thickness Major Comments Cost Description Date Code (in) M&R 12/25/1999 INITIAL **Initial Construction** \$0 0.00 True Network: TMB Branch: AP NE (NORTHEAST APRON) Section: 4325 Surface: AC L.C.D.: 12/25/1999 Use: APRON Rank P Length: True Area: 49.524.03 SqF 495.00 Ft Width: 100.00 Ft Work Work Thickness Major Comments Cost Description Date Code (in) M&R 12/25/1999 INITIAL **Initial Construction** \$0 0.00 True Network: TMB Branch: AP NE (NORTHEAST APRON) Section: 4330 Surface: PCC L.C.D.: 12/25/1999 Use: APRON Rank P Length: 60.00 Ft Width: 45.00 Ft True Area: 2,700.00 SqF Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 12/25/1999 INITIAL **Initial Construction** \$0 0.00 True Network: TMB Branch: AP S Section: 4105 Surface: AC (SOUTH APRON) L.C.D.: 01/01/1998 Use: APRON Rank P Length: 700.00 Ft Width: 300.00 Ft True Area:210.000.00 SqF Work Work Thickness Major Comments Cost Date Code Description (in) M&R 1998 AC PAVEMENT (FIELD 01/01/1998 **IMPORTED BUILT** True OBSERVATION) Network: TMB (SOUTH APRON) Surface: AAC Branch: AP S Section: 4110 L.C.D.: 01/01/1998 Use: APRON Rank P Length: 800.00 Ft 300.00 Ft True Area:240.842.74 SqF Width: Work Work Thickness Work Major Comments Cost Date Code Description (in) M&R 01/01/1998 **IMPORTED OVERLAY** True 1998 AC overlay 01/01/1967 **IMPORTED BUILT** 2.00 True 1967: 2" P-401 ON 8" P-401 Network: TMB Branch: AP S (SOUTH APRON) Section: 4115 Surface: AAC L.C.D.: 01/01/1998 Use: APRON Rank P Length: 2,775.05 Ft Width: 300.00 Ft True Area:832,515.06 SqF Work Work Work Thickness Major Comments Cost Date Description M&R Code (in) 01/01/1998 ML-OL Mill and Overlay \$0 0.00 True 01/01/1967 **IMPORTED** RI III T 2.00 True 1967: 2" P-401 ON 8" P-401 THIS FEATURE HAS SAME PVT. **IMPORTED OVERLAY** 01/01/1967 True SECTION AS 4110 - HOWEVER THEY WERE BUILT U THIS FEATURE HAS AN EMULSION 01/01/1967 **IMPORTED OVERLAY** True SEAL Network: TMB Branch: AP S (SOUTH APRON) Section: 4125 Surface: AC L.C.D.: 12/25/1999 Use: APRON Rank T Length: Width: 150.00 Ft 230.00 Ft True Area: 35,370.73 SqF Work Work Work Thickness Major Comments

12/25/1999 INITIAL Initial Construction \$0 0.00 True Network: TMB Branch: AP S (SOUTH APRON) Surface: AC Section: 4130 L.C.D.: 12/25/1999 Use: APRON Rank P Length: 264.00 Ft Width: 50.00 Ft True Area: 19,714.38 SqF Work Work Work Thickness Major Comments Cost (in) M&R Date Code Description 12/25/1999 INITIAL Initial Construction \$0 0.00 True

Cost

M&R

(in)

Work History Report

3 of 12

Pavement Database:

(SOUTH APRON) Network: TMB Branch: AP S Section: 4135 Surface: AC L.C.D.: 12/25/1999 Use: APRON 750.00 Ft 36.00 Ft Rank P Length: Width: True Area: 29,788.29 SqF Work Work Work Thickness Major Comments Cost Description Date Code (in) M&R 12/25/1999 INITIAL Initial Construction \$0 0.00 True Network: TMB Branch: AP S (SOUTH APRON) Section: 4140 Surface: AC L.C.D.: 12/25/1999 Use: APRON Rank P Length: 1,400.00 Ft Width: 30.00 Ft True Area: 43.873.95 SqF Work Work Thickness Major Comments Cost Date Code Description (in) M&R 12/25/1999 INITIAL **Initial Construction** 0.00 True Network: TMB Branch: AP SE (SOUTHEAST APRON) Section: 4410 Surface: AC L.C.D.: 12/25/1999 Use: APRON Rank P Length: 400.00 Ft Width: 100.00 Ft True Area: 45,220.00 SqF Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 12/25/1999 INITIAL **Initial Construction** \$0 0.00 True Network: TMB Branch: RW 13-31 Section: 6205 Surface: AAC (RUNWAY 13-31) L.C.D.: 01/01/2004 Use: RUNWAY Rank P Length: 4,002.00 Ft Width: 100.00 Ft True Area:400.200.00 SqF Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2004 ML-OL Mill and Overlay \$0 0.00 True 01/01/1965 **IMPORTED BUILT** 2.00 True 1965: 2" P-401 ON 8" P-211 Branch: RW 13-31 Network: TMB (RUNWAY 13-31) Section: 6210 Surface: AAC L.C.D.: 01/01/2004 Use: RUNWAY True Area:200,100.00 SqF Rank P Length: 8,004.00 Ft Width: 25.00 Ft Major Work Work Work Thickness Comments Cost Date Code Description (in) M&R 01/01/2004 ML-OL Mill and Overlay \$0 0.00 True 01/01/1965 **IMPORTED BUILT** 2.00 True 1965: 2" P-401 ON 8" P-211 Branch: RW 9L-27R (RUNWAY 9L-27R) Network: TMB Section: 6104 Surface: AC L.C.D.: 01/01/1997 Use: RUNWAY Rank P Length: True Area: 20,000.00 SqF 200.00 Ft Width: 100.00 Ft Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2001 SS-RE Surface Seal - Rejuvenating 0.00 False BUILT 01/01/1997 **IMPORTED** True 1997 AC construction (field observation) Network: TMB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6105 Surface: AC L.C.D.: 01/01/1965 Use: RUNWAY Rank P Length: 4,600.00 Ft Width: 100.00 Ft True Area:460.000.00 SqF Work Work Work Thickness Major Comments Cost Description Date Code M&R (in) Surface Seal - Rejuvenating 01/01/2001 SS-RE \$0 0.00 False **BUILT** 01/01/1965 **IMPORTED** 2.00 True 1965: 2" P-401 ON 8" P-211 Network: TMB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6109 Surface: AC L.C.D.: 01/01/1997 Use: RUNWAY Rank P Length: 400.00 Ft Width: 25.00 Ft True Area: 10.000.00 SqF Work Work Work Thickness Major Comments Cost Date Code Description M&R (in) 01/01/2001 0.00 SS-RE Surface Seal - Rejuvenating \$0 False 01/01/1997 **IMPORTED BUILT** True 1997 AC CONSTRUCTION (FIELD

Work History Report

Pavement Database:

Pavement Database:

4 of 12

Network: TMB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6110 Surface: AC L.C.D.: 01/01/1965 Use: RUNWAY Rank P Length: 25.00 Ft True Area:230,000.00 SqF 9,200.00 Ft Width: Work Work Thickness Major Comments Cost Date Code Description (in) M&R Surface Seal - Rejuvenating 01/01/2001 SS-RE \$0 0.00 False **IMPORTED BUILT** 01/01/1965 2.00 True 1965: 2" P-401 ON 8" P-211 Network: TMB Branch: RW 9L-27R Surface: AC (RUNWAY 9L-27R) Section: 6126 L.C.D.: 01/01/1997 Use: RUNWAY Rank P Length: 404.00 Ft Width: 25.00 Ft True Area: 10,100.00 SqF Work Work Thickness Major Comments Cost M&R Date Code Description (in) 01/01/2001 SS-RE Surface Seal - Rejuvenating 0.00 False 01/01/1997 **IMPORTED BUILT** True 1997 AC (FIELD OBSERVATION) Branch: RW 9L-27R Network: TMB (RUNWAY 9L-27R) Section: 6131 Surface: AC L.C.D.: 01/01/1997 Use: RUNWAY True Area: 20.200.00 SqF Rank P Length: 202.00 Ft 100.00 Ft Width: Work Work Work Thickness Major Cost Comments M&R Date Code Description (in) 01/01/2001 SS-RF Surface Seal - Rejuvenating \$0 0.00 False **IMPORTED** 1997 AC PAVEMENT (FIELD 01/01/1997 **BUILT** True OBSERVATION) Network: TMB Branch: RW 9R-27L (RUNWAY 9R-27L) Section: 6302 Surface: AC L.C.D.: 01/01/2012 Use: RUNWAY Rank P Length: 1.000.00 Ft Width: 100.00 Ft True Area:100.000.00 SqF Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2012 INITIAL **Initial Construction** \$0 2012: 4" P-401, 10" P-211, 12" P-154, 8" 4.00 True P-152 Branch: RW 9R-27L (RUNWAY 9R-27L) Surface: AAC Network: TMB Section: 6304 L.C.D.: 01/01/2012 Use: RUNWAY True Area: 20,000.00 SqF Rank P Length: 200.00 Ft Width: 100.00 Ft Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2012 ML-OL Mill and Overlay \$0 0.00 True **BUILT** 1997 AC PAVEMENT (FIELD 01/01/1997 **IMPORTED** True OBSERVATION) Network: TMB Branch: RW 9R-27L (RUNWAY 9R-27L) Section: 6305 Surface: AAC L.C.D.: 01/01/1997 Use: RUNWAY Rank P Length: 4.600.00 Ft Width: 100.00 Ft True Area:460,000.00 SqF Work Work Thickness Major Comments Cost M&R Date Code Description (in) 01/01/1997 ML-OL Mill and Overlay \$0 0.00 True 01/01/1967 **IMPORTED BUILT** 2.00 True 1967: 2" P-401 ON 8" P-401 Surface: AC Branch: RW 9R-27L Network: TMB (RUNWAY 9R-27L) Section: 6306 L.C.D.: 01/01/1997 Use: RUNWAY Rank P Length: 201.00 Ft Width: 100.00 Ft True Area: 20.100.00 SqF Work Work Work Thickness Maior Comments Cost Date Code Description (in) M&R 1997 AC PAVEMENT (FIELD 01/01/1997 **IMPORTED BUILT** OBSERVATION) Network: TMB (RUNWAY 9R-27L) Section: 6307 Surface: AC Branch: RW 9R-27L L.C.D.: 01/01/2012 Use: RUNWAY 2,000.00 Ft 25.00 Ft Rank P Length: Width: True Area: 50,000.00 SqF Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R INITIAL **Initial Construction** 01/01/2012 \$0 4.00 True 2012: 4" P-401, 10" P-211, 12" P-154, 8" P-152

Work History Report

Pavement Database:

(RUNWAY 9R-27L) Section: 6309 Surface: AAC

5 of 12

| Network: Th | MB Br : 1/2012 Use: RU | · · | Y 9R-27L) 400.00 Ft | \A/: al4b - | Section: 6309 Surface: AAC 25.00 Ft True Area: 10,000.00 SqF | | | |
|---|--|---|--|---------------------------------|---|--|--|--|
| Work | Work | Work Vork | | Width: Thickness | Maior | | | |
| Date | Code | Description | Cost | (in) | M&R Comments | | | |
| 01/01/2012 01/01/1997 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | 0.00 | True 1997 AC PAVEMENT (FIELD OBSERVATION) | | | |
| Network: TN L.C.D.: 01/01 | MB Br 1/1997 Use : RL | · · | Y 9R-27L) 9,200.00 Ft | Width: | Section: 6310 Surface: AAC 25.00 Ft True Area: 230,000.00 SqF | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R Comments | | | |
| 01/01/1997 01/01/1967 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | 0.00 2.00 | True True 2" P-401 ON 8" P-401 | | | |
| Network: TMB Branch: RW 9R-27L (RUNWAY 9R-27L) Section: 6311 Surface: AC L.C.D.: 01/01/1997 Use: RUNWAY Rank P Length: 402.00 Ft Width: 25.00 Ft True Area: 10.050.00 SqF | | | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R Comments | | | |
| 01/01/1997 | IMPORTED | BUILT | | | True 1997 AC PAVEMENT (FIELD OBSERVATION) | | | |
| Network: TN L.C.D.: 01/01 | MB Br : 1/2006 Use: TA | anch: TW 1 (TAXIWA XIWAY Rank P Length: | Y 1) 200.00 Ft | Width: | Section: 270 Surface: AAC 50.00 Ft True Area: 12,842.70 SqF | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R Comments | | | |
| 01/01/2006 01/01/1967 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | 0.00 2.00 | True 1967: 2" P-401 ON 8" P-401 | | | |
| Network: TN L.C.D.: 01/01 | MB Br 1/2006 Use: TA | anch: TW 2 (TAXIWA XIWAY Rank P Length: | Y 2) 200.00 Ft | Width: | Section: 260 Surface: AAC 90.00 Ft True Area: 19,697.18 SqF | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R Comments | | | |
| 01/01/2006 01/01/1967 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | 0.00 2.00 | True | | | |
| Network: TN L.C.D.: 01/01 | MB B r: 1/2006 Use : TA | anch: TW 3 (TAXIWA XIWAY Rank P Length: | - * | Width: | Section: 250 Surface: AAC 90.00 Ft True Area: 19,697.18 SqF | | | |
| Work Date | Work Code | Work Description | | Thickness (in) | Major M&R Comments | | | |
| 01/01/2006 01/01/1967 | ML-OL | • | | ` ' | | | | |
| | | Mill and Overlay BUII T | \$0 | 0.00 2.00 | True 1967: 2" P-401 ON 8" P-401 | | | |
| Network: Th | IMPORTED | BUILT anch: TW 4 (TAXIWA | · | 0.00 2.00 Width: | True 1967: 2" P-401 ON 8" P-401 Section: 240 Surface: AAC 90.00 Ft True Area: 19.697.18 SqF | | | |
| Network: Th | IMPORTED MB Br | BUILT anch: TW 4 (TAXIWA | Y 4) 200.00 Ft | 2.00 | True 1967: 2" P-401 ON 8" P-401 Section: 240 Surface: AAC | | | |
| Network: TN L.C.D.: 01/01 Work | IMPORTED MB Br. 1/2006 Use: TA Work | BUILT anch: TW 4 (TAXIWA XIWAY Rank P Length: Work | Y 4) 200.00 Ft | 2.00 Width: Thickness | True 1967: 2" P-401 ON 8" P-401 Section: 240 Surface: AAC 90.00 Ft True Area: 19.697.18 SqF Major | | | |
| Network: TN L.C.D.: 01/01 Work Date 01/01/2006 01/01/1967 Network: TN | MB Br. 1/2006 Use: TA Work Code ML-OL IMPORTED | BUILT anch: TW 4 XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW 5 (TAXIWA | Y 4) 200.00 Ft Cost \$0 | Width: Thickness (in) 0.00 | True 1967: 2" P-401 ON 8" P-401 Section: 240 Surface: AAC 90.00 Ft True Area: 19.697.18 SqF Major M&R Comments True | | | |
| Network: TN L.C.D.: 01/01 Work Date 01/01/2006 01/01/1967 Network: TN | MB Br. 1/2006 Use: TA Work Code ML-OL IMPORTED MB Br. | BUILT anch: TW 4 XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW 5 (TAXIWA | Y 4) 200.00 Ft Cost \$0 Y 5) 200.00 Ft | Width: Thickness (in) 0.00 2.00 | True 1967: 2" P-401 ON 8" P-401 Section: 240 Surface: AAC 90.00 Ft True Area: 19.697.18 SqF Major M&R Comments True True 1967: 2" P-401 ON 8" P-401 Section: 230 Surface: AAC | | | |

Work History Report

6 of 12

Pavement Database:

Network: TMB Branch: TW 6 (TAXIWAY 6) Section: 220 Surface: AAC L.C.D.: 01/01/2006 Use: TAXIWAY 200.00 Ft 90.00 Ft True Area: 19,696.66 SqF Rank P Length: Width: Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2006 ML-OL Mill and Overlay \$0 0.00 True **IMPORTED BUILT** 01/01/1967 2.00 True 1967: 2" P-401 ON 8" P-401 Network: TMB Branch: TW 7 Surface: AAC (TAXIWAY 7) Section: 210 L.C.D.: 01/01/2005 Use: TAXIWAY Rank P Length: 200.00 Ft Width: 90.00 Ft True Area: 18,557.11 SqF Work Work Thickness Major Comments Cost M&R Date Code Description (in) 01/01/2005 ML-OL Mill and Overlay 0.00 01/01/1965 **IMPORTED BUILT** 2.00 True 1965: 2" P-401 ON 8" P-211 Network: TMB Branch: TW A (TAXIWAY A) Surface: AAC Section: 105 **L.C.D.:** 01/01/2005 **Use:** TAXIWAY True Area:279.575.51 SqF Rank P Length: 5.500.00 Ft Width: 50.00 Ft Work Work Work Thickness Major Comments Cost Code Description M&R Date (in) 01/01/2005 ML-OL Mill and Overlay \$0 0.00 **IMPORTED BUILT** 1965: 2" P-401 ON 8" P-211 01/01/1965 2.00 True Network: TMB Branch: TW A (TAXIWAY A) Section: 108 Surface: AAC **L.C.D.:** 01/01/2005 **Use:** TAXIWAY Rank P Length: 370.00 Ft Width: 50.00 Ft True Area: 18,500.00 SqF Work Work Work Thickness Major Comments Cost (in) Date Code Description M&R 01/01/2005 ML-OL Mill and Overlay True 0.00 \$0 01/01/1965 INITIAL **Initial Construction** 0.00 True Network: TMB Branch: TW A (TAXIWAY A) Section: 110 Surface: AC L.C.D.: 01/01/1965 Use: TAXIWAY Rank P Length: 360.00 Ft 100.00 Ft Width: True Area: 36,179.51 SqF Work Work Thickness Major Comments Cost Description M&R Date Code (in) 01/01/2001 SS-RE Surface Seal - Rejuvenating \$0 False 0.00 **IMPORTED BUILT** 01/01/1965 2.00 True 1965: 2" P-401 ON 8" P-211 Network: TMB Branch: TW A Surface: AC (TAXIWAY A) Section: 111 L.C.D.: 12/25/1999 Use: TAXIWAY Rank P Length: 300.00 Ft Width: 75.00 Ft True Area: 27.392.04 SqF Work Work Work Thickness Major Comments Cost M&R Date Code Description (in) INITIAL 12/25/1999 \$0 0.00 **Initial Construction** True Network: TMB Branch: TW A1 (TAXIWAY A1) Surface: AC Section: 115 L.C.D.: 01/01/1965 Use: TAXIWAY Rank P Length: 300.00 Ft Width: 75.00 Ft True Area: 50,474.98 SqF Work Work Thickness Major Comments Cost M&R Date Code Description (in) 01/01/2001 Surface Seal - Rejuvenating False SS-RE \$0 0.00 01/01/1965 **IMPORTED BUILT** 2.00 True 1965: 2" P-401 ON 8" P-211 Surface: AC Network: TMB Branch: TW A2 (TAXIWAY A2) Section: 120 **L.C.D.**: 01/01/1965 **Use**: TAXIWAY Rank P Length: 300.00 Ft Width: 75.00 Ft True Area: 50,474.98 SqF Work Work Work Thickness Major Comments Cost Description M&R Date Code (in) 01/01/2001 Surface Seal - Rejuvenating SS-RE \$0 0.00 False 01/01/1965 **IMPORTED BUILT** 1965: 2" P-401 ON 8" P-211 True

Work History Report

7 of 12

Pavement Database:

Network: TMB Branch: TW A3 (TAXIWAY A3) Section: 124 Surface: AC L.C.D.: 12/25/1999 Use: TAXIWAY 75.00 Ft Rank P Length: 300.00 Ft Width: True Area: 26,792.04 SqF Work Work Work Thickness Major Comments Cost Description Date Code (in) M&R 12/25/1999 INITIAL Initial Construction \$0 0.00 True Network: TMB Branch: TW A3 (TAXIWAY A3) Section: 125 Surface: AC L.C.D.: 01/01/1965 Use: TAXIWAY Rank P Length: 320.00 Ft Width: 100.00 Ft True Area: 32,146.02 SqF Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2001 SS-RE Surface Seal - Rejuvenating \$0 0.00 False 1965: 2" P-401 ON 8" P-211 01/01/1965 **IMPORTED BUILT** 2.00 True Branch: TW AP NE (TAXIWAY TO NE APRON) Network: TMB Section: 1005 Surface: AC L.C.D.: 12/25/1999 Use: TAXIWAY Rank P Length: 1,200.00 Ft Width: 35.00 Ft True Area: 44,690.90 SqF Work Work Thickness Major Comments Cost Date Code Description (in) M&R 12/25/1999 INITIAL **Initial Construction** 0.00 True Network: TMB Branch: TW AP SE Surface: AC (TAXIWAY TO SE APRON) Section: 1105 L.C.D.: 12/25/1999 Use: TAXIWAY Rank P Length: 1,400.00 Ft Width: 30.00 Ft True Area: 42,726.72 SqF Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 12/25/1999 INITIAL **Initial Construction** \$0 0.00 True Network: TMB (TAXIWAY C) Section: 910 Surface: AC Branch: TW C L.C.D.: 01/01/1998 Use: TAXIWAY Rank P Length: 2,600.00 Ft Width: 50.00 Ft True Area: 138,068.51 SqF Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/1998 **IMPORTED BUILT** 1998 2" AC SURFACE ON 8" P211 BASE ON 8" P154 SUBBASE Network: TMB Branch: TW C1 (TAXIWAY C1) Section: 310 Surface: AAC L.C.D.: 01/01/1997 Use: TAXIWAY Rank P Length: 190.00 Ft Width: 90.00 Ft True Area: 17.643.88 SqF Work Work Thickness Major Work Comments Cost Date Description M&R Code (in) 01/01/1997 **IMPORTED OVERLAY** 1997 AC SURFACE (FIELD True OBSERVATION) 01/01/1965 **IMPORTED BUILT** 2.00 1965: 2" P-401 ON 8" P-211 Network: TMB (TAXIWAY C2) Surface: AAC Branch: TW C2 Section: 320 L.C.D.: 01/01/1997 Use: TAXIWAY Rank P Length: True Area: 17,567.42 SqF 190.00 Ft Width: 90.00 Ft Work Work Work Thickness Major Cost Comments Date Code Description (in) M&R 01/01/1997 **OVERLAY IMPORTED** True 1997 AC SURFACE 1967: 2" P-401 ON 8" P-401 **IMPORTED BUILT** 01/01/1967 2.00 True Network: TMB Branch: TW CC (TAXIWAY CC) Section: 905 Surface: AC L.C.D.: 01/01/1998 Use: TAXIWAY True Area: 7,838.05 SqF Rank P Length: 125.00 Ft Width: 50.00 Ft Work Work Work Thickness Major Comments Cost Description (in) M&R Date Code **IMPORTED BUILT** 1998 2" P401 AC SURFACE ON 8" P211 01/01/1998 2.00 BASE ON 8" P154 SUBBASE

01/01/1965

IMPORTED

IMPORTED

IMPORTED

BUILT

BUILT

01/01/1965

01/01/1965

BUILT

Work History Report

Pavement Database:

0.00

2.00

False

True

True

True

1965: 2" P-401 ON 8" P-211

1965: 2" P-401 ON 8" P-211

2.00

2.00

1965: 2" P-401 ON 8" P-211

8 of 12

Network: TMB Branch: TW D (TAXIWAY D) Section: 405 Surface: AC L.C.D.: 01/01/1965 Use: TAXIWAY 50.00 Ft Rank P Length: 4,200.00 Ft Width: True Area:210,897.78 SqF Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2001 SS-RE Surface Seal - Rejuvenating \$0

Branch: TW D Surface: AC Network: TMB (TAXIWAY D) Section: 410 L.C.D.: 01/01/1965 Use: TAXIWAY Rank P Length: 361.00 Ft Width: 100.00 Ft True Area: 36,141.84 SqF

Work Work Thickness Major Cost Comments Date Code Description (in) M&R 01/01/2001 SS-RE Surface Seal - Rejuvenating 0.00 False 01/01/1965 **IMPORTED BUILT** 2.00 True 1965: 2" P-401 ON 8" P-211

Network: TMB Branch: TW D (TAXIWAY D) Surface: AC Section: 411 L.C.D.: 12/25/1999 Use: TAXIWAY True Area: 27.092.04 SqF Rank P Length: 300.00 Ft 75.00 Ft Width:

Work Work Work Thickness Major Cost Comments M&R Date Code Description (in) 01/01/2001 SS-RE Surface Seal - Rejuvenating 0.00 False 12/25/1999 INITIAL **Initial Construction** \$0 0.00 True

Network: TMB Branch: TW D (TAXIWAY D) Section: 412 Surface: AC L.C.D.: 12/25/1999 Use: TAXIWAY True Area: 10.003.98 SqF Rank P Length: 100.00 Ft Width: 100.00 Ft

Work Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2001 SS-RE Surface Seal - Rejuvenating False \$0 0.00 12/25/1999 INITIAL **Initial Construction** 0.00 \$0 True

Network: TMB Branch: TW D1 (TAXIWAY D1) Section: 415 Surface: AC L.C.D.: 01/01/1965 Use: TAXIWAY Rank P Length: 500.00 Ft Width: 100.00 Ft True Area: 50,474.98 SqF

Work Work Work Thickness Major Comments Cost Description M&R Date Code (in) 01/01/2001 SS-RE Surface Seal - Rejuvenating \$0 False 0.00

Network: TMB Branch: TW D2 (TAXIWAY D2) Section: 420 Surface: AC L.C.D.: 01/01/1965 Use: TAXIWAY Rank P Length: 300.00 Ft Width: 75.00 Ft True Area: 50,462.90 SqF

Work Work Work Thickness Major Comments Cost M&R Date Code Description (in) Surface Seal - Rejuvenating 01/01/2001 SS-RE \$0 0.00 False

Network: TMB Branch: TW E (TAXIWAY E) Surface: AC Section: 503 L.C.D.: 01/01/2012 Use: TAXIWAY Rank P Length: 1.120.00 Ft Width: 50.00 Ft True Area: 56,118.63 SqF

Work Work Work Thickness Major Comments Cost M&R Date Code Description (in) 01/01/2012 2012: 4" P-401, 10" P-211 LIMEROCK INITIAL **Initial Construction** 4.00 BASE COURSE, 8" P-152 COMPACTED SUB

Network: TMB Surface: AAC Branch: TW E (TAXIWAY E) Section: 505 **L.C.D.**: 01/01/2007 **Use**: TAXIWAY Rank P Length: 4,700.00 Ft Width: 50.00 Ft True Area:238,386.04 SqF

| Work Date | Work Code | Work Description | Cost | Thickness Major (in) M&R | | Comments |
|--------------|--------------|---------------------|------|--------------------------|------|----------------------------|
| 01/01/2007 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1967 | IMPORTED | BUILT | | 2.00 | True | 1967: 2" P-401 ON 8" P-401 |

Work History Report

Pavement Database:

Pavement Database:

9 of 12

Network: TMB Branch: TW E (TAXIWAY E) Section: 507 Surface: AAC L.C.D.: 01/01/2007 Use: TAXIWAY 200.00 Ft 150.00 Ft True Area: 30,930.07 SqF Rank P Length: Width: Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2007 ML-OL Mill and Overlay \$0 0.00 True **IMPORTED BUILT** 01/01/1965 2.00 True 1965: 2" P-401 ON 8" P-211 Network: TMB Branch: TW F Surface: AAC (TAXIWAY E) Section: 510 **L.C.D.**: 01/01/2007 **Use**: TAXIWAY Rank P Length: 600.00 Ft Width: 50.00 Ft True Area: 32,263.02 SqF Work Work Thickness Major Comments Cost Date Code Description (in) M&R 01/01/2007 ML-OL Mill and Overlay 0.00 01/01/1967 **IMPORTED BUILT** 2.00 True 1967: 2" P-401 ON 8" P-401 Branch: TW E Network: TMB (TAXIWAY E) Surface: AC Section: 513 **L.C.D.:** 01/01/2012 **Use:** TAXIWAY True Area: 54.091.64 SqF Rank P Length: 300.00 Ft Width: 170.00 Ft Work Work Work Thickness Major Cost Comments Code Description M&R Date (in) INITIAL 2012: 4" P-401, 10" P-211 LIMEROCK 01/01/2012 **Initial Construction** \$0 4.00 BASE COURSE, 8" P-152 COMPACTED Network: TMB (TAXIWAY E1) Surface: AAC Branch: TW E1 Section: 515 L.C.D.: 01/01/2012 Use: TAXIWAY Rank P Length: 210.00 Ft Width: 100.00 Ft True Area: 21.049.02 SqF Work Work Thickness Major Cost Comments Code Description Date (in) M&R 01/01/2012 ML-OL Mill and Overlay 0.00 True Mill and Overlay 01/01/1999 ML-OL \$0 0.00 True 01/01/1967 INITIAL **Initial Construction** \$0 2.00 True 1967: 2" P-401 ON 8" P-401 Network: TMB Branch: TW E1 (TAXIWAY E1) Section: 516 Surface: AC L.C.D.: 12/25/1999 Use: TAXIWAY True Area: 38,835.05 SqF Rank P Length: 388.00 Ft Width: 100.00 Ft Work Thickness Work Work Major Comments Cost Date Code Description (in) M&R 12/25/1999 INITIAL Initial Construction 0.00 True Network: TMB Branch: TW E2 (TAXIWAY E2) Section: 520 Surface: AAC L.C.D.: 01/01/2007 Use: TAXIWAY Rank P Length: 300.00 Ft Width: 75.00 Ft True Area: 50.474.48 SqF Work Work Work Thickness Major Comments Cost Date Code Description M&R (in) 01/01/2007 ML-OL Mill and Overlay \$0 0.00 True **IMPORTED BUILT** 2.00 1967: 2" P-401 ON 8" P-401 01/01/1967 True Network: TMB Branch: TW E3 (TAXIWAY E3) Surface: AAC Section: 525 **L.C.D.:** 01/01/2007 **Use:** TAXIWAY Rank P Length: 300.00 Ft Width: 75.00 Ft True Area: 41.823.46 SqF Work Work Work Thickness Major Comments Cost Code Description Date M&R (in) Mill and Overlay 01/01/2007 ML-OL 0.00 \$0 True 01/01/1967 **IMPORTED BUILT** 2.00 1967: 2" P-401 ON 8" P-401 True Branch: TW E4 Network: TMB (TAXIWAY E4) Surface: AC Section: 527 **L.C.D.:** 01/01/1996 **Use:** TAXIWAY Rank P Length: 300.00 Ft 50.00 Ft Width: True Area: 26,266.60 SqF Work Work Work Thickness Major Comments Cost Date Code Description M&R (in) **IMPORTED** 01/01/1996 BUILT 2.00 True 1996: 2" P-401 ON 8" P-211 ON 8" P-154 Date:03/29/2012 Work History Report

Pavement Database: 10 of 12

| | | Paven | nent Database: | | | | | |
|--|--|---|--|---|--|--|--|--|
| Network: TI L.C.D.: 12/25 | MB Br 5/1999 Use : TA | anch: TW E5 (TAXIWA XIWAY Rank P Length: | - * | Width: | Section: 529 Surface: AC 75.00 Ft True Area: 26,192.04 SqF | | | |
| Work Date | Work Code | Work Description | Th Cost | nickness (in) | Major M&R Comments | | | |
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | | | |
| Network: TI L.C.D.: 01/01 | MB Br a 1/1999 Use: TA | anch: TW E5 (TAXIWA XIWAY Rank P Length: | • | Width: | Section: 530 Surface: AAC 90.00 Ft True Area: 32.146.02 SqF | | | |
| Work Date | Work Code | Work Description | Cost | nickness (in) | Major M&R Comments | | | |
| 01/01/1999 01/01/1967 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | | True 1967: 2" P-401 ON 8" P-401 | | | |
| Network: Ti | MB Br : 1/1998 Use: TA | anch: TW F (TAXIWA XIWAY Rank P Length: | • | Width: | Section: 605 Surface: AAC 50.00 Ft True Area: 57.730.09 SqF | | | |
| Work Date | Work Code | Work Description | Cost | nickness (in) | Major M&R Comments | | | |
| 01/01/1998 01/01/1965 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | | True 1965: 2" P-401 ON 8" P-211 | | | |
| Network: Ti | MB Br : 1/2006 Use: TA | anch: TW G (TAXIWA XIWAY Rank P Length: | - * | Width: | Section: 705 Surface: AAC 50.00 Ft True Area: 51,621.67 SqF | | | |
| Work Date | Work Code | Work Description | Cost | nickness (in) | Major M&R Comments | | | |
| 01/01/2006 01/01/1965 | ML-OL IMPORTED | Mill and Overlay | \$0 | 0.00 | True | | | |
| Network: TMB Branch: TWG (TAXIWAY G) Section: 710 Surface: AC | | | | | | | | |
| Network: Ti | MB B r | · · | • | 2.00 Width: | True 1965: 2" P-401 ON 8" P-211 Section: 710 Surface: AC 50.00 Ft True Area: 17,106.11 SqF | | | |
| Network: Ti | MB B r | anch: TW G (TAXIWA | 340.00 Ft | | Section: 710 Surface: AC | | | |
| Network: Tr L.C.D.: 01/02 | MB Br 1/1997 Use: TA Work | anch: TWG (TAXIWA XIWAY Rank P Length: Work | 340.00 Ft Th | Width: | Section: 710 Surface: AC 50.00 Ft True Area: 17,106.11 SqF Major | | | |
| Network: TI L.C.D.: 01/0 ² Work Date 01/01/1997 Network: TI | MB Br. 1/1997 Use: TA Work Code IMPORTED | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H (TAXIWA | 340.00 Ft Cost Th | Width: | Section: 710 Surface: AC 50.00 Ft True Area: 17,106.11 SqF Major M&R Comments True 1997 AC PAVEMENT (FIELD OBSERVATION) Section: 815 Surface: AAC | | | |
| Network: TI L.C.D.: 01/0 ² Work Date 01/01/1997 Network: TI | MB Br. 1/1997 Use: TA Work Code IMPORTED | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H (TAXIWA | 340.00 Ft Cost Th 2.200.00 Ft | Width: nickness (in) | Section: 710 Surface: AC | | | |
| Network: TI L.C.D.: 01/0' Work Date 01/01/1997 Network: TI L.C.D.: 01/0' | MB Br. 1/1997 Use: TA Work Code IMPORTED MB Br. 1/2007 Use: TA | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H XIWAY Rank P Length: Work MYRAN (TAXIWA) | 340.00 Ft Cost Th 2.200.00 Ft | Width: nickness (in) Width: | Section: 710 Surface: AC 50.00 Ft True Area: 17,106.11 SqF Major M&R Comments True 1997 AC PAVEMENT (FIELD DBSERVATION) Section: 815 Surface: AAC 50.00 Ft True Area:119.041.80 SqF Major Comments | | | |
| Network: TI L.C.D.: 01/0 ² Work Date 01/01/1997 Network: TI L.C.D.: 01/0 ² Work Date 01/01/2007 01/01/1998 | MB Br. 1/1997 Use: TA Work Code IMPORTED MB Br. 1/2007 Use: TA Work Code ML-OL IMPORTED | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW H1 XIWAY Rank P Length: | 340.00 Ft Cost Th Cost Th 2.200.00 Ft Cost \$0 Y H1) | Width: nickness (in) Width: nickness (in) 0.00 | Section: 710 Surface: AC | | | |
| Network: TI L.C.D.: 01/07 Work Date 01/01/1997 Network: TI L.C.D.: 01/07 Work Date 01/01/2007 01/01/1998 | MB Br. 1/1997 Use: TA Work Code IMPORTED MB Br. 1/2007 Use: TA Work Code ML-OL IMPORTED | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW H1 (TAXIWA | 340.00 Ft Cost Th Cost Y H) 2.200.00 Ft \$0 Y H1) 90.00 Ft | Width: nickness (in) Width: nickness (in) 0.00 2.00 | Section: 710 Surface: AC | | | |
| Network: TI L.C.D.: 01/0 ² Work Date 01/01/1997 Network: TI L.C.D.: 01/0 ² Work Date 01/01/2007 01/01/1998 Network: TI L.C.D.: 01/0 ² | MB Br. 1/1997 Use: TA Work Code IMPORTED MB Br. 1/2007 Use: TA Work Code ML-OL IMPORTED MB Br. 1/1998 Use: TA | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW H1 XIWAY Rank P Length: Work CTAXIWA Rank P Length: Work CTAXIWA | 340.00 Ft Cost Th Cost Y H) 2.200.00 Ft \$0 Y H1) 90.00 Ft | Width: nickness (in) Width: nickness (in) 0.00 2.00 Width: nickness | Section: 710 Surface: AC | | | |
| Network: TI L.C.D.: 01/0′ Work Date 01/01/1997 Network: TI L.C.D.: 01/0′ Work Date 01/01/2007 01/01/1998 Network: TI L.C.D.: 01/0′ Work Date | MB Br. 1/1997 Use: TA Work Code IMPORTED MB Br. 1/2007 Use: TA Work Code ML-OL IMPORTED MB Br. 1/1998 Use: TA Work Code | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW H1 XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW H1 XIWAY Rank P Length: Work Description BUILT Anch: TW H2 (TAXIWA | 340.00 Ft Cost Th Cost Y H) 2.200.00 Ft \$0 Y H1) 90.00 Ft Cost Th Cost | Width: nickness (in) Width: nickness (in) 0.00 2.00 Width: nickness (in) | Section: 710 Surface: AC | | | |
| Network: TI L.C.D.: 01/0′ Work Date 01/01/1997 Network: TI L.C.D.: 01/0′ Work Date 01/01/2007 01/01/1998 Network: TI L.C.D.: 01/0′ Work Date | MB Br. 1/1997 Use: TA Work Code IMPORTED MB Br. 1/2007 Use: TA Work Code ML-OL IMPORTED MB Br. 1/1998 Use: TA Work Code IMPORTED | anch: TW G XIWAY Rank P Length: Work Description BUILT anch: TW H XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW H1 XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW H1 XIWAY Rank P Length: Work Description BUILT Work Description BUILT Anch: TW H2 (TAXIWA | 340.00 Ft Cost Th Cost Th Cost Ft Cost Th Th Th Th Th Th Th Th Th T | Width: nickness (in) Width: nickness (in) 0.00 2.00 Width: nickness (in) 2.00 | Section: 710 Surface: AC | | | |

| Date:03/29/2012 | Work History Report | |
|-----------------|---------------------|------|
| | Pavement Database: | |
| | | |

| Date:03/ | /29/2012 | | story Replace Delayers Database: | port | 11 of 12 | |
|---|---------------------------------------|---|---------------------------------------|------------------------------------|---|--|
| Network: TI L.C.D.: 01/0 | MB Br 1/2007 Use: TA | anch: TW H3 (TAXIWA XIWAY Rank P Length: | Y H3) 200.00 Ft | Width: | Section: 330 Surface: AAC 90.00 Ft True Area: 18,456.28 SqF | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R Comments | |
| 01/01/2007 01/01/1967 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | 0.00 2.00 | True 1967: 2" P-401 ON 8" P-401 | |
| Network: TI L.C.D.: 01/0 | MB Br 1/2007 Use: TA | anch: TW H4 (TAXIWA XIWAY Rank P Length: | Y H4) 190.00 Ft | Width: | Section: 340 Surface: AAC 90.00 Ft True Area: 17,255.03 SqF | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R Comments | |
| 01/01/2007 01/01/1967 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | 0.00 2.00 | True | |
| Network: TI L.C.D.: 01/0 | MB Br 1/2007 Use: TA | anch: TW H5 (TAXIWA' | Y H5) 200.00 Ft | Width: | Section: 350 Surface: AAC 90.00 Ft True Area: 19.697.18 SqF | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R Comments | |
| 01/01/2007 01/01/1967 | ML-OL IMPORTED | Mill and Overlay BUILT | \$0 | 0.00 2.00 | True | |
| Network: TMB Branch: TW H6 (TAXIWAY H6) Section: 360 Surface: AAC | | | | | | |
| | 1/2007 Use: TA | (,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | Width: | | |
| Work Date | Work Code | (170111111 | 200.00 Ft | Width: Thickness (in) | | |
| Work | Work | XXIWAY Rank P Length: | 200.00 Ft | Thickness | 90.00 Ft | |
| Work Date 01/01/2007 01/01/1967 Network: TI | Work Code ML-OL IMPORTED | Work Description Mill and Overlay BUILT anch: TW H7 (TAXIWA) | 200.00 Ft Cost \$0 | Thickness (in) | 90.00 Ft | |
| Work Date 01/01/2007 01/01/1967 Network: TI | Work Code ML-OL IMPORTED | Work Description Mill and Overlay BUILT anch: TW H7 (TAXIWA) | 200.00 Ft Cost \$0 Y H7) 190.00 Ft | Thickness (in) 0.00 2.00 | 90.00 Ft | |

Work History Report

12 of 12

Pavement Database:

Summary:

| Work Description | Section Count | Area Total (SqFt) | Thickness Avg (in) | Thickness STD (in) |
|-----------------------------|------------------|----------------------|-----------------------|-----------------------|
| BUILT | 58 | 6,299,689.06 | 2.00 | .00 |
| Initial Construction | 27 | 917,750.05 | .67 | 1.47 |
| Mill and Overlay | 34 | 4,265,204.92 | .00 | .00 |
| OVERLAY | 8 | 3,000,084.16 | 1.50 | |
| Surface Seal - Rejuvenating | 16 | 1,304,649.01 | .00 | .00 |

STD = Standard Deviation

APPENDIX B

2012 CONDITION MAP PAVEMENT CONDITION INDEX TABLE




Table B-1: Pavement Condition Index

| Branch Name | Branch ID | Branch Use | Section ID | True Area (ft²) | Section Rank | Surface Type | Total Samples Inspected | Total Samples | PCI | PCI Category |
|-----------------|-----------|---------------|---------------|-----------------------|-----------------|-----------------|-------------------------------|------------------|-----|-----------------|
| North Apron | AP N | APRON | 4205 | 840,000 | P | AAC | 16 | 168 | 90 | Good |
| North Apron | AP N | APRON | 4215 | 60,000 | P | AAC | 2 | 12 | 91 | Good |
| North Apron | AP N | APRON | 4220 | 109,500 | P | AAC | 3 | 24 | 76 | Satisfactory |
| North Apron | AP N | APRON | 4225 | 69,490 | P | AC | 3 | 20 | 64 | Fair |
| North Apron | AP N | APRON | 4230 | 18,795 | P | AC | 1 | 3 | 66 | Fair |
| Northeast Apron | AP NE | APRON | 4305 | 9,600 | P | PCC | 1 | 3 | 95 | Good |
| Northeast Apron | AP NE | APRON | 4310 | 19,797 | P | AC | 1 | 5 | 89 | Good |
| Northeast Apron | AP NE | APRON | 4315 | 21,176 | P | AC | 1 | 5 | 89 | Good |
| Northeast Apron | AP NE | APRON | 4320 | 9,216 | P | PCC | 1 | 3 | 92 | Good |
| Northeast Apron | AP NE | APRON | 4325 | 49,524 | P | AC | 2 | 12 | 81 | Satisfactory |
| Northeast Apron | AP NE | APRON | 4330 | 2,700 | P | PCC | 1 | 1 | 91 | Good |
| South Apron | AP S | APRON | 4105 | 210,000 | P | AC | 5 | 42 | 77 | Satisfactory |
| South Apron | AP S | APRON | 4110 | 240,843 | P | AAC | 5 | 48 | 83 | Satisfactory |
| South Apron | AP S | APRON | 4115 | 832,515 | P | AAC | 10 | 168 | 86 | Good |
| South Apron | AP S | APRON | 4125 | 35,371 | T | AC | 1 | 7 | 62 | Fair |
| South Apron | AP S | APRON | 4130 | 19,714 | P | AC | 1 | 6 | 35 | Very Poor |
| South Apron | AP S | APRON | 4135 | 29,788 | P | AC | 1 | 8 | 59 | Fair |
| South Apron | AP S | APRON | 4140 | 43,874 | P | AC | 3 | 16 | 66 | Fair |
| Southeast Apron | AP SE | APRON | 4410 | 45,220 | P | AC | 2 | 8 | 65 | Fair |
| Runway 13-31 | RW 13-31 | RUNWAY | 6205 | 400,200 | P | AAC | 16 | 80 | 90 | Good |
| Runway 13-31 | RW 13-31 | RUNWAY | 6210 | 200,100 | P | AAC | 7 | 40 | 91 | Good |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6104 | 20,000 | P | AC | 1 | 4 | 90 | Good |

Table B-1: Pavement Condition Index (Continued)

| Branch Name | Branch ID | Branch Use | Section ID | True Area (ft²) | Section Rank | Surface Type | Total Samples Inspected | Total Samples | PCI | PCI Category |
|---------------|-----------|---------------|---------------|-----------------------|-----------------|-----------------|-------------------------------|------------------|-----|-----------------|
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6105 | 460,000 | P | AC | 19 | 92 | 91 | Good |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6109 | 10,000 | P | AC | 1 | 2 | 91 | Good |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6110 | 230,000 | P | AC | 8 | 46 | 93 | Good |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6126 | 10,100 | P | AC | 1 | 2 | 96 | Good |
| Runway 9L-27R | RW 9L-27R | RUNWAY | 6131 | 20,200 | P | AC | 1 | 4 | 90 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6302 | 100,000 | P | AC | 5 | 20 | 100 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6304 | 20,000 | P | AAC | 1 | 4 | 100 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6305 | 460,000 | P | AAC | 19 | 92 | 88 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6306 | 20,100 | P | AC | 1 | 4 | 100 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6307 | 50,000 | P | AC | 2 | 10 | 100 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6309 | 10,000 | P | AAC | 1 | 2 | 100 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6310 | 230,000 | P | AAC | 8 | 46 | 86 | Good |
| Runway 9R-27L | RW 9R-27L | RUNWAY | 6311 | 10,050 | P | AC | 1 | 2 | 91 | Good |
| Taxiway 1 | TW 1 | TAXIWAY | 270 | 12,843 | P | AAC | 1 | 2 | 94 | Good |
| Taxiway 2 | TW 2 | TAXIWAY | 260 | 19,697 | P | AAC | 1 | 4 | 91 | Good |
| Taxiway 3 | TW 3 | TAXIWAY | 250 | 19,697 | P | AAC | 1 | 4 | 96 | Good |
| Taxiway 4 | TW 4 | TAXIWAY | 240 | 19,697 | P | AAC | 1 | 4 | 94 | Good |
| Taxiway 5 | TW 5 | TAXIWAY | 230 | 19,697 | P | AAC | 1 | 4 | 89 | Good |
| Taxiway 6 | TW 6 | TAXIWAY | 220 | 19,697 | P | AAC | 1 | 4 | 91 | Good |
| Taxiway 7 | TW 7 | TAXIWAY | 210 | 18,557 | P | AAC | 1 | 4 | 92 | Good |
| Taxiway Alpha | TW A | TAXIWAY | 105 | 279,576 | P | AAC | 10 | 56 | 94 | Good |
| Taxiway Alpha | TW A | TAXIWAY | 108 | 18,500 | P | AAC | 1 | 4 | 79 | Satisfactory |

Table B-1: Pavement Condition Index (Continued)

| Branch Name | Branch ID | Branch Use | Section ID | True Area (ft²) | Section Rank | Surface Type | Total Samples Inspected | Total Samples | PCI | PCI Category |
|---------------------|-----------|---------------|---------------|-----------------------|-----------------|-----------------|-------------------------------|------------------|-----|-----------------|
| Taxiway Alpha | TW A | TAXIWAY | 110 | 36,180 | P | AC | 1 | 7 | 91 | Good |
| Taxiway Alpha | TW A | TAXIWAY | 111 | 27,392 | P | AC | 1 | 6 | 100 | Good |
| Taxiway A-1 | TW A1 | TAXIWAY | 115 | 50,475 | P | AC | 2 | 14 | 97 | Good |
| Taxiway A-2 | TW A2 | TAXIWAY | 120 | 50,475 | P | AC | 2 | 14 | 95 | Good |
| Taxiway A-3 | TW A3 | TAXIWAY | 124 | 26,792 | P | AC | 1 | 6 | 92 | Good |
| Taxiway A-3 | TW A3 | TAXIWAY | 125 | 32,146 | P | AC | 2 | 6 | 93 | Good |
| Taxiway to NE Apron | TW AP NE | TAXIWAY | 1005 | 44,691 | P | AC | 2 | 13 | 78 | Satisfactory |
| Taxiway to SE Apron | TW AP SE | TAXIWAY | 1105 | 42,727 | P | AC | 1 | 10 | 89 | Good |
| Taxiway Charlie | TW C | TAXIWAY | 910 | 138,069 | P | AC | 3 | 27 | 86 | Good |
| Taxiway C-1 | TW C1 | TAXIWAY | 310 | 17,644 | P | AAC | 1 | 5 | 72 | Satisfactory |
| Taxiway C-2 | TW C2 | TAXIWAY | 320 | 17,567 | P | AAC | 1 | 5 | 78 | Satisfactory |
| Taxiway CC | TW CC | TAXIWAY | 905 | 7,838 | P | AC | 1 | 2 | 78 | Satisfactory |
| Taxiway Delta | TW D | TAXIWAY | 405 | 210,898 | P | AC | 5 | 43 | 47 | Poor |
| Taxiway Delta | TW D | TAXIWAY | 410 | 36,142 | P | AC | 1 | 7 | 94 | Good |
| Taxiway Delta | TW D | TAXIWAY | 411 | 27,092 | P | AC | 1 | 6 | 88 | Good |
| Taxiway Delta | TW D | TAXIWAY | 412 | 10,004 | P | AC | 1 | 2 | 94 | Good |
| Taxiway D-1 | TW D1 | TAXIWAY | 415 | 50,475 | P | AC | 2 | 14 | 56 | Fair |
| Taxiway D-2 | TW D2 | TAXIWAY | 420 | 50,463 | P | AC | 2 | 14 | 53 | Poor |
| Taxiway Echo | TW E | TAXIWAY | 503 | 56,119 | P | AC | 1 | 11 | 100 | Good |
| Taxiway Echo | TW E | TAXIWAY | 505 | 238,386 | P | AAC | 5 | 47 | 95 | Good |
| Taxiway Echo | TW E | TAXIWAY | 507 | 30,930 | P | AAC | 1 | 7 | 91 | Good |
| Taxiway Echo | TW E | TAXIWAY | 510 | 32,263 | P | AAC | 1 | 7 | 95 | Good |

Table B-1: Pavement Condition Index (Continued)

| Branch Name | Branch ID | Branch Use | Section ID | True Area (ft²) | Section Rank | Surface Type | Total Samples Inspected | Total Samples | PCI | PCI Category |
|-----------------|-----------|---------------|---------------|-----------------------|-----------------|-----------------|-------------------------------|------------------|-----|-----------------|
| Taxiway Echo | TW E | TAXIWAY | 513 | 54,092 | P | AC | 2 | 12 | 100 | Good |
| Taxiway E-1 | TW E1 | TAXIWAY | 515 | 21,049 | P | AAC | 1 | 4 | 100 | Good |
| Taxiway E-1 | TW E1 | TAXIWAY | 516 | 38,835 | P | AC | 1 | 8 | 91 | Good |
| Taxiway E-2 | TW E2 | TAXIWAY | 520 | 50,474 | P | AAC | 3 | 14 | 83 | Satisfactory |
| Taxiway E-3 | TW E3 | TAXIWAY | 525 | 41,823 | P | AAC | 3 | 11 | 83 | Satisfactory |
| Taxiway E-4 | TW E4 | TAXIWAY | 527 | 26,267 | P | AC | 1 | 7 | 87 | Good |
| Taxiway E-5 | TW E5 | TAXIWAY | 529 | 26,192 | P | AC | 1 | 6 | 93 | Good |
| Taxiway E-5 | TW E5 | TAXIWAY | 530 | 32,146 | P | AAC | 2 | 6 | 92 | Good |
| Taxiway Foxtrot | TW F | TAXIWAY | 605 | 57,730 | P | AAC | 3 | 12 | 93 | Good |
| Taxiway Golf | TW G | TAXIWAY | 705 | 51,622 | P | AAC | 2 | 10 | 96 | Good |
| Taxiway Golf | TW G | TAXIWAY | 710 | 17,106 | P | AC | 1 | 3 | 91 | Good |
| Taxiway Hotel | TW H | TAXIWAY | 815 | 119,042 | P | AAC | 3 | 25 | 91 | Good |
| Taxiway H-1 | TW H1 | TAXIWAY | 805 | 4,802 | P | AC | 1 | 1 | 91 | Good |
| Taxiway H-2 | TW H2 | TAXIWAY | 810 | 7,744 | P | AC | 1 | 2 | 85 | Satisfactory |
| Taxiway H-3 | TW H3 | TAXIWAY | 330 | 18,456 | P | AAC | 1 | 4 | 88 | Good |
| Taxiway H-4 | TW H4 | TAXIWAY | 340 | 17,255 | P | AAC | 1 | 4 | 100 | Good |
| Taxiway H-5 | TW H5 | TAXIWAY | 350 | 19,697 | P | AAC | 1 | 4 | 91 | Good |
| Taxiway H-6 | TW H6 | TAXIWAY | 360 | 19,697 | P | AAC | 1 | 4 | 93 | Good |
| Taxiway H-7 | TW H7 | TAXIWAY | 370 | 12,809 | P | AAC | 1 | 2 | 94 | Good |

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

APPENDIX C

BRANCH CONDITION REPORT SECTION CONDITION REPORT

Branch Condition Report

Pavement Database: NetworkID: TMB

Sum Section | Avg Section Number of PCI **True Area** Weighted Average **Branch ID** Use **Sections** Length Width Standard Average (SqFt) PCI PCI (Ft) (Ft) Deviation APN (NORTH APRON) 5 5,815.00 206.00 1,097,784.76 **APRON** 77.40 11.45 86.60 AP NE (NORTHEAST APRON) 112,013.84 6 1,325.00 70.00 **APRON** 89.50 4.31 86.27 APS (SOUTH APRON) 7 6,919.05 1,412,105.15 **APRON** 81.65 166.57 66.86 16.17 AP SE (SOUTHEAST APRON) 45,220.00 400.00 **APRON** 100.00 65.00 0.00 65.00 1 RW 13-31 (RUNWAY 13-31) 2 12,006.00 62.50 600,300.00 **RUNWAY** 90.50 0.50 90.33 15,006.00 62.50 750,300.00 **RUNWAY** RW 9L-27R (RUNWAY 9L-27R) 6 91.83 2.11 91.63 RW 9R-27L (RUNWAY 9R-27L) 8 18,003.00 62.50 900,150.00 **RUNWAY** 95.63 5.79 90.19 TW 1 (TAXIWAY 1) 200.00 1 50.00 12,842.70 **TAXIWAY** 94.00 0.00 94.00 200.00 **TAXIWAY** TW 2 (TAXIWAY 2) 1 90.00 19,697.18 91.00 0.00 91.00 TW 3 (TAXIWAY 3) 200.00 19,697.18 **TAXIWAY** 1 90.00 96.00 0.00 96.00 TW 4 (TAXIWAY 4) 1 200.00 90.00 19,697.18 **TAXIWAY** 94.00 0.00 94.00 TW 5 (TAXIWAY 5) 200.00 90.00 19,697.18 **TAXIWAY** 89.00 0.00 89.00 1 TW 6 (TAXIWAY 6) 1 200.00 90.00 19,696.66 **TAXIWAY** 91.00 0.00 91.00 TW 7 (TAXIWAY 7) 200.00 90.00 18,557.11 **TAXIWAY** 92.00 0.00 92.00 1 TW A (TAXIWAY A) **TAXIWAY** 4 6,530.00 68.75 361,647.06 91.00 7.65 93.39 TW A1 (TAXIWAY A1) 1 300.00 75.00 50,474.98 **TAXIWAY** 97.00 0.00 97.00

Branch Condition Report

Pavement Database: NetworkID: TMB

Number of Sum Section Avg Section PCI Weighted **True Area Branch ID** Use Average **Sections** Length Width Standard Average (SqFt) PCI PCI (Ft) (Ft) Deviation TW A2 (TAXIWAY A2) 300.00 75.00 50,474.98 **TAXIWAY** 95.00 0.00 95.00 1 TW A3 (TAXIWAY A3) 620.00 **TAXIWAY** 2 87.50 58,938.06 92.50 0.50 92.55 TW AP NE (TAXIWAY TO NE 1,200.00 44,690.90 **TAXIWAY** 78.00 1 35.00 78.00 0.00 APRON) TW AP SE (TAXIWAY TO SE 1,400.00 **TAXIWAY** 30.00 42,726.72 89.00 0.00 89.00 1 APRON) TW C (TAXIWAY C) 1 2,600.00 50.00 138,068.51 **TAXIWAY** 86.00 0.00 86.00 190.00 **TAXIWAY** TW C1 (TAXIWAY C1) 1 90.00 17,643.88 72.00 0.00 72.00 TW C2 (TAXIWAY C2) 190.00 17,567.42 **TAXIWAY** 78.00 1 90.00 78.00 0.00 TW CC (TAXIWAY CC) 1 125.00 50.00 7,838.05 **TAXIWAY** 78.00 0.00 78.00 **TAXIWAY** TW D (TAXIWAY D) 4 4,961.00 81.25 284,135.64 80.75 19.64 58.54 500.00 50,474.98 **TAXIWAY** TW D1 (TAXIWAY D1) 1 100.00 56.00 0.00 56.00 TW D2 (TAXIWAY D2) 1 300.00 75.00 50,462.90 **TAXIWAY** 53.00 0.00 53.00 TW E (TAXIWAY E) 5 6,920.00 94.00 411,789.40 **TAXIWAY** 96.20 3.43 96.04 TW E1 (TAXIWAY E1) 2 598.00 100.00 59,884.07 **TAXIWAY** 95.50 4.50 94.16 TW E2 (TAXIWAY E2) 300.00 75.00 50,474.48 **TAXIWAY** 83.00 0.00 83.00 1 TW E3 (TAXIWAY E3) 300.00 75.00 41,823.46 **TAXIWAY** 83.00 0.00 83.00 1 TW E4 (TAXIWAY E4) 1 300.00 50.00 26,266.60 **TAXIWAY** 87.00 0.00 87.00

Branch Condition Report

Pavement Database: NetworkID: TMB

Sum Section Avg Section PCI Number of Weighted **True Area** Average **Branch ID** Use Sections Length Width Standard Average (SqFt) PCI PCI (Ft) (Ft) Deviation TW E5 (TAXIWAY E5) 2 600.00 82.50 58,338.06 **TAXIWAY** 92.50 0.50 92.45 TW F (TAXIWAY F) 1,050.00 57,730.09 **TAXIWAY** 93.00 1 50.00 93.00 0.00 TW G (TAXIWAY G) 2 1,340.00 50.00 68,727.78 **TAXIWAY** 93.50 2.50 94.76 TW H (TAXIWAY H) 2,200.00 119,041.80 **TAXIWAY** 0.00 91.00 1 50.00 91.00 TW H1 (TAXIWAY H1) 1 90.00 50.00 4,801.55 **TAXIWAY** 91.00 0.00 91.00 TW H2 (TAXIWAY H2) 1 75.00 100.00 7,744.33 **TAXIWAY** 85.00 0.00 85.00 TW H3 (TAXIWAY H3) 1 200.00 90.00 18,456.28 **TAXIWAY** 88.00 0.00 88.00 TW H4 (TAXIWAY H4) 190.00 17,255.03 **TAXIWAY** 100.00 1 90.00 100.00 0.00 TW H5 (TAXIWAY H5) 200.00 **TAXIWAY** 1 90.00 19,697.18 91.00 0.00 91.00 93.00 TW H6 (TAXIWAY H6) 200.00 19,697.18 **TAXIWAY** 0.00 1 90.00 93.00 TW H7 (TAXIWAY H7) **TAXIWAY** 1 190.00 50.00 12,808.80 94.00 0.00 94.00

Pavement Database:

| Use Category | Number of Sections | Total Area (SqFt) | Arithmetic Average PCI | Average PCI STD. | Weighted Average PCI |
|-----------------|--------------------------|-------------------------|------------------------------|------------------------|----------------------------|
| APRON | 19 | 2,667,123.75 | 76.68 | 15.21 | 83.60 |
| RUNWAY | 16 | 2,250,750.00 | 93.56 | 4.78 | 90.71 |
| TAXIWAY | 50 | 2,299,565.36 | 88.48 | 11.08 | 86.09 |
| All | 85 | 7,217,439.11 | 86.80 | 12.71 | 86.61 |

STD = Standard Deviation

Section Condition Report

Pavement Database:

NetworkID: TMB

Last Age **Branch ID** Section ID Last Surface Use Rank Lanes **True Area PCI** Inspection Αt Const. (SqFt) Date Inspection Date APN (NORTH APRON) **APRON** Ρ 840,000.00 03/26/2012 4205 01/01/2006 AAC 0 90.00 APN (NORTH APRON) 4215 01/01/2006 AAC **APRON** Ρ 0 60,000.00 03/26/2012 6 91.00 APN (NORTH APRON) 4220 01/01/1994 AAC **APRON** Ρ 109,500.00 03/26/2012 76.00 APN (NORTH APRON) 4225 12/25/1999 AC **APRON** 0 69,490.00 03/26/2012 13 64.00 APN (NORTH APRON) 4230 **APRON** Ρ 12/25/1999 AC 0 18,794.76 03/26/2012 66.00 13 AP NE (NORTHEAST APRON) 4305 12/25/1999 **PCC APRON** Ρ 0 9,600.00 03/26/2012 13 95.00 AP NE (NORTHEAST APRON) 4310 12/25/1999 AC **APRON** Р 0 19.797.46 03/26/2012 13 89.00 AP NE (NORTHEAST APRON) 4315 12/25/1999 AC **APRON** Р 21.176.35 03/26/2012 89.00 0 13 12/25/1999 PCC **APRON** Ρ 9,216.00 03/26/2012 AP NE (NORTHEAST APRON) 4320 0 92.00 13 AP NE (NORTHEAST APRON) **APRON** P 49,524.03 03/26/2012 4325 12/25/1999 AC 0 13 81.00 Р AP NE (NORTHEAST APRON) 4330 12/25/1999 PCC **APRON** 0 2,700.00 03/26/2012 13 91.00 APS (SOUTH APRON) 4105 01/01/1998 AC **APRON** Ρ O 210,000.00 03/26/2012 14 77.00 Р APS (SOUTH APRON) 01/01/1998 AAC **APRON** 0 240,842.74 03/26/2012 83.00 4110 14 Р APS (SOUTH APRON) 4115 01/01/1998 AAC **APRON** 0 832,515.06 03/26/2012 14 86.00 APS (SOUTH APRON) 4125 12/25/1999 AC **APRON** Т 0 35,370.73 03/26/2012 62.00 13 **APRON** Ρ 19,714.38 03/26/2012 APS (SOUTH APRON) 4130 12/25/1999 AC 13 35.00 APS (SOUTH APRON) 4135 12/25/1999 AC **APRON** 0 29.788.29 03/26/2012 13 59.00 43,873.95 03/26/2012 APS (SOUTH APRON) 4140 12/25/1999 AC **APRON** Р 0 66.00 13 AP SE (SOUTHEAST APRON) 4410 12/25/1999 AC **APRON** Р 0 45,220.00 03/26/2012 13 65.00 **RUNWAY** Р 400,200.00 03/26/2012 RW 13-31 (RUNWAY 13-31) 6205 01/01/2004 AAC 0 8 90.00 **RUNWAY** Р RW 13-31 (RUNWAY 13-31) 6210 01/01/2004 AAC 0 200,100.00 03/26/2012 8 91.00 RW 9L-27R (RUNWAY 9L-27R) **RUNWAY** Р 20,000.00 03/26/2012 6104 01/01/1997 AC 0 90.00 15 RW 9L-27R (RUNWAY 9L-27R) 6105 01/01/1965 AC **RUNWAY** Р 0 460,000.00 03/26/2012 47 91.00 RW 9L-27R (RUNWAY 9L-27R) 6109 01/01/1997 AC **RUNWAY** Ρ 0 10,000.00 03/26/2012 15 91.00 RW 9L-27R (RUNWAY 9L-27R) 6110 01/01/1965 AC **RUNWAY** Ρ 0 230,000.00 03/26/2012 93.00 RW 9L-27R (RUNWAY 9L-27R) **RUNWAY** Р 10,100.00 03/26/2012 6126 01/01/1997 AC 15 96.00 RW 9L-27R (RUNWAY 9L-27R) 6131 01/01/1997 AC **RUNWAY** 0 20,200.00 03/26/2012 90.00 15

Section Condition Report

Pavement Database:

NetworkID: TMB

Last Age **Branch ID** Section ID Last Surface Use Rank Lanes **True Area** PCI Inspection Αt Const. (SqFt) Date Inspection Date Ρ RW 9R-27L (RUNWAY 9R-27L) 6302 01/01/2012 AC **RUNWAY** 0 100,000.00 01/01/2012 100.00 RW 9R-27L (RUNWAY 9R-27L) 6304 01/01/2012 AAC **RUNWAY** Ρ 0 20,000.00 01/01/2012 0 100.00 RW 9R-27L (RUNWAY 9R-27L) 6305 01/01/1997 AAC **RUNWAY** Ρ 460,000.00 03/26/2012 15 88.00 RW 9R-27L (RUNWAY 9R-27L) 01/01/1997 AC **RUNWAY** 0 20,100.00 03/26/2012 6306 15 100.00 01/01/2012 **RUNWAY** Ρ RW 9R-27L (RUNWAY 9R-27L) 6307 AC 0 50,000.00 01/01/2012 0 100.00 RW 9R-27L (RUNWAY 9R-27L) Р 0 6309 01/01/2012 AAC RUNWAY 10,000.00 01/01/2012 0 100.00 RW 9R-27L (RUNWAY 9R-27L) 01/01/1997 **RUNWAY** Р 0 230,000.00 03/26/2012 6310 AAC 15 86.00 Р RW 9R-27L (RUNWAY 9R-27L) 6311 01/01/1997 AC RUNWAY 0 10,050.00 03/26/2012 15 91.00 TW 1 (TAXIWAY 1) 270 01/01/2006 **TAXIWAY** Ρ 0 12,842.70 03/26/2012 94.00 AAC 6 TW 2 (TAXIWAY 2) 260 01/01/2006 AAC **TAXIWAY** 0 19,697.18 03/26/2012 6 91.00 TW 3 (TAXIWAY 3) 250 01/01/2006 AAC **TAXIWAY** Р 0 19,697.18 03/26/2012 6 96.00 TW 4 (TAXIWAY 4) 01/01/2006 **TAXIWAY** Р 0 19,697.18 03/26/2012 240 AAC 6 94.00 Ρ TW 5 (TAXIWAY 5) 230 01/01/2006 AAC **TAXIWAY** 0 19,697.18 03/26/2012 6 89.00 TW 6 (TAXIWAY 6) 220 01/01/2006 AAC **TAXIWAY** Ρ 0 19,696.66 03/26/2012 6 91.00 01/01/2005 **TAXIWAY** Р 7 TW 7 (TAXIWAY 7) AAC 0 18,557.11 03/26/2012 92.00 210 **TAXIWAY** Ρ TW A (TAXIWAY A) 105 01/01/2005 AAC 0 279,575.51 03/26/2012 7 94.00 TW A (TAXIWAY A) 01/01/2005 AAC **TAXIWAY** Ρ 18,500.00 03/26/2012 108 0 7 79.00 Р TW A (TAXIWAY A) 110 01/01/1965 AC **TAXIWAY** 0 36,179.51 03/26/2012 47 91.00 TW A (TAXIWAY A) Р 111 12/25/1999 AC **TAXIWAY** 0 27,392.04 03/26/2012 13 100.00 TW A1 (TAXIWAY A1) 01/01/1965 AC. **TAXIWAY** Ρ O 50,474.98 03/26/2012 97.00 115 47 TW A2 (TAXIWAY A2) 120 01/01/1965 AC **TAXIWAY** Ρ 50,474.98 03/26/2012 95.00 12/25/1999 Ρ 0 TW A3 (TAXIWAY A3) 124 AC **TAXIWAY** 26,792.04 03/26/2012 13 92.00 TW A3 (TAXIWAY A3) 125 01/01/1965 AC **TAXIWAY** Ρ 0 32,146.02 03/26/2012 47 93.00 **TAXIWAY** Р TW AP NE (TAXIWAY TO NE 1005 12/25/1999 AC 0 44,690.90 03/26/2012 78.00 13 APRON) TW AP SE (TAXIWAY TO SE 1105 12/25/1999 AC **TAXIWAY** Ρ 0 42,726.72 03/26/2012 13 89.00 APRON) TW C (TAXIWAY C) 910 01/01/1998 AC **TAXIWAY** 138,068.51 03/26/2012 14 86.00

Section Condition Report

Pavement Database:

NetworkID: TMB

Last Age **Branch ID** Section ID Last Surface Use Rank Lanes **True Area** PCI Inspection Αt Const. (SqFt) Date Inspection Date TW C1 (TAXIWAY C1) **TAXIWAY** Ρ 310 01/01/1997 AAC 17,643.88 03/26/2012 15 72.00 01/01/1997 **TAXIWAY** Р TW C2 (TAXIWAY C2) 320 AAC 0 17,567.42 03/26/2012 15 78.00 TW CC (TAXIWAY CC) 905 01/01/1998 AC **TAXIWAY** Ρ 0 7,838.05 03/26/2012 14 78.00 **TAXIWAY** Ρ 210,897.78 03/26/2012 TW D (TAXIWAY D) 405 01/01/1965 AC 0 47 47.00 Ρ TW D (TAXIWAY D) 410 01/01/1965 AC **TAXIWAY** 0 36,141.84 03/26/2012 47 94.00 TW D (TAXIWAY D) 411 12/25/1999 AC **TAXIWAY** Р 27,092.04 03/26/2012 13 88.00 TW D (TAXIWAY D) 412 12/25/1999 AC **TAXIWAY** Ρ 0 10,003.98 03/26/2012 94.00 13 TW D1 (TAXIWAY D1) 415 01/01/1965 AC **TAXIWAY** Ρ 0 50,474.98 03/26/2012 47 56.00 **TAXIWAY** Ρ TW D2 (TAXIWAY D2) 420 01/01/1965 AC 0 50,462.90 03/26/2012 47 53.00 TW E (TAXIWAY E) 503 01/01/2012 AC **TAXIWAY** Ρ 0 56,118.63 01/01/2012 100.00 0 TW E (TAXIWAY E) 505 01/01/2007 AAC **TAXIWAY** Ρ 0 238.386.04 03/26/2012 5 95.00 01/01/2007 TW E (TAXIWAY E) **TAXIWAY** Р 30,930.07 03/26/2012 507 AAC Λ 5 91.00 TW E (TAXIWAY E) 510 01/01/2007 AAC **TAXIWAY** Ρ 0 32,263.02 03/26/2012 5 95.00 TW E (TAXIWAY E) 513 01/01/2012 AC **TAXIWAY** Ρ 0 54,091.64 01/01/2012 100.00 **TAXIWAY** Р 21,049.02 01/01/2012 TW E1 (TAXIWAY E1) 01/01/2012 AAC n 0 100.00 515 Р TW E1 (TAXIWAY E1) 516 12/25/1999 AC **TAXIWAY** 0 38,835.05 03/26/2012 13 91.00 TW E2 (TAXIWAY E2) 01/01/2007 AAC **TAXIWAY** 0 50,474.48 03/26/2012 83.00 520 5 TW E3 (TAXIWAY E3) 525 01/01/2007 AAC **TAXIWAY** Р 41,823.46 03/26/2012 5 83.00 TW E4 (TAXIWAY E4) 01/01/1996 AC **TAXIWAY** Р 0 26,266.60 03/26/2012 527 16 87.00 TW E5 (TAXIWAY E5) 12/25/1999 **TAXIWAY** Ρ 26,192.04 03/26/2012 529 AC 0 13 93.00 TW E5 (TAXIWAY E5) Р 530 01/01/1999 AAC **TAXIWAY** n 32,146.02 03/26/2012 13 92.00 TW F (TAXIWAY F) 605 01/01/1998 AAC **TAXIWAY** Ρ 0 57,730.09 03/26/2012 93.00 14 TW G (TAXIWAY G) 705 01/01/2006 AAC **TAXIWAY** Ρ 51,621.67 03/26/2012 6 96.00 TW G (TAXIWAY G) 01/01/1997 **TAXIWAY** Ρ 17,106.11 03/26/2012 710 AC 0 15 91.00 Р TW H (TAXIWAY H) 815 01/01/2007 AAC **TAXIWAY** 0 119,041.80 03/26/2012 5 91.00 TW H1 (TAXIWAY H1) 805 01/01/1998 AC **TAXIWAY** Р 0 4,801.55 03/26/2012 14 91.00

Section Condition Report

Pavement Database:

NetworkID: TMB

Last Age **Branch ID** Section ID Last Surface Use Rank Lanes **True Area** PCI Inspection Αt Const. (SqFt) Date Inspection Date Ρ TW H2 (TAXIWAY H2) 810 01/01/1998 AC **TAXIWAY** 0 7,744.33 03/26/2012 85.00 TW H3 (TAXIWAY H3) 330 01/01/2007 AAC **TAXIWAY** Р 0 18,456.28 03/26/2012 5 88.00 Ρ TW H4 (TAXIWAY H4) 340 01/01/2007 AAC **TAXIWAY** 0 17,255.03 03/26/2012 5 100.00 **TAXIWAY** Ρ 0 TW H5 (TAXIWAY H5) 350 01/01/2007 AAC 19,697.18 03/26/2012 5 91.00 01/01/2007 **TAXIWAY** Р 19,697.18 03/26/2012 TW H6 (TAXIWAY H6) 360 AAC 0 5 93.00 **TAXIWAY** Ρ TW H7 (TAXIWAY H7) 370 01/01/2007 AAC 0 12,808.80 03/26/2012 5 94.00

Section Condition Report

5 of 5

Pavement Database:

| Age Category | Average Age At Inspection | Total Area (SqFt) | Number of Sections | Arithmetic Average PCI | PCI Standard Deviation | Weighted Average PCI |
|-----------------|---------------------------------|-------------------------|--------------------------|------------------------------|------------------------------|----------------------------|
| 0-02 | 0.00 | 311,259.29 | 7 | 100.00 | 0.00 | 100.00 |
| 03-05 | 5.00 | 600,833.34 | 11 | 91.27 | 4.88 | 91.87 |
| 06-10 | 6.50 | 1,979,882.37 | 14 | 91.29 | 4.03 | 90.90 |
| 11-15 | 13.73 | 2,982,444.52 | 41 | 83.49 | 13.01 | 83.88 |
| 16-20 | 17.00 | 135,766.60 | 2 | 81.50 | 5.50 | 78.13 |
| over 40 | 47.00 | 1,207,252.99 | 10 | 81.00 | 19.17 | 81.20 |
| AII | 14.27 | 7,217,439.11 | 85 | 86.80 | 12.71 | 86.61 |

APPENDIX D

PAVEMENT CONDITION PREDICTION TABLE PREDICTED PCI BY PAVEMENT USE GRAPH

Table D-1: Pavement Condition Prediction

| D 137 | D 170 | Section | Current | | | | | PCI Fo | recast | | | | |
|--------------------|-----------|---------|---------|------|------|------|------|--------|--------|------|------|------|------|
| Branch Name | Branch ID | ID | PCI | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 |
| North Apron | AP N | 4205 | 90 | 89 | 88 | 86 | 84 | 83 | 81 | 80 | 79 | 77 | 76 |
| North Apron | AP N | 4215 | 91 | 90 | 89 | 87 | 85 | 84 | 82 | 81 | 79 | 78 | 77 |
| North Apron | AP N | 4220 | 76 | 76 | 75 | 73 | 72 | 71 | 70 | 68 | 67 | 66 | 64 |
| North Apron | AP N | 4225 | 64 | 64 | 63 | 62 | 60 | 59 | 58 | 57 | 56 | 55 | 54 |
| North Apron | AP N | 4230 | 66 | 66 | 65 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 |
| Northeast Apron | AP NE | 4305 | 95 | 95 | 94 | 93 | 92 | 91 | 90 | 89 | 88 | 87 | 86 |
| Northeast Apron | AP NE | 4310 | 89 | 88 | 86 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 |
| Northeast Apron | AP NE | 4315 | 89 | 88 | 86 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 |
| Northeast Apron | AP NE | 4320 | 92 | 92 | 91 | 90 | 89 | 88 | 87 | 86 | 85 | 84 | 83 |
| Northeast Apron | AP NE | 4325 | 81 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 | 68 |
| Northeast Apron | AP NE | 4330 | 91 | 91 | 90 | 89 | 88 | 87 | 86 | 85 | 84 | 83 | 82 |
| South Apron | AP S | 4105 | 77 | 77 | 75 | 74 | 72 | 71 | 70 | 69 | 67 | 66 | 65 |
| South Apron | AP S | 4110 | 83 | 83 | 81 | 80 | 79 | 77 | 76 | 75 | 74 | 73 | 71 |
| South Apron | AP S | 4115 | 86 | 86 | 84 | 82 | 81 | 80 | 78 | 77 | 76 | 75 | 74 |
| South Apron | AP S | 4125 | 62 | 62 | 61 | 60 | 59 | 57 | 56 | 55 | 54 | 53 | 52 |
| South Apron | AP S | 4130 | 35 | 35 | 33 | 31 | 28 | 26 | 24 | 21 | 19 | 16 | 13 |
| South Apron | AP S | 4135 | 59 | 59 | 58 | 57 | 55 | 54 | 53 | 52 | 51 | 50 | 48 |
| South Apron | AP S | 4140 | 66 | 66 | 65 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 |
| Southeast Apron | AP SE | 4410 | 65 | 65 | 64 | 63 | 61 | 60 | 59 | 58 | 57 | 56 | 55 |
| Runway 13-31 | RW 13-31 | 6205 | 90 | 89 | 86 | 83 | 80 | 78 | 75 | 73 | 71 | 69 | 68 |
| Runway 13-31 | RW 13-31 | 6210 | 91 | 90 | 87 | 84 | 81 | 78 | 76 | 74 | 72 | 70 | 68 |
| Runway 9L-27R | RW 9L-27R | 6104 | 90 | 89 | 87 | 85 | 83 | 81 | 79 | 77 | 75 | 72 | 70 |

Table D-1: Pavement Condition Prediction (Continued)

| | D 1.10 | Section | Current | | | | | PCI Fo | recast | | | | |
|---------------|-----------|---------|---------|------|------|------|------|--------|--------|------|------|------|------|
| Branch Name | Branch ID | ID | PCI | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 |
| Runway 9L-27R | RW 9L-27R | 6105 | 91 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 71 |
| Runway 9L-27R | RW 9L-27R | 6109 | 91 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 71 |
| Runway 9L-27R | RW 9L-27R | 6110 | 93 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 |
| Runway 9L-27R | RW 9L-27R | 6126 | 96 | 96 | 94 | 92 | 90 | 88 | 85 | 83 | 81 | 79 | 77 |
| Runway 9L-27R | RW 9L-27R | 6131 | 90 | 89 | 87 | 85 | 83 | 81 | 79 | 77 | 75 | 72 | 70 |
| Runway 9R-27L | RW 9R-27L | 6302 | 100 | 99 | 98 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 82 |
| Runway 9R-27L | RW 9R-27L | 6304 | 100 | 98 | 94 | 91 | 87 | 84 | 81 | 79 | 76 | 74 | 72 |
| Runway 9R-27L | RW 9R-27L | 6305 | 88 | 87 | 84 | 81 | 79 | 76 | 74 | 72 | 70 | 68 | 67 |
| Runway 9R-27L | RW 9R-27L | 6306 | 100 | 100 | 98 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 82 |
| Runway 9R-27L | RW 9R-27L | 6307 | 100 | 99 | 98 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 82 |
| Runway 9R-27L | RW 9R-27L | 6309 | 100 | 98 | 94 | 91 | 87 | 84 | 81 | 79 | 76 | 74 | 72 |
| Runway 9R-27L | RW 9R-27L | 6310 | 86 | 85 | 82 | 80 | 77 | 75 | 73 | 71 | 69 | 67 | 66 |
| Runway 9R-27L | RW 9R-27L | 6311 | 91 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 71 |
| Taxiway 1 | TW 1 | 270 | 94 | 93 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 |
| Taxiway 2 | TW 2 | 260 | 91 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 | 73 |
| Taxiway 3 | TW 3 | 250 | 96 | 95 | 92 | 89 | 86 | 84 | 82 | 80 | 78 | 76 | 75 |
| Taxiway 4 | TW 4 | 240 | 94 | 93 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 |
| Taxiway 5 | TW 5 | 230 | 89 | 88 | 86 | 83 | 81 | 79 | 77 | 76 | 74 | 73 | 72 |
| Taxiway 6 | TW 6 | 220 | 91 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 | 73 |
| Taxiway 7 | TW 7` | 210 | 92 | 91 | 88 | 86 | 83 | 81 | 79 | 77 | 76 | 74 | 73 |
| Taxiway Alpha | TW A | 105 | 94 | 93 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 |
| Taxiway Alpha | TW A | 108 | 79 | 79 | 77 | 75 | 74 | 73 | 72 | 71 | 70 | 69 | 68 |

Table D-1: Pavement Condition Prediction (Continued)

| D. L.N. | D 1 1D | Section | Current | | | | | PCI Fo | recast | | | | |
|---------------------|-----------|---------|---------|------|------|------|------|--------|--------|------|------|------|------|
| Branch Name | Branch ID | ID | PCI | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 |
| Taxiway Alpha | TW A | 110 | 91 | 90 | 89 | 87 | 85 | 83 | 82 | 80 | 79 | 77 | 76 |
| Taxiway Alpha | TW A | 111 | 100 | 99 | 97 | 95 | 93 | 91 | 89 | 87 | 85 | 84 | 82 |
| Taxiway A-1 | TW A1 | 115 | 97 | 96 | 94 | 92 | 90 | 88 | 87 | 85 | 83 | 81 | 80 |
| Taxiway A-2 | TW A2 | 120 | 95 | 94 | 92 | 90 | 89 | 87 | 85 | 83 | 82 | 80 | 78 |
| Taxiway A-3 | TW A3 | 124 | 92 | 91 | 90 | 88 | 86 | 84 | 82 | 81 | 79 | 78 | 76 |
| Taxiway A-3 | TW A3 | 125 | 93 | 92 | 90 | 89 | 87 | 85 | 83 | 82 | 80 | 79 | 77 |
| Taxiway to NE Apron | TW AP NE | 1005 | 78 | 78 | 76 | 75 | 73 | 72 | 71 | 70 | 68 | 67 | 66 |
| Taxiway to SE Apron | TW AP SE | 1105 | 89 | 89 | 87 | 85 | 83 | 82 | 80 | 78 | 77 | 76 | 74 |
| Taxiway Charlie | TW C | 910 | 86 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 75 | 73 | 72 |
| Taxiway C-1 | TW C1 | 310 | 72 | 72 | 71 | 70 | 69 | 68 | 68 | 67 | 66 | 66 | 65 |
| Taxiway C-2 | TW C2 | 320 | 78 | 78 | 76 | 74 | 73 | 72 | 71 | 70 | 69 | 68 | 68 |
| Taxiway CC | TW CC | 905 | 78 | 78 | 76 | 75 | 73 | 72 | 71 | 70 | 68 | 67 | 66 |
| Taxiway Delta | TW D | 405 | 47 | 47 | 46 | 44 | 43 | 42 | 41 | 40 | 38 | 37 | 35 |
| Taxiway Delta | TW D | 410 | 94 | 93 | 91 | 90 | 88 | 86 | 84 | 82 | 81 | 79 | 78 |
| Taxiway Delta | TW D | 411 | 88 | 88 | 86 | 84 | 82 | 81 | 79 | 78 | 76 | 75 | 73 |
| Taxiway Delta | TW D | 412 | 94 | 93 | 91 | 90 | 88 | 86 | 84 | 82 | 81 | 79 | 78 |
| Taxiway D-1 | TW D1 | 415 | 56 | 56 | 55 | 54 | 53 | 52 | 51 | 50 | 49 | 47 | 46 |
| Taxiway D-2 | TW D2 | 420 | 53 | 53 | 52 | 51 | 50 | 49 | 47 | 46 | 45 | 44 | 43 |
| Taxiway Echo | TW E | 503 | 100 | 99 | 97 | 95 | 92 | 91 | 89 | 87 | 85 | 83 | 82 |
| Taxiway Echo | TW E | 505 | 95 | 94 | 91 | 88 | 86 | 83 | 81 | 79 | 77 | 76 | 74 |
| Taxiway Echo | TW E | 507 | 91 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 | 73 |
| Taxiway Echo | TW E | 510 | 95 | 94 | 91 | 88 | 86 | 83 | 81 | 79 | 77 | 76 | 74 |

Table D-1: Pavement Condition Prediction (Continued)

| David North | Door of ID | Section | Current | | | | | PCI Fo | recast | | | | |
|-----------------|------------|---------|---------|------|------|------|------|--------|--------|------|------|------|------|
| Branch Name | Branch ID | ID | PCI | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 |
| Taxiway Echo | TW E | 513 | 100 | 99 | 97 | 95 | 92 | 91 | 89 | 87 | 85 | 83 | 82 |
| Taxiway E-1 | TW E1 | 515 | 100 | 98 | 95 | 92 | 89 | 86 | 84 | 81 | 79 | 78 | 76 |
| Taxiway E-1 | TW E1 | 516 | 91 | 90 | 89 | 87 | 85 | 83 | 82 | 80 | 79 | 77 | 76 |
| Taxiway E-2 | TW E2 | 520 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 73 | 71 | 71 | 70 |
| Taxiway E-3 | TW E3 | 525 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 73 | 71 | 71 | 70 |
| Taxiway E-4 | TW E4 | 527 | 87 | 87 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 73 |
| Taxiway E-5 | TW E5 | 529 | 93 | 92 | 90 | 89 | 87 | 85 | 83 | 82 | 80 | 79 | 77 |
| Taxiway E-5 | TW E5 | 530 | 92 | 91 | 88 | 86 | 83 | 81 | 79 | 77 | 76 | 74 | 73 |
| Taxiway Foxtrot | TW F | 605 | 93 | 92 | 89 | 87 | 84 | 82 | 80 | 78 | 76 | 75 | 73 |
| Taxiway Golf | TW G | 705 | 96 | 95 | 92 | 89 | 86 | 84 | 82 | 80 | 78 | 76 | 75 |
| Taxiway Golf | TW G | 710 | 91 | 90 | 89 | 87 | 85 | 83 | 82 | 80 | 79 | 77 | 76 |
| Taxiway Hotel | TW H | 815 | 91 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 | 73 |
| Taxiway H-1 | TW H1 | 805 | 91 | 90 | 89 | 87 | 85 | 83 | 82 | 80 | 79 | 77 | 76 |
| Taxiway H-2 | TW H2 | 810 | 85 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 73 | 71 |
| Taxiway H-3 | TW H3 | 330 | 88 | 87 | 85 | 82 | 80 | 78 | 77 | 75 | 74 | 73 | 72 |
| Taxiway H-4 | TW H4 | 340 | 100 | 99 | 96 | 92 | 89 | 87 | 84 | 82 | 80 | 78 | 76 |
| Taxiway H-5 | TW H5 | 350 | 91 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 | 73 |
| Taxiway H-6 | TW H6 | 360 | 93 | 92 | 89 | 87 | 84 | 82 | 80 | 78 | 76 | 75 | 73 |
| Taxiway H-7 | TW H7 | 370 | 94 | 93 | 90 | 87 | 85 | 83 | 80 | 79 | 77 | 75 | 74 |




Figure D-1: Predicted PCI by Pavement Use

APPENDIX E

YEAR 1 MAINTENANCE ACTIVITIES TABLE

Table E-1: Year 1 Maintenance Activities

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| North Apron | AP N | 4205 | OIL SPILLAGE | N | Patching - AC Shallow | 1,782.80 | SqFt | \$2.90 | \$5,170.22 |
| North Apron | AP N | 4205 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 24,779.80 | SqFt | \$0.40 | \$9,912.00 |
| North Apron | AP N | 4205 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 31.50 | SqFt | \$0.40 | \$12.60 |
| North Apron | AP N | 4215 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,200.00 | SqFt | \$0.40 | \$480.00 |
| North Apron | AP N | 4220 | OIL SPILLAGE | N | Patching - AC Shallow | 36.90 | SqFt | \$2.90 | \$106.98 |
| North Apron | AP N | 4220 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 7,437.70 | SqFt | \$0.40 | \$2,975.09 |
| North Apron | AP N | 4230 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 628.30 | SqFt | \$0.40 | \$251.32 |
| Northeast Apron | AP NE | 4310 | OIL SPILLAGE | N | Patching - AC Shallow | 80.40 | SqFt | \$2.90 | \$233.14 |
| Northeast Apron | AP NE | 4310 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 769.90 | SqFt | \$0.40 | \$307.96 |
| Northeast Apron | AP NE | 4315 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 486.80 | SqFt | \$0.40 | \$194.73 |
| Northeast Apron | AP NE | 4315 | OIL SPILLAGE | N | Patching - AC Shallow | 55.00 | SqFt | \$2.90 | \$159.39 |
| Northeast Apron | AP NE | 4325 | OIL SPILLAGE | N | Patching - AC Shallow | 786.40 | SqFt | \$2.90 | \$2,280.52 |
| Northeast Apron | AP NE | 4325 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 15,266.90 | SqFt | \$0.40 | \$6,106.82 |
| South Apron | AP S | 4105 | OIL SPILLAGE | N | Patching - AC Shallow | 37.30 | SqFt | \$2.90 | \$108.16 |
| South Apron | AP S | 4105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 65,754.70 | SqFt | \$0.40 | \$26,302.08 |
| South Apron | AP S | 4105 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 1,948.80 | SqFt | \$0.40 | \$779.52 |
| South Apron | AP S | 4110 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 2,234.60 | SqFt | \$0.40 | \$893.85 |
| South Apron | AP S | 4110 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 23,805.80 | SqFt | \$0.40 | \$9,522.39 |
| South Apron | AP S | 4110 | OIL SPILLAGE | N | Patching - AC Shallow | 2,410.10 | SqFt | \$2.90 | \$6,989.23 |
| South Apron | AP S | 4115 | OIL SPILLAGE | N | Patching - AC Shallow | 12,653.20 | SqFt | \$2.90 | \$36,694.29 |
| South Apron | AP S | 4115 | WEATH/RAVEL | Н | Microsurfacing - AC | 249.80 | SqFt | \$0.65 | \$162.34 |
| South Apron | AP S | 4115 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 48,751.70 | SqFt | \$0.40 | \$19,500.83 |
| South Apron | AP S | 4115 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 6,460.30 | SqFt | \$0.40 | \$2,584.13 |

Table E-1: Year 1 Maintenance Activities (Continued)

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| South Apron | AP S | 4140 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 43,873.60 | SqFt | \$0.40 | \$17,549.58 |
| Southeast Apron | AP SE | 4410 | OIL SPILLAGE | N | Patching - AC Shallow | 346.90 | SqFt | \$2.90 | \$1,005.91 |
| Southeast Apron | AP SE | 4410 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 45,219.60 | SqFt | \$0.40 | \$18,088.00 |
| Runway 13-31 | RW 13-31 | 6205 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 11,875.80 | SqFt | \$0.40 | \$4,750.37 |
| Runway 13-31 | RW 13-31 | 6210 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,002.00 | SqFt | \$0.40 | \$1,600.80 |
| Runway 9L-27R | RW 9L-27R | 6104 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 400.00 | SqFt | \$0.40 | \$160.00 |
| Runway 9L-27R | RW 9L-27R | 6105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 12,618.40 | SqFt | \$0.40 | \$5,047.41 |
| Runway 9L-27R | RW 9L-27R | 6109 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 200.00 | SqFt | \$0.40 | \$80.00 |
| Runway 9L-27R | RW 9L-27R | 6110 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,600.00 | SqFt | \$0.40 | \$1,840.00 |
| Runway 9L-27R | RW 9L-27R | 6126 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 200.00 | SqFt | \$0.40 | \$80.00 |
| Runway 9L-27R | RW 9L-27R | 6131 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 404.00 | SqFt | \$0.40 | \$161.60 |
| Runway 9R-27L | RW 9R-27L | 6305 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 8,217.00 | SqFt | \$0.40 | \$3,286.82 |
| Runway 9R-27L | RW 9R-27L | 6305 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 9,914.10 | SqFt | \$0.40 | \$3,965.68 |
| Runway 9R-27L | RW 9R-27L | 6310 | OIL SPILLAGE | N | Patching - AC Shallow | 46.30 | SqFt | \$2.90 | \$134.28 |
| Runway 9R-27L | RW 9R-27L | 6310 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,571.20 | SqFt | \$0.40 | \$1,828.50 |
| Runway 9R-27L | RW 9R-27L | 6310 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 8,348.90 | SqFt | \$0.40 | \$3,339.60 |
| Runway 9R-27L | RW 9R-27L | 6311 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 336.00 | SqFt | \$0.40 | \$134.40 |
| Taxiway 1 | TW 1 | 270 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 252.50 | SqFt | \$0.40 | \$101.00 |
| Taxiway 2 | TW 2 | 260 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 41.40 | SqFt | \$0.40 | \$16.55 |
| Taxiway 2 | TW 2 | 260 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 413.70 | SqFt | \$0.40 | \$165.47 |
| Taxiway 3 | TW 3 | 250 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 359.90 | SqFt | \$0.40 | \$143.96 |
| Taxiway 4 | TW 4 | 240 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 865.30 | SqFt | \$0.40 | \$346.11 |
| Taxiway 5 | TW 5 | 230 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 2,585.50 | SqFt | \$0.40 | \$1,034.22 |

Table E-1: Year 1 Maintenance Activities (Continued)

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|---------------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| Taxiway 6 | TW 6 | 220 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,802.70 | SqFt | \$0.40 | \$721.09 |
| Taxiway 7 | TW 7 | 210 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,308.20 | SqFt | \$0.40 | \$523.26 |
| Taxiway Alpha | TW A | 105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,684.90 | SqFt | \$0.40 | \$1,873.97 |
| Taxiway Alpha | TW A | 108 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 5,550.00 | SqFt | \$0.40 | \$2,220.00 |
| Taxiway Alpha | TW A | 110 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 101.30 | SqFt | \$0.40 | \$40.52 |
| Taxiway A-1 | TW A1 | 115 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 857.10 | SqFt | \$0.40 | \$342.83 |
| Taxiway A-2 | TW A2 | 120 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 914.20 | SqFt | \$0.40 | \$365.68 |
| Taxiway A-3 | TW A3 | 124 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 810.50 | SqFt | \$0.40 | \$324.18 |
| Taxiway A-3 | TW A3 | 125 | OIL SPILLAGE | N | Patching - AC Shallow | 20.40 | SqFt | \$2.90 | \$59.13 |
| Taxiway A-3 | TW A3 | 125 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 31.50 | SqFt | \$0.40 | \$12.59 |
| Taxiway to NE Apron | TW AP NE | 1005 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 9,576.50 | SqFt | \$0.40 | \$3,830.65 |
| Taxiway to SE Apron | TW AP SE | 1105 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 805.00 | SqFt | \$0.40 | \$322.02 |
| Taxiway Charlie | TW C | 910 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 2,761.30 | SqFt | \$0.40 | \$1,104.55 |
| Taxiway C-1 | TW C1 | 310 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,762.30 | SqFt | \$0.40 | \$704.93 |
| Taxiway C-1 | TW C1 | 310 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 65.90 | SqFt | \$0.40 | \$26.35 |
| Taxiway C-2 | TW C2 | 320 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,753.80 | SqFt | \$0.40 | \$701.53 |
| Taxiway CC | TW CC | 905 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,174.50 | SqFt | \$0.40 | \$469.79 |
| Taxiway Delta | TW D | 410 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 289.10 | SqFt | \$0.40 | \$115.65 |
| Taxiway Delta | TW D | 411 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,425.90 | SqFt | \$0.40 | \$570.36 |
| Taxiway Delta | TW D | 412 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 199.10 | SqFt | \$0.40 | \$79.63 |
| Taxiway Echo | TW E | 505 | WEATH/RAVEL | M | Surface Seal - Coat Tar | 99.30 | SqFt | \$0.40 | \$39.70 |
| Taxiway Echo | TW E | 505 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 4,893.10 | SqFt | \$0.40 | \$1,957.27 |
| Taxiway Echo | TW E | 507 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 618.60 | SqFt | \$0.40 | \$247.44 |

Table E-1: Year 1 Maintenance Activities (Continued)

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|---------------|-------------------------|----------------------|-----------------------------|------------------|--------------|--------------|--------------|
| Taxiway Echo | TWE | 510 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 806.60 | SqFt | \$0.40 | \$322.63 |
| Taxiway E-1 | TW E1 | 516 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 1,618.20 | SqFt | \$0.40 | \$647.29 |
| Taxiway E-2 | TW E2 | 520 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 12,613.30 | SqFt | \$0.40 | \$5,045.35 |
| Taxiway E-3 | TW E3 | 525 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 9,121.50 | SqFt | \$0.40 | \$3,648.61 |
| Taxiway E-4 | TW E4 | 527 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 2,101.30 | SqFt | \$0.40 | \$840.53 |
| Taxiway E-5 | TW E5 | 529 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 516.40 | SqFt | \$0.40 | \$206.57 |
| Taxiway E-5 | TW E5 | 530 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 742.50 | SqFt | \$0.40 | \$297.02 |
| Taxiway Foxtrot | TW F | 605 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 800.50 | SqFt | \$0.40 | \$320.22 |
| Taxiway Golf | TW G | 710 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 244.40 | SqFt | \$0.40 | \$97.75 |
| Taxiway Hotel | TW H | 815 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 5,513.90 | SqFt | \$0.40 | \$2,205.59 |
| Taxiway H-1 | TW H1 | 805 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 70.00 | SqFt | \$0.40 | \$28.00 |
| Taxiway H-2 | TW H2 | 810 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 437.90 | SqFt | \$0.40 | \$175.16 |
| Taxiway H-3 | TW H3 | 330 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 324.40 | SqFt | \$0.40 | \$129.77 |
| Taxiway H-5 | TW H5 | 350 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 413.70 | SqFt | \$0.40 | \$165.47 |
| Taxiway H-6 | TW H6 | 360 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 413.70 | SqFt | \$0.40 | \$165.47 |
| Taxiway H-7 | TW H7 | 370 | WEATH/RAVEL | L | Surface Seal - Rejuvenating | 248.80 | SqFt | \$0.40 | \$99.53 |
| | | | | | | | | Total = | \$227,635.93 |

APPENDIX F

MAJOR M&R PLAN BY YEAR UNDER UNLIMITED FUNDING SCENARIO TABLE


Table F-1: Major M&R Plan by Year under Unlimited Funding Scenario

| Year | Branch Name | Section ID | Surface Type | Section Area (ft²) | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|------|-----------------|---------------|-----------------|--------------------|---------------------|----------------------|------------------|---------------------|
| 2012 | North Apron | 4225 | AC | 69,490 | \$178,450.31 | 64 | Mill and Overlay | 100 |
| 2012 | South Apron | 4125 | AC | 35,371 | \$110,498.16 | 62 | Mill and Overlay | 100 |
| 2012 | South Apron | 4130 | AC | 19,714 | \$258,061.25 | 35 | Reconstruction | 100 |
| 2012 | South Apron | 4135 | AC | 29,788 | \$121,327.74 | 59 | Mill and Overlay | 100 |
| 2012 | Taxiway Delta | 405 | AC | 210,898 | \$1,604,932.90 | 47 | Mill and Overlay | 100 |
| 2012 | Taxiway D-1 | 415 | AC | 50,475 | \$265,094.71 | 56 | Mill and Overlay | 100 |
| 2012 | Taxiway D-2 | 420 | AC | 50,463 | \$324,527.06 | 53 | Mill and Overlay | 100 |
| 2013 | Southeast Apron | 4410 | AC | 45,220 | \$119,608.70 | 64 | Mill and Overlay | 100 |
| 2014 | North Apron | 4230 | AC | 18,795 | \$56,747.42 | 63 | Mill and Overlay | 100 |
| 2014 | South Apron | 4140 | AC | 43,874 | \$132,469.55 | 63 | Mill and Overlay | 100 |
| 2021 | North Apron | 4220 | AAC | 109,500 | \$366,896.97 | 64 | Mill and Overlay | 100 |
| | | | | \$3,538,614.77 | 57 | | 100 | |

^{*} Costs are adjusted for inflation.

APPENDIX G

10-YEAR M&R MAP



APPENDIX H

PHOTOGRAPHS




Runway 13-31, Section 6210, Sample Unit 508 – Low severity (52) Weathering and Raveling; low severity (48) Longitudinal and Transverse Cracking



Runway 9L-27R, Section 6131, Sample Unit 396 – Low severity (52) Weathering and Raveling; low severity (48) Longitudinal and Transverse Cracking



Runway 9R-27L, Section 6310, Sample Unit 544 – Low to medium severity (52) Weathering and Raveling



Taxiway Alpha, Section 108, Sample Unit 148 – Low severity (52) Weathering and Raveling; low severity (48) Longitudinal and Transverse Cracking



Taxiway D-1, Section 415, Sample Unit 101 – Low to medium severity (52) Weathering and Raveling; low severity (48) Longitudinal and Transverse Cracking



Taxiway D-2, Section 420, Sample Unit 205 – Low to medium severity (52) Weathering and Raveling; low severity (48) Longitudinal and Transverse Cracking



Taxiway Echo, Section 505, Sample Unit 159 – Medium severity (52) Weathering and Raveling



North Apron, Section 4205, Sample Unit 312 – Low severity (52) Weathering and Raveling; low severity (48) Longitudinal and Transverse Cracking; low severity (56) Swelling; (49) Oil Spillage



North Apron, Section 4230, Sample Unit 102 – Low severity (52) Weathering and Raveling; low severity (45) Depression



Northeast Apron, Section 4305, Sample Unit 201 – Low severity (74) Joint Spalling



South Apron, Section 4140, Sample Unit 402 – Low severity (52) Weathering and Raveling; low severity (43) Block Cracking



Southeast Apron, Section 4410, Sample Unit 501 – Low severity (52) Weathering and Raveling; low severity (48) Longitudinal and Transverse Cracking; (49) Oil Spillage

APPENDIX I

PCI RE-INSPECTION REPORT

FDOT COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Branch: AP N Name: NORTH APRON Use: APRON Area: 1,097,784.76SqFt Section: 5 From: -To: -Last Const.: 1/1/2006 4205 of Surface: Family: DEFAULT Zone: Category: Rank: P AAC Area: 840,000.00SqFt Length: 2,800.00Ft Width: 300.00Ft Lanes: 0 Shoulder: Street Type: Grade: 0.00 Section Comments: Last Insp. Date3/26/2012 Total Samples: 168 Surveyed: 16 Conditions: PCI:90.00 | Inspection Comments: Type: R 5,000.00SqFt PCI = 89Sample Number: 104 Area: Sample Comments: 52 WEATHERING/RAVELING 3.00 SqFt Comments: Μ 52 WEATHERING/RAVELING 150.00 SqFt L Comments: 49 OIL SPILLAGE Ν 8.00 SqFt Comments: PCI = 93Sample Number: 114 Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 11.00 Ft Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: Sample Number: 207 Area: 5,000.00SqFt PCI = 96Type: R Sample Comments: 52 WEATHERING/RAVELING L 110.00 SqFt Comments: Sample Number: 217 Type: R Area: 5,000.00SqFt PCI = 88Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 10.00 Ft Comments: 200.00 SqFt 52 WEATHERING/RAVELING L Comments: 49 OIL SPILLAGE Ν 12.00 SqFt Comments: Sample Number: 221 Type: R Area: 5,000.00SqFt PCI = 86Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 31.01 Ft Comments: 49 OIL SPILLAGE Ν 98.00 SqFt Comments: 49 OIL SPILLAGE Ν 10.00 SaFt Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 227 PCI = 90Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 32.01 Ft Comments: 52 WEATHERING/RAVELING L 200.00 SqFt Comments: Sample Number: 312 5,000.00SqFt PCI = 80Type: R Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 141.04 Ft L Comments: 49 OIL SPILLAGE Ν 8.00 SqFt Comments: 56 SWELLING 48.00 SqFt Comments: L 52 WEATHERING/RAVELING 200.00 SqFt Comments: PCI = 96Sample Number: 325 Area: 5,000.00SqFt Type: R Sample Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

| Sample Number: 402 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 93 | |
|---|-------|---|--------------|------|-----------|--|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 8.00 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 | SqFt | Comments: | |
| Sample Number: 508 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 91 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 47.01 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 | SqFt | Comments: | |
| Sample Number: 516 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 93 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 6.00 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 | SqFt | Comments: | |
| Sample Number: 523 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 92 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 32.01 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 | SqFt | Comments: | |
| Sample Number: 604 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 92 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 29.01 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 | SqFt | Comments: | |
| Sample Number: 610 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 94 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 2.00 | | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 | SqFt | Comments: | |
| Sample Number: 619 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 81 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 47.01 | Ft | Comments: | |
| 49 OIL SPILLAGE | | N | 18.00 | | Comments: | |
| 52 WEATHERING/RAVELING | | L | 500.00 | _ | Comments: | |
| 56 SWELLING | | L | 12.00 | SqFt | Comments: | |
| Sample Number: 627 Type: R Sample Comments: | Area: | | 5,000.00SqFt | | PCI = 94 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 1.00 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 | SqFt | Comments: | |

300.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: NORTH APRON Use: APRON AP N Area: 1,097,784.76SqFt

Section: 4215 of 5 From: -To: -Last Const.: 1/1/2006

Family: DEFAULT Zone: Rank: P Surface: Category: AAC

Area: 60,000.00SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 12 Surveyed: 2

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 228 Type: R Area: 5,000.00SqFt PCI = 92

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 21.01 Ft Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

Sample Number: 529 Type: R Area: 5,000.00SqFt PCI = 91Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING

L 55.01 Ft Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP N Name: NORTH APRON Use: APRON Area: 1,097,784.76SqFt

Section: 4220 of 5 From: - To: - Last Const.: 1/1/1994

300.00Ft

Comments:

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 109,500.00SqFt Length: 365.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 24 Surveyed: 3

Conditions: PCI:76.00 | Inspection Comments:

| Sample Number: 133 | Type: R | Area: | 3,250.00SqFt | PCI = 76 |
|--------------------|---------|-------|--------------|----------|
| Sample Comments: | | | | |

48 LONGITUDINAL/TRANSVERSE CRACKING L 148.04 Ft

52 WEATHERING/RAVELING L 500.00 SqFt Comments: 56 SWELLING L 136.00 SqFt Comments:

| Sample Number: | 231 | Type: R | Area: | 5,000.00SqFt | PCI = 88 |
|------------------|-----|---------|-------|--------------|----------|
| Sample Comments: | | | | | |

48 LONGITUDINAL/TRANSVERSE CRACKING L 62.02 Ft Comments: 52 WEATHERING/RAVELING L 150.00 SqFt Comments:

56 SWELLING L 26.00 SqFt Comments:

Sample Number: 532 Type: R Area: 5,000.00SqFt PCI = 65Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 506.13 Ft Comments: 56 SWELLING L 639.99 SqFt Comments: 52 WEATHERING/RAVELING L 250.00 SqFt Comments:

49 OIL SPILLAGE N 2.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: NORTH APRON Use: APRON AP N Area: 1,097,784.76SqFt

Section: 4225 of 5 From: -To: -Last Const.: 12/25/199

3,000.00SqFt

30.00Ft

PCI = 68

Family: DEFAULT Zone: Category: Rank: P Surface: AC

Area: 69,490.00SqFt Length: 2,300.00Ft Width: Street Type: Grade: 0.00 Lanes: 0

Type: R

Shoulder: Section Comments:

Last Insp. Date3/26/2012 Total Samples: 20 Surveyed: 3

Conditions: PCI:64.00 | Inspection Comments:

Sample Number: 101

| Sample Comments: | | | | |
|------------------------|---|----------|------|-----------|
| 52 WEATHERING/RAVELING | M | 90.00 | SqFt | Comments: |
| 52 WEATHERING/RAVELING | L | 2,399.98 | SqFt | Comments: |
| 49 OIL SPILLAGE | N | 7.00 | SqFt | Comments: |

Area:

| Sample Number: 302 | Type: R | Area: | 4,500.00SqFt | PCI = 64 |
|----------------------|-----------------|-------|--------------|----------------|
| Sample Comments: | | | | |
| 48 LONGITUDINAL/TRAN | SVERSE CRACKING | L | 172.04 | Ft Comments: |
| 52 WEATHERING/RAVELI | ING | L | 3,599.97 | SqFt Comments: |
| 50 PATCHING | | L | 20.00 | SqFt Comments: |
| 52 WEATHERING/RAVELT | NG | M | 4.00 | Saft Comments: |

| Sample Number: 500 Sample Comments: | Type: R | Area: | 3,760.00SqFt | PCI = 62 |
|-------------------------------------|--------------------|-------|--------------|----------------|
| 49 OIL SPILLAGE | | N | 16.00 | SqFt Comments: |
| 49 OIL SPILLAGE | | N | 30.00 | SqFt Comments: |
| 48 LONGITUDINAL/T | RANSVERSE CRACKING | L | 62.02 | Ft Comments: |
| 52 WEATHERING/RAV | ELING | L | 3,007.97 | SqFt Comments: |
| 52 WEATHERING/RAV | ELING | H | 4.00 | SqFt Comments: |

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP N Name: NORTH APRON Use: APRON Area: 1,097,784.76SqFt

Section: 4230 of 5 From: - To: - Last Const.: 12/25/199

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 18,794.76SqFt Length: 150.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

.

Last Insp. Date3/26/2012 Total Samples: 3 Surveyed: 1

Conditions: PCI:66.00 | Inspection Comments:

Sample Number: 102 Type: R Area: 7,478.41SqFt PCI = 66

Sample Comments:

45 DEPRESSION L 901.99 SqFt Comments: 52 WEATHERING/RAVELING L 250.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP NE Name: NORTHEAST APRON Use: APRON Area: 112,013.84SqFt

Section: 4305 of 6 From: - To: - Last Const.: 12/25/199

50.00Ft

Surface: PCC Family: DEFAULT Zone: Category: Rank: P

Area: 9,600.00SqFt Length: 190.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 3 Surveyed: 1

Conditions: PCI:95.00 | Inspection Comments:

Sample Number: 201 Type: R Area: 20.00Slabs PCI = 95

Sample Comments:

74 JOINT SPALLING L 3.00 Slabs Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP NE Name: NORTHEAST APRON Use: APRON Area: 112,013.84SqFt

Section: 4310 of 6 From: - To: - Last Const.: 12/25/199

90.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 19,797.46SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 5 Surveyed: 1

Conditions: PCI:89.00 | Inspection Comments:

| Sample Number: 103 | Type: R | Area: | 4.500.00SaFt | PCI = 89 |
|--------------------|---------|-------|--------------|----------|

Sample Comments: 75.00 SqFt 52 WEATHERING/RAVELING L Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 3.00 Ft Comments: 49 OIL SPILLAGE Ν 11.00 SqFt Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP NE Name: NORTHEAST APRON Use: APRON Area: 112,013.84SqFt

Section: 4315 of 6 From: - To: - Last Const.: 12/25/199

85.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 21,176.35SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 5 Surveyed: 1

Conditions: PCI:89.00 | Inspection Comments:

Sample Number: 103 Type: R Area: 4,350.00SqFt PCI = 89

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 27.01 Ft Comments: 49 OIL SPILLAGE N 6.00 SqFt Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP NE Name: NORTHEAST APRON Use: APRON Area: 112,013.84SqFt

Section: 4320 of 6 From: - To: - Last Const.: 12/25/199

50.00Ft

Surface: PCC Family: DEFAULT Zone: Category: Rank: P

Area: 9,216.00SqFt Length: 180.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 3 Surveyed: 1

Conditions: PCI:92.00 | Inspection Comments:

Sample Number: 201 Type: R Area: 20.00Slabs PCI = 92

Sample Comments:

74 JOINT SPALLING L 6.00 Slabs Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP NE Name: NORTHEAST APRON Use: APRON Area: 112,013.84SqFt

Section: 4325 of 6 From: - To: - Last Const.: 12/25/199

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 49,524.03SqFt Length: 495.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Shoulder: Street Type: Grade: 0.00 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 12 Surveyed: 2

Conditions: PCI:81.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 3,504.82SqFt PCI = 80

Sample Comments:

49 OIL SPILLAGE N 45.00 SqFt Comments: 49 OIL SPILLAGE N 70.00 SqFt Comments: 52 WEATHERING/RAVELING L 875.99 SqFt Comments:

Sample Number: 108 Type: R Area: 4,900.00SqFt PCI = 82

Sample Comments:

52 WEATHERING/RAVELING L 1,714.99 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP NE Name: NORTHEAST APRON Use: APRON Area: 112,013.84SqFt

Section: 4330 of 6 From: - To: - Last Const.: 12/25/199

45.00Ft

Surface: PCC Family: DEFAULT Zone: Category: Rank: P

Area: 2,700.00SqFt Length: 60.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 1 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 300 Type: R Area: 12.00Slabs PCI = 91

Sample Comments:

74 JOINT SPALLING L 4.00 Slabs Comments:

FDOT COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Use: APRON Branch: AP S Name: SOUTH APRON Area: 1,412,105.15SqFt Section: of 7 From: -To: -Last Const.: 1/1/1998 4105 Zone: Surface: Family: DEFAULT Category: Rank: P ACArea: 210,000.00SqFt Length: 700.00Ft Width: 300.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date3/26/2012 Total Samples: 42 Surveyed: 5 Conditions: PCI:77.00 | Inspection Comments: Sample Number: 200 Type: R 5,000.00SqFt PCI = 57Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 626.16 Ft Comments: 52 WEATHERING/RAVELING 1,999.98 SqFt Comments: L 49 OIL SPILLAGE Ν 2.00 SqFt Comments: 52 WEATHERING/RAVELING 8.00 SqFt Comments: M 260.00 SqFt 56 SWELLING Comments: L Sample Number: 205 PCI = 98Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING L 19.00 SqFt Comments: 5,000.00SqFt Sample Number: 302 Type: R Area: PCI = 64Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 336.09 Ft Comments: 52 WEATHERING/RAVELING Μ 110.00 SqFt Comments: 52 WEATHERING/RAVELING Μ 60.00 SqFt Comments: 52 WEATHERING/RAVELING 4,829.96 SqFt Comments: Τ, Sample Number: 504 Type: R Area: 5,000.00SqFt PCI = 82Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 15.00 Ft Comments: L 52 WEATHERING/RAVELING Μ 54.00 SqFt Comments: 336.00 SqFt 52 WEATHERING/RAVELING Comments: L 52 WEATHERING/RAVELING 168.00 SaFt Comments:

| 32 WEATHERING/RAVEDING | ш | 100.00 5416 | Commerce. |
|---|-------|--------------|-----------|
| Sample Number: 606 Type: R Sample Comments: | Area: | 5,000.00SqFt | PCI = 85 |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 69.02 Ft | Comments: |
| 52 WEATHERING/RAVELING | L | 290.00 SqFt | Comments: |
| 52 WEATHERING/RAVELING | L | 185.00 SqFt | Comments: |

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

| Network: TMB Name: KENDALL-TAMIAMI EX | KECUTIVE A | AIRPORT | | | | | |
|--|------------|-----------------|----------------|------|-----------|---------------------|-----|
| Branch: AP S Name: SOUTH APRON | | | Use: AP | RON | Area: | 1,412,105.15SqFt | |
| Section: 4110 of 7 From: - Surface: AAC Family: DEFAULT Area: 240,842.74SqFt Length: 800.00Ft Shoulder: Street Type: Grade: 0.00 Section Comments: | | Zone: Width: | To: - Categ | • | Rank: P | Last Const.: 1/1/19 | 998 |
| Last Insp. Date3/26/2012 Total Samples: 48 Sur- Conditions: PCI:83.00 Inspection Comments: | veyed: 5 | | | | | | |
| Sample Number: 107 Type: R Sample Comments: <no distresses=""></no> | Area: | 5,000.0 |)SqFt | | PCI = 100 | | |
| Sample Number: 111 Type: R | Area: | 4,685.2 | 5SqFt | | PCI = 97 | | |
| Sample Comments: 52 WEATHERING/RAVELING | | L | 48.00 | C~F+ | Commen | + a • | |
| 52 WEATHERING/RAVELING | | L | 27.00 | - | Commen | | |
| Sample Number: 213 Type: R Sample Comments: | Area: | 5,000.0 |)SqFt | | PCI = 76 | | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 48.01 | Ft | Commen | ts: | |
| 52 WEATHERING/RAVELING |] | M | 20.00 | _ | Commen | ts: | |
| 52 WEATHERING/RAVELING |] | L 1, | L51.99 | SqFt | Commen | ts: | |
| Sample Number: 510 Type: R Sample Comments: | Area: | 6,043.6 |)SqFt | | PCI = 73 | | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L : | L22.03 | Ft | Commen | ts: | |
| 49 OIL SPILLAGE |] | N | 56.00 | SqFt | Commen | ts: | |
| 52 WEATHERING/RAVELING |] | M : | 228.00 | SqFt | Commen | ts: | |
| 52 WEATHERING/RAVELING | | | L56.00 | - | Commen | ts: | |
| 52 WEATHERING/RAVELING | - | L : | L23.00 | SqFt | Commen | ts: | |
| Sample Number: 515 Type: R Sample Comments: | Area: | 6,000.0 |)SqFt | | PCI = 77 | | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | 1 | L | 88.02 | Ft | Commen | ts: | |
| 49 OIL SPILLAGE |] | N : | L90.00 | SqFt | Commen | ts: | |
| 52 WEATHERING/RAVELING | 1 | | L64.00 | | Commen | ts: | |
| 52 WEATHERING/RAVELING | - | L ! | 971.99 | SqFt | Commen | ts: | |

FDOT_COMB

| Report Generated Date: 3/29/2012 Site Name: | | | | | | |
|--|-------------|-----------------|--------------------------|-------|--------------|-----------------------|
| Network: TMB Name: KENDALL-TAMIAMI | EXECUTIVE | AIRPORT | | | | |
| Branch: AP S Name: SOUTH APRON | | | Use: AF | PRON | Area: 1,412, | 105.15SqFt |
| Section: 4115 of 7 From: - Surface: AAC Family: DEFAULT Area: 832,515.06SqFt Length: 2,775.05Ft Shoulder: Street Type: Grade: 0.00 Section Comments: | t Lanes: | Zone: Width: | To: - Categ 300.00 | gory: | Rank: P | Last Const.: 1/1/1998 |
| Last Insp. Date3/26/2012 Total Samples: 168 S Conditions: PCI:86.00 Inspection Comments: | urveyed: 1 | 0 | | | | |
| Sample Number: 227 Type: R Sample Comments: | Area: | 5,000 | .00SqFt | | PCI = 82 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 3.00 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 26.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELING | | L | 288.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELING | | L | 80.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELING | | L | 90.00 | SqFt | Comments: | |
| 49 OIL SPILLAGE | | N | 52.00 | SqFt | Comments: | |
| 49 OIL SPILLAGE | | N | 32.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELING | | L | 58.00 | SqFt | Comments: | |
| Sample Number: 230 Type: R Sample Comments: | Area: | 5,000 | .00SqFt | | PCI = 89 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 66.02 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 117.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELING | | L | 76.00 | SqFt | Comments: | |
| Sample Number: 235 Type: R Sample Comments: | Area: | 5,000 | .00SqFt | | PCI = 97 | |
| 52 WEATHERING/RAVELING | | L | 66.00 | SqFt | Comments: | |
| Sample Number: 317 Type: R Sample Comments: | Area: | 5,000 | .00SqFt | | PCI = 77 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 80.02 | | Comments: | |
| 52 WEATHERING/RAVELING | | M | 12.00 | _ | Comments: | |
| 52 WEATHERING/RAVELING | | L | 867.99 | SqFt | Comments: | |
| Sample Number: 322 Type: R Sample Comments: | Area: | 5,000 | .00SqFt | | PCI = 98 | |
| 52 WEATHERING/RAVELING | | L | 20.00 | SqFt | Comments: | |
| Sample Number: 342 Type: R Sample Comments: | Area: | 5,000 | .00SqFt | | PCI = 70 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 12.00 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | | M | 312.00 | | Comments: | |
| 49 OIL SPILLAGE | | N | 396.00 | _ | Comments: | |
| 52 WEATHERING/RAVELING | | L | 84.00 | | Comments: | |
| 52 WEATHERING/RAVELING | | L | 122.00 | | Comments: | |
| Sample Number: 419 Type: R Sample Comments: | Area: | 5,000 | .00SqFt | | PCI = 78 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 19.00 | | Comments: | |
| 49 OIL SPILLAGE | | N | | SqFt | Comments: | |
| 52 WEATHERING/RAVELING | | M | 64.00 | SqFt | Comments: | |

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

| 52 WEATHERING/RAVELI | NG | | L | 611.99 | SqFt | Comments: | |
|-------------------------------------|-----------------|-------|---|--------------|------|-----------|--|
| Sample Number: 534 Sample Comments: | Type: R | Area: | | 5,000.00SqFt | | PCI = 94 | |
| 52 WEATHERING/RAVELI | NG | | L | 220.00 | SqFt | Comments: | |
| Sample Number: 539 Sample Comments: | Type: R | Area: | | 5,000.00SqFt | | PCI = 79 | |
| 49 OIL SPILLAGE | | | N | 195.00 | SqFt | Comments: | |
| 49 OIL SPILLAGE | | | N | 50.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELI | NG | | L | 50.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELI | NG | | Η | 15.00 | SqFt | Comments: | |
| 52 WEATHERING/RAVELI | NG | | L | 120.00 | SqFt | Comments: | |
| Sample Number: 626 Sample Comments: | Type: R | Area: | | 5,000.00SqFt | | PCI = 94 | |
| 48 LONGITUDINAL/TRAN | SVERSE CRACKING | | L | 27.01 | Ft | Comments: | |
| 52 WEATHERING/RAVELI | NG | | L | 31.00 | SqFt | Comments: | |

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: APS Name: SOUTH APRON Use: APRON Area: 1,412,105.15SqFt

Section: 4125 of 7 From: To: Last Const.: 12/25/199

150.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: T

Area: 35,370.73SqFt Length: 230.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 7 Surveyed: 1

Conditions: PCI:62.00 | Inspection Comments:

| Sample Number: 100 Type: R Sample Comments: | Area: | 5,000.00SqFt | PCI = 62 |
|---|--------------|--------------|--------------|
| 52 WEATHERING/RAVELING | L | 4,999.96 Sql | Ft Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | \mathbf{L} | 54.01 Ft | Comments: |
| 49 OIL SPILLAGE | N | 174.00 Sq | Ft Comments: |
| 49 OIL SPILLAGE | N | 21.00 Sq | Ft Comments: |
| 49 OIL SPILLAGE | N | 12.00 Sql | Ft Comments: |
| 56 SWELLING | L | 16.00 Sql | Ft Comments: |

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: APS Name: SOUTH APRON Use: APRON Area: 1,412,105.15SqFt

Section: 4130 of 7 From: - To: - Last Const.: 12/25/199

50.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 19,714.38SqFt Length: 264.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 6 Surveyed: 1

Conditions: PCI:35.00 | Inspection Comments:

| Sample Number: 101 Type: R | Area: | 5,085.00SqFt | PCI = 35 |
|-------------------------------------|-------------|--------------|--------------|
| Sample Comments: | | | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 226.06 Ft | Comments: |
| 52 WEATHERING/RAVELING | L | 1,270.99 Sql | Ft Comments: |
| 52 WEATHERING/RAVELING | M | 3,813.97 Sql | Ft Comments: |
| 43 BLOCK CRACKING | L | 418.00 Sql | Ft Comments: |
| 43 BLOCK CRACKING | $\mathbf L$ | 189.00 Sql | Ft Comments: |

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: APS Name: SOUTH APRON Use: APRON Area: 1,412,105.15SqFt

Section: 4135 of 7 From: - To: - Last Const.: 12/25/199

36.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 29,788.29SqFt Length: 750.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 8 Surveyed: 1

Conditions: PCI:59.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 5,000.00SqFt PCI = 59

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 167.04 Ft Comments: 43 BLOCK CRACKING L 2,999.98 SqFt Comments: 52 WEATHERING/RAVELING L 4,499.96 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Name: SOUTH APRON Use: APRON Branch: AP S Area: 1,412,105.15SqFt

Section: 4140 of 7 From: -To: -Last Const.: 12/25/199

30.00Ft

Zone: Surface: Family: DEFAULT Category: Rank: P AC

Area: 43,873.95SqFt Length: 1,400.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Total Samples: 16 Last Insp. Date3/26/2012 Surveyed: 3

Conditions: PCI:66.00 | Inspection Comments:

Sample Number: 103 Type: R Area: 3,325.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 65.02 Ft Comments:

52 WEATHERING/RAVELING L 3,324.97 SqFt Comments:

Sample Number: 301 Type: R Area: 2,500.00SqFt PCI = 69

Sample Comments:

52 WEATHERING/RAVELING 2,499.98 SqFt Comments: L

43 BLOCK CRACKING L 500.00 SqFt Comments:

Sample Number: 402 Type: R Area: 2,500.00SqFt PCI = 59

Sample Comments:

52 WEATHERING/RAVELING 2,499.98 SqFt Comments: L

43 BLOCK CRACKING L 2,499.98 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: AP SE Name: SOUTHEAST APRON Use: APRON Area: 45,220.00SqFt

Section: 4410 of 1 From: - To: - Last Const.: 12/25/199

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 45,220.00SqFt Length: 400.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 8 Surveyed: 2

Conditions: PCI:65.00 | Inspection Comments:

| Sample Number: 200 Type: R | Area: | 5,950.00SqFt | | PCI = 65 | |
|-------------------------------------|-----------|--------------|------|-----------|--|
| Sample Comments: | | | | | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | $_{ m L}$ | 132.03 | Ft | Comments: | |
| 52 WEATHERING/RAVELING | L | 5,949.95 | SqFt | Comments: | |
| 49 OIL SPILLAGE | N | 40.00 | SqFt | Comments: | |
| 49 OIL SPILLAGE | N | 4.00 | SqFt | Comments: | |
| | | | | | |

Sample Number: 501 Type: R PCI = 66Area: 5,355.00SqFt Sample Comments: 52 WEATHERING/RAVELING L 5,354.96 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 98.03 Ft Comments: 49 OIL SPILLAGE 25.00 SqFt Comments: Ν

FDOT COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Name: RUNWAY 13-31 Branch: RW 13-31 Use: RUNWAY Area: 600,300.00SqFt Section: 2 To: -Last Const.: 1/1/2004 6205 of From: -Surface: Family: DEFAULT Zone: Category: Rank: P AAC Area: 400,200.00SqFt Length: 4,002.00Ft Width: 100.00Ft Lanes: 0 Shoulder: Street Type: Grade: 0.00 Section Comments: Last Insp. Date3/26/2012 Total Samples: 80 Surveyed: 16 Conditions: PCI:90.00 | Inspection Comments: PCI = 96Sample Number: 301 Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 305 Type: R Area: 5,000.00SqFt PCI = 94Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 1.00 Ft Comments: 100.00 SqFt 52 WEATHERING/RAVELING L Comments: Sample Number: 312 Area: 5,000.00SqFt PCI = 88Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 78.02 Ft L Comments: 52 WEATHERING/RAVELING 250.00 SqFt L Comments: PCI = 91Sample Number: 317 Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 62.02 Ft Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: 5,000.00SqFt PCI = 90Sample Number: 322 Type: R Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 20.01 Ft L Comments: 52 WEATHERING/RAVELING 200.00 SqFt L Comments: PCI = 91Sample Number: 326 Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 56.01 Ft Comments: L 52 WEATHERING/RAVELING 100.00 SqFt L Comments: PCI = 91Sample Number: 330 Type: R 5,000.00SqFt Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING $_{\rm L}$ 46.01 Ft Comments: 52 WEATHERING/RAVELING Τ. 100.00 SqFt Comments: PCI = 88Sample Number: 334 5,000.00SqFt Type: R Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 22.01 Ft Comments: 52 WEATHERING/RAVELING L 320.00 SqFt Comments: Sample Number: 338 Area: 5,000.00SqFt PCI = 90Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 31.01 Ft Comments: 100.00 SqFt 52 WEATHERING/RAVELING L Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

| Sample Number: 343 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 92 | |
|---|-------|---|--------------|--------------|--|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 24.01 Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: | |
| Sample Number: 348 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 89 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 55.01 Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 200.00 Sq | Ft Comments: | |
| Sample Number: 353 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 89 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 78.02 Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 150.00 Sq | Ft Comments: | |
| Sample Number: 358 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 90 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 33.01 Ft | Comments: | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 25.01 Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 154.00 Sq | Ft Comments: | |
| Sample Number: 364 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 88 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 104.03 Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: | |
| Sample Number: 372 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 89 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 90.02 Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: | |
| Sample Number: 378 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 89 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 76.02 Ft | Comments: | |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: | |
| 42 BLEEDING | | N | 8.00 Sq | | |
| | | | 1 | | |

FDOT COMB

Sample Comments:

52 WEATHERING/RAVELING

48 LONGITUDINAL/TRANSVERSE CRACKING

Report Generated Date: 3/29/2012

Site Name: Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Branch: RW 13-31 Name: RUNWAY 13-31 Use: RUNWAY Area: 600,300.00SqFt Section: 2 From: -To: -Last Const.: 1/1/2004 6210 of Surface: Family: DEFAULT Zone: Category: Rank: P AAC Area: 200,100.00SqFt Length: 8,004.00Ft Width: 25.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date3/26/2012 Total Samples: 40 Surveyed: 7 Conditions: PCI:91.00 | Inspection Comments: Sample Number: 100 PCI = 96Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: Sample Number: 120 Type: R Area: 5,000.00SqFt PCI = 91Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 54.01 Ft L Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: PCI = 94Sample Number: 128 Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 4.00 Ft Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 172 PCI = 92Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 29.01 Ft Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 508 Type: R 5,000.00SqFt PCI = 81Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 261.07 Ft Comments: L 3.00 Ft 48 LONGITUDINAL/TRANSVERSE CRACKING Comments: L 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 556 PCI = 93Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 6.00 Ft Comments: L 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 572 PCI = 925,000.00SqFt Type: R Area:

L

L

20.01 Ft

100.00 SqFt

Comments:

Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 750,300.00SqFt

Section: 6104 of 6 From: - To: - Last Const.: 1/1/1997

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 20,000.00SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:90.00 | Inspection Comments:

Sample Number: 301 Type: R Area: 5,000.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 72.02 Ft Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 10.00 Ft Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Branch: Name: RUNWAY 9L-27R Use: RUNWAY Area: 750,300.00SqFt RW 9L-27R Section: 6 From: -To: -Last Const.: 1/1/1965 6105 of Surface: Family: DEFAULT Zone: Category: Rank: P ACArea: 460,000.00SqFt Length: 4,600.00Ft Width: 100.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date3/26/2012 Total Samples: 92 Surveyed: 19 Conditions: PCI:91.00 | Inspection Comments: Type: R PCI = 92Sample Number: 306 Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 21.01 Ft Comments: L 52 WEATHERING/RAVELING 100.00 SqFt Comments: L Sample Number: 309 Type: R Area: 5,000.00SqFt PCI = 85Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 54.01 Ft Comments: 52 WEATHERING/RAVELING L 500.00 SaFt Comments: Sample Number: 312 Type: R Area: 5,000.00SqFt PCI = 90Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 71.02 Ft L Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: Sample Number: 316 Type: R Area: 5,000.00SqFt PCI = 91Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 59.02 Ft Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 322 Type: R Area: 5,000.00SqFt PCI = 91Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 44.01 Ft Comments: L 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 328 PCI = 92Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 31.01 Ft T. Comments: PCI = 92Sample Number: 331 5,000.00SqFt Type: R Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 18.00 Ft Comments: 52 WEATHERING/RAVELING Comments: L 100.00 SqFt Sample Number: 334 PCI = 91Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING $_{\rm L}$ 42.01 Ft Comments: 52 WEATHERING/RAVELING 100.00 SqFt Τ. Comments: PCI = 96Sample Number: 340 Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 28.01 Ft L Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

| | | - | · | |
|---|--------|--------|---|---------------------|
| Sample Number: 347 Type: R | Area: | | 5,000.00SqFt | PCI = 91 |
| Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 42.01 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comments: |
| | | | | |
| Sample Number: 352 Type: R | Area: | | 5,000.00SqFt | PCI = 91 |
| Sample Comments: | | - | 40.01.71 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING 52 WEATHERING/RAVELING | | L L | 49.01 Ft 100.00 SqFt | Comments: Comments: |
| 32 WEATHERING/RAVELING | | ш | 100.00 Sqrt | Commencs. |
| Sample Number: 358 Type: R | Area: | | 5,000.00SqFt | PCI = 92 |
| Sample Comments: | | | . 1 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 30.01 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comments: |
| Consula Number: 264 Tomas B | A | | 5 000 00G F: | DCI 02 |
| Sample Number: 364 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 92 |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 18.00 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 4.00 Ft | Comments: |
| - | | | | |
| Sample Number: 367 Type: R | Area: | | 5,000.00SqFt | PCI = 91 |
| Sample Comments: | | т. | 42 O1 ⊞≒ | Commont at |
| 48 LONGITUDINAL/TRANSVERSE CRACKING 52 WEATHERING/RAVELING | | L L | 43.01 Ft 100.00 SqFt | Comments: Comments: |
| JZ WEATHERING/RAVELING | | ш | 100.00 5qrc | Commence. |
| Sample Number: 370 Type: R | Area: | | 5,000.00SqFt | PCI = 92 |
| Sample Comments: | | | - | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 33.01 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 106.00 SqFt | Comments: |
| Sample Number: 27/ Type: B | A root | | 5 000 000 -E4 | PCI = 91 |
| Sample Number: 376 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PC1 = 91 |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 59.02 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comments: |
| | | | | |
| Sample Number: 383 Type: R | Area: | | 5,000.00SqFt | PCI = 85 |
| Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 52.01 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 500.00 SqFt | Comments: |
| —————————————————————————————————————— | | ш | 300.00 bqrc | Commerces. |
| Sample Number: 388 Type: R | Area: | | 5,000.00SqFt | PCI = 90 |
| Sample Comments: | | | -) - v - · · · · · · · · · · · · · · · · · | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 37.01 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 200.00 SqFt | Comments: |
| G 1 N 1 | | | | DOI: 0.4 |
| Sample Number: 391 Type: R | Area: | | 5,000.00SqFt | PCI = 94 |
| Sample Comments: | | | | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 76.02 Ft | Comments: |

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 750,300.00SqFt

Section: 6109 of 6 From: - To: - Last Const.: 1/1/1997

25.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 10,000.00SqFt Length: 400.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 2 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 100 Type: R Area: 5,000.00SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 47.01 Ft Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Sample Comments:

52 WEATHERING/RAVELING

48 LONGITUDINAL/TRANSVERSE CRACKING

Report Generated Date: 3/29/2012

Site Name:

| Site Name: | | | | | |
|---|---------------|-----------------|-------------------------------|----------|-----------------------|
| Network: TMB Name: KENDALL-TAMIA | AMI EXECUTIVE | AIRPORT | | | |
| Branch: RW 9L-27R Name: RUNWAY 9L-27R | | | Use: RUNWAY | Area: | 750,300.00SqFt |
| Section: 6110 of 6 From: - Surface: AC Family: DEFAULT Area: 230,000.00SqFt Length: 9,200. Shoulder: Street Type: Grade: 0.00 Section Comments: | | Zone: Width: | To: - Category: 25.00Ft | Rank: P | Last Const.: 1/1/1965 |
| Last Insp. Date3/26/2012 Total Samples: 46 Conditions: PCI:93.00 Inspection Comments: | Surveyed: 8 | | | | |
| Sample Number: 116 Type: R | Area: | 5,000 | 0.00SqFt | PCI = 96 | |
| Sample Comments: 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comment | cs: |
| Sample Number: 144 Type: R | Area: | 5,000 | 0.00SqFt | PCI = 96 | |
| Sample Comments: 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comment | s: |
| Sample Number: 168 Type: R | Area: | 5,000 | 0.00SqFt | PCI = 96 | |
| Sample Comments: 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comment | cs: |
| Sample Number: 184 Type: R | Area: | 5,000 | 0.00SqFt | PCI = 93 | |
| Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKIN | īG | L | 7.00 Ft | Comment | cs: |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comment | cs: |
| Sample Number: 504 Type: R Sample Comments: | Area: | 5,000 | 0.00SqFt | PCI = 90 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKIN | 1G | L | 73.02 Ft | Comment | cs: |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comment | cs: |
| Sample Number: 520 Type: R Sample Comments: | Area: | 5,000 | 0.00SqFt | PCI = 91 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKIN | IG | L | 44.01 Ft | Comment | es: |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comment | cs: |
| Sample Number: 580 Type: R Sample Comments: | Area: | 5,000 | 0.00SqFt | PCI = 90 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKIN | | L - | 67.02 Ft | Comment | |
| 52 WEATHERING/RAVELING | | L | 100.00 SqFt | Comment | S: |
| Sample Number: 592 Type: R | Area: | 5,000 | 0.00SqFt | PCI = 94 | |

L

100.00 SqFt

2.00 Ft

Comments:

Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 750,300.00SqFt

Section: 6126 of 6 From: - To: - Last Const.: 1/1/1997

25.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 10,100.00SqFt Length: 404.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Conditions: PCI:96.00 | Inspection Comments:

Sample Number: 596 Type: R Area: 5,050.00SqFt PCI = 96

Sample Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: RUNWAY 9L-27R Use: RUNWAY RW 9L-27R Area: 750,300.00SqFt

To: -Section: 6131 of 6 From: -Last Const.: 1/1/1997

100.00Ft

Surface: Family: DEFAULT Zone: Category: Rank: P AC

Area: 20,200.00SqFt Length: 202.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:90.00 | Inspection Comments:

Sample Number: 396 Type: R Area: 5,000.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 74.02 Ft L Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

100.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 900,150.00SqFt

Section: 6302 of 8 From: - To: - Last Const.: 1/1/2012

Surface: AC Family: FDOT-RL-RW-AC Zone: Category: Rank: P

Area: 100,000.00SqFt Length: 1,000.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date1/1/2012 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00

<NO SAMPLE RECORDS>

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 900,150.00SqFt

Section: 6304 of 8 From: - To: - Last Const.: 1/1/2012

100.00Ft

Surface: AAC Family: FDOT-RL-RW-AAC Zone: Category: Rank: P

Area: 20,000.00SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

NOTE: *** Pre-Construction PCI ***

Last Insp. Date9/17/2007 Total Samples: 4 Surveyed: 1

Conditions: PCI:82.00 | Inspection Comments:

Sample Number: 301 Type: R Area: 5,000.00SqFt PCI = 82

Sample Comments:

50 PATCHING L 0.40 SqFt Comments: 52 WEATH/RAVEL L 900.00 SqFt Comments: 48 L & T CR L 9.50 Ft Comments:

FDOT COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Name: RUNWAY 9R-27L Branch: Use: RUNWAY 900,150.00SqFt RW 9R-27L Area: 8 To: -Last Const.: 1/1/1997 Section: 6305 of From: -Family: DEFAULT Zone: Category: Rank: P Surface: AAC Area: 460,000.00SqFt Length: 4,600.00Ft Width: 100.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Total Samples: 92 Surveyed: 19 Last Insp. Date3/26/2012 Conditions: PCI:88.00 | Inspection Comments: PCI = 76Sample Number: 325 Type: R Area: 5,000.00SqFt Sample Comments: 50 PATCHING 1,524.99 SqFt L Comments: Sample Number: 330 Type: R Area: 5,000.00SqFt PCI = 78Sample Comments: 52 WEATHERING/RAVELING Μ 56.00 SqFt Comments: 52 WEATHERING/RAVELING Μ 196.00 SqFt Comments: 52 WEATHERING/RAVELING 100.00 SqFt Comments: L 48 LONGITUDINAL/TRANSVERSE CRACKING 1.00 Ft Τ, Comments: Sample Number: 336 Area: 5,000.00SqFt PCI = 86Type: R Sample Comments: 52 WEATHERING/RAVELING Μ 20.00 SqFt Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING Comments: Τ, 43.01 Ft Sample Number: 342 Area: 5,000.00SqFt PCI = 58Type: R Sample Comments: 52 WEATHERING/RAVELING Μ 1,359.99 SqFt Comments: 80.00 SaFt 52 WEATHERING/RAVELING Μ Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING Ь 54.01 Ft Comments: 100.00 SqFt 52 WEATHERING/RAVELING L Comments: Sample Number: 348 Area: 5,000.00SqFt PCI = 84Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 68.02 Ft Comments: 52 WEATHERING/RAVELING М 33.00 SqFt Comments: 52 WEATHERING/RAVELING Τ, 100.00 SqFt Comments: Sample Number: 352 Area: 5,000.00SqFt PCI = 91Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 43.01 Ft Comments: 52 WEATHERING/RAVELING 100.00 SqFt Comments: L Sample Number: 356 5,000.00SqFt PCI = 80Type: R Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 54.01 Ft Comments: L 52 WEATHERING/RAVELING Μ 115.50 SqFt Comments: 52 WEATHERING/RAVELING 100.00 SqFt Comments: L PCI = 96Sample Number: 362 Area: 5,000.00SqFt Type: R Sample Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

| Sample Number: 365 Type: R | Area: | | 5,000.00SqFt | PCI = 83 |
|---|---------|--------|----------------------|-----------------|
| Sample Comments: | Alca. | | 3,000.003qFt | 101 – 63 |
| 52 WEATHERING/RAVELING | | M | 187.00 Sq | |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: |
| Sample Number: 370 Type: R | Area: | | 5,000.00SqFt | PCI = 96 |
| Sample Comments: | | | | |
| 52 WEATHERING/RAVELING | | L | 18.00 Sq | |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: |
| Sample Number: 377 Type: R | Area: | | 5,000.00SqFt | PCI = 96 |
| Sample Comments: | | | | _ |
| 52 WEATHERING/RAVELING | | L | 120.00 Sq | Ft Comments: |
| Sample Number: 384 Type: R | Area: | | 5,000.00SqFt | PCI = 94 |
| Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRAC | 'K TNG | L | 5.00 Ft | Comments: |
| 52 WEATHERING/RAVELING | .1.110 | L | 100.00 Sq | |
| 52 HILLING, IGIVEDING | | | 100.00 54 | . C Commerces . |
| Sample Number: 391 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 94 |
| 48 LONGITUDINAL/TRANSVERSE CRAC | KING | L | 2.00 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: |
| Sample Number: 395 Type: R | Area: | | 5,000.00SqFt | PCI = 96 |
| Sample Comments: 52 WEATHERING/RAVELING | | L | 100.00 Sq | Ft Comments: |
| 32 WHITEKING/IGIVELING | | | 100.00 54 | Commerce . |
| Sample Number: 398 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 92 |
| 48 LONGITUDINAL/TRANSVERSE CRAC | KING | L | 3.00 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 150.00 Sq | Ft Comments: |
| Sample Number: 403 Type: R | Area: | | 5,000.00SqFt | PCI = 94 |
| Sample Comments: | 'K TNC | т | 1.00 Ft | Commont g: |
| 48 LONGITUDINAL/TRANSVERSE CRAC 52 WEATHERING/RAVELING | VING | L L | 1.00 Ft 80.00 Sq | Comments: |
| OZ WEATHERING/KAVELING | | ш | 60.00 SQ | ft Comments: |
| Sample Number: 407 Type: R Sample Comments: | Area: | | 5,000.00SqFt | PCI = 93 |
| 48 LONGITUDINAL/TRANSVERSE CRAC | KING | L | 6.00 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 100.00 Sq | |
| Sample Number: 412 Type: R | Area: | | 5,000.00SqFt | PCI = 94 |
| Sample Comments: | TZ TNO | т. | 04 01 = = | Commonta |
| 48 LONGITUDINAL/TRANSVERSE CRAC | V TING | L | 24.01 Ft | Comments: |
| 52 WEATHERING/RAVELING | | L | 20.00 Sq | Ft Comments: |
| Sample Number: 415 Type: R | Area: | | 5,000.00SqFt | PCI = 96 |
| Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRAC | KING | L | 2.00 Ft | Comments: |
| 52 WEATHERING/RAVELING | .11.110 | L | 9.00 FC | |
| 52 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | | 2.00 DQ | Commercial . |

100.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 900,150.00SqFt

Section: 6306 of 8 From: - To: - Last Const.: 1/1/1997

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 20,100.00SqFt Length: 201.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:100.00 | Inspection Comments:

Sample Number: 418 Type: R Area: 5,000.00SqFt PCI = 100

Sample Comments:

<NO DISTRESSES>

25.00Ft

Last Const.: 1/1/2012

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 900,150.00SqFt

Section: 6307 of 8 From: - To: -

Surface: AC Family: FDOT-RL-RW-AC Zone: Category: Rank: P

Area: 50,000.00SqFt Length: 2,000.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date1/1/2012 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00

<NO SAMPLE RECORDS>

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 900,150.00SqFt

Section: 6309 of 8 From: - To: - Last Const.: 1/1/2012

25.00Ft

Surface: AAC Family: FDOT-RL-RW-AAC Zone: Category: Rank: P

Area: 10,000.00SqFt Length: 400.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

NOTE: *** Pre-Construction PCI ***

Last Insp. Date9/17/2007 Total Samples: 4 Surveyed: 1

Conditions: PCI:88.00 | Inspection Comments:

Sample Number: 500 Type: R Area: 5,000.00SqFt PCI = 88

Sample Comments:

Section Comments:

52 WEATH/RAVEL L 750.00 SqFt Comments:

FDOT COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 900,150.00SqFt Section: 8 From: -To: -Last Const.: 1/1/1997 6310 of Surface: Family: DEFAULT Zone: Category: Rank: P AAC Area: 230,000.00SqFt Length: 9,200.00Ft Width: 25.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date3/26/2012 Total Samples: 46 Surveyed: 8 Conditions: PCI:86.00 | Inspection Comments: 5,000.00SqFt PCI = 73Sample Number: 128 Type: R Area: Sample Comments: 52 WEATHERING/RAVELING 546.00 SaFt Comments: Μ 52 WEATHERING/RAVELING 100.00 SqFt Comments: L 70.00 SqFt 52 WEATHERING/RAVELING Μ Comments: Sample Number: 152 PCI = 96Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: Sample Number: 176 Type: R Area: 5,000.00SqFt PCI = 94Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 3.00 Ft L Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: Sample Number: 204 Type: R Area: 5,000.00SqFt PCI = 87Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 135.03 Ft Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 528 Type: R Area: 5,000.00SqFt PCI = 75Sample Comments: 52 WEATHERING/RAVELING 546.00 SqFt Comments: Μ 50.00 SqFt 52 WEATHERING/RAVELING L Comments: 70.00 SqFt 52 WEATHERING/RAVELING Μ Comments: PCI = 78Sample Number: 544 Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING Μ 220.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 10.00 Ft L Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: PCI = 91Sample Number: 568 Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 2.00 Ft Comments: 52 WEATHERING/RAVELING 200.00 SqFt L Comments: Sample Number: 596 Type: R Area: 5,000.00SqFt PCI = 91Sample Comments: 49 OIL SPILLAGE Ν 4.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING Τ, 29.01 Ft Comments: 45.00 SqFt 52 WEATHERING/RAVELING L Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 900,150.00SqFt

Section: 6311 of 8 From: - To: - Last Const.: 1/1/1997

25.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 10,050.00SqFt Length: 402.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Shoulder: Street Type: Section Comments:

Last Insp. Date3/26/2012 Total Samples: 2 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 216 Type: R Area: 5,025.00SqFt PCI = 91

Sample Comments:

52 WEATHERING/RAVELING L 168.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 12.00 Ft Comments:

50.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW 1 Name: TAXIWAY 1 Use: TAXIWAY Area: 12,842.70SqFt

Section: 270 of 1 From: - To: - Last Const.: 1/1/2006

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 12,842.70SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 2 Surveyed: 1

Conditions: PCI:94.00 | Inspection Comments:

Sample Number: 700 Type: R Area: 5,086.41 SqFt PCI = 94

Sample Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 4.00 Ft Comments:

90.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW 2 Name: TAXIWAY 2 Use: TAXIWAY Area: 19,697.18SqFt

Section: 260 of 1 From: - To: - Last Const.: 1/1/2006

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 19,697.18SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 602 Type: R Area: 4,761.37SqFt PCI = 91

Sample Comments:

52 WEATHERING/RAVELING M 10.00 SqFt Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments:

90.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW 3 Name: TAXIWAY 3 Use: TAXIWAY Area: 19,697.18SqFt

Section: 250 of 1 From: - To: - Last Const.: 1/1/2006

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 19,697.18SqFt Length: 200.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:96.00 | Inspection Comments:

Sample Number: 502 Type: R Area: 4,761.37SqFt PCI = 96

Sample Comments:

52 WEATHERING/RAVELING L 75.00 SqFt Comments: 52 WEATHERING/RAVELING L 12.00 SqFt Comments:

90.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW 4 Name: TAXIWAY 4 Use: TAXIWAY Area: 19,697.18SqFt

Section: 240 of 1 From: - To: - Last Const.: 1/1/2006

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 19,697.18SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:94.00 | Inspection Comments:

Sample Number: 400 Type: R Area: 6,829.26SqFt PCI = 94

Sample Comments:

52 WEATHERING/RAVELING L 300.00 Sqft Comments:

90.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW 5 Name: TAXIWAY 5 Use: TAXIWAY Area: 19,697.18SqFt

Section: 230 of 1 From: - To: - Last Const.: 1/1/2006

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 19,697.18SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:89.00 | Inspection Comments:

Sample Number: 302 Type: R Area: 4,761.37SqFt PCI = 89

Sample Comments:

52 WEATHERING/RAVELING L 624.99 SqFt Comments:

90.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW 6 Name: TAXIWAY 6 Use: TAXIWAY Area: 19,696.66SqFt

Section: 220 of 1 From: - To: - Last Const.: 1/1/2006

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 19,696.66SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 200 Type: R Area: 6,828.74SqFt PCI = 91

Sample Comments:

52 WEATHERING/RAVELING L 624.99 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW 7 Name: TAXIWAY 7 Use: TAXIWAY Area: 18,557.11SqFt

Section: 210 of 1 From: - To: - Last Const.: 1/1/2005

90.00Ft

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 18,557.11SqFt Length: 200.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:92.00 | Inspection Comments:

Sample Number: 102 Type: R Area: 4,255.69SqFt PCI = 92

Sample Comments:

52 WEATHERING/RAVELING L 300.00 SqFt Comments:

FDOT COMB

Report Generated Date: 3/29/2012

52 WEATHERING/RAVELING

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 361,647.06SqFt Section: 4 From: -To: -Last Const.: 1/1/2005 105 of Surface: Family: DEFAULT Zone: Category: Rank: P AAC Area: 279,575.51SqFt Length: 5,500.00Ft Width: 50.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date3/26/2012 Total Samples: 56 Surveyed: 10 Conditions: PCI:94.00 | Inspection Comments: PCI = 92Sample Number: 105 Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 60.02 Ft Comments: L 52 WEATHERING/RAVELING 25.00 SqFt Comments: L 52 WEATHERING/RAVELING L 12.00 SqFt Comments: PCI = 89Sample Number: 113 Type: R Area: 5,000.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 69.02 Ft Comments: 52 WEATHERING/RAVELING L 150.00 SqFt Comments: Sample Number: 121 Area: 5,000.00SqFt PCI = 89Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 57.01 Ft Comments: 52 WEATHERING/RAVELING L 200.00 SqFt Comments: Sample Number: 129 Area: 5,000.00SqFt PCI = 92Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 32.01 Ft Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: Sample Number: 133 Type: R Area: 5,000.00SqFt PCI = 100Sample Comments: <NO DISTRESSES> PCI = 100Sample Number: 137 Type: R Area: 5,000.00SqFt Sample Comments: <NO DISTRESSES> PCI = 95Sample Number: 145 Type: R Area: 6,500.00SqFt Sample Comments: 52 WEATHERING/RAVELING $_{\rm L}$ 27.00 SqFt Comments: 3.00 Ft 48 LONGITUDINAL/TRANSVERSE CRACKING L Comments: 52 WEATHERING/RAVELING L 20.00 SqFt Comments: Sample Number: 150 5,000.00SqFt PCI = 94Type: R Area: Sample Comments: 52 WEATHERING/RAVELING $_{\rm L}$ 168.00 SqFt Comments: 52 WEATHERING/RAVELING 29.00 SqFt L Comments: PCI = 96Sample Number: 154 Type: R Area: 5,000.00SqFt Sample Comments:

100.00 SqFt

L

Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

PCI = 95 Sample Number: 158 Type: R 5,000.00SqFt Area:

Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING 2.00 Ft L Comments:

52 WEATHERING/RAVELING L 32.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 361,647.06SqFt

Section: 108 of 4 From: - To: - Last Const.: 1/1/2005

50.00Ft

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 18,500.00SqFt Length: 370.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:79.00 | Inspection Comments:

Sample Number: 148 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 39.01 Ft Comments: 52 WEATHERING/RAVELING L 1,499.99 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 361,647.06SqFt

Section: 110 of 4 From: - To: - Last Const.: 1/1/1965

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 36,179.51SqFt Length: 360.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 7 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 105 Type: R Area: 5,000.00SqFt PCI = 91

Sample Comments:

52 WEATHERING/RAVELING M 14.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 16.00 Ft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: TAXIWAY A Use: TAXIWAY TW A Area: 361,647.06SqFt

To: -Section: 111 of 4 From: -Last Const.: 12/25/199

75.00Ft

Surface: Family: DEFAULT Zone: Category: Rank: P AC

Area: 27,392.04SqFt Length: 300.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 6 Surveyed: 1

Conditions: PCI:100.00 | Inspection Comments:

Sample Number: 103 Type: R Area: 3,850.00SqFt PCI = 100

Sample Comments:

<NO DISTRESSES>

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW A1 Name: TAXIWAY A1 Use: TAXIWAY Area: 50,474.98SqFt

Section: 115 of 1 From: - To: - Last Const.: 1/1/1965

75.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 50,474.98SqFt Length: 300.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 14 Surveyed: 2

Conditions: PCI:97.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 5,000.00SqFt PCI = 95

Sample Comments:

52 WEATHERING/RAVELING L 150.00 SqFt Comments:

Sample Number: 103 Type: R Area: 3,833.84SqFt PCI = 100

Sample Comments:

<NO DISTRESSES>

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW A2 Name: TAXIWAY A2 Use: TAXIWAY Area: 50,474.98SqFt

Section: 120 of 1 From: - To: - Last Const.: 1/1/1965

75.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 50,474.98SqFt Length: 300.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 14 Surveyed: 2

Conditions: PCI:95.00 | Inspection Comments:

Sample Number: 201 Type: R Area: 5,000.00SqFt PCI = 96

Sample Comments:

52 WEATHERING/RAVELING L 110.00 SqFt Comments:

Sample Number: 203 Type: R Area: 3,833.84SqFt PCI = 94

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 2.00 Ft Comments: 52 WEATHERING/RAVELING L 50.00 Sqft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW A3 Name: TAXIWAY A3 Use: TAXIWAY Area: 58,938.06SqFt

Section: 124 of 2 From: - To: - Last Const.: 12/25/199

75.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 26,792.04SqFt Length: 300.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 6 Surveyed: 1

Conditions: PCI:92.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 3,966.94SqFt PCI = 92

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 7.00 Ft Comments: 52 WEATHERING/RAVELING L 120.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW A3 Name: TAXIWAY A3 Use: TAXIWAY Area: 58,938.06SqFt

Section: 125 of 2 From: - To: - Last Const.: 1/1/1965

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 32,146.02SqFt Length: 320.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 6 Surveyed: 2

Conditions: PCI:93.00 | Inspection Comments:

Sample Number: 302 Type: R Area: 5,000.00SqFt PCI = 96

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 4.00 Ft Comments:

52 WEATHERING/RAVELING L 10.00 SqFt Comments:

Sample Number: 304 Type: R Area: 5,216.94SqFt PCI = 90

Sample Comments:

50 PATCHING L 98.00 SqFt Comments: 49 OIL SPILLAGE N 2.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 2.00 Ft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Use: TAXIWAY TW AP NE Name: TAXIWAY TO NE APRON Area: 44,690.90SqFt

Section: 1005 of 1 From: -To: -Last Const.: 12/25/199

35.00Ft

Family: DEFAULT Zone: Rank: P Surface: ACCategory:

Area: 44,690.90SqFt Length: 1,200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 13 Surveyed: 2

Conditions: PCI:78.00 | Inspection Comments:

Sample Number: 503 Type: R Area: 3,500.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 89.02 Ft L Comments: 52 WEATHERING/RAVELING L 1,399.99 SqFt Comments:

56 SWELLING 36.00 SqFt Comments: L

Sample Number: 509 Type: R PCI = 82Area: 3,500.00SqFt

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 144.04 Ft L Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: TAXIWAY TO SE APRON Use: TAXIWAY TW AP SE Area: 42,726.72SqFt

To: -Section: 1105 of 1 From: -Last Const.: 12/25/199

30.00Ft

Surface: Family: DEFAULT Zone: Category: Rank: P AC

Area: 42,726.72SqFt Length: 1,400.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 10 Surveyed: 1

Conditions: PCI:89.00 | Inspection Comments:

Sample Number: 104 Type: R Area: 5,307.37SqFt PCI = 89

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 108.03 Ft L Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Use: TAXIWAY Branch: TW C Name: TAXIWAY C Area: 138,068.51SqFt

Section: 910 of 1 From: -To: -Last Const.: 1/1/1998

50.00Ft

Family: DEFAULT Zone: Surface: Category: Rank: P AC

Area: 138,068.51SqFt Length: 2,600.00Ft Width:

Type: R

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 27 Surveyed: 3

Conditions: PCI:86.00 | Inspection Comments:

| Sample Number: | 103 | Type: R | Area: | 5,000.00SqFt | PCI = 88 |
|------------------|-----|---------|-------|--------------|----------|
| Sample Comments: | | | | | |

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 84.02 Ft Comments: 56 SWELLING L 12.00 SqFt Comments:

100.00 SqFt 52 WEATHERING/RAVELING L Comments:

Sample Number: 109 PCI = 78Type: R Area: 5,000.00SqFt

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 212.05 Ft Comments: 43 BLOCK CRACKING L 40.00 SqFt Comments: 100.00 SqFt 52 WEATHERING/RAVELING L Comments:

PCI = 91

Sample Number: 118 Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 41.01 Ft Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments:

Area:

5,000.00SqFt

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW C1 Name: TAXIWAY C1 Use: TAXIWAY Area: 17,643.88SqFt

Section: 310 of 1 From: - To: - Last Const.: 1/1/1997

90.00Ft

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 17,643.88SqFt Length: 190.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 5 Surveyed: 1

Conditions: PCI:72.00 | Inspection Comments:

Sample Number: 103 Type: R Area: 3,213.74SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 183.05 Ft L Comments: 56 SWELLING L 18.00 SqFt Comments: 52 WEATHERING/RAVELING 321.00 SqFt Comments: L 52 WEATHERING/RAVELING 12.00 SqFt Μ Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: TAXIWAY C2 Use: TAXIWAY TW C2 Area: 17,567.42SqFt

Section: 320 of 1 From: -To: -Last Const.: 1/1/1997

90.00Ft

Family: DEFAULT Zone: Category: Rank: P Surface: AAC

Area: 17,567.42SqFt Length: 190.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 5 Surveyed: 1

Conditions: PCI:78.00 | Inspection Comments:

Sample Number: 203 Type: R Area: 3,555.89SqFt PCI = 78Sample Comments:

171.04 Ft 48 LONGITUDINAL/TRANSVERSE CRACKING L Comments: 56 SWELLING L 11.00 SqFt Comments:

52 WEATHERING/RAVELING 355.00 SqFt Comments: L

56 SWELLING 22.00 SqFt L Comments:

50.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW CC Name: TAXIWAY CC Use: TAXIWAY Area: 7,838.05SqFt

Section: 905 of 1 From: - To: - Last Const.: 1/1/1998

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 7,838.05SqFt Length: 125.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 2 Surveyed: 1

Conditions: PCI:78.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 3,036.50SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 26.01 Ft Comments: 52 WEATHERING/RAVELING L 455.00 SqFt Comments:

50 PATCHING L 65.00 SqFt Comments:

FDOT_COMB

Sample Number: 133

52 WEATHERING/RAVELING

Sample Comments:

50 PATCHING

Type: R

48 LONGITUDINAL/TRANSVERSE CRACKING

Report Generated Date: 3/29/2012

Site Name:

| Site Name. | | | | | |
|--|-----------|---------------|--------------|----------|-----------------------|
| Network: TMB Name: KENDALL-TAMIAMI E | XECUTIVE | AIRPO | RT | | |
| Branch: TW D Name: TAXIWAY D | | | Use: TAXIWA | Y Area: | 284,135.64SqFt |
| Section: 405 of 4 From: - Surface: AC Family: DEFAULT Area: 210,897.78SqFt Length: 4,200.00Ft Shoulder: Street Type: Grade: 0.00 Section Comments: | Lanes: | Zone: Widt | 6 - 3 - | Rank: P | Last Const.: 1/1/1965 |
| Last Insp. Date3/26/2012 Total Samples: 43 Sur Conditions: PCI:47.00 Inspection Comments: | rveyed: 5 | i | | | |
| Sample Number: 103 Type: R | Area: | 5 | 5,000.00SqFt | PCI = 33 | |
| Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 48.01 Ft | Commen | tg: |
| 50 PATCHING | | M | 4.00 SqF | | |
| 52 WEATHERING/RAVELING | | M | 4,999.96 SqF | | |
| Sample Number: 108 Type: R Sample Comments: | Area: | 5 | 5,000.00SqFt | PCI = 33 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 88.02 Ft | Commen | ts: |
| 50 PATCHING | | M | 1.00 SqF | | ts: |
| 52 WEATHERING/RAVELING | | M | 4,999.96 SqF | commen. | ts: |
| Sample Number: 116 Type: R Sample Comments: | Area: | 5 | 5,000.00SqFt | PCI = 38 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 231.06 Ft | Commen | ts: |
| 52 WEATHERING/RAVELING | | M | 4,999.96 SqF | t Commen | ts: |
| Sample Number: 127 Type: R Sample Comments: | Area: | 5 | 5,000.00SqFt | PCI = 69 | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | | L | 291.07 Ft | Commen | ts: |
| 52 WEATHERING/RAVELING | | L | 4,999.96 SqF | commen. | ts: |
| | | | | | |

Area:

L

M

5,000.00SqFt

293.08 Ft

4,999.96 SqFt

1.00 SqFt

PCI = 64

Comments:

Comments:

Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 284,135.64SqFt

Section: 410 of 4 From: - To: - Last Const.: 1/1/1965

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 36,141.84SqFt Length: 361.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 7 Surveyed: 1

Conditions: PCI:94.00 | Inspection Comments:

Sample Number: 108 Type: R Area: 5,000.00SqFt PCI = 94

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 18.00 Ft Comments: 52 WEATHERING/RAVELING L 40.00 Sqft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 284,135.64SqFt

Section: 411 of 4 From: - To: - Last Const.: 12/25/199

75.00Ft

100.00 SqFt

Comments:

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 27,092.04SqFt Length: 300.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 6 Surveyed: 1

Conditions: PCI:88.00 | Inspection Comments:

52 WEATHERING/RAVELING

| Sample Number: 103 Sample Comments: | Type: R | Area: | 3,800.00SqFt | PCI = 88 |
|-------------------------------------|-----------------|-------|--------------|-----------|
| r | NO. | - | 00 00 0 | C = |
| 52 WEATHERING/RAVELI | .NG | Ц | 88.00 SqFt | Comments: |
| 48 LONGITUDINAL/TRAN | SVERSE CRACKING | L | 52.01 Ft | Comments: |
| 52 WEATHERING/RAVELI | NG | L | 12.00 SqFt | Comments: |

L

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 284,135.64SqFt

Section: 412 of 4 From: - To: - Last Const.: 12/25/199

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 10,003.98SqFt Length: 100.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 2 Surveyed: 1

Conditions: PCI:94.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 5,025.07SqFt PCI = 94

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 3.00 Ft Comments: 52 WEATHERING/RAVELING L 100.00 Sqft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW D1 Name: TAXIWAY D1 Use: TAXIWAY Area: 50,474.98SqFt

Section: 415 of 1 From: - To: - Last Const.: 1/1/1965

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 50,474.98SqFt Length: 500.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 14 Surveyed: 2

Conditions: PCI:56.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 3,750.00SqFt PCI = 55

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 327.08 Ft Comments: 52 WEATHERING/RAVELING M 937.99 Sqft Comments:

52 WEATHERING/RAVELING L 1,874.98 SqFt Comments:

Sample Number: 103 Type: R Area: 3,833.84SqFt PCI = 58

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 177.05 Ft Comments: 52 WEATHERING/RAVELING M 957.99 SqFt Comments:

52 WEATHERING/RAVELING L 2,874.98 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW D2 Name: TAXIWAY D2 Use: TAXIWAY Area: 50,462.90SqFt

Section: 420 of 1 From: - To: - Last Const.: 1/1/1965

75.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 50,462.90SqFt Length: 300.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 14 Surveyed: 2

Conditions: PCI:53.00 | Inspection Comments:

Sample Number: 203 Type: R Area: 3,833.84SqFt PCI = 56

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 156.04 Ft Comments: 52 WEATHERING/RAVELING L 2,682.98 SqFt Comments:

52 WEATHERING/RAVELING M 1,148.99 SqFt Comments:

Sample Number: 205 Type: R Area: 3,750.00SqFt PCI = 49

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 314.08 Ft Comments: 52 WEATHERING/RAVELING M 1,499.99 SqFt Comments:

52 WEATHERING/RAVELING L 2,249.98 SqFt Comments:

50.00Ft

Last Const.: 1/1/2012

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TWE Name: TAXIWAY E Use: TAXIWAY Area: 411,789.40SqFt

Section: 503 of 5 From: - To: -

Surface: AC Family: FDOT-RL-TW-AC Zone: Category: Rank: P

Area: 56,118.63SqFt Length: 1,120.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date1/1/2012 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00

<NO SAMPLE RECORDS>

FDOT COMB

Report Generated Date: 3/29/2012

52 WEATHERING/RAVELING

52 WEATHERING/RAVELING

52 WEATHERING/RAVELING

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT Use: TAXIWAY Branch: TW E Name: TAXIWAY E Area: 411,789.40SqFt Section: 505 of 5 From: -To: -Last Const.: 1/1/2007 Zone: Surface: Family: DEFAULT Category: Rank: P AAC Area: 238,386.04SqFt Length: 4,700.00Ft Width: 50.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date3/26/2012 Total Samples: 47 Surveyed: 5 Conditions: PCI:95.00 | Inspection Comments: Sample Number: 120 Type: R PCI = 100Area: 5,000.00SqFt Sample Comments: <NO DISTRESSES> Sample Number: 124 Type: R Area: 5,000.00SqFt PCI = 98Sample Comments: 52 WEATHERING/RAVELING 36.00 SqFt L Comments: Sample Number: 144 Type: R Area: PCI = 965,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING 100.00 SqFt $_{\rm L}$ Comments: Sample Number: 155 Type: R 5,000.00SqFt PCI = 95Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 17.00 Ft Comments: 52 WEATHERING/RAVELING L 9.00 SqFt Comments: PCI = 87Sample Number: 159 Type: R Area: 5,000.00SqFt Sample Comments:

L

L

M

148.00 SqFt

200.00 SqFt

10.00 SqFt

Comments:

Comments:

Comments:

150.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: TAXIWAY E Use: TAXIWAY TW E Area: 411,789.40SqFt

To: -Section: 507 of 5 From: -Last Const.: 1/1/2007

Family: DEFAULT Zone: Category: Rank: P Surface: AAC

Area: 30,930.07SqFt Length: 200.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 7 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 224 Type: R Area: 5,000.00SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 47.01 Ft L Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Area:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: TAXIWAY E Use: TAXIWAY TW E Area: 411,789.40SqFt

5 To: -Section: 510 of From: -Last Const.: 1/1/2007

Width:

50.00Ft

Surface: Family: DEFAULT Zone: Category: Rank: P AAC 600.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Length:

Section Comments:

Last Insp. Date3/26/2012

32,263.02SqFt

Surveyed: 1 Total Samples: 7

Conditions: PCI:95.00 | Inspection Comments:

Sample Number: 163 Type: R Area: 5,000.00SqFt PCI = 95

Sample Comments:

52 WEATHERING/RAVELING 125.00 SqFt L Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TWE Name: TAXIWAY E Use: TAXIWAY Area: 411,789.40SqFt

Section: 513 of 5 From: - To: - Last Const.: 1/1/2012

170.00Ft

Surface: AC Family: FDOT-RL-TW-AC Zone: Category: Rank: P

Area: 54,091.64SqFt Length: 300.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date1/1/2012 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00

<NO SAMPLE RECORDS>

100.00Ft

Last Const.: 1/1/2012

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW E1 Name: TAXIWAY E1 Use: TAXIWAY Area: 59,884.07SqFt

Section: 515 of 2 From: - To: -

Surface: AAC Family: FDOT-RL-TW-AAC Zone: Category: Rank: P

Area: 21,049.02SqFt Length: 210.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date1/1/2012 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00

<NO SAMPLE RECORDS>

100.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW E1 Name: TAXIWAY E1 Use: TAXIWAY Area: 59,884.07SqFt

Section: 516 of 2 From: - To: - Last Const.: 12/25/199

Surface: AC Family: FDOT-RL-TW-AC Zone: Category: Rank: P

Area: 38,835.05SqFt Length: 388.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 8 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 303 Type: R Area: 4,895.72SqFt PCI = 91

Sample Comments:

52 WEATHERING/RAVELING L 204.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 3.00 Ft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW E2 Name: TAXIWAY E2 Use: TAXIWAY Area: 50,474.48SqFt

Section: 520 of 1 From: - To: - Last Const.: 1/1/2007

75.00Ft

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 50,474.48SqFt Length: 300.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 14 Surveyed: 3

Conditions: PCI:83.00 | Inspection Comments:

Sample Number: 196 Type: R Area: 4,835.84SqFt PCI = 85

Sample Comments:

52 WEATHERING/RAVELING L 1,207.99 SqFt Comments:

Sample Number: 203 Type: R Area: 3,833.84SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 13.00 Ft Comments: 52 WEATHERING/RAVELING L 957.99 Sqft Comments:

Sample Number: 205 Type: R Area: 5,000.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 8.00 Ft Comments:

52 WEATHERING/RAVELING L 1,249.99 SqFt Comments:

FDOT COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Use: TAXIWAY Branch: TW E3 Name: TAXIWAY E3 Area: 41,823.46SqFt

Section: of 1 From: -To: -Last Const.: 1/1/2007 525

75.00Ft

Family: DEFAULT Zone: Surface: Category: Rank: P AAC

Area: 41,823.46SqFt Length: 300.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 11 Surveyed: 3

Conditions: PCI:83.00 | Inspection Comments:

Sample Number: 298 Type: R Area: 3,750.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 216.06 Ft Comments: 52 WEATHERING/RAVELING L 1,874.98 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 60.02 Ft L Comments:

Sample Number: 301 PCI = 86Type: R Area: 3,750.00SqFt

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 38.01 Ft Comments:

52 WEATHERING/RAVELING L 300.00 SqFt Comments:

Sample Number: 303 Type: R Area: 3,848.21SqFt PCI = 87

Sample Comments:

52 WEATHERING/RAVELING L 300.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 33.01 Ft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW E4 Name: TAXIWAY E4 Use: TAXIWAY Area: 26,266.60SqFt

To: -Section: 527 of 1 From: -Last Const.: 1/1/1996

50.00Ft

Surface: Family: DEFAULT Zone: Category: Rank: P AC

Area: 26,266.60SqFt Length: 300.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 7 Surveyed: 1

Conditions: PCI:87.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 5,000.00SqFt PCI = 87

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 42.01 Ft L Comments:

52 WEATHERING/RAVELING L 400.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW E5 Name: TAXIWAY E5 Use: TAXIWAY Area: 58,338.06SqFt

Section: 529 of 2 From: - To: - Last Const.: 12/25/199

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 26,192.04SqFt Length: 300.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 6 Surveyed: 1

Conditions: PCI:93.00 | Inspection Comments:

Sample Number: 100 Type: R Area: 5,579.08SqFt PCI = 93

Sample Comments:

10.00 SqFt 52 WEATHERING/RAVELING L Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 3.00 Ft Comments: L 45 DEPRESSION 4.00 SqFt L Comments:

90.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW E5 Name: TAXIWAY E5 Use: TAXIWAY Area: 58,338.06SqFt

Section: 530 of 2 From: - To: - Last Const.: 1/1/1999

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 32,146.02SqFt Length: 300.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 6 Surveyed: 2

Conditions: PCI:92.00 | Inspection Comments:

Sample Number: 402 Type: R Area: 5,000.00SqFt PCI = 92

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 27.01 Ft Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

Sample Number: 404 Type: R Area: 5,216.94SqFt PCI = 93

Sample Comments: 52 WEATHERING/RAVELING

52 WEATHERING/RAVELING L 136.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 4.00 Ft Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TWF Name: TAXIWAY F Use: TAXIWAY Area: 57,730.09SqFt

Section: 605 of 1 From: - To: - Last Const.: 1/1/1998

50.00Ft

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 57,730.09SqFt Length: 1,050.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 12 Surveyed: 3

Conditions: PCI:93.00 | Inspection Comments:

Sample Number: 100 Type: R Area: 4,422.75SqFt PCI = 85

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 144.04 Ft Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

Sample Number: 104 Type: R Area: 5,000.00SqFt PCI = 97

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 12.00 Ft Comments:

Sample Number: 108 Type: R Area: 5,000.00SqFt PCI = 96

Sample Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

50.00Ft

Last Const.: 1/1/2006

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW G Name: TAXIWAY G Use: TAXIWAY Area: 68,727.78SqFt

Section: 705 of 2 From: - To: -

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 51,621.67SqFt Length: 1,000.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 10 Surveyed: 2

Conditions: PCI:96.00 | Inspection Comments:

Sample Number: 205 Type: R Area: 5,000.00SqFt PCI = 95

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 39.01 Ft Comments:

Sample Number: 209 Type: R Area: 5,000.00SqFt PCI = 98

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 1.00 Ft Comments:

50.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW G Name: TAXIWAY G Use: TAXIWAY Area: 68,727.78SqFt

Section: 710 of 2 From: - To: - Last Const.: 1/1/1997

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 17,106.11SqFt Length: 340.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 3 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 201 Type: R Area: 7,000.00SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 87.02 Ft Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW H Name: TAXIWAY H Use: TAXIWAY Area: 119,041.80SqFt

Section: 815 of 1 From: - To: - Last Const.: 1/1/2007

50.00Ft

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 119,041.80SqFt Length: 2,200.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 25 Surveyed: 3

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 103 Type: R Area: 5,000.00SqFt PCI = 96

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 15.00 Ft Comments:

Sample Number: 111 Type: R Area: 6,191.84SqFt PCI = 86

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 31.01 Ft Comments:

52 WEATHERING/RAVELING L 649.99 SqFt Comments:

Sample Number: 120 Type: R Area: 5,000.00SqFt PCI = 94

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 3.00 Ft Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW H1 Name: TAXIWAY H1 Use: TAXIWAY Area: 4,801.55SqFt

Section: 805 of 1 From: - To: - Last Const.: 1/1/1998

50.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 4,801.55SqFt Length: 90.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 1 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 100 Type: R Area: 4,801.55SqFt PCI = 91

Sample Comments:

52 WEATHERING/RAVELING L 20.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 60.02 Ft Comments: 52 WEATHERING/RAVELING L 50.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW H2 Name: TAXIWAY H2 Use: TAXIWAY Area: 7,744.33SqFt

Section: 810 of 1 From: - To: - Last Const.: 1/1/1998

100.00Ft

Surface: AC Family: DEFAULT Zone: Category: Rank: P

Area: 7,744.33SqFt Length: 75.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 2 Surveyed: 1

Conditions: PCI:85.00 | Inspection Comments:

Sample Number: 101 Type: R Area: 3,537.07SqFt PCI = 85

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 89.02 Ft Comments: 52 WEATHERING/RAVELING L 200.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 20.01 Ft Comments:

90.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW H3 Name: TAXIWAY H3 Use: TAXIWAY Area: 18,456.28SqFt

Section: 330 of 1 From: - To: - Last Const.: 1/1/2007

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 18,456.28SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Shoulder: Street Type: Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:88.00 | Inspection Comments:

Sample Number: 300 Type: R Area: 5,688.91SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 128.03 Ft Comments: 52 WEATHERING/RAVELING L 100.00 Sqft Comments:

90.00Ft

Last Const.: 1/1/2007

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW H4 Name: TAXIWAY H4 Use: TAXIWAY Area: 17,255.03SqFt

Section: 340 of 1 From: - To: -

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 17,255.03SqFt Length: 190.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:100.00 | Inspection Comments:

Sample Number: 402 Type: R Area: 3,295.40SqFt PCI = 100

Sample Comments:

<NO DISTRESSES>

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW H5 Name: TAXIWAY H5 Use: TAXIWAY Area: 19,697.18SqFt

To: -Section: 350 of 1 From: -Last Const.: 1/1/2007

90.00Ft

Family: DEFAULT Zone: Category: Rank: P Surface: AAC

Area: 19,697.18SqFt Length: 200.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments:

Sample Number: 502 Type: R Area: 4,761.37SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 39.01 Ft L Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments:

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: TW H6 Name: TAXIWAY H6 Use: TAXIWAY Area: 19,697.18SqFt

Section: 360 of 1 From: - To: - Last Const.: 1/1/2007

90.00Ft

Surface: AAC Family: DEFAULT Zone: Category: Rank: P

Area: 19,697.18SqFt Length: 200.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 4 Surveyed: 1

Conditions: PCI:93.00 | Inspection Comments:

Sample Number: 602 Type: R Area: 4,761.37SqFt PCI = 93

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 2.00 Ft Comments: 52 WEATHERING/RAVELING L 100.00 Sqft Comments:

50.00Ft

FDOT_COMB

Report Generated Date: 3/29/2012

Site Name:

Network: TMB Name: KENDALL-TAMIAMI EXECUTIVE AIRPORT

Branch: Name: TAXIWAY H7 Use: TAXIWAY TW H7 Area: 12,808.80SqFt

To: -Section: 370 of 1 From: -Last Const.: 1/1/2007

Family: DEFAULT Zone: Category: Rank: P Surface: AAC

Area: 12,808.80SqFt Length: 190.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date3/26/2012 Total Samples: 2 Surveyed: 1

Conditions: PCI:94.00 | Inspection Comments:

Sample Number: 700 Type: R Area: 5,147.71SqFt PCI = 94

Sample Comments:

2.00 Ft 48 LONGITUDINAL/TRANSVERSE CRACKING L Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments: