

STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION OFFICE

Statewide Airfield Pavement Management Program

Ormond Beach Municipal Airport- OMN
(Regional Reliever)
Ormond Beach, Florida
(District 5)



TABLE OF CONTENTS

SEC	CTION PAGE	NO.
Exec	cutive Summary	iii
1.	Introduction	
2.	Network Definition and Pavement Inventory	10
3.	Pavement Condition	14
4.	Pavement Condition Prediction	19
5.	Maintenance Policies and costs	
6.	Pavement Rehabilitation Needs Analysis	26
7.	Maintenance and Rehabilitation Plan	
8.	Visual Aids	
9.	Recommendations	33
LIS	T OF FIGURES	
	re 1-1: Pavement Life Cycle	
Figu	re 1-2: PCI Rating Scale	6
	re 2-1: Pavement Area by Surface Type	
Figu	re 3-1: Network PCI Distribution by Rating Category	16
	re 3-1a: Condition Rating Summary	
	re 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use	
	re 4-1: Predicted PCI by Pavement Use	
Figu	re 6-1: Budget Scenario Analysis	29
LIS	T OF TABLES	
Tabl	le I: Condition Summary by Branch	iv
Tabl	le II: Condition Summary by Pavement Use	iv
Tabl	le III: Condition Summary by Pavement Rank	iv
	le IV: Immediate Major M&R Needs	
Tabl	le V: 10-Year M&R Costs under Unlimited Funding Scenario	vi
Tabl	le 1-1: Sampling Rate for FDOT Condition Surveys	5
	le 2-1: Construction Since Last Inspection & Anticipated Construction Activity	
	le 2-2: Pavement Area by Pavement Use	
	le 2-3: Branch and Section Inventory	
	le 3-1: Pavement Distresses for Asphalt Concrete Surfaces	
	le 3-2: Pavement Distresses for Portland Cement Concrete Surfaces	
Tabl	le 3-3: Condition by Pavement Use	17
Tabl	le 5-1: Routine Maintenance Activities for Airfield Pavements	21
Tabl	le 5-2: Critical PCI for Regional Reliever Airports	22
	le 5-3: FDOT Minimum Service Level PCI for Regional Reliever Airports	
	le 5-4: M&R Activities for Regional Reliever Airports	
	le 5-5: Maintenance Unit Costs for FDOT	
	le 5-6: M&R Activities and Unit Costs by Condition for Regional Reliever Airpor	
	le 6-1: Summary of Immediate Major M&R Needs Option No. 1	

i

TABLE OF CONTENTS

SECTION	PAGE NO.
Table 6-3: Su	mmary of Immediate Major M&R Needs Option No. 2
APPENDIC	ES
Appendix A	Network Definition Map
	System Inventory Map
	Pavement Inventory Table
	Work History Report
Appendix B	2011 Condition Map
	Pavement Condition Index Table
Appendix C	Branch Condition Report
	Section Condition Report
Appendix D	Pavement Condition Prediction Table
	Predicted PCI by Pavement Use Graph
Appendix E	Year 1 Maintenance Activities Table
Appendix F	Major M&R Plan by Year under Unlimited Funding Scenario Table
Appendix G	10-Year M&R Map
Appendix H	Photographs
Appendix I	PCI Re-inspection Report

EXECUTIVE SUMMARY

In 2010, the Florida Department of Transportation (FDOT) Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing Statewide Airfield Pavement Management Program (SAPMP) to be completed over fiscal years 2011 and 2012.

The tasks required to achieve this objective at Ormond Beach Municipal Airport included:

- ➤ Obtain recent construction history from the Airport to update the Pavement Inventory CADD drawings from the previous SAPMP update,
- ➤ Perform a visual Pavement Condition Index (PCI) survey of the airfield pavements at the Airport,
- ➤ Update the MicroPAVER database to analyze the PCI field data and determine the current condition of the airfield pavements,
- > Predict the future deterioration of the pavements,
- ➤ Develop a 10-year M&R plan to address the pavement needs at Ormond Beach Municipal Airport, and
- ➤ Provide the estimated costs associated with the suggested immediate and future M&R activities

During February 2011, the PCI survey was performed at Ormond Beach Municipal Airport. The results of the survey indicate that, based on a numerical scale of 0 to 100, the overall area-weighted average PCI of the airfield pavements in 2011 is 64, representing a Fair overall network condition.

Table I below summarizes the overall condition summary by network branch.

Table I: Condition Summary by Branch

Branch Name	Area Weighted PCI	Condition Rating	FDOT Minimum Service Level	MicroPAVER Minimum PCI	Action Required
Center Apron	50	Poor	65	65	X
East Apron - Hangar Area	26	Very Poor	65	65	X
Apron at T-Hangars	85	Satisfactory	65	65	
West Apron	61	Fair	65	65	X
Intersection of TW D and TW C	23	Serious	65	65	X
Runway 17-35	95	Good	75	65	
Runway 8-26	67	Satisfactory	75	65	X
Taxiway Alpha	67	Satisfactory	65	65	
Taxiway Bravo	47	Poor	65	65	X
Taxiway Charlie	24	Serious	65	65	X
Taxiway Delta	27	Very Poor	65	65	X
Taxiway Echo	43	Poor	65	65	X
Taxiway Foxtrot	59	Fair	65	65	X

Tables II and III below illustrate the area-weighted PCI computed individually for each pavement use and rank, respectively.

Table II: Condition Summary by Pavement Use

Use	Average Area- Weighted PCI	Condition Rating
Runway	82	Satisfactory
Taxiway	44	Poor
Apron	56	Fair
All (Weighted)	64	Fair

Table III: Condition Summary by Pavement Rank

Rank*	Average Area- Weighted PCI	Condition Rating
Primary	64	Fair
Secondary	67	Fair
Tertiary	58	Fair
All (Weighted)	64	Fair

^{*}The pavement rank for the airport pavement network is listed on Table 2-3.

The immediate M&R needs, or needs that have been programmed to be completed in the first year of the 10-year M&R plan based on an unlimited budget at Ormond Beach Municipal Airport, include: East Apron, Center Apron, West Apron, Intersection of TW D and TW C, Taxiway Foxtrot, Taxiway Echo, Taxiway Delta, Taxiway Charlie, Taxiway Bravo and Taxiway Alpha. These pavement sections exhibit distresses which justify either mill and overlay rehabilitation or full pavement reconstruction. The immediate needs are summarized in Table IV below.

Table IV: Immediate Major M&R Needs

Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	Major M&R Costs*		PCI Before M&R	M&R Activity	PCI After M&R
2011	East Apron	4305	AC	56,770	\$	1,054,218.83	25	Reconstruction	100
2011	Center Apron	4210	AAC	43,450	\$	123,658.70	63	Mill and Overlay	100
2011	Center Apron	4205	AAC	91,080	\$	693,119.14	41	Mill and Overlay	100
2011	Center Apron	4204	AC	5,930	\$	26,483.39	58	Mill and Overlay	100
2011	West Apron	4102	AC	22,250	\$	413,182.47	19	Reconstruction	100
2011	Intersection of TW D and TW C	805	AAC	4,010	\$	74,465.70	22	Reconstruction	100
2011	Taxiway Foxtrot	650	AC	6,270	\$	28,001.83	58	Mill and Overlay	100
2011	Taxiway Foxtrot	605	AC	41,690	\$	169,803.42	59	Mill and Overlay	100
2011	Taxiway Echo	505	AAC	78,240	\$	595,406.69	42	Mill and Overlay	100
2011	Taxiway Delta	405	AAC	104,640	\$	1,943,164.67	26	Reconstruction	100
2011	Taxiway Charlie	305	AAC	58,430	\$	1,085,045.03	23	Reconstruction	100
2011	Taxiway Bravo	210	AAC	20,570	\$	58,542.22	63	Mill and Overlay	100
2011	Taxiway Bravo	205	AAC	26,680	\$	140,123.42	56	Mill and Overlay	100
2011	Taxiway Bravo	204	PCC	17,500	\$	324,974.98	14	Reconstruction	100
2011	Taxiway Alpha	110	AC	6,990	\$	28,470.28	59	Mill and Overlay	100
		Total		\$6,758,660.77	42		100		

^{*} Costs are adjusted for inflation.

A forecast of Major M&R needs for a 10-year period, starting from 2011, was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval. The results of this analysis are provided in Table V below.

Table V: 10-Year M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$174,359.70	\$6,758,660.76	\$6,933,020.46
2012	\$144,528.64	\$0.00	\$144,528.64
2013	\$23,617.77	\$1,461,145.38	\$1,484,763.15
2014	\$38,715.21	\$0.00	\$38,715.21
2015	\$63,144.00	\$0.00	\$63,144.00
2016	\$91,144.75	\$0.00	\$91,144.75
2017	\$129,693.48	\$0.00	\$129,693.48
2018	\$165,791.14	\$36,636.46	\$202,427.60
2019	\$205,290.64	\$0.00	\$205,290.64
2020	\$248,571.44	\$0.00	\$248,571.44
Total	\$1,284,856.77	\$8,256,442.60	\$9,541,299.37

Note: Costs are adjusted for inflation.

The implementation of the 10-Year major M&R plan is expected to provide an improvement in the overall condition of the airfield pavement, where the area-weighted PCI would increase from 64 in 2011 to 77 in 2020. Appendix F lists the major M&R for the 10-Year program. Appendix G graphically depicts the activity.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all Ormond Beach Municipal Airport pavements in 2020 may remain near 77. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for Ormond Beach Municipal Airport is conducted at some point in the 10-year plan.

1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. There are millions of square yards of pavement for the runways, taxiways, aprons and other areas of these airports that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time.

In order to support the planning, scheduling, and design of the M&R activities based on pavement evaluation and pavement management performance trends, the Florida Department of Transportation (FDOT) Aviation Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992.

In 2010, the FDOT Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

This report discusses the work performed, a summary of the findings, results, and recommendations for M&R planning associated with the update to the SAPMP. It also describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented during the performance of the SAPMP.

1.1 Purpose

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the SAPMP and the roles and responsibilities of the program's participants;
- Provide background information on pavement management principles, objectives, and benefits to this airport;
- Outline the procedures used to collect, evaluate and report pavement inspection results at this airport;
- Present the findings from the pavement inspection;
- Analyze and discuss the needs for Maintenance and Rehabilitation (M&R) activities and associated costs for this airport.

1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The 1992 SAPMP provided valuable information for establishing and performing pavement M&R.

In 1992/1993, and 1998/1999, the FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement maintenance. This system, AIRPAV, was implemented, and initial condition surveys were

performed in 1992 and 1993. The SAPMP was updated with additional surveys in 1998 and 1999.

In 2004, the FDOT Aviation Office undertook a project to update the pavement management system software utilized for the SAPMP. This project involved a review of the AIRPAV software and other available pavement management system software. As a result of this review, MicroPAVER was selected as the software for the update project. Data from the 1998/1999 condition surveys were converted to the MicroPAVER system, and the inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999. The pavements were inspected between 2006 and 2008, and an updated M&R program was developed based on the new condition of the airfield pavements. As part of the update, procedures for the inspection and collection of pavement data were developed, and a website (www.floridaairportpavement.com) was created for the input of data under secure procedures.

Currently, airports using the AIP Grant Program are required by the Federal Aviation Administration (FAA) to develop a pavement maintenance program (FAA/AC 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements") using trained personnel to perform a detailed inspection of airfield pavements. The inspections are required to be performed at least once a year or every 3 years if pavement inspection is characterized in the form of a Pavement Condition Index (PCI) survey (such as ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys", (2004 edition)). The 2004 edition was utilized in lieu of the 2010 edition to maintain database integrity and benefit of pavement performance curves from the previous inspections.

In 2010, the FDOT Aviation Office selected a team consisting of the Consultant and their Subconsultants to provided services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

1.3 Organization

1.3.1 Aviation Office Program Manager Role

The Aviation Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) monitoring the work of the Consultant. The AO-PM has review and approval authority for each program task and also manages the day-to-day details of the SAPMP and the updates.

1.3.2 Consultant Role

The Consultant (Kimley-Horn and Associates, Inc.) and their Subconsultants (MACTEC Engineering and Consulting and All About Pavements, Inc.) provide technical and administrative assistance to the AO-PM during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the SAPMP based upon procedures outlined in FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

1.3.3 Airport Role

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP update, indicate any construction activity that has been performed since the previous inspections.

1.4 Pavement Types and Pavement Management

1.4.1 Pavement basics

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of an asphalt concrete (AC) surface, and
- Rigid pavement composed of a Portland Cement Concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying natural subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland Cement Concrete supports most of the load, and the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the construction of the concrete surface.

A small percentage of the airport pavements in Florida are composed of asphalt concrete surface over Portland Cement Concrete (APC). This pavement type is known as "composite" pavement.

Due to the different nature of the pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

1.4.2 Pavement Management System Concept

The SAPMP utilized a Pavement Management System (PMS) to develop the M&R recommendations discussed in this report. A PMS is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1 below, taken from FAA/AC 5380-7A "Airport Pavement Management Program", illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in "good" condition depends on how well it is maintained. As the illustration demonstrates, the cost of maintaining the pavement above a critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.




Figure 1-1: Pavement Life Cycle

Source: FAA/AC 150/5380-7A "Airport Pavement Management Program" *Modified to reflect current construction costs.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi-year M&R plan can be determined.

1.4.3 Pavement Inspection Methodology for the SAPMP

Pavement condition assessment is one of the primary decision variables in any airport PMS. Pavement condition assessments generally include visual surveys in accordance with ASTM D 5340, "Standard Test Method for Airport Pavement Condition Index Surveys" and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the Statewide Aviation Pavement Management Program update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine the appropriate rehabilitation methods during the design process.

In preparation of the PCI surveys, the airfield pavements are divided into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Further discussion of how the airport pavements are divided and subdivided into units by construction and use can be found in Section 2 "Network Definition and Pavement Inventory" of this report.

Sample unit sizes are approximately 5000 ± 2000 square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements. Prior to conducting the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of Branches, Sections, use patterns, construction types and history. The sampling rate used for the FDOT Statewide Airfield Pavement Management Program is provided in Table 1-1 below.

Table 1-1: Sampling Rate for FDOT Condition Surveys

	AC Pavemen	ts		PCC Paveme	ents		
N	n		N	n			
	Runway	Others	11	Runway	Others		
1-4	1	1	1-3	1	1		
5-10	2	1	4-6	2	1		
11-15	3	2	7-10	3	2		
16-30	5	3	11-15	4	2		
31-40	7	4	16-20	5	3		
41-50	8	5	21-30	7	3		
<u>≥</u> 51	20% but ≤20	10% but ≤10	31-40	8	4		
			41-50	10	5		
			<u>≥</u> 51	20% but <u><</u> 20	10% but <u><</u> 10		

Where

N = total number of sample units in Section

n = number of sample units to inspect

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the Section. In the case when nonrepresentive distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each Section. PCI values range from 0 to 100. As Figure 1-2 below indicates, MicroPAVER provides a rating scale that relates PCI to pavement condition. A PCI between 0 and 10 is considered 'Failed' pavement, and a PCI between 86 and 100 is considered 'Good' pavement, with five other conditions for PCI values between 11 and 85.

Figure 1-2: PCI Rating Scale

PCI	Condition Rating
86 – 100	Good
71 – 85	Satisfactory
56 – 70	Fair
41 – 55	Poor
26 - 40	Very Poor
11 – 25	Serious
0 - 10	Failed

1.5 Definitions

<u>Aviation Office</u> - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office Program Manager (AO-PM) has review and approval authority for each program task of the SAPMP.

<u>Base Course</u> - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

<u>Branch</u> - A Branch designates pavements that have common usage and functionality, such as an entire runway, taxiway, or apron.

<u>Branch ID</u> - A short form identification for the pavement Branch. In this report, Branch includes the common designation for the item e.g. RW 18-36.

<u>Category</u> - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA for general aviation or community airports;
- RL for regional relievers or small hubs;
- PR for primary (certified under Part 139 requirements).

<u>Critical PCI</u> - The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

<u>Distress Type</u> - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland Cement Concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

<u>Florida DOT (FDOT)</u> - Florida Department of Transportation was represented in this project by the Office of Aviation.

<u>Global M&R</u> - Global M&R is defined as activities applied to entire pavement Sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

<u>Localized M&R (Maintenance and Repair)</u> - Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

<u>Major M&R (e.g. Rehabilitation)</u> - Activities performed over the entire area of a pavement Section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

<u>MicroPAVER</u> - A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that, if properly implemented, maintained, and operated, it meets the pavement management program requirements described by the FAA in Advisory Circular 150/5380-7A.

<u>Minimum Condition Level</u> - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

<u>Network Definition</u> - A Network Definition is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport is in Appendix A along with a table of inventory data.

<u>Pavement Condition Index (PCI)</u> - The Pavement Condition Index is a number which represents the condition of a pavement segment at a specific point in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340, published by ASTM International.

<u>Pavement Evaluation</u> - A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

<u>Pavement Management System (PMS)</u> - A Pavement Management System is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

<u>Pavement Surface Type</u> - The surface of pavement is identified as one of four types:

- AC for asphalt surface pavements;
- PCC for Portland Cement Concrete pavements;
- AAC for asphalt surface pavements that have had an asphalt overlay at some point in their construction history;
- APC for composite pavements, which consist of asphalt over Portland Cement Concrete pavement.
- PAC for composite pavements, which consist of Portland Cement Concrete over asphalt pavement.

<u>Rank</u> - Pavement rank in MicroPAVER determines the priority to be assigned to a pavement Section when developing an M&R plan. Pavement Sections are ranked as follows according to their use:

- P for Primary pavements, such as primary runways, primary taxiways, and primary aprons;
- S or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons;
- T for Tertiary pavements such as "T" hangars and slightly used aprons.

<u>Reconstruction</u> - Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

<u>Rehabilitation</u> - Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

<u>Sample Unit</u> - Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are $5,000 \pm 2,000$ square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements.

<u>Section</u> - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition, and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

<u>Section ID</u> - A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series Sections are taxiways, 4000 and 5000 series Sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series Sections are runways.

<u>Statewide Airfield Pavement Management Program (SAPMP)</u> – The Statewide Airfield Pavement Management Program is a program implemented in 1992 by the Florida Department of Transportation to plan, schedule, and design the maintenance and rehabilitation activities

necessary for the airfield pavement on Florida's public airports to allow the airports to operate efficiently, economically, and without excessive down time.

<u>System Inventory</u> - A System Inventory is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline and identifies airfield construction activities since the last inspection. The System Inventory for the airport is included in Appendix A.

<u>Use</u> - In MicroPAVER, Use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

2. NETWORK DEFINITION AND PAVEMENT INVENTORY

Ormond Beach Municipal Airport (OMN) consists of two runways; RW 8-26, which is 75-ft wide by 4,004-ft long and RW 17-35, which is 100-ft wide by 3,701-ft long. RW 8-26 is served by a parallel taxiway, TW Alpha, which is 35-ft wide. RW 17-35 is served by taxiways Echo and Foxtrot, which are 35-ft and 40-ft wide, respectively. Taxiways Bravo and Delta are used to direct traffic to and from the apron, and taxiway Charlie is currently listed is inactive. Currently the airport has multiple T-Hangar and conventional hangar facilities located on the east side of RW 17-35 and tie-down spaces located throughout the apron. All of the pavement for the runway, taxiways, apron and hangars is constructed with Asphalt Concrete. A section of pavement used to access the hangars on the south side of TW Delta is composed of Portland Cement Concrete.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric dimensions may vary slightly from the geometry used in the condition and M&R analysis based on field measurements.

Ormond Beach Municipal Airport was established in 1943 as Outlying Field Ormond Beach, which was a naval aviation training field supporting operations at Naval Air Station Deland and Naval Air Station Daytona Beach. Military operations were discontinued at the end of World War II and the airport was deeded to the city by the US Government in 1959. Currently, the airport provides an additional location for flight training operations from nearby Embry-Riddle Aeronautical University at Daytona Beach International Airport.

This airport is designated as a Regional Reliever airport and is located in District 5 of the Florida Department of Transportation.

2.1 Network Definition

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units.

2.1.1 Branch Section Identification

The airport pavement network is subdivided into separate Branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then further divided into Sections with similar pavement construction and performance that may share other common attributes.

Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage. A pavement rank, consisting of primary, secondary, and tertiary levels, is assigned to each Section based on their level and type of use. The pavement rankings that were designated for each Section in the previous SAPMP update were again used for this update.

As discussed in Section 1.4.3 "Pavement Inspection Methodology for the SAPMP", the sections are sub-divided into sample units, which are the smallest subdivision in a pavement network, only for the purpose of conducting the pavement condition survey.

2.1.2 System Inventory and Network Definition Update

The System Inventory and Network Definition drawings are used to identify changes in the network since the most recent update from the 2006/2008 inspections and also to plan the field inspection activities for the 2011 survey. Prior to the field inspection process, the System Inventory drawing was updated from the previous inspection with notes indicating recent construction projects on the various Sections of pavement throughout the airfield. This System Inventory drawing is used to update the Network Definition drawing.

The Network Definition drawing shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The previous airport configuration and history was compared with the current airport configuration, and the existing network branch, section and sample unit designations were revised to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important historical record.

The updated System Inventory and Network Definition drawings for Ormond Beach Municipal Airport are provided in Appendix A. Table 2-1 below lists the recent construction projects at the airport.

Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity

Construction Year	Location	Work Type / Pavement Section
2011-2012	Taxiway Alpha	Reconstruction
2011-2012	Taxiway Charlie	Re-Surface

2.2 Pavement Inventory

The detailed pavement inventory was updated to reflect the network definition update and field inspection results.

The total airfield pavement area in 2011 at Ormond Beach Municipal Airport is 1,548,775 square feet. The breakdown of pavement area for each pavement use is provided in Table 2-2.

Table 2-2: Pavement Area by Pavement Use

Use	Area (ft²)	% of Total Area		
Runway	663,445	43%		
Taxiway	447,900	29%		
Apron	437,430	28%		
All (Weighted)	1,548,775	100%		

Figure 2-1 presents the breakdown of the pavement area at Ormond Beach Municipal Airport by surface type.




Figure 2-1: Pavement Area by Surface Type

Details of pavement Branch and Section information including Branch name (which indicates pavement use), Branch ID, Section ID, section area, rank, surface type, last construction date, number of samples inspected, and number of samples in each Section are given in Table 2-3 below. A more detailed Pavement Inventory Table may be found in Appendix A of this report.

Table 2-3: Branch and Section Inventory

Branch Name	Branch ID	Section ID	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
Center Apron	AP CENTER	4210	43,450	P	AAC	1/1/1992	1	9
Center Apron	AP CENTER	4205	91,080	T	AAC	1/1/1992	3	18
Center Apron	AP CENTER	4204	5,930	Т	AC	7/31/2008	1	2
East Apron - Hangar Area	AP E	4305	56,770	P	AC	1/1/1984	3	12
Apron at T-Hangars	AP T HANG	4410	53,360	P	AC	1/1/2005	2	10
West Apron	AP W	4102	22,250	P	AC	1/1/1992	1	7
West Apron	AP W	4105	164,590	T	AC	1/1/1992	4	38
Intersection of TW D and TW C	INT TWD/C	805	4,010	P	AAC	1/1/1990	1	1
Runway 17-35	RW 17-35	6205	342,210	P	AAC	1/1/2008	14	68
Runway 17-35	RW 17-35	6210	20,785	P	AAC	1/1/2008	1	4
Runway 8-26	RW 8-26	6105	300,450	S	AAC	1/1/1977	16	80
Taxiway Alpha	TW A	105	71,280	P	AC	1/1/1977	4	20
Taxiway Alpha	TW A	110	6,990	P	AC	1/1/1977	1	1
Taxiway Alpha	TW A	112	11,600	P	AAC	1/1/1977	1	2
Taxiway Bravo	TW B	205	26,680	P	AAC	1/1/1977	2	7
Taxiway Bravo	TW B	210	20,570	P	AAC	1/1/1977	1	4
Taxiway Bravo	TW B	204	17,500	P	PCC	1/1/1992	1	6
Taxiway Charlie	TW C	305	58,430	P	AAC	1/1/1990	3	12
Taxiway Delta	TW D	405	104,640	P	AAC	1/1/1984	6	21
Taxiway Echo	TW E	505	78,240	P	AAC	1/1/1990	4	22
Taxiway Foxtrot	TW F	605	41,690	P	AC	1/1/1984	2	10
Taxiway Foxtrot	TW F	650	6,270	P	AC	1/1/1984	1	1

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

3. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340-04 "Standard Practice for Airport Pavement Condition Index Surveys." These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

3.1 Inspection Methodology

A PCI survey is performed by measuring the amount and severity of pavement distresses, which are caused by traffic load, climate, and other factors, observed within a sample unit. This data is imported into MicroPAVER, which calculates PCI values for the pavement sections. Tables 3-1 and 3-2 below list the pavement distress types and related causes for asphalt concrete (AC) and Portland Cement Concrete (PCC), respectively.

Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces

Code	Distress	Mechanism					
41	Alligator Cracking	Load					
42	Bleeding	Construction Quality / Mix Design					
43	Block Cracking	Climate / Age					
44	Corrugation	Load / Construction Quality					
45	Depression	Subgrade Quality					
46	Jet Blast	Aircraft					
47	Joint Reflection - Cracking Climate / Prior Paveme						
48	Longitudinal/Transverse Cracking	Climate / Age					
49	Oil Spillage Aircraft / Vehicl						
50	Patching	Utility / Pavement Repair					
51	Polished Aggregate	Load					
52	Weathering/Raveling	Climate / Load					
53	Rutting	Load					
54	Shoving	Pavement Growth					
55	Slippage Cracking	Load / Pavement Bond					
56	Swelling	Climate / Subgrade Quality					
Source: U.S	Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual						

Table 3-2: Pavement Distresses for Portland Cement Concrete Surfaces

Code	Distress	Mechanism
61	Blow-up	Climate
62	Corner Break	Load
63	Linear Cracking	Load
64	Durability Cracking	Climate
65	Joint Seal Damage	Climate
66	Small Patch	Pavement Repair
67	Large Patch/Utility Cut	Utility / Pavement Repair
68	Popout	Climate
69	Pumping	Load
70	Scaling/Crazing	Construction Quality
71	Faulting	Subgrade Quality
72	Shattered Slab	Load
73	Shrinkage Cracking	Construction Quality / Load
74	Joint Spalling	Load
75	Corner Spalling	Load
Source: U.S	. Army CERL, FDOT Airfield In	spection Reference Manual

Prior to conducting the inspections, Global Positioning System (GPS) coordinates were recorded using CADD at the centroid of each sample unit. The centroid is usually the geometric center of the area, but in cases where sample units are irregular in shape, this is the center of mass. These data are presented in a table on the updated Network Definition Map in Appendix A of this report.

Pavement condition inspections at Ormond Beach Municipal Airport were performed in February 2011. Data were recorded in the field in accordance with FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

After the completion of data collection, the data was imported into MicroPAVER, and PCI values were calculated for the pavement sections.

3.2 Pavement Condition Index Results

According to the 2011 survey, the overall area-weighted PCI at Ormond Beach Municipal Airport is 64, representing a Fair overall network condition.

Overall the airport exhibited pavement distresses associated with climate and age distresses. Asphalt Concrete pavement distresses include; weathering, raveling, longitudinal and transverse cracking, swelling, and block cracking distresses of which are common of pavements of similar age.

Runway 8-26 exhibited low to medium severity weathering and raveling in addition to longitudinal cracks primarily located along the paving joints. This distress is common along the paving joints due to the pavement being weakest at this location.

Other than the small amount of low severity weathering and raveling, Runway 17-35 was in an overall good condition.

Taxiways throughout the airfield exhibited low to medium severity weathering and raveling along with low to medium severity block cracking. There were a few isolated locations which exhibited medium severity swelling.

Appendix B contains a table and a Condition Map which depicts the PCI results by Section, and Appendix C contains a table of PCI results by Branch. Appendix I includes detailed distress data generated by MicroPAVER for each inspected sample unit.

Figure 3-1 provides the PCI distribution by rating category for Ormond Beach Municipal Airport.




Figure 3-1: Network PCI Distribution by Rating Category

Figure 3-1a: Condition Rating Summary

Condition Rating	Total Area (ft²)	Percent
Good	362,995	23%
Satisfactory	53,360	3%
Fair	699,500	45%
Poor	169,320	11%
Very Poor	161,410	10%
Serious	102,190	7%
Failed	0	0%


Approximately 26% of the network is in Good and Satisfactory condition while 17% of the network is in Very Poor and Serious condition. Table 3-3 illustrates the area-weighted PCI computed individually for each pavement use.

Table 3-3: Condition by Pavement Use


Use	Area-Weighted PCI	Condition Rating		
Runway	82	Satisfactory		
Taxiway	44	Poor		
Apron	56	Fair		
All (Weighted)	64	Fair		

Figure 3-2 presents the breakdown of PCI by range for each pavement use.

Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use



(b) Taxiway



□ Failed: 0-10

4. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 4-1 illustrates the predicted performance of pavements at Ormond Beach Municipal Airport based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum service level for Regional Reliever (RL) airports.




Figure 4-1: Predicted PCI by Pavement Use

Appendix D presents the tabular summary of the predicted Section PCI for each year from 2011 to 2020.

5. MAINTENANCE POLICIES AND COSTS

5.1 Policies

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature and are recommended to help achieve the performance goal.

Table 5-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules. These repairs are used only in the first year of an analysis.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called "Critical PCI." The critical PCI levels for different pavement and branch types established in the previous SAPMP update were used in this update for the development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 5-2 gives the critical PCI levels for Regional Reliever Airports.

The maintenance rehabilitation policy and activity costs have been updated based on the study of readily available construction cost data at the time of this study. The costs depicted in this report are intended for planning purposes.

Table 5-1: Routine Maintenance Activities for Airfield Pavements

Surface	Distress	Severity*	Work Type	Code	Work Unit
	Alligator Crack	M, H	Patching - AC Deep	PA-AD	SqFt
	Bleeding	N/A	No Localized M&R	NONE	N/A
	Block Crack	M, H	Crack Sealing – AC	CS-AC	SqFt
	Corrugation	L, M, H	Patching - AC Deep	PA-AD	SqFt
	Depression	M, H	Patching - AC Deep	PA-AD	SqFt
	Jet Blast	N/A	Patching - AC Deep	PA-AD	SqFt
	Joint Ref. Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	L & T Crack	M, H	Crack Sealing – AC	CS-AC	Ft
AC	Oil Spillage	N/A	Patching - AC Shallow	PA-AS	SqFt
AC	Patching	M, H	Patching - AC Deep	PA-AD	SqFt
	Polished Agg.	N/A	No Localized M&R	NONE	N/A
		L	Surface Sealing - Rejuvenating	SS-RE	SqFt
	Raveling	M	Surface Seal - Coal Tar	SS-CT	SqFt
		Н	Microsurfacing	MI-AC	SqFt
	Rutting	M, H	Patching - AC Deep	PA-AD	SqFt
	Shoving	M, H	Grinding (Localized)	GR-LL	SqFt
	Slippage Crack	N/A	Patching - AC Shallow	PA-AS	SqFt
	Swelling	M, H	Patching - AC Deep	PA-AD	SqFt
	Blow-Up	L, M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Corner Break	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Linear Crack	M, H	Crack Sealing – PCC	CS-PC	Ft
	Durability Crack	Grack H Slab Replacement – PCC		SL-PC	SqFt
	Durability Crack	M	Patching - PCC Full Depth	PA-PF	SqFt
	Jt. Seal Damage	M, H	Joint Seal (Localized)	JS-LC	Ft
	Small Patch	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
PCC	Large Patch	M, H	Patching - PCC Full Depth	PA-PF	SqFt
FCC	Popouts	N/A	No Localized M&R	NONE	N/A
	Pumping	N/A	No Localized M&R	NONE	N/A
	Scaling	H	Slab Replacement – PCC	SL-PC	SqFt
	Faulting	M, H	Grinding (Localized)	GR-PP	Ft
	Shattered Slab	M, H	Slab Replacement – PCC	SL-PC	SqFt
	Shrinkage Crack	N/A	No Localized M&R	NONE	N/A
	Joint Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Corner Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt

^{*}L = Low, M = Medium, H = High

Table 5-2: Critical PCI for Regional Reliever Airports

Use	Critical PCI
Runway	65
Taxiway	65
Apron	65

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 5-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of Regional Reliever Airports.

Table 5-3: FDOT Minimum Service Level PCI for Regional Reliever Airports

Minimum PCI						
Runway Taxiway Apron						
75 65 65						

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 5-2, the PCI trigger range when the likely activity would be a mill and resurface was 40 to 79 and reconstruction at a PCI of 39 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 5-4 summarizes the M&R activities for Regional Reliever Airports based on PCI value.

Table 5-4: M&R Activities for Regional Reliever Airports

	Activity	PCI Range
Maintenance	Crack Sealing and Full-Depth Patching	80 and 90
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	40 to 79
	Reconstruction	39 and less

5.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were updated from the previous SAPMP study based on current construction cost trends in order to determine meaningful costs for the program. Table 5-5 presents the unit costs summary.

5.3 M&R Activities

FDOT recognizes that although Mill and Overlay work is recommended for asphalt pavements within a PCI range from 40 to 79, it is conceivable that airports may not have adequate funding to perform this type of rehabilitation. Microsurfacing treatment is a maintenance/rehabilitation measure that can be used in lieu of asphalt pavement mill and overlay; however it should be understood that this measure is intended for short term pavement life extension. While the cost of microsurfacing is significantly lower than that of pavement mill and overlay, it is not intended to be a full rehabilitative measure for long term benefit.

Table 5-5: Maintenance Unit Costs for FDOT

Code	Name	Cost	Unit
GR-LL	Grinding (Localized for AC)	\$2.10	SqFt
PA-AL	Patching – AC Leveling	\$2.30	SqFt
PA-AS	Patching – AC Shallow	\$2.90	SqFt
PA-PF	Patching – PCC Full Depth	\$38.11	SqFt
PA-PP	Patching – PCC Partial Depth	\$19.06	SqFt
SL-PC	Slab Replacement – PCC	\$39.11	SqFt
CS-PC	Crack Sealing – PCC	\$4.24	Ft
UN-PC	Undersealing – PCC	\$3.40	Ft
CS-AC	Crack Sealing – AC	\$2.25	Ft
GR-PP	Grinding (Localized for PCC)	\$22.51	Ft
JS-LC	Joint Seal (Localized)	\$2.00	Ft
SH-LE	Shoulder Leveling	\$2.81	Ft
JS-SI	Joint Seal – Silicon	\$2.81	Ft
PA-AD	Patching – AC Deep	\$4.90	SqFt
OL-AT	Overlay – AC Thin	\$2.80	SqFt
SS-CT	Surface Seal – Coal Tar	\$0.40	SqFt
SS-FS	Surface Seal – Fog Seal	\$0.40	SqFt
SS-RE	Surface Seal – Rejuvenating	\$0.40	SqFt
ST-SB	Surface Treatment – Single Bitum.	\$0.30	SqFt
ST-SS	Surface Treatment – Slurry Seal	\$0.55	SqFt
ST-ST	Surface Treatment – Sand Tar	\$0.28	SqFt
MI-AC	Microsurfacing - AC	\$0.65	SqFt

The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection was performed recently and only in the first year of the M&R analysis. In subsequent years, MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCIs. That is, for low PCI, it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly.

Using available unit cost data, the Major M&R Cost by Condition table was set up as shown in Table 5-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

Table 5-6: M&R Activities and Unit Costs by Condition for Regional Reliever Airports

	Activity	PCI Trigger	Cost/SqFt
Maintenance	Crack Sealing and Full-Depth Patching	90	\$0.06
Wiamitemanice	Crack Scannig and I un-Depth I atching	80	\$0.24
		70	\$3.00
	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	60	\$3.42
Dahahilitation		50	\$6.29
Rehabilitation		40	\$6.29
	Reconstruction	30	\$13.62
	Reconstruction	20	\$13.62

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

6. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years, starting from 2011. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Table 6-1 presents the M&R list of immediate needs for Major M&R, i.e. Year 1 of the forecast. The importance of this listing is that it points out the major activities triggered by the current condition of the pavements.

Table 6-1: Summary of Immediate Major M&R Needs Option No. 1

Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	N	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	East Apron	4305	AC	56,770	\$	1,054,218.83	25	Reconstruction	100
2011	Center Apron	4210	AAC	43,450	\$	123,658.70	63	Mill and Overlay	100
2011	Center Apron	4205	AAC	91,080	\$	693,119.14	41	Mill and Overlay	100
2011	Center Apron	4204	AC	5,930	\$	26,483.39	58	Mill and Overlay	100
2011	West Apron	4102	AC	22,250	\$	413,182.47	19	Reconstruction	100
2011	Intersection of TW D and TW C	805	AAC	4,010	\$	74,465.70	22	Reconstruction	100
2011	Taxiway Foxtrot	650	AC	6,270	\$	28,001.83	58	Mill and Overlay	100
2011	Taxiway Foxtrot	605	AC	41,690	\$	169,803.42	59	Mill and Overlay	100
2011	Taxiway Echo	505	AAC	78,240	\$	595,406.69	42	Mill and Overlay	100
2011	Taxiway Delta	405	AAC	104,640	\$	1,943,164.67	26	Reconstruction	100
2011	Taxiway Charlie	305	AAC	58,430	\$	1,085,045.03	23	Reconstruction	100
2011	Taxiway Bravo	210	AAC	20,570	\$	58,542.22	63	Mill and Overlay	100
2011	Taxiway Bravo	205	AAC	26,680	\$	140,123.42	56	Mill and Overlay	100
2011	Taxiway Bravo	204	PCC	17,500	\$	324,974.98	14	Reconstruction	100
2011	Taxiway Alpha	110	AC	6,990	\$	28,470.28	59	Mill and Overlay	100
	Total					\$6,758,660.77	42		100

^{*} Costs are adjusted for inflation.

FDOT recognizes that the costs attributed to the aforementioned 'Major Activity' of performing a pavement 'Mill and Overlay' may conflict with budgetary constraints. Table 6-2 presents an alternative minor rehabilitative activity to the mid-range performing pavements. The alternative activity is performing a 'Microsurfacing/Slurry Seal' to the pavement to retard the degradation of the facility until funding is available for a 'Mill and Overlay' activity.

Table 6-2: Summary of Immediate Major M&R Needs Option No. 2

Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	N	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	East Apron	4305	AC	56,770	\$	1,054,218.83	25	Reconstruction	100
2011	Center Apron	4210	AAC	43,450	\$	28,242.50	63	Microsurfacing	100
2011	Center Apron	4205	AAC	91,080	\$	59,202.00	41	Microsurfacing	100
2011	Center Apron	4204	AC	5,930	\$	3,854.50	58	Microsurfacing	100
2011	West Apron	4102	AC	22,250	\$	413,182.47	19	Reconstruction	100
2011	Intersection of TW D and TW C	805	AAC	4,010	\$	74,465.70	22	Reconstruction	100
2011	Taxiway Foxtrot	650	AC	6,270	\$	4,075.50	58	Microsurfacing	100
2011	Taxiway Foxtrot	605	AC	41,690	\$	27,098.50	59	Microsurfacing	100
2011	Taxiway Echo	505	AAC	78,240	\$	50,856.00	42	Microsurfacing	100
2011	Taxiway Delta	405	AAC	104,640	\$	1,943,164.67	26	Reconstruction	100
2011	Taxiway Charlie	305	AAC	58,430	\$	1,085,045.03	23	Reconstruction	100
2011	Taxiway Bravo	210	AAC	20,570	\$	13,370.50	63	Microsurfacing	100
2011	Taxiway Bravo	205	AAC	26,680	\$	17,342.00	56	Microsurfacing	100
2011	Taxiway Bravo	204	PCC	17,500	\$	324,974.98	14	Reconstruction	100
2011	Taxiway Alpha	110	AC	6,990	\$	4,543.50	59	Microsurfacing	100
	Total					\$5,103,636.68	42		100

^{*} Costs are adjusted for inflation.

In addition to the immediate Major M&R needs, maintenance activities for pavement areas above critical PCI have been recommended by MicroPAVER for Year 1 and are shown in Table 6-3 below. The costs provided in Table 5-5 were used to calculate the costs associated with this work, which is intended to treat specific distress types. A more detailed table is provided in Appendix E.

Table 6-3: Summary of Year 1 Maintenance Activities

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Runway 17-35	RW 17-35	6210	WEATH/RAVEL	L	Surface Seal - Rejuvenating	415.70	SqFt	\$0.40	\$166.28
Runway 17-35	RW 17-35	6205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	10,021.80	SqFt	\$0.40	\$4,008.77
Runway 17-35	RW 17-35	6205	WEATH/RAVEL	M	Surface Seal - Coat Tar	73.30	SqFt	\$0.40	\$29.33
Runway 8-26	RW 8-26	6105	L & T CR	M	Crack Sealing - AC	1,111.60	Ft	\$2.25	\$2,501.21
Runway 8-26	RW 8-26	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	186,779.50	SqFt	\$0.40	\$74,712.42
Runway 8-26	RW 8-26	6105	WEATH/RAVEL	M	Surface Seal - Coat Tar	21,782.60	SqFt	\$0.40	\$8,713.11
Apron at T-Hangar	AP T HANG	4410	WEATH/RAVEL	L	Surface Seal - Rejuvenating	10,672.00	SqFt	\$0.40	\$4,268.84
West Apron	AP W	4105	L & T CR	M	Crack Sealing - AC	2,103.10	Ft	\$2.25	\$4,731.95
West Apron	AP W	4105	OIL SPILLAGE	N	Patching - AC Shallow	461.90	SqFt	\$2.90	\$1,339.43
West Apron	AP W	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	121,613.40	SqFt	\$0.40	\$48,645.75
Taxiway Alpha	TW A	112	WEATH/RAVEL	L	Surface Seal - Rejuvenating	6,026.00	SqFt	\$0.40	\$2,410.41
Taxiway Alpha	TW A	105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	56,144.30	SqFt	\$0.40	\$22,457.91
Taxiway Alpha	TW A	105	WEATH/RAVEL	M	Surface Seal - Coat Tar	935.70	SqFt	\$0.40	\$374.30
								Total =	\$174,359.71

The 10 year forecast results are shown in Figure 6-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.




Figure 6-1: Budget Scenario Analysis

The following network level observations can be made from the figure above:

- The PCI will deteriorate from 64 in 2011 to 46 in ten years if no M&R activities are performed.
- The PCI will remain at or above 77 through the 10-year analysis period under the unlimited budget scenario. A 2020 PCI of 77 with this scenario is 31 PCI points higher than a "No M&R" scenario. The total cost for Major M&R over this 10-year period is about \$8.3 million.

7. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels, the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCIs less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 7-1 provides the summary results under the critical PCI unlimited funding scenario.

Table 7-1: M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$174,359.70	\$6,758,660.76	\$6,933,020.46
2012	\$144,528.64	\$0.00	\$144,528.64
2013	\$23,617.77	\$1,461,145.38	\$1,484,763.15
2014	\$38,715.21	\$0.00	\$38,715.21
2015	\$63,144.00	\$0.00	\$63,144.00
2016	\$91,144.75	\$0.00	\$91,144.75
2017	\$129,693.48	\$0.00	\$129,693.48
2018	\$165,791.14	\$36,636.46	\$202,427.60
2019	\$205,290.64	\$0.00	\$205,290.64
2020	\$248,571.44	\$0.00	\$248,571.44
Total	\$1,284,856.77	\$8,256,442.60	\$9,541,299.37

Note: Costs are adjusted for inflation.

Approximately 82% of the total Major M&R cost is required in the first year (2011). According to the 2011 inspections, the following pavement sections were in immediate need of Major M&R Activity:

- East Apron Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Center Apron** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.
- **West Apron** Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Intersection of TW D and TW C** Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Alpha** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.

Pavement Evaluation Report –Ormond Beach Municipal Airport Florida Statewide Pavement Management Program May 2011

- Taxiway Bravo Asphalt Pavement mill and overlay activity per the FAA P-401 Specification and Portland Cement Concrete reconstruction per the FAA P-501 Specification.
- **Taxiway Charlie** Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Delta** Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Echo** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.
- **Taxiway Foxtrot** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.

The unlimited budget scenario provides the basis for estimating the total repair cost.

Appendix F provides details of M&R plan by year under the unlimited funding scenario, and the map of the 10-year M&R plan is provided in Appendix G. It is important to understand that the SAPMP is a network level tool and the M&R costs provided in this report are only for planning purposes.

Pavement Evaluation Report –Ormond Beach Municipal Airport Florida Statewide Pavement Management Program May 2011

8. VISUAL AIDS

8.1 System Inventory and Network Definition Drawings

The System Inventory and Network Definition CADD drawings, which show the airport pavement outline with Branch and Section boundaries and identify changes in the network pavement since the last inspection and the sampling plan, respectively, are included in Appendix A of this report.

8.2 Condition Map

A Condition Map that has been prepared based on data linked to the airport's shape file is included in Appendix B. The Condition Map graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

8.3 10-Year M&R Map

A 10-Year M&R Map that shows the summary of the M&R plan is attached in Appendix G.

8.4 Photographs

Selected digital photographs taken during the pavement inspection are provided in Appendix H to provide visual support to special pavement conditions or distress observed during the inspection of the airport.

9. RECOMMENDATIONS

Pavement condition inspections were performed at Ormond Beach Municipal Airport, and a 10-year M&R plan was developed based on the unlimited funding scenario.


The following recommendations were made based on the 2011 condition inspection and M&R analysis results:

- East Apron Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Center Apron** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.
- West Apron Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Intersection of TW D and TW C** Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Alpha** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.
- Taxiway Bravo Asphalt Pavement mill and overlay activity per the FAA P-401 Specification and Portland Cement Concrete reconstruction per the FAA P-501 Specification.
- **Taxiway Charlie** Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Delta** Asphalt Pavement reconstruction activity per the FAA P-401 Specification.
- **Taxiway Echo** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.
- **Taxiway Foxtrot** Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.

Further evaluation of these features is necessary in order to develop repair plans and timing for future budgets since these needs cannot be addressed with typical annual expenditures.

APPENDIX A

NETWORK DEFINITION MAP SYSTEM INVENTORY MAP PAVEMENT INVENTORY TABLE WORK HISTORY REPORT






Table A-1: Pavement Inventory

Branch Name	Branch ID	Branch Use	Section ID	Length (ft)	Width (ft)	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
Center Apron	AP CENTER	APRON	4210	180	205	43,450	P	AAC	1/1/1992	2/28/2011	9
Center Apron	AP CENTER	APRON	4205	450	200	91,080	T	AAC	1/1/1992	2/28/2011	18
Center Apron	AP CENTER	APRON	4204	285	22	5,930	T	AC	7/31/2008	2/28/2011	2
East Apron - Hangar Area	AP E	APRON	4305	360	133	56,770	P	AC	1/1/1984	2/28/2011	12
Apron at T-Hangars	AP T HANG	APRON	4410	2,000	25	53,360	P	AC	1/1/2005	2/28/2011	10
West Apron	AP W	APRON	4102	670	34	22,250	P	AC	1/1/1992	2/28/2011	7
West Apron	AP W	APRON	4105	835	180	164,590	T	AC	1/1/1992	2/28/2011	38
Intersection of TW D and TW C	INT TWD/C	TAXIWAY	805	120	35	4,010	P	AAC	1/1/1990	2/28/2011	1
Runway 17-35	RW 17-35	RUNWAY	6205	3,420	100	342,210	P	AAC	1/1/2008	2/28/2011	68
Runway 17-35	RW 17-35	RUNWAY	6210	207	100	20,785	P	AAC	1/1/2008	2/28/2011	4
Runway 8-26	RW 8-26	RUNWAY	6105	4,000	75	300,450	S	AAC	1/1/1977	2/28/2011	80
Taxiway Alpha	TW A	TAXIWAY	105	2,020	35	71,280	P	AC	1/1/1977	2/28/2011	20
Taxiway Alpha	TW A	TAXIWAY	110	145	35	6,990	P	AC	1/1/1977	2/28/2011	1
Taxiway Alpha	TW A	TAXIWAY	112	215	50	11,600	P	AAC	1/1/1977	2/28/2011	2
Taxiway Bravo	TW B	TAXIWAY	205	630	40	26,680	P	AAC	1/1/1977	2/28/2011	7
Taxiway Bravo	TW B	TAXIWAY	210	390	40	20,570	P	AAC	1/1/1977	2/28/2011	4
Taxiway Bravo	TW B	TAXIWAY	204	640	22	17,500	P	PCC	1/1/1992	2/28/2011	6
Taxiway Charlie	TW C	TAXIWAY	305	1,160	50	58,430	P	AAC	1/1/1990	2/28/2011	12
Taxiway Delta	TW D	TAXIWAY	405	2,160	45	104,640	P	AAC	1/1/1984	2/28/2011	21
Taxiway Echo	TW E	TAXIWAY	505	2,060	35	78,240	P	AAC	1/1/1990	2/28/2011	22
Taxiway Foxtrot	TW F	TAXIWAY	605	1,040	40	41,690	P	AC	1/1/1984	2/28/2011	10
Taxiway Foxtrot	TW F	TAXIWAY	650	130	40	6,270	P	AC	1/1/1984	2/28/2011	1

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

01/01/1992

IMPORTED

OVERLAY

Work History Report

1 of 5

Pavement Database:

Branch: AP CENTER (CENTER APRON) Network: OMN Section: 4204 Surface: AC L.C.D.: 07/31/2008 Use: APRON Rank: T Length: 285.00 Ft Width: 22.00 Ft True Area: 5.930.00 SqF Work Work Work Thickness Major

Work Work Code Description Cost Inickness Major Comments

07/31/2008 INITIAL Initial Construction \$0 0.00 True

 Network:
 OMN
 Branch:
 AP CENTER
 (CENTER APRON)
 Section:
 4205
 Surface:
 AAC

 L.C.D.:
 01/01/1992
 Use:
 APRON
 Rank:
 T Length:
 450.00 Ft
 Width:
 200.00 Ft
 True Area:
 91.080.00 SqF

Work Work Work Thickness Maior Comments Cost Date Code Description (in) M&R 01/01/1992 **IMPORTED OVERLAY** True 1992: AC OVERLAY 01/01/1979 **IMPORTED BUILT** 1.00 True 1979: 1" TYPE S1 AC OVERLAY PLACED ON EXISTING AC ON BASE COURSE

 Network:
 OMN
 Branch:
 AP CENTER
 (CENTER APRON)
 Section:
 4210
 Surface:
 AAC

 L.C.D.:
 01/01/1992
 Use:
 APRON
 Rank:
 P Length:
 180.00
 Ft
 Width:
 205.00
 Ft
 True Area:
 43.450.00
 SqF

Work Work Work Thickness Major Comments Cost Code M&R Date Description (in) 01/01/1992 **IMPORTED OVERLAY** 1992: AC OVERLAY True 01/01/1979 **IMPORTED** 1.00 1979: 1" TYPE S1 AC OVERLAY PLACED **BUILT** True ON EXISTING AC AND BASE COURSE

 Network:
 OMN
 Branch:
 AP E
 (EAST APRON - HANGAR AREA)
 Section:
 4305
 Surface:
 AC

 L.C.D.:
 01/01/1984
 Use:
 APRON
 Rank:
 P Length:
 360.00
 Ft
 Width:
 133.00
 Ft
 True Area:
 56.770.00
 SqF

Work Work Work Thickness Maior Comments Cost (in) Date Code Description M&R 01/01/1984 **IMPORTED BUILT** True ESTIMATE 1984 AC PAVEMENT 01/01/1984 **IMPORTED OVERLAY** True SOIL: SP

 Network:
 OMN
 Branch:
 AP T HANG
 (AP T HANG)
 Section:
 4410
 Surface:
 AC

 L.C.D.:
 01/01/2005
 Use:
 APRON
 Rank:
 P Length:
 2,000.00
 Ft
 Width:
 25.00
 Ft
 True Area:
 53,360.00
 SqF

Work Work Thickness Work Major Comments Cost Date M&R Code Description (in) 01/01/2005 NC-AC New Construction - AC \$0 0.00 True

 Network:
 OMN
 Branch:
 AP W
 (WEST APRON)
 Section:
 4102
 Surface:
 AC

 L.C.D.:
 01/01/1992
 Use:
 APRON
 Rank:
 P Length:
 670.00 Ft
 Width:
 34.00 Ft
 True Area:
 22.250.00 SqF

Work Work Work Thickness Major Comments Cost Date Description Code (in) M&R 01/01/1992 IMPORTED **BUILT** 2 00 True 1992: 2" P-401 ON 6" RECLAIMED PAVEMENT BASE

 Network:
 OMN
 Branch:
 AP W
 (WEST APRON)
 Section:
 4105
 Surface:
 AC

 L.C.D.:
 01/01/1992
 Use:
 APRON
 Rank:
 T Length:
 835.00
 Ft
 Width:
 180.00
 Ft
 True Area:
 164.590.00
 SaF

SOIL: SP

True

Work Work Work Major Thickness Comments Cost Date Code Description M&R (in) 01/01/1992 **IMPORTED BUILT** 1992: SEAL ON 2" P-401 ON 6" 2.00 True RECLAIMED PAVEMENT BASE **IMPORTED** SOIL: SP 01/01/1992 **OVERLAY**

Network: OMN Branch: INT TWD/C (INTERSECTION TWD & TWC) Section: 805 Surface: AAC L.C.D.: 01/01/1990 Use: TAXIWAY Rank: P Length: 120.00 Ft Width: 35.00 Ft True Area: 4.010.00 SqF

Work Work Work Thickness Major Comments Cost M&R Date Code Description (in) 01/01/1990 INITIAL **Initial Construction** \$0 0.00 True

Branch: RW 17-35

Network: OMN

01/01/1943

IMPORTED

BUILT

Work History Report

Pavement Database:

(RUNWAY 17-35) Section: 6205 Surface: AAC

2 of 5

True 1943: 1" BIT SURFACE ON 6" LIMEROCK

1.00

L.C.D. : 01/0	1/2008 Use : Rl	JNWAY Rank: P Length:	3.420.00 Ft	Width:	100.	00 Ft
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2008	ML-OL	Mill and Overlay	\$0	0.00	True	
01/01/1983	IMPORTED	OVERLAY		2.50		1983: 2.5" P-401 ON 1" - 3.5" LEVELING COURSE
01/01/1983	IMPORTED	OVERLAY			True	N RANDOM LOCATIONS AND OFTEN TIMES HAD CRACKING OCCURING
01/01/1983	IMPORTED	OVERLAY		0.00	True	WITH THEM. THIS PAVEMENT HAD VERY UNUSUAL DISTRESS THAT WAS RECORDED AS
01/01/1943	IMPORTED	BUILT		1.00	True	SWELL. T 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BASE
Network: O	MN Br 1/2008 Use : Rl	anch: RW 17-35 (RUNWA	•	180 141		ction: 6210 Surface: AAC
			207.00 Ft	Width:		00 Ft
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2008	ML-OL	Mill and Overlay	\$0	0.00	True	ACCUME, 4072 AC OVERLAY
01/01/1973 01/01/1943	IMPORTED IMPORTED	OVERLAY BUILT		1.00		ASSUME: 1973 AC OVERLAY 1943: 1" DOUBLE BITUMINOUS
						SURFACE ON 6" LIME ROCK BASE
Network: O L.C.D.: 01/01	MN Br 1/1977 Use : RU	anch: RW 8-26 (RUNWA) JNWAY Rank: S Length:	Y 8-26) 4.000.00 Ft	Width:		ction: 6105 Surface: AAC 00 Ft True Area: 300.450.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1977	IMPORTED	OVERLAY				1977: VARIABLE THICKNESS TYPE 1
01/01/1943	IMPORTED	BUILT		1.00	True	ASPHALT CONCRETE 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BASE
Network: O		anch: TW A (TAXIWA	-			ction: 105 Surface: AC
L.C.D. : 01/0 ²	1/1977 Use : TA		2,020.00 Ft	Width:	35.	00 Ft
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1977	IMPORTED	BUILT		1.00		1977: 1" TYPE S-1 ASPHALT CONCRETE
01/01/1977	IMPORTED	OVERLAY				ON 6" P-211 SOIL: SP
Network: O	MNI Br	anch: TW A (TAXIWA	V Δ)		Sa	ction: 110 Surface: AC
	1/1977 Use : TA	•	145.00 Ft	Width:		00 Ft True Area: 6.990.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1977	IMPORTED	OVERLAY			True	SOIL: SP
01/01/1977	IMPORTED	BUILT		1.00		1977: 1" TYPE S-1 ASPHALT CONCRETE ON 6" P-211
Network: O	MN Br : 1/1977 Use : TA	anch: TW A (TAXIWA XIWAY R ank: P Le ngth:	Y A) 215.00 Ft	Width:	Se	ction: 112 Surface: AAC 00 Ft True Area: 11.600.00 SqF
Work	Work	Work	Cost	Thickness	Major	Comments
Date	Code	Description	CUSI	(in)	M&R	
01/01/1977	IMPORTED	OVERLAY			True	1977: AC OVERLAY

Work History Report

3 of 5

Pavement Database:

		raven	nent Database:		
Network: O L.C.D. : 01/01	MN B i //1992 Use: Ta	ranch: TW B (TAXIWA AXIWAY Rank: P Length:	YB) 640.00 Ft	Width:	Section: 204 Surface: PCC 22.00 Ft True Area: 17.500.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1992	INITIAL	Initial Construction	\$0	0.00	True
Network: O L.C.D.: 01/01	MN B i /1977 Use: Ta	ranch: TW B (TAXIWA AXIWAY Rank: P Length:	•	Width:	Section: 205 Surface: AAC 40.00 Ft True Area: 26.680.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1977 01/01/1977	IMPORTED IMPORTED	OVERLAY OVERLAY			True SOIL: SP True 1977: TYPE 1 ASPHALT CONCRETE (NO THICNESS INFO)
01/01/1943	IMPORTED	BUILT		1.00	True 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BASE
Network: O L.C.D. : 01/01	MN B i 1/1977 Use: Ta	ranch: TW B (TAXIWA AXIWAY Rank: P Length:	YB) 390.00 Ft	Width:	Section: 210 Surface: AAC 40.00 Ft True Area: 20.570.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1977	IMPORTED	OVERLAY			True 1977: AC OVERLAY (NO THICKNESS NFO)
01/01/1943	IMPORTED	BUILT		1.00	True 1943: 1" AC SURFACE ON 6" LIME ROCK BASE
Network: O L.C.D. : 01/01	MN B i //1990 Use: Ta	ranch: TW C (TAXIWA AXIWAY Rank: P Length:	•	Width:	Section: 305 Surface: AAC 50.00 Ft True Area: 58.430.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1990	IMPORTED	OVERLAY		6.00	True ESISTING 6" AC ON 6" CRUSHED SHELL BASE
01/01/1990	IMPORTED	BUILT		2.00	True 1990: 2" P-401 OVERLAY PLACED ON
Network : O L.C.D. : 01/01	MN Bi /1984 Use: Ta	ranch: TW D (TAXIWA AXIWAY Rank: P Length:	Y D) 2.160.00 Ft	Width:	Section: 405 Surface: AAC 45.00 Ft True Area: 104.640.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1984 01/01/1984 01/01/1943	IMPORTED IMPORTED IMPORTED	OVERLAY OVERLAY BUILT		3.00 1.00	True SOIL: SP True 1984: 3" RECYCLED HOT MIX AC True 1943: 1" BITUMINOUS SURFACE ON 6" LIME ROCK BASE
Network: O L.C.D.: 01/01	MN B i //1990 Use: Ta	ranch: TW E (TAXIWA AXIWAY Rank: P Length:	YE) 2.060.00 Ft	Width:	Section: 505 Surface: AAC 35.00 Ft True Area: 78.240.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1990 01/01/1990	IMPORTED IMPORTED	OVERLAY OVERLAY		2.00	True 1990: 2" P-401 OVERLAY True SOIL: SP
01/01/1943	IMPORTED	BUILT		4.50	True 1943: 4.5" AC ON 5" TAN SHELL ON 6" DARK GREY SAND
Network : O L.C.D. : 01/01	MN B /1984 Use: T	ranch: TW F (TAXIWA AXIWAY Rank : P Length :	Y F) 1.040.00 Ft	Width:	Section: 605 Surface: AC 40.00 Ft True Area: 41.690.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1984	IMPORTED	BUILT		2.00	True 1984: 2" RECYCLED HOT MIX ON 6" LIME ROCK BASE ON 2" WORK
01/01/1984	IMPORTED	OVERLAY			PLATFORM True SOIL: SP

Work History Report

4 of 5

Pavement Database:

Network: OMN Branch: TW F (TAXIWAY F)
L.C.D.: 01/01/1984 Use: TAXIWAY Rank: P Length:

Rank: P Length: 130.00 Ft Width:

Section: 650

Surface: AC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1984 01/01/1984	IMPORTED IMPORTED	OVERLAY BUILT		2.00	True	SOIL: SP 1984: 2" RECYCLED HOT MIX ON 6" LIME ROCK BASE ON 2" WORK PLATFORM

Work History Report

5 of 5

Pavement Database:

Summary:

Work Description	Section Count	Area Total (SqFt)	Thi ckness Avg (in)	Thickness STD (in)
BUILT	18	1,467,975.00	1.50	.90
Initial Construction	3	27,440.00	.00	.00
Mill and Overlay	2	362,995.00	.00	.00
New Construction - AC	1	53,360.00	.00	
OVERLAY	23	2,361,955.00	2.70	2.17

STD = Standard Deviation

APPENDIX B

2011 CONDITION MAP PAVEMENT CONDITION INDEX TABLE




Table B-1: Pavement Condition Index

Branch Name	Branch ID	Branch Use	Section ID	True Area (ft²)	Section Rank	Surface Type	Total Samples Inspected	Total Samples	PCI	PCI Category
Center Apron	AP CENTER	APRON	4210	43,450	P	AAC	1	9	64	Fair
Center Apron	AP CENTER	APRON	4205	91,080	T	AAC	3	18	42	Poor
Center Apron	AP CENTER	APRON	4204	5,930	T	AC	1	2	59	Fair
East Apron - Hangar Area	AP E	APRON	4305	56,770	P	AC	3	12	26	Very Poor
Apron at T-Hangars	AP T HANG	APRON	4410	53,360	P	AC	2	10	85	Satisfactory
West Apron	AP W	APRON	4102	22,250	P	AC	1	7	20	Serious
West Apron	AP W	APRON	4105	164,590	T	AC	4	38	67	Fair
Intersection of TW D and TW C	INT TWD/C	TAXIWAY	805	4,010	P	AAC	1	1	23	Serious
Runway 17-35	RW 17-35	RUNWAY	6205	342,210	P	AAC	14	68	95	Good
Runway 17-35	RW 17-35	RUNWAY	6210	20,785	P	AAC	1	4	91	Good
Runway 8-26	RW 8-26	RUNWAY	6105	300,450	S	AAC	16	80	67	Fair
Taxiway Alpha	TW A	TAXIWAY	105	71,280	P	AC	4	20	67	Fair
Taxiway Alpha	TW A	TAXIWAY	110	6,990	P	AC	1	1	59	Fair
Taxiway Alpha	TW A	TAXIWAY	112	11,600	P	AAC	1	2	69	Fair
Taxiway Bravo	TW B	TAXIWAY	205	26,680	P	AAC	2	7	56	Fair
Taxiway Bravo	TW B	TAXIWAY	210	20,570	P	AAC	1	4	63	Fair
Taxiway Bravo	TW B	TAXIWAY	204	17,500	P	PCC	1	6	14	Serious
Taxiway Charlie	TW C	TAXIWAY	305	58,430	P	AAC	3	12	24	Serious
Taxiway Delta	TW D	TAXIWAY	405	104,640	P	AAC	6	21	27	Very Poor
Taxiway Echo	TW E	TAXIWAY	505	78,240	P	AAC	4	22	43	Poor
Taxiway Foxtrot	TW F	TAXIWAY	605	41,690	P	AC	2	10	59	Fair
Taxiway Foxtrot	TW F	TAXIWAY	650	6,270	P	AC	1	1	58	Fair

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

APPENDIX C

BRANCH CONDITION REPORT SECTION CONDITION REPORT

Date: 5 /9/2011

Branch Condition Report

1 of 2

Pavement Database: NetworkID: OMN

Number of Sum Section Avg Section PCI Weighted True Area Average **Branch ID** Use Average PCI Sections Length Width Standard (SqFt) PCI (Ft) (Ft) Deviation AP CENTER (CENTER APRON) 3 915.00 142.33 140,460.00 **APRON** 9.42 55.00 49.52 AP E (EAST APRON - HANGAR 1 360.00 133.00 56,770.00 **APRON** 26.00 0.00 26.00 AREA) AP THANG (AP THANG) 2,000.00 53,360.00 APRON 0.00 85.00 1 25.00 85.00 AP W (WEST APRON) APRON 2 1,505.00 107.00 186,840.00 43.50 23.50 61.40 INT TWD/C (INTERSECTION TWD & 1 120.00 35.00 4,010.00 **TAXIWAY** 23.00 0.00 23.00 TWC) RW 17-35 (RUNWAY 17-35) 2 3,627.00 100.00 362,995.00 RUNWAY 93.00 2.00 94.77 RW 8-26 (RUNWAY 8-26) 4,000.00 75.00 300,450.00 RUNWAY 0.00 67.00 1 67.00 TW A (TAXIWAY A) 3 2,380.00 40.00 89,870.00 **TAXIWAY** 65.00 4.32 66.64 1,660.00 64,750.00 **TAXIWAY** 46.87 TW B (TAXIWAY B) 3 34.00 44.33 21.64 TW C (TAXIWAY C) 50.00 58,430.00 **TAXIWAY** 24.00 0.00 1 1,160.00 24.00 TW D (TAXIWAY D) **TAXIWAY** 1 2,160.00 45.00 104,640.00 27.00 0.00 27.00 TW E (TAXIWAY E) **TAXIWAY** 2,060.00 35.00 0.00 43.00 1 78,240.00 43.00 TW F (TAXIWAY F) 2 1,170.00 40.00 47,960.00 **TAXIWAY** 58.50 0.50 58.87

Branch Condition Report

Pavement Database:

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	7	437,430.00	51.86	21.73	55.87
RUNWAY	3	663,445.00	84.33	12.36	82.19
TAXIWAY	12	447,900.00	46.83	18.80	43.61
All	22	1,548,775.00	53.55	22.77	63.60

STD = Standard Deviation

Date: 5 /9/2011

Section Condition Report

Pavement Database:

NetworkID: OMN

Last Age Use PCI **Branch ID** Section ID Last **Surface** Rank Lanes **True Area** Inspection Αt Const. (SqFt) **Date** Inspection **Date** AP CENTER (CENTER APRON) **APRON** Т 5,930.00 02/28/2011 4204 07/31/2008 AC 0 3 59.00 AP CENTER (CENTER APRON) 4205 01/01/1992 AAC **APRON** Т 91,080.00 02/28/2011 19 42.00 AP CENTER (CENTER APRON) 4210 01/01/1992 AAC **APRON** Р 0 43,450.00 02/28/2011 19 64.00 AP E (EAST APRON - HANGAR Ρ 56,770.00 02/28/2011 4305 01/01/1984 AC **APRON** 0 27 26.00 AREA) AP THANG (APTHANG) 4410 01/01/2005 AC **APRON** Р 0 53,360.00 02/28/2011 6 85.00 AP W (WEST APRON) 4102 01/01/1992 AC **APRON** Ρ 0 22,250.00 02/28/2011 19 20.00 AP W (WEST APRON) 4105 01/01/1992 AC **APRON** Т 164,590.00 02/28/2011 67.00 19 INT TWD/C (INTERSECTION TWD Ρ 805 01/01/1990 AAC **TAXIWAY** 0 4,010.00 02/28/2011 21 23.00 & TWC) RW 17-35 (RUNWAY 17-35) 6205 01/01/2008 AAC **RUNWAY** Ρ 342,210.00 02/28/2011 3 95.00 RW 17-35 (RUNWAY 17-35) AAC **RUNWAY** Ρ 20.785.00 02/28/2011 6210 01/01/2008 3 91.00 RW 8-26 (RUNWAY 8-26) 6105 01/01/1977 AAC **RUNWAY** S 300,450.00 02/28/2011 67.00 34 TW A (TAXIWAY A) 01/01/1977 **TAXIWAY** Р 71,280.00 02/28/2011 105 AC 0 34 67.00 TW A (TAXIWAY A) Ρ 110 01/01/1977 AC **TAXIWAY** 0 6,990.00 02/28/2011 34 59.00 TW A (TAXIWAY A) Ρ 112 01/01/1977 AAC **TAXIWAY** 0 11,600.00 02/28/2011 34 69.00 TW B (TAXIWAY B) Р 204 01/01/1992 **PCC TAXIWAY** 0 17,500.00 02/28/2011 19 14.00 TWB (TAXIWAYB) 01/01/1977 AAC **TAXIWAY** Ρ 0 26,680.00 02/28/2011 205 34 56.00 TWB (TAXIWAYB) Р 20,570.00 02/28/2011 210 01/01/1977 AAC **TAXIWAY** 0 34 63.00 TW C (TAXIWAY C) **TAXIWAY** Р 58.430.00 02/28/2011 305 01/01/1990 AAC 0 24.00 21 TW D (TAXIWAY D) 405 01/01/1984 AAC **TAXIWAY** Ρ 0 104,640.00 02/28/2011 27 27.00 TW E (TAXIWAY E) 505 01/01/1990 AAC **TAXIWAY** Ρ 0 78,240.00 02/28/2011 21 43.00 TW F (TAXIWAY F) **TAXIWAY** Ρ 01/01/1984 AC 0 41,690.00 02/28/2011 59.00 605 27 TW F (TAXIWAY F) Ρ 01/01/1984 AC **TAXIWAY** 0 58.00 650 6,270.00 02/28/2011 27

1 of 2

Date: 5 /9/2011

Section Condition Report

Pavement Database:

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
03-05	3.00	368,925.00	3	81.67	16.11	94.20
06-10	6.00	53,360.00	1	85.00	0.00	85.00
16-20	19.00	338,870.00	5	41.40	21.80	54.07
21-25	21.00	140,680.00	3	30.00	9.20	34.54
26-30	27.00	209,370.00	4	42.50	16.01	34.03
31-35	34.00	437,570.00	6	63.50	4.68	66.07
AII	22.05	1,548,775.00	22	53.55	22.77	63.60

2 of 2


APPENDIX D

PAVEMENT CONDITION PREDICTION TABLE PREDICTED PCI BY PAVEMENT USE GRAPH

Table D-1: Pavement Condition Prediction

D I. N.	Dk ID	Section	Current					PCI Fo	recast				
Branch Name	Branch ID	ID	PCI	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020
Center Apron	AP CENTER	4204	59	58	55	52	49	46	43	40	37	34	31
Center Apron	AP CENTER	4205	42	41	38	34	30	26	22	17	13	9	5
Center Apron	AP CENTER	4210	64	63	62	60	58	56	54	52	49	46	44
East Apron - Hangar Area	AP E	4305	26	25	23	20	18	15	12	9	6	3	0
Apron at T-Hangars	AP T HANG	4410	85	84	83	81	79	78	76	75	73	72	71
West Apron	AP W	4102	20	19	16	14	11	8	5	1	0	0	0
West Apron	AP W	4105	67	67	65	64	63	62	61	60	59	58	57
Intersection of TW D and TW C	INT TWD/C	805	23	22	21	19	17	15	14	12	10	8	7
Runway 17-35	RW 17-35	6205	95	94	90	87	84	81	78	76	74	72	70
Runway 17-35	RW 17-35	6210	91	90	87	84	81	78	76	74	72	70	68
Runway 8-26	RW 8-26	6105	67	66	65	64	63	61	60	59	59	58	57
Taxiway Alpha	TW A	105	67	67	65	64	63	62	61	60	59	58	57
Taxiway Alpha	TW A	110	59	59	58	57	56	55	54	53	52	51	49
Taxiway Alpha	TW A	112	69	69	68	67	67	66	66	65	64	64	63
Taxiway Bravo	TW B	204	14	14	13	12	11	10	9	8	7	5	4
Taxiway Bravo	TW B	205	56	56	54	52	50	49	47	45	43	41	40
Taxiway Bravo	TW B	210	63	63	62	61	60	59	58	57	56	54	52
Taxiway Charlie	TW C	305	24	23	22	20	18	16	15	13	11	9	8
Taxiway Delta	TW D	405	27	26	25	23	21	19	18	16	14	12	11
Taxiway Echo	TW E	505	43	42	41	39	37	35	34	32	30	28	27
Taxiway Foxtrot	TW F	605	59	59	58	57	56	55	54	53	52	51	49
Taxiway Foxtrot	TW F	650	58	58	57	56	55	54	53	52	51	49	48

Figure D-1: Predicted PCI by Pavement Use



APPENDIX E

YEAR 1 MAINTENANCE ACTIVITIES TABLE

Table E-1: Year 1 Maintenance Activities

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Runway 17-35	RW 17-35	6210	WEATH/RAVEL	L	Surface Seal - Rejuvenating	415.70	SqFt	\$0.40	\$166.28
Runway 17-35	RW 17-35	6205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	10,021.80	SqFt	\$0.40	\$4,008.77
Runway 17-35	RW 17-35	6205	WEATH/RAVEL	M	Surface Seal - Coat Tar	73.30	SqFt	\$0.40	\$29.33
Runway 8-26	RW 8-26	6105	L & T CR	M	Crack Sealing - AC	1,111.60	Ft	\$2.25	\$2,501.21
Runway 8-26	RW 8-26	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	186,779.50	SqFt	\$0.40	\$74,712.42
Runway 8-26	RW 8-26	6105	WEATH/RAVEL	M	Surface Seal - Coat Tar	21,782.60	SqFt	\$0.40	\$8,713.11
Apron at T-Hangar	AP T HANG	4410	WEATH/RAVEL	L	Surface Seal - Rejuvenating	10,672.00	SqFt	\$0.40	\$4,268.84
West Apron	AP W	4105	L & T CR	M	Crack Sealing - AC	2,103.10	Ft	\$2.25	\$4,731.95
West Apron	AP W	4105	OIL SPILLAGE	N	Patching - AC Shallow	461.90	SqFt	\$2.90	\$1,339.43
West Apron	AP W	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	121,613.40	SqFt	\$0.40	\$48,645.75
Taxiway Alpha	TW A	112	WEATH/RAVEL	L	Surface Seal - Rejuvenating	6,026.00	SqFt	\$0.40	\$2,410.41
Taxiway Alpha	TW A	105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	56,144.30	SqFt	\$0.40	\$22,457.91
Taxiway Alpha	TW A	105	WEATH/RAVEL	M	Surface Seal - Coat Tar	935.70	SqFt	\$0.40	\$374.30
								Total =	\$174,359.71

APPENDIX F

MAJOR M&R PLAN BY YEAR UNDER UNLIMITED FUNDING SCENARIO TABLE


Table F-1: Major M&R Plan by Year under Unlimited Funding Scenario

Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	N	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	East Apron	4305	AC	56,770	\$	1,054,218.83	25	Reconstruction	100
2011	Center Apron	4210	AAC	43,450	\$	123,658.70	63	Mill and Overlay	100
2011	Center Apron	4205	AAC	91,080	\$	693,119.14	41	Mill and Overlay	100
2011	Center Apron	4204	AC	5,930	\$	26,483.39	58	Mill and Overlay	100
2011	West Apron	4102	AC	22,250	\$	413,182.47	19	Reconstruction	100
2011	Intersection of TW D and TW C	805	AAC	4,010	\$	74,465.70	22	Reconstruction	100
2011	Taxiway Foxtrot	650	AC	6,270	\$	28,001.83	58	Mill and Overlay	100
2011	Taxiway Foxtrot	605	AC	41,690	\$	169,803.42	59	Mill and Overlay	100
2011	Taxiway Echo	505	AAC	78,240	\$	595,406.69	42	Mill and Overlay	100
2011	Taxiway Delta	405	AAC	104,640	\$	1,943,164.67	26	Reconstruction	100
2011	Taxiway Charlie	305	AAC	58,430	\$	1,085,045.03	23	Reconstruction	100
2011	Taxiway Bravo	210	AAC	20,570	\$	58,542.22	63	Mill and Overlay	100
2011	Taxiway Bravo	205	AAC	26,680	\$	140,123.42	56	Mill and Overlay	100
2011	Taxiway Bravo	204	PCC	17,500	\$	324,974.98	14	Reconstruction	100
2011	Taxiway Alpha	110	AC	6,990	\$	28,470.28	59	Mill and Overlay	100
2013	Runway 8-26	6105	AAC	300,450	\$	818,543.27	64	Mill and Overlay	100
2013	West Apron	4105	AC	164,590	\$	448,407.51	64	Mill and Overlay	100
2013	Taxiway Alpha	105	AC	71,280	\$	194,194.59	64	Mill and Overlay	100
2018	Taxiway Alpha	112	AAC	11,600	\$	36,636.46	64	Mill and Overlay	100
				Total		\$8,256,442.60	47		100

^{*} Costs are adjusted for inflation.

APPENDIX G

10-YEAR M&R MAP



APPENDIX H

PHOTOGRAPHS



Apron, Section 4105, Sample Unit 205 – Low and medium severity (48) Longitudinal and Transverse Cracking, (49) Oil Spillage, low severity (52) Weathering and Raveling



Apron, Section 4105, Sample Unit 205 – Low and medium severity (48) Longitudinal and Transverse Cracking, (49) Oil Spillage, low severity (52) Weathering and Raveling



Apron, Section 4305, Sample Unit 104 – Low severity (48) Longitudinal and Transverse Cracking, low severity (43) Block Cracking, medium severity (52) Weathering and Raveling



Apron, Section 4205, Sample Unit 111 – Low severity (48) Longitudinal and Transverse Cracking, low severity (43) Block Cracking, medium severity (52) Weathering and Raveling



Runway 17-35, Section 6205, Sample Unit 164 – Low severity (52) Weathering and Raveling



Runway 17-35, Section 6205, Sample Unit 164 – Low severity (52) Weathering and Raveling



Runway 8-26, Section 6105, Sample Unit 103 – Low severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Weathering and Raveling



Runway 8-26, Section 6105, Sample Unit 117 – Medium severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Weathering and Raveling



Taxiway Echo, Section 505, Sample Unit 107 – Low and medium severity (43) Block Cracking, low severity (52) Weathering and Raveling



Taxiway Echo, Section 505, Sample Unit 107 - Low and medium severity (43) Block Cracking, low severity (52) Weathering and Raveling



Taxiway Echo, Section 505, Sample Unit 101 - Low and medium severity (43) Block Cracking, low severity (52) Weathering and Raveling



Taxiway Echo, Section 505, Sample Unit 101 – Low and medium severity (43) Block Cracking, low severity (52) Weathering and Raveling



Taxiway Charlie, Section 805, Sample Unit 100 – Low and medium severity (43) Block Cracking, medium severity (48) Longitudinal and Transverse Cracking, medium severity (52) Weathering and Raveling, medium severity (56) Swell



Taxiway Charlie, Section 805, Sample Unit 100 – Low and medium severity (43) Block Cracking, medium severity (48) Longitudinal and Transverse Cracking, medium severity (52) Weathering and Raveling, medium severity (56) Swell

APPENDIX I

PCI RE-INSPECTION REPORT

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: AP CENTER Name: CENTER APRON Use: APRON Area: 140,460.00SqFt

Section: of 3 To: -4204 From: -Last Const.: 7/31/2008

Family: DEFAULT Surface: AC Zone: Category: Rank: T Width: 22.00Ft

Length: Area: 5,930.00SqFt 285.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 2 Surveyed: 1

Conditions: PCI:59.00 | Inspection Comments: KHA

Sample Number: 115 Type: R Sample Comments:	Area:	3,300.00SqFt		PCI = 59
48 LONGITUDINAL/TRANSVERSE CRACKING	L	317.00	Ft	Comments:
43 BLOCK CRACKING	L	60.00	SqFt	Comments:
52 WEATHERING/RAVELING	M	330.00	SqFt	Comments:
52 WEATHERING/RAVELING	L	1,400.00	SqFt	Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: AP CENTER Name: CENTER APRON Use: APRON Area: 140,460.00SqFt

Section: 4205 of 3 From: - To: - Last Const.: 1/1/1992

200.00Ft

Surface: AAC Family: FDOT-RL-AP-AAC Zone: Category: Rank: T

Area: 91,080.00SqFt Length: 450.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/28/2011 Total Samples: 18 Surveyed: 3

Conditions: PCI:42.00 | Inspection Comments: KHA

Sample Number: 111 Sample Comments:	Type: R	Area:	5,000.00SqFt		PCI = 39
43 BLOCK CRACKING		L	4,000.00	SqFt	Comments:
48 LONGITUDINAL/TR	ANSVERSE CRACKING	L	16.00	Ft	Comments:
52 WEATHERING/RAVE	LING	M	4,000.00	SqFt	Comments:

Sample Number: 205	Type: R	Area:	5,000.00SqFt	PCI = 48
Sample Comments:				
43 BLOCK CRACKING		Н	536.00	SqFt Comments:
48 LONGITUDINAL/TRA	ANSVERSE CRACKING	L	75.00	Ft Comments:
52 WEATHERING/RAVEI	LING	L	4,999.96	SqFt Comments:

- 1	Sample Number: 209	Type: R	Area:		5,000.00SqFt		PC1 = 38
,	Sample Comments:						
	43 BLOCK CRACKING		I		1,250.00	SqFt	Comments:
	43 BLOCK CRACKING		I		260.00	SqFt	Comments:
	52 WEATHERING/RAVEL	ING	I	1	4,000.00	SqFt	Comments:
	52 WEATHERING/RAVEL	ING	I	I	50.00	SqFt	Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: AP CENTER Name: CENTER APRON Use: APRON Area: 140,460.00SqFt

Section: of 3 To: -4210 From: -Last Const.: 1/1/1992

Surface: Family: FDOT-RL-AP-AAC Zone: Category: Rank: P AAC Width: 205.00Ft

Length: 180.00Ft Area: 43,450.00SqFt Shoulder: Lanes: 0

Street Type: Grade: 0.00

Section Comments:

Total Samples: 9 Surveyed: 1 Last Insp. Date2/28/2011

Conditions: PCI:64.00 | Inspection Comments: KHA

PCI = 64Sample Number: 102 Type: R Area: 5,450.00SqFt

Sample Comments: 43 BLOCK CRACKING Μ 300.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 247.00 Ft Comments: 52 WEATHERING/RAVELING L 5,000.00 SqFt Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: AP E Name: EAST APRON - HANGAR AREA Use: APRON Area: 56,770.00SqFt

Section: 4305 of 1 From: - To: - Last Const.: 1/1/1984

133.00Ft

Surface: AC Family: FDOT-RL-AP-AC Zone: Category: Rank: P

Area: 56,770.00SqFt Length: 360.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/28/2011 Total Samples: 12 Surveyed: 3

Conditions: PCI:26.00 | Inspection Comments: KHA

Sample Number: 102 Sample Comments:	Type: R	Area:	5,820.00SqFt	PCI = 5	
41 ALLIGATOR CRACKIN	IG	Н	400.00	SqFt Comments:	
41 ALLIGATOR CRACKIN		M	252.00	SqFt Comments:	
50 PATCHING		L	18.00		
43 BLOCK CRACKING		L	5,819.95		
52 WEATHERING/RAVELI	NG	М	5,819.95	SqFt Comments:	
Sample Number: 104 Sample Comments:	Type: R	Area:	6,156.00SqFt	PCI = 38	
48 LONGITUDINAL/TRAN	ISVERSE CRACKING	L	338.00	Ft Comments:	
43 BLOCK CRACKING	.5.21.02 01110111110	L	300.00		
52 WEATHERING/RAVELI	NG	М	4,925.00	_	
Sample Number: 201 Sample Comments:	Type: R	Area:	5,400.00SqFt	PCI = 36	
52 WEATHERING/RAVELI	NC	М	4,320.00	SaFt Comments:	
48 LONGITUDINAL/TRAN		L	344.00	±	
43 BLOCK CRACKING		L	3,900.00		
45 DEPRESSION		L	16.00	_	
10 DITTEDSTON			10.00	541 COMMETTED	

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: AP T HANG Name: AP T HANG Use: APRON Area: 53,360.00SqFt

Section: 4410 of 1 From: - To: - Last Const.: 1/1/2005

25.00Ft

Surface: AC Family: FDOT-RL-AP-AC Zone: Category: Rank: P

Area: 53,360.00SqFt Length: 2,000.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 10 Surveyed: 2

Conditions: PCI:85.00 | Inspection Comments: KHA

Sample Number: 102 Type: R Area: 5,000.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 5.00 Ft Comments: 52 WEATHERING/RAVELING L 1,000.00 Sqft Comments:

Sample Number: 303 Type: R Area: 5,000.00SqFt PCI = 86

Sample Comments:

52 WEATHERING/RAVELING L 1,000.00 SqFt Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 186,840.00SqFt

Section: 4102 of 2 From: - To: - Last Const.: 1/1/1992

34.00Ft

Surface: AC Family: FDOT-RL-AP-AC Zone: Category: Rank: P

Area: 22,250.00SqFt Length: 670.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/28/2011 Total Samples: 7 Surveyed: 1

Conditions: PCI:20.00 | Inspection Comments: KHA

PCI = 20Sample Number: 101 Type: R Area: 3,365.00SqFt Sample Comments: 50 PATCHING L 140.00 SqFt Comments: 43 BLOCK CRACKING 3,300.00 SqFt Μ Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING М 12.00 Ft Comments:

52 WEATHERING/RAVELING M 3,300.00 Sqft Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 186,840.00SqFt

Section: 4105 of 2 From: - To: - Last Const.: 1/1/1992

180.00Ft

Surface: AC Family: FDOT-RL-AP-AC Zone: Category: Rank: T

Area: 164,590.00SqFt Length: 835.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 38 Surveyed: 4

Conditions: PCI:67.00 Inspection Comments: KHA	rveyeu. 4			
Sample Number: 102 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 67	
52 WEATHERING/RAVELING	L	4,999.96 S	SqFt Comments:	
49 OIL SPILLAGE	N	1.50 S	SqFt Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	388.00 F	Comments:	
Sample Number: 205 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 59	
52 WEATHERING/RAVELING	L	4,500.00 S	SqFt Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	M	200.00 F	Tt Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L			
49 OIL SPILLAGE	N	40.00 S	SqFt Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	M	30.00 F	Tt Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	20.00 F	Comments:	
Sample Number: 307 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 74	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	419.00 F	Comments:	
52 WEATHERING/RAVELING	L	1,000.00 S	SqFt Comments:	
Sample Number: 403 Type: R Sample Comments:	Area:	3,000.00SqFt	PCI = 67	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	12.00 F	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	312.00 F	Comments:	
52 WEATHERING/RAVELING	L	2,800.00 S	SqFt Comments:	

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: INT TWD/C Name: INTERSECTION TWD & TWC Use: TAXIWAY Area: 4,010.00SqFt

Section: 805 of 1 From: - To: - Last Const.: 1/1/1990

35.00Ft

Surface: AAC Family: FDOT-RL-TW-AAC Zone: Category: Rank: P

Area: 4,010.00SqFt Length: 120.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/28/2011 Total Samples: 1 Surveyed: 1

Conditions: PCI:23.00 | Inspection Comments: KHA

Sample Number: 100 Type: R Sample Comments:	Area:	4,010.00SqFt		PCI = 23
48 LONGITUDINAL/TRANSVERSE CRACKING	М	86.00	Ft	Comments:
43 BLOCK CRACKING	M	125.00	SqFt	Comments:
43 BLOCK CRACKING	L	2,000.00	SqFt	Comments:
56 SWELLING	M	308.00	SqFt	Comments:
52 WEATHERING/RAVELING	M	4,009.97	SqFt	Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Sample Comments:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT Name: RUNWAY 17-35 Use: RUNWAY Area: Branch: RW 17-35 362,995.00SqFt Section: 6205 of 2 From: -To: -Last Const.: 1/1/2008 Family: FDOT-RL-RW-AAC Zone: Category: Rank: P Surface: AAC 100.00Ft Area: 342,210.00SqFt Length: 3,420.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date2/28/2011 Total Samples: 68 Surveyed: 14 Conditions: PCI:95.00 | Inspection Comments: KHA Sample Number: 103 Type: R Area: 5,000.00SqFt PCI = 97Sample Comments: 52 WEATHERING/RAVELING L 50.00 SqFt Comments: Sample Number: 107 PCI = 96Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: Sample Number: 112 PCI = 84Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING \mathbf{L} 1,000.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 2.00 Ft Comments: Sample Number: 117 5,000.00SqFt PCI = 96Type: R Area: Sample Comments: 52 WEATHERING/RAVELING 100.00 SqFt \mathbf{L} Comments: Type: R PCI = 96Sample Number: 119 Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: PCI = 97Sample Number: 126 Area: 5,000.00SqFt Type: R Sample Comments: 52 WEATHERING/RAVELING 50.00 SqFt Comments: PCI = 96Sample Number: 131 Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING L 100.00 SqFt Comments: PCI = 95Sample Number: 135 Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING 50.00 SqFt Comments: Τ. 48 LONGITUDINAL/TRANSVERSE CRACKING 5.00 Ft Comments: T. PCI = 92Sample Number: 139 Type: R Area: 5,000.00SqFt Sample Comments: 52 WEATHERING/RAVELING Μ 15.00 SqFt Comments: 52 WEATHERING/RAVELING L 50.00 SqFt Comments: Sample Number: 142 Type: R Area: 5,000.00SqFt PCI = 96Sample Comments: 52 WEATHERING/RAVELING 100.00 SqFt L Comments: Sample Number: 152 PCI = 97Type: R Area: 5,000.00SqFt

FDOT

Report Generated Date: 5/9/2011

Site Name:

52 WEATHERING/RAVE	LING		L	50.00 SqFt	Comments:
Sample Number: 158	Type: R	Area:		5,000.00SqFt	PCI = 96
Sample Comments: 52 WEATHERING/RAVE	LING		L	100.00 SqFt	Comments:
Sample Number: 164	Type: R	Area:		5,000.00SqFt	PCI = 96
Sample Comments: 52 WEATHERING/RAVE	LING		L	100.00 SqFt	Comments:
Sample Number: 170	Type: R	Area:		5,000.00SqFt	PCI = 96
Sample Comments: 52 WEATHERING/RAVE	LING		L	100.00 SqFt	Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: RW 17-35 Name: RUNWAY 17-35 Use: RUNWAY Area: 362,995.00SqFt

Section: 6210 of 2 From: - To: - Last Const.: 1/1/2008

100.00Ft

Surface: AAC Family: FDOT-RL-RW-AAC Zone: Category: Rank: P

Area: 20,785.00SqFt Length: 207.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 4 Surveyed: 1

Conditions: PCI:91.00 | Inspection Comments: KHA

Sample Number: 146 Type: R Area: 5,000.00SqFt PCI = 91

Sample Comments:

52 WEATHERING/RAVELING L 100.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 50.00 Ft Comments:

FDOT

Report Generated Date: 5/9/2011 Site Name: Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT Name: RUNWAY 8-26 Use: RUNWAY Area: Branch: RW 8-26 300,450.00SqFt Section: 6105 of 1 From: -To: -Last Const.: 1/1/1977 Family: FDOT-RL-RW-AAC Zone: Surface: Category: Rank: S AAC Area: 300,450.00SqFt Length: 4,000.00Ft Width: 75.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date2/28/2011 Total Samples: 80 Surveyed: 16 Conditions: PCI:67.00 | Inspection Comments: KHA Sample Number: 103 Type: R Area: 3,750.00SqFt PCI = 39Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 3,280.00 Ft \mathbf{L} Comments: 52 WEATHERING/RAVELING 600.00 SqFt Μ Comments: 52 WEATHERING/RAVELING \mathbf{L} 2,400.00 SqFt Comments: PCI = 60Sample Number: 107 Type: R Area: 3,750.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 212.00 Ft Comments: 52 WEATHERING/RAVELING 3,500.00 SqFt \mathbf{L} Comments: 52 WEATHERING/RAVELING 500.00 SqFt Μ Comments: Sample Number: 112 Type: R PCI = 53Area: 3,750.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING Μ 100.00 Ft Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 45.00 Ft Comments: \mathbf{L} 52 WEATHERING/RAVELING L 2,800.00 SqFt Comments: 52 WEATHERING/RAVELING 750.00 SqFt Comments: Μ

Sample Number: 117 Type: R	Area:	3,750.00SqFt	PCI = 53	
Sample Comments:				
48 LONGITUDINAL/TRANSVERSE	CRACKING	L 254.00	Ft Comments:	
48 LONGITUDINAL/TRANSVERSE	CRACKING	M 30.00	Ft Comments:	
52 WEATHERING/RAVELING		M 750.00	SqFt Comments:	
52 WEATHERING/RAVELING		L 2,800.00	SqFt Comments:	
Sample Number: 120 Type: R	Area:	3,750.00SqFt	PCI = 66	

Sample Comments:			
48 LONGITUDINAL/TRANSVERSE CRACKING	L	129.00 Ft	Comments:
52 WEATHERING/RAVELING	M	250.00 SqFt	Comments:
52 WEATHERING/RAVELING	L	3,000.00 SqFt	Comments:

Sample Number: 124 T	Type: R	Area:	3,750.00SqFt	PCI = 65
Sample Comments:				
48 LONGITUDINAL/TRANSV	ERSE CRACKING	M	50.00	Ft Comments:
48 LONGITUDINAL/TRANSV	ERSE CRACKING	L	155.00	Ft Comments:
52 WEATHERING/RAVELING	;	L	3,200.00	SqFt Comments:

Sample Number: 131 Type: R	Area:	3,750.00SqFt	PCI = 70
Sample Comments:			
48 LONGITUDINAL/TRANSVERSE CRACKING	L	109.00 Ft	Comments:
52 WEATHERING/RAVELING	L	3,200.00 SqFt	Comments:

Sample Number: 136 Type: R Area: 3,750.00SqFt PCI = 69

Sample Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

48 LONGITUDINAL/TRANSVERSE CRACKING		L	223.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	3,749.97	SqFt	Comments:	
Sample Number: 140 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 79	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	144.00	Ft.	Comments:	
52 WEATHERING/RAVELING		L	1,000.00		Comments:	
					COMMICTION.	
Sample Number: 146 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 74	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	228.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	2,000.00	SqFt	Comments:	
Sample Number: 151 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 74	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	213.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	2,000.00	SqFt	Comments:	
Sample Number: 155 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 74	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	186.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	2,000.00	SqFt	Comments:	
Sample Number: 161 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 79	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	200.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	1,000.00		Comments:	
Sample Number: 166 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 47	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	80.00	Ft.	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		M	42.00		Comments:	
52 WEATHERING/RAVELING		L	3,499.97		Comments:	
52 WEATHERING/RAVELING		М	1,500.00		Comments:	
Sample Number: 172 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 79	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	171.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	1,000.00	SqFt	Comments:	
Sample Number: 177 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 81	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	173.00		Comments:	
52 WEATHERING/RAVELING		L	150.00	SqFt	Comments:	
				-		

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 89,870.00SqFt

Section: 105 of 3 From: - To: - Last Const.: 1/1/1977

Surface: AC Family: FDOT-RL-TW-AC Zone: Category: Rank: P
Area: 71,280.00SqFt Length: 2,020.00Ft Width: 35.00Ft

Area: 71,280.00SqFt Length: 2,020.00Ft V Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/28/2011 Total Samples: 20 Surveyed: 4

48 LONGITUDINAL/TRANSVERSE CRACKING

Conditions: PCI:67.00 | Inspection Comments: KHA

Sample Number: 101 Type: R Area: 3,500.008qFt PCI = 70

Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L

48 LONGITUDINAL/TRANSVERSE CRACKING L 186.00 Ft Comments: 52 WEATHERING/RAVELING L 3,000.00 SqFt Comments:

Sample Number: 107 Type: R Area: 3,500.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 322.00 Ft Comments: 52 WEATHERING/RAVELING L 3,000.00 Sqft Comments:

Sample Number: 113 Type: R Area: 3,500.00SqFt PCI = 70

Sample Number: 113 Type. R Area. 3,500.005qFt PCI = 70

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 305.00 Ft Comments: 52 WEATHERING/RAVELING L 3,000.00 SqFt Comments:

Sample Number: 119 Type: R Area: 4,735.00SqFt PCI = 63

Sample Comments:

43 BLOCK CRACKING L 260.00 SqFt Comments:

52 WEATHERING/RAVELING M 200.00 SqFt Comments: 52 WEATHERING/RAVELING L 3,000.00 SqFt Comments:

L

91.00 Ft

Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TWA Name: TAXIWAY A Use: TAXIWAY Area: 89,870.00SqFt

Section: 110 of 3 From: - To: - Last Const.: 1/1/1977

35.00Ft

Surface: AC Family: FDOT-RL-TW-AC Zone: Category: Rank: P

Area: 6,990.00SqFt Length: 145.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 1 Surveyed: 1

Conditions: PCI:59.00 | Inspection Comments: KHA

Sample Number: 100 Type: R Area: 6,990.00SqFt PCI = 59

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING

43 BLOCK CRACKING

52 WEATHERING/RAVELING

L 153.00 Ft Comments:

3,825.00 SqFt Comments:

5,592.00 SqFt Comments:

50 PATCHING L 4.00 SqFt Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 89,870.00SqFt

Section: of 3 To: -112 From: -Last Const.: 1/1/1977

Surface: AAC Family: FDOT-RL-TW-AAC Zone: Category: Rank: P Width: 50.00Ft

Length: Area: 11,600.00SqFt 215.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Total Samples: 2 Surveyed: 1 Last Insp. Date2/28/2011

Conditions: PCI:69.00 | Inspection Comments: KHA

PCI = 69Sample Number: 300 Type: R Area: 5,775.00SqFt

Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 139.00 Ft Comments:

43 BLOCK CRACKING 510.00 SqFt \mathbf{L} Comments: 52 WEATHERING/RAVELING L 3,000.00 SqFt Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TWB Name: TAXIWAY B Use: TAXIWAY Area: 64,750.00SqFt

Section: 204 of 3 From: - To: - Last Const.: 1/1/1992

Surface: PCC Family: FDOT-RL-PCC Zone: Category: Rank: P
Area: 17,500.00SqFt Length: 640.00Ft Width: 22.00Ft

Area: 17,500.00SqFt Length: 640.00Ft V Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 6 Surveyed: 1

Conditions: PCI:14.00 | Inspection Comments: KHA

Sample Number: 603 Sample Comments:	Type: R	Area:	5.00Slabs		PCI = 14
72 SHATTERED SLAB		L	4.00	Slabs	Comments:
70 SCALING/CRAZING		L	2.00	Slabs	Comments:
67 LARGE PATCH/UTIL	ITY	L	1.00	Slabs	Comments:
72 SHATTERED SLAB		M	1.00	Slabs	Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TWB Name: TAXIWAY B Use: TAXIWAY Area: 64,750.00SqFt

Section: 205 of 3 From: - To: - Last Const.: 1/1/1977

Surface: AAC Family: FDOT-RL-TW-AAC Zone: Category: Rank: P
Area: 26,680.00SqFt Length: 630.00Ft Width: 40.00Ft

Area: 26,680.00SqFt Length: 630.00Ft V Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 7 Surveyed: 2

Conditions: PCI:56.00 | Inspection Comments: KHA

Sample Number: 101	Type: R	Area:	4,275.00SqFt		PCI = 47	
Sample Comments:						
43 BLOCK CRACKING		M	500.00	SqFt	Comments:	
43 BLOCK CRACKING		L	2,700.00	SqFt	Comments:	
52 WEATHERING/RAVE	LING	L	3,500.00	SqFt	Comments:	
56 SWELLING		L	400.00	SqFt	Comments:	
Sample Number: 105	Type: R	Area:	4.000.00SaFt		PCI = 65	

Sa	impic indinoci. 105	rypc. K	Alca.	4,000.005qFt	1 C1 - 03
Sar	nple Comments:				
43	BLOCK CRACKING		L	1,050.00	SqFt Comments:
52	WEATHERING/RAVELING	IG	L	3,200.00	SqFt Comments:
48	LONGITUDINAL/TRANS	SVERSE CRACKING	L	52.00	Ft Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TWB Name: TAXIWAY B Use: TAXIWAY Area: 64,750.00SqFt

Section: 210 of 3 From: - To: - Last Const.: 1/1/1977

40.00Ft

Surface: AAC Family: FDOT-RL-TW-AAC Zone: Category: Rank: P

Area: 20,570.00SqFt Length: 390.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/28/2011 Total Samples: 4 Surveyed: 1

Conditions: PCI:63.00 | Inspection Comments: KHA

Sample Number: 108 Type: R Area: 4,000.00SqFt PCI = 63

Sample Comments:

43 BLOCK CRACKING L 2,026.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 16.00 Ft Comments: 52 WEATHERING/RAVELING L 3,000.00 SqFt Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 58,430.00SqFt

Section: 305 of 1 From: - To: - Last Const.: 1/1/1990

Surface: AAC Family: FDOT-RL-TW-AAC Zone: Category: Rank: P
Area: 58,430.00SqFt Length: 1,160.00Ft Width: 50.00Ft

Area: 58,430.00SqFt Length: 1,160.00Ft V Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/28/2011 Total Samples: 12 Surveyed: 3

Conditions: PCI:24.00 | Inspection Comments: KHA

Sample Number: 102 Type: R Area: 5,000.00SqFt PCI = 22

Sample Comments:
43 BLOCK CRACKING M 4,999.96 SqFt Comments:

52 WEATHERING/RAVELING M 4,999.96 SqFt Comments: 50 PATCHING L 750.00 SqFt Comments:

Sample Number: 105 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

43 BLOCK CRACKING M 4,999.96 SqFt Comments: 52 WEATHERING/RAVELING M 4,999.96 SqFt Comments:

Sample Number: 108 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

43 BLOCK CRACKING M 4,999.96 SqFt Comments: 52 WEATHERING/RAVELING M 4,999.96 SqFt Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Site Name:					
Network: OMN Name: ORMOND BEACH MUN	IICIPAL AIRI	PORT			
Branch: TW D Name: TAXIWAY D		Use: TA	XIWAY	Area: 10	04,640.00SqFt
Section: 405 of 1 From: - Surface: AAC Family: FDOT-RL-TW-AAC Area: 104,640.00SqFt Length: 2,160.00Ft Shoulder: Street Type: Grade: 0.00 Section Comments:	Lanes:	Zone: Categ Width: 45.000	gory:	Rank: P	Last Const.: 1/1/1984
Last Insp. Date2/28/2011 Total Samples: 21 Su Conditions: PCI:27.00 Inspection Comments: KHA	rveyed: 6				
Sample Number: 101 Type: R Sample Comments:	Area:	4,500.00SqFt		PCI = 27	
43 BLOCK CRACKING]	M 800.00		Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		M 380.00		Comments:	
52 WEATHERING/RAVELING]	M 4,499.96	SqFt	Comments:	
Sample Number: 103 Type: R Sample Comments:	Area:	4,500.00SqFt		PCI = 27	
43 BLOCK CRACKING]	M 800.00		Comments:	
52 WEATHERING/RAVELING]	M 4,499.96	_	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING]	M 403.00	Ft	Comments:	
Sample Number: 107 Type: R Sample Comments:	Area:	4,500.00SqFt		PCI = 26	
43 BLOCK CRACKING]	M 800.00		Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING]	M 335.00		Comments:	
52 WEATHERING/RAVELING		M 4,499.96		Comments:	
50 PATCHING		M 45.00	SqFt	Comments:	
Sample Number: 109 Type: R Sample Comments:	Area:	4,500.00SqFt		PCI = 22	
48 LONGITUDINAL/TRANSVERSE CRACKING]	M 124.00	-	Comments:	
43 BLOCK CRACKING		M 2,389.00	-	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		L 87.00		Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		H 56.00		Comments:	
52 WEATHERING/RAVELING		M 4,499.96		Comments:	
56 SWELLING		M 91.00		Comments:	
56 SWELLING		L 26.00	sqrt	Comments:	
Sample Number: 113 Type: R Sample Comments:	Area:	4,500.00SqFt		PCI = 27	
50 PATCHING		M 150.00	-	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		M 84.00		Comments:	
43 BLOCK CRACKING		M 2,110.00	-	Comments:	
52 WEATHERING/RAVELING		M 4,499.96	sqr't	Comments:	
Sample Number: 119 Type: R Sample Comments:	Area:	4,500.00SqFt		PCI = 35	
43 BLOCK CRACKING]	M 2,603.00		Comments:	
50 PATCHING		L 100.00	_	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		M 159.00		Comments:	
56 SWELLING		M 120.00		Comments:	
56 SWELLING		L 4.00		Comments:	
52 WEATHERING/RAVELING	1	M 1,000.00	syrt	Comments:	

FDOT

Report Generated Date: 5/9/2011

Site Name:

Sample Comments:

43 BLOCK CRACKING

43 BLOCK CRACKING

52 WEATHERING/RAVELING

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT Branch: Name: TAXIWAY E Use: TAXIWAY Area: 78,240.00SqFt TW E To: -Section: 505 of 1 From: -Last Const.: 1/1/1990 Surface: Family: FDOT-RL-TW-AAC Zone: Category: Rank: P AAC Width: Area: 78,240.00SqFt Length: 2,060.00Ft 35.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Datc2/28/2011 Total Samples: 22 Surveyed: 4 Conditions: PCI:43.00 | Inspection Comments: KHA PCI = 50Sample Number: 101 Type: R Area: 3,500.00SqFt Sample Comments: 3,000.00 SqFt 43 BLOCK CRACKING L Comments: 43 BLOCK CRACKING 200.00 SqFt Μ Comments: 52 WEATHERING/RAVELING 3,499.97 SqFt $_{\rm L}$ Comments: Sample Number: 107 Type: R PCI = 41Area: 3,500.00SqFt Sample Comments: 43 BLOCK CRACKING 1,700.00 SqFt Μ Comments: 43 BLOCK CRACKING 1,700.00 SqFt \mathbb{L} Comments: 52 WEATHERING/RAVELING 3,000.00 SqFt \mathbf{L} Comments: PCI = 39Sample Number: 111 Type: R Area: 3,500.00SqFt Sample Comments: 50 PATCHING 36.00 SqFt L Comments: 43 BLOCK CRACKING Μ 1,500.00 SqFt Comments: 43 BLOCK CRACKING L 2,000.00 SqFt Comments: 52 WEATHERING/RAVELING L 3,000.00 SqFt Comments: PCI = 40Sample Number: 117 Type: R Area: 3,465.00SqFt

Μ

 \mathbb{L}

L

2,000.00 SqFt

1,500.00 SqFt

3,000.00 SqFt

Comments:

Comments:

Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TW F Name: TAXIWAY F Use: TAXIWAY Area: 47,960.00SqFt

Section: of 2 To: -Last Const.: 1/1/1984 605 From: -

Family: FDOT-RL-TW-AC Zone: Surface: ACCategory: Rank: P 40.00Ft

Length: Width: Area: 1,040.00Ft 41,690.00SqFt

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Total Samples: 10 Surveyed: 2 Last Insp. Date2/28/2011

Conditions: PCI:59.00 | Inspection Comments: KHA

Sample Number: 102 Type: R	Area:	4,000.00SqFt	PCI = 64	
Sample Comments:				
52 WEATHERING/RAVELING	$_{ m L}$	3,600.00 SqFt	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	M	32.00 Ft	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	400.00 Ft	Comments:	
Sample Number: 107 Type: R	Area:	4.000.00SaFt	PCI = 53	

San	nple Number: 10	7 Type: R		Area:		4,000.00SqFt		PCI = 53
Sam	ple Comments:							
48	LONGITUDINA	L/TRANSVERSE	CRACKING	M	1	275.00	Ft	Comments:
48	LONGITUDINA	L/TRANSVERSE	CRACKING	I	_	110.00	Ft	Comments:
43	BLOCK CRACK	ING		I		190.00	SqFt	Comments:
52	WEATHERING/	RAVELING		I	_	3,999.97	SqFt	Comments:

FDOT

Report Generated Date: 5/9/2011

Site Name:

Network: OMN Name: ORMOND BEACH MUNICIPAL AIRPORT

Branch: TWF Name: TAXIWAY F Use: TAXIWAY Area: 47,960.00SqFt

Section: 650 of 2 From: - To: - Last Const.: 1/1/1984

40.00Ft

Surface: AC Family: FDOT-RL-TW-AC Zone: Category: Rank: P

Area: 6,270.00SqFt Length: 130.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/28/2011 Total Samples: 1 Surveyed: 1

Conditions: PCI:58.00 | Inspection Comments: KHA

Sample Number: 100 Type: R Area: 6,270.00SqFt PCI = 58
Sample Comments:

50 PATCHING 1,196.00 SqFt L Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 290.00 Ft \mathbf{L} Comments: 43 BLOCK CRACKING L 731.00 SqFt Comments: 52 WEATHERING/RAVELING L 5,643.00 SqFt Comments: