

**STATE OF FLORIDA
DEPARTMENT OF TRANSPORTATION
AVIATION OFFICE**

**Statewide Airfield Pavement
Management Program**

**Peter Prince Field– 2R4
(General Aviation)
Milton, Florida
(District 3)**



May 2011

TABLE OF CONTENTS

SECTION	PAGE NO.
Executive Summary	iii
1. Introduction.....	1
2. Network Definition and Pavement Inventory	10
3. Pavement Condition.....	14
4. Pavement Condition Prediction	20
5. Maintenance Policies and costs	21
6. Pavement Rehabilitation Needs Analysis	27
7. Maintenance and Rehabilitation Plan	32
8. Visual Aids.....	33
9. Recommendations.....	34

LIST OF FIGURES

Figure 1-1: Pavement Life Cycle.....	4
Figure 1-2: PCI Rating Scale	6
Figure 2-1: Pavement Area by Surface Type.....	12
Figure 3-1: Network PCI Distribution by Rating Category.....	16
Figure 3-1a: Condition Rating Summary.....	16
Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use.....	17
Figure 4-1: Predicted PCI by Pavement Use	20
Figure 6-1: Budget Scenario Analysis	31

LIST OF TABLES

Table I: Condition Summary by Branch.....	iii
Table II: Condition Summary by Pavement Use	iv
Table III: Condition Summary by Pavement Rank.....	iv
Table IV: Immediate Major M&R Needs	iv
Table V: 10-Year M&R Costs under Unlimited Funding Scenario	v
Table 1-1: Sampling Rate for FDOT Condition Surveys	5
Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity	11
Table 2-2: Pavement Area by Pavement Use	11
Table 2-3: Branch and Section Inventory	13
Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces.....	14
Table 3-2: Condition by Pavement Use.....	17
Table 5-1: Routine Maintenance Activities for Airfield Pavements	22
Table 5-2: Critical PCI for General Aviation Airports	23
Table 5-3: FDOT Minimum Service Level PCI for General Aviation Airports.....	23
Table 5-4: M&R Activities for General Aviation Airports	24
Table 5-5: Maintenance Unit Costs for FDOT	25
Table 5-6: M&R Activities and Unit Costs by Condition for General Aviation Airports...	26
Table 6-1: Summary of Immediate Major M&R Needs Option No. 1	27
Table 6-2: Summary of Immediate Major M&R Needs Option No. 2.....	27

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE NO.</u>
-----------------------	------------------------

Table 6-3: Summary of Year 1 Maintenance Activities	29
Table 7-1: M&R Costs under Unlimited Funding Scenario	32

APPENDICES

Appendix A	Network Definition Map
	System Inventory Map
	Pavement Inventory Table
	Work History Report
Appendix B	2011 Condition Map
	Pavement Condition Index Table
Appendix C	Branch Condition Report
	Section Condition Report
Appendix D	Pavement Condition Prediction Table
	Predicted PCI by Pavement Use Graph
Appendix E	Year 1 Maintenance Activities Table
Appendix F	Major M&R Plan by Year under Unlimited Funding Scenario Table
Appendix G	10-Year M&R Map
Appendix H	Photographs
Appendix I	PCI Re-inspection Report

EXECUTIVE SUMMARY

In 2010, the Florida Department of Transportation (FDOT) Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing Statewide Airfield Pavement Management Program (SAPMP) to be completed over fiscal years 2011 and 2012.

The tasks required to achieve this objective at Peter Prince Field included:

- Obtain recent construction history from the Airport to update the Pavement Inventory CADD drawings from the previous SAPMP update,
- Perform a visual Pavement Condition Index (PCI) survey of the airfield pavements at the Airport,
- Update the MicroPAVER database to analyze the PCI field data and determine the current condition of the airfield pavements,
- Predict the future deterioration of the pavements,
- Develop a 10-year M&R plan to address the pavement needs at Peter Prince Field, and
- Provide the estimated costs associated with the suggested immediate and future M&R activities

During March 2011, the PCI survey was performed at Peter Prince Field. The results of the survey indicate that, based on a numerical scale of 0 to 100, the overall area-weighted average PCI of the airfield pavements in 2011 is 76, representing a Satisfactory overall network condition.

Table I below summarizes the overall condition summary by network branch.

Table I: Condition Summary by Branch

Branch Name	Area Weighted PCI	Condition Rating	FDOT Minimum Service Level	MicroPAVER Minimum PCI	Action Required
Apron East	81	Satisfactory	60	65	
Apron West	47	Poor	60	65	X
Runway 18-36	76	Satisfactory	75	65	
Taxiway Alpha to T-Hangars	84	Satisfactory	65	65	
Taxiway Bravo	74	Satisfactory	65	65	
Center Connector Taxiway	76	Satisfactory	65	65	
East Connector Taxiway	73	Satisfactory	65	65	

Tables II and III below illustrate the area-weighted PCI computed individually for each pavement use and rank, respectively.

Table II: Condition Summary by Pavement Use

Use	Average Area-Weighted PCI	Condition Rating
Runway	76	Satisfactory
Taxiway	78	Satisfactory
Apron	77	Satisfactory
All (Weighted)	76	Satisfactory

Table III: Condition Summary by Pavement Rank

Rank*	Average Area-Weighted PCI	Condition Rating
Primary	77	Satisfactory
Tertiary	92	Good
All (Weighted)	76	Satisfactory

*The pavement rank for the airport pavement network is listed on Table 2-3.

The immediate M&R needs, or needs that have been programmed to be completed in the first year of the 10-year M&R plan based on an unlimited budget at Peter Prince Field, include: Apron West and Taxiway Bravo. These sections of pavement exhibited low, medium and high severity distresses such as longitudinal and transverse cracking, block cracking, weathering and raveling. The extent of these distresses justify mill and overlay rehabilitation activity. The immediate needs are summarized in Table IV below.

Table IV: Immediate Major M&R Needs

Branch Name	Section ID	Surface Type	Section Area (ft ²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
Apron West	4205	AC	60,360	\$379,664.43	46	Mill and Overlay	100
Taxiway Bravo	210	AC	8,970	\$51,272.53	52	Mill and Overlay	100
Taxiway Bravo	250	AC	4,620	\$29,059.80	47	Mill and Overlay	100
Total				\$459,996.76	48		100

* Costs are adjusted for inflation.

A forecast of Major M&R needs for a 10-year period, starting from 2011, was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval. The results of this analysis are provided in Table V below.

Table V: 10-Year M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$53,292.55	\$459,996.76	\$513,289.31
2012	\$131,712.40	\$0.00	\$131,712.40
2013	\$151,299.53	\$0.00	\$151,299.53
2014	\$175,183.24	\$0.00	\$175,183.24
2015	\$194,818.90	\$27,342.39	\$222,161.29
2016	\$216,018.26	\$30,145.50	\$246,163.76
2017	\$141,607.07	\$881,238.09	\$1,022,845.16
2018	\$103,414.92	\$527,563.68	\$630,978.60
2019	\$110,836.74	\$33,176.73	\$144,013.47
2020	\$97,483.75	\$289,687.70	\$387,171.45
Total	\$1,375,667.36	\$2,249,150.85	\$3,624,818.21

Note: Costs are adjusted for inflation.

The implementation of the 10-Year major M&R plan is expected to provide an improvement in the overall condition of the airfield pavement, where the area-weighted PCI would increase from 76 in 2011 to 86 in 2020. Appendix F lists the major M&R for the 10-Year program. Appendix G graphically depicts the activity.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all Peter Prince Field pavements in 2020 may remain near 86. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for Peter Prince Field is conducted at some point in the 10-year plan.

1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. There are millions of square yards of pavement for the runways, taxiways, aprons and other areas of these airports that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time.

In order to support the planning, scheduling, and design of the M&R activities based on pavement evaluation and pavement management performance trends, the Florida Department of Transportation (FDOT) Aviation Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992.

In 2010, the FDOT Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

This report discusses the work performed, a summary of the findings, results, and recommendations for M&R planning associated with the update to the SAPMP. It also describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented during the performance of the SAPMP.

1.1 Purpose

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the SAPMP and the roles and responsibilities of the program's participants;
- Provide background information on pavement management principles, objectives, and benefits to this airport;
- Outline the procedures used to collect, evaluate and report pavement inspection results at this airport;
- Present the findings from the pavement inspection;
- Analyze and discuss the needs for Maintenance and Rehabilitation (M&R) activities and associated costs for this airport.

1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The 1992 SAPMP provided valuable information for establishing and performing pavement M&R.

In 1992/1993, and 1998/1999, the FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement maintenance. This system, AIRPAV, was implemented, and initial condition surveys were

performed in 1992 and 1993. The SAPMP was updated with additional surveys in 1998 and 1999.

In 2004, the FDOT Aviation Office undertook a project to update the pavement management system software utilized for the SAPMP. This project involved a review of the AIRPAV software and other available pavement management system software. As a result of this review, MicroPAVER was selected as the software for the update project. Data from the 1998/1999 condition surveys were converted to the MicroPAVER system, and the inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999. The pavements were inspected between 2006 and 2008, and an updated M&R program was developed based on the new condition of the airfield pavements. As part of the update, procedures for the inspection and collection of pavement data were developed, and a website (www.floridaairportpavement.com) was created for the input of data under secure procedures.

Currently, airports using the AIP Grant Program are required by the Federal Aviation Administration (FAA) to develop a pavement maintenance program (FAA/AC 150/5380-6B “Guidelines and Procedures for Maintenance of Airport Pavements”) using trained personnel to perform a detailed inspection of airfield pavements. The inspections are required to be performed at least once a year or every 3 years if pavement inspection is characterized in the form of a Pavement Condition Index (PCI) survey (such as ASTM D 5340 “Standard Test Method for Airport Pavement Condition Index Surveys”, (2004 edition)). The 2004 edition was utilized in lieu of the 2010 edition to maintain database integrity and benefit of pavement performance curves from the previous inspections.

In 2010, the FDOT Aviation Office selected a team consisting of the Consultant and their Subconsultants to provide services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

1.3 Organization

1.3.1 Aviation Office Program Manager Role

The Aviation Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) monitoring the work of the Consultant. The AO-PM has review and approval authority for each program task and also manages the day-to-day details of the SAPMP and the updates.

1.3.2 Consultant Role

The Consultant (Kimley-Horn and Associates, Inc.) and their Subconsultants (MACTEC Engineering and Consulting and All About Pavements, Inc.) provide technical and administrative assistance to the AO-PM during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the SAPMP based upon procedures outlined in FAA Advisory Circular 150/5380-6B “Guidelines and Procedures for Maintenance of Airport Pavements” and ASTM D 5340 “Standard Test Method for Airport Pavement Condition Index Surveys” (2004).

1.3.3 Airport Role

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP update, indicate any construction activity that has been performed since the previous inspections.

1.4 Pavement Types and Pavement Management

1.4.1 Pavement basics

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of an asphalt concrete (AC) surface, and
- Rigid pavement composed of a Portland Cement Concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying natural subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland Cement Concrete supports most of the load, and the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the construction of the concrete surface.


A small percentage of the airport pavements in Florida are composed of asphalt concrete surface over Portland Cement Concrete (APC). This pavement type is known as “composite” pavement.

Due to the different nature of the pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

1.4.2 Pavement Management System Concept

The SAPMP utilized a Pavement Management System (PMS) to develop the M&R recommendations discussed in this report. A PMS is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1 below, taken from FAA/AC 5380-7A “Airport Pavement Management Program”, illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement’s life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in “good” condition depends on how well it is maintained. As the illustration demonstrates, the cost of maintaining the pavement above a critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Figure 1-1: Pavement Life Cycle



Source: FAA/AC 150/5380-7A "Airport Pavement Management Program"
*Modified to reflect current construction costs.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi-year M&R plan can be determined.

1.4.3 Pavement Inspection Methodology for the SAPMP

Pavement condition assessment is one of the primary decision variables in any airport PMS. Pavement condition assessments generally include visual surveys in accordance with ASTM D 5340, "Standard Test Method for Airport Pavement Condition Index Surveys" and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the Statewide Aviation Pavement Management Program update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine the appropriate rehabilitation methods during the design process.

In preparation of the PCI surveys, the airfield pavements are divided into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Further discussion of how the airport pavements are divided and subdivided into units by construction and use can be found in Section 2 “Network Definition and Pavement Inventory” of this report.

Sample unit sizes are approximately 5000 ± 2000 square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements. Prior to conducting the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of Branches, Sections, use patterns, construction types and history. The sampling rate used for the FDOT Statewide Airfield Pavement Management Program is provided in Table 1-1 below.

Table 1-1: Sampling Rate for FDOT Condition Surveys

AC Pavements			PCC Pavements		
N	n		N	n	
	Runway	Others		Runway	Others
1-4	1	1	1-3	1	1
5-10	2	1	4-6	2	1
11-15	3	2	7-10	3	2
16-30	5	3	11-15	4	2
31-40	7	4	16-20	5	3
41-50	8	5	21-30	7	3
≥51	20% but ≤20	10% but ≤10	31-40	8	4
			41-50	10	5
			≥51	20% but ≤20	10% but ≤10

Where N = total number of sample units in Section
 n = number of sample units to inspect

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the Section. In the case when nonrepresentative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each Section. PCI values range from 0 to 100. As Figure 1-2 below indicates, MicroPAVER provides a rating scale that relates PCI to pavement condition. A PCI between 0 and 10 is considered ‘Failed’ pavement, and a PCI between 86 and 100 is considered ‘Good’ pavement, with five other conditions for PCI values between 11 and 85.

Figure 1-2: PCI Rating Scale

	PCI	Condition Rating
	86 – 100	Good
	71 – 85	Satisfactory
	56 – 70	Fair
	41 – 55	Poor
	26 – 40	Very Poor
	11 – 25	Serious
	0 – 10	Failed

1.5 Definitions

Aviation Office - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office Program Manager (AO-PM) has review and approval authority for each program task of the SAPMP.

Base Course - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

Branch - A Branch designates pavements that have common usage and functionality, such as an entire runway, taxiway, or apron.

Branch ID - A short form identification for the pavement Branch. In this report, Branch includes the common designation for the item e.g. RW 18-36.

Category - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA – for general aviation or community airports;
- RL – for regional relievers or small hubs;
- PR – for primary (certified under Part 139 requirements).

Critical PCI - The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

Distress Type - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland Cement Concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

Florida DOT (FDOT) - Florida Department of Transportation was represented in this project by the Office of Aviation.

Global M&R - Global M&R is defined as activities applied to entire pavement Sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

Localized M&R (Maintenance and Repair) - Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

Major M&R (e.g. Rehabilitation) - Activities performed over the entire area of a pavement Section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

MicroPAVER - A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that, if properly implemented, maintained, and operated, it meets the pavement management program requirements described by the FAA in Advisory Circular 150/5380-7A.

Minimum Condition Level - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

Network Definition - A Network Definition is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport is in Appendix A along with a table of inventory data.

Pavement Condition Index (PCI) - The Pavement Condition Index is a number which represents the condition of a pavement segment at a specific point in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340, published by ASTM International.

Pavement Evaluation - A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

Pavement Management System (PMS) - A Pavement Management System is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

Pavement Surface Type - The surface of pavement is identified as one of four types:

- AC – for asphalt surface pavements;
- PCC – for Portland Cement Concrete pavements;
- AAC – for asphalt surface pavements that have had an asphalt overlay at some point in their construction history;
- APC – for composite pavements, which consist of asphalt over Portland Cement Concrete pavement.
- PAC – for composite pavements, which consist of Portland Cement Concrete over asphalt pavement.

Rank - Pavement rank in MicroPAVER determines the priority to be assigned to a pavement Section when developing an M&R plan. Pavement Sections are ranked as follows according to their use:

- P – for Primary pavements, such as primary runways, primary taxiways, and primary aprons;
- S – or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons;
- T – for Tertiary pavements such as “T” hangars and slightly used aprons.

Reconstruction - Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

Rehabilitation - Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

Sample Unit - Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are $5,000 \pm 2,000$ square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements.

Section - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition, and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

Section ID - A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series Sections are taxiways, 4000 and 5000 series Sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series Sections are runways.

Statewide Airfield Pavement Management Program (SAPMP) – The Statewide Airfield Pavement Management Program is a program implemented in 1992 by the Florida Department of Transportation to plan, schedule, and design the maintenance and rehabilitation activities

necessary for the airfield pavement on Florida's public airports to allow the airports to operate efficiently, economically, and without excessive down time.

System Inventory - A System Inventory is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline and identifies airfield construction activities since the last inspection. The System Inventory for the airport is included in Appendix A.

Use - In MicroPAVER, Use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

2. NETWORK DEFINITION AND PAVEMENT INVENTORY

Peter Prince Field (2R4) is a public-use airport located in Santa Rosa County. Airport operations primarily encompass general aviation and general aviation training. Peter Prince Field consists of a single runway; RW 18-36, which is 75-ft wide by 3701-ft long. The airport is served by two parallel taxiways, TW Alpha and Bravo, which are both 25-ft wide. Currently the airport has T-Hangar facilities located along the west side of TW Alpha and tie-down spaces along the two separate apron areas. The runway, taxiways and aprons are all constructed out of Asphalt Concrete pavement.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric dimensions may vary slightly from the geometry used in the condition and M&R analysis based on field measurements.

This airport is designated as a General Aviation airport and is located in District 3 of the Florida Department of Transportation.

2.1 Network Definition

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units.

2.1.1 Branch Section Identification

The airport pavement network is subdivided into separate Branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then further divided into Sections with similar pavement construction and performance that may share other common attributes.

Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage. A pavement rank, consisting of primary, secondary, and tertiary levels, is assigned to each Section based on their level and type of use. The pavement rankings that were designated for each Section in the previous SAPMP update were again used for this update.

As discussed in Section 1.4.3 “Pavement Inspection Methodology for the SAPMP”, the sections are sub-divided into sample units, which are the smallest subdivision in a pavement network, only for the purpose of conducting the pavement condition survey.

2.1.2 System Inventory and Network Definition Update

The System Inventory and Network Definition drawings are used to identify changes in the network since the most recent update from the 2006/2008 inspections and also to plan the field inspection activities for the 2011 survey. Prior to the field inspection process, the System Inventory drawing was updated from the previous inspection with notes indicating recent construction projects on the various Sections of pavement throughout the airfield. This System Inventory drawing is used to update the Network Definition drawing.

The Network Definition drawing shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample

units to be surveyed, i.e. the sampling plan. The previous airport configuration and history was compared with the current airport configuration, and the existing network branch, section and sample unit designations were revised to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important historical record.

The updated System Inventory and Network Definition drawings for Peter Prince Field are provided in Appendix A. Table 2-1 below lists the recent construction projects at the airport.

Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity

Construction Year	Location	Work Type/Pavement Section
2011	End of Each Taxiway, Four Total	Taxiway Hold Bays

2.2 Pavement Inventory

The detailed pavement inventory was updated to reflect the network definition update and field inspection results.


The total airfield pavement area in 2011 at Peter Prince Field is 1,044,380 square feet. The breakdown of pavement area for each pavement use is provided in Table 2-2.

Table 2-2: Pavement Area by Pavement Use

Use	Area (ft²)	% of Total Area
Runway	277,500	27%
Taxiway	255,250	24%
Apron	511,630	49%
All (Weighted)	1,044,380	100%

Figure 2-1 presents the breakdown of the pavement area at Peter Prince Field by surface type.

Figure 2-1: Pavement Area by Surface Type



Details of pavement Branch and Section information including Branch name (which indicates pavement use), Branch ID, Section ID, section area, rank, surface type, last construction date, number of samples inspected, and number of samples in each Section are given in Table 2-3 below. A more detailed Pavement Inventory Table may be found in Appendix A of this report.

Table 2-3: Branch and Section Inventory

Branch Name	Branch ID	Section ID	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Sample Units in Section
Apron East	AP E	4105	90,760	P	AC	1/1/1992	3	16
Apron East	AP E	4110	71,870	P	AAC	1/1/2000	2	16
Apron East	AP E	4115	36,670	P	AAC	1/1/2000	1	9
Apron East	AP E	4120	49,870	P	AC	1/1/1995	1	10
Apron East	AP E	4125	116,740	P	AC	1/1/1996	3	24
Apron East	AP E	4130	85,360	P	AC	1/1/2007	3	22
Apron West	AP W	4205	60,360	P	AC	1/1/1992	2	12
Runway 18-36	RW 18-36	6105	277,500	P	AAC	1/1/1992	15	74
Taxiway Alpha to T-Hangars	TW A	105	12,760	T	AC	1/1/1992	2	5
Taxiway Alpha to T-Hangars	TW A	110	11,250	P	AC	1/1/1995	1	4
Taxiway Alpha to T-Hangars	TW A	115	27,010	P	AC	1/1/1995	3	11
Taxiway Alpha to T-Hangars	TW A	120	6,720	P	AC	1/1/1996	1	2
Taxiway Alpha to T-Hangars	TW A	500	9,340	P	AC	1/1/2007	1	2
Taxiway Alpha to T-Hangars	TW A	510	38,830	P	AC	1/1/2001	1	8
Taxiway Bravo	TW B	205	104,950	P	AC	1/1/1992	4	21
Taxiway Bravo	TW B	210	8,970	P	AC	1/1/1992	1	1
Taxiway Bravo	TW B	215	9,340	P	AC	1/1/1996	1	2
Taxiway Bravo	TW B	250	4,620	P	AC	1/1/1992	1	1
Center Connector Taxiway	TW CONN CT	405	7,440	P	AAC	1/1/1992	1	2
Center Connector Taxiway	TW CONN CT	410	2,850	P	AAC	1/1/1992	1	1
East Connector Taxiway	TW CONN E	305	11,170	P	AC	1/1/1968	1	2

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

3. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340-04 “Standard Practice for Airport Pavement Condition Index Surveys.” These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

3.1 Inspection Methodology

A PCI survey is performed by measuring the amount and severity of pavement distresses, which are caused by traffic load, climate, and other factors, observed within a sample unit. This data is imported into MicroPAVER, which calculates PCI values for the pavement sections. Table 3-1 below lists the pavement distress types and related causes for asphalt concrete (AC).

Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces

Code	Distress	Mechanism
41	Alligator Cracking	Load
42	Bleeding	Construction Quality / Mix Design
43	Block Cracking	Climate / Age
44	Corrugation	Load / Construction Quality
45	Depression	Subgrade Quality
46	Jet Blast	Aircraft
47	Joint Reflection - Cracking	Climate / Prior Pavement
48	Longitudinal/Transverse Cracking	Climate / Age
49	Oil Spillage	Aircraft / Vehicle
50	Patching	Utility / Pavement Repair
51	Polished Aggregate	Load
52	Weathering/Raveling	Climate / Load
53	Rutting	Load
54	Shoving	Pavement Growth
55	Slippage Cracking	Load / Pavement Bond
56	Swelling	Climate / Subgrade Quality
<i>Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual</i>		

Prior to conducting the inspections, Global Positioning System (GPS) coordinates were recorded using CADD at the centroid of each sample unit. The centroid is usually the geometric center of the area, but in cases where sample units are irregular in shape, this is the center of mass. These data are presented in a table on the updated Network Definition Map in Appendix A of this report.

Pavement condition inspections at Peter Prince Field were performed in March 2011. Data were recorded in the field in accordance with FAA Advisory Circular 150/5380-6B “Guidelines and Procedures for Maintenance of Airport Pavements” and ASTM D 5340 “Standard Test Method for Airport Pavement Condition Index Surveys” (2004).

After the completion of data collection, the data was imported into MicroPAVER, and PCI values were calculated for the pavement sections.

3.2 Pavement Condition Index Results

According to the 2011 survey, the overall area-weighted PCI at Peter Prince Field is 76, representing a Satisfactory overall network condition.

Overall the airport exhibited pavement distresses associated with climate and age distresses. Asphalt Concrete pavement distresses include; weathering, raveling, longitudinal and transverse cracking distresses of which are common of pavements of similar age.

Runway 18-36 exhibited low and medium severity longitudinal and transverse cracking along with low severity weathering and raveling. The taxiway, apron and hangar facilities pavement throughout the airport exhibited very similar distresses to the runway. There were a few isolated locations along the taxiways where high severity longitudinal and transverse cracking was observed. Medium severity block cracking was also identified in remote locations. Overall the runway exhibited a PCI of 76, with a condition rating of ‘Satisfactory’. Based on the FDOT and FAA minimum criteria for runway pavement condition, Runway 18-36 is above the recommended PCI.

Appendix B contains a table and a Condition Map which depicts the PCI results by Section, and Appendix C contains a table of PCI results by Branch. Appendix I includes detailed distress data generated by MicroPAVER for each inspected sample unit.

Figure 3-1 provides the PCI distribution by rating category for Peter Prince Field.

Figure 3-1: Network PCI Distribution by Rating Category




Figure 3-1a: Condition Rating Summary

Condition Rating	Total Area (ft ²)	Percent
Good	145,560	14%
Satisfactory	824,870	79%
Fair	0	0%
Poor	73,950	7%
Very Poor	0	0%
Serious	0	0%
Failed	0	0%


Approximately 14% of the network is in Good condition while 7% of the network is in Poor condition. Table 3-3 illustrates the area-weighted PCI computed individually for each pavement use.

Table 3-2: Condition by Pavement Use


Use	Area-Weighted PCI	Condition Rating
Runway	76	Satisfactory
Taxiway	78	Satisfactory
Apron	77	Satisfactory
All (Weighted)	76	Satisfactory

Figure 3-2 presents the breakdown of PCI by range for each pavement use.


Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use



(b) Taxiway




(c) Apron



4. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 4-1 illustrates the predicted performance of pavements at Peter Prince Field based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum service level for General Aviation (GA) airports.

Figure 4-1: Predicted PCI by Pavement Use



Appendix D presents the tabular summary of the predicted Section PCI for each year from 2011 to 2020.

5. MAINTENANCE POLICIES AND COSTS

5.1 Policies

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature and are recommended to help achieve the performance goal.

Table 5-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules. These repairs are used only in the first year of an analysis.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called “Critical PCI.” The critical PCI levels for different pavement and branch types established in the previous SAPMP update were used in this update for the development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 5-2 gives the critical PCI levels for General Aviation Airports.

The maintenance rehabilitation policy and activity costs have been updated based on the study of readily available construction cost data at the time of this study. The costs depicted in this report are intended for planning purposes.

Table 5-1: Routine Maintenance Activities for Airfield Pavements

Surface	Distress	Severity*	Work Type	Code	Work Unit
AC	Alligator Crack	M, H	Patching - AC Deep	PA-AD	SqFt
	Bleeding	N/A	No Localized M&R	NONE	N/A
	Block Crack	M, H	Crack Sealing – AC	CS-AC	SqFt
	Corrugation	L, M, H	Patching - AC Deep	PA-AD	SqFt
	Depression	M, H	Patching - AC Deep	PA-AD	SqFt
	Jet Blast	N/A	Patching - AC Deep	PA-AD	SqFt
	Joint Ref. Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	L & T Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	Oil Spillage	N/A	Patching - AC Shallow	PA-AS	SqFt
	Patching	M, H	Patching - AC Deep	PA-AD	SqFt
	Polished Agg.	N/A	No Localized M&R	NONE	N/A
	Raveling and Weathering	L	Surface Sealing - Rejuvenating	SS-RE	SqFt
		M	Surface Seal - Coal Tar	SS-CT	SqFt
		H	Microsurfacing	MI-AC	SqFt
	Rutting	M, H	Patching - AC Deep	PA-AD	SqFt
	Shoving	M, H	Grinding (Localized)	GR-LL	SqFt
	Slippage Crack	N/A	Patching - AC Shallow	PA-AS	SqFt
	Swelling	M, H	Patching - AC Deep	PA-AD	SqFt
PCC	Blow-Up	L, M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Corner Break	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Linear Crack	M, H	Crack Sealing – PCC	CS-PC	Ft
	Durability Crack	H	Slab Replacement – PCC	SL-PC	SqFt
		M	Patching - PCC Full Depth	PA-PF	SqFt
	Jt. Seal Damage	M, H	Joint Seal (Localized)	JS-LC	Ft
	Small Patch	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Large Patch	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Popouts	N/A	No Localized M&R	NONE	N/A
	Pumping	N/A	No Localized M&R	NONE	N/A
	Scaling	H	Slab Replacement – PCC	SL-PC	SqFt
	Faulting	M, H	Grinding (Localized)	GR-PP	Ft
	Shattered Slab	M, H	Slab Replacement – PCC	SL-PC	SqFt
	Shrinkage Crack	N/A	No Localized M&R	NONE	N/A
	Joint Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Corner Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt

*L = Low, M = Medium, H = High

Table 5-2: Critical PCI for General Aviation Airports

Use	Critical PCI
Runway	65
Taxiway	65
Apron	65

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 5-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of General Aviation Airports.

Table 5-3: FDOT Minimum Service Level PCI for General Aviation Airports

Minimum PCI		
Runway	Taxiway	Apron
75	65	60

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 5-2 the PCI trigger range when the likely activity would be a mill and resurface was 40 to 79 and reconstruction at a PCI of 39 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 5-4 summarizes the M&R activities for General Aviation Airports based on PCI value.

Table 5-4: M&R Activities for General Aviation Airports

	Activity	PCI Range
Maintenance	Crack Sealing and Full-Depth Patching	80 and 90
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	40 to 79
	Reconstruction	39 and less

5.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were updated from the previous SAPMP study based on current construction cost trends in order to determine meaningful costs for the program. Table 5-5 presents the unit costs summary.

5.3 M&R Activities

FDOT recognizes that although Mill and Overlay work is recommended for asphalt pavements within a PCI range from 40 to 79, it is conceivable that airports may not have adequate funding to perform this type of rehabilitation. Microsurfacing treatment is a maintenance/rehabilitation measure that can be used in lieu of asphalt pavement mill and overlay; however it should be understood that this measure is intended for short term pavement life extension. While the cost of microsurfacing is significantly lower than that of pavement mill and overlay, it is not intended to be a full rehabilitative measure for long term benefit.

Table 5-5: Maintenance Unit Costs for FDOT

Code	Name	Cost	Unit
GR-LL	Grinding (Localized for AC)	\$2.10	SqFt
PA-AL	Patching – AC Leveling	\$2.30	SqFt
PA-AS	Patching – AC Shallow	\$2.90	SqFt
PA-PF	Patching – PCC Full Depth	\$38.11	SqFt
PA-PP	Patching – PCC Partial Depth	\$19.06	SqFt
SL-PC	Slab Replacement – PCC	\$39.11	SqFt
CS-PC	Crack Sealing – PCC	\$4.24	Ft
UN-PC	Undersealing – PCC	\$3.40	Ft
CS-AC	Crack Sealing – AC	\$2.25	Ft
GR-PP	Grinding (Localized for PCC)	\$22.51	Ft
JS-LC	Joint Seal (Localized)	\$2.00	Ft
SH-LE	Shoulder Leveling	\$2.81	Ft
JS-SI	Joint Seal – Silicon	\$2.81	Ft
PA-AD	Patching – AC Deep	\$4.90	SqFt
OL-AT	Overlay – AC Thin	\$2.80	SqFt
SS-CT	Surface Seal – Coal Tar	\$0.40	SqFt
SS-FS	Surface Seal – Fog Seal	\$0.40	SqFt
SS-RE	Surface Seal – Rejuvenating	\$0.40	SqFt
ST-SB	Surface Treatment – Single Bitum.	\$0.30	SqFt
ST-SS	Surface Treatment – Slurry Seal	\$0.55	SqFt
ST-ST	Surface Treatment – Sand Tar	\$0.28	SqFt
MI-AC	Microsurfacing - AC	\$0.65	SqFt

The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection was performed recently and only in the first year of the M&R analysis. In subsequent years, MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCIs. That is, for low PCI, it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly.

Using available unit cost data, the Major M&R Cost by Condition table was set up as shown in Table 5-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

**Table 5-6: M&R Activities and Unit Costs by Condition for
 General Aviation Airports**

	Activity	PCI Trigger	Cost/SqFt
Maintenance	Crack Sealing and Full-Depth Patching	90	\$0.06
		80	\$0.24
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	70	\$3.00
		60	\$3.42
		50	\$6.29
		40	\$6.29
	Reconstruction	30	\$13.62
		20	\$13.62

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

6. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years, starting from 2011. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Table 6-1 presents the M&R list of immediate needs for Major M&R, i.e. Year 1 of the forecast. The importance of this listing is that it points out the major activities triggered by the current condition of the pavements.

Table 6-1: Summary of Immediate Major M&R Needs Option No. 1

Branch Name	Section ID	Surface Type	Section Area (ft²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
Apron West	4205	AC	60,360	\$379,664.43	46	Mill and Overlay	100
Taxiway Bravo	210	AC	8,970	\$51,272.53	52	Mill and Overlay	100
Taxiway Bravo	250	AC	4,620	\$29,059.80	47	Mill and Overlay	100
Total				\$459,996.76	48		100

* Costs are adjusted for inflation.

FDOT recognizes that the costs attributed to the aforementioned ‘Major Activity’ of performing a pavement ‘Mill and Overlay’ may conflict with budgetary constraints. Table 6-2 presents an alternative minor rehabilitative activity to the mid-range performing pavements. The alternative activity is performing a ‘Microsurfacing/Slurry Seal’ to the pavement to retard the degradation of the facility until funding is available for a ‘Mill and Overlay’ activity.

Table 6-2: Summary of Immediate Major M&R Needs Option No. 2

Branch Name	Section ID	Surface Type	Section Area (ft²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
Apron West	4205	AC	60,360	\$39,234.00	46	Microsurfacing	100
Taxiway Bravo	210	AC	8,970	\$5,830.50	52	Microsurfacing	100
Taxiway Bravo	250	AC	4,620	\$3,003.00	47	Microsurfacing	100
Total				\$48,067.50	48		100

* Costs are adjusted for inflation.

In addition to the immediate Major M&R needs, maintenance activities for pavement areas above critical PCI have been recommended by MicroPAVER for Year 1 and are shown in Table 6-3 below. The costs provided in Table 5-5 were used to calculate the costs associated with this work, which is intended to treat specific distress types. A more detailed table is provided in Appendix E.

Table 6-3: Summary of Year 1 Maintenance Activities


Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Apron East	AP E	4105	L & T CR	M	Crack Sealing - AC	280.7	Ft	\$2.25	\$631.48
Apron East	AP E	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	8,419.20	SqFt	\$0.40	\$3,367.72
Apron East	AP E	4110	OIL SPILLAGE	N	Patching - AC Shallow	213.1	SqFt	\$2.90	\$617.93
Apron East	AP E	4110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	12,673.60	SqFt	\$0.40	\$5,069.49
Apron East	AP E	4115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	15,334.70	SqFt	\$0.40	\$6,133.94
Apron East	AP E	4120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	5,024.60	SqFt	\$0.40	\$2,009.87
Apron East	AP E	4125	WEATH/RAVEL	L	Surface Seal - Rejuvenating	6,361.80	SqFt	\$0.40	\$2,544.74
Apron East	AP E	4130	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,225.60	SqFt	\$0.40	\$1,290.23
Apron East	AP E	4130	WEATH/RAVEL	M	Surface Seal - Coat Tar	8,402.30	SqFt	\$0.40	\$3,360.93
Runway 18-36	RW 18-36	6105	L & T CR	H	Crack Sealing - AC	246.7	Ft	\$2.25	\$555.03
Runway 18-36	RW 18-36	6105	L & T CR	M	Crack Sealing - AC	1,262.90	Ft	\$2.25	\$2,841.55
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	16,279.90	SqFt	\$0.40	\$6,512.00
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	M	Surface Seal - Coat Tar	794.3	SqFt	\$0.40	\$317.71
Taxiway Alpha to T-Hangars	TW A	105	L & T CR	M	Crack Sealing - AC	38.3	Ft	\$2.25	\$86.15
Taxiway Alpha to T-Hangars	TW A	110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	400	SqFt	\$0.40	\$160.00
Taxiway Alpha to T-Hangars	TW A	115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,099.60	SqFt	\$0.40	\$1,639.84
Taxiway Alpha to T-Hangars	TW A	120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	171.4	SqFt	\$0.40	\$68.57
Taxiway Alpha to T-Hangars	TW A	500	WEATH/RAVEL	L	Surface Seal - Rejuvenating	236.7	SqFt	\$0.40	\$94.69
Taxiway Alpha to T-Hangars	TW A	510	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,659.60	SqFt	\$0.40	\$1,863.84
Taxiway Bravo	TW B	205	L & T CR	H	Crack Sealing - AC	307.6	Ft	\$2.25	\$692.08
Taxiway Bravo	TW B	205	L & T CR	M	Crack Sealing - AC	879.5	Ft	\$2.25	\$1,978.97
Taxiway Bravo	TW B	205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	17,806.40	SqFt	\$0.40	\$7,122.64
Taxiway Bravo	TW B	215	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,982.90	SqFt	\$0.40	\$1,593.19
Taxiway Bravo	TW B	215	L & T CR	M	Crack Sealing - AC	278.8	Ft	\$2.25	\$627.30

Table 6-3: Summary of Year 1 Maintenance Activities (Continued)

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Center Connector Taxiway	TW CONN CT	405	L & T CR	M	Crack Sealing - AC	108.7	Ft	\$2.25	\$244.49
Center Connector Taxiway	TW CONN CT	405	WEATH/RAVEL	L	Surface Seal - Rejuvenating	383.5	SqFt	\$0.40	\$153.40
Center Connector Taxiway	TW CONN CT	410	L & T CR	M	Crack Sealing - AC	50	Ft	\$2.25	\$112.51
East Connector Taxiway	TW CONN E	305	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,468.90	SqFt	\$0.40	\$1,387.59
East Connector Taxiway	TW CONN E	305	L & T CR	M	Crack Sealing - AC	95.4	Ft	\$2.25	\$214.66
Total =									\$53,292.54

The 10 year forecast results are shown in Figure 6-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.

Figure 6-1: Budget Scenario Analysis



The following network level observations can be made from the figure above:

- The PCI will deteriorate from 76 in 2011 to 61 in ten years if no M&R activities are performed.
- The PCI will remain at or above 86 through the 10-year analysis period under the unlimited budget scenario. A 2020 PCI of 86 with this scenario is 25 PCI points higher than a “No M&R” scenario. The total cost for Major M&R over this 10-year period is about \$2.2 million.

7. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels, the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCIs less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 7-1 provides the summary results under the critical PCI unlimited funding scenario.

Table 7-1: M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$53,292.55	\$459,996.76	\$513,289.31
2012	\$131,712.40	\$0.00	\$131,712.40
2013	\$151,299.53	\$0.00	\$151,299.53
2014	\$175,183.24	\$0.00	\$175,183.24
2015	\$194,818.90	\$27,342.39	\$222,161.29
2016	\$216,018.26	\$30,145.50	\$246,163.76
2017	\$141,607.07	\$881,238.09	\$1,022,845.16
2018	\$103,414.92	\$527,563.68	\$630,978.60
2019	\$110,836.74	\$33,176.73	\$144,013.47
2020	\$97,483.75	\$289,687.70	\$387,171.45
Total	\$1,375,667.36	\$2,249,150.85	\$3,624,818.21

Note: Costs are adjusted for inflation.

Approximately 20% of the total Major M&R cost is required in the first year (2011). According to the 2011 inspections, the following pavement sections were in immediate need of Major M&R Activity:

- **Apron West** – Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.
- **Taxiway Bravo** – Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.

The unlimited budget scenario provides the basis for estimating the total repair cost.

Appendix F provides details of M&R plan by year under the unlimited funding scenario, and the map of the 10-year M&R plan is provided in Appendix G. It is important to understand that the SAPMP is a network level tool and the M&R costs provided in this report are only for planning purposes.

8. VISUAL AIDS

8.1 System Inventory and Network Definition Drawings

The System Inventory and Network Definition CADD drawings, which show the airport pavement outline with Branch and Section boundaries and identify changes in the network pavement since the last inspection and the sampling plan, respectively, are included in Appendix A of this report.

8.2 Condition Map

A Condition Map that has been prepared based on data linked to the airport's shape file is included in Appendix B. The Condition Map graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

8.3 10-Year M&R Map

A 10-Year M&R Map that shows the summary of the M&R plan is attached in Appendix G.

8.4 Photographs

Selected digital photographs taken during the pavement inspection are provided in Appendix H to provide visual support to special pavement conditions or distress observed during the inspection of the airport.

9. RECOMMENDATIONS

Pavement condition inspections were performed at Peter Prince Field, and a 10-year M&R plan was developed based on the unlimited funding scenario.

The following recommendations were made based on the 2011 condition inspection and M&R analysis results:

- **Apron West** – Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.
- **Taxiway Bravo** – Asphalt Pavement mill and overlay activity per the FAA P-401 Specification.

Further evaluation of these features is necessary in order to develop repair plans and timing for future budgets since these needs cannot be addressed with typical annual expenditures.

APPENDIX A

NETWORK DEFINITION MAP


SYSTEM INVENTORY MAP

PAVEMENT INVENTORY TABLE

WORK HISTORY REPORT

GPS COORDINATES - PETER PRINCE FIELD AIRPORT				
LOCATION	SECTION	SAMPLE	LATITUDE	LONGITUDE
RW 18-36	6105	101	30.64249881	-86.99349587
RW 18-36	6105	105	30.64194915	-86.99351381
RW 18-36	6105	109	30.64139949	-86.99353174
RW 18-36	6105	114	30.64071242	-86.99355417
RW 18-36	6105	120	30.63988793	-86.99358107
RW 18-36	6105	123	30.63947569	-86.99359452
RW 18-36	6105	127	30.63892603	-86.99361246
RW 18-36	6105	131	30.63837637	-86.99363039
RW 18-36	6105	135	30.63782671	-86.99364833
RW 18-36	6105	141	30.63700222	-86.99367523
RW 18-36	6105	149	30.63590291	-86.99371111
RW 18-36	6105	156	30.634941	-86.99374249
RW 18-36	6105	162	30.63411651	-86.99376939
RW 18-36	6105	167	30.63342944	-86.99379181
RW 18-36	6105	171	30.63287978	-86.99380974
AP W	4205	150	30.63785529	-86.99176557
AP W	4205	251	30.63758822	-86.99209237
AP E	4130	100	30.63470864	-86.99522839
AP E	4130	108	30.63399376	-86.99525178
AP E	4130	116	30.63328063	-86.99527504
AP E	4125	150	30.6420324	-86.99503725
AP E	4125	300	30.6415718	-86.99505251
AP E	4125	451	30.64098661	-86.99464143
AP E	4120	750	30.63988242	-86.99510735
AP E	4115	101	30.6363841	-86.99462265
AP E	4110	105	30.63755992	-86.99458419
AP E	4110	203	30.63693784	-86.99477212
AP E	4105	51	30.63921509	-86.9946973
AP E	4105	200	30.63887806	-86.99514011
AP E	4105	500	30.6383691	-86.99515696
TW A	510	103	30.63452354	-86.99455558
TW A	500	98	30.63727678	-86.99443297
TW CONN CT	410	400	30.63755679	-86.99381179
TW CONN CT	405	401	30.63759216	-86.99426735
TW CONN E	305	101	30.63638809	-86.99436726
TW B	250	200	30.637528	-86.99250814
TW B	215	101	30.64009269	-86.99278448
TW B	210	200	30.63754621	-86.99313728
TW B	205	103	30.64136755	-86.99257849
TW B	205	111	30.63697028	-86.99272202
TW B	205	117	30.63367233	-86.99282966
TW B	205	120	30.63259488	-86.99351562
TW A	120	101	30.64012175	-86.99378784
TW A	115	112	30.64121946	-86.99433714
TW A	115	116	30.64231878	-86.99430127
TW A	115	118	30.64268325	-86.99396982
TW A	110	107	30.63984532	-86.99438197
TW A	105	101	30.63812562	-86.99443807
TW A	105	103	30.63867494	-86.99442015

NOTE: GEODETICS REPRESENT DECIMAL DEGREES (NAD 83 FLORIDA STATE PLANES, NORTH ZONE, US FOOT). ALL GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNITS.



LEGEND

RW 13-31

TYPICAL RUNWAY BRANCH ID

TW A

TYPICAL TAXIWAY BRANCH ID

AP S

TYPICAL APRON BRANCH ID

4105

SECTION NUMBER

AC

PAVEMENT TYPE

100' X 25'

TYPICAL SAMPLE UNIT INFORMATION

FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH

RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE

5

14

NUMBER OF SAMPLE UNITS IN SECTION

NUMBER OF SAMPLE UNITS TO BE INSPECTED

105

INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.



TOTAL SAMPLES INSPECTED = 49

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS
DESIGNED:	ELT	DRAWN: ALB
CHECKED:	DRB	DATE:
PLOTTED: July 15, 2011 - 3:46 PM BY: Sheldene, Rev		















NETWORK DEFINITION MAP		IDENTIFIER
PETER PRINCE FIELD AIRPORT		2R4
MILTON, SANTA ROSA, FLORIDA		FOOT DISTRICT
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE		3



CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2011	END OF EACH TAXIWAY, FOUR TOTAL	TAXIWAY HOLD BAYS

LEGEND

- | | | | |
|---|----------|------|------|
|  | PROJECTS | YEAR | 2006 |
|  | PROJECTS | YEAR | 2007 |
|  | PROJECTS | YEAR | 2008 |
|  | PROJECTS | YEAR | 2009 |
|  | PROJECTS | YEAR | 2010 |
|  | PROJECTS | YEAR | 2011 |
|  | PROJECTS | YEAR | 2012 |
|  | PROJECTS | YEAR | 2013 |
|  | PROJECTS | YEAR | 2014 |
|  | PROJECTS | YEAR | 2015 |
|  | PROJECTS | YEAR | 2016 |
|  | PROJECTS | YEAR | 2017 |

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

[illegible]

SYSTEM INVENTORY MAP

PETER PRINCE FIELD AIRPORT
MILTON, SANTA ROSA, FLORIDA

FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER
2R4
FOOT DISTRICT
3

Table A-1: Pavement Inventory

Branch Name	Branch ID	Branch Use	Section ID	Length (ft)	Width (ft)	True Area (ft ²)	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
Apron East	AP E	APRON	4105	300	267	90,760	P	AC	1/1/1992	2/8/2011	16
Apron East	AP E	APRON	4110	400	150	71,870	P	AAC	1/1/2000	2/8/2011	16
Apron East	AP E	APRON	4115	250	150	36,670	P	AAC	1/1/2000	2/8/2011	9
Apron East	AP E	APRON	4120	210	267	49,870	P	AC	1/1/1995	2/8/2011	10
Apron East	AP E	APRON	4125	440	267	116,740	P	AC	1/1/1996	2/8/2011	24
Apron East	AP E	APRON	4130	275	275	85,360	P	AC	1/1/2007	2/8/2011	22
Apron West	AP W	APRON	4205	255	235	60,360	P	AC	1/1/1992	2/8/2011	12
Runway 18-36	RW 18-36	RUNWAY	6105	3,700.00	75	277,500	P	AAC	1/1/1992	2/8/2011	74
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	105	500	25	12,760	T	AC	1/1/1992	2/8/2011	5
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	110	450	25	11,250	P	AC	1/1/1995	2/8/2011	4
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	115	1,040.00	25	27,010	P	AC	1/1/1995	2/8/2011	11
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	120	200	25	6,720	P	AC	1/1/1996	2/8/2011	2
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	500	380	25	9,340	P	AC	1/1/2007	2/8/2011	2
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	510	1,518.00	25	38,830	P	AC	1/1/2001	2/8/2011	8
Taxiway Bravo	TW B	TAXIWAY	205	4,200.00	25	104,950	P	AC	1/1/1992	2/8/2011	21
Taxiway Bravo	TW B	TAXIWAY	210	250	25	8,970	P	AC	1/1/1992	2/8/2011	1
Taxiway Bravo	TW B	TAXIWAY	215	250	25	9,340	P	AC	1/1/1996	2/8/2011	2
Taxiway Bravo	TW B	TAXIWAY	250	100	35	4,620	P	AC	1/1/1992	2/8/2011	1
Center Connector Taxiway	TW CONN CT	TAXIWAY	405	160	40	7,440	P	AAC	1/1/1992	2/8/2011	2
Center Connector Taxiway	TW CONN CT	TAXIWAY	410	40	40	2,850	P	AAC	1/1/1992	2/8/2011	1
East Connector Taxiway	TW CONN E	TAXIWAY	305	250	40	11,170	P	AC	1/1/1968	2/8/2011	2

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

Date:05/19/2011

Work History Report

1 of 4

Pavement Database:

Network: 2R4 **Branch:** AP E **(APRON EAST)** **Section:** 4105 **Surface:** AC
L.C.D.: 01/01/1992 **Use:** APRON **Rank:**P **Length:** 300.00 Ft **Width:** 267.00 Ft **True Area:** 90.760.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	IMPORTED	OVERLAY			True	SOIL: SP
01/01/1992	IMPORTED	BUILT		3.00	True	1992: 3" AC ON 6" SAND/CLAY BASE

Network: 2R4 **Branch:** AP E **(APRON EAST)** **Section:** 4110 **Surface:** AAC
L.C.D.: 01/01/2000 **Use:** APRON **Rank:**P **Length:** 400.00 Ft **Width:** 150.00 Ft **True Area:** 71.870.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2000	ML-OL	Mill and Overlay	\$0	0.00	True	Construction year verification pending
01/01/1970	IMPORTED	BUILT			True	ESTIMATE 1970 AC PAVEMENT
01/01/1970	IMPORTED	OVERLAY			True	SOIL: SP

Network: 2R4 **Branch:** AP E **(APRON EAST)** **Section:** 4115 **Surface:** AAC
L.C.D.: 01/01/2000 **Use:** APRON **Rank:**P **Length:** 250.00 Ft **Width:** 150.00 Ft **True Area:** 36.670.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2000	ML-OL	Mill and Overlay	\$0	0.00	True	
01/01/1968	IMPORTED	BUILT		1.00	True	1968 1" AC ON 6" SAND-CLAY BASE

Network: 2R4 **Branch:** AP E **(APRON EAST)** **Section:** 4120 **Surface:** AC
L.C.D.: 01/01/1995 **Use:** APRON **Rank:**P **Length:** 210.00 Ft **Width:** 267.00 Ft **True Area:** 49.870.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1995	IMPORTED	BUILT		3.00	True	1995 3" P401 ON 6" P213

Network: 2R4 **Branch:** AP E **(APRON EAST)** **Section:** 4125 **Surface:** AC
L.C.D.: 01/01/1996 **Use:** APRON **Rank:**P **Length:** 440.00 Ft **Width:** 267.00 Ft **True Area:** 116.740.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1996	IMPORTED	BUILT			True	1996 AC PAVEMENT

Network: 2R4 **Branch:** AP E **(APRON EAST)** **Section:** 4130 **Surface:** AC
L.C.D.: 01/01/2007 **Use:** APRON **Rank:**P **Length:** 275.00 Ft **Width:** 275.00 Ft **True Area:** 85.360.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2007	NC-AC	New Construction - AC	\$0	2.00	True	

Network: 2R4 **Branch:** AP W **(APRON WEST)** **Section:** 4205 **Surface:** AC
L.C.D.: 01/01/1992 **Use:** APRON **Rank:**P **Length:** 255.00 Ft **Width:** 235.00 Ft **True Area:** 60.360.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1998	IMPORTED	REPAIR			False	EST 1998 COAL TAR SAND SLURRY SEAL SURFACE TREATMENT
01/01/1992	IMPORTED	BUILT			True	1992 AC PAVEMENT

Network: 2R4 **Branch:** RW 18-36 **(RUNWAY 18-36)** **Section:** 6105 **Surface:** AAC
L.C.D.: 01/01/1992 **Use:** RUNWAY **Rank:**P **Length:** 3.700.00 Ft **Width:** 75.00 Ft **True Area:** 277.500.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	IMPORTED	OVERLAY		1.00	True	1992: 1" - 4.64" AC OVERLAY
01/01/1992	IMPORTED	OVERLAY			True	SOIL: SP
01/01/1968	IMPORTED	BUILT		1.00	True	1968: 1" AC ON 6" COMPACTED SAND/CLAY

Date:05/19/2011

Work History Report

2 of 4

Pavement Database:

Network: 2R4 Branch: TW A (TAXIWAY A TO T-HANGARS) Section: 105 Surface: AC
 L.C.D.: 01/01/1992 Use: TAXIWAY Rank:T Length: 500.00 Ft Width: 25.00 Ft True Area: 12.760.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	IMPORTED	BUILT		3.00	True	1992: 3" AC ON 6" SAND/CLAY BASE
01/01/1992	IMPORTED	OVERLAY			True	SOIL: SP

Network: 2R4 Branch: TW A (TAXIWAY A TO T-HANGARS) Section: 110 Surface: AC
 L.C.D.: 01/01/1995 Use: TAXIWAY Rank:P Length: 450.00 Ft Width: 25.00 Ft True Area: 11.250.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1995	IMPORTED	BUILT		3.00	True	1995 3" P401 ON 6" P213

Network: 2R4 Branch: TW A (TAXIWAY A TO T-HANGARS) Section: 115 Surface: AC
 L.C.D.: 01/01/1995 Use: TAXIWAY Rank:P Length: 1.040.00 Ft Width: 25.00 Ft True Area: 27.010.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1995	IMPORTED	BUILT			True	1995 AC PAVEMENT

Network: 2R4 Branch: TW A (TAXIWAY A TO T-HANGARS) Section: 120 Surface: AC
 L.C.D.: 01/01/1996 Use: TAXIWAY Rank:P Length: 200.00 Ft Width: 25.00 Ft True Area: 6.720.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1996	IMPORTED	BUILT			True	1996 AC PAVEMENT

Network: 2R4 Branch: TW A (TAXIWAY A TO T-HANGARS) Section: 500 Surface: AC
 L.C.D.: 01/01/2007 Use: TAXIWAY Rank:P Length: 380.00 Ft Width: 25.00 Ft True Area: 9.340.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2007	NC-AC	New Construction - AC	\$0	2.00	True	

Network: 2R4 Branch: TW A (TAXIWAY A TO T-HANGARS) Section: 510 Surface: AC
 L.C.D.: 01/01/2001 Use: TAXIWAY Rank:P Length: 1.518.00 Ft Width: 25.00 Ft True Area: 38.830.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2001	NC-AC	New Construction - AC	\$0	3.00	True	

Network: 2R4 Branch: TW B (TAXIWAY B) Section: 205 Surface: AC
 L.C.D.: 01/01/1992 Use: TAXIWAY Rank:P Length: 4.200.00 Ft Width: 25.00 Ft True Area: 104.950.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	IMPORTED	BUILT		3.00	True	1992: 3" AC ON 6" SAND/CLAY BASE

Network: 2R4 Branch: TW B (TAXIWAY B) Section: 210 Surface: AC
 L.C.D.: 01/01/1992 Use: TAXIWAY Rank:P Length: 250.00 Ft Width: 25.00 Ft True Area: 8.970.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	IMPORTED	OVERLAY			True	SOIL: SP
01/01/1992	IMPORTED	BUILT		3.00	True	1992: 3" AC ON 6" SAND/CLAY BASE

Network: 2R4 Branch: TW B (TAXIWAY B) Section: 215 Surface: AC
 L.C.D.: 01/01/1996 Use: TAXIWAY Rank:P Length: 250.00 Ft Width: 25.00 Ft True Area: 9.340.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1996	IMPORTED	BUILT			True	1996 AC PAVEMENT

Date:05/19/2011

Work History Report

3 of 4

Pavement Database:

Network: 2R4 **Branch:** TW B (TAXIWAY B) **Section:** 250 **Surface:** AC
L.C.D.: 01/01/1992 **Use:** TAXIWAY **Rank:**P **Length:** 100.00 Ft **Width:** 35.00 Ft **True Area:** 4.620.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	IMPORTED	BUILT			True	1992 AC PAVEMENT

Network: 2R4 **Branch:** TW CONN CT (CENTER CONNECTOR TAXIWAY) **Section:** 405 **Surface:** AAC
L.C.D.: 01/01/1992 **Use:** TAXIWAY **Rank:**P **Length:** 160.00 Ft **Width:** 40.00 Ft **True Area:** 7.440.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	ML-OL	Mill and Overlay	\$0	0.00	True	ESTIMATE 1970 AC PAVEMENT SOIL: SP
01/01/1970	IMPORTED	BUILT			True	
01/01/1970	IMPORTED	OVERLAY			True	

Network: 2R4 **Branch:** TW CONN CT (CENTER CONNECTOR TAXIWAY) **Section:** 410 **Surface:** AAC
L.C.D.: 01/01/1992 **Use:** TAXIWAY **Rank:**P **Length:** 40.00 Ft **Width:** 40.00 Ft **True Area:** 2.850.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1992	IMPORTED	OVERLAY			True	1992 FEATHERED P401 AC OVERLAY 1970 2" P401 ON 6" P213
01/01/1970	IMPORTED	BUILT		2.00	True	

Network: 2R4 **Branch:** TW CONN E (EAST CONNECTOR TAXIWAY) **Section:** 305 **Surface:** AC
L.C.D.: 01/01/1968 **Use:** TAXIWAY **Rank:**P **Length:** 250.00 Ft **Width:** 40.00 Ft **True Area:** 11,170.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1968	IMPORTED	BUILT		1.00	True	1968: 1" AC ON 6" SAND-CLAY BASE SOIL: SP
01/01/1968	IMPORTED	OVERLAY			True	



Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	18	910,850.00	2.30	.95
Mill and Overlay	3	115,980.00	.00	.00
New Construction - AC	3	133,530.00	2.33	.58
OVERLAY	9	760,820.00	1.00	
REPAIR	1	60,360.00		

STD = Standard Deviation

APPENDIX B

2011 CONDITION MAP PAVEMENT CONDITION INDEX TABLE



LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS
DESIGNED:	ELT	DRAWN: ALB
CHECKED:	DRB	DATE:



2011 CONDITION MAP
PETER PRINCE FIELD AIRPORT
MILTON, SANTA ROSA, FLORIDA
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER
2R4
FOOT DISTRICT
3

Table B-1: Pavement Condition Index

Branch Name	Branch ID	Branch Use	Section ID	True Area (ft ²)	Section Rank	Surface Type	Total Samples Inspected	Total Samples	PCI	PCI Category
Apron East	AP E	APRON	4105	90,760	P	AC	3	16	79	Satisfactory
Apron East	AP E	APRON	4110	71,870	P	AAC	2	16	77	Satisfactory
Apron East	AP E	APRON	4115	36,670	P	AAC	1	9	76	Satisfactory
Apron East	AP E	APRON	4120	49,870	P	AC	1	10	82	Satisfactory
Apron East	AP E	APRON	4125	116,740	P	AC	3	24	88	Good
Apron East	AP E	APRON	4130	85,360	P	AC	3	22	77	Satisfactory
Apron West	AP W	APRON	4205	60,360	P	AC	2	12	47	Poor
Runway 18-36	RW 18-36	RUNWAY	6105	277,500	P	AAC	15	74	76	Satisfactory
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	105	12,760	T	AC	2	5	92	Good
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	110	11,250	P	AC	1	4	78	Satisfactory
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	115	27,010	P	AC	3	11	82	Satisfactory
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	120	6,720	P	AC	1	2	89	Good
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	500	9,340	P	AC	1	2	95	Good
Taxiway Alpha to T-Hangars	TW A	TAXIWAY	510	38,830	P	AC	1	8	82	Satisfactory
Taxiway Bravo	TW B	TAXIWAY	205	104,950	P	AC	4	21	77	Satisfactory
Taxiway Bravo	TW B	TAXIWAY	210	8,970	P	AC	1	1	53	Poor
Taxiway Bravo	TW B	TAXIWAY	215	9,340	P	AC	1	2	71	Satisfactory
Taxiway Bravo	TW B	TAXIWAY	250	4,620	P	AC	1	1	48	Poor
Center Connector Taxiway	TW CONN CT	TAXIWAY	405	7,440	P	AAC	1	2	77	Satisfactory
Center Connector Taxiway	TW CONN CT	TAXIWAY	410	2,850	P	AAC	1	1	75	Satisfactory
East Connector Taxiway	TW CONN E	TAXIWAY	305	11,170	P	AC	1	2	73	Satisfactory

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

APPENDIX C

**BRANCH CONDITION REPORT
SECTION CONDITION REPORT**

Date: 3 /17/2011

Branch Condition Report

1 of 2

Pavement Database: NetworkID: 2R4

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	PCI Standard Deviation	Weighted Average PCI
AP E (APRON EAST)	6	1,875.00	229.33	451,270.00	APRON	79.83	4.14	80.72
AP W (APRON WEST)	1	255.00	235.00	60,360.00	APRON	47.00	0.00	47.00
RW 18-36 (RUNWAY 18-36)	1	3,700.00	75.00	277,500.00	RUNWAY	76.00	0.00	76.00
TW A (TAXIWAY A TO T-HANGARS)	6	4,088.00	25.00	105,910.00	TAXIWAY	86.33	6.07	84.37
TW B (TAXIWAY B)	4	4,800.00	27.50	127,880.00	TAXIWAY	62.25	12.07	73.83
TW CONN CT (CENTER CONNECTOR TAXIWAY)	2	200.00	40.00	10,290.00	TAXIWAY	76.00	1.00	76.45
TW CONN E (EAST CONNECTOR TAXIWAY)	1	250.00	40.00	11,170.00	TAXIWAY	73.00	0.00	73.00

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	7	511,630.00	75.14	12.11	76.74
RUNWAY	1	277,500.00	76.00	0.00	76.00
TAXIWAY	13	255,250.00	76.31	13.04	78.27
All	21	1,044,380.00	75.90	12.43	76.92

STD = Standard Deviation

Date: 3 /17/2011

Section Condition Report

1 of 2

Pavement Database: NetworkID: 2R4

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP E (APRON EAST)	4105	01/01/1992	AC	APRON	P	0	90,760.00	02/08/2011	19	79.00
AP E (APRON EAST)	4110	01/01/2000	AAC	APRON	P	0	71,870.00	02/08/2011	11	77.00
AP E (APRON EAST)	4115	01/01/2000	AAC	APRON	P	0	36,670.00	02/08/2011	11	76.00
AP E (APRON EAST)	4120	01/01/1995	AC	APRON	P	0	49,870.00	02/08/2011	16	82.00
AP E (APRON EAST)	4125	01/01/1996	AC	APRON	P	0	116,740.00	02/08/2011	15	88.00
AP E (APRON EAST)	4130	01/01/2007	AC	APRON	P	0	85,360.00	02/08/2011	4	77.00
AP W (APRON WEST)	4205	01/01/1992	AC	APRON	P	0	60,360.00	02/08/2011	19	47.00
RW 18-36 (RUNWAY 18-36)	6105	01/01/1992	AAC	RUNWAY	P	0	277,500.00	02/08/2011	19	76.00
TW A (TAXIWAY A TO T-HANGARS)	105	01/01/1992	AC	TAXIWAY	T	0	12,760.00	02/08/2011	19	92.00
TW A (TAXIWAY A TO T-HANGARS)	110	01/01/1995	AC	TAXIWAY	P	0	11,250.00	02/08/2011	16	78.00
TW A (TAXIWAY A TO T-HANGARS)	115	01/01/1995	AC	TAXIWAY	P	0	27,010.00	02/08/2011	16	82.00
TW A (TAXIWAY A TO T-HANGARS)	120	01/01/1996	AC	TAXIWAY	P	0	6,720.00	02/08/2011	15	89.00
TW A (TAXIWAY A TO T-HANGARS)	500	01/01/2007	AC	TAXIWAY	P	0	9,340.00	02/08/2011	4	95.00
TW A (TAXIWAY A TO T-HANGARS)	510	01/01/2001	AC	TAXIWAY	P	0	38,830.00	02/08/2011	10	82.00
TW B (TAXIWAY B)	205	01/01/1992	AC	TAXIWAY	P	0	104,950.00	02/08/2011	19	77.00
TW B (TAXIWAY B)	210	01/01/1992	AC	TAXIWAY	P	0	8,970.00	02/08/2011	19	53.00
TW B (TAXIWAY B)	215	01/01/1996	AC	TAXIWAY	P	0	9,340.00	02/08/2011	15	71.00
TW B (TAXIWAY B)	250	01/01/1992	AC	TAXIWAY	P	0	4,620.00	02/08/2011	19	48.00
TW CONN CT (CENTER CONNECTOR TAXIWAY)	405	01/01/1992	AAC	TAXIWAY	P	0	7,440.00	02/08/2011	19	77.00
TW CONN CT (CENTER CONNECTOR TAXIWAY)	410	01/01/1992	AAC	TAXIWAY	P	0	2,850.00	02/08/2011	19	75.00
TW CONN E (EAST CONNECTOR TAXIWAY)	305	01/01/1968	AC	TAXIWAY	P	0	11,170.00	02/08/2011	43	73.00

Date: 3 /17/2011

Section Condition Report

2 of 2

Pavement Database:

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
03-05	4.00	94,700.00	2	86.00	9.00	78.78
06-10	10.00	38,830.00	1	82.00	0.00	82.00
11-15	13.40	241,340.00	5	80.20	7.08	82.27
16-20	18.25	658,340.00	12	72.17	13.91	74.46
over 40	43.00	11,170.00	1	73.00	0.00	73.00
All	16.52	1,044,380.00	21	75.90	12.43	76.92


APPENDIX D

PAVEMENT CONDITION PREDICTION TABLE PREDICTED PCI BY PAVEMENT USE GRAPH

Table D-1: Pavement Condition Prediction

Branch Name	Branch ID	Section ID	Current PCI	PCI Forecast									
				2011	2012	2013	2014	2015	2016	2017	2018	2019	2020
Apron East	AP E	4105	79	78	77	76	74	73	71	70	68	67	65
Apron East	AP E	4110	77	76	74	72	71	69	67	65	64	62	60
Apron East	AP E	4115	76	75	73	72	70	68	66	64	63	61	59
Apron East	AP E	4120	82	81	80	79	77	76	74	73	71	70	68
Apron East	AP E	4125	88	87	86	85	83	82	80	79	77	76	74
Apron East	AP E	4130	77	76	75	74	72	71	69	68	66	65	63
Apron West	AP W	4205	47	46	45	44	42	41	39	38	36	35	33
Runway 18-36	RW 18-36	6105	76	75	73	71	69	67	65	64	62	60	58
Taxiway Alpha to T-Hangars	TW A	105	92	91	90	88	86	84	83	81	79	78	76
Taxiway Alpha to T-Hangars	TW A	110	78	77	76	74	72	70	69	67	65	64	62
Taxiway Alpha to T-Hangars	TW A	115	82	81	80	78	76	74	73	71	69	68	66
Taxiway Alpha to T-Hangars	TW A	120	89	88	87	85	83	81	80	78	76	75	73
Taxiway Alpha to T-Hangars	TW A	500	95	94	93	91	89	87	86	84	82	81	79
Taxiway Alpha to T-Hangars	TW A	510	82	81	80	78	76	74	73	71	69	68	66
Taxiway Bravo	TW B	205	77	76	75	73	71	69	68	66	64	63	61
Taxiway Bravo	TW B	210	53	52	51	49	47	45	44	42	40	39	37
Taxiway Bravo	TW B	215	71	70	69	67	65	63	62	60	58	57	55
Taxiway Bravo	TW B	250	48	47	46	44	42	40	39	37	35	34	32
Center Connector Taxiway	TW CONN CT	405	77	76	75	73	71	69	68	66	64	62	61
Center Connector Taxiway	TW CONN CT	410	75	74	73	71	69	67	66	64	62	60	59
East Connector Taxiway	TW CONN E	305	73	72	71	69	67	65	64	62	60	59	57

Figure D-1: Predicted PCI by Pavement Use



APPENDIX E

YEAR 1 MAINTENANCE ACTIVITIES TABLE

Table E-1: Year 1 Maintenance Activities

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Apron East	AP E	4105	L & T CR	M	Crack Sealing - AC	280.7	Ft	\$2.25	\$631.48
Apron East	AP E	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	8,419.20	SqFt	\$0.40	\$3,367.72
Apron East	AP E	4110	OIL SPILLAGE	N	Patching - AC Shallow	213.1	SqFt	\$2.90	\$617.93
Apron East	AP E	4110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	12,673.60	SqFt	\$0.40	\$5,069.49
Apron East	AP E	4115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	15,334.70	SqFt	\$0.40	\$6,133.94
Apron East	AP E	4120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	5,024.60	SqFt	\$0.40	\$2,009.87
Apron East	AP E	4125	WEATH/RAVEL	L	Surface Seal - Rejuvenating	6,361.80	SqFt	\$0.40	\$2,544.74
Apron East	AP E	4130	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,225.60	SqFt	\$0.40	\$1,290.23
Apron East	AP E	4130	WEATH/RAVEL	M	Surface Seal - Coat Tar	8,402.30	SqFt	\$0.40	\$3,360.93
Runway 18-36	RW 18-36	6105	L & T CR	H	Crack Sealing - AC	246.7	Ft	\$2.25	\$555.03
Runway 18-36	RW 18-36	6105	L & T CR	M	Crack Sealing - AC	1,262.90	Ft	\$2.25	\$2,841.55
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	16,279.90	SqFt	\$0.40	\$6,512.00
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	M	Surface Seal - Coat Tar	794.3	SqFt	\$0.40	\$317.71
Taxiway Alpha to T-Hangars	TW A	105	L & T CR	M	Crack Sealing - AC	38.3	Ft	\$2.25	\$86.15
Taxiway Alpha to T-Hangars	TW A	110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	400	SqFt	\$0.40	\$160.00
Taxiway Alpha to T-Hangars	TW A	115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,099.60	SqFt	\$0.40	\$1,639.84
Taxiway Alpha to T-Hangars	TW A	120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	171.4	SqFt	\$0.40	\$68.57
Taxiway Alpha to T-Hangars	TW A	500	WEATH/RAVEL	L	Surface Seal - Rejuvenating	236.7	SqFt	\$0.40	\$94.69
Taxiway Alpha to T-Hangars	TW A	510	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,659.60	SqFt	\$0.40	\$1,863.84
Taxiway Bravo	TW B	205	L & T CR	H	Crack Sealing - AC	307.6	Ft	\$2.25	\$692.08
Taxiway Bravo	TW B	205	L & T CR	M	Crack Sealing - AC	879.5	Ft	\$2.25	\$1,978.97
Taxiway Bravo	TW B	205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	17,806.40	SqFt	\$0.40	\$7,122.64
Taxiway Bravo	TW B	215	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,982.90	SqFt	\$0.40	\$1,593.19
Taxiway Bravo	TW B	215	L & T CR	M	Crack Sealing - AC	278.8	Ft	\$2.25	\$627.30

Table E-1: Year 1 Maintenance Activities (Continued)

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Center Connector Taxiway	TW CONN CT	405	L & T CR	M	Crack Sealing - AC	108.7	Ft	\$2.25	\$244.49
Center Connector Taxiway	TW CONN CT	405	WEATH/RAVEL	L	Surface Seal - Rejuvenating	383.5	SqFt	\$0.40	\$153.40
Center Connector Taxiway	TW CONN CT	410	L & T CR	M	Crack Sealing - AC	50	Ft	\$2.25	\$112.51
East Connector Taxiway	TW CONN E	305	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,468.90	SqFt	\$0.40	\$1,387.59
East Connector Taxiway	TW CONN E	305	L & T CR	M	Crack Sealing - AC	95.4	Ft	\$2.25	\$214.66
								Total =	\$53,292.54

APPENDIX F

MAJOR M&R PLAN BY YEAR UNDER UNLIMITED FUNDING SCENARIO TABLE



Table F-1: Major M&R Plan by Year under Unlimited Funding Scenario

Year	Branch Name	Section ID	Surface Type	Section Area (ft ²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	Apron West	4205	AC	60,360	\$379,664.43	46	Mill and Overlay	100
2011	Taxiway Bravo	210	AC	8,970	\$51,272.53	52	Mill and Overlay	100
2011	Taxiway Bravo	250	AC	4,620	\$29,059.80	47	Mill and Overlay	100
2015	Taxiway Bravo	215	AC	9,340	\$27,342.39	63	Mill and Overlay	100
2016	East Connector Taxiway	305	AC	11,170	\$30,145.50	64	Mill and Overlay	100
2017	Apron East	4115	AAC	36,670	\$101,933.63	64	Mill and Overlay	100
2017	Runway 18-36	6105	AAC	277,500	\$771,382.15	64	Mill and Overlay	100
2017	Center Connector Taxiway	410	AAC	2,850	\$7,922.30	64	Mill and Overlay	100
2018	Apron East	4110	AAC	71,870	\$205,774.46	64	Mill and Overlay	100
2018	Taxiway Bravo	205	AC	104,950	\$300,487.40	64	Mill and Overlay	100
2018	Center Connector Taxiway	405	AAC	7,440	\$21,301.82	64	Mill and Overlay	100
2019	Taxiway Alpha to T-Hangars	110	AC	11,250	\$33,176.73	64	Mill and Overlay	100
2019	Apron East	4130	AC	85,360	\$289,687.70	63	Mill and Overlay	100
Total					\$2,249,150.84	60		100

* Costs are adjusted for inflation.

APPENDIX G

10-YEAR M&R MAP



LEGEND

- RW 13-3 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

YEAR		ACTIVITY	
<div></div>	2011	<div></div>	MICROSURFACING
<div></div>	2012	<div></div>	MILL AND OVERLAY
<div></div>	2013	<div></div>	RECONSTRUCTION
<div></div>	2014	<div></div>	CONCRETE PAVEMENT RESTORATION
<div></div>	2015	<div></div>	
<div></div>	2016	<div></div>	
<div></div>	2017	<div></div>	
<div></div>	2018	<div></div>	
<div></div>	2019	<div></div>	
<div></div>	2020	<div></div>	

"PLAN YEAR"

"BRANCH"; "SECTION"

"M AND R ACTIVITY"

"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER		DATE		REVISIONS	
DESIGNED:	ELT	DRAWN:	ALB	CHECKED:	DRB
				DATE:	



10-YEAR M & R MAP

PETER PRINCE FIELD AIRPORT
MILTON, SANTA ROSA, FLORIDA

FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER
2R4
FOOT DISTRICT
3

APPENDIX H

PHOTOGRAPHS



Hangars, Section 4125, Sample Unit 500 – Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Hangars, Section 4125, Sample Unit 500 – Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Hangars, Section 4130, Sample Unit 116 – Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Hangars, Section 4130, Sample Unit 116 – Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Apron, Section 4205, Sample Unit 251 – Medium severity (43) Block Cracking, high severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Apron, Section 4205, Sample Unit 251 – Medium severity (43) Block Cracking, high severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Runway 18-36, Section 6105, Sample Unit 171 – Low and medium severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Runway 18-36, Section 6105, Sample Unit 171 – Low and medium severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Runway 18-36, Section 6105, Sample Unit 135 – Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Runway 18-36, Section 6105, Sample Unit 135 – Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Taxiway Connector, Section 250, Sample Unit 200 – Low, medium and high severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Taxiway Connector, Section 250, Sample Unit 200 – Low, medium and high severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Taxiway B-3, Section 210, Sample Unit 200 – Medium and high severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling



Taxiway B-3, Section 210, Sample Unit 200 – Medium and high severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling

APPENDIX I

PCI RE-INSPECTION REPORT

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: AP E Name: APRON EAST Use: APRON Area: 451,270.00SqFt

Section: 4105 of 6 From: - To: - Last Const.: 1/1/1992
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 90,760.00SqFt Length: 300.00Ft Width: 267.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 16 Surveyed: 3
Conditions: PCI: 79.00 |
Inspection Comments: KHA

Sample Number: 51 Type: R Area: 6,170.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 305.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 50.00 Ft Comments:
52 WEATHERING/RAVELING L 500.00 SqFt Comments:

Sample Number: 200 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 210.00 Ft Comments:
52 WEATHERING/RAVELING L 500.00 SqFt Comments:

Sample Number: 500 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 247.00 Ft Comments:
52 WEATHERING/RAVELING L 500.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: AP E Name: APRON EAST Use: APRON Area: 451,270.00SqFt

Section: 4110 of 6 From: - To: - Last Const.: 1/1/2000
Surface: AAC Family: FDOT-GA-AP-AAC Zone: Category: Rank: P
Area: 71,870.00SqFt Length: 400.00Ft Width: 150.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 16 Surveyed: 2
Conditions: PCI:77.00 |
Inspection Comments: KHA

Sample Number: 105 Type: R Area: 8,610.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 494.00 Ft Comments:
52 WEATHERING/RAVELING L 1,200.00 SqFt Comments:
50 PATCHING L 8.00 SqFt Comments:

Sample Number: 203 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 214.00 Ft Comments:
49 OIL SPILLAGE N 30.00 SqFt Comments:
52 WEATHERING/RAVELING L 1,200.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: AP E Name: APRON EAST Use: APRON Area: 451,270.00SqFt

Section: 4115 of 6 From: - To: - Last Const.: 1/1/2000
Surface: AAC Family: FDOT-GA-AP-AAC Zone: Category: Rank: P
Area: 36,670.00SqFt Length: 250.00Ft Width: 150.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 9 Surveyed: 1
Conditions: PCI:76.00 |
Inspection Comments: KHA

Sample Number: 101 Type: R Area: 5,500.00SqFt
Sample Comments:
52 WEATHERING/RAVELING L 2,300.00 SqFt Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 406.00 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: AP E Name: APRON EAST Use: APRON Area: 451,270.00SqFt

Section: 4120 of 6 From: - To: - Last Const.: 1/1/1995
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 49,870.00SqFt Length: 210.00Ft Width: 267.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 10 Surveyed: 1
Conditions: PCI:82.00 |
Inspection Comments: KHA

Sample Number: 750 Type: R Area: 3,970.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 168.00 Ft Comments:
52 WEATHERING/RAVELING L 400.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: AP E Name: APRON EAST Use: APRON Area: 451,270.00SqFt

Section: 4125 of 6 From: - To: - Last Const.: 1/1/1996
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 116,740.00SqFt Length: 440.00Ft Width: 267.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 24 Surveyed: 3
Conditions: PCI:88.00 |
Inspection Comments: KHA

Sample Number: 150 Type: R Area: 4,400.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 8.00 Ft Comments:
52 WEATHERING/RAVELING L 200.00 SqFt Comments:

Sample Number: 300 Type: R Area: 4,500.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 65.00 Ft Comments:
52 WEATHERING/RAVELING L 300.00 SqFt Comments:

Sample Number: 451 Type: R Area: 5,780.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 126.00 Ft Comments:
52 WEATHERING/RAVELING L 300.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: AP E Name: APRON EAST Use: APRON Area: 451,270.00SqFt

Section: 4130 of 6 From: - To: - Last Const.: 1/1/2007
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 85,360.00SqFt Length: 275.00Ft Width: 275.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 22 Surveyed: 3
Conditions: PCI:77.00 |
Inspection Comments: KHA

Sample Number: 100 Type: R Area: 3,550.00SqFt
Sample Comments:
52 WEATHERING/RAVELING M 384.00 SqFt Comments:
52 WEATHERING/RAVELING L 300.00 SqFt Comments:

Sample Number: 108 Type: R Area: 3,650.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 94.00 Ft Comments:
52 WEATHERING/RAVELING M 684.00 SqFt Comments:

Sample Number: 116 Type: R Area: 3,650.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 61.00 Ft Comments:
52 WEATHERING/RAVELING L 110.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: AP W Name: APRON WEST Use: APRON Area: 60,360.00SqFt

Section: 4205 of 1 From: - To: - Last Const.: 1/1/1992
Surface: AC Family: FDOT-GA-AP-AC Zone: Category: Rank: P
Area: 60,360.00SqFt Length: 255.00Ft Width: 235.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 12 Surveyed: 2
Conditions: PCI:47.00 |
Inspection Comments: KHA

Sample Number: 150 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 100.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING H 232.00 Ft Comments:
52 WEATHERING/RAVELING L 2,000.00 SqFt Comments:

Sample Number: 251 Type: R Area: 5,000.00SqFt
Sample Comments:
43 BLOCK CRACKING M 1,200.00 SqFt Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING H 225.00 Ft Comments:
52 WEATHERING/RAVELING L 2,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: RW 18-36 Name: RUNWAY 18-36 Use: RUNWAY Area: 277,500.00SqFt

Section: 6105 of 1 From: - To: - Last Const.: 1/1/1992
Surface: AAC Family: FDOT-GA-RW-AAC Zone: Category: Rank: P
Area: 277,500.00SqFt Length: 3,700.00Ft Width: 75.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 74 Surveyed: 15

Conditions: PCI:76.00 |

Inspection Comments: KHA

Sample Number: 101 Type: R Area: 3,750.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	184.00	Ft	Comments:
52	WEATHERING/RAVELING	L	300.00	SqFt	Comments:
52	WEATHERING/RAVELING	M	161.00	SqFt	Comments:

Sample Number: 105 Type: R Area: 3,750.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	194.00	Ft	Comments:
52	WEATHERING/RAVELING	L	200.00	SqFt	Comments:

Sample Number: 109 Type: R Area: 3,750.00SqFt

Sample Comments:

52	WEATHERING/RAVELING	L	100.00	SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	205.00	Ft	Comments:

Sample Number: 114 Type: R Area: 3,750.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	100.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	H	50.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	71.00	Ft	Comments:
52	WEATHERING/RAVELING	L	300.00	SqFt	Comments:

Sample Number: 120 Type: R Area: 3,750.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	223.00	Ft	Comments:
52	WEATHERING/RAVELING	L	400.00	SqFt	Comments:

Sample Number: 123 Type: R Area: 3,750.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	206.00	Ft	Comments:
52	WEATHERING/RAVELING	L	100.00	SqFt	Comments:

Sample Number: 127 Type: R Area: 3,750.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	235.00	Ft	Comments:
52	WEATHERING/RAVELING	L	100.00	SqFt	Comments:

Sample Number: 131 Type: R Area: 3,750.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	219.00	Ft	Comments:
52	WEATHERING/RAVELING	L	100.00	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Sample Number:	135	Type:	R	Area:	3,750.00SqFt		
Sample Comments:							
48	LONGITUDINAL/TRANSVERSE	CRACKING		L	235.00	Ft	Comments:
52	WEATHERING/RAVELING			L	300.00	SqFt	Comments:

Sample Number:	141	Type:	R	Area:	3,750.00SqFt		
Sample Comments:							
48	LONGITUDINAL/TRANSVERSE	CRACKING		L	264.00	Ft	Comments:
52	WEATHERING/RAVELING			L	300.00	SqFt	Comments:

Sample Number:	149	Type:	R	Area:	3,750.00SqFt		
Sample Comments:							
48	LONGITUDINAL/TRANSVERSE	CRACKING		L	160.00	Ft	Comments:
52	WEATHERING/RAVELING			L	300.00	SqFt	Comments:

Sample Number:	156	Type:	R	Area:	3,750.00SqFt		
Sample Comments:							
48	LONGITUDINAL/TRANSVERSE	CRACKING		L	270.00	Ft	Comments:
52	WEATHERING/RAVELING			L	300.00	SqFt	Comments:

Sample Number:	162	Type:	R	Area:	3,750.00SqFt		
Sample Comments:							
48	LONGITUDINAL/TRANSVERSE	CRACKING		L	251.00	Ft	Comments:
52	WEATHERING/RAVELING			L	300.00	SqFt	Comments:

Sample Number:	167	Type:	R	Area:	3,750.00SqFt		
Sample Comments:							
52	WEATHERING/RAVELING			L	100.00	SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE	CRACKING		L	256.00	Ft	Comments:

Sample Number:	171	Type:	R	Area:	3,750.00SqFt		
Sample Comments:							
48	LONGITUDINAL/TRANSVERSE	CRACKING		M	106.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE	CRACKING		L	100.00	Ft	Comments:
52	WEATHERING/RAVELING			L	100.00	SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW A Name: TAXIWAY A TO T-HANGARS Use: TAXIWAY Area: 105,910.00SqFt

Section: 105 of 6 From: - To: - Last Const.: 1/1/1992
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: T
Area: 12,760.00SqFt Length: 500.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 5 Surveyed: 2
Conditions: PCI:92.00 |
Inspection Comments: KHA

Sample Number: 101 Type: R Area: 2,500.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 3.00 Ft Comments:

Sample Number: 103 Type: R Area: 2,500.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 15.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 35.00 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW A Name: TAXIWAY A TO T-HANGARS Use: TAXIWAY Area: 105,910.00SqFt

Section: 110 of 6 From: - To: - Last Const.: 1/1/1995
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 11,250.00SqFt Length: 450.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 4 Surveyed: 1
Conditions: PCI:78.00 |
Inspection Comments: KHA

Sample Number: 107 Type: R Area: 2,500.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 152.00 Ft Comments:
52 WEATHERING/RAVELING L 100.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW A Name: TAXIWAY A TO T-HANGARS Use: TAXIWAY Area: 105,910.00SqFt

Section: 115 of 6 From: - To: - Last Const.: 1/1/1995
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 27,010.00SqFt Length: 1,040.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 11 Surveyed: 3
Conditions: PCI:82.00 |
Inspection Comments: KHA

Sample Number: 112 Type: R Area: 2,500.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 79.00 Ft Comments:
52 WEATHERING/RAVELING L 100.00 SqFt Comments:

Sample Number: 116 Type: R Area: 2,500.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 85.00 Ft Comments:
52 WEATHERING/RAVELING L 500.00 SqFt Comments:

Sample Number: 118 Type: R Area: 2,580.00SqFt
Sample Comments:
52 WEATHERING/RAVELING L 500.00 SqFt Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 88.00 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW A Name: TAXIWAY A TO T-HANGARS Use: TAXIWAY Area: 105,910.00SqFt

Section: 120 of 6 From: - To: - Last Const.: 1/1/1996
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 6,720.00SqFt Length: 200.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 2 Surveyed: 1
Conditions: PCI:89.00 |
Inspection Comments: KHA

Sample Number: 101 Type: R Area: 3,920.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 61.00 Ft Comments:
52 WEATHERING/RAVELING L 100.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW A Name: TAXIWAY A TO T-HANGARS Use: TAXIWAY Area: 105,910.00SqFt

Section: 500 of 6 From: - To: - Last Const.: 1/1/2007
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 9,340.00SqFt Length: 380.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 2 Surveyed: 1
Conditions: PCI:95.00 |
Inspection Comments: KHA

Sample Number: 98 Type: R Area: 4,340.00SqFt
Sample Comments:
52 WEATHERING/RAVELING L 110.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW A Name: TAXIWAY A TO T-HANGARS Use: TAXIWAY Area: 105,910.00SqFt

Section: 510 of 6 From: - To: - Last Const.: 1/1/2001
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 38,830.00SqFt Length: 1,518.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 8 Surveyed: 1
Conditions: PCI:82.00 |
Inspection Comments: KHA

Sample Number: 103 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 200.00 Ft Comments:
52 WEATHERING/RAVELING L 600.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 127,880.00SqFt

Section: 205 of 4 From: - To: - Last Const.: 1/1/1992
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 104,950.00SqFt Length: 4,200.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 21 Surveyed: 4
Conditions: PCI:77.00 |
Inspection Comments: KHA

Sample Number: 103 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 200.00 Ft Comments:
52 WEATHERING/RAVELING L 500.00 SqFt Comments:

Sample Number: 111 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 226.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 36.00 Ft Comments:
52 WEATHERING/RAVELING L 1,000.00 SqFt Comments:

Sample Number: 117 Type: R Area: 5,000.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 113.00 Ft Comments:
52 WEATHERING/RAVELING L 1,000.00 SqFt Comments:

Sample Number: 120 Type: R Area: 4,450.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 127.00 Ft Comments:
52 WEATHERING/RAVELING L 800.00 SqFt Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING H 57.00 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 127,880.00SqFt

Section: 210 of 4 From: - To: - Last Const.: 1/1/1992
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 8,970.00SqFt Length: 250.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 1 Surveyed: 1
Conditions: PCI:53.00 |
Inspection Comments: KHA

Sample Number: 200 Type: R Area: 8,970.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 110.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING H 351.00 Ft Comments:
52 WEATHERING/RAVELING L 2,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 127,880.00SqFt

Section: 215 of 4 From: - To: - Last Const.: 1/1/1996
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 9,340.00SqFt Length: 250.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 2 Surveyed: 1
Conditions: PCI: 71.00 |
Inspection Comments: KHA

Sample Number: 100 Type: R Area: 4,690.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 140.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 25.00 Ft Comments:
52 WEATHERING/RAVELING L 2,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 127,880.00SqFt

Section: 250 of 4 From: - To: - Last Const.: 1/1/1992
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 4,620.00SqFt Length: 100.00Ft Width: 35.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 1 Surveyed: 1
Conditions: PCI:48.00 |
Inspection Comments: KHA

Sample Number: 200 Type: R Area: 4,620.00SqFt

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	16.00 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	62.00 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	H	190.00 Ft	Comments:
52	WEATHERING/RAVELING	L	1,100.00 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW CONN CT Name: CENTER CONNECTOR TAXIWAY Use: TAXIWAY Area: 10,290.00SqFt

Section: 405 of 2 From: - To: - Last Const.: 1/1/1992
Surface: AAC Family: FDOT-GA-TW-AAC Zone: Category: Rank: P
Area: 7,440.00SqFt Length: 160.00Ft Width: 40.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 2 Surveyed: 1
Conditions: PCI:77.00 |
Inspection Comments: KHA

Sample Number: 401	Type: R	Area: 5,820.00SqFt	
Sample Comments:			
48 LONGITUDINAL/TRANSVERSE CRACKING	M	85.00 Ft	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	100.00 Ft	Comments:
52 WEATHERING/RAVELING	L	300.00 SqFt	Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW CONN CT Name: CENTER CONNECTOR TAXIWAY Use: TAXIWAY Area: 10,290.00SqFt

Section: 410 of 2 From: - To: - Last Const.: 1/1/1992
Surface: AAC Family: FDOT-GA-TW-AAC Zone: Category: Rank: P
Area: 2,850.00SqFt Length: 40.00Ft Width: 40.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 1 Surveyed: 1
Conditions: PCI:75.00 |
Inspection Comments: KHA

Sample Number: 400 Type: R Area: 2,850.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 230.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 50.00 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: 3/17/2011

Site Name:

Network: 2R4 Name: PETER PRINCE FIELD - MILTON

Branch: TW CONN E Name: EAST CONNECTOR TAXIWAY Use: TAXIWAY Area: 11,170.00SqFt

Section: 305 of 1 From: - To: - Last Const.: 1/1/1968
Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P
Area: 11,170.00SqFt Length: 250.00Ft Width: 40.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 2/8/2011 Total Samples: 2 Surveyed: 1
Conditions: PCI:73.00 |
Inspection Comments: KHA

Sample Number: 101 Type: R Area: 6,440.00SqFt
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 250.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING M 55.00 Ft Comments:
52 WEATHERING/RAVELING L 2,000.00 SqFt Comments: