

# STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION OFFICE

# Statewide Airfield Pavement Management Program

Wauchula Municipal Airport– CHN (General Aviation) Wauchula, Florida (District 1)



# **TABLE OF CONTENTS**

SEC'	TION	AGE NO.
Exec	utive Summary	iii
1.	Introduction	1
2.	Network Definition and Pavement Inventory	10
3.	Pavement Condition	14
4.	Pavement Condition Prediction	20
5.	Maintenance Policies and costs	21
6.	Pavement Rehabilitation Needs Analysis	27
7.	Maintenance and Rehabilitation Plan	30
8.	Visual Aids	31
9.	Recommendations	32
LIST	T OF FIGURES	
	re 1-1: Pavement Life Cycle	
	re 1-2: PCI Rating Scale	
_	re 2-1: Pavement Area by Surface Type	
Figur	re 3-1: Network PCI Distribution by Rating Category	16
	re 3-1a: Condition Rating Summary	
Figur	re 3-2: Percentage of Pavement Area within Each PCI Range by Pavement U	Jse17
Figur	re 4-1: Predicted PCI by Pavement Use	20
Figur	re 6-1: Budget Scenario Analysis	29
LIST	T OF TABLES	
Table	e I: Condition Summary by Branch	iii
Table	e II: Condition Summary by Pavement Use	iv
Table	e III: Condition Summary by Pavement Rank	iv
Table	e IV: 10-Year M&R Costs under Unlimited Funding Scenario	v
Table	e 1-1: Sampling Rate for FDOT Condition Surveys	5
	e 2-1: Construction Since Last Inspection & Anticipated Construction Activity	
	e 2-2: Pavement Area by Pavement Use	•
	e 2-3: Branch and Section Inventory	
Table	e 3-1: Pavement Distresses for Asphalt Concrete Surfaces	14
	e 3-2: Condition by Pavement Use	
Table	e 5-1: Routine Maintenance Activities for Airfield Pavements	22
Table	e 5-2: Critical PCI for General Aviation Airports	23
	e 5-3: Fdot Minimum Service Level PCI for General Aviation Airports	
	e 5-4: M&R Activities for General Aviation Airports	
	e 5-5: Maintenance Unit Costs for FDOT	
	e 5-6: M&R Activities and Unit Costs by Condition for General Aviation Ai	
	e 6-1: Major M&R Plan by Year under Unlimited Budget Scenario	
	e 6-2: Summary of Year 1 Maintenance Activities	
	e 7-1: M&R Costs under Unlimited Funding Scenario	

i

# **TABLE OF CONTENTS**

SECTION PAGE NO.

### APPENDICES

APPENDICE	28
Appendix A	Network Definition Map
	System Inventory Map
	Pavement Inventory Table
	Work History Report
Appendix B	2011 Condition Map
	Pavement Condition Index Table
Appendix C	Branch Condition Report
	Section Condition Report
Appendix D	Pavement Condition Prediction Table
	Predicted PCI by Pavement Use Graph
Appendix E	Year 1 Maintenance Activities Table
Appendix F	Major M&R Plan by Year under Unlimited Funding Scenario Table
Appendix G	10-Year M&R Map
Appendix H	Photographs
Appendix I	PCI Re-inspection Report

#### **EXECUTIVE SUMMARY**

In 2010, the Florida Department of Transportation (FDOT) Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing Statewide Airfield Pavement Management Program (SAPMP) to be completed over fiscal years 2011 and 2012.

The tasks required to achieve this objective at Wauchula Municipal Airport included:

- ➤ Obtain recent construction history from the Airport to update the Pavement Inventory CADD drawings from the previous SAPMP update,
- ➤ Perform a visual Pavement Condition Index (PCI) survey of the airfield pavements at the Airport,
- ➤ Update the MicroPAVER database to analyze the PCI field data and determine the current condition of the airfield pavements,
- > Predict the future deterioration of the pavements,
- ➤ Develop a 10-year M&R plan to address the pavement needs at Wauchula Municipal Airport, and
- ➤ Provide the estimated costs associated with the suggested immediate and future M&R activities

During February 2011, the PCI survey was performed at Wauchula Municipal Airport. The results of the survey indicate that, based on a numerical scale of 0 to 100, the overall area-weighted average PCI of the airfield pavements in 2011 is 71, representing a Satisfactory overall network condition.

Table I below summarizes the overall condition summary by network branch.

**Table I: Condition Summary by Branch** 

Branch Name	Area Weighted PCI	Condition Rating	FDOT Minimum Service Level	MicroPAVER Minimum PCI	Action Required
Apron	74	Satisfactory	60	65	
Runway 18-36	67	Fair	75	65	X
Taxiway to North Hangars	100	Good	65	65	
Taxiway Parallel	69	Fair	65	65	
Taxiway To Hangars	75	Satisfactory	65	65	

Tables II and III below illustrate the area-weighted PCI computed individually for each pavement use and rank, respectively.

**Table II: Condition Summary by Pavement Use** 

Use Average Area- Weighted PCI		Condition Rating
Runway	67	Fair
Taxiway	75	Satisfactory
Apron	74	Satisfactory
All (Weighted)	71	Satisfactory

**Table III: Condition Summary by Pavement Rank** 

Rank*	Average Area- Weighted PCI	Condition Rating
Primary	69	Fair
Tertiary	100	Good
All (Weighted)	71	Satisfactory

<sup>\*</sup>The pavement rank for the airport pavement network is listed on Table 2-3.

Based upon the policies set by the Florida Department of Transportation Aviation office and the analysis of the condition survey data; the airport did not warrant any immediate major rehabilitation work. The current weighted average PCI value of 71, a condition rating of Satisfactory, indicate that the pavement does not exhibit any substantial distress that could impact the operation of aircraft over the facilities.

A forecast of Major M&R needs for a 10-year period, starting from 2011, was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval. The results of this analysis are provided in Table IV below.

Table IV: 10-Year M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$164,596.07	\$0.00	\$164,596.07
2012	\$133,785.89	\$0.00	\$133,785.89
2013	\$44,720.98	\$957,578.85	\$1,002,299.83
2014	\$48,433.09	\$31,690.36	\$80,123.45
2015	\$44,672.04	\$81,251.97	\$125,924.01
2016	\$38,443.74	\$125,043.40	\$163,487.14
2017	\$37,366.63	\$56,234.45	\$93,601.08
2018	\$10,511.54	\$317,315.27	\$327,826.81
2019	\$12,777.63	\$0.00	\$12,777.63
2020	\$16,878.05	\$0.00	\$16,878.05
Total	\$552,185.66	\$1,569,114.30	\$2,121,299.96

Note: Costs are adjusted for inflation.

The implementation of the 10-Year major M&R plan is expected to provide an improvement in the overall condition of the airfield pavement, where the area-weighted PCI would increase from 71 in 2011 to 89 in 2020. Appendix F lists the major M&R for the 10-Year program. Appendix G graphically depicts the activity.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all Wauchula Municipal Airport pavements in 2020 may remain near 89. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for Wauchula Municipal Airport is conducted at some point in the 10-Year plan.

#### 1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. There are millions of square yards of pavement for the runways, taxiways, aprons and other areas of these airports that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time.

In order to support the planning, scheduling, and design of the M&R activities based on pavement evaluation and pavement management performance trends, the Florida Department of Transportation (FDOT) Aviation Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992.

In 2010, the FDOT Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

This report discusses the work performed, a summary of the findings, results, and recommendations for M&R planning associated with the update to the SAPMP. It also describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented during the performance of the SAPMP.

#### 1.1 Purpose

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the SAPMP and the roles and responsibilities of the program's participants;
- Provide background information on pavement management principles, objectives, and benefits to this airport;
- Outline the procedures used to collect, evaluate and report pavement inspection results at this airport;
- Present the findings from the pavement inspection;
- Analyze and discuss the needs for Maintenance and Rehabilitation (M&R) activities and associated costs for this airport.

#### 1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The 1992 SAPMP provided valuable information for establishing and performing pavement M&R.

In 1992/1993, and 1998/1999, the FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement maintenance. This system, AIRPAV, was implemented, and initial condition surveys were

performed in 1992 and 1993. The SAPMP was updated with additional surveys in 1998 and 1999.

In 2004, the FDOT Aviation Office undertook a project to update the pavement management system software utilized for the SAPMP. This project involved a review of the AIRPAV software and other available pavement management system software. As a result of this review, MicroPAVER was selected as the software for the update project. Data from the 1998/1999 condition surveys were converted to the MicroPAVER system, and the inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999. The pavements were inspected between 2006 and 2008, and an updated M&R program was developed based on the new condition of the airfield pavements. As part of the update, procedures for the inspection and collection of pavement data were developed, and a website (www.floridaairportpavement.com) was created for the input of data under secure procedures.

Currently, airports using the AIP Grant Program are required by the Federal Aviation Administration (FAA) to develop a pavement maintenance program (FAA/AC 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements") using trained personnel to perform a detailed inspection of airfield pavements. The inspections are required to be performed at least once a year or every 3 years if pavement inspection is characterized in the form of a Pavement Condition Index (PCI) survey (such as ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys", (2004 edition)). The 2004 edition was utilized in lieu of the 2010 edition to maintain database integrity and benefit of pavement performance curves from the previous inspections.

In 2010, the FDOT Aviation Office selected a team consisting of the Consultant and their Subconsultants to provided services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

#### 1.3 Organization

#### 1.3.1 Aviation Office Program Manager Role

The Aviation Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) monitoring the work of the Consultant. The AO-PM has review and approval authority for each program task and also manages the day-to-day details of the SAPMP and the updates.

#### 1.3.2 Consultant Role

The Consultant (Kimley-Horn and Associates, Inc.) and their Subconsultants (MACTEC Engineering and Consulting and All About Pavements, Inc.) provide technical and administrative assistance to the AO-PM during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the SAPMP based upon procedures outlined in FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

#### 1.3.3 Airport Role

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP update, indicate any construction activity that has been performed since the previous inspections.

#### 1.4 Pavement Types and Pavement Management

#### 1.4.1 Pavement basics

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of an asphalt concrete (AC) surface, and
- Rigid pavement composed of a Portland Cement Concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying natural subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland Cement Concrete supports most of the load, and the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the construction of the concrete surface.

A small percentage of the airport pavements in Florida are composed of asphalt concrete surface over Portland Cement Concrete (APC). This pavement type is known as "composite" pavement.

Due to the different nature of the pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

#### 1.4.2 Pavement Management System Concept

The SAPMP utilized a Pavement Management System (PMS) to develop the M&R recommendations discussed in this report. A PMS is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1 below, taken from FAA/AC 5380-7A "Airport Pavement Management Program", illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in "good" condition depends on how well it is maintained. As the illustration demonstrates, the cost of maintaining the pavement above a critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.




Figure 1-1: Pavement Life Cycle

Source: FAA/AC 150/5380-7A "Airport Pavement Management Program" \*Modified to reflect current construction costs.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi-year M&R plan can be determined.

#### 1.4.3 Pavement Inspection Methodology for the SAPMP

Pavement condition assessment is one of the primary decision variables in any airport PMS. Pavement condition assessments generally include visual surveys in accordance with ASTM D 5340, "Standard Test Method for Airport Pavement Condition Index Surveys" and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the Statewide Aviation Pavement Management Program update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine the appropriate rehabilitation methods during the design process.

In preparation of the PCI surveys, the airfield pavements are divided into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Further discussion of how the airport pavements are divided and subdivided into units by construction and use can be found in Section 2 "Network Definition and Pavement Inventory" of this report.

Sample unit sizes are approximately  $5000 \pm 2000$  square feet for AC-surfaced pavements and  $20 \pm 8$  slabs for PCC-surfaced pavements. Prior to conducting the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of Branches, Sections, use patterns, construction types and history. The sampling rate used for the FDOT Statewide Airfield Pavement Management Program is provided in Table 1-1 below.

**Table 1-1: Sampling Rate for FDOT Condition Surveys** 

AC Pavements				PCC Paveme	ents	
NI	n		NI	n		
N	Runway	Others	N	Runway	Others	
1-4	1	1	1-3	1	1	
5-10	2	1	4-6	2	1	
11-15	3	2	7-10	3	2	
16-30	5	3	11-15	4	2	
31-40	7	4	16-20	5	3	
41-50	8	5	21-30	7	3	
<u>≥</u> 51	20% but <u>&lt;</u> 20	10% but ≤10	31-40	8	4	
			41-50	10	5	
			<u>≥</u> 51	20% but <u>&lt;</u> 20	10% but <u>&lt;</u> 10	

Where

N = total number of sample units in Section

n = number of sample units to inspect

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the Section. In the case when nonrepresentive distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each Section. PCI values range from 0 to 100. As Figure 1-2 below indicates, MicroPAVER provides a rating scale that relates PCI to pavement condition. A PCI between 0 and 10 is considered 'Failed' pavement, and a PCI between 86 and 100 is considered 'Good' pavement, with five other conditions for PCI values between 11 and 85.

Figure 1-2: PCI Rating Scale

PCI	Condition Rating	
86 – 100	Good	
71 – 85	Satisfactory	
56 – 70	Fair	
41 – 55	Poor	
26 – 40 Very Poor		
11 – 25	Serious	
0 – 10 Failed		

#### 1.5 Definitions

<u>Aviation Office</u> - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office Program Manager (AO-PM) has review and approval authority for each program task of the SAPMP.

<u>Base Course</u> - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

<u>Branch</u> - A Branch designates pavements that have common usage and functionality, such as an entire runway, taxiway, or apron.

<u>Branch ID</u> - A short form identification for the pavement Branch. In this report, Branch includes the common designation for the item e.g. RW 18-36.

<u>Category</u> - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA for general aviation or community airports;
- RL for regional relievers or small hubs;
- PR for primary (certified under Part 139 requirements).

<u>Critical PCI</u> - The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

<u>Distress Type</u> - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland Cement Concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

<u>Florida DOT (FDOT)</u> - Florida Department of Transportation was represented in this project by the Office of Aviation.

<u>Global M&R</u> - Global M&R is defined as activities applied to entire pavement Sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

<u>Localized M&R (Maintenance and Repair)</u> - Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

<u>Major M&R (e.g. Rehabilitation)</u> - Activities performed over the entire area of a pavement Section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

<u>MicroPAVER</u> - A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that, if properly implemented, maintained, and operated, it meets the pavement management program requirements described by the FAA in Advisory Circular 150/5380-7A.

<u>Minimum Condition Level</u> - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

<u>Network Definition</u> - A Network Definition is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport is in Appendix A along with a table of inventory data.

<u>Pavement Condition Index (PCI)</u> - The Pavement Condition Index is a number which represents the condition of a pavement segment at a specific point in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340, published by ASTM International.

<u>Pavement Evaluation</u> - A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

<u>Pavement Management System (PMS)</u> - A Pavement Management System is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

Pavement Surface Type - The surface of pavement is identified as one of four types:

- AC for asphalt surface pavements;
- PCC for Portland Cement Concrete pavements;
- AAC for asphalt surface pavements that have had an asphalt overlay at some point in their construction history;
- APC for composite pavements, which consist of asphalt over Portland Cement Concrete pavement.
- PAC for composite pavements, which consist of Portland Cement Concrete over asphalt pavement.

<u>Rank</u> - Pavement rank in MicroPAVER determines the priority to be assigned to a pavement Section when developing an M&R plan. Pavement Sections are ranked as follows according to their use:

- P for Primary pavements, such as primary runways, primary taxiways, and primary aprons;
- S or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons;
- T for Tertiary pavements such as "T" hangars and slightly used aprons.

<u>Reconstruction</u> - Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

<u>Rehabilitation</u> - Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

<u>Sample Unit</u> - Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are  $5,000 \pm 2,000$  square feet for AC-surfaced pavements and  $20 \pm 8$  slabs for PCC-surfaced pavements.

<u>Section</u> - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition, and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

<u>Section ID</u> - A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series Sections are taxiways, 4000 and 5000 series Sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series Sections are runways.

<u>Statewide Airfield Pavement Management Program (SAPMP)</u> – The Statewide Airfield Pavement Management Program is a program implemented in 1992 by the Florida Department of Transportation to plan, schedule, and design the maintenance and rehabilitation activities

necessary for the airfield pavement on Florida's public airports to allow the airports to operate efficiently, economically, and without excessive down time.

<u>System Inventory</u> - A System Inventory is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline and identifies airfield construction activities since the last inspection. The System Inventory for the airport is included in Appendix A.

<u>Use</u> - In MicroPAVER, Use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

#### 2. NETWORK DEFINITION AND PAVEMENT INVENTORY

Wauchula Municipal Airport (CHN) consists of one single runway; RW 18-36, which is 75-ft wide by 4,005-ft long. The airport is served by a parallel taxiway which is 35-ft wide. Currently the airport has two separate T-Hangar facilities located on the west side of RW 18-36 and tiedown spaces located on the apron. All of the pavement for the runway, taxiways, apron and hangars is constructed with Asphalt Concrete.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric dimensions may vary slightly from the geometry used in the condition and M&R analysis based on field measurements.

Wauchula Municipal Airport is publicly owned by the City of Wauchula and is operated by the Wauchula Municipal Airport Authority. Opened in 1983, Wauchula Municipal Airport serves many local businesses, including spraying operators for the local agricultural industry, along with providing for flight training, aircraft repair, aircraft storage and fueling.

This airport is designated as a General Aviation airport and is located in District 1 of the Florida Department of Transportation.

#### 2.1 Network Definition

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units.

#### 2.1.1 Branch Section Identification

The airport pavement network is subdivided into separate Branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then further divided into Sections with similar pavement construction and performance that may share other common attributes.

Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage. A pavement rank, consisting of primary, secondary, and tertiary levels, is assigned to each Section based on their level and type of use. The pavement rankings that were designated for each Section in the previous SAPMP update were again used for this update.

As discussed in Section 1.4.3 "Pavement Inspection Methodology for the SAPMP", the sections are sub-divided into sample units, which are the smallest subdivision in a pavement network, only for the purpose of conducting the pavement condition survey.

#### 2.1.2 System Inventory and Network Definition Update

The System Inventory and Network Definition drawings are used to identify changes in the network since the most recent update from the 2006/2008 inspections and also to plan the field inspection activities for the 2011 survey. Prior to the field inspection process, the System Inventory drawing was updated from the previous inspection with notes indicating recent construction projects on the various Sections of pavement throughout the airfield. This System Inventory drawing is used to update the Network Definition drawing.

The Network Definition drawing shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The previous airport configuration and history was compared with the current airport configuration, and the existing network branch, section and sample unit designations were revised to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important historical record.

The updated System Inventory and Network Definition drawings for Wauchula Municipal Airport are provided in Appendix A. Table 2-1 below lists the recent construction projects at the airport.

**Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity** 

Construction Year	Location	Work Type / Pavement Section
2009	Mid Field West of Taxiway	New Pad

As indicated by the airport, no recent construction projects have occurred on the airfield pavement since the previous update.

#### 2.2 Pavement Inventory

The detailed pavement inventory was updated to reflect the network definition update and field inspection results.


The total airfield pavement area in 2011 at Wauchula Municipal Airport is 617,430 square feet. The breakdown of pavement area for each pavement use is provided in Table 2-2.

**Table 2-2: Pavement Area by Pavement Use** 

Use	Area (ft²)	% of Total Area
Runway	300,300	49%
Taxiway	263,805	43%
Apron	53,325	8%
All	617,430	100%

Figure 2-1 presents the breakdown of the pavement area at Wauchula Municipal Airport by surface type.

Figure 2-1: Pavement Area by Surface Type



Details of pavement Branch and Section information including Branch name (which indicates pavement use), Branch ID, Section ID, section area, rank, surface type, last construction date, number of samples inspected, and number of samples in each Section are given in Table 2-3 below. A more detailed Pavement Inventory Table may be found in Appendix A of this report.

**Table 2-3: Branch and Section Inventory** 

Branch Name	Branch ID	Section ID	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Sample Units in Section
Apron	AP	4105	53,325	P	AC	1/1/1991	1	10
Runway 18-36	RW 18-36	6105	300,300	P	AC	1/1/1991	23	80
Taxiway to North Hangars	T-HANG N	240	34,675	T	AC	7/31/2008	0	9
Taxiway Parallel	TW PARALL	105	11,020	P	AC	1/1/1993	1	3
Taxiway Parallel	TW PARALL	110	11,150	P	AC	1/1/1993	1	3
Taxiway Parallel	TW PARALL	125	31,010	P	AC	1/1/1993	2	8
Taxiway Parallel	TW PARALL	160	9,230	P	AC	1/1/1993	1	2
Taxiway Parallel	TW PARALL	115	41,470	P	AC	1/1/1996	3	12
Taxiway Parallel	TW PARALL	120	59,150	P	AC	1/1/1996	3	17
Taxiway to Hangars	TW T-HANG	205	24,330	P	AC	1/1/1991	2	6
Taxiway to Hangars	TW T-HANG	210	21,540	P	AC	1/1/1991	2	5
Taxiway to Hangars	TW T-HANG	235	20,230	P	AC	1/1/1996	2	8

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

#### 3. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340-04 "Standard Practice for Airport Pavement Condition Index Surveys." These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

#### 3.1 Inspection Methodology

A PCI survey is performed by measuring the amount and severity of pavement distresses, which are caused by traffic load, climate, and other factors, observed within a sample unit. This data is imported into MicroPAVER, which calculates PCI values for the pavement sections. Table 3-1 below lists the pavement distress types and related causes for asphalt concrete (AC).

**Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces** 

Code	Distress	Mechanism
41	Alligator Cracking	Load
42	Bleeding	Construction Quality / Mix Design
43	Block Cracking	Climate / Age
44	Corrugation	Load / Construction Quality
45	Depression	Subgrade Quality
46	Jet Blast	Aircraft
47	Joint Reflection - Cracking	Climate / Prior Pavement
48	Longitudinal/Transverse Cracking	Climate / Age
49	Oil Spillage	Aircraft / Vehicle
50	Patching	Utility / Pavement Repair
51	Polished Aggregate	Load
52	Weathering/Raveling	Climate / Load
53	Rutting	Load
54	Shoving Pavement Growth	
55	Slippage Cracking Load / Pavement Bond	
56	Swelling	Climate / Subgrade Quality

Prior to conducting the inspections, Global Positioning System (GPS) coordinates were recorded using CADD at the centroid of each sample unit. The centroid is usually the geometric center of the area, but in cases where sample units are irregular in shape, this is the center of mass. These data are presented in a table on the updated Network Definition Map in Appendix A of this report.

Pavement condition inspections at Wauchula Municipal Airport were performed in February 2011. Data were recorded in the field in accordance with FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

After the completion of data collection, the data was imported into MicroPAVER, and PCI values were calculated for the pavement sections.

#### 3.2 Pavement Condition Index Results

According to the 2011 survey, the overall area-weighted PCI at Wauchula Municipal Airport is 71, representing a Satisfactory overall network condition.

Overall the airport exhibited pavement distresses associated with climate and age distresses. Asphalt Concrete pavement distresses include; weathering, raveling, longitudinal and transverse cracking, and block cracking distresses of which are common of pavements of similar age.

Runway 18-36, exhibited low to medium severity weathering and raveling in addition to longitudinal cracks primarily located along the paving joints. This is a common distress due to the pavement being weakest at the joint locations. There were also isolated locations along the runway which exhibited low severity block cracking.

New hangar spaces were added towards the north side of the airfield along with new hangar and taxiway pavement. The recently constructed pavement was assumed to have a PCI of 100.

Appendix B contains a table and a Condition Map which depicts the PCI results by Section, and Appendix C contains a table of PCI results by Branch. Appendix I includes detailed distress data generated by MicroPAVER for each inspected sample unit.

Figure 3-1 provides the PCI distribution by rating category for Wauchula Municipal Airport.

Satisfactory 31%
Fair 63%

Figure 3-1: Network PCI Distribution by Rating Category

**Figure 3-1a: Condition Rating Summary** 

Condition Rating	Total Area (ft²)	Percent	
Good	34,675	6%	
Satisfactory	191,905	31%	
Fair	390,850	63%	
Poor	0	0%	
Very Poor	0	0%	
Serious	0	0%	
Failed	0	0%	

Approximately 37% of the network is in Good and Satisfactory condition while 63% of the network is in Fair condition. Table 3-3 illustrates the area-weighted PCI computed individually for each pavement use.


**Table 3-2: Condition by Pavement Use** 

Use	Area-Weighted PCI	Condition Rating		
Runway	67	Fair		
Taxiway	75	Satisfactory		
Apron	74	Satisfactory		
All (Weighted)	71	Fair		


Figure 3-2 presents the breakdown of PCI by range for each pavement use.

Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use






# (b) Taxiway



# (c) Apron



#### 4. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 4-1 illustrates the predicted performance of pavements at Wauchula Municipal Airport based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum service level for General Aviation (GA) airports.




Figure 4-1: Predicted PCI by Pavement Use

Appendix D presents the tabular summary of the predicted Section PCI for each year from 2011 to 2020.

#### 5. MAINTENANCE POLICIES AND COSTS

#### 5.1 Policies

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature and are recommended to help achieve the performance goal.

Table 5-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules. These repairs are used only in the first year of an analysis.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called "Critical PCI." The critical PCI levels for different pavement and branch types established in the previous SAPMP update were used in this update for the development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 5-2 gives the critical PCI levels for General Aviation Airports.

The maintenance rehabilitation policy and activity costs have been updated based on the study of readily available construction cost data at the time of this study. The costs depicted in this report are intended for planning purposes.

**Table 5-1: Routine Maintenance Activities for Airfield Pavements** 

Surface	Distress	Severity*	Work Type	Code	Work Unit
	Alligator Crack	M, H	Patching - AC Deep	PA-AD	SqFt
	Bleeding	N/A	No Localized M&R	NONE	N/A
	Block Crack	M, H	Crack Sealing – AC	CS-AC	SqFt
	Corrugation	L, M, H	Patching - AC Deep	PA-AD	SqFt
	Depression	M, H	Patching - AC Deep	PA-AD	SqFt
	Jet Blast	N/A	Patching - AC Deep	PA-AD	SqFt
	Joint Ref. Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	L & T Crack	M, H	Crack Sealing – AC	CS-AC	Ft
AC	Oil Spillage	N/A	Patching - AC Shallow	PA-AS	SqFt
AC	Patching	M, H	Patching - AC Deep	PA-AD	SqFt
	Polished Agg.	N/A	No Localized M&R	NONE	N/A
	Daviding and	L	Surface Sealing - Rejuvenating	SS-RE	SqFt
	Raveling and Weathering	M	Surface Seal - Coal Tar	SS-CT	SqFt
	weathering	Н	Microsurfacing	MI-AC	SqFt
	Rutting	M, H	Patching - AC Deep	PA-AD	SqFt
	Shoving	M, H	Grinding (Localized)	GR-LL	SqFt
	Slippage Crack		Patching - AC Shallow	PA-AS	SqFt
	Swelling M		Patching - AC Deep	PA-AD	SqFt
	Blow-Up	L, M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Corner Break	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Linear Crack	M, H	Crack Sealing – PCC	CS-PC	Ft
	Durability Crack	Н	Slab Replacement – PCC	SL-PC	SqFt
	Durability Clack	M	Patching - PCC Full Depth	PA-PF	SqFt
	Jt. Seal Damage	M, H	Joint Seal (Localized)	JS-LC	Ft
	Small Patch	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
PCC	Large Patch	M, H	Patching - PCC Full Depth	PA-PF	SqFt
rcc	Popouts	N/A	No Localized M&R	NONE	N/A
	Pumping	N/A	No Localized M&R	NONE	N/A
	Scaling	Н	Slab Replacement – PCC	SL-PC	SqFt
	Faulting	M, H	Grinding (Localized)	GR-PP	Ft
	Shattered Slab	M, H	Slab Replacement – PCC	SL-PC	SqFt
	Shrinkage Crack	N/A	No Localized M&R	NONE	N/A
	Joint Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Corner Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt

<sup>\*</sup>L = Low, M = Medium, H = High

**Table 5-2: Critical PCI for General Aviation Airports** 

Use	Critical PCI
Runway	65
Taxiway	65
Apron	65

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 5-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of General Aviation Airports.

**Table 5-3: Fdot Minimum Service Level PCI for General Aviation Airports** 

Minimum PCI					
Runway Taxiway Apron					
75	65	60			

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 5-2 the PCI trigger range when the likely activity would be a mill and resurface was 40 to 79 and reconstruction at a PCI of 39 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 5-4 summarizes the M&R activities for General Aviation Airports based on PCI value.

Table 5-4: M&R Activities for General Aviation Airports

	Activity	PCI Range
Maintenance	Crack Sealing and Full-Depth Patching	80 and 90
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	40 to 79
	Reconstruction	39 and less

#### 5.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were updated from the previous SAPMP study based on current construction cost trends in order to determine meaningful costs for the program. Table 5-5 presents the unit costs summary.

#### 5.3 M&R Activities

FDOT recognizes that although Mill and Overlay work is recommended for asphalt pavements within a PCI range from 40 to 79, it is conceivable that airports may not have adequate funding to perform this type of rehabilitation. Microsurfacing treatment is a maintenance/rehabilitation measure that can be used in lieu of asphalt pavement mill and overlay; however it should be understood that this measure is intended for short term pavement life extension. While the cost of microsurfacing is significantly lower than that of pavement mill and overlay, it is not intended to be a full rehabilitative measure for long term benefit.

**Table 5-5: Maintenance Unit Costs for FDOT** 

Code	Name	Cost	Unit
GR-LL	Grinding (Localized for AC)	\$2.10	SqFt
PA-AL	Patching – AC Leveling	\$2.30	SqFt
PA-AS	Patching – AC Shallow	\$2.90	SqFt
PA-PF	Patching – PCC Full Depth	\$38.11	SqFt
PA-PP	Patching – PCC Partial Depth	\$19.06	SqFt
SL-PC	Slab Replacement – PCC	\$39.11	SqFt
CS-PC	Crack Sealing – PCC	\$4.24	Ft
UN-PC	Undersealing – PCC	\$3.40	Ft
CS-AC	Crack Sealing – AC	\$2.25	Ft
GR-PP	Grinding (Localized for PCC)	\$22.51	Ft
JS-LC	Joint Seal (Localized)	\$2.00	Ft
SH-LE	Shoulder Leveling	\$2.81	Ft
JS-SI	Joint Seal – Silicon	\$2.81	Ft
PA-AD	Patching – AC Deep	\$4.90	SqFt
OL-AT	Overlay – AC Thin	\$2.80	SqFt
SS-CT	Surface Seal – Coal Tar	\$0.40	SqFt
SS-FS	Surface Seal – Fog Seal	\$0.40	SqFt
SS-RE	Surface Seal – Rejuvenating	\$0.40	SqFt
ST-SB	Surface Treatment – Single Bitum.	\$0.30	SqFt
ST-SS	Surface Treatment – Slurry Seal	\$0.55	SqFt
ST-ST	Surface Treatment – Sand Tar	\$0.28	SqFt
MI-AC	Microsurfacing - AC	\$0.65	SqFt

The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection was performed recently and only in the first year of the M&R analysis. In subsequent years, MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCIs. That is, for low PCI, it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly.

Using available unit cost data, the Major M&R Cost by Condition table was set up as shown in Table 5-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

Table 5-6: M&R Activities and Unit Costs by Condition for General Aviation Airports

	Activity	PCI Trigger	Cost/SqFt
Maintenance	Crack Sealing and Full-Depth Patching	90	\$0.06
Wantenance	Crack Scannig and I un-Depth I atching	80	\$0.24
		70	\$3.00
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	60	\$3.42
		50	\$6.29
		40	\$6.29
	Reconstruction	30	\$13.62
	Reconstruction	20	\$13.62

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

#### 6. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years, starting from 2011. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Table 6-1 presents the M&R list of 10-Year needs for Major M&R. The importance of this listing is that it points out the major activities triggered by the current and predicted conditions of the pavements.

Table 6-1: Major M&R Plan by Year under Unlimited Budget Scenario

Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	N	Aajor M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2013	Runway 18-36	6105	AC	300,300	\$	741,673.96	64	Mill and Overlay	100
2013	Taxiway Parallel	105	AC	11,020	\$	27,216.94	64	Mill and Overlay	100
2013	Taxiway Parallel	120	AC	59,150	\$	163,218.66	63	Mill and Overlay	100
2013	Taxiway Parallel	160	AC	9,230	\$	25,469.29	63	Mill and Overlay	100
2014	Taxiway Parallel	110	AC	11,150	\$	31,690.36	63	Mill and Overlay	100
2015	Taxiway Parallel	125	AC	31,010	\$	81,251.97	64	Mill and Overlay	100
2016	Taxiway Parallel	115	AC	41,470	\$	125,043.40	63	Mill and Overlay	100
2017	Taxiway to Hangars	235	AC	20,230	\$	56,234.45	64	Mill and Overlay	100
2018	Apron	4105	AC	53,325	\$	170,581.55	63	Mill and Overlay	100
2018	Taxiway to Hangars	205	AC	24,330	\$	77,829.33	63	Mill and Overlay	100
2018	Taxiway to Hangars	210	AC	21,540	\$	68,904.39	63	Mill and Overlay	100
				Total		\$1,569,114.30	63		100

<sup>\*</sup> Costs are adjusted for inflation.

In addition to the 10-Year Major M&R needs, maintenance activities for pavement areas currently above critical PCI have been recommended by MicroPAVER for the immediate activity and are shown in Table 6-2 below. The costs provided in Table 5-5 were used to calculate the costs associated with this work, which is intended to treat specific distress types. A more detailed table is provided in Appendix E.

**Table 6-2: Summary of Year 1 Maintenance Activities** 

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description		Work Unit	Unit Cost	Work Cost
Apron	AP	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	30,336.00	SqFt	\$0.40	\$12,134.51
Runway 18-36	RW 18-36	6105	L & T CR	M	Crack Sealing - AC	174.10	Ft	\$2.25	\$391.72
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	224,571.90	SqFt	\$0.40	\$89,829.51
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	M	Surface Seal - Coat Tar	7,311.60	SqFt	\$0.40	\$2,924.66
Taxiway Parallel	TW PARALL	105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	7,064.10	SqFt	\$0.40	\$2,825.67
Taxiway Parallel	TW PARALL	105	WEATH/RAVEL	M	Surface Seal - Coat Tar	706.40	SqFt	\$0.40	\$282.56
Taxiway Parallel	TW PARALL	110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	6,453.40	SqFt	\$0.40	\$2,581.36
Taxiway Parallel	TW PARALL	115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	30,016.40	SqFt	\$0.40	\$12,006.65
Taxiway Parallel	TW PARALL	120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	47,319.90	SqFt	\$0.40	\$18,928.14
Taxiway Parallel	TW PARALL	125	WEATH/RAVEL	L	Surface Seal - Rejuvenating	24,808.00	SqFt	\$0.40	\$9,923.27
Taxiway Parallel	TW PARALL	160	WEATH/RAVEL	M	Surface Seal - Coat Tar	1,197.40	SqFt	\$0.40	\$478.96
Taxiway Parallel	TW PARALL	160	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,390.50	SqFt	\$0.40	\$1,756.21
Taxiway to Hangars	TW T-HANG	205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	11,283.50	SqFt	\$0.40	\$4,513.42
Taxiway to Hangars	TW T-HANG	210	WEATH/RAVEL	L	Surface Seal - Rejuvenating	7,292.90	SqFt	\$0.40	\$2,917.17
Taxiway to Hangars	TW T-HANG	210	WEATH/RAVEL	M	Surface Seal - Coat Tar	78.10	SqFt	\$0.40	\$31.26
Taxiway to Hangars	TW T-HANG	235	WEATH/RAVEL	L	Surface Seal - Rejuvenating	7,677.40	SqFt	\$0.40	\$3,071.00
								Total =	\$164,596.07

The 10 year forecast results are shown in Figure 6-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.




Figure 6-1: Budget Scenario Analysis

The following network level observations can be made from the figure above:

- The PCI will deteriorate from 71 in 2011 to 55 in ten years if no M&R activities are performed.
- The PCI will remain at or above 89 through the 10-year analysis period under the unlimited budget scenario. A 2020 PCI of 89 with this scenario is 18 PCI points higher than a "No M&R" scenario. The total cost for Major M&R over this 10-year period is about \$1.6 million.

#### 7. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels, the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCIs less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 7-1 provides the summary results under the critical PCI unlimited funding scenario.

Table 7-1: M&R Costs under Unlimited Funding Scenario

Year	Preventative	Major M&R	Total Year Cost
2011	\$164,596.07	\$0.00	\$164,596.07
2012	\$133,785.89	\$0.00	\$133,785.89
2013	\$44,720.98	\$957,578.85	\$1,002,299.83
2014	\$48,433.09	\$31,690.36	\$80,123.45
2015	\$44,672.04	\$81,251.97	\$125,924.01
2016	\$38,443.74	\$125,043.40	\$163,487.14
2017	\$37,366.63	\$56,234.45	\$93,601.08
2018	\$10,511.54	\$317,315.27	\$327,826.81
2019	\$12,777.63	\$0.00	\$12,777.63
2020	\$16,878.05	\$0.00	\$16,878.05
Total	\$552,185.66	\$1,569,114.30	\$2,121,299.96

Note: Costs are adjusted for inflation.

The unlimited budget scenario provides the basis for estimating the total repair cost.

Appendix F provides details of M&R plan by year under the unlimited funding scenario, and the map of the 10-year M&R plan is provided in Appendix G. It is important to understand that the SAPMP is a network level tool and the M&R costs provided in this report are only for planning purposes.

Pavement Evaluation Report –Wauchula Municipal Airport Florida Statewide Pavement Management Program May 2011

#### 8. VISUAL AIDS

#### 8.1 System Inventory and Network Definition Drawings

The System Inventory and Network Definition CADD drawings, which show the airport pavement outline with Branch and Section boundaries and identify changes in the network pavement since the last inspection and the sampling plan, respectively, are included in Appendix A of this report.

#### 8.2 Condition Map

A Condition Map that has been prepared based on data linked to the airport's shape file is included in Appendix B. The Condition Map graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

#### 8.3 10-Year M&R Map

A 10-Year M&R Map that shows the summary of the M&R plan is attached in Appendix G.

#### 8.4 Photographs

Selected digital photographs taken during the pavement inspection are provided in Appendix H to provide visual support to special pavement conditions or distress observed during the inspection of the airport.

#### 9. RECOMMENDATIONS

Pavement condition inspections were performed at Wauchula Municipal Airport, and a 10-year M&R plan was developed based on the unlimited funding scenario. No immediate construction activity was identified based on the overall PCI value of 71 for the airport's pavement.


The following recommendations were made based on the 2011 condition inspection and M&R analysis results for the 10-Year M&R program duration:


- **Runway 18-36** Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2013.
- Taxiway Parallel (Sections 105, 120, and 160) Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2013.
- **Taxiway Parallel (Sections 110)** Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2014.
- Taxiway Parallel (Sections 125) Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2015.
- **Taxiway Parallel (Sections 115)** Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2016.
- **Taxiway to Hangars (Section 235)** Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2017.
- **Apron** Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2018.
- Taxiway to Hangars (Sections 205 and 210) Asphalt pavement mill and overlay per the FAA P-401 Specification in the year 2018.

Further evaluation of these features is necessary in order to develop repair plans and timing for future budgets since these needs cannot be addressed with typical annual expenditures.

# **APPENDIX A**

# NETWORK DEFINITION MAP SYSTEM INVENTORY MAP PAVEMENT INVENTORY TABLE WORK HISTORY REPORT





LOCATION	SECTION	SAMPLE	LATITUDE	LONGITU
RW 18-36	6105	101	27.50960401	-81.8804591
RW 18-36	6105	102	27.50974155	-81.8804592
RW 18-36	6105	106	27.5102917	-81.8804599
RW 18-36	6105	107	27.51042924	-81.880460°
RW 18-36	6105	111	27.5109794	-81.8804608
RW 18-36	6105	115	27,51152955	-81.8804615
RW 18-36	6105	116	27.51166709	-81.8804617
RW 18-36	6105	120	27.51221724	-81.8804623
RW 18-36	6105	121	27.51235478	-81.8804625
RW 18-36	6105	124	27.5127674	-81.8804630
RW 18-36	6105	125	27.51290494	-81.8804632
RW 18-36	6105	129	27.51345509	-81.8804639
RW 18-36	6105	130	27.51359263	-81.880464
RW 18-36	6105	136	27.51441786	-81.8804651
RW 18-36	6105	143	27.51538063	-81.8804663
RW 18-36	6105	149	27.51620587	-81.8804673
RW 18-36	6105	150	27.5163434	-81.8804675
RW 18-36	6105	153	27.51675602	-81.8804680
RW 18-36	6105	157	27.51730618	-81.880468
RW 18-36	6105	162	27.51799387	-81,8804696
RW 18-36	6105	166	27.51854402	-81.8804703
RW 18-36	6105	171	27.51923172	-81.880471
RW 18-36	6105	175	27.51978187	-81.8804718
AP	4105	102	27.51318733	-81.8820833
TW T-HANG	235	100	27.51222882	-81.8827786
TW T-HANG	235	201	27.51258868	-81.8831145
TW T-HANG	210	100	27.51305722	-81.8826138
TW T-HANG	210	102	27.51311478	-81.8829243
TW T-HANG	205	100	27.51298588	-81.8806746
TW T-HANG	205	105	27.51298415	-81.8823880
TW PARALL	160	101	27.51496144	-81.880669
TW PARALL	125	101	27.51348877	-81.8812013
TW PARALL	125	105	27.51458908	-81.881202
TW PARALL	120	105	27,51932041	-81,8812086
TW PARALL	120	110	27.51794503	-81.8812069
TW PARALL	120	117	27.51601949	-81.8812045
TW PARALL	115	104	27.51020212	-81.8811972
TW PARALL	115	107	27,51102735	-81.8811982
TW PARALL	115	111	27.51212766	-81.8811996
TW PARALL	110	101	27.52034678	-81.8810312
TW PARALL	105	101	27.50946161	-81.8810175

#### **LEGEND**

RW 13-3) TYPICAL RUNWAY BRANCH ID

TW A TYPICAL TAXIWAY BRANCH ID

TYPICAL APRON BRANCH ID

SECTION NUMBER
PAVEMENT TYPE
TYPICAL SAMPLE UNIT INFORMATION
FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH
RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE

- NUMBER OF SAMPLE UNITS IN SECTION
- NUMBER OF SAMPLE UNITS TO BE INSPECTED



SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.

INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 41

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER DATE 

















# CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY

CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2009	MID FIELD WEST OF TAXIWAY	NEW PAD

#### LEGEND

PROJECTS YEAR 2006
PROJECTS YEAR 2007
PROJECTS YEAR 2008
PROJECTS YEAR 2010
PROJECTS YEAR 2011
PROJECTS YEAR 2012
PROJECTS YEAR 2013
PROJECTS YEAR 2014
PROJECTS YEAR 2015
PROJECTS YEAR 2016
PROJECTS YEAR 2016
PROJECTS YEAR 2017

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

K: \WFB_Aviation\142179	005\CAEO\FLANSHEETS\0	M/DHB12/003-OW-W		PLOTTED: July 11, 2011 -	3:25 PM, BY: Stanford, R							
DESIGNED:	ELT	DRAWN:	ALB	CHECKED:	DRB	DATE:						
NUMBER	DATE			REVIS	SIONS							





SYSTEM INVENTORY MAP

WAUCHULA MUNICIPAL AIRPORT
HARDEE COUNTY, FLORIDA

FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE



Pavement Evaluation Report –Wauchula Municipal Airport Florida Statewide Pavement Management Program May 2011

**Table A-1: Pavement Inventory** 

Branch Name	Branch ID	Branch Use	Section ID	Length (ft)	Width (ft)	True Area (ft²)	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
Apron	AP	APRON	4105	237	225	53,325	P	AC	1/1/1991	2/23/2011	10
Runway 18-36	RW 18-36	RUNWAY	6105	4,004	75	300,300	P	AC	1/1/1991	2/23/2011	80
Taxiway to North Hangars	T-HANG N	TAXIWAY	240	1,285	25	34,675	T	AC	7/31/2008	7/31/2008	9
Taxiway Parallel	TW PARALL	TAXIWAY	105	300	35	11,020	P	AC	1/1/1993	2/23/2011	3
Taxiway Parallel	TW PARALL	TAXIWAY	110	300	35	11,150	P	AC	1/1/1993	2/23/2011	3
Taxiway Parallel	TW PARALL	TAXIWAY	125	845	35	31,010	P	AC	1/1/1993	2/23/2011	8
Taxiway Parallel	TW PARALL	TAXIWAY	160	184	35	9,230	P	AC	1/1/1993	2/23/2011	2
Taxiway Parallel	TW PARALL	TAXIWAY	115	1,144	35	41,470	P	AC	1/1/1996	2/23/2011	12
Taxiway Parallel	TW PARALL	TAXIWAY	120	1,690	35	59,150	P	AC	1/1/1996	2/23/2011	17
Taxiway to Hangars	TW T-HANG	TAXIWAY	205	647	35	24,330	P	AC	1/1/1991	2/23/2011	6
Taxiway to Hangars	TW T-HANG	TAXIWAY	210	980	20	21,540	P	AC	1/1/1991	2/23/2011	5
Taxiway to Hangars	TW T-HANG	TAXIWAY	235	800	25	20,230	P	AC	1/1/1996	2/23/2011	8

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

Date:05/23/2011

# **Work History Report**

1 of 3

Pavement Database:

Network: CHN			1 avon	ient Database:		
Date				237.00 Ft	Width:	
Network: CHN   Series   Runway   Rank: P Length:   4,004.00   Ft   Width:   75,00   Ft   True Area: 300,300.00   Series   Runway   Rank: P Length:   4,004.00   Ft   Width:   75,00   Ft   True Area: 300,300.00   Series   Runway   Rank: P Length:   4,004.00   Ft   Width:   75,00   Ft   True Area: 300,300.00   Series   Runway   Rank: P Length:   4,004.00   Ft   Width:   75,00   Ft   True Area: 300,300.00   Series   Runway   Rank: P Length:   4,004.00   Ft   Width:   5,00   Ft   True Area: 300,300.00   Series   Runway   Rank: P Length:   1,000.00   Runway   Runway						
Lc.D.: 01/01/1991   Use: RUNWAY   Rank: P Length:   4,004,00 Ft   Width:   75,00 Ft   True Area: 30,300,00   SoF	01/01/1991	INITIAL	Initial Construction	\$0	0.00	True
Date   Code   Description   Cost   (in)   M&R   Comments			-		Width:	
Network: CHN						
L.C.D.: 07/31/2008   Use: TAXIWAY   Rank:T Length: 1.285.00 Ft   Width: 25.00 Ft   True Area: 34.675.00 Sofolate   Code   Description   Cost   Thickness   Major   Comments   Comments   Code   Code   Description   Cost   Thickness   Code   Code	01/01/1991	INITIAL	Initial Construction	\$0	0.00	True
Date   Code   Description   Cost   (in)   M&R   Comments			XIWAY Rank: T Length:		•	
Network			-			Comments
C.D.: 01/01/1993   Use: TAXIWAY   Rank: P. Length: 300.00 Ft   Width: 35.00 Ft   True Area: 11.020.00 SqF	07/31/2008	INITIAL	Initial Construction	\$0	0.00	True
Date	<b>L.C.D.</b> : 01/0	01/1993 <b>Use</b> : TA	XIWAY Rank: P Length:	300.00 Ft	_	
Network: CHN			-			Comments
L.C.D.: 01/01/1993   Use: TAXIWAY   Rank:P Length: 300.00 Ft   Width: 35.00 Ft   True Area: 11.150.00 SoF	01/01/1993	INITIAL	Initial Construction	\$0	0.00	True
Date   Code   Description   Cost   (in)   M&R   Comments			· ·	•	Width:	
Network: CHN			-			' I Cammanta
L.C.D.: 01/01/1996   Use: TAXIWAY   Rank: P Length:   1.144.00 Ft   Width:   35.00 Ft   True Area:   41.470.00   SaF	01/01/1993	INITIAL	Initial Construction	\$0	0.00	True
Date   Code   Description   Cost   (in)   M&R   Comments			· ·	•	Width:	
Network:         CHN         Branch:         TW PARALL         (PARALLEL TAXIWAY)         Section:         120         Surface:         AC           L.C.D.:         01/01/1996         Use:         TAXIWAY         Rank:         P Length:         1.690.00         Ft         Width:         35.00         Ft         True Area:         59.150.00         Sq           Work Date         Work Code         Description         Cost         Thickness (in)         Major M&R         Comments           Network:         CHN         Branch:         TW PARALL         (PARALLEL TAXIWAY)         Section:         125         Surface:         AC           L.C.D.:         01/01/1993         Use:         TAXIWAY         Rank:         P Length:         845.00         Ft         Width:         35.00         Ft         True Area:         31.010.00         Sq           Work Date         Work Code         Description         Cost         Thickness (in)         Major M&R         Comments           Network:         CHN         Branch:         TW PARALL         (PARALLEL TAXIWAY)         Section:         160         Surface:         AC           Network:         CHN         Branch:         TW PARALL         (PARALLEL TAXIWAY)         Section:						
L.C.D.: 01/01/1996   Use: TAXIWAY   Rank: P Length: 1.690.00   Ft   Width: 35.00   Ft   True Area: 59.150.00   SqF	01/01/1996	INITIAL	Initial Construction	\$0	0.00	True
Date         Code         Description         Cost         (in)         M&R         Comments           01/01/1996         INITIAL         Initial Construction         \$0         0.00         True           Network: CHN Branch: TW PARALL (PARALLEL TAXIWAY)         Section: 125 Surface: AC           L.C.D.: 01/01/1993         Use: TAXIWAY Rank: P Length: 845.00 Ft         Width: 35.00 Ft         True Area: 31.010.00 SaF           Work Date         Code         Description         Cost         Thickness (in)         Major M&R         Comments           01/01/1993         INITIAL         Initial Construction         \$0         0.00         True         Network: CHN Branch: TW PARALL (PARALLEL TAXIWAY)         Section: 160 Surface: AC           L.C.D.: 01/01/1993         Use: TAXIWAY         Rank: P Length: 184.00 Ft         Width: 35.00 Ft         True Area: 9.230.00 SqF           Work         Work         Work         Thickness         Major         Comments			•	•	Width:	
Network:         CHN         Branch:         TW PARALL         (PARALLEL TAXIWAY)         Section:         125         Surface:         AC           L.C.D.:         01/01/1993         Use:         TAXIWAY         Rank:         P Length:         845.00 Ft         Width:         35.00 Ft         True Area:         31.010.00 SqF           Work Date         Code         Description         Cost         Thickness (in)         Major (magnetic Magnetic				Cost		
Work Date         Work Code         Work Description         Cost         Thickness (in)         Major M&R         Comments           01/01/1993         INITIAL         Initial Construction         \$0         0.00         True         Section: 160         Surface: AC           L.C.D.: 01/01/1993         Use: TAXIWAY         Rank: P Length: 184.00 Ft         Width: 35.00 Ft         True Area: 9.230.00 SqF           Work         Work         Thickness         Major Comments	01/01/1996	INITIAL	Initial Construction	\$0	0.00	True
Date         Code         Description         Cost         (in)         M&R         Comments           01/01/1993         INITIAL         Initial Construction         \$0         0.00         True           Network: CHN Branch: TW PARALL (PARALLEL TAXIWAY)         Section: 160 Surface: AC           L.C.D.: 01/01/1993         Use: TAXIWAY Rank: P Length: 184.00 Ft         Width: 35.00 Ft         True Area: 9.230.00 SqF           Work         Work         Thickness         Major	Network: (			•	Width:	
Network:     CHN     Branch:     TW PARALL     (PARALLEL TAXIWAY)     Section:     160     Surface:     AC       L.C.D.:     01/01/1993     Use:     TAXIWAY     Rank:     P Length:     184.00 Ft     Width:     35.00 Ft     True Area:     9.230.00 SqF       Work     Work     Thickness     Major	<b>L.C.D.</b> : 01/0		Ength:			
L.C.D.:         01/01/1993         Use:         TAXIWAY         Rank:         P Length:         184.00 Ft         Width:         35.00 Ft         True Area:         9.230.00 SqF           Work         Work         Thickness         Major         Comments	Work	Work	Work			Comments
l Commonto	Work	Work Code	Work Description	Cost	( in)	M&R Comments
	Work Date 01/01/1993 Network: (	Work Code INITIAL	Work Description  Initial Construction  anch: TW PARALL (PARALL)	Cost \$0 EL TAXIWAY)	( in) 0.00	M&R Comments  True  Section: 160 Surface: AC
01/01/1993 INITIAL Initial Construction \$0 0.00 True	Work Date 01/01/1993 Network: (L.C.D.: 01/0	Work Code  INITIAL  CHN Br 01/1993 Use: TA  Work	Work Description  Initial Construction  anch: TW PARALL (PARALL AXIWAY Rank: P Length:  Work	Cost \$0 EL TAXIWAY) 184.00 Ft	( in) 0.00 Width:	True   Section: 160   Surface: AC   35.00   Ft   True Area: 9.230.00   SqF   Major   Commonts

Date:05/	23/2011		story Re	port		2 of 3				
Network: C L.C.D.: 01/0		·	Y TO HANGARS) 647.00 Ft	Width:		<b>ction:</b> 205 <b>Surface:</b> AC 00 Ft <b>True Area:</b> 24.330.00 SqF				
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments				
01/01/1991	INITIAL	Initial Construction	\$0	0.00	True					
Network: C L.C.D.: 01/0		•		Width:	20.	ction:         210         Surface:         AC           00 Ft         True Area:         21,540.00         SqF				
Date	Code	Description	Cost	Thickness (in)	Major M&R	Comments				
01/01/1991	INITIAL	Initial Construction	\$0	0.00	True					
	Network:         CHN         Branch:         TW T-HANG         (TAXIWAY TO HANGARS)         Section:         235         Surface:         AC           L.C.D.:         01/01/1996         Use:         TAXIWAY         Rank:         P Length:         800.00         Ft         Width:         25.00         Ft         True Area:         20.230.00         SqF									
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments				
01/01/1996	INITIAL	Initial Construction	\$0	0.00	True					

Date:05/23/2011

# Work History Report

3 of 3

Pavement Database:


Summary:


Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
Initial Construction	12	617,430.00	.00	.00

STD = Standard Deviation

# **APPENDIX B**

# 2011 CONDITION MAP PAVEMENT CONDITION INDEX TABLE





#### <u>LEGEND</u>

TYPICAL RUNWAY BRANCH ID

TW A

TYPICAL TAXIWAY BRANCH ID

AP S

TYPICAL APRON BRANCH ID

PCI 86–100 GOOD

PCI 71–85 SATISFACTORY

PCI 56–70 FAIR

PCI 41–55 POOR

PCI 26–40 VERY POOR

PCI 11–25 SERIOUS

PCI 0–10 FAILED

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

K:\WFB_Aviation\142179	DODS\CACO\FLANSHEETS\C	O-M/DHRITS/003-OIN-00	ONOTTON.dwg		PLOTTED: July 11, 2011 -	3:26 PM, BY: Stonford, R	lex					
DESIGNED:	ELT	DRAWN:	ALB	CHECKED:	DRB	DATE:						
			•			•						
NUMBER	DATE		REVISIONS									









**Table B-1: Pavement Condition Index** 

Branch Name	Branch ID	Branch Use	Section ID	True Area (ft²)	Section Rank	Surface Type	Total Samples Inspected	Total Samples	PCI	PCI Category
Apron	AP	APRON	4105	53,325	P	AC	1	10	74	Satisfactory
Runway 18-36	RW 18-36	RUNWAY	6105	300,300	P	AC	23	80	67	Fair
Taxiway to North Hangars	T-HANG N	TAXIWAY	240	34,675	T	AC	0	9	100	Good
Taxiway Parallel	TW PARALL	TAXIWAY	105	11,020	P	AC	1	3	68	Fair
Taxiway Parallel	TW PARALL	TAXIWAY	110	11,150	P	AC	1	3	69	Fair
Taxiway Parallel	TW PARALL	TAXIWAY	125	31,010	P	AC	2	8	71	Satisfactory
Taxiway Parallel	TW PARALL	TAXIWAY	160	9,230	P	AC	1	2	67	Fair
Taxiway Parallel	TW PARALL	TAXIWAY	115	41,470	P	AC	3	12	72	Satisfactory
Taxiway Parallel	TW PARALL	TAXIWAY	120	59,150	P	AC	3	17	67	Fair
Taxiway to Hangars	TW T-HANG	TAXIWAY	205	24,330	P	AC	2	6	76	Satisfactory
Taxiway to Hangars	TW T-HANG	TAXIWAY	210	21,540	P	AC	2	5	76	Satisfactory
Taxiway to Hangars	TW T-HANG	TAXIWAY	235	20,230	P	AC	2	8	75	Satisfactory

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

# **APPENDIX C**

# BRANCH CONDITION REPORT SECTION CONDITION REPORT

Date: 5 /23/2011

# **Branch Condition Report**

1 of 2

Pavement Database: NetworkID: CHN

Sum Section Avg Section Number of PCI Weighted True Area Average **Branch ID** Use Average PCI Sections Length Width Standard (SqFt) PCI (Ft) (Ft) Deviation AP (APRON) 237.00 225.00 **APRON** 0.00 74.00 53,325.00 74.00 1 RW 18-36 (RUNWAY 18-36) 4,004.00 75.00 300,300.00 **RUNWAY** 0.00 67.00 1 67.00 T-HANG N (TAXIWAY TO HANGARS 1 1,285.00 25.00 34,675.00 **TAXIWAY** 100.00 0.00 100.00 NORTH) 4,463.00 TW PARALL (PARALLEL TAXIWAY) 6 35.00 163,030.00 **TAXIWAY** 69.00 1.91 69.24 TW T-HANG (TAXIWAY TO 3 2,427.00 26.67 66,100.00 **TAXIWAY** 75.67 0.47 75.69 HANGARS)

# **Branch Condition Report**

Pavement Database:

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	1	53,325.00	74.00	0.00	74.00
RUNWAY	1	300,300.00	67.00	0.00	67.00
TAXIWAY	10	263,805.00	74.10	9.26	74.90
All	12	617,430.00	73.50	8.67	70.98

STD = Standard Deviation

Date: 5 /23/2011

HANGARS)

### **Section Condition Report**

Pavement Database: NetworkID: CHN

Last Age **Section ID** Surface Use PCI **Branch ID** Last Rank Lanes **True Area** Inspection Αt Const. (SqFt) Date Inspection Date AP (APRON) Р 01/01/1991 **APRON** 53,325.00 02/23/2011 4105 AC 0 20 74.00 RW 18-36 (RUNWAY 18-36) 6105 01/01/1991 AC **RUNWAY** Р 0 300,300.00 02/23/2011 20 67.00 T-HANG N (TAXIWAY TO 240 07/31/2008 AC **TAXIWAY** Τ 0 34,675.00 07/31/2008 0 100.00 HANGARS NORTH) TW PARALL (PARALLEL 105 01/01/1993 AC **TAXIWAY** Ρ 0 11,020.00 02/23/2011 18 68.00 TAXIWAY) TW PARALL (PARALLEL 01/01/1993 **TAXIWAY** Ρ 110 AC 0 11,150.00 02/23/2011 18 69.00 TAXIWAY) TW PARALL (PARALLEL **TAXIWAY** Ρ 115 01/01/1996 AC 0 41,470.00 02/23/2011 15 72.00 TAXIWAY) TW PARALL (PARALLEL 120 01/01/1996 AC **TAXIWAY** Ρ 0 59.150.00 02/23/2011 15 67.00 TAXIWAY) TW PARALL (PARALLEL 125 01/01/1993 AC **TAXIWAY** Ρ 0 31,010.00 02/23/2011 18 71.00 TAXIWAY) TW PARALL (PARALLEL 01/01/1993 **TAXIWAY** Ρ 160 AC 0 9,230.00 02/23/2011 18 67.00 TAXIWAY) TW T-HANG (TAXIWAY TO 205 01/01/1991 AC **TAXIWAY** Ρ 0 24,330.00 02/23/2011 20 76.00 HANGARS) TW T-HANG (TAXIWAY TO 210 01/01/1991 AC **TAXIWAY** Ρ 0 21,540.00 02/23/2011 20 76.00 HANGARS) TW T-HANG (TAXIWAY TO Ρ 235 01/01/1996 AC **TAXIWAY** 0 20,230.00 02/23/2011 75.00 15

1 of 2

Date: 5 /23/2011

# **Section Condition Report**

2 of 2

Pavement Database:

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
0-02	0.00	34,675.00	1	100.00	0.00	100.00
11-15	15.00	120,850.00	3	71.33	3.30	70.05
16-20	19.00	461,905.00	8	71.00	3.61	69.04
AII	16.42	617,430.00	12	73.50	8.67	70.98

# **APPENDIX D**


# PAVEMENT CONDITION PREDICTION TABLE PREDICTED PCI BY PAVEMENT USE GRAPH

Pavement Evaluation Report –Wauchula Municipal Airport Florida Statewide Pavement Management Program May 2011

**Table D-1: Pavement Condition Prediction** 

Down als Manna	D ID	Section	Current					PCI Fo	recast				
Branch Name	Branch ID	ID	PCI	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020
Apron	AP	4105	74	73	72	71	69	68	66	65	63	62	60
Runway 18-36	RW 18-36	6105	67	66	65	64	62	61	59	58	56	55	53
Taxiway to Hangers to the North	T-HANG N	240	100	91	88	85	82	79	76	73	70	67	64
Taxiway Parallel	TW PARALL	105	68	67	66	64	62	61	59	57	55	54	52
Taxiway Parallel	TW PARALL	110	69	68	67	65	63	62	60	58	56	55	53
Taxiway Parallel	TW PARALL	115	72	71	70	68	66	65	63	61	59	58	56
Taxiway Parallel	TW PARALL	120	67	66	65	63	61	60	58	56	54	53	51
Taxiway Parallel	TW PARALL	125	71	70	69	67	65	64	62	60	58	57	55
Taxiway Parallel	TW PARALL	160	67	66	65	63	61	60	58	56	54	53	51
Taxiway to Hangers	TW T-HANG	205	76	75	74	72	70	69	67	65	63	62	60
Taxiway to Hangers	TW T-HANG	210	76	75	74	72	70	69	67	65	63	62	60
Taxiway to Hangers	TW T-HANG	235	75	74	73	71	69	68	66	64	62	61	59

Figure D-1: Predicted PCI by Pavement Use



# **APPENDIX E**

## YEAR 1 MAINTENANCE ACTIVITIES TABLE

**Table E-1: Year 1 Maintenance Activities** 

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Apron	AP	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	30,336.00	SqFt	\$0.40	\$12,134.51
Runway 18-36	RW 18-36	6105	L & T CR	M	Crack Sealing - AC	174.10	Ft	\$2.25	\$391.72
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	224,571.90	SqFt	\$0.40	\$89,829.51
Runway 18-36	RW 18-36	6105	WEATH/RAVEL	M	Surface Seal - Coat Tar	7,311.60	SqFt	\$0.40	\$2,924.66
Taxiway Parallel	TW PARALL	105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	7,064.10	SqFt	\$0.40	\$2,825.67
Taxiway Parallel	TW PARALL	105	WEATH/RAVEL	M	Surface Seal - Coat Tar	706.40	SqFt	\$0.40	\$282.56
Taxiway Parallel	TW PARALL	110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	6,453.40	SqFt	\$0.40	\$2,581.36
Taxiway Parallel	TW PARALL	115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	30,016.40	SqFt	\$0.40	\$12,006.65
Taxiway Parallel	TW PARALL	120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	47,319.90	SqFt	\$0.40	\$18,928.14
Taxiway Parallel	TW PARALL	125	WEATH/RAVEL	L	Surface Seal - Rejuvenating	24,808.00	SqFt	\$0.40	\$9,923.27
Taxiway Parallel	TW PARALL	160	WEATH/RAVEL	M	Surface Seal - Coat Tar	1,197.40	SqFt	\$0.40	\$478.96
Taxiway Parallel	TW PARALL	160	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,390.50	SqFt	\$0.40	\$1,756.21
Taxiway to Hangars	TW T-HANG	205	WEATH/RAVEL	L	Surface Seal - Rejuvenating	11,283.50	SqFt	\$0.40	\$4,513.42
Taxiway to Hangars	TW T-HANG	210	WEATH/RAVEL	L	Surface Seal - Rejuvenating	7,292.90	SqFt	\$0.40	\$2,917.17
Taxiway to Hangars	TW T-HANG	210	WEATH/RAVEL	M	Surface Seal - Coat Tar	78.10	SqFt	\$0.40	\$31.26
Taxiway to Hangars	TW T-HANG	235	WEATH/RAVEL	L	Surface Seal - Rejuvenating	7,677.40	SqFt	\$0.40	\$3,071.00
								Total =	\$164,596.07

# **APPENDIX F**

# MAJOR M&R PLAN BY YEAR UNDER UNLIMITED FUNDING SCENARIO TABLE


Table F-1: Major M&R Plan by Year under Unlimited Funding Scenario


Year	Branch Name	Section ID	Surface Type	Section Area (ft²)	]	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2013	Runway 18-36	6105	AC	300,300	\$	741,673.96	64	Mill and Overlay	100
2013	Taxiway Parallel	105	AC	11,020	\$	27,216.94	64	Mill and Overlay	100
2013	Taxiway Parallel	120	AC	59,150	\$	163,218.66	63	Mill and Overlay	100
2013	Taxiway Parallel	160	AC	9,230	\$	25,469.29	63	Mill and Overlay	100
2014	Taxiway Parallel	110	AC	11,150	\$	31,690.36	63	Mill and Overlay	100
2015	Taxiway Parallel	125	AC	31,010	\$	81,251.97	64	Mill and Overlay	100
2016	Taxiway Parallel	115	AC	41,470	\$	125,043.40	63	Mill and Overlay	100
2017	Taxiway to Hangars	235	AC	20,230	\$	56,234.45	64	Mill and Overlay	100
2018	Apron	4105	AC	53,325	\$	170,581.55	63	Mill and Overlay	100
2018	Taxiway to Hangars	205	AC	24,330	\$	77,829.33	63	Mill and Overlay	100
2018	Taxiway to Hangars	210	AC	21,540	\$	68,904.39	63	Mill and Overlay	100
				Total		\$1,569,114.30	63		100

<sup>\*</sup> Costs are adjusted for inflation.

# **APPENDIX G**

10-YEAR M&R MAP





#### LEGEND

TYPICAL RUNWAY BRANCH ID TW A TYPICAL TAXIWAY BRANCH ID

AP S TYPICAL APRON BRANCH ID



## ACTIVITY

MICROSURFACING



CONCRETE PAVEMENT RESTORATION

CHN

"PLAN YEAR"
"BRANCH": "SECTION"
"M AND R ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

K:\WF8_Aviation\14217	DODS\CACO\PLANSHEETS\C	H/(2008)15/004-01N-M	ANTENANCE.deg		PLOTTED: July 11, 2011 -	3:28 PM, BY: Stanford, R	•×
DESIGNED:	ELT	DRAWN:	ALB	CHECKED:	DRB	DATE:	
NUMBER	DATE			REVI	SIONS		







# **APPENDIX H**

## **PHOTOGRAPHS**




Apron, Section 4105, Sample Unit 102 - Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Raveling and Weathering




Runway 18-36, Section 6105, Sample Unit 101 – Low severity (43) Block Cracking, low severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Raveling and Weathering




Runway 18-36, Section 6105, Sample Unit 101 – Low severity (43) Block Cracking, low severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Raveling and Weathering




Runway 18-36, Section 6105, Sample Unit 124 – Low severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Raveling and Weathering



Runway 18-36, Section 6105, Sample Unit 124 – Low severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Raveling and Weathering



Taxiway Parallel, Section 120, Sample Unit 117 – Low severity (43) Block Cracking, low severity (48) Longitudinal and Transverse Cracking, and low severity (52) Raveling and Weathering



Taxiway Parallel, Section 115, Sample Unit 111 – Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Raveling and Weathering



T-Hangar, Section 210, Sample Unit 201 - Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Raveling and Weathering

# **APPENDIX I**

## PCI RE-INSPECTION REPORT

FDOT

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: Name: APRON Use: APRON Area: 53,325.00SqFt AP

Section: of From: -To: -Last Const.: 1/1/1991 4105 1

Family: FDOT-GA-AP-AC Surface: AC Zone: Category: Rank: P 225.00Ft

Width: Area: Length: 237.00Ft 53,325.00SqFt

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Total Samples: 10 Surveyed: 1 Last Insp. Date2/23/2011

Conditions: PCI:74.00 | Inspection Comments: KHA

PCI = 74Sample Number: 102 Type: R Area: 5,625.00SqFt

Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING

L 83.00 Ft Comments: 52 WEATHERING/RAVELING 3,200.00 SqFt L Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Sample Comments:

Name: WAUCHULA MUNICIPAL AIRPORT Network: CHN Name: RUNWAY 18-36 Use: RUNWAY Area: Branch: RW 18-36 300,300.00SqFt Section: 6105 of 1 From: -To: -Last Const.: 1/1/1991 Family: FDOT-GA-RW-AC Surface: AC Zone: Category: Rank: P Area: 300,300.00SqFt Length: 4,004.00Ft Width: 75.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0 Section Comments: Last Insp. Date2/23/2011 Total Samples: 80 Surveyed: 23 Conditions: PCI:67.00 | Inspection Comments: KHA Sample Number: 101 Type: R Area: 3,750.00SqFt PCI = 61Sample Comments: 43 BLOCK CRACKING  $\mathbf{L}$ 400.00 SqFt Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING  $\mathbf{L}$ 150.00 Ft Comments:  $\mathbb{L}$ 52 WEATHERING/RAVELING 2,800.00 SqFt Comments: 52 WEATHERING/RAVELING Μ 100.00 SqFt Comments: PCI = 66Sample Number: 102 Type: R Area: 3,750.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 175.00 Ft Comments:  $\mathbf{L}$ 52 WEATHERING/RAVELING 2,800.00 SqFt L Comments: 52 WEATHERING/RAVELING 100.00 SqFt M Comments: PCI = 66Sample Number: 106 Type: R Area: 3,750.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING  $\mathbf{L}$ 195.00 Ft Comments: 52 WEATHERING/RAVELING L 2,800.00 SqFt Comments: 52 WEATHERING/RAVELING Μ 100.00 SqFt Comments: PCI = 66Sample Number: 107 Type: R Area: 3,750.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 139.00 Ft Comments: 52 WEATHERING/RAVELING 2,800.00 SqFt L Comments: 52 WEATHERING/RAVELING 100.00 SqFt Comments: Μ Sample Number: 111 PCI = 66Type: R Area: 3,750.00SqFt Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 71.00 Ft Comments: 52 WEATHERING/RAVELING L 2,800.00 SqFt Comments: 52 WEATHERING/RAVELING Μ 100.00 SqFt Comments: 3,750.00SqFt PCI = 66Sample Number: 115 Type: R Area: Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 150.00 Ft Comments: 52 WEATHERING/RAVELING L 2,800.00 SqFt Comments: 52 WEATHERING/RAVELING Μ 100.00 SqFt Comments: Sample Number: 116 PCI = 66Type: R Area: 3,750.00SqFt Sample Comments: 52 WEATHERING/RAVELING 2,800.00 SqFt  $_{\rm L}$ Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 96.00 Ft Comments: 52 WEATHERING/RAVELING Μ 100.00 SqFt Comments: Sample Number: 120 Type: R Area: 3,750.00SqFt PCI = 66

FDOT

Report Generated Date: 5/23/2011

Site Name:

Site I tunio.						
48 LONGITUDINAL/TRANSVERSE CRACKING		L	160.00	r+	Comments:	
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
52 WEATHERING/RAVELING		М	100.00		Comments:	
J2 WEATHERING/ NAVELLING		1-1	100.00	bqrc	Commencs.	
Sample Number: 121 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments:	Aica.		3,730.003qFt		1 C1 00	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	150.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
52 WEATHERING/RAVELING		Μ	100.00		Comments:	
Sample Number: 124 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments:						
48 LONGITUDINAL/TRANSVERSE CRACKING		L	150.00		Comments:	
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
52 WEATHERING/RAVELING		M	100.00	SqFt	Comments:	
G 1 N 1					DOI //	
Sample Number: 125 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments: 52 WEATHERING/RAVELING		М	100.00	Saft	Comments:	
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	150.00	-	Comments:	
			130.00	10	COMMICTION.	
Sample Number: 129 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments:	mou.		3,730.005 <b>q1</b> t		101 00	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	200.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	2,800.00	SqFt	Comments:	
52 WEATHERING/RAVELING		M	100.00	SqFt	Comments:	
Sample Number: 130 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments:		_	0 000 00			
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
52 WEATHERING/RAVELING		M	100.00		Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	203.00	ľτ	Comments:	
Comple Number: 126 Trace B	A #20:		2.750.000 Fr		DCI - 61	
Sample Number: 136 Type: R Sample Comments:	Area:		3,750.00SqFt		PCI = 61	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	90.00	Ft.	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING		M	50.00		Comments:	
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
52 WEATHERING/RAVELING		М	100.00		Comments:	
Sample Number: 143 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments:						
48 LONGITUDINAL/TRANSVERSE CRACKING		L	150.00		Comments:	
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
52 WEATHERING/RAVELING		M	100.00	SqFt	Comments:	
					DOI //	
Sample Number: 149 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING		L	150.00	F+	Comments:	
52 WEATHERING/RAVELING		Г	2,800.00		Comments:	
52 WEATHERING/RAVELING 52 WEATHERING/RAVELING		М	100.00		Comments:	
		11	100.00	241 0		
Sample Number: 150 Type: R	Area:		3,750.00SqFt		PCI = 66	
Sample Comments:	ı ıı cu.		5,750.00bq1 t		101 00	
48 LONGITUDINAL/TRANSVERSE CRACKING		L	120.00	Ft	Comments:	
52 WEATHERING/RAVELING		L	2,800.00		Comments:	
52 WEATHERING/RAVELING		M	100.00	SqFt	Comments:	

FDOT

Report Generated Date: 5/23/2011

Site Name:

Sample Number: 153 Type: R Sample Comments:	Area:	3,750.00SqFt	PCI = 71
48 LONGITUDINAL/TRANSVERSE CRACKING	L	120.00 Ft	Comments:
52 WEATHERING/RAVELING	L	2,800.00 SqFt	Comments:
Sample Number: 157 Type: R Sample Comments:	Area:	3,750.00SqFt	PCI = 71
48 LONGITUDINAL/TRANSVERSE CRACKING	L	150.00 Ft	Comments:
52 WEATHERING/RAVELING	L	100.00 SqFt	Comments:
52 WEATHERING/RAVELING	L	2,800.00 SqFt	
Sample Number: 162 Type: R Sample Comments:	Area:	3,750.00SqFt	PCI = 71
48 LONGITUDINAL/TRANSVERSE CRACKING	L	83.00 Ft	Comments:
52 WEATHERING/RAVELING	L	2,800.00 SqFt	Comments:
Sample Number: 166 Type: R	Area:	3,750.00SqFt	PCI = 71
Sample Comments:		3,750.00SqFt 184.00 Ft	PCI = 71  Comments:
	Area:	, 1	Comments:
Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 52 WEATHERING/RAVELING  Sample Number: 171 Type: R	L	184.00 Ft	Comments:
Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 52 WEATHERING/RAVELING	L L	184.00 Ft 2,800.00 SqFt	Comments: Comments:
Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 52 WEATHERING/RAVELING  Sample Number: 171 Type: R Sample Comments:	L Area:	184.00 Ft 2,800.00 SqFt 3,750.00SqFt	Comments: Comments: PCI = 65 Comments:
Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING  52 WEATHERING/RAVELING  Sample Number: 171 Type: R Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING	L Area:	184.00 Ft 2,800.00 SqFt 3,750.00SqFt 220.00 Ft	Comments: Comments:  PCI = 65  Comments: Comments:
Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING  52 WEATHERING/RAVELING  Sample Number: 171 Type: R  Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING  52 WEATHERING/RAVELING  52 WEATHERING/RAVELING  Sample Number: 175 Type: R	L L L L L	184.00 Ft 2,800.00 SqFt 3,750.00SqFt 220.00 Ft 2,800.00 SqFt	Comments: Comments:  PCI = 65  Comments: Comments:
Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING  52 WEATHERING/RAVELING  Sample Number: 171 Type: R Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING  52 WEATHERING/RAVELING  52 WEATHERING/RAVELING  Sample Number: 175 Type: R Sample Comments:	L Area: L L M	184.00 Ft 2,800.00 SqFt 3,750.00SqFt 220.00 Ft 2,800.00 SqFt 300.00 SqFt	Comments: Comments:  PCI = 65  Comments: Comments: Comments: Comments:
Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING  52 WEATHERING/RAVELING  Sample Number: 171 Type: R  Sample Comments:  48 LONGITUDINAL/TRANSVERSE CRACKING  52 WEATHERING/RAVELING  52 WEATHERING/RAVELING  Sample Number: 175 Type: R	Area:  L L M Area:	184.00 Ft 2,800.00 SqFt  3,750.00SqFt  220.00 Ft 2,800.00 SqFt 300.00 SqFt 3,750.00SqFt	Comments: Comments: PCI = 65  Comments: Comments: Comments: PCI = 66 Comments:

25.00Ft

FDOT

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: T-HANG N Name: TAXIWAY TO HANGARS NORTH Use: TAXIWAY Area: 34,675.00SqFt

Section: 240 of 1 From: - To: - Last Const.: 7/31/2008

Surface: AC Family: DEFAULT Zone: Category: Rank: T

Area: 34,675.00SqFt Length: 1,285.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date7/31/2008 Total Samples: 0 Surveyed: 0

Conditions: PCI:100.00 |

Inspection Comments: Construction/Major M&R inspection record.

Sample Number: Type: Area: 0.00

<NO SAMPLE RECORDS>

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY Use: TAXIWAY Area: 163,030.00SqFt

Section: of 6 To: -105 From: -Last Const.: 1/1/1993

35.00Ft

Comments:

Surface: Family: FDOT-GA-TW-AC Zone: Category: Rank: P AC

Width: Length: Area: 11,020.00SqFt 300.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Sample Comments:

Total Samples: 3 Surveyed: 1 Last Insp. Date2/23/2011

Conditions: PCI:68.00 | Inspection Comments: KHA

3,120.00SqFt PCI = 68Sample Number: 101 Type: R Area:

48 LONGITUDINAL/TRANSVERSE CRACKING L 95.00 Ft Comments: 52 WEATHERING/RAVELING 2,000.00 SqFt  $\mathbf{L}$ Comments: 52 WEATHERING/RAVELING 200.00 SqFt

Μ

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY Use: TAXIWAY Area: 163,030.00SqFt

Section: 110 of 6 From: - To: - Last Const.: 1/1/1993

35.00Ft

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P

Area: 11,150.00SqFt Length: 300.00Ft Width:

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/23/2011 Total Samples: 3 Surveyed: 1

Conditions: PCI:69.00 | Inspection Comments: KHA

Sample Number: 101 Type: R Area: 3,110.00SqFt PCI = 69

Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 160.00 Ft Comments:

43 BLOCK CRACKING L 300.00 SqFt Comments: 52 WEATHERING/RAVELING L 1,800.00 SqFt Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY Use: TAXIWAY Area: 163,030.00SqFt

To: -Section: 115 of 6 From: -Last Const.: 1/1/1996

35.00Ft

Surface: Family: FDOT-GA-TW-AC Zone: Category: Rank: P AC

Length: Width: Area: 41,470.00SqFt 1,144.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Total Samples: 12 Surveyed: 3 Last Insp. Date2/23/2011

Conditions: PCI:72.00 | Inspection Comments: KHA

PCI = 74Sample Number: 104 Type: R Area: 3,500.00SqFt

Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING

140.00 Ft L Comments: 52 WEATHERING/RAVELING 2,000.00 SqFt  $\mathbf{L}$ Comments:

Sample Number: 107 PCI = 71Type: R Area: 3,500.00SqFt

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 200.00 Ft L Comments: 52 WEATHERING/RAVELING 2,800.00 SqFt  $\mathbf{L}$ Comments:

Sample Number: 111 Type: R PCI = 71Area: 3,500.00SqFt

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 200.00 Ft Comments:

52 WEATHERING/RAVELING L 2,800.00 SqFt Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY Use: TAXIWAY Area: 163,030.00SqFt

Section: 120 of 6 From: - To: - Last Const.: 1/1/1996

35.00Ft

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P

Area: 59,150.00SqFt Length: 1,690.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Datc2/23/2011 Total Samples: 17 Surveyed: 3

Conditions: PCI:67.00 | Inspection Comments: KHA

Sample Number: 105 Type: R Area: 3,500.00SqFt PCI = 71

Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 100.00 Ft Comments:

52 WEATHERING/RAVELING L 2,800.00 SqFt Comments:

Sample Number: 110 Type: R Area: 3,500.00SqFt PCI = 66
Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 121.00 Ft Comments:

43 BLOCK CRACKING L 80.00 SqFt Comments: 52 WEATHERING/RAVELING L 2,800.00 SqFt Comments:

Sample Number: 117 Type: R Area: 3,500.00SqFt PCI = 66

Sample Comments:

43 BLOCK CRACKING L 120.00 SqFt Comments: 52 WEATHERING/RAVELING L 2,800.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 193.00 Ft Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY Use: TAXIWAY Area: 163,030.00SqFt

Section: 125 To: of 6 From: -Last Const.: 1/1/1993

35.00Ft

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P

Length: Width: Area: 31,010.00SqFt 845.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Total Samples: 8 Surveyed: 2 Last Insp. Date2/23/2011

Conditions: PCI:71.00 | Inspection Comments: KHA

PCI = 71Sample Number: 101 Type: R Area: 3,500.00SqFt

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 200.00 Ft L Comments: 52 WEATHERING/RAVELING 2,800.00 SqFt  $\mathbf{L}$ Comments:

Sample Number: 105 3,500.00SqFt PCI = 71Type: R Area:

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 129.00 Ft Comments: L

52 WEATHERING/RAVELING 2,800.00 SqFt Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY Use: TAXIWAY Area: 163,030.00SqFt

Section: 160 of 6 From: - To: - Last Const.: 1/1/1993

35.00Ft

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P

Area: 9,230.00SqFt Length: 184.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Sample Comments:

Last Insp. Datc2/23/2011 Total Samples: 2 Surveyed: 1

Conditions: PCI:67.00 | Inspection Comments: KHA

Sample Number: 101 Type: R Area: 4,625.00SqFt PCI = 67

48 LONGITUDINAL/TRANSVERSE CRACKING L 53.00 Ft Comments: 52 WEATHERING/RAVELING M 600.00 SqFt Comments:

52 WEATHERING/RAVELING L 2,200.00 SqFt Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW T-HANG Name: TAXIWAY TO HANGARS Use: TAXIWAY Area: 66,100.00SqFt

Section: 205 of 3 From: - To: - Last Const.: 1/1/1991

35.00Ft

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P

Area: 24,330.00SqFt Length: 647.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/23/2011 Total Samples: 6 Surveyed: 2

Conditions: PCI:76.00 | Inspection Comments: KHA

Sample Number: 100 Type: R Area: 4,930.00SqFt PCI = 73

Sample Comments:

52 WEATHERING/RAVELING L 3,000.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 49.00 Ft Comments:

Sample Number: 105 Type: R Area: 5,420.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 199.00 Ft Comments:

52 WEATHERING/RAVELING L 1,800.00 SqFt Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW T-HANG Name: TAXIWAY TO HANGARS Use: TAXIWAY Area: 66,100.00SqFt

Section: 210 of 3 From: - To: - Last Const.: 1/1/1991

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P Area: 21,540.00SqFt Length: 980.00Ft Width: 20.00Ft

Area: 21,540.00SqFt Length: 980.00Ft Width: Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date2/23/2011 Total Samples: 5 Surveyed: 2

Conditions: PCI:76.00 | Inspection Comments: KHA

Sample Number: 100 Type: R Area: 3,750.00SqFt PCI = 74

Sample Comments:
52 WEATHERING/RAVELING
M 30.00 SqFt Comments:
52 WEATHERING/RAVELING
L 1,000.00 SqFt Comments:

52 WEATHERING/RAVELING L 1,000.00 Sqft Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING L 116.00 Ft Comments:

Sample Number: 102 Type: R Area: 4,520.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 70.00 Ft Comments: 52 WEATHERING/RAVELING L 1,800.00 SqFt Comments:

**FDOT** 

Report Generated Date: 5/23/2011

Site Name:

Network: CHN Name: WAUCHULA MUNICIPAL AIRPORT

Branch: TW T-HANG Name: TAXIWAY TO HANGARS Use: TAXIWAY Area: 66,100.00SqFt

Section: To: -235 of 3 From: -Last Const.: 1/1/1996

25.00Ft

Comments:

Surface: Family: FDOT-GA-TW-AC Zone: Category: Rank: P AC

Length: Width: Area: 20,230.00SqFt 800.00Ft Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Total Samples: 8 Surveyed: 2 Last Insp. Date2/23/2011

Conditions: PCI:75.00 | Inspection Comments: KHA

PCI = 71Sample Number: 100 Type: R Area: 2,500.00SqFt

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING 28.00 Ft L Comments: 240.00 SqFt 43 BLOCK CRACKING  $\mathbf{L}$ Comments: 52 WEATHERING/RAVELING L 1,000.00 SqFt

Sample Number: 201 Type: R 2,770.00SqFt PCI = 77Area:

Sample Comments:

Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 38.00 Ft  $\mathbf{L}$ 

52 WEATHERING/RAVELING L 1,000.00 SqFt Comments: