

FLORIDA DEPARTMENT OF TRANSPORTATION  
AVIATION AND SPACEPORT OFFICE




BROOKSVILLE/  
TAMPA BAY  
REGIONAL  
AIRPORT (BKV)

DISTRICT 7  
GENERAL AVIATION  
AIRPORT

DECEMBER 2013

# STATEWIDE Airfield Pavement Management PROGRAM





## TABLE OF CONTENTS

Executive Summary .....	1
1. Introduction.....	8
2. Airfield Pavement Network Definition and Pavement Inventory .....	19
3. Airfield Pavement Condition .....	27
4. Pavement Performance.....	35
5. Airfield Pavement Maintenance Policies and Costs.....	38
6. Major Pavement Rehabilitation Needs.....	46
7. Preventative and Major Rehabilitation Planning.....	49
8. Visual Aid Exhibits .....	52
9. Recommendations.....	53

## LIST OF TABLES

Table I: Condition Summary by Branch.....	2
Table II: Condition Summary by Pavement Facility Use .....	2
Table III: Year-1 Major Rehabilitation Needs for Brooksville - Tampa Bay Regional Airport .....	5
Table IV: 10-Year Preventative Maintenance and Major Rehabilitation .....	7
Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections.....	16
Table 2-1: Recent and/or Anticipated Airfield Pavement Construction .....	21
Table 2-2: Pavement Inventory Summary.....	23
Table 2-3: Airfield Pavement Inventory Details.....	24
Table 3-1: Airfield Pavement Distresses for Asphalt Concrete .....	28
Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete .....	29
Table 3-3: Pavement Condition Index Rating Summary .....	32
Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy .....	39
Table 5-2: Recommended PCC Maintenance and Repair Policy .....	40
Table 5-3: Critical and Minimum Service Level PCI for General Aviation Airports .....	42
Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI.....	42
Table 5-5: AC Maintenance Unit Costs .....	44
Table 5-6: PCC Maintenance Unit Costs.....	44



Table 5-7: Rehabilitation Activities and Unit Costs by Condition for General Aviation Airports .....	45
Table 6-1: Summary of Major Rehabilitation .....	47
Table 7-1: 10-Year Preventative and Major Rehabilitation Summary .....	49

## LIST OF FIGURES

Figure 1-1: Pavement Life Cycle .....	14
Figure 1-2: Flexible Pavement, Asphalt Concrete .....	17
Figure 1-3: Rigid Pavement, Portland Cement Concrete .....	18
Figure 2-1: Airfield Pavement Type .....	24
Figure 3-1: Airfield Pavement Condition Index Rating Summary .....	31
Figure 3-2: Percentage of Pavement Area by Condition Rating by Use .....	33
Figure 4-1: Runway Pavement Performance Prediction Summary .....	36
Figure 4-2: Taxiway Pavement Performance Prediction Summary .....	36
Figure 4-3: Apron Pavement Performance Prediction Summary .....	37
Figure 6-1: 10-Year Major Rehabilitation Budget Scenario Analysis .....	48
Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary .....	50

## APPENDICES

Appendix A	Airfield Pavement Network Definition Exhibit Airfield Pavement System Inventory Exhibit Pavement Geometry Inventory Work History Report
Appendix B	Airfield Pavement Condition Index Rating Exhibit Pavement Condition Index Inventory
Appendix C	Branch Condition Report Section Condition Report
Appendix D	Pavement Performance Prediction Table Pavement Performance by Pavement Use
Appendix E	Year-1 Preventative Activities
Appendix F	Airfield Pavement 10-Year Major Rehabilitation Exhibit Airfield Pavement 10-Year Major Rehabilitation Table
Appendix G	Photographs
Appendix H	Distress Data – Re-inspection Report





## EXECUTIVE SUMMARY

---

In 2012, the Florida Department of Transportation (FDOT) Aviation and Spaceport Office selected a team lead by *Kimley-Horn and Associates, Inc.* and including their subconsultants Peneul Consulting, LLC, Roy D. McQueen & Associates, LTD, and All About Pavements, Inc., to provide services in support of FDOT in the continued efforts of updating the existing Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed over the fiscal years of 2013 and 2014.

The tasks required to achieve this objective at each participating airport specifically included the following:

- Obtain recent construction history from the airport to update the Pavement Network Definition Exhibits using CADD from the previous SAPMP update.
- Update the airport pavement inventory data (construction history, geometry, identification, and classification) based on airport information provided.
- Update the FDOT SAPMP MicroPAVER database files and system tables for the purpose of analyzing field data for Pavement Condition Index (PCI) calculation of current pavement condition
- Development of pavement performance models for the approximation of future pavement performance.
- Development of a maintenance and repair plan, and a 10-year major rehabilitation program to address the pavement needs based on condition.
- Development of planning level opinions of probable costs for pavement preservation and rehabilitation.

During June 2013, a PCI survey inspection was performed at Brooksville - Tampa Bay Regional Airport. The results of the inspection indicate that, based on ASTM 5340-11, the airport's airfield pavement facilities had an overall area-weighted average PCI 56, representing a Fair overall network condition. Table I summarizes the overall condition summary by network level branch in comparison to the FDOT recommended minimum service level.



Table I: Condition Summary by Branch

Branch Name	Area Weighted PCI	PCI Range	Average Condition Rating	FDOT Minimum Service Level	MicroPAVER Minimum PCI	Action Required
NORTHEAST APRON	62	36 - 72	FAIR	60	65	X
SOUTH APRON	84	64 - 100	SATISFACTORY	60	65	X
RUNWAY 3-21	54	53 - 55	POOR	75	65	X
RUNWAY 9-27	54	46 - 58	POOR	75	65	X
TAXIWAY A	50	50	POOR	65	65	X
TAXIWAY A1	55	44 - 77	POOR	65	65	X
TAXIWAY A3	26	20 - 41	POOR	65	65	X
TAXIWAY A5	59	59	FAIR	65	65	X
TAXIWAY A6	20	20	SERIOUS	65	65	X
TAXIWAY A9	69	69	FAIR	65	65	
TAXIWAY B	57	38 - 66	FAIR	65	65	X
TAXIWAY B1	63	58 - 72	FAIR	65	65	X
TAXIWAY B2	38	38	VERY POOR	65	65	X
TAXIWAY B3	59	59	FAIR	65	65	X
TAXIWAY B4	62	62	FAIR	65	65	X

For project level planning and inspection development; the airfield pavement facilities have been divided at the branch level based on facility use and designation, and at the section level based on pavement construction history, composition (e.g. asphalt versus concrete), aircraft traffic operations, and pavement surface conditions. Table II provides the overall area weighted condition of the pavement based on facility branch use.

Table II: Condition Summary by Pavement Facility Use

Use	Average Area-Weighted PCI	Condition Rating
Runway	54	POOR
Taxiway	52	POOR
Apron	68	FAIR



Based on the inspection performed at the airport for this SAPMP update; the current conditions were determined using the collected PCI distress data. PCI values were computed and used to identify pavement facilities that were below the defined critical PCI as sections that would benefit from immediate major rehabilitation activity. These pavement sections that were determined to be below the critical PCI would most likely benefit from long-term major rehabilitative construction activity rather than localized, short-term maintenance and repairs.

The Year-1 Major Rehabilitation Needs, or projects that are recommended to be completed because the pavement is below the critical PCI, were developed on the assumption that there is an unlimited repair budget. These projects include:

- ⦿ Runway 3-21 – Sections 6205 and 6210
  - PCC Restoration attributed to climate and age of pavement.
- ⦿ Runway 9-27 – Sections 6105 and 6110
  - PCC Restoration attributed to climate and age of pavement.
- ⦿ Taxiway A3 – Sections 120 and 125
  - Reconstruction and PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ⦿ Taxiway A – Section 105
  - PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ⦿ Taxiway A6 – Section 135
  - Reconstruction attributed to pavement repair along with the climate and age of pavement.
- ⦿ Taxiway B – Section 205
  - Reconstruction attributed to climate and age of pavement.
- ⦿ Taxiway A1 – Sections 110 and 112
  - Mill and Overlay along with PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ⦿ Taxiway A5 – Section 130
  - PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ⦿ Taxiway B1 – Sections 215 and 216
  - Mill and Overlay along with PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ⦿ Taxiway B2 – Section 220



- Reconstruction attributed to climate and age of pavement.
- ⊙ Taxiway B3 – Section 225
  - Mill and Overlay attributed to climate and age of pavement.
- ⊙ Taxiway B4 – Section 230
  - Mill and Overlay attributed to climate and age of pavement.
- ⊙ Apron NE – Sections 4135, 4145, 4147, 4150, 4125, 4110, 4130, 4115, 4105 and 4120
  - Mill and Overlay, Reconstruction and PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ⊙ Apron S – Section 4205
  - Mill and Overlay attributed to subgrade quality, climate and age of pavement.

The section level projects that were identified as Year-1 Major Rehabilitation Needs are in Table III.



Table III: Year-1 Major Rehabilitation Needs for Brooksville - Tampa Bay Regional Airport

Branch ID	Section ID	Major Rehabilitation Costs	PCI Before M&R	Rehabilitation Activity	PCI After M&R
AP NE	4135	\$ 591,224.27	63	Mill and Overlay	100
AP NE	4145	\$ 728,091.77	55	Mill and Overlay	100
AP NE	4147	\$ 73,709.00	55	Mill and Overlay	100
AP NE	4150	\$ 280,173.09	56	PCC Restoration	100
AP NE	4125	\$ 237,395.29	62	Mill and Overlay	100
AP NE	4110	\$ 145,918.09	51	Mill and Overlay	100
AP NE	4130	\$ 92,197.07	35	Reconstruction	100
AP NE	4115	\$ 357,996.18	51	Mill and Overlay	100
AP NE	4105	\$ 330,801.57	48	Mill and Overlay	100
AP NE	4120	\$ 530,576.18	52	Mill and Overlay	100
AP S	4205	\$ 33,984.70	64	Mill and Overlay	100
RW 3-21	6210	\$ 5,014,999.76	54	PCC Restoration	100
RW 3-21	6205	\$ 2,507,499.88	52	PCC Restoration	100
RW 9-27	6105	\$ 4,205,250.52	46	PCC Restoration	100
RW 9-27	6110	\$ 6,999,999.67	57	PCC Restoration	100
TW A3	125	\$ 394,835.34	20	Reconstruction	100
TW A	105	\$ 6,570,585.63	50	PCC Restoration	100
TW A6	135	\$ 474,208.76	20	Reconstruction	100
TW B	205	\$ 833,257.40	38	Reconstruction	100
TW A1	110	\$ 568,940.67	52	PCC Restoration	100
TW A1	112	\$ 241,721.64	43	Mill and Overlay	100
TW A3	120	\$ 158,483.82	41	PCC Restoration	100
TW A5	130	\$ 330,460.18	58	PCC Restoration	100
TW B1	215	\$ 637,452.57	57	PCC Restoration	100
TW B1	216	\$ 454,292.08	58	Mill and Overlay	100
TW B2	220	\$ 109,627.83	38	Reconstruction	100
TW B3	225	\$ 73,085.20	59	Mill and Overlay	100
TW B4	230	\$ 62,462.40	62	Mill and Overlay	100
Total =		\$33,039,230.56			





The SAPMP uses historic pavement condition data from the previous inspections to develop pavement performance models. These pavement performance models are used to create PCI prediction curves to estimate future pavement conditions based on the historic trends. The section areas, prediction curves, and current condition data were used to develop a 10-year major rehabilitation program. Major rehabilitation costs for each year of the 10-year program are based on general unit costs for pavement repairs and not detailed cost estimates that are typically prepared for a construction set of bid documents. Additionally, preventative maintenance level repair budgets were estimated for a 10-year duration. Table IV provides an annual summary of the 10-year Preventative Maintenance and Major Rehabilitation planning level cost opinions for the airfield pavement facilities at the airport. Refer to Section 6 of this report for additional information.




Table IV: 10-Year Preventative Maintenance and Major Rehabilitation

Year	Preventative	Major M&R	Total Year Cost
2014	\$ 207,639.77	\$ 33,039,230.55	\$ 33,246,870.32
2015	\$ 219,589.87	\$ -	\$ 219,589.87
2016	\$ 177,950.77	\$ 1,595,546.10	\$ 1,773,496.87
2017	\$ 188,748.09	\$ 889,328.50	\$ 1,078,076.59
2018	\$ 238,788.73	\$ -	\$ 238,788.73
2019	\$ 502,486.88	\$ -	\$ 502,486.88
2020	\$ 742,429.75	\$ -	\$ 742,429.75
2021	\$ 999,267.46	\$ -	\$ 999,267.46
2022	\$ 1,263,019.43	\$ -	\$ 1,263,019.43
2023	\$ 1,266,090.66	\$ 3,953,369.27	\$ 5,219,459.93
Total	\$5,806,011.41	\$39,477,474.42	\$ 45,283,485.83

The success of the repair program for your airport depends on the timely implementation of preservation, localized maintenance and repairs, and major rehabilitation work activities. If work is completed as scheduled, your airport will probably experience an improvement to the overall area-weighted average PCI. Though this analysis was performed with the assumption of an “unlimited budget”, the purpose has been to identify specific projects over the course of 10-years for each pavement section where the condition is projected to fall below the critical PCI. The costs depicted in this study are intended to aid the airports in planning level budgets. Prior to construction work, it is recommended that the airport perform additional investigation at the design level to better estimate costs associated with the maintenance, repair, and major rehabilitation activity discussed.

## 1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. The aviation system in Florida allows the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.



There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.



The Florida Department of Transportation (FDOT) Aviation and Spaceport Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992. In 2012, the FDOT Aviation and Spaceport Office selected a team led by Kimley-Horn and Associates, Inc. and including Peneul Consulting, LLC, Roy D. McQueen & Associates, LTD, and All About Pavements, Inc., to provide services in support of the Aviation and Spaceport Office Program Manager. The continued evaluation and update of the existing SAPMP is to be completed over fiscal years 2013 and 2014.

This individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance repair and major rehabilitation planning associated with the SAPMP update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

## 1.1 Purpose of Pavement Evaluation Report

The purpose of this Airfield Pavement Evaluation Report is to:

- Describe, briefly, the SAPMP goals, procedures, and responsibilities of the program's participants.
- Provide a brief technical explanation on pavement management principles, standard practices, objectives, and benefits of implementation.
- Outline procedures used to coordinate, collect, evaluate and report pavement inspection results at this airport.
- Analyze and utilize condition results for the development of maintenance, repair, and major rehabilitation based on pavement performance trends.

## 1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the Florida Airports System, identify maintenance and rehabilitation needs at each airport, automate pavement infrastructure information management, and establish standards to address future needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.

During the 1992-1993 implementations and again during the 1998-1999 updates; the SAPMP performed the development of proprietary software for pavement



management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation (M&R) policies, M&R budget costs, and the development of recommendations for performing routine pavement preservation maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER was selected for implementation of the system update. MicroPAVER was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for the purpose of pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER system. This data conversion included all documented pavement facility, classification, type, history, geometry, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In 2006-2008, the SAPMP was updated again with continued use of the MicroPAVER system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In 2010-2012, the SAPMP was updated using new GPS integrated technology to digitally collect pavement distress data. Interactive GIS map files were developed from updated Airfield Pavement Network Definition Maps to aid pavement condition inspectors in the collection of sample distress data. The





data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the Federal Aviation Administration (FAA) to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6B *Guidelines and Procedures for Maintenance of Airport Pavements*). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year or every three years, if the pavement is inspected in accordance to the PCI survey procedure (such as ASTM International D 5340 *Standard Test Method for Airport Pavement Condition Index Surveys*). The previous 2010-2012 SAPMP update utilized the ASTM D 5340-04 released in 2004, in lieu of the 2010/2011 edition, in order to maintain consistent database integrity and benefit of pavement performance models from previous inspections.

### 1.3 Organization

#### *FDOT Aviation and Spaceport Office Program Manager*

The FDOT Central Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) for the SAPMP. The AO-PM monitors the work performed by the Consultant. The AO-PM has review and approval authority for each program task and manages the day-to-day details of the SAPMP and the pertinent updates.

The AO-PM reports updates and milestones to the FDOT State Aviation Manager and Aviation Development Administrator.

#### *Consultant*

The Consultant, Kimley-Horn and Associates, Inc. and their team consisting of Peneul Consulting, LLC, Roy D. McQueen & Associates, LTD, and All About Pavements, Inc. provide technical and administrative assistance to the AO-PM during the execution of the update to the SAPMP. The efforts include updating the airport pavement inventory data, performing the condition survey inspections, evaluating the airfield pavement conditions and updating the SAPMP based upon procedures outlined in the FAA Advisory Circular 150/5380-6B *Guidelines and Procedures for Maintenance of Airport Pavements* and ASTM D 5340.



### *Airport Role*

The airports are the ultimate client for each condition survey inspection performed at their respective airfields as part of the SAPMP. The individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP, indicate any construction activity that has been performed since the previous inspections.

### *FDOT District Offices*

The seven FDOT District Offices, specifically the Aviation Representatives, provide vital support to the SAPMP update and the AO-PM. Each District supports the SAPMP's on-going efforts of provided representative construction trend costs and practices through the Florida Airports System. Each District Office receives copies of individual Airfield Pavement Evaluation Reports for the airport facilities located within their respective districts.

## **1.4 Introduction to Pavement Types and Pavement Management**

### *Pavement Basics*

A pavement is a prepared surface designed to provide a continuous smooth ride at all taxi, takeoff, and landing speeds and to support an estimated amount of traffic loading for a certain number of years. Pavements are composed of a combination of constructed layers of subgrade soils, subbases, base course material, and surface level courses. There are mainly two types of pavements:

- Flexible Pavement, a composition of bituminous asphalt concrete (AC) surface, base, and subbase layers.
- Rigid Pavement, a composition of Portland Cement Concrete (PCC) surface, base, and subbase layers.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads (both magnitude and repeated application) and protect the underlying subgrade soil. Flexible pavements dissipate applied loads from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements, the PCC layer supports the majority of the structural load applied, and the base or subbase layer is constructed to provide a smooth, level, and continuous platform that provides uniform support for PCC slabs.



A small percentage of airfield pavements within the Florida Airports System are composed of hybrid 'composite pavement' sections that may include both AC pavement and PCC pavement. The two known composite pavements are AC surface over PCC (APC) and PCC over AC (White Topping).


Due to the different nature of the pavement types, construction, and their materials; flexible and rigid pavements have different modes of failure and fatigue. This results in varying deterioration and distress development. Understanding the mechanics and modes of failure of the pavement types will assist the engineers in making timely, adequate, consistent, and economical maintenance repairs and major rehabilitation to the pavement structures at each airfield.

### *The Concept of an Airfield Pavement Management System*

The SAPMP is a program that provides the Florida Airports System an opportunity to implement and/or maintain a proactive Airfield Pavement Management System (APMS) in a consistent manner at a regular schedule. The SAPMP Airfield Pavement Management System consists of pavement inventory, pavement construction and history, condition survey inspections, pavement performance modeling, maintenance recommendations, and major rehabilitation planning. The various elements of the APMS are used by experienced engineers to identify critical pavements, make pavement preservation or rehabilitation recommendations, and approximate pavement performance. The APMS as a whole is used by an airport's stakeholders, managing agencies, engineers, and planners as a tool in decision making for future project planning, budgeting, and scheduling of activities for its airfield pavement infrastructure.

A benefit of an active APMS is it provides an understanding of an airport's pavement performance trends for the purpose of project planning. Based on the performance trend of their pavements, an airport can schedule pavement maintenance and rehabilitation prior to when the pavement section has deteriorated to a condition that would require reconstruction. The use of pavement performance trends will help airports plan M&R and Rehabilitation projects in a manner and sequence that maximizes benefit and minimizes costs. Figure 1-1, which is based upon the FAA Advisory Circular 150 5380-7A *Airport Pavement Management Program*, illustrates how pavement generally deteriorates over time and the relative cost of rehabilitation and reconstruction throughout its life.

Figure 1-1: Pavement Life Cycle



Source: FAA Advisory Circular 150 5380-7A Airport Pavement Management Program

Note that during approximately the first 75% of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in 'Good' and 'Satisfactory' conditions depends on how well it is proactively maintained. As the Figure 1-1 demonstrates, the cost of maintaining the pavement above critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Pavements tend to deteriorate at an accelerated rate when actual traffic loading exceeds the original design assumptions and when limited resources are available for maintenance and repair (M&R) efforts. Planned maintenance and rehabilitation, essentially preserving pavements and delaying condition deterioration, help airport (managers, agencies, and engineers) maximize the use of their budgets and prolong the life of their pavements. An APMS provides a tool to schedule planned maintenance and major rehabilitation efforts based on a consistent methodology of condition assessment. This consistent methodology of pavement condition assessment allows for the development of pavement performance models to help forecast future pavement conditions.



Part of the implementation of the APMS is the clear identification and inventorying of pavement infrastructure that needs to be managed specifically within the airport (owner, manager, and agencies) responsibility. Another aspect of the APMS is development of maintenance, repair, and major rehabilitation policies that align with the expectations of pavement performance and are based on ability to fund the types of work identified. Once there is an understanding of the cause and extent of pavement distresses, appropriate maintenance and rehabilitation can be planned. By using representative construction costs based on historic bid trends; planning level budget costs can be developed on a multiyear duration.

#### *Airfield Pavement Inspection Methodology for the SAPMP*

Pavement condition assessment requires the application of professional judgments regarding the condition of the pavement. The SAPMP airfield pavement condition survey inspections assess pavement, comparing it to a set of standards in ASTM D 5340-11. As part of this update, SAPMP has adopted the changes made in updates to ASTM D 5340-11. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reactivity distress for rigid pavement distresses. The change in distress classification, as described in ASTM D 5340-11, may result in small variances in the PCI values from the previous inspection analysis.

The pavement condition surveys assess the functional condition of the pavement surface based on surface distresses as defined by the ASTM D 5340-11. Typically, deficiencies within a pavement structure will eventually reflect to the pavement surface as distresses described within ASTM D 5340-11. The SAPMP is specifically a visual evaluation and analysis based on the ASTM D 5340-11. The structural condition and relative support of the pavement layers can be directly quantified using non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the SAPMP update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine design level rehabilitation and/or reconstruction needs should the airport proceed to the design process.

In preparation for the PCI survey inspections, the airfield pavements for each airport are divided into branches, sections, and sample units as established by FAA Advisory Circular 150/5380-6B and ASTM D 5340. Further discussion of the process of inventorying and categorizing pavement facilities by use,





composition, and history can be found in SECTION 2 *AIRFIELD PAVEMENT NETWORK DEFINITION and PAVEMENT INVENTORY*.

Sample units are uniformly divided areas of pavement that are defined for inspection. Sample unit sizes are approximately 5,000 ± 2,000 square feet for flexible AC pavements and 20 ± 8 slabs for rigid PCC pavements. Prior to conducting the field condition survey inspections, the sampling plan was developed for the airfield pavements based on updates to the previous inspection sampling based on the available knowledge of construction updates. The sample rate adopted for the SAPMP is depicted on Table 1-1.

Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections

Flexible Pavements Asphalt Concrete			Rigid Pavements Portland Cement Concrete		
Number of Sample Units in Section	Number of Sample Units to Inspect		Number of Sample Units in Section	Number of Sample Units to Inspect	
	Runway	Taxiways, Aprons, Others		Runway	Taxiways, Aprons, Others
1 - 4	1	1	1 - 3	1	1
5 - 10	2	1	4 - 6	2	1
11 - 15	3	2	7 - 10	3	2
16 - 30	5	3	11 - 15	4	2
31 - 40	7	4	16 - 20	5	3
41 - 50	8	5	21 - 30	7	3
			31 - 40	8	4
			41 - 50	10	5
≥ 51	20% but ≤ 20	10% but ≤ 10	≥ 51	20% but ≤ 20	10% but ≤ 10

The sample units to be inspected were determined through a systematic random sampling technique to provide an unbiased representation of sample units for each pavement facility. The sample unit locations had been determined in such a way that they are distributed evenly throughout each defined pavement section area. In certain cases when no representative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from each inspected sample unit are used to compute the PCI value and rating for each Section using the ASTM D 5340-11 and MicroPAVER software. Figures 1-2 and 1-3 depict graphical representations of the color ranges associated with PCI values and ranges with



a photograph of airfield pavement that exhibited the conditions for both flexible and rigid pavements respectively.

Figure 1-2: Flexible Pavement, Asphalt Concrete









	PCI	PCI	REPRESENTATIVE PAVEMENT SURFACE	REPAIR ACTIVITIES
ROUTINE MAINTENANCE	86 - 100	90		Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching.
PAVEMENT PRESERVATION	65 - 85	70		Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
MAJOR REHABILITATION	40 - 64	40		Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as pavement mill and overlay or PCC restoration activity.
MAJOR REHABILITATION	0 - 39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction.



Figure 1-3: Rigid Pavement, Portland Cement Concrete

	PCI	PCI	REPRESENTATIVE PAVEMENT SURFACE	REPAIR ACTIVITIES
ROUTINE MAINTENANCE	86 - 100	90		Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching.
PAVEMENT PRESERVATION	65 - 85	70		Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments, patches, and/or joint/crack sealing.
MAJOR REHABILITATION	40 - 64	40		Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as Slab replacement and PCC restoration activity.
MAJOR REHABILITATION	0 - 39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction.

Using the ASTM D 5340-11 standard seven qualitative ranges, the SAPMP provides a PCI value and a standard qualitative condition rating for the pavement facilities inspected.



## 2. AIRFIELD PAVEMENT NETWORK DEFINITION AND PAVEMENT INVENTORY

---

Brooksville – Tampa Bay Regional Airport (BKV) is located approximately six miles southwest of Brooksville, Florida. Directly regulated by the Hernando County Board of County Commissioners, this airport focuses primarily on serving general aviation aircraft. The airport facility includes two runways: Runway 3-21 (Length = 5,015 ft) and Runway 9-27 (Length = 7,002 ft). Both runways are served by full-length parallel taxiways with the general aviation ramp being located to the northeast of the airfield. Private hangar facilities are located throughout the north side of Taxiway Alpha on the north side of the airfield.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric attributes may vary slightly from the geometry used in the condition exhibit in Appendix B and the major rehabilitation exhibit in Appendix F based on field measurements.

The Brooksville – Tampa Bay Regional Airport was originally constructed in 1942 by the War Department and known as Brooksville Army Airfield. The airfield was used as an auxiliary airfield to MacDill Field and Drew Field for training pilots and ground crews during World War II. In late 1945, it began concluding its activities and closing down. In 1948, the airfield was deeded to the City of Brooksville who subsequently transferred the property to Hernando County. In April 2013, for improved geographic reference and to reflect its inclusion within the Tampa Bay region, the airport was renamed Brooksville – Tampa Bay Regional Airport.

Brooksville – Tampa Bay Regional Airport is designated as a General Aviation (GA) airport and is located in District 7 of the Florida Department of Transportation

### 2.1 Network Definition

The airfield pavements within each airport network are separated into manageable units within the FDOT SAPMP MicroPAVER database system, organizing pavement data by similar use and constructive history.

#### *Branch and Section Identification*

Each airport's airfield pavement network is generally subdivided into separate Branches (runways, taxiways, aprons/ramps, or others) that have distinctly different functional identifications and uses. Each Branch is further subdivided



into Sections as defined by pavement location, composition, and construction history. A Section is typically understood to be a project level subdivision within a Branch feature. Sections are manageable units to organize data collection and are treated individually during the maintenance and major rehabilitation planning process. A pavement rank (primary, secondary, or tertiary) is assigned to each Section based on its importance and type of use to airport operations. The pavement rankings designated for each section at this airport were defined by the previous SAPMP, unless changes were communicated by the airport. These Sections are further subdivided into condition survey sample units based on the methodology described in ASTM D 5340.

#### *Airfield Pavement System Inventory and Network Definition Update*

The Airfield Pavement System Inventory and Airfield Pavement Network Definition Exhibits are developed individually for each participating airport. Based on information requested of and provided by the airport, the airfield pavements are evaluated on designation updates, and recent or anticipated pavement construction activity. As mentioned previously, a Section is defined partially by its construction history; this variable that factored in the performance and condition of the pavement section.

The Airfield Pavement System Inventory Exhibit, Figure A-2 in Appendix A, is a snapshot of recent and anticipated airfield pavement construction activity communicated by the airport since the last SAPMP update. Construction activities identified include maintenance and repair activity, major rehabilitation, and airfield pavement expansion efforts. Maintenance and repair activity may include; surface treatments, crack sealing, patching, slab replacement, and others. Both maintenance and rehabilitation activities are identified at the pavement section level. This type of work may result in an increase in overall Section PCI since the last inspection. Major rehabilitation efforts may include; asphalt milling and overlay, and full depth pavement reconstruction. This type of effort will result in a resetting of the pavement section PCI value to 100 due to the nature of the work. Lastly, airfield pavement expansions are accounted for as new inventory and assigned a section PCI of 100. Typically the new pavement sections are not inspected due to its condition; however these pavements are incorporated into the SAPMP pavement database. When possible, these changes are reflected in the Airfield Pavement Network Definition Exhibit, in Appendix A, prior to the field inspection. The updates are typically discussed and confirmed with airport personnel at the beginning and end of condition survey inspections to ensure accuracy.





The Airfield Pavement Network Definition Exhibit depicts the airport's pavement limits with Branch and Section delineations. This exhibit also includes the subdivision on Section areas into sample units and is used to identify those sample units that are to be inspected. The previous SAPMP Airfield Pavement Network Definition Exhibits were used as a base. Updates and information provided by each airport was reviewed and the exhibits were revised appropriately. Characteristics that are considered include; airfield configuration, branch designations (magnetic declination, Airport Layout Plan updates) and pavement composition. The exhibit serves not only as a primary guide for the airfield inspectors but also allows specific distresses found in the re-inspection report to be geographically located.

Due to recent and anticipated construction efforts; pavement area sections may have been consolidated and created which will affect the total number of sample units to be inspected based upon the methods described in ASTM D 5340 and from the sampling rate schedule. Table 2-1 summarizes the recent and anticipated airfield pavement construction efforts communicated by the airport.

Table 2-1: Recent and/or Anticipated Airfield Pavement Construction

Construction Year	Section Location	Work Type/Pavement Section
2011	RUNWAYS AND TAXIWAYS	SPALL AND JOINT REPAIR
2014	NORTHEAST APRON	RESURFACING OF AC PAVEMENTS



### *Airfield Pavement Network Definition & Geographic Information System (GIS)*

As part of this SAPMP update, geographic information system (GIS), global positioning system (GPS), and digital data collection were integrated into the Pavement Inspection Methodology at each airport. Using AutoCAD Civil 3D, ArcMap, ArcPad, and FDOT Survey and Mapping Office Aerial Photography; digital navigation maps have been developed for each airport to represent the SAPMP pavement inventory attributes. These navigation maps were used with field data tablets to assist survey teams as they performed condition inspections by navigating pavement infrastructure and collecting distress data.

## **2.2 Pavement Inventory**

The detailed pavement inventory database was updated to reflect the Airfield Pavement Network Definition Exhibit, in Appendix A, updates and field inspection results. Table 2-2 and Figure 2-1 provides a summary of the pavement inventory attributes at Brooksville - Tampa Bay Regional Airport-(BKV) for this SAPMP update.




Table 2-2: Pavement Inventory Summary

Airfield Pavement Network Definition		
Number of Branches	15	
Number of Sections	37	
Sample Units	136	
Airfield Pavement Use		
Use	Area (SF)	Relative Area (%)
Runway	1,802,250	47%
Taxiway	1,259,981	33%
Apron	784,074	20%
Total =	3,846,305	100%
Airfield Pavement Type		
Type	Area (SF)	Relative Area (%)
Asphalt Concrete (AC)	1,116,110	29%
Asphalt Overlay (AAC)	48,980	1%
Portland Cement Concrete (PCC)	2,681,215	70%
AC over PCC (APC)	0	0%



Figure 2-1: Airfield Pavement Type



Specific details to each Branch and Section such as; name, geometry, age, rank, surface type, and construction history are provided in Table 2-3.

Table 2-3: Airfield Pavement Inventory Details

Branch Name	Branch ID	Section ID	True Area (SF)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
RUNWAY 3-21	RW 3-21	6210	501,500	S	PCC	1/1/1942	20	100
RUNWAY 3-21	RW 3-21	6205	250,750	S	PCC	1/1/1942	10	50
RUNWAY 9-27	RW 9-27	6110	700,000	P	PCC	1/1/1942	20	140
RUNWAY 9-27	RW 9-27	6105	350,000	P	PCC	1/1/1942	14	70
SOUTH APRON	AP S	4225	114,556	P	AC	1/1/2009	4	28
SOUTH APRON	AP S	4220	28,845	P	AC	12/25/1999	1	7
SOUTH APRON	AP S	4215	32,595	P	AC	12/25/1999	1	7
SOUTH APRON	AP S	4210	52,541	P	AC	12/25/1999	1	9
SOUTH APRON	AP S	4205	3,398	P	AC	1/1/1991	1	1



Branch Name	Branch ID	Section ID	True Area (SF)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
NE APRON	AP NE	4150	28,017	P	PCC	1/1/1991	1	5
NE APRON	AP NE	4147	7,371	P	AAC	1/1/1989	1	2
NE APRON	AP NE	4145	72,809	P	AC	1/1/1991	2	13
NE APRON	AP NE	4140	222,039	P	AC	1/1/1991	5	44
NE APRON	AP NE	4135	59,122	P	AC	1/1/1983	2	12
NE APRON	AP NE	4130	6,146	P	PCC	1/1/1942	1	1
NE APRON	AP NE	4125	23,740	P	AAC	1/1/1975	1	5
NE APRON	AP NE	4120	53,058	P	AC	1/1/1964	2	11
NE APRON	AP NE	4115	35,800	P	AC	1/1/1975	2	6
NE APRON	AP NE	4110	14,592	P	AC	1/1/1975	1	4
NE APRON	AP NE	4105	29,444	P	AC	1/1/1975	1	7
TAXIWAY B4	TW B4	230	6,246	P	AC	1/1/1991	1	2
TAXIWAY B3	TW B3	225	7,309	P	AC	1/1/1991	1	2
TAXIWAY B2	TW B2	220	7,309	P	AC	1/1/1990	1	2
TAXIWAY B1	TW B1	216	45,429	P	AC	1/1/1991	2	9
TAXIWAY B1	TW B1	215	63,745	P	PCC	1/1/1942	3	16
TAXIWAY B	TW B	210	118,423	P	AC	1/1/1991	5	34
TAXIWAY B	TW B	205	55,550	P	AC	1/1/1990	3	15
TAXIWAY B1	TW B1	145	80,954	P	AC	1/1/1998	3	18
TAXIWAY A9	TW A9	140	31,973	P	PCC	1/1/1942	2	8
TAXIWAY A6	TW A6	135	31,614	P	AC	1/1/1986	2	9
TAXIWAY A5	TW A5	130	33,046	P	PCC	1/1/1942	2	8
TAXIWAY A3	TW A3	125	26,322	P	AC	1/1/1986	1	5
TAXIWAY A3	TW A3	120	10,836	P	PCC	1/1/1942	1	2



Branch Name	Branch ID	Section ID	True Area (SF)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
TAXIWAY A1	TW A1	112	18,154	P	AC	1/1/1964	1	5
TAXIWAY A1	TW A1	111	17,870	P	AAC	1/1/1991	1	4
TAXIWAY A1	TW A1	110	56,894	P	PCC	1/1/1942	3	15
TAXIWAY A	TW A	105	648,307	P	PCC	1/1/1942	13	173

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.





### 3. AIRFIELD PAVEMENT CONDITION

---

Airfield pavement distresses and condition were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6B and ASTM D 5340-11. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating.

The program has been updated from ASTM D 5340-04, released in 2004, to ASTM D 5340-11, released in 2011, for this SAPMP update. The primary updates include the separation of certain distress types and the addition of new types with corresponding changes to PCI calculation. These changes in distress classification may result in small variances in the PCI values from the previous inspection analyses.

#### 3.1 Inspection Methodology

A pavement condition survey inspection is performed by measuring the amount and severity of defined pavement distresses observed within the boundaries of sample units. These distresses, as defined by ASTM D 5340, are generally caused by traffic fatigue loading, exposure to climate and elements, and other airfield specific factors. This data is collected by field personnel experienced in pavement condition survey inspection. Data collection is then transferred into the FDOT MicroPAVER database system. MicroPAVER is used to calculate PCI values using the methodology described in ASTM D 5340-11. The values are calculated for each sample and extrapolated on a Section level to determine an area-weighted PCI value ranging from 0 to 100 and one of seven condition ratings. Tables 3-1 and 3-2 describe the distresses as defined by the ASTM D 5340-11 and adopted for the SAPMP procedures.



Table 3-1: Airfield Pavement Distresses for Asphalt Concrete

Code	Distress	Primary Mechanisms
41	Alligator Cracking	Load / Fatigue Failure
42	Bleeding	Construction Quality/ Mix Design
43	Block Cracking	Climate / Age
44	Corrugation	Load / Construction Quality
45	Depression	Subgrade Quality
46	Jet Blast	Aircraft
47	Joint Reflection - Cracking	Climate / Prior Pavement
48	Longitudinal/Transverse Cracking	Climate / Age
49	Oil Spillage	Aircraft / Vehicle
50	Patching	Utility / Pavement Repair
51	Polished Aggregate	Repeated Traffic Loading
52	Raveling	Climate / Load
53	Rutting	Repeated Traffic Loading
54	Shoving	PCC Pavement Growth / Movement
55	Slippage Cracking	Load / Pavement Bond
56	Swelling	Climate / Subgrade Quality
57	Weathering	Climate

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual



Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete

Code	Distress	Primary Mechanisms
61	Blow-up	Climate / Alkali Silica Reaction
62	Corner Break	Load Repetition / Curling Stresses
63	Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
64	Durability Cracking	Freeze-Thaw Cycling
65	Joint Seal Damage	Material Deterioration / Construction Quality
66	Small Patch	Pavement Repair
67	Large Patch/Utility Cut	Utility / Pavement Repair
68	Popout	Freeze-Thaw Cycling
69	Pumping	Load Repetition / Poor Joint Sealant
70	Scaling/Crazing	Construction Quality / Freeze-Thaw Cycling
71	Faulting	Load Repetition / Subgrade Quality
72	Shattered Slab	Overloading
73	Shrinkage Cracking	Construction Quality / Load
74	Joint Spalling	Load Repetition / Infiltration of Incompressible Material
75	Corner Spalling	Load Repetition / Infiltration of Incompressible Material
76	Alkali-Silica Reaction	Construction Quality / Climate

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

## 3.2 Airfield Pavement Condition Index Rating Results

From the condition survey inspection performed in 2013 at Brooksville - Tampa Bay Regional Airport, the overall weighted average PCI value is 56 representing a condition rating of Fair.

Overall the airport exhibited pavement distresses associated with climate and age distress. Both runways and the parallel taxiway to Runway 9-27 (Alpha) are constructed of PCC pavement. Runway 3-21's parallel taxiway (Bravo) and the majority of the general aviation ramp is constructed of AC pavement.

Runway 3-21 exhibited low and medium severity map cracking, longitudinal, transverse and diagonal cracking, joint spalling, corner spalling, patching, and shrinkage cracking. One instance of a high severity shattered slab was located



and identified to the airport for future repair due to its high risk of FOD. The majority of these distresses observed can be attributed to the age of the PCC pavement.

Runway 9-27 exhibited very similar distresses to Runway 3-21 while having isolated locations of high severity joint spalling.

Taxiways Alpha exhibited the same distresses as both runways which is to be expected based on its same construction date as both of the PCC runways.

Taxiway Bravo exhibited AC pavement distresses including low and medium severity longitudinal/transverse cracking, low, medium and high severity raveling, and low severity weathering. Isolated low severity swelling was observed on several of the taxiway connectors to Runway 3-21.

The general aviation ramp exhibited a variety of AC pavement distresses throughout which vary greatly from pavement section to pavement section due to the vast differences in the pavement construction history. Several of the older pavement sections exhibited low severity block cracking, low and medium severity longitudinal/transverse cracking, low and medium severity raveling. Low severity depressions were also identified at multiple locations throughout the ramp area.

Appendix B contains Table B-1 and an Airfield Pavement Condition Index Rating Exhibit, Figure B-1, which depicts the PCI results by Section, and Appendix C contains MicroPAVER reports of PCI results by Branch and Section. Appendix H includes detailed distress data generated by MicroPAVER for each inspected sample unit.

The pavement condition at Brooksville - Tampa Bay Regional Airport is represented in Figure 3-1 in accordance with the condition categories and PCI scale referenced in ASTM D 5340. Further detail is provided in Table 3-3 which describes the breakdown of the airport's airfield conditions according to area and use.

Appendix B contains Table B-1 summarizes the Section Condition values and the Airfield Pavement Condition Index Rating Exhibit, Figure B-1, that depicts the PCI results by Section. Appendix H is dedicated to the reporting of the specific airfield pavement distress data collected at the time of the inspection for this update.



Figure 3-1: Airfield Pavement Condition Index Rating Summary






Table 3-3: Pavement Condition Index Rating Summary

Airfield Pavement Use		
Use	Average Area-Weighted PCI	Condition Rating
Runway	54	POOR
Taxiway	52	POOR
Apron	68	FAIR
Condition Area		
Condition Rating	Area (SF)	Relative Area (%)
Good	114,556	3%
Satisfactory	353,458	9%
Fair	1,274,644	33%
Poor	1,976,705	51%
Very Poor	69,005	2%
Serious	57,936	2%
Failed	-	0%


Approximately 12% of the airfield network is in Good and Satisfactory condition; while 55% of the network is in a Poor to Serious condition. Table 3-3 provides a breakdown of total area for each pavement by condition rating. Figures 3.2 a, b, c depict the condition rating of the airfield pavement by Branch Use. Photographs taken during the condition survey inspection are included in Appendix G. The photographs included are intended to be representative of the distress observed.






Figure 3-2: Percentage of Pavement Area by Condition Rating by Use

(a) Runway




(b) Taxiway





(c) Apron





## 4. PAVEMENT PERFORMANCE

Pavement performance models are developed from the distress data collected for the SAPMP for the Florida Airports System. This data is consolidated in a database and organized by inspection date, pavement type, age, pavement use, and airport category. The pavement performance models are used to develop broad prediction models, also known as pavement condition deterioration curves.

The consolidation of the Florida Airports System's pavement infrastructure within the FDOT SAPMP is based on data that have been collected in a consistent method of measurement. The historic pavement condition, or performance trend, has been compiled throughout the system with data from the inception of the SAPMP. This data is processed into models that have been analyzed and developed into prediction curves based upon pavement characteristics. These characteristics include; climate, construction material, and operations. Each model has been developed based on the following criteria:

AIRPORT TYPE (Primary, Regional Reliever, or General Aviation)

>FACILITY USE (Runway, Taxiway, or Apron)

>>FACILITY SURFACE TYPE (AC, AAC, APC, or PCC)

The historic trends of pavement performance at Florida airport facilities for all performance models are consolidated within the program database. This information is utilized in the prediction of pavement performance based on the current PCI determined from the inspections that took place between 2013 and 2014. Major rehabilitation is planned based on the predicted PCI. The intent of this is for both the individual airport and the FDOT District personnel to be aware of anticipated major rehabilitation work based on condition.

Each airport's airfield pavement section condition, for a given inspection year, is one data point that was used as the basis of each performance trend using a performance model based on pavements of similar background. Figures 4-1, 4-2, and 4-3 represent the pavement performance prediction at Brooksville - Tampa Bay Regional Airport based on pavement use. Each figure depicts the FDOT recommended Minimum Service Level PCI value for each pavement type.



Figure 4-1: Runway Pavement Performance Prediction Summary




Figure 4-2: Taxiway Pavement Performance Prediction Summary







Figure 4-3: Apron Pavement Performance Prediction Summary



Pavement performance modeling to predict the future PCI is primarily done to predict PCI at the Section level for the purpose of planning Major Rehabilitation work. In Appendix D, Table D-1 represents the predicted area-weighted PCI by Section for the airport's airfield pavement infrastructure.



## 5. AIRFIELD PAVEMENT MAINTENANCE POLICIES AND COSTS

---

### 5.1 Policies

Airfield Pavement Maintenance policies are guidance on pavement construction methods used to develop, maintain, repair, and rehabilitate pavement infrastructure based on distresses encountered during the condition surveys.

Maintenance refers to the repair and preservation-type activities that are applied locally to specific distress types on the pavement. These activities for the SAPMP are considered preventative and corrective in nature and are highly recommended to help improve pavement performance and extend pavement life. The SAPMP maintenance policies are based on the FAA Advisory Circular 150/5380-6B and guidance provided in the FDOT Airfield Pavement Repair Manual.

For the purpose of the SAPMP; the maintenance repair needs that are identified and quantified are based solely on the pavement distresses observed and recorded at the time of the inspection. Based on a specific distress type and severity observed, a particular repair work type is recommended and quantified based on the extrapolated section distresses. The repair program identified is specific to the current distresses. Future maintenance planning budgets are based on this initial determination. Tables 5-1 and 5-2 provide the list of maintenance activities incorporated into the SAPMP MicroPAVER database to treat specific distress types and severities.





Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy

Surface Type	Distress Code	Distress Name	Severity	Maintenance Work Type	Work Unit
Flexible Asphalt Concrete (AC, AAC, APC)	41	Alligator Cracking	L, M, H	Full Depth Pavement Patch	Square Feet
	42	Bleeding	N/A	Partial Depth Pavement Patch	Square Feet
	43	Block Cracking	L	Seal Coat Treatment	Square Feet
	43	Block Cracking	M, H	Full Depth Pavement Patch	Square Feet
	44	Corrugation	L, M, H	Full Depth Pavement Patch	Square Feet
	45	Depression	L, M, H	Full Depth Pavement Patch	Square Feet
	46	Jet Blast Erosion	L, M, H	Full Depth Pavement Patch	Square Feet
	47	Joint Reflection Cracking	L	Crack Sealing	Linear Feet
	47	Joint Reflection Cracking	M, H	Full Depth Pavement Patch	Square Feet
	48	Longitudinal/Transverse Cracking	L, M, H	Crack Sealing	Linear Feet
	49	Oil Spillage	L, M	Seal Coat Treatment	Square Feet
	49	Oil Spillage	H	Full Depth Pavement Patch	Square Feet
	50	Patch and Utility Patching	M	Crack Sealing	Linear Feet
	50	Patch and Utility Patching	H	Full Depth Pavement Patch	Square Feet
	51	Polished Aggregate	L, M, H	Slurry Seal Coat Treatment	Square Feet
	52	Raveling	L, M	Slurry Seal Coat Treatment	Square Feet
	52	Raveling	H	Partial Depth Pavement Patch	Square Feet
	53	Rutting	L, M, H	Full Depth Pavement Patch	Square Feet
	54	Shoving	L, M, H	Grinding / Removal	Square Feet
	55	Slippage Cracking	L, M, H	Full Depth Pavement Patch	Square Feet
	56	Swelling	M, H	Full Depth Pavement Patch	Square Feet
	57	Weathering	M, H	Seal Coat Treatment	Square Feet



Table 5-2: Recommended PCC Maintenance and Repair Policy

Surface Type	Distress Code	Distress Name	Severity	Maintenance Work Type	Work Unit
Rigid Pavement (PCC)	61	Blowup	L, M, H	Slab Replacement / Full Depth Patch	Square Feet
	62	Corner Break	L, M, H	Partial Patch - PCC	Square Feet
	63	Longitudinal/Transverse/Diagonal Cracking	H	Crack Sealing - PCC	Linear Feet
	64	Durability Cracking	M, H	Slab Replacement / Full Depth Patch	Square Feet
	65	Joint Seal Damage	L, M, H	Joint Seal Repair (Local)	Linear Feet
	66	Patching, Small	M, H	Slab Replacement / Full Depth Patch	Square Feet
	67	Patching, Large	M, H	Slab Replacement / Full Depth Patch	Square Feet
	68	Popouts	L	Crack Sealing - PCC	Linear Feet
	69	Pumping	L, M, H	Slab Stabilization / Slab Jacking	Square Feet
	70	Scaling/Map Cracking/Crazing	L, M	Micro-mill and Seal - PCC	Square Feet
	70	Scaling/Map Cracking/Crazing	H	Slab Replacement / Full Depth Patch	Square Feet
	71	Settlement / Faulting	L	Micro-mill and Seal - PCC	Square Feet
	71	Settlement / Faulting	M, H	Slab Stabilization / Slab Jacking	Square Feet
	72	Shattered Slab	L, M, H	Slab Replacement / Full Depth Patch	Square Feet



Surface Type	Distress Code	Distress Name	Severity	Maintenance Work Type	Work Unit
	73	Shrinkage Cracks	N/A	Crack Sealing - PCC	Linear Feet
	74	Longitudinal/Transverse Joint Spalling	L, M, H	Partial Patch - PCC	Square Feet
	75	Corner Spalling	L, M, H	Partial Patch - PCC	Square Feet
	76	Alkali-Silica Reaction	L	Seal Coat Treatment	Square Feet
	76	Alkali-Silica Reaction	M	Micro-mill and Seal - PCC	Square Feet
	76	Alkali-Silica Reaction	H	Slab Replacement / Full Depth Patch	Square Feet

Though proactive pavement maintenance and preservation is highly recommended in an APMS; it is recognized that pavement that has deteriorated below a certain PCI will require a major rehabilitation rather than localized maintenance and repair work. Major rehabilitation is recommended when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that maintenance repair efforts are no longer cost-efficient. This critical point is called "Critical PCI". The critical PCI levels for different pavement and branch types were established by the FDOT and were used in this update to develop a maintenance and major rehabilitation plan for the airport. Sections that are above the "Critical PCI" levels will be recommended for maintenance, repair, and preservation treatments, assuming there are no significant load-related distresses. For those Sections below the Critical PCI, the recommended action will consist of major rehabilitation work. This approach is used for the current Section's PCI value and the predicted PCI value for future rehabilitation.

The FDOT has recommended minimum service level PCI for airports based on pavement facility use, airport type, and expected loading frequency. This minimum service level PCI is recommended to ensure the pavement provides a safe operational surface and efficiently uses maintenance and rehabilitation budgets. Separately, the Critical PCI is a value based on historic pavement performance trends and costs. It is at a PCI value of 65, for most airports, at which major rehabilitation is recommended over maintenance level efforts.



Table 5-3 identifies the FDOT recommended PCI by use and the critical PCI value for the most important pavements at the airport. This is due to the condition of the pavement and the cost effectiveness of the work. A very important concept of a good pavement management system is the proactive preservation of pavements that are above Critical PCI condition. Conversely, allowing pavement to deteriorate beyond maintenance and performing “worst first” major rehabilitation may cost much more over the life of a pavement.

**Table 5-3: Critical and Minimum Service Level PCI for General Aviation Airports**

Use	FDOT Recommended PCI	Critical PCI
Runway	75	65
Taxiway	65	65
Apron	60	65

Based on historic trends of pavement performance and industry standard practices in pavement maintenance and rehabilitation, the SAPMP included general guidance on construction activity based on condition PCI, as shown on Table 5-4. It is recommended that further investigation of underlying pavement conditions is performed at the design phase.

**Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI**

Category	Activity	PCI Range
Maintenance	<ul style="list-style-type: none"> <li>▪ Crack Sealing (AC/PCC)</li> <li>▪ Partial Depth Patching (AC)</li> <li>▪ Full Depth Patching (AC/PCC)</li> <li>▪ Surface Treatment (AC)</li> </ul>	75 - 90
Rehabilitation	<ul style="list-style-type: none"> <li>▪ Mill and Overlay (AC)</li> <li>▪ Concrete Pavement Restoration (PCC)</li> </ul>	40 - 74
	<ul style="list-style-type: none"> <li>▪ Full Depth Pavement Reconstruction</li> </ul>	0 - 39

The PCI standard scale ranges from a value of 0, typically representing a pavement in a failed condition, to a value of 100 which typically represents a pavement in new or good condition. Generally, airfield pavement sections with



a PCI of 75 or higher that are not exhibiting distresses due to aircraft loading will benefit from maintenance activities such as crack sealing, patching, and surface treatments. Pavement sections with PCI values within the range of 40 to 74 may require major rehabilitation, such as a mill and overlay. Lastly, pavement sections with a PCI value of 40 or less are recommended to undergo pavement reconstruction. Generally pavement reconstruction is the only practical means of restoration due to the substantial distresses observed in the pavement structure. Since PCI values are based solely on the visual determination of pavement distresses and deterioration, this method does not provide a direct measure of structural integrity.

## 5.2 Unit Costs

The FDOT SAPMP developed and updated the maintenance and major rehabilitation costs based on public cost databases for airport and highway pavement construction. Additionally, cost data collected from FDOT and FAA sponsored projects in the Florida Airports System were utilized to identify construction cost trends across the state.

The maintenance, repair, and preservation activity costs have been updated and developed using readily available construction cost data at the time of this update. The costs depicted in this report for both maintenance and major rehabilitation are intended for planning purposes.

## 5.3 Maintenance, Repair, and Major Rehabilitation

FDOT recognizes that although pavement mill and overlay is recommended for flexible asphalt concrete pavement within a PCI range from 40 to 74, it is conceivable that airports may not have adequate funding to perform this type of major rehabilitation. A comprehensive surface treatment; such as GSB-88 and Microsurfacing, as a maintenance rehabilitation activity, can be used in lieu of asphalt concrete pavement mill and overlay. However, it should be understood that these measures provide only a short term extension of pavement life. While the cost of surface treatments are significantly lower than that of pavement mill and overlay, it is not intended or implied to be a full rehabilitative measure for long term benefit. Table 5-5 and Table 5-6 provide budget costs associated with the work types shown in the table.



Table 5-5: AC Maintenance Unit Costs

Surface Type	Maintenance Work Type	Cost	Work Unit
Flexible Asphalt Concrete (AC, AAC, APC)	Full Depth Pavement Patch	\$5.00	Square Feet
	Partial Depth Pavement Patch	\$3.00	Square Feet
	Seal Coat Treatment	\$0.55	Square Feet
	Crack Sealing	\$2.75	Linear Feet
	Slurry Seal Coat Treatment	\$0.55	Square Feet
	Grinding / Removal	\$2.10	Square Feet

Table 5-6: PCC Maintenance Unit Costs

Surface Type	Maintenance Work Type	Cost	Work Unit
Rigid Pavement (PCC)	Slab Replacement / Full Depth Patch	\$45.00	Square Feet
	Partial Patch - PCC	\$19.10	Square Feet
	Crack Sealing - PCC	\$4.25	Linear Feet
	Joint Seal Repair (Local)	\$3.00	Linear Feet
	Slab Stabilization / Slab Jacking	\$45.00	Square Feet
	Micro-mill and Seal - PCC	\$1.00	Square Feet
	Seal Coat Treatment	\$1.00	Square Feet

As part of the SAPMP update, the distress data observed at each airport during the inspection is extrapolated on a section basis to make maintenance recommendations. These recommendations are a direct result of the distress types, severities, and quantities observed at the time of inspection. The





maintenance recommendations and planning costs are correlated with the airport's airfield pavement network's overall area weighted PCI and used to plan future maintenance costs. Future maintenance costs are planning budgets that are not specific to a pavement section, but are estimates for the entire airfield. Table 5-7 provides budget costs associated with the rehabilitation activities.

Table 5-7: Rehabilitation Activities and Unit Costs by Condition for General Aviation Airports

Category	Activity	PCI Range	Cost/SqFt
Rehabilitation	▪ Mill and Overlay (AC)	40 - 74	\$8.00
	▪ Concrete Pavement Restoration (PCC)		\$10.00
	▪ Full Depth Pavement Reconstruction	0 - 39	\$15.00

A cost scale has been developed based on PCI to develop planning level budgets for the airfield pavements. The cost scale is adjusted by project year based on an assumed inflation rate of 3%. In Appendix E, Table E-1 summarizes the Year-1 maintenance and repair recommendations based on the most recent inspection. The summary in Table E-1 does not take into account any rehabilitation activities, but rather summarizes preventative activities for all PCI ranges, including below critical PCI sections.



## 6. MAJOR PAVEMENT REHABILITATION NEEDS

As part of the SAPMP, major pavement rehabilitation planning is developed based on current and predicted PCI in comparison with the Critical PCI. The Critical PCI has been determined based on the historic trends of pavement condition relative to the benefit of maintenance and repair activities. Pavement sections determined to have a PCI less than that of the Critical PCI are assumed to have deteriorated to a point at which maintenance and repair level activity would provide little benefit.

The objective of the major pavement rehabilitation needs analysis is to provide planning level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value from a functionality perspective. In addition, major rehabilitation is also recommended when the Section PCI is above the Critical PCI but the Section has load-related PCI distresses. However, most major rehabilitation work is recommended when the Section PCI is below the Critical PCI, which is when maintenance and repair level activities are not considered to be cost effective.

Major rehabilitation is identified within the SAPMP as major construction activity that would result in an improvement or "resetting" of the pavement section's PCI to a value of 100. Such activities could include; mill and hot-mix asphalt overlay and re-construction. This analysis was conducted with no constraints to budgets as a means to identify all pavement projects based on Critical PCI for a 10-year duration. It is recommended that the airport use this as a planning tool for future project development and prioritization. Table 6-1 depicts the major rehabilitation work identified on the pavement section level based on current and predicted pavement PCI.



Table 6-1: Summary of Major Rehabilitation


Year	Branch Name	Section ID	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2014	AP NE	4135	\$ 591,224.27	63	Mill and Overlay	100
2014	AP NE	4145	\$ 728,091.77	55	Mill and Overlay	100
2014	AP NE	4147	\$ 73,709.00	55	Mill and Overlay	100
2014	AP NE	4150	\$ 280,173.09	56	PCC Restoration	100
2014	AP NE	4125	\$ 237,395.29	62	Mill and Overlay	100
2014	AP NE	4110	\$ 145,918.09	51	Mill and Overlay	100
2014	AP NE	4130	\$ 92,197.07	35	Reconstruction	100
2014	AP NE	4115	\$ 357,996.18	51	Mill and Overlay	100
2014	AP NE	4105	\$ 330,801.57	48	Mill and Overlay	100
2014	AP NE	4120	\$ 530,576.18	52	Mill and Overlay	100
2014	AP S	4205	\$ 33,984.70	64	Mill and Overlay	100
2014	RW 3-21	6210	\$ 5,014,999.76	54	PCC Restoration	100
2014	RW 3-21	6205	\$ 2,507,499.88	52	PCC Restoration	100
2014	RW 9-27	6105	\$ 4,205,250.52	46	PCC Restoration	100
2014	RW 9-27	6110	\$ 6,999,999.67	57	PCC Restoration	100
2014	TW A3	125	\$ 394,835.34	20	Reconstruction	100
2014	TW A	105	\$ 6,570,585.63	50	PCC Restoration	100
2014	TW A6	135	\$ 474,208.76	20	Reconstruction	100
2014	TW B	205	\$ 833,257.40	38	Reconstruction	100
2014	TW A1	110	\$ 568,940.67	52	PCC Restoration	100
2014	TW A1	112	\$ 241,721.64	43	Mill and Overlay	100
2014	TW A3	120	\$ 158,483.82	41	PCC Restoration	100
2014	TW A5	130	\$ 330,460.18	58	PCC Restoration	100
2014	TW B1	215	\$ 637,452.57	57	PCC Restoration	100
2014	TW B1	216	\$ 454,292.08	58	Mill and Overlay	100
2014	TW B2	220	\$ 109,627.83	38	Reconstruction	100
2014	TW B3	225	\$ 73,085.20	59	Mill and Overlay	100
2014	TW B4	230	\$ 62,462.40	62	Mill and Overlay	100
2016	TW A9	140	\$ 339,201.65	64	PCC Restoration	100
2016	TW B	210	\$ 1,256,344.46	65	Mill and Overlay	100
2017	AP S	4210	\$ 574,127.59	65	Mill and Overlay	100
2017	AP S	4220	\$ 315,200.91	65	Mill and Overlay	100
2023	TW B1	145	\$ 1,056,260.16	65	Mill and Overlay	100
2023	AP NE	4140	\$ 2,897,109.11	65	Mill and Overlay	100
Total =			\$39,477,474.44			

\*Costs are adjusted for inflation at 3%.



The 10-year major rehabilitation program addresses those pavement sections that have a current or project PCI that is below the Critical PCI of 65 during the 10-year analysis period. The unconstrained or “unlimited budget” Major Rehabilitation Program is compared to a “No Major Rehabilitation Program” scenario in Figure 6-1. As shown, if no major rehabilitation work is completed in the next 10 years at your airport, the average PCI may be 29 points less than a plan that provides timely repairs to the airfield pavements.

Figure 6-1: 10-Year Major Rehabilitation Budget Scenario Analysis





## 7. PREVENTATIVE AND MAJOR REHABILITATION PLANNING

The preventative and major rehabilitation results include activities that are based on distresses observed and unconstrained by budget limits. FDOT recognizes that the projects identified as Year-1 needs in 2013, based on condition, may exceed a typical annual budget level. It is recommended that each airport further evaluate each project's feasibility and desirability based on the airport's future development plans and budgeting scenarios.


In an effort to identify appropriate budget levels, the 10-year Preventative and Major Rehabilitation analysis evaluated projected budget needs based on predicted PCI of each pavement section. Table 7-1 and Figure 7-1 provides a summary of the expected preventative and major rehabilitation for each program year.

Table 7-1: 10-Year Preventative and Major Rehabilitation Summary

Program Year	Maintenance & Repair	Major Rehabilitation	Total Year Costs
2014	\$ 207,639.77	\$ 33,039,230.55	\$ 33,246,870.32
2015	\$ 219,589.87	\$ -	\$ 219,589.87
2016	\$ 177,950.77	\$ 1,595,546.10	\$ 1,773,496.87
2017	\$ 188,748.09	\$ 889,328.50	\$ 1,078,076.59
2018	\$ 238,788.73	\$ -	\$ 238,788.73
2019	\$ 502,486.88	\$ -	\$ 502,486.88
2020	\$ 742,429.75	\$ -	\$ 742,429.75
2021	\$ 999,267.46	\$ -	\$ 999,267.46
2022	\$ 1,263,019.43	\$ -	\$ 1,263,019.43
2023	\$ 1,266,090.66	\$ 3,953,369.27	\$ 5,219,459.93
Total =			\$ 45,283,485.83



Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary



According to the most recent inspections at the time of this update; the following pavement sections were identified as a Year-1 need for major rehabilitation:

- Runway 3-21 – Sections 6205 and 6210
  - PCC Restoration attributed to climate and age of pavement.
- Runway 9-27 – Sections 6105 and 6110
  - PCC Restoration attributed to climate and age of pavement.
- Taxiway A3 – Sections 120 and 125
  - Reconstruction and PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- Taxiway A – Section 105
  - PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- Taxiway A6 – Section 135
  - Reconstruction attributed to pavement repair along with the climate and age of pavement.
- Taxiway B – Section 205
  - Reconstruction attributed to climate and age of pavement.
- Taxiway A1 – Sections 110 and 112
  - Mill and Overlay along with PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.



- ◎ Taxiway A5 – Section 130
  - PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ◎ Taxiway B1 – Sections 215 and 216
  - Mill and Overlay along with PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ◎ Taxiway B2 – Section 220
  - Reconstruction attributed to climate and age of pavement.
- ◎ Taxiway B3 – Section 225
  - Mill and Overlay attributed to climate and age of pavement.
- ◎ Taxiway B4 – Section 230
  - Mill and Overlay attributed to climate and age of pavement.
- ◎ Apron NE – Sections 4135, 4145, 4147, 4150, 4125, 4110, 4130, 4115, 4105 and 4120
  - Mill and Overlay, Reconstruction and PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ◎ Apron S – Section 4205
  - Mill and Overlay attributed to subgrade quality, climate and age of pavement.

Appendix E summarizes the preventative repair recommendations for Year-1 and Appendix F provides an exhibit, Airfield Pavement Major Rehabilitation, that depicts the recommended major rehabilitation on the airfield pavement network according to work type and year.



## 8. VISUAL AID EXHIBITS

---

### 8.1 Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit in Appendix A depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D 5340-11. The exhibits are prepared and updated with information provided by the airport and from aerial imagery from the FDOT Surveying and Mapping publications.

### 8.2 Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in Appendix A depicts any recent airfield pavement construction activity reported by the airport. The exhibit is intended to identify pavement sections that may have changed in geometry and pavement composition that would affect the section delineation. The information provided in the Airport Response Form was used as the basis of the changes and confirmed with the airport personnel at the time of inspection.

### 8.3 Airfield Pavement Condition Index Rating Exhibit

The Airfield Pavement Condition Index Rating Exhibit in Appendix B has been prepared based on the section condition analysis of the distress data collected during the recent condition index rating survey. The exhibit graphically depicts the inventory with associated condition rating colors and PCI values.

### 8.4 Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit in Appendix F has been prepared based on the section pavement performance model and major rehabilitation analysis. The exhibit graphically depicts the inventory with associated rehabilitation activity, program year, and the planning level costs.

### 8.5 Airfield Pavement Condition Survey Inspection Photographs

During the field condition survey inspection; inspectors photographed representative distress types observed. Select photographs are provided in Appendix G to provide visual support to special pavement conditions or distresses observed.





## 9. RECOMMENDATIONS

---

The following recommendations were made based on the 2013 condition survey inspection, condition analysis, and maintenance/rehabilitation analysis results:

- ⦿ Runway 3-21 – Sections 6205 and 6210
  - PCC Restoration attributed to climate and age of pavement.
- ⦿ Runway 9-27 – Sections 6105 and 6110
  - PCC Restoration attributed to climate and age of pavement.
- ⦿ Taxiway A3 – Sections 120 and 125
  - Reconstruction and PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ⦿ Taxiway A – Section 105
  - PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ⦿ Taxiway A6 – Section 135
  - Reconstruction attributed to pavement repair along with the climate and age of pavement.
- ⦿ Taxiway B – Section 205 and 210
  - Mill and Overlay along with Reconstruction attributed to climate and age of pavement.
- ⦿ Taxiway A1 – Sections 110 and 112
  - Mill and Overlay along with PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ⦿ Taxiway A5 – Section 130
  - PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ⦿ Taxiway A9 – Section 140
  - PCC Restoration attributed to climate and age of pavement, load repetition and construction quality.
- ⦿ Taxiway B1 – Sections 215, 216 and 145
  - Mill and Overlay along with PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ⦿ Taxiway B2 – Section 220
  - Reconstruction attributed to climate and age of pavement.
- ⦿ Taxiway B3 – Section 225
  - Mill and Overlay attributed to climate and age of pavement.




- ◎ Taxiway B4 – Section 230
  - Mill and Overlay attributed to climate and age of pavement.
- ◎ Apron NE – Sections 4135, 4140, 4145, 4147, 4150, 4125, 4110, 4130, 4115, 4105 and 4120
  - Mill and Overlay, Reconstruction and PCC Restoration attributed to climate and age of pavement, subgrade quality, load repetition and construction quality.
- ◎ Apron S – Section 4205, 4210 and 4220
  - Mill and Overlay attributed to subgrade quality, climate and age of pavement.

# APPENDIX A

---

- AIRFIELD PAVEMENT NETWORK DEFINITION EXHIBIT
- AIRFIELD PAVEMENT SYSTEM INVENTORY EXHIBIT
- PAVEMENT GEOMETRY INVENTORY
- WORK HISTORY REPORT



NUMBER	DATE	REVISIONS
DESIGNED:	KHA	DRAWN: KHA
CHECKED:	KHA	DATE: 2013
PLOTTED: November 18, 2013 - 2:48 PM ET, Bepko, AT		



OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS



AIRFIELD PAVEMENT NETWORK DEFINITION EXHIBIT  
BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT  
HERNANDO COUNTY, FLORIDA  
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE






Table A-1: Pavement Geometry Inventory

Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
RUNWAY 3-21	RW 3-21	RUNWAY	6210	5,000	100	501,500	S	PCC	1/1/1942	6/10/2013	100
RUNWAY 3-21	RW 3-21	RUNWAY	6205	10,000	25	250,750	S	PCC	1/1/1942	6/10/2013	50
RUNWAY 9-27	RW 9-27	RUNWAY	6110	7,000	100	700,000	P	PCC	1/1/1942	6/10/2013	140
RUNWAY 9-27	RW 9-27	RUNWAY	6105	14,000	25	350,000	P	PCC	1/1/1942	6/10/2013	70
SOUTH APRON	AP S	APRON	4225	1,800	65	114,556	P	AC	1/1/2009	6/10/2013	28
SOUTH APRON	AP S	APRON	4220	453	65	28,845	P	AC	12/25/1999	6/10/2013	7
SOUTH APRON	AP S	APRON	4215	355	65	32,595	P	AC	12/25/1999	6/10/2013	7
SOUTH APRON	AP S	APRON	4210	453	112	52,541	P	AC	12/25/1999	6/10/2013	9
SOUTH APRON	AP S	APRON	4205	100	35	3,398	P	AC	1/1/1991	6/10/2013	1
NE APRON	AP NE	APRON	4150	148	200	28,017	P	PCC	1/1/1991	6/10/2013	5
NE APRON	AP NE	APRON	4147	70	200	7,371	P	AAC	1/1/1989	6/10/2013	2
NE APRON	AP NE	APRON	4145	600	120	72,809	P	AC	1/1/1991	6/10/2013	13
NE APRON	AP NE	APRON	4140	1,022	200	222,039	P	AC	1/1/1991	6/10/2013	44
NE APRON	AP NE	APRON	4135	612	95	59,122	P	AC	1/1/1983	6/10/2013	12
NE APRON	AP NE	APRON	4130	25	200	6,146	P	PCC	1/1/1942	6/10/2013	1
NE APRON	AP NE	APRON	4125	260	90	23,740	P	AAC	1/1/1975	6/10/2013	5
NE APRON	AP NE	APRON	4120	422	200	53,058	P	AC	1/1/1964	6/10/2013	11
NE APRON	AP NE	APRON	4115	500	75	35,800	P	AC	1/1/1975	6/10/2013	6
NE APRON	AP NE	APRON	4110	390	50	14,592	P	AC	1/1/1975	6/10/2013	4
NE APRON	AP NE	APRON	4105	800	42	29,444	P	AC	1/1/1975	6/10/2013	7
TAXIWAY B4	TW B4	TAXIWAY	230	150	35	6,246	P	AC	1/1/1991	6/10/2013	2
TAXIWAY B3	TW B3	TAXIWAY	225	150	35	7,309	P	AC	1/1/1991	6/10/2013	2
TAXIWAY B2	TW B2	TAXIWAY	220	150	35	7,309	P	AC	1/1/1990	6/10/2013	2
TAXIWAY B1	TW B1	TAXIWAY	216	885	50	45,429	P	AC	1/1/1991	6/10/2013	9

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
TAXIWAY B1	TW B1	TAXIWAY	215	810	75	63,745	P	PCC	1/1/1942	6/10/2013	16
TAXIWAY B	TW B	TAXIWAY	210	3,375	35	118,423	P	AC	1/1/1991	6/10/2013	34
TAXIWAY B	TW B	TAXIWAY	205	1,590	35	55,550	P	AC	1/1/1990	6/10/2013	15
TAXIWAY B1	TW B1	TAXIWAY	145	850	76	80,954	P	AC	1/1/1998	6/10/2013	18
TAXIWAY A9	TW A9	TAXIWAY	140	440	75	31,973	P	PCC	1/1/1942	6/10/2013	8
TAXIWAY A6	TW A6	TAXIWAY	135	418	53	31,614	P	AC	1/1/1986	6/10/2013	9
TAXIWAY A5	TW A5	TAXIWAY	130	430	75	33,046	P	PCC	1/1/1942	6/10/2013	8
TAXIWAY A3	TW A3	TAXIWAY	125	400	53	26,322	P	AC	1/1/1986	6/10/2013	5
TAXIWAY A3	TW A3	TAXIWAY	120	413	25	10,836	P	PCC	1/1/1942	6/10/2013	2
TAXIWAY A1	TW A1	TAXIWAY	112	455	40	18,154	P	AC	1/1/1964	6/10/2013	5
TAXIWAY A1	TW A1	TAXIWAY	111	445	40	17,870	P	AAC	1/1/1991	6/10/2013	4
TAXIWAY A1	TW A1	TAXIWAY	110	750	75	56,894	P	PCC	1/1/1942	6/10/2013	15
TAXIWAY A	TW A	TAXIWAY	105	8,650	75	648,307	P	PCC	1/1/1942	6/10/2013	173

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.



Date:09/16/2013

## Work History Report

1 of 6

Pavement Database:FDOT

Network: BKV Branch: AP NE (NE APRON) Section: 4105 Surface: AC  
 L.C.D.: 01/01/1975 Use: APRON Rank P Length: 800.00 Ft Width: 42.00 Ft True Area: 29,443.85 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1975	IMPORTED	OVERLAY			True	SOIL: SP & MS
01/01/1975	IMPORTED	BUILT		2.00	True	2" P-401 ON 6" P-211 (ESTIMATE 1975)

Network: BKV Branch: AP NE (NE APRON) Section: 4110 Surface: AC  
 L.C.D.: 01/01/1975 Use: APRON Rank P Length: 390.00 Ft Width: 50.00 Ft True Area: 14,591.81 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1975	IMPORTED	OVERLAY			True	SOIL: SP & MS
01/01/1975	IMPORTED	BUILT		2.00	True	2" P-401 ON 6" P-211 (ESTIMATE 1975)

Network: BKV Branch: AP NE (NE APRON) Section: 4115 Surface: AC  
 L.C.D.: 01/01/1975 Use: APRON Rank P Length: 500.00 Ft Width: 75.00 Ft True Area: 35,799.62 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1975	IMPORTED	BUILT		2.00	True	2" P-401 ON 6" P-211 (ESTIMATE 1975 CONSTRUCTION)
01/01/1975	IMPORTED	OVERLAY			True	SOIL: SP & MS

Network: BKV Branch: AP NE (NE APRON) Section: 4120 Surface: AC  
 L.C.D.: 01/01/1964 Use: APRON Rank P Length: 422.50 Ft Width: 200.00 Ft True Area: 53,057.62 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1964	IMPORTED	BUILT		2.00	True	1964: 2" P-401 ON 6" P-211
01/01/1964	IMPORTED	OVERLAY			True	SOIL: SP & MS

Network: BKV Branch: AP NE (NE APRON) Section: 4125 Surface: AAC  
 L.C.D.: 01/01/1975 Use: APRON Rank P Length: 260.00 Ft Width: 90.00 Ft True Area: 23,739.53 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1975	IMPORTED	OVERLAY			True	SOIL: SP & MS
01/01/1975	IMPORTED	OVERLAY			True	ESTIMATE 1975 AC OVERLAY
01/01/1964	IMPORTED	BUILT		2.00	True	1964: 2" P-401 ON 6" P-211

Network: BKV Branch: AP NE (NE APRON) Section: 4130 Surface: PCC  
 L.C.D.: 01/01/1942 Use: APRON Rank P Length: 25.50 Ft Width: 200.00 Ft True Area: 6,146.47 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		8.00	True	8" PCC PAVEMENT (ESTIMATE 1942 CONSTRUCTION)
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & MS

Network: BKV Branch: AP NE (NE APRON) Section: 4135 Surface: AC  
 L.C.D.: 01/01/1983 Use: APRON Rank P Length: 612.00 Ft Width: 95.00 Ft True Area: 59,122.43 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1983	IMPORTED	BUILT		2.00	True	1983: 2" AC TYPE S1 ON 6" P-211
01/01/1983	IMPORTED	OVERLAY			True	SOIL: SP & MS

Network: BKV Branch: AP NE (NE APRON) Section: 4140 Surface: AC  
 L.C.D.: 01/01/1991 Use: APRON Rank P Length: 1,022.50 Ft Width: 200.00 Ft True Area: 222,039.30 SqF

Work Date	Work Code	Work Description	Cost	Thickness ( in )	Major M&R	Comments
01/01/1991	IMPORTED	BUILT		2.00	True	1991: 2" AC ON 6" LIMEROCK



Date:09/16/2013

## Work History Report

2 of 6

Pavement Database:FDOT

01/01/1991	IMPORTED	OVERLAY			True	SOIL: SP-MS
<b>Network:</b> BKV <b>Branch:</b> AP NE <b>(NE APRON)</b> <b>Section:</b> 4145 <b>Surface:</b> AC <b>L.C.D.:</b> 01/01/1991 <b>Use:</b> APRON <b>Rank P Length:</b> 600.00 Ft <b>Width:</b> 120.00 Ft <b>True Area:</b> 72,809.18 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SP-MS
01/01/1991	IMPORTED	BUILT		4.00	True	1991: 4" AC ON 8" LIMEROCK
<b>Network:</b> BKV <b>Branch:</b> AP NE <b>(NE APRON)</b> <b>Section:</b> 4147 <b>Surface:</b> AAC <b>L.C.D.:</b> 01/01/1989 <b>Use:</b> APRON <b>Rank P Length:</b> 70.00 Ft <b>Width:</b> 200.00 Ft <b>True Area:</b> 7,370.90 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1989	IMPORTED	BUILT			True	ESTIMATE 1989 AC OVERLAY ON AC
<b>Network:</b> BKV <b>Branch:</b> AP NE <b>(NE APRON)</b> <b>Section:</b> 4150 <b>Surface:</b> PCC <b>L.C.D.:</b> 01/01/1991 <b>Use:</b> APRON <b>Rank P Length:</b> 148.00 Ft <b>Width:</b> 200.00 Ft <b>True Area:</b> 28,017.31 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SP-MS
01/01/1991	IMPORTED	BUILT		15.00	True	1991: 15" PORTLAND CEMENT CONCRETE ON 10" LIMEROCK
<b>Network:</b> BKV <b>Branch:</b> AP S <b>(SOUTH APRON)</b> <b>Section:</b> 4205 <b>Surface:</b> AC <b>L.C.D.:</b> 01/01/1991 <b>Use:</b> APRON <b>Rank P Length:</b> 100.00 Ft <b>Width:</b> 35.00 Ft <b>True Area:</b> 3,398.47 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SM
01/01/1991	IMPORTED	BUILT		2.00	True	1991: 2" AC ON 6" LIMEROCK
<b>Network:</b> BKV <b>Branch:</b> AP S <b>(SOUTH APRON)</b> <b>Section:</b> 4210 <b>Surface:</b> AC <b>L.C.D.:</b> 12/25/1999 <b>Use:</b> APRON <b>Rank P Length:</b> 453.00 Ft <b>Width:</b> 112.00 Ft <b>True Area:</b> 52,540.81 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	INITIAL	Initial Construction	\$0	0.00	True	
<b>Network:</b> BKV <b>Branch:</b> AP S <b>(SOUTH APRON)</b> <b>Section:</b> 4215 <b>Surface:</b> AC <b>L.C.D.:</b> 12/25/1999 <b>Use:</b> APRON <b>Rank P Length:</b> 355.00 Ft <b>Width:</b> 65.00 Ft <b>True Area:</b> 32,595.35 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	INITIAL	Initial Construction	\$0	0.00	True	
<b>Network:</b> BKV <b>Branch:</b> AP S <b>(SOUTH APRON)</b> <b>Section:</b> 4220 <b>Surface:</b> AC <b>L.C.D.:</b> 12/25/1999 <b>Use:</b> APRON <b>Rank P Length:</b> 453.00 Ft <b>Width:</b> 65.00 Ft <b>True Area:</b> 28,845.35 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	INITIAL	Initial Construction	\$0	0.00	True	
<b>Network:</b> BKV <b>Branch:</b> AP S <b>(SOUTH APRON)</b> <b>Section:</b> 4225 <b>Surface:</b> AC <b>L.C.D.:</b> 01/01/2009 <b>Use:</b> APRON <b>Rank P Length:</b> 1,800.00 Ft <b>Width:</b> 65.00 Ft <b>True Area:</b> 114,556.42 SqF						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/2009	INITIAL	Initial Construction	\$0	0.00	True	

Date:09/16/2013

## Work History Report

3 of 6

Pavement Database:FDOT

Network: BKV Branch: RW 3-21 (RUNWAY 3-21) Section: 6205 Surface: PCC  
 L.C.D.: 01/01/1942 Use: RUNWAY Rank S Length: 10,000.00 Ft Width: 25.00 Ft True Area:250,750.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
03/01/2011	JS-LC	Joint Seal (Localized)	\$0	0.00	False	
01/01/1942	IMPORTED	BUILT		8.00	True	1942 8" PCC PAVEMENT
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML

Network: BKV Branch: RW 3-21 (RUNWAY 3-21) Section: 6210 Surface: PCC  
 L.C.D.: 01/01/1942 Use: RUNWAY Rank S Length: 5,000.00 Ft Width: 100.00 Ft True Area:501,500.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
03/01/2011	JS-LC	Joint Seal (Localized)	\$0	0.00	False	
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML

Network: BKV Branch: RW 9-27 (RUNWAY 9-27) Section: 6105 Surface: PCC  
 L.C.D.: 01/01/1942 Use: RUNWAY Rank P Length: 14,000.00 Ft Width: 25.00 Ft True Area:350,000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
03/01/2011	JS-LC	Joint Seal (Localized)	\$0	0.00	False	
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT

Network: BKV Branch: RW 9-27 (RUNWAY 9-27) Section: 6110 Surface: PCC  
 L.C.D.: 01/01/1942 Use: RUNWAY Rank P Length: 7,000.00 Ft Width: 100.00 Ft True Area:700,000.00 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
03/01/2011	JS-LC	Joint Seal (Localized)	\$0	0.00	False	
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML

Network: BKV Branch: TW A (TAXIWAY A) Section: 105 Surface: PCC  
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank P Length: 8,650.00 Ft Width: 75.00 Ft True Area:648,306.61 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML

Network: BKV Branch: TW A1 (TAXIWAY A1) Section: 110 Surface: PCC  
 L.C.D.: 01/01/1942 Use: TAXIWAY Rank P Length: 750.00 Ft Width: 75.00 Ft True Area: 56,894.07 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML

Network: BKV Branch: TW A1 (TAXIWAY A1) Section: 111 Surface: AAC  
 L.C.D.: 01/01/1991 Use: TAXIWAY Rank P Length: 445.00 Ft Width: 40.00 Ft True Area: 17,869.99 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SP & MS
01/01/1991	IMPORTED	OVERLAY		1.00	True	1991: 1" P-401 OVERLAY
01/01/1964	IMPORTED	BUILT		2.00	True	1964: 2" P-401 ON 6" P-211

Date:09/16/2013

# Work History Report

4 of 6

*Pavement Database:FDOT*

**Network:** BKV **Branch:** TW A1 **(TAXIWAY A1)** **Section:** 112 **Surface:** AC  
**L.C.D.:** 01/01/1964 **Use:** TAXIWAY **Rank P Length:** 455.00 Ft **Width:** 40.00 Ft **True Area:** 18,154.08 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1964	IMPORTED	BUILT		2.00	True	1964: 2" P-401 ON 6" P-211

**Network:** BKV **Branch:** TW A3 **(TAXIWAY A3)** **Section:** 120 **Surface:** PCC  
**L.C.D.:** 01/01/1942 **Use:** TAXIWAY **Rank P Length:** 413.00 Ft **Width:** 25.00 Ft **True Area:** 10,836.50 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML

**Network:** BKV **Branch:** TW A3 **(TAXIWAY A3)** **Section:** 125 **Surface:** AC  
**L.C.D.:** 01/01/1986 **Use:** TAXIWAY **Rank P Length:** 400.00 Ft **Width:** 53.00 Ft **True Area:** 26,322.35 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1986	IMPORTED	BUILT		4.00	True	1986: 4" P-401 ON 6" P-211
01/01/1986	IMPORTED	OVERLAY			True	SOIL: SP & ML

**Network:** BKV **Branch:** TW A5 **(TAXIWAY A5)** **Section:** 130 **Surface:** PCC  
**L.C.D.:** 01/01/1942 **Use:** TAXIWAY **Rank P Length:** 430.00 Ft **Width:** 75.00 Ft **True Area:** 33,046.02 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT

**Network:** BKV **Branch:** TW A6 **(TAXIWAY A6)** **Section:** 135 **Surface:** AC  
**L.C.D.:** 01/01/1986 **Use:** TAXIWAY **Rank P Length:** 418.00 Ft **Width:** 53.00 Ft **True Area:** 31,613.91 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1986	IMPORTED	OVERLAY			True	SOIL: SP & ML
01/01/1986	IMPORTED	BUILT		4.00	True	1986: 4" P-401 ON 6" P-211

**Network:** BKV **Branch:** TW A9 **(TAXIWAY A9)** **Section:** 140 **Surface:** PCC  
**L.C.D.:** 01/01/1942 **Use:** TAXIWAY **Rank P Length:** 440.00 Ft **Width:** 75.00 Ft **True Area:** 31,973.01 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT

**Network:** BKV **Branch:** TW B **(TAXIWAY B)** **Section:** 205 **Surface:** AC  
**L.C.D.:** 01/01/1990 **Use:** TAXIWAY **Rank P Length:** 1,590.00 Ft **Width:** 35.00 Ft **True Area:** 55,550.48 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1990	IMPORTED	OVERLAY			True	SOIL: SM
01/01/1990	IMPORTED	BUILT		2.00	True	1990: 2" AC ON 6" LIMEROCK

**Network:** BKV **Branch:** TW B **(TAXIWAY B)** **Section:** 210 **Surface:** AC  
**L.C.D.:** 01/01/1991 **Use:** TAXIWAY **Rank P Length:** 3,375.00 Ft **Width:** 35.00 Ft **True Area:** 118,422.52 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SM
01/01/1991	IMPORTED	BUILT		2.00	True	1991: 2" AC ON 6" LIMEROCK

Date:09/16/2013

**Work History Report**

5 of 6

*Pavement Database:FDOT*

**Network:** BKV      **Branch:** TW B1      **(TAXIWAY B1)**      **Section:** 145      **Surface:** AC  
**L.C.D.:** 01/01/1998   **Use:** TAXIWAY      **Rank P Length:** 850.00 Ft      **Width:** 76.00 Ft      **True Area:** 80,953.55 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1998	IMPORTED	BUILT			True	EST 1998: AC PAVEMENT

**Network:** BKV      **Branch:** TW B1      **(TAXIWAY B1)**      **Section:** 215      **Surface:** PCC  
**L.C.D.:** 01/01/1942   **Use:** TAXIWAY      **Rank P Length:** 810.00 Ft      **Width:** 75.00 Ft      **True Area:** 63,745.26 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1942	IMPORTED	BUILT		8.00	True	1942: 8" PCC PAVEMENT
01/01/1942	IMPORTED	OVERLAY			True	SOIL: SP & ML

**Network:** BKV      **Branch:** TW B1      **(TAXIWAY B1)**      **Section:** 216      **Surface:** AC  
**L.C.D.:** 01/01/1991   **Use:** TAXIWAY      **Rank P Length:** 885.00 Ft      **Width:** 50.00 Ft      **True Area:** 45,429.21 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SP / ML
01/01/1991	IMPORTED	BUILT		4.00	True	1991: 4" AC ON 14" LIMEROCK

**Network:** BKV      **Branch:** TW B2      **(TAXIWAY B2)**      **Section:** 220      **Surface:** AC  
**L.C.D.:** 01/01/1990   **Use:** TAXIWAY      **Rank P Length:** 150.00 Ft      **Width:** 35.00 Ft      **True Area:** 7,308.52 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1990	IMPORTED	OVERLAY			True	SOIL: SM
01/01/1990	IMPORTED	BUILT		2.00	True	1990: 2" AC ON 6" LIMEROCK

**Network:** BKV      **Branch:** TW B3      **(TAXIWAY B3)**      **Section:** 225      **Surface:** AC  
**L.C.D.:** 01/01/1991   **Use:** TAXIWAY      **Rank P Length:** 150.00 Ft      **Width:** 35.00 Ft      **True Area:** 7,308.52 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SM
01/01/1991	IMPORTED	BUILT		2.00	True	1991: 2" AC ON 6" LIMEROCK

**Network:** BKV      **Branch:** TW B4      **(TAXIWAY B4)**      **Section:** 230      **Surface:** AC  
**L.C.D.:** 01/01/1991   **Use:** TAXIWAY      **Rank P Length:** 150.00 Ft      **Width:** 35.00 Ft      **True Area:** 6,246.24 SqF

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
01/01/1991	IMPORTED	OVERLAY			True	SOIL: SM
01/01/1991	IMPORTED	BUILT		2.00	True	1991: 2" AC ON 6" LIMEROCK


**Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	33	3,617,767.33	4.81	3.35
Initial Construction	4	228,537.93	.00	.00
Joint Seal (Localized)	4	1,802,250.00	.00	.00
OVERLAY	32	3,552,898.32	1.00	

# APPENDIX B

---

- AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
- PAVEMENT CONDITION INDEX INVENTORY



NUMBER	DATE	REVISIONS
DESIGNED:	KHA	DRAWN: KHA
CHECKED:	KHA	DATE: 2013
PLOTTED:	November 15, 2013	2:57 PM, BY: Bepi, AT





Table B-1: Pavement Condition Index Inventory

Branch Name	Branch ID	Branch Use	Section ID	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	PCI	PCI Category	Total Samples Inspected	Total Samples
RUNWAY 3-21	RW 3-21	RUNWAY	6210	501,500	S	PCC	55	Poor	20	100
RUNWAY 3-21	RW 3-21	RUNWAY	6205	250,750	S	PCC	53	Poor	10	50
RUNWAY 9-27	RW 9-27	RUNWAY	6110	700,000	P	PCC	58	Fair	20	140
RUNWAY 9-27	RW 9-27	RUNWAY	6105	350,000	P	PCC	46	Poor	14	70
SOUTH APRON	AP S	APRON	4225	114,556	P	AC	100	Good	4	28
SOUTH APRON	AP S	APRON	4220	28,845	P	AC	67	Fair	1	7
SOUTH APRON	AP S	APRON	4215	32,595	P	AC	74	Satisfactory	1	7
SOUTH APRON	AP S	APRON	4210	52,541	P	AC	67	Fair	1	9
SOUTH APRON	AP S	APRON	4205	3,398	P	AC	64	Fair	1	1
NE APRON	AP NE	APRON	4150	28,017	P	PCC	57	Fair	1	5
NE APRON	AP NE	APRON	4147	7,371	P	AAC	55	Poor	1	2
NE APRON	AP NE	APRON	4145	72,809	P	AC	56	Fair	2	13
NE APRON	AP NE	APRON	4140	222,039	P	AC	72	Satisfactory	5	44
NE APRON	AP NE	APRON	4135	59,122	P	AC	63	Fair	2	12
NE APRON	AP NE	APRON	4130	6,146	P	PCC	36	Very Poor	1	1
NE APRON	AP NE	APRON	4125	23,740	P	AAC	63	Fair	1	5
NE APRON	AP NE	APRON	4120	53,058	P	AC	53	Poor	2	11
NE APRON	AP NE	APRON	4115	35,800	P	AC	52	Poor	2	6
NE APRON	AP NE	APRON	4110	14,592	P	AC	52	Poor	1	4
NE APRON	AP NE	APRON	4105	29,444	P	AC	48	Poor	1	7
TAXIWAY B4	TW B4	TAXIWAY	230	6,246	P	AC	62	Fair	1	2
TAXIWAY B3	TW B3	TAXIWAY	225	7,309	P	AC	59	Fair	1	2
TAXIWAY B2	TW B2	TAXIWAY	220	7,309	P	AC	38	Very Poor	1	2
TAXIWAY B1	TW B1	TAXIWAY	216	45,429	P	AC	58	Fair	2	9

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.





# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Branch Use	Section ID	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	PCI	PCI Category	Total Samples Inspected	Total Samples
TAXIWAY B1	TW B1	TAXIWAY	215	63,745	P	PCC	58	Fair	3	16
TAXIWAY B	TW B	TAXIWAY	210	118,423	P	AC	66	Fair	5	34
TAXIWAY B	TW B	TAXIWAY	205	55,550	P	AC	38	Very Poor	3	15
TAXIWAY B1	TW B1	TAXIWAY	145	80,954	P	AC	72	Satisfactory	3	18
TAXIWAY A9	TW A9	TAXIWAY	140	31,973	P	PCC	69	Fair	2	8
TAXIWAY A6	TW A6	TAXIWAY	135	31,614	P	AC	20	Serious	2	9
TAXIWAY A5	TW A5	TAXIWAY	130	33,046	P	PCC	59	Fair	2	8
TAXIWAY A3	TW A3	TAXIWAY	125	26,322	P	AC	20	Serious	1	5
TAXIWAY A3	TW A3	TAXIWAY	120	10,836	P	PCC	41	Poor	1	2
TAXIWAY A1	TW A1	TAXIWAY	112	18,154	P	AC	44	Poor	1	5
TAXIWAY A1	TW A1	TAXIWAY	111	17,870	P	AAC	77	Satisfactory	1	4
TAXIWAY A1	TW A1	TAXIWAY	110	56,894	P	PCC	53	Poor	3	15
TAXIWAY A	TW A	TAXIWAY	105	648,307	P	PCC	50	Poor	13	173

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

# APPENDIX C

---

- BRANCH CONDITION REPORT
- SECTION CONDITION REPORT

Date: 9 /16/2013

**Branch Condition Report**

1 of 2

*Pavement Database: FDOT NetworkID: BKV*

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	PCI Standard Deviation	Weighted Average PCI
AP NE (NE APRON)	11	4,850.50	133.82	552,138.02	APRON	55.18	8.81	62.22
AP S (SOUTH APRON)	5	3,161.00	68.40	231,936.40	APRON	74.40	13.22	84.24
RW 3-21 (RUNWAY 3-21)	2	15,000.00	62.50	752,250.00	RUNWAY	54.00	1.00	54.33
RW 9-27 (RUNWAY 9-27)	2	21,000.00	62.50	1,050,000.00	RUNWAY	52.00	6.00	54.00
TW A (TAXIWAY A)	1	8,650.00	75.00	648,306.61	TAXIWAY	50.00	0.00	50.00
TW A1 (TAXIWAY A1)	3	1,650.00	51.67	92,918.14	TAXIWAY	58.00	13.93	55.86
TW A3 (TAXIWAY A3)	2	813.00	39.00	37,158.85	TAXIWAY	30.50	10.50	26.12
TW A5 (TAXIWAY A5)	1	430.00	75.00	33,046.02	TAXIWAY	59.00	0.00	59.00
TW A6 (TAXIWAY A6)	1	418.00	53.00	31,613.91	TAXIWAY	20.00	0.00	20.00
TW A9 (TAXIWAY A9)	1	440.00	75.00	31,973.01	TAXIWAY	69.00	0.00	69.00
TW B (TAXIWAY B)	2	4,965.00	35.00	173,973.00	TAXIWAY	52.00	14.00	57.06
TW B1 (TAXIWAY B1)	3	2,545.00	67.00	190,128.02	TAXIWAY	62.67	6.60	63.96
TW B2 (TAXIWAY B2)	1	150.00	35.00	7,308.52	TAXIWAY	38.00	0.00	38.00
TW B3 (TAXIWAY B3)	1	150.00	35.00	7,308.52	TAXIWAY	59.00	0.00	59.00
TW B4 (TAXIWAY B4)	1	150.00	35.00	6,246.24	TAXIWAY	62.00	0.00	62.00

Date: 9 /16/2013

## Branch Condition Report

2 of 2

*Pavement Database: FDOT*

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	16	784,074.42	61.19	13.68	68.73
RUNWAY	4	1,802,250.00	53.00	4.42	54.14
TAXIWAY	17	1,259,980.84	52.00	16.11	52.82
<b>All</b>	37	3,846,305.26	56.08	14.91	56.68

<div> <div>Date: 9 /16/2013</div> <div>Section Condition Report</div> <div>1 of 3</div> </div> <div> <div>Pavement Database: FDOT</div> <div>NetworkID: BKV</div> </div>										
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP NE (NE APRON)	4105	01/01/1975	AC	APRON	P	0	29,443.85	06/10/2013	38	48.00
AP NE (NE APRON)	4110	01/01/1975	AC	APRON	P	0	14,591.81	06/10/2013	38	52.00
AP NE (NE APRON)	4115	01/01/1975	AC	APRON	P	0	35,799.62	06/10/2013	38	52.00
AP NE (NE APRON)	4120	01/01/1964	AC	APRON	P	0	53,057.62	06/10/2013	49	53.00
AP NE (NE APRON)	4125	01/01/1975	AAC	APRON	P	0	23,739.53	06/10/2013	38	63.00
AP NE (NE APRON)	4130	01/01/1942	PCC	APRON	P	0	6,146.47	06/10/2013	71	36.00
AP NE (NE APRON)	4135	01/01/1983	AC	APRON	P	0	59,122.43	06/10/2013	30	63.00
AP NE (NE APRON)	4140	01/01/1991	AC	APRON	P	0	222,039.30	06/10/2013	22	72.00
AP NE (NE APRON)	4145	01/01/1991	AC	APRON	P	0	72,809.18	06/10/2013	22	56.00
AP NE (NE APRON)	4147	01/01/1989	AAC	APRON	P	0	7,370.90	06/10/2013	24	55.00
AP NE (NE APRON)	4150	01/01/1991	PCC	APRON	P	0	28,017.31	06/10/2013	22	57.00
AP S (SOUTH APRON)	4205	01/01/1991	AC	APRON	P	0	3,398.47	06/10/2013	22	64.00
AP S (SOUTH APRON)	4210	12/25/1999	AC	APRON	P	0	52,540.81	06/10/2013	14	67.00
AP S (SOUTH APRON)	4215	12/25/1999	AC	APRON	P	0	32,595.35	06/10/2013	14	74.00
AP S (SOUTH APRON)	4220	12/25/1999	AC	APRON	P	0	28,845.35	06/10/2013	14	67.00
AP S (SOUTH APRON)	4225	01/01/2009	AC	APRON	P	0	114,556.42	06/10/2013	4	100.00
RW 3-21 (RUNWAY 3-21)	6205	01/01/1942	PCC	RUNWAY	S	0	250,750.00	06/10/2013	71	53.00
RW 3-21 (RUNWAY 3-21)	6210	01/01/1942	PCC	RUNWAY	S	0	501,500.00	06/10/2013	71	55.00
RW 9-27 (RUNWAY 9-27)	6105	01/01/1942	PCC	RUNWAY	P	0	350,000.00	06/10/2013	71	46.00
RW 9-27 (RUNWAY 9-27)	6110	01/01/1942	PCC	RUNWAY	P	0	700,000.00	06/10/2013	71	58.00
TW A (TAXIWAY A)	105	01/01/1942	PCC	TAXIWAY	P	0	648,306.61	06/10/2013	71	50.00
TW A1 (TAXIWAY A1)	110	01/01/1942	PCC	TAXIWAY	P	0	56,894.07	06/10/2013	71	53.00
TW A1 (TAXIWAY A1)	111	01/01/1991	AAC	TAXIWAY	P	0	17,869.99	06/10/2013	22	77.00
TW A1 (TAXIWAY A1)	112	01/01/1964	AC	TAXIWAY	P	0	18,154.08	06/10/2013	49	44.00
TW A3 (TAXIWAY A3)	120	01/01/1942	PCC	TAXIWAY	P	0	10,836.50	06/10/2013	71	41.00
TW A3 (TAXIWAY A3)	125	01/01/1986	AC	TAXIWAY	P	0	26,322.35	06/10/2013	27	20.00

Date: 9 /16/2013

## Section Condition Report

2 of 3

Pavement Database: FDOT NetworkID: BKV

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
TW A5 (TAXIWAY A5)	130	01/01/1942	PCC	TAXIWAY	P	0	33,046.02	06/10/2013	71	59.00
TW A6 (TAXIWAY A6)	135	01/01/1986	AC	TAXIWAY	P	0	31,613.91	06/10/2013	27	20.00
TW A9 (TAXIWAY A9)	140	01/01/1942	PCC	TAXIWAY	P	0	31,973.01	06/10/2013	71	69.00
TW B (TAXIWAY B)	205	01/01/1990	AC	TAXIWAY	P	0	55,550.48	06/10/2013	23	38.00
TW B (TAXIWAY B)	210	01/01/1991	AC	TAXIWAY	P	0	118,422.52	06/10/2013	22	66.00
TW B1 (TAXIWAY B1)	145	01/01/1998	AC	TAXIWAY	P	0	80,953.55	06/10/2013	15	72.00
TW B1 (TAXIWAY B1)	215	01/01/1942	PCC	TAXIWAY	P	0	63,745.26	06/10/2013	71	58.00
TW B1 (TAXIWAY B1)	216	01/01/1991	AC	TAXIWAY	P	0	45,429.21	06/10/2013	22	58.00
TW B2 (TAXIWAY B2)	220	01/01/1990	AC	TAXIWAY	P	0	7,308.52	06/10/2013	23	38.00
TW B3 (TAXIWAY B3)	225	01/01/1991	AC	TAXIWAY	P	0	7,308.52	06/10/2013	22	59.00
TW B4 (TAXIWAY B4)	230	01/01/1991	AC	TAXIWAY	P	0	6,246.24	06/10/2013	22	62.00

**Section Condition Report***Pavement Database: FDOT*

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
03-05	<b>4.00</b>	<b>114,556.42</b>	<b>1</b>	<b>100.00</b>	<b>0.00</b>	<b>100.00</b>
11-15	<b>14.25</b>	<b>194,935.06</b>	<b>4</b>	<b>70.00</b>	<b>3.56</b>	<b>70.25</b>
21-25	<b>22.33</b>	<b>591,770.64</b>	<b>12</b>	<b>58.50</b>	<b>11.62</b>	<b>63.06</b>
26-30	<b>28.00</b>	<b>117,058.69</b>	<b>3</b>	<b>34.33</b>	<b>24.83</b>	<b>41.72</b>
36-40	<b>38.00</b>	<b>103,574.81</b>	<b>4</b>	<b>53.75</b>	<b>6.45</b>	<b>53.38</b>
over 40	<b>67.62</b>	<b>2,724,409.64</b>	<b>13</b>	<b>51.92</b>	<b>8.67</b>	<b>53.27</b>
<b>All</b>	<b>39.03</b>	<b>3,846,305.26</b>	<b>37</b>	<b>56.08</b>	<b>15.11</b>	<b>56.68</b>

# APPENDIX D

---

- PAVEMENT PERFORMANCE PREDICTION
- PAVEMENT PERFORMANCE BY PAVEMENT USE





Table D-1: Pavement Performance Prediction

Branch ID	Section ID	Current PCI	Pavement Performance Model - PCI									
			2014	2015	2016	2017	2018	2019	2020	2021	2022	2023
RW 3-21	6210	55	54	53	52	52	51	50	50	49	49	49
RW 3-21	6205	53	52	52	51	50	50	49	49	49	49	48
RW 9-27	6110	58	57	56	55	53	52	52	51	50	50	49
RW 9-27	6105	46	46	46	46	46	46	46	46	46	46	46
AP S	4225	100	97	92	87	84	80	78	76	74	72	71
AP S	4220	67	67	66	65	65	64	63	63	62	61	60
AP S	4215	74	73	72	70	69	68	67	67	66	65	65
AP S	4210	67	67	66	65	65	64	63	63	62	61	60
AP S	4205	64	64	63	62	62	61	60	59	58	57	57
AP NE	4150	57	56	56	55	54	54	54	53	53	53	53
AP NE	4147	55	55	55	54	54	54	53	52	52	51	50
AP NE	4145	56	55	55	54	53	52	51	50	49	48	47
AP NE	4140	72	71	70	69	68	67	67	66	65	65	64
AP NE	4135	63	63	62	61	60	60	59	58	57	56	55
AP NE	4130	36	35	34	33	32	32	31	30	29	29	29
AP NE	4125	63	62	61	61	60	59	58	58	58	57	57
AP NE	4120	53	52	52	51	50	49	48	47	46	46	45
AP NE	4115	52	51	51	50	49	48	47	46	46	45	44
AP NE	4110	52	51	51	50	49	48	47	46	46	45	44
AP NE	4105	48	48	47	46	45	44	44	43	43	42	42
TW B4	230	62	62	61	61	60	60	59	58	57	56	56
TW B3	225	59	59	58	57	56	55	54	53	52	51	49
TW B2	220	38	38	37	36	36	36	35	35	35	35	35
TW B1	216	58	58	57	56	55	54	53	51	50	49	48
TW B1	215	58	57	56	55	53	52	52	51	50	50	49
TW B	210	66	66	65	65	64	64	64	64	64	63	63
TW B	205	38	38	37	36	36	36	35	35	35	35	35




Branch ID	Section ID	Current PCI	Pavement Performance Model - PCI									
			2014	2015	2016	2017	2018	2019	2020	2021	2022	2023
TW B1	145	72	71	70	69	68	67	66	66	65	65	64
TW A9	140	69	68	65	63	61	60	58	57	55	54	53
TW A6	135	20	20	20	20	20	20	20	20	20	20	20
TW A5	130	59	58	57	55	54	53	52	51	51	50	50
TW A3	125	20	20	20	20	20	20	20	20	20	20	20
TW A3	120	41	41	40	40	39	39	39	38	38	37	37
TW A1	112	44	43	42	41	40	39	39	38	37	37	36
TW A1	111	77	76	75	74	72	71	70	69	68	67	65
TW A1	110	53	52	52	51	50	50	49	49	49	49	48
TW A	105	50	50	49	49	49	49	48	48	48	48	48




Figure D-1: Pavement Performance by Pavement Use

(a) Runway




(b) Taxiway





(c) Apron



# APPENDIX E

---

## ● YEAR-1 PREVENTATIVE ACTIVITIES



Table E-1: Year-1 Preventative Activities

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
RUNWAY 3-21	RW 3-21	6210	CORNER BREAK	L	Patching - PCC Partial Depth	161.50	SqFt	\$19.10	\$ 3,083.86
RUNWAY 3-21	RW 3-21	6210	SCALING	M	Patching - PCC Partial Depth	512.60	SqFt	\$19.10	\$ 9,791.26
RUNWAY 3-21	RW 3-21	6210	SCALING	L	Patching - PCC Partial Depth	163,529.40	SqFt	\$19.10	\$ 3,123,411.01
RUNWAY 3-21	RW 3-21	6210	SHAT. SLAB	H	Slab Replacement - PCC	1,562.50	SqFt	\$45.00	\$ 70,312.50
RUNWAY 3-21	RW 3-21	6210	SHRINKAGE CR	N	Crack Sealing - PCC	3,002.00	Ft	\$4.25	\$ 12,758.39
RUNWAY 3-21	RW 3-21	6210	JOINT SPALL	M	Patching - PCC Partial Depth	64.60	SqFt	\$19.10	\$ 1,233.54
RUNWAY 3-21	RW 3-21	6210	JOINT SPALL	L	Patching - PCC Partial Depth	269.10	SqFt	\$19.10	\$ 5,139.77
RUNWAY 3-21	RW 3-21	6210	CORNER SPALL	L	Patching - PCC Partial Depth	67.30	SqFt	\$19.10	\$ 1,284.94
RUNWAY 3-21	RW 3-21	6210	CORNER SPALL	M	Patching - PCC Partial Depth	13.50	SqFt	\$19.10	\$ 256.99
RUNWAY 3-21	RW 3-21	6205	SMALL PATCH	M	Slab Replacement - PCC	1,562.50	SqFt	\$45.00	\$ 70,312.50
RUNWAY 3-21	RW 3-21	6205	SCALING	M	Patching - PCC Partial Depth	8,202.10	SqFt	\$19.10	\$ 156,660.11
RUNWAY 3-21	RW 3-21	6205	SCALING	L	Patching - PCC Partial Depth	73,818.90	SqFt	\$19.10	\$ 1,409,941.02
RUNWAY 3-21	RW 3-21	6205	SHRINKAGE CR	N	Crack Sealing - PCC	1,156.50	Ft	\$4.25	\$ 4,915.12
RUNWAY 3-21	RW 3-21	6205	JOINT SPALL	L	Patching - PCC Partial Depth	174.90	SqFt	\$19.10	\$ 3,340.85



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
RUNWAY 3-21	RW 3-21	6205	JOINT SPALL	H	Patching - PCC Partial Depth	40.40	SqFt	\$19.10	\$ 770.97
RUNWAY 3-21	RW 3-21	6205	JOINT SPALL	M	Patching - PCC Partial Depth	226.00	SqFt	\$19.10	\$ 4,317.40
RUNWAY 3-21	RW 3-21	6205	CORNER SPALL	L	Patching - PCC Partial Depth	94.20	SqFt	\$19.10	\$ 1,798.92
RUNWAY 3-21	RW 3-21	6205	CORNER SPALL	M	Patching - PCC Partial Depth	26.90	SqFt	\$19.10	\$ 513.98
RUNWAY 9-27	RW 9-27	6110	SCALING	L	Patching - PCC Partial Depth	190,903.90	SqFt	\$19.10	\$ 3,646,264.14
RUNWAY 9-27	RW 9-27	6110	SCALING	M	Patching - PCC Partial Depth	5,741.50	SqFt	\$19.10	\$ 109,662.08
RUNWAY 9-27	RW 9-27	6110	SHRINKAGE CR	N	Crack Sealing - PCC	4,306.10	Ft	\$4.25	\$ 18,300.98
RUNWAY 9-27	RW 9-27	6110	JOINT SPALL	L	Patching - PCC Partial Depth	244.90	SqFt	\$19.10	\$ 4,677.19
RUNWAY 9-27	RW 9-27	6110	JOINT SPALL	M	Patching - PCC Partial Depth	135.60	SqFt	\$19.10	\$ 2,590.44
RUNWAY 9-27	RW 9-27	6110	CORNER SPALL	L	Patching - PCC Partial Depth	113.00	SqFt	\$19.10	\$ 2,158.70
RUNWAY 9-27	RW 9-27	6105	SCALING	M	Patching - PCC Partial Depth	27,682.10	SqFt	\$19.10	\$ 528,727.88
RUNWAY 9-27	RW 9-27	6105	SCALING	L	Patching - PCC Partial Depth	77,407.30	SqFt	\$19.10	\$ 1,478,479.82
RUNWAY 9-27	RW 9-27	6105	SHRINKAGE CR	N	Crack Sealing - PCC	935.00	Ft	\$4.25	\$ 3,973.93
RUNWAY 9-27	RW 9-27	6105	JOINT SPALL	L	Patching - PCC Partial Depth	309.50	SqFt	\$19.10	\$ 5,910.73
RUNWAY 9-27	RW 9-27	6105	JOINT SPALL	M	Patching - PCC Partial Depth	419.80	SqFt	\$19.10	\$ 8,018.04



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
RUNWAY 9-27	RW 9-27	6105	JOINT SPALL	H	Patching - PCC Partial Depth	121.10	SqFt	\$19.10	\$ 2,312.90
RUNWAY 9-27	RW 9-27	6105	CORNER SPALL	L	Patching - PCC Partial Depth	242.20	SqFt	\$19.10	\$ 4,625.79
RUNWAY 9-27	RW 9-27	6105	CORNER SPALL	M	Patching - PCC Partial Depth	53.80	SqFt	\$19.10	\$ 1,027.95
SOUTH APRON	AP S	4220	L & T CR	L	Crack Sealing - AC	158.60	Ft	\$2.75	\$ 436.29
SOUTH APRON	AP S	4220	RAVELING	L	Surface Seal	21,634.00	SqFt	\$0.55	\$ 11,898.81
SOUTH APRON	AP S	4215	DEPRESSION	L	Patching - AC Full Depth	239.20	SqFt	\$5.00	\$ 1,196.24
SOUTH APRON	AP S	4215	RAVELING	L	Surface Seal	10,865.10	SqFt	\$0.55	\$ 5,975.86
SOUTH APRON	AP S	4210	DEPRESSION	L	Patching - AC Full Depth	411.90	SqFt	\$5.00	\$ 2,059.74
SOUTH APRON	AP S	4210	L & T CR	L	Crack Sealing - AC	445.80	Ft	\$2.75	\$ 1,225.95
SOUTH APRON	AP S	4210	RAVELING	L	Surface Seal	23,882.20	SqFt	\$0.55	\$ 13,135.31
SOUTH APRON	AP S	4205	DEPRESSION	L	Patching - AC Full Depth	31.10	SqFt	\$5.00	\$ 155.56
SOUTH APRON	AP S	4205	L & T CR	L	Crack Sealing - AC	98.60	Ft	\$2.75	\$ 271.03
SOUTH APRON	AP S	4205	RAVELING	L	Surface Seal	2,548.90	SqFt	\$0.55	\$ 1,401.88
NE APRON	AP NE	4150	SHAT. SLAB	L	Slab Replacement - PCC	3,593.80	SqFt	\$45.00	\$ 161,718.76
NE APRON	AP NE	4150	SHRINKAGE CR	N	Crack Sealing - PCC	56.60	Ft	\$4.25	\$ 240.53





# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
NE APRON	AP NE	4150	JOINT SPALL	L	Patching - PCC Partial Depth	15.50	SqFt	\$19.10	\$ 295.54
NE APRON	AP NE	4150	JOINT SPALL	M	Patching - PCC Partial Depth	37.10	SqFt	\$19.10	\$ 709.29
NE APRON	AP NE	4147	ALLIGATOR CR	L	Patching - AC Full Depth	138.00	SqFt	\$5.00	\$ 689.76
NE APRON	AP NE	4147	BLOCK CR	L	Surface Seal	7,276.10	SqFt	\$0.55	\$ 4,001.91
NE APRON	AP NE	4147	DEPRESSION	L	Patching - AC Full Depth	75.00	SqFt	\$5.00	\$ 374.96
NE APRON	AP NE	4145	L & T CR	M	Crack Sealing - AC	128.30	Ft	\$2.75	\$ 352.83
NE APRON	AP NE	4145	L & T CR	L	Crack Sealing - AC	4,313.40	Ft	\$2.75	\$ 11,861.95
NE APRON	AP NE	4145	OIL SPILLAGE	N	Surface Seal	2,239.20	SqFt	\$0.55	\$ 1,231.58
NE APRON	AP NE	4145	RAVELING	L	Surface Seal	48,877.50	SqFt	\$0.55	\$ 26,882.86
NE APRON	AP NE	4140	L & T CR	L	Crack Sealing - AC	4,822.70	Ft	\$2.75	\$ 13,262.39
NE APRON	AP NE	4140	RAVELING	L	Surface Seal	9,769.70	SqFt	\$0.55	\$ 5,373.40
NE APRON	AP NE	4135	BLOCK CR	L	Surface Seal	23,649.00	SqFt	\$0.55	\$ 13,007.04
NE APRON	AP NE	4135	DEPRESSION	L	Patching - AC Full Depth	871.50	SqFt	\$5.00	\$ 4,357.45
NE APRON	AP NE	4135	L & T CR	L	Crack Sealing - AC	999.20	Ft	\$2.75	\$ 2,747.71
NE APRON	AP NE	4135	RAVELING	L	Surface Seal	8,868.40	SqFt	\$0.55	\$ 4,877.64



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
NE APRON	AP NE	4130	CORNER BREAK	L	Patching - PCC Partial Depth	96.90	SqFt	\$19.10	\$ 1,850.32
NE APRON	AP NE	4130	SHAT. SLAB	L	Slab Replacement - PCC	1,700.00	SqFt	\$45.00	\$ 76,500.02
NE APRON	AP NE	4130	JOINT SPALL	L	Patching - PCC Partial Depth	2.70	SqFt	\$19.10	\$ 51.40
NE APRON	AP NE	4125	BLOCK CR	L	Surface Seal	16,427.80	SqFt	\$0.55	\$ 9,035.34
NE APRON	AP NE	4125	L & T CR	L	Crack Sealing - AC	1,395.90	Ft	\$2.75	\$ 3,838.68
NE APRON	AP NE	4120	BLOCK CR	L	Surface Seal	27,696.10	SqFt	\$0.55	\$ 15,232.97
NE APRON	AP NE	4120	L & T CR	L	Crack Sealing - AC	2,010.90	Ft	\$2.75	\$ 5,529.92
NE APRON	AP NE	4120	RAVELING	L	Surface Seal	15,917.30	SqFt	\$0.55	\$ 8,754.58
NE APRON	AP NE	4120	RAVELING	M	Surface Seal	10,611.50	SqFt	\$0.55	\$ 5,836.39
NE APRON	AP NE	4115	ALLIGATOR CR	L	Patching - AC Full Depth	156.40	SqFt	\$5.00	\$ 781.98
NE APRON	AP NE	4115	BLOCK CR	L	Surface Seal	24,233.60	SqFt	\$0.55	\$ 13,328.58
NE APRON	AP NE	4115	DEPRESSION	L	Patching - AC Full Depth	111.90	SqFt	\$5.00	\$ 559.63
NE APRON	AP NE	4115	L & T CR	L	Crack Sealing - AC	1,636.00	Ft	\$2.75	\$ 4,498.92
NE APRON	AP NE	4115	RAVELING	L	Surface Seal	12,239.20	SqFt	\$0.55	\$ 6,731.61
NE APRON	AP NE	4110	BLOCK CR	L	Surface Seal	4,169.10	SqFt	\$0.55	\$ 2,293.02



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
NE APRON	AP NE	4110	L & T CR	L	Crack Sealing - AC	1,391.40	Ft	\$2.75	\$ 3,826.44
NE APRON	AP NE	4110	RAVELING	L	Surface Seal	14,591.80	SqFt	\$0.55	\$ 8,025.56
NE APRON	AP NE	4105	BLOCK CR	L	Surface Seal	15,703.40	SqFt	\$0.55	\$ 8,636.93
NE APRON	AP NE	4105	L & T CR	L	Crack Sealing - AC	1,819.00	Ft	\$2.75	\$ 5,002.18
NE APRON	AP NE	4105	RAVELING	H	Patching - AC Partial Depth	65.40	SqFt	\$3.00	\$ 196.29
NE APRON	AP NE	4105	RAVELING	L	Surface Seal	29,378.40	SqFt	\$0.55	\$ 16,158.27
TAXIWAY B4	TW B4	230	L & T CR	L	Crack Sealing - AC	454.10	Ft	\$2.75	\$ 1,248.67
TAXIWAY B4	TW B4	230	L & T CR	M	Crack Sealing - AC	131.60	Ft	\$2.75	\$ 362.01
TAXIWAY B4	TW B4	230	RAVELING	L	Surface Seal	3,804.20	SqFt	\$0.55	\$ 2,092.34
TAXIWAY B3	TW B3	225	L & T CR	M	Crack Sealing - AC	113.70	Ft	\$2.75	\$ 312.64
TAXIWAY B3	TW B3	225	L & T CR	L	Crack Sealing - AC	422.30	Ft	\$2.75	\$ 1,161.24
TAXIWAY B3	TW B3	225	RAVELING	L	Surface Seal	7,308.50	SqFt	\$0.55	\$ 4,019.72
TAXIWAY B2	TW B2	220	L & T CR	L	Crack Sealing - AC	617.60	Ft	\$2.75	\$ 1,698.32
TAXIWAY B2	TW B2	220	RAVELING	M	Surface Seal	7,308.50	SqFt	\$0.55	\$ 4,019.72
TAXIWAY B1	TW B1	216	L & T CR	L	Crack Sealing - AC	1,962.50	Ft	\$2.75	\$ 5,396.98



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
TAXIWAY B1	TW B1	216	RAVELING	L	Surface Seal	29,529.00	SqFt	\$0.55	\$ 16,241.08
TAXIWAY B1	TW B1	215	SCALING	L	Patching - PCC Partial Depth	17,464.50	SqFt	\$19.10	\$ 333,571.41
TAXIWAY B1	TW B1	215	SCALING	M	Patching - PCC Partial Depth	970.20	SqFt	\$19.10	\$ 18,531.75
TAXIWAY B1	TW B1	215	SHRINKAGE CR	N	Crack Sealing - PCC	186.30	Ft	\$4.25	\$ 791.72
TAXIWAY B1	TW B1	215	JOINT SPALL	L	Patching - PCC Partial Depth	25.50	SqFt	\$19.10	\$ 486.40
TAXIWAY B1	TW B1	215	CORNER SPALL	L	Patching - PCC Partial Depth	12.70	SqFt	\$19.10	\$ 243.20
TAXIWAY B	TW B	210	L & T CR	M	Crack Sealing - AC	1,421.10	Ft	\$2.75	\$ 3,907.94
TAXIWAY B	TW B	210	L & T CR	L	Crack Sealing - AC	7,403.10	Ft	\$2.75	\$ 20,358.50
TAXIWAY B	TW B	210	RAVELING	L	Surface Seal	71,053.50	SqFt	\$0.55	\$ 39,079.76
TAXIWAY B	TW B	205	L & T CR	M	Crack Sealing - AC	137.00	Ft	\$2.75	\$ 376.82
TAXIWAY B	TW B	205	L & T CR	L	Crack Sealing - AC	4,860.10	Ft	\$2.75	\$ 13,365.20
TAXIWAY B	TW B	205	RAVELING	L	Surface Seal	12,846.00	SqFt	\$0.55	\$ 7,065.37
TAXIWAY B	TW B	205	RAVELING	M	Surface Seal	30,830.50	SqFt	\$0.55	\$ 16,956.89
TAXIWAY B	TW B	205	RAVELING	H	Patching - AC Partial Depth	1,284.60	SqFt	\$3.00	\$ 3,853.80
TAXIWAY B1	TW B1	145	L & T CR	M	Crack Sealing - AC	190.00	Ft	\$2.75	\$ 522.55



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
TAXIWAY B1	TW B1	145	L & T CR	L	Crack Sealing - AC	3,863.70	Ft	\$2.75	\$ 10,625.10
TAXIWAY B1	TW B1	145	RAVELING	L	Surface Seal	5,700.50	SqFt	\$0.55	\$ 3,135.31
TAXIWAY A9	TW A9	140	SCALING	L	Patching - PCC Partial Depth	10,415.00	SqFt	\$19.10	\$ 198,925.71
TAXIWAY A9	TW A9	140	SCALING	M	Patching - PCC Partial Depth	452.80	SqFt	\$19.10	\$ 8,648.94
TAXIWAY A9	TW A9	140	SHRINKAGE CR	N	Crack Sealing - PCC	130.40	Ft	\$4.25	\$ 554.26
TAXIWAY A9	TW A9	140	JOINT SPALL	L	Patching - PCC Partial Depth	11.90	SqFt	\$19.10	\$ 227.01
TAXIWAY A6	TW A6	135	BLOCK CR	H	Patching - AC Full Depth	94.70	SqFt	\$5.00	\$ 473.74
TAXIWAY A6	TW A6	135	L & T CR	M	Crack Sealing - AC	710.60	Ft	\$2.75	\$ 1,954.18
TAXIWAY A6	TW A6	135	L & T CR	L	Crack Sealing - AC	2,895.70	Ft	\$2.75	\$ 7,963.29
TAXIWAY A6	TW A6	135	RAVELING	M	Surface Seal	23,687.10	SqFt	\$0.55	\$ 13,028.01
TAXIWAY A6	TW A6	135	RAVELING	H	Patching - AC Partial Depth	2,931.30	SqFt	\$3.00	\$ 8,793.82
TAXIWAY A5	TW A5	130	SCALING	L	Patching - PCC Partial Depth	10,662.70	SqFt	\$19.10	\$ 203,658.15
TAXIWAY A5	TW A5	130	SHRINKAGE CR	N	Crack Sealing - PCC	149.30	Ft	\$4.25	\$ 634.43
TAXIWAY A5	TW A5	130	JOINT SPALL	L	Patching - PCC Partial Depth	11.70	SqFt	\$19.10	\$ 222.72
TAXIWAY A3	TW A3	125	L & T CR	M	Crack Sealing - AC	774.30	Ft	\$2.75	\$ 2,129.43



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
TAXIWAY A3	TW A3	125	L & T CR	L	Crack Sealing - AC	1,997.80	Ft	\$2.75	\$ 5,493.93
TAXIWAY A3	TW A3	125	RAVELING	M	Surface Seal	22,713.90	SqFt	\$0.55	\$ 12,492.77
TAXIWAY A3	TW A3	125	RAVELING	H	Patching - AC Partial Depth	3,097.40	SqFt	\$3.00	\$ 9,292.05
TAXIWAY A3	TW A3	120	SCALING	L	Patching - PCC Partial Depth	3,383.40	SqFt	\$19.10	\$ 64,622.30
TAXIWAY A3	TW A3	120	SHRINKAGE CR	N	Crack Sealing - PCC	56.80	Ft	\$4.25	\$ 241.57
TAXIWAY A3	TW A3	120	JOINT SPALL	L	Patching - PCC Partial Depth	4.40	SqFt	\$19.10	\$ 84.81
TAXIWAY A1	TW A1	112	DEPRESSION	L	Patching - AC Full Depth	197.70	SqFt	\$5.00	\$ 988.69
TAXIWAY A1	TW A1	112	L & T CR	L	Crack Sealing - AC	1,851.70	Ft	\$2.75	\$ 5,092.21
TAXIWAY A1	TW A1	112	RAVELING	L	Surface Seal	13,615.60	SqFt	\$0.55	\$ 7,488.62
TAXIWAY A1	TW A1	112	RAVELING	M	Surface Seal	4,538.50	SqFt	\$0.55	\$ 2,496.21
TAXIWAY A1	TW A1	111	L & T CR	L	Crack Sealing - AC	750.50	Ft	\$2.75	\$ 2,063.98
TAXIWAY A1	TW A1	111	RAVELING	L	Surface Seal	1,787.00	SqFt	\$0.55	\$ 982.86
TAXIWAY A1	TW A1	110	CORNER BREAK	L	Patching - PCC Partial Depth	158.80	SqFt	\$19.10	\$ 3,033.85
TAXIWAY A1	TW A1	110	SCALING	M	Patching - PCC Partial Depth	3,530.20	SqFt	\$19.10	\$ 67,427.36
TAXIWAY A1	TW A1	110	SCALING	L	Patching - PCC Partial Depth	11,095.00	SqFt	\$19.10	\$ 211,914.56



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
TAXIWAY A1	TW A1	110	SHRINKAGE CR	N	Crack Sealing - PCC	193.70	Ft	\$4.25	\$ 823.05
TAXIWAY A1	TW A1	110	JOINT SPALL	L	Patching - PCC Partial Depth	92.70	SqFt	\$19.10	\$ 1,769.75
TAXIWAY A1	TW A1	110	CORNER SPALL	L	Patching - PCC Partial Depth	92.70	SqFt	\$19.10	\$1,769.75
TAXIWAY A	TW A	105	CORNER BREAK	L	Patching - PCC Partial Depth	424.30	SqFt	\$19.10	\$ 8,103.92
TAXIWAY A	TW A	105	SMALL PATCH	H	Slab Replacement - PCC	8,212.00	SqFt	\$45.00	\$ 369,541.16
TAXIWAY A	TW A	105	SMALL PATCH	M	Slab Replacement - PCC	28,742.10	SqFt	\$45.00	\$ 1,293,394.07
TAXIWAY A	TW A	105	SCALING	M	Patching - PCC Partial Depth	75,438.60	SqFt	\$19.10	\$ 1,440,876.44
TAXIWAY A	TW A	105	SCALING	L	Patching - PCC Partial Depth	117,199.20	SqFt	\$19.10	\$ 2,238,504.46
TAXIWAY A	TW A	105	FAULTING	L	Patching - PCC Partial Depth	1,077.70	SqFt	\$19.10	\$ 20,583.95
TAXIWAY A	TW A	105	SHRINKAGE CR	N	Crack Sealing - PCC	3,362.40	Ft	\$4.25	\$ 14,290.25
TAXIWAY A	TW A	105	JOINT SPALL	M	Patching - PCC Partial Depth	254.60	SqFt	\$19.10	\$ 4,862.35
TAXIWAY A	TW A	105	JOINT SPALL	H	Patching - PCC Partial Depth	106.10	SqFt	\$19.10	\$ 2,025.98
TAXIWAY A	TW A	105	JOINT SPALL	L	Patching - PCC Partial Depth	106.10	SqFt	\$19.10	\$ 2,025.98
TAXIWAY A	TW A	105	CORNER SPALL	M	Patching - PCC Partial Depth	35.40	SqFt	\$19.10	\$ 675.33



# Pavement Evaluation Report - Brooksville - Tampa Bay Regional Airport

[illegible]



# APPENDIX F

---

- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION  
EXHIBIT

- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION  
TABLE






Table F-1: Airfield Pavement 10-Year Major Rehabilitation Table

Year	Branch Name	Section ID	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2014	AP NE	4135	\$ 591,224.27	63	Mill and Overlay	100
2014	AP NE	4145	\$ 728,091.77	55	Mill and Overlay	100
2014	AP NE	4147	\$ 73,709.00	55	Mill and Overlay	100
2014	AP NE	4150	\$ 280,173.09	56	PCC Restoration	100
2014	AP NE	4125	\$ 237,395.29	62	Mill and Overlay	100
2014	AP NE	4110	\$ 145,918.09	51	Mill and Overlay	100
2014	AP NE	4130	\$ 92,197.07	35	Reconstruction	100
2014	AP NE	4115	\$ 357,996.18	51	Mill and Overlay	100
2014	AP NE	4105	\$ 330,801.57	48	Mill and Overlay	100
2014	AP NE	4120	\$ 530,576.18	52	Mill and Overlay	100
2014	AP S	4205	\$ 33,984.70	64	Mill and Overlay	100
2014	RW 3-21	6210	\$ 5,014,999.76	54	PCC Restoration	100
2014	RW 3-21	6205	\$ 2,507,499.88	52	PCC Restoration	100
2014	RW 9-27	6105	\$ 4,205,250.52	46	PCC Restoration	100
2014	RW 9-27	6110	\$ 6,999,999.67	57	PCC Restoration	100
2014	TW A3	125	\$ 394,835.34	20	Reconstruction	100
2014	TW A	105	\$ 6,570,585.63	50	PCC Restoration	100
2014	TW A6	135	\$ 474,208.76	20	Reconstruction	100
2014	TW B	205	\$ 833,257.40	38	Reconstruction	100
2014	TW A1	110	\$ 568,940.67	52	PCC Restoration	100
2014	TW A1	112	\$ 241,721.64	43	Mill and Overlay	100
2014	TW A3	120	\$ 158,483.82	41	PCC Restoration	100
2014	TW A5	130	\$ 330,460.18	58	PCC Restoration	100
2014	TW B1	215	\$ 637,452.57	57	PCC Restoration	100
2014	TW B1	216	\$ 454,292.08	58	Mill and Overlay	100
2014	TW B2	220	\$ 109,627.83	38	Reconstruction	100
2014	TW B3	225	\$ 73,085.20	59	Mill and Overlay	100
2014	TW B4	230	\$ 62,462.40	62	Mill and Overlay	100
2016	TW A9	140	\$ 339,201.65	64	PCC Restoration	100
2016	TW B	210	\$ 1,256,344.46	65	Mill and Overlay	100
2017	AP S	4210	\$ 574,127.59	65	Mill and Overlay	100
2017	AP S	4220	\$ 315,200.91	65	Mill and Overlay	100
2023	TW B1	145	\$ 1,056,260.16	65	Mill and Overlay	100
2023	AP NE	4140	\$ 2,897,109.11	65	Mill and Overlay	100
Total =			\$39,477,474.44			

# APPENDIX G

---

## ● PHOTOGRAPHS





Runway 9-27, Section 6110, Sample Unit 300 – Low Severity (66) Small Patching, Low Severity (63) Longitudinal, Transverse and Diagonal Cracking



Runway 9-27, Section 6105, Sample Unit 104 – Medium Severity (70) Scaling, Map Cracking, Crazing





Runway 9-27, Section 6105, Sample Unit 168 –Medium Severity (70) Scaling, Map Cracking, Crazing, Low Severity (66) Small Patching, Low Severity (75) Corner Spalling



Taxiway Alpha, Section 105, Sample Unit 254 –Medium Severity (70) Scaling, Map Cracking, Crazing, Low Severity (66) Small Patching, Low Severity (74) Joint Spalling





Taxiway A9, Section 140, Sample Unit 902 – Low and Medium Severity (70) Scaling, Map Cracking, Crazing, Low Severity (66) Small Patching, Low Severity (63) Longitudinal, Transverse and Diagonal Cracking



Taxiway A6, Section 135, Sample Unit 606 –Low and Medium Severity (48) Longitudinal and Transverse Cracking, Medium and High Severity (52) Raveling





Taxiway A6, Section 125, Sample Unit 301 –Low and Medium Severity (48) Longitudinal and Transverse Cracking, Medium and High Severity (52) Raveling



Runway 3-21, Section 6205, Sample Unit 592 –Low Severity (70) Scaling, Map Cracking, Crazing, Low Severity (66) Small Patching, Low Severity (74) Joint Spalling





Runway 3-21, Section 6205, Sample Unit 164 – Low Severity (66) Small Patching, Medium Severity (63) Longitudinal, Transverse and Diagonal Cracking, (73) Shrinkage Cracking



Runway 3-21, Section 6210, Sample Unit 337 – Low Severity (63) Longitudinal, Transverse and Diagonal Cracking, Medium Severity (74) Joint Spalling





Runway 3-21, Section 6210, Sample Unit 313 – High Severity (72) Shattered Slab



Taxiway Bravo, Section 205, Sample Unit 148 – Low and Medium Severity (48) Longitudinal and Transverse Cracking, Medium and High Severity (52) Raveling





Apron North East, Section 4105, Sample Unit 852 – Low Severity (43) Block Cracking, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering, Low and High Severity (52) Raveling



Apron North East, Section 4130, Sample Unit 100 – Low Severity (63) Longitudinal, Transverse and Diagonal Cracking





Apron North East, Section 4147, Sample Unit 155 – Low Severity (45) Depression, Low Severity (43) Block Cracking



Taxiway A1, Section 112, Sample Unit 119 – Low Severity (45) Depression, Low Severity (57) Weathering, Low and Medium Severity (52) Raveling, Low Severity (48) Longitudinal and Transverse Cracking

# APPENDIX H

---

- DISTRESS DATA – RE-INSPECTION REPORT

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4105 of 11 From: - To: - Last Const.: 01/01/1975

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 29,443.85SqFt Length: 800.00Ft Width: 42.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 7 Surveyed: 1

Conditions: PCI : 48

Inspection Comments:

Sample Number: 852 Type: R Area: 4,500.00SqFt PCI = 48

Sample Comments:

43 BLOCK CRACKING L 2,400.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 278.00 Ft Comments:

57 WEATHERING L 4,490.00 SqFt Comments:

52 RAVELING H 10.00 SqFt Comments:

52 RAVELING L 4,490.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4110 of 11 From: - To: - Last Const.: 01/01/1975

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 14,591.81SqFt Length: 390.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 4 Surveyed: 1

Conditions: PCI : 52

Inspection Comments:

Sample Number: 650 Type: R Area: 2,800.00SqFt PCI = 52

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	267.00 Ft	Comments:
57	WEATHERING	L	2,800.00 SqFt	Comments:
52	RAVELING	L	2,800.00 SqFt	Comments:
43	BLOCK CRACKING	L	800.00 SqFt	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4115 of 11 From: - To: - Last Const.: 01/01/1975

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 35,799.62SqFt Length: 500.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 6 Surveyed: 2

Conditions: PCI : 52

Inspection Comments:

Sample Number: 551 Type: R Area: 3,000.00SqFt PCI = 49

Sample Comments:

43 BLOCK CRACKING L 740.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 288.00 Ft Comments:

57 WEATHERING L 3,000.00 SqFt Comments:

52 RAVELING L 3,000.00 SqFt Comments:

41 ALLIGATOR CRACKING L 27.00 SqFt Comments:

Sample Number: 554 Type: R Area: 5,775.00SqFt PCI = 54

Sample Comments:

43 BLOCK CRACKING L 5,200.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 113.00 Ft Comments:

57 WEATHERING L 5,775.00 SqFt Comments:

45 DEPRESSION L 18.00 SqFt Comments:



# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4120 of 11 From: - To: - Last Const.: 01/01/1964  
Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P  
Area: 53,057.62SqFt Length: 422.50Ft Width: 200.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 11 Surveyed: 2

Conditions: PCI : 53

Inspection Comments:

Sample Number: 354 Type: R Area: 5,000.00SqFt PCI = 64

Sample Comments:

43 BLOCK CRACKING L 5,000.00 SqFt Comments:

Sample Number: 402 Type: R Area: 5,000.00SqFt PCI = 42

Sample Comments:

43 BLOCK CRACKING L 220.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 379.00 Ft Comments:

57 WEATHERING L 3,000.00 SqFt Comments:

52 RAVELING L 3,000.00 SqFt Comments:

52 RAVELING M 2,000.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4125 of 11 From: - To: - Last Const.: 01/01/1975

Surface: AAC Family: FDOT-SAPMP-GA-AP-AAC Zone: Category: Rank: P

Area: 23,739.53SqFt Length: 260.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 5 Surveyed: 1

Conditions: PCI : 63

Inspection Comments:

Sample Number: 204 Type: R Area: 5,000.00SqFt PCI = 63

Sample Comments:

43 BLOCK CRACKING L 3,460.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 294.00 Ft Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4130 of 11 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-AP-PCC Zone: Category: Rank: P  
Area: 6,146.47SqFt Length: 25.50Ft Width: 200.00Ft  
Slabs: 12 Slab Width: 20.62Ft Slab Length: 20.62Ft Joint Length: 269.27Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 1 Surveyed: 1

Conditions: PCI : 36

Inspection Comments:

Sample Number: 100 Type: R Area: 12.00Slabs PCI = 36

Sample Comments:

62 CORNER BREAK	L	3.00 Slabs	Comments:
63 LINEAR CRACKING	L	7.00 Slabs	Comments:
63 LINEAR CRACKING	M	1.00 Slabs	Comments:
72 SHATTERED SLAB	L	4.00 Slabs	Comments:
74 JOINT SPALLING	L	1.00 Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4135 of 11 From: - To: - Last Const.: 01/01/1983  
Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P  
Area: 59,122.43SqFt Length: 612.00Ft Width: 95.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 12 Surveyed: 2

Conditions: PCI : 63

Inspection Comments:

Sample Number: 250 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	72.00 Ft	Comments:
57	WEATHERING	L	5,000.00 SqFt	Comments:
52	RAVELING	L	1,500.00 SqFt	Comments:

Sample Number: 304 Type: R Area: 5,000.00SqFt PCI = 52

Sample Comments:

45	DEPRESSION	L	128.00 SqFt	Comments:
43	BLOCK CRACKING	L	4,000.00 SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	97.00 Ft	Comments:
57	WEATHERING	L	5,000.00 SqFt	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4140 of 11 From: - To: - Last Const.: 01/01/1991  
Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P  
Area: 222,039.30SqFt Length: 1,022.50Ft Width: 200.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 44 Surveyed: 5

Conditions: PCI: 72

Inspection Comments:

Sample Number: 60 Type: R Area: 5,000.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	80.00 Ft	Comments:
57 WEATHERING	L	5,000.00 SqFt	Comments:
52 RAVELING	L	300.00 SqFt	Comments:

Sample Number: 207 Type: R Area: 5,000.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	86.00 Ft	Comments:
57 WEATHERING	L	4,967.00 SqFt	Comments:
50 PATCHING	L	25.00 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	16.00 Ft	Comments:
50 PATCHING	L	8.00 SqFt	Comments:
52 RAVELING	L	400.00 SqFt	Comments:
56 SWELLING	L	24.00 SqFt	Comments:

Sample Number: 209 Type: R Area: 5,000.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	111.00 Ft	Comments:
56 SWELLING	L	230.00 SqFt	Comments:
57 WEATHERING	L	5,000.00 SqFt	Comments:
52 RAVELING	L	400.00 SqFt	Comments:

Sample Number: 305 Type: R Area: 5,000.00SqFt PCI = 71

Sample Comments:

56 SWELLING	L	500.00 SqFt	Comments:
57 WEATHERING	L	5,000.00 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	194.00 Ft	Comments:
56 SWELLING	L	116.00 SqFt	Comments:

Sample Number: 411 Type: R Area: 5,000.00SqFt PCI = 53

Sample Comments:

57 WEATHERING	L	5,000.00 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	56.00 Ft	Comments:
56 SWELLING	L	2,700.00 SqFt	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4145 of 11 From: - To: - Last Const.: 01/01/1991  
Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P  
Area: 72,809.18SqFt Length: 600.00Ft Width: 120.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 13 Surveyed: 2

Conditions: PCI : 56

Inspection Comments:

Sample Number: 303 Type: R Area: 5,000.00SqFt PCI = 63

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	287.00 Ft	Comments:
57	WEATHERING	L	5,000.00 SqFt	Comments:
52	RAVELING	L	3,000.00 SqFt	Comments:
56	SWELLING	L	122.00 SqFt	Comments:

Sample Number: 504 Type: R Area: 6,917.00SqFt PCI = 51

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	419.00 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	21.00 Ft	Comments:
56	SWELLING	L	1,350.00 SqFt	Comments:
57	WEATHERING	L	6,917.00 SqFt	Comments:
52	RAVELING	L	5,000.00 SqFt	Comments:
49	OIL SPILLAGE	N	336.00 SqFt	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4147 of 11 From: - To: - Last Const.: 01/01/1989

Surface: AAC Family: FDOT-SAPMP-GA-AP-AAC Zone: Category: Rank: P

Area: 7,370.90SqFt Length: 70.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 2 Surveyed: 1

Conditions: PCI : 55

Inspection Comments:

Sample Number: 155 Type: R Area: 3,500.00SqFt PCI = 55

Sample Comments:

45 DEPRESSION L 21.00 SqFt Comments:

41 ALLIGATOR CRACKING L 45.00 SqFt Comments:

43 BLOCK CRACKING L 3,455.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP NE Name: NE APRON Use: APRON Area: 552,138.02SqFt

Section: 4150 of 11 From: - To: - Last Const.: 01/01/1991  
Surface: PCC Family: FDOT-SAPMP-GA-AP-PCC Zone: Category: Rank: P  
Area: 28,017.31SqFt Length: 148.00Ft Width: 200.00Ft  
Slabs: 46 Slab Width: 25.00Ft Slab Length: 25.00Ft Joint Length: 2,020.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 5 Surveyed: 1

Conditions: PCI : 57

Inspection Comments:

Sample Number: 100 Type: R Area: 8.00Slabs PCI = 57

Sample Comments:

63	LINEAR CRACKING	L	3.00	Slabs	Comments:
72	SHATTERED SLAB	L	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:



# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP S Name: SOUTH APRON Use: APRON Area: 231,936.40SqFt

Section: 4205 of 5 From: - To: - Last Const.: 01/01/1991

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 3,398.47SqFt Length: 100.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 1 Surveyed: 1

Conditions: PCI : 64

Inspection Comments:

Sample Number: 100 Type: R Area: 4,000.00SqFt PCI = 64

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 116.00 Ft Comments:

57 WEATHERING L 4,000.00 SqFt Comments:

52 RAVELING L 3,000.00 SqFt Comments:

45 DEPRESSION L 15.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP S Name: SOUTH APRON Use: APRON Area: 231,936.40SqFt

Section: 4210 of 5 From: - To: - Last Const.: 12/25/1999

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 52,540.81SqFt Length: 453.00Ft Width: 112.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 9 Surveyed: 1

Conditions: PCI : 67

Inspection Comments:

Sample Number: 505 Type: R Area: 6,600.00SqFt PCI = 67

Sample Comments:

45 DEPRESSION L 42.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 56.00 Ft Comments:

57 WEATHERING L 6,600.00 SqFt Comments:

52 RAVELING L 3,000.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP S Name: SOUTH APRON Use: APRON Area: 231,936.40SqFt

Section: 4215 of 5 From: - To: - Last Const.: 12/25/1999

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 32,595.35SqFt Length: 355.00Ft Width: 65.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 7 Surveyed: 1

Conditions: PCI : 74

Inspection Comments:

Sample Number: 402 Type: R Area: 4,500.00SqFt PCI = 74

Sample Comments:

45 DEPRESSION L 25.00 SqFt Comments:

57 WEATHERING L 4,500.00 SqFt Comments:

52 RAVELING L 1,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP S Name: SOUTH APRON Use: APRON Area: 231,936.40SqFt

Section: 4220 of 5 From: - To: - Last Const.: 12/25/1999

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 28,845.35SqFt Length: 453.00Ft Width: 65.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 7 Surveyed: 1

Conditions: PCI : 67

Inspection Comments:

Sample Number: 102 Type: R Area: 4,000.00SqFt PCI = 67

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 22.00 Ft Comments:

57 WEATHERING L 4,000.00 SqFt Comments:

52 RAVELING L 3,000.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: AP S Name: SOUTH APRON Use: APRON Area: 231,936.40SqFt

Section: 4225 of 5 From: - To: - Last Const.: 01/01/2009

Surface: AC Family: FDOT-SAPMP-GA-AP-AC Zone: Category: Rank: P

Area: 114,556.42SqFt Length: 1,800.00Ft Width: 65.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 28 Surveyed: 4

Conditions: PCI : 100

Inspection Comments:

Sample Number: 102 Type: R Area: 4,000.00SqFt PCI = 100

Sample Comments:  
<NO DISTRESSES>

Sample Number: 302 Type: R Area: 4,000.00SqFt PCI = 100

Sample Comments:  
<NO DISTRESSES>

Sample Number: 602 Type: R Area: 4,000.00SqFt PCI = 100

Sample Comments:  
<NO DISTRESSES>

Sample Number: 802 Type: R Area: 4,000.00SqFt PCI = 100

Sample Comments:  
<NO DISTRESSES>

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: RW 3-21 Name: RUNWAY 3-21 Use: RUNWAY Area: 752,250.00SqFt

Section: 6205 of 2 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: S  
Area: 250,750.00SqFt Length: 10,000.00Ft Width: 25.00Ft  
Slabs: 800 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 19,975.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 50 Surveyed: 10

Conditions: PCI : 53

Inspection Comments:

Sample Number: 104 Type: R Area: 16.00Slabs PCI = 66

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	4.00	Slabs	Comments:
66 SMALL PATCH	L	14.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74 JOINT SPALLING	L	1.00	Slabs	Comments:
75 CORNER SPALLING	M	1.00	Slabs	Comments:

Sample Number: 132 Type: R Area: 16.00Slabs PCI = 54

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	7.00	Slabs	Comments:
66 SMALL PATCH	L	14.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	3.00	Slabs	Comments:
74 JOINT SPALLING	L	2.00	Slabs	Comments:
74 JOINT SPALLING	M	2.00	Slabs	Comments:
75 CORNER SPALLING	L	2.00	Slabs	Comments:

Sample Number: 148 Type: R Area: 16.00Slabs PCI = 39

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	10.00	Slabs	Comments:
66 SMALL PATCH	L	14.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
63 LINEAR CRACKING	M	2.00	Slabs	Comments:
74 JOINT SPALLING	L	2.00	Slabs	Comments:
74 JOINT SPALLING	M	2.00	Slabs	Comments:
74 JOINT SPALLING	H	1.00	Slabs	Comments:
75 CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 164 Type: R Area: 16.00Slabs PCI = 53

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	2.00	Slabs	Comments:
63 LINEAR CRACKING	M	3.00	Slabs	Comments:
66 SMALL PATCH	L	16.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	9.00	Slabs	Comments:

Sample Number: 192 Type: R Area: 16.00Slabs PCI = 59

Sample Comments:

63 LINEAR CRACKING	L	2.00	Slabs	Comments:
--------------------	---	------	-------	-----------

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

66	SMALL PATCH	L	12.00	Slabs	Comments:
66	SMALL PATCH	M	1.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	7.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:
75	CORNER SPALLING	L	2.00	Slabs	Comments:

Sample Number: 504      Type: R      Area: 16.00Slabs      PCI = 38

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	9.00	Slabs	Comments:
63	LINEAR CRACKING	M	5.00	Slabs	Comments:
66	SMALL PATCH	L	14.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:

Sample Number: 512      Type: R      Area: 16.00Slabs      PCI = 60

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	4.00	Slabs	Comments:
66	SMALL PATCH	L	15.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	5.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 544      Type: R      Area: 16.00Slabs      PCI = 63

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	6.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 580      Type: R      Area: 16.00Slabs      PCI = 73

Sample Comments:

63	LINEAR CRACKING	L	2.00	Slabs	Comments:
66	SMALL PATCH	L	13.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	7.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 592      Type: R      Area: 16.00Slabs      PCI = 29

Sample Comments:

63	LINEAR CRACKING	L	7.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
66	SMALL PATCH	L	8.00	Slabs	Comments:
70	SCALING/CRAZING	M	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	8.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	2.00	Slabs	Comments:
75	CORNER SPALLING	M	1.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: RW 3-21 Name: RUNWAY 3-21 Use: RUNWAY Area: 752,250.00SqFt

Section: 6210 of 2 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: S  
Area: 501,500.00SqFt Length: 5,000.00Ft Width: 100.00Ft  
Slabs: 1,600 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 54,900.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 100 Surveyed: 20

Conditions: PCI : 55

Inspection Comments:

Sample Number: 301 Type: R Area: 16.00Slabs PCI = 70

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	4.00	Slabs	Comments:
66 SMALL PATCH	L	12.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	8.00	Slabs	Comments:

Sample Number: 306 Type: R Area: 16.00Slabs PCI = 55

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	8.00	Slabs	Comments:
63 LINEAR CRACKING	M	1.00	Slabs	Comments:
66 SMALL PATCH	L	10.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	6.00	Slabs	Comments:
74 JOINT SPALLING	L	3.00	Slabs	Comments:

Sample Number: 313 Type: R Area: 16.00Slabs PCI = 34

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	4.00	Slabs	Comments:
62 CORNER BREAK	L	1.00	Slabs	Comments:
63 LINEAR CRACKING	L	3.00	Slabs	Comments:
66 SMALL PATCH	L	9.00	Slabs	Comments:
67 LARGE PATCH/UTILITY	L	1.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	9.00	Slabs	Comments:
72 SHATTERED SLAB	H	1.00	Slabs	Comments:

Sample Number: 316 Type: R Area: 16.00Slabs PCI = 42

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	6.00	Slabs	Comments:
63 LINEAR CRACKING	M	3.00	Slabs	Comments:
66 SMALL PATCH	L	10.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	9.00	Slabs	Comments:
74 JOINT SPALLING	L	2.00	Slabs	Comments:
75 CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 319 Type: R Area: 16.00Slabs PCI = 46

Sample Comments:

70 SCALING/CRAZING	L	16.00	Slabs	Comments:
63 LINEAR CRACKING	L	5.00	Slabs	Comments:
63 LINEAR CRACKING	M	4.00	Slabs	Comments:



# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

66	SMALL PATCH	L	10.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	7.00	Slabs	Comments:

Sample Number: 325      Type: R      Area: 16.00Slabs      PCI = 50

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	3.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
66	SMALL PATCH	L	10.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:
75	CORNER SPALLING	M	1.00	Slabs	Comments:

Sample Number: 331      Type: R      Area: 16.00Slabs      PCI = 63

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	8.00	Slabs	Comments:
66	SMALL PATCH	L	10.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	5.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 337      Type: R      Area: 16.00Slabs      PCI = 48

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
66	SMALL PATCH	L	9.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	1.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:

Sample Number: 344      Type: R      Area: 16.00Slabs      PCI = 63

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	6.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 349      Type: R      Area: 16.00Slabs      PCI = 69

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	5.00	Slabs	Comments:
66	SMALL PATCH	L	11.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:

Sample Number: 355      Type: R      Area: 16.00Slabs      PCI = 58

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	6.00	Slabs	Comments:
66	SMALL PATCH	L	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:

Sample Number: 361      Type: R      Area: 16.00Slabs      PCI = 56

Sample Comments:

70	SCALING/CRAZING	L	15.00	Slabs	Comments:
----	-----------------	---	-------	-------	-----------

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

63	LINEAR CRACKING	L	9.00	Slabs	Comments:
66	SMALL PATCH	L	9.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	3.00	Slabs	Comments:
70	SCALING/CRAZING	M	1.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 367      Type: R      Area: 16.00Slabs      PCI = 51

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	9.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
66	SMALL PATCH	L	11.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:

Sample Number: 373      Type: R      Area: 16.00Slabs      PCI = 51

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:

Sample Number: 379      Type: R      Area: 16.00Slabs      PCI = 61

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	4.00	Slabs	Comments:
66	SMALL PATCH	L	8.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	8.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:
75	CORNER SPALLING	L	2.00	Slabs	Comments:

Sample Number: 384      Type: R      Area: 16.00Slabs      PCI = 43

Sample Comments:

74	JOINT SPALLING	L	2.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	3.00	Slabs	Comments:
66	SMALL PATCH	L	11.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:

Sample Number: 388      Type: R      Area: 16.00Slabs      PCI = 45

Sample Comments:

70	SCALING/CRAZING	L	16.00	Slabs	Comments:
63	LINEAR CRACKING	L	12.00	Slabs	Comments:
63	LINEAR CRACKING	M	3.00	Slabs	Comments:
66	SMALL PATCH	L	11.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:

Sample Number: 391      Type: R      Area: 16.00Slabs      PCI = 68

Sample Comments:

63	LINEAR CRACKING	L	4.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	8.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 393      Type: R      Area: 16.00Slabs      PCI = 63

Sample Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

63	LINEAR CRACKING	L	14.00	Slabs	Comments:
66	SMALL PATCH	L	10.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	9.00	Slabs	Comments:

Sample Number: 398      Type: R      Area: 16.00Slabs      PCI = 60

Sample Comments:

63	LINEAR CRACKING	L	6.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	9.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 1,050,000.00SqFt

Section: 6105 of 2 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 350,000.00SqFt Length: 14,000.00Ft Width: 25.00Ft  
Slabs: 1,120 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 27,975.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 70 Surveyed: 14

Conditions: PCI: 46

Inspection Comments:

Sample Number: 104 Type: R Area: 16.00Slabs PCI = 37

Sample Comments:

63	LINEAR CRACKING	L	4.00	Slabs	Comments:
66	SMALL PATCH	L	6.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
70	SCALING/CRAZING	L	5.00	Slabs	Comments:
70	SCALING/CRAZING	M	11.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	L	3.00	Slabs	Comments:
75	CORNER SPALLING	L	4.00	Slabs	Comments:

Sample Number: 120 Type: R Area: 16.00Slabs PCI = 43

Sample Comments:

63	LINEAR CRACKING	L	2.00	Slabs	Comments:
66	SMALL PATCH	L	8.00	Slabs	Comments:
70	SCALING/CRAZING	L	4.00	Slabs	Comments:
70	SCALING/CRAZING	M	6.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:
75	CORNER SPALLING	M	1.00	Slabs	Comments:
74	JOINT SPALLING	H	1.00	Slabs	Comments:

Sample Number: 144 Type: R Area: 16.00Slabs PCI = 53

Sample Comments:

63	LINEAR CRACKING	L	2.00	Slabs	Comments:
66	SMALL PATCH	L	11.00	Slabs	Comments:
70	SCALING/CRAZING	L	13.00	Slabs	Comments:
70	SCALING/CRAZING	M	3.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	M	2.00	Slabs	Comments:
75	CORNER SPALLING	L	4.00	Slabs	Comments:

Sample Number: 168 Type: R Area: 16.00Slabs PCI = 37

Sample Comments:

63	LINEAR CRACKING	L	1.00	Slabs	Comments:
66	SMALL PATCH	L	7.00	Slabs	Comments:
70	SCALING/CRAZING	L	2.00	Slabs	Comments:
70	SCALING/CRAZING	M	14.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	1.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:
75	CORNER SPALLING	L	2.00	Slabs	Comments:
75	CORNER SPALLING	M	2.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

---

Sample Number:	188	Type:	R	Area:	16.00Slabs	PCI = 43
Sample Comments:						
66	SMALL PATCH			L	6.00 Slabs	Comments:
70	SCALING/CRAZING			L	4.00 Slabs	Comments:
70	SCALING/CRAZING			M	12.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	4.00 Slabs	Comments:
74	JOINT SPALLING			L	4.00 Slabs	Comments:
75	CORNER SPALLING			L	2.00 Slabs	Comments:

---

Sample Number:	208	Type:	R	Area:	16.00Slabs	PCI = 49
Sample Comments:						
63	LINEAR CRACKING			L	2.00 Slabs	Comments:
66	SMALL PATCH			L	4.00 Slabs	Comments:
70	SCALING/CRAZING			L	8.00 Slabs	Comments:
70	SCALING/CRAZING			M	8.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	3.00 Slabs	Comments:
74	JOINT SPALLING			M	1.00 Slabs	Comments:

---

Sample Number:	228	Type:	R	Area:	16.00Slabs	PCI = 42
Sample Comments:						
63	LINEAR CRACKING			L	5.00 Slabs	Comments:
63	LINEAR CRACKING			M	5.00 Slabs	Comments:
66	SMALL PATCH			L	9.00 Slabs	Comments:
70	SCALING/CRAZING			L	16.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	3.00 Slabs	Comments:
74	JOINT SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	504	Type:	R	Area:	16.00Slabs	PCI = 52
Sample Comments:						
63	LINEAR CRACKING			L	6.00 Slabs	Comments:
63	LINEAR CRACKING			M	1.00 Slabs	Comments:
66	SMALL PATCH			L	5.00 Slabs	Comments:
70	SCALING/CRAZING			L	16.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	3.00 Slabs	Comments:
74	JOINT SPALLING			L	4.00 Slabs	Comments:
74	JOINT SPALLING			M	1.00 Slabs	Comments:
75	CORNER SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	520	Type:	R	Area:	16.00Slabs	PCI = 39
Sample Comments:						
63	LINEAR CRACKING			L	5.00 Slabs	Comments:
63	LINEAR CRACKING			M	2.00 Slabs	Comments:
66	SMALL PATCH			L	7.00 Slabs	Comments:
70	SCALING/CRAZING			L	10.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	2.00 Slabs	Comments:
74	JOINT SPALLING			M	5.00 Slabs	Comments:
74	JOINT SPALLING			H	1.00 Slabs	Comments:
75	CORNER SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	536	Type:	R	Area:	16.00Slabs	PCI = 36
Sample Comments:						
63	LINEAR CRACKING			L	3.00 Slabs	Comments:
63	LINEAR CRACKING			M	4.00 Slabs	Comments:
66	SMALL PATCH			L	5.00 Slabs	Comments:
70	SCALING/CRAZING			L	15.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	4.00 Slabs	Comments:
74	JOINT SPALLING			L	1.00 Slabs	Comments:
74	JOINT SPALLING			M	2.00 Slabs	Comments:
74	JOINT SPALLING			H	1.00 Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

75	CORNER SPALLING	L	3.00	Slabs	Comments:
75	CORNER SPALLING	M	1.00	Slabs	Comments:

Sample Number: 556      Type: R      Area: 16.00Slabs      PCI = 35

Sample Comments:

63	LINEAR CRACKING	L	5.00	Slabs	Comments:
63	LINEAR CRACKING	M	5.00	Slabs	Comments:
66	SMALL PATCH	L	6.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:
74	JOINT SPALLING	L	3.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:

Sample Number: 592      Type: R      Area: 16.00Slabs      PCI = 61

Sample Comments:

63	LINEAR CRACKING	L	6.00	Slabs	Comments:
66	SMALL PATCH	L	9.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	3.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 616      Type: R      Area: 16.00Slabs      PCI = 66

Sample Comments:

63	LINEAR CRACKING	L	1.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
66	SMALL PATCH	L	9.00	Slabs	Comments:
70	SCALING/CRAZING	L	10.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	5.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 628      Type: R      Area: 16.00Slabs      PCI = 55

Sample Comments:

73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:
63	LINEAR CRACKING	L	5.00	Slabs	Comments:
66	SMALL PATCH	L	6.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: RW 9-27 Name: RUNWAY 9-27 Use: RUNWAY Area: 1,050,000.00SqFt

Section: 6110 of 2 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 700,000.00SqFt Length: 7,000.00Ft Width: 100.00Ft  
Slabs: 2,240 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 76,900.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 140 Surveyed: 20

Conditions: PCI : 58

Inspection Comments:

Sample Number: 300 Type: R Area: 16.00Slabs PCI = 40

Sample Comments:

63	LINEAR CRACKING	L	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
66	SMALL PATCH	L	6.00	Slabs	Comments:
70	SCALING/CRAZING	L	8.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:
74	JOINT SPALLING	L	2.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:
75	CORNER SPALLING	L	2.00	Slabs	Comments:

Sample Number: 306 Type: R Area: 16.00Slabs PCI = 50

Sample Comments:

63	LINEAR CRACKING	L	11.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
66	SMALL PATCH	L	7.00	Slabs	Comments:
70	SCALING/CRAZING	L	14.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 314 Type: R Area: 16.00Slabs PCI = 57

Sample Comments:

63	LINEAR CRACKING	L	8.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 321 Type: R Area: 16.00Slabs PCI = 72

Sample Comments:

63	LINEAR CRACKING	L	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:

Sample Number: 328 Type: R Area: 16.00Slabs PCI = 60

Sample Comments:

63	LINEAR CRACKING	L	5.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	10.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

---

Sample Number:	335	Type:	R	Area:	16.00Slabs	PCI = 45
Sample Comments:						
63	LINEAR CRACKING			L	4.00 Slabs	Comments:
63	LINEAR CRACKING			M	4.00 Slabs	Comments:
66	SMALL PATCH			L	13.00 Slabs	Comments:
70	SCALING/CRAZING			L	14.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	7.00 Slabs	Comments:
75	CORNER SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	342	Type:	R	Area:	16.00Slabs	PCI = 61
Sample Comments:						
63	LINEAR CRACKING			L	11.00 Slabs	Comments:
66	SMALL PATCH			L	10.00 Slabs	Comments:
70	SCALING/CRAZING			L	15.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	6.00 Slabs	Comments:
74	JOINT SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	349	Type:	R	Area:	16.00Slabs	PCI = 61
Sample Comments:						
63	LINEAR CRACKING			L	4.00 Slabs	Comments:
63	LINEAR CRACKING			M	1.00 Slabs	Comments:
66	SMALL PATCH			L	10.00 Slabs	Comments:
70	SCALING/CRAZING			L	14.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	11.00 Slabs	Comments:
74	JOINT SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	356	Type:	R	Area:	16.00Slabs	PCI = 73
Sample Comments:						
63	LINEAR CRACKING			L	2.00 Slabs	Comments:
66	SMALL PATCH			L	8.00 Slabs	Comments:
70	SCALING/CRAZING			L	16.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	10.00 Slabs	Comments:
74	JOINT SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	363	Type:	R	Area:	16.00Slabs	PCI = 52
Sample Comments:						
63	LINEAR CRACKING			L	9.00 Slabs	Comments:
63	LINEAR CRACKING			M	1.00 Slabs	Comments:
66	SMALL PATCH			L	9.00 Slabs	Comments:
70	SCALING/CRAZING			L	14.00 Slabs	Comments:
70	SCALING/CRAZING			M	1.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	8.00 Slabs	Comments:
74	JOINT SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	370	Type:	R	Area:	16.00Slabs	PCI = 63
Sample Comments:						
63	LINEAR CRACKING			L	4.00 Slabs	Comments:
66	SMALL PATCH			L	8.00 Slabs	Comments:
70	SCALING/CRAZING			L	15.00 Slabs	Comments:
70	SCALING/CRAZING			M	1.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	6.00 Slabs	Comments:
74	JOINT SPALLING			L	1.00 Slabs	Comments:

---

Sample Number:	374	Type:	R	Area:	16.00Slabs	PCI = 61
Sample Comments:						
63	LINEAR CRACKING			L	7.00 Slabs	Comments:
66	SMALL PATCH			L	6.00 Slabs	Comments:
70	SCALING/CRAZING			L	16.00 Slabs	Comments:



# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

73 SHRINKAGE CRACKING	N	4.00	Slabs	Comments:
63 LINEAR CRACKING	M	1.00	Slabs	Comments:

Sample Number: 377      Type: R      Area: 16.00Slabs      PCI = 66

Sample Comments:

63 LINEAR CRACKING	L	3.00	Slabs	Comments:
63 LINEAR CRACKING	M	1.00	Slabs	Comments:
66 SMALL PATCH	L	7.00	Slabs	Comments:
70 SCALING/CRAZING	L	16.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	10.00	Slabs	Comments:

Sample Number: 384      Type: R      Area: 16.00Slabs      PCI = 64

Sample Comments:

63 LINEAR CRACKING	L	10.00	Slabs	Comments:
66 SMALL PATCH	L	8.00	Slabs	Comments:
70 SCALING/CRAZING	L	16.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	8.00	Slabs	Comments:

Sample Number: 398      Type: R      Area: 16.00Slabs      PCI = 63

Sample Comments:

63 LINEAR CRACKING	L	6.00	Slabs	Comments:
63 LINEAR CRACKING	M	1.00	Slabs	Comments:
66 SMALL PATCH	L	8.00	Slabs	Comments:
70 SCALING/CRAZING	L	16.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	3.00	Slabs	Comments:

Sample Number: 409      Type: R      Area: 16.00Slabs      PCI = 62

Sample Comments:

63 LINEAR CRACKING	L	7.00	Slabs	Comments:
66 SMALL PATCH	L	5.00	Slabs	Comments:
70 SCALING/CRAZING	L	15.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	5.00	Slabs	Comments:
75 CORNER SPALLING	L	2.00	Slabs	Comments:

Sample Number: 419      Type: R      Area: 16.00Slabs      PCI = 61

Sample Comments:

63 LINEAR CRACKING	L	7.00	Slabs	Comments:
63 LINEAR CRACKING	M	1.00	Slabs	Comments:
66 SMALL PATCH	L	9.00	Slabs	Comments:
70 SCALING/CRAZING	L	13.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	4.00	Slabs	Comments:

Sample Number: 426      Type: R      Area: 16.00Slabs      PCI = 55

Sample Comments:

63 LINEAR CRACKING	L	6.00	Slabs	Comments:
63 LINEAR CRACKING	M	2.00	Slabs	Comments:
66 SMALL PATCH	L	9.00	Slabs	Comments:
70 SCALING/CRAZING	L	16.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	1.00	Slabs	Comments:
74 JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 435      Type: R      Area: 16.00Slabs      PCI = 47

Sample Comments:

63 LINEAR CRACKING	L	4.00	Slabs	Comments:
63 LINEAR CRACKING	M	1.00	Slabs	Comments:
66 SMALL PATCH	L	4.00	Slabs	Comments:
70 SCALING/CRAZING	L	9.00	Slabs	Comments:
70 SCALING/CRAZING	M	4.00	Slabs	Comments:
73 SHRINKAGE CRACKING	N	9.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

---

74	JOINT SPALLING	L	2.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:

---

Sample Number:	439	Type:	R	Area:	16.00Slabs	PCI = 44
----------------	-----	-------	---	-------	------------	----------

Sample Comments:

63	LINEAR CRACKING	L	9.00	Slabs	Comments:
63	LINEAR CRACKING	M	2.00	Slabs	Comments:
66	SMALL PATCH	L	4.00	Slabs	Comments:
70	SCALING/CRAZING	L	7.00	Slabs	Comments:
70	SCALING/CRAZING	M	2.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	7.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 648,306.61SqFt

Section: 105 of 1 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 648,306.61SqFt Length: 8,650.00Ft Width: 75.00Ft  
Slabs: 2,076 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 69,125.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 173 Surveyed: 13

Conditions: PCI : 50

Inspection Comments:

Sample Number: 107 Type: R Area: 12.00Slabs PCI = 59

Sample Comments:

63 LINEAR CRACKING	M	1.00 Slabs	Comments:
66 SMALL PATCH	L	5.00 Slabs	Comments:
66 SMALL PATCH	M	3.00 Slabs	Comments:
70 SCALING/CRAZING	L	11.00 Slabs	Comments:
73 SHRINKAGE CRACKING	N	6.00 Slabs	Comments:
70 SCALING/CRAZING	M	1.00 Slabs	Comments:

Sample Number: 121 Type: R Area: 12.00Slabs PCI = 36

Sample Comments:

63 LINEAR CRACKING	L	1.00 Slabs	Comments:
66 SMALL PATCH	L	3.00 Slabs	Comments:
66 SMALL PATCH	H	2.00 Slabs	Comments:
70 SCALING/CRAZING	L	5.00 Slabs	Comments:
70 SCALING/CRAZING	M	7.00 Slabs	Comments:
73 SHRINKAGE CRACKING	N	4.00 Slabs	Comments:
74 JOINT SPALLING	L	1.00 Slabs	Comments:
74 JOINT SPALLING	H	1.00 Slabs	Comments:

Sample Number: 135 Type: R Area: 12.00Slabs PCI = 62

Sample Comments:

66 SMALL PATCH	L	7.00 Slabs	Comments:
70 SCALING/CRAZING	L	9.00 Slabs	Comments:
70 SCALING/CRAZING	M	3.00 Slabs	Comments:
73 SHRINKAGE CRACKING	N	3.00 Slabs	Comments:
75 CORNER SPALLING	L	1.00 Slabs	Comments:

Sample Number: 149 Type: R Area: 12.00Slabs PCI = 41

Sample Comments:

63 LINEAR CRACKING	L	1.00 Slabs	Comments:
63 LINEAR CRACKING	M	1.00 Slabs	Comments:
66 SMALL PATCH	L	6.00 Slabs	Comments:
66 SMALL PATCH	M	2.00 Slabs	Comments:
73 SHRINKAGE CRACKING	N	3.00 Slabs	Comments:
70 SCALING/CRAZING	M	4.00 Slabs	Comments:
70 SCALING/CRAZING	L	4.00 Slabs	Comments:
75 CORNER SPALLING	L	1.00 Slabs	Comments:
71 FAULTING	L	1.00 Slabs	Comments:

Sample Number: 163 Type: R Area: 12.00Slabs PCI = 75

Sample Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

66	SMALL PATCH	L	9.00	Slabs	Comments:
70	SCALING/CRAZING	L	12.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	5.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 177      Type: R      Area: 12.00Slabs      PCI = 60

Sample Comments:

66	SMALL PATCH	L	8.00	Slabs	Comments:
70	SCALING/CRAZING	L	8.00	Slabs	Comments:
70	SCALING/CRAZING	M	4.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:

Sample Number: 191      Type: R      Area: 12.00Slabs      PCI = 62

Sample Comments:

63	LINEAR CRACKING	L	2.00	Slabs	Comments:
66	SMALL PATCH	L	5.00	Slabs	Comments:
70	SCALING/CRAZING	L	9.00	Slabs	Comments:
70	SCALING/CRAZING	M	2.00	Slabs	Comments:
66	SMALL PATCH	M	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	3.00	Slabs	Comments:

Sample Number: 205      Type: R      Area: 12.00Slabs      PCI = 29

Sample Comments:

63	LINEAR CRACKING	M	3.00	Slabs	Comments:
66	SMALL PATCH	L	8.00	Slabs	Comments:
70	SCALING/CRAZING	L	6.00	Slabs	Comments:
70	SCALING/CRAZING	M	5.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	6.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 226      Type: R      Area: 12.00Slabs      PCI = 46

Sample Comments:

63	LINEAR CRACKING	L	2.00	Slabs	Comments:
62	CORNER BREAK	L	1.00	Slabs	Comments:
66	SMALL PATCH	L	7.00	Slabs	Comments:
70	SCALING/CRAZING	L	6.00	Slabs	Comments:
70	SCALING/CRAZING	M	6.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:

Sample Number: 240      Type: R      Area: 14.00Slabs      PCI = 39

Sample Comments:

63	LINEAR CRACKING	M	1.00	Slabs	Comments:
66	SMALL PATCH	L	8.00	Slabs	Comments:
66	SMALL PATCH	M	1.00	Slabs	Comments:
70	SCALING/CRAZING	L	4.00	Slabs	Comments:
70	SCALING/CRAZING	M	6.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	5.00	Slabs	Comments:
74	JOINT SPALLING	M	1.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:
75	CORNER SPALLING	M	1.00	Slabs	Comments:

Sample Number: 247      Type: R      Area: 12.00Slabs      PCI = 54

Sample Comments:

66	SMALL PATCH	L	7.00	Slabs	Comments:
70	SCALING/CRAZING	L	5.00	Slabs	Comments:
70	SCALING/CRAZING	M	6.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

---

Sample Number:	254	Type:	R	Area:	12.00Slabs	PCI = 49
Sample Comments:						
63	LINEAR CRACKING			L	2.00 Slabs	Comments:
66	SMALL PATCH			L	7.00 Slabs	Comments:
70	SCALING/CRAZING			L	4.00 Slabs	Comments:
70	SCALING/CRAZING			M	6.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	1.00 Slabs	Comments:
74	JOINT SPALLING			M	1.00 Slabs	Comments:

---

Sample Number:	268	Type:	R	Area:	12.00Slabs	PCI = 43
Sample Comments:						
63	LINEAR CRACKING			L	3.00 Slabs	Comments:
63	LINEAR CRACKING			M	1.00 Slabs	Comments:
66	SMALL PATCH			L	5.00 Slabs	Comments:
70	SCALING/CRAZING			L	4.00 Slabs	Comments:
70	SCALING/CRAZING			M	6.00 Slabs	Comments:
73	SHRINKAGE CRACKING			N	4.00 Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A1 Name: TAXIWAY A1 Use: TAXIWAY Area: 92,918.14SqFt

Section: 110 of 3 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 56,894.07SqFt Length: 750.00Ft Width: 75.00Ft  
Slabs: 182 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 5,925.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 15 Surveyed: 3

Conditions: PCI : 53

Inspection Comments:

Sample Number: 101 Type: R Area: 12.00Slabs PCI = 52

Sample Comments:

63	LINEAR CRACKING	L	1.00	Slabs	Comments:
62	CORNER BREAK	L	1.00	Slabs	Comments:
66	SMALL PATCH	L	4.00	Slabs	Comments:
70	SCALING/CRAZING	L	7.00	Slabs	Comments:
70	SCALING/CRAZING	M	3.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 106 Type: R Area: 13.00Slabs PCI = 51

Sample Comments:

63	LINEAR CRACKING	L	1.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
66	SMALL PATCH	L	6.00	Slabs	Comments:
70	SCALING/CRAZING	L	9.00	Slabs	Comments:
70	SCALING/CRAZING	M	2.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	3.00	Slabs	Comments:
74	JOINT SPALLING	L	4.00	Slabs	Comments:
75	CORNER SPALLING	L	2.00	Slabs	Comments:

Sample Number: 111 Type: R Area: 12.00Slabs PCI = 55

Sample Comments:

63	LINEAR CRACKING	L	7.00	Slabs	Comments:
66	SMALL PATCH	L	2.00	Slabs	Comments:
70	SCALING/CRAZING	L	6.00	Slabs	Comments:
70	SCALING/CRAZING	M	2.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	1.00	Slabs	Comments:
74	JOINT SPALLING	L	3.00	Slabs	Comments:
75	CORNER SPALLING	L	4.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A1 Name: TAXIWAY A1 Use: TAXIWAY Area: 92,918.14SqFt

Section: 111 of 3 From: - To: - Last Const.: 01/01/1991

Surface: AAC Family: FDOT-SAPMP-GA-TW-AAC Zone: Category: Rank: P

Area: 17,869.99SqFt Length: 445.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 4 Surveyed: 1

Conditions: PCI : 77

Inspection Comments:

Sample Number: 116 Type: R Area: 4,000.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 168.00 Ft Comments:

57 WEATHERING L 4,000.00 SqFt Comments:

52 RAVELING L 400.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A1 Name: TAXIWAY A1 Use: TAXIWAY Area: 92,918.14SqFt

Section: 112 of 3 From: - To: - Last Const.: 01/01/1964

Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P

Area: 18,154.08SqFt Length: 455.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 5 Surveyed: 1

Conditions: PCI : 44

Inspection Comments:

Sample Number: 119 Type: R Area: 4,000.00SqFt PCI = 44

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	408.00 Ft	Comments:
57	WEATHERING	L	3,000.00 SqFt	Comments:
52	RAVELING	L	3,000.00 SqFt	Comments:
52	RAVELING	M	1,000.00 SqFt	Comments:
45	DEPRESSION	L	32.00 SqFt	Comments:



# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A3 Name: TAXIWAY A3 Use: TAXIWAY Area: 37,158.85SqFt

Section: 120 of 2 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 10,836.50SqFt Length: 413.00Ft Width: 25.00Ft  
Slabs: 33 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 801.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 2 Surveyed: 1

Conditions: PCI : 41

Inspection Comments:

Sample Number: 401 Type: R Area: 20.00Slabs PCI = 41

Sample Comments:

63	LINEAR CRACKING	L	3.00	Slabs	Comments:
63	LINEAR CRACKING	M	7.00	Slabs	Comments:
66	SMALL PATCH	L	12.00	Slabs	Comments:
70	SCALING/CRAZING	L	20.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	7.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A3 Name: TAXIWAY A3 Use: TAXIWAY Area: 37,158.85SqFt

Section: 125 of 2 From: - To: - Last Const.: 01/01/1986

Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P

Area: 26,322.35SqFt Length: 400.00Ft Width: 53.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 5 Surveyed: 1

Conditions: PCI : 20

Inspection Comments:

Sample Number: 301 Type: R Area: 5,099.00SqFt PCI = 20

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 150.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 387.00 Ft Comments:

52 RAVELING M 4,400.00 SqFt Comments:

52 RAVELING H 600.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A5 Name: TAXIWAY A5 Use: TAXIWAY Area: 33,046.02SqFt

Section: 130 of 1 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 33,046.02SqFt Length: 430.00Ft Width: 75.00Ft  
Slabs: 104 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 3,365.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 8 Surveyed: 2

Conditions: PCI : 59

Inspection Comments:

Sample Number: 502 Type: R Area: 12.00Slabs PCI = 75

Sample Comments:

63 LINEAR CRACKING	L	2.00 Slabs	Comments:
66 SMALL PATCH	L	3.00 Slabs	Comments:
70 SCALING/CRAZING	L	12.00 Slabs	Comments:
73 SHRINKAGE CRACKING	N	4.00 Slabs	Comments:

Sample Number: 506 Type: R Area: 12.00Slabs PCI = 42

Sample Comments:

63 LINEAR CRACKING	L	5.00 Slabs	Comments:
63 LINEAR CRACKING	M	3.00 Slabs	Comments:
66 SMALL PATCH	L	6.00 Slabs	Comments:
70 SCALING/CRAZING	L	12.00 Slabs	Comments:
73 SHRINKAGE CRACKING	N	3.00 Slabs	Comments:
74 JOINT SPALLING	L	1.00 Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A6 Name: TAXIWAY A6 Use: TAXIWAY Area: 31,613.91SqFt

Section: 135 of 1 From: - To: - Last Const.: 01/01/1986  
Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P  
Area: 31,613.91SqFt Length: 418.00Ft Width: 53.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 9 Surveyed: 2

Conditions: PCI : 20

Inspection Comments:

Sample Number: 603 Type: R Area: 2,569.79SqFt PCI = 21

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	238.00 Ft	Comments:
52	RAVELING	M	2,250.00 SqFt	Comments:
52	RAVELING	H	250.00 SqFt	Comments:

Sample Number: 606 Type: R Area: 2,768.80SqFt PCI = 19

Sample Comments:

52	RAVELING	M	1,750.00 SqFt	Comments:
52	RAVELING	H	245.00 SqFt	Comments:
50	PATCHING	L	750.00 SqFt	Comments:
43	BLOCK CRACKING	H	16.00 SqFt	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	251.00 Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	70.00 Ft	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW A9 Name: TAXIWAY A9 Use: TAXIWAY Area: 31,973.01SqFt

Section: 140 of 1 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 31,973.01SqFt Length: 440.00Ft Width: 75.00Ft  
Slabs: 106 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 3,445.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 8 Surveyed: 2

Conditions: PCI : 69

Inspection Comments:

Sample Number: 902 Type: R Area: 12.00Slabs PCI = 62

Sample Comments:

63	LINEAR CRACKING	L	4.00	Slabs	Comments:
66	SMALL PATCH	L	6.00	Slabs	Comments:
70	SCALING/CRAZING	L	11.00	Slabs	Comments:
70	SCALING/CRAZING	M	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

Sample Number: 906 Type: R Area: 12.00Slabs PCI = 76

Sample Comments:

63	LINEAR CRACKING	L	1.00	Slabs	Comments:
66	SMALL PATCH	L	8.00	Slabs	Comments:
70	SCALING/CRAZING	L	12.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 173,973.00SqFt

Section: 205 of 2 From: - To: - Last Const.: 01/01/1990  
Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P  
Area: 55,550.48SqFt Length: 1,590.00Ft Width: 35.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 15 Surveyed: 3

Conditions: PCI : 38

Inspection Comments:

Sample Number: 137 Type: R Area: 3,500.00SqFt PCI = 45

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	334.00	Ft	Comments:
52	RAVELING	L	1,500.00	SqFt	Comments:
52	RAVELING	M	2,000.00	SqFt	Comments:

Sample Number: 143 Type: R Area: 3,500.00SqFt PCI = 40

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	293.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	12.00	Ft	Comments:
52	RAVELING	L	1,500.00	SqFt	Comments:
52	RAVELING	M	2,000.00	SqFt	Comments:

Sample Number: 148 Type: R Area: 5,973.00SqFt PCI = 32

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	280.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	228.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	20.00	Ft	Comments:
52	RAVELING	M	3,200.00	SqFt	Comments:
52	RAVELING	H	300.00	SqFt	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 173,973.00SqFt

Section: 210 of 2 From: - To: - Last Const.: 01/01/1991  
Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P  
Area: 118,422.52SqFt Length: 3,375.00Ft Width: 35.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 34 Surveyed: 5

Conditions: PCI : 66

Inspection Comments:

Sample Number: 104 Type: R Area: 3,500.00SqFt PCI = 62

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	183.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	M	100.00	Ft	Comments:
57	WEATHERING	L	3,500.00	SqFt	Comments:
52	RAVELING	L	2,500.00	SqFt	Comments:

Sample Number: 112 Type: R Area: 3,500.00SqFt PCI = 59

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	234.00	Ft	Comments:
57	WEATHERING	L	3,500.00	SqFt	Comments:
52	RAVELING	L	3,500.00	SqFt	Comments:

Sample Number: 120 Type: R Area: 3,500.00SqFt PCI = 71

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	229.00	Ft	Comments:
57	WEATHERING	L	3,500.00	SqFt	Comments:
52	RAVELING	L	1,500.00	SqFt	Comments:

Sample Number: 128 Type: R Area: 3,500.00SqFt PCI = 71

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	251.00	Ft	Comments:
57	WEATHERING	L	3,500.00	SqFt	Comments:
52	RAVELING	L	1,500.00	SqFt	Comments:

Sample Number: 132 Type: R Area: 3,500.00SqFt PCI = 66

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	M	60.00	Ft	Comments:
48	LONGITUDINAL/TRANSVERSE CRACKING	L	197.00	Ft	Comments:
57	WEATHERING	L	3,500.00	SqFt	Comments:
52	RAVELING	L	1,500.00	SqFt	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B1 Name: TAXIWAY B1 Use: TAXIWAY Area: 190,128.02SqFt

Section: 145 of 3 From: - To: - Last Const.: 01/01/1998  
Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P  
Area: 80,953.55SqFt Length: 850.00Ft Width: 76.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 18 Surveyed: 3

Conditions: PCI : 72

Inspection Comments:

Sample Number: 302 Type: R Area: 4,901.00SqFt PCI = 73

Sample Comments:

57 WEATHERING	L	4,901.00 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	L	253.00 Ft	Comments:
52 RAVELING	L	400.00 SqFt	Comments:
56 SWELLING	L	12.00 SqFt	Comments:

Sample Number: 305 Type: R Area: 4,130.00SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	144.00 Ft	Comments:
57 WEATHERING	L	4,130.00 SqFt	Comments:
56 SWELLING	L	26.00 SqFt	Comments:
52 RAVELING	L	200.00 SqFt	Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING	M	30.00 Ft	Comments:

Sample Number: 308 Type: R Area: 3,750.00SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING	L	213.00 Ft	Comments:
57 WEATHERING	L	3,750.00 SqFt	Comments:
52 RAVELING	L	300.00 SqFt	Comments:
56 SWELLING	L	22.00 SqFt	Comments:



# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B1 Name: TAXIWAY B1 Use: TAXIWAY Area: 190,128.02SqFt

Section: 215 of 3 From: - To: - Last Const.: 01/01/1942  
Surface: PCC Family: FDOT-SAPMP-GA-RW-TW-PCC Zone: Category: Rank: P  
Area: 63,745.26SqFt Length: 810.00Ft Width: 75.00Ft  
Slabs: 194 Slab Width: 25.00Ft Slab Length: 12.50Ft Joint Length: 6,405.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 16 Surveyed: 3

Conditions: PCI : 58

Inspection Comments:

Sample Number: 100 Type: R Area: 17.00Slabs PCI = 46

Sample Comments:

63	LINEAR CRACKING	L	10.00	Slabs	Comments:
63	LINEAR CRACKING	M	3.00	Slabs	Comments:
66	SMALL PATCH	L	4.00	Slabs	Comments:
70	SCALING/CRAZING	L	16.00	Slabs	Comments:
70	SCALING/CRAZING	M	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:

Sample Number: 106 Type: R Area: 12.00Slabs PCI = 72

Sample Comments:

66	SMALL PATCH	L	5.00	Slabs	Comments:
70	SCALING/CRAZING	L	9.00	Slabs	Comments:
70	SCALING/CRAZING	M	1.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	4.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:
75	CORNER SPALLING	L	1.00	Slabs	Comments:

Sample Number: 112 Type: R Area: 12.00Slabs PCI = 61

Sample Comments:

63	LINEAR CRACKING	L	3.00	Slabs	Comments:
63	LINEAR CRACKING	M	1.00	Slabs	Comments:
66	SMALL PATCH	L	7.00	Slabs	Comments:
70	SCALING/CRAZING	L	11.00	Slabs	Comments:
73	SHRINKAGE CRACKING	N	2.00	Slabs	Comments:
74	JOINT SPALLING	L	1.00	Slabs	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B1 Name: TAXIWAY B1 Use: TAXIWAY Area: 190,128.02SqFt

Section: 216 of 3 From: - To: - Last Const.: 01/01/1991  
Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P  
Area: 45,429.21SqFt Length: 885.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 9 Surveyed: 2

Conditions: PCI : 58

Inspection Comments:

Sample Number: 119 Type: R Area: 5,000.00SqFt PCI = 63

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	193.00 Ft	Comments:
57	WEATHERING	L	5,000.00 SqFt	Comments:
52	RAVELING	L	3,000.00 SqFt	Comments:
56	SWELLING	L	165.00 SqFt	Comments:

Sample Number: 123 Type: R Area: 5,000.00SqFt PCI = 53

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	239.00 Ft	Comments:
57	WEATHERING	L	5,000.00 SqFt	Comments:
52	RAVELING	L	3,500.00 SqFt	Comments:
56	SWELLING	L	1,900.00 SqFt	Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B2 Name: TAXIWAY B2 Use: TAXIWAY Area: 7,308.52SqFt

Section: 220 of 1 From: - To: - Last Const.: 01/01/1990

Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P

Area: 7,308.52SqFt Length: 150.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 2 Surveyed: 1

Conditions: PCI : 38

Inspection Comments:

Sample Number: 200 Type: R Area: 2,000.00SqFt PCI = 38

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 169.00 Ft Comments:

52 RAVELING M 2,000.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B3 Name: TAXIWAY B3 Use: TAXIWAY Area: 7,308.52SqFt

Section: 225 of 1 From: - To: - Last Const.: 01/01/1991

Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P

Area: 7,308.52SqFt Length: 150.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 2 Surveyed: 1

Conditions: PCI : 59

Inspection Comments:

Sample Number: 301 Type: R Area: 4,500.00SqFt PCI = 59

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 70.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 260.00 Ft Comments:

57 WEATHERING L 4,500.00 SqFt Comments:

52 RAVELING L 4,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: November 11, 2013

Network: BKV Name: Brooksville - Tampa Bay Regional Airport

Branch: TW B4 Name: TAXIWAY B4 Use: TAXIWAY Area: 6,246.24SqFt

Section: 230 of 1 From: - To: - Last Const.: 01/01/1991

Surface: AC Family: FDOT-SAPMP-GA-TW-AC Zone: Category: Rank: P

Area: 6,246.24SqFt Length: 150.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 06/10/2013 Total Samples: 2 Surveyed: 1

Conditions: PCI : 62

Inspection Comments:

Sample Number: 401 Type: R Area: 3,274.00SqFt PCI = 62

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 69.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 238.00 Ft Comments:

57 WEATHERING L 1,994.00 SqFt Comments:

52 RAVELING L 1,994.00 SqFt Comments: