# FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION AND SPACEPORT OFFICE



PROGRAM

142179022.13

# TABLE OF CONTENTS

Exe	ecutive Summary	1
1.	Introduction	6
2.	Airfield Pavement Network Definition and Pavement Inventory	17
3.	Airfield Pavement Condition	24
4.	Pavement Performance	32
5.	Airfield Pavement Maintenance Policies and Costs	35
6.	Major Pavement Rehabilitation Needs	43
7.	Preventative and Major Rehabilitation Planning	45
8.	Visual Aid Exhibits	47
9.	Recommendations	. 48

# LIST OF TABLES

Table I: Condition Summary by Branch2
Table II: Condition Summary by Pavement Facility Use
Table III: Year-1 Major Rehabilitation Needs for Bob Sikes Airport4
Table IV: 10-Year Preventative Maintenance and Major Rehabilitation5
Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections
Table 2-1: Recent and/or Anticipated Airfield Pavement Construction
Table 2-2: Pavement Inventory Summary
Table 2-3: Airfield Pavement Inventory Details
Table 3-1: Airfield Pavement Distresses for Asphalt Concrete
Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete
Table 3-3: Pavement Condition Index Rating Summary
Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy
Table 5-2: Recommended PCC Maintenance and Repair Policy
Table 5-3: Critical and Minimum Service Level PCI for General Aviation Airports 39
Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI
Table 5-5: AC Maintenance Unit Costs 41
Table 5-6: PCC Maintenance Unit Costs

Pavement Evaluation Report - Bob Sikes Airport

Table 5-7: Rehabilitation Activities and Unit Costs by Condition for General	
Aviation Airports	42
Table 6-1: Summary of Major Rehabilitation	44
Table 7-1: 10-Year Preventative and Major Rehabilitation Summary	45

# LIST OF FIGURES

Figure 1-1: Pavement Life Cycle	. 12
Figure 1-2: Flexible Pavement, Asphalt Concrete	. 15
Figure 1-3: Rigid Pavement, Portland Cement Concrete	. 16
Figure 2-1: Airfield Pavement Type	. 21
Figure 3-1: Airfield Pavement Condition Index Rating Summary	. 28
Figure 3-2: Percentage of Pavement Area by Condition Rating by Use	. 30
Figure 4-1: Runway Pavement Performance Prediction Summary	. 33
Figure 4-2: Taxiway Pavement Performance Prediction Summary	. 33
Figure 4-3: Apron Pavement Performance Prediction Summary	. 34
Figure 6-1: 10-Year Major Rehabilitation Budget Scenario Analysis	. 44
Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary	. 46

# **APPENDICES**

Appendix A	Airfield Pavement Network Definition Exhibit
	Airfield Pavement System Inventory Exhibit
	Pavement Geometry Inventory
	Work History Report
Appendix B	Airfield Pavement Condition Index Rating Exhibit
	Pavement Condition Index Inventory
Appendix C	Branch Condition Report
	Section Condition Report
Appendix D	Pavement Performance Prediction Table
	Pavement Performance by Pavement Use
Appendix E	Year-1 Preventative Activities
Appendix F	Airfield Pavement 10-Year Major Rehabilitation Exhibit
	Airfield Pavement 10-Year Major Rehabilitation Table
Appendix G	Photographs
Appendix H	Distress Data – Re-inspection Report

## **EXECUTIVE SUMMARY**

In 2012, the Florida Department of Transportation (FDOT) Aviation and Spaceport Office selected a team lead by *Kimley-Horn and Associates, Inc.* and including their subconsultants Peneul Consulting, LLC, Roy D. McQueen & Associates, LTD, and All About Pavements, Inc., to provide services in support of FDOT in the continued efforts of updating the existing Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed over the fiscal years of 2013 and 2014.

The tasks required to achieve this objective at each participating airport specifically included the following:

- Obtain recent construction history from the airport to update the Pavement Network Definition Exhibits using CADD from the previous SAPMP update.
- Update the airport pavement inventory data (construction history, geometry, identification, and classification) based on airport information provided.
- Update the FDOT SAPMP MicroPAVER database files and system tables for the purpose of analyzing field data for Pavement Condition Index (PCI) calculation of current pavement condition
- Development of pavement performance models for the approximation of future pavement performance.
- Development of a maintenance and repair plan, and a 10-year major rehabilitation program to address the pavement needs based on condition.
- Development of planning level opinions of probable costs for pavement preservation and rehabilitation.

In AUGUST 2013, a PCI survey inspection was performed at Bob Sikes Airport. The results of the inspection indicate that, based on ASTM D 5340-11, the airport's airfield pavement facilities had an overall area-weighted average PCI of 87, representing a GOOD overall network condition. Table I summarizes the overall condition summary by network level branch in comparison to the FDOT recommended minimum service level.

Branch Name	Area Weighted PCI	PCI Range	Average Condition Rating	FDOT Minimum Service Level	MicroPAVER Minimum PCI	Action Required
APRON	55	30 - 100	POOR	60	65	Х
HANGAR APRON	49	18 - 62	POOR	60	65	Х
NORTH APRON	100	100	GOOD	60	65	
WEST RUN-UP APRON AT RW 17	100	100	GOOD	60	65	
RUNWAY 17-35	87	79 - 93	GOOD	75	65	
TAXIWAY A	100	100	GOOD	65	65	
TAXIWAY A2	100	100	GOOD	65	65	
TAXIWAY A3	100	100	GOOD	65	65	
TAXIWAY A4	100	100	GOOD	65	65	
CONNECTOR TAXIWAYS TO APRON	100	100	GOOD	65	65	
ΤΑΧΙΨΑΥ Κ	94	94	GOOD	65	65	
TAXIWAY PMV	94	94	GOOD	65	65	

### Table I: Condition Summary by Branch

For project level planning and inspection development; the airfield pavement facilities have been divided at the branch level based on facility use and designation, and at the section level based on pavement construction history, composition (e.g. asphalt versus concrete), aircraft traffic operations, and pavement surface conditions. Table II provides the overall area weighted condition of the pavement based on facility branch use.

#### Table II: Condition Summary by Pavement Facility Use

Use	Average Area- Weighted PCI	Condition Rating		
Runway	87	GOOD		
Taxiway	99	GOOD		
Apron	71	SATISFACTORY		

Based on the inspection performed at the airport for this SAPMP update; the current conditions were determined using the collected PCI distress data. PCI values were computed and used to identify pavement facilities that were below

the defined critical PCI as sections that would benefit from immediate major rehabilitation activity. These pavement sections that were determined to be below the critical PCI would most likely benefit from long-term major rehabilitative construction activity rather than localized, short-term maintenance and repairs.

The Year-1 Major Rehabilitation Needs, or projects that are recommended to be completed because the pavement is below the critical PCI, were developed on the assumption that there is an unlimited repair budget. These projects include:

- Hangar Apron Section 4210
  - Reconstruction attributed to distresses related to subgrade quality, climate, and age of pavement.
- Hangar Apron Section 4205
  - Mill and Overlay attributed to distresses related to climate and age of pavement.
- Apron Section 4115, 4110, and 4105
  - Reconstruction attributed to distresses related to subgrade quality, climate, and age of pavement.

The section level projects that were identified as Year-1 Major Rehabilitation Needs are in Table III.

Branch ID	Section ID	Major Rehabilitation Costs	PCI Before M&R	Rehabilitation Activity	PCI After M&R
AP HANG	4210	\$106,552.98	18	Reconstruction	100
AP HANG	4205	\$180,101.89	62	Mill and Overlay	100
AP	4115	\$2,808,460.86	32	Reconstruction	100
AP	4110	\$1,406,250.33	30	Reconstruction	100
AP	4105	\$843,750.20	37	Reconstruction	100
	Total =	\$5,345,116.26			

T. I. I. III	A A STAR DO STAR STOLEN PROVIDENT	NUMBER OF COMPANY	011
lable III: Year-I	Major Rehabilitation	Needs for Bob	Sikes Airport

The SAPMP uses historic pavement condition data from the previous inspections to develop pavement performance models. These pavement performance models are used to create PCI prediction curves to estimate future pavement conditions based on the historic trends. The section areas, prediction curves, and current condition data were used to develop a 10-year major rehabilitation program. Major rehabilitation costs for each year of the 10-year program are based on general unit costs for pavement repairs and not detailed cost estimates that are typically prepared for a construction set of bid documents. Additionally, preventative maintenance level repair budgets were estimated for a 10-year duration. Table IV provides an annual summary of the 10-year Preventative Maintenance and Major Rehabilitation planning level cost opinions for the airfield pavement facilities at the airport. Refer to Section 6 of this report for additional information.

Year	Preventative		Preventative Major M&R		Total Year Cost	
2014	\$	93,949.13	\$	5,345,116.26	\$	5,439,065.39
2015	\$	142,722.24	\$	-	\$	142,722.24
2016	\$	240,648.93	\$	-	\$	240,648.93
2017	\$	426,777.85	\$	-	\$	426,777.85
2018	\$	606,072.87	\$	-	\$	606,072.87
2019	\$	776,398.50	\$	-	\$	776,398.50
2020	\$	923,913.36	\$	-	\$	923,913.36
2021	\$	1,053,103.49	\$	-	\$	1,053,103.49
2022	\$	1,160,323.99	\$	-	\$	1,160,323.99
2023	\$	1,254,406.66	\$	-	\$	1,254,406.66
Total		\$6,678,317.02		\$5,345,116.26	\$	12,023,433.28


Table IV: 10-Year	Preventative	Maintenance	and Major	Rehabilitation
	The ventative	manificiance	and major	Rendbindation

The success of the repair program for your airport depends on the timely implementation of preservation, localized maintenance and repairs, and major rehabilitation work activities. If work is completed as scheduled, your airport will probably experience an improvement to the overall area-weighted average PCI. Though this analysis was performed with the assumption of an "unlimited budget", the purpose has been to identify specific projects over the course of 10-years for each pavement section where the condition is projected to fall below the critical PCI. The costs depicted in this study are intended to aid the airports in planning level budgets. Prior to construction work, it is recommended that the airport perform additional investigation at the design level to better estimate costs associated with the maintenance, repair, and major rehabilitation activity discussed.



# 1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. The aviation system in Florida allows the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.



There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

The Florida Department of Transportation (FDOT) Aviation and Spaceport Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992. In 2012, the FDOT Aviation and Spaceport Office selected a team led by Kimley-Horn and Associates, Inc. and including Peneul Consulting, LLC, Roy D. McQueen & Associates, LTD, and All About Pavements, Inc., to provide services in support of the Aviation and Spaceport Office Program Manager. The continued evaluation and update of the existing SAPMP is to be completed over fiscal years 2013 and 2014.

This individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance repair and major rehabilitation planning associated with the SAPMP update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

# 1.1 Purpose of Pavement Evaluation Report

The purpose of this Airfield Pavement Evaluation Report is to:

- Describe, briefly, the SAPMP goals, procedures, and responsibilities of the program's participants.
- Provide a brief technical explanation on pavement management principles, standard practices, objectives, and benefits of implementation.
- Outline procedures used to coordinate, collect, evaluate and report pavement inspection results at this airport.
- Analyze and utilize condition results for the development of maintenance, repair, and major rehabilitation based on pavement performance trends.

# 1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the Florida Airports System, identify maintenance and rehabilitation needs at each airport, automate pavement infrastructure information management, and establish standards to address future needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.

During the 1992-1993 implementations and again during the 1998-1999 updates; the SAPMP performed the development of proprietary software for pavement

management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation (M&R) policies, M&R budget costs, and the development of recommendations for performing routine pavement preservation maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER was selected for implementation of the system update. MicroPAVER was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for the purpose of pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER system. This data conversion included all documented pavement facility, classification, type, history, geometry, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In 2006-2008, the SAPMP was updated again with continued use of the MicroPAVER system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (http://www.dot.state.fl.us/aviation/pavement.shtm) was established for input of data.

In 2010-2012, the SAPMP was updated using new GPS integrated technology to digitally collect pavement distress data. Interactive GIS map files were developed from updated Airfield Pavement Network Definition Maps to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the Federal Aviation Administration (FAA) to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6B *Guidelines and Procedures for Maintenance of Airport Pavements*). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year or every three years, if the pavement is inspected in accordance to the PCI survey procedure (such as ASTM International D 5340 *Standard Test Method for Airport Pavement Condition Index Surveys*). The previous 2010-2012 SAPMP update utilized the ASTM D 5340-04 released in 2004, in lieu of the 2010/2011 edition, in order to maintain consistent database integrity and benefit of pavement performance models from previous inspections.

# 1.3 Organization

### FDOT Aviation and Spaceport Office Program Manager

The FDOT Central Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) for the SAPMP. The AO-PM monitors the work performed by the Consultant. The AO-PM has review and approval authority for each program task and manages the day-to-day details of the SAPMP and the pertinent updates.

The AO-PM reports updates and milestones to the FDOT State Aviation Manager and Aviation Development Administrator.

#### Consultant

The Consultant, Kimley-Horn and Associates, Inc. and their team consisting of Peneul Consulting, LLC, Roy D. McQueen & Associates, LTD, and All About Pavements, Inc. provide technical and administrative assistance to the AO-PM during the execution of the update to the SAPMP. The efforts include updating the airport pavement inventory data, performing the condition survey inspections, evaluating the airfield pavement conditions and updating the SAPMP based upon procedures outlined in the FAA Advisory Circular 150/5380-6B Guidelines and Procedures for Maintenance of Airport Pavements and ASTM D 5340.

#### Airport Role

The airports are the ultimate client for each condition survey inspection performed at their respective airfields as part of the SAPMP. The individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP, indicate any construction activity that has been performed since the previous inspections.

#### FDOT District Offices

The seven FDOT District Offices, specifically the Aviation Representatives, provide vital support to the SAPMP update and the AO-PM. Each District supports the SAPMP's on-going efforts of provided representative construction trend costs and practices through the Florida Airports System. Each District Office receives copies of individual Airfield Pavement Evaluation Reports for the airport facilities located within their respective districts.

### 1.4 Introduction to Pavement Types and Pavement Management

#### **Pavement Basics**

A pavement is a prepared surface designed to provide a continuous smooth ride at all taxi, takeoff, and landing speeds and to support an estimated amount of traffic loading for a certain number of years. Pavements are composed of a combination of constructed layers of subgrade soils, subbases, base course material, and surface level courses. There are mainly two types of pavements:

- Flexible Pavement, a composition of bituminous asphalt concrete (AC) surface, base, and subbase layers.
- Rigid Pavement, a composition of Portland Cement Concrete (PCC) surface, base, and subbase layers.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads (both magnitude and repeated application) and protect the underlying subgrade soil. Flexible pavements dissipate applied loads from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements, the PCC layer supports the majority of the structural load applied, and the base or subbase layer is constructed to provide a smooth, level, and continuous platform that provides uniform support for PCC slabs. A small percentage of airfield pavements within the Florida Airports System are composed of hybrid 'composite pavement' sections that may include both AC pavement and PCC pavement. The two known composite pavements are AC surface over PCC (APC) and PCC over AC (White Topping).


Due to the different nature of the pavement types, construction, and their materials; flexible and rigid pavements have different modes of failure and fatigue. This results in varying deterioration and distress development. Understanding the mechanics and modes of failure of the pavement types will assist the engineers in making timely, adequate, consistent, and economical maintenance repairs and major rehabilitation to the pavement structures at each airfield.

### The Concept of an Airfield Pavement Management System

The SAPMP is a program that provides the Florida Airports System an opportunity to implement and/or maintain a proactive Airfield Pavement Management System (APMS) in a consistent manner at a regular schedule. The SAPMP Airfield Pavement Management System consists of pavement inventory, pavement construction and history, condition survey inspections, pavement performance modeling, maintenance recommendations, and major rehabilitation planning. The various elements of the APMS are used by experienced engineers to identify critical pavement preservation pavements, make or rehabilitation recommendations, and approximate pavement performance. The APMS as a whole is used by an airport's stakeholders, managing agencies, engineers, and planners as a tool in decision making for future project planning, budgeting, and scheduling of activities for its airfield pavement infrastructure.

A benefit of an active APMS is it provides an understanding of an airport's pavement performance trends for the purpose of project planning. Based on the performance trend of their pavements, an airport can schedule pavement maintenance and rehabilitation prior to when the pavement section has deteriorated to a condition that would require reconstruction. The use of pavement performance trends will help airports plan M&R and Rehabilitation projects in a manner and sequence that maximizes benefit and minimizes costs. Figure 1-1, which is based upon the FAA Advisory Circular 150 5380-7A Airport Pavement Management Program, illustrates how pavement generally deteriorates over time and the relative cost of rehabilitation and reconstruction throughout its life.

### Figure 1-1: Pavement Life Cycle



Source: FAA Advisory Circular 150 5380-7A Airport Pavement Management Program

Note that during approximately the first 75% of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in 'Good' and 'Satisfactory' conditions depends on how well it is proactively maintained. As the Figure 1-1 demonstrates, the cost of maintaining the pavement above critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Pavements tend to deteriorate at an accelerated rate when actual traffic loading exceeds the original design assumptions and when limited resources are available for maintenance and repair (M&R) efforts. Planned maintenance and rehabilitation, essentially preserving pavements and delaying condition deterioration, help airport (managers, agencies, and engineers) maximize the use of their budgets and prolong the life of their pavements. An APMS provides a tool to schedule planned maintenance and major rehabilitation efforts based on a consistent methodology of condition assessment. This consistent methodology of pavement condition assessment allows for the development of pavement performance models to help forecast future pavement conditions.

Part of the implementation of the APMS is the clear identification and inventorying of pavement infrastructure that needs to be managed specifically within the airport (owner, manager, and agencies) responsibility. Another aspect of the APMS is development of maintenance, repair, and major rehabilitation policies that align with the expectations of pavement performance and are based on ability to fund the types of work identified. Once there is an understanding of the cause and extent of pavement distresses, appropriate maintenance and rehabilitation can be planned. By using representative construction costs based on historic bid trends; planning level budget costs can be developed on a multiyear duration.

#### Airfield Pavement Inspection Methodology for the SAPMP

Pavement condition assessment requires the application of professional judgments regarding the condition of the pavement. The SAPMP airfield pavement condition survey inspections assess pavement, comparing it to a set of standards in ASTM D 5340-11. As part of this update, SAPMP has adopted the changes made in updates to ASTM D 5340-11. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reactivity distress for rigid pavement distresses. The change in distress classification, as described in ASTM D 5340-11, may result in small variances in the PCI values from the previous inspection analysis.

The pavement condition surveys assess the functional condition of the pavement surface based on surface distresses as defined by the ASTM D 5340-11. Typically, deficiencies within a pavement structure will eventually reflect to the pavement surface as distresses described within ASTM D 5340-11. The SAPMP is specifically a visual evaluation and analysis based on the ASTM D 5340-11. The structural condition and relative support of the pavement layers can be directly quantified using non-destructive deflection testing (NDT) as well as other indepth engineering evaluation or sampling and testing methods.

For the SAPMP update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine design level rehabilitation and/or reconstruction needs should the airport proceed to the design process.

In preparation for the PCI survey inspections, the airfield pavements for each airport are divided into branches, sections, and sample units as established by FAA Advisory Circular 150/5380-6B and ASTM D 5340. Further discussion of the process of inventorying and categorizing pavement facilities by use,

composition, and history can be found in SECTION 2 AIRFIELD PAVEMENT NETWORK DEFINITION and PAVEMENT INVENTORY.


Sample units are uniformly divided areas of pavement that are defined for inspection. Sample unit sizes are approximately  $5,000 \pm 2,000$  square feet for flexible AC pavements and  $20 \pm 8$  slabs for rigid PCC pavements. Prior to conducting the field condition survey inspections, the sampling plan was developed for the airfield pavements based on updates to the previous inspection sampling based on the available knowledge of construction updates. The sample rate adopted for the SAPMP is depicted on Table 1-1.

Flexible Pavements Asphalt Concrete			Rigid Pavements Portland Cement Concrete			
	Number of Sample Units to Inspect			Number of Sample Units to Inspect		
Number of Sample Units in Section	Runway	Taxiways, Aprons, Others	Number of Sample Units in Section	Runway	Taxiways, Aprons, Others	
1 - 4	1	1	1 - 3	1	1	
5 - 10	2	1	4 - 6	2	1	
11 - 15	3	2	7 - 10	3	2	
16 - 30	5	3	11 - 15	4	2	
31 - 40	7	4	16 - 20	5	3	
41 - 50	8	5	21 - 30	7	3	
			31 - 40	8	4	
≥ 51	20% but ≤	10% but < 10	41 - 50	10	5	
≥ 51	$10\% \text{ but } \le 10$		≥ 51	20% but ≤ 20	10% but ≤ 10	


### Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections

The sample units to be inspected were determined through a systematic random sampling technique to provide an unbiased representation of sample units for each pavement facility. The sample unit locations had been determined in such a way that they are distributed evenly throughout each defined pavement section area. In certain cases when no representative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from each inspected sample unit are used to compute the PCI value and rating for each Section using the ASTM D 5340-11 and MicroPAVER software. Figures 1-2 and 1-3 depict graphical representations of the color ranges associated with PCI values and ranges with a photograph of airfield pavement that exhibited the conditions for both flexible and rigid pavements respectively.



### Figure 1-2: Flexible Pavement, Asphalt Concrete



Using the ASTM D 5340-11 standard seven qualitative ranges, the SAPMP provides a PCI value and a standard qualitative condition rating for the pavement facilities inspected.



# 2. AIRFIELD PAVEMENT NETWORK DEFINITION AND PAVEMENT INVENTORY

Bob Sikes Airport (CEW) consists of a single runway, Runway 17-35 at 150-ft wide by 8,005-ft long, and a recently rehabilitated 75-ft wide parallel taxiway. The airport apron is located on the west side of the runway and the majority of the apron was also recently rehabilitated and expanded. The airport runway, taxiways and apron are constructed of Asphalt Concrete pavement.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric attributes may vary slightly from the geometry used in the condition exhibit in Appendix B and the major rehabilitation exhibit in Appendix F based on field measurements.

Bob Sikes Airport is publicly owned by Okaloosa County and supports a mix of general aviation and aerospace corporations which work on military aircraft. The airport receives frequent military training use by aircraft based out of many nearby military bases such as Eglin AFB, Duke Field, Hurlburt Field, NAS Pensacola, NAS Whiting Field and Fort Rucker. This airport is designated as a General Aviation airport and is located in District 3 of the Florida Department of Transportation.

### 2.1 Network Definition

The airfield pavements within each airport network are separated into manageable units within the FDOT SAPMP MicroPAVER database system, organizing pavement data by similar use and constructive history.

#### Branch and Section Identification

Each airport's airfield pavement network is generally subdivided into separate Branches (runways, taxiways, aprons/ramps, or others) that have distinctly different functional identifications and uses. Each Branch is further subdivided into Sections as defined by pavement location, composition, and construction history. A Section is typically understood to be a project level subdivision within a Branch feature. Sections are manageable units to organize data collection and are treated individually during the maintenance and major rehabilitation planning process. A pavement rank (primary, secondary, or tertiary) is assigned to each Section based on its importance and type of use to airport operations. The pavement rankings designated for each section at this airport were defined by the previous SAPMP, unless changes were communicated by the airport. These Sections are further subdivided into condition survey sample units based on the methodology described in ASTM D 5340.

#### Airfield Pavement System Inventory and Network Definition Update

The Airfield Pavement System Inventory and Airfield Pavement Network Definition Exhibits are developed individually for each participating airport. Based on information requested of and provided by the airport, the airfield pavements are evaluated on designation updates, and recent or anticipated pavement construction activity. As mentioned previously, a Section is defined partially by its construction history; this variable that factored in the performance and condition of the pavement section.

The Airfield Pavement System Inventory Exhibit, Figure A-2 in Appendix A, is a snapshot of recent and anticipated airfield pavement construction activity communicated by the airport since the last SAPMP update. Construction identified include maintenance activities and repair activity, major rehabilitation, and airfield pavement expansion efforts. Maintenance and repair activity may include; surface treatments, crack sealing, patching, slab replacement, and others. Both maintenance and rehabilitation activities are identified at the pavement section level. This type of work may result in an increase in overall Section PCI since the last inspection. Major rehabilitation efforts may include; asphalt milling and overlay, and full depth pavement reconstruction. This type of effort will result in a resetting of the pavement section PCI value to 100 due to the nature of the work. Lastly, airfield pavement expansions are accounted for as new inventory and assigned a section PCI of 100. Typically the new pavement sections are not inspected due to its condition; however these pavements are incorporated into the SAPMP pavement database. When possible, these changes are reflected in the Airfield Pavement Network Definition Exhibit, in Appendix A, prior to the field inspection. The updates are typically discussed and confirmed with airport personnel at the beginning and end of condition survey inspections to ensure accuracy.

The Airfield Pavement Network Definition Exhibit depicts the airport's pavement limits with Branch and Section delineations. This exhibit also includes the subdivision on Section areas into sample units and is used to identify those sample units that are to be inspected. The previous SAPMP Airfield Pavement Network Definition Exhibits were used as a base. Updates and information provided by each airport was reviewed and the exhibits were revised appropriately. Characteristics that are considered include; airfield configuration, branch designations (magnetic declination, Airport Layout Plan updates) and pavement composition. The exhibit serves not only as a primary guide for the airfield inspectors but also allows specific distresses found in the re-inspection report to be geographically located.

Due to recent and anticipated construction efforts; pavement area sections may have been consolidated and created which will affect the total number of sample units to be inspected based upon the methods described in ASTM D 5340 and from the sampling rate schedule. Table 2-1 summarizes the recent and anticipated airfield pavement construction efforts communicated by the airport.

Construction Year	Section Location	Work Type/Pavement Section
2012	North Apron	REHABILITATION - 1" MILL, AC OVERLAY OVER EXISTING; NEW PCC 432' X 75' SECTION, 10" P-501 PCC, 6" P-304 CEMENT TREATED BASE, 15.5" P-152 SUBGRADE, 12.5" SUBGRADE
2012	Taxiway a and New Aprons	REHABILITATION AND WIDENING OF TAXIWAY A - 1" MILL OF EXISTING VARIABLE OVERLAY. NEW WIDENING PAVEMENT - 4.5" P-401 BITUMINOUS SURFACE COURSE, 8" P-211 LIMEROCK, COMPACTED SUBGRADE

#### Table 2-1: Recent and/or Anticipated Airfield Pavement Construction

### Airfield Pavement Network Definition & Geographic Information System (GIS)

As part of this SAPMP update, geographic information system (GIS), global positioning system (GPS), and digital data collection were integrated into the Pavement Inspection Methodology at each airport. Using AutoCAD Civil 3D, ArcMap, ArcPad, and FDOT Survey and Mapping Office Aerial Photography; digital navigation maps have been developed for each airport to represent the SAPMP pavement inventory attributes. These navigation maps were used with field data tablets to assist survey teams as they performed condition inspections by navigating pavement infrastructure and collecting distress data.


### 2.2 Pavement Inventory

The detailed pavement inventory database was updated to reflect the Airfield Pavement Network Definition Exhibit, in Appendix A, updates and field inspection results. Table 2-2 and Figure 2-1 provides a summary of the pavement inventory attributes at Bob Sikes Airport-(CEW) for this SAPMP update.

Table 2-2. Pavement inventory summary						
Airfield Pavement Network Definition						
Number of Branches	12					
Number of Sections		35				
Sample Units		117				
Airfield	Pavement l	Jse				
Use	Area (SF)	Relative Area (%)				
Runway	1,200,000	38%				
Taxiway	1,108,186	35%				
Apron	850,824	27%				
Total =	3,159,010	100%				
Airfield	Pavement T	ype				
Туре	Area (SF)	Relative Area (%)				
Asphalt Concrete (AC)	1,918,168	60%				
Asphalt Overlay (AAC)	1,185,162	38%				
Portland Cement Concrete (PCC)	55,680	2%				
AC over PCC (APC)	0	0%				

### Table 2-2: Pavement Inventory Summary

Figure 2-1: Airfield Pavement Type



Specific details to each Branch and Section such as; name, geometry, age, rank, surface type, and construction history are provided in Table 2-3.

Branch Name	Branch ID	Section ID	True Area (SF)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
RUNWAY 17-35	RW 17-35	6130	150,000	Р	AC	1/1/2008	5	30
RUNWAY 17-35	RW 17-35	6125	300,000	Р	AC	1/1/2008	12	60
RUNWAY 17-35	RW 17-35	6120	210,000	Р	AC	1/1/2008	8	42
RUNWAY 17-35	RW 17-35	6115	420,000	Р	AC	1/1/2008	18	84
RUNWAY 17-35	RW 17-35	6110	40,000	Р	AC	1/1/2008	2	8
RUNWAY 17-35	RW 17-35	6105	80,000	Р	AC	1/1/2008	5	16
WEST RUN-UP APRON AT RW 17	AP RU	5105	46,560	Р	AAC	11/1/2012	2	10
NORTH APRON	AP N	4355	105,318	Р	AC	11/1/2012	3	22
NORTH APRON	AP N	4350	23,280	Р	PCC	11/1/2012	1	6
NORTH APRON	AP N	4345	99,461	Р	AC	11/1/2012	3	19
NORTH APRON	AP N	4340	33,816	Р	AAC	11/1/2012	1	6
HANGAR APRON	AP HANG	4210	7,104	Р	AC	1/1/1963	1	3
HANGAR APRON	AP HANG	4205	18,010	Р	AC	1/1/1994	1	4
APRON	AP	4130	32,400	Р	PCC	3/1/2012	2	7
APRON	AP	4120	147,645	Р	AAC	3/1/2012	5	27
APRON	AP	4115	187,231	Р	AC	1/1/1987	5	37
APRON	AP	4110	93,750	Р	AC	1/1/1983	3	18
APRON	AP	4105	56,250	Р	AAC	1/1/1980	2	12
ΤΑΧΙΨΑΥ Κ	TW K	605	25,848	Р	AC	3/1/2008	1	8
TAXIWAY PMV	TW PMV	505	75,709	S	AC	1/1/2008	3	15
CONNECTOR TAXIWAYS TO APRON	TW CONN	340	26,273	Р	AAC	11/1/2012	1	5
CONNECTOR TAXIWAYS TO APRON	TW CONN	335	26,207	Р	AAC	11/1/2012	1	5
TAXIWAY A3	TW A3	330	7,151	Р	AAC	11/1/2012	1	2
CONNECTOR TAXIWAYS TO APRON	TW CONN	320	2,982	Р	AAC	11/1/2012	1	1
CONNECTOR TAXIWAYS TO APRON	TW CONN	310	7,038	Р	AAC	11/1/2012	1	2
TAXIWAY A	TW A	160	25,973	Р	AC	11/1/2012	1	5
TAXIWAY A	TW A	150	25,816	Р	AC	11/1/2012	1	5
TAXIWAY A	TW A	140	27,340	Р	AC	11/1/2012	1	5
TAXIWAY A4	TW A4	135	26,609	Р	AC	11/1/2012	1	5
TAXIWAY A4	TW A4	130	53,404	Р	AAC	11/1/2012	2	12

Table 2-3: Airfield Pavement Inventory Details



Branch Name	Branch ID	Section ID	True Area (SF)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
TAXIWAY A	TW A	125	267,093	Р	AAC	11/1/2012	7	68
TAXIWAY A3	TW A3	120	53,835	Р	AAC	11/1/2012	2	12
TAXIWAY A2	TW A2	115	54,612	Р	AAC	11/1/2012	2	12
TAXIWAY A	TW A	110	303,843	Р	AAC	11/1/2012	9	81
TAXIWAY A	TW A	105	98,453	Р	AAC	11/1/2012	3	22

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER. \* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

# 3. AIRFIELD PAVEMENT CONDITION

Airfield pavement distresses and condition were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6B and ASTM D 5340-11. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating.

The program has been updated from ASTM D 5340-04, released in 2004, to ASTM D 5340-11, released in 2011, for this SAPMP update. The primary updates include the separation of certain distress types and the addition of new types with corresponding changes to PCI calculation. These changes in distress classification may result in small variances in the PCI values from the previous inspection analyses.

## 3.1 Inspection Methodology

A pavement condition survey inspection is performed by measuring the amount and severity of defined pavement distresses observed within the boundaries of sample units. These distresses, as defined by ASTM D 5340, are generally caused by traffic fatigue loading, exposure to climate and elements, and other airfield specific factors. This data is collected by field personnel experienced in pavement condition survey inspection. Data collection is then transferred into the FDOT MicroPAVER database system. MicroPAVER is used to calculate PCI values using the methodology described in ASTM D 5340-11. The values are calculated for each sample and extrapolated on a Section level to determine an area-weighted PCI value ranging from 0 to 100 and one of seven condition ratings. Tables 3-1 and 3-2 describe the distresses as defined by the ASTM D 5340-11 and adopted for the SAPMP procedures.

Code	Distress	Primary Mechanisms
41	Alligator Cracking	Load / Fatigue Failure
42	Bleeding	Construction Quality/ Mix Design
43	Block Cracking	Climate / Age
44	Corrugation	Load / Construction Quality
45	Depression	Subgrade Quality
46	Jet Blast	Aircraft
47	Joint Reflection - Cracking	Climate / Prior Pavement
48	Longitudinal/Transverse Cracking	Climate / Age
49	Oil Spillage	Aircraft / Vehicle
50	Patching	Utility / Pavement Repair
51	Polished Aggregate	Repeated Traffic Loading
52	Raveling	Climate / Load
53	Rutting	Repeated Traffic Loading
54	Shoving	PCC Pavement Growth / Movement
55	Slippage Cracking	Load / Pavement Bond
56	Swelling	Climate / Subgrade Quality
57	Weathering	Climate

### Table 3-1: Airfield Pavement Distresses for Asphalt Concrete

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

Code	Distress	Primary Mechanisms
61	Blow-up	Climate / Alkali Silica Reaction
62	Corner Break	Load Repetition / Curling Stresses
63	Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
64	Durability Cracking	Freeze-Thaw Cycling
65	Joint Seal Damage	Material Deterioration / Construction Quality
66	Small Patch	Pavement Repair
67	Large Patch/Utility Cut	Utility / Pavement Repair
68	Popout	Freeze-Thaw Cycling
69	Pumping	Load Repetition / Poor Joint Sealant
70	Scaling/Crazing	Construction Quality / Freeze- Thaw Cycling
71	Faulting	Load Repetition / Subgrade Quality
72	Shattered Slab	Overloading
73	Shrinkage Cracking	Construction Quality / Load
74	Joint Spalling	Load Repetition / Infiltration of Incompressible Material
75	Corner Spalling	Load Repetition / Infiltration of Incompressible Material
76	Alkali-Silica Reaction	Construction Quality / Climate

	D		<b>D</b>	
lable 3-2: Alffield	Pavement	Distresses to	or Portland	Cement Concrete

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

# 3.2 Airfield Pavement Condition Index Rating Results

From the condition survey inspection performed in 2013 at Bob Sikes Airport, the overall weighted average PCI value is 87 representing a condition rating of GOOD.

The airport's airfield pavements exhibited distresses typically associated with climate and age based distresses. The predominant AC and AAC pavement distresses observed include: weathering, raveling, swelling, oil spillage, patching, block cracking, and longitudinal/transverse cracking.

Runway 17-35 exhibited low severity weathering and longitudinal/transverse cracking with isolated locations of low severity raveling. The majority of the longitudinal/transverse cracking was within the first 2,000' of either end of the runway, where most of the cracking was occurring at the pavement joints.

The entire taxiway and associated connectors were rehabilitated in late 2012 with both mill and overlay rehabilitation along with new pavement construction due to the updated geometry per the new Advisory Circular along with widening the parallel taxiway from being 50' wide to 75' wide. This pavement was not inspected based on its recent construction but has been incorporated in the network definition map so it is a part of the overall pavement network for future inspections.

The majority of the apron pavement was also rehabilitated and expanded during the same timeframe as the parallel taxiway construction. This pavement was also not inspected based on its recent construction but has been incorporated in the network definition map so it is a part of the overall pavement network for future inspections.

The portions of the apron that were inspected were located towards the southwest side of the airfield. These pavement sections were significantly aged which was reflected in the pavement distresses that were found. These pavement sections exhibited distresses such as low and medium severity block cracking, longitudinal/transverse cracking, swelling, raveling, and patching.

Appendix B contains Table B-1 and an Airfield Pavement Condition Index Rating Exhibit, Figure B-1, which depicts the PCI results by Section, and Appendix C contains MicroPAVER reports of PCI results by Branch and Section. Appendix H includes detailed distress data generated by MicroPAVER for each inspected sample unit.

The pavement condition at Bob Sikes Airport is represented in Figure 3-1 in accordance with the condition categories and PCI scale referenced in ASTM D 5340. Further detail is provided in Table 3-3 which describes the breakdown of the airport's airfield conditions according to area and use.

Appendix B contains Table B-1 summarizes the Section Condition values and the Airfield Pavement Condition Index Rating Exhibit, Figure B-1, that depicts the PCI results by Section. Appendix H is dedicated to the reporting of the specific

airfield pavement distress data collected at the time of the inspection for this update.





Figure 3-1: Airfield Pavement Condition Index Rating Summary

Table 3-3: Pavement Condition index Rating Summary						
Airfield Pavement Use						
Use	Average Area- Weighted PCI	Condition Rating				
Runway	87	GOOD				
Taxiway	99	GOOD				
Apron	71	SATISFACTORY				
	Condition Area					
Condition Rating	Area (SF)	Relative Area (%)				
Good	2,266,666	71%				
Satisfactory	530,000	17%				
Fair	18,010	1%				
Poor	-	0%				
Very Poor	337,231	10%				
Serious	7,104	1%				
Failed	-	0%				


### Table 3-3: Pavement Condition Index Rating Summary


Approximately 88% of the airfield network is in Good and Satisfactory condition; while 11% of the network is in a Poor to Serious condition. Table 3-3 provides a breakdown of total area for each pavement by condition rating. Figures 3.2 a, b, c depict the condition rating of the airfield pavement by Branch Use. Photographs taken during the condition survey inspection are included in Appendix G. The photographs included are intended to be representative of the distress observed.

Figure 3-2: Percentage of Pavement Area by Condition Rating by Use



### (b) Taxiway





## 4. PAVEMENT PERFORMANCE

Pavement performance models are developed from the distress data collected for the SAPMP for the Florida Airports System. This data is consolidated in a database and organized by inspection date, pavement type, age, pavement use, and airport category. The pavement performance models are used to develop broad prediction models, also known as pavement condition deterioration curves.

The consolidation of the Florida Airports System's pavement infrastructure within the FDOT SAPMP is based on data that have been collected in a consistent method of measurement. The historic pavement condition, or performance trend, has been compiled throughout the system with data from the inception of the SAPMP. This data is processed into models that have been analyzed and developed into prediction curves based upon pavement characteristics. These characteristics include; climate, construction material, and operations. Each model has been developed based on the following criteria:

AIRPORT TYPE (Primary, Regional Reliever, or General Aviation)


>FACILITY USE (Runway, Taxiway, or Apron)

>>FACILITY SURFACE TYPE (AC, AAC, APC, or PCC)


The historic trends of pavement performance at Florida airport facilities for all performance models are consolidated within the program database. This information is utilized in the prediction of pavement performance based on the current PCI determined from the inspections that took place between 2013 and 2014. Major rehabilitation is planned based on the predicted PCI. The intent of this is for both the individual airport and the FDOT District personnel to be aware of anticipated major rehabilitation work based on condition.

Each airport's airfield pavement section condition, for a given inspection year, is one data point that was used as the basis of each performance trend using a performance model based on pavements of similar background. Figures 4-1, 4-2, and 4-3 represent the pavement performance prediction at Bob Sikes Airport based on pavement use. Each figure depicts the FDOT recommended Minimum Service Level PCI value for each pavement type.





### Figure 4-2: Taxiway Pavement Performance Prediction Summary






Figure 4-3: Apron Pavement Performance Prediction Summary

Pavement performance modeling to predict the future PCI is primarily done to predict PCI at the Section level for the purpose of planning Major Rehabilitation work. In Appendix D, Table D-1 represents the predicted area-weighted PCI by Section for the airport's airfield pavement infrastructure.

#### 5. AIRFIELD PAVEMENT MAINTENANCE POLICIES AND COSTS

#### 5.1 Policies


Airfield Pavement Maintenance policies are guidance on pavement construction methods used to develop, maintain, repair, and rehabilitate pavement infrastructure based on distresses encountered during the condition surveys.

Maintenance refers to the repair and preservation-type activities that are applied locally to specific distress types on the pavement. These activities for the SAPMP are considered preventative and corrective in nature and are highly recommended to help improve pavement performance and extend pavement life. The SAPMP maintenance policies are based on the FAA Advisory Circular 150/5380-6B and guidance provided in the FDOT Airfield Pavement Repair Manual.

For the purpose of the SAPMP; the maintenance repair needs that are identified and quantified are based solely on the pavement distresses observed and recorded at the time of the inspection. Based on a specific distress type and severity observed, a particular repair work type is recommended and quantified based on the extrapolated section distresses. The repair program identified is specific to the current distresses. Future maintenance planning budgets are based on this initial determination. Tables 5-1 and 5-2 provide the list of maintenance activities incorporated into the SAPMP MicroPAVER database to treat specific distress types and severities.

Surface Type	Distress Code	Distress Name	Severity	Maintenance Work Type	Work Unit
	41	Alligator Cracking	L, M, H	Full Depth Pavement Patch	Square Feet
	42	Bleeding	N/A	Partial Depth Pavement Patch	Square Feet
	43	Block Cracking	L	Seal Coat Treatment	Square Feet
	43	Block Cracking	M, H	Full Depth Pavement Patch	Square Feet
	44	Corrugation	L, M, H	Full Depth Pavement Patch	Square Feet
	45	Depression	L, M, H	Full Depth Pavement Patch	Square Feet
	46	Jet Blast Erosion	L, M, H	Full Depth Pavement Patch	Square Feet
	47	Joint Reflection Cracking	L	Crack Sealing	Linear Feet
Ð	47	Joint Reflection Cracking	M, H	Full Depth Pavement Patch	Square Feet
ncret C)	48	Longitudinal/Transverse Cracking	L, M, H	Crack Sealing	Linear Feet
le Asphalt Con (AC, AAC, APC)	49	Oil Spillage	L, M	Seal Coat Treatment	Square Feet
Asph. C, AA	49	Oil Spillage	Н	Full Depth Pavement Patch	Square Feet
Flexible Asphalt Concrete (AC, AAC, APC)	50	Patch and Utility Patching	М	Crack Sealing	Linear Feet
Fle	50	Patch and Utility Patching	Н	Full Depth Pavement Patch	Square Feet
	51	Polished Aggregate	L, M, H	Slurry Seal Coat Treatment	Square Feet
	52	Raveling	L, M	Slurry Seal Coat Treatment	Square Feet
	52	Raveling	Н	Partial Depth Pavement Patch	Square Feet
	53	Rutting	L, M, H	Full Depth Pavement Patch	Square Feet
	54	Shoving	L, M, H	Grinding / Removal	Square Feet
	55	Slippage Cracking	L, M, H	Full Depth Pavement Patch	Square Feet
	56	Swelling	M, H	Full Depth Pavement Patch	Square Feet
	57	Weathering	M, H	Seal Coat Treatment	Square Feet

#### Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy



#### Table 5-2: Recommended PCC Maintenance and Repair Policy

Surface Type	Distress Code	Distress Name	Severity	Maintenance Work Type	Work Unit
	73	Shrinkage Cracks	N/A	Crack Sealing - PCC	Linear Feet
	74	Longitudinal/Transverse Joint Spalling	L, M, H	Partial Patch - PCC	Square Feet
	75	Corner Spalling	L, M, H	Partial Patch - PCC	Square Feet
	76	Alkali-Silica Reaction	L	Seal Coat Treatment	Square Feet
	76	Alkali-Silica Reaction	М	Micro-mill and Seal - PCC	Square Feet
	76	Alkali-Silica Reaction	Н	Slab Replacement / Full Depth Patch	Square Feet

Though proactive pavement maintenance and preservation is highly recommended in an APMS; it is recognized that pavement that has deteriorated below a certain PCI will require a major rehabilitation rather than localized maintenance and repair work. Major rehabilitation is recommended when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that maintenance repair efforts are no longer cost-efficient. This critical point is called "Critical PCI". The critical PCI levels for different pavement and branch types were established by the FDOT and were used in this update to develop a maintenance and major rehabilitation plan for the airport. Sections that are above the "Critical PCI" levels will be recommended for maintenance, repair, and preservation treatments, assuming there are no significant load-related distresses. For those Sections below the Critical PCI, the recommended action will consist of major rehabilitation work. This approach is used for the current Section's PCI value and the predicted PCI value for future rehabilitation.

The FDOT has recommended minimum service level PCI for airports based on pavement facility use, airport type, and expected loading frequency. This minimum service level PCI is recommended to ensure the pavement provides a safe operational surface and efficiently uses maintenance and rehabilitation budgets. Separately, the Critical PCI is a value based on historic pavement performance trends and costs. It is at a PCI value of 65, for most airports, at which major rehabilitation is recommended over maintenance level efforts. Table 5-3 identifies the FDOT recommended PCI by use and the critical PCI value for the most important pavements at the airport. This is due to the condition of the pavement and the cost effectiveness of the work. A very important concept of a good pavement management system is the proactive preservation of pavements that are above Critical PCI condition. Conversely, allowing pavement to deteriorate beyond maintenance and performing "worst first" major rehabilitation may cost much more over the life of a pavement.

Use	FDOT Recommended PCI	Critical PCI
Runway	75	65
Taxiway	65	65
Apron	60	65

Table 5-3: Critical and Minimum Service Level PCI for General Aviation Airports

Based on historic trends of pavement performance and industry standard practices in pavement maintenance and rehabilitation, the SAPMP included general guidance on construction activity based on condition PCI, as shown on Table 5-4. It is recommended that further investigation of underlying pavement conditions is performed at the design phase.

Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI

Category	Activity	PCI Range
	<ul> <li>Crack Sealing (AC/PCC)</li> </ul>	
Maintenance	<ul> <li>Partial Depth Patching (AC)</li> </ul>	75 00
Maintenance	<ul> <li>Full Depth Patching (AC/PCC)</li> </ul>	75 - 90
	<ul> <li>Surface Treatment (AC)</li> </ul>	
	<ul> <li>Mill and Overlay (AC)</li> </ul>	
Rehabilitation	<ul> <li>Concrete Pavement Restoration (PCC)</li> </ul>	40 - 74
	<ul> <li>Full Depth Pavement Reconstruction</li> </ul>	0 - 39

The PCI standard scale ranges from a value of 0, typically representing a pavement in a failed condition, to a value of 100 which typically represents a pavement in new or good condition. Generally, airfield pavement sections with



a PCI of 75 or higher that are not exhibiting distresses due to aircraft loading will benefit from maintenance activities such as crack sealing, patching, and surface treatments. Pavement sections with PCI values within the range of 40 to 74 may require major rehabilitation, such as a mill and overlay. Lastly, pavement sections with a PCI value of 40 or less are recommended to undergo pavement reconstruction. Generally pavement reconstruction is the only practical means of restoration due to the substantial distresses observed in the pavement structure. Since PCI values are based solely on the visual determination of pavement distresses and deterioration, this method does not provide a direct measure of structural integrity.

#### 5.2 Unit Costs

The FDOT SAPMP developed and updated the maintenance and major rehabilitation costs based on public cost databases for airport and highway pavement construction. Additionally, cost data collected from FDOT and FAA sponsored projects in the Florida Airports System were utilized to identify construction cost trends across the state.

The maintenance, repair, and preservation activity costs have been updated and developed using readily available construction cost data at the time of this update. The costs depicted in this report for both maintenance and major rehabilitation are intended for planning purposes.

#### 5.3 Maintenance, Repair, and Major Rehabilitation

FDOT recognizes that although pavement mill and overlay is recommended for flexible asphalt concrete pavement within a PCI range from 40 to 74, it is conceivable that airports may not have adequate funding to perform this type of major rehabilitation. A comprehensive surface treatment; such as GSB-88 and Microsurfacing, as a maintenance rehabilitation activity, can be used in lieu of asphalt concrete pavement mill and overlay. However, it should be understood that these measures provide only a short term extension of pavement life. While the cost of surface treatments are significantly lower than that of pavement mill and overlay, it is not intended or implied to be a full rehabilitative measure for long term benefit. Table 5-5 and Table 5-6 provide budget costs associated with the work types shown in the table.

Surface Type	Maintenance Work Type	Cost	Work Unit
	Full Depth Pavement Patch	\$5.00	Square Feet
ncrete C)	Partial Depth Pavement Patch	\$3.00	Square Feet
alt Co C, AP(	Seal Coat Treatment	\$0.55	Square Feet
e Asph C, AA	Crack Sealing	\$2.75	Linear Feet
Flexible Asphalt Concrete (AC, AAC, APC)	Slurry Seal Coat Treatment	\$0.55	Square Feet
	Grinding / Removal	\$2.10	Square Feet

#### Table 5-5: AC Maintenance Unit Costs

#### Table 5-6: PCC Maintenance Unit Costs

Surface Type	Maintenance Work Type	Cost	Work Unit
	Slab Replacement / Full Depth Patch	\$45.00	Square Feet
	Partial Patch - PCC	\$19.10	Square Feet
nent	Crack Sealing - PCC	\$4.25	Linear Feet
Rigid Pavement (PCC)	Joint Seal Repair (Local)	\$3.00	Linear Feet
Rigid	Slab Stabilization / Slab Jacking	\$45.00	Square Feet
	Micro-mill and Seal - PCC	\$1.00	Square Feet
	Seal Coat Treatment	\$1.00	Square Feet

As part of the SAPMP update, the distress data observed at each airport during the inspection is extrapolated on a section basis to make maintenance recommendations. These recommendations are a direct result of the distress types, severities, and quantities observed at the time of inspection. The maintenance recommendations and planning costs are correlated with the airport's airfield pavement network's overall area weighted PCI and used to plan future maintenance costs. Future maintenance costs are planning budgets that are not specific to a pavement section, but are estimates for the entire airfield. Table 5-7 provides budget costs associated with the rehabilitation activities.

Category	Activity	PCI Range	Cost/SqFt
	<ul> <li>Mill and Overlay (AC)</li> </ul>		\$8.00
Rehabilitation	<ul> <li>Concrete Pavement Restoration (PCC)</li> </ul>	40 - 74	\$10.00
	Full Depth Pavement Reconstruction	0 - 39	\$15.00

## Table 5-7: Rehabilitation Activities and Unit Costs by Condition for GeneralAviation Airports

A cost scale has been developed based on PCI to develop planning level budgets for the airfield pavements. The cost scale is adjusted by project year based on an assumed inflation rate of 3%. In Appendix E, Table E-1 summarizes the Year-1 maintenance and repair recommendations based on the most recent inspection. The summary in Table E-1 does not take into account any rehabilitation activities, but rather summarizes preventative activities for all PCI ranges, including below critical PCI sections.

#### 6. MAJOR PAVEMENT REHABILITATION NEEDS

As part of the SAPMP, major pavement rehabilitation planning is developed based on current and predicted PCI in comparison with the Critical PCI. The Critical PCI has been determined based on the historic trends of pavement condition relative to the benefit of maintenance and repair activities. Pavement sections determined to have a PCI less than that of the Critical PCI are assumed to have deteriorated to a point at which maintenance and repair level activity would provide little benefit.

The objective of the major pavement rehabilitation needs analysis is to provide planning level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value from a functionality perspective. In addition, major rehabilitation is also recommended when the Section PCI is above the Critical PCI but the Section has load-related PCI distresses. However, most major rehabilitation work is recommended when the Section PCI is below the Critical PCI, which is when maintenance and repair level activities are not considered to be cost effective.


Major rehabilitation is identified within the SAPMP as major construction activity that would result in an improvement or "resetting" of the pavement section's PCI to a value of 100. Such activities could include; mill and hot-mix asphalt overlay and re-construction. This analysis was conducted with no constraints to budgets as a means to identify all pavement projects based on Critical PCI for a 10-year duration. It is recommended that the airport use this as a planning tool for future project development and prioritization. Table 6-1 depicts the major rehabilitation work identified on the pavement section level based on current and predicted pavement PCI.

Year	Branch ID	Section ID	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2014	AP HANG	4210	\$106,552.98	18	Reconstruction	100
2014	AP HANG	4205	\$180,101.89	62	Mill and Overlay	100
2014	AP	4115	\$2,808,460.86	32	Reconstruction	100
2014	AP	4110	\$1,406,250.33	30	Reconstruction	100
2014	AP	4105	\$843,750.20	37	Reconstruction	100
		Total =	\$5,345,116.26			

#### Table 6-1: Summary of Major Rehabilitation

\* Costs are adjusted for inflation AT 3%

The 10-year major rehabilitation program addresses those pavement sections that have a current or project PCI that is below the Critical PCI of 65 during the 10-year analysis period. The unconstrained or "unlimited budget" Major Rehabilitation Program is compared to a "No Major Rehabilitation Program" scenario in Figure 6-1. As shown, if no major rehabilitation work is completed in the next 10 years at your airport, the average PCI may be 6 points less than a plan that provides timely repairs to the airfield pavements.






#### 7. PREVENTATIVE AND MAJOR REHABILITATION PLANNING

The preventative and major rehabilitation results include activities that are based on distresses observed and unconstrained by budget limits. FDOT recognizes that the projects identified as Year-1 needs in 2013, based on condition, may exceed a typical annual budget level. It is recommended that each airport further evaluate each project's feasibility and desirability based on the airport's future development plans and budgeting scenarios.

In an effort to identify appropriate budget levels, the 10-year Preventative and Major Rehabilitation analysis evaluated projected budget needs based on predicted PCI of each pavement section. Table 7-1 and Figure 7-1 provides a summary of the expected preventative and major rehabilitation for each program year.

Program Year	Preventative	Major Rehabilitation		Total Year Costs
2014	\$ 93,949.13	\$	5,345,116.26	\$ 5,439,065.39
2015	\$ 142,722.24	\$	-	\$ 142,722.24
2016	\$ 240,648.93	\$	-	\$ 240,648.93
2017	\$ 426,777.85	\$	-	\$ 426,777.85
2018	\$ 606,072.87	\$	-	\$ 606,072.87
2019	\$ 776,398.50	\$	-	\$ 776,398.50
2020	\$ 923,913.36	\$	-	\$ 923,913.36
2021	\$ 1,053,103.49	\$	-	\$ 1,053,103.49
2022	\$ 1,160,323.99	\$	-	\$ 1,160,323.99
2023	\$ 1,254,406.66	\$		\$ 1,254,406.66
			Total =	\$ 12,023,433.28

Table 7-1: 10-Year Preventative and Major Rehabilitation Summary



#### Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary

According to the most recent inspections at the time of this update; the following pavement sections were identified as a Year-1 need for major rehabilitation:

- Hangar Apron Section 4210
  - Reconstruction attributed to distresses related to subgrade quality, climate, and age of pavement.
- Hangar Apron Section 4205
  - Mill and Overlay attributed to distresses related to climate and age of pavement.
- Apron Section 4115, 4110, and 4105
  - Reconstruction attributed to distresses related to subgrade quality, climate, and age of pavement.

Appendix E summarizes the preventative repair recommendations for Year-1 and Appendix F provides an exhibit, Airfield Pavement Major Rehabilitation, that depicts the recommended major rehabilitation on the airfield pavement network according to work type and year.

#### 8. VISUAL AID EXHIBITS

#### 8.1 Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit in Appendix A depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D 5340-11. The exhibits are prepared and updated with information provided by the airport and from aerial imagery from the FDOT Surveying and Mapping publications.

#### 8.2 Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in Appendix A depicts any recent airfield pavement construction activity reported by the airport. The exhibit is intended to identify pavement sections that may have changed in geometry and pavement composition that would affect the section delineation. The information provided in the Airport Response Form was used as the basis of the changes and confirmed with the airport personnel at the time of inspection.

#### 8.3 Airfield Pavement Condition Index Rating Exhibit

The Airfield Pavement Condition Index Rating Exhibit in Appendix B has been prepared based on the section condition analysis of the distress data collected during the recent condition index rating survey. The exhibit graphically depicts the inventory with associated condition rating colors and PCI values.

#### 8.4 Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit in Appendix F has been prepared based on the section pavement performance model and major rehabilitation analysis. The exhibit graphically depicts the inventory with associated rehabilitation activity, program year, and the planning level costs.

#### 8.5 Airfield Pavement Condition Survey Inspection Photographs

During the field condition survey inspection; inspectors photographed representative distress types observed. Select photographs are provided in Appendix G to provide visual support to special pavement conditions or distresses observed.


#### 9. **RECOMMENDATIONS**


The following recommendations were made based on the 2013 condition survey inspection, condition analysis, and maintenance/rehabilitation analysis results:

- Hangar Apron Section 4210
  - Reconstruction attributed to distresses related to subgrade quality, climate, and age of pavement.
- Hangar Apron Section 4205
  - Mill and Overlay attributed to distresses related to climate and age of pavement.
- Apron Section 4115, 4110, and 4105
  - Reconstruction attributed to distresses related to subgrade quality, climate, and age of pavement.

# APPENDIX A

- AIRFIELD PAVEMENT NETWORK DEFINITION EXHIBIT
- AIRFIELD PAVEMENT SYSTEM INVENTORY EXHIBIT
- PAVEMENT GEOMETRY INVENTORY
- WORK HISTORY REPORT





FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE

3

Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
RUNWAY 17-35	RW 17-35	RUNWAY	6130	6,000	25	150,000	Р	AC	1/1/2008	8/27/2013	30
RUNWAY 17-35	RW 17-35	RUNWAY	6125	3,000	100	300,000	Р	AC	1/1/2008	8/27/2013	60
RUNWAY 17-35	RW 17-35	RUNWAY	6120	8,400	25	210,000	Р	AC	1/1/2008	8/27/2013	42
RUNWAY 17-35	RW 17-35	RUNWAY	6115	4,200	100	420,000	Р	AC	1/1/2008	8/27/2013	84
RUNWAY 17-35	RW 17-35	RUNWAY	6110	1,600	25	40,000	Р	AC	1/1/2008	8/27/2013	8
RUNWAY 17-35	RW 17-35	RUNWAY	6105	800	100	80,000	Р	AC	1/1/2008	8/27/2013	16
WEST RUN-UP APRON AT RW 17	AP RU	APRON	5105	415	100	46,560	Р	AAC	11/1/2012	11/1/2012	10
NORTH APRON	AP N	APRON	4355	660	155	105,318	Р	AC	11/1/2012	11/1/2012	22
NORTH APRON	AP N	APRON	4350	150	155	23,280	Р	PCC	11/1/2012	11/1/2012	6
NORTH APRON	AP N	APRON	4345	641	155	99,461	Р	AC	11/1/2012	11/1/2012	19
NORTH APRON	AP N	APRON	4340	330	100	33,816	Р	AAC	11/1/2012	11/1/2012	6
HANGAR APRON	AP HANG	APRON	4210	350	20	7,104	Р	AC	1/1/1963	8/27/2013	3
HANGAR APRON	AP HANG	APRON	4205	350	35	18,010	Р	AC	1/1/1994	8/27/2013	4
APRON	AP	APRON	4130	432	75	32,400	Р	PCC	3/1/2012	3/1/2012	7
APRON	AP	APRON	4120	730	185	147,645	Р	AAC	3/1/2012	3/1/2012	27
APRON	AP	APRON	4115	1,350	100	187,231	Р	AC	1/1/1987	8/27/2013	37
APRON	AP	APRON	4110	625	150	93,750	Р	AC	1/1/1983	8/27/2013	18
APRON	AP	APRON	4105	375	150	56,250	Р	AAC	1/1/1980	8/27/2013	12
ΤΑΧΙΨΑΥ Κ	TW K	TAXIWAY	605	500	35	25,848	Р	AC	3/1/2008	8/27/2013	8
TAXIWAY PMV	TW PMV	TAXIWAY	505	1,450	50	75,709	S	AC	1/1/2008	8/27/2013	15
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	340	127	40	26,273	Р	AAC	11/1/2012	11/1/2012	5
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	335	113	90	26,207	Р	AAC	11/1/2012	11/1/2012	5
TAXIWAY A3	TW A3	TAXIWAY	330	95	40	7,151	Р	AAC	11/1/2012	11/1/2012	2

Table A-1: Pavement Geometry Inventory



#### Pavement Evaluation Report - Bob Sikes Airport

Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Total Samples
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	320	55	40	2,982	Р	AAC	11/1/2012	11/1/2012	1
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	310	75	40	7,038	Р	AAC	11/1/2012	11/1/2012	2
TAXIWAY A	TW A	TAXIWAY	160	150	130	25,973	Р	AC	11/1/2012	11/1/2012	5
TAXIWAY A	TW A	TAXIWAY	150	150	130	25,816	Р	AC	11/1/2012	11/1/2012	5
TAXIWAY A	TW A	TAXIWAY	140	150	130	27,340	Р	AC	11/1/2012	11/1/2012	5
TAXIWAY A4	TW A4	TAXIWAY	135	150	130	26,609	Р	AC	11/1/2012	11/1/2012	5
TAXIWAY A4	TW A4	TAXIWAY	130	250	130	53,404	Р	AAC	11/1/2012	11/1/2012	12
TAXIWAY A	TW A	TAXIWAY	125	3,700	50	267,093	Р	AAC	11/1/2012	11/1/2012	68
TAXIWAY A3	TW A3	TAXIWAY	120	300	50	53,835	Р	AAC	11/1/2012	11/1/2012	12
Taxiway A2	TW A2	TAXIWAY	115	300	50	54,612	Р	AAC	11/1/2012	11/1/2012	12
TAXIWAY A	TW A	TAXIWAY	110	4,300	50	303,843	Р	AAC	11/1/2012	11/1/2012	81
TAXIWAY A	TW A	TAXIWAY	105	1,200	50	98,453	Р	AAC	11/1/2012	11/1/2012	22

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER. \* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

Date:09/	05/2013		story Re	-	1 of 7
Network: CE L.C.D.: 01/01	EW Bra /1980 Use: AP	anch:AP (APRON) PRON Rank PLength:	375.00 Ft	Width:	Section: 4105 Surface: AAC 150.00 Ft True Area: 56,250.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1980 01/01/1980 01/01/1963	IMPORTED IMPORTED IMPORTED	OVERLAY OVERLAY BUILT		4.00 6.00	True SOIL: SP
Network: CE L.C.D.: 01/01	EW Bra /1983 Use: AP	anch:AP (APRON) PRON Rank PLength:	625.00 Ft	Width:	<b>Section:</b> 4110 <b>Surface:</b> AC 150.00 Ft <b>True Area:</b> 93.750.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1983 01/01/1983	IMPORTED IMPORTED	OVERLAY BUILT		4.00	True SOIL: SP True 1983: P-625 SEAL ON 4" P-401 ON 6" P-209 ON 4" SUBBASE (P-154?)
Network: CE L.C.D.: 01/01	EW Bra /1987 Use: AP	anch:AP (APRON) PRON Rank PLength:	1,350.00 Ft	Width:	<b>Section:</b> 4115 <b>Surface:</b> AC 100.00 Ft <b>True Area:</b> 187,230.68 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1987	IMPORTED	BUILT		4.00	True 1987: P-625 SEAL ON 4" P-401 ON 6" P-209 ON 4" P-154 True SOIL: SP
Network: CE	EW Bra /2012 Use: AP	anch:AP (APRON) RON Rank PLength:	730.00 Ft	Width:	<b>Section:</b> 4120 <b>Surface:</b> AAC 185.00 Ft <b>True Area:</b> 147,645.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
03/01/2012 01/01/1984	ML-OV IMPORTED	Mill and Overlay BUILT	\$0	0.00	True 1" MILL, 3.5" OVERLAY MAX P-401 True ESTIMATE 1984 AC PAVEMENT
Network: CE L.C.D.: 03/01	EW Bra /2012 Use: AP	anch:AP (APRON) PRON Rank PLength:	432.00 Ft	Width:	<b>Section:</b> 4130 <b>Surface:</b> PCC 75.00 Ft <b>True Area:</b> 32,400.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
03/01/2012	NU-IN	New Construction - Initial	\$0	10.00	True 10" P-501, 6" P304, 15.5" P-152
Network: CE L.C.D.: 01/01	EW Bra /1994 Use: AP	• -	R APRON <b>)</b> 350.00 Ft	Width:	<b>Section:</b> 4205 <b>Surface:</b> AC 35.00 Ft <b>True Area:</b> 18.010.19 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1994	IMPORTED	BUILT			True ESTIMATE 1994 AC PAVEMENT
Network: CE L.C.D.: 01/01	EW Bra /1963 Use: AP	•	R APRON <b>)</b> 350.00 Ft	Width:	<b>Section:</b> 4210 <b>Surface:</b> AC 20.00 Ft <b>True Area:</b> 7.103.53 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1963	IMPORTED	BUILT			True ESTIMATED 1963 AC PAVEMENT
Network: CE L.C.D.: 11/01	EW Bra /2012 Use: AP	anch: APN (NORTH PRON Rank P Length:	APRON <b>)</b> 330.00 Ft	Width:	<b>Section:</b> 4340 <b>Surface:</b> AAC 100.00 Ft <b>True Area:</b> 33,815.64 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
11/01/2012 01/01/1987 01/01/1987	ML-OV IMPORTED IMPORTED	Mill and Overlay OVERLAY BUILT	\$0	0.00 1.50	True SOIL: SP

Date:09/	/05/2013		story Re t Database:FD	-	2 of 7
<b>Network:</b> C	EW Br	anch: APN (NORTH)	APRON <b>)</b>	Width:	Section: 4345 Surface: AC
L.C.D.: 11/07	1/2012 Use: AP	PRON Rank PLength:	641.00 Ft		155.00 Ft True Area: 99,461.38 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012	NU-IN	New Construction - Initial	\$0	5.00	True 5" P-401, 8" P-211, 17" P-152
<b>Network:</b> C	EW Br	anch: APN (NORTH)	APRON <b>)</b>	Width:	<b>Section:</b> 4350 <b>Surface:</b> PCC
<b>L.C.D.:</b> 11/01	1/2012 Use: AF	PRON Rank PLength:	150.00 Ft		155.00 Ft <b>True Area:</b> 23.279.79 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012	NU-IN	New Construction - Initial	\$0	10.50	True 10.5" P-501, 6" P-209, 15.5" P-152
Network: C	EW Bra	anch: APN (NORTH)	APRON <b>)</b>	Width:	<b>Section:</b> 4355 <b>Surface:</b> AC
L.C.D.: 11/07	1/2012 Use: AF	PRON Rank PLength:	660.00 Ft		155.00 Ft <b>True Area:</b> 105,318.32 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012	NU-IN	New Construction - Initial	\$0	5.00	True 5" P-401, 8" P-211, 17" P-152
<b>Network:</b> C	EW Bra	-	UN-UP APRON A	TRW17)	<b>Section:</b> 5105 <b>Surface:</b> AAC
<b>L.C.D.:</b> 11/07	1/2012 Use: AF		415.00 Ft	Width:	100.00 Ft <b>True Area:</b> 46.559.69 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		( in)	M&R Comments
11/01/2012 01/01/1996	ML-OV IMPORTED	Mill and Overlay BUILT	\$0	0.00 4.00	True         1" MILL, 2" OVERLAY P-401           True         1996 4" P401 ON 13" P209 ON 12" P154           ON P152
<b>Network:</b> C	EW Br	anch:RW17-35 (RUNWA)	Y 17-35 <b>)</b>	Width:	<b>Section:</b> 6105 <b>Surface:</b> AC
<b>L.C.D.</b> : 01/01	1/2008 Use: RL	JNWAY RankPLength:	800.00 Ft		100.00 Ft <b>True Area:</b> 80,000.00 SqF
Work Date	Work Code	Work Description		Thickness (in)	Major M&R Comments
01/01/2008 01/01/1999 01/01/1998 01/01/1980 01/01/1963	CR-AC IMPORTED IMPORTED IMPORTED IMPORTED	Complete Reconstruction - AC REPAIR OVERLAY OVERLAY BUILT	\$0	0.00 4.00 1.50	False1999 AC OVERLAYTrueSOIL TYPE: SPTrue1980 4" AC OVERLAY
Network: C	EW Br	anch:RW17-35 (RUNWA)	Y 17-35 <b>)</b>	Width:	Section: 6110 Surface: AC
L.C.D.: 01/01	1/2008 Use: RL	JNWAY RankPLength:	1,600.00 Ft		25.00 Ft True Area: 40,000.00 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
01/01/2008 01/01/1999 01/01/1980 01/01/1964	CR-AC IMPORTED IMPORTED IMPORTED	Complete Reconstruction - AC REPAIR OVERLAY BUILT	\$0	0.00 2.00 1.50	True False 1999 AC OVERLAY True 1980 2" AC OVERLAY True 1964 1.5" AC SURFACE COURSE ON 1.5" AC BINDER COURSE ON 8" SOIL-CEMENT
Network: C	EW Br	anch:RW17-35 (RUNWA'	Y 17-35 <b>)</b>	Width:	<b>Section:</b> 6115 <b>Surface:</b> AC
L.C.D.: 01/01	1/2008 Use: RL	JNWAY RankPLength:	4,200.00 Ft		100.00 Ft <b>True Area:</b> 420.000.00 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
01/01/2008 01/01/1999 01/01/1980 01/01/1964	CR-AC IMPORTED IMPORTED IMPORTED	Complete Reconstruction - AC REPAIR OVERLAY OVERLAY	\$0	0.00 2.00 1.50	True False 1999 AC OVERLAY True 1980 2" AC OVERLAY True 1964 1.5" AC SURFACE ON 1.5" AC BINDER

Date:09/	/05/2013		story Re	-	3 of 7			
01/01/1963	IMPORTED	BUILT		1.50	True 1963 1.5" AC SURFACE ON 1.5" AC BINDER ON 10" SAND-CLAY BASE			
<b>Network:</b> C <b>L.C.D.:</b> 01/0 <sup>7</sup>	EW Br 1/2008 Use: RU	anch:RW 17-35 (RUNWA JNWAY Rank PLength:	Y 17-35 <b>)</b> 8,400.00 Ft	Width:	Section: 6120 Surface: AC 25.00 Ft True Area:210,000.00 SqF			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments			
01/01/2008 01/01/1999 01/01/1980 01/01/1964 01/01/1963	CR-AC IMPORTED IMPORTED IMPORTED	Complete Reconstruction - AC REPAIR OVERLAY OVERLAY BUILT	\$0	0.00 2.00 1.50 1.50	True False 1999 AC OVERLAY True 1980 2" TAPERED AC OVERLAY True 1964 1.5" AC SURFACE ON 1.5" AC BINDER True 1963 1.5" AC SURFACE ON 1.5" AC BINDER ON 1963 8" SOIL-CEMENT			
Network:         CEW         Branch:         RW 17-35         (RUNWAY 17-35)         Section:         6125         Surface:         AC           L.C.D.:         01/01/2008         Use:         RUNWAY         Rank P         Length:         3,000.00         Ft         Width:         100.00         Ft         True Area:300,000.00         SqF								
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments			
01/01/2008 01/01/1999 01/01/1980 01/01/1964	NC-AC IMPORTED IMPORTED IMPORTED	New Construction - AC REPAIR OVERLAY BUILT	\$0	0.00 2.00 1.50	TrueFalse1999 AC OVERLAYTrue1980 2" AC OVERLAYTrue1964 1.5" AC SURFACE ON 1.5" ACBINDER ON 10" SAND-CLAY BASE			
<b>Network:</b> C <b>L.C.D.:</b> 01/0 <sup>7</sup>	EW Br 1/2008 Use: Rl	anch: RW 17-35 (RUNWA JNWAY Rank PLength:	Y 17-35 <b>)</b> 6.000.00 Ft	Width:	<b>Section:</b> 6130 <b>Surface:</b> AC 25.00 Ft <b>True Area:</b> 150.000.00 SaF			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments			
01/01/2008 01/01/1999 01/01/1998 01/01/1980 01/01/1964	CR-AC IMPORTED IMPORTED IMPORTED IMPORTED	Complete Reconstruction - AC REPAIR OVERLAY OVERLAY BUILT	\$0	0.00 2.00 1.50	True False 1999 AC OVERLAY True SOIL TYPE: SP True 1980 2" AC OVERLAY True 1964 1.5" AC SURFACE COURSE ON 1.5" AC BINDER COURSE ON 10" SAND-CLAY			
<b>Network:</b> C <b>L.C.D.:</b> 11/0 <sup>-</sup>	EW Br 1/2012 Use: TA	anch:TWA (TAXIWA AXIWAY RankPLength:	Y A <b>)</b> 1.200.00 Ft	Width:	Section: 105 Surface: AAC 50.00 Ft True Area: 98.453.32 SaF			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments			
11/01/2012 01/01/1999	ML-OV IMPORTED	Mill and Overlay REPAIR	\$0	0.00	True 1" MILL, 2" OVERLAY P-401 False 1999 AC OVERLAY			
01/01/1985	IMPORTED	BUILT		4.00	True 1985 4" AC SURFACE ON 6" CRUSHED AGGREGATE ON 4" SUBBASE			
Network: C		anch: TW A (TAXIWA	Y A <b>)</b> 4,300.00 Ft	4.00 Width:				
Network: C	EW <b>Br</b>	anch: TW A (TAXIWA	4,300.00 Ft		AGGREGATE ON 4" SUBBASE Section: 110 Surface: AAC			

Date:09/	/05/2013		story Re	-	4 of 7
<b>Network:</b> C	EW Bra	anch: TWA (TAXIWA	Y A <b>)</b>	Width:	Section: 125 Surface: AAC
L.C.D.: 11/01	1/2012 Use: TA	XIWAY Rank PLength:	3,700.00 Ft		50.00 Ft True Area:267,093.11 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012 01/01/1996	ML-OV IMPORTED	Mill and Overlay BUILT	\$0	0.00 4.00	True 1" MILL, 2" OVERLAY P-401 True 1996 4" P401 ON 13" P209 ON 12" P154 ON 20" P152
<b>Network:</b> C	EW Bra	anch: TWA (TAXIWA	Y A <b>)</b>	Width:	<b>Section:</b> 140 <b>Surface:</b> AC
<b>L.C.D.:</b> 11/01	1/2012 Use: TA	XIWAY Rank PLength:	150.00 Ft		130.00 Ft <b>True Area:</b> 27,340.32 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012	NU-IN	New Construction - Initial	\$0	4.50	True 4.5" P-401, 8" P-211, 17" P-152
<b>Network:</b> C	EW Bra	anch:TWA (TAXIWA	Y A <b>)</b>	Width:	<b>Section:</b> 150 <b>Surface:</b> AC
<b>L.C.D.:</b> 11/01	1/2012 Use: TA	XIWAY Rank PLength:	150.00 Ft		130.00 Ft <b>True Area:</b> 25.815.68 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012	NU-IN	New Construction - Initial	\$0	4.50	True 4.5" P-401, 8" P-211, 17" P-152
<b>Network:</b> C	EW Bra	anch: TWA (TAXIWA	YA <b>)</b>	Width:	<b>Section:</b> 160 <b>Surface:</b> AC
L.C.D.: 11/01	1/2012 Use: TA	XIWAY Rank PLength:	150.00 Ft		130.00 Ft <b>True Area:</b> 25.973.07 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012	NU-IN	New Construction - Initial	\$0	4.50	True 4.5" P-401, 8" P-211, 17" P-152
<b>Network:</b> C	EW Bra	anch:TWA2 (TAXIWA	Y A2 <b>)</b>	Width:	Section: 115 Surface: AAC
<b>L.C.D.:</b> 11/07	1/2012 Use: TA	XIWAY Rank PLength:	300.00 Ft		50.00 Ft True Area: 54,611.89 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012 01/01/1999 01/01/1980 01/01/1963	ML-OV IMPORTED IMPORTED IMPORTED	Mill and Overlay REPAIR OVERLAY BUILT	\$0	0.00 4.00 6.00	False 1999 AC OVERLAY True 1980 4" AC
<b>Network:</b> C	EW Bra	anch:TWA3 (TAXIWA	Y A3 <b>)</b>	Width:	<b>Section:</b> 120 <b>Surface:</b> AAC
<b>L.C.D.:</b> 11/0 <sup>2</sup>	1/2012 Use: TA	XIWAY Rank PLength:	300.00 Ft		50.00 Ft <b>True Area:</b> 53,835.00 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012 01/01/1999 01/01/1980 01/01/1963	ML-OV IMPORTED IMPORTED IMPORTED	Mill and Overlay REPAIR OVERLAY BUILT	\$0	0.00 4.00 6.00	False 1999 AC OVERLAY True 1980 4" AC OVERLAY
<b>Network:</b> C	EW Bra	anch: TW A3 (TAXIWA	Y A3 <b>)</b>	Width:	Section: 330 Surface: AAC
L.C.D.: 11/01	1/2012 Use: TA	XIWAY Rank P Length:	95.00 Ft		40.00 Ft True Area: 7,150.80 SqF
Work	Work	Work	Cost	Thickness	Major
Date	Code	Description		(in)	M&R Comments
11/01/2012	ML-OV	Mill and Overlay	\$0	0.00	True 1" MILL, 2" OVERLAY P-401
01/01/1980	IMPORTED	OVERLAY		4.00	True 1980: 4" P-401 OVERLAY

Date:09/	/05/2013		story Re	-		5 of 7
Network: Cl L.C.D.: 11/01	EW Bra 1/2012 Use: TA	anch: TW A4 (TAXIWA XIWAY Rank PLength:	•	Width:		ection: 130 Surface: AAC .00 Ft True Area: 53,403.85 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/01/2012 01/01/1999 01/01/1980 01/01/1963	ML-OV IMPORTED IMPORTED IMPORTED	Mill and Overlay REPAIR OVERLAY BUILT	\$0 \$0 \$0 \$0	0.00		MILL 1", 2" P-401 OVERLAY 1999 AC OVERLAY 1980 4" AC SURFACE 1963 1.5" AC SURFACE ON 1.5" AC BINDER COURSE ON 8" SOIL-CEMENT BASE
Network: Cl L.C.D.: 11/01	EW Bra 1/2012 Use: TA	anch: TW A4 (TAXIWA XIWAY Rank P Length:	Y A4 <b>)</b> 150.00 Ft	Width:		ection: 135 Surface: AC .00 Ft True Area: 26.609.01 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/01/2012	NU-IN	New Construction - Initial	\$0	4.50	True	4.5" P-401, 8" P-211, 17" P-152
Network: CI L.C.D.: 11/01	EW Bra 1/2012 Use: TA		CTOR TAXIWAYS 75.00 Ft	TO APRO Width:		ection: 310 Surface: AAC .00 Ft True Area: 7.038.40 SqF
Work Date	Work Code	Work Description		Thickness ( in)	Major M&R	
11/01/2012 01/01/1980 01/01/1963	ML-OV IMPORTED IMPORTED	Mill and Overlay OVERLAY BUILT	\$0	. ,	True	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT
Network: Cl L.C.D.: 11/01	EW Bra 1/2012 Use: TA		CTOR TAXIWAYS 55.00 Ft	TO APRO Width:	,	e <b>ction:</b> 320 <b>Surface:</b> AAC .00 Ft <b>True Area:</b> 2,982.48 SqF
Work Date	Work	Work		Thickness	Major	
	Code	Description	Cost	( in)	M&R	Comments
11/01/2012 01/01/1980 01/01/1963	Code ML-OV IMPORTED IMPORTED	Description Mill and Overlay OVERLAY BUILT	Cost \$0	( in)	M&R	Comments 1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE
01/01/1980 01/01/1963 Network: Cl	ML-OV IMPORTED IMPORTED EW Br	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNE)	\$0 CTOR TAXIWAYS	(in) 0.00 4.00 6.00	M&R True True True N) Se	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC
01/01/1980 01/01/1963 Network: Cl	ML-OV IMPORTED IMPORTED	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNE)	\$0 CTOR TAXIWAYS 113.00 Ft	(in) 0.00 4.00 6.00 TO APRO Width: Thickness	M&R True True True N) Se	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC .00 Ft True Area: 26.206.75 SqF
01/01/1980 01/01/1963 Network: CI L.C.D.: 11/01 Work	ML-OV IMPORTED IMPORTED EW Bra 1/2012 Use: TA Work	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNE) XIWAY Rank P Length: Work	\$0 CTOR TAXIWAYS 113.00 Ft	(in) 0.00 4.00 6.00 TO APRO Width: Thickness (in) 0.00	M&R True True True N) Se 90 Major M&R True	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC .00 Ft True Area: 26.206.75 SaF
01/01/1980 01/01/1963 Network: CL L.C.D.: 11/01 Work Date 11/01/2012 01/01/2005 Network: CL	ML-OV IMPORTED IMPORTED EW Br. 1/2012 Use: TA Work Code ML-OV INITIAL	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNE) XIWAY Rank P Length: Work Description Mill and Overlay Initial Construction anch: TW CONN (CONNE)	\$0 CTOR TAXIWAYS 113.00 Ft Cost \$0	(in) 0.00 4.00 6.00 STO APRO Width: Thickness (in) 0.00 0.00	M&R True True True N) Se 90 Major M&R True True True	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC .00 Ft True Area: 26.206.75 SaF Comments 1" MILL, 2" OVERLAY P-401 4" AC, 10" P-211, 6" LIMEROCK BASE,
01/01/1980 01/01/1963 Network: CL L.C.D.: 11/01 Work Date 11/01/2012 01/01/2005 Network: CL	ML-OV IMPORTED IMPORTED IMPORTED EW Br. Code ML-OV INITIAL EW Br.	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNE) XIWAY Rank P Length: Work Description Mill and Overlay Initial Construction anch: TW CONN (CONNE)	\$0 CTOR TAXIWAYS 113.00 Ft <b>Cost</b> \$0 \$0 CTOR TAXIWAYS 127.25 Ft	(in) 0.00 4.00 6.00 5 TO APRO Width: Thickness (in) 0.00 0.00 5 TO APRO	M&R True True True N) Se 90 Major M&R True True True	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC .00 Ft True Area: 26.206.75 SaF Comments 1" MILL, 2" OVERLAY P-401 4" AC, 10" P-211, 6" LIMEROCK BASE, 12" TYPE B STABILIZATION LBR 40 ection: 340 Surface: AAC .00 Ft True Area: 26.273.04 SaF
01/01/1980 01/01/1963 Network: CI L.C.D.: 11/01 Work Date 11/01/2012 01/01/2005 Network: CI L.C.D.: 11/01 Work	ML-OV IMPORTED IMPORTED IMPORTED EW Br ML-OV INITIAL EW Br 1/2012 Use: TA Work	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNEC XIWAY Rank P Length: Work Description Mill and Overlay Initial Construction anch: TW CONN (CONNEC XIWAY Rank P Length: Work	\$0 CTOR TAXIWAYS 113.00 Ft Cost \$0 \$0 CTOR TAXIWAYS 127.25 Ft	(in) 0.00 4.00 6.00 5 TO APRO Width: Thickness (in) 0.00 0.00 5 TO APRO Width: Thickness (in)	M&R True True True N) Se 90 Major M&R True True N) Se 40 Major M&R True True	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC .00 Ft True Area: 26.206.75 SaF Comments 1" MILL, 2" OVERLAY P-401 4" AC, 10" P-211, 6" LIMEROCK BASE, 12" TYPE B STABILIZATION LBR 40 ection: 340 Surface: AAC .00 Ft True Area: 26,273.04 SaF
01/01/1980 01/01/1963 Network: CI L.C.D.: 11/01 Work Date 11/01/2012 01/01/2005 Network: CI L.C.D.: 11/01 Work Date 11/01/2012 01/01/1987 Network: CI	ML-OV IMPORTED IMPORTED IMPORTED EW Br. 1/2012 Use: TA Work Code ML-OV INITIAL EW Br. 1/2012 Use: TA Work Code ML-OV IMPORTED	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNEC XIWAY Rank P Length: Work Description Mill and Overlay Initial Construction Annch: TW CONN (CONNEC XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW K (TAXIWA	\$0 CTOR TAXIWAYS 113.00 Ft <b>Cost</b> \$0 \$0 CTOR TAXIWAYS 127.25 Ft <b>Cost</b> \$0	(in) 0.00 4.00 6.00 5 TO APRO Width: Thickness (in) 0.00 0.00 5 TO APRO Width: Thickness (in)	M&R True True True 90 Major M&R True True N) Se 40 Major Magor Magor Magor Magor Magor Se	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC .00 Ft True Area: 26.206.75 SaF Comments 1" MILL, 2" OVERLAY P-401 4" AC, 10" P-211, 6" LIMEROCK BASE, 12" TYPE B STABILIZATION LBR 40 ection: 340 Surface: AAC .00 Ft True Area: 26,273.04 SaF Comments 1" MILL, 2" OVERLAY P-401
01/01/1980 01/01/1963 Network: CI L.C.D.: 11/01 Work Date 11/01/2012 01/01/2005 Network: CI L.C.D.: 11/01 Work Date 11/01/2012 01/01/1987 Network: CI	ML-OV IMPORTED IMPORTED IMPORTED IMPORTED EW Br. ML-OV INITIAL EW Br. ML-OV IMPORTED EW Br.	Mill and Overlay OVERLAY BUILT anch: TW CONN (CONNEC XIWAY Rank P Length: Work Description Mill and Overlay Initial Construction anch: TW CONN (CONNEC XIWAY Rank P Length: Work Description Mill and Overlay BUILT anch: TW K (TAXIWA	\$0 CTOR TAXIWAYS 113.00 Ft <b>Cost</b> \$0 \$0 CTOR TAXIWAYS 127.25 Ft <b>Cost</b> \$0 Y K) 500.00 Ft	(in) 0.00 4.00 6.00 5 TO APRO Width: Thickness (in) 0.00 0.00 5 TO APRO Width: Thickness (in) 0.00	M&R True True True 90 Major M&R True True N) Se 40 Major Magor Magor Magor Magor Magor Se	1" MILL, 2" OVERLAY P-401 1980: 4" P-401 OVERLAY 1963: DOUBLE BITUMINOUS SURFACE TREATMENT ON 6" SOIL CEMENT BASE ection: 335 Surface: AAC .00 Ft True Area: 26.206.75 SaF Comments 1" MILL, 2" OVERLAY P-401 4" AC, 10" P-211, 6" LIMEROCK BASE, 12" TYPE B STABILIZATION LBR 40 ection: 340 Surface: AAC .00 Ft True Area: 26,273.04 SaF Comments 1" MILL, 2" OVERLAY P-401 ESTIMATE 1987 AC PAVEMENT ection: 605 Surface: AC .00 Ft True Area: 25,847.69 SaF

Date:09/	05/2013		story Re	-		6 of 7		
Network: Ci L.C.D.: 01/01	EW Bra 1/2008 Use: TA	anch: TW PMV (TAXIWA XIWAY Rank SLength:	,	Width:	Section: 505 Surface: AC 50.00 Ft True Area: 75,708.54 SqF			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments		
01/01/2008	INITIAL	Initial Construction	\$0	0.00	True			


Pavement Database:FDOT

#### Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	24	2,665,049.87	3.47	1.98
Complete Reconstruction - AC	5	900,000.00	.00	.00
Initial Construction	2	101,915.29	.00	.00
Mill and Overlay	14	1,128,912.22	.00	.00
New Construction - AC	1	300,000.00	.00	
New Construction - Initial	9	392,045.26	5.61	2.78
OVERLAY	22	2,970,161.99	3.06	1.11
REPAIR	11	1,764,147.31	.00	

# APPENDIX B

- AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
- PAVEMENT CONDITION INDEX INVENTORY





### Pavement Evaluation Report - Bob Sikes Airport

Branch Name	Branch ID	Branch Use	Section ID	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	PCI	PCI Category	Total Samples Inspected	Total Samples
RUNWAY 17-35	RW 17-35	RUNWAY	6130	150,000	Р	AC	85	Satisfactory	5	30
RUNWAY 17-35	RW 17-35	RUNWAY	6125	300,000	Р	AC	84	Satisfactory	12	60
RUNWAY 17-35	RW 17-35	RUNWAY	6120	210,000	Р	AC	93	Good	8	42
RUNWAY 17-35	RW 17-35	RUNWAY	6115	420,000	Р	AC	91	Good	18	84
RUNWAY 17-35	RW 17-35	RUNWAY	6110	40,000	Р	AC	89	Good	2	8
RUNWAY 17-35	RW 17-35	RUNWAY	6105	80,000	Р	AC	79	Satisfactory	5	16
WEST RUN-UP APRON AT RW 17	AP RU	APRON	5105	46,560	Р	AAC	100	Good	2	10
NORTH APRON	AP N	APRON	4355	105,318	Р	AC	100	Good	3	22
NORTH APRON	AP N	APRON	4350	23,280	Р	PCC	100	Good	1	6
NORTH APRON	AP N	APRON	4345	99,461	Р	AC	100	Good	3	19
NORTH APRON	AP N	APRON	4340	33,816	Р	AAC	100	Good	1	6
HANGAR APRON	AP HANG	APRON	4210	7,104	Р	AC	18	Serious	1	3
HANGAR APRON	AP HANG	APRON	4205	18,010	Р	AC	62	Fair	1	4
APRON	AP	APRON	4130	32,400	Р	PCC	100	Good	2	7
APRON	AP	APRON	4120	147,645	Р	AAC	100	Good	5	27
APRON	AP	APRON	4115	187,231	Р	AC	32	Very Poor	5	37
APRON	AP	APRON	4110	93,750	Р	AC	30	Very Poor	3	18
APRON	AP	APRON	4105	56,250	Р	AAC	38	Very Poor	2	12
ΤΑΧΙΨΑΥ Κ	TW K	TAXIWAY	605	25,848	Р	AC	94	Good	1	8
Taxiway PMV	TW PMV	TAXIWAY	505	75,709	S	AC	94	Good	3	15
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	340	26,273	Р	AAC	100	Good	1	5
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	335	26,207	Р	AAC	100	Good	1	5
TAXIWAY A3	TW A3	TAXIWAY	330	7,151	Р	AAC	100	Good	1	2

#### Table B-1: Pavement Condition Index Inventory

\_\_\_\_\_



Branch Name	Branch ID	Branch Use	Section ID	True Area (FT <sup>2</sup> )	Section Rank	Surface Type	PCI	PCI Category	Total Samples Inspected	Total Samples
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	320	2,982	Р	AAC	100	Good	1	1
CONNECTOR TAXIWAYS TO APRON	TW CONN	TAXIWAY	310	7,038	Р	AAC	100	Good	1	2
TAXIWAY A	TW A	TAXIWAY	160	25,973	Р	AC	100	Good	1	5
TAXIWAY A	TW A	TAXIWAY	150	25,816	Р	AC	100	Good	1	5
TAXIWAY A	TW A	TAXIWAY	140	27,340	Р	AC	100	Good	1	5
TAXIWAY A4	TW A4	TAXIWAY	135	26,609	Р	AC	100	Good	1	5
TAXIWAY A4	TW A4	TAXIWAY	130	53,404	Р	AAC	100	Good	2	12
ΤΑΧΙΨΑΥ Α	TW A	TAXIWAY	125	267,093	Р	AAC	100	Good	7	68
ΤΑΧΙΨΑΥ Α3	TW A3	TAXIWAY	120	53,835	Р	AAC	100	Good	2	12
Taxiway A2	TW A2	TAXIWAY	115	54,612	Р	AAC	100	Good	2	12
TAXIWAY A	TW A	TAXIWAY	110	303,843	Р	AAC	100	Good	9	81
TAXIWAY A	TW A	TAXIWAY	105	98,453	Р	AAC	100	Good	3	22

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER. \* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

# APPENDIX C

- BRANCH CONDITION REPORT
- SECTION CONDITION REPORT

### **Branch Condition Report**

Pavement Database: FDOT NetworkID: CEW

1 of 2

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	PCI Standard Deviation	Weighted Average PCI
AP (APRON)	5	3,512.00	132.00	517,275.68	APRON	60.00	32.77	55.96
AP HANG (HANGAR APRON)	2	700.00	27.50	25,113.72	APRON	40.00	22.00	49.55
AP N (NORTH APRON)	4	1,781.00	141.25	261,875.13	APRON	100.00	0.00	100.00
AP RU (WEST RUN-UP APRON AT RW 17)	1	415.00	100.00	46,559.69	APRON	100.00	0.00	100.00
RW 17-35 (RUNWAY 17-35)	6	24,000.00	62.50	1,200,000.00	RUNWAY	86.83	4.71	87.98
TW A (TAXIWAY A)	6	9,650.00	90.00	748,518.75	TAXIWAY	100.00	0.00	100.00
TW A2 (TAXIWAY A2)	1	300.00	50.00	54,611.89	TAXIWAY	100.00	0.00	100.00
TW A3 (TAXIWAY A3)	2	395.00	45.00	60,985.80	TAXIWAY	100.00	0.00	100.00
TW A4 (TAXIWAY A4)	2	400.00	130.00	80,012.86	TAXIWAY	100.00	0.00	100.00
TW CONN (CONNECTOR TAXIWAYS TO APRON)	4	370.25	52.50	62,500.67	TAXIWAY	100.00	0.00	100.00
ΤΨ Κ (ΤΑΧΙΨΑΥ Κ)	1	500.00	35.00	25,847.69	TAXIWAY	94.00	0.00	94.00
TW PMV (TAXIWAY PMV)	1	1,450.00	50.00	75,708.54	TAXIWAY	94.00	0.00	94.00

Date: 9 /5/2013

### **Branch Condition Report**

Pavement Database: FDOT

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	12	850,824.22	73.33	32.92	71.73
RUNWAY	6	1,200,000.00	86.83	4.71	87.98
TAXIWAY	17	1,108,186.20	99.29	1.93	99.45
All	35	3,159,010.42	88.26	22.65	87.63

2 of 2

Date: 9 /5/2013	Pavemei		on Conc se: FDOT		n Re	-		1 of 3		
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP (APRON)	4105	01/01/1980	AAC	APRON	Ρ	0	56,250.00	08/27/2013	33	38.00
AP (APRON)	4110	01/01/1983	AC	APRON	Р	0	93,750.00	08/27/2013	30	30.00
AP (APRON)	4115	01/01/1987	AC	APRON	Р	0	187,230.68	08/27/2013	26	32.00
AP (APRON)	4120	03/01/2012	AAC	APRON	Р	0	147,645.00	03/01/2012	0	100.00
AP (APRON)	4130	03/01/2012	PCC	APRON	Р	0	32,400.00	03/01/2012	0	100.00
AP HANG (HANGAR APRON)	4205	01/01/1994	AC	APRON	Р	0	18,010.19	08/27/2013	19	62.00
AP HANG (HANGAR APRON)	4210	01/01/1963	AC	APRON	Р	0	7,103.53	08/27/2013	50	18.00
AP N (NORTH APRON)	4340	11/01/2012	AAC	APRON	Р	0	33,815.64	11/01/2012	0	100.00
AP N (NORTH APRON)	4345	11/01/2012	AC	APRON	Р	0	99,461.38	11/01/2012	0	100.00
AP N (NORTH APRON)	4350	11/01/2012	PCC	APRON	Р	0	23,279.79	11/01/2012	0	100.00
AP N (NORTH APRON)	4355	11/01/2012	AC	APRON	Р	0	105,318.32	11/01/2012	0	100.00
AP RU (WEST RUN-UP APRON AT RW 17)	5105	11/01/2012	AAC	APRON	Ρ	0	46,559.69	11/01/2012	0	100.00
RW 17-35 (RUNWAY 17-35)	6105	01/01/2008	AC	RUNWAY	Ρ	0	80,000.00	08/27/2013	5	79.00
RW 17-35 (RUNWAY 17-35)	6110	01/01/2008	AC	RUNWAY	Ρ	0	40,000.00	08/27/2013	5	89.00
RW 17-35 (RUNWAY 17-35)	6115	01/01/2008	AC	RUNWAY	Р	0	420,000.00	08/27/2013	5	91.00
RW 17-35 (RUNWAY 17-35)	6120	01/01/2008	AC	RUNWAY	Р	0	210,000.00	08/27/2013	5	93.00
RW 17-35 (RUNWAY 17-35)	6125	01/01/2008	AC	RUNWAY	Р	0	300,000.00	08/27/2013	5	84.00
RW 17-35 (RUNWAY 17-35)	6130	01/01/2008	AC	RUNWAY	Р	0	150,000.00	08/27/2013	5	85.00
TW A (TAXIWAY A)	105	11/01/2012	AAC	TAXIWAY	Р	0	98,453.32	11/01/2012	0	100.00
TW A (TAXIWAY A)	110	11/01/2012	AAC	TAXIWAY	Р	0	303,843.25	11/01/2012	0	100.00
TW A (TAXIWAY A)	125	11/01/2012	AAC	TAXIWAY	Р	0	267,093.11	11/01/2012	0	100.00
TW A (TAXIWAY A)	140	11/01/2012	AC	TAXIWAY	Р	0	27,340.32	11/01/2012	0	100.00
TW A (TAXIWAY A)	150	11/01/2012	AC	TAXIWAY	Р	0	25,815.68	11/01/2012	0	100.00
TW A (TAXIWAY A)	160	11/01/2012	AC	TAXIWAY	Р	0	25,973.07	11/01/2012	0	100.00
TW A2 (TAXIWAY A2)	115	11/01/2012	AAC	TAXIWAY	Ρ	0	54,611.89	11/01/2012	0	100.00
TW A3 (TAXIWAY A3)	120	11/01/2012	AAC	TAXIWAY	Р	0	53,835.00	11/01/2012	0	100.00

Date: 9 /5/2013	Date: 9 /5/2013       Section Condition Report         Pavement Database: FDOT       NetworkID: CEW									2 of 3	
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI	
TW A3 (TAXIWAY A3)	330	11/01/2012	AAC	TAXIWAY	Ρ	0	7,150.80	11/01/2012	0	100.00	
TW A4 (TAXIWAY A4)	130	11/01/2012	AAC	TAXIWAY	Р	0	53,403.85	11/01/2012	0	100.00	
TW A4 (TAXIWAY A4)	135	11/01/2012	AC	TAXIWAY	Ρ	0	26,609.01	11/01/2012	0	100.00	
TW CONN (CONNECTOR TAXIWAYS TO APRON)	310	11/01/2012	AAC	TAXIWAY	Ρ	0	7,038.40	11/01/2012	0	100.00	
TW CONN (CONNECTOR TAXIWAYS TO APRON)	320	11/01/2012	AAC	TAXIWAY	Р	0	2,982.48	11/01/2012	0	100.00	
TW CONN (CONNECTOR TAXIWAYS TO APRON)	335	11/01/2012	AAC	TAXIWAY	Р	0	26,206.75	11/01/2012	0	100.00	
TW CONN (CONNECTOR TAXIWAYS TO APRON)	340	11/01/2012	AAC	TAXIWAY	Ρ	0	26,273.04	11/01/2012	0	100.00	
TW K (TAXIWAY K)	605	03/01/2008	AC	TAXIWAY	Ρ	0	25,847.69	08/27/2013	5	94.00	
TW PMV (TAXIWAY PMV)	505	01/01/2008	AC	TAXIWAY	S	0	75,708.54	08/27/2013	5	94.00	

Date: 9 /5/2013

# Section Condition Report

Pavement Database: FDOT

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmeti c Average PCI	PCI Standard Deviation	Weighted Average PCI
0-02	0.00	1,495,109.79	22	100.00	0.00	100.00
03-05	5.00	1,301,556.23	8	88.63	5.48	88.45
16-20	19.00	18,010.19	1	62.00	0.00	62.00
26-30	28.00	280,980.68	2	31.00	1.41	31.33
31-35	33.00	56,250.00	1	38.00	0.00	38.00
over 40	50.00	7,103.53	1	18.00	0.00	18.00
All	5.66	3,159,010.42	35	88.26	22.98	87.63

3 of 3

# APPENDIX D

- PAVEMENT PERFORMANCE PREDICTION
- PAVEMENT PERFORMANCE BY PAVEMENT USE


Branch	Section	Current			Paver	ment P	Perform	nance	Mode	I - PCI		
ID	ID	PCI	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023
RW 17-35	6130	85	84	83	81	79	77	76	74	73	71	70
RW 17-35	6125	84	83	82	80	78	76	75	73	72	70	69
RW 17-35	6120	93	92	90	88	86	84	83	81	79	77	76
RW 17-35	6115	91	90	88	86	84	83	81	79	77	76	74
RW 17-35	6110	89	88	86	84	83	81	79	77	76	74	73
RW 17-35	6105	79	78	77	75	74	72	71	69	68	66	65
AP RU	5105	100	96	92	89	86	83	80	78	75	73	71
AP N	4355	100	94	89	85	82	79	76	74	73	71	70
AP N	4350	100	97	94	91	88	85	82	79	76	73	71
AP N	4345	100	94	89	85	82	79	76	74	73	71	70
AP N	4340	100	96	92	89	86	83	80	78	75	73	71
AP HANG	4210	18	18	18	18	18	18	17	17	17	17	17
AP HANG	4205	62	62	61	60	59	59	58	57	56	55	54
AP	4130	100	95	92	89	86	83	80	77	74	72	69
AP	4120	100	93	90	87	84	81	79	76	74	72	70
AP	4115	32	32	32	32	32	32	31	31	31	31	31
AP	4110	30	30	30	30	30	30	29	29	29	29	29
AP	4105	38	37	35	33	31	30	28	26	24	22	20
TW K	605	94	93	90	88	85	83	81	78	76	75	73
TW PMV	505	94	93	90	88	85	83	81	78	76	75	73
TW CONN	340	100	96	93	90	88	86	84	82	80	79	77
TW CONN	335	100	96	93	90	88	86	84	82	80	79	77
TW A3	330	100	96	93	90	88	86	84	82	80	79	77
TW CONN	320	100	96	93	90	88	86	84	82	80	79	77
TW CONN	310	100	96	93	90	88	86	84	82	80	79	77
TW A	160	100	97	94	91	89	86	84	81	79	77	75
TW A	150	100	97	94	91	89	86	84	81	79	77	75
TW A	140	100	97	94	91	89	86	84	81	79	77	75

# Table D-1: Pavement Performance Prediction


Branch	Section	Current			Paver	ment P	erform	nance	Mode	- PCI		
ID	ID	PCI	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023
TW A4	135	100	97	94	91	89	86	84	81	79	77	75
TW A4	130	100	96	93	90	88	86	84	82	80	79	77
TW A	125	100	96	93	90	88	86	84	82	80	79	77
TW A3	120	100	96	93	90	88	86	84	82	80	79	77
TW A2	115	100	96	93	90	88	86	84	82	80	79	77
TW A	110	100	96	93	90	88	86	84	82	80	79	77
TW A	105	100	96	93	90	88	86	84	82	80	79	77

#### Figure D-1: Pavement Performance by Pavement Use


(a) Runway



#### (b) Taxiway



#### (c) Apron



# APPENDIX E

• YEAR-1 PREVENTATIVE ACTIVITIES

Pavement Evaluation Report - Bob Sikes Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost		
RUNWAY 17-35	RW 17-35	6130	L&TCR	L	Crack Sealing - AC	6,900.00	Ft	\$2.75	\$18,974.98		
RUNWAY 17-35	RW 17-35	6125	L&TCR	L	Crack Sealing - AC	12,845.00	Ft	\$2.75	\$35,323.71		
RUNWAY 17-35	RW 17-35	6120	L&TCR	L	Crack Sealing - AC	378.00	Ft	\$2.75	\$1,039.50		
RUNWAY 17-35	RW 17-35	6120	RAVELING	L	Surface Seal	2,115.80	SqFt	\$0.55	\$1,163.67		
RUNWAY 17-35	RW 17-35	6115	L&TCR	L	Crack Sealing - AC	2,781.30	Ft	\$2.75	\$7,648.66		
RUNWAY 17-35	RW 17-35	6115	RAVELING	L	Surface Seal	1,717.30	SqFt	\$0.55	\$944.54		
RUNWAY 17-35	RW 17-35	6110	L&TCR	L	Crack Sealing - AC	644.00	Ft	\$2.75	\$1,771.00		
RUNWAY 17-35	RW 17-35	6105	L&TCR	L	Crack Sealing - AC	4,614.40	Ft	\$2.75	\$12,689.59		
HANGAR APRON	AP HANG	4210	BLOCK CR	М	Patching - AC Full Depth	2,749.60	SqFt	\$5.00	\$13,747.79		
HANGAR APRON	AP HANG	4210	DEPRESSION	М	Patching - AC Full Depth	259.80	SqFt	\$5.00	\$1,299.01		
HANGAR APRON	AP HANG	4210	PATCHING	Н	Patching - AC Full Depth	100.60	SqFt	\$5.00	\$502.87		
HANGAR APRON	AP HANG	4210	PATCHING	М	Crack Sealing - AC	870.70	Ft	\$2.75	\$2,394.29		
HANGAR APRON	AP HANG	4210	RAVELING	Н	Patching - AC Partial Depth	24.50	SqFt	\$3.00	\$73.48		
HANGAR APRON	AP HANG	4210	RAVELING	М	Surface Seal	2,725.10	SqFt	\$0.55	\$1,498.80		

#### Table E-1: Year-1 Preventative Activities



Pavement Evaluation Report - Bob Sikes Airport

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
HANGAR APRON	AP HANG	4205	L & T CR	L	Crack Sealing - AC	115.30	Ft	\$2.75	\$317.17
HANGAR APRON	AP HANG	4205	RAVELING	L	Surface Seal	13,631.90	SqFt	\$0.55	\$7,497.58
APRON	AP	4115	BLOCK CR	М	Patching - AC Full Depth	73,205.40	SqFt	\$5.00	\$366,027.22
APRON	AP	4115	BLOCK CR	L	Surface Seal	6,340.40	SqFt	\$0.55	\$3,487.25
APRON	AP	4115	L&TCR	L	Crack Sealing - AC	1,985.00	Ft	\$2.75	\$5,458.77
APRON	AP	4115	L&TCR	Н	Crack Sealing - AC	87.30	Ft	\$2.75	\$239.95
APRON	AP	4115	L&TCR	М	Crack Sealing - AC	12,724.40	Ft	\$2.75	\$34,992.10
APRON	AP	4115	OIL SPILLAGE	N	Surface Seal	330.90	SqFt	\$0.55	\$181.98
APRON	AP	4115	RAVELING	L	Surface Seal	187,230.70	SqFt	\$0.55	\$102,977.73
APRON	AP	4115	SWELLING	М	Patching - AC Full Depth	460.40	SqFt	\$5.00	\$2,301.80
APRON	AP	4110	BLOCK CR	М	Patching - AC Full Depth	39,230.80	SqFt	\$5.00	\$196,154.02
APRON	AP	4110	BLOCK CR	L	Surface Seal	7,015.40	SqFt	\$0.55	\$3,858.49
APRON	AP	4110	L&TCR	L	Crack Sealing - AC	2,203.80	Ft	\$2.75	\$6,060.57
APRON	AP	4110	L&TCR	М	Crack Sealing - AC	3,888.50	Ft	\$2.75	\$10,693.26
APRON	AP	4110	OIL SPILLAGE	N	Surface Seal	223.40	SqFt	\$0.55	\$122.85

\_\_\_\_\_




Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
APRON	AP	4110	RAVELING	М	Surface Seal	57,692.30	SqFt	\$0.55	\$31,731.03
APRON	AP	4110	RAVELING	L	Surface Seal	36,057.70	SqFt	\$0.55	\$19,831.90
APRON	AP	4105	BLOCK CR	М	Patching - AC Full Depth	32,142.90	SqFt	\$5.00	\$160,714.43
APRON	AP	4105	BLOCK CR	L	Surface Seal	9,000.00	SqFt	\$0.55	\$4,950.04
APRON	AP	4105	L&TCR	L	Crack Sealing - AC	668.60	Ft	\$2.75	\$1,838.57
APRON	AP	4105	L&TCR	М	Crack Sealing - AC	1,356.40	Ft	\$2.75	\$3,730.17
APRON	AP	4105	RAVELING	L	Surface Seal	56,250.00	SqFt	\$0.55	\$30,937.76
APRON	AP	4105	WEATHERING	М	Surface Seal	47,571.40	SqFt	\$0.55	\$26,164.50
								Total =	\$ 1,119,341.03


\_\_\_\_\_

# APPENDIX F

- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION
   EXHIBIT
- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION TABLE



DESIGNED: KHA DRAWN: KHA CHECKED: KHA DATE: 2013
WEL\_MARK/M27N227(2017),LIGHETT/201 HD 5825 MP07T(20815)20-4-29-HDMAde
ROTED Network 25, 203 - 563 FM, 57 Network 274





Year	Branch ID	Section ID	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2014	AP HANG	4210	\$106,552.98	18	Reconstruction	100
2014	AP HANG	4205	\$180,101.89	62	Mill and Overlay	100
2014	AP	4115	\$2,808,460.86	32	Reconstruction	100
2014	AP	4110	\$1,406,250.33	30	Reconstruction	100
2014	AP	4105	\$843,750.20	37	Reconstruction	100
		Total =	\$5,345,116.26			

#### Table F-1: Airfield Pavement 10-Year Major Rehabilitation Table

\* Costs are adjusted for inflation AT 3%

# APPENDIX G

• PHOTOGRAPHS



Runway 17-35, Section 6130, Sample Unit 252 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 17-35, Section 6130, Sample Unit 252 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 17-35, Section 6125, Sample Unit 445 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 17-35, Section 6115, Sample Unit 346 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Taxiway PMV, Section 505, Sample Unit 109 - Low Severity (57) Weathering



Apron Hang, Section 4210, Sample Unit 301 – Medium Severity (43) Block Cracking, Medium and High Severity (52) Raveling, Low, Medium, and High Severity (50) Patching



Apron Hang, Section 4210, Sample Unit 301 – Medium Severity (43) Block Cracking, Medium Severity (52) Raveling, Medium Severity (50) Patching



Apron Hang, Section 4210, Sample Unit 301 – Medium Severity (43) Block Cracking, Medium Severity (50) Patching, Medium and High Severity (52) Raveling



Apron Hang, Section 4210, Sample Unit 301 – High Severity (50) Patching



Apron, Section 4115, Sample Unit 207 – High Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Apron, Section 4110, Sample Unit 306 – Low and Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering, Low Severity (43) Block Cracking, Oil Spillage (49)



Apron, Section 4105, Sample Unit 410– Medium Severity (43) Block Cracking, Low Severity (52) Raveling, Medium Severity (57) Weathering

# APPENDIX H

O DISTRESS DATA – RE-INSPECTION REPORT

<b>Re-inspection</b>	Report
----------------------	--------

ranch: AP Name: APRON Use: APRON Area: 517,275.68SqFt ection: 4105 of 5 From: - To: - Last Const.: 01/01/198 urface: AAC Family: FDOT-GA-AP-AAC Zone: Category: Rank: P rea: 56,250.00SqFt Length: 375.00Ft Width: 150.00Ft houlder: Street Type: Grade: 0.00 Lanes: 0 ection Comments: ast Insp. Date: 08/27/2013 Total Samples: 12 Surveyed: 2 onditions: PCI: 38 sepection Comments: ample Number: 407 Type: R Area: 3,750.00SqFt PCI = 38 ample Comments: 3 BLOCK CRACKING L 1,400.00 SqFt Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments: 9 CONGINIENT Comments: 1 RAVELING M 2,400.00 SqFt Comments: 1 RAVELING M 2,400.00 SqFt Comments: 2 RAVELING M 2,400.00 SqFt Comments: 3 BLOCK CRACKING L 1,350.00 SqFt Comments: 3 BLOCK CRACKING M 2,400.00 SqFt Comments: 2 RAVELING M 2,400.00 SqFt Comments: 3 BLOK CRACKING L 1,350.00 SqFt Comments: 3 BLOK CRACKING M 2,400.00 SqFt Comments: 3 BLOK CRACKING L 1,350.00 SqFt Comments: 3 BLOK CRACKING L 1,350.00 SqFt Comments: 3 BLOK CRACKING L 1,350.00 SqFt Comments: 2 RAVELING M 5,000.00 SqFt Comments: 3 BLOK CRACKING M 5,000.00 SqFt Comments: 3 BLOK CRACKING M 5,000.00 SqFt Comments: 3 RAVELING M 5,000.00 SqFt Comments:	Report Generated Date: September 05, 2013				
ection: 4105 of 5 From: - To: - Last Const.: 01/01/198 urface: AAC Family: FDOT-GA-AP-AAC Zone: Category: Rank: P rea: 56,250.00SqFt Length: 375.00Ft Width: 150.00Ft houlder: Street Type: Grade: 0.00 Lanes: 0 ection Comments: asst Insp. Date: 08/27/2013 Total Samples: 12 Surveyed: 2 conditions: PCI: 38 ispection Comments: ample Number: 407 Type: R Area: 3,750.00SqFt PCI = 38 ample Comments: 3 BLOCK CRACKING L 1,400.00 SqFt Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments: 2 RAVELING M 211.00 Ft Comments: 7 WEATHERING M 2,400.00 SqFt Comments: 7 WEATHERING L 3,750.00 SqFt Comments: 7 WEATHERING M 2,400.00 SqFt Comments: ample Number: 410 Type: R Area: 5,000.00SqFt PCI = 37 ample Comments: 3 BLOCK CRACKING M 5,000.00 SqFt Comments: 2 RAVELING M 5,000.00 SqFt Comments: 2 RAVELING M 5,000.00 SqFt Comments: 3 BLOCK CRACKING L 1,350.00 SqFt Comments: 2 RAVELING M 2,400.00 SqFt Comments: 3 BLOCK CRACKING L 1,350.00 SqFt Comments: 3 BLOCK CRACKING M 5,000.00 SqFt Comments:	Network: CEW Name: BOB SIKES AIRPORT				
<pre>urface: AAC Family: FDOT-GA-AP-AAC Zone: Category: Rank: P rea: 56,250.00SqFt Length: 375.00Ft Width: 150.00Ft houlder: Street Type: Grade: 0.00 Lanes: 0 ection Comments: ast Insp. Date: 08/27/2013 Total Samples: 12 Surveyed: 2 onditions: PCI: 38 spection Comments: ample Number: 407 Type: R Area: 3,750.00SqFt PCI = 38 ample Comments: 3 BLOCK CRACKING L 1,400.00 SqFt Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING M 211.00 Ft Comments: 2 RAVELING L 3,750.00 SqFt Comments: 7 WEATHERING L 3,750.00 SqFt Comments: ample Number: 410 Type: R Area: 5,000.00SqFt PCI = 37 ample Comments: 3 BLOCK CRACKING M 5,000.00 SqFt Comments: 2 RAVELING M 5,000.00 SqFt Comments: </pre>	Branch: AP Name: APRON		Use: APRON	Area:	517,275.68SqFt
houlder: Street Type: Grade: 0.00 Lanes: 0 ection Comments: asst Insp. Date: 08/27/2013 Total Samples: 12 Surveyed: 2 ionditions: PCI:38 ispection Comments: ample Number: 407 Type: R Area: 3,750.00SqFt PCI = 38 ample Comments: 3 BLOCK CRACKING L 1,400.00 SqFt Comments: 6 SWELLING L 242.00 SqFt Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING M 211.00 Ft Comments: 2 RAVELING M 2,400.00 SqFt Comments: 7 WEATHERING M 2,400.00 SqFt Comments: 7 WEATHERING L 1,350.00 SqFt Comments: ample Number: 410 Type: R Area: 5,000.00SqFt PCI = 37 ample Comments: 3 BLOCK CRACKING M 5,000.00 SqFt Comments: 2 RAVELING M 5,000.00 SqFt Comments: 2 RAVELING L 5,000.00 SqFt Comments:			То: -	Zone:	
ast Insp. Date: 08/27/2013 Total Samples: 12 Surveyed: 2 conditions: PCI: 38 isspection Comments: ample Number: 407 Type: R Area: 3,750.00SqFt PCI = 38 ample Comments: 3 BLOCK CRACKING L 1,400.00 SqFt Comments: 6 SWELLING L 242.00 SqFt Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments: 8 LONGITUDINAL/TRANSVERSE CRACKING M 211.00 Ft Comments: 2 RAVELING L 3,750.00 SqFt Comments: 7 WEATHERING M 2,400.00 SqFt Comments: 7 WEATHERING M 2,400.00 SqFt Comments: ample Number: 410 Type: R Area: 5,000.00 SqFt Comments: 3 BLOCK CRACKING M 5,000.00 SqFt Comments: 2 RAVELING M 5,000.00 SqFt Comments:			dth: 150.00Ft		
Area:       3,750.00SqFt       PCI = 38         ample Number:       407       Type: R       Area:       3,750.00SqFt       PCI = 38         ample Comments:       3       BLOCK CRACKING       L       1,400.00       SqFt       Comments:         3       BLOCK CRACKING       L       1,400.00       SqFt       Comments:         6       SWELLING       L       242.00       SqFt       Comments:         8       LONGITUDINAL/TRANSVERSE CRACKING       L       104.00       Ft       Comments:         8       LONGITUDINAL/TRANSVERSE CRACKING       M       211.00       Ft       Comments:         2       RAVELING       L       3,750.00       SqFt       Comments:         7       WEATHERING       M       2,400.00       SqFt       Comments:         ample Number:       410       Type: R       Area:       5,000.00SqFt       PCI = 37         ample Comments:       3       BLOCK CRACKING       M       5,000.00 SqFt       Comments:         3       BLOCK CRACKING       M       5,000.00 SqFt       Comments:       2         3       BLOCK CRACKING       M       5,000.00 SqFt       Comments:         2       RAVELING	Section Comments:				
ample Comments:       Area:       1,400.00 SqFt       Comments:         3 BLOCK CRACKING       L       1,400.00 SqFt       Comments:         6 SWELLING       L       242.00 SqFt       Comments:         8 LONGITUDINAL/TRANSVERSE CRACKING       L       104.00 Ft       Comments:         8 LONGITUDINAL/TRANSVERSE CRACKING       M       211.00 Ft       Comments:         2 RAVELING       L       3,750.00 SqFt       Comments:         7 WEATHERING       M       2,400.00 SqFt       Comments:         7 WEATHERING       L       1,350.00 SqFt       Comments:         ample Number:       410       Type: R       Area:       5,000.00 SqFt       Comments:         3 BLOCK CRACKING       M       5,000.00 SqFt       Comments:       Comments:         2 RAVELING       M       5,000.00 SqFt       Comments:         2 RAVELING       M       5,000.00 SqFt       Comments:	Conditions: PCI : 38 Inspection Comments:		3 750 00SaEt	PCI - 38	
6SWELLINGL242.00SqFtComments:8LONGITUDINAL/TRANSVERSE CRACKINGL104.00FtComments:8LONGITUDINAL/TRANSVERSE CRACKINGM211.00FtComments:2RAVELINGM211.00FtComments:7WEATHERINGL3,750.00SqFtComments:7WEATHERINGM2,400.00SqFtComments:7WEATHERINGL1,350.00SqFtComments:ample Number:410Type: RArea:5,000.00SqFtPCI = 37ample Comments:3BLOCK CRACKINGM5,000.00SqFtComments:2RAVELINGM5,000.00SqFtComments:	Sample Comments:	nica.	<i>5,75</i> 0.005q1 t	101 - 50	
8 LONGITUDINAL/TRANSVERSE CRACKING       L       104.00 Ft       Comments:         8 LONGITUDINAL/TRANSVERSE CRACKING       M       211.00 Ft       Comments:         2 RAVELING       L       3,750.00 SqFt       Comments:         7 WEATHERING       M       2,400.00 SqFt       Comments:         7 WEATHERING       L       1,350.00 SqFt       Comments:         ample Number:       410       Type: R       Area:       5,000.00 SqFt       Comments:         3 BLOCK CRACKING       M       5,000.00 SqFt       Comments:       2         2 RAVELING       M       5,000.00 SqFt       Comments:         2 RAVELING       M       5,000.00 SqFt       Comments:	43 BLOCK CRACKING	$\mathbf{L}$		Comments	3:
8 LONGITUDINAL/TRANSVERSE CRACKING       M       211.00 Ft       Comments:         2 RAVELING       L       3,750.00 SqFt       Comments:         7 WEATHERING       M       2,400.00 SqFt       Comments:         7 WEATHERING       L       1,350.00 SqFt       Comments:         ample Number:       410       Type: R       Area:       5,000.00SqFt       PCI = 37         ample Comments:       3       BLOCK CRACKING       M       5,000.00 SqFt       Comments:         2       RAVELING       M       5,000.00 SqFt       Comments:		L			
2 RAVELING       L       3,750.00 SqFt       Comments:         7 WEATHERING       M       2,400.00 SqFt       Comments:         7 WEATHERING       L       1,350.00 SqFt       Comments:         ample Number:       410       Type: R       Area:       5,000.00SqFt       PCI = 37         ample Comments:       3       BLOCK CRACKING       M       5,000.00 SqFt       Comments:         2       RAVELING       L       5,000.00 SqFt       Comments:		L			
7 WEATHERING       M       2,400.00 SqFt       Comments:         7 WEATHERING       L       1,350.00 SqFt       Comments:         ample Number:       410       Type: R       Area:       5,000.00SqFt       PCI = 37         ample Comments:					
7 WEATHERING       L       1,350.00 SqFt       Comments:         ample Number:       410       Type: R       Area:       5,000.00SqFt       PCI = 37         ample Comments:       .3       BLOCK CRACKING       M       5,000.00 SqFt       Comments:         2       RAVELING       M       5,000.00 SqFt       Comments:	- ·		_		
ample Number:410Type: RArea:5,000.00SqFtPCI = 37ample Comments:.3BLOCK CRACKINGM5,000.00 SqFtComments:2RAVELINGL5,000.00 SqFtComments:			—		
ample Comments: 3 BLOCK CRACKING M 5,000.00 SqFt Comments: 2 RAVELING L 5,000.00 SqFt Comments:	57 WEATHERING	L	1,350.00 SqFt	Comments	3:
3 BLOCK CRACKINGM5,000.00 SqFtComments:2 RAVELINGL5,000.00 SqFtComments:	Sample Number: 410 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 37	
	43 BLOCK CRACKING	М	5,000.00 SqFt	Comments	3:
7 WEATHERING M 5,000.00 SqFt Comments:	52 RAVELING	L	5,000.00 SqFt	Comments	3:
	57 WEATHERING	М	5,000.00 SqFt	Comments	3:

FDOT

<b>Re-inspection</b>	Report
----------------------	--------

	re-mspe	ction Report			
FDOT					
Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRPORT					
Branch: AP Name: APRON		Use: APRON	Area: 5	517,275.68SqFt	
Section: 4110 of 5 From: - Surface: AC Family: FDOT-GA-AP-AC		То: -	Zone:	Last Const.: Category:	01/01/1983 Rank: P
Area: 93,750.00SqFt Length: 625.00Ft	W	vidth: 150.00Ft			
Shoulder: Street Type: Grade: 0.00	Lanes: 0				
Section Comments:					
Last Insp. Date: 08/27/2013 Total Samples: 18 Surve	yed: 3				
Conditions: PCI : 30 Inspection Comments:					
Sample Number: 306 Type: R Sample Comments:	Area:	6,250.00SqFt	PCI = 40		
48 LONGITUDINAL/TRANSVERSE CRACKING	М	512.00 Ft	Comments	:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	117.00 Ft	Comments	:	
52 RAVELING	$\mathbf{L}$	6,250.00 SqFt	Comments	:	
57 WEATHERING	$\mathbf{L}$	6,250.00 SqFt	Comments	:	
49 OIL SPILLAGE	N	16.00 SqFt	Comments	:	
49 OIL SPILLAGE	N	4.00 SqFt	Comments	:	
49 OIL SPILLAGE	N	9.00 SqFt	Comments	:	
43 BLOCK CRACKING	L	1,216.00 SqFt	Comments	:	
Sample Number: 403 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 23		
43 BLOCK CRACKING	М	2,600.00 SqFt	Comments	:	
56 SWELLING	$\mathbf{L}$	194.00 SqFt	Comments	:	
52 RAVELING	М	5,000.00 SqFt	Comments	:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	191.00 Ft	Comments	:	
48 LONGITUDINAL/TRANSVERSE CRACKING	М	162.00 Ft	Comments	:	
Sample Number: 501 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 24		
52 RAVELING	М	5,000.00 SqFt	Comments	:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	74.00 Ft	Comments	:	
43 BLOCK CRACKING	М	4,200.00 SqFt	Comments	:	

<b>Re-inspection</b>	Report
----------------------	--------

FDOT	ke-msp	ection Report		
FDOT Report Generated Date: September 05, 2013				
Network: CEW Name: BOB SIKES AIRPORT				
Branch: AP Name: APRON		Use: APRON	Area: 51	7,275.68SqFt
Section: 4115 of 5 From: -		То: -	7	Last Const.: 01/01/1987
Surface: AC Family: FDOT-GA-AP-AC	Ţ	7.41.	Zone:	Category: Rank: P
Area:         187,230.68SqFt         Length:         1,350.00Ft	-	Vidth: 100.00Ft		
Shoulder: Street Type: Grade: 0.00	Lanes: 0			
Section Comments:				
Last Insp. Date: 08/27/2013 Total Samples: 37 Su	rveyed: 5			
Conditions: PCI: 32				
Inspection Comments:				
Sample Number: 200 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 34	
56 SWELLING	L	720.00 SqFt	Comments:	
43 BLOCK CRACKING	М	518.00 SqFt		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	48.00 Ft	Comments:	
52 RAVELING	L	5,000.00 SqFt		
57 WEATHERING	L	5,000.00 SqFt 574.00 Ft		
48 LONGITUDINAL/TRANSVERSE CRACKING 49 OIL SPILLAGE	M N	36.00 FC 36.00 SqFt	Comments: Comments:	
Sample Number: 203 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 27	
43 BLOCK CRACKING	М	3,800.00 SqFt	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	114.00 Ft	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	М	176.00 Ft	Comments:	
52 RAVELING	L	5,000.00 SqFt		
57 WEATHERING 56 SWELLING	L L	5,000.00 SqFt 78.00 SqFt		
56 SWELLING	M	<b>_</b>		
Sample Number: 207 Type: R	Area:	5,000.00SqFt	PCI = 33	
Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING	Н	12.00 Ft	Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	M		Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	64.00 Ft	Comments:	
52 RAVELING	L	5,000.00 SqFt		
57 WEATHERING	L	5,000.00 SqFt		
56 SWELLING	L	246.00 SqFt		
43 BLOCK CRACKING	L	680.00 SqFt	Comments:	
Sample Number: 210 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 40	
56 <sup>°</sup> SWELLING	L	72.00 SqFt		
52 RAVELING	L	5,000.00 SqFt		
57 WEATHERING	L	5,000.00 SqFt		
48 LONGITUDINAL/TRANSVERSE CRACKING 48 LONGITUDINAL/TRANSVERSE CRACKING	M L	500.00 Ft 47.00 Ft	Comments: Comments:	
48 LONGITUDINAL/TRANSVERSE CRACKING 43 BLOCK CRACKING	L L	47.00 Ft 192.00 SqFt		
Sample Number: 312 Type: R Sample Comments:	Area:	5,750.00SqFt	PCI = 27	
56 SWELLING	L	2,522.00 SqFt	Comments:	
52 RAVELING	L	5,750.00 SqFt		
	_	1-		

FDOT	-	•	
Report Generated Date: September 05, 2013			
57 WEATHERING	L	5,750.00 SqFt	Comments:
43 BLOCK CRACKING	М	5,750.00 SqFt	Comments:

EDOT	Re-IIIs	specific	on Kepor	L			
FDOT Report Generated Date: September 05, 2013							
Network: CEW Name: BOB SIKES AIRPORT							
Branch: AP Name: APRON			Use: APF	RON	Area:	517,275.68SqFt	
Section: 4120 of 5 From: - Surface: AAC Family: FDOT-GA-AP-AC			То: -		Zone:	Last Const.:	03/01/2012
Surface: AAC Family: FDOT-GA-AP-AC Area: 147,645.00SqFt Length: 730.00Ft	ŀ	Width:	185.00F	't	Zone:	Category:	Rank: P
Shoulder: Street Type: Grade: 0.00	Lanes:		105.001	L			
Section Comments:							
NOTE: *** Pre-Construction PCI ***							
	urveyed: 5						
Conditions: PCI: 65							
Inspection Comments: KHA							
Sample Number: 113 Type: R Sample Comments:	Area:	2,50	00.00SqFt		PCI = 62		
43 BLOCK CRACKING		L	1,250.00		Comment	s:	
48 LONGITUDINAL/TRANSVERSE CRACKING		L T	22.00		Comment		
52 RAVELING		L	1,000.00	Sdrt	Comment	S •	
Sample Number: 215 Type: R Sample Comments:	Area:	5,00	00.00SqFt		PCI = 73		
48 LONGITUDINAL/TRANSVERSE CRACKING		L	442.00		Comment	s:	
52 RAVELING		L	800.00	SqFt	Comment	s:	
Sample Number: 316 Type: R Sample Comments:	Area:	5,00	00.00SqFt		PCI = 65		
43 BLOCK CRACKING		L	396.00		Comment	s:	
48 LONGITUDINAL/TRANSVERSE CRACKING		M	200.00		Comment		
52 RAVELING 43 BLOCK CRACKING		L L	1,200.00 625.00	-	Comment Comment		
				1 -			
Sample Number: 317 Type: R Sample Comments:	Area:	5,00	00.00SqFt		PCI = 68		
48 LONGITUDINAL/TRANSVERSE CRACKING		М	251.00	Ft	Comment	s:	
43 BLOCK CRACKING		L	1,300.00		Comment	s:	
Sample Number: 319 Type: R Sample Comments:	Area:	5,00	00.00SqFt		PCI = 55		
48 LONGITUDINAL/TRANSVERSE CRACKING		М	319.00		Comment		
48 LONGITUDINAL/TRANSVERSE CRACKING		H	58.00		Comment		
52 RAVELING 43 BLOCK CRACKING		L L	1,800.00 600.00		Comment Comment		
12 DROCK CIVECITING		ш	000.00	DAT C	Comment	· ·	

Network: CEW Name: BOB SIKES AIRPORT					
Branch: AP Name: APRON		Use: APRON	Area: 517	7,275.68SqFt	
Section: 4130 of 5 From: -		То: -		Last Const.:	03/01/2012
Surface: PCC Family: FDOT-GA-PCC			Zone:	Category:	Rank: P
Area: 32,400.00SqFt Length: 432.00Ft	Width:	75.00Ft			
Slabs: 144 Slab Width: 15.00Ft	Slab Length:	15.00Ft	Joint Length:	3,813.00Ft	
Shoulder: Street Type: Grade: 0.00	Lanes: 0				
Section Comments:					
Total Samples 0 Summer	and o				
Last Insp. Date: Total Samples: 0 Survey	/ed: 0				

Sample Number:Type:Area:0.00<NO</td>VALIDINSPECTIONS>0.00

FDOT

FDOT	ne mspecuo	n noport			
Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRPORT					
Branch: AP HANG Name: HANGAR APRON		Use: APRON	Area:	25,113.72SqFt	
Section: 4205 of 2 From: -		То: -		Last Const.:	01/01/1994
Surface: AC Family: FDOT-GA-AP-AC			Zone:	Category:	Rank: P
Area: 18,010.19SqFt Length: 350.00Ft	Width:	35.00Ft			
Shoulder: Street Type: Grade: 0.00	Lanes: 0				
Section Comments: Last Insp. Date: 08/27/2013 Total Samples: 4 Sur Conditions: PCI : 62 Inspection Comments:	veyed: 1				
Sample Number: 201 Type: R Sample Comments:	Area: 4,06	0.00SqFt	PCI = 62		
50 PATCHING	L	987.00 SqFt	Comments	:	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	26.00 Ft	Comments	:	
52 RAVELING		3,073.00 SqFt	Comments		
57 WEATHERING	L 3	3,073.00 SqFt	Comments	:	

FDOT Report Generated Date: September 05, 2013 Network: CEW Name: BOB SIKES AIRPORT Branch: AP HANG Name: HANGAR APRON Use: APRON Area: 25,113.72 Section: 4210 of 2 From: - To: - Last	!SqFt
Branch: AP HANG Name: HANGAR APRON Use: APRON Area: 25,113.72	'SqFt
	?SqFt
Section: 1210 of 2 From: To: Last	
	Const.: 01/01/1963 egory: Rank: P
Area: 7,103.53SqFt Length: 350.00Ft Width: 20.00Ft	
Shoulder: Street Type: Grade: 0.00 Lanes: 0	
Inspection Comments:	
Sample Number:301Type: RArea:2,320.00SqFtPCI = 18Sample Comments:	
50 PATCHING M 864.00 SqFt Comments:	
50 PATCHING L 300.00 SqFt Comments:	
50 PATCHING L 237.00 SqFt Comments:	
50 PATCHING H 21.00 SqFt Comments:	
45 DEPRESSION M 65.00 SqFt Comments: 52 PAVELINC H 8.00 SqFt Comments:	
45 DEPRESSIONM65.00 SqFtComments:52 RAVELINGH8.00 SqFtComments:43 BLOCK CRACKINGM898.00 SqFtComments:	

FDOT	ac-mspec	uon Keport			
Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRPORT					
Branch: AP N Name: NORTH APRON		Use: APRON	Area:	261,875.13SqFt	
Section: 4340 of 4 From: -		То: -		Last Const.:	11/01/2012
Surface: AAC Family: FDOT-GA-AP-AC			Zone:	Category:	Rank: P
Area: 33,815.64SqFt Length: 330.00Ft	Wid	th: 100.00Ft			
Shoulder: Street Type: Grade: 0.00	Lanes: 0				
Section Comments:					
NOTE: *** Pre-Construction PCI ***					
Last Insp. Date: 02/07/2011 Total Samples: 6 Surve Conditions: PCI: 70	eyed: 1				
Inspection Comments: KHA					
Sample Number: 201 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 70		
-	L	348.00 Ft	Comments	:	
48 LONGITUDINAL/TRANSVERSE CRACKING	-	510.00 10			
48 LONGITUDINAL/TRANSVERSE CRACKING 52 RAVELING	L	3,000.00 SqFt	Comments		

FDOT		ne mspee				
_	:: September 05, 2013					
Network: CEW	Name: BOB SIKES AI	RPORT				
Branch: AP N	Name: NORTH APRO	N	Use: APRON	Area:	261,875.13SqFt	
Section: 4345	of 4 From: -		To: -		Last Const.:	11/01/2012
Surface: AC	Family: FDOT-GA-	AP-AC		Zone:	Category:	Rank: P
Area: 99,461.38SqF	t Length:	541.00Ft Wid	th: 155.00Ft			
Shoulder: Stree	t Type: Grade: 0	.00 Lanes: 0				
Section Comments:						
Last Insp. Date:	Total Samples: 0	Surveyed: 0				
Conditions:						
Sample Number:	Type:	Area:	0.00			

Sample Number: Type: <NO VALID INSPECTIONS>

0.

Branch: AP N Name: NORTH APRON	Use: APRON			
		Area: 26	1,875.13SqFt	
Section: 4350 of 4 From: -	То: -		Last Const.:	11/01/2012
Surface: PCC Family: FDOT-GA-PCC		Zone:	Category:	Rank: P
Area: 23,279.79SqFt Length: 150.00Ft Width:	155.00Ft			
Slabs: 103 Slab Width: 15.00Ft Slab Length:	15.00Ft	Joint Length:	2,795.00Ft	
Shoulder: Street Type: Grade: 0.00 Lanes: 0				
Section Comments:				

Sample Number:Type:Area:0.00<NO</td>VALIDINSPECTIONS>

FDOT Papart Congrated Date	e: September 05, 2013	110 1115 1000	1011 110p 011			
Network: CEW	Name: BOB SIKES AIF	RPORT				
Branch: AP N	Name: NORTH APRON	1	Use: APRON	Area:	261,875.13SqFt	
Section: 4355	of 4 From: -		То: -		Last Const.:	11/01/2012
Surface: AC Area: 105,318.32SqF Shoulder: Stree	Family: FDOT-GA-A Ft Length: 6 et Type: Grade: 0.	60.00Ft Width	h: 155.00Ft	Zone:	Category:	Rank: P
Section Comments:						
Last Insp. Date: Conditions:	Total Samples: 0	Surveyed: 0				
Sample Number:	Type:	Area:	0.00			

Sample Number: Type: <NO VALID INSPECTIONS>

0.

FDOT Papart Congrated Data: Soptambar 05, 2013					
Report Generated Date: September 05, 2013 Network: CEW Name: BOB SIKES A	IRPORT				
Branch: AP RU Name: WEST RUN-U	P APRON AT RW 1	Use: APRON	Area:	46,559.69SqFt	
Section: 5105 of 1 From: - Surface: AAC Family: FDOT-GA-	AP-AC	To: -	Zone:	Last Const.: Category:	11/01/2012 Rank: Р
Area: 46,559.69SqFt Length:	415.00Ft Wid	th: 100.00Ft			
Shoulder: Street Type: Grade: (	0.00 Lanes: 0				
NOTE: *** Pre-Construction PCI *** Last Insp. Date: 02/07/2011 Total Samples: 12	Surveyed: 2				
Last Insp. Date: 02/07/2011 Total Samples: 12 Conditions: PCI: 90	Surveyed: 2				
Last Insp. Date: 02/07/2011 Total Samples: 12 Conditions: PCI: 90 Inspection Comments: KHA Sample Number: 100 Type: R		3,810.00SqFt	PCI = 89		
Last Insp. Date: 02/07/2011 Total Samples: 12 Conditions: PCI: 90 Inspection Comments: KHA Sample Number: 100 Type: R Sample Comments:	Area:	3,810.00SqFt 59.00 Ft	PCI = 89 Comments		
Last Insp. Date: 02/07/2011 Total Samples: 12 Conditions: PCI: 90 Inspection Comments: KHA Sample Number: 100 Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRAC	Area:				
Last Insp. Date: 02/07/2011 Total Samples: 12 Conditions: PCI: 90 Inspection Comments: KHA Sample Number: 100 Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRAC: 52 RAVELING Sample Number: 202 Type: R	Area: KING L L	59.00 Ft	Comments		
Last Insp. Date: 02/07/2011 Total Samples: 12 Conditions: PCI:90 Inspection Comments: KHA Sample Number: 100 Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRAC: 52 RAVELING	Area: KING L L Area:	59.00 Ft 100.00 SqFt	Comments: Comments:		

FDOT	Ke-mspe	cuon Report			
Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRPORT					
Branch: RW 17-35 Name: RUNWAY 17-35		Use: RUNWAY	Area: 1,2	200,000.00SqFt	
Section: 6105 of 6 From: - Surface: AC Family: FDOT-GA-RW-AC		То: -	Zone:	Last Const.: Category:	01/01/2008 Rank: P
Area:80,000.00SqFtLength:800.00FtShoulder:Street Type:Grade:0.00	W Lanes: 0	idth: 100.00Ft			
Section Comments:					
Last Insp. Date: 08/27/2013 Total Samples: 16 Su Conditions: PCI : 79 Inspection Comments:	rveyed: 5				
Sample Number: 301 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 80		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	272.00 Ft	Comments	:	
57 WEATHERING	L	2,500.00 SqFt	Comments	:	
Sample Number: 303 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 77		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	340.00 Ft	Comments	:	
57 WEATHERING	L	4,000.00 SqFt	Comments	:	
Sample Number: 306 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 77		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	336.00 Ft	Comments	:	
57 WEATHERING	L	3,500.00 SqFt	Comments	:	
Sample Number: 310 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 78		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	317.00 Ft	Comments		
57 WEATHERING	L	3,000.00 SqFt	Comments	:	
Sample Number: 313 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 84		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	177.00 Ft	Comments	:	
57 WEATHERING	L	3,500.00 SqFt	Comments	:	

FDOT Report Generated Date: September 05, 2013				
	Use: RUNWAY	Area: 1,20	0,000.00SqFt	
	То: -		Last Const.:	01/01/2008
		Zone:	Category:	Rank: P
Width:	25.00Ft			
Lanes: 0				
Area: 5,00	00.00SqFt	PCI = 88		
$\mathbf{L}$	87.00 Ft	Comments:		
L :	2,500.00 SqFt	Comments:		
Area: 5,00	00.00SqFt	PCI = 90		
L	74.00 Ft	Comments:		
	Width: Lanes: 0 eyed: 2 Area: 5,00 L L 2	Image: Line size of the system       Use: RUNWAY         To: -       To: -         Width:       25.00Ft         Lanes:       0         eyed:       2         Area:       5,000.00SqFt         L       87.00 Ft         L       2,500.00 SqFt	L       Use: RUNWAY       Area: 1,20         To: -       Zone:         Width:       25.00Ft         Lanes:       0         Eved:       2         Area:       5,000.00SqFt       PCI = 88         L       87.00 Ft       Comments:         L       2,500.00 SqFt       Comments:	Use: RUNWAY       Area:       1,200,000.00SqFt         To: -       Last Const.:         Zone:       Category:         Width:       25.00Ft         Lanes:       0         eyed:       2         Area:       5,000.00SqFt       PCI = 88         L       87.00 Ft       Comments:         L       2,500.00 SqFt       Comments:

	Re-Ins	pection	n Report					
FDOT Report Generated Date: September 05, 2013								
Network: CEW Name: BOB SIKES AIRPORT								
Branch: RW 17-35 Name: RUNWAY 17-35			Use: RUNV	WAY	Area:	1,200	,000.00SqFt	
Section: 6115 of 6 From: - Surface: AC Family: FDOT-GA-RW-AAC	2		То: -		Zone:		Last Const.: Category:	01/01/2008 Rank: P
Area: 420,000.00SqFt Length: 4,200.00Ft		Width:	100.00Ft					
Shoulder: Street Type: Grade: 0.00	Lanes:	0						
Section Comments:								
Last Insp. Date: 08/27/2013 Total Samples: 84 Su Conditions: PCI : 91 Inspection Comments:	rveyed: 1	8						
Sample Number: 316 Type: R Sample Comments:	Area:	5,000	).00SqFt	Р	PCI = 86			
48 LONGITUDINAL/TRANSVERSE CRACKING 57 WEATHERING		L L 3	122.00 F ,000.00 S		Commen Commen			
Sample Number: 321 Type: R	Area:		).00SqFt		PCI = 87			
Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING		L	112.00 F	't	Commen	ts:		
57 WEATHERING		L 3	,000.00 S	SqFt	Commen	ts:		
Sample Number: 326 Type: R Sample Comments:	Area:		).00SqFt		PCI = 90			
57 WEATHERING 48 LONGITUDINAL/TRANSVERSE CRACKING		L 2 L	,500.00 S 52.00 F		Commen			
40 LONGITUDINAL/IRANSVERSE CRACKING		Ц	52.00 F	L	Commen			
Sample Number: 331 Type: R Sample Comments:	Area:		0.00SqFt		PCI = 88			
57 WEATHERING 48 LONGITUDINAL/TRANSVERSE CRACKING		L 2 L	,500.00 S 97.00 F		Commen Commen			
Sample Number: 336 Type: R Sample Comments:	Area:	5,000	).00SqFt	Р	PCI = 91			
48 LONGITUDINAL/TRANSVERSE CRACKING		L	19.00 F		Commen			
57 WEATHERING		L 2	,500.00 S	SqFt	Commen	ts:		
Sample Number: 341 Type: R Sample Comments:	Area:	5,000	).00SqFt	Р	PCI = 95			
57 WEATHERING		L 2	,500.00 S	βqFt	Commen	ts:		
Sample Number: 346 Type: R Sample Comments:	Area:	5,000	).00SqFt	Р	PCI = 90			
48 LONGITUDINAL/TRANSVERSE CRACKING		L	60.00 F		Commen			
57 WEATHERING		ь 3	,000.00 S	SqFt	Commen	ts:		
Sample Number: 351 Type: R Sample Comments:	Area:	5,000	).00SqFt	Р	PCI = 86			
48 LONGITUDINAL/TRANSVERSE CRACKING		L I	60.00 F		Commen			
57 WEATHERING 52 RAVELING		L 3 L	,000.00 S		Commen Commen			
Sample Number: 355 Type: R	Area:	5,000	).00SqFt	Р	PCI = 89			
Sample Comments: 57 WEATHERING		L 4	,000.00 S	gFt	Commen	ts:		

Report Generated Date. Sep	2013					
52 RAVELING			L	150.00	SqFt	Comments:
Sample Number: 360 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 91
57 WEATHERING			L	3,500.00	SqFt	Comments:
52 RAVELING			L	100.00	SqFt	Comments:
Sample Number: 365 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 95
57 WEATHERING			L	3,000.00	SqFt	Comments:
Sample Number: 370 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 91
48 LONGITUDINAL/T	RANSVERSE CRACKING		L	14.00	Ft	Comments:
57 WEATHERING			L	3,500.00	SqFt	Comments:
Sample Number: 375 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 88
	RANSVERSE CRACKING		L	25.00	Ft	Comments:
57 WEATHERING			L	4,000.00	SqFt	Comments:
52 RAVELING			L	50.00	SqFt	Comments:
Sample Number: 380 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 90
-	RANSVERSE CRACKING		L	35.00	Ft	Comments:
57 WEATHERING			L	3,500.00	SqFt	Comments:
Sample Number: 385 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 95
57 WEATHERING			L	2,500.00	SqFt	Comments:
Sample Number: 390 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 95
57 WEATHERING			L	2,500.00	SqFt	Comments:
Sample Number: 394 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 97
57 WEATHERING			L	1,000.00	SqFt	Comments:
Sample Number: 399 Sample Comments:	Type: R	Area:		5,000.00SqFt		PCI = 98
57 WEATHERING			L	500.00	SqFt	Comments:

			Keport	inspectio	N					EDOT
					3	05 2013	entember	Date: S	Generated I	FDOT Report (
					ES AIRPORT		-	24415	rk: CEW	-
Ft	1,200,000.00SqFt	Area: 1,20	Use: RUNWAY		Y 17-35	RUNWAY	Name:	-35	: RW 17-	Branch:
	Last Const.: Category:	Zone:	То: -		m: - Γ-GA-RW-AAC		of 6 Famil			Section: Surface:
j	8).		25.00Ft	Width:	8,400.00Ft	ength:		0SqFt	210,000.00	Area:
				nes: 0	de: 0.00	-		Street T		Shoulder
									Comments:	Section C
				8	42 Surve	Samples:	13 Total S	93	sp. Date: 08 ons: PCI : on Comments	Conditio
		PCI = 91	)SqFt	ea: 5,00		ype: R	Ту	120	Number: Comments:	
	:s:	Comments:	21.00 Ft	L	RACKING	ERSE CRA	TRANSVE	INAL/		
	:s:	Comments:	000.00 SqFt	L 3				NG	EATHERIN	57 WE2
		PCI = 92	)SqFt	ea: 5,00		ype: R	Ту	148	Number: Comments:	
	s:	Comments:	000.00 SqFt					NG	EATHERIN	57 WE2
	:s:	Comments:	84.00 SqFt	L					AVELING	52 RAV
		PCI = 96	)SqFt	ea: 5,00		ype: R	Ту	172	Number: Comments:	-
	:s:	Comments:	000.00 SqFt	L 2				NG	EATHERIN	57 WE2
		PCI = 96	)SqFt	ea: 5,00		ype: R	Ту	196	Number: Comments:	
	:s:	Comments:	500.00 SqFt	L 1				NG	EATHERIN	-
		PCI = 91	)SqFt	ea: 5,00		ype: R	Ту	524	Number: Comments:	
	:s:	Comments:	51.00 Ft	L	RACKING	ERSE CRA	TRANSVE		ONGITUDI	48 LOI
	:s:	Comments:	00.00 SqFt	L 2				NG	EATHERIN	57 WE2
		PCI = 87	ØSqFt	ea: 5,00		ype: R	Ту	548	Number: Comments:	-
		Comments:	00.00 SqFt					NG	EATHERIN	57 WE2
	:s:	Comments:	319.00 SqFt	L					AVELING	52 RAV
		PCI = 96	)SqFt	ea: 5,00		ype: R	Ту	572	Number: Comments:	
	s:	Comments:	00.00 SqFt	L 1				NG	EATHERIN	
		PCI = 97	)SqFt	ea: 5,00		ype: R	Ту	596	Number: Comments:	
	:s:	Comments:	000.00 SqFt	L 1				NG	EATHERIN	
	:s:					ype: R	Ту		Comments:	Sample C

FDOT	<b>IXC-1115</b>	spection R	port			
Report Generated Date: September 05, 2013						
Network: CEW Name: BOB SIKES AIRP	ORT					
Branch: RW 17-35 Name: RUNWAY 17-35		U	se: RUNWAY	Area:	1,200,000.00SqFt	
Section: 6125 of 6 From: - Surface: AC Family: FDOT-GA-RW	/-AAC		То: -	Zone:	Last Const.: Category:	01/01/2008 Rank: P
Area: 300,000.00SqFt Length: 3,000	).00Ft	Width:	100.00Ft			
Shoulder: Street Type: Grade: 0.00	Lanes:	0				
Section Comments:						
Last Insp. Date: 08/27/2013 Total Samples: 60 Conditions: PCI: 84 Inspection Comments:	Surveyed: 1	2				
Sample Number: 400 Type: R Sample Comments:	Area:	5,000.00Sql	Ft	PCI = 98		
57 WEATHERING		L 500	).00 SqFt	Comment	s:	
Sample Number: 404 Type: R Sample Comments:	Area:	5,000.00Sql	Ft	PCI = 94		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG		2.00 Ft	Comment		
57 WEATHERING		L 1,500	).00 SqFt	Comment	s:	
Sample Number: 410 Type: R Sample Comments:	Area:	5,000.00Sql	Ŧ	PCI = 92		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG	L 12	2.00 Ft	Comment	s:	
57 WEATHERING		L 2,000	).00 SqFt	Comment	s:	
Sample Number: 416 Type: R Sample Comments:	Area:	5,000.00Sql	Ft	PCI = 91		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG		5.00 Ft	Comment		
57 WEATHERING		L 2,500	).00 SqFt	Comment	s:	
Sample Number: 422 Type: R Sample Comments:	Area:	5,000.00Sql	Ft	PCI = 94		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG		5.00 Ft	Comment		
57 WEATHERING		L 1,000	).00 SqFt	Comment	s:	
Sample Number: 428 Type: R Sample Comments:	Area:	5,000.00Sql	Ft	PCI = 77		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG		).00 Ft	Comment		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG		8.00 Ft	Comment		
57 WEATHERING		L 1,500	).00 SqFt	Comment	s:	
Sample Number: 433 Type: R Sample Comments:	Area:	5,000.00Sql	Ft	PCI = 73		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG		5.00 Ft	Comment		
57 WEATHERING		L 2,000	).00 SqFt	Comment	s:	
Sample Number: 440 Type: R Sample Comments:	Area:	5,000.00Sq1	Ft	PCI = 74		
48 LONGITUDINAL/TRANSVERSE CRACKI			).00 Ft	Comment		
48 LONGITUDINAL/TRANSVERSE CRACKI 57 WEATHERING	NG		).00 Ft ).00 SqFt	Comment Comment		
		L 2,300	byru	Comment	v ·	
Sample Number: 445 Type: R Sample Comments:	Area:	5,000.00Sql	Ft	PCI = 73		

	pee	non nepoi			
	-	-			
	L	450.00	Ft	Comments:	
	L	24.00	Ft	Comments:	
	L	2,000.00	SqFt	Comments:	
Area:		5,000.00SqFt		PCI = 77	
	L	250.00	Ft	Comments:	
	L	77.00	Ft	Comments:	
	L	2,500.00	SqFt	Comments:	
Area:		5,000.00SqFt		PCI = 75	
	L	400.00	Ft	Comments:	
	L				
	L			Comments:	
Area:		5,000.00SqFt		PCI = 96	
	L			Comments:	
	Area: Area:	L L L L Area: L L L Area:	L $450.00$ L $24.00$ L $24.00$ L $24.00$ L $24.00$ L $2,000.00$ Area: $5,000.00$ SqFt         L $250.00$ L $77.00$ L $2,500.00$ Area: $5,000.00$ SqFt         L $400.00$ L $8.00$ L $2,000.00$ Area: $5,000.00$ SqFt         L $2,000.00$	L       24.00 Ft         L       24.00 Ft         L       2,000.00 SqFt         Area:       5,000.00SqFt         L       250.00 Ft         L       2,500.00 SqFt         L       2,500.00 SqFt         Area:       5,000.00SqFt         L       400.00 Ft         L       8.00 Ft         L       2,000.00 SqFt         L       2,000.00 SqFt	L       450.00 Ft       Comments:         L       24.00 Ft       Comments:         L       24.00 Ft       Comments:         L       2,000.00 SqFt       Comments:         Area:       5,000.00SqFt       PCI = 77         L       250.00 Ft       Comments:         L       77.00 Ft       Comments:         L       2,500.00 SqFt       Comments:         L       2,500.00 SqFt       Comments:         L       2,000.00 SqFt       Comments:         L       2,000.00 SqFt       Comments:         L       400.00 Ft       Comments:         L       8.00 Ft       Comments:         L       2,000.00 SqFt       Comments:         Area:       5,000.00SqFt       PCI = 96

FDOT	Ke-msp	ection Report			
FDOT Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRPORT					
Branch: RW 17-35 Name: RUNWAY 17-35		Use: RUNWAY	Area: 1,	200,000.00SqFt	
Section: 6130 of 6 From: - Surface: AC Family: FDOT-GA-RW-AAC		То: -	Zone:	Last Const.: Category:	01/01/2008 Rank: P
Area:150,000.00SqFtLength:6,000.00FtShoulder:Street Type:Grade:0.00		Vidth: 25.00Ft			
Section Comments:					
Last Insp. Date: 08/27/2013 Total Samples: 30 Su Conditions: PCI: 85 Inspection Comments:	rveyed: 5				
Sample Number: 204 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 95		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	10.00 Ft	Comments	:	
57 WEATHERING	L	500.00 SqFt	Comments	:	
Sample Number: 224 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 81		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	257.00 Ft	Comments	:	
57 WEATHERING	L	1,500.00 SqFt	Comments	:	
Sample Number: 252 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 75		
48 LONGITUDINAL/TRANSVERSE CRACKING	L		Comments	:	
57 WEATHERING	L	1,000.00 SqFt	Comments	:	
Sample Number: 616 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 96		
48 LONGITUDINAL/TRANSVERSE CRACKING	L		Comments	:	
57 WEATHERING	L	500.00 SqFt	Comments	:	
Sample Number: 628 Type: R Sample Comments:	Area:	5,000.00SqFt	PCI = 76		
48 LONGITUDINAL/TRANSVERSE CRACKING	L	405.00 Ft	Comments	:	
57 WEATHERING	L	1,500.00 SqFt	Comments	:	

<b>Re-inspection</b>	Report
----------------------	--------

FDOT Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRPORT					
Branch: TW A Name: TAXIWAY A		Use: TAXIWAY	Area:	748,518.75SqFt	
Section: 105 of 6 From: -		То: -	-	Last Const.:	11/01/2012
Surface: AAC Family: FDOT-GA-TW-AAC			Zone:	Category:	Rank: P
Area: 98,453.32SqFt Length: 1,200.00Ft	W	idth: 50.00Ft			
Shoulder: Street Type: Grade: 0.00	Lanes: 0				
Section Comments:					
NOTE: *** Pre-Construction PCI ***					
	veyed: 2				
Last Insp. Date: 02/07/2011 Total Samples: 7 Surv	reyed: 2				
NOTE: *** Pre-Construction PCI *** Last Insp. Date: 02/07/2011 Total Samples: 7 Surv Conditions: PCI : 50 Inspection Comments: KHA	reyed: 2				
Last Insp. Date: 02/07/2011 Total Samples: 7 Surv Conditions: PCI: 50 Inspection Comments: KHA Sample Number: 101 Type: R	reyed: 2 Area:	5,000.00SqFt	PCI = 48		
Last Insp. Date: 02/07/2011 Total Samples: 7 Surv Conditions: PCI: 50 Inspection Comments: KHA Sample Number: 101 Type: R Sample Comments:		5,000.00SqFt 321.00 Ft	PCI = 48 Comments	5 :	
Last Insp. Date: 02/07/2011 Total Samples: 7 Surv Conditions: PCI: 50 Inspection Comments: KHA Sample Number: 101 Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING	Area:				
Last Insp. Date: 02/07/2011 Total Samples: 7 Surv Conditions: PCI: 50 Inspection Comments: KHA Sample Number: 101 Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 52 RAVELING Sample Number: 110 Type: R	Area:	321.00 Ft	Comments		
Last Insp. Date: 02/07/2011 Total Samples: 7 Surv Conditions: PCI: 50 Inspection Comments: KHA Sample Number: 101 Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 52 RAVELING Sample Number: 110 Type: R Sample Comments:	Area: M M	321.00 Ft 3,100.00 SqFt	Comments Comments	;:	
Last Insp. Date: 02/07/2011 Total Samples: 7 Surv Conditions: PCI: 50 Inspection Comments: KHA Sample Number: 101 Type: R Sample Comments: 48 LONGITUDINAL/TRANSVERSE CRACKING 52 RAVELING	Area: M M Area:	321.00 Ft 3,100.00 SqFt 5,000.00SqFt	Comments Comments PCI = 52	5 :	

FDOT	ite msp	cetton Report			
Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRP	ORT				
Branch: TW A Name: TAXIWAY A		Use: TAXIWAY	Area: 74	48,518.75SqFt	
Section: 110 of 6 From: -		То: -		Last Const.:	11/01/2012
Surface: AAC Family: FDOT-GA-TW	-AAC		Zone:	Category:	Rank: P
Area: 303,843.25SqFt Length: 4,300	0.00Ft W	Vidth: 50.00Ft			
Shoulder: Street Type: Grade: 0.00	Lanes: 0				
Section Comments:					
NOTE: *** Pre-Construction PCI ***					
Last Insp. Date: 02/07/2011 Total Samples: 43	Surveyed: 5				
Conditions: PCI: 67					
Inspection Comments: KHA					
Samula Number 115 Turas D	A.r	5 000 000 -E4	PCI = 69		
Sample Number: 115 Type: R Sample Comments:	Area:	5,000.00SqFt	$\Gamma CI = 09$		
43 BLOCK CRACKING	L	3,100.00 SqFt	Comments:		
	_	0,100,000 0410			
Sample Number: 125 Type: R	Area:	5,000.00SqFt	PCI = 63		
Sample Comments:					
43 BLOCK CRACKING	L	2,100.00 SqFt	Comments:		
43 BLOCK CRACKING	M	100.00 SqFt	Comments:		
52 RAVELING	L	2,000.00 SqFt	Comments:		
Sample Number: 136 Type: R	Area:	5,000.00SqFt	PCI = 71		
Sample Comments:	NO		Commont a t		
48 LONGITUDINAL/TRANSVERSE CRACKI 43 BLOCK CRACKING	NG L	273.00 Ft 165.00 SqFt	Comments: Comments:		
52 RAVELING	L	2,000.00 SqFt	Comments:		
		2,000.00 5410	conmerred		
Sample Number: 147 Type: R	Area:	5,000.00SqFt	PCI = 71		
Sample Comments:					
48 LONGITUDINAL/TRANSVERSE CRACKI	NG L	200.00 Ft	Comments:		
43 BLOCK CRACKING	L	400.00 SqFt	Comments:		
52 RAVELING	L	2,000.00 SqFt	Comments:		
Sample Number: 153 Type: R	Area:	5,000.00SqFt	PCI = 62		
Sample Comments:	_		<b>a</b> .		
43 BLOCK CRACKING	L	2,800.00 SqFt	Comments:		
52 RAVELING		2,200.00 SqFt	Comments:		
48 LONGITUDINAL/TRANSVERSE CRACKI	NG L	18.00 Ft	Comments:		

FDOT				spec	tion Report			
FDOT		1 05 0010						
Report Generated D	Date: Septem	ber 05, 2013						
Network: CEW	Nan	ne: BOB SIKES AIRPORT						
Branch: TW A	Nan	ne: TAXIWAY A			Use: TAXIWAY	Area:	748,518.75SqFt	
Section: 125 Surface: AAC	of	6 From: - amily: FDOT-GA-TW-AC			То: -	Zone:	Last Const.: Category:	11/01/2012 Rank: P
Area: 267,093.11		Length: 3,700.00Ft		Wic	lth: 50.00Ft	Zone.	Category.	Kalik. F
,	sqri treet Type:	Grade: 0.00	Lanes:		itii. 50.00Ft			
Shoulder. St	licet Type.	01ade. 0.00	Lanes.	0				
Section Comments:								
Conditions: PCI:9 Inspection Comments: Sample Number: Sample Comments: 52 RAVELING	КНА 101	Type: R SVERSE CRACKING	Area:	L	7,500.00SqFt 200.00 SqFt 165.00 Ft	PCI = 87 Comments Comments		
46 LONGIIODI	NAL/ IRAN	SVERSE CRACKING		Ц	105.00 FC	Comments	•	
Sample Number: Sample Comments:	108	Type: R	Area:		5,000.00SqFt	PCI = 92		
•	NAL/TRAN	SVERSE CRACKING		L	34.00 Ft	Comments	:	
52 RAVELING				L	100.00 SqFt	Comments	:	
Sample Number: Sample Comments:	118	Type: R	Area:		5,000.00SqFt	PCI = 96		
52 RAVELING				L	100.00 SqFt	Comments	:	
Sample Number:	128	Type: R	Area:		5,000.00SqFt	PCI = 96		
Sample Comments: 52 RAVELING				L	100.00 SqFt	Comments	:	

FDOT Report Concreted Date	Sentember 05, 2012					
Network: CEW	Name: BOB SIKES AI	RPORT				
Branch: TW A	Name: TAXIWAY A		Use: TAXIWAY	Area:	748,518.75SqFt	
Section: 140	of 6 From: -		То: -	-	Last Const.:	11/01/2012
Surface:ACArea:27,340.32SqFShoulder:Stree	e	W-AC 50.00Ft Widt 00 Lanes: 0	th: 130.00Ft	Zone:	Category:	Rank: P
Section Comments:						
Last Insp. Date: Conditions:	Total Samples: 0	Surveyed: 0				
Sample Number:	Type:	Area:	0.00			

Sample Number: Type: <NO VALID INSPECTIONS>

FDOT Report Generated Date	e: September 05, 2013					
Network: CEW	Name: BOB SIKES AI	RPORT				
Branch: TW A	Name: TAXIWAY A		Use: TAXIWAY	Area:	748,518.75SqFt	
Section: 150 Surface: AC	of 6 From: - Family: FDOT-GA-'		То: -	Zone:	Last Const.:	11/01/2012 Rank: Р
Area: 25,815.68SqF	t Length:	1W-AC 150.00Ft Width .00 Lanes: 0	n: 130.00Ft	Zone.	Category:	Kank: P
Section Comments:						
Last Insp. Date: Conditions:	Total Samples: 0	Surveyed: 0				
Sample Number:	Type:	Area:	0.00			

Sample Number: Type: <NO VALID INSPECTIONS>

FDOT Report Congrated Date	September 05, 2013					
Network: CEW	Name: BOB SIKES AI	RPORT				
Branch: TW A	Name: TAXIWAY A		Use: TAXIWAY	Area:	748,518.75SqFt	
Section: 160	of 6 From: -		То: -	_	Last Const.:	11/01/2012
Surface:ACArea:25,973.07SqFShoulder:Stree	e		Width: 130.00Ft	Zone:	Category:	Rank: P
Section Comments:						
Last Insp. Date: Conditions:	Total Samples: 0	Surveyed: 0				
Sample Number:	Type:	Area:	0.00			

Sample Number: Type: <NO VALID INSPECTIONS>

0

FDOT Report Generated Date:	September 05, 2013		speene	in report			
Network: CEW	Name: BOB SIKES AIRPOR	Т					
Branch: TW A2	Name: TAXIWAY A2			Use: TAXIWAY	Area:	54,611.89SqFt	
Section: 115 Surface: AAC	of 1 From: - Family: FDOT-GA-TW-A	AC		То: -	Zone:	Last Const.: Category:	11/01/2012 Rank: P
Area: 54,611.89SqFt Shoulder: Street	Length: 300.00 Type: Grade: 0.00	Ft Lanes:	Width:	50.00Ft			
Section Comments:							
NOTE: *** Pre-Cons Last Insp. Date: 02/07/2 Conditions: PCI: 52 Inspection Comments: KHA	011 Total Samples: 3	Surveyed:	1				
Sample Number: 101 Sample Comments:	Type: R	Area:	5,00	00.00SqFt	PCI = 52		
43 BLOCK CRACKI	NG /TRANSVERSE CRACKING	ł	М	2,000.00 SqFt 24.00 Ft 2,000.00 SqFt	Comments Comments Comments	:	

FDOT Report Generated Date: S	eptember 05, 2013		Jeenon				
Network: CEW	Name: BOB SIKES AIRPORT						
Branch: TW A3	Name: TAXIWAY A3			Use: TAXIWAY	Area:	60,985.80SqFt	
Section: 120 Surface: AAC	of 2 From: - Family: FDOT-GA-TW-AAC			То: -	Zone:	Last Const.: Category:	11/01/2012 Rank: P
Area: 53,835.00SqFt Shoulder: Street Ty	Length:300.00Ftype:Grade:0.00	Lanes:	Width: 0	50.00Ft			
Section Comments:							
NOTE: *** Pre-Const Last Insp. Date: 02/07/20 Conditions: PCI : 60		veyed: 1					
Inspection Comments: KHA							
Inspection Comments: KHA Sample Number: 101 Sample Comments:	Type: R	Area:	5,000.0	00SqFt	PCI = 60		

Network:	CEW	Name: B	OB SIKES	AIRPORT						
Branch:	TW A3	Name: T.	AXIWAY	A3			Use: TAXIWAY	Area:	60,985.80SqFt	
Section:	330	of 2	From:	-			То: -		Last Const.:	11/01/2012
Surface:	AAC	Family:	FDOT-G	A-TW-AAC				Zone:	Category:	Rank: P
Area:	7,150.80SqFt	Len	gth:	95.00Ft		Width:	40.00Ft			
Shoulder:	Street Ty	ype:	Grade:	0.00	Lanes:	0				
Section Con	nments:									
NOTE: *	** Pre-Const	ruction PC	[ ***							
Last Insp. l	Date: 02/07/20	11 Total San	nples: 1	l Surv	eyed: 1	l				
Conditions		11 Total San	npies:	l Surv	eyed:	l				
Inspection C	Comments: KHA									

Sample Number: 360 Sample Comments:	Type: R	Area:	3,873.00SqFt		PCI = 62
43 BLOCK CRACKING		L	1,937.00	SqFt	Comments:
52 RAVELING		М	800.00	SqFt	Comments:

FDOT

FDOT		ite-mspt	cuon report			
Report Generated Date: Se	ptember 05, 2013					
Network: CEW	Name: BOB SIKES AIRPOR	T				
Branch: TW A4	Name: TAXIWAY A4		Use: TAXIWAY	Area:	80,012.86SqFt	
Section: 130	of 2 From: -		То: -		Last Const.:	11/01/2012
Surface: AAC	Family: FDOT-GA-TW-A			Zone:	Category:	Rank: P
Area: 53,403.85SqFt	Length: 250.00	)Ft W	idth: 130.00Ft			
Shoulder: Street Ty	pe: Grade: 0.00	Lanes: 0				
Section Comments:						
NOTE: *** Pre-Constr	uction PCI ***					
Last Insp. Date: 02/07/201	1 Total Samples: 43	Surveyed: 5				
Conditions: PCI: 67						
Inspection Comments: KHA						
Sample Number: 115	Type: R	Area:	5,000.00SqFt	PCI = 69		
Sample Comments:	Type: It	11104	2,000,00541	101 07		
43 BLOCK CRACKING	3	L	3,100.00 SqFt	Comments:		
Sample Number: 125 Sample Comments:	Type: R	Area:	5,000.00SqFt	PCI = 63		
43 BLOCK CRACKING	3	L	2,100.00 SqFt	Comments:		
43 BLOCK CRACKING		М	100.00 SqFt	Comments:		
52 RAVELING		L	2,000.00 SqFt	Comments:		
Sample Number: 136 Sample Comments:	Type: R	Area:	5,000.00SqFt	PCI = 71		
-	RANSVERSE CRACKING	; L	273.00 Ft	Comments:		
43 BLOCK CRACKING		L	165.00 SqFt	Comments:		
52 RAVELING		L	2,000.00 SqFt	Comments:		
Sample Number: 147	Type: R	Area:	5,000.00SqFt	PCI = 71		
Sample Comments:	RANSVERSE CRACKING	; L	200.00 Ft	Comments:		
43 BLOCK CRACKING		, <u> </u>	400.00 SqFt	Comments:		
52 RAVELING		_ L	2,000.00 SqFt	Comments:		
Sample Number: 153	Type: R	Area:	5,000.00SqFt	PCI = 62		
Sample Comments: 43 BLOCK CRACKING	N	L	2,800.00 SqFt	Comments:		
52 RAVELING	-	L	2,200.00 SqFt	Comments:		
	RANSVERSE CRACKING					
	TRANSVERSE CRACKING		2,200.00 SqFt 18.00 Ft	Comments:		

FDOT Report Generated Date	:September 05, 2013	110 1115 prov				
Network: CEW	Name: BOB SIKES AII	RPORT				
Branch: TW A4	Name: TAXIWAY A4		Use: TAXIWAY	Area:	80,012.86SqFt	
Section: 135	of 2 From: -		То: -	-	Last Const.:	11/01/2012
Surface: AC Area: 26,609.01SqF Shoulder: Street	e	W-AC 50.00Ft Width 00 Lanes: 0	1: 130.00Ft	Zone:	Category:	Rank: P
Section Comments:						
Last Insp. Date: Conditions:	Total Samples: 0	Surveyed: 0				
Sample Number:	Type:	Area:	0.00			

Sample Number: Type: <NO VALID INSPECTIONS>

0.

FDOT		ite msp	centil Repor	t		
-	nerated Date: September 05, 2013					
Network:	CEW Name: BOB SIKES A	RPORT				
Branch:	TW CONN Name: CONNECTOR	TAXIWAYS TO APR	Use: TA	XIWAY Area:	62,500.67SqFt	
Section:	310 of 4 From: -		То: -		Last Const.:	11/01/2012
Surface:	AAC Family: FDOT-GA-	TW-AAC		Zone:	Category:	Rank: P
Area:	7,038.40SqFt Length:	75.00Ft	Width: 40.00	Ft		
Shoulder:	Street Type: Grade: 0	0.00 Lanes: 0	)			
Section Com	nments:					
Last Insp. I Conditions		Surveyed: 1				
Inspection C	Comments: KHA					
Sample Nu Sample Corr	umber: 350 Type: R nments: 3/2011 (KHA) - AREA CHANGED F	Area: ROM 3000	3,873.00SqFt	PCI = 62		
-	GITUDINAL/TRANSVERSE CRAC		143.00	Ft Comme	nts:	
	CK CRACKING	L		-	nts:	
52 RAVE	ELING	L	800.00	SqFt Comme	nts:	

<b>Re-inspection</b> 1	Report
------------------------	--------

Network:	CEW	Name:	BOB SIKES	AIRPORT							
Branch:	TW CONN	Name:	CONNECTO	R TAXIWAY	S TO APR		Use: TAXI	IWAY	Area:	62,500.67SqFt	
Section:	320	of 4	From:	-			То: -			Last Const.:	11/01/2012
Surface:	AAC	Famil	ly: FDOT-G	A-TW-AAC					Zone:	Category:	Rank: P
Area:	2,982.48SqFt	L	ength:	55.00Ft		Width:	40.00Ft				
Shoulder:	Street Ty	/pe:	Grade:	0.00	Lanes:	0					
Last Insp. 1	*** <b>Pre-Constr</b> Date: 02/07/201			Surv	eyed: 1						
Last Insp. 1 Conditions				Surv	eyed: 1						
Last Insp. 1 Conditions Inspection C Sample Nu	Date: 02/07/20 3: PCI : 20 Comments: KHA Imber: 355	11 Total S	ype: R		eyed: 1 Area:	2,200	0.00SqFt		PCI = 20		
Last Insp. 1 Conditions Inspection C Sample Nu Sample Con	Date: 02/07/20 :: PCI : 20 Comments: KHA umber: 355 nments: 3/11 (KH/	11 Total S Ty A) - CHANG	ype: R		Area:		1				
Last Insp. 1 Conditions Inspection C Sample Nu Sample Con 43 BLOC	Date: 02/07/20 3: PCI : 20 Comments: KHA Imber: 355	11 Total S Ty A) - CHANG	ype: R		Area:	Ľ	100.00 s	qFt	PCI = 20 Comments Comments		
Last Insp. 1 Conditions Inspection C Sample Nu Sample Con 43 BLOO 52 RAVI	Date: 02/07/20 :: PCI : 20 Comments: KHA umber: 355 nments: 3/11 (KH/ CK CRACKING	11 Total S Ty A) - CHANG	ype: R		Area:	Ľ	1	lqFt lqFt	Comments	:	
Last Insp. 1 Conditions Inspection C Sample Nu Sample Con 43 BLOO 52 RAVI 52 RAVI	Date: 02/07/2025 PCI : 20 Comments: KHA Imber: 355 Imments: 3/11 (KHA CK CRACKING ELING	11 Total S Ty A) - CHANG	ype: R		Area:	L M 1	100.00 s	lqFt lqFt lqFt	Comments Comments	::	
Last Insp. 1 Conditions Inspection C Sample Nu Sample Con 43 BLOC 52 RAVI 52 RAVI 50 PATC 48 LONC	Date: 02/07/20 S: PCI: 20 Comments: KHA Imber: 355 Imments: 3/11 (KH/ CK CRACKING ELING ELING	Ty A) - CHANG G TRANSVI	amples: 1 /pe: R GED AREA FI	ROM 2255 CKING	Area:	- M 1 H	100.00 s ,000.00 s 70.00 s	GqFt GqFt GqFt GqFt 't	Comments Comments Comments	:	

FDOT	ne mspectio	in http://			
Report Generated Date: September 05, 2013					
Network: CEW Name: BOB SIKES AIRPORT	,				
Branch: TW CONN Name: CONNECTOR TAXIW	YAYS TO APR	Use: TAXIWAY	Area:	62,500.67SqFt	
Section: 335 of 4 From:		To:		Last Const.:	11/01/2012
Surface: AAC Family: FDOT-GA-TW-AC			Zone:	Category:	Rank: P
Area: 26,206.75SqFt Length: 113.00F	t Width:	90.00Ft			
Shoulder: Street Type: Grade: 0.00	Lanes: 0				
Section Comments: NOTE: *** Pre-Construction PCI ***					
	urveyed: 1				
Conditions: PCI : 92					
Inspection Comments: KHA					
Sample Number: 100 Type: R Sample Comments:	Area: 4,030	D.00SqFt	PCI = 92		
•	-				
48 LONGITUDINAL/TRANSVERSE CRACKING	L	10.00 Ft	Comments	:	

<b>Re-inspection</b>	Report
----------------------	--------

FDOT Report Ger	nerated Date: S	eptember	05, 2013		pece				
Network:		-	BOB SIKES AIRPORT						
Branch:	TW CONN	Name:	CONNECTOR TAXIWA	YS TO APR		Use: TAXIWAY	Area:	62,500.67SqFt	
Section: Surface:	340 AAC	of 4 Famil	From: - ly: FDOT-GA-TW-AC			То: -	Zone:	Last Const.: Category:	11/01/2012 Rank: P
Area: Shoulder:	26,273.04SqFt Street T		ength: 127.25Ft Grade: 0.00	Lanes:	Width 0	a: 40.00Ft			
Section Con	nments:								
Last Insp. I Conditions	** <b>Pre-Const</b> Date: 02/07/20 5: PCI : 63 Comments: KHA		-	rveyed: 1					
Sample Nu Sample Con		Ту	vpe: R	Area:	7	,345.00SqFt	PCI = 63		
43 BLOC	CK CRACKIN GITUDINAL/		ERSE CRACKING		L L L	3,162.00 SqFt 110.00 Ft 1,800.00 SqFt	Comments Comments Comments	:	

FDOT				
Report Generated Date: Network: CEW	September 05, 2013 Name: BOB SIKES AIRPORT			
Branch: TW K	Name: TAXIWAY K	Use: TAXIWAY	Area:	25,847.69SqFt
Section: 605 Surface: AC	of 1 From: - Family: FDOT-GA-TW-AC	То: -	Zone:	Last Const.: 03/01/2008 Category: Rank: P
Area: 25,847.69SqFt Shoulder: Street	Length: 500.00Ft Type: Grade: 0.00	Width: 35.00Ft Lanes: 0		
Section Comments: Last Insp. Date: 08/27/2 Conditions: PCI : 94	013 Total Samples: 8 Sur	reyed: 1		
Inspection Comments: Sample Number: 103 Sample Comments:	Type: R	Area: 3,500.00SqFt	PCI = 94	

FDOT			cetion Report			
Report Generated Date: Network: CEW	September 05, 2013 Name: BOB SIKES AIRPO	RT				
Branch: TW PMV	Name: TAXIWAY PMV		Use: TAXIWAY	Area:	75,708.54SqFt	
Section: 505 Surface: AC	of 1 From: - Family: FDOT-GA-TW-A	AC	То: -	Zone:	Last Const.: Category:	01/01/2008 Rank: S
Area: 75,708.54SqFt Shoulder: Street	Length: 1,450.0		Width: 50.00Ft			
Section Comments:						
Last Insp. Date: 08/27/2 Conditions: PCI : 94 Inspection Comments:	013 Total Samples: 15	Surveyed: 3				
Sample Number: 104	Type: R	Area:	4,182.00SqFt	PCI = 94		
Sample Comments: 57 WEATHERING		I	4,182.00 SqFt	Comments	:	
Sample Number: 109 Sample Comments:	Type: R	Area:	5,000.00SqFt	PCI = 94		
57 WEATHERING		I	5,000.00 SqFt	Comments	:	
Sample Number: 114	Type: R	Area:	5,000.00SqFt	PCI = 94		
Sample Comments: 57 WEATHERING		I	5,000.00 SqFt	Comments	:	