

FLORIDA DEPARTMENT OF TRANSPORTATION
AVIATION AND SPACEPORT OFFICE



**MELBOURNE
INTERNATIONAL
AIRPORT (MLB)**

DISTRICT 5

PRIMARY AIRPORT

JUNE 2015

STATEWIDE
**Airfield
Pavement
Management**
PROGRAM



TABLE OF CONTENTS

| | |
|---|----|
| Executive Summary | 1 |
| 1. Introduction..... | 7 |
| 2. Airfield Pavement Network Definition and Pavement Inventory..... | 19 |
| 3. Airfield Pavement Condition | 29 |
| 4. Pavement Performance | 41 |
| 5. Airfield Pavement Maintenance Policies and Costs | 45 |
| 6. Major Pavement Rehabilitation Needs..... | 53 |
| 7. Preventative and Major Rehabilitation Planning | 57 |
| 8. Visual Aid Exhibits..... | 61 |
| 9. Recommendations..... | 63 |

LIST OF TABLES

| | |
|--|----|
| Table I: Condition Summary by Branch | 2 |
| Table II: Condition Summary by Pavement Facility Use | 3 |
| Table III: Year-1 Major Rehabilitation Needs for Melbourne International Airport..... | 4 |
| Table IV: 10-Year Preventative Maintenance and Major Rehabilitation | 5 |
| Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections | 15 |
| Table 2-1: Previous and/or Anticipated Airfield Pavement Construction | 21 |
| Table 2-2: Pavement Inventory Summary..... | 22 |
| Table 2-3: Airfield Pavement Inventory Details..... | 23 |
| Table 3-1: Airfield Pavement Distresses for Asphalt Concrete..... | 32 |
| Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete | 33 |
| Table 3-3: Pavement Condition Index Rating Summary..... | 37 |
| Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy..... | 46 |
| Table 5-2: Recommended PCC Maintenance and Repair Policy | 47 |
| Table 5-3: Critical and Minimum Service Level PCI for Primary Airports | 49 |
| Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI..... | 49 |
| Table 5-5: AC Maintenance Unit Costs | 51 |
| Table 5-6: PCC Maintenance Unit Costs..... | 51 |
| Table 5-7: Rehabilitation Activities and Unit Costs by Condition for Primary Airports..... | 52 |
| Table 6-1: Summary of Major Rehabilitation..... | 54 |
| Table 7-1: 10-Year Preventative and Major Rehabilitation Summary..... | 57 |

LIST OF FIGURES

| | |
|--|----|
| Figure 1-1: Pavement Life Cycle..... | 13 |
| Figure 1-2: Flexible Pavement, Asphalt Concrete..... | 16 |
| Figure 1-3: Rigid Pavement, Portland Cement Concrete | 17 |
| Figure 2-1: Airfield Pavement Type..... | 23 |
| Figure 3-1: Airfield Pavement Condition Index Rating Summary | 36 |
| Figure 3-2: Percentage of Pavement Area by Condition Rating by Use | 38 |
| Figure 4-1: Runway Pavement Performance Prediction Summary | 42 |
| Figure 4-2: Taxiway Pavement Performance Prediction Summary..... | 42 |
| Figure 4-3: Apron Pavement Performance Prediction Summary..... | 43 |
| Figure 6-1: 10-Year Major Rehabilitation Budget Scenario Analysis..... | 55 |
| Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary..... | 58 |

APPENDICES

| | |
|------------|--|
| Appendix A | Airfield Pavement Network Definition Exhibit Airfield Pavement System Inventory Exhibit Pavement Geometry Inventory Work History Report |
| Appendix B | Airfield Pavement Condition Index Rating Exhibit Pavement Condition Index Inventory |
| Appendix C | Branch Condition Report Section Condition Report |
| Appendix D | Pavement Performance Prediction Table Pavement Performance by Pavement Use |
| Appendix E | Year-1 Preventative Activities |
| Appendix F | Airfield Pavement 10-Year Major Rehabilitation Exhibit Airfield Pavement 10-Year Major Rehabilitation Table |
| Appendix G | Photographs |
| Appendix H | Distress Data – Re-inspection Report |

EXECUTIVE SUMMARY

In 2012, the Florida Department of Transportation (FDOT) Central Aviation Office selected a team lead by Kimley-Horn and Associates, Inc. and including their subconsultants Penuel Consulting and LLC, Roy D. McQueen & Associates, LTD, to provide services in support of FDOT in the continued efforts of updating the existing Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed over the fiscal years of 2013 through 2015.

The tasks required to achieve this objective at each participating airport specifically included the following:

- Obtain recent construction history from the airport to update the Pavement Network Definition Exhibits using CADD from the previous SAPMP update.
- Update the airport pavement inventory data (construction history, geometry, identification, and classification) based on airport provided information.
- Update the FDOT SAPMP MicroPAVER database files and system tables for the purpose of analyzing field data for Pavement Condition Index (PCI) calculation of current pavement condition
- Development of pavement performance models for the approximation of future pavement performance.
- Development of a maintenance and repair plan, and a 10-year major rehabilitation program to address the pavement needs based on condition.
- Development of planning level opinions of probable costs for pavement preservation and rehabilitation.

In March 2015, a PCI survey inspection was performed at Melbourne International Airport. The results of the inspection indicate that, based on ASTM D 5340-12, the airport's airfield pavement facilities had an overall area-weighted average PCI of 75, representing a Satisfactory overall network condition. Table I summarizes the overall condition summary by network level branch in comparison to the FDOT recommended minimum service level and action recommendations for either major rehabilitation or maintenance level activities.

Table I: Condition Summary by Branch

| Branch Name | Area Weighted PCI | PCI Range | Average Condition Rating | FDOT Minimum Service Level | MicroPAVER Minimum PCI | Action Required |
|-------------------------------------|-------------------|-----------|--------------------------|----------------------------|------------------------|-----------------|
| CENTER APRON | 84 | 70 - 92 | SATISFACTORY | 65 | 65 | |
| EAST APRON | 87 | 45 - 100 | GOOD | 65 | 65 | X |
| NORTH GA APRON | 77 | 59 - 100 | SATISFACTORY | 65 | 65 | X |
| SOUTHWEST APRON | 84 | 80 - 100 | SATISFACTORY | 65 | 65 | |
| TERMINAL APRON | 81 | 80 - 82 | SATISFACTORY | 65 | 65 | |
| WEST APRON | 50 | 0 - 94 | POOR | 65 | 65 | X |
| THRESHOLD TO RW 27L | 73 | 72 - 76 | SATISFACTORY | 75 | 65 | X |
| RUNWAY 5-23 | 68 | 54 - 69 | FAIR | 75 | 65 | X |
| RUNWAY 9L-27R | 67 | 61 - 96 | FAIR | 75 | 65 | X |
| RUNWAY 9R-27L | 63 | 58 - 74 | FAIR | 75 | 65 | X |
| TAXIWAY ALPHA | 79 | 78 - 92 | SATISFACTORY | 70 | 65 | |
| TAXIWAY BRAVO | 81 | 81 | SATISFACTORY | 70 | 65 | |
| TAXIWAY CHARLIE | 78 | 71 - 91 | SATISFACTORY | 70 | 65 | |
| CONNECTOR TAXIWAY TO TERMINAL APRON | 86 | 86 | GOOD | 70 | 65 | |
| TAXIWAY DELTA | 74 | 63 - 94 | SATISFACTORY | 70 | 65 | X |
| TAXIWAY FOXTROT | 100 | 100 | GOOD | 70 | 65 | |
| TAXIWAY GOLF | 94 | 94 | GOOD | 70 | 65 | |
| TAXIWAY KILO | 80 | 70 - 100 | SATISFACTORY | 70 | 65 | X |
| TAXIWAY LIMA | 74 | 74 - 75 | SATISFACTORY | 70 | 65 | |
| TAXIWAY MIKE | 75 | 70 - 88 | SATISFACTORY | 70 | 65 | X |
| TAXIWAY NOVEMBER | 90 | 81 - 93 | GOOD | 70 | 65 | |
| TAXIWAY QUEBEC | 81 | 72 - 91 | SATISFACTORY | 70 | 65 | |
| TAXIWAY ROMEO | 85 | 69 - 90 | SATISFACTORY | 70 | 65 | X |
| TAXIWAY SIERRA | 65 | 55 - 87 | FAIR | 70 | 65 | X |
| TAXIWAY S1 | 89 | 76 - 100 | GOOD | 70 | 65 | |
| TAXIWAY TANGO | 83 | 83 - 84 | SATISFACTORY | 70 | 65 | |
| TAXIWAY VICTOR | 90 | 70 - 100 | GOOD | 70 | 65 | X |
| TAXIWAY V1 | 88 | 88 | GOOD | 70 | 65 | |
| TAXIWAY V2 | 100 | 100 | GOOD | 70 | 65 | |

“Action Required” in Table I is triggered when a section within the identified Branch Facility falls below the FDOT Minimum Service Level. Year 1 Major Rehabilitation needs are triggered in Table III when a section in the identified Branch falls below the MicroPAVER Minimum PCI. Major Rehabilitation is also

triggered in Table III when the section PCI is above critical and the section exhibits significant structural related distresses.

For project level planning and inspection development; the airfield pavement facilities have been divided at the branch level based on facility use and designation, and at the section level based on pavement construction history, composition (e.g. asphalt versus concrete), aircraft traffic operations, and pavement surface conditions. Table II provides the overall area weighted condition of the pavement based on facility branch use.

Table II: Condition Summary by Pavement Facility Use

| Use | Average Area-Weighted PCI | Condition Rating |
|---------|---------------------------|------------------|
| Runway | 65 | FAIR |
| Taxiway | 80 | SATISFACTORY |
| Apron | 79 | SATISFACTORY |

Based on the inspection performed at the airport for this SAPMP update; the current conditions were determined using the collected PCI distress data. PCI values were computed and used to identify pavement facilities that were below the defined critical PCI as sections that would benefit from immediate major rehabilitation activity. These pavement sections that were determined to be below the critical PCI would most likely benefit from long-term major rehabilitative construction activity rather than localized, short-term maintenance and repairs.

The Year-1 Major Rehabilitation Needs, or projects that are recommended to be completed because the pavement is below the critical PCI, were developed on the assumption that there is an unlimited repair budget. These projects include:

- Runway 5-23 – Sections 6310 and 6315
 - Mill and Overlay attributed to climate/age and construction quality.
- Runway 9L-27R – Section 6210
 - Mill and Overlay attributed to structural, climate/age, and construction quality.
- Runway 9R-27L– Section 6105
 - Mill and Overlay attributed to structural, climate/age, and construction quality.

- East Apron – Sections 4406 and 4410
 - Mill and Overlay attributed to climate/age and construction quality.
- West Apron – Sections 4312, 4325, and 4330
 - Reconstruction attributed to structural, climate/age, and construction quality.
- West Apron – Section 4320
 - Mill and Overlay attributed to climate/age and construction quality.
- North General Aviation Apron – Section 4110
 - Mill and Overlay attributed to climate/age and construction quality.
- Taxiway S – Sections 505 and 510
 - Mill and Overlay attributed to climate/age and construction quality.
- Taxiway D – Sections 410 and 412
 - Mill and Overlay attributed to climate/age.

The section level projects that were identified as Year-1 Major Rehabilitation Needs are in Table III.

Table III: Year-1 Major Rehabilitation Needs for Melbourne International Airport

| Branch ID | Section ID | Major Rehabilitation Costs | PCI Before M&R | Rehabilitation Activity | PCI After M&R |
|-----------|------------|----------------------------|----------------|-------------------------|---------------|
| RW 5-23 | 6315 | \$ 124,200.00 | 54 | Mill and Overlay | 100 |
| RW 5-23 | 6310 | \$ 124,200.00 | 57 | Mill and Overlay | 100 |
| RW 9L-27R | 6210 | \$10,172,369.00 | 61 | Mill and Overlay | 100 |
| RW 9R-27L | 6105 | \$17,100,001.00 | 58 | Mill and Overlay | 100 |
| AP E | 4410 | \$ 2,083,391.00 | 45 | Mill and Overlay | 100 |
| AP E | 4406 | \$ 235,672.00 | 50 | Mill and Overlay | 100 |
| AP W | 4330 | \$ 1,199,128.00 | 5 | Reconstruction | 100 |
| AP W | 4325 | \$ 1,043,050.00 | 0 | Reconstruction | 100 |
| AP W | 4320 | \$ 1,367,100.00 | 57 | Mill and Overlay | 100 |
| AP W | 4312 | \$ 196,581.00 | 13 | Reconstruction | 100 |
| AP N GA | 4110 | \$ 2,287,267.00 | 59 | Mill and Overlay | 100 |
| TW S | 510 | \$ 1,231,722.00 | 55 | Mill and Overlay | 100 |
| TW S | 505 | \$ 336,600.00 | 63 | Mill and Overlay | 100 |
| TW D | 412 | \$ 80,970.00 | 63 | Mill and Overlay | 100 |
| TW D | 410 | \$ 1,872,918.00 | 63 | Mill and Overlay | 100 |
| Total = | | \$39,455,169.00 | | | |

The SAPMP uses historic pavement condition data from the previous inspections to develop pavement performance models. These pavement performance models are used to create PCI prediction curves to estimate future pavement conditions based on the historic trends. The section areas, prediction curves, and current condition data were used to develop a 10-year major rehabilitation program. Major rehabilitation costs for each year of the 10-year program are based on general unit costs for pavement repairs and not detailed cost estimates that are typically prepared for a construction set of bid documents. Additionally, preventative maintenance level repair budgets were estimated for a 10-year duration. Table IV provides an annual summary of the 10-year Preventative Maintenance and Major Rehabilitation planning level cost opinions for the airfield pavement facilities at the airport. Refer to Section 6 of this report for additional information.

Since the previous update performed in 2012, significant updates to the ASTM D 5340 Standard Test Method for Airport Pavement Condition Index Surveys have affected the analysis of the program. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reaction distress for rigid pavement distresses. Additionally, the deterioration associated with the rigid pavement distress Scaling/Map Cracking has been modified. The change in distress classification, as described in ASTM D 5340-12, may result in small variances in the PCI values from the previous inspection analysis. The update included changes in distress deduction values that may be less than the previous analysis. Please refer to Section 3 Airfield Pavement Condition Index for additional information.

Additionally, pavement repair and rehabilitation work reported by the airports are entered into the SAPMP which can improve PCI values.

Table IV: 10-Year Preventative Maintenance and Major Rehabilitation


| Year | Preventative | Major M&R | Total Year Cost |
|------|-----------------|------------------|------------------|
| 2015 | \$ 1,311,049.00 | \$ 39,455,168.43 | \$ 40,766,217.43 |
| 2016 | \$ 1,490,288.97 | \$ - | \$ 1,490,288.97 |
| 2017 | \$ 1,629,990.71 | \$ 1,829,416.05 | \$ 3,459,406.75 |
| 2018 | \$ 1,646,657.58 | \$ 7,175,477.05 | \$ 8,822,134.63 |
| 2019 | \$ 1,786,906.98 | \$ 1,664,963.98 | \$ 3,451,870.96 |
| 2020 | \$ 1,735,877.72 | \$ 10,858,188.57 | \$ 12,594,066.29 |
| 2021 | \$ 1,969,713.43 | \$ 1,419,919.20 | \$ 3,389,632.63 |
| 2022 | \$ 2,029,814.42 | \$ 9,348,889.83 | \$ 11,378,704.25 |
| 2023 | \$ 2,232,549.55 | \$ 3,582,761.12 | \$ 5,815,310.68 |

| Year | Preventative | Major M&R | Total Year Cost |
|-------|------------------|------------------|-------------------|
| 2024 | \$ 2,229,689.80 | \$ 13,409,731.36 | \$ 15,639,421.16 |
| Total | \$ 18,062,538.16 | \$ 88,744,515.59 | \$ 106,807,053.75 |

The success of the repair program for your airport depends on the timely implementation of preservation, localized maintenance and repairs, and major rehabilitation work activities. If work is completed as scheduled, your airport should experience an improvement to the overall area-weighted average PCI. Though this analysis was performed with the assumption of an “unlimited budget”, the purpose has been to identify specific projects over the course of 10-years for each pavement section where the condition is projected to fall below the critical PCI. The costs depicted in this study are intended to aid the airports in planning level budgets. Prior to construction work, it is recommended that the airport perform additional investigation at the design level to better estimate costs associated with the maintenance, repair, and major rehabilitation activity discussed.

1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. The aviation system in Florida allows the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.



There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

The Florida Department of Transportation (FDOT) Central Aviation and Spaceport Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992. In 2012, the FDOT Central Aviation and Spaceport Office selected a team led by Kimley-Horn and Associates, Inc. and including Penuel Consulting, LLC and Roy D. McQueen & Associates, LTD, to provide services in support of the Central Aviation and Spaceport Office Program Manager. The continued evaluation and update of the existing SAPMP is to be completed over fiscal years 2013 through 2015.

This individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance repair and major rehabilitation planning associated with the SAPMP update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

1.1 Purpose of Pavement Evaluation Report

The purpose of this Airfield Pavement Evaluation Report is to:

- Briefly describe the SAPMP goals, procedures, and responsibilities of the program's participants.
- Provide a technical explanation on pavement management principles, standard practices, objectives, and benefits of implementation.
- Outline procedures used to coordinate, collect, evaluate and report pavement inspection results at this airport.
- Analyze and utilize condition results for the development of maintenance, repair, and major rehabilitation based on pavement performance trends.

1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the Florida Airports System, identify maintenance and rehabilitation needs at each airport, automate pavement infrastructure information management, and establish standards to address future needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.

During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement

management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation (M&R) policies, M&R budget costs, and the development of recommendations for performing routine pavement preservation maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER was selected for implementation of the system update. MicroPAVER was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for the purpose of pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER system. This data conversion included all documented pavement facility, classification, type, history, geometry, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In 2006-2008, the SAPMP was updated again with continued use of the MicroPAVER system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In 2010-2012, the SAPMP was updated using new GPS integrated technology to digitally collect pavement distress data. Interactive GIS map files were developed from updated Airfield Pavement Network Definition Maps to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the Federal Aviation Administration (FAA) to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C *Guidelines and Procedures for Maintenance of Airport Pavements*). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year or every three years, if the pavement is inspected in accordance to the PCI survey procedure (such as ASTM International D 5340 *Standard Test Method for Airport Pavement Condition Index Surveys*). The previous 2010-2012 SAPMP update utilized the ASTM D 5340-04 released in 2004, in lieu of the 2010/2011 edition, in order to maintain consistent database integrity and benefit of pavement performance models from previous inspections.

1.3 Organization

FDOT Central Aviation Office Program Manager

The FDOT Central Office Airport Engineering Manager serves as the Aviation and Spaceport Office Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the Consultant. The ASO-PM has review and approval authority for each program task and manages the day-to-day details of the SAPMP and the pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceport Manager and Development Administrator.

Consultant

The Consultant, Kimley-Horn and Associates, Inc. and their team consisting of Penuel Consulting, LLC and Roy D. McQueen & Associates, LTD, provides technical and administrative assistance to the ASO-PM during the execution of the update to the SAPMP. The efforts include updating the airport pavement inventory data, performing the condition survey inspections, evaluating the airfield pavement conditions and updating the SAPMP based upon procedures outlined in the FAA Advisory Circular 150/5380-6C *Guidelines and Procedures for Maintenance of Airport Pavements* and ASTM D 5340.

Airport Role

The airports are the ultimate beneficiary for each condition survey inspection performed at their respective airfields as part of the SAPMP. The individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the ASO-PM. The airport should have provided a

current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP, indicate any construction activity that was performed since the previous inspections.

FDOT District Offices

The seven FDOT District Offices, specifically the Aviation Representatives, provide vital support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing representative construction trend costs and practices through the Florida Airports System. Each District Office receives copies of individual Airfield Pavement Evaluation Reports for the airport facilities located within their respective districts.

1.4 Introduction to Pavement Types and Pavement Management

Pavement Basics

A pavement is a prepared surface designed to provide a continuous smooth ride at all taxi, takeoff, and landing speeds and to support an estimated amount of traffic loading for a certain number of years. Pavements are composed of a combination of constructed layers of subgrade soils, subbases, base course material, and surface level courses. There are two primary types of pavements:

- Flexible Pavement, composed of bituminous asphalt concrete (AC) surface, base, and subbase layers.
- Rigid Pavement, composed of Portland Cement Concrete (PCC) surface, base, and subbase layers.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads (both magnitude and repeated application) and protect the underlying subgrade soil. Flexible pavements dissipate applied loads from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements, the PCC layer supports the majority of the structural load applied, and the base or subbase layer is constructed to provide a smooth, level, and continuous platform that provides uniform support for PCC slabs.

A small percentage of airfield pavements within the Florida Airports System are composed of hybrid 'composite pavement' sections that may include both AC pavement and PCC pavement. The two known composite pavements are AC surface over PCC (APC) and PCC over AC (White Topping).

Due to the different nature of the pavement types, construction, and their materials; flexible and rigid pavements have different modes of failure and


fatigue. This results in varying deterioration and distress development. Understanding the mechanics and modes of failure of the pavement types assists the engineers in making timely, adequate and consistent observations, and in recommending economical maintenance repairs and major rehabilitation to the pavement structures at each airfield.

The Concept of an Airfield Pavement Management System

The SAPMP is a program that provides the Florida Airports System an opportunity to implement and/or maintain a proactive Airfield Pavement Management System (APMS) in a consistent manner at a regular schedule. The SAPMP Airfield Pavement Management System consists of pavement inventory, pavement construction and history, condition survey inspections, pavement performance modeling, maintenance recommendations, and major rehabilitation planning. The various elements of the APMS are used by experienced engineers to identify critical pavements, make pavement preservation or rehabilitation recommendations, and approximate pavement performance. The APMS as a whole is used by an airport's stakeholders, managing agencies, engineers, and planners as a tool in decision making for future project planning, budgeting, and scheduling of activities for its airfield pavement infrastructure.

A benefit of an active APMS is it provides an understanding of an airport's pavement performance trends for the purpose of project planning. Based on the performance trend of their pavements, an airport can schedule pavement maintenance and rehabilitation prior to when the pavement section has deteriorated to a condition that would require reconstruction. The use of pavement performance trends will help airports plan M&R and Rehabilitation projects in a manner and sequence that maximizes benefit and minimizes costs. Figure 1-1, which is based upon the FAA Advisory Circular 150 5380-7B *Airport Pavement Management Program*, illustrates how pavement generally deteriorates over time and the relative cost of rehabilitation and reconstruction throughout its life.

Figure 1-1: Pavement Life Cycle



Source: FAA Advisory Circular 150 5380-7B Airport Pavement Management Program

Note that during approximately the first 75% of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in 'Good' and 'Satisfactory' conditions depends on how well it is proactively maintained. As the Figure 1-1 demonstrates, the cost of maintaining the pavement above critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Pavements tend to deteriorate at an accelerated rate when actual traffic loading exceeds the original design assumptions and when limited resources are available for maintenance and repair (M&R) efforts. Planned maintenance and rehabilitation, essentially preserving pavements and delaying condition deterioration, help airport managers, agencies, and engineers maximize the use of their budgets and prolong the life of their pavements. An APMS provides a tool to schedule planned maintenance and major rehabilitation efforts based on a consistent methodology of condition assessment. This consistent methodology of pavement condition assessment allows for the development of pavement performance models to help forecast future pavement conditions.

Part of the implementation of the APMS is the clear identification and inventorying of pavement infrastructure that needs to be managed specifically within the airport owner, manager, and agency responsibility. Another aspect of the APMS is development of maintenance, repair, and major rehabilitation policies that align with the expectations of pavement performance and are based on ability to fund the types of work identified. Once there is an understanding of the cause and extent of pavement distresses, appropriate maintenance and rehabilitation can be planned. By using representative construction costs based on historic bid trends; planning level budget costs can be developed on a multiyear duration.

Airfield Pavement Inspection Methodology for the SAPMP

Pavement condition assessment requires the application of professional judgments regarding the condition of the pavement. The SAPMP airfield pavement condition survey inspections assess pavement, comparing it to a set of standards in ASTM D 5340-12. As part of this update, SAPMP has adopted the changes made in updates to ASTM D 5340-12. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reaction distress for rigid pavement distresses. Additionally, the deterioration associated with the rigid pavement distress Scaling/Map Cracking has been modified which results in moving Map Cracking from Scaling to ASR. In the newest version of ASTM D 5340-12, there are two kinds of Shrinkage Cracking, Drying Shrinkage and Plastic Shrinkage. The difference between these two is that the depth of first one may extend through the entire depth of the slab while the thickness of the latter one normally does not extend very deep into the pavement's surface. Furthermore, the Plastic Shrinkage consists of two subcategories: Plastic shrinkage (caused by atmosphere) and Plastic shrinkage (caused by construction). Another kind of Map Cracking is listed under Plastic shrinkage that is caused by construction, as well as Crazeing. This additional type of Shrinkage change in distress classification, as described in ASTM D 5340-12, may result in small variances in the PCI values from the previous inspection analysis.

The pavement condition surveys assess the functional condition of the pavement surface based on surface distresses as defined by the ASTM D 5340-12. Typically, deficiencies within a pavement structure will eventually reflect to the pavement surface as distresses described within ASTM D 5340-12. The SAPMP is specifically a visual evaluation and analysis based on the ASTM D 5340-12. The structural condition and relative support of the pavement layers can be directly quantified

using non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the SAPMP update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine design level rehabilitation and/or reconstruction needs should the airport proceed to the design process.

In preparation for the PCI survey inspections, the airfield pavements for each airport are divided into branches, sections, and sample units as established by FAA Advisory Circular 150/5380-6C and ASTM D 5340. Further discussion of the process of inventorying and categorizing pavement facilities by use, composition, and history can be found in SECTION 2 AIRFIELD PAVEMENT NETWORK DEFINITION and PAVEMENT INVENTORY.

Sample units are uniformly divided areas of pavement that are defined for inspection. Sample unit sizes are approximately 5,000 ± 2,000 square feet for flexible AC pavements and 20 ± 8 slabs for rigid PCC pavements. Prior to conducting the field condition survey inspections, the sampling plan was developed for the airfield pavements based on updates to the previous inspection sampling based on the available knowledge of construction updates. The sample rate adopted for the SAPMP is depicted on Table 1-1.

Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections

| Flexible Pavements Asphalt Concrete | | | Rigid Pavements Portland Cement Concrete | | |
|---|-----------------------------------|-----------------------------|---|-----------------------------------|-----------------------------|
| Number of Sample Units in Section | Number of Sample Units to Inspect | | Number of Sample Units in Section | Number of Sample Units to Inspect | |
| | Runway | Taxiways, Aprons, Others | | Runway | Taxiways, Aprons, Others |
| 1 - 4 | 1 | 1 | 1 - 3 | 1 | 1 |
| 5 - 10 | 2 | 1 | 4 - 6 | 2 | 1 |
| 11 - 15 | 3 | 2 | 7 - 10 | 3 | 2 |
| 16 - 30 | 5 | 3 | 11 - 15 | 4 | 2 |
| 31 - 40 | 7 | 4 | 16 - 20 | 5 | 3 |
| 41 - 50 | 8 | 5 | 21 - 30 | 7 | 3 |
| | | | 31 - 40 | 8 | 4 |
| | | | 41 - 50 | 10 | 5 |
| ≥ 51 | 20% but ≤ 20 | 10% but ≤ 10 | ≥ 51 | 20% but ≤ 20 | 10% but ≤ 10 |

The sample units to be inspected were determined through a systematic random sampling technique to provide an unbiased representation of sample units for each pavement facility. The sample unit locations had been determined in such a way that they are distributed evenly throughout each defined pavement section area. In certain cases when no representative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from each inspected sample unit are used to compute the PCI value and rating for each Section using the ASTM D 5340-12 and MicroPAVER (also known currently as PAVER) software. Figures 1-2 and 1-3 depict graphical representations of the color ranges associated with PCI values and ranges with a photograph of airfield pavement that exhibited the conditions for both flexible and rigid pavements respectively.

Figure 1-2: Flexible Pavement, Asphalt Concrete









| | PCI | PCI | REPRESENTATIVE PAVEMENT SURFACE | REPAIR ACTIVITIES |
|--------------------------|----------|-----|---|---|
| ROUTINE MAINTENANCE | 86 - 100 | 90 |  | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching. |
| PAVEMENT PRESERVATION | 65 - 85 | 70 |  | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing. |
| MAJOR REHABILITATION | 40 - 64 | 40 |  | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as pavement mill and overlay or PCC restoration activity. |
| MAJOR RECONSTRUCTION | 0 - 39 | 15 |  | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction. |

Figure 1-3: Rigid Pavement, Portland Cement Concrete

| | PCI | PCI | REPRESENTATIVE PAVEMENT SURFACE | REPAIR ACTIVITIES |
|--------------------------|----------|-----|--|---|
| ROUTINE MAINTENANCE | 86 - 100 | 90 |  | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching. |
| PAVEMENT PRESERVATION | 65 - 85 | 70 |  | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments, patches, and/or joint/crack sealing. |
| MAJOR REHABILITATION | 40 - 64 | 40 |  | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as Slab replacement and PCC restoration activity. |
| MAJOR RECONSTRUCTION | 0 - 39 | 15 |  | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction. |

Using the ASTM D 5340-12 standard seven qualitative ranges, the SAPMP provides a PCI value and a standard qualitative condition rating for the pavement facilities inspected.

2. AIRFIELD PAVEMENT NETWORK DEFINITION AND PAVEMENT INVENTORY

Melbourne International Airport (MLB) is a public commercial airport located in Melbourne, Florida in Brevard County. The Airport is owned by the City of Melbourne. It is managed and operated by the Melbourne Airport Authority. The Airport is served by three runways. Runway 9R-27L is the primary runway. It is 150-ft wide by 10,181-ft long. Runway 9L-27R is 150-ft wide by 6,000-ft long. Runway 5-23 is 75-ft wide by 3001-ft long. Runway 9R-27L is served by parallel Taxiway A. Runway 9L-27R is served by parallel Taxiway K. Runway 5-23 is served by parallel Taxiway D. The commercial terminal and associated aprons are located on the southeast side of the property. GA aprons are located on the north side of the property. This airport is designated as a Primary / Part 139 airport and is located in District 5 of the Florida Department of Transportation.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric attributes may vary slightly from the geometry used in the condition exhibit in Appendix B and the major rehabilitation exhibit in Appendix F based on field measurements.

Melbourne International Airport started as a designated fueling stop for airmail service in 1928. The area was developed starting in 1933 and operated as a Naval Air Station during World War II. Afterwards, the airport was deeded to the city in 1947 and operated as a municipal airport until the Melbourne Airport Authority was created in 1967.

2.1 Network Definition

The airfield pavements within each airport network are separated into manageable units within the FDOT SAPMP MicroPAVER database system, organizing pavement data by similar use and constructive history.

Branch and Section Identification

Each airport's airfield pavement network is generally subdivided into separate Branches (runways, taxiways, aprons/ramps, or others) that have distinctly different functional identifications and uses. Each Branch is further subdivided into Sections as defined by pavement location, composition, and construction history. A Section is typically understood to be a project level subdivision within a Branch feature. Sections are manageable units to organize data collection and are treated individually during the maintenance and major rehabilitation planning

process. A pavement rank (primary, secondary, or tertiary) is assigned to each Section based on its importance and type of use to airport operations. The pavement rankings designated for each section at this airport were defined by the previous SAPMP, unless changes were communicated by the airport. These Sections are further subdivided into condition survey sample units based on the methodology described in ASTM D 5340.

Airfield Pavement System Inventory and Network Definition Update

The Airfield Pavement System Inventory and Airfield Pavement Network Definition Exhibits are developed individually for each participating airport. Based on information requested of and provided by the airport, the airfield pavements are evaluated on designation updates, and recent or anticipated pavement construction activity. As mentioned previously, a Section is defined partially by its construction history of which is factored in the performance and condition of the pavement section.

The Airfield Pavement System Inventory Exhibit, Figure A-2 in Appendix A, is a snapshot of recent and anticipated airfield pavement construction activity communicated by the airport since the last SAPMP update. Construction activities identified include maintenance and repair activity, major rehabilitation, and airfield pavement expansion efforts. Maintenance and repair activity may include; surface treatments, crack sealing, patching, slab replacement, and others. Both maintenance and rehabilitation activities are identified at the pavement section level. This type of work may result in an increase in overall Section PCI since the last inspection. Major rehabilitation efforts may include; asphalt milling and overlay, and full depth pavement reconstruction. This type of effort will result in a resetting of the pavement section PCI value to 100 due to the nature of the work. Lastly, airfield pavement expansions are accounted for as new inventory and assigned a section PCI of 100. Typically the new pavement sections are not inspected due to its condition; however these pavements are incorporated into the SAPMP pavement database. When possible, these changes are reflected in the Airfield Pavement Network Definition Exhibit, in Appendix A, prior to the field inspection. The updates are typically discussed and confirmed with airport personnel at the beginning and end of condition survey inspections to ensure accuracy.

The Airfield Pavement Network Definition Exhibit depicts the airport's pavement limits with Branch and Section delineations. This exhibit also includes the subdivision on Section areas into sample units and is used to identify those sample units that are to be inspected. The previous SAPMP Airfield Pavement Network

Page | 20

Definition Exhibits were used as a base. Updates and information provided by each airport was reviewed and the exhibits were revised appropriately. Characteristics that are considered include; airfield configuration, branch designations (magnetic declination, Airport Layout Plan updates) and pavement composition. The exhibit serves not only as a primary guide for the airfield inspectors but also allows specific distresses found in the re-inspection report to be geographically located.

Due to recent and anticipated construction efforts; pavement area sections may have been consolidated or created which will affect the total number of sample units to be inspected based upon the methods described in ASTM D 5340 and from the sampling rate schedule. Table 2-1 summarizes the recent and anticipated airfield pavement construction efforts communicated by the airport.

Table 2-1: Previous and/or Anticipated Airfield Pavement Construction

| Construction Year | Section Location | Work Type/Pavement Section |
|-------------------|-------------------------------|--|
| 2010 | TAXIWAYS G & S | NEW ASPHALT PAVEMENT SECTION |
| 2011 | AP N GA | NEW ASPHALT CONSTRUCTION IN FRONT OF NEW BUILDINGS |
| 2013 | TAXIWAY V AND T-HANGARS APRON | APRON: 2" P-401, 6" P-211, 8" WORK PLATFORM TAXIWAY: 2" P-401, 8" P-211, 8" WORK PLATFORM |
| 2013 | TAXIWAY F | TAXIWAY: 2" P-401, 8" P-211, 8" WORK PLATFORM |
| 2014 | TAXIWAY S1 | TAXIWAY: 3" P-401, 8" P-211, 8" WORK PLATFORM |
| 2014 | TAXIWAY K | WIDENING OF TAXIWAY FROM 40' TO 50' TAXIWAY: 3" P-401, 8" P-211, 8" WORK PLATFORM |
| 2014 | AP E | APRON: 4" P-401, 12" P-211, 8" WORK PLATFORM |
| 2014 | AP E | NEW APRON: 14" P-501, 8" P-211, COMPACTED SUBGRADE |

Airfield Pavement Network Definition & Geographic Information System (GIS)

As part of this SAPMP update, geographic information system (GIS), global positioning system (GPS), and digital data collection were integrated into the Pavement Inspection Methodology at each airport. Using AutoCAD Civil 3D,

ArcMap, ArcPad, and FDOT Survey and Mapping Office Aerial Photography; digital navigation maps have been developed for each airport to represent the SAPMP pavement inventory attributes. These navigation maps were used with field data tablets to assist survey teams as they performed condition inspections by navigating pavement infrastructure and collecting distress data.


2.2 Pavement Inventory

The detailed pavement inventory database was updated to reflect the updates to the Airfield Pavement Network Definition Exhibit, in Appendix A, and field inspection results. Table 2-2 and Figure 2-1 provides a summary of the pavement inventory attributes at Melbourne International Airport for this SAPMP update.

Table 2-2: Pavement Inventory Summary

| Airfield Pavement Network Definition | | |
|--------------------------------------|-----------|-------------------|
| Number of Branches | 27 | |
| Number of Sections | 111 | |
| Sample Units | 293 | |
| Airfield Pavement Use | | |
| Use | Area (SF) | Relative Area (%) |
| Runway | 2,652,396 | 31% |
| Taxiway | 3,118,368 | 36% |
| Apron | 2,903,985 | 33% |
| Total = | 8,674,749 | 100% |
| Airfield Pavement Type | | |
| Type | Area (SF) | Relative Area (%) |
| Asphalt Concrete (AC) | 2,184,967 | 25% |
| Asphalt Overlay (AAC) | 5,426,738 | 63% |
| Portland Cement Concrete (PCC) | 934,760 | 11% |
| AC over PCC (APC) | 128,284 | 1% |

Figure 2-1: Airfield Pavement Type



Specific details to each Branch and Section such as; name, geometry, age, rank, surface type, and construction history are provided in Table 2-3.

Table 2-3: Airfield Pavement Inventory Details

| Branch Name | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|---------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| RUNWAY 5-23 | RW 5-23 | 6315 | 6,900 | S | AAC | 1/1/1992 | 1 | 2 |
| RUNWAY 5-23 | RW 5-23 | 6310 | 6,900 | S | AAC | 1/1/1992 | 1 | 2 |
| RUNWAY 5-23 | RW 5-23 | 6305 | 211,297 | S | AC | 1/1/1992 | 12 | 56 |
| RUNWAY 9L-27R | RW 9L-27R | 6220 | 17,500 | S | AAC | 1/1/2011 | 1 | 3 |
| RUNWAY 9L-27R | RW 9L-27R | 6215 | 8,750 | S | AAC | 1/1/2011 | 1 | 2 |
| RUNWAY 9L-27R | RW 9L-27R | 6210 | 565,132 | S | AAC | 1/1/1991 | 20 | 114 |
| RUNWAY 9L-27R | RW 9L-27R | 6205 | 282,566 | S | AAC | 1/1/1991 | 12 | 56 |
| RUNWAY 9L-27R | RW 9L-27R | 6204 | 17,500 | P | AAC | 1/1/2011 | 1 | 3 |
| RUNWAY 9L-27R | RW 9L-27R | 6203 | 8,750 | P | AAC | 1/1/2011 | 1 | 2 |
| RUNWAY 9R-27L | RW 9R-27L | 6110 | 475,000 | P | AAC | 1/1/1998 | 20 | 96 |
| RUNWAY 9R-27L | RW 9R-27L | 6105 | 950,000 | P | AAC | 1/1/1998 | 21 | 190 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|-----------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| CENTER APRON | AP CENTER | 4998 | 48,745 | P | PCC | 1/1/1995 | 2 | 8 |
| APRON SOUTHWEST | AP SW | 4730 | 101,878 | P | AC | 1/1/2013 | 3 | 24 |
| APRON SOUTHWEST | AP SW | 4720 | 146,718 | P | AC | 1/1/2008 | 4 | 31 |
| APRON SOUTHWEST | AP SW | 4710 | 216,728 | P | AC | 1/1/2008 | 5 | 42 |
| CENTER APRON | AP CENTER | 4520 | 55,946 | P | AC | 1/1/2009 | 1 | 9 |
| CENTER APRON | AP CENTER | 4515 | 2,842 | P | APC | 1/1/2009 | 1 | 1 |
| CENTER APRON | AP CENTER | 4510 | 23,048 | P | PCC | 1/1/2009 | 1 | 3 |
| EAST APRON | AP E | 4425 | 253,400 | P | PCC | 1/1/2014 | 4 | 34 |
| EAST APRON | AP E | 4420 | 129,420 | P | AC | 1/1/2014 | 3 | 26 |
| EAST APRON | AP E | 4415 | 14,188 | P | APC | 1/1/2014 | 1 | 4 |
| EAST APRON | AP E | 4410 | 100,915 | P | AC | 12/25/1999 | 3 | 22 |
| EAST APRON | AP E | 4407 | 69,765 | P | AAC | 1/1/2004 | 3 | 18 |
| EAST APRON | AP E | 4406 | 12,949 | P | APC | 1/1/1998 | 1 | 2 |
| EAST APRON | AP E | 4404 | 76,125 | P | APC | 1/1/2004 | 2 | 12 |
| WEST APRON | AP W | 4330 | 52,136 | P | PCC | 1/1/1942 | 2 | 8 |
| WEST APRON | AP W | 4325 | 45,350 | P | PCC | 1/1/1942 | 2 | 7 |
| WEST APRON | AP W | 4320 | 75,950 | P | AC | 1/1/1979 | 2 | 15 |
| WEST APRON | AP W | 4315 | 57,374 | P | AAC | 1/1/2012 | 2 | 11 |
| WEST APRON | AP W | 4312 | 8,547 | P | PCC | 12/25/1994 | 1 | 1 |
| WEST APRON | AP W | 4310 | 47,311 | P | AAC | 1/1/2012 | 1 | 9 |
| WEST APRON | AP W | 4305 | 34,199 | P | AAC | 1/1/2012 | 1 | 6 |
| TERMINAL APRON | AP TERM | 4210 | 344,919 | P | AAC | 1/1/2009 | 8 | 74 |
| TERMINAL APRON | AP TERM | 4205 | 290,074 | P | PCC | 1/1/1989 | 4 | 37 |
| NORTH GA APRON | AP N GA | 4145 | 7,860 | P | AAC | 1/1/2013 | 1 | 2 |

| Branch Name | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|-------------------------------------|------------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| NORTH GA APRON | AP N GA | 4140 | 23,711 | P | AC | 1/1/2010 | 1 | 4 |
| NORTH GA APRON | AP N GA | 4135 | 22,180 | P | APC | 1/1/2010 | 1 | 6 |
| NORTH GA APRON | AP N GA | 4130 | 97,785 | P | AC | 1/1/2006 | 2 | 15 |
| NORTH GA APRON | AP N GA | 4125 | 51,200 | P | PCC | 1/1/2003 | 2 | 10 |
| NORTH GA APRON | AP N GA | 4120 | 96,139 | P | AC | 1/1/2003 | 3 | 22 |
| NORTH GA APRON | AP N GA | 4115 | 162,260 | P | PCC | 1/1/2003 | 3 | 20 |
| NORTH GA APRON | AP N GA | 4110 | 127,070 | P | AC | 1/1/1982 | 3 | 26 |
| NORTH GA APRON | AP N GA | 4105 | 95,800 | P | AC | 1/1/1986 | 3 | 18 |
| THRESHOLD TO RW 27L | RW 27L THR | 3315 | 34,034 | P | AAC | 1/1/2001 | 2 | 8 |
| THRESHOLD TO RW 27L | RW 27L THR | 3310 | 68,068 | P | AAC | 1/1/2001 | 3 | 14 |
| TAXIWAY V | TW V | 2210 | 13,665 | P | AAC | 1/1/2012 | 1 | 3 |
| TAXIWAY V | TW V | 2205 | 14,782 | P | AAC | 1/1/2012 | 1 | 4 |
| CONNECTOR TAXIWAY TO TERMINAL APRON | TW CONN AP | 2110 | 8,354 | P | AC | 1/1/1989 | 1 | 2 |
| TAXIWAY T | TW T | 2015 | 54,727 | P | AC | 1/1/2001 | 2 | 11 |
| TAXIWAY T | TW T | 2005 | 47,619 | P | AAC | 1/1/1986 | 2 | 9 |
| TAXIWAY R | TW R | 1820 | 49,954 | P | AAC | 1/1/2009 | 2 | 10 |
| TAXIWAY R | TW R | 1810 | 61,999 | P | AAC | 1/1/2009 | 3 | 13 |
| TAXIWAY R | TW R | 1807 | 14,115 | P | AAC | 1/1/1998 | 1 | 3 |
| TAXIWAY R | TW R | 1805 | 61,344 | P | AAC | 1/1/2009 | 2 | 13 |
| TAXIWAY Q | TW Q | 1735 | 15,616 | P | AAC | 1/1/2006 | 1 | 4 |
| TAXIWAY Q | TW Q | 1732 | 4,295 | P | AAC | 1/1/2006 | 1 | 1 |
| TAXIWAY Q | TW Q | 1725 | 106,628 | P | AAC | 1/1/2004 | 5 | 28 |
| TAXIWAY Q | TW Q | 1722 | 7,921 | P | AAC | 1/1/2004 | 1 | 2 |
| TAXIWAY Q | TW Q | 1720 | 54,194 | P | AAC | 1/1/2009 | 1 | 10 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|-------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| TAXIWAY Q | TW Q | 1710 | 12,104 | P | AAC | 1/1/2007 | 1 | 2 |
| TAXIWAY Q | TW Q | 1705 | 91,926 | P | AAC | 1/1/2007 | 3 | 19 |
| TAXIWAY V | TW V | 1610 | 36,715 | P | AC | 1/1/2013 | 1 | 9 |
| TAXIWAY V | TW V | 1605 | 61,171 | P | AAC | 1/1/2009 | 2 | 12 |
| TAXIWAY V | TW V | 1602 | 10,398 | P | AAC | 1/1/1998 | 1 | 3 |
| TAXIWAY N | TW N | 1405 | 34,529 | P | AAC | 1/1/2009 | 1 | 8 |
| TAXIWAY N | TW N | 1404 | 10,300 | P | AAC | 1/1/1998 | 1 | 2 |
| TAXIWAY M | TW M | 1325 | 5,526 | P | AAC | 1/1/2003 | 1 | 2 |
| TAXIWAY M | TW M | 1320 | 5,526 | P | AAC | 1/1/2003 | 1 | 2 |
| TAXIWAY M | TW M | 1315 | 50,873 | P | AC | 1/1/2003 | 2 | 13 |
| TAXIWAY M | TW M | 1312 | 16,404 | P | AC | 1/1/2003 | 1 | 4 |
| TAXIWAY M | TW M | 1305 | 8,625 | P | AAC | 1/1/2003 | 1 | 2 |
| TAXIWAY L | TW L | 1210 | 34,316 | P | AAC | 1/1/2009 | 1 | 7 |
| TAXIWAY L | TW L | 1204 | 10,453 | P | AAC | 1/1/1998 | 1 | 2 |
| TAXIWAY K | TW K | 1140 | 23,583 | P | AC | 1/1/2014 | 1 | 5 |
| TAXIWAY K | TW K | 1135 | 82,706 | P | AAC | 1/1/2006 | 5 | 20 |
| TAXIWAY K | TW K | 1132 | 21,084 | P | AC | 1/1/2011 | 1 | 4 |
| TAXIWAY K | TW K | 1130 | 76,184 | P | AAC | 1/1/2006 | 3 | 19 |
| TAXIWAY K | TW K | 1125 | 94,533 | P | AAC | 1/1/2006 | 4 | 23 |
| TAXIWAY K | TW K | 1120 | 9,926 | P | AAC | 1/1/2006 | 1 | 2 |
| TAXIWAY K | TW K | 1116 | 6,760 | P | AAC | 1/1/2006 | 1 | 2 |
| TAXIWAY K | TW K | 1115 | 145,056 | P | AAC | 1/1/2006 | 5 | 35 |
| TAXIWAY K | TW K | 1110 | 5,207 | P | AAC | 1/1/2006 | 1 | 1 |
| TAXIWAY B | TW B | 1105 | 101,687 | P | AAC | 1/1/2006 | 3 | 18 |

| Branch Name | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|-------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| TAXIWAY F | TW F | 810 | 64,381 | P | AC | 1/1/2013 | 3 | 14 |
| TAXIWAY V2 | TW V2 | 720 | 8,446 | P | AC | 1/1/2013 | 1 | 2 |
| TAXIWAY V1 | TW V1 | 710 | 11,452 | P | AC | 1/1/2008 | 1 | 2 |
| TAXIWAY G | TW G | 605 | 40,977 | P | AC | 1/1/2010 | 1 | 8 |
| TAXIWAY S1 | TW S1 | 525 | 19,360 | P | AC | 1/1/2014 | 1 | 5 |
| TAXIWAY S1 | TW S1 | 520 | 14,644 | P | AC | 1/1/2009 | 1 | 4 |
| TAXIWAY S | TW S | 515 | 18,556 | P | AC | 1/1/2010 | 1 | 5 |
| TAXIWAY S | TW S | 510 | 68,429 | P | AAC | 1/1/2006 | 3 | 19 |
| TAXIWAY S | TW S | 505 | 18,700 | P | AAC | 1/1/2004 | 1 | 4 |
| TAXIWAY D | TW D | 455 | 32,702 | P | AAC | 1/1/2012 | 2 | 5 |
| TAXIWAY D | TW D | 450 | 23,692 | P | AAC | 1/1/2012 | 1 | 4 |
| TAXIWAY D | TW D | 416 | 8,423 | P | AC | 1/1/2001 | 1 | 2 |
| TAXIWAY D | TW D | 415 | 19,192 | P | AC | 1/1/2001 | 1 | 5 |
| TAXIWAY D | TW D | 412 | 4,498 | P | AC | 1/1/1979 | 1 | 1 |
| TAXIWAY D | TW D | 410 | 104,051 | P | AC | 1/1/1979 | 5 | 25 |
| TAXIWAY D | TW D | 408 | 7,930 | P | AAC | 1/1/2008 | 1 | 2 |
| TAXIWAY D | TW D | 405 | 8,073 | P | AAC | 1/1/2012 | 1 | 2 |
| TAXIWAY C | TW C | 350 | 71,723 | P | AC | 1/1/2003 | 3 | 19 |
| TAXIWAY C | TW C | 340 | 20,582 | P | AAC | 1/1/2003 | 1 | 5 |
| TAXIWAY C | TW C | 330 | 108,166 | P | AC | 1/1/1991 | 3 | 27 |
| TAXIWAY C | TW C | 320 | 41,105 | P | AAC | 1/1/2009 | 1 | 9 |
| TAXIWAY C | TW C | 315 | 63,222 | P | AAC | 1/1/2004 | 3 | 17 |
| TAXIWAY C | TW C | 310 | 13,011 | P | AAC | 1/1/2004 | 1 | 3 |
| TAXIWAY C | TW C | 305 | 43,008 | P | AAC | 1/1/2007 | 2 | 8 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|-------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| TAXIWAY A | TW A | 132 | 58,319 | P | AAC | 1/1/2009 | 2 | 13 |
| TAXIWAY A | TW A | 130 | 36,222 | P | AAC | 1/1/2009 | 1 | 8 |
| TAXIWAY A | TW A | 120 | 691,660 | P | AAC | 1/1/2009 | 10 | 172 |
| TAXIWAY A | TW A | 105 | 38,493 | P | AAC | 1/1/2009 | 1 | 8 |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.

3. AIRFIELD PAVEMENT CONDITION

Airfield pavement distresses and condition were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D 5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating.

The program has been updated from ASTM D 5340-04, released in 2004, to ASTM D 5340-12, released in 2013, for this SAPMP update. The primary updates include the separation of certain distress types and the addition of new types with corresponding changes to PCI calculation. These changes in distress classification may result in small variances in the PCI values from the previous inspection analysis.

Below is a brief description of the changes to the distresses presented in the ASTM D 5340 methodology and a table summarizing the deduction affected.

- a) Flexible Asphalt Concrete Pavement distresses for airfield pavements: The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering". Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling", the PCI deduction is not as high as the former "Weathering and Raveling". Therefore, areas identified only as "(57) Weathering" based on current ASTM standards, which were previously identified as "(52) Weathering and Raveling", may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.
- b) Rigid Portland Cement Concrete Pavement distresses for airfield pavements: The previous methodology defined "(70) Scaling" as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as "(76) Alkali-Silica Reaction / ASR". As a result the previous "(70) Scaling" numerical deduction

contribution to the PCI has been reduced. Previous inspections that recorded "(70) Scaling", and currently do not exhibit "(76) Alkali-Silica Reactivity / ASR" may potentially see an increase in PCI. Additionally, (73) Shrinkage Cracks has been redefined as (73) Shrinkage Cracking. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.

| Distress Updates to Reflect ASTM 5340-12 | | | |
|--|-------------------------------------|--------------------------------------|--------------|
| Use and Surface Type | Old 5340-04 Distress | New Distress | Deduct Curve |
| AC/AAC/APC Airfield | (52) Weathering & Raveling - Low | (52) Raveling - Low | No Change |
| | (52) Weathering & Raveling - Medium | (52) Raveling - Medium | No Change |
| | (52) Weathering & Raveling - High | (52) Raveling - High | No Change |
| | N/A | (57) Weathering - Low | New |
| | N/A | (57) Weathering - Medium | New |
| | N/A | (57) Weathering - High | New |
| PCC Airfield | (70) Scaling - Low | (70) Scaling - Low | New |
| | (70) Scaling - Medium | (70) Scaling - Medium | New |
| | (70) Scaling - High | (70) Scaling - High | New |
| | N/A | (76) Alkali Silica Reaction – Low | New |
| | N/A | (76) Alkali Silica Reaction – Medium | New |
| | N/A | (76) Alkali Silica Reaction – High | New |

3.1 Inspection Methodology

A pavement condition survey inspection is performed by measuring the amount and severity of defined pavement distresses observed within the boundaries of sample units. These distresses, as defined by ASTM D 5340, are generally caused by traffic fatigue loading, exposure to climate and elements, and other airfield specific factors. This data is collected by field personnel experienced in pavement condition survey inspection. Data collection is then transferred into the FDOT MicroPAVER database system. MicroPAVER (also known as PAVER) is used to calculate PCI values using the methodology described in ASTM D 5340-12. The values are calculated for each sample and extrapolated on a Section level to determine an area-weighted PCI value ranging from 0 to 100 and one of seven condition ratings. Tables 3-1 and 3-2 describe the distresses as defined by the ASTM D 5340-12 and adopted for the SAPMP procedures.

Table 3-1: Airfield Pavement Distresses for Asphalt Concrete

| Code | Distress | Primary Mechanisms |
|------|----------------------------------|----------------------------------|
| 41 | Alligator Cracking | Load / Fatigue Failure |
| 42 | Bleeding | Construction Quality/ Mix Design |
| 43 | Block Cracking | Climate / Age |
| 44 | Corrugation | Load / Construction Quality |
| 45 | Depression | Subgrade Quality |
| 46 | Jet Blast | Aircraft |
| 47 | Joint Reflection - Cracking | Climate / Prior Pavement |
| 48 | Longitudinal/Transverse Cracking | Climate / Age |
| 49 | Oil Spillage | Aircraft / Vehicle |
| 50 | Patching | Utility / Pavement Repair |
| 51 | Polished Aggregate | Repeated Traffic Loading |
| 52 | Raveling | Climate / Load |
| 53 | Rutting | Repeated Traffic Loading |
| 54 | Shoving | PCC Pavement Growth / Movement |
| 55 | Slippage Cracking | Load / Pavement Bond |
| 56 | Swelling | Climate / Subgrade Quality |
| 57 | Weathering | Climate |

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete

| Code | Distress | Primary Mechanisms |
|------|-------------------------|---|
| 61 | Blow-up | Climate / Alkali Silica Reaction |
| 62 | Corner Break | Load Repetition / Curling Stresses |
| 63 | Linear Cracking | Load Repetition / Curling Stresses / Shrinkage Stresses |
| 64 | Durability Cracking | Freeze-Thaw Cycling |
| 65 | Joint Seal Damage | Material Deterioration / Construction Quality |
| 66 | Small Patch | Pavement Repair |
| 67 | Large Patch/Utility Cut | Utility / Pavement Repair |
| 68 | Popout | Freeze-Thaw Cycling |
| 69 | Pumping | Load Repetition / Poor Joint Sealant |
| 70 | Scaling/Crazing | Construction Quality / Freeze-Thaw Cycling |
| 71 | Faulting | Load Repetition / Subgrade Quality |
| 72 | Shattered Slab | Overloading |
| 73 | Shrinkage Cracking | Construction Quality / Load |
| 74 | Joint Spalling | Load Repetition / Infiltration of Incompressible Material |
| 75 | Corner Spalling | Load Repetition / Infiltration of Incompressible Material |
| 76 | Alkali-Silica Reaction | Construction Quality / Climate |

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

3.2 Airfield Pavement Condition Index Rating Results

From the condition survey inspection performed in 2015 at Melbourne International Airport, the overall weighted average PCI value is 75 representing a condition rating of Satisfactory.

The airport's airfield pavements exhibited distresses typically associated with climate and age, structural, and construction quality. The predominant AC and AAC pavement distresses observed include: longitudinal and transverse cracking, joint reflection cracking, block cracking, swelling, bleeding, oil spillage, depression, patching, alligator cracking, raveling, and weathering. The predominant PCC pavement distresses observed include: scaling/crazing, shrinkage cracking, joint spalling, corner spalling, linear cracking, small patch, faulting, large patch, corner break, joint seal damage, shattered slab.

Runway 9R-27L exhibited pavement distresses typically associated with fatigue loading, construction quality, and climate/age. Distresses exhibited by Runway 9R-27L include: longitudinal and transverse cracking, swelling, alligator cracking, depressions, patching, raveling, and weathering. Alligator cracking is considered a major structural distress and is caused by fatigue failure of the asphalt surface under repeated traffic loading. The observed alligator cracking was located near the touch down areas at both ends of the runway. Swelling was observed throughout the runway, and is caused by water within the pavement structure that heats due to warm temperatures, which builds up pressure. The pressure causes the pavement to swell and often crack.

Runway 9L-27R observed distresses include: longitudinal and transverse cracking, alligator cracking, patching, swelling, bleeding, raveling, and weathering. Alligator was observed near touch down areas on both ends of the runway. Longitudinal and transverse cracking was observed in large quantities down the keel of the runway indicative of the advanced age of the pavement. Bleeding was observed in isolated areas of the runway. Bleeding occurs when the pavement mix is too rich and/or lack of air voids, causing the asphalt binder to be released to the surface. Bleeding is irreversible and is typically associated with construction quality.

Runway 5-23 distresses are typically associated with climate/age and construction quality. The exhibited distresses include: longitudinal and transverse cracking, bleeding, block cracking, swelling, raveling, and weathering.

Taxiway Alpha is composed of AC pavement and services the primary Runway 9R-27L. Taxiway Alpha observed distresses include: longitudinal and transverse cracking, block cracking, swelling, bleeding, raveling, and weathering. These distresses are typically associated with climate/age and construction quality.

It is significant to note that slippage cracking was observed on Taxiway Alpha adjacent to Taxiway Lima. Slippage cracking occurs when braking or turning movements cause the pavement surface to slide and deform. This is typically a result of a poor bond between the surface pavement and the adjacent layer in the pavement structure.

Taxiway Kilo services Runway 9L-27R and exhibited distresses associated with climate/age, pavement repairs, and construction quality. Distresses observed include: longitudinal and transverse cracking, swelling, depression, patching,

raveling, and weathering. Taxiway Kilo from Runway 9R-27L to Taxiway G was widened from 40-ft to 50-ft via a 10-ft of new pavement.

The remaining AC and AAC taxiways exhibited distresses associated with climate/age, pavement repairs, and construction quality. The pavement condition indices range from 55-100. Notable new pavements include Taxiway Foxtrot and Taxiway Victor constructed in 2013.

Terminal Apron AC pavement distresses include: longitudinal and transverse cracking, swelling, bleeding, depression, and weathering. Terminal Apron PCC pavement distresses include: faulting, scaling/crazing, shrinkage cracking, small patch, large patch, joint spalling, corner spalling, and linear cracking. Faulting is described as a difference in elevation at a joint or crack caused by upheaval or consolidation.

West Apron is composed of PCC and AC pavement types. The PCC pavements exhibited distresses associated with structural failure. Observed distresses include shattered slab, linear cracking, joint spalling, corner spalling, shrinkage cracking, joint seal damage, faulting, and scaling/crazing. Shattered slabs are described as intersecting crack that break the slab into four or more pieces due to overloading and/or inadequate support. The AC pavements of West Apron vary in condition rating from Good to Fair with distresses common to climate and age such as longitudinal and transverse cracking, block cracking, raveling and weathering. A few isolated instances of depressions were exhibited. Depressions are caused by settlement of the foundation soil.

The remaining apron AC pavements vary in pavement condition with pavement condition indices ranging from 45 -100. The majority of distresses can be attributed to climate/age, along with isolated instances of construction quality issues. The remaining PCC pavements range in pavement condition indices from 74-100.

Appendix B contains Table B-1 which summarizes the Section Condition Values and an Airfield Pavement Condition Index Rating Exhibit, Figure B-1, which depicts the PCI results by Section. Appendix C contains MicroPAVER reports of PCI results by Branch and Section. Appendix H includes the most current detailed distress data generated by MicroPAVER for each inspected sample unit for this update.

The pavement condition at Melbourne International Airport is represented in Figure 3-1 in accordance with the condition categories and PCI scale referenced in ASTM D 5340. Further detail is provided in Table 3-3 which describes the breakdown of the airport's airfield conditions according to area and use.

Figure 3-1: Airfield Pavement Condition Index Rating Summary





Table 3-3: Pavement Condition Index Rating Summary

| Airfield Pavement Use | | |
|-----------------------|---------------------------|-------------------|
| Use | Average Area-Weighted PCI | Condition Rating |
| Runway | 65 | FAIR |
| Taxiway | 80 | SATISFACTORY |
| Apron | 79 | SATISFACTORY |
| Condition Area | | |
| Condition Rating | Area (SF) | Relative Area (%) |
| Good | 1,823,320 | 21% |
| Satisfactory | 4,197,385 | 48% |
| Fair | 2,358,818 | 27% |
| Poor | 189,193 | 2% |
| Very Poor | - | 0% |
| Serious | 8,547 | 1% |
| Failed | 97,486 | 1% |


Approximately 69% of the airfield network is in Good and Satisfactory condition, while 4% of the network is in a Poor to Failed condition. Table 3-3 provides a breakdown of total area for each pavement by condition rating. Figures 3.2 a, b, c depict the condition rating of the airfield pavement by Branch Use. Photographs taken during the condition survey inspection are included in Appendix G. The photographs included are intended to be representative of the distress observed.

Figure 3-2: Percentage of Pavement Area by Condition Rating by Use


(a) Runway



(b) Taxiway



(c) Apron



4. PAVEMENT PERFORMANCE

Pavement performance models are developed from the distress data collected for the SAPMP for the Florida Airports System. This data is consolidated in a database and organized by inspection date, pavement type, age, pavement use, and airport category. The pavement performance models are used to develop broad prediction models, also known as pavement condition deterioration curves.

The consolidation of the Florida Airports System's pavement infrastructure within the FDOT SAPMP is based on data that has been collected in a consistent method of measurement. The historic pavement condition, or performance trend, has been compiled throughout the system with data from the inception of the SAPMP. This data is processed into models that have been analyzed and developed into prediction curves based upon pavement characteristics. These characteristics include; climate, construction material, and operations. Each model has been developed based on the following criteria:

- AIRPORT TYPE (Primary, Regional Reliever, or General Aviation)

- >FACILITY USE (Runway, Taxiway, or Apron)

- >>FACILITY SURFACE TYPE (AC, AAC, APC, or PCC)

The historic trends of pavement performance at Florida airport facilities for all performance models are consolidated within the program database. This information is utilized in the prediction of pavement performance based on the current PCI determined from the inspections that took place between 2013 and 2015. Major rehabilitation is planned based on the predicted PCI. The intent of this is for both the individual airport and the FDOT District personnel to be aware of anticipated major rehabilitation work based on condition.

Each airport's airfield pavement section condition, for a given inspection year, is one data point that was used as the basis of each performance trend using a performance model based on pavements of similar background. Figures 4-1, 4-2, and 4-3 represent the pavement performance prediction at Melbourne International Airport based on pavement use. Each figure depicts the FDOT recommended Minimum Service Level PCI value for each facility use.

Figure 4-1: Runway Pavement Performance Prediction Summary




Figure 4-2: Taxiway Pavement Performance Prediction Summary





Figure 4-3: Apron Pavement Performance Prediction Summary



Pavement performance modeling to predict the future PCI is primarily done to predict PCI at the Section level for the purpose of planning Major Rehabilitation work. In Appendix D, Table D-1 represents the predicted area-weighted PCI by Section for the airport's airfield pavement infrastructure.

5. AIRFIELD PAVEMENT MAINTENANCE POLICIES AND COSTS

5.1 Policies

Airfield Pavement Maintenance policies are guidance on pavement construction methods used to develop, maintain, repair, and rehabilitate pavement infrastructure based on distresses encountered during the condition surveys.

Maintenance refers to the repair and preservation-type activities that are applied locally to specific distress types on the pavement. These activities for the SAPMP are considered preventative and corrective in nature and are highly recommended to help improve pavement performance and extend pavement life. The SAPMP maintenance policies are based on the FAA Advisory Circular 150/5380-6C and guidance provided in the FDOT Airfield Pavement Repair Manual.

For the purpose of the SAPMP; the maintenance repair needs that are identified and quantified are based solely on the pavement distresses observed and recorded at the time of the inspection. Based on a specific distress type and severity observed, a particular repair work type is recommended and quantified based on the extrapolated section distresses. The repair program identified is specific to the current distresses. Future maintenance planning budgets are based on this initial determination. Tables 5-1 and 5-2 provide the list of maintenance activities incorporated into the SAPMP MicroPAVER database to treat specific distress types and severities.

Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|--|---------------|----------------------------------|----------|------------------------------|-------------|
| Flexible Asphalt Concrete (AC, AAC, APC) | 41 | Alligator Cracking | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 42 | Bleeding | N/A | Partial Depth Pavement Patch | Square Feet |
| | 43 | Block Cracking | L | Seal Coat Treatment | Square Feet |
| | 43 | Block Cracking | M, H | Full Depth Pavement Patch | Square Feet |
| | 44 | Corrugation | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 45 | Depression | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 46 | Jet Blast Erosion | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 47 | Joint Reflection Cracking | L | Crack Sealing | Linear Feet |
| | 47 | Joint Reflection Cracking | M, H | Full Depth Pavement Patch | Square Feet |
| | 48 | Longitudinal/Transverse Cracking | L, M, H | Crack Sealing | Linear Feet |
| | 49 | Oil Spillage | L, M | Seal Coat Treatment | Square Feet |
| | 49 | Oil Spillage | H | Full Depth Pavement Patch | Square Feet |
| | 50 | Patch and Utility Patching | M | Full Depth Pavement Patch | Square Feet |
| | 50 | Patch and Utility Patching | H | Full Depth Pavement Patch | Square Feet |
| | 51 | Polished Aggregate | L, M, H | Slurry Seal Coat Treatment | Square Feet |
| | 52 | Raveling | L, M | Slurry Seal Coat Treatment | Square Feet |
| | 52 | Raveling | H | Partial Depth Pavement Patch | Square Feet |
| | 53 | Rutting | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 54 | Shoving | L, M, H | Grinding / Removal | Square Feet |
| | 55 | Slippage Cracking | L, M, H | Full Depth Pavement Patch | Square Feet |
| | 56 | Swelling | M, H | Full Depth Pavement Patch | Square Feet |
| | 57 | Weathering | M, H | Seal Coat Treatment | Square Feet |

Table 5-2: Recommended PCC Maintenance and Repair Policy

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|----------------------|---------------|---|----------|-------------------------------------|-------------|
| Rigid Pavement (PCC) | 61 | Blowup | L, M, H | Slab Replacement / Full Depth Patch | Square Feet |
| | 62 | Corner Break | L, M, H | Partial Slab Full Depth Patch - PCC | Square Feet |
| | 63 | Longitudinal/Transverse/Diagonal Cracking | H | Crack Sealing - PCC | Linear Feet |
| | 64 | Durability Cracking | M, H | Slab Replacement / Full Depth Patch | Square Feet |
| | 65 | Joint Seal Damage | L, M, H | Joint Seal Repair (Local) | Linear Feet |
| | 66 | Patching, Small | M, H | Partial Slab Full Depth Patch - PCC | Square Feet |
| | 67 | Patching, Large | M, H | Partial Slab Full Depth Patch - PCC | Square Feet |
| | 69 | Pumping | L, M, H | Slab Stabilization / Slab Jacking | Square Feet |
| | 70 | Scaling/Map Cracking/Crazing | L, M | Micro-mill and Seal - PCC | Square Feet |
| | 70 | Scaling/Map Cracking/Crazing | H | Slab Replacement / Full Depth Patch | Square Feet |
| | 71 | Settlement / Faulting | L | Micro-mill and Seal - PCC | Square Feet |
| | 71 | Settlement / Faulting | M, H | Slab Stabilization / Slab Jacking | Square Feet |
| | 72 | Shattered Slab | L, M, H | Slab Replacement / Full Depth Patch | Square Feet |
| | 73 | Shrinkage Cracks | N/A | Crack Sealing - PCC | Linear Feet |
| | 74 | Longitudinal/Transverse Joint Spalling | L, M, H | Partial Patch - PCC | Square Feet |

| Surface Type | Distress Code | Distress Name | Severity | Maintenance Work Type | Work Unit |
|--------------|---------------|------------------------|----------|-------------------------------------|-------------|
| | 75 | Corner Spalling | L, M, H | Partial Patch - PCC | Square Feet |
| | 76 | Alkali-Silica Reaction | L | Seal Coat Treatment | Square Feet |
| | 76 | Alkali-Silica Reaction | M | Micro-mill and Seal - PCC | Square Feet |
| | 76 | Alkali-Silica Reaction | H | Slab Replacement / Full Depth Patch | Square Feet |

Though proactive pavement maintenance and preservation is highly recommended in an APMS; it is recognized that pavement that has deteriorated below a certain PCI would benefit more from major rehabilitation rather than localized maintenance and repair work. Major rehabilitation is recommended when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that maintenance repair efforts are no longer cost-efficient. This critical point is called "Critical PCI". The critical PCI levels for different pavement and branch types were established by the FDOT and were used in this update to develop a maintenance and major rehabilitation plan for the airport. Sections that are above the "Critical PCI" levels will be recommended for maintenance, repair, and preservation treatments, assuming there are no significant load-related distresses. For those Sections below the Critical PCI, the recommended action will consist of major rehabilitation work. This approach is used for the Section's Current PCI value and the predicted PCI value for future rehabilitation.

The FDOT has recommended minimum service level PCI for airports based on pavement facility use, airport type, and expected loading frequency. This minimum service level PCI is recommended to ensure the pavement provides a safe operational surface and efficiently uses maintenance and rehabilitation budgets. Separately, the Critical PCI is a value based on historic pavement performance trends and costs. It is at a PCI value of 65, for most airports, at which major rehabilitation is recommended over maintenance level efforts. Table 5-3 identifies the FDOT recommended PCI by use and the critical PCI value for the most important pavements at the airport. This is due to the condition of the pavement and the cost effectiveness of the work. A very important concept of a good pavement management system is the proactive preservation of

pavements that are above Critical PCI condition. Conversely, allowing pavement to deteriorate beyond maintenance and performing “worst first” major rehabilitation may cost much more over the life of a pavement.

Table 5-3: Critical and Minimum Service Level PCI for Primary Airports

| Use | FDOT Recommended PCI | Critical PCI |
|---------|----------------------|--------------|
| Runway | 75 | 65 |
| Taxiway | 70 | 65 |
| Apron | 65 | 65 |

Based on historic trends of pavement performance and industry standard practices in pavement maintenance and rehabilitation, the SAPMP included general guidance on construction activity based on condition PCI, as shown on Table 5-4. It is recommended that further investigation of underlying pavement conditions is performed at the design phase.

Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI

| Category | Activity | PCI Range |
|----------------|---|-----------|
| Maintenance | <ul style="list-style-type: none"> ▪ Crack Sealing (AC/PCC) ▪ Partial Depth Patching (AC) ▪ Full Depth Patching (AC/PCC) ▪ Surface Treatment (AC) | 75 - 90 |
| Rehabilitation | <ul style="list-style-type: none"> ▪ Mill and Overlay (AC) ▪ Concrete Pavement Restoration (PCC) | 40 - 74 |
| | <ul style="list-style-type: none"> ▪ Full Depth Pavement Reconstruction | 0 - 39 |

The PCI standard scale ranges from a value of 0, typically representing a pavement in a failed condition, to a value of 100 which typically represents a pavement in new or good condition. Generally, airfield pavement sections with a PCI of 75 or higher that are not exhibiting distresses due to aircraft loading will benefit from maintenance activities such as crack sealing, patching, and surface treatments. Pavement sections with PCI values within the range of 40 to 74 may require major rehabilitation, such as a mill and overlay. Lastly, pavement sections with a PCI value of 40 or less are recommended to undergo pavement

reconstruction. Generally pavement reconstruction is the only practical means of restoration due to the substantial distresses observed in the pavement structure. Since PCI values are based solely on the visual determination of pavement distresses and deterioration, this method does not provide a direct measure of structural integrity.

5.2 Unit Costs

The FDOT SAPMP developed and updated the maintenance and major rehabilitation costs based on public cost databases for airport and highway pavement construction. Additionally, cost data collected from FDOT and FAA sponsored projects in the Florida Airports System were utilized to identify construction cost trends across the state.

The maintenance, repair, and preservation activity costs have been updated and developed using readily available construction cost data at the time of this update. The costs depicted in this report for both maintenance and major rehabilitation are intended for planning purposes.

5.3 Maintenance, Repair, and Major Rehabilitation

FDOT recognizes that although pavement mill and overlay is recommended for flexible asphalt concrete pavement within a PCI range from 40 to 74, it is conceivable that airports may not have adequate funding to perform this type of major rehabilitation. A comprehensive surface treatment; per the treatments described in FAA AC 150/5370-10G Standards for Specifying Construction of Airports, as a maintenance rehabilitation activity, can be used in lieu of asphalt concrete pavement mill and overlay. However, it should be understood that these measures provide only a short term extension of pavement life. While the cost of surface treatments are significantly lower than that of pavement mill and overlay, it is not intended or implied to be a full rehabilitative measure for long term benefit. Table 5-5 and Table 5-6 provide budget costs associated with the work types shown in the table.

Table 5-5: AC Maintenance Unit Costs

| Surface Type | Maintenance Work Type | Cost | Work Unit |
|---|------------------------------|--------|-------------|
| Flexible Asphalt Concrete (AC, AAC, APC) | Full Depth Pavement Patch | \$5.00 | Square Feet |
| | Partial Depth Pavement Patch | \$3.00 | Square Feet |
| | Seal Coat Treatment | \$0.55 | Square Feet |
| | Crack Sealing | \$2.75 | Linear Feet |
| | Slurry Seal Coat Treatment | \$0.55 | Square Feet |
| | Grinding / Removal | \$2.10 | Square Feet |

Table 5-6: PCC Maintenance Unit Costs

| Surface Type | Maintenance Work Type | Cost | Work Unit |
|-------------------------|-------------------------------------|---------|-------------|
| Rigid Pavement (PCC) | Slab Replacement / Full Depth Patch | \$45.00 | Square Feet |
| | Partial Patch - PCC | \$19.10 | Square Feet |
| | Crack Sealing - PCC | \$4.25 | Linear Feet |
| | Joint Seal Repair (Local) | \$3.00 | Linear Feet |
| | Slab Stabilization / Slab Jacking | \$45.00 | Square Feet |
| | Micro-mill and Seal - PCC | \$1.00 | Square Feet |
| | Seal Coat Treatment | \$1.00 | Square Feet |

As part of the SAPMP update, the distress data observed at each airport during the inspection is extrapolated on a section basis to make maintenance recommendations. These recommendations are a direct result of the distress types, severities, and quantities observed at the time of inspection. The maintenance recommendations and planning costs are correlated with the airport's airfield pavement network's overall area weighted PCI and used to plan

future maintenance costs. Future maintenance costs are planning budgets that are not specific to a pavement section, but are estimates for the entire airfield. Table 5-7 provides budget costs associated with the rehabilitation activities.

Table 5-7: Rehabilitation Activities and Unit Costs by Condition for Primary Airports

| Category | Activity | PCI Range | Cost/SqFt |
|----------------|---------------------------------------|-----------|-----------|
| Rehabilitation | ▪ Mill and Overlay (AC) | 40 - 74 | \$13.00 |
| | ▪ Concrete Pavement Restoration (PCC) | | \$18.00 |
| | ▪ Full Depth Pavement Reconstruction | 0 - 39 | \$23.00 |

A cost scale has been developed based on PCI to develop planning level budgets for the airfield pavements. The cost scale is adjusted by project year based on an assumed inflation rate of 3%. In Appendix E, Table E-1 summarizes the Year-1 maintenance and repair recommendations based on the most recent inspection. The summary in Table E-1 does not take into account any rehabilitation activities, but rather summarizes preventative activities for all PCI ranges, including below critical PCI sections.

6. MAJOR PAVEMENT REHABILITATION NEEDS

As part of the SAPMP, major pavement rehabilitation planning is developed based on current and predicted PCI in comparison with the Critical PCI. The Critical PCI has been determined based on the historic trends of pavement condition relative to the benefit of maintenance and repair activities. Pavement sections determined to have a PCI less than that of the Critical PCI are assumed to have deteriorated to a point at which maintenance and repair level activity would provide little benefit.

The objective of the major pavement rehabilitation needs analysis is to provide planning level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value from a functionality perspective. In addition, major rehabilitation is also recommended when the Section PCI is above the Critical PCI but the Section has load-related PCI distresses. However, most major rehabilitation work is recommended when the Section PCI is below the Critical PCI, which is when maintenance and repair level activities are not considered to be cost effective.

Major rehabilitation is identified within the SAPMP as major construction activity that would result in an improvement or "resetting" of the pavement section's PCI to a value of 100. Such activities could include; mill and hot-mix asphalt overlay and re-construction. This analysis was conducted with no constraints to budgets as a means to identify all pavement projects based on Critical PCI for a 10-year duration. It is recommended that the airport use this as a planning tool for future project development and prioritization. Table 6-1 depicts the major rehabilitation work identified on the pavement section level based on current and predicted pavement PCI.

Airports should consider the major rehabilitation work types of mill and overlay, PCC restoration, and reconstruction planning level classifications only. Additional design level investigation in accordance to the FAA Advisory Circulars will be required to identify specific areas within each section that are subject to reconstruction, mill and overlay, and PCC restoration. The work and budgets identified are intended for the planning level not the design level. Areas identified as mill and overlay may in fact require select areas of reconstruction should load-based distresses observed warrant it.

Table 6-1: Summary of Major Rehabilitation


| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|------|------------|------------|------------------|----------------|------------------|---------------|
| 2015 | AP E | 4406 | \$ 235,672.00 | 50 | Mill and Overlay | 100 |
| 2015 | AP E | 4410 | \$ 2,083,391.00 | 45 | Mill and Overlay | 100 |
| 2015 | AP N GA | 4110 | \$ 2,287,267.00 | 59 | Mill and Overlay | 100 |
| 2015 | AP W | 4312 | \$ 196,581.00 | 13 | Reconstruction | 100 |
| 2015 | AP W | 4320 | \$ 1,367,100.00 | 57 | Mill and Overlay | 100 |
| 2015 | AP W | 4325 | \$ 1,043,050.00 | 0 | Reconstruction | 100 |
| 2015 | AP W | 4330 | \$ 1,199,128.00 | 5 | Reconstruction | 100 |
| 2015 | RW 5-23 | 6310 | \$ 124,200.00 | 57 | Mill and Overlay | 100 |
| 2015 | RW 5-23 | 6315 | \$ 124,200.00 | 54 | Mill and Overlay | 100 |
| 2015 | RW 9L-27R | 6210 | \$ 10,172,369.00 | 61 | Mill and Overlay | 100 |
| 2015 | RW 9R-27L | 6105 | \$ 17,100,001.00 | 58 | Mill and Overlay | 100 |
| 2015 | TW D | 410 | \$ 1,872,918.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW D | 412 | \$ 80,970.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW S | 505 | \$ 336,600.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW S | 510 | \$ 1,231,722.00 | 55 | Mill and Overlay | 100 |
| 2017 | AP N GA | 4105 | \$ 1,829,416.00 | 63 | Mill and Overlay | 100 |
| 2018 | AP N GA | 4120 | \$ 1,890,970.00 | 64 | Mill and Overlay | 100 |
| 2018 | AP W | 4315 | \$ 1,128,494.00 | 64 | Mill and Overlay | 100 |
| 2018 | RW 5-23 | 6305 | \$ 4,156,013.00 | 65 | Mill and Overlay | 100 |
| 2019 | RW 27L THR | 3310 | \$ 1,379,000.00 | 65 | Mill and Overlay | 100 |
| 2019 | TW R | 1807 | \$ 285,964.00 | 65 | Mill and Overlay | 100 |
| 2020 | RW 9R-27L | 6110 | \$ 9,911,794.00 | 65 | Mill and Overlay | 100 |
| 2020 | TW K | 1120 | \$ 207,133.00 | 65 | Mill and Overlay | 100 |
| 2020 | TW M | 1305 | \$ 179,977.00 | 65 | Mill and Overlay | 100 |
| 2020 | TW M | 1312 | \$ 342,308.00 | 64 | Mill and Overlay | 100 |
| 2020 | TW V | 1602 | \$ 216,977.00 | 65 | Mill and Overlay | 100 |
| 2021 | AP CENTER | 4515 | \$ 61,083.00 | 64 | Mill and Overlay | 100 |
| 2021 | TW C | 315 | \$ 1,358,836.00 | 65 | Mill and Overlay | 100 |
| 2022 | AP N GA | 4130 | \$ 2,164,738.00 | 64 | Mill and Overlay | 100 |
| 2022 | RW 27L THR | 3315 | \$ 753,436.00 | 63 | Mill and Overlay | 100 |
| 2022 | RW 9L-27R | 6205 | \$ 6,255,366.00 | 63 | Mill and Overlay | 100 |
| 2022 | TW Q | 1722 | \$ 175,351.00 | 65 | Mill and Overlay | 100 |
| 2023 | TW C | 330 | \$ 2,466,386.00 | 64 | Mill and Overlay | 100 |
| 2023 | TW L | 1210 | \$ 782,464.00 | 65 | Mill and Overlay | 100 |
| 2023 | TW S1 | 520 | \$ 333,910.00 | 65 | Mill and Overlay | 100 |
| 2024 | AP CENTER | 4998 | \$ 1,144,821.00 | 64 | PCC Restoration | 100 |

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2024 | AP SW | 4710 | \$ 5,090,052.00 | 65 | Mill and Overlay | 100 |
| 2024 | AP SW | 4720 | \$ 3,445,807.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW L | 1204 | \$ 245,507.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW M | 1315 | \$ 1,194,799.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW M | 1320 | \$ 129,778.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW Q | 1705 | \$ 2,158,966.00 | 65 | Mill and Overlay | 100 |
| Total = | | | \$ 88,744,515.00 | | | |

*Costs are adjusted for inflation at 3%.

The 10-year major rehabilitation program addresses those pavement sections that have a current or project PCI that is below the Critical PCI of 65 during the 10-year analysis period. The unconstrained or “unlimited budget” Major Rehabilitation Program is compared to a “No Major Rehabilitation Program” scenario in Figure 6-1. As shown, if no major rehabilitation work is completed in the next 10 years at your airport, the average PCI may be 22 points less than a plan that provides timely repairs to the airfield pavements.

Figure 6-1: 10-Year Major Rehabilitation Budget Scenario Analysis



7. PREVENTATIVE AND MAJOR REHABILITATION PLANNING


The preventative and major rehabilitation results include activities that are based on distresses observed and unconstrained by budget limits. FDOT recognizes that the projects identified as Year-1 needs in 2015, based on condition, may exceed a typical annual budget level. It is recommended that each airport further evaluate each project's feasibility and desirability based on the airport's future development plans and budgeting scenarios.

In an effort to identify appropriate budget levels, the 10-year Preventative and Major Rehabilitation analysis evaluated projected budget needs based on predicted PCI of each pavement section. Table 7-1 and Figure 7-1 provides a summary of the expected preventative and major rehabilitation for each program year.

Table 7-1: 10-Year Preventative and Major Rehabilitation Summary

| Program Year | Preventative | Major Rehabilitation | Total Year Costs |
|--------------|-----------------|----------------------|-------------------|
| 2015 | \$ 1,311,049.00 | \$ 39,455,168.43 | \$ 40,766,217.43 |
| 2016 | \$ 1,490,288.97 | \$ - | \$ 1,490,288.97 |
| 2017 | \$ 1,629,990.71 | \$ 1,829,416.05 | \$ 3,459,406.75 |
| 2018 | \$ 1,646,657.58 | \$ 7,175,477.05 | \$ 8,822,134.63 |
| 2019 | \$ 1,786,906.98 | \$ 1,664,963.98 | \$ 3,451,870.96 |
| 2020 | \$ 1,735,877.72 | \$ 10,858,188.57 | \$ 12,594,066.29 |
| 2021 | \$ 1,969,713.43 | \$ 1,419,919.20 | \$ 3,389,632.63 |
| 2022 | \$ 2,029,814.42 | \$ 9,348,889.83 | \$ 11,378,704.25 |
| 2023 | \$ 2,232,549.55 | \$ 3,582,761.12 | \$ 5,815,310.68 |
| 2024 | \$ 2,229,689.80 | \$ 13,409,731.36 | \$ 15,639,421.16 |
| Total = | | | \$ 106,807,053.75 |

Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary



According to the most recent inspections at the time of this update; the following pavement sections were identified as a Year-1 need for major rehabilitation:

- ⦿ Runway 5-23 – Sections 6310 and 6315
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ Runway 9L-27R – Section 6210
 - Mill and Overlay attributed to structural, climate/age, and construction quality.
- ⦿ Runway 9R-27L– Section 6105
 - Mill and Overlay attributed to structural, climate/age, and construction quality.
- ⦿ East Apron – Sections 4406 and 4410
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ West Apron – Sections 4312, 4325, and 4330
 - Reconstruction attributed to structural, climate/age, and construction quality.
- ⦿ West Apron – Section 4320
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ North General Aviation Apron – Section 4110
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ Taxiway S – Sections 505 and 510

- Mill and Overlay attributed to climate/age and construction quality.
- ◎ Taxiway D – Sections 410 and 412
 - Mill and Overlay attributed to climate/age.

Appendix E summarizes the preventative repair recommendations for Year-1 and Appendix F provides an exhibit, Airfield Pavement Major Rehabilitation that depicts the recommended major rehabilitation on the airfield pavement network according to work type and year.

8. VISUAL AID EXHIBITS

8.1 Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit in Appendix A depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D 5340-12. The exhibits are prepared and updated with information provided by the airport and from aerial imagery from the FDOT Surveying and Mapping publications.

8.2 Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in Appendix A depicts any recent airfield pavement construction activity reported by the airport. The exhibit is intended to identify pavement sections that may have changed in geometry and pavement composition that would affect the section delineation. The information provided in the Airport Response Form was used as the basis of the changes and confirmed with the airport personnel at the time of inspection.

8.3 Airfield Pavement Condition Index Rating Exhibit

The Airfield Pavement Condition Index Rating Exhibit in Appendix B has been prepared based on the section condition analysis of the distress data collected during the recent condition index rating survey. The exhibit graphically depicts the inventory with associated condition rating colors and PCI values.

8.4 Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit in Appendix F has been prepared based on the section pavement performance model and major rehabilitation analysis. The exhibit graphically depicts the inventory with associated rehabilitation activity, program year, and the planning level costs.

8.5 Airfield Pavement Condition Survey Inspection Photographs

During the field condition survey inspection; inspectors photographed representative distress types observed. Select photographs are provided in Appendix G to provide visual support to special pavement conditions or distresses observed.

9. RECOMMENDATIONS

The recommendations developed are intended for the planning level for each airport. Additional project specific investigation in accordance with the FAA Advisory Circulars is recommended to further refine the project scope and budget requirements.


The following recommendations were made based on the 2015 condition survey inspection, condition analysis, and maintenance/rehabilitation analysis results:

- ◎ Runway 5-23 – Sections 6305, 6310, and 6315
 - Mill and Overlay attributed to climate/age and construction quality.
- ◎ Runway 9L-27R – Sections 6205 and 6210
 - Mill and Overlay attributed to structural, climate/age, and construction quality.
- ◎ Runway 9R-27L – Sections 6105 and 6110
 - Mill and Overlay attributed to structural, climate/age, and construction quality.
- ◎ East Apron – Sections 4406 and 4410
 - Mill and Overlay attributed to climate/age and construction quality.
- ◎ West Apron – Sections 4312, 4325, and 4330
 - Reconstruction attributed to structural, climate/age, and construction quality.
- ◎ West Apron – Sections 4315 and 4320
 - Mill and Overlay attributed to climate/age and construction quality.
- ◎ North General Aviation Apron – Sections 4105, 4110, 4120, and 4130
 - Mill and Overlay attributed to climate/age and construction quality.
- ◎ Taxiway S – Sections 505 and 510
 - Mill and Overlay attributed to climate/age and construction quality.
- ◎ Taxiway D – Sections 410 and 412
 - Mill and Overlay attributed to climate/age.
- ◎ Runway 27L Threshold – Sections 3310 and 3315
 - Mill and Overlay attributed to climate/age.
- ◎ Taxiway R – Section 1807
 - Mill and Overlay attributed to climate/age.
- ◎ Taxiway K – Section 1120
 - Mill and Overlay attributed to climate/age.
- ◎ Taxiway M – Sections 1305, 1312, 1315, and 1320
 - Mill and Overlay attributed to climate/age and construction quality.

- ⦿ Taxiway V – Section 1602
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ Center Apron – Section 4515
 - Mill and Overlay attributed to climate/age.
- ⦿ Taxiway C – Sections 315 and 330
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ Taxiway Q – Sections 1705 and 1722
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ Taxiway L – Sections 1204 and 1210
 - Mill and Overlay attributed to climate/age and construction quality.
- ⦿ Taxiway S1 – Sections 520
 - Mill and Overlay attributed to climate/age.
- ⦿ Center Apron – Section 4998
 - PCC Restoration attributed to structural and construction quality.
- ⦿ Southwest Apron – Sections 4710 and 4720
 - Mill and Overlay attributed to climate/age and construction quality.


APPENDIX A

- ◉ AIRFIELD PAVEMENT NETWORK DEFINITION EXHIBIT
- ◉ AIRFIELD PAVEMENT SYSTEM INVENTORY EXHIBIT
- ◉ PAVEMENT GEOMETRY INVENTORY
- ◉ WORK HISTORY REPORT



CONSTRUCTION SINCE LAST INSPECTION
& ANTICIPATED CONSTRUCTION ACTIVITY

| CONSTRUCTION YEAR | LOCATION | WORK TYPE / PAVEMENT SECTION |
|-------------------|-------------------------------|--|
| 2010 | TAXIWAYS G & S | NEW ASPHALT PAVEMENT SECTION |
| 2011 | AP N GA | NEW ASPHALT CONSTRUCTION IN FRONT OF NEW BUILDINGS |
| 2013 | TAXIWAY V AND T-HANGARS APRON | APRON: 2" P-401, 6" P-211, 8" WORK PLATFORM TAXIWAY: 2" P-401, 8" P-211, 8" WORK PLATFORM |
| 2013 | TAXIWAY F | TAXIWAY: 2" P-401, 8" P-211, 8" WORK PLATFORM |
| 2014 | TAXIWAY S1 | TAXIWAY: 3" P-401, 8" P-211, 8" WORK PLATFORM |
| 2014 | TAXIWAY K | WIDENING OF TAXIWAY FROM 40' TO 50' TAXIWAY: 3" P-401, 8" P-211, 8" WORK PLATFORM |
| 2014 | AP E | APRON: 4" P-401, 12" P-211, 8" WORK PLATFORM |
| 2014 | AP E | NEW APRON: 14" P-501, 8" P-211, COMPACTED SUBGRADE |



| | | | | | | | | | | | | | | | | | | |
|------------|----------------------|------------|------------|------------|----------------------|----------------------|------------|----------------------|----------------------|------------|------------|------------|------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| 105 | 120 | 130 | 132 | 305 | 310 | 315 | 320 | 330 | 340 | 350 | 405 | 408 | 410 | 412 | 415 | 416 | 450 | 455 |
| AAC | AAC | AAC | AAC | AAC | AC | AAC | AAC | AC | AAC | AAC | AAC | AAC | AC | AC | AC | AC | AAC | AAC |
| 90° X 50' | 90° X 50' | 90° X 50' | 90° X 50' | 100° X 50' | VAR | 100° X 37.5' | 77° X 50' | 75° X 50' | 90° X VAR | 75° X 50' | 100° X VAR | 100° X VAR | 100° X 40' | 100° X 40' | VAR X 40' | AC | 100° X VAR | 100° X VAR |
| 1 | 8 | 10 | 172 | 2 | 1 | 3 | 3 | 3 | 1 | 3 | 1 | 1 | 5 | 1 | 1 | 1 | 4 | 2 |
| 505 | 510 | 515 | 520 | 525 | 605 | 710 | 720 | 810 | 1105 | 1110 | 1115 | 1116 | 1120 | 1125 | 1130 | 1132 | 1135 | 1140 |
| AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AAC | AAC | AAC | AC | AAC | AAC | AC | AAC | AAC |
| 40° X 100' | 36° X 100' | 35° X 100' | 35° X 100' | 35° X 100' | 100° X 35' | 100° X VAR | 100° X VAR | 200° X 25' | 90° X 50' | 100° X 40' | 100° X 40' | 100° X 40' | VAR | 100° X 40' | 100° X 40' | 400° X 11.5' | 100° X 40' | 500° X 10' |
| 1 | 4 | 3 | 19 | 1 | 5 | 1 | 2 | 3 | 3 | 1 | 1 | 1 | 2 | 1 | 2 | 1 | 5 | 1 |
| 1204 | 1210 | 1305 | 1312 | 1315 | 1320 | 1325 | 1404 | 1405 | 1602 | 1605 | 1610 | 1705 | 1710 | 1720 | 1722 | 1725 | 1732 | 1735 |
| VAR | AC | AC | AC | AC | AC | AC | AC | AC | AC | 90° X 50' | 100° X 25' | 90° X 50' | AC | VAR | AC | VAR | VAR | VAR |
| 1 | 2 | 1 | 7 | 1 | 2 | 1 | 2 | 1 | 1 | 2 | 1 | 3 | 1 | 2 | 1 | 2 | 1 | 4 |
| 1805 | 1807 | 1810 | 1820 | 2005 | 2015 | 2110 | 2205 | 2210 | 3310 | 3315 | 4105 | 4110 | 4115 | 4120 | 4125 | 4130 | 4135 | 4140 |
| AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC |
| 92° X 50' | 100° X 50' | 100° X 48' | 100° X 50' | 92° X 50' | 92° X 50' | 100° X 50' | 100° X 40' | 100° X 50' | 100° X 50' | 200° X 25' | 100° X 50' | 100° X 50' | 100° X 50' | 20 SLABS @ 20' X 20' | 12 SLABS @ 20' X 20' | 71° X 50' | VAR X 62.5' | VAR X 62.5' |
| 2 | 13 | 1 | 3 | 2 | 9 | 2 | 11 | 1 | 1 | 3 | 2 | 8 | 3 | 3 | 3 | 2 | 1 | 4 |
| 4145 | 4205 | 4210 | 4305 | 4310 | 4312 | 4315 | 4320 | 4325 | 4330 | 4404 | 4406 | 4407 | 4410 | 4415 | 4420 | 4425 | 4510 | 4515 |
| AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC | AC |
| 131' X 30' | 20 SLABS @ 20' X 20' | 100° X 50' | 100° X 50' | 100° X 50' | 12 SLABS @ 20' X 20' | 20 SLABS @ 20' X 20' | 100° X 50' | 20 SLABS @ 20' X 20' | 20 SLABS @ 20' X 20' | 120° X 50' | 120° X 50' | 75° X 50' | 100° X 50' | 100° X 50' | 100° X 50' | 20 SLABS @ 20' X 20' | 20 SLABS @ 20' X 20' | 20 SLABS @ 20' X 20' |
| 1 | 2 | 1 | 8 | 1 | 9 | 1 | 1 | 2 | 11 | 2 | 1 | 2 | 1 | 2 | 1 | 2 | 1 | 1 |
| 4520 | 4710 | 4720 | 4730 | 4998 | 6105 | 6110 | 6203 | 6204 | 6205 | 6210 | 6215 | 6220 | 6305 | 6310 | 6315 | | | |
| AC | AC | AC | AC | AC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AAC | AC | AAC | AAC | | | |
| VAR | 100° X 50' | 100° X 50' | 85° X 50' | VAR | 100° X 50' | 200° X 25' | 175° X 25' | 100° X 50' | 200° X 25' | 100° X 50' | 175° X 25' | 100° X 50' | 75° X 50' | 75° X 48' | VAR | | | |
| 1 | 9 | 5 | 42 | 4 | 31 | 3 | 24 | 2 | 8 | 21 | 190 | 20 | 98 | 1 | 2 | | | |

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|-----------|------|------------|
| | | |
| | | |
| DESIGNED: | KHA | DRAWN: KHA |
| CHECKED: | KHA | DATE: |
| | | 2015 |



AIRFIELD PAVEMENT SYSTEM INVENTORY EXHIBIT
MELBOURNE INTERNATIONAL AIRPORT
BREVARD COUNTY, FLORIDA
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE

Table A-1: Pavement Geometry Inventory

| Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT ²) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|-----------------|-----------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| RUNWAY 5-23 | RW 5-23 | RUNWAY | 6315 | 92 | 75 | 6,900 | S | AAC | 1/1/1992 | 4/6/2015 | 2 |
| RUNWAY 5-23 | RW 5-23 | RUNWAY | 6310 | 75 | 45 | 6,900 | S | AAC | 1/1/1992 | 4/6/2015 | 2 |
| RUNWAY 5-23 | RW 5-23 | RUNWAY | 6305 | 2,800 | 75 | 211,297 | S | AC | 1/1/1992 | 4/6/2015 | 56 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6220 | 175 | 100 | 17,500 | S | AAC | 1/1/2011 | 4/6/2015 | 3 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6215 | 350 | 25 | 8,750 | S | AAC | 1/1/2011 | 4/6/2015 | 2 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6210 | 5,651 | 100 | 565,132 | S | AAC | 1/1/1991 | 4/6/2015 | 114 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6205 | 11,302 | 25 | 282,566 | S | AAC | 1/1/1991 | 4/6/2015 | 56 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6204 | 175 | 100 | 17,500 | P | AAC | 1/1/2011 | 4/6/2015 | 3 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6203 | 350 | 25 | 8,750 | P | AAC | 1/1/2011 | 4/6/2015 | 2 |
| RUNWAY 9R-27L | RW 9R-27L | RUNWAY | 6110 | 19,000 | 25 | 475,000 | P | AAC | 1/1/1998 | 4/6/2015 | 96 |
| RUNWAY 9R-27L | RW 9R-27L | RUNWAY | 6105 | 9,300 | 100 | 950,000 | P | AAC | 1/1/1998 | 4/6/2015 | 190 |
| CENTER APRON | AP CENTER | APRON | 4998 | 250 | 200 | 48,745 | P | PCC | 1/1/1995 | 4/6/2015 | 8 |
| APRON SOUTHWEST | AP SW | APRON | 4730 | 1,200 | 85 | 101,878 | P | AC | 1/1/2013 | 1/1/2013 | 24 |
| APRON SOUTHWEST | AP SW | APRON | 4720 | 1,500 | 100 | 146,718 | P | AC | 1/1/2008 | 4/6/2015 | 31 |
| APRON SOUTHWEST | AP SW | APRON | 4710 | 500 | 420 | 216,728 | P | AC | 1/1/2008 | 4/6/2015 | 42 |
| CENTER APRON | AP CENTER | APRON | 4520 | 559 | 100 | 55,946 | P | AC | 1/1/2009 | 4/6/2015 | 9 |
| CENTER APRON | AP CENTER | APRON | 4515 | 290 | 10 | 2,842 | P | APC | 1/1/2009 | 4/6/2015 | 1 |
| CENTER APRON | AP CENTER | APRON | 4510 | 230 | 100 | 23,048 | P | PCC | 1/1/2009 | 4/6/2015 | 3 |
| EAST APRON | AP E | APRON | 4425 | 650 | 550 | 253,400 | P | PCC | 1/1/2014 | 1/1/2014 | 34 |
| EAST APRON | AP E | APRON | 4420 | 800 | 200 | 129,420 | P | AC | 1/1/2014 | 1/1/2014 | 26 |
| EAST APRON | AP E | APRON | 4415 | 380 | 200 | 14,188 | P | APC | 1/1/2014 | 1/1/2014 | 4 |
| EAST APRON | AP E | APRON | 4410 | 700 | 300 | 100,915 | P | AC | 12/25/1999 | 4/6/2015 | 22 |
| EAST APRON | AP E | APRON | 4407 | 600 | 100 | 69,765 | P | AAC | 1/1/2004 | 4/6/2015 | 18 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT ²) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|----------------|-----------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| EAST APRON | AP E | APRON | 4406 | 380 | 200 | 12,949 | P | APC | 1/1/1998 | 4/6/2015 | 2 |
| EAST APRON | AP E | APRON | 4404 | 380 | 200 | 76,125 | P | APC | 1/1/2004 | 4/6/2015 | 12 |
| WEST APRON | AP W | APRON | 4330 | 280 | 300 | 52,136 | P | PCC | 1/1/1942 | 4/6/2015 | 8 |
| WEST APRON | AP W | APRON | 4325 | 251 | 200 | 45,350 | P | PCC | 1/1/1942 | 4/6/2015 | 7 |
| WEST APRON | AP W | APRON | 4320 | 400 | 150 | 75,950 | P | AC | 1/1/1979 | 4/6/2015 | 15 |
| WEST APRON | AP W | APRON | 4315 | 325 | 200 | 57,374 | P | AAC | 1/1/2012 | 4/6/2015 | 11 |
| WEST APRON | AP W | APRON | 4312 | 260 | 32 | 8,547 | P | PCC | 12/25/1994 | 4/6/2015 | 1 |
| WEST APRON | AP W | APRON | 4310 | 235 | 200 | 47,311 | P | AAC | 1/1/2012 | 4/6/2015 | 9 |
| WEST APRON | AP W | APRON | 4305 | 170 | 200 | 34,199 | P | AAC | 1/1/2012 | 4/6/2015 | 6 |
| TERMINAL APRON | AP TERM | APRON | 4210 | 1,700 | 200 | 344,919 | P | AAC | 1/1/2009 | 4/6/2015 | 74 |
| TERMINAL APRON | AP TERM | APRON | 4205 | 580 | 500 | 290,074 | P | PCC | 1/1/1989 | 4/6/2015 | 37 |
| NORTH GA APRON | AP N GA | APRON | 4145 | 150 | 50 | 7,860 | P | AAC | 1/1/2013 | 1/1/2013 | 2 |
| NORTH GA APRON | AP N GA | APRON | 4140 | 185 | 125 | 23,711 | P | AC | 1/1/2010 | 4/6/2015 | 4 |
| NORTH GA APRON | AP N GA | APRON | 4135 | 350 | 100 | 22,180 | P | APC | 1/1/2010 | 4/6/2015 | 6 |
| NORTH GA APRON | AP N GA | APRON | 4130 | 650 | 170 | 97,785 | P | AC | 1/1/2006 | 4/6/2015 | 15 |
| NORTH GA APRON | AP N GA | APRON | 4125 | 642 | 160 | 51,200 | P | PCC | 1/1/2003 | 4/6/2015 | 10 |
| NORTH GA APRON | AP N GA | APRON | 4120 | 950 | 100 | 96,139 | P | AC | 1/1/2003 | 4/6/2015 | 22 |
| NORTH GA APRON | AP N GA | APRON | 4115 | 760 | 214 | 162,260 | P | PCC | 1/1/2003 | 4/6/2015 | 20 |
| NORTH GA APRON | AP N GA | APRON | 4110 | 480 | 250 | 127,070 | P | AC | 1/1/1982 | 4/6/2015 | 26 |

| Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT ²) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|-------------------------------------|------------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| NORTH GA APRON | AP N GA | APRON | 4105 | 479 | 200 | 95,800 | P | AC | 1/1/1986 | 4/6/2015 | 18 |
| THRESHOLD TO RW 27L | RW 27L THR | RUNWAY | 3315 | 1,361 | 25 | 34,034 | P | AAC | 1/1/2001 | 4/6/2015 | 8 |
| THRESHOLD TO RW 27L | RW 27L THR | RUNWAY | 3310 | 430 | 100 | 68,068 | P | AAC | 1/1/2001 | 4/6/2015 | 14 |
| TAXIWAY V | TW V | TAXIWAY | 2210 | 270 | 50 | 13,665 | P | AAC | 1/1/2012 | 4/6/2015 | 3 |
| TAXIWAY V | TW V | TAXIWAY | 2205 | 380 | 40 | 14,782 | P | AAC | 1/1/2012 | 4/6/2015 | 4 |
| CONNECTOR TAXIWAY TO TERMINAL APRON | TW CONN AP | TAXIWAY | 2110 | 100 | 80 | 8,354 | P | AC | 1/1/1989 | 4/6/2015 | 2 |
| TAXIWAY T | TW T | TAXIWAY | 2015 | 540 | 100 | 54,727 | P | AC | 1/1/2001 | 4/6/2015 | 11 |
| TAXIWAY T | TW T | TAXIWAY | 2005 | 600 | 75 | 47,619 | P | AAC | 1/1/1986 | 4/6/2015 | 9 |
| TAXIWAY R | TW R | TAXIWAY | 1820 | 400 | 50 | 49,954 | P | AAC | 1/1/2009 | 4/6/2015 | 10 |
| TAXIWAY R | TW R | TAXIWAY | 1810 | 1,500 | 40 | 61,999 | P | AAC | 1/1/2009 | 4/6/2015 | 13 |
| TAXIWAY R | TW R | TAXIWAY | 1807 | 350 | 40 | 14,115 | P | AAC | 1/1/1998 | 4/6/2015 | 3 |
| TAXIWAY R | TW R | TAXIWAY | 1805 | 1,200 | 50 | 61,344 | P | AAC | 1/1/2009 | 4/6/2015 | 13 |
| TAXIWAY Q | TW Q | TAXIWAY | 1735 | 350 | 40 | 15,616 | P | AAC | 1/1/2006 | 4/6/2015 | 4 |
| TAXIWAY Q | TW Q | TAXIWAY | 1732 | 100 | 40 | 4,295 | P | AAC | 1/1/2006 | 4/6/2015 | 1 |
| TAXIWAY Q | TW Q | TAXIWAY | 1725 | 1,400 | 75 | 106,628 | P | AAC | 1/1/2004 | 4/6/2015 | 28 |
| TAXIWAY Q | TW Q | TAXIWAY | 1722 | 120 | 60 | 7,921 | P | AAC | 1/1/2004 | 4/6/2015 | 2 |
| TAXIWAY Q | TW Q | TAXIWAY | 1720 | 540 | 100 | 54,194 | P | AAC | 1/1/2009 | 4/6/2015 | 10 |
| TAXIWAY Q | TW Q | TAXIWAY | 1710 | 120 | 100 | 12,104 | P | AAC | 1/1/2007 | 4/6/2015 | 2 |
| TAXIWAY Q | TW Q | TAXIWAY | 1705 | 1,000 | 90 | 91,926 | P | AAC | 1/1/2007 | 4/6/2015 | 19 |
| TAXIWAY V | TW V | TAXIWAY | 1610 | 1,300 | 25 | 36,715 | P | AC | 1/1/2013 | 1/1/2013 | 9 |
| TAXIWAY V | TW V | TAXIWAY | 1605 | 611 | 100 | 61,171 | P | AAC | 1/1/2009 | 4/6/2015 | 12 |
| TAXIWAY V | TW V | TAXIWAY | 1602 | 115 | 90 | 10,398 | P | AAC | 1/1/1998 | 4/6/2015 | 3 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT ²) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|-------------|-----------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| TAXIWAY N | TW N | TAXIWAY | 1405 | 380 | 90 | 34,529 | P | AAC | 1/1/2009 | 4/6/2015 | 8 |
| TAXIWAY N | TW N | TAXIWAY | 1404 | 110 | 90 | 10,300 | P | AAC | 1/1/1998 | 4/6/2015 | 2 |
| TAXIWAY M | TW M | TAXIWAY | 1325 | 220 | 25 | 5,526 | P | AAC | 1/1/2003 | 4/6/2015 | 2 |
| TAXIWAY M | TW M | TAXIWAY | 1320 | 220 | 25 | 5,526 | P | AAC | 1/1/2003 | 4/6/2015 | 2 |
| TAXIWAY M | TW M | TAXIWAY | 1315 | 660 | 75 | 50,873 | P | AC | 1/1/2003 | 4/6/2015 | 13 |
| TAXIWAY M | TW M | TAXIWAY | 1312 | 800 | 20 | 16,404 | P | AC | 1/1/2003 | 4/6/2015 | 4 |
| TAXIWAY M | TW M | TAXIWAY | 1305 | 200 | 40 | 8,625 | P | AAC | 1/1/2003 | 4/6/2015 | 2 |
| TAXIWAY L | TW L | TAXIWAY | 1210 | 380 | 90 | 34,316 | P | AAC | 1/1/2009 | 4/6/2015 | 7 |
| TAXIWAY L | TW L | TAXIWAY | 1204 | 115 | 90 | 10,453 | P | AAC | 1/1/1998 | 4/6/2015 | 2 |
| TAXIWAY K | TW K | TAXIWAY | 1140 | 2,300 | 10 | 23,583 | P | AC | 1/1/2014 | 1/1/2014 | 5 |
| TAXIWAY K | TW K | TAXIWAY | 1135 | 1,900 | 40 | 82,706 | P | AAC | 1/1/2006 | 4/6/2015 | 20 |
| TAXIWAY K | TW K | TAXIWAY | 1132 | 1,700 | 12 | 21,084 | P | AC | 1/1/2011 | 4/6/2015 | 4 |
| TAXIWAY K | TW K | TAXIWAY | 1130 | 1,900 | 40 | 76,184 | P | AAC | 1/1/2006 | 4/6/2015 | 19 |
| TAXIWAY K | TW K | TAXIWAY | 1125 | 2,350 | 40 | 94,533 | P | AAC | 1/1/2006 | 4/6/2015 | 23 |
| TAXIWAY K | TW K | TAXIWAY | 1120 | 240 | 40 | 9,926 | P | AAC | 1/1/2006 | 4/6/2015 | 2 |
| TAXIWAY K | TW K | TAXIWAY | 1116 | 170 | 40 | 6,760 | P | AAC | 1/1/2006 | 4/6/2015 | 2 |
| TAXIWAY K | TW K | TAXIWAY | 1115 | 3,600 | 40 | 145,056 | P | AAC | 1/1/2006 | 4/6/2015 | 35 |
| TAXIWAY K | TW K | TAXIWAY | 1110 | 120 | 40 | 5,207 | P | AAC | 1/1/2006 | 4/6/2015 | 1 |
| TAXIWAY B | TW B | TAXIWAY | 1105 | 1,000 | 100 | 101,687 | P | AAC | 1/1/2006 | 4/6/2015 | 18 |
| TAXIWAY F | TW F | TAXIWAY | 810 | 2,225 | 25 | 64,381 | P | AC | 1/1/2013 | 1/1/2013 | 14 |
| TAXIWAY V2 | TW V2 | TAXIWAY | 720 | 250 | 30 | 8,446 | P | AC | 1/1/2013 | 1/1/2013 | 2 |
| TAXIWAY V1 | TW V1 | APRON | 710 | 225 | 40 | 11,452 | P | AC | 1/1/2008 | 4/6/2015 | 2 |
| TAXIWAY G | TW G | TAXIWAY | 605 | 700 | 50 | 40,977 | P | AC | 1/1/2010 | 4/6/2015 | 8 |
| TAXIWAY S1 | TW S1 | TAXIWAY | 525 | 525 | 35 | 19,360 | P | AC | 1/1/2014 | 1/1/2014 | 5 |
| TAXIWAY S1 | TW S1 | TAXIWAY | 520 | 375 | 38 | 14,644 | P | AC | 1/1/2009 | 4/6/2015 | 4 |
| TAXIWAY S | TW S | TAXIWAY | 515 | 520 | 40 | 18,556 | P | AC | 1/1/2010 | 4/6/2015 | 5 |

| Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT ²) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|-------------|-----------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| TAXIWAY S | TW S | TAXIWAY | 510 | 1,900 | 36 | 68,429 | P | AAC | 1/1/2006 | 4/6/2015 | 19 |
| TAXIWAY S | TW S | TAXIWAY | 505 | 485 | 40 | 18,700 | P | AAC | 1/1/2004 | 4/6/2015 | 4 |
| TAXIWAY D | TW D | TAXIWAY | 455 | 270 | 70 | 32,702 | P | AAC | 1/1/2012 | 4/6/2015 | 5 |
| TAXIWAY D | TW D | TAXIWAY | 450 | 370 | 60 | 23,692 | P | AAC | 1/1/2012 | 4/6/2015 | 4 |
| TAXIWAY D | TW D | TAXIWAY | 416 | 210 | 40 | 8,423 | P | AC | 1/1/2001 | 4/6/2015 | 2 |
| TAXIWAY D | TW D | TAXIWAY | 415 | 450 | 40 | 19,192 | P | AC | 1/1/2001 | 4/6/2015 | 5 |
| TAXIWAY D | TW D | TAXIWAY | 412 | 110 | 40 | 4,498 | P | AC | 1/1/1979 | 4/6/2015 | 1 |
| TAXIWAY D | TW D | TAXIWAY | 410 | 2,600 | 40 | 104,051 | P | AC | 1/1/1979 | 4/6/2015 | 25 |
| TAXIWAY D | TW D | TAXIWAY | 408 | 190 | 40 | 7,930 | P | AAC | 1/1/2008 | 4/6/2015 | 2 |
| TAXIWAY D | TW D | TAXIWAY | 405 | 95 | 40 | 8,073 | P | AAC | 1/1/2012 | 4/6/2015 | 2 |
| TAXIWAY C | TW C | TAXIWAY | 350 | 1,075 | 75 | 71,723 | P | AC | 1/1/2003 | 4/6/2015 | 19 |
| TAXIWAY C | TW C | TAXIWAY | 340 | 500 | 40 | 20,582 | P | AAC | 1/1/2003 | 4/6/2015 | 5 |
| TAXIWAY C | TW C | TAXIWAY | 330 | 1,200 | 35 | 108,166 | P | AC | 1/1/1991 | 4/6/2015 | 27 |
| TAXIWAY C | TW C | TAXIWAY | 320 | 450 | 80 | 41,105 | P | AAC | 1/1/2009 | 4/6/2015 | 9 |
| TAXIWAY C | TW C | TAXIWAY | 315 | 1,550 | 40 | 63,222 | P | AAC | 1/1/2004 | 4/6/2015 | 17 |
| TAXIWAY C | TW C | TAXIWAY | 310 | 250 | 50 | 13,011 | P | AAC | 1/1/2004 | 4/6/2015 | 3 |
| TAXIWAY C | TW C | TAXIWAY | 305 | 800 | 50 | 43,008 | P | AAC | 1/1/2007 | 4/6/2015 | 8 |
| TAXIWAY A | TW A | TAXIWAY | 132 | 600 | 90 | 58,319 | P | AAC | 1/1/2009 | 4/6/2015 | 13 |
| TAXIWAY A | TW A | TAXIWAY | 130 | 400 | 90 | 36,222 | P | AAC | 1/1/2009 | 4/6/2015 | 8 |
| TAXIWAY A | TW A | TAXIWAY | 120 | 9,000 | 75 | 691,660 | P | AAC | 1/1/2009 | 4/6/2015 | 172 |
| TAXIWAY A | TW A | TAXIWAY | 105 | 400 | 90 | 38,493 | P | AAC | 1/1/2009 | 4/6/2015 | 8 |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.

Date:05/27/2015

Work History Report

1 of 15

Pavement Database:FDOT

Network: MLB **Branch:** AP CENTER (CENTER APRON) **Section:** 4510 **Surface:** PCC
L.C.D.: 01/01/2009 **Use:** APRON **Rank P Length:** 230.00 Ft **Width:** 100.00 Ft **True Area:** 23,048.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2009 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB **Branch:** AP CENTER (CENTER APRON) **Section:** 4515 **Surface:** APC
L.C.D.: 01/01/2009 **Use:** APRON **Rank P Length:** 290.00 Ft **Width:** 10.00 Ft **True Area:** 2,842.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|---------------------------|
| 01/01/2009 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 6" CONCRETE ESTIMATE 1942 |
| 01/01/1942 | INITIAL | Initial Construction | \$0 | 6.00 | True | |
| 01/01/1942 | NC-PC | New Construction - PCC | \$0 | 0.00 | True | |

Network: MLB **Branch:** AP CENTER (CENTER APRON) **Section:** 4520 **Surface:** AC
L.C.D.: 01/01/2009 **Use:** APRON **Rank P Length:** 559.00 Ft **Width:** 100.00 Ft **True Area:** 55,946.19 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2009 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB **Branch:** AP CENTER (CENTER APRON) **Section:** 4998 **Surface:** PCC
L.C.D.: 01/01/1995 **Use:** APRON **Rank P Length:** 250.00 Ft **Width:** 200.00 Ft **True Area:** 48,745.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|------------------------------|
| 01/01/1995 | IMPORTED | BUILT | | 14.00 | True | 1995 14" P501 ON 9" LIMEROCK |

Network: MLB **Branch:** AP E (EAST APRON) **Section:** 4404 **Surface:** APC
L.C.D.: 01/01/2004 **Use:** APRON **Rank P Length:** 380.00 Ft **Width:** 200.00 Ft **True Area:** 76,125.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-----------------------------|------|----------------|-----------|---------------|
| 01/01/2004 | SR-AC | Surface Reconstruction - AC | \$0 | 0.00 | True | 4"AC/12"P-211 |
| 01/01/1996 | IMPORTED | OVERLAY | | 1.00 | True | 1996 1" P401 |
| 01/01/1947 | IMPORTED | BUILT | | 6.00 | True | 1947 6" P501 |

Network: MLB **Branch:** AP E (EAST APRON) **Section:** 4406 **Surface:** APC
L.C.D.: 01/01/1998 **Use:** APRON **Rank P Length:** 380.00 Ft **Width:** 200.00 Ft **True Area:** 12,949.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--------------|
| 01/01/1998 | IMPORTED | OVERLAY | | 1.00 | True | 1998 1" P401 |
| 01/01/1942 | IMPORTED | BUILT | | 6.00 | True | 1942 6" P501 |

Network: MLB **Branch:** AP E (EAST APRON) **Section:** 4407 **Surface:** AAC
L.C.D.: 01/01/2004 **Use:** APRON **Rank P Length:** 600.00 Ft **Width:** 100.00 Ft **True Area:** 69,764.58 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-----------------------------|------|----------------|-----------|----------------------|
| 01/01/2004 | SR-AC | Surface Reconstruction - AC | \$0 | 4.00 | True | 2004 4" AC/12" P-211 |
| 01/01/1996 | OL-AS | Overlay - AC Structural | \$0 | 1.00 | True | 1996 1" P401 |
| 01/01/1947 | INITIAL | Initial Construction | \$0 | 6.00 | True | 1947 6" P501 |

Network: MLB **Branch:** AP E (EAST APRON) **Section:** 4410 **Surface:** AC
L.C.D.: 12/25/1999 **Use:** APRON **Rank P Length:** 700.00 Ft **Width:** 300.00 Ft **True Area:**100,915.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Date:05/27/2015

Work History Report

2 of 15

Pavement Database:FDOT

Network: MLB Branch: AP E (EAST APRON) Section: 4415 Surface: APC
 L.C.D.: 01/01/2014 Use: APRON Rank P Length: 380.00 Ft Width: 200.00 Ft True Area: 14,188.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/2014 | ML-OV | MILL and OVERLAY | \$0 | 0.00 | True | 2014: TRANSITIONAL ML&OL 2" P-401, ON VAR. THICKNESS LIMEROCK 1998 1" P401 1942 6" P501 |
| 01/01/1998 | IMPORTED | OVERLAY | \$0 | 1.00 | True | |
| 01/01/1942 | IMPORTED | BUILT | \$0 | 6.00 | True | |

Network: MLB Branch: AP E (EAST APRON) Section: 4420 Surface: AC
 L.C.D.: 01/01/2014 Use: APRON Rank P Length: 800.00 Ft Width: 200.00 Ft True Area:129.420.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|---|
| 01/01/2014 | NU-IN | New Construction - Initial | \$0 | 4.00 | True | 2014: 4" P-401, 12" P-211, 8" WORK PLATFORM |

Network: MLB Branch: AP E (EAST APRON) Section: 4425 Surface: PCC
 L.C.D.: 01/01/2014 Use: APRON Rank P Length: 650.00 Ft Width: 550.00 Ft True Area:253.400.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|---|
| 01/01/2014 | NU-IN | New Construction - Initial | \$0 | 14.00 | True | 2014: 14" P-501, 8" P-211, COMPACTED SUBGRADE |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4105 Surface: AC
 L.C.D.: 01/01/1986 Use: APRON Rank P Length: 479.00 Ft Width: 200.00 Ft True Area: 95,800.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/1986 | IMPORTED | BUILT | | 1.00 | True | 1986: 1" P-401 ON 8" P-211 |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4110 Surface: AC
 L.C.D.: 01/01/1982 Use: APRON Rank P Length: 480.00 Ft Width: 250.00 Ft True Area:127.070.36 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/1982 | IMPORTED | BUILT | | 1.00 | True | 1982: 1" P-401 ON 8" P-211 |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4115 Surface: PCC
 L.C.D.: 01/01/2003 Use: APRON Rank P Length: 760.00 Ft Width: 213.50 Ft True Area:162.260.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|------------------|
| 01/01/2003 | INITIAL | Initial Construction | \$0 | 0.00 | True | 14" PCC/EXISTING |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4120 Surface: AC
 L.C.D.: 01/01/2003 Use: APRON Rank P Length: 950.00 Ft Width: 100.00 Ft True Area: 96.139.17 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|-----------------|
| 01/01/2003 | INITIAL | Initial Construction | \$0 | 0.00 | True | 4" AC/16" P-211 |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4125 Surface: PCC
 L.C.D.: 01/01/2003 Use: APRON Rank P Length: 642.00 Ft Width: 160.00 Ft True Area: 51.200.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|--------------------------|
| 01/01/2003 | INITIAL | Initial Construction | \$0 | 0.00 | True | 14"PCC/EXISTING PAVEMENT |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4130 Surface: AC
 L.C.D.: 01/01/2006 Use: APRON Rank P Length: 650.00 Ft Width: 170.00 Ft True Area: 97,785.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|------------------|------|----------------|-----------|----------|
| | | | | | | |

Date:05/27/2015

Work History Report

3 of 15

Pavement Database:FDOT

| | | | | | | |
|------------|---------|-----------------------|-----|------|------|-----------------|
| 01/01/2006 | NC-AC | New Construction - AC | \$0 | 0.00 | True | |
| 01/01/2003 | INITIAL | Initial Construction | \$0 | 0.00 | True | 4" AC/16" P-211 |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4135 Surface: APC
 L.C.D.: 01/01/2010 Use: APRON Rank P Length: 350.00 Ft Width: 100.00 Ft True Area: 22.180.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|----------|
| 01/01/2010 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | |
| 12/25/2004 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4140 Surface: AC
 L.C.D.: 01/01/2010 Use: APRON Rank P Length: 185.00 Ft Width: 125.00 Ft True Area: 23.711.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|----------|
| 01/01/2010 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |

Network: MLB Branch: AP N GA (NORTH GA APRON) Section: 4145 Surface: AAC
 L.C.D.: 01/01/2013 Use: APRON Rank P Length: 150.00 Ft Width: 50.00 Ft True Area: 7,860.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|----------|
| 01/01/2013 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |

Network: MLB Branch: AP SW (APRON SOUTHWEST) Section: 4710 Surface: AC
 L.C.D.: 01/01/2008 Use: APRON Rank P Length: 500.00 Ft Width: 420.00 Ft True Area:216.727.84 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2008 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: AP SW (APRON SOUTHWEST) Section: 4720 Surface: AC
 L.C.D.: 01/01/2008 Use: APRON Rank P Length: 1,500.00 Ft Width: 100.00 Ft True Area:146.718.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2008 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: AP SW (APRON SOUTHWEST) Section: 4730 Surface: AC
 L.C.D.: 01/01/2013 Use: APRON Rank P Length: 1,200.00 Ft Width: 85.00 Ft True Area:101,878.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|--|
| 01/01/2013 | NU-IN | New Construction - Initial | \$0 | 2.00 | True | 2013: 2" P-401, 6" P-211, 8" WORK PLATFORM |

Network: MLB Branch: AP TERM (TERMINAL APRON) Section: 4205 Surface: PCC
 L.C.D.: 01/01/1989 Use: APRON Rank P Length: 580.00 Ft Width: 500.00 Ft True Area:290.074.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|-----------------|
| 01/01/1989 | IMPORTED | BUILT | | 14.00 | True | 1989: 14" P-501 |

Network: MLB Branch: AP TERM (TERMINAL APRON) Section: 4210 Surface: AAC
 L.C.D.: 01/01/2009 Use: APRON Rank P Length: 1,700.00 Ft Width: 200.00 Ft True Area:344,919.36 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|-----------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1989 | IMPORTED | BUILT | | 4.00 | True | 1989: 4" P-401 ON 12" P-211 |

Date:05/27/2015

Work History Report

4 of 15

Pavement Database:FDOT

Network: MLB Branch: AP W (WEST APRON) Section: 4305 Surface: AAC
 L.C.D.: 01/01/2012 Use: APRON Rank P Length: 170.00 Ft Width: 200.00 Ft True Area: 34,199.31 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--|
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | THIS PAVEMENT HAS AN EMULSION SEAL 1979: 1" P-401 ON 6" P-211 |
| 01/01/1979 | IMPORTED | OVERLAY | | | True | |
| 01/01/1979 | IMPORTED | BUILT | | 1.00 | True | |

Network: MLB Branch: AP W (WEST APRON) Section: 4310 Surface: AAC
 L.C.D.: 01/01/2012 Use: APRON Rank P Length: 235.00 Ft Width: 200.00 Ft True Area: 47,311.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------|
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | ESTIMATE 1965 AC PAVEMENT |
| 01/01/1965 | IMPORTED | BUILT | | | True | |

Network: MLB Branch: AP W (WEST APRON) Section: 4312 Surface: PCC
 L.C.D.: 12/25/1994 Use: APRON Rank P Length: 260.00 Ft Width: 32.00 Ft True Area: 8,547.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|----------|
| 12/25/1994 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |

Network: MLB Branch: AP W (WEST APRON) Section: 4315 Surface: AAC
 L.C.D.: 01/01/2012 Use: APRON Rank P Length: 325.00 Ft Width: 200.00 Ft True Area: 57,374.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--|
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | ESTIMATE 1965 AC PAVEMENT THIS FEATURE HAS AN EMULSION SEAL |
| 01/01/1965 | IMPORTED | BUILT | | | True | |
| 01/01/1965 | IMPORTED | OVERLAY | | | True | |

Network: MLB Branch: AP W (WEST APRON) Section: 4320 Surface: AC
 L.C.D.: 01/01/1979 Use: APRON Rank P Length: 400.00 Ft Width: 150.00 Ft True Area: 75,950.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/1979 | IMPORTED | BUILT | | 1.00 | True | 1979: 1" P-401 ON 6" P-211 |

Network: MLB Branch: AP W (WEST APRON) Section: 4325 Surface: PCC
 L.C.D.: 01/01/1942 Use: APRON Rank P Length: 250.75 Ft Width: 200.00 Ft True Area: 45,350.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--|
| 01/01/1942 | IMPORTED | BUILT | | 6.00 | True | 6" CONCRETE - ESTIMATE 1942 CONSTRUCTION |

Network: MLB Branch: AP W (WEST APRON) Section: 4330 Surface: PCC
 L.C.D.: 01/01/1942 Use: APRON Rank P Length: 280.00 Ft Width: 300.00 Ft True Area: 52,136.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/1942 | IMPORTED | BUILT | | 6.00 | True | 6" CONCRETE PAVEMENT - ESTIMATE 1942 CONSTRUCTION |

Network: MLB Branch: RW 27L THR (THRESHOLD TO RW 27L) Section: 3310 Surface: AAC
 L.C.D.: 01/01/2001 Use: RUNWAY Rank P Length: 430.00 Ft Width: 100.00 Ft True Area: 68,068.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|-----------|
| 01/01/2001 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC |
| 01/01/1975 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Date:05/27/2015

Work History Report

5 of 15

Pavement Database:FDOT

Network: MLB Branch: RW 27L THR (THRESHOLD TO RW 27L) Section: 3315 Surface: AAC
 L.C.D.: 01/01/2001 Use: RUNWAY Rank P Length: 1,361.00 Ft Width: 25.00 Ft True Area: 34,034.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|-----------|
| 01/01/2001 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC |
| 01/01/1975 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: RW 5-23 (RUNWAY 5-23) Section: 6305 Surface: AC
 L.C.D.: 01/01/1992 Use: RUNWAY Rank S Length: 2,800.00 Ft Width: 75.00 Ft True Area:211,296.70 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/1992 | IMPORTED | BUILT | | 2.00 | True | 1992: 2" P-401 ON 6" P-211 |

Network: MLB Branch: RW 5-23 (RUNWAY 5-23) Section: 6310 Surface: AAC
 L.C.D.: 01/01/1992 Use: RUNWAY Rank S Length: 75.00 Ft Width: 45.00 Ft True Area: 6,900.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|-------------------------------------|
| 01/01/1992 | IMPORTED | OVERLAY | | 0.00 | True | 1992: 0" - 11" P-401 OVERLAY |
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN - 3" AVG P-401 OVERLAY |
| 01/01/1978 | IMPORTED | BUILT | | 3.00 | True | 1978: 3" P-401 ON 12" P-211 |

Network: MLB Branch: RW 5-23 (RUNWAY 5-23) Section: 6315 Surface: AAC
 L.C.D.: 01/01/1992 Use: RUNWAY Rank S Length: 92.00 Ft Width: 75.00 Ft True Area: 6,900.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|-----------------------------|
| 01/01/1992 | IMPORTED | OVERLAY | | 0.00 | True | 1992: 0" - 6" P-401 OVERLAY |
| 01/01/1989 | IMPORTED | BUILT | | 3.00 | True | 1989: 3" P-401 ON 12" P-211 |

Network: MLB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6203 Surface: AAC
 L.C.D.: 01/01/2011 Use: RUNWAY Rank P Length: 350.00 Ft Width: 25.00 Ft True Area: 8,750.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2011 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6204 Surface: AAC
 L.C.D.: 01/01/2011 Use: RUNWAY Rank P Length: 175.00 Ft Width: 100.00 Ft True Area: 17,500.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2011 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6205 Surface: AAC
 L.C.D.: 01/01/1991 Use: RUNWAY Rank S Length: 11,302.00 Ft Width: 25.00 Ft True Area:282,565.80 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN. - 3" AVG. P-401 OVERLAY |
| 01/01/1981 | IMPORTED | BUILT | | 1.00 | True | 1981: 1" P-401 ON 8" P-211 |

Network: MLB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6210 Surface: AAC
 L.C.D.: 01/01/1991 Use: RUNWAY Rank S Length: 5,651.00 Ft Width: 100.00 Ft True Area:565,131.61 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN. - 3" AVG. P-401 OVERLAY |
| 01/01/1981 | IMPORTED | BUILT | | 1.00 | True | 1981: 1" P-401 ON 8" P-211 |

Date:05/27/2015

Work History Report

6 of 15

Pavement Database:FDOT

Network: MLB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6215 Surface: AAC
 L.C.D.: 01/01/2011 Use: RUNWAY Rank S Length: 350.00 Ft Width: 25.00 Ft True Area: 8,750.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/2011 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN. - 3" AVG. P-401 OVERLAY |
| 01/01/1985 | IMPORTED | BUILT | | 1.00 | True | 1985: 1" P-401 ON 8" P-211 |

Network: MLB Branch: RW 9L-27R (RUNWAY 9L-27R) Section: 6220 Surface: AAC
 L.C.D.: 01/01/2011 Use: RUNWAY Rank S Length: 175.00 Ft Width: 100.00 Ft True Area: 17,500.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/2011 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | IMPORTED | BUILT | | 3.00 | True | 1991: 3" P-401 ON 8" P-211 |

Network: MLB Branch: RW 9R-27L (RUNWAY 9R-27L) Section: 6105 Surface: AAC
 L.C.D.: 01/01/1998 Use: RUNWAY Rank P Length: 9,300.00 Ft Width: 100.00 Ft True Area:950,000.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|---|
| 01/01/1998 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC |
| 01/01/1998 | IMPORTED | OVERLAY | | 1.50 | True | ON 1.5" AC ON 9" SOIL CEMENT BASE COURSE |
| 01/01/1998 | IMPORTED | OVERLAY | | 2.00 | True | EXISTING 2" AC ON 4" BITUMONOUS BASE COURSE |
| 01/01/1998 | IMPORTED | OVERLAY | | 2.00 | True | 1998 2" P401 OVERLAY |
| 01/01/1983 | IMPORTED | BUILT | | 2.25 | True | 1983 2.25" P401 OVERLAY |

Network: MLB Branch: RW 9R-27L (RUNWAY 9R-27L) Section: 6110 Surface: AAC
 L.C.D.: 01/01/1998 Use: RUNWAY Rank P Length: 19,000.00 Ft Width: 25.00 Ft True Area:475,000.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|----------------------------|
| 01/01/1998 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC |
| 01/01/1998 | IMPORTED | OVERLAY | | 1.50 | True | ON 1.5" P401 ON 9" P301 |
| 01/01/1998 | IMPORTED | OVERLAY | | 2.00 | True | EXISTING 2"P401 ON 4" P201 |
| 01/01/1998 | IMPORTED | OVERLAY | | 2.00 | True | 1998 2" P401 OVERLAY ON |
| 01/01/1983 | IMPORTED | BUILT | | 2.25 | True | 1983 2.25" P401 OVERLAY ON |

Network: MLB Branch: TW A (TAXIWAY A) Section: 105 Surface: AAC
 L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 400.00 Ft Width: 90.00 Ft True Area: 38,492.70 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | IMPORTED | OVERLAY | | 5.00 | True | EXISTING: 5" P401 ON 9" SOIL-CEMENT BASE |
| 01/01/1991 | IMPORTED | BUILT | | 3.00 | True | 1991: 3" P401 OVERLAY |

Network: MLB Branch: TW A (TAXIWAY A) Section: 120 Surface: AAC
 L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 9,000.00 Ft Width: 75.00 Ft True Area:691,659.95 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN. - 3" AVG. P-401 OVERLAY |
| 01/01/1978 | IMPORTED | BUILT | | 3.00 | True | 1978: 3" P-401 ON 12" P-211 |

Network: MLB Branch: TW A (TAXIWAY A) Section: 130 Surface: AAC
 L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 400.00 Ft Width: 90.00 Ft True Area: 36,221.74 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|------------------|------|----------------|-----------|----------|
|-----------|-----------|------------------|------|----------------|-----------|----------|

Date:05/27/2015

Work History Report

7 of 15

Pavement Database:FDOT

| | | | | | | |
|------------|----------|------------------|-----|------|------|-----------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | 1989: 3" P-401 ON 12" P-211 |
| 01/01/1989 | IMPORTED | BUILT | | 3.00 | True | |

Network: MLB Branch: TW A (TAXIWAY A) Section: 132 Surface: AAC
 L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 600.00 Ft Width: 90.00 Ft True Area: 58.318.55 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | THIS PAVEMENT HAS AN EMULSION SEAL ESTIMATE 1991 CONSTR. AND ASSUME: 3" P-401 ON 12" P-211 |
| 01/01/1991 | IMPORTED | OVERLAY | | | True | |
| 01/01/1991 | IMPORTED | BUILT | | 3.00 | True | |

Network: MLB Branch: TW B (TAXIWAY B) Section: 1105 Surface: AAC
 L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 1,000.00 Ft Width: 100.00 Ft True Area: 101,687.15 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------------------------|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | 1991: 3" P-401 ON 8" P-211 |
| 01/01/1991 | INITIAL | Initial Construction | \$0 | 3.00 | True | |

Network: MLB Branch: TW C (TAXIWAY C) Section: 305 Surface: AAC
 L.C.D.: 01/01/2007 Use: TAXIWAY Rank P Length: 800.00 Ft Width: 50.00 Ft True Area: 43,008.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|---|
| 01/01/2007 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | 1.5-2.5" AC ON EXISTING BASE COURSE 1987: 1.5" P-401 AND 8" MIN. - 10" AVG. P-211 PLACED |
| 01/01/2004 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | |
| 01/01/1987 | IMPORTED | OVERLAY | | | True | |
| 01/01/1987 | IMPORTED | BUILT | | 1.50 | True | |

Network: MLB Branch: TW C (TAXIWAY C) Section: 310 Surface: AAC
 L.C.D.: 01/01/2004 Use: TAXIWAY Rank P Length: 250.00 Ft Width: 50.00 Ft True Area: 13,011.46 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|---|
| 01/01/2004 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2.5" AC 1992: 2" P-401 ON 6" P-211 |
| 01/01/1992 | IMPORTED | BUILT | | 2.00 | True | |

Network: MLB Branch: TW C (TAXIWAY C) Section: 315 Surface: AAC
 L.C.D.: 01/01/2004 Use: TAXIWAY Rank P Length: 1,550.00 Ft Width: 40.00 Ft True Area: 63,222.44 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|--|
| 01/01/2004 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2.5" AC 1987: 1.5" P-401 ON 8" MIN. - 10" AVG. P-211 PLACED ON EXISTING BASE COURSE |
| 01/01/1987 | IMPORTED | BUILT | | 1.50 | True | |
| 01/01/1987 | IMPORTED | OVERLAY | | | True | |

Network: MLB Branch: TW C (TAXIWAY C) Section: 320 Surface: AAC
 L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 450.00 Ft Width: 80.00 Ft True Area: 41,105.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | 1991: 3" P-401 ON 8" P-211 |
| 01/01/1991 | IMPORTED | BUILT | | 3.00 | True | |

Network: MLB Branch: TW C (TAXIWAY C) Section: 330 Surface: AC
 L.C.D.: 01/01/1991 Use: TAXIWAY Rank P Length: 1,200.00 Ft Width: 35.00 Ft True Area: 108,166.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--------------------------|
| 01/01/1991 | IMPORTED | BUILT | | | True | ASSUME: 1991 AC PAVEMENT |

Date:05/27/2015

Work History Report

8 of 15

Pavement Database:FDOT

Network: MLB Branch: TW C (TAXIWAY C) Section: 340 Surface: AAC
 L.C.D.: 01/01/2003 Use: TAXIWAY Rank P Length: 500.00 Ft Width: 40.00 Ft True Area: 20,581.69 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-----------------------------|------|----------------|-----------|-------------------------------|
| 01/01/2003 | SR-AC | Surface Reconstruction - AC | \$0 | 0.00 | True | 2" AC/8" P-211/EXISTING BASE |
| 01/01/1991 | IMPORTED | OVERLAY | | | True | 1991: P-401 FEATHERED OVERLAY |
| 01/01/1985 | IMPORTED | BUILT | | 1.00 | True | 1985: 1" P-401 ON 8" P-211 |

Network: MLB Branch: TW C (TAXIWAY C) Section: 350 Surface: AC
 L.C.D.: 01/01/2003 Use: TAXIWAY Rank P Length: 1.075.00 Ft Width: 75.00 Ft True Area: 71.723.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|-----------------|
| 01/01/2003 | INITIAL | Initial Construction | \$0 | 0.00 | True | 4" AC/16" P-211 |

Network: MLB Branch: TW CONN AP (CONNECTOR TAXIWAY TO TERM) Section: 2110 Surface: AC
 L.C.D.: 01/01/1989 Use: TAXIWAY Rank P Length: 100.00 Ft Width: 80.00 Ft True Area: 8.353.54 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|------------------------------|
| 01/01/1989 | IMPORTED | BUILT | | 1.50 | True | 1989: 1.5" P-401 ON 8" P-211 |

Network: MLB Branch: TW D (TAXIWAY D) Section: 405 Surface: AAC
 L.C.D.: 01/01/2012 Use: TAXIWAY Rank P Length: 95.00 Ft Width: 40.00 Ft True Area: 8,073.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1992 | IMPORTED | BUILT | | 2.00 | True | 1992: 2" P-401 ON 6" P-211 |

Network: MLB Branch: TW D (TAXIWAY D) Section: 408 Surface: AAC
 L.C.D.: 01/01/2008 Use: TAXIWAY Rank P Length: 190.00 Ft Width: 40.00 Ft True Area: 7,929.70 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------------------------|
| 01/01/2008 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1979 | INITIAL | Initial Construction | \$0 | 1.00 | True | 1979: 1" P-401 ON 6" P-211 |

Network: MLB Branch: TW D (TAXIWAY D) Section: 410 Surface: AC
 L.C.D.: 01/01/1979 Use: TAXIWAY Rank P Length: 2,600.00 Ft Width: 40.00 Ft True Area: 104,051.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/1979 | IMPORTED | BUILT | | 1.00 | True | 1979: 1" P-401 ON 6" P-211 |

Network: MLB Branch: TW D (TAXIWAY D) Section: 412 Surface: AC
 L.C.D.: 01/01/1979 Use: TAXIWAY Rank P Length: 110.00 Ft Width: 40.00 Ft True Area: 4,498.34 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/1979 | IMPORTED | BUILT | | 1.00 | True | 1979: 1" P-401 ON 6" P-211 |

Network: MLB Branch: TW D (TAXIWAY D) Section: 415 Surface: AC
 L.C.D.: 01/01/2001 Use: TAXIWAY Rank P Length: 450.00 Ft Width: 40.00 Ft True Area: 19,192.44 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------------|
| 01/01/2001 | INITIAL | Initial Construction | \$0 | 0.00 | True | 2" AC/8" P-211 |

Network: MLB Branch: TW D (TAXIWAY D) Section: 416 Surface: AC
 L.C.D.: 01/01/2001 Use: TAXIWAY Rank P Length: 210.00 Ft Width: 40.00 Ft True Area: 8,422.93 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|-----------|------------------|------|----------------|-----------|----------|
| | | | | | | |

Date:05/27/2015

Work History Report

9 of 15

Pavement Database:FDOT

| 01/01/2001 | INITIAL | Initial Construction | \$0 | 0.00 | True | 2" AC/8" P-211 |
|--|-----------|----------------------------|------|----------------|-----------|--|
| Network: MLB Branch: TW D (TAXIWAY D) Section: 450 Surface: AAC L.C.D.: 01/01/2012 Use: TAXIWAY Rank P Length: 370.00 Ft Width: 60.00 Ft True Area: 23,691.60 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1979 | IMPORTED | BUILT | | 1.00 | True | 1979: 1" P-401 ON 6" P-211 |
| Network: MLB Branch: TW D (TAXIWAY D) Section: 455 Surface: AAC L.C.D.: 01/01/2012 Use: TAXIWAY Rank P Length: 270.00 Ft Width: 70.00 Ft True Area: 32,702.00 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1965 | IMPORTED | BUILT | | | True | ESTIMATE 1965 AC PAVEMENT |
| Network: MLB Branch: TW F (TAXIWAY F) Section: 810 Surface: AC L.C.D.: 01/01/2013 Use: TAXIWAY Rank P Length: 2,225.00 Ft Width: 25.00 Ft True Area: 64,381.00 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2013 | NU-IN | New Construction - Initial | \$0 | 2.00 | True | 2013: 2" P-401, 8" P-211, 8" WORK PLATFORM |
| Network: MLB Branch: TW G (TAXIWAY G) Section: 605 Surface: AC L.C.D.: 01/01/2010 Use: TAXIWAY Rank P Length: 700.00 Ft Width: 50.00 Ft True Area: 40,977.00 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2010 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |
| Network: MLB Branch: TW K (TAXIWAY K) Section: 1110 Surface: AAC L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 120.00 Ft Width: 40.00 Ft True Area: 5,207.14 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN. - 3" AVG. P-401 OVERLAY |
| 01/01/1981 | IMPORTED | BUILT | | 1.00 | True | 1981: 1" P-401 ON 8" P-211 |
| Network: MLB Branch: TW K (TAXIWAY K) Section: 1115 Surface: AAC L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 3,600.00 Ft Width: 40.00 Ft True Area: 145,056.06 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1983 | IMPORTED | BUILT | | 1.00 | True | 1983: 1" P-401 ON 8" P-211 |
| Network: MLB Branch: TW K (TAXIWAY K) Section: 1116 Surface: AAC L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 170.00 Ft Width: 40.00 Ft True Area: 6,760.00 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1983 | INITIAL | Initial Construction | \$0 | 0.00 | True | |
| Network: MLB Branch: TW K (TAXIWAY K) Section: 1120 Surface: AAC L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 240.00 Ft Width: 40.00 Ft True Area: 9,926.37 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1986 | IMPORTED | BUILT | | 1.00 | True | 1986: 1" P-401 ON 8" P-211 |

Date:05/27/2015

Work History Report

10 of 15

Pavement Database:FDOT

Network: MLB Branch: TW K (TAXIWAY K) Section: 1125 Surface: AAC
 L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 2,350.00 Ft Width: 40.00 Ft True Area: 94,533.01 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1985 | IMPORTED | BUILT | | 1.00 | True | 1985: 1" P-401 ON 8" P-211 |

Network: MLB Branch: TW K (TAXIWAY K) Section: 1130 Surface: AAC
 L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 1,900.00 Ft Width: 40.00 Ft True Area: 76,184.15 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1986 | IMPORTED | BUILT | | 1.00 | True | 1986: 1" P-401 ON 8" P-211 |

Network: MLB Branch: TW K (TAXIWAY K) Section: 1132 Surface: AC
 L.C.D.: 01/01/2011 Use: TAXIWAY Rank P Length: 1,700.00 Ft Width: 12.00 Ft True Area: 21,084.44 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2011 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: TW K (TAXIWAY K) Section: 1135 Surface: AAC
 L.C.D.: 01/01/2006 Use: TAXIWAY Rank P Length: 1,900.00 Ft Width: 40.00 Ft True Area: 82,706.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1983 | IMPORTED | BUILT | | 1.00 | True | 1983: 1" P-401 AND 6" MIN. - 8" AVG. P-211 PLACED ON |
| 01/01/1983 | IMPORTED | OVERLAY | | | True | EXISTING BASE COURSE |

Network: MLB Branch: TW K (TAXIWAY K) Section: 1140 Surface: AC
 L.C.D.: 01/01/2014 Use: TAXIWAY Rank P Length: 2,300.00 Ft Width: 10.00 Ft True Area: 23,583.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|--|
| 01/01/2014 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | 2014: 3" P-401, 8" P-211, 8" WORK PLATFORM |

Network: MLB Branch: TW L (TAXIWAY L) Section: 1204 Surface: AAC
 L.C.D.: 01/01/1998 Use: TAXIWAY Rank P Length: 115.00 Ft Width: 90.00 Ft True Area: 10,453.39 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|---|
| 01/01/1998 | IMPORTED | BUILT | | 2.00 | True | 1998 FEATHERED AC SURFACE ON 2" MILLED FOR BUTT JOINT |
| 01/01/1998 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC |
| 01/01/1975 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | 1975: 4" P-401 ON 10" P-211 |

Network: MLB Branch: TW L (TAXIWAY L) Section: 1210 Surface: AAC
 L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 380.00 Ft Width: 90.00 Ft True Area: 34,315.81 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|-----------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1975 | IMPORTED | BUILT | | 4.00 | True | 1975: 4" P-401 ON 10" P-211 |

Network: MLB Branch: TW M (TAXIWAY M) Section: 1305 Surface: AAC
 L.C.D.: 01/01/2003 Use: TAXIWAY Rank P Length: 200.00 Ft Width: 40.00 Ft True Area: 8,625.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-----------------------------|------|----------------|-----------|----------|
| 01/01/2003 | SR-AC | Surface Reconstruction - AC | \$0 | 0.00 | True | |

Date:05/27/2015

Work History Report

11 of 15

Pavement Database:FDOT

| 01/01/1991 | IMPORTED | OVERLAY | | 3.00 | True | 1991: 3" P-401 OVERLAY |
|---|-----------|-------------------------|------|----------------|-----------|--|
| 01/01/1983 | IMPORTED | BUILT | | 1.00 | True | 1983: 1" P-401 ON 8" P-211 |
| Network: MLB Branch: TW M (TAXIWAY M) Section: 1312 Surface: AC L.C.D.: 01/01/2003 Use: TAXIWAY Rank P Length: 800.00 Ft Width: 20.00 Ft True Area: 16.404.32 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2003 | INITIAL | Initial Construction | \$0 | 0.00 | True | 4" AC/12" P-211/6" SUBGRADE |
| Network: MLB Branch: TW M (TAXIWAY M) Section: 1315 Surface: AC L.C.D.: 01/01/2003 Use: TAXIWAY Rank P Length: 660.00 Ft Width: 75.00 Ft True Area: 50.873.01 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2003 | INITIAL | Initial Construction | \$0 | 0.00 | True | |
| Network: MLB Branch: TW M (TAXIWAY M) Section: 1320 Surface: AAC L.C.D.: 01/01/2003 Use: TAXIWAY Rank P Length: 220.00 Ft Width: 25.00 Ft True Area: 5.525.77 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2003 | OL-AS | Overlay - AC Structural | \$0 | 6.00 | True | |
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |
| Network: MLB Branch: TW M (TAXIWAY M) Section: 1325 Surface: AAC L.C.D.: 01/01/2003 Use: TAXIWAY Rank P Length: 220.00 Ft Width: 25.00 Ft True Area: 5.525.77 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2003 | OL-AS | Overlay - AC Structural | \$0 | 6.00 | True | |
| 12/25/1999 | INITIAL | Initial Construction | \$0 | 0.00 | True | |
| Network: MLB Branch: TW N (TAXIWAY N) Section: 1404 Surface: AAC L.C.D.: 01/01/1998 Use: TAXIWAY Rank P Length: 110.00 Ft Width: 90.00 Ft True Area: 10,299.73 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/1998 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC |
| 01/01/1998 | IMPORTED | OVERLAY | | 2.00 | True | 1998 2" AC PAVEMENT FEATHERED TO MATCH R/W AND T/W |
| 01/01/1986 | IMPORTED | BUILT | | 3.00 | True | 1986 3" P401 ON 12" P211 |
| Network: MLB Branch: TW N (TAXIWAY N) Section: 1405 Surface: AAC L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 380.00 Ft Width: 90.00 Ft True Area: 34.528.58 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1986 | IMPORTED | BUILT | | 3.00 | True | 1986: 3" P-401 ON 12" P-211 |
| Network: MLB Branch: TW Q (TAXIWAY Q) Section: 1705 Surface: AAC L.C.D.: 01/01/2007 Use: TAXIWAY Rank P Length: 1,000.00 Ft Width: 90.00 Ft True Area: 91.925.99 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2007 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1987 | IMPORTED | BUILT | | 3.00 | True | 1987: 3" P-401 ON 12" P-211 |
| Network: MLB Branch: TW Q (TAXIWAY Q) Section: 1710 Surface: AAC L.C.D.: 01/01/2007 Use: TAXIWAY Rank P Length: 120.00 Ft Width: 100.00 Ft True Area: 12.103.97 SqF | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 01/01/2007 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1987 | IMPORTED | BUILT | | 3.00 | True | 1987: 3" P-401 ON 12" P-211 |

Date:05/27/2015

Work History Report

12 of 15

Pavement Database:FDOT

Network: MLB **Branch:** TW Q (TAXIWAY Q) **Section:** 1720 **Surface:** AAC
L.C.D.: 01/01/2009 **Use:** TAXIWAY **Rank P Length:** 540.00 Ft **Width:** 100.00 Ft **True Area:** 54,193.57 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | EXISTING 6.5" AC ON 10" LIME ROCK 1978: 2" P-401 OVERLAY |
| 01/01/2004 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1978 | IMPORTED | OVERLAY | | 6.50 | True | |
| 01/01/1978 | IMPORTED | BUILT | | 2.00 | True | |

Network: MLB **Branch:** TW Q (TAXIWAY Q) **Section:** 1722 **Surface:** AAC
L.C.D.: 01/01/2004 **Use:** TAXIWAY **Rank P Length:** 120.00 Ft **Width:** 60.00 Ft **True Area:** 7,920.90 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|--------------------------------------|
| 01/01/2004 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | 1.5-2" AC 1978 2" P401 OVERLAY ON |
| 01/01/1998 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | |
| 01/01/1978 | IMPORTED | BUILT | | 2.00 | True | |

Network: MLB **Branch:** TW Q (TAXIWAY Q) **Section:** 1725 **Surface:** AAC
L.C.D.: 01/01/2004 **Use:** TAXIWAY **Rank P Length:** 1,400.00 Ft **Width:** 75.00 Ft **True Area:** 106,628.29 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-----------------------------|------|----------------|-----------|---|
| 01/01/2004 | SR-AC | Surface Reconstruction - AC | \$0 | 0.00 | True | 4" AC/12" P-211/EXISTING BASE 1981: 1" P-401 ON 8" P-211 |
| 01/01/1981 | IMPORTED | BUILT | | 1.00 | True | |

Network: MLB **Branch:** TW Q (TAXIWAY Q) **Section:** 1732 **Surface:** AAC
L.C.D.: 01/01/2006 **Use:** TAXIWAY **Rank P Length:** 100.00 Ft **Width:** 40.00 Ft **True Area:** 4,294.68 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|--|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | 1991: 3" P-401 OVERLAY 1982: 1" P-401 ON 8" P-211 |
| 01/01/1991 | IMPORTED | OVERLAY | | 3.00 | True | |
| 01/01/1982 | IMPORTED | BUILT | | 1.00 | True | |

Network: MLB **Branch:** TW Q (TAXIWAY Q) **Section:** 1735 **Surface:** AAC
L.C.D.: 01/01/2006 **Use:** TAXIWAY **Rank P Length:** 350.00 Ft **Width:** 40.00 Ft **True Area:** 15,616.09 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/2006 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | 1982: 1" P-401 ON 8" P-211 |
| 01/01/1982 | IMPORTED | BUILT | | 1.00 | True | |

Network: MLB **Branch:** TW R (TAXIWAY R) **Section:** 1805 **Surface:** AAC
L.C.D.: 01/01/2009 **Use:** TAXIWAY **Rank P Length:** 1,200.00 Ft **Width:** 50.00 Ft **True Area:** 61,343.65 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | EXISTING 6.5" AC ON 10" LIME ROCK 1991: 2" MIN - 3" AVG. P-401 OVERLAY 1978: 2" P-401 OVERLAY |
| 01/01/1991 | IMPORTED | OVERLAY | | 6.50 | True | |
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | |
| 01/01/1978 | IMPORTED | BUILT | | 2.00 | True | |

Network: MLB **Branch:** TW R (TAXIWAY R) **Section:** 1807 **Surface:** AAC
L.C.D.: 01/01/1998 **Use:** TAXIWAY **Rank P Length:** 350.00 Ft **Width:** 40.00 Ft **True Area:** 14,115.27 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|--|
| 01/01/1998 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC 1998 TAPERED AC ON 2" MILLED AC SURFACE 1981 3" P401 OVERLAY 1978 3" P401 ON 12" P211 |
| 01/01/1998 | IMPORTED | OVERLAY | | 2.00 | True | |
| 01/01/1981 | IMPORTED | OVERLAY | | 3.00 | True | |
| 01/01/1978 | IMPORTED | BUILT | | 3.00 | True | |

Date:05/27/2015

Work History Report

13 of 15

Pavement Database:FDOT

Network: MLB **Branch:** TW R (TAXIWAY R) **Section:** 1810 **Surface:** AAC
L.C.D.: 01/01/2009 **Use:** TAXIWAY **Rank P Length:** 1,500.00 Ft **Width:** 40.00 Ft **True Area:** 61,999.35 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN. - 3" AVG. P-401 OVERLAY |
| 01/01/1978 | IMPORTED | BUILT | | 3.00 | True | 1978: 3" P-401 ON 12" P-211 |

Network: MLB **Branch:** TW R (TAXIWAY R) **Section:** 1820 **Surface:** AAC
L.C.D.: 01/01/2009 **Use:** TAXIWAY **Rank P Length:** 400.00 Ft **Width:** 50.00 Ft **True Area:** 49,954.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1991 | IMPORTED | OVERLAY | | 2.00 | True | 1991: 2" MIN. - 3" AVG. P-401 OVERLAY |
| 01/01/1991 | IMPORTED | OVERLAY | | 6.50 | True | EXISTING 6.5" P-401 ON 10" P-211 |
| 01/01/1978 | IMPORTED | BUILT | | 2.00 | True | 1978: 2" P-401 OVERLAY |

Network: MLB **Branch:** TW S (TAXIWAY S) **Section:** 505 **Surface:** AAC
L.C.D.: 01/01/2004 **Use:** TAXIWAY **Rank P Length:** 485.00 Ft **Width:** 40.00 Ft **True Area:** 18,700.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|---------------------------|
| 01/01/2004 | ML-OV | MILL and OVERLAY | \$0 | 0.00 | True | |
| 12/25/1951 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | EST. CONST. OF ABANDON RW |

Network: MLB **Branch:** TW S (TAXIWAY S) **Section:** 510 **Surface:** AAC
L.C.D.: 01/01/2006 **Use:** TAXIWAY **Rank P Length:** 1,900.00 Ft **Width:** 36.00 Ft **True Area:** 68,429.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|--------------|
| 01/01/2006 | ML-OV | MILL and OVERLAY | \$0 | 0.00 | True | |
| 01/01/1983 | ML-OV | MILL and OVERLAY | \$0 | 0.00 | True | EST. OVERLAY |
| 12/25/1951 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |

Network: MLB **Branch:** TW S (TAXIWAY S) **Section:** 515 **Surface:** AC
L.C.D.: 01/01/2010 **Use:** TAXIWAY **Rank P Length:** 520.00 Ft **Width:** 40.00 Ft **True Area:** 18,556.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|----------|
| 01/01/2010 | RECONAC | Reconstruct with AC | \$0 | 0.00 | True | |
| 12/25/1951 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |

Network: MLB **Branch:** TW S1 (TAXIWAY S1) **Section:** 520 **Surface:** AC
L.C.D.: 01/01/2009 **Use:** TAXIWAY **Rank P Length:** 375.00 Ft **Width:** 37.50 Ft **True Area:** 14,644.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|----------|
| 01/01/2009 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | |

Network: MLB **Branch:** TW S1 (TAXIWAY S1) **Section:** 525 **Surface:** AC
L.C.D.: 01/01/2014 **Use:** TAXIWAY **Rank P Length:** 525.00 Ft **Width:** 35.00 Ft **True Area:** 19,360.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|--------------------------|
| 01/01/2014 | NU-IN | New Construction - Initial | \$0 | 3.00 | True | 2014: 3" P-401, 8" P-211 |

Network: MLB **Branch:** TW T (TAXIWAY T) **Section:** 2005 **Surface:** AAC
L.C.D.: 01/01/1986 **Use:** TAXIWAY **Rank P Length:** 600.00 Ft **Width:** 75.00 Ft **True Area:** 47,618.77 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/1986 | IMPORTED | OVERLAY | | 7.00 | True | EXISTING 7" AC ON 12" LIMEROCK |
| 01/01/1986 | IMPORTED | BUILT | | 2.00 | True | 1986: 2" MIN. - 3" AVG. P-401 OVERLAY |

Date:05/27/2015

Work History Report

14 of 15

Pavement Database:FDOT

Network: MLB Branch: TW T (TAXIWAY T) Section: 2015 Surface: AC
 L.C.D.: 01/01/2001 Use: TAXIWAY Rank P Length: 540.00 Ft Width: 100.00 Ft True Area: 54,726.76 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|---------------------------------------|
| 01/01/2001 | INITIAL | Initial Construction | \$0 | 0.00 | True | 4" AC/12" P-211/6" P-152/20" SUBGRADE |

Network: MLB Branch: TW V (TAXIWAY V) Section: 1602 Surface: AAC
 L.C.D.: 01/01/1998 Use: TAXIWAY Rank P Length: 115.00 Ft Width: 90.00 Ft True Area: 10,398.11 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-------------------------|------|----------------|-----------|--|
| 01/01/1998 | IMPORTED | OVERLAY | | 2.00 | True | 1998 TAPERED AC PAVEMENT ON 2" MILLED AC SURFACE |
| 01/01/1998 | OL-AS | Overlay - AC Structural | \$0 | 0.00 | True | 1.5-2" AC |
| 01/01/1978 | IMPORTED | BUILT | | 3.00 | True | 1978 3" P401 ON 12" P211 |

Network: MLB Branch: TW V (TAXIWAY V) Section: 1605 Surface: AAC
 L.C.D.: 01/01/2009 Use: TAXIWAY Rank P Length: 611.00 Ft Width: 100.00 Ft True Area: 61,170.72 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|-------------------------------------|
| 01/01/2009 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1978 | IMPORTED | BUILT | | 3.00 | True | 1978: 3" P-401 OVERLAY ON 12" P-211 |

Network: MLB Branch: TW V (TAXIWAY V) Section: 1610 Surface: AC
 L.C.D.: 01/01/2013 Use: TAXIWAY Rank P Length: 1,300.00 Ft Width: 25.00 Ft True Area: 36,715.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|--|
| 01/01/2013 | NU-IN | New Construction - Initial | \$0 | 0.00 | True | 2013: 2" P-401, 8" P-211, 8" WORK PLATFORM |

Network: MLB Branch: TW V (TAXIWAY V) Section: 2205 Surface: AAC
 L.C.D.: 01/01/2012 Use: TAXIWAY Rank P Length: 380.00 Ft Width: 40.00 Ft True Area: 14,782.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------|------|----------------|-----------|----------------------------|
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1979 | IMPORTED | BUILT | | 1.00 | True | 1979: 1" P-401 ON 6" P-211 |

Network: MLB Branch: TW V (TAXIWAY V) Section: 2210 Surface: AAC
 L.C.D.: 01/01/2012 Use: TAXIWAY Rank P Length: 270.00 Ft Width: 50.00 Ft True Area: 13,664.52 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2012 | ML-OL | Mill and Overlay | \$0 | 0.00 | True | |
| 01/01/1979 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: TW V1 (TAXIWAY V1) Section: 710 Surface: AC
 L.C.D.: 01/01/2008 Use: APRON Rank P Length: 225.00 Ft Width: 40.00 Ft True Area: 11,452.00 SqF

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2008 | INITIAL | Initial Construction | \$0 | 0.00 | True | |

Network: MLB Branch: TW V2 (TAXIWAY V2) Section: 720 Surface: AC
 L.C.D.: 01/01/2013 Use: TAXIWAY Rank P Length: 250.00 Ft Width: 30.00 Ft True Area: 8,446.00 SqF



| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------------|------|----------------|-----------|--|
| 01/01/2013 | NU-IN | New Construction - Initial | \$0 | 2.00 | True | 2013: 2" P-401, 8" P-211, 8" WORK PLATFORM |

Summary:

| Work Description | Section Count | Area Total (SqFt) | Thickness Avg (in) | Thickness STD (in) |
|-----------------------------|---------------|-------------------|--------------------|--------------------|
| BUILT | 65 | 6,267,292.75 | 2.67 | 2.54 |
| Initial Construction | 29 | 1,546,669.59 | .55 | 1.62 |
| MILL and OVERLAY | 45 | 2,781,319.19 | .00 | .00 |
| New Construction - AC | 1 | 97,785.00 | .00 | |
| New Construction - Initial | 18 | 871,240.39 | 1.50 | 3.37 |
| New Construction - PCC | 1 | 2,842.00 | .00 | |
| OVERLAY | 38 | 6,798,434.24 | 2.53 | 1.83 |
| Overlay - AC Structural | 17 | 1,805,369.42 | .76 | 1.99 |
| Reconstruct with AC | 1 | 18,556.00 | .00 | |
| Surface Reconstruction - AC | 5 | 281,724.56 | .80 | 1.79 |

APPENDIX B

- AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
- PAVEMENT CONDITION INDEX INVENTORY



RUNWAYS

| | | | | | |
|------------------|------------------|------------------|------------------|------------------|------------------|
| 6105 PCI = 58 | 6110 PCI = 74 | 6203 PCI = 95 | 6204 PCI = 90 | 6205 PCI = 76 | 6210 PCI = 61 |
| 6215 PCI = 96 | 6220 PCI = 91 | 6305 PCI = 69 | 6310 PCI = 57 | 6315 PCI = 54 | |

TAXIWAYS

| | | | | | | | | | | | | | |
|------------------|------------------|------------------|------------------|------------------|------------------|------------------|-------------------|------------------|-------------------|------------------|------------------|------------------|------------------|
| 105 PCI = 78 | 120 PCI = 78 | 130 PCI = 88 | 132 PCI = 92 | 305 PCI = 84 | 310 PCI = 77 | 315 PCI = 71 | 320 PCI = 91 | 330 PCI = 75 | 340 PCI = 84 | 350 PCI = 79 | 405 PCI = 87 | 408 PCI = 84 | 410 PCI = 63 |
| 412 PCI = 63 | 415 PCI = 82 | 416 PCI = 80 | 450 PCI = 94 | 455 PCI = 90 | 505 PCI = 63 | 510 PCI = 55 | 515 PCI = 87 | 520 PCI = 76 | 525 PCI = 100 | 605 PCI = 94 | 710 PCI = 88 | 720 PCI = 100 | 810 PCI = 100 |
| 1105 PCI = 81 | 1110 PCI = 84 | 1115 PCI = 78 | 1116 PCI = 76 | 1120 PCI = 70 | 1125 PCI = 80 | 1130 PCI = 82 | 1132 PCI = 92 | 1135 PCI = 78 | 1140 PCI = 100 | 1204 PCI = 75 | 1210 PCI = 74 | 1305 PCI = 70 | 1312 PCI = 71 |
| 1315 PCI = 77 | 1320 PCI = 75 | 1325 PCI = 88 | 1404 PCI = 81 | 1405 PCI = 93 | 1602 PCI = 70 | 1605 PCI = 87 | 1610 PCI = 100 | 1705 PCI = 75 | 1710 PCI = 83 | 1720 PCI = 88 | 1722 PCI = 72 | 1725 PCI = 83 | 1732 PCI = 91 |
| 1735 PCI = 88 | 1805 PCI = 90 | 1807 PCI = 69 | 1810 PCI = 85 | 1820 PCI = 87 | 2005 PCI = 83 | 2015 PCI = 84 | 2110 PCI = 86 | 2205 PCI = 94 | 2210 PCI = 94 | | | | |

OTHERS

| | | | | | | | | | | | | | | | | |
|------------------|------------------|------------------|------------------|------------------|------------------|------------------|-------------------|-------------------|-------------------|-------------------|------------------|------------------|------------------|------------------|-------------------|------------------|
| 3310 PCI = 72 | 3315 PCI = 76 | 4105 PCI = 67 | 4110 PCI = 59 | 4115 PCI = 96 | 4120 PCI = 69 | 4125 PCI = 91 | 4130 PCI = 76 | 4135 PCI = 86 | 4140 PCI = 94 | 4145 PCI = 100 | 4205 PCI = 80 | 4210 PCI = 82 | 4305 PCI = 94 | 4310 PCI = 91 | 4312 PCI = 13 | 4315 PCI = 67 |
| 4320 PCI = 57 | 4325 PCI = 0 | 4330 PCI = 5 | 4404 PCI = 88 | 4406 PCI = 50 | 4407 PCI = 85 | 4410 PCI = 45 | 4415 PCI = 100 | 4420 PCI = 100 | 4425 PCI = 100 | 4510 PCI = 91 | 4515 PCI = 70 | 4520 PCI = 92 | 4710 PCI = 80 | 4720 PCI = 80 | 4730 PCI = 100 | 4498 PCI = 74 |

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

"SECTION NO."
"PCI NO."

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|-----------|------|------------|
| | | |
| DESIGNED: | KHA | DRAWN: KHA |
| CHECKED: | KHA | DATE: 2015 |



AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
MELBOURNE INTERNATIONAL AIRPORT
BREVARD COUNTY, FLORIDA
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE

Table B-1: Pavement Condition Index Inventory

| Branch Name | Branch ID | Branch Use | Section ID | True Area (FT ²) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|-----------------|-----------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| RUNWAY 5-23 | RW 5-23 | RUNWAY | 6315 | 6,900 | S | AAC | 54 | Poor | 1 | 2 |
| RUNWAY 5-23 | RW 5-23 | RUNWAY | 6310 | 6,900 | S | AAC | 57 | Fair | 1 | 2 |
| RUNWAY 5-23 | RW 5-23 | RUNWAY | 6305 | 211,297 | S | AC | 69 | Fair | 12 | 56 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6220 | 17,500 | S | AAC | 91 | Good | 1 | 3 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6215 | 8,750 | S | AAC | 96 | Good | 1 | 2 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6210 | 565,132 | S | AAC | 61 | Fair | 20 | 114 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6205 | 282,566 | S | AAC | 76 | Satisfactory | 12 | 56 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6204 | 17,500 | P | AAC | 90 | Good | 1 | 3 |
| RUNWAY 9L-27R | RW 9L-27R | RUNWAY | 6203 | 8,750 | P | AAC | 95 | Good | 1 | 2 |
| RUNWAY 9R-27L | RW 9R-27L | RUNWAY | 6110 | 475,000 | P | AAC | 74 | Satisfactory | 20 | 96 |
| RUNWAY 9R-27L | RW 9R-27L | RUNWAY | 6105 | 950,000 | P | AAC | 58 | Fair | 21 | 190 |
| CENTER APRON | AP CENTER | APRON | 4998 | 48,745 | P | PCC | 74 | Satisfactory | 2 | 8 |
| APRON SOUTHWEST | AP SW | APRON | 4730 | 101,878 | P | AC | 100 | Good | 3 | 24 |
| APRON SOUTHWEST | AP SW | APRON | 4720 | 146,718 | P | AC | 80 | Satisfactory | 4 | 31 |
| APRON SOUTHWEST | AP SW | APRON | 4710 | 216,728 | P | AC | 80 | Satisfactory | 5 | 42 |
| CENTER APRON | AP CENTER | APRON | 4520 | 55,946 | P | AC | 92 | Good | 1 | 9 |
| CENTER APRON | AP CENTER | APRON | 4515 | 2,842 | P | APC | 70 | Fair | 1 | 1 |
| CENTER APRON | AP CENTER | APRON | 4510 | 23,048 | P | PCC | 91 | Good | 1 | 3 |
| EAST APRON | AP E | APRON | 4425 | 253,400 | P | PCC | 100 | Good | 4 | 34 |
| EAST APRON | AP E | APRON | 4420 | 129,420 | P | AC | 100 | Good | 3 | 26 |
| EAST APRON | AP E | APRON | 4415 | 14,188 | P | APC | 100 | Good | 1 | 4 |
| EAST APRON | AP E | APRON | 4410 | 100,915 | P | AC | 45 | Poor | 3 | 22 |
| EAST APRON | AP E | APRON | 4407 | 69,765 | P | AAC | 85 | Satisfactory | 3 | 18 |
| EAST APRON | AP E | APRON | 4406 | 12,949 | P | APC | 50 | Poor | 1 | 2 |
| EAST APRON | AP E | APRON | 4404 | 76,125 | P | APC | 88 | Good | 2 | 12 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Branch Use | Section ID | True Area (FT ²) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|-------------------------------------|------------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| WEST APRON | AP W | APRON | 4330 | 52,136 | P | PCC | 5 | Failed | 2 | 8 |
| WEST APRON | AP W | APRON | 4325 | 45,350 | P | PCC | 0 | Failed | 2 | 7 |
| WEST APRON | AP W | APRON | 4320 | 75,950 | P | AC | 57 | Fair | 2 | 15 |
| WEST APRON | AP W | APRON | 4315 | 57,374 | P | AAC | 67 | Fair | 2 | 11 |
| WEST APRON | AP W | APRON | 4312 | 8,547 | P | PCC | 13 | Serious | 1 | 1 |
| WEST APRON | AP W | APRON | 4310 | 47,311 | P | AAC | 91 | Good | 1 | 9 |
| WEST APRON | AP W | APRON | 4305 | 34,199 | P | AAC | 94 | Good | 1 | 6 |
| TERMINAL APRON | AP TERM | APRON | 4210 | 344,919 | P | AAC | 82 | Satisfactory | 8 | 74 |
| TERMINAL APRON | AP TERM | APRON | 4205 | 290,074 | P | PCC | 80 | Satisfactory | 4 | 37 |
| NORTH GA APRON | AP N GA | APRON | 4145 | 7,860 | P | AAC | 100 | Good | 1 | 2 |
| NORTH GA APRON | AP N GA | APRON | 4140 | 23,711 | P | AC | 94 | Good | 1 | 4 |
| NORTH GA APRON | AP N GA | APRON | 4135 | 22,180 | P | APC | 86 | Good | 1 | 6 |
| NORTH GA APRON | AP N GA | APRON | 4130 | 97,785 | P | AC | 76 | Satisfactory | 2 | 15 |
| NORTH GA APRON | AP N GA | APRON | 4125 | 51,200 | P | PCC | 91 | Good | 2 | 10 |
| NORTH GA APRON | AP N GA | APRON | 4120 | 96,139 | P | AC | 69 | Fair | 3 | 22 |
| NORTH GA APRON | AP N GA | APRON | 4115 | 162,260 | P | PCC | 96 | Good | 3 | 20 |
| NORTH GA APRON | AP N GA | APRON | 4110 | 127,070 | P | AC | 59 | Fair | 3 | 26 |
| NORTH GA APRON | AP N GA | APRON | 4105 | 95,800 | P | AC | 67 | Fair | 3 | 18 |
| THRESHOLD TO RW 27L | RW 27L THR | RUNWAY | 3315 | 34,034 | P | AAC | 76 | Satisfactory | 2 | 8 |
| THRESHOLD TO RW 27L | RW 27L THR | RUNWAY | 3310 | 68,068 | P | AAC | 72 | Satisfactory | 3 | 14 |
| TAXIWAY V | TW V | TAXIWAY | 2210 | 13,665 | P | AAC | 94 | Good | 1 | 3 |
| TAXIWAY V | TW V | TAXIWAY | 2205 | 14,782 | P | AAC | 94 | Good | 1 | 4 |
| CONNECTOR TAXIWAY TO TERMINAL APRON | TW CONN AP | TAXIWAY | 2110 | 8,354 | P | AC | 86 | Good | 1 | 2 |
| TAXIWAY T | TW T | TAXIWAY | 2015 | 54,727 | P | AC | 84 | Satisfactory | 2 | 11 |
| TAXIWAY T | TW T | TAXIWAY | 2005 | 47,619 | P | AAC | 83 | Satisfactory | 2 | 9 |

| Branch Name | Branch ID | Branch Use | Section ID | True Area (FT ²) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|-------------|-----------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| TAXIWAY R | TW R | TAXIWAY | 1820 | 49,954 | P | AAC | 87 | Good | 2 | 10 |
| TAXIWAY R | TW R | TAXIWAY | 1810 | 61,999 | P | AAC | 85 | Satisfactory | 3 | 13 |
| TAXIWAY R | TW R | TAXIWAY | 1807 | 14,115 | P | AAC | 69 | Fair | 1 | 3 |
| TAXIWAY R | TW R | TAXIWAY | 1805 | 61,344 | P | AAC | 90 | Good | 2 | 13 |
| TAXIWAY Q | TW Q | TAXIWAY | 1735 | 15,616 | P | AAC | 88 | Good | 1 | 4 |
| TAXIWAY Q | TW Q | TAXIWAY | 1732 | 4,295 | P | AAC | 91 | Good | 1 | 1 |
| TAXIWAY Q | TW Q | TAXIWAY | 1725 | 106,628 | P | AAC | 83 | Satisfactory | 5 | 28 |
| TAXIWAY Q | TW Q | TAXIWAY | 1722 | 7,921 | P | AAC | 72 | Satisfactory | 1 | 2 |
| TAXIWAY Q | TW Q | TAXIWAY | 1720 | 54,194 | P | AAC | 88 | Good | 1 | 10 |
| TAXIWAY Q | TW Q | TAXIWAY | 1710 | 12,104 | P | AAC | 83 | Satisfactory | 1 | 2 |
| TAXIWAY Q | TW Q | TAXIWAY | 1705 | 91,926 | P | AAC | 75 | Satisfactory | 3 | 19 |
| TAXIWAY V | TW V | TAXIWAY | 1610 | 36,715 | P | AC | 100 | Good | 1 | 9 |
| TAXIWAY V | TW V | TAXIWAY | 1605 | 61,171 | P | AAC | 87 | Good | 2 | 12 |
| TAXIWAY V | TW V | TAXIWAY | 1602 | 10,398 | P | AAC | 70 | Fair | 1 | 3 |
| TAXIWAY N | TW N | TAXIWAY | 1405 | 34,529 | P | AAC | 93 | Good | 1 | 8 |
| TAXIWAY N | TW N | TAXIWAY | 1404 | 10,300 | P | AAC | 81 | Satisfactory | 1 | 2 |
| TAXIWAY M | TW M | TAXIWAY | 1325 | 5,526 | P | AAC | 88 | Good | 1 | 2 |
| TAXIWAY M | TW M | TAXIWAY | 1320 | 5,526 | P | AAC | 75 | Satisfactory | 1 | 2 |
| TAXIWAY M | TW M | TAXIWAY | 1315 | 50,873 | P | AC | 77 | Satisfactory | 2 | 13 |
| TAXIWAY M | TW M | TAXIWAY | 1312 | 16,404 | P | AC | 71 | Satisfactory | 1 | 4 |
| TAXIWAY M | TW M | TAXIWAY | 1305 | 8,625 | P | AAC | 70 | Fair | 1 | 2 |
| TAXIWAY L | TW L | TAXIWAY | 1210 | 34,316 | P | AAC | 74 | Satisfactory | 1 | 7 |
| TAXIWAY L | TW L | TAXIWAY | 1204 | 10,453 | P | AAC | 75 | Satisfactory | 1 | 2 |
| TAXIWAY K | TW K | TAXIWAY | 1140 | 23,583 | P | AC | 100 | Good | 1 | 5 |
| TAXIWAY K | TW K | TAXIWAY | 1135 | 82,706 | P | AAC | 78 | Satisfactory | 5 | 20 |
| TAXIWAY K | TW K | TAXIWAY | 1132 | 21,084 | P | AC | 92 | Good | 1 | 4 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Branch Use | Section ID | True Area (FT ²) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|-------------|-----------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| TAXIWAY K | TW K | TAXIWAY | 1130 | 76,184 | P | AAC | 82 | Satisfactory | 3 | 19 |
| TAXIWAY K | TW K | TAXIWAY | 1125 | 94,533 | P | AAC | 80 | Satisfactory | 4 | 23 |
| TAXIWAY K | TW K | TAXIWAY | 1120 | 9,926 | P | AAC | 70 | Fair | 1 | 2 |
| TAXIWAY K | TW K | TAXIWAY | 1116 | 6,760 | P | AAC | 76 | Satisfactory | 1 | 2 |
| TAXIWAY K | TW K | TAXIWAY | 1115 | 145,056 | P | AAC | 78 | Satisfactory | 5 | 35 |
| TAXIWAY K | TW K | TAXIWAY | 1110 | 5,207 | P | AAC | 84 | Satisfactory | 1 | 1 |
| TAXIWAY B | TW B | TAXIWAY | 1105 | 101,687 | P | AAC | 81 | Satisfactory | 3 | 18 |
| TAXIWAY F | TW F | TAXIWAY | 810 | 64,381 | P | AC | 100 | Good | 3 | 14 |
| TAXIWAY V2 | TW V2 | TAXIWAY | 720 | 8,446 | P | AC | 100 | Good | 1 | 2 |
| TAXIWAY V1 | TW V1 | APRON | 710 | 11,452 | P | AC | 88 | Good | 1 | 2 |
| TAXIWAY G | TW G | TAXIWAY | 605 | 40,977 | P | AC | 94 | Good | 1 | 8 |
| TAXIWAY S1 | TW S1 | TAXIWAY | 525 | 19,360 | P | AC | 100 | Good | 1 | 5 |
| TAXIWAY S1 | TW S1 | TAXIWAY | 520 | 14,644 | P | AC | 76 | Satisfactory | 1 | 4 |
| TAXIWAY S | TW S | TAXIWAY | 515 | 18,556 | P | AC | 87 | Good | 1 | 5 |
| TAXIWAY S | TW S | TAXIWAY | 510 | 68,429 | P | AAC | 55 | Poor | 3 | 19 |
| TAXIWAY S | TW S | TAXIWAY | 505 | 18,700 | P | AAC | 63 | Fair | 1 | 4 |
| TAXIWAY D | TW D | TAXIWAY | 455 | 32,702 | P | AAC | 90 | Good | 2 | 5 |
| TAXIWAY D | TW D | TAXIWAY | 450 | 23,692 | P | AAC | 94 | Good | 1 | 4 |
| TAXIWAY D | TW D | TAXIWAY | 416 | 8,423 | P | AC | 80 | Satisfactory | 1 | 2 |
| TAXIWAY D | TW D | TAXIWAY | 415 | 19,192 | P | AC | 82 | Satisfactory | 1 | 5 |
| TAXIWAY D | TW D | TAXIWAY | 412 | 4,498 | P | AC | 63 | Fair | 1 | 1 |
| TAXIWAY D | TW D | TAXIWAY | 410 | 104,051 | P | AC | 63 | Fair | 5 | 25 |
| TAXIWAY D | TW D | TAXIWAY | 408 | 7,930 | P | AAC | 84 | Satisfactory | 1 | 2 |
| TAXIWAY D | TW D | TAXIWAY | 405 | 8,073 | P | AAC | 87 | Good | 1 | 2 |
| TAXIWAY C | TW C | TAXIWAY | 350 | 71,723 | P | AC | 79 | Satisfactory | 3 | 19 |
| TAXIWAY C | TW C | TAXIWAY | 340 | 20,582 | P | AAC | 84 | Satisfactory | 1 | 5 |

| Branch Name | Branch ID | Branch Use | Section ID | True Area (FT ²) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|-------------|-----------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| TAXIWAY C | TW C | TAXIWAY | 330 | 108,166 | P | AC | 75 | Satisfactory | 3 | 27 |
| TAXIWAY C | TW C | TAXIWAY | 320 | 41,105 | P | AAC | 91 | Good | 1 | 9 |
| TAXIWAY C | TW C | TAXIWAY | 315 | 63,222 | P | AAC | 71 | Satisfactory | 3 | 17 |
| TAXIWAY C | TW C | TAXIWAY | 310 | 13,011 | P | AAC | 77 | Satisfactory | 1 | 3 |
| TAXIWAY C | TW C | TAXIWAY | 305 | 43,008 | P | AAC | 84 | Satisfactory | 2 | 8 |
| TAXIWAY A | TW A | TAXIWAY | 132 | 58,319 | P | AAC | 92 | Good | 2 | 13 |
| TAXIWAY A | TW A | TAXIWAY | 130 | 36,222 | P | AAC | 88 | Good | 1 | 8 |
| TAXIWAY A | TW A | TAXIWAY | 120 | 691,660 | P | AAC | 78 | Satisfactory | 10 | 172 |
| TAXIWAY A | TW A | TAXIWAY | 105 | 38,493 | P | AAC | 78 | Satisfactory | 1 | 8 |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.

APPENDIX C

- BRANCH CONDITION REPORT
- SECTION CONDITION REPORT

Date: 5 /27/2015

Branch Condition Report

1 of 3

Pavement Database: FDOT NetworkID: MLB

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP CENTER (CENTER APRON) | 4 | 1,329.00 | 102.50 | 130,581.19 | APRON | 81.75 | 9.86 | 84.63 |
| AP E (EAST APRON) | 7 | 3,890.00 | 250.00 | 656,761.58 | APRON | 81.14 | 22.05 | 87.58 |
| AP N GA (NORTH GA APRON) | 9 | 4,646.00 | 152.06 | 684,005.53 | APRON | 82.00 | 13.82 | 77.69 |
| AP SW (APRON SOUTHWEST) | 3 | 3,200.00 | 201.67 | 465,323.84 | APRON | 86.67 | 9.43 | 84.38 |
| AP TERM (TERMINAL APRON) | 2 | 2,280.00 | 350.00 | 634,993.36 | APRON | 81.00 | 1.00 | 81.09 |
| AP W (WEST APRON) | 7 | 1,920.75 | 183.14 | 320,867.31 | APRON | 46.71 | 37.37 | 50.07 |
| RW 27L THR (THRESHOLD TO RW 27L) | 2 | 1,791.00 | 62.50 | 102,102.00 | RUNWAY | 74.00 | 2.00 | 73.33 |
| RW 5-23 (RUNWAY 5-23) | 3 | 2,967.00 | 65.00 | 225,096.70 | RUNWAY | 60.00 | 6.48 | 68.17 |
| RW 9L-27R (RUNWAY 9L-27R) | 6 | 18,003.00 | 62.50 | 900,197.41 | RUNWAY | 84.83 | 12.51 | 67.53 |
| RW 9R-27L (RUNWAY 9R-27L) | 2 | 28,300.00 | 62.50 | 1,425,000.00 | RUNWAY | 66.00 | 8.00 | 63.33 |
| TW A (TAXIWAY A) | 4 | 10,400.00 | 86.25 | 824,692.94 | TAXIWAY | 84.00 | 6.16 | 79.43 |
| TW B (TAXIWAY B) | 1 | 1,000.00 | 100.00 | 101,687.15 | TAXIWAY | 81.00 | 0.00 | 81.00 |
| TW C (TAXIWAY C) | 7 | 5,825.00 | 52.86 | 360,817.59 | TAXIWAY | 80.14 | 6.20 | 78.58 |
| TW CONN AP (CONNECTOR TAXIWAY TO TERMINAL APRON) | 1 | 100.00 | 80.00 | 8,353.54 | TAXIWAY | 86.00 | 0.00 | 86.00 |
| TW D (TAXIWAY D) | 8 | 4,295.00 | 46.25 | 208,561.01 | TAXIWAY | 80.38 | 10.85 | 74.92 |
| TW F (TAXIWAY F) | 1 | 2,225.00 | 25.00 | 64,381.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |

Date: 5 /27/2015

Branch Condition Report

2 of 3

Pavement Database: FDOT NetworkID: MLB

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| TW G (TAXIWAY G) | 1 | 700.00 | 50.00 | 40,977.00 | TAXIWAY | 94.00 | 0.00 | 94.00 |
| TW K (TAXIWAY K) | 9 | 14,280.00 | 33.56 | 465,040.17 | TAXIWAY | 82.22 | 8.46 | 80.68 |
| TW L (TAXIWAY L) | 2 | 495.00 | 90.00 | 44,769.20 | TAXIWAY | 74.50 | 0.50 | 74.23 |
| TW M (TAXIWAY M) | 5 | 2,100.00 | 37.00 | 86,953.87 | TAXIWAY | 76.20 | 6.43 | 75.75 |
| TW N (TAXIWAY N) | 2 | 490.00 | 90.00 | 44,828.31 | TAXIWAY | 87.00 | 6.00 | 90.24 |
| TW Q (TAXIWAY Q) | 7 | 3,630.00 | 72.14 | 292,683.49 | TAXIWAY | 82.86 | 6.53 | 81.50 |
| TW R (TAXIWAY R) | 4 | 3,450.00 | 45.00 | 187,412.27 | TAXIWAY | 82.75 | 8.14 | 85.96 |
| TW S (TAXIWAY S) | 3 | 2,905.00 | 38.67 | 105,685.00 | TAXIWAY | 68.33 | 13.60 | 62.03 |
| TW S1 (TAXIWAY S1) | 2 | 900.00 | 36.25 | 34,004.00 | TAXIWAY | 88.00 | 12.00 | 89.66 |
| TW T (TAXIWAY T) | 2 | 1,140.00 | 87.50 | 102,345.53 | TAXIWAY | 83.50 | 0.50 | 83.53 |
| TW V (TAXIWAY V) | 5 | 2,676.00 | 61.00 | 136,730.35 | TAXIWAY | 89.00 | 10.35 | 90.65 |
| TW V1 (TAXIWAY V1) | 1 | 225.00 | 40.00 | 11,452.00 | APRON | 88.00 | 0.00 | 88.00 |
| TW V2 (TAXIWAY V2) | 1 | 250.00 | 30.00 | 8,446.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |

Date: 5 /27/2015

Branch Condition Report

3 of 3

Pavement Database: FDOT

| Use Category | Number of Sections | Total Area (SqFt) | Arithmetic Average PCI | Average PCI STD. | Weighted Average PCI |
|--------------|--------------------|---------------------|------------------------|------------------|----------------------|
| APRON | 33 | 2,903,984.81 | 74.85 | 26.22 | 79.04 |
| RUNWAY | 13 | 2,652,396.11 | 74.54 | 14.19 | 65.55 |
| TAXIWAY | 65 | 3,118,368.42 | 82.29 | 9.86 | 80.67 |
| All | 111 | 8,674,749.34 | 79.17 | 17.28 | 75.50 |

| <div> <div>Date: 5 /27/2015</div> <div>Section Condition Report</div> <div>1 of 6</div> </div> <div> <div>Pavement Database: FDOT</div> <div>NetworkID: MLB</div> </div> | | | | | | | | | | |
|--|------------|------------------|---------|-------|------|-------|------------------|----------------------|-------------------|--------|
| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
| AP CENTER (CENTER APRON) | 4510 | 01/01/2009 | PCC | APRON | P | 0 | 23,048.00 | 04/06/2015 | 6 | 91.00 |
| AP CENTER (CENTER APRON) | 4515 | 01/01/2009 | APC | APRON | P | 0 | 2,842.00 | 04/06/2015 | 6 | 70.00 |
| AP CENTER (CENTER APRON) | 4520 | 01/01/2009 | AC | APRON | P | 0 | 55,946.19 | 04/06/2015 | 6 | 92.00 |
| AP CENTER (CENTER APRON) | 4998 | 01/01/1995 | PCC | APRON | P | 0 | 48,745.00 | 04/06/2015 | 20 | 74.00 |
| AP E (EAST APRON) | 4404 | 01/01/2004 | APC | APRON | P | 0 | 76,125.00 | 04/06/2015 | 11 | 88.00 |
| AP E (EAST APRON) | 4406 | 01/01/1998 | APC | APRON | P | 0 | 12,949.00 | 04/06/2015 | 17 | 50.00 |
| AP E (EAST APRON) | 4407 | 01/01/2004 | AAC | APRON | P | 0 | 69,764.58 | 04/06/2015 | 11 | 85.00 |
| AP E (EAST APRON) | 4410 | 12/25/1999 | AC | APRON | P | 0 | 100,915.00 | 04/06/2015 | 16 | 45.00 |
| AP E (EAST APRON) | 4415 | 01/01/2014 | APC | APRON | P | 0 | 14,188.00 | 01/01/2014 | 0 | 100.00 |
| AP E (EAST APRON) | 4420 | 01/01/2014 | AC | APRON | P | 0 | 129,420.00 | 01/01/2014 | 0 | 100.00 |
| AP E (EAST APRON) | 4425 | 01/01/2014 | PCC | APRON | P | 0 | 253,400.00 | 01/01/2014 | 0 | 100.00 |
| AP N GA (NORTH GA APRON) | 4105 | 01/01/1986 | AC | APRON | P | 0 | 95,800.00 | 04/06/2015 | 29 | 67.00 |
| AP N GA (NORTH GA APRON) | 4110 | 01/01/1982 | AC | APRON | P | 0 | 127,070.36 | 04/06/2015 | 33 | 59.00 |
| AP N GA (NORTH GA APRON) | 4115 | 01/01/2003 | PCC | APRON | P | 0 | 162,260.00 | 04/06/2015 | 12 | 96.00 |
| AP N GA (NORTH GA APRON) | 4120 | 01/01/2003 | AC | APRON | P | 0 | 96,139.17 | 04/06/2015 | 12 | 69.00 |
| AP N GA (NORTH GA APRON) | 4125 | 01/01/2003 | PCC | APRON | P | 0 | 51,200.00 | 04/06/2015 | 12 | 91.00 |
| AP N GA (NORTH GA APRON) | 4130 | 01/01/2006 | AC | APRON | P | 0 | 97,785.00 | 04/06/2015 | 9 | 76.00 |
| AP N GA (NORTH GA APRON) | 4135 | 01/01/2010 | APC | APRON | P | 0 | 22,180.00 | 04/06/2015 | 5 | 86.00 |
| AP N GA (NORTH GA APRON) | 4140 | 01/01/2010 | AC | APRON | P | 0 | 23,711.00 | 04/06/2015 | 5 | 94.00 |
| AP N GA (NORTH GA APRON) | 4145 | 01/01/2013 | AAC | APRON | P | 0 | 7,860.00 | 01/01/2013 | 0 | 100.00 |
| AP SW (APRON SOUTHWEST) | 4710 | 01/01/2008 | AC | APRON | P | 0 | 216,727.84 | 04/06/2015 | 7 | 80.00 |
| AP SW (APRON SOUTHWEST) | 4720 | 01/01/2008 | AC | APRON | P | 0 | 146,718.00 | 04/06/2015 | 7 | 80.00 |
| AP SW (APRON SOUTHWEST) | 4730 | 01/01/2013 | AC | APRON | P | 0 | 101,878.00 | 01/01/2013 | 0 | 100.00 |
| AP TERM (TERMINAL APRON) | 4205 | 01/01/1989 | PCC | APRON | P | 0 | 290,074.00 | 04/06/2015 | 26 | 80.00 |
| AP TERM (TERMINAL APRON) | 4210 | 01/01/2009 | AAC | APRON | P | 0 | 344,919.36 | 04/06/2015 | 6 | 82.00 |
| AP W (WEST APRON) | 4305 | 01/01/2012 | AAC | APRON | P | 0 | 34,199.31 | 04/06/2015 | 3 | 94.00 |
| AP W (WEST APRON) | 4310 | 01/01/2012 | AAC | APRON | P | 0 | 47,311.00 | 04/06/2015 | 3 | 91.00 |

| <div> <div>Date: 5 /27/2015</div> <div> <div>Section Condition Report</div> <div> <div>Pavement Database: FDOT</div> <div>NetworkID: MLB</div> </div> </div> <div>2 of 6</div> </div> | | | | | | | | | | |
|---|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
| AP W (WEST APRON) | 4312 | 12/25/1994 | PCC | APRON | P | 0 | 8,547.00 | 04/06/2015 | 21 | 13.00 |
| AP W (WEST APRON) | 4315 | 01/01/2012 | AAC | APRON | P | 0 | 57,374.00 | 04/06/2015 | 3 | 67.00 |
| AP W (WEST APRON) | 4320 | 01/01/1979 | AC | APRON | P | 0 | 75,950.00 | 04/06/2015 | 36 | 57.00 |
| AP W (WEST APRON) | 4325 | 01/01/1942 | PCC | APRON | P | 0 | 45,350.00 | 04/06/2015 | 73 | 0.00 |
| AP W (WEST APRON) | 4330 | 01/01/1942 | PCC | APRON | P | 0 | 52,136.00 | 04/06/2015 | 73 | 5.00 |
| RW 27L THR (THRESHOLD TO RW 27L) | 3310 | 01/01/2001 | AAC | RUNWAY | P | 0 | 68,068.00 | 04/06/2015 | 14 | 72.00 |
| RW 27L THR (THRESHOLD TO RW 27L) | 3315 | 01/01/2001 | AAC | RUNWAY | P | 0 | 34,034.00 | 04/06/2015 | 14 | 76.00 |
| RW 5-23 (RUNWAY 5-23) | 6305 | 01/01/1992 | AC | RUNWAY | S | 0 | 211,296.70 | 04/06/2015 | 23 | 69.00 |
| RW 5-23 (RUNWAY 5-23) | 6310 | 01/01/1992 | AAC | RUNWAY | S | 0 | 6,900.00 | 04/06/2015 | 23 | 57.00 |
| RW 5-23 (RUNWAY 5-23) | 6315 | 01/01/1992 | AAC | RUNWAY | S | 0 | 6,900.00 | 04/06/2015 | 23 | 54.00 |
| RW 9L-27R (RUNWAY 9L-27R) | 6203 | 01/01/2011 | AAC | RUNWAY | P | 0 | 8,750.00 | 04/06/2015 | 4 | 95.00 |
| RW 9L-27R (RUNWAY 9L-27R) | 6204 | 01/01/2011 | AAC | RUNWAY | P | 0 | 17,500.00 | 04/06/2015 | 4 | 90.00 |
| RW 9L-27R (RUNWAY 9L-27R) | 6205 | 01/01/1991 | AAC | RUNWAY | S | 0 | 282,565.80 | 04/06/2015 | 24 | 76.00 |
| RW 9L-27R (RUNWAY 9L-27R) | 6210 | 01/01/1991 | AAC | RUNWAY | S | 0 | 565,131.61 | 04/06/2015 | 24 | 61.00 |
| RW 9L-27R (RUNWAY 9L-27R) | 6215 | 01/01/2011 | AAC | RUNWAY | S | 0 | 8,750.00 | 04/06/2015 | 4 | 96.00 |
| RW 9L-27R (RUNWAY 9L-27R) | 6220 | 01/01/2011 | AAC | RUNWAY | S | 0 | 17,500.00 | 04/06/2015 | 4 | 91.00 |
| RW 9R-27L (RUNWAY 9R-27L) | 6105 | 01/01/1998 | AAC | RUNWAY | P | 0 | 950,000.00 | 04/06/2015 | 17 | 58.00 |
| RW 9R-27L (RUNWAY 9R-27L) | 6110 | 01/01/1998 | AAC | RUNWAY | P | 0 | 475,000.00 | 04/06/2015 | 17 | 74.00 |
| TW A (TAXIWAY A) | 105 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 38,492.70 | 04/06/2015 | 6 | 78.00 |
| TW A (TAXIWAY A) | 120 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 691,659.95 | 04/06/2015 | 6 | 78.00 |
| TW A (TAXIWAY A) | 130 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 36,221.74 | 04/06/2015 | 6 | 88.00 |
| TW A (TAXIWAY A) | 132 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 58,318.55 | 04/06/2015 | 6 | 92.00 |
| TW B (TAXIWAY B) | 1105 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 101,687.15 | 04/06/2015 | 9 | 81.00 |
| TW C (TAXIWAY C) | 305 | 01/01/2007 | AAC | TAXIWAY | P | 0 | 43,008.00 | 04/06/2015 | 8 | 84.00 |
| TW C (TAXIWAY C) | 310 | 01/01/2004 | AAC | TAXIWAY | P | 0 | 13,011.46 | 04/06/2015 | 11 | 77.00 |
| TW C (TAXIWAY C) | 315 | 01/01/2004 | AAC | TAXIWAY | P | 0 | 63,222.44 | 04/06/2015 | 11 | 71.00 |

| <div> <div>Date: 5 /27/2015</div> <div>Section Condition Report</div> <div>3 of 6</div> </div> <div> <div>Pavement Database: FDOT</div> <div>NetworkID: MLB</div> </div> | | | | | | | | | | |
|--|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
| TW C (TAXIWAY C) | 320 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 41,105.00 | 04/06/2015 | 6 | 91.00 |
| TW C (TAXIWAY C) | 330 | 01/01/1991 | AC | TAXIWAY | P | 0 | 108,166.00 | 04/06/2015 | 24 | 75.00 |
| TW C (TAXIWAY C) | 340 | 01/01/2003 | AAC | TAXIWAY | P | 0 | 20,581.69 | 04/06/2015 | 12 | 84.00 |
| TW C (TAXIWAY C) | 350 | 01/01/2003 | AC | TAXIWAY | P | 0 | 71,723.00 | 04/06/2015 | 12 | 79.00 |
| TW CONN AP (CONNECTOR TAXIWAY TO TERMINAL APRON) | 2110 | 01/01/1989 | AC | TAXIWAY | P | 0 | 8,353.54 | 04/06/2015 | 26 | 86.00 |
| TW D (TAXIWAY D) | 405 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 8,073.00 | 04/06/2015 | 3 | 87.00 |
| TW D (TAXIWAY D) | 408 | 01/01/2008 | AAC | TAXIWAY | P | 0 | 7,929.70 | 04/06/2015 | 7 | 84.00 |
| TW D (TAXIWAY D) | 410 | 01/01/1979 | AC | TAXIWAY | P | 0 | 104,051.00 | 04/06/2015 | 36 | 63.00 |
| TW D (TAXIWAY D) | 412 | 01/01/1979 | AC | TAXIWAY | P | 0 | 4,498.34 | 04/06/2015 | 36 | 63.00 |
| TW D (TAXIWAY D) | 415 | 01/01/2001 | AC | TAXIWAY | P | 0 | 19,192.44 | 04/06/2015 | 14 | 82.00 |
| TW D (TAXIWAY D) | 416 | 01/01/2001 | AC | TAXIWAY | P | 0 | 8,422.93 | 04/06/2015 | 14 | 80.00 |
| TW D (TAXIWAY D) | 450 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 23,691.60 | 04/06/2015 | 3 | 94.00 |
| TW D (TAXIWAY D) | 455 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 32,702.00 | 04/06/2015 | 3 | 90.00 |
| TW F (TAXIWAY F) | 810 | 01/01/2013 | AC | TAXIWAY | P | 0 | 64,381.00 | 01/01/2013 | 0 | 100.00 |
| TW G (TAXIWAY G) | 605 | 01/01/2010 | AC | TAXIWAY | P | 0 | 40,977.00 | 04/06/2015 | 5 | 94.00 |
| TW K (TAXIWAY K) | 1110 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 5,207.14 | 04/06/2015 | 9 | 84.00 |
| TW K (TAXIWAY K) | 1115 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 145,056.06 | 04/06/2015 | 9 | 78.00 |
| TW K (TAXIWAY K) | 1116 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 6,760.00 | 04/06/2015 | 9 | 76.00 |
| TW K (TAXIWAY K) | 1120 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 9,926.37 | 04/06/2015 | 9 | 70.00 |
| TW K (TAXIWAY K) | 1125 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 94,533.01 | 04/06/2015 | 9 | 80.00 |
| TW K (TAXIWAY K) | 1130 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 76,184.15 | 04/06/2015 | 9 | 82.00 |
| TW K (TAXIWAY K) | 1132 | 01/01/2011 | AC | TAXIWAY | P | 0 | 21,084.44 | 04/06/2015 | 4 | 92.00 |
| TW K (TAXIWAY K) | 1135 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 82,706.00 | 04/06/2015 | 9 | 78.00 |
| TW K (TAXIWAY K) | 1140 | 01/01/2014 | AC | TAXIWAY | P | 0 | 23,583.00 | 01/01/2014 | 0 | 100.00 |
| TW L (TAXIWAY L) | 1204 | 01/01/1998 | AAC | TAXIWAY | P | 0 | 10,453.39 | 04/06/2015 | 17 | 75.00 |
| TW L (TAXIWAY L) | 1210 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 34,315.81 | 04/06/2015 | 6 | 74.00 |

Date: 5 /27/2015

Section Condition Report

4 of 6

Pavement Database: FDOT NetworkID: MLB

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|--------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| TW M (TAXIWAY M) | 1305 | 01/01/2003 | AAC | TAXIWAY | P | 0 | 8,625.00 | 04/06/2015 | 12 | 70.00 |
| TW M (TAXIWAY M) | 1312 | 01/01/2003 | AC | TAXIWAY | P | 0 | 16,404.32 | 04/06/2015 | 12 | 71.00 |
| TW M (TAXIWAY M) | 1315 | 01/01/2003 | AC | TAXIWAY | P | 0 | 50,873.01 | 04/06/2015 | 12 | 77.00 |
| TW M (TAXIWAY M) | 1320 | 01/01/2003 | AAC | TAXIWAY | P | 0 | 5,525.77 | 04/06/2015 | 12 | 75.00 |
| TW M (TAXIWAY M) | 1325 | 01/01/2003 | AAC | TAXIWAY | P | 0 | 5,525.77 | 04/06/2015 | 12 | 88.00 |
| TW N (TAXIWAY N) | 1404 | 01/01/1998 | AAC | TAXIWAY | P | 0 | 10,299.73 | 04/06/2015 | 17 | 81.00 |
| TW N (TAXIWAY N) | 1405 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 34,528.58 | 04/06/2015 | 6 | 93.00 |
| TW Q (TAXIWAY Q) | 1705 | 01/01/2007 | AAC | TAXIWAY | P | 0 | 91,925.99 | 04/06/2015 | 8 | 75.00 |
| TW Q (TAXIWAY Q) | 1710 | 01/01/2007 | AAC | TAXIWAY | P | 0 | 12,103.97 | 04/06/2015 | 8 | 83.00 |
| TW Q (TAXIWAY Q) | 1720 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 54,193.57 | 04/06/2015 | 6 | 88.00 |
| TW Q (TAXIWAY Q) | 1722 | 01/01/2004 | AAC | TAXIWAY | P | 0 | 7,920.90 | 04/06/2015 | 11 | 72.00 |
| TW Q (TAXIWAY Q) | 1725 | 01/01/2004 | AAC | TAXIWAY | P | 0 | 106,628.29 | 04/06/2015 | 11 | 83.00 |
| TW Q (TAXIWAY Q) | 1732 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 4,294.68 | 04/06/2015 | 9 | 91.00 |
| TW Q (TAXIWAY Q) | 1735 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 15,616.09 | 04/06/2015 | 9 | 88.00 |
| TW R (TAXIWAY R) | 1805 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 61,343.65 | 04/06/2015 | 6 | 90.00 |
| TW R (TAXIWAY R) | 1807 | 01/01/1998 | AAC | TAXIWAY | P | 0 | 14,115.27 | 04/06/2015 | 17 | 69.00 |
| TW R (TAXIWAY R) | 1810 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 61,999.35 | 04/06/2015 | 6 | 85.00 |
| TW R (TAXIWAY R) | 1820 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 49,954.00 | 04/06/2015 | 6 | 87.00 |
| TW S (TAXIWAY S) | 505 | 01/01/2004 | AAC | TAXIWAY | P | 0 | 18,700.00 | 04/06/2015 | 11 | 63.00 |
| TW S (TAXIWAY S) | 510 | 01/01/2006 | AAC | TAXIWAY | P | 0 | 68,429.00 | 04/06/2015 | 9 | 55.00 |
| TW S (TAXIWAY S) | 515 | 01/01/2010 | AC | TAXIWAY | P | 0 | 18,556.00 | 04/06/2015 | 5 | 87.00 |
| TW S1 (TAXIWAY S1) | 520 | 01/01/2009 | AC | TAXIWAY | P | 0 | 14,644.00 | 04/06/2015 | 6 | 76.00 |
| TW S1 (TAXIWAY S1) | 525 | 01/01/2014 | AC | TAXIWAY | P | 0 | 19,360.00 | 01/01/2014 | 0 | 100.00 |
| TW T (TAXIWAY T) | 2005 | 01/01/1986 | AAC | TAXIWAY | P | 0 | 47,618.77 | 04/06/2015 | 29 | 83.00 |
| TW T (TAXIWAY T) | 2015 | 01/01/2001 | AC | TAXIWAY | P | 0 | 54,726.76 | 04/06/2015 | 14 | 84.00 |
| TW V (TAXIWAY V) | 1602 | 01/01/1998 | AAC | TAXIWAY | P | 0 | 10,398.11 | 04/06/2015 | 17 | 70.00 |

Date: 5 /27/2015

Section Condition Report

5 of 6

Pavement Database: FDOT NetworkID: MLB

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|--------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|--------|
| TW V (TAXIWAY V) | 1605 | 01/01/2009 | AAC | TAXIWAY | P | 0 | 61,170.72 | 04/06/2015 | 6 | 87.00 |
| TW V (TAXIWAY V) | 1610 | 01/01/2013 | AC | TAXIWAY | P | 0 | 36,715.00 | 01/01/2013 | 0 | 100.00 |
| TW V (TAXIWAY V) | 2205 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 14,782.00 | 04/06/2015 | 3 | 94.00 |
| TW V (TAXIWAY V) | 2210 | 01/01/2012 | AAC | TAXIWAY | P | 0 | 13,664.52 | 04/06/2015 | 3 | 94.00 |
| TW V1 (TAXIWAY V1) | 710 | 01/01/2008 | AC | APRON | P | 0 | 11,452.00 | 04/06/2015 | 7 | 88.00 |
| TW V2 (TAXIWAY V2) | 720 | 01/01/2013 | AC | TAXIWAY | P | 0 | 8,446.00 | 01/01/2013 | 0 | 100.00 |

Section Condition Report*Pavement Database: FDOT*

| Age Category | Average Age At Inspection | Total Area (SqFt) | Number of Sections | Arithmetic Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------|---------------------------|-------------------|--------------------|------------------------|------------------------|----------------------|
| 0-02 | 0.00 | 659,231.00 | 10 | 100.00 | 0.00 | 100.00 |
| 03-05 | 3.76 | 410,805.87 | 17 | 90.35 | 6.73 | 88.34 |
| 06-10 | 7.28 | 2,902,753.32 | 36 | 82.08 | 7.85 | 80.52 |
| 11-15 | 12.14 | 1,028,674.53 | 22 | 78.77 | 8.17 | 81.56 |
| 16-20 | 17.22 | 1,632,875.50 | 9 | 66.22 | 12.35 | 62.69 |
| 21-25 | 23.14 | 1,189,507.11 | 7 | 57.86 | 21.54 | 66.85 |
| 26-30 | 27.50 | 441,846.31 | 4 | 79.00 | 8.37 | 77.62 |
| 31-35 | 33.00 | 127,070.36 | 1 | 59.00 | 0.00 | 59.00 |
| 36-40 | 36.00 | 184,499.34 | 3 | 61.00 | 3.46 | 60.53 |
| over 40 | 73.00 | 97,486.00 | 2 | 2.50 | 3.54 | 2.67 |
| All | 11.77 | 8,674,749.34 | 111 | 79.17 | 17.36 | 75.50 |

APPENDIX D

- PAVEMENT PERFORMANCE PREDICTION
- PAVEMENT PERFORMANCE BY PAVEMENT USE

Table D-1: Pavement Performance Prediction

| Branch ID | Section ID | Current PCI | Pavement Performance Model - PCI | | | | | | | | | |
|--------------|---------------|----------------|----------------------------------|------|------|------|------|------|------|------|------|------|
| | | | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| AP CENTER | 4510 | 91 | 91 | 90 | 88 | 87 | 86 | 85 | 84 | 83 | 81 | 80 |
| AP CENTER | 4515 | 70 | 70 | 69 | 67 | 66 | 65 | 65 | 64 | 63 | 62 | 60 |
| AP CENTER | 4520 | 92 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 77 | 75 |
| AP CENTER | 4998 | 74 | 74 | 73 | 71 | 70 | 69 | 68 | 67 | 66 | 64 | 63 |
| AP E | 4404 | 88 | 87 | 84 | 81 | 79 | 76 | 74 | 73 | 71 | 70 | 68 |
| AP E | 4406 | 50 | 50 | 47 | 44 | 40 | 36 | 32 | 27 | 22 | 16 | 11 |
| AP E | 4407 | 85 | 85 | 82 | 79 | 77 | 75 | 73 | 71 | 70 | 69 | 68 |
| AP E | 4410 | 45 | 45 | 43 | 41 | 39 | 37 | 35 | 33 | 31 | 30 | 28 |
| AP E | 4415 | 100 | 94 | 90 | 86 | 83 | 80 | 78 | 76 | 74 | 72 | 71 |
| AP E | 4420 | 100 | 97 | 95 | 94 | 92 | 90 | 88 | 86 | 84 | 82 | 80 |
| AP E | 4425 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 91 | 90 | 89 | 88 |
| AP N GA | 4105 | 67 | 67 | 65 | 63 | 61 | 59 | 57 | 55 | 53 | 52 | 50 |
| AP N GA | 4110 | 59 | 59 | 57 | 55 | 53 | 51 | 49 | 47 | 45 | 44 | 42 |
| AP N GA | 4115 | 96 | 96 | 95 | 93 | 92 | 91 | 90 | 89 | 88 | 86 | 85 |
| AP N GA | 4120 | 69 | 69 | 67 | 65 | 63 | 61 | 59 | 57 | 55 | 54 | 52 |
| AP N GA | 4125 | 91 | 91 | 90 | 88 | 87 | 86 | 85 | 84 | 83 | 81 | 80 |
| AP N GA | 4130 | 76 | 76 | 74 | 72 | 70 | 68 | 66 | 64 | 62 | 61 | 59 |
| AP N GA | 4135 | 86 | 85 | 82 | 80 | 77 | 75 | 73 | 72 | 70 | 69 | 68 |
| AP N GA | 4140 | 94 | 94 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| AP N GA | 4145 | 100 | 90 | 86 | 83 | 80 | 78 | 76 | 74 | 72 | 71 | 69 |
| AP SW | 4710 | 80 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 66 | 65 | 63 |
| AP SW | 4720 | 80 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 66 | 65 | 63 |
| AP SW | 4730 | 100 | 95 | 94 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 78 |
| AP TERM | 4205 | 80 | 80 | 79 | 77 | 76 | 75 | 74 | 73 | 72 | 70 | 69 |
| AP TERM | 4210 | 82 | 82 | 79 | 77 | 75 | 73 | 71 | 70 | 69 | 68 | 66 |
| AP W | 4305 | 94 | 93 | 89 | 86 | 83 | 80 | 78 | 75 | 74 | 72 | 70 |
| AP W | 4310 | 91 | 90 | 87 | 84 | 81 | 78 | 76 | 74 | 72 | 71 | 69 |



| Branch ID | Section ID | Current PCI | Pavement Performance Model - PCI | | | | | | | | | |
|------------|------------|-------------|----------------------------------|------|------|------|------|------|------|------|------|------|
| | | | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| AP W | 4312 | 13 | 13 | 12 | 10 | 9 | 8 | 7 | 6 | 5 | 3 | 2 |
| AP W | 4315 | 67 | 67 | 66 | 65 | 64 | 63 | 62 | 61 | 60 | 58 | 57 |
| AP W | 4320 | 57 | 57 | 55 | 53 | 51 | 49 | 47 | 45 | 43 | 42 | 40 |
| AP W | 4325 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| AP W | 4330 | 5 | 5 | 4 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| RW 27L THR | 3310 | 72 | 72 | 70 | 68 | 66 | 64 | 61 | 59 | 57 | 55 | 53 |
| RW 27L THR | 3315 | 76 | 76 | 74 | 72 | 70 | 68 | 65 | 63 | 61 | 59 | 57 |
| RW 5-23 | 6305 | 69 | 69 | 67 | 66 | 64 | 63 | 62 | 60 | 59 | 57 | 56 |
| RW 5-23 | 6310 | 57 | 57 | 55 | 53 | 51 | 49 | 46 | 44 | 42 | 40 | 38 |
| RW 5-23 | 6315 | 54 | 54 | 52 | 50 | 48 | 46 | 43 | 41 | 39 | 37 | 35 |
| RW 9L-27R | 6203 | 95 | 95 | 93 | 91 | 89 | 87 | 84 | 82 | 80 | 78 | 76 |
| RW 9L-27R | 6204 | 90 | 90 | 88 | 86 | 84 | 82 | 79 | 77 | 75 | 73 | 71 |
| RW 9L-27R | 6205 | 76 | 76 | 74 | 72 | 70 | 68 | 65 | 63 | 61 | 59 | 57 |
| RW 9L-27R | 6210 | 61 | 61 | 59 | 57 | 55 | 53 | 50 | 48 | 46 | 44 | 42 |
| RW 9L-27R | 6215 | 96 | 96 | 94 | 92 | 90 | 88 | 85 | 83 | 81 | 79 | 77 |
| RW 9L-27R | 6220 | 91 | 91 | 89 | 87 | 85 | 83 | 80 | 78 | 76 | 74 | 72 |
| RW 9R-27L | 6105 | 58 | 58 | 56 | 54 | 52 | 50 | 47 | 45 | 43 | 41 | 39 |
| RW 9R-27L | 6110 | 74 | 74 | 72 | 70 | 68 | 66 | 63 | 61 | 59 | 57 | 55 |
| TW A | 105 | 78 | 78 | 76 | 74 | 73 | 71 | 70 | 69 | 68 | 66 | 65 |
| TW A | 120 | 78 | 78 | 76 | 74 | 73 | 71 | 70 | 69 | 68 | 66 | 65 |
| TW A | 130 | 88 | 88 | 85 | 83 | 81 | 79 | 78 | 76 | 74 | 73 | 71 |
| TW A | 132 | 92 | 92 | 89 | 86 | 84 | 82 | 80 | 78 | 77 | 75 | 73 |
| TW B | 1105 | 81 | 81 | 79 | 77 | 75 | 74 | 72 | 71 | 70 | 68 | 67 |
| TW C | 305 | 84 | 84 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 70 | 69 |
| TW C | 310 | 77 | 77 | 75 | 73 | 72 | 71 | 69 | 68 | 67 | 66 | 65 |
| TW C | 315 | 71 | 71 | 69 | 68 | 67 | 66 | 65 | 64 | 63 | 62 | 61 |
| TW C | 320 | 91 | 91 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 73 |

| Branch ID | Section ID | Current PCI | Pavement Performance Model - PCI | | | | | | | | | |
|------------|------------|-------------|----------------------------------|------|------|------|------|------|------|------|------|------|
| | | | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| TW C | 330 | 75 | 75 | 73 | 72 | 70 | 69 | 67 | 66 | 64 | 63 | 61 |
| TW C | 340 | 84 | 84 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 70 | 69 |
| TW C | 350 | 79 | 79 | 77 | 76 | 74 | 73 | 71 | 70 | 68 | 67 | 65 |
| TW CONN AP | 2110 | 86 | 86 | 84 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 72 |
| TW D | 405 | 87 | 87 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 |
| TW D | 408 | 84 | 84 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 70 | 69 |
| TW D | 410 | 63 | 63 | 61 | 60 | 58 | 57 | 55 | 54 | 52 | 51 | 49 |
| TW D | 412 | 63 | 63 | 61 | 60 | 58 | 57 | 55 | 54 | 52 | 51 | 49 |
| TW D | 415 | 82 | 82 | 80 | 79 | 77 | 76 | 74 | 73 | 71 | 70 | 68 |
| TW D | 416 | 80 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 69 | 68 | 66 |
| TW D | 450 | 94 | 94 | 91 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 |
| TW D | 455 | 90 | 90 | 87 | 85 | 83 | 81 | 79 | 77 | 75 | 74 | 72 |
| TW F | 810 | 100 | 96 | 95 | 93 | 92 | 90 | 89 | 87 | 86 | 85 | 83 |
| TW G | 605 | 94 | 94 | 92 | 91 | 89 | 88 | 86 | 85 | 83 | 82 | 80 |
| TW K | 1110 | 84 | 84 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 70 | 69 |
| TW K | 1115 | 78 | 78 | 76 | 74 | 73 | 71 | 70 | 69 | 68 | 66 | 65 |
| TW K | 1116 | 76 | 76 | 74 | 73 | 71 | 70 | 69 | 67 | 66 | 65 | 64 |
| TW K | 1120 | 70 | 70 | 69 | 67 | 66 | 65 | 64 | 63 | 62 | 61 | 60 |
| TW K | 1125 | 80 | 80 | 78 | 76 | 75 | 73 | 71 | 70 | 69 | 68 | 67 |
| TW K | 1130 | 82 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 70 | 69 | 68 |
| TW K | 1132 | 92 | 92 | 90 | 89 | 87 | 86 | 84 | 83 | 81 | 80 | 78 |
| TW K | 1135 | 78 | 78 | 76 | 74 | 73 | 71 | 70 | 69 | 68 | 66 | 65 |
| TW K | 1140 | 100 | 98 | 96 | 95 | 93 | 92 | 90 | 89 | 87 | 86 | 85 |
| TW L | 1204 | 75 | 75 | 73 | 72 | 70 | 69 | 68 | 67 | 66 | 65 | 64 |
| TW L | 1210 | 74 | 74 | 72 | 71 | 70 | 68 | 67 | 66 | 65 | 64 | 63 |
| TW M | 1305 | 70 | 70 | 69 | 67 | 66 | 65 | 64 | 63 | 62 | 61 | 60 |
| TW M | 1312 | 71 | 71 | 69 | 68 | 66 | 65 | 63 | 62 | 60 | 59 | 57 |
| TW M | 1315 | 77 | 77 | 75 | 74 | 72 | 71 | 69 | 68 | 66 | 65 | 63 |




| Branch ID | Section ID | Current PCI | Pavement Performance Model - PCI | | | | | | | | | |
|-----------|------------|-------------|----------------------------------|------|------|------|------|------|------|------|------|------|
| | | | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| TW M | 1320 | 75 | 75 | 73 | 72 | 70 | 69 | 68 | 67 | 66 | 65 | 64 |
| TW M | 1325 | 88 | 88 | 85 | 83 | 81 | 79 | 78 | 76 | 74 | 73 | 71 |
| TW N | 1404 | 81 | 81 | 79 | 77 | 75 | 74 | 72 | 71 | 70 | 68 | 67 |
| TW N | 1405 | 93 | 93 | 90 | 87 | 85 | 83 | 81 | 79 | 77 | 76 | 74 |
| TW Q | 1705 | 75 | 75 | 73 | 72 | 70 | 69 | 68 | 67 | 66 | 65 | 64 |
| TW Q | 1710 | 83 | 83 | 81 | 79 | 77 | 75 | 74 | 72 | 71 | 70 | 68 |
| TW Q | 1720 | 88 | 88 | 85 | 83 | 81 | 79 | 78 | 76 | 74 | 73 | 71 |
| TW Q | 1722 | 72 | 72 | 70 | 69 | 68 | 67 | 66 | 65 | 64 | 63 | 62 |
| TW Q | 1725 | 83 | 83 | 81 | 79 | 77 | 75 | 74 | 72 | 71 | 70 | 68 |
| TW Q | 1732 | 91 | 91 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 73 |
| TW Q | 1735 | 88 | 88 | 85 | 83 | 81 | 79 | 78 | 76 | 74 | 73 | 71 |
| TW R | 1805 | 90 | 90 | 87 | 85 | 83 | 81 | 79 | 77 | 75 | 74 | 72 |
| TW R | 1807 | 69 | 69 | 68 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 |
| TW R | 1810 | 85 | 85 | 83 | 81 | 79 | 77 | 75 | 74 | 72 | 71 | 69 |
| TW R | 1820 | 87 | 87 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 |
| TW S | 505 | 63 | 63 | 62 | 61 | 59 | 58 | 56 | 55 | 53 | 50 | 48 |
| TW S | 510 | 55 | 55 | 53 | 51 | 48 | 46 | 44 | 42 | 41 | 40 | 39 |
| TW S | 515 | 87 | 87 | 85 | 84 | 82 | 81 | 79 | 78 | 76 | 75 | 73 |
| TW S1 | 520 | 76 | 76 | 74 | 73 | 71 | 70 | 68 | 67 | 65 | 64 | 62 |
| TW S1 | 525 | 100 | 98 | 96 | 95 | 93 | 92 | 90 | 89 | 87 | 86 | 85 |
| TW T | 2005 | 83 | 83 | 81 | 79 | 77 | 75 | 74 | 72 | 71 | 70 | 68 |
| TW T | 2015 | 84 | 84 | 82 | 81 | 79 | 78 | 76 | 75 | 73 | 72 | 70 |
| TW V | 1602 | 70 | 70 | 69 | 67 | 66 | 65 | 64 | 63 | 62 | 61 | 60 |
| TW V | 1605 | 87 | 87 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 |
| TW V | 1610 | 100 | 96 | 95 | 93 | 92 | 90 | 89 | 87 | 86 | 85 | 83 |
| TW V | 2205 | 94 | 94 | 91 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 |
| TW V | 2210 | 94 | 94 | 91 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 |
| TW V1 | 710 | 88 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 73 | 71 |
| TW V2 | 720 | 100 | 96 | 95 | 93 | 92 | 90 | 89 | 87 | 86 | 85 | 83 |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.


** Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.*

Figure D-1: Pavement Performance by Pavement Use


(a) Runway



(b) Taxiway



(c) Apron



APPENDIX E

● YEAR-1 PREVENTATIVE ACTIVITIES

Table E-1: Year-1 Preventative Activities

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|--------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|---------------|
| CENTER APRON | AP CENTER | 4510 | SCALING | L | Patching - PCC Partial Depth | 3,092.20 | SqFt | \$19.10 | \$ 59,060.86 |
| CENTER APRON | AP CENTER | 4510 | SHRINKAGE CR | N | Crack Sealing - PCC | 14.30 | Ft | \$4.25 | \$ 60.65 |
| CENTER APRON | AP CENTER | 4510 | JOINT SPALL | L | Patching - PCC Partial Depth | 7.80 | SqFt | \$19.10 | \$ 149.05 |
| CENTER APRON | AP CENTER | 4510 | CORNER SPALL | L | Patching - PCC Partial Depth | 7.80 | SqFt | \$19.10 | \$ 149.05 |
| CENTER APRON | AP CENTER | 4515 | JT REF. CR | L | Crack Sealing - AC | 174.00 | Ft | \$2.75 | \$ 478.50 |
| CENTER APRON | AP CENTER | 4515 | L & T CR | L | Crack Sealing - AC | 168.00 | Ft | \$2.75 | \$ 462.00 |
| CENTER APRON | AP CENTER | 4515 | RAVELING | L | Surface Seal | 50.00 | SqFt | \$0.55 | \$ 27.50 |
| CENTER APRON | AP CENTER | 4520 | RAVELING | L | Surface Seal | 223.80 | SqFt | \$0.55 | \$ 123.08 |
| CENTER APRON | AP CENTER | 4998 | SCALING | L | Patching - PCC Partial Depth | 8,778.80 | SqFt | \$19.10 | \$ 167,675.28 |
| CENTER APRON | AP CENTER | 4998 | SHRINKAGE CR | N | Crack Sealing - PCC | 63.20 | Ft | \$4.25 | \$ 268.63 |
| CENTER APRON | AP CENTER | 4998 | JOINT SPALL | M | Patching - PCC Partial Depth | 110.60 | SqFt | \$19.10 | \$ 2,112.44 |
| CENTER APRON | AP CENTER | 4998 | JOINT SPALL | L | Patching - PCC Partial Depth | 126.70 | SqFt | \$19.10 | \$ 2,420.51 |
| CENTER APRON | AP CENTER | 4998 | CORNER SPALL | L | Patching - PCC Partial Depth | 23.00 | SqFt | \$19.10 | \$ 440.09 |
| EAST APRON | AP E | 4404 | L & T CR | L | Crack Sealing - AC | 2,874.50 | Ft | \$2.75 | \$ 7,904.81 |
| EAST APRON | AP E | 4406 | BLOCK CR | M | Patching - AC Full Depth | 480.60 | SqFt | \$5.00 | \$ 2,402.95 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|----------------|-----------|------------|----------------------|-------------------|--------------------------|---------------|-----------|-----------|---------------|
| EAST APRON | AP E | 4406 | BLOCK CR | L | Surface Seal | 12,468.40 | SqFt | \$0.55 | \$ 6,857.68 |
| EAST APRON | AP E | 4406 | RAVELING | L | Surface Seal | 961.20 | SqFt | \$0.55 | \$ 528.65 |
| EAST APRON | AP E | 4407 | L & T CR | L | Crack Sealing - AC | 1,767.40 | Ft | \$2.75 | \$ 4,860.26 |
| EAST APRON | AP E | 4410 | BLOCK CR | H | Patching - AC Full Depth | 10,131.20 | SqFt | \$5.00 | \$ 50,656.12 |
| EAST APRON | AP E | 4410 | BLOCK CR | M | Patching - AC Full Depth | 23,709.40 | SqFt | \$5.00 | \$ 118,547.32 |
| EAST APRON | AP E | 4410 | L & T CR | L | Crack Sealing - AC | 3,574.40 | Ft | \$2.75 | \$ 9,829.59 |
| EAST APRON | AP E | 4410 | OIL SPILLAGE | N | Surface Seal | 677.70 | SqFt | \$0.55 | \$ 372.73 |
| EAST APRON | AP E | 4410 | RAVELING | L | Surface Seal | 93,593.80 | SqFt | \$0.55 | \$ 51,477.04 |
| EAST APRON | AP E | 4410 | RAVELING | M | Surface Seal | 6,579.30 | SqFt | \$0.55 | \$ 3,618.64 |
| NORTH GA APRON | AP N GA | 4105 | DEPRESSION | L | Patching - AC Full Depth | 177.20 | SqFt | \$5.00 | \$ 886.11 |
| NORTH GA APRON | AP N GA | 4105 | L & T CR | L | Crack Sealing - AC | 2,356.70 | Ft | \$2.75 | \$ 6,480.86 |
| NORTH GA APRON | AP N GA | 4105 | RAVELING | L | Surface Seal | 92,606.70 | SqFt | \$0.55 | \$ 50,934.09 |
| NORTH GA APRON | AP N GA | 4105 | RAVELING | M | Surface Seal | 3,193.30 | SqFt | \$0.55 | \$ 1,756.35 |
| NORTH GA APRON | AP N GA | 4110 | DEPRESSION | L | Patching - AC Full Depth | 104.90 | SqFt | \$5.00 | \$ 524.53 |
| NORTH GA APRON | AP N GA | 4110 | L & T CR | L | Crack Sealing - AC | 53,064.60 | Ft | \$2.75 | \$ 145,927.44 |
| NORTH GA APRON | AP N GA | 4110 | OIL SPILLAGE | N | Surface Seal | 94.30 | SqFt | \$0.55 | \$ 51.86 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|----------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|---------------|
| NORTH GA APRON | AP N GA | 4110 | RAVELING | L | Surface Seal | 84,713.60 | SqFt | \$0.55 | \$ 46,592.85 |
| NORTH GA APRON | AP N GA | 4115 | SCALING | L | Patching - PCC Partial Depth | 10,536.10 | SqFt | \$19.10 | \$ 201,239.05 |
| NORTH GA APRON | AP N GA | 4115 | SHRINKAGE CR | N | Crack Sealing - PCC | 218.20 | Ft | \$4.25 | \$ 927.25 |
| NORTH GA APRON | AP N GA | 4120 | L & T CR | L | Crack Sealing - AC | 8,525.80 | Ft | \$2.75 | \$ 23,446.01 |
| NORTH GA APRON | AP N GA | 4120 | RAVELING | L | Surface Seal | 2,511.50 | SqFt | \$0.55 | \$ 1,381.36 |
| NORTH GA APRON | AP N GA | 4120 | RAVELING | M | Surface Seal | 29.80 | SqFt | \$0.55 | \$ 16.40 |
| NORTH GA APRON | AP N GA | 4125 | SCALING | L | Patching - PCC Partial Depth | 8,783.10 | SqFt | \$19.10 | \$ 167,756.87 |
| NORTH GA APRON | AP N GA | 4125 | SHRINKAGE CR | N | Crack Sealing - PCC | 210.80 | Ft | \$4.25 | \$ 895.88 |
| NORTH GA APRON | AP N GA | 4125 | JOINT SPALL | L | Patching - PCC Partial Depth | 28.80 | SqFt | \$19.10 | \$ 550.38 |
| NORTH GA APRON | AP N GA | 4125 | CORNER SPALL | L | Patching - PCC Partial Depth | 28.80 | SqFt | \$19.10 | \$ 550.38 |
| NORTH GA APRON | AP N GA | 4130 | BLEEDING | N | Patching - AC Partial Depth | 174.00 | SqFt | \$3.00 | \$ 522.02 |
| NORTH GA APRON | AP N GA | 4130 | DEPRESSION | L | Patching - AC Full Depth | 190.70 | SqFt | \$5.00 | \$ 953.47 |
| NORTH GA APRON | AP N GA | 4130 | L & T CR | L | Crack Sealing - AC | 1,489.50 | Ft | \$2.75 | \$ 4,096.12 |
| NORTH GA APRON | AP N GA | 4130 | PATCHING | M | Patching - AC Full Depth | 115.80 | SqFt | \$5.00 | \$ 578.91 |
| NORTH GA APRON | AP N GA | 4130 | RAVELING | L | Surface Seal | 1,294.60 | SqFt | \$0.55 | \$ 712.04 |
| NORTH GA APRON | AP N GA | 4135 | JT REF. CR | L | Crack Sealing - AC | 818.50 | Ft | \$2.75 | \$ 2,250.80 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|---------------|
| APRON SOUTHWEST | AP SW | 4710 | DEPRESSION | L | Patching - AC Full Depth | 101.30 | SqFt | \$5.00 | \$ 506.46 |
| APRON SOUTHWEST | AP SW | 4710 | L & T CR | L | Crack Sealing - AC | 5,944.10 | Ft | \$2.75 | \$ 16,346.20 |
| APRON SOUTHWEST | AP SW | 4710 | OIL SPILLAGE | N | Surface Seal | 59.40 | SqFt | \$0.55 | \$ 32.65 |
| APRON SOUTHWEST | AP SW | 4710 | RAVELING | L | Surface Seal | 7,590.30 | SqFt | \$0.55 | \$ 4,174.68 |
| APRON SOUTHWEST | AP SW | 4720 | BLEEDING | N | Patching - AC Partial Depth | 61.90 | SqFt | \$3.00 | \$ 185.68 |
| APRON SOUTHWEST | AP SW | 4720 | L & T CR | L | Crack Sealing - AC | 4,435.60 | Ft | \$2.75 | \$ 12,197.83 |
| APRON SOUTHWEST | AP SW | 4720 | RAVELING | L | Surface Seal | 5,054.50 | SqFt | \$0.55 | \$ 2,780.00 |
| TERMINAL APRON | AP TERM | 4205 | CORNER BREAK | L | Patching - PCC Partial Depth | 304.90 | SqFt | \$19.10 | \$ 5,823.29 |
| TERMINAL APRON | AP TERM | 4205 | SCALING | L | Patching - PCC Partial Depth | 44,141.10 | SqFt | \$19.10 | \$ 843,095.90 |
| TERMINAL APRON | AP TERM | 4205 | FAULTING | L | Patching - PCC Partial Depth | 3,097.60 | SqFt | \$19.10 | \$ 59,164.62 |
| TERMINAL APRON | AP TERM | 4205 | SHRINKAGE CR | N | Crack Sealing - PCC | 371.70 | Ft | \$4.25 | \$ 1,579.79 |
| TERMINAL APRON | AP TERM | 4205 | JOINT SPALL | L | Patching - PCC Partial Depth | 355.70 | SqFt | \$19.10 | \$ 6,793.84 |
| TERMINAL APRON | AP TERM | 4205 | CORNER SPALL | L | Patching - PCC Partial Depth | 25.40 | SqFt | \$19.10 | \$ 485.27 |
| TERMINAL APRON | AP TERM | 4210 | BLEEDING | N | Patching - AC Partial Depth | 457.10 | SqFt | \$3.00 | \$ 1,371.17 |
| TERMINAL APRON | AP TERM | 4210 | DEPRESSION | L | Patching - AC Full Depth | 1,328.70 | SqFt | \$5.00 | \$ 6,643.68 |
| TERMINAL APRON | AP TERM | 4210 | L & T CR | L | Crack Sealing - AC | 8,195.80 | Ft | \$2.75 | \$ 22,538.44 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|---------------|
| WEST APRON | AP W | 4310 | L & T CR | L | Crack Sealing - AC | 84.50 | Ft | \$2.75 | \$ 232.33 |
| WEST APRON | AP W | 4312 | JT SEAL DMG | L | Joint Seal - PCC | 337.80 | Ft | \$3.00 | \$ 1,013.33 |
| WEST APRON | AP W | 4312 | SCALING | L | Patching - PCC Partial Depth | 738.20 | SqFt | \$19.10 | \$ 14,099.41 |
| WEST APRON | AP W | 4312 | SHAT. SLAB | L | Slab Replacement - PCC | 7,200.00 | SqFt | \$45.00 | \$ 324,000.02 |
| WEST APRON | AP W | 4312 | SHAT. SLAB | M | Slab Replacement - PCC | 1,440.00 | SqFt | \$45.00 | \$ 64,800.00 |
| WEST APRON | AP W | 4312 | SHRINKAGE CR | N | Crack Sealing - PCC | 49.20 | Ft | \$4.25 | \$ 209.15 |
| WEST APRON | AP W | 4312 | JOINT SPALL | L | Patching - PCC Partial Depth | 2.70 | SqFt | \$19.10 | \$ 51.40 |
| WEST APRON | AP W | 4312 | CORNER SPALL | L | Patching - PCC Partial Depth | 2.70 | SqFt | \$19.10 | \$ 51.40 |
| WEST APRON | AP W | 4315 | BLOCK CR | L | Surface Seal | 29,168.40 | SqFt | \$0.55 | \$ 16,042.73 |
| WEST APRON | AP W | 4315 | DEPRESSION | L | Patching - AC Full Depth | 2,009.40 | SqFt | \$5.00 | \$ 10,046.88 |
| WEST APRON | AP W | 4315 | PATCHING | M | Patching - AC Full Depth | 17.70 | SqFt | \$5.00 | \$ 88.69 |
| WEST APRON | AP W | 4315 | RAVELING | L | Surface Seal | 29,114.90 | SqFt | \$0.55 | \$ 16,013.31 |
| WEST APRON | AP W | 4315 | RAVELING | H | Patching - AC Partial Depth | 53.50 | SqFt | \$3.00 | \$ 160.45 |
| WEST APRON | AP W | 4320 | BLOCK CR | L | Surface Seal | 1,204.50 | SqFt | \$0.55 | \$ 662.47 |
| WEST APRON | AP W | 4320 | DEPRESSION | L | Patching - AC Full Depth | 238.80 | SqFt | \$5.00 | \$ 1,193.86 |
| WEST APRON | AP W | 4320 | L & T CR | L | Crack Sealing - AC | 11,954.50 | Ft | \$2.75 | \$ 32,874.74 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|---------------------|------------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|-----------------|
| WEST APRON | AP W | 4320 | RAVELING | L | Surface Seal | 15,191.50 | SqFt | \$0.55 | \$ 8,355.40 |
| WEST APRON | AP W | 4320 | WEATHERING | M | Surface Seal | 59,930.40 | SqFt | \$0.55 | \$ 32,962.00 |
| WEST APRON | AP W | 4325 | JT SEAL DMG | M | Joint Seal - PCC | 4,565.80 | Ft | \$3.00 | \$ 13,697.44 |
| WEST APRON | AP W | 4325 | SHAT. SLAB | M | Slab Replacement - PCC | 42,900.00 | SqFt | \$45.00 | \$ 1,930,500.12 |
| WEST APRON | AP W | 4325 | SHAT. SLAB | H | Slab Replacement - PCC | 10,725.00 | SqFt | \$45.00 | \$ 482,625.03 |
| WEST APRON | AP W | 4325 | CORNER SPALL | L | Patching - PCC Partial Depth | 12.00 | SqFt | \$19.10 | \$ 229.68 |
| WEST APRON | AP W | 4330 | JT SEAL DMG | M | Joint Seal - PCC | 1,383.90 | Ft | \$3.00 | \$ 4,151.60 |
| WEST APRON | AP W | 4330 | JT SEAL DMG | H | Joint Seal - PCC | 1,476.10 | Ft | \$3.00 | \$ 4,428.38 |
| WEST APRON | AP W | 4330 | SCALING | L | Patching - PCC Partial Depth | 3,365.50 | SqFt | \$19.10 | \$ 64,281.18 |
| WEST APRON | AP W | 4330 | FAULTING | L | Patching - PCC Partial Depth | 448.70 | SqFt | \$19.10 | \$ 8,570.82 |
| WEST APRON | AP W | 4330 | SHAT. SLAB | H | Slab Replacement - PCC | 10,941.90 | SqFt | \$45.00 | \$ 492,387.13 |
| WEST APRON | AP W | 4330 | SHAT. SLAB | M | Slab Replacement - PCC | 35,561.30 | SqFt | \$45.00 | \$ 1,600,258.17 |
| WEST APRON | AP W | 4330 | SHAT. SLAB | L | Slab Replacement - PCC | 2,735.50 | SqFt | \$45.00 | \$ 123,096.78 |
| WEST APRON | AP W | 4330 | SHRINKAGE CR | N | Crack Sealing - PCC | 67.30 | Ft | \$4.25 | \$ 286.07 |
| THRESHOLD TO RW 27L | RW 27L THR | 3310 | L & T CR | L | Crack Sealing - AC | 4,365.40 | Ft | \$2.75 | \$ 12,004.91 |
| THRESHOLD TO RW 27L | RW 27L THR | 3310 | RAVELING | L | Surface Seal | 14,748.10 | SqFt | \$0.55 | \$ 8,111.50 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|---------------------|------------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| THRESHOLD TO RW 27L | RW 27L THR | 3315 | L & T CR | L | Crack Sealing - AC | 1,751.80 | Ft | \$2.75 | \$ 4,817.46 |
| THRESHOLD TO RW 27L | RW 27L THR | 3315 | L & T CR | M | Crack Sealing - AC | 18.80 | Ft | \$2.75 | \$ 51.80 |
| THRESHOLD TO RW 27L | RW 27L THR | 3315 | RAVELING | L | Surface Seal | 851.40 | SqFt | \$0.55 | \$ 468.28 |
| RUNWAY 5-23 | RW 5-23 | 6305 | BLEEDING | N | Patching - AC Partial Depth | 43.40 | SqFt | \$3.00 | \$ 130.30 |
| RUNWAY 5-23 | RW 5-23 | 6305 | L & T CR | L | Crack Sealing - AC | 18,284.20 | Ft | \$2.75 | \$ 50,281.52 |
| RUNWAY 5-23 | RW 5-23 | 6305 | RAVELING | L | Surface Seal | 30,145.00 | SqFt | \$0.55 | \$ 16,579.89 |
| RUNWAY 5-23 | RW 5-23 | 6310 | L & T CR | L | Crack Sealing - AC | 972.00 | Ft | \$2.75 | \$ 2,673.00 |
| RUNWAY 5-23 | RW 5-23 | 6310 | RAVELING | L | Surface Seal | 346.00 | SqFt | \$0.55 | \$ 190.30 |
| RUNWAY 5-23 | RW 5-23 | 6315 | BLOCK CR | L | Surface Seal | 296.00 | SqFt | \$0.55 | \$ 162.80 |
| RUNWAY 5-23 | RW 5-23 | 6315 | L & T CR | L | Crack Sealing - AC | 1,062.90 | Ft | \$2.75 | \$ 2,923.02 |
| RUNWAY 5-23 | RW 5-23 | 6315 | RAVELING | L | Surface Seal | 3,460.10 | SqFt | \$0.55 | \$ 1,903.07 |
| RUNWAY 9L-27R | RW 9L-27R | 6204 | BLEEDING | N | Patching - AC Partial Depth | 3.50 | SqFt | \$3.00 | \$ 10.50 |
| RUNWAY 9L-27R | RW 9L-27R | 6204 | L & T CR | L | Crack Sealing - AC | 182.00 | Ft | \$2.75 | \$ 500.50 |
| RUNWAY 9L-27R | RW 9L-27R | 6205 | L & T CR | L | Crack Sealing - AC | 10,240.00 | Ft | \$2.75 | \$ 28,159.84 |
| RUNWAY 9L-27R | RW 9L-27R | 6205 | RAVELING | L | Surface Seal | 45,713.90 | SqFt | \$0.55 | \$ 25,142.86 |
| RUNWAY 9L-27R | RW 9L-27R | 6210 | ALLIGATOR CR | L | Patching - AC Full Depth | 1,077.40 | SqFt | \$5.00 | \$ 5,387.20 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|---------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|---------------|
| RUNWAY 9L-27R | RW 9L-27R | 6210 | DEPRESSION | L | Patching - AC Full Depth | 316.10 | SqFt | \$5.00 | \$ 1,580.63 |
| RUNWAY 9L-27R | RW 9L-27R | 6210 | L & T CR | L | Crack Sealing - AC | 67,358.00 | Ft | \$2.75 | \$ 185,234.40 |
| RUNWAY 9L-27R | RW 9L-27R | 6210 | L & T CR | M | Crack Sealing - AC | 282.60 | Ft | \$2.75 | \$ 777.06 |
| RUNWAY 9L-27R | RW 9L-27R | 6210 | PATCHING | M | Patching - AC Full Depth | 132.70 | SqFt | \$5.00 | \$ 663.47 |
| RUNWAY 9L-27R | RW 9L-27R | 6210 | RAVELING | L | Surface Seal | 102,814.40 | SqFt | \$0.55 | \$ 56,548.39 |
| RUNWAY 9L-27R | RW 9L-27R | 6215 | BLEEDING | N | Patching - AC Partial Depth | 4.00 | SqFt | \$3.00 | \$ 12.00 |
| RUNWAY 9L-27R | RW 9L-27R | 6220 | BLEEDING | N | Patching - AC Partial Depth | 3.50 | SqFt | \$3.00 | \$ 10.50 |
| RUNWAY 9L-27R | RW 9L-27R | 6220 | L & T CR | L | Crack Sealing - AC | 56.00 | Ft | \$2.75 | \$ 154.00 |
| RUNWAY 9L-27R | RW 9R-27L | 6105 | ALLIGATOR CR | L | Patching - AC Full Depth | 971.90 | SqFt | \$5.00 | \$ 4,859.28 |
| RUNWAY 9L-27R | RW 9R-27L | 6105 | DEPRESSION | L | Patching - AC Full Depth | 228.70 | SqFt | \$5.00 | \$ 1,143.38 |
| RUNWAY 9L-27R | RW 9R-27L | 6105 | L & T CR | L | Crack Sealing - AC | 112,317.10 | Ft | \$2.75 | \$ 308,871.81 |
| RUNWAY 9L-27R | RW 9R-27L | 6105 | L & T CR | M | Crack Sealing - AC | 3,637.10 | Ft | \$2.75 | \$ 10,002.13 |
| RUNWAY 9L-27R | RW 9R-27L | 6105 | RAVELING | L | Surface Seal | 336,879.00 | SqFt | \$0.55 | \$ 185,285.02 |
| RUNWAY 9L-27R | RW 9R-27L | 6105 | RAVELING | M | Surface Seal | 452.40 | SqFt | \$0.55 | \$ 248.81 |
| RUNWAY 9L-27R | RW 9R-27L | 6110 | DEPRESSION | L | Patching - AC Full Depth | 138.20 | SqFt | \$5.00 | \$ 691.15 |
| RUNWAY 9L-27R | RW 9R-27L | 6110 | L & T CR | L | Crack Sealing - AC | 22,277.50 | Ft | \$2.75 | \$ 61,263.06 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| RUNWAY 9L-27R | RW 9R-27L | 6110 | L & T CR | M | Crack Sealing - AC | 194.80 | Ft | \$2.75 | \$ 535.56 |
| RUNWAY 9L-27R | RW 9R-27L | 6110 | RAVELING | M | Surface Seal | 608.00 | SqFt | \$0.55 | \$ 334.40 |
| RUNWAY 9L-27R | RW 9R-27L | 6110 | RAVELING | L | Surface Seal | 28,523.80 | SqFt | \$0.55 | \$ 15,688.19 |
| RUNWAY 9L-27R | RW 9R-27L | 6110 | WEATHERING | M | Surface Seal | 874.00 | SqFt | \$0.55 | \$ 480.70 |
| TAXIWAY ALPHA | TW A | 105 | L & T CR | L | Crack Sealing - AC | 1,465.60 | Ft | \$2.75 | \$ 4,030.26 |
| TAXIWAY ALPHA | TW A | 120 | BLEEDING | N | Patching - AC Partial Depth | 57.00 | SqFt | \$3.00 | \$ 170.99 |
| TAXIWAY ALPHA | TW A | 120 | BLOCK CR | L | Surface Seal | 5,471.80 | SqFt | \$0.55 | \$ 3,009.53 |
| TAXIWAY ALPHA | TW A | 120 | L & T CR | L | Crack Sealing - AC | 29,761.80 | Ft | \$2.75 | \$ 81,844.94 |
| TAXIWAY ALPHA | TW A | 120 | RAVELING | L | Surface Seal | 3,086.70 | SqFt | \$0.55 | \$ 1,697.68 |
| TAXIWAY ALPHA | TW A | 130 | L & T CR | L | Crack Sealing - AC | 56.30 | Ft | \$2.75 | \$ 154.95 |
| TAXIWAY ALPHA | TW A | 130 | RAVELING | L | Surface Seal | 611.70 | SqFt | \$0.55 | \$ 336.46 |
| TAXIWAY ALPHA | TW A | 132 | BLEEDING | N | Patching - AC Partial Depth | 1.60 | SqFt | \$3.00 | \$ 4.88 |
| TAXIWAY ALPHA | TW A | 132 | L & T CR | L | Crack Sealing - AC | 65.00 | Ft | \$2.75 | \$ 178.79 |
| TAXIAWY BRAVO | TW B | 1105 | L & T CR | L | Crack Sealing - AC | 860.80 | Ft | \$2.75 | \$ 2,367.27 |
| TAXIAWY BRAVO | TW B | 1105 | RAVELING | L | Surface Seal | 10,740.10 | SqFt | \$0.55 | \$ 5,907.10 |
| TAXIWAY CHARLIE | TW C | 305 | BLEEDING | N | Patching - AC Partial Depth | 111.10 | SqFt | \$3.00 | \$ 333.31 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-----------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY CHARLIE | TW C | 305 | L & T CR | L | Crack Sealing - AC | 548.40 | Ft | \$2.75 | \$ 1,507.97 |
| TAXIWAY CHARLIE | TW C | 305 | RAVELING | L | Surface Seal | 458.80 | SqFt | \$0.55 | \$ 252.32 |
| TAXIWAY CHARLIE | TW C | 310 | BLEEDING | N | Patching - AC Partial Depth | 3.40 | SqFt | \$3.00 | \$ 10.13 |
| TAXIWAY CHARLIE | TW C | 310 | L & T CR | L | Crack Sealing - AC | 418.50 | Ft | \$2.75 | \$ 1,150.95 |
| TAXIWAY CHARLIE | TW C | 310 | OIL SPILLAGE | N | Surface Seal | 21.20 | SqFt | \$0.55 | \$ 11.66 |
| TAXIWAY CHARLIE | TW C | 310 | RAVELING | L | Surface Seal | 651.40 | SqFt | \$0.55 | \$ 358.28 |
| TAXIWAY CHARLIE | TW C | 315 | BLEEDING | N | Patching - AC Partial Depth | 52.00 | SqFt | \$3.00 | \$ 155.95 |
| TAXIWAY CHARLIE | TW C | 315 | DEPRESSION | L | Patching - AC Full Depth | 185.60 | SqFt | \$5.00 | \$ 928.09 |
| TAXIWAY CHARLIE | TW C | 315 | L & T CR | L | Crack Sealing - AC | 2,483.90 | Ft | \$2.75 | \$ 6,830.83 |
| TAXIWAY CHARLIE | TW C | 315 | RAVELING | L | Surface Seal | 1,264.40 | SqFt | \$0.55 | \$ 695.45 |
| TAXIWAY CHARLIE | TW C | 320 | L & T CR | L | Crack Sealing - AC | 53.40 | Ft | \$2.75 | \$ 146.80 |
| TAXIWAY CHARLIE | TW C | 330 | L & T CR | L | Crack Sealing - AC | 5,740.00 | Ft | \$2.75 | \$ 15,785.01 |
| TAXIWAY CHARLIE | TW C | 330 | RAVELING | L | Surface Seal | 11,066.60 | SqFt | \$0.55 | \$ 6,086.67 |
| TAXIWAY CHARLIE | TW C | 340 | L & T CR | L | Crack Sealing - AC | 170.10 | Ft | \$2.75 | \$ 467.89 |
| TAXIWAY CHARLIE | TW C | 340 | RAVELING | L | Surface Seal | 1,031.80 | SqFt | \$0.55 | \$ 567.51 |
| TAXIWAY CHARLIE | TW C | 350 | L & T CR | L | Crack Sealing - AC | 1,511.00 | Ft | \$2.75 | \$ 4,155.15 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|-------------------------------------|------------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY CHARLIE | TW C | 350 | RAVELING | L | Surface Seal | 2,792.40 | SqFt | \$0.55 | \$ 1,535.84 |
| CONNECTOR TAXIWAY TO TERMINAL APRON | TW CONN AP | 2110 | L & T CR | L | Crack Sealing - AC | 138.90 | Ft | \$2.75 | \$ 381.92 |
| CONNECTOR TAXIWAY TO TERMINAL APRON | TW CONN AP | 2110 | RAVELING | L | Surface Seal | 97.20 | SqFt | \$0.55 | \$ 53.47 |
| TAXIWAY DELTA | TW D | 405 | L & T CR | L | Crack Sealing - AC | 8.50 | Ft | \$2.75 | \$ 23.27 |
| TAXIWAY DELTA | TW D | 405 | RAVELING | L | Surface Seal | 228.40 | SqFt | \$0.55 | \$ 125.63 |
| TAXIWAY DELTA | TW D | 408 | BLEEDING | N | Patching - AC Partial Depth | 10.30 | SqFt | \$3.00 | \$ 31.02 |
| TAXIWAY DELTA | TW D | 408 | L & T CR | L | Crack Sealing - AC | 189.60 | Ft | \$2.75 | \$ 521.35 |
| TAXIWAY DELTA | TW D | 408 | RAVELING | L | Surface Seal | 86.20 | SqFt | \$0.55 | \$ 47.40 |
| TAXIWAY DELTA | TW D | 410 | BLEEDING | N | Patching - AC Partial Depth | 24.80 | SqFt | \$3.00 | \$ 74.34 |
| TAXIWAY DELTA | TW D | 410 | L & T CR | L | Crack Sealing - AC | 8,241.80 | Ft | \$2.75 | \$ 22,664.95 |
| TAXIWAY DELTA | TW D | 410 | RAVELING | M | Surface Seal | 6,938.40 | SqFt | \$0.55 | \$ 3,816.14 |
| TAXIWAY DELTA | TW D | 410 | RAVELING | L | Surface Seal | 57,667.90 | SqFt | \$0.55 | \$ 31,717.61 |
| TAXIWAY DELTA | TW D | 412 | BLEEDING | N | Patching - AC Partial Depth | 4.00 | SqFt | \$3.00 | \$ 12.00 |
| TAXIWAY DELTA | TW D | 412 | L & T CR | M | Crack Sealing - AC | 3.00 | Ft | \$2.75 | \$ 8.25 |
| TAXIWAY DELTA | TW D | 412 | L & T CR | L | Crack Sealing - AC | 490.00 | Ft | \$2.75 | \$ 1,347.60 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|---------------|-----------|------------|----------------------|-------------------|--------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY DELTA | TW D | 412 | RAVELING | L | Surface Seal | 3,598.30 | SqFt | \$0.55 | \$ 1,979.07 |
| TAXIWAY DELTA | TW D | 415 | L & T CR | L | Crack Sealing - AC | 254.30 | Ft | \$2.75 | \$ 699.32 |
| TAXIWAY DELTA | TW D | 415 | RAVELING | L | Surface Seal | 1,439.40 | SqFt | \$0.55 | \$ 791.69 |
| TAXIWAY DELTA | TW D | 416 | L & T CR | L | Crack Sealing - AC | 283.70 | Ft | \$2.75 | \$ 780.16 |
| TAXIWAY DELTA | TW D | 416 | RAVELING | L | Surface Seal | 167.80 | SqFt | \$0.55 | \$ 92.30 |
| TAXIWAY DELTA | TW D | 455 | L & T CR | L | Crack Sealing - AC | 204.10 | Ft | \$2.75 | \$ 561.17 |
| TAXIAWY KILO | TW K | 1110 | L & T CR | L | Crack Sealing - AC | 36.00 | Ft | \$2.75 | \$ 99.00 |
| TAXIAWY KILO | TW K | 1110 | RAVELING | L | Surface Seal | 260.00 | SqFt | \$0.55 | \$ 143.01 |
| TAXIAWY KILO | TW K | 1115 | DEPRESSION | L | Patching - AC Full Depth | 394.40 | SqFt | \$5.00 | \$ 1,972.21 |
| TAXIAWY KILO | TW K | 1115 | L & T CR | L | Crack Sealing - AC | 5,448.00 | Ft | \$2.75 | \$ 14,982.11 |
| TAXIAWY KILO | TW K | 1115 | RAVELING | L | Surface Seal | 3,237.00 | SqFt | \$0.55 | \$ 1,780.35 |
| TAXIAWY KILO | TW K | 1116 | L & T CR | L | Crack Sealing - AC | 256.90 | Ft | \$2.75 | \$ 706.42 |
| TAXIAWY KILO | TW K | 1116 | RAVELING | L | Surface Seal | 256.90 | SqFt | \$0.55 | \$ 141.29 |
| TAXIAWY KILO | TW K | 1120 | L & T CR | L | Crack Sealing - AC | 329.80 | Ft | \$2.75 | \$ 906.89 |
| TAXIAWY KILO | TW K | 1120 | PATCHING | M | Patching - AC Full Depth | 34.90 | SqFt | \$5.00 | \$ 174.62 |
| TAXIAWY KILO | TW K | 1120 | RAVELING | L | Surface Seal | 2,283.10 | SqFt | \$0.55 | \$ 1,255.71 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|--------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| TAXIAWY KILO | TW K | 1125 | L & T CR | L | Crack Sealing - AC | 4,041.30 | Ft | \$2.75 | \$ 11,113.53 |
| TAXIAWY KILO | TW K | 1125 | RAVELING | L | Surface Seal | 1,654.30 | SqFt | \$0.55 | \$ 909.89 |
| TAXIAWY KILO | TW K | 1130 | L & T CR | L | Crack Sealing - AC | 1,545.90 | Ft | \$2.75 | \$ 4,251.10 |
| TAXIAWY KILO | TW K | 1130 | RAVELING | L | Surface Seal | 2,777.60 | SqFt | \$0.55 | \$ 1,527.70 |
| TAXIAWY KILO | TW K | 1132 | L & T CR | L | Crack Sealing - AC | 22.90 | Ft | \$2.75 | \$ 63.02 |
| TAXIAWY KILO | TW K | 1135 | BLEEDING | N | Patching - AC Partial Depth | 31.50 | SqFt | \$3.00 | \$ 94.36 |
| TAXIAWY KILO | TW K | 1135 | DEPRESSION | L | Patching - AC Full Depth | 108.60 | SqFt | \$5.00 | \$ 543.15 |
| TAXIAWY KILO | TW K | 1135 | L & T CR | L | Crack Sealing - AC | 2,956.60 | Ft | \$2.75 | \$ 8,130.62 |
| TAXIAWY KILO | TW K | 1135 | L & T CR | M | Crack Sealing - AC | 196.60 | Ft | \$2.75 | \$ 540.60 |
| TAXIAWY KILO | TW K | 1135 | RAVELING | L | Surface Seal | 3,341.90 | SqFt | \$0.55 | \$ 1,838.06 |
| TAXIAWY LIMA | TW L | 1204 | DEPRESSION | L | Patching - AC Full Depth | 84.90 | SqFt | \$5.00 | \$ 424.69 |
| TAXIAWY LIMA | TW L | 1204 | L & T CR | L | Crack Sealing - AC | 230.00 | Ft | \$2.75 | \$ 632.47 |
| TAXIAWY LIMA | TW L | 1204 | RAVELING | L | Surface Seal | 1,046.10 | SqFt | \$0.55 | \$ 575.35 |
| TAXIAWY LIMA | TW L | 1210 | L & T CR | L | Crack Sealing - AC | 1,119.00 | Ft | \$2.75 | \$ 3,077.23 |
| TAXIAWY LIMA | TW L | 1210 | RAVELING | L | Surface Seal | 1,715.80 | SqFt | \$0.55 | \$ 943.69 |
| TAXIWAY MIKE | TW M | 1305 | L & T CR | M | Crack Sealing - AC | 150.00 | Ft | \$2.75 | \$ 412.55 |



Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|------------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY MIKE | TW M | 1305 | L & T CR | L | Crack Sealing - AC | 272.00 | Ft | \$2.75 | \$ 748.09 |
| TAXIWAY MIKE | TW M | 1305 | RAVELING | L | Surface Seal | 432.10 | SqFt | \$0.55 | \$ 237.63 |
| TAXIWAY MIKE | TW M | 1312 | L & T CR | L | Crack Sealing - AC | 753.50 | Ft | \$2.75 | \$ 2,072.13 |
| TAXIWAY MIKE | TW M | 1312 | RAVELING | L | Surface Seal | 190.60 | SqFt | \$0.55 | \$ 104.84 |
| TAXIWAY MIKE | TW M | 1315 | L & T CR | L | Crack Sealing - AC | 1,695.80 | Ft | \$2.75 | \$ 4,663.35 |
| TAXIWAY MIKE | TW M | 1315 | RAVELING | L | Surface Seal | 1,187.00 | SqFt | \$0.55 | \$ 652.88 |
| TAXIWAY MIKE | TW M | 1320 | L & T CR | L | Crack Sealing - AC | 171.70 | Ft | \$2.75 | \$ 472.20 |
| TAXIWAY MIKE | TW M | 1320 | PATCHING | M | Patching - AC Full Depth | 15.30 | SqFt | \$5.00 | \$ 76.73 |
| TAXIWAY MIKE | TW M | 1320 | RAVELING | L | Surface Seal | 137.00 | SqFt | \$0.55 | \$ 75.35 |
| TAXIWAY MIKE | TW M | 1325 | L & T CR | L | Crack Sealing - AC | 18.30 | Ft | \$2.75 | \$ 50.22 |
| TAXIWAY MIKE | TW M | 1325 | RAVELING | L | Surface Seal | 32.90 | SqFt | \$0.55 | \$ 18.08 |
| TAXIWAY NOVEMBER | TW N | 1404 | L & T CR | L | Crack Sealing - AC | 50.80 | Ft | \$2.75 | \$ 139.69 |
| TAXIWAY NOVEMBER | TW N | 1404 | RAVELING | L | Surface Seal | 1,029.60 | SqFt | \$0.55 | \$ 566.28 |
| TAXIWAY QUEBEC | TW Q | 1705 | BLEEDING | N | Patching - AC Partial Depth | 29.50 | SqFt | \$3.00 | \$ 88.44 |
| TAXIWAY QUEBEC | TW Q | 1705 | L & T CR | L | Crack Sealing - AC | 4,339.20 | Ft | \$2.75 | \$ 11,932.91 |
| TAXIWAY QUEBEC | TW Q | 1705 | RAVELING | L | Surface Seal | 4,598.70 | SqFt | \$0.55 | \$ 2,529.28 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|----------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|-------------|
| TAXIWAY QUEBEC | TW Q | 1710 | BLEEDING | N | Patching - AC Partial Depth | 7.60 | SqFt | \$3.00 | \$ 22.85 |
| TAXIWAY QUEBEC | TW Q | 1710 | L & T CR | L | Crack Sealing - AC | 196.50 | Ft | \$2.75 | \$ 540.31 |
| TAXIWAY QUEBEC | TW Q | 1710 | RAVELING | L | Surface Seal | 604.70 | SqFt | \$0.55 | \$ 332.57 |
| TAXIWAY QUEBEC | TW Q | 1720 | L & T CR | L | Crack Sealing - AC | 800.60 | Ft | \$2.75 | \$ 2,201.61 |
| TAXIWAY QUEBEC | TW Q | 1722 | L & T CR | L | Crack Sealing - AC | 94.70 | Ft | \$2.75 | \$ 260.56 |
| TAXIWAY QUEBEC | TW Q | 1722 | RAVELING | L | Surface Seal | 733.90 | SqFt | \$0.55 | \$ 403.63 |
| TAXIWAY QUEBEC | TW Q | 1725 | L & T CR | L | Crack Sealing - AC | 3,155.50 | Ft | \$2.75 | \$ 8,677.68 |
| TAXIWAY QUEBEC | TW Q | 1725 | RAVELING | L | Surface Seal | 926.80 | SqFt | \$0.55 | \$ 509.72 |
| TAXIWAY QUEBEC | TW Q | 1732 | L & T CR | L | Crack Sealing - AC | 7.00 | Ft | \$2.75 | \$ 19.25 |
| TAXIWAY QUEBEC | TW Q | 1735 | L & T CR | L | Crack Sealing - AC | 86.00 | Ft | \$2.75 | \$ 236.63 |
| TAXIWAY QUEBEC | TW Q | 1735 | RAVELING | L | Surface Seal | 51.60 | SqFt | \$0.55 | \$ 28.40 |
| TAXIWAY ROMEO | TW R | 1805 | L & T CR | L | Crack Sealing - AC | 332.40 | Ft | \$2.75 | \$ 914.19 |
| TAXIWAY ROMEO | TW R | 1807 | L & T CR | L | Crack Sealing - AC | 1,155.50 | Ft | \$2.75 | \$ 3,177.75 |
| TAXIWAY ROMEO | TW R | 1807 | RAVELING | L | Surface Seal | 1,228.30 | SqFt | \$0.55 | \$ 675.59 |
| TAXIWAY ROMEO | TW R | 1810 | L & T CR | L | Crack Sealing - AC | 712.90 | Ft | \$2.75 | \$ 1,960.44 |
| TAXIWAY ROMEO | TW R | 1810 | RAVELING | L | Surface Seal | 131.20 | SqFt | \$0.55 | \$ 72.16 |





Pavement Evaluation Report - Melbourne International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|----------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY ROMEO | TW R | 1820 | BLEEDING | N | Patching - AC Partial Depth | 1.20 | SqFt | \$3.00 | \$ 3.51 |
| TAXIWAY ROMEO | TW R | 1820 | L & T CR | L | Crack Sealing - AC | 613.30 | Ft | \$2.75 | \$ 1,686.59 |
| TAXIWAY ROMEO | TW R | 1820 | RAVELING | L | Surface Seal | 234.10 | SqFt | \$0.55 | \$ 128.75 |
| TAXIWAY SIERRA | TW S | 505 | L & T CR | L | Crack Sealing - AC | 4,995.30 | Ft | \$2.75 | \$ 13,737.11 |
| TAXIWAY SIERRA | TW S | 505 | PATCHING | M | Patching - AC Full Depth | 37.80 | SqFt | \$5.00 | \$ 188.77 |
| TAXIWAY SIERRA | TW S | 505 | RAVELING | L | Surface Seal | 54,726.10 | SqFt | \$0.55 | \$ 30,099.60 |
| TAXIWAY SIERRA | TW S | 510 | BLOCK CR | L | Surface Seal | 865.70 | SqFt | \$0.55 | \$ 476.16 |
| TAXIWAY SIERRA | TW S | 510 | L & T CR | L | Crack Sealing - AC | 1,000.80 | Ft | \$2.75 | \$ 2,752.19 |
| TAXIWAY SIERRA | TW S | 510 | L & T CR | M | Crack Sealing - AC | 929.80 | Ft | \$2.75 | \$ 2,556.96 |
| TAXIWAY SIERRA | TW S | 510 | RAVELING | L | Surface Seal | 18,613.40 | SqFt | \$0.55 | \$ 10,237.47 |
| TAXIWAY SIERRA | TW S | 515 | RAVELING | L | Surface Seal | 1,267.10 | SqFt | \$0.55 | \$ 696.92 |
| TAXIWAY S1 | TW S1 | 520 | L & T CR | L | Crack Sealing - AC | 25.10 | Ft | \$2.75 | \$ 69.04 |
| TAXIWAY S1 | TW S1 | 520 | RAVELING | L | Surface Seal | 4,393.20 | SqFt | \$0.55 | \$ 2,416.28 |
| TAXIAWY TANGO | TW T | 2005 | L & T CR | L | Crack Sealing - AC | 1,558.00 | Ft | \$2.75 | \$ 4,284.39 |
| TAXIAWY TANGO | TW T | 2015 | L & T CR | L | Crack Sealing - AC | 1,308.90 | Ft | \$2.75 | \$ 3,599.45 |
| TAXIAWY TANGO | TW T | 2015 | RAVELING | L | Surface Seal | 1,580.70 | SqFt | \$0.55 | \$ 869.41 |

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description | Work Quantity | Work Unit | Unit Cost | Work Cost |
|----------------|-----------|------------|----------------------|-------------------|--------------------------|---------------|-----------|-----------|-----------------|
| TAXIWAY VICTOR | TW V | 1602 | DEPRESSION | L | Patching - AC Full Depth | 430.20 | SqFt | \$5.00 | \$ 2,151.02 |
| TAXIWAY VICTOR | TW V | 1602 | L & T CR | L | Crack Sealing - AC | 376.60 | Ft | \$2.75 | \$ 1,035.68 |
| TAXIWAY VICTOR | TW V | 1602 | RAVELING | L | Surface Seal | 288.90 | SqFt | \$0.55 | \$ 158.90 |
| TAXIWAY VICTOR | TW V | 1605 | L & T CR | L | Crack Sealing - AC | 836.70 | Ft | \$2.75 | \$ 2,301.01 |
| TAXIAWY V1 | TW V1 | 710 | L & T CR | L | Crack Sealing - AC | 87.20 | Ft | \$2.75 | \$ 239.92 |
| TAXIAWY V1 | TW V1 | 710 | RAVELING | L | Surface Seal | 58.20 | SqFt | \$0.55 | \$ 31.99 |
| Total = | | | | | | | | | \$ 8,762,320.12 |

APPENDIX F

- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION
EXHIBIT
- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION
TABLE



| | | | | | | | | |
|--|---|---|---|--|--|--|--|---|
| SECTION: 410 FY 2015 TW D: 410 MILL AND OVERLAY \$1.87M | SECTION: 412 FY 2015 TW D: 412 MILL AND OVERLAY \$0.08M | SECTION: 505 FY 2015 TW S: 505 MILL AND OVERLAY \$0.34M | SECTION: 510 FY 2015 TW S: 510 MILL AND OVERLAY \$1.23M | SECTION: 4110 FY 2015 AP N GA: 4110 MILL AND OVERLAY \$2.29M | SECTION: 4312 FY 2015 AP W: 4312 RECONSTRUCTION \$0.20M | SECTION: 4320 FY 2015 AP W: 4320 MILL AND OVERLAY \$1.37M | SECTION: 4325 FY 2015 AP W: 4325 RECONSTRUCTION \$1.04M | SECTION: 4330 FY 2015 AP W: 4330 RECONSTRUCTION \$1.20M |
| SECTION: 4406 FY 2015 AP E: 4406 MILL AND OVERLAY \$0.24M | SECTION: 4410 FY 2015 AP E: 4410 MILL AND OVERLAY \$2.08M | SECTION: 6105 FY 2015 RW 9R-27L: 6105 MILL AND OVERLAY \$17.10M | SECTION: 6210 FY 2015 RW 9L-27R: 6210 MILL AND OVERLAY \$10.17M | SECTION: 6310 FY 2015 RW 5-23: 6310 MILL AND OVERLAY \$0.12M | SECTION: 6315 FY 2015 RW 5-23: 6315 MILL AND OVERLAY \$0.12M | SECTION: 4105 FY 2017 AP N GA: 4105 MILL AND OVERLAY \$1.83M | SECTION: 4120 FY 2018 AP N GA: 4120 MILL AND OVERLAY \$1.89M | SECTION: 4315 FY 2018 AP W: 4315 MILL AND OVERLAY \$1.13M |
| SECTION: 6305 FY 2018 RW 5-23: 6305 MILL AND OVERLAY \$4.16M | SECTION: 1807 FY 2019 TW R: 1807 MILL AND OVERLAY \$0.29M | SECTION: 3310 FY 2019 RW 27L THR: 3310 MILL AND OVERLAY \$1.38M | SECTION: 1120 FY 2020 TW K: 1120 MILL AND OVERLAY \$0.21M | SECTION: 1305 FY 2020 TW M: 1305 MILL AND OVERLAY \$0.18M | SECTION: 1312 FY 2020 TW M: 1312 MILL AND OVERLAY \$0.34M | SECTION: 1602 FY 2020 TW V: 1602 MILL AND OVERLAY \$0.22M | SECTION: 6110 FY 2020 RW 9R-27L: 6110 MILL AND OVERLAY \$9.91M | SECTION: 315 FY 2021 TW C: 315 MILL AND OVERLAY \$1.36M |
| SECTION: 4515 FY 2021 AP CENTER: 4515 MILL AND OVERLAY \$0.06M | SECTION: 1722 FY 2022 TW Q: 1722 MILL AND OVERLAY \$0.18M | SECTION: 3315 FY 2022 RW 27L THR: 3315 MILL AND OVERLAY \$0.75M | SECTION: 4130 FY 2022 AP N GA: 4130 MILL AND OVERLAY \$2.16M | SECTION: 6205 FY 2022 RW 9L-27R: 6205 MILL AND OVERLAY \$6.26M | SECTION: 330 FY 2023 TW C: 330 MILL AND OVERLAY \$2.47M | SECTION: 520 FY 2023 TW S: 520 MILL AND OVERLAY \$0.33M | SECTION: 1210 FY 2023 TW L: 1210 MILL AND OVERLAY \$0.78M | SECTION: 1204 FY 2024 TW L: 1204 MILL AND OVERLAY \$0.25M |
| SECTION: 1315 FY 2024 TW M: 1315 MILL AND OVERLAY \$1.19M | SECTION: 1320 FY 2024 TW M: 1320 MILL AND OVERLAY \$0.13M | SECTION: 1705 FY 2024 TW Q: 1705 MILL AND OVERLAY \$2.16M | SECTION: 4710 FY 2024 AP SW: 4710 MILL AND OVERLAY \$5.09M | SECTION: 4720 FY 2024 AP SW: 4720 MILL AND OVERLAY \$3.45M | SECTION: 4998 FY 2024 PCC RESTORATION \$1.14M | | | |

- LEGEND**
- RW 13-31 — TYPICAL RUNWAY BRANCH ID
 - TW A — TYPICAL TAXIWAY BRANCH ID
 - AP S — TYPICAL APRON BRANCH ID

PROGRAM YEAR

| | |
|------|------|
| 2015 | 2020 |
| 2016 | 2021 |
| 2017 | 2022 |
| 2018 | 2023 |
| 2019 | 2024 |

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAYMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER | DATE | REVISIONS |
|-----------|------|------------|
| | | |
| DESIGNED: | KHA | DRAWN: KHA |
| CHECKED: | KHA | DATE: 2015 |



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT
MELBOURNE INTERNATIONAL AIRPORT
BREVARD COUNTY, FLORIDA
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE

Table F-1: Airfield Pavement 10-Year Major Rehabilitation Table

| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|------|------------|------------|------------------|----------------|------------------|---------------|
| 2015 | AP E | 4406 | \$ 235,672.00 | 50 | Mill and Overlay | 100 |
| 2015 | AP E | 4410 | \$ 2,083,391.00 | 45 | Mill and Overlay | 100 |
| 2015 | AP N GA | 4110 | \$ 2,287,267.00 | 59 | Mill and Overlay | 100 |
| 2015 | AP W | 4312 | \$ 196,581.00 | 13 | Reconstruction | 100 |
| 2015 | AP W | 4320 | \$ 1,367,100.00 | 57 | Mill and Overlay | 100 |
| 2015 | AP W | 4325 | \$ 1,043,050.00 | 0 | Reconstruction | 100 |
| 2015 | AP W | 4330 | \$ 1,199,128.00 | 5 | Reconstruction | 100 |
| 2015 | RW 5-23 | 6310 | \$ 124,200.00 | 57 | Mill and Overlay | 100 |
| 2015 | RW 5-23 | 6315 | \$ 124,200.00 | 54 | Mill and Overlay | 100 |
| 2015 | RW 9L-27R | 6210 | \$ 10,172,369.00 | 61 | Mill and Overlay | 100 |
| 2015 | RW 9R-27L | 6105 | \$ 17,100,001.00 | 58 | Mill and Overlay | 100 |
| 2015 | TW D | 410 | \$ 1,872,918.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW D | 412 | \$ 80,970.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW S | 505 | \$ 336,600.00 | 63 | Mill and Overlay | 100 |
| 2015 | TW S | 510 | \$ 1,231,722.00 | 55 | Mill and Overlay | 100 |
| 2017 | AP N GA | 4105 | \$ 1,829,416.00 | 63 | Mill and Overlay | 100 |
| 2018 | AP N GA | 4120 | \$ 1,890,970.00 | 64 | Mill and Overlay | 100 |
| 2018 | AP W | 4315 | \$ 1,128,494.00 | 64 | Mill and Overlay | 100 |
| 2018 | RW 5-23 | 6305 | \$ 4,156,013.00 | 65 | Mill and Overlay | 100 |
| 2019 | RW 27L THR | 3310 | \$ 1,379,000.00 | 65 | Mill and Overlay | 100 |
| 2019 | TW R | 1807 | \$ 285,964.00 | 65 | Mill and Overlay | 100 |
| 2020 | RW 9R-27L | 6110 | \$ 9,911,794.00 | 65 | Mill and Overlay | 100 |
| 2020 | TW K | 1120 | \$ 207,133.00 | 65 | Mill and Overlay | 100 |
| 2020 | TW M | 1305 | \$ 179,977.00 | 65 | Mill and Overlay | 100 |
| 2020 | TW M | 1312 | \$ 342,308.00 | 64 | Mill and Overlay | 100 |
| 2020 | TW V | 1602 | \$ 216,977.00 | 65 | Mill and Overlay | 100 |
| 2021 | AP CENTER | 4515 | \$ 61,083.00 | 64 | Mill and Overlay | 100 |
| 2021 | TW C | 315 | \$ 1,358,836.00 | 65 | Mill and Overlay | 100 |
| 2022 | AP N GA | 4130 | \$ 2,164,738.00 | 64 | Mill and Overlay | 100 |
| 2022 | RW 27L THR | 3315 | \$ 753,436.00 | 63 | Mill and Overlay | 100 |
| 2022 | RW 9L-27R | 6205 | \$ 6,255,366.00 | 63 | Mill and Overlay | 100 |
| 2022 | TW Q | 1722 | \$ 175,351.00 | 65 | Mill and Overlay | 100 |
| 2023 | TW C | 330 | \$ 2,466,386.00 | 64 | Mill and Overlay | 100 |
| 2023 | TW L | 1210 | \$ 782,464.00 | 65 | Mill and Overlay | 100 |
| 2023 | TW S1 | 520 | \$ 333,910.00 | 65 | Mill and Overlay | 100 |
| 2024 | AP CENTER | 4998 | \$ 1,144,821.00 | 64 | PCC Restoration | 100 |



| Year | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2024 | AP SW | 4710 | \$ 5,090,052.00 | 65 | Mill and Overlay | 100 |
| 2024 | AP SW | 4720 | \$ 3,445,807.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW L | 1204 | \$ 245,507.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW M | 1315 | \$ 1,194,799.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW M | 1320 | \$ 129,778.00 | 65 | Mill and Overlay | 100 |
| 2024 | TW Q | 1705 | \$ 2,158,966.00 | 65 | Mill and Overlay | 100 |
| Total = | | | \$ 88,744,515.00 | | | |

* Costs are adjusted for inflation AT 3%

APPENDIX G

● PHOTOGRAPHS



Runway 9R-27L, Section 6105, Sample Unit 326 – Low Severity (41) Alligator Cracking, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, Low Severity (57) Weathering



Runway 9R-27L, Section 6105, Sample Unit 382 – Low and Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (56) Swelling, Low Severity (57) Weathering



Runway 9L-27R, Section 6210, Sample Unit 377 – Low and Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (56) Swelling, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 5-23, Section 6310, Sample Unit 108 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering




Taxiway Alpha, Section 120, Sample Unit 209 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, Low Severity (57) Weathering



Taxiway Charlie, Section 305, Sample Unit 310 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, Low Severity (57) Weathering



Taxiway Delta, Section 410, Sample Unit 102 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling



Taxiway Kilo, Section 1116, Sample Unit 125 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, Low Severity (57) Weathering



Taxiway Sierra, Section 510, Sample Unit 120 – Low and Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



East Apron, Section 4410, Sample Unit 801 – Medium Severity (43) Block Cracking, High Severity (43) Block Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling



Terminal Apron, Section 4210, Sample Unit 250 – (42) Bleeding, Low Severity (57) Weathering



Terminal Apron, Section 4205, Sample Unit 202 – Low Severity (74) Joint Spalling



Center Apron, Section 4998, Sample Unit 103 – Low Severity (70) Scaling, Map Cracking, Crazing, Low Severity (74) Joint Spalling



West Apron, Section 4325, Sample Unit 301 – Medium Severity (65) Joint Seal Damage, Medium Severity (72) Shattered Slab



Taxiway Alpha, Section 120- (55) Slippage Cracking (*Not an inspected sample.)

APPENDIX H

- DISTRESS DATA – RE-INSPECTION REPORT

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP CENTER Name: CENTER APRON Use: APRON Area: 130,581.19SqFt

Section: 4510 of 4 From: - To: - Last Const.: 01/01/2009
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 23,048.00SqFt Length: 230.00Ft Width: 100.00Ft
Slabs: 58 Slab Width: 20.00Ft Slab Length: 20.00Ft Joint Length: 1,970.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 91

Inspection Comments:

Sample Number: 100 Type: R Area: 20.00Slabs PCI = 91

Sample Comments:

| | | | | | |
|----|--------------------|---|-------|-------|-----------|
| 70 | SCALING/CRAZING | L | 13.00 | Slabs | Comments: |
| 73 | SHRINKAGE CRACKING | N | 1.00 | Slabs | Comments: |
| 74 | JOINT SPALLING | L | 1.00 | Slabs | Comments: |
| 75 | CORNER SPALLING | L | 1.00 | Slabs | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP CENTER Name: CENTER APRON Use: APRON Area: 130,581.19SqFt

Section: 4515 of 4 From: - To: - Last Const.: 01/01/2009

Surface: APC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 2,842.00SqFt Length: 290.00Ft Width: 10.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 1 Surveyed: 1

Conditions: PCI : 70

Inspection Comments:

Sample Number: 406 Type: R Area: 2,842.00SqFt PCI = 70

Sample Comments:

47 JOINT REFLECTION CRACKING L 174.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 168.00 Ft Comments:

52 RAVELING L 50.00 SqFt Comments:

57 WEATHERING L 2,792.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP CENTER Name: CENTER APRON Use: APRON Area: 130,581.19SqFt

Section: 4520 of 4 From: - To: - Last Const.: 01/01/2009

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 55,946.19SqFt Length: 559.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 9 Surveyed: 1

Conditions: PCI : 92

Inspection Comments:

Sample Number: 305 Type: R Area: 6,250.00SqFt PCI = 92

Sample Comments:

52 RAVELING L 25.00 SqFt Comments:

57 WEATHERING L 6,225.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP CENTER Name: CENTER APRON Use: APRON Area: 130,581.19SqFt

Section: 4998 of 4 From: - To: - Last Const.: 01/01/1995
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 48,745.00SqFt Length: 250.00Ft Width: 200.00Ft
Slabs: 137 Slab Width: 20.00Ft Slab Length: 20.00Ft Joint Length: 4,550.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 2

Conditions: PCI : 74

Inspection Comments:

Sample Number: 103 Type: R Area: 16.00Slabs PCI = 62

Sample Comments:

| | | | | | |
|----|--------------------|---|-------|-------|-----------|
| 63 | LINEAR CRACKING | L | 4.00 | Slabs | Comments: |
| 70 | SCALING/CRAZING | L | 9.00 | Slabs | Comments: |
| 74 | JOINT SPALLING | L | 10.00 | Slabs | Comments: |
| 73 | SHRINKAGE CRACKING | N | 3.00 | Slabs | Comments: |
| 66 | SMALL PATCH | L | 1.00 | Slabs | Comments: |
| 74 | JOINT SPALLING | M | 4.00 | Slabs | Comments: |

Sample Number: 205 Type: R Area: 16.00Slabs PCI = 86

Sample Comments:

| | | | | | |
|----|-----------------|---|-------|-------|-----------|
| 70 | SCALING/CRAZING | L | 16.00 | Slabs | Comments: |
| 75 | CORNER SPALLING | L | 2.00 | Slabs | Comments: |
| 74 | JOINT SPALLING | L | 1.00 | Slabs | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP E Name: EAST APRON Use: APRON Area: 656,761.58SqFt

Section: 4404 of 7 From: - To: - Last Const.: 01/01/2004

Surface: APC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 76,125.00SqFt Length: 380.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 12 Surveyed: 2

Conditions: PCI : 88

Inspection Comments:

Sample Number: 208 Type: R Area: 6,250.00SqFt PCI = 87

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 275.00 Ft Comments:

Sample Number: 213 Type: R Area: 6,250.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 197.00 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP E Name: EAST APRON Use: APRON Area: 656,761.58SqFt

Section: 4406 of 7 From: - To: - Last Const.: 01/01/1998

Surface: APC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 12,949.00SqFt Length: 380.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 50

Inspection Comments:

Sample Number: 810 Type: R Area: 6,736.00SqFt PCI = 50

Sample Comments:

| | | | | | |
|----|----------------|---|----------|------|-----------|
| 52 | RAVELING | L | 500.00 | SqFt | Comments: |
| 43 | BLOCK CRACKING | L | 6,486.00 | SqFt | Comments: |
| 43 | BLOCK CRACKING | M | 250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 6,236.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP E Name: EAST APRON Use: APRON Area: 656,761.58SqFt

Section: 4407 of 7 From: - To: - Last Const.: 01/01/2004

Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 69,764.58SqFt Length: 600.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 18 Surveyed: 3

Conditions: PCI : 85

Inspection Comments:

Sample Number: 103 Type: R Area: 3,750.00SqFt PCI = 85

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 98.00 Ft Comments:

56 SWELLING L 6.00 SqFt Comments:

57 WEATHERING L 3,750.00 SqFt Comments:

Sample Number: 106 Type: R Area: 3,750.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 42.00 Ft Comments:

56 SWELLING L 6.00 SqFt Comments:

57 WEATHERING L 3,750.00 SqFt Comments:

Sample Number: 116 Type: R Area: 3,750.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 45.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 100.00 Ft Comments:

56 SWELLING L 2.00 SqFt Comments:

57 WEATHERING L 3,650.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP E Name: EAST APRON Use: APRON Area: 656,761.58SqFt

Section: 4410 of 7 From: - To: - Last Const.: 12/25/1999
Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P
Area: 100,915.00SqFt Length: 700.00Ft Width: 300.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 22 Surveyed: 3

Conditions: PCI : 45

Inspection Comments:

Sample Number: 302 Type: R Area: 5,000.00SqFt PCI = 61

Sample Comments:

| | | | | |
|-------------------------------------|---|----------|------|-----------|
| 52 RAVELING | M | 250.00 | SqFt | Comments: |
| 49 OIL SPILLAGE | N | 34.00 | SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 205.00 | Ft | Comments: |
| 52 RAVELING | L | 4,750.00 | SqFt | Comments: |

Sample Number: 401 Type: R Area: 3,862.00SqFt PCI = 55

Sample Comments:

| | | | | |
|-------------------------------------|---|----------|------|-----------|
| 52 RAVELING | M | 100.00 | SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 174.00 | Ft | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 44.00 | Ft | Comments: |
| 49 OIL SPILLAGE | N | 34.00 | SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 54.00 | Ft | Comments: |
| 49 OIL SPILLAGE | N | 9.00 | SqFt | Comments: |
| 52 RAVELING | M | 12.00 | SqFt | Comments: |
| 43 BLOCK CRACKING | M | 10.00 | SqFt | Comments: |
| 52 RAVELING | M | 16.00 | SqFt | Comments: |
| 52 RAVELING | L | 3,734.00 | SqFt | Comments: |

Sample Number: 801 Type: R Area: 4,605.00SqFt PCI = 18

Sample Comments:

| | | | | |
|-------------------|---|----------|------|-----------|
| 52 RAVELING | M | 500.00 | SqFt | Comments: |
| 43 BLOCK CRACKING | M | 3,154.00 | SqFt | Comments: |
| 43 BLOCK CRACKING | H | 1,352.00 | SqFt | Comments: |
| 52 RAVELING | L | 4,006.00 | SqFt | Comments: |
| 50 PATCHING | L | 63.00 | SqFt | Comments: |
| 50 PATCHING | L | 36.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP E Name: EAST APRON Use: APRON Area: 656,761.58SqFt

Section: 4415 of 7 From: - To: - Last Const.: 01/01/2014
Surface: APC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P
Area: 14,188.00SqFt Length: 380.00Ft Width: 200.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

NOTE: * Pre-Construction PCI *****

Last Insp. Date: 01/09/2012 Total Samples: 16 Surveyed: 4

Conditions: PCI : 43

Inspection Comments:

Sample Number: 200 Type: R Area: 5,000.00SqFt PCI = 39

Sample Comments:

| | | | | |
|-------------------|---|----------|------|-----------|
| 43 BLOCK CRACKING | M | 1,199.99 | SqFt | Comments: |
| 43 BLOCK CRACKING | L | 3,799.97 | SqFt | Comments: |
| 45 DEPRESSION | L | 16.00 | SqFt | Comments: |
| 52 RAVELING | M | 196.00 | SqFt | Comments: |
| 52 RAVELING | L | 4,803.96 | SqFt | Comments: |

Sample Number: 203 Type: R Area: 3,750.00SqFt PCI = 46

Sample Comments:

| | | | | |
|-------------------|---|----------|------|-----------|
| 43 BLOCK CRACKING | L | 3,749.97 | SqFt | Comments: |
| 52 RAVELING | H | 6.00 | SqFt | Comments: |
| 52 RAVELING | M | 344.00 | SqFt | Comments: |
| 52 RAVELING | L | 3,399.97 | SqFt | Comments: |

Sample Number: 303 Type: R Area: 3,750.00SqFt PCI = 43

Sample Comments:

| | | | | |
|-------------------------------------|---|----------|------|-----------|
| 43 BLOCK CRACKING | L | 2,324.98 | SqFt | Comments: |
| 43 BLOCK CRACKING | M | 375.00 | SqFt | Comments: |
| 52 RAVELING | M | 125.00 | SqFt | Comments: |
| 52 RAVELING | L | 3,624.97 | SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 64.02 | Ft | Comments: |

Sample Number: 402 Type: R Area: 5,000.00SqFt PCI = 43

Sample Comments:

| | | | | |
|-------------------------------------|---|----------|------|-----------|
| 52 RAVELING | M | 45.00 | SqFt | Comments: |
| 52 RAVELING | L | 4,954.96 | SqFt | Comments: |
| 43 BLOCK CRACKING | M | 125.00 | SqFt | Comments: |
| 43 BLOCK CRACKING | L | 2,099.98 | SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 456.12 | Ft | Comments: |
| 49 OIL SPILLAGE | N | 75.00 | SqFt | Comments: |

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | | | | |
|-------------------|----------------|---------|---------------------------------|--------|----------|-------|----------------|--------------|------------|
| Network: | MLB | Name: | MELBOURNE INTERNATIONAL AIRPORT | | | | | | |
| Branch: | AP E | Name: | EAST APRON | Use: | APRON | Area: | 656,761.58SqFt | | |
| Section: | 4420 | of | 7 | From: | - | To: | - | Last Const.: | 01/01/2014 |
| Surface: | AC | Family: | FDOT-SAPMP-PR-AP-AC | | | | Zone: | Category: | Rank: P |
| Area: | 129,420.00SqFt | Length: | 800.00Ft | Width: | 200.00Ft | | | | |
| Shoulder: | Street Type: | Grade: | 0.00 | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | |
| Last Insp. Date: | Total Samples: | 0 | Surveyed: | 0 | | | | | |
| Conditions: | | | | | | | | | |

| | | | |
|------------------------|-------|-------|------|
| Sample Number: | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> | | | |

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | | | | |
|-------------------|----------------|-------------|---------------------------------|----------|--------------|---------|----------|----------------|-------------|
| Network: | MLB | Name: | MELBOURNE INTERNATIONAL AIRPORT | | | | | | |
| Branch: | AP E | Name: | EAST APRON | | Use: | APRON | Area: | 656,761.58SqFt | |
| Section: | 4425 | of | 7 | From: | - | To: | - | Last Const.: | 01/01/2014 |
| Surface: | PCC | Family: | FDOT-SAPMP-PR-AP-PCC | | | | Zone: | Category: | Rank: P |
| Area: | 253,400.00SqFt | | Length: | 650.00Ft | | Width: | 550.00Ft | | |
| Slabs: | 894 | Slab Width: | 20.00Ft | | Slab Length: | 20.00Ft | | Joint Length: | 34,550.00Ft |
| Shoulder: | Street Type: | | Grade: | 0.00 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | |

| | | | | |
|------------------|----------------|---|-----------|---|
| Last Insp. Date: | Total Samples: | 0 | Surveyed: | 0 |
| Conditions: | | | | |

| | | | |
|------------------------|-------|-------|------|
| Sample Number: | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> | | | |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4105 of 9 From: - To: - Last Const.: 01/01/1986

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 95,800.00SqFt Length: 479.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 18 Surveyed: 3

Conditions: PCI : 67

Inspection Comments:

Sample Number: 101 Type: R Area: 5,000.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 97.00 Ft Comments:

52 RAVELING L 5,000.00 SqFt Comments:

Sample Number: 107 Type: R Area: 5,000.00SqFt PCI = 62

Sample Comments:

52 RAVELING M 500.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 230.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 11.00 Ft Comments:

45 DEPRESSION L 20.00 SqFt Comments:

52 RAVELING L 4,500.00 SqFt Comments:

Sample Number: 205 Type: R Area: 5,000.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 31.00 Ft Comments:

52 RAVELING L 5,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4110 of 9 From: - To: - Last Const.: 01/01/1982

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 127,070.36SqFt Length: 480.00Ft Width: 250.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 26 Surveyed: 3

Conditions: PCI : 59

Inspection Comments:

Sample Number: 301 Type: R Area: 5,000.00SqFt PCI = 60

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 900.00 Ft Comments:

52 RAVELING L 5,000.00 SqFt Comments:

45 DEPRESSION L 8.00 SqFt Comments:

49 OIL SPILLAGE N 6.00 SqFt Comments:

Sample Number: 403 Type: R Area: 5,000.00SqFt PCI = 50

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 260.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 5,000.00 Ft Comments:

Sample Number: 407 Type: R Area: 5,000.00SqFt PCI = 67

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 104.00 Ft Comments:

49 OIL SPILLAGE N 1.00 SqFt Comments:

52 RAVELING L 5,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4115 of 9 From: - To: - Last Const.: 01/01/2003
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 162,260.00SqFt Length: 760.00Ft Width: 213.50Ft
Slabs: 380 Slab Width: 21.35Ft Slab Length: 20.00Ft Joint Length: 14,739.50Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 20 Surveyed: 3

Conditions: PCI : 96

Inspection Comments:

Sample Number: 251 Type: R Area: 20.00Slabs PCI = 93

Sample Comments:

73 SHRINKAGE CRACKING N 6.00 Slabs Comments:

70 SCALING/CRAZING L 9.00 Slabs Comments:

Sample Number: 450 Type: R Area: 20.00Slabs PCI = 97

Sample Comments:

70 SCALING/CRAZING L 6.00 Slabs Comments:

Sample Number: 551 Type: R Area: 20.00Slabs PCI = 96

Sample Comments:

70 SCALING/CRAZING L 4.00 Slabs Comments:

73 SHRINKAGE CRACKING N 1.00 Slabs Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4120 of 9 From: - To: - Last Const.: 01/01/2003

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 96,139.17SqFt Length: 950.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 22 Surveyed: 3

Conditions: PCI : 69

Inspection Comments:

Sample Number: 153 Type: R Area: 3,750.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 135.00 Ft Comments:

56 SWELLING L 39.00 SqFt Comments:

52 RAVELING L 100.00 SqFt Comments:

57 WEATHERING L 3,650.00 SqFt Comments:

Sample Number: 402 Type: R Area: 4,575.00SqFt PCI = 55

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 818.00 Ft Comments:

56 SWELLING L 100.00 SqFt Comments:

52 RAVELING L 137.00 SqFt Comments:

52 RAVELING M 4.00 SqFt Comments:

Sample Number: 702 Type: R Area: 4,575.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 146.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 45.00 Ft Comments:

52 RAVELING L 100.00 SqFt Comments:

57 WEATHERING L 4,475.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4125 of 9 From: - To: - Last Const.: 01/01/2003
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 51,200.00SqFt Length: 642.00Ft Width: 160.00Ft
Slabs: 257 Slab Width: 20.00Ft Slab Length: 20.00Ft Joint Length: 9,470.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 10 Surveyed: 2

Conditions: PCI : 91

Inspection Comments:

Sample Number: 302 Type: R Area: 12.00Slabs PCI = 94

Sample Comments:

70 SCALING/CRAZING L 6.00 Slabs Comments:
73 SHRINKAGE CRACKING N 2.00 Slabs Comments:

Sample Number: 404 Type: R Area: 12.00Slabs PCI = 89

Sample Comments:

70 SCALING/CRAZING L 4.00 Slabs Comments:
73 SHRINKAGE CRACKING N 2.00 Slabs Comments:
75 CORNER SPALLING L 1.00 Slabs Comments:
74 JOINT SPALLING L 1.00 Slabs Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4130 of 9 From: - To: - Last Const.: 01/01/2006

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 97,785.00SqFt Length: 650.00Ft Width: 170.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 15 Surveyed: 2

Conditions: PCI : 76

Inspection Comments:

Sample Number: 102 Type: R Area: 6,943.00SqFt PCI = 73

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 181.00 | Ft | Comments: |
| 56 | SWELLING | L | 52.00 | SqFt | Comments: |
| 50 | PATCHING | L | 120.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 20.00 | SqFt | Comments: |
| 52 | RAVELING | L | 136.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 6,687.00 | SqFt | Comments: |

Sample Number: 108 Type: R Area: 7,106.00SqFt PCI = 79

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 33.00 | Ft | Comments: |
| 50 | PATCHING | M | 11.00 | SqFt | Comments: |
| 42 | BLEEDING | N | 25.00 | SqFt | Comments: |
| 52 | RAVELING | L | 50.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 7,045.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4135 of 9 From: - To: - Last Const.: 01/01/2010

Surface: APC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 22,180.00SqFt Length: 350.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 6 Surveyed: 1

Conditions: PCI : 86

Inspection Comments:

Sample Number: 211 Type: R Area: 3,550.00SqFt PCI = 86

Sample Comments:

47 JOINT REFLECTION CRACKING L 81.00 Ft Comments:

47 JOINT REFLECTION CRACKING L 50.00 Ft Comments:

57 WEATHERING L 3,550.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP N GA Name: NORTH GA APRON Use: APRON Area: 684,005.53SqFt

Section: 4140 of 9 From: - To: - Last Const.: 01/01/2010

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 23,711.00SqFt Length: 185.00Ft Width: 125.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 94

Inspection Comments:

Sample Number: 717 Type: R Area: 5,750.00SqFt PCI = 94

Sample Comments:

57 WEATHERING L 5,750.00 SqFt Comments:

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | | | | |
|---|--------------|---------|---------------------------------|--------|---------|-------|-------|----------------|------------|
| Network: | MLB | Name: | MELBOURNE INTERNATIONAL AIRPORT | | | | | | |
| Branch: | AP N GA | Name: | NORTH GA APRON | | Use: | APRON | Area: | 684,005.53SqFt | |
| Section: | 4145 | of | 9 | From: | - | To: | - | Last Const.: | 01/01/2013 |
| Surface: | AAC | Family: | FDOT-SAPMP-PR-AP-AAC | | | | Zone: | Category: | Rank: P |
| Area: | 7,860.00SqFt | Length: | 150.00Ft | Width: | 50.00Ft | | | | |
| Shoulder: | Street Type: | Grade: | 0.00 | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | |
| Last Insp. Date: Total Samples: 0 Surveyed: 0 | | | | | | | | | |
| Conditions: | | | | | | | | | |

| | | | |
|------------------------|-------|-------|------|
| Sample Number: | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> | | | |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP SW Name: APRON SOUTHWEST Use: APRON Area: 465,323.84SqFt

Section: 4710 of 3 From: - To: - Last Const.: 01/01/2008
Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P
Area: 216,727.84SqFt Length: 500.00Ft Width: 420.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 42 Surveyed: 5

Conditions: PCI : 80

Inspection Comments:

Sample Number: 253 Type: R Area: 5,000.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 246.00 Ft Comments:
52 RAVELING L 150.00 SqFt Comments:
57 WEATHERING L 4,850.00 SqFt Comments:

Sample Number: 301 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 285.00 Ft Comments:
45 DEPRESSION L 8.00 SqFt Comments:
52 RAVELING L 150.00 SqFt Comments:
57 WEATHERING L 4,850.00 SqFt Comments:

Sample Number: 502 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 31.00 Ft Comments:
52 RAVELING L 150.00 SqFt Comments:
57 WEATHERING L 4,850.00 SqFt Comments:
49 OIL SPILLAGE N 4.00 SqFt Comments:

Sample Number: 703 Type: R Area: 5,000.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 49.00 Ft Comments:
52 RAVELING L 150.00 SqFt Comments:
57 WEATHERING L 4,850.00 SqFt Comments:

Sample Number: 750 Type: R Area: 6,726.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 122.00 Ft Comments:
52 RAVELING L 336.00 SqFt Comments:
57 WEATHERING L 6,390.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP SW Name: APRON SOUTHWEST Use: APRON Area: 465,323.84SqFt

Section: 4720 of 3 From: - To: - Last Const.: 01/01/2008

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 146,718.00SqFt Length: 1,500.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 31 Surveyed: 4

Conditions: PCI : 80

Inspection Comments:

Sample Number: 204 Type: R Area: 6,600.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 239.00 Ft Comments:

52 RAVELING L 204.00 SqFt Comments:

52 RAVELING L 128.00 SqFt Comments:

57 WEATHERING L 6,268.00 SqFt Comments:

Sample Number: 208 Type: R Area: 3,835.00SqFt PCI = 85

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 56.00 Ft Comments:

52 RAVELING L 76.00 SqFt Comments:

57 WEATHERING L 3,759.00 SqFt Comments:

Sample Number: 255 Type: R Area: 5,000.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 140.00 Ft Comments:

52 RAVELING L 150.00 SqFt Comments:

57 WEATHERING L 4,850.00 SqFt Comments:

Sample Number: 802 Type: R Area: 5,900.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 210.00 Ft Comments:

42 BLEEDING N 9.00 SqFt Comments:

52 RAVELING L 177.00 SqFt Comments:

57 WEATHERING L 5,723.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP SW Name: APRON SOUTHWEST Use: APRON Area: 465,323.84SqFt

Section: 4730 of 3 From: - To: - Last Const.: 01/01/2013

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 101,878.00SqFt Length: 1,200.00Ft Width: 85.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: Total Samples: 0 Surveyed: 0

Conditions:

Sample Number: Type: Area: 0.00

<NO VALID INSPECTIONS>

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 634,993.36SqFt

Section: 4205 of 2 From: - To: - Last Const.: 01/01/1989
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 290,074.00SqFt Length: 580.00Ft Width: 500.00Ft
Slabs: 727 Slab Width: 20.00Ft Slab Length: 20.00Ft Joint Length: 27,920.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 37 Surveyed: 4

Conditions: PCI : 80

Inspection Comments:

Sample Number: 202 Type: R Area: 20.00Slabs PCI = 75

Sample Comments:

| | | | |
|------------------------|---|-------------|-----------|
| 71 FAULTING | L | 2.00 Slabs | Comments: |
| 70 SCALING/CRAZING | L | 17.00 Slabs | Comments: |
| 67 LARGE PATCH/UTILITY | L | 1.00 Slabs | Comments: |
| 73 SHRINKAGE CRACKING | N | 2.00 Slabs | Comments: |
| 66 SMALL PATCH | L | 1.00 Slabs | Comments: |
| 74 JOINT SPALLING | L | 6.00 Slabs | Comments: |

Sample Number: 404 Type: R Area: 24.00Slabs PCI = 87

Sample Comments:

| | | | |
|-----------------------|---|------------|-----------|
| 66 SMALL PATCH | L | 1.00 Slabs | Comments: |
| 73 SHRINKAGE CRACKING | N | 3.00 Slabs | Comments: |
| 70 SCALING/CRAZING | L | 8.00 Slabs | Comments: |
| 71 FAULTING | L | 2.00 Slabs | Comments: |

Sample Number: 500 Type: R Area: 20.00Slabs PCI = 73

Sample Comments:

| | | | |
|-----------------------|---|-------------|-----------|
| 71 FAULTING | L | 1.00 Slabs | Comments: |
| 70 SCALING/CRAZING | L | 20.00 Slabs | Comments: |
| 74 JOINT SPALLING | L | 5.00 Slabs | Comments: |
| 73 SHRINKAGE CRACKING | N | 1.00 Slabs | Comments: |
| 62 CORNER BREAK | L | 1.00 Slabs | Comments: |
| 63 LINEAR CRACKING | L | 1.00 Slabs | Comments: |

Sample Number: 803 Type: R Area: 13.00Slabs PCI = 83

Sample Comments:

| | | | |
|-----------------------|---|-------------|-----------|
| 74 JOINT SPALLING | L | 3.00 Slabs | Comments: |
| 70 SCALING/CRAZING | L | 12.00 Slabs | Comments: |
| 73 SHRINKAGE CRACKING | N | 2.00 Slabs | Comments: |
| 75 CORNER SPALLING | L | 1.00 Slabs | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 634,993.36SqFt

Section: 4210 of 2 From: - To: - Last Const.: 01/01/2009
Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P
Area: 344,919.36SqFt Length: 1,700.00Ft Width: 200.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 74 Surveyed: 8

Conditions: PCI : 82

Inspection Comments:

Sample Number: 152 Type: R Area: 5,000.00SqFt PCI = 89

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 24.00 Ft Comments:
56 SWELLING L 4.00 SqFt Comments:
42 BLEEDING N 0.25 SqFt Comments:
57 WEATHERING L 5,000.00 SqFt Comments:

Sample Number: 156 Type: R Area: 5,000.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 115.00 Ft Comments:
56 SWELLING L 37.00 SqFt Comments:
57 WEATHERING L 5,000.00 SqFt Comments:
42 BLEEDING N 1.00 SqFt Comments:

Sample Number: 250 Type: R Area: 5,000.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 141.00 Ft Comments:
56 SWELLING L 87.00 SqFt Comments:
42 BLEEDING N 42.00 SqFt Comments:
57 WEATHERING L 5,000.00 SqFt Comments:

Sample Number: 401 Type: R Area: 5,500.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 145.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 38.00 Ft Comments:
42 BLEEDING N 3.00 SqFt Comments:
56 SWELLING L 15.00 SqFt Comments:
57 WEATHERING L 5,500.00 SqFt Comments:

Sample Number: 458 Type: R Area: 3,176.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 16.00 Ft Comments:
56 SWELLING L 10.00 SqFt Comments:
57 WEATHERING L 3,176.00 SqFt Comments:

Sample Number: 599 Type: R Area: 5,000.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 175.00 Ft Comments:
42 BLEEDING N 4.00 SqFt Comments:
56 SWELLING L 45.00 SqFt Comments:
57 WEATHERING L 5,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 657 | Type: | R | Area: | 5,000.00SqFt | PCI = 85 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 88.00 | Ft | Comments: | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 32.00 | Ft | Comments: | |
| 57 | WEATHERING | L | 4,500.00 | SqFt | Comments: | |
| 56 | SWELLING | L | 6.00 | SqFt | Comments: | |

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 800 | Type: | R | Area: | 5,000.00SqFt | PCI = 75 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 114.00 | Ft | Comments: | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 31.00 | Ft | Comments: | |
| 45 | DEPRESSION | L | 48.00 | SqFt | Comments: | |
| 45 | DEPRESSION | L | 85.00 | SqFt | Comments: | |
| 57 | WEATHERING | L | 5,000.00 | SqFt | Comments: | |
| 42 | BLEEDING | N | 1.00 | SqFt | Comments: | |
| 56 | SWELLING | L | 13.00 | SqFt | Comments: | |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 320,867.31SqFt

Section: 4305 of 7 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 34,199.31SqFt Length: 170.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 6 Surveyed: 1

Conditions: PCI : 94

Inspection Comments:

Sample Number: 901 Type: R Area: 4,854.00SqFt PCI = 94

Sample Comments:

57 WEATHERING L 4,854.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 320,867.31SqFt

Section: 4310 of 7 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 47,311.00SqFt Length: 235.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 9 Surveyed: 1

Conditions: PCI : 91

Inspection Comments:

Sample Number: 501 Type: R Area: 5,600.00SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 10.00 Ft Comments:

57 WEATHERING L 5,600.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 320,867.31SqFt

Section: 4312 of 7 From: - To: - Last Const.: 12/25/1994
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 8,547.00SqFt Length: 260.00Ft Width: 32.00Ft
Slabs: 12 Slab Width: 22.50Ft Slab Length: 32.00Ft Joint Length: 337.78Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 1 Surveyed: 1

Conditions: PCI : 13

Inspection Comments:

Sample Number: 351 Type: R Area: 12.00Slabs PCI = 13

Sample Comments:

| | | | |
|-----------------------|---|-------------|-----------|
| 72 SHATTERED SLAB | L | 10.00 Slabs | Comments: |
| 72 SHATTERED SLAB | M | 2.00 Slabs | Comments: |
| 70 SCALING/CRAZING | L | 8.00 Slabs | Comments: |
| 73 SHRINKAGE CRACKING | N | 10.00 Slabs | Comments: |
| 74 JOINT SPALLING | L | 1.00 Slabs | Comments: |
| 75 CORNER SPALLING | L | 1.00 Slabs | Comments: |
| 65 JOINT SEAL DAMAGE | L | 12.00 Slabs | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 320,867.31SqFt

Section: 4315 of 7 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 57,374.00SqFt Length: 325.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 11 Surveyed: 2

Conditions: PCI : 67

Inspection Comments:

Sample Number: 100 Type: R Area: 6,000.00SqFt PCI = 41

Sample Comments:

| | | | |
|-------------------|---|---------------|-----------|
| 45 DEPRESSION | L | 90.00 SqFt | Comments: |
| 45 DEPRESSION | L | 36.00 SqFt | Comments: |
| 45 DEPRESSION | L | 66.00 SqFt | Comments: |
| 45 DEPRESSION | L | 30.00 SqFt | Comments: |
| 45 DEPRESSION | L | 144.00 SqFt | Comments: |
| 50 PATCHING | M | 1.00 SqFt | Comments: |
| 52 RAVELING | H | 11.00 SqFt | Comments: |
| 43 BLOCK CRACKING | L | 5,999.00 SqFt | Comments: |
| 52 RAVELING | L | 5,988.00 SqFt | Comments: |

Sample Number: 301 Type: R Area: 5,800.00SqFt PCI = 93

Sample Comments:

| | | | |
|---------------|---|---------------|-----------|
| 45 DEPRESSION | L | 11.00 SqFt | Comments: |
| 57 WEATHERING | L | 5,800.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 320,867.31SqFt

Section: 4320 of 7 From: - To: - Last Const.: 01/01/1979

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 75,950.00SqFt Length: 400.00Ft Width: 150.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 15 Surveyed: 2

Conditions: PCI : 57

Inspection Comments:

Sample Number: 204 Type: R Area: 5,423.00SqFt PCI = 60

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 855.00 Ft Comments:

52 RAVELING L 1,085.00 SqFt Comments:

57 WEATHERING M 4,228.00 SqFt Comments:

Sample Number: 301 Type: R Area: 4,666.00SqFt PCI = 52

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 733.00 Ft Comments:

43 BLOCK CRACKING L 160.00 SqFt Comments:

45 DEPRESSION L 24.00 SqFt Comments:

52 RAVELING L 933.00 SqFt Comments:

57 WEATHERING M 3,733.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 320,867.31SqFt

Section: 4325 of 7 From: - To: - Last Const.: 01/01/1942
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 45,350.00SqFt Length: 250.75Ft Width: 200.00Ft
Slabs: 143 Slab Width: 20.00Ft Slab Length: 20.00Ft Joint Length: 4,564.25Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 7 Surveyed: 2

Conditions: PCI : 0

Inspection Comments:

Sample Number: 200 Type: R Area: 12.00Slabs PCI = 0

Sample Comments:

| | | | |
|----------------------|---|-------------|-----------|
| 65 JOINT SEAL DAMAGE | M | 12.00 Slabs | Comments: |
| 72 SHATTERED SLAB | H | 4.00 Slabs | Comments: |
| 72 SHATTERED SLAB | M | 6.00 Slabs | Comments: |
| 63 LINEAR CRACKING | M | 2.00 Slabs | Comments: |
| 75 CORNER SPALLING | L | 1.00 Slabs | Comments: |

Sample Number: 301 Type: R Area: 20.00Slabs PCI = 0

Sample Comments:

| | | | |
|----------------------|---|-------------|-----------|
| 65 JOINT SEAL DAMAGE | M | 20.00 Slabs | Comments: |
| 72 SHATTERED SLAB | M | 18.00 Slabs | Comments: |
| 72 SHATTERED SLAB | H | 2.00 Slabs | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: AP W Name: WEST APRON Use: APRON Area: 320,867.31SqFt

Section: 4330 of 7 From: - To: - Last Const.: 01/01/1942
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P
Area: 52,136.00SqFt Length: 280.00Ft Width: 300.00Ft
Slabs: 212 Slab Width: 20.00Ft Slab Length: 40.00Ft Joint Length: 5,720.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 2

Conditions: PCI : 5

Inspection Comments:

Sample Number: 204 Type: R Area: 16.00Slabs PCI = 10

Sample Comments:

| | | | |
|-----------------------|---|-------------|-----------|
| 72 SHATTERED SLAB | H | 1.00 Slabs | Comments: |
| 71 FAULTING | L | 2.00 Slabs | Comments: |
| 65 JOINT SEAL DAMAGE | H | 16.00 Slabs | Comments: |
| 72 SHATTERED SLAB | M | 4.00 Slabs | Comments: |
| 63 LINEAR CRACKING | M | 3.00 Slabs | Comments: |
| 63 LINEAR CRACKING | L | 4.00 Slabs | Comments: |
| 70 SCALING/CRAZING | L | 11.00 Slabs | Comments: |
| 73 SHRINKAGE CRACKING | N | 2.00 Slabs | Comments: |
| 72 SHATTERED SLAB | L | 1.00 Slabs | Comments: |

Sample Number: 303 Type: R Area: 15.00Slabs PCI = 0

Sample Comments:

| | | | |
|-----------------------|---|-------------|-----------|
| 65 JOINT SEAL DAMAGE | M | 15.00 Slabs | Comments: |
| 63 LINEAR CRACKING | M | 3.00 Slabs | Comments: |
| 73 SHRINKAGE CRACKING | N | 2.00 Slabs | Comments: |
| 72 SHATTERED SLAB | M | 9.00 Slabs | Comments: |
| 72 SHATTERED SLAB | H | 3.00 Slabs | Comments: |
| 70 SCALING/CRAZING | L | 1.00 Slabs | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 27L THR Name: THRESHOLD TO RW 27L Use: RUNWAY Area: 102,102.00SqFt

Section: 3310 of 2 From: - To: - Last Const.: 01/01/2001

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: P

Area: 68,068.00SqFt Length: 430.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 14 Surveyed: 3

Conditions: PCI : 72

Inspection Comments:

Sample Number: 492 Type: R Area: 5,000.00SqFt PCI = 70

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 389.00 Ft Comments:

52 RAVELING L 1,000.00 SqFt Comments:

57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 494 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 294.00 Ft Comments:

52 RAVELING L 1,000.00 SqFt Comments:

57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 500 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 279.00 Ft Comments:

52 RAVELING L 1,250.00 SqFt Comments:

57 WEATHERING L 3,750.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 27L THR Name: THRESHOLD TO RW 27L Use: RUNWAY Area: 102,102.00SqFt

Section: 3315 of 2 From: - To: - Last Const.: 01/01/2001

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: P

Area: 34,034.00SqFt Length: 1,361.00Ft Width: 25.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 2

Conditions: PCI : 76

Inspection Comments:

Sample Number: 300 Type: R Area: 4,517.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 23.00 Ft Comments:

57 WEATHERING L 4,517.00 SqFt Comments:

Sample Number: 700 Type: R Area: 4,517.00SqFt PCI = 63

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 442.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 5.00 Ft Comments:

52 RAVELING L 226.00 SqFt Comments:

57 WEATHERING L 4,291.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 5-23 Name: RUNWAY 5-23 Use: RUNWAY Area: 225,096.70SqFt

Section: 6305 of 3 From: - To: - Last Const.: 01/01/1992
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: S
Area: 211,296.70SqFt Length: 2,800.00Ft Width: 75.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 56 Surveyed: 12

Conditions: PCI : 69

Inspection Comments:

Sample Number: 101 Type: R Area: 3,750.00SqFt PCI = 64

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 176.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 250.00 Ft Comments:
52 RAVELING L 160.00 SqFt Comments:
52 RAVELING L 250.00 SqFt Comments:
57 WEATHERING L 3,340.00 SqFt Comments:
42 BLEEDING N 8.00 SqFt Comments:

Sample Number: 108 Type: R Area: 3,750.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 310.00 Ft Comments:
52 RAVELING L 150.00 SqFt Comments:
57 WEATHERING L 3,600.00 SqFt Comments:

Sample Number: 113 Type: R Area: 3,750.00SqFt PCI = 68

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 334.00 Ft Comments:
52 RAVELING L 188.00 SqFt Comments:
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 118 Type: R Area: 3,750.00SqFt PCI = 70

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 295.00 Ft Comments:
52 RAVELING L 188.00 SqFt Comments:
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 123 Type: R Area: 3,750.00SqFt PCI = 65

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 420.00 Ft Comments:
52 RAVELING L 113.00 SqFt Comments:
57 WEATHERING L 3,637.00 SqFt Comments:
42 BLEEDING N 0.25 SqFt Comments:

Sample Number: 128 Type: R Area: 3,750.00SqFt PCI = 70

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 288.00 Ft Comments:
52 RAVELING L 188.00 SqFt Comments:
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 134 Type: R Area: 3,750.00SqFt PCI = 67

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 393.00 Ft Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|----|----------|---|----------|------|-----------|
| 52 | RAVELING | L | 188.00 | SqFt | Comments: |
| 52 | RAVELING | L | 3,562.00 | SqFt | Comments: |

Sample Number: 140 Type: R Area: 3,750.00SqFt PCI = 71

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 266.00 | Ft | Comments: |
| 52 | RAVELING | L | 188.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,562.00 | SqFt | Comments: |

Sample Number: 144 Type: R Area: 3,750.00SqFt PCI = 69

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 320.00 | Ft | Comments: |
| 52 | RAVELING | L | 50.00 | SqFt | Comments: |
| 52 | RAVELING | L | 74.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,626.00 | SqFt | Comments: |

Sample Number: 150 Type: R Area: 3,750.00SqFt PCI = 71

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 263.00 | Ft | Comments: |
| 52 | RAVELING | L | 188.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,562.00 | SqFt | Comments: |

Sample Number: 154 Type: R Area: 3,750.00SqFt PCI = 72

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 266.00 | Ft | Comments: |
| 42 | BLEEDING | N | 1.00 | SqFt | Comments: |
| 52 | RAVELING | L | 75.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,675.00 | SqFt | Comments: |

Sample Number: 158 Type: R Area: 3,750.00SqFt PCI = 69

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 313.00 | Ft | Comments: |
| 52 | RAVELING | L | 299.00 | SqFt | Comments: |
| 52 | RAVELING | L | 231.00 | SqFt | Comments: |
| 52 | RAVELING | L | 204.00 | SqFt | Comments: |
| 52 | RAVELING | L | 65.00 | SqFt | Comments: |
| 52 | RAVELING | L | 59.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 2,892.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 5-23 Name: RUNWAY 5-23 Use: RUNWAY Area: 225,096.70SqFt

Section: 6310 of 3 From: - To: - Last Const.: 01/01/1992

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: S

Area: 6,900.00SqFt Length: 75.00Ft Width: 45.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 57

Inspection Comments:

Sample Number: 137 Type: R Area: 3,450.00SqFt PCI = 57

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 486.00 Ft | Comments: |
| 52 | RAVELING | L | 173.00 SqFt | Comments: |
| 57 | WEATHERING | L | 3,277.00 SqFt | Comments: |
| 56 | SWELLING | L | 92.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 5-23 Name: RUNWAY 5-23 Use: RUNWAY Area: 225,096.70SqFt

Section: 6315 of 3 From: - To: - Last Const.: 01/01/1992

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: S

Area: 6,900.00SqFt Length: 92.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 54

Inspection Comments:

Sample Number: 147 Type: R Area: 3,077.00SqFt PCI = 54

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 474.00 Ft Comments:

43 BLOCK CRACKING L 132.00 SqFt Comments:

56 SWELLING L 12.00 SqFt Comments:

52 RAVELING L 1,543.00 SqFt Comments:

57 WEATHERING L 2,923.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 900,197.41SqFt

Section: 6203 of 6 From: - To: - Last Const.: 01/01/2011

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: P

Area: 8,750.00SqFt Length: 350.00Ft Width: 25.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 95

Inspection Comments:

Sample Number: 100 Type: R Area: 4,375.00SqFt PCI = 95

Sample Comments:

57 WEATHERING L 1,969.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 900,197.41SqFt

Section: 6204 of 6 From: - To: - Last Const.: 01/01/2011

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: P

Area: 17,500.00SqFt Length: 175.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 90

Inspection Comments:

Sample Number: 300 Type: R Area: 5,000.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 52.00 Ft Comments:

42 BLEEDING N 1.00 SqFt Comments:

57 WEATHERING L 2,500.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 900,197.41SqFt

Section: 6205 of 6 From: - To: - Last Const.: 01/01/1991
Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: S
Area: 282,565.80SqFt Length: 11,302.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 56 Surveyed: 12

Conditions: PCI : 76

Inspection Comments:

Sample Number: 108 Type: R Area: 5,000.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 320.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 102.00 Ft Comments:
52 RAVELING L 240.00 SqFt Comments:
52 RAVELING L 200.00 SqFt Comments:
57 WEATHERING L 4,560.00 SqFt Comments:

Sample Number: 136 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 94.00 Ft Comments:
56 SWELLING L 11.00 SqFt Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 183.00 Ft Comments:
52 RAVELING L 750.00 SqFt Comments:
57 WEATHERING L 4,250.00 SqFt Comments:

Sample Number: 152 Type: R Area: 5,000.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 28.00 Ft Comments:
52 RAVELING L 250.00 SqFt Comments:
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 168 Type: R Area: 5,000.00SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 339.00 Ft Comments:
52 RAVELING L 380.00 SqFt Comments:
52 RAVELING L 240.00 SqFt Comments:
57 WEATHERING L 4,380.00 SqFt Comments:

Sample Number: 184 Type: R Area: 5,000.00SqFt PCI = 70

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 257.00 Ft Comments:
56 SWELLING L 82.00 SqFt Comments:
52 RAVELING L 250.00 SqFt Comments:
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 208 Type: R Area: 5,000.00SqFt PCI = 68

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 102.00 Ft Comments:
52 RAVELING L 4,750.00 SqFt Comments:
57 WEATHERING L 250.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 504 | Type: | R | Area: | 5,625.00SqFt | PCI = 73 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 155.00 | Ft | Comments: | |
| 50 | PATCHING | L | 12.00 | SqFt | Comments: | |
| 52 | RAVELING | L | 1,403.00 | SqFt | Comments: | |
| 57 | WEATHERING | L | 4,210.00 | SqFt | Comments: | |

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 524 | Type: | R | Area: | 5,000.00SqFt | PCI = 78 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 188.00 | Ft | Comments: | |
| 52 | RAVELING | L | 100.00 | SqFt | Comments: | |
| 52 | RAVELING | L | 245.00 | SqFt | Comments: | |
| 57 | WEATHERING | L | 4,655.00 | SqFt | Comments: | |

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 544 | Type: | R | Area: | 5,000.00SqFt | PCI = 80 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 150.00 | Ft | Comments: | |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: | |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: | |

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 564 | Type: | R | Area: | 5,000.00SqFt | PCI = 83 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 46.00 | Ft | Comments: | |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: | |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: | |

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 576 | Type: | R | Area: | 5,000.00SqFt | PCI = 84 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 33.00 | Ft | Comments: | |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: | |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: | |

| | | | | | | |
|------------------|----------------------------------|-------|----------|-------|--------------|----------|
| Sample Number: | 600 | Type: | R | Area: | 5,000.00SqFt | PCI = 77 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 200.00 | Ft | Comments: | |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: | |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: | |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 900,197.41SqFt

Section: 6210 of 6 From: - To: - Last Const.: 01/01/1991

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: S

Area: 565,131.61SqFt Length: 5,651.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 114 Surveyed: 20

Conditions: PCI : 61

Inspection Comments:

Sample Number: 307 Type: R Area: 5,000.00SqFt PCI = 56

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 520.00 Ft Comments:

41 ALLIGATOR CRACKING L 33.00 SqFt Comments:

50 PATCHING L 150.00 SqFt Comments:

52 RAVELING L 970.00 SqFt Comments:

57 WEATHERING L 3,880.00 SqFt Comments:

Sample Number: 314 Type: R Area: 5,000.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 423.00 Ft Comments:

52 RAVELING L 44.00 SqFt Comments:

52 RAVELING L 991.00 SqFt Comments:

57 WEATHERING L 3,965.00 SqFt Comments:

Sample Number: 321 Type: R Area: 5,000.00SqFt PCI = 61

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 308.00 Ft Comments:

52 RAVELING L 100.00 SqFt Comments:

50 PATCHING L 1,700.00 SqFt Comments:

52 RAVELING L 640.00 SqFt Comments:

57 WEATHERING L 1,160.00 SqFt Comments:

Sample Number: 325 Type: R Area: 5,000.00SqFt PCI = 64

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 512.00 Ft Comments:

52 RAVELING L 100.00 SqFt Comments:

56 SWELLING L 29.00 SqFt Comments:

52 RAVELING L 980.00 SqFt Comments:

57 WEATHERING L 3,920.00 SqFt Comments:

Sample Number: 328 Type: R Area: 5,000.00SqFt PCI = 64

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 526.00 Ft Comments:

56 SWELLING L 30.00 SqFt Comments:

52 RAVELING L 100.00 SqFt Comments:

52 RAVELING L 980.00 SqFt Comments:

57 WEATHERING L 3,920.00 SqFt Comments:

Sample Number: 335 Type: R Area: 5,000.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 246.00 Ft Comments:

52 RAVELING L 1,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|------------------|----------------------------------|---------|----------|--------------|-----------|
| 57 | WEATHERING | L | 4,000.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 339 | Type: R | Area: | 5,000.00SqFt | PCI = 67 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 343.00 | Ft | Comments: |
| 50 | PATCHING | M | 15.00 | SqFt | Comments: |
| 52 | RAVELING | L | 748.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,252.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 342 | Type: R | Area: | 5,000.00SqFt | PCI = 71 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 346.00 | Ft | Comments: |
| 52 | RAVELING | L | 54.00 | SqFt | Comments: |
| 52 | RAVELING | L | 336.00 | SqFt | Comments: |
| 52 | RAVELING | L | 922.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,688.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 349 | Type: R | Area: | 5,000.00SqFt | PCI = 69 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 428.00 | Ft | Comments: |
| 52 | RAVELING | L | 100.00 | SqFt | Comments: |
| 52 | RAVELING | L | 980.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,920.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 356 | Type: R | Area: | 5,000.00SqFt | PCI = 73 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 296.00 | Ft | Comments: |
| 52 | RAVELING | L | 88.00 | SqFt | Comments: |
| 52 | RAVELING | L | 982.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,930.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 363 | Type: R | Area: | 5,000.00SqFt | PCI = 56 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 931.00 | Ft | Comments: |
| 56 | SWELLING | L | 36.00 | SqFt | Comments: |
| 52 | RAVELING | L | 100.00 | SqFt | Comments: |
| 52 | RAVELING | L | 980.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,920.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 370 | Type: R | Area: | 5,000.00SqFt | PCI = 63 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 579.00 | Ft | Comments: |
| 52 | RAVELING | L | 88.00 | SqFt | Comments: |
| 52 | RAVELING | L | 491.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,421.00 | SqFt | Comments: |
| 56 | SWELLING | L | 25.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 377 | Type: R | Area: | 5,000.00SqFt | PCI = 43 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 1,068.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 50.00 | Ft | Comments: |
| 56 | SWELLING | L | 62.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 40.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,000.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,000.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 381 | Type: R | Area: | 5,000.00SqFt | PCI = 50 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 1,218.00 | Ft | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|----|------------|---|----------|------|-----------|
| 56 | SWELLING | L | 75.00 | SqFt | Comments: |
| 52 | RAVELING | L | 750.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,250.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 4.00 | SqFt | Comments: |

Sample Number: 384 Type: R Area: 5,000.00SqFt PCI = 51

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 1,115.00 | Ft | Comments: |
| 56 | SWELLING | L | 100.00 | SqFt | Comments: |
| 52 | RAVELING | L | 987.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,949.00 | SqFt | Comments: |
| 52 | RAVELING | L | 64.00 | SqFt | Comments: |

Sample Number: 391 Type: R Area: 5,000.00SqFt PCI = 64

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 447.00 | Ft | Comments: |
| 56 | SWELLING | L | 68.00 | SqFt | Comments: |
| 52 | RAVELING | L | 100.00 | SqFt | Comments: |
| 52 | RAVELING | L | 735.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,165.00 | SqFt | Comments: |

Sample Number: 395 Type: R Area: 5,000.00SqFt PCI = 60

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 607.00 | Ft | Comments: |
| 56 | SWELLING | L | 63.00 | SqFt | Comments: |
| 52 | RAVELING | L | 100.00 | SqFt | Comments: |
| 52 | RAVELING | L | 735.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,165.00 | SqFt | Comments: |

Sample Number: 398 Type: R Area: 5,000.00SqFt PCI = 55

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 526.00 | Ft | Comments: |
| 56 | SWELLING | L | 87.00 | SqFt | Comments: |
| 50 | PATCHING | L | 1,600.00 | SqFt | Comments: |
| 52 | RAVELING | L | 70.00 | SqFt | Comments: |
| 52 | RAVELING | L | 333.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 2,997.00 | SqFt | Comments: |

Sample Number: 405 Type: R Area: 5,000.00SqFt PCI = 44

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 815.00 | Ft | Comments: |
| 56 | SWELLING | L | 104.00 | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING | L | 135.00 | SqFt | Comments: |
| 50 | PATCHING | M | 1.00 | SqFt | Comments: |
| 52 | RAVELING | L | 749.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,250.00 | SqFt | Comments: |

Sample Number: 412 Type: R Area: 5,000.00SqFt PCI = 60

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 665.00 | Ft | Comments: |
| 56 | SWELLING | L | 53.00 | SqFt | Comments: |
| 52 | RAVELING | L | 54.00 | SqFt | Comments: |
| 52 | RAVELING | L | 742.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,204.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 900,197.41SqFt

Section: 6215 of 6 From: - To: - Last Const.: 01/01/2011

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: S

Area: 8,750.00SqFt Length: 350.00Ft Width: 25.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 96

Inspection Comments:

Sample Number: 616 Type: R Area: 4,375.00SqFt PCI = 96

Sample Comments:

42 BLEEDING N 2.00 SqFt Comments:

57 WEATHERING L 1,750.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9L-27R Name: RUNWAY 9L-27R Use: RUNWAY Area: 900,197.41SqFt

Section: 6220 of 6 From: - To: - Last Const.: 01/01/2011

Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: S

Area: 17,500.00SqFt Length: 175.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 91

Inspection Comments:

Sample Number: 419 Type: R Area: 5,000.00SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 16.00 Ft Comments:

57 WEATHERING L 3,750.00 SqFt Comments:

42 BLEEDING N 1.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 1,425,000.00SqFt

Section: 6105 of 2 From: - To: - Last Const.: 01/01/1998
Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: P
Area: 950,000.00SqFt Length: 9,300.00Ft Width: 100.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 190 Surveyed: 21

Conditions: PCI : 58

Inspection Comments:

Sample Number: 302 Type: R Area: 5,000.00SqFt PCI = 59

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 721.00 | Ft | Comments: |
| 45 | DEPRESSION | L | 1.00 | SqFt | Comments: |
| 56 | SWELLING | L | 27.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,000.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,000.00 | SqFt | Comments: |

Sample Number: 318 Type: R Area: 5,000.00SqFt PCI = 46

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 800.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 65.00 | Ft | Comments: |
| 56 | SWELLING | L | 73.00 | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING | L | 7.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,750.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,250.00 | SqFt | Comments: |

Sample Number: 326 Type: R Area: 5,000.00SqFt PCI = 48

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 665.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 14.00 | Ft | Comments: |
| 56 | SWELLING | L | 120.00 | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING | L | 27.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,750.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,250.00 | SqFt | Comments: |

Sample Number: 333 Type: R Area: 5,000.00SqFt PCI = 53

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 560.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 26.00 | Ft | Comments: |
| 56 | SWELLING | L | 151.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,500.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,500.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 8.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 9.00 | SqFt | Comments: |

Sample Number: 342 Type: R Area: 5,000.00SqFt PCI = 52

Sample Comments:

| | | | | | |
|----|----------------------------------|---|--------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 466.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 58.00 | Ft | Comments: |
| 50 | PATCHING | L | 2.00 | SqFt | Comments: |
| 56 | SWELLING | L | 74.00 | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING | L | 16.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|----|------------|---|----------|------|-----------|
| 52 | RAVELING | L | 1,249.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,749.00 | SqFt | Comments: |

Sample Number: 347 Type: R Area: 5,000.00SqFt PCI = 67

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 280.00 | Ft | Comments: |
| 56 | SWELLING | L | 105.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,750.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,250.00 | SqFt | Comments: |

Sample Number: 354 Type: R Area: 5,000.00SqFt PCI = 52

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 580.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 30.00 | Ft | Comments: |
| 56 | SWELLING | L | 49.00 | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING | L | 12.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,000.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,000.00 | SqFt | Comments: |

Sample Number: 361 Type: R Area: 5,000.00SqFt PCI = 68

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 378.00 | Ft | Comments: |
| 56 | SWELLING | L | 40.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,500.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,500.00 | SqFt | Comments: |

Sample Number: 368 Type: R Area: 5,000.00SqFt PCI = 63

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 398.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 20.00 | Ft | Comments: |
| 56 | SWELLING | L | 18.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,750.00 | SqFt | Comments: |

Sample Number: 375 Type: R Area: 5,000.00SqFt PCI = 62

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 435.00 | Ft | Comments: |
| 52 | RAVELING | M | 50.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,485.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,465.00 | SqFt | Comments: |
| 56 | SWELLING | L | 8.00 | SqFt | Comments: |

Sample Number: 382 Type: R Area: 5,000.00SqFt PCI = 59

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 80.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 456.00 | Ft | Comments: |
| 56 | SWELLING | L | 65.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,750.00 | SqFt | Comments: |

Sample Number: 389 Type: R Area: 5,000.00SqFt PCI = 60

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 584.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 25.00 | Ft | Comments: |
| 52 | RAVELING | L | 1,250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,750.00 | SqFt | Comments: |

Sample Number: 403 Type: R Area: 5,000.00SqFt PCI = 57

Sample Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 468.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 409.00 | Ft | Comments: |
| 56 | SWELLING | L | 40.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,500.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 2,500.00 | SqFt | Comments: |

Sample Number: 416 Type: R Area: 5,000.00SqFt PCI = 70

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 335.00 | Ft | Comments: |
| 56 | SWELLING | L | 10.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,000.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,000.00 | SqFt | Comments: |

Sample Number: 430 Type: R Area: 5,000.00SqFt PCI = 67

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 428.00 | Ft | Comments: |
| 56 | SWELLING | L | 16.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,000.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,000.00 | SqFt | Comments: |

Sample Number: 438 Type: R Area: 5,000.00SqFt PCI = 68

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 389.00 | Ft | Comments: |
| 56 | SWELLING | L | 29.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 2,750.00 | SqFt | Comments: |

Sample Number: 445 Type: R Area: 5,000.00SqFt PCI = 58

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 725.00 | Ft | Comments: |
| 56 | SWELLING | L | 54.00 | SqFt | Comments: |
| 52 | RAVELING | L | 1,750.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,250.00 | SqFt | Comments: |

Sample Number: 459 Type: R Area: 5,000.00SqFt PCI = 48

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 1,073.00 | Ft | Comments: |
| 56 | SWELLING | L | 58.00 | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING | L | 23.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 1.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,000.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,000.00 | SqFt | Comments: |

Sample Number: 473 Type: R Area: 5,000.00SqFt PCI = 53

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 657.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 34.00 | Ft | Comments: |
| 41 | ALLIGATOR CRACKING | L | 9.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,500.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 2,500.00 | SqFt | Comments: |

Sample Number: 480 Type: R Area: 5,000.00SqFt PCI = 54

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 50.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 739.00 | Ft | Comments: |
| 56 | SWELLING | L | 31.00 | SqFt | Comments: |
| 52 | RAVELING | L | 2,000.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,000.00 | SqFt | Comments: |

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | |
|------------------|----------------------------------|-------|---|-------|---------------|-----------|
| Sample Number: | 487 | Type: | R | Area: | 5,000.00SqFt | PCI = 56 |
| Sample Comments: | | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | | | L | 868.00 Ft | Comments: |
| 56 | SWELLING | | | L | 50.00 SqFt | Comments: |
| 52 | RAVELING | | | L | 1,500.00 SqFt | Comments: |
| 57 | WEATHERING | | | L | 3,500.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: RW 9R-27L Name: RUNWAY 9R-27L Use: RUNWAY Area: 1,425,000.00SqFt

Section: 6110 of 2 From: - To: - Last Const.: 01/01/1998
Surface: AAC Family: FDOT-SAPMP-PR-RW-AAC Zone: Category: Rank: P
Area: 475,000.00SqFt Length: 19,000.00Ft Width: 25.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 96 Surveyed: 20

Conditions: PCI : 74

Inspection Comments:

Sample Number: 120 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 134.00 | Ft | Comments: |
| 56 | SWELLING | L | 31.00 | SqFt | Comments: |
| 52 | RAVELING | L | 80.00 | SqFt | Comments: |
| 52 | RAVELING | L | 36.00 | SqFt | Comments: |
| 52 | RAVELING | L | 9.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,875.00 | SqFt | Comments: |

Sample Number: 160 Type: R Area: 5,000.00SqFt PCI = 76

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 182.00 | Ft | Comments: |
| 56 | SWELLING | L | 40.00 | SqFt | Comments: |
| 52 | RAVELING | L | 282.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,718.00 | SqFt | Comments: |

Sample Number: 184 Type: R Area: 5,000.00SqFt PCI = 82

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 99.00 | Ft | Comments: |
| 52 | RAVELING | L | 52.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 2.00 | SqFt | Comments: |
| 52 | RAVELING | L | 247.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,701.00 | SqFt | Comments: |

Sample Number: 200 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 212.00 | Ft | Comments: |
| 56 | SWELLING | L | 64.00 | SqFt | Comments: |
| 52 | RAVELING | L | 336.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,231.00 | SqFt | Comments: |
| 52 | RAVELING | L | 200.00 | SqFt | Comments: |
| 52 | RAVELING | L | 223.00 | SqFt | Comments: |

Sample Number: 220 Type: R Area: 5,000.00SqFt PCI = 75

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 219.00 | Ft | Comments: |
| 56 | SWELLING | L | 11.00 | SqFt | Comments: |
| 52 | RAVELING | L | 500.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,500.00 | SqFt | Comments: |

Sample Number: 240 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

| | | | | | |
|----|----------------------------------|---|--------|----|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 111.00 | Ft | Comments: |
|----|----------------------------------|---|--------|----|-----------|

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|----|------------|---|----------|------|-----------|
| 52 | RAVELING | L | 65.00 | SqFt | Comments: |
| 52 | RAVELING | L | 24.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,911.00 | SqFt | Comments: |

Sample Number: 268 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 206.00 | Ft | Comments: |
| 57 | WEATHERING | M | 184.00 | SqFt | Comments: |
| 56 | SWELLING | L | 19.00 | SqFt | Comments: |
| 52 | RAVELING | L | 240.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,576.00 | SqFt | Comments: |

Sample Number: 284 Type: R Area: 5,000.00SqFt PCI = 70

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 193.00 | Ft | Comments: |
| 56 | SWELLING | L | 12.00 | SqFt | Comments: |
| 52 | RAVELING | L | 72.00 | SqFt | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 200.00 | Ft | Comments: |
| 57 | WEATHERING | L | 4,928.00 | SqFt | Comments: |

Sample Number: 504 Type: R Area: 5,000.00SqFt PCI = 62

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 334.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 274.00 | Ft | Comments: |
| 56 | SWELLING | L | 15.00 | SqFt | Comments: |
| 56 | SWELLING | L | 17.00 | SqFt | Comments: |
| 52 | RAVELING | L | 200.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,800.00 | SqFt | Comments: |

Sample Number: 520 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 143.00 | Ft | Comments: |
| 56 | SWELLING | L | 8.00 | SqFt | Comments: |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: |

Sample Number: 544 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 47.00 | Ft | Comments: |
| 56 | SWELLING | L | 15.00 | SqFt | Comments: |
| 52 | RAVELING | L | 117.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,883.00 | SqFt | Comments: |

Sample Number: 568 Type: R Area: 5,000.00SqFt PCI = 84

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 31.00 | Ft | Comments: |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: |

Sample Number: 584 Type: R Area: 5,000.00SqFt PCI = 60

Sample Comments:

| | | | | | |
|----|----------------------------------|---|--------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 143.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 135.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 41.00 | Ft | Comments: |
| 45 | DEPRESSION | L | 18.00 | SqFt | Comments: |
| 56 | SWELLING | L | 37.00 | SqFt | Comments: |
| 52 | RAVELING | M | 128.00 | SqFt | Comments: |
| 52 | RAVELING | L | 342.00 | SqFt | Comments: |
| 52 | RAVELING | L | 233.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|------------------|----------------------------------|---------|----------|--------------|-----------|
| 57 | WEATHERING | L | 4,425.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 600 | Type: R | Area: | 5,000.00SqFt | PCI = 73 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 249.00 | Ft | Comments: |
| 52 | RAVELING | L | 487.00 | SqFt | Comments: |
| 56 | SWELLING | L | 30.00 | SqFt | Comments: |
| 52 | RAVELING | L | 128.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,385.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 620 | Type: R | Area: | 5,000.00SqFt | PCI = 70 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 305.00 | Ft | Comments: |
| 56 | SWELLING | L | 34.00 | SqFt | Comments: |
| 56 | SWELLING | L | 19.00 | SqFt | Comments: |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 624 | Type: R | Area: | 5,000.00SqFt | PCI = 83 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 37.00 | Ft | Comments: |
| 56 | SWELLING | L | 4.00 | SqFt | Comments: |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 636 | Type: R | Area: | 5,000.00SqFt | PCI = 63 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 469.00 | Ft | Comments: |
| 56 | SWELLING | L | 37.00 | SqFt | Comments: |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,748.00 | SqFt | Comments: |
| 50 | PATCHING | L | 2.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 648 | Type: R | Area: | 5,000.00SqFt | PCI = 61 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 378.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 163.00 | Ft | Comments: |
| 56 | SWELLING | L | 101.00 | SqFt | Comments: |
| 52 | RAVELING | L | 500.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,500.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 664 | Type: R | Area: | 5,000.00SqFt | PCI = 83 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 94.00 | Ft | Comments: |
| 52 | RAVELING | L | 132.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,868.00 | SqFt | Comments: |
| <hr/> | | | | | |
| Sample Number: | 684 | Type: R | Area: | 5,000.00SqFt | PCI = 70 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 332.00 | Ft | Comments: |
| 52 | RAVELING | L | 250.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 4,750.00 | SqFt | Comments: |
| 56 | SWELLING | L | 37.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 824,692.94SqFt

Section: 105 of 4 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 38,492.70SqFt Length: 400.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 1

Conditions: PCI : 78

Inspection Comments:

Sample Number: 106 Type: R Area: 5,253.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 200.00 Ft Comments:

56 SWELLING L 127.00 SqFt Comments:

57 WEATHERING L 5,253.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 824,692.94SqFt

Section: 120 of 4 From: - To: - Last Const.: 01/01/2009
Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P
Area: 691,659.95SqFt Length: 9,000.00Ft Width: 75.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 172 Surveyed: 10

Conditions: PCI : 78

Inspection Comments:

Sample Number: 101 Type: R Area: 4,500.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 272.00 Ft Comments:
56 SWELLING L 61.00 SqFt Comments:
42 BLEEDING N 1.00 SqFt Comments:
57 WEATHERING L 4,500.00 SqFt Comments:

Sample Number: 114 Type: R Area: 4,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 278.00 Ft Comments:
56 SWELLING L 36.00 SqFt Comments:
57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 138 Type: R Area: 4,000.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 107.00 Ft Comments:
56 SWELLING L 11.00 SqFt Comments:
57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 150 Type: R Area: 4,000.00SqFt PCI = 86

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 92.00 Ft Comments:
56 SWELLING L 5.00 SqFt Comments:
57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 174 Type: R Area: 4,000.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 73.00 Ft Comments:
56 SWELLING L 23.00 SqFt Comments:
57 WEATHERING L 3,920.00 SqFt Comments:
52 RAVELING L 80.00 SqFt Comments:

Sample Number: 193 Type: R Area: 3,927.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 301.00 Ft Comments:
57 WEATHERING L 3,915.00 SqFt Comments:
52 RAVELING L 12.00 SqFt Comments:

Sample Number: 209 Type: R Area: 3,750.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 128.00 Ft Comments:
56 SWELLING L 43.00 SqFt Comments:
52 RAVELING L 28.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

| | | | | | |
|------------------|----------------------------------|---------|----------|--------------|-----------|
| 57 | WEATHERING | L | 3,722.00 | SqFt | Comments: |
| | | | | | |
| Sample Number: | 230 | Type: R | Area: | 3,750.00SqFt | PCI = 78 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 149.00 | Ft | Comments: |
| 56 | SWELLING | L | 3.00 | SqFt | Comments: |
| 52 | RAVELING | L | 56.00 | SqFt | Comments: |
| 42 | BLEEDING | N | 2.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,694.00 | SqFt | Comments: |
| | | | | | |
| Sample Number: | 250 | Type: R | Area: | 3,750.00SqFt | PCI = 74 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 152.00 | Ft | Comments: |
| 43 | BLOCK CRACKING | L | 312.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,750.00 | SqFt | Comments: |
| | | | | | |
| Sample Number: | 258 | Type: R | Area: | 3,761.00SqFt | PCI = 81 |
| Sample Comments: | | | | | |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 145.00 | Ft | Comments: |
| 56 | SWELLING | L | 14.00 | SqFt | Comments: |
| 42 | BLEEDING | N | 0.25 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,761.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 824,692.94SqFt

Section: 130 of 4 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 36,221.74SqFt Length: 400.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 1

Conditions: PCI : 88

Inspection Comments:

Sample Number: 120 Type: R Area: 4,500.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 7.00 Ft Comments:

52 RAVELING L 76.00 SqFt Comments:

57 WEATHERING L 4,424.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 824,692.94SqFt

Section: 132 of 4 From: - To: - Last Const.: 01/01/2009
Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P
Area: 58,318.55SqFt Length: 600.00Ft Width: 90.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 13 Surveyed: 2

Conditions: PCI : 92

Inspection Comments:

Sample Number: 105 Type: R Area: 4,600.00SqFt PCI = 94
Sample Comments:
57 WEATHERING L 4,600.00 SqFt Comments:

Sample Number: 112 Type: R Area: 4,370.00SqFt PCI = 91
Sample Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 10.00 Ft Comments:
57 WEATHERING L 4,370.00 SqFt Comments:
42 BLEEDING N 0.25 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 101,687.15SqFt

Section: 1105 of 1 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 101,687.15SqFt Length: 1,000.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 18 Surveyed: 3

Conditions: PCI : 81

Inspection Comments:

Sample Number: 101 Type: R Area: 4,993.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 70.00 Ft Comments:

52 RAVELING L 748.00 SqFt Comments:

57 WEATHERING L 4,245.00 SqFt Comments:

Sample Number: 107 Type: R Area: 8,108.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 29.00 Ft Comments:

52 RAVELING L 811.00 SqFt Comments:

57 WEATHERING L 7,297.00 SqFt Comments:

Sample Number: 112 Type: R Area: 4,500.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 50.00 Ft Comments:

52 RAVELING L 300.00 SqFt Comments:

57 WEATHERING L 4,200.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 360,817.59SqFt

Section: 305 of 7 From: - To: - Last Const.: 01/01/2007
Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P
Area: 43,008.00SqFt Length: 800.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 2

Conditions: PCI : 84

Inspection Comments:

Sample Number: 303 Type: R Area: 5,000.00SqFt PCI = 81

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 70.00 Ft | Comments: |
| 52 | RAVELING | L | 88.00 SqFt | Comments: |
| 56 | SWELLING | L | 10.00 SqFt | Comments: |
| 57 | WEATHERING | L | 4,912.00 SqFt | Comments: |
| 42 | BLEEDING | N | 20.00 SqFt | Comments: |

Sample Number: 307 Type: R Area: 7,000.00SqFt PCI = 87

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 83.00 Ft | Comments: |
| 42 | BLEEDING | N | 11.00 SqFt | Comments: |
| 52 | RAVELING | L | 40.00 SqFt | Comments: |
| 57 | WEATHERING | L | 6,960.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 360,817.59SqFt

Section: 310 of 7 From: - To: - Last Const.: 01/01/2004

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 13,011.46SqFt Length: 250.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 77

Inspection Comments:

Sample Number: 300 Type: R Area: 3,855.00SqFt PCI = 77

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 124.00 Ft | Comments: |
| 42 | BLEEDING | N | 1.00 SqFt | Comments: |
| 52 | RAVELING | L | 193.00 SqFt | Comments: |
| 49 | OIL SPILLAGE | N | 2.00 SqFt | Comments: |
| 57 | WEATHERING | L | 3,662.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 360,817.59SqFt

Section: 315 of 7 From: - To: - Last Const.: 01/01/2004
Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P
Area: 63,222.44SqFt Length: 1,550.00Ft Width: 40.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 17 Surveyed: 3

Conditions: PCI : 71

Inspection Comments:

Sample Number: 102 Type: R Area: 3,750.00SqFt PCI = 62

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 131.00 | Ft | Comments: |
| 50 | PATCHING | L | 1,071.00 | SqFt | Comments: |
| 42 | BLEEDING | N | 5.00 | SqFt | Comments: |
| 52 | RAVELING | L | 62.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 2,617.00 | SqFt | Comments: |

Sample Number: 107 Type: R Area: 3,750.00SqFt PCI = 77

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 183.00 | Ft | Comments: |
| 42 | BLEEDING | N | 0.25 | SqFt | Comments: |
| 52 | RAVELING | L | 50.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,700.00 | SqFt | Comments: |

Sample Number: 112 Type: R Area: 3,750.00SqFt PCI = 75

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 128.00 | Ft | Comments: |
| 52 | RAVELING | L | 113.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,637.00 | SqFt | Comments: |
| 42 | BLEEDING | N | 4.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 24.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 360,817.59SqFt

Section: 320 of 7 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 41,105.00SqFt Length: 450.00Ft Width: 80.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 9 Surveyed: 1

Conditions: PCI : 91

Inspection Comments:

Sample Number: 505 Type: R Area: 3,850.00SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 5.00 Ft Comments:

57 WEATHERING L 3,850.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 360,817.59SqFt

Section: 330 of 7 From: - To: - Last Const.: 01/01/1991

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 108,166.00SqFt Length: 1,200.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 27 Surveyed: 3

Conditions: PCI : 75

Inspection Comments:

Sample Number: 106 Type: R Area: 3,750.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 129.00 Ft Comments:

56 SWELLING L 14.00 SqFt Comments:

52 RAVELING L 18.00 SqFt Comments:

52 RAVELING L 187.00 SqFt Comments:

57 WEATHERING L 3,545.00 SqFt Comments:

Sample Number: 113 Type: R Area: 3,750.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 88.00 Ft Comments:

56 SWELLING L 4.00 SqFt Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 123 Type: R Area: 3,750.00SqFt PCI = 67

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 380.00 Ft Comments:

56 SWELLING L 145.00 SqFt Comments:

52 RAVELING L 600.00 SqFt Comments:

52 RAVELING L 158.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 360,817.59SqFt

Section: 340 of 7 From: - To: - Last Const.: 01/01/2003

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 20,581.69SqFt Length: 500.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 5 Surveyed: 1

Conditions: PCI : 84

Inspection Comments:

Sample Number: 402 Type: R Area: 3,750.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 31.00 Ft Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 360,817.59SqFt

Section: 350 of 7 From: - To: - Last Const.: 01/01/2003

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 71,723.00SqFt Length: 1,075.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 19 Surveyed: 3

Conditions: PCI : 79

Inspection Comments:

Sample Number: 506 Type: R Area: 3,750.00SqFt PCI = 71

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 170.00 Ft Comments:

56 SWELLING L 160.00 SqFt Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 511 Type: R Area: 3,750.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 26.00 Ft Comments:

56 SWELLING L 14.00 SqFt Comments:

52 RAVELING L 150.00 SqFt Comments:

57 WEATHERING L 3,600.00 SqFt Comments:

Sample Number: 517 Type: R Area: 3,750.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 41.00 Ft Comments:

56 SWELLING L 20.00 SqFt Comments:

52 RAVELING L 100.00 SqFt Comments:

57 WEATHERING L 3,650.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW CONN AP Name: CONNECTOR TAXIWAY TO TERM Use: TAXIWAY Area: 8,353.54SqFt

Section: 2110 of 1 From: - To: - Last Const.: 01/01/1989

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 8,353.54SqFt Length: 100.00Ft Width: 80.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 86

Inspection Comments:

Sample Number: 100 Type: R Area: 4,812.00SqFt PCI = 86

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 80.00 Ft Comments:

52 RAVELING L 56.00 SqFt Comments:

57 WEATHERING L 4,756.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 405 of 8 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 8,073.00SqFt Length: 95.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 87

Inspection Comments:

Sample Number: 100 Type: R Area: 3,817.00SqFt PCI = 87

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 4.00 Ft Comments:

52 RAVELING L 108.00 SqFt Comments:

57 WEATHERING L 3,709.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 408 of 8 From: - To: - Last Const.: 01/01/2008

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 7,929.70SqFt Length: 190.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 84

Inspection Comments:

Sample Number: 119 Type: R Area: 4,601.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 110.00 Ft Comments:

42 BLEEDING N 6.00 SqFt Comments:

52 RAVELING L 50.00 SqFt Comments:

57 WEATHERING L 4,551.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 410 of 8 From: - To: - Last Const.: 01/01/1979
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P
Area: 104,051.00SqFt Length: 2,600.00Ft Width: 40.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 25 Surveyed: 5

Conditions: PCI : 63

Inspection Comments:

Sample Number: 102 Type: R Area: 4,003.00SqFt PCI = 62

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 458.00 Ft Comments:
52 RAVELING M 400.00 SqFt Comments:
52 RAVELING L 36.00 SqFt Comments:
57 WEATHERING L 3,567.00 SqFt Comments:

Sample Number: 107 Type: R Area: 4,992.00SqFt PCI = 58

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 128.00 Ft Comments:
52 RAVELING M 1,000.00 SqFt Comments:
52 RAVELING L 2,400.00 SqFt Comments:
57 WEATHERING L 1,592.00 SqFt Comments:
42 BLEEDING N 4.00 SqFt Comments:

Sample Number: 115 Type: R Area: 4,000.00SqFt PCI = 62

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 660.00 Ft Comments:
52 RAVELING L 3,200.00 SqFt Comments:
57 WEATHERING L 800.00 SqFt Comments:
42 BLEEDING N 1.00 SqFt Comments:

Sample Number: 123 Type: R Area: 4,000.00SqFt PCI = 68

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 289.00 Ft Comments:
52 RAVELING L 2,800.00 SqFt Comments:
57 WEATHERING L 1,200.00 SqFt Comments:

Sample Number: 129 Type: R Area: 4,000.00SqFt PCI = 68

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 128.00 Ft Comments:
52 RAVELING L 3,200.00 SqFt Comments:
57 WEATHERING L 800.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 412 of 8 From: - To: - Last Const.: 01/01/1979

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 4,498.34SqFt Length: 110.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 1 Surveyed: 1

Conditions: PCI : 63

Inspection Comments:

Sample Number: 100 Type: R Area: 4,498.00SqFt PCI = 63

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 3.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 490.00 Ft Comments:

42 BLEEDING N 4.00 SqFt Comments:

52 RAVELING L 3,598.00 SqFt Comments:

57 WEATHERING L 900.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 415 of 8 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 19,192.44SqFt Length: 450.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 5 Surveyed: 1

Conditions: PCI : 82

Inspection Comments:

Sample Number: 132 Type: R Area: 4,000.00SqFt PCI = 82

Sample Comments:

52 RAVELING L 300.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 53.00 Ft Comments:

57 WEATHERING L 3,700.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 416 of 8 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 8,422.93SqFt Length: 210.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 80

Inspection Comments:

Sample Number: 201 Type: R Area: 4,216.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 142.00 Ft Comments:

52 RAVELING L 84.00 SqFt Comments:

57 WEATHERING L 4,132.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 450 of 8 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 23,691.60SqFt Length: 370.00Ft Width: 60.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 94

Inspection Comments:

Sample Number: 102 Type: R Area: 6,000.00SqFt PCI = 94

Sample Comments:

57 WEATHERING L 6,000.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 208,561.01SqFt

Section: 455 of 8 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 32,702.00SqFt Length: 270.00Ft Width: 70.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 5 Surveyed: 2

Conditions: PCI : 90

Inspection Comments:

Sample Number: 105 Type: R Area: 6,700.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 52.00 Ft Comments:

57 WEATHERING L 3,700.00 SqFt Comments:

Sample Number: 107 Type: R Area: 5,800.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 26.00 Ft Comments:

57 WEATHERING L 5,800.00 SqFt Comments:

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | | | | |
|-------------------|----------------|---------|---------------------------------|--------|---------|-------|---------------|--------------|------------|
| Network: | MLB | Name: | MELBOURNE INTERNATIONAL AIRPORT | | | | | | |
| Branch: | TW F | Name: | TAXIWAY F | Use: | TAXIWAY | Area: | 64,381.00SqFt | | |
| Section: | 810 | of | 1 | From: | - | To: | - | Last Const.: | 01/01/2013 |
| Surface: | AC | Family: | FDOT-SAPMP-PR-TW-AC | | | | Zone: | Category: | Rank: P |
| Area: | 64,381.00SqFt | Length: | 2,225.00Ft | Width: | 25.00Ft | | | | |
| Shoulder: | Street Type: | Grade: | 0.00 | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | |
| Last Insp. Date: | Total Samples: | 0 | Surveyed: | 0 | | | | | |
| Conditions: | | | | | | | | | |

| | | | |
|------------------------|-------|-------|------|
| Sample Number: | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> | | | |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW G Name: TAXIWAY G Use: TAXIWAY Area: 40,977.00SqFt

Section: 605 of 1 From: - To: - Last Const.: 01/01/2010

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 40,977.00SqFt Length: 700.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 1

Conditions: PCI : 94

Inspection Comments:

Sample Number: 104 Type: R Area: 4,904.00SqFt PCI = 94

Sample Comments:

57 WEATHERING L 4,904.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1110 of 9 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 5,207.14SqFt Length: 120.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 1 Surveyed: 1

Conditions: PCI : 84

Inspection Comments:

Sample Number: 100 Type: R Area: 5,207.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 36.00 Ft Comments:

52 RAVELING L 260.00 SqFt Comments:

57 WEATHERING L 4,947.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1115 of 9 From: - To: - Last Const.: 01/01/2006
Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P
Area: 145,056.06SqFt Length: 3,600.00Ft Width: 40.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 35 Surveyed: 5

Conditions: PCI : 78

Inspection Comments:

Sample Number: 106 Type: R Area: 4,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 74.00 Ft Comments:
52 RAVELING L 120.00 SqFt Comments:
57 WEATHERING L 3,880.00 SqFt Comments:

Sample Number: 114 Type: R Area: 4,000.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 215.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 100.00 Ft Comments:
57 WEATHERING L 3,900.00 SqFt Comments:

Sample Number: 121 Type: R Area: 4,000.00SqFt PCI = 86

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 34.00 Ft Comments:
52 RAVELING L 50.00 SqFt Comments:
57 WEATHERING L 3,944.00 SqFt Comments:

Sample Number: 129 Type: R Area: 4,000.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 170.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 80.00 Ft Comments:
57 WEATHERING L 3,920.00 SqFt Comments:

Sample Number: 137 Type: R Area: 6,764.67SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 182.00 Ft Comments:
50 PATCHING L 9.00 SqFt Comments:
45 DEPRESSION L 50.00 SqFt Comments:
52 RAVELING L 338.00 SqFt Comments:
57 WEATHERING L 6,427.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1116 of 9 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 6,760.00SqFt Length: 170.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 76

Inspection Comments:

Sample Number: 125 Type: R Area: 4,000.00SqFt PCI = 76

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 152.00 Ft | Comments: |
| 56 | SWELLING | L | 16.00 SqFt | Comments: |
| 52 | RAVELING | L | 52.00 SqFt | Comments: |
| 52 | RAVELING | L | 100.00 SqFt | Comments: |
| 57 | WEATHERING | L | 3,848.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1120 of 9 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 9,926.37SqFt Length: 240.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 70

Inspection Comments:

Sample Number: 100 Type: R Area: 3,913.00SqFt PCI = 70

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 130.00 Ft Comments:

50 PATCHING M 6.00 SqFt Comments:

52 RAVELING L 900.00 SqFt Comments:

57 WEATHERING L 3,007.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1125 of 9 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 94,533.01SqFt Length: 2,350.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 23 Surveyed: 4

Conditions: PCI : 80

Inspection Comments:

Sample Number: 142 Type: R Area: 4,000.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 87.00 Ft Comments:

52 RAVELING L 120.00 SqFt Comments:

57 WEATHERING L 3,880.00 SqFt Comments:

Sample Number: 148 Type: R Area: 4,000.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 153.00 Ft Comments:

52 RAVELING L 160.00 SqFt Comments:

57 WEATHERING L 3,840.00 SqFt Comments:

Sample Number: 157 Type: R Area: 4,000.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 125.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 160.00 Ft Comments:

57 WEATHERING L 3,840.00 SqFt Comments:

Sample Number: 160 Type: R Area: 4,000.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 141.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 18.00 Ft Comments:

50 PATCHING L 36.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1130 of 9 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 76,184.15SqFt Length: 1,900.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 19 Surveyed: 3

Conditions: PCI : 82

Inspection Comments:

Sample Number: 164 Type: R Area: 4,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 65.00 Ft Comments:

52 RAVELING L 200.00 SqFt Comments:

57 WEATHERING L 3,800.00 SqFt Comments:

Sample Number: 171 Type: R Area: 4,000.00SqFt PCI = 85

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 20.00 Ft Comments:

52 RAVELING L 120.00 SqFt Comments:

57 WEATHERING L 3,880.00 SqFt Comments:

Sample Number: 176 Type: R Area: 4,370.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 166.00 Ft Comments:

52 RAVELING L 131.00 SqFt Comments:

57 WEATHERING L 4,239.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1132 of 9 From: - To: - Last Const.: 01/01/2011

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 21,084.44SqFt Length: 1,700.00Ft Width: 12.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 92

Inspection Comments:

Sample Number: 204 Type: R Area: 4,600.00SqFt PCI = 92

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 5.00 Ft Comments:

57 WEATHERING L 4,600.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW K Name: TAXIWAY K Use: TAXIWAY Area: 465,040.17SqFt

Section: 1135 of 9 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 82,706.00SqFt Length: 1,900.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 20 Surveyed: 5

Conditions: PCI : 78

Inspection Comments:

Sample Number: 181 Type: R Area: 4,000.00SqFt PCI = 76

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 152.00 | Ft | Comments: |
| 56 | SWELLING | L | 2.00 | SqFt | Comments: |
| 52 | RAVELING | L | 200.00 | SqFt | Comments: |
| 52 | RAVELING | L | 160.00 | SqFt | Comments: |
| 52 | RAVELING | L | 84.00 | SqFt | Comments: |
| 52 | RAVELING | L | 6.00 | SqFt | Comments: |
| 42 | BLEEDING | N | 8.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,550.00 | SqFt | Comments: |

Sample Number: 187 Type: R Area: 4,000.00SqFt PCI = 74

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 192.00 | Ft | Comments: |
| 56 | SWELLING | L | 9.00 | SqFt | Comments: |
| 52 | RAVELING | L | 200.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,800.00 | SqFt | Comments: |

Sample Number: 193 Type: R Area: 4,000.00SqFt PCI = 76

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 193.00 | Ft | Comments: |
| 52 | RAVELING | L | 200.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,800.00 | SqFt | Comments: |

Sample Number: 198 Type: R Area: 4,000.00SqFt PCI = 76

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 182.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 50.00 | Ft | Comments: |
| 57 | WEATHERING | L | 4,000.00 | SqFt | Comments: |

Sample Number: 200 Type: R Area: 5,036.00SqFt PCI = 88

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 33.00 | Ft | Comments: |
| 45 | DEPRESSION | L | 18.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 5,036.00 | SqFt | Comments: |

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | | | | |
|-------------------|----------------|---------|---------------------------------|--------|---------|---------|-------|----------------|------------|
| Network: | MLB | Name: | MELBOURNE INTERNATIONAL AIRPORT | | | | | | |
| Branch: | TW K | Name: | TAXIWAY K | | Use: | TAXIWAY | Area: | 465,040.17SqFt | |
| Section: | 1140 | of | 9 | From: | - | To: | - | Last Const.: | 01/01/2014 |
| Surface: | AC | Family: | FDOT-SAPMP-PR-TW-AC | | | | Zone: | Category: | Rank: P |
| Area: | 23,583.00SqFt | Length: | 2,300.00Ft | Width: | 10.00Ft | | | | |
| Shoulder: | Street Type: | Grade: | 0.00 | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | |
| Last Insp. Date: | Total Samples: | 0 | Surveyed: | 0 | | | | | |
| Conditions: | | | | | | | | | |

| | | | |
|------------------------|-------|-------|------|
| Sample Number: | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> | | | |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW L Name: TAXIWAY L Use: TAXIWAY Area: 44,769.20SqFt

Section: 1204 of 2 From: - To: - Last Const.: 01/01/1998

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 10,453.39SqFt Length: 115.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 75

Inspection Comments:

Sample Number: 200 Type: R Area: 4,227.00SqFt PCI = 75

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 93.00 Ft | Comments: |
| 45 | DEPRESSION | L | 21.00 SqFt | Comments: |
| 56 | SWELLING | L | 10.00 SqFt | Comments: |
| 52 | RAVELING | L | 423.00 SqFt | Comments: |
| 57 | WEATHERING | L | 3,804.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW L Name: TAXIWAY L Use: TAXIWAY Area: 44,769.20SqFt

Section: 1210 of 2 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 34,315.81SqFt Length: 380.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 7 Surveyed: 1

Conditions: PCI : 74

Inspection Comments:

Sample Number: 204 Type: R Area: 4,600.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 150.00 Ft Comments:

56 SWELLING L 72.00 SqFt Comments:

56 SWELLING L 40.00 SqFt Comments:

52 RAVELING L 230.00 SqFt Comments:

57 WEATHERING L 4,370.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW M Name: TAXIWAY M Use: TAXIWAY Area: 86,953.87SqFt

Section: 1305 of 5 From: - To: - Last Const.: 01/01/2003

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 8,625.00SqFt Length: 200.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 70

Inspection Comments:

Sample Number: 201 Type: R Area: 4,312.00SqFt PCI = 70

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 136.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 75.00 Ft Comments:

52 RAVELING L 216.00 SqFt Comments:

57 WEATHERING L 4,096.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW M Name: TAXIWAY M Use: TAXIWAY Area: 86,953.87SqFt

Section: 1312 of 5 From: - To: - Last Const.: 01/01/2003

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 16,404.32SqFt Length: 800.00Ft Width: 20.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 71

Inspection Comments:

Sample Number: 100 Type: R Area: 5,508.00SqFt PCI = 71

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 253.00 Ft | Comments: |
| 52 | RAVELING | L | 14.00 SqFt | Comments: |
| 52 | RAVELING | L | 50.00 SqFt | Comments: |
| 50 | PATCHING | L | 143.00 SqFt | Comments: |
| 56 | SWELLING | L | 27.00 SqFt | Comments: |
| 57 | WEATHERING | L | 5,301.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW M Name: TAXIWAY M Use: TAXIWAY Area: 86,953.87SqFt

Section: 1315 of 5 From: - To: - Last Const.: 01/01/2003
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P
Area: 50,873.01SqFt Length: 660.00Ft Width: 75.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 13 Surveyed: 2

Conditions: PCI : 77

Inspection Comments:

Sample Number: 201 Type: R Area: 3,750.00SqFt PCI = 81

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 115.00 Ft | Comments: |
| 52 | RAVELING | L | 75.00 SqFt | Comments: |
| 57 | WEATHERING | L | 3,675.00 SqFt | Comments: |

Sample Number: 205 Type: R Area: 3,750.00SqFt PCI = 74

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 135.00 Ft | Comments: |
| 56 | SWELLING | L | 97.00 SqFt | Comments: |
| 57 | WEATHERING | L | 3,650.00 SqFt | Comments: |
| 52 | RAVELING | L | 100.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW M Name: TAXIWAY M Use: TAXIWAY Area: 86,953.87SqFt

Section: 1320 of 5 From: - To: - Last Const.: 01/01/2003

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 5,525.77SqFt Length: 220.00Ft Width: 25.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 75

Inspection Comments:

Sample Number: 100 Type: R Area: 3,025.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 94.00 Ft Comments:

52 RAVELING L 75.00 SqFt Comments:

57 WEATHERING L 2,948.00 SqFt Comments:

50 PATCHING M 2.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW M Name: TAXIWAY M Use: TAXIWAY Area: 86,953.87SqFt

Section: 1325 of 5 From: - To: - Last Const.: 01/01/2003

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 5,525.77SqFt Length: 220.00Ft Width: 25.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 88

Inspection Comments:

Sample Number: 200 Type: R Area: 3,026.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 10.00 Ft Comments:

52 RAVELING L 18.00 SqFt Comments:

57 WEATHERING L 3,008.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW N Name: TAXIWAY N Use: TAXIWAY Area: 44,828.31SqFt

Section: 1404 of 2 From: - To: - Last Const.: 01/01/1998

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 10,299.73SqFt Length: 110.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 81

Inspection Comments:

Sample Number: 301 Type: R Area: 5,272.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 26.00 Ft Comments:

52 RAVELING L 527.00 SqFt Comments:

57 WEATHERING L 4,745.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW N Name: TAXIWAY N Use: TAXIWAY Area: 44,828.31SqFt

Section: 1405 of 2 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 34,528.58SqFt Length: 380.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 8 Surveyed: 1

Conditions: PCI : 93

Inspection Comments:

Sample Number: 307 Type: R Area: 4,627.00SqFt PCI = 93

Sample Comments:

56 SWELLING L 3.00 SqFt Comments:

57 WEATHERING L 4,627.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW Q Name: TAXIWAY Q Use: TAXIWAY Area: 292,683.49SqFt

Section: 1705 of 7 From: - To: - Last Const.: 01/01/2007

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 91,925.99SqFt Length: 1,000.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 19 Surveyed: 3

Conditions: PCI : 75

Inspection Comments:

Sample Number: 101 Type: R Area: 5,260.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 170.00 Ft Comments:

42 BLEEDING N 2.00 SqFt Comments:

52 RAVELING L 263.00 SqFt Comments:

57 WEATHERING L 4,997.00 SqFt Comments:

Sample Number: 109 Type: R Area: 4,500.00SqFt PCI = 75

Sample Comments:

42 BLEEDING N 2.00 SqFt Comments:

52 RAVELING L 225.00 SqFt Comments:

57 WEATHERING L 4,275.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 239.00 Ft Comments:

Sample Number: 114 Type: R Area: 5,832.00SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 327.00 Ft Comments:

56 SWELLING L 40.00 SqFt Comments:

42 BLEEDING N 1.00 SqFt Comments:

52 RAVELING L 292.00 SqFt Comments:

57 WEATHERING L 5,540.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW Q Name: TAXIWAY Q Use: TAXIWAY Area: 292,683.49SqFt

Section: 1710 of 7 From: - To: - Last Const.: 01/01/2007

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 12,103.97SqFt Length: 120.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 100 Type: R Area: 7,947.00SqFt PCI = 83

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 129.00 Ft | Comments: |
| 52 | RAVELING | L | 397.00 SqFt | Comments: |
| 57 | WEATHERING | L | 7,550.00 SqFt | Comments: |
| 42 | BLEEDING | N | 5.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW Q Name: TAXIWAY Q Use: TAXIWAY Area: 292,683.49SqFt

Section: 1720 of 7 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 54,193.57SqFt Length: 540.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 10 Surveyed: 1

Conditions: PCI : 88

Inspection Comments:

Sample Number: 103 Type: R Area: 4,400.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 65.00 Ft Comments:

56 SWELLING L 3.00 SqFt Comments:

57 WEATHERING L 4,400.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW Q Name: TAXIWAY Q Use: TAXIWAY Area: 292,683.49SqFt

Section: 1722 of 7 From: - To: - Last Const.: 01/01/2004

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 7,920.90SqFt Length: 120.00Ft Width: 60.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 72

Inspection Comments:

Sample Number: 96 Type: R Area: 4,598.00SqFt PCI = 72

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 55.00 | Ft | Comments: |
| 50 | PATCHING | L | 360.00 | SqFt | Comments: |
| 52 | RAVELING | L | 225.00 | SqFt | Comments: |
| 52 | RAVELING | L | 32.00 | SqFt | Comments: |
| 52 | RAVELING | L | 53.00 | SqFt | Comments: |
| 52 | RAVELING | L | 51.00 | SqFt | Comments: |
| 52 | RAVELING | L | 65.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,812.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW Q Name: TAXIWAY Q Use: TAXIWAY Area: 292,683.49SqFt

Section: 1725 of 7 From: - To: - Last Const.: 01/01/2004
Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P
Area: 106,628.29SqFt Length: 1,400.00Ft Width: 75.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 28 Surveyed: 5

Conditions: PCI : 83

Inspection Comments:

Sample Number: 101 Type: R Area: 3,750.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 130.00 Ft Comments:
48 LONGITUDINAL/TRANSVERSE CRACKING L 12.00 Ft Comments:
57 WEATHERING L 3,750.00 SqFt Comments:

Sample Number: 103 Type: R Area: 3,750.00SqFt PCI = 89

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 54.00 Ft Comments:
57 WEATHERING L 3,750.00 SqFt Comments:

Sample Number: 109 Type: R Area: 3,750.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 65.00 Ft Comments:
52 RAVELING L 113.00 SqFt Comments:
57 WEATHERING L 3,637.00 SqFt Comments:

Sample Number: 117 Type: R Area: 3,750.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 137.00 Ft Comments:
56 SWELLING L 3.00 SqFt Comments:
52 RAVELING L 50.00 SqFt Comments:
57 WEATHERING L 3,700.00 SqFt Comments:

Sample Number: 123 Type: R Area: 3,754.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 157.00 Ft Comments:
57 WEATHERING L 3,754.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW Q Name: TAXIWAY Q Use: TAXIWAY Area: 292,683.49SqFt

Section: 1732 of 7 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 4,294.68SqFt Length: 100.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 1 Surveyed: 1

Conditions: PCI : 91

Inspection Comments:

Sample Number: 300 Type: R Area: 4,294.00SqFt PCI = 91

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 7.00 Ft Comments:

57 WEATHERING L 4,294.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW Q Name: TAXIWAY Q Use: TAXIWAY Area: 292,683.49SqFt

Section: 1735 of 7 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 15,616.09SqFt Length: 350.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 88

Inspection Comments:

Sample Number: 304 Type: R Area: 4,537.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 25.00 Ft Comments:

57 WEATHERING L 4,522.00 SqFt Comments:

52 RAVELING L 15.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW R Name: TAXIWAY R Use: TAXIWAY Area: 187,412.27SqFt

Section: 1805 of 4 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 61,343.65SqFt Length: 1,200.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 13 Surveyed: 2

Conditions: PCI : 90

Inspection Comments:

Sample Number: 703 Type: R Area: 4,811.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 27.00 Ft Comments:

57 WEATHERING L 4,811.00 SqFt Comments:

Sample Number: 706 Type: R Area: 4,600.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 24.00 Ft Comments:

57 WEATHERING L 4,600.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW R Name: TAXIWAY R Use: TAXIWAY Area: 187,412.27SqFt

Section: 1807 of 4 From: - To: - Last Const.: 01/01/1998

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 14,115.27SqFt Length: 350.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 69

Inspection Comments:

Sample Number: 699 Type: R Area: 4,654.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 351.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 30.00 Ft Comments:

52 RAVELING L 112.00 SqFt Comments:

52 RAVELING L 69.00 SqFt Comments:

52 RAVELING L 224.00 SqFt Comments:

57 WEATHERING L 4,249.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW R Name: TAXIWAY R Use: TAXIWAY Area: 187,412.27SqFt

Section: 1810 of 4 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 61,999.35SqFt Length: 1,500.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 13 Surveyed: 3

Conditions: PCI : 85

Inspection Comments:

Sample Number: 716 Type: R Area: 4,668.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 79.00 Ft Comments:

57 WEATHERING L 4,668.00 SqFt Comments:

Sample Number: 723 Type: R Area: 4,600.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 54.00 Ft Comments:

50 PATCHING L 285.00 SqFt Comments:

57 WEATHERING L 4,315.00 SqFt Comments:

Sample Number: 726 Type: R Area: 4,908.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 30.00 Ft Comments:

52 RAVELING L 30.00 SqFt Comments:

57 WEATHERING L 4,878.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW R Name: TAXIWAY R Use: TAXIWAY Area: 187,412.27SqFt

Section: 1820 of 4 From: - To: - Last Const.: 01/01/2009
Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P
Area: 49,954.00SqFt Length: 400.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 10 Surveyed: 2

Conditions: PCI : 87

Inspection Comments:

Sample Number: 730 Type: R Area: 6,066.00SqFt PCI = 88

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 32.00 Ft | Comments: |
| 52 | RAVELING | L | 50.00 SqFt | Comments: |
| 57 | WEATHERING | L | 6,016.00 SqFt | Comments: |

Sample Number: 736 Type: R Area: 4,604.00SqFt PCI = 85

Sample Comments:

| | | | | |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 99.00 Ft | Comments: |
| 56 | SWELLING | L | 18.00 SqFt | Comments: |
| 42 | BLEEDING | N | 0.25 SqFt | Comments: |
| 57 | WEATHERING | L | 4,604.00 SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW S Name: TAXIWAY S Use: TAXIWAY Area: 105,685.00SqFt

Section: 505 of 3 From: - To: - Last Const.: 01/01/2004

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 18,700.00SqFt Length: 485.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 63

Inspection Comments:

Sample Number: 102 Type: R Area: 4,000.00SqFt PCI = 63

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 292.00 Ft Comments:

50 PATCHING M 1.00 SqFt Comments:

52 RAVELING L 3,199.00 SqFt Comments:

57 WEATHERING L 800.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW S Name: TAXIWAY S Use: TAXIWAY Area: 105,685.00SqFt

Section: 510 of 3 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 68,429.00SqFt Length: 1,900.00Ft Width: 36.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 19 Surveyed: 3

Conditions: PCI : 55

Inspection Comments:

Sample Number: 106 Type: R Area: 3,600.00SqFt PCI = 51

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 155.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 179.00 | Ft | Comments: |
| 43 | BLOCK CRACKING | L | 344.00 | SqFt | Comments: |
| 43 | BLOCK CRACKING | L | 156.00 | SqFt | Comments: |
| 52 | RAVELING | L | 3,600.00 | SqFt | Comments: |
| 56 | SWELLING | L | 25.00 | SqFt | Comments: |

Sample Number: 113 Type: R Area: 3,600.00SqFt PCI = 61

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 257.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 100.00 | Ft | Comments: |
| 52 | RAVELING | L | 3,600.00 | SqFt | Comments: |

Sample Number: 120 Type: R Area: 3,600.00SqFt PCI = 53

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 258.00 | Ft | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 166.00 | Ft | Comments: |
| 50 | PATCHING | L | 50.00 | SqFt | Comments: |
| 52 | RAVELING | L | 3,550.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW S Name: TAXIWAY S Use: TAXIWAY Area: 105,685.00SqFt

Section: 515 of 3 From: - To: - Last Const.: 01/01/2010

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 18,556.00SqFt Length: 520.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 5 Surveyed: 1

Conditions: PCI : 87

Inspection Comments:

Sample Number: 126 Type: R Area: 3,500.00SqFt PCI = 87

Sample Comments:

52 RAVELING L 50.00 SqFt Comments:

52 RAVELING L 189.00 SqFt Comments:

57 WEATHERING L 3,261.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW S1 Name: TAXIWAY S1 Use: TAXIWAY Area: 34,004.00SqFt

Section: 520 of 2 From: - To: - Last Const.: 01/01/2009

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 14,644.00SqFt Length: 375.00Ft Width: 37.50Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 76

Inspection Comments:

Sample Number: 207 Type: R Area: 3,500.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 6.00 Ft Comments:

52 RAVELING L 1,050.00 SqFt Comments:

57 WEATHERING L 2,450.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW S1 Name: TAXIWAY S1 Use: TAXIWAY Area: 34,004.00SqFt

Section: 525 of 2 From: - To: - Last Const.: 01/01/2014

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 19,360.00SqFt Length: 525.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: Total Samples: 0 Surveyed: 0

Conditions:

Sample Number: Type: Area: 0.00

<NO VALID INSPECTIONS>

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW T Name: TAXIWAY T Use: TAXIWAY Area: 102,345.53SqFt

Section: 2005 of 2 From: - To: - Last Const.: 01/01/1986

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 47,618.77SqFt Length: 600.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 9 Surveyed: 2

Conditions: PCI : 83

Inspection Comments:

Sample Number: 102 Type: R Area: 4,600.00SqFt PCI = 90

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 27.00 Ft Comments:

57 WEATHERING L 4,600.00 SqFt Comments:

Sample Number: 105 Type: R Area: 4,600.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 274.00 Ft Comments:

56 SWELLING L 25.00 SqFt Comments:

57 WEATHERING L 4,600.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW T Name: TAXIWAY T Use: TAXIWAY Area: 102,345.53SqFt

Section: 2015 of 2 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 54,726.76SqFt Length: 540.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 11 Surveyed: 2

Conditions: PCI : 84

Inspection Comments:

Sample Number: 111 Type: R Area: 4,600.00SqFt PCI = 87

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 106.00 Ft Comments:

57 WEATHERING L 4,600.00 SqFt Comments:

Sample Number: 117 Type: R Area: 6,271.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 154.00 Ft Comments:

52 RAVELING L 314.00 SqFt Comments:

57 WEATHERING L 5,903.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW V Name: TAXIWAY V Use: TAXIWAY Area: 136,730.35SqFt

Section: 1602 of 5 From: - To: - Last Const.: 01/01/1998

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 10,398.11SqFt Length: 115.00Ft Width: 90.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 70

Inspection Comments:

Sample Number: 399 Type: R Area: 4,031.00SqFt PCI = 70

Sample Comments:

| | | | | | |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 146.00 | Ft | Comments: |
| 45 | DEPRESSION | L | 100.00 | SqFt | Comments: |
| 45 | DEPRESSION | L | 36.00 | SqFt | Comments: |
| 52 | RAVELING | L | 52.00 | SqFt | Comments: |
| 57 | WEATHERING | L | 3,919.00 | SqFt | Comments: |
| 52 | RAVELING | L | 60.00 | SqFt | Comments: |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW V Name: TAXIWAY V Use: TAXIWAY Area: 136,730.35SqFt

Section: 1605 of 5 From: - To: - Last Const.: 01/01/2009

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 61,170.72SqFt Length: 611.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 12 Surveyed: 2

Conditions: PCI : 87

Inspection Comments:

Sample Number: 402 Type: R Area: 4,568.00SqFt PCI = 87

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 44.00 Ft Comments:

56 SWELLING L 24.00 SqFt Comments:

57 WEATHERING L 4,568.00 SqFt Comments:

Sample Number: 410 Type: R Area: 5,009.00SqFt PCI = 86

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 87.00 Ft Comments:

56 SWELLING L 30.00 SqFt Comments:

57 WEATHERING L 5,009.00 SqFt Comments:

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | | | | |
|---|---------------|---------|---------------------------------|--------|---------|---------|-------|----------------|------------|
| Network: | MLB | Name: | MELBOURNE INTERNATIONAL AIRPORT | | | | | | |
| Branch: | TW V | Name: | TAXIWAY V | | Use: | TAXIWAY | Area: | 136,730.35SqFt | |
| Section: | 1610 | of | 5 | From: | - | To: | - | Last Const.: | 01/01/2013 |
| Surface: | AC | Family: | FDOT-SAPMP-PR-TW-AC | | | | Zone: | Category: | Rank: P |
| Area: | 36,715.00SqFt | Length: | 1,300.00Ft | Width: | 25.00Ft | | | | |
| Shoulder: | Street Type: | Grade: | 0.00 | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | |
| Last Insp. Date: Total Samples: 0 Surveyed: 0 | | | | | | | | | |
| Conditions: | | | | | | | | | |

| | | | |
|------------------------|-------|-------|------|
| Sample Number: | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> | | | |

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW V Name: TAXIWAY V Use: TAXIWAY Area: 136,730.35SqFt

Section: 2205 of 5 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 14,782.00SqFt Length: 380.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 94

Inspection Comments:

Sample Number: 102 Type: R Area: 4,001.00SqFt PCI = 94

Sample Comments:

57 WEATHERING L 4,001.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW V Name: TAXIWAY V Use: TAXIWAY Area: 136,730.35SqFt

Section: 2210 of 5 From: - To: - Last Const.: 01/01/2012

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 13,664.52SqFt Length: 270.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 94

Inspection Comments:

Sample Number: 105 Type: R Area: 4,727.00SqFt PCI = 94

Sample Comments:

57 WEATHERING L 4,727.00 SqFt Comments:

Re-inspection Report

FDOT

Report Generated Date: May 27, 2015

Network: MLB Name: MELBOURNE INTERNATIONAL AIRPORT

Branch: TW V1 Name: TAXIWAY V1 Use: APRON Area: 11,452.00SqFt

Section: 710 of 1 From: - To: - Last Const.: 01/01/2008

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 11,452.00SqFt Length: 225.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 04/06/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 88

Inspection Comments:

Sample Number: 150 Type: R Area: 5,907.00SqFt PCI = 88

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 45.00 Ft Comments:

52 RAVELING L 30.00 SqFt Comments:


57 WEATHERING L 5,877.00 SqFt Comments:

Re-inspection Report

FDOT
Report Generated Date: May 27, 2015

| | | | | | | | | | |
|---|--------------|---------|---------------------------------|--------|---------|---------|-------|--------------|------------|
| Network: | MLB | Name: | MELBOURNE INTERNATIONAL AIRPORT | | | | | | |
| Branch: | TW V2 | Name: | TAXIWAY V2 | | Use: | TAXIWAY | Area: | 8,446.00SqFt | |
| Section: | 720 | of | 1 | From: | - | To: | - | Last Const.: | 01/01/2013 |
| Surface: | AC | Family: | FDOT-SAPMP-PR-TW-AC | | | | Zone: | Category: | Rank: P |
| Area: | 8,446.00SqFt | Length: | 250.00Ft | Width: | 30.00Ft | | | | |
| Shoulder: | Street Type: | Grade: | 0.00 | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | |
| Last Insp. Date: Total Samples: 0 Surveyed: 0 | | | | | | | | | |
| Conditions: | | | | | | | | | |

| | | | |
|------------------------|-------|-------|------|
| Sample Number: | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> | | | |



FLORIDA DEPARTMENT OF TRANSPORTATION
AVIATION AND SPACEPORT OFFICE

