

FLORIDA DEPARTMENT OF TRANSPORTATION  
AVIATION AND SPACEPORT OFFICE



**PENSACOLA  
INTERNATIONAL  
AIRPORT (PNS)**

DISTRICT 3

PRIMARY AIRPORT

JUNE 2015

---

STATEWIDE  
**Airfield  
Pavement  
Management**  
PROGRAM







## TABLE OF CONTENTS

|   |    |
|---|----|
| Executive Summary .....   | 1  |
| 1. Introduction.....  | 7  |
| 2. Airfield Pavement Network Definition and Pavement Inventory..... | 19 |
| 3. Airfield Pavement Condition .....                                | 27 |
| 4. Pavement Performance .....                                       | 37 |
| 5. Airfield Pavement Maintenance Policies and Costs .....           | 41 |
| 6. Major Pavement Rehabilitation Needs.....                         | 49 |
| 7. Preventative and Major Rehabilitation Planning .....             | 53 |
| 8. Visual Aid Exhibits.....   | 55 |
| 9. Recommendations.....   | 57 |

## LIST OF TABLES

|  |    |
|--|----|
| Table I: Condition Summary by Branch .....   | 2  |
| Table II: Condition Summary by Pavement Facility Use .....                                 | 3  |
| Table III: Year-1 Major Rehabilitation Needs for Pensacola International Airport.....      | 4  |
| Table IV: 10-Year Preventative Maintenance and Major Rehabilitation .....                  | 5  |
| Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections .....                   | 15 |
| Table 2-1: Previous and/or Anticipated Airfield Pavement Construction .....                | 21 |
| Table 2-2: Pavement Inventory Summary.....   | 22 |
| Table 2-3: Airfield Pavement Inventory Details.....  | 23 |
| Table 3-1: Airfield Pavement Distresses for Asphalt Concrete.....                          | 30 |
| Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete .....                 | 31 |
| Table 3-3: Pavement Condition Index Rating Summary.....                                    | 34 |
| Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy.....                 | 42 |
| Table 5-2: Recommended PCC Maintenance and Repair Policy .....                             | 43 |
| Table 5-3: Critical and Minimum Service Level PCI for Primary Airports .....               | 45 |
| Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI.....                 | 45 |
| Table 5-5: AC Maintenance Unit Costs .....   | 47 |
| Table 5-6: PCC Maintenance Unit Costs.....   | 47 |
| Table 5-7: Rehabilitation Activities and Unit Costs by Condition for Primary Airports..... | 48 |
| Table 6-1: Summary of Major Rehabilitation.....  | 50 |
| Table 7-1: 10-Year Preventative and Major Rehabilitation Summary.....                      | 53 |

## LIST OF FIGURES

|  |    |
|--|----|
| Figure 1-1: Pavement Life Cycle.....                                     | 13 |
| Figure 1-2: Flexible Pavement, Asphalt Concrete.....                     | 16 |
| Figure 1-3: Rigid Pavement, Portland Cement Concrete .....               | 17 |
| Figure 2-1: Airfield Pavement Type.....                                  | 22 |
| Figure 3-1: Airfield Pavement Condition Index Rating Summary .....       | 33 |
| Figure 3-2: Percentage of Pavement Area by Condition Rating by Use ..... | 35 |
| Figure 4-1: Runway Pavement Performance Prediction Summary .....         | 38 |
| Figure 4-2: Taxiway Pavement Performance Prediction Summary.....         | 38 |
| Figure 4-3: Apron Pavement Performance Prediction Summary.....           | 39 |
| Figure 6-1: 10-Year Major Rehabilitation Budget Scenario Analysis.....   | 51 |
| Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary.....   | 54 |

## APPENDICES

|            |  |
|------------|--|
| Appendix A | Airfield Pavement Network Definition Exhibit<br>Airfield Pavement System Inventory Exhibit<br>Pavement Geometry Inventory<br>Work History Report |
| Appendix B | Airfield Pavement Condition Index Rating Exhibit<br>Pavement Condition Index Inventory   |
| Appendix C | Branch Condition Report<br>Section Condition Report  |
| Appendix D | Pavement Performance Prediction Table<br>Pavement Performance by Pavement Use  |
| Appendix E | Year-1 Preventative Activities   |
| Appendix F | Airfield Pavement 10-Year Major Rehabilitation Exhibit<br>Airfield Pavement 10-Year Major Rehabilitation Table                                   |
| Appendix G | Photographs  |
| Appendix H | Distress Data – Re-inspection Report   |



## EXECUTIVE SUMMARY

---

In 2012, the Florida Department of Transportation (FDOT) Central Aviation Office selected a team lead by Kimley-Horn and Associates, Inc. and including their subconsultants Penuel Consulting and LLC, Roy D. McQueen & Associates, LTD, to provide services in support of FDOT in the continued efforts of updating the existing Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed over the fiscal years of 2013 through 2015.

The tasks required to achieve this objective at each participating airport specifically included the following:

- Obtain recent construction history from the airport to update the Pavement Network Definition Exhibits using CADD from the previous SAPMP update.
- Update the airport pavement inventory data (construction history, geometry, identification, and classification) based on airport provided information.
- Update the FDOT SAPMP MicroPAVER database files and system tables for the purpose of analyzing field data for Pavement Condition Index (PCI) calculation of current pavement condition
- Development of pavement performance models for the approximation of future pavement performance.
- Development of a maintenance and repair plan, and a 10-year major rehabilitation program to address the pavement needs based on condition.
- Development of planning level opinions of probable costs for pavement preservation and rehabilitation.

In February 2015, a PCI survey inspection was performed at Pensacola International Airport. The results of the inspection indicate that, based on ASTM D 5340-12, the airport's airfield pavement facilities had an overall area-weighted average PCI of 79, representing a Satisfactory overall network condition. Table I summarizes the overall condition summary by network level branch in comparison to the FDOT recommended minimum service level and action recommendations for either major rehabilitation or maintenance level activities.

Table I: Condition Summary by Branch

| Branch Name     | Area Weighted PCI | PCI Range | Average Condition Rating | FDOT Minimum Service Level | MicroPAVER Minimum PCI | Action Required |
|-----------------|-------------------|-----------|--------------------------|----------------------------|------------------------|-----------------|
| CARGO APRON     | 100               | 100       | GOOD                     | 65                         | 65                     |                 |
| EAST APRON      | 63                | 63        | FAIR                     | 65                         | 65                     | X               |
| GA APRON        | 100               | 100       | GOOD                     | 65                         | 65                     |                 |
| SOUTH APRON     | 59                | 51 - 71   | FAIR                     | 65                         | 65                     | X               |
| TERMINAL APRON  | 91                | 9 - 100   | GOOD                     | 65                         | 65                     | X               |
| APRON WEST      | 71                | 71        | SATISFACTORY             | 65                         | 65                     |                 |
| RUNWAY 17-35    | 90                | 75 - 91   | GOOD                     | 75                         | 65                     |                 |
| RUNWAY 8-26     | 76                | 72 -84    | SATISFACTORY             | 75                         | 65                     | X               |
| TAXIWAY ALPHA   | 76                | 74 - 79   | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY A1      | 37                | 37        | VERY POOR                | 70                         | 65                     | X               |
| TAXIWAY A2      | 79                | 76 - 82   | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY A3      | 94                | 94        | GOOD                     | 70                         | 65                     |                 |
| TAXIWAY A4      | 84                | 84        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY A5      | 83                | 83        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY A7      | 67                | 67        | FAIR                     | 70                         | 65                     | X               |
| TAXIWAY BRAVO   | 81                | 75 - 88   | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY B2      | 83                | 83 - 94   | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY B3      | 83                | 83        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY B4      | 83                | 83        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY B5      | 80                | 80        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY B7      | 66                | 66        | FAIR                     | 70                         | 65                     | X               |
| TAXIWAY B8      | 75                | 75        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY CHARLIE | 78                | 73 - 82   | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY C2      | 80                | 80        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY DELTA   | 79                | 75 - 86   | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY D1      | 83                | 83        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY D2      | 80                | 80        | SATISFACTORY             | 70                         | 65                     |                 |
| TAXIWAY D3      | 87                | 87        | GOOD                     | 70                         | 65                     |                 |

“Action Required” in Table I is triggered when a section within the identified Branch Facility falls below the FDOT Minimum Service Level. Year 1 Major Rehabilitation needs are triggered in Table III when a section in the identified Branch falls below the MicroPAVER Minimum PCI. Major Rehabilitation is also triggered in Table III when the section PCI is above critical and the section exhibits significant structural related distresses.

For project level planning and inspection development; the airfield pavement facilities have been divided at the branch level based on facility use and designation, and at the section level based on pavement construction history, composition (e.g. asphalt versus concrete), aircraft traffic operations, and pavement surface conditions. Table II provides the overall area weighted condition of the pavement based on facility branch use.

**Table II: Condition Summary by Pavement Facility Use**

| Use     | Average Area-Weighted PCI | Condition Rating |
|---------|---------------------------|------------------|
| Runway  | 82                        | SATISFACTORY     |
| Taxiway | 78                        | SATISFACTORY     |
| Apron   | 79                        | SATISFACTORY     |

Based on the inspection performed at the airport for this SAPMP update; the current conditions were determined using the collected PCI distress data. PCI values were computed and used to identify pavement facilities that were below the defined critical PCI as sections that would benefit from immediate major rehabilitation activity. These pavement sections that were determined to be below the critical PCI would most likely benefit from long-term major rehabilitative construction activity rather than localized, short-term maintenance and repairs.

The Year-1 Major Rehabilitation Needs, or projects that are recommended to be completed because the pavement is below the critical PCI, were developed on the assumption that there is an unlimited repair budget. These projects include:

- East Apron – Section 4405
  - Mill and Overlay attributed to climate and age of pavement.
- South Apron – Section 4510
  - Mill and Overlay attributed to climate and age of pavement.
- Terminal Apron – Section 4230
  - Reconstruction attributed to load, climate, and age of pavement.
- Taxiway A1 – Section 120
  - Reconstruction attributed to load, climate, and age of pavement.

The section level projects that were identified as Year-1 Major Rehabilitation Needs are in Table III.



Table III: Year-1 Major Rehabilitation Needs for Pensacola International Airport

| Branch ID | Section ID | Major Rehabilitation Costs | PCI Before M&R | Rehabilitation Activity | PCI After M&R |
|-----------|------------|----------------------------|----------------|-------------------------|---------------|
| AP E      | 4405       | \$ 4,594,320.00            | 62             | Mill and Overlay        | 100           |
| AP S      | 4510       | \$ 6,088,788.00            | 50             | Mill and Overlay        | 100           |
| AP TERM   | 4230       | \$ 546,503.00              | 8              | Reconstruction          | 100           |
| TW A1     | 120        | \$ 1,090,177.00            | 37             | Reconstruction          | 100           |
| Total =   |            | \$ 12,319,788.00           |                |                         |               |

The SAPMP uses historic pavement condition data from the previous inspections to develop pavement performance models. These pavement performance models are used to create PCI prediction curves to estimate future pavement conditions based on the historic trends. The section areas, prediction curves, and current condition data were used to develop a 10-year major rehabilitation program. Major rehabilitation costs for each year of the 10-year program are based on general unit costs for pavement repairs and not detailed cost estimates that are typically prepared for a construction set of bid documents. Additionally, preventative maintenance level repair budgets were estimated for a 10-year duration. Table IV provides an annual summary of the 10-year Preventative Maintenance and Major Rehabilitation planning level cost opinions for the airfield pavement facilities at the airport. Refer to Section 6 of this report for additional information.

*Since the previous update performed in 2012, significant updates to the ASTM D 5340 Standard Test Method for Airport Pavement Condition Index Surveys have affected the analysis of the program. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reaction distress for rigid pavement distresses. Additionally, the deterioration associated with the rigid pavement distress Scaling/Map Cracking has been modified. The change in distress classification, as described in ASTM D 5340-12, may result in small variances in the PCI values from the previous inspection analysis. The update included changes in distress deduction values that may be less than the previous analysis. Please refer to Section 3 Airfield Pavement Condition Index for additional information.*

Additionally, pavement repair and rehabilitation work reported by the airports are entered into the SAPMP which can improve PCI values.

Table IV: 10-Year Preventative Maintenance and Major Rehabilitation

| Year  | Preventative     | Major M&R        | Total Year Cost  |
|-------|------------------|------------------|------------------|
| 2015  | \$ 1,061,869.86  | \$ 12,319,788.25 | \$ 13,381,658.11 |
| 2016  | \$ 1,164,419.15  | \$ 276,227.47    | \$ 1,440,646.62  |
| 2017  | \$ 1,168,247.89  | \$ 5,561,825.80  | \$ 6,730,073.70  |
| 2018  | \$ 1,301,233.45  | \$ -             | \$ 1,301,233.45  |
| 2019  | \$ 1,296,832.08  | \$ 6,724,258.16  | \$ 8,021,090.24  |
| 2020  | \$ 1,441,763.35  | \$ -             | \$ 1,441,763.35  |
| 2021  | \$ 1,459,691.63  | \$ 6,908,927.81  | \$ 8,368,619.45  |
| 2022  | \$ 1,416,189.67  | \$ 9,915,223.89  | \$ 11,331,413.57 |
| 2023  | \$ 1,436,265.37  | \$ 7,325,189.55  | \$ 8,761,454.92  |
| 2024  | \$ 1,548,381.26  | \$ 3,863,010.83  | \$ 5,411,392.10  |
| Total | \$ 13,294,893.71 | \$ 52,894,451.76 | \$ 66,189,345.51 |


The success of the repair program for your airport depends on the timely implementation of preservation, localized maintenance and repairs, and major rehabilitation work activities. If work is completed as scheduled, your airport should experience an improvement to the overall area-weighted average PCI. Though this analysis was performed with the assumption of an “unlimited budget”, the purpose has been to identify specific projects over the course of 10-years for each pavement section where the condition is projected to fall below the critical PCI. The costs depicted in this study are intended to aid the airports in planning level budgets. Prior to construction work, it is recommended that the airport perform additional investigation at the design level to better estimate costs associated with the maintenance, repair, and major rehabilitation activity discussed.





## 1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. The aviation system in Florida allows the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.



There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

The Florida Department of Transportation (FDOT) Central Aviation and Spaceport Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992. In 2012, the FDOT Central Aviation and Spaceport Office selected a team led by Kimley-Horn and Associates, Inc. and including Penuel Consulting, LLC and Roy D. McQueen & Associates, LTD, to provide services in support of the Central Aviation and Spaceport Office Program Manager. The continued evaluation and update of the existing SAPMP is to be completed over fiscal years 2013 through 2015.

This individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance repair and major rehabilitation planning associated with the SAPMP update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

## 1.1 Purpose of Pavement Evaluation Report

The purpose of this Airfield Pavement Evaluation Report is to:

- Briefly describe the SAPMP goals, procedures, and responsibilities of the program's participants.
- Provide a technical explanation on pavement management principles, standard practices, objectives, and benefits of implementation.
- Outline procedures used to coordinate, collect, evaluate and report pavement inspection results at this airport.
- Analyze and utilize condition results for the development of maintenance, repair, and major rehabilitation based on pavement performance trends.

## 1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the Florida Airports System, identify maintenance and rehabilitation needs at each airport, automate pavement infrastructure information management, and establish standards to address future needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.

During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement

management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation (M&R) policies, M&R budget costs, and the development of recommendations for performing routine pavement preservation maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER was selected for implementation of the system update. MicroPAVER was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for the purpose of pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER system. This data conversion included all documented pavement facility, classification, type, history, geometry, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In 2006-2008, the SAPMP was updated again with continued use of the MicroPAVER system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In 2010-2012, the SAPMP was updated using new GPS integrated technology to digitally collect pavement distress data. Interactive GIS map files were developed from updated Airfield Pavement Network Definition Maps to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.



Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the Federal Aviation Administration (FAA) to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C *Guidelines and Procedures for Maintenance of Airport Pavements*). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year or every three years, if the pavement is inspected in accordance to the PCI survey procedure (such as ASTM International D 5340 *Standard Test Method for Airport Pavement Condition Index Surveys*). The previous 2010-2012 SAPMP update utilized the ASTM D 5340-04 released in 2004, in lieu of the 2010/2011 edition, in order to maintain consistent database integrity and benefit of pavement performance models from previous inspections.

### 1.3 Organization

#### *FDOT Central Aviation Office Program Manager*

The FDOT Central Office Airport Engineering Manager serves as the Aviation and Spaceport Office Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the Consultant. The ASO-PM has review and approval authority for each program task and manages the day-to-day details of the SAPMP and the pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceport Manager and Development Administrator.

#### *Consultant*

The Consultant, Kimley-Horn and Associates, Inc. and their team consisting of Penuel Consulting, LLC and Roy D. McQueen & Associates, LTD, provides technical and administrative assistance to the ASO-PM during the execution of the update to the SAPMP. The efforts include updating the airport pavement inventory data, performing the condition survey inspections, evaluating the airfield pavement conditions and updating the SAPMP based upon procedures outlined in the FAA Advisory Circular 150/5380-6C *Guidelines and Procedures for Maintenance of Airport Pavements* and ASTM D 5340.

#### *Airport Role*

The airports are the ultimate beneficiary for each condition survey inspection performed at their respective airfields as part of the SAPMP. The individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the ASO-PM. The airport should have provided a

current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP, indicate any construction activity that was performed since the previous inspections.

#### *FDOT District Offices*

The seven FDOT District Offices, specifically the Aviation Representatives, provide vital support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing representative construction trend costs and practices through the Florida Airports System. Each District Office receives copies of individual Airfield Pavement Evaluation Reports for the airport facilities located within their respective districts.

## 1.4 Introduction to Pavement Types and Pavement Management

### *Pavement Basics*

A pavement is a prepared surface designed to provide a continuous smooth ride at all taxi, takeoff, and landing speeds and to support an estimated amount of traffic loading for a certain number of years. Pavements are composed of a combination of constructed layers of subgrade soils, subbases, base course material, and surface level courses. There are two primary types of pavements:

- Flexible Pavement, composed of bituminous asphalt concrete (AC) surface, base, and subbase layers.
- Rigid Pavement, composed of Portland Cement Concrete (PCC) surface, base, and subbase layers.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads (both magnitude and repeated application) and protect the underlying subgrade soil. Flexible pavements dissipate applied loads from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements, the PCC layer supports the majority of the structural load applied, and the base or subbase layer is constructed to provide a smooth, level, and continuous platform that provides uniform support for PCC slabs.

A small percentage of airfield pavements within the Florida Airports System are composed of hybrid 'composite pavement' sections that may include both AC pavement and PCC pavement. The two known composite pavements are AC surface over PCC (APC) and PCC over AC (White Topping).

Due to the different nature of the pavement types, construction, and their materials; flexible and rigid pavements have different modes of failure and

fatigue. This results in varying deterioration and distress development. Understanding the mechanics and modes of failure of the pavement types assists the engineers in making timely, adequate and consistent observations, and in recommending economical maintenance repairs and major rehabilitation to the pavement structures at each airfield.


### *The Concept of an Airfield Pavement Management System*

The SAPMP is a program that provides the Florida Airports System an opportunity to implement and/or maintain a proactive Airfield Pavement Management System (APMS) in a consistent manner at a regular schedule. The SAPMP Airfield Pavement Management System consists of pavement inventory, pavement construction and history, condition survey inspections, pavement performance modeling, maintenance recommendations, and major rehabilitation planning. The various elements of the APMS are used by experienced engineers to identify critical pavements, make pavement preservation or rehabilitation recommendations, and approximate pavement performance. The APMS as a whole is used by an airport's stakeholders, managing agencies, engineers, and planners as a tool in decision making for future project planning, budgeting, and scheduling of activities for its airfield pavement infrastructure.

A benefit of an active APMS is it provides an understanding of an airport's pavement performance trends for the purpose of project planning. Based on the performance trend of their pavements, an airport can schedule pavement maintenance and rehabilitation prior to when the pavement section has deteriorated to a condition that would require reconstruction. The use of pavement performance trends will help airports plan M&R and Rehabilitation projects in a manner and sequence that maximizes benefit and minimizes costs. Figure 1-1, which is based upon the FAA Advisory Circular 150 5380-7B *Airport Pavement Management Program*, illustrates how pavement generally deteriorates over time and the relative cost of rehabilitation and reconstruction throughout its life.



Figure 1-1: Pavement Life Cycle



Source: FAA Advisory Circular 150 5380-7B Airport Pavement Management Program

Note that during approximately the first 75% of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in 'Good' and 'Satisfactory' conditions depends on how well it is proactively maintained. As the Figure 1-1 demonstrates, the cost of maintaining the pavement above critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Pavements tend to deteriorate at an accelerated rate when actual traffic loading exceeds the original design assumptions and when limited resources are available for maintenance and repair (M&R) efforts. Planned maintenance and rehabilitation, essentially preserving pavements and delaying condition deterioration, help airport managers, agencies, and engineers maximize the use of their budgets and prolong the life of their pavements. An APMS provides a tool to schedule planned maintenance and major rehabilitation efforts based on a consistent methodology of condition assessment. This consistent methodology of pavement condition assessment allows for the development of pavement performance models to help forecast future pavement conditions.

Part of the implementation of the APMS is the clear identification and inventorying of pavement infrastructure that needs to be managed specifically within the airport owner, manager, and agency responsibility. Another aspect of the APMS is development of maintenance, repair, and major rehabilitation policies that align with the expectations of pavement performance and are based on ability to fund the types of work identified. Once there is an understanding of the cause and extent of pavement distresses, appropriate maintenance and rehabilitation can be planned. By using representative construction costs based on historic bid trends; planning level budget costs can be developed on a multiyear duration.

#### *Airfield Pavement Inspection Methodology for the SAPMP*

Pavement condition assessment requires the application of professional judgments regarding the condition of the pavement. The SAPMP airfield pavement condition survey inspections assess pavement, comparing it to a set of standards in ASTM D 5340-12. As part of this update, SAPMP has adopted the changes made in updates to ASTM D 5340-12. These include the separation of Weathering and Raveling into two distinct flexible pavement distresses, and the addition of the Alkali-Silica Reaction distress for rigid pavement distresses. Additionally, the deterioration associated with the rigid pavement distress Scaling/Map Cracking has been modified which results in moving Map Cracking from Scaling to ASR. In the newest version of ASTM D 5340-12, there are two kinds of Shrinkage Cracking, Drying Shrinkage and Plastic Shrinkage. The difference between these two is that the depth of first one may extend through the entire depth of the slab while the thickness of the latter one normally does not extend very deep into the pavement's surface. Furthermore, the Plastic Shrinkage consists of two subcategories: Plastic shrinkage (caused by atmosphere) and Plastic shrinkage (caused by construction). Another kind of Map Cracking is listed under Plastic shrinkage that is caused by construction, as well as Crazeing. This additional type of Shrinkage change in distress classification, as described in ASTM D 5340-12, may result in small variances in the PCI values from the previous inspection analysis.

The pavement condition surveys assess the functional condition of the pavement surface based on surface distresses as defined by the ASTM D 5340-12. Typically, deficiencies within a pavement structure will eventually reflect to the pavement surface as distresses described within ASTM D 5340-12. The SAPMP is specifically a visual evaluation and analysis based on the ASTM D 5340-12. The structural condition and relative support of the pavement layers can be directly quantified

using non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the SAPMP update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine design level rehabilitation and/or reconstruction needs should the airport proceed to the design process.

In preparation for the PCI survey inspections, the airfield pavements for each airport are divided into branches, sections, and sample units as established by FAA Advisory Circular 150/5380-6C and ASTM D 5340. Further discussion of the process of inventorying and categorizing pavement facilities by use, composition, and history can be found in SECTION 2 AIRFIELD PAVEMENT NETWORK DEFINITION and PAVEMENT INVENTORY.

Sample units are uniformly divided areas of pavement that are defined for inspection. Sample unit sizes are approximately 5,000 ± 2,000 square feet for flexible AC pavements and 20 ± 8 slabs for rigid PCC pavements. Prior to conducting the field condition survey inspections, the sampling plan was developed for the airfield pavements based on updates to the previous inspection sampling based on the available knowledge of construction updates. The sample rate adopted for the SAPMP is depicted on Table 1-1.

Table 1-1: Sampling Rate Schedule for SAPMP PCI Survey Inspections

| Flexible Pavements<br>Asphalt Concrete  |                                   |                             | Rigid Pavements<br>Portland Cement Concrete |                                   |                             |
|---|-----------------------------------|-----------------------------|---|-----------------------------------|-----------------------------|
| Number of<br>Sample Units in<br>Section | Number of Sample Units to Inspect |                             | Number of<br>Sample Units in<br>Section     | Number of Sample Units to Inspect |                             |
|   | Runway                            | Taxiways,<br>Aprons, Others |   | Runway                            | Taxiways,<br>Aprons, Others |
| 1 - 4                                   | 1                                 | 1                           | 1 - 3                                       | 1                                 | 1                           |
| 5 - 10                                  | 2                                 | 1                           | 4 - 6                                       | 2                                 | 1                           |
| 11 - 15                                 | 3                                 | 2                           | 7 - 10                                      | 3                                 | 2                           |
| 16 - 30                                 | 5                                 | 3                           | 11 - 15                                     | 4                                 | 2                           |
| 31 - 40                                 | 7                                 | 4                           | 16 - 20                                     | 5                                 | 3                           |
| 41 - 50                                 | 8                                 | 5                           | 21 - 30                                     | 7                                 | 3                           |
|   |                                   |                             | 31 - 40                                     | 8                                 | 4                           |
|   |                                   |                             | 41 - 50                                     | 10                                | 5                           |
| ≥ 51                                    | 20% but ≤<br>20                   | 10% but ≤ 10                | ≥ 51  | 20% but ≤<br>20                   | 10% but ≤ 10                |

The sample units to be inspected were determined through a systematic random sampling technique to provide an unbiased representation of sample units for each pavement facility. The sample unit locations had been determined in such a way that they are distributed evenly throughout each defined pavement section area. In certain cases when no representative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from each inspected sample unit are used to compute the PCI value and rating for each Section using the ASTM D 5340-12 and MicroPAVER (also known currently as PAVER) software. Figures 1-2 and 1-3 depict graphical representations of the color ranges associated with PCI values and ranges with a photograph of airfield pavement that exhibited the conditions for both flexible and rigid pavements respectively.

Figure 1-2: Flexible Pavement, Asphalt Concrete









|                          | PCI      | PCI | REPRESENTATIVE<br>PAVEMENT<br>SURFACE   | REPAIR<br>ACTIVITIES  |
|--------------------------|----------|-----|---|---|
| ROUTINE<br>MAINTENANCE   | 86 - 100 | 90  |   | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching.   |
| PAVEMENT<br>PRESERVATION | 65 - 85  | 70  |  | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments, patches, and/or joint/crack sealing.  |
| MAJOR<br>REHABILITATION  | 40 - 64  | 40  |  | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as Slab replacement and PCC restoration activity. |
| MAJOR<br>RECONSTRUCTION  | 0 - 39   | 15  |  | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction.  |

Figure 1-3: Rigid Pavement, Portland Cement Concrete

|                          | PCI      | PCI | REPRESENTATIVE<br>PAVEMENT<br>SURFACE  | REPAIR<br>ACTIVITIES  |
|--------------------------|----------|-----|--|---|
| ROUTINE<br>MAINTENANCE   | 86 - 100 | 90  |   | Pavements with PCI indexes above 85, or 'Good' may require periodic joint/crack sealing and local patching.   |
| PAVEMENT<br>PRESERVATION | 65 - 85  | 70  |   | Pavements with PCI conditions ranging from 'Satisfactory' to 'Good' may require surface treatments, patches, and/or joint/crack sealing.  |
| MAJOR<br>REHABILITATION  | 40 - 64  | 40  |   | Pavements that have deteriorated below a PCI 64, or within the range of 'Poor' to 'Fair' conditions may require major rehabilitation such as Slab replacement and PCC restoration activity. |
| MAJOR<br>RECONSTRUCTION  | 0 - 39   | 15  |  | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions may require major reconstruction.  |

Using the ASTM D 5340-12 standard seven qualitative ranges, the SAPMP provides a PCI value and a standard qualitative condition rating for the pavement facilities inspected.





## 2. AIRFIELD PAVEMENT NETWORK DEFINITION AND PAVEMENT INVENTORY

---

Pensacola International Airport (PNS) consists of two runways, Runway 8-26 at 150-ft wide by 7,000-ft long, and Runway 17-35 at 150-ft wide by 7,004-ft long. Runway 8-26 is composed of Asphalt Concrete pavement and RW 17-35 is composed of Portland Cement Concrete. The airport terminal is located in the North West side of the airfield with apron tie down spaces and hangar facilities located throughout. Runways 17-35 and 8-26 are served by parallel taxiways Alpha and Bravo, which are both 75-ft wide respectively. This airport is designated as a Primary / Part 139 airport and is located in District 3 of the Florida Department of Transportation.

It is important to note that the aforementioned runway data in addition to the remaining airfield pavement facilities geometric attributes may vary slightly from the geometry used in the condition exhibit in Appendix B and the major rehabilitation exhibit in Appendix F based on field measurements.

In 1933, Lee Conner Hagler and Harry Blanchard began construction of the airport facility which at the time consisted of two grass airstrips and a surplus Navy hangar. The City of Pensacola purchased the airfield in 1935, and with the help of the Works Progress Administration was able to develop Hagler Field into a permanent municipal airport. The Navy took over command of the airport in 1942-1945, although civilian air service continued. Hagler Field later became known as Pensacola Gulf Coast Airport. In late 2011 the airport was renamed Pensacola International Airport, despite not serving any international destinations at the time.

### 2.1 Network Definition

The airfield pavements within each airport network are separated into manageable units within the FDOT SAPMP MicroPAVER database system, organizing pavement data by similar use and constructive history.

#### *Branch and Section Identification*

Each airport's airfield pavement network is generally subdivided into separate Branches (runways, taxiways, aprons/ramps, or others) that have distinctly different functional identifications and uses. Each Branch is further subdivided into Sections as defined by pavement location, composition, and construction history. A Section is typically understood to be a project level subdivision within a Branch feature. Sections are manageable units to organize data collection and are

treated individually during the maintenance and major rehabilitation planning process. A pavement rank (primary, secondary, or tertiary) is assigned to each Section based on its importance and type of use to airport operations. The pavement rankings designated for each section at this airport were defined by the previous SAPMP, unless changes were communicated by the airport. These Sections are further subdivided into condition survey sample units based on the methodology described in ASTM D 5340.

#### *Airfield Pavement System Inventory and Network Definition Update*

The Airfield Pavement System Inventory and Airfield Pavement Network Definition Exhibits are developed individually for each participating airport. Based on information requested of and provided by the airport, the airfield pavements are evaluated on designation updates, and recent or anticipated pavement construction activity. As mentioned previously, a Section is defined partially by its construction history of which is factored in the performance and condition of the pavement section.

The Airfield Pavement System Inventory Exhibit, Figure A-2 in Appendix A, is a snapshot of recent and anticipated airfield pavement construction activity communicated by the airport since the last SAPMP update. Construction activities identified include maintenance and repair activity, major rehabilitation, and airfield pavement expansion efforts. Maintenance and repair activity may include; surface treatments, crack sealing, patching, slab replacement, and others. Both maintenance and rehabilitation activities are identified at the pavement section level. This type of work may result in an increase in overall Section PCI since the last inspection. Major rehabilitation efforts may include; asphalt milling and overlay, and full depth pavement reconstruction. This type of effort will result in a resetting of the pavement section PCI value to 100 due to the nature of the work. Lastly, airfield pavement expansions are accounted for as new inventory and assigned a section PCI of 100. Typically the new pavement sections are not inspected due to its condition; however these pavements are incorporated into the SAPMP pavement database. When possible, these changes are reflected in the Airfield Pavement Network Definition Exhibit, in Appendix A, prior to the field inspection. The updates are typically discussed and confirmed with airport personnel at the beginning and end of condition survey inspections to ensure accuracy.

The Airfield Pavement Network Definition Exhibit depicts the airport's pavement limits with Branch and Section delineations. This exhibit also includes the subdivision on Section areas into sample units and is used to identify those sample

units that are to be inspected. The previous SAPMP Airfield Pavement Network Definition Exhibits were used as a base. Updates and information provided by each airport was reviewed and the exhibits were revised appropriately. Characteristics that are considered include; airfield configuration, branch designations (magnetic declination, Airport Layout Plan updates) and pavement composition. The exhibit serves not only as a primary guide for the airfield inspectors but also allows specific distresses found in the re-inspection report to be geographically located.

Due to recent and anticipated construction efforts; pavement area sections may have been consolidated or created which will affect the total number of sample units to be inspected based upon the methods described in ASTM D 5340 and from the sampling rate schedule. Table 2-1 summarizes the recent and anticipated airfield pavement construction efforts communicated by the airport.

**Table 2-1: Previous and/or Anticipated Airfield Pavement Construction**

| Construction Year | Section Location | Work Type/Pavement Section    |
|-------------------|------------------|-------------------------------|
| 2010              | TERMINAL APRON   | AIR CARRIER APRON EXPANSION   |
| 2015              | NORTH CARGO RAMP | REHABILITATION / NEW PAVEMENT |

### *Airfield Pavement Network Definition & Geographic Information System (GIS)*

As part of this SAPMP update, geographic information system (GIS), global positioning system (GPS), and digital data collection were integrated into the Pavement Inspection Methodology at each airport. Using AutoCAD Civil 3D, ArcMap, ArcPad, and FDOT Survey and Mapping Office Aerial Photography; digital navigation maps have been developed for each airport to represent the SAPMP pavement inventory attributes. These navigation maps were used with field data tablets to assist survey teams as they performed condition inspections by navigating pavement infrastructure and collecting distress data.


## **2.2 Pavement Inventory**

The detailed pavement inventory database was updated to reflect the updates to the Airfield Pavement Network Definition Exhibit, in Appendix A, and field inspection results. Table 2-2 and Figure 2-1 provides a summary of the pavement inventory attributes at Pensacola International Airport for this SAPMP update.

Table 2-2: Pavement Inventory Summary

| Airfield Pavement Network Definition |           |                   |
|--------------------------------------|-----------|-------------------|
| Number of Branches                   | 28        |                   |
| Number of Sections                   | 72        |                   |
| Sample Units                         | 229       |                   |
| Airfield Pavement Use                |           |                   |
| Use                                  | Area (SF) | Relative Area (%) |
| Runway                               | 1,778,396 | 27%               |
| Taxiway                              | 2,308,190 | 35%               |
| Apron                                | 2,444,716 | 37%               |
| Total =                              | 6,531,302 | 100%              |
| Airfield Pavement Type               |           |                   |
| Type                                 | Area (SF) | Relative Area (%) |
| Asphalt Concrete (AC)                | 4,452,505 | 68%               |
| Asphalt Overlay (AAC)                | 145,820   | 2%                |
| Portland Cement Concrete (PCC)       | 1,932,977 | 30%               |
| AC over PCC (APC)                    | 0         | 0%                |

Figure 2-1: Airfield Pavement Type





Specific details to each Branch and Section such as; name, geometry, age, rank, surface type, and construction history are provided in Table 2-3.

Table 2-3: Airfield Pavement Inventory Details

| Branch Name    | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|----------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| RUNWAY 8-26    | RW 8-26   | 6270       | 50,050         | P            | AC           | 1/1/2006         | 2                       | 10            |
| RUNWAY 8-26    | RW 8-26   | 6265       | 100,100        | P            | AC           | 1/1/2006         | 5                       | 20            |
| RUNWAY 8-26    | RW 8-26   | 6260       | 30,000         | P            | AC           | 1/1/2004         | 2                       | 6             |
| RUNWAY 8-26    | RW 8-26   | 6255       | 60,000         | P            | AC           | 1/1/2004         | 3                       | 12            |
| RUNWAY 8-26    | RW 8-26   | 6250       | 20,000         | P            | AC           | 1/1/2004         | 1                       | 4             |
| RUNWAY 8-26    | RW 8-26   | 6245       | 40,000         | P            | AC           | 1/1/2004         | 2                       | 8             |
| RUNWAY 8-26    | RW 8-26   | 6240       | 85,000         | P            | AC           | 1/1/2004         | 5                       | 18            |
| RUNWAY 8-26    | RW 8-26   | 6235       | 170,000        | P            | AC           | 1/1/2004         | 7                       | 34            |
| RUNWAY 8-26    | RW 8-26   | 6230       | 44,999         | P            | AC           | 1/1/2004         | 3                       | 12            |
| RUNWAY 8-26    | RW 8-26   | 6225       | 89,997         | P            | AC           | 1/1/2004         | 5                       | 18            |
| RUNWAY 8-26    | RW 8-26   | 6220       | 47,500         | P            | AC           | 1/1/2004         | 3                       | 12            |
| RUNWAY 8-26    | RW 8-26   | 6215       | 95,000         | P            | AC           | 1/1/2004         | 5                       | 19            |
| RUNWAY 8-26    | RW 8-26   | 6210       | 65,000         | P            | AC           | 1/1/2004         | 3                       | 14            |
| RUNWAY 8-26    | RW 8-26   | 6205       | 130,000        | P            | AC           | 1/1/2004         | 5                       | 26            |
| RUNWAY 17-35   | RW 17-35  | 6130       | 131,789        | P            | PCC          | 11/1/2007        | 9                       | 30            |
| RUNWAY 17-35   | RW 17-35  | 6125       | 396,211        | P            | PCC          | 11/1/2007        | 15                      | 59            |
| RUNWAY 17-35   | RW 17-35  | 6120       | 26,250         | P            | AC           | 11/1/2007        | 2                       | 6             |
| RUNWAY 17-35   | RW 17-35  | 6115       | 52,500         | P            | AC           | 11/1/2007        | 3                       | 11            |
| RUNWAY 17-35   | RW 17-35  | 6110       | 110,822        | P            | PCC          | 11/1/2007        | 7                       | 24            |
| RUNWAY 17-35   | RW 17-35  | 6105       | 33,178         | P            | PCC          | 11/1/2007        | 12                      | 49            |
| CARGO APRON    | AP CARGO  | 4710       | 145,521        | P            | PCC          | 1/1/2015         | 0                       | 0             |
| CARGO APRON    | AP CARGO  | 4705       | 68,880         | P            | PCC          | 1/1/2015         | 0                       | 0             |
| APRON WEST     | AP W      | 4605       | 219,372        | P            | AC           | 1/1/2002         | 5                       | 42            |
| SOUTH APRON    | AP S      | 4515       | 219,093        | T            | AC           | 1/1/1997         | 4                       | 37            |
| SOUTH APRON    | AP S      | 4510       | 338,266        | T            | AC           | 1/1/1997         | 8                       | 72            |
| SOUTH APRON    | AP S      | 4505       | 112,540        | T            | AC           | 1/1/1997         | 3                       | 26            |
| EAST APRON     | AP E      | 4405       | 255,240        | P            | AC           | 12/25/1999       | 7                       | 67            |
| GA APRON       | AP GA     | 4325       | 37,703         | P            | AAC          | 1/1/2015         | 0                       | 0             |
| GA APRON       | AP GA     | 4320       | 12,201         | P            | AAC          | 1/1/2015         | 0                       | 0             |
| GA APRON       | AP GA     | 4315       | 9,900          | P            | PCC          | 1/1/2015         | 0                       | 0             |
| GA APRON       | AP GA     | 4310       | 26,365         | P            | AAC          | 1/1/2015         | 0                       | 0             |
| TERMINAL APRON | AP TERM   | 4235       | 127,593        | P            | PCC          | 12/25/1998       | 4                       | 37            |
| TERMINAL APRON | AP TERM   | 4230       | 23,761         | P            | AC           | 1/1/2001         | 1                       | 5             |
| TERMINAL APRON | AP TERM   | 4225       | 106,612        | P            | PCC          | 1/1/2010         | 3                       | 18            |

| Branch Name    | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|----------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| TERMINAL APRON | AP TERM   | 4220       | 76,245         | P            | PCC          | 1/1/2010         | 3                       | 29            |
| TERMINAL APRON | AP TERM   | 4215       | 42,079         | P            | PCC          | 1/1/2010         | 1                       | 6             |
| TERMINAL APRON | AP TERM   | 4210       | 256,288        | P            | PCC          | 1/1/1977         | 7                       | 69            |
| TERMINAL APRON | AP TERM   | 4205       | 367,057        | T            | PCC          | 1/1/1988         | 10                      | 122           |
| TAXIWAY C2     | TW C2     | 515        | 31,643         | P            | AC           | 1/1/1997         | 1                       | 9             |
| TAXIWAY C      | TW C      | 510        | 67,178         | P            | AC           | 1/1/1997         | 3                       | 19            |
| TAXIWAY C      | TW C      | 505        | 13,138         | P            | AC           | 1/1/1997         | 1                       | 3             |
| TAXIWAY D      | TW D      | 430        | 48,300         | P            | AC           | 1/1/2005         | 3                       | 12            |
| TAXIWAY D3     | TW D3     | 425        | 14,220         | P            | AAC          | 1/1/2006         | 1                       | 3             |
| TAXIWAY D2     | TW D2     | 420        | 13,134         | P            | AC           | 1/1/2000         | 1                       | 3             |
| TAXIWAY D1     | TW D1     | 415        | 13,134         | P            | AC           | 1/1/2000         | 1                       | 3             |
| TAXIWAY D      | TW D      | 410        | 20,158         | P            | AC           | 1/1/2005         | 1                       | 4             |
| TAXIWAY D      | TW D      | 405        | 118,752        | P            | AC           | 1/1/2000         | 4                       | 33            |
| TAXIWAY B8     | TW B8     | 280        | 13,317         | P            | AC           | 1/1/2002         | 1                       | 3             |
| TAXIWAY B7     | TW B7     | 270        | 14,899         | P            | AC           | 1/1/2002         | 1                       | 3             |
| TAXIWAY B5     | TW B5     | 265        | 48,322         | P            | AC           | 1/1/2002         | 2                       | 10            |
| TAXIWAY B4     | TW B4     | 260        | 50,114         | P            | AC           | 1/1/2002         | 1                       | 10            |
| TAXIWAY B3     | TW B3     | 255        | 50,248         | P            | AC           | 1/1/2002         | 1                       | 10            |
| TAXIWAY C      | TW C      | 252        | 16,451         | P            | AC           | 1/1/2002         | 1                       | 3             |
| TAXIWAY C      | TW C      | 250        | 33,625         | P            | AC           | 1/1/2004         | 1                       | 7             |
| TAXIWAY B2     | TW B2     | 240        | 50,378         | P            | AC           | 1/1/2002         | 1                       | 10            |
| TAXIWAY B      | TW B      | 230        | 124,670        | P            | AC           | 1/1/2005         | 4                       | 29            |
| TAXIWAY B      | TW B      | 220        | 256,627        | P            | AC           | 1/1/2002         | 7                       | 68            |
| TAXIWAY B      | TW B      | 217        | 11,000         | P            | AC           | 1/1/2002         | 1                       | 2             |
| TAXIWAY A7     | TW A7     | 215        | 72,160         | P            | AC           | 1/1/2002         | 3                       | 17            |
| TAXIWAY B2     | TW B2     | 213        | 10,751         | P            | PCC          | 1/1/1988         | 1                       | 4             |
| TAXIWAY B2     | TW B2     | 212        | 32,535         | P            | AC           | 1/1/2002         | 1                       | 8             |
| TAXIWAY B      | TW B      | 210        | 51,982         | P            | AC           | 1/1/2002         | 1                       | 9             |
| TAXIWAY B      | TW B      | 205        | 213,853        | P            | AC           | 1/1/2002         | 6                       | 52            |
| TAXIWAY A3     | TW A3     | 170        | 50,051         | T            | PCC          | 1/1/2006         | 1                       | 8             |
| TAXIWAY A2     | TW A2     | 160        | 37,493         | P            | AC           | 1/1/2000         | 1                       | 7             |
| TAXIWAY A2     | TW A2     | 150        | 55,331         | P            | AAC          | 1/1/2006         | 2                       | 11            |
| TAXIWAY D      | TW D      | 140        | 43,648         | P            | AC           | 1/1/2001         | 2                       | 9             |
| TAXIWAY A4     | TW A4     | 130        | 49,968         | P            | AC           | 1/1/2001         | 1                       | 10            |
| TAXIWAY A5     | TW A5     | 125        | 49,806         | P            | AC           | 1/1/2001         | 1                       | 10            |
| TAXIWAY A1     | TW A1     | 120        | 47,399         | P            | AC           | 1/1/2001         | 1                       | 9             |
| TAXIWAY A      | TW A      | 115        | 297,891        | P            | AC           | 2/1/2001         | 8                       | 74            |

| Branch Name | Branch ID | Section ID | True Area (SF) | Section Rank | Surface Type | Last Const. Date | Total Samples Inspected | Total Samples |
|-------------|-----------|------------|----------------|--------------|--------------|------------------|-------------------------|---------------|
| TAXIWAY A   | TW A      | 105        | 286,014        | P            | AC           | 1/1/2001         | 8                       | 73            |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.



### 3. AIRFIELD PAVEMENT CONDITION

---

Airfield pavement distresses and condition were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D 5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating.

The program has been updated from ASTM D 5340-04, released in 2004, to ASTM D 5340-12, released in 2013, for this SAPMP update. The primary updates include the separation of certain distress types and the addition of new types with corresponding changes to PCI calculation. These changes in distress classification may result in small variances in the PCI values from the previous inspection analysis.

Below is a brief description of the changes to the distresses presented in the ASTM D 5340 methodology and a table summarizing the deduction affected.

- a) Flexible Asphalt Concrete Pavement distresses for airfield pavements: The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering". Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling", the PCI deduction is not as high as the former "Weathering and Raveling". Therefore, areas identified only as "(57) Weathering" based on current ASTM standards, which were previously identified as "(52) Weathering and Raveling", may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.
- b) Rigid Portland Cement Concrete Pavement distresses for airfield pavements: The previous methodology defined "(70) Scaling" as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as "(76) Alkali-Silica Reaction / ASR". As a result the previous "(70) Scaling" numerical deduction



contribution to the PCI has been reduced. Previous inspections that recorded "(70) Scaling", and currently do not exhibit "(76) Alkali-Silica Reactivity / ASR" may potentially see an increase in PCI. Additionally, (73) Shrinkage Cracks has been redefined as (73) Shrinkage Cracking. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.

| Distress Updates to Reflect ASTM 5340-12 |                                     |                                      |              |
|--|-------------------------------------|--------------------------------------|--------------|
| Use and Surface Type                     | Old 5340-04 Distress                | New Distress                         | Deduct Curve |
| AC/AAC/APC Airfield                      | (52) Weathering & Raveling - Low    | (52) Raveling - Low                  | No Change    |
|  | (52) Weathering & Raveling - Medium | (52) Raveling - Medium               | No Change    |
|  | (52) Weathering & Raveling - High   | (52) Raveling - High                 | No Change    |
|  | N/A                                 | (57) Weathering - Low                | New          |
|  | N/A                                 | (57) Weathering - Medium             | New          |
|  | N/A                                 | (57) Weathering - High               | New          |
| PCC Airfield                             | (70) Scaling - Low                  | (70) Scaling - Low                   | New          |
|  | (70) Scaling - Medium               | (70) Scaling - Medium                | New          |
|  | (70) Scaling - High                 | (70) Scaling - High                  | New          |
|  | N/A                                 | (76) Alkali Silica Reaction – Low    | New          |
|  | N/A                                 | (76) Alkali Silica Reaction – Medium | New          |
|  | N/A                                 | (76) Alkali Silica Reaction – High   | New          |

### 3.1 Inspection Methodology

A pavement condition survey inspection is performed by measuring the amount and severity of defined pavement distresses observed within the boundaries of sample units. These distresses, as defined by ASTM D 5340, are generally caused by traffic fatigue loading, exposure to climate and elements, and other airfield specific factors. This data is collected by field personnel experienced in pavement condition survey inspection. Data collection is then transferred into the FDOT MicroPAVER database system. MicroPAVER (also known as PAVER) is used to calculate PCI values using the methodology described in ASTM D 5340-12. The values are calculated for each sample and extrapolated on a Section level to determine an area-weighted PCI value ranging from 0 to 100 and one of seven condition ratings. Tables 3-1 and 3-2 describe the distresses as defined by the ASTM D 5340-12 and adopted for the SAPMP procedures.

Table 3-1: Airfield Pavement Distresses for Asphalt Concrete

| Code | Distress                         | Primary Mechanisms               |
|------|----------------------------------|----------------------------------|
| 41   | Alligator Cracking               | Load / Fatigue Failure           |
| 42   | Bleeding                         | Construction Quality/ Mix Design |
| 43   | Block Cracking                   | Climate / Age                    |
| 44   | Corrugation                      | Load / Construction Quality      |
| 45   | Depression                       | Subgrade Quality                 |
| 46   | Jet Blast                        | Aircraft                         |
| 47   | Joint Reflection - Cracking      | Climate / Prior Pavement         |
| 48   | Longitudinal/Transverse Cracking | Climate / Age                    |
| 49   | Oil Spillage                     | Aircraft / Vehicle               |
| 50   | Patching                         | Utility / Pavement Repair        |
| 51   | Polished Aggregate               | Repeated Traffic Loading         |
| 52   | Raveling                         | Climate / Load                   |
| 53   | Rutting                          | Repeated Traffic Loading         |
| 54   | Shoving                          | PCC Pavement Growth / Movement   |
| 55   | Slippage Cracking                | Load / Pavement Bond             |
| 56   | Swelling                         | Climate / Subgrade Quality       |
| 57   | Weathering                       | Climate                          |

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

Table 3-2: Airfield Pavement Distresses for Portland Cement Concrete

| Code | Distress                | Primary Mechanisms  |
|------|-------------------------|---|
| 61   | Blow-up                 | Climate / Alkali Silica Reaction                          |
| 62   | Corner Break            | Load Repetition / Curling Stresses                        |
| 63   | Linear Cracking         | Load Repetition / Curling Stresses / Shrinkage Stresses   |
| 64   | Durability Cracking     | Freeze-Thaw Cycling                                       |
| 65   | Joint Seal Damage       | Material Deterioration / Construction Quality             |
| 66   | Small Patch             | Pavement Repair   |
| 67   | Large Patch/Utility Cut | Utility / Pavement Repair                                 |
| 68   | Popout                  | Freeze-Thaw Cycling                                       |
| 69   | Pumping                 | Load Repetition / Poor Joint Sealant                      |
| 70   | Scaling/Crazing         | Construction Quality / Freeze-Thaw Cycling                |
| 71   | Faulting                | Load Repetition / Subgrade Quality                        |
| 72   | Shattered Slab          | Overloading   |
| 73   | Shrinkage Cracking      | Construction Quality / Load                               |
| 74   | Joint Spalling          | Load Repetition / Infiltration of Incompressible Material |
| 75   | Corner Spalling         | Load Repetition / Infiltration of Incompressible Material |
| 76   | Alkali-Silica Reaction  | Construction Quality / Climate                            |

Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual

### 3.2 Airfield Pavement Condition Index Rating Results

From the condition survey inspection performed in 2015 at Pensacola International Airport, the overall weighted average PCI value is 79 representing a condition rating of Satisfactory.

The airport's airfield pavements exhibited distresses typically associated with climate and age based distresses. The predominant AC and AAC pavement distresses observed include: weathering, raveling, block cracking, and longitudinal and transverse cracking. The predominate PCC pavement distresses observed include: longitudinal, transverse and diagonal cracking, joint seal damage, patching, map cracking, shrinkage cracking, corner and joint spalling.

Runway 8-26 exhibited low severity longitudinal and transverse cracking along with low severity weathering and raveling. These distresses were observed in low quantities due to the good overall condition of the runway pavement. Alligator cracking was recorded at an isolated location at the Taxiway Alpha intersection but was not indicative of the overall pavement condition.

Runway 17-35 exhibited low severity patching, joint and corner spalling distresses. The runway is still considered to be fairly new which was evident in the good overall condition of the Portland Cement Concrete pavement.

The taxiways and taxiway connectors exhibited very similar distresses to Runway 8-26, with low quantities of low severity longitudinal and transverse cracking along with low severity weathering and raveling. Taxiway connector A-1 had significant low and medium severity alligator cracking recorded, which is a series of interconnecting cracks caused by fatigue failure of the asphalt concrete surface under repeated traffic loading. This is considered to be a significant structural distress.

The main terminal apron which is constructed of Portland Cement Concrete exhibited distresses such as longitudinal, transverse and diagonal cracking, joint seal damage, patching, map cracking, shrinkage cracking, and joint spalling. These distresses varied from mostly low and medium severities.

The East Apron along Taxiway Delta exhibited low and medium severity longitudinal and transverse cracking along with low severity swelling, raveling and block cracking. A chip seal was put over the apron asphalt concrete pavements quite a while ago, which is now degrading with surficial cracking throughout.

The South apron exhibited low severity longitudinal and transverse cracking, raveling, weathering, patching, block cracking, depressions and swelling. Medium severity longitudinal and transverse cracking along with raveling was recorded in isolated locations.

The cargo apron is currently scheduled for pavement rehabilitation and was not included as part of the recent inspections at the direction of airport personnel.

Appendix B contains Table B-1 which summarizes the Section Condition Values and an Airfield Pavement Condition Index Rating Exhibit, Figure B-1, which depicts the PCI results by Section. Appendix C contains MicroPAVER reports of PCI results by Branch and Section. Appendix H includes the most current detailed distress data generated by MicroPAVER for each inspected sample unit for this update.



The pavement condition at Pensacola International Airport is represented in Figure 3-1 in accordance with the condition categories and PCI scale referenced in ASTM D 5340. Further detail is provided in Table 3-3 which describes the breakdown of the airport's airfield conditions according to area and use.

Figure 3-1: Airfield Pavement Condition Index Rating Summary





Table 3-3: Pavement Condition Index Rating Summary

| Airfield Pavement Use |                           |                   |
|-----------------------|---------------------------|-------------------|
| Use                   | Average Area-Weighted PCI | Condition Rating  |
| Runway                | 82                        | SATISFACTORY      |
| Taxiway               | 78                        | SATISFACTORY      |
| Apron                 | 79                        | SATISFACTORY      |
| Condition Area        |                           |                   |
| Condition Rating      | Area (SF)                 | Relative Area (%) |
| Good                  | 2,196,436                 | 34%               |
| Satisfactory          | 3,364,048                 | 50%               |
| Fair                  | 561,392                   | 9%                |
| Poor                  | 338,266                   | 5%                |
| Very Poor             | 47,399                    | 1%                |
| Serious               | -                         | 0%                |
| Failed                | 23,761                    | 1%                |


Approximately 84% of the airfield network is in Good and Satisfactory condition, while 7% of the network is in a Poor to Failed condition. Table 3-3 provides a breakdown of total area for each pavement by condition rating. Figures 3.2 a, b, c depict the condition rating of the airfield pavement by Branch Use. Photographs taken during the condition survey inspection are included in Appendix G. The photographs included are intended to be representative of the distress observed.

Figure 3-2: Percentage of Pavement Area by Condition Rating by Use


(a) Runway



(b) Taxiway



(c) Apron



#### 4. PAVEMENT PERFORMANCE

---

Pavement performance models are developed from the distress data collected for the SAPMP for the Florida Airports System. This data is consolidated in a database and organized by inspection date, pavement type, age, pavement use, and airport category. The pavement performance models are used to develop broad prediction models, also known as pavement condition deterioration curves.

The consolidation of the Florida Airports System's pavement infrastructure within the FDOT SAPMP is based on data that has been collected in a consistent method of measurement. The historic pavement condition, or performance trend, has been compiled throughout the system with data from the inception of the SAPMP. This data is processed into models that have been analyzed and developed into prediction curves based upon pavement characteristics. These characteristics include; climate, construction material, and operations. Each model has been developed based on the following criteria:

AIRPORT TYPE (Primary, Regional Reliever, or General Aviation)

>FACILITY USE (Runway, Taxiway, or Apron)

>>FACILITY SURFACE TYPE (AC, AAC, APC, or PCC)

The historic trends of pavement performance at Florida airport facilities for all performance models are consolidated within the program database. This information is utilized in the prediction of pavement performance based on the current PCI determined from the inspections that took place between 2013 and 2015. Major rehabilitation is planned based on the predicted PCI. The intent of this is for both the individual airport and the FDOT District personnel to be aware of anticipated major rehabilitation work based on condition.

Each airport's airfield pavement section condition, for a given inspection year, is one data point that was used as the basis of each performance trend using a performance model based on pavements of similar background. Figures 4-1, 4-2, and 4-3 represent the pavement performance prediction at Pensacola International Airport based on pavement use. Each figure depicts the FDOT recommended Minimum Service Level PCI value for each facility use.

Figure 4-1: Runway Pavement Performance Prediction Summary




Figure 4-2: Taxiway Pavement Performance Prediction Summary







Figure 4-3: Apron Pavement Performance Prediction Summary



Pavement performance modeling to predict the future PCI is primarily done to predict PCI at the Section level for the purpose of planning Major Rehabilitation work. In Appendix D, Table D-1 represents the predicted area-weighted PCI by Section for the airport's airfield pavement infrastructure.



## 5. AIRFIELD PAVEMENT MAINTENANCE POLICIES AND COSTS

---

### 5.1 Policies

Airfield Pavement Maintenance policies are guidance on pavement construction methods used to develop, maintain, repair, and rehabilitate pavement infrastructure based on distresses encountered during the condition surveys.

Maintenance refers to the repair and preservation-type activities that are applied locally to specific distress types on the pavement. These activities for the SAPMP are considered preventative and corrective in nature and are highly recommended to help improve pavement performance and extend pavement life. The SAPMP maintenance policies are based on the FAA Advisory Circular 150/5380-6C and guidance provided in the FDOT Airfield Pavement Repair Manual.

For the purpose of the SAPMP; the maintenance repair needs that are identified and quantified are based solely on the pavement distresses observed and recorded at the time of the inspection. Based on a specific distress type and severity observed, a particular repair work type is recommended and quantified based on the extrapolated section distresses. The repair program identified is specific to the current distresses. Future maintenance planning budgets are based on this initial determination. Tables 5-1 and 5-2 provide the list of maintenance activities incorporated into the SAPMP MicroPAVER database to treat specific distress types and severities.

Table 5-1: Recommended AC, AAC, and APC Maintenance and Repair Policy

| Surface Type                             | Distress Code | Distress Name                    | Severity | Maintenance Work Type        | Work Unit   |
|--|---------------|----------------------------------|----------|------------------------------|-------------|
| Flexible Asphalt Concrete (AC, AAC, APC) | 41            | Alligator Cracking               | L, M, H  | Full Depth Pavement Patch    | Square Feet |
|  | 42            | Bleeding                         | N/A      | Partial Depth Pavement Patch | Square Feet |
|  | 43            | Block Cracking                   | L        | Seal Coat Treatment          | Square Feet |
|  | 43            | Block Cracking                   | M, H     | Full Depth Pavement Patch    | Square Feet |
|  | 44            | Corrugation                      | L, M, H  | Full Depth Pavement Patch    | Square Feet |
|  | 45            | Depression                       | L, M, H  | Full Depth Pavement Patch    | Square Feet |
|  | 46            | Jet Blast Erosion                | L, M, H  | Full Depth Pavement Patch    | Square Feet |
|  | 47            | Joint Reflection Cracking        | L        | Crack Sealing                | Linear Feet |
|  | 47            | Joint Reflection Cracking        | M, H     | Full Depth Pavement Patch    | Square Feet |
|  | 48            | Longitudinal/Transverse Cracking | L, M, H  | Crack Sealing                | Linear Feet |
|  | 49            | Oil Spillage                     | L, M     | Seal Coat Treatment          | Square Feet |
|  | 49            | Oil Spillage                     | H        | Full Depth Pavement Patch    | Square Feet |
|  | 50            | Patch and Utility Patching       | M        | Full Depth Pavement Patch    | Square Feet |
|  | 50            | Patch and Utility Patching       | H        | Full Depth Pavement Patch    | Square Feet |
|  | 51            | Polished Aggregate               | L, M, H  | Slurry Seal Coat Treatment   | Square Feet |
|  | 52            | Raveling                         | L, M     | Slurry Seal Coat Treatment   | Square Feet |
|  | 52            | Raveling                         | H        | Partial Depth Pavement Patch | Square Feet |
|  | 53            | Rutting                          | L, M, H  | Full Depth Pavement Patch    | Square Feet |
|  | 54            | Shoving                          | L, M, H  | Grinding / Removal           | Square Feet |
|  | 55            | Slippage Cracking                | L, M, H  | Full Depth Pavement Patch    | Square Feet |
|  | 56            | Swelling                         | M, H     | Full Depth Pavement Patch    | Square Feet |
|  | 57            | Weathering                       | M, H     | Seal Coat Treatment          | Square Feet |

Table 5-2: Recommended PCC Maintenance and Repair Policy

| Surface Type         | Distress Code | Distress Name                             | Severity | Maintenance Work Type               | Work Unit   |
|----------------------|---------------|---|----------|-------------------------------------|-------------|
| Rigid Pavement (PCC) | 61            | Blowup                                    | L, M, H  | Slab Replacement / Full Depth Patch | Square Feet |
|                      | 62            | Corner Break                              | L, M, H  | Partial Slab Full Depth Patch - PCC | Square Feet |
|                      | 63            | Longitudinal/Transverse/Diagonal Cracking | H        | Crack Sealing - PCC                 | Linear Feet |
|                      | 64            | Durability Cracking                       | M, H     | Slab Replacement / Full Depth Patch | Square Feet |
|                      | 65            | Joint Seal Damage                         | L, M, H  | Joint Seal Repair (Local)           | Linear Feet |
|                      | 66            | Patching, Small                           | M, H     | Partial Slab Full Depth Patch - PCC | Square Feet |
|                      | 67            | Patching, Large                           | M, H     | Partial Slab Full Depth Patch - PCC | Square Feet |
|                      | 69            | Pumping                                   | L, M, H  | Slab Stabilization / Slab Jacking   | Square Feet |
|                      | 70            | Scaling/Map Cracking/Crazing              | L, M     | Micro-mill and Seal - PCC           | Square Feet |
|                      | 70            | Scaling/Map Cracking/Crazing              | H        | Slab Replacement / Full Depth Patch | Square Feet |
|                      | 71            | Settlement / Faulting                     | L        | Micro-mill and Seal - PCC           | Square Feet |
|                      | 71            | Settlement / Faulting                     | M, H     | Slab Stabilization / Slab Jacking   | Square Feet |
|                      | 72            | Shattered Slab                            | L, M, H  | Slab Replacement / Full Depth Patch | Square Feet |
|                      | 73            | Shrinkage Cracks                          | N/A      | Crack Sealing - PCC                 | Linear Feet |
|                      | 74            | Longitudinal/Transverse Joint Spalling    | L, M, H  | Partial Patch - PCC                 | Square Feet |

| Surface Type | Distress Code | Distress Name          | Severity | Maintenance Work Type               | Work Unit   |
|--------------|---------------|------------------------|----------|-------------------------------------|-------------|
|              | 75            | Corner Spalling        | L, M, H  | Partial Patch - PCC                 | Square Feet |
|              | 76            | Alkali-Silica Reaction | L        | Seal Coat Treatment                 | Square Feet |
|              | 76            | Alkali-Silica Reaction | M        | Micro-mill and Seal - PCC           | Square Feet |
|              | 76            | Alkali-Silica Reaction | H        | Slab Replacement / Full Depth Patch | Square Feet |

Though proactive pavement maintenance and preservation is highly recommended in an APMS; it is recognized that pavement that has deteriorated below a certain PCI would benefit more from major rehabilitation rather than localized maintenance and repair work. Major rehabilitation is recommended when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that maintenance repair efforts are no longer cost-efficient. This critical point is called "Critical PCI". The critical PCI levels for different pavement and branch types were established by the FDOT and were used in this update to develop a maintenance and major rehabilitation plan for the airport. Sections that are above the "Critical PCI" levels will be recommended for maintenance, repair, and preservation treatments, assuming there are no significant load-related distresses. For those Sections below the Critical PCI, the recommended action will consist of major rehabilitation work. This approach is used for the Section's Current PCI value and the predicted PCI value for future rehabilitation.

The FDOT has recommended minimum service level PCI for airports based on pavement facility use, airport type, and expected loading frequency. This minimum service level PCI is recommended to ensure the pavement provides a safe operational surface and efficiently uses maintenance and rehabilitation budgets. Separately, the Critical PCI is a value based on historic pavement performance trends and costs. It is at a PCI value of 65, for most airports, at which major rehabilitation is recommended over maintenance level efforts. Table 5-3 identifies the FDOT recommended PCI by use and the critical PCI value for the most important pavements at the airport. This is due to the condition of the pavement and the cost effectiveness of the work. A very important concept of a good pavement management system is the proactive preservation of



pavements that are above Critical PCI condition. Conversely, allowing pavement to deteriorate beyond maintenance and performing “worst first” major rehabilitation may cost much more over the life of a pavement.

**Table 5-3: Critical and Minimum Service Level PCI for Primary Airports**

| Use     | FDOT Recommended PCI | Critical PCI |
|---------|----------------------|--------------|
| Runway  | 75                   | 65           |
| Taxiway | 70                   | 65           |
| Apron   | 65                   | 65           |

Based on historic trends of pavement performance and industry standard practices in pavement maintenance and rehabilitation, the SAPMP included general guidance on construction activity based on condition PCI, as shown on Table 5-4. It is recommended that further investigation of underlying pavement conditions is performed at the design phase.

**Table 5-4: Maintenance and Major Rehabilitation Activity Based on PCI**

| Category       | Activity  | PCI Range |
|----------------|---|-----------|
| Maintenance    | <ul style="list-style-type: none"> <li>▪ Crack Sealing (AC/PCC)</li> <li>▪ Partial Depth Patching (AC)</li> <li>▪ Full Depth Patching (AC/PCC)</li> <li>▪ Surface Treatment (AC)</li> </ul> | 75 - 90   |
| Rehabilitation | <ul style="list-style-type: none"> <li>▪ Mill and Overlay (AC)</li> <li>▪ Concrete Pavement Restoration (PCC)</li> </ul>  | 40 - 74   |
|                | <ul style="list-style-type: none"> <li>▪ Full Depth Pavement Reconstruction</li> </ul>  | 0 - 39    |

The PCI standard scale ranges from a value of 0, typically representing a pavement in a failed condition, to a value of 100 which typically represents a pavement in new or good condition. Generally, airfield pavement sections with a PCI of 75 or higher that are not exhibiting distresses due to aircraft loading will benefit from maintenance activities such as crack sealing, patching, and surface treatments. Pavement sections with PCI values within the range of 40 to 74 may require major rehabilitation, such as a mill and overlay. Lastly, pavement sections with a PCI value of 40 or less are recommended to undergo pavement

reconstruction. Generally pavement reconstruction is the only practical means of restoration due to the substantial distresses observed in the pavement structure. Since PCI values are based solely on the visual determination of pavement distresses and deterioration, this method does not provide a direct measure of structural integrity.

## 5.2 Unit Costs

The FDOT SAPMP developed and updated the maintenance and major rehabilitation costs based on public cost databases for airport and highway pavement construction. Additionally, cost data collected from FDOT and FAA sponsored projects in the Florida Airports System were utilized to identify construction cost trends across the state.

The maintenance, repair, and preservation activity costs have been updated and developed using readily available construction cost data at the time of this update. The costs depicted in this report for both maintenance and major rehabilitation are intended for planning purposes.

## 5.3 Maintenance, Repair, and Major Rehabilitation

FDOT recognizes that although pavement mill and overlay is recommended for flexible asphalt concrete pavement within a PCI range from 40 to 74, it is conceivable that airports may not have adequate funding to perform this type of major rehabilitation. A comprehensive surface treatment; per the treatments described in FAA AC 150/5370-10G Standards for Specifying Construction of Airports, as a maintenance rehabilitation activity, can be used in lieu of asphalt concrete pavement mill and overlay. However, it should be understood that these measures provide only a short term extension of pavement life. While the cost of surface treatments are significantly lower than that of pavement mill and overlay, it is not intended or implied to be a full rehabilitative measure for long term benefit. Table 5-5 and Table 5-6 provide budget costs associated with the work types shown in the table.

Table 5-5: AC Maintenance Unit Costs

| Surface Type                                | Maintenance Work Type        | Cost   | Work Unit   |
|---|------------------------------|--------|-------------|
| Flexible Asphalt Concrete<br>(AC, AAC, APC) | Full Depth Pavement Patch    | \$5.00 | Square Feet |
|   | Partial Depth Pavement Patch | \$3.00 | Square Feet |
|   | Seal Coat Treatment          | \$0.55 | Square Feet |
|   | Crack Sealing                | \$2.75 | Linear Feet |
|   | Slurry Seal Coat Treatment   | \$0.55 | Square Feet |
|   | Grinding / Removal           | \$2.10 | Square Feet |

Table 5-6: PCC Maintenance Unit Costs

| Surface Type            | Maintenance Work Type               | Cost    | Work Unit   |
|-------------------------|-------------------------------------|---------|-------------|
| Rigid Pavement<br>(PCC) | Slab Replacement / Full Depth Patch | \$45.00 | Square Feet |
|                         | Partial Patch - PCC                 | \$19.10 | Square Feet |
|                         | Crack Sealing - PCC                 | \$4.25  | Linear Feet |
|                         | Joint Seal Repair (Local)           | \$3.00  | Linear Feet |
|                         | Slab Stabilization / Slab Jacking   | \$45.00 | Square Feet |
|                         | Micro-mill and Seal - PCC           | \$1.00  | Square Feet |
|                         | Seal Coat Treatment                 | \$1.00  | Square Feet |

As part of the SAPMP update, the distress data observed at each airport during the inspection is extrapolated on a section basis to make maintenance recommendations. These recommendations are a direct result of the distress types, severities, and quantities observed at the time of inspection. The maintenance recommendations and planning costs are correlated with the airport's airfield pavement network's overall area weighted PCI and used to plan

future maintenance costs. Future maintenance costs are planning budgets that are not specific to a pavement section, but are estimates for the entire airfield. Table 5-7 provides budget costs associated with the rehabilitation activities.

**Table 5-7: Rehabilitation Activities and Unit Costs by Condition for Primary Airports**

| Category       | Activity                              | PCI Range | Cost/SqFt |
|----------------|---------------------------------------|-----------|-----------|
| Rehabilitation | ▪ Mill and Overlay (AC)               | 40 - 74   | \$13.00   |
|                | ▪ Concrete Pavement Restoration (PCC) |           | \$18.00   |
|                | ▪ Full Depth Pavement Reconstruction  | 0 - 39    | \$23.00   |

A cost scale has been developed based on PCI to develop planning level budgets for the airfield pavements. The cost scale is adjusted by project year based on an assumed inflation rate of 3%. In Appendix E, Table E-1 summarizes the Year-1 maintenance and repair recommendations based on the most recent inspection. The summary in Table E-1 does not take into account any rehabilitation activities, but rather summarizes preventative activities for all PCI ranges, including below critical PCI sections.

## 6. MAJOR PAVEMENT REHABILITATION NEEDS

---

As part of the SAPMP, major pavement rehabilitation planning is developed based on current and predicted PCI in comparison with the Critical PCI. The Critical PCI has been determined based on the historic trends of pavement condition relative to the benefit of maintenance and repair activities. Pavement sections determined to have a PCI less than that of the Critical PCI are assumed to have deteriorated to a point at which maintenance and repair level activity would provide little benefit.

The objective of the major pavement rehabilitation needs analysis is to provide planning level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value from a functionality perspective. In addition, major rehabilitation is also recommended when the Section PCI is above the Critical PCI but the Section has load-related PCI distresses. However, most major rehabilitation work is recommended when the Section PCI is below the Critical PCI, which is when maintenance and repair level activities are not considered to be cost effective.

Major rehabilitation is identified within the SAPMP as major construction activity that would result in an improvement or "resetting" of the pavement section's PCI to a value of 100. Such activities could include; mill and hot-mix asphalt overlay and re-construction. This analysis was conducted with no constraints to budgets as a means to identify all pavement projects based on Critical PCI for a 10-year duration. It is recommended that the airport use this as a planning tool for future project development and prioritization. Table 6-1 depicts the major rehabilitation work identified on the pavement section level based on current and predicted pavement PCI.

Airports should consider the major rehabilitation work types of mill and overlay, PCC restoration, and reconstruction planning level classifications only. Additional design level investigation in accordance to the FAA Advisory Circulars will be required to identify specific areas within each section that are subject to reconstruction, mill and overlay, and PCC restoration. The work and budgets identified are intended for the planning level not the design level. Areas identified as mill and overlay may in fact require select areas of reconstruction should load-based distresses observed warrant it.

Table 6-1: Summary of Major Rehabilitation


| Year    | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity     | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2015    | AP E      | 4405       | \$ 4,594,320.00  | 62             | Mill and Overlay | 100           |
| 2015    | AP S      | 4510       | \$ 6,088,788.00  | 50             | Mill and Overlay | 100           |
| 2015    | AP TERM   | 4230       | \$ 546,503.00    | 8              | Reconstruction   | 100           |
| 2015    | TW A1     | 120        | \$ 1,090,177.00  | 37             | Reconstruction   | 100           |
| 2016    | TW B7     | 270        | \$ 276,227.00    | 64             | Mill and Overlay | 100           |
| 2017    | AP S      | 4515       | \$ 4,183,844.00  | 64             | Mill and Overlay | 100           |
| 2017    | TW A7     | 215        | \$ 1,377,982.00  | 64             | Mill and Overlay | 100           |
| 2019    | AP S      | 4505       | \$ 2,279,966.00  | 64             | Mill and Overlay | 100           |
| 2019    | AP W      | 4605       | \$ 4,444,292.00  | 64             | Mill and Overlay | 100           |
| 2021    | RW 8-26   | 6215       | \$ 2,041,830.00  | 64             | Mill and Overlay | 100           |
| 2021    | RW 8-26   | 6235       | \$ 3,653,800.00  | 64             | Mill and Overlay | 100           |
| 2021    | RW 8-26   | 6245       | \$ 859,718.00    | 65             | Mill and Overlay | 100           |
| 2021    | TW C      | 252        | \$ 353,580.00    | 65             | Mill and Overlay | 100           |
| 2022    | RW 8-26   | 6225       | \$ 1,992,329.00  | 65             | Mill and Overlay | 100           |
| 2022    | RW 8-26   | 6255       | \$ 1,328,264.00  | 65             | Mill and Overlay | 100           |
| 2022    | TW A      | 115        | \$ 6,594,631.00  | 64             | Mill and Overlay | 100           |
| 2023    | RW 17-35  | 6115       | \$ 1,197,098.00  | 64             | Mill and Overlay | 100           |
| 2023    | RW 8-26   | 6205       | \$ 2,964,242.00  | 64             | Mill and Overlay | 100           |
| 2023    | TW A2     | 160        | \$ 854,910.00    | 65             | Mill and Overlay | 100           |
| 2023    | TW B      | 217        | \$ 250,820.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW B8     | 280        | \$ 303,652.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW C      | 505        | \$ 299,571.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW D      | 140        | \$ 995,256.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW D      | 410        | \$ 459,640.00    | 64             | Mill and Overlay | 100           |
| 2024    | RW 8-26   | 6210       | \$ 1,526,585.00  | 65             | Mill and Overlay | 100           |
| 2024    | RW 8-26   | 6220       | \$ 1,115,581.00  | 64             | Mill and Overlay | 100           |
| 2024    | TW B      | 210        | \$ 1,220,845.00  | 65             | Mill and Overlay | 100           |
| Total = |           |            | \$ 52,894,451.00 |                |                  |               |

\*Costs are adjusted for inflation at 3%.

The 10-year major rehabilitation program addresses those pavement sections that have a current or project PCI that is below the Critical PCI of 65 during the 10-year analysis period. The unconstrained or “unlimited budget” Major Rehabilitation Program is compared to a “No Major Rehabilitation Program” scenario in Figure 6-1. As shown, if no major rehabilitation work is completed in the next 10 years at your airport, the average PCI may be 17 points less than a plan that provides timely repairs to the airfield pavements.



Figure 6-1: 10-Year Major Rehabilitation Budget Scenario Analysis





## 7. PREVENTATIVE AND MAJOR REHABILITATION PLANNING


The preventative and major rehabilitation results include activities that are based on distresses observed and unconstrained by budget limits. FDOT recognizes that the projects identified as Year-1 needs in 2015, based on condition, may exceed a typical annual budget level. It is recommended that each airport further evaluate each project's feasibility and desirability based on the airport's future development plans and budgeting scenarios.

In an effort to identify appropriate budget levels, the 10-year Preventative and Major Rehabilitation analysis evaluated projected budget needs based on predicted PCI of each pavement section. Table 7-1 and Figure 7-1 provides a summary of the expected preventative and major rehabilitation for each program year.

Table 7-1: 10-Year Preventative and Major Rehabilitation Summary

| Program Year | Preventative    | Major Rehabilitation | Total Year Costs |
|--------------|-----------------|----------------------|------------------|
| 2015         | \$ 1,061,869.86 | \$ 12,319,788.25     | \$ 13,381,658.11 |
| 2016         | \$ 1,164,419.15 | \$ 276,227.47        | \$ 1,440,646.62  |
| 2017         | \$ 1,168,247.89 | \$ 5,561,825.80      | \$ 6,730,073.70  |
| 2018         | \$ 1,301,233.45 | \$ -                 | \$ 1,301,233.45  |
| 2019         | \$ 1,296,832.08 | \$ 6,724,258.16      | \$ 8,021,090.24  |
| 2020         | \$ 1,441,763.35 | \$ -                 | \$ 1,441,763.35  |
| 2021         | \$ 1,459,691.63 | \$ 6,908,927.81      | \$ 8,368,619.45  |
| 2022         | \$ 1,416,189.67 | \$ 9,915,223.89      | \$ 11,331,413.57 |
| 2023         | \$ 1,436,265.37 | \$ 7,325,189.55      | \$ 8,761,454.92  |
| 2024         | \$ 1,548,381.26 | \$ 3,863,010.83      | \$ 5,411,392.10  |
| Total =      |                 |                      | \$ 66,189,345.51 |

Figure 7-1: 10-Year Preventative and Major Rehabilitation Summary



According to the most recent inspections at the time of this update; the following pavement sections were identified as a Year-1 need for major rehabilitation:

- East Apron – Section 4405
  - Mill and Overlay attributed to climate and age of pavement.
- South Apron – Section 4510
  - Mill and Overlay attributed to climate and age of pavement.
- Terminal Apron – Section 4230
  - Reconstruction attributed to load, climate, and age of pavement.
- Taxiway A1 – Section 120
  - Reconstruction attributed to load, climate, and age of pavement.

Appendix E summarizes the preventative repair recommendations for Year-1 and Appendix F provides an exhibit, Airfield Pavement Major Rehabilitation that depicts the recommended major rehabilitation on the airfield pavement network according to work type and year.

## 8. VISUAL AID EXHIBITS

---

### 8.1 Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit in Appendix A depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D 5340-12. The exhibits are prepared and updated with information provided by the airport and from aerial imagery from the FDOT Surveying and Mapping publications.

### 8.2 Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in Appendix A depicts any recent airfield pavement construction activity reported by the airport. The exhibit is intended to identify pavement sections that may have changed in geometry and pavement composition that would affect the section delineation. The information provided in the Airport Response Form was used as the basis of the changes and confirmed with the airport personnel at the time of inspection.

### 8.3 Airfield Pavement Condition Index Rating Exhibit

The Airfield Pavement Condition Index Rating Exhibit in Appendix B has been prepared based on the section condition analysis of the distress data collected during the recent condition index rating survey. The exhibit graphically depicts the inventory with associated condition rating colors and PCI values.

### 8.4 Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit in Appendix F has been prepared based on the section pavement performance model and major rehabilitation analysis. The exhibit graphically depicts the inventory with associated rehabilitation activity, program year, and the planning level costs.

### 8.5 Airfield Pavement Condition Survey Inspection Photographs

During the field condition survey inspection; inspectors photographed representative distress types observed. Select photographs are provided in Appendix G to provide visual support to special pavement conditions or distresses observed.



## 9. RECOMMENDATIONS

---

The recommendations developed are intended for the planning level for each airport. Additional project specific investigation in accordance with the FAA Advisory Circulars is recommended to further refine the project scope and budget requirements.

The following recommendations were made based on the 2015 condition survey inspection, condition analysis, and maintenance/rehabilitation analysis results:

- East Apron – Section 4405
  - Mill and Overlay attributed to climate and age of pavement.
- South Apron – Section 4510, 4515, and 4505
  - Mill and Overlay attributed to climate and age of pavement.
- Terminal Apron – Section 4230
  - Reconstruction attributed to load, climate, and age of pavement.
- Taxiway A1 – Section 120
  - Reconstruction attributed to load, climate, and age of pavement.
- Runway 17-35 – Section 6115
  - Mill and Overlay attributed to climate and age of pavement.
- Runway 8-26 – Sections 6215, 6255, 6245, 6235, 6225, 6220, 6210, and 6205
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway A – Section 115
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway A2 – Section 160
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway A7 – Section 215
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway B – Sections 217 and 210
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway B7 – Section 270
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway B8 – Section 280
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway C – Sections 505 and 252
  - Mill and Overlay attributed to climate and age of pavement.
- Taxiway D – Sections 410 and 140
  - Mill and Overlay attributed to climate and age of pavement.






# APPENDIX A

---

- ◉ AIRFIELD PAVEMENT NETWORK DEFINITION EXHIBIT
- ◉ AIRFIELD PAVEMENT SYSTEM INVENTORY EXHIBIT
- ◉ PAVEMENT GEOMETRY INVENTORY
- ◉ WORK HISTORY REPORT





|             |            |              |             |            |            |            |            |            |            |            |            |
|-------------|------------|--------------|-------------|------------|------------|------------|------------|------------|------------|------------|------------|
| 105         | 115        | 120          | 125         | 130        | 140        | 150        | 160        | 170        | 205        | 210        | 212        |
| AC          | AC         | AC           | AC          | AC         | AC         | AC         | AC         | AC         | AC         | AC         | AC         |
| 75' X 50'   | 75' X 50'  | 104' X 50'   | 104' X 50'  | 104' X 50' | 97' X 50'  | 104' X 50' | 100' X 50' | 18' X 50'  | 104' X 50' | 132' X 50' | 100' X 50' |
| 8           | 8          | 1            | 1           | 1          | 2          | 2          | 1          | 8          | 6          | 1          | 1          |
| 73          | 74         | 9            | 10          | 10         | 9          | 11         | 7          | 52         | 9          | 8          | 8          |
| 213         | 215        | 217          | 220         | 230        | 240        | 250        | 252        | 255        | 260        | 265        | 270        |
| VAR         | AC         | AC           | AC          | AC         | AC         | AC         | AC         | VAR        | AC         | AC         | AC         |
| 125' X 125' | 100' X 50' | 27.5' X 200' | 75' X 50'   | 104' X 50' | 104' X 50' | 104' X 50' | 104' X 50' | 104' X 50' | 104' X 50' | 104' X 50' | 100' X 50' |
| 1           | 3          | 1            | 7           | 4          | 1          | 1          | 1          | 1          | 2          | 1          | 1          |
| 4           | 17         | 2            | 68          | 28         | 10         | 7          | 3          | 10         | 10         | 10         | 3          |
| 280         | 405        | 410          | 415         | 420        | 425        | 430        | 505        | 510        | 515        | 4205       | 4210       |
| AC          | AC         | VAR          | AC          | 100' X 35' | 100' X 35' | AC         | AC         | AC         | AC         | AC         | AC         |
| 1           | 3          | 4            | 1           | 1          | 1          | 3          | 1          | 3          | 1          | 10         | 7          |
| 3           | 33         | 4            | 3           | 3          | 3          | 12         | 3          | 19         | 9          | 122        | 89         |
| 4215        | 4220       | 4225         | 4230        | 4235       | 4310       | 4315       | 4320       | 4325       | 4405       | 4505       | 4510       |
| VAR         | AC         | AC           | AC          | AC         | AC         | AC         | AC         | AC         | AC         | VAR        | AC         |
| 20' X 50'   | 20' X 50'  | 18' X 50'    | 92.5' X 50' | 20' X 50'  | 20' X 50'  | 20' X 50'  | 78' X 50'  | 100' X 50' | 80' X 45'  | VAR        | 100' X 50' |
| 1           | 3          | 3            | 1           | 4          | 2          | 1          | 1          | 7          | 87         | 3          | 73         |
| 8           | 25         | 18           | 5           | 37         | 6          | 1          | 1          | 7          | 87         | 26         | 73         |
| 4515        | 4605       | 4705         | 4710        | 6105       | 6110       | 6115       | 6120       | 6125       | 6130       | 6205       | 6210       |
| AC          | AC         | AC           | AC          | AC         | AC         | AC         | AC         | AC         | AC         | AC         | AC         |
| 100' X 50'  | 100' X 35' | 20' X 50'    | 20' X 50'   | 18' X 50'  | 12' X 50'  | 50' X 100' | 200' X 25' | 18' X 50'  | 12' X 50'  | 100' X 50' | 200' X 25' |
| 4           | 37         | 5            | 2           | 12         | 7          | 3          | 11         | 58         | 9          | 5          | 3          |
| 37          | 42         | 10           | 20          | 8          | 24         | 1          | 1          | 58         | 30         | 26         | 14         |
| 6215        | 6220       | 6225         | 6230        | 6235       | 6240       | 6245       | 6250       | 6255       | 6260       | 6265       | 6270       |
| AC          | AC         | AC           | AC          | AC         | AC         | AC         | AC         | AC         | AC         | AC         | AC         |
| 100' X 50'  | 200' X 25' | 100' X 50'   | 200' X 25'  | 200' X 25' | 200' X 25' | 100' X 50' | 200' X 25' | 100' X 50' | 200' X 25' | 100' X 50' | 200' X 25' |
| 5           | 18         | 5            | 2           | 7          | 5          | 2          | 1          | 3          | 2          | 5          | 2          |
| 18          | 12         | 18           | 12          | 34         | 16         | 8          | 4          | 12         | 6          | 20         | 10         |

LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- SECTION NUMBER
- PAYMENT TYPE
- TYPICAL SAMPLE UNIT INFORMATION
- FLEXIBLE (AC) PAYMENT LENGTH & WIDTH
- RIGID (PCC) PAYMENT NO. OF SLABS AND SLAB SIZE
- NUMBER OF SAMPLE UNITS IN SECTION
- NUMBER OF SAMPLE UNITS TO BE INSPECTED
- SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 239

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.



| NUMBER    | DATE | REVISIONS  |
|-----------|------|------------|
|           |      |            |
|           |      |            |
|           |      |            |
| DESIGNED: | KHA  | DRAWN: KHA |
| CHECKED:  | KHA  | DATE:      |
|           |      |            |
|           |      |            |

OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS



AIRFIELD PAVEMENT NETWORK DEFINITION EXHIBIT  
PENSACOLA INTERNATIONAL AIRPORT  
ESCAMBIA COUNTY, FLORIDA  
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE





|               |             |              |             |             |             |             |             |             |             |             |             |
|---------------|-------------|--------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| 105           | 115         | 120          | 125         | 130         | 140         | 150         | 160         | 170         | 205         | 210         | 212         |
| AC            | AC          | AC           | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          |
| 75' X 50'     | 75' X 50'   | 104' X 50'   | 104' X 50'  | 104' X 50'  | 97' X 50'   | 104' X 50'  | 100' X 50'  | 18' SLABS W | 104' X 50'  | 132' X 90'  | 100' X 50'  |
| 8 73          | 8 74        | 1 9          | 1 10        | 1 10        | 2 9         | 2 11        | 1 7         | 6 52        | 1 9         | 1 8         | 1 8         |
| 213           | 215         | 217          | 220         | 230         | 240         | 250         | 252         | 255         | 260         | 265         | 270         |
| VAR           | AC          | AC           | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          |
| 12.5' X 12.5' | 100' X 50'  | 27.5' X 200' | 75' X 50'   | 104' X 50'  | 104' X 50'  | 104' X 50'  | VAR         | VAR         | 104' X 50'  | 104' X 50'  | 100' X 50'  |
| 1 4           | 3 17        | 1 2          | 7 68        | 4 28        | 1 10        | 1 7         | 1 3         | 1 10        | 1 10        | 2 10        | 1 3         |
| 280           | 405         | 410          | 415         | 420         | 425         | 430         | 505         | 510         | 515         | 4205        | 4210        |
| AC            | AC          | AC           | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          |
| 100' X 50'    | 100' X 35'  | VAR          | 100' X 35'  | 100' X 40'  | 100' X 35'  | 100' X 35'  | 100' X 35'  | 100' X 35'  | 100' X 35'  | 20' SLABS W | 100' X 50'  |
| 1 3           | 4 33        | 1 4          | 1 3         | 1 3         | 1 3         | 3 12        | 1 3         | 3 19        | 1 9         | 10 122      | 7 89        |
| 4215          | 4220        | 4225         | 4230        | 4235        | 4310        | 4315        | 4320        | 4325        | 4405        | 4505        | 4510        |
| RCC           | RCC         | RCC          | RCC         | RCC         | AAC         | AAC         | AAC         | AAC         | AAC         | AAC         | AAC         |
| VAR           | 20' SLABS W | 20' SLABS W  | 20' SLABS W | 20' SLABS W | 20' SLABS W | 20' SLABS W | 20' SLABS W | 20' SLABS W | 20' SLABS W | 20' SLABS W | 20' SLABS W |
| 1 6           | 5 28        | 3 18         | 1 5         | 4 37        | 2 6         | 1 1         | 1 3         | 1 3         | 7 67        | 3 26        | 8 72        |
| 4515          | 4605        | 4705         | 4710        | 6105        | 6110        | 6115        | 6120        | 6125        | 6130        | 6205        | 6210        |
| AC            | AC          | AC           | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          |
| 100' X 50'    | 100' X 35'  | 20' SLABS W  | 20' SLABS W | 18' SLABS W | 12' SLABS W | 50' X 100'  | 200' X 25'  | 18' SLABS W | 12' SLABS W | 100' X 50'  | 200' X 25'  |
| 4 37          | 5 42        | 2 10         | 2 10        | 12 48       | 7 24        | 3 11        | 2 8         | 15 58       | 9 30        | 5 26        | 3 14        |
| 6215          | 6220        | 6225         | 6230        | 6235        | 6240        | 6245        | 6250        | 6255        | 6260        | 6265        | 6270        |
| AC            | AC          | AC           | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          | AC          |
| 100' X 50'    | 200' X 25'  | 100' X 50'   | 200' X 25'  | 100' X 50'  | 200' X 25'  | 100' X 50'  | 200' X 25'  | 100' X 50'  | 200' X 25'  | 100' X 50'  | 200' X 25'  |
| 5 18          | 5 12        | 5 18         | 3 12        | 7 34        | 5 18        | 2 8         | 1 4         | 3 12        | 2 6         | 5 20        | 2 10        |

CONSTRUCTION SINCE LAST INSPECTION  
& ANTICIPATED CONSTRUCTION ACTIVITY

| CONSTRUCTION YEAR | LOCATION         | WORK TYPE / PAVEMENT SECTION |
|-------------------|------------------|------------------------------|
| 2010              | TERMINAL APRON   | AIR CARRIER APRON EXPANSION  |
| 2015              | NORTH CARGO RAMP | REHABILITATION/NEW PAVEMENT  |

LEGEND

- PROJECTS YEAR 2010
- PROJECTS YEAR 2011
- PROJECTS YEAR 2012
- PROJECTS YEAR 2013
- PROJECTS YEAR 2014
- PROJECTS YEAR 2015
- PROJECTS YEAR 2016
- PROJECTS YEAR 2017
- PROJECTS YEAR 2018
- PROJECTS YEAR 2019

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER    | DATE | REVISIONS  |
|-----------|------|------------|
|           |      |            |
|           |      |            |
|           |      |            |
| DESIGNED: | KHA  | DRAWN: KHA |
| CHECKED:  | KHA  | DATE:      |
|           |      | 2015       |



AIRFIELD PAVEMENT SYSTEM INVENTORY EXHIBIT  
PENSACOLA INTERNATIONAL AIRPORT  
ESCAMBIA COUNTY, FLORIDA  
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE





Table A-1: Pavement Geometry Inventory

| Branch Name  | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT <sup>2</sup> ) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|--------------|-----------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6270       | 1,001       | 50         | 50,050                       | P            | AC           | 1/1/2006         | 2/10/2015       | 10            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6265       | 1,001       | 100        | 100,100                      | P            | AC           | 1/1/2006         | 2/10/2015       | 20            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6260       | 600         | 50         | 30,000                       | P            | AC           | 1/1/2004         | 2/10/2015       | 6             |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6255       | 600         | 100        | 60,000                       | P            | AC           | 1/1/2004         | 2/10/2015       | 12            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6250       | 400         | 50         | 20,000                       | P            | AC           | 1/1/2004         | 2/10/2015       | 4             |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6245       | 400         | 100        | 40,000                       | P            | AC           | 1/1/2004         | 2/10/2015       | 8             |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6240       | 1,700       | 50         | 85,000                       | P            | AC           | 1/1/2004         | 2/10/2015       | 18            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6235       | 1,700       | 100        | 170,000                      | P            | AC           | 1/1/2004         | 2/10/2015       | 34            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6230       | 900         | 50         | 44,999                       | P            | AC           | 1/1/2004         | 2/10/2015       | 12            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6225       | 900         | 100        | 89,997                       | P            | AC           | 1/1/2004         | 2/10/2015       | 18            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6220       | 950         | 50         | 47,500                       | P            | AC           | 1/1/2004         | 2/10/2015       | 12            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6215       | 950         | 100        | 95,000                       | P            | AC           | 1/1/2004         | 2/10/2015       | 19            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6210       | 1,300       | 50         | 65,000                       | P            | AC           | 1/1/2004         | 2/10/2015       | 14            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6205       | 1,300       | 100        | 130,000                      | P            | AC           | 1/1/2004         | 2/10/2015       | 26            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6130       | 3,520       | 38         | 131,789                      | P            | PCC          | 11/1/2007        | 2/10/2015       | 30            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6125       | 3,520       | 113        | 396,211                      | P            | PCC          | 11/1/2007        | 2/10/2015       | 59            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6120       | 525         | 50         | 26,250                       | P            | AC           | 11/1/2007        | 2/10/2015       | 6             |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6115       | 525         | 100        | 52,500                       | P            | AC           | 11/1/2007        | 2/10/2015       | 11            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6110       | 2,960       | 38         | 110,822                      | P            | PCC          | 11/1/2007        | 2/10/2015       | 24            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6105       | 2,960       | 113        | 33,178                       | P            | PCC          | 11/1/2007        | 2/10/2015       | 49            |
| CARGO APRON  | AP CARGO  | APRON      | 4710       | 500         | 250        | 145,521                      | P            | PCC          | 1/1/2015         | 1/1/2015        | 0             |
| CARGO APRON  | AP CARGO  | APRON      | 4705       | 350         | 200        | 68,880                       | P            | PCC          | 1/1/2015         | 1/1/2015        | 0             |
| APRON WEST   | AP W      | APRON      | 4605       | 710         | 310        | 219,372                      | P            | AC           | 1/1/2002         | 2/10/2015       | 42            |
| SOUTH APRON  | AP S      | APRON      | 4515       | 935         | 230        | 219,093                      | T            | AC           | 1/1/1997         | 2/10/2015       | 37            |





# Pavement Evaluation Report - Pensacola International Airport

| Branch Name    | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT <sup>2</sup> ) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|----------------|-----------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| SOUTH APRON    | AP S      | APRON      | 4510       | 3,230       | 105        | 338,266                      | T            | AC           | 1/1/1997         | 2/10/2015       | 72            |
| SOUTH APRON    | AP S      | APRON      | 4505       | 1,680       | 70         | 112,540                      | T            | AC           | 1/1/1997         | 2/10/2015       | 26            |
| EAST APRON     | AP E      | APRON      | 4405       | 985         | 260        | 255,240                      | P            | AC           | 12/25/1999       | 2/10/2015       | 67            |
| GA APRON       | AP GA     | APRON      | 4325       | 475         | 200        | 37,703                       | P            | AAC          | 1/1/2015         | 1/1/2015        | 0             |
| GA APRON       | AP GA     | APRON      | 4320       | 275         | 78         | 12,201                       | P            | AAC          | 1/1/2015         | 1/1/2015        | 0             |
| GA APRON       | AP GA     | APRON      | 4315       | 110         | 90         | 9,900                        | P            | PCC          | 1/1/2015         | 1/1/2015        | 0             |
| GA APRON       | AP GA     | APRON      | 4310       | 210         | 150        | 26,365                       | P            | AAC          | 1/1/2015         | 1/1/2015        | 0             |
| TERMINAL APRON | AP TERM   | APRON      | 4235       | 1,000       | 130        | 127,593                      | P            | PCC          | 12/25/1998       | 2/10/2015       | 37            |
| TERMINAL APRON | AP TERM   | APRON      | 4230       | 230         | 92         | 23,761                       | P            | AC           | 1/1/2001         | 2/10/2015       | 5             |
| TERMINAL APRON | AP TERM   | APRON      | 4225       | 710         | 150        | 106,612                      | P            | PCC          | 1/1/2010         | 2/10/2015       | 18            |
| TERMINAL APRON | AP TERM   | APRON      | 4220       | 300         | 300        | 76,245                       | P            | PCC          | 1/1/2010         | 2/10/2015       | 29            |
| TERMINAL APRON | AP TERM   | APRON      | 4215       | 700         | 70         | 42,079                       | P            | PCC          | 1/1/2010         | 2/10/2015       | 6             |
| TERMINAL APRON | AP TERM   | APRON      | 4210       | 600         | 500        | 256,288                      | P            | PCC          | 1/1/1977         | 2/10/2015       | 69            |
| TERMINAL APRON | AP TERM   | APRON      | 4205       | 800         | 600        | 367,057                      | T            | PCC          | 1/1/1988         | 2/10/2015       | 122           |
| TAXIWAY C2     | TW C2     | TAXIWAY    | 515        | 882         | 35         | 31,643                       | P            | AC           | 1/1/1997         | 2/10/2015       | 9             |
| TAXIWAY C      | TW C      | TAXIWAY    | 510        | 1,864       | 35         | 67,178                       | P            | AC           | 1/1/1997         | 2/10/2015       | 19            |
| TAXIWAY C      | TW C      | TAXIWAY    | 505        | 308         | 35         | 13,138                       | P            | AC           | 1/1/1997         | 2/10/2015       | 3             |
| TAXIWAY D      | TW D      | TAXIWAY    | 430        | 1,340       | 35         | 48,300                       | P            | AC           | 1/1/2005         | 2/10/2015       | 12            |
| TAXIWAY D3     | TW D3     | TAXIWAY    | 425        | 308         | 40         | 14,220                       | P            | AAC          | 1/1/2006         | 2/10/2015       | 3             |
| TAXIWAY D2     | TW D2     | TAXIWAY    | 420        | 308         | 35         | 13,134                       | P            | AC           | 1/1/2000         | 2/10/2015       | 3             |
| TAXIWAY D1     | TW D1     | TAXIWAY    | 415        | 308         | 35         | 13,134                       | P            | AC           | 1/1/2000         | 2/10/2015       | 3             |
| TAXIWAY D      | TW D      | TAXIWAY    | 410        | 132         | 154        | 20,158                       | P            | AC           | 1/1/2005         | 2/10/2015       | 4             |
| TAXIWAY D      | TW D      | TAXIWAY    | 405        | 3,352       | 35         | 118,752                      | P            | AC           | 1/1/2000         | 2/10/2015       | 33            |
| TAXIWAY B8     | TW B8     | TAXIWAY    | 280        | 228         | 50         | 13,317                       | P            | AC           | 1/1/2002         | 2/10/2015       | 3             |
| TAXIWAY B7     | TW B7     | TAXIWAY    | 270        | 228         | 50         | 14,899                       | P            | AC           | 1/1/2002         | 2/10/2015       | 3             |
| TAXIWAY B5     | TW B5     | TAXIWAY    | 265        | 375         | 104        | 48,322                       | P            | AC           | 1/1/2002         | 2/10/2015       | 10            |
| TAXIWAY B4     | TW B4     | TAXIWAY    | 260        | 375         | 104        | 50,114                       | P            | AC           | 1/1/2002         | 2/10/2015       | 10            |

| Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | True Area (FT <sup>2</sup> ) | Section Rank | Surface Type | Last Const. Date | Last Insp. Date | Total Samples |
|-------------|-----------|------------|------------|-------------|------------|------------------------------|--------------|--------------|------------------|-----------------|---------------|
| TAXIWAY B3  | TW B3     | TAXIWAY    | 255        | 375         | 104        | 50,248                       | P            | AC           | 1/1/2002         | 2/10/2015       | 10            |
| TAXIWAY C   | TW C      | TAXIWAY    | 252        | 200         | 75         | 16,451                       | P            | AC           | 1/1/2002         | 2/10/2015       | 3             |
| TAXIWAY C   | TW C      | TAXIWAY    | 250        | 300         | 104        | 33,625                       | P            | AC           | 1/1/2004         | 2/10/2015       | 7             |
| TAXIWAY B2  | TW B2     | TAXIWAY    | 240        | 375         | 104        | 50,378                       | P            | AC           | 1/1/2002         | 2/10/2015       | 10            |
| TAXIWAY B   | TW B      | TAXIWAY    | 230        | 1,450       | 75         | 124,670                      | P            | AC           | 1/1/2005         | 2/10/2015       | 29            |
| TAXIWAY B   | TW B      | TAXIWAY    | 220        | 3,367       | 75         | 256,627                      | P            | AC           | 1/1/2002         | 2/10/2015       | 68            |
| TAXIWAY B   | TW B      | TAXIWAY    | 217        | 400         | 28         | 11,000                       | P            | AC           | 1/1/2002         | 2/10/2015       | 2             |
| TAXIWAY A7  | TW A7     | TAXIWAY    | 215        | 310         | 230        | 72,160                       | P            | AC           | 1/1/2002         | 2/10/2015       | 17            |
| TAXIWAY B2  | TW B2     | TAXIWAY    | 213        | 113         | 75         | 10,751                       | P            | PCC          | 1/1/1988         | 2/10/2015       | 4             |
| TAXIWAY B2  | TW B2     | TAXIWAY    | 212        | 200         | 150        | 32,535                       | P            | AC           | 1/1/2002         | 2/10/2015       | 8             |
| TAXIWAY B   | TW B      | TAXIWAY    | 210        | 347         | 132        | 51,982                       | P            | AC           | 1/1/2002         | 2/10/2015       | 9             |
| TAXIWAY B   | TW B      | TAXIWAY    | 205        | 2,485       | 75         | 213,853                      | P            | AC           | 1/1/2002         | 2/10/2015       | 52            |
| TAXIWAY A3  | TW A3     | TAXIWAY    | 170        | 375         | 103        | 50,051                       | T            | PCC          | 1/1/2006         | 2/10/2015       | 8             |
| TAXIWAY A2  | TW A2     | TAXIWAY    | 160        | 340         | 100        | 37,493                       | P            | AC           | 1/1/2000         | 2/10/2015       | 7             |
| TAXIWAY A2  | TW A2     | TAXIWAY    | 150        | 375         | 104        | 55,331                       | P            | AAC          | 1/1/2006         | 2/10/2015       | 11            |
| TAXIWAY D   | TW D      | TAXIWAY    | 140        | 375         | 97         | 43,648                       | P            | AC           | 1/1/2001         | 2/10/2015       | 9             |
| TAXIWAY A4  | TW A4     | TAXIWAY    | 130        | 375         | 104        | 49,968                       | P            | AC           | 1/1/2001         | 2/10/2015       | 10            |
| TAXIWAY A5  | TW A5     | TAXIWAY    | 125        | 375         | 104        | 49,806                       | P            | AC           | 1/1/2001         | 2/10/2015       | 10            |
| TAXIWAY A1  | TW A1     | TAXIWAY    | 120        | 375         | 104        | 47,399                       | P            | AC           | 1/1/2001         | 2/10/2015       | 9             |
| TAXIWAY A   | TW A      | TAXIWAY    | 115        | 3,690       | 75         | 297,891                      | P            | AC           | 2/1/2001         | 2/10/2015       | 74            |
| TAXIWAY A   | TW A      | TAXIWAY    | 105        | 3,620       | 75         | 286,014                      | P            | AC           | 1/1/2001         | 2/10/2015       | 73            |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.



Date:05/14/2015

# Work History Report

1 of 11

*Pavement Database:FDOT*

**Network:** PNS **Branch:** AP CARGO (CARGO APRON) **Section:** 4705 **Surface:** PCC  
**L.C.D.:** 01/01/2015 **Use:** APRON **Rank P Length:** 350.00 Ft **Width:** 200.00 Ft **True Area:** 68,880.00 SqF

| Work Date  | Work Code | Work Description           | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|----------------------------|------|----------------|-----------|---|
| 01/01/2015 | NU-IN     | New Construction - Initial | \$0  | 0.00           | True      | 14" P-501, 4" P-401/P-403 BASE, 8" P-209, 12" P-154 |

**Network:** PNS **Branch:** AP CARGO (CARGO APRON) **Section:** 4710 **Surface:** PCC  
**L.C.D.:** 01/01/2015 **Use:** APRON **Rank P Length:** 500.00 Ft **Width:** 250.00 Ft **True Area:** 145,521.00 SqF

| Work Date  | Work Code | Work Description           | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|----------------------------|------|----------------|-----------|---|
| 01/01/2015 | NU-IN     | New Construction - Initial | \$0  | 0.00           | True      | 14" P-501, 4" P-401/P-403 BASE, 8" P-209, 12" P-154 |

**Network:** PNS **Branch:** AP E (EAST APRON) **Section:** 4405 **Surface:** AC  
**L.C.D.:** 12/25/1999 **Use:** APRON **Rank P Length:** 985.00 Ft **Width:** 260.00 Ft **True Area:** 255,240.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 12/25/1999 | INITIAL   | Initial Construction | \$0  | 0.00           | True      |          |

**Network:** PNS **Branch:** AP GA (GA APRON) **Section:** 4310 **Surface:** AAC  
**L.C.D.:** 01/01/2015 **Use:** APRON **Rank P Length:** 210.00 Ft **Width:** 150.00 Ft **True Area:** 26,365.00 SqF

| Work Date  | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments                                |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/2015 | ML-OV     | MILL and OVERLAY | \$0  | 0.00           | True      | 2015: 3" ML & OL                        |
| 01/01/1990 | IMPORTED  | BUILT            |      | 4.00           | True      | 1990: 4" P-401 SURFACE ON 9" P-401 BASE |

**Network:** PNS **Branch:** AP GA (GA APRON) **Section:** 4315 **Surface:** PCC  
**L.C.D.:** 01/01/2015 **Use:** APRON **Rank P Length:** 110.00 Ft **Width:** 90.00 Ft **True Area:** 9,900.00 SqF

| Work Date  | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments                              |
|------------|-----------|------------------|------|----------------|-----------|---------------------------------------|
| 01/01/2015 | ML-OV     | MILL and OVERLAY | \$0  | 0.00           | True      | 2015: 3" ML & OL                      |
| 01/01/1990 | IMPORTED  | BUILT            |      |                | True      | EST 1990 PCC PAVEMENT SECTION UNKNOWN |

**Network:** PNS **Branch:** AP GA (GA APRON) **Section:** 4320 **Surface:** AAC  
**L.C.D.:** 01/01/2015 **Use:** APRON **Rank P Length:** 275.00 Ft **Width:** 78.00 Ft **True Area:** 12,201.00 SqF

| Work Date  | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments                                    |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/2015 | ML-OV     | MILL and OVERLAY | \$0  | 0.00           | True      | 2015: 3" ML & OL                            |
| 01/01/1990 | IMPORTED  | BUILT            |      |                | True      | 1990: P-401 OVERLAY ON EX. FLXIBLE PAVEMENT |

**Network:** PNS **Branch:** AP GA (GA APRON) **Section:** 4325 **Surface:** AAC  
**L.C.D.:** 01/01/2015 **Use:** APRON **Rank P Length:** 475.00 Ft **Width:** 200.00 Ft **True Area:** 37,703.00 SqF

| Work Date  | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|------------------|------|----------------|-----------|---|
| 01/01/2015 | ML-OV     | MILL and OVERLAY | \$0  | 0.00           | True      | 2015: 3" ML & OL  |
| 01/01/1988 | IMPORTED  | BUILT            |      | 4.00           | True      | 1988: P-609 ON 4" P-401 ON 8" P-304 (CEMENT TREATED BASE) |

**Network:** PNS **Branch:** AP S (SOUTH APRON) **Section:** 4505 **Surface:** AC  
**L.C.D.:** 01/01/1997 **Use:** APRON **Rank T Length:** 1,680.00 Ft **Width:** 70.00 Ft **True Area:** 112,540.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments                  |
|------------|-----------|----------------------|------|----------------|-----------|---------------------------|
| 01/01/1997 | INITIAL   | Initial Construction | \$0  | 2.00           | True      | 2" P-401, 6" P-209, P-152 |

Date:05/14/2015

# Work History Report

2 of 11

Pavement Database:FDOT

Network: PNS Branch: AP S (SOUTH APRON) Section: 4510 Surface: AC  
 L.C.D.: 01/01/1997 Use: APRON Rank T Length: 3,230.00 Ft Width: 105.00 Ft True Area:338,266.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness ( in ) | Major M&R | Comments                  |
|------------|-----------|----------------------|------|------------------|-----------|---------------------------|
| 01/01/1997 | INITIAL   | Initial Construction | \$0  | 4.00             | True      | 4" P-401, 6" P-209, P-152 |

Network: PNS Branch: AP S (SOUTH APRON) Section: 4515 Surface: AC  
 L.C.D.: 01/01/1997 Use: APRON Rank T Length: 935.00 Ft Width: 230.00 Ft True Area:219,093.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness ( in ) | Major M&R | Comments                  |
|------------|-----------|----------------------|------|------------------|-----------|---------------------------|
| 01/01/1997 | INITIAL   | Initial Construction | \$0  | 4.00             | True      | 4" P-401, 6" P-209, P-152 |

Network: PNS Branch: AP TERM (TERMINAL APRON) Section: 4205 Surface: PCC  
 L.C.D.: 01/01/1988 Use: APRON Rank T Length: 800.00 Ft Width: 600.00 Ft True Area:367,057.00 SqF

| Work Date  | Work Code | Work Description | Cost | Thickness ( in ) | Major M&R | Comments                                 |
|------------|-----------|------------------|------|------------------|-----------|--|
| 01/01/1988 | IMPORTED  | BUILT            |      | 0.50             | True      | 1988: 17-1/2" PCC ON 6" SOIL-CEMENT BASE |

Network: PNS Branch: AP TERM (TERMINAL APRON) Section: 4210 Surface: PCC  
 L.C.D.: 01/01/1977 Use: APRON Rank P Length: 600.00 Ft Width: 500.00 Ft True Area:256,288.00 SqF

| Work Date  | Work Code | Work Description | Cost | Thickness ( in ) | Major M&R | Comments                              |
|------------|-----------|------------------|------|------------------|-----------|---------------------------------------|
| 01/01/1977 | IMPORTED  | BUILT            |      |                  | True      | EST 1977 PCC PAVEMENT SECTION UNKNOWN |

Network: PNS Branch: AP TERM (TERMINAL APRON) Section: 4215 Surface: PCC  
 L.C.D.: 01/01/2010 Use: APRON Rank P Length: 700.00 Ft Width: 70.00 Ft True Area: 42,079.00 SqF

| Work Date  | Work Code | Work Description           | Cost | Thickness ( in ) | Major M&R | Comments        |
|------------|-----------|----------------------------|------|------------------|-----------|-----------------|
| 01/01/2010 | NU-IN     | New Construction - Initial | \$0  | 0.00             | True      | 15.5" - 19" PCC |

Network: PNS Branch: AP TERM (TERMINAL APRON) Section: 4220 Surface: PCC  
 L.C.D.: 01/01/2010 Use: APRON Rank P Length: 300.00 Ft Width: 300.00 Ft True Area: 76,245.00 SqF

| Work Date  | Work Code | Work Description           | Cost | Thickness ( in ) | Major M&R | Comments      |
|------------|-----------|----------------------------|------|------------------|-----------|---------------|
| 01/01/2010 | NU-IN     | New Construction - Initial | \$0  | 0.00             | True      | 15.5"-19" PCC |

Network: PNS Branch: AP TERM (TERMINAL APRON) Section: 4225 Surface: PCC  
 L.C.D.: 01/01/2010 Use: APRON Rank P Length: 710.00 Ft Width: 150.00 Ft True Area:106,612.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness ( in ) | Major M&R | Comments |
|------------|-----------|----------------------|------|------------------|-----------|----------|
| 01/01/2010 | INITIAL   | Initial Construction | \$0  | 0.00             | True      |          |

Network: PNS Branch: AP TERM (TERMINAL APRON) Section: 4230 Surface: AC  
 L.C.D.: 01/01/2001 Use: APRON Rank P Length: 230.00 Ft Width: 92.50 Ft True Area: 23,761.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness ( in ) | Major M&R | Comments                                |
|------------|-----------|----------------------|------|------------------|-----------|---|
| 01/01/2001 | INITIAL   | Initial Construction | \$0  | 12.00            | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152 |

Network: PNS Branch: AP TERM (TERMINAL APRON) Section: 4235 Surface: PCC  
 L.C.D.: 12/25/1998 Use: APRON Rank P Length: 1,000.00 Ft Width: 130.00 Ft True Area:127,593.00 SqF

| Work Date  | Work Code | Work Description           | Cost | Thickness ( in ) | Major M&R | Comments        |
|------------|-----------|----------------------------|------|------------------|-----------|-----------------|
| 12/25/1998 | NU-IN     | New Construction - Initial | \$0  | 0.00             | True      | SECTION UNKNOWN |

Date:05/14/2015

# Work History Report

3 of 11

Pavement Database:FDOT

**Network:** PNS **Branch:** AP W (APRON WEST) **Section:** 4605 **Surface:** AC  
**L.C.D.:** 01/01/2002 **Use:** APRON **Rank P Length:** 710.00 Ft **Width:** 310.00 Ft **True Area:**219,372.00 SqF

| Work Date  | Work Code | Work Description      | Cost | Thickness ( in ) | Major M&R | Comments |
|------------|-----------|-----------------------|------|------------------|-----------|----------|
| 01/01/2002 | NC-AC     | New Construction - AC | \$0  | 0.00             | True      |          |

**Network:** PNS **Branch:** RW 17-35 (RUNWAY 17-35) **Section:** 6105 **Surface:** PCC  
**L.C.D.:** 11/01/2007 **Use:** RUNWAY **Rank P Length:** 2,960.00 Ft **Width:** 112.50 Ft **True Area:** 33,178.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 11/01/2007 | CR-PC     | Complete Reconstruction - PC | \$0  | 0.00             | True      |   |
| 01/01/1977 | IMPORTED  | BUILT                        |      | 0.50             | True      | 1977: 1-1/2" P-401 ON 1-1/2" MIN. P-201 ON EX. FLEX. PAVEMENT |

**Network:** PNS **Branch:** RW 17-35 (RUNWAY 17-35) **Section:** 6110 **Surface:** PCC  
**L.C.D.:** 11/01/2007 **Use:** RUNWAY **Rank P Length:** 2,960.00 Ft **Width:** 38.00 Ft **True Area:**110,822.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 11/01/2007 | CR-PC     | Complete Reconstruction - PC | \$0  | 0.00             | True      |   |
| 01/01/1977 | NU-IN     | New Construction - Initial   | \$0  | 0.50             | True      | 1977: 1-1/2" P-401 ON 1-1/2" MIN. P-201 ON EX. FLEX. PAVEMENT |

**Network:** PNS **Branch:** RW 17-35 (RUNWAY 17-35) **Section:** 6115 **Surface:** AC  
**L.C.D.:** 11/01/2007 **Use:** RUNWAY **Rank P Length:** 525.00 Ft **Width:** 100.00 Ft **True Area:** 52,500.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 11/01/2007 | CR-AC     | Complete Reconstruction - AC | \$0  | 0.00             | True      |  |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" MIN. P-201  |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" EX. BIT SURFACE ON 6" EX. SHELL BASE ON ORIG. FLE |

**Network:** PNS **Branch:** RW 17-35 (RUNWAY 17-35) **Section:** 6120 **Surface:** AC  
**L.C.D.:** 11/01/2007 **Use:** RUNWAY **Rank P Length:** 525.00 Ft **Width:** 50.00 Ft **True Area:** 26,250.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 11/01/2007 | CR-AC     | Complete Reconstruction - AC | \$0  | 0.00             | True      |  |
| 01/01/1977 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1" P-401 ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON ORIG. FLEX. PA |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" MIN. P-201  |

**Network:** PNS **Branch:** RW 17-35 (RUNWAY 17-35) **Section:** 6125 **Surface:** PCC  
**L.C.D.:** 11/01/2007 **Use:** RUNWAY **Rank P Length:** 3,520.00 Ft **Width:** 112.50 Ft **True Area:**396,211.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments                        |
|------------|-----------|------------------------------|------|------------------|-----------|---------------------------------|
| 11/01/2007 | CR-PC     | Complete Reconstruction - PC | \$0  | 0.00             | True      |                                 |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" MIN. P-201 |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 2.00             | True      | 1966: 2" P-401 ON 7" P-212      |

**Network:** PNS **Branch:** RW 17-35 (RUNWAY 17-35) **Section:** 6130 **Surface:** PCC  
**L.C.D.:** 11/01/2007 **Use:** RUNWAY **Rank P Length:** 3,520.00 Ft **Width:** 38.00 Ft **True Area:**131,789.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments                        |
|------------|-----------|------------------------------|------|------------------|-----------|---------------------------------|
| 11/01/2007 | CR-PC     | Complete Reconstruction - PC | \$0  | 0.00             | True      |                                 |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" MIN. P-201 |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 2.00             | True      | 1966: 2" P-401 ON 7" P-212      |

Date:05/14/2015

# Work History Report

4 of 11

Pavement Database:FDOT

**Network:** PNS **Branch:** RW 8-26 **(RUNWAY 8-26)** **Section:** 6205 **Surface:** AC  
**L.C.D.:** 01/01/2004 **Use:** RUNWAY **Rank P Length:** 1,300.00 Ft **Width:** 100.00 Ft **True Area:**130,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152                                |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 4" MIN. P-201  |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" EX. ASPHALT ON 6" EX. SHELL BASE ON ORIG. PAVEMEN |

**Network:** PNS **Branch:** RW 8-26 **(RUNWAY 8-26)** **Section:** 6210 **Surface:** AC  
**L.C.D.:** 01/01/2004 **Use:** RUNWAY **Rank P Length:** 1,300.00 Ft **Width:** 50.00 Ft **True Area:** 65,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152                                |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 4" MIN. P-201  |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" EX. ASPHALT ON 6" EX. SHELL BASE ON ORIG. PAVEMEN |

**Network:** PNS **Branch:** RW 8-26 **(RUNWAY 8-26)** **Section:** 6215 **Surface:** AC  
**L.C.D.:** 01/01/2004 **Use:** RUNWAY **Rank P Length:** 950.00 Ft **Width:** 100.00 Ft **True Area:** 95,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152                                |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 4" MIN. P-201  |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" MIN. P-201  |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" BIT. SURFACE ON 6" SHELL BASE ON ORIG. FLEX. PAVE |

**Network:** PNS **Branch:** RW 8-26 **(RUNWAY 8-26)** **Section:** 6220 **Surface:** AC  
**L.C.D.:** 01/01/2004 **Use:** RUNWAY **Rank P Length:** 950.00 Ft **Width:** 50.00 Ft **True Area:** 47,500.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152                                |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 4" MIN. P-201  |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" MIN. P-201  |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" BIT. SURFACE ON 6" SHELL BASE ON ORIG. FLEX. PAVE |

**Network:** PNS **Branch:** RW 8-26 **(RUNWAY 8-26)** **Section:** 6225 **Surface:** AC  
**L.C.D.:** 01/01/2004 **Use:** RUNWAY **Rank P Length:** 900.00 Ft **Width:** 100.00 Ft **True Area:** 89,997.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152                                |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" P-201   |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON ORIG. FL |

**Network:** PNS **Branch:** RW 8-26 **(RUNWAY 8-26)** **Section:** 6230 **Surface:** AC  
**L.C.D.:** 01/01/2004 **Use:** RUNWAY **Rank P Length:** 900.00 Ft **Width:** 50.00 Ft **True Area:** 44,999.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152Q                               |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1977: 2" P-401 ON 4" P-201   |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON ORIG. FL |

Date:05/14/2015

## Work History Report

5 of 11

Pavement Database:FDOT

Network: PNS Branch: RW 8-26 (RUNWAY 8-26) Section: 6235 Surface: AC  
 L.C.D.: 01/01/2004 Use: RUNWAY Rank P Length: 1,700.00 Ft Width: 100.00 Ft True Area:170,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152                                |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 4" P-201   |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON ORIG. BI |

Network: PNS Branch: RW 8-26 (RUNWAY 8-26) Section: 6240 Surface: AC  
 L.C.D.: 01/01/2004 Use: RUNWAY Rank P Length: 1,700.00 Ft Width: 50.00 Ft True Area: 85,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|------------------|-----------|--|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152                                |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 4" P-201   |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00             | True      | 1966: 1" P-401 ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON ORIG. BI |

Network: PNS Branch: RW 8-26 (RUNWAY 8-26) Section: 6245 Surface: AC  
 L.C.D.: 01/01/2004 Use: RUNWAY Rank P Length: 400.00 Ft Width: 100.00 Ft True Area: 40,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments                                |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152 |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 3" MIN. P-201         |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 3.00             | True      | 1966: 3" P-401 ON 11" P-212             |

Network: PNS Branch: RW 8-26 (RUNWAY 8-26) Section: 6250 Surface: AC  
 L.C.D.: 01/01/2004 Use: RUNWAY Rank P Length: 400.00 Ft Width: 50.00 Ft True Area: 20,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments                                |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152 |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 2.00             | True      | 1979: 2" P-401 ON 3" MIN. P-201         |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 3.00             | True      | 1966: 3" P-401 ON 11" P-212             |

Network: PNS Branch: RW 8-26 (RUNWAY 8-26) Section: 6255 Surface: AC  
 L.C.D.: 01/01/2004 Use: RUNWAY Rank P Length: 600.00 Ft Width: 100.00 Ft True Area: 60,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments                                |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152 |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 3.00             | True      | 3" EX. P-401 ON 8" EX. P-212            |
| 01/01/1979 | IMPORTED  | BUILT                        |      | 2.00             | True      | 1979: 2" P-401 ON 3" MIN. P-201         |

Network: PNS Branch: RW 8-26 (RUNWAY 8-26) Section: 6260 Surface: AC  
 L.C.D.: 01/01/2004 Use: RUNWAY Rank P Length: 600.00 Ft Width: 50.00 Ft True Area: 30,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments                                |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152 |
| 01/01/1979 | IMPORTED  | BUILT                        |      | 2.00             | True      | 1979: 2" P-401 ON 3" MIN. P-201         |
| 01/01/1979 | IMPORTED  | OVERLAY                      |      | 3.00             | True      | 3" EX. P-401 ON 8" EX. P-212            |

Network: PNS Branch: RW 8-26 (RUNWAY 8-26) Section: 6265 Surface: AC  
 L.C.D.: 01/01/2006 Use: RUNWAY Rank P Length: 1,001.00 Ft Width: 100.00 Ft True Area:100,100.00 SqF

| Work Date  | Work Code | Work Description      | Cost | Thickness ( in ) | Major M&R | Comments |
|------------|-----------|-----------------------|------|------------------|-----------|----------|
| 01/01/2006 | NC-AC     | New Construction - AC | \$0  | 0.00             | True      |          |
| 01/01/2005 | INITIAL   | Initial Construction  | \$0  | 0.00             | True      |          |



Date:05/14/2015

# Work History Report

6 of 11

Pavement Database:FDOT

**Network:** PNS **Branch:** RW 8-26 **(RUNWAY 8-26)** **Section:** 6270 **Surface:** AC  
**L.C.D.:** 01/01/2006 **Use:** RUNWAY **Rank P Length:** 1,001.00 Ft **Width:** 50.00 Ft **True Area:** 50,050.00 SqF

| Work Date  | Work Code | Work Description      | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-----------------------|------|----------------|-----------|----------|
| 01/01/2006 | NC-AC     | New Construction - AC | \$0  | 0.00           | True      |          |
| 01/01/2005 | INITIAL   | Initial Construction  | \$0  | 0.00           | True      |          |

**Network:** PNS **Branch:** TW A **(TAXIWAY A)** **Section:** 105 **Surface:** AC  
**L.C.D.:** 01/01/2001 **Use:** TAXIWAY **Rank P Length:** 3,620.00 Ft **Width:** 75.00 Ft **True Area:**286,014.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|----------------|-----------|---|
| 01/01/2001 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 12" RESCARIFY & COMPACTED, SAND-CLAY/SHELL BASE |
| 01/01/1977 | IMPORTED  | BUILT                        |      | 0.50           | True      | 1977: 1-1/2" P-401 ON 1-1/2" MIN. P-201 ON EX. FLEX. PAVEMENT       |

**Network:** PNS **Branch:** TW A **(TAXIWAY A)** **Section:** 115 **Surface:** AC  
**L.C.D.:** 02/01/2001 **Use:** TAXIWAY **Rank P Length:** 3,690.00 Ft **Width:** 75.00 Ft **True Area:**297,891.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|----------------|-----------|---|
| 02/01/2001 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 12" RESCARIFY & COMPACTED, SAND-CLAY/SHELL BASE |
| 01/01/1977 | IMPORTED  | BUILT                        |      | 2.00           | True      | 1977: 2" P-401 ON 7" P-201 ON 6" P-213 SAND-CLAY BASE               |

**Network:** PNS **Branch:** TW A1 **(TAXIWAY A1)** **Section:** 120 **Surface:** AC  
**L.C.D.:** 01/01/2001 **Use:** TAXIWAY **Rank P Length:** 375.00 Ft **Width:** 104.00 Ft **True Area:** 47,399.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|----------------|-----------|---|
| 01/01/2001 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 12" RESCARIFY & COMPACTED, SAND-CLAY/SHELL BASE |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00           | True      | 1977: 2" P-401 ON 3"-4" P-201                                       |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 3.00           | True      | 1966: 3" P-401 ON 8" P-212 SHELL BASE                               |

**Network:** PNS **Branch:** TW A2 **(TAXIWAY A2)** **Section:** 150 **Surface:** AAC  
**L.C.D.:** 01/01/2006 **Use:** TAXIWAY **Rank P Length:** 375.00 Ft **Width:** 104.00 Ft **True Area:** 55,331.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|----------------|-----------|--|
| 01/01/2006 | SR-AC     | Surface Reconstruction - AC  | \$0  | 0.00           | True      |  |
| 01/01/2001 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 12" RESCARIFY & COMPACTED, SAND-CLAY/SHELL BASE    |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00           | True      | 1977: 2" P-401 ON 3"-4" P-201  |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00           | True      | 1966: 1" P-401 ON 2" EX. BIT SURFACE ON 6" EX. SHELL BASE ON ORIG. BIT |

**Network:** PNS **Branch:** TW A2 **(TAXIWAY A2)** **Section:** 160 **Surface:** AC  
**L.C.D.:** 01/01/2000 **Use:** TAXIWAY **Rank P Length:** 340.00 Ft **Width:** 100.00 Ft **True Area:** 37,493.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2000 | INITIAL   | Initial Construction | \$0  | 0.00           | True      |          |

**Network:** PNS **Branch:** TW A3 **(TAXIWAY A3)** **Section:** 170 **Surface:** PCC  
**L.C.D.:** 01/01/2006 **Use:** TAXIWAY **Rank T Length:** 375.00 Ft **Width:** 103.00 Ft **True Area:** 50,051.00 SqF

| Work Date  | Work Code | Work Description       | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|------------------------|------|----------------|-----------|----------|
| 01/01/2006 | NC-PC     | New Construction - PCC | \$0  | 0.00           | True      |          |

Date:05/14/2015

## Work History Report

7 of 11

Pavement Database:FDOT

Network: PNS Branch: TW A4 (TAXIWAY A4) Section: 130 Surface: AC  
 L.C.D.: 01/01/2001 Use: TAXIWAY Rank P Length: 375.00 Ft Width: 104.00 Ft True Area: 49,968.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|----------------|-----------|--|
| 01/01/2001 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 12" RESCARIFY & COMPACTED, SAND-CLAY/SHELL BASE<br>1977: 2" P-401 ON 3"-4" P-201<br>1966: 1" P-401 ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON ORIG. FL |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00           | True      |  |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00           | True      |  |

Network: PNS Branch: TW A5 (TAXIWAY A5) Section: 125 Surface: AC  
 L.C.D.: 01/01/2001 Use: TAXIWAY Rank P Length: 375.00 Ft Width: 104.00 Ft True Area: 49,806.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|----------------|-----------|--|
| 01/01/2001 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 12" RESCARIFY & COMPACTED, SAND-CLAY/SHELL BASE<br>1977: 2" P-401 ON 7" P-201 ON 6" P-213 SAND-CLAY BASE |
| 01/01/1977 | IMPORTED  | BUILT                        |      | 2.00           | True      |  |

Network: PNS Branch: TW A7 (TAXIWAY A7) Section: 215 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 310.00 Ft Width: 230.00 Ft True Area: 72,160.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|----------------|-----------|---|
| 01/01/2002 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1977: 2" P-401 ON 3"-4" MIN. P-201<br>1966: 1" P-401 ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON ORIG. BI |
| 01/01/1977 | IMPORTED  | OVERLAY                      |      | 2.00           | True      |   |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00           | True      |   |

Network: PNS Branch: TW B (TAXIWAY B) Section: 205 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 2,485.00 Ft Width: 75.00 Ft True Area: 213,853.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|----------------|-----------|---|
| 01/01/2002 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1980: 2" P-401 ON 3"-4" P-201<br>1966: 1" P-401 OVERLAY ON 2" EX. BIT. SURFACE ON 6" EX. SHELL BASE ON |
| 01/01/1980 | IMPORTED  | OVERLAY                      |      | 2.00           | True      |   |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00           | True      |   |

Network: PNS Branch: TW B (TAXIWAY B) Section: 210 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 347.00 Ft Width: 132.00 Ft True Area: 51,982.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|------------------------------|------|----------------|-----------|--|
| 01/01/2002 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1980: 2" P-401 ON 7" P-201 ON 6" P-213 SAND-CLAY BASE |
| 01/01/1980 | IMPORTED  | BUILT                        |      | 2.00           | True      |  |

Network: PNS Branch: TW B (TAXIWAY B) Section: 217 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 400.00 Ft Width: 27.50 Ft True Area: 11,000.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|----------------|-----------|---|
| 01/01/2002 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1980 2" P401 AC ON 3 1/2" P201 AC<br>1966 1" P401 AC ON 2" P201 AC BASE ON 6" P212 SUBBASE |
| 01/01/1980 | IMPORTED  | OVERLAY                      |      | 2.00           | True      |   |
| 01/01/1966 | IMPORTED  | BUILT                        |      | 1.00           | True      |   |

Network: PNS Branch: TW B (TAXIWAY B) Section: 220 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 3,367.00 Ft Width: 75.00 Ft True Area: 256,627.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness (in) | Major M&R | Comments                                |
|------------|-----------|------------------------------|------|----------------|-----------|---|
| 01/01/2002 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00           | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152 |

|                        |           |                              |                            |                  |                          |  |         |  |
|------------------------|-----------|------------------------------|----------------------------|------------------|--------------------------|--|---------|--|
| Date:05/14/2015        |           |                              | Work History Report        |                  |                          |  | 8 of 11 |  |
| Pavement Database:FDOT |           |                              |                            |                  |                          |  |         |  |
| 01/01/1977             | IMPORTED  | BUILT                        |                            | 2.00             | True                     | 1977: 2" P-401 ON 7" P-201 ON 6" P-213   |         |  |
| Network: PNS           |           | Branch: TW B                 |                            | (TAXIWAY B)      |                          | Section: 230 Surface: AC   |         |  |
| L.C.D.: 01/01/2005     |           | Use: TAXIWAY                 | Rank P Length: 1,450.00 Ft | Width: 75.00 Ft  | True Area:124,670.00 SqF |  |         |  |
| Work Date              | Work Code | Work Description             | Cost                       | Thickness (in)   | Major M&R                | Comments   |         |  |
| 01/01/2005             | CR-AC     | Complete Reconstruction - AC | \$0                        | 0.00             | True                     | 1977: 2" P-401 ON 7" P-201 ON 6" P-213   |         |  |
| 01/01/1977             | IMPORTED  | BUILT                        |                            | 2.00             | True                     |  |         |  |
| Network: PNS           |           | Branch: TW B2                |                            | (TAXIWAY B2)     |                          | Section: 212 Surface: AC   |         |  |
| L.C.D.: 01/01/2002     |           | Use: TAXIWAY                 | Rank P Length: 200.00 Ft   | Width: 150.00 Ft | True Area: 32,535.00 SqF |  |         |  |
| Work Date              | Work Code | Work Description             | Cost                       | Thickness (in)   | Major M&R                | Comments   |         |  |
| 01/01/2002             | CR-AC     | Complete Reconstruction - AC | \$0                        | 4.00             | True                     | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1980: 2" P-401 ON 3"-4" P-201 ON EX. FLEX. PAVEMENT   |         |  |
| 01/01/1980             | IMPORTED  | BUILT                        |                            | 2.00             | True                     |  |         |  |
| Network: PNS           |           | Branch: TW B2                |                            | (TAXIWAY B2)     |                          | Section: 213 Surface: PCC  |         |  |
| L.C.D.: 01/01/1988     |           | Use: TAXIWAY                 | Rank P Length: 112.50 Ft   | Width: 75.00 Ft  | True Area: 10,751.00 SqF |  |         |  |
| Work Date              | Work Code | Work Description             | Cost                       | Thickness (in)   | Major M&R                | Comments   |         |  |
| 01/01/1988             | INITIAL   | Initial Construction         | \$0                        | 0.00             | True                     | 17 1/2" PCC OVERLAY ON 6" SOIL-CEMENT BASE   |         |  |
| Network: PNS           |           | Branch: TW B2                |                            | (TAXIWAY B2)     |                          | Section: 240 Surface: AC   |         |  |
| L.C.D.: 01/01/2002     |           | Use: TAXIWAY                 | Rank P Length: 375.00 Ft   | Width: 104.00 Ft | True Area: 50,378.00 SqF |  |         |  |
| Work Date              | Work Code | Work Description             | Cost                       | Thickness (in)   | Major M&R                | Comments   |         |  |
| 01/01/2002             | CR-AC     | Complete Reconstruction - AC | \$0                        | 4.00             | True                     | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1977: 2" P-401 ON 7" P-201 ON 6" P-213<br>SAND-CLAY BASE  |         |  |
| 01/01/1977             | IMPORTED  | BUILT                        |                            | 2.00             | True                     |  |         |  |
| Network: PNS           |           | Branch: TW B3                |                            | (TAXIWAY B3)     |                          | Section: 255 Surface: AC   |         |  |
| L.C.D.: 01/01/2002     |           | Use: TAXIWAY                 | Rank P Length: 375.00 Ft   | Width: 104.00 Ft | True Area: 50,248.00 SqF |  |         |  |
| Work Date              | Work Code | Work Description             | Cost                       | Thickness (in)   | Major M&R                | Comments   |         |  |
| 01/01/2002             | CR-AC     | Complete Reconstruction - AC | \$0                        | 4.00             | True                     | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1980: 2" P-401 ON 3"-4" P-201 ON EX. FLEX. PAVEMENT   |         |  |
| 01/01/1980             | IMPORTED  | BUILT                        |                            | 2.00             | True                     |  |         |  |
| Network: PNS           |           | Branch: TW B4                |                            | (TAXIWAY B4)     |                          | Section: 260 Surface: AC   |         |  |
| L.C.D.: 01/01/2002     |           | Use: TAXIWAY                 | Rank P Length: 375.00 Ft   | Width: 104.00 Ft | True Area: 50,114.00 SqF |  |         |  |
| Work Date              | Work Code | Work Description             | Cost                       | Thickness (in)   | Major M&R                | Comments   |         |  |
| 01/01/2002             | CR-AC     | Complete Reconstruction - AC | \$0                        | 4.00             | True                     | 4" P-401, 8" P-401, 5" P-154, 12" P-152<br>1980: 2" P-401 ON 3"-4" P-201<br>1979: 2" P-401 ON 4" P-201<br>1966: 1" P-401 ON 2" BIT. SURFACE ON 6" SHELL BASE ON ORIG. BIT. PAVEM |         |  |
| 01/01/1980             | IMPORTED  | OVERLAY                      |                            | 2.00             | True                     |  |         |  |
| 01/01/1979             | IMPORTED  | OVERLAY                      |                            | 2.00             | True                     |  |         |  |
| 01/01/1966             | IMPORTED  | BUILT                        |                            | 1.00             | True                     |  |         |  |
| Network: PNS           |           | Branch: TW B5                |                            | (TAXIWAY B5)     |                          | Section: 265 Surface: AC   |         |  |
| L.C.D.: 01/01/2002     |           | Use: TAXIWAY                 | Rank P Length: 375.00 Ft   | Width: 104.00 Ft | True Area: 48,322.00 SqF |  |         |  |
| Work Date              | Work Code | Work Description             | Cost                       | Thickness (in)   | Major M&R                | Comments   |         |  |
| 01/01/2002             | INITIAL   | Initial Construction         | \$0                        | 4.00             | True                     | 4" P-401, 8" P-401, 5" P-154, 12" P-152  |         |  |

Date:05/14/2015

## Work History Report

9 of 11

Pavement Database:FDOT

Network: PNS Branch: TW B7 (TAXIWAY B7) Section: 270 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 228.00 Ft Width: 50.00 Ft True Area: 14,899.00 SqF

| Work Date  | Work Code | Work Description      | Cost | Thickness ( in ) | Major M&R | Comments |
|------------|-----------|-----------------------|------|------------------|-----------|----------|
| 01/01/2002 | NC-AC     | New Construction - AC | \$0  | 0.00             | True      |          |

Network: PNS Branch: TW B8 (TAXIWAY B8) Section: 280 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 228.00 Ft Width: 50.00 Ft True Area: 13,317.00 SqF

| Work Date  | Work Code | Work Description      | Cost | Thickness ( in ) | Major M&R | Comments |
|------------|-----------|-----------------------|------|------------------|-----------|----------|
| 01/01/2002 | NC-AC     | New Construction - AC | \$0  | 0.00             | True      |          |

Network: PNS Branch: TW C (TAXIWAY C) Section: 250 Surface: AC  
 L.C.D.: 01/01/2004 Use: TAXIWAY Rank P Length: 300.00 Ft Width: 104.00 Ft True Area: 33,625.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 01/01/2004 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152               |
| 01/01/1980 | IMPORTED  | BUILT                        |      | 2.00             | True      | 1980: 2" P-401 ON 7" P-201 ON 6" P-213 SAND-CLAY BASE |

Network: PNS Branch: TW C (TAXIWAY C) Section: 252 Surface: AC  
 L.C.D.: 01/01/2002 Use: TAXIWAY Rank P Length: 200.00 Ft Width: 75.00 Ft True Area: 16,451.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 01/01/2002 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 5" P-154, 12" P-152               |
| 01/01/1980 | IMPORTED  | BUILT                        |      | 2.00             | True      | 1980: 2" P-401 ON 7" P-201 ON 6" P-213 SAND-CLAY BASE |

Network: PNS Branch: TW C (TAXIWAY C) Section: 505 Surface: AC  
 L.C.D.: 01/01/1997 Use: TAXIWAY Rank P Length: 308.00 Ft Width: 35.00 Ft True Area: 13,138.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness ( in ) | Major M&R | Comments                  |
|------------|-----------|----------------------|------|------------------|-----------|---------------------------|
| 01/01/1997 | INITIAL   | Initial Construction | \$0  | 4.00             | True      | 4" P-401, 6" P-209, P-152 |

Network: PNS Branch: TW C (TAXIWAY C) Section: 510 Surface: AC  
 L.C.D.: 01/01/1997 Use: TAXIWAY Rank P Length: 1,864.00 Ft Width: 35.00 Ft True Area: 67,178.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness ( in ) | Major M&R | Comments                  |
|------------|-----------|----------------------|------|------------------|-----------|---------------------------|
| 01/01/1997 | INITIAL   | Initial Construction | \$0  | 4.00             | True      | 4" P-401, 6" P-209, P-152 |

Network: PNS Branch: TW C2 (TAXIWAY C2) Section: 515 Surface: AC  
 L.C.D.: 01/01/1997 Use: TAXIWAY Rank P Length: 882.00 Ft Width: 35.00 Ft True Area: 31,643.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness ( in ) | Major M&R | Comments                  |
|------------|-----------|----------------------|------|------------------|-----------|---------------------------|
| 01/01/1997 | INITIAL   | Initial Construction | \$0  | 4.00             | True      | 4" P-401, 6" P-209, P-152 |

Network: PNS Branch: TW D (TAXIWAY D) Section: 140 Surface: AC  
 L.C.D.: 01/01/2001 Use: TAXIWAY Rank P Length: 375.00 Ft Width: 97.00 Ft True Area: 43,648.00 SqF

| Work Date  | Work Code | Work Description             | Cost | Thickness ( in ) | Major M&R | Comments  |
|------------|-----------|------------------------------|------|------------------|-----------|---|
| 01/01/2001 | CR-AC     | Complete Reconstruction - AC | \$0  | 4.00             | True      | 4" P-401, 8" P-401, 12" RESCARIFY & COMPACTED, SAND-CLAY/SHELL BASE |
| 01/01/1977 | IMPORTED  | BUILT                        |      | 2.00             | True      | 1977: 2" P-401 ON 7" P-201 ON 6" P-213 SAND-CLAY BASE               |

Date:05/14/2015

**Work History Report**

10 of 11

*Pavement Database:FDOT*

**Network:** PNS      **Branch:** TW D      **(TAXIWAY D)**      **Section:** 405      **Surface:** AC  
**L.C.D.:** 01/01/2000   **Use:** TAXIWAY      **Rank P Length:** 3,352.00 Ft      **Width:** 35.00 Ft      **True Area:**118,752.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2000 | INITIAL   | Initial Construction | \$0  | 0.00           | True      |          |

**Network:** PNS      **Branch:** TW D      **(TAXIWAY D)**      **Section:** 410      **Surface:** AC  
**L.C.D.:** 01/01/2005   **Use:** TAXIWAY      **Rank P Length:** 132.00 Ft      **Width:** 154.00 Ft      **True Area:** 20,158.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2005 | INITIAL   | Initial Construction | \$0  | 0.00           | True      |          |

**Network:** PNS      **Branch:** TW D      **(TAXIWAY D)**      **Section:** 430      **Surface:** AC  
**L.C.D.:** 01/01/2005   **Use:** TAXIWAY      **Rank P Length:** 1,340.00 Ft      **Width:** 35.00 Ft      **True Area:** 48,300.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2005 | INITIAL   | Initial Construction | \$0  | 0.00           | True      |          |

**Network:** PNS      **Branch:** TW D1      **(TAXIWAY D1)**      **Section:** 415      **Surface:** AC  
**L.C.D.:** 01/01/2000   **Use:** TAXIWAY      **Rank P Length:** 308.00 Ft      **Width:** 35.00 Ft      **True Area:** 13,134.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2000 | INITIAL   | Initial Construction | \$0  | 0.00           | True      |          |

**Network:** PNS      **Branch:** TW D2      **(TAXIWAY D2)**      **Section:** 420      **Surface:** AC  
**L.C.D.:** 01/01/2000   **Use:** TAXIWAY      **Rank P Length:** 308.00 Ft      **Width:** 35.00 Ft      **True Area:** 13,134.00 SqF

| Work Date  | Work Code | Work Description     | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|----------------------|------|----------------|-----------|----------|
| 01/01/2000 | INITIAL   | Initial Construction | \$0  | 0.00           | True      |          |

**Network:** PNS      **Branch:** TW D3      **(TAXIWAY D3)**      **Section:** 425      **Surface:** AAC  
**L.C.D.:** 01/01/2006   **Use:** TAXIWAY      **Rank P Length:** 308.00 Ft      **Width:** 40.00 Ft      **True Area:** 14,220.00 SqF

| Work Date  | Work Code | Work Description            | Cost | Thickness (in) | Major M&R | Comments |
|------------|-----------|-----------------------------|------|----------------|-----------|----------|
| 01/01/2006 | SR-AC     | Surface Reconstruction - AC | \$0  | 0.00           | True      |          |
| 01/01/2000 | INITIAL   | Initial Construction        | \$0  | 0.00           | True      |          |

**Summary:**

| Work Description              | Section Count | Area Total (SqFt) | Thickness Avg (in) | Thickness STD (in) |
|-------------------------------|---------------|-------------------|--------------------|--------------------|
| BUILT                         | 42            | 4,020,638.00      | 1.65               | .87                |
| Complete Reconstruction - AC  | 33            | 2,749,946.00      | 3.64               | 1.17               |
| Complete Reconstruction - PCC | 4             | 672,000.00        | .00                | .00                |
| Initial Construction          | 20            | 1,641,885.00      | 1.90               | 3.01               |
| MILL and OVERLAY              | 4             | 86,169.00         | .00                | .00                |
| New Construction - AC         | 5             | 397,738.00        | .00                | .00                |
| New Construction - Initial    | 6             | 571,140.00        | .08                | .20                |
| New Construction - PCC        | 1             | 50,051.00         | .00                |                    |
| OVERLAY                       | 26            | 2,176,685.00      | 2.08               | .27                |
| Surface Reconstruction - AC   | 2             | 69,551.00         | .00                | .00                |



# APPENDIX B

---

- AIRFIELD PAVEMENT CONDITION INDEX RATING EXHIBIT
- PAVEMENT CONDITION INDEX INVENTORY









Table B-1: Pavement Condition Index Inventory

| Branch Name  | Branch ID | Branch Use | Section ID | True Area (FT <sup>2</sup> ) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|--------------|-----------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6270       | 50,050                       | P            | AC           | 84  | Satisfactory | 2                        | 10            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6265       | 100,100                      | P            | AC           | 80  | Satisfactory | 5                        | 20            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6260       | 30,000                       | P            | AC           | 79  | Satisfactory | 2                        | 6             |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6255       | 60,000                       | P            | AC           | 74  | Satisfactory | 3                        | 12            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6250       | 20,000                       | P            | AC           | 83  | Satisfactory | 1                        | 4             |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6245       | 40,000                       | P            | AC           | 73  | Satisfactory | 2                        | 8             |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6240       | 85,000                       | P            | AC           | 79  | Satisfactory | 5                        | 18            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6235       | 170,000                      | P            | AC           | 72  | Satisfactory | 7                        | 34            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6230       | 44,999                       | P            | AC           | 83  | Satisfactory | 3                        | 12            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6225       | 89,997                       | P            | AC           | 74  | Satisfactory | 5                        | 18            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6220       | 47,500                       | P            | AC           | 76  | Satisfactory | 3                        | 12            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6215       | 95,000                       | P            | AC           | 72  | Satisfactory | 5                        | 19            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6210       | 65,000                       | P            | AC           | 77  | Satisfactory | 3                        | 14            |
| RUNWAY 8-26  | RW 8-26   | RUNWAY     | 6205       | 130,000                      | P            | AC           | 75  | Satisfactory | 5                        | 26            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6130       | 131,789                      | P            | PCC          | 91  | Good         | 9                        | 30            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6125       | 396,211                      | P            | PCC          | 92  | Good         | 15                       | 59            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6120       | 26,250                       | P            | AC           | 78  | Satisfactory | 2                        | 6             |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6115       | 52,500                       | P            | AC           | 75  | Satisfactory | 3                        | 11            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6110       | 110,822                      | P            | PCC          | 93  | Good         | 7                        | 24            |
| RUNWAY 17-35 | RW 17-35  | RUNWAY     | 6105       | 33,178                       | P            | PCC          | 91  | Good         | 12                       | 49            |
| CARGO APRON  | AP CARGO  | APRON      | 4710       | 145,521                      | P            | PCC          | 100 | Good         | 0                        | 0             |
| CARGO APRON  | AP CARGO  | APRON      | 4705       | 68,880                       | P            | PCC          | 100 | Good         | 0                        | 0             |
| APRON WEST   | AP W      | APRON      | 4605       | 219,372                      | P            | AC           | 71  | Satisfactory | 5                        | 42            |
| SOUTH APRON  | AP S      | APRON      | 4515       | 219,093                      | T            | AC           | 68  | Fair         | 4                        | 37            |
| SOUTH APRON  | AP S      | APRON      | 4510       | 338,266                      | T            | AC           | 51  | Poor         | 8                        | 72            |
| SOUTH APRON  | AP S      | APRON      | 4505       | 112,540                      | T            | AC           | 71  | Satisfactory | 3                        | 26            |



# Pavement Evaluation Report - Pensacola International Airport

| Branch Name    | Branch ID | Branch Use | Section ID | True Area (FT <sup>2</sup> ) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|----------------|-----------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| EAST APRON     | AP E      | APRON      | 4405       | 255,240                      | P            | AC           | 63  | Fair         | 7                        | 67            |
| GA APRON       | AP GA     | APRON      | 4325       | 37,703                       | P            | AAC          | 100 | Good         | 0                        | 0             |
| GA APRON       | AP GA     | APRON      | 4320       | 12,201                       | P            | AAC          | 100 | Good         | 0                        | 0             |
| GA APRON       | AP GA     | APRON      | 4315       | 9,900                        | P            | PCC          | 100 | Good         | 0                        | 0             |
| GA APRON       | AP GA     | APRON      | 4310       | 26,365                       | P            | AAC          | 100 | Good         | 0                        | 0             |
| TERMINAL APRON | AP TERM   | APRON      | 4235       | 127,593                      | P            | PCC          | 91  | Good         | 4                        | 37            |
| TERMINAL APRON | AP TERM   | APRON      | 4230       | 23,761                       | P            | AC           | 9   | Failed       | 1                        | 5             |
| TERMINAL APRON | AP TERM   | APRON      | 4225       | 106,612                      | P            | PCC          | 97  | Good         | 3                        | 18            |
| TERMINAL APRON | AP TERM   | APRON      | 4220       | 76,245                       | P            | PCC          | 100 | Good         | 3                        | 29            |
| TERMINAL APRON | AP TERM   | APRON      | 4215       | 42,079                       | P            | PCC          | 97  | Good         | 1                        | 6             |
| TERMINAL APRON | AP TERM   | APRON      | 4210       | 256,288                      | P            | PCC          | 91  | Good         | 7                        | 69            |
| TERMINAL APRON | AP TERM   | APRON      | 4205       | 367,057                      | T            | PCC          | 94  | Good         | 10                       | 122           |
| TAXIWAY C2     | TW C2     | TAXIWAY    | 515        | 31,643                       | P            | AC           | 80  | Satisfactory | 1                        | 9             |
| TAXIWAY C      | TW C      | TAXIWAY    | 510        | 67,178                       | P            | AC           | 79  | Satisfactory | 3                        | 19            |
| TAXIWAY C      | TW C      | TAXIWAY    | 505        | 13,138                       | P            | AC           | 75  | Satisfactory | 1                        | 3             |
| TAXIWAY D      | TW D      | TAXIWAY    | 430        | 48,300                       | P            | AC           | 86  | Good         | 3                        | 12            |
| TAXIWAY D3     | TW D3     | TAXIWAY    | 425        | 14,220                       | P            | AAC          | 87  | Good         | 1                        | 3             |
| TAXIWAY D2     | TW D2     | TAXIWAY    | 420        | 13,134                       | P            | AC           | 80  | Satisfactory | 1                        | 3             |
| TAXIWAY D1     | TW D1     | TAXIWAY    | 415        | 13,134                       | P            | AC           | 83  | Satisfactory | 1                        | 3             |
| TAXIWAY D      | TW D      | TAXIWAY    | 410        | 20,158                       | P            | AC           | 75  | Satisfactory | 1                        | 4             |
| TAXIWAY D      | TW D      | TAXIWAY    | 405        | 118,752                      | P            | AC           | 79  | Satisfactory | 4                        | 33            |
| TAXIWAY B8     | TW B8     | TAXIWAY    | 280        | 13,317                       | P            | AC           | 75  | Satisfactory | 1                        | 3             |
| TAXIWAY B7     | TW B7     | TAXIWAY    | 270        | 14,899                       | P            | AC           | 66  | Fair         | 1                        | 3             |
| TAXIWAY B5     | TW B5     | TAXIWAY    | 265        | 48,322                       | P            | AC           | 80  | Satisfactory | 2                        | 10            |
| TAXIWAY B4     | TW B4     | TAXIWAY    | 260        | 50,114                       | P            | AC           | 83  | Satisfactory | 1                        | 10            |
| TAXIWAY B3     | TW B3     | TAXIWAY    | 255        | 50,248                       | P            | AC           | 83  | Satisfactory | 1                        | 10            |
| TAXIWAY C      | TW C      | TAXIWAY    | 252        | 16,451                       | P            | AC           | 73  | Satisfactory | 1                        | 3             |

| Branch Name | Branch ID | Branch Use | Section ID | True Area (FT <sup>2</sup> ) | Section Rank | Surface Type | PCI | PCI Category | Total Inspection Samples | Total Samples |
|-------------|-----------|------------|------------|------------------------------|--------------|--------------|-----|--------------|--------------------------|---------------|
| TAXIWAY C   | TW C      | TAXIWAY    | 250        | 33,625                       | P            | AC           | 82  | Satisfactory | 1                        | 7             |
| TAXIWAY B2  | TW B2     | TAXIWAY    | 240        | 50,378                       | P            | AC           | 83  | Satisfactory | 1                        | 10            |
| TAXIWAY B   | TW B      | TAXIWAY    | 230        | 124,670                      | P            | AC           | 88  | Good         | 4                        | 29            |
| TAXIWAY B   | TW B      | TAXIWAY    | 220        | 256,627                      | P            | AC           | 80  | Satisfactory | 7                        | 68            |
| TAXIWAY B   | TW B      | TAXIWAY    | 217        | 11,000                       | P            | AC           | 75  | Satisfactory | 1                        | 2             |
| TAXIWAY A7  | TW A7     | TAXIWAY    | 215        | 72,160                       | P            | AC           | 67  | Fair         | 3                        | 17            |
| TAXIWAY B2  | TW B2     | TAXIWAY    | 213        | 10,751                       | P            | PCC          | 91  | Good         | 1                        | 4             |
| TAXIWAY B2  | TW B2     | TAXIWAY    | 212        | 32,535                       | P            | AC           | 83  | Satisfactory | 1                        | 8             |
| TAXIWAY B   | TW B      | TAXIWAY    | 210        | 51,982                       | P            | AC           | 77  | Satisfactory | 1                        | 9             |
| TAXIWAY B   | TW B      | TAXIWAY    | 205        | 213,853                      | P            | AC           | 80  | Satisfactory | 6                        | 52            |
| TAXIWAY A3  | TW A3     | TAXIWAY    | 170        | 50,051                       | T            | PCC          | 94  | Good         | 1                        | 8             |
| TAXIWAY A2  | TW A2     | TAXIWAY    | 160        | 37,493                       | P            | AC           | 76  | Satisfactory | 1                        | 7             |
| TAXIWAY A2  | TW A2     | TAXIWAY    | 150        | 55,331                       | P            | AAC          | 82  | Satisfactory | 2                        | 11            |
| TAXIWAY D   | TW D      | TAXIWAY    | 140        | 43,648                       | P            | AC           | 75  | Satisfactory | 2                        | 9             |
| TAXIWAY A4  | TW A4     | TAXIWAY    | 130        | 49,968                       | P            | AC           | 84  | Satisfactory | 1                        | 10            |
| TAXIWAY A5  | TW A5     | TAXIWAY    | 125        | 49,806                       | P            | AC           | 83  | Satisfactory | 1                        | 10            |
| TAXIWAY A1  | TW A1     | TAXIWAY    | 120        | 47,399                       | P            | AC           | 37  | Very Poor    | 1                        | 9             |
| TAXIWAY A   | TW A      | TAXIWAY    | 115        | 297,891                      | P            | AC           | 74  | Satisfactory | 8                        | 74            |
| TAXIWAY A   | TW A      | TAXIWAY    | 105        | 286,014                      | P            | AC           | 79  | Satisfactory | 8                        | 73            |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.



# APPENDIX C

---

- BRANCH CONDITION REPORT
- SECTION CONDITION REPORT





Date: 5 /14/2015

**Branch Condition Report**

1 of 3

*Pavement Database: FDOT NetworkID: PNS*

| Branch ID                | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use     | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| AP CARGO (CARGO APRON)   | 2                  | 850.00                  | 225.00                 | 214,401.00       | APRON   | 100.00      | 0.00                   | 100.00               |
| AP E (EAST APRON)        | 1                  | 985.00                  | 260.00                 | 255,240.00       | APRON   | 63.00       | 0.00                   | 63.00                |
| AP GA (GA APRON)         | 4                  | 1,070.00                | 129.50                 | 86,169.00        | APRON   | 100.00      | 0.00                   | 100.00               |
| AP S (SOUTH APRON)       | 3                  | 5,845.00                | 135.00                 | 669,899.00       | APRON   | 63.33       | 8.81                   | 59.92                |
| AP TERM (TERMINAL APRON) | 7                  | 4,340.00                | 263.21                 | 999,635.00       | APRON   | 82.71       | 30.25                  | 91.73                |
| AP W (APRON WEST)        | 1                  | 710.00                  | 310.00                 | 219,372.00       | APRON   | 71.00       | 0.00                   | 71.00                |
| RW 17-35 (RUNWAY 17-35)  | 6                  | 14,010.00               | 75.17                  | 750,750.00       | RUNWAY  | 86.67       | 7.27                   | 90.25                |
| RW 8-26 (RUNWAY 8-26)    | 14                 | 13,702.00               | 75.00                  | 1,027,646.00     | RUNWAY  | 77.21       | 4.02                   | 76.05                |
| TW A (TAXIWAY A)         | 2                  | 7,310.00                | 75.00                  | 583,905.00       | TAXIWAY | 76.50       | 2.50                   | 76.45                |
| TW A1 (TAXIWAY A1)       | 1                  | 375.00                  | 104.00                 | 47,399.00        | TAXIWAY | 37.00       | 0.00                   | 37.00                |
| TW A2 (TAXIWAY A2)       | 2                  | 715.00                  | 102.00                 | 92,824.00        | TAXIWAY | 79.00       | 3.00                   | 79.58                |
| TW A3 (TAXIWAY A3)       | 1                  | 375.00                  | 103.00                 | 50,051.00        | TAXIWAY | 94.00       | 0.00                   | 94.00                |
| TW A4 (TAXIWAY A4)       | 1                  | 375.00                  | 104.00                 | 49,968.00        | TAXIWAY | 84.00       | 0.00                   | 84.00                |
| TW A5 (TAXIWAY A5)       | 1                  | 375.00                  | 104.00                 | 49,806.00        | TAXIWAY | 83.00       | 0.00                   | 83.00                |
| TW A7 (TAXIWAY A7)       | 1                  | 310.00                  | 230.00                 | 72,160.00        | TAXIWAY | 67.00       | 0.00                   | 67.00                |
| TW B (TAXIWAY B)         | 5                  | 8,049.00                | 76.90                  | 658,132.00       | TAXIWAY | 80.00       | 4.43                   | 81.19                |

Date: 5 /14/2015

**Branch Condition Report**

2 of 3

*Pavement Database: FDOT NetworkID: PNS*

| Branch ID          | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use     | Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------------|--------------------|-------------------------|------------------------|------------------|---------|-------------|------------------------|----------------------|
| TW B2 (TAXIWAY B2) | 3                  | 687.50                  | 109.67                 | 93,664.00        | TAXIWAY | 85.67       | 3.77                   | 83.92                |
| TW B3 (TAXIWAY B3) | 1                  | 375.00                  | 104.00                 | 50,248.00        | TAXIWAY | 83.00       | 0.00                   | 83.00                |
| TW B4 (TAXIWAY B4) | 1                  | 375.00                  | 104.00                 | 50,114.00        | TAXIWAY | 83.00       | 0.00                   | 83.00                |
| TW B5 (TAXIWAY B5) | 1                  | 375.00                  | 104.00                 | 48,322.00        | TAXIWAY | 80.00       | 0.00                   | 80.00                |
| TW B7 (TAXIWAY B7) | 1                  | 228.00                  | 50.00                  | 14,899.00        | TAXIWAY | 66.00       | 0.00                   | 66.00                |
| TW B8 (TAXIWAY B8) | 1                  | 228.00                  | 50.00                  | 13,317.00        | TAXIWAY | 75.00       | 0.00                   | 75.00                |
| TW C (TAXIWAY C)   | 4                  | 2,672.00                | 62.25                  | 130,392.00       | TAXIWAY | 77.25       | 3.49                   | 78.61                |
| TW C2 (TAXIWAY C2) | 1                  | 882.00                  | 35.00                  | 31,643.00        | TAXIWAY | 80.00       | 0.00                   | 80.00                |
| TW D (TAXIWAY D)   | 4                  | 5,199.00                | 80.25                  | 230,858.00       | TAXIWAY | 78.75       | 4.49                   | 79.36                |
| TW D1 (TAXIWAY D1) | 1                  | 308.00                  | 35.00                  | 13,134.00        | TAXIWAY | 83.00       | 0.00                   | 83.00                |
| TW D2 (TAXIWAY D2) | 1                  | 308.00                  | 35.00                  | 13,134.00        | TAXIWAY | 80.00       | 0.00                   | 80.00                |
| TW D3 (TAXIWAY D3) | 1                  | 308.00                  | 40.00                  | 14,220.00        | TAXIWAY | 87.00       | 0.00                   | 87.00                |

Date: 5 /14/2015

## Branch Condition Report

3 of 3

*Pavement Database: FDOT*

| Use Category | Number of Sections | Total Area (SqFt)   | Arithmetic Average PCI | Average PCI STD. | Weighted Average PCI |
|--------------|--------------------|---------------------|------------------------|------------------|----------------------|
| APRON        | 18                 | 2,444,716.00        | 83.50                  | 23.66            | 79.17                |
| RUNWAY       | 20                 | 1,778,396.00        | 80.05                  | 6.78             | 82.05                |
| TAXIWAY      | 34                 | 2,308,190.00        | 78.65                  | 9.29             | 78.68                |
| <b>All</b>   | <b>72</b>          | <b>6,531,302.00</b> | <b>80.25</b>           | <b>14.05</b>     | <b>79.78</b>         |



| <div> <div>Date: 5 /14/2015</div> <div>Section Condition Report</div> <div>1 of 4</div> </div> <div> <div>Pavement Database: FDOT</div> <div>NetworkID: PNS</div> </div> |            |                  |         |        |      |       |                  |                      |                   |        |
|--|------------|------------------|---------|--------|------|-------|------------------|----------------------|-------------------|--------|
| Branch ID  | Section ID | Last Const. Date | Surface | Use    | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI    |
| AP CARGO (CARGO APRON)   | 4705       | 01/01/2015       | PCC     | APRON  | P    | 0     | 68,880.00        | 01/01/2015           | 0                 | 100.00 |
| AP CARGO (CARGO APRON)   | 4710       | 01/01/2015       | PCC     | APRON  | P    | 0     | 145,521.00       | 01/01/2015           | 0                 | 100.00 |
| AP E (EAST APRON)  | 4405       | 12/25/1999       | AC      | APRON  | P    | 0     | 255,240.00       | 02/10/2015           | 16                | 63.00  |
| AP GA (GA APRON)   | 4310       | 01/01/2015       | AAC     | APRON  | P    | 0     | 26,365.00        | 01/01/2015           | 0                 | 100.00 |
| AP GA (GA APRON)   | 4315       | 01/01/2015       | PCC     | APRON  | P    | 0     | 9,900.00         | 01/01/2015           | 0                 | 100.00 |
| AP GA (GA APRON)   | 4320       | 01/01/2015       | AAC     | APRON  | P    | 0     | 12,201.00        | 01/01/2015           | 0                 | 100.00 |
| AP GA (GA APRON)   | 4325       | 01/01/2015       | AAC     | APRON  | P    | 0     | 37,703.00        | 01/01/2015           | 0                 | 100.00 |
| AP S (SOUTH APRON)   | 4505       | 01/01/1997       | AC      | APRON  | T    | 0     | 112,540.00       | 02/10/2015           | 18                | 71.00  |
| AP S (SOUTH APRON)   | 4510       | 01/01/1997       | AC      | APRON  | T    | 0     | 338,266.00       | 02/10/2015           | 18                | 51.00  |
| AP S (SOUTH APRON)   | 4515       | 01/01/1997       | AC      | APRON  | T    | 0     | 219,093.00       | 02/10/2015           | 18                | 68.00  |
| AP TERM (TERMINAL APRON)   | 4205       | 01/01/1988       | PCC     | APRON  | T    | 0     | 367,057.00       | 02/10/2015           | 27                | 94.00  |
| AP TERM (TERMINAL APRON)   | 4210       | 01/01/1977       | PCC     | APRON  | P    | 0     | 256,288.00       | 02/10/2015           | 38                | 91.00  |
| AP TERM (TERMINAL APRON)   | 4215       | 01/01/2010       | PCC     | APRON  | P    | 0     | 42,079.00        | 02/10/2015           | 5                 | 97.00  |
| AP TERM (TERMINAL APRON)   | 4220       | 01/01/2010       | PCC     | APRON  | P    | 0     | 76,245.00        | 02/10/2015           | 5                 | 100.00 |
| AP TERM (TERMINAL APRON)   | 4225       | 01/01/2010       | PCC     | APRON  | P    | 0     | 106,612.00       | 02/10/2015           | 5                 | 97.00  |
| AP TERM (TERMINAL APRON)   | 4230       | 01/01/2001       | AC      | APRON  | P    | 0     | 23,761.00        | 02/10/2015           | 14                | 9.00   |
| AP TERM (TERMINAL APRON)   | 4235       | 12/25/1998       | PCC     | APRON  | P    | 0     | 127,593.00       | 02/10/2015           | 17                | 91.00  |
| AP W (APRON WEST)  | 4605       | 01/01/2002       | AC      | APRON  | P    | 0     | 219,372.00       | 02/10/2015           | 13                | 71.00  |
| RW 17-35 (RUNWAY 17-35)  | 6105       | 11/01/2007       | PCC     | RUNWAY | P    | 0     | 33,178.00        | 02/10/2015           | 8                 | 91.00  |
| RW 17-35 (RUNWAY 17-35)  | 6110       | 11/01/2007       | PCC     | RUNWAY | P    | 0     | 110,822.00       | 02/10/2015           | 8                 | 93.00  |
| RW 17-35 (RUNWAY 17-35)  | 6115       | 11/01/2007       | AC      | RUNWAY | P    | 0     | 52,500.00        | 02/10/2015           | 8                 | 75.00  |
| RW 17-35 (RUNWAY 17-35)  | 6120       | 11/01/2007       | AC      | RUNWAY | P    | 0     | 26,250.00        | 02/10/2015           | 8                 | 78.00  |
| RW 17-35 (RUNWAY 17-35)  | 6125       | 11/01/2007       | PCC     | RUNWAY | P    | 0     | 396,211.00       | 02/10/2015           | 8                 | 92.00  |
| RW 17-35 (RUNWAY 17-35)  | 6130       | 11/01/2007       | PCC     | RUNWAY | P    | 0     | 131,789.00       | 02/10/2015           | 8                 | 91.00  |
| RW 8-26 (RUNWAY 8-26)  | 6205       | 01/01/2004       | AC      | RUNWAY | P    | 0     | 130,000.00       | 02/10/2015           | 11                | 75.00  |
| RW 8-26 (RUNWAY 8-26)  | 6210       | 01/01/2004       | AC      | RUNWAY | P    | 0     | 65,000.00        | 02/10/2015           | 11                | 77.00  |

Date: 5 /14/2015

## Section Condition Report

2 of 4

Pavement Database: FDOT NetworkID: PNS

| Branch ID             | Section ID | Last Const. Date | Surface | Use     | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI   |
|-----------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| RW 8-26 (RUNWAY 8-26) | 6215       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 95,000.00        | 02/10/2015           | 11                | 72.00 |
| RW 8-26 (RUNWAY 8-26) | 6220       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 47,500.00        | 02/10/2015           | 11                | 76.00 |
| RW 8-26 (RUNWAY 8-26) | 6225       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 89,997.00        | 02/10/2015           | 11                | 74.00 |
| RW 8-26 (RUNWAY 8-26) | 6230       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 44,999.00        | 02/10/2015           | 11                | 83.00 |
| RW 8-26 (RUNWAY 8-26) | 6235       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 170,000.00       | 02/10/2015           | 11                | 72.00 |
| RW 8-26 (RUNWAY 8-26) | 6240       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 85,000.00        | 02/10/2015           | 11                | 79.00 |
| RW 8-26 (RUNWAY 8-26) | 6245       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 40,000.00        | 02/10/2015           | 11                | 73.00 |
| RW 8-26 (RUNWAY 8-26) | 6250       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 20,000.00        | 02/10/2015           | 11                | 83.00 |
| RW 8-26 (RUNWAY 8-26) | 6255       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 60,000.00        | 02/10/2015           | 11                | 74.00 |
| RW 8-26 (RUNWAY 8-26) | 6260       | 01/01/2004       | AC      | RUNWAY  | P    | 0     | 30,000.00        | 02/10/2015           | 11                | 79.00 |
| RW 8-26 (RUNWAY 8-26) | 6265       | 01/01/2006       | AC      | RUNWAY  | P    | 0     | 100,100.00       | 02/10/2015           | 9                 | 80.00 |
| RW 8-26 (RUNWAY 8-26) | 6270       | 01/01/2006       | AC      | RUNWAY  | P    | 0     | 50,050.00        | 02/10/2015           | 9                 | 84.00 |
| TW A (TAXIWAY A)      | 105        | 01/01/2001       | AC      | TAXIWAY | P    | 0     | 286,014.00       | 02/10/2015           | 14                | 79.00 |
| TW A (TAXIWAY A)      | 115        | 02/01/2001       | AC      | TAXIWAY | P    | 0     | 297,891.00       | 02/10/2015           | 14                | 74.00 |
| TW A1 (TAXIWAY A1)    | 120        | 01/01/2001       | AC      | TAXIWAY | P    | 0     | 47,399.00        | 02/10/2015           | 14                | 37.00 |
| TW A2 (TAXIWAY A2)    | 150        | 01/01/2006       | AAC     | TAXIWAY | P    | 0     | 55,331.00        | 02/10/2015           | 9                 | 82.00 |
| TW A2 (TAXIWAY A2)    | 160        | 01/01/2000       | AC      | TAXIWAY | P    | 0     | 37,493.00        | 02/10/2015           | 15                | 76.00 |
| TW A3 (TAXIWAY A3)    | 170        | 01/01/2006       | PCC     | TAXIWAY | T    | 0     | 50,051.00        | 02/10/2015           | 9                 | 94.00 |
| TW A4 (TAXIWAY A4)    | 130        | 01/01/2001       | AC      | TAXIWAY | P    | 0     | 49,968.00        | 02/10/2015           | 14                | 84.00 |
| TW A5 (TAXIWAY A5)    | 125        | 01/01/2001       | AC      | TAXIWAY | P    | 0     | 49,806.00        | 02/10/2015           | 14                | 83.00 |
| TW A7 (TAXIWAY A7)    | 215        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 72,160.00        | 02/10/2015           | 13                | 67.00 |
| TW B (TAXIWAY B)      | 205        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 213,853.00       | 02/10/2015           | 13                | 80.00 |
| TW B (TAXIWAY B)      | 210        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 51,982.00        | 02/10/2015           | 13                | 77.00 |
| TW B (TAXIWAY B)      | 217        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 11,000.00        | 02/10/2015           | 13                | 75.00 |
| TW B (TAXIWAY B)      | 220        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 256,627.00       | 02/10/2015           | 13                | 80.00 |
| TW B (TAXIWAY B)      | 230        | 01/01/2005       | AC      | TAXIWAY | P    | 0     | 124,670.00       | 02/10/2015           | 10                | 88.00 |

Date: 5 /14/2015

## Section Condition Report

3 of 4

Pavement Database: FDOT NetworkID: PNS

| Branch ID          | Section ID | Last Const. Date | Surface | Use     | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI   |
|--------------------|------------|------------------|---------|---------|------|-------|------------------|----------------------|-------------------|-------|
| TW B2 (TAXIWAY B2) | 212        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 32,535.00        | 02/10/2015           | 13                | 83.00 |
| TW B2 (TAXIWAY B2) | 213        | 01/01/1988       | PCC     | TAXIWAY | P    | 0     | 10,751.00        | 02/10/2015           | 27                | 91.00 |
| TW B2 (TAXIWAY B2) | 240        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 50,378.00        | 02/10/2015           | 13                | 83.00 |
| TW B3 (TAXIWAY B3) | 255        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 50,248.00        | 02/10/2015           | 13                | 83.00 |
| TW B4 (TAXIWAY B4) | 260        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 50,114.00        | 02/10/2015           | 13                | 83.00 |
| TW B5 (TAXIWAY B5) | 265        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 48,322.00        | 02/10/2015           | 13                | 80.00 |
| TW B7 (TAXIWAY B7) | 270        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 14,899.00        | 02/10/2015           | 13                | 66.00 |
| TW B8 (TAXIWAY B8) | 280        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 13,317.00        | 02/10/2015           | 13                | 75.00 |
| TW C (TAXIWAY C)   | 250        | 01/01/2004       | AC      | TAXIWAY | P    | 0     | 33,625.00        | 02/10/2015           | 11                | 82.00 |
| TW C (TAXIWAY C)   | 252        | 01/01/2002       | AC      | TAXIWAY | P    | 0     | 16,451.00        | 02/10/2015           | 13                | 73.00 |
| TW C (TAXIWAY C)   | 505        | 01/01/1997       | AC      | TAXIWAY | P    | 0     | 13,138.00        | 02/10/2015           | 18                | 75.00 |
| TW C (TAXIWAY C)   | 510        | 01/01/1997       | AC      | TAXIWAY | P    | 0     | 67,178.00        | 02/10/2015           | 18                | 79.00 |
| TW C2 (TAXIWAY C2) | 515        | 01/01/1997       | AC      | TAXIWAY | P    | 0     | 31,643.00        | 02/10/2015           | 18                | 80.00 |
| TW D (TAXIWAY D)   | 140        | 01/01/2001       | AC      | TAXIWAY | P    | 0     | 43,648.00        | 02/10/2015           | 14                | 75.00 |
| TW D (TAXIWAY D)   | 405        | 01/01/2000       | AC      | TAXIWAY | P    | 0     | 118,752.00       | 02/10/2015           | 15                | 79.00 |
| TW D (TAXIWAY D)   | 410        | 01/01/2005       | AC      | TAXIWAY | P    | 0     | 20,158.00        | 02/10/2015           | 10                | 75.00 |
| TW D (TAXIWAY D)   | 430        | 01/01/2005       | AC      | TAXIWAY | P    | 0     | 48,300.00        | 02/10/2015           | 10                | 86.00 |
| TW D1 (TAXIWAY D1) | 415        | 01/01/2000       | AC      | TAXIWAY | P    | 0     | 13,134.00        | 02/10/2015           | 15                | 83.00 |
| TW D2 (TAXIWAY D2) | 420        | 01/01/2000       | AC      | TAXIWAY | P    | 0     | 13,134.00        | 02/10/2015           | 15                | 80.00 |
| TW D3 (TAXIWAY D3) | 425        | 01/01/2006       | AAC     | TAXIWAY | P    | 0     | 14,220.00        | 02/10/2015           | 9                 | 87.00 |



**Section Condition Report***Pavement Database: FDOT*

| Age Category | Average Age At Inspection | Total Area (SqFt) | Number of Sections | Arithmetic Average PCI | PCI Standard Deviation | Weighted Average PCI |
|--------------|---------------------------|-------------------|--------------------|------------------------|------------------------|----------------------|
| 0-02         | 0.00                      | 300,570.00        | 6                  | 100.00                 | 0.00                   | 100.00               |
| 03-05        | 5.00                      | 224,936.00        | 3                  | 98.00                  | 1.73                   | 98.02                |
| 06-10        | 8.79                      | 1,213,630.00      | 14                 | 85.43                  | 6.57                   | 88.23                |
| 11-15        | 12.71                     | 2,993,379.00      | 38                 | 74.58                  | 13.56                  | 75.64                |
| 16-20        | 17.63                     | 1,164,691.00      | 8                  | 72.25                  | 12.08                  | 65.82                |
| 26-30        | 27.00                     | 377,808.00        | 2                  | 92.50                  | 2.12                   | 93.91                |
| 36-40        | 38.00                     | 256,288.00        | 1                  | 91.00                  | 0.00                   | 91.00                |
| All          | 11.86                     | 6,531,302.00      | 72                 | 80.25                  | 14.14                  | 79.78                |

# APPENDIX D

---

- PAVEMENT PERFORMANCE PREDICTION
- PAVEMENT PERFORMANCE BY PAVEMENT USE



Table D-1: Pavement Performance Prediction

| Branch ID | Section ID | 2014 PCI | Pavement Performance Model - PCI |      |      |      |      |      |      |      |      |      |
|-----------|------------|----------|----------------------------------|------|------|------|------|------|------|------|------|------|
|           |            |          | 2015                             | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| AP CARGO  | 4705       | 100      | 100                              | 98   | 97   | 96   | 95   | 94   | 93   | 91   | 90   | 89   |
| AP CARGO  | 4710       | 100      | 100                              | 98   | 97   | 96   | 95   | 94   | 93   | 91   | 90   | 89   |
| AP E      | 4405       | 63       | 62                               | 61   | 59   | 57   | 55   | 53   | 51   | 49   | 47   | 45   |
| AP GA     | 4310       | 100      | 98                               | 94   | 90   | 86   | 83   | 80   | 78   | 76   | 74   | 72   |
| AP GA     | 4315       | 100      | 100                              | 98   | 97   | 96   | 95   | 94   | 93   | 91   | 90   | 89   |
| AP GA     | 4320       | 100      | 98                               | 94   | 90   | 86   | 83   | 80   | 78   | 76   | 74   | 72   |
| AP GA     | 4325       | 100      | 98                               | 94   | 90   | 86   | 83   | 80   | 78   | 76   | 74   | 72   |
| AP S      | 4505       | 71       | 70                               | 69   | 67   | 65   | 63   | 61   | 59   | 57   | 55   | 53   |
| AP S      | 4510       | 51       | 50                               | 49   | 47   | 45   | 43   | 41   | 39   | 37   | 35   | 33   |
| AP S      | 4515       | 68       | 67                               | 66   | 64   | 62   | 60   | 58   | 56   | 54   | 52   | 50   |
| AP TERM   | 4205       | 94       | 94                               | 92   | 91   | 90   | 89   | 88   | 87   | 85   | 84   | 83   |
| AP TERM   | 4210       | 91       | 91                               | 89   | 88   | 87   | 86   | 85   | 84   | 82   | 81   | 80   |
| AP TERM   | 4215       | 97       | 97                               | 95   | 94   | 93   | 92   | 91   | 90   | 88   | 87   | 86   |
| AP TERM   | 4220       | 100      | 100                              | 98   | 97   | 96   | 95   | 94   | 93   | 91   | 90   | 89   |
| AP TERM   | 4225       | 97       | 97                               | 95   | 94   | 93   | 92   | 91   | 90   | 88   | 87   | 86   |
| AP TERM   | 4230       | 9        | 8                                | 7    | 5    | 3    | 1    | 0    | 0    | 0    | 0    | 0    |
| AP TERM   | 4235       | 91       | 91                               | 89   | 88   | 87   | 86   | 85   | 84   | 82   | 81   | 80   |
| AP W      | 4605       | 71       | 70                               | 69   | 67   | 65   | 63   | 61   | 59   | 57   | 55   | 53   |
| RW 17-35  | 6105       | 91       | 91                               | 89   | 88   | 87   | 85   | 84   | 83   | 82   | 80   | 79   |
| RW 17-35  | 6110       | 93       | 93                               | 91   | 90   | 89   | 87   | 86   | 85   | 84   | 82   | 81   |
| RW 17-35  | 6115       | 75       | 75                               | 73   | 72   | 70   | 69   | 67   | 66   | 64   | 63   | 62   |
| RW 17-35  | 6120       | 78       | 78                               | 76   | 75   | 73   | 72   | 70   | 69   | 67   | 66   | 65   |
| RW 17-35  | 6125       | 92       | 92                               | 90   | 89   | 88   | 86   | 85   | 84   | 83   | 81   | 80   |
| RW 17-35  | 6130       | 91       | 91                               | 89   | 88   | 87   | 85   | 84   | 83   | 82   | 80   | 79   |
| RW 8-26   | 6205       | 75       | 75                               | 73   | 72   | 70   | 69   | 67   | 66   | 64   | 63   | 62   |
| RW 8-26   | 6210       | 77       | 77                               | 75   | 74   | 72   | 71   | 69   | 68   | 66   | 65   | 64   |
| RW 8-26   | 6215       | 72       | 72                               | 70   | 69   | 67   | 66   | 64   | 63   | 61   | 60   | 59   |
| RW 8-26   | 6220       | 76       | 76                               | 74   | 73   | 71   | 70   | 68   | 67   | 65   | 64   | 63   |



| Branch ID | Section ID | 2014 PCI | Pavement Performance Model - PCI |      |      |      |      |      |      |      |      |      |
|-----------|------------|----------|----------------------------------|------|------|------|------|------|------|------|------|------|
|           |            |          | 2015                             | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| RW 8-26   | 6225       | 74       | 74                               | 72   | 71   | 69   | 68   | 66   | 65   | 63   | 62   | 61   |
| RW 8-26   | 6230       | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 70   |
| RW 8-26   | 6235       | 72       | 72                               | 70   | 69   | 67   | 66   | 64   | 63   | 61   | 60   | 59   |
| RW 8-26   | 6240       | 79       | 79                               | 77   | 76   | 74   | 73   | 71   | 70   | 68   | 67   | 66   |
| RW 8-26   | 6245       | 73       | 73                               | 71   | 70   | 68   | 67   | 65   | 64   | 62   | 61   | 60   |
| RW 8-26   | 6250       | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 70   |
| RW 8-26   | 6255       | 74       | 74                               | 72   | 71   | 69   | 68   | 66   | 65   | 63   | 62   | 61   |
| RW 8-26   | 6260       | 79       | 79                               | 77   | 76   | 74   | 73   | 71   | 70   | 68   | 67   | 66   |
| RW 8-26   | 6265       | 80       | 80                               | 78   | 77   | 75   | 74   | 72   | 71   | 69   | 68   | 67   |
| RW 8-26   | 6270       | 84       | 84                               | 82   | 81   | 79   | 78   | 76   | 75   | 73   | 72   | 71   |
| TW A      | 105        | 79       | 79                               | 77   | 76   | 74   | 73   | 71   | 70   | 68   | 67   | 65   |
| TW A      | 115        | 74       | 74                               | 72   | 71   | 69   | 68   | 66   | 65   | 63   | 62   | 60   |
| TW A1     | 120        | 37       | 37                               | 35   | 34   | 32   | 31   | 29   | 28   | 26   | 25   | 23   |
| TW A2     | 150        | 82       | 81                               | 80   | 78   | 76   | 74   | 73   | 71   | 70   | 69   | 68   |
| TW A2     | 160        | 76       | 76                               | 74   | 73   | 71   | 70   | 68   | 67   | 65   | 64   | 62   |
| TW A3     | 170        | 94       | 94                               | 92   | 91   | 90   | 88   | 87   | 86   | 85   | 83   | 82   |
| TW A4     | 130        | 84       | 84                               | 82   | 81   | 79   | 78   | 76   | 75   | 73   | 72   | 70   |
| TW A5     | 125        | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 69   |
| TW A7     | 215        | 67       | 67                               | 65   | 64   | 62   | 61   | 59   | 58   | 56   | 55   | 53   |
| TW B      | 205        | 80       | 80                               | 78   | 77   | 75   | 74   | 72   | 71   | 69   | 68   | 66   |
| TW B      | 210        | 77       | 77                               | 75   | 74   | 72   | 71   | 69   | 68   | 66   | 65   | 63   |
| TW B      | 217        | 75       | 75                               | 73   | 72   | 70   | 69   | 67   | 66   | 64   | 63   | 61   |
| TW B      | 220        | 80       | 80                               | 78   | 77   | 75   | 74   | 72   | 71   | 69   | 68   | 66   |
| TW B      | 230        | 88       | 88                               | 86   | 85   | 83   | 82   | 80   | 79   | 77   | 76   | 74   |
| TW B2     | 212        | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 69   |
| TW B2     | 213        | 91       | 91                               | 89   | 88   | 87   | 85   | 84   | 83   | 82   | 80   | 79   |
| TW B2     | 240        | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 69   |
| TW B3     | 255        | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 69   |
| TW B4     | 260        | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 69   |


| Branch ID | Section ID | 2014 PCI | Pavement Performance Model - PCI |      |      |      |      |      |      |      |      |      |
|-----------|------------|----------|----------------------------------|------|------|------|------|------|------|------|------|------|
|           |            |          | 2015                             | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 |
| TW B5     | 265        | 80       | 80                               | 78   | 77   | 75   | 74   | 72   | 71   | 69   | 68   | 66   |
| TW B7     | 270        | 66       | 66                               | 64   | 63   | 61   | 60   | 58   | 57   | 55   | 54   | 52   |
| TW B8     | 280        | 75       | 75                               | 73   | 72   | 70   | 69   | 67   | 66   | 64   | 63   | 61   |
| TW C      | 250        | 82       | 82                               | 80   | 79   | 77   | 76   | 74   | 73   | 71   | 70   | 68   |
| TW C      | 252        | 73       | 73                               | 71   | 70   | 68   | 67   | 65   | 64   | 62   | 61   | 59   |
| TW C      | 505        | 75       | 75                               | 73   | 72   | 70   | 69   | 67   | 66   | 64   | 63   | 61   |
| TW C      | 510        | 79       | 79                               | 77   | 76   | 74   | 73   | 71   | 70   | 68   | 67   | 65   |
| TW C2     | 515        | 80       | 80                               | 78   | 77   | 75   | 74   | 72   | 71   | 69   | 68   | 66   |
| TW D      | 140        | 75       | 75                               | 73   | 72   | 70   | 69   | 67   | 66   | 64   | 63   | 61   |
| TW D      | 405        | 79       | 79                               | 77   | 76   | 74   | 73   | 71   | 70   | 68   | 67   | 65   |
| TW D      | 410        | 75       | 75                               | 73   | 72   | 70   | 69   | 67   | 66   | 64   | 63   | 61   |
| TW D      | 430        | 86       | 86                               | 84   | 83   | 81   | 80   | 78   | 77   | 75   | 74   | 72   |
| TW D1     | 415        | 83       | 83                               | 81   | 80   | 78   | 77   | 75   | 74   | 72   | 71   | 69   |
| TW D2     | 420        | 80       | 80                               | 78   | 77   | 75   | 74   | 72   | 71   | 69   | 68   | 66   |
| TW D3     | 425        | 87       | 86                               | 84   | 82   | 80   | 78   | 77   | 75   | 73   | 72   | 70   |

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.


\* Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey. Please refer to Section 3 for discussion on the updates to the ASTM D 5640 that may affect PCI in comparison to previous program update.

Figure D-1: Pavement Performance by Pavement Use


(a) Runway



(b) Taxiway



(c) Apron







# APPENDIX E

---

## ● YEAR-1 PREVENTATIVE ACTIVITIES



Table E-1: Year-1 Preventative Activities

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description         | Work Quantity | Work Unit | Unit Cost | Work Cost     |
|-------------|-----------|------------|----------------------|-------------------|--------------------------|---------------|-----------|-----------|---------------|
| EAST APRON  | AP E      | 4405       | BLOCK CR             | L                 | Surface Seal             | 22,069.60     | SqFt      | \$0.55    | \$ 12,138.39  |
| EAST APRON  | AP E      | 4405       | L & T CR             | M                 | Crack Sealing - AC       | 3,099.30      | Ft        | \$2.75    | \$ 8,523.18   |
| EAST APRON  | AP E      | 4405       | L & T CR             | L                 | Crack Sealing - AC       | 13,261.00     | Ft        | \$2.75    | \$ 36,467.62  |
| EAST APRON  | AP E      | 4405       | RAVELING             | L                 | Surface Seal             | 255,240.00    | SqFt      | \$0.55    | \$ 140,383.17 |
| SOUTH APRON | AP S      | 4505       | L & T CR             | L                 | Crack Sealing - AC       | 3,692.70      | Ft        | \$2.75    | \$ 10,154.82  |
| SOUTH APRON | AP S      | 4505       | OIL SPILLAGE         | N                 | Surface Seal             | 127.70        | SqFt      | \$0.55    | \$ 70.22      |
| SOUTH APRON | AP S      | 4505       | RAVELING             | L                 | Surface Seal             | 34,899.10     | SqFt      | \$0.55    | \$ 19,194.68  |
| SOUTH APRON | AP S      | 4510       | BLOCK CR             | L                 | Surface Seal             | 127,195.10    | SqFt      | \$0.55    | \$ 69,957.91  |
| SOUTH APRON | AP S      | 4510       | L & T CR             | L                 | Crack Sealing - AC       | 11,516.20     | Ft        | \$2.75    | \$ 31,669.51  |
| SOUTH APRON | AP S      | 4510       | L & T CR             | M                 | Crack Sealing - AC       | 445.70        | Ft        | \$2.75    | \$ 1,225.60   |
| SOUTH APRON | AP S      | 4510       | OIL SPILLAGE         | N                 | Surface Seal             | 109.30        | SqFt      | \$0.55    | \$ 60.11      |
| SOUTH APRON | AP S      | 4510       | RAVELING             | L                 | Surface Seal             | 265,621.30    | SqFt      | \$0.55    | \$ 146,092.91 |
| SOUTH APRON | AP S      | 4510       | RAVELING             | M                 | Surface Seal             | 69,525.00     | SqFt      | \$0.55    | \$ 38,239.08  |
| SOUTH APRON | AP S      | 4515       | DEPRESSION           | L                 | Patching - AC Full Depth | 743.30        | SqFt      | \$5.00    | \$ 3,716.41   |
| SOUTH APRON | AP S      | 4515       | L & T CR             | L                 | Crack Sealing - AC       | 9,396.90      | Ft        | \$2.75    | \$ 25,841.42  |



# Pavement Evaluation Report - Pensacola International Airport

| Branch Name    | Branch ID | Section ID | Distress Description | Distress Severity | Work Description             | Work Quantity | Work Unit | Unit Cost | Work Cost     |
|----------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|---------------|
| SOUTH APRON    | AP S      | 4515       | L & T CR             | M                 | Crack Sealing - AC           | 358.00        | Ft        | \$2.75    | \$ 984.44     |
| SOUTH APRON    | AP S      | 4515       | OIL SPILLAGE         | N                 | Surface Seal                 | 75.70         | SqFt      | \$0.55    | \$ 41.62      |
| SOUTH APRON    | AP S      | 4515       | RAVELING             | L                 | Surface Seal                 | 50,463.50     | SqFt      | \$0.55    | \$ 27,755.18  |
| SOUTH APRON    | AP S      | 4515       | RAVELING             | M                 | Surface Seal                 | 14,319.10     | SqFt      | \$0.55    | \$ 7,875.56   |
| TERMINAL APRON | AP TERM   | 4205       | SCALING              | M                 | Patching - PCC Partial Depth | 3,045.50      | SqFt      | \$19.10   | \$ 58,169.39  |
| TERMINAL APRON | AP TERM   | 4205       | SCALING              | L                 | Patching - PCC Partial Depth | 30,455.20     | SqFt      | \$19.10   | \$ 581,693.92 |
| TERMINAL APRON | AP TERM   | 4205       | FAULTING             | L                 | Patching - PCC Partial Depth | 1,218.20      | SqFt      | \$19.10   | \$ 23,267.76  |
| TERMINAL APRON | AP TERM   | 4205       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 438.60        | Ft        | \$4.25    | \$ 1,863.86   |
| TERMINAL APRON | AP TERM   | 4205       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 40.00         | SqFt      | \$19.10   | \$ 763.38     |
| TERMINAL APRON | AP TERM   | 4210       | SCALING              | L                 | Patching - PCC Partial Depth | 8,657.00      | SqFt      | \$19.10   | \$ 165,348.16 |
| TERMINAL APRON | AP TERM   | 4210       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 767.00        | Ft        | \$4.25    | \$ 3,259.70   |
| TERMINAL APRON | AP TERM   | 4210       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 104.80        | SqFt      | \$19.10   | \$ 2,002.61   |
| TERMINAL APRON | AP TERM   | 4210       | CORNER SPALL         | L                 | Patching - PCC Partial Depth | 26.20         | SqFt      | \$19.10   | \$ 500.65     |
| TERMINAL APRON | AP TERM   | 4215       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 36.50         | SqFt      | \$19.10   | \$ 696.72     |
| TERMINAL APRON | AP TERM   | 4220       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 47.10         | Ft        | \$4.25    | \$ 200.13     |
| TERMINAL APRON | AP TERM   | 4225       | SCALING              | L                 | Patching - PCC Partial Depth | 6,302.20      | SqFt      | \$19.10   | \$ 120,371.08 |

| Branch Name    | Branch ID | Section ID | Distress Description | Distress Severity | Work Description             | Work Quantity | Work Unit | Unit Cost | Work Cost     |
|----------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|---------------|
| TERMINAL APRON | AP TERM   | 4225       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 11.50         | SqFt      | \$19.10   | \$ 219.40     |
| TERMINAL APRON | AP TERM   | 4230       | ALLIGATOR CR         | M                 | Patching - AC Full Depth     | 955.10        | SqFt      | \$5.00    | \$ 4,775.71   |
| TERMINAL APRON | AP TERM   | 4230       | ALLIGATOR CR         | L                 | Patching - AC Full Depth     | 1,378.30      | SqFt      | \$5.00    | \$ 6,891.68   |
| TERMINAL APRON | AP TERM   | 4230       | ALLIGATOR CR         | H                 | Patching - AC Full Depth     | 748.20        | SqFt      | \$5.00    | \$ 3,740.94   |
| TERMINAL APRON | AP TERM   | 4230       | BLOCK CR             | M                 | Patching - AC Full Depth     | 3,210.90      | SqFt      | \$5.00    | \$ 16,054.74  |
| TERMINAL APRON | AP TERM   | 4230       | BLOCK CR             | L                 | Surface Seal                 | 1,926.60      | SqFt      | \$0.55    | \$ 1,059.62   |
| TERMINAL APRON | AP TERM   | 4230       | DEPRESSION           | L                 | Patching - AC Full Depth     | 89.70         | SqFt      | \$5.00    | \$ 448.42     |
| TERMINAL APRON | AP TERM   | 4230       | L & T CR             | L                 | Crack Sealing - AC           | 976.10        | Ft        | \$2.75    | \$ 2,684.35   |
| TERMINAL APRON | AP TERM   | 4230       | OIL SPILLAGE         | N                 | Surface Seal                 | 835.80        | SqFt      | \$0.55    | \$ 459.69     |
| TERMINAL APRON | AP TERM   | 4230       | PATCHING             | H                 | Patching - AC Full Depth     | 178.10        | SqFt      | \$5.00    | \$ 890.26     |
| TERMINAL APRON | AP TERM   | 4230       | PATCHING             | M                 | Patching - AC Full Depth     | 3,025.80      | SqFt      | \$5.00    | \$ 15,129.06  |
| TERMINAL APRON | AP TERM   | 4230       | RAVELING             | L                 | Surface Seal                 | 4,165.70      | SqFt      | \$0.55    | \$ 2,291.14   |
| TERMINAL APRON | AP TERM   | 4230       | RAVELING             | M                 | Surface Seal                 | 16,658.40     | SqFt      | \$0.55    | \$ 9,162.19   |
| TERMINAL APRON | AP TERM   | 4230       | RUTTING              | M                 | Patching - AC Full Depth     | 642.20        | SqFt      | \$5.00    | \$ 3,210.95   |
| TERMINAL APRON | AP TERM   | 4235       | SCALING              | L                 | Patching - PCC Partial Depth | 8,530.20      | SqFt      | \$19.10   | \$ 162,926.52 |
| TERMINAL APRON | AP TERM   | 4235       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 36.10         | Ft        | \$4.25    | \$ 153.54     |



# Pavement Evaluation Report - Pensacola International Airport

| Branch Name  | Branch ID | Section ID | Distress Description | Distress Severity | Work Description             | Work Quantity | Work Unit | Unit Cost | Work Cost    |
|--------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|--------------|
| APRON WEST   | AP W      | 4605       | L & T CR             | M                 | Crack Sealing - AC           | 202.50        | Ft        | \$2.75    | \$ 556.87    |
| APRON WEST   | AP W      | 4605       | L & T CR             | L                 | Crack Sealing - AC           | 514.70        | Ft        | \$2.75    | \$ 1,415.37  |
| APRON WEST   | AP W      | 4605       | OIL SPILLAGE         | N                 | Surface Seal                 | 359.00        | SqFt      | \$0.55    | \$ 197.47    |
| APRON WEST   | AP W      | 4605       | RAVELING             | L                 | Surface Seal                 | 63,280.40     | SqFt      | \$0.55    | \$ 34,804.50 |
| RUNWAY 17-35 | RW 17-35  | 6105       | JT SEAL DMG          | L                 | Joint Seal - PCC             | 5,228.20      | Ft        | \$3.00    | \$ 15,684.64 |
| RUNWAY 17-35 | RW 17-35  | 6105       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 60.80         | Ft        | \$4.25    | \$ 258.54    |
| RUNWAY 17-35 | RW 17-35  | 6105       | JOINT SPALL          | M                 | Patching - PCC Partial Depth | 26.60         | SqFt      | \$19.10   | \$ 508.27    |
| RUNWAY 17-35 | RW 17-35  | 6105       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 665.30        | SqFt      | \$19.10   | \$ 12,706.65 |
| RUNWAY 17-35 | RW 17-35  | 6105       | CORNER SPALL         | L                 | Patching - PCC Partial Depth | 22.20         | SqFt      | \$19.10   | \$ 423.55    |
| RUNWAY 17-35 | RW 17-35  | 6110       | JT SEAL DMG          | L                 | Joint Seal - PCC             | 1,177.50      | Ft        | \$3.00    | \$ 3,532.38  |
| RUNWAY 17-35 | RW 17-35  | 6110       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 16.60         | Ft        | \$4.25    | \$ 70.35     |
| RUNWAY 17-35 | RW 17-35  | 6110       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 126.70        | SqFt      | \$19.10   | \$ 2,420.36  |
| RUNWAY 17-35 | RW 17-35  | 6110       | CORNER SPALL         | L                 | Patching - PCC Partial Depth | 36.20         | SqFt      | \$19.10   | \$ 691.53    |
| RUNWAY 17-35 | RW 17-35  | 6115       | L & T CR             | L                 | Crack Sealing - AC           | 367.50        | Ft        | \$2.75    | \$ 1,010.62  |
| RUNWAY 17-35 | RW 17-35  | 6115       | RAVELING             | L                 | Surface Seal                 | 17,500.00     | SqFt      | \$0.55    | \$ 9,625.08  |
| RUNWAY 17-35 | RW 17-35  | 6120       | L & T CR             | M                 | Crack Sealing - AC           | 31.50         | Ft        | \$2.75    | \$ 86.62     |

| Branch Name  | Branch ID | Section ID | Distress Description | Distress Severity | Work Description             | Work Quantity | Work Unit | Unit Cost | Work Cost    |
|--------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|--------------|
| RUNWAY 17-35 | RW 17-35  | 6120       | L & T CR             | L                 | Crack Sealing - AC           | 364.90        | Ft        | \$2.75    | \$ 1,003.41  |
| RUNWAY 17-35 | RW 17-35  | 6120       | RAVELING             | L                 | Surface Seal                 | 2,625.00      | SqFt      | \$0.55    | \$ 1,443.76  |
| RUNWAY 17-35 | RW 17-35  | 6125       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 250.70        | Ft        | \$4.25    | \$ 1,065.45  |
| RUNWAY 17-35 | RW 17-35  | 6125       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 643.20        | SqFt      | \$19.10   | \$ 12,285.57 |
| RUNWAY 17-35 | RW 17-35  | 6125       | CORNER SPALL         | L                 | Patching - PCC Partial Depth | 10.50         | SqFt      | \$19.10   | \$ 201.40    |
| RUNWAY 17-35 | RW 17-35  | 6130       | SCALING              | L                 | Patching - PCC Partial Depth | 259.80        | SqFt      | \$19.10   | \$ 4,962.99  |
| RUNWAY 17-35 | RW 17-35  | 6130       | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 83.30         | Ft        | \$4.25    | \$ 353.95    |
| RUNWAY 17-35 | RW 17-35  | 6130       | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 236.80        | SqFt      | \$19.10   | \$ 4,523.00  |
| RUNWAY 8-26  | RW 8-26   | 6205       | L & T CR             | L                 | Crack Sealing - AC           | 6,042.40      | Ft        | \$2.75    | \$ 16,616.58 |
| RUNWAY 8-26  | RW 8-26   | 6205       | RAVELING             | L                 | Surface Seal                 | 31,200.00     | SqFt      | \$0.55    | \$ 17,160.14 |
| RUNWAY 8-26  | RW 8-26   | 6210       | L & T CR             | L                 | Crack Sealing - AC           | 2,873.00      | Ft        | \$2.75    | \$ 7,900.74  |
| RUNWAY 8-26  | RW 8-26   | 6210       | RAVELING             | L                 | Surface Seal                 | 3,250.00      | SqFt      | \$0.55    | \$ 1,787.51  |
| RUNWAY 8-26  | RW 8-26   | 6215       | L & T CR             | L                 | Crack Sealing - AC           | 6,034.40      | Ft        | \$2.75    | \$ 16,594.58 |
| RUNWAY 8-26  | RW 8-26   | 6215       | RAVELING             | L                 | Surface Seal                 | 28,500.00     | SqFt      | \$0.55    | \$ 15,675.13 |
| RUNWAY 8-26  | RW 8-26   | 6220       | L & T CR             | L                 | Crack Sealing - AC           | 2,344.30      | Ft        | \$2.75    | \$ 6,446.84  |
| RUNWAY 8-26  | RW 8-26   | 6220       | RAVELING             | L                 | Surface Seal                 | 2,376.50      | SqFt      | \$0.55    | \$ 1,307.06  |





# Pavement Evaluation Report - Pensacola International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description         | Work Quantity | Work Unit | Unit Cost | Work Cost    |
|-------------|-----------|------------|----------------------|-------------------|--------------------------|---------------|-----------|-----------|--------------|
| RUNWAY 8-26 | RW 8-26   | 6225       | ALLIGATOR CR         | L                 | Patching - AC Full Depth | 49.40         | SqFt      | \$5.00    | \$ 247.02    |
| RUNWAY 8-26 | RW 8-26   | 6225       | L & T CR             | L                 | Crack Sealing - AC       | 2,066.30      | Ft        | \$2.75    | \$ 5,682.40  |
| RUNWAY 8-26 | RW 8-26   | 6225       | RAVELING             | L                 | Surface Seal             | 28,799.00     | SqFt      | \$0.55    | \$ 15,839.60 |
| RUNWAY 8-26 | RW 8-26   | 6230       | L & T CR             | L                 | Crack Sealing - AC       | 606.00        | Ft        | \$2.75    | \$ 1,666.46  |
| RUNWAY 8-26 | RW 8-26   | 6230       | RAVELING             | L                 | Surface Seal             | 2,249.90      | SqFt      | \$0.55    | \$ 1,237.48  |
| RUNWAY 8-26 | RW 8-26   | 6235       | L & T CR             | L                 | Crack Sealing - AC       | 10,049.40     | Ft        | \$2.75    | \$ 27,635.90 |
| RUNWAY 8-26 | RW 8-26   | 6235       | RAVELING             | L                 | Surface Seal             | 60,714.30     | SqFt      | \$0.55    | \$ 33,393.14 |
| RUNWAY 8-26 | RW 8-26   | 6240       | L & T CR             | L                 | Crack Sealing - AC       | 2,937.60      | Ft        | \$2.75    | \$ 8,078.39  |
| RUNWAY 8-26 | RW 8-26   | 6240       | RAVELING             | L                 | Surface Seal             | 4,250.00      | SqFt      | \$0.55    | \$ 2,337.52  |
| RUNWAY 8-26 | RW 8-26   | 6245       | L & T CR             | L                 | Crack Sealing - AC       | 2,392.00      | Ft        | \$2.75    | \$ 6,577.99  |
| RUNWAY 8-26 | RW 8-26   | 6245       | RAVELING             | L                 | Surface Seal             | 12,000.00     | SqFt      | \$0.55    | \$ 6,600.05  |
| RUNWAY 8-26 | RW 8-26   | 6250       | L & T CR             | L                 | Crack Sealing - AC       | 400.00        | Ft        | \$2.75    | \$ 1,100.00  |
| RUNWAY 8-26 | RW 8-26   | 6250       | RAVELING             | L                 | Surface Seal             | 1,000.00      | SqFt      | \$0.55    | \$ 550.00    |
| RUNWAY 8-26 | RW 8-26   | 6255       | L & T CR             | L                 | Crack Sealing - AC       | 3,404.00      | Ft        | \$2.75    | \$ 9,360.99  |
| RUNWAY 8-26 | RW 8-26   | 6255       | RAVELING             | L                 | Surface Seal             | 14,000.00     | SqFt      | \$0.55    | \$ 7,700.06  |
| RUNWAY 8-26 | RW 8-26   | 6260       | L & T CR             | L                 | Crack Sealing - AC       | 972.00        | Ft        | \$2.75    | \$ 2,673.00  |

| Branch Name   | Branch ID | Section ID | Distress Description | Distress Severity | Work Description         | Work Quantity | Work Unit | Unit Cost | Work Cost    |
|---------------|-----------|------------|----------------------|-------------------|--------------------------|---------------|-----------|-----------|--------------|
| RUNWAY 8-26   | RW 8-26   | 6260       | RAVELING             | L                 | Surface Seal             | 1,500.00      | SqFt      | \$0.55    | \$ 825.01    |
| RUNWAY 8-26   | RW 8-26   | 6265       | L & T CR             | L                 | Crack Sealing - AC       | 1,809.80      | Ft        | \$2.75    | \$ 4,976.97  |
| RUNWAY 8-26   | RW 8-26   | 6265       | RAVELING             | L                 | Surface Seal             | 11,011.00     | SqFt      | \$0.55    | \$ 6,056.10  |
| RUNWAY 8-26   | RW 8-26   | 6270       | L & T CR             | L                 | Crack Sealing - AC       | 340.30        | Ft        | \$2.75    | \$ 935.93    |
| RUNWAY 8-26   | RW 8-26   | 6270       | RAVELING             | L                 | Surface Seal             | 2,502.50      | SqFt      | \$0.55    | \$ 1,376.39  |
| TAXIWAY ALPHA | TW A      | 105        | L & T CR             | L                 | Crack Sealing - AC       | 9,585.30      | Ft        | \$2.75    | \$ 26,359.64 |
| TAXIWAY ALPHA | TW A      | 105        | RAVELING             | L                 | Surface Seal             | 17,742.90     | SqFt      | \$0.55    | \$ 9,758.66  |
| TAXIWAY ALPHA | TW A      | 115        | ALLIGATOR CR         | L                 | Patching - AC Full Depth | 223.00        | SqFt      | \$5.00    | \$ 1,114.98  |
| TAXIWAY ALPHA | TW A      | 115        | L & T CR             | L                 | Crack Sealing - AC       | 15,195.60     | Ft        | \$2.75    | \$ 41,787.82 |
| TAXIWAY ALPHA | TW A      | 115        | RAVELING             | L                 | Surface Seal             | 14,926.60     | SqFt      | \$0.55    | \$ 8,209.67  |
| TAXIWAY ALPHA | TW A      | 115        | RUTTING              | L                 | Patching - AC Full Depth | 167.00        | SqFt      | \$5.00    | \$ 834.92    |
| TAXIWAY A1    | TW A1     | 120        | ALLIGATOR CR         | L                 | Patching - AC Full Depth | 215.80        | SqFt      | \$5.00    | \$ 1,078.99  |
| TAXIWAY A1    | TW A1     | 120        | ALLIGATOR CR         | M                 | Patching - AC Full Depth | 1,065.10      | SqFt      | \$5.00    | \$ 5,325.28  |
| TAXIWAY A1    | TW A1     | 120        | L & T CR             | L                 | Crack Sealing - AC       | 473.40        | Ft        | \$2.75    | \$ 1,301.75  |
| TAXIWAY A1    | TW A1     | 120        | OIL SPILLAGE         | N                 | Surface Seal             | 87.10         | SqFt      | \$0.55    | \$ 47.88     |
| TAXIWAY A1    | TW A1     | 120        | RAVELING             | L                 | Surface Seal             | 4,742.60      | SqFt      | \$0.55    | \$ 2,608.44  |



# Pavement Evaluation Report - Pensacola International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description             | Work Quantity | Work Unit | Unit Cost | Work Cost   |
|-------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|-------------|
| TAXIWAY A1  | TW A1     | 120        | RUTTING              | L                 | Patching - AC Full Depth     | 937.80        | SqFt      | \$5.00    | \$ 4,689.00 |
| TAXIWAY A2  | TW A2     | 150        | L & T CR             | L                 | Crack Sealing - AC           | 1,057.60      | Ft        | \$2.75    | \$ 2,908.48 |
| TAXIWAY A2  | TW A2     | 150        | RAVELING             | L                 | Surface Seal                 | 2,763.80      | SqFt      | \$0.55    | \$ 1,520.11 |
| TAXIWAY A2  | TW A2     | 160        | L & T CR             | L                 | Crack Sealing - AC           | 989.80        | Ft        | \$2.75    | \$ 2,721.99 |
| TAXIWAY A2  | TW A2     | 160        | RAVELING             | L                 | Surface Seal                 | 7,498.60      | SqFt      | \$0.55    | \$ 4,124.26 |
| TAXIWAY A3  | TW A3     | 170        | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 79.50         | SqFt      | \$19.10   | \$ 1,519.09 |
| TAXIWAY A3  | TW A4     | 130        | BLEEDING             | N                 | Patching - AC Partial Depth  | 48.00         | SqFt      | \$3.00    | \$ 144.14   |
| TAXIWAY A4  | TW A4     | 130        | L & T CR             | L                 | Crack Sealing - AC           | 192.20        | Ft        | \$2.75    | \$ 528.51   |
| TAXIWAY A4  | TW A4     | 130        | RAVELING             | L                 | Surface Seal                 | 2,498.40      | SqFt      | \$0.55    | \$ 1,374.13 |
| TAXIWAY A5  | TW A5     | 125        | DEPRESSION           | L                 | Patching - AC Full Depth     | 295.80        | SqFt      | \$5.00    | \$ 1,479.18 |
| TAXIWAY A5  | TW A5     | 125        | L & T CR             | L                 | Crack Sealing - AC           | 51.30         | Ft        | \$2.75    | \$ 140.98   |
| TAXIWAY A5  | TW A5     | 125        | RAVELING             | L                 | Surface Seal                 | 2,486.50      | SqFt      | \$0.55    | \$ 1,367.56 |
| TAXIWAY A7  | TW A7     | 215        | BLEEDING             | N                 | Patching - AC Partial Depth  | 2,701.70      | SqFt      | \$3.00    | \$ 8,105.23 |
| TAXIWAY A7  | TW A7     | 215        | L & T CR             | L                 | Crack Sealing - AC           | 538.30        | Ft        | \$2.75    | \$ 1,480.37 |
| TAXIWAY A7  | TW A7     | 215        | L & T CR             | M                 | Crack Sealing - AC           | 507.80        | Ft        | \$2.75    | \$ 1,396.58 |
| TAXIWAY A7  | TW A7     | 215        | RAVELING             | L                 | Surface Seal                 | 3,605.70      | SqFt      | \$0.55    | \$ 1,983.16 |

| Branch Name   | Branch ID | Section ID | Distress Description | Distress Severity | Work Description            | Work Quantity | Work Unit | Unit Cost | Work Cost    |
|---------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY BRAVO | TW B      | 205        | BLEEDING             | N                 | Patching - AC Partial Depth | 339.30        | SqFt      | \$3.00    | \$ 1,017.92  |
| TAXIWAY BRAVO | TW B      | 205        | L & T CR             | L                 | Crack Sealing - AC          | 5,241.40      | Ft        | \$2.75    | \$ 14,413.86 |
| TAXIWAY BRAVO | TW B      | 205        | RAVELING             | L                 | Surface Seal                | 10,715.00     | SqFt      | \$0.55    | \$ 5,893.28  |
| TAXIWAY BRAVO | TW B      | 210        | L & T CR             | L                 | Crack Sealing - AC          | 2,133.80      | Ft        | \$2.75    | \$ 5,868.07  |
| TAXIWAY BRAVO | TW B      | 210        | RAVELING             | L                 | Surface Seal                | 2,598.70      | SqFt      | \$0.55    | \$ 1,429.31  |
| TAXIWAY BRAVO | TW B      | 217        | L & T CR             | L                 | Crack Sealing - AC          | 48.00         | Ft        | \$2.75    | \$ 132.00    |
| TAXIWAY BRAVO | TW B      | 217        | RAVELING             | M                 | Surface Seal                | 90.00         | SqFt      | \$0.55    | \$ 49.50     |
| TAXIWAY BRAVO | TW B      | 217        | RAVELING             | L                 | Surface Seal                | 550.00        | SqFt      | \$0.55    | \$ 302.50    |
| TAXIWAY BRAVO | TW B      | 217        | SWELLING             | M                 | Patching - AC Full Depth    | 39.10         | SqFt      | \$5.00    | \$ 195.38    |
| TAXIWAY BRAVO | TW B      | 220        | L & T CR             | L                 | Crack Sealing - AC          | 8,446.70      | Ft        | \$2.75    | \$ 23,228.38 |
| TAXIWAY BRAVO | TW B      | 220        | RAVELING             | L                 | Surface Seal                | 8,446.70      | SqFt      | \$0.55    | \$ 4,645.72  |
| TAXIWAY BRAVO | TW B      | 230        | L & T CR             | L                 | Crack Sealing - AC          | 416.80        | Ft        | \$2.75    | \$ 1,146.28  |
| TAXIWAY BRAVO | TW B      | 230        | RAVELING             | L                 | Surface Seal                | 3,675.70      | SqFt      | \$0.55    | \$ 2,021.64  |
| TAXIWAY B2    | TW B2     | 212        | L & T CR             | L                 | Crack Sealing - AC          | 394.70        | Ft        | \$2.75    | \$ 1,085.37  |
| TAXIWAY B2    | TW B2     | 212        | RAVELING             | L                 | Surface Seal                | 1,623.40      | SqFt      | \$0.55    | \$ 892.88    |
| TAXIWAY B2    | TW B2     | 213        | JT SEAL DMG          | L                 | Joint Seal - PCC            | 1,167.00      | Ft        | \$3.00    | \$ 3,500.89  |



# Pavement Evaluation Report - Pensacola International Airport

| Branch Name | Branch ID | Section ID | Distress Description | Distress Severity | Work Description             | Work Quantity | Work Unit | Unit Cost | Work Cost    |
|-------------|-----------|------------|----------------------|-------------------|------------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY B2  | TW B2     | 213        | SCALING              | L                 | Patching - PCC Partial Depth | 589.50        | SqFt      | \$19.10   | \$ 11,259.95 |
| TAXIWAY B2  | TW B2     | 213        | SHRINKAGE CR         | N                 | Crack Sealing - PCC          | 14.10         | Ft        | \$4.25    | \$ 60.13     |
| TAXIWAY B2  | TW B2     | 213        | JOINT SPALL          | L                 | Patching - PCC Partial Depth | 23.20         | SqFt      | \$19.10   | \$ 443.30    |
| TAXIWAY B2  | TW B2     | 240        | L & T CR             | L                 | Crack Sealing - AC           | 842.90        | Ft        | \$2.75    | \$ 2,317.87  |
| TAXIWAY B2  | TW B2     | 240        | RAVELING             | L                 | Surface Seal                 | 2,518.90      | SqFt      | \$0.55    | \$ 1,385.41  |
| TAXIWAY B3  | TW B3     | 255        | L & T CR             | L                 | Crack Sealing - AC           | 618.40        | Ft        | \$2.75    | \$ 1,700.70  |
| TAXIWAY B3  | TW B3     | 255        | RAVELING             | L                 | Surface Seal                 | 2,512.40      | SqFt      | \$0.55    | \$ 1,381.83  |
| TAXIWAY B3  | TW B4     | 260        | L & T CR             | L                 | Crack Sealing - AC           | 975.10        | Ft        | \$2.75    | \$ 2,681.39  |
| TAXIWAY B4  | TW B4     | 260        | RAVELING             | L                 | Surface Seal                 | 2,502.00      | SqFt      | \$0.55    | \$ 1,376.12  |
| TAXIWAY B4  | TW B5     | 265        | L & T CR             | L                 | Crack Sealing - AC           | 1,406.80      | Ft        | \$2.75    | \$ 3,868.70  |
| TAXIWAY B5  | TW B5     | 265        | RAVELING             | L                 | Surface Seal                 | 2,416.30      | SqFt      | \$0.55    | \$ 1,328.99  |
| TAXIWAY B7  | TW B7     | 270        | L & T CR             | L                 | Crack Sealing - AC           | 216.30        | Ft        | \$2.75    | \$ 594.94    |
| TAXIWAY B7  | TW B7     | 270        | PATCHING             | M                 | Patching - AC Full Depth     | 800.50        | SqFt      | \$5.00    | \$ 4,002.58  |
| TAXIWAY B7  | TW B7     | 270        | RAVELING             | L                 | Surface Seal                 | 745.50        | SqFt      | \$0.55    | \$ 410.01    |
| TAXIWAY B7  | TW B8     | 280        | PATCHING             | M                 | Patching - AC Full Depth     | 480.40        | SqFt      | \$5.00    | \$ 2,401.91  |
| TAXIWAY B8  | TW B8     | 280        | RAVELING             | L                 | Surface Seal                 | 647.20        | SqFt      | \$0.55    | \$ 355.98    |

| Branch Name     | Branch ID | Section ID | Distress Description | Distress Severity | Work Description            | Work Quantity | Work Unit | Unit Cost | Work Cost    |
|-----------------|-----------|------------|----------------------|-------------------|-----------------------------|---------------|-----------|-----------|--------------|
| TAXIWAY CHARLIE | TW C      | 250        | BLEEDING             | N                 | Patching - AC Partial Depth | 62.50         | SqFt      | \$3.00    | \$ 187.53    |
| TAXIWAY CHARLIE | TW C      | 250        | L & T CR             | L                 | Crack Sealing - AC          | 575.10        | Ft        | \$2.75    | \$ 1,581.54  |
| TAXIWAY CHARLIE | TW C      | 250        | RAVELING             | L                 | Surface Seal                | 1,681.60      | SqFt      | \$0.55    | \$ 924.87    |
| TAXIWAY CHARLIE | TW C      | 252        | L & T CR             | L                 | Crack Sealing - AC          | 968.50        | Ft        | \$2.75    | \$ 2,663.33  |
| TAXIWAY CHARLIE | TW C      | 252        | RAVELING             | L                 | Surface Seal                | 822.90        | SqFt      | \$0.55    | \$ 452.62    |
| TAXIWAY CHARLIE | TW C      | 505        | L & T CR             | L                 | Crack Sealing - AC          | 689.70        | Ft        | \$2.75    | \$ 1,896.80  |
| TAXIWAY CHARLIE | TW C      | 505        | RAVELING             | L                 | Surface Seal                | 1,313.80      | SqFt      | \$0.55    | \$ 722.60    |
| TAXIWAY CHARLIE | TW C      | 510        | L & T CR             | L                 | Crack Sealing - AC          | 2,181.70      | Ft        | \$2.75    | \$ 5,999.63  |
| TAXIWAY CHARLIE | TW C      | 510        | RAVELING             | L                 | Surface Seal                | 3,358.90      | SqFt      | \$0.55    | \$ 1,847.41  |
| TAXIWAY C2      | TW C2     | 515        | L & T CR             | L                 | Crack Sealing - AC          | 949.30        | Ft        | \$2.75    | \$ 2,610.54  |
| TAXIWAY C2      | TW C2     | 515        | RAVELING             | L                 | Surface Seal                | 1,582.10      | SqFt      | \$0.55    | \$ 870.19    |
| TAXIWAY DELTA   | TW D      | 140        | L & T CR             | L                 | Crack Sealing - AC          | 1,352.20      | Ft        | \$2.75    | \$ 3,718.60  |
| TAXIWAY DELTA   | TW D      | 140        | L & T CR             | M                 | Crack Sealing - AC          | 367.50        | Ft        | \$2.75    | \$ 1,010.63  |
| TAXIWAY DELTA   | TW D      | 140        | RAVELING             | L                 | Surface Seal                | 2,186.20      | SqFt      | \$0.55    | \$ 1,202.40  |
| TAXIWAY DELTA   | TW D      | 405        | DEPRESSION           | L                 | Patching - AC Full Depth    | 61.40         | SqFt      | \$5.00    | \$ 306.87    |
| TAXIWAY DELTA   | TW D      | 405        | L & T CR             | L                 | Crack Sealing - AC          | 4,029.10      | Ft        | \$2.75    | \$ 11,079.97 |



# Pavement Evaluation Report - Pensacola International Airport

| Branch Name   | Branch ID | Section ID | Distress Description | Distress Severity | Work Description         | Work Quantity | Work Unit | Unit Cost | Work Cost       |
|---------------|-----------|------------|----------------------|-------------------|--------------------------|---------------|-----------|-----------|-----------------|
| TAXIWAY DELTA | TW D      | 405        | RAVELING             | L                 | Surface Seal             | 5,937.60      | SqFt      | \$0.55    | \$ 3,265.71     |
| TAXIWAY DELTA | TW D      | 410        | L & T CR             | L                 | Crack Sealing - AC       | 1,021.70      | Ft        | \$2.75    | \$ 2,809.65     |
| TAXIWAY DELTA | TW D      | 410        | RAVELING             | L                 | Surface Seal             | 1,006.20      | SqFt      | \$0.55    | \$ 553.39       |
| TAXIWAY DELTA | TW D      | 430        | L & T CR             | L                 | Crack Sealing - AC       | 347.10        | Ft        | \$2.75    | \$ 954.40       |
| TAXIWAY DELTA | TW D      | 430        | RAVELING             | L                 | Surface Seal             | 1,527.90      | SqFt      | \$0.55    | \$ 840.35       |
| TAXIWAY D1    | TW D1     | 415        | L & T CR             | L                 | Crack Sealing - AC       | 168.90        | Ft        | \$2.75    | \$ 464.38       |
| TAXIWAY D1    | TW D1     | 415        | RAVELING             | L                 | Surface Seal             | 656.70        | SqFt      | \$0.55    | \$ 361.19       |
| TAXIWAY D2    | TW D2     | 420        | L & T CR             | L                 | Crack Sealing - AC       | 402.40        | Ft        | \$2.75    | \$ 1,106.59     |
| TAXIWAY D2    | TW D2     | 420        | RAVELING             | L                 | Surface Seal             | 657.00        | SqFt      | \$0.55    | \$ 361.34       |
| TAXIWAY D2    | TW D3     | 425        | DEPRESSION           | L                 | Patching - AC Full Depth | 63.50         | SqFt      | \$5.00    | \$ 317.74       |
| TAXIWAY D3    | TW D3     | 425        | RAVELING             | L                 | Surface Seal             | 711.00        | SqFt      | \$0.55    | \$ 391.05       |
| Total =       |           |            |                      |                   |                          |               |           |           | \$ 2,390,603.62 |



# APPENDIX F

---

- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION  
EXHIBIT
- AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION  
TABLE







|  |  |   |  |  |
|--|--|---|--|--|
| SECTION: 120<br>FY 2015<br>TW A1: 120<br>RECONSTRUCTION<br>\$1.09M       | SECTION: 4230<br>FY 2015<br>AP TERM: 4230<br>RECONSTRUCTION<br>\$0.55M   | SECTION: 4405<br>FY 2015<br>AP E: 4405<br>MILL AND OVERLAY<br>\$4.59M     | SECTION: 4510<br>FY 2015<br>AP S: 4510<br>MILL AND OVERLAY<br>\$6.09M    | SECTION: 270<br>FY 2016<br>TW B7: 270<br>MILL AND OVERLAY<br>\$0.28M     |
| SECTION: 215<br>FY 2017<br>TW A7: 215<br>MILL AND OVERLAY<br>\$1.38M     | SECTION: 4515<br>FY 2017<br>AP S: 4515<br>MILL AND OVERLAY<br>\$4.18M    | SECTION: 4505<br>FY 2019<br>AP S: 4505<br>MILL AND OVERLAY<br>\$2.28M     | SECTION: 4605<br>FY 2019<br>AP W: 4605<br>MILL AND OVERLAY<br>\$4.44M    | SECTION: 252<br>FY 2021<br>TW C: 252<br>MILL AND OVERLAY<br>\$0.35M      |
| SECTION: 6215<br>FY 2021<br>RW 8-26: 6215<br>MILL AND OVERLAY<br>\$2.04M | SECTION: 6235<br>FY 2021<br>RW 8-26: 6235<br>MILL AND OVERLAY<br>\$3.65M | SECTION: 6245<br>FY 2021<br>RW 8-26: 6245<br>MILL AND OVERLAY<br>\$0.86M  | SECTION: 115<br>FY 2022<br>TW A: 115<br>MILL AND OVERLAY<br>\$6.59M      | SECTION: 6225<br>FY 2022<br>RW 8-26: 6225<br>MILL AND OVERLAY<br>\$1.99M |
| SECTION: 6255<br>FY 2022<br>RW 8-26: 6255<br>MILL AND OVERLAY<br>\$1.33M | SECTION: 140<br>FY 2023<br>TW D: 140<br>MILL AND OVERLAY<br>\$1.00M      | SECTION: 160<br>FY 2023<br>TW A2: 160<br>MILL AND OVERLAY<br>\$0.85M      | SECTION: 217<br>FY 2023<br>TW B: 217<br>MILL AND OVERLAY<br>\$0.25M      | SECTION: 280<br>FY 2023<br>TW B8: 280<br>MILL AND OVERLAY<br>\$0.30M     |
| SECTION: 410<br>FY 2023<br>TW D: 410<br>MILL AND OVERLAY<br>\$0.46M      | SECTION: 505<br>FY 2023<br>TW C: 505<br>MILL AND OVERLAY<br>\$0.30M      | SECTION: 6115<br>FY 2023<br>RW 17-35: 6115<br>MILL AND OVERLAY<br>\$1.20M | SECTION: 6205<br>FY 2023<br>RW 8-26: 6205<br>MILL AND OVERLAY<br>\$2.96M | SECTION: 210<br>FY 2024<br>TW B: 210<br>MILL AND OVERLAY<br>\$1.22M      |
| SECTION: 6210<br>FY 2024<br>RW 8-26: 6210<br>MILL AND OVERLAY<br>\$1.53M | SECTION: 6220<br>FY 2024<br>RW 8-26: 6220<br>MILL AND OVERLAY<br>\$1.12M |   |  |  |

LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID

PROGRAM YEAR

|      |      |
|------|------|
| 2015 | 2020 |
| 2016 | 2021 |
| 2017 | 2022 |
| 2018 | 2023 |
| 2019 | 2024 |

"PROGRAM YEAR"  
"BRANCH": "SECTION"  
"REHAB ACTIVITY"  
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR  
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT  
MATCH PUBLISHED RUNWAY LENGTHS.

| NUMBER    | DATE | REVISIONS  |
|-----------|------|------------|
|           |      |            |
|           |      |            |
| DESIGNED: | KHA  | DRAWN: KHA |
| CHECKED:  | KHA  | DATE:      |
|           |      |            |



AIRFIELD PAVEMENT 10-YEAR MAJOR REHABILITATION EXHIBIT  
PENSACOLA INTERNATIONAL AIRPORT  
ESCAMBIA COUNTY, FLORIDA  
FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION AND SPACEPORT OFFICE



Table F-1: Airfield Pavement 10-Year Major Rehabilitation Table

| Year    | Branch ID | Section ID | Major M&R Costs* | PCI Before M&R | M&R Activity     | PCI After M&R |
|---------|-----------|------------|------------------|----------------|------------------|---------------|
| 2015    | AP E      | 4405       | \$ 4,594,320.00  | 62             | Mill and Overlay | 100           |
| 2015    | AP S      | 4510       | \$ 6,088,788.00  | 50             | Mill and Overlay | 100           |
| 2015    | AP TERM   | 4230       | \$ 546,503.00    | 8              | Reconstruction   | 100           |
| 2015    | TW A1     | 120        | \$ 1,090,177.00  | 37             | Reconstruction   | 100           |
| 2016    | TW B7     | 270        | \$ 276,227.00    | 64             | Mill and Overlay | 100           |
| 2017    | AP S      | 4515       | \$ 4,183,844.00  | 64             | Mill and Overlay | 100           |
| 2017    | TW A7     | 215        | \$ 1,377,982.00  | 64             | Mill and Overlay | 100           |
| 2019    | AP S      | 4505       | \$ 2,279,966.00  | 64             | Mill and Overlay | 100           |
| 2019    | AP W      | 4605       | \$ 4,444,292.00  | 64             | Mill and Overlay | 100           |
| 2021    | RW 8-26   | 6215       | \$ 2,041,830.00  | 64             | Mill and Overlay | 100           |
| 2021    | RW 8-26   | 6235       | \$ 3,653,800.00  | 64             | Mill and Overlay | 100           |
| 2021    | RW 8-26   | 6245       | \$ 859,718.00    | 65             | Mill and Overlay | 100           |
| 2021    | TW C      | 252        | \$ 353,580.00    | 65             | Mill and Overlay | 100           |
| 2022    | RW 8-26   | 6225       | \$ 1,992,329.00  | 65             | Mill and Overlay | 100           |
| 2022    | RW 8-26   | 6255       | \$ 1,328,264.00  | 65             | Mill and Overlay | 100           |
| 2022    | TW A      | 115        | \$ 6,594,631.00  | 64             | Mill and Overlay | 100           |
| 2023    | RW 17-35  | 6115       | \$ 1,197,098.00  | 64             | Mill and Overlay | 100           |
| 2023    | RW 8-26   | 6205       | \$ 2,964,242.00  | 64             | Mill and Overlay | 100           |
| 2023    | TW A2     | 160        | \$ 854,910.00    | 65             | Mill and Overlay | 100           |
| 2023    | TW B      | 217        | \$ 250,820.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW B8     | 280        | \$ 303,652.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW C      | 505        | \$ 299,571.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW D      | 140        | \$ 995,256.00    | 64             | Mill and Overlay | 100           |
| 2023    | TW D      | 410        | \$ 459,640.00    | 64             | Mill and Overlay | 100           |
| 2024    | RW 8-26   | 6210       | \$ 1,526,585.00  | 65             | Mill and Overlay | 100           |
| 2024    | RW 8-26   | 6220       | \$ 1,115,581.00  | 64             | Mill and Overlay | 100           |
| 2024    | TW B      | 210        | \$ 1,220,845.00  | 65             | Mill and Overlay | 100           |
| Total = |           |            | \$ 52,894,451.00 |                |                  |               |

\* Costs are adjusted for inflation AT 3%



# APPENDIX G

---

## ● PHOTOGRAPHS







Runway 17-35, Section 6125, Sample Unit 402 – Low Severity (66) Small Patching



Runway 17-35, Section 6105, Sample Unit 346 – Medium Severity (74) Joint Spalling





Runway 8-26, Section 6215, Sample Unit 330 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 8-26, Section 6255, Sample Unit 418 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering






Taxiway Alpha, Section 105, Sample Unit 115 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Taxiway A1, Section 120, Sample Unit 102 – Low Severity (41) Alligator Cracking, Low Severity (53) Rutting, Low Severity (57) Weathering






Taxiway Charlie, Section 250, Sample Unit 405 – (42) Bleeding, Low Severity (57) Weathering



Taxiway Delta, Section 410, Sample Unit 601 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering





Taxiway Charlie, Section 510, Sample Unit 517 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Apron South, Section 4510, Sample Unit 502 – Low Severity (43) Block Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling





Taxiway A7, Section 215, Sample Unit 400 – (42) Bleeding, Low Severity (57) Weathering



Terminal Apron, Section 4235, Sample Unit 936 – Low Severity (66) Small Patching, Low Severity (67) Large Patching





Terminal Apron, Section 4210, Sample Unit 803 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking



Terminal Apron, Section 4230, Sample Unit 101 – High Severity (41) Alligator Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling



# APPENDIX H

---

- DISTRESS DATA – RE-INSPECTION REPORT





Re-inspection Report

FDOT  
Report Generated Date: May 14, 2015

|                   |               |             |                                 |              |          |               |            |                |            |
|-------------------|---------------|-------------|---------------------------------|--------------|----------|---------------|------------|----------------|------------|
| Network:          | PNS           | Name:       | PENSACOLA INTERNATIONAL AIRPORT |              |          |               |            |                |            |
| Branch:           | AP CARGO      | Name:       | CARGO APRON                     |              | Use:     | APRON         | Area:      | 214,401.00SqFt |            |
| Section:          | 4705          | of          | 2                               | From:        | -        | To:           | -          | Last Const.:   | 01/01/2015 |
| Surface:          | PCC           | Family:     | FDOT-SAPMP-PR-AP-PCC            |              |          |               | Zone:      | Category:      | Rank: P    |
| Area:             | 68,880.00SqFt | Length:     | 350.00Ft                        | Width:       | 200.00Ft |               |            |                |            |
| Slabs:            | 175           | Slab Width: | 20.00Ft                         | Slab Length: | 20.00Ft  | Joint Length: | 6,450.00Ft |                |            |
| Shoulder:         | Street Type:  | Grade:      | 0.00                            | Lanes:       | 0        |               |            |                |            |
| Section Comments: |               |             |                                 |              |          |               |            |                |            |

|                  |                |   |           |   |
|------------------|----------------|---|-----------|---|
| Last Insp. Date: | Total Samples: | 0 | Surveyed: | 0 |
| Conditions:      |                |   |           |   |

|                        |       |       |      |
|------------------------|-------|-------|------|
| Sample Number:         | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> |       |       |      |

Re-inspection Report

FDOT  
Report Generated Date: May 14, 2015

|          |     |       |                                 |  |  |
|----------|-----|-------|---------------------------------|--|--|
| Network: | PNS | Name: | PENSACOLA INTERNATIONAL AIRPORT |  |  |
|----------|-----|-------|---------------------------------|--|--|

|         |          |       |             |      |       |       |                |
|---------|----------|-------|-------------|------|-------|-------|----------------|
| Branch: | AP CARGO | Name: | CARGO APRON | Use: | APRON | Area: | 214,401.00SqFt |
|---------|----------|-------|-------------|------|-------|-------|----------------|

|           |                |              |                      |              |          |               |             |              |            |
|-----------|----------------|--------------|----------------------|--------------|----------|---------------|-------------|--------------|------------|
| Section:  | 4710           | of           | 2                    | From:        | -        | To:           | -           | Last Const.: | 01/01/2015 |
| Surface:  | PCC            | Family:      | FDOT-SAPMP-PR-AP-PCC |              |          | Zone:         |             | Category:    | Rank: P    |
| Area:     | 145,521.00SqFt | Length:      | 500.00Ft             | Width:       | 250.00Ft |               |             |              |            |
| Slabs:    | 312            | Slab Width:  | 20.00Ft              | Slab Length: | 20.00Ft  | Joint Length: | 11,750.00Ft |              |            |
| Shoulder: |                | Street Type: | Grade:               | 0.00         | Lanes:   | 0             |             |              |            |

Section Comments:

|                  |                |   |           |   |
|------------------|----------------|---|-----------|---|
| Last Insp. Date: | Total Samples: | 0 | Surveyed: | 0 |
| Conditions:      |                |   |           |   |

|                        |       |       |      |
|------------------------|-------|-------|------|
| Sample Number:         | Type: | Area: | 0.00 |
| <NO VALID INSPECTIONS> |       |       |      |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP E Name: EAST APRON Use: APRON Area: 255,240.00SqFt

Section: 4405 of 1 From: - To: - Last Const.: 12/25/1999  
Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P  
Area: 255,240.00SqFt Length: 985.00Ft Width: 260.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 67 Surveyed: 7

Conditions: PCI : 63

Inspection Comments:

Sample Number: 108 Type: R Area: 3,825.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 225.00 Ft Comments:  
52 RAVELING L 3,825.00 SqFt Comments:

Sample Number: 200 Type: R Area: 3,825.00SqFt PCI = 55

Sample Comments:

43 BLOCK CRACKING L 1,620.00 SqFt Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING M 39.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 90.00 Ft Comments:  
56 SWELLING L 45.00 SqFt Comments:  
52 RAVELING L 3,825.00 SqFt Comments:

Sample Number: 203 Type: R Area: 3,825.00SqFt PCI = 63

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 255.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING M 85.00 Ft Comments:  
52 RAVELING L 3,825.00 SqFt Comments:

Sample Number: 311 Type: R Area: 4,500.00SqFt PCI = 62

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 345.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING M 101.00 Ft Comments:  
52 RAVELING L 4,500.00 SqFt Comments:

Sample Number: 405 Type: R Area: 3,825.00SqFt PCI = 62

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 255.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING M 98.00 Ft Comments:  
52 RAVELING L 3,825.00 SqFt Comments:

Sample Number: 501 Type: R Area: 3,825.00SqFt PCI = 64

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 74.00 Ft Comments:  
43 BLOCK CRACKING L 680.00 SqFt Comments:  
52 RAVELING L 3,825.00 SqFt Comments:

Sample Number: 607 Type: R Area: 2,975.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 138.00 Ft Comments:  
52 RAVELING L 2,975.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP GA Name: GA APRON Use: APRON Area: 86,169.00SqFt

Section: 4310 of 4 From: - To: - Last Const.: 01/01/2015

Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 26,365.00SqFt Length: 210.00Ft Width: 150.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

**NOTE: \*\*\* Pre-Construction PCI \*\*\***

Last Insp. Date: 04/18/2011 Total Samples: 10 Surveyed: 2

Conditions: PCI : 66

Inspection Comments:

Sample Number: 650 Type: R Area: 1,856.00SqFt PCI = 52

Sample Comments:

47 JOINT REFLECTION CRACKING H 72.02 Ft Comments:

52 RAVELING H 12.00 SqFt Comments:

50 PATCHING L 0.25 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 49.01 Ft Comments:

Sample Number: 750 Type: R Area: 5,093.00SqFt PCI = 71

Sample Comments:

47 JOINT REFLECTION CRACKING L 115.03 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 468.12 Ft Comments:

56 SWELLING L 13.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP GA Name: GA APRON Use: APRON Area: 86,169.00SqFt

Section: 4315 of 4 From: - To: - Last Const.: 01/01/2015  
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P  
Area: 9,900.00SqFt Length: 110.00Ft Width: 90.00Ft  
Slabs: 16 Slab Width: 25.00Ft Slab Length: 25.00Ft Joint Length: 592.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

**NOTE: \*\*\* Pre-Construction PCI \*\*\***

Last Insp. Date: 04/18/2011 Total Samples: 1 Surveyed: 1

Conditions: PCI : 78

Inspection Comments:

Sample Number: 100 Type: R Area: 16.00Slabs PCI = 78

Sample Comments:

|                      |   |             |           |
|----------------------|---|-------------|-----------|
| 70 SCALING/CRAZING   | L | 16.00 Slabs | Comments: |
| 65 JOINT SEAL DAMAGE | L | 16.00 Slabs | Comments: |
| 74 JOINT SPALLING    | L | 1.00 Slabs  | Comments: |
| 63 LINEAR CRACKING   | M | 1.00 Slabs  | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP GA Name: GA APRON Use: APRON Area: 86,169.00SqFt

Section: 4320 of 4 From: - To: - Last Const.: 01/01/2015

Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 12,201.00SqFt Length: 275.00Ft Width: 78.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

**NOTE: \*\*\* Pre-Construction PCI \*\*\***

Last Insp. Date: 04/18/2011 Total Samples: 6 Surveyed: 1

Conditions: PCI : 59

Inspection Comments:

Sample Number: 502 Type: R Area: 3,900.00SqFt PCI = 59

Sample Comments:

52 RAVELING L 3,899.97 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 25.01 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 73.02 Ft Comments:

56 SWELLING L 16.00 SqFt Comments:

49 OIL SPILLAGE N 32.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP GA Name: GA APRON Use: APRON Area: 86,169.00SqFt

Section: 4325 of 4 From: - To: - Last Const.: 01/01/2015

Surface: AAC Family: FDOT-SAPMP-PR-AP-AAC Zone: Category: Rank: P

Area: 37,703.00SqFt Length: 475.00Ft Width: 200.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

**NOTE: \*\*\* Pre-Construction PCI \*\*\***

Last Insp. Date: 04/18/2011 Total Samples: 23 Surveyed: 3

Conditions: PCI : 22

Inspection Comments:

Sample Number: 303 Type: R Area: 5,000.00SqFt PCI = 23

Sample Comments:

|                                     |   |               |           |
|-------------------------------------|---|---------------|-----------|
| 52 RAVELING                         | M | 4,888.96 SqFt | Comments: |
| 52 RAVELING                         | H | 111.00 SqFt   | Comments: |
| 50 PATCHING                         | L | 7.00 SqFt     | Comments: |
| 50 PATCHING                         | M | 3.00 SqFt     | Comments: |
| 56 SWELLING                         | L | 49.00 SqFt    | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 150.04 Ft     | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 11.00 Ft      | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 16.00 Ft      | Comments: |

Sample Number: 355 Type: R Area: 5,000.00SqFt PCI = 20

Sample Comments:

|                                     |   |               |           |
|-------------------------------------|---|---------------|-----------|
| 50 PATCHING                         | L | 575.00 SqFt   | Comments: |
| 52 RAVELING                         | H | 360.00 SqFt   | Comments: |
| 52 RAVELING                         | M | 4,064.97 SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 71.02 Ft      | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 88.02 Ft      | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 65.02 Ft      | Comments: |

Sample Number: 454 Type: R Area: 5,000.00SqFt PCI = 21

Sample Comments:

|                                     |   |               |           |
|-------------------------------------|---|---------------|-----------|
| 52 RAVELING                         | M | 2,384.98 SqFt | Comments: |
| 52 RAVELING                         | H | 325.00 SqFt   | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 94.02 Ft      | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 74.02 Ft      | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 118.03 Ft     | Comments: |
| 50 PATCHING                         | L | 2,289.98 SqFt | Comments: |
| 56 SWELLING                         | L | 68.00 SqFt    | Comments: |



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP S Name: SOUTH APRON Use: APRON Area: 669,899.00SqFt

Section: 4505 of 3 From: To: Last Const.: 01/01/1997  
Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: T  
Area: 112,540.00SqFt Length: 1,680.00Ft Width: 70.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 26 Surveyed: 3

Conditions: PCI : 71

Inspection Comments:

Sample Number: 100 Type: R Area: 4,969.00SqFt PCI = 67

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 227.00 Ft Comments:  
52 RAVELING L 2,485.00 SqFt Comments:  
57 WEATHERING L 2,484.00 SqFt Comments:  
50 PATCHING L 30.00 SqFt Comments:

Sample Number: 203 Type: R Area: 4,000.00SqFt PCI = 69

Sample Comments:

49 OIL SPILLAGE N 10.00 SqFt Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 85.00 Ft Comments:  
52 RAVELING L 745.00 SqFt Comments:  
57 WEATHERING L 2,980.00 SqFt Comments:  
50 PATCHING L 275.00 SqFt Comments:

Sample Number: 401 Type: R Area: 4,075.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 116.00 Ft Comments:  
52 RAVELING L 815.00 SqFt Comments:  
57 WEATHERING L 3,260.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP S Name: SOUTH APRON Use: APRON Area: 669,899.00SqFt

Section: 4510 of 3 From: To: Last Const.: 01/01/1997  
Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: T  
Area: 338,266.00SqFt Length: 3,230.00Ft Width: 105.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 72 Surveyed: 8

Conditions: PCI : 51

Inspection Comments:

Sample Number: 105 Type: R Area: 5,400.00SqFt PCI = 61

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 12.00 Ft Comments:  
52 RAVELING M 1,080.00 SqFt Comments:  
52 RAVELING L 4,320.00 SqFt Comments:  
49 OIL SPILLAGE N 8.00 SqFt Comments:

Sample Number: 204 Type: R Area: 3,250.00SqFt PCI = 41

Sample Comments:

43 BLOCK CRACKING L 3,200.00 SqFt Comments:  
52 RAVELING L 2,600.00 SqFt Comments:  
52 RAVELING M 650.00 SqFt Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 100.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 36.00 Ft Comments:

Sample Number: 211 Type: R Area: 3,250.00SqFt PCI = 52

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 367.00 Ft Comments:  
52 RAVELING L 2,600.00 SqFt Comments:  
52 RAVELING M 650.00 SqFt Comments:

Sample Number: 300 Type: R Area: 5,000.00SqFt PCI = 57

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 325.00 Ft Comments:  
52 RAVELING L 4,000.00 SqFt Comments:  
52 RAVELING M 1,000.00 SqFt Comments:

Sample Number: 311 Type: R Area: 5,000.00SqFt PCI = 47

Sample Comments:

52 RAVELING L 4,000.00 SqFt Comments:  
52 RAVELING M 1,000.00 SqFt Comments:  
43 BLOCK CRACKING L 2,000.00 SqFt Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 239.00 Ft Comments:

Sample Number: 408 Type: R Area: 5,350.00SqFt PCI = 60

Sample Comments:

52 RAVELING L 4,280.00 SqFt Comments:  
52 RAVELING M 1,070.00 SqFt Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 213.00 Ft Comments:

Sample Number: 502 Type: R Area: 5,350.00SqFt PCI = 43

Sample Comments:

43 BLOCK CRACKING L 3,000.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 52 | RAVELING                         | L | 3,000.00 | SqFt | Comments: |
| 52 | RAVELING                         | M | 1,280.00 | SqFt | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 50.00    | Ft   | Comments: |
| 52 | RAVELING                         | L | 720.00   | SqFt | Comments: |
| 43 | BLOCK CRACKING                   | L | 720.00   | SqFt | Comments: |

Sample Number: 514      Type: R      Area: 5,350.00SqFt      PCI = 44

Sample Comments:

|    |                |   |          |      |           |
|----|----------------|---|----------|------|-----------|
| 43 | BLOCK CRACKING | L | 5,350.00 | SqFt | Comments: |
| 52 | RAVELING       | L | 4,280.00 | SqFt | Comments: |
| 52 | RAVELING       | M | 1,070.00 | SqFt | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP S Name: SOUTH APRON Use: APRON Area: 669,899.00SqFt

Section: 4515 of 3 From: To: Last Const.: 01/01/1997  
Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: T  
Area: 219,093.00SqFt Length: 935.00Ft Width: 230.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 37 Surveyed: 4

Conditions: PCI : 68

Inspection Comments:

Sample Number: 104 Type: R Area: 6,400.00SqFt PCI = 62

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 149.00   | Ft   | Comments: |
| 52 | RAVELING                         | M | 1,280.00 | SqFt | Comments: |
| 45 | DEPRESSION                       | L | 12.00    | SqFt | Comments: |
| 45 | DEPRESSION                       | L | 33.00    | SqFt | Comments: |
| 45 | DEPRESSION                       | L | 8.00     | SqFt | Comments: |
| 45 | DEPRESSION                       | L | 4.00     | SqFt | Comments: |

Sample Number: 201 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 175.00   | Ft   | Comments: |
| 56 | SWELLING                         | L | 10.00    | SqFt | Comments: |
| 49 | OIL SPILLAGE                     | N | 4.00     | SqFt | Comments: |
| 52 | RAVELING                         | L | 1,000.00 | SqFt | Comments: |
| 57 | WEATHERING                       | L | 4,000.00 | SqFt | Comments: |

Sample Number: 404 Type: R Area: 4,685.00SqFt PCI = 67

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 381.00   | Ft   | Comments: |
| 52 | RAVELING                         | L | 2,811.00 | SqFt | Comments: |
| 57 | WEATHERING                       | L | 1,874.00 | SqFt | Comments: |
| 56 | SWELLING                         | L | 30.00    | SqFt | Comments: |

Sample Number: 501 Type: R Area: 3,500.00SqFt PCI = 71

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 135.00   | Ft   | Comments: |
| 52 | RAVELING                         | L | 700.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 2,800.00 | SqFt | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 32.00    | Ft   | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 999,635.00SqFt

Section: 4205 of 7 From: - To: - Last Const.: 01/01/1988  
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: T  
Area: 367,057.00SqFt Length: 800.00Ft Width: 600.00Ft  
Slabs: 3,119 Slab Width: 12.50Ft Slab Length: 12.50Ft Joint Length: 75,400.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 122 Surveyed: 10

Conditions: PCI : 94

Inspection Comments:

Sample Number: 159 Type: R Area: 20.00Slabs PCI = 75

Sample Comments:

70 SCALING/CRAZING L 8.00 Slabs Comments:  
70 SCALING/CRAZING M 4.00 Slabs Comments:  
67 LARGE PATCH/UTILITY M 1.00 Slabs Comments:

Sample Number: 176 Type: R Area: 20.00Slabs PCI = 97

Sample Comments:

73 SHRINKAGE CRACKING N 1.00 Slabs Comments:  
70 SCALING/CRAZING L 2.00 Slabs Comments:

Sample Number: 211 Type: R Area: 20.00Slabs PCI = 100

Sample Comments:

<NO DISTRESSES>

Sample Number: 229 Type: R Area: 20.00Slabs PCI = 93

Sample Comments:

70 SCALING/CRAZING L 9.00 Slabs Comments:  
73 SHRINKAGE CRACKING N 2.00 Slabs Comments:  
74 JOINT SPALLING L 1.00 Slabs Comments:

Sample Number: 234 Type: R Area: 20.00Slabs PCI = 87

Sample Comments:

70 SCALING/CRAZING L 15.00 Slabs Comments:  
71 FAULTING L 2.00 Slabs Comments:

Sample Number: 250 Type: R Area: 20.00Slabs PCI = 97

Sample Comments:

70 SCALING/CRAZING L 2.00 Slabs Comments:  
73 SHRINKAGE CRACKING N 1.00 Slabs Comments:

Sample Number: 325 Type: R Area: 20.00Slabs PCI = 95

Sample Comments:

70 SCALING/CRAZING L 3.00 Slabs Comments:  
73 SHRINKAGE CRACKING N 2.00 Slabs Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:

Sample Number: 340 Type: R Area: 30.00Slabs PCI = 99

Sample Comments:

66 SMALL PATCH L 1.00 Slabs Comments:

Re-inspection Report

FDOT  
Report Generated Date: May 14, 2015

|                    |     |       |   |       |            |           |
|--------------------|-----|-------|---|-------|------------|-----------|
| Sample Number:     | 362 | Type: | R | Area: | 20.00Slabs | PCI = 99  |
| Sample Comments:   |     |       |   |       |            |           |
| 70 SCALING/CRAZING |     |       |   | L     | 1.00 Slabs | Comments: |
| Sample Number:     | 606 | Type: | R | Area: | 20.00Slabs | PCI = 100 |
| Sample Comments:   |     |       |   |       |            |           |
| <NO DISTRESSES>    |     |       |   |       |            |           |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 999,635.00SqFt

Section: 4210 of 7 From: - To: - Last Const.: 01/01/1977  
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P  
Area: 256,288.00SqFt Length: 600.00Ft Width: 500.00Ft  
Slabs: 1,315 Slab Width: 16.67Ft Slab Length: 12.50Ft Joint Length: 40,896.40Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 69 Surveyed: 7

Conditions: PCI : 91

Inspection Comments:

Sample Number: 803 Type: R Area: 20.00Slabs PCI = 90

Sample Comments:

|    |                    |   |      |       |           |
|----|--------------------|---|------|-------|-----------|
| 63 | LINEAR CRACKING    | L | 1.00 | Slabs | Comments: |
| 73 | SHRINKAGE CRACKING | N | 3.00 | Slabs | Comments: |
| 70 | SCALING/CRAZING    | L | 1.00 | Slabs | Comments: |
| 74 | JOINT SPALLING     | L | 1.00 | Slabs | Comments: |

Sample Number: 808 Type: R Area: 15.00Slabs PCI = 90

Sample Comments:

|    |                     |   |      |       |           |
|----|---------------------|---|------|-------|-----------|
| 70 | SCALING/CRAZING     | L | 1.00 | Slabs | Comments: |
| 73 | SHRINKAGE CRACKING  | N | 2.00 | Slabs | Comments: |
| 66 | SMALL PATCH         | L | 2.00 | Slabs | Comments: |
| 67 | LARGE PATCH/UTILITY | L | 1.00 | Slabs | Comments: |

Sample Number: 854 Type: R Area: 20.00Slabs PCI = 93

Sample Comments:

|    |                    |   |      |       |           |
|----|--------------------|---|------|-------|-----------|
| 70 | SCALING/CRAZING    | L | 7.00 | Slabs | Comments: |
| 73 | SHRINKAGE CRACKING | N | 4.00 | Slabs | Comments: |
| 66 | SMALL PATCH        | L | 1.00 | Slabs | Comments: |

Sample Number: 859 Type: R Area: 20.00Slabs PCI = 95

Sample Comments:

|    |                 |   |      |       |           |
|----|-----------------|---|------|-------|-----------|
| 66 | SMALL PATCH     | L | 3.00 | Slabs | Comments: |
| 70 | SCALING/CRAZING | L | 3.00 | Slabs | Comments: |

Sample Number: 877 Type: R Area: 20.00Slabs PCI = 91

Sample Comments:

|    |                    |   |      |       |           |
|----|--------------------|---|------|-------|-----------|
| 74 | JOINT SPALLING     | L | 2.00 | Slabs | Comments: |
| 73 | SHRINKAGE CRACKING | N | 7.00 | Slabs | Comments: |
| 70 | SCALING/CRAZING    | L | 1.00 | Slabs | Comments: |

Sample Number: 906 Type: R Area: 20.00Slabs PCI = 91

Sample Comments:

|    |                     |   |      |       |           |
|----|---------------------|---|------|-------|-----------|
| 67 | LARGE PATCH/UTILITY | L | 2.00 | Slabs | Comments: |
| 66 | SMALL PATCH         | L | 1.00 | Slabs | Comments: |
| 75 | CORNER SPALLING     | L | 1.00 | Slabs | Comments: |

Sample Number: 933 Type: R Area: 20.00Slabs PCI = 89

Sample Comments:

|    |                     |   |      |       |           |
|----|---------------------|---|------|-------|-----------|
| 66 | SMALL PATCH         | L | 1.00 | Slabs | Comments: |
| 67 | LARGE PATCH/UTILITY | L | 3.00 | Slabs | Comments: |
| 74 | JOINT SPALLING      | L | 1.00 | Slabs | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 999,635.00SqFt

Section: 4215 of 7 From: - To: - Last Const.: 01/01/2010

Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P

Area: 42,079.00SqFt Length: 700.00Ft Width: 70.00Ft

Slabs: 122 Slab Width: 20.00Ft Slab Length: 20.00Ft Joint Length: 4,130.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 6 Surveyed: 1

Conditions: PCI : 97

Inspection Comments:

Sample Number: 102 Type: R Area: 18.00Slabs PCI = 97

Sample Comments:

74 JOINT SPALLING L 2.00 Slabs Comments:



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 999,635.00SqFt

Section: 4220 of 7 From: - To: - Last Const.: 01/01/2010  
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P  
Area: 76,245.00SqFt Length: 300.00Ft Width: 300.00Ft  
Slabs: 488 Slab Width: 12.50Ft Slab Length: 12.50Ft Joint Length: 13,800.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 29 Surveyed: 3

Conditions: PCI : 100

Inspection Comments:

Sample Number: 174 Type: R Area: 16.00Slabs PCI = 100

Sample Comments:

<NO DISTRESSES>

Sample Number: 221 Type: R Area: 20.00Slabs PCI = 99

Sample Comments:

73 SHRINKAGE CRACKING N 1.00 Slabs Comments:

Sample Number: 272 Type: R Area: 15.00Slabs PCI = 100

Sample Comments:

<NO DISTRESSES>

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 999,635.00SqFt

Section: 4225 of 7 From: - To: - Last Const.: 01/01/2010  
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P  
Area: 106,612.00SqFt Length: 710.00Ft Width: 150.00Ft  
Slabs: 286 Slab Width: 20.00Ft Slab Length: 18.67Ft Joint Length: 10,169.34Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 18 Surveyed: 3

Conditions: PCI : 97

Inspection Comments:

Sample Number: 103 Type: R Area: 24.00Slabs PCI = 97  
Sample Comments:  
70 SCALING/CRAZING L 7.00 Slabs Comments:

Sample Number: 300 Type: R Area: 24.00Slabs PCI = 98  
Sample Comments:  
70 SCALING/CRAZING L 5.00 Slabs Comments:

Sample Number: 499 Type: R Area: 19.00Slabs PCI = 95  
Sample Comments:  
74 JOINT SPALLING L 1.00 Slabs Comments:  
70 SCALING/CRAZING L 6.00 Slabs Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 999,635.00SqFt

Section: 4230 of 7 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P

Area: 23,761.00SqFt Length: 230.00Ft Width: 92.50Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 5 Surveyed: 1

Conditions: PCI : 9

Inspection Comments:

Sample Number: 101 Type: R Area: 5,550.00SqFt PCI = 9

Sample Comments:

|                                     |   |          |      |           |
|-------------------------------------|---|----------|------|-----------|
| 50 PATCHING                         | M | 340.00   | SqFt | Comments: |
| 50 PATCHING                         | M | 208.00   | SqFt | Comments: |
| 50 PATCHING                         | M | 108.00   | SqFt | Comments: |
| 45 DEPRESSION                       | L | 4.00     | SqFt | Comments: |
| 49 OIL SPILLAGE                     | N | 25.00    | SqFt | Comments: |
| 43 BLOCK CRACKING                   | L | 450.00   | SqFt | Comments: |
| 41 ALLIGATOR CRACKING               | L | 144.00   | SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 146.00   | Ft   | Comments: |
| 41 ALLIGATOR CRACKING               | H | 150.00   | SqFt | Comments: |
| 53 RUTTING                          | M | 150.00   | SqFt | Comments: |
| 41 ALLIGATOR CRACKING               | M | 195.00   | SqFt | Comments: |
| 43 BLOCK CRACKING                   | M | 750.00   | SqFt | Comments: |
| 50 PATCHING                         | H | 30.00    | SqFt | Comments: |
| 52 RAVELING                         | M | 3,891.00 | SqFt | Comments: |
| 52 RAVELING                         | L | 973.00   | SqFt | Comments: |
| 45 DEPRESSION                       | L | 9.00     | SqFt | Comments: |
| 49 OIL SPILLAGE                     | N | 144.00   | SqFt | Comments: |
| 41 ALLIGATOR CRACKING               | L | 144.00   | SqFt | Comments: |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 82.00    | Ft   | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP TERM Name: TERMINAL APRON Use: APRON Area: 999,635.00SqFt

Section: 4235 of 7 From: - To: - Last Const.: 12/25/1998  
Surface: PCC Family: FDOT-SAPMP-PR-AP-PCC Zone: Category: Rank: P  
Area: 127,593.00SqFt Length: 1,000.00Ft Width: 130.00Ft  
Slabs: 208 Slab Width: 25.00Ft Slab Length: 25.00Ft Joint Length: 9,270.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 37 Surveyed: 4

Conditions: PCI : 91

Inspection Comments:

Sample Number: 425 Type: R Area: 24.00Slabs PCI = 94

Sample Comments:

70 SCALING/CRAZING L 13.00 Slabs Comments:  
73 SHRINKAGE CRACKING N 3.00 Slabs Comments:

Sample Number: 559 Type: R Area: 20.00Slabs PCI = 97

Sample Comments:

70 SCALING/CRAZING L 10.00 Slabs Comments:

Sample Number: 927 Type: R Area: 21.00Slabs PCI = 94

Sample Comments:

66 SMALL PATCH L 5.00 Slabs Comments:  
70 SCALING/CRAZING L 6.00 Slabs Comments:

Sample Number: 936 Type: R Area: 20.00Slabs PCI = 77

Sample Comments:

67 LARGE PATCH/UTILITY L 9.00 Slabs Comments:  
70 SCALING/CRAZING L 5.00 Slabs Comments:  
66 SMALL PATCH L 4.00 Slabs Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: AP W Name: APRON WEST Use: APRON Area: 219,372.00SqFt

Section: 4605 of 1 From: - To: - Last Const.: 01/01/2002  
Surface: AC Family: FDOT-SAPMP-PR-AP-AC Zone: Category: Rank: P  
Area: 219,372.00SqFt Length: 710.00Ft Width: 310.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 42 Surveyed: 5

Conditions: PCI : 71

Inspection Comments:

Sample Number: 100 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 2.00 Ft Comments:  
49 OIL SPILLAGE N 9.00 SqFt Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 109 Type: R Area: 5,000.00SqFt PCI = 66

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 53.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,356.00 SqFt Comments:  
49 OIL SPILLAGE N 9.00 SqFt Comments:  
50 PATCHING L 144.00 SqFt Comments:

Sample Number: 205 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 302 Type: R Area: 5,500.00SqFt PCI = 74

Sample Comments:

52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,676.00 SqFt Comments:  
50 PATCHING L 324.00 SqFt Comments:

Sample Number: 312 Type: R Area: 5,500.00SqFt PCI = 64

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING M 24.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 6.00 Ft Comments:  
49 OIL SPILLAGE N 16.00 SqFt Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,838.00 SqFt Comments:  
50 PATCHING L 162.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 17-35 Name: RUNWAY 17-35 Use: RUNWAY Area: 750,750.00SqFt

Section: 6105 of 6 From: - To: - Last Const.: 11/01/2007  
Surface: PCC Family: FDOT-SAPMP-PR-RW-TW-PCC Zone: Category: Rank: P  
Area: 33,178.00SqFt Length: 2,960.00Ft Width: 112.50Ft  
Slabs: 890 Slab Width: 18.72Ft Slab Length: 20.00Ft Joint Length: 31,365.96Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 49 Surveyed: 12

Conditions: PCI : 91

Inspection Comments:

Sample Number: 301 Type: R Area: 18.00Slabs PCI = 91

Sample Comments:

65 JOINT SEAL DAMAGE L 18.00 Slabs Comments:  
74 JOINT SPALLING L 4.00 Slabs Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:

Sample Number: 307 Type: R Area: 18.00Slabs PCI = 95

Sample Comments:

73 SHRINKAGE CRACKING N 1.00 Slabs Comments:  
74 JOINT SPALLING L 2.00 Slabs Comments:

Sample Number: 313 Type: R Area: 18.00Slabs PCI = 97

Sample Comments:

74 JOINT SPALLING L 2.00 Slabs Comments:

Sample Number: 316 Type: R Area: 18.00Slabs PCI = 95

Sample Comments:

74 JOINT SPALLING L 3.00 Slabs Comments:

Sample Number: 319 Type: R Area: 18.00Slabs PCI = 95

Sample Comments:

74 JOINT SPALLING L 3.00 Slabs Comments:

Sample Number: 321 Type: R Area: 18.00Slabs PCI = 88

Sample Comments:

74 JOINT SPALLING L 7.00 Slabs Comments:  
75 CORNER SPALLING L 1.00 Slabs Comments:

Sample Number: 325 Type: R Area: 18.00Slabs PCI = 89

Sample Comments:

73 SHRINKAGE CRACKING N 2.00 Slabs Comments:  
74 JOINT SPALLING L 6.00 Slabs Comments:

Sample Number: 328 Type: R Area: 18.00Slabs PCI = 92

Sample Comments:

74 JOINT SPALLING L 5.00 Slabs Comments:

Sample Number: 332 Type: R Area: 18.00Slabs PCI = 88

Sample Comments:

65 JOINT SEAL DAMAGE L 18.00 Slabs Comments:  
74 JOINT SPALLING L 8.00 Slabs Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

---

|                  |                |       |   |       |            |           |
|------------------|----------------|-------|---|-------|------------|-----------|
| Sample Number:   | 338            | Type: | R | Area: | 18.00Slabs | PCI = 90  |
| Sample Comments: |                |       |   |       |            |           |
| 74               | JOINT SPALLING |       |   | L     | 7.00 Slabs | Comments: |

---

|                  |                 |       |   |       |            |           |
|------------------|-----------------|-------|---|-------|------------|-----------|
| Sample Number:   | 342             | Type: | R | Area: | 18.00Slabs | PCI = 90  |
| Sample Comments: |                 |       |   |       |            |           |
| 75               | CORNER SPALLING |       |   | L     | 1.00 Slabs | Comments: |
| 74               | JOINT SPALLING  |       |   | L     | 5.00 Slabs | Comments: |

---

|                  |                |       |   |       |            |           |
|------------------|----------------|-------|---|-------|------------|-----------|
| Sample Number:   | 346            | Type: | R | Area: | 18.00Slabs | PCI = 85  |
| Sample Comments: |                |       |   |       |            |           |
| 74               | JOINT SPALLING |       |   | M     | 1.00 Slabs | Comments: |
| 74               | JOINT SPALLING |       |   | L     | 8.00 Slabs | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 17-35 Name: RUNWAY 17-35 Use: RUNWAY Area: 750,750.00SqFt

Section: 6110 of 6 From: - To: - Last Const.: 11/01/2007  
Surface: PCC Family: FDOT-SAPMP-PR-RW-TW-PCC Zone: Category: Rank: P  
Area: 110,822.00SqFt Length: 2,960.00Ft Width: 38.00Ft  
Slabs: 296 Slab Width: 18.72Ft Slab Length: 20.00Ft Joint Length: 8,634.55Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 24 Surveyed: 7

Conditions: PCI : 93

Inspection Comments:

Sample Number: 104 Type: R Area: 12.00Slabs PCI = 95

Sample Comments:

65 JOINT SEAL DAMAGE L 12.00 Slabs Comments:

74 JOINT SPALLING L 1.00 Slabs Comments:

Sample Number: 120 Type: R Area: 12.00Slabs PCI = 89

Sample Comments:

75 CORNER SPALLING L 3.00 Slabs Comments:

74 JOINT SPALLING L 1.00 Slabs Comments:

Sample Number: 128 Type: R Area: 12.00Slabs PCI = 97

Sample Comments:

74 JOINT SPALLING L 1.00 Slabs Comments:

Sample Number: 140 Type: R Area: 12.00Slabs PCI = 95

Sample Comments:

74 JOINT SPALLING L 2.00 Slabs Comments:

Sample Number: 512 Type: R Area: 12.00Slabs PCI = 91

Sample Comments:

74 JOINT SPALLING L 3.00 Slabs Comments:

73 SHRINKAGE CRACKING N 1.00 Slabs Comments:

Sample Number: 520 Type: R Area: 12.00Slabs PCI = 97

Sample Comments:

74 JOINT SPALLING L 1.00 Slabs Comments:

Sample Number: 544 Type: R Area: 16.00Slabs PCI = 89

Sample Comments:

74 JOINT SPALLING L 5.00 Slabs Comments:

75 CORNER SPALLING L 1.00 Slabs Comments:



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 17-35 Name: RUNWAY 17-35 Use: RUNWAY Area: 750,750.00SqFt

Section: 6115 of 6 From: - To: - Last Const.: 11/01/2007  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 52,500.00SqFt Length: 525.00Ft Width: 100.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 11 Surveyed: 3

Conditions: PCI : 75

Inspection Comments:

Sample Number: 350 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 18.00 Ft Comments:  
52 RAVELING L 2,000.00 SqFt Comments:  
57 WEATHERING L 3,000.00 SqFt Comments:

Sample Number: 353 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 87.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 357 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 17-35 Name: RUNWAY 17-35 Use: RUNWAY Area: 750,750.00SqFt

Section: 6120 of 6 From: - To: - Last Const.: 11/01/2007  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 26,250.00SqFt Length: 525.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 6 Surveyed: 2

Conditions: PCI : 78

Inspection Comments:

Sample Number: 150 Type: R Area: 5,000.00SqFt PCI = 76

Sample Comments:

|    |                                  |   |               |           |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 12.00 Ft      | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 30.00 Ft      | Comments: |
| 52 | RAVELING                         | L | 500.00 SqFt   | Comments: |
| 57 | WEATHERING                       | L | 4,500.00 SqFt | Comments: |

Sample Number: 554 Type: R Area: 5,000.00SqFt PCI = 80

Sample Comments:

|    |                                  |   |               |           |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 109.00 Ft     | Comments: |
| 52 | RAVELING                         | L | 500.00 SqFt   | Comments: |
| 57 | WEATHERING                       | L | 4,500.00 SqFt | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 17-35 Name: RUNWAY 17-35 Use: RUNWAY Area: 750,750.00SqFt

Section: 6125 of 6 From: - To: - Last Const.: 11/01/2007  
Surface: PCC Family: FDOT-SAPMP-PR-RW-TW-PCC Zone: Category: Rank: P  
Area: 396,211.00SqFt Length: 3,520.00Ft Width: 112.50Ft  
Slabs: 1,058 Slab Width: 18.72Ft Slab Length: 20.00Ft Joint Length: 37,321.35Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 59 Surveyed: 15

Conditions: PCI : 92

Inspection Comments:

Sample Number: 367 Type: R Area: 18.00Slabs PCI = 93

Sample Comments:

73 SHRINKAGE CRACKING N 1.00 Slabs Comments:  
74 JOINT SPALLING L 3.00 Slabs Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:

Sample Number: 370 Type: R Area: 18.00Slabs PCI = 94

Sample Comments:

74 JOINT SPALLING L 4.00 Slabs Comments:

Sample Number: 374 Type: R Area: 18.00Slabs PCI = 95

Sample Comments:

66 SMALL PATCH L 1.00 Slabs Comments:  
74 JOINT SPALLING L 2.00 Slabs Comments:

Sample Number: 377 Type: R Area: 18.00Slabs PCI = 93

Sample Comments:

73 SHRINKAGE CRACKING N 2.00 Slabs Comments:  
74 JOINT SPALLING L 3.00 Slabs Comments:

Sample Number: 380 Type: R Area: 18.00Slabs PCI = 91

Sample Comments:

74 JOINT SPALLING L 5.00 Slabs Comments:  
73 SHRINKAGE CRACKING N 1.00 Slabs Comments:

Sample Number: 384 Type: R Area: 18.00Slabs PCI = 92

Sample Comments:

73 SHRINKAGE CRACKING N 2.00 Slabs Comments:  
74 JOINT SPALLING L 4.00 Slabs Comments:

Sample Number: 388 Type: R Area: 18.00Slabs PCI = 85

Sample Comments:

73 SHRINKAGE CRACKING N 3.00 Slabs Comments:  
66 SMALL PATCH L 4.00 Slabs Comments:  
74 JOINT SPALLING L 6.00 Slabs Comments:

Sample Number: 394 Type: R Area: 18.00Slabs PCI = 91

Sample Comments:

74 JOINT SPALLING L 5.00 Slabs Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

---

|                  |                    |       |   |       |            |           |
|------------------|--------------------|-------|---|-------|------------|-----------|
| Sample Number:   | 398                | Type: | R | Area: | 18.00Slabs | PCI = 84  |
| Sample Comments: |                    |       |   |       |            |           |
| 73               | SHRINKAGE CRACKING |       |   | N     | 1.00 Slabs | Comments: |
| 74               | JOINT SPALLING     |       |   | L     | 7.00 Slabs | Comments: |
| 75               | CORNER SPALLING    |       |   | L     | 1.00 Slabs | Comments: |
| 66               | SMALL PATCH        |       |   | L     | 3.00 Slabs | Comments: |

---

|                  |                    |       |   |       |            |           |
|------------------|--------------------|-------|---|-------|------------|-----------|
| Sample Number:   | 402                | Type: | R | Area: | 18.00Slabs | PCI = 86  |
| Sample Comments: |                    |       |   |       |            |           |
| 66               | SMALL PATCH        |       |   | L     | 2.00 Slabs | Comments: |
| 73               | SHRINKAGE CRACKING |       |   | N     | 1.00 Slabs | Comments: |
| 74               | JOINT SPALLING     |       |   | L     | 9.00 Slabs | Comments: |

---

|                  |                    |       |   |       |            |           |
|------------------|--------------------|-------|---|-------|------------|-----------|
| Sample Number:   | 407                | Type: | R | Area: | 18.00Slabs | PCI = 94  |
| Sample Comments: |                    |       |   |       |            |           |
| 74               | JOINT SPALLING     |       |   | L     | 3.00 Slabs | Comments: |
| 73               | SHRINKAGE CRACKING |       |   | N     | 1.00 Slabs | Comments: |

---

|                  |                    |       |   |       |            |           |
|------------------|--------------------|-------|---|-------|------------|-----------|
| Sample Number:   | 412                | Type: | R | Area: | 18.00Slabs | PCI = 99  |
| Sample Comments: |                    |       |   |       |            |           |
| 73               | SHRINKAGE CRACKING |       |   | N     | 1.00 Slabs | Comments: |

---

|                  |                |       |   |       |            |           |
|------------------|----------------|-------|---|-------|------------|-----------|
| Sample Number:   | 416            | Type: | R | Area: | 18.00Slabs | PCI = 96  |
| Sample Comments: |                |       |   |       |            |           |
| 66               | SMALL PATCH    |       |   | L     | 2.00 Slabs | Comments: |
| 74               | JOINT SPALLING |       |   | L     | 1.00 Slabs | Comments: |

---

|                  |             |       |   |       |            |           |
|------------------|-------------|-------|---|-------|------------|-----------|
| Sample Number:   | 421         | Type: | R | Area: | 18.00Slabs | PCI = 99  |
| Sample Comments: |             |       |   |       |            |           |
| 66               | SMALL PATCH |       |   | L     | 1.00 Slabs | Comments: |

---

|                  |                |       |   |       |            |           |
|------------------|----------------|-------|---|-------|------------|-----------|
| Sample Number:   | 423            | Type: | R | Area: | 18.00Slabs | PCI = 85  |
| Sample Comments: |                |       |   |       |            |           |
| 66               | SMALL PATCH    |       |   | L     | 5.00 Slabs | Comments: |
| 74               | JOINT SPALLING |       |   | L     | 9.00 Slabs | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 17-35 Name: RUNWAY 17-35 Use: RUNWAY Area: 750,750.00SqFt

Section: 6130 of 6 From: - To: - Last Const.: 11/01/2007  
Surface: PCC Family: FDOT-SAPMP-PR-RW-TW-PCC Zone: Category: Rank: P  
Area: 131,789.00SqFt Length: 3,520.00Ft Width: 38.00Ft  
Slabs: 352 Slab Width: 18.72Ft Slab Length: 20.00Ft Joint Length: 10,275.30Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 30 Surveyed: 9

Conditions: PCI : 91

Inspection Comments:

Sample Number: 180 Type: R Area: 12.00Slabs PCI = 95  
Sample Comments:  
74 JOINT SPALLING L 2.00 Slabs Comments:

Sample Number: 196 Type: R Area: 12.00Slabs PCI = 86  
Sample Comments:  
74 JOINT SPALLING L 7.00 Slabs Comments:  
70 SCALING/CRAZING L 1.00 Slabs Comments:

Sample Number: 208 Type: R Area: 12.00Slabs PCI = 97  
Sample Comments:  
73 SHRINKAGE CRACKING N 1.00 Slabs Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:

Sample Number: 564 Type: R Area: 6.00Slabs PCI = 92  
Sample Comments:  
73 SHRINKAGE CRACKING N 1.00 Slabs Comments:  
74 JOINT SPALLING L 1.00 Slabs Comments:

Sample Number: 572 Type: R Area: 12.00Slabs PCI = 89  
Sample Comments:  
66 SMALL PATCH L 2.00 Slabs Comments:  
74 JOINT SPALLING L 4.00 Slabs Comments:

Sample Number: 580 Type: R Area: 12.00Slabs PCI = 91  
Sample Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:  
73 SHRINKAGE CRACKING N 2.00 Slabs Comments:  
74 JOINT SPALLING L 2.00 Slabs Comments:

Sample Number: 588 Type: R Area: 12.00Slabs PCI = 92  
Sample Comments:  
66 SMALL PATCH L 1.00 Slabs Comments:  
74 JOINT SPALLING L 3.00 Slabs Comments:

Sample Number: 600 Type: R Area: 12.00Slabs PCI = 84  
Sample Comments:  
66 SMALL PATCH L 3.00 Slabs Comments:  
73 SHRINKAGE CRACKING N 1.00 Slabs Comments:  
74 JOINT SPALLING L 6.00 Slabs Comments:

# Re-inspection Report

FDOT  
Report Generated Date: May 14, 2015

---

|                  |                |       |   |       |       |       |           |
|------------------|----------------|-------|---|-------|-------|-------|-----------|
| Sample Number:   | 620            | Type: | R | Area: | 14.00 | Slabs | PCI = 94  |
| Sample Comments: |                |       |   |       |       |       |           |
| 66               | SMALL PATCH    |       |   | L     | 4.00  | Slabs | Comments: |
| 74               | JOINT SPALLING |       |   | L     | 1.00  | Slabs | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6205 of 14 From: - To: - Last Const.: 01/01/2004

Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P

Area: 130,000.00SqFt Length: 1,300.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 26 Surveyed: 5

Conditions: PCI : 75

Inspection Comments:

Sample Number: 301 Type: R Area: 5,000.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 201.00 Ft Comments:

52 RAVELING L 500.00 SqFt Comments:

57 WEATHERING L 4,500.00 SqFt Comments:

Sample Number: 304 Type: R Area: 5,000.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 261.00 Ft Comments:

52 RAVELING L 1,000.00 SqFt Comments:

57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 313 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 181.00 Ft Comments:

52 RAVELING L 1,500.00 SqFt Comments:

57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 317 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 248.00 Ft Comments:

52 RAVELING L 1,500.00 SqFt Comments:

57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 323 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 271.00 Ft Comments:

52 RAVELING L 1,500.00 SqFt Comments:

57 WEATHERING L 3,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6210 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 65,000.00SqFt Length: 1,300.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 14 Surveyed: 3

Conditions: PCI : 77

Inspection Comments:

Sample Number: 104 Type: R Area: 5,000.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 150.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 120 Type: R Area: 5,000.00SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 343.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 516 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 71.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 99.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6215 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 95,000.00SqFt Length: 950.00Ft Width: 100.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 19 Surveyed: 5

Conditions: PCI : 72

Inspection Comments:

Sample Number: 327 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 284.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 330 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 140.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 129.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 356 Type: R Area: 5,000.00SqFt PCI = 67

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 188.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 300.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 360 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 283.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 364 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 264.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6220 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 47,500.00SqFt Length: 950.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 12 Surveyed: 3

Conditions: PCI : 76

Inspection Comments:

Sample Number: 128 Type: R Area: 5,000.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 228.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 156 Type: R Area: 6,250.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 238.00 Ft Comments:  
52 RAVELING L 313.00 SqFt Comments:  
57 WEATHERING L 5,937.00 SqFt Comments:

Sample Number: 560 Type: R Area: 5,000.00SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 336.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6225 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 89,997.00SqFt Length: 900.00Ft Width: 100.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 18 Surveyed: 5

Conditions: PCI : 74

Inspection Comments:

Sample Number: 336 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 221.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 339 Type: R Area: 5,000.00SqFt PCI = 71

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 189.00 Ft Comments:  
52 RAVELING L 2,000.00 SqFt Comments:  
57 WEATHERING L 3,000.00 SqFt Comments:

Sample Number: 342 Type: R Area: 5,000.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 159.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:  
41 ALLIGATOR CRACKING L 7.00 SqFt Comments:

Sample Number: 348 Type: R Area: 5,000.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 5.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 354 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6230 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 44,999.00SqFt Length: 900.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 12 Surveyed: 3

Conditions: PCI : 83

Inspection Comments:

Sample Number: 144 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 75.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 536 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 52.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 544 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 75.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6235 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 170,000.00SqFt Length: 1,700.00Ft Width: 100.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 34 Surveyed: 7

Conditions: PCI : 72

Inspection Comments:

Sample Number: 366 Type: R Area: 5,000.00SqFt PCI = 74  
Sample Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 271.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 370 Type: R Area: 5,000.00SqFt PCI = 73  
Sample Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 293.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 376 Type: R Area: 5,000.00SqFt PCI = 74  
Sample Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 276.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 381 Type: R Area: 5,000.00SqFt PCI = 71  
Sample Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 250.00 Ft Comments:  
52 RAVELING L 2,000.00 SqFt Comments:  
57 WEATHERING L 3,000.00 SqFt Comments:

Sample Number: 386 Type: R Area: 5,000.00SqFt PCI = 70  
Sample Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 264.00 Ft Comments:  
52 RAVELING L 2,500.00 SqFt Comments:  
57 WEATHERING L 2,500.00 SqFt Comments:

Sample Number: 392 Type: R Area: 5,000.00SqFt PCI = 71  
Sample Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 299.00 Ft Comments:  
52 RAVELING L 2,000.00 SqFt Comments:  
57 WEATHERING L 3,000.00 SqFt Comments:

Sample Number: 397 Type: R Area: 5,000.00SqFt PCI = 69  
Sample Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 416.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6240 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 85,000.00SqFt Length: 1,700.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 18 Surveyed: 5

Conditions: PCI : 79

Inspection Comments:

Sample Number: 168 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 79.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 180 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 71.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 188 Type: R Area: 5,000.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 133.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 576 Type: R Area: 5,000.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 225.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 3,750.00 SqFt Comments:

Sample Number: 596 Type: R Area: 5,000.00SqFt PCI = 71

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 356.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6245 of 14 From: - To: - Last Const.: 01/01/2004

Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P

Area: 40,000.00SqFt Length: 400.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 8 Surveyed: 2

Conditions: PCI : 73

Inspection Comments:

Sample Number: 401 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 280.00 Ft Comments:

52 RAVELING L 1,500.00 SqFt Comments:

57 WEATHERING L 3,500.00 SqFt Comments:

Sample Number: 407 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 318.00 Ft Comments:

52 RAVELING L 1,500.00 SqFt Comments:

57 WEATHERING L 3,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6250 of 14 From: - To: - Last Const.: 01/01/2004

Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P

Area: 20,000.00SqFt Length: 400.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 204 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 100.00 Ft Comments:

52 RAVELING L 250.00 SqFt Comments:

57 WEATHERING L 4,750.00 SqFt Comments:



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6255 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 60,000.00SqFt Length: 600.00Ft Width: 100.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 12 Surveyed: 3

Conditions: PCI : 74

Inspection Comments:

Sample Number: 409 Type: R Area: 5,000.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 266.00 Ft Comments:  
52 RAVELING L 1,000.00 SqFt Comments:  
57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 413 Type: R Area: 5,000.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 314.00 Ft Comments:  
52 RAVELING L 1,000.00 SqFt Comments:  
57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 418 Type: R Area: 5,000.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 121.00 Ft Comments:  
48 LONGITUDINAL/TRANSVERSE CRACKING L 150.00 Ft Comments:  
52 RAVELING L 1,500.00 SqFt Comments:  
57 WEATHERING L 3,500.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6260 of 14 From: - To: - Last Const.: 01/01/2004  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 30,000.00SqFt Length: 600.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 6 Surveyed: 2

Conditions: PCI : 79

Inspection Comments:

Sample Number: 212 Type: R Area: 5,000.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 150.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 608 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 174.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6265 of 14 From: To: Last Const.: 01/01/2006  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 100,100.00SqFt Length: 1,001.00Ft Width: 100.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 20 Surveyed: 5

Conditions: PCI : 80

Inspection Comments:

Sample Number: 423 Type: R Area: 5,000.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 46.00 Ft Comments:  
52 RAVELING L 1,000.00 SqFt Comments:  
57 WEATHERING L 4,000.00 SqFt Comments:

Sample Number: 426 Type: R Area: 5,000.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 71.00 Ft Comments:  
52 RAVELING L 500.00 SqFt Comments:  
57 WEATHERING L 4,500.00 SqFt Comments:

Sample Number: 428 Type: R Area: 5,000.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 173.00 Ft Comments:  
52 RAVELING L 500.00 SqFt Comments:  
57 WEATHERING L 4,500.00 SqFt Comments:

Sample Number: 432 Type: R Area: 5,000.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 71.00 Ft Comments:  
52 RAVELING L 500.00 SqFt Comments:  
57 WEATHERING L 4,500.00 SqFt Comments:

Sample Number: 437 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 91.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: RW 8-26 Name: RUNWAY 8-26 Use: RUNWAY Area: 1,027,646.00SqFt

Section: 6270 of 14 From: To: Last Const.: 01/01/2006  
Surface: AC Family: FDOT-SAPMP-PR-RW-AC Zone: Category: Rank: P  
Area: 50,050.00SqFt Length: 1,001.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 10 Surveyed: 2

Conditions: PCI : 84

Inspection Comments:

Sample Number: 232 Type: R Area: 5,000.00SqFt PCI = 85

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 14.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

Sample Number: 624 Type: R Area: 5,000.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 54.00 Ft Comments:  
52 RAVELING L 250.00 SqFt Comments:  
57 WEATHERING L 4,750.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 583,905.00SqFt

Section: 105 of 2 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 286,014.00SqFt Length: 3,620.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 73 Surveyed: 8

Conditions: PCI : 79

Inspection Comments:

Sample Number: 106 Type: R Area: 3,750.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 95.00 Ft Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 115 Type: R Area: 3,750.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 174.00 Ft Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 124 Type: R Area: 3,750.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 130.00 Ft Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 133 Type: R Area: 3,750.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 106.00 Ft Comments:

52 RAVELING L 563.00 SqFt Comments:

57 WEATHERING L 3,187.00 SqFt Comments:

Sample Number: 142 Type: R Area: 3,750.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 58.00 Ft Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 151 Type: R Area: 3,750.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 197.00 Ft Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 160 Type: R Area: 3,750.00SqFt PCI = 72

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 108.00 Ft Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 140.00 Ft Comments:

52 RAVELING L 188.00 SqFt Comments:

57 WEATHERING L 3,562.00 SqFt Comments:

Re-inspection Report

FDOT  
Report Generated Date: May 14, 2015

|                  |                                  |       |   |       |               |           |
|------------------|----------------------------------|-------|---|-------|---------------|-----------|
| Sample Number:   | 603                              | Type: | R | Area: | 5,200.00SqFt  | PCI = 83  |
| Sample Comments: |                                  |       |   |       |               |           |
| 48               | LONGITUDINAL/TRANSVERSE CRACKING |       |   | L     | 46.00 Ft      | Comments: |
| 52               | RAVELING                         |       |   | L     | 260.00 SqFt   | Comments: |
| 57               | WEATHERING                       |       |   | L     | 4,940.00 SqFt | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A Name: TAXIWAY A Use: TAXIWAY Area: 583,905.00SqFt

Section: 115 of 2 From: - To: - Last Const.: 02/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 297,891.00SqFt Length: 3,690.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 74 Surveyed: 8

Conditions: PCI : 74

Inspection Comments:

Sample Number: 103 Type: R Area: 5,150.00SqFt PCI = 74

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 228.00   | Ft   | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 50.00    | Ft   | Comments: |
| 52 | RAVELING                         | L | 258.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 4,892.00 | SqFt | Comments: |

Sample Number: 113 Type: R Area: 4,461.00SqFt PCI = 64

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 246.00   | Ft   | Comments: |
| 52 | RAVELING                         | L | 223.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 4,238.00 | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING               | L | 18.00    | SqFt | Comments: |
| 53 | RUTTING                          | L | 18.00    | SqFt | Comments: |

Sample Number: 123 Type: R Area: 3,750.00SqFt PCI = 80

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 113.00   | Ft   | Comments: |
| 52 | RAVELING                         | L | 188.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 3,562.00 | SqFt | Comments: |

Sample Number: 133 Type: R Area: 3,750.00SqFt PCI = 75

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 118.00   | Ft   | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 78.00    | Ft   | Comments: |
| 52 | RAVELING                         | L | 188.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 3,562.00 | SqFt | Comments: |

Sample Number: 143 Type: R Area: 3,750.00SqFt PCI = 76

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 177.00   | Ft   | Comments: |
| 52 | RAVELING                         | L | 188.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 3,562.00 | SqFt | Comments: |

Sample Number: 153 Type: R Area: 3,750.00SqFt PCI = 72

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 240.00   | Ft   | Comments: |
| 52 | RAVELING                         | L | 188.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 3,562.00 | SqFt | Comments: |

Sample Number: 163 Type: R Area: 3,750.00SqFt PCI = 75

Sample Comments:

|    |                                  |   |        |    |           |
|----|----------------------------------|---|--------|----|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 136.00 | Ft | Comments: |
|----|----------------------------------|---|--------|----|-----------|

Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

|    |                         |          |   |          |      |           |
|----|-------------------------|----------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE | CRACKING | L | 50.00    | Ft   | Comments: |
| 52 | RAVELING                |          | L | 188.00   | SqFt | Comments: |
| 57 | WEATHERING              |          | L | 3,562.00 | SqFt | Comments: |

Sample Number: 172      Type: R      Area: 3,750.00SqFt      PCI = 74

Sample Comments:

|    |                         |          |   |          |      |           |
|----|-------------------------|----------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE | CRACKING | L | 202.00   | Ft   | Comments: |
| 52 | RAVELING                |          | L | 188.00   | SqFt | Comments: |
| 57 | WEATHERING              |          | L | 3,562.00 | SqFt | Comments: |



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A1 Name: TAXIWAY A1 Use: TAXIWAY Area: 47,399.00SqFt

Section: 120 of 1 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 47,399.00SqFt Length: 375.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 9 Surveyed: 1

Conditions: PCI : 37

Inspection Comments:

Sample Number: 102 Type: R Area: 5,307.00SqFt PCI = 37

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 53.00    | Ft   | Comments: |
| 41 | ALLIGATOR CRACKING               | L | 18.00    | SqFt | Comments: |
| 41 | ALLIGATOR CRACKING               | M | 105.00   | SqFt | Comments: |
| 53 | RUTTING                          | L | 105.00   | SqFt | Comments: |
| 52 | RAVELING                         | L | 531.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 4,776.00 | SqFt | Comments: |
| 49 | OIL SPILLAGE                     | N | 6.00     | SqFt | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A2 Name: TAXIWAY A2 Use: TAXIWAY Area: 92,824.00SqFt

Section: 150 of 2 From: - To: - Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 55,331.00SqFt Length: 375.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 11 Surveyed: 2

Conditions: PCI : 82

Inspection Comments:

Sample Number: 203 Type: R Area: 5,202.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 35.00 Ft Comments:

52 RAVELING L 260.00 SqFt Comments:

57 WEATHERING L 4,942.00 SqFt Comments:

Sample Number: 207 Type: R Area: 5,889.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 177.00 Ft Comments:

52 RAVELING L 294.00 SqFt Comments:

57 WEATHERING L 5,595.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A2 Name: TAXIWAY A2 Use: TAXIWAY Area: 92,824.00SqFt

Section: 160 of 2 From: To: Last Const.: 01/01/2000

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 37,493.00SqFt Length: 340.00Ft Width: 100.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 7 Surveyed: 1

Conditions: PCI : 76

Inspection Comments:

Sample Number: 203 Type: R Area: 5,000.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 132.00 Ft Comments:

52 RAVELING L 1,000.00 SqFt Comments:

57 WEATHERING L 4,000.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A3 Name: TAXIWAY A3 Use: TAXIWAY Area: 50,051.00SqFt

Section: 170 of 1 From: - To: - Last Const.: 01/01/2006

Surface: PCC Family: FDOT-SAPMP-PR-RW-TW-PCC Zone: Category: Rank: T

Area: 50,051.00SqFt Length: 375.00Ft Width: 103.00Ft

Slabs: 133 Slab Width: 18.75Ft Slab Length: 20.00Ft Joint Length: 3,513.25Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 8 Surveyed: 1

Conditions: PCI : 94

Inspection Comments:

Sample Number: 103 Type: R Area: 18.00Slabs PCI = 94

Sample Comments:

74 JOINT SPALLING L 4.00 Slabs Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A4 Name: TAXIWAY A4 Use: TAXIWAY Area: 49,968.00SqFt

Section: 130 of 1 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 49,968.00SqFt Length: 375.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 10 Surveyed: 1

Conditions: PCI : 84

Inspection Comments:

Sample Number: 404 Type: R Area: 5,200.00SqFt PCI = 84

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 20.00 Ft Comments:

52 RAVELING L 260.00 SqFt Comments:

57 WEATHERING L 4,940.00 SqFt Comments:

42 BLEEDING N 2.00 SqFt Comments:

42 BLEEDING N 3.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A5 Name: TAXIWAY A5 Use: TAXIWAY Area: 49,806.00SqFt

Section: 125 of 1 From: - To: - Last Const.: 01/01/2001

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 49,806.00SqFt Length: 375.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 10 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 502 Type: R Area: 5,829.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 6.00 Ft Comments:

52 RAVELING L 291.00 SqFt Comments:

57 WEATHERING L 5,538.00 SqFt Comments:

45 DEPRESSION L 27.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW A7 Name: TAXIWAY A7 Use: TAXIWAY Area: 72,160.00SqFt

Section: 215 of 1 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 72,160.00SqFt Length: 310.00Ft Width: 230.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 17 Surveyed: 3

Conditions: PCI : 67

Inspection Comments:

Sample Number: 400 Type: R Area: 3,748.00SqFt PCI = 62

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 100.00   | Ft   | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 62.00    | Ft   | Comments: |
| 52 | RAVELING                         | L | 187.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 3,561.00 | SqFt | Comments: |
| 42 | BLEEDING                         | N | 72.00    | SqFt | Comments: |
| 42 | BLEEDING                         | N | 54.00    | SqFt | Comments: |

Sample Number: 402 Type: R Area: 5,461.00SqFt PCI = 86

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 8.00     | Ft   | Comments: |
| 52 | RAVELING                         | L | 273.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 5,188.00 | SqFt | Comments: |

Sample Number: 601 Type: R Area: 5,000.00SqFt PCI = 52

Sample Comments:

|    |                                  |   |          |      |           |
|----|----------------------------------|---|----------|------|-----------|
| 42 | BLEEDING                         | N | 202.00   | SqFt | Comments: |
| 42 | BLEEDING                         | N | 126.00   | SqFt | Comments: |
| 42 | BLEEDING                         | N | 78.00    | SqFt | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 36.00    | Ft   | Comments: |
| 52 | RAVELING                         | L | 250.00   | SqFt | Comments: |
| 57 | WEATHERING                       | L | 4,750.00 | SqFt | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 658,132.00SqFt

Section: 205 of 5 From: - To: - Last Const.: 01/01/2002  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 213,853.00SqFt Length: 2,485.00Ft Width: 75.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 52 Surveyed: 6

Conditions: PCI : 80

Inspection Comments:

Sample Number: 205 Type: R Area: 3,750.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 44.00 Ft Comments:  
42 BLEEDING N 6.00 SqFt Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 211 Type: R Area: 3,750.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 12.00 Ft Comments:  
42 BLEEDING N 32.00 SqFt Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 217 Type: R Area: 3,750.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 131.00 Ft Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 223 Type: R Area: 3,750.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 162.00 Ft Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 232 Type: R Area: 3,750.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 131.00 Ft Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 602 Type: R Area: 5,200.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 107.00 Ft Comments:  
52 RAVELING L 260.00 SqFt Comments:  
57 WEATHERING L 4,940.00 SqFt Comments:



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 658,132.00SqFt

Section: 210 of 5 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 51,982.00SqFt Length: 347.00Ft Width: 132.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 9 Surveyed: 1

Conditions: PCI : 77

Inspection Comments:

Sample Number: 105 Type: R Area: 6,821.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 280.00 Ft Comments:

52 RAVELING L 341.00 SqFt Comments:

57 WEATHERING L 6,480.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 658,132.00SqFt

Section: 217 of 5 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 11,000.00SqFt Length: 400.00Ft Width: 27.50Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 2 Surveyed: 1

Conditions: PCI : 75

Inspection Comments:

Sample Number: 307 Type: R Area: 5,500.00SqFt PCI = 75

Sample Comments:

56 SWELLING M 9.00 SqFt Comments:

52 RAVELING M 45.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 24.00 Ft Comments:

52 RAVELING L 275.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 658,132.00SqFt

Section: 220 of 5 From: - To: - Last Const.: 01/01/2002  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 256,627.00SqFt Length: 3,367.00Ft Width: 75.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 68 Surveyed: 7

Conditions: PCI : 80

Inspection Comments:

Sample Number: 110 Type: R Area: 3,750.00SqFt PCI = 78

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 146.00 Ft Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 119 Type: R Area: 3,750.00SqFt PCI = 74

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 238.00 Ft Comments:  
52 RAVELING L 75.00 SqFt Comments:  
57 WEATHERING L 3,675.00 SqFt Comments:

Sample Number: 128 Type: R Area: 3,750.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 97.00 Ft Comments:  
52 RAVELING L 75.00 SqFt Comments:  
57 WEATHERING L 3,675.00 SqFt Comments:

Sample Number: 137 Type: R Area: 3,750.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 72.00 Ft Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

Sample Number: 146 Type: R Area: 3,750.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 105.00 Ft Comments:  
52 RAVELING L 75.00 SqFt Comments:  
57 WEATHERING L 3,675.00 SqFt Comments:

Sample Number: 155 Type: R Area: 3,750.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 103.00 Ft Comments:  
52 RAVELING L 75.00 SqFt Comments:  
57 WEATHERING L 3,675.00 SqFt Comments:

Sample Number: 164 Type: R Area: 3,750.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 103.00 Ft Comments:  
52 RAVELING L 188.00 SqFt Comments:  
57 WEATHERING L 3,562.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B Name: TAXIWAY B Use: TAXIWAY Area: 658,132.00SqFt

Section: 230 of 5 From: - To: - Last Const.: 01/01/2005  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 124,670.00SqFt Length: 1,450.00Ft Width: 75.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 29 Surveyed: 4

Conditions: PCI : 88

Inspection Comments:

Sample Number: 105 Type: R Area: 5,200.00SqFt PCI = 86

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 5.00 Ft Comments:  
52 RAVELING L 260.00 SqFt Comments:  
57 WEATHERING L 4,940.00 SqFt Comments:

Sample Number: 174 Type: R Area: 3,750.00SqFt PCI = 90

Sample Comments:

52 RAVELING L 75.00 SqFt Comments:  
57 WEATHERING L 3,675.00 SqFt Comments:

Sample Number: 180 Type: R Area: 3,750.00SqFt PCI = 90

Sample Comments:

52 RAVELING L 75.00 SqFt Comments:  
57 WEATHERING L 3,675.00 SqFt Comments:

Sample Number: 186 Type: R Area: 3,750.00SqFt PCI = 85

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 50.00 Ft Comments:  
52 RAVELING L 75.00 SqFt Comments:  
57 WEATHERING L 3,675.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B2 Name: TAXIWAY B2 Use: TAXIWAY Area: 93,664.00SqFt

Section: 212 of 3 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 32,535.00SqFt Length: 200.00Ft Width: 150.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 8 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 510 Type: R Area: 4,369.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 53.00 Ft Comments:

52 RAVELING L 218.00 SqFt Comments:

57 WEATHERING L 4,151.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B2 Name: TAXIWAY B2 Use: TAXIWAY Area: 93,664.00SqFt

Section: 213 of 3 From: - To: - Last Const.: 01/01/1988  
Surface: PCC Family: FDOT-SAPMP-PR-RW-TW-PCC Zone: Category: Rank: P  
Area: 10,751.00SqFt Length: 112.50Ft Width: 75.00Ft  
Slabs: 69 Slab Width: 12.50Ft Slab Length: 12.50Ft Joint Length: 1,162.50Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 91

Inspection Comments:

Sample Number: 301 Type: R Area: 24.00Slabs PCI = 91

Sample Comments:

|                       |   |             |           |
|-----------------------|---|-------------|-----------|
| 70 SCALING/CRAZING    | L | 4.00 Slabs  | Comments: |
| 74 JOINT SPALLING     | L | 3.00 Slabs  | Comments: |
| 73 SHRINKAGE CRACKING | N | 1.00 Slabs  | Comments: |
| 65 JOINT SEAL DAMAGE  | L | 24.00 Slabs | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B2 Name: TAXIWAY B2 Use: TAXIWAY Area: 93,664.00SqFt

Section: 240 of 3 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 50,378.00SqFt Length: 375.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 10 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 502 Type: R Area: 5,200.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 87.00 Ft Comments:

52 RAVELING L 260.00 SqFt Comments:

57 WEATHERING L 4,940.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B3 Name: TAXIWAY B3 Use: TAXIWAY Area: 50,248.00SqFt

Section: 255 of 1 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 50,248.00SqFt Length: 375.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 10 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 302 Type: R Area: 5,200.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 64.00 Ft Comments:

52 RAVELING L 260.00 SqFt Comments:

57 WEATHERING L 4,940.00 SqFt Comments:



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B4 Name: TAXIWAY B4 Use: TAXIWAY Area: 50,114.00SqFt

Section: 260 of 1 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 50,114.00SqFt Length: 375.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 10 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 206 Type: R Area: 5,448.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 106.00 Ft Comments:

52 RAVELING L 272.00 SqFt Comments:

57 WEATHERING L 5,176.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B5 Name: TAXIWAY B5 Use: TAXIWAY Area: 48,322.00SqFt

Section: 265 of 1 From: To: Last Const.: 01/01/2002  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 48,322.00SqFt Length: 375.00Ft Width: 104.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 10 Surveyed: 2

Conditions: PCI : 80

Inspection Comments:

Sample Number: 103 Type: R Area: 5,200.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 81.00 Ft Comments:  
52 RAVELING L 260.00 SqFt Comments:  
57 WEATHERING L 4,940.00 SqFt Comments:

Sample Number: 106 Type: R Area: 5,139.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 220.00 Ft Comments:  
52 RAVELING L 257.00 SqFt Comments:  
57 WEATHERING L 4,882.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B7 Name: TAXIWAY B7 Use: TAXIWAY Area: 14,899.00SqFt

Section: 270 of 1 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 14,899.00SqFt Length: 228.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 66

Inspection Comments:

Sample Number: 101 Type: R Area: 5,716.00SqFt PCI = 66

Sample Comments:

|    |                                  |   |               |           |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 83.00 Ft      | Comments: |
| 52 | RAVELING                         | L | 286.00 SqFt   | Comments: |
| 50 | PATCHING                         | M | 265.00 SqFt   | Comments: |
| 57 | WEATHERING                       | L | 5,165.00 SqFt | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW B8 Name: TAXIWAY B8 Use: TAXIWAY Area: 13,317.00SqFt

Section: 280 of 1 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 13,317.00SqFt Length: 228.00Ft Width: 50.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 75

Inspection Comments:

Sample Number: 101 Type: R Area: 5,041.00SqFt PCI = 75

Sample Comments:

50 PATCHING M 150.00 SqFt Comments:

52 RAVELING L 245.00 SqFt Comments:

57 WEATHERING L 4,646.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 130,392.00SqFt

Section: 250 of 4 From: - To: - Last Const.: 01/01/2004

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 33,625.00SqFt Length: 300.00Ft Width: 104.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 7 Surveyed: 1

Conditions: PCI : 82

Inspection Comments:

Sample Number: 405 Type: R Area: 5,379.00SqFt PCI = 82

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 92.00 Ft Comments:

52 RAVELING L 269.00 SqFt Comments:

57 WEATHERING L 5,110.00 SqFt Comments:

42 BLEEDING N 10.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 130,392.00SqFt

Section: 252 of 4 From: - To: - Last Const.: 01/01/2002

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 16,451.00SqFt Length: 200.00Ft Width: 75.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 73

Inspection Comments:

Sample Number: 407 Type: R Area: 6,217.00SqFt PCI = 73

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 366.00 Ft Comments:

52 RAVELING L 311.00 SqFt Comments:

57 WEATHERING L 5,906.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 130,392.00SqFt

Section: 505 of 4 From: To: Last Const.: 01/01/1997

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 13,138.00SqFt Length: 308.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 75

Inspection Comments:

Sample Number: 401 Type: R Area: 4,800.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 252.00 Ft Comments:

52 RAVELING L 480.00 SqFt Comments:

57 WEATHERING L 4,320.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW C Name: TAXIWAY C Use: TAXIWAY Area: 130,392.00SqFt

Section: 510 of 4 From: To: Last Const.: 01/01/1997  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 67,178.00SqFt Length: 1,864.00Ft Width: 35.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 19 Surveyed: 3

Conditions: PCI : 79

Inspection Comments:

Sample Number: 505 Type: R Area: 3,500.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 97.00 Ft Comments:  
52 RAVELING L 175.00 SqFt Comments:  
57 WEATHERING L 3,325.00 SqFt Comments:

Sample Number: 511 Type: R Area: 3,500.00SqFt PCI = 77

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 144.00 Ft Comments:  
52 RAVELING L 175.00 SqFt Comments:  
57 WEATHERING L 3,325.00 SqFt Comments:

Sample Number: 517 Type: R Area: 3,500.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 100.00 Ft Comments:  
52 RAVELING L 175.00 SqFt Comments:  
57 WEATHERING L 3,325.00 SqFt Comments:



# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW C2 Name: TAXIWAY C2 Use: TAXIWAY Area: 31,643.00SqFt

Section: 515 of 1 From: - To: - Last Const.: 01/01/1997

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 31,643.00SqFt Length: 882.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 9 Surveyed: 1

Conditions: PCI : 80

Inspection Comments:

Sample Number: 605 Type: R Area: 3,500.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 105.00 Ft Comments:

52 RAVELING L 175.00 SqFt Comments:

57 WEATHERING L 3,325.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 230,858.00SqFt

Section: 140 of 4 From: - To: - Last Const.: 01/01/2001  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 43,648.00SqFt Length: 375.00Ft Width: 97.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 9 Surveyed: 2

Conditions: PCI : 75

Inspection Comments:

Sample Number: 301 Type: R Area: 4,410.00SqFt PCI = 70

Sample Comments:

|    |                                  |   |               |           |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | M | 78.00 Ft      | Comments: |
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 120.00 Ft     | Comments: |
| 52 | RAVELING                         | L | 221.00 SqFt   | Comments: |
| 57 | WEATHERING                       | L | 4,189.00 SqFt | Comments: |

Sample Number: 306 Type: R Area: 4,854.00SqFt PCI = 79

Sample Comments:

|    |                                  |   |               |           |
|----|----------------------------------|---|---------------|-----------|
| 48 | LONGITUDINAL/TRANSVERSE CRACKING | L | 167.00 Ft     | Comments: |
| 52 | RAVELING                         | L | 243.00 SqFt   | Comments: |
| 57 | WEATHERING                       | L | 4,611.00 SqFt | Comments: |

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 230,858.00SqFt

Section: 405 of 4 From: To: Last Const.: 01/01/2000  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 118,752.00SqFt Length: 3,352.00Ft Width: 35.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 33 Surveyed: 4

Conditions: PCI : 79

Inspection Comments:

Sample Number: 406 Type: R Area: 3,500.00SqFt PCI = 79

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 114.00 Ft Comments:  
52 RAVELING L 175.00 SqFt Comments:  
57 WEATHERING L 3,325.00 SqFt Comments:  
45 DEPRESSION L 4.00 SqFt Comments:

Sample Number: 413 Type: R Area: 3,500.00SqFt PCI = 76

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 164.00 Ft Comments:  
52 RAVELING L 175.00 SqFt Comments:  
57 WEATHERING L 3,325.00 SqFt Comments:

Sample Number: 421 Type: R Area: 3,500.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 100.00 Ft Comments:  
52 RAVELING L 175.00 SqFt Comments:  
57 WEATHERING L 3,325.00 SqFt Comments:

Sample Number: 429 Type: R Area: 3,500.00SqFt PCI = 81

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 97.00 Ft Comments:  
52 RAVELING L 175.00 SqFt Comments:  
57 WEATHERING L 3,325.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 230,858.00SqFt

Section: 410 of 4 From: - To: - Last Const.: 01/01/2005

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 20,158.00SqFt Length: 132.00Ft Width: 154.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 4 Surveyed: 1

Conditions: PCI : 75

Inspection Comments:

Sample Number: 601 Type: R Area: 5,189.00SqFt PCI = 75

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 263.00 Ft Comments:

52 RAVELING L 259.00 SqFt Comments:

57 WEATHERING L 4,930.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW D Name: TAXIWAY D Use: TAXIWAY Area: 230,858.00SqFt

Section: 430 of 4 From: To: Last Const.: 01/01/2005  
Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P  
Area: 48,300.00SqFt Length: 1,340.00Ft Width: 35.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 12 Surveyed: 3

Conditions: PCI : 86

Inspection Comments:

Sample Number: 437 Type: R Area: 3,500.00SqFt PCI = 86

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 12.00 Ft Comments:  
52 RAVELING L 70.00 SqFt Comments:  
57 WEATHERING L 3,430.00 SqFt Comments:

Sample Number: 440 Type: R Area: 3,500.00SqFt PCI = 90

Sample Comments:

52 RAVELING L 70.00 SqFt Comments:  
57 WEATHERING L 3,430.00 SqFt Comments:

Sample Number: 445 Type: R Area: 4,412.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 70.00 Ft Comments:  
52 RAVELING L 221.00 SqFt Comments:  
57 WEATHERING L 4,191.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW D1 Name: TAXIWAY D1 Use: TAXIWAY Area: 13,134.00SqFt

Section: 415 of 1 From: To: Last Const.: 01/01/2000

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 13,134.00SqFt Length: 308.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 83

Inspection Comments:

Sample Number: 302 Type: R Area: 3,500.00SqFt PCI = 83

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 45.00 Ft Comments:

52 RAVELING L 175.00 SqFt Comments:

57 WEATHERING L 3,325.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW D2 Name: TAXIWAY D2 Use: TAXIWAY Area: 13,134.00SqFt

Section: 420 of 1 From: To: Last Const.: 01/01/2000

Surface: AC Family: FDOT-SAPMP-PR-TW-AC Zone: Category: Rank: P

Area: 13,134.00SqFt Length: 308.00Ft Width: 35.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 80

Inspection Comments:

Sample Number: 201 Type: R Area: 4,798.00SqFt PCI = 80

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 147.00 Ft Comments:

52 RAVELING L 240.00 SqFt Comments:

57 WEATHERING L 4,558.00 SqFt Comments:

# Re-inspection Report

FDOT

Report Generated Date: May 14, 2015

Network: PNS Name: PENSACOLA INTERNATIONAL AIRPORT

Branch: TW D3 Name: TAXIWAY D3 Use: TAXIWAY Area: 14,220.00SqFt

Section: 425 of 1 From: To: Last Const.: 01/01/2006

Surface: AAC Family: FDOT-SAPMP-PR-TW-AAC Zone: Category: Rank: P

Area: 14,220.00SqFt Length: 308.00Ft Width: 40.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 02/10/2015 Total Samples: 3 Surveyed: 1

Conditions: PCI : 87

Inspection Comments:

Sample Number: 102 Type: R Area: 4,000.00SqFt PCI = 87

Sample Comments:

45 DEPRESSION L 4.00 SqFt Comments:


45 DEPRESSION L 6.00 SqFt Comments:

52 RAVELING L 200.00 SqFt Comments:

57 WEATHERING L 3,800.00 SqFt Comments:







**FLORIDA DEPARTMENT OF TRANSPORTATION**  
AVIATION AND SPACEPORT OFFICE

