

**FLORIDA DEPARTMENT OF TRANSPORTATION**  
**AVIATION AND SPACEPORTS OFFICE**

# **Statewide Airfield Pavement Management Program**

**Airport Pavement  
Evaluation Report  
September 2017**



**Brooksville -  
Tampa Bay Regional  
Airport (BKV)**  
General Aviation Airport  
District 7





---

*Florida Department of Transportation*

---

# Statewide Airfield Pavement Management Program

**Prepared by:**

*FDOT Aviation and Spaceports Office  
605 Suwannee Street  
Tallahassee, Florida 32399-0450*



OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS




# Table of Contents

<b>Executive Summary.....</b>	<b>10</b>
<b>Program Background.....</b>	<b>10</b>
<b>Summary of Results.....</b>	<b>11</b>
Pavement Condition Index (Latest Inspection) .....	11
Forecasted Pavement Condition Index 2018-2027.....	13
Major Rehabilitation Planning 2018-2027 .....	14
<b>Summary of Brooksville – Tampa Bay Regional Airport .....</b>	<b>16</b>
<b>Chapter 1 – Introduction.....</b>	<b>18</b>
1.1 Background .....	18
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017 ....	18
1.3 Organization .....	20
1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager .....	20
1.3.2 Participating Florida Public-Use and Publicly Owned Airports .....	20
1.3.3 Florida Department of Transportation District Offices.....	20
1.3.4 Consultant .....	20
1.4 Purpose of Airport Pavement Evaluation Report .....	22
1.5 History of the Program.....	22
1.6 Federal Aviation Administration (FAA) .....	24
1.7 FDOT SAPMP Objectives and Components .....	24
1.7.1 Program Objectives.....	24
1.7.2 Program Components .....	24
1.8 References .....	28
<b>Chapter 2 – Methodology .....</b>	<b>30</b>
2.1 Airfield Pavement Database.....	30
2.2 Airfield Pavement System Inventory .....	30
2.2.1 Pavement Management Program Network Definition Terminology .....	31
2.3 Airfield Pavement Structure.....	33
2.3.1 Pavement Structure Types.....	33
2.4 Airfield Pavement Work History .....	35
2.4.1 Airfield Pavement Record Keeping .....	35
2.5 Airfield Pavement Traffic .....	35
2.6 Airfield Pavement Condition Index (PCI) Survey.....	35
2.6.1 PCI Survey Methodology .....	35
2.6.2 Pavement Distress Types .....	37


2.6.3 PCI Survey Inspection Procedures .....	41
2.6.4 Updates to the ASTM D5340-12 .....	42
<b>Chapter 3 – Airfield Pavement System Inventory .....</b>	<b>45</b>
<b>3.1 Airfield Pavement Network Information .....</b>	<b>45</b>
3.1.1 Previous and/or Anticipated Airfield Pavement Construction .....	45
3.1.2 Estimated Pavement Age.....	47
3.1.3 Functional Use Classification .....	49
3.1.4 Pavement Surface Type.....	50
3.1.5 Pavement System Inventory Details .....	51
<b>Chapter 4 – Airfield Pavement Condition .....</b>	<b>56</b>
<b>4.1 Airfield Pavement Condition Index (Latest Inspection) .....</b>	<b>56</b>
4.1.1 Network-Level Analysis .....	56
4.1.2 Branch-Level Analysis.....	56
4.1.3 Section-Level Analysis .....	59
<b>4.2 Summary of Pavement Condition Evaluation Results .....</b>	<b>63</b>
4.2.1 Network-Level Observations .....	63
4.2.2 Branch-Level Observations.....	63
<b>4.3 Forecasted Pavement Conditions .....</b>	<b>66</b>
4.3.1 Performance Models and Prediction Curves .....	66
4.3.2 Branch-Level Pavement Condition Forecast .....	66
4.3.3 Section-Level Pavement Condition Forecast.....	68
4.3.4 Forecasted PCI Considerations .....	71
<b>Chapter 5 – Localized Maintenance and Repair Planning.....</b>	<b>73</b>
5.1 Localized Maintenance and Repair .....	73
5.2 Localized Maintenance and Repair Policy .....	74
5.3 Localized Maintenance and Repair Analysis and Recommendations .....	78
<b>Chapter 6 – Major Rehabilitation Planning.....</b>	<b>83</b>
<b>6.1 Major Rehabilitation .....</b>	<b>83</b>
6.1.1 Critical PCI .....	85
6.1.2 FDOT Recommended Minimum Service-Level PCI .....	85
<b>6.2 Major Rehabilitation Policy .....</b>	<b>86</b>
6.2.1 Major Rehabilitation Pavement Section Development.....	86
6.2.2 Major Rehabilitation Planning-Level Unit Costs.....	87
<b>6.3 Major Rehabilitation Needs.....</b>	<b>88</b>
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs .....	88
<b>Chapter 7 – Conclusion .....</b>	<b>93</b>
<b>7.1 Recommendations .....</b>	<b>93</b>
7.1.1 Continued PCI Survey Inspections .....	93
7.1.2 Localized Maintenance and Repair.....	93



7.1.3 Major Rehabilitation .....	93
7.1.4 Pavement Management System .....	93
<b>7.2 Supporting Documents .....</b>	<b>94</b>
001 – Airfield Pavement Network Definition Exhibit .....	94
002 – Airfield Pavement System Inventory Exhibit .....	94
003 – Airfield Pavement Condition Index Exhibit .....	94
004 – Airfield Pavement Major Rehabilitation Exhibit .....	94
Inspection Photograph Documentation .....	94
<b>7.3 Conclusion .....</b>	<b>95</b>



Appendix A	Airfield Pavement Analysis Tables
Appendix B	Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
Appendix C	Technical Exhibits
Appendix D	Inspection Photograph Documentation
Appendix E	Inspection Distress Details





## List of Figures

Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027 .....	16
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts .....	19
Figure 1.7-1 Typical Pavement Condition Life Cycle .....	25
Figure 1.7-2 General Pavement Treatments by Condition Range .....	26
Figure 1.7-3 Flexible Asphalt Concrete .....	27
Figure 1.7-4 Rigid Portland Cement Concrete .....	27
Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit .....	46
Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit .....	47
Figure 3.1.2 Average Age of Pavements at Inspection .....	48
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area .....	49
Figure 3.1.4 (a) Pavement Surface Type by Area (SF) .....	50
Figure 3.1.4 (b) Pavement Surface Type by Area (%) .....	51
Figure 4.1.1 Latest Condition – Overall Network .....	56
Figure 4.1.2 (a) Latest Condition – Runway Pavements .....	57
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements .....	57
Figure 4.1.2 (c) Latest Condition – Apron Pavements .....	58
Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit .....	62
Figure 4.2.2 Pavement Condition Summary by Facility Use .....	63
Figure 4.3.2 (a) Forecasted Runway Pavement Performance .....	66
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance .....	67
Figure 4.3.2 (c) Forecasted Apron Pavement Performance .....	67
Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, $PCI \leq$ Critical PCI .....	83
Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, $PCI >$ Critical PCI .....	84
Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year .....	90
Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit .....	91

## List of Tables

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level.....	11
Table E-2 Pavement Condition Index Forecast 2018-2027 .....	13
Table E-3 Major Rehabilitation Planning 2018-2027 .....	14
Table 2.2.1 Airfield Pavement Database Network Definition Terminology .....	32
Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields .....	37
Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields.....	38
Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields.....	38
Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields..	39
Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields.....	40
Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields.....	40
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete .....	41
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete....	41
Table 2.6.4 Summary of Updates to ASTM D5340-12.....	43
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction .....	45
Table 3.1.5 Pavement System Inventory Details .....	52
Table 4.1.3 Latest Pavement Condition Index Summary.....	60
Table 4.3.3 Forecasted PCI 2018-2027 .....	69
Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete .....	74
Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete.....	75
Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete .....	77
Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete ..	77



Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level	78
Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level	79
Table 5.3-3 Summary of Localized Maintenance	81
Table 6.1.2 FDOT Recommended Minimum Service-Level PCI	85
Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete	86
Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete	87
Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type	88
Table 6.3.1 10-Year Major Rehabilitation Needs	89



# **Executive Summary**







# Executive Summary

## Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP)”** using the documented procedures set forth by ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.



## Summary of Results

### Pavement Condition Index (Latest Inspection)

*Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level*

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BKV	RUNWAY 9-27	RUNWAY	6105	350,000	44	Poor
BKV	RUNWAY 9-27	RUNWAY	6110	700,000	55	Poor
BKV	RUNWAY 3-21	RUNWAY	6205	250,750	43	Poor
BKV	RUNWAY 3-21	RUNWAY	6210	501,500	52	Poor
BKV	TAXIWAY A	TAXIWAY	105	636,744	48	Poor
BKV	TAXIWAY A	TAXIWAY	108	11,563	98	Good
BKV	TAXIWAY A1	TAXIWAY	110	56,894	50	Poor
BKV	TAXIWAY A1	TAXIWAY	111	17,870	74	Satisfactory
BKV	TAXIWAY A1	TAXIWAY	112	18,154	51	Poor
BKV	TAXIWAY A3	TAXIWAY	120	10,837	35	Very Poor
BKV	TAXIWAY A3	TAXIWAY	125	26,322	15	Serious
BKV	TAXIWAY A5	TAXIWAY	130	33,046	48	Poor
BKV	TAXIWAY A6	TAXIWAY	135	31,614	16	Serious
BKV	TAXIWAY A9	TAXIWAY	140	31,973	58	Fair
BKV	TAXIWAY B	TAXIWAY	205	55,550	35	Very Poor
BKV	TAXIWAY B	TAXIWAY	210	118,423	60	Fair
BKV	TAXIWAY B1	TAXIWAY	145	80,954	61	Fair
BKV	TAXIWAY B1	TAXIWAY	215	63,745	54	Poor
BKV	TAXIWAY B1	TAXIWAY	216	45,429	53	Poor
BKV	TAXIWAY B2	TAXIWAY	220	7,309	33	Very Poor
BKV	TAXIWAY B3	TAXIWAY	225	7,309	56	Fair
BKV	TAXIWAY B4	TAXIWAY	230	6,246	56	Fair
BKV	NE APRON	APRON	4105	29,444	35	Very Poor
BKV	NE APRON	APRON	4110	14,592	40	Very Poor
BKV	NE APRON	APRON	4115	21,610	100	Good
BKV	NE APRON	APRON	4117	14,188	31	Very Poor
BKV	NE APRON	APRON	4120	29,272	31	Very Poor
BKV	NE APRON	APRON	4123	23,785	100	Good
BKV	NE APRON	APRON	4125	23,740	100	Good
BKV	NE APRON	APRON	4130	6,146	100	Good
BKV	NE APRON	APRON	4135	47,738	74	Satisfactory
BKV	NE APRON	APRON	4137	11,384	100	Good
BKV	NE APRON	APRON	4140	188,863	68	Fair
BKV	NE APRON	APRON	4143	33,176	100	Good





Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BKV	NE APRON	APRON	4145	72,809	100	Good
BKV	NE APRON	APRON	4147	7,371	100	Good
BKV	NE APRON	APRON	4150	28,017	55	Poor
BKV	SOUTH APRON	APRON	4205	3,398	59	Fair
BKV	SOUTH APRON	APRON	4210	52,541	61	Fair
BKV	SOUTH APRON	APRON	4215	32,595	66	Fair
BKV	SOUTH APRON	APRON	4220	28,845	64	Fair
BKV	SOUTH APRON	APRON	4225	114,556	90	Good



## Forecasted Pavement Condition Index 2018-2027

Table E-2 Pavement Condition Index Forecast 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BKV	AP NE	4105	35	33	32	30	29	27	25	24	22	21	19
BKV	AP NE	4110	40	38	37	35	34	32	30	29	27	26	24
BKV	AP NE	4115	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4117	31	29	28	26	25	23	21	20	18	17	15
BKV	AP NE	4120	31	29	28	26	25	23	21	20	18	17	15
BKV	AP NE	4123	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4125	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4130	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4135	74	72	71	69	68	66	64	63	61	60	58
BKV	AP NE	4137	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4140	68	66	65	63	62	60	58	57	55	54	52
BKV	AP NE	4143	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4145	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4147	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4150	55	54	53	52	51	50	49	48	47	47	46
BKV	AP S	4205	59	57	56	54	53	51	49	48	46	45	43
BKV	AP S	4210	61	59	58	56	55	53	51	50	48	47	45
BKV	AP S	4215	66	64	63	61	60	58	56	55	53	52	50
BKV	AP S	4220	64	62	61	59	58	56	54	53	51	50	48
BKV	AP S	4225	90	88	87	85	84	82	80	79	77	76	74
BKV	RW 3-21	6205	43	42	41	40	39	39	38	37	36	35	34
BKV	RW 3-21	6210	52	51	50	49	48	48	47	46	45	44	43
BKV	RW 9-27	6105	44	43	42	41	40	40	39	38	37	36	35
BKV	RW 9-27	6110	55	54	53	52	51	51	50	49	48	47	46
BKV	TW A	105	48	47	46	45	44	44	43	42	41	40	39
BKV	TW A	108	98	97	96	95	94	94	93	92	91	90	89
BKV	TW A1	110	50	49	48	47	46	46	45	44	43	42	41
BKV	TW A1	111	74	73	72	71	70	69	68	67	66	65	64
BKV	TW A1	112	51	49	48	46	44	43	41	40	38	37	35
BKV	TW A3	120	35	34	33	32	31	31	30	29	28	27	26
BKV	TW A3	125	15	12	10	7	4	2	0	0	0	0	0
BKV	TW A5	130	48	47	46	45	44	44	43	42	41	40	39
BKV	TW A6	135	16	13	11	8	5	3	0	0	0	0	0
BKV	TW A9	140	58	57	56	55	54	54	53	52	51	50	49
BKV	TW B	205	35	34	33	32	31	30	29	28	28	27	26





Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BKV	TW B	210	60	59	58	56	55	54	52	51	49	47	46
BKV	TW B1	145	61	60	59	58	56	55	54	52	51	49	47
BKV	TW B1	215	54	53	52	51	50	50	49	48	47	46	45
BKV	TW B1	216	53	51	50	48	47	45	43	42	40	39	37
BKV	TW B2	220	33	32	31	30	29	29	28	27	26	25	23
BKV	TW B3	225	56	54	53	52	50	48	47	45	44	42	40
BKV	TW B4	230	56	54	53	52	50	48	47	45	44	42	40

## Major Rehabilitation Planning 2018-2027

Table E-3 Major Rehabilitation Planning 2018-2027


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BKV	AP NE	4105	AC	29,444	33	AC Reconstruction	\$ 266,000.00
2018	BKV	AP NE	4110	AC	14,592	38	AC Reconstruction	\$ 132,000.00
2018	BKV	AP NE	4117	AC	14,188	29	AC Reconstruction	\$ 128,000.00
2018	BKV	AP NE	4120	AC	29,272	29	AC Reconstruction	\$ 264,000.00
2018	BKV	AP NE	4150	PCC	28,017	54	PCC Restoration	\$ 281,000.00
2018	BKV	AP S	4205	AC	3,398	57	AC Restoration	\$ 24,000.00
2018	BKV	AP S	4210	AC	52,541	59	AC Restoration	\$ 368,000.00
2018	BKV	AP S	4215	AC	32,595	64	AC Restoration	\$ 229,000.00
2018	BKV	AP S	4220	AC	28,845	62	AC Restoration	\$ 202,000.00
2018	BKV	RW 3-21	6205	PCC	250,750	42	PCC Restoration	\$ 3,466,000.00
2018	BKV	RW 3-21	6210	PCC	501,500	51	PCC Restoration	\$ 5,016,000.00
2018	BKV	RW 9-27	6105	PCC	350,000	43	PCC Restoration	\$ 4,663,000.00
2018	BKV	RW 9-27	6110	PCC	700,000	54	PCC Restoration	\$ 7,001,000.00
2018	BKV	TW A	105	PCC	636,744	47	PCC Restoration	\$ 7,209,000.00
2018	BKV	TW A1	110	PCC	56,894	49	PCC Restoration	\$ 588,000.00
2018	BKV	TW A1	112	AC	18,154	49	AC Restoration	\$ 128,000.00
2018	BKV	TW A3	120	PCC	10,837	34	PCC Reconstruction	\$ 163,000.00
2018	BKV	TW A3	125	AC	26,322	12	AC Reconstruction	\$ 237,000.00
2018	BKV	TW A5	130	PCC	33,046	47	PCC Restoration	\$ 375,000.00
2018	BKV	TW A6	135	AC	31,614	13	AC Reconstruction	\$ 285,000.00
2018	BKV	TW A9	140	PCC	31,973	57	PCC Restoration	\$ 320,000.00
2018	BKV	TW B	205	AC	55,550	34	AC Reconstruction	\$ 500,000.00
2018	BKV	TW B	210	AC	118,423	59	AC Restoration	\$ 829,000.00
2018	BKV	TW B1	145	AC	80,954	60	AC Restoration	\$ 567,000.00
2018	BKV	TW B1	215	PCC	63,745	53	PCC Restoration	\$ 638,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BKV	TW B1	216	AC	45,429	51	AC Restoration	\$ 319,000.00
2018	BKV	TW B2	220	AC	7,309	32	AC Reconstruction	\$ 66,000.00
2018	BKV	TW B3	225	AC	7,309	54	AC Restoration	\$ 52,000.00
2018	BKV	TW B4	230	AC	6,246	54	AC Restoration	\$ 44,000.00
2020	BKV	AP NE	4140	AC	188,863	63	AC Restoration	\$ 1,323,000.00
2023	BKV	AP NE	4135	AC	47,738	64	AC Restoration	\$ 335,000.00
2027	BKV	TW A1	111	AAC	17,870	64	AC Restoration	\$ 126,000.00

*\*All planning cost values have been rounded to the nearest thousand-dollar.*




*Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027*

## Summary of Brooksville – Tampa Bay Regional Airport

Brooksville – Tampa Bay Regional Airport was inspected in March 2017 – the overall weighted PCI value was 55, a condition rating of Poor. The results of the maintenance, repair, and major rehabilitation analysis identified \$4,719,220 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$36,144,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$34,360,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.

# Chapter 1







# Chapter 1 – Introduction

## 1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

## 1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating public-use airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.





## 1.3 Organization

### 1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

### 1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."** Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

### 1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

### 1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys,"** evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."**

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- **Research and evaluation of existing record documentation** was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- **An update to the existing Network Definition Map** was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- **A functional pavement evaluation with PCI Survey inspections** was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- **Maintenance, Repair, and Rehabilitation Planning** was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.





## 1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

***The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.***

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA **AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

## 1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."** The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.



## 1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and **150/5380-7B “Airport Pavement Management Program (PMP)”**). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.”

## 1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC **150/5380-7B “Airport Pavement Management Program (PMP)”** an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

### 1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

### 1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data






## F. Pavement Performance Modeling for the Prediction/Forecast of PCI

## G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements’ past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and cost-effective manner. **Figure 1.7-1 Typical Pavement Condition Life Cycle**, which is based on the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”** **Figure 1.7-1 Typical Pavement Condition Life Cycle**, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.

*Figure 1.7-1 Typical Pavement Condition Life Cycle*




*\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).*

**Figure 1.7-2 General Pavement Treatments by Condition Range** depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

*Figure 1.7-2 General Pavement Treatments by Condition Range*



Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7-1 and 1.7-2**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

**Figures 1.7-3 and Figure 1.7-4** depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.



Figure 1.7-3 Flexible Asphalt Concrete









	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figure 1.7-4 Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.






## 1.8 References

---

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”
- FAA Advisory Circular 150/5380-7B 150/5380-7B “Airport Pavement Management Program.”
- FAA Advisory Circular 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”
- FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation.”
- Department of the Air Force, Air Force Civil Engineer Center “Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements.”
- Unified Facilities Criteria (UFC) 3-260-16FA 16 “Airfield Pavement Condition Survey Procedures Pavements.”
- Unified Facilities Criteria (UFC) 3-260-03 “Airfield Pavement Evaluation.”
- Pavement Management for Airports, Roads, and Parking Lots 2<sup>nd</sup> Edition, M.Y. Shahin.

# Chapter 2





## Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”**

### 2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

### 2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.





A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

### 2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

#### Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

#### Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

#### Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a “parent” pavement network.

## Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs ( $\pm 8$  slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ( $\pm 2,000$  ft<sup>2</sup>) for flexible asphalt concrete (AC) or porous friction course pavements.

*Table 2.2.1 Airfield Pavement Database Network Definition Terminology*

PMS Network Level	Common Definition	Airport Example
<b>Network</b>	Overall pavement assets maintained by the Airport	“Tallahassee International Airport – Airfield Pavements”
<b>Branch Name</b>	Commonly defined asset name as established by Airport and by use	“Runway 18-36”
<b>Branch ID</b>	Codified shorthand name for commonly defined asset established for database identification	“RW 18-36”  RW, Branch Use, “Runway” 18-36, Runway Facility
<b>Section ID</b>	Codified identification for pavement asset that is distinct by the following: <ul style="list-style-type: none"><li>• Pavement Composition</li><li>• Construction Work History</li><li>• Aircraft Traffic</li><li>• Condition Records</li></ul>	“6105”
<b>Sample Unit</b>	A numeric identification of an area of pavement (5,000 $\pm$ 2,000 SF of AC or 20 $\pm$ 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	“300”



## 2.3 Airfield Pavement Structure

### 2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

#### Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

##### *Asphalt Concrete (AC)*

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

##### *Asphalt Concrete Overlaid on Asphalt Concrete (AAC)*

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

##### *Asphalt Concrete Overlaid on Portland Cement Concrete (APC)*

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.





## Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

### *Portland Cement Concrete (PCC)*

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

## Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

### *Conventional Whitetopping (WHT)*

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 6-inches in thickness.

### *Thin Whitetopping (TWT)*

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

### *Ultra-Thin Whitetopping (UTW)*

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.



## 2.4 Airfield Pavement Work History

### 2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

1. Location and Limits of Work.
2. Types and Severity of Distresses Repaired.
3. Type of Work.
4. Cost of Work.
5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

## 2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

## 2.6 Airfield Pavement Condition Index (PCI) Survey

### 2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP),"** the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.





## 2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

*Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields*

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age



*Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields*

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> <li>Alligator Cracking</li> <li>Corrugation</li> <li>Depression</li> <li>Patching of Load-based distress</li> <li>Polished Aggregate</li> <li>Rutting</li> <li>Slippage Cracking</li> </ul>	<ul style="list-style-type: none"> <li>Bleeding</li> <li>Block Cracking</li> <li>Joint Reflection Cracking</li> <li>L/T Cracking</li> <li>Patching of climate / durability-caused distresses</li> <li>Shoving from PCC</li> <li>Raveling</li> <li>Weathering</li> <li>Swelling</li> </ul>	<ul style="list-style-type: none"> <li>Alligator Cracking</li> <li>Depression</li> <li>Patching of moisture / drainage caused distress</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	<ul style="list-style-type: none"> <li>Oil Spillage</li> <li>Jet Blast Erosion</li> <li>Polished Aggregate</li> </ul>

*Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields*

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> <li>Corrugation</li> <li>Depression</li> <li>Rutting</li> <li>Shoving of asphalt pavement</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	<ul style="list-style-type: none"> <li>Bleeding</li> <li>Depression</li> <li>Polished Aggregate</li> <li>Rutting</li> </ul>	<ul style="list-style-type: none"> <li>Block Cracking</li> <li>Joint Reflection Cracking</li> <li>L/T Cracking</li> <li>Slippage Cracking</li> </ul>	<ul style="list-style-type: none"> <li>All Distresses</li> </ul>



*Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields*

Distress	Common Distress Mechanisms
Blowup	Climate / ASR
Corner Break	Load Repetition / Curling Stresses
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
Durability Cracking	Freeze-Thaw Cycling
Joint Seal Damage	Material Deterioration / Construction Quality / Age
Small Patch	Pavement Repair
Large Patch/Utility Cut	Utility / Pavement Repair
Popout	Freeze-Thaw Cycling / ASR / Material Quality
Pumping	Load Repetition / Poor Joint Sealant
Scaling	Construction Quality / Freeze-Thaw Cycling
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer
Shattered Slab	Overloading
Shrinkage Cracking	Construction Quality / Climate
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction





*Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields*

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> <li>• Corner Break</li> <li>• Shattered Slab</li> <li>• L/T/D Cracking</li> <li>• Pumping</li> <li>• Patching of Load-associated distress</li> <li>• Spalling</li> </ul>	<ul style="list-style-type: none"> <li>• Blowup</li> <li>• "D" Cracking</li> <li>• Joint Seal Damage</li> <li>• Popouts</li> <li>• Scaling</li> <li>• Patch of Climate/Durability-associated distress</li> <li>• Shrinkage Cracking</li> <li>• Spalling</li> <li>• L/T/D Cracking</li> </ul>	<ul style="list-style-type: none"> <li>• Corner Break</li> <li>• Shattered Slab</li> <li>• Pumping</li> <li>• Patching of Moisture/Drainage-associated distress</li> </ul>	<ul style="list-style-type: none"> <li>• Settlement / Faulting</li> </ul>

*Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields*

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> <li>• Blowup</li> <li>• Corner Break</li> <li>• L/T/D Cracking</li> <li>• Shattered Slab</li> <li>• Settlement / Faulting</li> <li>• Spalling</li> </ul>	<ul style="list-style-type: none"> <li>• Settlement / Faulting</li> <li>• Spalling</li> </ul>	<ul style="list-style-type: none"> <li>• Corner Break</li> <li>• L/T/D Cracking</li> <li>• "D" Cracking</li> <li>• Joint Seal Damage</li> <li>• Shattered Slab</li> <li>• Popouts</li> <li>• Scaling</li> </ul>	<ul style="list-style-type: none"> <li>• All distresses</li> </ul>



### 2.6.3 PCI Survey Inspection Procedures

#### Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

*Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete*

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but $\leq 20$	10% but $\leq 10$

*Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete*

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but $\leq 20$	10% but $\leq 10$



#### 2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in an adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

##### *Flexible Asphalt Concrete Pavement Distress Updates*

The previous methodology which featured “(52) Weathering and Raveling” distress has been separated into two distresses “(52) Raveling” and “(57) Weathering.” Previously, areas that were recorded as “Weathering and Raveling” were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where “Weathering” only exists and does not meet the definition of “Raveling,” the PCI deduction is not as high as the former “Weathering and Raveling.” Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling,” may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

##### *Rigid Portland Cement Concrete Pavement Distress Updates*

The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR.” As a result the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling,” and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, “(73) Shrinkage Cracks” has been redefined as “(73) Shrinkage Cracking”. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.






Table 2.6.4 Summary of Updates to ASTM D5340-12

Distress Updates to Reflect ASTM 5340-12				
Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Cracking - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Cracking - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Cracking - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Cracking' may now be identified as 'Shrinkage Cracking'

# **Chapter 3**





# Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

## 3.1 Airfield Pavement Network Information

### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1-1** and **Figure 3.1.1-2** provides an inset view of the 2017 Airfield Pavement Network Definition Exhibit and the 2017 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.

*Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction*


Year	General Work Description
2013	TW A - Reconstruction
2015	AP NE - Mill and Overlay: 4" P-401
2018	TW B - Reconstruction
2019	RW 3-21 - Runway Extension
	TW Connectors - New Construction

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.






*Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit*



*The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.*



Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit




The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections since any major construction activity has occurred during the PCI Survey inspection. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.



Figure 3.1.2 Average Age of Pavements at Inspection



The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.






### 3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

*Figure 3.1.3 Airfield Pavement Functional Classification Use by Area*







### 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.

*Figure 3.1.4 (a) Pavement Surface Type by Area (SF)*



*Figure 3.1.4 (b) Pavement Surface Type by Area (%)*

### 3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BKV	NE APRON	AP NE	APRON	4105	600	42	29,444	AC	1/1/1975
BKV	NE APRON	AP NE	APRON	4110	290	50	14,592	AC	1/1/1975
BKV	NE APRON	AP NE	APRON	4115	250	75	21,610	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4117	150	75	14,188	AC	1/1/1975
BKV	NE APRON	AP NE	APRON	4120	125	200	29,272	AC	1/1/1964
BKV	NE APRON	AP NE	APRON	4123	100	200	23,785	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4125	260	90	23,740	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4130	25.5	200	6,146	APC	1/1/2015
BKV	NE APRON	AP NE	APRON	4135	500	95	47,738	AC	1/1/1983
BKV	NE APRON	AP NE	APRON	4137	100	95	11,384	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4140	925	200	188,863	AC	1/1/1991
BKV	NE APRON	AP NE	APRON	4143	150	200	33,176	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4145	600	120	72,809	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4147	35	200	7,371	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4150	148	200	28,017	PCC	1/1/1991
BKV	SOUTH APRON	AP S	APRON	4205	90	35	3,398	AC	1/1/1991
BKV	SOUTH APRON	AP S	APRON	4210	453	112	52,541	AC	12/25/1999
BKV	SOUTH APRON	AP S	APRON	4215	450	65	32,595	AC	12/25/1999
BKV	SOUTH APRON	AP S	APRON	4220	425	65	28,845	AC	12/25/1999
BKV	SOUTH APRON	AP S	APRON	4225	1700	65	114,556	AC	1/1/2009
BKV	RUNWAY 3-21	RW 3-21	RUNWAY	6205	10000	25	250,750	PCC	1/1/1942
BKV	RUNWAY 3-21	RW 3-21	RUNWAY	6210	5000	100	501,500	PCC	1/1/1942
BKV	RUNWAY 9-27	RW 9-27	RUNWAY	6105	14000	25	350,000	PCC	1/1/1942
BKV	RUNWAY 9-27	RW 9-27	RUNWAY	6110	7000	100	700,000	PCC	1/1/1942
BKV	TAXIWAY A	TW A	TAXIWAY	105	8400	75	636,744	PCC	1/1/1942






Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BKV	TAXIWAY A	TW A	TAXIWAY	108	110	100	11,563	PCC	1/1/2013
BKV	TAXIWAY A1	TW A1	TAXIWAY	110	750	75	56,894	PCC	1/1/1942
BKV	TAXIWAY A1	TW A1	TAXIWAY	111	445	40	17,870	AAC	1/1/1991
BKV	TAXIWAY A1	TW A1	TAXIWAY	112	450	40	18,154	AC	1/1/1964
BKV	TAXIWAY A3	TW A3	TAXIWAY	120	413	25	10,837	PCC	1/1/1942
BKV	TAXIWAY A3	TW A3	TAXIWAY	125	400	53	26,322	AC	1/1/1986
BKV	TAXIWAY A5	TW A5	TAXIWAY	130	430	75	33,046	PCC	1/1/1942
BKV	TAXIWAY A6	TW A6	TAXIWAY	135	500	53	31,614	AC	1/1/1986
BKV	TAXIWAY A9	TW A9	TAXIWAY	140	420	75	31,973	PCC	1/1/1942
BKV	TAXIWAY B	TW B	TAXIWAY	205	1580	35	55,550	AC	1/1/1990
BKV	TAXIWAY B	TW B	TAXIWAY	210	3375	35	118,423	AC	1/1/1991
BKV	TAXIWAY B1	TW B1	TAXIWAY	145	1000	76	80,954	AC	1/1/1998
BKV	TAXIWAY B1	TW B1	TAXIWAY	215	810	75	63,745	PCC	1/1/1942
BKV	TAXIWAY B1	TW B1	TAXIWAY	216	885	50	45,429	AC	1/1/1991
BKV	TAXIWAY B2	TW B2	TAXIWAY	220	150	35	7,309	AC	1/1/1990
BKV	TAXIWAY B3	TW B3	TAXIWAY	225	150	35	7,309	AC	1/1/1991
BKV	TAXIWAY B4	TW B4	TAXIWAY	230	150	35	6,246	AC	1/1/1991



PAGE INTENTIONALLY LEFT BLANK

# Chapter 4





# Chapter 4 – Airfield Pavement Condition


The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

## 4.1 Airfield Pavement Condition Index (Latest Inspection)

### 4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.

*Figure 4.1.1 Latest Condition – Overall Network*



### 4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (c)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.





Figure 4.1.2 (a) Latest Condition – Runway Pavements




Figure 4.1.2 (b) Latest Condition – Taxiway Pavements







Figure 4.1.2 (c) Latest Condition – Apron Pavements





#### 4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement.

**Appendix C Technical Exhibits** provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.



Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
BKV	AP NE	NE APRON	APRON	4105	29,444	AC	35	Very Poor	100%	0%	0%	1	7
BKV	AP NE	NE APRON	APRON	4110	14,592	AC	40	Very Poor	100%	0%	0%	1	3
BKV	AP NE	NE APRON	APRON	4115	21,610	AAC	100	Good	0%	0%	0%	0	4
BKV	AP NE	NE APRON	APRON	4117	14,188	AC	31	Very Poor	83%	17%	0%	1	3
BKV	AP NE	NE APRON	APRON	4120	29,272	AC	31	Very Poor	100%	0%	0%	1	6
BKV	AP NE	NE APRON	APRON	4123	23,785	AAC	100	Good	0%	0%	0%	0	5
BKV	AP NE	NE APRON	APRON	4125	23,740	AAC	100	Good	0%	0%	0%	0	5
BKV	AP NE	NE APRON	APRON	4130	6,146	APC	100	Good	0%	0%	0%	0	1
BKV	AP NE	NE APRON	APRON	4135	47,738	AC	74	Satisfactory	100%	0%	0%	1	10
BKV	AP NE	NE APRON	APRON	4137	11,384	AAC	100	Good	0%	0%	0%	0	2
BKV	AP NE	NE APRON	APRON	4140	188,863	AC	68	Fair	96%	0%	4%	4	37
BKV	AP NE	NE APRON	APRON	4143	33,176	AAC	100	Good	0%	0%	0%	0	7
BKV	AP NE	NE APRON	APRON	4145	72,809	AAC	100	Good	0%	0%	0%	0	13
BKV	AP NE	NE APRON	APRON	4147	7,371	AAC	100	Good	0%	0%	0%	0	2
BKV	AP NE	NE APRON	APRON	4150	28,017	PCC	55	Poor	3%	64%	33%	1	5
BKV	AP S	SOUTH APRON	APRON	4205	3,398	AC	59	Fair	88%	0%	12%	1	1
BKV	AP S	SOUTH APRON	APRON	4210	52,541	AC	61	Fair	76%	0%	24%	1	8
BKV	AP S	SOUTH APRON	APRON	4215	32,595	AC	66	Fair	92%	0%	8%	1	7
BKV	AP S	SOUTH APRON	APRON	4220	28,845	AC	64	Fair	100%	0%	0%	1	7
BKV	AP S	SOUTH APRON	APRON	4225	114,556	AC	90	Good	100%	0%	0%	4	28
BKV	RW 3-21	RUNWAY 3-21	RUNWAY	6205	250,750	PCC	43	Poor	2%	44%	54%	10	50
BKV	RW 3-21	RUNWAY 3-21	RUNWAY	6210	501,500	PCC	52	Poor	2%	59%	39%	20	100
BKV	RW 9-27	RUNWAY 9-27	RUNWAY	6105	350,000	PCC	44	Poor	2%	38%	60%	14	70
BKV	RW 9-27	RUNWAY 9-27	RUNWAY	6110	700,000	PCC	55	Poor	3%	51%	46%	20	140
BKV	TW A	TAXIWAY A	TAXIWAY	105	636,744	PCC	48	Poor	2%	29%	69%	13	169
BKV	TW A	TAXIWAY A	TAXIWAY	108	11,563	PCC	98	Good	100%	0%	0%	1	3
BKV	TW A1	TAXIWAY A1	TAXIWAY	110	56,894	PCC	50	Poor	2%	39%	59%	3	15
BKV	TW A1	TAXIWAY A1	TAXIWAY	111	17,870	AAC	74	Satisfactory	100%	0%	0%	1	4
BKV	TW A1	TAXIWAY A1	TAXIWAY	112	18,154	AC	51	Poor	93%	0%	7%	1	5
BKV	TW A3	TAXIWAY A3	TAXIWAY	120	10,837	PCC	35	Very Poor	2%	47%	51%	1	2
BKV	TW A3	TAXIWAY A3	TAXIWAY	125	26,322	AC	15	Serious	100%	0%	0%	1	5
BKV	TW A5	TAXIWAY A5	TAXIWAY	130	33,046	PCC	48	Poor	3%	69%	28%	2	8
BKV	TW A6	TAXIWAY A6	TAXIWAY	135	31,614	AC	16	Serious	100%	0%	0%	2	8
BKV	TW A9	TAXIWAY A9	TAXIWAY	140	31,973	PCC	58	Fair	3%	41%	56%	2	8
BKV	TW B	TAXIWAY B	TAXIWAY	205	55,550	AC	35	Very Poor	100%	0%	0%	3	15
BKV	TW B	TAXIWAY B	TAXIWAY	210	118,423	AC	60	Fair	100%	0%	0%	5	34
BKV	TW B1	TAXIWAY B1	TAXIWAY	145	80,954	AC	61	Fair	88%	0%	12%	3	18




Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
BKV	TW B1	TAXIWAY B1	TAXIWAY	215	63,745	PCC	54	Poor	3%	54%	43%	3	16
BKV	TW B1	TAXIWAY B1	TAXIWAY	216	45,429	AC	53	Poor	84%	0%	16%	2	9
BKV	TW B2	TAXIWAY B2	TAXIWAY	220	7,309	AC	33	Very Poor	100%	0%	0%	1	2
BKV	TW B3	TAXIWAY B3	TAXIWAY	225	7,309	AC	56	Fair	96%	0%	4%	1	2
BKV	TW B4	TAXIWAY B4	TAXIWAY	230	6,246	AC	56	Fair	100%	0%	0%	1	2



**Figure 4.1.3** is an inset view of the 2017 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits**.

*Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit*





## 4.2 Summary of Pavement Condition Evaluation Results

### 4.2.1 Network-Level Observations

The field PCI Survey performed at Brooksville – Tampa Bay Regional Airport (BKV) started on 03/29/2017 and was completed on 03/30/2017. The resulting overall average area-weighted PCI value was 55 representing a condition rating of Poor. Two runways service Brooksville – Tampa Bay Regional Airport: Runway 03-21 is 150-ft wide and 5,014-ft long, Runway 09-27 is 150-ft wide and 7,001-ft long.

Based on the FAA 5010 Report as of 08/03/2017 the Airport has reported 78,000 operations for 12 months ending 11/02/2015.

### 4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

#### *Runway 09-27*

Runway 09-27 consists of 2 sections constructed of PCC. The last construction year for Runway 09-27 was 1942. The average area-weighted PCI for Runway 09-27 is 51 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Runway 09-27 consist of Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### *Runway 03-21*

Runway 03-21 consists of 2 sections constructed of PCC. The last construction year for Runway 03-21 was 1942. The average area-weighted PCI for Runway 03-21 is 49 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Runway 03-21 consist of Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shattered Slab, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### *Taxiway A*

Taxiway A consists of 2 sections constructed of PCC. The last construction years range from 1942 to 2013. The average area-weighted PCI for Taxiway A is 48 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway A consist of Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shattered Slab, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### *Taxiway A1*

Taxiway A1 consists of 3 sections constructed of AC, AAC, and PCC. The last construction years range from 1942 to 1991. The average area-weighted PCI for Taxiway A1 is 54 representing a Poor condition rating. The pavement distresses observed were related to



Climate, Load, and Other distress classifications. Distresses observed in Taxiway A1 consist of Block Cracking, Depression, Longitudinal & Transverse Cracking, Weathering, Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

### *Taxiway A3*

Taxiway A3 consists of 2 sections constructed of AC and PCC. The last construction years range from 1942 to 1986. The average area-weighted PCI for Taxiway A3 is 20 representing a Serious condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway A3 consist of Block Cracking, Longitudinal & Transverse Cracking, Raveling, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Shrinkage Cracking, Joint Spall, and Corner Spall.

### *Taxiway A5*

Taxiway A5 consists of 1 section constructed of PCC. The last construction year for Taxiway A5 was 1942. The average area-weighted PCI for Taxiway A5 is 48 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway A5 consist of Linear Cracking, Joint Seal Damage, Small Patch, and Shrinkage Cracking.

### *Taxiway A9*

Taxiway A9 consists of 1 section constructed of PCC. The last construction year for Taxiway A9 was 1942. The average area-weighted PCI for Taxiway A9 is 58 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway A9 consist of Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Shrinkage Cracking, and Joint Spall.

### *Taxiway B1*

Taxiway B1 consists of 3 sections constructed of AC and PCC. The last construction years range from 1942 to 1998. The average area-weighted PCI for Taxiway B1 is 56 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway B1 consist of Block Cracking, Longitudinal & Transverse Cracking, Raveling, Swelling, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

### *NE Apron*

NE Apron consists of 15 sections constructed of AC, AAC, APC, and PCC. The last construction years range from 1964 to 2015. The average area-weighted PCI for NE Apron is 74 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in NE Apron consist of Alligator Cracking, Block Cracking, Depression, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Weathering, Linear Cracking, Joint Seal Damage, Shattered Slab, Shrinkage Cracking, and Joint Spall.



*Figure 4.2.2 Pavement Condition Summary by Facility Use*

Facility Use	Average Area-Weighted PCI	Condition Rating
Runway	50	Poor
Taxiway	49	Poor
Apron	74	Satisfactory



## 4.3 Forecasted Pavement Conditions

### 4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to develop forecasted PCI values based on historic trends and statistical models.

### 4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2018 through January 2027.

*Figure 4.3.2 (a) Forecasted Runway Pavement Performance*






Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance





#### 4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.





Table 4.3.3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BKV	AP NE	4105	35	33	32	30	29	27	25	24	22	21	19
BKV	AP NE	4110	40	38	37	35	34	32	30	29	27	26	24
BKV	AP NE	4115	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4117	31	29	28	26	25	23	21	20	18	17	15
BKV	AP NE	4120	31	29	28	26	25	23	21	20	18	17	15
BKV	AP NE	4123	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4125	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4130	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4135	74	72	71	69	68	66	64	63	61	60	58
BKV	AP NE	4137	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4140	68	66	65	63	62	60	58	57	55	54	52
BKV	AP NE	4143	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4145	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4147	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4150	55	54	53	52	51	50	49	48	47	47	46
BKV	AP S	4205	59	57	56	54	53	51	49	48	46	45	43
BKV	AP S	4210	61	59	58	56	55	53	51	50	48	47	45
BKV	AP S	4215	66	64	63	61	60	58	56	55	53	52	50
BKV	AP S	4220	64	62	61	59	58	56	54	53	51	50	48
BKV	AP S	4225	90	88	87	85	84	82	80	79	77	76	74
BKV	RW 3-21	6205	43	42	41	40	39	39	38	37	36	35	34
BKV	RW 3-21	6210	52	51	50	49	48	48	47	46	45	44	43
BKV	RW 9-27	6105	44	43	42	41	40	40	39	38	37	36	35
BKV	RW 9-27	6110	55	54	53	52	51	51	50	49	48	47	46
BKV	TW A	105	48	47	46	45	44	44	43	42	41	40	39




Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BKV	TW A	108	98	97	96	95	94	94	93	92	91	90	89
BKV	TW A1	110	50	49	48	47	46	46	45	44	43	42	41
BKV	TW A1	111	74	73	72	71	70	69	68	67	66	65	64
BKV	TW A1	112	51	49	48	46	44	43	41	40	38	37	35
BKV	TW A3	120	35	34	33	32	31	31	30	29	28	27	26
BKV	TW A3	125	15	12	10	7	4	2	0	0	0	0	0
BKV	TW A5	130	48	47	46	45	44	44	43	42	41	40	39
BKV	TW A6	135	16	13	11	8	5	3	0	0	0	0	0
BKV	TW A9	140	58	57	56	55	54	54	53	52	51	50	49
BKV	TW B	205	35	34	33	32	31	30	29	28	28	27	26
BKV	TW B	210	60	59	58	56	55	54	52	51	49	47	46
BKV	TW B1	145	61	60	59	58	56	55	54	52	51	49	47
BKV	TW B1	215	54	53	52	51	50	50	49	48	47	46	45
BKV	TW B1	216	53	51	50	48	47	45	43	42	40	39	37
BKV	TW B2	220	33	32	31	30	29	29	28	27	26	25	23
BKV	TW B3	225	56	54	53	52	50	48	47	45	44	42	40
BKV	TW B4	230	56	54	53	52	50	48	47	45	44	42	40



#### 4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA **AC 150/5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements** to determine structural and/or functional conditions at the time of project.

# **Chapter 5**





# Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- **Localized Maintenance and Repair** includes patching and crack sealing.
- **Global Treatments** includes surface seals and rejuvenators (flexible pavements).
- **Major Rehabilitation** includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

## 5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distress pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety (“stopgap”) measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

### Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

### Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.





## 5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2.1** and **Table 5.2.2**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and the **FDOT Airfield Pavement Distress Repair Manual**. Additionally, the **Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements** was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

*Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete*

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	High	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft



Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L & T CR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

*Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete*

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt



Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$6.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$3.00	SqFt

Table 5.2-3 (b) Localized M&amp;R Planning-Level Unit Costs – Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$100.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

\*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



### 5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in **5.2 Localized M&R Policy**. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. **Appendix B** provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to near-term Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3-1** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

*Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level*

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	200	SqFt	\$ 1,190.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	165	SqFt	\$ 490.00
FDOT - JOINT SEAL - PCC	PREVENTIVE	1,110	Ft	\$ 3,060.00
FDOT - SURFACE SEAL	PREVENTIVE	42,185	SqFt	\$ 23,200.00
FDOT - CRACK SEALING - PCC	STOPGAP	16,395	Ft	\$ 69,680.00
FDOT - CRACK SEALING - AC	STOPGAP	14,195	Ft	\$ 42,580.00
FDOT - PATCHING - PCC PARTIAL DEPTH	STOPGAP	42,240	SqFt	\$ 3,041,050.00
FDOT - JOINT SEAL - PCC	STOPGAP	268,680	Ft	\$ 738,860.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	130,860	SqFt	\$ 392,570.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	1,400	SqFt	\$ 8,390.00
FDOT - SURFACE SEAL	STOPGAP	416,080	SqFt	\$ 228,850.00
FDOT - PATCHING - PCC FULL DEPTH	STOPGAP	1,225	SqFt	\$ 122,420.00
FDOT - SLAB REPLACEMENT - PCC	STOPGAP	1,565	SqFt	\$ 46,880.00





The following **Table 5.3-2** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved “End Condition” of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

*Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level*

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
BKV	AP NE	4105	29,444	35	58	\$ 49,100.00
BKV	AP NE	4110	14,592	40	51	\$ 22,340.00
BKV	AP NE	4115	21,610	100	100	\$ -
BKV	AP NE	4117	14,188	31	49	\$ 23,570.00
BKV	AP NE	4120	29,272	31	54	\$ 63,150.00
BKV	AP NE	4123	23,785	100	100	\$ -
BKV	AP NE	4125	23,740	100	100	\$ -
BKV	AP NE	4130	6,146	100	100	\$ -
BKV	AP NE	4135	47,738	74	74	\$ -
BKV	AP NE	4137	11,384	100	100	\$ -
BKV	AP NE	4140	188,863	68	72	\$ 5,690.00
BKV	AP NE	4143	33,176	100	100	\$ -
BKV	AP NE	4145	72,809	100	100	\$ -
BKV	AP NE	4147	7,371	100	100	\$ -
BKV	AP NE	4150	28,017	55	59	\$ 9,070.00
BKV	AP S	4205	3,398	59	76	\$ 2,480.00
BKV	AP S	4210	52,541	61	87	\$ 33,570.00
BKV	AP S	4215	32,595	66	93	\$ 19,120.00
BKV	AP S	4220	28,845	64	93	\$ 16,140.00
BKV	AP S	4225	114,556	90	91	\$ 80.00
BKV	RW 3-21	6205	250,750	43	58	\$ 96,350.00
BKV	RW 3-21	6210	501,500	52	64	\$ 227,560.00
BKV	RW 9-27	6105	350,000	44	61	\$ 905,240.00
BKV	RW 9-27	6110	700,000	55	64	\$ 247,510.00
BKV	TW A	105	636,744	48	63	\$ 2,406,040.00
BKV	TW A	108	11,563	98	100	\$ 3,060.00
BKV	TW A1	110	56,894	50	60	\$ 20,760.00
BKV	TW A1	111	17,870	74	74	\$ -
BKV	TW A1	112	18,154	51	56	\$ 2,790.00
BKV	TW A3	120	10,837	35	61	\$ 64,090.00
BKV	TW A3	125	26,322	15	46	\$ 82,070.00
BKV	TW A5	130	33,046	48	68	\$ 11,340.00
BKV	TW A6	135	31,614	16	50	\$ 86,080.00



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
BKV	TW A9	140	31,973	58	65	\$ 10,240.00
BKV	TW B	205	55,550	35	64	\$ 110,790.00
BKV	TW B	210	118,423	60	76	\$ 74,990.00
BKV	TW B1	145	80,954	61	76	\$ 47,380.00
BKV	TW B1	215	63,745	54	67	\$ 21,040.00
BKV	TW B1	216	45,429	53	60	\$ 24,990.00
BKV	TW B2	220	7,309	33	57	\$ 22,250.00
BKV	TW B3	225	7,309	56	74	\$ 5,980.00
BKV	TW B4	230	6,246	56	75	\$ 4,890.00




The following **Table 5.3-3** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

*Table 5.3-3 Summary of Localized Maintenance*

Work Category	Cost
Preventive	\$ 27,940.00
Stopgap	\$ 4,691,280.00
<b>Planning-Level Localized M&amp;R Needs =</b>	<b>\$ 4,719,220.00</b>

# Chapter 6





# Chapter 6 – Major Rehabilitation Planning

## 6.1 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1-1 and 6.1-2** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

*Figure 6.1-1 Major Rehabilitation Planning Decision Diagram,  $PCI \leq \text{Critical PCI}$*









Figure 6.1-2 Major Rehabilitation Planning Decision Diagram,  $PCI > \text{Critical } PCI$





### 6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The **Critical PCI** concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

1. Develop a pavement performance model and refine a prediction model for the pavements considered.
2. Select a localized maintenance and repair policy to be used in developing a work plan.
3. Apply the selected localized policy to the pavement sections for a range of PCI.
4. Compute the unit cost per area for each PCI range.
5. Plot the cost versus the PCI.
6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

### 6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended **Minimum Service-Level PCI** for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

*Table 6.1.2 FDOT Recommended Minimum Service-Level PCI*

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	60	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)



## 6.2 Major Rehabilitation Policy

### 6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA **AC 150/ 5320-6F "Airport Pavement Design and Evaluation."** It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following **Tables 6.2.1 (a) and (b)** provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average GA Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

*Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete*

Rehabilitation Type	General Aviation (GA) Airport
<b>AC Restoration</b>  <i>Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.</i>  <b>PCI = 41 to 65</b>	<b>75% Mill and Overlay</b> P-101 AC Milling (2") P-603 Bituminous Tack P-401 (HMA) (2")  <b>25% AC Reconstruction</b> P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2")  <i>Excludes any paved shoulder features.</i>
<b>AC Reconstruction</b>  <i>Full-depth asphalt pavement section reconstruction.</i>  <b>PCI = 40 or less</b>	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2")  <i>Excludes any paved shoulder features.</i>



*Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete*

Rehabilitation Type	General Aviation (GA) Airport
<b>PCC Restoration</b>  <i>Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.</i>  <b>PCI = 41 to 65</b>	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (10")  *Select Slabs (25%) **Crack Seal and Limited Patching
<b>PCC Reconstruction</b>  <i>Full-depth rigid pavement section reconstruction.</i>  <b>PCI = 40 or less</b>	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (6") P-501 Rigid PCC (10")

***The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.***

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

### 6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs



provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

*Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type*

Rehabilitation Type	PCI Range	Flexible Asphalt Concrete Cost Per SF	Rigid Portland Cement Concrete Cost per SF
Restoration	41 to 65	\$ 7.00	\$ 10.00
Reconstruction	0 to 40	\$ 9.00	\$ 15.00

*Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.*

## 6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

### 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.





Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BKV	AP NE	4105	AC	29,444	33	AC Reconstruction	\$ 266,000.00
2018	BKV	AP NE	4110	AC	14,592	38	AC Reconstruction	\$ 132,000.00
2018	BKV	AP NE	4117	AC	14,188	29	AC Reconstruction	\$ 128,000.00
2018	BKV	AP NE	4120	AC	29,272	29	AC Reconstruction	\$ 264,000.00
2018	BKV	AP NE	4150	PCC	28,017	54	PCC Restoration	\$ 281,000.00
2018	BKV	AP S	4205	AC	3,398	57	AC Restoration	\$ 24,000.00
2018	BKV	AP S	4210	AC	52,541	59	AC Restoration	\$ 368,000.00
2018	BKV	AP S	4215	AC	32,595	64	AC Restoration	\$ 229,000.00
2018	BKV	AP S	4220	AC	28,845	62	AC Restoration	\$ 202,000.00
2018	BKV	RW 3-21	6205	PCC	250,750	42	PCC Restoration	\$ 3,466,000.00
2018	BKV	RW 3-21	6210	PCC	501,500	51	PCC Restoration	\$ 5,016,000.00
2018	BKV	RW 9-27	6105	PCC	350,000	43	PCC Restoration	\$ 4,663,000.00
2018	BKV	RW 9-27	6110	PCC	700,000	54	PCC Restoration	\$ 7,001,000.00
2018	BKV	TW A	105	PCC	636,744	47	PCC Restoration	\$ 7,209,000.00
2018	BKV	TW A1	110	PCC	56,894	49	PCC Restoration	\$ 588,000.00
2018	BKV	TW A1	112	AC	18,154	49	AC Restoration	\$ 128,000.00
2018	BKV	TW A3	120	PCC	10,837	34	PCC Reconstruction	\$ 163,000.00
2018	BKV	TW A3	125	AC	26,322	12	AC Reconstruction	\$ 237,000.00
2018	BKV	TW A5	130	PCC	33,046	47	PCC Restoration	\$ 375,000.00
2018	BKV	TW A6	135	AC	31,614	13	AC Reconstruction	\$ 285,000.00
2018	BKV	TW A9	140	PCC	31,973	57	PCC Restoration	\$ 320,000.00
2018	BKV	TW B	205	AC	55,550	34	AC Reconstruction	\$ 500,000.00
2018	BKV	TW B	210	AC	118,423	59	AC Restoration	\$ 829,000.00
2018	BKV	TW B1	145	AC	80,954	60	AC Restoration	\$ 567,000.00
2018	BKV	TW B1	215	PCC	63,745	53	PCC Restoration	\$ 638,000.00
2018	BKV	TW B1	216	AC	45,429	51	AC Restoration	\$ 319,000.00
2018	BKV	TW B2	220	AC	7,309	32	AC Reconstruction	\$ 66,000.00
2018	BKV	TW B3	225	AC	7,309	54	AC Restoration	\$ 52,000.00
2018	BKV	TW B4	230	AC	6,246	54	AC Restoration	\$ 44,000.00
2020	BKV	AP NE	4140	AC	188,863	63	AC Restoration	\$ 1,323,000.00
2023	BKV	AP NE	4135	AC	47,738	64	AC Restoration	\$ 335,000.00
2027	BKV	TW A1	111	AAC	17,870	64	AC Restoration	\$ 126,000.00

\*All values have been rounded to the nearest thousand-dollar.

The following **Figure 6.3.1-1** summarizes the section-level major rehabilitation needs for a 10-year period between 2018 and 2027. **Figure 6.3.1-2** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.



Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year








Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit



# **Chapter 7**







# Chapter 7 – Conclusion

## 7.1 Recommendations

### 7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and re-inspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

### 7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2018-2027. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

### 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- ▶ Develop a detailed preventive maintenance program for the airport.
- ▶ Further refine and implement the identified 10-year major rehabilitation needs.
- ▶ Maintain detailed records on pavement maintenance, construction, and inspection.
- ▶ Maintain records on major pavement construction projects (year, scope, cost, and construction documents).





## 7.2 Supporting Documents

### *001 – Airfield Pavement Network Definition Exhibit*

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

### *002 – Airfield Pavement System Inventory Exhibit*

The Airfield Pavement System Inventory Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the **Airport Response Form** provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

### *003 – Airfield Pavement Condition Index Exhibit*

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

### *004 – Airfield Pavement Major Rehabilitation Exhibit*

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

### *Inspection Photograph Documentation*

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation**. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.



## 7.3 Conclusion

---

The FDOT SAPMP Update Phase 1 2016-2017 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars **150/5380-7B “Airport Pavement Management Program (PMP)”** and **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** FDOT’s implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

# Appendix A

## Airfield Pavement Analysis Tables



Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BKV	NE APRON	AP NE	APRON	4105	600	42	29,444	AC	1/1/1975
BKV	NE APRON	AP NE	APRON	4110	290	50	14,592	AC	1/1/1975
BKV	NE APRON	AP NE	APRON	4115	250	75	21,610	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4117	150	75	14,188	AC	1/1/1975
BKV	NE APRON	AP NE	APRON	4120	125	200	29,272	AC	1/1/1964
BKV	NE APRON	AP NE	APRON	4123	100	200	23,785	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4125	260	90	23,740	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4130	25.5	200	6,146	APC	1/1/2015
BKV	NE APRON	AP NE	APRON	4135	500	95	47,738	AC	1/1/1983
BKV	NE APRON	AP NE	APRON	4137	100	95	11,384	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4140	925	200	188,863	AC	1/1/1991
BKV	NE APRON	AP NE	APRON	4143	150	200	33,176	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4145	600	120	72,809	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4147	35	200	7,371	AAC	1/1/2015
BKV	NE APRON	AP NE	APRON	4150	148	200	28,017	PCC	1/1/1991
BKV	SOUTH APRON	AP S	APRON	4205	90	35	3,398	AC	1/1/1991
BKV	SOUTH APRON	AP S	APRON	4210	453	112	52,541	AC	12/25/1999
BKV	SOUTH APRON	AP S	APRON	4215	450	65	32,595	AC	12/25/1999
BKV	SOUTH APRON	AP S	APRON	4220	425	65	28,845	AC	12/25/1999
BKV	SOUTH APRON	AP S	APRON	4225	1700	65	114,556	AC	1/1/2009
BKV	RUNWAY 3-21	RW 3-21	RUNWAY	6205	10000	25	250,750	PCC	1/1/1942
BKV	RUNWAY 3-21	RW 3-21	RUNWAY	6210	5000	100	501,500	PCC	1/1/1942
BKV	RUNWAY 9-27	RW 9-27	RUNWAY	6105	14000	25	350,000	PCC	1/1/1942
BKV	RUNWAY 9-27	RW 9-27	RUNWAY	6110	7000	100	700,000	PCC	1/1/1942
BKV	TAXIWAY A	TW A	TAXIWAY	105	8400	75	636,744	PCC	1/1/1942
BKV	TAXIWAY A	TW A	TAXIWAY	108	110	100	11,563	PCC	1/1/2013
BKV	TAXIWAY A1	TW A1	TAXIWAY	110	750	75	56,894	PCC	1/1/1942
BKV	TAXIWAY A1	TW A1	TAXIWAY	111	445	40	17,870	AAC	1/1/1991
BKV	TAXIWAY A1	TW A1	TAXIWAY	112	450	40	18,154	AC	1/1/1964
BKV	TAXIWAY A3	TW A3	TAXIWAY	120	413	25	10,837	PCC	1/1/1942
BKV	TAXIWAY A3	TW A3	TAXIWAY	125	400	53	26,322	AC	1/1/1986
BKV	TAXIWAY A5	TW A5	TAXIWAY	130	430	75	33,046	PCC	1/1/1942
BKV	TAXIWAY A6	TW A6	TAXIWAY	135	500	53	31,614	AC	1/1/1986
BKV	TAXIWAY A9	TW A9	TAXIWAY	140	420	75	31,973	PCC	1/1/1942
BKV	TAXIWAY B	TW B	TAXIWAY	205	1580	35	55,550	AC	1/1/1990
BKV	TAXIWAY B	TW B	TAXIWAY	210	3375	35	118,423	AC	1/1/1991





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BKV	TAXIWAY B1	TW B1	TAXIWAY	145	1000	76	80,954	AC	1/1/1998
BKV	TAXIWAY B1	TW B1	TAXIWAY	215	810	75	63,745	PCC	1/1/1942
BKV	TAXIWAY B1	TW B1	TAXIWAY	216	885	50	45,429	AC	1/1/1991
BKV	TAXIWAY B2	TW B2	TAXIWAY	220	150	35	7,309	AC	1/1/1990
BKV	TAXIWAY B3	TW B3	TAXIWAY	225	150	35	7,309	AC	1/1/1991
BKV	TAXIWAY B4	TW B4	TAXIWAY	230	150	35	6,246	AC	1/1/1991





*Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level*

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BKV	RUNWAY 9-27	RUNWAY	6105	350,000	44	Poor
BKV	RUNWAY 9-27	RUNWAY	6110	700,000	55	Poor
BKV	RUNWAY 3-21	RUNWAY	6205	250,750	43	Poor
BKV	RUNWAY 3-21	RUNWAY	6210	501,500	52	Poor
BKV	TAXIWAY A	TAXIWAY	105	636,744	48	Poor
BKV	TAXIWAY A	TAXIWAY	108	11,563	98	Good
BKV	TAXIWAY A1	TAXIWAY	110	56,894	50	Poor
BKV	TAXIWAY A1	TAXIWAY	111	17,870	74	Satisfactory
BKV	TAXIWAY A1	TAXIWAY	112	18,154	51	Poor
BKV	TAXIWAY A3	TAXIWAY	120	10,837	35	Very Poor
BKV	TAXIWAY A3	TAXIWAY	125	26,322	15	Serious
BKV	TAXIWAY A5	TAXIWAY	130	33,046	48	Poor
BKV	TAXIWAY A6	TAXIWAY	135	31,614	16	Serious
BKV	TAXIWAY A9	TAXIWAY	140	31,973	58	Fair
BKV	TAXIWAY B	TAXIWAY	205	55,550	35	Very Poor
BKV	TAXIWAY B	TAXIWAY	210	118,423	60	Fair
BKV	TAXIWAY B1	TAXIWAY	145	80,954	61	Fair
BKV	TAXIWAY B1	TAXIWAY	215	63,745	54	Poor
BKV	TAXIWAY B1	TAXIWAY	216	45,429	53	Poor
BKV	TAXIWAY B2	TAXIWAY	220	7,309	33	Very Poor
BKV	TAXIWAY B3	TAXIWAY	225	7,309	56	Fair
BKV	TAXIWAY B4	TAXIWAY	230	6,246	56	Fair
BKV	NE APRON	APRON	4105	29,444	35	Very Poor
BKV	NE APRON	APRON	4110	14,592	40	Very Poor
BKV	NE APRON	APRON	4115	21,610	100	Good
BKV	NE APRON	APRON	4117	14,188	31	Very Poor
BKV	NE APRON	APRON	4120	29,272	31	Very Poor
BKV	NE APRON	APRON	4123	23,785	100	Good
BKV	NE APRON	APRON	4125	23,740	100	Good
BKV	NE APRON	APRON	4130	6,146	100	Good
BKV	NE APRON	APRON	4135	47,738	74	Satisfactory
BKV	NE APRON	APRON	4137	11,384	100	Good
BKV	NE APRON	APRON	4140	188,863	68	Fair
BKV	NE APRON	APRON	4143	33,176	100	Good
BKV	NE APRON	APRON	4145	72,809	100	Good
BKV	NE APRON	APRON	4147	7,371	100	Good
BKV	NE APRON	APRON	4150	28,017	55	Poor
BKV	SOUTH APRON	APRON	4205	3,398	59	Fair



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BKV	SOUTH APRON	APRON	4210	52,541	61	Fair
BKV	SOUTH APRON	APRON	4215	32,595	66	Fair
BKV	SOUTH APRON	APRON	4220	28,845	64	Fair
BKV	SOUTH APRON	APRON	4225	114,556	90	Good



Table A-3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BKV	AP NE	4105	35	33	32	30	29	27	25	24	22	21	19
BKV	AP NE	4110	40	38	37	35	34	32	30	29	27	26	24
BKV	AP NE	4115	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4117	31	29	28	26	25	23	21	20	18	17	15
BKV	AP NE	4120	31	29	28	26	25	23	21	20	18	17	15
BKV	AP NE	4123	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4125	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4130	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4135	74	72	71	69	68	66	64	63	61	60	58
BKV	AP NE	4137	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4140	68	66	65	63	62	60	58	57	55	54	52
BKV	AP NE	4143	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4145	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4147	100	84	82	81	79	78	76	74	72	69	67
BKV	AP NE	4150	55	54	53	52	51	50	49	48	47	47	46
BKV	AP S	4205	59	57	56	54	53	51	49	48	46	45	43
BKV	AP S	4210	61	59	58	56	55	53	51	50	48	47	45
BKV	AP S	4215	66	64	63	61	60	58	56	55	53	52	50
BKV	AP S	4220	64	62	61	59	58	56	54	53	51	50	48
BKV	AP S	4225	90	88	87	85	84	82	80	79	77	76	74
BKV	RW 3-21	6205	43	42	41	40	39	39	38	37	36	35	34
BKV	RW 3-21	6210	52	51	50	49	48	48	47	46	45	44	43
BKV	RW 9-27	6105	44	43	42	41	40	40	39	38	37	36	35
BKV	RW 9-27	6110	55	54	53	52	51	51	50	49	48	47	46
BKV	TW A	105	48	47	46	45	44	44	43	42	41	40	39
BKV	TW A	108	98	97	96	95	94	94	93	92	91	90	89
BKV	TW A1	110	50	49	48	47	46	46	45	44	43	42	41
BKV	TW A1	111	74	73	72	71	70	69	68	67	66	65	64
BKV	TW A1	112	51	49	48	46	44	43	41	40	38	37	35
BKV	TW A3	120	35	34	33	32	31	31	30	29	28	27	26
BKV	TW A3	125	15	12	10	7	4	2	0	0	0	0	0
BKV	TW A5	130	48	47	46	45	44	44	43	42	41	40	39
BKV	TW A6	135	16	13	11	8	5	3	0	0	0	0	0
BKV	TW A9	140	58	57	56	55	54	54	53	52	51	50	49
BKV	TW B	205	35	34	33	32	31	30	29	28	28	27	26
BKV	TW B	210	60	59	58	56	55	54	52	51	49	47	46
BKV	TW B1	145	61	60	59	58	56	55	54	52	51	49	47



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BKV	TW B1	215	54	53	52	51	50	50	49	48	47	46	45
BKV	TW B1	216	53	51	50	48	47	45	43	42	40	39	37
BKV	TW B2	220	33	32	31	30	29	29	28	27	26	25	23
BKV	TW B3	225	56	54	53	52	50	48	47	45	44	42	40
BKV	TW B4	230	56	54	53	52	50	48	47	45	44	42	40

8/1/2017

**Work History Report**

Page 1 of 9

*Pavement Database: FDOT*

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4105 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1975 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 600.00 (Ft) <b>Width:</b> 42.00 (Ft) <b>True Area:</b> 29,444.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1975	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ON 6" P-211 (ESTIMATE 1975)
1/1/1975	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4110 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1975 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 290.00 (Ft) <b>Width:</b> 50.00 (Ft) <b>True Area:</b> 14,592.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1975	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS
1/1/1975	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ON 6" P-211 (ESTIMATE 1975)

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4115 <b>Surface:</b> AAC <b>L.C.D.:</b> 1/1/2015 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 250.00 (Ft) <b>Width:</b> 75.00 (Ft) <b>True Area:</b> 21,610.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ML-OV	MILL and OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY
1/1/1975	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS
1/1/1975	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ON 6" P-211 (ESTIMATE 1975 CONSTRUCTION)

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4117 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1975 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 150.00 (Ft) <b>Width:</b> 75.00 (Ft) <b>True Area:</b> 14,188.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1975	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS
1/1/1975	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ON 6" P-211 (ESTIMATE 1975 CONSTRUCTION)

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4120 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1964 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 125.00 (Ft) <b>Width:</b> 200.00 (Ft) <b>True Area:</b> 29,272.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1964	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS
1/1/1964	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1964: 2" P-401 ON 6" P-211



8/1/2017

## Work History Report

Page 2 of 9

Pavement Database: FDOT

<b>Network:</b> BROOKSVILLE - TA		<b>Branch:</b> AP NE		NE APRON		<b>Section:</b> 4123	<b>Surface:</b> AAC
<b>L.C.D.:</b> 1/1/2015	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 100.00 (Ft)	<b>Width:</b> 200.00 (Ft)	<b>True Area:</b> 23,785.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ML-OV	MILL and OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY	
1/1/1964	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1964: 2" P-401 ON 6" P-211	
1/1/1964	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS	

<b>Network:</b> BROOKSVILLE - TA		<b>Branch:</b> AP NE		NE APRON		<b>Section:</b> 4125	<b>Surface:</b> AAC
<b>L.C.D.:</b> 1/1/2015	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 260.00 (Ft)	<b>Width:</b> 90.00 (Ft)	<b>True Area:</b> 23,740.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY	
1/1/1975	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS	
1/1/1975	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1975 AC OVERLAY	
1/1/1964	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1964: 2" P-401 ON 6" P-211	

<b>Network:</b> BROOKSVILLE - TA		<b>Branch:</b> AP NE		NE APRON		<b>Section:</b> 4130	<b>Surface:</b> APC
<b>L.C.D.:</b> 1/1/2015	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 25.50 (Ft)	<b>Width:</b> 200.00 (Ft)	<b>True Area:</b> 6,146.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	8" PCC PAVEMENT (ESTIMATE 1942 CONSTRUCTION)	
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS	

<b>Network:</b> BROOKSVILLE - TA		<b>Branch:</b> AP NE		NE APRON		<b>Section:</b> 4135	<b>Surface:</b> AC
<b>L.C.D.:</b> 1/1/1983	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 500.00 (Ft)	<b>Width:</b> 95.00 (Ft)	<b>True Area:</b> 47,738.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ST-SS	Surface Treatment - Slurry Seal	3,819.04	0.00	<input type="checkbox"/>	Estimated rehab based on response from	
1/1/1983	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983: 2" AC TYPE S1 ON 6" P-211	

<b>Network:</b> BROOKSVILLE - TA		<b>Branch:</b> AP NE		NE APRON		<b>Section:</b> 4137	<b>Surface:</b> AAC
<b>L.C.D.:</b> 1/1/2015	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 100.00 (Ft)	<b>Width:</b> 95.00 (Ft)	<b>True Area:</b> 11,384.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ML-OV	MILL and OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY	
1/1/1983	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983: 2" AC TYPE S1 ON 6" P-211	

8/1/2017

## Work History Report

Page 3 of 9

Pavement Database: FDOT

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4140 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1991 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 925.00 (Ft) <b>Width:</b> 200.00 (Ft) <b>True Area:</b> 188,863.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ST-SS	Surface Treatment - Slurry Seal	15,109.04	0.00	<input type="checkbox"/>	Estimated rehab date based on response
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-MS
1/1/1991	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1991: 2" AC ON 6" LIMEROCK

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4143 <b>Surface:</b> AAC <b>L.C.D.:</b> 1/1/2015 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 150.00 (Ft) <b>Width:</b> 200.00 (Ft) <b>True Area:</b> 33,176.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ML-OV	MILL and OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY
1/1/1991	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1991: 2" AC ON 6" LIMEROCK
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-MS

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4145 <b>Surface:</b> AAC <b>L.C.D.:</b> 1/1/2015 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 600.00 (Ft) <b>Width:</b> 120.00 (Ft) <b>True Area:</b> 72,809.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ML-OV	MILL and OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991: 4" AC ON 8" LIMEROCK
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-MS

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4147 <b>Surface:</b> AAC <b>L.C.D.:</b> 1/1/2015 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 35.00 (Ft) <b>Width:</b> 200.00 (Ft) <b>True Area:</b> 7,371.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401 ASPHALT OVERLAY
1/1/1989	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1989 AC OVERLAY ON AC

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> AP NE    NE APRON <b>Section:</b> 4150 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1991 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 148.00 (Ft) <b>Width:</b> 200.00 (Ft) <b>True Area:</b> 28,017.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	15.00	<input checked="" type="checkbox"/>	1991: 15" PORTLAND CEMENT CONCRETE ON 10" LIMEROCK
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-MS

8/1/2017

## Work History Report

Page 4 of 9

Pavement Database: FDOT

Network: BROOKSVILLE - TA		Branch: AP S	SOUTH APRON		Section: 4205	Surface: AC
L.C.D.: 1/1/1991	Use: APRON	Rank: P	Length: 90.00 (Ft)	Width: 35.00 (Ft)	True Area: 3,398.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SM
1/1/1991	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1991: 2" AC ON 6" LIMEROCK

Network: BROOKSVILLE - TA		Branch: AP S	SOUTH APRON		Section: 4210	Surface: AC
L.C.D.: 12/25/199	Use: APRON	Rank: P	Length: 453.00 (Ft)	Width: 112.00 (Ft)	True Area: 52,541.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	Estimated rehab date based on response
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BROOKSVILLE - TA		Branch: AP S	SOUTH APRON		Section: 4215	Surface: AC
L.C.D.: 12/25/199	Use: APRON	Rank: P	Length: 450.00 (Ft)	Width: 65.00 (Ft)	True Area: 32,595.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	Estimated rehab date based on response
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BROOKSVILLE - TA		Branch: AP S	SOUTH APRON		Section: 4220	Surface: AC
L.C.D.: 12/25/199	Use: APRON	Rank: P	Length: 425.00 (Ft)	Width: 65.00 (Ft)	True Area: 28,845.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	Estimated rehab date based on response
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BROOKSVILLE - TA		Branch: AP S	SOUTH APRON		Section: 4225	Surface: AC
L.C.D.: 1/1/2009	Use: APRON	Rank: P	Length: 1,700.00 (Ft)	Width: 65.00 (Ft)	True Area: 114,556.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BROOKSVILLE - TA		Branch: RW 3-21	RUNWAY 3-21		Section: 6205	Surface: PCC
L.C.D.: 1/1/1942	Use: RUNWAY	Rank: S	Length: 10,000.00 (Ft)	Width: 25.00 (Ft)	True Area: 250,750.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
3/1/2011	JS-LC	JT SEAL DMG	0.00	0.00	<input type="checkbox"/>	
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942 8" PCC PAVEMENT

8/1/2017

## Work History Report

Page 5 of 9

Pavement Database: FDOT

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> RW 3-21    RUNWAY 3-21 <b>Section:</b> 6210 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> RUNWAY <b>Rank:</b> S <b>Length:</b> 5,000.00 (Ft) <b>Width:</b> 100.00 (Ft) <b>True Area:</b> 501,500.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
3/1/2011	JS-LC	JT SEAL DMG	0.00	0.00	<input type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> RW 9-27    RUNWAY 9-27 <b>Section:</b> 6105 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> RUNWAY <b>Rank:</b> P <b>Length:</b> 14,000.00 (Ft) <b>Width:</b> 25.00 (Ft) <b>True Area:</b> 350,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
3/1/2011	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	0.00	0.00	<input type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> RW 9-27    RUNWAY 9-27 <b>Section:</b> 6110 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> RUNWAY <b>Rank:</b> P <b>Length:</b> 7,000.00 (Ft) <b>Width:</b> 100.00 (Ft) <b>True Area:</b> 700,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
3/1/2011	JS-LC	JT SEAL DMG	0.00	0.00	<input type="checkbox"/>	SOIL: SP & ML
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A    TAXIWAY A <b>Section:</b> 105 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 8,400.00 (Ft) <b>Width:</b> 75.00 (Ft) <b>True Area:</b> 636,744.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A    TAXIWAY A <b>Section:</b> 108 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/2013 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 110.00 (Ft) <b>Width:</b> 100.00 (Ft) <b>True Area:</b> 11,563.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	

8/1/2017

## Work History Report

Page 6 of 9

Pavement Database: FDOT

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A1    TAXIWAY A1 <b>Section:</b> 110 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 750.00 (Ft) <b>Width:</b> 75.00 (Ft) <b>True Area:</b> 56,894.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A1    TAXIWAY A1 <b>Section:</b> 111 <b>Surface:</b> AAC <b>L.C.D.:</b> 1/1/1991 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 445.00 (Ft) <b>Width:</b> 40.00 (Ft) <b>True Area:</b> 17,870.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	Estimated rehab based on response from
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & MS
1/1/1991	IMPORT ED	OVERLAY	0.00	1.00	<input checked="" type="checkbox"/>	1991: 1" P-401 OVERLAY
1/1/1964	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1964: 2" P-401 ON 6" P-211

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A1    TAXIWAY A1 <b>Section:</b> 112 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1964 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 450.00 (Ft) <b>Width:</b> 40.00 (Ft) <b>True Area:</b> 18,154.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	Estimated rehab based on response from
1/1/1964	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1964: 2" P-401 ON 6" P-211

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A3    TAXIWAY A3 <b>Section:</b> 120 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 413.00 (Ft) <b>Width:</b> 25.00 (Ft) <b>True Area:</b> 10,837.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A3    TAXIWAY A3 <b>Section:</b> 125 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1986 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 400.00 (Ft) <b>Width:</b> 53.00 (Ft) <b>True Area:</b> 26,322.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1986	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML
1/1/1986	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1986: 4" P-401 ON 6" P-211



8/1/2017

## Work History Report

Page 7 of 9

Pavement Database: FDOT

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A5    TAXIWAY A5 <b>Section:</b> 130 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 430.00 (Ft) <b>Width:</b> 75.00 (Ft) <b>True Area:</b> 33,046.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A6    TAXIWAY A6 <b>Section:</b> 135 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1986 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 500.00 (Ft) <b>Width:</b> 53.00 (Ft) <b>True Area:</b> 31,614.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1986	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1986: 4" P-401 ON 6" P-211
1/1/1986	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW A9    TAXIWAY A9 <b>Section:</b> 140 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 420.00 (Ft) <b>Width:</b> 75.00 (Ft) <b>True Area:</b> 31,973.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B1    TAXIWAY B1 <b>Section:</b> 145 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1998 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 1,000.00 (Ft) <b>Width:</b> 76.00 (Ft) <b>True Area:</b> 80,954.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1998: AC PAVEMENT

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B1    TAXIWAY B1 <b>Section:</b> 215 <b>Surface:</b> PCC <b>L.C.D.:</b> 1/1/1942 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 810.00 (Ft) <b>Width:</b> 75.00 (Ft) <b>True Area:</b> 63,745.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP & ML

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B1    TAXIWAY B1 <b>Section:</b> 216 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1991 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 885.00 (Ft) <b>Width:</b> 50.00 (Ft) <b>True Area:</b> 45,429.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP / ML
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991: 4" AC ON 14" LIMEROCK

8/1/2017

**Work History Report**

Page 8 of 9

*Pavement Database: FDOT*

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B    TAXIWAY B <b>Section:</b> 205 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1990 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 1,580.00 (Ft) <b>Width:</b> 35.00 (Ft) <b>True Area:</b> 55,550.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1990	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" AC ON 6" LIMEROCK
1/1/1990	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SM

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B    TAXIWAY B <b>Section:</b> 210 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1991 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 3,375.00 (Ft) <b>Width:</b> 35.00 (Ft) <b>True Area:</b> 118,423.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SM
1/1/1991	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1991: 2" AC ON 6" LIMEROCK

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B2    TAXIWAY B2 <b>Section:</b> 220 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1990 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 150.00 (Ft) <b>Width:</b> 35.00 (Ft) <b>True Area:</b> 7,309.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1990	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" AC ON 6" LIMEROCK
1/1/1990	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SM

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B3    TAXIWAY B3 <b>Section:</b> 225 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1991 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 150.00 (Ft) <b>Width:</b> 35.00 (Ft) <b>True Area:</b> 7,309.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SM
1/1/1991	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1991: 2" AC ON 6" LIMEROCK

<b>Network:</b> BROOKSVILLE - TA <b>Branch:</b> TW B4    TAXIWAY B4 <b>Section:</b> 230 <b>Surface:</b> AC <b>L.C.D.:</b> 1/1/1991 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 150.00 (Ft) <b>Width:</b> 35.00 (Ft) <b>True Area:</b> 6,246.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SM
1/1/1991	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1991: 2" AC ON 6" LIMEROCK

**Work History Report***Pavement Database: FDOT***Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	37	3,606,202.00	4.24	3.30
FDOT - JOINT SEAL - PCC	1	350,000.00	0.00	0.00
JT SEAL DMG	3	1,452,250.00	0.00	0.00
MILL and OVERLAY	8	200,021.00	1.25	0.97
New Construction - Initial	4	228,537.00	0.00	0.00
New Construction - PCC	1	11,563.00	0.00	0.00
OVERLAY	36	3,541,333.00	0.03	0.16
Surface Treatment - Slurry Seal	7	386,606.00	0.00	0.00

8/1/2017

**Branch Condition Report**

Page 1 of 2

*Pavement Database: FDOT*

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP NE	15	4,258.50	136.13	552,135.00	APRON	75.60	28.45	74.04
AP S	5	3,118.00	68.40	231,935.00	APRON	68.00	11.26	76.37
RW 3-21	2	15,000.00	62.50	752,250.00	RUNWAY	47.50	4.50	49.00
RW 9-27	2	21,000.00	62.50	1,050,000.00	RUNWAY	49.50	5.50	51.33
TW A	2	8,510.00	87.50	648,307.00	TAXIWAY	73.00	25.00	48.89
TW A1	3	1,645.00	51.67	92,918.00	TAXIWAY	58.33	11.09	54.81
TW A3	2	813.00	39.00	37,159.00	TAXIWAY	25.00	10.00	20.83
TW A5	1	430.00	75.00	33,046.00	TAXIWAY	48.00	0.00	48.00
TW A6	1	500.00	53.00	31,614.00	TAXIWAY	16.00	0.00	16.00
TW A9	1	420.00	75.00	31,973.00	TAXIWAY	58.00	0.00	58.00
TW B	2	4,955.00	35.00	173,973.00	TAXIWAY	47.50	12.50	52.02
TW B1	3	2,695.00	67.00	190,128.00	TAXIWAY	56.00	3.56	56.74
TW B2	1	150.00	35.00	7,309.00	TAXIWAY	33.00	0.00	33.00
TW B3	1	150.00	35.00	7,309.00	TAXIWAY	56.00	0.00	56.00
TW B4	1	150.00	35.00	6,246.00	TAXIWAY	56.00	0.00	56.00

8/1/2017

**Branch Condition Report**

Page 2 of 2

*Pavement Database: FDOT*

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	20	784070.000239672	73.70	25.49	74.73
RUNWAY	4	1802250.00032936	48.50	5.12	50.36
TAXIWAY	18	1259982.00038515	50.06	18.84	49.48
ALL	42	3846302.00095418	61.17	24.64	55.04



Pavement Database: FDOT

NetworkId: BKV

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP NE	4105	1/1/1975	AC	APRON	P	0	29,444.00	3/29/2017	42	35
AP NE	4110	1/1/1975	AC	APRON	P	0	14,592.00	3/29/2017	42	40
AP NE	4115	1/1/2015	AAC	APRON	P	0	21,610.00	1/1/2015	0	100
AP NE	4117	1/1/1975	AC	APRON	P	0	14,188.00	3/29/2017	42	31
AP NE	4120	1/1/1964	AC	APRON	P	0	29,272.00	3/29/2017	53	31
AP NE	4123	1/1/2015	AAC	APRON	P	0	23,785.00	1/1/2015	0	100
AP NE	4125	1/1/2015	AAC	APRON	P	0	23,740.00	1/1/2015	0	100
AP NE	4130	1/1/2015	APC	APRON	P	0	6,146.00	1/1/2015	0	100
AP NE	4135	1/1/1983	AC	APRON	P	0	47,738.00	3/29/2017	34	74
AP NE	4137	1/1/2015	AAC	APRON	P	0	11,384.00	1/1/2015	0	100
AP NE	4140	1/1/1991	AC	APRON	P	0	188,863.00	3/29/2017	26	68
AP NE	4143	1/1/2015	AAC	APRON	P	0	33,176.00	1/1/2015	0	100
AP NE	4145	1/1/2015	AAC	APRON	P	0	72,809.00	1/1/2015	0	100
AP NE	4147	1/1/2015	AAC	APRON	P	0	7,371.00	1/1/2015	0	100
AP NE	4150	1/1/1991	PCC	APRON	P	0	28,017.00	3/29/2017	26	55
AP S	4205	1/1/1991	AC	APRON	P	0	3,398.00	3/29/2017	26	59
AP S	4210	12/25/1999	AC	APRON	P	0	52,541.00	3/29/2017	18	61
AP S	4215	12/25/1999	AC	APRON	P	0	32,595.00	3/29/2017	18	66
AP S	4220	12/25/1999	AC	APRON	P	0	28,845.00	3/29/2017	18	64
AP S	4225	1/1/2009	AC	APRON	P	0	114,556.00	3/29/2017	8	90
RW 3-21	6205	1/1/1942	PCC	RUNWAY	S	0	250,750.00	3/29/2017	75	43
RW 3-21	6210	1/1/1942	PCC	RUNWAY	S	0	501,500.00	3/29/2017	75	52
RW 9-27	6105	1/1/1942	PCC	RUNWAY	P	0	350,000.00	3/29/2017	75	44
RW 9-27	6110	1/1/1942	PCC	RUNWAY	P	0	700,000.00	3/29/2017	75	55
TW A	105	1/1/1942	PCC	TAXIWAY	P	0	636,744.00	3/29/2017	75	48
TW A	108	1/1/2013	PCC	TAXIWAY	P	0	11,563.00	3/29/2017	4	98
TW A1	110	1/1/1942	PCC	TAXIWAY	P	0	56,894.00	3/29/2017	75	50
TW A1	111	1/1/1991	AAC	TAXIWAY	P	0	17,870.00	3/29/2017	26	74
TW A1	112	1/1/1964	AC	TAXIWAY	P	0	18,154.00	3/29/2017	53	51
TW A3	120	1/1/1942	PCC	TAXIWAY	P	0	10,837.00	3/29/2017	75	35
TW A3	125	1/1/1986	AC	TAXIWAY	P	0	26,322.00	3/29/2017	31	15
TW A5	130	1/1/1942	PCC	TAXIWAY	P	0	33,046.00	3/29/2017	75	48
TW A6	135	1/1/1986	AC	TAXIWAY	P	0	31,614.00	3/29/2017	31	16
TW A9	140	1/1/1942	PCC	TAXIWAY	P	0	31,973.00	3/29/2017	75	58
TW B	205	1/1/1990	AC	TAXIWAY	P	0	55,550.00	3/29/2017	27	35
TW B	210	1/1/1991	AC	TAXIWAY	P	0	118,423.00	3/29/2017	26	60
TW B1	145	1/1/1998	AC	TAXIWAY	P	0	80,954.00	3/29/2017	19	61
TW B1	215	1/1/1942	PCC	TAXIWAY	P	0	63,745.00	3/29/2017	75	54
TW B1	216	1/1/1991	AC	TAXIWAY	P	0	45,429.00	3/29/2017	26	53
TW B2	220	1/1/1990	AC	TAXIWAY	P	0	7,309.00	3/29/2017	27	33
TW B3	225	1/1/1991	AC	TAXIWAY	P	0	7,309.00	3/29/2017	26	56
TW B4	230	1/1/1991	AC	TAXIWAY	P	0	6,246.00	3/29/2017	26	56

8/1/2017

**Section Condition Report (Summary)**

Page 2 of 2

*Pavement Database: FDOT*

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		200,021.00	8	100.00	0.00	100.00
03-05	4	11,563.00	1	98.00	0.00	98.00
06-10	8	114,556.00	1	90.00	0.00	90.00
16-20	18	194,935.00	4	63.00	2.12	62.28
26-30	26	478,414.00	10	54.90	12.09	59.29
31-35	32	105,674.00	3	35.00	27.58	41.95
41-50	42	58,224.00	3	35.33	3.68	35.28
ALL	34	3,846,302.00	42	61.17	24.64	55.04
Over 50	71	2,682,915.00	12	47.42	7.69	49.67

# Appendix B

Airfield Pavement Localized Maintenance and Repair and  
Major Rehabilitation



Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BKV	AP NE	4105	43	BLOCK CR	Medium	4416.65	SqFt	15.0%	FDOT - CRACK SEALING - AC	1346.13	Ft	\$ 3.00	\$ 4,040.00
BKV	AP NE	4105	52	RAVELING	Low	17666.38	SqFt	60.0%	FDOT - SURFACE SEAL	17666.81	SqFt	\$ 0.55	\$ 9,720.00
BKV	AP NE	4105	52	RAVELING	Medium	11777.55	SqFt	40.0%	FDOT - PATCHING - AC PARTIAL DEPTH	11777.87	SqFt	\$ 3.00	\$ 35,340.00
BKV	AP NE	4110	52	RAVELING	Low	8755.15	SqFt	60.0%	FDOT - SURFACE SEAL	8755.36	SqFt	\$ 0.55	\$ 4,820.00
BKV	AP NE	4110	52	RAVELING	Medium	5836.84	SqFt	40.0%	FDOT - PATCHING - AC PARTIAL DEPTH	5837.27	SqFt	\$ 3.00	\$ 17,520.00
BKV	AP NE	4117	41	ALLIGATOR CR	Low	203.33	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	264.79	SqFt	\$ 6.00	\$ 1,590.00
BKV	AP NE	4117	45	DEPRESSION	Low	18.84	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	39.83	SqFt	\$ 6.00	\$ 250.00
BKV	AP NE	4117	52	RAVELING	Low	8511.35	SqFt	60.0%	FDOT - SURFACE SEAL	8511.02	SqFt	\$ 0.55	\$ 4,690.00
BKV	AP NE	4117	52	RAVELING	Medium	5676.67	SqFt	40.0%	FDOT - PATCHING - AC PARTIAL DEPTH	5676.89	SqFt	\$ 3.00	\$ 17,040.00
BKV	AP NE	4120	43	BLOCK CR	Medium	4394.37	SqFt	15.0%	FDOT - CRACK SEALING - AC	1339.57	Ft	\$ 3.00	\$ 4,020.00
BKV	AP NE	4120	52	RAVELING	Low	11708.77	SqFt	40.0%	FDOT - SURFACE SEAL	11708.98	SqFt	\$ 0.55	\$ 6,440.00
BKV	AP NE	4120	52	RAVELING	Medium	17563.15	SqFt	60.0%	FDOT - PATCHING - AC PARTIAL DEPTH	17563.47	SqFt	\$ 3.00	\$ 52,690.00
BKV	AP NE	4140	49	OIL SPILLAGE	N/A	113.34	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	160.38	SqFt	\$ 3.00	\$ 490.00
BKV	AP NE	4140	52	RAVELING	Low	9443.18	SqFt	5.0%	FDOT - SURFACE SEAL	9443.18	SqFt	\$ 0.55	\$ 5,200.00
BKV	AP NE	4150	65	JT SEAL DMG	Low	46	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2020.01	Ft	\$ 2.75	\$ 5,560.00
BKV	AP NE	4150	72	SHAT. SLAB	Low	5.11	Slabs	11.1%	FDOT - CRACK SEALING - PCC	255.58	Ft	\$ 4.25	\$ 1,090.00
BKV	AP NE	4150	74	JOINT SPALL	Low	5.11	Slabs	11.1%	FDOT - CRACK SEALING - PCC	8.53	Ft	\$ 4.25	\$ 40.00
BKV	AP NE	4150	74	JOINT SPALL	Medium	5.11	Slabs	11.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	33.37	SqFt	\$ 72.00	\$ 2,380.00
BKV	AP S	4205	45	DEPRESSION	Low	41.01	SqFt	1.2%	FDOT - PATCHING - AC FULL DEPTH	71.04	SqFt	\$ 6.00	\$ 430.00
BKV	AP S	4205	52	RAVELING	Low	3327.99	SqFt	97.9%	FDOT - SURFACE SEAL	3328.2	SqFt	\$ 0.55	\$ 1,840.00
BKV	AP S	4205	52	RAVELING	Medium	69.97	SqFt	2.1%	FDOT - PATCHING - AC PARTIAL DEPTH	69.97	SqFt	\$ 3.00	\$ 210.00
BKV	AP S	4210	45	DEPRESSION	Low	668.65	SqFt	1.3%	FDOT - PATCHING - AC FULL DEPTH	777.15	SqFt	\$ 6.00	\$ 4,670.00
BKV	AP S	4210	52	RAVELING	Low	52541.01	SqFt	100.0%	FDOT - SURFACE SEAL	52540.8	SqFt	\$ 0.55	\$ 28,900.00
BKV	AP S	4215	45	DEPRESSION	Low	144.88	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	196.98	SqFt	\$ 6.00	\$ 1,190.00
BKV	AP S	4215	52	RAVELING	Low	32594.95	SqFt	100.0%	FDOT - SURFACE SEAL	32595.27	SqFt	\$ 0.55	\$ 17,930.00
BKV	AP S	4220	52	RAVELING	Low	28736.84	SqFt	99.6%	FDOT - SURFACE SEAL	28736.41	SqFt	\$ 0.55	\$ 15,810.00
BKV	AP S	4220	52	RAVELING	Medium	108.18	SqFt	0.4%	FDOT - PATCHING - AC PARTIAL DEPTH	107.64	SqFt	\$ 3.00	\$ 330.00
BKV	AP S	4225	52	RAVELING	Low	143.16	SqFt	0.1%	FDOT - SURFACE SEAL	143.16	SqFt	\$ 0.55	\$ 80.00
BKV	RW 3-21	6205	63	LINEAR CR	Medium	105	Slabs	13.1%	FDOT - CRACK SEALING - PCC	1968.83	Ft	\$ 4.25	\$ 8,370.00
BKV	RW 3-21	6205	65	JT SEAL DMG	Low	800	Slabs	100.0%	FDOT - JOINT SEAL - PCC	19975.07	Ft	\$ 2.75	\$ 54,940.00
BKV	RW 3-21	6205	66	SMALL PATCH	Medium	20	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	53.82	SqFt	\$ 72.00	\$ 3,880.00
BKV	RW 3-21	6205	72	SHAT. SLAB	Low	5	Slabs	0.6%	FDOT - CRACK SEALING - PCC	187.66	Ft	\$ 4.25	\$ 800.00
BKV	RW 3-21	6205	74	JOINT SPALL	Low	55	Slabs	6.9%	FDOT - CRACK SEALING - PCC	90.22	Ft	\$ 4.25	\$ 390.00
BKV	RW 3-21	6205	74	JOINT SPALL	Medium	45	Slabs	5.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	290.63	SqFt	\$ 72.00	\$ 20,930.00
BKV	RW 3-21	6205	74	JOINT SPALL	High	10	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	80.73	SqFt	\$ 72.00	\$ 5,820.00
BKV	RW 3-21	6205	75	CORNER SPALL	Low	35	Slabs	4.4%	FDOT - CRACK SEALING - PCC	57.41	Ft	\$ 4.25	\$ 250.00
BKV	RW 3-21	6205	75	CORNER SPALL	Medium	5	Slabs	0.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	12.92	SqFt	\$ 72.00	\$ 970.00
BKV	RW 3-21	6210	62	CORNER BREAK	Low	5	Slabs	0.3%	FDOT - CRACK SEALING - PCC	41.01	Ft	\$ 4.25	\$ 180.00





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BKV	RW 3-21	6210	63	LINEAR CR	Medium	150	Slabs	9.4%	FDOT - CRACK SEALING - PCC	2812.66	Ft	\$ 4.25	\$ 11,960.00
BKV	RW 3-21	6210	65	JT SEAL DMG	Low	1600	Slabs	100.0%	FDOT - JOINT SEAL - PCC	54899.93	Ft	\$ 2.75	\$ 150,980.00
BKV	RW 3-21	6210	66	SMALL PATCH	Medium	30	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	80.73	SqFt	\$ 72.00	\$ 5,820.00
BKV	RW 3-21	6210	66	SMALL PATCH	High	5	Slabs	0.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	12.92	SqFt	\$ 72.00	\$ 970.00
BKV	RW 3-21	6210	72	SHAT. SLAB	High	5	Slabs	0.3%	FDOT - SLAB REPLACEMENT - PCC	1562.92	SqFt	\$ 30.00	\$ 46,880.00
BKV	RW 3-21	6210	74	JOINT SPALL	Low	100	Slabs	6.3%	FDOT - CRACK SEALING - PCC	164.04	Ft	\$ 4.25	\$ 700.00
BKV	RW 3-21	6210	74	JOINT SPALL	Medium	15	Slabs	0.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	96.88	SqFt	\$ 72.00	\$ 6,980.00
BKV	RW 3-21	6210	75	CORNER SPALL	Low	25	Slabs	1.6%	FDOT - CRACK SEALING - PCC	41.01	Ft	\$ 4.25	\$ 180.00
BKV	RW 3-21	6210	75	CORNER SPALL	Medium	10	Slabs	0.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	26.91	SqFt	\$ 72.00	\$ 1,940.00
BKV	RW 3-21	6210	75	CORNER SPALL	High	5	Slabs	0.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	12.92	SqFt	\$ 72.00	\$ 970.00
BKV	RW 9-27	6105	63	LINEAR CR	Medium	130	Slabs	11.6%	FDOT - CRACK SEALING - PCC	2437.66	Ft	\$ 4.25	\$ 10,360.00
BKV	RW 9-27	6105	65	JT SEAL DMG	Low	1120	Slabs	100.0%	FDOT - JOINT SEAL - PCC	27975.07	Ft	\$ 2.75	\$ 76,940.00
BKV	RW 9-27	6105	67	LARGE PATCH	Medium	5	Slabs	0.5%	FDOT - PATCHING - PCC FULL DEPTH	615.7	SqFt	\$ 100.00	\$ 61,520.00
BKV	RW 9-27	6105	70	SCALING	Medium	95	Slabs	8.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	9740.26	SqFt	\$ 72.00	\$ 701,280.00
BKV	RW 9-27	6105	74	JOINT SPALL	Low	90	Slabs	8.0%	FDOT - CRACK SEALING - PCC	147.64	Ft	\$ 4.25	\$ 630.00
BKV	RW 9-27	6105	74	JOINT SPALL	Medium	70	Slabs	6.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	452.08	SqFt	\$ 72.00	\$ 32,560.00
BKV	RW 9-27	6105	74	JOINT SPALL	High	20	Slabs	1.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	161.46	SqFt	\$ 72.00	\$ 11,630.00
BKV	RW 9-27	6105	75	CORNER SPALL	Low	90	Slabs	8.0%	FDOT - CRACK SEALING - PCC	147.64	Ft	\$ 4.25	\$ 630.00
BKV	RW 9-27	6105	75	CORNER SPALL	Medium	50	Slabs	4.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	134.55	SqFt	\$ 72.00	\$ 9,690.00
BKV	RW 9-27	6110	63	LINEAR CR	Medium	161	Slabs	7.2%	FDOT - CRACK SEALING - PCC	3018.7	Ft	\$ 4.25	\$ 12,830.00
BKV	RW 9-27	6110	65	JT SEAL DMG	Low	2240	Slabs	100.0%	FDOT - JOINT SEAL - PCC	76899.93	Ft	\$ 2.75	\$ 211,480.00
BKV	RW 9-27	6110	66	SMALL PATCH	Medium	7	Slabs	0.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	19.38	SqFt	\$ 72.00	\$ 1,360.00
BKV	RW 9-27	6110	74	JOINT SPALL	Low	91	Slabs	4.1%	FDOT - CRACK SEALING - PCC	149.28	Ft	\$ 4.25	\$ 640.00
BKV	RW 9-27	6110	74	JOINT SPALL	Medium	42	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	271.25	SqFt	\$ 72.00	\$ 19,540.00
BKV	RW 9-27	6110	75	CORNER SPALL	Low	42	Slabs	1.9%	FDOT - CRACK SEALING - PCC	68.9	Ft	\$ 4.25	\$ 300.00
BKV	RW 9-27	6110	75	CORNER SPALL	Medium	7	Slabs	0.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	19.38	SqFt	\$ 72.00	\$ 1,360.00
BKV	TW A	105	62	CORNER BREAK	Low	12.5	Slabs	0.6%	FDOT - CRACK SEALING - PCC	102.69	Ft	\$ 4.25	\$ 440.00
BKV	TW A	105	63	LINEAR CR	Medium	125.03	Slabs	6.1%	FDOT - CRACK SEALING - PCC	2344.49	Ft	\$ 4.25	\$ 9,970.00
BKV	TW A	105	65	JT SEAL DMG	Low	2038	Slabs	100.0%	FDOT - JOINT SEAL - PCC	67125	Ft	\$ 2.75	\$ 184,600.00
BKV	TW A	105	66	SMALL PATCH	Medium	225.06	Slabs	11.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	606.01	SqFt	\$ 72.00	\$ 43,610.00
BKV	TW A	105	66	SMALL PATCH	High	25.01	Slabs	1.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	67.81	SqFt	\$ 72.00	\$ 4,850.00
BKV	TW A	105	70	SCALING	Medium	287.57	Slabs	14.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	29483.43	SqFt	\$ 72.00	\$ 2,122,820.00
BKV	TW A	105	72	SHAT. SLAB	Low	12.5	Slabs	0.6%	FDOT - CRACK SEALING - PCC	468.83	Ft	\$ 4.25	\$ 2,000.00
BKV	TW A	105	74	JOINT SPALL	Low	87.52	Slabs	4.3%	FDOT - CRACK SEALING - PCC	143.7	Ft	\$ 4.25	\$ 620.00
BKV	TW A	105	74	JOINT SPALL	Medium	62.52	Slabs	3.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	403.65	SqFt	\$ 72.00	\$ 29,070.00
BKV	TW A	105	75	CORNER SPALL	Low	112.53	Slabs	5.5%	FDOT - CRACK SEALING - PCC	184.71	Ft	\$ 4.25	\$ 790.00
BKV	TW A	105	75	CORNER SPALL	Medium	37.51	Slabs	1.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	101.18	SqFt	\$ 72.00	\$ 7,270.00
BKV	TW A	108	65	JT SEAL DMG	Low	35	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1109.91	Ft	\$ 2.75	\$ 3,060.00
BKV	TW A1	110	62	CORNER BREAK	Low	4.79	Slabs	2.6%	FDOT - CRACK SEALING - PCC	39.37	Ft	\$ 4.25	\$ 170.00





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BKV	TW A1	110	63	LINEAR CR	Medium	14.37	Slabs	7.9%	FDOT - CRACK SEALING - PCC	269.36	Ft	\$ 4.25	\$ 1,150.00
BKV	TW A1	110	65	JT SEAL DMG	Low	182	Slabs	100.0%	FDOT - JOINT SEAL - PCC	5924.87	Ft	\$ 2.75	\$ 16,300.00
BKV	TW A1	110	74	JOINT SPALL	Low	19.16	Slabs	10.5%	FDOT - CRACK SEALING - PCC	31.5	Ft	\$ 4.25	\$ 140.00
BKV	TW A1	110	74	JOINT SPALL	High	4.79	Slabs	2.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	38.75	SqFt	\$ 72.00	\$ 2,790.00
BKV	TW A1	110	75	CORNER SPALL	Low	28.74	Slabs	15.8%	FDOT - CRACK SEALING - PCC	47.24	Ft	\$ 4.25	\$ 210.00
BKV	TW A1	112	43	BLOCK CR	Medium	1815.44	SqFt	10.0%	FDOT - CRACK SEALING - AC	553.48	Ft	\$ 3.00	\$ 1,660.00
BKV	TW A1	112	45	DEPRESSION	Low	136.16	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	187.29	SqFt	\$ 6.00	\$ 1,130.00
BKV	TW A3	120	63	LINEAR CR	Medium	11.55	Slabs	35.0%	FDOT - CRACK SEALING - PCC	216.54	Ft	\$ 4.25	\$ 930.00
BKV	TW A3	120	65	JT SEAL DMG	Low	33	Slabs	100.0%	FDOT - JOINT SEAL - PCC	800.85	Ft	\$ 2.75	\$ 2,210.00
BKV	TW A3	120	67	LARGE PATCH	Medium	4.95	Slabs	15.0%	FDOT - PATCHING - PCC FULL DEPTH	609.24	SqFt	\$ 100.00	\$ 60,910.00
BKV	TW A3	120	74	JOINT SPALL	Low	1.65	Slabs	5.0%	FDOT - CRACK SEALING - PCC	2.62	Ft	\$ 4.25	\$ 20.00
BKV	TW A3	120	75	CORNER SPALL	Low	1.65	Slabs	5.0%	FDOT - CRACK SEALING - PCC	2.62	Ft	\$ 4.25	\$ 20.00
BKV	TW A3	125	48	L & T CR	Medium	1032.45	Ft	3.9%	FDOT - CRACK SEALING - AC	1032.48	Ft	\$ 3.00	\$ 3,100.00
BKV	TW A3	125	52	RAVELING	Medium	22372.9	SqFt	85.0%	FDOT - PATCHING - AC PARTIAL DEPTH	22372.79	SqFt	\$ 3.00	\$ 67,120.00
BKV	TW A3	125	52	RAVELING	High	3949.06	SqFt	15.0%	FDOT - PATCHING - AC PARTIAL DEPTH	3949.28	SqFt	\$ 3.00	\$ 11,850.00
BKV	TW A5	130	63	LINEAR CR	Medium	26	Slabs	25.0%	FDOT - CRACK SEALING - PCC	487.53	Ft	\$ 4.25	\$ 2,080.00
BKV	TW A5	130	65	JT SEAL DMG	Low	104	Slabs	100.0%	FDOT - JOINT SEAL - PCC	3365.16	Ft	\$ 2.75	\$ 9,260.00
BKV	TW A6	135	48	L & T CR	Medium	1575.07	Ft	5.0%	FDOT - CRACK SEALING - AC	1575.13	Ft	\$ 3.00	\$ 4,730.00
BKV	TW A6	135	52	RAVELING	Medium	23951.75	SqFt	75.8%	FDOT - PATCHING - AC PARTIAL DEPTH	23951.85	SqFt	\$ 3.00	\$ 71,860.00
BKV	TW A6	135	52	RAVELING	High	3162.01	SqFt	10.0%	FDOT - PATCHING - AC PARTIAL DEPTH	3162.44	SqFt	\$ 3.00	\$ 9,490.00
BKV	TW A9	140	63	LINEAR CR	Medium	4.25	Slabs	4.2%	FDOT - CRACK SEALING - PCC	79.72	Ft	\$ 4.25	\$ 340.00
BKV	TW A9	140	65	JT SEAL DMG	Low	102	Slabs	100.0%	FDOT - JOINT SEAL - PCC	3285.1	Ft	\$ 2.75	\$ 9,040.00
BKV	TW A9	140	66	SMALL PATCH	Medium	4.25	Slabs	4.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	11.84	SqFt	\$ 72.00	\$ 830.00
BKV	TW A9	140	74	JOINT SPALL	Low	4.25	Slabs	4.2%	FDOT - CRACK SEALING - PCC	6.89	Ft	\$ 4.25	\$ 30.00
BKV	TW B	205	48	L & T CR	Medium	2993.11	Ft	5.4%	FDOT - CRACK SEALING - AC	2993.11	Ft	\$ 3.00	\$ 8,980.00
BKV	TW B	205	52	RAVELING	Low	26471.15	SqFt	47.7%	FDOT - SURFACE SEAL	26470.61	SqFt	\$ 0.55	\$ 14,560.00
BKV	TW B	205	52	RAVELING	Medium	28145.37	SqFt	50.7%	FDOT - PATCHING - AC PARTIAL DEPTH	28145.47	SqFt	\$ 3.00	\$ 84,440.00
BKV	TW B	205	52	RAVELING	High	933.45	SqFt	1.7%	FDOT - PATCHING - AC PARTIAL DEPTH	933.23	SqFt	\$ 3.00	\$ 2,810.00
BKV	TW B	210	48	L & T CR	Medium	3282.02	Ft	2.8%	FDOT - CRACK SEALING - AC	3282.15	Ft	\$ 3.00	\$ 9,850.00
BKV	TW B	210	52	RAVELING	Low	118423.04	SqFt	100.0%	FDOT - SURFACE SEAL	118423.5	SqFt	\$ 0.55	\$ 65,140.00
BKV	TW B1	145	48	L & T CR	Medium	949.93	Ft	1.2%	FDOT - CRACK SEALING - AC	949.8	Ft	\$ 3.00	\$ 2,850.00
BKV	TW B1	145	52	RAVELING	Low	80953.97	SqFt	100.0%	FDOT - SURFACE SEAL	80954.29	SqFt	\$ 0.55	\$ 44,530.00
BKV	TW B1	215	63	LINEAR CR	Medium	18.93	Slabs	9.8%	FDOT - CRACK SEALING - PCC	354.99	Ft	\$ 4.25	\$ 1,510.00
BKV	TW B1	215	65	JT SEAL DMG	Low	194	Slabs	100.0%	FDOT - JOINT SEAL - PCC	6404.86	Ft	\$ 2.75	\$ 17,620.00
BKV	TW B1	215	74	JOINT SPALL	Low	9.46	Slabs	4.9%	FDOT - CRACK SEALING - PCC	15.42	Ft	\$ 4.25	\$ 70.00
BKV	TW B1	215	75	CORNER SPALL	Medium	9.46	Slabs	4.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.83	SqFt	\$ 72.00	\$ 1,840.00
BKV	TW B1	216	52	RAVELING	Low	45428.98	SqFt	100.0%	FDOT - SURFACE SEAL	45429.08	SqFt	\$ 0.55	\$ 24,990.00
BKV	TW B2	220	48	L & T CR	Medium	105.28	Ft	1.4%	FDOT - CRACK SEALING - AC	105.31	Ft	\$ 3.00	\$ 320.00
BKV	TW B2	220	52	RAVELING	Medium	7309.02	SqFt	100.0%	FDOT - PATCHING - AC PARTIAL DEPTH	7308.7	SqFt	\$ 3.00	\$ 21,930.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BKV	TW B3	225	45	DEPRESSION	Low	31.65	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	58.13	SqFt	\$ 6.00	\$ 350.00
BKV	TW B3	225	48	L & T CR	Medium	533.66	Ft	7.3%	FDOT - CRACK SEALING - AC	533.79	Ft	\$ 3.00	\$ 1,610.00
BKV	TW B3	225	52	RAVELING	Low	7309.02	SqFt	100.0%	FDOT - SURFACE SEAL	7308.7	SqFt	\$ 0.55	\$ 4,020.00
BKV	TW B4	230	48	L & T CR	Medium	480.74	Ft	7.7%	FDOT - CRACK SEALING - AC	480.64	Ft	\$ 3.00	\$ 1,450.00
BKV	TW B4	230	52	RAVELING	Low	6245.97	SqFt	100.0%	FDOT - SURFACE SEAL	6246.3	SqFt	\$ 0.55	\$ 3,440.00



Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BKV	AP NE	4105	AC	29,444	33	AC Reconstruction	\$ 266,000.00
2018	BKV	AP NE	4110	AC	14,592	38	AC Reconstruction	\$ 132,000.00
2018	BKV	AP NE	4117	AC	14,188	29	AC Reconstruction	\$ 128,000.00
2018	BKV	AP NE	4120	AC	29,272	29	AC Reconstruction	\$ 264,000.00
2018	BKV	AP NE	4150	PCC	28,017	54	PCC Restoration	\$ 281,000.00
2018	BKV	AP S	4205	AC	3,398	57	AC Restoration	\$ 24,000.00
2018	BKV	AP S	4210	AC	52,541	59	AC Restoration	\$ 368,000.00
2018	BKV	AP S	4215	AC	32,595	64	AC Restoration	\$ 229,000.00
2018	BKV	AP S	4220	AC	28,845	62	AC Restoration	\$ 202,000.00
2018	BKV	RW 3-21	6205	PCC	250,750	42	PCC Restoration	\$ 3,466,000.00
2018	BKV	RW 3-21	6210	PCC	501,500	51	PCC Restoration	\$ 5,016,000.00
2018	BKV	RW 9-27	6105	PCC	350,000	43	PCC Restoration	\$ 4,663,000.00
2018	BKV	RW 9-27	6110	PCC	700,000	54	PCC Restoration	\$ 7,001,000.00
2018	BKV	TW A	105	PCC	636,744	47	PCC Restoration	\$ 7,209,000.00
2018	BKV	TW A1	110	PCC	56,894	49	PCC Restoration	\$ 588,000.00
2018	BKV	TW A1	112	AC	18,154	49	AC Restoration	\$ 128,000.00
2018	BKV	TW A3	120	PCC	10,837	34	PCC Reconstruction	\$ 163,000.00
2018	BKV	TW A3	125	AC	26,322	12	AC Reconstruction	\$ 237,000.00
2018	BKV	TW A5	130	PCC	33,046	47	PCC Restoration	\$ 375,000.00
2018	BKV	TW A6	135	AC	31,614	13	AC Reconstruction	\$ 285,000.00
2018	BKV	TW A9	140	PCC	31,973	57	PCC Restoration	\$ 320,000.00
2018	BKV	TW B	205	AC	55,550	34	AC Reconstruction	\$ 500,000.00
2018	BKV	TW B	210	AC	118,423	59	AC Restoration	\$ 829,000.00
2018	BKV	TW B1	145	AC	80,954	60	AC Restoration	\$ 567,000.00
2018	BKV	TW B1	215	PCC	63,745	53	PCC Restoration	\$ 638,000.00
2018	BKV	TW B1	216	AC	45,429	51	AC Restoration	\$ 319,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BKV	TW B2	220	AC	7,309	32	AC Reconstruction	\$ 66,000.00
2018	BKV	TW B3	225	AC	7,309	54	AC Restoration	\$ 52,000.00
2018	BKV	TW B4	230	AC	6,246	54	AC Restoration	\$ 44,000.00
2020	BKV	AP NE	4140	AC	188,863	63	AC Restoration	\$ 1,323,000.00
2023	BKV	AP NE	4135	AC	47,738	64	AC Restoration	\$ 335,000.00
2027	BKV	TW A1	111	AAC	17,870	64	AC Restoration	\$ 126,000.00




# Appendix C

## Technical Exhibits








LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- SECTION NUMBER
- PAVEMENT TYPE
- TYPICAL SAMPLE UNIT INFORMATION
- FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH
- RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE
- NUMBER OF SAMPLE UNITS IN SECTION
- NUMBER OF SAMPLE UNITS TO BE INSPECTED
- SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 128  
AC: 38 PCC: 90

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2013	TW A	RECONSTRUCTION
2015	AP NE	MILL AND OVERLAY/ 4" P-401
2018	TW B	RECONSTRUCTION
2019	RW 3-21	RUNWAY EXTENSION
2019	TW CONNECTORS	NEW CONSTRUCTION




#### LEGEND

- PROJECTS YEAR 2013
- PROJECTS YEAR 2014
- PROJECTS YEAR 2015
- PROJECTS YEAR 2016
- PROJECTS YEAR 2017
- PROJECTS YEAR 2018
- PROJECTS YEAR 2019
- PROJECTS YEAR 2020
- PROJECTS YEAR 2021
- PROJECTS YEAR 2022

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.









# Appendix D

## Inspection Photograph Documentation





Runway 9-27, Section 6110, Sample Unit 300 – Medium Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage, (73) Shrinkage Cracks



Runway 9-27, Section 6110, Sample Unit 349 – Medium Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage, Low Severity (66) Small Patching, (73) Shrinkage Cracks





Runway 9-27, Section 6110, Sample Unit 398 – Low Severity (65) Joint Seal Damage, Low Severity (66) Small Patching, (73) Shrinkage Cracks



Runway 9-27, Section 6110, Sample Unit 439 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage, Low Severity (74) Joint Spalling





Runway 3-21, Section 6210, Sample Unit 301 – Low Severity (65) Joint Seal Damage, Medium Severity (66) Small Patching, Low Severity (74) Joint Spalling, Low Severity (75) Corner Spalling



Runway 3-21, Section 6210, Sample Unit 337 – Medium Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage





Runway 3-21, Section 6210, Sample Unit 367 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage, Low Severity (70) Scaling, Map Cracking, Cracking, (73) Shrinkage Cracks



Runway 3-21, Section 6210, Sample Unit 398 – Low Severity (65) Joint Seal Damage, Low Severity (66) Small Patching





Taxiway A, Section 105, Sample Unit 107 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage, Low Severity (66) Small Patching, (73) Shrinkage Cracks



Taxiway A, Section 105, Sample Unit 191 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage, Low Severity (67) Large Patching





Taxiway A, Section 105, Sample Unit 268 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage



Taxiway A3, Section 125, Sample Unit 301 – Low Severity (48) Longitudinal and Transverse Cracking, Medium Severity (52) Raveling, High Severity (52) Raveling





Taxiway A6, Section 135, Sample Unit 605 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (50) Patching, Medium Severity (52) Raveling, High Severity (52) Raveling



Taxiway B, Section 210, Sample Unit 104 – Low and Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling





Taxiway B, Section 210, Sample Unit 128 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling



Taxiway B, Section 205, Sample Unit 148 – Medium Severity (52) Raveling, High Severity (52) Raveling





South Apron, Section 4210, Sample Unit 504 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling



South Apron, Section 4225, Sample Unit 302 – Low Severity (57) Weathering





Apron NE, Section 4140, Sample Unit 207 – Low Severity (48) Longitudinal and Transverse Cracking, (49) Oil Spillage, Low Severity (57) Weathering

# Appendix E

## Inspection Distress Details

# Re-Inspection Report

FDOT

Generated Date

8/1/2017

Page 1 of 52

Network: BKV

Name: BROOKSVILLE - TAMPA BAY REGIONAL  
AIRPORT

Branch: AP NE Name: NE APRON Use: APRON Area: 552,135 SqFt

Section: 4105 of 15 From: - To: - Last Const.: 1/1/1975

Surface: AC Family: C9N59-GA-AP-AC Zone: Category: Rank: P

Area: 29,444 SqFt Length: 600 Ft Width: 42 Ft

Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft

Shoulder: Street Type: Grade: 0 Lanes: 0

Section Comments:

Work Date: 1/1/1975 Work Type: OVERLAY Code: IMPORTED Is Major M&R: True

Work Date: 1/1/1975 Work Type: BUILT Code: IMPORTED Is Major M&R: True

Last Insp. Date: 3/29/2017 TotalSamples: 7 Surveyed: 1

Conditions: PCI: 35

Inspection Comments:

Sample Number: 852 Type: R Area: 4500.00 SqFt PCI: 35

Sample Comments:

43	BLOCK CR	L	3825.00	SqFt
43	BLOCK CR	M	675.00	SqFt
52	RAVELING	L	2700.00	SqFt
52	RAVELING	M	1800.00	SqFt

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP NE	Name:	NE APRON	Use:	APRON	Area:	552,135 SqFt		
Section:	4110	of	15	From:	-	To:	-	Last Const.:	1/1/1975
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	14,592 SqFt	Length:	290 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1975	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/1975	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True		
Last Insp. Date:	3/29/2017	TotalSamples:	3	Surveyed:		1			
Conditions:	PCI:	40							
Inspection Comments:									
Sample Number:	650	Type:	R	Area:	3325.00 SqFt	PCI:	40		
Sample Comments:									
43	BLOCK CR	L	1275.00	SqFt					
48	L & T CR	L	397.00	Ft					
52	RAVELING	L	1995.00	SqFt					
52	RAVELING	M	1330.00	SqFt					



Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
Branch:	AP NE	Name:	NE APRON	Use:	APRON	Area:	552,135 SqFt		
Section:	4115	of	15	From:	-	To:	-	Last Const.:	1/1/2015
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC	Zone:		Category:		Rank:	P
Area:	21,610 SqFt	Length:	250 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1975	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R:	True	
Work Date:	1/1/1975	Work Type: BUILT			Code:	IMPORTED	Is Major M&R:	True	
Work Date:	1/1/2015	Work Type: MILL and OVERLAY			Code:	ML-OV	Is Major M&R:	True	
Last Insp. Date:	6/10/2013	TotalSamples:		6	Surveyed:		2		
Conditions:	PCI: 52	NOTE: *** Pre-Construction PCI ***							
Inspection Comments:									
Sample Number:	551	Type:	R	Area:	3000.00 SqFt	PCI:	49		
Sample Comments:									
43	BLOCK CRACKING	L	740.00	SqFt					
48	LONGITUDINAL/TRANSVERSE CRACKING	L	288.00	Ft					
57	WEATHERING	L	3000.00	SqFt					
52	RAVELING	L	3000.00	SqFt					
41	ALLIGATOR CRACKING	L	27.00	SqFt					
Sample Number:	554	Type:	R	Area:	5775.00 SqFt	PCI:	54		
Sample Comments:									
43	BLOCK CRACKING	L	5200.00	SqFt					
48	LONGITUDINAL/TRANSVERSE CRACKING	L	113.00	Ft					
57	WEATHERING	L	5775.00	SqFt					
45	DEPRESSION	L	18.00	SqFt					

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP NE	Name:	NE APRON	Use:	APRON	Area:	552,135 SqFt		
Section:	4117	of	15	From:	-	To:	-	Last Const.:	1/1/1975
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	14,188 SqFt	Length:	150 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1975	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1975	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/29/2017	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI: 31								
Inspection Comments:									
Sample Number:	551	Type:	R	Area:	3769.00 SqFt	PCI:	31		
Sample Comments:									
41	ALLIGATOR CR	L	54.00	SqFt					
43	BLOCK CR	L	2393.00	SqFt					
45	DEPRESSION	L	5.00	SqFt					
48	L & T CR	L	366.00	Ft					
52	RAVELING	L	2261.00	SqFt					
52	RAVELING	M	1508.00	SqFt					

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP NE	Name:	NE APRON	Use:	APRON	Area:	552,135 SqFt		
Section:	4120	of	15	From:	-	To:	-	Last Const.:	1/1/1964
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	29,272 SqFt	Length:	125 Ft	Width:	200 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1964	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/1964	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True		
Last Insp. Date:	3/29/2017	TotalSamples:	6	Surveyed:		1			
Conditions:	PCI:	31							
Inspection Comments:									
Sample Number:	402	Type:	R	Area:	4050.00 SqFt	PCI:	31		
Sample Comments:									
43	BLOCK CR	L	3442.00	SqFt					
43	BLOCK CR	M	608.00	SqFt					
52	RAVELING	L	1620.00	SqFt					
52	RAVELING	M	2430.00	SqFt					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP NE		Name:	NE APRON		Use:	APRON		Area:	552,135 SqFt	
Section:	4123		of	15		From:	-		To:	-	
Surface:	AAC		Family:	C9N59-GA-AP-AAC-APC		Zone:			Category:		
Area:	23,785 SqFt		Length:	100 Ft		Width:	200 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1964		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1964		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2015		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	6/10/2013		TotalSamples:	11		Surveyed:	2				
Conditions:	PCI:	53	NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	354		Type:	R		Area:	5000.00 SqFt		PCI:	64	
Sample Comments:											
43	BLOCK CRACKING		L	5000.00 SqFt							
Sample Number:	402		Type:	R		Area:	5000.00 SqFt		PCI:	42	
Sample Comments:											
43	BLOCK CRACKING		L	220.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	379.00 Ft							
57	WEATHERING		L	3000.00 SqFt							
52	RAVELING		L	3000.00 SqFt							
52	RAVELING		M	2000.00 SqFt							



Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP NE	Name:	NE APRON	Use:	APRON	Area:	552,135 SqFt		
Section:	4125	of	15	From:	-	To:	-	Last Const.:	1/1/2015
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC	Zone:		Category:		Rank:	P
Area:	23,740 SqFt	Length:	260 Ft	Width:	90 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1964	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1975	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1975	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2015	Work Type:	MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True		
Last Insp. Date:	6/10/2013	TotalSamples:	5	Surveyed:	1				
Conditions:	PCI: 63	NOTE: *** Pre-Construction PCI ***							
Inspection Comments:									
Sample Number:	204	Type:	R	Area:	5000.00 SqFt	PCI:	63		
Sample Comments:									
43	BLOCK CRACKING	L	3460.00 SqFt						
48	LONGITUDINAL/TRANSVERSE CRACKING	L	294.00 Ft						

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
Branch:	AP NE	Name:	NE APRON		Use:	APRON	Area:	552,135 SqFt	
Section:	4130	of	15	From:	-	To:	-	Last Const.:	1/1/2015
Surface:	APC	Family:	C9N59-GA-AP-AAC-APC	Zone:		Category:		Rank:	P
Area:	6,146 SqFt	Length:	25 Ft	Width:	200 Ft				
Slabs:	12	Slab Length:	21 Ft	Slab Width:	21 Ft	Joint Length:	269 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1942	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1942	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2015	Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	6/10/2013	TotalSamples:	1	Surveyed: 1					
Conditions:	PCI: 37	NOTE: *** Pre-Construction PCI ***							
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	12.00 Slabs	PCI:	37		
Sample Comments:									
62	CORNER BREAK	L	3.00	Slabs					
63	LINEAR CRACKING	L	7.00	Slabs					
63	LINEAR CRACKING	M	1.00	Slabs					
72	SHATTERED SLAB	L	4.00	Slabs					
74	JOINT SPALLING	L	1.00	Slabs					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT					
Branch:	AP NE	Name:	NE APRON		Use:	APRON	Area:	552,135 SqFt		
Section:	4135	of	15	From:	-	To:	-	Last Const.:	1/1/1983	
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:	P
Area:	47,738 SqFt	Length:	500 Ft		Width:	95 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1983		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1983		Work Type: BUILT			Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/2015		Work Type: Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R: False	
Last Insp. Date:	3/29/2017		TotalSamples:	10		Surveyed:	1			
Conditions:	PCI: 74									
Inspection Comments:										
Sample Number:	250	Type:	R	Area:	5000.00 SqFt		PCI:	74		
Sample Comments:										
48	L & T CR		L	408.00 Ft						
57	WEATHERING		L	5000.00 SqFt						

<b>Network:</b>	BKV		<b>Name:</b>	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
<b>Branch:</b>	AP NE	<b>Name:</b>	NE APRON	<b>Use:</b>	APRON	<b>Area:</b>	552,135 SqFt	
<b>Section:</b>	4137	of 15	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b>	1/1/2015
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-AP-AAC-APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b>	P
<b>Area:</b>	11,384 SqFt	<b>Length:</b>	100 Ft	<b>Width:</b>	95 Ft			
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0	
<b>Section Comments:</b>								
<b>Work Date:</b>	1/1/1983	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	1/1/1983	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	1/1/2015	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	<b>Is Major M&amp;R:</b>	True	
<b>Last Insp. Date:</b>	6/10/2013	<b>TotalSamples:</b>	12	<b>Surveyed:</b>	2			
<b>Conditions:</b>	PCI: 63	<b>NOTE: *** Pre-Construction PCI ***</b>						
<b>Inspection Comments:</b>								
<b>Sample Number:</b>	250	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	74	
<b>Sample Comments:</b>								
48	LONGITUDINAL/TRANSVERSE CRACKING	L	72.00	Ft				
57	WEATHERING	L	5000.00	SqFt				
52	RAVELING	L	1500.00	SqFt				
<b>Sample Number:</b>	304	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	52	
<b>Sample Comments:</b>								
45	DEPRESSION	L	128.00	SqFt				
43	BLOCK CRACKING	L	4000.00	SqFt				
48	LONGITUDINAL/TRANSVERSE CRACKING	L	97.00	Ft				
57	WEATHERING	L	5000.00	SqFt				



Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
Branch:	AP NE	Name:	NE APRON	Use:	APRON	Area:	552,135 SqFt		
Section:	4140	of	15	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	188,863 SqFt	Length:	925 Ft	Width:	200 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1991	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/1991	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/2015	Work Type: Surface Treatment - Slurry Seal			Code:	ST-SS	Is Major M&R: False		
Last Insp. Date:	3/29/2017	TotalSamples:	37	Surveyed: 4					
Conditions:	PCI: 68								
Inspection Comments:									
Sample Number:	207	Type:	R	Area:	5000.00 SqFt	PCI:	63		
Sample Comments:									
48	L & T CR	L	630.00	Ft					
49	OIL SPILLAGE	N	12.00	SqFt					
50	PATCHING	L	28.00	SqFt					
57	WEATHERING	L	4972.00	SqFt					
Sample Number:	209	Type:	R	Area:	5000.00 SqFt	PCI:	66		
Sample Comments:									
48	L & T CR	L	531.00	Ft					
52	RAVELING	L	500.00	SqFt					
57	WEATHERING	L	4500.00	SqFt					
Sample Number:	411	Type:	R	Area:	5000.00 SqFt	PCI:	64		
Sample Comments:									
43	BLOCK CR	L	1755.00	SqFt					
48	L & T CR	L	508.00	Ft					
57	WEATHERING	L	5000.00	SqFt					
Sample Number:	60	Type:	R	Area:	5000.00 SqFt	PCI:	80		
Sample Comments:									
48	L & T CR	L	107.00	Ft					
52	RAVELING	L	500.00	SqFt					
57	WEATHERING	L	4500.00	SqFt					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT									
Branch:	AP NE		Name:	NE APRON		Use:	APRON		Area:	552,135 SqFt				
Section:	4143		of	15		From:	-		To:	-		Last Const.:	1/1/2015	
Surface:	AAC		Family:	C9N59-GA-AP-AAC-APC		Zone:			Category:			Rank:	P	
Area:	33,176 SqFt		Length:	150 Ft		Width:	200 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1991		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1991		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2015		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	6/10/2013		TotalSamples:	44		Surveyed:	5							
Conditions:	PCI: 72		NOTE: *** Pre-Construction PCI ***											
Inspection Comments:														
Sample Number:	207		Type:	R		Area:	5000.00 SqFt		PCI:	77				
Sample Comments:														
48	LONGITUDINAL/TRANSVERSE CRACKING		L	86.00		Ft								
57	WEATHERING		L	4967.00		SqFt								
50	PATCHING		L	25.00		SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	16.00		Ft								
50	PATCHING		L	8.00		SqFt								
52	RAVELING		L	400.00		SqFt								
56	SWELLING		L	24.00		SqFt								
Sample Number:	209		Type:	R		Area:	5000.00 SqFt		PCI:	75				
Sample Comments:														
48	LONGITUDINAL/TRANSVERSE CRACKING		L	111.00		Ft								
56	SWELLING		L	230.00		SqFt								
57	WEATHERING		L	5000.00		SqFt								
52	RAVELING		L	400.00		SqFt								
Sample Number:	305		Type:	R		Area:	5000.00 SqFt		PCI:	71				
Sample Comments:														
56	SWELLING		L	500.00		SqFt								
57	WEATHERING		L	5000.00		SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	194.00		Ft								
56	SWELLING		L	116.00		SqFt								
Sample Number:	411		Type:	R		Area:	5000.00 SqFt		PCI:	53				
Sample Comments:														
48	LONGITUDINAL/TRANSVERSE CRACKING		L	56.00		Ft								
56	SWELLING		L	2700.00		SqFt								
57	WEATHERING		L	5000.00		SqFt								
Sample Number:	60		Type:	R		Area:	5000.00 SqFt		PCI:	82				
Sample Comments:														
48	LONGITUDINAL/TRANSVERSE CRACKING		L	80.00		Ft								
57	WEATHERING		L	5000.00		SqFt								
52	RAVELING		L	300.00		SqFt								

<b>Network:</b>	BKV			<b>Name:</b>	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT								
<b>Branch:</b>	AP NE		<b>Name:</b>	NE APRON		<b>Use:</b>	APRON		<b>Area:</b>	552,135 SqFt			
<b>Section:</b>	4145		of	15	<b>From:</b>	-		<b>To:</b>	-		<b>Last Const.:</b>	1/1/2015	
<b>Surface:</b>	AAC		<b>Family:</b>	C9N59-GA-AP-AAC-APC		<b>Zone:</b>			<b>Category:</b>			<b>Rank:</b>	P
<b>Area:</b>	72,809 SqFt		<b>Length:</b>	600 Ft		<b>Width:</b>	120 Ft						
<b>Slabs:</b>			<b>Slab Length:</b>	Ft		<b>Slab Width:</b>	Ft		<b>Joint Length:</b>	Ft			
<b>Shoulder:</b>			<b>Street Type:</b>			<b>Grade:</b>	0		<b>Lanes:</b>	0			
<b>Section Comments:</b>													
<b>Work Date:</b>	1/1/1991		<b>Work Type:</b> OVERLAY				<b>Code:</b>	IMPORTED		<b>Is Major M&amp;R:</b> True			
<b>Work Date:</b>	1/1/1991		<b>Work Type:</b> BUILT				<b>Code:</b>	IMPORTED		<b>Is Major M&amp;R:</b> True			
<b>Work Date:</b>	1/1/2015		<b>Work Type:</b> MILL and OVERLAY				<b>Code:</b>	ML-OV		<b>Is Major M&amp;R:</b> True			
<b>Last Insp. Date:</b>	6/10/2013		<b>TotalSamples:</b>	13		<b>Surveyed:</b>	2						
<b>Conditions:</b>	PCI:	56	NOTE: *** Pre-Construction PCI ***										
<b>Inspection Comments:</b>													
<b>Sample Number:</b>	303	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt		<b>PCI:</b>	63					
<b>Sample Comments:</b>													
48	LONGITUDINAL/TRANSVERSE CRACKING	L	287.00	Ft									
57	WEATHERING	L	5000.00	SqFt									
52	RAVELING	L	3000.00	SqFt									
56	SWELLING	L	122.00	SqFt									
<b>Sample Number:</b>	504	<b>Type:</b>	R	<b>Area:</b>	6917.00 SqFt		<b>PCI:</b>	51					
<b>Sample Comments:</b>													
48	LONGITUDINAL/TRANSVERSE CRACKING	L	419.00	Ft									
48	LONGITUDINAL/TRANSVERSE CRACKING	M	21.00	Ft									
56	SWELLING	L	1350.00	SqFt									
57	WEATHERING	L	6917.00	SqFt									
52	RAVELING	L	5000.00	SqFt									
49	OIL SPILLAGE	N	336.00	SqFt									

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT					
Branch:	AP NE		Name:	NE APRON		Use:	APRON	Area:	552,135 SqFt	
Section:	4147 of 15		From:	-		To:	-		Last Const.:	1/1/2015
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC		Zone:			Category:	Rank:	P
Area:	7,371 SqFt		Length:	35 Ft		Width:	200 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1989		Work Type:			BUILT		Code:	IMPORTED	
Work Date:	1/1/2015		Work Type:			MILL and OVERLAY		Code:	ML-OV	
Last Insp. Date:	6/10/2013		TotalSamples:	2		Surveyed:	1			
Conditions:	PCI: 55		NOTE: *** Pre-Construction PCI ***							
Inspection Comments:										
Sample Number:	155	Type:	R	Area:	3500.00 SqFt		PCI:	55		
Sample Comments:										
45	DEPRESSION		L	21.00 SqFt						
41	ALLIGATOR CRACKING		L	45.00 SqFt						
43	BLOCK CRACKING		L	3455.00 SqFt						



Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
Branch:	AP NE	Name:	NE APRON	Use:	APRON	Area:	552,135 SqFt		
Section:	4150	of	15	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	PCC	Family:	C9N59-GA-AP-PCC	Zone:		Category:		Rank:	P
Area:	28,017 SqFt	Length:	148 Ft	Width:	200 Ft				
Slabs:	46	Slab Length:	25 Ft	Slab Width:	25 Ft	Joint Length:	2,020 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1991	Work Type:			OVERLAY	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1991	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/29/2017	TotalSamples:	5	Surveyed:	1				
Conditions:	PCI: 55								
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	9.00 Slabs	PCI:	55		
Sample Comments:									
63	LINEAR CR	L	4.00	Slabs					
65	JT SEAL DMG	L	9.00	Slabs					
72	SHAT. SLAB	L	1.00	Slabs					
73	SHRINKAGE CR	N	5.00	Slabs					
74	JOINT SPALL	L	1.00	Slabs					
74	JOINT SPALL	M	1.00	Slabs					

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP S	Name:	SOUTH APRON	Use:	APRON	Area:	231,935 SqFt		
Section:	4205	of	5	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	3,398 SqFt	Length:	90 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1991	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/1991	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True		
Last Insp. Date:	3/29/2017	TotalSamples:	1	Surveyed:		1			
Conditions:	PCI: 59								
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	3398.00 SqFt	PCI:	59		
Sample Comments:									
52	RAVELING	M	70.00	SqFt					
45	DEPRESSION	L	41.00	SqFt					
48	L & T CR	L	235.00	Ft					
52	RAVELING	L	3328.00	SqFt					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT							
Branch:	AP S		Name:	SOUTH APRON		Use:	APRON	Area:	231,935 SqFt			
Section:	4210	of	5	From:	-			To:	-		Last Const.:	12/25/1999
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:				Category:	Rank: P		
Area:	52,541 SqFt		Length:	453 Ft		Width:	112 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1999		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2014		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	3/29/2017		TotalSamples:	8		Surveyed:	1					
Conditions:	PCI:	61										
Inspection Comments:												
Sample Number:	504		Type:	R		Area:	6600.00 SqFt		PCI:	61		
Sample Comments:												
45	DEPRESSION		L	84.00		SqFt						
48	L & T CR		L	118.00		Ft						
52	RAVELING		L	6600.00		SqFt						
54	SHOVING		L	8.00		SqFt						

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT							
Branch:	AP S		Name:	SOUTH APRON		Use:	APRON	Area:	231,935 SqFt			
Section:	4215	of	5	From:	-			To:	-		Last Const.:	12/25/1999
Surface:	AC		Family:	C9N59-GA-AP-AC		Zone:				Category:	Rank: P	
Area:	32,595 SqFt		Length:	450 Ft		Width:	65 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True	
Work Date:	1/1/2014		Work Type:	Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R:	False	
Last Insp. Date:	3/29/2017		TotalSamples:	7		Surveyed:	1					
Conditions:	PCI: 66											
Inspection Comments:												
Sample Number:	402		Type:	R		Area:	4500.00 SqFt		PCI:	66		
Sample Comments:												
45	DEPRESSION		L	20.00 SqFt								
48	L & T CR		L	32.00 Ft								
52	RAVELING		L	4500.00 SqFt								



Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP S	Name:	SOUTH APRON	Use:	APRON	Area:	231,935 SqFt		
Section:	4220	of	5	From:	-	To:	-	Last Const.:	12/25/1999
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	28,845 SqFt	Length:	425 Ft	Width:	65 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1999	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Work Date:	1/1/2014	Work Type:	Surface Treatment - Slurry Seal		Code:	ST-SS	Is Major M&R:	False	
Last Insp. Date:	3/29/2017	TotalSamples:	7	Surveyed:	1				
Conditions:	PCI:	64							
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	4000.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	L	29.00	Ft					
52	RAVELING	L	3985.00	SqFt					
52	RAVELING	M	15.00	SqFt					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	AP S		Name:	SOUTH APRON		Use:	APRON	Area:	231,935 SqFt		
Section:	4225 of 5		From:	-			To:	-		Last Const.:	1/1/2009
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	114,556 SqFt		Length:	1,700 Ft		Width:	65 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0			Lanes:	0		
Section Comments:											
Work Date:	1/1/2009		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	3/29/2017		TotalSamples:	28		Surveyed:	4				
Conditions:	PCI: 90										
Inspection Comments:											
Sample Number:	102	Type:	R	Area:	4000.00 SqFt		PCI:	90			
Sample Comments:											
48	L & T CR	L	5.00 Ft								
52	RAVELING	L	20.00 SqFt								
57	WEATHERING	L	3980.00 SqFt								
Sample Number:	302	Type:	R	Area:	4000.00 SqFt		PCI:	89			
Sample Comments:											
48	L & T CR	L	34.00 Ft								
57	WEATHERING	L	4000.00 SqFt								
Sample Number:	602	Type:	R	Area:	4000.00 SqFt		PCI:	87			
Sample Comments:											
48	L & T CR	L	84.00 Ft								
57	WEATHERING	L	4000.00 SqFt								
Sample Number:	802	Type:	R	Area:	4000.00 SqFt		PCI:	94			
Sample Comments:											
57	WEATHERING	L	4000.00 SqFt								

<b>Network:</b>	BKV		<b>Name:</b>	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT								
<b>Branch:</b>	RW 3-21		<b>Name:</b>	RUNWAY 3-21		<b>Use:</b>	RUNWAY	<b>Area:</b>	752,250 SqFt			
<b>Section:</b>	6205		of	2	<b>From:</b>	-		<b>To:</b>	-		<b>Last Const.:</b>	1/1/1942
<b>Surface:</b>	PCC		<b>Family:</b>	C9N59-GA-RW-TW-PCC		<b>Zone:</b>			<b>Category:</b>	<b>Rank:</b> S		
<b>Area:</b>	250,750 SqFt		<b>Length:</b>	10,000 Ft		<b>Width:</b>	25 Ft					
<b>Slabs:</b>	800		<b>Slab Length:</b>	13 Ft		<b>Slab Width:</b>	25 Ft		<b>Joint Length:</b>	19,975 Ft		
<b>Shoulder:</b>			<b>Street Type:</b>			<b>Grade:</b>	0		<b>Lanes:</b>	0		
<b>Section Comments:</b>												
<b>Work Date:</b>	1/1/1942		<b>Work Type:</b>	OVERLAY				<b>Code:</b>	IMPORTED		<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1942		<b>Work Type:</b>	BUILT				<b>Code:</b>	IMPORTED		<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	3/1/2011		<b>Work Type:</b>	JT SEAL DMG				<b>Code:</b>	JS-LC		<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	3/29/2017		<b>TotalSamples:</b>	50		<b>Surveyed:</b>	10					
<b>Conditions:</b>	<b>PCI:</b> 43											
<b>Inspection Comments:</b>												
<b>Sample Number:</b>	104		<b>Type:</b>	R		<b>Area:</b>	16.00 Slabs		<b>PCI:</b>	43		
<b>Sample Comments:</b>												
63	LINEAR CR		L	4.00		Slabs						
63	LINEAR CR		M	2.00		Slabs						
65	JT SEAL DMG		L	16.00		Slabs						
66	SMALL PATCH		L	11.00		Slabs						
66	SMALL PATCH		M	2.00		Slabs						
67	LARGE PATCH		L	4.00		Slabs						
73	SHRINKAGE CR		N	16.00		Slabs						
74	JOINT SPALL		L	4.00		Slabs						
<b>Sample Number:</b>	132		<b>Type:</b>	R		<b>Area:</b>	16.00 Slabs		<b>PCI:</b>	34		
<b>Sample Comments:</b>												
63	LINEAR CR		L	9.00		Slabs						
63	LINEAR CR		M	1.00		Slabs						
65	JT SEAL DMG		L	16.00		Slabs						
66	SMALL PATCH		L	12.00		Slabs						
67	LARGE PATCH		L	9.00		Slabs						
73	SHRINKAGE CR		N	16.00		Slabs						
74	JOINT SPALL		M	2.00		Slabs						
74	JOINT SPALL		H	1.00		Slabs						
75	CORNER SPALL		L	3.00		Slabs						
<b>Sample Number:</b>	148		<b>Type:</b>	R		<b>Area:</b>	16.00 Slabs		<b>PCI:</b>	32		
<b>Sample Comments:</b>												
63	LINEAR CR		L	9.00		Slabs						
63	LINEAR CR		M	2.00		Slabs						
65	JT SEAL DMG		L	16.00		Slabs						
66	SMALL PATCH		L	13.00		Slabs						
67	LARGE PATCH		L	4.00		Slabs						
72	SHAT. SLAB		L	1.00		Slabs						
73	SHRINKAGE CR		N	16.00		Slabs						
74	JOINT SPALL		L	2.00		Slabs						
74	JOINT SPALL		M	4.00		Slabs						
75	CORNER SPALL		L	1.00		Slabs						
<b>Sample Number:</b>	164		<b>Type:</b>	R		<b>Area:</b>	16.00 Slabs		<b>PCI:</b>	39		
<b>Sample Comments:</b>												
63	LINEAR CR		L	3.00		Slabs						
63	LINEAR CR		M	4.00		Slabs						
65	JT SEAL DMG		L	16.00		Slabs						
66	SMALL PATCH		L	13.00		Slabs						
67	LARGE PATCH		L	8.00		Slabs						
73	SHRINKAGE CR		N	16.00		Slabs						
75	CORNER SPALL		L	1.00		Slabs						

E-21

<b>Sample Number:</b> 192		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 53
<b>Sample Comments:</b>					
63	LINEAR CR	L	2.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	12.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	3.00	Slabs	
71	FAULTING	L	1.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
74	JOINT SPALL	M	2.00	Slabs	
<b>Sample Number:</b> 504		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 30
<b>Sample Comments:</b>					
63	LINEAR CR	L	6.00	Slabs	
63	LINEAR CR	M	9.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	13.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
<b>Sample Number:</b> 512		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 46
<b>Sample Comments:</b>					
63	LINEAR CR	L	6.00	Slabs	
63	LINEAR CR	M	1.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	14.00	Slabs	
67	LARGE PATCH	L	7.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
<b>Sample Number:</b> 544		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 57
<b>Sample Comments:</b>					
63	LINEAR CR	L	6.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	12.00	Slabs	
67	LARGE PATCH	L	3.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
<b>Sample Number:</b> 580		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 48
<b>Sample Comments:</b>					
63	LINEAR CR	L	3.00	Slabs	
63	LINEAR CR	M	1.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	13.00	Slabs	
67	LARGE PATCH	L	4.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	H	1.00	Slabs	
<b>Sample Number:</b> 592		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 49
<b>Sample Comments:</b>					
63	LINEAR CR	L	8.00	Slabs	
63	LINEAR CR	M	1.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	7.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	



Network:	BKV		Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT							
Branch:	RW 3-21		Name:	RUNWAY 3-21		Use:	RUNWAY	Area:	752,250 SqFt		
Section:	6210 of 2		From:	-		To:	-		Last Const.:	1/1/1942	
Surface:	PCC		Family:	C9N59-GA-RW-TW-PCC		Zone:			Rank:	S	
Area:	501,500 SqFt		Length:	5,000 Ft		Width:	100 Ft				
Slabs:	1,600		Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	54,900 Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	3/1/2011		Work Type: JT SEAL DMG				Code:	JS-LC		Is Major M&R:	False
Last Insp. Date:	3/29/2017		TotalSamples:	100		Surveyed:	20				
Conditions:	PCI: 52										
Inspection Comments:											
Sample Number:	301		Type:	R		Area:	16.00 Slabs		PCI:	59	
Sample Comments:											
63	LINEAR CR		L	5.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	13.00 Slabs							
66	SMALL PATCH		M	1.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	2.00 Slabs							
75	CORNER SPALL		L	1.00 Slabs							
Sample Number:	306		Type:	R		Area:	16.00 Slabs		PCI:	49	
Sample Comments:											
63	LINEAR CR		L	7.00 Slabs							
63	LINEAR CR		M	2.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	10.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	3.00 Slabs							
Sample Number:	313		Type:	R		Area:	16.00 Slabs		PCI:	31	
Sample Comments:											
62	CORNER BREAK		L	1.00 Slabs							
63	LINEAR CR		L	5.00 Slabs							
63	LINEAR CR		M	2.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	11.00 Slabs							
67	LARGE PATCH		L	1.00 Slabs							
72	SHAT. SLAB		H	1.00 Slabs							
73	SHRINKAGE CR		N	15.00 Slabs							
Sample Number:	316		Type:	R		Area:	16.00 Slabs		PCI:	45	
Sample Comments:											
63	LINEAR CR		L	7.00 Slabs							
63	LINEAR CR		M	4.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	14.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
Sample Number:	319		Type:	R		Area:	16.00 Slabs		PCI:	43	
Sample Comments:											
63	LINEAR CR		L	6.00 Slabs							
63	LINEAR CR		M	4.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	10.00 Slabs							
66	SMALL PATCH		M	1.00 Slabs							

E-23

73	SHRINKAGE CR	N	16.00	Slabs
<b>Sample Number: 325                      Type: R                      Area: 16.00 Slabs                      PCI: 54</b>				
<b>Sample Comments:</b>				
63	LINEAR CR	L	3.00	Slabs
63	LINEAR CR	M	2.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	15.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
75	CORNER SPALL	H	1.00	Slabs
<b>Sample Number: 331                      Type: R                      Area: 16.00 Slabs                      PCI: 65</b>				
<b>Sample Comments:</b>				
63	LINEAR CR	L	9.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	11.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
<b>Sample Number: 337                      Type: R                      Area: 16.00 Slabs                      PCI: 41</b>				
<b>Sample Comments:</b>				
63	LINEAR CR	L	10.00	Slabs
63	LINEAR CR	M	2.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	9.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
74	JOINT SPALL	M	1.00	Slabs
75	CORNER SPALL	L	1.00	Slabs
<b>Sample Number: 344                      Type: R                      Area: 16.00 Slabs                      PCI: 52</b>				
<b>Sample Comments:</b>				
63	LINEAR CR	L	6.00	Slabs
63	LINEAR CR	M	1.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	11.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
75	CORNER SPALL	L	1.00	Slabs
<b>Sample Number: 349                      Type: R                      Area: 16.00 Slabs                      PCI: 66</b>				
<b>Sample Comments:</b>				
63	LINEAR CR	L	6.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	12.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
<b>Sample Number: 355                      Type: R                      Area: 16.00 Slabs                      PCI: 50</b>				
<b>Sample Comments:</b>				
63	LINEAR CR	L	7.00	Slabs
63	LINEAR CR	M	1.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	11.00	Slabs
66	SMALL PATCH	M	2.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
<b>Sample Number: 361                      Type: R                      Area: 16.00 Slabs                      PCI: 62</b>				
<b>Sample Comments:</b>				
63	LINEAR CR	L	11.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	11.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
75	CORNER SPALL	L	1.00	Slabs

Sample Number: 367		Type:	R	Area:		16.00 Slabs	PCI: 37
Sample Comments:							
63	LINEAR CR		L	10.00	Slabs		
63	LINEAR CR		M	2.00	Slabs		
65	JT SEAL DMG		L	16.00	Slabs		
66	SMALL PATCH		L	8.00	Slabs		
66	SMALL PATCH		M	2.00	Slabs		
66	SMALL PATCH		H	1.00	Slabs		
70	SCALING		L	2.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
74	JOINT SPALL		M	1.00	Slabs		
75	CORNER SPALL		M	1.00	Slabs		
Sample Number: 373		Type:	R	Area:		16.00 Slabs	PCI: 51
Sample Comments:							
63	LINEAR CR		L	12.00	Slabs		
65	JT SEAL DMG		L	16.00	Slabs		
66	SMALL PATCH		L	14.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
63	LINEAR CR		M	2.00	Slabs		
Sample Number: 379		Type:	R	Area:		16.00 Slabs	PCI: 63
Sample Comments:							
63	LINEAR CR		L	5.00	Slabs		
65	JT SEAL DMG		L	16.00	Slabs		
66	SMALL PATCH		L	12.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
74	JOINT SPALL		M	1.00	Slabs		
Sample Number: 384		Type:	R	Area:		16.00 Slabs	PCI: 42
Sample Comments:							
63	LINEAR CR		L	10.00	Slabs		
63	LINEAR CR		M	4.00	Slabs		
65	JT SEAL DMG		L	16.00	Slabs		
66	SMALL PATCH		L	12.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
Sample Number: 388		Type:	R	Area:		16.00 Slabs	PCI: 41
Sample Comments:							
63	LINEAR CR		L	11.00	Slabs		
63	LINEAR CR		M	4.00	Slabs		
65	JT SEAL DMG		L	16.00	Slabs		
66	SMALL PATCH		L	12.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
74	JOINT SPALL		L	2.00	Slabs		
Sample Number: 391		Type:	R	Area:		16.00 Slabs	PCI: 64
Sample Comments:							
63	LINEAR CR		L	4.00	Slabs		
65	JT SEAL DMG		L	16.00	Slabs		
66	SMALL PATCH		L	16.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
74	JOINT SPALL		L	2.00	Slabs		
75	CORNER SPALL		L	1.00	Slabs		
Sample Number: 393		Type:	R	Area:		16.00 Slabs	PCI: 60
Sample Comments:							
63	LINEAR CR		L	14.00	Slabs		
65	JT SEAL DMG		L	16.00	Slabs		
66	SMALL PATCH		L	10.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
75	CORNER SPALL		M	1.00	Slabs		
Sample Number: 398		Type:	R	Area:		16.00 Slabs	PCI: 64
Sample Comments:							

E-25

63	LINEAR CR	L	6.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	15.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	2.00	Slabs

Network:	BKV		Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT							
Branch:	RW 9-27		Name:	RUNWAY 9-27		Use:	RUNWAY	Area:	1,050,000 SqFt		
Section:	6105 of 2		From:	-		To:	-		Last Const.:	1/1/1942	
Surface:	PCC		Family:	C9N59-GA-RW-TW-PCC		Zone:			Rank:	P	
Area:	350,000 SqFt		Length:	14,000 Ft		Width:	25 Ft				
Slabs:	1,120		Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	27,975 Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	3/1/2011		Work Type: FDOT - JOINT SEAL - PCC				Code:	FDOT-JS-PC		Is Major M&R:	False
Last Insp. Date:	3/29/2017		TotalSamples:	70		Surveyed:	14				
Conditions:	PCI: 44										
Inspection Comments:											
Sample Number:	104		Type:	R		Area:	16.00 Slabs		PCI:	42	
Sample Comments:											
63	LINEAR CR		L	3.00 Slabs							
63	LINEAR CR		M	2.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	7.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		M	1.00 Slabs							
75	CORNER SPALL		L	2.00 Slabs							
75	CORNER SPALL		M	1.00 Slabs							
74	JOINT SPALL		L	2.00 Slabs							
70	SCALING		M	1.00 Slabs							
Sample Number:	120		Type:	R		Area:	16.00 Slabs		PCI:	45	
Sample Comments:											
63	LINEAR CR		L	2.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	8.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	2.00 Slabs							
74	JOINT SPALL		M	1.00 Slabs							
75	CORNER SPALL		M	4.00 Slabs							
74	JOINT SPALL		H	1.00 Slabs							
70	SCALING		M	1.00 Slabs							
70	SCALING		L	4.00 Slabs							
Sample Number:	144		Type:	R		Area:	16.00 Slabs		PCI:	49	
Sample Comments:											
63	LINEAR CR		L	2.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	9.00 Slabs							
67	LARGE PATCH		L	3.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
74	JOINT SPALL		M	2.00 Slabs							
75	CORNER SPALL		L	3.00 Slabs							
70	SCALING		L	5.00 Slabs							
70	SCALING		M	3.00 Slabs							
Sample Number:	168		Type:	R		Area:	16.00 Slabs		PCI:	42	
Sample Comments:											
63	LINEAR CR		L	1.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	6.00 Slabs							
67	LARGE PATCH		L	1.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							

E-27



74	JOINT SPALL	L	2.00	Slabs
75	CORNER SPALL	L	2.00	Slabs
75	CORNER SPALL	M	2.00	Slabs
70	SCALING	M	6.00	Slabs
<hr/>				
<b>Sample Number:</b> 188		<b>Type:</b> R	<b>Area:</b> 16.00 Slabs	<b>PCI:</b> 53
<b>Sample Comments:</b>				
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	6.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	4.00	Slabs
75	CORNER SPALL	L	2.00	Slabs
70	SCALING	M	4.00	Slabs
70	SCALING	L	8.00	Slabs
<hr/>				
<b>Sample Number:</b> 208		<b>Type:</b> R	<b>Area:</b> 16.00 Slabs	<b>PCI:</b> 59
<b>Sample Comments:</b>				
63	LINEAR CR	L	2.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	4.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
74	JOINT SPALL	M	2.00	Slabs
70	SCALING	L	5.00	Slabs
70	SCALING	M	1.00	Slabs
<hr/>				
<b>Sample Number:</b> 228		<b>Type:</b> R	<b>Area:</b> 16.00 Slabs	<b>PCI:</b> 35
<b>Sample Comments:</b>				
63	LINEAR CR	L	4.00	Slabs
63	LINEAR CR	M	6.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	9.00	Slabs
67	LARGE PATCH	L	2.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	M	1.00	Slabs
70	SCALING	L	4.00	Slabs
<hr/>				
<b>Sample Number:</b> 504		<b>Type:</b> R	<b>Area:</b> 16.00 Slabs	<b>PCI:</b> 37
<b>Sample Comments:</b>				
63	LINEAR CR	L	8.00	Slabs
63	LINEAR CR	M	2.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	7.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
74	JOINT SPALL	H	1.00	Slabs
75	CORNER SPALL	L	2.00	Slabs
70	SCALING	M	1.00	Slabs
<hr/>				
<b>Sample Number:</b> 520		<b>Type:</b> R	<b>Area:</b> 16.00 Slabs	<b>PCI:</b> 33
<b>Sample Comments:</b>				
63	LINEAR CR	L	6.00	Slabs
63	LINEAR CR	M	2.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	8.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	M	4.00	Slabs
74	JOINT SPALL	H	1.00	Slabs
75	CORNER SPALL	L	3.00	Slabs
75	CORNER SPALL	M	1.00	Slabs
70	SCALING	L	5.00	Slabs
<hr/>				
<b>Sample Number:</b> 536		<b>Type:</b> R	<b>Area:</b> 16.00 Slabs	<b>PCI:</b> 33
<b>Sample Comments:</b>				
63	LINEAR CR	L	4.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	4.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
67	LARGE PATCH	M	1.00	Slabs

73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	M	2.00	Slabs
75	CORNER SPALL	L	2.00	Slabs
75	CORNER SPALL	M	1.00	Slabs
63	LINEAR CR	M	4.00	Slabs
74	JOINT SPALL	H	1.00	Slabs

**Sample Number:** 556      **Type:** R      **Area:** 16.00 Slabs      **PCI:** 35

**Sample Comments:**

63	LINEAR CR	L	4.00	Slabs
63	LINEAR CR	M	6.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	6.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
74	JOINT SPALL	M	1.00	Slabs
75	CORNER SPALL	L	2.00	Slabs

**Sample Number:** 592      **Type:** R      **Area:** 16.00 Slabs      **PCI:** 49

**Sample Comments:**

63	LINEAR CR	L	9.00	Slabs
63	LINEAR CR	M	1.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	10.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
70	SCALING	M	1.00	Slabs
70	SCALING	L	8.00	Slabs

**Sample Number:** 616      **Type:** R      **Area:** 16.00 Slabs      **PCI:** 58

**Sample Comments:**

63	LINEAR CR	L	1.00	Slabs
63	LINEAR CR	M	1.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	9.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
70	SCALING	L	8.00	Slabs
70	SCALING	M	1.00	Slabs

**Sample Number:** 628      **Type:** R      **Area:** 16.00 Slabs      **PCI:** 47

**Sample Comments:**

63	LINEAR CR	L	5.00	Slabs
63	LINEAR CR	M	2.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	6.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
75	CORNER SPALL	M	1.00	Slabs
70	SCALING	L	8.00	Slabs

Network:	BKV		Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT							
Branch:	RW 9-27		Name:	RUNWAY 9-27		Use:	RUNWAY	Area:	1,050,000 SqFt		
Section:	6110 of 2		From:	-		To:	-		Last Const.:	1/1/1942	
Surface:	PCC		Family:	C9N59-GA-RW-TW-PCC		Zone:			Rank:	P	
Area:	700,000 SqFt		Length:	7,000 Ft		Width:	100 Ft				
Slabs:	2,240		Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	76,900 Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	3/1/2011		Work Type: JT SEAL DMG				Code:	JS-LC		Is Major M&R:	False
Last Insp. Date:	3/29/2017		TotalSamples:	140		Surveyed: 20					
Conditions:	PCI: 55										
Inspection Comments:											
Sample Number:	300		Type:	R		Area:	16.00 Slabs		PCI:	45	
Sample Comments:											
63	LINEAR CR		L	12.00 Slabs							
63	LINEAR CR		M	1.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	9.00 Slabs							
67	LARGE PATCH		L	2.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
74	JOINT SPALL		M	2.00 Slabs							
75	CORNER SPALL		L	4.00 Slabs							
Sample Number:	306		Type:	R		Area:	16.00 Slabs		PCI:	50	
Sample Comments:											
63	LINEAR CR		L	11.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	9.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
63	LINEAR CR		M	2.00 Slabs							
Sample Number:	314		Type:	R		Area:	16.00 Slabs		PCI:	57	
Sample Comments:											
63	LINEAR CR		L	9.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	12.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
63	LINEAR CR		M	1.00 Slabs							
Sample Number:	321		Type:	R		Area:	16.00 Slabs		PCI:	57	
Sample Comments:											
63	LINEAR CR		L	10.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	12.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
63	LINEAR CR		M	1.00 Slabs							
Sample Number:	328		Type:	R		Area:	16.00 Slabs		PCI:	48	
Sample Comments:											
63	LINEAR CR		L	9.00 Slabs							
65	JT SEAL DMG		L	16.00 Slabs							
66	SMALL PATCH		L	8.00 Slabs							
67	LARGE PATCH		L	6.00 Slabs							

E-30

73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
63	LINEAR CR	M	1.00	Slabs
<hr/>				
<b>Sample Number:</b>	335	<b>Type:</b>	R	<b>Area:</b> 16.00 Slabs <b>PCI:</b> 39
<b>Sample Comments:</b>				
63	LINEAR CR	L	6.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	12.00	Slabs
67	LARGE PATCH	L	3.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
75	CORNER SPALL	L	1.00	Slabs
63	LINEAR CR	M	4.00	Slabs
<hr/>				
<b>Sample Number:</b>	342	<b>Type:</b>	R	<b>Area:</b> 16.00 Slabs <b>PCI:</b> 60
<b>Sample Comments:</b>				
63	LINEAR CR	L	13.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	10.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
75	CORNER SPALL	L	1.00	Slabs
<hr/>				
<b>Sample Number:</b>	349	<b>Type:</b>	R	<b>Area:</b> 16.00 Slabs <b>PCI:</b> 53
<b>Sample Comments:</b>				
63	LINEAR CR	L	7.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	9.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	M	1.00	Slabs
63	LINEAR CR	M	1.00	Slabs
<hr/>				
<b>Sample Number:</b>	356	<b>Type:</b>	R	<b>Area:</b> 16.00 Slabs <b>PCI:</b> 60
<b>Sample Comments:</b>				
63	LINEAR CR	L	3.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	7.00	Slabs
67	LARGE PATCH	L	2.00	Slabs
71	FAULTING	L	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
<hr/>				
<b>Sample Number:</b>	363	<b>Type:</b>	R	<b>Area:</b> 16.00 Slabs <b>PCI:</b> 57
<b>Sample Comments:</b>				
63	LINEAR CR	L	11.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	9.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
63	LINEAR CR	M	1.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
<hr/>				
<b>Sample Number:</b>	370	<b>Type:</b>	R	<b>Area:</b> 16.00 Slabs <b>PCI:</b> 63
<b>Sample Comments:</b>				
63	LINEAR CR	L	7.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	8.00	Slabs
66	SMALL PATCH	M	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
<hr/>				
<b>Sample Number:</b>	374	<b>Type:</b>	R	<b>Area:</b> 16.00 Slabs <b>PCI:</b> 63
<b>Sample Comments:</b>				
63	LINEAR CR	L	7.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
66	SMALL PATCH	L	10.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs

<b>Sample Number:</b> 377		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 60
<b>Sample Comments:</b>					
63	LINEAR CR	L	5.00	Slabs	
63	LINEAR CR	M	1.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	7.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
<b>Sample Number:</b> 384		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 65
<b>Sample Comments:</b>					
63	LINEAR CR	L	11.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	8.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
<b>Sample Number:</b> 398		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 60
<b>Sample Comments:</b>					
63	LINEAR CR	L	7.00	Slabs	
63	LINEAR CR	M	1.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	10.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
<b>Sample Number:</b> 409		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 61
<b>Sample Comments:</b>					
63	LINEAR CR	L	9.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	7.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
<b>Sample Number:</b> 419		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 50
<b>Sample Comments:</b>					
63	LINEAR CR	L	6.00	Slabs	
63	LINEAR CR	M	3.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	9.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
<b>Sample Number:</b> 426		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 51
<b>Sample Comments:</b>					
63	LINEAR CR	L	6.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	9.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
63	LINEAR CR	M	2.00	Slabs	
<b>Sample Number:</b> 435		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 55
<b>Sample Comments:</b>					
63	LINEAR CR	L	6.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
63	LINEAR CR	M	1.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
<b>Sample Number:</b> 439		<b>Type:</b> R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b> 45
<b>Sample Comments:</b>					
63	LINEAR CR	L	8.00	Slabs	
63	LINEAR CR	M	3.00	Slabs	
65	JT SEAL DMG	L	16.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	M	2.00	Slabs	



Network:	BKV		Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	648,307 SqFt		
Section:	105	of 2	From:	-		To:	-		Last Const.:	1/1/1942	
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC		Zone:			Category:	Rank: P		
Area:	636,744 SqFt		Length:	8,400 Ft		Width:	75 Ft				
Slabs:	2,038	Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	67,125 Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/29/2017		TotalSamples:	169		Surveyed:	13				
Conditions:	PCI: 48										
Inspection Comments:											
Sample Number:	107	Type:	R	Area:	12.00 Slabs		PCI:	48			
Sample Comments:											
63	LINEAR CR	L	1.00	Slabs							
65	JT SEAL DMG	L	12.00	Slabs							
66	SMALL PATCH	L	4.00	Slabs							
66	SMALL PATCH	M	4.00	Slabs							
67	LARGE PATCH	L	1.00	Slabs							
73	SHRINKAGE CR	N	12.00	Slabs							
74	JOINT SPALL	L	2.00	Slabs							
63	LINEAR CR	M	1.00	Slabs							
70	SCALING	M	1.00	Slabs							
Sample Number:	121	Type:	R	Area:	12.00 Slabs		PCI:	49			
Sample Comments:											
63	LINEAR CR	L	1.00	Slabs							
65	JT SEAL DMG	L	12.00	Slabs							
66	SMALL PATCH	L	3.00	Slabs							
66	SMALL PATCH	M	1.00	Slabs							
66	SMALL PATCH	H	2.00	Slabs							
73	SHRINKAGE CR	N	12.00	Slabs							
74	JOINT SPALL	L	1.00	Slabs							
74	JOINT SPALL	M	1.00	Slabs							
70	SCALING	M	2.00	Slabs							
70	SCALING	L	5.00	Slabs							
Sample Number:	135	Type:	R	Area:	12.00 Slabs		PCI:	61			
Sample Comments:											
65	JT SEAL DMG	L	12.00	Slabs							
66	SMALL PATCH	L	7.00	Slabs							
67	LARGE PATCH	L	1.00	Slabs							
73	SHRINKAGE CR	N	12.00	Slabs							
75	CORNER SPALL	L	2.00	Slabs							
70	SCALING	M	1.00	Slabs							
70	SCALING	L	3.00	Slabs							
Sample Number:	149	Type:	R	Area:	12.00 Slabs		PCI:	39			
Sample Comments:											
63	LINEAR CR	L	1.00	Slabs							
63	LINEAR CR	M	2.00	Slabs							
65	JT SEAL DMG	L	12.00	Slabs							
66	SMALL PATCH	L	6.00	Slabs							
66	SMALL PATCH	M	2.00	Slabs							
67	LARGE PATCH	L	1.00	Slabs							
71	FAULTING	L	1.00	Slabs							
73	SHRINKAGE CR	N	12.00	Slabs							
75	CORNER SPALL	M	1.00	Slabs							

<b>Sample Number:</b> 163		<b>Type:</b> R	<b>Area:</b>	12.00 Slabs	<b>PCI:</b> 62
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	12.00	Slabs	
66	SMALL PATCH	L	8.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	12.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
70	SCALING	L	6.00	Slabs	
<b>Sample Number:</b> 177		<b>Type:</b> R	<b>Area:</b>	12.00 Slabs	<b>PCI:</b> 60
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	12.00	Slabs	
66	SMALL PATCH	L	6.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	12.00	Slabs	
70	SCALING	L	2.00	Slabs	
70	SCALING	M	2.00	Slabs	
<b>Sample Number:</b> 191		<b>Type:</b> R	<b>Area:</b>	17.00 Slabs	<b>PCI:</b> 40
<b>Sample Comments:</b>					
63	LINEAR CR	L	7.00	Slabs	
65	JT SEAL DMG	L	17.00	Slabs	
66	SMALL PATCH	L	7.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
72	SHAT. SLAB	L	1.00	Slabs	
73	SHRINKAGE CR	N	17.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
75	CORNER SPALL	L	2.00	Slabs	
63	LINEAR CR	M	2.00	Slabs	
<b>Sample Number:</b> 205		<b>Type:</b> R	<b>Area:</b>	12.00 Slabs	<b>PCI:</b> 39
<b>Sample Comments:</b>					
63	LINEAR CR	M	3.00	Slabs	
65	JT SEAL DMG	L	12.00	Slabs	
66	SMALL PATCH	L	7.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	12.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
70	SCALING	M	2.00	Slabs	
<b>Sample Number:</b> 226		<b>Type:</b> R	<b>Area:</b>	12.00 Slabs	<b>PCI:</b> 47
<b>Sample Comments:</b>					
63	LINEAR CR	L	3.00	Slabs	
65	JT SEAL DMG	L	12.00	Slabs	
66	SMALL PATCH	L	6.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	12.00	Slabs	
62	CORNER BREAK	L	1.00	Slabs	
70	SCALING	M	3.00	Slabs	
70	SCALING	L	3.00	Slabs	
<b>Sample Number:</b> 240		<b>Type:</b> R	<b>Area:</b>	14.00 Slabs	<b>PCI:</b> 43
<b>Sample Comments:</b>					
63	LINEAR CR	M	1.00	Slabs	
65	JT SEAL DMG	L	14.00	Slabs	
66	SMALL PATCH	L	7.00	Slabs	
66	SMALL PATCH	M	4.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	14.00	Slabs	
75	CORNER SPALL	L	3.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
70	SCALING	M	3.00	Slabs	
70	SCALING	L	2.00	Slabs	

<b>Sample Number:</b> 247		<b>Type:</b> R	<b>Area:</b> 12.00 Slabs	<b>PCI:</b> 54
<b>Sample Comments:</b>				
65	JT SEAL DMG	L	12.00 Slabs	
66	SMALL PATCH	L	6.00 Slabs	
66	SMALL PATCH	M	1.00 Slabs	
67	LARGE PATCH	L	2.00 Slabs	
73	SHRINKAGE CR	N	12.00 Slabs	
70	SCALING	M	3.00 Slabs	
70	SCALING	L	2.00 Slabs	
<b>Sample Number:</b> 254		<b>Type:</b> R	<b>Area:</b> 12.00 Slabs	<b>PCI:</b> 47
<b>Sample Comments:</b>				
63	LINEAR CR	L	2.00 Slabs	
65	JT SEAL DMG	L	12.00 Slabs	
66	SMALL PATCH	L	7.00 Slabs	
66	SMALL PATCH	M	1.00 Slabs	
67	LARGE PATCH	L	1.00 Slabs	
73	SHRINKAGE CR	N	12.00 Slabs	
74	JOINT SPALL	M	1.00 Slabs	
70	SCALING	M	3.00 Slabs	
<b>Sample Number:</b> 268		<b>Type:</b> R	<b>Area:</b> 12.00 Slabs	<b>PCI:</b> 37
<b>Sample Comments:</b>				
63	LINEAR CR	L	3.00 Slabs	
65	JT SEAL DMG	L	12.00 Slabs	
66	SMALL PATCH	L	7.00 Slabs	
71	FAULTING	L	2.00 Slabs	
73	SHRINKAGE CR	N	12.00 Slabs	
74	JOINT SPALL	L	3.00 Slabs	
75	CORNER SPALL	M	1.00 Slabs	
63	LINEAR CR	M	1.00 Slabs	
70	SCALING	M	3.00 Slabs	

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	648,307 SqFt		
Section:	108	of	2	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC	Zone:		Category:		Rank:	P
Area:	11,563 SqFt	Length:	110 Ft	Width:	100 Ft				
Slabs:	35	Slab Length:	12 Ft	Slab Width:	25 Ft	Joint Length:	1,110 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2013	Work Type:	New Construction - PCC		Code:	NC-PC	Is Major M&R:	True	
Last Insp. Date:	3/29/2017	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI: 98								
Inspection Comments:									
Sample Number:	194	Type:	R	Area:	12.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L	12.00	Slabs					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY	Area:	92,918 SqFt		
Section:	110	of	3	From:	-	To:	-	Last Const.:	1/1/1942		
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC		Zone:		Category:		Rank:	P	
Area:	56,894 SqFt		Length:	750 Ft		Width:	75 Ft				
Slabs:	182	Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	5,925 Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date: 3/29/2017											
TotalSamples:			15		Surveyed: 3						
Conditions:	PCI: 50										
Inspection Comments:											
Sample Number:	101	Type:	R	Area:	12.00 Slabs		PCI:	57			
Sample Comments:											
63	LINEAR CR		L	1.00 Slabs							
63	LINEAR CR		M	1.00 Slabs							
65	JT SEAL DMG		L	12.00 Slabs							
66	SMALL PATCH		L	3.00 Slabs							
67	LARGE PATCH		L	2.00 Slabs							
73	SHRINKAGE CR		N	12.00 Slabs							
62	CORNER BREAK		L	1.00 Slabs							
Sample Number:	106	Type:	R	Area:	14.00 Slabs		PCI:	42			
Sample Comments:											
63	LINEAR CR		M	2.00 Slabs							
65	JT SEAL DMG		L	14.00 Slabs							
66	SMALL PATCH		L	5.00 Slabs							
67	LARGE PATCH		L	3.00 Slabs							
71	FAULTING		L	1.00 Slabs							
73	SHRINKAGE CR		N	14.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
74	JOINT SPALL		H	1.00 Slabs							
75	CORNER SPALL		L	2.00 Slabs							
Sample Number:	111	Type:	R	Area:	12.00 Slabs		PCI:	54			
Sample Comments:											
63	LINEAR CR		L	7.00 Slabs							
65	JT SEAL DMG		L	12.00 Slabs							
66	SMALL PATCH		L	2.00 Slabs							
71	FAULTING		L	1.00 Slabs							
73	SHRINKAGE CR		N	12.00 Slabs							
74	JOINT SPALL		L	3.00 Slabs							
75	CORNER SPALL		L	4.00 Slabs							



Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY		Area:	92,918 SqFt	
Section:	111 of 3		From:	-			To:	-		Last Const.:	1/1/1991
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	17,870 SqFt		Length:	445 Ft		Width:	40 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1964		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/2015		Work Type: Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R: False	
Last Insp. Date:	3/29/2017		TotalSamples:	4		Surveyed:		1			
Conditions:	PCI: 74										
Inspection Comments:											
Sample Number:	116		Type:	R		Area:	4022.00 SqFt		PCI:	74	
Sample Comments:											
48	L & T CR		L	340.00 Ft							
57	WEATHERING		L	4022.00 SqFt							

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY	Area:	92,918 SqFt		
Section:	112	of 3	From:	-			To:	-		Last Const.:	1/1/1964
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	18,154 SqFt		Length:	450 Ft		Width:	40 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1964		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2015		Work Type:	Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	3/29/2017		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI:	51									
Inspection Comments:											
Sample Number:	119	Type:	R	Area:	4000.00 SqFt		PCI:	51			
Sample Comments:											
43	BLOCK CR	L	3600.00	SqFt							
43	BLOCK CR	M	400.00	SqFt							
45	DEPRESSION	L	30.00	SqFt							
57	WEATHERING	L	4000.00	SqFt							

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW A3	Name:	TAXIWAY A3	Use:	TAXIWAY	Area:	37,159 SqFt		
Section:	120	of	2	From:	-	To:	-	Last Const.:	1/1/1942
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC	Zone:		Category:		Rank:	P
Area:	10,837 SqFt	Length:	413 Ft	Width:	25 Ft				
Slabs:	33	Slab Length:	13 Ft	Slab Width:	25 Ft	Joint Length:	801 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1942	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1942	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/29/2017	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI: 35								
Inspection Comments:									
Sample Number:	401	Type:	R	Area:	20.00 Slabs	PCI:	35		
Sample Comments:									
63	LINEAR CR	L	1.00	Slabs					
63	LINEAR CR	M	7.00	Slabs					
65	JT SEAL DMG	L	20.00	Slabs					
66	SMALL PATCH	L	10.00	Slabs					
67	LARGE PATCH	M	3.00	Slabs					
73	SHRINKAGE CR	N	20.00	Slabs					
74	JOINT SPALL	L	1.00	Slabs					
75	CORNER SPALL	L	1.00	Slabs					

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW A3	Name:	TAXIWAY A3	Use:	TAXIWAY	Area:	37,159 SqFt		
Section:	125	of	2	From:	-	To:	-	Last Const.:	1/1/1986
Surface:	AC	Family:	C9N59-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	26,322 SqFt	Length:	400 Ft	Width:	53 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1986	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/1986	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True		
Last Insp. Date:	3/29/2017	TotalSamples:	5	Surveyed:		1			
Conditions:	PCI:	15							
Inspection Comments:									
Sample Number:	301	Type:	R	Area:	5099.00 SqFt	PCI:	15		
Sample Comments:									
43	BLOCK CR	L	982.00	SqFt					
48	L & T CR	L	477.00	Ft					
48	L & T CR	M	200.00	Ft					
52	RAVELING	M	4334.00	SqFt					
52	RAVELING	H	765.00	SqFt					

<b>Network:</b>	BKV			<b>Name:</b>	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
<b>Branch:</b>	TW A5		<b>Name:</b>	TAXIWAY A5		<b>Use:</b>	TAXIWAY	<b>Area:</b>	33,046 SqFt
<b>Section:</b>	130	of	1	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b>	1/1/1942
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC		<b>Zone:</b>		<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	33,046 SqFt	<b>Length:</b>	430 Ft		<b>Width:</b>	75 Ft			
<b>Slabs:</b>	104	<b>Slab Length:</b>	13 Ft		<b>Slab Width:</b>	25 Ft		<b>Joint Length:</b>	3,365 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0			<b>Lanes:</b>	0
<b>Section Comments:</b>									
<b>Work Date:</b>	1/1/1942		<b>Work Type:</b> OVERLAY			<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1942		<b>Work Type:</b> BUILT			<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	3/29/2017		<b>TotalSamples:</b>	8		<b>Surveyed:</b>	2		
<b>Conditions:</b>	<b>PCI:</b> 48								
<b>Inspection Comments:</b>									
<b>Sample Number:</b>	502	<b>Type:</b>	R	<b>Area:</b>	12.00 Slabs	<b>PCI:</b>	55		
<b>Sample Comments:</b>									
63	LINEAR CR	L	3.00	Slabs					
65	JT SEAL DMG	L	12.00	Slabs					
66	SMALL PATCH	L	3.00	Slabs					
73	SHRINKAGE CR	N	12.00	Slabs					
63	LINEAR CR	M	2.00	Slabs					
<b>Sample Number:</b>	506	<b>Type:</b>	R	<b>Area:</b>	12.00 Slabs	<b>PCI:</b>	42		
<b>Sample Comments:</b>									
63	LINEAR CR	L	5.00	Slabs					
63	LINEAR CR	M	4.00	Slabs					
65	JT SEAL DMG	L	12.00	Slabs					
66	SMALL PATCH	L	6.00	Slabs					
73	SHRINKAGE CR	N	12.00	Slabs					



Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW A6		Name:	TAXIWAY A6		Use:	TAXIWAY	Area:	31,614 SqFt		
Section:	135	of	1	From:	-		To:	-	Last Const.:	1/1/1986	
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	31,614 SqFt		Length:	500 Ft		Width:	53 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1986		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/29/2017		TotalSamples:	8		Surveyed: 2					
Conditions:	PCI:	16									
Inspection Comments:											
Sample Number:	603	Type:	R	Area:	2570.00 SqFt		PCI:	20			
Sample Comments:											
48	L & T CR		L	290.00	Ft						
48	L & T CR		M	100.00	Ft						
52	RAVELING		M	2313.00	SqFt						
52	RAVELING		H	257.00	SqFt						
Sample Number:	605	Type:	R	Area:	2769.00 SqFt		PCI:	13			
Sample Comments:											
43	BLOCK CR		L	406.00	SqFt						
48	L & T CR		L	278.00	Ft						
48	L & T CR		M	166.00	Ft						
50	PATCHING		L	760.00	SqFt						
52	RAVELING		M	1732.00	SqFt						
52	RAVELING		H	277.00	SqFt						

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT					
Branch:	TW A9		Name:	TAXIWAY A9		Use:	TAXIWAY	Area:	31,973 SqFt	
Section:	140	of	1	From:	-	To:	-	Last Const.:	1/1/1942	
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC		Zone:		Category:		Rank: P	
Area:	31,973 SqFt	Length:	420 Ft		Width:	75 Ft				
Slabs:	102	Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	3,285 Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1942		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1942		Work Type: BUILT			Code:	IMPORTED		Is Major M&R: True	
Last Insp. Date:	3/29/2017		TotalSamples:	8		Surveyed:	2			
Conditions:	PCI:	58								
Inspection Comments:										
Sample Number:	902	Type:	R	Area:	12.00 Slabs		PCI:	59		
Sample Comments:										
63	LINEAR CR	L	3.00 Slabs							
63	LINEAR CR	M	1.00 Slabs							
65	JT SEAL DMG	L	12.00 Slabs							
66	SMALL PATCH	L	6.00 Slabs							
73	SHRINKAGE CR	N	12.00 Slabs							
74	JOINT SPALL	L	1.00 Slabs							
Sample Number:	906	Type:	R	Area:	12.00 Slabs		PCI:	57		
Sample Comments:										
63	LINEAR CR	L	4.00 Slabs							
65	JT SEAL DMG	L	12.00 Slabs							
66	SMALL PATCH	L	7.00 Slabs							
66	SMALL PATCH	M	1.00 Slabs							
67	LARGE PATCH	L	4.00 Slabs							
73	SHRINKAGE CR	N	12.00 Slabs							

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	173,973 SqFt
Section:	205	of	2	From:	-	To:	-	Last Const.:	1/1/1990
Surface:	AC	Family:	C9N59-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	55,550 SqFt	Length:	1,580 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1990	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1990	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/29/2017	TotalSamples:	15	Surveyed:	3				
Conditions:	PCI: 35								
Inspection Comments:									
Sample Number:	137	Type:	R	Area:	3500.00 SqFt	PCI:	45		
Sample Comments:									
48	L & T CR	L	272.00	Ft					
48	L & T CR	M	120.00	Ft					
52	RAVELING	L	2000.00	SqFt					
52	RAVELING	M	1500.00	SqFt					
Sample Number:	143	Type:	R	Area:	3500.00 SqFt	PCI:	40		
Sample Comments:									
48	L & T CR	L	92.00	Ft					
48	L & T CR	M	244.00	Ft					
52	RAVELING	L	2000.00	SqFt					
52	RAVELING	M	1500.00	SqFt					
Sample Number:	148	Type:	R	Area:	5973.00 SqFt	PCI:	27		
Sample Comments:									
48	L & T CR	L	352.00	Ft					
48	L & T CR	M	335.00	Ft					
52	RAVELING	L	2182.00	SqFt					
52	RAVELING	M	3573.00	SqFt					
52	RAVELING	H	218.00	SqFt					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	173,973 SqFt
Section:	210	of	2	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	AC	Family:	C9N59-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	118,423 SqFt	Length:	3,375 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1991	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1991	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/29/2017	TotalSamples:	34	Surveyed:	5				
Conditions:	PCI: 60								
Inspection Comments:									
Sample Number:	104	Type:	R	Area:	3500.00 SqFt	PCI:	57		
Sample Comments:									
48	L & T CR	L	260.00 Ft						
48	L & T CR	M	149.00 Ft						
52	RAVELING	L	3500.00 SqFt						
Sample Number:	112	Type:	R	Area:	3500.00 SqFt	PCI:	61		
Sample Comments:									
48	L & T CR	L	244.00 Ft						
48	L & T CR	M	110.00 Ft						
52	RAVELING	L	3500.00 SqFt						
Sample Number:	120	Type:	R	Area:	3500.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	L	286.00 Ft						
48	L & T CR	M	20.00 Ft						
52	RAVELING	L	3500.00 SqFt						
Sample Number:	128	Type:	R	Area:	3500.00 SqFt	PCI:	59		
Sample Comments:									
48	L & T CR	L	299.00 Ft						
48	L & T CR	M	100.00 Ft						
52	RAVELING	L	3500.00 SqFt						
Sample Number:	132	Type:	R	Area:	3500.00 SqFt	PCI:	61		
Sample Comments:									
48	L & T CR	L	250.00 Ft						
48	L & T CR	M	106.00 Ft						
52	RAVELING	L	3500.00 SqFt						

<b>Network:</b>	BKV			<b>Name:</b>	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT							
<b>Branch:</b>	TW B1		<b>Name:</b>	TAXIWAY B1		<b>Use:</b>	TAXIWAY		<b>Area:</b>	190,128 SqFt		
<b>Section:</b>	145	of	3	<b>From:</b>	-			<b>To:</b>	-		<b>Last Const.:</b>	1/1/1998
<b>Surface:</b>	AC	<b>Family:</b>	C9N59-GA-TW-AC		<b>Zone:</b>				<b>Category:</b>	<b>Rank:</b> P		
<b>Area:</b>	80,954 SqFt		<b>Length:</b>	1,000 Ft		<b>Width:</b>	76 Ft					
<b>Slabs:</b>	<b>Slab Length:</b>		Ft		<b>Slab Width:</b>	Ft			<b>Joint Length:</b>	Ft		
<b>Shoulder:</b>	<b>Street Type:</b>				<b>Grade:</b>	0			<b>Lanes:</b>	0		
<b>Section Comments:</b>												
<b>Work Date:</b>	1/1/1998		<b>Work Type:</b> BUILT				<b>Code:</b>	IMPORTED		<b>Is Major M&amp;R:</b>	True	
<b>Last Insp. Date:</b>	3/29/2017		<b>TotalSamples:</b>	18		<b>Surveyed:</b>	3					
<b>Conditions:</b>	<b>PCI:</b>	61										
<b>Inspection Comments:</b>												
<b>Sample Number:</b>	302	<b>Type:</b>	R	<b>Area:</b>	4901.00 SqFt			<b>PCI:</b>	64			
<b>Sample Comments:</b>												
48	L & T CR		L	384.00 Ft								
52	RAVELING		L	4901.00 SqFt								
56	SWELLING		L	136.00 SqFt								
<b>Sample Number:</b>	305	<b>Type:</b>	R	<b>Area:</b>	4131.00 SqFt			<b>PCI:</b>	59			
<b>Sample Comments:</b>												
48	L & T CR		L	183.00 Ft								
52	RAVELING		L	4131.00 SqFt								
56	SWELLING		L	99.00 SqFt								
48	L & T CR		M	50.00 Ft								
<b>Sample Number:</b>	308	<b>Type:</b>	R	<b>Area:</b>	3751.00 SqFt			<b>PCI:</b>	59			
<b>Sample Comments:</b>												
48	L & T CR		L	182.00 Ft								
48	L & T CR		M	100.00 Ft								
52	RAVELING		L	3751.00 SqFt								
56	SWELLING		L	155.00 SqFt								



Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW B1		Name:	TAXIWAY B1		Use:	TAXIWAY	Area:	190,128 SqFt		
Section:	215	of	3	From:	-	To:	-	Last Const.:	1/1/1942		
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC		Zone:		Category:		Rank:	P	
Area:	63,745 SqFt		Length:	810 Ft		Width:	75 Ft				
Slabs:	194	Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	6,405 Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/29/2017		TotalSamples:	16		Surveyed:	3				
Conditions:	PCI: 54										
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	17.00 Slabs		PCI:	39			
Sample Comments:											
63	LINEAR CR	L	9.00		Slabs						
63	LINEAR CR	M	4.00		Slabs						
65	JT SEAL DMG	L	17.00		Slabs						
66	SMALL PATCH	L	4.00		Slabs						
71	FAULTING	L	1.00		Slabs						
73	SHRINKAGE CR	N	17.00		Slabs						
75	CORNER SPALL	M	1.00		Slabs						
Sample Number:	106	Type:	R	Area:	12.00 Slabs		PCI:	71			
Sample Comments:											
65	JT SEAL DMG	L	12.00		Slabs						
66	SMALL PATCH	L	5.00		Slabs						
73	SHRINKAGE CR	N	12.00		Slabs						
75	CORNER SPALL	M	1.00		Slabs						
74	JOINT SPALL	L	1.00		Slabs						
Sample Number:	112	Type:	R	Area:	12.00 Slabs		PCI:	60			
Sample Comments:											
63	LINEAR CR	L	5.00		Slabs						
65	JT SEAL DMG	L	12.00		Slabs						
66	SMALL PATCH	L	6.00		Slabs						
67	LARGE PATCH	L	1.00		Slabs						
73	SHRINKAGE CR	N	12.00		Slabs						
74	JOINT SPALL	L	1.00		Slabs						

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT					
Branch:	TW B1		Name:	TAXIWAY B1		Use:	TAXIWAY	Area:	190,128 SqFt	
Section:	216	of	3	From:	-	To:	-	Last Const.:	1/1/1991	
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:	Category:		Rank:	P	
Area:	45,429 SqFt		Length:	885 Ft		Width:	50 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	1/1/1991		Work Type:			OVERLAY	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1991		Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/29/2017		TotalSamples:	9		Surveyed:				2
Conditions:	PCI: 53									
Inspection Comments:										
Sample Number:	119	Type:	R	Area:	5000.00 SqFt		PCI:	55		
Sample Comments:										
43	BLOCK CR	L	240.00	SqFt						
48	L & T CR	L	737.00	Ft						
52	RAVELING	L	5000.00	SqFt						
56	SWELLING	L	223.00	SqFt						
Sample Number:	123	Type:	R	Area:	5000.00 SqFt		PCI:	51		
Sample Comments:										
43	BLOCK CR	L	3228.00	SqFt						
48	L & T CR	L	109.00	Ft						
52	RAVELING	L	5000.00	SqFt						
56	SWELLING	L	500.00	SqFt						

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW B2	Name:	TAXIWAY B2	Use:	TAXIWAY	Area:	7,309 SqFt		
Section:	220	of	1	From:	-	To:	-	Last Const.:	1/1/1990
Surface:	AC	Family:	C9N59-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	7,309 SqFt	Length:	150 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1990	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1990	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/29/2017	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	33							
Inspection Comments:									
Sample Number:	200	Type:	R	Area:	3610.00 SqFt	PCI:	33		
Sample Comments:									
48	L & T CR	L	200.00	Ft					
48	L & T CR	M	52.00	Ft					
52	RAVELING	M	3610.00	SqFt					

Network:	BKV	Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT						
Branch:	TW B3	Name:	TAXIWAY B3	Use:	TAXIWAY	Area:	7,309 SqFt		
Section:	225	of	1	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	AC	Family:	C9N59-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	7,309 SqFt	Length:	150 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1991	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1991	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/29/2017	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI: 56								
Inspection Comments:									
Sample Number:	301	Type:	R	Area:	3698.00 SqFt	PCI:	56		
Sample Comments:									
45	DEPRESSION	L	16.00	SqFt					
48	L & T CR	L	100.00	Ft					
48	L & T CR	M	270.00	Ft					
52	RAVELING	L	3698.00	SqFt					

Network:	BKV			Name:	BROOKSVILLE - TAMPA BAY REGIONAL AIRPORT									
Branch:	TW B4		Name:	TAXIWAY B4		Use:	TAXIWAY	Area:	6,246 SqFt					
Section:	230		of	1	From:	-		To:	-		Last Const.:	1/1/1991		
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Category:			Rank:	P	
Area:	6,246 SqFt		Length:	150 Ft		Width:	35 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1991			Work Type:	OVERLAY			Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1991			Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True		
Last Insp. Date:	3/29/2017			TotalSamples:	2		Surveyed:	1						
Conditions:	PCI:		56											
Inspection Comments:														
Sample Number:	401		Type:	R		Area:	3274.00 SqFt		PCI:	56				
Sample Comments:														
48	L & T CR		L	131.00		Ft								
48	L & T CR		M	252.00		Ft								
52	RAVELING		L	3274.00		SqFt								