

FLORIDA DEPARTMENT OF TRANSPORTATION
AVIATION AND SPACEPORTS OFFICE

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report September 2017



**Bartow Municipal
Airport (BOW)**
General Aviation Airport
District 1





Florida Department of Transportation

Statewide Airfield Pavement Management Program

Prepared by:

*FDOT Aviation and Spaceports Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*




OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS

Table of Contents


Executive Summary.....	10
Program Background.....	10
Summary of Results.....	11
Pavement Condition Index (Latest Inspection)	11
Forecasted Pavement Condition Index 2018-2027.....	13
Major Rehabilitation Planning 2018-2027	14
Summary of Bartow Municipal Airport.....	16
Chapter 1 – Introduction.....	18
1.1 Background	18
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017	18
1.3 Organization	20
1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager	20
1.3.2 Participating Florida Public-Use and Publicly Owned Airports	20
1.3.3 Florida Department of Transportation District Offices.....	20
1.3.4 Consultant	20
1.4 Purpose of Airport Pavement Evaluation Report	22
1.5 History of the Program.....	22
1.6 Federal Aviation Administration (FAA)	24
1.7 FDOT SAPMP Objectives and Components	24
1.7.1 Program Objectives.....	24
1.7.2 Program Components	24
1.8 References	28
Chapter 2 – Methodology	30
2.1 Airfield Pavement Database.....	30
2.2 Airfield Pavement System Inventory	30
2.2.1 Pavement Management Program Network Definition Terminology	31
2.3 Airfield Pavement Structure.....	33
2.3.1 Pavement Structure Types.....	33
2.4 Airfield Pavement Work History	35
2.4.1 Airfield Pavement Record Keeping	35
2.5 Airfield Pavement Traffic	35
2.6 Airfield Pavement Condition Index (PCI) Survey.....	35
2.6.1 PCI Survey Methodology	35
2.6.2 Pavement Distress Types	37

2.6.3 PCI Survey Inspection Procedures	41
2.6.4 Updates to the ASTM D5340-12	42
Chapter 3 – Airfield Pavement System Inventory	45
3.1 Airfield Pavement Network Information	45
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	45
3.1.2 Estimated Pavement Age.....	47
3.1.3 Functional Use Classification	49
3.1.4 Pavement Surface Type.....	50
3.1.5 Pavement System Inventory Details	51
Chapter 4 – Airfield Pavement Condition	57
4.1 Airfield Pavement Condition Index (Latest Inspection)	57
4.1.1 Network-Level Analysis	57
4.1.2 Branch-Level Analysis.....	57
4.1.3 Section-Level Analysis	60
4.2 Summary of Pavement Condition Evaluation Results	64
4.2.1 Network-Level Observations	64
4.2.2 Branch-Level Observations.....	64
4.3 Forecasted Pavement Conditions	66
4.3.1 Performance Models and Prediction Curves	66
4.3.2 Branch-Level Pavement Condition Forecast	66
4.3.3 Section-Level Pavement Condition Forecast.....	68
4.3.4 Forecasted PCI Considerations	72
Chapter 5 – Localized Maintenance and Repair Planning.....	74
5.1 Localized Maintenance and Repair	74
5.2 Localized Maintenance and Repair Policy	75
5.3 Localized Maintenance and Repair Analysis and Recommendations	79
Chapter 6 – Major Rehabilitation Planning.....	85
6.1 Major Rehabilitation	85
6.1.1 Critical PCI	87
6.1.2 FDOT Recommended Minimum Service-Level PCI	87
6.2 Major Rehabilitation Policy	88
6.2.1 Major Rehabilitation Pavement Section Development.....	88
6.2.2 Major Rehabilitation Planning-Level Unit Costs.....	89
6.3 Major Rehabilitation Needs.....	90
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs	90
Chapter 7 – Conclusion	95
7.1 Recommendations	95
7.1.1 Continued PCI Survey Inspections	95
7.1.2 Localized Maintenance and Repair.....	95

7.1.3 Major Rehabilitation	95
7.1.4 Pavement Management System	95
7.2 Supporting Documents	96
001 – Airfield Pavement Network Definition Exhibit	96
002 – Airfield Pavement System Inventory Exhibit	96
003 – Airfield Pavement Condition Index Exhibit	96
004 – Airfield Pavement Major Rehabilitation Exhibit	96
Inspection Photograph Documentation	96
7.3 Conclusion	97



Appendix A	Airfield Pavement Analysis Tables
Appendix B	Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
Appendix C	Technical Exhibits
Appendix D	Inspection Photograph Documentation
Appendix E	Inspection Distress Details



List of Figures

Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027	16
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts	19
Figure 1.7-1 Typical Pavement Condition Life Cycle	25
Figure 1.7-2 General Pavement Treatments by Condition Range	26
Figure 1.7-3 Flexible Asphalt Concrete	27
Figure 1.7-4 Rigid Portland Cement Concrete	27
Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit	46
Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit	47
Figure 3.1.2 Average Age of Pavements at Inspection	48
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area	49
Figure 3.1.4 (a) Pavement Surface Type by Area (SF)	50
Figure 3.1.4 (b) Pavement Surface Type by Area (%)	51
Figure 4.1.1 Latest Condition – Overall Network	57
Figure 4.1.2 (a) Latest Condition – Runway Pavements	58
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements	58
Figure 4.1.2 (c) Latest Condition – Apron Pavements	59
Figure 4.1.2 (d) Latest Condition – Taxilane Pavements	59
Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit	63
Figure 4.2.2 Pavement Condition Summary by Facility Use	65
Figure 4.3.2 (a) Forecasted Runway Pavement Performance	66
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance	67
Figure 4.3.2 (c) Forecasted Apron Pavement Performance	67
Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, $PCI \leq$ Critical PCI	85
Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, $PCI >$ Critical PCI	86
Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year	92
Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit	93

List of Tables

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level.....	11
Table E-2 Pavement Condition Index Forecast 2018-2027	13
Table E-3 Major Rehabilitation Planning 2018-2027	14
Table 2.2.1 Airfield Pavement Database Network Definition Terminology	32
Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields	37
Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields.....	38
Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields.....	38
Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields..	39
Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields.....	40
Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields.....	40
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete	41
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete....	41
Table 2.6.4 Summary of Updates to ASTM D5340-12.....	43
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction	45
Table 3.1.5 Pavement System Inventory Details	52
Table 4.1.3 Latest Pavement Condition Index Summary.....	61
Table 4.3.3 Forecasted PCI 2018-2027	69
Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete	75
Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete.....	76
Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete	78
Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete .	78

Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level	79
Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level	81
Table 5.3-3 Summary of Localized Maintenance	83
Table 6.1.2 FDOT Recommended Minimum Service-Level PCI	87
Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete	88
Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete	89
Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type	90
Table 6.3.1 10-Year Major Rehabilitation Needs	91



Executive Summary





Executive Summary

Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP)”** using the documented procedures set forth by ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.



Summary of Results

Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BOW	RUNWAY 9L-27R	RUNWAY	6105	30,000	83	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6110	20,000	87	Good
BOW	RUNWAY 9L-27R	RUNWAY	6115	440,000	80	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6118	9,250	73	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6120	170,750	88	Good
BOW	RUNWAY 9L-27R	RUNWAY	6124	30,000	78	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6125	30,000	82	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6130	20,000	86	Good
BOW	RUNWAY 9R-27L	RUNWAY	6205	350,236	22	Serious
BOW	RUNWAY 9R-27L	RUNWAY	6210	175,118	26	Very Poor
BOW	RUNWAY 9R-27L	RUNWAY	6215	30,000	76	Satisfactory
BOW	RUNWAY 9R-27L	RUNWAY	6220	15,000	77	Satisfactory
BOW	RUNWAY 9R-27L	RUNWAY	6225	44,518	69	Fair
BOW	RUNWAY 9R-27L	RUNWAY	6230	22,390	66	Fair
BOW	RUNWAY 5-23	RUNWAY	6305	30,000	53	Poor
BOW	RUNWAY 5-23	RUNWAY	6310	55,000	49	Poor
BOW	RUNWAY 5-23	RUNWAY	6315	353,620	53	Poor
BOW	RUNWAY 5-23	RUNWAY	6320	40,640	78	Satisfactory
BOW	TAXIWAY A1	TAXIWAY	105	93,327	82	Satisfactory
BOW	TAXIWAY A2	TAXIWAY	110	33,575	86	Good
BOW	TAXIWAY A2	TAXIWAY	112	43,953	69	Fair
BOW	TAXIWAY A2	TAXIWAY	114	6,638	84	Satisfactory
BOW	TAXIWAY A3	TAXIWAY	115	44,009	41	Poor
BOW	TAXIWAY C1	TAXIWAY	305	18,037	86	Good
BOW	TAXIWAY C2	TAXIWAY	310	30,619	56	Fair
BOW	TAXIWAY C3	TAXIWAY	315	41,491	58	Fair
BOW	TAXIWAY C3	TAXIWAY	320	4,912	38	Very Poor
BOW	TAXIWAY D	TAXIWAY	405	95,846	81	Satisfactory
BOW	TAXIWAY D	TAXIWAY	407	15,000	83	Satisfactory
BOW	TAXIWAY D	TAXIWAY	410	72,003	100	Good
BOW	TAXIWAY D	TAXIWAY	415	76,821	100	Good
BOW	TAXIWAY D	TAXIWAY	420	81,983	67	Fair
BOW	TAXIWAY D	TAXIWAY	425	32,996	69	Fair
BOW	TAXIWAY F	TAXIWAY	605	10,259	76	Satisfactory



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BOW	TAXIWAY F	TAXIWAY	610	30,778	42	Poor
BOW	TAXIWAY F	TAXIWAY	615	5,898	65	Fair
BOW	TAXIWAY F	TAXIWAY	620	37,090	88	Good
BOW	TAXIWAY G	TAXIWAY	705	32,612	39	Very Poor
BOW	TAXIWAY G	TAXIWAY	710	34,447	23	Serious
BOW	TAXIWAY H	TAXIWAY	802	3,573	84	Satisfactory
BOW	TAXIWAY H	TAXIWAY	805	24,823	90	Good
BOW	T-HANGAR TAXILANE	TAXILANE	4205	120,980	47	Poor
BOW	T-HANGAR TAXILANE	TAXILANE	4305	28,752	64	Fair
BOW	T-HANGAR TAXILANE	TAXILANE	4310	10,686	89	Good
BOW	NORTH APRON	APRON	4105	24,590	54	Poor
BOW	NORTH APRON	APRON	4107	39,764	86	Good
BOW	NORTH APRON	APRON	4110	254,768	23	Serious
BOW	NORTH APRON	APRON	4112	34,136	96	Good
BOW	NORTH APRON	APRON	4115	30,089	58	Fair
BOW	NORTH APRON	APRON	4120	4,597	63	Fair
BOW	NORTH APRON	APRON	4125	23,419	64	Fair
BOW	NORTH APRON	APRON	4127	6,397	59	Fair
BOW	NORTH APRON	APRON	4130	146,118	64	Fair
BOW	NORTH APRON	APRON	4132	17,250	15	Serious
BOW	T-HANGAR APRON	APRON	4210	30,250	69	Fair
BOW	APRON FBO	APRON	4405	83,163	66	Fair
BOW	HOLD APRON ON TW A	APRON	5105	29,073	26	Very Poor



Forecasted Pavement Condition Index 2018-2027

Table E-2 Pavement Condition Index Forecast 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BOW	AP FBO	4405	66	64	63	61	59	58	56	55	53	51	50
BOW	AP H TW A	5105	26	24	23	21	19	18	16	15	13	11	10
BOW	AP N	4105	54	53	52	52	52	52	52	52	51	50	48
BOW	AP N	4107	86	83	82	80	79	77	76	74	71	69	66
BOW	AP N	4110	23	22	20	19	18	17	16	15	14	13	12
BOW	AP N	4112	96	93	90	87	84	82	79	77	74	72	70
BOW	AP N	4115	58	56	54	53	53	52	52	52	52	52	52
BOW	AP N	4120	63	60	58	56	55	54	53	52	52	52	52
BOW	AP N	4125	64	61	59	57	55	54	53	52	52	52	52
BOW	AP N	4127	59	57	56	54	52	51	49	48	46	44	43
BOW	AP N	4130	64	62	61	59	58	56	55	54	53	52	51
BOW	AP N	4132	15	14	12	11	10	9	8	7	6	5	4
BOW	AP T-HANG	4210	69	67	65	63	62	60	59	57	56	55	54
BOW	RW 5-23	6305	53	50	48	45	41	38	35	32	30	27	24
BOW	RW 5-23	6310	49	46	43	39	36	33	31	28	26	23	20
BOW	RW 5-23	6315	53	50	48	45	41	38	35	32	30	27	24
BOW	RW 5-23	6320	78	75	73	71	69	67	65	64	63	62	61
BOW	RW 9L-27R	6105	83	80	78	76	73	71	69	67	65	64	63
BOW	RW 9L-27R	6110	87	85	82	80	77	75	72	70	68	66	65
BOW	RW 9L-27R	6115	80	77	75	73	70	68	67	65	64	62	62
BOW	RW 9L-27R	6118	73	71	69	67	65	64	63	62	61	61	60
BOW	RW 9L-27R	6120	88	86	83	81	78	76	73	71	69	67	65
BOW	RW 9L-27R	6124	78	75	73	71	69	67	65	64	63	62	61
BOW	RW 9L-27R	6125	82	79	77	75	72	70	68	66	65	63	62
BOW	RW 9L-27R	6130	86	84	81	79	76	74	71	69	67	66	64
BOW	RW 9R-27L	6205	22	20	19	17	15	14	12	10	9	7	6
BOW	RW 9R-27L	6210	26	24	23	21	19	18	16	14	13	11	10
BOW	RW 9R-27L	6215	76	75	74	73	72	71	71	70	69	68	67
BOW	RW 9R-27L	6220	77	76	75	74	73	72	72	71	70	69	68
BOW	RW 9R-27L	6225	69	67	65	64	63	62	61	61	60	60	60
BOW	RW 9R-27L	6230	66	64	63	62	61	61	60	60	60	60	60
BOW	T-HANG	4205	47	45	44	42	40	39	37	36	35	34	33
BOW	T-HANG	4305	64	63	62	61	60	59	58	57	55	54	53
BOW	T-HANG	4310	89	86	84	82	80	77	76	74	72	71	70
BOW	TW A1	105	82	80	78	76	75	74	73	72	71	70	69



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BOW	TW A2	110	86	83	81	79	77	76	75	73	72	72	71
BOW	TW A2	112	69	68	67	66	65	64	63	62	62	61	60
BOW	TW A2	114	84	82	80	78	76	75	74	73	72	71	70
BOW	TW A3	115	41	39	35	30	26	22	18	15	11	7	3
BOW	TW C1	305	86	83	81	79	77	76	75	73	72	72	71
BOW	TW C2	310	56	54	52	51	49	48	47	45	45	44	44
BOW	TW C3	315	58	56	54	53	51	49	48	47	46	45	44
BOW	TW C3	320	38	34	29	25	22	18	14	10	6	3	0
BOW	TW D	405	81	79	77	76	74	73	72	71	71	70	69
BOW	TW D	407	83	81	79	77	76	74	73	72	71	70	70
BOW	TW D	410	100	96	94	91	89	86	84	81	79	77	75
BOW	TW D	415	100	96	94	91	89	86	84	81	79	77	75
BOW	TW D	420	67	66	65	64	63	62	61	61	60	58	57
BOW	TW D	425	69	68	67	66	65	64	63	62	62	61	60
BOW	TW F	605	76	74	73	72	71	71	70	69	68	67	66
BOW	TW F	610	42	40	38	34	28	25	21	17	13	10	6
BOW	TW F	615	65	63	62	60	59	57	56	54	52	50	49
BOW	TW F	620	88	85	83	81	79	77	76	74	73	72	71
BOW	TW G	705	39	36	31	27	23	19	15	11	8	4	0
BOW	TW G	710	23	19	16	12	8	4	0	0	0	0	0
BOW	TW H	802	84	82	80	78	76	75	74	73	72	71	70
BOW	TW H	805	90	87	85	82	80	78	77	75	74	73	72

Major Rehabilitation Planning 2018-2027


Table E-3 Major Rehabilitation Planning 2018-2027

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BOW	AP FBO	4405	AC	83,163	64	AC Restoration	\$ 583,000.00
2018	BOW	AP H TW A	5105	AC	29,073	24	AC Reconstruction	\$ 262,000.00
2018	BOW	AP N	4105	AAC	24,590	53	AC Restoration	\$ 173,000.00
2018	BOW	AP N	4110	PCC	254,768	22	PCC Reconstruction	\$ 3,822,000.00
2018	BOW	AP N	4115	AAC	30,089	56	AC Restoration	\$ 211,000.00
2018	BOW	AP N	4120	AAC	4,597	60	AC Restoration	\$ 33,000.00
2018	BOW	AP N	4125	AAC	23,419	61	AC Restoration	\$ 164,000.00
2018	BOW	AP N	4127	AC	6,397	57	AC Restoration	\$ 45,000.00
2018	BOW	AP N	4130	PCC	146,118	62	PCC Restoration	\$ 1,462,000.00
2018	BOW	AP N	4132	PCC	17,250	14	PCC Reconstruction	\$ 259,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BOW	AP T-HANG	4210	PCC	30,250	67	PCC Restoration	\$ 303,000.00
2018	BOW	RW 5-23	6305	AAC	30,000	50	AC Restoration	\$ 211,000.00
2018	BOW	RW 5-23	6310	AAC	55,000	46	AC Restoration	\$ 424,000.00
2018	BOW	RW 5-23	6315	AAC	353,620	50	AC Restoration	\$ 2,476,000.00
2018	BOW	RW 9R-27L	6205	AC	350,236	20	AC Reconstruction	\$ 3,153,000.00
2018	BOW	RW 9R-27L	6210	AC	175,118	24	AC Reconstruction	\$ 1,577,000.00
2018	BOW	RW 9R-27L	6230	AAC	22,390	64	AC Restoration	\$ 157,000.00
2018	BOW	T-HANG	4205	AC	120,980	45	AC Restoration	\$ 952,000.00
2018	BOW	T-HANG	4305	AC	28,752	63	AC Restoration	\$ 202,000.00
2018	BOW	TW A3	115	AAC	44,009	39	AC Restoration	\$ 397,000.00
2018	BOW	TW C2	310	AAC	30,619	54	AC Restoration	\$ 215,000.00
2018	BOW	TW C3	315	AAC	41,491	56	AC Restoration	\$ 291,000.00
2018	BOW	TW C3	320	AAC	4,912	34	AC Reconstruction	\$ 45,000.00
2018	BOW	TW F	610	AAC	30,778	40	AC Restoration	\$ 274,000.00
2018	BOW	TW F	615	AAC	5,898	63	AC Restoration	\$ 42,000.00
2018	BOW	TW G	705	AAC	32,612	36	AC Reconstruction	\$ 294,000.00
2018	BOW	TW G	710	AAC	34,447	19	AC Reconstruction	\$ 311,000.00
2020	BOW	RW 9R-27L	6225	AAC	44,518	64	AC Restoration	\$ 312,000.00
2020	BOW	TW D	420	AC	81,983	64	AC Restoration	\$ 574,000.00
2022	BOW	RW 9L-27R	6118	AAC	9,250	64	AC Restoration	\$ 65,000.00
2022	BOW	TW A2	112	AC	43,953	64	AC Restoration	\$ 308,000.00
2022	BOW	TW D	425	AC	32,996	64	AC Restoration	\$ 231,000.00
2024	BOW	RW 5-23	6320	AAC	40,640	64	AC Restoration	\$ 285,000.00
2024	BOW	RW 9L-27R	6124	AAC	30,000	64	AC Restoration	\$ 211,000.00
2025	BOW	RW 9L-27R	6115	AAC	440,000	64	AC Restoration	\$ 3,081,000.00
2026	BOW	RW 9L-27R	6105	AAC	30,000	64	AC Restoration	\$ 211,000.00
2026	BOW	RW 9L-27R	6125	APC	30,000	63	AC Restoration	\$ 211,000.00
2027	BOW	RW 9L-27R	6130	AAC	20,000	64	AC Restoration	\$ 141,000.00

**All planning cost values have been rounded to the nearest thousand-dollar.*


*Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027*

Summary of Bartow Municipal Airport

Bartow Municipal Airport was inspected in March 2017 – the overall weighted PCI value was 59, a condition rating of Fair. The results of the maintenance, repair, and major rehabilitation analysis identified \$3,924,740 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$23,968,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$18,338,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.

Chapter 1





Chapter 1 – Introduction

1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating public-use airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.



1.3 Organization

1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."** Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys,"** evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."**

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- ▶ **Research and evaluation of existing record documentation** was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- ▶ **An update to the existing Network Definition Map** was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- ▶ **A functional pavement evaluation with PCI Survey inspections** was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- ▶ **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- ▶ **Maintenance, Repair, and Rehabilitation Planning** was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.



1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA **AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."** The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.



1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and **150/5380-7B “Airport Pavement Management Program (PMP)”**). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.”

1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC **150/5380-7B “Airport Pavement Management Program (PMP)”** an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data




F. Pavement Performance Modeling for the Prediction/Forecast of PCI

G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements’ past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and cost-effective manner. **Figure 1.7-1 Typical Pavement Condition Life Cycle**, which is based on the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”** **Figure 1.7-1 Typical Pavement Condition Life Cycle**, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.

Figure 1.7-1 Typical Pavement Condition Life Cycle




**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).*

Figure 1.7-2 General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

Figure 1.7-2 General Pavement Treatments by Condition Range



Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7-1 and 1.7-2**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7-3 and Figure 1.7-4 depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.



Figure 1.7-3 Flexible Asphalt Concrete









	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figure 1.7-4 Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.




1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”
- FAA Advisory Circular 150/5380-7B 150/5380-7B “Airport Pavement Management Program.”
- FAA Advisory Circular 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”
- FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation.”
- Department of the Air Force, Air Force Civil Engineer Center “Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements.”
- Unified Facilities Criteria (UFC) 3-260-16FA 16 “Airfield Pavement Condition Survey Procedures Pavements.”
- Unified Facilities Criteria (UFC) 3-260-03 “Airfield Pavement Evaluation.”
- Pavement Management for Airports, Roads, and Parking Lots 2nd Edition, M.Y. Shahin.

Chapter 2





Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”**

2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.



A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a “parent” pavement network.

Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (± 8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ($\pm 2,000$ ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	“Tallahassee International Airport – Airfield Pavements”
Branch Name	Commonly defined asset name as established by Airport and by use	“Runway 18-36”
Branch ID	Codified shorthand name for commonly defined asset established for database identification	“RW 18-36” RW, Branch Use, “Runway” 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following: <ul style="list-style-type: none"> • Pavement Composition • Construction Work History • Aircraft Traffic • Condition Records 	“6105”
Sample Unit	A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	“300”



2.3 Airfield Pavement Structure

2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.



Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 6-inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.



2.4 Airfield Pavement Work History

2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

1. Location and Limits of Work.
2. Types and Severity of Distresses Repaired.
3. Type of Work.
4. Cost of Work.
5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.6 Airfield Pavement Condition Index (PCI) Survey

2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP),"** the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.



2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age



Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> Alligator Cracking Corrugation Depression Patching of Load-based distress Polished Aggregate Rutting Slippage Cracking 	<ul style="list-style-type: none"> Bleeding Block Cracking Joint Reflection Cracking L/T Cracking Patching of climate / durability-caused distresses Shoving from PCC Raveling Weathering Swelling 	<ul style="list-style-type: none"> Alligator Cracking Depression Patching of moisture / drainage caused distress Swelling Raveling Weathering 	<ul style="list-style-type: none"> Oil Spillage Jet Blast Erosion Polished Aggregate

Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> Corrugation Depression Rutting Shoving of asphalt pavement Swelling Raveling Weathering 	<ul style="list-style-type: none"> Bleeding Depression Polished Aggregate Rutting 	<ul style="list-style-type: none"> Block Cracking Joint Reflection Cracking L/T Cracking Slippage Cracking 	<ul style="list-style-type: none"> All Distresses



Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Blowup	Climate / ASR
Corner Break	Load Repetition / Curling Stresses
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
Durability Cracking	Freeze-Thaw Cycling
Joint Seal Damage	Material Deterioration / Construction Quality / Age
Small Patch	Pavement Repair
Large Patch/Utility Cut	Utility / Pavement Repair
Popout	Freeze-Thaw Cycling / ASR / Material Quality
Pumping	Load Repetition / Poor Joint Sealant
Scaling	Construction Quality / Freeze-Thaw Cycling
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer
Shattered Slab	Overloading
Shrinkage Cracking	Construction Quality / Climate
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction



Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> • Corner Break • Shattered Slab • L/T/D Cracking • Pumping • Patching of Load-associated distress • Spalling 	<ul style="list-style-type: none"> • Blowup • "D" Cracking • Joint Seal Damage • Popouts • Scaling • Patch of Climate/Durability-associated distress • Shrinkage Cracking • Spalling • L/T/D Cracking 	<ul style="list-style-type: none"> • Corner Break • Shattered Slab • Pumping • Patching of Moisture/Drainage-associated distress 	<ul style="list-style-type: none"> • Settlement / Faulting

Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> • Blowup • Corner Break • L/T/D Cracking • Shattered Slab • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Corner Break • L/T/D Cracking • "D" Cracking • Joint Seal Damage • Shattered Slab • Popouts • Scaling 	<ul style="list-style-type: none"> • All distresses



2.6.3 PCI Survey Inspection Procedures

Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤20	10% but ≤10

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤20	10% but ≤10



2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in an adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured “(52) Weathering and Raveling” distress has been separated into two distresses “(52) Raveling” and “(57) Weathering.” Previously, areas that were recorded as “Weathering and Raveling” were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where “Weathering” only exists and does not meet the definition of “Raveling,” the PCI deduction is not as high as the former “Weathering and Raveling.” Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling,” may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

Rigid Portland Cement Concrete Pavement Distress Updates


The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR.” As a result the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling,” and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, “(73) Shrinkage Cracks” has been redefined as “(73) Shrinkage Cracking”. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Distress Updates to Reflect ASTM 5340-12				
Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Cracking - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Cracking - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Cracking - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Cracking' may now be identified as 'Shrinkage Cracking'

Chapter 3





Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1-1** and **Figure 3.1.1-2** provides an inset view of the 2017 Airfield Pavement Network Definition Exhibit and the 2017 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.


Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Year	General Work Description
2014	AP N - Reconstruction: PCC
2016	TW D - New Construction: 4" P-401, 6" P-211, 12" P-160

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.




Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit



The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.



Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit




The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections since any major construction activity has occurred during the PCI Survey inspection. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.



Figure 3.1.2 Average Age of Pavements at Inspection




The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.



3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.

Figure 3.1.4 (a) Pavement Surface Type by Area (SF)



*Figure 3.1.4 (b) Pavement Surface Type by Area (%)*

3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BOW	APRON FBO	AP FBO	APRON	4405	183	410	83,163	AC	1/1/2007
BOW	HOLD APRON ON TW A	AP H TW A	APRON	5105	500	50	29,073	AC	1/1/1942
BOW	NORTH APRON	AP N	APRON	4105	450	130	24,590	AAC	1/1/1990
BOW	NORTH APRON	AP N	APRON	4107	300	130	39,764	AAC	2/1/2012
BOW	NORTH APRON	AP N	APRON	4110	1050	300	254,768	PCC	1/1/1942
BOW	NORTH APRON	AP N	APRON	4112	180	187.5	34,136	PCC	1/1/2014
BOW	NORTH APRON	AP N	APRON	4115	550	50	30,089	AAC	1/1/1990
BOW	NORTH APRON	AP N	APRON	4120	125	40	4,597	AAC	1/1/1987
BOW	NORTH APRON	AP N	APRON	4125	350	100	23,419	AAC	1/1/1990
BOW	NORTH APRON	AP N	APRON	4127	120	50	6,397	AC	1/1/1998
BOW	NORTH APRON	AP N	APRON	4130	480	300	146,118	PCC	1/1/1942
BOW	NORTH APRON	AP N	APRON	4132	280	40	17,250	PCC	1/1/1942
BOW	T-HANGAR APRON	AP T-HANG	APRON	4210	125	25	30,250	PCC	1/1/2004
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6305	300	100	30,000	AAC	1/1/2001
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6310	550	100	55,000	AAC	1/1/2001
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6315	3550	100	353,620	AAC	1/1/2001
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6320	400	100	40,640	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6105	300	100	30,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6110	600	25	20,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6115	4400	100	440,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6118	360	25	9,250	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6120	7300	25	170,750	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6124	1100	25	30,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6125	300	100	30,000	APC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6130	600	25	20,000	AAC	1/1/2006



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6205	3484	100	350,236	AC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6210	6966	25	175,118	AC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6215	300	100	30,000	PCC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6220	600	25	15,000	PCC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6225	454	100	44,518	AAC	1/1/2001
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6230	910	25	22,390	AAC	1/1/2001
BOW	T-HANGAR TAXILANE	T-HANG	TAXILANE	4205	2725	28	120,980	AC	1/1/2004
BOW	T-HANGAR TAXILANE	T-HANG	TAXILANE	4305	985	20	28,752	AC	1/1/2004
BOW	T-HANGAR TAXILANE	T-HANG	TAXILANE	4310	515	20	10,686	AC	9/1/2012
BOW	TAXIWAY A1	TW A1	TAXIWAY	105	1820	50	93,327	AAC	2/1/2012
BOW	TAXIWAY A2	TW A2	TAXIWAY	110	649	50	33,575	AAC	2/1/2012
BOW	TAXIWAY A2	TW A2	TAXIWAY	112	2400	55	43,953	AC	1/1/2003
BOW	TAXIWAY A2	TW A2	TAXIWAY	114	2400	55	6,638	AAC	1/1/2006
BOW	TAXIWAY A3	TW A3	TAXIWAY	115	1100	38	44,009	AAC	1/1/1987
BOW	TAXIWAY C1	TW C1	TAXIWAY	305	330	50	18,037	AAC	7/1/2009
BOW	TAXIWAY C2	TW C2	TAXIWAY	310	850	35	30,619	AAC	1/1/1987
BOW	TAXIWAY C3	TW C3	TAXIWAY	315	1175	35	41,491	AAC	1/1/1987
BOW	TAXIWAY C3	TW C3	TAXIWAY	320	125	35	4,912	AAC	1/1/1990
BOW	TAXIWAY D	TW D	TAXIWAY	405	2000	50	95,846	AAC	7/1/2009
BOW	TAXIWAY D	TW D	TAXIWAY	407	200	50	15,000	AAC	7/1/2009
BOW	TAXIWAY D	TW D	TAXIWAY	410	775	50	72,003	AC	6/1/2016
BOW	TAXIWAY D	TW D	TAXIWAY	415	1270	50	76,821	AC	6/1/2016
BOW	TAXIWAY D	TW D	TAXIWAY	420	2400	55	81,983	AC	1/1/2003
BOW	TAXIWAY D	TW D	TAXIWAY	425	1200	25	32,996	AC	1/1/2003
BOW	TAXIWAY F	TW F	TAXIWAY	605	85	90	10,259	AAC	1/1/2006
BOW	TAXIWAY F	TW F	TAXIWAY	610	340	90	30,778	AAC	1/1/1971




Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BOW	TAXIWAY F	TW F	TAXIWAY	615	290	120	5,898	AAC	1/1/2006
BOW	TAXIWAY F	TW F	TAXIWAY	620	290	120	37,090	AAC	2/1/2012
BOW	TAXIWAY G	TW G	TAXIWAY	705	210	150	32,612	AAC	1/1/1971
BOW	TAXIWAY G	TW G	TAXIWAY	710	210	150	34,447	AAC	1/1/1971
BOW	TAXIWAY H	TW H	TAXIWAY	802	25	50	3,573	AAC	2/1/2012
BOW	TAXIWAY H	TW H	TAXIWAY	805	475	50	24,823	AAC	2/1/2012



PAGE INTENTIONALLY LEFT BLANK

Chapter 4





Chapter 4 – Airfield Pavement Condition


The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

4.1 Airfield Pavement Condition Index (Latest Inspection)

4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.

Figure 4.1.1 Latest Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (d)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.



Figure 4.1.2 (a) Latest Condition – Runway Pavements




Figure 4.1.2 (b) Latest Condition – Taxiway Pavements






Figure 4.1.2 (c) Latest Condition – Apron Pavements





Figure 4.1.2 (d) Latest Condition – Taxiway Pavements





4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement.

Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.



Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
BOW	AP FBO	APRON FBO	APRON	4405	83,163	AC	66	Fair	96%	0%	4%	3	18
BOW	AP H TW A	HOLD APRON ON TW A	APRON	5105	29,073	AC	26	Very Poor	100%	0%	0%	1	5
BOW	AP N	NORTH APRON	APRON	4105	24,590	AAC	54	Poor	94%	0%	6%	1	5
BOW	AP N	NORTH APRON	APRON	4107	39,764	AAC	86	Good	100%	0%	0%	1	9
BOW	AP N	NORTH APRON	APRON	4110	254,768	PCC	23	Serious	1%	68%	31%	6	48
BOW	AP N	NORTH APRON	APRON	4112	34,136	PCC	96	Good	0%	75%	25%	2	12
BOW	AP N	NORTH APRON	APRON	4115	30,089	AAC	58	Fair	100%	0%	0%	1	8
BOW	AP N	NORTH APRON	APRON	4120	4,597	AAC	63	Fair	81%	0%	19%	1	1
BOW	AP N	NORTH APRON	APRON	4125	23,419	AAC	64	Fair	83%	0%	17%	1	5
BOW	AP N	NORTH APRON	APRON	4127	6,397	AC	59	Fair	100%	0%	0%	1	2
BOW	AP N	NORTH APRON	APRON	4130	146,118	PCC	64	Fair	24%	11%	65%	4	35
BOW	AP N	NORTH APRON	APRON	4132	17,250	PCC	15	Serious	1%	77%	22%	1	4
BOW	AP T-HANG	T-HANGAR APRON	APRON	4210	30,250	PCC	69	Fair	30%	44%	26%	2	10
BOW	RW 5-23	RUNWAY 5-23	RUNWAY	6305	30,000	AAC	53	Poor	71%	0%	29%	2	6
BOW	RW 5-23	RUNWAY 5-23	RUNWAY	6310	55,000	AAC	49	Poor	75%	0%	25%	3	11
BOW	RW 5-23	RUNWAY 5-23	RUNWAY	6315	353,620	AAC	53	Poor	90%	0%	10%	15	71
BOW	RW 5-23	RUNWAY 5-23	RUNWAY	6320	40,640	AAC	78	Satisfactory	84%	0%	16%	2	8
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6105	30,000	AAC	83	Satisfactory	100%	0%	0%	2	6
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6110	20,000	AAC	87	Good	91%	0%	9%	2	4
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6115	440,000	AAC	80	Satisfactory	94%	0%	6%	18	87
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6118	9,250	AAC	73	Satisfactory	59%	0%	41%	1	2
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6120	170,750	AAC	88	Good	93%	0%	7%	7	35
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6124	30,000	AAC	78	Satisfactory	70%	0%	30%	2	6
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6125	30,000	APC	82	Satisfactory	100%	0%	0%	2	6
BOW	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6130	20,000	AAC	86	Good	100%	0%	0%	2	4
BOW	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6205	350,236	AC	22	Serious	96%	4%	0%	15	71
BOW	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6210	175,118	AC	26	Very Poor	100%	0%	0%	7	36
BOW	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6215	30,000	PCC	76	Satisfactory	42%	0%	58%	3	8
BOW	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6220	15,000	PCC	77	Satisfactory	46%	0%	54%	2	4
BOW	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6225	44,518	AAC	69	Fair	100%	0%	0%	2	10
BOW	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6230	22,390	AAC	66	Fair	100%	0%	0%	1	4
BOW	T-HANG	T-HANGAR TAXILANE	TAXILANE	4205	120,980	AC	47	Poor	91%	9%	0%	3	27
BOW	T-HANG	T-HANGAR TAXILANE	TAXILANE	4305	28,752	AC	64	Fair	96%	0%	4%	1	7
BOW	T-HANG	T-HANGAR TAXILANE	TAXILANE	4310	10,686	AC	89	Good	87%	0%	13%	1	2
BOW	TW A1	TAXIWAY A1	TAXIWAY	105	93,327	AAC	82	Satisfactory	100%	0%	0%	3	19
BOW	TW A2	TAXIWAY A2	TAXIWAY	110	33,575	AAC	86	Good	100%	0%	0%	1	6
BOW	TW A2	TAXIWAY A2	TAXIWAY	112	43,953	AC	69	Fair	100%	0%	0%	1	10




Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
BOW	TW A2	TAXIWAY A2	TAXIWAY	114	6,638	AAC	84	Satisfactory	68%	0%	32%	1	2
BOW	TW A3	TAXIWAY A3	TAXIWAY	115	44,009	AAC	41	Poor	92%	0%	8%	2	11
BOW	TW C1	TAXIWAY C1	TAXIWAY	305	18,037	AAC	86	Good	100%	0%	0%	1	4
BOW	TW C2	TAXIWAY C2	TAXIWAY	310	30,619	AAC	56	Fair	100%	0%	0%	1	8
BOW	TW C3	TAXIWAY C3	TAXIWAY	315	41,491	AAC	58	Fair	98%	0%	2%	2	12
BOW	TW C3	TAXIWAY C3	TAXIWAY	320	4,912	AAC	38	Very Poor	71%	0%	29%	1	1
BOW	TW D	TAXIWAY D	TAXIWAY	405	95,846	AAC	81	Satisfactory	93%	0%	7%	3	19
BOW	TW D	TAXIWAY D	TAXIWAY	407	15,000	AAC	83	Satisfactory	100%	0%	0%	1	3
BOW	TW D	TAXIWAY D	TAXIWAY	410	72,003	AC	100	Good	0%	0%	0%	0	16
BOW	TW D	TAXIWAY D	TAXIWAY	415	76,821	AC	100	Good	0%	0%	0%	0	15
BOW	TW D	TAXIWAY D	TAXIWAY	420	81,983	AC	67	Fair	100%	0%	0%	2	15
BOW	TW D	TAXIWAY D	TAXIWAY	425	32,996	AC	69	Fair	100%	0%	0%	1	9
BOW	TW F	TAXIWAY F	TAXIWAY	605	10,259	AAC	76	Satisfactory	74%	0%	26%	1	2
BOW	TW F	TAXIWAY F	TAXIWAY	610	30,778	AAC	42	Poor	96%	0%	4%	1	7
BOW	TW F	TAXIWAY F	TAXIWAY	615	5,898	AAC	65	Fair	83%	0%	17%	1	1
BOW	TW F	TAXIWAY F	TAXIWAY	620	37,090	AAC	88	Good	100%	0%	0%	1	8
BOW	TW G	TAXIWAY G	TAXIWAY	705	32,612	AAC	39	Very Poor	100%	0%	0%	1	8
BOW	TW G	TAXIWAY G	TAXIWAY	710	34,447	AAC	23	Serious	89%	0%	11%	1	9
BOW	TW H	TAXIWAY H	TAXIWAY	802	3,573	AAC	84	Satisfactory	100%	0%	0%	1	1
BOW	TW H	TAXIWAY H	TAXIWAY	805	24,823	AAC	90	Good	100%	0%	0%	1	5



Figure 4.1.3 is an inset view of the 2017 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits**.

Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit





4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The field PCI Survey performed at Bartow Municipal Airport (BOW) started on 03/05/2017 and was completed on 03/06/2017. The resulting overall average area-weighted PCI value was 59 representing a condition rating of Fair. Three runways service Bartow Municipal Airport: Runway 05-23 is 100-ft wide and 5,000-ft long, Runway 09L-27R is 150-ft wide and 5,000-ft long, Runway 09R-27L is 150-ft wide and 4,400-ft long.

Based on the FAA 5010 Report as of 07/12/2017 the Airport has reported 27,759 operations for 12 months ending 08/16/2016.

4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

Runway 05-23

Runway 5-23 consists of 4 sections constructed of AAC. The last construction years vary from 2001 to 2006. The average area-weighted PCI for Runway 5-23 is 54 representing a Poor condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Runway 5-23 include Bleeding, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, and Weathering.

Runway 09L-27R

Runway 9L-27R consists of 8 sections constructed of AAC and APC. The last construction year for Runway 9L-27R was 2006. The average area-weighted PCI for Runway 9L-27R is 82 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Runway 9L-27R include Depression, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Runway 09R-27L

Runway 9R-27L consists of 6 sections constructed of AC, AAC, and PCC. The last construction years vary from 1942 to 2001. The average area-weighted PCI for Runway 9R-27L is 31 representing a Very Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Runway 9R-27L include Alligator Cracking, Block Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, Weathering, Joint Seal Damage, Small Patch, Shrinkage Cracking, Joint Spall, and Corner Spall.

Taxiway G

Taxiway G consists of 2 sections constructed of AAC. The last construction year for Taxiway G was 1971. The average area-weighted PCI for Taxiway G is 30 representing a Very Poor condition rating. The pavement distresses observed were related to Climate and Other distress



classifications. Distresses observed in Taxiway G include Block Cracking, Depression, Longitudinal & Transverse Cracking, and Raveling.

T-Hangar Taxilane

T-Hangar Taxilane consists of 3 sections constructed of AC. The last construction years vary from 2004 to 2012. The average area-weighted PCI for T-Hangar Taxilane is 52 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in T-Hangar Taxilane include Block Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Swelling, and Weathering.

North Apron

North Apron consists of 10 sections constructed of AC, AAC, and PCC. The last construction years vary from 1942 to 2014. The average area-weighted PCI for North Apron is 47 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in North Apron include Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Shoving, Swelling, Weathering, Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Faulting, Shattered Slab, Shrinkage Cracking, Joint Spall, and Corner Spall.

T-Hangar Apron

T-Hangar Apron consists of 1 section constructed of PCC. The last construction date for T-Hangar Apron was 2004. The average area-weighted PCI for T-Hangar Apron is 69 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress types. Distresses observed in T-Hangar Apron include Corner Break, Linear Cracking, Joint Seal Damage, Faulting, Shattered Slab, Shrinkage Cracking, and Joint Spall.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Average Area-Weighted PCI	Condition Rating
Runway	57	Fair
Taxiway	73	Satisfactory
Apron	49	Poor
Taxilane	52	Poor



4.3 Forecasted Pavement Conditions

4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to develop forecasted PCI values based on historic trends and statistical models.

4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2018 through January 2027.

Figure 4.3.2 (a) Forecasted Runway Pavement Performance






Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance





4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.



Table 4.3.3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BOW	AP FBO	4405	66	64	63	61	59	58	56	55	53	51	50
BOW	AP H TW A	5105	26	24	23	21	19	18	16	15	13	11	10
BOW	AP N	4105	54	53	52	52	52	52	52	52	51	50	48
BOW	AP N	4107	86	83	82	80	79	77	76	74	71	69	66
BOW	AP N	4110	23	22	20	19	18	17	16	15	14	13	12
BOW	AP N	4112	96	93	90	87	84	82	79	77	74	72	70
BOW	AP N	4115	58	56	54	53	53	52	52	52	52	52	52
BOW	AP N	4120	63	60	58	56	55	54	53	52	52	52	52
BOW	AP N	4125	64	61	59	57	55	54	53	52	52	52	52
BOW	AP N	4127	59	57	56	54	52	51	49	48	46	44	43
BOW	AP N	4130	64	62	61	59	58	56	55	54	53	52	51
BOW	AP N	4132	15	14	12	11	10	9	8	7	6	5	4
BOW	AP T-HANG	4210	69	67	65	63	62	60	59	57	56	55	54
BOW	RW 5-23	6305	53	50	48	45	41	38	35	32	30	27	24
BOW	RW 5-23	6310	49	46	43	39	36	33	31	28	26	23	20
BOW	RW 5-23	6315	53	50	48	45	41	38	35	32	30	27	24
BOW	RW 5-23	6320	78	75	73	71	69	67	65	64	63	62	61
BOW	RW 9L-27R	6105	83	80	78	76	73	71	69	67	65	64	63
BOW	RW 9L-27R	6110	87	85	82	80	77	75	72	70	68	66	65
BOW	RW 9L-27R	6115	80	77	75	73	70	68	67	65	64	62	62
BOW	RW 9L-27R	6118	73	71	69	67	65	64	63	62	61	61	60
BOW	RW 9L-27R	6120	88	86	83	81	78	76	73	71	69	67	65
BOW	RW 9L-27R	6124	78	75	73	71	69	67	65	64	63	62	61
BOW	RW 9L-27R	6125	82	79	77	75	72	70	68	66	65	63	62
BOW	RW 9L-27R	6130	86	84	81	79	76	74	71	69	67	66	64



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BOW	RW 9R-27L	6205	22	20	19	17	15	14	12	10	9	7	6
BOW	RW 9R-27L	6210	26	24	23	21	19	18	16	14	13	11	10
BOW	RW 9R-27L	6215	76	75	74	73	72	71	71	70	69	68	67
BOW	RW 9R-27L	6220	77	76	75	74	73	72	72	71	70	69	68
BOW	RW 9R-27L	6225	69	67	65	64	63	62	61	61	60	60	60
BOW	RW 9R-27L	6230	66	64	63	62	61	61	60	60	60	60	60
BOW	T-HANG	4205	47	45	44	42	40	39	37	36	35	34	33
BOW	T-HANG	4305	64	63	62	61	60	59	58	57	55	54	53
BOW	T-HANG	4310	89	86	84	82	80	77	76	74	72	71	70
BOW	TW A1	105	82	80	78	76	75	74	73	72	71	70	69
BOW	TW A2	110	86	83	81	79	77	76	75	73	72	72	71
BOW	TW A2	112	69	68	67	66	65	64	63	62	62	61	60
BOW	TW A2	114	84	82	80	78	76	75	74	73	72	71	70
BOW	TW A3	115	41	39	35	30	26	22	18	15	11	7	3
BOW	TW C1	305	86	83	81	79	77	76	75	73	72	72	71
BOW	TW C2	310	56	54	52	51	49	48	47	45	45	44	44
BOW	TW C3	315	58	56	54	53	51	49	48	47	46	45	44
BOW	TW C3	320	38	34	29	25	22	18	14	10	6	3	0
BOW	TW D	405	81	79	77	76	74	73	72	71	71	70	69
BOW	TW D	407	83	81	79	77	76	74	73	72	71	70	70
BOW	TW D	410	100	96	94	91	89	86	84	81	79	77	75
BOW	TW D	415	100	96	94	91	89	86	84	81	79	77	75
BOW	TW D	420	67	66	65	64	63	62	61	61	60	58	57
BOW	TW D	425	69	68	67	66	65	64	63	62	62	61	60
BOW	TW F	605	76	74	73	72	71	71	70	69	68	67	66
BOW	TW F	610	42	40	38	34	28	25	21	17	13	10	6
BOW	TW F	615	65	63	62	60	59	57	56	54	52	50	49




Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BOW	TW F	620	88	85	83	81	79	77	76	74	73	72	71
BOW	TW G	705	39	36	31	27	23	19	15	11	8	4	0
BOW	TW G	710	23	19	16	12	8	4	0	0	0	0	0
BOW	TW H	802	84	82	80	78	76	75	74	73	72	71	70
BOW	TW H	805	90	87	85	82	80	78	77	75	74	73	72



4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA **AC 150/5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements** to determine structural and/or functional conditions at the time of project.

Chapter 5





Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- **Localized Maintenance and Repair** includes patching and crack sealing.
- **Global Treatments** includes surface seals and rejuvenators (flexible pavements).
- **Major Rehabilitation** includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distress pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety (“stopgap”) measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.



5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2.1** and **Table 5.2.2**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and the **FDOT Airfield Pavement Distress Repair Manual**. Additionally, the **Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements** was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	High	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft



Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L & T CR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt



Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$6.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$3.00	SqFt

Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$100.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in **5.2 Localized M&R Policy**. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. **Appendix B** provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to near-term Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3-1** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - CRACK SEALING - AC	PREVENTIVE	45	Ft	\$ 140.00
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	695	SqFt	\$ 4,170.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	340	SqFt	\$ 1,020.00
FDOT - PATCHING - PCC FULL DEPTH	PREVENTIVE	135	SqFt	\$ 13,060.00
FDOT - SURFACE SEAL	PREVENTIVE	369,395	SqFt	\$ 203,170.00
FDOT - PATCHING - PCC PARTIAL DEPTH	PREVENTIVE	70	SqFt	\$ 4,960.00
FDOT - CRACK SEALING - PCC	PREVENTIVE	325	Ft	\$ 1,370.00
FDOT - JOINT SEAL - PCC	PREVENTIVE	6,525	Ft	\$ 17,950.00
FDOT - CRACK SEALING - AC	STOPGAP	71,270	Ft	\$ 213,810.00
FDOT - GRINDING (LOCALIZED)	STOPGAP	135	Ft	\$ 270.00
FDOT - CRACK SEALING - PCC	STOPGAP	12,515	Ft	\$ 53,190.00
FDOT - PATCHING - PCC PARTIAL DEPTH	STOPGAP	870	SqFt	\$ 62,490.00
FDOT - PATCHING - PCC FULL DEPTH	STOPGAP	3,235	SqFt	\$ 323,070.00
FDOT - JOINT SEAL - PCC	STOPGAP	57,815	Ft	\$ 158,990.00
FDOT - SLAB REPLACEMENT - PCC	STOPGAP	16,925	SqFt	\$ 507,690.00



Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	16,695	SqFt	\$ 100,170.00
FDOT - SURFACE SEAL	STOPGAP	735,285	SqFt	\$ 404,410.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	618,250	SqFt	\$ 1,854,750.00
FDOT - MILLING - AC	STOPGAP	30	SqFt	\$ 60.00



The following **Table 5.3-2** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved “End Condition” of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
BOW	AP FBO	4405	83,163	66	79	\$ 45,750.00
BOW	AP H TW A	5105	29,073	26	46	\$ 102,830.00
BOW	AP N	4105	24,590	54	54	\$ -
BOW	AP N	4107	39,764	86	86	\$ -
BOW	AP N	4110	254,768	23	45	\$ 660,120.00
BOW	AP N	4112	34,136	96	96	\$ 50.00
BOW	AP N	4115	30,089	58	61	\$ 990.00
BOW	AP N	4120	4,597	63	68	\$ 60.00
BOW	AP N	4125	23,419	64	64	\$ 2,640.00
BOW	AP N	4127	6,397	59	59	\$ -
BOW	AP N	4130	146,118	64	81	\$ 399,790.00
BOW	AP N	4132	17,250	15	38	\$ 45,920.00
BOW	AP T-HANG	4210	30,250	69	78	\$ 17,060.00
BOW	RW 5-23	6305	30,000	53	76	\$ 24,720.00
BOW	RW 5-23	6310	55,000	49	72	\$ 51,880.00
BOW	RW 5-23	6315	353,620	53	75	\$ 263,510.00
BOW	RW 5-23	6320	40,640	78	78	\$ -
BOW	RW 9L-27R	6105	30,000	83	89	\$ 830.00
BOW	RW 9L-27R	6110	20,000	87	89	\$ 60.00
BOW	RW 9L-27R	6115	440,000	80	89	\$ 29,850.00
BOW	RW 9L-27R	6118	9,250	73	83	\$ 1,630.00
BOW	RW 9L-27R	6120	170,750	88	88	\$ 70.00
BOW	RW 9L-27R	6124	30,000	78	82	\$ 1,600.00
BOW	RW 9L-27R	6125	30,000	82	88	\$ 1,240.00
BOW	RW 9L-27R	6130	20,000	86	92	\$ 550.00
BOW	RW 9R-27L	6205	350,236	22	49	\$ 1,159,200.00
BOW	RW 9R-27L	6210	175,118	26	49	\$ 551,670.00
BOW	RW 9R-27L	6215	30,000	76	86	\$ 14,000.00
BOW	RW 9R-27L	6220	15,000	77	89	\$ 6,270.00
BOW	RW 9R-27L	6225	44,518	69	95	\$ 22,590.00
BOW	RW 9R-27L	6230	22,390	66	95	\$ 12,530.00
BOW	T-HANG	4205	120,980	47	66	\$ 131,860.00
BOW	T-HANG	4305	28,752	64	92	\$ 15,940.00



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
BOW	T-HANG	4310	10,686	89	89	\$ -
BOW	TW A1	105	93,327	82	82	\$ -
BOW	TW A2	110	33,575	86	86	\$ -
BOW	TW A2	112	43,953	69	94	\$ 24,180.00
BOW	TW A2	114	6,638	84	86	\$ 510.00
BOW	TW A3	115	44,009	41	60	\$ 37,810.00
BOW	TW C1	305	18,037	86	90	\$ 200.00
BOW	TW C2	310	30,619	56	74	\$ 29,570.00
BOW	TW C3	315	41,491	58	75	\$ 25,630.00
BOW	TW C3	320	4,912	38	56	\$ 4,380.00
BOW	TW D	405	95,846	81	86	\$ 2,110.00
BOW	TW D	407	15,000	83	89	\$ 420.00
BOW	TW D	410	72,003	100	100	\$ -
BOW	TW D	415	76,821	100	100	\$ -
BOW	TW D	420	81,983	67	92	\$ 45,180.00
BOW	TW D	425	32,996	69	96	\$ 18,150.00
BOW	TW F	605	10,259	76	81	\$ 1,060.00
BOW	TW F	610	30,778	42	65	\$ 29,480.00
BOW	TW F	615	5,898	65	83	\$ 2,270.00
BOW	TW F	620	37,090	88	88	\$ -
BOW	TW G	705	32,612	39	64	\$ 29,140.00
BOW	TW G	710	34,447	23	48	\$ 109,920.00
BOW	TW H	802	3,573	84	90	\$ 100.00
BOW	TW H	805	24,823	90	90	\$ -




The following **Table 5.3-3** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-3 Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 245,840.00
Stopgap	\$ 3,678,900.00
<i>Planning-Level Localized M&R Needs =</i>	<i>\$ 3,924,740.00</i>

Chapter 6





Chapter 6 – Major Rehabilitation Planning

6.1 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1-1 and 6.1-2** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, $PCI \leq \text{Critical PCI}$







Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, $PCI > \text{Critical } PCI$





6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The **Critical PCI** concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

1. Develop a pavement performance model and refine a prediction model for the pavements considered.
2. Select a localized maintenance and repair policy to be used in developing a work plan.
3. Apply the selected localized policy to the pavement sections for a range of PCI.
4. Compute the unit cost per area for each PCI range.
5. Plot the cost versus the PCI.
6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended **Minimum Service-Level PCI** for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	60	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)



6.2 Major Rehabilitation Policy

6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA **AC 150/ 5320-6F "Airport Pavement Design and Evaluation."** It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following **Tables 6.2.1 (a) and (b)** provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average GA Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete

Rehabilitation Type	General Aviation (GA) Airport
AC Restoration <i>Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.</i> PCI = 41 to 65	75% Mill and Overlay P-101 AC Milling (2") P-603 Bituminous Tack P-401 (HMA) (2") 25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2") <i>Excludes any paved shoulder features.</i>
AC Reconstruction <i>Full-depth asphalt pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2") <i>Excludes any paved shoulder features.</i>



Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete

Rehabilitation Type	General Aviation (GA) Airport
PCC Restoration <i>Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.</i> PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (10") *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction <i>Full-depth rigid pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (6") P-501 Rigid PCC (10")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs



provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Flexible Asphalt Concrete Cost Per SF	Rigid Portland Cement Concrete Cost per SF
Restoration	41 to 65	\$ 7.00	\$ 10.00
Reconstruction	0 to 40	\$ 9.00	\$ 15.00

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.



Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BOW	AP FBO	4405	AC	83,163	64	AC Restoration	\$ 583,000.00
2018	BOW	AP H TW A	5105	AC	29,073	24	AC Reconstruction	\$ 262,000.00
2018	BOW	AP N	4105	AAC	24,590	53	AC Restoration	\$ 173,000.00
2018	BOW	AP N	4110	PCC	254,768	22	PCC Reconstruction	\$ 3,822,000.00
2018	BOW	AP N	4115	AAC	30,089	56	AC Restoration	\$ 211,000.00
2018	BOW	AP N	4120	AAC	4,597	60	AC Restoration	\$ 33,000.00
2018	BOW	AP N	4125	AAC	23,419	61	AC Restoration	\$ 164,000.00
2018	BOW	AP N	4127	AC	6,397	57	AC Restoration	\$ 45,000.00
2018	BOW	AP N	4130	PCC	146,118	62	PCC Restoration	\$ 1,462,000.00
2018	BOW	AP N	4132	PCC	17,250	14	PCC Reconstruction	\$ 259,000.00
2018	BOW	AP T-HANG	4210	PCC	30,250	67	PCC Restoration	\$ 303,000.00
2018	BOW	RW 5-23	6305	AAC	30,000	50	AC Restoration	\$ 211,000.00
2018	BOW	RW 5-23	6310	AAC	55,000	46	AC Restoration	\$ 424,000.00
2018	BOW	RW 5-23	6315	AAC	353,620	50	AC Restoration	\$ 2,476,000.00
2018	BOW	RW 9R-27L	6205	AC	350,236	20	AC Reconstruction	\$ 3,153,000.00
2018	BOW	RW 9R-27L	6210	AC	175,118	24	AC Reconstruction	\$ 1,577,000.00
2018	BOW	RW 9R-27L	6230	AAC	22,390	64	AC Restoration	\$ 157,000.00
2018	BOW	T-HANG	4205	AC	120,980	45	AC Restoration	\$ 952,000.00
2018	BOW	T-HANG	4305	AC	28,752	63	AC Restoration	\$ 202,000.00
2018	BOW	TW A3	115	AAC	44,009	39	AC Restoration	\$ 397,000.00
2018	BOW	TW C2	310	AAC	30,619	54	AC Restoration	\$ 215,000.00
2018	BOW	TW C3	315	AAC	41,491	56	AC Restoration	\$ 291,000.00
2018	BOW	TW C3	320	AAC	4,912	34	AC Reconstruction	\$ 45,000.00
2018	BOW	TW F	610	AAC	30,778	40	AC Restoration	\$ 274,000.00
2018	BOW	TW F	615	AAC	5,898	63	AC Restoration	\$ 42,000.00
2018	BOW	TW G	705	AAC	32,612	36	AC Reconstruction	\$ 294,000.00
2018	BOW	TW G	710	AAC	34,447	19	AC Reconstruction	\$ 311,000.00
2020	BOW	RW 9R-27L	6225	AAC	44,518	64	AC Restoration	\$ 312,000.00
2020	BOW	TW D	420	AC	81,983	64	AC Restoration	\$ 574,000.00
2022	BOW	RW 9L-27R	6118	AAC	9,250	64	AC Restoration	\$ 65,000.00
2022	BOW	TW A2	112	AC	43,953	64	AC Restoration	\$ 308,000.00
2022	BOW	TW D	425	AC	32,996	64	AC Restoration	\$ 231,000.00
2024	BOW	RW 5-23	6320	AAC	40,640	64	AC Restoration	\$ 285,000.00
2024	BOW	RW 9L-27R	6124	AAC	30,000	64	AC Restoration	\$ 211,000.00
2025	BOW	RW 9L-27R	6115	AAC	440,000	64	AC Restoration	\$ 3,081,000.00
2026	BOW	RW 9L-27R	6105	AAC	30,000	64	AC Restoration	\$ 211,000.00
2026	BOW	RW 9L-27R	6125	APC	30,000	63	AC Restoration	\$ 211,000.00




Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2027	BOW	RW 9L-27R	6130	AAC	20,000	64	AC Restoration	\$ 141,000.00


**All values have been rounded to the nearest thousand-dollar.*

The following **Figure 6.3.1-1** summarizes the section-level major rehabilitation needs for a 10-year period between 2018 and 2027. **Figure 6.3.1-2** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.

Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year



Chapter 7





Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and re-inspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2018-2027. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- ▶ Develop a detailed preventive maintenance program for the airport.
- ▶ Further refine and implement the identified 10-year major rehabilitation needs.
- ▶ Maintain detailed records on pavement maintenance, construction, and inspection.
- ▶ Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



7.2 Supporting Documents

001 – Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

002 – Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the **Airport Response Form** provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

003 – Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

004 – Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation**. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.



7.3 Conclusion

The FDOT SAPMP Update Phase 1 2016-2017 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars **150/5380-7B “Airport Pavement Management Program (PMP)”** and **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** FDOT’s implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Appendix A

Airfield Pavement Analysis Tables



Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BOW	APRON FBO	AP FBO	APRON	4405	183	410	83,163	AC	1/1/2007
BOW	HOLD APRON ON TW A	AP H TW A	APRON	5105	500	50	29,073	AC	1/1/1942
BOW	NORTH APRON	AP N	APRON	4105	450	130	24,590	AAC	1/1/1990
BOW	NORTH APRON	AP N	APRON	4107	300	130	39,764	AAC	2/1/2012
BOW	NORTH APRON	AP N	APRON	4110	1050	300	254,768	PCC	1/1/1942
BOW	NORTH APRON	AP N	APRON	4112	180	187.5	34,136	PCC	1/1/2014
BOW	NORTH APRON	AP N	APRON	4115	550	50	30,089	AAC	1/1/1990
BOW	NORTH APRON	AP N	APRON	4120	125	40	4,597	AAC	1/1/1987
BOW	NORTH APRON	AP N	APRON	4125	350	100	23,419	AAC	1/1/1990
BOW	NORTH APRON	AP N	APRON	4127	120	50	6,397	AC	1/1/1998
BOW	NORTH APRON	AP N	APRON	4130	480	300	146,118	PCC	1/1/1942
BOW	NORTH APRON	AP N	APRON	4132	280	40	17,250	PCC	1/1/1942
BOW	T-HANGAR APRON	AP T-HANG	APRON	4210	125	25	30,250	PCC	1/1/2004
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6305	300	100	30,000	AAC	1/1/2001
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6310	550	100	55,000	AAC	1/1/2001
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6315	3550	100	353,620	AAC	1/1/2001
BOW	RUNWAY 5-23	RW 5-23	RUNWAY	6320	400	100	40,640	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6105	300	100	30,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6110	600	25	20,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6115	4400	100	440,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6118	360	25	9,250	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6120	7300	25	170,750	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6124	1100	25	30,000	AAC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6125	300	100	30,000	APC	1/1/2006
BOW	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6130	600	25	20,000	AAC	1/1/2006
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6205	3484	100	350,236	AC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6210	6966	25	175,118	AC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6215	300	100	30,000	PCC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6220	600	25	15,000	PCC	1/1/1942
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6225	454	100	44,518	AAC	1/1/2001
BOW	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6230	910	25	22,390	AAC	1/1/2001
BOW	T-HANGAR TAXILANE	T-HANG	TAXILANE	4205	2725	28	120,980	AC	1/1/2004
BOW	T-HANGAR TAXILANE	T-HANG	TAXILANE	4305	985	20	28,752	AC	1/1/2004
BOW	T-HANGAR TAXILANE	T-HANG	TAXILANE	4310	515	20	10,686	AC	9/1/2012
BOW	TAXIWAY A1	TW A1	TAXIWAY	105	1820	50	93,327	AAC	2/1/2012
BOW	TAXIWAY A2	TW A2	TAXIWAY	110	649	50	33,575	AAC	2/1/2012



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
BOW	TAXIWAY A2	TW A2	TAXIWAY	112	2400	55	43,953	AC	1/1/2003
BOW	TAXIWAY A2	TW A2	TAXIWAY	114	2400	55	6,638	AAC	1/1/2006
BOW	TAXIWAY A3	TW A3	TAXIWAY	115	1100	38	44,009	AAC	1/1/1987
BOW	TAXIWAY C1	TW C1	TAXIWAY	305	330	50	18,037	AAC	7/1/2009
BOW	TAXIWAY C2	TW C2	TAXIWAY	310	850	35	30,619	AAC	1/1/1987
BOW	TAXIWAY C3	TW C3	TAXIWAY	315	1175	35	41,491	AAC	1/1/1987
BOW	TAXIWAY C3	TW C3	TAXIWAY	320	125	35	4,912	AAC	1/1/1990
BOW	TAXIWAY D	TW D	TAXIWAY	405	2000	50	95,846	AAC	7/1/2009
BOW	TAXIWAY D	TW D	TAXIWAY	407	200	50	15,000	AAC	7/1/2009
BOW	TAXIWAY D	TW D	TAXIWAY	410	775	50	72,003	AC	6/1/2016
BOW	TAXIWAY D	TW D	TAXIWAY	415	1270	50	76,821	AC	6/1/2016
BOW	TAXIWAY D	TW D	TAXIWAY	420	2400	55	81,983	AC	1/1/2003
BOW	TAXIWAY D	TW D	TAXIWAY	425	1200	25	32,996	AC	1/1/2003
BOW	TAXIWAY F	TW F	TAXIWAY	605	85	90	10,259	AAC	1/1/2006
BOW	TAXIWAY F	TW F	TAXIWAY	610	340	90	30,778	AAC	1/1/1971
BOW	TAXIWAY F	TW F	TAXIWAY	615	290	120	5,898	AAC	1/1/2006
BOW	TAXIWAY F	TW F	TAXIWAY	620	290	120	37,090	AAC	2/1/2012
BOW	TAXIWAY G	TW G	TAXIWAY	705	210	150	32,612	AAC	1/1/1971
BOW	TAXIWAY G	TW G	TAXIWAY	710	210	150	34,447	AAC	1/1/1971
BOW	TAXIWAY H	TW H	TAXIWAY	802	25	50	3,573	AAC	2/1/2012
BOW	TAXIWAY H	TW H	TAXIWAY	805	475	50	24,823	AAC	2/1/2012



Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BOW	RUNWAY 9L-27R	RUNWAY	6105	30,000	83	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6110	20,000	87	Good
BOW	RUNWAY 9L-27R	RUNWAY	6115	440,000	80	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6118	9,250	73	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6120	170,750	88	Good
BOW	RUNWAY 9L-27R	RUNWAY	6124	30,000	78	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6125	30,000	82	Satisfactory
BOW	RUNWAY 9L-27R	RUNWAY	6130	20,000	86	Good
BOW	RUNWAY 9R-27L	RUNWAY	6205	350,236	22	Serious
BOW	RUNWAY 9R-27L	RUNWAY	6210	175,118	26	Very Poor
BOW	RUNWAY 9R-27L	RUNWAY	6215	30,000	76	Satisfactory
BOW	RUNWAY 9R-27L	RUNWAY	6220	15,000	77	Satisfactory
BOW	RUNWAY 9R-27L	RUNWAY	6225	44,518	69	Fair
BOW	RUNWAY 9R-27L	RUNWAY	6230	22,390	66	Fair
BOW	RUNWAY 5-23	RUNWAY	6305	30,000	53	Poor
BOW	RUNWAY 5-23	RUNWAY	6310	55,000	49	Poor
BOW	RUNWAY 5-23	RUNWAY	6315	353,620	53	Poor
BOW	RUNWAY 5-23	RUNWAY	6320	40,640	78	Satisfactory
BOW	TAXIWAY A1	TAXIWAY	105	93,327	82	Satisfactory
BOW	TAXIWAY A2	TAXIWAY	110	33,575	86	Good
BOW	TAXIWAY A2	TAXIWAY	112	43,953	69	Fair
BOW	TAXIWAY A2	TAXIWAY	114	6,638	84	Satisfactory
BOW	TAXIWAY A3	TAXIWAY	115	44,009	41	Poor
BOW	TAXIWAY C1	TAXIWAY	305	18,037	86	Good
BOW	TAXIWAY C2	TAXIWAY	310	30,619	56	Fair
BOW	TAXIWAY C3	TAXIWAY	315	41,491	58	Fair
BOW	TAXIWAY C3	TAXIWAY	320	4,912	38	Very Poor
BOW	TAXIWAY D	TAXIWAY	405	95,846	81	Satisfactory
BOW	TAXIWAY D	TAXIWAY	407	15,000	83	Satisfactory
BOW	TAXIWAY D	TAXIWAY	410	72,003	100	Good
BOW	TAXIWAY D	TAXIWAY	415	76,821	100	Good
BOW	TAXIWAY D	TAXIWAY	420	81,983	67	Fair
BOW	TAXIWAY D	TAXIWAY	425	32,996	69	Fair
BOW	TAXIWAY F	TAXIWAY	605	10,259	76	Satisfactory
BOW	TAXIWAY F	TAXIWAY	610	30,778	42	Poor
BOW	TAXIWAY F	TAXIWAY	615	5,898	65	Fair
BOW	TAXIWAY F	TAXIWAY	620	37,090	88	Good



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
BOW	TAXIWAY G	TAXIWAY	705	32,612	39	Very Poor
BOW	TAXIWAY G	TAXIWAY	710	34,447	23	Serious
BOW	TAXIWAY H	TAXIWAY	802	3,573	84	Satisfactory
BOW	TAXIWAY H	TAXIWAY	805	24,823	90	Good
BOW	T-HANGAR TAXILANE	TAXILANE	4205	120,980	47	Poor
BOW	T-HANGAR TAXILANE	TAXILANE	4305	28,752	64	Fair
BOW	T-HANGAR TAXILANE	TAXILANE	4310	10,686	89	Good
BOW	NORTH APRON	APRON	4105	24,590	54	Poor
BOW	NORTH APRON	APRON	4107	39,764	86	Good
BOW	NORTH APRON	APRON	4110	254,768	23	Serious
BOW	NORTH APRON	APRON	4112	34,136	96	Good
BOW	NORTH APRON	APRON	4115	30,089	58	Fair
BOW	NORTH APRON	APRON	4120	4,597	63	Fair
BOW	NORTH APRON	APRON	4125	23,419	64	Fair
BOW	NORTH APRON	APRON	4127	6,397	59	Fair
BOW	NORTH APRON	APRON	4130	146,118	64	Fair
BOW	NORTH APRON	APRON	4132	17,250	15	Serious
BOW	T-HANGAR APRON	APRON	4210	30,250	69	Fair
BOW	APRON FBO	APRON	4405	83,163	66	Fair
BOW	HOLD APRON ON TW A	APRON	5105	29,073	26	Very Poor



Table A-3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BOW	AP FBO	4405	66	64	63	61	59	58	56	55	53	51	50
BOW	AP H TW A	5105	26	24	23	21	19	18	16	15	13	11	10
BOW	AP N	4105	54	53	52	52	52	52	52	52	51	50	48
BOW	AP N	4107	86	83	82	80	79	77	76	74	71	69	66
BOW	AP N	4110	23	22	20	19	18	17	16	15	14	13	12
BOW	AP N	4112	96	93	90	87	84	82	79	77	74	72	70
BOW	AP N	4115	58	56	54	53	53	52	52	52	52	52	52
BOW	AP N	4120	63	60	58	56	55	54	53	52	52	52	52
BOW	AP N	4125	64	61	59	57	55	54	53	52	52	52	52
BOW	AP N	4127	59	57	56	54	52	51	49	48	46	44	43
BOW	AP N	4130	64	62	61	59	58	56	55	54	53	52	51
BOW	AP N	4132	15	14	12	11	10	9	8	7	6	5	4
BOW	AP T-HANG	4210	69	67	65	63	62	60	59	57	56	55	54
BOW	RW 5-23	6305	53	50	48	45	41	38	35	32	30	27	24
BOW	RW 5-23	6310	49	46	43	39	36	33	31	28	26	23	20
BOW	RW 5-23	6315	53	50	48	45	41	38	35	32	30	27	24
BOW	RW 5-23	6320	78	75	73	71	69	67	65	64	63	62	61
BOW	RW 9L-27R	6105	83	80	78	76	73	71	69	67	65	64	63
BOW	RW 9L-27R	6110	87	85	82	80	77	75	72	70	68	66	65
BOW	RW 9L-27R	6115	80	77	75	73	70	68	67	65	64	62	62
BOW	RW 9L-27R	6118	73	71	69	67	65	64	63	62	61	61	60
BOW	RW 9L-27R	6120	88	86	83	81	78	76	73	71	69	67	65
BOW	RW 9L-27R	6124	78	75	73	71	69	67	65	64	63	62	61
BOW	RW 9L-27R	6125	82	79	77	75	72	70	68	66	65	63	62
BOW	RW 9L-27R	6130	86	84	81	79	76	74	71	69	67	66	64
BOW	RW 9R-27L	6205	22	20	19	17	15	14	12	10	9	7	6
BOW	RW 9R-27L	6210	26	24	23	21	19	18	16	14	13	11	10
BOW	RW 9R-27L	6215	76	75	74	73	72	71	71	70	69	68	67
BOW	RW 9R-27L	6220	77	76	75	74	73	72	72	71	70	69	68
BOW	RW 9R-27L	6225	69	67	65	64	63	62	61	61	60	60	60
BOW	RW 9R-27L	6230	66	64	63	62	61	61	60	60	60	60	60
BOW	T-HANG	4205	47	45	44	42	40	39	37	36	35	34	33
BOW	T-HANG	4305	64	63	62	61	60	59	58	57	55	54	53
BOW	T-HANG	4310	89	86	84	82	80	77	76	74	72	71	70
BOW	TW A1	105	82	80	78	76	75	74	73	72	71	70	69
BOW	TW A2	110	86	83	81	79	77	76	75	73	72	72	71
BOW	TW A2	112	69	68	67	66	65	64	63	62	62	61	60



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
BOW	TW A2	114	84	82	80	78	76	75	74	73	72	71	70
BOW	TW A3	115	41	39	35	30	26	22	18	15	11	7	3
BOW	TW C1	305	86	83	81	79	77	76	75	73	72	72	71
BOW	TW C2	310	56	54	52	51	49	48	47	45	45	44	44
BOW	TW C3	315	58	56	54	53	51	49	48	47	46	45	44
BOW	TW C3	320	38	34	29	25	22	18	14	10	6	3	0
BOW	TW D	405	81	79	77	76	74	73	72	71	71	70	69
BOW	TW D	407	83	81	79	77	76	74	73	72	71	70	70
BOW	TW D	410	100	96	94	91	89	86	84	81	79	77	75
BOW	TW D	415	100	96	94	91	89	86	84	81	79	77	75
BOW	TW D	420	67	66	65	64	63	62	61	61	60	58	57
BOW	TW D	425	69	68	67	66	65	64	63	62	62	61	60
BOW	TW F	605	76	74	73	72	71	71	70	69	68	67	66
BOW	TW F	610	42	40	38	34	28	25	21	17	13	10	6
BOW	TW F	615	65	63	62	60	59	57	56	54	52	50	49
BOW	TW F	620	88	85	83	81	79	77	76	74	73	72	71
BOW	TW G	705	39	36	31	27	23	19	15	11	8	4	0
BOW	TW G	710	23	19	16	12	8	4	0	0	0	0	0
BOW	TW H	802	84	82	80	78	76	75	74	73	72	71	70
BOW	TW H	805	90	87	85	82	80	78	77	75	74	73	72

7/10/2017

Work History Report

Page 1 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP Branch: AP FBO APRON FBO Section: 4405 Surface: AC L.C.D.: 1/1/2007 Use: APRON Rank: P Length: 183.00 (Ft) Width: 410.00 (Ft) True Area: 83,163.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BARTOW MUNICIP Branch: AP H TW A HOLD APRON O Section: 5105 Surface: AC L.C.D.: 1/1/1942 Use: APRON Rank: P Length: 500.00 (Ft) Width: 50.00 (Ft) True Area: 29,073.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1942 AC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM

Network: BARTOW MUNICIP Branch: AP N NORTH APRON Section: 4105 Surface: AAC L.C.D.: 1/1/1990 Use: APRON Rank: P Length: 450.00 (Ft) Width: 130.00 (Ft) True Area: 24,590.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Estimated Rehabilitation Date
1/1/1990	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" P-401 OVERLAY ON EXISTING AC PAVEMENT

Network: BARTOW MUNICIP Branch: AP N NORTH APRON Section: 4107 Surface: AAC L.C.D.: 2/1/2012 Use: APRON Rank: P Length: 300.00 (Ft) Width: 130.00 (Ft) True Area: 39,764.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
2/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	3" MILL, 3' P-401 OVERLAY
1/1/1990	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" P-401 OVERLAY ON EXISTING AC PAVEMENT

Network: BARTOW MUNICIP Branch: AP N NORTH APRON Section: 4110 Surface: PCC L.C.D.: 1/1/1942 Use: APRON Rank: P Length: 1,050.00 (Ft) Width: 300.00 (Ft) True Area: 254,768.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	0.00	0.00	<input type="checkbox"/>	Estimated rehabilitation date
1/1/2014	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	0.00	0.00	<input type="checkbox"/>	Estimated rehabilitation date
1/1/1985	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1985: JOINT REPAIR
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM

7/10/2017

Work History Report

Page 2 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP		Branch: AP N		NORTH APRON		Section: 4112	Surface: PCC
L.C.D.: 1/1/2014	Use: APRON	Rank: P	Length: 180.00 (Ft)	Width: 187.50 (Ft)	True Area: 34,136.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	CR-PC	Complete Reconstruction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	Estimated Construction Date	
1/1/1985	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1985: JOINT REPAIR	
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT	

Network: BARTOW MUNICIP		Branch: AP N		NORTH APRON		Section: 4115	Surface: AAC
L.C.D.: 1/1/1990	Use: APRON	Rank: P	Length: 550.00 (Ft)	Width: 50.00 (Ft)	True Area: 30,089.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Estimated Rehabilitation Date	
1/1/1990	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1990	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1990: MINIMUM 2" P-401 OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 7" LIME ROCK BASE	

Network: BARTOW MUNICIP		Branch: AP N		NORTH APRON		Section: 4120	Surface: AAC
L.C.D.: 1/1/1987	Use: APRON	Rank: P	Length: 125.00 (Ft)	Width: 40.00 (Ft)	True Area: 4,597.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Estimated Rehabilitation Date	
1/1/1987	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1987: 2" AC OVERLAY	
1/1/1987	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1942	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1942: 2" AC ON 7.5" LIMEROCK	

Network: BARTOW MUNICIP		Branch: AP N		NORTH APRON		Section: 4125	Surface: AAC
L.C.D.: 1/1/1990	Use: APRON	Rank: P	Length: 350.00 (Ft)	Width: 100.00 (Ft)	True Area: 23,419.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Estimated Rehabilitation Date	
1/1/1990	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 7.5" LIME ROCK BASE	

7/10/2017

Work History Report

Page 3 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP Branch: AP N Section: 4127 Surface: AC L.C.D.: 1/1/1998 Use: APRON Rank: P Length: 120.00 (Ft) Width: 50.00 (Ft) True Area: 6,397.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Estimated Rehabilitation Date
1/1/1998	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1998: AC SURFACE

Network: BARTOW MUNICIP Branch: AP N Section: 4130 Surface: PCC L.C.D.: 1/1/1942 Use: APRON Rank: P Length: 480.00 (Ft) Width: 300.00 (Ft) True Area: 146,118.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM

Network: BARTOW MUNICIP Branch: AP N Section: 4132 Surface: PCC L.C.D.: 1/1/1942 Use: APRON Rank: P Length: 280.00 (Ft) Width: 40.00 (Ft) True Area: 17,250.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1942 PCC PAVEMENT

Network: BARTOW MUNICIP Branch: AP T-HANG T-HANGAR APR Section: 4210 Surface: PCC L.C.D.: 1/1/2004 Use: APRON Rank: T Length: 125.00 (Ft) Width: 25.00 (Ft) True Area: 30,250.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2004	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BARTOW MUNICIP Branch: RW 5-23 Section: 6305 Surface: AAC L.C.D.: 1/1/2001 Use: RUNWAY Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 30,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2001	ML-OV	MILL and OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	3"M&O in center 50" and 1" M&O in o
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991: SLURRY SEAL
1/1/1990	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" - 4" AC OVERLAY
1/1/1990	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT

7/10/2017

Work History Report

Page 4 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP		Branch: RW 5-23		RUNWAY 5-23		Section: 6310	Surface: AAC
L.C.D.: 1/1/2001	Use: RUNWAY	Rank: P	Length: 550.00 (Ft)	Width: 100.00 (Ft)	True Area: 55,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2001	ML-OV	MILL and OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	3"M&O in center 50" and 1" M&O in o 1991: SLURRY SEAL	
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>		
1/1/1990	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" - 4" AC OVERLAY	
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1971: 1.5" P-401 OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1942: 3" AC ON 8" LIME ROCK BASE	

Network: BARTOW MUNICIP		Branch: RW 5-23		RUNWAY 5-23		Section: 6315	Surface: AAC
L.C.D.: 1/1/2001	Use: RUNWAY	Rank: P	Length: 3,550.00 (Ft)	Width: 100.00 (Ft)	True Area: 353,620.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2001	ML-OV	MILL and OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	3"M&O in center 50" and 1" M&O in o 1991: SLURRY SEAL	
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>		
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1971: 1.5" P-401 OVERLAY	
1/1/1971	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1942	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1942: 3" AC ON 8" LIME ROCK BASE ON 6" SUBBASE	

Network: BARTOW MUNICIP		Branch: RW 5-23		RUNWAY 5-23		Section: 6320	Surface: AAC
L.C.D.: 1/1/2006	Use: RUNWAY	Rank: P	Length: 400.00 (Ft)	Width: 100.00 (Ft)	True Area: 40,640.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/2001	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: RW 9L-27R		RUNWAY 9L-27		Section: 6105	Surface: AAC
L.C.D.: 1/1/2006	Use: RUNWAY	Rank: P	Length: 300.00 (Ft)	Width: 100.00 (Ft)	True Area: 30,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1998 AC PAVEMENT UNKNOWN SECTION SOIL: SP-SM	
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1998	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

7/10/2017

Work History Report

Page 5 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP		Branch: RW 9L-27R RUNWAY 9L-27		Section: 6110		Surface: AAC
L.C.D.: 1/1/2006		Use: RUNWAY	Rank: P	Length: 600.00 (Ft)	Width: 25.00 (Ft)	True Area: 20,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1998	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	
						1998 AC PAVEMENT UNKNOWN SECTION

Network: BARTOW MUNICIP		Branch: RW 9L-27R RUNWAY 9L-27		Section: 6115		Surface: AAC
L.C.D.: 1/1/2006		Use: RUNWAY	Rank: P	Length: 4,400.00 (Ft)	Width: 100.00 (Ft)	True Area: 440,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1985	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1985: 1.5" - 6" P-401 OVERLAY
1/1/1942	IMPORT ED	BUILT	0.00	5.50	<input checked="" type="checkbox"/>	1942: 5.5" - 6" AC ON 8" - 10" LIME ROCK BASE

Network: BARTOW MUNICIP		Branch: RW 9L-27R RUNWAY 9L-27		Section: 6118		Surface: AAC
L.C.D.: 1/1/2006		Use: RUNWAY	Rank: P	Length: 360.00 (Ft)	Width: 25.00 (Ft)	True Area: 9,250.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME: 1985 P-401 OVERLAY
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	5.50	<input checked="" type="checkbox"/>	ASSUME: 1942 5.5" - 6" AC ON 8" - 10" LIME ROCK BASE

Network: BARTOW MUNICIP		Branch: RW 9L-27R RUNWAY 9L-27		Section: 6120		Surface: AAC
L.C.D.: 1/1/2006		Use: RUNWAY	Rank: P	Length: 7,300.00 (Ft)	Width: 25.00 (Ft)	True Area: 170,750.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	5.50	<input checked="" type="checkbox"/>	1942: 5.5" - 6" AC ON 8" - 10" LIME ROCK BASE

Network: BARTOW MUNICIP		Branch: RW 9L-27R RUNWAY 9L-27		Section: 6124		Surface: AAC
L.C.D.: 1/1/2006		Use: RUNWAY	Rank: P	Length: 1,100.00 (Ft)	Width: 25.00 (Ft)	True Area: 30,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME: 1985 P-401 OVERLAY
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	5.50	<input checked="" type="checkbox"/>	ASSUME: 1942 5.5" - 6" AC ON 8" - 10" LIME ROCK BASE

7/10/2017

Work History Report

Page 6 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP Branch: RW 9L-27R RUNWAY 9L-27 Section: 6125 Surface: APC						
L.C.D.: 1/1/2006 Use: RUNWAY Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 30,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM 1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	

Network: BARTOW MUNICIP Branch: RW 9L-27R RUNWAY 9L-27 Section: 6130 Surface: AAC						
L.C.D.: 1/1/2006 Use: RUNWAY Rank: P Length: 600.00 (Ft) Width: 25.00 (Ft) True Area: 20,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM 1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	

Network: BARTOW MUNICIP Branch: RW 9R-27L RUNWAY 9R-27 Section: 6205 Surface: AC						
L.C.D.: 1/1/1942 Use: RUNWAY Rank: S Length: 3,484.00 (Ft) Width: 100.00 (Ft) True Area: 350,236.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	5.50	<input checked="" type="checkbox"/>	1942: 5.5" - 6" AC ON 8" - 10" LIME ROCK BASE SOIL: SP-SM
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BARTOW MUNICIP Branch: RW 9R-27L RUNWAY 9R-27 Section: 6210 Surface: AC						
L.C.D.: 1/1/1942 Use: RUNWAY Rank: S Length: 6,966.00 (Ft) Width: 25.00 (Ft) True Area: 175,118.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1942	IMPORT ED	BUILT	0.00	5.50	<input checked="" type="checkbox"/>	1942: 5.5" - 6" AC ON 8" - 10" LIME ROCK BASE

Network: BARTOW MUNICIP Branch: RW 9R-27L RUNWAY 9R-27 Section: 6215 Surface: PCC						
L.C.D.: 1/1/1942 Use: RUNWAY Rank: S Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 30,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT

7/10/2017

Work History Report

Page 7 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP Branch: RW 9R-27L RUNWAY 9R-27 Section: 6220 Surface: PCC L.C.D.: 1/1/1942 Use: RUNWAY Rank: S Length: 600.00 (Ft) Width: 25.00 (Ft) True Area: 15,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT

Network: BARTOW MUNICIP Branch: RW 9R-27L RUNWAY 9R-27 Section: 6225 Surface: AAC L.C.D.: 1/1/2001 Use: RUNWAY Rank: S Length: 454.00 (Ft) Width: 100.00 (Ft) True Area: 44,518.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2001	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BARTOW MUNICIP Branch: RW 9R-27L RUNWAY 9R-27 Section: 6230 Surface: AAC L.C.D.: 1/1/2001 Use: RUNWAY Rank: S Length: 910.00 (Ft) Width: 25.00 (Ft) True Area: 22,390.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2001	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: BARTOW MUNICIP Branch: T-HANG T-HANGAR TAX Section: 4205 Surface: AC L.C.D.: 1/1/2004 Use: TAXILAN Rank: T Length: 2,725.00 (Ft) Width: 28.00 (Ft) True Area: 120,980.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	
1/1/2004	NU-IN	New Construction - Initial	0.00	2.00	<input checked="" type="checkbox"/>	2"AC/6"P-211/6"P-160

Network: BARTOW MUNICIP Branch: T-HANG T-HANGAR TAX Section: 4305 Surface: AC L.C.D.: 1/1/2004 Use: TAXILAN Rank: T Length: 985.00 (Ft) Width: 20.00 (Ft) True Area: 28,752.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2004	NU-IN	New Construction - Initial	0.00	2.00	<input checked="" type="checkbox"/>	2"AC/6"P-211/6"P-160

Network: BARTOW MUNICIP Branch: T-HANG T-HANGAR TAX Section: 4310 Surface: AC L.C.D.: 9/1/2012 Use: TAXILAN Rank: P Length: 515.00 (Ft) Width: 20.00 (Ft) True Area: 10,686.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2012	NU-IN	New Construction - Initial	0.00	2.00	<input checked="" type="checkbox"/>	2" FDOT SP 12.5, 6" P-211, 6" P-160

7/10/2017

Work History Report

Page 8 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP		Branch: TW A1		TAXIWAY A1		Section: 105	Surface: AAC
L.C.D.: 2/1/2012		Use: TAXIWAY	Rank: P	Length: 1,820.00 (Ft)	Width: 50.00 (Ft)	True Area: 93,327.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
2/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	3" MILL, 3" P-401 OVERLAY	
1/1/1987	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1987: 1.5" P-401 OVERLAY	
1/1/1987	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1942	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1942: 1" AC ON 7.5" LIME ROCK BASE	

Network: BARTOW MUNICIP		Branch: TW A2		TAXIWAY A2		Section: 110	Surface: AAC
L.C.D.: 2/1/2012		Use: TAXIWAY	Rank: P	Length: 649.00 (Ft)	Width: 50.00 (Ft)	True Area: 33,575.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
2/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1 1/2" MILL, 3" P-401 OVERLAY	
1/1/1987	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1987	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1987: 1.5" P-401 OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1942: 1" AC SURFACE ON 7.5" LIME ROCK BASE	

Network: BARTOW MUNICIP		Branch: TW A2		TAXIWAY A2		Section: 112	Surface: AC
L.C.D.: 1/1/2003		Use: TAXIWAY	Rank: P	Length: 2,400.00 (Ft)	Width: 55.00 (Ft)	True Area: 43,953.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: TW A2		TAXIWAY A2		Section: 114	Surface: AAC
L.C.D.: 1/1/2006		Use: TAXIWAY	Rank: P	Length: 2,400.00 (Ft)	Width: 55.00 (Ft)	True Area: 6,638.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: TW A3		TAXIWAY A3		Section: 115	Surface: AAC
L.C.D.: 1/1/1987		Use: TAXIWAY	Rank: P	Length: 1,100.00 (Ft)	Width: 38.00 (Ft)	True Area: 44,009.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1987	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1987: 1.5" P-401 OVERLAY	
1/1/1987	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1942	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1942: 1" AC ON 7.5" LIME ROCK BASE	

7/10/2017

Work History Report

Page 9 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIPAL		Branch: TW C1		TAXIWAY C1		Section: 305		Surface: AAC	
L.C.D.: 7/1/2009		Use: TAXIWAY		Rank: P		Length: 330.00 (Ft)		Width: 50.00 (Ft) True Area: 18,037.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
7/1/2009	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM 1987: 1.5" P-401 OVERLAY 1942: 1" AC ON 7.5" LIME ROCK BASE			
1/1/1987	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>				
1/1/1987	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>				
1/1/1942	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>				

Network: BARTOW MUNICIPAL		Branch: TW C2		TAXIWAY C2		Section: 310		Surface: AAC	
L.C.D.: 1/1/1987		Use: TAXIWAY		Rank: P		Length: 850.00 (Ft)		Width: 35.00 (Ft) True Area: 30,619.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/1987	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1987: 1.5" P-401 OVERLAY			
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1971: 1.5" P-401 OVERLAY			
1/1/1942	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1942: 1" AC ON 7.5" LIME ROCK BASE			

Network: BARTOW MUNICIPAL		Branch: TW C3		TAXIWAY C3		Section: 315		Surface: AAC	
L.C.D.: 1/1/1987		Use: TAXIWAY		Rank: P		Length: 1,175.00 (Ft)		Width: 35.00 (Ft) True Area: 41,491.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/1987	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM			
1/1/1987	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1987: 1.5" P-401 OVERLAY			
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1971: 1.5" P-401 OVERLAY			
1/1/1942	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1942: 1" AC ON 7.5" LIME ROCK BASE			

Network: BARTOW MUNICIPAL		Branch: TW C3		TAXIWAY C3		Section: 320		Surface: AAC	
L.C.D.: 1/1/1990		Use: TAXIWAY		Rank: P		Length: 125.00 (Ft)		Width: 35.00 (Ft) True Area: 4,912.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/1990	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME: 1990 AC OVERLAY			
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	ASSUME: 1971 1.5" P-401 OVERLAY			
1/1/1942	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	ASSUME: 1942 1" AC ON 7.5" LIME ROCK BASE			

7/10/2017

Work History Report

Page 10 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP		Branch: TW D		TAXIWAY D		Section: 405	Surface: AAC
L.C.D.: 7/1/2009		Use: TAXIWAY	Rank: P	Length: 2,000.00 (Ft)	Width: 50.00 (Ft)	True Area: 95,846.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
7/1/2009	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM 1984: 3" P-401 ON 8" P-211	
1/1/1984	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1984	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: TW D		TAXIWAY D		Section: 407	Surface: AAC
L.C.D.: 7/1/2009		Use: TAXIWAY	Rank: P	Length: 200.00 (Ft)	Width: 50.00 (Ft)	True Area: 15,000.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
7/1/2009	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME: 1984 3" P-401 OVERLAY ASSUME: 1942 AC PAVEMENT	
1/1/1984	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: TW D		TAXIWAY D		Section: 410	Surface: AC
L.C.D.: 6/1/2016		Use: TAXIWAY	Rank: P	Length: 775.00 (Ft)	Width: 50.00 (Ft)	True Area: 72,003.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160	

Network: BARTOW MUNICIP		Branch: TW D		TAXIWAY D		Section: 415	Surface: AC
L.C.D.: 6/1/2016		Use: TAXIWAY	Rank: P	Length: 1,270.00 (Ft)	Width: 50.00 (Ft)	True Area: 76,821.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160	

Network: BARTOW MUNICIP		Branch: TW D		TAXIWAY D		Section: 420	Surface: AC
L.C.D.: 1/1/2003		Use: TAXIWAY	Rank: P	Length: 2,400.00 (Ft)	Width: 55.00 (Ft)	True Area: 81,983.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2003	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4"AC/9"P-211	

Network: BARTOW MUNICIP		Branch: TW D		TAXIWAY D		Section: 425	Surface: AC
L.C.D.: 1/1/2003		Use: TAXIWAY	Rank: P	Length: 1,200.00 (Ft)	Width: 25.00 (Ft)	True Area: 32,996.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2003	NU-IN	New Construction - Initial	0.00	2.00	<input checked="" type="checkbox"/>	2" AC/6" P211	

7/10/2017

Work History Report

Page 11 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP		Branch: TW F		TAXIWAY F		Section: 605	Surface: AAC
L.C.D.: 1/1/2006		Use: TAXIWAY	Rank: P	Length: 85.00 (Ft)	Width: 90.00 (Ft)	True Area: 10,259.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1971	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: TW F		TAXIWAY F		Section: 610	Surface: AAC
L.C.D.: 1/1/1971		Use: TAXIWAY	Rank: P	Length: 340.00 (Ft)	Width: 90.00 (Ft)	True Area: 30,778.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	SOIL: SP-SM	
1/1/1971	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: TW F		TAXIWAY F		Section: 615	Surface: AAC
L.C.D.: 1/1/2006		Use: TAXIWAY	Rank: P	Length: 290.00 (Ft)	Width: 120.00 (Ft)	True Area: 5,898.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1990	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1990	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>		

Network: BARTOW MUNICIP		Branch: TW F		TAXIWAY F		Section: 620	Surface: AAC
L.C.D.: 2/1/2012		Use: TAXIWAY	Rank: P	Length: 290.00 (Ft)	Width: 120.00 (Ft)	True Area: 37,090.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
2/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1990	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1990	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>		

7/10/2017

Work History Report

Page 12 of 13

Pavement Database: FDOT

Network: BARTOW MUNICIP		Branch: TW G		TAXIWAY G		Section: 705	Surface: AAC
L.C.D.: 1/1/1971		Use: TAXIWAY	Rank: P	Length: 210.00 (Ft)	Width: 150.00 (Ft)	True Area: 32,612.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991: SLURRY SEAL	
1/1/1971	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1971: P-401 OVERLAY	
1/1/1971	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1942	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1942: 3" AC ON 8" EXISTING LIME ROCK	

Network: BARTOW MUNICIP		Branch: TW G		TAXIWAY G		Section: 710	Surface: AAC
L.C.D.: 1/1/1971		Use: TAXIWAY	Rank: P	Length: 210.00 (Ft)	Width: 150.00 (Ft)	True Area: 34,447.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1971	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1971: 1.5" P-401 OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1942: 3" AC ON 8" LIME ROCK BASE	

Network: BARTOW MUNICIP		Branch: TW H		TAXIWAY H		Section: 802	Surface: AAC
L.C.D.: 2/1/2012		Use: TAXIWAY	Rank: P	Length: 25.00 (Ft)	Width: 50.00 (Ft)	True Area: 3,573.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
2/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1 1/2" MILL, 3" P-401 OVERLAY	
1/1/1971	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1971 AC PAVEMENT	

Network: BARTOW MUNICIP		Branch: TW H		TAXIWAY H		Section: 805	Surface: AAC
L.C.D.: 2/1/2012		Use: TAXIWAY	Rank: P	Length: 475.00 (Ft)	Width: 50.00 (Ft)	True Area: 24,823.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
2/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1 1/2" MILL, 3" P-401 OVERLAY	
1/1/1971	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1971 AC PAVEMENT	
1/1/1971	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP-SM	

Work History Report*Pavement Database: FDOT***Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	43	2,925,471.00	3.19	2.84
Complete Reconstruction - PCC	1	34,136.00	0.00	0.00
FDOT - PATCHING - PCC PARTIAL DEPTH	1	254,768.00	0.00	0.00
FDOT - SLAB REPLACEMENT - PCC	1	254,768.00	0.00	0.00
MILL and OVERLAY	26	1,679,998.00	0.35	0.96
New Construction - AC	3	231,987.00	0.00	0.00
New Construction - Initial	11	463,786.00	1.09	1.31
OVERLAY	59	4,212,145.00	0.64	0.85
Overlay - AC Structural	1	23,419.00	0.00	0.00
REPAIR	7	790,914.00	0.00	0.00
Surface Treatment - Seal Coat	5	89,092.00	0.00	0.00
Surface Treatment - Slurry Seal	1	120,980.00	0.00	0.00

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP FBO	1	183.00	410.00	83,163.00	APRON	66.00	0.00	66.00
AP H TW A	1	500.00	50.00	29,073.00	APRON	26.00	0.00	26.00
AP N	10	3,885.00	132.75	581,128.00	APRON	58.20	23.27	47.16
AP T-HAN	1	125.00	25.00	30,250.00	APRON	69.00	0.00	69.00
RW 5-23	4	4,800.00	100.00	479,260.00	RUNWAY	58.25	11.52	54.66
RW 9L-27R	8	14,960.00	53.12	750,000.00	RUNWAY	82.13	4.73	82.20
RW 9R-27L	6	12,714.00	62.50	637,262.00	RUNWAY	56.00	22.97	31.77
T-HANG	3	4,225.00	22.67	160,418.00	TAXILANE	66.67	17.25	52.84
TW A1	1	1,820.00	50.00	93,327.00	TAXIWAY	82.00	0.00	82.00
TW A2	3	5,449.00	53.33	84,166.00	TAXIWAY	79.67	7.59	76.96
TW A3	1	1,100.00	38.00	44,009.00	TAXIWAY	41.00	0.00	41.00
TW C1	1	330.00	50.00	18,037.00	TAXIWAY	86.00	0.00	86.00
TW C2	1	850.00	35.00	30,619.00	TAXIWAY	56.00	0.00	56.00
TW C3	2	1,300.00	35.00	46,403.00	TAXIWAY	48.00	10.00	55.88
TW D	6	7,845.00	46.67	374,649.00	TAXIWAY	83.33	13.12	84.51
TW F	4	1,005.00	105.00	84,025.00	TAXIWAY	67.75	16.95	68.07
TW G	2	420.00	150.00	67,059.00	TAXIWAY	31.00	8.00	30.78
TW H	2	500.00	50.00	28,396.00	TAXIWAY	87.00	3.00	89.25

7/10/2017**Branch Condition Report****Page 2 of 2***Pavement Database: FDOT*

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	13	723614.000221192	57.15	22.56	49.39
RUNWAY	18	1866522.00047623	68.11	19.32	57.91
TAXILANE	3	160418.000012055	66.67	17.25	52.84
TAXIWAY	23	870690.000236505	69.87	20.95	73.24
ALL	57	3621244.00094598	66.25	21.26	59.67

Pavement Database: FDOT

NetworkId: BOW

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP FBO	4405	1/1/2007	AC	APRON	P	0	83,163.00	3/6/2017	10	66
AP H TW A	5105	1/1/1942	AC	APRON	P	0	29,073.00	3/6/2017	75	26
AP N	4105	1/1/1990	AAC	APRON	P	0	24,590.00	3/6/2017	27	54
AP N	4107	2/1/2012	AAC	APRON	P	0	39,764.00	3/6/2017	5	86
AP N	4110	1/1/1942	PCC	APRON	P	0	254,768.00	3/6/2017	75	23
AP N	4112	1/1/2014	PCC	APRON	P	0	34,136.00	3/6/2017	3	96
AP N	4115	1/1/1990	AAC	APRON	P	0	30,089.00	3/6/2017	27	58
AP N	4120	1/1/1987	AAC	APRON	P	0	4,597.00	3/6/2017	30	63
AP N	4125	1/1/1990	AAC	APRON	P	0	23,419.00	3/6/2017	27	64
AP N	4127	1/1/1998	AC	APRON	P	0	6,397.00	3/6/2017	19	59
AP N	4130	1/1/1942	PCC	APRON	P	0	146,118.00	3/6/2017	75	64
AP N	4132	1/1/1942	PCC	APRON	P	0	17,250.00	3/6/2017	75	15
AP T-HANG	4210	1/1/2004	PCC	APRON	T	0	30,250.00	3/6/2017	13	69
RW 5-23	6305	1/1/2001	AAC	RUNWAY	P	0	30,000.00	3/6/2017	16	53
RW 5-23	6310	1/1/2001	AAC	RUNWAY	P	0	55,000.00	3/6/2017	16	49
RW 5-23	6315	1/1/2001	AAC	RUNWAY	P	0	353,620.00	3/6/2017	16	53
RW 5-23	6320	1/1/2006	AAC	RUNWAY	P	0	40,640.00	3/6/2017	11	78
RW 9L-27R	6105	1/1/2006	AAC	RUNWAY	P	0	30,000.00	3/6/2017	11	83
RW 9L-27R	6110	1/1/2006	AAC	RUNWAY	P	0	20,000.00	3/6/2017	11	87
RW 9L-27R	6115	1/1/2006	AAC	RUNWAY	P	0	440,000.00	3/6/2017	11	80
RW 9L-27R	6118	1/1/2006	AAC	RUNWAY	P	0	9,250.00	3/6/2017	11	73
RW 9L-27R	6120	1/1/2006	AAC	RUNWAY	P	0	170,750.00	3/6/2017	11	88
RW 9L-27R	6124	1/1/2006	AAC	RUNWAY	P	0	30,000.00	3/6/2017	11	78
RW 9L-27R	6125	1/1/2006	APC	RUNWAY	P	0	30,000.00	3/6/2017	11	82
RW 9L-27R	6130	1/1/2006	AAC	RUNWAY	P	0	20,000.00	3/6/2017	11	86
RW 9R-27L	6205	1/1/1942	AC	RUNWAY	S	0	350,236.00	3/6/2017	75	22
RW 9R-27L	6210	1/1/1942	AC	RUNWAY	S	0	175,118.00	3/6/2017	75	26
RW 9R-27L	6215	1/1/1942	PCC	RUNWAY	S	0	30,000.00	3/6/2017	75	76
RW 9R-27L	6220	1/1/1942	PCC	RUNWAY	S	0	15,000.00	3/6/2017	75	77
RW 9R-27L	6225	1/1/2001	AAC	RUNWAY	S	0	44,518.00	3/6/2017	16	69
RW 9R-27L	6230	1/1/2001	AAC	RUNWAY	S	0	22,390.00	3/6/2017	16	66
T-HANG	4205	1/1/2004	AC	TAXILANE	T	0	120,980.00	3/6/2017	13	47
T-HANG	4305	1/1/2004	AC	TAXILANE	T	0	28,752.00	3/6/2017	13	64
T-HANG	4310	9/1/2012	AC	TAXILANE	P	0	10,686.00	3/6/2017	5	89
TW A1	105	2/1/2012	AAC	TAXIWAY	P	0	93,327.00	3/6/2017	5	82
TW A2	110	2/1/2012	AAC	TAXIWAY	P	0	33,575.00	3/6/2017	5	86
TW A2	112	1/1/2003	AC	TAXIWAY	P	0	43,953.00	3/6/2017	14	69
TW A2	114	1/1/2006	AAC	TAXIWAY	P	0	6,638.00	3/6/2017	11	84
TW A3	115	1/1/1987	AAC	TAXIWAY	P	0	44,009.00	3/6/2017	30	41
TW C1	305	7/1/2009	AAC	TAXIWAY	P	0	18,037.00	3/6/2017	8	86
TW C2	310	1/1/1987	AAC	TAXIWAY	P	0	30,619.00	3/6/2017	30	56
TW C3	315	1/1/1987	AAC	TAXIWAY	P	0	41,491.00	3/6/2017	30	58
TW C3	320	1/1/1990	AAC	TAXIWAY	P	0	4,912.00	3/6/2017	27	38
TW D	405	7/1/2009	AAC	TAXIWAY	P	0	95,846.00	3/6/2017	8	81
TW D	407	7/1/2009	AAC	TAXIWAY	P	0	15,000.00	3/6/2017	8	83
TW D	410	6/1/2016	AC	TAXIWAY	P	0	72,003.00	6/1/2016	0	100
TW D	415	6/1/2016	AC	TAXIWAY	P	0	76,821.00	6/1/2016	0	100
TW D	420	1/1/2003	AC	TAXIWAY	P	0	81,983.00	3/6/2017	14	67

7/10/2017		Section Condition Report						Page 2 of 3		
TW D	425	1/1/2003	AC	TAXIWAY	P	0	32,996.00	3/6/2017	14	69
TW F	605	1/1/2006	AAC	TAXIWAY	P	0	10,259.00	3/6/2017	11	76
TW F	610	1/1/1971	AAC	TAXIWAY	P	0	30,778.00	3/6/2017	46	42
TW F	615	1/1/2006	AAC	TAXIWAY	P	0	5,898.00	3/6/2017	11	65
TW F	620	2/1/2012	AAC	TAXIWAY	P	0	37,090.00	3/6/2017	5	88
TW G	705	1/1/1971	AAC	TAXIWAY	P	0	32,612.00	3/6/2017	46	39
TW G	710	1/1/1971	AAC	TAXIWAY	P	0	34,447.00	3/6/2017	46	23
TW H	802	2/1/2012	AAC	TAXIWAY	P	0	3,573.00	3/6/2017	5	84
TW H	805	2/1/2012	AAC	TAXIWAY	P	0	24,823.00	3/6/2017	5	90

7/10/2017

Section Condition Report (Summary)

Page 3 of 3

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		148,824.00	2	100.00	0.00	100.00
03-05	5	276,974.00	8	87.63	4.00	86.60
06-10	9	212,046.00	4	79.00	7.71	75.68
11-15	12	1,152,349.00	18	74.72	10.14	75.46
16-20	17	511,925.00	6	58.17	7.27	54.61
26-30	29	203,726.00	8	54.00	8.96	53.86
41-50	46	97,837.00	3	34.67	8.34	34.31
ALL	24	3,621,244.00	57	66.25	21.26	59.67
Over 50	75	1,017,563.00	8	41.13	24.65	31.37

Appendix B

Airfield Pavement Localized Maintenance and Repair and
Major Rehabilitation



Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BOW	AP FBO	4405	52	RAVELING	Low	83163.05	SqFt	100.0%	FDOT - SURFACE SEAL	83163.05	SqFt	\$ 0.55	\$ 45,750.00
BOW	AP H TW A	5105	43	BLOCK CR	Medium	15329.42	SqFt	52.7%	FDOT - CRACK SEALING - AC	4672.24	Ft	\$ 3.00	\$ 14,020.00
BOW	AP H TW A	5105	48	L & T CR	Medium	528.61	Ft	1.8%	FDOT - CRACK SEALING - AC	528.54	Ft	\$ 3.00	\$ 1,590.00
BOW	AP H TW A	5105	52	RAVELING	Medium	29073	SqFt	100.0%	FDOT - PATCHING - AC PARTIAL DEPTH	29073.32	SqFt	\$ 3.00	\$ 87,220.00
BOW	AP N	4110	63	LINEAR CR	Medium	266.86	Slabs	32.7%	FDOT - CRACK SEALING - PCC	5003.61	Ft	\$ 4.25	\$ 21,270.00
BOW	AP N	4110	65	JT SEAL DMG	Low	815	Slabs	100.0%	FDOT - JOINT SEAL - PCC	36450.13	Ft	\$ 2.75	\$ 100,240.00
BOW	AP N	4110	66	SMALL PATCH	Medium	50.49	Slabs	6.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	135.63	SqFt	\$ 72.00	\$ 9,790.00
BOW	AP N	4110	72	SHAT. SLAB	Low	158.67	Slabs	19.5%	FDOT - CRACK SEALING - PCC	5950.13	Ft	\$ 4.25	\$ 25,290.00
BOW	AP N	4110	72	SHAT. SLAB	Medium	50.49	Slabs	6.2%	FDOT - SLAB REPLACEMENT - PCC	15776.66	SqFt	\$ 30.00	\$ 473,320.00
BOW	AP N	4110	74	JOINT SPALL	Low	43.27	Slabs	5.3%	FDOT - CRACK SEALING - PCC	70.87	Ft	\$ 4.25	\$ 310.00
BOW	AP N	4110	74	JOINT SPALL	Medium	57.7	Slabs	7.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	372.43	SqFt	\$ 72.00	\$ 26,840.00
BOW	AP N	4110	75	CORNER SPALL	Low	36.06	Slabs	4.4%	FDOT - CRACK SEALING - PCC	59.06	Ft	\$ 4.25	\$ 260.00
BOW	AP N	4110	75	CORNER SPALL	Medium	14.42	Slabs	1.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	38.75	SqFt	\$ 72.00	\$ 2,800.00
BOW	AP N	4112	74	JOINT SPALL	Low	6.23	Slabs	2.9%	FDOT - CRACK SEALING - PCC	10.17	Ft	\$ 4.25	\$ 50.00
BOW	AP N	4115	50	PATCHING	Medium	116.47	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	163.61	SqFt	\$ 6.00	\$ 990.00
BOW	AP N	4120	54	SHOVING	Medium	11.95	SqFt	0.3%	FDOT - MILLING - AC	30.14	SqFt	\$ 2.00	\$ 60.00
BOW	AP N	4125	45	DEPRESSION	Low	358.76	SqFt	1.5%	FDOT - PATCHING - AC FULL DEPTH	439.17	SqFt	\$ 6.00	\$ 2,640.00
BOW	AP N	4130	62	CORNER BREAK	Low	17.51	Slabs	2.3%	FDOT - CRACK SEALING - PCC	143.7	Ft	\$ 4.25	\$ 620.00
BOW	AP N	4130	65	JT SEAL DMG	High	779	Slabs	100.0%	FDOT - JOINT SEAL - PCC	20339.9	Ft	\$ 2.75	\$ 55,940.00
BOW	AP N	4130	66	SMALL PATCH	Medium	17.51	Slabs	2.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	47.36	SqFt	\$ 72.00	\$ 3,400.00
BOW	AP N	4130	67	LARGE PATCH	Medium	43.76	Slabs	5.6%	FDOT - PATCHING - PCC FULL DEPTH	3230.25	SqFt	\$ 100.00	\$ 323,070.00
BOW	AP N	4130	71	FAULTING	Medium	8.75	Slabs	1.1%	FDOT - GRINDING (LOCALIZED)	131.23	Ft	\$ 2.00	\$ 270.00
BOW	AP N	4130	74	JOINT SPALL	Low	17.51	Slabs	2.3%	FDOT - CRACK SEALING - PCC	28.87	Ft	\$ 4.25	\$ 130.00
BOW	AP N	4130	74	JOINT SPALL	Medium	35.01	Slabs	4.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	226.04	SqFt	\$ 72.00	\$ 16,290.00
BOW	AP N	4130	75	CORNER SPALL	Low	8.75	Slabs	1.1%	FDOT - CRACK SEALING - PCC	14.44	Ft	\$ 4.25	\$ 70.00
BOW	AP N	4132	63	LINEAR CR	Medium	14.67	Slabs	26.7%	FDOT - CRACK SEALING - PCC	274.93	Ft	\$ 4.25	\$ 1,170.00
BOW	AP N	4132	65	JT SEAL DMG	Low	55	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1023.95	Ft	\$ 2.75	\$ 2,820.00
BOW	AP N	4132	72	SHAT. SLAB	Low	25.67	Slabs	46.7%	FDOT - CRACK SEALING - PCC	962.6	Ft	\$ 4.25	\$ 4,100.00
BOW	AP N	4132	72	SHAT. SLAB	Medium	3.67	Slabs	6.7%	FDOT - SLAB REPLACEMENT - PCC	1146.36	SqFt	\$ 30.00	\$ 34,380.00
BOW	AP N	4132	74	JOINT SPALL	Low	3.67	Slabs	6.7%	FDOT - CRACK SEALING - PCC	5.91	Ft	\$ 4.25	\$ 30.00
BOW	AP N	4132	74	JOINT SPALL	Medium	7.33	Slabs	13.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	47.36	SqFt	\$ 72.00	\$ 3,420.00
BOW	AP T-HANG	4210	62	CORNER BREAK	Low	8.08	Slabs	4.2%	FDOT - CRACK SEALING - PCC	66.27	Ft	\$ 4.25	\$ 290.00
BOW	AP T-HANG	4210	62	CORNER BREAK	Medium	4.04	Slabs	2.1%	FDOT - PATCHING - PCC FULL DEPTH	130.24	SqFt	\$ 100.00	\$ 13,060.00
BOW	AP T-HANG	4210	65	JT SEAL DMG	High	194	Slabs	100.0%	FDOT - JOINT SEAL - PCC	350.07	Ft	\$ 2.75	\$ 970.00
BOW	AP T-HANG	4210	72	SHAT. SLAB	Low	8.08	Slabs	4.2%	FDOT - CRACK SEALING - PCC	202.1	Ft	\$ 4.25	\$ 860.00
BOW	AP T-HANG	4210	74	JOINT SPALL	Medium	4.04	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.83	SqFt	\$ 72.00	\$ 1,880.00
BOW	RW 5-23	6305	45	DEPRESSION	Low	72.01	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	109.79	SqFt	\$ 6.00	\$ 670.00
BOW	RW 5-23	6305	52	RAVELING	Low	28628.99	SqFt	95.4%	FDOT - SURFACE SEAL	28628.77	SqFt	\$ 0.55	\$ 15,750.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BOW	RW 5-23	6305	52	RAVELING	Medium	1292.96	SqFt	4.3%	FDOT - PATCHING - AC PARTIAL DEPTH	1292.75	SqFt	\$ 3.00	\$ 3,880.00
BOW	RW 5-23	6305	56	SWELLING	Medium	630.01	SqFt	2.1%	FDOT - PATCHING - AC FULL DEPTH	735.18	SqFt	\$ 6.00	\$ 4,420.00
BOW	RW 5-23	6310	48	L & T CR	Medium	894.65	Ft	1.6%	FDOT - CRACK SEALING - AC	894.69	Ft	\$ 3.00	\$ 2,690.00
BOW	RW 5-23	6310	52	RAVELING	Low	50416.65	SqFt	91.7%	FDOT - SURFACE SEAL	50417.08	SqFt	\$ 0.55	\$ 27,730.00
BOW	RW 5-23	6310	52	RAVELING	Medium	4583.38	SqFt	8.3%	FDOT - PATCHING - AC PARTIAL DEPTH	4583.27	SqFt	\$ 3.00	\$ 13,750.00
BOW	RW 5-23	6310	56	SWELLING	Medium	1143.99	SqFt	2.1%	FDOT - PATCHING - AC FULL DEPTH	1284.13	SqFt	\$ 6.00	\$ 7,710.00
BOW	RW 5-23	6315	43	BLOCK CR	Medium	13577.06	SqFt	3.8%	FDOT - CRACK SEALING - AC	4138.45	Ft	\$ 3.00	\$ 12,420.00
BOW	RW 5-23	6315	45	DEPRESSION	Low	240.57	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	306.77	SqFt	\$ 6.00	\$ 1,850.00
BOW	RW 5-23	6315	48	L & T CR	Medium	2795.28	Ft	0.8%	FDOT - CRACK SEALING - AC	2795.28	Ft	\$ 3.00	\$ 8,390.00
BOW	RW 5-23	6315	52	RAVELING	Low	335275.04	SqFt	94.8%	FDOT - SURFACE SEAL	335275.4	SqFt	\$ 0.55	\$ 184,410.00
BOW	RW 5-23	6315	52	RAVELING	Medium	8241.5	SqFt	2.3%	FDOT - PATCHING - AC PARTIAL DEPTH	8241.93	SqFt	\$ 3.00	\$ 24,730.00
BOW	RW 5-23	6315	52	RAVELING	High	10103.44	SqFt	2.9%	FDOT - PATCHING - AC PARTIAL DEPTH	10103.01	SqFt	\$ 3.00	\$ 30,320.00
BOW	RW 5-23	6315	56	SWELLING	Medium	173.19	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	230.35	SqFt	\$ 6.00	\$ 1,390.00
BOW	RW 9L-27R	6105	52	RAVELING	Low	1499.95	SqFt	5.0%	FDOT - SURFACE SEAL	1500.49	SqFt	\$ 0.55	\$ 830.00
BOW	RW 9L-27R	6110	48	L & T CR	Medium	20.01	Ft	0.1%	FDOT - CRACK SEALING - AC	20.01	Ft	\$ 3.00	\$ 60.00
BOW	RW 9L-27R	6115	52	RAVELING	Low	54266.68	SqFt	12.3%	FDOT - SURFACE SEAL	54266.25	SqFt	\$ 0.55	\$ 29,850.00
BOW	RW 9L-27R	6118	45	DEPRESSION	Low	174.16	SqFt	1.9%	FDOT - PATCHING - AC FULL DEPTH	231.42	SqFt	\$ 6.00	\$ 1,390.00
BOW	RW 9L-27R	6118	52	RAVELING	Low	435.29	SqFt	4.7%	FDOT - SURFACE SEAL	434.86	SqFt	\$ 0.55	\$ 240.00
BOW	RW 9L-27R	6120	52	RAVELING	Low	121.96	SqFt	0.1%	FDOT - SURFACE SEAL	121.63	SqFt	\$ 0.55	\$ 70.00
BOW	RW 9L-27R	6124	45	DEPRESSION	Low	168.02	SqFt	0.6%	FDOT - PATCHING - AC FULL DEPTH	223.89	SqFt	\$ 6.00	\$ 1,350.00
BOW	RW 9L-27R	6124	48	L & T CR	Medium	24.02	Ft	0.1%	FDOT - CRACK SEALING - AC	23.95	Ft	\$ 3.00	\$ 80.00
BOW	RW 9L-27R	6124	52	RAVELING	Low	299.99	SqFt	1.0%	FDOT - SURFACE SEAL	300.31	SqFt	\$ 0.55	\$ 170.00
BOW	RW 9L-27R	6125	52	RAVELING	Low	2249.98	SqFt	7.5%	FDOT - SURFACE SEAL	2249.66	SqFt	\$ 0.55	\$ 1,240.00
BOW	RW 9L-27R	6130	52	RAVELING	Low	999.97	SqFt	5.0%	FDOT - SURFACE SEAL	999.97	SqFt	\$ 0.55	\$ 550.00
BOW	RW 9R-27L	6205	41	ALLIGATOR CR	Low	337.45	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	415.49	SqFt	\$ 6.00	\$ 2,500.00
BOW	RW 9R-27L	6205	43	BLOCK CR	Medium	109950.44	SqFt	31.4%	FDOT - CRACK SEALING - AC	33512.8	Ft	\$ 3.00	\$ 100,540.00
BOW	RW 9R-27L	6205	48	L & T CR	Medium	482.12	Ft	0.1%	FDOT - CRACK SEALING - AC	482.28	Ft	\$ 3.00	\$ 1,450.00
BOW	RW 9R-27L	6205	50	PATCHING	Medium	1108.9	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	1246.46	SqFt	\$ 6.00	\$ 7,490.00
BOW	RW 9R-27L	6205	52	RAVELING	Medium	346991.23	SqFt	99.1%	FDOT - PATCHING - AC PARTIAL DEPTH	346990.8	SqFt	\$ 3.00	\$ 1,040,980.00
BOW	RW 9R-27L	6205	52	RAVELING	High	2077.97	SqFt	0.6%	FDOT - PATCHING - AC PARTIAL DEPTH	2078.51	SqFt	\$ 3.00	\$ 6,240.00
BOW	RW 9R-27L	6210	43	BLOCK CR	Medium	28473.34	SqFt	16.3%	FDOT - CRACK SEALING - AC	8678.81	Ft	\$ 3.00	\$ 26,040.00
BOW	RW 9R-27L	6210	50	PATCHING	Medium	33.8	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	61.35	SqFt	\$ 6.00	\$ 370.00
BOW	RW 9R-27L	6210	52	RAVELING	Medium	174601.93	SqFt	99.7%	FDOT - PATCHING - AC PARTIAL DEPTH	174602.5	SqFt	\$ 3.00	\$ 523,810.00
BOW	RW 9R-27L	6210	52	RAVELING	High	482.22	SqFt	0.3%	FDOT - PATCHING - AC PARTIAL DEPTH	482.22	SqFt	\$ 3.00	\$ 1,450.00
BOW	RW 9R-27L	6215	65	JT SEAL DMG	High	192	Slabs	100.0%	FDOT - JOINT SEAL - PCC	4399.93	Ft	\$ 2.75	\$ 12,100.00
BOW	RW 9R-27L	6215	74	JOINT SPALL	Low	8	Slabs	4.2%	FDOT - CRACK SEALING - PCC	13.12	Ft	\$ 4.25	\$ 60.00
BOW	RW 9R-27L	6215	74	JOINT SPALL	Medium	2.67	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	17.22	SqFt	\$ 72.00	\$ 1,240.00
BOW	RW 9R-27L	6215	75	CORNER SPALL	Low	10.67	Slabs	5.6%	FDOT - CRACK SEALING - PCC	17.39	Ft	\$ 4.25	\$ 80.00
BOW	RW 9R-27L	6215	75	CORNER SPALL	Medium	2.67	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	7.53	SqFt	\$ 72.00	\$ 520.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BOW	RW 9R-27L	6220	65	JT SEAL DMG	High	96	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1774.93	Ft	\$ 2.75	\$ 4,890.00
BOW	RW 9R-27L	6220	74	JOINT SPALL	Low	4	Slabs	4.2%	FDOT - CRACK SEALING - PCC	6.56	Ft	\$ 4.25	\$ 30.00
BOW	RW 9R-27L	6220	74	JOINT SPALL	Medium	2	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	12.92	SqFt	\$ 72.00	\$ 930.00
BOW	RW 9R-27L	6220	75	CORNER SPALL	Low	4	Slabs	4.2%	FDOT - CRACK SEALING - PCC	6.56	Ft	\$ 4.25	\$ 30.00
BOW	RW 9R-27L	6220	75	CORNER SPALL	Medium	2	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	5.38	SqFt	\$ 72.00	\$ 390.00
BOW	RW 9R-27L	6225	52	RAVELING	Low	39820.55	SqFt	89.5%	FDOT - SURFACE SEAL	39821.09	SqFt	\$ 0.55	\$ 21,910.00
BOW	RW 9R-27L	6225	52	RAVELING	Medium	223.67	SqFt	0.5%	FDOT - PATCHING - AC PARTIAL DEPTH	223.89	SqFt	\$ 3.00	\$ 680.00
BOW	RW 9R-27L	6230	52	RAVELING	Low	22309.5	SqFt	99.6%	FDOT - SURFACE SEAL	22309.28	SqFt	\$ 0.55	\$ 12,280.00
BOW	RW 9R-27L	6230	52	RAVELING	Medium	80.51	SqFt	0.4%	FDOT - PATCHING - AC PARTIAL DEPTH	80.73	SqFt	\$ 3.00	\$ 250.00
BOW	T-HANG	4205	43	BLOCK CR	Medium	6631.32	SqFt	5.5%	FDOT - CRACK SEALING - AC	2021.33	Ft	\$ 3.00	\$ 6,070.00
BOW	T-HANG	4205	50	PATCHING	Medium	9564.49	SqFt	7.9%	FDOT - PATCHING - AC FULL DEPTH	9962	SqFt	\$ 6.00	\$ 59,780.00
BOW	T-HANG	4205	52	RAVELING	Low	109485.65	SqFt	90.5%	FDOT - SURFACE SEAL	109485.1	SqFt	\$ 0.55	\$ 60,220.00
BOW	T-HANG	4205	52	RAVELING	Medium	1929.86	SqFt	1.6%	FDOT - PATCHING - AC PARTIAL DEPTH	1929.97	SqFt	\$ 3.00	\$ 5,790.00
BOW	T-HANG	4305	52	RAVELING	Low	28703.04	SqFt	99.8%	FDOT - SURFACE SEAL	28703.04	SqFt	\$ 0.55	\$ 15,790.00
BOW	T-HANG	4305	52	RAVELING	Medium	48.98	SqFt	0.2%	FDOT - PATCHING - AC PARTIAL DEPTH	48.44	SqFt	\$ 3.00	\$ 150.00
BOW	TW A2	112	52	RAVELING	Low	43953.03	SqFt	100.0%	FDOT - SURFACE SEAL	43953.35	SqFt	\$ 0.55	\$ 24,180.00
BOW	TW A2	114	45	DEPRESSION	Low	50.91	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	83.96	SqFt	\$ 6.00	\$ 510.00
BOW	TW A3	115	43	BLOCK CR	Medium	4389.85	SqFt	10.0%	FDOT - CRACK SEALING - AC	1337.93	Ft	\$ 3.00	\$ 4,020.00
BOW	TW A3	115	48	L & T CR	Medium	2547.01	Ft	5.8%	FDOT - CRACK SEALING - AC	2546.92	Ft	\$ 3.00	\$ 7,650.00
BOW	TW A3	115	50	PATCHING	Medium	275.02	SqFt	0.6%	FDOT - PATCHING - AC FULL DEPTH	345.52	SqFt	\$ 6.00	\$ 2,080.00
BOW	TW A3	115	52	RAVELING	Low	43733.98	SqFt	99.4%	FDOT - SURFACE SEAL	43733.77	SqFt	\$ 0.55	\$ 24,060.00
BOW	TW C1	305	52	RAVELING	Low	360.7	SqFt	2.0%	FDOT - SURFACE SEAL	360.59	SqFt	\$ 0.55	\$ 200.00
BOW	TW C2	310	48	L & T CR	Medium	664.86	Ft	2.2%	FDOT - CRACK SEALING - AC	665.03	Ft	\$ 3.00	\$ 2,000.00
BOW	TW C2	310	52	RAVELING	Low	26244.89	SqFt	85.7%	FDOT - SURFACE SEAL	26244.57	SqFt	\$ 0.55	\$ 14,440.00
BOW	TW C2	310	52	RAVELING	Medium	4374.13	SqFt	14.3%	FDOT - PATCHING - AC PARTIAL DEPTH	4374.45	SqFt	\$ 3.00	\$ 13,130.00
BOW	TW C3	315	48	L & T CR	Medium	930.58	Ft	2.2%	FDOT - CRACK SEALING - AC	930.45	Ft	\$ 3.00	\$ 2,800.00
BOW	TW C3	315	52	RAVELING	Low	41491	SqFt	100.0%	FDOT - SURFACE SEAL	41490.57	SqFt	\$ 0.55	\$ 22,830.00
BOW	TW C3	320	45	DEPRESSION	Low	75.02	SqFt	1.5%	FDOT - PATCHING - AC FULL DEPTH	114.1	SqFt	\$ 6.00	\$ 690.00
BOW	TW C3	320	48	L & T CR	Medium	152	Ft	3.1%	FDOT - CRACK SEALING - AC	151.9	Ft	\$ 3.00	\$ 460.00
BOW	TW C3	320	52	RAVELING	Low	4912	SqFt	100.0%	FDOT - SURFACE SEAL	4911.57	SqFt	\$ 0.55	\$ 2,710.00
BOW	TW C3	320	56	SWELLING	Medium	51.99	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	85.03	SqFt	\$ 6.00	\$ 520.00
BOW	TW D	405	52	RAVELING	Low	3833.89	SqFt	4.0%	FDOT - SURFACE SEAL	3834.1	SqFt	\$ 0.55	\$ 2,110.00
BOW	TW D	407	52	RAVELING	Low	750.03	SqFt	5.0%	FDOT - SURFACE SEAL	750.24	SqFt	\$ 0.55	\$ 420.00
BOW	TW D	420	52	RAVELING	Low	81950.17	SqFt	100.0%	FDOT - SURFACE SEAL	81949.96	SqFt	\$ 0.55	\$ 45,080.00
BOW	TW D	420	52	RAVELING	Medium	32.83	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	32.29	SqFt	\$ 3.00	\$ 100.00
BOW	TW D	425	52	RAVELING	Low	32996.01	SqFt	100.0%	FDOT - SURFACE SEAL	32995.69	SqFt	\$ 0.55	\$ 18,150.00
BOW	TW F	605	45	DEPRESSION	Low	109.15	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	155	SqFt	\$ 6.00	\$ 940.00
BOW	TW F	605	52	RAVELING	Low	204.84	SqFt	2.0%	FDOT - SURFACE SEAL	204.51	SqFt	\$ 0.55	\$ 120.00
BOW	TW F	610	43	BLOCK CR	Medium	13716.24	SqFt	44.6%	FDOT - CRACK SEALING - AC	4180.77	Ft	\$ 3.00	\$ 12,550.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
BOW	TW F	610	52	RAVELING	Low	30778	SqFt	100.0%	FDOT - SURFACE SEAL	30778.33	SqFt	\$ 0.55	\$ 16,930.00
BOW	TW F	615	45	DEPRESSION	Low	64.05	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	100.1	SqFt	\$ 6.00	\$ 610.00
BOW	TW F	615	52	RAVELING	Low	3000.01	SqFt	50.9%	FDOT - SURFACE SEAL	2999.9	SqFt	\$ 0.55	\$ 1,660.00
BOW	TW G	705	43	BLOCK CR	Medium	10818.7	SqFt	33.2%	FDOT - CRACK SEALING - AC	3297.57	Ft	\$ 3.00	\$ 9,900.00
BOW	TW G	705	48	L & T CR	Medium	432.74	Ft	1.3%	FDOT - CRACK SEALING - AC	432.74	Ft	\$ 3.00	\$ 1,300.00
BOW	TW G	705	52	RAVELING	Low	32611.96	SqFt	100.0%	FDOT - SURFACE SEAL	32612.5	SqFt	\$ 0.55	\$ 17,940.00
BOW	TW G	710	45	DEPRESSION	Low	964.55	SqFt	2.8%	FDOT - PATCHING - AC FULL DEPTH	1093.61	SqFt	\$ 6.00	\$ 6,570.00
BOW	TW G	710	52	RAVELING	Medium	34355.17	SqFt	99.7%	FDOT - PATCHING - AC PARTIAL DEPTH	34355.17	SqFt	\$ 3.00	\$ 103,070.00
BOW	TW G	710	52	RAVELING	High	91.82	SqFt	0.3%	FDOT - PATCHING - AC PARTIAL DEPTH	91.49	SqFt	\$ 3.00	\$ 280.00
BOW	TW H	802	52	RAVELING	Low	179	SqFt	5.0%	FDOT - SURFACE SEAL	178.68	SqFt	\$ 0.55	\$ 100.00



Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BOW	AP FBO	4405	AC	83,163	64	AC Restoration	\$ 583,000.00
2018	BOW	AP H TW A	5105	AC	29,073	24	AC Reconstruction	\$ 262,000.00
2018	BOW	AP N	4105	AAC	24,590	53	AC Restoration	\$ 173,000.00
2018	BOW	AP N	4110	PCC	254,768	22	PCC Reconstruction	\$ 3,822,000.00
2018	BOW	AP N	4115	AAC	30,089	56	AC Restoration	\$ 211,000.00
2018	BOW	AP N	4120	AAC	4,597	60	AC Restoration	\$ 33,000.00
2018	BOW	AP N	4125	AAC	23,419	61	AC Restoration	\$ 164,000.00
2018	BOW	AP N	4127	AC	6,397	57	AC Restoration	\$ 45,000.00
2018	BOW	AP N	4130	PCC	146,118	62	PCC Restoration	\$ 1,462,000.00
2018	BOW	AP N	4132	PCC	17,250	14	PCC Reconstruction	\$ 259,000.00
2018	BOW	AP T-HANG	4210	PCC	30,250	67	PCC Restoration	\$ 303,000.00
2018	BOW	RW 5-23	6305	AAC	30,000	50	AC Restoration	\$ 211,000.00
2018	BOW	RW 5-23	6310	AAC	55,000	46	AC Restoration	\$ 424,000.00
2018	BOW	RW 5-23	6315	AAC	353,620	50	AC Restoration	\$ 2,476,000.00
2018	BOW	RW 9R-27L	6205	AC	350,236	20	AC Reconstruction	\$ 3,153,000.00
2018	BOW	RW 9R-27L	6210	AC	175,118	24	AC Reconstruction	\$ 1,577,000.00
2018	BOW	RW 9R-27L	6230	AAC	22,390	64	AC Restoration	\$ 157,000.00
2018	BOW	T-HANG	4205	AC	120,980	45	AC Restoration	\$ 952,000.00
2018	BOW	T-HANG	4305	AC	28,752	63	AC Restoration	\$ 202,000.00
2018	BOW	TW A3	115	AAC	44,009	39	AC Restoration	\$ 397,000.00
2018	BOW	TW C2	310	AAC	30,619	54	AC Restoration	\$ 215,000.00
2018	BOW	TW C3	315	AAC	41,491	56	AC Restoration	\$ 291,000.00
2018	BOW	TW C3	320	AAC	4,912	34	AC Reconstruction	\$ 45,000.00
2018	BOW	TW F	610	AAC	30,778	40	AC Restoration	\$ 274,000.00
2018	BOW	TW F	615	AAC	5,898	63	AC Restoration	\$ 42,000.00
2018	BOW	TW G	705	AAC	32,612	36	AC Reconstruction	\$ 294,000.00




Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	BOW	TW G	710	AAC	34,447	19	AC Reconstruction	\$ 311,000.00
2020	BOW	RW 9R-27L	6225	AAC	44,518	64	AC Restoration	\$ 312,000.00
2020	BOW	TW D	420	AC	81,983	64	AC Restoration	\$ 574,000.00
2022	BOW	RW 9L-27R	6118	AAC	9,250	64	AC Restoration	\$ 65,000.00
2022	BOW	TW A2	112	AC	43,953	64	AC Restoration	\$ 308,000.00
2022	BOW	TW D	425	AC	32,996	64	AC Restoration	\$ 231,000.00
2024	BOW	RW 5-23	6320	AAC	40,640	64	AC Restoration	\$ 285,000.00
2024	BOW	RW 9L-27R	6124	AAC	30,000	64	AC Restoration	\$ 211,000.00
2025	BOW	RW 9L-27R	6115	AAC	440,000	64	AC Restoration	\$ 3,081,000.00
2026	BOW	RW 9L-27R	6105	AAC	30,000	64	AC Restoration	\$ 211,000.00
2026	BOW	RW 9L-27R	6125	APC	30,000	63	AC Restoration	\$ 211,000.00
2027	BOW	RW 9L-27R	6130	AAC	20,000	64	AC Restoration	\$ 141,000.00


Appendix C

Technical Exhibits









FY 2018
TW F: 615
AC RESTORATION
\$0.04 M


FY 2018
AP N: 4120
AC RESTORATION
\$0.03 M

FY 2018
AP N: 4125
AC RESTORATION
\$0.16 M

FY 2018
AP N: 4127
AC RESTORATION
\$0.05 M

FY 2018
RW 9R-27L: 6230
AC RESTORATION
\$0.16 M

FY 2027
RW 9L-27R: 6130
AC RESTORATION
\$0.14 M



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.



004 - AIRFIELD PAVEMENT
MAJOR REHABILITATION EXHIBIT



Appendix D

Inspection Photograph Documentation



Runway 5-23, Section 6305, Sample Unit 100 – Low Severity (45) Depression, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling



Runway 5-23, Section 6305, Sample Unit 153 – Low Severity (43) Block Cracking, Low Severity (52) Raveling



Runway 5-23, Section 6315, Sample Unit 125 – Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (56) Swelling, Low Severity (52) Raveling, Medium Severity (52) Raveling



Runway 9L-27R, Section 6110, Sample Unit 504 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway RW 9L-27R, Section 6115, Sample Unit 378 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway RW 9R-27L, Section 6205, Sample Unit 375 – Low Severity (41) Alligator Cracking, Medium Severity (52) Raveling



Runway RW 9R-27L, Section 6205, Sample Unit 361 – Medium Severity (43) Block Cracking, Medium Severity (52) Raveling



Runway RW 9R-27L, Section 6205, Sample Unit 300 – Medium Severity (43) Block Cracking, Medium Severity (52) Raveling



Taxiway A1, Section 105, Sample Unit 102 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering




Taxiway A2, Section 114, Sample Unit 116 – Low Severity (45) Depression, Low Severity (57) Weathering



Taxiway A3, Section 115, Sample Unit 105 – Medium Severity (48) Longitudinal and Transverse Cracking, Medium Severity (50) Patching, Low Severity (52) Raveling



Taxiway C1, Section 305, Sample Unit 102 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Taxiway C2, Section 310, Sample Unit 106 – Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling



Taxiway C3, Section 315, Sample Unit 105 – Low Severity (43) Block Cracking, Low Severity (52) Raveling



Taxiway C3, Section 320, Sample Unit 112 – Low Severity (45) Depression, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling



Taxiway D, Section 405, Sample Unit 108 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (56) Swelling, Low Severity (57) Weathering



Taxiway D, Section 420, Sample Unit 204 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling



Taxiway F, Section 605, Sample Unit 101 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (45) Depression, Medium Severity (52) Raveling, Low Severity (57) Weathering



Taxiway F, Section 610, Sample Unit 103 – Low Severity (52) Raveling, Low Severity (56) Swelling



Taxiway G, Section 710, Sample Unit 106 – Low Severity (45) Depression, Low Severity (48) Longitudinal and Transverse Cracking, Medium Severity (52) Raveling, High Severity (52) Raveling



Taxiway H, Section 802, Sample Unit 100 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



T-Hangar Taxilane, Section 4205, Sample Unit 102 – Medium Severity (43) Block Cracking, Low Severity (52) Raveling, Low Severity (52) Raveling



T-Hangar Taxilane, Section 4205, Sample Unit 207 – Low Severity (48) Longitudinal and Transverse Cracking, Medium Severity (52) Raveling



T-Hangar Taxilane, Section 4205, Sample Unit 207 – Medium Severity (50) Patching, Low Severity (52) Raveling



Apron FBO, Section 4405, Sample Unit 202 – Low Severity (43) Block Cracking, Low Severity (52) Raveling



Apron FBO, Section 4405, Sample Unit 105 – (42) Bleeding, Low Severity (43) Block Cracking



Hold Apron on Taxiway A, Section 5105, Sample Unit 102 – Medium Severity (43) Block Cracking, Medium Severity (52) Raveling



North Apron, Section 4110, Sample Unit 807 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (74) Joint Spalling, (73) Shrinkage Cracks



North Apron, Section 4110, Sample Unit 405 – Low Severity (63) Longitudinal, Transverse, and Diagonal Cracking, Low Severity (65) Joint Seal Damage, Low Severity (72) Shattered Slab



North Apron, Section 4130, Sample Unit 202 – High Severity (65) Joint Seal Damage, Medium Severity (71) Faulting



T-Hangar Apron, Section 4210, Sample Unit 306 – Low Severity (62) Corner Break, Medium Severity (74) Joint Spalling, High Severity (65) Joint Seal Damage

Appendix E

Inspection Distress Details

Re-Inspection Report

FDOT

Generated Date 7/10/2017

Page 1 of 61

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT		
Branch:	AP FBO	Name:	APRON FBO	Use:	APRON	Area: 83,163 SqFt
Section:	4405	of 1	From:	-	To:	-
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:	Category:	Rank: P
Area:	83,163 SqFt	Length:	183 Ft	Width:	410 Ft	
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length: Ft
Shoulder:		Street Type:		Grade:	0	Lanes: 0
Section Comments:						

Work Date:	1/1/2007	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
-------------------	----------	-------------------	-----------------------	--------------	-------	--------------------------	------

Last Insp. Date:	3/6/2017	TotalSamples:	18	Surveyed:	3
-------------------------	----------	----------------------	----	------------------	---

Conditions: PCI: 66

Inspection Comments:

Sample Number:	100	Type:	R	Area:	5000.00 SqFt	PCI:	66
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

56	SWELLING	L	50.00	SqFt
43	BLOCK CR	L	750.00	SqFt
52	RAVELING	L	5000.00	SqFt

Sample Number:	105	Type:	R	Area:	5000.00 SqFt	PCI:	69
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

43	BLOCK CR	L	500.00	SqFt
52	RAVELING	L	5000.00	SqFt
42	BLEEDING	N	2.00	SqFt

Sample Number:	202	Type:	R	Area:	5000.00 SqFt	PCI:	63
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

48	L & T CR	L	12.00	Ft
42	BLEEDING	N	21.00	SqFt
43	BLOCK CR	L	500.00	SqFt
52	RAVELING	L	5000.00	SqFt

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	AP H TW A		Name:	HOLD APRON ON TW A		Use:	APRON	Area:	29,073 SqFt			
Section:	5105		of	1	From:	-		To:	-		Last Const.:	1/1/1942
Surface:	AC		Family:	C9N59-GA-AP-AC		Zone:			Category:	Rank: P		
Area:	29,073 SqFt		Length:	500 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	5		Surveyed:	1					
Conditions:	PCI: 26											
Inspection Comments:												
Sample Number:	102		Type:	R		Area:	5500.00 SqFt		PCI:	26		
Sample Comments:												
48	L & T CR		M	100.00		Ft						
48	L & T CR		L	300.00		Ft						
43	BLOCK CR		M	2900.00		SqFt						
52	RAVELING		M	5500.00		SqFt						

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	AP N		Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt		
Section:	4105 of 10		From:	-		To:	-		Last Const.:	1/1/1990	
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC		Zone:			Category:	Rank:	P	
Area:	24,590 SqFt		Length:	450 Ft		Width:	130 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1990		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2014		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	3/6/2017		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI: 54										
Inspection Comments:											
Sample Number:	200	Type:	R	Area:	4190.00 SqFt		PCI:	54			
Sample Comments:											
43	BLOCK CR		L	3650.00	SqFt						
56	SWELLING		L	38.00	SqFt						
48	L & T CR		L	20.00	Ft						
57	WEATHERING		L	4190.00	SqFt						

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	AP N		Name:	NORTH APRON		Use:	APRON		Area:	581,128 SqFt		
Section:	4107		of	10	From:	-		To:	-		Last Const.:	2/1/2012
Surface:	AAC		Family:	C9N59-GA-AP-AAC-APC		Zone:			Category:	Rank: P		
Area:	39,764 SqFt		Length:	300 Ft		Width:	130 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	1/1/1990		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	2/1/2012		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True		
Last Insp. Date:	3/6/2017		TotalSamples:	9		Surveyed:	1					
Conditions:	PCI: 86											
Inspection Comments:												
Sample Number:	102		Type:	R		Area:	2614.00 SqFt		PCI:	86		
Sample Comments:												
48	L & T CR		L	64.00 Ft								
57	WEATHERING		L	2614.00 SqFt								

Network:	BOW		Name:		BARTOW MUNICIPAL AIRPORT					
Branch:	AP N		Name:		NORTH APRON		Use:	APRON	Area:	581,128 SqFt
Section:	4110		of 10		From: -		To: -		Last Const.: 1/1/1942	
Surface:	PCC		Family:		C9N59-GA-AP-PCC		Zone:		Category: Rank: P	
Area:	254,768 SqFt		Length:		1,050 Ft		Width:		300 Ft	
Slabs:	815		Slab Length:		12 Ft		Slab Width:		25 Ft Joint Length: 36,450 Ft	
Shoulder:			Street Type:		Grade: 0				Lanes: 0	
Section Comments:										
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1985		Work Type: REPAIR				Code:	IMPORTED		Is Major M&R: False
Work Date:	1/1/2014		Work Type: FDOT - SLAB REPLACEMENT - PCC				Code:	FDOT-SL-PC		Is Major M&R: False
Work Date:	1/1/2014		Work Type: FDOT - PATCHING - PCC PARTIAL DEPTH				Code:	FDOT-PA-PP		Is Major M&R: False
Last Insp. Date:	3/6/2017		TotalSamples:		48		Surveyed:		6	
Conditions:	PCI: 23									
Inspection Comments:										
Sample Number:	203		Type:	R		Area:		20.00 Slabs		PCI: 21
Sample Comments:										
73	SHRINKAGE CR		N		20.00 Slabs					
65	JT SEAL DMG		L		20.00 Slabs					
66	SMALL PATCH		L		16.00 Slabs					
74	JOINT SPALL		M		2.00 Slabs					
63	LINEAR CR		L		4.00 Slabs					
63	LINEAR CR		M		10.00 Slabs					
67	LARGE PATCH		L		1.00 Slabs					
66	SMALL PATCH		M		1.00 Slabs					
75	CORNER SPALL		L		2.00 Slabs					
71	FAULTING		L		1.00 Slabs					
72	SHAT. SLAB		L		4.00 Slabs					
75	CORNER SPALL		M		1.00 Slabs					
Sample Number:	401		Type:	R		Area:		17.00 Slabs		PCI: 15
Sample Comments:										
73	SHRINKAGE CR		N		15.00 Slabs					
65	JT SEAL DMG		L		17.00 Slabs					
72	SHAT. SLAB		L		4.00 Slabs					
66	SMALL PATCH		L		8.00 Slabs					
72	SHAT. SLAB		M		2.00 Slabs					
75	CORNER SPALL		M		1.00 Slabs					
63	LINEAR CR		L		5.00 Slabs					
71	FAULTING		L		3.00 Slabs					
66	SMALL PATCH		M		2.00 Slabs					
63	LINEAR CR		M		4.00 Slabs					
Sample Number:	405		Type:	R		Area:		16.00 Slabs		PCI: 16
Sample Comments:										
73	SHRINKAGE CR		N		15.00 Slabs					
65	JT SEAL DMG		L		16.00 Slabs					
66	SMALL PATCH		L		9.00 Slabs					
63	LINEAR CR		M		11.00 Slabs					
66	SMALL PATCH		M		2.00 Slabs					
72	SHAT. SLAB		L		3.00 Slabs					
63	LINEAR CR		L		1.00 Slabs					
72	SHAT. SLAB		M		1.00 Slabs					
Sample Number:	702		Type:	R		Area:		24.00 Slabs		PCI: 10
Sample Comments:										
73	SHRINKAGE CR		N		20.00 Slabs					

E-5

65	JT SEAL DMG	L	24.00	Slabs
63	LINEAR CR	M	4.00	Slabs
63	LINEAR CR	L	5.00	Slabs
66	SMALL PATCH	L	10.00	Slabs
71	FAULTING	L	10.00	Slabs
72	SHAT. SLAB	L	11.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
74	JOINT SPALL	M	2.00	Slabs
66	SMALL PATCH	M	2.00	Slabs
72	SHAT. SLAB	M	4.00	Slabs

Sample Number: 704 **Type:** R **Area:** 20.00 Slabs **PCI:** 46

Sample Comments:

71	FAULTING	L	1.00	Slabs
73	SHRINKAGE CR	N	12.00	Slabs
65	JT SEAL DMG	L	20.00	Slabs
63	LINEAR CR	L	10.00	Slabs
63	LINEAR CR	M	2.00	Slabs
66	SMALL PATCH	L	5.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
74	JOINT SPALL	M	1.00	Slabs
75	CORNER SPALL	L	2.00	Slabs

Sample Number: 807 **Type:** R **Area:** 16.00 Slabs **PCI:** 29

Sample Comments:

63	LINEAR CR	M	6.00	Slabs
65	JT SEAL DMG	L	16.00	Slabs
73	SHRINKAGE CR	N	16.00	Slabs
63	LINEAR CR	L	10.00	Slabs
66	SMALL PATCH	L	8.00	Slabs
74	JOINT SPALL	M	3.00	Slabs
75	CORNER SPALL	L	1.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
71	FAULTING	L	1.00	Slabs

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt			
Section:	4112	of	10	From:	-	To:	-	Last Const.:	1/1/2014		
Surface:	PCC	Family:	C9N59-GA-AP-PCC		Zone:		Category:		Rank:	P	
Area:	34,136 SqFt		Length:	180 Ft		Width:	187 Ft				
Slabs:	218	Slab Length:	12 Ft		Slab Width:	12 Ft		Joint Length:	5,032 Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type:	OVERLAY			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1985		Work Type:	REPAIR			Code:	IMPORTED		Is Major M&R:	False
Work Date:	1/1/2014		Work Type:	Complete Reconstruction - PCC			Code:	CR-PC		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	12		Surveyed:	2				
Conditions:	PCI:	96									
Inspection Comments:											
Sample Number:	103	Type:	R	Area:	15.00 Slabs		PCI:	92			
Sample Comments:											
63	LINEAR CR		L	1.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
Sample Number:	106	Type:	R	Area:	20.00 Slabs		PCI:	100			
Sample Comments:											
<No Distress>											

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt		
Section:	4115	of 10	From:	-		To:	-		Last Const.:	1/1/1990
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC	Zone:				Category:	Rank:	P
Area:	30,089 SqFt		Length:	550 Ft		Width:	50 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1942		Work Type: BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1990		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1990		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2014		Work Type: Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	3/6/2017		TotalSamples:	8		Surveyed:	1			
Conditions:	PCI: 58									
Inspection Comments:										
Sample Number:	103	Type:	R	Area:	3100.00 SqFt		PCI:	58		
Sample Comments:										
48	L & T CR		L	399.00 Ft						
50	PATCHING		M	12.00 SqFt						
43	BLOCK CR		L	500.00 SqFt						
57	WEATHERING		L	3088.00 SqFt						

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT								
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt				
Section:	4120	of 10	From:	-		To:	-		Last Const.:	1/1/1987		
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC		Zone:	Category:		Rank:		P		
Area:	4,597 SqFt		Length:	125 Ft		Width:	40 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:		0			
Section Comments:												
Work Date:	1/1/1942		Work Type:				BUILT		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1987		Work Type:				OVERLAY		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1987		Work Type:				OVERLAY		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2014		Work Type:				Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	3/6/2017		TotalSamples:	1		Surveyed:					1	
Conditions:	PCI:		63									
Inspection Comments:												
Sample Number:	106	Type:	R	Area:	4597.00 SqFt		PCI:		63			
Sample Comments:												
48	L & T CR		L	382.00 Ft								
43	BLOCK CR		L	315.00 SqFt								
54	SHOVING		M	12.00 SqFt								
56	SWELLING		L	13.00 SqFt								
57	WEATHERING		L	4597.00 SqFt								

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	AP N		Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt		
Section:	4125		of 10	From:	-		To:	-		Last Const.:	1/1/1990
Surface:	AAC		Family:	C9N59-GA-AP-AAC-APC		Zone:			Category:	Rank: P	
Area:	23,419 SqFt		Length:	350 Ft		Width:	100 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1990		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R: True	
Work Date:	1/1/2014		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False	
Last Insp. Date:	3/6/2017		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI: 64										
Inspection Comments:											
Sample Number:	108		Type:	R		Area:	4700.00 SqFt		PCI:	64	
Sample Comments:											
48	L & T CR		L	394.00 Ft							
43	BLOCK CR		L	707.00 SqFt							
45	DEPRESSION		L	72.00 SqFt							
57	WEATHERING		L	4700.00 SqFt							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT					
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt		
Section:	4127	of	10	From:	-	To:	-	Last Const.:	1/1/1998	
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:	Rank: P		
Area:	6,397 SqFt	Length:	120 Ft		Width:	50 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1998	Work Type:	OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1998	Work Type:	BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2014	Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	3/6/2017	TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	59								
Inspection Comments:										
Sample Number:	208	Type:	R	Area:	3329.00 SqFt		PCI:	59		
Sample Comments:										
43	BLOCK CR	L	3329.00 SqFt							
57	WEATHERING	L	3329.00 SqFt							

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	AP N		Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt		
Section:	4130	of	10	From:	-	To:	-	Last Const.:	1/1/1942		
Surface:	PCC	Family:	C9N59-GA-AP-PCC		Zone:		Category:		Rank:	P	
Area:	146,118 SqFt		Length:	480 Ft		Width:	300 Ft				
Slabs:	779	Slab Length:	12 Ft		Slab Width:	15 Ft		Joint Length:	20,340 Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	35		Surveyed:	4				
Conditions:	PCI:	64									
Inspection Comments:											
Sample Number:	104	Type:	R	Area:	24.00 Slabs		PCI:	80			
Sample Comments:											
65	JT SEAL DMG	H	24.00	Slabs							
73	SHRINKAGE CR	N	10.00	Slabs							
66	SMALL PATCH	L	4.00	Slabs							
Sample Number:	202	Type:	R	Area:	24.00 Slabs		PCI:	49			
Sample Comments:											
65	JT SEAL DMG	H	24.00	Slabs							
73	SHRINKAGE CR	N	13.00	Slabs							
66	SMALL PATCH	L	8.00	Slabs							
66	SMALL PATCH	M	2.00	Slabs							
63	LINEAR CR	L	2.00	Slabs							
71	FAULTING	L	1.00	Slabs							
71	FAULTING	M	1.00	Slabs							
74	JOINT SPALL	L	1.00	Slabs							
74	JOINT SPALL	M	3.00	Slabs							
62	CORNER BREAK	L	2.00	Slabs							
Sample Number:	401	Type:	R	Area:	24.00 Slabs		PCI:	81			
Sample Comments:											
65	JT SEAL DMG	H	24.00	Slabs							
73	SHRINKAGE CR	N	10.00	Slabs							
75	CORNER SPALL	L	1.00	Slabs							
Sample Number:	504	Type:	R	Area:	17.00 Slabs		PCI:	40			
Sample Comments:											
65	JT SEAL DMG	H	17.00	Slabs							
73	SHRINKAGE CR	N	6.00	Slabs							
67	LARGE PATCH	M	5.00	Slabs							
67	LARGE PATCH	L	2.00	Slabs							
66	SMALL PATCH	L	4.00	Slabs							
74	JOINT SPALL	M	1.00	Slabs							
71	FAULTING	L	1.00	Slabs							
74	JOINT SPALL	L	1.00	Slabs							
63	LINEAR CR	L	1.00	Slabs							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT					
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	581,128 SqFt		
Section:	4132	of	10	From:	-	To:	-	Last Const.:	1/1/1942	
Surface:	PCC	Family:	C9N59-GA-AP-PCC		Zone:		Category:		Rank:	P
Area:	17,250 SqFt	Length:	280 Ft		Width:	40 Ft				
Slabs:	55	Slab Length:	12 Ft		Slab Width:	25 Ft		Joint Length:	1,024 Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1942		Work Type:			BUILT		Code:	IMPORTED	
								Is Major M&R:	True	
Last Insp. Date:	3/6/2017		TotalSamples:		4		Surveyed:		1	
Conditions:	PCI:	15								
Inspection Comments:										
Sample Number:	602	Type:	R	Area:	15.00 Slabs		PCI:	15		
Sample Comments:										
73	SHRINKAGE CR		N	14.00	Slabs					
65	JT SEAL DMG		L	15.00	Slabs					
72	SHAT. SLAB		M	1.00	Slabs					
63	LINEAR CR		L	3.00	Slabs					
74	JOINT SPALL		L	1.00	Slabs					
66	SMALL PATCH		L	6.00	Slabs					
72	SHAT. SLAB		L	7.00	Slabs					
74	JOINT SPALL		M	2.00	Slabs					
63	LINEAR CR		M	4.00	Slabs					

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	APT-HANG		Name:	T-HANGAR APRON		Use:	APRON	Area:	30,250 SqFt	
Section:	4210 of 1		From:	-		To:	-		Last Const.:	1/1/2004
Surface:	PCC		Family:	C9N59-GA-AP-PCC		Zone:			Rank:	T
Area:	30,250 SqFt		Length:	125 Ft		Width:	25 Ft			
Slabs:	194		Slab Length:	12 Ft		Slab Width:	13 Ft		Joint Length:	350 Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	1/1/2004		Work Type:	New Construction - Initial				Code:	NU-IN	
Last Insp. Date:	3/6/2017		TotalSamples:	10		Surveyed:	2			
Conditions:	PCI: 69									
Inspection Comments:										
Sample Number:	302		Type:	R		Area:	20.00 Slabs		PCI:	78
Sample Comments:										
65	JT SEAL DMG		H	20.00		Slabs				
73	SHRINKAGE CR		N	9.00		Slabs				
62	CORNER BREAK		M	1.00		Slabs				
Sample Number:	306		Type:	R		Area:	28.00 Slabs		PCI:	62
Sample Comments:										
65	JT SEAL DMG		H	28.00		Slabs				
73	SHRINKAGE CR		N	13.00		Slabs				
71	FAULTING		L	1.00		Slabs				
63	LINEAR CR		L	1.00		Slabs				
62	CORNER BREAK		L	2.00		Slabs				
74	JOINT SPALL		M	1.00		Slabs				
72	SHAT. SLAB		L	2.00		Slabs				

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT				
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	479,260 SqFt
Section:	6305	of	4	From:	-	To:	-	Last Const.:	1/1/2001
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:	Category:	Rank:	P	
Area:	30,000 SqFt		Length:	300 Ft		Width:	100 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:	0		Lanes:	0		
Section Comments:									
Work Date:	1/1/1942		Work Type: BUILT			Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1990		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1990		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1991		Work Type: REPAIR			Code:	IMPORTED		Is Major M&R: False
Work Date:	1/1/2001		Work Type: MILL and OVERLAY			Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	3/6/2017		TotalSamples:	6		Surveyed:	2		
Conditions:	PCI: 53								
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	5000.00 SqFt		PCI:	49	
Sample Comments:									
56	SWELLING	L	152.00 SqFt						
48	L & T CR	L	284.00 Ft						
56	SWELLING	M	10.00 SqFt						
52	RAVELING	M	331.00 SqFt						
52	RAVELING	L	4643.00 SqFt						
45	DEPRESSION	L	24.00 SqFt						
50	PATCHING	L	26.00 SqFt						
Sample Number:	104	Type:	R	Area:	5000.00 SqFt		PCI:	57	
Sample Comments:									
48	L & T CR	L	264.00 Ft						
56	SWELLING	L	10.00 SqFt						
56	SWELLING	M	200.00 SqFt						
52	RAVELING	L	4900.00 SqFt						
52	RAVELING	M	100.00 SqFt						

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT										
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	479,260 SqFt					
Section:	6310		of	4		From:	-		To:	-		Last Const.:	1/1/2001	
Surface:	AAC		Family:	C9N59-GA-RW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	55,000 SqFt		Length:	550 Ft		Width:	100 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1942		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1971		Work Type: OVERLAY					Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1990		Work Type: OVERLAY					Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1991		Work Type: REPAIR					Code:	IMPORTED		Is Major M&R:	False		
Work Date:	1/1/2001		Work Type: MILL and OVERLAY					Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	3/6/2017		TotalSamples:	11		Surveyed:	3							
Conditions:	PCI: 49													
Inspection Comments:														
Sample Number:	109		Type:	R		Area:	5000.00 SqFt		PCI:	45				
Sample Comments:														
48	L & T CR		M	100.00 Ft										
48	L & T CR		L	315.00 Ft										
56	SWELLING		M	132.00 SqFt										
56	SWELLING		L	300.00 SqFt										
52	RAVELING		L	4750.00 SqFt										
52	RAVELING		M	250.00 SqFt										
Sample Number:	112		Type:	R		Area:	5000.00 SqFt		PCI:	49				
Sample Comments:														
48	L & T CR		L	254.00 Ft										
48	L & T CR		M	80.00 Ft										
56	SWELLING		M	100.00 SqFt										
56	SWELLING		L	117.00 SqFt										
52	RAVELING		L	4750.00 SqFt										
52	RAVELING		M	250.00 SqFt										
Sample Number:	115		Type:	R		Area:	5000.00 SqFt		PCI:	53				
Sample Comments:														
48	L & T CR		M	64.00 Ft										
48	L & T CR		L	188.00 Ft										
52	RAVELING		L	4250.00 SqFt										
52	RAVELING		M	750.00 SqFt										
56	SWELLING		M	80.00 SqFt										
56	SWELLING		L	10.00 SqFt										

Network:		BOW		Name:		BARTOW MUNICIPAL AIRPORT																									
Branch:		RW 5-23		Name:		RUNWAY 5-23		Use:		RUNWAY		Area:		479,260 SqFt																	
Section:		6315		of 4		From:		-		To:		-		Last Const.: 1/1/2001																	
Surface:		AAC		Family:		C9N59-GA-RW-AAC-APC		Zone:		Category:		Rank:		P																	
Area:		353,620 SqFt		Length:		3,550 Ft		Width:		100 Ft																					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																			
Shoulder:		Street Type:		Grade:		0		Lanes:		0																					
Section Comments:																															
Work Date:				1/1/1942				Work Type:				BUILT				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				1/1/1971				Work Type:				OVERLAY				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				1/1/1971				Work Type:				OVERLAY				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				1/1/1991				Work Type:				REPAIR				Code:				IMPORTED				Is Major M&R:				False			
Work Date:				1/1/2001				Work Type:				MILL and OVERLAY				Code:				ML-OV				Is Major M&R:				True			
Last Insp. Date:				3/6/2017				TotalSamples:				71				Surveyed:				15											
Conditions:				PCI: 53																											
Inspection Comments:																															
Sample Number:		117		Type:		R		Area:		5000.00 SqFt		PCI:		50																	
Sample Comments:																															
43		BLOCK CR		L		500.00		SqFt																							
48		L & T CR		M		26.00		Ft																							
48		L & T CR		L		118.00		Ft																							
52		RAVELING		L		5000.00		SqFt																							
56		SWELLING		L		60.00		SqFt																							
56		SWELLING		M		10.00		SqFt																							
Sample Number:		121		Type:		R		Area:		5000.00 SqFt		PCI:		23																	
Sample Comments:																															
48		L & T CR		L		142.00		Ft																							
52		RAVELING		H		2100.00		SqFt																							
52		RAVELING		L		2900.00		SqFt																							
56		SWELLING		L		25.00		SqFt																							
Sample Number:		125		Type:		R		Area:		5000.00 SqFt		PCI:		54																	
Sample Comments:																															
48		L & T CR		M		40.00		Ft																							
48		L & T CR		L		159.00		Ft																							
52		RAVELING		L		4900.00		SqFt																							
52		RAVELING		M		100.00		SqFt																							
56		SWELLING		L		122.00		SqFt																							
Sample Number:		133		Type:		R		Area:		5000.00 SqFt		PCI:		58																	
Sample Comments:																															
56		SWELLING		L		10.00		SqFt																							
48		L & T CR		M		5.00		Ft																							
48		L & T CR		L		177.00		Ft																							
52		RAVELING		L		4900.00		SqFt																							
52		RAVELING		M		100.00		SqFt																							
Sample Number:		137		Type:		R		Area:		5000.00 SqFt		PCI:		64																	
Sample Comments:																															
48		L & T CR		L		235.00		Ft																							
52		RAVELING		L		4900.00		SqFt																							
52		RAVELING		M		100.00		SqFt																							
Sample Number:		145		Type:		R		Area:		5000.00 SqFt		PCI:		58																	
Sample Comments:																															
48		L & T CR		M		50.00		Ft																							
E-17																															

48	L & T CR	L	112.00	Ft
43	BLOCK CR	M	672.00	SqFt
52	RAVELING	L	5000.00	SqFt
Sample Number: 153 Type: R Area: 5000.00 SqFt PCI: 52				
Sample Comments:				
43	BLOCK CR	L	360.00	SqFt
48	L & T CR	M	22.00	Ft
48	L & T CR	L	320.00	Ft
52	RAVELING	L	4800.00	SqFt
52	RAVELING	M	200.00	SqFt
56	SWELLING	L	20.00	SqFt
Sample Number: 160 Type: R Area: 5000.00 SqFt PCI: 57				
Sample Comments:				
48	L & T CR	M	30.00	Ft
48	L & T CR	L	102.00	Ft
52	RAVELING	M	100.00	SqFt
52	RAVELING	L	4900.00	SqFt
56	SWELLING	L	24.00	SqFt
Sample Number: 165 Type: R Area: 3500.00 SqFt PCI: 59				
Sample Comments:				
48	L & T CR	M	21.00	Ft
48	L & T CR	L	270.00	Ft
52	RAVELING	L	3500.00	SqFt
42	BLEEDING	N	1.00	SqFt
56	SWELLING	L	55.00	SqFt
Sample Number: 180 Type: R Area: 5000.00 SqFt PCI: 51				
Sample Comments:				
43	BLOCK CR	M	1000.00	SqFt
48	L & T CR	M	42.00	Ft
48	L & T CR	L	56.00	Ft
52	RAVELING	M	100.00	SqFt
52	RAVELING	L	4900.00	SqFt
Sample Number: 184 Type: R Area: 5000.00 SqFt PCI: 49				
Sample Comments:				
43	BLOCK CR	M	1150.00	SqFt
48	L & T CR	M	57.00	Ft
48	L & T CR	L	200.00	Ft
52	RAVELING	M	100.00	SqFt
52	RAVELING	L	4900.00	SqFt
Sample Number: 187 Type: R Area: 5000.00 SqFt PCI: 61				
Sample Comments:				
48	L & T CR	M	148.00	Ft
48	L & T CR	L	350.00	Ft
52	RAVELING	L	5000.00	SqFt
Sample Number: 191 Type: R Area: 5000.00 SqFt PCI: 59				
Sample Comments:				
48	L & T CR	M	70.00	Ft
48	L & T CR	L	225.00	Ft
52	RAVELING	L	4900.00	SqFt
52	RAVELING	M	100.00	SqFt
Sample Number: 195 Type: R Area: 5000.00 SqFt PCI: 49				
Sample Comments:				
48	L & T CR	M	50.00	Ft
48	L & T CR	L	300.00	Ft
52	RAVELING	M	13.00	SqFt
52	RAVELING	L	4987.00	SqFt
56	SWELLING	L	124.00	SqFt
56	SWELLING	M	26.00	SqFt

Sample Number: 198		Type:	R	Area:	5000.00 SqFt	PCI:	48
Sample Comments:							
45	DEPRESSION		L	50.00	SqFt		
48	L & T CR		M	20.00	Ft		
48	L & T CR		L	407.00	Ft		
52	RAVELING		M	800.00	SqFt		
52	RAVELING		L	4200.00	SqFt		
56	SWELLING		L	44.00	SqFt		

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	479,260 SqFt		
Section:	6320	of	4	From:	-	To:	-	Last Const.:	1/1/2006		
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:		Category:		Rank:	P	
Area:	40,640 SqFt		Length:	400 Ft		Width:	100 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2001		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	8		Surveyed:	2				
Conditions:	PCI: 78										
Inspection Comments:											
Sample Number:	168	Type:	R	Area:	5139.00 SqFt		PCI:	78			
Sample Comments:											
48	L & T CR	L	194.00 Ft								
56	SWELLING	L	120.00 SqFt								
57	WEATHERING	L	5139.00 SqFt								
42	BLEEDING	N	.50 SqFt								
Sample Number:	177	Type:	R	Area:	5000.00 SqFt		PCI:	79			
Sample Comments:											
48	L & T CR	L	252.00 Ft								
56	SWELLING	L	15.00 SqFt								
57	WEATHERING	L	5000.00 SqFt								

Network:		BOW		Name:		BARTOW MUNICIPAL AIRPORT													
Branch:		RW 9L-27R		Name:		RUNWAY 9L-27R		Use:		RUNWAY		Area:		750,000 SqFt					
Section:		6105		of		8		From:		-		To:		-		Last Const.:		1/1/2006	
Surface:		AAC		Family:		C9N59-GA-RW-AAC-APC		Zone:				Category:				Rank:		P	
Area:		30,000 SqFt		Length:		300 Ft		Width:		100 Ft									
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft					
Shoulder:				Street Type:				Grade:		0		Lanes:		0					
Section Comments:																			
Work Date:		1/1/1998		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		1/1/1998		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		1/1/2006		Work Type:		MILL and OVERLAY		Code:		ML-OV		Is Major M&R:		True					
Last Insp. Date:		3/6/2017		TotalSamples:		6		Surveyed:		2									
Conditions:		PCI: 83																	
Inspection Comments:																			
Sample Number:		300		Type:		R		Area:		5000.00 SqFt		PCI:		84					
Sample Comments:																			
48	L & T CR			L		40.00 Ft													
52	RAVELING			L		250.00 SqFt													
57	WEATHERING			L		4750.00 SqFt													
Sample Number:		304		Type:		R		Area:		5000.00 SqFt		PCI:		83					
Sample Comments:																			
48	L & T CR			L		64.00 Ft													
52	RAVELING			L		250.00 SqFt													
57	WEATHERING			L		4750.00 SqFt													

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT					
Branch:	RW 9L-27R		Name:	RUNWAY 9L-27R		Use:	RUNWAY	Area:	750,000 SqFt	
Section:	6110	of	8	From:	-	To:	-	Last Const.:	1/1/2006	
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:		Category:		Rank:	P
Area:	20,000 SqFt		Length:	600 Ft		Width:	25 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1998		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1998		Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	4		Surveyed:	2			
Conditions:	PCI:	87								
Inspection Comments:										
Sample Number:	104	Type:	R	Area:	5000.00 SqFt		PCI:	83		
Sample Comments:										
48	L & T CR	M	10.00 Ft							
48	L & T CR	L	40.00 Ft							
57	WEATHERING	L	5000.00 SqFt							
56	SWELLING	L	8.00 SqFt							
Sample Number:	504	Type:	R	Area:	5000.00 SqFt		PCI:	90		
Sample Comments:										
48	L & T CR	L	6.00 Ft							
57	WEATHERING	L	5000.00 SqFt							
56	SWELLING	L	6.00 SqFt							

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT					
Branch:	RW 9L-27R		Name:	RUNWAY 9L-27R		Use:	RUNWAY	Area:	750,000 SqFt
Section:	6115	of	8	From:	-	To:	-	Last Const.:	1/1/2006
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC	Zone:		Category:		Rank:	P
Area:	440,000 SqFt	Length:	4,400 Ft	Width:	100 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1942	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1985	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1985	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2006	Work Type:	MILL and OVERLAY			Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/6/2017	TotalSamples:	87	Surveyed:	18				
Conditions:	PCI:	80							
Inspection Comments:									
Sample Number:	307	Type:	R	Area:	5000.00 SqFt	PCI:	78		
Sample Comments:									
48	L & T CR	L	79.00	Ft					
52	RAVELING	L	800.00	SqFt					
57	WEATHERING	L	4200.00	SqFt					
Sample Number:	310	Type:	R	Area:	5000.00 SqFt	PCI:	78		
Sample Comments:									
48	L & T CR	L	17.00	Ft					
52	RAVELING	L	900.00	SqFt					
57	WEATHERING	L	4100.00	SqFt					
Sample Number:	313	Type:	R	Area:	5000.00 SqFt	PCI:	82		
Sample Comments:									
48	L & T CR	L	2.00	Ft					
52	RAVELING	L	600.00	SqFt					
57	WEATHERING	L	4400.00	SqFt					
Sample Number:	318	Type:	R	Area:	5000.00 SqFt	PCI:	82		
Sample Comments:									
48	L & T CR	L	6.00	Ft					
52	RAVELING	L	600.00	SqFt					
57	WEATHERING	L	4400.00	SqFt					
Sample Number:	321	Type:	R	Area:	5000.00 SqFt	PCI:	80		
Sample Comments:									
48	L & T CR	L	26.00	Ft					
57	WEATHERING	L	4400.00	SqFt					
52	RAVELING	L	600.00	SqFt					
Sample Number:	324	Type:	R	Area:	5000.00 SqFt	PCI:	82		
Sample Comments:									
52	RAVELING	L	600.00	SqFt					
57	WEATHERING	L	4400.00	SqFt					
48	L & T CR	L	7.00	Ft					
Sample Number:	330	Type:	R	Area:	5000.00 SqFt	PCI:	81		
Sample Comments:									
52	RAVELING	L	700.00	SqFt					
57	WEATHERING	L	4300.00	SqFt					
48	L & T CR	L	6.00	Ft					

Sample Number: 338		Type: R	Area: 5000.00 SqFt	PCI: 81
Sample Comments:				
48	L & T CR	L	15.00 Ft	
52	RAVELING	L	600.00 SqFt	
57	WEATHERING	L	4400.00 SqFt	
Sample Number: 346		Type: R	Area: 5000.00 SqFt	PCI: 78
Sample Comments:				
48	L & T CR	L	11.00 Ft	
52	RAVELING	L	1000.00 SqFt	
57	WEATHERING	L	4000.00 SqFt	
Sample Number: 354		Type: R	Area: 5000.00 SqFt	PCI: 77
Sample Comments:				
48	L & T CR	L	108.00 Ft	
52	RAVELING	L	500.00 SqFt	
57	WEATHERING	L	4500.00 SqFt	
56	SWELLING	L	50.00 SqFt	
Sample Number: 362		Type: R	Area: 5000.00 SqFt	PCI: 73
Sample Comments:				
48	L & T CR	L	106.00 Ft	
52	RAVELING	L	1000.00 SqFt	
57	WEATHERING	L	4000.00 SqFt	
56	SWELLING	L	50.00 SqFt	
Sample Number: 370		Type: R	Area: 5000.00 SqFt	PCI: 81
Sample Comments:				
48	L & T CR	L	40.00 Ft	
52	RAVELING	L	500.00 SqFt	
57	WEATHERING	L	4500.00 SqFt	
Sample Number: 374		Type: R	Area: 5000.00 SqFt	PCI: 79
Sample Comments:				
48	L & T CR	L	109.00 Ft	
52	RAVELING	L	400.00 SqFt	
57	WEATHERING	L	4600.00 SqFt	
56	SWELLING	L	25.00 SqFt	
Sample Number: 378		Type: R	Area: 5000.00 SqFt	PCI: 80
Sample Comments:				
48	L & T CR	L	133.00 Ft	
52	RAVELING	L	500.00 SqFt	
57	WEATHERING	L	4500.00 SqFt	
Sample Number: 382		Type: R	Area: 5000.00 SqFt	PCI: 80
Sample Comments:				
48	L & T CR	L	92.00 Ft	
52	RAVELING	L	500.00 SqFt	
57	WEATHERING	L	4500.00 SqFt	
Sample Number: 385		Type: R	Area: 5000.00 SqFt	PCI: 80
Sample Comments:				
48	L & T CR	L	44.00 Ft	
52	RAVELING	L	500.00 SqFt	
57	WEATHERING	L	4500.00 SqFt	
Sample Number: 389		Type: R	Area: 5000.00 SqFt	PCI: 83
Sample Comments:				
48	L & T CR	L	41.00 Ft	
52	RAVELING	L	300.00 SqFt	
57	WEATHERING	L	4700.00 SqFt	
Sample Number: 392		Type: R	Area: 5000.00 SqFt	PCI: 80
Sample Comments:				
48	L & T CR	L	103.00 Ft	

52	RAVELING	L	500.00	SqFt
57	WEATHERING	L	4500.00	SqFt

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	RW 9L-27R		Name:	RUNWAY 9L-27R		Use:	RUNWAY		Area:	750,000 SqFt	
Section:	6118	of	8	From:	-			To:	-		
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:				Category:		
Area:	9,250 SqFt		Length:	360 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft	
Shoulder:	Street Type:				Grade:	0			Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1985		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI: 73										
Inspection Comments:											
Sample Number:	136	Type:	R	Area:	4250.00 SqFt			PCI:	73		
Sample Comments:											
48	L & T CR		L	41.00 Ft							
57	WEATHERING		L	4050.00 SqFt							
45	DEPRESSION		L	80.00 SqFt							
56	SWELLING		L	6.00 SqFt							
52	RAVELING		L	200.00 SqFt							

Network:		BOW		Name:		BARTOW MUNICIPAL AIRPORT						
Branch:	RW 9L-27R		Name:	RUNWAY 9L-27R		Use:	RUNWAY	Area:	750,000 SqFt			
Section:	6120		of	8	From:	-		To:	-		Last Const.:	1/1/2006
Surface:	AAC		Family:	C9N59-GA-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	170,750 SqFt		Length:	7,300 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True		
Last Insp. Date:	3/6/2017		TotalSamples:	35		Surveyed:	7					
Conditions:	PCI: 88											
Inspection Comments:												
Sample Number:	116		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	14.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	172		Type:	R		Area:	5000.00 SqFt		PCI:	83		
Sample Comments:												
48	L & T CR		L	193.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	184		Type:	R		Area:	5000.00 SqFt		PCI:	78		
Sample Comments:												
48	L & T CR		L	234.00 Ft								
56	SWELLING		L	10.00 SqFt								
52	RAVELING		L	25.00 SqFt								
57	WEATHERING		L	4975.00 SqFt								
Sample Number:	516		Type:	R		Area:	5000.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	536		Type:	R		Area:	5000.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	572		Type:	R		Area:	5000.00 SqFt		PCI:	88		
Sample Comments:												
48	L & T CR		L	66.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
56	SWELLING		L	6.00 SqFt								
Sample Number:	584		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	13.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT					
Branch:	RW 9L-27R		Name:	RUNWAY 9L-27R		Use:	RUNWAY	Area:	750,000 SqFt
Section:	6124	of 8	From:	-			To:	-	Last Const.: 1/1/2006
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:	Category:		Rank:	P
Area:	30,000 SqFt		Length:	1,100 Ft		Width:	25 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1985		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	3/6/2017		TotalSamples:	6		Surveyed: 2			
Conditions:	PCI:	78							
Inspection Comments:									
Sample Number:	160	Type:	R	Area:	5000.00 SqFt		PCI:	71	
Sample Comments:									
48	L & T CR	L	98.00	Ft					
56	SWELLING	L	52.00	SqFt					
52	RAVELING	L	100.00	SqFt					
57	WEATHERING	L	4900.00	SqFt					
45	DEPRESSION	L	56.00	SqFt					
48	L & T CR	M	8.00	Ft					
Sample Number:	560	Type:	R	Area:	5000.00 SqFt		PCI:	84	
Sample Comments:									
48	L & T CR	L	51.00	Ft					
57	WEATHERING	L	5000.00	SqFt					
56	SWELLING	L	95.00	SqFt					

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT								
Branch:	RW 9L-27R		Name:	RUNWAY 9L-27R		Use:	RUNWAY		Area:	750,000 SqFt			
Section:	6125		of	8	From:	-		To:	-		Last Const.:	1/1/2006	
Surface:	APC		Family:	C9N59-GA-RW-AAC-APC		Zone:			Category:			Rank:	P
Area:	30,000 SqFt		Length:	300 Ft		Width:	100 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	3/6/2017		TotalSamples:	6		Surveyed:	2						
Conditions:	PCI: 82												
Inspection Comments:													
Sample Number:	395		Type:	R		Area:	5000.00 SqFt		PCI:	83			
Sample Comments:													
48	L & T CR		L	67.00		Ft							
52	RAVELING		L	250.00		SqFt							
57	WEATHERING		L	4750.00		SqFt							
Sample Number:	399		Type:	R		Area:	5000.00 SqFt		PCI:	80			
Sample Comments:													
48	L & T CR		L	101.00		Ft							
52	RAVELING		L	500.00		SqFt							
57	WEATHERING		L	4500.00		SqFt							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	RW 9L-27R		Name:	RUNWAY 9L-27R		Use:	RUNWAY	Area:	750,000 SqFt		
Section:	6130	of	8	From:	-	To:	-	Last Const.:	1/1/2006		
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:		Category:		Rank:	P	
Area:	20,000 SqFt		Length:	600 Ft		Width:	25 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	4		Surveyed:	2				
Conditions:	PCI:	86									
Inspection Comments:											
Sample Number:	196	Type:	R	Area:	5000.00 SqFt		PCI:	85			
Sample Comments:											
48	L & T CR		L	13.00 Ft							
52	RAVELING		L	250.00 SqFt							
57	WEATHERING		L	4750.00 SqFt							
Sample Number:	596	Type:	R	Area:	5000.00 SqFt		PCI:	88			
Sample Comments:											
52	RAVELING		L	250.00 SqFt							
57	WEATHERING		L	4750.00 SqFt							

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT										
Branch:	RW 9R-27L		Name:	RUNWAY 9R-27L		Use:	RUNWAY		Area:	637,262 SqFt				
Section:	6205		of	6		From:	-		To:	-		Last Const.:	1/1/1942	
Surface:	AC		Family:	C9N59-GA-RW-AC		Zone:			Category:			Rank:	S	
Area:	350,236 SqFt		Length:	3,484 Ft		Width:			100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True				
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True				
Last Insp. Date:	3/6/2017		TotalSamples:	71		Surveyed:	15							
Conditions:	PCI: 22													
Inspection Comments:														
Sample Number:	300		Type:	R		Area:	3500.00 SqFt		PCI:	21				
Sample Comments:														
50	PATCHING		L	4.00 SqFt										
43	BLOCK CR		M	1500.00 SqFt										
43	BLOCK CR		L	1996.00 SqFt										
52	RAVELING		M	3490.00 SqFt										
52	RAVELING		H	6.00 SqFt										
Sample Number:	305		Type:	R		Area:	5000.00 SqFt		PCI:	22				
Sample Comments:														
43	BLOCK CR		L	3000.00 SqFt										
43	BLOCK CR		M	2000.00 SqFt										
52	RAVELING		M	4990.00 SqFt										
52	RAVELING		H	10.00 SqFt										
Sample Number:	309		Type:	R		Area:	5000.00 SqFt		PCI:	24				
Sample Comments:														
43	BLOCK CR		M	1500.00 SqFt										
50	PATCHING		L	4.00 SqFt										
43	BLOCK CR		L	3496.00 SqFt										
52	RAVELING		M	4996.00 SqFt										
Sample Number:	314		Type:	R		Area:	5000.00 SqFt		PCI:	25				
Sample Comments:														
43	BLOCK CR		M	1500.00 SqFt										
43	BLOCK CR		L	3500.00 SqFt										
52	RAVELING		M	5000.00 SqFt										
Sample Number:	319		Type:	R		Area:	5000.00 SqFt		PCI:	22				
Sample Comments:														
43	BLOCK CR		M	2500.00 SqFt										
43	BLOCK CR		L	2500.00 SqFt										
52	RAVELING		M	4900.00 SqFt										
52	RAVELING		H	100.00 SqFt										
Sample Number:	324		Type:	R		Area:	5000.00 SqFt		PCI:	19				
Sample Comments:														
43	BLOCK CR		M	2000.00 SqFt										
43	BLOCK CR		L	3000.00 SqFt										
52	RAVELING		M	4800.00 SqFt										
52	RAVELING		H	200.00 SqFt										
Sample Number:	329		Type:	R		Area:	4522.00 SqFt		PCI:	23				
Sample Comments:														
43	BLOCK CR		M	1022.00 SqFt										
43	BLOCK CR		L	3270.00 SqFt										
52	RAVELING		M	4270.00 SqFt										

E-31

50	PATCHING	M	230.00	SqFt					
52	RAVELING	H	22.00	SqFt					
Sample Number: 343					Type:	R	Area:	4621.00 SqFt	PCI: 21
Sample Comments:									
41	ALLIGATOR CR	L	24.00	SqFt					
43	BLOCK CR	M	1460.00	SqFt					
43	BLOCK CR	L	3137.00	SqFt					
52	RAVELING	M	4606.00	SqFt					
52	RAVELING	H	15.00	SqFt					
Sample Number: 347					Type:	R	Area:	5000.00 SqFt	PCI: 24
Sample Comments:									
50	PATCHING	L	4.00	SqFt					
52	RAVELING	H	11.00	SqFt					
52	RAVELING	M	4985.00	SqFt					
43	BLOCK CR	M	950.00	SqFt					
43	BLOCK CR	L	4046.00	SqFt					
Sample Number: 354					Type:	R	Area:	5000.00 SqFt	PCI: 21
Sample Comments:									
52	RAVELING	H	2.00	SqFt					
52	RAVELING	M	4998.00	SqFt					
43	BLOCK CR	M	1474.00	SqFt					
43	BLOCK CR	L	3500.00	SqFt					
41	ALLIGATOR CR	L	26.00	SqFt					
Sample Number: 361					Type:	R	Area:	5000.00 SqFt	PCI: 21
Sample Comments:									
48	L & T CR	L	90.00	Ft					
43	BLOCK CR	M	1500.00	SqFt					
43	BLOCK CR	L	2993.00	SqFt					
52	RAVELING	M	4950.00	SqFt					
41	ALLIGATOR CR	L	7.00	SqFt					
52	RAVELING	H	50.00	SqFt					
Sample Number: 367					Type:	R	Area:	5000.00 SqFt	PCI: 22
Sample Comments:									
48	L & T CR	M	50.00	Ft					
48	L & T CR	L	254.00	Ft					
43	BLOCK CR	M	1000.00	SqFt					
43	BLOCK CR	L	2050.00	SqFt					
52	RAVELING	M	4990.00	SqFt					
52	RAVELING	H	10.00	SqFt					
Sample Number: 371					Type:	R	Area:	5000.00 SqFt	PCI: 25
Sample Comments:									
41	ALLIGATOR CR	L	7.00	SqFt					
43	BLOCK CR	M	999.00	SqFt					
43	BLOCK CR	L	3994.00	SqFt					
52	RAVELING	M	5000.00	SqFt					
Sample Number: 375					Type:	R	Area:	5000.00 SqFt	PCI: 23
Sample Comments:									
41	ALLIGATOR CR	L	6.00	SqFt					
48	L & T CR	L	113.00	Ft					
48	L & T CR	M	50.00	Ft					
43	BLOCK CR	L	2044.00	SqFt					
52	RAVELING	M	5000.00	SqFt					
43	BLOCK CR	M	1400.00	SqFt					
Sample Number: 378					Type:	R	Area:	5000.00 SqFt	PCI: 22
Sample Comments:									
43	BLOCK CR	M	2000.00	SqFt					
43	BLOCK CR	L	3000.00	SqFt					
52	RAVELING	M	4995.00	SqFt					
52	RAVELING	H	5.00	SqFt					

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT								
Branch:	RW 9R-27L		Name:	RUNWAY 9R-27L		Use:	RUNWAY	Area:	637,262 SqFt				
Section:	6210 of 6		From:	-			To:	-			Last Const.:	1/1/1942	
Surface:	AC		Family:	C9N59-GA-RW-AC		Zone:				Category:	Rank: S		
Area:	175,118 SqFt			Length:	6,966 Ft		Width:	25 Ft					
Slabs:	Slab Length:			Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:			Grade:		0			Lanes:	0			
Section Comments:													
Work Date:	1/1/1942			Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1942			Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True	
Last Insp. Date:	3/6/2017			TotalSamples:	36		Surveyed:	7					
Conditions:	PCI: 26												
Inspection Comments:													
Sample Number:	112		Type:	R		Area:	5000.00 SqFt		PCI:	29			
Sample Comments:													
43	BLOCK CR		M	500.00 SqFt									
43	BLOCK CR		L	4500.00 SqFt									
52	RAVELING		M	5000.00 SqFt									
Sample Number:	148		Type:	R		Area:	5000.00 SqFt		PCI:	25			
Sample Comments:													
43	BLOCK CR		M	1500.00 SqFt									
43	BLOCK CR		L	3500.00 SqFt									
52	RAVELING		M	5000.00 SqFt									
Sample Number:	168		Type:	R		Area:	5000.00 SqFt		PCI:	28			
Sample Comments:													
43	BLOCK CR		M	100.00 SqFt									
48	L & T CR		L	76.00 Ft									
43	BLOCK CR		L	4508.00 SqFt									
52	RAVELING		M	5000.00 SqFt									
Sample Number:	512		Type:	R		Area:	5000.00 SqFt		PCI:	27			
Sample Comments:													
43	BLOCK CR		M	1000.00 SqFt									
43	BLOCK CR		L	4000.00 SqFt									
52	RAVELING		M	5000.00 SqFt									
Sample Number:	524		Type:	R		Area:	6311.00 SqFt		PCI:	24			
Sample Comments:													
43	BLOCK CR		M	304.00 SqFt									
43	BLOCK CR		L	6000.00 SqFt									
52	RAVELING		M	6204.00 SqFt									
50	PATCHING		M	7.00 SqFt									
52	RAVELING		H	100.00 SqFt									
Sample Number:	548		Type:	R		Area:	5000.00 SqFt		PCI:	27			
Sample Comments:													
43	BLOCK CR		M	1000.00 SqFt									
43	BLOCK CR		L	4000.00 SqFt									
52	RAVELING		M	5000.00 SqFt									
Sample Number:	568		Type:	R		Area:	5000.00 SqFt		PCI:	25			
Sample Comments:													
43	BLOCK CR		M	1500.00 SqFt									
43	BLOCK CR		L	3500.00 SqFt									
52	RAVELING		M	5000.00 SqFt									

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	RW 9R-27L		Name:	RUNWAY 9R-27L		Use:	RUNWAY	Area:	637,262 SqFt		
Section:	6215	of	6	From:	-	To:	-	Last Const.:	1/1/1942		
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC		Zone:		Category:		Rank:	S	
Area:	30,000 SqFt		Length:	300 Ft		Width:	100 Ft				
Slabs:	192	Slab Length:	12 Ft		Slab Width:	12 Ft		Joint Length:	4,400 Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type:	OVERLAY			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	8		Surveyed:	3				
Conditions:	PCI:	76									
Inspection Comments:											
Sample Number:	382	Type:	R	Area:	24.00 Slabs		PCI:	70			
Sample Comments:											
75	CORNER SPALL		M	1.00	Slabs						
65	JT SEAL DMG		H	24.00	Slabs						
73	SHRINKAGE CR		N	20.00	Slabs						
75	CORNER SPALL		L	3.00	Slabs						
74	JOINT SPALL		L	3.00	Slabs						
Sample Number:	387	Type:	R	Area:	24.00 Slabs		PCI:	81			
Sample Comments:											
65	JT SEAL DMG		H	24.00	Slabs						
73	SHRINKAGE CR		N	17.00	Slabs						
66	SMALL PATCH		L	1.00	Slabs						
Sample Number:	389	Type:	R	Area:	24.00 Slabs		PCI:	78			
Sample Comments:											
65	JT SEAL DMG		H	24.00	Slabs						
73	SHRINKAGE CR		N	10.00	Slabs						
74	JOINT SPALL		M	1.00	Slabs						
75	CORNER SPALL		L	1.00	Slabs						

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	RW 9R-27L		Name:	RUNWAY 9R-27L		Use:	RUNWAY	Area:	637,262 SqFt		
Section:	6220	of 6	From:	-			To:	-			
Surface:	PCC	Family:	C9N59-GA-RW-TW-PCC		Zone:			Category:	Rank: S		
Area:	15,000 SqFt		Length:	600 Ft		Width:	25 Ft				
Slabs:	96	Slab Length:	13 Ft		Slab Width:	13 Ft		Joint Length:	1,775 Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	4		Surveyed:	2				
Conditions:	PCI: 77										
Inspection Comments:											
Sample Number:	184	Type:	R	Area:	24.00 Slabs		PCI:	72			
Sample Comments:											
75	CORNER SPALL		L	2.00 Slabs							
65	JT SEAL DMG		H	24.00 Slabs							
73	SHRINKAGE CR		N	16.00 Slabs							
74	JOINT SPALL		L	1.00 Slabs							
75	CORNER SPALL		M	1.00 Slabs							
74	JOINT SPALL		M	1.00 Slabs							
Sample Number:	584	Type:	R	Area:	24.00 Slabs		PCI:	82			
Sample Comments:											
74	JOINT SPALL		L	1.00 Slabs							
65	JT SEAL DMG		H	24.00 Slabs							
73	SHRINKAGE CR		N	8.00 Slabs							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	RW 9R-27L		Name:	RUNWAY 9R-27L		Use:	RUNWAY	Area:	637,262 SqFt			
Section:	6225	of	6	From:	-			To:	-		Last Const.:	1/1/2001
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:				Category:	Rank: S		
Area:	44,518 SqFt		Length:	454 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True		
Work Date:	1/1/2001		Work Type: Mill and Overlay				Code:	ML-OL		Is Major M&R: True		
Last Insp. Date:	3/6/2017		TotalSamples:	10		Surveyed:	2					
Conditions:	PCI: 69											
Inspection Comments:												
Sample Number:	334		Type:	R		Area:	4951.00 SqFt		PCI:	66		
Sample Comments:												
48	L & T CR		L	9.00 Ft								
52	RAVELING		L	4901.00 SqFt								
52	RAVELING		M	50.00 SqFt								
Sample Number:	339		Type:	R		Area:	5000.00 SqFt		PCI:	73		
Sample Comments:												
57	WEATHERING		L	1000.00 SqFt								
52	RAVELING		L	4000.00 SqFt								

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	RW 9R-27L		Name:	RUNWAY 9R-27L		Use:	RUNWAY	Area:	637,262 SqFt		
Section:	6230	of	6	From:	-	To:	-	Last Const.:	1/1/2001		
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:		Category:		Rank:	S	
Area:	22,390 SqFt		Length:	910 Ft		Width:	25 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1942		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2001		Work Type: Mill and Overlay				Code:	ML-OL		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI: 66										
Inspection Comments:											
Sample Number:	140	Type:	R	Area:	5565.00 SqFt		PCI:	66			
Sample Comments:											
52	RAVELING		L	5545.00 SqFt							
48	L & T CR		L	10.00 Ft							
52	RAVELING		M	20.00 SqFt							

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	160,418 SqFt		
Section:	4205		of	3	From:				To:	Last Const.: 1/1/2004	
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:				Category:	Rank: T
Area:	120,980 SqFt		Length:	2,725 Ft		Width:	28 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft			Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0			Lanes:	0
Section Comments:											
Work Date:	1/1/2004		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2006		Work Type:	Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	3/6/2017		TotalSamples:	27		Surveyed:	3				
Conditions:	PCI: 47										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	4844.00 SqFt		PCI:	45	
Sample Comments:											
53	RUTTING		L	60.00		SqFt					
52	RAVELING		M	50.00		SqFt					
48	L & T CR		L	472.00		Ft					
43	BLOCK CR		M	780.00		SqFt					
52	RAVELING		L	4794.00		SqFt					
Sample Number:	207		Type:	R		Area:	5000.00 SqFt		PCI:	45	
Sample Comments:											
52	RAVELING		M	27.00		SqFt					
48	L & T CR		L	174.00		Ft					
50	PATCHING		M	1125.00		SqFt					
52	RAVELING		L	3848.00		SqFt					
Sample Number:	902		Type:	R		Area:	4386.00 SqFt		PCI:	50	
Sample Comments:											
52	RAVELING		M	150.00		SqFt					
48	L & T CR		L	369.00		Ft					
43	BLOCK CR		L	2193.00		SqFt					
52	RAVELING		L	4236.00		SqFt					

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	160,418 SqFt		
Section:	4305	of 3	From:				To:				
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:			Category:			
Area:	28,752 SqFt		Length:	985 Ft		Width:	20 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2004		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	7		Surveyed:	1				
Conditions:	PCI:	64									
Inspection Comments:											
Sample Number:	201	Type:	R	Area:	4700.00 SqFt		PCI:	64			
Sample Comments:											
56	SWELLING		L	11.00 SqFt							
52	RAVELING		M	8.00 SqFt							
52	RAVELING		L	4692.00 SqFt							
48	L & T CR		L	21.00 Ft							

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	160,418 SqFt		
Section:	4310	of 3	From:	-			To:	-		Last Const.:	9/1/2012
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Category:	Rank: P	
Area:	10,686 SqFt		Length:	515 Ft		Width:	20 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	9/1/2012		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	3/6/2017		TotalSamples:		2		Surveyed:		1		
Conditions:	PCI:		89								
Inspection Comments:											
Sample Number:	300		Type:	R		Area:	5386.00 SqFt		PCI: 89		
Sample Comments:											
48	L & T CR		L		17.00 Ft						
56	SWELLING		L		9.00 SqFt						
57	WEATHERING		L		5386.00 SqFt						

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY		Area:	93,327 SqFt		
Section:	105	of	1	From:	-			To:	-		Last Const.:	2/1/2012
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:				Category:	Rank: P		
Area:	93,327 SqFt		Length:	1,820 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:				Grade:		0		Lanes:		0	
Section Comments:												
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	2/1/2012		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True		
Last Insp. Date:	3/6/2017		TotalSamples:	19		Surveyed:		3				
Conditions:	PCI:	82										
Inspection Comments:												
Sample Number:	102	Type:	R	Area:	5000.00 SqFt			PCI:	89			
Sample Comments:												
48	L & T CR		L	67.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	107	Type:	R	Area:	5000.00 SqFt			PCI:	77			
Sample Comments:												
48	L & T CR		L	343.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	113	Type:	R	Area:	5000.00 SqFt			PCI:	81			
Sample Comments:												
48	L & T CR		L	240.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY		Area:	84,166 SqFt	
Section:	110 of 3		From:	-			To:	-		Last Const.:	2/1/2012
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	33,575 SqFt		Length:	649 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	2/1/2012		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	6		Surveyed:	1				
Conditions:	PCI: 86										
Inspection Comments:											
Sample Number:	101		Type:	R		Area:	5000.00 SqFt		PCI:	86	
Sample Comments:											
48	L & T CR		L	132.00 Ft							
57	WEATHERING		L	5000.00 SqFt							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY		Area:	84,166 SqFt	
Section:	112 of 3		From:				To:	Last Const.: 1/1/2003			
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:	Category:		Rank: P		
Area:	43,953 SqFt		Length:	2,400 Ft		Width:	55 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:	0		Lanes:		0	
Section Comments:											
Work Date:	1/1/2003		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	3/6/2017		TotalSamples:	10		Surveyed:		1			
Conditions:	PCI: 69										
Inspection Comments:											
Sample Number:	111		Type:	R		Area:	3969.00 SqFt		PCI: 69		
Sample Comments:											
48	L & T CR		L	50.00 Ft							
52	RAVELING		L	3969.00 SqFt							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT													
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY		Area:	84,166 SqFt								
Section:	114		of	3		From:					To:			Last Const.:	1/1/2006			
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:					Category:					Rank:	P	
Area:	6,638 SqFt		Length:	2,400 Ft		Width:	55 Ft											
Slabs:			Slab Length:	Ft		Slab Width:	Ft				Joint Length:	Ft						
Shoulder:			Street Type:			Grade:	0				Lanes:	0						
Section Comments:																		
Work Date:	1/1/2003			Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True					
Work Date:	1/1/2006			Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True					
Last Insp. Date:	3/6/2017			TotalSamples:	2				Surveyed:	1								
Conditions:	PCI: 84																	
Inspection Comments:																		
Sample Number:	116		Type:	R		Area:	2346.00 SqFt				PCI:	84						
Sample Comments:																		
48	L & T CR		L	25.00 Ft														
45	DEPRESSION		L	18.00 SqFt														
57	WEATHERING		L	2346.00 SqFt														

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	TW A3		Name:	TAXIWAY A3		Use:	TAXIWAY		Area:	44,009 SqFt	
Section:	115	of	1	From:	-		To:	-		Last Const.:	1/1/1987
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	44,009 SqFt		Length:	1,100 Ft		Width:	38 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	11		Surveyed:	2				
Conditions:	PCI: 41										
Inspection Comments:											
Sample Number:	105	Type:	R	Area:	4000.00 SqFt		PCI:	38			
Sample Comments:											
48	L & T CR		M	300.00	Ft						
48	L & T CR		L	356.00	Ft						
52	RAVELING		L	3950.00	SqFt						
43	BLOCK CR		M	498.00	SqFt						
56	SWELLING		L	172.00	SqFt						
50	PATCHING		M	50.00	SqFt						
Sample Number:	109	Type:	R	Area:	4000.00 SqFt		PCI:	45			
Sample Comments:											
48	L & T CR		M	163.00	Ft						
48	L & T CR		L	300.00	Ft						
52	RAVELING		L	4000.00	SqFt						
43	BLOCK CR		L	150.00	SqFt						
43	BLOCK CR		M	300.00	SqFt						
56	SWELLING		L	228.00	SqFt						

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	TW C1		Name:	TAXIWAY C1		Use:	TAXIWAY	Area:	18,037 SqFt		
Section:	305 of 1		From:	-		To:	-		Last Const.:	7/1/2009	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Rank:	P	
Area:	18,037 SqFt		Length:	330 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2009		Work Type: Mill and Overlay				Code:	ML-OL		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI: 86										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	5000.00 SqFt		PCI:	86	
Sample Comments:											
48	L & T CR		L	26.00 Ft							
52	RAVELING		L	100.00 SqFt							
57	WEATHERING		L	4900.00 SqFt							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT								
Branch:	TW C2		Name:	TAXIWAY C2		Use:	TAXIWAY		Area:	30,619 SqFt			
Section:	310		of	1	From:	-		To:	-		Last Const.:	1/1/1987	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P
Area:	30,619 SqFt		Length:	850 Ft		Width:	35 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1987		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Last Insp. Date:	3/6/2017		TotalSamples:	8		Surveyed:	1						
Conditions:	PCI: 56												
Inspection Comments:													
Sample Number:	106		Type:	R		Area:	3500.00 SqFt		PCI:	56			
Sample Comments:													
52	RAVELING		M	500.00 SqFt									
48	L & T CR		L	213.00 Ft									
48	L & T CR		M	76.00 Ft									
52	RAVELING		L	3000.00 SqFt									

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT				
Branch:	TW C3		Name:	TAXIWAY C3		Use:	TAXIWAY	Area:	46,403 SqFt
Section:	315	of	2	From:	-	To:	-	Last Const.:	1/1/1987
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	41,491 SqFt	Length:	1,175 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1942	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1971	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1987	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1987	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/6/2017	TotalSamples:	12	Surveyed:	2				
Conditions:	PCI:	58							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	3500.00 SqFt	PCI:	62		
Sample Comments:									
48	L & T CR	M	100.00	Ft					
48	L & T CR	L	150.00	Ft					
52	RAVELING	L	3500.00	SqFt					
56	SWELLING	L	9.00	SqFt					
Sample Number:	105	Type:	R	Area:	3500.00 SqFt	PCI:	55		
Sample Comments:									
48	L & T CR	M	57.00	Ft					
48	L & T CR	L	327.00	Ft					
43	BLOCK CR	L	525.00	SqFt					
52	RAVELING	L	3500.00	SqFt					

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT					
Branch:	TW C3		Name:	TAXIWAY C3		Use:	TAXIWAY	Area:	46,403 SqFt	
Section:	320	of	2	From:	-		To:	-	Last Const.: 1/1/1990	
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	4,912 SqFt		Length:	125 Ft		Width:	35 Ft			
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1990		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Last Insp. Date: 3/6/2017										
TotalSamples:			1		Surveyed: 1					
Conditions:	PCI: 38									
Inspection Comments:										
Sample Number:	112	Type:	R	Area:	4912.00 SqFt		PCI:	38		
Sample Comments:										
48	L & T CR		M	152.00 Ft						
48	L & T CR		L	567.00 Ft						
56	SWELLING		M	52.00 SqFt						
56	SWELLING		L	312.00 SqFt						
45	DEPRESSION		L	75.00 SqFt						
43	BLOCK CR		L	540.00 SqFt						
52	RAVELING		L	4912.00 SqFt						

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT				
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	374,649 SqFt
Section:	405	of	6	From:	-	To:	-	Last Const.:	7/1/2009
Surface:	AAC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank: P
Area:	95,846 SqFt	Length:	2,000 Ft		Width:	50 Ft			
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1984		Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1984		Work Type: BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	7/1/2009		Work Type: MILL and OVERLAY			Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	19	Surveyed:	3			
Conditions:	PCI:	81							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	5000.00 SqFt	PCI:	80		
Sample Comments:									
48	L & T CR	L	131.00	Ft					
52	RAVELING	L	250.00	SqFt					
57	WEATHERING	L	4750.00	SqFt					
56	SWELLING	L	9.00	SqFt					
Sample Number:	108	Type:	R	Area:	5000.00 SqFt	PCI:	82		
Sample Comments:									
48	L & T CR	L	108.00	Ft					
52	RAVELING	L	100.00	SqFt					
57	WEATHERING	L	4900.00	SqFt					
56	SWELLING	L	15.00	SqFt					
Sample Number:	117	Type:	R	Area:	5000.00 SqFt	PCI:	83		
Sample Comments:									
48	L & T CR	L	69.00	Ft					
52	RAVELING	L	250.00	SqFt					
57	WEATHERING	L	4750.00	SqFt					

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	374,649 SqFt		
Section:	407 of 6		From:	-		To:	-		Last Const.:	7/1/2009	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:	Category:		Rank:	P	
Area:	15,000 SqFt		Length:	200 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1984		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2009		Work Type: Mill and Overlay				Code:	ML-OL		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	3		Surveyed:	1				
Conditions:	PCI: 83										
Inspection Comments:											
Sample Number:	115	Type:	R	Area:	5000.00 SqFt		PCI:	83			
Sample Comments:											
48	L & T CR		L	73.00 Ft							
52	RAVELING		L	250.00 SqFt							
57	WEATHERING		L	4750.00 SqFt							

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	374,649 SqFt		
Section:	420	of 6	From:				To:				
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:			Category:			
Area:	81,983 SqFt		Length:	2,400 Ft		Width:	55 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2003		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	15		Surveyed:	2				
Conditions:	PCI:	67									
Inspection Comments:											
Sample Number:	204	Type:	R	Area:	5000.00 SqFt		PCI:	65			
Sample Comments:											
48	L & T CR	L	105.00 Ft								
52	RAVELING	L	4996.00 SqFt								
52	RAVELING	M	4.00 SqFt								
Sample Number:	209	Type:	R	Area:	5000.00 SqFt		PCI:	69			
Sample Comments:											
48	L & T CR	L	84.00 Ft								
52	RAVELING	L	5000.00 SqFt								

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	374,649 SqFt		
Section:	425	of 6	From:				To:				
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:			Category:			
Area:	32,996 SqFt		Length:	1,200 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2003		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	9		Surveyed:	1				
Conditions:	PCI:	69									
Inspection Comments:											
Sample Number:	302	Type:	R	Area:	3332.00 SqFt		PCI:	69			
Sample Comments:											
48	L & T CR		L	21.00 Ft							
52	RAVELING		L	3332.00 SqFt							

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT				
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	84,025 SqFt
Section:	605	of	4	From:	-	To:	-	Last Const.:	1/1/2006
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	10,259 SqFt	Length:	85 Ft	Width:	90 Ft				
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:	Street Type:	Grade:	0	Lanes:	0				
Section Comments:									
Work Date:	1/1/1942	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1971	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1971	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2006	Work Type:	MILL and OVERLAY			Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/6/2017	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	76							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	4607.00 SqFt	PCI:	76		
Sample Comments:									
48	L & T CR	L	134.00	Ft					
52	RAVELING	L	92.00	SqFt					
57	WEATHERING	L	4515.00	SqFt					
45	DEPRESSION	L	49.00	SqFt					

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT										
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	84,025 SqFt					
Section:	610		of	4		From:	-		To:	-		Last Const.:	1/1/1971	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	30,778 SqFt		Length:	340 Ft		Width:	90 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1942		Work Type:	BUILT		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1971		Work Type:	OVERLAY		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1971		Work Type:	OVERLAY		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1991		Work Type:	REPAIR		Code:	IMPORTED		Is Major M&R:	False				
Last Insp. Date:	3/6/2017		TotalSamples:	7		Surveyed:	1							
Conditions:	PCI:	42												
Inspection Comments:														
Sample Number:	103		Type:	R		Area:	4600.00 SqFt		PCI:	42				
Sample Comments:														
56	SWELLING		L	63.00 SqFt										
43	BLOCK CR		M	2050.00 SqFt										
43	BLOCK CR		L	1000.00 SqFt										
52	RAVELING		L	4600.00 SqFt										

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT				
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	84,025 SqFt
Section:	615	of	4	From:	-	To:	-	Last Const.:	1/1/2006
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:		Category:		Rank: P
Area:	5,898 SqFt		Length:	290 Ft		Width:	120 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0
Section Comments:									
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1990		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1990		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2006		Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	3/6/2017		TotalSamples:	1		Surveyed:	1		
Conditions:	PCI: 65								
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	5898.00 SqFt		PCI:	65	
Sample Comments:									
48	L & T CR		L	142.00 Ft					
52	RAVELING		L	3000.00 SqFt					
57	WEATHERING		L	2898.00 SqFt					
45	DEPRESSION		L	64.00 SqFt					

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT					
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	84,025 SqFt	
Section:	620	of	4	From:	-	To:	-	Last Const.:	2/1/2012	
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:		Category:		Rank:	P
Area:	37,090 SqFt		Length:	290 Ft		Width:	120 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1990		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1990		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	2/1/2012		Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	8		Surveyed:	1			
Conditions:	PCI:	88								
Inspection Comments:										
Sample Number:	103	Type:	R	Area:	3258.00 SqFt		PCI:	88		
Sample Comments:										
48	L & T CR		L	62.00 Ft						
57	WEATHERING		L	3258.00 SqFt						

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT										
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY	Area:	67,059 SqFt					
Section:	705		of	2		From:	-		To:	-		Last Const.:	1/1/1971	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	32,612 SqFt		Length:	210 Ft		Width:	150 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1942		Work Type:	BUILT		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1971		Work Type:	OVERLAY		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1971		Work Type:	OVERLAY		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1991		Work Type:	REPAIR		Code:	IMPORTED		Is Major M&R:	False				
Last Insp. Date:	3/6/2017		TotalSamples:	8		Surveyed:	1							
Conditions:	PCI:	39												
Inspection Comments:														
Sample Number:	201		Type:	R		Area:	3768.00 SqFt		PCI:	39				
Sample Comments:														
43	BLOCK CR		L	1300.00 SqFt										
43	BLOCK CR		M	1250.00 SqFt										
48	L & T CR		M	50.00 Ft										
48	L & T CR		L	76.00 Ft										
52	RAVELING		L	3768.00 SqFt										

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT						
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY	Area:	67,059 SqFt		
Section:	710	of	2	From:	-	To:	-	Last Const.:	1/1/1971		
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:		Category:		Rank:	P	
Area:	34,447 SqFt		Length:	210 Ft		Width:	150 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/6/2017		TotalSamples:	9		Surveyed:	1				
Conditions:	PCI:	23									
Inspection Comments:											
Sample Number:	106	Type:	R	Area:	3750.00 SqFt		PCI:	23			
Sample Comments:											
48	L & T CR		L	167.00	Ft						
43	BLOCK CR		L	2500.00	SqFt						
45	DEPRESSION		L	105.00	SqFt						
52	RAVELING		M	3740.00	SqFt						
52	RAVELING		H	10.00	SqFt						

Network:	BOW			Name:	BARTOW MUNICIPAL AIRPORT									
Branch:	TW H		Name:	TAXIWAY H		Use:	TAXIWAY	Area:	28,396 SqFt					
Section:	802		of	2	From:	-		To:	-		Last Const.:	2/1/2012		
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	3,573 SqFt		Length:	25 Ft		Width:	50 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1971			Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True		
Work Date:	2/1/2012			Work Type:	MILL and OVERLAY			Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	3/6/2017			TotalSamples:	1			Surveyed:	1					
Conditions:	PCI: 84													
Inspection Comments:														
Sample Number:	100		Type:	R		Area:	3573.00 SqFt		PCI:	84				
Sample Comments:														
48	L & T CR		L	15.00		Ft								
52	RAVELING		L	179.00		SqFt								
57	WEATHERING		L	3394.00		SqFt								

Network:	BOW		Name:	BARTOW MUNICIPAL AIRPORT										
Branch:	TW H		Name:	TAXIWAY H		Use:	TAXIWAY	Area:	28,396 SqFt					
Section:	805		of	2		From:	-		To:	-		Last Const.:	2/1/2012	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	24,823 SqFt		Length:	475 Ft		Width:	50 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1971		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	2/1/2012		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	3/6/2017		TotalSamples:	5		Surveyed:	1							
Conditions:	PCI: 90													
Inspection Comments:														
Sample Number:	102		Type:	R		Area:	5000.00 SqFt		PCI:	90				
Sample Comments:														
57	WEATHERING		L	5000.00 SqFt										
48	L & T CR		L	36.00 Ft										