

Statewide Airfield Pavement Management Program

**Airport Pavement
Evaluation Report
September 2017**



**Winter Haven's
Gilbert Airport (GIF)**
General Aviation Airport
District 1





Florida Department of Transportation

Statewide Airfield Pavement Management Program

Prepared by:

*FDOT Aviation and Spaceports Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*




OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS

Table of Contents


Executive Summary.....	10
Program Background.....	10
Summary of Results.....	11
Pavement Condition Index (Latest Inspection)	11
Forecasted Pavement Condition Index 2018-2027.....	13
Major Rehabilitation Planning 2018-2027	14
Summary of Winter Haven's Gilbert Airport	16
Chapter 1 – Introduction.....	18
1.1 Background	18
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017	18
1.3 Organization	20
1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager	20
1.3.2 Participating Florida Public-Use and Publicly Owned Airports	20
1.3.3 Florida Department of Transportation District Offices.....	20
1.3.4 Consultant	20
1.4 Purpose of Airport Pavement Evaluation Report	22
1.5 History of the Program.....	22
1.6 Federal Aviation Administration (FAA)	24
1.7 FDOT SAPMP Objectives and Components	24
1.7.1 Program Objectives.....	24
1.7.2 Program Components	24
1.8 References	28
Chapter 2 – Methodology	30
2.1 Airfield Pavement Database.....	30
2.2 Airfield Pavement System Inventory	30
2.2.1 Pavement Management Program Network Definition Terminology	31
2.3 Airfield Pavement Structure.....	33
2.3.1 Pavement Structure Types.....	33
2.4 Airfield Pavement Work History	35
2.4.1 Airfield Pavement Record Keeping	35
2.5 Airfield Pavement Traffic	35
2.6 Airfield Pavement Condition Index (PCI) Survey.....	35
2.6.1 PCI Survey Methodology	35
2.6.2 Pavement Distress Types	37

2.6.3 PCI Survey Inspection Procedures	41
2.6.4 Updates to the ASTM D5340-12	42
Chapter 3 – Airfield Pavement System Inventory	45
3.1 Airfield Pavement Network Information	45
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	45
3.1.2 Estimated Pavement Age.....	47
3.1.3 Functional Use Classification	49
3.1.4 Pavement Surface Type.....	50
3.1.5 Pavement System Inventory Details	51
Chapter 4 – Airfield Pavement Condition	57
4.1 Airfield Pavement Condition Index (Latest Inspection)	57
4.1.1 Network-Level Analysis	57
4.1.2 Branch-Level Analysis.....	57
4.1.3 Section-Level Analysis	60
4.2 Summary of Pavement Condition Evaluation Results	64
4.2.1 Network-Level Observations	64
4.2.2 Branch-Level Observations.....	64
4.3 Forecasted Pavement Conditions	66
4.3.1 Performance Models and Prediction Curves	66
4.3.2 Branch-Level Pavement Condition Forecast	66
4.3.3 Section-Level Pavement Condition Forecast.....	68
4.3.4 Forecasted PCI Considerations	72
Chapter 5 – Localized Maintenance and Repair Planning.....	74
5.1 Localized Maintenance and Repair	74
5.2 Localized Maintenance and Repair Policy	75
5.3 Localized Maintenance and Repair Analysis and Recommendations	79
Chapter 6 – Major Rehabilitation Planning.....	84
6.1 Major Rehabilitation	84
6.1.1 Critical PCI	86
6.1.2 FDOT Recommended Minimum Service-Level PCI	86
6.2 Major Rehabilitation Policy	87
6.2.1 Major Rehabilitation Pavement Section Development.....	87
6.2.2 Major Rehabilitation Planning-Level Unit Costs.....	88
6.3 Major Rehabilitation Needs.....	89
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs	89
Chapter 7 – Conclusion	94
7.1 Recommendations	94
7.1.1 Continued PCI Survey Inspections	94
7.1.2 Localized Maintenance and Repair.....	94

7.1.3 Major Rehabilitation	94
7.1.4 Pavement Management System	94
7.2 Supporting Documents	95
001 – Airfield Pavement Network Definition Exhibit	95
002 – Airfield Pavement System Inventory Exhibit	95
003 – Airfield Pavement Condition Index Exhibit	95
004 – Airfield Pavement Major Rehabilitation Exhibit	95
Inspection Photograph Documentation	95
7.3 Conclusion	96



Appendix A	Airfield Pavement Analysis Tables
Appendix B	Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
Appendix C	Technical Exhibits
Appendix D	Inspection Photograph Documentation
Appendix E	Inspection Distress Details



List of Figures

Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027	16
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts	19
Figure 1.7-1 Typical Pavement Condition Life Cycle	25
Figure 1.7-2 General Pavement Treatments by Condition Range	26
Figure 1.7-3 Flexible Asphalt Concrete	27
Figure 1.7-4 Rigid Portland Cement Concrete	27
Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit	46
Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit	47
Figure 3.1.2 Average Age of Pavements at Inspection	48
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area	49
Figure 3.1.4 (a) Pavement Surface Type by Area (SF)	50
Figure 3.1.4 (b) Pavement Surface Type by Area (%)	51
Figure 4.1.1 Latest Condition – Overall Network	57
Figure 4.1.2 (a) Latest Condition – Runway Pavements	58
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements	58
Figure 4.1.2 (c) Latest Condition – Apron Pavements	59
Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit	63
Figure 4.2.2 Pavement Condition Summary by Facility Use	64
Figure 4.3.2 (a) Forecasted Runway Pavement Performance	66
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance	67
Figure 4.3.2 (c) Forecasted Apron Pavement Performance	67
Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, $PCI \leq$ Critical PCI	84
Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, $PCI >$ Critical PCI	85
Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year	91
Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit	92

List of Tables

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level.....	11
Table E-2 Pavement Condition Index Forecast 2018-2027	13
Table E-3 Major Rehabilitation Planning 2018-2027	14
Table 2.2.1 Airfield Pavement Database Network Definition Terminology	32
Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields	37
Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields.....	38
Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields.....	38
Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields..	39
Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields.....	40
Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields.....	40
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete	41
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete....	41
Table 2.6.4 Summary of Updates to ASTM D5340-12.....	43
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction	45
Table 3.1.5 Pavement System Inventory Details	52
Table 4.1.3 Latest Pavement Condition Index Summary.....	61
Table 4.3.3 Forecasted PCI 2018-2027	69
Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete	75
Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete.....	76
Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete	78
Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete .	78

Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

79

Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

..80

Table 5.3-3 Summary of Localized Maintenance

.....82

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

.....86

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete

.....87

Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete


.....88

Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type

.....89

Table 6.3.1 10-Year Major Rehabilitation Needs

.....90



Executive Summary





Executive Summary

Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)"** using the documented procedures set forth by ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."**

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.



Summary of Results

Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
GIF	RUNWAY 5-23	RUNWAY	6105	182,500	81	Satisfactory
GIF	RUNWAY 5-23	RUNWAY	6110	182,500	88	Good
GIF	RUNWAY 5-23	RUNWAY	6115	50,300	85	Satisfactory
GIF	RUNWAY 5-23	RUNWAY	6117	50,300	89	Good
GIF	RUNWAY 5-23	RUNWAY	6120	17,500	82	Satisfactory
GIF	RUNWAY 5-23	RUNWAY	6122	17,500	87	Good
GIF	RUNWAY 11-29	RUNWAY	6205	367,600	65	Fair
GIF	RUNWAY 11-29	RUNWAY	6210	22,301	86	Good
GIF	TAXIWAY A	TAXIWAY	110	62,789	63	Fair
GIF	TAXIWAY A	TAXIWAY	115	2,744	37	Very Poor
GIF	TAXIWAY A	TAXIWAY	320	23,750	51	Poor
GIF	TAXIWAY A	TAXIWAY	405	7,000	51	Poor
GIF	TAXIWAY A	TAXIWAY	410	43,255	32	Very Poor
GIF	TAXIWAY A	TAXIWAY	417	10,400	58	Fair
GIF	TAXIWAY A2	TAXIWAY	105	8,491	55	Poor
GIF	TAXIWAY B	TAXIWAY	205	40,742	36	Very Poor
GIF	TAXIWAY B	TAXIWAY	210	48,281	64	Fair
GIF	TAXIWAY B	TAXIWAY	212	2,283	87	Good
GIF	TAXIWAY B	TAXIWAY	215	68,940	33	Very Poor
GIF	TAXIWAY B	TAXIWAY	225	28,746	87	Good
GIF	TAXIWAY B	TAXIWAY	230	12,000	86	Good
GIF	TAXIWAY B	TAXIWAY	270	13,236	62	Fair
GIF	TAXIWAY B	TAXIWAY	275	2,301	83	Satisfactory
GIF	TAXIWAY B1	TAXIWAY	240	10,879	71	Satisfactory
GIF	TAXIWAY B1	TAXIWAY	245	3,235	92	Good
GIF	TAXIWAY B2	TAXIWAY	250	8,852	41	Poor
GIF	TAXIWAY B2	TAXIWAY	255	2,494	89	Good
GIF	TAXIWAY B2	TAXIWAY	310	3,077	31	Very Poor
GIF	TAXIWAY B2	TAXIWAY	315	3,386	28	Very Poor
GIF	TAXIWAY B3	TAXIWAY	258	2,948	73	Satisfactory
GIF	TAXIWAY B3	TAXIWAY	260	12,078	56	Fair
GIF	TAXIWAY C	TAXIWAY	330	38,971	77	Satisfactory
GIF	TAXIWAY C3	TAXIWAY	305	22,138	60	Fair
GIF	TAXIWAY C3	TAXIWAY	307	2,704	90	Good
GIF	TAXIWAY D	TAXIWAY	420	31,033	64	Fair



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
GIF	TAXIWAY F	TAXIWAY	605	51,882	78	Satisfactory
GIF	TAXIWAY F1	TAXIWAY	610	7,988	85	Satisfactory
GIF	TAXIWAY F1	TAXIWAY	612	2,702	86	Good
GIF	TAXIWAY F2	TAXIWAY	615	7,725	89	Good
GIF	TAXIWAY F2	TAXIWAY	617	4,418	92	Good
GIF	TAXIWAY TO HANGAR	TAXIWAY	4605	9,405	15	Serious
GIF	APRON AREA	APRON	4105	161,696	49	Poor
GIF	APRON AREA	APRON	4110	174,018	41	Poor
GIF	APRON AREA	APRON	4115	32,078	35	Very Poor
GIF	APRON AREA	APRON	4120	49,139	52	Poor
GIF	APRON AREA	APRON	4123	17,601	72	Satisfactory
GIF	APRON AREA	APRON	4125	12,408	15	Serious
GIF	APRON T-HANGARS TAXILANES	APRON	4205	159,635	55	Poor
GIF	APRON T-HANGARS TAXILANES	APRON	4210	13,307	87	Good
GIF	APRON T-HANGARS TAXILANES	APRON	4305	43,314	57	Fair
GIF	APRON T-HANGARS TAXILANES	APRON	4310	19,911	40	Very Poor
GIF	APRON TO HANGAR	APRON	4405	23,666	47	Poor
GIF	APRON NORTH	APRON	4505	188,239	82	Satisfactory
GIF	APRON WEST	APRON	4705	37,020	12	Serious
GIF	TURNAROUND APRON RW 11-29	APRON	5105	11,639	50	Poor
GIF	TURNAROUND APRON RW 11-29	APRON	5110	11,131	50	Poor



Forecasted Pavement Condition Index 2018-2027

Table E-2 Pavement Condition Index Forecast 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
GIF	AP	4105	49	47	44	41	38	36	34	31	28	26	23
GIF	AP	4110	41	38	35	33	31	28	25	23	20	17	15
GIF	AP	4115	35	33	32	30	28	27	25	24	22	21	19
GIF	AP	4120	52	50	49	47	45	44	42	41	39	38	36
GIF	AP	4123	72	69	67	64	62	59	57	55	54	53	52
GIF	AP	4125	15	13	12	10	8	7	5	4	2	1	0
GIF	AP HANG	4405	47	45	44	42	40	39	37	36	34	33	31
GIF	AP N	4505	82	80	79	77	75	74	72	71	69	68	66
GIF	AP RW11-29	5105	50	48	46	43	40	37	35	33	30	27	25
GIF	AP RW11-29	5110	50	48	46	43	40	37	35	33	30	27	25
GIF	AP T-HANG	4205	55	53	52	50	48	47	45	44	42	41	39
GIF	AP T-HANG	4210	87	85	84	82	80	79	77	76	74	73	71
GIF	AP T-HANG	4305	57	55	54	52	50	49	47	46	44	43	41
GIF	AP T-HANG	4310	40	38	37	35	33	32	30	29	27	26	24
GIF	AP W	4705	12	10	9	7	5	4	2	1	0	0	0
GIF	RW 11-29	6205	65	63	62	62	61	61	60	60	60	60	60
GIF	RW 11-29	6210	86	84	81	79	76	74	71	69	67	66	64
GIF	RW 5-23	6105	81	78	76	74	71	69	67	66	64	63	62
GIF	RW 5-23	6110	88	86	83	81	78	76	73	71	69	67	65
GIF	RW 5-23	6115	85	82	80	78	75	73	71	68	67	65	64
GIF	RW 5-23	6117	89	87	86	84	82	81	79	77	76	74	73
GIF	RW 5-23	6120	82	79	77	75	72	70	68	66	65	63	62
GIF	RW 5-23	6122	87	85	84	82	80	79	77	75	74	72	71
GIF	TW A	110	63	61	60	58	56	55	53	51	50	48	47
GIF	TW A	115	37	35	34	33	32	31	30	30	29	28	27
GIF	TW A	320	51	49	48	46	44	43	41	40	38	37	35
GIF	TW A	405	51	49	48	47	45	45	44	44	43	43	43
GIF	TW A	410	32	28	24	20	16	12	9	5	1	0	0
GIF	TW A	417	58	56	54	53	51	49	48	47	46	45	44
GIF	TW A2	105	55	53	52	50	49	47	46	44	42	41	39
GIF	TW B	205	36	34	33	32	31	31	30	29	28	28	27
GIF	TW B	210	64	63	62	61	60	59	58	57	55	54	53
GIF	TW B	212	87	84	82	80	78	76	75	74	73	72	71
GIF	TW B	215	33	32	31	30	29	29	28	27	26	25	23
GIF	TW B	225	87	84	82	80	78	76	75	74	73	72	71



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
GIF	TW B	230	86	83	81	79	77	76	75	73	72	72	71
GIF	TW B	270	62	60	59	57	55	54	52	50	49	47	46
GIF	TW B	275	83	81	79	77	76	74	73	72	71	70	70
GIF	TW B1	240	71	70	69	68	67	66	65	64	62	61	59
GIF	TW B1	245	92	89	86	84	81	79	78	76	75	74	73
GIF	TW B2	250	41	39	38	36	35	34	33	32	31	30	29
GIF	TW B2	255	89	86	84	81	79	78	76	75	74	73	72
GIF	TW B2	310	31	27	23	19	16	12	8	4	0	0	0
GIF	TW B2	315	28	27	26	24	22	20	17	14	11	9	6
GIF	TW B3	258	73	72	71	70	69	68	67	66	65	64	62
GIF	TW B3	260	56	54	52	51	49	48	47	45	45	44	44
GIF	TW C	330	77	75	73	72	71	69	68	67	66	66	65
GIF	TW C3	305	60	58	56	55	53	51	50	48	47	46	45
GIF	TW C3	307	90	87	85	82	80	78	77	75	74	73	72
GIF	TW D	420	64	63	62	61	60	59	58	57	55	54	53
GIF	TW F	605	78	76	74	73	71	70	69	68	67	66	65
GIF	TW F1	610	85	83	80	78	76	75	73	72	70	69	68
GIF	TW F1	612	86	83	81	79	77	76	75	73	72	72	71
GIF	TW F2	615	89	86	84	82	80	77	76	74	72	71	70
GIF	TW F2	617	92	89	86	84	81	79	78	76	75	74	73
GIF	TW HANG	4605	15	12	10	7	4	2	0	0	0	0	0

Major Rehabilitation Planning 2018-2027


Table E-3 Major Rehabilitation Planning 2018-2027

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	GIF	AP	4105	AAC	161,696	47	AC Restoration	\$ 1,219,000.00
2018	GIF	AP	4110	AAC	174,018	38	AC Restoration	\$ 1,567,000.00
2018	GIF	AP	4115	AC	32,078	33	AC Reconstruction	\$ 289,000.00
2018	GIF	AP	4120	AC	49,139	50	AC Restoration	\$ 344,000.00
2018	GIF	AP	4125	AC	12,408	13	AC Reconstruction	\$ 112,000.00
2018	GIF	AP HANG	4405	AC	23,666	45	AC Restoration	\$ 187,000.00
2018	GIF	AP RW11-29	5105	AAC	11,639	48	AC Restoration	\$ 85,000.00
2018	GIF	AP RW11-29	5110	AAC	11,131	48	AC Restoration	\$ 82,000.00
2018	GIF	AP T-HANG	4205	AC	159,635	53	AC Restoration	\$ 1,118,000.00
2018	GIF	AP T-HANG	4305	AC	43,314	55	AC Restoration	\$ 304,000.00
2018	GIF	AP T-HANG	4310	AC	19,911	38	AC Reconstruction	\$ 180,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	GIF	AP W	4705	AC	37,020	10	AC Reconstruction	\$ 334,000.00
2018	GIF	RW 11-29	6205	AAC	367,600	63	AC Restoration	\$ 2,574,000.00
2018	GIF	TW A	110	AAC	62,789	61	AC Restoration	\$ 440,000.00
2018	GIF	TW A	115	AC	2,744	35	AC Reconstruction	\$ 25,000.00
2018	GIF	TW A	320	AC	23,750	49	AC Restoration	\$ 168,000.00
2018	GIF	TW A	405	AAC	7,000	49	AC Restoration	\$ 50,000.00
2018	GIF	TW A	410	AAC	43,255	28	AC Reconstruction	\$ 390,000.00
2018	GIF	TW A	417	AAC	10,400	56	AC Restoration	\$ 73,000.00
2018	GIF	TW A2	105	AC	8,491	53	AC Restoration	\$ 60,000.00
2018	GIF	TW B	205	AC	40,742	34	AC Reconstruction	\$ 367,000.00
2018	GIF	TW B	210	AC	48,281	63	AC Restoration	\$ 338,000.00
2018	GIF	TW B	215	AC	68,940	32	AC Reconstruction	\$ 621,000.00
2018	GIF	TW B	270	AAC	13,236	60	AC Restoration	\$ 93,000.00
2018	GIF	TW B2	250	AC	8,852	39	AC Restoration	\$ 80,000.00
2018	GIF	TW B2	310	AAC	3,077	27	AC Reconstruction	\$ 28,000.00
2018	GIF	TW B2	315	AC	3,386	27	AC Reconstruction	\$ 31,000.00
2018	GIF	TW B3	260	AAC	12,078	54	AC Restoration	\$ 85,000.00
2018	GIF	TW C3	305	AAC	22,138	58	AC Restoration	\$ 155,000.00
2018	GIF	TW D	420	AC	31,033	63	AC Restoration	\$ 218,000.00
2018	GIF	TW HANG	4605	AC	9,405	12	AC Reconstruction	\$ 85,000.00
2020	GIF	AP	4123	AAC	17,601	64	AC Restoration	\$ 124,000.00
2024	GIF	TW B1	240	AAC	10,879	64	AC Restoration	\$ 77,000.00
2025	GIF	RW 5-23	6105	AAC	182,500	64	AC Restoration	\$ 1,278,000.00
2026	GIF	RW 5-23	6120	AAC	17,500	63	AC Restoration	\$ 123,000.00
2026	GIF	TW B3	258	AAC	2,948	64	AC Restoration	\$ 21,000.00
2027	GIF	RW 11-29	6210	AAC	22,301	64	AC Restoration	\$ 157,000.00
2027	GIF	RW 5-23	6115	AAC	50,300	64	AC Restoration	\$ 353,000.00

*All planning cost values have been rounded to the nearest thousand-dollar.


*Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027*

Summary of Winter Haven's Gilbert Airport

Winter Haven's Gilbert Airport was inspected in March 2017 – the overall weighted PCI value was 63, a condition rating of Fair. The results of the maintenance, repair, and major rehabilitation analysis identified \$1,565,500 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$13,835,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$11,702,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.

Chapter 1





Chapter 1 – Introduction

1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating public-use airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.



1.3 Organization

1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."** Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys,"** evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."**

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- ▶ **Research and evaluation of existing record documentation** was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- ▶ **An update to the existing Network Definition Map** was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- ▶ **A functional pavement evaluation with PCI Survey inspections** was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- ▶ **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- ▶ **Maintenance, Repair, and Rehabilitation Planning** was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA **AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements."** Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.



1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA **AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."** The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.



1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and **150/5380-7B “Airport Pavement Management Program (PMP)”**). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.”

1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC **150/5380-7B “Airport Pavement Management Program (PMP)”** an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data




F. Pavement Performance Modeling for the Prediction/Forecast of PCI

G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements’ past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and cost-effective manner. **Figure 1.7-1 Typical Pavement Condition Life Cycle**, which is based on the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”** **Figure 1.7-1 Typical Pavement Condition Life Cycle**, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.

Figure 1.7-1 Typical Pavement Condition Life Cycle




**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).*

Figure 1.7-2 General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

Figure 1.7-2 General Pavement Treatments by Condition Range



Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7-1 and 1.7-2**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7-3 and Figure 1.7-4 depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.



Figure 1.7-3 Flexible Asphalt Concrete









	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figure 1.7-4 Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.




1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”
- FAA Advisory Circular 150/5380-7B 150/5380-7B “Airport Pavement Management Program.”
- FAA Advisory Circular 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”
- FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation.”
- Department of the Air Force, Air Force Civil Engineer Center “Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements.”
- Unified Facilities Criteria (UFC) 3-260-16FA 16 “Airfield Pavement Condition Survey Procedures Pavements.”
- Unified Facilities Criteria (UFC) 3-260-03 “Airfield Pavement Evaluation.”
- Pavement Management for Airports, Roads, and Parking Lots 2nd Edition, M.Y. Shahin.

Chapter 2





Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”**

2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.



A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a “parent” pavement network.

Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (± 8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ($\pm 2,000$ ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	“Tallahassee International Airport – Airfield Pavements”
Branch Name	Commonly defined asset name as established by Airport and by use	“Runway 18-36”
Branch ID	Codified shorthand name for commonly defined asset established for database identification	“RW 18-36” RW, Branch Use, “Runway” 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following: <ul style="list-style-type: none"> • Pavement Composition • Construction Work History • Aircraft Traffic • Condition Records 	“6105”
Sample Unit	A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	“300”



2.3 Airfield Pavement Structure

2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.



Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 6-inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.



2.4 Airfield Pavement Work History

2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

1. Location and Limits of Work.
2. Types and Severity of Distresses Repaired.
3. Type of Work.
4. Cost of Work.
5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.6 Airfield Pavement Condition Index (PCI) Survey

2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP),"** the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.



2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age



Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> Alligator Cracking Corrugation Depression Patching of Load-based distress Polished Aggregate Rutting Slippage Cracking 	<ul style="list-style-type: none"> Bleeding Block Cracking Joint Reflection Cracking L/T Cracking Patching of climate / durability-caused distresses Shoving from PCC Raveling Weathering Swelling 	<ul style="list-style-type: none"> Alligator Cracking Depression Patching of moisture / drainage caused distress Swelling Raveling Weathering 	<ul style="list-style-type: none"> Oil Spillage Jet Blast Erosion Polished Aggregate

Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> Corrugation Depression Rutting Shoving of asphalt pavement Swelling Raveling Weathering 	<ul style="list-style-type: none"> Bleeding Depression Polished Aggregate Rutting 	<ul style="list-style-type: none"> Block Cracking Joint Reflection Cracking L/T Cracking Slippage Cracking 	<ul style="list-style-type: none"> All Distresses



Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Blowup	Climate / ASR
Corner Break	Load Repetition / Curling Stresses
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
Durability Cracking	Freeze-Thaw Cycling
Joint Seal Damage	Material Deterioration / Construction Quality / Age
Small Patch	Pavement Repair
Large Patch/Utility Cut	Utility / Pavement Repair
Popout	Freeze-Thaw Cycling / ASR / Material Quality
Pumping	Load Repetition / Poor Joint Sealant
Scaling	Construction Quality / Freeze-Thaw Cycling
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer
Shattered Slab	Overloading
Shrinkage Cracking	Construction Quality / Climate
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction



Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> • Corner Break • Shattered Slab • L/T/D Cracking • Pumping • Patching of Load-associated distress • Spalling 	<ul style="list-style-type: none"> • Blowup • "D" Cracking • Joint Seal Damage • Popouts • Scaling • Patch of Climate/Durability-associated distress • Shrinkage Cracking • Spalling • L/T/D Cracking 	<ul style="list-style-type: none"> • Corner Break • Shattered Slab • Pumping • Patching of Moisture/Drainage-associated distress 	<ul style="list-style-type: none"> • Settlement / Faulting

Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> • Blowup • Corner Break • L/T/D Cracking • Shattered Slab • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Corner Break • L/T/D Cracking • "D" Cracking • Joint Seal Damage • Shattered Slab • Popouts • Scaling 	<ul style="list-style-type: none"> • All distresses



2.6.3 PCI Survey Inspection Procedures

Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤20	10% but ≤10

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤20	10% but ≤10



2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in an adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured “(52) Weathering and Raveling” distress has been separated into two distresses “(52) Raveling” and “(57) Weathering.” Previously, areas that were recorded as “Weathering and Raveling” were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where “Weathering” only exists and does not meet the definition of “Raveling,” the PCI deduction is not as high as the former “Weathering and Raveling.” Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling,” may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

Rigid Portland Cement Concrete Pavement Distress Updates


The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR.” As a result the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling,” and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, “(73) Shrinkage Cracks” has been redefined as “(73) Shrinkage Cracking”. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Distress Updates to Reflect ASTM 5340-12				
Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Cracking - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Cracking - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Cracking - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Cracking' may now be identified as 'Shrinkage Cracking'

Chapter 3





Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1-1** and **Figure 3.1.1-2** provides an inset view of the 2017 Airfield Pavement Network Definition Exhibit and the 2017 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.


Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Year	General Work Description
2018	TW E, TW F - New Construction: 4" P-401, 6" P-211, 8" P-154, 12" P-152
	TW E - New Construction: 2" P-401, 10" P-211, 12" P-152
	RW 5-23 Blast Pads - New Construction: 4" P-401, 6" P-211, 8" P-154, 12" P-152

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.




Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit



The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.



Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit




The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections since any major construction activity has occurred during the PCI Survey inspection. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.



Figure 3.1.2 Average Age of Pavements at Inspection




The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.



3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.

Figure 3.1.4 (a) Pavement Surface Type by Area (SF)



*Figure 3.1.4 (b) Pavement Surface Type by Area (%)*

3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
GIF	APRON AREA	AP	APRON	4105	250	650	161,696	AAC	1/1/1986
GIF	APRON AREA	AP	APRON	4110	680	250	174,018	AAC	1/1/1990
GIF	APRON AREA	AP	APRON	4115	250	130	32,078	AC	1/1/1960
GIF	APRON AREA	AP	APRON	4120	240	200	49,139	AC	1/1/1980
GIF	APRON AREA	AP	APRON	4123	200	100	17,601	AAC	1/1/1997
GIF	APRON AREA	AP	APRON	4125	250	50	12,408	AC	1/1/1980
GIF	APRON TO HANGAR	AP HANG	APRON	4405	210	160	23,666	AC	1/1/1995
GIF	APRON NORTH	AP N	APRON	4505	1650	100	188,239	AC	1/1/2011
GIF	TURNAROUND APRON RW 11-29	AP RW11-29	APRON	5105	200	60	11,639	AAC	1/1/1997
GIF	TURNAROUND APRON RW 11-29	AP RW11-29	APRON	5110	200	55	11,131	AAC	1/1/1997
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4205	6500	25	159,635	AC	1/1/1984
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4210	550	20	13,307	AC	1/1/2009
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4305	400	120	43,314	AC	1/1/1984
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4310	300	20	19,911	AC	1/1/1984
GIF	APRON WEST	AP W	APRON	4705	250	100	37,020	AC	1/1/1965
GIF	RUNWAY 11-29	RW 11-29	RUNWAY	6205	3673	100	367,600	AAC	1/1/1997
GIF	RUNWAY 11-29	RW 11-29	RUNWAY	6210	214	100	22,301	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6105	3650	50	182,500	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6110	3650	50	182,500	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6115	1000	100	50,300	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6117	1006	25	50,300	AC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6120	350	100	17,500	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6122	350	25	17,500	AC	1/1/2010
GIF	TAXIWAY A	TW A	TAXIWAY	110	11500	50	62,789	AAC	1/1/1997
GIF	TAXIWAY A	TW A	TAXIWAY	115	60	30	2,744	AC	1/1/1997



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
GIF	TAXIWAY A	TW A	TAXIWAY	320	500	50	23,750	AC	1/1/2002
GIF	TAXIWAY A	TW A	TAXIWAY	405	135	50	7,000	AAC	1/1/1997
GIF	TAXIWAY A	TW A	TAXIWAY	410	880	50	43,255	AAC	1/1/1960
GIF	TAXIWAY A	TW A	TAXIWAY	417	200	110	10,400	AAC	1/1/1997
GIF	TAXIWAY A2	TW A2	TAXIWAY	105	200	30	8,491	AC	1/1/1984
GIF	TAXIWAY B	TW B	TAXIWAY	205	975	40	40,742	AC	1/1/1985
GIF	TAXIWAY B	TW B	TAXIWAY	210	1225	35	48,281	AC	1/1/1991
GIF	TAXIWAY B	TW B	TAXIWAY	212	75	35	2,283	AAC	1/1/2010
GIF	TAXIWAY B	TW B	TAXIWAY	215	1600	40	68,940	AC	1/1/1985
GIF	TAXIWAY B	TW B	TAXIWAY	225	1014	45	28,746	AAC	1/1/2004
GIF	TAXIWAY B	TW B	TAXIWAY	230	300	40	12,000	AAC	1/1/2010
GIF	TAXIWAY B	TW B	TAXIWAY	270	255	50	13,236	AAC	1/1/1997
GIF	TAXIWAY B	TW B	TAXIWAY	275	45	50	2,301	AAC	1/1/2010
GIF	TAXIWAY B1	TW B1	TAXIWAY	240	250	45	10,879	AAC	1/1/2004
GIF	TAXIWAY B1	TW B1	TAXIWAY	245	70	45	3,235	AAC	1/1/2010
GIF	TAXIWAY B2	TW B2	TAXIWAY	250	175	50	8,852	AC	1/1/1985
GIF	TAXIWAY B2	TW B2	TAXIWAY	255	50	50	2,494	AAC	1/1/2010
GIF	TAXIWAY B2	TW B2	TAXIWAY	310	66	50	3,077	AAC	1/1/1970
GIF	TAXIWAY B2	TW B2	TAXIWAY	315	120	50	3,386	AC	1/1/1985
GIF	TAXIWAY B3	TW B3	TAXIWAY	258	50	50	2,948	AAC	1/1/1997
GIF	TAXIWAY B3	TW B3	TAXIWAY	260	105	50	12,078	AAC	1/1/1997
GIF	TAXIWAY C	TW C	TAXIWAY	330	1325	25	38,971	AC	1/9/1998
GIF	TAXIWAY C3	TW C3	TAXIWAY	305	450	50	22,138	AAC	1/1/1960
GIF	TAXIWAY C3	TW C3	TAXIWAY	307	50	50	2,704	AAC	1/1/2010
GIF	TAXIWAY D	TW D	TAXIWAY	420	1070	25	31,033	AC	1/9/1998
GIF	TAXIWAY F	TW F	TAXIWAY	605	843	35	51,882	AC	1/1/2009




Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
GIF	TAXIWAY F1	TW F1	TAXIWAY	610	200	40	7,988	AC	1/1/2009
GIF	TAXIWAY F1	TW F1	TAXIWAY	612	70	40	2,702	AAC	1/1/2010
GIF	TAXIWAY F2	TW F2	TAXIWAY	615	200	40	7,725	AC	1/1/2009
GIF	TAXIWAY F2	TW F2	TAXIWAY	617	110	40	4,418	AAC	1/1/2010
GIF	TAXIWAY TO HANGAR	TW HANG	TAXIWAY	4605	350	25	9,405	AC	1/1/1965



PAGE INTENTIONALLY LEFT BLANK

Chapter 4





Chapter 4 – Airfield Pavement Condition


The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

4.1 Airfield Pavement Condition Index (Latest Inspection)

4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.

Figure 4.1.1 Latest Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (c)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.



Figure 4.1.2 (a) Latest Condition – Runway Pavements




Figure 4.1.2 (b) Latest Condition – Taxiway Pavements







Figure 4.1.2 (c) Latest Condition – Apron Pavements





4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement.

Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.



Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
GIF	AP	APRON AREA	APRON	4105	161,696	AAC	49	Poor	93%	0%	7%	4	34
GIF	AP	APRON AREA	APRON	4110	174,018	AAC	41	Poor	94%	0%	6%	4	39
GIF	AP	APRON AREA	APRON	4115	32,078	AC	35	Very Poor	93%	0%	7%	1	9
GIF	AP	APRON AREA	APRON	4120	49,139	AC	52	Poor	100%	0%	0%	2	11
GIF	AP	APRON AREA	APRON	4123	17,601	AAC	72	Satisfactory	100%	0%	0%	1	4
GIF	AP	APRON AREA	APRON	4125	12,408	AC	15	Serious	62%	29%	9%	1	3
GIF	AP HANG	APRON TO HANGAR	APRON	4405	23,666	AC	47	Poor	96%	0%	4%	1	5
GIF	AP N	APRON NORTH	APRON	4505	188,239	AC	82	Satisfactory	60%	0%	40%	5	45
GIF	AP RW11-29	TURNAROUND APRON RW 11-29	APRON	5105	11,639	AAC	50	Poor	85%	0%	15%	1	2
GIF	AP RW11-29	TURNAROUND APRON RW 11-29	APRON	5110	11,131	AAC	50	Poor	86%	0%	14%	1	2
GIF	AP T-HANG	APRON T-HANGARS TAXILANES	APRON	4205	159,635	AC	55	Poor	77%	0%	23%	6	36
GIF	AP T-HANG	APRON T-HANGARS TAXILANES	APRON	4210	13,307	AC	87	Good	100%	0%	0%	1	3
GIF	AP T-HANG	APRON T-HANGARS TAXILANES	APRON	4305	43,314	AC	57	Fair	95%	0%	5%	1	10
GIF	AP T-HANG	APRON T-HANGARS TAXILANES	APRON	4310	19,911	AC	40	Very Poor	100%	0%	0%	1	4
GIF	AP W	APRON WEST	APRON	4705	37,020	AC	12	Serious	71%	22%	7%	1	7
GIF	RW 11-29	RUNWAY 11-29	RUNWAY	6205	367,600	AAC	65	Fair	98%	0%	2%	15	73
GIF	RW 11-29	RUNWAY 11-29	RUNWAY	6210	22,301	AAC	86	Good	100%	0%	0%	1	4
GIF	RW 5-23	RUNWAY 5-23	RUNWAY	6105	182,500	AAC	81	Satisfactory	88%	0%	12%	7	36
GIF	RW 5-23	RUNWAY 5-23	RUNWAY	6110	182,500	AAC	88	Good	78%	0%	22%	7	38
GIF	RW 5-23	RUNWAY 5-23	RUNWAY	6115	50,300	AAC	85	Satisfactory	100%	0%	0%	2	10
GIF	RW 5-23	RUNWAY 5-23	RUNWAY	6117	50,300	AC	89	Good	100%	0%	0%	3	12
GIF	RW 5-23	RUNWAY 5-23	RUNWAY	6120	17,500	AAC	82	Satisfactory	100%	0%	0%	1	4
GIF	RW 5-23	RUNWAY 5-23	RUNWAY	6122	17,500	AC	87	Good	100%	0%	0%	1	4
GIF	TW A	TAXIWAY A	TAXIWAY	110	62,789	AAC	63	Fair	100%	0%	0%	2	13
GIF	TW A	TAXIWAY A	TAXIWAY	115	2,744	AC	37	Very Poor	75%	0%	25%	1	1
GIF	TW A	TAXIWAY A	TAXIWAY	320	23,750	AC	51	Poor	100%	0%	0%	2	6
GIF	TW A	TAXIWAY A	TAXIWAY	405	7,000	AAC	51	Poor	100%	0%	0%	1	2
GIF	TW A	TAXIWAY A	TAXIWAY	410	43,255	AAC	32	Very Poor	100%	0%	0%	2	8
GIF	TW A	TAXIWAY A	TAXIWAY	417	10,400	AAC	58	Fair	100%	0%	0%	1	2
GIF	TW A2	TAXIWAY A2	TAXIWAY	105	8,491	AC	55	Poor	88%	0%	12%	1	2
GIF	TW B	TAXIWAY B	TAXIWAY	205	40,742	AC	36	Very Poor	100%	0%	0%	2	10
GIF	TW B	TAXIWAY B	TAXIWAY	210	48,281	AC	64	Fair	100%	0%	0%	3	14
GIF	TW B	TAXIWAY B	TAXIWAY	212	2,283	AAC	87	Good	100%	0%	0%	1	1
GIF	TW B	TAXIWAY B	TAXIWAY	215	68,940	AC	33	Very Poor	100%	0%	0%	3	17
GIF	TW B	TAXIWAY B	TAXIWAY	225	28,746	AAC	87	Good	100%	0%	0%	1	7
GIF	TW B	TAXIWAY B	TAXIWAY	230	12,000	AAC	86	Good	99%	0%	1%	1	3




Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
GIF	TW B	TAXIWAY B	TAXIWAY	270	13,236	AAC	62	Fair	100%	0%	0%	1	3
GIF	TW B	TAXIWAY B	TAXIWAY	275	2,301	AAC	83	Satisfactory	100%	0%	0%	1	1
GIF	TW B1	TAXIWAY B1	TAXIWAY	240	10,879	AAC	71	Satisfactory	100%	0%	0%	1	3
GIF	TW B1	TAXIWAY B1	TAXIWAY	245	3,235	AAC	92	Good	100%	0%	0%	1	1
GIF	TW B2	TAXIWAY B2	TAXIWAY	250	8,852	AC	41	Poor	100%	0%	0%	1	2
GIF	TW B2	TAXIWAY B2	TAXIWAY	255	2,494	AAC	89	Good	100%	0%	0%	1	1
GIF	TW B2	TAXIWAY B2	TAXIWAY	310	3,077	AAC	31	Very Poor	98%	0%	2%	1	1
GIF	TW B2	TAXIWAY B2	TAXIWAY	315	3,386	AC	28	Very Poor	91%	0%	9%	1	1
GIF	TW B3	TAXIWAY B3	TAXIWAY	258	2,948	AAC	73	Satisfactory	100%	0%	0%	1	1
GIF	TW B3	TAXIWAY B3	TAXIWAY	260	12,078	AAC	56	Fair	82%	0%	18%	1	2
GIF	TW C	TAXIWAY C	TAXIWAY	330	38,971	AC	77	Satisfactory	100%	0%	0%	1	8
GIF	TW C3	TAXIWAY C3	TAXIWAY	305	22,138	AAC	60	Fair	100%	0%	0%	2	5
GIF	TW C3	TAXIWAY C3	TAXIWAY	307	2,704	AAC	90	Good	100%	0%	0%	1	1
GIF	TW D	TAXIWAY D	TAXIWAY	420	31,033	AC	64	Fair	100%	0%	0%	1	6
GIF	TW F	TAXIWAY F	TAXIWAY	605	51,882	AC	78	Satisfactory	66%	0%	34%	2	12
GIF	TW F1	TAXIWAY F1	TAXIWAY	610	7,988	AC	85	Satisfactory	100%	0%	0%	1	2
GIF	TW F1	TAXIWAY F1	TAXIWAY	612	2,702	AAC	86	Good	100%	0%	0%	1	1
GIF	TW F2	TAXIWAY F2	TAXIWAY	615	7,725	AC	89	Good	92%	0%	8%	1	2
GIF	TW F2	TAXIWAY F2	TAXIWAY	617	4,418	AAC	92	Good	100%	0%	0%	1	1
GIF	TW HANG	TAXIWAY TO HANGAR	TAXIWAY	4605	9,405	AC	15	Serious	48%	52%	0%	1	2



Figure 4.1.3 is an inset view of the 2017 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits**.

Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit





4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The field PCI Survey performed at Winter Haven's Gilbert Airport (GIF) started on 03/08/2017 and was completed on 03/09/2017. The resulting overall average area-weighted PCI value was 63 representing a condition rating of Fair. Two runways service Winter Haven's Gilbert Airport: Runway 05-23 is 100-ft wide and 5,006-ft long, Runway 11-29 is 100-ft wide and 4,001-ft long.

Based on the FAA 5010 Report as of 07/12/2017 the Airport has reported 76,200 operations for 12 months ending 08/16/2016.

4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

Runway 05-23

Runway 05-23 consists of 6 sections constructed of AC and AAC. The last construction year for Runway 05-23 was 2010. The average area-weighted PCI for Runway 05-23 is 85 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Runway 05-23 consist of Bleeding, Longitudinal & Transverse Cracking, Raveling, and Weathering.

Runway 11-29

Runway 11-29 consists of 2 sections constructed of AAC. The last construction years range from 1997 to 2010. The average area-weighted PCI for Runway 11-29 is 66 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Runway 11-29 consist of Depression, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Taxiway A

Taxiway A consists of 6 sections constructed of AC and AAC. The last construction years range from 1960 to 2002. The average area-weighted PCI for Taxiway A is 50 representing a Poor condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Taxiway A consist of Bleeding, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Shoving, Swelling, and Weathering.

Taxiway B

Taxiway B consists of 8 sections constructed of AC and AAC. The last construction years range from 1985 to 2010. The average area-weighted PCI for Taxiway B is 53 representing a Poor condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Taxiway B consist of Bleeding, Block Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, and Weathering.



Taxiway to Hangar

Taxiway to Hangar consists of 1 section constructed of AC. The last construction year for Taxiway to Hangar was 1965. The average area-weighted PCI for Taxiway to Hangar is 15 representing a Serious condition rating. The pavement distresses observed were related to Climate and Load distress classifications. Distresses observed in Taxiway to Hangar consist of Alligator Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, and Rutting.

Apron West

Apron West consists of 1 section constructed of AC. The last construction year for Apron West was 1965. The average area-weighted PCI for Apron West is 12 representing a Serious condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Apron West consist of Alligator Cracking, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, and Raveling.

Apron

The Apron consists of 6 sections constructed of AC and AAC. The last construction years range from 1960 to 1997. The average area-weighted PCI for the Apron is 45 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in the Apron consist of Alligator Cracking, Bleeding, Block Cracking, Depression, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Swelling, and Weathering.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Average Area-Weighted PCI	Condition Rating
Runway	76	Satisfactory
Taxiway	58	Fair
Apron	53	Poor



4.3 Forecasted Pavement Conditions

4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to develop forecasted PCI values based on historic trends and statistical models.

4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2018 through January 2027.

Figure 4.3.2 (a) Forecasted Runway Pavement Performance






Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance





4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.



Table 4.3.3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
GIF	AP	4105	49	47	44	41	38	36	34	31	28	26	23
GIF	AP	4110	41	38	35	33	31	28	25	23	20	17	15
GIF	AP	4115	35	33	32	30	28	27	25	24	22	21	19
GIF	AP	4120	52	50	49	47	45	44	42	41	39	38	36
GIF	AP	4123	72	69	67	64	62	59	57	55	54	53	52
GIF	AP	4125	15	13	12	10	8	7	5	4	2	1	0
GIF	AP HANG	4405	47	45	44	42	40	39	37	36	34	33	31
GIF	AP N	4505	82	80	79	77	75	74	72	71	69	68	66
GIF	AP RW11-29	5105	50	48	46	43	40	37	35	33	30	27	25
GIF	AP RW11-29	5110	50	48	46	43	40	37	35	33	30	27	25
GIF	AP T-HANG	4205	55	53	52	50	48	47	45	44	42	41	39
GIF	AP T-HANG	4210	87	85	84	82	80	79	77	76	74	73	71
GIF	AP T-HANG	4305	57	55	54	52	50	49	47	46	44	43	41
GIF	AP T-HANG	4310	40	38	37	35	33	32	30	29	27	26	24
GIF	AP W	4705	12	10	9	7	5	4	2	1	0	0	0
GIF	RW 11-29	6205	65	63	62	62	61	61	60	60	60	60	60
GIF	RW 11-29	6210	86	84	81	79	76	74	71	69	67	66	64
GIF	RW 5-23	6105	81	78	76	74	71	69	67	66	64	63	62
GIF	RW 5-23	6110	88	86	83	81	78	76	73	71	69	67	65
GIF	RW 5-23	6115	85	82	80	78	75	73	71	68	67	65	64
GIF	RW 5-23	6117	89	87	86	84	82	81	79	77	76	74	73
GIF	RW 5-23	6120	82	79	77	75	72	70	68	66	65	63	62
GIF	RW 5-23	6122	87	85	84	82	80	79	77	75	74	72	71
GIF	TW A	110	63	61	60	58	56	55	53	51	50	48	47
GIF	TW A	115	37	35	34	33	32	31	30	30	29	28	27



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
GIF	TW A	320	51	49	48	46	44	43	41	40	38	37	35
GIF	TW A	405	51	49	48	47	45	45	44	44	43	43	43
GIF	TW A	410	32	28	24	20	16	12	9	5	1	0	0
GIF	TW A	417	58	56	54	53	51	49	48	47	46	45	44
GIF	TW A2	105	55	53	52	50	49	47	46	44	42	41	39
GIF	TW B	205	36	34	33	32	31	31	30	29	28	28	27
GIF	TW B	210	64	63	62	61	60	59	58	57	55	54	53
GIF	TW B	212	87	84	82	80	78	76	75	74	73	72	71
GIF	TW B	215	33	32	31	30	29	29	28	27	26	25	23
GIF	TW B	225	87	84	82	80	78	76	75	74	73	72	71
GIF	TW B	230	86	83	81	79	77	76	75	73	72	72	71
GIF	TW B	270	62	60	59	57	55	54	52	50	49	47	46
GIF	TW B	275	83	81	79	77	76	74	73	72	71	70	70
GIF	TW B1	240	71	70	69	68	67	66	65	64	62	61	59
GIF	TW B1	245	92	89	86	84	81	79	78	76	75	74	73
GIF	TW B2	250	41	39	38	36	35	34	33	32	31	30	29
GIF	TW B2	255	89	86	84	81	79	78	76	75	74	73	72
GIF	TW B2	310	31	27	23	19	16	12	8	4	0	0	0
GIF	TW B2	315	28	27	26	24	22	20	17	14	11	9	6
GIF	TW B3	258	73	72	71	70	69	68	67	66	65	64	62
GIF	TW B3	260	56	54	52	51	49	48	47	45	45	44	44
GIF	TW C	330	77	75	73	72	71	69	68	67	66	66	65
GIF	TW C3	305	60	58	56	55	53	51	50	48	47	46	45
GIF	TW C3	307	90	87	85	82	80	78	77	75	74	73	72
GIF	TW D	420	64	63	62	61	60	59	58	57	55	54	53
GIF	TW F	605	78	76	74	73	71	70	69	68	67	66	65
GIF	TW F1	610	85	83	80	78	76	75	73	72	70	69	68




Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
GIF	TW F1	612	86	83	81	79	77	76	75	73	72	72	71
GIF	TW F2	615	89	86	84	82	80	77	76	74	72	71	70
GIF	TW F2	617	92	89	86	84	81	79	78	76	75	74	73
GIF	TW HANG	4605	15	12	10	7	4	2	0	0	0	0	0



4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA **AC 150/5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements** to determine structural and/or functional conditions at the time of project.

Chapter 5





Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- **Localized Maintenance and Repair** includes patching and crack sealing.
- **Global Treatments** includes surface seals and rejuvenators (flexible pavements).
- **Major Rehabilitation** includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distress pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety (“stopgap”) measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.



5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2.1** and **Table 5.2.2**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA **AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements"** and the **FDOT Airfield Pavement Distress Repair Manual**. Additionally, the **Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements** was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	High	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft



Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L & T CR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt



Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$6.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$3.00	SqFt

Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$100.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in **5.2 Localized M&R Policy**. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. **Appendix B** provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to near-term Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3-1** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	3,665	SqFt	\$ 21,990.00
FDOT - SURFACE SEAL	PREVENTIVE	22,520	SqFt	\$ 12,390.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	280,970	SqFt	\$ 842,910.00
FDOT - SURFACE SEAL	STOPGAP	950,105	SqFt	\$ 522,560.00
FDOT - CRACK SEALING - AC	STOPGAP	23,800	Ft	\$ 71,400.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	15,370	SqFt	\$ 92,220.00
FDOT - MILLING - AC	STOPGAP	1,015	SqFt	\$ 2,030.00



The following **Table 5.3-2** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved “End Condition” of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
GIF	AP	4105	161,696	49	61	\$ 111,970.00
GIF	AP	4110	174,018	41	54	\$ 247,060.00
GIF	AP	4115	32,078	35	59	\$ 32,140.00
GIF	AP	4120	49,139	52	59	\$ 33,060.00
GIF	AP	4123	17,601	72	77	\$ 490.00
GIF	AP	4125	12,408	15	53	\$ 41,890.00
GIF	AP HANG	4405	23,666	47	57	\$ 4,250.00
GIF	AP N	4505	188,239	82	87	\$ 17,540.00
GIF	AP RW11-29	5105	11,639	50	56	\$ 2,160.00
GIF	AP RW11-29	5110	11,131	50	63	\$ 4,580.00
GIF	AP T-HANG	4205	159,635	55	75	\$ 108,790.00
GIF	AP T-HANG	4210	13,307	87	91	\$ 150.00
GIF	AP T-HANG	4305	43,314	57	78	\$ 39,580.00
GIF	AP T-HANG	4310	19,911	40	59	\$ 40,230.00
GIF	AP W	4705	37,020	12	49	\$ 150,110.00
GIF	RW 11-29	6205	367,600	65	78	\$ 135,670.00
GIF	RW 11-29	6210	22,301	86	86	\$ -
GIF	RW 5-23	6105	182,500	81	87	\$ 4,740.00
GIF	RW 5-23	6110	182,500	88	88	\$ 80.00
GIF	RW 5-23	6115	50,300	85	90	\$ 1,390.00
GIF	RW 5-23	6117	50,300	89	93	\$ 550.00
GIF	RW 5-23	6120	17,500	82	87	\$ 490.00
GIF	RW 5-23	6122	17,500	87	91	\$ 200.00
GIF	TW A	110	62,789	63	71	\$ 4,510.00
GIF	TW A	115	2,744	37	61	\$ 5,020.00
GIF	TW A	320	23,750	51	61	\$ 18,060.00
GIF	TW A	405	7,000	51	58	\$ 4,820.00
GIF	TW A	410	43,255	32	58	\$ 78,300.00
GIF	TW A	417	10,400	58	63	\$ 290.00
GIF	TW A2	105	8,491	55	74	\$ 7,790.00
GIF	TW B	205	40,742	36	57	\$ 93,120.00
GIF	TW B	210	48,281	64	77	\$ 34,610.00
GIF	TW B	212	2,283	87	91	\$ 30.00



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
GIF	TW B	215	68,940	33	57	\$ 206,830.00
GIF	TW B	225	28,746	87	90	\$ 160.00
GIF	TW B	230	12,000	86	91	\$ 200.00
GIF	TW B	270	13,236	62	77	\$ 8,080.00
GIF	TW B	275	2,301	83	87	\$ 30.00
GIF	TW B1	240	10,879	71	76	\$ 300.00
GIF	TW B1	245	3,235	92	92	\$ -
GIF	TW B2	250	8,852	41	61	\$ 20,060.00
GIF	TW B2	255	2,494	89	89	\$ -
GIF	TW B2	310	3,077	31	55	\$ 9,240.00
GIF	TW B2	315	3,386	28	57	\$ 10,640.00
GIF	TW B3	258	2,948	73	80	\$ 120.00
GIF	TW B3	260	12,078	56	80	\$ 9,290.00
GIF	TW C	330	38,971	77	82	\$ 1,080.00
GIF	TW C3	305	22,138	60	86	\$ 12,470.00
GIF	TW C3	307	2,704	90	90	\$ -
GIF	TW D	420	31,033	64	82	\$ 18,600.00
GIF	TW F	605	51,882	78	87	\$ 6,550.00
GIF	TW F1	610	7,988	85	90	\$ 110.00
GIF	TW F1	612	2,702	86	89	\$ 30.00
GIF	TW F2	615	7,725	89	88	\$ 230.00
GIF	TW F2	617	4,418	92	94	\$ 20.00
GIF	TW HANG	4605	9,405	15	44	\$ 38,350.00




The following **Table 5.3-3** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-3 Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 34,380.00
Stopgap	\$ 1,531,120.00
<i>Planning-Level Localized M&R Needs =</i>	<i>\$ 1,565,500.00</i>

Chapter 6





Chapter 6 – Major Rehabilitation Planning

6.1 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1-1 and 6.1-2** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, $PCI \leq \text{Critical PCI}$







Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, $PCI > \text{Critical } PCI$





6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The **Critical PCI** concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

1. Develop a pavement performance model and refine a prediction model for the pavements considered.
2. Select a localized maintenance and repair policy to be used in developing a work plan.
3. Apply the selected localized policy to the pavement sections for a range of PCI.
4. Compute the unit cost per area for each PCI range.
5. Plot the cost versus the PCI.
6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended **Minimum Service-Level PCI** for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	60	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)



6.2 Major Rehabilitation Policy

6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA **AC 150/ 5320-6F "Airport Pavement Design and Evaluation."** It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following **Tables 6.2.1 (a) and (b)** provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average GA Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete

Rehabilitation Type	General Aviation (GA) Airport
AC Restoration <i>Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.</i> PCI = 41 to 65	75% Mill and Overlay P-101 AC Milling (2") P-603 Bituminous Tack P-401 (HMA) (2") 25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2") <i>Excludes any paved shoulder features.</i>
AC Reconstruction <i>Full-depth asphalt pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2") <i>Excludes any paved shoulder features.</i>



Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete

Rehabilitation Type	General Aviation (GA) Airport
PCC Restoration <i>Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.</i> PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (10") *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction <i>Full-depth rigid pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (6") P-501 Rigid PCC (10")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs



provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Flexible Asphalt Concrete Cost Per SF	Rigid Portland Cement Concrete Cost per SF
Restoration	41 to 65	\$ 7.00	\$ 10.00
Reconstruction	0 to 40	\$ 9.00	\$ 15.00

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.



Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	GIF	AP	4105	AAC	161,696	47	AC Restoration	\$ 1,219,000.00
2018	GIF	AP	4110	AAC	174,018	38	AC Restoration	\$ 1,567,000.00
2018	GIF	AP	4115	AC	32,078	33	AC Reconstruction	\$ 289,000.00
2018	GIF	AP	4120	AC	49,139	50	AC Restoration	\$ 344,000.00
2018	GIF	AP	4125	AC	12,408	13	AC Reconstruction	\$ 112,000.00
2018	GIF	AP HANG	4405	AC	23,666	45	AC Restoration	\$ 187,000.00
2018	GIF	AP RW11-29	5105	AAC	11,639	48	AC Restoration	\$ 85,000.00
2018	GIF	AP RW11-29	5110	AAC	11,131	48	AC Restoration	\$ 82,000.00
2018	GIF	AP T-HANG	4205	AC	159,635	53	AC Restoration	\$ 1,118,000.00
2018	GIF	AP T-HANG	4305	AC	43,314	55	AC Restoration	\$ 304,000.00
2018	GIF	AP T-HANG	4310	AC	19,911	38	AC Reconstruction	\$ 180,000.00
2018	GIF	AP W	4705	AC	37,020	10	AC Reconstruction	\$ 334,000.00
2018	GIF	RW 11-29	6205	AAC	367,600	63	AC Restoration	\$ 2,574,000.00
2018	GIF	TW A	110	AAC	62,789	61	AC Restoration	\$ 440,000.00
2018	GIF	TW A	115	AC	2,744	35	AC Reconstruction	\$ 25,000.00
2018	GIF	TW A	320	AC	23,750	49	AC Restoration	\$ 168,000.00
2018	GIF	TW A	405	AAC	7,000	49	AC Restoration	\$ 50,000.00
2018	GIF	TW A	410	AAC	43,255	28	AC Reconstruction	\$ 390,000.00
2018	GIF	TW A	417	AAC	10,400	56	AC Restoration	\$ 73,000.00
2018	GIF	TW A2	105	AC	8,491	53	AC Restoration	\$ 60,000.00
2018	GIF	TW B	205	AC	40,742	34	AC Reconstruction	\$ 367,000.00
2018	GIF	TW B	210	AC	48,281	63	AC Restoration	\$ 338,000.00
2018	GIF	TW B	215	AC	68,940	32	AC Reconstruction	\$ 621,000.00
2018	GIF	TW B	270	AAC	13,236	60	AC Restoration	\$ 93,000.00
2018	GIF	TW B2	250	AC	8,852	39	AC Restoration	\$ 80,000.00
2018	GIF	TW B2	310	AAC	3,077	27	AC Reconstruction	\$ 28,000.00
2018	GIF	TW B2	315	AC	3,386	27	AC Reconstruction	\$ 31,000.00
2018	GIF	TW B3	260	AAC	12,078	54	AC Restoration	\$ 85,000.00
2018	GIF	TW C3	305	AAC	22,138	58	AC Restoration	\$ 155,000.00
2018	GIF	TW D	420	AC	31,033	63	AC Restoration	\$ 218,000.00
2018	GIF	TW HANG	4605	AC	9,405	12	AC Reconstruction	\$ 85,000.00
2020	GIF	AP	4123	AAC	17,601	64	AC Restoration	\$ 124,000.00
2024	GIF	TW B1	240	AAC	10,879	64	AC Restoration	\$ 77,000.00
2025	GIF	RW 5-23	6105	AAC	182,500	64	AC Restoration	\$ 1,278,000.00
2026	GIF	RW 5-23	6120	AAC	17,500	63	AC Restoration	\$ 123,000.00
2026	GIF	TW B3	258	AAC	2,948	64	AC Restoration	\$ 21,000.00
2027	GIF	RW 11-29	6210	AAC	22,301	64	AC Restoration	\$ 157,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2027	GIF	RW 5-23	6115	AAC	50,300	64	AC Restoration	\$ 353,000.00

**All values have been rounded to the nearest thousand-dollar.*

The following **Figure 6.3.1-1** summarizes the section-level major rehabilitation needs for a 10-year period between 2018 and 2027. **Figure 6.3.1-2** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.

Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year






Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit



Chapter 7





Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and re-inspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2018-2027. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- ▶ Develop a detailed preventive maintenance program for the airport.
- ▶ Further refine and implement the identified 10-year major rehabilitation needs.
- ▶ Maintain detailed records on pavement maintenance, construction, and inspection.
- ▶ Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



7.2 Supporting Documents

001 – Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

002 – Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the **Airport Response Form** provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

003 – Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

004 – Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation**. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.



7.3 Conclusion

The FDOT SAPMP Update Phase 1 2016-2017 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars **150/5380-7B “Airport Pavement Management Program (PMP)”** and **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** FDOT’s implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Appendix A

Airfield Pavement Analysis Tables



Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
GIF	APRON AREA	AP	APRON	4105	250	650	161,696	AAC	1/1/1986
GIF	APRON AREA	AP	APRON	4110	680	250	174,018	AAC	1/1/1990
GIF	APRON AREA	AP	APRON	4115	250	130	32,078	AC	1/1/1960
GIF	APRON AREA	AP	APRON	4120	240	200	49,139	AC	1/1/1980
GIF	APRON AREA	AP	APRON	4123	200	100	17,601	AAC	1/1/1997
GIF	APRON AREA	AP	APRON	4125	250	50	12,408	AC	1/1/1980
GIF	APRON TO HANGAR	AP HANG	APRON	4405	210	160	23,666	AC	1/1/1995
GIF	APRON NORTH	AP N	APRON	4505	1650	100	188,239	AC	1/1/2011
GIF	TURNAROUND APRON RW 11-29	AP RW11-29	APRON	5105	200	60	11,639	AAC	1/1/1997
GIF	TURNAROUND APRON RW 11-29	AP RW11-29	APRON	5110	200	55	11,131	AAC	1/1/1997
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4205	6500	25	159,635	AC	1/1/1984
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4210	550	20	13,307	AC	1/1/2009
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4305	400	120	43,314	AC	1/1/1984
GIF	APRON T-HANGARS TAXILANES	AP T-HANG	APRON	4310	300	20	19,911	AC	1/1/1984
GIF	APRON WEST	AP W	APRON	4705	250	100	37,020	AC	1/1/1965
GIF	RUNWAY 11-29	RW 11-29	RUNWAY	6205	3673	100	367,600	AAC	1/1/1997
GIF	RUNWAY 11-29	RW 11-29	RUNWAY	6210	214	100	22,301	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6105	3650	50	182,500	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6110	3650	50	182,500	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6115	1000	100	50,300	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6117	1006	25	50,300	AC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6120	350	100	17,500	AAC	1/1/2010
GIF	RUNWAY 5-23	RW 5-23	RUNWAY	6122	350	25	17,500	AC	1/1/2010
GIF	TAXIWAY A	TW A	TAXIWAY	110	11500	50	62,789	AAC	1/1/1997
GIF	TAXIWAY A	TW A	TAXIWAY	115	60	30	2,744	AC	1/1/1997
GIF	TAXIWAY A	TW A	TAXIWAY	320	500	50	23,750	AC	1/1/2002
GIF	TAXIWAY A	TW A	TAXIWAY	405	135	50	7,000	AAC	1/1/1997
GIF	TAXIWAY A	TW A	TAXIWAY	410	880	50	43,255	AAC	1/1/1960
GIF	TAXIWAY A	TW A	TAXIWAY	417	200	110	10,400	AAC	1/1/1997
GIF	TAXIWAY A2	TW A2	TAXIWAY	105	200	30	8,491	AC	1/1/1984
GIF	TAXIWAY B	TW B	TAXIWAY	205	975	40	40,742	AC	1/1/1985
GIF	TAXIWAY B	TW B	TAXIWAY	210	1225	35	48,281	AC	1/1/1991
GIF	TAXIWAY B	TW B	TAXIWAY	212	75	35	2,283	AAC	1/1/2010
GIF	TAXIWAY B	TW B	TAXIWAY	215	1600	40	68,940	AC	1/1/1985
GIF	TAXIWAY B	TW B	TAXIWAY	225	1014	45	28,746	AAC	1/1/2004
GIF	TAXIWAY B	TW B	TAXIWAY	230	300	40	12,000	AAC	1/1/2010



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
GIF	TAXIWAY B	TW B	TAXIWAY	270	255	50	13,236	AAC	1/1/1997
GIF	TAXIWAY B	TW B	TAXIWAY	275	45	50	2,301	AAC	1/1/2010
GIF	TAXIWAY B1	TW B1	TAXIWAY	240	250	45	10,879	AAC	1/1/2004
GIF	TAXIWAY B1	TW B1	TAXIWAY	245	70	45	3,235	AAC	1/1/2010
GIF	TAXIWAY B2	TW B2	TAXIWAY	250	175	50	8,852	AC	1/1/1985
GIF	TAXIWAY B2	TW B2	TAXIWAY	255	50	50	2,494	AAC	1/1/2010
GIF	TAXIWAY B2	TW B2	TAXIWAY	310	66	50	3,077	AAC	1/1/1970
GIF	TAXIWAY B2	TW B2	TAXIWAY	315	120	50	3,386	AC	1/1/1985
GIF	TAXIWAY B3	TW B3	TAXIWAY	258	50	50	2,948	AAC	1/1/1997
GIF	TAXIWAY B3	TW B3	TAXIWAY	260	105	50	12,078	AAC	1/1/1997
GIF	TAXIWAY C	TW C	TAXIWAY	330	1325	25	38,971	AC	1/9/1998
GIF	TAXIWAY C3	TW C3	TAXIWAY	305	450	50	22,138	AAC	1/1/1960
GIF	TAXIWAY C3	TW C3	TAXIWAY	307	50	50	2,704	AAC	1/1/2010
GIF	TAXIWAY D	TW D	TAXIWAY	420	1070	25	31,033	AC	1/9/1998
GIF	TAXIWAY F	TW F	TAXIWAY	605	843	35	51,882	AC	1/1/2009
GIF	TAXIWAY F1	TW F1	TAXIWAY	610	200	40	7,988	AC	1/1/2009
GIF	TAXIWAY F1	TW F1	TAXIWAY	612	70	40	2,702	AAC	1/1/2010
GIF	TAXIWAY F2	TW F2	TAXIWAY	615	200	40	7,725	AC	1/1/2009
GIF	TAXIWAY F2	TW F2	TAXIWAY	617	110	40	4,418	AAC	1/1/2010
GIF	TAXIWAY TO HANGAR	TW HANG	TAXIWAY	4605	350	25	9,405	AC	1/1/1965



Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
GIF	RUNWAY 5-23	RUNWAY	6105	182,500	81	Satisfactory
GIF	RUNWAY 5-23	RUNWAY	6110	182,500	88	Good
GIF	RUNWAY 5-23	RUNWAY	6115	50,300	85	Satisfactory
GIF	RUNWAY 5-23	RUNWAY	6117	50,300	89	Good
GIF	RUNWAY 5-23	RUNWAY	6120	17,500	82	Satisfactory
GIF	RUNWAY 5-23	RUNWAY	6122	17,500	87	Good
GIF	RUNWAY 11-29	RUNWAY	6205	367,600	65	Fair
GIF	RUNWAY 11-29	RUNWAY	6210	22,301	86	Good
GIF	TAXIWAY A	TAXIWAY	110	62,789	63	Fair
GIF	TAXIWAY A	TAXIWAY	115	2,744	37	Very Poor
GIF	TAXIWAY A	TAXIWAY	320	23,750	51	Poor
GIF	TAXIWAY A	TAXIWAY	405	7,000	51	Poor
GIF	TAXIWAY A	TAXIWAY	410	43,255	32	Very Poor
GIF	TAXIWAY A	TAXIWAY	417	10,400	58	Fair
GIF	TAXIWAY A2	TAXIWAY	105	8,491	55	Poor
GIF	TAXIWAY B	TAXIWAY	205	40,742	36	Very Poor
GIF	TAXIWAY B	TAXIWAY	210	48,281	64	Fair
GIF	TAXIWAY B	TAXIWAY	212	2,283	87	Good
GIF	TAXIWAY B	TAXIWAY	215	68,940	33	Very Poor
GIF	TAXIWAY B	TAXIWAY	225	28,746	87	Good
GIF	TAXIWAY B	TAXIWAY	230	12,000	86	Good
GIF	TAXIWAY B	TAXIWAY	270	13,236	62	Fair
GIF	TAXIWAY B	TAXIWAY	275	2,301	83	Satisfactory
GIF	TAXIWAY B1	TAXIWAY	240	10,879	71	Satisfactory
GIF	TAXIWAY B1	TAXIWAY	245	3,235	92	Good
GIF	TAXIWAY B2	TAXIWAY	250	8,852	41	Poor
GIF	TAXIWAY B2	TAXIWAY	255	2,494	89	Good
GIF	TAXIWAY B2	TAXIWAY	310	3,077	31	Very Poor
GIF	TAXIWAY B2	TAXIWAY	315	3,386	28	Very Poor
GIF	TAXIWAY B3	TAXIWAY	258	2,948	73	Satisfactory
GIF	TAXIWAY B3	TAXIWAY	260	12,078	56	Fair
GIF	TAXIWAY C	TAXIWAY	330	38,971	77	Satisfactory
GIF	TAXIWAY C3	TAXIWAY	305	22,138	60	Fair
GIF	TAXIWAY C3	TAXIWAY	307	2,704	90	Good
GIF	TAXIWAY D	TAXIWAY	420	31,033	64	Fair
GIF	TAXIWAY F	TAXIWAY	605	51,882	78	Satisfactory
GIF	TAXIWAY F1	TAXIWAY	610	7,988	85	Satisfactory
GIF	TAXIWAY F1	TAXIWAY	612	2,702	86	Good



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
GIF	TAXIWAY F2	TAXIWAY	615	7,725	89	Good
GIF	TAXIWAY F2	TAXIWAY	617	4,418	92	Good
GIF	TAXIWAY TO HANGAR	TAXIWAY	4605	9,405	15	Serious
GIF	APRON AREA	APRON	4105	161,696	49	Poor
GIF	APRON AREA	APRON	4110	174,018	41	Poor
GIF	APRON AREA	APRON	4115	32,078	35	Very Poor
GIF	APRON AREA	APRON	4120	49,139	52	Poor
GIF	APRON AREA	APRON	4123	17,601	72	Satisfactory
GIF	APRON AREA	APRON	4125	12,408	15	Serious
GIF	APRON T-HANGARS TAXILANES	APRON	4205	159,635	55	Poor
GIF	APRON T-HANGARS TAXILANES	APRON	4210	13,307	87	Good
GIF	APRON T-HANGARS TAXILANES	APRON	4305	43,314	57	Fair
GIF	APRON T-HANGARS TAXILANES	APRON	4310	19,911	40	Very Poor
GIF	APRON TO HANGAR	APRON	4405	23,666	47	Poor
GIF	APRON NORTH	APRON	4505	188,239	82	Satisfactory
GIF	APRON WEST	APRON	4705	37,020	12	Serious
GIF	TURNAROUND APRON RW 11-29	APRON	5105	11,639	50	Poor
GIF	TURNAROUND APRON RW 11-29	APRON	5110	11,131	50	Poor



Table A-3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
GIF	AP	4105	49	47	44	41	38	36	34	31	28	26	23
GIF	AP	4110	41	38	35	33	31	28	25	23	20	17	15
GIF	AP	4115	35	33	32	30	28	27	25	24	22	21	19
GIF	AP	4120	52	50	49	47	45	44	42	41	39	38	36
GIF	AP	4123	72	69	67	64	62	59	57	55	54	53	52
GIF	AP	4125	15	13	12	10	8	7	5	4	2	1	0
GIF	AP HANG	4405	47	45	44	42	40	39	37	36	34	33	31
GIF	AP N	4505	82	80	79	77	75	74	72	71	69	68	66
GIF	AP RW11-29	5105	50	48	46	43	40	37	35	33	30	27	25
GIF	AP RW11-29	5110	50	48	46	43	40	37	35	33	30	27	25
GIF	AP T-HANG	4205	55	53	52	50	48	47	45	44	42	41	39
GIF	AP T-HANG	4210	87	85	84	82	80	79	77	76	74	73	71
GIF	AP T-HANG	4305	57	55	54	52	50	49	47	46	44	43	41
GIF	AP T-HANG	4310	40	38	37	35	33	32	30	29	27	26	24
GIF	AP W	4705	12	10	9	7	5	4	2	1	0	0	0
GIF	RW 11-29	6205	65	63	62	62	61	61	60	60	60	60	60
GIF	RW 11-29	6210	86	84	81	79	76	74	71	69	67	66	64
GIF	RW 5-23	6105	81	78	76	74	71	69	67	66	64	63	62
GIF	RW 5-23	6110	88	86	83	81	78	76	73	71	69	67	65
GIF	RW 5-23	6115	85	82	80	78	75	73	71	68	67	65	64
GIF	RW 5-23	6117	89	87	86	84	82	81	79	77	76	74	73
GIF	RW 5-23	6120	82	79	77	75	72	70	68	66	65	63	62
GIF	RW 5-23	6122	87	85	84	82	80	79	77	75	74	72	71
GIF	TW A	110	63	61	60	58	56	55	53	51	50	48	47
GIF	TW A	115	37	35	34	33	32	31	30	30	29	28	27
GIF	TW A	320	51	49	48	46	44	43	41	40	38	37	35
GIF	TW A	405	51	49	48	47	45	45	44	44	43	43	43
GIF	TW A	410	32	28	24	20	16	12	9	5	1	0	0
GIF	TW A	417	58	56	54	53	51	49	48	47	46	45	44
GIF	TW A2	105	55	53	52	50	49	47	46	44	42	41	39
GIF	TW B	205	36	34	33	32	31	31	30	29	28	28	27
GIF	TW B	210	64	63	62	61	60	59	58	57	55	54	53
GIF	TW B	212	87	84	82	80	78	76	75	74	73	72	71
GIF	TW B	215	33	32	31	30	29	29	28	27	26	25	23
GIF	TW B	225	87	84	82	80	78	76	75	74	73	72	71
GIF	TW B	230	86	83	81	79	77	76	75	73	72	72	71
GIF	TW B	270	62	60	59	57	55	54	52	50	49	47	46



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
GIF	TW B	275	83	81	79	77	76	74	73	72	71	70	70
GIF	TW B1	240	71	70	69	68	67	66	65	64	62	61	59
GIF	TW B1	245	92	89	86	84	81	79	78	76	75	74	73
GIF	TW B2	250	41	39	38	36	35	34	33	32	31	30	29
GIF	TW B2	255	89	86	84	81	79	78	76	75	74	73	72
GIF	TW B2	310	31	27	23	19	16	12	8	4	0	0	0
GIF	TW B2	315	28	27	26	24	22	20	17	14	11	9	6
GIF	TW B3	258	73	72	71	70	69	68	67	66	65	64	62
GIF	TW B3	260	56	54	52	51	49	48	47	45	45	44	44
GIF	TW C	330	77	75	73	72	71	69	68	67	66	66	65
GIF	TW C3	305	60	58	56	55	53	51	50	48	47	46	45
GIF	TW C3	307	90	87	85	82	80	78	77	75	74	73	72
GIF	TW D	420	64	63	62	61	60	59	58	57	55	54	53
GIF	TW F	605	78	76	74	73	71	70	69	68	67	66	65
GIF	TW F1	610	85	83	80	78	76	75	73	72	70	69	68
GIF	TW F1	612	86	83	81	79	77	76	75	73	72	72	71
GIF	TW F2	615	89	86	84	82	80	77	76	74	72	71	70
GIF	TW F2	617	92	89	86	84	81	79	78	76	75	74	73
GIF	TW HANG	4605	15	12	10	7	4	2	0	0	0	0	0

7/5/2017

Work History Report

Page 1 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S Branch: AP HANG APRON TO HAN Section: 4405 Surface: AC L.C.D.: 1/1/1995 Use: APRON Rank: P Length: 210.00 (Ft) Width: 160.00 (Ft) True Area: 23,666.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1995	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED

Network: WINTER HAVEN'S Branch: AP N APRON NORTH Section: 4505 Surface: AC L.C.D.: 1/1/2011 Use: APRON Rank: P Length: 1,650.00 (Ft) Width: 100.00 (Ft) True Area: 188,239.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: WINTER HAVEN'S Branch: AP RW11-29 TURNAROUND Section: 5105 Surface: AAC L.C.D.: 1/1/1997 Use: APRON Rank: P Length: 200.00 (Ft) Width: 60.00 (Ft) True Area: 11,639.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1942 AC PAVEMENT

Network: WINTER HAVEN'S Branch: AP RW11-29 TURNAROUND Section: 5110 Surface: AAC L.C.D.: 1/1/1997 Use: APRON Rank: P Length: 200.00 (Ft) Width: 55.00 (Ft) True Area: 11,131.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1942 AC PAVEMENT

Network: WINTER HAVEN'S Branch: AP T-HANG APRON T-HANG Section: 4205 Surface: AC L.C.D.: 1/1/1984 Use: APRON Rank: P Length: 6,500.00 (Ft) Width: 25.00 (Ft) True Area: 159,635.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP
1/1/1984	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1984: 1.5" P-401 ON 6" P-211

Network: WINTER HAVEN'S Branch: AP T-HANG APRON T-HANG Section: 4210 Surface: AC L.C.D.: 1/1/2009 Use: APRON Rank: P Length: 550.00 (Ft) Width: 20.00 (Ft) True Area: 13,307.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: WINTER HAVEN'S Branch: AP T-HANG APRON T-HANG Section: 4305 Surface: AC L.C.D.: 1/1/1984 Use: APRON Rank: P Length: 400.00 (Ft) Width: 120.00 (Ft) True Area: 43,314.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED

7/5/2017

Work History Report

Page 2 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S		Branch: AP T-HANG		APRON T-HANG		Section: 4310	Surface: AC
L.C.D.: 1/1/1984	Use: APRON	Rank: P	Length: 300.00 (Ft)	Width: 20.00 (Ft)	True Area: 19,911.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED	

Network: WINTER HAVEN'S		Branch: AP W		APRON WEST		Section: 4705	Surface: AC
L.C.D.: 1/1/1965	Use: APRON	Rank: P	Length: 250.00 (Ft)	Width: 100.00 (Ft)	True Area: 37,020.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1965	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED	

Network: WINTER HAVEN'S		Branch: AP		APRON AREA		Section: 4105	Surface: AAC
L.C.D.: 1/1/1986	Use: APRON	Rank: P	Length: 250.00 (Ft)	Width: 650.00 (Ft)	True Area: 161,696.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1986	IMPORT ED	OVERLAY	0.00	1.00	<input checked="" type="checkbox"/>	1986: 1" P-401 OVERLAY	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1973	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1973: 1.5" P-401 ON 6" P-211	

Network: WINTER HAVEN'S		Branch: AP		APRON AREA		Section: 4110	Surface: AAC
L.C.D.: 1/1/1990	Use: APRON	Rank: P	Length: 680.00 (Ft)	Width: 250.00 (Ft)	True Area: 174,018.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	SS-RE	Surface Seal - Rejuvenating	0.00	0.00	<input type="checkbox"/>		
1/1/1990	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1990 AC OVERLAY ON AC	

Network: WINTER HAVEN'S		Branch: AP		APRON AREA		Section: 4115	Surface: AC
L.C.D.: 1/1/1960	Use: APRON	Rank: P	Length: 250.00 (Ft)	Width: 130.00 (Ft)	True Area: 32,078.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1960	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1960 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: AP		APRON AREA		Section: 4120	Surface: AC
L.C.D.: 1/1/1980	Use: APRON	Rank: P	Length: 240.00 (Ft)	Width: 200.00 (Ft)	True Area: 49,139.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1980	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1980 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: AP		APRON AREA		Section: 4123	Surface: AAC
L.C.D.: 1/1/1997	Use: APRON	Rank: P	Length: 200.00 (Ft)	Width: 100.00 (Ft)	True Area: 17,601.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Date Estimated	
1/1/1980	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1980 AC PAVEMENT	

7/5/2017

Work History Report

Page 3 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S		Branch: AP		APRON AREA		Section: 4125	Surface: AC
L.C.D.: 1/1/1980		Use: APRON		Rank: P	Length: 250.00 (Ft)	Width: 50.00 (Ft)	True Area: 12,408.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1980	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1980 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: RW 11-29		RUNWAY 11-29		Section: 6205	Surface: AAC
L.C.D.: 1/1/1997		Use: RUNWAY		Rank: S	Length: 3,673.00 (Ft)	Width: 100.00 (Ft)	True Area: 367,600.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY	
1/1/1965	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1965 AC OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1942 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: RW 11-29		RUNWAY 11-29		Section: 6210	Surface: AAC
L.C.D.: 1/1/2010		Use: RUNWAY		Rank: S	Length: 214.00 (Ft)	Width: 100.00 (Ft)	True Area: 22,301.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1997	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: RW 5-23		RUNWAY 5-23		Section: 6105	Surface: AAC
L.C.D.: 1/1/2010		Use: RUNWAY		Rank: P	Length: 3,650.00 (Ft)	Width: 50.00 (Ft)	True Area: 182,500.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1985	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1985: 3" P-401 OVERLAY	
1/1/1942	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	ASSUME: 1942 2" AC ON 8" LIME ROCK BASE	

Network: WINTER HAVEN'S		Branch: RW 5-23		RUNWAY 5-23		Section: 6110	Surface: AAC
L.C.D.: 1/1/2010		Use: RUNWAY		Rank: P	Length: 3,650.00 (Ft)	Width: 50.00 (Ft)	True Area: 182,500.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME: 1985 P-401 OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	ASSUME: 1942 2" AC ON 8" LIME ROCK BASE	

7/5/2017

Work History Report

Page 4 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S		Branch: RW 5-23		RUNWAY 5-23		Section: 6115	Surface: AAC
L.C.D.: 1/1/2010		Use: RUNWAY	Rank: P	Length: 1,000.00 (Ft)	Width: 100.00 (Ft)	True Area: 50,300.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991: 1.5" P-401 ON 8" P-211 ON 6" SUBBASE SOIL: SP	
1/1/1991	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: RW 5-23		RUNWAY 5-23		Section: 6117	Surface: AC
L.C.D.: 1/1/2010		Use: RUNWAY	Rank: P	Length: 1,006.00 (Ft)	Width: 25.00 (Ft)	True Area: 50,300.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: RW 5-23		RUNWAY 5-23		Section: 6120	Surface: AAC
L.C.D.: 1/1/2010		Use: RUNWAY	Rank: P	Length: 350.00 (Ft)	Width: 100.00 (Ft)	True Area: 17,500.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY 1985 3" TAPERED AC OVERLAY 1960'S AC OVERLAY 1942 AC PAVEMENT	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1960	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: RW 5-23		RUNWAY 5-23		Section: 6122	Surface: AC
L.C.D.: 1/1/2010		Use: RUNWAY	Rank: P	Length: 350.00 (Ft)	Width: 25.00 (Ft)	True Area: 17,500.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW A		TAXIWAY A		Section: 110	Surface: AAC
L.C.D.: 1/1/1997		Use: TAXIWAY	Rank: P	Length: 11,500.00 (Ft)	Width: 50.00 (Ft)	True Area: 62,789.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY 1942 2" AC ON 8" LIMEROCK	
1/1/1942	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW A		TAXIWAY A		Section: 115	Surface: AC
L.C.D.: 1/1/1997		Use: TAXIWAY	Rank: P	Length: 60.00 (Ft)	Width: 30.00 (Ft)	True Area: 2,744.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC PAVEMENT	

7/5/2017

Work History Report

Page 5 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S		Branch: TW A2		TAXIWAY A2		Section: 105	Surface: AC
L.C.D.: 1/1/1984		Use: TAXIWAY	Rank: P	Length: 200.00 (Ft)	Width: 30.00 (Ft)	True Area: 8,491.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1984: 1.5" P-401 ON 6" P-211	
1/1/1984	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	

Network: WINTER HAVEN'S		Branch: TW A		TAXIWAY A		Section: 320	Surface: AC
L.C.D.: 1/1/2002		Use: TAXIWAY	Rank: P	Length: 500.00 (Ft)	Width: 50.00 (Ft)	True Area: 23,750.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2002	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE ORIGINAL 1942 AC PAVEMENT	
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW A		TAXIWAY A		Section: 405	Surface: AAC
L.C.D.: 1/1/1997		Use: TAXIWAY	Rank: P	Length: 135.00 (Ft)	Width: 50.00 (Ft)	True Area: 7,000.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1942 AC PAVEMENT	
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW A		TAXIWAY A		Section: 410	Surface: AAC
L.C.D.: 1/1/1960		Use: TAXIWAY	Rank: P	Length: 880.00 (Ft)	Width: 50.00 (Ft)	True Area: 43,255.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1960	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1960 AC SURFACE - ASSUME AC OVERLAY ON EXISTI	

Network: WINTER HAVEN'S		Branch: TW A		TAXIWAY A		Section: 417	Surface: AAC
L.C.D.: 1/1/1997		Use: TAXIWAY	Rank: P	Length: 200.00 (Ft)	Width: 110.00 (Ft)	True Area: 10,400.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Date Estimated	
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1942 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: TW B1		TAXIWAY B1		Section: 240	Surface: AAC
L.C.D.: 1/1/2004		Use: TAXIWAY	Rank: P	Length: 250.00 (Ft)	Width: 45.00 (Ft)	True Area: 10,879.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2004	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

7/5/2017

Work History Report

Page 6 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S		Branch: TW B1		TAXIWAY B1		Section: 245	Surface: AAC
L.C.D.: 1/1/2010		Use: TAXIWAY	Rank: P	Length: 70.00 (Ft)	Width: 45.00 (Ft)	True Area: 3,235.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/2004	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 205	Surface: AC
L.C.D.: 1/1/1985		Use: TAXIWAY	Rank: P	Length: 975.00 (Ft)	Width: 40.00 (Ft)	True Area: 40,742.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1985	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1985: 2" P-401 ON 6" P-211 ON 11" P-154	

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 210	Surface: AC
L.C.D.: 1/1/1991		Use: TAXIWAY	Rank: P	Length: 1,225.00 (Ft)	Width: 35.00 (Ft)	True Area: 48,281.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	THIS PAVEMENT WAS LESS THAN 2 YEARS OLD DURING 1993 PCI SU	
1/1/1991	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1991: 1.5" P-401 ON 8" P-211 ON 6" SUBBASE	
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 212	Surface: AAC
L.C.D.: 1/1/2010		Use: TAXIWAY	Rank: P	Length: 75.00 (Ft)	Width: 35.00 (Ft)	True Area: 2,283.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1993	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	THIS PAVEMENT WAS LESS THAN 2 YEARS OLD DURING 1993 PCI SU	
1/1/1991	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1991: 1.5" P-401 ON 8" P-211 ON 6" SUBBASE	
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 215	Surface: AC
L.C.D.: 1/1/1985		Use: TAXIWAY	Rank: P	Length: 1,600.00 (Ft)	Width: 40.00 (Ft)	True Area: 68,940.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1985	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1985 AC PAVEMENT	

7/5/2017

Work History Report

Page 7 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 225	Surface: AAC
L.C.D.: 1/1/2004		Use: TAXIWAY	Rank: P	Length: 1,014.00 (Ft)	Width: 45.00 (Ft)	True Area: 28,746.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2004	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW B2		TAXIWAY B2		Section: 250	Surface: AC
L.C.D.: 1/1/1985		Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 50.00 (Ft)	True Area: 8,852.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1985	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1985: 2" P-401 ON 6" P-211 ON 11" P-154	

Network: WINTER HAVEN'S		Branch: TW B2		TAXIWAY B2		Section: 255	Surface: AAC
L.C.D.: 1/1/2010		Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 50.00 (Ft)	True Area: 2,494.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1985	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1985: 2" P-401 ON 6" P-211 ON 11" P-154	

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 230	Surface: AAC
L.C.D.: 1/1/2010		Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 40.00 (Ft)	True Area: 12,000.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW B2		TAXIWAY B2		Section: 310	Surface: AAC
L.C.D.: 1/1/1970		Use: TAXIWAY	Rank: P	Length: 66.00 (Ft)	Width: 50.00 (Ft)	True Area: 3,077.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1970 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: TW B2		TAXIWAY B2		Section: 315	Surface: AC
L.C.D.: 1/1/1985		Use: TAXIWAY	Rank: P	Length: 120.00 (Ft)	Width: 50.00 (Ft)	True Area: 3,386.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1985	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1985 AC PAVEMENT	

7/5/2017

Work History Report

Page 8 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 270	Surface: AAC
L.C.D.: 1/1/1997		Use: TAXIWAY	Rank: P	Length: 255.00 (Ft)	Width: 50.00 (Ft)	True Area: 13,236.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY	
1/1/1985	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1985 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: TW B		TAXIWAY B		Section: 275	Surface: AAC
L.C.D.: 1/1/2010		Use: TAXIWAY	Rank: P	Length: 45.00 (Ft)	Width: 50.00 (Ft)	True Area: 2,301.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1985	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1985 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: TW B3		TAXIWAY B3		Section: 258	Surface: AAC
L.C.D.: 1/1/1997		Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 50.00 (Ft)	True Area: 2,948.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY	
1/1/1965	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1965 AC OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1942 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: TW B3		TAXIWAY B3		Section: 260	Surface: AAC
L.C.D.: 1/1/1997		Use: TAXIWAY	Rank: P	Length: 105.00 (Ft)	Width: 50.00 (Ft)	True Area: 12,078.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1942 AC PAVEMENT	

Network: WINTER HAVEN'S		Branch: TW C		TAXIWAY C		Section: 330	Surface: AC
L.C.D.: 1/9/1998		Use: TAXIWAY	Rank: P	Length: 1,325.00 (Ft)	Width: 25.00 (Ft)	True Area: 38,971.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/9/1998	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: WINTER HAVEN'S		Branch: TW C3		TAXIWAY C3		Section: 305	Surface: AAC
L.C.D.: 1/1/1960		Use: TAXIWAY	Rank: P	Length: 450.00 (Ft)	Width: 50.00 (Ft)	True Area: 22,138.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1960	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1960 AC OVERLAY	
1/1/1942	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	ASSUME: 1942 2" AC ON 8" LIME ROCK BASE	

7/5/2017

Work History Report

Page 9 of 11

Pavement Database: FDOT

Network:		WINTER HAVEN'S		Branch:		TW C3		TAXIWAY C3		Section:		307		Surface:		AAC							
L.C.D.:		1/1/2010		Use:		TAXIWAY		Rank:		P		Length:		50.00 (Ft)		Width:		50.00 (Ft)		True Area:		2,704.00 (SqFt)	
Work Date		Work Code		Work Description		Cost		Thickness (in)		Major M&R		Comments											
1/1/2010		ML-OV		MILL and OVERLAY		0.00		0.00		<input checked="" type="checkbox"/>		ESTIMATE 1960 AC OVERLAY											
1/1/1960		IMPORT ED		OVERLAY		0.00		0.00		<input checked="" type="checkbox"/>													
1/1/1942		IMPORT ED		BUILT		0.00		2.00		<input checked="" type="checkbox"/>													
Network:		WINTER HAVEN'S		Branch:		TW D		TAXIWAY D		Section:		420		Surface:		AC							
L.C.D.:		1/9/1998		Use:		TAXIWAY		Rank:		P		Length:		1,070.00 (Ft)		Width:		25.00 (Ft)		True Area:		31,033.00 (SqFt)	
Work Date		Work Code		Work Description		Cost		Thickness (in)		Major M&R		Comments											
1/9/1998		NC-AC		New Construction - AC		0.00		0.00		<input checked="" type="checkbox"/>													
Network:		WINTER HAVEN'S		Branch:		TW F1		TAXIWAY F1		Section:		610		Surface:		AC							
L.C.D.:		1/1/2009		Use:		TAXIWAY		Rank:		P		Length:		200.00 (Ft)		Width:		40.00 (Ft)		True Area:		7,988.00 (SqFt)	
Work Date		Work Code		Work Description		Cost		Thickness (in)		Major M&R		Comments											
1/1/2009		NU-IN		New Construction - Initial		0.00		0.00		<input checked="" type="checkbox"/>													
Network:		WINTER HAVEN'S		Branch:		TW F1		TAXIWAY F1		Section:		612		Surface:		AAC							
L.C.D.:		1/1/2010		Use:		TAXIWAY		Rank:		P		Length:		70.00 (Ft)		Width:		40.00 (Ft)		True Area:		2,702.00 (SqFt)	
Work Date		Work Code		Work Description		Cost		Thickness (in)		Major M&R		Comments											
1/1/2010		ML-OV		MILL and OVERLAY		0.00		0.00		<input checked="" type="checkbox"/>													
1/1/2009		NU-IN		New Construction - Initial		0.00		0.00		<input checked="" type="checkbox"/>													
Network:		WINTER HAVEN'S		Branch:		TW F2		TAXIWAY F2		Section:		615		Surface:		AC							
L.C.D.:		1/1/2009		Use:		TAXIWAY		Rank:		P		Length:		200.00 (Ft)		Width:		40.00 (Ft)		True Area:		7,725.00 (SqFt)	
Work Date		Work Code		Work Description		Cost		Thickness (in)		Major M&R		Comments											
1/1/2009		NU-IN		New Construction - Initial		0.00		0.00		<input checked="" type="checkbox"/>													
Network:		WINTER HAVEN'S		Branch:		TW F2		TAXIWAY F2		Section:		617		Surface:		AAC							
L.C.D.:		1/1/2010		Use:		TAXIWAY		Rank:		P		Length:		110.00 (Ft)		Width:		40.00 (Ft)		True Area:		4,418.00 (SqFt)	
Work Date		Work Code		Work Description		Cost		Thickness (in)		Major M&R		Comments											
1/1/2010		ML-OV		MILL and OVERLAY		0.00		0.00		<input checked="" type="checkbox"/>													
1/1/2009		NU-IN		New Construction - Initial		0.00		0.00		<input checked="" type="checkbox"/>													
Network:		WINTER HAVEN'S		Branch:		TW F		TAXIWAY F		Section:		605		Surface:		AC							
L.C.D.:		1/1/2009		Use:		TAXIWAY		Rank:		P		Length:		843.00 (Ft)		Width:		35.00 (Ft)		True Area:		51,882.00 (SqFt)	
Work Date		Work Code		Work Description		Cost		Thickness (in)		Major M&R		Comments											
1/1/2009		NU-IN		New Construction - Initial		0.00		0.00		<input checked="" type="checkbox"/>													

7/5/2017

Work History Report

Page 10 of 11

Pavement Database: FDOT

Network: WINTER HAVEN'S Branch: TW HANG TAXIWAY TO H Section: 4605 Surface: AC						
L.C.D.: 1/1/1965 Use: TAXIWAY Rank: P Length: 350.00 (Ft) Width: 25.00 (Ft) True Area: 9,405.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1965	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	35	1,821,634.00	0.74	0.94
Complete Reconstruction - AC	1	23,750.00	0.00	0.00
MILL and OVERLAY	19	565,099.00	0.00	0.00
New Construction - AC	2	70,004.00	0.00	0.00
New Construction - Initial	19	554,538.00	0.00	0.00
OVERLAY	28	2,123,582.00	0.21	0.67
REPAIR	2	50,564.00	0.00	0.00
Surface Seal - Rejuvenating	1	174,018.00	0.00	0.00

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP	6	1,870.00	230.00	446,940.00	APRON	44.00	17.34	45.17
AP HANG	1	210.00	160.00	23,666.00	APRON	47.00	0.00	47.00
AP N	1	1,650.00	100.00	188,239.00	APRON	82.00	0.00	82.00
AP RW11-2	2	400.00	57.50	22,770.00	APRON	50.00	0.00	50.00
AP T-HAN	4	7,750.00	46.25	236,167.00	APRON	59.75	17.05	55.91
AP W	1	250.00	100.00	37,020.00	APRON	12.00	0.00	12.00
RW 11-29	2	3,887.00	100.00	389,901.00	RUNWAY	75.50	10.50	66.20
RW 5-23	6	10,006.00	58.33	500,600.00	RUNWAY	85.33	2.98	85.00
TW A	6	13,275.00	56.67	149,938.00	TAXIWAY	48.67	10.93	50.77
TW A2	1	200.00	30.00	8,491.00	TAXIWAY	55.00	0.00	55.00
TW B	8	5,489.00	41.88	216,529.00	TAXIWAY	67.25	21.12	53.46
TW B1	2	320.00	45.00	14,114.00	TAXIWAY	81.50	10.50	75.81
TW B2	4	411.00	50.00	17,809.00	TAXIWAY	47.25	24.58	43.52
TW B3	2	155.00	50.00	15,026.00	TAXIWAY	64.50	8.50	59.34
TW C	1	1,325.00	25.00	38,971.00	TAXIWAY	77.00	0.00	77.00
TW C3	2	500.00	50.00	24,842.00	TAXIWAY	75.00	15.00	63.27
TW D	1	1,070.00	25.00	31,033.00	TAXIWAY	64.00	0.00	64.00
TW F	1	843.00	35.00	51,882.00	TAXIWAY	78.00	0.00	78.00
TW F1	2	270.00	40.00	10,690.00	TAXIWAY	85.50	0.50	85.25
TW F2	2	310.00	40.00	12,143.00	TAXIWAY	90.50	1.50	90.09
TW HANG	1	350.00	25.00	9,405.00	TAXIWAY	15.00	0.00	15.00

7/5/2017

Branch Condition Report

Page 2 of 2

Pavement Database: FDOT

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	15	954802.000145288	49.60	20.06	53.96
RUNWAY	8	890501.000057246	82.88	7.24	76.77
TAXIWAY	33	600873.000093589	63.70	22.13	58.49
ALL	56	2446176.00029612	62.66	22.55	63.38

Pavement Database: FDOT

NetworkId: GIF

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP	4105	1/1/1986	AAC	APRON	P	0	161,696.00	3/8/2017	31	49
AP	4110	1/1/1990	AAC	APRON	P	0	174,018.00	3/8/2017	27	41
AP	4115	1/1/1960	AC	APRON	P	0	32,078.00	3/8/2017	57	35
AP	4120	1/1/1980	AC	APRON	P	0	49,139.00	3/8/2017	37	52
AP	4123	1/1/1997	AAC	APRON	P	0	17,601.00	3/8/2017	20	72
AP	4125	1/1/1980	AC	APRON	P	0	12,408.00	3/8/2017	37	15
AP HANG	4405	1/1/1995	AC	APRON	P	0	23,666.00	3/8/2017	22	47
AP N	4505	1/1/2011	AC	APRON	P	0	188,239.00	3/8/2017	6	82
AP RW11-29	5105	1/1/1997	AAC	APRON	P	0	11,639.00	3/8/2017	20	50
AP RW11-29	5110	1/1/1997	AAC	APRON	P	0	11,131.00	3/8/2017	20	50
AP T-HANG	4205	1/1/1984	AC	APRON	P	0	159,635.00	3/8/2017	33	55
AP T-HANG	4210	1/1/2009	AC	APRON	P	0	13,307.00	3/8/2017	8	87
AP T-HANG	4305	1/1/1984	AC	APRON	P	0	43,314.00	3/8/2017	33	57
AP T-HANG	4310	1/1/1984	AC	APRON	P	0	19,911.00	3/8/2017	33	40
AP W	4705	1/1/1965	AC	APRON	P	0	37,020.00	3/8/2017	52	12
RW 11-29	6205	1/1/1997	AAC	RUNWAY	S	0	367,600.00	3/8/2017	20	65
RW 11-29	6210	1/1/2010	AAC	RUNWAY	S	0	22,301.00	3/8/2017	7	86
RW 5-23	6105	1/1/2010	AAC	RUNWAY	P	0	182,500.00	3/8/2017	7	81
RW 5-23	6110	1/1/2010	AAC	RUNWAY	P	0	182,500.00	3/8/2017	7	88
RW 5-23	6115	1/1/2010	AAC	RUNWAY	P	0	50,300.00	3/8/2017	7	85
RW 5-23	6117	1/1/2010	AC	RUNWAY	P	0	50,300.00	3/8/2017	7	89
RW 5-23	6120	1/1/2010	AAC	RUNWAY	P	0	17,500.00	3/8/2017	7	82
RW 5-23	6122	1/1/2010	AC	RUNWAY	P	0	17,500.00	3/8/2017	7	87
TW A	110	1/1/1997	AAC	TAXIWAY	P	0	62,789.00	3/8/2017	20	63
TW A	115	1/1/1997	AC	TAXIWAY	P	0	2,744.00	3/8/2017	20	37
TW A	320	1/1/2002	AC	TAXIWAY	P	0	23,750.00	3/8/2017	15	51
TW A	405	1/1/1997	AAC	TAXIWAY	P	0	7,000.00	3/8/2017	20	51
TW A	410	1/1/1960	AAC	TAXIWAY	P	0	43,255.00	3/8/2017	57	32
TW A	417	1/1/1997	AAC	TAXIWAY	P	0	10,400.00	3/8/2017	20	58
TW A2	105	1/1/1984	AC	TAXIWAY	P	0	8,491.00	3/8/2017	33	55
TW B	205	1/1/1985	AC	TAXIWAY	P	0	40,742.00	3/8/2017	32	36
TW B	210	1/1/1991	AC	TAXIWAY	P	0	48,281.00	3/8/2017	26	64
TW B	212	1/1/2010	AAC	TAXIWAY	P	0	2,283.00	3/8/2017	7	87
TW B	215	1/1/1985	AC	TAXIWAY	P	0	68,940.00	3/8/2017	32	33
TW B	225	1/1/2004	AAC	TAXIWAY	P	0	28,746.00	3/8/2017	13	87
TW B	230	1/1/2010	AAC	TAXIWAY	P	0	12,000.00	3/8/2017	7	86
TW B	270	1/1/1997	AAC	TAXIWAY	P	0	13,236.00	3/8/2017	20	62
TW B	275	1/1/2010	AAC	TAXIWAY	P	0	2,301.00	3/8/2017	7	83
TW B1	240	1/1/2004	AAC	TAXIWAY	P	0	10,879.00	3/8/2017	13	71
TW B1	245	1/1/2010	AAC	TAXIWAY	P	0	3,235.00	3/8/2017	7	92
TW B2	250	1/1/1985	AC	TAXIWAY	P	0	8,852.00	3/8/2017	32	41
TW B2	255	1/1/2010	AAC	TAXIWAY	P	0	2,494.00	3/8/2017	7	89
TW B2	310	1/1/1970	AAC	TAXIWAY	P	0	3,077.00	3/8/2017	47	31
TW B2	315	1/1/1985	AC	TAXIWAY	P	0	3,386.00	3/8/2017	32	28
TW B3	258	1/1/1997	AAC	TAXIWAY	P	0	2,948.00	3/8/2017	20	73
TW B3	260	1/1/1997	AAC	TAXIWAY	P	0	12,078.00	3/8/2017	20	56
TW C	330	1/9/1998	AC	TAXIWAY	P	0	38,971.00	3/8/2017	19	77
TW C3	305	1/1/1960	AAC	TAXIWAY	P	0	22,138.00	3/8/2017	57	60

7/5/2017		Section Condition Report							Page 2 of 3		
TW C3	307	1/1/2010	AAC	TAXIWAY	P	0	2,704.00	3/8/2017	7	90	
TW D	420	1/9/1998	AC	TAXIWAY	P	0	31,033.00	3/8/2017	19	64	
TW F	605	1/1/2009	AC	TAXIWAY	P	0	51,882.00	3/8/2017	8	78	
TW F1	610	1/1/2009	AC	TAXIWAY	P	0	7,988.00	3/8/2017	8	85	
TW F1	612	1/1/2010	AAC	TAXIWAY	P	0	2,702.00	3/8/2017	7	86	
TW F2	615	1/1/2009	AC	TAXIWAY	P	0	7,725.00	3/8/2017	8	89	
TW F2	617	1/1/2010	AAC	TAXIWAY	P	0	4,418.00	3/8/2017	7	92	
TW HANG	4605	1/1/1965	AC	TAXIWAY	P	0	9,405.00	3/8/2017	52	15	

7/5/2017

Section Condition Report (Summary)

Page 3 of 3

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
06-10	7	824,179.00	20	86.20	3.56	84.08
11-15	14	63,375.00	3	69.67	14.73	70.76
16-20	20	589,170.00	13	59.85	10.69	64.53
21-25	22	23,666.00	1	47.00	0.00	47.00
26-30	27	222,299.00	2	52.50	11.50	46.00
31-35	32	514,967.00	9	43.78	10.01	47.84
36-40	37	61,547.00	2	33.50	18.50	44.54
41-50	47	3,077.00	1	31.00	0.00	31.00
ALL	22	2,446,176.00	56	62.66	22.55	63.38
Over 50	55	143,896.00	5	30.80	17.17	30.72

Appendix B

Airfield Pavement Localized Maintenance and Repair and
Major Rehabilitation



Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
GIF	AP	4105	43	BLOCK CR	Medium	1667.65	SqFt	1.0%	FDOT - CRACK SEALING - AC	508.2	Ft	\$ 3.00	\$ 1,530.00
GIF	AP	4105	45	DEPRESSION	Low	1300.82	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	1449.9	SqFt	\$ 6.00	\$ 8,700.00
GIF	AP	4105	49	OIL SPILLAGE	N/A	200.1	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	261.56	SqFt	\$ 3.00	\$ 790.00
GIF	AP	4105	52	RAVELING	Low	156793.04	SqFt	97.0%	FDOT - SURFACE SEAL	156793.6	SqFt	\$ 0.55	\$ 86,240.00
GIF	AP	4105	52	RAVELING	Medium	4902.96	SqFt	3.0%	FDOT - PATCHING - AC PARTIAL DEPTH	4902.96	SqFt	\$ 3.00	\$ 14,710.00
GIF	AP	4110	43	BLOCK CR	Medium	10805.24	SqFt	6.2%	FDOT - CRACK SEALING - AC	3293.31	Ft	\$ 3.00	\$ 9,890.00
GIF	AP	4110	45	DEPRESSION	Low	1498.34	SqFt	0.9%	FDOT - PATCHING - AC FULL DEPTH	1657.64	SqFt	\$ 6.00	\$ 9,950.00
GIF	AP	4110	52	RAVELING	Low	58800.01	SqFt	33.8%	FDOT - SURFACE SEAL	58800.01	SqFt	\$ 0.55	\$ 32,350.00
GIF	AP	4110	52	RAVELING	Medium	64956.65	SqFt	37.3%	FDOT - PATCHING - AC PARTIAL DEPTH	64956.97	SqFt	\$ 3.00	\$ 194,870.00
GIF	AP	4115	43	BLOCK CR	Medium	11227.3	SqFt	35.0%	FDOT - CRACK SEALING - AC	3422.24	Ft	\$ 3.00	\$ 10,270.00
GIF	AP	4115	45	DEPRESSION	Low	384.92	SqFt	1.2%	FDOT - PATCHING - AC FULL DEPTH	468.23	SqFt	\$ 6.00	\$ 2,810.00
GIF	AP	4115	52	RAVELING	Low	31410.81	SqFt	97.9%	FDOT - SURFACE SEAL	31411.24	SqFt	\$ 0.55	\$ 17,280.00
GIF	AP	4115	52	RAVELING	Medium	590.19	SqFt	1.8%	FDOT - PATCHING - AC PARTIAL DEPTH	589.86	SqFt	\$ 3.00	\$ 1,780.00
GIF	AP	4120	52	RAVELING	Low	46682	SqFt	95.0%	FDOT - SURFACE SEAL	46682	SqFt	\$ 0.55	\$ 25,680.00
GIF	AP	4120	52	RAVELING	Medium	2456.97	SqFt	5.0%	FDOT - PATCHING - AC PARTIAL DEPTH	2457.4	SqFt	\$ 3.00	\$ 7,380.00
GIF	AP	4123	52	RAVELING	Low	878.01	SqFt	5.0%	FDOT - SURFACE SEAL	878.34	SqFt	\$ 0.55	\$ 490.00
GIF	AP	4125	41	ALLIGATOR CR	Low	236.16	SqFt	1.9%	FDOT - PATCHING - AC FULL DEPTH	302.47	SqFt	\$ 6.00	\$ 1,820.00
GIF	AP	4125	41	ALLIGATOR CR	Medium	210.43	SqFt	1.7%	FDOT - PATCHING - AC FULL DEPTH	272.33	SqFt	\$ 6.00	\$ 1,640.00
GIF	AP	4125	45	DEPRESSION	Low	42.09	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	72.12	SqFt	\$ 6.00	\$ 440.00
GIF	AP	4125	45	DEPRESSION	Medium	84.17	SqFt	0.7%	FDOT - PATCHING - AC FULL DEPTH	124.86	SqFt	\$ 6.00	\$ 760.00
GIF	AP	4125	52	RAVELING	Medium	10523.23	SqFt	84.8%	FDOT - PATCHING - AC PARTIAL DEPTH	10522.8	SqFt	\$ 3.00	\$ 31,570.00
GIF	AP	4125	52	RAVELING	High	1884.87	SqFt	15.2%	FDOT - PATCHING - AC PARTIAL DEPTH	1884.76	SqFt	\$ 3.00	\$ 5,660.00
GIF	AP HANG	4405	43	BLOCK CR	Medium	1183.28	SqFt	5.0%	FDOT - CRACK SEALING - AC	360.56	Ft	\$ 3.00	\$ 1,090.00
GIF	AP HANG	4405	49	OIL SPILLAGE	N/A	132.5	SqFt	0.6%	FDOT - PATCHING - AC PARTIAL DEPTH	182.99	SqFt	\$ 3.00	\$ 550.00
GIF	AP HANG	4405	52	RAVELING	Low	4733.21	SqFt	20.0%	FDOT - SURFACE SEAL	4732.89	SqFt	\$ 0.55	\$ 2,610.00
GIF	AP N	4505	45	DEPRESSION	Low	2554.17	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	2762.02	SqFt	\$ 6.00	\$ 16,570.00
GIF	AP N	4505	52	RAVELING	Low	1749.46	SqFt	0.9%	FDOT - SURFACE SEAL	1749.14	SqFt	\$ 0.55	\$ 970.00
GIF	AP RW11-29	5105	45	DEPRESSION	Low	144.34	SqFt	1.2%	FDOT - PATCHING - AC FULL DEPTH	196.98	SqFt	\$ 6.00	\$ 1,190.00
GIF	AP RW11-29	5105	52	RAVELING	Low	1745.8	SqFt	15.0%	FDOT - SURFACE SEAL	1745.91	SqFt	\$ 0.55	\$ 970.00
GIF	AP RW11-29	5110	43	BLOCK CR	Medium	1199.42	SqFt	10.8%	FDOT - CRACK SEALING - AC	365.49	Ft	\$ 3.00	\$ 1,100.00
GIF	AP RW11-29	5110	45	DEPRESSION	Low	299.88	SqFt	2.7%	FDOT - PATCHING - AC FULL DEPTH	373.51	SqFt	\$ 6.00	\$ 2,250.00
GIF	AP RW11-29	5110	52	RAVELING	Low	2227.05	SqFt	20.0%	FDOT - SURFACE SEAL	2227.05	SqFt	\$ 0.55	\$ 1,230.00
GIF	AP T-HANG	4205	45	DEPRESSION	Low	380.4	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	462.85	SqFt	\$ 6.00	\$ 2,780.00
GIF	AP T-HANG	4205	52	RAVELING	Low	153034.6	SqFt	95.9%	FDOT - SURFACE SEAL	153034.8	SqFt	\$ 0.55	\$ 84,170.00
GIF	AP T-HANG	4205	52	RAVELING	Medium	6600.43	SqFt	4.1%	FDOT - PATCHING - AC PARTIAL DEPTH	6600.43	SqFt	\$ 3.00	\$ 19,810.00
GIF	AP T-HANG	4205	54	SHOVING	Medium	887.7	SqFt	0.6%	FDOT - MILLING - AC	1011.81	SqFt	\$ 2.00	\$ 2,030.00
GIF	AP T-HANG	4210	52	RAVELING	Low	266.19	SqFt	2.0%	FDOT - SURFACE SEAL	265.87	SqFt	\$ 0.55	\$ 150.00
GIF	AP T-HANG	4305	48	L & T CR	Medium	83.3	Ft	0.2%	FDOT - CRACK SEALING - AC	83.33	Ft	\$ 3.00	\$ 250.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
GIF	AP T-HANG	4305	49	OIL SPILLAGE	N/A	324.85	SqFt	0.8%	FDOT - PATCHING - AC PARTIAL DEPTH	401.49	SqFt	\$ 3.00	\$ 1,210.00
GIF	AP T-HANG	4305	52	RAVELING	Low	37483.27	SqFt	86.5%	FDOT - SURFACE SEAL	37483.17	SqFt	\$ 0.55	\$ 20,620.00
GIF	AP T-HANG	4305	52	RAVELING	Medium	5830.7	SqFt	13.5%	FDOT - PATCHING - AC PARTIAL DEPTH	5830.81	SqFt	\$ 3.00	\$ 17,500.00
GIF	AP T-HANG	4310	52	RAVELING	Low	7964.43	SqFt	40.0%	FDOT - SURFACE SEAL	7964.22	SqFt	\$ 0.55	\$ 4,390.00
GIF	AP T-HANG	4310	52	RAVELING	Medium	11946.65	SqFt	60.0%	FDOT - PATCHING - AC PARTIAL DEPTH	11946.86	SqFt	\$ 3.00	\$ 35,840.00
GIF	AP W	4705	41	ALLIGATOR CR	Low	5253	SqFt	14.2%	FDOT - PATCHING - AC FULL DEPTH	5548.8	SqFt	\$ 6.00	\$ 33,300.00
GIF	AP W	4705	45	DEPRESSION	Low	1129.78	SqFt	3.1%	FDOT - PATCHING - AC FULL DEPTH	1269.07	SqFt	\$ 6.00	\$ 7,620.00
GIF	AP W	4705	52	RAVELING	Medium	32041.47	SqFt	86.6%	FDOT - PATCHING - AC PARTIAL DEPTH	32040.93	SqFt	\$ 3.00	\$ 96,130.00
GIF	AP W	4705	52	RAVELING	High	4353.03	SqFt	11.8%	FDOT - PATCHING - AC PARTIAL DEPTH	4352.93	SqFt	\$ 3.00	\$ 13,060.00
GIF	RW 11-29	6205	45	DEPRESSION	Low	58.77	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	93.65	SqFt	\$ 6.00	\$ 570.00
GIF	RW 11-29	6205	48	L & T CR	Medium	2793.77	Ft	0.8%	FDOT - CRACK SEALING - AC	2793.64	Ft	\$ 3.00	\$ 8,390.00
GIF	RW 11-29	6205	52	RAVELING	Low	230362.64	SqFt	62.7%	FDOT - SURFACE SEAL	230362.8	SqFt	\$ 0.55	\$ 126,710.00
GIF	RW 5-23	6105	52	RAVELING	Low	8603.59	SqFt	4.7%	FDOT - SURFACE SEAL	8603.59	SqFt	\$ 0.55	\$ 4,740.00
GIF	RW 5-23	6110	52	RAVELING	Low	130.35	SqFt	0.1%	FDOT - SURFACE SEAL	130.24	SqFt	\$ 0.55	\$ 80.00
GIF	RW 5-23	6115	52	RAVELING	Low	2514.99	SqFt	5.0%	FDOT - SURFACE SEAL	2515.53	SqFt	\$ 0.55	\$ 1,390.00
GIF	RW 5-23	6117	52	RAVELING	Low	994.05	SqFt	2.0%	FDOT - SURFACE SEAL	994.59	SqFt	\$ 0.55	\$ 550.00
GIF	RW 5-23	6120	52	RAVELING	Low	875	SqFt	5.0%	FDOT - SURFACE SEAL	875.11	SqFt	\$ 0.55	\$ 490.00
GIF	RW 5-23	6122	52	RAVELING	Low	351.98	SqFt	2.0%	FDOT - SURFACE SEAL	351.98	SqFt	\$ 0.55	\$ 200.00
GIF	TW A	110	48	L & T CR	Medium	63.62	Ft	0.1%	FDOT - CRACK SEALING - AC	63.65	Ft	\$ 3.00	\$ 200.00
GIF	TW A	110	52	RAVELING	Low	7831.18	SqFt	12.5%	FDOT - SURFACE SEAL	7830.74	SqFt	\$ 0.55	\$ 4,310.00
GIF	TW A	115	45	DEPRESSION	Low	112.05	SqFt	4.1%	FDOT - PATCHING - AC FULL DEPTH	158.23	SqFt	\$ 6.00	\$ 960.00
GIF	TW A	115	50	PATCHING	Medium	540.03	SqFt	19.7%	FDOT - PATCHING - AC FULL DEPTH	637.22	SqFt	\$ 6.00	\$ 3,830.00
GIF	TW A	115	52	RAVELING	Low	412.04	SqFt	15.0%	FDOT - SURFACE SEAL	412.26	SqFt	\$ 0.55	\$ 230.00
GIF	TW A	320	52	RAVELING	Low	21714.25	SqFt	91.4%	FDOT - SURFACE SEAL	21714.04	SqFt	\$ 0.55	\$ 11,950.00
GIF	TW A	320	52	RAVELING	Medium	2035.67	SqFt	8.6%	FDOT - PATCHING - AC PARTIAL DEPTH	2035.46	SqFt	\$ 3.00	\$ 6,110.00
GIF	TW A	405	52	RAVELING	Low	6607.1	SqFt	94.4%	FDOT - SURFACE SEAL	6606.89	SqFt	\$ 0.55	\$ 3,640.00
GIF	TW A	405	52	RAVELING	Medium	392.88	SqFt	5.6%	FDOT - PATCHING - AC PARTIAL DEPTH	392.88	SqFt	\$ 3.00	\$ 1,180.00
GIF	TW A	410	43	BLOCK CR	Medium	39596.66	SqFt	91.5%	FDOT - CRACK SEALING - AC	12068.9	Ft	\$ 3.00	\$ 36,210.00
GIF	TW A	410	43	BLOCK CR	High	645.62	SqFt	1.5%	FDOT - PATCHING - AC PARTIAL DEPTH	645.83	SqFt	\$ 3.00	\$ 1,940.00
GIF	TW A	410	52	RAVELING	Low	36583.84	SqFt	84.6%	FDOT - SURFACE SEAL	36583.3	SqFt	\$ 0.55	\$ 20,130.00
GIF	TW A	410	52	RAVELING	Medium	6671.15	SqFt	15.4%	FDOT - PATCHING - AC PARTIAL DEPTH	6671.47	SqFt	\$ 3.00	\$ 20,020.00
GIF	TW A	417	52	RAVELING	Low	519.68	SqFt	5.0%	FDOT - SURFACE SEAL	519.9	SqFt	\$ 0.55	\$ 290.00
GIF	TW A2	105	45	DEPRESSION	Low	120.56	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	168.99	SqFt	\$ 6.00	\$ 1,020.00
GIF	TW A2	105	52	RAVELING	Low	7640.87	SqFt	90.0%	FDOT - SURFACE SEAL	7641.3	SqFt	\$ 0.55	\$ 4,210.00
GIF	TW A2	105	52	RAVELING	Medium	850.13	SqFt	10.0%	FDOT - PATCHING - AC PARTIAL DEPTH	850.35	SqFt	\$ 3.00	\$ 2,560.00
GIF	TW B	205	48	L & T CR	Medium	275.3	Ft	0.7%	FDOT - CRACK SEALING - AC	275.26	Ft	\$ 3.00	\$ 830.00
GIF	TW B	205	52	RAVELING	Low	12222.64	SqFt	30.0%	FDOT - SURFACE SEAL	12222.42	SqFt	\$ 0.55	\$ 6,730.00
GIF	TW B	205	52	RAVELING	Medium	28519.41	SqFt	70.0%	FDOT - PATCHING - AC PARTIAL DEPTH	28518.98	SqFt	\$ 3.00	\$ 85,560.00
GIF	TW B	210	52	RAVELING	Low	44995.94	SqFt	93.2%	FDOT - SURFACE SEAL	44996.37	SqFt	\$ 0.55	\$ 24,750.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
GIF	TW B	210	52	RAVELING	Medium	3285.04	SqFt	6.8%	FDOT - PATCHING - AC PARTIAL DEPTH	3285.15	SqFt	\$ 3.00	\$ 9,860.00
GIF	TW B	212	52	RAVELING	Low	45.96	SqFt	2.0%	FDOT - SURFACE SEAL	46.28	SqFt	\$ 0.55	\$ 30.00
GIF	TW B	215	52	RAVELING	Medium	68372.57	SqFt	99.2%	FDOT - PATCHING - AC PARTIAL DEPTH	68372.36	SqFt	\$ 3.00	\$ 205,120.00
GIF	TW B	215	52	RAVELING	High	567.37	SqFt	0.8%	FDOT - PATCHING - AC PARTIAL DEPTH	567.26	SqFt	\$ 3.00	\$ 1,710.00
GIF	TW B	225	52	RAVELING	Low	287.5	SqFt	1.0%	FDOT - SURFACE SEAL	287.4	SqFt	\$ 0.55	\$ 160.00
GIF	TW B	230	52	RAVELING	Low	360.05	SqFt	3.0%	FDOT - SURFACE SEAL	359.51	SqFt	\$ 0.55	\$ 200.00
GIF	TW B	270	48	L & T CR	Medium	265.88	Ft	2.0%	FDOT - CRACK SEALING - AC	265.75	Ft	\$ 3.00	\$ 800.00
GIF	TW B	270	52	RAVELING	Low	13231.86	SqFt	100.0%	FDOT - SURFACE SEAL	13232.08	SqFt	\$ 0.55	\$ 7,280.00
GIF	TW B	275	52	RAVELING	Low	45.96	SqFt	2.0%	FDOT - SURFACE SEAL	46.28	SqFt	\$ 0.55	\$ 30.00
GIF	TW B1	240	52	RAVELING	Low	542.93	SqFt	5.0%	FDOT - SURFACE SEAL	542.5	SqFt	\$ 0.55	\$ 300.00
GIF	TW B2	250	52	RAVELING	Low	2655.78	SqFt	30.0%	FDOT - SURFACE SEAL	2655.46	SqFt	\$ 0.55	\$ 1,470.00
GIF	TW B2	250	52	RAVELING	Medium	6196.25	SqFt	70.0%	FDOT - PATCHING - AC PARTIAL DEPTH	6195.71	SqFt	\$ 3.00	\$ 18,590.00
GIF	TW B2	310	52	RAVELING	Medium	3056.95	SqFt	99.4%	FDOT - PATCHING - AC PARTIAL DEPTH	3056.95	SqFt	\$ 3.00	\$ 9,180.00
GIF	TW B2	310	52	RAVELING	High	20.02	SqFt	0.7%	FDOT - PATCHING - AC PARTIAL DEPTH	20.45	SqFt	\$ 3.00	\$ 60.00
GIF	TW B2	315	45	DEPRESSION	Low	45.96	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	77.5	SqFt	\$ 6.00	\$ 470.00
GIF	TW B2	315	52	RAVELING	Medium	3375.99	SqFt	99.7%	FDOT - PATCHING - AC PARTIAL DEPTH	3375.56	SqFt	\$ 3.00	\$ 10,130.00
GIF	TW B2	315	52	RAVELING	High	10.01	SqFt	0.3%	FDOT - PATCHING - AC PARTIAL DEPTH	9.69	SqFt	\$ 3.00	\$ 40.00
GIF	TW B3	258	50	PATCHING	Medium	2.05	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	11.84	SqFt	\$ 6.00	\$ 80.00
GIF	TW B3	258	52	RAVELING	Low	58.99	SqFt	2.0%	FDOT - SURFACE SEAL	59.2	SqFt	\$ 0.55	\$ 40.00
GIF	TW B3	260	45	DEPRESSION	Low	258.55	SqFt	2.1%	FDOT - PATCHING - AC FULL DEPTH	327.22	SqFt	\$ 6.00	\$ 1,970.00
GIF	TW B3	260	48	L & T CR	Medium	232.28	Ft	1.9%	FDOT - CRACK SEALING - AC	232.28	Ft	\$ 3.00	\$ 700.00
GIF	TW B3	260	52	RAVELING	Low	12029.53	SqFt	99.6%	FDOT - SURFACE SEAL	12029.75	SqFt	\$ 0.55	\$ 6,620.00
GIF	TW C	330	52	RAVELING	Low	1948.59	SqFt	5.0%	FDOT - SURFACE SEAL	1948.27	SqFt	\$ 0.55	\$ 1,080.00
GIF	TW C3	305	48	L & T CR	Medium	65.81	Ft	0.3%	FDOT - CRACK SEALING - AC	65.94	Ft	\$ 3.00	\$ 200.00
GIF	TW C3	305	52	RAVELING	Low	22006.38	SqFt	99.4%	FDOT - SURFACE SEAL	22006.81	SqFt	\$ 0.55	\$ 12,110.00
GIF	TW C3	305	52	RAVELING	Medium	52.64	SqFt	0.2%	FDOT - PATCHING - AC PARTIAL DEPTH	52.74	SqFt	\$ 3.00	\$ 160.00
GIF	TW D	420	52	RAVELING	Low	30412.35	SqFt	98.0%	FDOT - SURFACE SEAL	30412.35	SqFt	\$ 0.55	\$ 16,730.00
GIF	TW D	420	52	RAVELING	Medium	620.65	SqFt	2.0%	FDOT - PATCHING - AC PARTIAL DEPTH	621.08	SqFt	\$ 3.00	\$ 1,870.00
GIF	TW F	605	45	DEPRESSION	Low	739.16	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	852.5	SqFt	\$ 6.00	\$ 5,120.00
GIF	TW F	605	52	RAVELING	Low	2592.7	SqFt	5.0%	FDOT - SURFACE SEAL	2593.03	SqFt	\$ 0.55	\$ 1,430.00
GIF	TW F1	610	52	RAVELING	Low	198.27	SqFt	2.5%	FDOT - SURFACE SEAL	198.06	SqFt	\$ 0.55	\$ 110.00
GIF	TW F1	612	52	RAVELING	Low	50.05	SqFt	1.9%	FDOT - SURFACE SEAL	49.51	SqFt	\$ 0.55	\$ 30.00
GIF	TW F2	615	45	DEPRESSION	Low	17.01	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	37.67	SqFt	\$ 6.00	\$ 230.00
GIF	TW F2	617	52	RAVELING	Low	24.97	SqFt	0.6%	FDOT - SURFACE SEAL	24.76	SqFt	\$ 0.55	\$ 20.00
GIF	TW HANG	4605	41	ALLIGATOR CR	Low	1544.62	SqFt	16.4%	FDOT - PATCHING - AC FULL DEPTH	1707.16	SqFt	\$ 6.00	\$ 10,250.00
GIF	TW HANG	4605	52	RAVELING	Medium	9363.63	SqFt	99.6%	FDOT - PATCHING - AC PARTIAL DEPTH	9363.53	SqFt	\$ 3.00	\$ 28,100.00



Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	GIF	AP	4105	AAC	161,696	47	AC Restoration	\$ 1,219,000.00
2018	GIF	AP	4110	AAC	174,018	38	AC Restoration	\$ 1,567,000.00
2018	GIF	AP	4115	AC	32,078	33	AC Reconstruction	\$ 289,000.00
2018	GIF	AP	4120	AC	49,139	50	AC Restoration	\$ 344,000.00
2018	GIF	AP	4125	AC	12,408	13	AC Reconstruction	\$ 112,000.00
2018	GIF	AP HANG	4405	AC	23,666	45	AC Restoration	\$ 187,000.00
2018	GIF	AP RW11-29	5105	AAC	11,639	48	AC Restoration	\$ 85,000.00
2018	GIF	AP RW11-29	5110	AAC	11,131	48	AC Restoration	\$ 82,000.00
2018	GIF	AP T-HANG	4205	AC	159,635	53	AC Restoration	\$ 1,118,000.00
2018	GIF	AP T-HANG	4305	AC	43,314	55	AC Restoration	\$ 304,000.00
2018	GIF	AP T-HANG	4310	AC	19,911	38	AC Reconstruction	\$ 180,000.00
2018	GIF	AP W	4705	AC	37,020	10	AC Reconstruction	\$ 334,000.00
2018	GIF	RW 11-29	6205	AAC	367,600	63	AC Restoration	\$ 2,574,000.00
2018	GIF	TW A	110	AAC	62,789	61	AC Restoration	\$ 440,000.00
2018	GIF	TW A	115	AC	2,744	35	AC Reconstruction	\$ 25,000.00
2018	GIF	TW A	320	AC	23,750	49	AC Restoration	\$ 168,000.00
2018	GIF	TW A	405	AAC	7,000	49	AC Restoration	\$ 50,000.00
2018	GIF	TW A	410	AAC	43,255	28	AC Reconstruction	\$ 390,000.00
2018	GIF	TW A	417	AAC	10,400	56	AC Restoration	\$ 73,000.00
2018	GIF	TW A2	105	AC	8,491	53	AC Restoration	\$ 60,000.00
2018	GIF	TW B	205	AC	40,742	34	AC Reconstruction	\$ 367,000.00
2018	GIF	TW B	210	AC	48,281	63	AC Restoration	\$ 338,000.00
2018	GIF	TW B	215	AC	68,940	32	AC Reconstruction	\$ 621,000.00
2018	GIF	TW B	270	AAC	13,236	60	AC Restoration	\$ 93,000.00
2018	GIF	TW B2	250	AC	8,852	39	AC Restoration	\$ 80,000.00
2018	GIF	TW B2	310	AAC	3,077	27	AC Reconstruction	\$ 28,000.00




Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	GIF	TW B2	315	AC	3,386	27	AC Reconstruction	\$ 31,000.00
2018	GIF	TW B3	260	AAC	12,078	54	AC Restoration	\$ 85,000.00
2018	GIF	TW C3	305	AAC	22,138	58	AC Restoration	\$ 155,000.00
2018	GIF	TW D	420	AC	31,033	63	AC Restoration	\$ 218,000.00
2018	GIF	TW HANG	4605	AC	9,405	12	AC Reconstruction	\$ 85,000.00
2020	GIF	AP	4123	AAC	17,601	64	AC Restoration	\$ 124,000.00
2024	GIF	TW B1	240	AAC	10,879	64	AC Restoration	\$ 77,000.00
2025	GIF	RW 5-23	6105	AAC	182,500	64	AC Restoration	\$ 1,278,000.00
2026	GIF	RW 5-23	6120	AAC	17,500	63	AC Restoration	\$ 123,000.00
2026	GIF	TW B3	258	AAC	2,948	64	AC Restoration	\$ 21,000.00
2027	GIF	RW 11-29	6210	AAC	22,301	64	AC Restoration	\$ 157,000.00
2027	GIF	RW 5-23	6115	AAC	50,300	64	AC Restoration	\$ 353,000.00

Appendix C

Technical Exhibits





GRAPHIC SCALE IN FEET
0 100 200 400


LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID
- 4105 — SECTION NUMBER
AC — PAVEMENT TYPE
100' X 50' — TYPICAL SAMPLE UNIT INFORMATION
5 14 — FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH
RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE
NUMBER OF SAMPLE UNITS IN SECTION
NUMBER OF SAMPLE UNITS TO BE INSPECTED
- 100 — INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 111
AC: 111 PCC: 0

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.






CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2018	TW E, TW F	NEW CONSTRUCTION/ 4" P-401, 6" P-211, 8" P-154, 12" P-152
2018	TW E	NEW CONSTRUCTION/ 2" P-401, 10" P-211, 12" P-152
2018	RW 5-23 BLAST PADS	NEW CONSTRUCTION/ 4" P-401, 6" P-211, 8" P-154, 12" P-152

LEGEND

- PROJECTS YEAR 2013
- PROJECTS YEAR 2014
- PROJECTS YEAR 2015
- PROJECTS YEAR 2016
- PROJECTS YEAR 2017
- PROJECTS YEAR 2018
- PROJECTS YEAR 2019
- PROJECTS YEAR 2020
- PROJECTS YEAR 2021
- PROJECTS YEAR 2022

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.






LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- PCI 86-100 GOOD
- PCI 71-85 SATISFACTORY
- PCI 56-70 FAIR
- PCI 41-55 POOR
- PCI 26-40 VERY POOR
- PCI 11-25 SERIOUS
- PCI 0-10 FAILED

SECTION NO.
PCI NO.

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.



Appendix D

Inspection Photograph Documentation



Runway 11-29, Section 6205, Sample Unit 163 – Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 11-29, Section 6205, Sample Unit 151 – Low Severity (45) Depression, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 11-29, Section 6210, Sample Unit 136 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 11-29, Section 6205, Sample Unit 103 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 5-23, Section 6115, Sample Unit 147 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 5-23, Section 6105, Sample Unit 135 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 5-23, Section 6105, Sample Unit 114 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 5-23, Section 6105, Sample Unit 101 – (42) Bleeding, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Taxiway B, Section 215, Sample Unit 111 – Low Severity (48) Longitudinal and Transverse Cracking, Medium Severity (52) Raveling, High Severity (52) Raveling



Taxiway B, Section 205, Sample Unit 204 – Low Severity (43) Block Cracking, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling



Taxiway B, Section 230, Sample Unit 105 – (42) Bleeding, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Apron, Section 4110, Sample Unit 255 – (42) Bleeding, Low Severity (45) Depression, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, Low Severity (57) Weathering



Apron, Section 4105, Sample Unit 154 – Low Severity (43) Block Cracking, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling



Apron T-Hangars, Section 4205, Sample Unit 454 – Low Severity (43) Block Cracking, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling, Low Severity (54) Shoving, Low Severity (56) Swelling



Apron North, Section 4505, Sample Unit 305 – Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Apron, Section 4125, Sample Unit 101 – Low Severity (41) Alligator Cracking, Medium Severity (41) Alligator Cracking, Medium Severity (52) Raveling, High Severity (52) Raveling



Apron, Section 4125, Sample Unit 101 – Low Severity (45) Depression, Medium Severity (45) Depression, Low Severity (48)
Longitudinal and Transverse Cracking

Appendix E

Inspection Distress Details

Re-Inspection Report

FDOT

Generated Date 7/5/2017

Page 1 of 58

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT		
Branch:	AP	Name:	APRON AREA	Use:	APRON	Area: 446,940 SqFt
Section:	4105	of 6	From: -	To: -	Last Const.: 1/1/1986	
Surface:	AAC	Family: C9N59-GA-AP-AAC-APC	Zone:	Category:	Rank: P	
Area:	161,696 SqFt	Length:	250 Ft	Width:	650 Ft	
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length: Ft
Shoulder:		Street Type:		Grade:	0	Lanes: 0
Section Comments:						
Work Date:	1/1/1973	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1986	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1986	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	3/8/2017	TotalSamples:	34	Surveyed:	4	
Conditions:	PCI: 49					
Inspection Comments:						
Sample Number:	154	Type:	R	Area:	5000.00 SqFt	PCI: 49
Sample Comments:						
52	RAVELING	M	100.00	SqFt		
43	BLOCK CR	L	2000.00	SqFt		
48	L & T CR	L	410.00	Ft		
49	OIL SPILLAGE	N	24.00	SqFt		
52	RAVELING	L	4900.00	SqFt		
Sample Number:	200	Type:	R	Area:	5000.00 SqFt	PCI: 47
Sample Comments:						
52	RAVELING	M	150.00	SqFt		
43	BLOCK CR	M	200.00	SqFt		
43	BLOCK CR	L	4800.00	SqFt		
52	RAVELING	L	4850.00	SqFt		
Sample Number:	299	Type:	R	Area:	5000.00 SqFt	PCI: 49
Sample Comments:						
52	RAVELING	M	250.00	SqFt		
43	BLOCK CR	L	5000.00	SqFt		
45	DEPRESSION	L	156.00	SqFt		
52	RAVELING	L	4750.00	SqFt		
Sample Number:	352	Type:	R	Area:	4392.00 SqFt	PCI: 51
Sample Comments:						
43	BLOCK CR	L	2500.00	SqFt		
52	RAVELING	M	88.00	SqFt		
48	L & T CR	L	298.00	Ft		
52	RAVELING	L	4304.00	SqFt		

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT									
Branch:	AP	Name:	APRON AREA		Use:	APRON	Area:	446,940 SqFt					
Section:	4110	of 6	From:	-		To:	-		Last Const.:	1/1/1990			
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC	Zone:		Category:		Rank:	P				
Area:	174,018 SqFt		Length:	680 Ft		Width:	250 Ft						
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:		Street Type:		Grade:	0		Lanes:	0					
Section Comments:													
Work Date:	1/1/1990		Work Type:			BUILT		Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/2010		Work Type:			Surface Seal - Rejuvenating			Code:	SS-RE		Is Major M&R:	False
Last Insp. Date:	3/8/2017		TotalSamples:	39		Surveyed:	4						
Conditions:	PCI:	41											
Inspection Comments:													
Sample Number:	104	Type:	R	Area:	4500.00 SqFt		PCI:	25					
Sample Comments:													
43	BLOCK CR	L	3375.00	SqFt									
43	BLOCK CR	M	1125.00	SqFt									
45	DEPRESSION	L	6.00	SqFt									
52	RAVELING	M	4500.00	SqFt									
56	SWELLING	L	34.00	SqFt									
Sample Number:	201	Type:	R	Area:	5000.00 SqFt		PCI:	40					
Sample Comments:													
43	BLOCK CR	L	2263.00	SqFt									
48	L & T CR	L	273.00	Ft									
50	PATCHING	L	12.00	SqFt									
52	RAVELING	L	2725.00	SqFt									
52	RAVELING	M	2263.00	SqFt									
Sample Number:	255	Type:	R	Area:	5000.00 SqFt		PCI:	52					
Sample Comments:													
42	BLEEDING	N	1.00	SqFt									
43	BLOCK CR	L	1950.00	SqFt									
45	DEPRESSION	L	60.00	SqFt									
48	L & T CR	L	244.00	Ft									
57	WEATHERING	L	3050.00	SqFt									
52	RAVELING	L	1950.00	SqFt									
56	SWELLING	L	19.00	SqFt									
Sample Number:	401	Type:	R	Area:	3618.00 SqFt		PCI:	49					
Sample Comments:													
43	BLOCK CR	L	2500.00	SqFt									
45	DEPRESSION	L	90.00	SqFt									
48	L & T CR	L	15.00	Ft									
52	RAVELING	L	1447.00	SqFt									
57	WEATHERING	L	2171.00	SqFt									

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	AP		Name:	APRON AREA		Use:	APRON	Area:	446,940 SqFt		
Section:	4115	of 6	From:	-			To:	-		Last Const.:	1/1/1960
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	32,078 SqFt		Length:	250 Ft		Width:	130 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1960		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	9		Surveyed:	1				
Conditions:	PCI:	35									
Inspection Comments:											
Sample Number:	201	Type:	R	Area:	5000.00 SqFt		PCI:	35			
Sample Comments:											
43	BLOCK CR	L	3238.00	SqFt							
43	BLOCK CR	M	1750.00	SqFt							
45	DEPRESSION	L	60.00	SqFt							
52	RAVELING	L	4896.00	SqFt							
50	PATCHING	L	12.00	SqFt							
52	RAVELING	M	92.00	SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	AP	Name:	APRON AREA		Use:	APRON	Area:	446,940 SqFt			
Section:	4120	of	6	From:	-	To:	-	Last Const.:	1/1/1980		
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	49,139 SqFt	Length:	240 Ft		Width:	200 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1980		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	11		Surveyed:	2				
Conditions:	PCI:	52									
Inspection Comments:											
Sample Number:	301	Type:	R	Area:	5000.00 SqFt		PCI:	52			
Sample Comments:											
43	BLOCK CR	L	5000.00 SqFt								
52	RAVELING	L	4750.00 SqFt								
52	RAVELING	M	250.00 SqFt								
Sample Number:	501	Type:	R	Area:	4920.00 SqFt		PCI:	52			
Sample Comments:											
43	BLOCK CR	L	4920.00 SqFt								
52	RAVELING	L	4674.00 SqFt								
52	RAVELING	M	246.00 SqFt								

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT			
Branch:	AP	Name:	APRON AREA		Use:	APRON	Area: 446,940 SqFt
Section:	4123	of 6	From:	-	To:	-	Last Const.: 1/1/1997
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC		Zone:	Category:	Rank: P
Area:	17,601 SqFt	Length:	200 Ft	Width:	100 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1980	Work Type:	BUILT		Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1997	Work Type:	MILL and OVERLAY		Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	3/8/2017	TotalSamples:	4	Surveyed:	1		
Conditions:	PCI: 72						
Inspection Comments:							
Sample Number:	100	Type:	R	Area:	3989.00 SqFt	PCI:	72
Sample Comments:							
42	BLEEDING	N	1.00 SqFt				
48	L & T CR	L	271.00 Ft				
52	RAVELING	L	199.00 SqFt				
57	WEATHERING	L	3790.00 SqFt				

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT					
Branch:	AP	Name:	APRON AREA		Use:	APRON	Area:	446,940 SqFt	
Section:	4125	of	6	From:	-	To:	-	Last Const.:	1/1/1980
Surface:	AC	Family:	C9N59-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	12,408 SqFt	Length:	250 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1980	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/8/2017	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI:	15							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	5306.00 SqFt	PCI:	15		
Sample Comments:									
41	ALLIGATOR CR	M	90.00	SqFt					
45	DEPRESSION	M	36.00	SqFt					
41	ALLIGATOR CR	L	101.00	SqFt					
45	DEPRESSION	L	18.00	SqFt					
48	L & T CR	L	392.00	Ft					
52	RAVELING	M	4500.00	SqFt					
56	SWELLING	L	75.00	SqFt					
52	RAVELING	H	806.00	SqFt					

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	AP HANG		Name:	APRON TO HANGAR		Use:	APRON	Area:	23,666 SqFt		
Section:	4405	of 1	From:	-			To:	-		Last Const.:	1/1/1995
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	23,666 SqFt	Length:	210 Ft		Width:	160 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft			Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0			Lanes:	0	
Section Comments:											
Work Date:	1/1/1995		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI:	47									
Inspection Comments:											
Sample Number:	200	Type:	R	Area:	5000.00 SqFt		PCI:	47			
Sample Comments:											
49	OIL SPILLAGE	N	28.00	SqFt							
43	BLOCK CR	L	4750.00	SqFt							
43	BLOCK CR	M	250.00	SqFt							
52	RAVELING	L	1000.00	SqFt							
57	WEATHERING	L	4000.00	SqFt							

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	AP N		Name:	APRON NORTH		Use:	APRON		Area:	188,239 SqFt	
Section:	4505		of	1		From:	-		To:	-	
Surface:	AC		Family:	C9N59-GA-AP-AC		Zone:			Category:		
Area:	188,239 SqFt		Length:	1,650 Ft		Width:	100 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2011		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	3/8/2017		TotalSamples:	45		Surveyed:	5				
Conditions:	PCI: 82										
Inspection Comments:											
Sample Number:	150		Type:	R		Area:	5000.00 SqFt		PCI:	74	
Sample Comments:											
45	DEPRESSION		L	200.00 SqFt							
48	L & T CR		L	19.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	156		Type:	R		Area:	3100.00 SqFt		PCI:	89	
Sample Comments:											
48	L & T CR		L	35.00 Ft							
57	WEATHERING		L	3100.00 SqFt							
Sample Number:	252		Type:	R		Area:	5000.00 SqFt		PCI:	85	
Sample Comments:											
52	RAVELING		L	100.00 SqFt							
48	L & T CR		L	70.00 Ft							
57	WEATHERING		L	4900.00 SqFt							
Sample Number:	305		Type:	R		Area:	5000.00 SqFt		PCI:	86	
Sample Comments:											
52	RAVELING		L	100.00 SqFt							
48	L & T CR		L	17.00 Ft							
57	WEATHERING		L	4900.00 SqFt							
Sample Number:	404		Type:	R		Area:	3420.00 SqFt		PCI:	78	
Sample Comments:											
45	DEPRESSION		L	92.00 SqFt							
48	L & T CR		L	13.00 Ft							
57	WEATHERING		L	3420.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT				
Branch:	AP RW11-29		Name:	TURNAROUND APRON RW 11-29	Use:	APRON	Area:	22,770 SqFt
Section:	5105	of 2	From:	-	To:	-	Last Const.:	1/1/1997
Surface:	AAC	Family:	C9N59-GA-AP-AAC-APC	Zone:		Category:	Rank:	P
Area:	11,639 SqFt	Length:	200 Ft	Width:	60 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1942	Work Type: BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1997	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/8/2017	TotalSamples:	2	Surveyed:	1			
Conditions:	PCI: 50							
Inspection Comments:								
Sample Number:	183	Type:	R	Area:	6047.00 SqFt	PCI:	50	
Sample Comments:								
56	SWELLING	L	9.00	SqFt				
43	BLOCK CR	L	5230.00	SqFt				
45	DEPRESSION	L	75.00	SqFt				
52	RAVELING	L	907.00	SqFt				
57	WEATHERING	L	5140.00	SqFt				

Network:		GIF		Name:		WINTER HAVEN'S GILBERT AIRPORT											
Branch:		AP RW11-29		Name:		TURNAROUND APRON RW 11-29		Use:		APRON		Area:		22,770 SqFt			
Section:		5110		of 2		From:		-		To:		-		Last Const.:		1/1/1997	
Surface:		AAC		Family:		C9N59-GA-AP-AAC-APC		Zone:		Category:		Rank:		P			
Area:		11,131 SqFt		Length:		200 Ft		Width:		55 Ft							
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:				Street Type:				Grade:		0		Lanes:		0			
Section Comments:																	
Work Date:		1/1/1942		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True			
Work Date:		1/1/1997		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True			
Last Insp. Date:		3/8/2017		TotalSamples:		2		Surveyed:		1							
Conditions:		PCI: 50															
Inspection Comments:																	
Sample Number:		181		Type:		R		Area:		5568.00 SqFt		PCI:		50			
Sample Comments:																	
43	BLOCK CR		M		600.00		SqFt										
43	BLOCK CR		L		557.00		SqFt										
45	DEPRESSION		L		150.00		SqFt										
48	L & T CR		L		493.00		Ft										
52	RAVELING		L		1114.00		SqFt										
57	WEATHERING		L		4454.00		SqFt										

Network:	GIF		Name:		WINTER HAVEN'S GILBERT AIRPORT						
Branch:	APT-HANG		Name:		APRON T-HANGARS TAXILANES		Use:	APRON	Area:	236,167 SqFt	
Section:	4205	of 4	From:	-			To:	-		Last Const.:	1/1/1984
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:		P
Area:	159,635 SqFt		Length:		6,500 Ft		Width:		25 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:		0		Lanes:		0
Section Comments:											
Work Date:	1/1/1984		Work Type:				OVERLAY		Code:	IMPORTED	
Work Date:	1/1/1984		Work Type:				BUILT		Code:	IMPORTED	
Last Insp. Date: 3/8/2017											
TotalSamples:		36		Surveyed:		6					
Conditions:	PCI:		55								
Inspection Comments:											
Sample Number:	152	Type:	R	Area:		5000.00 SqFt		PCI:		59	
Sample Comments:											
45	DEPRESSION		L	9.00 SqFt							
48	L & T CR		L	231.00 Ft							
52	RAVELING		L	4000.00 SqFt							
52	RAVELING		M	1000.00 SqFt							
Sample Number:	450	Type:	R	Area:		4386.00 SqFt		PCI:		57	
Sample Comments:											
52	RAVELING		M	16.00 SqFt							
48	L & T CR		L	338.00 Ft							
52	RAVELING		L	4370.00 SqFt							
56	SWELLING		L	19.00 SqFt							
54	SHOVING		L	55.00 SqFt							
Sample Number:	454	Type:	R	Area:		4386.00 SqFt		PCI:		49	
Sample Comments:											
52	RAVELING		M	25.00 SqFt							
43	BLOCK CR		L	326.00 SqFt							
48	L & T CR		L	187.00 Ft							
52	RAVELING		L	4361.00 SqFt							
56	SWELLING		L	150.00 SqFt							
54	SHOVING		M	83.00 SqFt							
Sample Number:	506	Type:	R	Area:		3891.00 SqFt		PCI:		49	
Sample Comments:											
52	RAVELING		M	30.00 SqFt							
43	BLOCK CR		L	160.00 SqFt							
48	L & T CR		L	170.00 Ft							
52	RAVELING		L	3861.00 SqFt							
56	SWELLING		L	122.00 SqFt							
54	SHOVING		M	64.00 SqFt							
Sample Number:	550	Type:	R	Area:		4386.00 SqFt		PCI:		59	
Sample Comments:											
52	RAVELING		M	6.00 SqFt							
48	L & T CR		L	402.00 Ft							
52	RAVELING		L	4380.00 SqFt							
54	SHOVING		L	15.00 SqFt							
56	SWELLING		L	27.00 SqFt							
Sample Number:	604	Type:	R	Area:		4386.00 SqFt		PCI:		55	
Sample Comments:											
52	RAVELING		M	16.00 SqFt							
45	DEPRESSION		L	54.00 SqFt							
48	L & T CR		L	32.00 Ft							
52	RAVELING		L	4370.00 SqFt							

E-11

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	APT-HANG		Name:	APRON T-HANGARS TAXILANES		Use:	APRON	Area:	236,167 SqFt	
Section:	4210	of 4	From:	-		To:	-		Last Const.:	1/1/2009
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:			Category:	Rank: P	
Area:	13,307 SqFt		Length:	550 Ft		Width:	20 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	1/1/2009		Work Type: New Construction - Initial			Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	3/8/2017		TotalSamples:	3		Surveyed:	1			
Conditions:	PCI: 87									
Inspection Comments:										
Sample Number:	656	Type:	R	Area:	4000.00 SqFt		PCI:	87		
Sample Comments:										
48	L & T CR		L	6.00 Ft						
52	RAVELING		L	80.00 SqFt						
57	WEATHERING		L	3920.00 SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	APT T-HANG		Name:	APRON T-HANGARS TAXILANES		Use:	APRON	Area:	236,167 SqFt		
Section:	4305	of 4	From:	-			To:	-		Last Const.:	1/1/1984
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	43,314 SqFt		Length:	400 Ft		Width:	120 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1984		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	10		Surveyed:	1				
Conditions:	PCI: 57										
Inspection Comments:											
Sample Number:	103	Type:	R	Area:	5200.00 SqFt		PCI:	57			
Sample Comments:											
48	L & T CR	L	207.00 Ft								
49	OIL SPILLAGE	N	39.00 SqFt								
52	RAVELING	L	4500.00 SqFt								
52	RAVELING	M	700.00 SqFt								
48	L & T CR	M	10.00 Ft								

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	APT-HANG		Name:	APRON T-HANGARS TAXILANES		Use:	APRON	Area:	236,167 SqFt		
Section:	4310	of 4	From:	-		To:	-		Last Const.:	1/1/1984	
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:			Category:	Rank: P		
Area:	19,911 SqFt		Length:	300 Ft		Width:	20 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0	Lanes:		0			
Section Comments:											
Work Date:	1/1/1984		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI: 40										
Inspection Comments:											
Sample Number:	402	Type:	R	Area:	5000.00 SqFt		PCI:	40			
Sample Comments:											
43	BLOCK CR	L	87.00	SqFt							
48	L & T CR	L	21.00	Ft							
52	RAVELING	L	2000.00	SqFt							
52	RAVELING	M	3000.00	SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	AP W		Name:	APRON WEST		Use:	APRON	Area:	37,020 SqFt		
Section:	4705	of 1	From:	-			To:	-		Last Const.:	1/1/1965
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	37,020 SqFt	Length:	250 Ft		Width:	100 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1965		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	7		Surveyed:	1				
Conditions:	PCI:	12									
Inspection Comments:											
Sample Number:	203	Type:	R	Area:	5800.00 SqFt		PCI:	12			
Sample Comments:											
52	RAVELING	H	682.00	SqFt							
41	ALLIGATOR CR	L	823.00	SqFt							
43	BLOCK CR	L	4000.00	SqFt							
45	DEPRESSION	L	177.00	SqFt							
48	L & T CR	L	109.00	Ft							
50	PATCHING	L	98.00	SqFt							
52	RAVELING	M	5020.00	SqFt							

Network:	GIF		Name:		WINTER HAVEN'S GILBERT AIRPORT					
Branch:	RW 11-29		Name:		RUNWAY 11-29		Use:	RUNWAY	Area:	389,901 SqFt
Section:	6205 of 2		From:	-		To:	-		Last Const.:	1/1/1997
Surface:	AAC		Family:	C9N59-GA-RW-AAC-APC		Zone:			Category:	Rank: S
Area:	367,600 SqFt		Length:	3,673 Ft		Width:	100 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1965		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1997		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	73		Surveyed:	15			
Conditions:	PCI: 65									
Inspection Comments:										
Sample Number:	103		Type:	R		Area:	5000.00 SqFt		PCI:	68
Sample Comments:										
48	L & T CR		L	339.00 Ft						
52	RAVELING		L	3500.00 SqFt						
57	WEATHERING		L	1500.00 SqFt						
Sample Number:	109		Type:	R		Area:	5000.00 SqFt		PCI:	63
Sample Comments:										
48	L & T CR		L	161.00 Ft						
48	L & T CR		M	150.00 Ft						
52	RAVELING		L	3500.00 SqFt						
57	WEATHERING		L	1500.00 SqFt						
Sample Number:	115		Type:	R		Area:	5000.00 SqFt		PCI:	63
Sample Comments:										
48	L & T CR		L	285.00 Ft						
48	L & T CR		M	100.00 Ft						
52	RAVELING		L	3500.00 SqFt						
57	WEATHERING		L	1500.00 SqFt						
Sample Number:	121		Type:	R		Area:	5000.00 SqFt		PCI:	62
Sample Comments:										
48	L & T CR		M	50.00 Ft						
48	L & T CR		L	357.00 Ft						
52	RAVELING		L	3500.00 SqFt						
56	SWELLING		L	14.00 SqFt						
57	WEATHERING		L	1500.00 SqFt						
Sample Number:	127		Type:	R		Area:	5000.00 SqFt		PCI:	64
Sample Comments:										
48	L & T CR		M	50.00 Ft						
48	L & T CR		L	325.00 Ft						
52	RAVELING		L	3000.00 SqFt						
57	WEATHERING		L	2000.00 SqFt						
Sample Number:	139		Type:	R		Area:	5000.00 SqFt		PCI:	64
Sample Comments:										
48	L & T CR		M	50.00 Ft						
48	L & T CR		L	273.00 Ft						
52	RAVELING		L	3000.00 SqFt						
57	WEATHERING		L	2000.00 SqFt						
Sample Number:	143		Type:	R		Area:	5000.00 SqFt		PCI:	69
Sample Comments:										

48	L & T CR	L	280.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
Sample Number: 147 Type: R Area: 5000.00 SqFt PCI: 69				
Sample Comments:				
48	L & T CR	L	292.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
Sample Number: 151 Type: R Area: 5000.00 SqFt PCI: 68				
Sample Comments:				
45	DEPRESSION	L	12.00	SqFt
48	L & T CR	L	328.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
Sample Number: 155 Type: R Area: 5000.00 SqFt PCI: 69				
Sample Comments:				
48	L & T CR	L	310.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
Sample Number: 159 Type: R Area: 5000.00 SqFt PCI: 64				
Sample Comments:				
48	L & T CR	M	50.00	Ft
48	L & T CR	L	286.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
Sample Number: 163 Type: R Area: 5000.00 SqFt PCI: 64				
Sample Comments:				
48	L & T CR	L	228.00	Ft
48	L & T CR	M	50.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
Sample Number: 167 Type: R Area: 5000.00 SqFt PCI: 64				
Sample Comments:				
48	L & T CR	M	25.00	Ft
48	L & T CR	L	269.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
Sample Number: 171 Type: R Area: 5000.00 SqFt PCI: 64				
Sample Comments:				
48	L & T CR	L	269.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt
48	L & T CR	M	25.00	Ft
Sample Number: 175 Type: R Area: 5000.00 SqFt PCI: 64				
Sample Comments:				
48	L & T CR	M	20.00	Ft
48	L & T CR	L	300.00	Ft
52	RAVELING	L	3000.00	SqFt
57	WEATHERING	L	2000.00	SqFt

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	RW 11-29		Name:	RUNWAY 11-29		Use:	RUNWAY	Area:	389,901 SqFt		
Section:	6210 of 2		From:	-		To:	-		Last Const.:	1/1/2010	
Surface:	AAC		Family:	C9N59-GA-RW-AAC-APC		Zone:			Category:	Rank: S	
Area:	22,301 SqFt		Length:	214 Ft		Width:	100 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1997		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Mill and Overlay				Code:	ML-OL		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	4		Surveyed: 1					
Conditions:	PCI: 86										
Inspection Comments:											
Sample Number:	136		Type:	R		Area:	5080.00 SqFt		PCI:	86	
Sample Comments:											
48	L & T CR		L	125.00 Ft							
57	WEATHERING		L	5080.00 SqFt							

Network:	GIF		Name:		WINTER HAVEN'S GILBERT AIRPORT								
Branch:	RW 5-23		Name:		RUNWAY 5-23		Use:	RUNWAY	Area:	500,600 SqFt			
Section:	6105 of 6		From:		-		To:	-		Last Const.:	1/1/2010		
Surface:	AAC		Family:		C9N59-GA-RW-AAC-APC		Zone:		Category:		Rank:	P	
Area:	182,500 SqFt		Length:		3,650 Ft		Width:		50 Ft				
Slabs:			Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft	
Shoulder:			Street Type:				Grade:		0		Lanes:	0	
Section Comments:													
Work Date:	1/1/1942		Work Type:					OVERLAY		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1985		Work Type:					OVERLAY		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1985		Work Type:					BUILT		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2010		Work Type:					MILL and OVERLAY		Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:		36		Surveyed:		7				
Conditions:	PCI:		81										
Inspection Comments:													
Sample Number:	101		Type:	R		Area:		5000.00 SqFt		PCI:			72
Sample Comments:													
42	BLEEDING		N		135.00 SqFt								
48	L & T CR		L		21.00 Ft								
52	RAVELING		L		250.00 SqFt								
57	WEATHERING		L		4750.00 SqFt								
Sample Number:	107		Type:	R		Area:		5000.00 SqFt		PCI:			85
Sample Comments:													
48	L & T CR		L		32.00 Ft								
52	RAVELING		L		150.00 SqFt								
57	WEATHERING		L		4850.00 SqFt								
Sample Number:	114		Type:	R		Area:		5000.00 SqFt		PCI:			83
Sample Comments:													
48	L & T CR		L		71.00 Ft								
52	RAVELING		L		250.00 SqFt								
57	WEATHERING		L		4750.00 SqFt								
Sample Number:	122		Type:	R		Area:		5000.00 SqFt		PCI:			82
Sample Comments:													
48	L & T CR		L		116.00 Ft								
52	RAVELING		L		250.00 SqFt								
57	WEATHERING		L		4750.00 SqFt								
Sample Number:	126		Type:	R		Area:		5000.00 SqFt		PCI:			83
Sample Comments:													
48	L & T CR		L		73.00 Ft								
52	RAVELING		L		250.00 SqFt								
57	WEATHERING		L		4750.00 SqFt								
Sample Number:	130		Type:	R		Area:		5000.00 SqFt		PCI:			82
Sample Comments:													
48	L & T CR		L		117.00 Ft								
52	RAVELING		L		250.00 SqFt								
57	WEATHERING		L		4750.00 SqFt								
Sample Number:	135		Type:	R		Area:		5000.00 SqFt		PCI:			83
Sample Comments:													
48	L & T CR		L		71.00 Ft								
52	RAVELING		L		250.00 SqFt								
57	WEATHERING		L		4750.00 SqFt								

E-20

Network:	GIF		Name:		WINTER HAVEN'S GILBERT AIRPORT					
Branch:	RW 5-23		Name:		RUNWAY 5-23		Use:	RUNWAY	Area:	500,600 SqFt
Section:	6110	of 6	From:	-				To:	-	Last Const.: 1/1/2010
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:		Category:		Rank: P	
Area:	182,500 SqFt		Length:	3,650 Ft		Width:	50 Ft			
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0	
Section Comments:										
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1985		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	38		Surveyed: 7				
Conditions:	PCI: 88									
Inspection Comments:										
Sample Number:	312	Type:	R	Area:	5000.00 SqFt		PCI:	77		
Sample Comments:										
42	BLEEDING	N	170.00 SqFt							
57	WEATHERING	L	5000.00 SqFt							
Sample Number:	324	Type:	R	Area:	5000.00 SqFt		PCI:	90		
Sample Comments:										
48	L & T CR	L	4.00 Ft							
52	RAVELING	L	25.00 SqFt							
57	WEATHERING	L	4975.00 SqFt							
Sample Number:	348	Type:	R	Area:	5000.00 SqFt		PCI:	92		
Sample Comments:										
48	L & T CR	L	3.00 Ft							
57	WEATHERING	L	5000.00 SqFt							
Sample Number:	364	Type:	R	Area:	5000.00 SqFt		PCI:	90		
Sample Comments:										
48	L & T CR	L	17.00 Ft							
57	WEATHERING	L	5000.00 SqFt							
Sample Number:	504	Type:	R	Area:	5000.00 SqFt		PCI:	89		
Sample Comments:										
48	L & T CR	L	63.00 Ft							
57	WEATHERING	L	5000.00 SqFt							
Sample Number:	560	Type:	R	Area:	5000.00 SqFt		PCI:	88		
Sample Comments:										
48	L & T CR	L	90.00 Ft							
57	WEATHERING	L	5000.00 SqFt							
Sample Number:	572	Type:	R	Area:	5000.00 SqFt		PCI:	90		
Sample Comments:										
48	L & T CR	L	19.00 Ft							
57	WEATHERING	L	5000.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT					
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	500,600 SqFt
Section:	6115	of 6	From:	-			To:	-	Last Const.: 1/1/2010
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:	Category:		Rank:	P
Area:	50,300 SqFt		Length:	1,000 Ft		Width:	100 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	1/1/1991		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	10		Surveyed: 2			
Conditions:	PCI:	85							
Inspection Comments:									
Sample Number:	141	Type:	R	Area:	5000.00 SqFt		PCI:	84	
Sample Comments:									
48	L & T CR	L	20.00 Ft						
52	RAVELING	L	250.00 SqFt						
57	WEATHERING	L	4750.00 SqFt						
Sample Number:	147	Type:	R	Area:	5000.00 SqFt		PCI:	85	
Sample Comments:									
48	L & T CR	L	12.00 Ft						
52	RAVELING	L	250.00 SqFt						
57	WEATHERING	L	4750.00 SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	500,600 SqFt		
Section:	6117 of 6		From:	-		To:	-		Last Const.:	1/1/2010	
Surface:	AC		Family:	C9N59-GA-RW-AC		Zone:			Category:	Rank: P	
Area:	50,300 SqFt		Length:	1,006 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2010		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	12		Surveyed:	3				
Conditions:	PCI: 89										
Inspection Comments:											
Sample Number:	384		Type:	R		Area:	5000.00 SqFt		PCI:	90	
Sample Comments:											
52	RAVELING		L	100.00 SqFt							
57	WEATHERING		L	4900.00 SqFt							
Sample Number:	400		Type:	R		Area:	2650.00 SqFt		PCI:	87	
Sample Comments:											
48	L & T CR		L	5.00 Ft							
52	RAVELING		L	50.00 SqFt							
57	WEATHERING		L	2600.00 SqFt							
Sample Number:	596		Type:	R		Area:	5000.00 SqFt		PCI:	90	
Sample Comments:											
52	RAVELING		L	100.00 SqFt							
57	WEATHERING		L	4900.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT									
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	500,600 SqFt				
Section:	6120	of 6	From:	-			To:	-		Last Const.:	1/1/2010		
Surface:	AAC	Family:	C9N59-GA-RW-AAC-APC		Zone:				Category:	Rank:	P		
Area:	17,500 SqFt		Length:	350 Ft		Width:	100 Ft						
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:		0			
Section Comments:													
Work Date:	1/1/1942		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1960		Work Type:				OVERLAY		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1985		Work Type:				OVERLAY		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1997		Work Type:				OVERLAY		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type:				MILL and OVERLAY		Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	4		Surveyed:		1					
Conditions:	PCI:		82										
Inspection Comments:													
Sample Number:	117	Type:	R	Area:	5000.00 SqFt			PCI:	82				
Sample Comments:													
48	L & T CR		L	116.00 Ft									
52	RAVELING		L	250.00 SqFt									
57	WEATHERING		L	4750.00 SqFt									

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	500,600 SqFt		
Section:	6122	of 6	From:	-			To:	-		Last Const.:	1/1/2010
Surface:	AC	Family:	C9N59-GA-RW-AC		Zone:		Category:		Rank:	P	
Area:	17,500 SqFt		Length:	350 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2010		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	87									
Inspection Comments:											
Sample Number:	336	Type:	R	Area:	4375.00 SqFt		PCI:	87			
Sample Comments:											
52	RAVELING		L	88.00 SqFt							
48	L & T CR		L	7.00 Ft							
57	WEATHERING		L	4287.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT					
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	149,938 SqFt
Section:	110	of 6	From:	-			To:	-	Last Const.: 1/1/1997
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:	Category:		Rank: P	
Area:	62,789 SqFt		Length:	11,500 Ft		Width:	50 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1997		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	13		Surveyed:	2		
Conditions:	PCI: 63								
Inspection Comments:									
Sample Number:	406	Type:	R	Area:	5000.00 SqFt		PCI:	63	
Sample Comments:									
48	L & T CR		L	462.00 Ft					
48	L & T CR		M	10.00 Ft					
52	RAVELING		L	500.00 SqFt					
57	WEATHERING		L	4500.00 SqFt					
Sample Number:	411	Type:	R	Area:	4870.00 SqFt		PCI:	64	
Sample Comments:									
48	L & T CR		L	613.00 Ft					
52	RAVELING		L	731.00 SqFt					
57	WEATHERING		L	4139.00 SqFt					

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	149,938 SqFt		
Section:	115	of 6	From:	-			To:	-		Last Const.:	1/1/1997
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Category:	Rank: P	
Area:	2,744 SqFt		Length:	60 Ft		Width:	30 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	1/1/1997		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Last Insp. Date:	3/8/2017		TotalSamples:		1		Surveyed:		1		
Conditions:	PCI: 37										
Inspection Comments:											
Sample Number:	100	Type:	R	Area:		2744.00 SqFt		PCI:	37		
Sample Comments:											
56	SWELLING		L	10.00 SqFt							
50	PATCHING		M	540.00 SqFt							
45	DEPRESSION		L	112.00 SqFt							
48	L & T CR		L	167.00 Ft							
52	RAVELING		L	412.00 SqFt							
54	SHOVING		L	16.00 SqFt							
57	WEATHERING		L	1792.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT								
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	149,938 SqFt			
Section:	320	of	6	From:	-		To:	-		Last Const.:	1/1/2002	
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Category:	Rank: P		
Area:	23,750 SqFt		Length:	500 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2002		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date: 3/8/2017												
TotalSamples: 6												
Surveyed: 2												
Conditions: PCI: 51												
Inspection Comments:												
Sample Number:	101		Type:	R		Area:	3500.00 SqFt		PCI:	52		
Sample Comments:												
52	RAVELING		M	300.00		SqFt						
43	BLOCK CR		L	1624.00		SqFt						
48	L & T CR		L	179.00		Ft						
52	RAVELING		L	3200.00		SqFt						
Sample Number:	103		Type:	R		Area:	3500.00 SqFt		PCI:	51		
Sample Comments:												
52	RAVELING		M	300.00		SqFt						
43	BLOCK CR		L	1930.00		SqFt						
48	L & T CR		L	167.00		Ft						
52	RAVELING		L	3200.00		SqFt						

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT				
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	149,938 SqFt
Section:	405	of 6	From:	-			To:	-	Last Const.: 1/1/1997
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:	Category:		Rank:	P
Area:	7,000 SqFt		Length:	135 Ft		Width:	50 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED	
Work Date:	1/1/1997		Work Type: MILL and OVERLAY				Code:	ML-OV	
Last Insp. Date:	3/8/2017		TotalSamples:	2		Surveyed:	1		
Conditions:	PCI: 51								
Inspection Comments:									
Sample Number:	350	Type:	R	Area:	3563.00 SqFt		PCI:	51	
Sample Comments:									
52	RAVELING		M	200.00	SqFt				
43	BLOCK CR		L	2496.00	SqFt				
48	L & T CR		L	120.00	Ft				
52	RAVELING		L	3363.00	SqFt				

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT					
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	149,938 SqFt
Section:	410	of 6	From:	-			To:	-	Last Const.: 1/1/1960
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC	Zone:				Category:	Rank: P
Area:	43,255 SqFt	Length:	880 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1960		Work Type: BUILT			Code:	IMPORTED		Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	8		Surveyed:	2		
Conditions:	PCI:	32							
Inspection Comments:									
Sample Number:	353	Type:	R	Area:	5000.00 SqFt		PCI:	33	
Sample Comments:									
43	BLOCK CR	M	4300.00	SqFt					
48	L & T CR	L	56.00	Ft					
52	RAVELING	L	4000.00	SqFt					
52	RAVELING	M	1000.00	SqFt					
Sample Number:	357	Type:	R	Area:	5050.00 SqFt		PCI:	31	
Sample Comments:									
43	BLOCK CR	H	150.00	SqFt					
43	BLOCK CR	M	4900.00	SqFt					
52	RAVELING	L	4500.00	SqFt					
52	RAVELING	M	550.00	SqFt					

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT		
Branch:	TW A		Name:	TAXIWAY A		Use: TAXIWAY
Area:	10,400 SqFt		Length:	200 Ft		Width: 110 Ft
Slabs:	Slab Length:		Ft	Slab Width:		Ft
Shoulder:	Street Type:		Grade:	0		Lanes: 0
Section Comments:						
Work Date:	1/1/1942		Work Type:	BUILT		Code: IMPORTED
Work Date:	1/1/1997		Work Type:	MILL and OVERLAY		Code: ML-OV
Last Insp. Date:	3/8/2017		TotalSamples:	2		Surveyed: 1
Conditions:	PCI: 58					
Inspection Comments:						
Sample Number:	359		Type:	R		Area: 4823.00 SqFt
Sample Comments:						
42	BLEEDING		N	3.00		SqFt
43	BLOCK CR		L	270.00		SqFt
48	L & T CR		L	616.00		Ft
52	RAVELING		L	241.00		SqFt
57	WEATHERING		L	4582.00		SqFt

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT					
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY	Area:	8,491 SqFt	
Section:	105	of	1	From:	-	To:	-	Last Const.:	1/1/1984	
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P
Area:	8,491 SqFt	Length:	200 Ft		Width:	30 Ft				
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1984		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1984		Work Type: BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	2		Surveyed:	1			
Conditions:	PCI:	55								
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	3945.00 SqFt		PCI:	55		
Sample Comments:										
45	DEPRESSION	L	56.00	SqFt						
48	L & T CR	L	341.00	Ft						
52	RAVELING	L	3550.00	SqFt						
52	RAVELING	M	395.00	SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT										
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	216,529 SqFt					
Section:	205		of	8		From:	-		To:	-		Last Const.:	1/1/1985	
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Category:			Rank:	P	
Area:	40,742 SqFt		Length:	975 Ft		Width:			40 Ft					
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:		Ft		
Shoulder:			Street Type:			Grade:	0				Lanes:	0		
Section Comments:														
Work Date:	1/1/1985		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True				
Work Date:	1/1/1985		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True				
Last Insp. Date:	3/8/2017		TotalSamples:	10		Surveyed:		2						
Conditions:	PCI: 36													
Inspection Comments:														
Sample Number:	204		Type:	R		Area:	4000.00 SqFt		PCI:	36				
Sample Comments:														
43	BLOCK CR		L	2210.00 SqFt										
48	L & T CR		L	154.00 Ft										
52	RAVELING		L	1200.00 SqFt										
52	RAVELING		M	2800.00 SqFt										
Sample Number:	209		Type:	R		Area:	3400.00 SqFt		PCI:	36				
Sample Comments:														
48	L & T CR		M	50.00 Ft										
48	L & T CR		L	300.00 Ft										
52	RAVELING		L	1020.00 SqFt										
52	RAVELING		M	2380.00 SqFt										

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	216,529 SqFt		
Section:	210 of 8		From:	-		To:	-		Last Const.:	1/1/1991	
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Rank:	P	
Area:	48,281 SqFt		Length:	1,225 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1991		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1993		Work Type: REPAIR				Code:	IMPORTED		Is Major M&R:	False
Last Insp. Date:	3/8/2017		TotalSamples:	14		Surveyed:	3				
Conditions:	PCI: 64										
Inspection Comments:											
Sample Number:	301		Type:	R		Area:	3288.00 SqFt		PCI:	53	
Sample Comments:											
48	L & T CR		L	297.00 Ft							
52	RAVELING		L	2588.00 SqFt							
52	RAVELING		M	700.00 SqFt							
Sample Number:	307		Type:	R		Area:	3500.00 SqFt		PCI:	69	
Sample Comments:											
48	L & T CR		L	253.00 Ft							
52	RAVELING		L	3500.00 SqFt							
Sample Number:	310		Type:	R		Area:	3500.00 SqFt		PCI:	68	
Sample Comments:											
48	L & T CR		L	320.00 Ft							
52	RAVELING		L	3500.00 SqFt							

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT					
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	216,529 SqFt	
Section:	212	of 8	From:	-			To:	-	Last Const.: 1/1/2010	
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:	Category:			Rank: P	
Area:	2,283 SqFt		Length:	75 Ft		Width:	35 Ft			
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0	
Section Comments:										
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1991		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1993		Work Type: REPAIR				Code:	IMPORTED		Is Major M&R: False
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:		1		
Conditions:	PCI: 87									
Inspection Comments:										
Sample Number:	299	Type:	R	Area:	2283.00 SqFt		PCI:	87		
Sample Comments:										
48	L & T CR		L	4.00 Ft						
52	RAVELING		L	46.00 SqFt						
57	WEATHERING		L	2237.00 SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT											
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY		Area:	216,529 SqFt					
Section:	215		of	8		From:	-		To:	-		Last Const.:	1/1/1985		
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Category:			Rank:	P		
Area:	68,940 SqFt		Length:	1,600 Ft		Width:			40 Ft						
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:		Ft			
Shoulder:			Street Type:			Grade:	0				Lanes:	0			
Section Comments:															
Work Date:	1/1/1985		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:		True	
Last Insp. Date:	3/8/2017		TotalSamples:	17		Surveyed:		3							
Conditions:	PCI:	33													
Inspection Comments:															
Sample Number:	102		Type:	R		Area:	4000.00 SqFt		PCI:	33					
Sample Comments:															
48	L & T CR		L	178.00 Ft											
52	RAVELING		M	3980.00 SqFt											
52	RAVELING		H	20.00 SqFt											
Sample Number:	111		Type:	R		Area:	4000.00 SqFt		PCI:	34					
Sample Comments:															
52	RAVELING		H	50.00 SqFt											
48	L & T CR		L	169.00 Ft											
52	RAVELING		M	3950.00 SqFt											
Sample Number:	118		Type:	R		Area:	4029.00 SqFt		PCI:	33					
Sample Comments:															
48	L & T CR		L	177.00 Ft											
52	RAVELING		M	4000.00 SqFt											
52	RAVELING		H	29.00 SqFt											

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	216,529 SqFt			
Section:	225		of	8	From:	-		To:	-		Last Const.:	1/1/2004
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	28,746 SqFt		Length:	1,014 Ft		Width:	45 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1985		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2004		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	7		Surveyed:	1					
Conditions:	PCI: 87											
Inspection Comments:												
Sample Number:	214		Type:	R		Area:	4000.00 SqFt		PCI:	87		
Sample Comments:												
52	RAVELING		L	40.00 SqFt								
48	L & T CR		L	22.00 Ft								
57	WEATHERING		L	3960.00 SqFt								

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	216,529 SqFt
Section:	230	of 8	From:	-			To:	-	Last Const.: 1/1/2010
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P
Area:	12,000 SqFt		Length:	300 Ft		Width:	40 Ft		
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length: Ft
Shoulder:			Street Type:			Grade:	0		Lanes: 0
Section Comments:									
Work Date:	1/1/1985		Work Type: New Construction - Initial				Code:	NU-IN	Is Major M&R: True
Work Date:	1/1/2010		Work Type: Mill and Overlay				Code:	ML-OL	Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	3		Surveyed: 1			
Conditions:	PCI: 86								
Inspection Comments:									
Sample Number:	105	Type:	R	Area:	4000.00 SqFt		PCI:	86	
Sample Comments:									
42	BLEEDING		N	5.00 SqFt					
48	L & T CR		L	9.00 Ft					
52	RAVELING		L	120.00 SqFt					
57	WEATHERING		L	3880.00 SqFt					

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	216,529 SqFt
Section:	270	of	8	From:	-	To:	-	Last Const.:	1/1/1997
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	13,236 SqFt	Length:	255 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1985	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1997	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/8/2017	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI: 62								
Inspection Comments: Large patch in previous inspection was added to the network as an additional section.									
Sample Number:	400	Type:	R	Area:	3236.00 SqFt	PCI:	62		
Sample Comments:									
48	L & T CR	L	200.00	Ft					
48	L & T CR	M	65.00	Ft					
50	PATCHING	L	1.00	SqFt					
52	RAVELING	L	3235.00	SqFt					

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT										
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	216,529 SqFt					
Section:	275		of	8		From:	-		To:	-		Last Const.:	1/1/2010	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	2,301 SqFt		Length:	45 Ft		Width:	50 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1985		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1997		Work Type: OVERLAY					Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2010		Work Type: MILL and OVERLAY					Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1							
Conditions:	PCI: 83													
Inspection Comments:														
Sample Number:	399		Type:	R		Area:	2301.00 SqFt		PCI:	83				
Sample Comments:														
48	L & T CR		L	52.00 Ft										
52	RAVELING		L	46.00 SqFt										
57	WEATHERING		L	2255.00 SqFt										

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW B1		Name:	TAXIWAY B1		Use:	TAXIWAY	Area:	14,114 SqFt			
Section:	240		of	2	From:	-		To:	-		Last Const.:	1/1/2004
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	10,879 SqFt		Length:	250 Ft		Width:	45 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1985		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2004		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	3		Surveyed:	1					
Conditions:	PCI: 71											
Inspection Comments:												
Sample Number:	218		Type:	R		Area:	4248.00 SqFt		PCI:	71		
Sample Comments:												
52	RAVELING		L	212.00 SqFt								
48	L & T CR		L	318.00 Ft								
57	WEATHERING		L	4036.00 SqFt								

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	TW B1		Name:	TAXIWAY B1		Use:	TAXIWAY	Area:	14,114 SqFt		
Section:	245	of 2	From:	-			To:	-		Last Const.:	1/1/2010
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:				Category:	Rank:	P
Area:	3,235 SqFt		Length:	70 Ft		Width:	45 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1985		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2004		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 92										
Inspection Comments:											
Sample Number:	220	Type:	R	Area:	3235.00 SqFt		PCI:	92			
Sample Comments:											
48	L & T CR		L	4.00 Ft							
57	WEATHERING		L	3235.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	17,809 SqFt		
Section:	250	of 4	From:	-			To:	-		Last Const.:	1/1/1985
Surface:	AC		Family:	C9N59-GA-TW-AC		Zone:			Category:	Rank: P	
Area:	8,852 SqFt		Length:	175 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1985		Work Type:	OVERLAY			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1985		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date: 3/8/2017											
TotalSamples: 2											
Surveyed: 1											
Conditions:	PCI: 41										
Inspection Comments:											
Sample Number:	201	Type:	R	Area:	5673.00 SqFt		PCI:	41			
Sample Comments:											
48	L & T CR		L	342.00 Ft							
52	RAVELING		L	1702.00 SqFt							
52	RAVELING		M	3971.00 SqFt							

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	17,809 SqFt		
Section:	255	of	4	From:	-		To:	-		Last Const.:	1/1/2010
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	2,494 SqFt		Length:	50 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1985		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1985		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 89										
Inspection Comments:											
Sample Number:	199	Type:	R	Area:	2494.00 SqFt		PCI:	89			
Sample Comments:											
48	L & T CR		L	33.00 Ft							
57	WEATHERING		L	2494.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	17,809 SqFt		
Section:	310	of 4	From:	-			To:	-		Last Const.:	1/1/1970
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:				Category:	Rank: P	
Area:	3,077 SqFt		Length:	66 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1970		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 31										
Inspection Comments:											
Sample Number:	106	Type:	R	Area:	3077.00 SqFt		PCI:	31			
Sample Comments:											
56	SWELLING		L	18.00	SqFt						
48	L & T CR		L	205.00	Ft						
52	RAVELING		H	20.00	SqFt						
52	RAVELING		M	3057.00	SqFt						

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT				
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	17,809 SqFt
Section:	315	of	4	From:	-	To:	-	Last Const.:	1/1/1985
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank: P
Area:	3,386 SqFt		Length:	120 Ft		Width:	50 Ft		
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1985		Work Type:	BUILT			Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1		
Conditions:	PCI:	28							
Inspection Comments:									
Sample Number:	107	Type:	R	Area:	3385.00 SqFt		PCI:	28	
Sample Comments:									
45	DEPRESSION		L	46.00 SqFt					
48	L & T CR		L	263.00 Ft					
52	RAVELING		M	3375.00 SqFt					
52	RAVELING		H	10.00 SqFt					

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT								
Branch:	TW B3		Name:	TAXIWAY B3		Use:	TAXIWAY		Area:	15,026 SqFt			
Section:	258		of	2	From:	-		To:	-		Last Const.:	1/1/1997	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P
Area:	2,948 SqFt		Length:	50 Ft		Width:	50 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1965		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1997		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1						
Conditions:	PCI: 73												
Inspection Comments:													
Sample Number:	300		Type:	R		Area:	2948.00 SqFt		PCI:	73			
Sample Comments:													
48	L & T CR		L	125.00 Ft									
50	PATCHING		M	2.00 SqFt									
52	RAVELING		L	59.00 SqFt									
57	WEATHERING		L	2887.00 SqFt									

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	TW B3		Name:	TAXIWAY B3		Use:	TAXIWAY	Area:	15,026 SqFt		
Section:	260	of	2	From:	-	To:	-	Last Const.:	1/1/1997		
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:		Category:		Rank:	P	
Area:	12,078 SqFt		Length:	105 Ft		Width:	50 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1997		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI: 56										
Inspection Comments:											
Sample Number:	301	Type:	R	Area:	5980.00 SqFt		PCI:	56			
Sample Comments:											
45	DEPRESSION		L	128.00	SqFt						
48	L & T CR		L	203.00	Ft						
48	L & T CR		M	115.00	Ft						
50	PATCHING		L	24.00	SqFt						
52	RAVELING		L	5956.00	SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	38,971 SqFt		
Section:	330	of	1	From:	-	To:	-	Last Const.:	1/9/1998		
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	38,971 SqFt	Length:	1,325 Ft		Width:	25 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/9/1998		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	8		Surveyed:	1				
Conditions:	PCI:	77									
Inspection Comments:											
Sample Number:	103	Type:	R	Area:	5000.00 SqFt		PCI:	77			
Sample Comments:											
52	RAVELING	L	250.00 SqFt								
48	L & T CR	L	200.00 Ft								
57	WEATHERING	L	4750.00 SqFt								

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	TW C3		Name:	TAXIWAY C3		Use:	TAXIWAY	Area:	24,842 SqFt		
Section:	305	of	2	From:	-	To:	-	Last Const.:	1/1/1960		
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:		Category:		Rank:	P	
Area:	22,138 SqFt		Length:	450 Ft		Width:	50 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1960		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	5		Surveyed:	2				
Conditions:	PCI: 60										
Inspection Comments:											
Sample Number:	302	Type:	R	Area:	5000.00 SqFt		PCI:	61			
Sample Comments:											
50	PATCHING	L	30.00 SqFt								
48	L & T CR	L	51.00 Ft								
52	RAVELING	L	4970.00 SqFt								
48	L & T CR	M	15.00 Ft								
Sample Number:	304	Type:	R	Area:	3410.00 SqFt		PCI:	59			
Sample Comments:											
48	L & T CR	L	253.00 Ft								
48	L & T CR	M	10.00 Ft								
52	RAVELING	L	3390.00 SqFt								
52	RAVELING	M	20.00 SqFt								

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT					
Branch:	TW C3		Name:	TAXIWAY C3		Use:	TAXIWAY	Area:	24,842 SqFt	
Section:	307	of	2	From:	-			To:	-	
Surface:	AAC	Family:	C9N59-GA-TW-AAC-APC		Zone:				Category:	Rank: P
Area:	2,704 SqFt		Length:	50 Ft		Width:	50 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1960		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1			
Conditions:	PCI: 90									
Inspection Comments:										
Sample Number:	305	Type:	R	Area:	2704.00 SqFt		PCI:	90		
Sample Comments:										
48	L & T CR		L	11.00 Ft						
57	WEATHERING		L	2704.00 SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	31,033 SqFt		
Section:	420	of 1	From:	-			To:	-		Last Const.:	1/9/1998
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	31,033 SqFt		Length:	1,070 Ft		Width:	25 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/9/1998		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	6		Surveyed:	1				
Conditions:	PCI:	64									
Inspection Comments:											
Sample Number:	102	Type:	R	Area:	5000.00 SqFt		PCI:	64			
Sample Comments:											
52	RAVELING	M	100.00		SqFt						
48	L & T CR	L	200.00		Ft						
52	RAVELING	L	4900.00		SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	51,882 SqFt		
Section:	605	of 1	From:	-			To:	-		Last Const.:	1/1/2009
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	51,882 SqFt	Length:	843 Ft		Width:	35 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft			Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0			Lanes:	0	
Section Comments:											
Work Date:	1/1/2009		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	12		Surveyed:	2				
Conditions:	PCI:	78									
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	4750.00 SqFt			PCI:	74		
Sample Comments:											
52	RAVELING	L	238.00		SqFt						
45	DEPRESSION	L	130.00		SqFt						
48	L & T CR	L	3.00		Ft						
57	WEATHERING	L	4512.00		SqFt						
Sample Number:	106	Type:	R	Area:	4375.00 SqFt			PCI:	83		
Sample Comments:											
52	RAVELING	L	218.00		SqFt						
48	L & T CR	L	52.00		Ft						
57	WEATHERING	L	4157.00		SqFt						

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW F1		Name:	TAXIWAY F1		Use:	TAXIWAY	Area:	10,690 SqFt		
Section:	610	of 2	From:	-			To:	-		Last Const.:	1/1/2009
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	7,988 SqFt		Length:	200 Ft		Width:	40 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2009		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	85									
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	4916.00 SqFt		PCI:	85			
Sample Comments:											
48	L & T CR		L	28.00 Ft							
52	RAVELING		L	122.00 SqFt							
57	WEATHERING		L	4794.00 SqFt							

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT									
Branch:	TW F1		Name:	TAXIWAY F1		Use:	TAXIWAY		Area:	10,690 SqFt				
Section:	612		of	2		From:	-		To:	-		Last Const.:	1/1/2010	
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	2,702 SqFt		Length:	70 Ft		Width:	40 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2009		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Work Date:	1/1/2010		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed:	1							
Conditions:	PCI: 86													
Inspection Comments:														
Sample Number:	102		Type:	R		Area:	2702.00 SqFt		PCI:	86				
Sample Comments:														
48	L & T CR		L	22.00 Ft										
52	RAVELING		L	50.00 SqFt										
57	WEATHERING		L	2652.00 SqFt										

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW F2		Name:	TAXIWAY F2		Use:	TAXIWAY	Area:	12,143 SqFt		
Section:	615	of 2	From:	-			To:	-		Last Const.:	1/1/2009
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	7,725 SqFt		Length:	200 Ft		Width:	40 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2009		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	89									
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	4545.00 SqFt		PCI:	89			
Sample Comments:											
45	DEPRESSION		L	10.00 SqFt							
48	L & T CR		L	31.00 Ft							
57	WEATHERING		L	4545.00 SqFt							

Network:	GIF			Name:	WINTER HAVEN'S GILBERT AIRPORT						
Branch:	TW F2		Name:	TAXIWAY F2		Use:	TAXIWAY		Area:	12,143 SqFt	
Section:	617 of 2		From:	-			To:	-		Last Const.:	1/1/2010
Surface:	AAC		Family:	C9N59-GA-TW-AAC-APC		Zone:				Rank:	P
Area:	4,418 SqFt		Length:	110 Ft		Width:	40 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:	0		Lanes:		0	
Section Comments:											
Work Date:	1/1/2009		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True	
Last Insp. Date:	3/8/2017		TotalSamples:	1		Surveyed: 1					
Conditions:	PCI: 92										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	4418.00 SqFt		PCI:	92	
Sample Comments:											
52	RAVELING		L	25.00 SqFt							
57	WEATHERING		L	4393.00 SqFt							

Network:	GIF		Name:	WINTER HAVEN'S GILBERT AIRPORT							
Branch:	TW HANG		Name:	TAXIWAY TO HANGAR		Use:	TAXIWAY	Area:	9,405 SqFt		
Section:	4605	of 1	From:	-			To:	-	Last Const.:	1/1/1965	
Surface:	AC	Family:	C9N59-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	9,405 SqFt	Length:	350 Ft		Width:	25 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1965		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/8/2017		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	15									
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	5687.00 SqFt		PCI:	15			
Sample Comments:											
41	ALLIGATOR CR	L	934.00	SqFt							
48	L & T CR	L	356.00	Ft							
50	PATCHING	L	25.00	SqFt							
52	RAVELING	M	5662.00	SqFt							
53	RUTTING	L	1092.00	SqFt							