# FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION AND SPACEPORTS OFFICE







Florida Department of Transportation

# Statewide Airfield Pavement Management Program

#### Prepared by:

FDOT Aviation and Spaceports Office 605 Suwannee Street Tallahassee, Florida 32399-0450















OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS



# **Table of Contents**


Executive Summary10
Program Background10
Summary of Results11Pavement Condition Index (Latest Inspection)11Forecasted Pavement Condition Index 2018-202713Major Rehabilitation Planning 2018-202715
Summary of Pompano Beach Airpark16
Chapter 1 – Introduction18
1.1 Background18
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-201718
1.3 Organization201.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager201.3.2 Participating Florida Public-Use and Publicly Owned Airports201.3.3 Florida Department of Transportation District Offices201.3.4 Consultant20
1.4 Purpose of Airport Pavement Evaluation Report22
1.5 History of the Program
1.6 Federal Aviation Administration (FAA)24
1.7 FDOT SAPMP Objectives and Components241.7.1 Program Objectives241.7.2 Program Components24
1.8 References
Chapter 2 – Methodology30
2.1 Airfield Pavement Database
2.2 Airfield Pavement System Inventory       30         2.2.1 Pavement Management Program Network Definition Terminology       31
2.3 Airfield Pavement Structure
2.4 Airfield Pavement Work History
2.5 Airfield Pavement Traffic35
2.6 Airfield Pavement Condition Index (PCI) Survey



2.6.3 PCI Survey Inspection Procedures	
Chapter 3 – Airfield Pavement System Inventory	45
3.1 Airfield Pavement Network Information	
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	
3.1.2 Estimated Pavement Age	
3.1.3 Functional Use Classification	
3.1.4 Pavement Surface Type	
Chapter 4 – Airfield Pavement Condition	57
4.1 Airfield Pavement Condition Index (Latest Inspection)	
4.1.2 Branch-Level Analysis	
4.1.3 Section-Level Analysis	
4.2 Summary of Pavement Condition Evaluation Results	64
4.2.1 Network-Level Observations	
4.2.2 Branch-Level Observations	
4.3 Forecasted Pavement Conditions	66
4.3.1 Performance Models and Prediction Curves	
4.3.2 Branch-Level Pavement Condition Forecast	66
4.3.3 Section-Level Pavement Condition Forecast	
4.3.4 Forecasted PCI Considerations	72
Chapter 5 – Localized Maintenance and Repair Planning	74
5.1 Localized Maintenance and Repair	
5.2 Localized Maintenance and Repair Policy	
5.3 Localized Maintenance and Repair Analysis and Recommendations	79
Chapter 6 – Major Rehabilitation Planning	84
6.1 Major Rehabilitation	84
6.1.1 Critical PCI	
6.1.2 FDOT Recommended Minimum Service-Level PCI	
6.2 Major Rehabilitation Policy	87
6.2.1 Major Rehabilitation Pavement Section Development	
6.2.2 Major Rehabilitation Planning-Level Unit Costs	88
6.3 Major Rehabilitation Needs	89
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs	89
Chapter 7 – Conclusion	94
7.1 Recommendations	94
7.1.1 Continued PCI Survey Inspections	94
7.1.2 Localized Maintenance and Repair	94



7.1.3 Major Rehabilitation	94
7.1.4 Pavement Management System	
7.2 Supporting Documents	95
001 – Airfield Pavement Network Definition Exhibit	95
002 – Airfield Pavement System Inventory Exhibit	95
003 – Airfield Pavement Condition Index Exhibit	95
004 – Airfield Pavement Major Rehabilitation Exhibit	95
Inspection Photograph Documentation	95
7.3 Conclusion	06
7.3 COTICIUSIOTI	90





Appendix A Airfield Pavement Analysis Tables

Appendix B Airfield Pavement Localized Maintenance and Repair and Major

Rehabilitation

Appendix C Technical Exhibits

Appendix D Inspection Photograph Documentation

Appendix E Inspection Distress Details



# **List of Figures**

Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027	16
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts	19
Figure 1.7-1 Typical Pavement Condition Life Cycle	25
Figure 1.7-2 General Pavement Treatments by Condition Range	26
Figure 1.7-3 Flexible Asphalt Concrete	27
Figure 1.7-4 Rigid Portland Cement Concrete	27
Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit	46
Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit	47
Figure 3.1.2 Average Age of Pavements at Inspection	48
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area	49
Figure 3.1.4 (a) Pavement Surface Type by Area (SF)	50
Figure 3.1.4 (b) Pavement Surface Type by Area (%)	
Figure 4.1.1 Latest Condition – Overall Network	57
Figure 4.1.2 (a) Latest Condition – Runway Pavements	58
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements	58
Figure 4.1.2 (c) Latest Condition – Apron Pavements	59
Figure 4.1.2 (d) Latest Condition – Taxilane Pavements	59
Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit	63
Figure 4.2.2 Pavement Condition Summary by Facility Use	65
Figure 4.3.2 (a) Forecasted Runway Pavement Performance	66
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance	67
Figure 4.3.2 (c) Forecasted Apron Pavement Performance	67
Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI	84
Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI	85
Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year	91
Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit	92



# **List of Tables**

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level11
Table E-2 Pavement Condition Index Forecast 2018-202713
Table E-3 Major Rehabilitation Planning 2018-2027
Table 2.2.1 Airfield Pavement Database Network Definition Terminology32
Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields37
Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields
Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields
Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields .39
Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields
Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete41
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete41
Table 2.6.4 Summary of Updates to ASTM D5340-1243
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction45
Table 3.1.5 Pavement System Inventory Details
Table 4.1.3 Latest Pavement Condition Index Summary61
Table 4.3.3 Forecasted PCI 2018-202769
Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete75
Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete76
Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete78
Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete .78



Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level 79
Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level .80
Table 5.3-3 Summary of Localized Maintenance82
Table 6.1.2 FDOT Recommended Minimum Service-Level PCI
Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete
Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete
Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type89
Table 6.3.1 10-Year Major Rehabilitation Needs



# **Executive Summary**



## **Executive Summary**

#### Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the documented procedures set forth by ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.





### **Summary of Results**

#### Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) - Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	RUNWAY 10-28	RUNWAY	6105	271,200	66	Fair
PMP	RUNWAY 10-28	RUNWAY	6115	58,320	87	Good
PMP	RUNWAY 6-24	RUNWAY	6205	335,952	64	Fair
PMP	RUNWAY 6-24	RUNWAY	6210	167,976	63	Fair
PMP	RUNWAY 6-24	RUNWAY	6220	35,000	94	Good
PMP	RUNWAY 6-24	RUNWAY	6225	17,500	94	Good
PMP	RUNWAY 15-33	RUNWAY	6305	220,900	92	Good
PMP	RUNWAY 15-33	RUNWAY	6310	441,800	93	Good
PMP	RUNWAY 15-33	RUNWAY	6325	25,000	84	Satisfactory
PMP	RUNWAY 15-33	RUNWAY	6330	50,000	93	Good
PMP	TAXIWAY A	TAXIWAY	105	61,729	93	Good
PMP	TAXIWAY A	TAXIWAY	115	13,967	53	Poor
PMP	TAXIWAY B	TAXIWAY	210	118,013	64	Fair
PMP	TAXIWAY C	TAXIWAY	305	26,289	65	Fair
PMP	TAXIWAY C	TAXIWAY	350	6,807	94	Good
PMP	TAXIWAY C	TAXIWAY	360	9,668	94	Good
PMP	TAXIWAY D	TAXIWAY	405	105,607	63	Fair
PMP	TAXIWAY D	TAXIWAY	410	13,072	66	Fair
PMP	TAXIWAY D	TAXIWAY	415	36,063	84	Satisfactory
PMP	TAXIWAY D	TAXIWAY	420	23,098	74	Satisfactory
PMP	TAXIWAY D	TAXIWAY	425	36,577	94	Good
PMP	TAXIWAY E	TAXIWAY	505	12,246	89	Good
PMP	TAXIWAY F	TAXIWAY	610	117,893	64	Fair
PMP	TAXIWAY F	TAXIWAY	612	15,543	83	Satisfactory
PMP	TAXIWAY F	TAXIWAY	615	18,178	89	Good
PMP	TAXIWAY G	TAXIWAY	710	15,387	96	Good
PMP	TAXIWAY G	TAXIWAY	715	17,469	94	Good
PMP	TAXIWAY K	TAXIWAY	1110	89,261	94	Good
PMP	TAXIWAY K	TAXIWAY	1115	7,373	92	Good
PMP	TAXIWAY K	TAXIWAY	1120	14,097	92	Good
PMP	TAXIWAY L	TAXIWAY	1202	21,209	67	Fair
PMP	TAXIWAY L	TAXIWAY	1205	13,025	55	Poor
PMP	TAXIWAY L	TAXIWAY	1210	152,867	65	Fair
PMP	TAXIWAY L	TAXIWAY	1215	14,829	88	Good
PMP	TAXIWAY M	TAXIWAY	1305	27,738	69	Fair





Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	TAXIWAY M	TAXIWAY	1306	29,856	82	Satisfactory
PMP	TAXIWAY M	TAXIWAY	1310	24,002	83	Satisfactory
PMP	TAXIWAY M	TAXIWAY	1315	16,359	70	Fair
PMP	TAXIWAY M	TAXIWAY	1320	95,815	65	Fair
PMP	TAXIWAY M	TAXIWAY	1325	16,146	92	Good
PMP	TAXIWAY N	TAXIWAY	1405	28,235	82	Satisfactory
PMP	TAXIWAY R	TAXIWAY	1805	21,726	92	Good
PMP	TAXILANE TO HANGARS	TAXILANE	4305	31,764	39	Very Poor
PMP	TAXILANE TO HANGARS	TO HANGARS TAXILANE		49,387	30	Very Poor
PMP	TAXILANE TO HANGARS TAXILANE		4315	83,687	48	Poor
PMP	TAXILANE TO HANGARS	TAXILANE	4320	16,033	38	Very Poor
PMP	TAXILANE TO SW APRON	TAXILANE	4505	28,724	88	Good
PMP	SOUTH APRON	APRON	4105	203,761	63	Fair
PMP	SOUTH APRON	APRON	4107	3,846	88	Good
PMP	SOUTH APRON	APRON	4110	26,025	51	Poor
PMP	SOUTH APRON	APRON	4112	131,008	92	Good
PMP	SOUTH APRON	APRON	4125	117,688	48	Poor
PMP	SOUTH APRON	APRON	4130	71,613	100	Good
PMP	SOUTH APRON	APRON	4135	128,753	100	Good
PMP	NORTH APRON - OLD RW	APRON	4205	62,989	61	Fair
PMP	SOUTHWEST APRON	APRON	4410	61,737	81	Satisfactory
PMP	RUNUP TO RUNWAY 33	APRON	5105	14,310	92	Good
PMP	RUNUP TO RUNWAY 33	APRON	5110	20,490	59	Fair





#### Forecasted Pavement Condition Index 2018-2027

Table E-2 Pavement Condition Index Forecast 2018-2027

								Forecas	sted PC	I			
Network ID	Branch ID	Section ID	Last PCI	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
PMP	AP N	4205	61	59	57	55	54	53	52	52	52	52	52
PMP	AP RU RW33	5105	92	88	85	83	81	80	78	77	75	73	70
PMP	AP RU RW33	5110	59	57	55	54	53	52	52	52	52	52	52
PMP	AP S	4105	63	61	59	57	55	54	53	52	52	52	52
PMP	AP S	4107	88	86	83	80	78	76	73	71	69	67	65
PMP	AP S	4110	51	49	48	46	45	43	42	40	38	37	35
PMP	AP S	4112	92	90	89	87	86	84	83	81	79	78	76
PMP	AP S	4125	48	46	45	43	42	40	39	37	35	34	32
PMP	AP S	4130	100	84	82	81	79	78	76	74	72	69	67
PMP	AP S	4135	100	95	93	92	90	88	87	85	84	82	80
PMP	AP SW	4410	81	79	76	74	72	70	68	66	64	63	61
PMP	RW 10-28	6105	66	64	63	61	60	58	56	55	53	51	50
PMP	RW 10-28	6115	87	85	82	80	78	75	73	71	68	67	65
PMP	RW 15-33	6305	92	90	88	85	83	81	78	76	73	71	69
PMP	RW 15-33	6310	93	91	89	87	84	82	79	77	74	72	70
PMP	RW 15-33	6325	84	82	81	79	78	76	74	73	71	69	68
PMP	RW 15-33	6330	93	91	90	88	87	85	83	82	80	78	77
PMP	RW 6-24	6205	64	63	62	61	61	60	60	60	60	60	60
PMP	RW 6-24	6210	63	62	61	61	60	60	60	60	60	60	60
PMP	RW 6-24	6220	94	92	90	88	85	83	80	78	75	73	71
PMP	RW 6-24	6225	94	92	90	88	85	83	80	78	75	73	71
PMP	TL AP SW	4505	88	86	83	81	79	77	75	74	72	71	70
PMP	TL HANG	4305	39	38	36	35	34	33	32	31	30	29	29
PMP	TL HANG	4310	30	29	28	27	27	25	24	22	20	16	13
PMP	TL HANG	4315	48	46	45	43	42	40	39	37	36	35	33
PMP	TL HANG	4320	38	35	30	26	22	18	15	11	7	3	0
PMP	TW A	105	93	91	88	85	83	80	78	77	75	74	73
PMP	TW A	115	53	51	50	48	47	46	45	44	44	43	43
PMP	TW B	210	64	63	61	60	58	56	54	53	51	50	48
PMP	TW C	305	65	64	63	62	61	60	59	58	57	56	54
PMP	TW C	350	94	92	89	86	83	81	79	77	76	75	73
PMP	TW C	360	94	92	89	86	83	81	79	77	76	75	73
PMP	TW D	405	63	62	60	58	57	55	53	52	50	48	47
PMP	TW D	410	66	65	63	62	60	59	57	55	54	52	50
PMP	TW D	415	84	82	80	78	76	75	74	73	72	71	70





No. of IB	D	0	L BOL	Forecasted PCI									
Network ID	Branch ID	Section ID	Last PCI	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
PMP	TW D	420	74	73	72	71	70	69	68	67	66	65	64
PMP	TW D	425	94	92	89	87	84	82	80	78	76	74	73
PMP	TW E	505	89	87	84	82	80	78	76	75	74	73	72
PMP	TW F	610	64	63	61	60	58	56	54	53	51	50	48
PMP	TW F	612	83	81	79	77	76	75	73	72	71	71	70
PMP	TW F	615	89	87	84	82	80	78	76	75	74	73	72
PMP	TW G	710	96	94	91	89	86	84	82	79	77	76	74
PMP	TW G	715	94	92	89	87	84	82	80	78	76	74	73
PMP	TW K	1110	94	92	89	87	84	82	80	78	76	74	73
PMP	TW K	1115	92	90	87	85	82	80	78	76	75	73	71
PMP	TW K	1120	92	90	87	85	82	80	78	76	75	73	71
PMP	TW L	1202	67	66	65	63	62	60	59	57	55	54	52
PMP	TW L	1205	55	54	52	51	49	47	46	44	43	41	39
PMP	TW L	1210	65	64	62	61	59	58	56	54	52	51	49
PMP	TW L	1215	88	86	83	81	79	77	76	74	73	72	71
PMP	TW M	1305	69	68	67	66	65	64	63	63	62	61	60
PMP	TW M	1306	82	80	78	76	74	73	71	70	69	68	67
PMP	TW M	1310	83	81	79	77	75	73	72	71	69	68	67
PMP	TW M	1315	70	69	68	67	66	65	64	63	62	62	61
PMP	TW M	1320	65	64	63	62	61	60	59	58	57	56	54
PMP	TW M	1325	92	90	87	84	82	80	78	76	75	74	73
PMP	TW N	1405	82	80	78	76	74	73	71	70	69	68	67
PMP	TW R	1805	92	90	87	85	82	80	78	76	75	73	71





#### Major Rehabilitation Planning 2018-2027

Table E-3 Major Rehabilitation Planning 2018-2027


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	PMP	AP N	4205	AAC	62,989	59	AC Restoration	\$ 441,000.00
2018	PMP	AP RU RW33	5110	AAC	20,490	57	AC Restoration	\$ 144,000.00
2018	PMP	AP S	4105	AAC	203,761	61	AC Restoration	\$ 1,427,000.00
2018	PMP	AP S	4110	AC	26,025	49	AC Restoration	\$ 183,000.00
2018	PMP	AP S	4125	AC	117,688	46	AC Restoration	\$ 896,000.00
2018	PMP	AP SW	4410	PCC	61,737	79	PCC Restoration	\$ 618,000.00
2018	PMP	RW 10-28	6105	AC	271,200	64	AC Restoration	\$ 1,899,000.00
2018	PMP	RW 6-24	6205	AAC	335,952	63	AC Restoration	\$ 2,352,000.00
2018	PMP	RW 6-24	6210	AAC	167,976	62	AC Restoration	\$ 1,176,000.00
2018	PMP	TL HANG	4305	AC	31,764	38	AC Reconstruction	\$ 286,000.00
2018	PMP	TL HANG	4310	AC	49,387	29	AC Reconstruction	\$ 445,000.00
2018	PMP	TL HANG	4315	AC	83,687	46	AC Restoration	\$ 638,000.00
2018	PMP	TL HANG	4320	APC	16,033	35	AC Reconstruction	\$ 145,000.00
2018	PMP	TW A	115	AAC	13,967	51	AC Restoration	\$ 98,000.00
2018	PMP	TW B	210	AAC	118,013	63	AC Restoration	\$ 827,000.00
2018	PMP	TW C	305	AC	26,289	64	AC Restoration	\$ 185,000.00
2018	PMP	TW D	405	AAC	105,607	62	AC Restoration	\$ 740,000.00
2018	PMP	TW F	610	AAC	117,893	63	AC Restoration	\$ 826,000.00
2018	PMP	TW L	1205	AC	13,025	54	AC Restoration	\$ 92,000.00
2018	PMP	TW L	1210	AAC	152,867	64	AC Restoration	\$ 1,071,000.00
2018	PMP	TW M	1320	AC	95,815	64	AC Restoration	\$ 671,000.00
2019	PMP	TW D	410	AAC	13,072	63	AC Restoration	\$ 92,000.00
2020	PMP	TW L	1202	AAC	21,209	63	AC Restoration	\$ 149,000.00
2022	PMP	TW M	1305	AC	27,738	64	AC Restoration	\$ 195,000.00
2023	PMP	TW M	1315	AC	16,359	64	AC Restoration	\$ 115,000.00
2027	PMP	TW D	420	AAC	23,098	64	AC Restoration	\$ 162,000.00

<sup>\*</sup>All planning cost values have been rounded to the nearest thousand-dollar.





Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027



#### Summary of Pompano Beach Airpark

Pompano Beach Airpark was inspected in May 2017 - the overall weighted PCI value was 75, a condition rating of Satisfactory. The results of the maintenance, repair, and major rehabilitation analysis identified \$756.570 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$15,873,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$15,160,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.







## **Chapter 1 – Introduction**

#### 1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

#### 1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating publicuse airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.



#### 1.3 Organization

#### 1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

#### 1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

#### 1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

#### 1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys," evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- Research and evaluation of existing record documentation was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- An update to the existing Network Definition Map was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- A functional pavement evaluation with PCI Survey inspections was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- Maintenance, Repair, and Rehabilitation Planning was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." Planninglevel unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.





#### 1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

#### 1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.





During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (http://www.dot.state.fl.us/aviation/pavement.shtm) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys." The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.





#### 1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management **Program (PMP)**"). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications."

#### 1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC150/5380-7B "Airport Pavement Management Program (PMP)" an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

#### 1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- Procedures for modeling both past and future pavement performance conditions.
- Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

#### 1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data



- F. Pavement Performance Modeling for the Prediction/Forecast of PCI
- G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements' past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and costeffective manner. Figure 1.7-1 Typical Pavement Condition Life Cycle, which is based on the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Figure 1.7-1 Typical Pavement Condition Life Cycle, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.




Figure 1.7-1 Typical Pavement Condition Life Cycle

\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).

Figure 1.7-2 General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall

0

5

20

25



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

WITH TREATMENT Good 86-100 **Pavement Condition** \$2/sy to \$4/sy here for Satisfactory preventive maintenance surface seals every 5-7 71-85 Fair \$15/sy to \$25/sy here for minor resurfacing 56-70 thin AC overlay Poor 41-55 WITHOUT TREATMENT \$19/sv to \$35/sv here Very Poor for major resurfacing thick AC overlay 26-40 Serious 11-25 \$57/sy to \$86/sy here Failed 0-10

Figure 1.7-2 General Pavement Treatments by Condition Range

Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in Figures 1.7-1 and 1.7-2, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, nonaircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Age (Years)

Figures 1.7-3 and Figure 1.7-4 depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.





Figure 1.7-3 Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabiliation	40-64	50	A S	Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figure 1.7-4 Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabiliation	40-64	50		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.



#### 1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."
- FAA Advisory Circular 150/5380-7B 150/5380-7B "Airport Pavement Management Program."
- FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements."
- FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation."
- Department of the Air Force, Air Force Civil Engineer Center "Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements."
- Unified Facilities Criteria (UFC) 3-260-16FA 16 "Airfield Pavement Condition Survey Procedures Pavements."
- Unified Facilities Criteria (UFC) 3-260-03 "Airfield Pavement Evaluation."
- Pavement Management for Airports, Roads, and Parking Lots 2<sup>nd</sup> Edition, M.Y. Shahin.



# **Chapter 2**



## **Chapter 2 – Methodology**

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

#### 2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER<sup>TM</sup> database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

#### 2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.





A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's Aerial Photo Look Up System (APLUS). This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

#### 2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

#### **Pavement Network**

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement branches, which are typically comprised of one or many pavement sections. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the payement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

#### **Pavement Branch**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

#### **Pavement Section**

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related

Airport Pavement

**Evaluation Report** 





infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a "parent" pavement network.

#### **Pavement Sample Unit**

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (±8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet (±2,000 ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	"Tallahassee International Airport – Airfield Pavements"
Branch Name	Commonly defined asset name as established by Airport and by use	"Runway 18-36"
Branch ID	Codified shorthand name for commonly defined asset established for database identification	"RW 18-36" RW, Branch Use, "Runway" 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following:  Pavement Composition Construction Work History Aircraft Traffic Condition Records	"6105"
Sample Unit	A numeric identification of an area of pavement (5,000±2,000 SF of AC or 20±8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	"300"





#### 2.3 Airfield Pavement Structure

#### 2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

#### Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

#### Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

#### Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

#### Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.





#### Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

#### Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

#### Composite Structure - Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

#### Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 6inches in thickness.

#### Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

#### Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.





#### 2.4 Airfield Pavement Work History

#### 2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

- 1. Location and Limits of Work.
- Types and Severity of Distresses Repaired.
- 3. Type of Work.
- 4. Cost of Work.
- 5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

#### 2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular 150/5320-6F Airport Pavement Design and Evaluation when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

#### 2.6 Airfield Pavement Condition Index (PCI) Survey

#### 2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)," the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method





can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.





# 2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2-1 (a) Pavement Distress Types - Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms		
Alligator Cracking	Load / Fatigue		
Bleeding	Construction Quality/ Mix Design		
Block Cracking	Climate / Age		
Corrugation	Load / Construction Quality		
Depression	Load / Subsurface		
Jet Blast	Aircraft		
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load		
Longitudinal/Transverse Cracking	Climate / Construction Quality		
Oil Spillage	Aircraft / Vehicle		
Patching	Utility / Pavement Repair / Age		
Polished Aggregate	Repeated Traffic Loading		
Raveling	Climate / Age		
Rutting	Load / Fatigue		
Shoving	PCC Pavement Growth / Movement		
Slippage Cracking	Load / Pavement Bond / Mix Design		
Swelling	Climate / Subsurface		
Weathering	Climate / Age		



#### Table 2.6.2-1 (b) Pavement Distresses Possible Causes - Flexible Asphalt Concrete-Surfaced Airfields

	Classification by Poss	sible Causes	
Load	Climate / Durability	Moisture / Drainage	Others
<ul> <li>Alligator Cracking</li> <li>Corrugation</li> <li>Depression</li> <li>Patching of Load-based distress</li> <li>Polished Aggregate</li> <li>Rutting</li> <li>Slippage Cracking</li> </ul>	<ul> <li>Bleeding</li> <li>Block Cracking</li> <li>Joint Reflection Cracking</li> <li>L/T Cracking</li> <li>Patching of climate / durability-caused distresses</li> <li>Shoving from PCC</li> <li>Raveling</li> <li>Weathering</li> <li>Swelling</li> </ul>	<ul> <li>Alligator Cracking</li> <li>Depression</li> <li>Patching of moisture / drainage caused distress</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	Oil Spillage Jet Blast Erosion Polished Aggregate

Table 2.6.2-1 (c) Pavement Distresses Possible Effects - Flexible Asphalt Concrete-Surfaced Air fields

Classification by Possible Effects									
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements						
<ul> <li>Corrugation</li> <li>Depression</li> <li>Rutting</li> <li>Shoving of asphalt pavement</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	<ul> <li>Bleeding</li> <li>Depression</li> <li>Polished Aggregate</li> <li>Rutting</li> </ul>	Block Cracking     Joint Reflection     Cracking     L/T Cracking     Slippage     Cracking	All Distresses						





Table 2.6.2-2 (a) Pavement Distresses - Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms			
Blowup	Climate / ASR			
Corner Break	Load Repetition / Curling Stresses			
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses			
Durability Cracking	Freeze-Thaw Cycling			
Joint Seal Damage	Material Deterioration / Construction Quality / Age			
Small Patch	Pavement Repair			
Large Patch/Utility Cut	Utility / Pavement Repair			
Popout	Freeze-Thaw Cycling / ASR / Material Quality			
Pumping	Load Repetition / Poor Joint Sealant			
Scaling	Construction Quality / Freeze-Thaw Cycling			
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer			
Shattered Slab	Overloading			
Shrinkage Cracking	Construction Quality / Climate			
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars			
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars			
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction			





Table 2.6.2-2 (b) Pavement Distresses Possible Causes - Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Causes									
Load	Climate / Durability	Moisture / Drainage	Others						
<ul> <li>Corner Break</li> <li>Shattered Slab</li> <li>L/T/D Cracking</li> <li>Pumping</li> <li>Patching of Load-associated distress</li> <li>Spalling</li> </ul>	Blowup "D" Cracking Joint Seal Damage Popouts Scaling Patch of Climate/Durability- associated distress Shrinkage Cracking Spalling L/T/D Cracking	<ul> <li>Corner Break</li> <li>Shattered Slab</li> <li>Pumping</li> <li>Patching of Moisture/Drainage- associated distress</li> </ul>	Settlement     / Faulting						

Table 2.6.2-2 (c) Pavement Distresses Possible Effects - Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Effects										
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements							
<ul> <li>Blowup</li> <li>Corner Break</li> <li>L/T/D Cracking</li> <li>Shattered Slab</li> <li>Settlement / Faulting</li> <li>Spalling</li> </ul>	<ul> <li>Settlement / Faulting</li> <li>Spalling</li> </ul>	Corner Break L/T/D Cracking "D" Cracking Joint Seal Damage Shattered Slab Popouts Scaling	All distresses							



# 2.6.3 PCI Survey Inspection Procedures

# Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following Tables 2.6.3 (a) and (b) define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total	Sample Units to Inspect				
Sample Units in Section	Runways	Taxiways, Aprons, and Others			
1 - 4	1	1			
5 - 10	2	1			
11 - 15	3	2			
16 - 30	5	3			
31 - 40	7	4			
41 - 50	8	5			
51 or more	20% but ≤20	10% but ≤10			

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in	Sample Units to Inspect				
Section	Runways	Taxiways, Aprons, and Others			
1 - 3	1	1			
4 - 6	2	1			
7 - 10	3	2			
11 - 15	4	2			
16 - 20	5	3			
21 - 30	7	3			
31 - 40	8	4			
41 - 50	10	5			
51 or more	20% but ≤20	10% but ≤10			



#### 2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant chances to the ASTM D5340 (version D5340-12) resulted in an adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

#### Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering." Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling," the PCI deduction is not as high as the former "Weathering and Raveling." Therefore, areas identified only as "(57) Weathering" based on current ASTM standards, which were previously identified as "(52) Weathering and Raveling," may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

## Rigid Portland Cement Concrete Pavement Distress Updates

The previous methodology defined "(70) Scaling" as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included Alkali-Silica Reaction, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as "(76) Alkali-Silica Reaction / ASR." As a result the previous "(70) Scaling" numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded "(70) Scaling," and currently do not exhibit "(76) Alkali-Silica Reactivity / ASR" may potentially see an increase in PCI. Additionally, "(73) Shrinkage Cracks" has been redefined as "(73) Shrinkage Cracking". Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect	
AC/AAC/ APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A	
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A	
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A	
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance	
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance	
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance	
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Crazing - Low	New	Increase in PCI with no maintenance	
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Crazing - Medium	New	Increase in PCI with no maintenance	
	(70) Scaling - High	(70) Scaling, Map Cracking, and Crazing - High	New	Increase in PCI with no maintenance	
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance	
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance	
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance	
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Crazing' may now be identified as 'Shrinkage Cracking'	



# **Chapter 3**



# Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

#### 3.1 Airfield Pavement Network Information

## 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. Figure 3.1.1-1 and Figure 3.1.1-2 provides an inset view of the 2017 Airfield Pavement Network Definition Exhibit and the 2017 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.

Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction


Year	General Work Description				
2013	AP S - Apron Expansion				
2014	TW G, TW K - New Construction				
	AP S - Mill and Overlay				
2015	AP S - Apron Expansion				
	AP S - Reconstruction				

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.





Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit




The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.

Airport Pavement



Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit



The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.


## 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, Figure 3.1.2 summarizes the average age of the pavement sections since any major construction activity has occurred during the PCI Survey inspection. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.





Figure 3.1.2 Average Age of Pavements at Inspection




The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.



# 3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. Figure 3.1.3 summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area





# 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following Figures 3.1.4 (a) and (b) summarize the applicable pavement types observed at this specific airport's airfield.





Figure 3.1.4 (a) Pavement Surface Type by Area (SF)



Figure 3.1.4 (b) Pavement Surface Type by Area (%)



## 3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. Appendix A includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.





#### Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PMP	NORTH APRON - OLD RW	AP N	APRON	4205	950	100	62,989	AAC	1/1/1972
PMP	RUNUP TO RUNWAY 33	AP RU RW33	APRON	5105	100	100	14,310	AAC	6/1/2012
PMP	RUNUP TO RUNWAY 33	AP RU RW33	APRON	5110	200	100	20,490	AAC	1/1/1996
PMP	SOUTH APRON	AP S	APRON	4105	2300	90	203,761	AAC	1/1/1997
PMP	SOUTH APRON	AP S	APRON	4107	110	35	3,846	PCC	1/1/2015
PMP	SOUTH APRON	AP S	APRON	4110	450	45	26,025	AC	1/1/1960
PMP	SOUTH APRON	AP S	APRON	4112	700	200	131,008	AC	5/17/2013
PMP	SOUTH APRON	AP S	APRON	4125	500	220	117,688	AC	12/25/1999
PMP	SOUTH APRON	AP S	APRON	4130	500	150	71,613	AAC	1/1/2015
PMP	SOUTH APRON	AP S	APRON	4135	1300	100	128,753	AC	1/1/2015
PMP	SOUTHWEST APRON	AP SW	APRON	4410	1000	50	61,737	PCC	1/1/2012
PMP	RUNWAY 10-28	RW 10-28	RUNWAY	6105	935	100	271,200	AC	1/1/1968
PMP	RUNWAY 10-28	RW 10-28	RUNWAY	6115	225	100	58,320	AAC	1/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6305	4220	100	220,900	AAC	1/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6310	8400	25	441,800	AAC	1/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6325	500	50	25,000	AC	6/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6330	500	50	50,000	AC	6/1/2012
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6205	2875	100	335,952	AAC	1/1/1972
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6210	6100	25	167,976	AAC	1/1/1972
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6220	350	100	35,000	AAC	1/1/2012
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6225	750	25	17,500	AAC	1/1/2012
PMP	TAXILANE TO SW APRON	TL AP SW	TAXILANE	4505	550	50	28,724	AC	1/1/2004
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4305	675	25	31,764	AC	12/25/1999
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4310	1850	25	49,387	AC	12/25/1999
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4315	3300	25	83,687	AC	12/25/1999





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4320	200	40	16,033	APC	12/25/1999
PMP	TAXIWAY A	TW A	TAXIWAY	105	1500	40	61,729	AAC	11/1/2012
PMP	TAXIWAY A	TW A	TAXIWAY	115	350	40	13,967	AAC	1/1/1997
PMP	TAXIWAY B	TW B	TAXIWAY	210	2600	50	118,013	AAC	1/1/1972
PMP	TAXIWAY C	TW C	TAXIWAY	305	650	50	26,289	AC	1/1/1970
PMP	TAXIWAY C	TW C	TAXIWAY	350	212.5	40	6,807	AAC	11/1/2012
PMP	TAXIWAY C	TW C	TAXIWAY	360	132.5	40	9,668	AAC	11/1/2012
PMP	TAXIWAY D	TW D	TAXIWAY	405	2100	50	105,607	AAC	1/1/1972
PMP	TAXIWAY D	TW D	TAXIWAY	410	275	50	13,072	AAC	1/1/2008
PMP	TAXIWAY D	TW D	TAXIWAY	415	400	50	36,063	AAC	11/1/2012
PMP	TAXIWAY D	TW D	TAXIWAY	420	2415	50	23,098	AAC	1/1/2008
PMP	TAXIWAY D	TW D	TAXIWAY	425	1000	35	36,577	AC	6/1/2012
PMP	TAXIWAY E	TW E	TAXIWAY	505	200	40	12,246	AAC	1/1/2012
PMP	TAXIWAY F	TW F	TAXIWAY	610	2500	50	117,893	AAC	1/1/1972
PMP	TAXIWAY F	TW F	TAXIWAY	612	2500	50	15,543	AAC	1/1/2008
PMP	TAXIWAY F	TW F	TAXIWAY	615	264	50	18,178	AAC	1/1/2012
PMP	TAXIWAY G	TW G	TAXIWAY	710	260	55	15,387	AC	6/1/2012
PMP	TAXIWAY G	TW G	TAXIWAY	715	350	50	17,469	AC	6/1/2014
PMP	TAXIWAY K	TW K	TAXIWAY	1110	2500	35	89,261	AC	11/1/2012
PMP	TAXIWAY K	TW K	TAXIWAY	1115	150	50	7,373	AC	6/1/2014
PMP	TAXIWAY K	TW K	TAXIWAY	1120	280	50	14,097	AC	6/1/2012
PMP	TAXIWAY L	TW L	TAXIWAY	1202	290	75	21,209	AAC	1/1/1996
PMP	TAXIWAY L	TW L	TAXIWAY	1205	260	50	13,025	AC	1/1/1972
PMP	TAXIWAY L	TW L	TAXIWAY	1210	2550	60	152,867	AAC	1/1/1996
PMP	TAXIWAY L	TW L	TAXIWAY	1215	250	60	14,829	AAC	6/1/2012
PMP	TAXIWAY M	TW M	TAXIWAY	1305	884	50	27,738	AC	1/1/1970





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PMP	TAXIWAY M	TW M	TAXIWAY	1306	300	50	29,856	AC	11/1/2012
PMP	TAXIWAY M	TW M	TAXIWAY	1310	900	50	24,002	AC	1/1/1999
PMP	TAXIWAY M	TW M	TAXIWAY	1315	125	110	16,359	AC	1/1/1999
PMP	TAXIWAY M	TW M	TAXIWAY	1320	450	50	95,815	AC	1/1/1970
PMP	TAXIWAY M	TW M	TAXIWAY	1325	450	50	16,146	AAC	1/1/2012
PMP	TAXIWAY N	TW N	TAXIWAY	1405	560	50	28,235	AC	1/1/2004
PMP	TAXIWAY R	TW R	TAXIWAY	1805	600	35	21,726	AC	6/1/2012





# PAGE INTENTIONALLY LEFT BLANK



# **Chapter 4**



# **Chapter 4 – Airfield Pavement** Condition

The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

# 4.1 Airfield Pavement Condition Index (Latest Inspection)

## 4.1.1 Network-Level Analysis

The following Figure 4.1.1 summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.




Figure 4.1.1 Latest Condition - Overall Network

#### 4.1.2 Branch-Level Analysis

The following Figures 4.1.2 (a) through (d) summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.



Figure 4.1.2 (a) Latest Condition - Runway Pavements



Figure 4.1.2 (b) Latest Condition - Taxiway Pavements








Figure 4.1.2 (c) Latest Condition - Apron Pavements





Figure 4.1.2 (d) Latest Condition - Taxilane Pavements







## 4.1.3 Section-Level Analysis

The following Table 4.1.3 provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement. Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.





#### Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
PMP	AP N	NORTH APRON - OLD RW	APRON	4205	62,989	AAC	61	Fair	100%	0%	0%	2	13
PMP	AP RU RW33	RUNUP TO RUNWAY 33	APRON	5105	14,310	AAC	92	Good	100%	0%	0%	1	3
PMP	AP RU RW33	RUNUP TO RUNWAY 33	APRON	5110	20,490	AAC	59	Fair	92%	0%	8%	1	4
PMP	AP S	SOUTH APRON	APRON	4105	203,761	AAC	63	Fair	97%	0%	3%	5	45
PMP	AP S	SOUTH APRON	APRON	4107	3,846	PCC	88	Good	100%	0%	0%	1	1
PMP	AP S	SOUTH APRON	APRON	4110	26,025	AC	51	Poor	100%	0%	0%	1	5
PMP	AP S	SOUTH APRON	APRON	4112	131,008	AC	92	Good	85%	0%	15%	3	29
PMP	AP S	SOUTH APRON	APRON	4125	117,688	AC	48	Poor	95%	0%	5%	3	25
PMP	AP S	SOUTH APRON	APRON	4130	71,613	AAC	100	Good	0%	0%	0%	0	12
PMP	AP S	SOUTH APRON	APRON	4135	128,753	AC	100	Good	0%	0%	0%	0	26
PMP	AP SW	SOUTHWEST APRON	APRON	4410	61,737	PCC	81	Satisfactory	54%	40%	6%	3	21
PMP	RW 10-28	RUNWAY 10-28	RUNWAY	6105	271,200	AC	66	Fair	97%	0%	3%	11	54
PMP	RW 10-28	RUNWAY 10-28	RUNWAY	6115	58,320	AAC	87	Good	100%	0%	0%	3	12
PMP	RW 15-33	RUNWAY 15-33	RUNWAY	6305	220,900	AAC	92	Good	100%	0%	0%	8	44
PMP	RW 15-33	RUNWAY 15-33	RUNWAY	6310	441,800	AAC	93	Good	100%	0%	0%	18	88
PMP	RW 15-33	RUNWAY 15-33	RUNWAY	6325	25,000	AC	84	Satisfactory	100%	0%	0%	2	5
PMP	RW 15-33	RUNWAY 15-33	RUNWAY	6330	50,000	AC	93	Good	100%	0%	0%	2	10
PMP	RW 6-24	RUNWAY 6-24	RUNWAY	6205	335,952	AAC	64	Fair	98%	0%	2%	15	68
PMP	RW 6-24	RUNWAY 6-24	RUNWAY	6210	167,976	AAC	63	Fair	100%	0%	0%	7	34
PMP	RW 6-24	RUNWAY 6-24	RUNWAY	6220	35,000	AAC	94	Good	100%	0%	0%	2	7
PMP	RW 6-24	RUNWAY 6-24	RUNWAY	6225	17,500	AAC	94	Good	100%	0%	0%	1	4
PMP	TL AP SW	TAXILANE TO SW APRON	TAXILANE	4505	28,724	AC	88	Good	100%	0%	0%	1	8
PMP	TL HANG	TAXILANE TO HANGARS	TAXILANE	4305	31,764	AC	39	Very Poor	99%	0%	1%	1	7
PMP	TL HANG	TAXILANE TO HANGARS	TAXILANE	4310	49,387	AC	30	Very Poor	93%	0%	7%	2	10
PMP	TL HANG	TAXILANE TO HANGARS	TAXILANE	4315	83,687	AC	48	Poor	61%	7%	32%	3	21
PMP	TL HANG	TAXILANE TO HANGARS	TAXILANE	4320	16,033	APC	38	Very Poor	92%	0%	8%	1	4
PMP	TW A	TAXIWAY A	TAXIWAY	105	61,729	AAC	93	Good	100%	0%	0%	2	11
PMP	TW A	TAXIWAY A	TAXIWAY	115	13,967	AAC	53	Poor	84%	0%	16%	1	3
PMP	TW B	TAXIWAY B	TAXIWAY	210	118,013	AAC	64	Fair	100%	0%	0%	3	23
PMP	TW C	TAXIWAY C	TAXIWAY	305	26,289	AC	65	Fair	79%	0%	21%	2	5
PMP	TW C	TAXIWAY C	TAXIWAY	350	6,807	AAC	94	Good	100%	0%	0%	1	1
PMP	TW C	TAXIWAY C	TAXIWAY	360	9,668	AAC	94	Good	100%	0%	0%	1	2
PMP	TW D	TAXIWAY D	TAXIWAY	405	105,607	AAC	63	Fair	75%	25%	0%	3	20
PMP	TW D	TAXIWAY D	TAXIWAY	410	13,072	AAC	66	Fair	47%	0%	53%	1	3
PMP	TW D	TAXIWAY D	TAXIWAY	415	36,063	AAC	84	Satisfactory	100%	0%	0%	2	9
PMP	TW D	TAXIWAY D	TAXIWAY	420	23,098	AAC	74	Satisfactory	100%	0%	0%	1	4
PMP	TW D	TAXIWAY D	TAXIWAY	425	36,577	AC	94	Good	100%	0%	0%	1	10

Statewide Airfield Pavement
Management Program
Airport Pavement
Evaluation Report

2017

Pompano Beach Airpark (PMP)






Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
PMP	TW E	TAXIWAY E	TAXIWAY	505	12,246	AAC	89	Good	100%	0%	0%	1	3
PMP	TW F	TAXIWAY F	TAXIWAY	610	117,893	AAC	64	Fair	100%	0%	0%	3	24
PMP	TW F	TAXIWAY F	TAXIWAY	612	15,543	AAC	83	Satisfactory	100%	0%	0%	1	3
PMP	TW F	TAXIWAY F	TAXIWAY	615	18,178	AAC	89	Good	100%	0%	0%	1	4
PMP	TW G	TAXIWAY G	TAXIWAY	710	15,387	AC	96	Good	100%	0%	0%	1	4
PMP	TW G	TAXIWAY G	TAXIWAY	715	17,469	AC	94	Good	100%	0%	0%	1	4
PMP	TW K	TAXIWAY K	TAXIWAY	1110	89,261	AC	94	Good	100%	0%	0%	3	25
PMP	TW K	TAXIWAY K	TAXIWAY	1115	7,373	AC	92	Good	100%	0%	0%	1	2
PMP	TW K	TAXIWAY K	TAXIWAY	1120	14,097	AC	92	Good	100%	0%	0%	1	3
PMP	TW L	TAXIWAY L	TAXIWAY	1202	21,209	AAC	67	Fair	88%	0%	12%	1	4
PMP	TW L	TAXIWAY L	TAXIWAY	1205	13,025	AC	55	Poor	100%	0%	0%	1	3
PMP	TW L	TAXIWAY L	TAXIWAY	1210	152,867	AAC	65	Fair	100%	0%	0%	3	26
PMP	TW L	TAXIWAY L	TAXIWAY	1215	14,829	AAC	88	Good	100%	0%	0%	1	3
PMP	TW M	TAXIWAY M	TAXIWAY	1305	27,738	AC	69	Fair	100%	0%	0%	1	6
PMP	TW M	TAXIWAY M	TAXIWAY	1306	29,856	AC	82	Satisfactory	100%	0%	0%	2	6
PMP	TW M	TAXIWAY M	TAXIWAY	1310	24,002	AC	83	Satisfactory	100%	0%	0%	2	7
PMP	TW M	TAXIWAY M	TAXIWAY	1315	16,359	AC	70	Fair	100%	0%	0%	1	3
PMP	TW M	TAXIWAY M	TAXIWAY	1320	95,815	AC	65	Fair	90%	0%	10%	5	20
PMP	TW M	TAXIWAY M	TAXIWAY	1325	16,146	AAC	92	Good	100%	0%	0%	1	4
PMP	TW N	TAXIWAY N	TAXIWAY	1405	28,235	AC	82	Satisfactory	100%	0%	0%	1	5
PMP	TW R	TAXIWAY R	TAXIWAY	1805	21,726	AC	92	Good	100%	0%	0%	1	4





Figure 4.1.3 is an inset view of the 2017 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits.** 

Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit





# 4.2 Summary of Pavement Condition Evaluation Results

#### 4.2.1 Network-Level Observations

The field PCI Survey performed at Pompano Beach Airpark (PMP) started on 05/08/2017 and was completed on 05/09/2017. The resulting overall average area-weighted PCI value was 75 representing a condition rating of Satisfactory. Pompano Beach Airpark is serviced by three runways: Runway 06-24 is 150-ft wide and 4,001-ft long, Runway 10-28 is 100-ft wide and 3,502-ft long, and Runway 15-33 is 150-ft wide and 4,918-ft long.

Based on the FAA 5010 Report as of 07/28/2017 the Airport has reported 169,722 operations for 12 months ending 05/26/2016.

#### 4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and samplelevel may be referenced for all pavements assessed as part of this System Update. The branchlevel observations discussed are limited to select branches based on use and condition.

#### Runway 06-24

Runway 06-24 consists of 4 sections constructed of AAC. The last construction years range from 1972 to 2012. The average area-weighted PCI for Runway 06-24 is 66 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Runway 06-24 consist of Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, and Weathering.

#### Runway 10-28

Runway 10-28 consists of 2 sections constructed of AC and AAC. The last construction years range from 1968 to 2012. The average area-weighted PCI for Runway 10-28 is 69 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Runway 10-28 consist of Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, and Weathering.

#### Runway 15-33

Runway 15-33 consists of 4 sections constructed of AC and AAC. The last construction year for Runway 15-33 was 2012. The average area-weighted PCI for Runway 15-33 is 92 representing a Good condition rating. The pavement distresses observed were related to Climate distress classifications. Distresses observed in Runway 15-33 consist of Bleeding, Longitudinal & Transverse Cracking, Patching, Raveling, and Weathering.

#### Taxiway D

Taxiway D consists of 5 sections constructed of AC and AAC. The last construction years range from 1972 to 2012. The average area-weighted PCI for Taxiway D is 73 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway D consist of Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, and Weathering.



## Southwest Apron

Southwest Apron consists of 1 section constructed of PCC. The last construction year for Southwest Apron was 2012. The average area-weighted PCI for Southwest Apron is 81 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Southwest Apron consist of Corner Break, Joint Seal Damage, and Joint Spall.

## South Apron

South Apron consists of 7 sections constructed of AC, AAC, and PCC. The last construction years range from 1960 to 2015. The average area-weighted PCI for South Apron is 76 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in South Apron consist of Block Cracking, Depression, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Swelling, Weathering, and Joint Seal Damage.

#### Taxilane to Hangars

Taxilane to Hangars consists of 4 sections constructed of AC and APC. The last construction year for Taxilane to Hangars was 1999. The average area-weighted PCI for Taxilane to Hangars is 40 representing a Very Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxilane to Hangars consist of Alligator Cracking, Bleeding, Block Cracking, Depression, Joint Reflection Cracking, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, and Weathering.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Average Area-Weighted PCI	Condition Rating
Runway	78	Satisfactory
Taxiway	74	Satisfactory
Apron	75	Satisfactory
Taxilane	47	Poor





# 4.3 Forecasted Pavement Conditions

#### 4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to developed forecasted PCI values based on historic trends and statistical models.

#### 4.3.2 Branch-Level Pavement Condition Forecast

The following Figures 4.3.2 (a) through (c) depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2018 through January 2027.




Figure 4.3.2 (a) Forecasted Runway Pavement Performance





Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance







#### 4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.





Table 4.3.3 Forecasted PCI 2018-2027

No.	D	0	J	ast PCI Forecasted PCI												
Network ID	Branch ID	Section ID	Last PCI	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027			
PMP	AP N	4205	61	59	57	55	54	53	52	52	52	52	52			
PMP	AP RU RW33	5105	92	88	85	83	81	80	78	77	75	73	70			
PMP	AP RU RW33	5110	59	57	55	54	53	52	52	52	52	52	52			
PMP	AP S	4105	63	61	59	57	55	54	53	52	52	52	52			
PMP	AP S	4107	88	86	83	80	78	76	73	71	69	67	65			
PMP	AP S	4110	51	49	48	46	45	43	42	40	38	37	35			
PMP	AP S	4112	92	90	89	87	86	84	83	81	79	78	76			
PMP	AP S	4125	48	46	45	43	42	40	39	37	35	34	32			
PMP	AP S	4130	100	84	82	81	79	78	76	74	72	69	67			
PMP	AP S	4135	100	95	93	92	90	88	87	85	84	82	80			
PMP	AP SW	4410	81	79	76	74	72	70	68	66	64	63	61			
PMP	RW 10-28	6105	66	64	63	61	60	58	56	55	53	51	50			
PMP	RW 10-28	6115	87	85	82	80	78	75	73	71	68	67	65			
PMP	RW 15-33	6305	92	90	88	85	83	81	78	76	73	71	69			
PMP	RW 15-33	6310	93	91	89	87	84	82	79	77	74	72	70			
PMP	RW 15-33	6325	84	82	81	79	78	76	74	73	71	69	68			
PMP	RW 15-33	6330	93	91	90	88	87	85	83	82	80	78	77			
PMP	RW 6-24	6205	64	63	62	61	61	60	60	60	60	60	60			
PMP	RW 6-24	6210	63	62	61	61	60	60	60	60	60	60	60			
PMP	RW 6-24	6220	94	92	90	88	85	83	80	78	75	73	71			
PMP	RW 6-24	6225	94	92	90	88	85	83	80	78	75	73	71			
PMP	TL AP SW	4505	88	86	83	81	79	77	75	74	72	71	70			
PMP	TL HANG	4305	39	38	36	35	34	33	32	31	30	29	29			
PMP	TL HANG	4310	30	29	28	27	27	25	24	22	20	16	13			
PMP	TL HANG	4315	48	46	45	43	42	40	39	37	36	35	33			





Natural ID	Branch ID	Ozadian ID	Last PCI	Forecasted PCI											
Network ID	Branch ID	Section ID		2018	2019	2020	2021	2022	2023	2024	2025	2026	2027		
PMP	TL HANG	4320	38	35	30	26	22	18	15	11	7	3	0		
PMP	TW A	105	93	91	88	85	83	80	78	77	75	74	73		
PMP	TW A	115	53	51	50	48	47	46	45	44	44	43	43		
PMP	TW B	210	64	63	61	60	58	56	54	53	51	50	48		
PMP	TW C	305	65	64	63	62	61	60	59	58	57	56	54		
PMP	TW C	350	94	92	89	86	83	81	79	77	76	75	73		
PMP	TW C	360	94	92	89	86	83	81	79	77	76	75	73		
PMP	TW D	405	63	62	60	58	57	55	53	52	50	48	47		
PMP	TW D	410	66	65	63	62	60	59	57	55	54	52	50		
PMP	TW D	415	84	82	80	78	76	75	74	73	72	71	70		
PMP	TW D	420	74	73	72	71	70	69	68	67	66	65	64		
PMP	TW D	425	94	92	89	87	84	82	80	78	76	74	73		
PMP	TW E	505	89	87	84	82	80	78	76	75	74	73	72		
PMP	TW F	610	64	63	61	60	58	56	54	53	51	50	48		
PMP	TW F	612	83	81	79	77	76	75	73	72	71	71	70		
PMP	TW F	615	89	87	84	82	80	78	76	75	74	73	72		
PMP	TW G	710	96	94	91	89	86	84	82	79	77	76	74		
PMP	TW G	715	94	92	89	87	84	82	80	78	76	74	73		
PMP	TW K	1110	94	92	89	87	84	82	80	78	76	74	73		
PMP	TW K	1115	92	90	87	85	82	80	78	76	75	73	71		
PMP	TW K	1120	92	90	87	85	82	80	78	76	75	73	71		
PMP	TW L	1202	67	66	65	63	62	60	59	57	55	54	52		
PMP	TW L	1205	55	54	52	51	49	47	46	44	43	41	39		
PMP	TW L	1210	65	64	62	61	59	58	56	54	52	51	49		
PMP	TW L	1215	88	86	83	81	79	77	76	74	73	72	71		
PMP	TW M	1305	69	68	67	66	65	64	63	63	62	61	60		
PMP	TW M	1306	82	80	78	76	74	73	71	70	69	68	67		





Network ID	Branch ID	Section ID	Last PCI					Forecas	sted PCI				
Network ID	DIAIICII ID	Section id	Lasi PCI	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
PMP	TW M	1310	83	81	79	77	75	73	72	71	69	68	67
PMP	TW M	1315	70	69	68	67	66	65	64	63	62	62	61
PMP	TW M	1320	65	64	63	62	61	60	59	58	57	56	54
PMP	TW M	1325	92	90	87	84	82	80	78	76	75	74	73
PMP	TW N	1405	82	80	78	76	74	73	71	70	69	68	67
PMP	TW R	1805	92	90	87	85	82	80	78	76	75	73	71





#### 4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA AC 150/5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements to determine structural and/or functional conditions at the time of project.







# Chapter 5 - Localized Maintenance and **Repair Planning**

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- Localized Maintenance and Repair includes patching and crack sealing.
- Global Treatments includes surface seals and rejuvenators (flexible pavements).
- > Major Rehabilitation includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

## 5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distress pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety ("stopgap") measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

## Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

#### Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.





# 5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in Table 5.2.1 and Table 5.2.2, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and the FDOT Airfield Pavement Distress Repair Manual. Additionally, the Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis - it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2-1 Localized Maintenance and Repair - Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	High	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft





Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L&TCR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2-2 Localized Maintenance and Repair - Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt





Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT – SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs - Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$6.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$3.00	SqFt

Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs - Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$100.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

<sup>\*</sup>PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.





# 5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in 5.2 Localized M&R Policy. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. Appendix B provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to nearterm Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following Table 5.3-1 summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Plann	ing Material Cost
FDOT - SURFACE SEAL	PREVENTIVE	273,250	SqFt	\$	150,290.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	1,280	SqFt	\$	3,830.00
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	1,270	SqFt	\$	7,600.00
FDOT - CRACK SEALING - PCC	PREVENTIVE	320	Ft	\$	1,360.00
FDOT - JOINT SEAL - PCC	PREVENTIVE	6,575	Ft	\$	18,080.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	9,520	SqFt	\$	57,110.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	58,490	SqFt	\$	175,470.00
FDOT - SURFACE SEAL	STOPGAP	602,275	SqFt	\$	331,260.00
FDOT - CRACK SEALING - AC	STOPGAP	3,855	Ft	\$	11,570.00



The following Table 5.3-2 provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved "End Condition" of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
PMP	AP N	4205	62,989	61	71	\$ 4,170.00
PMP	AP RU RW33	5105	14,310	92	92	\$ -
PMP	AP RU RW33	5110	20,490	59	64	\$ 3,390.00
PMP	AP S	4105	203,761	63	71	\$ 101,590.00
PMP	AP S	4107	3,846	88	100	\$ 800.00
PMP	AP S	4110	26,025	51	60	\$ 14,860.00
PMP	AP S	4112	131,008	92	93	\$ 2,290.00
PMP	AP S	4125	117,688	48	61	\$ 84,690.00
PMP	AP S	4130	71,613	100	100	\$ -
PMP	AP S	4135	128,753	100	100	\$ -
PMP	AP SW	4410	61,737	81	90	\$ 18,650.00
PMP	RW 10-28	6105	271,200	66	81	\$ 141,250.00
PMP	RW 10-28	6115	58,320	87	87	\$ -
PMP	RW 15-33	6305	220,900	92	93	\$ 610.00
PMP	RW 15-33	6310	441,800	93	93	\$ 20.00
PMP	RW 15-33	6325	25,000	84	84	\$ -
PMP	RW 15-33	6330	50,000	93	93	\$ -
PMP	RW 6-24	6205	335,952	64	70	\$ 16,660.00
PMP	RW 6-24	6210	167,976	63	68	\$ 3,030.00
PMP	RW 6-24	6220	35,000	94	94	\$ -
PMP	RW 6-24	6225	17,500	94	94	\$ -
PMP	TL AP SW	4505	28,724	88	88	\$ -
PMP	TL HANG	4305	31,764	39	59	\$ 32,440.00
PMP	TL HANG	4310	49,387	30	51	\$ 138,340.00
PMP	TL HANG	4315	83,687	48	65	\$ 49,800.00
PMP	TL HANG	4320	16,033	38	67	\$ 8,740.00
PMP	TW A	105	61,729	93	93	\$ -
PMP	TW A	115	13,967	53	60	\$ 3,520.00
PMP	TW B	210	118,013	64	69	\$ 10,840.00
PMP	TW C	305	26,289	65	74	\$ 11,670.00
PMP	TW C	350	6,807	94	94	\$ -
PMP	TW C	360	9,668	94	94	\$ -
PMP	TW D	405	105,607	63	70	\$ 7,280.00





Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
PMP	TW D	410	13,072	66	81	\$ 6,040.00
PMP	TW D	415	36,063	84	84	\$ -
PMP	TW D	420	23,098	74	74	\$ -
PMP	TW D	425	36,577	94	94	\$ -
PMP	TW E	505	12,246	89	89	\$ -
PMP	TW F	610	117,893	64	70	\$ 5,670.00
PMP	TW F	612	15,543	83	89	\$ 430.00
PMP	TW F	615	18,178	89	89	\$ -
PMP	TW G	710	15,387	96	98	\$ 60.00
PMP	TW G	715	17,469	94	94	\$ -
PMP	TW K	1110	89,261	94	94	\$ -
PMP	TW K	1115	7,373	92	92	\$ -
PMP	TW K	1120	14,097	92	92	\$ -
PMP	TW L	1202	21,209	67	72	\$ 3,410.00
PMP	TW L	1205	13,025	55	64	\$ 2,890.00
PMP	TW L	1210	152,867	65	70	\$ 19,000.00
PMP	TW L	1215	14,829	88	92	\$ 140.00
PMP	TW M	1305	27,738	69	74	\$ 6,110.00
PMP	TW M	1306	29,856	82	83	\$ 90.00
PMP	TW M	1310	24,002	83	85	\$ 140.00
PMP	TW M	1315	16,359	70	75	\$ 890.00
PMP	TW M	1320	95,815	65	76	\$ 57,060.00
PMP	TW M	1325	16,146	92	92	\$ -
PMP	TW N	1405	28,235	82	86	\$ 320.00
PMP	TW R	1805	21,726	92	92	\$ -

Airport Pavement

**Evaluation Report** 





The following Table 5.3-3 provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3-3 Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 181,160.00
Stopgap	\$ 575,410.00
Planning-Level Localized M&R Needs =	\$ 756,570.00







# Chapter 6 – Major Rehabilitation **Planning**

## 6.1 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. Figures 6.1-1 and 6.1-2 depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI







Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI





#### 6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The Critical PCI concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

- 1. Develop a pavement performance model and refine a prediction model for the pavements considered.
- 2. Select a localized maintenance and repair policy to be used in developing a work
- 3. Apply the selected localized policy to the pavement sections for a range of PCI.
- 4. Compute the unit cost per area for each PCI range.
- 5. Plot the cost versus the PCI.
- 6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

#### 6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended *Minimum Service-Level PCI* for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. Table 6.1.2 summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	60	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)

Airport Pavement

**Evaluation Report** 





# 6.2 Major Rehabilitation Policy

#### 6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA AC 150/5320-6F "Airport Pavement Design and Evaluation." It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following Tables 6.2.1 (a) and (b) provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average GA Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation - Flexible Asphalt Concrete

Rehabilitation Type	General Aviation (GA) Airport
AC Restoration  Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.	75% Mill and Overlay P-101 AC Milling (2") P-603 Bituminous Tack P-401 (HMA) (2")
PCI = 41 to 65	25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2")  Excludes any paved shoulder features.
AC Reconstruction  Full-depth asphalt pavement section reconstruction.	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2")
PCI = 40 or less	Excludes any paved shoulder features.





Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation - Rigid Portland Cement Concrete

Rehabilitation Type	General Aviation (GA) Airport
PCC Restoration  Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.  PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (10")  *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction  Full-depth rigid pavement section reconstruction.  PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (6") P-501 Rigid PCC (10")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

# 6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs

Airport Pavement

**Evaluation Report** 



provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range Flexible Asphalt Concrete Cost Per Si			 tland Cement Cost per SF
Restoration	41 to 65	\$	7.00	\$ 10.00
Reconstruction	0 to 40	\$	9.00	\$ 15.00

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

# 6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

#### 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level investigation, and budgetary constraints. The following Table 6.3.1 summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.





Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	PMP	AP N	4205	AAC	62,989	59	AC Restoration	\$ 441,000.00
2018	PMP	AP RU RW33	5110	AAC	20,490	57	AC Restoration	\$ 144,000.00
2018	PMP	AP S	4105	AAC	203,761	61	AC Restoration	\$ 1,427,000.00
2018	PMP	AP S	4110	AC	26,025	49	AC Restoration	\$ 183,000.00
2018	PMP	AP S	4125	AC	117,688	46	AC Restoration	\$ 896,000.00
2018	PMP	AP SW	4410	PCC	61,737	79	PCC Restoration	\$ 618,000.00
2018	PMP	RW 10-28	6105	AC	271,200	64	AC Restoration	\$ 1,899,000.00
2018	PMP	RW 6-24	6205	AAC	335,952	63	AC Restoration	\$ 2,352,000.00
2018	PMP	RW 6-24	6210	AAC	167,976	62	AC Restoration	\$ 1,176,000.00
2018	PMP	TL HANG	4305	AC	31,764	38	AC Reconstruction	\$ 286,000.00
2018	PMP	TL HANG	4310	AC	49,387	29	AC Reconstruction	\$ 445,000.00
2018	PMP	TL HANG	4315	AC	83,687	46	AC Restoration	\$ 638,000.00
2018	PMP	TL HANG	4320	APC	16,033	35	AC Reconstruction	\$ 145,000.00
2018	PMP	TW A	115	AAC	13,967	51	AC Restoration	\$ 98,000.00
2018	PMP	TW B	210	AAC	118,013	63	AC Restoration	\$ 827,000.00
2018	PMP	TW C	305	AC	26,289	64	AC Restoration	\$ 185,000.00
2018	PMP	TW D	405	AAC	105,607	62	AC Restoration	\$ 740,000.00
2018	PMP	TW F	610	AAC	117,893	63	AC Restoration	\$ 826,000.00
2018	PMP	TW L	1205	AC	13,025	54	AC Restoration	\$ 92,000.00
2018	PMP	TW L	1210	AAC	152,867	64	AC Restoration	\$ 1,071,000.00
2018	PMP	TW M	1320	AC	95,815	64	AC Restoration	\$ 671,000.00
2019	PMP	TW D	410	AAC	13,072	63	AC Restoration	\$ 92,000.00
2020	PMP	TW L	1202	AAC	21,209	63	AC Restoration	\$ 149,000.00
2022	PMP	TW M	1305	AC	27,738	64	AC Restoration	\$ 195,000.00
2023	PMP	TW M	1315	AC	16,359	64	AC Restoration	\$ 115,000.00
2027	PMP	TW D	420	AAC	23,098	64	AC Restoration	\$ 162,000.00

<sup>\*</sup>All values have been rounded to the nearest thousand-dollar.

The following Figure 6.3.1-1 summarizes the section-level major rehabilitation needs for a 10year period between 2018 and 2027. Figure 6.3.1-2 provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in Appendix C Technical **Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.





Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year









Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit





# **Chapter 7**



# **Chapter 7 – Conclusion**

#### 7.1 Recommendations

#### 7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

Pompano Beach Airpark (PMP)

A high priority should be considered for continuous maintenance record keeping and reinspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

# 7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2018-2027. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

# 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- Develop a detailed preventive maintenance program for the airport.
- Further refine and implement the identified 10-year major rehabilitation needs.
- Maintain detailed records on pavement maintenance, construction, and inspection.
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).





# 7.2 Supporting Documents

#### 001 - Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in Appendix C Technical Exhibits. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in Appendix A **Pavement Analysis Tables.** 

#### 002 - Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in is located in Appendix C Technical Exhibits. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

#### 003 - Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in Appendix C Technical Exhibits. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in Appendix E Inspection Distress Details) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

## 004 - Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in Appendix C Technical **Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation.

#### Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in Appendix D Inspection Photograph Documentation. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.

**Statewide Airfield Pavement Management Program** 

Airport Pavement **Evaluation Report** 

2017

Pompano Beach Airpark (PMP)





#### 7.3 Conclusion

The FDOT SAPMP Update Phase 1 2016-2017 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars 150/5380-7B "Airport Pavement Management Program (PMP)" and 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."



# Appendix A

Airfield Pavement Analysis Tables








Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PMP	NORTH APRON - OLD RW	AP N	APRON	4205	950	100	62,989	AAC	1/1/1972
PMP	RUNUP TO RUNWAY 33	AP RU RW33	APRON	5105	100	100	14,310	AAC	6/1/2012
PMP	RUNUP TO RUNWAY 33	AP RU RW33	APRON	5110	200	100	20,490	AAC	1/1/1996
PMP	SOUTH APRON	AP S	APRON	4105	2300	90	203,761	AAC	1/1/1997
PMP	SOUTH APRON	AP S	APRON	4107	110	35	3,846	PCC	1/1/2015
PMP	SOUTH APRON	SOUTH APRON AP S APRON 4110 450 45 2		26,025	AC	1/1/1960			
PMP	SOUTH APRON	AP S	APRON	4112	700	200	131,008	AC	5/17/2013
PMP	SOUTH APRON	AP S	APRON	4125	500	220	117,688	AC	12/25/1999
PMP	SOUTH APRON	AP S	APRON	4130	500	150	71,613	AAC	1/1/2015
PMP	SOUTH APRON	AP S	APRON	4135	1300	100	128,753	AC	1/1/2015
PMP	SOUTHWEST APRON	AP SW	APRON	4410	1000	50	61,737	PCC	1/1/2012
PMP	RUNWAY 10-28	RW 10-28	RUNWAY	6105	935	100	271,200	AC	1/1/1968
PMP	RUNWAY 10-28	RW 10-28	RUNWAY	6115	225	100	58,320	AAC	1/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6305	4220	100	220,900	AAC	1/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6310	8400	25	441,800	AAC	1/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6325	500	50	25,000	AC	6/1/2012
PMP	RUNWAY 15-33	RW 15-33	RUNWAY	6330	500	50	50,000	AC	6/1/2012
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6205	2875	100	335,952	AAC	1/1/1972
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6210	6100	25	167,976	AAC	1/1/1972
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6220	350	100	35,000	AAC	1/1/2012
PMP	RUNWAY 6-24	RW 6-24	RUNWAY	6225	750	25	17,500	AAC	1/1/2012
PMP	TAXILANE TO SW APRON	TL AP SW	TAXILANE	4505	550	50	28,724	AC	1/1/2004
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4305	675	25	31,764	AC	12/25/1999
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4310	1850	25	49,387	AC	12/25/1999
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4315	3300	25	83,687	AC	12/25/1999
PMP	TAXILANE TO HANGARS	TL HANG	TAXILANE	4320	200	40	16,033	APC	12/25/1999
PMP	TAXIWAY A	TW A	TAXIWAY	105	1500	40	61,729	AAC	11/1/2012
PMP	TAXIWAY A	TW A	TAXIWAY	115	350	40	13,967	AAC	1/1/1997
PMP	TAXIWAY B	TW B	TAXIWAY	210	2600	50	118,013	AAC	1/1/1972
PMP	TAXIWAY C	TW C	TAXIWAY	305	650	50	26,289	AC	1/1/1970
PMP	TAXIWAYC	TW C	TAXIWAY	350	212.5	40	6,807	AAC	11/1/2012
PMP	TAXIWAYC	TW C	C TAXIWAY 360 132.5 40		40	9,668	AAC	11/1/2012	
PMP	TAXIWAY D	TAXIWAY D TW D TAXIWAY 405 2100 50		50	105,607	AAC	1/1/1972		
PMP	TAXIWAY D TW D TAXIWAY 410 275		50	13,072	AAC	1/1/2008			
PMP	TAXIWAY D TW D TAXIWAY 415 400		50	36,063	AAC	11/1/2012			
PMP	TAXIWAY D	TW D	TAXIWAY	420	2415	50	23,098	AAC	1/1/2008

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2017

# Pompano Beach Airpark (PMP)





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PMP	TAXIWAY D	TW D	TAXIWAY	425	1000	35	36,577	AC	6/1/2012
PMP	TAXIWAY E	TW E	TAXIWAY	505	200	40	12,246	AAC	1/1/2012
PMP	TAXIWAY F	TW F	TAXIWAY	610	2500	50	117,893	AAC	1/1/1972
PMP	TAXIWAY F	TW F	TAXIWAY	612	2500	50	15,543	AAC	1/1/2008
PMP	TAXIWAY F	TW F	TAXIWAY	615	264	50	18,178	AAC	1/1/2012
PMP	TAXIWAY G	TW G	TAXIWAY	710	260	55	15,387	AC	6/1/2012
PMP	TAXIWAY G	TW G	TAXIWAY	715	350	50	17,469	AC	6/1/2014
PMP	TAXIWAY K	TW K	TAXIWAY	1110	2500	35	89,261	AC	11/1/2012
PMP	TAXIWAY K	TW K	TAXIWAY	1115	150	50	7,373	AC	6/1/2014
PMP	TAXIWAY K	TW K	TAXIWAY	1120	280	50	14,097	AC	6/1/2012
PMP	TAXIWAY L	TW L	TAXIWAY	1202	290	75	21,209	AAC	1/1/1996
PMP	TAXIWAY L	TW L	TAXIWAY	1205	260	50	13,025	AC	1/1/1972
PMP	TAXIWAY L	TW L	TAXIWAY	1210	2550	60	152,867	AAC	1/1/1996
PMP	TAXIWAY L	TW L	TAXIWAY	1215	250	60	14,829	AAC	6/1/2012
PMP	TAXIWAY M	TW M	TAXIWAY	1305	884	50	27,738	AC	1/1/1970
PMP	TAXIWAY M	TW M	TAXIWAY	1306	300	50	29,856	AC	11/1/2012
PMP	TAXIWAY M	TW M	TAXIWAY	1310	900	50	24,002	AC	1/1/1999
PMP	TAXIWAY M	TW M	TAXIWAY	1315	125	110	16,359	AC	1/1/1999
PMP	TAXIWAY M	TW M	TAXIWAY	1320	450	50	95,815	AC	1/1/1970
PMP	TAXIWAY M	TW M	TAXIWAY	1325	450	50	16,146	AAC	1/1/2012
PMP	TAXIWAYN	TW N	TAXIWAY	1405	560	50	28,235	AC	1/1/2004
PMP	TAXIWAY R	TW R	TAXIWAY	1805	600	35	21,726	AC	6/1/2012





Table A-2 Pavement Condition Index Summary (Last Inspection) - Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	RUNWAY 10-28	RUNWAY	6105	271,200	66	Fair
PMP	RUNWAY 10-28	RUNWAY	6115	58,320	87	Good
PMP	RUNWAY 6-24	RUNWAY	6205	335,952	64	Fair
PMP	RUNWAY 6-24	RUNWAY	6210	167,976	63	Fair
PMP	RUNWAY 6-24	RUNWAY	6220	35,000	94	Good
PMP	RUNWAY 6-24	RUNWAY	6225	17,500	94	Good
PMP	RUNWAY 15-33	RUNWAY	6305	220,900	92	Good
PMP	RUNWAY 15-33	RUNWAY	6310	441,800	93	Good
PMP	RUNWAY 15-33	RUNWAY	6325	25,000	84	Satisfactory
PMP	RUNWAY 15-33	RUNWAY	6330	50,000	93	Good
PMP	TAXIWAY A	TAXIWAY	105	61,729	93	Good
PMP	TAXIWAY A	TAXIWAY	115	13,967	53	Poor
PMP	TAXIWAY B	TAXIWAY	210	118,013	64	Fair
PMP	TAXIWAY C	TAXIWAY	305	26,289	65	Fair
PMP	TAXIWAY C	TAXIWAY	350	6,807	94	Good
PMP	TAXIWAY C	TAXIWAY	360	9,668	94	Good
PMP	TAXIWAY D	TAXIWAY	405	105,607	63	Fair
PMP	TAXIWAY D	TAXIWAY	410	13,072	66	Fair
PMP	TAXIWAY D	TAXIWAY	415	36,063	84	Satisfactory
PMP	TAXIWAY D	TAXIWAY	420	23,098	74	Satisfactory
PMP	TAXIWAY D	TAXIWAY	425	36,577	94	Good
PMP	TAXIWAY E	TAXIWAY	505	12,246	89	Good
PMP	TAXIWAY F	TAXIWAY	610	117,893	64	Fair
PMP	TAXIWAY F	TAXIWAY	612	15,543	83	Satisfactory
PMP	TAXIWAY F	TAXIWAY	615	18,178	89	Good
PMP	TAXIWAY G	TAXIWAY	710	15,387	96	Good
PMP	TAXIWAY G	TAXIWAY	715	17,469	94	Good
PMP	TAXIWAY K	TAXIWAY	1110	89,261	94	Good
PMP	TAXIWAY K	TAXIWAY	1115	7,373	92	Good
PMP	TAXIWAY K	TAXIWAY	1120	14,097	92	Good
PMP	TAXIWAY L	TAXIWAY	1202	21,209	67	Fair
PMP	TAXIWAYL	TAXIWAY	1205	13,025	55	Poor
PMP	TAXIWAY L	TAXIWAY	1210	152,867	65	Fair
PMP	TAXIWAYL	TAXIWAY	1215	14,829	88	Good
PMP	TAXIWAY M	TAXIWAY	1305 27,738		69	Fair
PMP	TAXIWAY M TAXIWAY		1306	29,856	82	Satisfactory
PMP	TAXIWAY M	TAXIWAY	1310	24,002	83	Satisfactory

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report

2017

# Pompano Beach Airpark (PMP)





Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	TAXIWAY M	TAXIWAY	1315	16,359	70	Fair
PMP	TAXIWAY M	TAXIWAY	1320	95,815	65	Fair
PMP	TAXIWAY M	TAXIWAY	1325	16,146	92	Good
PMP	TAXIWAY N	TAXIWAY	1405	28,235	82	Satisfactory
PMP	TAXIWAY R	TAXIWAY	1805	21,726	92	Good
PMP	TAXILANE TO HANGARS	TAXILANE	4305	31,764	39	Very Poor
PMP	TAXILANE TO HANGARS	TAXILANE	4310	49,387	30	Very Poor
PMP	TAXILANE TO HANGARS	TAXILANE	4315	83,687	48	Poor
PMP	TAXILANE TO HANGARS	TAXILANE	4320	16,033	38	Very Poor
PMP	TAXILANE TO SW APRON	TAXILANE	4505	28,724	88	Good
PMP	SOUTH APRON	APRON	4105	203,761	63	Fair
PMP	SOUTH APRON	APRON	4107	3,846	88	Good
PMP	SOUTH APRON	APRON	4110	26,025	51	Poor
PMP	SOUTH APRON	APRON	4112	131,008	92	Good
PMP	SOUTH APRON	APRON	4125	117,688	48	Poor
PMP	SOUTH APRON	APRON	4130	71,613	100	Good
PMP	SOUTH APRON	APRON	4135	128,753	100	Good
PMP	NORTH APRON - OLD RW	APRON	4205	62,989	61	Fair
PMP	SOUTHWEST APRON	APRON	4410	61,737	81	Satisfactory
PMP	RUNUP TO RUNWAY 33	APRON	5105	14,310	92	Good
PMP	RUNUP TO RUNWAY 33	APRON	5110	20,490	59	Fair





Table A-3 Forecasted PCI 2018-2027

								Forecas	sted PC	I			
Network ID	Branch ID	Section ID	Last PCI	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
PMP	AP N	4205	61	59	57	55	54	53	52	52	52	52	52
PMP	AP RU RW33	5105	92	88	85	83	81	80	78	77	75	73	70
PMP	AP RU RW33	5110	59	57	55	54	53	52	52	52	52	52	52
PMP	AP S	4105	63	61	59	57	55	54	53	52	52	52	52
PMP	AP S	4107	88	86	83	80	78	76	73	71	69	67	65
PMP	AP S	4110	51	49	48	46	45	43	42	40	38	37	35
PMP	AP S	4112	92	90	89	87	86	84	83	81	79	78	76
PMP	AP S	4125	48	46	45	43	42	40	39	37	35	34	32
PMP	AP S	4130	100	84	82	81	79	78	76	74	72	69	67
PMP	AP S	4135	100	95	93	92	90	88	87	85	84	82	80
PMP	AP SW	4410	81	79	76	74	72	70	68	66	64	63	61
PMP	RW 10-28	6105	66	64	63	61	60	58	56	55	53	51	50
PMP	RW 10-28	6115	87	85	82	80	78	75	73	71	68	67	65
PMP	RW 15-33	6305	92	90	88	85	83	81	78	76	73	71	69
PMP	RW 15-33	6310	93	91	89	87	84	82	79	77	74	72	70
PMP	RW 15-33	6325	84	82	81	79	78	76	74	73	71	69	68
PMP	RW 15-33	6330	93	91	90	88	87	85	83	82	80	78	77
PMP	RW 6-24	6205	64	63	62	61	61	60	60	60	60	60	60
PMP	RW 6-24	6210	63	62	61	61	60	60	60	60	60	60	60
PMP	RW 6-24	6220	94	92	90	88	85	83	80	78	75	73	71
PMP	RW 6-24	6225	94	92	90	88	85	83	80	78	75	73	71
PMP	TL AP SW	4505	88	86	83	81	79	77	75	74	72	71	70
PMP	TL HANG	4305	39	38	36	35	34	33	32	31	30	29	29
PMP	TL HANG	4310	30	29	28	27	27	25	24	22	20	16	13
PMP	TL HANG	4315	48	46	45	43	42	40	39	37	36	35	33
PMP	TL HANG	4320	38	35	30	26	22	18	15	11	7	3	0
PMP	TW A	105	93	91	88	85	83	80	78	77	75	74	73
PMP	TW A	115	53	51	50	48	47	46	45	44	44	43	43
PMP	TW B	210	64	63	61	60	58	56	54	53	51	50	48
PMP	TW C	305	65	64	63	62	61	60	59	58	57	56	54
PMP	TW C	350	94	92	89	86	83	81	79	77	76	75	73
PMP	TW C	360	94	92	89	86	83	81	79	77	76	75	73
PMP	TW D	405	63	62	60	58	57	55	53	52	50	48	47
PMP	TW D	410	66	65	63	62	60	59	57	55	54	52	50
PMP	TW D	415	84	82	80	78	76	75	74	73	72	71	70
PMP	TW D	420	74	73	72	71	70	69	68	67	66	65	64
PMP	TW D	425	94	92	89	87	84	82	80	78	76	74	73

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report

2017

Pompano Beach Airpark (PMP)





Natura da ID	Daniel ID	Cartier ID	L L DOL					Forecas	sted PC	I			
Network ID	Branch ID	Section ID	Last PCI	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
PMP	TW E	505	89	87	84	82	80	78	76	75	74	73	72
PMP	TW F	610	64	63	61	60	58	56	54	53	51	50	48
PMP	TW F	612	83	81	79	77	76	75	73	72	71	71	70
PMP	TW F	615	89	87	84	82	80	78	76	75	74	73	72
PMP	TW G	710	96	94	91	89	86	84	82	79	77	76	74
PMP	TW G	715	94	92	89	87	84	82	80	78	76	74	73
PMP	TW K	1110	94	92	89	87	84	82	80	78	76	74	73
PMP	TW K	1115	92	90	87	85	82	80	78	76	75	73	71
PMP	TW K	1120	92	90	87	85	82	80	78	76	75	73	71
PMP	TW L	1202	67	66	65	63	62	60	59	57	55	54	52
PMP	TW L	1205	55	54	52	51	49	47	46	44	43	41	39
PMP	TW L	1210	65	64	62	61	59	58	56	54	52	51	49
PMP	TW L	1215	88	86	83	81	79	77	76	74	73	72	71
PMP	TW M	1305	69	68	67	66	65	64	63	63	62	61	60
PMP	TW M	1306	82	80	78	76	74	73	71	70	69	68	67
PMP	TW M	1310	83	81	79	77	75	73	72	71	69	68	67
PMP	TW M	1315	70	69	68	67	66	65	64	63	62	62	61
PMP	TW M	1320	65	64	63	62	61	60	59	58	57	56	54
PMP	TW M	1325	92	90	87	84	82	80	78	76	75	74	73
PMP	TW N	1405	82	80	78	76	74	73	71	70	69	68	67
PMP	TW R	1805	92	90	87	85	82	80	78	76	75	73	71

# **Work History Report**

Page 1 of 10

Pavement Database: FDOT

		2 07 0	nem Danabase.					
Network:	POMPAN	O BEACH	Branch: AP N	NORT	H APRON -	Section:	4205	Surface: AAC
<b>L.C.D.:</b> 1/1/1	972 Us	se: APRON	Rank: P L	ength: 950	.00 (Ft) <b>Wi</b>	dth: 100.0	00 (Ft) True Area:	
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comr	nents
1/1/1972	IMPORT ED	BUILT		0.00	1.50	<b>V</b>	1972 1.5" P-401 OL	ON EXISTING
	LD							
Network:	POMPAN	О ВЕАСН	Branch: AP RU	RW33 RUNU	P TO RUN	Section:	5105	Surface: AAC
<b>L.C.D.:</b> 6/1/2	012 Us	se: APRON	Rank: P L	ength: 100	.00 (Ft) <b>Wi</b>	dth: 100.0	00 (Ft) True Area:	14,310.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comr	nents
6/1/2012	ML-OV	MILL and O		0.00	0.00	<b>(</b>		
1/1/1950	NU-IN	New Constru	ction - Initial	0.00	0.00	<b>V</b>	ESTIMATED 1950 I	BIT SECTION UN
Network:	POMPAN	О ВЕАСН	Branch: AP RU	RW33 RUNU	P TO RUN	Section:	5110	Surface: AAC
<b>L.C.D.:</b> 1/1/1	996 <b>U</b> s	se: APRON	Rank: P L	ength: 200	.00 (Ft) <b>Wi</b>	dth: 100.0	00 (Ft) <b>True Area:</b>	20,490.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comm	nents
1/1/1996	ML-OV	MILL and O	VERLAY	0.00	0.00		Estimated Constructi	on Date
1/1/1950	NU-IN	New Constru	ction - Initial	0.00	0.00			
Network: L.C.D.: 1/1/1		O BEACH se: APRON	Branch: APS Rank: P L	SOUT ength: 2,300	H APRON .00 (Ft) <b>Wi</b> o	Section:	4105 00 (Ft) <b>True Area:</b>	Surface: AAC 203,761.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comm	nents
1/1/1997	IMPORT ED	BUILT		0.00	0.00	<	1997 STRUCTURAL	L AC OVERLAY
1/1/1970		OVERLAY		0.00	0.00	<b>V</b>	EST 1970 AC PAVE	EMENT
Natarak	DOMDAN.	ODEACH	Donath, ADC	COLUT	H ADDON	G4'	4107	Coords and DCC
Network: L.C.D.: 1/1/2		se: APRON	Branch: APS Rank: P L		H APRON .00 (Ft) <b>Wi</b> e	Section: dth: 35.0	90 (Ft) <b>True Area:</b>	Surface: PCC 3,846.00 (SqFt)
Work Date	Work Code		Description	Cost	Thickness	Major M&R	Comm	
1/1/2015		New Constru	ction - PCC	0.00	(in) 0.00			
Network:	POMPAN	O BEACH	<b>Branch:</b> AP S	SOUT	H APRON	Section:	4110	Surface: AC
<b>L.C.D.:</b> 1/1/1		se: APRON	Rank: P L	ength: 450	` '		00 (Ft) True Area:	26,025.00 (SqFt)
Work Date	Work Code		Description	Cost	Thickness (in)	Major M&R	Comr	
1/1/1960	IMPORT ED	BUILT		0.00	0.00	<b>&lt;</b>	EST 1960 BIT SECT	TON UNKNOWN
Network:	POMPAN	О ВЕАСН	<b>Branch:</b> AP S	SOUT	H APRON	Section:	4112	Surface: AC
<b>L.C.D.:</b> 5/17/		se: APRON	Rank: P L	ength: 700			00 (Ft) True Area:	131,008.00 (SqFt)
Work Date	Work Code		Description	Cost	Thickness (in)	Major M&R	Comr	nents
5/17/2013	NU-IN	New Constru	ction - Initial	0.00	0.00			

Pavement Management System PAVER 7.0 TM

Work

Code

ED

IMPORT BUILT

**Work Description** 

ML-OV MILL and OVERLAY

**Work Date** 

1/1/2012

1/1/1969

# **Work History Report**

Page 2 of 10

Pavement Database: FDOT

		Taven	teni Daiabase.	TDOI				
Network:	POMPAN	О ВЕАСН	Branch: APS	SOUT	H APRON	Section:	4125	Surface: AC
<b>L.C.D.:</b> 12/25	5/199 Us	se: APRON	Rank: P L	ength: 500	.00 (Ft) <b>Wi</b> o	dth: 220.0	00 (Ft) True Area:	117,688.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comr	ments
12/25/1999	NU-IN	New Constru	ction - Initial	0.00	0.00	<b>V</b>		
Network:	POMPAN	O BEACH	Branch: APS	SOUT	H APRON	Section:	4130	Surface: AAC
<b>L.C.D.:</b> 1/1/2		se: APRON					00 (Ft) True Area:	71,613.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comr	-
1/1/2015	ML-OV	MILL and OV	/ERLAY	0.00	0.00	<b>~</b>		
12/25/1999	NU-IN	New Constru	ction - Initial	0.00	0.00	<b>V</b>		
Network:	POMPAN	O BEACH	Branch: APS	SOUT	H APRON	Section:	4135	Surface: AC
L.C.D.: 1/1/2		se: APRON		ength: 1,300			00 (Ft) True Area:	
Work Date	Work	Work	Description	Cost	Thickness	Major	Comr	, , ,
1/1/2015	Code NC-AC	New Constru		0.00	(in) 0.00	M&R	Com	nents
1/1/2013	NC-AC	New Collstru	cuon - AC	0.00	0.00	<b>V</b>		
Network:	POMPAN	О ВЕАСН	Branch: AP SW	SOUT	HWEST AP	Section:	4410	Surface: PCC
<b>L.C.D.:</b> 1/1/2	012 Us	se: APRON	Rank: P L	ength: 1,000	.00 (Ft) Wio	dth: 50.0	00 (Ft) True Area:	61,737.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comr	nents
1/1/2012	NU-IN	New Constru	ction - Initial	0.00	0.00		ESTIMATED CONS	STRUCTION
	I							
Network:			Branch: RW 10		VAY 10-28	Section:		Surface: AC
<b>L.C.D.:</b> 1/1/1		se: RUNWAY	Rank: P L	ength: 935	. ,		00 (Ft) True Area:	271,200.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comr	nents
1/1/1968	IMPORT ED	BUILT		0.00	1.50	<b>\</b>	1968 1.5" BIT 6" LII	MEROCK
		O BEACH	Branch: RW 10		VAY 10-28	Section:		Surface: AAC
<b>L.C.D.:</b> 1/1/2		se: RUNWAY	Rank: P L	ength: 225		1	00 (Ft) True Area:	58,320.00 (SqFt)
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comr	nents
1/1/2012		MILL and OV	/ERLAY	0.00	0.00	<b>V</b>		
1/1/1968	IMPORT ED	BUILT		0.00	1.50		1968 1.5" BIT 6" LII	MEROCK
						ļ		
Network:	POMPAN	О ВЕАСН	Branch: RW 15	-33 RUNV	VAY 15-33	Section:	6305	Surface: AAC
<b>L.C.D.:</b> 1/1/2	012 Us	se: RUNWAY	Rank: P L	ength: 4,220	.00 (Ft) Wio	dth: 100.0	00 (Ft) <b>True Area:</b>	220,900.00 (SqFt)

Pavement Management System PAVER 7.0 TM

Cost

0.00

0.00

Thickness

(in)

0.00

1.50

Major

M&R

~

Comments

1969 1.5" P-401 OL ON EXISTING

1/1/1972

NU-IN

New Construction - Initial

# **Work History Report**

Page 3 of 10

Pavement Database: FDOT

Network:	DOMD A NA	O BEACH Branch: RW 15	. 22 DIINW	VAY 15-33	Section:	6310 Surface: AAC
L.C.D.: 1/1/2			ength: 8,400			00 (Ft) <b>True Area:</b> 441,800.00 (SqFt)
L.C.D.: 1/1/2	Work			Thickness	Major	00 (11) True Area. 441,900.00 (3q11)
Work Date	Code	Work Description	Cost	(in)	M&R	Comments
1/1/2012		MILL and OVERLAY	0.00	0.00	>	
1/1/1969	IMPORT ED	BUILT	0.00	1.50	<b>V</b>	1969 1.5" P-401 OL ON EXISTING R/W
	EB					10 11
Network:	POMPAN	O BEACH Branch: RW 15	5-33 RUNV	VAY 15-33	Section:	6325 Surface: AC
<b>L.C.D.:</b> 6/1/2	012 Us	se: RUNWAY Rank: P I	ength: 500	.00 (Ft) <b>Wi</b>	dth: 50.	00 (Ft) <b>True Area:</b> 25,000.00 (SqFt)
Work Date	Work	Work Description	Cost	Thickness	Major	Comments
6/1/2012	Code NU-IN	New Construction - Initial	0.00	(in) 0.00	M&R ✓	2" P-401, 8" P-211 LIMEROCK, 12" P-
0/1/2012	110-111	ivew construction - initial	0.00	0.00		2 1-401, 6 1-211 EIWEROCK, 12 1-
Network:	POMPAN	O BEACH <b>Branch:</b> RW 15	5-33 RUNV	VAY 15-33	Section:	6330 Surface: AC
<b>L.C.D.:</b> 6/1/2						00 (Ft) <b>True Area:</b> 50,000.00 (SqFt)
	Work			Thickness	Major	
Work Date	Code	Work Description	Cost	(in)	M&R	Comments
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<b>V</b>	2" P-401, 8" P-211 LIMEROCK BASE,
Network:	DOMD A NA	O BEACH <b>Branch:</b> RW 6-	24 DUNIN	VAY 6-24	Section:	6205 Surface: AAC
L.C.D.: 1/1/1						
L.C.D.: 1/1/1	Work	se: KUNWAT Kank: F T	<b>Length:</b> 2,875	Thickness	Major	00 (Ft) <b>True Area:</b> 335,952.00 (SqFt)
Work Date	Code	Work Description	Cost	(in)	M&R	Comments
1/1/1972	IMPORT	BUILT	0.00	1.50	>	1972 1.5" P-401 OL ON EXISTING
	ED					R/W
Network:	POMPAN	O BEACH <b>Branch:</b> RW 6-	24 RUNV	VAY 6-24	Section:	6210 Surface: AAC
<b>L.C.D.:</b> 1/1/1	972 Us	se: RUNWAY Rank: P I	ength: 6,100		dth: 25.	00 (Ft) <b>True Area:</b> 167,976.00 (SqFt)
Worls Date	Work			Thickness	Major	
Work Date	Code	Work Description	Cost	(in)	M&R	Comments
1/1/1972	IMPORT ED	BUILT	0.00	1.50		1972 1.5" P-401 OL ON EXISTING R/W
Network:	POMPAN	O BEACH Branch: RW 6-	24 RUNV	VAY 6-24	Section:	6220 Surface: AAC
<b>L.C.D.:</b> 1/1/2	012 Us	se: RUNWAY Rank: P I	ength: 350	.00 (Ft) <b>Wi</b>	dth: 100.	00 (Ft) <b>True Area:</b> 35,000.00 (SqFt)
Work Date	Work	Work Description	Cost	Thickness	Major	Comments
1/1/2012	Code ML-OV	MILL and OVERLAY	0.00	(in) 0.00	M&R ✓	
1/1/1972		OVERLAY	0.00	1.50		1972 1.5" P-401 OL
1/1/1060	ED	DIWIT	1 0.00	0.00		1000 P 401 OL ON EVYCEPING
1/1/1969	IMPORT ED	ROILI	0.00	0.00		1969 P-401 OL ON EXISTING
Network:	POMPAN	O BEACH Branch: RW 6-	24 RUNV	VAY 6-24	Section:	6225 Surface: AAC
<b>L.C.D.:</b> 1/1/2	012 Us	se: RUNWAY Rank: P I	Length: 750	.00 (Ft) <b>Wi</b>	dth: 25.	00 (Ft) <b>True Area:</b> 17,500.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012		MILL and OVERLAY	0.00	0.00	M&K	
			1	0.00		

Pavement Management System PAVER 7.0 TM

0.00

0.00

# **Work History Report**

Page 4 of 10

Pavement Database: FDOT

Network:								
	POMPAN	O BEACH	Branch: TL AP	SW TAXII	LANE TO S	Section:	4505	Surface: AC
<b>L.C.D.:</b> 1/1/2	004 Us	se: TAXILAN	Rank: P L	ength: 550	.00 (Ft) <b>Wi</b>	dth: 50.0	00 (Ft) True Area:	28,724.00 (SqFt)
Work Date	Work Code	Work Description		Cost Thickness Major (in) M&R		Comments		
1/1/2004	NU-IN	New Constructi	ion - Initial	0.00	` /		ESTIMATED CONS	STRUCTION
	•	•				•		
			Branch: TL HA	NG TAXII	LANE TO H	Section:	4305	Surface: AC
L.C.D.: 12/25		se: TAXILAN	Rank: P L	ength: 675			00 (Ft) True Area:	31,764.00 (SqFt)
Work Date	Work Code	Work Description		Cost	Thickness Major (in) M&R Comm		nents	
12/25/1999	NU-IN	New Constructi	ion - Initial	0.00	0.00	<b>V</b>		
Network: POMPANO BEACH Branch: TL HANG TAXILANE TO H Section: 4310 Surface: AC								
		se: TAXILAN		ength: 1,850			4310 00 (Ft) <b>True Area:</b>	<b>Surface:</b> AC 49,387.00 (SqFt)
	Work				Thickness	Major		
Work Date	Code		escription	Cost	(in)	M&R	Comn	nents
12/25/1999	NU-IN	New Constructi	ion - Initial	0.00	0.00	<b>&gt;</b>		
Notwork	POMDA N	О ВЕАСН	Branch: TL HA	NG TAVII	LANE TO H	Section:	4315	Surface: AC
		se: TAXILAN		ength: 3,300			00 (Ft) <b>True Area:</b>	
	Work				Thickness	Major	. ,	
Work Date	Code		escription	Cost	(in)	M&R	Comn	nents
12/25/1999	NU-IN	New Constructi	ion - Initial	0.00	0.00	<b>~</b> :		
Network: POMPANO BEACH Branch: TL HANG TAXILANE TO H Section: 4320 Surface: APC								
Network:	POMPAN	О ВЕАСН	Branch: TL HA	NG TAXII	LANE TO H	Section:	4320	Surface: APC
Network: L.C.D.: 12/25		O BEACH					4320 00 (Ft) <b>True Area:</b>	<b>Surface:</b> APC 16,033.00 (SqFt)
	5/199 Us Work	se: TAXILAN			.00 (Ft) Wi	dth: 40.0		16,033.00 (SqFt)
L.C.D.: 12/25	5/199 <b>U</b> s	se: TAXILAN	Rank: P L	ength: 200	.00 (Ft) <b>Wi</b>	dth: 40.0 Major M&R	00 (Ft) True Area:	16,033.00 (SqFt)
L.C.D.: 12/25 Work Date	5/199 Us Work Code	se: TAXILAN Work Do	Rank: P L	ength: 200	Thickness (in)	Major M&R	00 (Ft) True Area:	16,033.00 (SqFt) nents
L.C.D.: 12/25 Work Date 12/25/1999 1/1/1972	Work Code OL-AC NU-IN	Work Do Overlay - AC New Constructi	Rank: P L escription ion - Initial	Cost 0.00 0.00	.00 (Ft) Wickness (in) 0.00 0.00	Major M&R	O0 (Ft) True Area: Comn ESTIMATED INITIA	16,033.00 (SqFt) nents AL CONSTRUCTI
L.C.D.: 12/25  Work Date 12/25/1999 1/1/1972  Network:	Work Code OL-AC NU-IN	Work Do Overlay - AC New Constructi O BEACH	Rank: P L escription ion - Initial Branch: TW A	Cost 0.00 0.00 TAXIV	Thickness (in)  0.00  0.00  0.00  WAY A	Major M&R	Comn ESTIMATED INITIA	16,033.00 (SqFt) nents AL CONSTRUCTI Surface: AAC
L.C.D.: 12/25  Work Date  12/25/1999  1/1/1972  Network:  L.C.D.: 11/1/	Work Code OL-AC NU-IN POMPAN	Work Do Overlay - AC New Constructi O BEACH se: TAXIWAY	Rank: P L escription ion - Initial Branch: TW A	Cost 0.00 0.00 TAXIVength: 1,500	0.00 (Ft) Wideling 1.00 (Ft) (Ft) Wideling 1.00 (Ft) (Ft) Wideling 1.00 (Ft) (Ft) (Ft) (Ft) (Ft) (Ft) (Ft) (Ft)	Major M&R  Section:	Comn ESTIMATED INITIA  105 00 (Ft) True Area:	16,033.00 (SqFt) nents AL CONSTRUCTI Surface: AAC
L.C.D.: 12/25  Work Date  12/25/1999  1/1/1972  Network:  L.C.D.: 11/1/	Work Code OL-AC NU-IN	Work Do Overlay - AC New Constructi O BEACH se: TAXIWAY Work Do	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription	Cost 0.00 0.00 TAXIVength: 1,500	Thickness (in)  0.00  0.00  0.00  WAY A	Major M&R  Section: dth: 40.0  Major M&R	Comn ESTIMATED INITIA  105 00 (Ft) True Area:	16,033.00 (SqFt) nents AL CONSTRUCTI Surface: AAC 61,729.00 (SqFt)
L.C.D.: 12/25  Work Date  12/25/1999  1/1/1972  Network:  L.C.D.: 11/1/  Work Date  11/1/2012	Work Code OL-AC NU-IN  POMPAN 2012 Us  Work Code ML-OV	Work Do Overlay - AC New Constructi O BEACH se: TAXIWAY Work Do MILL and OVE	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription	Cost 0.00  TAXIVength: 1,500  Cost 0.00	0.00 (Ft) Wind Thickness (in) 0.00 0.00 0.00 WAY A 0.00 (Ft) Wind Thickness (in) 0.00	Major M&R  Section: dth: 40.0  Major M&R	Comn ESTIMATED INITIA  105 00 (Ft) True Area: Comn	16,033.00 (SqFt) nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt) nents
L.C.D.: 12/25  Work Date 12/25/1999 1/1/1972  Network: L.C.D.: 11/1/ Work Date	Work Code OL-AC NU-IN  POMPAN 2012 Us  Work Code	Work Do Overlay - AC New Constructi O BEACH se: TAXIWAY Work Do MILL and OVE	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription	Cost 0.00 0.00 TAXIV ength: 1,500 Cost	0.00 (Ft) With thickness (in) 0.00 0.00 0.00 WAY A 0.00 (Ft) With thickness (in)	Major M&R  Section: dth: 40.0  Major M&R	Comn ESTIMATED INITIA  105 00 (Ft) True Area:	16,033.00 (SqFt) nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt) nents
L.C.D.: 12/25  Work Date  12/25/1999  1/1/1972  Network:  L.C.D.: 11/1/  Work Date  11/1/2012	Work Code OL-AC NU-IN  POMPAN 2012 Us Work Code ML-OV IMPORT	Work Do Overlay - AC New Constructi O BEACH se: TAXIWAY Work Do MILL and OVE	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription	Cost 0.00  TAXIVength: 1,500  Cost 0.00	0.00 (Ft) Wind Thickness (in) 0.00 0.00 0.00 WAY A 0.00 (Ft) Wind Thickness (in) 0.00	Major M&R  Section: dth: 40.0  Major M&R	Comn ESTIMATED INITIA  105 00 (Ft) True Area: Comn	16,033.00 (SqFt) nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt) nents
L.C.D.: 12/25  Work Date  12/25/1999  1/1/1972  Network:  L.C.D.: 11/1/  Work Date  11/1/2012	Work Code OL-AC NU-IN  POMPAN 2012 Us Work Code ML-OV IMPORT ED	Work Do Overlay - AC New Constructi O BEACH se: TAXIWAY Work Do MILL and OVE BUILT	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription	Cost 0.00 0.00  TAXIVength: 1,500  Cost 0.00  0.00	0.00 (Ft) Wind Thickness (in) 0.00 0.00 0.00 WAY A 0.00 (Ft) Wind Thickness (in) 0.00	Major M&R  Section: dth: 40.0  Major M&R	Comm ESTIMATED INITIA  105 00 (Ft) True Area: Comm  1968 1.5" BIT 6" LIN	16,033.00 (SqFt) nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt) nents
L.C.D.: 12/25  Work Date  12/25/1999 1/1/1972  Network: L.C.D.: 11/1/  Work Date  11/1/2012 1/1/1968	Work Code OL-AC NU-IN POMPAN 2012 Us Work Code ML-OV IMPORT ED POMPAN 997 Us	Work Do Overlay - AC New Constructi O BEACH se: TAXIWAY Work Do MILL and OVE BUILT	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription  ERLAY  Branch: TW A	Cost 0.00 Cost 1,500 Cost 0.00 TAXIV	0.00 (Ft)   Wickness (in)	Major M&R  Section: dth: 40.0  Major M&R  V  Section: dth: 40.0  Section:	Comm ESTIMATED INITIA  105 00 (Ft) True Area: Comm  1968 1.5" BIT 6" LIN	16,033.00 (SqFt) nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt) nents  MEROCK
L.C.D.: 12/25  Work Date  12/25/1999  1/1/1972  Network:  L.C.D.: 11/1/  Work Date  11/1/2012  1/1/1968  Network:	Work Code OL-AC NU-IN POMPAN 2012 Us Work Code ML-OV IMPORT ED	Work Do Overlay - AC New Constructi O BEACH Se: TAXIWAY Work Do MILL and OVE BUILT O BEACH Se: TAXIWAY	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription  ERLAY  Branch: TW A	Cost	WAY A  0.00 (Ft) Wickness (in)  0.00  0.00  WAY A  0.00 (Ft) Wickness (in)  0.00  1.50	Major M&R  Section:  dth: 40.0  Major M&R  V  Section:	Comm ESTIMATED INITIA  105 00 (Ft) True Area: Comm  1968 1.5" BIT 6" LIN	16,033.00 (SqFt)  nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt)  nents  MEROCK  Surface: AAC 13,967.00 (SqFt)
L.C.D.: 12/25  Work Date  12/25/1999 1/1/1972  Network: L.C.D.: 11/1/  Work Date  11/1/2012 1/1/1968  Network: L.C.D.: 1/1/1	Work Code OL-AC NU-IN POMPAN 2012 Us Work Code ML-OV IMPORT ED POMPAN 997 Us Work Code IMPORT	Work Do Overlay - AC New Constructi O BEACH Se: TAXIWAY Work Do MILL and OVE BUILT O BEACH Se: TAXIWAY	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription  ERLAY  Branch: TW A Rank: P L	Cost  TAXIV ength: 1,500  Cost  0.00  TAXIV ength: 1,500  TAXIV ength: 350	0.00 (Ft)   Wickness (in)	Section:  Major M&R  Section:  Major M&R  V  Section:  Major M&R  V  Section:  40.0  Major	Comm ESTIMATED INITIA  105 00 (Ft) True Area: Comm  1968 1.5" BIT 6" LIN  115 00 (Ft) True Area:	16,033.00 (SqFt) nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt) nents  MEROCK  Surface: AAC 13,967.00 (SqFt) nents
L.C.D.: 12/25  Work Date  12/25/1999 1/1/1972  Network: L.C.D.: 11/1/  Work Date  11/1/2012 1/1/1968  Network: L.C.D.: 1/1/1  Work Date	Work Code OL-AC NU-IN POMPAN 2012 Us Work Code ML-OV IMPORT ED POMPAN 997 Us Work Code IMPORT ED	Work Do Overlay - AC New Constructi O BEACH Se: TAXIWAY Work Do MILL and OVE BUILT O BEACH Se: TAXIWAY	Rank: P L escription  ion - Initial  Branch: TW A Rank: P L escription  ERLAY  Branch: TW A Rank: P L	Cost	0.00 (Ft)   Wickness (in)	Section:  Major M&R  Section:  Major M&R  V  Section:  Major M&R  V  Section:  dth: 40.0	Comn ESTIMATED INITIA  105 00 (Ft) True Area: Comn  1968 1.5" BIT 6" LIN  115 00 (Ft) True Area: Comn	16,033.00 (SqFt) nents  AL CONSTRUCTI  Surface: AAC 61,729.00 (SqFt) nents  MEROCK  Surface: AAC 13,967.00 (SqFt) nents

Pavement Management System PAVER 7.0 TM

#### **Work History Report**

Page 5 of 10

Pavement Database: FDOT

	Pavement Database: FDOT								
NI	DOMBAN	O DE ACH Down by TW D	TAXII	VAV D	C4*	210	San A A C		
Network: L.C.D.: 1/1/1		O BEACH Branch: TW B		WAY B	Section:		Surface: AAC		
L.C.D.: 1/1/1	Work		ength: 2,000	Thickness	Major	00 (Ft) True Area:	118,013.00 (SqFt)		
Work Date	Code	Work Description	Cost	(in)	M&R	Comr	ments		
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<b>V</b>	1972 1.5" P-401 OL	ON EXISTING		
Network:	POMPAN	O BEACH <b>Branch:</b> TW C	TAXIV	WAY C	Section:	305	Surface: AC		
<b>L.C.D.:</b> 1/1/1		se: TAXIWAY Rank: P L	ength: 650	` '		00 (Ft) True Area:	26,289.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comr	ments		
1/1/1970	IMPORT	BUILT	0.00	0.00	<b>V</b>	EST 1970 BIT SECT	TION UNKNOWN		
	ED								
Network:	POMPAN	O BEACH Branch: TW C	TAXIV	WAY C	Section:	350	Surface: AAC		
<b>L.C.D.:</b> 11/1/	2012 Us	se: TAXIWAY Rank: P L	ength: 212	.50 (Ft) <b>Wi</b> o	dth: 40.	00 (Ft) True Area:	6,807.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comr	nents		
11/1/2012		MILL and OVERLAY	0.00	0.00	V	2" P-401 MILL ANI	O OVERLAY		
1/1/1970	IMPORT	BUILT	0.00	0.00	<b>~</b>	EST 1970 BIT SECT	TION UNKNOWN		
	ED								
Network:	POMPAN	O BEACH Branch: TW C	TAXIV	WAY C	Section:	360	Surface: AAC		
<b>L.C.D.:</b> 11/1/	2012 Us	se: TAXIWAY Rank: P L	ength: 132	.50 (Ft) <b>Wi</b> o	dth: 40.	00 (Ft) True Area:	9,668.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comr	ments		
11/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<b>V</b>	2" P-401 MILL ANI	OVERLAY		
1/1/1968	IMPORT ED	BUILT	0.00	1.50		1968 1.5" BIT 6" LII	MEROCK		
	ED								
Network:	POMPAN	O BEACH <b>Branch:</b> TW D	TAXIV	WAY D	Section:	405	Surface: AAC		
<b>L.C.D.:</b> 1/1/1	972 Us	se: TAXIWAY Rank: P L	ength: 2,100	.00 (Ft) <b>Wi</b> o	dth: 50.	00 (Ft) True Area:	105,607.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comr	nents		
1/1/1972	IMPORT	BUILT	0.00	` /		1972 1.5" P-401 OL	ON EXISTING		
	ED		1						
Network:	POMPAN	O BEACH <b>Branch:</b> TW D	TAXIV	WAY D	Section:	410	Surface: AAC		
<b>L.C.D.:</b> 1/1/2						00 (Ft) True Area:	13,072.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comr	nents		
1/1/2008		MILL and OVERLAY	0.00	0.00	<b>V</b>				
1/1/1972	IMPORT	BUILT	0.00	1.50	<b>V</b>	1972 1.5" P-401 OL	ON EXISTING		
	ED								
Network:	POMPAN	O BEACH Branch: TW D	TAXIV	WAY D	Section:	415	Surface: AAC		

Code (in) M&R 11/1/2012 ML-OV MILL and OVERLAY 2" P-401 MILL AND OVERLAY 0.00 0.00 **Y** IMPORT BUILT 0.00 1972 1.5" P-401 OL 0N EXISTING 1/1/1972 1.50 **V** ED

Cost

Thickness

Length:

400.00 (Ft) **Width:** 50.00 (Ft) **True Area:** 

Major

L.C.D.: 11/1/2012 Use: TAXIWAY Rank: P

**Work Description** 

Work

**Work Date** 

36,063.00 (SqFt)

Comments

**L.C.D.:** 6/1/2012

**Work Date** 

6/1/2012

Work

Code

NU-IN

Use: TAXIWAY Rank: P

New Construction - Initial

**Work Description** 

#### **Work History Report**

Page 6 of 10

Pavement Database: FDOT

	POMPAN.	O DE LOUI DE LE ENVE		W. W. D.	G 41	120	G . 6
Network:				WAY D	Section:		Surface: AAC
<b>L.C.D.:</b> 1/1/2	Work	se: TAXIWAY Rank: P	Length: 2,415	Thickness	Major	00 (Ft) True Area:	23,098.00 (SqFt)
Work Date	Code	Work Description	Cost	(in)	M&R	Comm	nents
1/1/2008	ML-OV	MILL and OVERLAY	0.00	0.00	<		
1/1/1972	NU-IN	New Construction - Initial	0.00	0.00	<b>V</b>		
Network:	POMPAN	O BEACH <b>Branch:</b> TW D	) TAXI	WAY D	Section:	425	Surface: AC
L.C.D.: 6/1/2			Length: 1,000			00 (Ft) True Area:	
Work Data	Work		Cost	Thickness	Major	Comr	
Work Date	Code	Work Description		(in)	M&R		
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00		2" P-401, 8" P-211 L	IMEROCK BASE,
Network:	POMPAN	O BEACH <b>Branch:</b> TW E	TAXI	WAY E	Section:	505	Surface: AAC
<b>L.C.D.:</b> 1/1/2	012 Us	se: TAXIWAY Rank: P	Length: 200	0.00 (Ft) <b>Wi</b> o	dth: 40.0	00 (Ft) True Area:	12,246.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comm	nents
1/1/2012	ML-OV	MILL and OVERLAY	0.00	( )	WICK		
1/1/1968	IMPORT	BUILT	0.00	1.50		1968 1.5" BIT 6" LII	MEROCK
	ED						
Notwork	POMPAN	O BEACH <b>Branch:</b> TW F	TAYI	WAY F	Section:	610	Surface: AAC
- 10011101111			Length: 2,500			00 (Ft) <b>True Area:</b>	
	Work			Thickness	Major		117,055.00 (541.7)
Work Date	G. 1.						4
4 14 14 0 = 0	Code	Work Description	Cost	(in)	M&R	Comm	
1/1/1972	IMPORT ED	•	0.00	` /	M&R	Comm	
1/1/1972	IMPORT	•		` /			
	IMPORT ED	•	0.00	` /		1972 1.5" P-401 OL	
	IMPORT ED	BUILT  O BEACH Branch: TW F	0.00	1.50 WAY F	Section:	1972 1.5" P-401 OL	ON EXISTING  Surface: AAC
Network:	IMPORT ED	BUILT  O BEACH Branch: TW F	0.00	1.50 WAY F	Section:	1972 1.5" P-401 OL	ON EXISTING  Surface: AAC 15,543.00 (SqFt)
Network: L.C.D.: 1/1/2	IMPORT ED  POMPANO  008 Us  Work  Code	BUILT  O BEACH Branch: TW F se: TAXIWAY Rank: P	0.00  TAXI  Length: 2,500	WAY F 0.00 (Ft) Wid Thickness (in)	Section: dth: 50.0 Major	1972 1.5" P-401 OL 612 00 (Ft) <b>True Area:</b>	ON EXISTING  Surface: AAC 15,543.00 (SqFt)
Network: L.C.D.: 1/1/2 Work Date	IMPORT ED  POMPANO  008 Us  Work  Code	BUILT O BEACH Branch: TW F se: TAXIWAY Rank: P Work Description	TAXII Length: 2,500	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00	Section: 60.0 Major M&R	1972 1.5" P-401 OL 612 00 (Ft) <b>True Area:</b>	ON EXISTING  Surface: AAC  15,543.00 (SqFt)  ments
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972	IMPORT ED  POMPANO 008 Us  Work Code  ML-OV  NU-IN	BUILT  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial	TAXI  Length: 2,500  Cost  0.00 0.00	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 0.00	Section: dth: 50.0 Major M&R	1972 1.5" P-401 OL 612 00 (Ft) True Area: Comm	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  nents  ON EXISTING
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972 Network:	POMPANO Work Code ML-OV NU-IN	BUILT  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial  O BEACH Branch: TW F	0.00  TAXI  Length: 2,500  Cost  0.00  0.00  TAXI	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 0.00 WAY F	Section: dth: 50.0 Major M&R  V Section:	1972 1.5" P-401 OL 612 00 (Ft) True Area: Comm 1972 1.5" P-401 OL	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  ments  ON EXISTING  Surface: AAC
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972	POMPANO 008 Us  Work Code ML-OV NU-IN  POMPANO 012 Us	BUILT  O BEACH Branch: TW F  Se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial  O BEACH Branch: TW F  Se: TAXIWAY Rank: P	0.00  TAXI  Length: 2,500  Cost  0.00  0.00  TAXI	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 0.00 WAY F 0.00 (Ft) Wid	Section: dth: 50.0 Major M&R  Section: dth: 50.0	1972 1.5" P-401 OL 612 00 (Ft) True Area: Comm	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  ments  ON EXISTING  Surface: AAC
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972 Network:	POMPANO 008 Us  Work Code ML-OV NU-IN  POMPANO 012 Us  Work Code	BUILT  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description	TAXI' Length: 2,500  Cost  0.00 0.00  TAXI' Length: 264  Cost	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 0.00 WAY F	Section: dth: 50.0 Major M&R  V Section:	1972 1.5" P-401 OL 612 00 (Ft) True Area: Comm 1972 1.5" P-401 OL	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  ments  ON EXISTING  Surface: AAC 18,178.00 (SqFt)
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972  Network: L.C.D.: 1/1/2 Work Date 1/1/2012	POMPANO 008 Us  Work Code ML-OV NU-IN  POMPANO 012 Us  Work Code ML-OV	BUILT  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY	TAXI  Length: 2,500  Cost  0.00 0.00  TAXI  Length: 264  Cost  0.00	1.50  WAY F  0.00 (Ft) Wic  Thickness (in)  0.00  0.00  WAY F  0.00 (Ft) Wic  Thickness (in)  0.00	Section: dth: 50.0 Major M&R  Section: dth: 50.0 Major M&R	1972 1.5" P-401 OL 612 00 (Ft) True Area: Comm 1972 1.5" P-401 OL 615 00 (Ft) True Area: Comm	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  ments  ON EXISTING  Surface: AAC 18,178.00 (SqFt)
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972 Network: L.C.D.: 1/1/2 Work Date	POMPANO 008 Us  Work Code ML-OV NU-IN  POMPANO 012 Us  Work Code ML-OV	BUILT  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial  O BEACH Branch: TW F  se: TAXIWAY Rank: P  Work Description	TAXI' Length: 2,500  Cost  0.00 0.00  TAXI' Length: 264  Cost	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 0.00 WAY F 0.00 (Ft) Wid Thickness (in) 0.00	Section: dth: 50.0 Major M&R  Section: dth: 50.0 Major M&R	1972 1.5" P-401 OL 612 00 (Ft) True Area: Comm 1972 1.5" P-401 OL 615 00 (Ft) True Area:	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  ments  ON EXISTING  Surface: AAC 18,178.00 (SqFt)
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972  Network: L.C.D.: 1/1/2 Work Date 1/1/2012	POMPANO 008 Us  Work Code  ML-OV NU-IN  POMPANO 012 Us  Work Code  ML-OV IMPORT ED IMPORT	BUILT  O BEACH Branch: TW F  Se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial  O BEACH Branch: TW F  Se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  OVERLAY	TAXI  Length: 2,500  Cost  0.00 0.00  TAXI  Length: 264  Cost  0.00	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 0.00 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 1.50	Section: dth: 50.0 Major M&R  Section: dth: 50.0 Major M&R	1972 1.5" P-401 OL 612 00 (Ft) True Area: Comm 1972 1.5" P-401 OL 615 00 (Ft) True Area: Comm	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  ments  ON EXISTING  Surface: AAC 18,178.00 (SqFt)  ments
Network: L.C.D.: 1/1/2 Work Date 1/1/2008 1/1/1972  Network: L.C.D.: 1/1/2 Work Date 1/1/2012 1/1/1972	POMPANO 008 Us Work Code ML-OV NU-IN  POMPANO 012 Us Work Code ML-OV IMPORT ED	BUILT  O BEACH Branch: TW F  Se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  New Construction - Initial  O BEACH Branch: TW F  Se: TAXIWAY Rank: P  Work Description  MILL and OVERLAY  OVERLAY	TAXI  Length: 2,500  Cost  0.00 0.00  TAXI  Length: 264  Cost  0.00 0.00	1.50 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 0.00 WAY F 0.00 (Ft) Wid Thickness (in) 0.00 1.50	Section: dth: 50.0 Major M&R  Section: dth: 50.0 Major M&R	1972 1.5" P-401 OL  612  Comm  1972 1.5" P-401 OL  615  O0 (Ft) True Area:  Comm  1972 1.5" P-401 OL	ON EXISTING  Surface: AAC 15,543.00 (SqFt)  ments  ON EXISTING  Surface: AAC 18,178.00 (SqFt)  ments

Pavement Management System PAVER 7.0 TM

0.00

Thickness

(in)

0.00

Length:

Cost

 $260.00 \ (Ft) \qquad \textbf{Width:} \qquad 55.00 \ (Ft) \quad \textbf{True Area:}$ 

Major

M&R

~

15,387.00 (SqFt)

Comments

2" P-401, 8" P-211 LIMEROCK BASE,

## **Work History Report**

Page 7 of 10

Pavement Database: FDOT

Network:	POMPAN	O BEACH Branch: TW G	TAXIV	WAY G	Section:	715	Surface: AC		
<b>L.C.D.:</b> 6/1/2	014 Us	se: TAXIWAY Rank: P	ength: 350	.00 (Ft) <b>Wi</b> o	dth: 50.0	00 (Ft) True Area:	17,469.00 (SqFt)		
W I D /	Work			Thickness	Major	- C			
Work Date	Code	Work Description	Cost	(in)	M&R	Comr	nents		
6/1/2014	NC-AC	New Construction - AC	0.00	0.00	<b>V</b>				
		O BEACH <b>Branch:</b> TW K		WAY K	Section:		Surface: AC		
<b>L.C.D.:</b> 11/1/		se: TAXIWAY Rank: P L	ength: 2,500	` ′		00 (Ft) True Area:	89,261.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comm	nents		
11/1/2012		New Construction - Initial	0.00	0.00	V				
Network:	Network: POMPANO BEACH Branch: TW K TAXIWAY K Section: 1115 Surface: AC								
<b>L.C.D.:</b> 6/1/2						00 (Ft) True Area:			
	Work			Thickness	Major				
Work Date	Code	Work Description	Cost	(in)	M&R	Comm	nents		
6/1/2014	NC-AC	New Construction - AC	0.00	0.00	<b>&gt;</b>				
Network:	POMPAN	O BEACH Branch: TW K	TAXIV	WAY K	Section:	1120	Surface: AC		
<b>L.C.D.:</b> 6/1/2	012 Us	se: TAXIWAY Rank: P L	ength: 280	.00 (Ft) <b>Wi</b> o	dth: 50.0	00 (Ft) <b>True Area:</b>	14,097.00 (SqFt)		
Work Date	Work	Work Description	Cost	Thickness	Major	Comr	nents		
6/1/2012	Code NC-AC	New Construction - AC	0.00	(in) 0.00	M&R ✓				
0/1/2012	NC-AC	New Construction - AC	0.00	0.00	<b>V</b> .				
Notwork:	POMPAN	O BEACH Branch: TW L	TAXIV	WAY L	Section:	1202	Surface: AAC		
L.C.D.: 1/1/1						00 (Ft) True Area:			
L.C.D.: 1/1/1	Work	E. TAATWAT Kalik. T	length. 290	Thickness	Major	(1t) True Area.	21,209.00 (Sql·t)		
Work Date	Code	Work Description	Cost	(in)	M&R	Comm	nents		
1/1/1996	ML-OV	MILL and OVERLAY	0.00	0.00	<b>V</b>	Estimated Constructi	on Date		
1/1/1950	IMPORT	BUILT	0.00	0.00		EST 1950 BIT SECT	TION UNKNOWN		
	ED		•						
No4	DOMDA NA	O DEACH Broads TWI	T 4 3/13	MAN I	Coatta	1205	Surface: AC		
		O BEACH Branch: TW L		WAY L	Section:				
<b>L.C.D.:</b> 1/1/1		se: TAXIWAY Rank: P L	ength: 260	` '		00 (Ft) True Area:	13,025.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comm	nents		
1/1/1972	NC-AC	New Construction - AC	0.00	0.00	<b>V</b>				
	ı		1						
Network:	POMPAN	O BEACH Branch: TW L	TAXIV	WAY L	Section:	1210	Surface: AAC		
<b>L.C.D.:</b> 1/1/1	996 Us	se: TAXIWAY Rank: P L	ength: 2,550	.00 (Ft) <b>Wi</b> o	dth: 60.0	00 (Ft) True Area:	152,867.00 (SqFt)		
Word Det	Work	Words Demoissing		Thickness	Major				
Work Date	Code	Work Description	Cost	(in)	M&R	Com			
1/1/1996		MILL and OVERLAY	0.00	0.00	<u> </u>	Estimated Constructi			
1/1/1950	IMPORT ED	BUILT	0.00	0.00	<b>V</b>	EST 1950 BIT SECT	TON UNKNOWN		
	10								

#### **Work History Report**

Page 8 of 10

Pavement Database: FDOT

Network:								
	POMPAN	O BEACH Branch: TW L	TAXI	WAY L	Section:	1215	Surface: AAC	
<b>L.C.D.:</b> 6/1/20	012 Us	se: TAXIWAY Rank: P	Length: 250	.00 (Ft) Wie	dth: 60.0	00 (Ft) True Area:	14,829.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comr	nents	
6/1/2012	ML-OV	MILL and OVERLAY	0.00	0.00	<b>✓</b>			
1/1/1950	NU-IN	New Construction - Initial	0.00	0.00				
Network:	POMPAN	O BEACH Branch: TW M	TAXI	WAY M	Section:	1305	Surface: AC	
<b>L.C.D.:</b> 1/1/19	970 Us	e: TAXIWAY Rank: P I	Length: 884	.00 (Ft) <b>Wi</b>	dth: 50.0	00 (Ft) True Area:	27,738.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comm	nents	
1/1/1970	IMPORT	BUILT	0.00	0.00	<b>&gt;</b>	1970 AC PAVEMEN	TV	
	ED		•					
Network:	POMPAN	O BEACH <b>Branch:</b> TW M	TAXI	WAY M	Section:	1306	Surface: AC	
L.C.D.: 11/1/2	2012 Us	se: TAXIWAY Rank: P I	Length: 300	.00 (Ft) <b>Wi</b> o	dth: 50.0	00 (Ft) True Area:	29,856.00 (SqFt)	
	Work			Thickness	Major		-	
Work Date	Code	Work Description	Cost	(in)	M&R	Comr	nents	
11/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<b>&gt;</b>			
		•			•			
Network:	POMPAN	O BEACH Branch: TW M	TAXI	WAY M	Section:	1310	Surface: AC	
<b>L.C.D.:</b> 1/1/19	999 Us	se: TAXIWAY Rank: P	Length: 900	.00 (Ft) <b>Wi</b>	dth: 50.0	00 (Ft) True Area:	24,002.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comr	ments	
1/1/1999	IMPORT	DIHLT	0.00	` ′				
	ED	BUILI	0.00	0.00		1999 AC PAVEMEN	NT	
			0.00	0.00		1999 AC PAVEMEN	NT	
Network:		O BEACH Branch: TW M		0.00 WAY M	Section:		Surface: AC	
Network: L.C.D.: 1/1/19	POMPAN	O BEACH Branch: TW M	TAXIV	WAY M	Section:		Surface: AC	
	POMPAN	O BEACH Branch: TW M	TAXIV	WAY M	Section:	1315	<b>Surface:</b> AC 16,359.00 (SqFt)	
<b>L.C.D.:</b> 1/1/19	POMPANO 999 Us Work Code IMPORT	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description	TAXIV	WAY M .00 (Ft) Wid	Section: dth: 110.0 Major M&R	1315 00 (Ft) <b>True Area:</b>	Surface: AC 16,359.00 (SqFt) nents	
L.C.D.: 1/1/19 Work Date	POMPANO 999 Us Work Code	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description	TAXIV	WAY M .00 (Ft) Wid Thickness (in)	Section: dth: 110.0 Major M&R	1315 00 (Ft) True Area:	Surface: AC 16,359.00 (SqFt) nents	
L.C.D.: 1/1/19 Work Date 1/1/1999	POMPANO 999 Us Work Code IMPORT ED	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT	TAXIV Length: 125 Cost	WAY M .00 (Ft) Wid Thickness (in) 0.00	Section: dth: 110.0 Major M&R	1315 00 (Ft) True Area: Comm	Surface: AC 16,359.00 (SqFt) nents	
L.C.D.: 1/1/19  Work Date  1/1/1999  Network:	POMPANO 999 Us Work Code IMPORT ED	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT O BEACH Branch: TW M	TAXIV	WAY M .00 (Ft) Wid Thickness (in) 0.00	Section: dth: 110.0 Major M&R	1315 00 (Ft) True Area: Comm 1999 AC PAVEMEN	Surface: AC 16,359.00 (SqFt) ments NT Surface: AC	
L.C.D.: 1/1/19 Work Date 1/1/1999	POMPANO 999 Us Work Code IMPORT ED POMPANO 970 Us	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT O BEACH Branch: TW M	TAXIV	WAY M .00 (Ft) Wic Thickness (in) 0.00 WAY M .00 (Ft) Wic	Section: dth: 110.0 Major M&R  Section: dth: 50.0	1315 00 (Ft) True Area: Comm	Surface: AC 16,359.00 (SqFt) ments NT Surface: AC	
L.C.D.: 1/1/19  Work Date  1/1/1999  Network:	POMPANO 999 Us Work Code IMPORT ED	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT O BEACH Branch: TW M	TAXIV	WAY M .00 (Ft) Wid Thickness (in) 0.00	Section: dth: 110.0 Major M&R	1315 00 (Ft) True Area: Comm 1999 AC PAVEMEN	Surface: AC 16,359.00 (SqFt)  nents  NT  Surface: AC 95,815.00 (SqFt)	
L.C.D.: 1/1/19  Work Date  1/1/1999  Network: L.C.D.: 1/1/19	POMPANO 999 Us Work Code IMPORT ED  POMPANO 970 Us Work Code IMPORT	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description	TAXIV Length: 125  Cost  0.00  TAXIV Length: 450	WAY M .00 (Ft) Wit Thickness (in) 0.00 WAY M .00 (Ft) Wit Thickness	Section: dth: 110.0 Major M&R  Section: dth: 50.0 Major M&R	1315 00 (Ft) True Area: Comm 1999 AC PAVEMEN  1320 00 (Ft) True Area:	Surface: AC 16,359.00 (SqFt) ments NT Surface: AC 95,815.00 (SqFt) ments	
L.C.D.: 1/1/19   Work Date   1/1/1999     Network:   L.C.D.: 1/1/19   Work Date	POMPANO 999 Us Work Code IMPORT ED  POMPANO 970 Us Work Code	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description	TAXIV Length: 125  Cost  0.00  TAXIV Length: 450  Cost	WAY M .00 (Ft) Wid Thickness (in) 0.00 WAY M .00 (Ft) Wid Thickness (in)	Section: dth: 110.0 Major M&R  Section: dth: 50.0 Major M&R	1315 00 (Ft) True Area:  Comm 1999 AC PAVEMEN  1320 00 (Ft) True Area:  Comm	Surface: AC 16,359.00 (SqFt) ments NT Surface: AC 95,815.00 (SqFt) ments	
Network: L.C.D.: 1/1/19  Network: L.C.D.: 1/1/19  Work Date  1/1/1970	POMPANO 999 Us Work Code IMPORT ED  POMPANO 970 Us Work Code IMPORT ED	O BEACH Branch: TW M  Se: TAXIWAY Rank: P I  Work Description  BUILT  O BEACH Branch: TW M  Se: TAXIWAY Rank: P I  Work Description  BUILT	TAXIV Length: 125  Cost  0.00  TAXIV Length: 450  Cost  0.00	WAY M .00 (Ft) Wide Thickness (in) 0.00  WAY M .00 (Ft) Wide Thickness (in) 0.00	Section: dth: 110.0 Major M&R  Section: dth: 50.0 Major M&R  W	1315 00 (Ft) True Area: Comm 1999 AC PAVEMEN  1320 00 (Ft) True Area: Comm EST 1970 BIT SECT	Surface: AC 16,359.00 (SqFt) ments NT Surface: AC 95,815.00 (SqFt) ments TION UNKNOWN	
L.C.D.: 1/1/19   Work Date   1/1/1999     Network:   L.C.D.: 1/1/19   Work Date	POMPANO 999 Us Work Code IMPORT ED  POMPANO 970 Us Work Code IMPORT ED	O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT O BEACH Branch: TW M se: TAXIWAY Rank: P I Work Description BUILT O BEACH Branch: TW M	TAXIV  Cost  Cost  TAXIV  Cost  Cost  Cost  Cost  TAXIV  TAXIV	WAY M .00 (Ft) With thickness (in) 0.00  WAY M .00 (Ft) With thickness (in) 0.00  WAY M	Section: dth: 110.0 Major M&R  Section: dth: 50.0 Major M&R  Section:	1315 00 (Ft) True Area: Comm 1999 AC PAVEMEN  1320 00 (Ft) True Area: Comm EST 1970 BIT SECT	Surface: AC 16,359.00 (SqFt) ments NT Surface: AC 95,815.00 (SqFt) ments	

PAVER 7.0 TM Pavement Management System

Thickness

(in)

0.00

0.00

Major

M&R

~

~

Comments

Cost

0.00

0.00

**Work Description** 

MILL and OVERLAY

New Construction - Initial

Work

Code

ML-OV

NU-IN

**Work Date** 

1/1/2012

1/1/1970

7/26/2017	Work History Report	Page 9 of 10
	Pavement Database: FDOT	

Network:	POMPAN	O BEACH Branch: TW N	WAY N	Section:	1405	Surface: AC	
L.C.D.: 1/1/2004 Use: TAXIWAY Rank: P Length: 560.00 (Ft) Width: 50.00 (Ft) True Area: 28,235.00 (SqF							28,235.00 (SqFt)
Work Date	Work Date Code Work Description Cost Thickness Major (in) M&R Code				Comm	nents	
1/1/2004	NU-IN	New Construction - Initial	0.00	0.00	<b>V</b>	ESTIMATED CONS	STRUCTION
Network: L.C.D.: 6/1/20				WAY R .00 (Ft) <b>Wi</b>	Section:	1805 00 (Ft) <b>True Area:</b>	<b>Surface:</b> AC 21,726.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comm	, , ,
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<b>V</b>	2" P-401, 8" P-211 L	IMEROCK BASE.

## **Work History Report**

Page 10 of 10

Pavement Database: FDOT

#### **Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	28	2,701,445.00	0.86	0.74
MILL and OVERLAY	21	1,281,388.00	0.00	0.00
New Construction - AC	5	180,717.00	0.00	0.00
New Construction - Initial	24	1,009,599.00	0.00	0.00
New Construction - PCC	1	3,846.00	0.00	0.00
OVERLAY	4	270,906.00	0.75	0.75
Overlay - AC	1	16,033.00	0.00	0.00

## **Branch Condition Report**

Page 1 of 2

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP N	1	950.00	100.00	62,989.00	APRON	61.00	0.00	61.00
AP RU RW3	2	300.00	100.00	34,800.00	APRON	75.50	16.50	72.57
AP S	7	5,860.00	120.00	682,694.00	APRON	77.43	21.10	76.52
AP SW	1	1,000.00	50.00	61,737.00	APRON	81.00	0.00	81.00
RW 10-28	2	1,160.00	100.00	329,520.00	RUNWAY	76.50	10.50	69.72
RW 15-33	4	13,620.00	56.25	737,700.00	RUNWAY	90.50	3.77	92.40
RW 6-24	4	10,075.00	62.50	556,428.00	RUNWAY	78.75	15.25	66.53
TL AP SW	1	550.00	50.00	28,724.00	TAXILANE	88.00	0.00	88.00
TL HANG	4	6,025.00	28.75	180,871.00	TAXILANE	38.75	6.38	40.62
TW A	2	1,850.00	40.00	75,696.00	TAXIWAY	73.00	20.00	85.62
TW B	1	2,600.00	50.00	118,013.00	TAXIWAY	64.00	0.00	64.00
TW C	3	995.00	43.33	42,764.00	TAXIWAY	84.33	13.67	76.17
TW D	5	6,190.00	47.00	214,417.00	TAXIWAY	76.20	11.50	73.19
TW E	1	200.00	40.00	12,246.00	TAXIWAY	89.00	0.00	89.00
TW F	3	5,264.00	50.00	151,614.00	TAXIWAY	78.67	10.66	68.95
TW G	2	610.00	52.50	32,856.00	TAXIWAY	95.00	1.00	94.94
TW K	3	2,930.00	45.00	110,731.00	TAXIWAY	92.67	0.94	93.61
TW L	4	3,350.00	61.25	201,930.00	TAXIWAY	68.75	12.01	66.25
TW M	6	3,109.00	60.00	209,916.00	TAXIWAY	76.83	9.51	72.47
TW N	1	560.00	50.00	28,235.00	TAXIWAY	82.00	0.00	82.00
TW R	1	600.00	35.00	21,726.00	TAXIWAY	92.00	0.00	92.00

7/26/2017	Branch Condition Report	Page 2 of 2
	Pavement Database: FDOT	

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	11	842220.000208684	75.91	18.89	75.53
RUNWAY	10	1623648.00017793	83.00	12.61	78.93
TAXILANE	5	209595.000023877	48.60	20.51	47.11
TAXIWAY	32	1220144.00019149	79.59	13.34	74.51
ALL	58	3895607.00060197	76.81	17.58	75.10

Pavement Database: FDOT

NetworkId: PMP

Pavement Dat	Pavement Database: FDOT					vorkId.	: PMP			
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspec tion	
AP N	4205	1/1/1972	AAC	APRON	Р	0	62,989.00	5/8/2017	45	61
AP RU RW33	5105	6/1/2012	AAC	APRON	Р	0	14,310.00	5/8/2017	5	92
AP RU RW33	5110	1/1/1996	AAC	APRON	Р	0	20,490.00	5/8/2017	21	59
AP S	4105	1/1/1997	AAC	APRON	Р	0	203,761.00	5/8/2017	20	63
AP S	4107	1/1/2015	PCC	APRON	Р	0	3,846.00	5/8/2017	2	
AP S	4110	1/1/1960	AC	APRON	Р	0	26,025.00	5/8/2017	57	51
AP S	4112	5/17/2013	AC	APRON	Р	0	131,008.00	5/8/2017	4	92
AP S	4125	12/25/1999	AC	APRON	Р	0	117,688.00	5/8/2017	18	48
AP S	4130	1/1/2015	AAC	APRON	Р	0	71,613.00	1/1/2015		
AP S	4135	1/1/2015	AC	APRON	Р	0	128,753.00	1/1/2015	0	100
AP SW	4410	1/1/2012	PCC	APRON	Р	0	61,737.00	5/8/2017	5	81
RW 10-28	6105	1/1/1968	AC	RUNWAY	Р	0	271,200.00	5/8/2017	49	66
RW 10-28	6115	1/1/2012	AAC	RUNWAY	Р	0	58,320.00	5/8/2017	5	87
RW 15-33	6305	1/1/2012	AAC	RUNWAY	Р	0	220,900.00	5/8/2017	5	92
RW 15-33	6310	1/1/2012	AAC	RUNWAY	P	0	441,800.00		5	
RW 15-33	6325	6/1/2012	AC	RUNWAY	Р	0	25,000.00		5	84
RW 15-33	6330	6/1/2012	AC	RUNWAY	Р	0	50,000.00	5/8/2017	5	93
RW 6-24	6205	1/1/1972	AAC	RUNWAY	Р	0	335,952.00	5/8/2017	45	64
RW 6-24	6210	1/1/1972	AAC	RUNWAY	Р	0	167,976.00		45	
RW 6-24	6220	1/1/2012	AAC	RUNWAY	Р	0	35,000.00	5/8/2017	5	94
RW 6-24	6225	1/1/2012	AAC	RUNWAY	Р	0	17,500.00	5/8/2017	5	94
TL AP SW	4505	1/1/2004	AC	TAXILANE	Р	0	28,724.00	5/8/2017	13	88
TL HANG	4305	12/25/1999	AC	TAXILANE	Р	0	31,764.00	5/8/2017	18	39
TL HANG	4310	12/25/1999	AC	TAXILANE	Р	0	49,387.00	5/8/2017	18	
TL HANG	4315	12/25/1999	AC	TAXILANE	Р	0	83,687.00	5/8/2017	18	48
TL HANG	4320	12/25/1999	APC	TAXILANE	Р	0	16,033.00	5/8/2017	18	38
TW A	105	11/1/2012	AAC	TAXIWAY	Р	0	61,729.00	5/8/2017	5	93
TW A	115	1/1/1997	AAC	TAXIWAY	Р	0	13,967.00	5/8/2017	20	53
TW B	210	1/1/1972	AAC	TAXIWAY	Т	0	118,013.00	5/8/2017	45	64
TW C	305	1/1/1970	AC	TAXIWAY	Р	0	26,289.00	5/8/2017	47	65
TW C	350	11/1/2012	AAC	TAXIWAY	Р	0	6,807.00		5	94
TW C	360	11/1/2012	AAC	TAXIWAY	Р	0	9,668.00	5/8/2017	5	94
TW D	405	1/1/1972	AAC	TAXIWAY	Р	0	105,607.00	5/8/2017	45	63
TW D	410	1/1/2008		TAXIWAY	Р	0	13,072.00		9	
TW D	415	11/1/2012	AAC	TAXIWAY	Р	0	36,063.00	5/8/2017	5	84
TW D	420	1/1/2008	AAC	TAXIWAY	Р	0	23,098.00	5/8/2017	9	74
TW D	425	6/1/2012	AC	TAXIWAY	Р	0	36,577.00	5/8/2017	5	94
TW E	505	1/1/2012	AAC	TAXIWAY	Р	0	12,246.00	5/8/2017	5	89
TW F	610	1/1/1972	AAC	TAXIWAY	Р	0	117,893.00	5/8/2017	45	64
TW F	612	1/1/2008	AAC	TAXIWAY	Р	0	15,543.00	5/8/2017	9	
TW F	615	1/1/2012	AAC	TAXIWAY	Р	0	18,178.00	5/8/2017	5	89
TW G	710	6/1/2012	AC	TAXIWAY	Р	0	15,387.00	5/8/2017	5	96
TW G	715	6/1/2014		TAXIWAY	Р	0	17,469.00		3	
TW K	1110	11/1/2012	AC	TAXIWAY	Р	0	89,261.00		5	94
TW K	1115	6/1/2014		TAXIWAY	P	0	7,373.00		3	
TW K	1120	6/1/2012		TAXIWAY	Р	0	14,097.00		5	
TW L	1202	1/1/1996	-	TAXIWAY	Р	0	21,209.00		-	
ı					•				•	

7/26/2017		Section		Page 2 of 3						
TW L	1205	1/1/1972	AC	TAXIWAY	P	0	13,025.00	5/8/2017	45	55
TW L	1210	1/1/1996	AAC	TAXIWAY	Р	0	152,867.00	5/8/2017	21	65
TW L	1215	6/1/2012	AAC	TAXIWAY	Р	0	14,829.00	5/8/2017	5	88
TW M	1305	1/1/1970	AC	TAXIWAY	Р	0	27,738.00	5/8/2017	47	69
TW M	1306	11/1/2012	AC	TAXIWAY	Р	0	29,856.00	5/8/2017	5	82
TW M	1310	1/1/1999	AC	TAXIWAY	Р	0	24,002.00	5/8/2017	18	83
TW M	1315	1/1/1999	AC	TAXIWAY	Р	0	16,359.00	5/8/2017	18	70
TW M	1320	1/1/1970	AC	TAXIWAY	Р	0	95,815.00	5/8/2017	47	65
TW M	1325	1/1/2012	AAC	TAXIWAY	Р	0	16,146.00	5/8/2017	5	92
TW N	1405	1/1/2004	AC	TAXIWAY	Р	0	28,235.00	5/8/2017	13	82
TW R	1805	6/1/2012	AC	TAXIWAY	Р	0	21,726.00	5/8/2017	5	92


7/26/2017	Section Condition Report (Summary)	Page 3 of 3
	Pavement Database: FDOT	

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02	1	204,212.00	3	96.00	5.66	99.77
03-05	5	1,462,987.00	26	90.81	4.01	91.41
06-10	9	51,713.00	3	74.33	6.94	74.68
11-15	13	56,959.00	2	85.00	3.00	85.03
16-20	18	556,648.00	9	52.44	15.94	53.37
21-25	21	194,566.00	3	63.67	3.40	64.59
41-50	46	1,342,497.00	11	63.55	3.31	64.17
ALL	17	3,895,607.00	58	76.81	17.58	75.10
Over 50	57	26,025.00	1	51.00	0.00	51.00



# Appendix B

Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation



2017





#### Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
PMP	AP N	4205	48	L&TCR	Medium	232.78	Ft	0.4%	FDOT - CRACK SEALING - AC	232.61	Ft	\$ 3.00	\$ 700.00
PMP	AP N	4205	52	RAVELING	Low	6291.61	SqFt	10.0%	FDOT - SURFACE SEAL	6291.51	SqFt	\$ 0.55	\$ 3,470.00
PMP	AP RU RW33	5110	52	RAVELING	Low	6148.02	SqFt	30.0%	FDOT - SURFACE SEAL	6148.35	SqFt	\$ 0.55	\$ 3,390.00
PMP	AP S	4105	48	L&TCR	Medium	255.77	Ft	0.1%	FDOT - CRACK SEALING - AC	255.91	Ft	\$ 3.00	\$ 770.00
PMP	AP S	4105	52	RAVELING	Low	183299.6	SqFt	90.0%	FDOT - SURFACE SEAL	183299.7	SqFt	\$ 0.55	\$ 100,820.00
PMP	AP S	4107	65	JT SEAL DMG	High	12	Slabs	100.0%	FDOT - JOINT SEAL - PCC	288.06	Ft	\$ 2.75	\$ 800.00
PMP	AP S	4110	48	L&TCR	High	179.2	Ft	0.7%	FDOT - CRACK SEALING - AC	179.13	Ft	\$ 3.00	\$ 540.00
PMP	AP S	4110	52	RAVELING	Low	26024.98	SqFt	100.0%	FDOT - SURFACE SEAL	26024.98	SqFt	\$ 0.55	\$ 14,320.00
PMP	AP S	4112	45	DEPRESSION	Low	305.7	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	379.97	SqFt	\$ 6.00	\$ 2,290.00
PMP	AP S	4125	45	DEPRESSION	Low	384.49	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	467.15	SqFt	\$ 6.00	\$ 2,810.00
PMP	AP S	4125	49	OIL SPILLAGE	N/A	141.22	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	192.67	SqFt	\$ 3.00	\$ 580.00
PMP	AP S	4125	52	RAVELING	Low	104091.1	SqFt	88.5%	FDOT - SURFACE SEAL	104091.3	SqFt	\$ 0.55	\$ 57,260.00
PMP	AP S	4125	52	RAVELING	Medium	7845.81	SqFt	6.7%	FDOT - PATCHING - AC PARTIAL DEPTH	7845.81	SqFt	\$ 3.00	\$ 23,540.00
PMP	AP S	4125	52	RAVELING	High	164.8	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	164.69	SqFt	\$ 3.00	\$ 500.00
PMP	AP SW	4410	62	CORNER BREAK	Low	36.56	Slabs	11.1%	FDOT - CRACK SEALING - PCC	299.87	Ft	\$ 4.25	\$ 1,280.00
PMP	AP SW	4410	65	JT SEAL DMG	High	329	Slabs	100.0%	FDOT - JOINT SEAL - PCC	6283.46	Ft	\$ 2.75	\$ 17,280.00
PMP	AP SW	4410	74	JOINT SPALL	Low	12.19	Slabs	3.7%	FDOT - CRACK SEALING - PCC	20.01	Ft	\$ 4.25	\$ 90.00
PMP	RW 10-28	6105	52	RAVELING	Low	254119.35	SqFt	93.7%	FDOT - SURFACE SEAL	254119.8	SqFt	\$ 0.55	\$ 139,770.00
PMP	RW 10-28	6105	52	RAVELING	Medium	493.09	SqFt	0.2%	FDOT - PATCHING - AC PARTIAL DEPTH	492.99	SqFt	\$ 3.00	\$ 1,480.00
PMP	RW 15-33	6305	52	RAVELING	Low	1104.48	SqFt	0.5%	FDOT - SURFACE SEAL	1104.38	SqFt	\$ 0.55	\$ 610.00
PMP	RW 15-33	6310	52	RAVELING	Medium	4.95	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	5.38	SqFt	\$ 3.00	\$ 20.00
PMP	RW 6-24	6205	45	DEPRESSION	Low	43.81	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	74.27	SqFt	\$ 6.00	\$ 450.00
PMP	RW 6-24	6205	48	L&TCR	Medium	437.99	Ft	0.1%	FDOT - CRACK SEALING - AC	437.99	Ft	\$ 3.00	\$ 1,320.00
PMP	RW 6-24	6205	52	RAVELING	Low	27060.15	SqFt	8.1%	FDOT - SURFACE SEAL	27060.47	SqFt	\$ 0.55	\$ 14,890.00
PMP	RW 6-24	6210	48	L&TCR	Medium	251.84	Ft	0.2%	FDOT - CRACK SEALING - AC	251.97	Ft	\$ 3.00	\$ 760.00
PMP	RW 6-24	6210	52	RAVELING	Low	4125.16	SqFt	2.5%	FDOT - SURFACE SEAL	4124.73	SqFt	\$ 0.55	\$ 2,270.00
PMP	TL HANG	4305	45	DEPRESSION	Low	78.68	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	118.4	SqFt	\$ 6.00	\$ 720.00
PMP	TL HANG	4305	50	PATCHING	Medium	104.95	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	149.62	SqFt	\$ 6.00	\$ 910.00
PMP	TL HANG	4305	50	PATCHING	High	45.85	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	77.5	SqFt	\$ 6.00	\$ 470.00
PMP	TL HANG	4305	52	RAVELING	Low	26283.1	SqFt	82.8%	FDOT - SURFACE SEAL	26283.32	SqFt	\$ 0.55	\$ 14,460.00
PMP	TL HANG	4305	52	RAVELING	Medium	5244.82	SqFt	16.5%	FDOT - PATCHING - AC PARTIAL DEPTH	5245.25	SqFt	\$ 3.00	\$ 15,740.00
PMP	TL HANG	4305	52	RAVELING	High	45.85	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	46.28	SqFt	\$ 3.00	\$ 140.00
PMP	TL HANG	4310	45	DEPRESSION	Low	667.9	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	776.08	SqFt	\$ 6.00	\$ 4,660.00
PMP	TL HANG	4310	50	PATCHING	Medium	317.86	SqFt	0.6%	FDOT - PATCHING - AC FULL DEPTH	393.96	SqFt	\$ 6.00	\$ 2,370.00
PMP	TL HANG	4310	52	RAVELING	Medium	43767.03	SqFt	88.6%	FDOT - PATCHING - AC PARTIAL DEPTH	43767.14	SqFt	\$ 3.00	\$ 131,310.00
PMP	TL HANG	4315	41	ALLIGATOR CR	Low	193.21	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	252.95	SqFt	\$ 6.00	\$ 1,520.00
PMP	TL HANG	4315	45	DEPRESSION	Low	1690.15	SqFt	2.0%	FDOT - PATCHING - AC FULL DEPTH	1860	SqFt	\$ 6.00	\$ 11,160.00
PMP	TL HANG	4315	45	DEPRESSION	Medium	662.3	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	769.62	SqFt	\$ 6.00	\$ 4,620.00

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2017

Pompano Beach Airpark (PMP)





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
PMP	TL HANG	4315	45	DEPRESSION	High	289.76	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	362.74	SqFt	\$ 6.00	\$ 2,180.00
PMP	TL HANG	4315	50	PATCHING	Medium	1897.14	SqFt	2.3%	FDOT - PATCHING - AC FULL DEPTH	2076.36	SqFt	\$ 6.00	\$ 12,460.00
PMP	TL HANG	4315	52	RAVELING	Low	32471.7	SqFt	38.8%	FDOT - SURFACE SEAL	32471.49	SqFt	\$ 0.55	\$ 17,860.00
PMP	TL HANG	4320	47	JT REF. CR	Medium	1717.81	Ft	10.7%	FDOT - CRACK SEALING - AC	1717.85	Ft	\$ 3.00	\$ 5,160.00
PMP	TL HANG	4320	48	L&TCR	Medium	412.27	Ft	2.6%	FDOT - CRACK SEALING - AC	412.4	Ft	\$ 3.00	\$ 1,240.00
PMP	TL HANG	4320	49	OIL SPILLAGE	N/A	137.46	SqFt	0.9%	FDOT - PATCHING - AC PARTIAL DEPTH	188.37	SqFt	\$ 3.00	\$ 570.00
PMP	TL HANG	4320	52	RAVELING	Low	3206.57	SqFt	20.0%	FDOT - SURFACE SEAL	3206.57	SqFt	\$ 0.55	\$ 1,770.00
РМР	TW A	115	45	DEPRESSION	Low	341.43	SqFt	2.4%	FDOT - PATCHING - AC FULL DEPTH	419.79	SqFt	\$ 6.00	\$ 2,520.00
PMP	TW A	115	52	RAVELING	Low	1810.92	SqFt	13.0%	FDOT - SURFACE SEAL	1810.49	SqFt	\$ 0.55	\$ 1,000.00
PMP	TW B	210	52	RAVELING	Low	14019.99	SqFt	11.9%	FDOT - SURFACE SEAL	14019.99	SqFt	\$ 0.55	\$ 7,720.00
PMP	TW B	210	52	RAVELING	Medium	1038.5	SqFt	0.9%	FDOT - PATCHING - AC PARTIAL DEPTH	1038.72	SqFt	\$ 3.00	\$ 3,120.00
РМР	TW C	305	45	DEPRESSION	Low	626.46	SqFt	2.4%	FDOT - PATCHING - AC FULL DEPTH	730.87	SqFt	\$ 6.00	\$ 4,390.00
PMP	TW C	305	52	RAVELING	Low	13220.99	SqFt	50.3%	FDOT - SURFACE SEAL	13221.31	SqFt	\$ 0.55	\$ 7,280.00
РМР	TW D	405	48	L&TCR	Medium	35.2	Ft	0.0%	FDOT - CRACK SEALING - AC	35.1	Ft	\$ 3.00	\$ 110.00
PMP	TW D	405	52	RAVELING	Low	13024.87	SqFt	12.3%	FDOT - SURFACE SEAL	13024.33	SqFt	\$ 0.55	\$ 7,170.00
РМР	TW D	410	45	DEPRESSION	Low	769.83	SqFt	5.9%	FDOT - PATCHING - AC FULL DEPTH	885.87	SqFt	\$ 6.00	\$ 5,320.00
PMP	TW D	410	52	RAVELING	Low	1308.35	SqFt	10.0%	FDOT - SURFACE SEAL	1308.89	SqFt	\$ 0.55	\$ 720.00
PMP	TW F	610	48	L&TCR	Medium	157.19	Ft	0.1%	FDOT - CRACK SEALING - AC	157.15	Ft	\$ 3.00	\$ 480.00
PMP	TW F	610	52	RAVELING	Low	9431.45	SqFt	8.0%	FDOT - SURFACE SEAL	9431.34	SqFt	\$ 0.55	\$ 5,190.00
PMP	TW F	612	52	RAVELING	Low	777.69	SqFt	5.0%	FDOT - SURFACE SEAL	778.23	SqFt	\$ 0.55	\$ 430.00
PMP	TW G	710	52	RAVELING	Medium	17.87	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	18.3	SqFt	\$ 3.00	\$ 60.00
PMP	TW L	1202	52	RAVELING	Low	2043.21	SqFt	9.6%	FDOT - SURFACE SEAL	2042.99	SqFt	\$ 0.55	\$ 1,130.00
PMP	TW L	1202	52	RAVELING	Medium	759.82	SqFt	3.6%	FDOT - PATCHING - AC PARTIAL DEPTH	759.93	SqFt	\$ 3.00	\$ 2,280.00
PMP	TW L	1205	48	L&TCR	Medium	173.65	Ft	1.3%	FDOT - CRACK SEALING - AC	173.56	Ft	\$ 3.00	\$ 530.00
PMP	TW L	1205	52	RAVELING	Low	4279.19	SqFt	32.9%	FDOT - SURFACE SEAL	4278.65	SqFt	\$ 0.55	\$ 2,360.00
PMP	TW L	1210	52	RAVELING	Low	34530.95	SqFt	22.6%	FDOT - SURFACE SEAL	34530.62	SqFt	\$ 0.55	\$ 19,000.00
PMP	TW L	1215	52	RAVELING	Low	238.96	SqFt	1.6%	FDOT - SURFACE SEAL	238.96	SqFt	\$ 0.55	\$ 140.00
PMP	TW M	1305	52	RAVELING	Low	11095.22	SqFt	40.0%	FDOT - SURFACE SEAL	11095.44	SqFt	\$ 0.55	\$ 6,110.00
PMP	TW M	1306	52	RAVELING	Low	154.46	SqFt	0.5%	FDOT - SURFACE SEAL	153.92	SqFt	\$ 0.55	\$ 90.00
PMP	TW M	1310	52	RAVELING	Low	240.04	SqFt	1.0%	FDOT - SURFACE SEAL	240.04	SqFt	\$ 0.55	\$ 140.00
PMP	TW M	1315	52	RAVELING	Low	1602.85	SqFt	9.8%	FDOT - SURFACE SEAL	1602.75	SqFt	\$ 0.55	\$ 890.00
PMP	TW M	1320	45	DEPRESSION	Low	865.42	SqFt	0.9%	FDOT - PATCHING - AC FULL DEPTH	988.13	SqFt	\$ 6.00	\$ 5,930.00
PMP	TW M	1320	52	RAVELING	Low	92954.01	SqFt	97.0%	FDOT - SURFACE SEAL	92953.9	SqFt	\$ 0.55	\$ 51,130.00
PMP	TW N	1405	52	RAVELING	Low	564.67	SqFt	2.0%	FDOT - SURFACE SEAL	565.11	SqFt	\$ 0.55	\$ 320.00






#### Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	PMP	AP N	4205	AAC	62,989	59	AC Restoration	\$ 441,000.00
2018	PMP	AP RU RW33	5110	AAC	20,490	57	AC Restoration	\$ 144,000.00
2018	PMP	AP S	4105	AAC	203,761	61	AC Restoration	\$ 1,427,000.00
2018	PMP	AP S	4110	AC	26,025	49	AC Restoration	\$ 183,000.00
2018	PMP	AP S	4125	AC	117,688	46	AC Restoration	\$ 896,000.00
2018	PMP	AP SW	4410	PCC	61,737	79	PCC Restoration	\$ 618,000.00
2018	PMP	RW 10-28	6105	AC	271,200	64	AC Restoration	\$ 1,899,000.00
2018	PMP	RW 6-24	6205	AAC	335,952	63	AC Restoration	\$ 2,352,000.00
2018	PMP	RW 6-24	6210	AAC	167,976	62	AC Restoration	\$ 1,176,000.00
2018	PMP	TL HANG	4305	AC	31,764	38	AC Reconstruction	\$ 286,000.00
2018	PMP	TL HANG	4310	AC	49,387	29	AC Reconstruction	\$ 445,000.00
2018	PMP	TL HANG	4315	AC	83,687	46	AC Restoration	\$ 638,000.00
2018	PMP	TL HANG	4320	APC	16,033	35	AC Reconstruction	\$ 145,000.00
2018	PMP	TW A	115	AAC	13,967	51	AC Restoration	\$ 98,000.00
2018	PMP	TW B	210	AAC	118,013	63	AC Restoration	\$ 827,000.00
2018	PMP	TW C	305	AC	26,289	64	AC Restoration	\$ 185,000.00
2018	PMP	TW D	405	AAC	105,607	62	AC Restoration	\$ 740,000.00
2018	PMP	TW F	610	AAC	117,893	63	AC Restoration	\$ 826,000.00
2018	PMP	TW L	1205	AC	13,025	54	AC Restoration	\$ 92,000.00
2018	PMP	TW L	1210	AAC	152,867	64	AC Restoration	\$ 1,071,000.00
2018	PMP	TW M	1320	AC	95,815	64	AC Restoration	\$ 671,000.00
2019	PMP	TW D	410	AAC	13,072	63	AC Restoration	\$ 92,000.00
2020	PMP	TW L	1202	AAC	21,209	63	AC Restoration	\$ 149,000.00
2022	PMP	TW M	1305	AC	27,738	64	AC Restoration	\$ 195,000.00
2023	PMP	TW M	1315	AC	16,359	64	AC Restoration	\$ 115,000.00
2027	PMP	TW D	420	AAC	23,098	64	AC Restoration	\$ 162,000.00




# Appendix C


Technical Exhibits








#### LEGEND







SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.




INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.


TOTAL SAMPLES INSPECTED = 148 AC: 144 PCC: 4


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

FDOT










#### CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY


& ANTION ATED CONSTRUCTION ACTIVITY									
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION							
2013	AP S	APRON EXPANSION							
2014	TW G, TW K	NEW CONSTRUCTION							
2015	AP S	MILL AND OVERLAY							
2015	AP S	APRON EXPANSION							
2015	AP S	RECONSTRUCTION							

#### **LEGEND**







**√**6310 612 PCI = 83 610 PCI = 64 6205-6210--1320 -420 10 1202 PCI = 67 ∠<sub>1305</sub> ∠1405 -5110 \<sub>1215</sub> 4320 4130 PCI = 100 4305 PCI = 39 4310 PCI = 30




#### **LEGEND**



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.























"PROGRAM YEAR"
"BRANCH":"SECTION"
"REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.



## Appendix D

Inspection Photograph Documentation









Runway 10-28, Section 6105, Sample Unit 152 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling, Low Severity (56) Swelling



Runway 10-28, Section 6105, Sample Unit 117 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling







Runway 10-28, Section 6105, Sample Unit 141 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling



Runway 15-33, Section 6305, Sample Unit 325 - Low Severity (57) Weathering

Airport Pavement Evaluation Report







Runway 15-33, Section 6305, Sample Unit 303 - Low Severity (57) Weathering



Runway 15-33, Section 6310, Sample Unit 112 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering







Runway 6-24, Section 6205, Sample Unit 306 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Runway 6-24, Section 6205, Sample Unit 323 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering







Runway 6-24, Section 6205, Sample Unit 346 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (50) Patching, Low Severity (52) Raveling, Low Severity (57) Weathering




Runway 6-24, Section 6210, Sample Unit 132 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering







Taxiway A, Section 115, Sample Unit 106 - Low Severity (43) Block Cracking, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Taxiway B, Section 210, Sample Unit 706 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering

Airport Pavement

**Evaluation Report** 





Taxiway D, Section 405, Sample Unit 413 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (53) Rutting, Low Severity (57) Weathering



Taxiway D, Section 405, Sample Unit 420 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering







Taxiway F, Section 610, Sample Unit 601 - Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (50) Patching, Low Severity (52) Raveling, Low Severity (57) Weathering



Taxiway F, Section 610, Sample Unit 625 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering





Taxiway K, Section 1110, Sample Unit 121 - Low Severity (57) Weathering



Taxiway M, Section 1306, Sample Unit 211 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (50) Patching, Low Severity (52) Raveling, Low Severity (57) Weathering







South Apron, Section 4105, Sample Unit 329 - Low Severity (43) Block Cracking, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling



South Apron, Section 4125, Sample Unit 201 - Low Severity (43) Block Cracking, Low Severity (52) Raveling, Medium Severity (52) Raveling







North Apron - Old RW, Section 4205, Sample Unit 321 - Low and Medium Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering



Taxilane To Hangars, Section 4305, Sample Unit 601 - Low Severity (43) Block Cracking, Low Severity (50) Patching, High Severity (50) Patching, Medium Severity (52) Raveling, High Severity (52) Raveling







Taxilane To Hangars, Section 4315, Sample Unit 602 - Medium Severity (45) Depression, Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering




Taxilane To Hangars, Section 4315, Sample Unit 700 - Low Severity (41) Alligator Cracking, Low Severity (45) Depression, Low Severity (52) Raveling



# Appendix E

Inspection Distress Details



#### **Re-Inspection Report**

**FDOT** 

Generated Date 7/26/2017 Page 1 of 60

	ed Date		7/26/2	2017						1 age	
Network:	: PMP				N	ame: PO	MPANO BEA	CH AIRPARK			
Branch:	AP N		N	ame:	NORTH AI	PRON - OLD RW	Use:	APRON	Area:	62,989 SqFt	
Section:	4205	0	f 1	Fr	om: -			То: -		Last Const.: 1/1/1	972
Surface:	AAC	Family:	C9N59 APC	-GA-AP-	AAC- Zo	one:		Category:		Rank: P	
Area:		62,989 SqFt	I	ength:	950	Ft	Width:	100 Ft			
Slabs:		Slab Len	gth:		Ft	Slab Width:		Ft	Joint Leng	gth: Ft	
Shoulder	:	Street T	ype:			Grade: 0			Lanes:	0	
<b>Section</b> C	Comments:										
Work Da	ite: 1/1/1972	W	ork Typ	e: BUILT			C	ode: IMPORTED	Is Ma	jor M&R: True	
Last Insp	<b>Date:</b> 5/8/2	2017		TotalSar	nples: 13		Surveye	<b>d:</b> 2			
Condition	ns: PCI:	61									
Inspection	n Comments:	:									
Sample N	Number: 32	1 Tyı	oe:	R	Area:	486	3.00 SqFt	PCI: 6	50		
-	Number: 322 Comments:	1 Typ	pe:	R	Area:	486	3.00 SqFt	PCI: 6	50		
Sample C		1 Туј	be:	R	Area: 560.00 Ft	486	3.00 SqFt	PCI: 6	50		
Sample C	Comments:	1 Туј		R			3.00 SqFt	PCI: 6	50		
<b>Sample C</b> 48 L 6 52 RA	Comments:		L	R	560.00 Ft	t	3.00 SqFt	PCI: 6	50		
<b>Sample C</b> 48 L 6  52 RA  57 W	Comments: & T CR AVELING		L L	R	560.00 Ft 486.00 SqF	t	3.00 SqFt	PCI: 6	50		
52 RA 57 W 48 L 6	Comments: & T CR AVELING 'EATHERINC	3	L L L M	R	560.00 Ft 486.00 SqF 4382.00 SqF	t t	3.00 SqFt 3.00 SqFt	PCI: 6			
48 L 4 52 RA 57 W 48 L 4 Sample N	Comments: & T CR AVELING EATHERING & T CR	3	L L L M		560.00 Ft 486.00 SqF 4382.00 SqF 15.00 Ft	t t					
48 L 4 52 RA 57 W 48 L 4 Sample N Sample C	& T CR & VELING EATHERING TCA TCR  Wumber: 517	3	L L L M		560.00 Ft 486.00 SqF 4382.00 SqF 15.00 Ft	t t					
Sample C           48         L a           52         RA           57         W           48         L a           Sample N         Sample C           48         L a	& T CR AVELING 'EATHERING & T CR Number: 51'	3	L L L M		560.00 Ft 486.00 SqF 4382.00 SqF 15.00 Ft <b>Area:</b>	460					
Sample C  48	& T CR AVELING EATHERING & T CR Number: 517 Comments:	ту <u>ј</u>	L L L M		560.00 Ft 486.00 SqF 4382.00 SqF 15.00 Ft <b>Area:</b>	4600					

Network:	PMP			·	Name:	POMPANO BE	EACH AIR	PARK		
Branch:	AP RU RW3	3	Name:	RUNU	P TO RUNWAY	Y 33 Use:	APRO	N	Area:	34,800 SqFt
Section:	5105	O	f 2 I	From: -			To:	: -		<b>Last Const.:</b> 6/1/2012
Surface:	AAC	Family:	C9N59-GA-AI APC	P-AAC-	Zone:		Car	tegory:		Rank: P
Area:	14,3	10 SqFt	Length:		100 Ft	Width:		100 Ft		
Slabs:		Slab Len	gth:	Ft	Slab W	idth:	Ft		Joint Length	ı: Ft
Shoulder:		Street Ty	vpe:		Grade:	0			Lanes: 0	)
Section Cor	mments:									
Work Date:	: 1/1/1950	W	ork Type: New	Construction	n - Initial		Code: N	U-IN	Is Major	r M&R: True
Work Date:	: 6/1/2012	W	ork Type: MIL	and OVER	RLAY		Code: M	L-OV	Is Major	r M&R: True
Last Insp. I	Date: 5/8/2017		TotalS	amples: 3	}	Surve	<b>yed:</b> 1			
Conditions:	<b>PCI:</b> 92									
Inspection (	Comments:									
Sample Nui	mber: 333	Тур	e: R	A	rea:	6975.00 SqFt		<b>PCI:</b> 92		
Sample Cor	mments.									

7.00 Ft 6975.00 SqFt

L L

L & T CR WEATHERING

48

57

Network:	PMP			1	Name: PC	MPANO BEA	ACH AIRPARK		
Branch:	AP RU RW33	3	Name:	RUNUP T	O RUNWAY 33	Use:	APRON	Area:	34,800 SqFt
Section:	5110	of	2 <b>F</b>	rom: -			То: -		<b>Last Const.:</b> 1/1/199
Surface:	AAC	Family:	C9N59-GA-AP- APC	AAC-	Zone:		Category:		Rank: P
Area:	20,49	00 SqFt	Length:	20	00 Ft	Width:	100 Ft		
Slabs:		Slab Len	gth:	Ft	Slab Width:		Ft	Joint Le	ength: Ft
Shoulder:		Street Ty	pe:		Grade: (	)		Lanes:	0
Section Co	omments:								
Work Dat	e: 1/1/1950	Wo	ork Type: New (	Construction -	Initial	C	ode: NU-IN	Is M	Tajor M&R: True
Work Date	e: 1/1/1996	Wo	ork Type: MILL	and OVERLA	ΛY	C	ode: ML-OV	Is M	Iajor M&R: True
Last Insp.	<b>Date:</b> 5/8/2017		TotalSa	mples: 4		Surveye	e <b>d:</b> 1		
Conditions	s: <b>PCI</b> : 59								
Inspection	Comments:								
Sample Nu	umber: 332	Тур	e: R	Area	: 624	19.00 SqFt	PCI:	59	
Sample Co	omments:								
48 L <i>&amp;</i>	& T CR		L	813.00 Ft					
52 RA	VELING		L	1875.00 Sq	Ft				
56 SW	ELLING		L	102.00 Sq	Ft				
57 WE	EATHERING		L	4374.00 Sq	Ft				

Network: PMP		Nam	e: POMPANO BE.	ACH AIRPARK		
Branch: AP S	Name:	SOUTH APRO	ON Use:	APRON	Area:	682,694 SqFt
Section: 4105	of 7	From: -		То: -		<b>Last Const.:</b> 1/1/1997
Surface: AAC	<b>Family:</b> C9N59-GA APC	-AP-AAC- <b>Zone</b>	:	Category:		Rank: P
Area: 203,76	1 SqFt Lengt	h: 2,300 Ft	Width:	90 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint L	ength: Ft
Shoulder:	Street Type:		Grade: 0		Lanes:	0
Section Comments:						
<b>Vork Date:</b> 1/1/1970	Work Type: O	VERLAY	(	Code: IMPORTED	Is N	Major M&R: True
<b>Work Date:</b> 1/1/1997	Work Type: B	UILT	(	Code: IMPORTED	Is N	Major M&R: True
Last Insp. Date: 5/8/2017	Tota	alSamples: 45	Survey	ed: 5		
Conditions: PCI: 63						
Inspection Comments:						
Sample Number: 310	Type: R	Area:	5000.00 SqFt	PCI:	53	
Sample Comments:						
18 L & T CR	L	556.00 Ft				
18 L & T CR	M	30.00 Ft				
52 RAVELING	L	5000.00 SqFt				
Sample Number: 320	<b>Type:</b> R	Area:	5000.00 SqFt	PCI:	50	
Sample Comments: Lar	ge repair in middle of sa	mple				
48 L & T CR	L	273.00 Ft				
50 PATCHING	L	2400.00 SqFt				
52 RAVELING	L	2600.00 SqFt				
Sample Number: 329	Type: R	Area:	5000.00 SqFt	PCI:	59	
Sample Comments:						
BLOCK CR	L	210.00 SqFt				
18 L & T CR	L	451.00 Ft				
52 RAVELING	L	5000.00 SqFt				
56 SWELLING	L	115.00 SqFt	5200 00 G T			
Sample Number: 514	Type: R	Area:	5200.00 SqFt	PCI:	59	
Sample Comments:						
18 L & T CR	L	463.00 Ft				
52 RAVELING	L	5200.00 SqFt				
Sample Number: 525	Type: R	Area:	3700.00 SqFt	PCI:	53	
Sample Comments:						

L 457.00 Ft L 3700.00 SqFt L 50.00 SqFt

48

52

56

L & T CR

RAVELING

SWELLING

POMPANO BEACH AIRPARK PMP Network: Name: **Branch:** AP S Name: SOUTH APRON Use: APRON Area: 682,694 SqFt Section: 4107 of 7 From: **Last Const.:** 1/1/2015 To: -Surface: PCC Family: C9N59-GA-AP-PCC Zone: Category: Rank: P Area: 3,846 SqFt Length: 110 Ft Width: 35 Ft Slabs: 12 Slab Length: 20 Ft Slab Width: 16 Ft Joint Length: 288 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/2015 Work Type: New Construction - PCC Code: NC-PC Is Major M&R: True **Last Insp. Date:** 5/8/2017 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 712 R 12.00 Slabs **PCI:** 88 Type: Area: **Sample Comments:** 

65 JT SEAL DMG H 12.00 Slabs

Network:	PMP			Name	POMPANO BE	EACH AIRPARK		
Branch:	AP S		Name:	SOUTH APRO	N Use:	APRON	Area:	682,694 SqFt
Section:	4110	of	7	From: -		То: -		Last Const.: 1/1/1960
Surface:	AC	Family:	C9N59-GA-A	AP-AC Zone:		Category:		Rank: P
Area:		26,025 SqFt	Length:	450 Ft	Width:	45 Ft		
Slabs:		Slab Leng	gth:	Ft S	Slab Width:	Ft	Joint Lengt	th: Ft
Shoulder:		Street Ty	pe:		Grade: 0		Lanes:	0
Section Co	mments:							
Work Date	: 1/1/1960	Wo	ork Type: BUI	LT		Code: IMPORTED	Is Majo	or M&R: True
Last Insp. I	<b>Date:</b> 5/8/	/2017	Totals	Samples: 5	Surve	yed: 1		
Conditions	: PCI:	51						
Inspection	Comments	<b>:</b>						
Sample Nu	mber: 71	3 <b>Typ</b>	e: R	Area:	5228.00 SqFt	<b>PCI:</b> 51		
Sample Co	mments:							
43 BLC	OCK CR		L	5192.00 SqFt				
	T CR		Н	36.00 Ft				
52 RAV	VELING		L	5228.00 SqFt				

Branch:	AP S		N	ame: S	SOUTH APRO	ON	Use:	APRON	Area:	68	82,694 SqFt
Section:	4112	of	7	From	-			То: -			<b>Last Const.:</b> 5/17/2013
Surface:	AC	Family:	C9N59	9-GA-AP-AC	Zon	e:		Category:			Rank: P
Area:	131,00	08 SqFt	Ι	ength:	700 F	it	Width:	200 Ft			
Slabs:		Slab Leng	gth:		Ft	Slab Width:		Ft	Join	t Length:	Ft
Shoulder:		Street Ty	pe:			<b>Grade:</b> 0			Lan	es: 0	
Section Co	omments:										
Work Dat	te: 5/17/2013	Wo	rk Typ	e: New Cons	truction - Init	ial	C	ode: NU-IN		Is Major N	<b>1&amp;R:</b> True
Last Insp.	Date: 5/8/2017			TotalSample	es: 29		Surveye	ed: 3			
Condition	s: <b>PCI</b> : 92										
Inspection	n Comments:										
Sample N	umber: 722	Тур	e:	R	Area:	5000	0.00 SqFt	PCI:	94		
Sample C	omments:										
57 WI	EATHERING		L	500	00.00 SqFt						
Sample N	umber: 818	Тур	e:	R	Area:	5000	0.00 SqFt	PCI:	94		
Sample C	omments:										
57 WI	EATHERING		L	500	00.00 SqFt						
Sample N	umber: 915	Тур	e:	R	Area:	5000	0.00 SqFt	PCI:	89		
Sample C	omments:										
45 DE	EDDECCION		т		25.00 G.E						
22	EPRESSION		L	3	85.00 SqFt						

Name:

POMPANO BEACH AIRPARK

PMP

Network:

Netw	ork: PMP			Na	me: POl	MPANO BEA	ACH AIRPARK				
Bran	ch: AP S		Name:	SOUTH AP	RON	Use:	APRON	Area:	68	32,694 SqFt	
Section	on: 4125	of 7		From: -			То: -			Last Const.:	12/25/1999
Surfa	ace: AC	Family: C	9N59-GA-A	P-AC Zo	ne:		Category:			Rank: P	
Area	: 117,6	88 SqFt	Length:	500	Ft	Width:	220 Ft				
Slabs	s <b>:</b>	Slab Length	:	Ft	Slab Width:		Ft	Join	t Length:	Ft	
Shou	lder:	Street Type:			Grade: 0			Lan	es: 0		
Section	on Comments:										
Worl	k Date: 12/25/1999	Work	Type: New	Construction - In	itial	C	ode: NU-IN	]	Is Major M	<b>1&amp;R:</b> True	
Last	Insp. Date: 5/8/2017	1	TotalS	Samples: 25		Surveye	ed: 3				
Cond	litions: PCI: 48										
Inspe	ection Comments: R	epairs done									
Samr	ple Number: 201	Type:	R	Area:	500	0.00 SqFt	PCI:	44			
	ole Comments:	-J <b>F</b> • •				1					
52	RAVELING		L	4000.00 SqFt							
52	RAVELING		M	1000.00 SqFt							
43	BLOCK CR		L	5000.00 SqFt							
Samp	ple Number: 403	Type:	R	Area:	500	0.00 SqFt	PCI:	43			
Samp	ple Comments:										
43	BLOCK CR		L	4288.00 SqFt							
45	DEPRESSION		L	49.00 SqFt							
49	OIL SPILLAGE		N	18.00 SqFt							
50	PATCHING		L	712.00 SqFt							
52	RAVELING		L	4267.00 SqFt							
52	RAVELING		Н	21.00 SqFt							
	ple Number: 500 ple Comments:	Type:	R	Area:	500	0.00 SqFt	PCI:	55			
43	BLOCK CR		L	2700.00 SqFt							
48	L & T CR		L	238.00 Ft							
52	RAVELING		L	5000.00 SqFt							
56	SWELLING		L	50.00 SqFt							

Network: PMP			Name:	POMPANO BEA	CH AIRPARK		
Branch: AP S		Name:	SOUTH APRON	Use:	APRON	Area: 682,69	94 SqFt
Section: 4130	of 7	1	From: -		То: -	La	ast Const.: 1/1/2015
Surface: AAC	•	9N59-GA- <i>A</i> PC	AP-AAC- Zone:		Category:	Ra	ank: P
Area:	71,613 SqFt	Length	500 Ft	Width:	150 Ft		
Slabs:	Slab Length	:	Ft Sla	b Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:	:	Gr	ade: 0		Lanes: 0	
Section Comments:							
Work Date: 12/25/199	9 Work	Type: Nev	w Construction - Initial	C	ode: NU-IN	Is Major M&F	R: True
Work Date: 1/1/2015	Work	Type: MII	LL and OVERLAY	C	ode: ML-OV	Is Major M&F	R: True
Last Insp. Date: 10/1	6/2013	Total	Samples: 38	Surveye	<b>d:</b> 4		
Conditions: PCI:	50		NOTE: *** PI	e-Construction PCI **	**)		
Inspection Comments:							
Sample Number: 201	Туре:	R	Area:	5000.00 SqFt	<b>PCI:</b> 45	5	
Sample Comments:				_			
52 RAVELING		L	4500.00 SqFt				
72 RAVELING 72 RAVELING		M	500.00 SqFt				
77 WEATHERING		L	4500.00 SqFt				
BLOCK CRAC		L	5000.00 SqFt				
Sample Number: 305	Type:	R	Area:	5000.00 SqFt	PCI: 42	2	
Sample Comments:							
5 DEPRESSION		L	9.00 SqFt				
5 DEPRESSION		M	56.00 SqFt				
5 DEPRESSION		L	16.00 SqFt				
5 DEPRESSION		M	15.00 SqFt				
5 DEPRESSION		L	16.00 SqFt				
50 PATCHING		L	20.00 SqFt				
BLOCK CRAC	KING	L	4980.00 SqFt				
52 RAVELING		L	4980.00 SqFt				
57 WEATHERING		L	4980.00 SqFt				
Sample Number: 403	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 57	7	
Sample Comments:							
45 DEPRESSION		L	12.00 SqFt				
43 BLOCK CRAC	KING	L	2000.00 SqFt				
	AL/TRANSVERSE	L	117.00 Ft				
52 RAVELING		L	5000.00 SqFt				
57 WEATHERING		L	5000.00 SqFt				
Sample Number: 500	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 56	5	
Sample Comments:							
48 LONGITUDINA CRACKING	AL/TRANSVERSE	L	194.00 Ft				
BLOCK CRAC	KING	L	2600.00 SqFt				
52 RAVELING		L	2600.00 SqFt				
32 TOTT EELITO							

Bran	ch: AP SW		Name:	SOUTHWEST	APRON Use:	APRON	Area:	61,7	37 SqFt
Secti	on: 4410	of 1	l	From: -		То: -		L	ast Const.: 1/1/2012
Surfa	ice: PCC	Family: C	9N59-GA- <i>A</i>	AP-PCC Zone	:	Category:		R	ank: P
Area	: 61,73	7 SqFt	Length	: 1,000 Ft	Width:	50 Ft			
Slabs	329	Slab Length	ı <b>:</b>	13 Ft	Slab Width:	15 Ft	Join	t Length:	6,283 Ft
Shou	lder:	Street Type:	:		Grade: 0		Lane	es: 0	
Secti	on Comments:								
Wor	<b>Date:</b> 1/1/2012	Work	Type: Nev	w Construction - Initia	al (	Code: NU-IN	]	Is Major M&l	R: True
Last	Insp. Date: 5/8/2017		Total	Samples: 21	Survey	ed: 3			
Cond	litions: PCI: 81								
Inspe	ection Comments:								
Samj	ole Number: 302	Type:	R	Area:	18.00 Slabs	PCI:	83		
Samj	ole Comments:								
62	CORNER BREAK		L	2.00 Slabs					
65	JT SEAL DMG		Н	18.00 Slabs					
Samj	ole Number: 351	Type:	R	Area:	18.00 Slabs	PCI:	77		
Samp	ole Comments:								
62	CORNER BREAK		L	3.00 Slabs					
65	JT SEAL DMG		Н	18.00 Slabs					
74	JOINT SPALL		L	2.00 Slabs					
Samp	ole Number: 453	Type:	R	Area:	18.00 Slabs	PCI:	83		
Samp	ole Comments:								
62	CORNER BREAK		L	1.00 Slabs					

Name:

PMP

Network:

POMPANO BEACH AIRPARK

Netwo	rk: PMP				Nam	ne: POMPANO BEA	CH AIRPARK			
Brancl	h: RW 10-28		Name:	RUNW	VAY 10	-28 Use:	RUNWAY	Area:	329,5	520 SqFt
ection	<b>n:</b> 6105	of 2			-		To: -		L	ast Const.: 1/1/1968
Surfac	e: AC	Family: C	9N59-GA-	RW-AC	Zone	e:	Category:		R	ank: P
rea:	271,200	O SqFt	Length	ı:	935 F	t Width:	100 Ft			
labs:		Slab Length	:	Ft		Slab Width:	Ft	Joint	Length:	Ft
Should	ler:	Street Type:				Grade: 0		Lane	es: 0	
Section	n Comments:									
Vork 1	<b>Date:</b> 1/1/1968	Work	Type: BU	JILT		Co	ode: IMPORTED	I	s Major M&l	R: True
ast Ir	nsp. Date: 5/8/2017		Tota	lSamples:	54	Surveye	<b>d:</b> 11			
	tions: PCI: 66									
	tion Comments:									
ample	e Number: 102	Type:	R	A	rea:	5000.00 SqFt	<b>PCI:</b> 67	,		
ampl	e Comments:									
18	L & T CR		L	35.00						
	PATCHING		L	1250.00						
	RAVELING		L	3750.00						
_	e Number: 106	Type:	R	A	rea:	5000.00 SqFt	PCI: 68			
ampl	e Comments:									
	L & T CR		L	27.00						
	PATCHING		L	4.00						
	RAVELING		L	4996.00						
_	e Number: 110 e Comments:	Type:	R	A	rea:	5000.00 SqFt	<b>PCI:</b> 67			
_										
	L & T CR		L	290.00						
	PATCHING RAVELING		L L	2.00 4998.00						
	e Number: 117	Type:	R		rea:	5000.00 SqFt	<b>PCI:</b> 69	<u> </u>		
_	e Comments:	••				•				
18	L & T CR		L	376.00	Ft					
52	RAVELING		L	5000.00	SqFt					
Sample	e Number: 124	Type:	R	A	rea:	5000.00 SqFt	<b>PCI:</b> 69	1		
Sample	e Comments:									
18	L & T CR		L	334.00	Ft					
	RAVELING		L	5000.00						
Sample	e Number: 127	Type:	R	A	rea:	5000.00 SqFt	PCI: 69	1		
Sample	e Comments:									
_	L & T CR		L	67.00	Ft					
	RAVELING		L	5000.00						
	e Number: 131	Type:	R		rea:	5000.00 SqFt	PCI: 66	;		
_		-in patch				•				
_		•	T	116.00	E+					
	L & T CR PATCHING		L L	116.00 1250.00						
	RAVELING		L	3750.00						
Sample	e Number: 134	Type:	R	A	rea:	5000.00 SqFt	PCI: 69	1		
Sample	e Comments:									
18	L & T CR		L	153.00	Ft					
	RAVELING		L	5000.00						
Sample	e Number: 141	Type:	R		rea:	5000.00 SqFt	PCI: 66	i		
Sample	e Comments:									
66	SWELLING		L	45.00	SqFt					
18	L & T CR		L	278.00	Ft					E-11
52	RAVELING		L	5000.00	S a Et					

Sam	ple Number: 146	Type: R	Area:	5000.00 SqFt	PCI: 62
	•	in patch			
, outing	pie comments.	in paten			
48	L & T CR	L	225.00 Ft		
50	PATCHING	L	858.00 SqFt		
52	RAVELING	L	4142.00 SqFt		
56	SWELLING	L	50.00 SqFt		
Sam	ple Number: 152	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 59
Sam	ple Comments:				
48	L & T CR	L	527.00 Ft		
52	RAVELING	L	4900.00 SqFt		
52	RAVELING	M	100.00 SqFt		
56	SWELLING	L	100.00 SqFt		

Network:	PMP				Name:	POMPA	NO BEA	ACH AIRPARK			
Branch:	RW 10-2	8	Name	: RUNW	AY 10-28		Use:	RUNWAY	Area:	329	,520 SqFt
Section:	6115	0	of 2	From: -				То: -			Last Const.: 1/1/2
Surface:	AAC	Family:	C9N59-GA APC	A-RW-AAC-	Zone:			Category:			Rank: P
Area:	5	58,320 SqFt	Leng	th:	225 Ft	Wi	lth:	100 Ft			
Slabs:		Slab Lei	ngth:	Ft	Sla	b Width:		Ft	Joint	Length:	Ft
Shoulder:		Street T	ype:		Gr	ade: 0			Lane	s: 0	
Section Co	omments:										
Work Date	<b>e:</b> 1/1/1968	W	ork Type: I	BUILT			C	ode: IMPORTE	D I	s Major Ma	&R: True
Work Date	<b>e:</b> 1/1/2012	W	ork Type: N	MILL and OVER	LAY		C	ode: ML-OV	I	s Major Mo	&R: True
Last Insp.	<b>Date:</b> 5/8/2	017	То	talSamples: 1	2		Surveye	ed: 3			
Conditions	s: PCI:	87									
Inspection	Comments:										
Sample Nu	umber: 156	Ty	pe: R	A	·ea:	5000.00	SqFt	PCI:	72		
Sample Co	omments:	Tie-in patch									
	TCHING EATHERING		L L	1300.00 3700.00	•						
Sample Nu	ımber: 166	Ty	pe: R	A	ea:	5002.00	SqFt	PCI:	94		
Sample Co	omments:										
57 WE	EATHERING		L	5002.00	SqFt						
Sample Nu	umber: 169	Ty	pe: R	A	ea:	5200.00	SqFt	PCI:	94		
Sample Co	omments:										
	EATHERING		L	5200.00							

Network: PMP			Name	e: POMPANO BE	EACH AIRPARK		
Branch: RW 15-3	33	Name:	RUNWAY 15-	33 Use:	RUNWAY	Area:	737,700 SqFt
Section: 6305	of 4	4 F	rom: -		То: -		Last Const.: 1/1/2012
Surface: AAC		9N59-GA-RV .PC	V-AAC- Zone	:	Category:		Rank: P
Area: 2	20,900 SqFt	Length:	4,220 Ft	Width:	100 Ft		
Slabs:	Slab Length	ı:	Ft	Slab Width:	Ft	Joint Leng	th: Ft
Shoulder:	Street Type	:		Grade: 0		Lanes:	0
<b>Section Comments:</b>							
Work Date: 1/1/1969	Work	Type: BUIL	T		Code: IMPORTED	Is Maj	or M&R: True
Work Date: 1/1/2012	Work	Type: MILI	and OVERLAY		Code: ML-OV	Is Maj	or M&R: True
Last Insp. Date: 5/8/	2017	TotalSa	amples: 44	Surve	yed: 8		
Conditions: PCI:	92						
Inspection Comments							
Sample Number: 303	Type:	R	Area:	5000.00 SqFt	PCI: 90	0	
Sample Comments:							
48 L & T CR		L	17.00 Ft				
57 WEATHERING	ł	L	5000.00 SqFt				
Sample Number: 310	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 94	4	
Sample Comments:							
57 WEATHERING	<del> </del>	L	5000.00 SqFt				
Sample Number: 310	Type:	R	Area:	5000.00 SqFt	PCI: 94	4	
Sample Comments:							
57 WEATHERING	ł	L	5000.00 SqFt				
Sample Number: 320	Type:	R	Area:	5000.00 SqFt	PCI: 83	5	
Sample Comments:							
48 L & T CR		L	23.00 Ft				
52 RAVELING		L	200.00 SqFt				
57 WEATHERING		L	4800.00 SqFt	5000 00 G T:	BOT. O	1	
Sample Number: 325 Sample Comments:	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 94	+	
_		<b>T</b>	5000.00 5 5				
57 WEATHERING		L	5000.00 SqFt	5000 00 G T:	DOI 0	1	
Sample Number: 329 Sample Comments:	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 94	+	
-							
57 WEATHERING		L	5000.00 SqFt	5000 00 0 =		4	
Sample Number: 333	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 94	4	
Sample Comments:							
42 BLEEDING 57 WEATHERING	1	N L	1.00 SqFt				
57 WEATHERING  Sample Number: 340		R	5000.00 SqFt	5000.00 SqFt	<b>PCI:</b> 94	1	
Sample Number: 340 Sample Comments:	Type:	ĸ	Area:	3000.00 SqFt	PCI: 9	+	

57 WEATHERING

L 5000.00 SqFt

Netwo	ork: PMP				Name:	POMPANO BI	EACH AIRPARK		
Branc	h: RW 15-33		N	ame:	RUNWAY 15-33	Use	: RUNWAY	Area:	737,700 SqFt
Section	<b>n:</b> 6310	of 4	4		From: -		То: -		<b>Last Const.:</b> 1/1/2012
Surfac	ce: AAC	•	9N5 PC	9-GA-R	RW-AAC- Zone:		Category:		Rank: P
Area:	441,80	00 SqFt	I	Length:	8,400 Ft	Width:	25 Ft		
Slabs:		Slab Length	1:		Ft Sla	b Width:	Ft	Joint	<b>Length:</b> Ft
Shoule	der:	Street Type	:		Gr	<b>ade:</b> 0		Lane	<b>s:</b> 0
Sectio	n Comments:								
Work	<b>Date:</b> 1/1/1969	Work	Тур	oe: BU	ILT		Code: IMPORTED	I	s Major M&R: True
Work	<b>Date:</b> 1/1/2012	Work	Тур	e: MII	LL and OVERLAY		Code: ML-OV	I	s Major M&R: True
Last I	nsp. Date: 5/8/2017			Total	Samples: 88	Surve	yed: 18		
Condi	tions: PCI: 93								
Inspec	ction Comments:								
Sampl	le Number: 102	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 90		
Sampl	le Comments:								
48	L & T CR		L		21.00 Ft				
57	WEATHERING		L		5000.00 SqFt				
Sampl	le Number: 107	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 92		
Sampl	le Comments:								
48	L & T CR		L		1.00 Ft				
57	WEATHERING		L		5000.00 SqFt				
	le Number: 112	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 90		
Sampl	le Comments:								
48 57	L & T CR WEATHERING		L L		18.00 Ft 5000.00 SqFt				
Sampl	le Number: 117	Туре:		R	Area:	5000.00 SqFt	<b>PCI:</b> 92		
Sampl	le Comments:								
48 57	L & T CR WEATHERING		L L		3.00 Ft 5000.00 SqFt				
Sampl	le Number: 122	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 94		
Sampl	le Comments:								
57	WEATHERING		L		5000.00 SqFt				
Sampl	le Number: 127	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 94		
_	le Comments:					-			
57	WEATHERING		L		5000.00 SqFt				
	le Number: 132	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 94		
_	le Comments:					•			
57	WEATHERING		L		5000.00 SqFt				
	le Number: 137	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 94		
_	le Comments:	- J Pc.		-		222.00 242 0	202.		
57	WEATHERING		L		5000.00 SqFt				
	le Number: 142	Type:	ь	R	Area:	5000.00 SqFt	<b>PCI:</b> 94		
_	le Comments:	туре:			Aica.	5000.00 bqrt	1 (1. 94		
_			_		<b></b>				
57	WEATHERING		L	D.	5000.00 SqFt	5000 00 5 7	<b>.</b>		
_	le Number: 500	Type:		R	Area:	5000.00 SqFt	<b>PCI:</b> 94		
Sampl	le Comments:								
57	WEATHERING		L		5000.00 SqFt				

Sample Number: 505	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 92	
<b>Sample Comments:</b>					
48 L & T CR	L	2.00 Ft			
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 511	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 92	
<b>Sample Comments:</b>					
48 L & T CR	L	5.00 Ft			
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 515	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 94	
<b>Sample Comments:</b>					
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 520	Type: F	Area:	5000.00 SqFt	<b>PCI:</b> 92	
<b>Sample Comments:</b>					
48 L & T CR	L	4.00 Ft			
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 524	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 96	
<b>Sample Comments:</b>					
52 RAVELING	M	1.00 SqFt			
Sample Number: 530	Type: F	Area:	5000.00 SqFt	<b>PCI:</b> 94	
<b>Sample Comments:</b>					
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 535	Type: F	Area:	5000.00 SqFt	<b>PCI:</b> 94	
<b>Sample Comments:</b>					
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 541	Type: B	Area:	5000.00 SqFt	<b>PCI:</b> 94	
<b>Sample Comments:</b>					
57 WEATHERING	L	5000.00 SqFt			

Branch	RW 15-	-33		Name:	RUNWA	AY 15-33	Use:	RUNWAY	Are	ea:	737,700 S	SqFt
Section	ı: 6325		of 4		From: -			То: -			Last C	Const.: 6/1/201
Surface	e: AC	Family	: C9	N59-GA-F	RW-AC	Zone:		Category:			Rank:	P
Area:		25,000 SqFt		Length	:	500 Ft	Width:	50 I	₹t			
Slabs:		Slab I	ength:		Ft	Slab V	Width:	Ft		Joint Lengt	h:	Ft
Should	er:	Street	Type:			Grad	<b>e:</b> 0			Lanes:	0	
Section	Comments:											
Work I	Date: 6/1/2012		Work 7	Гуре: Nev	w Construction	- Initial	(	Code: NU-IN		Is Majo	or M&R: T	True
Last In	sp. Date: 5/8/	/2017		Total	Samples: 5		Survoy	ed: 2				
Conditi	•			Total	Samples. 3		Survey					
Conditi	ions: PCI:	84		Total	Samples. 3		Survey	_				
	•	84		Total	Samples. 3		Survey					
Inspect	ions: PCI:	84	Type:	R	Ar	ea:	5000.00 SqFt	PCI:	81			
Inspect Sample	ions: PCI:	84	Type:		•	ea:			81			
Inspect Sample Sample	ions: PCI: tion Comments e Number: 34	84		R	•				81			
Sample Sample	ions: PCI: tion Comments e Number: 34 e Comments:	84			Ar.	₹t			81			
Inspect Sample Sample 48	ions: PCI: tion Comments e Number: 34 e Comments: L & T CR	84 :: 4 7		R L	Ar	Ft SqFt			81			
Sample Sample 48 50 57	ions: PCI: tion Comments e Number: 34 e Comments: L & T CR PATCHING	84 :: 4 7		R L L	10.00 F 300.00 S	Ft SqFt SqFt						
Sample Sample 48 50 57 Sample	ions: PCI: tion Comments Number: 34 Comments: L & T CR PATCHING WEATHERING	84 :: 4 7		R L L L	10.00 F 300.00 S 4700.00 S	Ft SqFt SqFt	5000.00 SqFt	PCI:				
Sample Sample 48 50 57 Sample Sample	ions: PCI: tion Comments e Number: 34 e Comments: L & T CR PATCHING WEATHERING	84 :: 4 7	Type:	R L L L	10.00 F 300.00 S 4700.00 S	<sup>7</sup> t SqFt SqFt <b>ea:</b>	5000.00 SqFt	PCI:				
Sample Sample 48 50 57 Sample Sample 48	ions: PCI: tion Comments Number: 34 Comments: L & T CR PATCHING WEATHERING Number: 34 Comments:	84 :: 4 7	`ype:	R L L L R	10.00 F 300.00 S 4700.00 S	Ft SqFt SqFt <b>ea:</b>	5000.00 SqFt	PCI:				

Name:

POMPANO BEACH AIRPARK

PMP

Network:

Network: PMP		Name:	POMPANO BEAC	H AIRPARK		
Branch: RW 15-33	Name:	RUNWAY 15-33	Use:	RUNWAY	Area:	737,700 SqFt
Section: 6330	of 4 F	rom: -		То: -		<b>Last Const.:</b> 6/1/2012
Surface: AC	Family: C9N59-GA-RW	-AC <b>Zone:</b>		Category:		Rank: P
<b>Area:</b> 50,00	00 SqFt Length:	500 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft Slab V	Vidth:	Ft	Joint Length	Ft Ft
Shoulder:	Street Type:	Grade	e: 0		Lanes: 0	)
<b>Section Comments:</b>						
Work Date: 6/1/2012	Work Type: New O	Construction - Initial	Cod	e: NU-IN	Is Major	r M&R: True
Last Insp. Date: 5/8/2017 Conditions: PCI: 93	TotalSa	mples: 10	Surveyed:	2		
Inspection Comments:						
Sample Number: 146	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 94	1	
<b>Sample Comments:</b>						
57 WEATHERING	L	5000.00 SqFt				
Sample Number: 545	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 92	2	
<b>Sample Comments:</b>						
48 L & T CR	L	2.00 Ft				
57 WEATHERING	L	5000.00 SqFt				

Netw	ork: PMP			Na	me: POMPANO BE	ACH AIRPARK	
Bran	ch: RW 6-24		Name:	RUNWAY 6	5-24 Use:	RUNWAY	<b>Area:</b> 556,428 SqFt
Section	on: 6205	of 4	1	From: -		То: -	<b>Last Const.:</b> 1/1/1972
Surfa	ace: AAC	Family: C	9N59-GA	-RW-AAC- <b>Zo</b>	ne:	Category:	Rank: P
		A	PC				
Area	: 335,95	2 SqFt	Lengt	<b>h:</b> 2,875	Ft Width:	100 Ft	
Slabs	S:	Slab Length	ı:	Ft	Slab Width:	Ft	Joint Length: Ft
Shou	lder:	Street Type:	:		Grade: 0		Lanes: 0
Section	on Comments:						
Worl	k Date: 1/1/1972	Work	Type: Bl	UILT	(	Code: IMPORTED	Is Major M&R: True
Last	Insp. Date: 5/8/2017		Tota	alSamples: 68	Survey	<b>ed:</b> 15	
Cond	litions: PCI: 64						
Inspe	ection Comments:						
Samr	ple Number: 302	Type:	R	Area:	5000.00 SqFt	PCI: 66	
_	ole Comments:	71			1		
_			T	525 00 Tr			
48 52	L & T CR RAVELING		L L	535.00 Ft 500.00 SqFt			
57	WEATHERING		L	4500.00 SqFt			
Samp	ple Number: 306	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 65	
Samp	ple Comments:						
48	L & T CR		L	576.00 Ft			
52	RAVELING		L	250.00 SqFt			
57	WEATHERING		L	4750.00 SqFt			
_	ple Number: 309	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 65	
Samp	ple Comments:						
48	L & T CR		L	561.00 Ft			
52	RAVELING		L	250.00 SqFt			
57	WEATHERING	<b>TD</b>	L	4750.00 SqFt		DCI (F	
_	ple Number: 312	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 65	
Samp	ole Comments:						
48	L & T CR		L	377.00 Ft			
50 52	PATCHING RAVELING		L L	745.00 SqFt 210.00 SqFt			
57	WEATHERING		L	4045.00 SqFt			
Samp	ple Number: 316	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 60	
Samp	ple Comments:						
50	PATCHING		L	86.00 SqFt			
45	DEPRESSION		L	10.00 SqFt			
48	L & T CR		L	518.00 Ft			
52 57	RAVELING WEATHERING		L L	246.00 SqFt 4668.00 SqFt			
	ole Number: 323	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 67	
_	ple Comments:	ı ypc.	X.	Aitd.	5000.00 Bq1 t	101. 07	
48	L & T CR		L	506.00 Ft			
52	RAVELING		L	241.00 SqFt			
57	WEATHERING		L	4759.00 SqFt			
_	ple Number: 330	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 70	
Samp	ple Comments:						
48	L & T CR		L	394.00 Ft			
52 57	RAVELING		L	250.00 SqFt			
57	WEATHERING	/AT	L	4750.00 SqFt		DCY C	
_	ole Number: 337	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 65	
_	ole Comments:						E-19
48	L & T CR		L	497.00 Ft			

52	RAVELING		L	250.00 SqFt			
57	WEATHERING		L	4750.00 SqFt			
56	SWELLING		L	35.00 SqFt			
Samj	ple Number: 343	Type:	R	Area:	5000.00 SqFt	PCI: 65	
Samp	ple Comments:						
48	L & T CR		L	550.00 Ft			
52	RAVELING		L	250.00 SqFt			
57	WEATHERING		L	4750.00 SqFt			
Samj	ple Number: 346	Type:	R	Area:	6700.00 SqFt	PCI: 59	
Samp	ple Comments:						
48	L & T CR		L	843.00 Ft			
50	PATCHING		L	84.00 SqFt			
52	RAVELING		L	331.00 SqFt			
57	WEATHERING		L	6285.00 SqFt			
Samj	ple Number: 358	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 63	
Samp	ple Comments:						
48	L & T CR		L	440.00 Ft			
48	L & T CR		M	50.00 Ft			
52	RAVELING		L	250.00 SqFt			
57	WEATHERING		L	4750.00 SqFt			
Samp	ple Number: 362	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 68	
Samj	ple Comments:						
48	L & T CR		L	457.00 Ft			
52	RAVELING		L	250.00 SqFt			
57	WEATHERING		L	4750.00 SqFt			
Samp	ple Number: 370	Type:	R	Area:	5000.00 SqFt	PCI: 65	
Samp	ple Comments:						
48	L & T CR		L	561.00 Ft			
52	RAVELING		L	250.00 SqFt			
57	WEATHERING		L	4750.00 SqFt			
Samp	ple Number: 374	Type:	R	Area:	5000.00 SqFt	PCI: 62	
Samj	ple Comments:						
48	L & T CR		M	50.00 Ft			
48	L & T CR		L	493.00 Ft			
52	RAVELING		L	250.00 SqFt			
57	WEATHERING		L	4750.00 SqFt			
Samp	ple Number: 378	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 58	
Samj	ple Comments:						
43	BLOCK CR		L	900.00 SqFt			
48	L & T CR		L	480.00 Ft			
	RAVELING		L	2400.00 SqFt			
52 57	WEATHERING		L	2600.00 SqFt			

Netwo						Name:	POM		CH AIRPARK				
rancl				Name:		WAY 6-24		Use:	RUNWAY	Area:		556,428 SqFt	
ection	<b>n:</b> 6210		4		From:	-			То: -			Last Const.:	1/1/1972
Surfac	e: AAC	Family:	C9N5 APC	59-GA-I	RW-AAC-	Zone:			Category:			Rank: P	
rea:	167,9	76 SqFt		Length	:	6,100 Ft		Width:	25 Ft				
Slabs:		Slab Leng	gth:		Ft	Sla	nb Width:		Ft	J	oint Length	: F	t
Should	ler:	Street Ty	pe:			Gr	<b>rade:</b> 0			I	anes: 0		
Section	n Comments:												
Vork	<b>Date:</b> 1/1/1972	Wo	rk Ty	pe: BU	ILT			Co	ode: IMPORTEI	)	Is Major	M&R: True	
Last Iı	nsp. Date: 5/8/2017			Total	Samples:	34		Surveye	<b>d:</b> 7				
Condi	tions: PCI: 63												
nspec	tion Comments:												
	e Number: 104	Турс	n•	R		Area:	5000	00 SqFt	PCI:	65			
_	e Comments:	Type		1	1	ııca.	5000.	oo bqi t	101.	0.5			
_						_							
18 52	L & T CR RAVELING		L L		583.00 250.00								
12 17	WEATHERING		L		4750.00								
	e Number: 132	Тур		R		Area:	5000	00 SqFt	PCI:	67			
_	e Comments:	-JP	•		-		2000.	00 <b>541</b> 0	1011				
8	L & T CR		L		543.00	Ft							
52	RAVELING		L		100.00								
57	WEATHERING		L		4900.00								
_	e Number: 164 e Comments:	Тур	e:	R	1	Area:	5000.	00 SqFt	PCI:	70			
_					286.00	E.							
	L & T CR L & T CR		L M		50.00								
52	RAVELING		L		100.00								
7	WEATHERING		L		4900.00	SqFt							
Sampl	e Number: 512	Тур	e:	R	1	Area:	5000.	00 SqFt	PCI:	55			
Sampl	e Comments: Tie	e-in patch											
-8	L & T CR		L		238.00								
0	PATCHING		L		3600.00								
52 57	RAVELING WEATHERING		L L		1330.00	SqFt SqFt							
	e Number: 540	Тур		R		Area:	5000	00 SqFt	PCI:	61			
_	e Comments:	тур	••		1	arvu.	5000.	oo bqi t	101.	V1			
_			-		20± 0=	T:							
	L & T CR PATCHING		L L		602.00 960.00								
50 52	RAVELING		L			SqFt SqFt							
57	WEATHERING		L		3959.00	•							
Sampl	e Number: 556	Тур	e:	R	1	Area:	3325.	00 SqFt	PCI:	60			
Sampl	e Comments:												
	L & T CR		L		596.00								
52 57	RAVELING		L			SqFt SqFt							
57 '1	WEATHERING	783	L	P	3258.00		5005	00 C F	DOI	<u> </u>			
_	e Number: 576 e Comments:	Тур	e <b>:</b>	R	1	Area:	5025.	00 SqFt	PCI:	04			
.8	L & T CR		L		619.00	Ft							
2	RAVELING		L		151.00								
57	WEATHERING		L		4874.00								

Network:	PMP				Nai	me: PO	MPANO BE	ACH A	AIRPARK				
Branch:	RW 6-24		Nan	ne: RUI	NWAY 6	-24	Use:	RU	INWAY	Area:		556,428 SqFt	
Section:	6220	of	f 4	From:	-				To: -			Last Const	1/1/2012
Surface:	AAC	Family:	C9N59-0 APC	GA-RW-AAC-	Zoi	ne:			Category:			Rank: P	
Area:	35,00	00 SqFt	Lei	ngth:	350	Ft	Width:		100 Ft				
Slabs:		Slab Len	gth:	F	₹t	Slab Width:			Ft	Join	nt Length	:	Ft
Shoulder:		Street Ty	vpe:			Grade: 0				Lar	nes: 0		
Section Co	omments:												
Work Date	e: 1/1/1969	W	ork Type:	BUILT			(	Code:	IMPORTE	D	Is Major	M&R: True	
Work Date	e: 1/1/1972	W	ork Type:	OVERLAY			(	Code:	IMPORTE	D	Is Major	M&R: True	
Work Date	e: 1/1/2012	W	ork Type:	MILL and OV	/ERLAY		(	Code:	ML-OV		Is Major	M&R: True	
Last Insp.	<b>Date:</b> 5/8/2017		Т	otalSamples:	7		Survey	ved: 2	2				
Conditions	s: <b>PCI</b> : 94												
Inspection	<b>Comments:</b>												
Sample Nu	imber: 349	Тур	e: R	<u> </u>	Area:	500	0.00 SqFt		PCI:	94			
Sample Co	omments:												
57 WE	EATHERING		L	5000.0	00 SqFt								
Sample Nu	ımber: 354	Тур	e: R	<u> </u>	Area:	580	0.00 SqFt		PCI:	94			
Sample Co	omments:												

Network:	PMP				Name:	POMPANO BE	ACH AIRPA	ARK		
Branch:	RW 6-24		Name:	RUNW	AY 6-24	Use:	RUNWA	ΑY	Area:	556,428 SqFt
Section:	6225	O	f 4	From: 0	)		To:	1600		<b>Last Const.:</b> 1/1/2012
Surface:	AAC	Family:	C9N59-GA-R APC	W-AAC-	Zone:		Cate	gory:		Rank: P
Area:	17,50	00 SqFt	Length:		750 Ft	Width:		25 Ft		
Slabs:		Slab Len	gth:	Ft	Slab V	Width:	Ft		Joint Leng	gth: Ft
Shoulder:		Street Ty	ype:		Grade	e: 0			Lanes:	0
Section Co	omments:									
Work Dat	te: 1/1/1972	W	ork Type: New	Construction	n - Initial	(	Code: NU-	·IN	Is Ma	jor M&R: True
Work Dat	te: 1/1/2012	W	ork Type: MIL	L and OVER	RLAY	(	Code: ML-	-OV	Is Ma	jor M&R: True
Last Insp.	<b>Date:</b> 5/8/2017		Totals	Samples: 4	ļ	Survey	<b>ed:</b> 1			
Condition	s: <b>PCI</b> : 94									
Inspection	n Comments:									
Sample No	umber: 148	Тур	oe: R	A	rea:	4375.00 SqFt		PCI: 94		

57 WEATHERING L 4375.00 SqFt

PMP POMPANO BEACH AIRPARK Network: Name: **Branch:** TL AP SW Name: TAXILANE TO SW APRON Use: TAXILANE Area: 28,724 SqFt **Section:** 4505 of 1 From: **Last Const.:** 1/1/2004 To: Surface: ACFamily: C9N59-GA-TW-AC Zone: Category: Rank: P Width: Area: 28,724 SqFt Length: 550 Ft 50 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 **Shoulder:** Grade: Lanes: **Section Comments: Work Date:** 1/1/2004 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 8 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 3500.00 SqFt Sample Number: 103 R **PCI:** 88 Type: Area: **Sample Comments:** 

48 L & T CR L 64.00 Ft 57 WEATHERING L 3500.00 SqFt

Networ	k: PMP						Nan	•••	DOMD A	ANO BEA	CH AID	DADK						
Branch	: TL HA	ANG		Na	me:	TAXI	LANE T	O HANG	ARS	Use:	TAXII	LANE	Area:		18	0,871 S	qFt	
Section	: 4305		of	4	Fron	n:	-				To:	-				Last C	Const.:	12/25/1999
Surface	: AC	F	amily:	C9N59	-GA-TW-A	C	Zon	e:			Cat	tegory:				Rank:	P	
Area:		31,764 \$	SqFt	L	ength:		675 F	`t	W	idth:		25 Ft						
Slabs:		5	Slab Leng	gth:		Ft		Slab Wid	th:		Ft		Joi	nt Leng	th:		F	rt .
Should	er:	5	Street Ty	pe:				Grade:	0				La	nes:	0			
Section	<b>Comments:</b>																	
Work I	Date: 12/25/1	999	Wo	rk Type	e: New Con	structi	on - Init	ial		C	ode: NU	J-IN		Is Maj	or M	I&R: T	rue	
														Ū				
Last In	sp. Date: 5/8	8/2017			TotalSamp	oles:	7			Surveye	<b>d:</b> 1							
Last In	_				TotalSamp	oles:	7			Surveye	<b>d:</b> 1							
Conditi	_	39			TotalSamp	oles:	7			Surveye	<b>d:</b> 1							
Conditi	ions: PCI:	39 ts:	Туре	e:	TotalSamp		7 Area:		4845.00		<b>d:</b> 1	PCI: 39	)					
Condition Inspect Sample	ions: PCI:	39 ts:	Туре	e:					4845.00		<b>d:</b> 1	PCI: 39	)					
Condition Inspect Sample Sample	ions: PCI: ion Comment Number: 6 Comments:	39 ts:	Турс		R	F	Area:		4845.00		<b>d:</b> 1	PCI: 35	)					
Condition Inspect Sample Sample 43	ions: PCI: ion Comment Number: 6 Comments: BLOCK CR	39 501	Туре	L	R	A 816.00	<b>Area:</b> SqFt		4845.00		<b>d:</b> 1	PCI: 39	)					
Conditi Inspect Sample Sample 43 45	ions: PCI: ion Comment Number: 6 Comments:	39 501	Турс	L L	R	816.00 12.00	Area: SqFt SqFt		4845.00		<b>d:</b> 1	PCI: 39	)					
Conditi Inspect Sample Sample 43 45 50	ions: PCI: ion Comment Number: 6 Comments: BLOCK CR DEPRESSION	39 501	Туре	L	R	816.00 12.00 6.00	<b>Area:</b> SqFt		4845.00		<b>d:</b> 1	<b>PCI:</b> 39	)					
Conditi Inspect Sample Sample 43 45 50 50	ions: PCI: ion Comment Number: 6 Comments: BLOCK CR DEPRESSION PATCHING	39 501	Турс	L L L	R	816.00 12.00 6.00 16.00	SqFt SqFt SqFt SqFt SqFt		4845.00		<b>d:</b> 1	PCI: 39	)					
Conditi Inspect Sample Sample 43 45 50 50 50	ions: PCI: ion Comment Number: 6 Comments: BLOCK CR DEPRESSION PATCHING PATCHING	39 501	Турс	L L L M	R 48	816.00 12.00 6.00 16.00	SqFt SqFt SqFt SqFt SqFt SqFt		4845.00		<b>d:</b> 1	<b>PCI:</b> 39	)					
Conditi Inspect Sample Sample 43 45 50 50 50 50 52	ions: PCI: ion Comment Number: 6 Comments: BLOCK CR DEPRESSION PATCHING PATCHING PATCHING	39 501	Турс	L L L M H	R 48	816.00 12.00 6.00 16.00 7.00 009.00	SqFt SqFt SqFt SqFt SqFt SqFt		4845.00		<b>d:</b> 1	PCI: 35	)					

Network:	PMP			Nan	ne: POM	IPANO BEA	CH AIRPARK			
Branch:	TL HANG		Name:	TAXILANE T	O HANGARS	Use:	TAXILANE	Area:	180,871 SqFt	
Section:	4310	of 4	ļ <u>1</u>	From: -			То: -		Last Const.	: 12/25/1999
Surface:	AC	Family: C	9N59-GA-TV	W-AC Zon	e:		Category:		Rank: P	
Area:	49,38	7 SqFt	Length:	1,850 F	`t	Width:	25 Ft			
Slabs:		Slab Length	:	Ft	Slab Width:		Ft	Joint I	Length:	Ft
Shoulder:	:	Street Type:	:		<b>Grade:</b> 0			Lanes:	: 0	
Section Co	omments:									
Work Dat	te: 12/25/1999	Work	Type: New	Construction - Init	ial	C	ode: NU-IN	Is	Major M&R: True	
Last Insp.	. Date: 5/8/2017		TotalS	amples: 10		Surveye	<b>d:</b> 2			
Condition	ns: PCI: 30									
Inspection	n Comments:									
Sample N	umber: 402	Type:	R	Area:	6346	.00 SqFt	PCI:	33		
Sample Co	omments:									
43 BL	LOCK CR		L	4676.00 SqFt						
	EPRESSION		L	36.00 SqFt						
	ATCHING		L	1151.00 SqFt						
52 RA	AVELING		M	5195.00 SqFt						
Sample N	umber: 500	Type:	R	Area:	4375	.00 SqFt	PCI:	25		
Sample Co	omments:									
43 BL	LOCK CR		L	3922.00 SqFt						
45 DE	EPRESSION		L	109.00 SqFt						
48 L &	& T CR		L	14.00 Ft						
50 PA	ATCHING		M	69.00 SqFt						
52 RA	AVELING		M	4306.00 SqFt						

Netwo	ork: PMP			Nan	ne: POM	IPANO BEA	ACH AIRPARK			
Branc	h: TL HANG		Name:	TAXILANE T	O HANGARS	Use:	TAXILANE	Area:	180,871 SqFt	
Section	<b>n:</b> 4315	of 4	]	From: -			To: -		Last Const.	: 12/25/1999
Surfac	ce: AC	Family: C91	N59-GA-TV	W-AC Zone	e:		Category:		Rank: P	
Area:	83,68	7 SqFt	Length:	3,300 F	`t	Width:	25 Ft			
Slabs:		Slab Length:		Ft	Slab Width:		Ft	Joint L	ength:	Ft
Should	der:	Street Type:			Grade: 0			Lanes:	0	
Section	on Comments:									
Work	<b>Date:</b> 12/25/1999	Work T	Type: New	Construction - Init	ial	C	ode: NU-IN	Is l	Major M&R: True	
Last I	nsp. Date: 5/8/2017		TotalS	amples: 21		Survey	ed: 3			
Condi	itions: PCI: 48									
Inspec	ction Comments:									
Samul	le Number: 308	Type:	R	Area:	3449	.00 SqFt	PCI:	65		
_	le Comments:	Type.		11104.	2	ioo bqr t	1011			
-										
48	L & T CR		L	180.00 Ft						
50	PATCHING		L -	688.00 SqFt						
52	RAVELING		L	600.00 SqFt						
57	WEATHERING		L	2161.00 SqFt	4600	00 G E	DCI	12		
_	le Number: 602	Type:	R	Area:	4682	.00 SqFt	PCI:	43		
Sampi	le Comments:									
45	DEPRESSION		L	173.00 SqFt						
45	DEPRESSION		M	96.00 SqFt						
45	DEPRESSION		H	42.00 SqFt						
48	L & T CR		L	114.00 Ft						
52	RAVELING		L -	467.00 SqFt						
57	WEATHERING		L	4199.00 SqFt						
43	BLOCK CR		L L	680.00 SqFt						
50	PATCHING 700			16.00 SqFt	4000	00 G F	PCI:	40		
_	le Number: 700 le Comments:	Type:	R	Area:	4000	.00 SqFt	PCI:	40		
41	ALLIGATOR CR	,	т	28.00 SqFt						
41 43	ALLIGATOR CR BLOCK CR		L L	28.00 SqFt 3612.00 SqFt						
45	DEPRESSION		L L	72.00 SqFt						
50	PATCHING		L L	72.00 SqFt 85.00 SqFt						
50	PATCHING		L M	275.00 SqFt						
52	RAVELING		L	3640.00 SqFt						

Network	: PMP				Nam	e: PON	IPANO BEA	ACH AIRPARK				
Branch:	TL HANG		Name:	TAXIL	ANE T	O HANGARS	Use:	TAXILANE	Area:	18	80,871 SqFt	
Section:	4320	of	4	From: -				То: -			Last Const.:	12/25/1999
Surface:	APC	Family:	C9N59-GA-T APC	W-AAC-	Zone	:		Category:			Rank: P	
Area:	16	,033 SqFt	Length:		200 Ft		Width:	40 F	<sup>7</sup> t			
Slabs:		Slab Len	gth:	Ft		Slab Width:		Ft	Joint	t Length:	Ft	
Shoulder	::	Street Ty	pe:			Grade: 0			Lane	es: 0		
Section (	Comments:											
Work Da	ate: 1/1/1972	Wo	ork Type: New	v Constructio	n - Initia	al	C	Code: NU-IN	]	ls Major N	<b>¼R:</b> True	
Work Da	nte: 12/25/1999	Wo	ork Type: Ove	erlay - AC			C	Code: OL-AC	]	ls Major N	<b>∕⁄⁄&amp;R:</b> True	
Last Insp	<b>Date:</b> 5/8/20	17	Totals	Samples: 4	1		Surveye	ed: 1				
Conditio	ns: PCI: 3	8										
Inspectio	on Comments:											
Sample N	Number: 208	Тур	e: R	A	rea:	3500	0.00 SqFt	PCI:	38			
Sample (	Comments:											
42 B	LEEDING		N	24.00	SqFt							
47 J7	Γ REF. CR		M	375.00	-							
48 L	& T CR		L	55.00	Ft							
48 L	& T CR		M	90.00	Ft							
49 O	IL SPILLAGE		N	30.00	SqFt							
52 R	AVELING		L	700.00	SqFt							
57 W	EATHERING		L	2800.00	SqFt							

Network:	PMP				Nan	ne: POM	MPANO BEA	ACH A	AIRPARK				
Branch:	TW A		Na	me:	TAXIWAY A		Use:	TA	XIWAY	A	Area:	75,696 SqF	t
Section:	105	C	f 2	Fr	om: -				To: -			Last Con	st.: 11/1/2012
Surface:	AAC	Family:	DEFA	ULT	Zon	e:			Category:			Rank: I	•
Area:		61,729 SqFt	L	ength:	1,500 H	₹t	Width:		40 Ft	t			
Slabs:		Slab Le	ngth:		Ft	Slab Width:			Ft		Joint Leng	gth:	Ft
Shoulder:		Street T	ype:			Grade: 0					Lanes:	0	
Section Co	omments:												
Work Date	<b>e:</b> 1/1/1968	W	ork Typ	e: BUILT	1		C	Code:	IMPORTE	ED	Is Maj	or M&R: True	<b>.</b>
Work Date	<b>e:</b> 11/1/201	2 <b>W</b>	ork Typ	e: MILL a	and OVERLAY		C	Code:	ML-OV		Is Maj	or M&R: True	2
Last Insp.	<b>Date:</b> 5/8.	/2017		TotalSan	nples: 11		Survey	ed: 2	2				
Conditions	s: PCI:	93											
Inspection	Comments	s <b>:</b>											
Sample Nu	ımber: 10	)1 <b>Ty</b>	pe:	R	Area:	5000	0.00 SqFt		PCI:	92			
Sample Co	omments:												
48 L&	t T CR		L		2.00 Ft								
57 WE	EATHERING	G	L		5000.00 SqFt								
Sample Nu	ımber: 20	00 <b>Ty</b>	pe:	R	Area:	5000	0.00 SqFt		PCI:	94			
Sample Co	omments:												

WEATHERING

L 5000.00 SqFt

Network:	PMP				Name	e: PON	MPANO BEA	ACH AIRPAR	КK			
Branch:	TW A		Name:	TAXIV	VAY A		Use:	TAXIWAY	Y Area	1:	75,696 SqF	t
Section:	115	0	f 2	From:				То: -			Last Con	st.: 1/1/199
Surface:	AAC	Family:	C9N59-GA-7 APC	ΓW-AAC-	Zone	:		Catego	ry:		Rank: P	•
Area:		13,967 SqFt	Length	:	350 Ft		Width:	4	0 Ft			
Slabs:		Slab Len	igth:	Ft	:	Slab Width:		Ft		Joint Lengtl	ı:	Ft
Shoulder:	:	Street T	ype:		(	Grade: 0				Lanes:	)	
Section Co	omments:											
Work Dat	te: 1/1/1950	W	ork Type: OV	ERLAY			C	ode: IMPO	RTED	Is Majo	r M&R: True	;
Work Dat	te: 1/1/1997	W	ork Type: BU	ILT			C	ode: IMPO	RTED	Is Majo	r M&R: True	)
Last Insp.	. Date: 5/8/2	2017	Total	Samples:	3		Surveye	<b>d:</b> 1				
Condition	s: PCI:	53										
Inspection	n Comments:											
Sample N	umber: 106	Typ	pe: R	A	rea:	5399	0.00 SqFt	PO	CI: 53			
Sample Co	omments:											
43 BL	OCK CR		L	1075.00	SqFt							
45 DE	EPRESSION		L	132.00	SqFt							
48 L &	& T CR		L	621.00	Ft							
50 PA	TCHING		L	14.00	SqFt							
52 RA	AVELING		L	700.00	SqFt							
57 WI	EATHERING		L	4685.00	C. E.							

Network:	PMP			Nai	me: PON	IPANO BEA	CH AIRPARK			
Branch:	TW B		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	118,013 SqFt	
						Use:		Area:		
Section:	210	of		From: -			To: -		Last Const.:	1/1/1972
Surface:	AAC		S9N59-GA-T APC	W-AAC- Zor	ie:		Category:		Rank: T	
Area:	118,01	13 SqFt	Length:	2,600 1	Ft	Width:	50 Ft			
Slabs:		Slab Length	ı:	Ft	Slab Width:		Ft	Joint L	ength: Ft	
Shoulder:		Street Type	:		Grade: 0			Lanes:	0	
Section Co	omments:									
Work Date	<b>e:</b> 1/1/1972	Work	Type: BUI	LT		C	ode: IMPORTED	Is N	Major M&R: True	
Last Insp.	<b>Date:</b> 5/8/2017		Totals	Samples: 23		Surveye	ed: 3			
Condition	s: PCI: 64									
Inspection	Comments:									
Sample Nu	umber: 706	Type:	R	Area:	5000	0.00 SqFt	PCI:	54		
Sample Co	omments:									
48 L &	k T CR		L	624.00 Ft						
	VELING		L	750.00 SqFt						
57 WE	EATHERING		L	4250.00 SqFt						
Sample Nu	umber: 715	Type:	R	Area:	5000	0.00 SqFt	PCI: 6	57		
Sample Co	omments:									
18 L &	k T CR		L	483.00 Ft						
	VELING		L	545.00 SqFt						
57 WE	EATHERING		L	4455.00 SqFt						
Sample Nu	umber: 720	Type:	R	Area:	5000	0.00 SqFt	PCI: 6	51		
Sample Co	omments:									
48 L &	k T CR		L	771.00 Ft						
52 RA	VELING		L	487.00 SqFt						
52 RA	VELING		M	132.00 SqFt						

Network: PMP			Name: PO	OMPANO BEA	ACH AIRPARK			
Branch: TW C	Nan	ne: TAXIW	AY C	Use:	TAXIWAY	Area:	42,	,764 SqFt
Section: 305	of 3	From: -			То: -		I	<b>Last Const.:</b> 1/1/19
Surface: AC	Family: C9N59-	GA-TW-AC	Zone:		Category:		I	Rank: P
Area: 26	5,289 SqFt <b>Le</b>	ngth:	650 Ft	Width:	50 Ft			
Slabs:	Slab Length:	Ft	Slab Width	ı:	Ft	Joint	Length:	Ft
Shoulder:	Street Type:		Grade:	0		Lane	s: 0	
Section Comments:								
<b>Work Date:</b> 1/1/1970	Work Type:	: BUILT		C	ode: IMPORTE	D I	s Major M&	<b>kR:</b> True
Last Insp. Date: 5/8/20	)17	FotalSamples: 5		Surveye	ed: 2			
Last Insp. Date: 5/8/20		<b>FotalSamples:</b> 5		Surveye	ed: 2			
Conditions: PCI: 6	017 T	<b>ΓotalSamples:</b> 5		Surveye	e <b>d:</b> 2			
_	55	-						
Conditions: PCI: 6	55	FotalSamples: 5  R Are	<b>ea:</b> 61	Surveye	PCI:	63		
Conditions: PCI: 6 Inspection Comments:	55	-	<b>ea:</b> 61			63		
Conditions: PCI: 6 Inspection Comments: Sample Number: 300	55	R Arc				63		
Conditions: PCI: 6 Inspection Comments: Sample Number: 300 Sample Comments: 45 DEPRESSION	Type: I	-	SqFt			63		
Conditions: PCI: 6 Inspection Comments: Sample Number: 300 Sample Comments: 45 DEPRESSION	Type: I	R Are 266.00 S	5qFt <sup>2</sup> t			63		
Conditions: PCI: 6 Inspection Comments: Sample Number: 300 Sample Comments: 45 DEPRESSION 48 L & T CR	Type: I L L	266.00 S 562.00 F	SqFt et SqFt			63		
Conditions: PCI: 6 Inspection Comments: Sample Number: 300 Sample Comments: 45 DEPRESSION 48 L & T CR 52 RAVELING	Type: I  L  L  L  L  L	266.00 S 562.00 F 616.00 S	sqFt Et SqFt SqFt					
Conditions: PCI: 6 Inspection Comments: Sample Number: 300 Sample Comments: 45 DEPRESSION 48 L & T CR 52 RAVELING 57 WEATHERING	Type: I  L  L  L  L  L	266.00 S 562.00 F 616.00 S 5547.00 S	sqFt Et SqFt SqFt	63.00 SqFt	PCI:			
Conditions: PCI: 6 Inspection Comments:  Sample Number: 300 Sample Comments:  45 DEPRESSION 48 L & T CR 52 RAVELING 57 WEATHERING  Sample Number: 303	Type: I L L L L Type: I	266.00 S 562.00 F 616.00 S 5547.00 S	6qFt Ft 6qFt 6qFt <b>ea:</b> 50	63.00 SqFt	PCI:			
Conditions: PCI: 6 Inspection Comments:  Sample Number: 300 Sample Comments:  45 DEPRESSION 48 L & T CR 52 RAVELING 57 WEATHERING  Sample Number: 303 Sample Comments:	Type: I  L  L  L  L  L	266.00 S 562.00 F 616.00 S 5547.00 S	SqFt Et SqFt SqFt <b>ea:</b> 50	63.00 SqFt	PCI:			

POMPANO BEACH AIRPARK PMP Network: Name: **Branch:** TW C TAXIWAY C Use: TAXIWAY Area: 42,764 SqFt Name: **Section:** 350 of 3 **Last Const.:** 11/1/2012 From: To: Surface: AAC Family: DEFAULT Zone: Category: Rank: P Area: 6,807 SqFt Length: 212 Ft Width: 40 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft 0 **Shoulder: Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1970 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Work Date:** 11/1/2012 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 5/8/2017 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 6807.00 SqFt Sample Number: 308 Type: R Area: **PCI:** 94

**Sample Comments:** 

57 WEATHERING L 6807.00 SqFt

POMPANO BEACH AIRPARK PMP Network: Name: **Branch:** TW C TAXIWAY C Use: TAXIWAY Area: 42,764 SqFt Name: **Section:** 360 of 3 **Last Const.:** 11/1/2012 From: To: Surface: AAC Family: DEFAULT Zone: Category: Rank: P Area: 9,668 SqFt Length: 132 Ft Width: 40 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft 0 **Shoulder: Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1968 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Work Date:** 11/1/2012 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 306 Type: R Area: 5073.00 SqFt **PCI:** 94

**Sample Comments:** 

57 WEATHERING L 5073.00 SqFt

Netw	ork: PMP			Nan	ne: POMPANO BE	ACH AIRPARK		
Bran	ch: TW D		Name:	TAXIWAY D	Use:	TAXIWAY	Area:	214,417 SqFt
Secti	on: 405	of	5	From: -		То: -		Last Const.: 1/1/1972
Surfa	ace: AAC		C9N59-GA-T APC	ΓW-AAC- <b>Zon</b>	e:	Category:		Rank: P
Area	: 105,60	07 SqFt	Length	: 2,100 H	Ft Width:	50 Ft		
Slabs	s <b>:</b>	Slab Lengtl	h:	Ft	Slab Width:	Ft	Joint Le	ngth: Ft
Shou	lder:	Street Type	<b>:</b>		Grade: 0		Lanes:	0
Secti	on Comments:							
Worl	k Date: 1/1/1972	Work	<b>Type:</b> BU	ILT	(	Code: IMPORTED	Is M	ajor M&R: True
Last	Insp. Date: 5/8/2017		Total	Samples: 20	Survey	ed: 3		
Cond	litions: PCI: 63							
Inspe	ection Comments:							
Samı	ple Number: 404	Type:	R	Area:	5000.00 SqFt	PCI: 65		
Samp	ple Comments:							
48	L & T CR		L	410.00 Ft				
48	L & T CR		M	5.00 Ft				
52	RAVELING		L	500.00 SqFt				
57	WEATHERING		L	4500.00 SqFt				
Samp	ple Number: 413	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 59		
Samp	ple Comments:							
48	L & T CR		L	595.00 Ft				
52	RAVELING		L	350.00 SqFt				
53	RUTTING		L	132.00 SqFt				
57	WEATHERING		L	4650.00 SqFt				
Samp	ple Number: 420	Type:	R	Area:	5000.00 SqFt	PCI: 65		
Samp	ple Comments:							
48	L & T CR		L	565.00 Ft				
52	RAVELING		L	1000.00 SqFt				
57	WEATHERING		L	4000.00 SqFt				

Network: Pl	MP			Na	me: PO	MPANO BEA	CH AIRPARK		
Branch: T	W D		Name:	TAXIWAY	D	Use:	TAXIWAY	Area:	214,417 SqFt
Section: 410		of	5 <b>F</b>	rom: -			То: -		<b>Last Const.:</b> 1/1/2008
Surface: AAC		•	C9N59-GA-TV APC	V-AAC- <b>Zo</b>	ne:		Category:		Rank: P
Area:	13,07	2 SqFt	Length:	275	Ft	Width:	50 Ft		
Slabs:		Slab Leng	th:	Ft	Slab Width:		Ft	Joint L	ength: Ft
Shoulder:		Street Typ	e:		Grade: 0	)		Lanes:	0
Section Comme	nts:								
Work Date: 1/1	1/1972	Woı	k Type: BUIL	Т		Co	ode: IMPORTED	Is N	Major M&R: True
Work Date: 1/1	1/2008	Woı	k Type: MILI	and OVERLAY	•	Co	ode: ML-OV	Is N	Major M&R: True
Last Insp. Date:	5/8/2017		TotalSa	amples: 3		Surveye	<b>d:</b> 1		
Conditions: I	PCI: 66								
Inspection Com	ments:								
Sample Number	r: 425	Туре	: R	Area:	548	35.00 SqFt	PCI: 66		
Sample Comme		- <del>-</del>							
45 DEPRES	SION		L	323.00 SqFt					
48 L & T CF	R		L	12.00 Ft					

549.00 SqFt 4936.00 SqFt

L L

52 57 RAVELING WEATHERING

Network:	PMP				Nai	me: PON	MPANO BEA	CH AIRPARK			
Branch:	TW D			Name:	TAXIWAY I	)	Use:	TAXIWAY	Area:	214,	417 SqFt
Section:	415		of 5		From: -			То: -		1	Last Const.: 11/1/20
Surface:	AAC	Family	: DE	EFAULT	Zoi	ne:		Category:		1	Rank: P
Area:		36,063 SqFt		Length:	400	Ft	Width:	50 Ft			
Slabs:		Slab I	ength:		Ft	Slab Width:		Ft	Join	nt Length:	Ft
Shoulder:		Street	Type:			Grade: 0			Lar	nes: 0	
Section Co	mments:										
Work Date	e: 1/1/1972		Work 7	Type: BUI	ILT		C	ode: IMPORTE	D	Is Major M&	<b>R:</b> True
Work Date	e: 11/1/201	2	Work '	Type: MII	L and OVERLAY		C	ode: ML-OV		Is Major M&	<b>₹R:</b> True
Last Insp.	<b>Date:</b> 5/8/	/2017 84		Totals	Samples: 9		Surveye	<b>d:</b> 2			
	Comments										
Sample Nu	imber: 42	9 1	Гуре:	R	Area:	4431	.00 SqFt	PCI:	87		
48 L &	t T CR			L	2.00 Ft						
50 PA	TCHING			L	76.00 SqFt						
57 WE	EATHERING	j.		L	4355.00 SqFt						
	ımbarı 53	1 7	Гуре:	R	Area:	4088	3.00 SqFt	PCI:	81		
Sample Nu	iiiibei. 33										
Sample Nu Sample Co											
Sample Co				L	392.00 SqFt						

Network:	PMP					Nam	ne: PO	MPANO BEA	ACH A	IRPARK		
Branch:	TW D			Name	TAX	XIWAY D		Use:	TA	XIWAY	Area:	214,417 SqFt
Section:	420		of	f 5	From:	-			7	Го: -		<b>Last Const.:</b> 1/1/2008
Surface:	AAC		Family:	C9N59-GA APC	-TW-AAC-	Zone	e:		(	Category:		Rank: P
Area:		23,098	3 SqFt	Leng	th:	2,415 F	't	Width:		50 Ft		
Slabs:			Slab Len	gth:	F	't	Slab Width:		I	₹t	Join	nt Length: Ft
Shoulder:			Street Ty	ype:			Grade: 0				Lar	nes: 0
Section Co	omments:											
Work Date	e: 1/1/1972	2	W	ork Type: N	lew Construc	tion - Initi	al	C	ode:	NU-IN		Is Major M&R: True
Work Date	e: 1/1/2008	8	W	ork Type: N	IILL and OV	ERLAY		C	ode:	ML-OV		Is Major M&R: True
Last Insp.	<b>Date:</b> 5/8	3/2017		Tot	alSamples:	4		Surveye	e <b>d:</b> 1			
Conditions	s: PCI:	74										
Inspection	Comment	s:										
Sample Nu	umber: 4	17	Тур	e: R		Area:	500	0.00 SqFt		PCI: 7	4	
Sample Co	omments:											

57

L & T CR

WEATHERING

L L 412.00 Ft 5000.00 SqFt

PMP POMPANO BEACH AIRPARK Network: Name: **Branch:** TW D Name: TAXIWAY D Use: TAXIWAY Area: 214,417 SqFt Section: 425 of 5 From: To: **Last Const.:** 6/1/2012 Surface: ACFamily: DEFAULT Zone: Category: Rank: P Area: 36,577 SqFt Length: 1,000 Ft Width: 35 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 Lanes: **Shoulder:** Grade: **Section Comments: Work Date:** 6/1/2012 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 10 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 3500.00 SqFt Sample Number: 109 R **PCI:** 94 Type: Area: **Sample Comments:** 

57

WEATHERING

L

POMPANO BEACH AIRPARK PMP Network: Name: 12,246 SqFt **Branch:** TW E TAXIWAY E Use: TAXIWAY Area: Name: **Section:** 505 of 1 **Last Const.:** 1/1/2012 From: To: Surface: AAC Family: DEFAULT Zone: Category: Rank: P Area: 12,246 SqFt Length: 200 Ft Width: 40 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft 0 **Shoulder: Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1968 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2012 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 500 Type: R Area: 4537.00 SqFt **PCI:** 89 **Sample Comments:** 

L & T CR

WEATHERING

48

57

L

L

40.00 Ft

Network: PMP		Name:	POMPANO BEA	CH AIRPARK		
Branch: TW F	Nam		Use:		Area: 151	,614 SqFt
			Use.			
Section: 610	of 3	From: -		То: -		<b>Last Const.:</b> 1/1/1972
Surface: AAC	Family: C9N59-C APC	A-TW-AAC- Zone:		Category:		Rank: P
Area: 117,89	93 SqFt Ler	<b>gth:</b> 2,500 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft Sla	b Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:	Gr	ade: 0		Lanes: 0	
Section Comments:						
<b>Work Date:</b> 1/1/1972	Work Type:	BUILT	C	ode: IMPORTED	Is Major M&	&R: True
<b>Last Insp. Date:</b> 5/8/2017	T	otalSamples: 24	Surveye	<b>d:</b> 3		
Conditions: PCI: 64						
Inspection Comments:						
Sample Number: 601	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 61		
Sample Comments:			-			
40 I 0 F CD	L	374.00 Ft				
48 L & T CR	L					
	M	20.00 Ft				
		20.00 Ft 175.00 SqFt				
48 L & T CR	M	20.00 Ft 175.00 SqFt 400.00 SqFt				
48 L & T CR 50 PATCHING	M L	20.00 Ft 175.00 SqFt				
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING	M L L	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt	5000.00 SqFt	PCI: 65		
48 L & T CR 50 PATCHING 52 RAVELING	M L L L	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt	5000.00 SqFt	<b>PCI:</b> 65		
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING  Sample Number: 609  Sample Comments:	M L L L Type: R	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt  Area:	5000.00 SqFt	PCI: 65		
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING  Sample Number: 609  Sample Comments: 48 L & T CR	M L L L Type: R	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt  Area:	5000.00 SqFt	PCI: 65		
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING  Sample Number: 609  Sample Comments: 48 L & T CR	M L L L Type: R	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt  Area:  555.00 Ft 400.00 SqFt	5000.00 SqFt	PCI: 65		
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING  Sample Number: 609  Sample Comments: 48 L & T CR 52 RAVELING	M L L L L L L L L L L L L L L L L L L L	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt  Area:  555.00 Ft 400.00 SqFt 4600.00 SqFt	5000.00 SqFt 5000.00 SqFt	PCI: 65		
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING  Sample Number: 609  Sample Comments: 48 L & T CR 52 RAVELING 57 WEATHERING	M L L L L L L L L L	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt  Area:  555.00 Ft 400.00 SqFt 4600.00 SqFt				
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING  Sample Number: 609  Sample Comments: 48 L & T CR 52 RAVELING 57 WEATHERING  Sample Number: 625	M L L L L L L L L L	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt  Area:  555.00 Ft 400.00 SqFt 4600.00 SqFt				
48 L & T CR 50 PATCHING 52 RAVELING 57 WEATHERING  Sample Number: 609  Sample Comments: 48 L & T CR 52 RAVELING 57 WEATHERING  Sample Number: 625  Sample Comments:	M L L L L L L L R R	20.00 Ft 175.00 SqFt 400.00 SqFt 4425.00 SqFt  Area:  555.00 Ft 400.00 SqFt 4600.00 SqFt  Area:				

Network:	PMP			Nam	e: POM	IPANO BEA	CH AIRPARK		
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	151,614 SqFt
Section:	612	0	f 3	From: -			То: -		Last Const.: 1/1/2008
Surface:	AAC	Family:	C9N59-GA-TY APC	W-AAC- Zone	e <b>:</b>		Category:		Rank: P
Area:		15,543 SqFt	Length:	2,500 F	t	Width:	50 Ft		
Slabs:		Slab Lei	ngth:	Ft	Slab Width:		Ft	Joint Len	gth: Ft
Shoulder:		Street T	ype:		Grade: 0			Lanes:	0
Section Co	mments:								
Work Date	e: 1/1/1972	2 <b>W</b>	ork Type: New	Construction - Initi	al	C	ode: NU-IN	Is Ma	jor M&R: True
Work Date	e: 1/1/2008	8 W	ork Type: MIL	L and OVERLAY		C	ode: ML-OV	Is Ma	jor M&R: True
Last Insp.	<b>Date:</b> 5/8	3/2017	TotalS	amples: 3		Surveye	<b>d:</b> 1		
Conditions	s: PCI:	83							
Inspection	Comments	s:							
Sample Nu	ımber: 61	16 <b>Ty</b> ]	pe: R	Area:	6575	.00 SqFt	PCI: 83	3	
Sample Co	omments:								
48 I.&	T CR		L	74.00 Ft					

Network:	PMP			·	Name	e: POI	MPANO BEA	ACH A	AIRPARK				
Branch:	TW F		Name:	TAXIW	VAY F		Use:	TA	XIWAY	Area:	151,614	SqFt	
Section:	615	O	f 3	From: -				1	To: -		Last	Const.	: 1/1/2012
Surface:	AAC	Family:	DEFAULT		Zone	:			Category:		Ran	<b>k:</b> P	
Area:		18,178 SqFt	Lengtl	ı:	264 Ft		Width:		50 Ft				
Slabs:		Slab Len	gth:	Ft		Slab Width:			Ft	Joint Leng	gth:	]	₹t
Shoulder:		Street Ty	ype:			Grade: 0				Lanes:	0		
Section Co	mments:												
Work Date	: 1/1/1969	W	ork Type: BU	JILT			C	ode:	IMPORTED	Is Maj	jor M&R:	True	
Work Date	: 1/1/1972	W	ork Type: O	VERLAY			C	ode:	IMPORTED	Is Maj	jor M&R:	True	
Work Date	: 1/1/2012	W	ork Type: M	ILL and OVER	RLAY		C	ode:	ML-OV	Is Maj	jor M&R:	True	
Last Insp. l	Date: 5/8/2	2017	Tota	lSamples: 4	ļ.		Surveye	ed: 1					
Conditions	: PCI:	89											
Inspection	Comments:												
Sample Nu	<b>mber:</b> 612	2 Typ	pe: R	A	rea:	450	0.00 SqFt		<b>PCI:</b> 89				
Sample Co	mments:												
48 L&	T CR		L	50.00	Ft								

WEATHERING

L

PMP POMPANO BEACH AIRPARK Network: Name: **Branch:** TW G Name: TAXIWAY G Use: TAXIWAY Area: 32,856 SqFt Section: 710 of 2 From: To: **Last Const.:** 6/1/2012 Surface: ACFamily: DEFAULT Zone: Category: Rank: P Area: 15,387 SqFt Length: 260 Ft Width: 55 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 Lanes: **Shoulder:** Grade: **Section Comments: Work Date:** 6/1/2012 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 4306.00 SqFt Sample Number: 251 R **PCI:** 96 Type: Area:

**Sample Comments:** 

5.00 SqFt 52 RAVELING M

PMP POMPANO BEACH AIRPARK Network: Name: **Branch:** TW G Name: TAXIWAY G Use: TAXIWAY Area: 32,856 SqFt Section: 715 of 2 From: To: **Last Const.:** 6/1/2014 Surface: ACFamily: C9N59-GA-TW-AC Zone: Category: Rank: P 350 Ft Area: 17,469 SqFt Length: Width: 50 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 Lanes: **Shoulder:** Grade: **Section Comments: Work Date:** 6/1/2014 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 147 R 5534.00 SqFt **PCI:** 94 Type: Area:

**Sample Comments:** 

57 WEATHERING L 5534.00 SqFt

Branch:	TW K			Name:	TAXIWAY I	X.	Use:	TAXIWAY	Area:	110,731 SqFt
Section:	1110	0	f 3	F	rom: -			То: -		<b>Last Const.:</b> 11/1/2012
Surface:	AC	Family:	DEF	AULT	Zor	ne:		Category:		Rank: P
Area:		89,261 SqFt		Length:	2,500 1	Ft	Width:	35 Ft		
Slabs:		Slab Ler	ngth:		Ft	Slab Width:		Ft	Joint I	Length: Ft
Shoulder:		Street T	ype:			Grade: 0			Lanes:	: 0
Section Co	omments:									
Work Dat	<b>e:</b> 11/1/201	12 <b>W</b>	ork T	ype: New	Construction - Ini	tial	C	ode: NU-IN	Is	Major M&R: True
Last Insp.	<b>Date:</b> 5/8	3/2017		TotalSa	amples: 25		Surveye	ed: 3		
Condition	s: PCI:	94								
Inspection	Comment	s:								
Sample Nu	umber: 10	02 <b>Ty</b> J	pe:	R	Area:	3772	2.00 SqFt	PCI:	94	
Sample Co	omments:									
57 WE	EATHERIN	G	L	,	3772.00 SqFt					
Sample Nu	umber: 1	13 <b>Ty</b> J	pe:	R	Area:	3500	0.00 SqFt	PCI:	94	
Sample Co	omments:									
57 WE	EATHERIN	G	L	,	3500.00 SqFt					
Sample Nu	umber: 12	21 <b>Ty</b> J	pe:	R	Area:	3500	0.00 SqFt	PCI:	94	
Sample Co	omments:									
57 WE	EATHERIN	G	L	,	3500.00 SqFt					

Name:

POMPANO BEACH AIRPARK

PMP

Network:

PMP POMPANO BEACH AIRPARK Network: Name: **Branch:** TW K Name: TAXIWAY K Use: TAXIWAY Area: 110,731 SqFt Section: 1115 of 3 From: To: **Last Const.:** 6/1/2014 Surface: ACFamily: C9N59-GA-TW-AC Zone: Category: Rank: P Area: 7,373 SqFt Length: 150 Ft Width: 50 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 Lanes: 0 **Shoulder:** Grade: **Section Comments: Work Date:** 6/1/2014 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 3629.00 SqFt Sample Number: 128 Type: R **PCI:** 92 Area: **Sample Comments:** 3.00 Ft 48 L & T CR L

57

WEATHERING

L

PMP POMPANO BEACH AIRPARK Network: Name: **Branch:** TW K Name: TAXIWAY K Use: TAXIWAY Area: 110,731 SqFt Section: 1120 of 3 **Last Const.:** 6/1/2012 From: To: Surface: ACFamily: C9N59-GA-TW-AC Zone: Category: Rank: P Area: 14,097 SqFt Length: 280 Ft Width: 50 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 0 **Shoulder:** Grade: Lanes: **Section Comments: Work Date:** 6/1/2012 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 5859.00 SqFt Sample Number: 131 R **PCI:** 92 Type: Area: **Sample Comments:** 

5.00 Ft 48 L & T CR L 57 WEATHERING L 5859.00 SqFt

Network:	PMP	<del></del>			Nar	ne: PO	MPANO BEA	ACH AIRPARK			
Branch:	TW L		Name:	TAXI	WAY I		Use:	TAXIWAY	Area:	201,930 SqFt	
Section:	1202	O	f 4	From:	-			То: -		Last Const	1/1/1996
Surface:	AAC	Family:	C9N59-GA- APC	TW-AAC-	Zor	ne:		Category:		Rank: P	
Area:	21,	209 SqFt	Lengtl	ı:	290 1	Ft	Width:	75 F	₹t		
Slabs:		Slab Len	gth:	Ft		Slab Width:		Ft	Join	nt Length:	Ft
Shoulder:		Street Ty	ype:			Grade: 0			Lar	nes: 0	
Section Co	mments:										
Work Date	e: 1/1/1950	W	ork Type: BU	JILT			C	dode: IMPORT	ED	Is Major M&R: True	
Work Date	e: 1/1/1996	W	ork Type: M	ILL and OVE	RLAY		C	dode: ML-OV		Is Major M&R: True	
Last Insp.	<b>Date:</b> 5/8/201	7	Tota	lSamples:	4		Surveye	ed: 1			
Conditions	s: <b>PCI</b> : 67	7									
Inspection	<b>Comments:</b>										
Sample Nu	ımber: 102	Тур	pe: R	A	\rea:	502	4.00 SqFt	PCI:	67		
Sample Co	omments:										
48 L&	T CR		L	343.00	Ft						
52 RA	VELING		L	484.00	SqFt						
52 RA	VELING		M	180.00	SqFt						
56 SW	ELLING		L	106.00	SqFt						

Network: PMP		Name:	POMPANO BEA	ACH AIRPARK		
Branch: TW L	Name	: TAXIWAY L	Use:	TAXIWAY	Area:	201,930 SqFt
Section: 1205	of 4	From: -		То: -		Last Const.: 1/1/1972
Surface: AC	Family: C9N59-G	A-TW-AC Zone:		Category:		Rank: P
Area: 13	3,025 SqFt Leng	<b>9th:</b> 260 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft Sl	ab Width:	Ft	Joint Leng	th: Ft
Shoulder:	Street Type:	$\mathbf{G}$	rade: 0		Lanes:	0
Section Comments:						
Work Date: 1/1/1972	Work Type:	New Construction - AC	C	Code: NC-AC	Is Maj	or M&R: True
Last Insp. Date: 5/8/20	17 <b>T</b> c	talSamples: 3	Surveye	e <b>d:</b> 1		
Conditions: PCI: 5	55					
<b>Inspection Comments:</b>						
Sample Number: 113	Type: R	Area:	3750.00 SqFt	PCI: 55	5	
Sample Comments:						
	L	412.00 Ft				
48 L & T CR						
	M	50.00 Ft				
48 L & T CR		50.00 Ft 231.00 SqFt				
48 L & T CR	M					

Network: PMP			Nan	ne: PO	MPANO BE.	ACH AIRPARK					
Branch: TW L	I	Name:	TAXIWAY L	,	Use:	TAXIWAY	Are	a:	201,930 Sc	<sub>l</sub> Ft	
Section: 1210	of 4	I	From: -			То: -			Last Co	onst.: 1/1	/1996
Surface: AAC	Family: C9N APC	59-GA-TV	W-AAC- Zon	ie:		Category:			Rank:	P	
Area: 152,	867 SqFt	Length:	2,550 H	₹t	Width:	60 F	₹t				
Slabs:	Slab Length:		Ft	Slab Width:		Ft		Joint Lengt	th:	Ft	
Shoulder:	Street Type:			Grade: 0	)			Lanes:	0		
Section Comments:											
Work Date: 1/1/1950	Work Ty	v <b>pe:</b> BUIL	LT .		(	Code: IMPORT	ED	Is Majo	or M&R: Ti	rue	
Work Date: 1/1/1996	Work Ty	vpe: MILI	L and OVERLAY		(	Code: ML-OV		Is Majo	or M&R: Ti	rue	
Last Insp. Date: 5/8/201	7	TotalSa	amples: 26		Survey	<b>ed:</b> 3					
G WI DOT	_										
Conditions: PCI: 65	5										
Inspection Comments:	5										
<b>Inspection Comments:</b>	Type:	R	Area:	600	00.00 SqFt	PCI:	68				
		R	Area:	600	00.00 SqFt	PCI:	68				
Inspection Comments: Sample Number: 211			Area: 560.00 Ft	600	00.00 SqFt	PCI:	68				
Inspection Comments: Sample Number: 211 Sample Comments: 48 L & T CR	Type:			600	00.00 SqFt	PCI:	68				
Inspection Comments: Sample Number: 211 Sample Comments: 48 L & T CR	Type:		560.00 Ft	600	00.00 SqFt	PCI:	68				
Sample Number: 211 Sample Comments:  48 L & T CR 52 RAVELING 57 WEATHERING	Type: L L		560.00 Ft 866.00 SqFt		00.00 SqFt	PCI:					
Sample Number: 211 Sample Comments:  48 L & T CR 52 RAVELING 57 WEATHERING Sample Number: 216	Type: L L L		560.00 Ft 866.00 SqFt 5134.00 SqFt								
Sample Number: 211 Sample Comments:  48 L & T CR 52 RAVELING 57 WEATHERING Sample Number: 216 Sample Comments:	Type: L L L	R	560.00 Ft 866.00 SqFt 5134.00 SqFt								
Sample Number: 211 Sample Comments:  48  L & T CR 52  RAVELING 57  WEATHERING Sample Number: 216 Sample Comments:  48  L & T CR	Type:  L L L Type:	R	560.00 Ft 866.00 SqFt 5134.00 SqFt **X*rea:** 494.00 Ft 1000.00 SqFt								
Sample Number: 211 Sample Comments:  48   L & T CR 52   RAVELING 57   WEATHERING  Sample Number: 216 Sample Comments:  48   L & T CR	Type:  L L L Type:	R	560.00 Ft 866.00 SqFt 5134.00 SqFt  Area:  494.00 Ft 1000.00 SqFt 1500.00 SqFt								
Sample Number: 211 Sample Comments:  48  L & T CR 52  RAVELING 57  WEATHERING  Sample Number: 216 Sample Comments:  48  L & T CR 50  PATCHING 52  RAVELING	Type:  L L L Type:	R	560.00 Ft 866.00 SqFt 5134.00 SqFt **X*rea:** 494.00 Ft 1000.00 SqFt								
Inspection Comments:  Sample Number: 211 Sample Comments:  48    L & T CR 52    RAVELING 57    WEATHERING  Sample Number: 216 Sample Comments:  48    L & T CR 50    PATCHING 52    RAVELING 57    WEATHERING	Type:  L L L Type:	R	560.00 Ft 866.00 SqFt 5134.00 SqFt  Area:  494.00 Ft 1000.00 SqFt 1500.00 SqFt	600			64				
Sample Number: 211 Sample Comments:  48  L & T CR 52  RAVELING 57  WEATHERING  Sample Number: 216 Sample Comments:  48  L & T CR 50  PATCHING 52  RAVELING	Type:  L L Type:  L L L L L L L L L L L L L L L L L L	R	560.00 Ft 866.00 SqFt 5134.00 SqFt  Area:  494.00 Ft 1000.00 SqFt 1500.00 SqFt 3500.00 SqFt	600	00.00 SqFt	PCI:	64				
Sample Number: 211 Sample Comments:  48   L & T CR 52   RAVELING 57   WEATHERING  Sample Number: 216 Sample Comments:  48   L & T CR 50   PATCHING 52   RAVELING 57   WEATHERING  58   PATCHING 59   PATCHING 50   PATCHING 51   PATCHING 52   RAVELING 53   WEATHERING 54   WEATHERING 55   WEATHERING 56   PATCHING 57   WEATHERING	Type:  L L Type:  L L L L L L L L L L L L L L L L L L	R	560.00 Ft 866.00 SqFt 5134.00 SqFt  Area:  494.00 Ft 1000.00 SqFt 1500.00 SqFt 3500.00 SqFt	600	00.00 SqFt	PCI:	64				
Inspection Comments:  Sample Number: 211  Sample Comments:  48    L & T CR 52    RAVELING 57    WEATHERING  Sample Number: 216  Sample Comments:  48    L & T CR 50    PATCHING 52    RAVELING 54    WEATHERING  Sample Number: 222  Sample Comments:	Type:  L L Type:  L L L L Type:	R	560.00 Ft 866.00 SqFt 5134.00 SqFt  Area:  494.00 Ft 1000.00 SqFt 1500.00 SqFt 3500.00 SqFt Area:	600	00.00 SqFt	PCI:	64				

Network:	PMP					Nan	ne: PO	MPANO BE.	ACH AIF	RPARK					
Branch:	TW L		N	lame:	TAXIV	VAY L		Use:	TAXI	WAY	Ar	·ea:	201,	930 SqFt	
Section:	1215	(	of 4	Fr	om: -				To	: -			I	ast Cons	t.: 6/1/2012
Surface:	AAC	Family:	DEF	AULT		Zon	e:		Ca	tegory:			F	ank: P	
Area:		14,829 SqFt		Length:		250 F	řt.	Width:		60 F	t				
Slabs:		Slab Le	ngth:		Ft		Slab Width:		Ft			Joint Len	gth:		Ft
Shoulder:		Street T	ype:				Grade: 0	)				Lanes:	0		
Section Co	omments:														
Work Dat	e: 1/1/1950	) <b>W</b>	ork Ty	pe: New C	Construction	n - Initi	ial	(	Code: N	U-IN		Is Ma	jor M&	R: True	
Work Dat	e: 6/1/2012	2 <b>W</b>	ork Ty	pe: MILL	and OVER	RLAY		(	Code: N	IL-OV		Is Ma	jor M&	R: True	
Last Insp.	<b>Date:</b> 5/8	3/2017		TotalSa	mples: 3	3		Survey	<b>ed:</b> 1						
Condition	s: PCI:	88													
Inspection	Comments	s:													
Sample Ni	ımber: 23	33 <b>Ty</b>	pe:	R	A	rea:	620	07.00 SqFt		PCI:	88				
Sample Co	omments:														
48 L &	t T CR		L		3.00	Ft									
	VELING		L		100.00										
57 WE	EATHERIN	G	L		6107.00	SqFt									

Network:	PMP			Nai	ne: POMPANO B	EACH AIRPARK		
Branch:	TW M		Name:	TAXIWAY N	M Use	: TAXIWAY	Area:	209,916 SqFt
Section:	1305	0	f 6	From: -		То: -		<b>Last Const.:</b> 1/1/1970
Surface:	AC	Family:	C9N59-GA	-TW-AC Zoi	ne:	Category:		Rank: P
Area:		27,738 SqFt	Lengt	<b>h:</b> 884 1	Ft Width:	50 Ft		
Slabs:		Slab Len	igth:	Ft	Slab Width:	Ft	Joint Len	gth: Ft
Shoulder:		Street T	ype:		Grade: 0		Lanes:	0
Section Co	omments:							
Work Dat	e: 1/1/1970	) W	ork Type: Bl	UILT		Code: IMPORTED	Is Ma	jor M&R: True
Last Insp.	<b>Date:</b> 5/8	/2017	Tota	alSamples: 6	Surve	yed: 1		
Condition	s: PCI:	69						
Inspection	Comments	s <b>:</b>						
Sample N	umber: 10	)4 <b>Ty</b> ]	pe: R	Area:	4000.00 SqFt	PCI: 6	59	
Sample Co	omments:							
48 L &	& T CR		L	344.00 Ft				
52 RA	VELING		L	1600.00 SqFt				
57 WI	EATHERIN	G	L	2400.00 SqFt				

Network: PMP		Name:	POMPANO BEA	ACH AIRPARK		
Branch: TW M	Name	: TAXIWAY M	Use:	TAXIWAY	Area:	209,916 SqFt
Section: 1306	of 6	From: -		То: -		Last Const.: 11/1/2012
Surface: AC	Family: DEFAULT	Zone:		Category:		Rank: P
Area: 29	,856 SqFt Leng	<b>th:</b> 300 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft Slal	Width:	Ft	Joint Length	: Ft
Shoulder:	Street Type:	Gra	nde: 0		Lanes: 0	
Section Comments:						
Work Date: 11/1/2012	Work Type: 1	New Construction - Initial	C	Code: NU-IN	Is Major	M&R: True
			Surveye	ed: 2		
Conditions: PCI: 8		talSamples: 6	Surveyo	e <b>a:</b> 2		
Conditions: PCI: 8 Inspection Comments: Sample Number: 108		Area:	6535.00 SqFt	PCI: 86	5	
Conditions: PCI: 8: Inspection Comments: Sample Number: 108 Sample Comments:	Type: R	Area:			5	
Conditions: PCI: 8: Inspection Comments: Sample Number: 108 Sample Comments: 50 PATCHING	2				5	
Conditions: PCI: 8: Inspection Comments: Sample Number: 108 Sample Comments: 50 PATCHING 57 WEATHERING	Type: R	Area: 279.00 SqFt				
Conditions: PCI: 8: Inspection Comments: Sample Number: 108 Sample Comments: 50 PATCHING 57 WEATHERING Sample Number: 211	Type: R  L L	Area: 279.00 SqFt 6256.00 SqFt	6535.00 SqFt	PCI: 80		
Inspection Comments: Sample Number: 108 Sample Comments: 50 PATCHING	Type: R  L L	Area: 279.00 SqFt 6256.00 SqFt	6535.00 SqFt	PCI: 80		
Conditions: PCI: 8: Inspection Comments: Sample Number: 108 Sample Comments: 50 PATCHING 57 WEATHERING Sample Number: 211 Sample Comments:	Type: R  L L L  Type: R	Area:  279.00 SqFt 6256.00 SqFt Area:	6535.00 SqFt	PCI: 80		
Conditions: PCI: 8: Inspection Comments: Sample Number: 108 Sample Comments: 50 PATCHING 57 WEATHERING Sample Number: 211 Sample Comments: 48 L & T CR	Type: R  L L Type: R	Area:  279.00 SqFt 6256.00 SqFt Area:	6535.00 SqFt	PCI: 80		

Netwo	rk: PMP			Nai	me: PON	MPANO BEA	ACH AIRPARK		
Brancl	h: TW M		Name:	TAXIWAY I	М	Use:	TAXIWAY	Area:	209,916 SqFt
Section	<b>n:</b> 1310	0	f 6	From: -			То: -		<b>Last Const.:</b> 1/1/1999
Surfac	e: AC	Family:	C9N59-GA	-TW-AC Zoi	ne:		Category:		Rank: P
Area:		24,002 SqFt	Lengt	<b>h:</b> 900	Ft	Width:	50 Ft		
Slabs:		Slab Ler	ngth:	Ft	Slab Width:		Ft	Joint Leng	th: Ft
Should	ler:	Street T	ype:		Grade: 0			Lanes:	0
Section	n Comments:								
Work	<b>Date:</b> 1/1/1999	W	ork Type: B	UILT		C	ode: IMPORTED	Is Maj	or M&R: True
Last I	nsp. Date: 5/8	/2017	Tota	alSamples: 7		Surveye	ed: 2		
Condi	tions: PCI:	83							
Inspec	tion Comments	:							
Sampl	e Number: 11	4 <b>Ty</b> J	pe: R	Area:	3500	0.00 SqFt	PCI: 8	8	
Sampl	e Comments:								
48	L & T CR		L	15.00 Ft					
50	PATCHING		L	13.00 SqFt					
57	WEATHERING	G	L	3487.00 SqFt					
Sampl	e Number: 11	6 <b>Ty</b> J	pe: R	Area:	3500	0.00 SqFt	PCI: 7	9	
Sampl	e Comments:								
48	L & T CR		L	133.00 Ft					
52	RAVELING		L	70.00 SqFt					
57	WEATHERING	G	L	3430.00 SqFt					

Network:	PMP				Naı	me: PO!	MPANO BEA	CH AIRPARK			
Branch:	TW M		Name	: TAXI	WAY N	M	Use:	TAXIWAY	Area:	20	9,916 SqFt
Section:	1315	of	6	From:	-			То: -			<b>Last Const.:</b> 1/1/19
Surface:	AC	Family:	C9N59-GA	A-TW-AC	Zor	ne:		Category:			Rank: P
Area:	16,3	59 SqFt	Leng	th:	125	Ft	Width:	110 Ft			
Slabs:		Slab Leng	gth:	Ft		Slab Width:		Ft	Joint L	ength:	Ft
Shoulder:		Street Ty	pe:			Grade: 0			Lanes:	0	
Section Co	omments:										
Work Dat	te: 1/1/1999	Wo	rk Type: I	BUILT			C	ode: IMPORTED	Is I	Major M	I&R: True
Last Insp.	. <b>Date:</b> 5/8/2017	1	То	talSamples:	3		Surveye	<b>d:</b> 1			
Condition	s: <b>PCI</b> : 70										
Inspection	n Comments:										
Sample N	umber: 200	Туре	e: R	A	Area:	598	1.00 SqFt	PCI: 7	70		
Sample C	omments:										
42 BL	EEDING		N	2.00	SqFt						
	& T CR		L	302.00	_						
48 L&			L	118.00	SqFt						
	TCHING		_								
50 PA	ATCHING AVELING		L	586.00	_						

Branc	ch: TW M		Name:	TAXIWAY N	1 Use:	TAXIWAY	Area:	209,916 SqFt
Sectio	on: 1320	of 6		From: -		То: -		<b>Last Const.:</b> 1/1/1970
Surfa	ce: AC	Family: C9N	159-GA-T	ΓW-AC <b>Z</b> or	e:	Category:		Rank: P
Area:	95,81	5 SqFt	Length	: 450 1	Ft Width:	50 Ft		
Slabs	:	Slab Length:		Ft	Slab Width:	Ft	Joint Leng	gth: Ft
Shoul	lder:	Street Type:			Grade: 0		Lanes:	0
Sectio	on Comments:							
Work	<b>Date:</b> 1/1/1970	Work T	ype: BU	ILT		Code: IMPORTED	Is Ma	jor M&R: True
Last l	Insp. Date: 5/8/2017		Total	Samples: 20	Survey	v <b>ed:</b> 5		
Cond	itions: PCI: 65							
Inspe	ction Comments:							
Samp	ole Number: 198	Type:	R	Area:	5687.00 SqFt	<b>PCI:</b> 64		
_	le Comments:	V E			1			
_		Υ.		222.00 8.75				
45 48	DEPRESSION L & T CR	I I		232.00 SqFt 257.00 Ft				
52	RAVELING	I		5687.00 SqFt				
Samp	ole Number: 202	Type:	R	Area:	5000.00 SqFt	PCI: 64		
Samp	le Comments:	••			•			
48	L & T CR	I	_	467.00 Ft				
50	PATCHING	I		132.00 SqFt				
52	RAVELING	I		4868.00 SqFt				
Samp	le Number: 206	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 69		
Samp	le Comments:							
48	L & T CR	I	_	413.00 Ft				
52	RAVELING	I		5000.00 SqFt				
Samp	le Number: 216	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 64		
Samp	le Comments:							
48	L & T CR	I	_	473.00 Ft				
50	PATCHING	I	_	85.00 SqFt				
52	RAVELING	I	_	4915.00 SqFt				
Samp	le Number: 220	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 63		
Samp	le Comments:							
48	L & T CR	I	_	420.00 Ft				
50	PATCHING	I		550.00 SqFt				
52	RAVELING	I		4450.00 SqFt				

POMPANO BEACH AIRPARK

Name:

PMP

Network:

Network:	PMP			N	ame:	POMPANO BEA	CH AIRPARK			
Branch:	TW M		Name:	TAXIWAY	M	Use:	TAXIWAY	Area:	209,916 \$	SqFt
Section:	1325	C	f 6	From: -			То: -		Last (	Const.: 1/1/2012
Surface:	AAC	Family:	DEFAULT	Ze	one:		Category:		Rank	: P
Area:		16,146 SqFt	Length:	450	Ft	Width:	50 Ft			
Slabs:		Slab Le	ngth:	Ft	Slab Widt	th:	Ft	Joint Lo	ength:	Ft
Shoulder:		Street T	ype:		Grade:	0		Lanes:	0	
Section Co	mments:									
Work Date: 1/1/1970 Work Type: New Construction			v Construction - In	nitial	C	ode: NU-IN	Is N	Iajor M&R:	Гruе	
Work Date: 1/1/2012 Work Type: MILL at			LL and OVERLA	Y	C	ode: ML-OV	Is N	Iajor M&R:	Ггие	
Last Insp.	<b>Date:</b> 5/8	3/2017	Totals	Samples: 4		Surveye	<b>d:</b> 1			
Conditions	s: PCI:	92								
Inspection	Comments	s:								
Sample Nu	ımber: 21	15 <b>Ty</b>	pe: R	Area:	4	1801.00 SqFt	PCI: 92	2		
Sample Co	mments:									

Network:	PMP			Nai	ne: PON	MPANO BEA	CH AIRPARK				
Branch:	TW N		Name:	TAXIWAY N	1	Use:	TAXIWAY	Area:	28,235 SqFt		
Section:	1405	0	f 1	From: -			То: -		Last Const.: 1/1/2004		
Surface:	AC	Family:	DEFAULT	Zoi	ne:	Category:			Rank: P		
Area:		28,235 SqFt	Length	560	Ft	Width:	50 Ft				
Slabs:		Slab Len	igth:	Ft	Slab Width:		Ft	Joint Le	ength: Ft		
Shoulder:		Street Ty	ype:		Grade: 0			Lanes:	0		
Section Co	mments:										
Work Date: 1/1/2004 Work Type: New Construction - Initial					tial	Code: NU-IN Is M			Major M&R: True		
Last Insp. l	<b>Date:</b> 5/8	/2017	Total	Samples: 5		Surveye	<b>d:</b> 1				
Conditions	: PCI:	82									
Inspection	Comments	s:									
Sample Nu	mber: 20	)3 <b>Ty</b> į	pe: R	Area:	5000	0.00 SqFt	PCI:	82			
Sample Co	mments:										
48 L&	TCR		L	135.00 Ft							
52 RAV	VELING		L	100.00 SqFt							
57 WE	ATHERIN	G	L	4900.00 SqFt							

POMPANO BEACH AIRPARK PMP Network: Name: **Branch:** TW R Name: TAXIWAY R Use: TAXIWAY Area: 21,726 SqFt **Section:** 1805 of 1 From: **Last Const.:** 6/1/2012 To: Surface: ACFamily: DEFAULT Zone: Category: Rank: P Area: 21,726 SqFt Length: 600 Ft Width: 35 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 **Shoulder:** Grade: Lanes: **Section Comments: Work Date:** 6/1/2012 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 5/8/2017 **TotalSamples:** 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 4989.00 SqFt Sample Number: 101 R **PCI:** 92 Type: Area: **Sample Comments:** 

6.00 Ft 48 L & T CR L 57 WEATHERING L 4989.00 SqFt