

**FLORIDA DEPARTMENT OF TRANSPORTATION  
AVIATION AND SPACEPORTS OFFICE**

# **Statewide Airfield Pavement Management Program**

**Airport Pavement  
Evaluation Report  
September 2017**



**Cecil Airport (VQQ)**  
General Aviation Airport  
District 2





---

*Florida Department of Transportation*

---

# Statewide Airfield Pavement Management Program

**Prepared by:**

*FDOT Aviation and Spaceports Office  
605 Suwannee Street  
Tallahassee, Florida 32399-0450*



# Table of Contents


<b>Executive Summary .....</b>	<b>10</b>
<b>Program Background.....</b>	<b>10</b>
<b>Summary of Results.....</b>	<b>11</b>
Pavement Condition Index (Latest Inspection) .....	11
Forecasted Pavement Condition Index 2018-2027.....	15
Major Rehabilitation Planning 2018-2027 .....	19
<b>Summary of Cecil Airport .....</b>	<b>21</b>
<b>Chapter 1 – Introduction .....</b>	<b>23</b>
<b>1.1 Background .....</b>	<b>23</b>
<b>1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017 ....</b>	<b>23</b>
<b>1.3 Organization .....</b>	<b>25</b>
1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager .....	25
1.3.2 Participating Florida Public-Use and Publicly Owned Airports .....	25
1.3.3 Florida Department of Transportation District Offices.....	25
1.3.4 Consultant .....	25
<b>1.4 Purpose of Airport Pavement Evaluation Report .....</b>	<b>27</b>
<b>1.5 History of the Program .....</b>	<b>27</b>
<b>1.6 Federal Aviation Administration (FAA) .....</b>	<b>29</b>
<b>1.7 FDOT SAPMP Objectives and Components .....</b>	<b>29</b>
1.7.1 Program Objectives.....	29
1.7.2 Program Components .....	29
<b>1.8 References .....</b>	<b>33</b>
<b>Chapter 2 – Methodology .....</b>	<b>35</b>
<b>2.1 Airfield Pavement Database .....</b>	<b>35</b>
<b>2.2 Airfield Pavement System Inventory .....</b>	<b>35</b>
2.2.1 Pavement Management Program Network Definition Terminology .....	36
<b>2.3 Airfield Pavement Structure .....</b>	<b>38</b>
2.3.1 Pavement Structure Types .....	38
<b>2.4 Airfield Pavement Work History .....</b>	<b>40</b>
2.4.1 Airfield Pavement Record Keeping .....	40
<b>2.5 Airfield Pavement Traffic .....</b>	<b>40</b>
<b>2.6 Airfield Pavement Condition Index (PCI) Survey.....</b>	<b>40</b>
2.6.1 PCI Survey Methodology .....	40
2.6.2 Pavement Distress Types .....	42

2.6.3 PCI Survey Inspection Procedures .....	46
2.6.4 Updates to the ASTM D5340-12.....	47
<b>Chapter 3 – Airfield Pavement System Inventory .....</b>	<b>50</b>
<b>3.1 Airfield Pavement Network Information .....</b>	<b>50</b>
3.1.1 Previous and/or Anticipated Airfield Pavement Construction .....	50
3.1.2 Estimated Pavement Age .....	52
3.1.3 Functional Use Classification.....	54
3.1.4 Pavement Surface Type.....	55
3.1.5 Pavement System Inventory Details .....	56
<b>Chapter 4 – Airfield Pavement Condition .....</b>	<b>65</b>
<b>4.1 Airfield Pavement Condition Index (Latest Inspection).....</b>	<b>65</b>
4.1.1 Network-Level Analysis.....	65
4.1.2 Branch-Level Analysis.....	65
4.1.3 Section-Level Analysis .....	68
<b>4.2 Summary of Pavement Condition Evaluation Results.....</b>	<b>74</b>
4.2.1 Network-Level Observations.....	74
4.2.2 Branch-Level Observations.....	74
<b>4.3 Forecasted Pavement Conditions .....</b>	<b>77</b>
4.3.1 Performance Models and Prediction Curves .....	77
4.3.2 Branch-Level Pavement Condition Forecast .....	77
4.3.3 Section-Level Pavement Condition Forecast.....	79
4.3.4 Forecasted PCI Considerations .....	86
<b>Chapter 5 – Localized Maintenance and Repair Planning.....</b>	<b>88</b>
<b>5.1 Localized Maintenance and Repair .....</b>	<b>88</b>
<b>5.2 Localized Maintenance and Repair Policy .....</b>	<b>89</b>
<b>5.3 Localized Maintenance and Repair Analysis and Recommendations .....</b>	<b>93</b>
<b>Chapter 6 – Major Rehabilitation Planning .....</b>	<b>100</b>
<b>6.1 Major Rehabilitation .....</b>	<b>100</b>
6.1.1 Critical PCI .....	102
6.1.2 FDOT Recommended Minimum Service-Level PCI .....	102
<b>6.2 Major Rehabilitation Policy .....</b>	<b>103</b>
6.2.1 Major Rehabilitation Pavement Section Development.....	103
6.2.2 Major Rehabilitation Planning-Level Unit Costs.....	104
<b>6.3 Major Rehabilitation Needs .....</b>	<b>105</b>
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs .....	105
<b>Chapter 7 – Conclusion.....</b>	<b>111</b>
<b>7.1 Recommendations .....</b>	<b>111</b>
7.1.1 Continued PCI Survey Inspections .....	111
7.1.2 Localized Maintenance and Repair.....	111

# Statewide Airfield Pavement Management Program




7.1.3 Major Rehabilitation .....	111
7.1.4 Pavement Management System.....	111
<b>7.2 Supporting Documents.....</b>	<b>112</b>
001 – Airfield Pavement Network Definition Exhibit.....	112
002 – Airfield Pavement System Inventory Exhibit .....	112
003 – Airfield Pavement Condition Index Exhibit.....	112
004 – Airfield Pavement Major Rehabilitation Exhibit.....	112
Inspection Photograph Documentation.....	112
<b>7.3 Conclusion.....</b>	<b>113</b>



# Statewide Airfield Pavement Management Program



- Appendix A      Airfield Pavement Analysis Tables
- Appendix B      Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
- Appendix C      Technical Exhibits
- Appendix D      Inspection Photograph Documentation
- Appendix E      Inspection Distress Details



## List of Figures

Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027 .....	21
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts .....	24
Figure 1.7-1 Typical Pavement Condition Life Cycle .....	30
Figure 1.7-2 General Pavement Treatments by Condition Range.....	31
Figure 1.7-3 Flexible Asphalt Concrete.....	32
Figure 1.7-4 Rigid Portland Cement Concrete.....	32
Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit .....	51
Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit.....	52
Figure 3.1.2 Average Age of Pavements at Inspection .....	53
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area.....	54
Figure 3.1.4 (a) Pavement Surface Type by Area (SF) .....	55
Figure 3.1.4 (b) Pavement Surface Type by Area (%).....	56
Figure 4.1.1 Latest Condition – Overall Network .....	65
Figure 4.1.2 (a) Latest Condition – Runway Pavements .....	66
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements .....	66
Figure 4.1.2 (c) Latest Condition – Apron Pavements.....	67
Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit.....	73
Figure 4.2.2 Pavement Condition Summary by Facility Use .....	74
Figure 4.3.2 (a) Forecasted Runway Pavement Performance .....	77
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance .....	78
Figure 4.3.2 (c) Forecasted Apron Pavement Performance .....	78
Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI .....	100
Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI.....	101
Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year .....	108
Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit .....	109

## List of Tables

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level.....	11
Table E-2 Pavement Condition Index Forecast 2018-2027 .....	15
Table E-3 Major Rehabilitation Planning 2018-2027 .....	19
Table 2.2.1 Airfield Pavement Database Network Definition Terminology .....	37
Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields .....	42
Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields .....	43
Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields .....	43
Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields .	44
Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields.....	45
Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields.....	45
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete .....	46
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete....	46
Table 2.6.4 Summary of Updates to ASTM D5340-12 .....	48
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction.....	50
Table 3.1.5 Pavement System Inventory Details .....	57
Table 4.1.3 Latest Pavement Condition Index Summary.....	69
Table 4.3.3 Forecasted PCI 2018-2027 .....	80
Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete .....	89
Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete.....	90
Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete .....	92
Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete .	92

# Statewide Airfield Pavement Management Program



Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level	93
Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level	.94
Table 5.3-3 Summary of Localized Maintenance.....	98
Table 6.1.2 FDOT Recommended Minimum Service-Level PCI .....	102
Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete .....	103
Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete .....	104
Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type .....	105
Table 6.3.1 10-Year Major Rehabilitation Needs .....	106

# **Executive Summary**



# Executive Summary

## Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP)”** using the documented procedures set forth by ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.



## Summary of Results

### Pavement Condition Index (Latest Inspection)

*Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level*

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	RUNWAY 18R-36L	RUNWAY	6135	50,000	74	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6140	50,000	84	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6145	26,000	91	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6150	26,000	93	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6155	30,000	89	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6160	30,000	88	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6165	31,200	87	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6170	31,200	88	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6175	20,400	74	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6180	20,400	88	Good
VQQ	RUNWAY 18L-36R	RUNWAY	6205	50,000	79	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6210	50,000	83	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6215	638,300	82	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6217	61,900	79	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6220	638,300	86	Good
VQQ	RUNWAY 18L-36R	RUNWAY	6222	61,900	75	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6225	50,200	72	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6230	50,200	82	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6235	450,000	80	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6240	450,000	85	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6305	50,000	76	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6310	48,500	79	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6315	603,300	76	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6317	20,000	76	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6320	585,202	84	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6322	19,400	71	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6325	57,000	89	Good
VQQ	RUNWAY 9R-27L	RUNWAY	6330	55,290	89	Good
VQQ	RUNWAY 9R-27L	RUNWAY	6335	50,000	78	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6340	48,500	74	Satisfactory
VQQ	RUNWAY 9L-27R	RUNWAY	6405	50,000	81	Satisfactory
VQQ	RUNWAY 9L-27R	RUNWAY	6410	50,000	77	Satisfactory
VQQ	RUNWAY 9L-27R	RUNWAY	6414	56,500	51	Poor
VQQ	RUNWAY 9L-27R	RUNWAY	6415	283,572	27	Very Poor
VQQ	RUNWAY 9L-27R	RUNWAY	6417	28,250	59	Fair



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	RUNWAY 9L-27R	RUNWAY	6420	311,822	33	Very Poor
VQQ	RUNWAY 9L-27R	RUNWAY	6425	33,700	88	Good
VQQ	RUNWAY 9L-27R	RUNWAY	6430	33,700	91	Good
VQQ	RUNWAY 9L-27R	RUNWAY	6435	20,000	92	Good
VQQ	RUNWAY 9L-27R	RUNWAY	6440	20,000	88	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6105	50,000	79	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6110	50,000	77	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6115	542,800	30	Very Poor
VQQ	RUNWAY 18R-36L	RUNWAY	6120	542,800	33	Very Poor
VQQ	RUNWAY 18R-36L	RUNWAY	6125	30,000	74	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6130	30,000	88	Good
VQQ	TAXIWAY A	TAXIWAY	105	67,381	62	Fair
VQQ	TAXIWAY A	TAXIWAY	110	269,943	75	Satisfactory
VQQ	TAXIWAY A	TAXIWAY	115	54,396	86	Good
VQQ	TAXIWAY A	TAXIWAY	117	27,484	78	Satisfactory
VQQ	TAXIWAY A	TAXIWAY	120	18,750	91	Good
VQQ	TAXIWAY A	TAXIWAY	125	19,405	81	Satisfactory
VQQ	TAXIWAY A	TAXIWAY	130	457,575	82	Satisfactory
VQQ	TAXIWAY A1	TAXIWAY	505	77,280	84	Satisfactory
VQQ	TAXIWAY A1	TAXIWAY	510	58,667	84	Satisfactory
VQQ	TAXIWAY A1	TAXIWAY	515	67,256	74	Satisfactory
VQQ	TAXIWAY A2	TAXIWAY	603	26,792	90	Good
VQQ	TAXIWAY A2	TAXIWAY	605	11,684	90	Good
VQQ	TAXIWAY A2	TAXIWAY	607	7,608	91	Good
VQQ	TAXIWAY A2	TAXIWAY	608	7,608	94	Good
VQQ	TAXIWAY A2	TAXIWAY	610	4,184	94	Good
VQQ	TAXIWAY A2	TAXIWAY	615	23,980	85	Satisfactory
VQQ	TAXIWAY A2	TAXIWAY	620	24,484	72	Satisfactory
VQQ	TAXIWAY A3	TAXIWAY	703	26,792	94	Good
VQQ	TAXIWAY A3	TAXIWAY	705	11,684	92	Good
VQQ	TAXIWAY A3	TAXIWAY	707	7,608	92	Good
VQQ	TAXIWAY A3	TAXIWAY	708	7,608	94	Good
VQQ	TAXIWAY A3	TAXIWAY	710	4,184	94	Good
VQQ	TAXIWAY A3	TAXIWAY	715	23,980	81	Satisfactory
VQQ	TAXIWAY A3	TAXIWAY	720	24,484	73	Satisfactory
VQQ	TAXIWAY A4	TAXIWAY	805	57,662	77	Satisfactory
VQQ	TAXIWAY A4	TAXIWAY	810	79,426	81	Satisfactory
VQQ	TAXIWAY A5	TAXIWAY	1005	166,214	75	Satisfactory
VQQ	TAXIWAY B	TAXIWAY	205	355,476	83	Satisfactory



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	TAXIWAY B	TAXIWAY	208	19,400	89	Good
VQQ	TAXIWAY B	TAXIWAY	210	11,684	91	Good
VQQ	TAXIWAY B	TAXIWAY	212	38,584	92	Good
VQQ	TAXIWAY B	TAXIWAY	215	165,208	81	Satisfactory
VQQ	TAXIWAY B1	TAXIWAY	1105	56,522	79	Satisfactory
VQQ	TAXIWAY B1	TAXIWAY	1110	77,371	77	Satisfactory
VQQ	TAXIWAY B1	TAXIWAY	1115	30,000	76	Satisfactory
VQQ	TAXIWAY B2	TAXIWAY	1203	11,792	88	Good
VQQ	TAXIWAY B2	TAXIWAY	1205	22,500	90	Good
VQQ	TAXIWAY B2	TAXIWAY	1207	23,696	91	Good
VQQ	TAXIWAY B2	TAXIWAY	1210	23,980	70	Fair
VQQ	TAXIWAY B2	TAXIWAY	1215	24,522	74	Satisfactory
VQQ	TAXIWAY B3	TAXIWAY	1405	58,667	76	Satisfactory
VQQ	TAXIWAY B3	TAXIWAY	1410	77,505	79	Satisfactory
VQQ	TAXIWAY C	TAXIWAY	305	175,845	80	Satisfactory
VQQ	TAXIWAY C	TAXIWAY	310	136,320	73	Satisfactory
VQQ	TAXIWAY C	TAXIWAY	315	44,457	30	Very Poor
VQQ	TAXIWAY D	TAXIWAY	405	435,222	75	Satisfactory
VQQ	TAXIWAY D	TAXIWAY	410	29,146	95	Good
VQQ	TAXIWAY D	TAXIWAY	415	123,375	86	Good
VQQ	TAXIWAY D	TAXIWAY	420	31,875	66	Fair
VQQ	TAXIWAY D2	TAXIWAY	905	59,738	78	Satisfactory
VQQ	TAXIWAY E	TAXIWAY	1610	228,000	100	Good
VQQ	TAXIWAY E1	TAXIWAY	1605	99,253	100	Good
VQQ	TAXIWAY M	TAXIWAY	1305	22,376	81	Satisfactory
VQQ	NORTH APRON	APRON	4103	62,610	73	Satisfactory
VQQ	NORTH APRON	APRON	4105	172,130	71	Satisfactory
VQQ	NORTH APRON	APRON	4110	290,625	56	Fair
VQQ	NORTH APRON	APRON	4115	236,250	78	Satisfactory
VQQ	NORTH APRON	APRON	4117	14,325	88	Good
VQQ	NORTH APRON	APRON	4120	391,125	73	Satisfactory
VQQ	NORTH APRON	APRON	4125	1,403,402	79	Satisfactory
VQQ	NORTH APRON	APRON	4132	37,875	75	Satisfactory
VQQ	NORTH APRON	APRON	4137	74,250	68	Fair
VQQ	NORTH APRON	APRON	4138	11,250	74	Satisfactory
VQQ	NORTH APRON	APRON	4140	102,688	71	Satisfactory
VQQ	NORTH APRON	APRON	4150	105,074	75	Satisfactory
VQQ	WEST PARKING APRON	APRON	4205	166,732	72	Satisfactory
VQQ	WEST PARKING APRON	APRON	4210	233,520	77	Satisfactory



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	WEST PARKING APRON	APRON	4220	266,686	76	Satisfactory
VQQ	WEST PARKING APRON	APRON	4225	35,000	14	Serious
VQQ	WEST PARKING APRON	APRON	4230	26,250	12	Serious
VQQ	WEST PARKING APRON	APRON	4235	13,730	12	Serious
VQQ	WEST PARKING APRON	APRON	4240	82,954	75	Satisfactory
VQQ	WEST PARKING APRON	APRON	4245	102,240	75	Satisfactory
VQQ	WEST PARKING APRON	APRON	4250	285,584	72	Satisfactory
VQQ	WEST PARKING APRON	APRON	4255	19,950	9	Failed
VQQ	WEST PARKING APRON	APRON	4260	50,613	77	Satisfactory
VQQ	WEST PARKING APRON	APRON	4265	99,400	80	Satisfactory
VQQ	WEST PARKING APRON	APRON	4270	41,180	73	Satisfactory
VQQ	NORTH APRON	APRON	4305	70,920	95	Good
VQQ	NORTH APRON	APRON	4310	43,214	99	Good
VQQ	EAST APRON	APRON	4405	26,675	100	Good
VQQ	EAST APRON	APRON	4410	60,000	100	Good
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5005	22,135	78	Satisfactory
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5010	22,135	72	Satisfactory
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5015	22,135	83	Satisfactory
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5020	22,135	43	Poor
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5055	13,010	30	Very Poor
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5125	22,115	76	Satisfactory
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5130	22,115	81	Satisfactory
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5135	22,115	62	Fair
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5140	22,115	44	Poor
VQQ	NATIONAL GUARD WASH APRON	APRON	5305	30,200	88	Good
VQQ	NATIONAL GUARD WASH APRON	APRON	5310	199,156	93	Good

## Forecasted Pavement Condition Index 2018-2027

Table E-2 Pavement Condition Index Forecast 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	AP E	4405	100	95	93	92	90	88	87	85	84	82	80
VQQ	AP E	4410	100	90	87	84	82	79	77	74	72	70	68
VQQ	AP N	4103	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP N	4105	71	69	67	65	64	62	60	59	58	56	55
VQQ	AP N	4110	56	55	54	53	51	51	50	49	48	47	47
VQQ	AP N	4115	78	76	74	72	70	68	66	64	62	61	59
VQQ	AP N	4117	88	86	83	80	78	76	73	71	69	67	65
VQQ	AP N	4120	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP N	4125	79	77	75	72	70	68	66	65	63	61	60
VQQ	AP N	4132	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP N	4137	68	66	65	63	61	60	58	57	56	54	53
VQQ	AP N	4138	74	72	70	68	66	64	63	61	60	58	57
VQQ	AP N	4140	71	69	67	65	64	62	60	59	58	56	55
VQQ	AP N	4150	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP N	4305	95	93	90	87	84	81	79	76	74	72	70
VQQ	AP N	4310	99	97	93	90	87	85	82	79	77	75	72
VQQ	AP N RFUEL	5125	76	74	72	70	68	66	64	62	61	59	58
VQQ	AP N RFUEL	5130	81	79	77	74	72	70	68	66	64	63	61
VQQ	AP N RFUEL	5135	62	61	59	58	56	55	54	53	52	51	50
VQQ	AP N RFUEL	5140	44	43	43	43	42	42	42	42	42	41	41
VQQ	AP NAT GRD	5305	88	86	83	80	78	76	73	71	69	67	65
VQQ	AP NAT GRD	5310	93	91	88	85	82	80	77	75	73	71	69
VQQ	AP W	4205	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W	4210	77	75	73	71	69	67	65	63	62	60	59
VQQ	AP W	4220	76	74	72	70	68	66	64	62	61	59	58
VQQ	AP W	4225	14	13	12	11	9	8	7	6	5	4	3
VQQ	AP W	4230	12	11	10	9	7	6	5	4	3	2	1
VQQ	AP W	4235	12	11	10	9	7	6	5	4	3	2	1
VQQ	AP W	4240	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP W	4245	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP W	4250	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W	4255	9	8	7	6	4	3	2	1	0	0	0
VQQ	AP W	4260	77	75	73	71	69	67	65	63	62	60	59
VQQ	AP W	4265	80	78	76	73	71	69	67	65	64	62	60
VQQ	AP W	4270	73	71	69	67	65	64	62	60	59	57	56



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	AP W RFUEL	5005	78	76	74	72	70	68	66	64	62	61	59
VQQ	AP W RFUEL	5010	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W RFUEL	5015	83	81	78	76	74	72	70	68	66	64	62
VQQ	AP W RFUEL	5020	43	42	42	42	42	41	41	41	41	41	41
VQQ	AP W RFUEL	5055	30	29	28	27	25	24	23	22	21	20	19
VQQ	RW 18L-36R	6205	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 18L-36R	6210	83	82	81	80	79	79	78	77	76	75	74
VQQ	RW 18L-36R	6215	82	80	77	75	73	70	68	67	65	64	63
VQQ	RW 18L-36R	6217	79	77	75	72	70	68	66	65	63	62	61
VQQ	RW 18L-36R	6220	86	84	82	79	77	74	72	70	68	66	64
VQQ	RW 18L-36R	6222	75	73	71	69	67	65	64	63	62	61	61
VQQ	RW 18L-36R	6225	72	71	70	69	68	68	67	66	65	64	63
VQQ	RW 18L-36R	6230	82	81	80	79	78	78	77	76	75	74	73
VQQ	RW 18L-36R	6235	80	79	78	77	76	76	75	74	73	72	71
VQQ	RW 18L-36R	6240	85	84	83	82	81	81	80	79	78	77	76
VQQ	RW 18R-36L	6105	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 18R-36L	6110	77	76	75	74	73	73	72	71	70	69	68
VQQ	RW 18R-36L	6115	30	28	25	22	19	17	14	11	8	6	3
VQQ	RW 18R-36L	6120	33	31	29	26	23	20	17	15	12	9	6
VQQ	RW 18R-36L	6125	74	73	72	71	70	70	69	68	67	66	65
VQQ	RW 18R-36L	6130	88	87	86	85	84	84	83	82	81	80	79
VQQ	RW 18R-36L	6135	74	73	72	71	70	70	69	68	67	66	65
VQQ	RW 18R-36L	6140	84	83	82	81	80	80	79	78	77	76	75
VQQ	RW 18R-36L	6145	91	89	87	84	82	79	77	75	72	70	68
VQQ	RW 18R-36L	6150	93	91	89	87	84	82	79	77	74	72	70
VQQ	RW 18R-36L	6155	89	87	85	82	80	77	75	73	70	68	66
VQQ	RW 18R-36L	6160	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 18R-36L	6165	87	85	83	80	78	75	73	71	69	67	65
VQQ	RW 18R-36L	6170	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 18R-36L	6175	74	72	70	68	66	65	63	62	61	61	61
VQQ	RW 18R-36L	6180	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9L-27R	6405	81	80	79	78	77	77	76	75	74	73	72
VQQ	RW 9L-27R	6410	77	76	75	74	73	73	72	71	70	69	68
VQQ	RW 9L-27R	6414	51	49	46	43	39	36	33	31	28	25	23
VQQ	RW 9L-27R	6415	27	25	22	19	16	14	11	8	5	3	0
VQQ	RW 9L-27R	6417	59	58	57	55	53	50	47	44	41	38	35
VQQ	RW 9L-27R	6420	33	31	29	26	23	20	17	15	12	9	6
VQQ	RW 9L-27R	6425	88	86	84	81	79	76	74	72	69	67	66



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	RW 9L-27R	6430	91	89	87	84	82	79	77	75	72	70	68
VQQ	RW 9L-27R	6435	92	90	88	86	83	81	78	76	73	71	69
VQQ	RW 9L-27R	6440	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9R-27L	6305	76	75	74	73	72	72	71	70	69	68	67
VQQ	RW 9R-27L	6310	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 9R-27L	6315	76	74	72	70	68	66	64	63	62	61	61
VQQ	RW 9R-27L	6317	76	74	72	70	68	66	64	63	62	61	61
VQQ	RW 9R-27L	6320	84	82	80	77	75	72	70	68	66	65	63
VQQ	RW 9R-27L	6322	71	69	67	66	64	63	62	61	61	60	60
VQQ	RW 9R-27L	6325	89	88	87	86	85	85	84	83	82	81	80
VQQ	RW 9R-27L	6330	89	88	87	86	85	85	84	83	82	81	80
VQQ	RW 9R-27L	6335	78	77	76	75	74	74	73	72	71	70	69
VQQ	RW 9R-27L	6340	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW A	105	62	61	60	59	58	58	57	56	55	54	53
VQQ	TW A	110	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW A	115	86	85	84	83	82	82	81	80	79	78	77
VQQ	TW A	117	78	77	75	74	73	72	71	70	69	68	68
VQQ	TW A	120	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW A	125	81	79	78	76	75	74	72	72	71	70	69
VQQ	TW A	130	82	81	80	79	78	78	77	76	75	74	73
VQQ	TW A1	505	84	83	82	81	80	80	79	78	77	76	75
VQQ	TW A1	510	84	83	82	81	80	80	79	78	77	76	75
VQQ	TW A1	515	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW A2	603	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW A2	605	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW A2	607	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW A2	608	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A2	610	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A2	615	85	84	83	82	81	81	80	79	78	77	76
VQQ	TW A2	620	72	71	70	69	68	68	67	66	65	64	63
VQQ	TW A3	703	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	705	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW A3	707	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW A3	708	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	710	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	715	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW A3	720	73	72	71	70	69	69	68	67	66	65	64
VQQ	TW A4	805	77	76	75	74	73	73	72	71	70	69	68



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	TW A4	810	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW A5	1005	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW B	205	83	82	81	80	79	79	78	77	76	75	74
VQQ	TW B	208	89	87	84	82	80	78	76	75	74	73	72
VQQ	TW B	210	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW B	212	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW B	215	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW B1	1105	79	78	77	76	75	75	74	73	72	71	70
VQQ	TW B1	1110	77	76	75	74	73	73	72	71	70	69	68
VQQ	TW B1	1115	76	75	74	73	72	72	71	70	69	68	67
VQQ	TW B2	1203	88	86	83	81	79	77	76	75	73	72	71
VQQ	TW B2	1205	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW B2	1207	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW B2	1210	70	69	68	67	66	66	65	64	63	62	61
VQQ	TW B2	1215	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW B3	1405	76	75	74	73	72	72	71	70	69	68	67
VQQ	TW B3	1410	79	78	77	76	75	75	74	73	72	71	70
VQQ	TW C	305	80	79	78	77	76	76	75	74	73	72	71
VQQ	TW C	310	73	72	71	70	69	69	68	67	66	65	64
VQQ	TW C	315	30	29	28	28	27	25	24	22	20	17	14
VQQ	TW D	405	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW D	410	95	94	93	92	91	91	90	89	88	87	86
VQQ	TW D	415	86	84	82	80	77	76	74	72	71	70	69
VQQ	TW D	420	66	65	64	63	62	62	61	60	58	57	56
VQQ	TW D2	905	78	76	75	73	72	70	69	68	67	66	65
VQQ	TW E	1610	100	93	90	88	85	83	81	78	76	75	73
VQQ	TW E1	1605	100	93	90	88	85	83	81	78	76	75	73
VQQ	TW M	1305	81	80	79	78	77	77	76	75	74	73	72

## Major Rehabilitation Planning 2018-2027

*Table E-3 Major Rehabilitation Planning 2018-2027*


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	VQQ	AP N	4110	PCC	290,625	55	PCC Restoration	\$ 4,941,000.00
2018	VQQ	AP N RFUEL	5135	PCC	22,115	61	PCC Restoration	\$ 376,000.00
2018	VQQ	AP N RFUEL	5140	PCC	22,115	43	PCC Restoration	\$ 459,000.00
2018	VQQ	AP W	4225	PCC	35,000	13	PCC Reconstruction	\$ 806,000.00
2018	VQQ	AP W	4230	PCC	26,250	11	PCC Reconstruction	\$ 604,000.00
2018	VQQ	AP W	4235	PCC	13,730	11	PCC Reconstruction	\$ 316,000.00
2018	VQQ	AP W	4255	PCC	19,950	8	PCC Reconstruction	\$ 459,000.00
2018	VQQ	AP W RFUEL	5020	PCC	22,135	42	PCC Restoration	\$ 472,000.00
2018	VQQ	AP W RFUEL	5055	PCC	13,010	29	PCC Reconstruction	\$ 300,000.00
2018	VQQ	RW 18R-36L	6115	AAC	542,800	28	AC Reconstruction	\$ 7,599,000.00
2018	VQQ	RW 18R-36L	6120	AAC	542,800	31	AC Reconstruction	\$ 7,599,000.00
2018	VQQ	RW 9L-27R	6414	AAC	56,500	49	AC Restoration	\$ 634,000.00
2018	VQQ	RW 9L-27R	6415	AAC	283,572	25	AC Reconstruction	\$ 3,970,000.00
2018	VQQ	RW 9L-27R	6417	AAC	28,250	58	AC Restoration	\$ 311,000.00
2018	VQQ	RW 9L-27R	6420	AAC	311,822	31	AC Reconstruction	\$ 4,366,000.00
2018	VQQ	TW A	105	PCC	67,381	61	PCC Restoration	\$ 1,146,000.00
2018	VQQ	TW C	315	AC	44,457	29	AC Reconstruction	\$ 623,000.00
2019	VQQ	TW D	420	AC	31,875	64	AC Restoration	\$ 351,000.00
2020	VQQ	AP N	4137	PCC	74,250	63	PCC Restoration	\$ 1,263,000.00
2021	VQQ	AP N	4105	PCC	172,130	64	PCC Restoration	\$ 2,927,000.00
2021	VQQ	AP N	4140	PCC	102,688	64	PCC Restoration	\$ 1,746,000.00
2021	VQQ	RW 9R-27L	6322	AAC	19,400	64	AC Restoration	\$ 214,000.00
2022	VQQ	AP N	4103	PCC	62,610	64	PCC Restoration	\$ 1,065,000.00
2022	VQQ	AP N	4120	PCC	391,125	64	PCC Restoration	\$ 6,650,000.00
2022	VQQ	AP N	4138	PCC	11,250	64	PCC Restoration	\$ 192,000.00
2022	VQQ	AP W	4205	PCC	166,732	63	PCC Restoration	\$ 2,835,000.00
2022	VQQ	AP W	4250	PCC	285,584	63	PCC Restoration	\$ 4,856,000.00
2022	VQQ	AP W	4270	PCC	41,180	64	PCC Restoration	\$ 701,000.00
2022	VQQ	AP W RFUEL	5010	PCC	22,135	63	PCC Restoration	\$ 377,000.00
2023	VQQ	AP N	4132	PCC	37,875	63	PCC Restoration	\$ 644,000.00
2023	VQQ	AP N	4150	PCC	105,074	63	PCC Restoration	\$ 1,787,000.00
2023	VQQ	AP N RFUEL	5125	PCC	22,115	64	PCC Restoration	\$ 376,000.00
2023	VQQ	AP W	4220	PCC	266,686	64	PCC Restoration	\$ 4,534,000.00
2023	VQQ	AP W	4240	PCC	82,954	63	PCC Restoration	\$ 1,411,000.00
2023	VQQ	AP W	4245	PCC	102,240	63	PCC Restoration	\$ 1,739,000.00
2023	VQQ	RW 18L-36R	6222	AAC	61,900	64	AC Restoration	\$ 681,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2023	VQQ	RW 18R-36L	6175	AAC	20,400	63	AC Restoration	\$ 225,000.00
2023	VQQ	RW 9R-27L	6315	AAC	603,300	64	AC Restoration	\$ 6,637,000.00
2023	VQQ	RW 9R-27L	6317	AAC	20,000	64	AC Restoration	\$ 220,000.00
2024	VQQ	AP N	4115	PCC	236,250	64	PCC Restoration	\$ 4,017,000.00
2024	VQQ	AP W	4210	PCC	233,520	63	PCC Restoration	\$ 3,970,000.00
2024	VQQ	AP W	4260	PCC	50,613	63	PCC Restoration	\$ 861,000.00
2024	VQQ	AP W RFUEL	5005	PCC	22,135	64	PCC Restoration	\$ 377,000.00
2024	VQQ	TW B2	1210	PCC	23,980	64	PCC Restoration	\$ 408,000.00
2025	VQQ	AP N	4125	PCC	1,403,402	63	PCC Restoration	\$ 23,859,000.00
2025	VQQ	AP N RFUEL	5130	PCC	22,115	64	PCC Restoration	\$ 376,000.00
2025	VQQ	AP W	4265	PCC	99,400	64	PCC Restoration	\$ 1,690,000.00
2025	VQQ	RW 18L-36R	6217	AAC	61,900	63	AC Restoration	\$ 681,000.00
2026	VQQ	AP W RFUEL	5015	PCC	22,135	64	PCC Restoration	\$ 377,000.00
2026	VQQ	RW 18L-36R	6215	AAC	638,300	64	AC Restoration	\$ 7,022,000.00
2026	VQQ	RW 18L-36R	6225	PCC	50,200	64	PCC Restoration	\$ 854,000.00
2026	VQQ	TW A2	620	PCC	24,484	64	PCC Restoration	\$ 417,000.00
2027	VQQ	RW 18L-36R	6220	AAC	638,300	64	AC Restoration	\$ 7,022,000.00
2027	VQQ	RW 9R-27L	6320	AAC	585,202	63	AC Restoration	\$ 6,438,000.00
2027	VQQ	TW A3	720	PCC	24,484	64	PCC Restoration	\$ 417,000.00
2027	VQQ	TW C	310	PCC	136,320	64	PCC Restoration	\$ 2,318,000.00

\*All planning cost values have been rounded to the nearest thousand-dollar.

Figure E-4 Major Rehabilitation Planning Annual Budget 2018-2027



## Summary of Cecil Airport

Cecil Airport was inspected in May 2017 – the overall weighted PCI value was 73, a condition rating of Satisfactory. The results of the maintenance, repair, and major rehabilitation analysis identified \$11,106,320 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$137,516,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$34,981,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.

# **Chapter 1**



# Chapter 1 – Introduction

## 1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.


There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

## 1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2016-2017

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating public-use airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.

*Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts*

In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.



## 1.3 Organization

### 1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

### 1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).**” Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport’s airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer’s Reports, and/or field pavement inspection reports.

### 1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP’s on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

### 1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys,”** evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).**”

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- **Research and evaluation of existing record documentation** was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- **An update to the existing Network Definition Map** was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- **A functional pavement evaluation with PCI Survey inspections** was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- **Maintenance, Repair, and Rehabilitation Planning** was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA AC 150/5380-6C **“Guidelines and Procedures for Maintenance of Airport Pavements.”** Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.



## 1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

***The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.***

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

## 1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”** The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.



## 1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and **150/5380-7B “Airport Pavement Management Program (PMP)”**). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.”

## 1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC **150/5380-7B “Airport Pavement Management Program (PMP)”** an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

### 1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

### 1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data




F. Pavement Performance Modeling for the Prediction/Forecast of PCI  
 G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular **150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements."** The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements' past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and cost-effective manner. **Figure 1.7-1 Typical Pavement Condition Life Cycle**, which is based on the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."**

**Figure 1.7-1 Typical Pavement Condition Life Cycle**, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.

*Figure 1.7-1 Typical Pavement Condition Life Cycle*




\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).

**Figure 1.7-2 General Pavement Treatments by Condition Range** depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

*Figure 1.7-2 General Pavement Treatments by Condition Range*



Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7-1 and 1.7-2**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

**Figures 1.7-3 and Figure 1.7-4** depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.

Figure 1.7-3 Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	<b>86-100</b>	<b>90</b>		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	<b>65-85</b>	<b>70</b>		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabilitation	<b>40-64</b>	<b>50</b>		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	<b>0-39</b>	<b>15</b>		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figure 1.7-4 Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	<b>86-100</b>	<b>90</b>		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	<b>65-85</b>	<b>70</b>		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabilitation	<b>40-64</b>	<b>50</b>		Pavements that have deteriorated below a PCI 65, or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	<b>0-39</b>	<b>15</b>		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.



## 1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”
- FAA Advisory Circular 150/5380-7B 150/5380-7B “Airport Pavement Management Program.”
- FAA Advisory Circular 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”
- FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation.”
- Department of the Air Force, Air Force Civil Engineer Center “Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements.”
- Unified Facilities Criteria (UFC) 3-260-16FA 16 “Airfield Pavement Condition Survey Procedures Pavements.”
- Unified Facilities Criteria (UFC) 3-260-03 “Airfield Pavement Evaluation.”
- Pavement Management for Airports, Roads, and Parking Lots 2<sup>nd</sup> Edition, M.Y. Shahin.

# **Chapter 2**



# Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”**

## 2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

## 2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.



A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

### *2.2.1 Pavement Management Program Network Definition Terminology*

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

#### **Pavement Network**

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

#### **Pavement Branch**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

#### **Pavement Section**

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a “parent” pavement network.

## Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs ( $\pm 8$  slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ( $\pm 2,000 \text{ ft}^2$ ) for flexible asphalt concrete (AC) or porous friction course pavements.

*Table 2.2.1 Airfield Pavement Database Network Definition Terminology*

PMS Network Level	Common Definition	Airport Example
<b>Network</b>	Overall pavement assets maintained by the Airport	“Tallahassee International Airport – Airfield Pavements”
<b>Branch Name</b>	Commonly defined asset name as established by Airport and by use	“Runway 18-36”
<b>Branch ID</b>	Codified shorthand name for commonly defined asset established for database identification	“RW 18-36” RW, Branch Use, “Runway” 18-36, Runway Facility
<b>Section ID</b>	Codified identification for pavement asset that is distinct by the following: <ul style="list-style-type: none"> <li>• Pavement Composition</li> <li>• Construction Work History</li> <li>• Aircraft Traffic</li> <li>• Condition Records</li> </ul>	“6105”
<b>Sample Unit</b>	A numeric identification of an area of pavement (5,000 $\pm$ 2,000 SF of AC or 20 $\pm$ 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	“300”



## 2.3 Airfield Pavement Structure

### 2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

#### Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

##### *Asphalt Concrete (AC)*

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

##### *Asphalt Concrete Overlaid on Asphalt Concrete (AAC)*

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

##### *Asphalt Concrete Overlaid on Portland Cement Concrete (APC)*

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.



## Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

### *Portland Cement Concrete (PCC)*

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

## Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

### *Conventional Whitetopping (WHT)*

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 6-inches in thickness.

### *Thin Whitetopping (TWT)*

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

### *Ultra-Thin Whitetopping (UTW)*

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.



## 2.4 Airfield Pavement Work History

### 2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

1. Location and Limits of Work.
2. Types and Severity of Distresses Repaired.
3. Type of Work.
4. Cost of Work.
5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

## 2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

## 2.6 Airfield Pavement Condition Index (PCI) Survey

### 2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)"**, the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

## 2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

*Table 2.6.2-1 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields*

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age

**Table 2.6.2-1 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields**

Classification by Possible Causes				
Load	Climate / Durability	Moisture / Drainage	Others	
<ul style="list-style-type: none"> <li>• Alligator Cracking</li> <li>• Corrugation</li> <li>• Depression</li> <li>• Patching of Load-based distress</li> <li>• Polished Aggregate</li> <li>• Rutting</li> <li>• Slippage Cracking</li> </ul>	<ul style="list-style-type: none"> <li>• Bleeding</li> <li>• Block Cracking</li> <li>• Joint Reflection Cracking</li> <li>• L/T Cracking</li> <li>• Patching of climate / durability-caused distresses</li> <li>• Shoving from PCC</li> <li>• Raveling</li> <li>• Weathering</li> <li>• Swelling</li> </ul>	<ul style="list-style-type: none"> <li>• Alligator Cracking</li> <li>• Depression</li> <li>• Patching of moisture / drainage caused distress</li> <li>• Swelling</li> <li>• Raveling</li> <li>• Weathering</li> </ul>	<ul style="list-style-type: none"> <li>• Oil Spillage</li> <li>• Jet Blast Erosion</li> <li>• Polished Aggregate</li> </ul>	

**Table 2.6.2-1 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields**

Classification by Possible Effects				
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements	
<ul style="list-style-type: none"> <li>• Corrugation</li> <li>• Depression</li> <li>• Rutting</li> <li>• Shoving of asphalt pavement</li> <li>• Swelling</li> <li>• Raveling</li> <li>• Weathering</li> </ul>	<ul style="list-style-type: none"> <li>• Bleeding</li> <li>• Depression</li> <li>• Polished Aggregate</li> <li>• Rutting</li> </ul>	<ul style="list-style-type: none"> <li>• Block Cracking</li> <li>• Joint Reflection Cracking</li> <li>• L/T Cracking</li> <li>• Slippage Cracking</li> </ul>	<ul style="list-style-type: none"> <li>• All Distresses</li> </ul>	

**Table 2.6.2-2 (a) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields**

Distress	Common Distress Mechanisms
<b>Blowup</b>	Climate / ASR
<b>Corner Break</b>	Load Repetition / Curling Stresses
<b>Linear Cracking</b>	Load Repetition / Curling Stresses / Shrinkage Stresses
<b>Durability Cracking</b>	Freeze-Thaw Cycling
<b>Joint Seal Damage</b>	Material Deterioration / Construction Quality / Age
<b>Small Patch</b>	Pavement Repair
<b>Large Patch/Utility Cut</b>	Utility / Pavement Repair
<b>Popout</b>	Freeze-Thaw Cycling / ASR / Material Quality
<b>Pumping</b>	Load Repetition / Poor Joint Sealant
<b>Scaling</b>	Construction Quality / Freeze-Thaw Cycling
<b>Faulting</b>	Subgrade Quality / ASR / Inadequate Load Transfer
<b>Shattered Slab</b>	Overloading
<b>Shrinkage Cracking</b>	Construction Quality / Climate
<b>Joint Spalling</b>	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
<b>Corner Spalling</b>	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
<b>Alkali-Silica Reaction (ASR)</b>	Construction Quality / Climate / Chemical Reaction

**Table 2.6.2-2 (b) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields**

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> <li>• Corner Break</li> <li>• Shattered Slab</li> <li>• L/T/D Cracking</li> <li>• Pumping</li> <li>• Patching of Load-associated distress</li> <li>• Spalling</li> </ul>	<ul style="list-style-type: none"> <li>• Blowup</li> <li>• "D" Cracking</li> <li>• Joint Seal Damage</li> <li>• Popouts</li> <li>• Scaling</li> <li>• Patch of Climate/Durability-associated distress</li> <li>• Shrinkage Cracking</li> <li>• Spalling</li> <li>• L/T/D Cracking</li> </ul>	<ul style="list-style-type: none"> <li>• Corner Break</li> <li>• Shattered Slab</li> <li>• Pumping</li> <li>• Patching of Moisture/Drainage-associated distress</li> </ul>	<ul style="list-style-type: none"> <li>• Settlement / Faulting</li> </ul>

**Table 2.6.2-2 (c) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields**

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> <li>• Blowup</li> <li>• Corner Break</li> <li>• L/T/D Cracking</li> <li>• Shattered Slab</li> <li>• Settlement / Faulting</li> <li>• Spalling</li> </ul>	<ul style="list-style-type: none"> <li>• Settlement / Faulting</li> <li>• Spalling</li> </ul>	<ul style="list-style-type: none"> <li>• Corner Break</li> <li>• L/T/D Cracking</li> <li>• "D" Cracking</li> <li>• Joint Seal Damage</li> <li>• Shattered Slab</li> <li>• Popouts</li> <li>• Scaling</li> </ul>	<ul style="list-style-type: none"> <li>• All distresses</li> </ul>

### 2.6.3 PCI Survey Inspection Procedures

#### *Inspection Sampling Rate*

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

*Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete*

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤20	10% but ≤10

*Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete*

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤20	10% but ≤10

## 2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in an adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

### Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured “(52) Weathering and Raveling” distress has been separated into two distresses “(52) Raveling” and “(57) Weathering.” Previously, areas that were recorded as “Weathering and Raveling” were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where “Weathering” only exists and does not meet the definition of “Raveling,” the PCI deduction is not as high as the former “Weathering and Raveling.” Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling,” may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

### Rigid Portland Cement Concrete Pavement Distress Updates

The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR.” As a result the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling,” and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, “(73) Shrinkage Cracks” has been redefined as “(73) Shrinkage Cracking”. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage develops when there is rapid loss of water in the surface of recently placed pavement or can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Distress Updates to Reflect ASTM 5340-12				
Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/ APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of ‘Weathering and Raveling’	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of ‘Weathering and Raveling’	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of ‘Weathering and Raveling’	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Crazing - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Crazing - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Crazing - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of ‘Scaling, Map Cracking, and Crazing’	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of ‘Scaling, Map Cracking, and Crazing’	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of ‘Scaling, Map Cracking, and Crazing’	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as ‘Scaling, Map Cracking, and Crazing’ may now be identified as ‘Shrinkage Cracking’

# **Chapter 3**



# Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

## 3.1 Airfield Pavement Network Information

### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction


Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1-1** and **Figure 3.1.1-2** provides an inset view of the 2017 Airfield Pavement Network Definition Exhibit and the 2017 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.

*Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction*


Year	General Work Description
2015	TW E, TW E1 - New Construction: 5" P-401, 13" P-211, P-152
	AP E - New Construction: 5" P-401, 11" P-211, P-152
	AP E - New Construction: 10" P-501, 6" P-306, 6" P-154, P-152

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.

Figure 3.1.1-1 2017 Airfield Pavement Network Definition Exhibit




The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.

**Figure 3.1.1-2 2017 Airfield Pavement System Inventory Exhibit**

The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections since any major construction activity has occurred during the PCI Survey inspection. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

*Figure 3.1.2 Average Age of Pavements at Inspection*


The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.



### 3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

*Figure 3.1.3 Airfield Pavement Functional Classification Use by Area*





### 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.

*Figure 3.1.4 (a) Pavement Surface Type by Area (SF)*







Figure 3.1.4 (b) Pavement Surface Type by Area (%)

## Pavement Surface Type by Area (%)



### 3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	EAST APRON	AP E	APRON	4405	212	125	26,675	AC	1/1/2015
VQQ	EAST APRON	AP E	APRON	4410	300	200	60,000	PCC	1/1/2015
VQQ	NORTH APRON	AP N	APRON	4103	230	300	62,610	PCC	1/1/1954
VQQ	NORTH APRON	AP N	APRON	4105	700	250	172,130	PCC	1/1/1988
VQQ	NORTH APRON	AP N	APRON	4110	762	387	290,625	PCC	1/1/1956
VQQ	NORTH APRON	AP N	APRON	4115	525	475	236,250	PCC	1/1/1965
VQQ	NORTH APRON	AP N	APRON	4117	110	125	14,325	PCC	1/1/1954
VQQ	NORTH APRON	AP N	APRON	4120	800	525	391,125	PCC	1/1/1954
VQQ	NORTH APRON	AP N	APRON	4125	2643	525	1,403,402	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4132	300	125	37,875	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4137	825	70	74,250	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4138	187.5	60	11,250	PCC	1/1/1953
VQQ	NORTH APRON	AP N	APRON	4140	525	200	102,688	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4150	375	237	105,074	PCC	1/1/1965
VQQ	NORTH APRON	AP N	APRON	4305	360	197	70,920	PCC	5/1/2005
VQQ	NORTH APRON	AP N	APRON	4310	460	75	43,214	PCC	1/1/2011
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5125	105	200	22,115	PCC	1/1/1954
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5130	105	200	22,115	PCC	1/1/1954
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5135	105	200	22,115	PCC	1/1/1954
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5140	105	200	22,115	PCC	1/1/1954
VQQ	NATIONAL GUARD WASH APRON	AP NAT GRD	APRON	5305	150	140	30,200	PCC	1/1/1976
VQQ	NATIONAL GUARD WASH APRON	AP NAT GRD	APRON	5310	1103	150	199,156	PCC	1/1/2010
VQQ	WEST PARKING APRON	AP W	APRON	4205	402	320	166,732	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4210	525	310	233,520	PCC	1/1/1959
VQQ	WEST PARKING APRON	AP W	APRON	4220	880	310	266,686	PCC	1/1/1960



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	WEST PARKING APRON	AP W	APRON	4225	320	105	35,000	PCC	1/1/1991
VQQ	WEST PARKING APRON	AP W	APRON	4230	270	115	26,250	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4235	320	30	13,730	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4240	1406	59	82,954	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4245	1704	60	102,240	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4250	555	500	285,584	PCC	1/1/1976
VQQ	WEST PARKING APRON	AP W	APRON	4255	320	30	19,950	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4260	320	200	50,613	PCC	1/1/1961
VQQ	WEST PARKING APRON	AP W	APRON	4265	710	140	99,400	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4270	710	58	41,180	PCC	1/1/1955
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5005	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5010	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5015	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5020	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5055	80	150	13,010	PCC	1/1/1955
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6205	500	100	50,000	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6210	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6215	6383	100	638,300	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6217	619	100	61,900	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6220	6383	100	638,300	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6222	619	100	61,900	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6225	500	100	50,200	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6230	1000	50	50,200	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6235	4500	100	450,000	PCC	1/1/1959
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6240	9000	50	450,000	PCC	1/1/1959
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6105	500	100	50,000	PCC	1/1/1951



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6110	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6115	10856	50	542,800	AAC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6120	5428	100	542,800	AAC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6125	300	100	30,000	PCC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6130	600	50	30,000	PCC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6135	500	100	50,000	PCC	1/1/1951
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6140	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6145	260	100	26,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6150	520	50	26,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6155	300	100	30,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6160	600	50	30,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6165	312	100	31,200	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6170	156	200	31,200	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6175	408	50	20,400	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6180	204	100	20,400	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6405	500	100	50,000	PCC	1/1/1951
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6410	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6414	200	100	56,500	AAC	1/1/2006
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6415	2835	100	283,572	AAC	1/1/1986
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6417	565	50	28,250	AAC	1/1/2006
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6420	3400	100	311,822	AAC	1/1/1986
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6425	337	100	33,700	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6430	337	100	33,700	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6435	275	100	20,000	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6440	550	50	20,000	AAC	1/1/2011
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6305	500	100	50,000	PCC	1/1/1956



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6310	1000	50	48,500	PCC	1/1/1956
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6315	6230	100	603,300	AAC	1/1/2010
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6317	200	100	20,000	AAC	1/1/2011
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6320	5850	100	585,202	AAC	1/1/2010
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6322	200	97	19,400	AAC	1/1/2011
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6325	570	100	57,000	PCC	1/1/1992
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6330	1140	50	55,290	PCC	1/1/1992
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6335	500	100	50,000	PCC	1/1/1956
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6340	1000	50	48,500	PCC	1/1/1956
VQQ	TAXIWAY A	TW A	TAXIWAY	105	900	75	67,381	PCC	1/1/1958
VQQ	TAXIWAY A	TW A	TAXIWAY	110	3600	75	269,943	PCC	1/1/1959
VQQ	TAXIWAY A	TW A	TAXIWAY	115	700	75	54,396	PCC	1/1/1951
VQQ	TAXIWAY A	TW A	TAXIWAY	117	120	75	27,484	AAC	1/1/2011
VQQ	TAXIWAY A	TW A	TAXIWAY	120	250	75	18,750	AAC	1/1/2011
VQQ	TAXIWAY A	TW A	TAXIWAY	125	100	100	19,405	AAC	1/1/2011
VQQ	TAXIWAY A	TW A	TAXIWAY	130	6100	75	457,575	PCC	1/1/1951
VQQ	TAXIWAY A1	TW A1	TAXIWAY	505	500	150	77,280	PCC	1/1/1951
VQQ	TAXIWAY A1	TW A1	TAXIWAY	510	360	150	58,667	PCC	1/1/1951
VQQ	TAXIWAY A1	TW A1	TAXIWAY	515	300	210	67,256	PCC	1/1/1954
VQQ	TAXIWAY A2	TW A2	TAXIWAY	603	300	75	26,792	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	605	150	75	11,684	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	607	100	75	7,608	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	608	50	75	7,608	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	610	75	50	4,184	APC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	615	260	75	23,980	PCC	1/1/1954
VQQ	TAXIWAY A2	TW A2	TAXIWAY	620	210	75	24,484	PCC	1/1/1954



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	TAXIWAY A3	TW A3	TAXIWAY	703	300	75	26,792	AAC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	705	150	75	11,684	AAC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	707	50	75	7,608	APC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	708	50	75	7,608	APC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	710	50	75	4,184	APC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	715	260	75	23,980	PCC	1/1/1951
VQQ	TAXIWAY A3	TW A3	TAXIWAY	720	210	75	24,484	PCC	1/1/1951
VQQ	TAXIWAY A4	TW A4	TAXIWAY	805	360	150	57,662	PCC	1/1/1951
VQQ	TAXIWAY A4	TW A4	TAXIWAY	810	500	150	79,426	PCC	1/1/1951
VQQ	TAXIWAY A5	TW A5	TAXIWAY	1005	1050	150	166,214	PCC	1/1/1958
VQQ	TAXIWAY B	TW B	TAXIWAY	205	4680	75	355,476	PCC	1/1/1951
VQQ	TAXIWAY B	TW B	TAXIWAY	208	100	130	19,400	AAC	1/1/2011
VQQ	TAXIWAY B	TW B	TAXIWAY	210	150	75	11,684	AAC	1/1/2011
VQQ	TAXIWAY B	TW B	TAXIWAY	212	100	75	38,584	AAC	1/1/2011
VQQ	TAXIWAY B	TW B	TAXIWAY	215	2200	75	165,208	PCC	1/1/1951
VQQ	TAXIWAY B1	TW B1	TAXIWAY	1105	370	150	56,522	PCC	1/1/1951
VQQ	TAXIWAY B1	TW B1	TAXIWAY	1110	500	150	77,371	PCC	1/1/1956
VQQ	TAXIWAY B1	TW B1	TAXIWAY	1115	200	150	30,000	PCC	1/1/1951
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1203	130	100	11,792	AAC	1/1/2011
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1205	300	75	22,500	AAC	1/1/2011
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1207	220	75	23,696	AAC	1/1/2011
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1210	240	75	23,980	PCC	1/1/1951
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1215	215	75	24,522	PCC	1/1/1951
VQQ	TAXIWAY B3	TW B3	TAXIWAY	1405	370	150	58,667	PCC	1/1/1951
VQQ	TAXIWAY B3	TW B3	TAXIWAY	1410	500	150	77,505	PCC	1/1/1956
VQQ	TAXIWAY C	TW C	TAXIWAY	305	2400	75	175,845	PCC	1/1/1951



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	TAXIWAY C	TW C	TAXIWAY	310	1700	80	136,320	PCC	1/1/1954
VQQ	TAXIWAY C	TW C	TAXIWAY	315	865	50	44,457	AC	1/1/1960
VQQ	TAXIWAY D	TW D	TAXIWAY	405	5460	75	435,222	PCC	1/1/1951
VQQ	TAXIWAY D	TW D	TAXIWAY	410	360	75	29,146	PCC	5/1/2005
VQQ	TAXIWAY D	TW D	TAXIWAY	415	1645	75	123,375	AC	1/1/2009
VQQ	TAXIWAY D	TW D	TAXIWAY	420	400	100	31,875	AC	1/1/2008
VQQ	TAXIWAY D2	TW D2	TAXIWAY	905	600	100	59,738	AC	1/1/2008
VQQ	TAXIWAY E	TW E	TAXIWAY	1610	3040	75	228,000	AC	1/1/2015
VQQ	TAXIWAY E1	TW E1	TAXIWAY	1605	1016	95	99,253	AC	1/1/2015
VQQ	TAXIWAY M	TW M	TAXIWAY	1305	210	75	22,376	PCC	1/1/1951



PAGE INTENTIONALLY LEFT BLANK

# **Chapter 4**



# Chapter 4 – Airfield Pavement Condition


The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

## 4.1 Airfield Pavement Condition Index (Latest Inspection)

### 4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.

*Figure 4.1.1 Latest Condition – Overall Network*



### 4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (c)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.

Figure 4.1.2 (a) Latest Condition – Runway Pavements




Figure 4.1.2 (b) Latest Condition – Taxiway Pavements





Figure 4.1.2 (c) Latest Condition – Apron Pavements





#### 4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement.

**Appendix C Technical Exhibits** provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.



Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
VQQ	AP E	EAST APRON	APRON	4405	26,675	AC	100	Good	0%	0%	0%	0	5
VQQ	AP E	EAST APRON	APRON	4410	60,000	PCC	100	Good	0%	0%	0%	0	20
VQQ	AP N	NORTH APRON	APRON	4103	62,610	PCC	73	Satisfactory	7%	0%	93%	2	15
VQQ	AP N	NORTH APRON	APRON	4105	172,130	PCC	71	Satisfactory	29%	2%	69%	5	47
VQQ	AP N	NORTH APRON	APRON	4110	290,625	PCC	56	Fair	25%	11%	64%	8	80
VQQ	AP N	NORTH APRON	APRON	4115	236,250	PCC	78	Satisfactory	28%	2%	70%	7	63
VQQ	AP N	NORTH APRON	APRON	4117	14,325	PCC	88	Good	0%	0%	100%	1	4
VQQ	AP N	NORTH APRON	APRON	4120	391,125	PCC	73	Satisfactory	5%	3%	92%	10	105
VQQ	AP N	NORTH APRON	APRON	4125	1,403,402	PCC	79	Satisfactory	7%	0%	93%	10	376
VQQ	AP N	NORTH APRON	APRON	4132	37,875	PCC	75	Satisfactory	0%	0%	100%	2	8
VQQ	AP N	NORTH APRON	APRON	4137	74,250	PCC	68	Fair	5%	34%	61%	3	20
VQQ	AP N	NORTH APRON	APRON	4138	11,250	PCC	74	Satisfactory	8%	0%	92%	1	3
VQQ	AP N	NORTH APRON	APRON	4140	102,688	PCC	71	Satisfactory	6%	0%	94%	3	28
VQQ	AP N	NORTH APRON	APRON	4150	105,074	PCC	75	Satisfactory	7%	0%	93%	3	26
VQQ	AP N	NORTH APRON	APRON	4305	70,920	PCC	95	Good	37%	0%	63%	3	18
VQQ	AP N	NORTH APRON	APRON	4310	43,214	PCC	99	Good	0%	0%	100%	2	11
VQQ	AP N RFUEL	N HOT REFUELING AND COMPASS ROSE AP	APRON	5125	22,115	PCC	76	Satisfactory	8%	0%	92%	1	6
VQQ	AP N RFUEL	N HOT REFUELING AND COMPASS ROSE AP	APRON	5130	22,115	PCC	81	Satisfactory	10%	0%	90%	1	6
VQQ	AP N RFUEL	N HOT REFUELING AND COMPASS ROSE AP	APRON	5135	22,115	PCC	62	Fair	4%	18%	78%	1	6
VQQ	AP N RFUEL	N HOT REFUELING AND COMPASS ROSE AP	APRON	5140	22,115	PCC	44	Poor	10%	0%	90%	1	6
VQQ	AP NAT GRD	NATIONAL GUARD WASH APRON	APRON	5305	30,200	PCC	88	Good	16%	0%	84%	2	8
VQQ	AP NAT GRD	NATIONAL GUARD WASH APRON	APRON	5310	199,156	PCC	93	Good	0%	0%	100%	6	54
VQQ	AP W	WEST PARKING APRON	APRON	4205	166,732	PCC	72	Satisfactory	6%	12%	82%	6	59
VQQ	AP W	WEST PARKING APRON	APRON	4210	233,520	PCC	77	Satisfactory	7%	0%	93%	7	64
VQQ	AP W	WEST PARKING APRON	APRON	4220	266,686	PCC	76	Satisfactory	7%	0%	93%	8	72
VQQ	AP W	WEST PARKING APRON	APRON	4225	35,000	PCC	14	Serious	5%	76%	19%	1	6
VQQ	AP W	WEST PARKING APRON	APRON	4230	26,250	PCC	12	Serious	1%	87%	12%	1	6
VQQ	AP W	WEST PARKING APRON	APRON	4235	13,730	PCC	12	Serious	8%	92%	0%	1	3
VQQ	AP W	WEST PARKING APRON	APRON	4240	82,954	PCC	75	Satisfactory	0%	0%	100%	5	32
VQQ	AP W	WEST PARKING APRON	APRON	4245	102,240	PCC	75	Satisfactory	0%	0%	100%	4	38
VQQ	AP W	WEST PARKING APRON	APRON	4250	285,584	PCC	72	Satisfactory	0%	4%	96%	8	76
VQQ	AP W	WEST PARKING APRON	APRON	4255	19,950	PCC	9	Failed	5%	81%	14%	1	3
VQQ	AP W	WEST PARKING APRON	APRON	4260	50,613	PCC	77	Satisfactory	0%	0%	100%	1	12
VQQ	AP W	WEST PARKING APRON	APRON	4265	99,400	PCC	80	Satisfactory	0%	0%	100%	5	36
VQQ	AP W	WEST PARKING APRON	APRON	4270	41,180	PCC	73	Satisfactory	0%	0%	100%	2	12
VQQ	AP W RFUEL	W HOT REFUELING AND COMPASS ROSE AP	APRON	5005	22,135	PCC	78	Satisfactory	9%	0%	91%	1	6



Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
VQQ	AP W RFUEL	W HOT REFUELING AND COMPASS ROSE AP	APRON	5010	22,135	PCC	72	Satisfactory	7%	17%	76%	1	6
VQQ	AP W RFUEL	W HOT REFUELING AND COMPASS ROSE AP	APRON	5015	22,135	PCC	83	Satisfactory	11%	0%	89%	1	6
VQQ	AP W RFUEL	W HOT REFUELING AND COMPASS ROSE AP	APRON	5020	22,135	PCC	43	Poor	2%	18%	80%	1	6
VQQ	AP W RFUEL	W HOT REFUELING AND COMPASS ROSE AP	APRON	5055	13,010	PCC	30	Very Poor	7%	63%	30%	1	2
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6205	50,000	PCC	79	Satisfactory	0%	0%	100%	4	14
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6210	50,000	PCC	83	Satisfactory	0%	0%	100%	4	14
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6215	638,300	AAC	82	Satisfactory	67%	26%	7%	19	128
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6217	61,900	AAC	79	Satisfactory	100%	0%	0%	3	12
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6220	638,300	AAC	86	Good	58%	34%	8%	18	128
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6222	61,900	AAC	75	Satisfactory	88%	0%	12%	3	12
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6225	50,200	PCC	72	Satisfactory	7%	5%	88%	4	14
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6230	50,200	PCC	82	Satisfactory	10%	0%	90%	4	14
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6235	450,000	PCC	80	Satisfactory	0%	7%	93%	20	120
VQQ	RW 18L-36R	RUNWAY 18L-36R	RUNWAY	6240	450,000	PCC	85	Satisfactory	0%	6%	94%	20	120
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6105	50,000	PCC	79	Satisfactory	0%	0%	100%	4	14
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6110	50,000	PCC	77	Satisfactory	0%	0%	100%	4	14
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6115	542,800	AAC	30	Very Poor	66%	19%	15%	20	108
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6120	542,800	AAC	33	Very Poor	86%	0%	14%	20	108
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6125	30,000	PCC	74	Satisfactory	45%	0%	55%	3	8
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6130	30,000	PCC	88	Good	91%	0%	9%	3	8
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6135	50,000	PCC	74	Satisfactory	6%	0%	94%	5	14
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6140	50,000	PCC	84	Satisfactory	10%	0%	90%	4	14
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6145	26,000	AAC	91	Good	100%	0%	0%	2	6
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6150	26,000	AAC	93	Good	100%	0%	0%	2	6
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6155	30,000	AAC	89	Good	100%	0%	0%	2	6
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6160	30,000	AAC	88	Good	92%	0%	8%	2	6
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6165	31,200	AAC	87	Good	100%	0%	0%	2	6
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6170	31,200	AAC	88	Good	100%	0%	0%	2	6
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6175	20,400	AAC	74	Satisfactory	94%	0%	6%	1	4
VQQ	RW 18R-36L	RUNWAY 18R-36L	RUNWAY	6180	20,400	AAC	88	Good	100%	0%	0%	2	4
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6405	50,000	PCC	81	Satisfactory	0%	0%	100%	4	14
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6410	50,000	PCC	77	Satisfactory	28%	0%	72%	4	14
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6414	56,500	AAC	51	Poor	65%	32%	3%	3	12
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6415	283,572	AAC	27	Very Poor	75%	18%	7%	12	56
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6417	28,250	AAC	59	Fair	96%	0%	4%	2	6
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6420	311,822	AAC	33	Very Poor	86%	0%	14%	13	62
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6425	33,700	AAC	88	Good	100%	0%	0%	2	6




Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6430	33,700	AAC	91	Good	100%	0%	0%	2	6
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6435	20,000	AAC	92	Good	100%	0%	0%	2	4
VQQ	RW 9L-27R	RUNWAY 9L-27R	RUNWAY	6440	20,000	AAC	88	Good	100%	0%	0%	2	4
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6305	50,000	PCC	76	Satisfactory	0%	0%	100%	4	14
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6310	48,500	PCC	79	Satisfactory	0%	0%	100%	4	14
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6315	603,300	AAC	76	Satisfactory	99%	0%	1%	20	120
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6317	20,000	AAC	76	Satisfactory	94%	0%	6%	1	4
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6320	585,202	AAC	84	Satisfactory	93%	0%	7%	20	120
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6322	19,400	AAC	71	Satisfactory	39%	0%	61%	1	4
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6325	57,000	PCC	89	Good	0%	0%	100%	5	16
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6330	55,290	PCC	89	Good	0%	0%	100%	5	16
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6335	50,000	PCC	78	Satisfactory	0%	0%	100%	4	14
VQQ	RW 9R-27L	RUNWAY 9R-27L	RUNWAY	6340	48,500	PCC	74	Satisfactory	7%	0%	93%	4	14
VQQ	TW A	TAXIWAY A	TAXIWAY	105	67,381	PCC	62	Fair	0%	6%	94%	3	16
VQQ	TW A	TAXIWAY A	TAXIWAY	110	269,943	PCC	75	Satisfactory	0%	0%	100%	6	60
VQQ	TW A	TAXIWAY A	TAXIWAY	115	54,396	PCC	86	Good	0%	0%	100%	2	12
VQQ	TW A	TAXIWAY A	TAXIWAY	117	27,484	AAC	78	Satisfactory	49%	0%	51%	1	9
VQQ	TW A	TAXIWAY A	TAXIWAY	120	18,750	AAC	91	Good	100%	0%	0%	1	5
VQQ	TW A	TAXIWAY A	TAXIWAY	125	19,405	AAC	81	Satisfactory	100%	0%	0%	1	6
VQQ	TW A	TAXIWAY A	TAXIWAY	130	457,575	PCC	82	Satisfactory	0%	0%	100%	10	102
VQQ	TW A1	TAXIWAY A1	TAXIWAY	505	77,280	PCC	84	Satisfactory	0%	0%	100%	3	22
VQQ	TW A1	TAXIWAY A1	TAXIWAY	510	58,667	PCC	84	Satisfactory	0%	0%	100%	3	17
VQQ	TW A1	TAXIWAY A1	TAXIWAY	515	67,256	PCC	74	Satisfactory	6%	0%	94%	3	20
VQQ	TW A2	TAXIWAY A2	TAXIWAY	603	26,792	AAC	90	Good	100%	0%	0%	1	8
VQQ	TW A2	TAXIWAY A2	TAXIWAY	605	11,684	AAC	90	Good	100%	0%	0%	1	3
VQQ	TW A2	TAXIWAY A2	TAXIWAY	607	7,608	AAC	91	Good	100%	0%	0%	1	3
VQQ	TW A2	TAXIWAY A2	TAXIWAY	608	7,608	AAC	94	Good	100%	0%	0%	1	3
VQQ	TW A2	TAXIWAY A2	TAXIWAY	610	4,184	APC	94	Good	100%	0%	0%	1	1
VQQ	TW A2	TAXIWAY A2	TAXIWAY	615	23,980	PCC	85	Satisfactory	0%	0%	100%	2	7
VQQ	TW A2	TAXIWAY A2	TAXIWAY	620	24,484	PCC	72	Satisfactory	7%	26%	67%	2	8
VQQ	TW A3	TAXIWAY A3	TAXIWAY	703	26,792	AAC	94	Good	100%	0%	0%	1	8
VQQ	TW A3	TAXIWAY A3	TAXIWAY	705	11,684	AAC	92	Good	100%	0%	0%	1	3
VQQ	TW A3	TAXIWAY A3	TAXIWAY	707	7,608	APC	92	Good	100%	0%	0%	1	3
VQQ	TW A3	TAXIWAY A3	TAXIWAY	708	7,608	APC	94	Good	100%	0%	0%	1	3
VQQ	TW A3	TAXIWAY A3	TAXIWAY	710	4,184	APC	94	Good	100%	0%	0%	1	1
VQQ	TW A3	TAXIWAY A3	TAXIWAY	715	23,980	PCC	81	Satisfactory	0%	0%	100%	2	7
VQQ	TW A3	TAXIWAY A3	TAXIWAY	720	24,484	PCC	73	Satisfactory	0%	0%	100%	2	8



Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI Pct Climate	PCI Pct Load	PCI Pct Other	Sample Units Inspected	Total Sample Units in Section
VQQ	TW A4	TAXIWAY A4	TAXIWAY	805	57,662	PCC	77	Satisfactory	0%	0%	100%	3	17
VQQ	TW A4	TAXIWAY A4	TAXIWAY	810	79,426	PCC	81	Satisfactory	9%	0%	91%	3	23
VQQ	TW A5	TAXIWAY A5	TAXIWAY	1005	166,214	PCC	75	Satisfactory	0%	18%	82%	5	45
VQQ	TW B	TAXIWAY B	TAXIWAY	205	355,476	PCC	83	Satisfactory	9%	0%	91%	9	82
VQQ	TW B	TAXIWAY B	TAXIWAY	208	19,400	AAC	89	Good	100%	0%	0%	1	7
VQQ	TW B	TAXIWAY B	TAXIWAY	210	11,684	AAC	91	Good	100%	0%	0%	1	3
VQQ	TW B	TAXIWAY B	TAXIWAY	212	38,584	AAC	92	Good	100%	0%	0%	2	12
VQQ	TW B	TAXIWAY B	TAXIWAY	215	165,208	PCC	81	Satisfactory	11%	0%	89%	4	37
VQQ	TW B1	TAXIWAY B1	TAXIWAY	1105	56,522	PCC	79	Satisfactory	9%	0%	91%	3	16
VQQ	TW B1	TAXIWAY B1	TAXIWAY	1110	77,371	PCC	77	Satisfactory	8%	0%	92%	3	22
VQQ	TW B1	TAXIWAY B1	TAXIWAY	1115	30,000	PCC	76	Satisfactory	7%	0%	93%	2	9
VQQ	TW B2	TAXIWAY B2	TAXIWAY	1203	11,792	AAC	88	Good	89%	0%	11%	1	4
VQQ	TW B2	TAXIWAY B2	TAXIWAY	1205	22,500	AAC	90	Good	100%	0%	0%	1	6
VQQ	TW B2	TAXIWAY B2	TAXIWAY	1207	23,696	AAC	91	Good	100%	0%	0%	2	8
VQQ	TW B2	TAXIWAY B2	TAXIWAY	1210	23,980	PCC	70	Fair	0%	52%	48%	1	6
VQQ	TW B2	TAXIWAY B2	TAXIWAY	1215	24,522	PCC	74	Satisfactory	7%	6%	87%	2	8
VQQ	TW B3	TAXIWAY B3	TAXIWAY	1405	58,667	PCC	76	Satisfactory	6%	0%	94%	3	17
VQQ	TW B3	TAXIWAY B3	TAXIWAY	1410	77,505	PCC	79	Satisfactory	0%	0%	100%	3	22
VQQ	TW C	TAXIWAY C	TAXIWAY	305	175,845	PCC	80	Satisfactory	10%	0%	90%	5	43
VQQ	TW C	TAXIWAY C	TAXIWAY	310	136,320	PCC	73	Satisfactory	7%	0%	93%	5	38
VQQ	TW C	TAXIWAY C	TAXIWAY	315	44,457	AC	30	Very Poor	100%	0%	0%	1	9
VQQ	TW D	TAXIWAY D	TAXIWAY	405	435,222	PCC	75	Satisfactory	7%	3%	90%	10	99
VQQ	TW D	TAXIWAY D	TAXIWAY	410	29,146	PCC	95	Good	37%	0%	63%	2	7
VQQ	TW D	TAXIWAY D	TAXIWAY	415	123,375	AC	86	Good	100%	0%	0%	4	32
VQQ	TW D	TAXIWAY D	TAXIWAY	420	31,875	AC	66	Fair	100%	0%	0%	1	8
VQQ	TW D2	TAXIWAY D2	TAXIWAY	905	59,738	AC	78	Satisfactory	100%	0%	0%	2	14
VQQ	TW E	TAXIWAY E	TAXIWAY	1610	228,000	AC	100	Good	0%	0%	0%	0	60
VQQ	TW E1	TAXIWAY E1	TAXIWAY	1605	99,253	AC	100	Good	0%	0%	0%	0	25
VQQ	TW M	TAXIWAY M	TAXIWAY	1305	22,376	PCC	81	Satisfactory	10%	0%	90%	2	7

**Figure 4.1.3** is an inset view of the 2017 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits**.

**Figure 4.1.3 2017 Airfield Pavement Condition Index Exhibit**





## 4.2 Summary of Pavement Condition Evaluation Results

### 4.2.1 Network-Level Observations

The field PCI Survey performed at Cecil Airport (VQQ) started on 05/22/17 and was completed on 05/25/17. The resulting overall average area-weighted PCI value was 73 a condition rating of Satisfactory. Cecil Airport consists of four runway facilities; Runway 09L-27R at 4,439-ft long by 200-ft wide, Runway 09R-27L at 8,0003-ft long by 200-ft wide, Runway 18L-36R at 12,503-ft long by 200-ft wide, and Runway 18R-36L at 8,0002-ft long by 200-ft wide.

Based on the FAA 5010 Report as of 07/20/2017 the Airport has reported 104,361 operations for 12 months ending 02/19/2016.

### 4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

#### *Runway 09L-27R*

Runway 9L-27R consists of 10 sections constructed of AC, AAC, and PCC. The last construction years range from 1951 to 2011. The average area-weighted PCI for Runway 9L-27R is 45 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Runway 9L-27R consist of Alligator Cracking, Bleeding, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Swelling, Weathering, Joint Seal Damage, Small Patch, Scaling, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### *Runway 09R-27L*

Runway 9R-27L consists of 10 sections constructed of AAC and PCC. The last construction years range from 1956 to 2011. The average area-weighted PCI for Runway 9R-27L is 80 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed in Runway 9R-27L consist of Bleeding, Depression, Longitudinal & Transverse Cracking, Raveling, Swelling, Weathering, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### *Runway 18L-36R*

Runway 18L-36R consists of 10 sections constructed of AAC and PCC. The last construction years range from 1951 to 2011. The average area-weighted PCI for Runway 18L-36R is 82 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Runway 18L-36R consist of Alligator Cracking, Bleeding, Depression, Longitudinal & Transverse Cracking, Swelling, Weathering, Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.



### Runway 18R-36L

Runway 18R-36L consists of 16 sections constructed of AAC and PCC. The last construction years range from 1951 to 2011. The average area-weighted PCI for Runway 18R-36L is 47 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Runway 18R-36L consist of Alligator Cracking, Bleeding, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Slippage Cracking, Swelling, Weathering, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

### Taxiway A

Taxiway A consists of 7 sections constructed of AAC and PCC. The last construction years range from 1951 to 2011. The average area-weighted PCI for Taxiway A is 78 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway A consist of Depression, Longitudinal & Transverse Cracking, Raveling, Weathering, Linear Cracking, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

### Taxiway A5

Taxiway A5 consists of 1 sections constructed of PCC. The last construction year for Taxiway A5 was 1958. The average area-weighted PCI for Taxiway A5 is 75 representing a Satisfactory condition rating. The pavement distresses observed were related to Load and Other distress classifications. Distresses observed in Taxiway A5 consist of Corner Break, Linear Cracking, Small Patch, Large Patch/Utility Cut, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

### Taxiway A2

Taxiway A2 consists of 7 sections constructed of AC, AAC, APC, and PCC. The last construction years range from 1954 to 2011. The average area-weighted PCI for Taxiway A2 is 85 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway A2 consist of Longitudinal & Transverse Cracking, Weathering, Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Shrinkage Cracking, and Corner Spall.

### Taxiway B2

Taxiway B2 consists of 5 sections constructed of AC, AAC, and PCC. The last construction years range from 1951 to 2011. The average area-weighted PCI for Taxiway B2 is 81 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in Taxiway B2 consist of Bleeding, Depression, Longitudinal & Transverse Cracking, Weathering, Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Shrinkage Cracking, Joint Spall, and Corner Spall.

### Taxiway D

Taxiway D consists of 4 sections constructed of AC and PCC. The last construction years range from 1951 to 2009. The average area-weighted PCI for Taxiway D is 77 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load,



and Other distress classifications. Distresses observed in Taxiway D consist of Longitudinal & Transverse Cracking, Patching, Weathering, Corner Break, Joint Seal Damage, Small Patch, Scaling, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

### *West Parking Apron*

West Parking Apron consists of 13 sections constructed of PCC. The last construction years range from 1955 to 1991. The average area-weighted PCI for West Parking Apron is 70 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in West Parking Apron consist of Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shattered Slab, Shrinkage Cracking, Joint Spall, and Corner Spall.

### *West Hot Refueling and Compass Rose Apron*

West Hot Refueling and Compass Rose Apron consists of 5 sections constructed of PCC. The last construction years range from 1955 to 1956. The average area-weighted PCI for W Hot Refueling and Compass Rose Apron is 64 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in W Hot Refueling and Compass Rose Apron consist of Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Shattered Slab, Shrinkage Cracking, Joint Spall, and Corner Spall.

### *North Hot Refueling and Compass Rose Apron*

N Hot Refueling and Compass Rose Apron consists of 4 sections constructed of PCC. The last construction year for N Hot Refueling and Compass Rose Apron was 1954. The average area-weighted PCI for N Hot Refueling and Compass Rose Apron is 65 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in N Hot Refueling and Compass Rose Apron consist of Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

### *North Apron*

North Apron consists of 14 sections constructed of PCC. The last construction years range from 1951 to 2011. The average area-weighted PCI for North Apron is 75 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed in North Apron consist of Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shrinkage Cracking, Joint Spall, Corner Spall, and ASR. The Alkali-Silica Reactivity distress was observed on PCC slabs that appear to be full-replacement slab repairs and not of the original pavement section.

*Figure 4.2.2 Pavement Condition Summary by Facility Use*

Facility Use	Average Area-Weighted PCI	Condition Rating
Runway	68	Fair
Taxiway	80	Satisfactory
Apron	74	Satisfactory



## 4.3 Forecasted Pavement Conditions

### 4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to developed forecasted PCI values based on historic trends and statistical models.

### 4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2018 through January 2027.

*Figure 4.3.2 (a) Forecasted Runway Pavement Performance*




Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance





#### 4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.

Table 4.3.3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	AP E	4405	100	95	93	92	90	88	87	85	84	82	80
VQQ	AP E	4410	100	90	87	84	82	79	77	74	72	70	68
VQQ	AP N	4103	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP N	4105	71	69	67	65	64	62	60	59	58	56	55
VQQ	AP N	4110	56	55	54	53	51	51	50	49	48	47	47
VQQ	AP N	4115	78	76	74	72	70	68	66	64	62	61	59
VQQ	AP N	4117	88	86	83	80	78	76	73	71	69	67	65
VQQ	AP N	4120	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP N	4125	79	77	75	72	70	68	66	65	63	61	60
VQQ	AP N	4132	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP N	4137	68	66	65	63	61	60	58	57	56	54	53
VQQ	AP N	4138	74	72	70	68	66	64	63	61	60	58	57
VQQ	AP N	4140	71	69	67	65	64	62	60	59	58	56	55
VQQ	AP N	4150	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP N	4305	95	93	90	87	84	81	79	76	74	72	70
VQQ	AP N	4310	99	97	93	90	87	85	82	79	77	75	72
VQQ	AP N RFUEL	5125	76	74	72	70	68	66	64	62	61	59	58
VQQ	AP N RFUEL	5130	81	79	77	74	72	70	68	66	64	63	61
VQQ	AP N RFUEL	5135	62	61	59	58	56	55	54	53	52	51	50
VQQ	AP N RFUEL	5140	44	43	43	43	42	42	42	42	42	41	41
VQQ	AP NAT GRD	5305	88	86	83	80	78	76	73	71	69	67	65
VQQ	AP NAT GRD	5310	93	91	88	85	82	80	77	75	73	71	69
VQQ	AP W	4205	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W	4210	77	75	73	71	69	67	65	63	62	60	59
VQQ	AP W	4220	76	74	72	70	68	66	64	62	61	59	58



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	AP W	4225	14	13	12	11	9	8	7	6	5	4	3
VQQ	AP W	4230	12	11	10	9	7	6	5	4	3	2	1
VQQ	AP W	4235	12	11	10	9	7	6	5	4	3	2	1
VQQ	AP W	4240	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP W	4245	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP W	4250	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W	4255	9	8	7	6	4	3	2	1	0	0	0
VQQ	AP W	4260	77	75	73	71	69	67	65	63	62	60	59
VQQ	AP W	4265	80	78	76	73	71	69	67	65	64	62	60
VQQ	AP W	4270	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP W RFUEL	5005	78	76	74	72	70	68	66	64	62	61	59
VQQ	AP W RFUEL	5010	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W RFUEL	5015	83	81	78	76	74	72	70	68	66	64	62
VQQ	AP W RFUEL	5020	43	42	42	42	42	41	41	41	41	41	41
VQQ	AP W RFUEL	5055	30	29	28	27	25	24	23	22	21	20	19
VQQ	RW 18L-36R	6205	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 18L-36R	6210	83	82	81	80	79	79	78	77	76	75	74
VQQ	RW 18L-36R	6215	82	80	77	75	73	70	68	67	65	64	63
VQQ	RW 18L-36R	6217	79	77	75	72	70	68	66	65	63	62	61
VQQ	RW 18L-36R	6220	86	84	82	79	77	74	72	70	68	66	64
VQQ	RW 18L-36R	6222	75	73	71	69	67	65	64	63	62	61	61
VQQ	RW 18L-36R	6225	72	71	70	69	68	68	67	66	65	64	63
VQQ	RW 18L-36R	6230	82	81	80	79	78	78	77	76	75	74	73
VQQ	RW 18L-36R	6235	80	79	78	77	76	76	75	74	73	72	71
VQQ	RW 18L-36R	6240	85	84	83	82	81	81	80	79	78	77	76
VQQ	RW 18R-36L	6105	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 18R-36L	6110	77	76	75	74	73	73	72	71	70	69	68



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	RW 18R-36L	6115	30	28	25	22	19	17	14	11	8	6	3
VQQ	RW 18R-36L	6120	33	31	29	26	23	20	17	15	12	9	6
VQQ	RW 18R-36L	6125	74	73	72	71	70	70	69	68	67	66	65
VQQ	RW 18R-36L	6130	88	87	86	85	84	84	83	82	81	80	79
VQQ	RW 18R-36L	6135	74	73	72	71	70	70	69	68	67	66	65
VQQ	RW 18R-36L	6140	84	83	82	81	80	80	79	78	77	76	75
VQQ	RW 18R-36L	6145	91	89	87	84	82	79	77	75	72	70	68
VQQ	RW 18R-36L	6150	93	91	89	87	84	82	79	77	74	72	70
VQQ	RW 18R-36L	6155	89	87	85	82	80	77	75	73	70	68	66
VQQ	RW 18R-36L	6160	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 18R-36L	6165	87	85	83	80	78	75	73	71	69	67	65
VQQ	RW 18R-36L	6170	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 18R-36L	6175	74	72	70	68	66	65	63	62	61	61	61
VQQ	RW 18R-36L	6180	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9L-27R	6405	81	80	79	78	77	77	76	75	74	73	72
VQQ	RW 9L-27R	6410	77	76	75	74	73	73	72	71	70	69	68
VQQ	RW 9L-27R	6414	51	49	46	43	39	36	33	31	28	25	23
VQQ	RW 9L-27R	6415	27	25	22	19	16	14	11	8	5	3	0
VQQ	RW 9L-27R	6417	59	58	57	55	53	50	47	44	41	38	35
VQQ	RW 9L-27R	6420	33	31	29	26	23	20	17	15	12	9	6
VQQ	RW 9L-27R	6425	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9L-27R	6430	91	89	87	84	82	79	77	75	72	70	68
VQQ	RW 9L-27R	6435	92	90	88	86	83	81	78	76	73	71	69
VQQ	RW 9L-27R	6440	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9R-27L	6305	76	75	74	73	72	72	71	70	69	68	67
VQQ	RW 9R-27L	6310	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 9R-27L	6315	76	74	72	70	68	66	64	63	62	61	61



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	RW 9R-27L	6317	76	74	72	70	68	66	64	63	62	61	61
VQQ	RW 9R-27L	6320	84	82	80	77	75	72	70	68	66	65	63
VQQ	RW 9R-27L	6322	71	69	67	66	64	63	62	61	61	60	60
VQQ	RW 9R-27L	6325	89	88	87	86	85	85	84	83	82	81	80
VQQ	RW 9R-27L	6330	89	88	87	86	85	85	84	83	82	81	80
VQQ	RW 9R-27L	6335	78	77	76	75	74	74	73	72	71	70	69
VQQ	RW 9R-27L	6340	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW A	105	62	61	60	59	58	58	57	56	55	54	53
VQQ	TW A	110	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW A	115	86	85	84	83	82	82	81	80	79	78	77
VQQ	TW A	117	78	77	75	74	73	72	71	70	69	68	68
VQQ	TW A	120	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW A	125	81	79	78	76	75	74	72	72	71	70	69
VQQ	TW A	130	82	81	80	79	78	78	77	76	75	74	73
VQQ	TW A1	505	84	83	82	81	80	80	79	78	77	76	75
VQQ	TW A1	510	84	83	82	81	80	80	79	78	77	76	75
VQQ	TW A1	515	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW A2	603	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW A2	605	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW A2	607	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW A2	608	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A2	610	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A2	615	85	84	83	82	81	81	80	79	78	77	76
VQQ	TW A2	620	72	71	70	69	68	68	67	66	65	64	63
VQQ	TW A3	703	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	705	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW A3	707	92	90	87	84	82	80	78	76	75	74	73



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	TW A3	708	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	710	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	715	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW A3	720	73	72	71	70	69	69	68	67	66	65	64
VQQ	TW A4	805	77	76	75	74	73	73	72	71	70	69	68
VQQ	TW A4	810	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW A5	1005	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW B	205	83	82	81	80	79	79	78	77	76	75	74
VQQ	TW B	208	89	87	84	82	80	78	76	75	74	73	72
VQQ	TW B	210	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW B	212	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW B	215	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW B1	1105	79	78	77	76	75	75	74	73	72	71	70
VQQ	TW B1	1110	77	76	75	74	73	73	72	71	70	69	68
VQQ	TW B1	1115	76	75	74	73	72	72	71	70	69	68	67
VQQ	TW B2	1203	88	86	83	81	79	77	76	75	73	72	71
VQQ	TW B2	1205	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW B2	1207	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW B2	1210	70	69	68	67	66	66	65	64	63	62	61
VQQ	TW B2	1215	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW B3	1405	76	75	74	73	72	72	71	70	69	68	67
VQQ	TW B3	1410	79	78	77	76	75	75	74	73	72	71	70
VQQ	TW C	305	80	79	78	77	76	76	75	74	73	72	71
VQQ	TW C	310	73	72	71	70	69	69	68	67	66	65	64
VQQ	TW C	315	30	29	28	28	27	25	24	22	20	17	14
VQQ	TW D	405	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW D	410	95	94	93	92	91	91	90	89	88	87	86



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	TW D	415	86	84	82	80	77	76	74	72	71	70	69
VQQ	TW D	420	66	65	64	63	62	62	61	60	58	57	56
VQQ	TW D2	905	78	76	75	73	72	70	69	68	67	66	65
VQQ	TW E	1610	100	93	90	88	85	83	81	78	76	75	73
VQQ	TW E1	1605	100	93	90	88	85	83	81	78	76	75	73
VQQ	TW M	1305	81	80	79	78	77	77	76	75	74	73	72



#### 4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA **AC 150/5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements** to determine structural and/or functional conditions at the time of project.

# **Chapter 5**



# Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- **Localized Maintenance and Repair** includes patching and crack sealing.
- **Global Treatments** includes surface seals and rejuvenators (flexible pavements).
- **Major Rehabilitation** includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

## 5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distress pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety ("stopgap") measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

### Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

### Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.

## 5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2.1** and **Table 5.2.2**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and the **FDOT Airfield Pavement Distress Repair Manual**. Additionally, the **Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements** was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

*Table 5.2-1 Localized Maintenance and Repair – Flexible Asphalt Concrete*

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	High	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft

Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L & T CR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2-2 Localized Maintenance and Repair – Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt



Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt

**Table 5.2-3 (a) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete**

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$6.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$3.00	SqFt

**Table 5.2-3 (b) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete**

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$100.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

\*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



## 5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in **5.2 Localized M&R Policy**. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. **Appendix B** provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to near-term Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3-1** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

*Table 5.3-1 Summary of Airport Localized M&R Planning Cost and Quantity at Network Level*

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	3,130	SqFt	\$ 39,120.00
FDOT - SURFACE SEAL	PREVENTIVE	2,600	SqFt	\$ 1,430.00
FDOT - CRACK SEALING - AC	PREVENTIVE	505	Ft	\$ 1,510.00
FDOT - GRINDING (LOCALIZED)	PREVENTIVE	90	Ft	\$ 180.00
FDOT - CRACK SEALING - PCC	PREVENTIVE	5,250	Ft	\$ 22,310.00
FDOT - JOINT SEAL - PCC	PREVENTIVE	437,265	Ft	\$ 1,202,470.00
FDOT - PATCHING - PCC PARTIAL DEPTH	PREVENTIVE	11,500	SqFt	\$ 827,690.00
FDOT - PATCHING - PCC FULL DEPTH	PREVENTIVE	17,440	SqFt	\$ 3,225,870.00
FDOT - SLAB REPLACEMENT - PCC	STOPGAP	42,775	SqFt	\$ 1,283,160.00
FDOT - SURFACE SEAL	STOPGAP	1,324,590	SqFt	\$ 728,530.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	347,120	SqFt	\$ 1,909,140.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	40,125	SqFt	\$ 501,540.00
FDOT - CRACK SEALING - AC	STOPGAP	89,535	Ft	\$ 268,600.00
FDOT - CRACK SEALING - PCC	STOPGAP	3,275	Ft	\$ 13,920.00
FDOT - JOINT SEAL - PCC	STOPGAP	47,020	Ft	\$ 129,310.00

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - PATCHING - PCC FULL DEPTH	STOPGAP	4,225	SqFt	\$ 780,960.00
FDOT - PATCHING - PCC PARTIAL DEPTH	STOPGAP	2,370	SqFt	\$ 170,580.00

The following **Table 5.3-2** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved “End Condition” of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

*Table 5.3-2 Summary of Airport Localized M&R Planning Cost and Quantity at Section Level*

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
VQQ	AP E	4405	26,675	100	100	\$ -
VQQ	AP E	4410	60,000	100	100	\$ -
VQQ	AP N	4103	62,610	73	80	\$ 34,820.00
VQQ	AP N	4105	172,130	71	76	\$ 82,060.00
VQQ	AP N	4110	290,625	56	71	\$ 452,410.00
VQQ	AP N	4115	236,250	78	80	\$ 48,120.00
VQQ	AP N	4117	14,325	88	88	\$ 40.00
VQQ	AP N	4120	391,125	73	77	\$ 301,440.00
VQQ	AP N	4125	1,403,402	79	81	\$ 1,038,370.00
VQQ	AP N	4132	37,875	75	76	\$ 25,230.00
VQQ	AP N	4137	74,250	68	74	\$ 76,450.00
VQQ	AP N	4138	11,250	74	78	\$ 4,120.00
VQQ	AP N	4140	102,688	71	74	\$ 45,320.00
VQQ	AP N	4150	105,074	75	77	\$ 34,490.00
VQQ	AP N	4305	70,920	95	97	\$ 24,520.00
VQQ	AP N	4310	43,214	99	99	\$ -
VQQ	AP N RFUEL	5125	22,115	76	86	\$ 12,580.00
VQQ	AP N RFUEL	5130	22,115	81	86	\$ 8,970.00
VQQ	AP N RFUEL	5135	22,115	62	69	\$ 14,320.00
VQQ	AP N RFUEL	5140	22,115	44	84	\$ 34,390.00
VQQ	AP NAT GRD	5305	30,200	88	90	\$ 7,780.00
VQQ	AP NAT GRD	5310	199,156	93	93	\$ -
VQQ	AP W	4205	166,732	72	76	\$ 28,950.00
VQQ	AP W	4210	233,520	77	80	\$ 36,320.00
VQQ	AP W	4220	266,686	76	79	\$ 119,040.00
VQQ	AP W	4225	35,000	14	55	\$ 450,480.00
VQQ	AP W	4230	26,250	12	54	\$ 598,830.00



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
VQQ	AP W	4235	13,730	12	100	\$ 396,800.00
VQQ	AP W	4240	82,954	75	78	\$ 11,100.00
VQQ	AP W	4245	102,240	75	76	\$ 3,810.00
VQQ	AP W	4250	285,584	72	76	\$ 1,728,890.00
VQQ	AP W	4255	19,950	9	67	\$ 87,900.00
VQQ	AP W	4260	50,613	77	80	\$ 16,100.00
VQQ	AP W	4265	99,400	80	82	\$ 6,080.00
VQQ	AP W	4270	41,180	73	80	\$ 5,910.00
VQQ	AP W RFUEL	5005	22,135	78	80	\$ 7,660.00
VQQ	AP W RFUEL	5010	22,135	72	74	\$ 7,820.00
VQQ	AP W RFUEL	5015	22,135	83	85	\$ 7,660.00
VQQ	AP W RFUEL	5020	22,135	43	60	\$ 316,400.00
VQQ	AP W RFUEL	5055	13,010	30	60	\$ 9,070.00
VQQ	RW 18L-36R	6205	50,000	79	80	\$ 770.00
VQQ	RW 18L-36R	6210	50,000	83	83	\$ 60.00
VQQ	RW 18L-36R	6215	638,300	82	82	\$ 3,240.00
VQQ	RW 18L-36R	6217	61,900	79	81	\$ 280.00
VQQ	RW 18L-36R	6220	638,300	86	87	\$ 7,190.00
VQQ	RW 18L-36R	6222	61,900	75	76	\$ 4,710.00
VQQ	RW 18L-36R	6225	50,200	72	78	\$ 23,180.00
VQQ	RW 18L-36R	6230	50,200	82	83	\$ 4,400.00
VQQ	RW 18L-36R	6235	450,000	80	80	\$ 85,050.00
VQQ	RW 18L-36R	6240	450,000	85	85	\$ 2,550.00
VQQ	RW 18R-36L	6105	50,000	79	81	\$ 2,410.00
VQQ	RW 18R-36L	6110	50,000	77	80	\$ 49,560.00
VQQ	RW 18R-36L	6115	542,800	30	53	\$ 1,071,650.00
VQQ	RW 18R-36L	6120	542,800	33	51	\$ 946,900.00
VQQ	RW 18R-36L	6125	30,000	74	86	\$ 11,720.00
VQQ	RW 18R-36L	6130	30,000	88	98	\$ 10,360.00
VQQ	RW 18R-36L	6135	50,000	74	80	\$ 49,600.00
VQQ	RW 18R-36L	6140	50,000	84	87	\$ 8,310.00
VQQ	RW 18R-36L	6145	26,000	91	91	\$ -
VQQ	RW 18R-36L	6150	26,000	93	93	\$ -
VQQ	RW 18R-36L	6155	30,000	89	89	\$ -
VQQ	RW 18R-36L	6160	30,000	88	88	\$ -
VQQ	RW 18R-36L	6165	31,200	87	87	\$ -
VQQ	RW 18R-36L	6170	31,200	88	88	\$ -
VQQ	RW 18R-36L	6175	20,400	74	74	\$ -
VQQ	RW 18R-36L	6180	20,400	88	88	\$ -



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
VQQ	RW 9L-27R	6405	50,000	81	82	\$ 16,090.00
VQQ	RW 9L-27R	6410	50,000	77	80	\$ 10,060.00
VQQ	RW 9L-27R	6414	56,500	51	60	\$ 14,960.00
VQQ	RW 9L-27R	6415	283,572	27	55	\$ 662,300.00
VQQ	RW 9L-27R	6417	28,250	59	62	\$ 320.00
VQQ	RW 9L-27R	6420	311,822	33	54	\$ 558,720.00
VQQ	RW 9L-27R	6425	33,700	88	88	\$ -
VQQ	RW 9L-27R	6430	33,700	91	91	\$ -
VQQ	RW 9L-27R	6435	20,000	92	92	\$ -
VQQ	RW 9L-27R	6440	20,000	88	92	\$ 340.00
VQQ	RW 9R-27L	6305	50,000	76	78	\$ 1,520.00
VQQ	RW 9R-27L	6310	48,500	79	80	\$ 770.00
VQQ	RW 9R-27L	6315	603,300	76	77	\$ 1,170.00
VQQ	RW 9R-27L	6317	20,000	76	76	\$ -
VQQ	RW 9R-27L	6320	585,202	84	84	\$ 2,570.00
VQQ	RW 9R-27L	6322	19,400	71	81	\$ 12,810.00
VQQ	RW 9R-27L	6325	57,000	89	89	\$ 220.00
VQQ	RW 9R-27L	6330	55,290	89	89	\$ 260.00
VQQ	RW 9R-27L	6335	50,000	78	83	\$ 52,010.00
VQQ	RW 9R-27L	6340	48,500	74	77	\$ 13,790.00
VQQ	TW A	105	67,381	62	72	\$ 17,610.00
VQQ	TW A	110	269,943	75	78	\$ 149,320.00
VQQ	TW A	115	54,396	86	86	\$ 50.00
VQQ	TW A	117	27,484	78	84	\$ 8,660.00
VQQ	TW A	120	18,750	91	91	\$ -
VQQ	TW A	125	19,405	81	86	\$ 430.00
VQQ	TW A	130	457,575	82	84	\$ 25,430.00
VQQ	TW A1	505	77,280	84	85	\$ 2,670.00
VQQ	TW A1	510	58,667	84	84	\$ 40.00
VQQ	TW A1	515	67,256	74	78	\$ 22,330.00
VQQ	TW A2	603	26,792	90	90	\$ -
VQQ	TW A2	605	11,684	90	90	\$ -
VQQ	TW A2	607	7,608	91	91	\$ -
VQQ	TW A2	608	7,608	94	94	\$ -
VQQ	TW A2	610	4,184	94	94	\$ -
VQQ	TW A2	615	23,980	85	85	\$ -
VQQ	TW A2	620	24,484	72	77	\$ 22,830.00
VQQ	TW A3	703	26,792	94	94	\$ -
VQQ	TW A3	705	11,684	92	92	\$ -



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
VQQ	TW A3	707	7,608	92	92	\$ -
VQQ	TW A3	708	7,608	94	94	\$ -
VQQ	TW A3	710	4,184	94	94	\$ -
VQQ	TW A3	715	23,980	81	81	\$ 40.00
VQQ	TW A3	720	24,484	73	80	\$ 3,130.00
VQQ	TW A4	805	57,662	77	77	\$ 990.00
VQQ	TW A4	810	79,426	81	82	\$ 9,590.00
VQQ	TW A5	1005	166,214	75	78	\$ 250,000.00
VQQ	TW B	205	355,476	83	85	\$ 53,860.00
VQQ	TW B	208	19,400	89	89	\$ -
VQQ	TW B	210	11,684	91	91	\$ -
VQQ	TW B	212	38,584	92	92	\$ -
VQQ	TW B	215	165,208	81	83	\$ 60,630.00
VQQ	TW B1	1105	56,522	79	83	\$ 23,960.00
VQQ	TW B1	1110	77,371	77	84	\$ 38,560.00
VQQ	TW B1	1115	30,000	76	83	\$ 12,920.00
VQQ	TW B2	1203	11,792	88	87	\$ 730.00
VQQ	TW B2	1205	22,500	90	90	\$ -
VQQ	TW B2	1207	23,696	91	91	\$ -
VQQ	TW B2	1210	23,980	70	70	\$ 220.00
VQQ	TW B2	1215	24,522	74	79	\$ 4,590.00
VQQ	TW B3	1405	58,667	76	81	\$ 224,820.00
VQQ	TW B3	1410	77,505	79	82	\$ 2,660.00
VQQ	TW C	305	175,845	80	84	\$ 70,930.00
VQQ	TW C	310	136,320	73	77	\$ 62,600.00
VQQ	TW C	315	44,457	30	58	\$ 153,150.00
VQQ	TW D	405	435,222	75	80	\$ 158,150.00
VQQ	TW D	410	29,146	95	97	\$ 8,710.00
VQQ	TW D	415	123,375	86	86	\$ -
VQQ	TW D	420	31,875	66	66	\$ -
VQQ	TW D2	905	59,738	78	78	\$ -
VQQ	TW E	1610	228,000	100	100	\$ -
VQQ	TW E1	1605	99,253	100	100	\$ -
VQQ	TW M	1305	22,376	81	84	\$ 4,490.00



The following **Table 5.3-3** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

*Table 5.3-3 Summary of Localized Maintenance*

Work Category	Cost
Preventive	\$ 5,320,580.00
Stopgap	\$ 5,785,740.00
<b><i>Planning-Level Localized M&amp;R Needs =</i></b>	<b><i>\$ 11,106,320.00</i></b>

# **Chapter 6**



# Chapter 6 – Major Rehabilitation Planning

## 6.1 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1-1 and 6.1-2** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

*Figure 6.1-1 Major Rehabilitation Planning Decision Diagram, PCI  $\leq$  Critical PCI*







Figure 6.1-2 Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI



### 6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The **Critical PCI** concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

1. Develop a pavement performance model and refine a prediction model for the pavements considered.
2. Select a localized maintenance and repair policy to be used in developing a work plan.
3. Apply the selected localized policy to the pavement sections for a range of PCI.
4. Compute the unit cost per area for each PCI range.
5. Plot the cost versus the PCI.
6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

### 6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended **Minimum Service-Level PCI** for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

*Table 6.1.2 FDOT Recommended Minimum Service-Level PCI*

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	60	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)



## 6.2 Major Rehabilitation Policy

### 6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA **AC 150/5320-6F "Airport Pavement Design and Evaluation."** It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following **Tables 6.2.1 (a) and (b)** provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average GA Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

**Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete**

Rehabilitation Type	General Aviation (GA) Airport
<b>AC Restoration</b>  <i>Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.</i>	<b>75% Mill and Overlay</b> P-101 AC Milling (2") P-603 Bituminous Tack P-401 (HMA) (2")
<b>PCI = 41 to 65</b>	<b>25% AC Reconstruction</b> P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2")  <i>Excludes any paved shoulder features.</i>
<b>AC Reconstruction</b>  <i>Full-depth asphalt pavement section reconstruction.</i>	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (6") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (2")  <i>Excludes any paved shoulder features.</i>

**Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete**

Rehabilitation Type	General Aviation (GA) Airport
<b>PCC Restoration</b> <i>Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.</i> <b>PCI = 41 to 65</b>	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (10")  *Select Slabs (25%) **Crack Seal and Limited Patching
<b>PCC Reconstruction</b> <i>Full-depth rigid pavement section reconstruction.</i> <b>PCI = 40 or less</b>	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (6") P-211 Base (6") P-501 Rigid PCC (10")

**The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.**

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

## 6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs

provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

**Table 6.2.2 General Aviation Major Rehabilitation Planning-Level Unit Cost by Pavement Type**

Rehabilitation Type	PCI Range	Flexible Asphalt Concrete Cost Per SF	Rigid Portland Cement Concrete Cost per SF
Restoration	41 to 65	\$ 7.00	\$ 10.00
Reconstruction	0 to 40	\$ 9.00	\$ 15.00

*Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.*

## 6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

### 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.



Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	VQQ	AP N	4110	PCC	290,625	55	PCC Restoration	\$ 4,941,000.00
2018	VQQ	AP N RFUEL	5135	PCC	22,115	61	PCC Restoration	\$ 376,000.00
2018	VQQ	AP N RFUEL	5140	PCC	22,115	43	PCC Restoration	\$ 459,000.00
2018	VQQ	AP W	4225	PCC	35,000	13	PCC Reconstruction	\$ 806,000.00
2018	VQQ	AP W	4230	PCC	26,250	11	PCC Reconstruction	\$ 604,000.00
2018	VQQ	AP W	4235	PCC	13,730	11	PCC Reconstruction	\$ 316,000.00
2018	VQQ	AP W	4255	PCC	19,950	8	PCC Reconstruction	\$ 459,000.00
2018	VQQ	AP W RFUEL	5020	PCC	22,135	42	PCC Restoration	\$ 472,000.00
2018	VQQ	AP W RFUEL	5055	PCC	13,010	29	PCC Reconstruction	\$ 300,000.00
2018	VQQ	RW 18R-36L	6115	AAC	542,800	28	AC Reconstruction	\$ 7,599,000.00
2018	VQQ	RW 18R-36L	6120	AAC	542,800	31	AC Reconstruction	\$ 7,599,000.00
2018	VQQ	RW 9L-27R	6414	AAC	56,500	49	AC Restoration	\$ 634,000.00
2018	VQQ	RW 9L-27R	6415	AAC	283,572	25	AC Reconstruction	\$ 3,970,000.00
2018	VQQ	RW 9L-27R	6417	AAC	28,250	58	AC Restoration	\$ 311,000.00
2018	VQQ	RW 9L-27R	6420	AAC	311,822	31	AC Reconstruction	\$ 4,366,000.00
2018	VQQ	TW A	105	PCC	67,381	61	PCC Restoration	\$ 1,146,000.00
2018	VQQ	TW C	315	AC	44,457	29	AC Reconstruction	\$ 623,000.00
2019	VQQ	TW D	420	AC	31,875	64	AC Restoration	\$ 351,000.00
2020	VQQ	AP N	4137	PCC	74,250	63	PCC Restoration	\$ 1,263,000.00
2021	VQQ	AP N	4105	PCC	172,130	64	PCC Restoration	\$ 2,927,000.00
2021	VQQ	AP N	4140	PCC	102,688	64	PCC Restoration	\$ 1,746,000.00
2021	VQQ	RW 9R-27L	6322	AAC	19,400	64	AC Restoration	\$ 214,000.00
2022	VQQ	AP N	4103	PCC	62,610	64	PCC Restoration	\$ 1,065,000.00
2022	VQQ	AP N	4120	PCC	391,125	64	PCC Restoration	\$ 6,650,000.00
2022	VQQ	AP N	4138	PCC	11,250	64	PCC Restoration	\$ 192,000.00
2022	VQQ	AP W	4205	PCC	166,732	63	PCC Restoration	\$ 2,835,000.00
2022	VQQ	AP W	4250	PCC	285,584	63	PCC Restoration	\$ 4,856,000.00
2022	VQQ	AP W	4270	PCC	41,180	64	PCC Restoration	\$ 701,000.00
2022	VQQ	AP W RFUEL	5010	PCC	22,135	63	PCC Restoration	\$ 377,000.00
2023	VQQ	AP N	4132	PCC	37,875	63	PCC Restoration	\$ 644,000.00
2023	VQQ	AP N	4150	PCC	105,074	63	PCC Restoration	\$ 1,787,000.00
2023	VQQ	AP N RFUEL	5125	PCC	22,115	64	PCC Restoration	\$ 376,000.00
2023	VQQ	AP W	4220	PCC	266,686	64	PCC Restoration	\$ 4,534,000.00
2023	VQQ	AP W	4240	PCC	82,954	63	PCC Restoration	\$ 1,411,000.00
2023	VQQ	AP W	4245	PCC	102,240	63	PCC Restoration	\$ 1,739,000.00
2023	VQQ	RW 18L-36R	6222	AAC	61,900	64	AC Restoration	\$ 681,000.00
2023	VQQ	RW 18R-36L	6175	AAC	20,400	63	AC Restoration	\$ 225,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2023	VQQ	RW 9R-27L	6315	AAC	603,300	64	AC Restoration	\$ 6,637,000.00
2023	VQQ	RW 9R-27L	6317	AAC	20,000	64	AC Restoration	\$ 220,000.00
2024	VQQ	AP N	4115	PCC	236,250	64	PCC Restoration	\$ 4,017,000.00
2024	VQQ	AP W	4210	PCC	233,520	63	PCC Restoration	\$ 3,970,000.00
2024	VQQ	AP W	4260	PCC	50,613	63	PCC Restoration	\$ 861,000.00
2024	VQQ	AP W RFUEL	5005	PCC	22,135	64	PCC Restoration	\$ 377,000.00
2024	VQQ	TW B2	1210	PCC	23,980	64	PCC Restoration	\$ 408,000.00
2025	VQQ	AP N	4125	PCC	1,403,402	63	PCC Restoration	\$ 23,859,000.00
2025	VQQ	AP N RFUEL	5130	PCC	22,115	64	PCC Restoration	\$ 376,000.00
2025	VQQ	AP W	4265	PCC	99,400	64	PCC Restoration	\$ 1,690,000.00
2025	VQQ	RW 18L-36R	6217	AAC	61,900	63	AC Restoration	\$ 681,000.00
2026	VQQ	AP W RFUEL	5015	PCC	22,135	64	PCC Restoration	\$ 377,000.00
2026	VQQ	RW 18L-36R	6215	AAC	638,300	64	AC Restoration	\$ 7,022,000.00
2026	VQQ	RW 18L-36R	6225	PCC	50,200	64	PCC Restoration	\$ 854,000.00
2026	VQQ	TW A2	620	PCC	24,484	64	PCC Restoration	\$ 417,000.00
2027	VQQ	RW 18L-36R	6220	AAC	638,300	64	AC Restoration	\$ 7,022,000.00
2027	VQQ	RW 9R-27L	6320	AAC	585,202	63	AC Restoration	\$ 6,438,000.00
2027	VQQ	TW A3	720	PCC	24,484	64	PCC Restoration	\$ 417,000.00
2027	VQQ	TW C	310	PCC	136,320	64	PCC Restoration	\$ 2,318,000.00

\*All values have been rounded to the nearest thousand-dollar.

The following **Figure 6.3.1-1** summarizes the section-level major rehabilitation needs for a 10-year period between 2018 and 2027. **Figure 6.3.1-2** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.

Figure 6.3.1-1 10-Year Major Rehabilitation Needs by Program Year







Figure 6.3.1-2 10-Year Major Rehabilitation Needs by Program Year Exhibit



# **Chapter 7**



# Chapter 7 – Conclusion

## 7.1 Recommendations

### 7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and re-inspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

### 7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2018-2027. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

### 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- Develop a detailed preventive maintenance program for the airport.
- Further refine and implement the identified 10-year major rehabilitation needs.
- Maintain detailed records on pavement maintenance, construction, and inspection.
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



## 7.2 Supporting Documents

### *001 – Airfield Pavement Network Definition Exhibit*

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

### *002 – Airfield Pavement System Inventory Exhibit*

The Airfield Pavement System Inventory Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the **Airport Response Form** provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

### *003 – Airfield Pavement Condition Index Exhibit*

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

### *004 – Airfield Pavement Major Rehabilitation Exhibit*

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

### *Inspection Photograph Documentation*

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation**. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.



## 7.3 Conclusion

The FDOT SAPMP Update Phase 1 2016-2017 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars **150/5380-7B “Airport Pavement Management Program (PMP)”** and **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** FDOT’s implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**



# **Appendix A**

## **Airfield Pavement Analysis Tables**



Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	EAST APRON	AP E	APRON	4405	212	125	26,675	AC	1/1/2015
VQQ	EAST APRON	AP E	APRON	4410	300	200	60,000	PCC	1/1/2015
VQQ	NORTH APRON	AP N	APRON	4103	230	300	62,610	PCC	1/1/1954
VQQ	NORTH APRON	AP N	APRON	4105	700	250	172,130	PCC	1/1/1988
VQQ	NORTH APRON	AP N	APRON	4110	762	387	290,625	PCC	1/1/1956
VQQ	NORTH APRON	AP N	APRON	4115	525	475	236,250	PCC	1/1/1965
VQQ	NORTH APRON	AP N	APRON	4117	110	125	14,325	PCC	1/1/1954
VQQ	NORTH APRON	AP N	APRON	4120	800	525	391,125	PCC	1/1/1954
VQQ	NORTH APRON	AP N	APRON	4125	2643	525	1,403,402	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4132	300	125	37,875	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4137	825	70	74,250	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4138	187.5	60	11,250	PCC	1/1/1953
VQQ	NORTH APRON	AP N	APRON	4140	525	200	102,688	PCC	1/1/1951
VQQ	NORTH APRON	AP N	APRON	4150	375	237	105,074	PCC	1/1/1965
VQQ	NORTH APRON	AP N	APRON	4305	360	197	70,920	PCC	5/1/2005
VQQ	NORTH APRON	AP N	APRON	4310	460	75	43,214	PCC	1/1/2011
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5125	105	200	22,115	PCC	1/1/1954
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5130	105	200	22,115	PCC	1/1/1954
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5135	105	200	22,115	PCC	1/1/1954
VQQ	N HOT REFUELING AND COMPASS ROSE AP	AP N RFUEL	APRON	5140	105	200	22,115	PCC	1/1/1954
VQQ	NATIONAL GUARD WASH APRON	AP NAT GRD	APRON	5305	150	140	30,200	PCC	1/1/1976
VQQ	NATIONAL GUARD WASH APRON	AP NAT GRD	APRON	5310	1103	150	199,156	PCC	1/1/2010
VQQ	WEST PARKING APRON	AP W	APRON	4205	402	320	166,732	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4210	525	310	233,520	PCC	1/1/1959
VQQ	WEST PARKING APRON	AP W	APRON	4220	880	310	266,686	PCC	1/1/1960
VQQ	WEST PARKING APRON	AP W	APRON	4225	320	105	35,000	PCC	1/1/1991
VQQ	WEST PARKING APRON	AP W	APRON	4230	270	115	26,250	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4235	320	30	13,730	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4240	1406	59	82,954	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4245	1704	60	102,240	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4250	555	500	285,584	PCC	1/1/1976



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	WEST PARKING APRON	AP W	APRON	4255	320	30	19,950	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4260	320	200	50,613	PCC	1/1/1961
VQQ	WEST PARKING APRON	AP W	APRON	4265	710	140	99,400	PCC	1/1/1955
VQQ	WEST PARKING APRON	AP W	APRON	4270	710	58	41,180	PCC	1/1/1955
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5005	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5010	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5015	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5020	210	100	22,135	PCC	1/1/1956
VQQ	W HOT REFUELING AND COMPASS ROSE AP	AP W RFUEL	APRON	5055	80	150	13,010	PCC	1/1/1955
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6205	500	100	50,000	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6210	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6215	6383	100	638,300	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6217	619	100	61,900	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6220	6383	100	638,300	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6222	619	100	61,900	AAC	1/1/2011
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6225	500	100	50,200	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6230	1000	50	50,200	PCC	1/1/1951
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6235	4500	100	450,000	PCC	1/1/1959
VQQ	RUNWAY 18L-36R	RW 18L-36R	RUNWAY	6240	9000	50	450,000	PCC	1/1/1959
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6105	500	100	50,000	PCC	1/1/1951
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6110	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6115	10856	50	542,800	AAC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6120	5428	100	542,800	AAC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6125	300	100	30,000	PCC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6130	600	50	30,000	PCC	1/1/1986
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6135	500	100	50,000	PCC	1/1/1951
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6140	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6145	260	100	26,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6150	520	50	26,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6155	300	100	30,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6160	600	50	30,000	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6165	312	100	31,200	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6170	156	200	31,200	AAC	1/1/2011



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6175	408	50	20,400	AAC	1/1/2011
VQQ	RUNWAY 18R-36L	RW 18R-36L	RUNWAY	6180	204	100	20,400	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6405	500	100	50,000	PCC	1/1/1951
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6410	1000	50	50,000	PCC	1/1/1951
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6414	200	100	56,500	AAC	1/1/2006
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6415	2835	100	283,572	AAC	1/1/1986
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6417	565	50	28,250	AAC	1/1/2006
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6420	3400	100	311,822	AAC	1/1/1986
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6425	337	100	33,700	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6430	337	100	33,700	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6435	275	100	20,000	AAC	1/1/2011
VQQ	RUNWAY 9L-27R	RW 9L-27R	RUNWAY	6440	550	50	20,000	AAC	1/1/2011
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6305	500	100	50,000	PCC	1/1/1956
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6310	1000	50	48,500	PCC	1/1/1956
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6315	6230	100	603,300	AAC	1/1/2010
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6317	200	100	20,000	AAC	1/1/2011
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6320	5850	100	585,202	AAC	1/1/2010
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6322	200	97	19,400	AAC	1/1/2011
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6325	570	100	57,000	PCC	1/1/1992
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6330	1140	50	55,290	PCC	1/1/1992
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6335	500	100	50,000	PCC	1/1/1956
VQQ	RUNWAY 9R-27L	RW 9R-27L	RUNWAY	6340	1000	50	48,500	PCC	1/1/1956
VQQ	TAXIWAY A	TW A	TAXIWAY	105	900	75	67,381	PCC	1/1/1958
VQQ	TAXIWAY A	TW A	TAXIWAY	110	3600	75	269,943	PCC	1/1/1959
VQQ	TAXIWAY A	TW A	TAXIWAY	115	700	75	54,396	PCC	1/1/1951
VQQ	TAXIWAY A	TW A	TAXIWAY	117	120	75	27,484	AAC	1/1/2011
VQQ	TAXIWAY A	TW A	TAXIWAY	120	250	75	18,750	AAC	1/1/2011
VQQ	TAXIWAY A	TW A	TAXIWAY	125	100	100	19,405	AAC	1/1/2011
VQQ	TAXIWAY A	TW A	TAXIWAY	130	6100	75	457,575	PCC	1/1/1951
VQQ	TAXIWAY A1	TW A1	TAXIWAY	505	500	150	77,280	PCC	1/1/1951
VQQ	TAXIWAY A1	TW A1	TAXIWAY	510	360	150	58,667	PCC	1/1/1951
VQQ	TAXIWAY A1	TW A1	TAXIWAY	515	300	210	67,256	PCC	1/1/1954
VQQ	TAXIWAY A2	TW A2	TAXIWAY	603	300	75	26,792	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	605	150	75	11,684	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	607	100	75	7,608	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	608	50	75	7,608	AAC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	610	75	50	4,184	APC	1/1/2011
VQQ	TAXIWAY A2	TW A2	TAXIWAY	615	260	75	23,980	PCC	1/1/1954



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
VQQ	TAXIWAY A2	TW A2	TAXIWAY	620	210	75	24,484	PCC	1/1/1954
VQQ	TAXIWAY A3	TW A3	TAXIWAY	703	300	75	26,792	AAC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	705	150	75	11,684	AAC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	707	50	75	7,608	APC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	708	50	75	7,608	APC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	710	50	75	4,184	APC	1/1/2011
VQQ	TAXIWAY A3	TW A3	TAXIWAY	715	260	75	23,980	PCC	1/1/1951
VQQ	TAXIWAY A3	TW A3	TAXIWAY	720	210	75	24,484	PCC	1/1/1951
VQQ	TAXIWAY A4	TW A4	TAXIWAY	805	360	150	57,662	PCC	1/1/1951
VQQ	TAXIWAY A4	TW A4	TAXIWAY	810	500	150	79,426	PCC	1/1/1951
VQQ	TAXIWAY A5	TW A5	TAXIWAY	1005	1050	150	166,214	PCC	1/1/1958
VQQ	TAXIWAY B	TW B	TAXIWAY	205	4680	75	355,476	PCC	1/1/1951
VQQ	TAXIWAY B	TW B	TAXIWAY	208	100	130	19,400	AAC	1/1/2011
VQQ	TAXIWAY B	TW B	TAXIWAY	210	150	75	11,684	AAC	1/1/2011
VQQ	TAXIWAY B	TW B	TAXIWAY	212	100	75	38,584	AAC	1/1/2011
VQQ	TAXIWAY B	TW B	TAXIWAY	215	2200	75	165,208	PCC	1/1/1951
VQQ	TAXIWAY B1	TW B1	TAXIWAY	1105	370	150	56,522	PCC	1/1/1951
VQQ	TAXIWAY B1	TW B1	TAXIWAY	1110	500	150	77,371	PCC	1/1/1956
VQQ	TAXIWAY B1	TW B1	TAXIWAY	1115	200	150	30,000	PCC	1/1/1951
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1203	130	100	11,792	AAC	1/1/2011
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1205	300	75	22,500	AAC	1/1/2011
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1207	220	75	23,696	AAC	1/1/2011
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1210	240	75	23,980	PCC	1/1/1951
VQQ	TAXIWAY B2	TW B2	TAXIWAY	1215	215	75	24,522	PCC	1/1/1951
VQQ	TAXIWAY B3	TW B3	TAXIWAY	1405	370	150	58,667	PCC	1/1/1951
VQQ	TAXIWAY B3	TW B3	TAXIWAY	1410	500	150	77,505	PCC	1/1/1956
VQQ	TAXIWAY C	TW C	TAXIWAY	305	2400	75	175,845	PCC	1/1/1951
VQQ	TAXIWAY C	TW C	TAXIWAY	310	1700	80	136,320	PCC	1/1/1954
VQQ	TAXIWAY C	TW C	TAXIWAY	315	865	50	44,457	AC	1/1/1960
VQQ	TAXIWAY D	TW D	TAXIWAY	405	5460	75	435,222	PCC	1/1/1951
VQQ	TAXIWAY D	TW D	TAXIWAY	410	360	75	29,146	PCC	5/1/2005
VQQ	TAXIWAY D	TW D	TAXIWAY	415	1645	75	123,375	AC	1/1/2009
VQQ	TAXIWAY D	TW D	TAXIWAY	420	400	100	31,875	AC	1/1/2008
VQQ	TAXIWAY D2	TW D2	TAXIWAY	905	600	100	59,738	AC	1/1/2008
VQQ	TAXIWAY E	TW E	TAXIWAY	1610	3040	75	228,000	AC	1/1/2015
VQQ	TAXIWAY E1	TW E1	TAXIWAY	1605	1016	95	99,253	AC	1/1/2015
VQQ	TAXIWAY M	TW M	TAXIWAY	1305	210	75	22,376	PCC	1/1/1951

**Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level**

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	RUNWAY 18R-36L	RUNWAY	6135	50,000	74	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6140	50,000	84	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6145	26,000	91	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6150	26,000	93	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6155	30,000	89	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6160	30,000	88	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6165	31,200	87	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6170	31,200	88	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6175	20,400	74	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6180	20,400	88	Good
VQQ	RUNWAY 18L-36R	RUNWAY	6205	50,000	79	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6210	50,000	83	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6215	638,300	82	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6217	61,900	79	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6220	638,300	86	Good
VQQ	RUNWAY 18L-36R	RUNWAY	6222	61,900	75	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6225	50,200	72	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6230	50,200	82	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6235	450,000	80	Satisfactory
VQQ	RUNWAY 18L-36R	RUNWAY	6240	450,000	85	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6305	50,000	76	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6310	48,500	79	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6315	603,300	76	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6317	20,000	76	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6320	585,202	84	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6322	19,400	71	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6325	57,000	89	Good
VQQ	RUNWAY 9R-27L	RUNWAY	6330	55,290	89	Good
VQQ	RUNWAY 9R-27L	RUNWAY	6335	50,000	78	Satisfactory
VQQ	RUNWAY 9R-27L	RUNWAY	6340	48,500	74	Satisfactory
VQQ	RUNWAY 9L-27R	RUNWAY	6405	50,000	81	Satisfactory
VQQ	RUNWAY 9L-27R	RUNWAY	6410	50,000	77	Satisfactory
VQQ	RUNWAY 9L-27R	RUNWAY	6414	56,500	51	Poor
VQQ	RUNWAY 9L-27R	RUNWAY	6415	283,572	27	Very Poor
VQQ	RUNWAY 9L-27R	RUNWAY	6417	28,250	59	Fair
VQQ	RUNWAY 9L-27R	RUNWAY	6420	311,822	33	Very Poor
VQQ	RUNWAY 9L-27R	RUNWAY	6425	33,700	88	Good
VQQ	RUNWAY 9L-27R	RUNWAY	6430	33,700	91	Good



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	RUNWAY 9L-27R	RUNWAY	6435	20,000	92	Good
VQQ	RUNWAY 9L-27R	RUNWAY	6440	20,000	88	Good
VQQ	RUNWAY 18R-36L	RUNWAY	6105	50,000	79	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6110	50,000	77	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6115	542,800	30	Very Poor
VQQ	RUNWAY 18R-36L	RUNWAY	6120	542,800	33	Very Poor
VQQ	RUNWAY 18R-36L	RUNWAY	6125	30,000	74	Satisfactory
VQQ	RUNWAY 18R-36L	RUNWAY	6130	30,000	88	Good
VQQ	TAXIWAY B	TAXIWAY	205	355,476	83	Satisfactory
VQQ	TAXIWAY B	TAXIWAY	208	19,400	89	Good
VQQ	TAXIWAY B	TAXIWAY	210	11,684	91	Good
VQQ	TAXIWAY B	TAXIWAY	212	38,584	92	Good
VQQ	TAXIWAY B	TAXIWAY	215	165,208	81	Satisfactory
VQQ	TAXIWAY B1	TAXIWAY	1105	56,522	79	Satisfactory
VQQ	TAXIWAY B1	TAXIWAY	1110	77,371	77	Satisfactory
VQQ	TAXIWAY B1	TAXIWAY	1115	30,000	76	Satisfactory
VQQ	TAXIWAY B2	TAXIWAY	1203	11,792	88	Good
VQQ	TAXIWAY B2	TAXIWAY	1205	22,500	90	Good
VQQ	TAXIWAY B2	TAXIWAY	1207	23,696	91	Good
VQQ	TAXIWAY B2	TAXIWAY	1210	23,980	70	Fair
VQQ	TAXIWAY B2	TAXIWAY	1215	24,522	74	Satisfactory
VQQ	TAXIWAY B3	TAXIWAY	1405	58,667	76	Satisfactory
VQQ	TAXIWAY B3	TAXIWAY	1410	77,505	79	Satisfactory
VQQ	TAXIWAY C	TAXIWAY	305	175,845	80	Satisfactory
VQQ	TAXIWAY C	TAXIWAY	310	136,320	73	Satisfactory
VQQ	TAXIWAY C	TAXIWAY	315	44,457	30	Very Poor
VQQ	TAXIWAY D	TAXIWAY	405	435,222	75	Satisfactory
VQQ	TAXIWAY D	TAXIWAY	410	29,146	95	Good
VQQ	TAXIWAY D	TAXIWAY	415	123,375	86	Good
VQQ	TAXIWAY D	TAXIWAY	420	31,875	66	Fair
VQQ	TAXIWAY D2	TAXIWAY	905	59,738	78	Satisfactory
VQQ	TAXIWAY E	TAXIWAY	1610	228,000	100	Good
VQQ	TAXIWAY E1	TAXIWAY	1605	99,253	100	Good
VQQ	TAXIWAY M	TAXIWAY	1305	22,376	81	Satisfactory
VQQ	TAXIWAY A	TAXIWAY	105	67,381	62	Fair
VQQ	TAXIWAY A	TAXIWAY	110	269,943	75	Satisfactory
VQQ	TAXIWAY A	TAXIWAY	115	54,396	86	Good
VQQ	TAXIWAY A	TAXIWAY	117	27,484	78	Satisfactory
VQQ	TAXIWAY A	TAXIWAY	120	18,750	91	Good



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	TAXIWAY A	TAXIWAY	125	19,405	81	Satisfactory
VQQ	TAXIWAY A	TAXIWAY	130	457,575	82	Satisfactory
VQQ	TAXIWAY A1	TAXIWAY	505	77,280	84	Satisfactory
VQQ	TAXIWAY A1	TAXIWAY	510	58,667	84	Satisfactory
VQQ	TAXIWAY A1	TAXIWAY	515	67,256	74	Satisfactory
VQQ	TAXIWAY A2	TAXIWAY	603	26,792	90	Good
VQQ	TAXIWAY A2	TAXIWAY	605	11,684	90	Good
VQQ	TAXIWAY A2	TAXIWAY	607	7,608	91	Good
VQQ	TAXIWAY A2	TAXIWAY	608	7,608	94	Good
VQQ	TAXIWAY A2	TAXIWAY	610	4,184	94	Good
VQQ	TAXIWAY A2	TAXIWAY	615	23,980	85	Satisfactory
VQQ	TAXIWAY A2	TAXIWAY	620	24,484	72	Satisfactory
VQQ	TAXIWAY A3	TAXIWAY	703	26,792	94	Good
VQQ	TAXIWAY A3	TAXIWAY	705	11,684	92	Good
VQQ	TAXIWAY A3	TAXIWAY	707	7,608	92	Good
VQQ	TAXIWAY A3	TAXIWAY	708	7,608	94	Good
VQQ	TAXIWAY A3	TAXIWAY	710	4,184	94	Good
VQQ	TAXIWAY A3	TAXIWAY	715	23,980	81	Satisfactory
VQQ	TAXIWAY A3	TAXIWAY	720	24,484	73	Satisfactory
VQQ	TAXIWAY A4	TAXIWAY	805	57,662	77	Satisfactory
VQQ	TAXIWAY A4	TAXIWAY	810	79,426	81	Satisfactory
VQQ	TAXIWAY A5	TAXIWAY	1005	166,214	75	Satisfactory
VQQ	NORTH APRON	APRON	4103	62,610	73	Satisfactory
VQQ	NORTH APRON	APRON	4105	172,130	71	Satisfactory
VQQ	NORTH APRON	APRON	4110	290,625	56	Fair
VQQ	NORTH APRON	APRON	4115	236,250	78	Satisfactory
VQQ	NORTH APRON	APRON	4117	14,325	88	Good
VQQ	NORTH APRON	APRON	4120	391,125	73	Satisfactory
VQQ	NORTH APRON	APRON	4125	1,403,402	79	Satisfactory
VQQ	NORTH APRON	APRON	4132	37,875	75	Satisfactory
VQQ	NORTH APRON	APRON	4137	74,250	68	Fair
VQQ	NORTH APRON	APRON	4138	11,250	74	Satisfactory
VQQ	NORTH APRON	APRON	4140	102,688	71	Satisfactory
VQQ	NORTH APRON	APRON	4150	105,074	75	Satisfactory
VQQ	WEST PARKING APRON	APRON	4205	166,732	72	Satisfactory
VQQ	WEST PARKING APRON	APRON	4210	233,520	77	Satisfactory
VQQ	WEST PARKING APRON	APRON	4220	266,686	76	Satisfactory
VQQ	WEST PARKING APRON	APRON	4225	35,000	14	Serious
VQQ	WEST PARKING APRON	APRON	4230	26,250	12	Serious



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VQQ	WEST PARKING APRON	APRON	4235	13,730	12	Serious
VQQ	WEST PARKING APRON	APRON	4240	82,954	75	Satisfactory
VQQ	WEST PARKING APRON	APRON	4245	102,240	75	Satisfactory
VQQ	WEST PARKING APRON	APRON	4250	285,584	72	Satisfactory
VQQ	WEST PARKING APRON	APRON	4255	19,950	9	Failed
VQQ	WEST PARKING APRON	APRON	4260	50,613	77	Satisfactory
VQQ	WEST PARKING APRON	APRON	4265	99,400	80	Satisfactory
VQQ	WEST PARKING APRON	APRON	4270	41,180	73	Satisfactory
VQQ	NORTH APRON	APRON	4305	70,920	95	Good
VQQ	NORTH APRON	APRON	4310	43,214	99	Good
VQQ	EAST APRON	APRON	4405	26,675	100	Good
VQQ	EAST APRON	APRON	4410	60,000	100	Good
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5005	22,135	78	Satisfactory
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5010	22,135	72	Satisfactory
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5015	22,135	83	Satisfactory
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5020	22,135	43	Poor
VQQ	W HOT REFUELING AND COMPASS ROSE AP	APRON	5055	13,010	30	Very Poor
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5125	22,115	76	Satisfactory
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5130	22,115	81	Satisfactory
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5135	22,115	62	Fair
VQQ	N HOT REFUELING AND COMPASS ROSE AP	APRON	5140	22,115	44	Poor
VQQ	NATIONAL GUARD WASH APRON	APRON	5305	30,200	88	Good
VQQ	NATIONAL GUARD WASH APRON	APRON	5310	199,156	93	Good

Table A-3 Forecasted PCI 2018-2027

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	AP E	4405	100	95	93	92	90	88	87	85	84	82	80
VQQ	AP E	4410	100	90	87	84	82	79	77	74	72	70	68
VQQ	AP N	4103	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP N	4105	71	69	67	65	64	62	60	59	58	56	55
VQQ	AP N	4110	56	55	54	53	51	51	50	49	48	47	47
VQQ	AP N	4115	78	76	74	72	70	68	66	64	62	61	59
VQQ	AP N	4117	88	86	83	80	78	76	73	71	69	67	65
VQQ	AP N	4120	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP N	4125	79	77	75	72	70	68	66	65	63	61	60
VQQ	AP N	4132	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP N	4137	68	66	65	63	61	60	58	57	56	54	53
VQQ	AP N	4138	74	72	70	68	66	64	63	61	60	58	57
VQQ	AP N	4140	71	69	67	65	64	62	60	59	58	56	55
VQQ	AP N	4150	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP N	4305	95	93	90	87	84	81	79	76	74	72	70
VQQ	AP N	4310	99	97	93	90	87	85	82	79	77	75	72
VQQ	AP N RFUEL	5125	76	74	72	70	68	66	64	62	61	59	58
VQQ	AP N RFUEL	5130	81	79	77	74	72	70	68	66	64	63	61
VQQ	AP N RFUEL	5135	62	61	59	58	56	55	54	53	52	51	50
VQQ	AP N RFUEL	5140	44	43	43	43	42	42	42	42	42	41	41
VQQ	AP NAT GRD	5305	88	86	83	80	78	76	73	71	69	67	65
VQQ	AP NAT GRD	5310	93	91	88	85	82	80	77	75	73	71	69
VQQ	AP W	4205	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W	4210	77	75	73	71	69	67	65	63	62	60	59
VQQ	AP W	4220	76	74	72	70	68	66	64	62	61	59	58
VQQ	AP W	4225	14	13	12	11	9	8	7	6	5	4	3
VQQ	AP W	4230	12	11	10	9	7	6	5	4	3	2	1
VQQ	AP W	4235	12	11	10	9	7	6	5	4	3	2	1
VQQ	AP W	4240	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP W	4245	75	73	71	69	67	65	63	62	60	59	57
VQQ	AP W	4250	72	70	68	66	65	63	61	60	58	57	56
VQQ	AP W	4255	9	8	7	6	4	3	2	1	0	0	0
VQQ	AP W	4260	77	75	73	71	69	67	65	63	62	60	59
VQQ	AP W	4265	80	78	76	73	71	69	67	65	64	62	60
VQQ	AP W	4270	73	71	69	67	65	64	62	60	59	57	56
VQQ	AP W RFUEL	5005	78	76	74	72	70	68	66	64	62	61	59
VQQ	AP W RFUEL	5010	72	70	68	66	65	63	61	60	58	57	56



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	AP W RFUEL	5015	83	81	78	76	74	72	70	68	66	64	62
VQQ	AP W RFUEL	5020	43	42	42	42	42	41	41	41	41	41	41
VQQ	AP W RFUEL	5055	30	29	28	27	25	24	23	22	21	20	19
VQQ	RW 18L-36R	6205	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 18L-36R	6210	83	82	81	80	79	79	78	77	76	75	74
VQQ	RW 18L-36R	6215	82	80	77	75	73	70	68	67	65	64	63
VQQ	RW 18L-36R	6217	79	77	75	72	70	68	66	65	63	62	61
VQQ	RW 18L-36R	6220	86	84	82	79	77	74	72	70	68	66	64
VQQ	RW 18L-36R	6222	75	73	71	69	67	65	64	63	62	61	61
VQQ	RW 18L-36R	6225	72	71	70	69	68	68	67	66	65	64	63
VQQ	RW 18L-36R	6230	82	81	80	79	78	78	77	76	75	74	73
VQQ	RW 18L-36R	6235	80	79	78	77	76	76	75	74	73	72	71
VQQ	RW 18L-36R	6240	85	84	83	82	81	81	80	79	78	77	76
VQQ	RW 18R-36L	6105	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 18R-36L	6110	77	76	75	74	73	73	72	71	70	69	68
VQQ	RW 18R-36L	6115	30	28	25	22	19	17	14	11	8	6	3
VQQ	RW 18R-36L	6120	33	31	29	26	23	20	17	15	12	9	6
VQQ	RW 18R-36L	6125	74	73	72	71	70	70	69	68	67	66	65
VQQ	RW 18R-36L	6130	88	87	86	85	84	84	83	82	81	80	79
VQQ	RW 18R-36L	6135	74	73	72	71	70	70	69	68	67	66	65
VQQ	RW 18R-36L	6140	84	83	82	81	80	80	79	78	77	76	75
VQQ	RW 18R-36L	6145	91	89	87	84	82	79	77	75	72	70	68
VQQ	RW 18R-36L	6150	93	91	89	87	84	82	79	77	74	72	70
VQQ	RW 18R-36L	6155	89	87	85	82	80	77	75	73	70	68	66
VQQ	RW 18R-36L	6160	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 18R-36L	6165	87	85	83	80	78	75	73	71	69	67	65
VQQ	RW 18R-36L	6170	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 18R-36L	6175	74	72	70	68	66	65	63	62	61	61	61
VQQ	RW 18R-36L	6180	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9L-27R	6405	81	80	79	78	77	77	76	75	74	73	72
VQQ	RW 9L-27R	6410	77	76	75	74	73	73	72	71	70	69	68
VQQ	RW 9L-27R	6414	51	49	46	43	39	36	33	31	28	25	23
VQQ	RW 9L-27R	6415	27	25	22	19	16	14	11	8	5	3	0
VQQ	RW 9L-27R	6417	59	58	57	55	53	50	47	44	41	38	35
VQQ	RW 9L-27R	6420	33	31	29	26	23	20	17	15	12	9	6
VQQ	RW 9L-27R	6425	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9L-27R	6430	91	89	87	84	82	79	77	75	72	70	68
VQQ	RW 9L-27R	6435	92	90	88	86	83	81	78	76	73	71	69

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	RW 9L-27R	6440	88	86	84	81	79	76	74	72	69	67	66
VQQ	RW 9R-27L	6305	76	75	74	73	72	72	71	70	69	68	67
VQQ	RW 9R-27L	6310	79	78	77	76	75	75	74	73	72	71	70
VQQ	RW 9R-27L	6315	76	74	72	70	68	66	64	63	62	61	61
VQQ	RW 9R-27L	6317	76	74	72	70	68	66	64	63	62	61	61
VQQ	RW 9R-27L	6320	84	82	80	77	75	72	70	68	66	65	63
VQQ	RW 9R-27L	6322	71	69	67	66	64	63	62	61	61	60	60
VQQ	RW 9R-27L	6325	89	88	87	86	85	85	84	83	82	81	80
VQQ	RW 9R-27L	6330	89	88	87	86	85	85	84	83	82	81	80
VQQ	RW 9R-27L	6335	78	77	76	75	74	74	73	72	71	70	69
VQQ	RW 9R-27L	6340	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW A	105	62	61	60	59	58	58	57	56	55	54	53
VQQ	TW A	110	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW A	115	86	85	84	83	82	82	81	80	79	78	77
VQQ	TW A	117	78	77	75	74	73	72	71	70	69	68	68
VQQ	TW A	120	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW A	125	81	79	78	76	75	74	72	72	71	70	69
VQQ	TW A	130	82	81	80	79	78	78	77	76	75	74	73
VQQ	TW A1	505	84	83	82	81	80	80	79	78	77	76	75
VQQ	TW A1	510	84	83	82	81	80	80	79	78	77	76	75
VQQ	TW A1	515	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW A2	603	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW A2	605	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW A2	607	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW A2	608	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A2	610	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A2	615	85	84	83	82	81	81	80	79	78	77	76
VQQ	TW A2	620	72	71	70	69	68	68	67	66	65	64	63
VQQ	TW A3	703	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	705	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW A3	707	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW A3	708	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	710	94	92	89	86	83	81	79	77	76	75	73
VQQ	TW A3	715	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW A3	720	73	72	71	70	69	69	68	67	66	65	64
VQQ	TW A4	805	77	76	75	74	73	73	72	71	70	69	68
VQQ	TW A4	810	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW A5	1005	75	74	73	72	71	71	70	69	68	67	66



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
VQQ	TW B	205	83	82	81	80	79	79	78	77	76	75	74
VQQ	TW B	208	89	87	84	82	80	78	76	75	74	73	72
VQQ	TW B	210	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW B	212	92	90	87	84	82	80	78	76	75	74	73
VQQ	TW B	215	81	80	79	78	77	77	76	75	74	73	72
VQQ	TW B1	1105	79	78	77	76	75	75	74	73	72	71	70
VQQ	TW B1	1110	77	76	75	74	73	73	72	71	70	69	68
VQQ	TW B1	1115	76	75	74	73	72	72	71	70	69	68	67
VQQ	TW B2	1203	88	86	83	81	79	77	76	75	73	72	71
VQQ	TW B2	1205	90	88	85	83	80	79	77	75	74	73	72
VQQ	TW B2	1207	91	89	86	83	81	79	77	76	75	73	72
VQQ	TW B2	1210	70	69	68	67	66	66	65	64	63	62	61
VQQ	TW B2	1215	74	73	72	71	70	70	69	68	67	66	65
VQQ	TW B3	1405	76	75	74	73	72	72	71	70	69	68	67
VQQ	TW B3	1410	79	78	77	76	75	75	74	73	72	71	70
VQQ	TW C	305	80	79	78	77	76	76	75	74	73	72	71
VQQ	TW C	310	73	72	71	70	69	69	68	67	66	65	64
VQQ	TW C	315	30	29	28	28	27	25	24	22	20	17	14
VQQ	TW D	405	75	74	73	72	71	71	70	69	68	67	66
VQQ	TW D	410	95	94	93	92	91	91	90	89	88	87	86
VQQ	TW D	415	86	84	82	80	77	76	74	72	71	70	69
VQQ	TW D	420	66	65	64	63	62	62	61	60	58	57	56
VQQ	TW D2	905	78	76	75	73	72	70	69	68	67	66	65
VQQ	TW E	1610	100	93	90	88	85	83	81	78	76	75	73
VQQ	TW E1	1605	100	93	90	88	85	83	81	78	76	75	73
VQQ	TW M	1305	81	80	79	78	77	77	76	75	74	73	72

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 1 of 30

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP E	<b>EAST APRON</b>	<b>Section:</b> 4405	<b>Surface:</b> AC		
L.C.D.: 1/1/2015	Use: APRON	Rank: P	Length: 212.00 (Ft)	Width: 125.00 (Ft) True Area: 26,675.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	5" P-401, 11" P-211, P-152

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP E	<b>EAST APRON</b>	<b>Section:</b> 4410	<b>Surface:</b> PCC		
L.C.D.: 1/1/2015	Use: APRON	Rank: P	Length: 300.00 (Ft)	Width: 200.00 (Ft) True Area: 60,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	10" P-501, 6" P-306, 6" P-154, P-152

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP N RFUEL N HOT REFUELI	<b>Section:</b> 5125	<b>Surface:</b> PCC			
L.C.D.: 1/1/1954	Use: APRON	Rank: P	Length: 105.00 (Ft)	Width: 200.00 (Ft) True Area: 22,115.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP N RFUEL N HOT REFUELI	<b>Section:</b> 5130	<b>Surface:</b> PCC			
L.C.D.: 1/1/1954	Use: APRON	Rank: P	Length: 105.00 (Ft)	Width: 200.00 (Ft) True Area: 22,115.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP N RFUEL N HOT REFUELI	<b>Section:</b> 5135	<b>Surface:</b> PCC			
L.C.D.: 1/1/1954	Use: APRON	Rank: P	Length: 105.00 (Ft)	Width: 200.00 (Ft) True Area: 22,115.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP N RFUEL N HOT REFUELI	<b>Section:</b> 5140	<b>Surface:</b> PCC			
L.C.D.: 1/1/1954	Use: APRON	Rank: P	Length: 105.00 (Ft)	Width: 200.00 (Ft) True Area: 22,115.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 2 of 30

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4103	Surface: PCC
L.C.D.:	1/1/1954	Use: APRON	Rank: P	Length: 230.00 (Ft)	Width: 300.00 (Ft)	True Area: 62,610.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLAB REPAIRS SPALLS AND JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT ON UNKNOWN FOUNDATION

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4105	Surface: PCC
L.C.D.:	1/1/1988	Use: APRON	Rank: P	Length: 700.00 (Ft)	Width: 250.00 (Ft)	True Area: 172,130.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1988	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1988 10" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4110	Surface: PCC
L.C.D.:	1/1/1956	Use: APRON	Rank: P	Length: 762.00 (Ft)	Width: 387.00 (Ft)	True Area: 290,625.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	EST 1956 10" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4115	Surface: PCC
L.C.D.:	1/1/1965	Use: APRON	Rank: P	Length: 525.00 (Ft)	Width: 475.00 (Ft)	True Area: 236,250.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLAB REPAIR SPALLS AND JOINTS
1/1/1965	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1965 SPALL REPAIR AND RESEAL JOINTS
1/1/1955	IMPORT ED	OVERLAY	0.00	10.00	<input checked="" type="checkbox"/>	EST 1955 10" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4117	Surface: PCC
L.C.D.:	1/1/1954	Use: APRON	Rank: P	Length: 110.00 (Ft)	Width: 125.00 (Ft)	True Area: 14,325.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	0.00	0.00	<input type="checkbox"/>	Estimated work date
1/1/1954	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1954 PCC PAVEMENT SECTION UNKNOWN

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 3 of 30

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON	Section: 4120	Surface: PCC	
L.C.D.: 1/1/1954		Use: APRON	Rank: P	Length: 800.00 (Ft)	Width: 525.00 (Ft)	True Area: 391,125.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	EST 1954 10" PCC PAVEMENT
Network: CECIL AIRPORT		Branch: AP N	NORTH APRON	Section: 4125	Surface: PCC	
L.C.D.: 1/1/1951		Use: APRON	Rank: P	Length: 2,643.00 (Ft)	Width: 525.00 (Ft)	True Area: 1,403,402.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE
Network: CECIL AIRPORT		Branch: AP N	NORTH APRON	Section: 4132	Surface: PCC	
L.C.D.: 1/1/1951		Use: APRON	Rank: P	Length: 300.00 (Ft)	Width: 125.00 (Ft)	True Area: 37,875.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1951	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1951 PCC PAVEMENT UNKNOWN SECTION
Network: CECIL AIRPORT		Branch: AP N	NORTH APRON	Section: 4137	Surface: PCC	
L.C.D.: 1/1/1951		Use: APRON	Rank: P	Length: 825.00 (Ft)	Width: 70.00 (Ft)	True Area: 74,250.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1951	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1951 PCC PAVEMENT UNKNOWN SECTION
Network: CECIL AIRPORT		Branch: AP N	NORTH APRON	Section: 4138	Surface: PCC	
L.C.D.: 1/1/1953		Use: APRON	Rank: P	Length: 187.50 (Ft)	Width: 60.00 (Ft)	True Area: 11,250.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1953	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1953 PCC PAVEMENT UNKNOWN SECTION
Network: CECIL AIRPORT		Branch: AP N	NORTH APRON	Section: 4140	Surface: PCC	
L.C.D.: 1/1/1951		Use: APRON	Rank: P	Length: 525.00 (Ft)	Width: 200.00 (Ft)	True Area: 102,688.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1951	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1951 PCC PAVEMENT SECTION UNKNOWN

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 4 of 30

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4150	Surface: PCC
L.C.D.: 1/1/1965		Use: APRON	Rank: P	Length: 375.00 (Ft)	Width: 237.00 (Ft)	True Area: 105,074.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1965	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1965 SPALL REPAIR RESEAL JOINTS
1/1/1954	IMPORT ED	OVERLAY	0.00	10.00	<input checked="" type="checkbox"/>	EST 1954 10" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4305	Surface: PCC
L.C.D.: 5/1/2005		Use: APRON	Rank: S	Length: 360.00 (Ft)	Width: 197.00 (Ft)	True Area: 70,920.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: AP N	NORTH APRON		Section: 4310	Surface: PCC
L.C.D.: 1/1/2011		Use: APRON	Rank: P	Length: 460.00 (Ft)	Width: 75.00 (Ft)	True Area: 43,214.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: AP NAT GRD NATIONAL GUA	Section: 5305		Surface: PCC	
L.C.D.: 1/1/1976		Use: APRON	Rank: P	Length: 150.00 (Ft)	Width: 140.00 (Ft)	True Area: 30,200.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1976	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1976 PCC PAVEMENT SECTION UNKNOWN

Network: CECIL AIRPORT		Branch: AP NAT GRD NATIONAL GUA	Section: 5310		Surface: PCC	
L.C.D.: 1/1/2010		Use: APRON	Rank: P	Length: 1,103.00 (Ft)	Width: 150.00 (Ft)	True Area: 199,156.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: AP W RFUEL W HOT REFUELI	Section: 5005		Surface: PCC	
L.C.D.: 1/1/1956		Use: APRON	Rank: P	Length: 210.00 (Ft)	Width: 100.00 (Ft)	True Area: 22,135.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" PCC PAVEMENT

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 5 of 30

Network: CECIL AIRPORT		Branch: AP W RFUEL W HOT REFUELI		Section: 5010		Surface: PCC
L.C.D.:	1/1/1956	Use: APRON	Rank: P	Length: 210.00 (Ft)	Width: 100.00 (Ft)	True Area: 22,135.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: AP W RFUEL W HOT REFUELI		Section: 5015		Surface: PCC
L.C.D.:	1/1/1956	Use: APRON	Rank: P	Length: 210.00 (Ft)	Width: 100.00 (Ft)	True Area: 22,135.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: AP W RFUEL W HOT REFUELI		Section: 5020		Surface: PCC
L.C.D.:	1/1/1956	Use: APRON	Rank: P	Length: 210.00 (Ft)	Width: 100.00 (Ft)	True Area: 22,135.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: AP W RFUEL W HOT REFUELI		Section: 5055		Surface: PCC
L.C.D.:	1/1/1955	Use: APRON	Rank: P	Length: 80.00 (Ft)	Width: 150.00 (Ft)	True Area: 13,010.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1955 PCC PAVEMENT UNKNOWN SECTION

Network: CECIL AIRPORT		Branch: AP W		WEST PARKING		Section: 4205	Surface: PCC
L.C.D.:	1/1/1955	Use: APRON	Rank: P	Length: 402.00 (Ft)	Width: 320.00 (Ft)	True Area: 166,732.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS	
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR	
1/1/1955	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1955 10" PCC PAVEMENT	

Network: CECIL AIRPORT		Branch: AP W		WEST PARKING		Section: 4210	Surface: PCC
L.C.D.:	1/1/1959	Use: APRON	Rank: P	Length: 525.00 (Ft)	Width: 310.00 (Ft)	True Area: 233,520.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS	
1/1/1959	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1959 10" PCC PAVEMENT	

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 6 of 30

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4220	<b>Surface:</b> PCC
L.C.D.: 1/1/1960	Use: APRON	Rank: P	Length: 880.00 (Ft)	Width: 310.00 (Ft) True Area: 266,686.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1960	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1960 10" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4225	<b>Surface:</b> PCC
L.C.D.: 1/1/1991	Use: APRON	Rank: P	Length: 320.00 (Ft)	Width: 105.00 (Ft) True Area: 35,000.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1955	IMPORT ED	OVERLAY	0.00	6.00	<input checked="" type="checkbox"/>	EST 1955 6" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4230	<b>Surface:</b> PCC
L.C.D.: 1/1/1955	Use: APRON	Rank: P	Length: 270.00 (Ft)	Width: 115.00 (Ft) True Area: 26,250.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>	EST 1955 6" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4235	<b>Surface:</b> PCC
L.C.D.: 1/1/1955	Use: APRON	Rank: P	Length: 320.00 (Ft)	Width: 30.00 (Ft) True Area: 13,730.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>	EST 1955 6" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4240	<b>Surface:</b> PCC
L.C.D.: 1/1/1955	Use: APRON	Rank: P	Length: 1,406.00 (Ft)	Width: 59.00 (Ft) True Area: 82,954.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1955 10" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4245	<b>Surface:</b> PCC
L.C.D.: 1/1/1955	Use: APRON	Rank: P	Length: 1,704.00 (Ft)	Width: 60.00 (Ft) True Area: 102,240.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1955 10" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4250	<b>Surface:</b> PCC
L.C.D.: 1/1/1976	Use: APRON	Rank: P	Length: 555.00 (Ft)	Width: 500.00 (Ft) True Area: 285,584.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1976	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1976 8" PCC PAVEMENT ON 6" SOIL CEMENT

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 7 of 30

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4255	<b>Surface:</b> PCC
L.C.D.: 1/1/1955	Use: APRON	Rank: P	Length: 320.00 (Ft)	Width: 30.00 (Ft) True Area: 19,950.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>	EST 1955 6" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4260	<b>Surface:</b> PCC
L.C.D.: 1/1/1961	Use: APRON	Rank: P	Length: 320.00 (Ft)	Width: 200.00 (Ft) True Area: 50,613.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1961	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1961 10" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4265	<b>Surface:</b> PCC
L.C.D.: 1/1/1955	Use: APRON	Rank: P	Length: 710.00 (Ft)	Width: 140.00 (Ft) True Area: 99,400.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1955 PCC PAVEMENT UNKNOWN SECTION

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> AP W	<b>WEST PARKING</b>	<b>Section:</b> 4270	<b>Surface:</b> PCC
L.C.D.: 1/1/1955	Use: APRON	Rank: P	Length: 710.00 (Ft)	Width: 58.00 (Ft) True Area: 41,180.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1955	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1955 PCC PAVEMENT UNKNOWN SECTION

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> RW 18L-36R RUNWAY 18L-36	<b>Section:</b> 6205	<b>Surface:</b> PCC
L.C.D.: 1/1/1951	Use: RUNWAY	Rank: T	Length: 500.00 (Ft) Width: 100.00 (Ft) True Area: 50,000.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> RW 18L-36R RUNWAY 18L-36	<b>Section:</b> 6210	<b>Surface:</b> PCC
L.C.D.: 1/1/1951	Use: RUNWAY	Rank: P	Length: 1,000.00 (Ft) Width: 50.00 (Ft) True Area: 50,000.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1960	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	6965 AND 1960 SPALL REPAIR AND JOINT SEAL
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 8 of 30

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6215		Surface: AAC	
L.C.D.: 1/1/2011		Use: RUNWAY	Rank: P	Length: 6,383.00 (Ft)	Width: 100.00 (Ft)	True Area: 638,300.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1975	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1965	IMPORT ED	OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	1965 AND 1960 SEAL COATS
1/1/1951	IMPORT ED	BUILT		0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6217		Surface: AAC	
L.C.D.: 1/1/2011		Use: RUNWAY	Rank: P	Length: 619.00 (Ft)	Width: 100.00 (Ft)	True Area: 61,900.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1975	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1965	IMPORT ED	OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	1965 AND 1960 SEAL COATS
1/1/1951	IMPORT ED	BUILT		0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6220		Surface: AAC	
L.C.D.: 1/1/2011		Use: RUNWAY	Rank: P	Length: 6,383.00 (Ft)	Width: 100.00 (Ft)	True Area: 638,300.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1975	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	1959 AND 1956 SEAL COATS
1/1/1951	IMPORT ED	BUILT		0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6222		Surface: AAC	
L.C.D.: 1/1/2011		Use: RUNWAY	Rank: P	Length: 619.00 (Ft)	Width: 100.00 (Ft)	True Area: 61,900.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1975	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	1959 AND 1956 SEAL COATS
1/1/1951	IMPORT ED	BUILT		0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 9 of 30

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6225		Surface: PCC	
L.C.D.: 1/1/1951		Use: RUNWAY	Rank: P	Length: 500.00 (Ft)	Width: 100.00 (Ft)	True Area: 50,200.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs		0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC		0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT		0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6230		Surface: PCC	
L.C.D.: 1/1/1951		Use: RUNWAY	Rank: P	Length: 1,000.00 (Ft)	Width: 50.00 (Ft)	True Area: 50,200.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs		0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC		0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SEAL COATS
1/1/1951	IMPORT ED	BUILT		0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6235		Surface: PCC	
L.C.D.: 1/1/1959		Use: RUNWAY	Rank: P	Length: 4,500.00 (Ft)	Width: 100.00 (Ft)	True Area: 450,000.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs		0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC		0.00	0.00	<input type="checkbox"/>	
1/1/1983	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1983 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND CORNER BRE
1/1/1965	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1959	IMPORT ED	BUILT		0.00	11.00	<input checked="" type="checkbox"/>	1959 11" PCC PAVEMENT ON 10" LIMEROCK BASE

Network: CECIL AIRPORT		Branch: RW 18L-36R RUNWAY 18L-36		Section: 6240		Surface: PCC	
L.C.D.: 1/1/1959		Use: RUNWAY	Rank: P	Length: 9,000.00 (Ft)	Width: 50.00 (Ft)	True Area: 450,000.00 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs		0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC		0.00	0.00	<input type="checkbox"/>	
1/1/1983	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1983 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND CORNER BRE
1/1/1965	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1959	IMPORT ED	BUILT		0.00	11.00	<input checked="" type="checkbox"/>	1959 11" PCC PAVEMENT ON 10" LIMEROCK BASE

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 10 of 30

Network: CECIL AIRPORT		Branch: RW 18R-36L RUNWAY 18R-36		Section: 6105		Surface: PCC			
L.C.D.:	1/1/1951	Use: RUNWAY	Rank: T	Length:	500.00 (Ft)	Width:	100.00 (Ft)	True Area:	50,000.00 (SqFt)
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments		
5/1/2007	PA-PCC	Patching - PCC		0.00	0.00	<input type="checkbox"/>			
1/1/1981	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS		
1/1/1965	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS		
1/1/1951	IMPORT ED	BUILT		0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT		

Network: CECIL AIRPORT		Branch: RW 18R-36L RUNWAY 18R-36		Section: 6110		Surface: PCC			
L.C.D.:	1/1/1951	Use: RUNWAY	Rank: S	Length:	1,000.00 (Ft)	Width:	50.00 (Ft)	True Area:	50,000.00 (SqFt)
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments		
5/1/2007	PA-PCC	Patching - PCC		0.00	0.00	<input type="checkbox"/>			
1/1/1981	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS		
1/1/1965	IMPORT ED	REPAIR		0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND RESEAL JOINTS		
1/1/1951	IMPORT ED	BUILT		0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT		

Network: CECIL AIRPORT		Branch: RW 18R-36L RUNWAY 18R-36		Section: 6115		Surface: AAC			
L.C.D.:	1/1/1986	Use: RUNWAY	Rank: S	Length:	10,856.00 (Ft)	Width:	50.00 (Ft)	True Area:	542,800.00 (SqFt)
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments		
1/1/1986	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY		
1/1/1975	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY		
1/1/1961	IMPORT ED	OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	1961 AND 1956 SEAL COATS		
1/1/1951	IMPORT ED	BUILT		0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE		

Network: CECIL AIRPORT		Branch: RW 18R-36L RUNWAY 18R-36		Section: 6120		Surface: AAC			
L.C.D.:	1/1/1986	Use: RUNWAY	Rank: S	Length:	5,428.00 (Ft)	Width:	100.00 (Ft)	True Area:	542,800.00 (SqFt)
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments		
1/1/1986	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY		
1/1/1975	IMPORT ED	OVERLAY		0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY		
1/1/1961	IMPORT ED	OVERLAY		0.00	0.00	<input checked="" type="checkbox"/>	1961 AND 1956 SEAL COATS		
1/1/1951	IMPORT ED	BUILT		0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC PAVEMENT ON 9" LIMEROCK BASE ON 6" STABILIZE		

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 11 of 30

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6125	<b>Surface:</b> PCC	
L.C.D.:	1/1/1986	Use: RUNWAY	Rank: S	Length: 300.00 (Ft)	Width: 100.00 (Ft)	True Area: 30,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1986	IMPORT ED	BUILT	0.00	11.00	<input checked="" type="checkbox"/>	1986 11" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6130	<b>Surface:</b> PCC	
L.C.D.:	1/1/1986	Use: RUNWAY	Rank: S	Length: 600.00 (Ft)	Width: 50.00 (Ft)	True Area: 30,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1986	IMPORT ED	BUILT	0.00	11.00	<input checked="" type="checkbox"/>	1986 11" PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6135	<b>Surface:</b> PCC	
L.C.D.:	1/1/1951	Use: RUNWAY	Rank: S	Length: 500.00 (Ft)	Width: 100.00 (Ft)	True Area: 50,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND SEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6140	<b>Surface:</b> PCC	
L.C.D.:	1/1/1951	Use: RUNWAY	Rank: S	Length: 1,000.00 (Ft)	Width: 50.00 (Ft)	True Area: 50,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6145	<b>Surface:</b> AAC	
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 260.00 (Ft)	Width: 100.00 (Ft)	True Area: 26,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

8/8/2017

**Work History Report**  
*Pavement Database: FDOT*

Page 12 of 30

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6150	<b>Surface:</b> AAC
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 520.00 (Ft)	Width: 50.00 (Ft) True Area: 26,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6155	<b>Surface:</b> AAC
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 300.00 (Ft)	Width: 100.00 (Ft) True Area: 30,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6160	<b>Surface:</b> AAC
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 600.00 (Ft)	Width: 50.00 (Ft) True Area: 30,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6165	<b>Surface:</b> AAC
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 312.00 (Ft)	Width: 100.00 (Ft) True Area: 31,200.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6170	<b>Surface:</b> AAC
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 156.00 (Ft)	Width: 200.00 (Ft) True Area: 31,200.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6175	<b>Surface:</b> AAC
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 408.00 (Ft)	Width: 50.00 (Ft) True Area: 20,400.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 18R-36L RUNWAY 18R-36		<b>Section:</b> 6180	<b>Surface:</b> AAC
L.C.D.:	1/1/2011	Use: RUNWAY	Rank: S	Length: 204.00 (Ft)	Width: 100.00 (Ft) True Area: 20,400.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 13 of 30

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6405	Surface: PCC		
L.C.D.: 1/1/1951		Use: RUNWAY Rank: T	Length: 500.00 (Ft)	Width: 100.00 (Ft) True Area: 50,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1982	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1982 PRESSURE GROUT SELECTED SLABS
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6410	Surface: PCC		
L.C.D.: 1/1/1951		Use: RUNWAY Rank: S	Length: 1,000.00 (Ft)	Width: 50.00 (Ft) True Area: 50,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1982	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1982 PRESSURE GROUT SELECTED SLABS
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6414	Surface: AAC		
L.C.D.: 1/1/2006		Use: RUNWAY Rank: S	Length: 200.00 (Ft)	Width: 100.00 (Ft) True Area: 56,500.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1990	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1990 MILL AND AC PATCH

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6415	Surface: AAC		
L.C.D.: 1/1/1986		Use: RUNWAY Rank: S	Length: 2,835.00 (Ft)	Width: 100.00 (Ft) True Area: 283,572.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1977	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1977 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1959 AND 1956 SEAL COATS
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

8/8/2017

**Work History Report**  
*Pavement Database: FDOT*

Page 14 of 30

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6417	Surface: AAC		
L.C.D.: 1/1/2006		Use: RUNWAY Rank: S	Length: 565.00 (Ft)	Width: 50.00 (Ft) True Area: 28,250.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1977	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1977 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1959 AND 1956 SEAL COATS
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6420	Surface: AAC		
L.C.D.: 1/1/1986		Use: RUNWAY Rank: S	Length: 3,400.00 (Ft)	Width: 100.00 (Ft) True Area: 311,822.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1977	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1977 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1959 AND 1956 SEAL COATS
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6425	Surface: AAC		
L.C.D.: 1/1/2011		Use: RUNWAY Rank: S	Length: 337.00 (Ft)	Width: 100.00 (Ft) True Area: 33,700.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1951	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6430	Surface: AAC		
L.C.D.: 1/1/2011		Use: RUNWAY Rank: S	Length: 337.00 (Ft)	Width: 100.00 (Ft) True Area: 33,700.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1951	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: RW 9L-27R RUNWAY 9L-27	Section: 6435	Surface: AAC		
L.C.D.: 1/1/2011		Use: RUNWAY Rank: S	Length: 275.00 (Ft)	Width: 100.00 (Ft) True Area: 20,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1951	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 15 of 30

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 9L-27R RUNWAY 9L-27	<b>Section:</b> 6440	<b>Surface:</b> AAC		
L.C.D.:	1/1/2011	Use: RUNWAY Rank: S Length: 550.00 (Ft) Width: 50.00 (Ft)	True Area: 20,000.00 (SqFt)			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1951	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 9R-27L RUNWAY 9R-27	<b>Section:</b> 6305	<b>Surface:</b> PCC		
L.C.D.:	1/1/1956	Use: RUNWAY Rank: P Length: 500.00 (Ft) Width: 100.00 (Ft)	True Area: 50,000.00 (SqFt)			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" REINFORCED PCC PAVEMENT ON 10" LIMEROCK STA

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 9R-27L RUNWAY 9R-27	<b>Section:</b> 6310	<b>Surface:</b> PCC		
L.C.D.:	1/1/1956	Use: RUNWAY Rank: P Length: 1,000.00 (Ft) Width: 50.00 (Ft)	True Area: 48,500.00 (SqFt)			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" REINFORCED PCC PAVEMENT ON 10" LIMEROCK STA

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 9R-27L RUNWAY 9R-27	<b>Section:</b> 6315	<b>Surface:</b> AAC		
L.C.D.:	1/1/2010	Use: RUNWAY Rank: P Length: 6,230.00 (Ft) Width: 100.00 (Ft)	True Area: 603,300.00 (SqFt)			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1975	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1975 11 1/2" AC OVERLAY
1/1/1956	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1956 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

<b>Network:</b> CECIL AIRPORT		<b>Branch:</b> RW 9R-27L RUNWAY 9R-27	<b>Section:</b> 6317	<b>Surface:</b> AAC		
L.C.D.:	1/1/2011	Use: RUNWAY Rank: S Length: 200.00 (Ft) Width: 100.00 (Ft)	True Area: 20,000.00 (SqFt)			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 16 of 30

Network: CECIL AIRPORT		Branch: RW 9R-27L RUNWAY 9R-27	Section: 6320	Surface: AAC		
L.C.D.:	1/1/2010	Use: RUNWAY Rank: P Length: 5,850.00 (Ft)	Width: 100.00 (Ft)	True Area: 585,202.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1975	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1956	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1956 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: RW 9R-27L RUNWAY 9R-27	Section: 6322	Surface: AAC		
L.C.D.:	1/1/2011	Use: RUNWAY Rank: S Length: 200.00 (Ft)	Width: 97.00 (Ft)	True Area: 19,400.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	OL-AC	Overlay - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: RW 9R-27L RUNWAY 9R-27	Section: 6325	Surface: PCC		
L.C.D.:	1/1/1992	Use: RUNWAY Rank: P Length: 570.00 (Ft)	Width: 100.00 (Ft)	True Area: 57,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
1/1/1992	IMPORT ED	BUILT	0.00	12.00	<input checked="" type="checkbox"/>	1992 12" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: RW 9R-27L RUNWAY 9R-27	Section: 6330	Surface: PCC		
L.C.D.:	1/1/1992	Use: RUNWAY Rank: P Length: 1,140.00 (Ft)	Width: 50.00 (Ft)	True Area: 55,290.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
1/1/1992	IMPORT ED	BUILT	0.00	12.00	<input checked="" type="checkbox"/>	1992 12" PCC PAVEMENT

Network: CECIL AIRPORT		Branch: RW 9R-27L RUNWAY 9R-27	Section: 6335	Surface: PCC		
L.C.D.:	1/1/1956	Use: RUNWAY Rank: P Length: 500.00 (Ft)	Width: 100.00 (Ft)	True Area: 50,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" REINFORCED PCC PAVEMENT ON 10" LIMEROCK BAS

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 17 of 30

Network: CECIL AIRPORT		Branch: RW 9R-27L RUNWAY 9R-27	Section: 6340	Surface: PCC		
L.C.D.:	1/1/1956	Use: RUNWAY Rank: P	Length: 1,000.00 (Ft)	Width: 50.00 (Ft) True Area: 48,500.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" REINFORCED PCC PAVEMENT ON 10" LIMEROCK BAS

Network: CECIL AIRPORT		Branch: TW A	TAXIWAY A	Section: 105	Surface: PCC	
L.C.D.:	1/1/1958	Use: TAXIWAY Rank: T	Length: 900.00 (Ft)	Width: 75.00 (Ft)	True Area: 67,381.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1958	IMPORT ED	BUILT	0.00	12.00	<input checked="" type="checkbox"/>	1958 12" REINFORCED PCC PAVEMENT ON 12" COMPACTED S

Network: CECIL AIRPORT		Branch: TW A	TAXIWAY A	Section: 110	Surface: PCC	
L.C.D.:	1/1/1959	Use: TAXIWAY Rank: P	Length: 3,600.00 (Ft)	Width: 75.00 (Ft)	True Area: 269,943.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1959	IMPORT ED	BUILT	0.00	11.00	<input checked="" type="checkbox"/>	1959 11" PCC PAVEMENT ON 10" LIMEROCK BASE ON 12" COMPACT

Network: CECIL AIRPORT		Branch: TW A	TAXIWAY A	Section: 115	Surface: PCC	
L.C.D.:	1/1/1951	Use: TAXIWAY Rank: P	Length: 700.00 (Ft)	Width: 75.00 (Ft)	True Area: 54,396.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE ON COMPACTE

8/8/2017

**Work History Report**  
*Pavement Database: FDOT*

Page 18 of 30

Network: CECIL AIRPORT		Branch: TW A	TAXIWAY A	Section: 117	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 120.00 (Ft)	Width: 75.00 (Ft)	True Area: 27,484.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" MILL AND AC OVERLAY
1/1/1975	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" MILL AND AC OVERLAY
1/1/1956	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1956 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW A	TAXIWAY A	Section: 120	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 250.00 (Ft)	Width: 75.00 (Ft)	True Area: 18,750.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1981	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1981 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1959 PRE MIXED SEAL COAT
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW A	TAXIWAY A	Section: 125	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 100.00 (Ft)	Width: 100.00 (Ft)	True Area: 19,405.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC MILL AND OVERLAY
1/1/1975	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1956	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1956 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW A	TAXIWAY A	Section: 130	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 6,100.00 (Ft)	Width: 75.00 (Ft)	True Area: 457,575.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED SUBBASE

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 19 of 30

Network: CECIL AIRPORT		Branch: TW A1	TAXIWAY A1	Section: 505	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: T	Length: 500.00 (Ft)	Width: 150.00 (Ft)	True Area: 77,280.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1960	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1960 RESEAL PCCP JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC

Network: CECIL AIRPORT		Branch: TW A1	TAXIWAY A1	Section: 510	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 360.00 (Ft)	Width: 150.00 (Ft)	True Area: 58,667.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1960	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1960 RESEAL PCC JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT ON UNKNOWN FOUNDATION

Network: CECIL AIRPORT		Branch: TW A1	TAXIWAY A1	Section: 515	Surface: PCC	
L.C.D.: 1/1/1954		Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 210.00 (Ft)	True Area: 67,256.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLAB REPAIRS SPALLS AND JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT ON UNKNOWN FOUNDATION

Network: CECIL AIRPORT		Branch: TW A2	TAXIWAY A2	Section: 603	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 75.00 (Ft)	True Area: 26,792.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1951	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 20 of 30

Network: CECIL AIRPORT		Branch: TW A2	TAXIWAY A2	Section: 605	Surface: AAC	
L.C.D.:	1/1/2011	Use: TAXIWAY	Rank: P	Length: 150.00 (Ft)	Width: 75.00 (Ft)	True Area: 11,684.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1981	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1981 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1959 SEAL COAT
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW A2	TAXIWAY A2	Section: 607	Surface: AAC	
L.C.D.:	1/1/2011	Use: TAXIWAY	Rank: P	Length: 100.00 (Ft)	Width: 75.00 (Ft)	True Area: 7,608.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1975	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1961	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1961 AND 1956 SEAL COAT
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW A2	TAXIWAY A2	Section: 608	Surface: AAC	
L.C.D.:	1/1/2011	Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 75.00 (Ft)	True Area: 7,608.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
5/1/2007	PAS-AC	Patching - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1975	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1975 1 1/2" AC OVERLAY
1/1/1961	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1961 AND 1956 SEAL COAT
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW A2	TAXIWAY A2	Section: 610	Surface: APC	
L.C.D.:	1/1/2011	Use: TAXIWAY	Rank: P	Length: 75.00 (Ft)	Width: 50.00 (Ft)	True Area: 4,184.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
5/1/2007	PAS-AC	Patching - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1982 1 1/2" AC OVERLAY
1/1/1981	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1981 1965 AND 1960 CLEAN AND RESEAL JOINTS REPAIR SPALLS A
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 21 of 30

Network: CECIL AIRPORT		Branch: TW A2	TAXIWAY A2	Section: 615	Surface: PCC	
L.C.D.: 1/1/1954		Use: TAXIWAY	Rank: P	Length: 260.00 (Ft)	Width: 75.00 (Ft)	True Area: 23,980.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT ON 6" STABILIZED BASE

Network: CECIL AIRPORT		Branch: TW A2	TAXIWAY A2	Section: 620	Surface: PCC	
L.C.D.: 1/1/1954		Use: TAXIWAY	Rank: P	Length: 210.00 (Ft)	Width: 75.00 (Ft)	True Area: 24,484.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND RESEAL JOINTS
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 PCC PAVEMENT

Network: CECIL AIRPORT		Branch: TW A3	TAXIWAY A3	Section: 703	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 75.00 (Ft)	True Area: 26,792.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1951	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: TW A3	TAXIWAY A3	Section: 705	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 150.00 (Ft)	Width: 75.00 (Ft)	True Area: 11,684.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1981	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1981 1 1/2" AC OVERLAY
1/1/1961	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1961 SEAL COAT
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

8/8/2017

**Work History Report**  
*Pavement Database: FDOT*

Page 22 of 30

Network: CECIL AIRPORT		Branch: TW A3	TAXIWAY A3		Section: 707	Surface: APC
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 75.00 (Ft)	True Area: 7,608.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1981	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

Network: CECIL AIRPORT		Branch: TW A3	TAXIWAY A3		Section: 708	Surface: APC
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 75.00 (Ft)	True Area: 7,608.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
5/1/2007	PAS-AC	Patching - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1981	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1965 AND 1960 SPALL REPAIRS AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

Network: CECIL AIRPORT		Branch: TW A3	TAXIWAY A3		Section: 710	Surface: APC
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 75.00 (Ft)	True Area: 4,184.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
5/1/2007	PAS-AC	Patching - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1981 1 1/2" AC OVERLAY
1/1/1965	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

Network: CECIL AIRPORT		Branch: TW A3	TAXIWAY A3		Section: 715	Surface: PCC
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 260.00 (Ft)	Width: 75.00 (Ft)	True Area: 23,980.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 23 of 30

Network: CECIL AIRPORT		Branch: TW A3	TAXIWAY A3	Section: 720	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 210.00 (Ft)	Width: 75.00 (Ft)	True Area: 24,484.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

Network: CECIL AIRPORT		Branch: TW A4	TAXIWAY A4	Section: 805	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 360.00 (Ft)	Width: 150.00 (Ft)	True Area: 57,662.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PF	Patching - PCC Full-Depth	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

Network: CECIL AIRPORT		Branch: TW A4	TAXIWAY A4	Section: 810	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 500.00 (Ft)	Width: 150.00 (Ft)	True Area: 79,426.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

Network: CECIL AIRPORT		Branch: TW A5	TAXIWAY A5	Section: 1005	Surface: PCC	
L.C.D.: 1/1/1958		Use: TAXIWAY	Rank: P	Length: 1,050.00 (Ft)	Width: 150.00 (Ft)	True Area: 166,214.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1958	IMPORT ED	BUILT	0.00	12.00	<input checked="" type="checkbox"/>	1958 12" REINFORCED PCC PAVEMENT ON 10" LIMEROCK BAS

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 24 of 30

Network: CECIL AIRPORT		Branch: TW B1	TAXIWAY B1	Section: 1105	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 370.00 (Ft)	Width: 150.00 (Ft)	True Area: 56,522.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND JOINT SEAL
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT

Network: CECIL AIRPORT		Branch: TW B1	TAXIWAY B1	Section: 1110	Surface: PCC	
L.C.D.: 1/1/1956		Use: TAXIWAY	Rank: P	Length: 500.00 (Ft)	Width: 150.00 (Ft)	True Area: 77,371.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 REPAIR SPALLS AND SEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" REINFORCED PCC PAVEMENT ON 10" LIMEROCK BAS

Network: CECIL AIRPORT		Branch: TW B1	TAXIWAY B1	Section: 1115	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: S	Length: 200.00 (Ft)	Width: 150.00 (Ft)	True Area: 30,000.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 REPAIR SPALLS
1/1/1960	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1960 RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW B	TAXIWAY B	Section: 205	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: T	Length: 4,680.00 (Ft)	Width: 75.00 (Ft)	True Area: 355,476.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	PA-SP	Spall Repairs	0.00	0.00	<input type="checkbox"/>	
5/1/2007	PA-PCC	Patching - PCC	0.00	0.00	<input type="checkbox"/>	
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1960	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1960 RESEAL PAVEMENT JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED SUBBASE

8/8/2017

**Work History Report**  
*Pavement Database: FDOT*

Page 25 of 30

Network: CECIL AIRPORT		Branch: TW B	TAXIWAY B	Section: 208	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 100.00 (Ft)	Width: 130.00 (Ft)	True Area: 19,400.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
5/1/2007	PAS-AC	Patching - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1975	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	EST 1975 VBL AC OVERLAY
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW B	TAXIWAY B	Section: 210	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 150.00 (Ft)	Width: 75.00 (Ft)	True Area: 11,684.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1982 1 1/2" AC OVERLAY
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW B	TAXIWAY B	Section: 212	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 100.00 (Ft)	Width: 75.00 (Ft)	True Area: 38,584.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1979	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1979 1 1/2" AC OVERLAY
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC ON 9" LIMEROCK BASE 6" STABILIZED SUBBASE

Network: CECIL AIRPORT		Branch: TW B2	TAXIWAY B2	Section: 1203	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 130.00 (Ft)	Width: 100.00 (Ft)	True Area: 11,792.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1951	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: CECIL AIRPORT		Branch: TW B2	TAXIWAY B2	Section: 1205	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: T	Length: 300.00 (Ft)	Width: 75.00 (Ft)	True Area: 22,500.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	BUILT	0.00	0.50	<input checked="" type="checkbox"/>	1982 1 1/2" AC OVERLAY
1/1/1951	IMPORT ED	OVERLAY	0.00	9.00	<input checked="" type="checkbox"/>	EST 1951 AC SURFACE ON 9" LIMEROCK BASE ON 6" SAND SUB

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 26 of 30

Network: CECIL AIRPORT		Branch: TW B2	TAXIWAY B2	Section: 1207	Surface: AAC	
L.C.D.: 1/1/2011		Use: TAXIWAY	Rank: P	Length: 220.00 (Ft)	Width: 75.00 (Ft)	True Area: 23,696.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1986 1 1/2" AC OVERLAY
1/1/1977	IMPORT ED	OVERLAY	0.00	0.50	<input checked="" type="checkbox"/>	1977 1 1/2" AC OVERLAY
1/1/1959	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1959 AND 1956 SEAL COAT
1/1/1951	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1951 3" AC SURFACE ON 9" LIMEROCK BASE ON 6" STABILIZE

Network: CECIL AIRPORT		Branch: TW B2	TAXIWAY B2	Section: 1210	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 240.00 (Ft)	Width: 75.00 (Ft)	True Area: 23,980.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC ON 6" STABILIZED SUBBASE

Network: CECIL AIRPORT		Branch: TW B2	TAXIWAY B2	Section: 1215	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 215.00 (Ft)	Width: 75.00 (Ft)	True Area: 24,522.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED SUBBASE

Network: CECIL AIRPORT		Branch: TW B	TAXIWAY B	Section: 215	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 2,200.00 (Ft)	Width: 75.00 (Ft)	True Area: 165,208.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1960	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1960 RESEAL PAVEMENT JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 27 of 30

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW B3	<b>TAXIWAY B3</b>	<b>Section:</b> 1405	<b>Surface:</b> PCC
L.C.D.: 1/1/1951	Use: TAXIWAY	Rank: P	Length: 370.00 (Ft)	Width: 150.00 (Ft) True Area: 58,667.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" REINFORCED PCC PAVEMENT ON 6" STABILIZED BA

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW B3	<b>TAXIWAY B3</b>	<b>Section:</b> 1410	<b>Surface:</b> PCC
L.C.D.: 1/1/1956	Use: TAXIWAY	Rank: P	Length: 500.00 (Ft)	Width: 150.00 (Ft) True Area: 77,505.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 AND 1960 SPALL REPAIR AND RESEAL JOINTS
1/1/1956	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1956 10" REINFORCED PCC PAVEMENT ON 10" LIMEROCK BAS

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW C	<b>TAXIWAY C</b>	<b>Section:</b> 305	<b>Surface:</b> PCC
L.C.D.: 1/1/1951	Use: TAXIWAY	Rank: P	Length: 2,400.00 (Ft)	Width: 75.00 (Ft) True Area: 175,845.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND RESEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW C	<b>TAXIWAY C</b>	<b>Section:</b> 310	<b>Surface:</b> PCC
L.C.D.: 1/1/1954	Use: TAXIWAY	Rank: P	Length: 1,700.00 (Ft)	Width: 80.00 (Ft) True Area: 136,320.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1954	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1954 10" PCC PAVEMENT ON UNKNOWN FOUNDATION

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW C	<b>TAXIWAY C</b>	<b>Section:</b> 315	<b>Surface:</b> AC
L.C.D.: 1/1/1960	Use: TAXIWAY	Rank: P	Length: 865.00 (Ft)	Width: 50.00 (Ft) True Area: 44,457.00 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1960	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1960 AC PAVEMENT UNKNOWN SECTION

8/8/2017

## Work History Report

*Pavement Database: FDOT*

Page 28 of 30

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW D2	<b>TAXIWAY D2</b>	<b>Section:</b> 905	<b>Surface:</b> AC		
L.C.D.: 1/1/2008	Use: TAXIWAY	Rank: P	Length: 600.00 (Ft)	Width: 100.00 (Ft) True Area: 59,738.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW D	<b>TAXIWAY D</b>	<b>Section:</b> 405	<b>Surface:</b> PCC		
L.C.D.: 1/1/1951	Use: TAXIWAY	Rank: P	Length: 5,460.00 (Ft)	Width: 75.00 (Ft) True Area: 435,222.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1991 SPALL REPAIR CLEAN AND RESEAL JOINTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW D	<b>TAXIWAY D</b>	<b>Section:</b> 410	<b>Surface:</b> PCC		
L.C.D.: 5/1/2005	Use: TAXIWAY	Rank: P	Length: 360.00 (Ft)	Width: 75.00 (Ft) True Area: 29,146.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW D	<b>TAXIWAY D</b>	<b>Section:</b> 415	<b>Surface:</b> AC		
L.C.D.: 1/1/2009	Use: TAXIWAY	Rank: P	Length: 1,645.00 (Ft)	Width: 75.00 (Ft) True Area: 123,375.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW D	<b>TAXIWAY D</b>	<b>Section:</b> 420	<b>Surface:</b> AC		
L.C.D.: 1/1/2008	Use: TAXIWAY	Rank: P	Length: 400.00 (Ft)	Width: 100.00 (Ft) True Area: 31,875.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW E1	<b>TAXIWAY E1</b>	<b>Section:</b> 1605	<b>Surface:</b> AC		
L.C.D.: 1/1/2015	Use: TAXIWAY	Rank: P	Length: 1,016.00 (Ft)	Width: 95.00 (Ft) True Area: 99,253.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	5" P-401, 13" P-211, P-152

<b>Network:</b> CECIL AIRPORT	<b>Branch:</b> TW E	<b>TAXIWAY E</b>	<b>Section:</b> 1610	<b>Surface:</b> AC		
L.C.D.: 1/1/2015	Use: TAXIWAY	Rank: P	Length: 3,040.00 (Ft)	Width: 75.00 (Ft) True Area: 228,000.00 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	5" P-401, 13" P-211, P-152

8/8/2017

**Work History Report**  
*Pavement Database: FDOT*

Page 29 of 30

Network: CECIL AIRPORT		Branch: TW M	TAXIWAY M	Section: 1305	Surface: PCC	
L.C.D.: 1/1/1951		Use: TAXIWAY	Rank: P	Length: 210.00 (Ft)	Width: 75.00 (Ft)	True Area: 22,376.00 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1981	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1981 CLEAN AND SEAL JOINTS REPAIR SPALLS AND POPOUTS
1/1/1965	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1965 SPALL REPAIR
1/1/1951	IMPORT ED	BUILT	0.00	10.00	<input checked="" type="checkbox"/>	1951 10" PCC PAVEMENT ON 6" STABILIZED BASE

8/8/2017

**Work History Report**  
*Pavement Database: FDOT*

Page 30 of 30

**Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	111	14,049,859.00	7.03	4.11
FDOT - PATCHING - PCC PARTIAL DEPTH	1	14,325.00	0.00	0.00
MILL and OVERLAY	31	3,090,099.00	0.00	0.00
New Construction - AC	7	461,328.00	0.00	0.00
New Construction - Initial	20	877,400.00	0.00	0.00
New Construction - PCC	1	60,000.00	0.00	0.00
OVERLAY	63	11,131,162.00	0.85	2.11
Overlay - AC	10	254,600.00	0.00	0.00
Patching - AC	5	42,984.00	0.00	0.00
Patching - PCC	23	2,855,988.00	0.00	0.00
Patching - PCC Full-Depth	1	57,662.00	0.00	0.00
REPAIR	115	14,990,894.00	0.00	0.00
Spall Repairs	15	1,813,126.00	0.00	0.00

8/8/2017

**Branch Condition Report****Page 1 of 2***Pavement Database: FDOT*

<b>Branch ID</b>	<b>Number of Sections</b>	<b>Sum Section Length (Ft)</b>	<b>Avg Section Width (Ft)</b>	<b>True Area (SqFt)</b>	<b>Use</b>	<b>Average PCI</b>	<b>Standard Deviation PCI</b>	<b>Weighted Average PCI</b>
AP E	2	512.00	162.50	86,675.00	APRON	100.00	0.00	100.00
AP N	14	8,802.50	253.64	3,015,738.00	APRON	76.79	10.61	75.30
AP N RFUE	4	420.00	200.00	88,460.00	APRON	65.75	14.36	65.75
AP NAT GR	2	1,253.00	145.00	229,356.00	APRON	90.50	2.50	92.34
AP W	13	8,442.00	172.08	1,423,839.00	APRON	55.69	29.38	70.73
AP W RFUE	5	920.00	110.00	101,550.00	APRON	61.20	20.87	64.00
RW 18L-36	10	30,504.00	85.00	2,500,800.00	RUNWAY	80.30	4.10	82.71
RW 18R-36	16	22,944.00	84.37	1,560,800.00	RUNWAY	77.31	18.38	47.17
RW 9L-27R	10	9,999.00	85.00	887,544.00	RUNWAY	68.70	23.29	45.10
RW 9R-27L	10	17,190.00	84.70	1,537,192.00	RUNWAY	79.20	5.84	80.03
TW A	7	11,770.00	78.57	914,934.00	TAXIWAY	79.29	8.55	78.74
TW A1	3	1,160.00	170.00	203,203.00	TAXIWAY	80.67	4.71	80.69
TW A2	7	1,145.00	71.43	106,340.00	TAXIWAY	88.00	7.11	85.24
TW A3	7	1,070.00	75.00	106,340.00	TAXIWAY	88.57	7.67	85.87
TW A4	2	860.00	150.00	137,088.00	TAXIWAY	79.00	2.00	79.32
TW A5	1	1,050.00	150.00	166,214.00	TAXIWAY	75.00	0.00	75.00
TW B	5	7,230.00	86.00	590,352.00	TAXIWAY	87.20	4.40	83.38
TW B1	3	1,070.00	150.00	163,893.00	TAXIWAY	77.33	1.25	77.51
TW B2	5	1,105.00	80.00	106,490.00	TAXIWAY	82.60	8.80	81.81
TW B3	2	870.00	150.00	136,172.00	TAXIWAY	77.50	1.50	77.71
TW C	3	4,965.00	68.33	356,622.00	TAXIWAY	61.00	22.11	71.09
TW D	4	7,865.00	81.25	619,618.00	TAXIWAY	80.50	10.97	77.67
TW D2	1	600.00	100.00	59,738.00	TAXIWAY	78.00	0.00	78.00
TW E	1	3,040.00	75.00	228,000.00	TAXIWAY	100.00	0.00	100.00
TW E1	1	1,016.00	95.00	99,253.00	TAXIWAY	100.00	0.00	100.00
TW M	1	210.00	75.00	22,376.00	TAXIWAY	81.00	0.00	81.00

8/8/2017

**Branch Condition Report****Page 2 of 2***Pavement Database: FDOT*

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	40	4945618.0005137	68.73	23.54	74.81
RUNWAY	46	6486336.001701	76.50	16.27	68.38
TAXIWAY	53	4016633.00043941	82.38	11.25	80.63
ALL	139	15448587.0026541	76.50	18.05	73.62

Pavement Database: FDOT

NetworkId: VQQ

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP E	4405	1/1/2015	AC	APRON	P	0	26,675.00	1/1/2015	0	100
AP E	4410	1/1/2015	PCC	APRON	P	0	60,000.00	1/1/2015	0	100
AP N	4103	1/1/1954	PCC	APRON	P	0	62,610.00	5/22/2017	63	73
AP N	4105	1/1/1988	PCC	APRON	P	0	172,130.00	5/22/2017	29	71
AP N	4110	1/1/1956	PCC	APRON	P	0	290,625.00	5/22/2017	61	56
AP N	4115	1/1/1965	PCC	APRON	P	0	236,250.00	5/22/2017	52	78
AP N	4117	1/1/1954	PCC	APRON	P	0	14,325.00	5/22/2017	63	88
AP N	4120	1/1/1954	PCC	APRON	P	0	391,125.00	5/22/2017	63	73
AP N	4125	1/1/1951	PCC	APRON	P	0	1,403,402.00	5/22/2017	66	79
AP N	4132	1/1/1951	PCC	APRON	P	0	37,875.00	5/22/2017	66	75
AP N	4137	1/1/1951	PCC	APRON	P	0	74,250.00	5/22/2017	66	68
AP N	4138	1/1/1953	PCC	APRON	P	0	11,250.00	5/22/2017	64	74
AP N	4140	1/1/1951	PCC	APRON	P	0	102,688.00	5/22/2017	66	71
AP N	4150	1/1/1965	PCC	APRON	P	0	105,074.00	5/22/2017	52	75
AP N	4305	5/1/2005	PCC	APRON	S	0	70,920.00	5/22/2017	12	95
AP N	4310	1/1/2011	PCC	APRON	P	0	43,214.00	5/22/2017	6	99
AP N RFUEL	5125	1/1/1954	PCC	APRON	P	0	22,115.00	5/22/2017	63	76
AP N RFUEL	5130	1/1/1954	PCC	APRON	P	0	22,115.00	5/22/2017	63	81
AP N RFUEL	5135	1/1/1954	PCC	APRON	P	0	22,115.00	5/22/2017	63	62
AP N RFUEL	5140	1/1/1954	PCC	APRON	P	0	22,115.00	5/22/2017	63	44
AP NAT GRD	5305	1/1/1976	PCC	APRON	P	0	30,200.00	5/22/2017	41	88
AP NAT GRD	5310	1/1/2010	PCC	APRON	P	0	199,156.00	5/22/2017	7	93
AP W	4205	1/1/1955	PCC	APRON	P	0	166,732.00	5/22/2017	62	72
AP W	4210	1/1/1959	PCC	APRON	P	0	233,520.00	5/22/2017	58	77
AP W	4220	1/1/1960	PCC	APRON	P	0	266,686.00	5/22/2017	57	76
AP W	4225	1/1/1991	PCC	APRON	P	0	35,000.00	5/22/2017	26	14
AP W	4230	1/1/1955	PCC	APRON	P	0	26,250.00	5/22/2017	62	12
AP W	4235	1/1/1955	PCC	APRON	P	0	13,730.00	5/22/2017	62	12
AP W	4240	1/1/1955	PCC	APRON	P	0	82,954.00	5/22/2017	62	75
AP W	4245	1/1/1955	PCC	APRON	P	0	102,240.00	5/22/2017	62	75
AP W	4250	1/1/1976	PCC	APRON	P	0	285,584.00	5/22/2017	41	72
AP W	4255	1/1/1955	PCC	APRON	P	0	19,950.00	5/22/2017	62	9
AP W	4260	1/1/1961	PCC	APRON	P	0	50,613.00	5/22/2017	56	77
AP W	4265	1/1/1955	PCC	APRON	P	0	99,400.00	5/22/2017	62	80
AP W	4270	1/1/1955	PCC	APRON	P	0	41,180.00	5/22/2017	62	73
AP W RFUEL	5005	1/1/1956	PCC	APRON	P	0	22,135.00	5/22/2017	61	78
AP W RFUEL	5010	1/1/1956	PCC	APRON	P	0	22,135.00	5/22/2017	61	72
AP W RFUEL	5015	1/1/1956	PCC	APRON	P	0	22,135.00	5/22/2017	61	83
AP W RFUEL	5020	1/1/1956	PCC	APRON	P	0	22,135.00	5/22/2017	61	43
AP W RFUEL	5055	1/1/1955	PCC	APRON	P	0	13,010.00	5/22/2017	62	30
RW 18L-36R	6205	1/1/1951	PCC	RUNWAY	T	0	50,000.00	5/22/2017	66	79
RW 18L-36R	6210	1/1/1951	PCC	RUNWAY	P	0	50,000.00	5/22/2017	66	83
RW 18L-36R	6215	1/1/2011	AAC	RUNWAY	P	0	638,300.00	5/22/2017	6	82
RW 18L-36R	6217	1/1/2011	AAC	RUNWAY	P	0	61,900.00	5/22/2017	6	79
RW 18L-36R	6220	1/1/2011	AAC	RUNWAY	P	0	638,300.00	5/22/2017	6	86
RW 18L-36R	6222	1/1/2011	AAC	RUNWAY	P	0	61,900.00	5/22/2017	6	75
RW 18L-36R	6225	1/1/1951	PCC	RUNWAY	P	0	50,200.00	5/22/2017	66	72
RW 18L-36R	6230	1/1/1951	PCC	RUNWAY	P	0	50,200.00	5/22/2017	66	82
RW 18L-36R	6235	1/1/1959	PCC	RUNWAY	P	0	450,000.00	5/22/2017	58	80

8/8/2017		Section Condition Report							Page 2 of 4	
RW 18L-36R	6240	1/1/1959	PCC	RUNWAY	P	0	450,000.00	5/22/2017	58	85
RW 18R-36L	6105	1/1/1951	PCC	RUNWAY	T	0	50,000.00	5/22/2017	66	79
RW 18R-36L	6110	1/1/1951	PCC	RUNWAY	S	0	50,000.00	5/22/2017	66	77
RW 18R-36L	6115	1/1/1986	AAC	RUNWAY	S	0	542,800.00	5/22/2017	31	30
RW 18R-36L	6120	1/1/1986	AAC	RUNWAY	S	0	542,800.00	5/22/2017	31	33
RW 18R-36L	6125	1/1/1986	PCC	RUNWAY	S	0	30,000.00	5/22/2017	31	74
RW 18R-36L	6130	1/1/1986	PCC	RUNWAY	S	0	30,000.00	5/22/2017	31	88
RW 18R-36L	6135	1/1/1951	PCC	RUNWAY	S	0	50,000.00	5/22/2017	66	74
RW 18R-36L	6140	1/1/1951	PCC	RUNWAY	S	0	50,000.00	5/22/2017	66	84
RW 18R-36L	6145	1/1/2011	AAC	RUNWAY	S	0	26,000.00	5/22/2017	6	91
RW 18R-36L	6150	1/1/2011	AAC	RUNWAY	S	0	26,000.00	5/22/2017	6	93
RW 18R-36L	6155	1/1/2011	AAC	RUNWAY	S	0	30,000.00	5/22/2017	6	89
RW 18R-36L	6160	1/1/2011	AAC	RUNWAY	S	0	30,000.00	5/22/2017	6	88
RW 18R-36L	6165	1/1/2011	AAC	RUNWAY	S	0	31,200.00	5/22/2017	6	87
RW 18R-36L	6170	1/1/2011	AAC	RUNWAY	S	0	31,200.00	5/22/2017	6	88
RW 18R-36L	6175	1/1/2011	AAC	RUNWAY	S	0	20,400.00	5/22/2017	6	74
RW 18R-36L	6180	1/1/2011	AAC	RUNWAY	S	0	20,400.00	5/22/2017	6	88
RW 9L-27R	6405	1/1/1951	PCC	RUNWAY	T	0	50,000.00	5/22/2017	66	81
RW 9L-27R	6410	1/1/1951	PCC	RUNWAY	S	0	50,000.00	5/22/2017	66	77
RW 9L-27R	6414	1/1/2006	AAC	RUNWAY	S	0	56,500.00	5/22/2017	11	51
RW 9L-27R	6415	1/1/1986	AAC	RUNWAY	S	0	283,572.00	5/22/2017	31	27
RW 9L-27R	6417	1/1/2006	AAC	RUNWAY	S	0	28,250.00	5/22/2017	11	59
RW 9L-27R	6420	1/1/1986	AAC	RUNWAY	S	0	311,822.00	5/22/2017	31	33
RW 9L-27R	6425	1/1/2011	AAC	RUNWAY	S	0	33,700.00	5/22/2017	6	88
RW 9L-27R	6430	1/1/2011	AAC	RUNWAY	S	0	33,700.00	5/22/2017	6	91
RW 9L-27R	6435	1/1/2011	AAC	RUNWAY	S	0	20,000.00	5/22/2017	6	92
RW 9L-27R	6440	1/1/2011	AAC	RUNWAY	S	0	20,000.00	5/22/2017	6	88
RW 9R-27L	6305	1/1/1956	PCC	RUNWAY	P	0	50,000.00	5/22/2017	61	76
RW 9R-27L	6310	1/1/1956	PCC	RUNWAY	P	0	48,500.00	5/22/2017	61	79
RW 9R-27L	6315	1/1/2010	AAC	RUNWAY	P	0	603,300.00	5/22/2017	7	76
RW 9R-27L	6317	1/1/2011	AAC	RUNWAY	S	0	20,000.00	5/22/2017	6	76
RW 9R-27L	6320	1/1/2010	AAC	RUNWAY	P	0	585,202.00	5/22/2017	7	84
RW 9R-27L	6322	1/1/2011	AAC	RUNWAY	S	0	19,400.00	5/22/2017	6	71
RW 9R-27L	6325	1/1/1992	PCC	RUNWAY	P	0	57,000.00	5/22/2017	25	89
RW 9R-27L	6330	1/1/1992	PCC	RUNWAY	P	0	55,290.00	5/22/2017	25	89
RW 9R-27L	6335	1/1/1956	PCC	RUNWAY	P	0	50,000.00	5/22/2017	61	78
RW 9R-27L	6340	1/1/1956	PCC	RUNWAY	P	0	48,500.00	5/22/2017	61	74
TW A	105	1/1/1958	PCC	TAXIWAY	T	0	67,381.00	5/22/2017	59	62
TW A	110	1/1/1959	PCC	TAXIWAY	P	0	269,943.00	5/22/2017	58	75
TW A	115	1/1/1951	PCC	TAXIWAY	P	0	54,396.00	5/22/2017	66	86
TW A	117	1/1/2011	AAC	TAXIWAY	P	0	27,484.00	5/22/2017	6	78
TW A	120	1/1/2011	AAC	TAXIWAY	P	0	18,750.00	5/22/2017	6	91
TW A	125	1/1/2011	AAC	TAXIWAY	P	0	19,405.00	5/22/2017	6	81
TW A	130	1/1/1951	PCC	TAXIWAY	P	0	457,575.00	5/22/2017	66	82
TW A1	505	1/1/1951	PCC	TAXIWAY	T	0	77,280.00	5/22/2017	66	84
TW A1	510	1/1/1951	PCC	TAXIWAY	P	0	58,667.00	5/22/2017	66	84
TW A1	515	1/1/1954	PCC	TAXIWAY	P	0	67,256.00	5/22/2017	63	74
TW A2	603	1/1/2011	AAC	TAXIWAY	P	0	26,792.00	5/22/2017	6	90
TW A2	605	1/1/2011	AAC	TAXIWAY	P	0	11,684.00	5/22/2017	6	90
TW A2	607	1/1/2011	AAC	TAXIWAY	P	0	7,608.00	5/22/2017	6	91
TW A2	608	1/1/2011	AAC	TAXIWAY	P	0	7,608.00	5/22/2017	6	94
TW A2	610	1/1/2011	APC	TAXIWAY	P	0	4,184.00	5/22/2017	6	94
TW A2	615	1/1/1954	PCC	TAXIWAY	P	0	23,980.00	5/22/2017	63	85
TW A2	620	1/1/1954	PCC	TAXIWAY	P	0	24,484.00	5/22/2017	63	72
TW A3	703	1/1/2011	AAC	TAXIWAY	P	0	26,792.00	5/22/2017	6	94

8/8/2017		Section Condition Report							Page 3 of 4	
TW A3	705	1/1/2011	AAC	TAXIWAY	P	0	11,684.00	5/22/2017	6	92
TW A3	707	1/1/2011	APC	TAXIWAY	P	0	7,608.00	5/22/2017	6	92
TW A3	708	1/1/2011	APC	TAXIWAY	P	0	7,608.00	5/22/2017	6	94
TW A3	710	1/1/2011	APC	TAXIWAY	P	0	4,184.00	5/22/2017	6	94
TW A3	715	1/1/1951	PCC	TAXIWAY	P	0	23,980.00	5/22/2017	66	81
TW A3	720	1/1/1951	PCC	TAXIWAY	P	0	24,484.00	5/22/2017	66	73
TW A4	805	1/1/1951	PCC	TAXIWAY	P	0	57,662.00	5/22/2017	66	77
TW A4	810	1/1/1951	PCC	TAXIWAY	P	0	79,426.00	5/22/2017	66	81
TW A5	1005	1/1/1958	PCC	TAXIWAY	P	0	166,214.00	5/22/2017	59	75
TW B	205	1/1/1951	PCC	TAXIWAY	T	0	355,476.00	5/22/2017	66	83
TW B	208	1/1/2011	AAC	TAXIWAY	P	0	19,400.00	5/22/2017	6	89
TW B	210	1/1/2011	AAC	TAXIWAY	P	0	11,684.00	5/22/2017	6	91
TW B	212	1/1/2011	AAC	TAXIWAY	P	0	38,584.00	5/22/2017	6	92
TW B	215	1/1/1951	PCC	TAXIWAY	P	0	165,208.00	5/22/2017	66	81
TW B1	1105	1/1/1951	PCC	TAXIWAY	P	0	56,522.00	5/22/2017	66	79
TW B1	1110	1/1/1956	PCC	TAXIWAY	P	0	77,371.00	5/22/2017	61	77
TW B1	1115	1/1/1951	PCC	TAXIWAY	S	0	30,000.00	5/22/2017	66	76
TW B2	1203	1/1/2011	AAC	TAXIWAY	P	0	11,792.00	5/22/2017	6	88
TW B2	1205	1/1/2011	AAC	TAXIWAY	T	0	22,500.00	5/22/2017	6	90
TW B2	1207	1/1/2011	AAC	TAXIWAY	P	0	23,696.00	5/22/2017	6	91
TW B2	1210	1/1/1951	PCC	TAXIWAY	P	0	23,980.00	5/22/2017	66	70
TW B2	1215	1/1/1951	PCC	TAXIWAY	P	0	24,522.00	5/22/2017	66	74
TW B3	1405	1/1/1951	PCC	TAXIWAY	P	0	58,667.00	5/22/2017	66	76
TW B3	1410	1/1/1956	PCC	TAXIWAY	P	0	77,505.00	5/22/2017	61	79
TW C	305	1/1/1951	PCC	TAXIWAY	P	0	175,845.00	5/22/2017	66	80
TW C	310	1/1/1954	PCC	TAXIWAY	P	0	136,320.00	5/22/2017	63	73
TW C	315	1/1/1960	AC	TAXIWAY	P	0	44,457.00	5/22/2017	57	30
TW D	405	1/1/1951	PCC	TAXIWAY	P	0	435,222.00	5/22/2017	66	75
TW D	410	5/1/2005	PCC	TAXIWAY	P	0	29,146.00	5/22/2017	12	95
TW D	415	1/1/2009	AC	TAXIWAY	P	0	123,375.00	5/22/2017	8	86
TW D	420	1/1/2008	AC	TAXIWAY	P	0	31,875.00	5/22/2017	9	66
TW D2	905	1/1/2008	AC	TAXIWAY	P	0	59,738.00	5/22/2017	9	78
TW E	1610	1/1/2015	AC	TAXIWAY	P	0	228,000.00	1/1/2015	0	100
TW E1	1605	1/1/2015	AC	TAXIWAY	P	0	99,253.00	1/1/2015	0	100
TW M	1305	1/1/1951	PCC	TAXIWAY	P	0	22,376.00	5/22/2017	66	81

8/8/2017

**Section Condition Report (Summary)****Page 4 of 4***Pavement Database: FDOT*

<b>Age Category</b>	<b>Average Age at Inspection</b>	<b>Total Area (SqFt)</b>	<b>Number of Sections</b>	<b>Arithmetic Average PCI</b>	<b>Standard Deviation PCI</b>	<b>Weighted Average PCI</b>
00-02		413,928.00	4	100.00	0.00	100.00
06-10	6	3,717,307.00	44	86.91	7.15	83.66
11-15	12	184,816.00	4	75.00	20.20	76.05
21-25	25	112,290.00	2	89.00	0.00	89.00
26-30	28	207,130.00	2	42.50	28.50	61.37
31-35	31	1,740,994.00	6	47.50	24.12	32.74
41-50	41	315,784.00	2	80.00	8.00	73.53
ALL	39	15,448,587.00	139	76.50	18.05	73.62
Over 50	63	8,756,338.00	75	72.03	16.32	76.29

# Appendix B

Airfield Pavement Localized Maintenance and Repair and  
Major Rehabilitation



Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	AP N	4120	65	JT SEAL DMG	Low	1120	Slabs	50.0%	FDOT - JOINT SEAL - PCC	30137.47	Ft	\$ 2.75	\$ 82,880.00
VQQ	AP N	4120	66	SMALL PATCH	Medium	134.4	Slabs	6.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	361.67	SqFt	\$ 72.00	\$ 26,050.00
VQQ	AP N	4120	67	LARGE PATCH	Medium	11.2	Slabs	0.5%	FDOT - PATCHING - PCC FULL DEPTH	826.67	SqFt	\$ 185.00	\$ 152,960.00
VQQ	AP N	4120	74	JOINT SPALL	Medium	56	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	361.67	SqFt	\$ 72.00	\$ 26,050.00
VQQ	AP N	4120	75	CORNER SPALL	Low	67.2	Slabs	3.0%	FDOT - CRACK SEALING - PCC	110.24	Ft	\$ 4.25	\$ 470.00
VQQ	AP N	4120	75	CORNER SPALL	Medium	67.2	Slabs	3.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	180.83	SqFt	\$ 72.00	\$ 13,030.00
VQQ	AP N	4125	65	JT SEAL DMG	Low	2220	Slabs	30.0%	FDOT - JOINT SEAL - PCC	60103.02	Ft	\$ 2.75	\$ 165,290.00
VQQ	AP N	4125	66	SMALL PATCH	Medium	74	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	199.13	SqFt	\$ 72.00	\$ 14,340.00
VQQ	AP N	4125	67	LARGE PATCH	Medium	37	Slabs	0.5%	FDOT - PATCHING - PCC FULL DEPTH	2730.8	SqFt	\$ 185.00	\$ 505,300.00
VQQ	AP N	4125	70	SCALING	Medium	74	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	4552.06	SqFt	\$ 72.00	\$ 327,760.00
VQQ	AP N	4125	74	JOINT SPALL	Low	74	Slabs	1.0%	FDOT - CRACK SEALING - PCC	121.39	Ft	\$ 4.25	\$ 520.00
VQQ	AP N	4125	74	JOINT SPALL	Medium	37	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	238.96	SqFt	\$ 72.00	\$ 17,210.00
VQQ	AP N	4125	75	CORNER SPALL	Low	111	Slabs	1.5%	FDOT - CRACK SEALING - PCC	182.09	Ft	\$ 4.25	\$ 780.00
VQQ	AP N	4125	75	CORNER SPALL	Medium	37	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	99.03	SqFt	\$ 72.00	\$ 7,170.00
VQQ	AP N	4132	70	SCALING	Medium	5.65	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	347.67	SqFt	\$ 72.00	\$ 25,030.00
VQQ	AP N	4132	74	JOINT SPALL	Low	16.95	Slabs	7.5%	FDOT - CRACK SEALING - PCC	27.89	Ft	\$ 4.25	\$ 120.00
VQQ	AP N	4132	75	CORNER SPALL	Low	11.3	Slabs	5.0%	FDOT - CRACK SEALING - PCC	18.37	Ft	\$ 4.25	\$ 80.00
VQQ	AP N	4137	62	CORNER BREAK	Medium	6.03	Slabs	1.7%	FDOT - PATCHING - PCC FULL DEPTH	194.83	SqFt	\$ 185.00	\$ 36,050.00
VQQ	AP N	4137	63	LINEAR CR	High	6.03	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	272.33	SqFt	\$ 72.00	\$ 19,600.00
VQQ	AP N	4137	65	JT SEAL DMG	Low	241.33	Slabs	66.7%	FDOT - JOINT SEAL - PCC	4616.47	Ft	\$ 2.75	\$ 12,700.00
VQQ	AP N	4137	74	JOINT SPALL	Low	12.07	Slabs	3.3%	FDOT - CRACK SEALING - PCC	19.69	Ft	\$ 4.25	\$ 90.00
VQQ	AP N	4137	74	JOINT SPALL	Medium	12.07	Slabs	3.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	77.5	SqFt	\$ 72.00	\$ 5,620.00
VQQ	AP N	4137	75	CORNER SPALL	Low	6.03	Slabs	1.7%	FDOT - CRACK SEALING - PCC	9.84	Ft	\$ 4.25	\$ 50.00
VQQ	AP N	4137	75	CORNER SPALL	Medium	12.07	Slabs	3.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	32.29	SqFt	\$ 72.00	\$ 2,340.00
VQQ	AP N	4138	65	JT SEAL DMG	Low	60	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1252.62	Ft	\$ 2.75	\$ 3,450.00
VQQ	AP N	4138	66	SMALL PATCH	Medium	3	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.61	SqFt	\$ 72.00	\$ 590.00
VQQ	AP N	4138	74	JOINT SPALL	Low	6	Slabs	10.0%	FDOT - CRACK SEALING - PCC	9.84	Ft	\$ 4.25	\$ 50.00
VQQ	AP N	4138	75	CORNER SPALL	Low	3	Slabs	5.0%	FDOT - CRACK SEALING - PCC	4.92	Ft	\$ 4.25	\$ 30.00
VQQ	AP N	4140	65	JT SEAL DMG	Low	548	Slabs	100.0%	FDOT - JOINT SEAL - PCC	14674.87	Ft	\$ 2.75	\$ 40,360.00
VQQ	AP N	4140	74	JOINT SPALL	Low	73.07	Slabs	13.3%	FDOT - CRACK SEALING - PCC	119.75	Ft	\$ 4.25	\$ 510.00
VQQ	AP N	4140	74	JOINT SPALL	Medium	9.13	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	59.2	SqFt	\$ 72.00	\$ 4,250.00
VQQ	AP N	4140	75	CORNER SPALL	Low	27.4	Slabs	5.0%	FDOT - CRACK SEALING - PCC	44.95	Ft	\$ 4.25	\$ 200.00
VQQ	AP N	4150	65	JT SEAL DMG	Low	484	Slabs	100.0%	FDOT - JOINT SEAL - PCC	12422.9	Ft	\$ 2.75	\$ 34,170.00
VQQ	AP N	4150	74	JOINT SPALL	Low	29.78	Slabs	6.2%	FDOT - CRACK SEALING - PCC	48.88	Ft	\$ 4.25	\$ 210.00
VQQ	AP N	4150	75	CORNER SPALL	Low	14.89	Slabs	3.1%	FDOT - CRACK SEALING - PCC	24.28	Ft	\$ 4.25	\$ 110.00
VQQ	AP N	4305	65	JT SEAL DMG	Low	315	Slabs	100.0%	FDOT - JOINT SEAL - PCC	8898.95	Ft	\$ 2.75	\$ 24,480.00
VQQ	AP N	4305	75	CORNER SPALL	Low	5.25	Slabs	1.7%	FDOT - CRACK SEALING - PCC	8.53	Ft	\$ 4.25	\$ 40.00
VQQ	AP N	4103	65	JT SEAL DMG	Low	495	Slabs	100.0%	FDOT - JOINT SEAL - PCC	9589.9	Ft	\$ 2.75	\$ 26,380.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	AP N	4103	66	SMALL PATCH	Medium	20.62	Slabs	4.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	55.97	SqFt	\$ 72.00	\$ 4,000.00
VQQ	AP N	4103	74	JOINT SPALL	Low	20.62	Slabs	4.2%	FDOT - CRACK SEALING - PCC	33.79	Ft	\$ 4.25	\$ 150.00
VQQ	AP N	4103	75	CORNER SPALL	Low	41.25	Slabs	8.3%	FDOT - CRACK SEALING - PCC	67.59	Ft	\$ 4.25	\$ 290.00
VQQ	AP N	4103	75	CORNER SPALL	Medium	20.62	Slabs	4.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	55.97	SqFt	\$ 72.00	\$ 4,000.00
VQQ	AP N	4105	62	CORNER BREAK	Low	9.18	Slabs	1.0%	FDOT - CRACK SEALING - PCC	75.46	Ft	\$ 4.25	\$ 330.00
VQQ	AP N	4105	65	JT SEAL DMG	Low	734.4	Slabs	80.0%	FDOT - JOINT SEAL - PCC	19773.29	Ft	\$ 2.75	\$ 54,380.00
VQQ	AP N	4105	65	JT SEAL DMG	High	183.6	Slabs	20.0%	FDOT - JOINT SEAL - PCC	4943.24	Ft	\$ 2.75	\$ 13,600.00
VQQ	AP N	4105	66	SMALL PATCH	Medium	9.18	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	24.76	SqFt	\$ 72.00	\$ 1,780.00
VQQ	AP N	4105	74	JOINT SPALL	Low	64.26	Slabs	7.0%	FDOT - CRACK SEALING - PCC	105.31	Ft	\$ 4.25	\$ 450.00
VQQ	AP N	4105	74	JOINT SPALL	Medium	9.18	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	59.2	SqFt	\$ 72.00	\$ 4,270.00
VQQ	AP N	4105	74	JOINT SPALL	High	9.18	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	74.27	SqFt	\$ 72.00	\$ 5,340.00
VQQ	AP N	4105	75	CORNER SPALL	Low	18.36	Slabs	2.0%	FDOT - CRACK SEALING - PCC	30.18	Ft	\$ 4.25	\$ 130.00
VQQ	AP N	4105	75	CORNER SPALL	Medium	9.18	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	24.76	SqFt	\$ 72.00	\$ 1,780.00
VQQ	AP N	4110	62	CORNER BREAK	Low	14.44	Slabs	1.9%	FDOT - CRACK SEALING - PCC	118.44	Ft	\$ 4.25	\$ 510.00
VQQ	AP N	4110	62	CORNER BREAK	Medium	9.63	Slabs	1.2%	FDOT - PATCHING - PCC FULL DEPTH	311.08	SqFt	\$ 185.00	\$ 57,520.00
VQQ	AP N	4110	63	LINEAR CR	Medium	4.81	Slabs	0.6%	FDOT - CRACK SEALING - PCC	96.13	Ft	\$ 4.25	\$ 410.00
VQQ	AP N	4110	65	JT SEAL DMG	Low	197.36	Slabs	25.5%	FDOT - JOINT SEAL - PCC	7717.85	Ft	\$ 2.75	\$ 21,230.00
VQQ	AP N	4110	65	JT SEAL DMG	Medium	481.37	Slabs	62.1%	FDOT - JOINT SEAL - PCC	18823.82	Ft	\$ 2.75	\$ 51,770.00
VQQ	AP N	4110	65	JT SEAL DMG	High	96.27	Slabs	12.4%	FDOT - JOINT SEAL - PCC	3764.76	Ft	\$ 2.75	\$ 10,360.00
VQQ	AP N	4110	66	SMALL PATCH	Medium	4.81	Slabs	0.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	12.92	SqFt	\$ 72.00	\$ 940.00
VQQ	AP N	4110	67	LARGE PATCH	Medium	14.44	Slabs	1.9%	FDOT - PATCHING - PCC FULL DEPTH	1065.63	SqFt	\$ 185.00	\$ 197,220.00
VQQ	AP N	4110	70	SCALING	Medium	14.44	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	888.02	SqFt	\$ 72.00	\$ 63,970.00
VQQ	AP N	4110	74	JOINT SPALL	Low	77.02	Slabs	9.9%	FDOT - CRACK SEALING - PCC	126.31	Ft	\$ 4.25	\$ 540.00
VQQ	AP N	4110	74	JOINT SPALL	Medium	38.51	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	248.65	SqFt	\$ 72.00	\$ 17,910.00
VQQ	AP N	4110	74	JOINT SPALL	High	43.32	Slabs	5.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	349.83	SqFt	\$ 72.00	\$ 25,190.00
VQQ	AP N	4110	75	CORNER SPALL	Low	24.07	Slabs	3.1%	FDOT - CRACK SEALING - PCC	39.37	Ft	\$ 4.25	\$ 170.00
VQQ	AP N	4110	75	CORNER SPALL	Medium	9.63	Slabs	1.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.83	SqFt	\$ 72.00	\$ 1,870.00
VQQ	AP N	4110	75	CORNER SPALL	High	14.44	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	38.75	SqFt	\$ 72.00	\$ 2,800.00
VQQ	AP N	4115	62	CORNER BREAK	Low	9.54	Slabs	0.7%	FDOT - CRACK SEALING - PCC	78.41	Ft	\$ 4.25	\$ 340.00
VQQ	AP N	4115	65	JT SEAL DMG	Low	381.71	Slabs	28.6%	FDOT - JOINT SEAL - PCC	10123.36	Ft	\$ 2.75	\$ 27,840.00
VQQ	AP N	4115	65	JT SEAL DMG	Medium	190.86	Slabs	14.3%	FDOT - JOINT SEAL - PCC	5061.68	Ft	\$ 2.75	\$ 13,920.00
VQQ	AP N	4115	66	SMALL PATCH	Medium	19.09	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	51.67	SqFt	\$ 72.00	\$ 3,700.00
VQQ	AP N	4115	74	JOINT SPALL	Low	38.17	Slabs	2.9%	FDOT - CRACK SEALING - PCC	62.66	Ft	\$ 4.25	\$ 270.00
VQQ	AP N	4115	75	CORNER SPALL	Low	28.63	Slabs	2.1%	FDOT - CRACK SEALING - PCC	46.92	Ft	\$ 4.25	\$ 200.00
VQQ	AP N	4115	75	CORNER SPALL	Medium	9.54	Slabs	0.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.83	SqFt	\$ 72.00	\$ 1,850.00
VQQ	AP N	4117	75	CORNER SPALL	Low	4.89	Slabs	5.6%	FDOT - CRACK SEALING - PCC	7.87	Ft	\$ 4.25	\$ 40.00
VQQ	AP N RFUEL	5125	65	JT SEAL DMG	Low	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2774.93	Ft	\$ 2.75	\$ 7,640.00
VQQ	AP N RFUEL	5125	66	SMALL PATCH	Medium	11.2	Slabs	10.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	30.14	SqFt	\$ 72.00	\$ 2,170.00
VQQ	AP N RFUEL	5125	74	JOINT SPALL	Low	16.8	Slabs	15.0%	FDOT - CRACK SEALING - PCC	27.56	Ft	\$ 4.25	\$ 120.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	AP N RFUEL	5125	74	JOINT SPALL	Medium	5.6	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	36.6	SqFt	\$ 72.00	\$ 2,610.00
VQQ	AP N RFUEL	5125	75	CORNER SPALL	Low	5.6	Slabs	5.0%	FDOT - CRACK SEALING - PCC	9.19	Ft	\$ 4.25	\$ 40.00
VQQ	AP N RFUEL	5130	65	JT SEAL DMG	Low	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2774.93	Ft	\$ 2.75	\$ 7,640.00
VQQ	AP N RFUEL	5130	66	SMALL PATCH	Medium	5.89	Slabs	5.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	16.15	SqFt	\$ 72.00	\$ 1,150.00
VQQ	AP N RFUEL	5130	74	JOINT SPALL	Low	5.89	Slabs	5.3%	FDOT - CRACK SEALING - PCC	9.51	Ft	\$ 4.25	\$ 50.00
VQQ	AP N RFUEL	5130	75	CORNER SPALL	Low	17.68	Slabs	15.8%	FDOT - CRACK SEALING - PCC	28.87	Ft	\$ 4.25	\$ 130.00
VQQ	AP N RFUEL	5135	65	JT SEAL DMG	Low	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2774.93	Ft	\$ 2.75	\$ 7,640.00
VQQ	AP N RFUEL	5135	66	SMALL PATCH	Medium	33.6	Slabs	30.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	90.42	SqFt	\$ 72.00	\$ 6,520.00
VQQ	AP N RFUEL	5135	74	JOINT SPALL	Low	22.4	Slabs	20.0%	FDOT - CRACK SEALING - PCC	36.75	Ft	\$ 4.25	\$ 160.00
VQQ	AP N RFUEL	5140	65	JT SEAL DMG	Medium	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2774.93	Ft	\$ 2.75	\$ 7,640.00
VQQ	AP N RFUEL	5140	66	SMALL PATCH	Medium	11.2	Slabs	10.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	30.14	SqFt	\$ 72.00	\$ 2,170.00
VQQ	AP N RFUEL	5140	74	JOINT SPALL	Low	5.6	Slabs	5.0%	FDOT - CRACK SEALING - PCC	9.19	Ft	\$ 4.25	\$ 40.00
VQQ	AP N RFUEL	5140	74	JOINT SPALL	Medium	22.4	Slabs	20.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	144.24	SqFt	\$ 72.00	\$ 10,420.00
VQQ	AP N RFUEL	5140	74	JOINT SPALL	High	22.4	Slabs	20.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	180.83	SqFt	\$ 72.00	\$ 13,030.00
VQQ	AP N RFUEL	5140	75	CORNER SPALL	Medium	5.6	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	15.07	SqFt	\$ 72.00	\$ 1,090.00
VQQ	AP NAT GRD	5305	65	JT SEAL DMG	Low	160	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2790.03	Ft	\$ 2.75	\$ 7,680.00
VQQ	AP NAT GRD	5305	74	JOINT SPALL	Low	13.06	Slabs	8.2%	FDOT - CRACK SEALING - PCC	21.33	Ft	\$ 4.25	\$ 100.00
VQQ	AP W	4205	63	LINEAR CR	Medium	18.72	Slabs	1.7%	FDOT - CRACK SEALING - PCC	233.92	Ft	\$ 4.25	\$ 1,000.00
VQQ	AP W	4205	65	JT SEAL DMG	Low	187.19	Slabs	16.7%	FDOT - JOINT SEAL - PCC	3453.41	Ft	\$ 2.75	\$ 9,500.00
VQQ	AP W	4205	66	SMALL PATCH	Medium	56.16	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	150.69	SqFt	\$ 72.00	\$ 10,890.00
VQQ	AP W	4205	74	JOINT SPALL	Low	112.32	Slabs	10.0%	FDOT - CRACK SEALING - PCC	184.38	Ft	\$ 4.25	\$ 790.00
VQQ	AP W	4205	74	JOINT SPALL	Medium	9.36	Slabs	0.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	60.28	SqFt	\$ 72.00	\$ 4,360.00
VQQ	AP W	4205	75	CORNER SPALL	Low	84.24	Slabs	7.5%	FDOT - CRACK SEALING - PCC	138.12	Ft	\$ 4.25	\$ 590.00
VQQ	AP W	4205	75	CORNER SPALL	Medium	9.36	Slabs	0.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	24.76	SqFt	\$ 72.00	\$ 1,820.00
VQQ	AP W	4210	65	JT SEAL DMG	Low	569.78	Slabs	44.4%	FDOT - JOINT SEAL - PCC	10237.86	Ft	\$ 2.75	\$ 28,160.00
VQQ	AP W	4210	66	SMALL PATCH	Medium	18.99	Slabs	1.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	50.59	SqFt	\$ 72.00	\$ 3,680.00
VQQ	AP W	4210	74	JOINT SPALL	Low	104.46	Slabs	8.2%	FDOT - CRACK SEALING - PCC	171.26	Ft	\$ 4.25	\$ 730.00
VQQ	AP W	4210	75	CORNER SPALL	Low	9.5	Slabs	0.7%	FDOT - CRACK SEALING - PCC	15.42	Ft	\$ 4.25	\$ 70.00
VQQ	AP W	4210	75	CORNER SPALL	Medium	9.5	Slabs	0.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.83	SqFt	\$ 72.00	\$ 1,840.00
VQQ	AP W	4210	75	CORNER SPALL	High	9.5	Slabs	0.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.83	SqFt	\$ 72.00	\$ 1,840.00
VQQ	AP W	4220	65	JT SEAL DMG	Low	1451	Slabs	100.0%	FDOT - JOINT SEAL - PCC	38820.54	Ft	\$ 2.75	\$ 106,760.00
VQQ	AP W	4220	66	SMALL PATCH	Medium	27.21	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	73.19	SqFt	\$ 72.00	\$ 5,280.00
VQQ	AP W	4220	74	JOINT SPALL	Low	108.82	Slabs	7.5%	FDOT - CRACK SEALING - PCC	178.48	Ft	\$ 4.25	\$ 760.00
VQQ	AP W	4220	74	JOINT SPALL	Medium	9.07	Slabs	0.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	58.13	SqFt	\$ 72.00	\$ 4,220.00
VQQ	AP W	4220	75	CORNER SPALL	Low	36.28	Slabs	2.5%	FDOT - CRACK SEALING - PCC	59.38	Ft	\$ 4.25	\$ 260.00
VQQ	AP W	4220	75	CORNER SPALL	Medium	9.07	Slabs	0.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	24.76	SqFt	\$ 72.00	\$ 1,760.00
VQQ	AP W	4225	63	LINEAR CR	Medium	16.8	Slabs	20.0%	FDOT - CRACK SEALING - PCC	335.96	Ft	\$ 4.25	\$ 1,430.00
VQQ	AP W	4225	65	JT SEAL DMG	Medium	84	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2935.04	Ft	\$ 2.75	\$ 8,080.00
VQQ	AP W	4225	66	SMALL PATCH	Medium	5.6	Slabs	6.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	15.07	SqFt	\$ 72.00	\$ 1,090.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	AP W	4225	67	LARGE PATCH	Medium	5.6	Slabs	6.7%	FDOT - PATCHING - PCC FULL DEPTH	551.11	SqFt	\$ 185.00	\$ 101,970.00
VQQ	AP W	4225	72	SHAT. SLAB	Low	11.2	Slabs	13.3%	FDOT - CRACK SEALING - PCC	448.16	Ft	\$ 4.25	\$ 1,910.00
VQQ	AP W	4225	72	SHAT. SLAB	Medium	28	Slabs	33.3%	FDOT - SLAB REPLACEMENT - PCC	11199.85	SqFt	\$ 30.00	\$ 336,000.00
VQQ	AP W	4230	63	LINEAR CR	Medium	6.5	Slabs	8.3%	FDOT - CRACK SEALING - PCC	129.92	Ft	\$ 4.25	\$ 560.00
VQQ	AP W	4230	65	JT SEAL DMG	Low	78	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2720.14	Ft	\$ 2.75	\$ 7,480.00
VQQ	AP W	4230	67	LARGE PATCH	Medium	6.5	Slabs	8.3%	FDOT - PATCHING - PCC FULL DEPTH	639.38	SqFt	\$ 185.00	\$ 118,360.00
VQQ	AP W	4230	72	SHAT. SLAB	Low	26	Slabs	33.3%	FDOT - CRACK SEALING - PCC	1040.03	Ft	\$ 4.25	\$ 4,430.00
VQQ	AP W	4230	72	SHAT. SLAB	Medium	39	Slabs	50.0%	FDOT - SLAB REPLACEMENT - PCC	15600.14	SqFt	\$ 30.00	\$ 468,000.00
VQQ	AP W	4235	65	JT SEAL DMG	Medium	11	Slabs	100.0%	FDOT - JOINT SEAL - PCC	290.03	Ft	\$ 2.75	\$ 800.00
VQQ	AP W	4235	72	SHAT. SLAB	Medium	11	Slabs	100.0%	FDOT - SLAB REPLACEMENT - PCC	13199.78	SqFt	\$ 30.00	\$ 396,000.00
VQQ	AP W	4240	66	SMALL PATCH	Medium	30.31	Slabs	4.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	81.81	SqFt	\$ 72.00	\$ 5,880.00
VQQ	AP W	4240	74	JOINT SPALL	Low	15.16	Slabs	2.2%	FDOT - CRACK SEALING - PCC	24.93	Ft	\$ 4.25	\$ 110.00
VQQ	AP W	4240	74	JOINT SPALL	Medium	7.58	Slabs	1.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	48.44	SqFt	\$ 72.00	\$ 3,530.00
VQQ	AP W	4240	75	CORNER SPALL	Low	15.16	Slabs	2.2%	FDOT - CRACK SEALING - PCC	24.93	Ft	\$ 4.25	\$ 110.00
VQQ	AP W	4240	75	CORNER SPALL	Medium	7.58	Slabs	1.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	20.45	SqFt	\$ 72.00	\$ 1,470.00
VQQ	AP W	4245	66	SMALL PATCH	Medium	17.15	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	46.28	SqFt	\$ 72.00	\$ 3,330.00
VQQ	AP W	4245	75	CORNER SPALL	Low	68.61	Slabs	5.6%	FDOT - CRACK SEALING - PCC	112.53	Ft	\$ 4.25	\$ 480.00
VQQ	AP W	4250	62	CORNER BREAK	Low	9.62	Slabs	0.6%	FDOT - CRACK SEALING - PCC	79.07	Ft	\$ 4.25	\$ 340.00
VQQ	AP W	4250	66	SMALL PATCH	Medium	9.62	Slabs	0.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.83	SqFt	\$ 72.00	\$ 1,870.00
VQQ	AP W	4250	67	LARGE PATCH	Medium	125.12	Slabs	8.1%	FDOT - PATCHING - PCC FULL DEPTH	9236.51	SqFt	\$ 185.00	\$ 1,708,770.00
VQQ	AP W	4250	74	JOINT SPALL	Low	96.25	Slabs	6.3%	FDOT - CRACK SEALING - PCC	157.81	Ft	\$ 4.25	\$ 680.00
VQQ	AP W	4250	74	JOINT SPALL	Medium	28.88	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	186.22	SqFt	\$ 72.00	\$ 13,430.00
VQQ	AP W	4250	75	CORNER SPALL	Low	9.62	Slabs	0.6%	FDOT - CRACK SEALING - PCC	15.75	Ft	\$ 4.25	\$ 70.00
VQQ	AP W	4250	75	CORNER SPALL	Medium	19.25	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	51.67	SqFt	\$ 72.00	\$ 3,730.00
VQQ	AP W	4255	63	LINEAR CR	Medium	15	Slabs	35.7%	FDOT - CRACK SEALING - PCC	228.67	Ft	\$ 4.25	\$ 980.00
VQQ	AP W	4255	65	JT SEAL DMG	Medium	42	Slabs	100.0%	FDOT - JOINT SEAL - PCC	917.65	Ft	\$ 2.75	\$ 2,530.00
VQQ	AP W	4255	66	SMALL PATCH	Medium	6	Slabs	14.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	16.15	SqFt	\$ 72.00	\$ 1,170.00
VQQ	AP W	4255	72	SHAT. SLAB	Medium	9	Slabs	21.4%	FDOT - SLAB REPLACEMENT - PCC	2078.51	SqFt	\$ 30.00	\$ 62,370.00
VQQ	AP W	4255	72	SHAT. SLAB	High	3	Slabs	7.1%	FDOT - SLAB REPLACEMENT - PCC	693.2	SqFt	\$ 30.00	\$ 20,790.00
VQQ	AP W	4255	74	JOINT SPALL	Low	3	Slabs	7.1%	FDOT - CRACK SEALING - PCC	4.92	Ft	\$ 4.25	\$ 30.00
VQQ	AP W	4255	75	CORNER SPALL	Low	3	Slabs	7.1%	FDOT - CRACK SEALING - PCC	4.92	Ft	\$ 4.25	\$ 30.00
VQQ	AP W	4260	74	JOINT SPALL	Low	17.05	Slabs	5.0%	FDOT - CRACK SEALING - PCC	27.89	Ft	\$ 4.25	\$ 120.00
VQQ	AP W	4260	74	JOINT SPALL	Medium	34.1	Slabs	10.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	220.66	SqFt	\$ 72.00	\$ 15,860.00
VQQ	AP W	4260	75	CORNER SPALL	Low	17.05	Slabs	5.0%	FDOT - CRACK SEALING - PCC	27.89	Ft	\$ 4.25	\$ 120.00
VQQ	AP W	4265	66	SMALL PATCH	Medium	20.37	Slabs	2.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	54.9	SqFt	\$ 72.00	\$ 3,950.00
VQQ	AP W	4265	74	JOINT SPALL	Low	20.37	Slabs	2.2%	FDOT - CRACK SEALING - PCC	33.46	Ft	\$ 4.25	\$ 150.00
VQQ	AP W	4265	75	CORNER SPALL	Medium	10.18	Slabs	1.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	26.91	SqFt	\$ 72.00	\$ 1,980.00
VQQ	AP W	4270	66	SMALL PATCH	Medium	22.92	Slabs	8.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	61.35	SqFt	\$ 72.00	\$ 4,450.00
VQQ	AP W	4270	66	SMALL PATCH	High	5.73	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	15.07	SqFt	\$ 72.00	\$ 1,120.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	AP W	4270	71	FAULTING	Medium	5.73	Slabs	2.1%	FDOT - GRINDING (LOCALIZED)	85.96	Ft	\$ 2.00	\$ 180.00
VQQ	AP W	4270	74	JOINT SPALL	Low	5.73	Slabs	2.1%	FDOT - CRACK SEALING - PCC	9.51	Ft	\$ 4.25	\$ 40.00
VQQ	AP W	4270	75	CORNER SPALL	Low	17.19	Slabs	6.3%	FDOT - CRACK SEALING - PCC	28.22	Ft	\$ 4.25	\$ 120.00
VQQ	AP W RFUEL	5005	65	JT SEAL DMG	Low	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2770.01	Ft	\$ 2.75	\$ 7,620.00
VQQ	AP W RFUEL	5005	74	JOINT SPALL	Low	4.87	Slabs	4.4%	FDOT - CRACK SEALING - PCC	7.87	Ft	\$ 4.25	\$ 40.00
VQQ	AP W RFUEL	5010	65	JT SEAL DMG	Low	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2770.01	Ft	\$ 2.75	\$ 7,620.00
VQQ	AP W RFUEL	5010	74	JOINT SPALL	Low	22.4	Slabs	20.0%	FDOT - CRACK SEALING - PCC	36.75	Ft	\$ 4.25	\$ 160.00
VQQ	AP W RFUEL	5010	75	CORNER SPALL	Low	5.6	Slabs	5.0%	FDOT - CRACK SEALING - PCC	9.19	Ft	\$ 4.25	\$ 40.00
VQQ	AP W RFUEL	5015	65	JT SEAL DMG	Low	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2770.01	Ft	\$ 2.75	\$ 7,620.00
VQQ	AP W RFUEL	5015	74	JOINT SPALL	Low	4.87	Slabs	4.4%	FDOT - CRACK SEALING - PCC	7.87	Ft	\$ 4.25	\$ 40.00
VQQ	AP W RFUEL	5020	62	CORNER BREAK	Low	5.6	Slabs	5.0%	FDOT - CRACK SEALING - PCC	45.93	Ft	\$ 4.25	\$ 200.00
VQQ	AP W RFUEL	5020	63	LINEAR CR	Medium	5.6	Slabs	5.0%	FDOT - CRACK SEALING - PCC	77.1	Ft	\$ 4.25	\$ 330.00
VQQ	AP W RFUEL	5020	65	JT SEAL DMG	Low	112	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2770.01	Ft	\$ 2.75	\$ 7,620.00
VQQ	AP W RFUEL	5020	66	SMALL PATCH	High	5.6	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	15.07	SqFt	\$ 72.00	\$ 1,090.00
VQQ	AP W RFUEL	5020	67	LARGE PATCH	Medium	22.4	Slabs	20.0%	FDOT - PATCHING - PCC FULL DEPTH	1653.34	SqFt	\$ 185.00	\$ 305,910.00
VQQ	AP W RFUEL	5020	74	JOINT SPALL	Low	16.8	Slabs	15.0%	FDOT - CRACK SEALING - PCC	27.56	Ft	\$ 4.25	\$ 120.00
VQQ	AP W RFUEL	5020	75	CORNER SPALL	Low	5.6	Slabs	5.0%	FDOT - CRACK SEALING - PCC	9.19	Ft	\$ 4.25	\$ 40.00
VQQ	AP W RFUEL	5020	75	CORNER SPALL	Medium	5.6	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	15.07	SqFt	\$ 72.00	\$ 1,090.00
VQQ	AP W RFUEL	5055	63	LINEAR CR	Medium	24.15	Slabs	35.0%	FDOT - CRACK SEALING - PCC	332.02	Ft	\$ 4.25	\$ 1,420.00
VQQ	AP W RFUEL	5055	65	JT SEAL DMG	Medium	69	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1529.86	Ft	\$ 2.75	\$ 4,210.00
VQQ	AP W RFUEL	5055	72	SHAT. SLAB	Low	3.45	Slabs	5.0%	FDOT - CRACK SEALING - PCC	94.82	Ft	\$ 4.25	\$ 410.00
VQQ	AP W RFUEL	5055	74	JOINT SPALL	Medium	3.45	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	22.6	SqFt	\$ 72.00	\$ 1,610.00
VQQ	AP W RFUEL	5055	75	CORNER SPALL	Low	10.35	Slabs	15.0%	FDOT - CRACK SEALING - PCC	17.06	Ft	\$ 4.25	\$ 80.00
VQQ	AP W RFUEL	5055	75	CORNER SPALL	Medium	6.9	Slabs	10.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	18.3	SqFt	\$ 72.00	\$ 1,340.00
VQQ	RW 18L-36R	6205	74	JOINT SPALL	Low	16.69	Slabs	6.3%	FDOT - CRACK SEALING - PCC	27.23	Ft	\$ 4.25	\$ 120.00
VQQ	RW 18L-36R	6205	75	CORNER SPALL	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.61	SqFt	\$ 72.00	\$ 650.00
VQQ	RW 18L-36R	6210	74	JOINT SPALL	Low	3.34	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.58	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18L-36R	6210	75	CORNER SPALL	Low	3.34	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.58	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18L-36R	6215	41	ALLIGATOR CR	Low	78.15	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	117.33	SqFt	\$ 12.50	\$ 1,480.00
VQQ	RW 18L-36R	6215	45	DEPRESSION	Low	96.98	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	141.01	SqFt	\$ 12.50	\$ 1,760.00
VQQ	RW 18L-36R	6217	48	L & T CR	Medium	90.65	Ft	0.2%	FDOT - CRACK SEALING - AC	90.55	Ft	\$ 3.00	\$ 280.00
VQQ	RW 18L-36R	6220	41	ALLIGATOR CR	Low	482.22	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	574.79	SqFt	\$ 12.50	\$ 7,190.00
VQQ	RW 18L-36R	6222	45	DEPRESSION	Low	214.2	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	276.63	SqFt	\$ 12.50	\$ 3,470.00
VQQ	RW 18L-36R	6222	48	L & T CR	Medium	411.98	Ft	0.7%	FDOT - CRACK SEALING - AC	412.07	Ft	\$ 3.00	\$ 1,240.00
VQQ	RW 18L-36R	6225	65	JT SEAL DMG	Low	267	Slabs	100.0%	FDOT - JOINT SEAL - PCC	6733.27	Ft	\$ 2.75	\$ 18,520.00
VQQ	RW 18L-36R	6225	66	SMALL PATCH	Medium	23.36	Slabs	8.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	62.43	SqFt	\$ 72.00	\$ 4,530.00
VQQ	RW 18L-36R	6225	74	JOINT SPALL	Low	13.35	Slabs	5.0%	FDOT - CRACK SEALING - PCC	21.98	Ft	\$ 4.25	\$ 100.00
VQQ	RW 18L-36R	6225	75	CORNER SPALL	Low	3.34	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.58	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18L-36R	6230	65	JT SEAL DMG	Low	66.75	Slabs	25.0%	FDOT - JOINT SEAL - PCC	1570.87	Ft	\$ 2.75	\$ 4,320.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	RW 18L-36R	6230	74	JOINT SPALL	Low	6.68	Slabs	2.5%	FDOT - CRACK SEALING - PCC	10.83	Ft	\$ 4.25	\$ 50.00
VQQ	RW 18L-36R	6230	75	CORNER SPALL	Low	3.34	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.58	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18L-36R	6235	62	CORNER BREAK	Low	12	Slabs	0.5%	FDOT - CRACK SEALING - PCC	98.43	Ft	\$ 4.25	\$ 420.00
VQQ	RW 18L-36R	6235	66	SMALL PATCH	Medium	6	Slabs	0.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	16.15	SqFt	\$ 72.00	\$ 1,170.00
VQQ	RW 18L-36R	6235	67	LARGE PATCH	Medium	6	Slabs	0.3%	FDOT - PATCHING - PCC FULL DEPTH	442.4	SqFt	\$ 185.00	\$ 81,940.00
VQQ	RW 18L-36R	6235	74	JOINT SPALL	Low	42	Slabs	1.8%	FDOT - CRACK SEALING - PCC	68.9	Ft	\$ 4.25	\$ 300.00
VQQ	RW 18L-36R	6235	75	CORNER SPALL	Low	6	Slabs	0.3%	FDOT - CRACK SEALING - PCC	9.84	Ft	\$ 4.25	\$ 50.00
VQQ	RW 18L-36R	6235	75	CORNER SPALL	Medium	6	Slabs	0.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	16.15	SqFt	\$ 72.00	\$ 1,170.00
VQQ	RW 18L-36R	6240	66	SMALL PATCH	Medium	12	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	32.29	SqFt	\$ 72.00	\$ 2,330.00
VQQ	RW 18L-36R	6240	74	JOINT SPALL	Low	24	Slabs	1.0%	FDOT - CRACK SEALING - PCC	39.37	Ft	\$ 4.25	\$ 170.00
VQQ	RW 18L-36R	6240	75	CORNER SPALL	Low	6	Slabs	0.3%	FDOT - CRACK SEALING - PCC	9.84	Ft	\$ 4.25	\$ 50.00
VQQ	RW 18R-36L	6105	66	SMALL PATCH	Medium	3.51	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	9.69	SqFt	\$ 72.00	\$ 690.00
VQQ	RW 18R-36L	6105	74	JOINT SPALL	Low	7.03	Slabs	2.6%	FDOT - CRACK SEALING - PCC	11.48	Ft	\$ 4.25	\$ 50.00
VQQ	RW 18R-36L	6105	74	JOINT SPALL	Medium	3.51	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	22.6	SqFt	\$ 72.00	\$ 1,640.00
VQQ	RW 18R-36L	6105	75	CORNER SPALL	Low	3.51	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.91	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18R-36L	6110	66	SMALL PATCH	Medium	20.02	Slabs	7.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	53.82	SqFt	\$ 72.00	\$ 3,880.00
VQQ	RW 18R-36L	6110	67	LARGE PATCH	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC FULL DEPTH	246.49	SqFt	\$ 185.00	\$ 45,580.00
VQQ	RW 18R-36L	6110	74	JOINT SPALL	Low	3.34	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.58	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18R-36L	6110	75	CORNER SPALL	Low	10.01	Slabs	3.8%	FDOT - CRACK SEALING - PCC	16.4	Ft	\$ 4.25	\$ 70.00
VQQ	RW 18R-36L	6115	41	ALLIGATOR CR	Low	6942.4	SqFt	1.3%	FDOT - PATCHING - AC FULL DEPTH	7281.79	SqFt	\$ 12.50	\$ 91,030.00
VQQ	RW 18R-36L	6115	43	BLOCK CR	Medium	67980.23	SqFt	12.5%	FDOT - CRACK SEALING - AC	20720.47	Ft	\$ 3.00	\$ 62,170.00
VQQ	RW 18R-36L	6115	45	DEPRESSION	Low	890.18	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	1013.96	SqFt	\$ 12.50	\$ 12,680.00
VQQ	RW 18R-36L	6115	45	DEPRESSION	Medium	271.36	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	341.22	SqFt	\$ 12.50	\$ 4,280.00
VQQ	RW 18R-36L	6115	50	PATCHING	Medium	5970.85	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	6286.12	SqFt	\$ 12.50	\$ 78,580.00
VQQ	RW 18R-36L	6115	52	Raveling	Low	417076.66	SqFt	76.8%	FDOT - SURFACE SEAL	417076.8	SqFt	\$ 0.55	\$ 229,400.00
VQQ	RW 18R-36L	6115	52	Raveling	Medium	107121.58	SqFt	19.7%	FDOT - PATCHING - AC PARTIAL DEPTH	107121.4	SqFt	\$ 5.50	\$ 589,170.00
VQQ	RW 18R-36L	6115	55	SLIPPAGE CR	N/A	678.45	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	786.84	SqFt	\$ 5.50	\$ 4,340.00
VQQ	RW 18R-36L	6120	43	BLOCK CR	Medium	57314.27	SqFt	10.6%	FDOT - CRACK SEALING - AC	17469.49	Ft	\$ 3.00	\$ 52,410.00
VQQ	RW 18R-36L	6120	45	DEPRESSION	Low	1997.46	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	2181.84	SqFt	\$ 12.50	\$ 27,270.00
VQQ	RW 18R-36L	6120	48	L & T CR	Medium	4787.5	Ft	0.9%	FDOT - CRACK SEALING - AC	4787.4	Ft	\$ 3.00	\$ 14,370.00
VQQ	RW 18R-36L	6120	50	PATCHING	Medium	1899.83	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	2079.59	SqFt	\$ 12.50	\$ 26,000.00
VQQ	RW 18R-36L	6120	52	Raveling	Low	420789.46	SqFt	77.5%	FDOT - SURFACE SEAL	420789.2	SqFt	\$ 0.55	\$ 231,440.00
VQQ	RW 18R-36L	6120	52	Raveling	Medium	108255.98	SqFt	19.9%	FDOT - PATCHING - AC PARTIAL DEPTH	108255.9	SqFt	\$ 5.50	\$ 595,410.00
VQQ	RW 18R-36L	6125	65	JT SEAL DMG	High	160	Slabs	100.0%	FDOT - JOINT SEAL - PCC	4000	Ft	\$ 2.75	\$ 11,000.00
VQQ	RW 18R-36L	6125	66	SMALL PATCH	Medium	2.67	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	7.53	SqFt	\$ 72.00	\$ 520.00
VQQ	RW 18R-36L	6125	74	JOINT SPALL	Low	18.67	Slabs	11.7%	FDOT - CRACK SEALING - PCC	30.51	Ft	\$ 4.25	\$ 140.00
VQQ	RW 18R-36L	6125	75	CORNER SPALL	Low	8	Slabs	5.0%	FDOT - CRACK SEALING - PCC	13.12	Ft	\$ 4.25	\$ 60.00
VQQ	RW 18R-36L	6130	65	JT SEAL DMG	Medium	53.33	Slabs	33.3%	FDOT - JOINT SEAL - PCC	1250	Ft	\$ 2.75	\$ 3,440.00
VQQ	RW 18R-36L	6130	65	JT SEAL DMG	High	106.67	Slabs	66.7%	FDOT - JOINT SEAL - PCC	2500	Ft	\$ 2.75	\$ 6,880.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	RW 18R-36L	6130	75	CORNER SPALL	Low	5.33	Slabs	3.3%	FDOT - CRACK SEALING - PCC	8.86	Ft	\$ 4.25	\$ 40.00
VQQ	RW 18R-36L	6135	65	JT SEAL DMG	Low	106.8	Slabs	40.0%	FDOT - JOINT SEAL - PCC	2693.24	Ft	\$ 2.75	\$ 7,410.00
VQQ	RW 18R-36L	6135	66	SMALL PATCH	Medium	16.02	Slabs	6.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	43.06	SqFt	\$ 72.00	\$ 3,110.00
VQQ	RW 18R-36L	6135	66	SMALL PATCH	High	10.68	Slabs	4.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	29.06	SqFt	\$ 72.00	\$ 2,070.00
VQQ	RW 18R-36L	6135	67	LARGE PATCH	High	2.67	Slabs	1.0%	FDOT - PATCHING - PCC FULL DEPTH	196.98	SqFt	\$ 185.00	\$ 36,470.00
VQQ	RW 18R-36L	6135	74	JOINT SPALL	Low	2.67	Slabs	1.0%	FDOT - CRACK SEALING - PCC	4.27	Ft	\$ 4.25	\$ 20.00
VQQ	RW 18R-36L	6135	75	CORNER SPALL	Medium	2.67	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	7.53	SqFt	\$ 72.00	\$ 520.00
VQQ	RW 18R-36L	6140	65	JT SEAL DMG	Low	70.26	Slabs	26.3%	FDOT - JOINT SEAL - PCC	1653.54	Ft	\$ 2.75	\$ 4,550.00
VQQ	RW 18R-36L	6140	66	SMALL PATCH	Medium	7.03	Slabs	2.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	19.38	SqFt	\$ 72.00	\$ 1,370.00
VQQ	RW 18R-36L	6140	74	JOINT SPALL	Low	3.51	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.91	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18R-36L	6140	74	JOINT SPALL	Medium	3.51	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	22.6	SqFt	\$ 72.00	\$ 1,640.00
VQQ	RW 18R-36L	6140	75	CORNER SPALL	Low	3.51	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.91	Ft	\$ 4.25	\$ 30.00
VQQ	RW 18R-36L	6140	75	CORNER SPALL	Medium	3.51	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	9.69	SqFt	\$ 72.00	\$ 690.00
VQQ	RW 9L-27R	6405	66	SMALL PATCH	Medium	6.68	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	18.3	SqFt	\$ 72.00	\$ 1,300.00
VQQ	RW 9L-27R	6405	70	SCALING	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	205.59	SqFt	\$ 72.00	\$ 14,790.00
VQQ	RW 9L-27R	6410	65	JT SEAL DMG	Low	66.75	Slabs	25.0%	FDOT - JOINT SEAL - PCC	1570.87	Ft	\$ 2.75	\$ 4,320.00
VQQ	RW 9L-27R	6410	65	JT SEAL DMG	Medium	66.75	Slabs	25.0%	FDOT - JOINT SEAL - PCC	1570.87	Ft	\$ 2.75	\$ 4,320.00
VQQ	RW 9L-27R	6410	66	SMALL PATCH	Medium	6.68	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	18.3	SqFt	\$ 72.00	\$ 1,300.00
VQQ	RW 9L-27R	6410	74	JOINT SPALL	Low	6.68	Slabs	2.5%	FDOT - CRACK SEALING - PCC	10.83	Ft	\$ 4.25	\$ 50.00
VQQ	RW 9L-27R	6410	75	CORNER SPALL	Low	10.01	Slabs	3.8%	FDOT - CRACK SEALING - PCC	16.4	Ft	\$ 4.25	\$ 70.00
VQQ	RW 9L-27R	6414	41	ALLIGATOR CR	Low	885.12	SqFt	1.6%	FDOT - PATCHING - AC FULL DEPTH	1008.58	SqFt	\$ 12.50	\$ 12,620.00
VQQ	RW 9L-27R	6414	48	L & T CR	Medium	632.81	Ft	1.1%	FDOT - CRACK SEALING - AC	632.87	Ft	\$ 3.00	\$ 1,900.00
VQQ	RW 9L-27R	6414	52	RAVELING	Low	783.51	SqFt	1.4%	FDOT - SURFACE SEAL	783.61	SqFt	\$ 0.55	\$ 440.00
VQQ	RW 9L-27R	6415	41	ALLIGATOR CR	Low	3728.94	SqFt	1.3%	FDOT - PATCHING - AC FULL DEPTH	3978.34	SqFt	\$ 12.50	\$ 49,740.00
VQQ	RW 9L-27R	6415	43	BLOCK CR	Medium	42516.91	SqFt	15.0%	FDOT - CRACK SEALING - AC	12958.99	Ft	\$ 3.00	\$ 38,880.00
VQQ	RW 9L-27R	6415	45	DEPRESSION	Low	250.48	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	318.61	SqFt	\$ 12.50	\$ 3,980.00
VQQ	RW 9L-27R	6415	48	L & T CR	Medium	453.71	Ft	0.2%	FDOT - CRACK SEALING - AC	453.74	Ft	\$ 3.00	\$ 1,370.00
VQQ	RW 9L-27R	6415	50	PATCHING	Medium	14244.74	SqFt	5.0%	FDOT - PATCHING - AC FULL DEPTH	14729.34	SqFt	\$ 12.50	\$ 184,120.00
VQQ	RW 9L-27R	6415	52	RAVELING	Low	212759.13	SqFt	75.0%	FDOT - SURFACE SEAL	212759.5	SqFt	\$ 0.55	\$ 117,020.00
VQQ	RW 9L-27R	6415	52	RAVELING	Medium	47148.51	SqFt	16.6%	FDOT - PATCHING - AC PARTIAL DEPTH	47148.08	SqFt	\$ 5.50	\$ 259,320.00
VQQ	RW 9L-27R	6415	52	RAVELING	High	784.58	SqFt	0.3%	FDOT - PATCHING - AC PARTIAL DEPTH	784.69	SqFt	\$ 5.50	\$ 4,320.00
VQQ	RW 9L-27R	6415	53	RUTTING	Medium	283.52	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	283.09	SqFt	\$ 12.50	\$ 3,550.00
VQQ	RW 9L-27R	6417	48	L & T CR	Medium	74.31	Ft	0.3%	FDOT - CRACK SEALING - AC	74.15	Ft	\$ 3.00	\$ 230.00
VQQ	RW 9L-27R	6417	52	RAVELING	Low	154.79	SqFt	0.6%	FDOT - SURFACE SEAL	155	SqFt	\$ 0.55	\$ 90.00
VQQ	RW 9L-27R	6420	43	BLOCK CR	Medium	50480.05	SqFt	16.2%	FDOT - CRACK SEALING - AC	15386.48	Ft	\$ 3.00	\$ 46,160.00
VQQ	RW 9L-27R	6420	45	DEPRESSION	Low	386.96	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	470.38	SqFt	\$ 12.50	\$ 5,880.00
VQQ	RW 9L-27R	6420	45	DEPRESSION	Medium	55.97	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	90.42	SqFt	\$ 12.50	\$ 1,130.00
VQQ	RW 9L-27R	6420	48	L & T CR	Medium	3496.49	Ft	1.1%	FDOT - CRACK SEALING - AC	3496.39	Ft	\$ 3.00	\$ 10,490.00
VQQ	RW 9L-27R	6420	50	PATCHING	Medium	32.61	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	59.2	SqFt	\$ 12.50	\$ 750.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	RW 9L-27R	6420	52	RAVELING	Low	246348.99	SqFt	79.0%	FDOT - SURFACE SEAL	246349.3	SqFt	\$ 0.55	\$ 135,500.00
VQQ	RW 9L-27R	6420	52	RAVELING	Medium	65100.02	SqFt	20.9%	FDOT - PATCHING - AC PARTIAL DEPTH	65100.13	SqFt	\$ 5.50	\$ 358,060.00
VQQ	RW 9L-27R	6420	52	RAVELING	High	135.19	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	135.63	SqFt	\$ 5.50	\$ 750.00
VQQ	RW 9L-27R	6440	52	RAVELING	Low	609.99	SqFt	3.1%	FDOT - SURFACE SEAL	610.31	SqFt	\$ 0.55	\$ 340.00
VQQ	RW 9R-27L	6305	66	SMALL PATCH	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.61	SqFt	\$ 72.00	\$ 650.00
VQQ	RW 9R-27L	6305	74	JOINT SPALL	Low	26.7	Slabs	10.0%	FDOT - CRACK SEALING - PCC	43.96	Ft	\$ 4.25	\$ 190.00
VQQ	RW 9R-27L	6305	75	CORNER SPALL	Low	3.34	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.58	Ft	\$ 4.25	\$ 30.00
VQQ	RW 9R-27L	6305	75	CORNER SPALL	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.61	SqFt	\$ 72.00	\$ 650.00
VQQ	RW 9R-27L	6310	66	SMALL PATCH	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.61	SqFt	\$ 72.00	\$ 650.00
VQQ	RW 9R-27L	6310	74	JOINT SPALL	Low	10.01	Slabs	3.8%	FDOT - CRACK SEALING - PCC	16.4	Ft	\$ 4.25	\$ 70.00
VQQ	RW 9R-27L	6310	75	CORNER SPALL	Low	6.68	Slabs	2.5%	FDOT - CRACK SEALING - PCC	10.83	Ft	\$ 4.25	\$ 50.00
VQQ	RW 9R-27L	6315	45	DEPRESSION	Low	18.08	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	38.75	SqFt	\$ 12.50	\$ 500.00
VQQ	RW 9R-27L	6315	52	RAVELING	Low	1206.63	SqFt	0.2%	FDOT - SURFACE SEAL	1206.63	SqFt	\$ 0.55	\$ 670.00
VQQ	RW 9R-27L	6320	45	DEPRESSION	Low	150.8	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	204.51	SqFt	\$ 12.50	\$ 2,560.00
VQQ	RW 9R-27L	6320	52	RAVELING	Low	6.03	SqFt	0.0%	FDOT - SURFACE SEAL	6.46	SqFt	\$ 0.55	\$ 10.00
VQQ	RW 9R-27L	6322	45	DEPRESSION	Low	899.97	SqFt	4.6%	FDOT - PATCHING - AC FULL DEPTH	1024.72	SqFt	\$ 12.50	\$ 12,810.00
VQQ	RW 9R-27L	6325	74	JOINT SPALL	Low	30.4	Slabs	10.0%	FDOT - CRACK SEALING - PCC	49.87	Ft	\$ 4.25	\$ 220.00
VQQ	RW 9R-27L	6330	74	JOINT SPALL	Low	18.24	Slabs	6.0%	FDOT - CRACK SEALING - PCC	29.86	Ft	\$ 4.25	\$ 130.00
VQQ	RW 9R-27L	6330	75	CORNER SPALL	Low	18.24	Slabs	6.0%	FDOT - CRACK SEALING - PCC	29.86	Ft	\$ 4.25	\$ 130.00
VQQ	RW 9R-27L	6335	66	SMALL PATCH	Medium	16.69	Slabs	6.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	45.21	SqFt	\$ 72.00	\$ 3,240.00
VQQ	RW 9R-27L	6335	67	LARGE PATCH	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC FULL DEPTH	246.49	SqFt	\$ 185.00	\$ 45,580.00
VQQ	RW 9R-27L	6335	74	JOINT SPALL	Low	6.68	Slabs	2.5%	FDOT - CRACK SEALING - PCC	10.83	Ft	\$ 4.25	\$ 50.00
VQQ	RW 9R-27L	6335	74	JOINT SPALL	Medium	6.68	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	43.06	SqFt	\$ 72.00	\$ 3,110.00
VQQ	RW 9R-27L	6335	75	CORNER SPALL	Low	3.34	Slabs	1.3%	FDOT - CRACK SEALING - PCC	5.58	Ft	\$ 4.25	\$ 30.00
VQQ	RW 9R-27L	6340	65	JT SEAL DMG	Low	133.5	Slabs	50.0%	FDOT - JOINT SEAL - PCC	3141.73	Ft	\$ 2.75	\$ 8,640.00
VQQ	RW 9R-27L	6340	66	SMALL PATCH	Medium	16.69	Slabs	6.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	45.21	SqFt	\$ 72.00	\$ 3,240.00
VQQ	RW 9R-27L	6340	74	JOINT SPALL	Low	30.04	Slabs	11.3%	FDOT - CRACK SEALING - PCC	49.21	Ft	\$ 4.25	\$ 210.00
VQQ	RW 9R-27L	6340	74	JOINT SPALL	Medium	3.34	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	21.53	SqFt	\$ 72.00	\$ 1,560.00
VQQ	RW 9R-27L	6340	75	CORNER SPALL	Low	20.02	Slabs	7.5%	FDOT - CRACK SEALING - PCC	32.81	Ft	\$ 4.25	\$ 140.00
VQQ	TW A	105	66	SMALL PATCH	Medium	5.15	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	13.99	SqFt	\$ 72.00	\$ 1,000.00
VQQ	TW A	105	66	SMALL PATCH	High	5.15	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	13.99	SqFt	\$ 72.00	\$ 1,000.00
VQQ	TW A	105	74	JOINT SPALL	Low	25.76	Slabs	6.9%	FDOT - CRACK SEALING - PCC	42.32	Ft	\$ 4.25	\$ 180.00
VQQ	TW A	105	74	JOINT SPALL	Medium	5.15	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	33.37	SqFt	\$ 72.00	\$ 2,400.00
VQQ	TW A	105	74	JOINT SPALL	High	20.61	Slabs	5.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	166.84	SqFt	\$ 72.00	\$ 11,990.00
VQQ	TW A	105	75	CORNER SPALL	Low	5.15	Slabs	1.4%	FDOT - CRACK SEALING - PCC	8.53	Ft	\$ 4.25	\$ 40.00
VQQ	TW A	105	75	CORNER SPALL	Medium	5.15	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	13.99	SqFt	\$ 72.00	\$ 1,000.00
VQQ	TW A	110	67	LARGE PATCH	Medium	10	Slabs	0.7%	FDOT - PATCHING - PCC FULL DEPTH	738.4	SqFt	\$ 185.00	\$ 136,570.00
VQQ	TW A	110	74	JOINT SPALL	Low	110	Slabs	7.6%	FDOT - CRACK SEALING - PCC	180.45	Ft	\$ 4.25	\$ 770.00
VQQ	TW A	110	75	CORNER SPALL	Low	50	Slabs	3.5%	FDOT - CRACK SEALING - PCC	82.02	Ft	\$ 4.25	\$ 350.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	TW A	110	75	CORNER SPALL	Medium	50	Slabs	3.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	134.55	SqFt	\$ 72.00	\$ 9,690.00
VQQ	TW A	110	75	CORNER SPALL	High	10	Slabs	0.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	26.91	SqFt	\$ 72.00	\$ 1,940.00
VQQ	TW A	115	74	JOINT SPALL	Low	5.83	Slabs	2.1%	FDOT - CRACK SEALING - PCC	9.51	Ft	\$ 4.25	\$ 50.00
VQQ	TW A	117	45	DEPRESSION	Low	590.83	SqFt	2.2%	FDOT - PATCHING - AC FULL DEPTH	692.12	SqFt	\$ 12.50	\$ 8,660.00
VQQ	TW A	125	52	Raveling	Low	776.19	SqFt	4.0%	FDOT - SURFACE SEAL	776.08	SqFt	\$ 0.55	\$ 430.00
VQQ	TW A	130	66	SMALL PATCH	Medium	50.79	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	136.7	SqFt	\$ 72.00	\$ 9,850.00
VQQ	TW A	130	74	JOINT SPALL	Low	30.48	Slabs	1.3%	FDOT - CRACK SEALING - PCC	49.87	Ft	\$ 4.25	\$ 220.00
VQQ	TW A	130	74	JOINT SPALL	Medium	20.32	Slabs	0.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	131.32	SqFt	\$ 72.00	\$ 9,450.00
VQQ	TW A	130	75	CORNER SPALL	Medium	30.48	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	81.81	SqFt	\$ 72.00	\$ 5,910.00
VQQ	TW A1	505	66	SMALL PATCH	Medium	13.77	Slabs	3.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	36.6	SqFt	\$ 72.00	\$ 2,670.00
VQQ	TW A1	510	75	CORNER SPALL	Low	5.2	Slabs	1.7%	FDOT - CRACK SEALING - PCC	8.53	Ft	\$ 4.25	\$ 40.00
VQQ	TW A1	515	65	JT SEAL DMG	Low	247.33	Slabs	66.7%	FDOT - JOINT SEAL - PCC	5886.81	Ft	\$ 2.75	\$ 16,190.00
VQQ	TW A1	515	74	JOINT SPALL	Low	6.18	Slabs	1.7%	FDOT - CRACK SEALING - PCC	10.17	Ft	\$ 4.25	\$ 50.00
VQQ	TW A1	515	75	CORNER SPALL	Low	12.37	Slabs	3.3%	FDOT - CRACK SEALING - PCC	20.34	Ft	\$ 4.25	\$ 90.00
VQQ	TW A1	515	75	CORNER SPALL	Medium	30.92	Slabs	8.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	82.88	SqFt	\$ 72.00	\$ 6,000.00
VQQ	TW A2	620	62	CORNER BREAK	Low	2.69	Slabs	2.1%	FDOT - CRACK SEALING - PCC	21.98	Ft	\$ 4.25	\$ 100.00
VQQ	TW A2	620	62	CORNER BREAK	Medium	2.69	Slabs	2.1%	FDOT - PATCHING - PCC FULL DEPTH	87.19	SqFt	\$ 185.00	\$ 16,060.00
VQQ	TW A2	620	65	JT SEAL DMG	Low	129	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2024.93	Ft	\$ 2.75	\$ 5,570.00
VQQ	TW A2	620	66	SMALL PATCH	Medium	2.69	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	7.53	SqFt	\$ 72.00	\$ 530.00
VQQ	TW A2	620	75	CORNER SPALL	Low	5.38	Slabs	4.2%	FDOT - CRACK SEALING - PCC	8.86	Ft	\$ 4.25	\$ 40.00
VQQ	TW A2	620	75	CORNER SPALL	Medium	2.69	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	7.53	SqFt	\$ 72.00	\$ 530.00
VQQ	TW A3	715	74	JOINT SPALL	Low	2.6	Slabs	2.1%	FDOT - CRACK SEALING - PCC	4.27	Ft	\$ 4.25	\$ 20.00
VQQ	TW A3	715	75	CORNER SPALL	Low	2.6	Slabs	2.1%	FDOT - CRACK SEALING - PCC	4.27	Ft	\$ 4.25	\$ 20.00
VQQ	TW A3	720	66	SMALL PATCH	Medium	2.65	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	7.53	SqFt	\$ 72.00	\$ 520.00
VQQ	TW A3	720	66	SMALL PATCH	High	5.29	Slabs	4.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	13.99	SqFt	\$ 72.00	\$ 1,030.00
VQQ	TW A3	720	74	JOINT SPALL	Low	2.65	Slabs	2.1%	FDOT - CRACK SEALING - PCC	4.27	Ft	\$ 4.25	\$ 20.00
VQQ	TW A3	720	74	JOINT SPALL	High	2.65	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	21.53	SqFt	\$ 72.00	\$ 1,540.00
VQQ	TW A3	720	75	CORNER SPALL	Low	2.65	Slabs	2.1%	FDOT - CRACK SEALING - PCC	4.27	Ft	\$ 4.25	\$ 20.00
VQQ	TW A4	805	66	SMALL PATCH	Medium	5.07	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	13.99	SqFt	\$ 72.00	\$ 990.00
VQQ	TW A4	810	65	JT SEAL DMG	Low	140.67	Slabs	33.3%	FDOT - JOINT SEAL - PCC	3450.13	Ft	\$ 2.75	\$ 9,490.00
VQQ	TW A4	810	74	JOINT SPALL	Low	7.03	Slabs	1.7%	FDOT - CRACK SEALING - PCC	11.48	Ft	\$ 4.25	\$ 50.00
VQQ	TW A4	810	75	CORNER SPALL	Low	7.03	Slabs	1.7%	FDOT - CRACK SEALING - PCC	11.48	Ft	\$ 4.25	\$ 50.00
VQQ	TW A5	1005	62	CORNER BREAK	Low	26.67	Slabs	3.0%	FDOT - CRACK SEALING - PCC	218.83	Ft	\$ 4.25	\$ 930.00
VQQ	TW A5	1005	67	LARGE PATCH	Medium	17.78	Slabs	2.0%	FDOT - PATCHING - PCC FULL DEPTH	1312.12	SqFt	\$ 185.00	\$ 242,820.00
VQQ	TW A5	1005	74	JOINT SPALL	Low	53.34	Slabs	6.0%	FDOT - CRACK SEALING - PCC	87.6	Ft	\$ 4.25	\$ 380.00
VQQ	TW A5	1005	74	JOINT SPALL	Medium	8.89	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	57.05	SqFt	\$ 72.00	\$ 4,140.00
VQQ	TW A5	1005	75	CORNER SPALL	Medium	8.89	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	23.68	SqFt	\$ 72.00	\$ 1,730.00
VQQ	TW B	205	65	JT SEAL DMG	Low	624	Slabs	33.3%	FDOT - JOINT SEAL - PCC	15575.13	Ft	\$ 2.75	\$ 42,840.00
VQQ	TW B	205	66	SMALL PATCH	Medium	8.67	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	23.68	SqFt	\$ 72.00	\$ 1,680.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	TW B	205	74	JOINT SPALL	Low	26	Slabs	1.4%	FDOT - CRACK SEALING - PCC	42.65	Ft	\$ 4.25	\$ 190.00
VQQ	TW B	205	74	JOINT SPALL	Medium	8.67	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	55.97	SqFt	\$ 72.00	\$ 4,040.00
VQQ	TW B	205	74	JOINT SPALL	High	8.67	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	69.97	SqFt	\$ 72.00	\$ 5,040.00
VQQ	TW B	205	75	CORNER SPALL	Low	8.67	Slabs	0.5%	FDOT - CRACK SEALING - PCC	14.11	Ft	\$ 4.25	\$ 70.00
VQQ	TW B	215	65	JT SEAL DMG	Low	880	Slabs	100.0%	FDOT - JOINT SEAL - PCC	21924.87	Ft	\$ 2.75	\$ 60,300.00
VQQ	TW B	215	74	JOINT SPALL	Low	18.33	Slabs	2.1%	FDOT - CRACK SEALING - PCC	30.18	Ft	\$ 4.25	\$ 130.00
VQQ	TW B	215	75	CORNER SPALL	Low	27.5	Slabs	3.1%	FDOT - CRACK SEALING - PCC	45.28	Ft	\$ 4.25	\$ 200.00
VQQ	TW B1	1105	65	JT SEAL DMG	Low	301	Slabs	100.0%	FDOT - JOINT SEAL - PCC	7620.08	Ft	\$ 2.75	\$ 20,960.00
VQQ	TW B1	1105	66	SMALL PATCH	Medium	15.05	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	40.9	SqFt	\$ 72.00	\$ 2,920.00
VQQ	TW B1	1105	74	JOINT SPALL	Low	5.02	Slabs	1.7%	FDOT - CRACK SEALING - PCC	8.2	Ft	\$ 4.25	\$ 40.00
VQQ	TW B1	1105	75	CORNER SPALL	Low	5.02	Slabs	1.7%	FDOT - CRACK SEALING - PCC	8.2	Ft	\$ 4.25	\$ 40.00
VQQ	TW B1	1110	65	JT SEAL DMG	Low	413	Slabs	100.0%	FDOT - JOINT SEAL - PCC	10350.07	Ft	\$ 2.75	\$ 28,470.00
VQQ	TW B1	1110	66	SMALL PATCH	Medium	27.53	Slabs	6.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	74.27	SqFt	\$ 72.00	\$ 5,340.00
VQQ	TW B1	1110	74	JOINT SPALL	Low	13.77	Slabs	3.3%	FDOT - CRACK SEALING - PCC	22.64	Ft	\$ 4.25	\$ 100.00
VQQ	TW B1	1110	74	JOINT SPALL	Medium	6.88	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	44.13	SqFt	\$ 72.00	\$ 3,210.00
VQQ	TW B1	1110	75	CORNER SPALL	Low	13.77	Slabs	3.3%	FDOT - CRACK SEALING - PCC	22.64	Ft	\$ 4.25	\$ 100.00
VQQ	TW B1	1110	75	CORNER SPALL	Medium	6.88	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	18.3	SqFt	\$ 72.00	\$ 1,340.00
VQQ	TW B1	1115	65	JT SEAL DMG	Low	88.89	Slabs	55.6%	FDOT - JOINT SEAL - PCC	2250	Ft	\$ 2.75	\$ 6,190.00
VQQ	TW B1	1115	66	SMALL PATCH	Medium	13.33	Slabs	8.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	35.52	SqFt	\$ 72.00	\$ 2,590.00
VQQ	TW B1	1115	74	JOINT SPALL	Medium	8.89	Slabs	5.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	57.05	SqFt	\$ 72.00	\$ 4,140.00
VQQ	TW B2	1203	45	DEPRESSION	Low	31.43	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	58.13	SqFt	\$ 12.50	\$ 730.00
VQQ	TW B2	1210	62	CORNER BREAK	Low	4.96	Slabs	4.2%	FDOT - CRACK SEALING - PCC	40.68	Ft	\$ 4.25	\$ 180.00
VQQ	TW B2	1210	75	CORNER SPALL	Low	4.96	Slabs	4.2%	FDOT - CRACK SEALING - PCC	8.2	Ft	\$ 4.25	\$ 40.00
VQQ	TW B2	1215	62	CORNER BREAK	Low	2.75	Slabs	2.1%	FDOT - CRACK SEALING - PCC	22.64	Ft	\$ 4.25	\$ 100.00
VQQ	TW B2	1215	65	JT SEAL DMG	Low	66	Slabs	50.0%	FDOT - JOINT SEAL - PCC	1037.4	Ft	\$ 2.75	\$ 2,860.00
VQQ	TW B2	1215	66	SMALL PATCH	Medium	5.5	Slabs	4.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	15.07	SqFt	\$ 72.00	\$ 1,070.00
VQQ	TW B2	1215	66	SMALL PATCH	High	2.75	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	7.53	SqFt	\$ 72.00	\$ 540.00
VQQ	TW B2	1215	74	JOINT SPALL	Low	2.75	Slabs	2.1%	FDOT - CRACK SEALING - PCC	4.59	Ft	\$ 4.25	\$ 20.00
VQQ	TW B3	1405	65	JT SEAL DMG	Low	106.33	Slabs	33.3%	FDOT - JOINT SEAL - PCC	2540.03	Ft	\$ 2.75	\$ 6,990.00
VQQ	TW B3	1405	67	LARGE PATCH	Medium	15.95	Slabs	5.0%	FDOT - PATCHING - PCC FULL DEPTH	1177.57	SqFt	\$ 185.00	\$ 217,830.00
VQQ	TW B3	1410	66	SMALL PATCH	Medium	6.85	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	18.3	SqFt	\$ 72.00	\$ 1,330.00
VQQ	TW B3	1410	75	CORNER SPALL	High	6.85	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	18.3	SqFt	\$ 72.00	\$ 1,330.00
VQQ	TW C	305	65	JT SEAL DMG	Low	997	Slabs	100.0%	FDOT - JOINT SEAL - PCC	23924.87	Ft	\$ 2.75	\$ 65,800.00
VQQ	TW C	305	66	SMALL PATCH	Medium	24.92	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	66.74	SqFt	\$ 72.00	\$ 4,830.00
VQQ	TW C	305	74	JOINT SPALL	Low	33.23	Slabs	3.3%	FDOT - CRACK SEALING - PCC	54.46	Ft	\$ 4.25	\$ 240.00
VQQ	TW C	305	75	CORNER SPALL	Low	8.31	Slabs	0.8%	FDOT - CRACK SEALING - PCC	13.78	Ft	\$ 4.25	\$ 60.00
VQQ	TW C	310	65	JT SEAL DMG	Low	909	Slabs	100.0%	FDOT - JOINT SEAL - PCC	20886.81	Ft	\$ 2.75	\$ 57,440.00
VQQ	TW C	310	66	SMALL PATCH	Medium	7.57	Slabs	0.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	20.45	SqFt	\$ 72.00	\$ 1,470.00
VQQ	TW C	310	74	JOINT SPALL	Low	68.18	Slabs	7.5%	FDOT - CRACK SEALING - PCC	111.88	Ft	\$ 4.25	\$ 480.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
VQQ	TW C	310	75	CORNER SPALL	Low	37.88	Slabs	4.2%	FDOT - CRACK SEALING - PCC	62.01	Ft	\$ 4.25	\$ 270.00
VQQ	TW C	310	75	CORNER SPALL	Medium	15.15	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	40.9	SqFt	\$ 72.00	\$ 2,940.00
VQQ	TW C	315	43	BLOCK CR	Medium	44457	SqFt	100.0%	FDOT - CRACK SEALING - AC	13550.52	Ft	\$ 3.00	\$ 40,660.00
VQQ	TW C	315	52	Raveling	Low	26674.15	SqFt	60.0%	FDOT - SURFACE SEAL	26674.05	SqFt	\$ 0.55	\$ 14,680.00
VQQ	TW C	315	52	Raveling	Medium	17782.84	SqFt	40.0%	FDOT - PATCHING - AC PARTIAL DEPTH	17783.06	SqFt	\$ 5.50	\$ 97,810.00
VQQ	TW D	405	62	CORNER BREAK	Low	9.28	Slabs	0.4%	FDOT - CRACK SEALING - PCC	76.12	Ft	\$ 4.25	\$ 330.00
VQQ	TW D	405	65	JT SEAL DMG	Low	1558.9	Slabs	70.0%	FDOT - JOINT SEAL - PCC	38167.65	Ft	\$ 2.75	\$ 104,970.00
VQQ	TW D	405	66	SMALL PATCH	Medium	74.23	Slabs	3.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	200.21	SqFt	\$ 72.00	\$ 14,390.00
VQQ	TW D	405	74	JOINT SPALL	Low	83.51	Slabs	3.8%	FDOT - CRACK SEALING - PCC	137.14	Ft	\$ 4.25	\$ 590.00
VQQ	TW D	405	74	JOINT SPALL	Medium	64.95	Slabs	2.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	419.79	SqFt	\$ 72.00	\$ 30,210.00
VQQ	TW D	405	75	CORNER SPALL	Low	64.95	Slabs	2.9%	FDOT - CRACK SEALING - PCC	106.63	Ft	\$ 4.25	\$ 460.00
VQQ	TW D	405	75	CORNER SPALL	Medium	37.12	Slabs	1.7%	FDOT - PATCHING - PCC PARTIAL DEPTH	100.1	SqFt	\$ 72.00	\$ 7,200.00
VQQ	TW D	410	65	JT SEAL DMG	Low	130	Slabs	100.0%	FDOT - JOINT SEAL - PCC	3165.03	Ft	\$ 2.75	\$ 8,710.00
VQQ	TW M	1305	65	JT SEAL DMG	Low	60	Slabs	50.0%	FDOT - JOINT SEAL - PCC	1012.47	Ft	\$ 2.75	\$ 2,790.00
VQQ	TW M	1305	74	JOINT SPALL	Low	5	Slabs	4.2%	FDOT - CRACK SEALING - PCC	8.2	Ft	\$ 4.25	\$ 40.00
VQQ	TW M	1305	74	JOINT SPALL	Medium	2.5	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	16.15	SqFt	\$ 72.00	\$ 1,170.00
VQQ	TW M	1305	75	CORNER SPALL	Medium	2.5	Slabs	2.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	6.46	SqFt	\$ 72.00	\$ 490.00



Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2018	VQQ	AP N	4110	PCC	290,625	55	PCC Restoration	\$ 4,941,000.00
2018	VQQ	AP N RFUEL	5135	PCC	22,115	61	PCC Restoration	\$ 376,000.00
2018	VQQ	AP N RFUEL	5140	PCC	22,115	43	PCC Restoration	\$ 459,000.00
2018	VQQ	AP W	4225	PCC	35,000	13	PCC Reconstruction	\$ 806,000.00
2018	VQQ	AP W	4230	PCC	26,250	11	PCC Reconstruction	\$ 604,000.00
2018	VQQ	AP W	4235	PCC	13,730	11	PCC Reconstruction	\$ 316,000.00
2018	VQQ	AP W	4255	PCC	19,950	8	PCC Reconstruction	\$ 459,000.00
2018	VQQ	AP W RFUEL	5020	PCC	22,135	42	PCC Restoration	\$ 472,000.00
2018	VQQ	AP W RFUEL	5055	PCC	13,010	29	PCC Reconstruction	\$ 300,000.00
2018	VQQ	RW 18R-36L	6115	AAC	542,800	28	AC Reconstruction	\$ 7,599,000.00
2018	VQQ	RW 18R-36L	6120	AAC	542,800	31	AC Reconstruction	\$ 7,599,000.00
2018	VQQ	RW 9L-27R	6414	AAC	56,500	49	AC Restoration	\$ 634,000.00
2018	VQQ	RW 9L-27R	6415	AAC	283,572	25	AC Reconstruction	\$ 3,970,000.00
2018	VQQ	RW 9L-27R	6417	AAC	28,250	58	AC Restoration	\$ 311,000.00
2018	VQQ	RW 9L-27R	6420	AAC	311,822	31	AC Reconstruction	\$ 4,366,000.00
2018	VQQ	TW A	105	PCC	67,381	61	PCC Restoration	\$ 1,146,000.00
2018	VQQ	TW C	315	AC	44,457	29	AC Reconstruction	\$ 623,000.00
2019	VQQ	TW D	420	AC	31,875	64	AC Restoration	\$ 351,000.00
2020	VQQ	AP N	4137	PCC	74,250	63	PCC Restoration	\$ 1,263,000.00
2021	VQQ	AP N	4105	PCC	172,130	64	PCC Restoration	\$ 2,927,000.00
2021	VQQ	AP N	4140	PCC	102,688	64	PCC Restoration	\$ 1,746,000.00
2021	VQQ	RW 9R-27L	6322	AAC	19,400	64	AC Restoration	\$ 214,000.00
2022	VQQ	AP N	4103	PCC	62,610	64	PCC Restoration	\$ 1,065,000.00
2022	VQQ	AP N	4120	PCC	391,125	64	PCC Restoration	\$ 6,650,000.00
2022	VQQ	AP N	4138	PCC	11,250	64	PCC Restoration	\$ 192,000.00
2022	VQQ	AP W	4205	PCC	166,732	63	PCC Restoration	\$ 2,835,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2022	VQQ	AP W	4250	PCC	285,584	63	PCC Restoration	\$ 4,856,000.00
2022	VQQ	AP W	4270	PCC	41,180	64	PCC Restoration	\$ 701,000.00
2022	VQQ	AP W RFUEL	5010	PCC	22,135	63	PCC Restoration	\$ 377,000.00
2023	VQQ	AP N	4132	PCC	37,875	63	PCC Restoration	\$ 644,000.00
2023	VQQ	AP N	4150	PCC	105,074	63	PCC Restoration	\$ 1,787,000.00
2023	VQQ	AP N RFUEL	5125	PCC	22,115	64	PCC Restoration	\$ 376,000.00
2023	VQQ	AP W	4220	PCC	266,686	64	PCC Restoration	\$ 4,534,000.00
2023	VQQ	AP W	4240	PCC	82,954	63	PCC Restoration	\$ 1,411,000.00
2023	VQQ	AP W	4245	PCC	102,240	63	PCC Restoration	\$ 1,739,000.00
2023	VQQ	RW 18L-36R	6222	AAC	61,900	64	AC Restoration	\$ 681,000.00
2023	VQQ	RW 18R-36L	6175	AAC	20,400	63	AC Restoration	\$ 225,000.00
2023	VQQ	RW 9R-27L	6315	AAC	603,300	64	AC Restoration	\$ 6,637,000.00
2023	VQQ	RW 9R-27L	6317	AAC	20,000	64	AC Restoration	\$ 220,000.00
2024	VQQ	AP N	4115	PCC	236,250	64	PCC Restoration	\$ 4,017,000.00
2024	VQQ	AP W	4210	PCC	233,520	63	PCC Restoration	\$ 3,970,000.00
2024	VQQ	AP W	4260	PCC	50,613	63	PCC Restoration	\$ 861,000.00
2024	VQQ	AP W RFUEL	5005	PCC	22,135	64	PCC Restoration	\$ 377,000.00
2024	VQQ	TW B2	1210	PCC	23,980	64	PCC Restoration	\$ 408,000.00
2025	VQQ	AP N	4125	PCC	1,403,402	63	PCC Restoration	\$ 23,859,000.00
2025	VQQ	AP N RFUEL	5130	PCC	22,115	64	PCC Restoration	\$ 376,000.00
2025	VQQ	AP W	4265	PCC	99,400	64	PCC Restoration	\$ 1,690,000.00
2025	VQQ	RW 18L-36R	6217	AAC	61,900	63	AC Restoration	\$ 681,000.00
2026	VQQ	AP W RFUEL	5015	PCC	22,135	64	PCC Restoration	\$ 377,000.00
2026	VQQ	RW 18L-36R	6215	AAC	638,300	64	AC Restoration	\$ 7,022,000.00
2026	VQQ	RW 18L-36R	6225	PCC	50,200	64	PCC Restoration	\$ 854,000.00
2026	VQQ	TW A2	620	PCC	24,484	64	PCC Restoration	\$ 417,000.00
2027	VQQ	RW 18L-36R	6220	AAC	638,300	64	AC Restoration	\$ 7,022,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2027	VQQ	RW 9R-27L	6320	AAC	585,202	63	AC Restoration	\$ 6,438,000.00
2027	VQQ	TW A3	720	PCC	24,484	64	PCC Restoration	\$ 417,000.00
2027	VQQ	TW C	310	PCC	136,320	64	PCC Restoration	\$ 2,318,000.00


# **Appendix C**

## **Technical Exhibits**

**001 - AIRFIELD PAVEMENT  
NETWORK DEFINITION EXHIBIT**

Airport Pavement Evaluation Report  
**2017**


**Statewide Airfield Pavement  
Management Program**  
CECIL AIRPORT - VQQ



**002 - AIRFIELD PAVEMENT  
SYSTEM INVENTORY EXHIBIT**

Airport Pavement Evaluation Report  
**2017**

**Statewide Airfield Pavement  
Management Program**  
CECIL AIRPORT - VQQ




RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR  
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT  
MATCH PUBLISHED RUNWAY LENGTHS.

## 003 - AIRFIELD PAVEMENT CONDITION INDEX EXHIBIT

Airport Pavement Evaluation Report  
**2017**

### Statewide Airfield Pavement Management Program CECIL AIRPORT - VQQ




RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

## 004 - AIRFIELD PAVEMENT MAJOR REHABILITATION EXHIBIT

Airport Pavement Evaluation Report  
**2017**

### Statewide Airfield Pavement Management Program CECIL AIRPORT - VQQ



# **Appendix D**

**Inspection Photograph Documentation**



Runway 18L-36R, Section 6215, Sample Unit 538 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 18L-36R, Section 6235, Sample Unit 388 - Low Severity (66) Small Patch



Runway 18L-36R, Section 6235, Sample Unit 425 - Low Severity (62) Corner Break, (73) Shrinkage Cracking



Runway 18R-36L, Section 6115, Sample Unit 216 - Low Severity (41) Alligator Cracking, Medium Severity (43) Block Cracking,  
Medium Severity (52) Raveling, Low Severity (56) Swelling



Runway 18R-36L, Section 6115, Sample Unit 229 - Medium Severity (43) Block Cracking, Low Severity (45) Depression, Medium Severity (52) Raveling, Low Severity (53) Rutting, Low Severity (56) Swelling



Runway 18R-36L, Section 6115, Sample Unit 313 - Medium Severity (43) Block Cracking, Medium Severity (52) Raveling, (55) Slippage Cracking



Runway 18R-36L, Section 6120, Sample Unit 169 - Medium Severity (43) Block Cracking, Medium Severity (52) Raveling, Low Severity (56) Swelling



Runway 9R-27L, Section 6315, Sample Unit 328 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 9R-27L, Section 6320, Sample Unit 741 - Low Severity (48) Longitudinal and Transverse Cracking, Low Severity (57) Weathering



Runway 9R-27L, Section 6335, Sample Unit 382 - Low Severity (66) Small Patch, (73) Shrinkage Cracking



Runway 9L-27R, Section 6420, Sample Unit 709 – Low Severity (43) Block Cracking, Medium Severity (52) Raveling, Low Severity (56) Swelling



Runway 9L-27R, Section 6410, Sample Unit 105 - Medium Severity (65) Joint Seal Damage, Medium Severity (66) Small Patch,  
Low Severity (71) Faulting



Taxiway A, Section 130, Sample Unit 131 - Low Severity (66) Small Patch, (73) Shrinkage Cracking



Taxiway A, Section 130, Sample Unit 158 - (73) Shrinkage Cracking, Medium Severity (75) Corner Spall



Taxiway A, Section 110, Sample Unit 266 - (73) Shrinkage Cracking, High Severity (75) Corner Spall



Taxiway B, Section 205, Sample Unit 148 - Low Severity (66) Small Patch, (73) Shrinkage Cracking



Taxiway B, Section 205, Sample Unit 177 - Medium Severity (66) Small Patch, (73) Shrinkage Cracking



Taxiway C, Section 305, Sample Unit 117 - Low Severity (65) Joint Seal Damage, Medium Severity (66) Small Patch, (73) Shrinkage Cracking



Taxiway D, Section 405, Sample Unit 468 - Low Severity (65) Joint Seal Damage, (73) Shrinkage Cracking, Low Severity (75) Corner Spall




Apron N, Section 4125, Sample Unit 473 - Low Severity (65) Joint Seal Damage, Low Severity (66) Small Patch, Medium Severity (66) Small Patch, Medium Severity (70) Scaling



Apron N, Section 4120, Sample Unit 288 - Low Severity (65) Joint Seal Damage, Medium Severity (73) Joint Spall



Apron W, Section 4270, Sample Unit 178 – Medium Severity (66) Small Patch, (73) Shrinkage Cracking



Apron W, Section 4270, Sample Unit 178 – Medium Severity (71) Faulting



# **Appendix E**

## **Inspection Distress Details**

# Re-Inspection Report

**FDOT**

**Generated Date**

8/8/2017

Page 1 of 160

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON	<b>Use:</b>	APRON
<b>Section:</b>	4103	<b>of:</b>	14	<b>From:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	
<b>Area:</b>	62,610 SqFt	<b>Length:</b>	230 Ft	<b>Width:</b>	300 Ft
<b>Slabs:</b>	495	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1984	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	15	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 73				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	428	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	24.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
<b>Sample Number:</b>	527	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	24.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
75	CORNER SPALL	L	3.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4105	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1988
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	172,130 SqFt	<b>Length:</b>	700 Ft	<b>Width:</b>	250 Ft		
<b>Slabs:</b>	918	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	24,717 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1988	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	47	<b>Surveyed:</b>	5		
<b>Conditions:</b>	PCI: 71						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	162	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	59
<b>Sample Comments:</b>							
62	CORNER BREAK	L	1.00	Slabs			
65	JT SEAL DMG	H	20.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	5.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
<b>Sample Number:</b>	165	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	263	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	66
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
67	LARGE PATCH	L	1.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	H	1.00	Slabs			
76	ASR	L	4.00	Slabs			
<b>Sample Number:</b>	267	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	71
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
76	ASR	L	4.00	Slabs			
<b>Sample Number:</b>	318	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	77
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
73	SHRINKAGE CR	N	19.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
76	ASR	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4110	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	290,625 SqFt	<b>Length:</b>	762 Ft	<b>Width:</b>	387 Ft		
<b>Slabs:</b>	775	<b>Slab Length:</b>	25 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	30,306 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	80	<b>Surveyed:</b>	8		
<b>Conditions:</b>	PCI: 56						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	202	<b>Type:</b>	R	<b>Area:</b>	21.00 Slabs	<b>PCI:</b>	60
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	21.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	21.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
74	JOINT SPALL	H	2.00	Slabs			
75	CORNER SPALL	H	1.00	Slabs			
<b>Sample Number:</b>	205	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	64
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			
70	SCALING	L	1.00	Slabs			
70	SCALING	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
<b>Sample Number:</b>	211	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	36
<b>Sample Comments:</b>							
62	CORNER BREAK	M	2.00	Slabs			
63	LINEAR CR	L	1.00	Slabs			
63	LINEAR CR	M	1.00	Slabs			
65	JT SEAL DMG	M	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			
70	SCALING	L	6.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
74	JOINT SPALL	M	2.00	Slabs			
74	JOINT SPALL	H	4.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
75	CORNER SPALL	H	1.00	Slabs			
<b>Sample Number:</b>	303	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	59
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
62	CORNER BREAK	L	1.00	Slabs			
65	JT SEAL DMG	M	20.00	Slabs			
67	LARGE PATCH	L	1.00	Slabs			
67	LARGE PATCH	M	1.00	Slabs			
70	SCALING	L	3.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

**Sample Number:** 309**Type:****R****Area:**

20.00 Slabs

**PCI:** 65**Sample Comments:**

65	JT SEAL DMG	M	20.00	Slabs
67	LARGE PATCH	L	3.00	Slabs
67	LARGE PATCH	M	1.00	Slabs
70	SCALING	L	6.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	2.00	Slabs

**Sample Number:** 404**Type:****R****Area:**

20.00 Slabs

**PCI:** 69**Sample Comments:**

65	JT SEAL DMG	M	20.00	Slabs
66	SMALL PATCH	M	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	3.00	Slabs
75	CORNER SPALL	L	2.00	Slabs

**Sample Number:** 407**Type:****R****Area:**

20.00 Slabs

**PCI:** 45**Sample Comments:**

74	JOINT SPALL	H	1.00	Slabs
75	CORNER SPALL	H	1.00	Slabs
63	LINEAR CR	L	3.00	Slabs
65	JT SEAL DMG	H	20.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
67	LARGE PATCH	M	1.00	Slabs
70	SCALING	L	4.00	Slabs
71	FAULTING	L	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	4.00	Slabs
74	JOINT SPALL	M	2.00	Slabs
75	CORNER SPALL	L	2.00	Slabs
62	CORNER BREAK	L	2.00	Slabs

**Sample Number:** 411**Type:****R****Area:**

20.00 Slabs

**PCI:** 50**Sample Comments:**

74	JOINT SPALL	H	2.00	Slabs
65	JT SEAL DMG	M	20.00	Slabs
66	SMALL PATCH	L	1.00	Slabs
67	LARGE PATCH	L	2.00	Slabs
70	SCALING	L	2.00	Slabs
70	SCALING	M	2.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
74	JOINT SPALL	M	2.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4115	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1965
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	236,250 SqFt	<b>Length:</b>	525 Ft	<b>Width:</b>	475 Ft		
<b>Slabs:</b>	1,336	<b>Slab Length:</b>	14 Ft	<b>Slab Width:</b>	14 Ft	<b>Joint Length:</b>	35,432 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1984	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	63	<b>Surveyed:</b>	7		
<b>Conditions:</b>	PCI: 78						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	150	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	82
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	14.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
<b>Sample Number:</b>	248	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	79
<b>Sample Comments:</b>							
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	347	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	77
<b>Sample Comments:</b>							
66	SMALL PATCH	L	3.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	349	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
70	SCALING	L	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	401	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	73
<b>Sample Comments:</b> Repairs done							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			
70	SCALING	L	4.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	499	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	66
<b>Sample Comments:</b>							
62	CORNER BREAK	L	1.00	Slabs			
65	JT SEAL DMG	M	20.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			

70 SCALING L 3.00 Slabs  
73 SHRINKAGE CR N 20.00 Slabs  
75 CORNER SPALL L 1.00 Slabs

---

**Sample Number:** 597      **Type:** R      **Area:** 20.00 Slabs      **PCI:** 86

**Sample Comments:**

73 SHRINKAGE CR N 20.00 Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4117	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	14,325 SqFt	<b>Length:</b>	110 Ft	<b>Width:</b>	125 Ft		
<b>Slabs:</b>	76	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	1,782 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/2014	<b>Work Type:</b>	FDOT - PATCHING - PCC PARTIAL DEPTH	<b>Code:</b>	FDOT-PA-PP	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 88						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	100	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	88
<b>Sample Comments:</b>	Repairs done						
66	SMALL PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	9.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4120	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	391,125 SqFt	<b>Length:</b>	800 Ft	<b>Width:</b>	525 Ft		
<b>Slabs:</b>	2,240	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	60,275 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	105		<b>Surveyed:</b>	10	
<b>Conditions:</b>	PCI: 73						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	136	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
65	JT SEAL DMG	L		20.00	Slabs		
71	FAULTING	L		1.00	Slabs		
66	SMALL PATCH	L		7.00	Slabs		
73	SHRINKAGE CR	N		20.00	Slabs		
<b>Sample Number:</b>	141	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
66	SMALL PATCH	L		2.00	Slabs		
66	SMALL PATCH	M		1.00	Slabs		
73	SHRINKAGE CR	N		20.00	Slabs		
75	CORNER SPALL	M		1.00	Slabs		
71	FAULTING	L		3.00	Slabs		
<b>Sample Number:</b>	244	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	59
<b>Sample Comments:</b>							
66	SMALL PATCH	L		3.00	Slabs		
66	SMALL PATCH	M		4.00	Slabs		
67	LARGE PATCH	L		4.00	Slabs		
73	SHRINKAGE CR	N		20.00	Slabs		
75	CORNER SPALL	L		4.00	Slabs		
75	CORNER SPALL	M		2.00	Slabs		
71	FAULTING	L		1.00	Slabs		
<b>Sample Number:</b>	288	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	59
<b>Sample Comments:</b>							
65	JT SEAL DMG	L		20.00	Slabs		
63	LINEAR CR	L		2.00	Slabs		
66	SMALL PATCH	M		3.00	Slabs		
73	SHRINKAGE CR	N		20.00	Slabs		
74	JOINT SPALL	M		5.00	Slabs		
75	CORNER SPALL	L		1.00	Slabs		
75	CORNER SPALL	M		2.00	Slabs		
<b>Sample Number:</b>	336	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	77
<b>Sample Comments:</b>							
65	JT SEAL DMG	L		20.00	Slabs		
66	SMALL PATCH	L		2.00	Slabs		
67	LARGE PATCH	M		1.00	Slabs		
73	SHRINKAGE CR	N		20.00	Slabs		
<b>Sample Number:</b>	344	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
71	FAULTING	L		1.00	Slabs		
66	SMALL PATCH	M		1.00	Slabs		
73	SHRINKAGE CR	N		20.00	Slabs		
75	CORNER SPALL	L		1.00	Slabs		
75	CORNER SPALL	M		1.00	Slabs		

**Sample Number:** 390

**Type:** R

**Area:**

20.00 Slabs

**PCI:** 84

**Sample Comments:**

65 JT SEAL DMG

L

20.00 Slabs

73 SHRINKAGE CR

N

20.00 Slabs

---

**Sample Number:** 492

**Type:** R

**Area:**

20.00 Slabs

**PCI:** 81

**Sample Comments:**

65 JT SEAL DMG

L

20.00 Slabs

66 SMALL PATCH

L

4.00 Slabs

73 SHRINKAGE CR

N

20.00 Slabs

---

**Sample Number:** 536

**Type:** R

**Area:**

20.00 Slabs

**PCI:** 66

**Sample Comments:**

67 LARGE PATCH

L

1.00 Slabs

71 FAULTING

L

4.00 Slabs

66 SMALL PATCH

L

5.00 Slabs

66 SMALL PATCH

M

2.00 Slabs

73 SHRINKAGE CR

N

20.00 Slabs

---

**Sample Number:** 540

**Type:** R

**Area:**

20.00 Slabs

**PCI:** 82

**Sample Comments:**

66 SMALL PATCH

L

1.00 Slabs

66 SMALL PATCH

M

1.00 Slabs

73 SHRINKAGE CR

N

20.00 Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON	<b>Use:</b>	APRON
<b>Section:</b>	4125	<b>of:</b>	14	<b>From:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	1,403,402 SqFt	<b>Length:</b>	2,643 Ft	<b>Width:</b>	525 Ft
<b>Slabs:</b>	7,400	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	376	<b>Surveyed:</b>	10
<b>Conditions:</b>	PCI:	79			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	173	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
<b>Sample Number:</b>	184	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
75	CORNER SPALL	M	1.00	Slabs	
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	208	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	229	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	255	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
74	JOINT SPALL	L	1.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	264	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	369	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
71	FAULTING	L	2.00	Slabs	
66	SMALL PATCH	L	2.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
67	LARGE PATCH	M	1.00	Slabs	
70	SCALING	L	3.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	433	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					

71	FAULTING	L	3.00	Slabs
66	SMALL PATCH	L	4.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

---

<b>Sample Number:</b> 452	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 86
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

73	SHRINKAGE CR	N	20.00	Slabs
----	--------------	---	-------	-------

---

<b>Sample Number:</b> 473	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 66
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

65	JT SEAL DMG	L	20.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
75	CORNER SPALL	L	2.00	Slabs
66	SMALL PATCH	L	2.00	Slabs
66	SMALL PATCH	M	1.00	Slabs
70	SCALING	L	2.00	Slabs
70	SCALING	M	2.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4132	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	37,875 SqFt	<b>Length:</b>	300 Ft	<b>Width:</b>	125 Ft		
<b>Slabs:</b>	202	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	5,075 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 75						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	103	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	76
<b>Sample Comments:</b>							
66	SMALL PATCH	L	3.00	Slabs			
70	SCALING	L	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
<b>Sample Number:</b>	201	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
70	SCALING	L	5.00	Slabs			
70	SCALING	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4137	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	74,250 SqFt	<b>Length:</b>	825 Ft	<b>Width:</b>	70 Ft		
<b>Slabs:</b>	396	<b>Slab Length:</b>	12 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	7,575 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	20	<b>Surveyed:</b>	3		
<b>Conditions:</b>	PCI: 68						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	103	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	71
<b>Sample Comments:</b>							
74	JOINT SPALL	L	2.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
71	FAULTING	L	1.00	Slabs			
63	LINEAR CR	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	105	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	69
<b>Sample Comments:</b>							
63	LINEAR CR	L	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	M	2.00	Slabs			
75	CORNER SPALL	M	2.00	Slabs			
<b>Sample Number:</b>	304	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	64
<b>Sample Comments:</b>							
62	CORNER BREAK	M	1.00	Slabs			
63	LINEAR CR	H	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
63	LINEAR CR	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4138	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1953
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	11,250 SqFt	<b>Length:</b>	187 Ft	<b>Width:</b>	60 Ft		
<b>Slabs:</b>	60	<b>Slab Length:</b>	15 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	1,252 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1953	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 74						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	307	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
75	CORNER SPALL	L	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4140	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	102,688 SqFt	<b>Length:</b>	525 Ft	<b>Width:</b>	200 Ft		
<b>Slabs:</b>	548	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	14,675 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	28	<b>Surveyed:</b>	3		
<b>Conditions:</b>	PCI: 71						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	300	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	63
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
67	LARGE PATCH	L	1.00	Slabs			
70	SCALING	L	1.00	Slabs			
71	FAULTING	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	5.00	Slabs			
<b>Sample Number:</b>	302	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	71
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
70	SCALING	L	1.00	Slabs			
71	FAULTING	L	3.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
<b>Sample Number:</b>	304	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	79
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4150	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1965
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	105,074 SqFt	<b>Length:</b>	375 Ft	<b>Width:</b>	237 Ft		
<b>Slabs:</b>	484	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	12,423 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	OVERLAY		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	26	<b>Surveyed:</b> 3			
<b>Conditions:</b>	PCI: 75						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	653	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	79
<b>Sample Comments:</b>							
65	JT SEAL DMG		L	20.00	Slabs		
66	SMALL PATCH		L	4.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	702	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	70
<b>Sample Comments:</b> Repairs done							
66	SMALL PATCH		L	8.00	Slabs		
65	JT SEAL DMG		L	20.00	Slabs		
71	FAULTING		L	3.00	Slabs		
67	LARGE PATCH		L	1.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
<b>Sample Number:</b>	804	<b>Type:</b>	R	<b>Area:</b>	25.00 Slabs	<b>PCI:</b>	75
<b>Sample Comments:</b>							
65	JT SEAL DMG		L	25.00	Slabs		
66	SMALL PATCH		L	3.00	Slabs		
73	SHRINKAGE CR		N	25.00	Slabs		
74	JOINT SPALL		L	3.00	Slabs		
75	CORNER SPALL		L	2.00	Slabs		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4305	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 5/1/2005
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> S
<b>Area:</b>	70,920 SqFt	<b>Length:</b>	360 Ft	<b>Width:</b>	197 Ft		
<b>Slabs:</b>	315	<b>Slab Length:</b>	15 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	8,899 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	5/1/2005	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	18	<b>Surveyed:</b>	3		
<b>Conditions:</b>	PCI: 95						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	200	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	95
<b>Sample Comments:</b>							
75	CORNER SPALL	L		1.00	Slabs		
65	JT SEAL DMG	L		20.00	Slabs		
73	SHRINKAGE CR	N		1.00	Slabs		
<b>Sample Number:</b>	302	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	97
<b>Sample Comments:</b>							
65	JT SEAL DMG	L		20.00	Slabs		
73	SHRINKAGE CR	N		1.00	Slabs		
<b>Sample Number:</b>	304	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	92
<b>Sample Comments:</b>							
65	JT SEAL DMG	L		20.00	Slabs		
73	SHRINKAGE CR	N		8.00	Slabs		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4310	of 14	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	43,214 SqFt	<b>Length:</b>	460 Ft	<b>Width:</b>	75 Ft		
<b>Slabs:</b>	191	<b>Slab Length:</b>	15 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	4,065 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	11	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 99						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	501	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	99
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N	1.00	Slabs			
<b>Sample Number:</b>	504	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	99
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N RFUEL	<b>Name:</b>	N HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5125	of 4	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	22,115 SqFt	<b>Length:</b>	105 Ft	<b>Width:</b>	200 Ft		
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,775 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 76						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	101	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	76
<b>Sample Comments:</b>							
75	CORNER SPALL	L	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	4.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
73	SHRINKAGE CR	N	3.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N RFUEL	<b>Name:</b>	N HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5130	of 4	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	22,115 SqFt	<b>Length:</b>	105 Ft	<b>Width:</b>	200 Ft		
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,775 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 81						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	200	<b>Type:</b>	R	<b>Area:</b>	19.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
74	JOINT SPALL	L	1.00	Slabs			
65	JT SEAL DMG	L	19.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	7.00	Slabs			
75	CORNER SPALL	L	3.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N RFUEL	<b>Name:</b>	N HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5135	of 4	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	22,115 SqFt	<b>Length:</b>	105 Ft	<b>Width:</b>	200 Ft		
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,775 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 62						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	102	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	62
<b>Sample Comments:</b>							
63	LINEAR CR	L	2.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
66	SMALL PATCH	M	6.00	Slabs			
67	LARGE PATCH	L	4.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	6.00	Slabs			
74	JOINT SPALL	L	4.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP N RFUEL	<b>Name:</b>	N HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5140	of 4	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	22,115 SqFt	<b>Length:</b>	105 Ft	<b>Width:</b>	200 Ft		
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,775 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 44						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	201	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	44
<b>Sample Comments:</b>							
65	JT SEAL DMG	M	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
73	SHRINKAGE CR	N	12.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
74	JOINT SPALL	M	4.00	Slabs			
74	JOINT SPALL	H	4.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP NAT GRD	<b>Name:</b>	NATIONAL GUARD WASH APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5305	of 2	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1976
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	30,200 SqFt		<b>Length:</b>	150 Ft	<b>Width:</b>	140 Ft	
<b>Slabs:</b>	160	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,790 Ft
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1976	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8		<b>Surveyed:</b>	2	
<b>Conditions:</b>	PCI: 88						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	560	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	78
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	661	<b>Type:</b>	R	<b>Area:</b>	29.00 Slabs	<b>PCI:</b>	94
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	29.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	3.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	AP NAT GRD	<b>Name:</b>	NATIONAL GUARD WASH APRON	<b>Use:</b>	APRON
<b>Section:</b>	5310	of 2	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2010
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	199,156 SqFt	<b>Length:</b>	1,103 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	1,062	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 23,013 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	54	<b>Surveyed:</b>	6
<b>Conditions:</b>	PCI: 93				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	308	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR		N	10.00	Slabs
<b>Sample Number:</b>	458	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH		L	1.00	Slabs
71	FAULTING		L	1.00	Slabs
73	SHRINKAGE CR		N	8.00	Slabs
<b>Sample Number:</b>	512	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR		N	2.00	Slabs
<b>Sample Number:</b>	514	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR		N	6.00	Slabs
<b>Sample Number:</b>	705	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR		N	10.00	Slabs
<b>Sample Number:</b>	708	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH		L	1.00	Slabs
73	SHRINKAGE CR		N	10.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4205	of 13	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	166,732 SqFt	<b>Length:</b>	402 Ft	<b>Width:</b>	320 Ft		
<b>Slabs:</b>	1,123	<b>Slab Length:</b>	10 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	20,718 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	59	<b>Surveyed:</b>	6		
<b>Conditions:</b>	PCI: 72						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	200	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	78
<b>Sample Comments:</b>							
75	CORNER SPALL	L	3.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	350	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
67	LARGE PATCH	L	7.00	Slabs			
73	SHRINKAGE CR	N	19.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
<b>Sample Number:</b>	501	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	71
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
<b>Sample Number:</b>	506	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	67
<b>Sample Comments:</b>							
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
63	LINEAR CR	M	2.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	553	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	75
<b>Sample Comments:</b>							
66	SMALL PATCH	L	1.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	605	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	66
<b>Sample Comments:</b>							
74	JOINT SPALL	L	3.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
75	CORNER SPALL	L	3.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4210	of 13	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1959
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	233,520 SqFt	<b>Length:</b>	525 Ft	<b>Width:</b>	310 Ft		
<b>Slabs:</b>	1,282	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	23,035 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	64	<b>Surveyed:</b>	7		
<b>Conditions:</b>	PCI: 77						
<b>Inspection Comments:</b> Repairs done							
<b>Sample Number:</b>	206	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	70
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
75	CORNER SPALL	H	1.00	Slabs			
<b>Sample Number:</b>	253	<b>Type:</b>	R	<b>Area:</b>	15.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
74	JOINT SPALL	L	2.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	14.00	Slabs			
<b>Sample Number:</b>	305	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	78
<b>Sample Comments:</b>							
74	JOINT SPALL	L	2.00	Slabs			
67	LARGE PATCH	L	3.00	Slabs			
73	SHRINKAGE CR	N	19.00	Slabs			
<b>Sample Number:</b>	357	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	4.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	19.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	403	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	76
<b>Sample Comments:</b>							
66	SMALL PATCH	L	1.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
67	LARGE PATCH	L	3.00	Slabs			
73	SHRINKAGE CR	N	19.00	Slabs			
<b>Sample Number:</b>	603	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
67	LARGE PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	651	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	83
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4220	of 13	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1960
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	266,686 SqFt	<b>Length:</b>	880 Ft	<b>Width:</b>	310 Ft		
<b>Slabs:</b>	1,451	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	38,821 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	72	<b>Surveyed:</b>	8		
<b>Conditions:</b>	PCI: 76						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	210	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	75
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
66	SMALL PATCH	L	5.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	213	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	267	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
70	SCALING	L	7.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	312	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	80
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	319	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	80
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
70	SCALING	L	3.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	364	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	66
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			

**Sample Number:** 411

**Type:** R

**Area:**

20.00 Slabs

**PCI:** 75

**Sample Comments:**

65	JT SEAL DMG	L	20.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
67	LARGE PATCH	L	3.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
66	SMALL PATCH	L	1.00	Slabs

---

**Sample Number:** 416

**Type:** R

**Area:**

20.00 Slabs

**PCI:** 77

**Sample Comments:**

65	JT SEAL DMG	L	20.00	Slabs
74	JOINT SPALL	L	3.00	Slabs
70	SCALING	L	5.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4225	of 13	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1991
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	35,000 SqFt	<b>Length:</b>	320 Ft	<b>Width:</b>	105 Ft		
<b>Slabs:</b>	84	<b>Slab Length:</b>	20 Ft	<b>Slab Width:</b>	20 Ft	<b>Joint Length:</b>	2,935 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 14						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	101	<b>Type:</b>	R	<b>Area:</b>	15.00 Slabs	<b>PCI:</b>	14
<b>Sample Comments:</b> Imgainary slabs added due to adjusted geometry.							
63	LINEAR CR	L	2.00	Slabs			
65	JT SEAL DMG	M	15.00	Slabs			
66	SMALL PATCH	L	5.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
67	LARGE PATCH	M	1.00	Slabs			
72	SHAT. SLAB	M	5.00	Slabs			
73	SHRINKAGE CR	N	6.00	Slabs			
72	SHAT. SLAB	L	2.00	Slabs			
63	LINEAR CR	M	3.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4230	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	26,250 SqFt	<b>Length:</b>	270 Ft	<b>Width:</b>	115 Ft		
<b>Slabs:</b>	78	<b>Slab Length:</b>	20 Ft	<b>Slab Width:</b>	20 Ft	<b>Joint Length:</b>	2,720 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6		<b>Surveyed:</b>	1	
<b>Conditions:</b>	PCI: 12						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	204	<b>Type:</b>	R	<b>Area:</b>	12.00 Slabs	<b>PCI:</b>	12
<b>Sample Comments:</b>	Imaginary slabs added due to adjusted geometry.						
63	LINEAR CR	L	1.00	Slabs			
63	LINEAR CR	M	1.00	Slabs			
65	JT SEAL DMG	L	12.00	Slabs			
67	LARGE PATCH	M	1.00	Slabs			
72	SHAT. SLAB	L	4.00	Slabs			
72	SHAT. SLAB	M	6.00	Slabs			
73	SHRINKAGE CR	N	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4235	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	13,730 SqFt	<b>Length:</b>	320 Ft	<b>Width:</b>	30 Ft		
<b>Slabs:</b>	11	<b>Slab Length:</b>	20 Ft	<b>Slab Width:</b>	60 Ft	<b>Joint Length:</b>	290 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3		<b>Surveyed:</b> 1		
<b>Conditions:</b>	PCI: 12						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	801	<b>Type:</b>	R	<b>Area:</b>	4.00 Slabs	<b>PCI:</b>	12
<b>Sample Comments:</b>							
72	SHAT. SLAB	M		4.00 Slabs			
65	JT SEAL DMG	M		4.00 Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4240	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	82,954 SqFt	<b>Length:</b>	1,406 Ft	<b>Width:</b>	59 Ft		
<b>Slabs:</b>	682	<b>Slab Length:</b>	10 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	12,361 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	32		<b>Surveyed:</b> 5		
<b>Conditions:</b> PCI: 75							
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	154	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	75
<b>Sample Comments:</b>							
66	SMALL PATCH		L	4.00	Slabs		
67	LARGE PATCH		L	2.00	Slabs		
73	SHRINKAGE CR		N	18.00	Slabs		
75	CORNER SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	159	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	69
<b>Sample Comments:</b>							
66	SMALL PATCH		L	3.00	Slabs		
66	SMALL PATCH		M	2.00	Slabs		
67	LARGE PATCH		L	2.00	Slabs		
73	SHRINKAGE CR		N	18.00	Slabs		
75	CORNER SPALL		M	1.00	Slabs		
<b>Sample Number:</b>	163	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	76
<b>Sample Comments:</b>							
66	SMALL PATCH		M	1.00	Slabs		
73	SHRINKAGE CR		N	18.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
74	JOINT SPALL		M	1.00	Slabs		
<b>Sample Number:</b>	170	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	82
<b>Sample Comments:</b>							
66	SMALL PATCH		L	2.00	Slabs		
73	SHRINKAGE CR		N	18.00	Slabs		
75	CORNER SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	180	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	71
<b>Sample Comments:</b>							
66	SMALL PATCH		L	12.00	Slabs		
66	SMALL PATCH		M	1.00	Slabs		
67	LARGE PATCH		L	2.00	Slabs		
73	SHRINKAGE CR		N	18.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4245	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	102,240 SqFt	<b>Length:</b>	1,704 Ft	<b>Width:</b>	60 Ft		
<b>Slabs:</b>	1,235	<b>Slab Length:</b>	10 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	15,276 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	38		<b>Surveyed:</b>	4	
<b>Conditions:</b>	PCI: 75						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	103	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	75
<b>Sample Comments:</b>							
66	SMALL PATCH	L	9.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	18.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
<b>Sample Number:</b>	116	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	75
<b>Sample Comments:</b>							
66	SMALL PATCH	L	9.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	18.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
<b>Sample Number:</b>	124	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	75
<b>Sample Comments:</b>							
66	SMALL PATCH	L	5.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
67	LARGE PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	18.00	Slabs			
<b>Sample Number:</b>	129	<b>Type:</b>	R	<b>Area:</b>	18.00 Slabs	<b>PCI:</b>	76
<b>Sample Comments:</b>							
66	SMALL PATCH	L	7.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	18.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	4250	of 13	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1976
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	285,584 SqFt	<b>Length:</b>	555 Ft	<b>Width:</b>	500 Ft		
<b>Slabs:</b>	1,523	<b>Slab Length:</b>	12 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	39,645 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1976	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	76		<b>Surveyed:</b>	8	
<b>Conditions:</b>	PCI: 72						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	150	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	86
<b>Sample Comments:</b>							
73	SHRINKAGE CR		N	20.00	Slabs		
<b>Sample Number:</b>	155	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	83
<b>Sample Comments:</b>							
70	SCALING		L	1.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	202	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	82
<b>Sample Comments:</b>							
74	JOINT SPALL		L	1.00	Slabs		
75	CORNER SPALL		L	1.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
<b>Sample Number:</b>	254	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	80
<b>Sample Comments:</b>							
63	LINEAR CR		L	1.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	351	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	69
<b>Sample Comments:</b>							
67	LARGE PATCH		L	4.00	Slabs		
74	JOINT SPALL		L	2.00	Slabs		
70	SCALING		L	1.00	Slabs		
71	FAULTING		L	3.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
<b>Sample Number:</b>	406	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	70
<b>Sample Comments:</b>							
71	FAULTING		L	6.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
74	JOINT SPALL		L	2.00	Slabs		
<b>Sample Number:</b>	453	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	73
<b>Sample Comments:</b>							
66	SMALL PATCH		L	1.00	Slabs		
71	FAULTING		L	3.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
74	JOINT SPALL		M	2.00	Slabs		
<b>Sample Number:</b>	555	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	32
<b>Sample Comments:</b>							
62	CORNER BREAK		L	1.00	Slabs		
66	SMALL PATCH		L	11.00	Slabs		
66	SMALL PATCH		M	1.00	Slabs		

67	LARGE PATCH	L	7.00	Slabs
67	LARGE PATCH	M	13.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	2.00	Slabs
74	JOINT SPALL	M	1.00	Slabs
75	CORNER SPALL	M	2.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4255	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	19,950 SqFt	<b>Length:</b>	320 Ft	<b>Width:</b>	30 Ft		
<b>Slabs:</b>	42	<b>Slab Length:</b>	14 Ft	<b>Slab Width:</b>	17 Ft	<b>Joint Length:</b>	918 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3		<b>Surveyed:</b>	1	
<b>Conditions:</b>	PCI: 9						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	301	<b>Type:</b>	R	<b>Area:</b>	14.00 Slabs	<b>PCI:</b>	9
<b>Sample Comments:</b>	Imaginary slabs added due to adjusted geometry.						
63	LINEAR CR	L	2.00	Slabs			
63	LINEAR CR	M	5.00	Slabs			
65	JT SEAL DMG	M	14.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
72	SHAT. SLAB	M	3.00	Slabs			
72	SHAT. SLAB	H	1.00	Slabs			
73	SHRINKAGE CR	N	8.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4260	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1961
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	50,613 SqFt	<b>Length:</b>	320 Ft	<b>Width:</b>	200 Ft		
<b>Slabs:</b>	341	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	8,867 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1961	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	12		<b>Surveyed:</b> 1		
<b>Conditions:</b> PCI: 77							
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	403	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	77
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N		20.00	Slabs		
74	JOINT SPALL	L		1.00	Slabs		
74	JOINT SPALL	M		2.00	Slabs		
75	CORNER SPALL	L		1.00	Slabs		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4265	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	99,400 SqFt	<b>Length:</b>	710 Ft	<b>Width:</b>	140 Ft		
<b>Slabs:</b>	937	<b>Slab Length:</b>	10 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	15,717 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	36		<b>Surveyed:</b>	5	
<b>Conditions:</b> PCI: 80							
<b>Inspection Comments:</b> Updated geometry based on field verification							
<b>Sample Number:</b>	175	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	73
<b>Sample Comments:</b>							
66	SMALL PATCH		L	7.00	Slabs		
66	SMALL PATCH		M	1.00	Slabs		
67	LARGE PATCH		L	1.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	277	<b>Type:</b>	R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
66	SMALL PATCH		L	1.00	Slabs		
66	SMALL PATCH		M	1.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
<b>Sample Number:</b>	426	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	84
<b>Sample Comments:</b>							
73	SHRINKAGE CR		N	20.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	527	<b>Type:</b>	R	<b>Area:</b>	16.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
75	CORNER SPALL		M	1.00	Slabs		
73	SHRINKAGE CR		N	16.00	Slabs		
<b>Sample Number:</b>	625	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	83
<b>Sample Comments:</b>							
67	LARGE PATCH		L	1.00	Slabs		
73	SHRINKAGE CR		N	20.00	Slabs		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W	<b>Name:</b>	WEST PARKING APRON	<b>Use:</b>	APRON	<b>Area:</b>	1,423,839 SqFt
<b>Section:</b>	4270	of 13	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	41,180 SqFt	<b>Length:</b>	710 Ft	<b>Width:</b>	58 Ft		
<b>Slabs:</b>	275	<b>Slab Length:</b>	10 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	6,095 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b> IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	12		<b>Surveyed:</b>	2	
<b>Conditions:</b>	PCI: 73						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	178	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	63
<b>Sample Comments:</b>							
66	SMALL PATCH	L	3.00	Slabs			
66	SMALL PATCH	M	3.00	Slabs			
66	SMALL PATCH	H	1.00	Slabs			
71	FAULTING	M	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	3.00	Slabs			
<b>Sample Number:</b>	378	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	82
<b>Sample Comments:</b>							
66	SMALL PATCH	L	1.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W RFUEL	<b>Name:</b>	W HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5005	of 5	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	22,135 SqFt		<b>Length:</b>	210 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,770 Ft
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6		<b>Surveyed:</b>	1	
<b>Conditions:</b>	PCI: 78						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	100	<b>Type:</b>	R	<b>Area:</b>	23.00 Slabs	<b>PCI:</b>	78
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	23.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
67	LARGE PATCH	L	1.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
73	SHRINKAGE CR	N	23.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W RFUEL	<b>Name:</b>	W HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5010	of 5	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	22,135 SqFt		<b>Length:</b>	210 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,770 Ft
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6		<b>Surveyed:</b>	1	
<b>Conditions:</b>	PCI: 72						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	301	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
63	LINEAR CR	L	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	17.00	Slabs			
74	JOINT SPALL	L	4.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	AP W RFUEL	<b>Name:</b>	W HOT REFUELING AND COMPASS ROSE AP	<b>Use:</b>	APRON
<b>Section:</b>	5015	of 5	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	22,135 SqFt	<b>Length:</b>	210 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 2,770 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 83				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	600	<b>Type:</b>	R	<b>Area:</b>	23.00 Slabs
<b>Sample Comments:</b>					
74	JOINT SPALL	L	1.00	Slabs	
65	JT SEAL DMG	L	23.00	Slabs	
73	SHRINKAGE CR	N	23.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W RFUEL	<b>Name:</b>	W HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5020	of 5	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	22,135 SqFt		<b>Length:</b>	210 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>	112	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,770 Ft
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6		<b>Surveyed:</b>	1	
<b>Conditions:</b>	PCI: 43						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	801	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	43
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
62	CORNER BREAK	L	1.00	Slabs			
63	LINEAR CR	M	1.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
66	SMALL PATCH	H	1.00	Slabs			
67	LARGE PATCH	L	4.00	Slabs			
67	LARGE PATCH	M	4.00	Slabs			
73	SHRINKAGE CR	N	19.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	AP W RFUEL	<b>Name:</b>	W HOT REFUELING AND COMPASS ROSE AP		<b>Use:</b>	APRON	<b>Area:</b>
<b>Section:</b>	5055	of 5	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1955
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-AP-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	13,010 SqFt		<b>Length:</b>	80 Ft	<b>Width:</b>	150 Ft	
<b>Slabs:</b>	69	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	1,530 Ft
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1955	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	2		<b>Surveyed:</b>	1	
<b>Conditions:</b>	PCI: 30						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	209	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	30
<b>Sample Comments:</b>							
63	LINEAR CR	L	8.00	Slabs			
63	LINEAR CR	M	7.00	Slabs			
65	JT SEAL DMG	M	20.00	Slabs			
72	SHAT. SLAB	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
75	CORNER SPALL	L	3.00	Slabs			
75	CORNER SPALL	M	2.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6205	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> T
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,733 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 79				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	300	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
<b>Sample Number:</b>	303	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	4.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	501	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
70	SCALING	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
<b>Sample Number:</b>	504	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6210	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	1,000 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,283 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 83				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	102	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		20.00	Slabs
75	CORNER SPALL	L		1.00	Slabs
<b>Sample Number:</b>	105	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		20.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
<b>Sample Number:</b>	702	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		4.00	Slabs
67	LARGE PATCH	L		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs
<b>Sample Number:</b>	705	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6215	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011	
<b>Surface:</b>	AAC	<b>Family:</b> C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P	
<b>Area:</b>	638,300 SqFt	<b>Length:</b>	6,383 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	128	<b>Surveyed:</b>	19	
<b>Conditions:</b>	PCI: 82					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	309	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
41	ALLIGATOR CR	L	11.00	SqFt		
48	L & T CR	L	116.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	315	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	163.00	Ft		
56	SWELLING	L	25.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	321	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	45.00	Ft		
56	SWELLING	L	10.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	328	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	128.00	Ft		
56	SWELLING	L	13.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	334	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	162.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	341	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	241.00	Ft		
56	SWELLING	L	20.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	348	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	222.00	Ft		
56	SWELLING	L	20.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	354	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						

48	L & T CR	L	375.00	Ft
56	SWELLING	L	5.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 360	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 74
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	359.00	Ft
56	SWELLING	L	38.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 367	<b>Type:</b> A	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 61
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

42	BLEEDING	N	1.00	SqFt
45	DEPRESSION	L	97.00	SqFt
48	L & T CR	L	537.00	Ft
56	SWELLING	L	430.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 512	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 87
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	115.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 518	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 88
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	48.00	Ft
56	SWELLING	L	14.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 524	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 89
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	21.00	Ft
56	SWELLING	L	9.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 531	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 87
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	85.00	Ft
56	SWELLING	L	11.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 538	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 82
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	185.00	Ft
56	SWELLING	L	15.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 544	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 87
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	90.00	Ft
56	SWELLING	L	2.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 551	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 87
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	68.00	Ft
56	SWELLING	L	17.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 557	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 77
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	294.00	Ft
56	SWELLING	L	10.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 570	<b>Type:</b> R	<b>Area:</b>	4150.00 SqFt	<b>PCI:</b> 68
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	481.00	Ft
56	SWELLING	L	15.00	SqFt
57	WEATHERING	L	4150.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6217	of	10	<b>From:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	61,900 SqFt	<b>Length:</b>	619 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	12	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI:	79			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	374	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	167.00	Ft	
57	WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b>	572	<b>Type:</b>	R	<b>Area:</b>	4925.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	388.00	Ft	
48	L & T CR	M	22.00	Ft	
57	WEATHERING	L	4925.00	SqFt	
<b>Sample Number:</b>	576	<b>Type:</b>	R	<b>Area:</b>	5100.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	176.00	Ft	
57	WEATHERING	L	5100.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6220	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011	
<b>Surface:</b>	AAC	<b>Family:</b> C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P	
<b>Area:</b>	638,300 SqFt	<b>Length:</b>	6,383 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	128	<b>Surveyed:</b>	18	
<b>Conditions:</b>	PCI: 86					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	112	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	43.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	117	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	92.00	Ft		
56	SWELLING	L	8.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	123	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
42	BLEEDING	N	1.00	SqFt		
48	L & T CR	L	11.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	132	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	20.00	Ft		
56	SWELLING	L	4.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	136	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
42	BLEEDING	N	1.00	SqFt		
48	L & T CR	L	31.00	Ft		
56	SWELLING	L	9.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	143	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	40.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	149	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	19.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	155	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						

42	BLEEDING	N	20.00	SqFt
48	L & T CR	L	192.00	Ft
56	SWELLING	L	56.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 167	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 83
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	131.00	Ft
56	SWELLING	L	57.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 713	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 89
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	60.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 719	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 90
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	18.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 729	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 92
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	3.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 733	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 90
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	38.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 739	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 89
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	43.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 748	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 91
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	14.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 753	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 85
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	146.00	Ft
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 758	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 62
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	68.00	SqFt
48	L & T CR	L	179.00	Ft
56	SWELLING	L	100.00	SqFt
57	WEATHERING	L	5000.00	SqFt

---

<b>Sample Number:</b> 769	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 78
---------------------------	----------------	--------------	--------------	----------------

**Sample Comments:**

48	L & T CR	L	197.00	Ft
56	SWELLING	L	77.00	SqFt
57	WEATHERING	L	5000.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6222	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011	
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>	
<b>Area:</b>	61,900 SqFt	<b>Length:</b>	619 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Lanes:</b>	0					
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	12	<b>Surveyed:</b>	3	
<b>Conditions:</b>	PCI: 75					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	175	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>PCI:</b>	78					
<b>Sample Comments:</b>						
45	DEPRESSION	L	52.00	SqFt		
48	L & T CR	L	194.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	773	<b>Type:</b>	R	<b>Area:</b>	5025.00 SqFt	
<b>PCI:</b>	69					
<b>Sample Comments:</b>						
48	L & T CR	L	303.00	Ft		
48	L & T CR	M	100.00	Ft		
56	SWELLING	L	86.00	SqFt		
57	WEATHERING	L	5025.00	SqFt		
<b>Sample Number:</b>	775	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>PCI:</b>	80					
<b>Sample Comments:</b>						
48	L & T CR	L	260.00	Ft		
57	WEATHERING	L	5000.00	SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6225	of 10	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	50,200 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	6,733 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4		
<b>Conditions:</b>	PCI: 72						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	378	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	73
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
<b>Sample Number:</b>	380	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
67	LARGE PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
<b>Sample Number:</b>	579	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
67	LARGE PATCH	L	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	581	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	68
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	M	2.00	Slabs			
63	LINEAR CR	L	1.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
67	LARGE PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
70	SCALING	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6230	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	50,200 SqFt	<b>Length:</b>	1,000 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,283 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 82				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	178	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		1.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs
<b>Sample Number:</b>	182	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
75	CORNER SPALL	L		1.00	Slabs
65	JT SEAL DMG	L		20.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs
<b>Sample Number:</b>	778	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		20.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
<b>Sample Number:</b>	781	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		5.00	Slabs
67	LARGE PATCH	L		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs



66	SMALL PATCH	L	4.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 422	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 82
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	1.00	Slabs
66	SMALL PATCH	M	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 425	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 80
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

62	CORNER BREAK	L	1.00	Slabs
66	SMALL PATCH	L	3.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 440	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 75
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	9.00	Slabs
67	LARGE PATCH	L	4.00	Slabs
70	SCALING	L	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 585	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 82
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	2.00	Slabs
70	SCALING	L	2.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 591	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 86
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

73	SHRINKAGE CR	N	20.00	Slabs
----	--------------	---	-------	-------

<b>Sample Number:</b> 593	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 79
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

63	LINEAR CR	L	1.00	Slabs
66	SMALL PATCH	L	3.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 603	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 84
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

74	JOINT SPALL	L	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 609	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 80
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	1.00	Slabs
63	LINEAR CR	L	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 615	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 85
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 618	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 83
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	2.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	1.00	Slabs

<b>Sample Number:</b> 631	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 84
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	2.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs

<b>Sample Number:</b> 635	<b>Type:</b> R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b> 72
---------------------------	----------------	--------------	-------------	----------------

**Sample Comments:**

66	SMALL PATCH	L	3.00	Slabs
67	LARGE PATCH	L	2.00	Slabs
70	SCALING	L	1.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
75	CORNER SPALL	M	1.00	Slabs

---

**Sample Number:** 642      **Type:** R      **Area:** 20.00 Slabs      **PCI:** 75

**Sample Comments:**

66	SMALL PATCH	L	5.00	Slabs
67	LARGE PATCH	L	1.00	Slabs
70	SCALING	L	2.00	Slabs
73	SHRINKAGE CR	N	20.00	Slabs
74	JOINT SPALL	L	1.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18L-36R	<b>Name:</b>	RUNWAY 18L-36R		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6240	of 10	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1959
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	450,000 SqFt		<b>Length:</b>	9,000 Ft	<b>Width:</b>	50 Ft	
<b>Slabs:</b>	2,400	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	56,950 Ft
<b>Shoulder:</b>	<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b> 0		
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Work Date:</b>	1/1/1983	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC		<b>Code:</b>	PA-PCC	<b>Is Major M&amp;R:</b> False
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs		<b>Code:</b>	PA-SP	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	120		<b>Surveyed:</b>	20	
<b>Conditions:</b>	PCI: 85						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	190	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	85
<b>Sample Comments:</b>							
75	CORNER SPALL	L		1.00 Slabs			
73	SHRINKAGE CR	N		17.00 Slabs			
<b>Sample Number:</b>	196	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	86
<b>Sample Comments:</b>							
66	SMALL PATCH	L		1.00 Slabs			
73	SHRINKAGE CR	N		17.00 Slabs			
<b>Sample Number:</b>	200	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	89
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N		14.00 Slabs			
<b>Sample Number:</b>	208	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	88
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N		16.00 Slabs			
<b>Sample Number:</b>	213	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	86
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N		20.00 Slabs			
<b>Sample Number:</b>	217	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	83
<b>Sample Comments:</b>							
66	SMALL PATCH	L		1.00 Slabs			
67	LARGE PATCH	L		1.00 Slabs			
73	SHRINKAGE CR	N		18.00 Slabs			
<b>Sample Number:</b>	226	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	87
<b>Sample Comments:</b>							
66	SMALL PATCH	L		1.00 Slabs			
73	SHRINKAGE CR	N		16.00 Slabs			
<b>Sample Number:</b>	233	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	85
<b>Sample Comments:</b>							
66	SMALL PATCH	L		2.00 Slabs			
73	SHRINKAGE CR	N		18.00 Slabs			
<b>Sample Number:</b>	237	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	83
<b>Sample Comments:</b>							
66	SMALL PATCH	L		2.00 Slabs			

73 SHRINKAGE CR N 20.00 Slabs  
74 JOINT SPALL L 1.00 Slabs

---

**Sample Number:** 241 **Type:** R **Area:** 20.00 Slabs **PCI:** 81

**Sample Comments:**

74 JOINT SPALL L 2.00 Slabs  
66 SMALL PATCH L 2.00 Slabs  
73 SHRINKAGE CR N 20.00 Slabs

---

**Sample Number:** 797 **Type:** R **Area:** 20.00 Slabs **PCI:** 73

**Sample Comments:**

66 SMALL PATCH L 3.00 Slabs  
67 LARGE PATCH L 9.00 Slabs  
73 SHRINKAGE CR N 20.00 Slabs

---

**Sample Number:** 801 **Type:** R **Area:** 20.00 Slabs **PCI:** 96

**Sample Comments:**

73 SHRINKAGE CR N 6.00 Slabs

---

**Sample Number:** 811 **Type:** R **Area:** 20.00 Slabs **PCI:** 80

**Sample Comments:**

66 SMALL PATCH L 1.00 Slabs  
66 SMALL PATCH M 2.00 Slabs  
73 SHRINKAGE CR N 20.00 Slabs

---

**Sample Number:** 821 **Type:** R **Area:** 20.00 Slabs **PCI:** 84

**Sample Comments:**

73 SHRINKAGE CR N 20.00 Slabs  
74 JOINT SPALL L 1.00 Slabs

---

**Sample Number:** 825 **Type:** R **Area:** 20.00 Slabs **PCI:** 86

**Sample Comments:**

73 SHRINKAGE CR N 20.00 Slabs

---

**Sample Number:** 829 **Type:** R **Area:** 20.00 Slabs **PCI:** 89

**Sample Comments:**

73 SHRINKAGE CR N 15.00 Slabs

---

**Sample Number:** 832 **Type:** R **Area:** 20.00 Slabs **PCI:** 86

**Sample Comments:**

73 SHRINKAGE CR N 20.00 Slabs

---

**Sample Number:** 834 **Type:** R **Area:** 20.00 Slabs **PCI:** 86

**Sample Comments:**

73 SHRINKAGE CR N 20.00 Slabs

---

**Sample Number:** 837 **Type:** R **Area:** 20.00 Slabs **PCI:** 80

**Sample Comments:**

63 LINEAR CR L 1.00 Slabs  
66 SMALL PATCH L 1.00 Slabs  
73 SHRINKAGE CR N 20.00 Slabs

---

**Sample Number:** 842 **Type:** R **Area:** 20.00 Slabs **PCI:** 86

**Sample Comments:**

73 SHRINKAGE CR N 20.00 Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6105	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,733 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 79				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	200	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	4.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
<b>Sample Number:</b>	206	<b>Type:</b>	R	<b>Area:</b>	16.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L	2.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
<b>Sample Number:</b>	302	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
75	CORNER SPALL	L	1.00	Slabs	
66	SMALL PATCH	L	3.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	304	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6110	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	1,000 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,283 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 77				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	101	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
66	SMALL PATCH	M	3.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
67	LARGE PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	L	3.00	Slabs	
<b>Sample Number:</b>	104	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	20.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
<b>Sample Number:</b>	401	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	M	2.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	405	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT						
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L		<b>Use:</b>	RUNWAY	<b>Area:</b>		
<b>Section:</b>	6115	of 16	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1986		
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> S		
<b>Area:</b>	542,800 SqFt	<b>Length:</b>	10,856 Ft	<b>Width:</b>	50 Ft				
<b>Slabs:</b>	<b>Slab Length:</b>		Ft	<b>Slab Width:</b>	Ft		<b>Joint Length:</b>		
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0 Lanes: 0				
<b>Section Comments:</b>									
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True			
<b>Work Date:</b>	1/1/1961	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True			
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True			
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True			
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	108	<b>Surveyed:</b>	20				
<b>Conditions:</b>	PCI: 30								
<b>Inspection Comments:</b>									
<b>Sample Number:</b>	212	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 32			
<b>Sample Comments:</b>									
53	RUTTING	L	130.00	SqFt					
43	BLOCK CR	L	4750.00	SqFt					
43	BLOCK CR	M	250.00	SqFt					
52	RAVELING	L	4000.00	SqFt					
52	RAVELING	M	1000.00	SqFt					
56	SWELLING	L	450.00	SqFt					
<b>Sample Number:</b>	216	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 26			
<b>Sample Comments:</b>									
41	ALLIGATOR CR	L	131.00	SqFt					
43	BLOCK CR	L	4621.00	SqFt					
43	BLOCK CR	M	248.00	SqFt					
52	RAVELING	L	4000.00	SqFt					
52	RAVELING	M	1000.00	SqFt					
56	SWELLING	L	1000.00	SqFt					
<b>Sample Number:</b>	221	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 36			
<b>Sample Comments:</b>									
43	BLOCK CR	L	2718.00	SqFt					
50	PATCHING	L	2282.00	SqFt					
52	RAVELING	L	2174.00	SqFt					
52	RAVELING	M	544.00	SqFt					
56	SWELLING	L	1200.00	SqFt					
<b>Sample Number:</b>	229	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 21			
<b>Sample Comments:</b>									
41	ALLIGATOR CR	L	159.00	SqFt					
43	BLOCK CR	L	4341.00	SqFt					
43	BLOCK CR	M	500.00	SqFt					
45	DEPRESSION	L	40.00	SqFt					
52	RAVELING	L	4000.00	SqFt					
52	RAVELING	M	1000.00	SqFt					
53	RUTTING	L	300.00	SqFt					
56	SWELLING	L	1500.00	SqFt					
<b>Sample Number:</b>	235	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 30			
<b>Sample Comments:</b>									
41	ALLIGATOR CR	L	50.00	SqFt					
43	BLOCK CR	L	4950.00	SqFt					
45	DEPRESSION	L	100.00	SqFt					
52	RAVELING	L	4000.00	SqFt					

52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	1300.00	SqFt

<b>Sample Number:</b> 245	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 32
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	142.00	SqFt
43	BLOCK CR	L	4858.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	600.00	SqFt

<b>Sample Number:</b> 249	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 27
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	84.00	SqFt
43	BLOCK CR	L	3316.00	SqFt
43	BLOCK CR	M	1600.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	400.00	SqFt

<b>Sample Number:</b> 251	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 30
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	44.00	SqFt
43	BLOCK CR	L	3956.00	SqFt
43	BLOCK CR	M	1000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	400.00	SqFt

<b>Sample Number:</b> 253	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 28
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	86.00	SqFt
43	BLOCK CR	L	2924.00	SqFt
43	BLOCK CR	M	1990.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt

<b>Sample Number:</b> 308	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 31
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	25.00	SqFt
53	RUTTING	L	140.00	SqFt
43	BLOCK CR	L	4975.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	750.00	SqFt

<b>Sample Number:</b> 313	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 24
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	50.00	SqFt
43	BLOCK CR	L	3950.00	SqFt
43	BLOCK CR	M	1000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
55	SLIPPAGE CR	N	45.00	SqFt
56	SWELLING	L	750.00	SqFt

<b>Sample Number:</b> 318	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 26
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	117.00	SqFt
43	BLOCK CR	L	4383.00	SqFt
43	BLOCK CR	M	500.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
55	SLIPPAGE CR	N	80.00	SqFt
56	SWELLING	L	100.00	SqFt

<b>Sample Number:</b> 326	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 29
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

41	ALLIGATOR CR	L	15.00	SqFt
56	SWELLING	L	350.00	SqFt
43	BLOCK CR	L	4197.00	SqFt
43	BLOCK CR	M	743.00	SqFt
45	DEPRESSION	M	36.00	SqFt
50	PATCHING	L	45.00	SqFt
52	RAVELING	L	3964.00	SqFt
52	RAVELING	M	991.00	SqFt

---

**Sample Number:** 331      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 25

**Sample Comments:**

41	ALLIGATOR CR	L	40.00	SqFt
43	BLOCK CR	L	3667.00	SqFt
43	BLOCK CR	M	193.00	SqFt
45	DEPRESSION	L	24.00	SqFt
50	PATCHING	M	1100.00	SqFt
52	RAVELING	L	2950.00	SqFt
52	RAVELING	M	950.00	SqFt
56	SWELLING	L	146.00	SqFt

---

**Sample Number:** 333      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 36

**Sample Comments:**

43	BLOCK CR	L	4500.00	SqFt
43	BLOCK CR	M	500.00	SqFt
45	DEPRESSION	M	14.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	100.00	SqFt

---

**Sample Number:** 338      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 40

**Sample Comments:**

43	BLOCK CR	L	4500.00	SqFt
43	BLOCK CR	M	500.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	80.00	SqFt

---

**Sample Number:** 344      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 41

**Sample Comments:**

41	ALLIGATOR CR	L	61.00	SqFt
43	BLOCK CR	L	4939.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt

---

**Sample Number:** 348      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 35

**Sample Comments:**

41	ALLIGATOR CR	L	125.00	SqFt
43	BLOCK CR	L	4875.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	300.00	SqFt

---

**Sample Number:** 363      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 29

**Sample Comments:**

41	ALLIGATOR CR	L	70.00	SqFt
43	BLOCK CR	L	3430.00	SqFt
43	BLOCK CR	M	1500.00	SqFt
52	RAVELING	L	3750.00	SqFt
52	RAVELING	M	1250.00	SqFt

---

**Sample Number:** 369      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 28

**Sample Comments:**

41	ALLIGATOR CR	L	80.00	SqFt
42	BLEEDING	N	25.00	SqFt
43	BLOCK CR	L	2920.00	SqFt
43	BLOCK CR	M	2000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6120	of 16	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1986
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	542,800 SqFt	<b>Length:</b>	5,428 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1961	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	108	<b>Surveyed:</b>	20		
<b>Conditions:</b>	PCI: 33						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	109	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	26
<b>Sample Comments:</b>							
43	BLOCK CR	L	2924.00	SqFt			
43	BLOCK CR	M	960.00	SqFt			
48	L & T CR	L	200.00	Ft			
48	L & T CR	M	22.00	Ft			
52	RAVELING	L	4000.00	SqFt			
52	RAVELING	M	1000.00	SqFt			
56	SWELLING	L	1500.00	SqFt			
<b>Sample Number:</b>	116	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	23
<b>Sample Comments:</b>							
45	DEPRESSION	L	20.00	SqFt			
43	BLOCK CR	L	2500.00	SqFt			
43	BLOCK CR	M	1000.00	SqFt			
48	L & T CR	L	216.00	Ft			
48	L & T CR	M	50.00	Ft			
52	RAVELING	L	4000.00	SqFt			
52	RAVELING	M	1000.00	SqFt			
56	SWELLING	L	2100.00	SqFt			
<b>Sample Number:</b>	120	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	30
<b>Sample Comments:</b>							
43	BLOCK CR	L	4492.00	SqFt			
43	BLOCK CR	M	499.00	SqFt			
50	PATCHING	L	9.00	SqFt			
52	RAVELING	L	3993.00	SqFt			
52	RAVELING	M	998.00	SqFt			
56	SWELLING	L	1500.00	SqFt			
<b>Sample Number:</b>	129	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	33
<b>Sample Comments:</b>							
43	BLOCK CR	L	1600.00	SqFt			
48	L & T CR	L	300.00	Ft			
48	L & T CR	M	60.00	Ft			
52	RAVELING	L	4000.00	SqFt			
52	RAVELING	M	1000.00	SqFt			
56	SWELLING	L	1800.00	SqFt			
<b>Sample Number:</b>	135	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	32
<b>Sample Comments:</b>							
43	BLOCK CR	M	200.00	SqFt			
43	BLOCK CR	L	4800.00	SqFt			

52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	1600.00	SqFt

<b>Sample Number:</b> 149	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 26
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

43	BLOCK CR	L	2864.00	SqFt
43	BLOCK CR	M	800.00	SqFt
48	L & T CR	L	100.00	Ft
48	L & T CR	M	72.00	Ft
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	1700.00	SqFt

<b>Sample Number:</b> 155	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 31
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

43	BLOCK CR	L	3160.00	SqFt
43	BLOCK CR	M	500.00	SqFt
48	L & T CR	L	17.00	Ft
48	L & T CR	M	100.00	Ft
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	800.00	SqFt

<b>Sample Number:</b> 164	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 30
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

56	SWELLING	L	100.00	SqFt
45	DEPRESSION	L	150.00	SqFt
43	BLOCK CR	L	3000.00	SqFt
43	BLOCK CR	M	2000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt

<b>Sample Number:</b> 169	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 29
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

43	BLOCK CR	L	3000.00	SqFt
43	BLOCK CR	M	2000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	1000.00	SqFt

<b>Sample Number:</b> 410	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 32
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

43	BLOCK CR	L	3000.00	SqFt
45	DEPRESSION	L	84.00	SqFt
48	L & T CR	L	250.00	Ft
48	L & T CR	M	24.00	Ft
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	993.00	SqFt

<b>Sample Number:</b> 415	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 36
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

43	BLOCK CR	L	2700.00	SqFt
43	BLOCK CR	M	300.00	SqFt
48	L & T CR	L	274.00	Ft
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	294.00	SqFt

<b>Sample Number:</b> 419	<b>Type:</b> R	<b>Area:</b>	5000.00	SqFt	<b>PCI:</b> 38
---------------------------	----------------	--------------	---------	------	----------------

**Sample Comments:**

43	BLOCK CR	L	3000.00	SqFt
48	L & T CR	L	274.00	Ft
48	L & T CR	M	83.00	Ft
52	RAVELING	L	3750.00	SqFt
52	RAVELING	M	1250.00	SqFt
56	SWELLING	L	100.00	SqFt

**Sample Number:** 421      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 40

**Sample Comments:**

48	L & T CR	L	481.00	Ft
48	L & T CR	M	103.00	Ft
50	PATCHING	L	2175.00	SqFt
52	RAVELING	L	2119.00	SqFt
52	RAVELING	M	706.00	SqFt
56	SWELLING	L	227.00	SqFt

---

**Sample Number:** 427      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 30

**Sample Comments:**

43	BLOCK CR	L	1900.00	SqFt
45	DEPRESSION	L	114.00	SqFt
48	L & T CR	L	540.00	Ft
48	L & T CR	M	156.00	Ft
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	352.00	SqFt

---

**Sample Number:** 432      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 35

**Sample Comments:**

43	BLOCK CR	L	2874.00	SqFt
48	L & T CR	L	100.00	Ft
48	L & T CR	M	50.00	Ft
50	PATCHING	M	350.00	SqFt
52	RAVELING	L	3910.00	SqFt
52	RAVELING	M	740.00	SqFt
56	SWELLING	L	232.00	SqFt

---

**Sample Number:** 438      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 31

**Sample Comments:**

43	BLOCK CR	L	1151.00	SqFt
43	BLOCK CR	M	800.00	SqFt
48	L & T CR	L	276.00	Ft
48	L & T CR	M	162.00	Ft
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	150.00	SqFt

---

**Sample Number:** 446      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 41

**Sample Comments:**

43	BLOCK CR	L	5000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	400.00	SqFt

---

**Sample Number:** 451      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 41

**Sample Comments:**

43	BLOCK CR	L	5000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	250.00	SqFt

---

**Sample Number:** 454      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 41

**Sample Comments:**

43	BLOCK CR	L	5000.00	SqFt
52	RAVELING	L	3750.00	SqFt
52	RAVELING	M	1250.00	SqFt
56	SWELLING	L	75.00	SqFt

---

**Sample Number:** 467      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 33

**Sample Comments:**

43	BLOCK CR	L	3500.00	SqFt
43	BLOCK CR	M	1500.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	400.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6125	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1986
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	30,000 SqFt	<b>Length:</b>	300 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	160	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 4,000 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	3
<b>Conditions:</b> PCI: 74					
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	277	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	H	20.00	Slabs	
66	SMALL PATCH	L	3.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	5.00	Slabs	
74	JOINT SPALL	L	4.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	374	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	H	20.00	Slabs	
66	SMALL PATCH	L	6.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	10.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	376	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
74	JOINT SPALL	L	2.00	Slabs	
75	CORNER SPALL	L	2.00	Slabs	
65	JT SEAL DMG	H	20.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6130	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1986
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	30,000 SqFt	<b>Length:</b>	600 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	160	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 3,750 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 88				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	175	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG		H	20.00	Slabs
<b>Sample Number:</b>	474	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG		M	20.00	Slabs
75	CORNER SPALL		L	2.00	Slabs
<b>Sample Number:</b>	476	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG		H	20.00	Slabs
66	SMALL PATCH		L	1.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6135	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,733 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	5
<b>Conditions:</b>	PCI: 74				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	281	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	5.00	Slabs	
66	SMALL PATCH	M	3.00	Slabs	
71	FAULTING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	283	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
74	JOINT SPALL	L	1.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
<b>Sample Number:</b>	378	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
66	SMALL PATCH	L	5.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
66	SMALL PATCH	H	4.00	Slabs	
67	LARGE PATCH	H	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	379	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
66	SMALL PATCH	L	6.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	382	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6140	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	1,000 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,283 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 84				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	180	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR		N	16.00	Slabs
<b>Sample Number:</b>	184	<b>Type:</b>	R	<b>Area:</b>	16.00 Slabs
<b>Sample Comments:</b>					
75	CORNER SPALL		L	1.00	Slabs
66	SMALL PATCH		L	2.00	Slabs
73	SHRINKAGE CR		N	16.00	Slabs
74	JOINT SPALL		L	1.00	Slabs
75	CORNER SPALL		M	1.00	Slabs
<b>Sample Number:</b>	479	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG		L	20.00	Slabs
73	SHRINKAGE CR		N	6.00	Slabs
<b>Sample Number:</b>	482	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH		M	2.00	Slabs
73	SHRINKAGE CR		N	20.00	Slabs
74	JOINT SPALL		M	1.00	Slabs
66	SMALL PATCH		L	1.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6145	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	26,000 SqFt	<b>Length:</b>	260 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC	<b>Code:</b>	OL-AC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI:	91			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	222	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	76.00	Ft	
57	WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b>	323	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L	5000.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6150	of 16	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	26,000 SqFt	<b>Length:</b>	520 Ft	<b>Width:</b>	50 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC		<b>Code:</b>	OL-AC	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 93						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	123	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	94
<b>Sample Comments:</b>							
57	WEATHERING		L	5000.00	SqFt		
<b>Sample Number:</b>	422	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	92
<b>Sample Comments:</b>							
48	L & T CR		L	1.00	Ft		
57	WEATHERING		L	5000.00	SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6155	of 16	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	30,000 SqFt	<b>Length:</b>	300 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC		<b>Code:</b>	OL-AC	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI:	89					
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	240	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	89
<b>Sample Comments:</b>							
48	L & T CR	L		80.00 Ft			
57	WEATHERING	L		5000.00 SqFt			
<b>Sample Number:</b>	342	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	90
<b>Sample Comments:</b>							
48	L & T CR	L		19.00 Ft			
57	WEATHERING	L		5000.00 SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6160	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011	
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>	
<b>Area:</b>	30,000 SqFt	<b>Length:</b>	600 Ft	<b>Width:</b>	50 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN	
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC	<b>Code:</b>	OL-AC	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2	
<b>Conditions:</b>	PCI: 88					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	141	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	81.00	Ft		
56	SWELLING	L	9.00	SqFt		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	441	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	63.00	Ft		
57	WEATHERING	L	5000.00	SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6165	of 16	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	31,200 SqFt	<b>Length:</b>	312 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC		<b>Code:</b>	OL-AC	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 87						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	260	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	88
<b>Sample Comments:</b>							
48	L & T CR	L		92.00 Ft			
57	WEATHERING	L		5000.00 SqFt			
<b>Sample Number:</b>	360	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	86
<b>Sample Comments:</b>							
48	L & T CR	L		131.00 Ft			
57	WEATHERING	L		5000.00 SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6170	of 16	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	31,200 SqFt	<b>Length:</b>	156 Ft	<b>Width:</b>	200 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC		<b>Code:</b>	OL-AC	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 88						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	160	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	87
<b>Sample Comments:</b>							
48	L & T CR	L		104.00 Ft			
57	WEATHERING	L		5000.00 SqFt			
<b>Sample Number:</b>	459	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	89
<b>Sample Comments:</b>							
48	L & T CR	L		55.00 Ft			
57	WEATHERING	L		5000.00 SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6175	of 16	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	20,400 SqFt	<b>Length:</b>	408 Ft	<b>Width:</b>	50 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC		<b>Code:</b>	OL-AC	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 74						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	270	<b>Type:</b>	R	<b>Area:</b>	5125.00 SqFt	<b>PCI:</b>	74
<b>Sample Comments:</b>							
48	L & T CR	L	393.00	Ft			
56	SWELLING	L	13.00	SqFt			
57	WEATHERING	L	5125.00	SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 18R-36L	<b>Name:</b>	RUNWAY 18R-36L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6180	of 16	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	20,400 SqFt	<b>Length:</b>	204 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC	<b>Code:</b>	OL-AC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 88				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	470	<b>Type:</b>	R	<b>Area:</b>	5125.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L		102.00 Ft	
57	WEATHERING	L		5125.00 SqFt	
<b>Sample Number:</b>	473	<b>Type:</b>	R	<b>Area:</b>	5075.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L		56.00 Ft	
57	WEATHERING	L		5075.00 SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6405	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> T
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,733 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1982	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 81				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	301	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b> Repairs done					
66	SMALL PATCH	L	3.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	304	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	500	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	4.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	503	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
70	SCALING	M	1.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6410	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	1,000 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,283 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1982	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 77				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	100	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	105	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	M	20.00	Slabs	
66	SMALL PATCH	L	3.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
71	FAULTING	L	2.00	Slabs	
<b>Sample Number:</b>	702	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	705	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
71	FAULTING	L	1.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6414	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	56,500 SqFt	<b>Length:</b>	200 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1990	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2006	<b>Work Type:</b>	Mill and Overlay	<b>Code:</b>	ML-OL
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	12	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 51				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	310	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	998.00	Ft	
48	L & T CR	M	68.00	Ft	
52	RAVELING	L	20.00	SqFt	
57	WEATHERING	L	4980.00	SqFt	
41	ALLIGATOR CR	L	50.00	SqFt	
<b>Sample Number:</b>	508	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	640.00	Ft	
52	RAVELING	L	15.00	SqFt	
56	SWELLING	L	110.00	SqFt	
57	WEATHERING	L	4985.00	SqFt	
41	ALLIGATOR CR	L	25.00	SqFt	
<b>Sample Number:</b>	511	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	715.00	Ft	
52	RAVELING	L	173.00	SqFt	
57	WEATHERING	L	4827.00	SqFt	
41	ALLIGATOR CR	L	160.00	SqFt	
48	L & T CR	M	100.00	Ft	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6415	of 10	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1986
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	283,572 SqFt	<b>Length:</b>	2,835 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1977	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	56	<b>Surveyed:</b>	12		
<b>Conditions:</b>	PCI: 27						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	315	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	33
<b>Sample Comments:</b>							
43	BLOCK CR	L	4410.00	SqFt			
43	BLOCK CR	M	490.00	SqFt			
50	PATCHING	M	100.00	SqFt			
52	RAVELING	L	3675.00	SqFt			
52	RAVELING	M	1225.00	SqFt			
56	SWELLING	L	380.00	SqFt			
<b>Sample Number:</b>	319	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	33
<b>Sample Comments:</b>							
43	BLOCK CR	L	4327.00	SqFt			
43	BLOCK CR	M	481.00	SqFt			
50	PATCHING	L	42.00	SqFt			
50	PATCHING	M	150.00	SqFt			
52	RAVELING	L	3606.00	SqFt			
52	RAVELING	M	1202.00	SqFt			
56	SWELLING	L	172.00	SqFt			
<b>Sample Number:</b>	324	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	23
<b>Sample Comments:</b>							
41	ALLIGATOR CR	L	82.00	SqFt			
43	BLOCK CR	L	2414.00	SqFt			
43	BLOCK CR	M	268.00	SqFt			
50	PATCHING	M	2236.00	SqFt			
52	RAVELING	L	2211.00	SqFt			
52	RAVELING	M	553.00	SqFt			
56	SWELLING	L	36.00	SqFt			
<b>Sample Number:</b>	328	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	31
<b>Sample Comments:</b>							
43	BLOCK CR	L	1225.00	SqFt			
43	BLOCK CR	M	2160.00	SqFt			
50	PATCHING	L	1785.00	SqFt			
52	RAVELING	L	2535.00	SqFt			
52	RAVELING	M	640.00	SqFt			
52	RAVELING	H	40.00	SqFt			
<b>Sample Number:</b>	335	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	32
<b>Sample Comments:</b>							
43	BLOCK CR	L	2575.00	SqFt			
48	L & T CR	L	283.00	Ft			
48	L & T CR	M	96.00	Ft			

52	RAVELING	L	4500.00	SqFt
52	RAVELING	M	500.00	SqFt
56	SWELLING	L	260.00	SqFt
41	ALLIGATOR CR	L	70.00	SqFt

---

**Sample Number:** 341      **Type:** R      **Area:** 5000.05 SqFt      **PCI:** 15

**Sample Comments:**

41	ALLIGATOR CR	L	74.00	SqFt
43	BLOCK CR	L	4433.00	SqFt
43	BLOCK CR	M	493.00	SqFt
45	DEPRESSION	L	6.00	SqFt
52	RAVELING	M	488.00	SqFt
52	RAVELING	H	124.00	SqFt
53	RUTTING	M	60.00	SqFt
52	RAVELING	L	4388.00	SqFt
56	SWELLING	L	10.00	SqFt

---

**Sample Number:** 518      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 24

**Sample Comments:**

43	BLOCK CR	L	4025.00	SqFt
43	BLOCK CR	M	447.00	SqFt
50	PATCHING	M	528.00	SqFt
52	RAVELING	L	3354.00	SqFt
52	RAVELING	M	1118.00	SqFt
56	SWELLING	L	1500.00	SqFt

---

**Sample Number:** 527      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 28

**Sample Comments:**

43	BLOCK CR	L	3750.00	SqFt
43	BLOCK CR	M	1250.00	SqFt
52	RAVELING	L	3750.00	SqFt
52	RAVELING	M	1250.00	SqFt
56	SWELLING	L	1200.00	SqFt

---

**Sample Number:** 531      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 25

**Sample Comments:**

41	ALLIGATOR CR	L	98.00	SqFt
43	BLOCK CR	L	3922.00	SqFt
43	BLOCK CR	M	980.00	SqFt
45	DEPRESSION	L	4.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	800.00	SqFt

---

**Sample Number:** 533      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 27

**Sample Comments:**

41	ALLIGATOR CR	L	128.00	SqFt
43	BLOCK CR	L	4378.00	SqFt
43	BLOCK CR	M	494.00	SqFt
45	DEPRESSION	L	35.00	SqFt
52	RAVELING	L	3998.00	SqFt
52	RAVELING	M	1000.00	SqFt
52	RAVELING	H	2.00	SqFt

---

**Sample Number:** 538      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 29

**Sample Comments:**

41	ALLIGATOR CR	L	155.00	SqFt
42	BLEEDING	N	1.00	SqFt
43	BLOCK CR	L	3876.00	SqFt
43	BLOCK CR	M	969.00	SqFt
45	DEPRESSION	L	8.00	SqFt
52	RAVELING	L	4500.00	SqFt
52	RAVELING	M	500.00	SqFt
56	SWELLING	L	100.00	SqFt

---

**Sample Number:** 540      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 30

**Sample Comments:**

41	ALLIGATOR CR	L	182.00	SqFt
----	--------------	---	--------	------

43	BLOCK CR	L	3854.00	SqFt
43	BLOCK CR	M	964.00	SqFt
52	RAVELING	L	4500.00	SqFt
52	RAVELING	M	500.00	SqFt
56	SWELLING	L	10.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6417	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2006	
<b>Surface:</b>	AAC	<b>Family:</b> C9N59-GA-RW-AAC-APC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> S	
<b>Area:</b>	28,250 SqFt	<b>Length:</b>	565 Ft	<b>Width:</b>	50 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1977	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/2006	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2	
<b>Conditions:</b>	PCI: 59					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	211	<b>Type:</b>	R	<b>Area:</b>	4125.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	939.00	Ft		
56	SWELLING	L	39.00	SqFt		
57	WEATHERING	L	4125.00	SqFt		
<b>Sample Number:</b>	607	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	705.00	Ft		
48	L & T CR	M	24.00	Ft		
52	RAVELING	L	50.00	SqFt		
57	WEATHERING	L	4950.00	SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6420	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1986	
<b>Surface:</b>	AAC	<b>Family:</b> C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> S	
<b>Area:</b>	311,822 SqFt	<b>Length:</b>	3,400 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Lanes:</b>	0					
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1977	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	62	<b>Surveyed:</b>	13	
<b>Conditions:</b>	PCI: 33					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	107	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>PCI:</b>	34					
<b>Sample Comments:</b>						
43	BLOCK CR	L	750.00	SqFt		
43	BLOCK CR	M	825.00	SqFt		
48	L & T CR	L	208.00	Ft		
48	L & T CR	M	162.00	Ft		
52	RAVELING	L	4250.00	SqFt		
52	RAVELING	M	750.00	SqFt		
56	SWELLING	L	78.00	SqFt		
<b>Sample Number:</b>	116	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>PCI:</b>	41					
<b>Sample Comments:</b>						
43	BLOCK CR	L	5000.00	SqFt		
45	DEPRESSION	L	13.00	SqFt		
52	RAVELING	L	4000.00	SqFt		
52	RAVELING	M	1000.00	SqFt		
56	SWELLING	L	120.00	SqFt		
<b>Sample Number:</b>	126	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>PCI:</b>	35					
<b>Sample Comments:</b>						
43	BLOCK CR	L	4000.00	SqFt		
43	BLOCK CR	M	1000.00	SqFt		
45	DEPRESSION	L	26.00	SqFt		
52	RAVELING	L	4000.00	SqFt		
52	RAVELING	M	1000.00	SqFt		
56	SWELLING	L	189.00	SqFt		
<b>Sample Number:</b>	131	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>PCI:</b>	35					
<b>Sample Comments:</b>						
43	BLOCK CR	L	4812.00	SqFt		
43	BLOCK CR	M	188.00	SqFt		
45	DEPRESSION	L	21.00	SqFt		
52	RAVELING	L	3500.00	SqFt		
52	RAVELING	M	1500.00	SqFt		
56	SWELLING	L	107.00	SqFt		
<b>Sample Number:</b>	135	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>PCI:</b>	30					
<b>Sample Comments:</b>						
43	BLOCK CR	L	1250.00	SqFt		
43	BLOCK CR	M	1250.00	SqFt		
45	DEPRESSION	L	23.00	SqFt		
45	DEPRESSION	M	12.00	SqFt		
48	L & T CR	L	26.00	Ft		

48	L & T CR	M	269.00	Ft
50	PATCHING	M	7.00	SqFt
52	RAVELING	L	4494.00	SqFt
52	RAVELING	M	499.00	SqFt
56	SWELLING	L	83.00	SqFt

**Sample Number:** 140      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 34

**Sample Comments:**

43	BLOCK CR	L	4000.00	SqFt
43	BLOCK CR	M	1000.00	SqFt
52	RAVELING	L	3750.00	SqFt
52	RAVELING	M	1250.00	SqFt
56	SWELLING	L	400.00	SqFt

**Sample Number:** 709      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 44

**Sample Comments:**

43	BLOCK CR	L	550.00	SqFt
48	L & T CR	L	418.00	Ft
48	L & T CR	M	22.00	Ft
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	100.00	SqFt

**Sample Number:** 717      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 36

**Sample Comments:**

50	PATCHING	L	35.00	SqFt
56	SWELLING	L	1000.00	SqFt
43	BLOCK CR	M	710.00	SqFt
48	L & T CR	L	354.00	Ft
52	RAVELING	L	3715.00	SqFt
52	RAVELING	M	1250.00	SqFt

**Sample Number:** 724      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 26

**Sample Comments:**

43	BLOCK CR	L	2000.00	SqFt
43	BLOCK CR	M	500.00	SqFt
48	L & T CR	L	103.00	Ft
48	L & T CR	M	237.00	Ft
50	PATCHING	L	9.00	SqFt
52	RAVELING	L	3992.00	SqFt
52	RAVELING	M	999.00	SqFt
56	SWELLING	L	1100.00	SqFt

**Sample Number:** 729      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 30

**Sample Comments:**

43	BLOCK CR	L	4250.00	SqFt
43	BLOCK CR	M	750.00	SqFt
52	RAVELING	L	3977.00	SqFt
52	RAVELING	M	994.00	SqFt
52	RAVELING	H	29.00	SqFt
56	SWELLING	L	900.00	SqFt

**Sample Number:** 735      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 31

**Sample Comments:**

43	BLOCK CR	M	1000.00	SqFt
43	BLOCK CR	L	4000.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	900.00	SqFt

**Sample Number:** 739      **Type:** R      **Area:** 5000.00 SqFt      **PCI:** 33

**Sample Comments:**

43	BLOCK CR	L	4500.00	SqFt
43	BLOCK CR	M	500.00	SqFt
52	RAVELING	L	4000.00	SqFt
52	RAVELING	M	1000.00	SqFt
56	SWELLING	L	900.00	SqFt

**Sample Number:** 743

**Type:** R

**Area:**

6886.00 SqFt

**PCI:** 26

**Sample Comments:**

56	SWELLING	L	1200.00	SqFt
43	BLOCK CR	L	2070.00	SqFt
43	BLOCK CR	M	3105.00	SqFt
48	L & T CR	L	210.00	Ft
48	L & T CR	M	60.00	Ft
52	RAVELING	L	5164.00	SqFt
52	RAVELING	M	1722.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY	<b>Area:</b>	887,544 SqFt
<b>Section:</b>	6425	of 10	<b>From:</b> -		To: -		<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	33,700 SqFt	<b>Length:</b>	337 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b> 0	
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	New Construction - AC	<b>Code:</b>	NC-AC	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 88						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	322	<b>Type:</b>	R	<b>Area:</b>	6850.00 SqFt	<b>PCI:</b>	89
<b>Sample Comments:</b>							
48	L & T CR	L		58.00 Ft			
57	WEATHERING	L		6850.00 SqFt			
<b>Sample Number:</b>	521	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	87
<b>Sample Comments:</b>							
48	L & T CR	L		118.00 Ft			
57	WEATHERING	L		5000.00 SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY	<b>Area:</b>	887,544 SqFt
<b>Section:</b>	6430	of 10	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	33,700 SqFt	<b>Length:</b>	337 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b> 0	
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	New Construction - AC	<b>Code:</b>	NC-AC	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 91						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	120	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	90
<b>Sample Comments:</b>							
48	L & T CR	L		24.00 Ft			
57	WEATHERING	L		5000.00 SqFt			
<b>Sample Number:</b>	722	<b>Type:</b>	R	<b>Area:</b>	6850.00 SqFt	<b>PCI:</b>	92
<b>Sample Comments:</b>							
48	L & T CR	L		3.00 Ft			
57	WEATHERING	L		6850.00 SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6435	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	20,000 SqFt	<b>Length:</b>	275 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	New Construction - AC	<b>Code:</b>	NC-AC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 92				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	344	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L		5000.00	SqFt
<b>Sample Number:</b>	545	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L		67.00	Ft
57	WEATHERING	L		5000.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9L-27R	<b>Name:</b>	RUNWAY 9L-27R	<b>Use:</b>	RUNWAY
<b>Section:</b>	6440	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	20,000 SqFt	<b>Length:</b>	550 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	New Construction - AC	<b>Code:</b>	NC-AC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 88				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	144	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L		5000.00 SqFt	
<b>Sample Number:</b>	745	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L		41.00 Ft	
52	RAVELING	L		305.00 SqFt	
57	WEATHERING	L		4695.00 SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6305	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,733 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 76				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	300	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	302	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	4.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
<b>Sample Number:</b>	305	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	4.00	Slabs	
<b>Sample Number:</b>	504	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6310	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	48,500 SqFt	<b>Length:</b>	1,000 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,283 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 79				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	101	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	4.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
70	SCALING	L	6.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	104	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	700	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	3.00	Slabs	
<b>Sample Number:</b>	705	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
75	CORNER SPALL	L	2.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6315	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2010	
<b>Surface:</b>	AAC	<b>Family:</b> C9N59-GA-RW-AAC-APC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P	
<b>Area:</b>	603,300 SqFt	<b>Length:</b>	6,230 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	120	<b>Surveyed:</b>	20	
<b>Conditions:</b>	PCI: 76					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	309	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	464.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	315	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	289.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	322	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	333.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	328	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	439.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	334	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	246.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	340	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	418.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
45	DEPRESSION	L	3.00	SqFt		
<b>Sample Number:</b>	346	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	469.00	Ft		
57	WEATHERING	L	5000.00	SqFt		
<b>Sample Number:</b>	356	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	672.00	Ft		
57	WEATHERING	L	5000.00	SqFt		

<b>Sample Number:</b> 364	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 78
<b>Sample Comments:</b>				
48 L & T CR	L	313.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 368				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 81
<b>Sample Comments:</b>				
48 L & T CR	L	225.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 507				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 78
<b>Sample Comments:</b>				
48 L & T CR	L	302.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 512				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 74
<b>Sample Comments:</b>				
48 L & T CR	L	334.00	Ft	
52 RAVELING	L	50.00	SqFt	
57 WEATHERING	L	4950.00	SqFt	
<b>Sample Number:</b> 518				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 83
<b>Sample Comments:</b>				
48 L & T CR	L	182.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 525				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 76
<b>Sample Comments:</b>				
48 L & T CR	L	368.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 531				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 79
<b>Sample Comments:</b>				
48 L & T CR	L	283.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 537				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 76
<b>Sample Comments:</b>				
48 L & T CR	L	365.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 543				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 70
<b>Sample Comments:</b>				
48 L & T CR	L	561.00	Ft	
57 WEATHERING	L	5000.00	SqFt	
<b>Sample Number:</b> 553				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 83
<b>Sample Comments:</b>				
48 L & T CR	L	129.00	Ft	
52 RAVELING	L	50.00	SqFt	
57 WEATHERING	L	4950.00	SqFt	
<b>Sample Number:</b> 559				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 69
<b>Sample Comments:</b>				
48 L & T CR	L	457.00	Ft	
52 RAVELING	L	100.00	SqFt	
57 WEATHERING	L	4900.00	SqFt	
<b>Sample Number:</b> 566				
	<b>Type:</b> R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 86
<b>Sample Comments:</b>				
48 L & T CR	L	135.00	Ft	
57 WEATHERING	L	5000.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6317	of 10	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	20,000 SqFt	<b>Length:</b>	200 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC		<b>Code:</b>	OL-AC	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 76						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	351	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	76
<b>Sample Comments:</b>							
48	L & T CR	L	325.00	Ft			
56	SWELLING	L	10.00	SqFt			
57	WEATHERING	L	5000.00	SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L	<b>Use:</b>	RUNWAY	
<b>Section:</b>	6320	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2010	
<b>Surface:</b>	AAC	<b>Family:</b> C9N59-GA-RW-AAC-APC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P	
<b>Area:</b>	585,202 SqFt	<b>Length:</b>	5,850 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	120	<b>Surveyed:</b>	20	
<b>Conditions:</b>	PCI: 84					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	107	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	42.00	Ft		
57	WEATHERING	L	4850.00	SqFt		
<b>Sample Number:</b>	110	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	142.00	Ft		
57	WEATHERING	L	4850.00	SqFt		
<b>Sample Number:</b>	114	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	225.00	Ft		
57	WEATHERING	L	4850.00	SqFt		
<b>Sample Number:</b>	123	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	143.00	Ft		
57	WEATHERING	L	4850.00	SqFt		
<b>Sample Number:</b>	132	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	24.00	Ft		
57	WEATHERING	L	4850.00	SqFt		
<b>Sample Number:</b>	137	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	118.00	Ft		
57	WEATHERING	L	4850.00	SqFt		
<b>Sample Number:</b>	142	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	
<b>Sample Comments:</b>						
42	BLEEDING	N	1.00	SqFt		
48	L & T CR	L	242.00	Ft		
52	RAVELING	L	1.00	SqFt		
57	WEATHERING	L	4849.00	SqFt		
<b>Sample Number:</b>	149	<b>Type:</b>	R	<b>Area:</b>	4861.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	309.00	Ft		
57	WEATHERING	L	4861.00	SqFt		

<b>Sample Number:</b> 154	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 87
<b>Sample Comments:</b>					
45 DEPRESSION		L	25.00	SqFt	
48 L & T CR		L	23.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 160	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 89
<b>Sample Comments:</b>					
48 L & T CR		L	67.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 165	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 89
<b>Sample Comments:</b>					
48 L & T CR		L	53.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 709	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 82
<b>Sample Comments:</b>					
48 L & T CR		L	199.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 718	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 81
<b>Sample Comments:</b>					
48 L & T CR		L	229.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 727	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 77
<b>Sample Comments:</b>					
48 L & T CR		L	321.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 737	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 86
<b>Sample Comments:</b>					
48 L & T CR		L	128.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 741	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 74
<b>Sample Comments:</b>					
48 L & T CR		L	394.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 745	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 82
<b>Sample Comments:</b>					
48 L & T CR		L	214.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 752	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 85
<b>Sample Comments:</b>					
48 L & T CR		L	118.00	Ft	
56 SWELLING		L	15.00	SqFt	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 761	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 85
<b>Sample Comments:</b>					
48 L & T CR		L	137.00	Ft	
57 WEATHERING		L	4850.00	SqFt	
<b>Sample Number:</b> 766	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b> 90
<b>Sample Comments:</b>					
48 L & T CR		L	24.00	Ft	
57 WEATHERING		L	4850.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6322	of 10	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2011
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-RW-AAC- APC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> S
<b>Area:</b>	19,400 SqFt	<b>Length:</b>	200 Ft	<b>Width:</b>	97 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Overlay - AC		<b>Code:</b>	OL-AC	<b>Is Major M&amp;R:</b> True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 71						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	750	<b>Type:</b>	R	<b>Area:</b>	4850.00 SqFt	<b>PCI:</b>	71
<b>Sample Comments:</b>							
45	DEPRESSION	L	225.00	SqFt			
48	L & T CR	L	72.00	Ft			
57	WEATHERING	L	4850.00	SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6325	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1992
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	57,000 SqFt	<b>Length:</b>	570 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	304	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 7,690 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1992	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	16	<b>Surveyed:</b>	5
<b>Conditions:</b>	PCI: 89				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	371	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L	2.00	Slabs	
73	SHRINKAGE CR	N	6.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
74	JOINT SPALL	L	8.00	Slabs	
<b>Sample Number:</b>	374	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L	2.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
73	SHRINKAGE CR	N	3.00	Slabs	
<b>Sample Number:</b>	377	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	4.00	Slabs	
<b>Sample Number:</b>	572	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	11.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	
<b>Sample Number:</b>	575	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L	4.00	Slabs	
73	SHRINKAGE CR	N	10.00	Slabs	
66	SMALL PATCH	L	3.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6330	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1992
<b>Surface:</b>	PCC	<b>Family:</b> C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	55,290 SqFt	<b>Length:</b>	1,140 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>	304	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 7,170 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1992	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	16	<b>Surveyed:</b>	5
<b>Conditions:</b>	PCI: 89				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	173	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		5.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
<b>Sample Number:</b>	175	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		11.00	Slabs
75	CORNER SPALL	L		5.00	Slabs
<b>Sample Number:</b>	177	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		10.00	Slabs
<b>Sample Number:</b>	772	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L		1.00	Slabs
73	SHRINKAGE CR	N		10.00	Slabs
66	SMALL PATCH	L		2.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
75	CORNER SPALL	L		1.00	Slabs
<b>Sample Number:</b>	776	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
70	SCALING	L		1.00	Slabs
66	SMALL PATCH	L		1.00	Slabs
74	JOINT SPALL	L		4.00	Slabs
73	SHRINKAGE CR	N		10.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L	<b>Use:</b>	RUNWAY
<b>Section:</b>	6335	of 10	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	50,000 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 6,733 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 78				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	380	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	12.00	Slabs	
<b>Sample Number:</b>	382	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
67	LARGE PATCH	L	2.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	19.00	Slabs	
<b>Sample Number:</b>	384	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	6.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
67	LARGE PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	4.00	Slabs	
74	JOINT SPALL	M	2.00	Slabs	
<b>Sample Number:</b>	583	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	17.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	RW 9R-27L	<b>Name:</b>	RUNWAY 9R-27L		<b>Use:</b>	RUNWAY	<b>Area:</b>
<b>Section:</b>	6340	of 10	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	48,500 SqFt	<b>Length:</b>	1,000 Ft	<b>Width:</b>	50 Ft		
<b>Slabs:</b>	267	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	6,283 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/2010	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	4		
<b>Conditions:</b>	PCI: 74						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	181	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	77
<b>Sample Comments:</b>							
66	SMALL PATCH	L	6.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	13.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	183	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
66	SMALL PATCH	L	7.00	Slabs			
67	LARGE PATCH	L	4.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	11.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	780	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	64
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
66	SMALL PATCH	M	3.00	Slabs			
75	CORNER SPALL	L	3.00	Slabs			
70	SCALING	L	2.00	Slabs			
73	SHRINKAGE CR	N	15.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
<b>Sample Number:</b>	784	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	79
<b>Sample Comments:</b>							
65	JT SEAL DMG	L	20.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
70	SCALING	L	2.00	Slabs			
73	SHRINKAGE CR	N	7.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A	<b>Name:</b>	TAXIWAY A	<b>Use:</b>	TAXIWAY
<b>Section:</b>	105	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	67,381 SqFt	<b>Length:</b>	900 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	371	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1958	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	16	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 62				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	296	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
70	SCALING	L	8.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	L	5.00	Slabs	
71	FAULTING	L	2.00	Slabs	
<b>Sample Number:</b>	302	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
63	LINEAR CR	L	1.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	
66	SMALL PATCH	H	1.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
71	FAULTING	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	H	2.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	307	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
63	LINEAR CR	L	1.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
74	JOINT SPALL	H	2.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW A	<b>Name:</b>	TAXIWAY A		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	110	of 7	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1959
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	269,943 SqFt	<b>Length:</b>	3,600 Ft	<b>Width:</b>	75 Ft		
<b>Slabs:</b>	1,440	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	35,925 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	60	<b>Surveyed:</b>	6		
<b>Conditions:</b>	PCI: 75						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	242	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	78
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
70	SCALING	L	2.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
<b>Sample Number:</b>	252	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	66
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
67	LARGE PATCH	L	2.00	Slabs			
67	LARGE PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
75	CORNER SPALL	M	3.00	Slabs			
<b>Sample Number:</b>	261	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
66	SMALL PATCH	L	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
<b>Sample Number:</b>	266	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	78
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	H	1.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
<b>Sample Number:</b>	277	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	78
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	M	2.00	Slabs			
66	SMALL PATCH	L	3.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	287	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
66	SMALL PATCH	L	7.00	Slabs			
70	SCALING	L	6.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A	<b>Name:</b>	TAXIWAY A	<b>Use:</b>	TAXIWAY
<b>Section:</b>	115	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	54,396 SqFt	<b>Length:</b>	700 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	280	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	12	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 86				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	226	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		5.00	Slabs
73	SHRINKAGE CR	N		24.00	Slabs
<b>Sample Number:</b>	231	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		3.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
73	SHRINKAGE CR	N		12.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A	<b>Name:</b>	TAXIWAY A	<b>Use:</b>	TAXIWAY
<b>Section:</b>	117	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	27,484 SqFt	<b>Length:</b>	120 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	9	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 78				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	222	<b>Type:</b>	R	<b>Area:</b>	4838.00 SqFt
<b>Sample Comments:</b>					
45	DEPRESSION	L	104.00	SqFt	
48	L & T CR	L	61.00	Ft	
57	WEATHERING	L	4838.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A	<b>Name:</b>	TAXIWAY A	<b>Use:</b>	TAXIWAY
<b>Section:</b>	120	<b>of</b>	7	<b>From:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	18,750 SqFt	<b>Length:</b>	250 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	5	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	91			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	212	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	9.00	Ft	
57	WEATHERING	L	3750.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A	<b>Name:</b>	TAXIWAY A	<b>Use:</b>	TAXIWAY
<b>Section:</b>	125	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC-APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	19,405 SqFt	<b>Length:</b>	100 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	81			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	203	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	97.00	Ft	
52	RAVELING	L	150.00	SqFt	
57	WEATHERING	L	3600.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW A	<b>Name:</b>	TAXIWAY A		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	130	of 7	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	457,575 SqFt	<b>Length:</b>	6,100 Ft	<b>Width:</b>	75 Ft		
<b>Slabs:</b>	2,438	<b>Slab Length:</b>	14 Ft	<b>Slab Width:</b>	14 Ft	<b>Joint Length:</b>	60,613 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	102	<b>Surveyed:</b>	10		
<b>Conditions:</b>	PCI: 82						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	104	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
71	FAULTING	L	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
75	CORNER SPALL	M	2.00	Slabs			
<b>Sample Number:</b>	113	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	83
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
<b>Sample Number:</b>	122	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	86
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N	24.00	Slabs			
<b>Sample Number:</b>	131	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	79
<b>Sample Comments:</b>							
66	SMALL PATCH	L	1.00	Slabs			
66	SMALL PATCH	M	3.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	140	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	85
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N	24.00	Slabs			
66	SMALL PATCH	L	1.00	Slabs			
<b>Sample Number:</b>	149	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	93
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N	12.00	Slabs			
<b>Sample Number:</b>	158	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
<b>Sample Number:</b>	167	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	84
<b>Sample Comments:</b>							
66	SMALL PATCH	L	3.00	Slabs			

73 SHRINKAGE CR N 24.00 Slabs

**Sample Number:** 176 **Type:** R **Area:** 24.00 Slabs **PCI:** 83

**Sample Comments:**

73 SHRINKAGE CR N 24.00 Slabs

74 JOINT SPALL M 1.00 Slabs

---

**Sample Number:** 196 **Type:** R **Area:** 24.00 Slabs **PCI:** 78

**Sample Comments:**

66 SMALL PATCH M 2.00 Slabs

73 SHRINKAGE CR N 24.00 Slabs

74 JOINT SPALL L 2.00 Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A1	<b>Name:</b>	TAXIWAY A1	<b>Use:</b>	TAXIWAY
<b>Section:</b>	505	of 3	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	77,280 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	413	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 10,350 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	22	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 84				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	501	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR		N	20.00	Slabs
<b>Sample Number:</b>	503	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH		M	2.00	Slabs
73	SHRINKAGE CR		N	20.00	Slabs
<b>Sample Number:</b>	505	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR		N	20.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A1	<b>Name:</b>	TAXIWAY A1	<b>Use:</b>	TAXIWAY
<b>Section:</b>	510	of 3	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	58,667 SqFt	<b>Length:</b>	360 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	312	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 7,410 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	17	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 84				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	514	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		1.00 Slabs	
73	SHRINKAGE CR	N		20.00 Slabs	
<b>Sample Number:</b>	516	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		2.00 Slabs	
73	SHRINKAGE CR	N		20.00 Slabs	
<b>Sample Number:</b>	617	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		20.00 Slabs	
75	CORNER SPALL	L		1.00 Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A1	<b>Name:</b>	TAXIWAY A1	<b>Use:</b>	TAXIWAY
<b>Section:</b>	515	of 3	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	67,256 SqFt	<b>Length:</b>	300 Ft	<b>Width:</b>	210 Ft
<b>Slabs:</b>	371	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	13 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 8,830 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1984	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	20	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 74				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	422	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
67	LARGE PATCH	L	3.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
<b>Sample Number:</b>	523	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
75	CORNER SPALL	M	4.00	Slabs	
<b>Sample Number:</b>	622	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
71	FAULTING	L	2.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A2	<b>Name:</b>	TAXIWAY A2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	603	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	26,792 SqFt	<b>Length:</b>	300 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	90			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	603	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	25.00	Ft	
57	WEATHERING	L	3750.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A2	<b>Name:</b>	TAXIWAY A2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	605	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	11,684 SqFt	<b>Length:</b>	150 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 90				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	607	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	20.00	Ft	
57	WEATHERING	L	3750.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A2	<b>Name:</b>	TAXIWAY A2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	607	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	7,608 SqFt	<b>Length:</b>	100 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1961	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 91				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	609	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	9.00	Ft	
57	WEATHERING	L	3750.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A2	<b>Name:</b>	TAXIWAY A2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	608	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	7,608 SqFt	<b>Length:</b>	50 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1961	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - AC	<b>Code:</b>	PAS-AC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	94			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	614	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L		3750.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A2	<b>Name:</b>	TAXIWAY A2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	610	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	APC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	4,184 SqFt	<b>Length:</b>	75 Ft	<b>Width:</b>	50 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1982	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - AC	<b>Code:</b>	PAS-AC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	1	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 94				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	615	<b>Type:</b>	R	<b>Area:</b>	4184.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L	4184.00 SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A2	<b>Name:</b>	TAXIWAY A2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	615	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	23,980 SqFt	<b>Length:</b>	260 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	125	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	7	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 85				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	617	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		24.00	Slabs
66	SMALL PATCH	L		1.00	Slabs
<b>Sample Number:</b>	619	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		1.00	Slabs
73	SHRINKAGE CR	N		24.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A2	<b>Name:</b>	TAXIWAY A2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	620	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	24,484 SqFt	<b>Length:</b>	210 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	129	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 72				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	624	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
					<b>PCI:</b> 71
<b>Sample Comments:</b>					
62	CORNER BREAK	L	1.00	Slabs	
62	CORNER BREAK	M	1.00	Slabs	
63	LINEAR CR	L	1.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
<b>Sample Number:</b>	625	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
					<b>PCI:</b> 73
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
75	CORNER SPALL	L	2.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A3	<b>Name:</b>	TAXIWAY A3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	703	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	26,792 SqFt	<b>Length:</b>	300 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	94			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	604	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L		3750.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A3	<b>Name:</b>	TAXIWAY A3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	705	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	11,684 SqFt	<b>Length:</b>	150 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1961	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	92			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	608	<b>Type:</b>	R	<b>Area:</b>	4184.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	4.00	Ft	
57	WEATHERING	L	4184.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A3	<b>Name:</b>	TAXIWAY A3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	707	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	APC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	7,608 SqFt	<b>Length:</b>	50 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 92				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	609	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	3.00	Ft	
57	WEATHERING	L	3750.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A3	<b>Name:</b>	TAXIWAY A3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	708	<b>of</b>	7	<b>From:</b>	-
<b>Surface:</b>	APC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	7,608 SqFt	<b>Length:</b>	50 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - AC	<b>Code:</b>	PAS-AC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	94			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	614	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L		3750.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A3	<b>Name:</b>	TAXIWAY A3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	710	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	APC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	4,184 SqFt	<b>Length:</b>	50 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - AC	<b>Code:</b>	PAS-AC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	1	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI:	94			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	615	<b>Type:</b>	R	<b>Area:</b>	4184.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L	4184.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A3	<b>Name:</b>	TAXIWAY A3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	715	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	23,980 SqFt	<b>Length:</b>	260 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	125	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	7	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 81				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	617	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		1.00	Slabs
73	SHRINKAGE CR	N		24.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
<b>Sample Number:</b>	619	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		3.00	Slabs
73	SHRINKAGE CR	N		24.00	Slabs
75	CORNER SPALL	L		1.00	Slabs
71	FAULTING	L		1.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A3	<b>Name:</b>	TAXIWAY A3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	720	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	24,484 SqFt	<b>Length:</b>	210 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	127	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 73				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	623	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
66	SMALL PATCH	H	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
74	JOINT SPALL	H	1.00	Slabs	
<b>Sample Number:</b>	625	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	M	1.00	Slabs	
66	SMALL PATCH	H	1.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
66	SMALL PATCH	L	4.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A4	<b>Name:</b>	TAXIWAY A4	<b>Use:</b>	TAXIWAY
<b>Section:</b>	805	of 2	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	57,662 SqFt	<b>Length:</b>	360 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	304	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 7,410 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC Full-Depth	<b>Code:</b>	PA-PF
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	17	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 77				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	402	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	18.00	Slabs	
71	FAULTING	L	1.00	Slabs	
<b>Sample Number:</b>	501	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
71	FAULTING	L	1.00	Slabs	
<b>Sample Number:</b>	503	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	7.00	Slabs	
67	LARGE PATCH	L	4.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A4	<b>Name:</b>	TAXIWAY A4	<b>Use:</b>	TAXIWAY
<b>Section:</b>	810	<b>of:</b>	2	<b>From:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	79,426 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	422	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	23	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI:	81			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	201	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
71	FAULTING	L	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	204	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	302	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW A5	<b>Name:</b>	TAXIWAY A5	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1005	<b>of</b>	1	<b>From:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	166,214 SqFt	<b>Length:</b>	1,050 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	889	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1958	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	45	<b>Surveyed:</b>	5
<b>Conditions:</b>	PCI: 75				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	504	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	4.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
<b>Sample Number:</b>	602	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
<b>Sample Number:</b>	607	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
67	LARGE PATCH	M	2.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	612	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
<b>Sample Number:</b>	710	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
62	CORNER BREAK	L	3.00	Slabs	
63	LINEAR CR	L	3.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	3.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B	<b>Name:</b>	TAXIWAY B	<b>Use:</b>	TAXIWAY
<b>Section:</b>	205	<b>of</b>	5	<b>From:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	355,476 SqFt	<b>Length:</b>	4,680 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	1,872	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - PCC	<b>Code:</b>	PA-PCC
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	Spall Repairs	<b>Code:</b>	PA-SP
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	82	<b>Surveyed:</b>	9
<b>Conditions:</b>	PCI:	83			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	104	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
<b>Sample Number:</b>	109	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
74	JOINT SPALL	H	1.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
<b>Sample Number:</b>	123	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
<b>Sample Number:</b>	135	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	24.00	Slabs	
<b>Sample Number:</b>	142	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	24.00	Slabs	
<b>Sample Number:</b>	148	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
<b>Sample Number:</b>	161	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	24.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
<b>Sample Number:</b>	167	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					

73 SHRINKAGE CR N 24.00 Slabs  
74 JOINT SPALL L 1.00 Slabs

---

**Sample Number:** 177      **Type:** R      **Area:** 24.00 Slabs      **PCI:** 82

**Sample Comments:**

66 SMALL PATCH L 1.00 Slabs  
66 SMALL PATCH M 1.00 Slabs  
73 SHRINKAGE CR N 24.00 Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT			
<b>Branch:</b>	TW B	<b>Name:</b>	TAXIWAY B	<b>Use:</b>	TAXIWAY	
<b>Section:</b>	208	of 5	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/2011	
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>	
<b>Area:</b>	19,400 SqFt	<b>Length:</b>	100 Ft	<b>Width:</b>	130 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b>	Ft
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	1/1/1975	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED	
<b>Work Date:</b>	5/1/2007	<b>Work Type:</b>	Patching - AC	<b>Code:</b>	PAS-AC	
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV	
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	7	<b>Surveyed:</b>	1	
<b>Conditions:</b>	PCI: 89					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	181	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt	
<b>Sample Comments:</b>						
48	L & T CR	L	58.00	Ft		
57	WEATHERING	L	3750.00	SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B	<b>Name:</b>	TAXIWAY B	<b>Use:</b>	TAXIWAY
<b>Section:</b>	210	<b>of</b>	5	<b>From:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	
<b>Area:</b>	11,684 SqFt	<b>Length:</b>	150 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1982	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	3	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 91				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	189	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L	6.00	Ft	
57	WEATHERING	L	3750.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B	<b>Name:</b>	TAXIWAY B	<b>Use:</b>	TAXIWAY
<b>Section:</b>	212	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	38,584 SqFt	<b>Length:</b>	100 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1979	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	12	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 92				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	193	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
57	WEATHERING	L		3750.00 SqFt	
<b>Sample Number:</b>	201	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L		38.00 Ft	
57	WEATHERING	L		3750.00 SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B	<b>Name:</b>	TAXIWAY B	<b>Use:</b>	TAXIWAY
<b>Section:</b>	215	of 5	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	165,208 SqFt	<b>Length:</b>	2,200 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	880	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 21,925 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	37	<b>Surveyed:</b>	4
<b>Conditions:</b>	PCI: 81				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	202	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	4.00	Slabs	
73	SHRINKAGE CR	N	22.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
<b>Sample Number:</b>	219	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	24.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	227	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	24.00	Slabs	
70	SCALING	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
<b>Sample Number:</b>	235	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	24.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
75	CORNER SPALL	L	2.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B1	<b>Name:</b>	TAXIWAY B1	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1105	of 3	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	56,522 SqFt	<b>Length:</b>	370 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	301	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 7,620 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	16	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 79				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	301	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
65	JT SEAL DMG	L	20.00	Slabs	
<b>Sample Number:</b>	303	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	
65	JT SEAL DMG	L	20.00	Slabs	
<b>Sample Number:</b>	402	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
65	JT SEAL DMG	L	20.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW B1	<b>Name:</b>	TAXIWAY B1		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	1110	of 3	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1956
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	77,371 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	150 Ft		
<b>Slabs:</b>	413	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	10,350 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	22	<b>Surveyed:</b>	3		
<b>Conditions:</b>	PCI: 77						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	503	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	77
<b>Sample Comments:</b>							
66	SMALL PATCH	L	6.00	Slabs			
66	SMALL PATCH	M	3.00	Slabs			
73	SHRINKAGE CR	N	6.00	Slabs			
74	JOINT SPALL	M	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
<b>Sample Number:</b>	601	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	73
<b>Sample Comments:</b>							
66	SMALL PATCH	M	1.00	Slabs			
73	SHRINKAGE CR	N	20.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	604	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	80
<b>Sample Comments:</b>							
73	SHRINKAGE CR	N	20.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
65	JT SEAL DMG	L	20.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B1	<b>Name:</b>	TAXIWAY B1	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1115	of 3	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	30,000 SqFt	<b>Length:</b>	200 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	160	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 4,050 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	9	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 76				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	382	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	20.00	Slabs	
66	SMALL PATCH	L	6.00	Slabs	
66	SMALL PATCH	M	3.00	Slabs	
73	SHRINKAGE CR	N	20.00	Slabs	
74	JOINT SPALL	M	2.00	Slabs	
<b>Sample Number:</b>	783	<b>Type:</b>	R	<b>Area:</b>	16.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B2	<b>Name:</b>	TAXIWAY B2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1203	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	11,792 SqFt	<b>Length:</b>	130 Ft	<b>Width:</b>	100 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	4	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 88				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	201	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
42	BLEEDING	N	5.00	SqFt	
45	DEPRESSION	L	10.00	SqFt	
48	L & T CR	L	52.00	Ft	
57	WEATHERING	L	3750.00	SqFt	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B2	<b>Name:</b>	TAXIWAY B2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1205	<b>of</b>	5	<b>From:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	22,500 SqFt	<b>Length:</b>	300 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1982	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1
<b>Conditions:</b>	PCI: 90				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	204	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR		L	11.00	Ft
57	WEATHERING		L	3750.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B2	<b>Name:</b>	TAXIWAY B2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1207	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	AAC	<b>Family:</b>	C9N59-GA-TW-AAC- APC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	23,696 SqFt	<b>Length:</b>	220 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1959	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1977	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1986	<b>Work Type:</b>	OVERLAY	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/2011	<b>Work Type:</b>	MILL and OVERLAY	<b>Code:</b>	ML-OV
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI:	91			
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	209	<b>Type:</b>	R	<b>Area:</b>	3863.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L		3.00	Ft
57	WEATHERING	L		3863.00	SqFt
<b>Sample Number:</b>	400	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt
<b>Sample Comments:</b>					
48	L & T CR	L		7.00	Ft
57	WEATHERING	L		3750.00	SqFt

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW B2	<b>Name:</b>	TAXIWAY B2		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	1210	of 5	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	23,980 SqFt	<b>Length:</b>	240 Ft	<b>Width:</b>	75 Ft		
<b>Slabs:</b>	119	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	2,325 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	6	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 70						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	403	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	70
<b>Sample Comments:</b>							
62	CORNER BREAK	L	1.00	Slabs			
63	LINEAR CR	L	6.00	Slabs			
66	SMALL PATCH	L	2.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B2	<b>Name:</b>	TAXIWAY B2	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1215	of 5	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	24,522 SqFt	<b>Length:</b>	215 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	132	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 2,075 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 74				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	407	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		3.00	Slabs
73	SHRINKAGE CR	N		24.00	Slabs
<b>Sample Number:</b>	409	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
62	CORNER BREAK	L		1.00	Slabs
66	SMALL PATCH	L		4.00	Slabs
66	SMALL PATCH	M		2.00	Slabs
66	SMALL PATCH	H		1.00	Slabs
73	SHRINKAGE CR	N		24.00	Slabs
74	JOINT SPALL	L		1.00	Slabs
65	JT SEAL DMG	L		24.00	Slabs
67	LARGE PATCH	L		1.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B3	<b>Name:</b>	TAXIWAY B3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1405	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	58,667 SqFt	<b>Length:</b>	370 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	319	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	17	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 76				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	102	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs
<b>Sample Number:</b>	201	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
67	LARGE PATCH	L		2.00	Slabs
67	LARGE PATCH	M		2.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs
66	SMALL PATCH	L		1.00	Slabs
71	FAULTING	L		1.00	Slabs
<b>Sample Number:</b>	203	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L		20.00	Slabs
66	SMALL PATCH	L		1.00	Slabs
67	LARGE PATCH	M		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW B3	<b>Name:</b>	TAXIWAY B3	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1410	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	77,505 SqFt	<b>Length:</b>	500 Ft	<b>Width:</b>	150 Ft
<b>Slabs:</b>	411	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1956	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	22	<b>Surveyed:</b>	3
<b>Conditions:</b>	PCI: 79				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	405	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs
<b>Sample Number:</b>	502	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N		20.00	Slabs
71	FAULTING	L		3.00	Slabs
<b>Sample Number:</b>	604	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L		3.00	Slabs
66	SMALL PATCH	M		1.00	Slabs
70	SCALING	L		1.00	Slabs
73	SHRINKAGE CR	N		20.00	Slabs
75	CORNER SPALL	H		1.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW C	<b>Name:</b>	TAXIWAY C	<b>Use:</b>	TAXIWAY
<b>Section:</b>	305	<b>From:</b>	-	<b>To:</b>	-
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	175,845 SqFt	<b>Length:</b>	2,400 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	997	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	43	<b>Surveyed:</b>	5
<b>Conditions:</b>	PCI: 80				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	100	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
65	JT SEAL DMG	L	24.00	Slabs	
66	SMALL PATCH	L	3.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
75	CORNER SPALL	L	1.00	Slabs	
<b>Sample Number:</b>	109	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	3.00	Slabs	
66	SMALL PATCH	M	2.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
<b>Sample Number:</b>	117	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
66	SMALL PATCH	M	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
<b>Sample Number:</b>	126	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	24.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
<b>Sample Number:</b>	133	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	1.00	Slabs	
73	SHRINKAGE CR	N	16.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW C	<b>Name:</b>	TAXIWAY C		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	310	of 3	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1954
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	136,320 SqFt	<b>Length:</b>	1,700 Ft	<b>Width:</b>	80 Ft		
<b>Slabs:</b>	909	<b>Slab Length:</b>	10 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	20,887 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1954	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	38	<b>Surveyed:</b>	5		
<b>Conditions:</b>	PCI: 73						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	142	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	68
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
67	LARGE PATCH	L	3.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
74	JOINT SPALL	L	3.00	Slabs			
65	JT SEAL DMG	L	24.00	Slabs			
66	SMALL PATCH	M	1.00	Slabs			
<b>Sample Number:</b>	155	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	64
<b>Sample Comments:</b>							
66	SMALL PATCH	L	1.00	Slabs			
67	LARGE PATCH	L	3.00	Slabs			
70	SCALING	L	1.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
75	CORNER SPALL	M	1.00	Slabs			
76	ASR	L	1.00	Slabs			
65	JT SEAL DMG	L	24.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			
<b>Sample Number:</b>	161	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	73
<b>Sample Comments:</b>							
66	SMALL PATCH	L	2.00	Slabs			
67	LARGE PATCH	L	3.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
65	JT SEAL DMG	L	24.00	Slabs			
75	CORNER SPALL	L	1.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
<b>Sample Number:</b>	170	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	88
<b>Sample Comments:</b>							
67	LARGE PATCH	L	3.00	Slabs			
74	JOINT SPALL	L	2.00	Slabs			
65	JT SEAL DMG	L	24.00	Slabs			
<b>Sample Number:</b>	175	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
67	LARGE PATCH	L	3.00	Slabs			
73	SHRINKAGE CR	N	24.00	Slabs			
75	CORNER SPALL	L	2.00	Slabs			
65	JT SEAL DMG	L	24.00	Slabs			
74	JOINT SPALL	L	1.00	Slabs			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW C	<b>Name:</b>	TAXIWAY C	<b>Use:</b>	TAXIWAY	<b>Area:</b>	356,622 SqFt
<b>Section:</b>	315	of 3	<b>From:</b> -	<b>To:</b> -		<b>Last Const.:</b>	1/1/1960
<b>Surface:</b>	AC	<b>Family:</b>	C9N59-GA-TW-AC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	44,457 SqFt	<b>Length:</b>	865 Ft	<b>Width:</b>	50 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b> 0	
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1960	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	9	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 30						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	103	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	30
<b>Sample Comments:</b>							
43	BLOCK CR	M	5000.00	SqFt			
52	RAVELING	L	3000.00	SqFt			
52	RAVELING	M	2000.00	SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW D	<b>Name:</b>	TAXIWAY D		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	405	of 4	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	435,222 SqFt	<b>Length:</b>	5,460 Ft	<b>Width:</b>	75 Ft		
<b>Slabs:</b>	2,227	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	54,525 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Work Date:</b>	1/1/1991	<b>Work Type:</b>	REPAIR		<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	99		<b>Surveyed:</b>	10	
<b>Conditions:</b>	PCI: 75						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	398	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	83
<b>Sample Comments:</b>							
66	SMALL PATCH		L	1.00	Slabs		
73	SHRINKAGE CR		N	24.00	Slabs		
75	CORNER SPALL		L	1.00	Slabs		
<b>Sample Number:</b>	403	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	74
<b>Sample Comments:</b>							
66	SMALL PATCH		L	8.00	Slabs		
73	SHRINKAGE CR		N	24.00	Slabs		
74	JOINT SPALL		M	2.00	Slabs		
65	JT SEAL DMG		L	24.00	Slabs		
<b>Sample Number:</b>	416	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	79
<b>Sample Comments:</b>							
66	SMALL PATCH		L	2.00	Slabs		
73	SHRINKAGE CR		N	24.00	Slabs		
71	FAULTING		L	2.00	Slabs		
<b>Sample Number:</b>	425	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
73	SHRINKAGE CR		N	24.00	Slabs		
74	JOINT SPALL		L	2.00	Slabs		
65	JT SEAL DMG		L	24.00	Slabs		
<b>Sample Number:</b>	435	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	80
<b>Sample Comments:</b>							
66	SMALL PATCH		L	7.00	Slabs		
73	SHRINKAGE CR		N	24.00	Slabs		
65	JT SEAL DMG		L	24.00	Slabs		
<b>Sample Number:</b>	442	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	81
<b>Sample Comments:</b>							
70	SCALING		L	1.00	Slabs		
73	SHRINKAGE CR		N	24.00	Slabs		
75	CORNER SPALL		L	2.00	Slabs		
<b>Sample Number:</b>	455	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs	<b>PCI:</b>	72
<b>Sample Comments:</b>							
62	CORNER BREAK		L	1.00	Slabs		
65	JT SEAL DMG		L	24.00	Slabs		
66	SMALL PATCH		L	6.00	Slabs		
66	SMALL PATCH		M	1.00	Slabs		
73	SHRINKAGE CR		N	24.00	Slabs		
74	JOINT SPALL		L	2.00	Slabs		

**Sample Number:** 468

**Type:**

R

**Area:**

24.00 Slabs

**PCI:** 71

**Sample Comments:**

65	JT SEAL DMG	L	24.00	Slabs
66	SMALL PATCH	L	10.00	Slabs
70	SCALING	L	2.00	Slabs
73	SHRINKAGE CR	N	23.00	Slabs
74	JOINT SPALL	M	2.00	Slabs
75	CORNER SPALL	L	1.00	Slabs

**Sample Number:** 478

**Type:**

R

**Area:**

24.00 Slabs

**PCI:** 61

**Sample Comments:** Repairs done

65	JT SEAL DMG	L	24.00	Slabs
66	SMALL PATCH	L	7.00	Slabs
66	SMALL PATCH	M	6.00	Slabs
73	SHRINKAGE CR	N	24.00	Slabs
74	JOINT SPALL	L	4.00	Slabs
74	JOINT SPALL	M	3.00	Slabs
75	CORNER SPALL	L	2.00	Slabs

**Sample Number:** 488

**Type:**

R

**Area:**

24.00 Slabs

**PCI:** 72

**Sample Comments:**

66	SMALL PATCH	L	2.00	Slabs
66	SMALL PATCH	M	1.00	Slabs
73	SHRINKAGE CR	N	24.00	Slabs
74	JOINT SPALL	L	1.00	Slabs
75	CORNER SPALL	L	1.00	Slabs
75	CORNER SPALL	M	4.00	Slabs
65	JT SEAL DMG	L	24.00	Slabs

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW D	<b>Name:</b>	TAXIWAY D	<b>Use:</b>	TAXIWAY	<b>Area:</b>	619,618 SqFt
<b>Section:</b>	410	of 4	<b>From:</b> -	<b>To:</b> -		<b>Last Const.:</b>	5/1/2005
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	29,146 SqFt	<b>Length:</b>	360 Ft	<b>Width:</b>	75 Ft		
<b>Slabs:</b>	130	<b>Slab Length:</b>	15 Ft	<b>Slab Width:</b>	15 Ft	<b>Joint Length:</b>	3,165 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	5/1/2005	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	7	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 95						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	101	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	94
<b>Sample Comments:</b>							
65	JT SEAL DMG	L		20.00	Slabs		
73	SHRINKAGE CR	N		4.00	Slabs		
66	SMALL PATCH	L		1.00	Slabs		
<b>Sample Number:</b>	104	<b>Type:</b>	R	<b>Area:</b>	20.00 Slabs	<b>PCI:</b>	95
<b>Sample Comments:</b>							
65	JT SEAL DMG	L		20.00	Slabs		
73	SHRINKAGE CR	N		3.00	Slabs		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW D	<b>Name:</b>	TAXIWAY D		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	415	of 4	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2009
<b>Surface:</b>	AC	<b>Family:</b>	C9N59-GA-TW-AC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	123,375 SqFt	<b>Length:</b>	1,645 Ft	<b>Width:</b>	75 Ft		
<b>Slabs:</b>	<b>Slab Length:</b>		Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/2009	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	32	<b>Surveyed:</b>	4		
<b>Conditions:</b>	PCI: 86						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	114	<b>Type:</b>	R	<b>Area:</b>	5625.00 SqFt	<b>PCI:</b>	89
<b>Sample Comments:</b>							
48	L & T CR	L		88.00	Ft		
57	WEATHERING	L		5625.00	SqFt		
<b>Sample Number:</b>	120	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt	<b>PCI:</b>	84
<b>Sample Comments:</b>							
48	L & T CR	L		130.00	Ft		
57	WEATHERING	L		3750.00	SqFt		
<b>Sample Number:</b>	126	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt	<b>PCI:</b>	86
<b>Sample Comments:</b>							
48	L & T CR	L		99.00	Ft		
57	WEATHERING	L		3750.00	SqFt		
<b>Sample Number:</b>	142	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt	<b>PCI:</b>	85
<b>Sample Comments:</b>							
48	L & T CR	L		116.00	Ft		
57	WEATHERING	L		3750.00	SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW D	<b>Name:</b>	TAXIWAY D	<b>Use:</b>	TAXIWAY	<b>Area:</b>	619,618 SqFt
<b>Section:</b>	420	of 4	<b>From:</b> -		<b>To:</b> -		<b>Last Const.:</b> 1/1/2008
<b>Surface:</b>	AC	<b>Family:</b>	C9N59-GA-TW-AC	<b>Zone:</b>		<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	31,875 SqFt	<b>Length:</b>	400 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0		<b>Lanes:</b> 0	
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/2008	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	8	<b>Surveyed:</b>	1		
<b>Conditions:</b>	PCI: 66						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	109	<b>Type:</b>	R	<b>Area:</b>	3750.00 SqFt	<b>PCI:</b>	66
<b>Sample Comments:</b>							
48	L & T CR	L	132.00	Ft			
57	WEATHERING	L	2700.00	SqFt			
50	PATCHING	L	1050.00	SqFt			

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT				
<b>Branch:</b>	TW D2	<b>Name:</b>	TAXIWAY D2		<b>Use:</b>	TAXIWAY	<b>Area:</b>
<b>Section:</b>	905	of 1	<b>From:</b>	-	<b>To:</b>	-	<b>Last Const.:</b> 1/1/2008
<b>Surface:</b>	AC	<b>Family:</b>	C9N59-GA-TW-AC	<b>Zone:</b>	<b>Category:</b>		<b>Rank:</b> P
<b>Area:</b>	59,738 SqFt	<b>Length:</b>	600 Ft	<b>Width:</b>	100 Ft		
<b>Slabs:</b>	<b>Slab Length:</b>		Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>	<b>Street Type:</b>			<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/2008	<b>Work Type:</b>	New Construction - Initial	<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	14	<b>Surveyed:</b>	2		
<b>Conditions:</b>	PCI: 78						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	201	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	78
<b>Sample Comments:</b>							
48	L & T CR	L		317.00	Ft		
57	WEATHERING	L		5000.00	SqFt		
42	BLEEDING	N		1.00	SqFt		
<b>Sample Number:</b>	205	<b>Type:</b>	R	<b>Area:</b>	4223.00 SqFt	<b>PCI:</b>	80
<b>Sample Comments:</b>							
42	BLEEDING	N		2.00	SqFt		
48	L & T CR	L		225.00	Ft		
57	WEATHERING	L		4223.00	SqFt		

<b>Network:</b>	VQQ	<b>Name:</b>	CECIL AIRPORT		
<b>Branch:</b>	TW M	<b>Name:</b>	TAXIWAY M	<b>Use:</b>	TAXIWAY
<b>Section:</b>	1305	of 1	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1951
<b>Surface:</b>	PCC	<b>Family:</b>	C9N59-GA-RW-TW-PCC	<b>Zone:</b>	<b>Category:</b>
<b>Area:</b>	22,376 SqFt	<b>Length:</b>	210 Ft	<b>Width:</b>	75 Ft
<b>Slabs:</b>	120	<b>Slab Length:</b>	13 Ft	<b>Slab Width:</b>	15 Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b> 0	<b>Joint Length:</b> 2,025 Ft
<b>Section Comments:</b>					
<b>Work Date:</b>	1/1/1951	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1965	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Work Date:</b>	1/1/1981	<b>Work Type:</b>	REPAIR	<b>Code:</b>	IMPORTED
<b>Last Insp. Date:</b>	5/22/2017	<b>Total Samples:</b>	7	<b>Surveyed:</b>	2
<b>Conditions:</b>	PCI: 81				
<b>Inspection Comments:</b>					
<b>Sample Number:</b>	100	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
66	SMALL PATCH	L	2.00	Slabs	
73	SHRINKAGE CR	N	18.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
<b>Sample Number:</b>	102	<b>Type:</b>	R	<b>Area:</b>	24.00 Slabs
<b>Sample Comments:</b>					
73	SHRINKAGE CR	N	24.00	Slabs	
75	CORNER SPALL	M	1.00	Slabs	
65	JT SEAL DMG	L	24.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	