

FLORIDA DEPARTMENT OF TRANSPORTATION
AVIATION AND SPACEPORTS OFFICE

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report November 2019



**Punta Gorda
Airport (PGD)**
Commercial Airport
District 1





Florida Department of Transportation

Statewide Airfield Pavement Management Program

Prepared by:

*FDOT Aviation and Spaceports Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*




OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS

Table of Contents


Executive Summary.....	10
Program Background.....	10
Summary of Results.....	11
Pavement Condition Index (Latest Inspection).....	11
Forecasted Pavement Condition Index 2020-2029	13
Major Rehabilitation Planning 2020-2029	14
Summary of Punta Gorda Airport.....	16
Chapter 1 – Introduction.....	18
1.1 Background	18
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019	18
1.3 Organization.....	20
1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager.....	20
1.3.2 Participating Florida Public-Use and Publicly Owned Airports	20
1.3.3 Florida Department of Transportation District Offices	20
1.3.4 Consultant.....	20
1.4 Purpose of Airport Pavement Evaluation Report	22
1.5 History of the Program.....	22
1.6 Federal Aviation Administration (FAA)	24
1.7 FDOT SAPMP Objectives and Components	24
1.7.1 Program Objectives.....	24
1.7.2 Program Components	24
1.8 References	28
Chapter 2 – Methodology	30
2.1 Airfield Pavement Database.....	30
2.2 Airfield Pavement System Inventory	30
2.2.1 Pavement Management Program Network Definition Terminology	31
2.3 Airfield Pavement Structure.....	33
2.3.1 Pavement Structure Types	33
2.4 Airfield Pavement Work History	35
2.4.1 Airfield Pavement Record Keeping	35
2.5 Airfield Pavement Traffic.....	35
2.6 Airfield Pavement Condition Index (PCI) Survey.....	35
2.6.1 PCI Survey Methodology.....	35
2.6.2 Pavement Distress Types.....	37

2.6.3 PCI Survey Inspection Procedures	41
2.6.4 Updates to the ASTM D5340-12.....	42
Chapter 3 – Airfield Pavement System Inventory	45
3.1 Airfield Pavement Network Information	45
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	45
3.1.2 Estimated Pavement Age	47
3.1.3 Functional Use Classification.....	49
3.1.4 Pavement Surface Type	50
3.1.5 Pavement System Inventory Details	51
Chapter 4 – Airfield Pavement Condition	56
4.1 Airfield Pavement Condition Index (Latest Inspection)	56
4.1.1 Network-Level Analysis	56
4.1.2 Branch-Level Analysis.....	56
4.1.3 Section-Level Analysis	59
4.2 Summary of Pavement Condition Evaluation Results	63
4.2.1 Network-Level Observations.....	63
4.2.2 Branch-Level Observations	63
4.3 Forecasted Pavement Conditions	65
4.3.1 Performance Models and Prediction Curves	65
4.3.2 Branch-Level Pavement Condition Forecast	65
4.3.3 Section-Level Pavement Condition Forecast	67
4.3.4 Forecasted PCI Considerations	70
Chapter 5 – Localized Maintenance and Repair Planning.....	72
5.1 Localized Maintenance and Repair	72
5.2 Localized Maintenance and Repair Policy	73
5.3 Localized Maintenance and Repair Analysis and Recommendations	77
Chapter 6 – Major Rehabilitation Planning.....	81
6.1 Major Rehabilitation	81
6.1.1 Critical PCI.....	83
6.1.2 FDOT Recommended Minimum Service-Level PCI	83
6.2 Major Rehabilitation Policy	84
6.2.1 Major Rehabilitation Pavement Section Development	84
6.2.2 Major Rehabilitation Planning-Level Unit Costs.....	86
6.3 Major Rehabilitation Needs.....	86
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs	86
Chapter 7 – Conclusion	91
7.1 Recommendations.....	91
7.1.1 Continued PCI Survey Inspections	91
7.1.2 Localized Maintenance and Repair.....	91

7.1.3 Major Rehabilitation.....	91
7.1.4 Pavement Management System.....	91
7.2 Supporting Documents	92
001 – Airfield Pavement Network Definition Exhibit	92
002 – Airfield Pavement System Inventory Exhibit.....	92
003 – Airfield Pavement Condition Index Exhibit.....	92
004 – Airfield Pavement Major Rehabilitation Exhibit.....	92
Inspection Photograph Documentation.....	92
7.3 Conclusion	93



Appendix A	Airfield Pavement Analysis Tables
Appendix B	Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
Appendix C	Technical Exhibits
Appendix D	Inspection Photograph Documentation
Appendix E	Inspection Distress Details



List of Figures

<i>Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029.....</i>	<i>16</i>
<i>Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts.....</i>	<i>19</i>
<i>Figure 1.7.2 (a) Typical Pavement Condition Life Cycle.....</i>	<i>25</i>
<i>Figure 1.7.2 (b) General Pavement Treatments by Condition Range</i>	<i>26</i>
<i>Figures 1.7.2 (c) Flexible Asphalt Concrete</i>	<i>27</i>
<i>Figures 1.7.2 (d) Rigid Portland Cement Concrete</i>	<i>27</i>
<i>Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit</i>	<i>46</i>
<i>Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit.....</i>	<i>47</i>
<i>Figure 3.1.2 Average Age of Pavements at Inspection.....</i>	<i>48</i>
<i>Figure 3.1.3 Airfield Pavement Functional Classification Use by Area</i>	<i>49</i>
<i>Figure 3.1.4 (a) Pavement Surface Type by Area (SF)</i>	<i>50</i>
<i>Figure 3.1.4 (b) Pavement Surface Type by Area (%)</i>	<i>51</i>
<i>Figure 4.1.1 Latest Condition – Overall Network</i>	<i>56</i>
<i>Figure 4.1.2 (a) Latest Condition – Runway Pavements.....</i>	<i>57</i>
<i>Figure 4.1.2 (b) Latest Condition – Taxiway Pavements</i>	<i>57</i>
<i>Figure 4.1.2 (c) Latest Condition – Apron Pavements</i>	<i>58</i>
<i>Figure 4.1.2 (d) Latest Condition – Taxilane Pavements</i>	<i>58</i>
<i>Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit.....</i>	<i>62</i>
<i>Figure 4.2.2 Pavement Condition Summary by Facility Use</i>	<i>65</i>
<i>Figure 4.3.2 (a) Forecasted Runway Pavement Performance</i>	<i>66</i>
<i>Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance.....</i>	<i>66</i>
<i>Figure 4.3.2 (c) Forecasted Apron Pavement Performance</i>	<i>67</i>
<i>Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, $PCI \leq$ Critical PCI.....</i>	<i>81</i>
<i>Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, $PCI >$ Critical PCI</i>	<i>82</i>
<i>Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year</i>	<i>88</i>
<i>Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit.....</i>	<i>89</i>

List of Tables

<i>Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level.....</i>	<i>11</i>
<i>Table E-2 Pavement Condition Index Forecast 2020-2029</i>	<i>13</i>
<i>Table E-3 Major Rehabilitation Planning 2020-2029</i>	<i>14</i>
<i>Table 2.2.1 Airfield Pavement Database Network Definition Terminology.....</i>	<i>32</i>
<i>Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>37</i>
<i>Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>38</i>
<i>Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>38</i>
<i>Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>39</i>
<i>Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>40</i>
<i>Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>40</i>
<i>Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete</i>	<i>41</i>
<i>Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete</i>	<i>41</i>
<i>Table 2.6.4 Summary of Updates to ASTM D5340-12</i>	<i>43</i>
<i>Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction</i>	<i>45</i>
<i>Table 3.1.5 Pavement System Inventory Details</i>	<i>52</i>
<i>Table 4.1.3 Latest Pavement Condition Index Summary</i>	<i>60</i>
<i>Table 4.3.3 Forecasted PCI 2020-2029.....</i>	<i>68</i>
<i>Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete</i>	<i>73</i>
<i>Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete</i>	<i>74</i>
<i>Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete</i>	<i>76</i>

<i>Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete</i>	<i>76</i>
<i>Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level</i>	<i>77</i>
<i>Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level</i>	<i>78</i>
<i>Table 5.3 (c) Summary of Localized Maintenance</i>	<i>79</i>
<i>Table 6.1.2 FDOT Recommended Minimum Service-Level PCI</i>	<i>83</i>
<i>Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete</i>	<i>84</i>
<i>Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete</i>	<i>85</i>
<i>Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type</i>	<i>86</i>
<i>Table 6.3.1 10-Year Major Rehabilitation Needs</i>	<i>87</i>



Executive Summary





Executive Summary

Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP)”** using the documented procedures set forth by ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.



Summary of Results

Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PGD	RUNWAY 4-22	RUNWAY	6105	520,000	50	Poor
PGD	RUNWAY 4-22	RUNWAY	6110	262,500	77	Satisfactory
PGD	RUNWAY 4-22	RUNWAY	6115	149,200	67	Fair
PGD	RUNWAY 4-22	RUNWAY	6120	72,100	78	Satisfactory
PGD	RUNWAY 4-22	RUNWAY	6125	50,300	58	Fair
PGD	RUNWAY 4-22	RUNWAY	6130	25,150	82	Satisfactory
PGD	RUNWAY 15-33	RUNWAY	6205	6,582	65	Fair
PGD	RUNWAY 15-33	RUNWAY	6210	494,128	59	Fair
PGD	RUNWAY 15-33	RUNWAY	6215	253,378	68	Fair
PGD	RUNWAY 15-33	RUNWAY	6220	53,287	66	Fair
PGD	RUNWAY 15-33	RUNWAY	6225	26,644	83	Satisfactory
PGD	RUNWAY 9-27	RUNWAY	6305	151,500	60	Fair
PGD	RUNWAY 9-27	RUNWAY	6310	33,102	86	Good
PGD	TAXIWAY A	TAXIWAY	320	162,031	100	Good
PGD	TAXIWAY A	TAXIWAY	330	271,000	50	Poor
PGD	TAXIWAY A2	TAXIWAY	365	38,414	67	Fair
PGD	TAXIWAY C	TAXIWAY	305	48,969	72	Satisfactory
PGD	TAXIWAY C	TAXIWAY	310	158,559	58	Fair
PGD	TAXIWAY C	TAXIWAY	315	23,546	100	Good
PGD	TAXIWAY C	TAXIWAY	350	3,675	62	Fair
PGD	TAXIWAY D	TAXIWAY	102	83,519	36	Very Poor
PGD	TAXIWAY D	TAXIWAY	115	214,000	35	Very Poor
PGD	TAXIWAY D	TAXIWAY	120	43,181	58	Fair
PGD	TAXIWAY D	TAXIWAY	155	4,146	64	Fair
PGD	TAXIWAY D	TAXIWAY	160	2,534	78	Satisfactory
PGD	TAXIWAY D	TAXIWAY	172	3,508	58	Fair
PGD	TAXIWAY D	TAXIWAY	180	10,800	77	Satisfactory
PGD	TAXIWAY D	TAXIWAY	195	3,304	69	Fair
PGD	TAXIWAY E	TAXIWAY	410	19,242	78	Satisfactory
PGD	TAXIWAY E	TAXIWAY	415	70,611	83	Satisfactory
PGD	TAXIWAY E1	TAXIWAY	450	7,748	62	Fair
PGD	TAXIWAY F	TAXIWAY	1105	50,341	62	Fair
PGD	TAXIWAY G	TAXIWAY	110	34,930	54	Poor
PGD	TAXIWAY TO NORTH T-HANGARS	TAXIWAY	215	6,938	35	Very Poor



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4405	22,295	62	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4410	15,629	59	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4415	7,080	80	Satisfactory
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4420	45,846	62	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4425	27,208	64	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4430	14,668	68	Fair
PGD	TAXILANE TO T-HANGARS	TAXILANE	4505	79,013	81	Satisfactory
PGD	SOUTH GA APRON	APRON	4105	192,015	53	Poor
PGD	MAIN APRON	APRON	4205	278,175	87	Good
PGD	MAIN APRON	APRON	4206	194,550	77	Satisfactory
PGD	MAIN APRON	APRON	4208	10,625	63	Fair
PGD	MAIN APRON	APRON	4210	14,657	88	Good
PGD	MAIN APRON	APRON	4215	32,858	76	Satisfactory
PGD	MAIN APRON	APRON	4220	31,145	80	Satisfactory
PGD	MAIN APRON	APRON	4225	102,541	100	Good
PGD	MAIN APRON	APRON	4230	30,430	100	Good
PGD	NORTH APRON	APRON	4305	221,433	56	Fair
PGD	NORTH APRON	APRON	4320	98,202	59	Fair



Forecasted Pavement Condition Index 2020-2029

Table E-2 Pavement Condition Index Forecast 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
PGD	AP MAIN	4205	87	86	85	84	84	83	82	81	80	80	79
PGD	AP MAIN	4206	77	75	73	72	70	68	67	65	64	62	61
PGD	AP MAIN	4208	63	61	59	57	55	53	52	50	48	46	44
PGD	AP MAIN	4210	88	86	84	83	81	79	78	76	75	73	72
PGD	AP MAIN	4215	76	74	72	71	69	67	66	64	63	61	60
PGD	AP MAIN	4220	80	78	76	75	73	71	70	68	67	65	64
PGD	AP MAIN	4225	100	96	94	93	91	90	89	88	87	86	86
PGD	AP MAIN	4230	100	97	96	94	92	91	89	88	86	85	83
PGD	AP N	4305	56	54	52	51	49	47	46	44	43	41	40
PGD	AP N	4320	59	57	55	54	52	50	49	47	46	44	43
PGD	AP S	4105	53	51	49	48	46	44	43	41	40	38	37
PGD	RW 15-33	6205	65	62	59	57	55	54	54	54	54	53	52
PGD	RW 15-33	6210	59	56	55	54	54	54	54	52	52	51	50
PGD	RW 15-33	6215	68	64	62	59	57	55	54	54	54	54	53
PGD	RW 15-33	6220	66	64	62	60	58	57	55	53	51	50	48
PGD	RW 15-33	6225	83	81	79	77	75	74	72	70	68	67	65
PGD	RW 4-22	6105	50	49	48	48	47	47	46	45	45	44	44
PGD	RW 4-22	6110	77	75	73	70	68	65	62	60	57	56	55
PGD	RW 4-22	6115	67	63	61	58	56	55	54	54	54	54	52
PGD	RW 4-22	6120	78	76	74	72	70	67	64	61	59	57	55
PGD	RW 4-22	6125	58	56	54	52	50	49	47	45	43	42	40
PGD	RW 4-22	6130	82	80	78	76	74	73	71	69	67	66	64
PGD	RW 9-27	6305	60	58	56	54	52	51	49	47	45	44	42
PGD	RW 9-27	6310	86	84	82	80	78	77	75	73	71	70	68
PGD	TL T-HANG	4505	81	79	77	76	75	73	72	71	70	69	68
PGD	TW A	320	100	93	91	89	87	85	83	82	80	79	77
PGD	TW A	330	50	49	48	47	45	44	43	41	39	37	35
PGD	TW A2	365	67	65	64	62	61	60	59	58	57	57	56
PGD	TW C	305	72	70	68	66	65	64	62	61	60	59	58
PGD	TW C	310	58	57	56	55	55	54	54	53	52	52	51
PGD	TW C	315	100	90	88	85	83	80	78	76	74	72	70
PGD	TW C	350	62	60	59	58	58	57	56	55	55	54	54
PGD	TW D	102	36	33	30	26	23	19	15	11	8	4	0
PGD	TW D	115	35	32	29	25	22	18	13	8	3	0	0
PGD	TW D	120	58	57	56	55	55	54	54	53	52	52	51



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
PGD	TW D	155	64	62	61	60	59	58	57	57	56	55	55
PGD	TW D	160	78	75	73	71	70	68	66	65	64	62	61
PGD	TW D	172	58	57	56	55	54	53	51	50	49	47	46
PGD	TW D	180	77	75	74	73	71	70	69	68	67	66	66
PGD	TW D	195	69	67	67	66	65	64	63	63	62	61	60
PGD	TW E	410	78	76	75	73	72	71	70	69	68	67	66
PGD	TW E	415	83	81	79	78	76	75	74	72	71	70	69
PGD	TW E1	450	62	61	60	59	59	58	57	56	55	54	53
PGD	TW F	1105	62	61	60	59	59	58	57	56	55	54	53
PGD	TW G	110	54	53	52	52	51	50	50	49	48	47	46
PGD	TW N T-HAN	215	35	31	28	25	21	18	14	10	6	3	0
PGD	TW T-HANG	4405	62	61	60	59	59	58	57	56	55	54	53
PGD	TW T-HANG	4410	59	58	57	56	55	54	53	52	51	49	48
PGD	TW T-HANG	4415	80	78	76	75	74	73	71	70	69	68	67
PGD	TW T-HANG	4420	62	61	60	59	59	58	57	56	55	54	53
PGD	TW T-HANG	4425	64	63	62	61	61	60	59	58	57	57	56
PGD	TW T-HANG	4430	68	67	66	65	64	63	63	62	61	60	60

Major Rehabilitation Planning 2020-2029


Table E-3 Major Rehabilitation Planning 2020-2029

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	PGD	AP MAIN	4208	PCC	10,625	61	PCC Restoration	\$ 181,000.00
2020	PGD	AP N	4305	AC	221,433	54	AC Restoration	\$ 2,436,000.00
2020	PGD	AP N	4320	AC	98,202	57	AC Restoration	\$ 1,081,000.00
2020	PGD	AP S	4105	AC	192,015	51	AC Restoration	\$ 2,113,000.00
2020	PGD	RW 15-33	6205	AAC	6,582	62	AC Restoration	\$ 73,000.00
2020	PGD	RW 15-33	6210	AAC	494,128	56	AC Restoration	\$ 5,436,000.00
2020	PGD	RW 15-33	6215	AAC	253,378	64	AC Restoration	\$ 2,788,000.00
2020	PGD	RW 15-33	6220	AC	53,287	64	AC Restoration	\$ 587,000.00
2020	PGD	RW 4-22	6105	AAC	520,000	49	AC Restoration	\$ 5,819,000.00
2020	PGD	RW 4-22	6115	AAC	149,200	63	AC Restoration	\$ 1,642,000.00
2020	PGD	RW 4-22	6125	AC	50,300	56	AC Restoration	\$ 554,000.00
2020	PGD	RW 9-27	6305	AC	151,500	58	AC Restoration	\$ 1,667,000.00
2020	PGD	TW A	330	AAC	271,000	49	AC Restoration	\$ 3,054,000.00
2020	PGD	TW C	310	AAC	158,559	57	AC Restoration	\$ 1,745,000.00
2020	PGD	TW C	350	AAC	3,675	60	AC Restoration	\$ 41,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	PGD	TW D	102	AC	83,519	33	AC Reconstruction	\$ 1,170,000.00
2020	PGD	TW D	115	AAC	214,000	32	AC Reconstruction	\$ 2,996,000.00
2020	PGD	TW D	120	AAC	43,181	57	AC Restoration	\$ 475,000.00
2020	PGD	TW D	155	AAC	4,146	62	AC Restoration	\$ 46,000.00
2020	PGD	TW D	172	AC	3,508	57	AC Restoration	\$ 39,000.00
2020	PGD	TW E1	450	AC	7,748	61	AC Restoration	\$ 86,000.00
2020	PGD	TW F	1105	AC	50,341	61	AC Restoration	\$ 554,000.00
2020	PGD	TW G	110	AAC	34,930	53	AC Restoration	\$ 385,000.00
2020	PGD	TW N T-HAN	215	AC	6,938	31	AC Reconstruction	\$ 98,000.00
2020	PGD	TW T-HANG	4405	AC	22,295	61	AC Restoration	\$ 246,000.00
2020	PGD	TW T-HANG	4410	AC	15,629	58	AC Restoration	\$ 172,000.00
2020	PGD	TW T-HANG	4420	AC	45,846	61	AC Restoration	\$ 505,000.00
2020	PGD	TW T-HANG	4425	AC	27,208	63	AC Restoration	\$ 300,000.00
2021	PGD	TW A2	365	AAC	38,414	64	AC Restoration	\$ 423,000.00
2023	PGD	TW T-HANG	4430	AC	14,668	64	AC Restoration	\$ 162,000.00
2024	PGD	TW C	305	AAC	48,969	64	AC Restoration	\$ 539,000.00
2024	PGD	TW D	195	AC	3,304	64	AC Restoration	\$ 37,000.00
2025	PGD	RW 4-22	6110	AAC	262,500	62	AC Restoration	\$ 2,888,000.00
2025	PGD	RW 4-22	6120	AAC	72,100	64	AC Restoration	\$ 794,000.00
2026	PGD	AP MAIN	4215	AC	32,858	64	AC Restoration	\$ 362,000.00
2027	PGD	AP MAIN	4206	AC	194,550	64	AC Restoration	\$ 2,140,000.00
2027	PGD	TW D	160	AAC	2,534	64	AC Restoration	\$ 28,000.00
2029	PGD	AP MAIN	4220	AC	31,145	64	AC Restoration	\$ 343,000.00
2029	PGD	RW 4-22	6130	AC	25,150	64	AC Restoration	\$ 277,000.00

**All planning cost values have been rounded to the nearest thousand-dollar.*


*Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029*

Summary of Punta Gorda Airport

Punta Gorda Airport was inspected in December 2018 – the overall weighted PCI value was 64, a condition rating of Fair. The results of the maintenance, repair, and major rehabilitation analysis identified \$2,226,020 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$44,282,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$36,289,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.

Chapter 1





Chapter 1 – Introduction

1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating public-use airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.



1.3 Organization

1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."** Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys,"** evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."**

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- ▶ **Research and evaluation of existing record documentation** was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- ▶ **An update to the existing Network Definition Map** was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- ▶ **A functional pavement evaluation with PCI Survey inspections** was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- ▶ **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- ▶ **Maintenance, Repair, and Rehabilitation Planning** was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.



1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA **AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."** The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.



1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and **150/5380-7B “Airport Pavement Management Program (PMP)”**). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.”

1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC **150/5380-7B “Airport Pavement Management Program (PMP)”** an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data




F. Pavement Performance Modeling for the Prediction/Forecast of PCI

G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements’ past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and cost-effective manner. **Figure 1.7.2 (a) Typical Pavement Condition Life Cycle**, which is based on the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”** **Figure 1.7.2 (a) Typical Pavement Condition Life Cycle**, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.

Figure 1.7.2 (a) Typical Pavement Condition Life Cycle




**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).*

Figure 1.7.2 (b) General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.





Figure 1.7.2 (b) General Pavement Treatments by Condition Range







Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7.2 (a) and 1.7.2 (b)**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7.2 (c) and 1.7.2 (d), depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.


Figures 1.7.2 (c) Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figures 1.7.2 (d) Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.




1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”
- FAA Advisory Circular 150/5380-7B “Airport Pavement Management Program.”
- FAA Advisory Circular 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”
- FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation.”
- Department of the Air Force, Air Force Civil Engineer Center “Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements.”
- Unified Facilities Criteria (UFC) 3-260-16FA 16 “Airfield Pavement Condition Survey Procedures Pavements.”
- Unified Facilities Criteria (UFC) 3-260-03 “Airfield Pavement Evaluation.”
- Pavement Management for Airports, Roads, and Parking Lots 2nd Edition, M.Y. Shahin.

Chapter 2





Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”**

2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.



A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a “parent” pavement network.

Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (± 8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ($\pm 2,000$ ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	“Tallahassee International Airport – Airfield Pavements”
Branch Name	Commonly defined asset name as established by Airport and by use	“Runway 18-36”
Branch ID	Codified shorthand name for commonly defined asset established for database identification	“RW 18-36” RW, Branch Use, “Runway” 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following: <ul style="list-style-type: none"> • Pavement Composition • Construction Work History • Aircraft Traffic • Condition Records 	“6105”
Sample Unit	A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	“300”



2.3 Airfield Pavement Structure

2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.



Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 8 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 8 inches in thickness.

Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.



2.4 Airfield Pavement Work History

2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

1. Location and Limits of Work.
2. Types and Severity of Distresses Repaired.
3. Type of Work.
4. Cost of Work.
5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.6 Airfield Pavement Condition Index (PCI) Survey

2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP),"** the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.



2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age



Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> • Alligator Cracking • Corrugation • Depression • Patching of Load-based distress • Polished Aggregate • Rutting • Slippage Cracking 	<ul style="list-style-type: none"> • Bleeding • Block Cracking • Joint Reflection Cracking • L/T Cracking • Patching of climate / durability-caused distresses • Shoving from PCC • Raveling • Weathering • Swelling 	<ul style="list-style-type: none"> • Alligator Cracking • Depression • Patching of moisture / drainage caused distress • Swelling • Raveling • Weathering 	<ul style="list-style-type: none"> • Oil Spillage • Jet Blast Erosion • Polished Aggregate

Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> • Corrugation • Depression • Rutting • Shoving of asphalt pavement • Swelling • Raveling • Weathering 	<ul style="list-style-type: none"> • Bleeding • Depression • Polished Aggregate • Rutting 	<ul style="list-style-type: none"> • Block Cracking • Joint Reflection Cracking • L/T Cracking • Slippage Cracking 	<ul style="list-style-type: none"> • All Distresses



Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Blowup	Climate / ASR
Corner Break	Load Repetition / Curling Stresses
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
Durability Cracking	Freeze-Thaw Cycling
Joint Seal Damage	Material Deterioration / Construction Quality / Age
Small Patch	Pavement Repair
Large Patch/Utility Cut	Utility / Pavement Repair
Popout	Freeze-Thaw Cycling / ASR / Material Quality
Pumping	Load Repetition / Poor Joint Sealant
Scaling	Construction Quality / Freeze-Thaw Cycling
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer
Shattered Slab	Overloading
Shrinkage Cracking	Construction Quality / Climate
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction



Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> • Corner Break • Shattered Slab • L/T/D Cracking • Pumping • Patching of Load-associated distress • Spalling 	<ul style="list-style-type: none"> • Blowup • "D" Cracking • Joint Seal Damage • Popouts • Scaling • Patch of Climate/Durability-associated distress • Shrinkage Cracking • Spalling • L/T/D Cracking 	<ul style="list-style-type: none"> • Corner Break • Shattered Slab • Pumping • Patching of Moisture/Drainage-associated distress 	<ul style="list-style-type: none"> • Settlement / Faulting

Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> • Blowup • Corner Break • L/T/D Cracking • Shattered Slab • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Corner Break • L/T/D Cracking • "D" Cracking • Joint Seal Damage • Shattered Slab • Popouts • Scaling 	<ul style="list-style-type: none"> • All distresses



2.6.3 PCI Survey Inspection Procedures

Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10



2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured “(52) Weathering and Raveling” distress has been separated into two distresses “(52) Raveling” and “(57) Weathering.” Previously, areas that were recorded as “Weathering and Raveling” were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where “Weathering” only exists and does not meet the definition of “Raveling,” the PCI deduction is not as high as the former “Weathering and Raveling.” Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling,” may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

Rigid Portland Cement Concrete Pavement Distress Updates


The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR.” As a result, the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling,” and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, “(73) Shrinkage Cracks” has been redefined as “(73) Shrinkage Cracking”. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage can be caused by both atmospheric conditions and construction. Plastic shrinkage caused by atmospheric conditions develops when there is rapid loss of water in the surface of recently placed pavement. High winds or low humidity are contributing factors to evaporation. These shrinkage cracks can appear as a series of parallel cracks, usually 1 to 3 feet apart and do not extend very deep into the pavement’s surface. Plastic shrinkage caused by construction can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Distress Updates to Reflect ASTM 5340-12				
Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Cracking - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Cracking - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Cracking - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Cracking' may now be identified as 'Shrinkage Cracking'

Chapter 3





Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1 (a)** and **Figure 3.1.1 (b)** provides an inset view of the 2019 Airfield Pavement Network Definition Exhibit and the 2019 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.


Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Year	General Work Description
2016	TW A - New Construction: 4" P-401, 12" P-211, 10" P-211
	TW C - Mill and Overlay: 4" P-401 Mill and Overlay
2018	AP MAIN - New Construction AC
	AP MAIN - New Construction PCC
2020	RW 15-33, TW D, TW E, TW G, TW H - Pavement Rehabilitation
2021	RW 4-22 - Pavement Rehabilitation

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.




Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit



The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.




Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit



The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections at the time of the PCI survey inspection. Age is determined to be the number of years since any major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

*Figure 3.1.2 Average Age of Pavements at Inspection*


The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.



3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.

Figure 3.1.4 (a) Pavement Surface Type by Area (SF)



*Figure 3.1.4 (b) Pavement Surface Type by Area (%)*

3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PGD	MAIN APRON	AP MAIN	APRON	4205	600	300	278,175	PCC	1/1/2009
PGD	MAIN APRON	AP MAIN	APRON	4206	950	300	194,550	AC	1/1/2009
PGD	MAIN APRON	AP MAIN	APRON	4208	300	30	10,625	PCC	12/25/1995
PGD	MAIN APRON	AP MAIN	APRON	4210	200	75	14,657	AC	1/1/2007
PGD	MAIN APRON	AP MAIN	APRON	4215	440	75	32,858	AC	1/1/2007
PGD	MAIN APRON	AP MAIN	APRON	4220	430	75	31,145	AC	1/1/2009
PGD	MAIN APRON	AP MAIN	APRON	4225	400	300	102,541	PCC	7/2/2018
PGD	MAIN APRON	AP MAIN	APRON	4230	400	75	30,430	AC	7/2/2018
PGD	NORTH APRON	AP N	APRON	4305	1,065	200	221,433	AC	12/25/1999
PGD	NORTH APRON	AP N	APRON	4320	830	140	98,202	AC	12/25/1999
PGD	SOUTH GA APRON	AP S	APRON	4105	845	200	192,015	AC	1/1/1992
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6205	75	87	6,582	AAC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6210	4,945	100	494,128	AAC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6215	9,890	25	253,378	AAC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6220	530	100	53,287	AC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6225	1,066	25	26,644	AC	1/1/2002
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6105	5,200	100	520,000	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6110	10,500	25	262,500	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6115	1,492	100	149,200	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6120	2,884	25	72,100	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6125	500	100	50,300	AC	1/1/2007
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6130	500	50	25,150	AC	1/1/2007
PGD	RUNWAY 9-27	RW 9-27	RUNWAY	6305	2,525	60	151,500	AC	1/1/2006
PGD	RUNWAY 9-27	RW 9-27	RUNWAY	6310	338	60	33,102	AC	1/1/2006
PGD	TAXILANE TO T-HANGARS	TL T-HANG	TAXILANE	4505	2,835	25	79,013	AC	1/1/2006




Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PGD	TAXIWAY A	TW A	TAXIWAY	320	2,100	60	162,031	AC	9/1/2016
PGD	TAXIWAY A	TW A	TAXIWAY	330	2,325	60	271,000	AAC	1/1/2009
PGD	TAXIWAY A2	TW A2	TAXIWAY	365	295	90	38,414	AAC	1/1/2009
PGD	TAXIWAY C	TW C	TAXIWAY	305	428	50	48,969	AAC	1/1/1993
PGD	TAXIWAY C	TW C	TAXIWAY	310	2,405	60	158,559	AAC	1/1/2009
PGD	TAXIWAY C	TW C	TAXIWAY	315	600	75	23,546	AAC	9/1/2016
PGD	TAXIWAY C	TW C	TAXIWAY	350	60	25	3,675	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	102	1,400	50	83,519	AC	1/1/2002
PGD	TAXIWAY D	TW D	TAXIWAY	115	4,280	50	214,000	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	120	725	50	43,181	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	155	90	25	4,146	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	160	65	27	2,534	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	172	55	60	3,508	AC	1/1/1992
PGD	TAXIWAY D	TW D	TAXIWAY	180	300	25	10,800	AC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	195	52	25	3,304	AC	1/1/1993
PGD	TAXIWAY E	TW E	TAXIWAY	410	895	25	19,242	AC	1/1/2006
PGD	TAXIWAY E	TW E	TAXIWAY	415	4,588	25	70,611	AC	1/1/2004
PGD	TAXIWAY E1	TW E1	TAXIWAY	450	200	30	7,748	AC	1/1/2010
PGD	TAXIWAY F	TW F	TAXIWAY	1105	750	50	50,341	AC	12/25/1999
PGD	TAXIWAY G	TW G	TAXIWAY	110	505	50	34,930	AAC	1/1/1993
PGD	TAXIWAY TO NORTH T-HANGARS	TW N T-HAN	TAXIWAY	215	250	25	6,938	AC	1/1/1989
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4405	300	75	22,295	AC	1/1/1992
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4410	234	66	15,629	AC	1/1/1990
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4415	184	30	7,080	AC	12/25/1999
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4420	519	30	45,846	AC	1/1/1992
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4425	475	30	27,208	AC	1/1/1992
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4430	500	30	14,668	AC	1/1/2003



PAGE INTENTIONALLY LEFT BLANK

Chapter 4





Chapter 4 – Airfield Pavement Condition


The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

4.1 Airfield Pavement Condition Index (Latest Inspection)

4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.

Figure 4.1.1 Latest Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (d)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.



Figure 4.1.2 (a) Latest Condition – Runway Pavements




Figure 4.1.2 (b) Latest Condition – Taxiway Pavements






Figure 4.1.2 (c) Latest Condition – Apron Pavements





Figure 4.1.2 (d) Latest Condition – Taxiway Pavements





4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement.

Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.



Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
PGD	AP MAIN	MAIN APRON	APRON	4205	278,175	PCC	87	Good	0%	13%	87%	3	27
PGD	AP MAIN	MAIN APRON	APRON	4206	194,550	AC	77	Satisfactory	94%	0%	6%	5	40
PGD	AP MAIN	MAIN APRON	APRON	4208	10,625	PCC	63	Fair	0%	0%	100%	1	4
PGD	AP MAIN	MAIN APRON	APRON	4210	14,657	AC	88	Good	100%	0%	0%	1	4
PGD	AP MAIN	MAIN APRON	APRON	4215	32,858	AC	76	Satisfactory	100%	0%	0%	1	9
PGD	AP MAIN	MAIN APRON	APRON	4220	31,145	AC	80	Satisfactory	100%	0%	0%	1	8
PGD	AP MAIN	MAIN APRON	APRON	4225	102,541	PCC	100	Good	0%	0%	0%	0	11
PGD	AP MAIN	MAIN APRON	APRON	4230	30,430	AC	100	Good	0%	0%	0%	0	8
PGD	AP N	NORTH APRON	APRON	4305	221,433	AC	56	Fair	93%	0%	7%	6	46
PGD	AP N	NORTH APRON	APRON	4320	98,202	AC	59	Fair	98%	0%	2%	3	21
PGD	AP S	SOUTH GA APRON	APRON	4105	192,015	AC	53	Poor	98%	0%	2%	4	38
PGD	RW 15-33	RUNWAY 15-33	RUNWAY	6205	6,582	AAC	65	Fair	100%	0%	0%	1	1
PGD	RW 15-33	RUNWAY 15-33	RUNWAY	6210	494,128	AAC	59	Fair	69%	12%	19%	20	99
PGD	RW 15-33	RUNWAY 15-33	RUNWAY	6215	253,378	AAC	68	Fair	92%	0%	8%	11	51
PGD	RW 15-33	RUNWAY 15-33	RUNWAY	6220	53,287	AC	66	Fair	91%	0%	9%	3	11
PGD	RW 15-33	RUNWAY 15-33	RUNWAY	6225	26,644	AC	83	Satisfactory	95%	0%	5%	2	6
PGD	RW 4-22	RUNWAY 4-22	RUNWAY	6105	520,000	AAC	50	Poor	54%	45%	1%	21	104
PGD	RW 4-22	RUNWAY 4-22	RUNWAY	6110	262,500	AAC	77	Satisfactory	100%	0%	0%	11	52
PGD	RW 4-22	RUNWAY 4-22	RUNWAY	6115	149,200	AAC	67	Fair	89%	10%	1%	5	30
PGD	RW 4-22	RUNWAY 4-22	RUNWAY	6120	72,100	AAC	78	Satisfactory	100%	0%	0%	3	14
PGD	RW 4-22	RUNWAY 4-22	RUNWAY	6125	50,300	AC	58	Fair	35%	46%	19%	2	10
PGD	RW 4-22	RUNWAY 4-22	RUNWAY	6130	25,150	AC	82	Satisfactory	79%	0%	21%	2	6
PGD	RW 9-27	RUNWAY 9-27	RUNWAY	6305	151,500	AC	60	Fair	100%	0%	0%	10	50
PGD	RW 9-27	RUNWAY 9-27	RUNWAY	6310	33,102	AC	86	Good	100%	0%	0%	2	8
PGD	TL T-HANG	TAXILANE TO T-HANGARS	TAXILANE	4505	79,013	AC	81	Satisfactory	100%	0%	0%	2	15
PGD	TW A	TAXIWAY A	TAXIWAY	320	162,031	AC	100	Good	0%	0%	0%	0	30
PGD	TW A	TAXIWAY A	TAXIWAY	330	271,000	AAC	50	Poor	40%	48%	12%	5	47
PGD	TW A2	TAXIWAY A2	TAXIWAY	365	38,414	AAC	67	Fair	54%	46%	0%	1	8
PGD	TW C	TAXIWAY C	TAXIWAY	305	48,969	AAC	72	Satisfactory	66%	34%	0%	2	11
PGD	TW C	TAXIWAY C	TAXIWAY	310	158,559	AAC	58	Fair	33%	66%	1%	4	30
PGD	TW C	TAXIWAY C	TAXIWAY	315	23,546	AAC	100	Good	0%	0%	0%	0	5
PGD	TW C	TAXIWAY C	TAXIWAY	350	3,675	AAC	62	Fair	100%	0%	0%	1	1
PGD	TW D	TAXIWAY D	TAXIWAY	102	83,519	AC	36	Very Poor	23%	68%	9%	3	17
PGD	TW D	TAXIWAY D	TAXIWAY	115	214,000	AAC	35	Very Poor	32%	67%	1%	5	43
PGD	TW D	TAXIWAY D	TAXIWAY	120	43,181	AAC	58	Fair	84%	0%	16%	2	8
PGD	TW D	TAXIWAY D	TAXIWAY	155	4,146	AAC	64	Fair	96%	0%	4%	1	1
PGD	TW D	TAXIWAY D	TAXIWAY	160	2,534	AAC	78	Satisfactory	100%	0%	0%	1	1




Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
PGD	TW D	TAXIWAY D	TAXIWAY	172	3,508	AC	58	Fair	97%	0%	3%	1	1
PGD	TW D	TAXIWAY D	TAXIWAY	180	10,800	AC	77	Satisfactory	100%	0%	0%	1	2
PGD	TW D	TAXIWAY D	TAXIWAY	195	3,304	AC	69	Fair	84%	0%	16%	1	1
PGD	TW E	TAXIWAY E	TAXIWAY	410	19,242	AC	78	Satisfactory	100%	0%	0%	1	4
PGD	TW E	TAXIWAY E	TAXIWAY	415	70,611	AC	83	Satisfactory	100%	0%	0%	2	15
PGD	TW E1	TAXIWAY E1	TAXIWAY	450	7,748	AC	62	Fair	97%	0%	3%	1	2
PGD	TW F	TAXIWAY F	TAXIWAY	1105	50,341	AC	62	Fair	99%	0%	1%	2	11
PGD	TW G	TAXIWAY G	TAXIWAY	110	34,930	AAC	54	Poor	43%	53%	4%	2	5
PGD	TW N T-HAN	TAXIWAY TO NORTH T-HANGARS	TAXIWAY	215	6,938	AC	35	Very Poor	34%	18%	48%	1	1
PGD	TW T-HANG	TAXIWAY TO T-HANGARS	TAXIWAY	4405	22,295	AC	62	Fair	81%	19%	0%	1	4
PGD	TW T-HANG	TAXIWAY TO T-HANGARS	TAXIWAY	4410	15,629	AC	59	Fair	96%	0%	4%	1	3
PGD	TW T-HANG	TAXIWAY TO T-HANGARS	TAXIWAY	4415	7,080	AC	80	Satisfactory	96%	0%	4%	1	2
PGD	TW T-HANG	TAXIWAY TO T-HANGARS	TAXIWAY	4420	45,846	AC	62	Fair	100%	0%	0%	3	11
PGD	TW T-HANG	TAXIWAY TO T-HANGARS	TAXIWAY	4425	27,208	AC	64	Fair	100%	0%	0%	2	6
PGD	TW T-HANG	TAXIWAY TO T-HANGARS	TAXIWAY	4430	14,668	AC	68	Fair	100%	0%	0%	1	4



Figure 4.1.3 is an inset view of the 2019 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits**.

Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit





4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The field PCI Survey performed at Punta Gorda Airport (PGD) was completed in December 2018. The resulting overall area-weighted average PCI value was 64 representing a condition rating of Fair. Punta Gorda Airport is serviced by three runways; Runway 4-22 is 150-ft wide and 7,193-ft long, Runway 9-27 is 60-ft wide and 2,636-ft long, and Runway 15-33 is 150-ft wide and 5,688-ft long. Portions of Taxiway A and the main apron were not inspected due to recent construction. The PCI of these areas have been set to 100, a condition rating of Good.

Based on the FAA 5010 Report as of 09/12/2019 the Airport has reported 84,113 operations for 12 months ending 12/30/2018.

4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

Runway 15-33

Runway 15-33 consists of 5 sections constructed of AC and AAC. The last construction year for Runway 15-33 was 2002. The area-weighted average PCI for Runway 15-33 is 62 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Runway 15-33 consist of Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Swelling, and Weathering.

Runway 4-22

Runway 4-22 consists of 6 sections constructed of AC and AAC. The last construction years range from 2000 to 2007. The area-weighted average PCI for Runway 4-22 is 61 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Runway 4-22 consist of Alligator Cracking, Bleeding, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Swelling, and Weathering.

Based on the structural distresses observed (Alligator Cracking and Rutting), it is indicative that the pavement is experiencing heavier or more frequent aircraft loading than what was originally anticipated based on design methodologies as prescribed by the FAA. The manifestation of structural distresses such as Alligator Cracking and Rutting are symptoms that the existing pavement structure may not be adequate. Rutting and alligator cracking are both considered major structural distresses. A rut is a surface depression in the wheel path and stems from a permanent deformation in any of the pavement layers or subgrade. It is usually caused by consolidation or lateral movement of the materials due to traffic loads. Alligator cracking appears as a series of interconnecting cracks and is caused by fatigue failure of the asphalt concrete surface under repeated traffic loading. This report has identified this runway facility for major rehabilitation, classified as “AC Restoration”. It should be noted that this program level identification of major rehabilitation need is for planning purposes, based on the aforementioned



distresses it is recommended that further evaluation and investigation is performed in order to identify if select reconstruction efforts would be of benefit in addressing the structural distresses.

Runway 9-27

Runway 9-27 consists of 2 sections constructed of AC. The last construction year for Runway 9-27 was 2006. The area-weighted average PCI for Runway 9-27 is 64 representing a Fair condition rating. The pavement distresses observed were related to Climate distress classifications. Distresses observed on Runway 9-27 consist of Depression, Longitudinal & Transverse Cracking, Patching, Raveling, and Weathering.

Taxiway A

Taxiway A consists of 2 sections constructed of AC and AAC. The last construction years range from 2009 to 2016. The area-weighted average PCI for Taxiway A is 68 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Taxiway A consist of Alligator Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Swelling, Weathering,

Taxiway D

Taxiway D consists of 8 sections constructed of AC and AAC. The last construction years range from 1992 to 2002. The area-weighted average PCI for Taxiway D is 40 representing a Very Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Taxiway D consist of Alligator Cracking, Block Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Shoving, Slippage Cracking, Swelling, and Weathering.

Taxiway G

Taxiway G consists of 1 section constructed of AAC. The last construction year for Taxiway G was 1993. The area-weighted average PCI for Taxiway G is 54 representing a Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Taxiway G consist of Alligator Cracking, Longitudinal & Transverse Cracking, Raveling, Rutting, Swelling, and Weathering.

Main Apron

Main Apron consists of 8 sections constructed of AC and PCC. The last construction years range from 1995 to 2018. The area-weighted average PCI for Main Apron is 85 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Main Apron consist of Bleeding, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Weathering, Linear Cracking, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

*Figure 4.2.2 Pavement Condition Summary by Facility Use*

Facility Use	Area-Weighted Average PCI	Condition Rating
Runway	62	Fair
Taxiway	60	Fair
Apron	72	Satisfactory
Taxilane	81	Satisfactory

4.3 Forecasted Pavement Conditions

4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to develop forecasted PCI values based on historic trends and statistical models.

4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2020 through January 2029.



Figure 4.3.2 (a) Forecasted Runway Pavement Performance




Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance







Figure 4.3.2 (c) Forecasted Apron Pavement Performance



4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.



Table 4.3.3 Forecasted PCI 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
PGD	AP MAIN	4205	87	86	85	84	84	83	82	81	80	80	79
PGD	AP MAIN	4206	77	75	73	72	70	68	67	65	64	62	61
PGD	AP MAIN	4208	63	61	59	57	55	53	52	50	48	46	44
PGD	AP MAIN	4210	88	86	84	83	81	79	78	76	75	73	72
PGD	AP MAIN	4215	76	74	72	71	69	67	66	64	63	61	60
PGD	AP MAIN	4220	80	78	76	75	73	71	70	68	67	65	64
PGD	AP MAIN	4225	100	96	94	93	91	90	89	88	87	86	86
PGD	AP MAIN	4230	100	97	96	94	92	91	89	88	86	85	83
PGD	AP N	4305	56	54	52	51	49	47	46	44	43	41	40
PGD	AP N	4320	59	57	55	54	52	50	49	47	46	44	43
PGD	AP S	4105	53	51	49	48	46	44	43	41	40	38	37
PGD	RW 15-33	6205	65	62	59	57	55	54	54	54	54	53	52
PGD	RW 15-33	6210	59	56	55	54	54	54	54	52	52	51	50
PGD	RW 15-33	6215	68	64	62	59	57	55	54	54	54	54	53
PGD	RW 15-33	6220	66	64	62	60	58	57	55	53	51	50	48
PGD	RW 15-33	6225	83	81	79	77	75	74	72	70	68	67	65
PGD	RW 4-22	6105	50	49	48	48	47	47	46	45	45	44	44
PGD	RW 4-22	6110	77	75	73	70	68	65	62	60	57	56	55
PGD	RW 4-22	6115	67	63	61	58	56	55	54	54	54	54	52
PGD	RW 4-22	6120	78	76	74	72	70	67	64	61	59	57	55
PGD	RW 4-22	6125	58	56	54	52	50	49	47	45	43	42	40
PGD	RW 4-22	6130	82	80	78	76	74	73	71	69	67	66	64
PGD	RW 9-27	6305	60	58	56	54	52	51	49	47	45	44	42
PGD	RW 9-27	6310	86	84	82	80	78	77	75	73	71	70	68
PGD	TL T-HANG	4505	81	79	77	76	75	73	72	71	70	69	68




Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
PGD	TW A	320	100	93	91	89	87	85	83	82	80	79	77
PGD	TW A	330	50	49	48	47	45	44	43	41	39	37	35
PGD	TW A2	365	67	65	64	62	61	60	59	58	57	57	56
PGD	TW C	305	72	70	68	66	65	64	62	61	60	59	58
PGD	TW C	310	58	57	56	55	55	54	54	53	52	52	51
PGD	TW C	315	100	90	88	85	83	80	78	76	74	72	70
PGD	TW C	350	62	60	59	58	58	57	56	55	55	54	54
PGD	TW D	102	36	33	30	26	23	19	15	11	8	4	0
PGD	TW D	115	35	32	29	25	22	18	13	8	3	0	0
PGD	TW D	120	58	57	56	55	55	54	54	53	52	52	51
PGD	TW D	155	64	62	61	60	59	58	57	57	56	55	55
PGD	TW D	160	78	75	73	71	70	68	66	65	64	62	61
PGD	TW D	172	58	57	56	55	54	53	51	50	49	47	46
PGD	TW D	180	77	75	74	73	71	70	69	68	67	66	66
PGD	TW D	195	69	67	67	66	65	64	63	63	62	61	60
PGD	TW E	410	78	76	75	73	72	71	70	69	68	67	66
PGD	TW E	415	83	81	79	78	76	75	74	72	71	70	69
PGD	TW E1	450	62	61	60	59	59	58	57	56	55	54	53
PGD	TW F	1105	62	61	60	59	59	58	57	56	55	54	53
PGD	TW G	110	54	53	52	52	51	50	50	49	48	47	46
PGD	TW N T-HAN	215	35	31	28	25	21	18	14	10	6	3	0
PGD	TW T-HANG	4405	62	61	60	59	59	58	57	56	55	54	53
PGD	TW T-HANG	4410	59	58	57	56	55	54	53	52	51	49	48
PGD	TW T-HANG	4415	80	78	76	75	74	73	71	70	69	68	67
PGD	TW T-HANG	4420	62	61	60	59	59	58	57	56	55	54	53
PGD	TW T-HANG	4425	64	63	62	61	61	60	59	58	57	57	56
PGD	TW T-HANG	4430	68	67	66	65	64	63	63	62	61	60	60



4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA **AC 150/5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements** to determine structural and/or functional conditions at the time of project.

Chapter 5





Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- **Localized Maintenance and Repair** includes patching and crack sealing.
- **Global Treatments** include surface seals and rejuvenators for flexible pavements.
- **Major Rehabilitation** includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distressed pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety (“stopgap”) measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.



5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2 (a)** and **Table 5.2 (b)**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and the **FDOT Airfield Pavement Distress Repair Manual**. Additionally, the **Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements** was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft



Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L & T CR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt



Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$12.50	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$5.50	SqFt

Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$185.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in **5.2 Localized M&R Policy**. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. **Appendix B** provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to near-term Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3 (a)** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - SURFACE SEAL	PREVENTIVE	395,830	SqFt	\$ 217,710.00
FDOT - MILLING - AC	PREVENTIVE	15	SqFt	\$ 30.00
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	630	SqFt	\$ 7,880.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	6,560	SqFt	\$ 36,080.00
FDOT - CRACK SEALING - AC	PREVENTIVE	2,590	Ft	\$ 7,760.00
FDOT - CRACK SEALING - PCC	PREVENTIVE	130	Ft	\$ 540.00
FDOT - CRACK SEALING - PCC	STOPGAP	85	Ft	\$ 360.00
FDOT - PATCHING - PCC PARTIAL DEPTH	STOPGAP	160	SqFt	\$ 11,300.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	51,760	SqFt	\$ 647,000.00
FDOT - CRACK SEALING - AC	STOPGAP	24,470	Ft	\$ 73,400.00
FDOT - SURFACE SEAL	STOPGAP	1,716,510	SqFt	\$ 944,090.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	50,885	SqFt	\$ 279,870.00



The following **Table 5.3 (b)** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved “End Condition” of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
PGD	AP MAIN	4205	278,175	87	87	\$ 540.00
PGD	AP MAIN	4206	194,550	77	90	\$ 32,510.00
PGD	AP MAIN	4208	10,625	63	76	\$ 11,660.00
PGD	AP MAIN	4210	14,657	88	94	\$ 430.00
PGD	AP MAIN	4215	32,858	76	82	\$ 1,450.00
PGD	AP MAIN	4220	31,145	80	91	\$ 2,290.00
PGD	AP MAIN	4225	102,541	100	100	\$ -
PGD	AP MAIN	4230	30,430	100	100	\$ -
PGD	AP N	4305	221,433	56	70	\$ 138,450.00
PGD	AP N	4320	98,202	59	71	\$ 48,130.00
PGD	AP S	4105	192,015	53	63	\$ 232,630.00
PGD	RW 15-33	6205	6,582	65	89	\$ 3,680.00
PGD	RW 15-33	6210	494,128	59	73	\$ 253,140.00
PGD	RW 15-33	6215	253,378	68	80	\$ 84,250.00
PGD	RW 15-33	6220	53,287	66	78	\$ 28,300.00
PGD	RW 15-33	6225	26,644	83	92	\$ 1,570.00
PGD	RW 4-22	6105	520,000	50	66	\$ 334,440.00
PGD	RW 4-22	6110	262,500	77	85	\$ 20,560.00
PGD	RW 4-22	6115	149,200	67	83	\$ 71,070.00
PGD	RW 4-22	6120	72,100	78	83	\$ 1,990.00
PGD	RW 4-22	6125	50,300	58	70	\$ 12,970.00
PGD	RW 4-22	6130	25,150	82	93	\$ 4,790.00
PGD	RW 9-27	6305	151,500	60	79	\$ 131,210.00
PGD	RW 9-27	6310	33,102	86	92	\$ 920.00
PGD	TL T-HANG	4505	79,013	81	89	\$ 4,350.00
PGD	TW A	320	162,031	100	100	\$ -
PGD	TW A	330	271,000	50	62	\$ 132,420.00
PGD	TW A2	365	38,414	67	72	\$ 3,260.00
PGD	TW C	305	48,969	72	81	\$ 4,560.00
PGD	TW C	310	158,559	58	66	\$ 27,210.00
PGD	TW C	315	23,546	100	100	\$ -
PGD	TW C	350	3,675	62	70	\$ 710.00




Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
PGD	TW D	102	83,519	36	58	\$ 162,380.00
PGD	TW D	115	214,000	35	56	\$ 308,720.00
PGD	TW D	120	43,181	58	73	\$ 19,000.00
PGD	TW D	155	4,146	64	74	\$ 380.00
PGD	TW D	160	2,534	78	83	\$ 170.00
PGD	TW D	172	3,508	58	69	\$ 530.00
PGD	TW D	180	10,800	77	82	\$ 550.00
PGD	TW D	195	3,304	69	84	\$ 320.00
PGD	TW E	410	19,242	78	83	\$ 530.00
PGD	TW E	415	70,611	83	89	\$ 1,870.00
PGD	TW E1	450	7,748	62	90	\$ 4,690.00
PGD	TW F	1105	50,341	62	76	\$ 32,280.00
PGD	TW G	110	34,930	54	62	\$ 10,550.00
PGD	TW N T-HAN	215	6,938	35	75	\$ 11,070.00
PGD	TW T-HANG	4405	22,295	62	76	\$ 12,270.00
PGD	TW T-HANG	4410	15,629	59	80	\$ 16,070.00
PGD	TW T-HANG	4415	7,080	80	85	\$ 240.00
PGD	TW T-HANG	4420	45,846	62	79	\$ 34,220.00
PGD	TW T-HANG	4425	27,208	64	81	\$ 17,600.00
PGD	TW T-HANG	4430	14,668	68	75	\$ 3,620.00

The following **Table 5.3 (c)** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (c) Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 270,000.00
Stopgap	\$ 1,956,020.00
Planning-Level Localized M&R Needs =	\$ 2,226,020.00

Chapter 6






Chapter 6 – Major Rehabilitation Planning

6.1 Major Rehabilitation


Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1 (a) and 6.1 (b)** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, $PCI \leq \text{Critical PCI}$





Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, $PCI > \text{Critical } PCI$





6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The **Critical PCI** concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

1. Develop a pavement performance model and refine a prediction model for the pavements considered.
2. Select a localized maintenance and repair policy to be used in developing a work plan.
3. Apply the selected localized policy to the pavement sections for a range of PCI.
4. Compute the unit cost per area for each PCI range.
5. Plot the cost versus the PCI.
6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended **Minimum Service-Level PCI** for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	70	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	65	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)



6.2 Major Rehabilitation Policy

6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA **AC 150/5320-6F "Airport Pavement Design and Evaluation."** It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following **Tables 6.2.1 (a) and (b)** provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average PR Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete

Rehabilitation Type	Commercial (PR) Airport
AC Restoration <i>Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.</i> PCI = 41 to 65	75% Mill and Overlay P-101 AC Milling (4") P-603 Bituminous Tack P-401 (HMA) (4") 25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (6") <i>Excludes any paved shoulder features.</i>
AC Reconstruction <i>Full-depth asphalt pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (6") <i>Excludes any paved shoulder features.</i>



Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete

Rehabilitation Type	Commercial (PR) Airport
PCC Restoration <i>Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.</i> PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (16") *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction <i>Full-depth rigid pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (6") P-501 Rigid PCC (17")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

The recommendations identified in the Major Rehabilitation Needs consider the **FAA AC 150/5370-10H Standard Specifications for Construction of Airports** when determining the appropriate materials and methods implemented for construction projects, such as pavement rehabilitation, on airports. It should be noted that the **AC 150/5370-10H Standard Specifications for Construction of Airports** was updated in December of 2018. Design-level determination of project specific specifications based on the AC should be developed by the Airport when performing applicable construction projects.



6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Flexible Asphalt Concrete Cost Per SF	Rigid Portland Cement Concrete Cost per SF
Restoration	41 to 65	\$ 11.00	\$ 17.00
Reconstruction	0 to 40	\$ 14.00	\$ 23.00

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level



investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.

Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	PGD	AP MAIN	4208	PCC	10,625	61	PCC Restoration	\$ 181,000.00
2020	PGD	AP N	4305	AC	221,433	54	AC Restoration	\$ 2,436,000.00
2020	PGD	AP N	4320	AC	98,202	57	AC Restoration	\$ 1,081,000.00
2020	PGD	AP S	4105	AC	192,015	51	AC Restoration	\$ 2,113,000.00
2020	PGD	RW 15-33	6205	AAC	6,582	62	AC Restoration	\$ 73,000.00
2020	PGD	RW 15-33	6210	AAC	494,128	56	AC Restoration	\$ 5,436,000.00
2020	PGD	RW 15-33	6215	AAC	253,378	64	AC Restoration	\$ 2,788,000.00
2020	PGD	RW 15-33	6220	AC	53,287	64	AC Restoration	\$ 587,000.00
2020	PGD	RW 4-22	6105	AAC	520,000	49	AC Restoration	\$ 5,819,000.00
2020	PGD	RW 4-22	6115	AAC	149,200	63	AC Restoration	\$ 1,642,000.00
2020	PGD	RW 4-22	6125	AC	50,300	56	AC Restoration	\$ 554,000.00
2020	PGD	RW 9-27	6305	AC	151,500	58	AC Restoration	\$ 1,667,000.00
2020	PGD	TW A	330	AAC	271,000	49	AC Restoration	\$ 3,054,000.00
2020	PGD	TW C	310	AAC	158,559	57	AC Restoration	\$ 1,745,000.00
2020	PGD	TW C	350	AAC	3,675	60	AC Restoration	\$ 41,000.00
2020	PGD	TW D	102	AC	83,519	33	AC Reconstruction	\$ 1,170,000.00
2020	PGD	TW D	115	AAC	214,000	32	AC Reconstruction	\$ 2,996,000.00
2020	PGD	TW D	120	AAC	43,181	57	AC Restoration	\$ 475,000.00
2020	PGD	TW D	155	AAC	4,146	62	AC Restoration	\$ 46,000.00
2020	PGD	TW D	172	AC	3,508	57	AC Restoration	\$ 39,000.00
2020	PGD	TW E1	450	AC	7,748	61	AC Restoration	\$ 86,000.00
2020	PGD	TW F	1105	AC	50,341	61	AC Restoration	\$ 554,000.00
2020	PGD	TW G	110	AAC	34,930	53	AC Restoration	\$ 385,000.00
2020	PGD	TW N T-HAN	215	AC	6,938	31	AC Reconstruction	\$ 98,000.00
2020	PGD	TW T-HANG	4405	AC	22,295	61	AC Restoration	\$ 246,000.00
2020	PGD	TW T-HANG	4410	AC	15,629	58	AC Restoration	\$ 172,000.00
2020	PGD	TW T-HANG	4420	AC	45,846	61	AC Restoration	\$ 505,000.00
2020	PGD	TW T-HANG	4425	AC	27,208	63	AC Restoration	\$ 300,000.00
2021	PGD	TW A2	365	AAC	38,414	64	AC Restoration	\$ 423,000.00
2023	PGD	TW T-HANG	4430	AC	14,668	64	AC Restoration	\$ 162,000.00
2024	PGD	TW C	305	AAC	48,969	64	AC Restoration	\$ 539,000.00
2024	PGD	TW D	195	AC	3,304	64	AC Restoration	\$ 37,000.00
2025	PGD	RW 4-22	6110	AAC	262,500	62	AC Restoration	\$ 2,888,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2025	PGD	RW 4-22	6120	AAC	72,100	64	AC Restoration	\$ 794,000.00
2026	PGD	AP MAIN	4215	AC	32,858	64	AC Restoration	\$ 362,000.00
2027	PGD	AP MAIN	4206	AC	194,550	64	AC Restoration	\$ 2,140,000.00
2027	PGD	TW D	160	AAC	2,534	64	AC Restoration	\$ 28,000.00
2029	PGD	AP MAIN	4220	AC	31,145	64	AC Restoration	\$ 343,000.00
2029	PGD	RW 4-22	6130	AC	25,150	64	AC Restoration	\$ 277,000.00

**All values have been rounded to the nearest thousand-dollar.*

The following **Figure 6.3.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2020 and 2029. **Figure 6.3.1 (b)** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.

Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year








Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit



Chapter 7





Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and re-inspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2020-2029. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- ▶ Develop a detailed preventive maintenance program for the airport.
- ▶ Further refine and implement the identified 10-year major rehabilitation needs.
- ▶ Maintain detailed records on pavement maintenance, construction, and inspection.
- ▶ Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



7.2 Supporting Documents

001 – Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

002 – Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the **Airport Response Form** provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

003 – Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

004 – Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation**. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.



7.3 Conclusion

The FDOT SAPMP Update Phase 2 2018-2019 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars **150/5380-7B “Airport Pavement Management Program (PMP)”** and **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** FDOT’s implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Appendix A

Airfield Pavement Analysis Tables



Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PGD	MAIN APRON	AP MAIN	APRON	4205	600	300	278,175	PCC	1/1/2009
PGD	MAIN APRON	AP MAIN	APRON	4206	950	300	194,550	AC	1/1/2009
PGD	MAIN APRON	AP MAIN	APRON	4208	300	30	10,625	PCC	12/25/1995
PGD	MAIN APRON	AP MAIN	APRON	4210	200	75	14,657	AC	1/1/2007
PGD	MAIN APRON	AP MAIN	APRON	4215	440	75	32,858	AC	1/1/2007
PGD	MAIN APRON	AP MAIN	APRON	4220	430	75	31,145	AC	1/1/2009
PGD	MAIN APRON	AP MAIN	APRON	4225	400	300	102,541	PCC	7/2/2018
PGD	MAIN APRON	AP MAIN	APRON	4230	400	75	30,430	AC	7/2/2018
PGD	NORTH APRON	AP N	APRON	4305	1,065	200	221,433	AC	12/25/1999
PGD	NORTH APRON	AP N	APRON	4320	830	140	98,202	AC	12/25/1999
PGD	SOUTH GA APRON	AP S	APRON	4105	845	200	192,015	AC	1/1/1992
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6205	75	87	6,582	AAC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6210	4,945	100	494,128	AAC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6215	9,890	25	253,378	AAC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6220	530	100	53,287	AC	1/1/2002
PGD	RUNWAY 15-33	RW 15-33	RUNWAY	6225	1,066	25	26,644	AC	1/1/2002
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6105	5,200	100	520,000	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6110	10,500	25	262,500	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6115	1,492	100	149,200	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6120	2,884	25	72,100	AAC	1/1/2000
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6125	500	100	50,300	AC	1/1/2007
PGD	RUNWAY 4-22	RW 4-22	RUNWAY	6130	500	50	25,150	AC	1/1/2007
PGD	RUNWAY 9-27	RW 9-27	RUNWAY	6305	2,525	60	151,500	AC	1/1/2006
PGD	RUNWAY 9-27	RW 9-27	RUNWAY	6310	338	60	33,102	AC	1/1/2006
PGD	TAXILANE TO T-HANGARS	TL T-HANG	TAXILANE	4505	2,835	25	79,013	AC	1/1/2006
PGD	TAXIWAY A	TW A	TAXIWAY	320	2,100	60	162,031	AC	9/1/2016
PGD	TAXIWAY A	TW A	TAXIWAY	330	2,325	60	271,000	AAC	1/1/2009
PGD	TAXIWAY A2	TW A2	TAXIWAY	365	295	90	38,414	AAC	1/1/2009
PGD	TAXIWAY C	TW C	TAXIWAY	305	428	50	48,969	AAC	1/1/1993
PGD	TAXIWAY C	TW C	TAXIWAY	310	2,405	60	158,559	AAC	1/1/2009
PGD	TAXIWAY C	TW C	TAXIWAY	315	600	75	23,546	AAC	9/1/2016
PGD	TAXIWAY C	TW C	TAXIWAY	350	60	25	3,675	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	102	1,400	50	83,519	AC	1/1/2002
PGD	TAXIWAY D	TW D	TAXIWAY	115	4,280	50	214,000	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	120	725	50	43,181	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	155	90	25	4,146	AAC	1/1/1993



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
PGD	TAXIWAY D	TW D	TAXIWAY	160	65	27	2,534	AAC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	172	55	60	3,508	AC	1/1/1992
PGD	TAXIWAY D	TW D	TAXIWAY	180	300	25	10,800	AC	1/1/1993
PGD	TAXIWAY D	TW D	TAXIWAY	195	52	25	3,304	AC	1/1/1993
PGD	TAXIWAY E	TW E	TAXIWAY	410	895	25	19,242	AC	1/1/2006
PGD	TAXIWAY E	TW E	TAXIWAY	415	4,588	25	70,611	AC	1/1/2004
PGD	TAXIWAY E1	TW E1	TAXIWAY	450	200	30	7,748	AC	1/1/2010
PGD	TAXIWAY F	TW F	TAXIWAY	1105	750	50	50,341	AC	12/25/1999
PGD	TAXIWAY G	TW G	TAXIWAY	110	505	50	34,930	AAC	1/1/1993
PGD	TAXIWAY TO NORTH T-HANGARS	TW N T-HAN	TAXIWAY	215	250	25	6,938	AC	1/1/1989
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4405	300	75	22,295	AC	1/1/1992
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4410	234	66	15,629	AC	1/1/1990
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4415	184	30	7,080	AC	12/25/1999
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4420	519	30	45,846	AC	1/1/1992
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4425	475	30	27,208	AC	1/1/1992
PGD	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	4430	500	30	14,668	AC	1/1/2003



Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PGD	RUNWAY 4-22	RUNWAY	6105	520,000	50	Poor
PGD	RUNWAY 4-22	RUNWAY	6110	262,500	77	Satisfactory
PGD	RUNWAY 4-22	RUNWAY	6115	149,200	67	Fair
PGD	RUNWAY 4-22	RUNWAY	6120	72,100	78	Satisfactory
PGD	RUNWAY 4-22	RUNWAY	6125	50,300	58	Fair
PGD	RUNWAY 4-22	RUNWAY	6130	25,150	82	Satisfactory
PGD	RUNWAY 15-33	RUNWAY	6205	6,582	65	Fair
PGD	RUNWAY 15-33	RUNWAY	6210	494,128	59	Fair
PGD	RUNWAY 15-33	RUNWAY	6215	253,378	68	Fair
PGD	RUNWAY 15-33	RUNWAY	6220	53,287	66	Fair
PGD	RUNWAY 15-33	RUNWAY	6225	26,644	83	Satisfactory
PGD	RUNWAY 9-27	RUNWAY	6305	151,500	60	Fair
PGD	RUNWAY 9-27	RUNWAY	6310	33,102	86	Good
PGD	TAXIWAY A	TAXIWAY	320	162,031	100	Good
PGD	TAXIWAY A	TAXIWAY	330	271,000	50	Poor
PGD	TAXIWAY A2	TAXIWAY	365	38,414	67	Fair
PGD	TAXIWAY C	TAXIWAY	305	48,969	72	Satisfactory
PGD	TAXIWAY C	TAXIWAY	310	158,559	58	Fair
PGD	TAXIWAY C	TAXIWAY	315	23,546	100	Good
PGD	TAXIWAY C	TAXIWAY	350	3,675	62	Fair
PGD	TAXIWAY D	TAXIWAY	102	83,519	36	Very Poor
PGD	TAXIWAY D	TAXIWAY	115	214,000	35	Very Poor
PGD	TAXIWAY D	TAXIWAY	120	43,181	58	Fair
PGD	TAXIWAY D	TAXIWAY	155	4,146	64	Fair
PGD	TAXIWAY D	TAXIWAY	160	2,534	78	Satisfactory
PGD	TAXIWAY D	TAXIWAY	172	3,508	58	Fair
PGD	TAXIWAY D	TAXIWAY	180	10,800	77	Satisfactory
PGD	TAXIWAY D	TAXIWAY	195	3,304	69	Fair
PGD	TAXIWAY E	TAXIWAY	410	19,242	78	Satisfactory
PGD	TAXIWAY E	TAXIWAY	415	70,611	83	Satisfactory
PGD	TAXIWAY E1	TAXIWAY	450	7,748	62	Fair
PGD	TAXIWAY F	TAXIWAY	1105	50,341	62	Fair
PGD	TAXIWAY G	TAXIWAY	110	34,930	54	Poor
PGD	TAXIWAY TO NORTH T-HANGARS	TAXIWAY	215	6,938	35	Very Poor
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4405	22,295	62	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4410	15,629	59	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4415	7,080	80	Satisfactory



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4420	45,846	62	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4425	27,208	64	Fair
PGD	TAXIWAY TO T-HANGARS	TAXIWAY	4430	14,668	68	Fair
PGD	TAXILANE TO T-HANGARS	TAXILANE	4505	79,013	81	Satisfactory
PGD	SOUTH GA APRON	APRON	4105	192,015	53	Poor
PGD	MAIN APRON	APRON	4205	278,175	87	Good
PGD	MAIN APRON	APRON	4206	194,550	77	Satisfactory
PGD	MAIN APRON	APRON	4208	10,625	63	Fair
PGD	MAIN APRON	APRON	4210	14,657	88	Good
PGD	MAIN APRON	APRON	4215	32,858	76	Satisfactory
PGD	MAIN APRON	APRON	4220	31,145	80	Satisfactory
PGD	MAIN APRON	APRON	4225	102,541	100	Good
PGD	MAIN APRON	APRON	4230	30,430	100	Good
PGD	NORTH APRON	APRON	4305	221,433	56	Fair
PGD	NORTH APRON	APRON	4320	98,202	59	Fair



Table A-3 Forecasted PCI 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
PGD	AP MAIN	4205	87	86	85	84	84	83	82	81	80	80	79
PGD	AP MAIN	4206	77	75	73	72	70	68	67	65	64	62	61
PGD	AP MAIN	4208	63	61	59	57	55	53	52	50	48	46	44
PGD	AP MAIN	4210	88	86	84	83	81	79	78	76	75	73	72
PGD	AP MAIN	4215	76	74	72	71	69	67	66	64	63	61	60
PGD	AP MAIN	4220	80	78	76	75	73	71	70	68	67	65	64
PGD	AP MAIN	4225	100	96	94	93	91	90	89	88	87	86	86
PGD	AP MAIN	4230	100	97	96	94	92	91	89	88	86	85	83
PGD	AP N	4305	56	54	52	51	49	47	46	44	43	41	40
PGD	AP N	4320	59	57	55	54	52	50	49	47	46	44	43
PGD	AP S	4105	53	51	49	48	46	44	43	41	40	38	37
PGD	RW 15-33	6205	65	62	59	57	55	54	54	54	54	53	52
PGD	RW 15-33	6210	59	56	55	54	54	54	54	52	52	51	50
PGD	RW 15-33	6215	68	64	62	59	57	55	54	54	54	54	53
PGD	RW 15-33	6220	66	64	62	60	58	57	55	53	51	50	48
PGD	RW 15-33	6225	83	81	79	77	75	74	72	70	68	67	65
PGD	RW 4-22	6105	50	49	48	48	47	47	46	45	45	44	44
PGD	RW 4-22	6110	77	75	73	70	68	65	62	60	57	56	55
PGD	RW 4-22	6115	67	63	61	58	56	55	54	54	54	54	52
PGD	RW 4-22	6120	78	76	74	72	70	67	64	61	59	57	55
PGD	RW 4-22	6125	58	56	54	52	50	49	47	45	43	42	40
PGD	RW 4-22	6130	82	80	78	76	74	73	71	69	67	66	64
PGD	RW 9-27	6305	60	58	56	54	52	51	49	47	45	44	42
PGD	RW 9-27	6310	86	84	82	80	78	77	75	73	71	70	68
PGD	TL T-HANG	4505	81	79	77	76	75	73	72	71	70	69	68
PGD	TW A	320	100	93	91	89	87	85	83	82	80	79	77
PGD	TW A	330	50	49	48	47	45	44	43	41	39	37	35
PGD	TW A2	365	67	65	64	62	61	60	59	58	57	57	56
PGD	TW C	305	72	70	68	66	65	64	62	61	60	59	58
PGD	TW C	310	58	57	56	55	55	54	54	53	52	52	51
PGD	TW C	315	100	90	88	85	83	80	78	76	74	72	70
PGD	TW C	350	62	60	59	58	58	57	56	55	55	54	54
PGD	TW D	102	36	33	30	26	23	19	15	11	8	4	0
PGD	TW D	115	35	32	29	25	22	18	13	8	3	0	0
PGD	TW D	120	58	57	56	55	55	54	54	53	52	52	51
PGD	TW D	155	64	62	61	60	59	58	57	57	56	55	55
PGD	TW D	160	78	75	73	71	70	68	66	65	64	62	61



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
PGD	TW D	172	58	57	56	55	54	53	51	50	49	47	46
PGD	TW D	180	77	75	74	73	71	70	69	68	67	66	66
PGD	TW D	195	69	67	67	66	65	64	63	63	62	61	60
PGD	TW E	410	78	76	75	73	72	71	70	69	68	67	66
PGD	TW E	415	83	81	79	78	76	75	74	72	71	70	69
PGD	TW E1	450	62	61	60	59	59	58	57	56	55	54	53
PGD	TW F	1105	62	61	60	59	59	58	57	56	55	54	53
PGD	TW G	110	54	53	52	52	51	50	50	49	48	47	46
PGD	TW N T-HAN	215	35	31	28	25	21	18	14	10	6	3	0
PGD	TW T-HANG	4405	62	61	60	59	59	58	57	56	55	54	53
PGD	TW T-HANG	4410	59	58	57	56	55	54	53	52	51	49	48
PGD	TW T-HANG	4415	80	78	76	75	74	73	71	70	69	68	67
PGD	TW T-HANG	4420	62	61	60	59	59	58	57	56	55	54	53
PGD	TW T-HANG	4425	64	63	62	61	61	60	59	58	57	57	56
PGD	TW T-HANG	4430	68	67	66	65	64	63	63	62	61	60	60

12/14/2018

Work History Report

Page 1 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4205 Surface: PCC L.C.D.: 1/1/2009 Use: APRON Rank: P Length: 600.00 (Ft) Width: 300.00 (Ft) True Area: 278,175.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	SR-PC	Surface Reconstruction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	2009: PCC
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942 6-8" PCC

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4206 Surface: AC L.C.D.: 1/1/2009 Use: APRON Rank: P Length: 950.00 (Ft) Width: 300.00 (Ft) True Area: 194,550.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	2009: AC
1/1/1942	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4208 Surface: PCC L.C.D.: 12/25/199 Use: APRON Rank: P Length: 300.00 (Ft) Width: 30.00 (Ft) True Area: 10,625.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1995	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4210 Surface: AC L.C.D.: 1/1/2007 Use: APRON Rank: P Length: 200.00 (Ft) Width: 75.00 (Ft) True Area: 14,657.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	observed jan 2008

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4215 Surface: AC L.C.D.: 1/1/2007 Use: APRON Rank: P Length: 440.00 (Ft) Width: 75.00 (Ft) True Area: 32,858.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	observed Jan 2008

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4220 Surface: AC L.C.D.: 1/1/2009 Use: APRON Rank: P Length: 430.00 (Ft) Width: 75.00 (Ft) True Area: 31,145.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4225 Surface: PCC L.C.D.: 7/2/2018 Use: APRON Rank: P Length: 400.00 (Ft) Width: 300.00 (Ft) True Area: 102,541.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/2/2018	NC-PC	New Construction - PCC			<input checked="" type="checkbox"/>	

12/14/2018

Work History Report

Page 2 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR Branch: AP MAIN MAIN APRON Section: 4230 Surface: AC L.C.D.: 7/2/2018 Use: APRON Rank: P Length: 400.00 (Ft) Width: 75.00 (Ft) True Area: 30,430.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/2/2018	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: AP N NORTH APRON Section: 4305 Surface: AC L.C.D.: 12/25/199 Use: APRON Rank: P Length: 1,065.00 (Ft) Width: 200.00 (Ft) True Area: 221,433.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: AP N NORTH APRON Section: 4320 Surface: AC L.C.D.: 12/25/199 Use: APRON Rank: P Length: 830.00 (Ft) Width: 140.00 (Ft) True Area: 98,202.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: AP S SOUTH GA APR Section: 4105 Surface: AC L.C.D.: 1/1/1992 Use: APRON Rank: P Length: 845.00 (Ft) Width: 200.00 (Ft) True Area: 192,015.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1992 2" P401 ON 8" P211

Network: PUNTA GORDA AIR Branch: RW 15-33 RUNWAY 15-33 Section: 6205 Surface: AAC L.C.D.: 1/1/2002 Use: RUNWAY Rank: P Length: 75.00 (Ft) Width: 87.00 (Ft) True Area: 6,582.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1985 P-401 OL
1/1/1979	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1979 1.5-2" P-401 OL ON EXISTING

Network: PUNTA GORDA AIR Branch: RW 15-33 RUNWAY 15-33 Section: 6210 Surface: AAC L.C.D.: 1/1/2002 Use: RUNWAY Rank: P Length: 4,945.00 (Ft) Width: 100.00 (Ft) True Area: 494,128.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" MIN P-401 ON EXISTING

Network: PUNTA GORDA AIR Branch: RW 15-33 RUNWAY 15-33 Section: 6215 Surface: AAC L.C.D.: 1/1/2002 Use: RUNWAY Rank: P Length: 9,890.00 (Ft) Width: 25.00 (Ft) True Area: 253,378.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" MIN P-401 OL ON EXISTING

12/14/2018

Work History Report

Page 3 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR Branch: RW 15-33 Section: 6220 Surface: AC L.C.D.: 1/1/2002 Use: RUNWAY Rank: P Length: 530.00 (Ft) Width: 100.00 (Ft) True Area: 53,287.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, P-602, 6" P-211, P-152

Network: PUNTA GORDA AIR Branch: RW 15-33 Section: 6225 Surface: AC L.C.D.: 1/1/2002 Use: RUNWAY Rank: P Length: 1,066.00 (Ft) Width: 25.00 (Ft) True Area: 26,644.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, P-602, 6" P-211, P-152

Network: PUNTA GORDA AIR Branch: RW 4-22 Section: 6105 Surface: AAC L.C.D.: 1/1/2000 Use: RUNWAY Rank: T Length: 5,200.00 (Ft) Width: 100.00 (Ft) True Area: 520,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1985 P-401 OL
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1979	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: RW 4-22 Section: 6110 Surface: AAC L.C.D.: 1/1/2000 Use: RUNWAY Rank: P Length: 10,500.00 (Ft) Width: 25.00 (Ft) True Area: 262,500.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1985 P-401 OL
1/1/1985	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1979	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: RW 4-22 Section: 6115 Surface: AAC L.C.D.: 1/1/2000 Use: RUNWAY Rank: P Length: 1,492.00 (Ft) Width: 100.00 (Ft) True Area: 149,200.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1985 4" P-401 12" P-211
1/1/1985	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: RW 4-22 Section: 6120 Surface: AAC L.C.D.: 1/1/2000 Use: RUNWAY Rank: P Length: 2,884.00 (Ft) Width: 25.00 (Ft) True Area: 72,100.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1985 4" P-401 12" P-211
1/1/1985	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	

12/14/2018

Work History Report

Page 4 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR Branch: RW 4-22 RUNWAY 4-22 Section: 6125 Surface: AC L.C.D.: 1/1/2007 Use: RUNWAY Rank: P Length: 500.00 (Ft) Width: 100.00 (Ft) True Area: 50,300.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: RW 4-22 RUNWAY 4-22 Section: 6130 Surface: AC L.C.D.: 1/1/2007 Use: RUNWAY Rank: P Length: 500.00 (Ft) Width: 50.00 (Ft) True Area: 25,150.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: RW 9-27 RUNWAY 9-27 Section: 6305 Surface: AC L.C.D.: 1/1/2006 Use: RUNWAY Rank: T Length: 2,525.00 (Ft) Width: 60.00 (Ft) True Area: 151,500.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1942 2" BIT 6-8" LIMEROCK
1/1/1942	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: RW 9-27 RUNWAY 9-27 Section: 6310 Surface: AC L.C.D.: 1/1/2006 Use: RUNWAY Rank: P Length: 338.00 (Ft) Width: 60.00 (Ft) True Area: 33,102.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1942 2" BIT 6-8" LIMEROCK
1/1/1942	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: TL T-HANG TAXILANE TO T- Section: 4505 Surface: AC L.C.D.: 1/1/2006 Use: TAXILAN Rank: P Length: 2,835.00 (Ft) Width: 25.00 (Ft) True Area: 79,013.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: TW A2 TAXIWAY A2 Section: 365 Surface: AAC L.C.D.: 1/1/2009 Use: TAXIWAY Rank: T Length: 295.00 (Ft) Width: 90.00 (Ft) True Area: 38,414.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2009: MILL AND OVERLAY
1/1/2006	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: TW A TAXIWAY A Section: 320 Surface: AC L.C.D.: 9/1/2016 Use: TAXIWAY Rank: P Length: 2,100.00 (Ft) Width: 60.00 (Ft) True Area: 162,031.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2016	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

12/14/2018

Work History Report

Page 5 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR Branch: TW A TAXIWAY A Section: 330 Surface: AAC L.C.D.: 1/1/2009 Use: TAXIWAY Rank: P Length: 2,325.00 (Ft) Width: 60.00 (Ft) True Area: 271,000.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2009: MILL AND OVERLAY
1/1/1984	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1984 2" P-401 9" P-211 4" P-154

Network: PUNTA GORDA AIR Branch: TW C TAXIWAY C Section: 305 Surface: AAC L.C.D.: 1/1/1993 Use: TAXIWAY Rank: T Length: 428.00 (Ft) Width: 50.00 (Ft) True Area: 48,969.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1993	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1993 2" P401
1/1/1983	IMPORT ED	OVERLAY	0.00	2.50	<input checked="" type="checkbox"/>	1983 2.5" MINIMUM P401
1/1/1966	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1966 1" AC ON 8" P211

Network: PUNTA GORDA AIR Branch: TW C TAXIWAY C Section: 310 Surface: AAC L.C.D.: 1/1/2009 Use: TAXIWAY Rank: P Length: 2,405.00 (Ft) Width: 60.00 (Ft) True Area: 158,559.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2009: MILL AND OVERLAY
1/1/1977	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 9" P-211 4" LIMEROCK

Network: PUNTA GORDA AIR Branch: TW C TAXIWAY C Section: 315 Surface: AAC L.C.D.: 9/1/2016 Use: TAXIWAY Rank: P Length: 600.00 (Ft) Width: 75.00 (Ft) True Area: 23,546.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2016	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401
1/1/2009	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2009: MILL AND OVERLAY
1/1/1977	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 9" P-211 4" LIMEROCK

Network: PUNTA GORDA AIR Branch: TW C TAXIWAY C Section: 350 Surface: AAC L.C.D.: 1/1/1993 Use: TAXIWAY Rank: P Length: 60.00 (Ft) Width: 25.00 (Ft) True Area: 3,675.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1993	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	EXISTING AC PAVEMENT
1/1/1993	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1993 FEATHERED AC OVERLAY

Network: PUNTA GORDA AIR Branch: TW D TAXIWAY D Section: 102 Surface: AC L.C.D.: 1/1/2002 Use: TAXIWAY Rank: P Length: 1,400.00 (Ft) Width: 50.00 (Ft) True Area: 83,519.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, P-602, 6" P-211, P-152

12/14/2018

Work History Report

Page 6 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR		Branch: TW D		TAXIWAY D		Section: 115	Surface: AAC
L.C.D.: 1/1/1993		Use: TAXIWAY	Rank: P	Length: 4,280.00 (Ft)	Width: 50.00 (Ft)	True Area: 214,000.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	1993 3" AC OVERLAY	
1/1/1993	IMPORT ED	OVERLAY	0.00	1.00	<input checked="" type="checkbox"/>	MILL 1" AC SURFACE DURING 1993 OVERLAY	
1/1/1983	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1983 MINIMUM 1" P401 ON 1.5" P401 LEVELING COURSE	

Network: PUNTA GORDA AIR		Branch: TW D		TAXIWAY D		Section: 120	Surface: AAC
L.C.D.: 1/1/1993		Use: TAXIWAY	Rank: P	Length: 725.00 (Ft)	Width: 50.00 (Ft)	True Area: 43,181.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	IMPORT ED	OVERLAY	0.00	2.50	<input checked="" type="checkbox"/>	1993 2.5" P401 OVERLAY	
1/1/1983	IMPORT ED	BUILT	0.00	2.50	<input checked="" type="checkbox"/>	1983 2.5" MINIMUM P401 ON EXISTING BIT PAVEMENT	

Network: PUNTA GORDA AIR		Branch: TW D		TAXIWAY D		Section: 155	Surface: AAC
L.C.D.: 1/1/1993		Use: TAXIWAY	Rank: P	Length: 90.00 (Ft)	Width: 25.00 (Ft)	True Area: 4,146.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1993 FEATHERED AC OVERLAY	
1/1/1992	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1992 AC PAVEMENT 2" P401 ON 8"	

Network: PUNTA GORDA AIR		Branch: TW D		TAXIWAY D		Section: 160	Surface: AAC
L.C.D.: 1/1/1993		Use: TAXIWAY	Rank: P	Length: 65.00 (Ft)	Width: 27.00 (Ft)	True Area: 2,534.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1993 FEATHERED AC OVERLAY	
1/1/1993	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	EXISTING AC PAVEMENT	

Network: PUNTA GORDA AIR		Branch: TW D		TAXIWAY D		Section: 172	Surface: AC
L.C.D.: 1/1/1992		Use: TAXIWAY	Rank: P	Length: 55.00 (Ft)	Width: 60.00 (Ft)	True Area: 3,508.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1992	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1992 2" P401 ON 8" P211	

Network: PUNTA GORDA AIR		Branch: TW D		TAXIWAY D		Section: 180	Surface: AC
L.C.D.: 1/1/1993		Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 25.00 (Ft)	True Area: 10,800.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1993 4" P401 ON 11" P211	

12/14/2018

Work History Report

Page 7 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR		Branch: TW D		TAXIWAY D		Section: 195	Surface: AC
L.C.D.: 1/1/1993		Use: TAXIWAY	Rank: P	Length: 52.00 (Ft)	Width: 25.00 (Ft)	True Area: 3,304.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1993 4" P401 ON 11" P211	

Network: PUNTA GORDA AIR		Branch: TW E1		TAXIWAY E1		Section: 450	Surface: AC
L.C.D.: 1/1/2010		Use: TAXIWAY	Rank: P	Length: 200.00 (Ft)	Width: 30.00 (Ft)	True Area: 7,748.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2010	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PUNTA GORDA AIR		Branch: TW E		TAXIWAY E		Section: 410	Surface: AC
L.C.D.: 1/1/2006		Use: TAXIWAY	Rank: P	Length: 895.00 (Ft)	Width: 25.00 (Ft)	True Area: 19,242.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PUNTA GORDA AIR		Branch: TW E		TAXIWAY E		Section: 415	Surface: AC
L.C.D.: 1/1/2004		Use: TAXIWAY	Rank: P	Length: 4,588.00 (Ft)	Width: 25.00 (Ft)	True Area: 70,611.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2004	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PUNTA GORDA AIR		Branch: TW F		TAXIWAY F		Section: 1105	Surface: AC
L.C.D.: 12/25/199		Use: TAXIWAY	Rank: P	Length: 750.00 (Ft)	Width: 50.00 (Ft)	True Area: 50,341.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PUNTA GORDA AIR		Branch: TW G		TAXIWAY G		Section: 110	Surface: AAC
L.C.D.: 1/1/1993		Use: TAXIWAY	Rank: P	Length: 505.00 (Ft)	Width: 50.00 (Ft)	True Area: 34,930.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1993	IMPORT ED	OVERLAY	0.00	1.00	<input checked="" type="checkbox"/>	MILL 1" AC SURFACE DURING 1993 OVERLAY 1993 3" P401 OVERLAY	
1/1/1993	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1988	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1988 2" P401 ON 9" P211	

Network: PUNTA GORDA AIR		Branch: TW N T-HAN TAXIWAY TO N		TAXIWAY TO N		Section: 215	Surface: AC
L.C.D.: 1/1/1989		Use: TAXIWAY	Rank: P	Length: 250.00 (Ft)	Width: 25.00 (Ft)	True Area: 6,938.00 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1989	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1989 1.5" TYPE 3 BIT 6" LIMEROCK	

12/14/2018

Work History Report

Page 8 of 9

Pavement Database: FDOT

Network: PUNTA GORDA AIR Branch: TW T-HANG TAXIWAY TO T- Section: 4405 Surface: AC L.C.D.: 1/1/1992 Use: TAXIWAY Rank: P Length: 300.00 (Ft) Width: 75.00 (Ft) True Area: 22,295.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1992 BIT SECTION UNKNOWN

Network: PUNTA GORDA AIR Branch: TW T-HANG TAXIWAY TO T- Section: 4410 Surface: AC L.C.D.: 1/1/1990 Use: TAXIWAY Rank: P Length: 234.00 (Ft) Width: 66.00 (Ft) True Area: 15,629.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1990	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1990 BIT SECTION UNKNOWN

Network: PUNTA GORDA AIR Branch: TW T-HANG TAXIWAY TO T- Section: 4415 Surface: AC L.C.D.: 12/25/1999 Use: TAXIWAY Rank: P Length: 184.00 (Ft) Width: 30.00 (Ft) True Area: 7,080.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PUNTA GORDA AIR Branch: TW T-HANG TAXIWAY TO T- Section: 4420 Surface: AC L.C.D.: 1/1/1992 Use: TAXIWAY Rank: T Length: 519.00 (Ft) Width: 30.00 (Ft) True Area: 45,846.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1992 BIT SECTION UNKNOWN

Network: PUNTA GORDA AIR Branch: TW T-HANG TAXIWAY TO T- Section: 4425 Surface: AC L.C.D.: 1/1/1992 Use: TAXIWAY Rank: P Length: 475.00 (Ft) Width: 30.00 (Ft) True Area: 27,208.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1992 BIT SECTION UNKNOWN

Network: PUNTA GORDA AIR Branch: TW T-HANG TAXIWAY TO T- Section: 4430 Surface: AC L.C.D.: 1/1/2003 Use: TAXIWAY Rank: P Length: 500.00 (Ft) Width: 30.00 (Ft) True Area: 14,668.00 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Work History Report*Pavement Database: FDOT***Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	26	3,164,000.00	2.00	1.74
Complete Reconstruction - AC	3	379,152.00	0.00	0.00
Mill and Overlay	11	2,249,407.00	0.00	0.00
New Construction - AC	13	845,222.00	0.60	0.92
New Construction - Initial	12	665,474.00	1.00	1.73
New Construction - PCC	1	102,541.00		
OVERLAY	12	1,434,270.00	1.25	1.22
Overlay - AC Structural	2	27,692.00	0.00	0.00
Surface Reconstruction - PCC	1	278,175.00	0.00	0.00
Surface Treatment - Slurry Seal	1	98,202.00	0.00	0.00

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP MAIN	8	3,720.00	153.75	694,981.00	APRON	83.88	11.76	85.51
AP N	2	1,895.00	170.00	319,635.00	APRON	57.50	1.50	56.92
AP S	1	845.00	200.00	192,015.00	APRON	53.00	0.00	53.00
RW 15-33	5	16,506.00	67.40	834,019.00	RUNWAY	68.20	7.98	63.00
RW 4-22	6	21,076.00	66.67	1,079,250.00	RUNWAY	68.67	11.54	61.91
RW 9-27	2	2,863.00	60.00	184,602.00	RUNWAY	73.00	13.00	64.66
TL T-HANG	1	2,835.00	25.00	79,013.00	TAXILANE	81.00	0.00	81.00
TW A	2	4,425.00	60.00	433,031.00	TAXIWAY	75.00	25.00	68.71
TW A2	1	295.00	90.00	38,414.00	TAXIWAY	67.00	0.00	67.00
TW C	4	3,493.00	52.50	234,749.00	TAXIWAY	73.00	16.40	65.20
TW D	8	6,967.00	39.00	364,992.00	TAXIWAY	59.38	15.48	40.35
TW E	2	5,483.00	25.00	89,853.00	TAXIWAY	80.50	2.50	81.93
TW E1	1	200.00	30.00	7,748.00	TAXIWAY	62.00	0.00	62.00
TW F	1	750.00	50.00	50,341.00	TAXIWAY	62.00	0.00	62.00
TW G	1	505.00	50.00	34,930.00	TAXIWAY	54.00	0.00	54.00
TW N T-HA	1	250.00	25.00	6,938.00	TAXIWAY	35.00	0.00	35.00
TW T-HAN	6	2,212.00	43.50	132,726.00	TAXIWAY	65.83	6.89	63.68

12/14/2018

Branch Condition Report

Page 2 of 2

Pavement Database: FDOT

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	11	1206631.00036884	76.27	16.01	72.76
RUNWAY	13	2097871.00064127	69.15	10.71	62.58
TAXILANE	1	79013.0000241524	81.00	0.00	81.00
TAXIWAY	27	1393722.00042603	64.93	15.84	60.20
ALL	52	4777237.00146029	68.69	15.35	64.76

Pavement Database: FDOT

NetworkId: PGD

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP MAIN	4205	1/1/2009	PCC	APRON	P	0	278,175.00	12/3/2018	9	87
AP MAIN	4206	1/1/2009	AC	APRON	P	0	194,550.00	12/3/2018	9	77
AP MAIN	4208	12/25/1995	PCC	APRON	P	0	10,625.00	12/3/2018	23	63
AP MAIN	4210	1/1/2007	AC	APRON	P	0	14,657.00	12/3/2018	11	88
AP MAIN	4215	1/1/2007	AC	APRON	P	0	32,858.00	12/3/2018	11	76
AP MAIN	4220	1/1/2009	AC	APRON	P	0	31,145.00	12/3/2018	9	80
AP MAIN	4225	7/2/2018	PCC	APRON	P	0	102,541.00	7/2/2018	0	100
AP MAIN	4230	7/2/2018	AC	APRON	P	0	30,430.00	7/2/2018	0	100
AP N	4305	12/25/1999	AC	APRON	P	0	221,433.00	12/3/2018	19	56
AP N	4320	12/25/1999	AC	APRON	P	0	98,202.00	12/3/2018	19	59
AP S	4105	1/1/1992	AC	APRON	P	0	192,015.00	12/3/2018	26	53
RW 15-33	6205	1/1/2002	AAC	RUNWAY	P	0	6,582.00	12/3/2018	16	65
RW 15-33	6210	1/1/2002	AAC	RUNWAY	P	0	494,128.00	12/3/2018	16	59
RW 15-33	6215	1/1/2002	AAC	RUNWAY	P	0	253,378.00	12/3/2018	16	68
RW 15-33	6220	1/1/2002	AC	RUNWAY	P	0	53,287.00	12/3/2018	16	66
RW 15-33	6225	1/1/2002	AC	RUNWAY	P	0	26,644.00	12/3/2018	16	83
RW 4-22	6105	1/1/2000	AAC	RUNWAY	T	0	520,000.00	12/3/2018	18	50
RW 4-22	6110	1/1/2000	AAC	RUNWAY	P	0	262,500.00	12/3/2018	18	77
RW 4-22	6115	1/1/2000	AAC	RUNWAY	P	0	149,200.00	12/3/2018	18	67
RW 4-22	6120	1/1/2000	AAC	RUNWAY	P	0	72,100.00	12/3/2018	18	78
RW 4-22	6125	1/1/2007	AC	RUNWAY	P	0	50,300.00	12/3/2018	11	58
RW 4-22	6130	1/1/2007	AC	RUNWAY	P	0	25,150.00	12/3/2018	11	82
RW 9-27	6305	1/1/2006	AC	RUNWAY	T	0	151,500.00	12/3/2018	12	60
RW 9-27	6310	1/1/2006	AC	RUNWAY	P	0	33,102.00	12/3/2018	12	86
TL T-HANG	4505	1/1/2006	AC	TAXILANE	P	0	79,013.00	12/3/2018	12	81
TW A	320	9/1/2016	AC	TAXIWAY	P	0	162,031.00	9/1/2016	0	100
TW A	330	1/1/2009	AAC	TAXIWAY	P	0	271,000.00	12/3/2018	9	50
TW A2	365	1/1/2009	AAC	TAXIWAY	T	0	38,414.00	12/3/2018	9	67
TW C	305	1/1/1993	AAC	TAXIWAY	T	0	48,969.00	12/3/2018	25	72
TW C	310	1/1/2009	AAC	TAXIWAY	P	0	158,559.00	12/3/2018	9	58
TW C	315	9/1/2016	AAC	TAXIWAY	P	0	23,546.00	9/1/2016	0	100
TW C	350	1/1/1993	AAC	TAXIWAY	P	0	3,675.00	12/3/2018	25	62
TW D	102	1/1/2002	AC	TAXIWAY	P	0	83,519.00	12/3/2018	16	36
TW D	115	1/1/1993	AAC	TAXIWAY	P	0	214,000.00	12/3/2018	25	35
TW D	120	1/1/1993	AAC	TAXIWAY	P	0	43,181.00	12/3/2018	25	58
TW D	155	1/1/1993	AAC	TAXIWAY	P	0	4,146.00	12/3/2018	25	64
TW D	160	1/1/1993	AAC	TAXIWAY	P	0	2,534.00	12/3/2018	25	78
TW D	172	1/1/1992	AC	TAXIWAY	P	0	3,508.00	12/3/2018	26	58
TW D	180	1/1/1993	AC	TAXIWAY	P	0	10,800.00	12/3/2018	25	77
TW D	195	1/1/1993	AC	TAXIWAY	P	0	3,304.00	12/3/2018	25	69
TW E	410	1/1/2006	AC	TAXIWAY	P	0	19,242.00	12/3/2018	12	78
TW E	415	1/1/2004	AC	TAXIWAY	P	0	70,611.00	12/3/2018	14	83
TW E1	450	1/1/2010	AC	TAXIWAY	P	0	7,748.00	12/3/2018	8	62
TW F	1105	12/25/1999	AC	TAXIWAY	P	0	50,341.00	12/3/2018	19	62
TW G	110	1/1/1993	AAC	TAXIWAY	P	0	34,930.00	12/3/2018	25	54
TW N T-HAN	215	1/1/1989	AC	TAXIWAY	P	0	6,938.00	12/3/2018	29	35
TW T-HANG	4405	1/1/1992	AC	TAXIWAY	P	0	22,295.00	12/3/2018	26	62
TW T-HANG	4410	1/1/1990	AC	TAXIWAY	P	0	15,629.00	12/3/2018	28	59

12/14/2018		Section Condition Report						Page 2 of 3		
TW T-HANG	4415	12/25/1999	AC	TAXIWAY	P	0	7,080.00	12/3/2018	19	80
TW T-HANG	4420	1/1/1992	AC	TAXIWAY	T	0	45,846.00	12/3/2018	26	62
TW T-HANG	4425	1/1/1992	AC	TAXIWAY	P	0	27,208.00	12/3/2018	26	64
TW T-HANG	4430	1/1/2003	AC	TAXIWAY	P	0	14,668.00	12/3/2018	15	68

12/14/2018

Section Condition Report (Summary)

Page 3 of 3

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		318,548.00	4	100.00	0.00	100.00
06-10	9	979,591.00	7	68.71	12.21	68.88
11-15	12	491,101.00	10	76.00	10.01	72.21
16-20	17	2,298,394.00	14	64.71	12.26	60.59
21-25	25	376,164.00	10	63.20	11.96	47.39
26-30	27	313,439.00	7	56.14	9.25	55.87
ALL	17	4,777,237.00	52	68.69	15.35	64.76

Appendix B

Airfield Pavement Localized Maintenance and Repair and
Major Rehabilitation



Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
PGD	AP MAIN	4205	74	JOINT SPALL	Low	77.25	Slabs	8.3%	FDOT - CRACK SEALING - PCC	126.6	Ft	\$ 4.25	\$ 540.00
PGD	AP MAIN	4206	49	OIL SPILLAGE	N/A	113.45	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	160.4	SqFt	\$ 5.50	\$ 890.00
PGD	AP MAIN	4206	52	RAVELING	Low	22688.06	SqFt	11.7%	FDOT - SURFACE SEAL	22688.2	SqFt	\$ 0.55	\$ 12,480.00
PGD	AP MAIN	4206	57	WEATHERING	Medium	34788.31	SqFt	17.9%	FDOT - SURFACE SEAL	34787.9	SqFt	\$ 0.55	\$ 19,140.00
PGD	AP MAIN	4208	74	JOINT SPALL	Low	50.88	Slabs	68.8%	FDOT - CRACK SEALING - PCC	83.3	Ft	\$ 4.25	\$ 360.00
PGD	AP MAIN	4208	74	JOINT SPALL	Medium	18.5	Slabs	25.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	119.5	SqFt	\$ 72.00	\$ 8,610.00
PGD	AP MAIN	4208	75	CORNER SPALL	Medium	13.88	Slabs	18.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	37.7	SqFt	\$ 72.00	\$ 2,690.00
PGD	AP MAIN	4210	52	RAVELING	Low	781.68	SqFt	5.3%	FDOT - SURFACE SEAL	781.5	SqFt	\$ 0.55	\$ 430.00
PGD	AP MAIN	4215	52	RAVELING	Low	2628.65	SqFt	8.0%	FDOT - SURFACE SEAL	2628.6	SqFt	\$ 0.55	\$ 1,450.00
PGD	AP MAIN	4220	52	RAVELING	Low	4152.72	SqFt	13.3%	FDOT - SURFACE SEAL	4152.7	SqFt	\$ 0.55	\$ 2,290.00
PGD	AP N	4305	45	DEPRESSION	Low	366.19	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	447.8	SqFt	\$ 12.50	\$ 5,600.00
PGD	AP N	4305	48	L & T CR	Medium	3531.99	Ft	1.6%	FDOT - CRACK SEALING - AC	3532.2	Ft	\$ 3.00	\$ 10,600.00
PGD	AP N	4305	50	PATCHING	Medium	16.25	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	36.6	SqFt	\$ 12.50	\$ 460.00
PGD	AP N	4305	52	RAVELING	Low	44434.71	SqFt	20.1%	FDOT - SURFACE SEAL	44434.5	SqFt	\$ 0.55	\$ 24,440.00
PGD	AP N	4305	57	WEATHERING	Medium	176982.04	SqFt	79.9%	FDOT - SURFACE SEAL	176982.4	SqFt	\$ 0.55	\$ 97,350.00
PGD	AP N	4320	48	L & T CR	Medium	2799.87	Ft	2.9%	FDOT - CRACK SEALING - AC	2799.9	Ft	\$ 3.00	\$ 8,400.00
PGD	AP N	4320	52	RAVELING	Low	69260.17	SqFt	70.5%	FDOT - SURFACE SEAL	69260.4	SqFt	\$ 0.55	\$ 38,100.00
PGD	AP N	4320	57	WEATHERING	Medium	2947.27	SqFt	3.0%	FDOT - SURFACE SEAL	2947.2	SqFt	\$ 0.55	\$ 1,630.00
PGD	AP S	4105	48	L & T CR	Medium	1592.32	Ft	0.8%	FDOT - CRACK SEALING - AC	1592.2	Ft	\$ 3.00	\$ 4,780.00
PGD	AP S	4105	52	RAVELING	Low	28268.4	SqFt	14.7%	FDOT - SURFACE SEAL	28268.2	SqFt	\$ 0.55	\$ 15,550.00
PGD	AP S	4105	52	RAVELING	Medium	38599.71	SqFt	20.1%	FDOT - PATCHING - AC PARTIAL DEPTH	38599.4	SqFt	\$ 5.50	\$ 212,300.00
PGD	RW 15-33	6205	48	L & T CR	Medium	14.01	Ft	0.2%	FDOT - CRACK SEALING - AC	14.1	Ft	\$ 3.00	\$ 50.00
PGD	RW 15-33	6205	52	RAVELING	Low	1700.05	SqFt	25.8%	FDOT - SURFACE SEAL	1699.6	SqFt	\$ 0.55	\$ 940.00
PGD	RW 15-33	6205	57	WEATHERING	Medium	4876.05	SqFt	74.1%	FDOT - SURFACE SEAL	4876.1	SqFt	\$ 0.55	\$ 2,690.00
PGD	RW 15-33	6210	48	L & T CR	Medium	4165.49	Ft	0.8%	FDOT - CRACK SEALING - AC	4165.4	Ft	\$ 3.00	\$ 12,500.00
PGD	RW 15-33	6210	52	RAVELING	Low	159479.82	SqFt	32.3%	FDOT - SURFACE SEAL	159480.3	SqFt	\$ 0.55	\$ 87,720.00
PGD	RW 15-33	6210	52	RAVELING	Medium	370.6	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	370.3	SqFt	\$ 5.50	\$ 2,040.00
PGD	RW 15-33	6210	56	SWELLING	Medium	197.63	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	258.3	SqFt	\$ 12.50	\$ 3,230.00
PGD	RW 15-33	6210	57	WEATHERING	Medium	268435.03	SqFt	54.3%	FDOT - SURFACE SEAL	268434.7	SqFt	\$ 0.55	\$ 147,650.00
PGD	RW 15-33	6215	45	DEPRESSION	Low	4.63	SqFt	#VALUE!	FDOT - PATCHING - AC FULL DEPTH	17.2	SqFt	\$ 12.50	\$ 220.00
PGD	RW 15-33	6215	48	L & T CR	Medium	1280.71	Ft	0.5%	FDOT - CRACK SEALING - AC	1280.8	Ft	\$ 3.00	\$ 3,850.00
PGD	RW 15-33	6215	52	RAVELING	Low	70181.13	SqFt	27.7%	FDOT - SURFACE SEAL	70180.7	SqFt	\$ 0.55	\$ 38,600.00
PGD	RW 15-33	6215	52	RAVELING	Medium	594.28	SqFt	0.2%	FDOT - PATCHING - AC PARTIAL DEPTH	594.2	SqFt	\$ 5.50	\$ 3,270.00
PGD	RW 15-33	6215	57	WEATHERING	Medium	69637.44	SqFt	27.5%	FDOT - SURFACE SEAL	69637.1	SqFt	\$ 0.55	\$ 38,310.00
PGD	RW 15-33	6220	52	RAVELING	Low	15922.19	SqFt	29.9%	FDOT - SURFACE SEAL	15922	SqFt	\$ 0.55	\$ 8,760.00
PGD	RW 15-33	6220	52	RAVELING	Medium	3552.41	SqFt	6.7%	FDOT - PATCHING - AC PARTIAL DEPTH	3552.1	SqFt	\$ 5.50	\$ 19,540.00
PGD	RW 15-33	6225	52	RAVELING	Low	2851.36	SqFt	10.7%	FDOT - SURFACE SEAL	2851.4	SqFt	\$ 0.55	\$ 1,570.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
PGD	RW 4-22	6105	41	ALLIGATOR CR	Low	3065.56	SqFt	0.6%	FDOT - PATCHING - AC FULL DEPTH	3292.7	SqFt	\$ 12.50	\$ 41,160.00
PGD	RW 4-22	6105	41	ALLIGATOR CR	Medium	574.47	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	674.9	SqFt	\$ 12.50	\$ 8,440.00
PGD	RW 4-22	6105	48	L & T CR	Medium	1946.29	Ft	0.4%	FDOT - CRACK SEALING - AC	1946.2	Ft	\$ 3.00	\$ 5,840.00
PGD	RW 4-22	6105	50	PATCHING	Medium	19.81	SqFt	#VALUE!	FDOT - PATCHING - AC FULL DEPTH	42	SqFt	\$ 12.50	\$ 530.00
PGD	RW 4-22	6105	52	RAVELING	Low	107055.59	SqFt	20.6%	FDOT - SURFACE SEAL	107055.7	SqFt	\$ 0.55	\$ 58,890.00
PGD	RW 4-22	6105	57	WEATHERING	Medium	399221.38	SqFt	76.8%	FDOT - SURFACE SEAL	399221.6	SqFt	\$ 0.55	\$ 219,580.00
PGD	RW 4-22	6110	48	L & T CR	Medium	496.36	Ft	0.2%	FDOT - CRACK SEALING - AC	496.4	Ft	\$ 3.00	\$ 1,490.00
PGD	RW 4-22	6110	50	PATCHING	Medium	38.21	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	66.7	SqFt	\$ 12.50	\$ 840.00
PGD	RW 4-22	6110	52	RAVELING	Low	33127.55	SqFt	12.6%	FDOT - SURFACE SEAL	33127	SqFt	\$ 0.55	\$ 18,230.00
PGD	RW 4-22	6115	41	ALLIGATOR CR	Low	29.82	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	56	SqFt	\$ 12.50	\$ 700.00
PGD	RW 4-22	6115	48	L & T CR	Medium	805.68	Ft	0.5%	FDOT - CRACK SEALING - AC	805.8	Ft	\$ 3.00	\$ 2,420.00
PGD	RW 4-22	6115	52	RAVELING	Low	47743.97	SqFt	32.0%	FDOT - SURFACE SEAL	47744.4	SqFt	\$ 0.55	\$ 26,260.00
PGD	RW 4-22	6115	52	RAVELING	Medium	2088.84	SqFt	1.4%	FDOT - PATCHING - AC PARTIAL DEPTH	2089.3	SqFt	\$ 5.50	\$ 11,490.00
PGD	RW 4-22	6115	57	WEATHERING	Medium	54905.63	SqFt	36.8%	FDOT - SURFACE SEAL	54905.6	SqFt	\$ 0.55	\$ 30,200.00
PGD	RW 4-22	6120	52	RAVELING	Low	3605.05	SqFt	5.0%	FDOT - SURFACE SEAL	3604.8	SqFt	\$ 0.55	\$ 1,990.00
PGD	RW 4-22	6125	41	ALLIGATOR CR	Low	110.65	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	157.2	SqFt	\$ 12.50	\$ 1,970.00
PGD	RW 4-22	6125	45	DEPRESSION	Low	221.31	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	285.2	SqFt	\$ 12.50	\$ 3,570.00
PGD	RW 4-22	6125	45	DEPRESSION	Medium	201.18	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	262.6	SqFt	\$ 12.50	\$ 3,280.00
PGD	RW 4-22	6125	52	RAVELING	Low	7544.96	SqFt	15.0%	FDOT - SURFACE SEAL	7545.5	SqFt	\$ 0.55	\$ 4,150.00
PGD	RW 4-22	6130	45	DEPRESSION	Low	176.1	SqFt	0.7%	FDOT - PATCHING - AC FULL DEPTH	233.6	SqFt	\$ 12.50	\$ 2,920.00
PGD	RW 4-22	6130	52	RAVELING	Low	1760.55	SqFt	7.0%	FDOT - SURFACE SEAL	1761	SqFt	\$ 0.55	\$ 970.00
PGD	RW 4-22	6130	52	RAVELING	Medium	163.5	SqFt	0.7%	FDOT - PATCHING - AC PARTIAL DEPTH	163.6	SqFt	\$ 5.50	\$ 900.00
PGD	RW 9-27	6305	45	DEPRESSION	Low	212.05	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	274.5	SqFt	\$ 12.50	\$ 3,440.00
PGD	RW 9-27	6305	48	L & T CR	Medium	1676.61	Ft	1.1%	FDOT - CRACK SEALING - AC	1676.5	Ft	\$ 3.00	\$ 5,030.00
PGD	RW 9-27	6305	52	RAVELING	Low	102196.87	SqFt	67.5%	FDOT - SURFACE SEAL	102196.9	SqFt	\$ 0.55	\$ 56,210.00
PGD	RW 9-27	6305	52	RAVELING	Medium	9897.95	SqFt	6.5%	FDOT - PATCHING - AC PARTIAL DEPTH	9898.5	SqFt	\$ 5.50	\$ 54,440.00
PGD	RW 9-27	6305	57	WEATHERING	Medium	21967.53	SqFt	14.5%	FDOT - SURFACE SEAL	21967	SqFt	\$ 0.55	\$ 12,090.00
PGD	RW 9-27	6310	52	RAVELING	Low	1655.06	SqFt	5.0%	FDOT - SURFACE SEAL	1655.5	SqFt	\$ 0.55	\$ 920.00
PGD	TL T-HANG	4505	52	RAVELING	Low	7898.23	SqFt	10.0%	FDOT - SURFACE SEAL	7898.6	SqFt	\$ 0.55	\$ 4,350.00
PGD	TW A	330	41	ALLIGATOR CR	Low	2910.24	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	3131.2	SqFt	\$ 12.50	\$ 39,150.00
PGD	TW A	330	45	DEPRESSION	Low	5195.42	SqFt	1.9%	FDOT - PATCHING - AC FULL DEPTH	5489.6	SqFt	\$ 12.50	\$ 68,620.00
PGD	TW A	330	48	L & T CR	Medium	283.2	Ft	0.1%	FDOT - CRACK SEALING - AC	283.1	Ft	\$ 3.00	\$ 850.00
PGD	TW A	330	50	PATCHING	Medium	97.63	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	141	SqFt	\$ 12.50	\$ 1,770.00
PGD	TW A	330	52	RAVELING	Low	34180.15	SqFt	12.6%	FDOT - SURFACE SEAL	34179.7	SqFt	\$ 0.55	\$ 18,800.00
PGD	TW A	330	52	RAVELING	Medium	585.99	SqFt	0.2%	FDOT - PATCHING - AC PARTIAL DEPTH	585.6	SqFt	\$ 5.50	\$ 3,230.00
PGD	TW A2	365	52	RAVELING	Low	5920.26	SqFt	15.4%	FDOT - SURFACE SEAL	5920.2	SqFt	\$ 0.55	\$ 3,260.00
PGD	TW C	305	41	ALLIGATOR CR	Low	195.9	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	256.2	SqFt	\$ 12.50	\$ 3,210.00
PGD	TW C	305	52	RAVELING	Low	2448.47	SqFt	5.0%	FDOT - SURFACE SEAL	2448.8	SqFt	\$ 0.55	\$ 1,350.00
PGD	TW C	310	41	ALLIGATOR CR	Low	608.59	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	711.5	SqFt	\$ 12.50	\$ 8,900.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
PGD	TW C	310	45	DEPRESSION	Low	320.33	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	396.1	SqFt	\$ 12.50	\$ 4,960.00
PGD	TW C	310	52	RAVELING	Low	24264.33	SqFt	15.3%	FDOT - SURFACE SEAL	24264	SqFt	\$ 0.55	\$ 13,350.00
PGD	TW C	350	48	L & T CR	Medium	100	Ft	2.7%	FDOT - CRACK SEALING - AC	100.1	Ft	\$ 3.00	\$ 300.00
PGD	TW C	350	52	RAVELING	Low	734.96	SqFt	20.0%	FDOT - SURFACE SEAL	735.2	SqFt	\$ 0.55	\$ 410.00
PGD	TW D	102	41	ALLIGATOR CR	Low	7071.89	SqFt	8.5%	FDOT - PATCHING - AC FULL DEPTH	7414.2	SqFt	\$ 12.50	\$ 92,680.00
PGD	TW D	102	52	RAVELING	Low	12805.72	SqFt	15.3%	FDOT - SURFACE SEAL	12805.8	SqFt	\$ 0.55	\$ 7,050.00
PGD	TW D	102	53	RUTTING	Medium	4555.18	SqFt	5.5%	FDOT - PATCHING - AC FULL DEPTH	4555.3	SqFt	\$ 12.50	\$ 56,940.00
PGD	TW D	102	55	SLIPPAGE CR	N/A	911.06	SqFt	1.1%	FDOT - PATCHING - AC PARTIAL DEPTH	1036.6	SqFt	\$ 5.50	\$ 5,710.00
PGD	TW D	115	41	ALLIGATOR CR	Low	9193.46	SqFt	4.3%	FDOT - PATCHING - AC FULL DEPTH	9583.1	SqFt	\$ 12.50	\$ 119,800.00
PGD	TW D	115	48	L & T CR	Medium	4793.6	Ft	2.2%	FDOT - CRACK SEALING - AC	4793.6	Ft	\$ 3.00	\$ 14,390.00
PGD	TW D	115	52	RAVELING	Low	44939.97	SqFt	21.0%	FDOT - SURFACE SEAL	44940.4	SqFt	\$ 0.55	\$ 24,720.00
PGD	TW D	115	53	RUTTING	High	11984	SqFt	5.6%	FDOT - PATCHING - AC FULL DEPTH	11984.5	SqFt	\$ 12.50	\$ 149,810.00
PGD	TW D	120	48	L & T CR	Medium	1652.69	Ft	3.8%	FDOT - CRACK SEALING - AC	1652.6	Ft	\$ 3.00	\$ 4,960.00
PGD	TW D	120	52	RAVELING	Low	9649.95	SqFt	22.4%	FDOT - SURFACE SEAL	9649.9	SqFt	\$ 0.55	\$ 5,310.00
PGD	TW D	120	56	SWELLING	Medium	33.26	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	60.3	SqFt	\$ 12.50	\$ 760.00
PGD	TW D	120	57	WEATHERING	Medium	14486.07	SqFt	33.6%	FDOT - SURFACE SEAL	14486.1	SqFt	\$ 0.55	\$ 7,970.00
PGD	TW D	155	48	L & T CR	Medium	8.01	Ft	0.2%	FDOT - CRACK SEALING - AC	7.9	Ft	\$ 3.00	\$ 30.00
PGD	TW D	155	52	RAVELING	Low	622.05	SqFt	15.0%	FDOT - SURFACE SEAL	622.2	SqFt	\$ 0.55	\$ 350.00
PGD	TW D	160	52	RAVELING	Low	299.99	SqFt	11.8%	FDOT - SURFACE SEAL	300.3	SqFt	\$ 0.55	\$ 170.00
PGD	TW D	172	48	L & T CR	Medium	108.01	Ft	3.1%	FDOT - CRACK SEALING - AC	107.9	Ft	\$ 3.00	\$ 330.00
PGD	TW D	172	52	RAVELING	Low	351.01	SqFt	10.0%	FDOT - SURFACE SEAL	350.9	SqFt	\$ 0.55	\$ 200.00
PGD	TW D	180	52	RAVELING	Low	999.97	SqFt	9.3%	FDOT - SURFACE SEAL	1000	SqFt	\$ 0.55	\$ 550.00
PGD	TW D	195	48	L & T CR	Medium	2.99	Ft	0.1%	FDOT - CRACK SEALING - AC	3	Ft	\$ 3.00	\$ 10.00
PGD	TW D	195	52	RAVELING	Low	496	SqFt	15.0%	FDOT - SURFACE SEAL	496.2	SqFt	\$ 0.55	\$ 280.00
PGD	TW D	195	54	SHOVING	Medium	3.01	SqFt	0.1%	FDOT - MILLING - AC	14	SqFt	\$ 2.00	\$ 30.00
PGD	TW E	410	52	RAVELING	Low	962.08	SqFt	5.0%	FDOT - SURFACE SEAL	962.3	SqFt	\$ 0.55	\$ 530.00
PGD	TW E	415	52	RAVELING	Low	753.15	SqFt	1.1%	FDOT - SURFACE SEAL	753.5	SqFt	\$ 0.55	\$ 420.00
PGD	TW E	415	57	WEATHERING	Medium	2636.19	SqFt	3.7%	FDOT - SURFACE SEAL	2636.1	SqFt	\$ 0.55	\$ 1,450.00
PGD	TW E1	450	52	RAVELING	Low	7662.72	SqFt	98.9%	FDOT - SURFACE SEAL	7662.8	SqFt	\$ 0.55	\$ 4,220.00
PGD	TW E1	450	52	RAVELING	Medium	85.25	SqFt	1.1%	FDOT - PATCHING - AC PARTIAL DEPTH	85	SqFt	\$ 5.50	\$ 470.00
PGD	TW F	1105	48	L & T CR	Medium	1524.51	Ft	3.0%	FDOT - CRACK SEALING - AC	1524.6	Ft	\$ 3.00	\$ 4,580.00
PGD	TW F	1105	52	RAVELING	Low	8891.21	SqFt	17.7%	FDOT - SURFACE SEAL	8891	SqFt	\$ 0.55	\$ 4,900.00
PGD	TW F	1105	57	WEATHERING	Medium	41449.77	SqFt	82.3%	FDOT - SURFACE SEAL	41449.7	SqFt	\$ 0.55	\$ 22,800.00
PGD	TW G	110	41	ALLIGATOR CR	Low	445.41	SqFt	1.3%	FDOT - PATCHING - AC FULL DEPTH	533.9	SqFt	\$ 12.50	\$ 6,680.00
PGD	TW G	110	48	L & T CR	Medium	130.71	Ft	0.4%	FDOT - CRACK SEALING - AC	130.6	Ft	\$ 3.00	\$ 400.00
PGD	TW G	110	52	RAVELING	Low	6303.78	SqFt	18.1%	FDOT - SURFACE SEAL	6303.4	SqFt	\$ 0.55	\$ 3,470.00
PGD	TW N T-HAN	215	41	ALLIGATOR CR	Low	14.96	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	34.4	SqFt	\$ 12.50	\$ 440.00
PGD	TW N T-HAN	215	45	DEPRESSION	Low	89.02	SqFt	1.3%	FDOT - PATCHING - AC FULL DEPTH	131.3	SqFt	\$ 12.50	\$ 1,640.00
PGD	TW N T-HAN	215	45	DEPRESSION	Medium	192.03	SqFt	2.8%	FDOT - PATCHING - AC FULL DEPTH	251.9	SqFt	\$ 12.50	\$ 3,150.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
PGD	TW N T-HAN	215	45	DEPRESSION	High	100	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	144.2	SqFt	\$ 12.50	\$ 1,810.00
PGD	TW N T-HAN	215	50	PATCHING	Medium	3.98	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	16.2	SqFt	\$ 12.50	\$ 210.00
PGD	TW N T-HAN	215	52	RAVELING	Low	6934	SqFt	99.9%	FDOT - SURFACE SEAL	6934.1	SqFt	\$ 0.55	\$ 3,820.00
PGD	TW T-HANG	4405	52	RAVELING	Low	6689.99	SqFt	30.0%	FDOT - SURFACE SEAL	6689.8	SqFt	\$ 0.55	\$ 3,680.00
PGD	TW T-HANG	4405	57	WEATHERING	Medium	15605.09	SqFt	70.0%	FDOT - SURFACE SEAL	15605.5	SqFt	\$ 0.55	\$ 8,590.00
PGD	TW T-HANG	4410	45	DEPRESSION	Low	73.95	SqFt	0.5%	FDOT - PATCHING - AC FULL DEPTH	113	SqFt	\$ 12.50	\$ 1,410.00
PGD	TW T-HANG	4410	50	PATCHING	Medium	302.14	SqFt	1.9%	FDOT - PATCHING - AC FULL DEPTH	375.7	SqFt	\$ 12.50	\$ 4,710.00
PGD	TW T-HANG	4410	52	RAVELING	Low	6120.25	SqFt	39.2%	FDOT - SURFACE SEAL	6120.4	SqFt	\$ 0.55	\$ 3,370.00
PGD	TW T-HANG	4410	52	RAVELING	Medium	308.28	SqFt	2.0%	FDOT - PATCHING - AC PARTIAL DEPTH	307.9	SqFt	\$ 5.50	\$ 1,700.00
PGD	TW T-HANG	4410	57	WEATHERING	Medium	8870.54	SqFt	56.8%	FDOT - SURFACE SEAL	8870.5	SqFt	\$ 0.55	\$ 4,880.00
PGD	TW T-HANG	4415	52	RAVELING	Low	419.04	SqFt	5.9%	FDOT - SURFACE SEAL	418.7	SqFt	\$ 0.55	\$ 240.00
PGD	TW T-HANG	4420	48	L & T CR	High	66.01	Ft	0.1%	FDOT - CRACK SEALING - AC	65.9	Ft	\$ 3.00	\$ 200.00
PGD	TW T-HANG	4420	50	PATCHING	Medium	632.38	SqFt	1.4%	FDOT - PATCHING - AC FULL DEPTH	737.3	SqFt	\$ 12.50	\$ 9,220.00
PGD	TW T-HANG	4420	52	RAVELING	Low	18171.63	SqFt	39.6%	FDOT - SURFACE SEAL	18171.6	SqFt	\$ 0.55	\$ 10,000.00
PGD	TW T-HANG	4420	57	WEATHERING	Medium	26902.99	SqFt	58.7%	FDOT - SURFACE SEAL	26903.3	SqFt	\$ 0.55	\$ 14,800.00
PGD	TW T-HANG	4425	48	L & T CR	High	72.51	Ft	0.3%	FDOT - CRACK SEALING - AC	72.5	Ft	\$ 3.00	\$ 220.00
PGD	TW T-HANG	4425	50	PATCHING	Medium	167.27	SqFt	0.6%	FDOT - PATCHING - AC FULL DEPTH	223.9	SqFt	\$ 12.50	\$ 2,800.00
PGD	TW T-HANG	4425	52	RAVELING	Low	18121.04	SqFt	66.6%	FDOT - SURFACE SEAL	18121	SqFt	\$ 0.55	\$ 9,970.00
PGD	TW T-HANG	4425	57	WEATHERING	Medium	8378.74	SqFt	30.8%	FDOT - SURFACE SEAL	8378.6	SqFt	\$ 0.55	\$ 4,610.00
PGD	TW T-HANG	4430	52	RAVELING	Low	6154.37	SqFt	42.0%	FDOT - SURFACE SEAL	6154.8	SqFt	\$ 0.55	\$ 3,390.00
PGD	TW T-HANG	4430	57	WEATHERING	Medium	410.32	SqFt	2.8%	FDOT - SURFACE SEAL	410.1	SqFt	\$ 0.55	\$ 230.00



Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	PGD	AP MAIN	4208	PCC	10,625	61	PCC Restoration	\$ 181,000.00
2020	PGD	AP N	4305	AC	221,433	54	AC Restoration	\$ 2,436,000.00
2020	PGD	AP N	4320	AC	98,202	57	AC Restoration	\$ 1,081,000.00
2020	PGD	AP S	4105	AC	192,015	51	AC Restoration	\$ 2,113,000.00
2020	PGD	RW 15-33	6205	AAC	6,582	62	AC Restoration	\$ 73,000.00
2020	PGD	RW 15-33	6210	AAC	494,128	56	AC Restoration	\$ 5,436,000.00
2020	PGD	RW 15-33	6215	AAC	253,378	64	AC Restoration	\$ 2,788,000.00
2020	PGD	RW 15-33	6220	AC	53,287	64	AC Restoration	\$ 587,000.00
2020	PGD	RW 4-22	6105	AAC	520,000	49	AC Restoration	\$ 5,819,000.00
2020	PGD	RW 4-22	6115	AAC	149,200	63	AC Restoration	\$ 1,642,000.00
2020	PGD	RW 4-22	6125	AC	50,300	56	AC Restoration	\$ 554,000.00
2020	PGD	RW 9-27	6305	AC	151,500	58	AC Restoration	\$ 1,667,000.00
2020	PGD	TW A	330	AAC	271,000	49	AC Restoration	\$ 3,054,000.00
2020	PGD	TW C	310	AAC	158,559	57	AC Restoration	\$ 1,745,000.00
2020	PGD	TW C	350	AAC	3,675	60	AC Restoration	\$ 41,000.00
2020	PGD	TW D	102	AC	83,519	33	AC Reconstruction	\$ 1,170,000.00
2020	PGD	TW D	115	AAC	214,000	32	AC Reconstruction	\$ 2,996,000.00
2020	PGD	TW D	120	AAC	43,181	57	AC Restoration	\$ 475,000.00
2020	PGD	TW D	155	AAC	4,146	62	AC Restoration	\$ 46,000.00
2020	PGD	TW D	172	AC	3,508	57	AC Restoration	\$ 39,000.00
2020	PGD	TW E1	450	AC	7,748	61	AC Restoration	\$ 86,000.00
2020	PGD	TW F	1105	AC	50,341	61	AC Restoration	\$ 554,000.00
2020	PGD	TW G	110	AAC	34,930	53	AC Restoration	\$ 385,000.00
2020	PGD	TW N T-HAN	215	AC	6,938	31	AC Reconstruction	\$ 98,000.00
2020	PGD	TW T-HANG	4405	AC	22,295	61	AC Restoration	\$ 246,000.00
2020	PGD	TW T-HANG	4410	AC	15,629	58	AC Restoration	\$ 172,000.00





Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	PGD	TW T-HANG	4420	AC	45,846	61	AC Restoration	\$ 505,000.00
2020	PGD	TW T-HANG	4425	AC	27,208	63	AC Restoration	\$ 300,000.00
2021	PGD	TW A2	365	AAC	38,414	64	AC Restoration	\$ 423,000.00
2023	PGD	TW T-HANG	4430	AC	14,668	64	AC Restoration	\$ 162,000.00
2024	PGD	TW C	305	AAC	48,969	64	AC Restoration	\$ 539,000.00
2024	PGD	TW D	195	AC	3,304	64	AC Restoration	\$ 37,000.00
2025	PGD	RW 4-22	6110	AAC	262,500	62	AC Restoration	\$ 2,888,000.00
2025	PGD	RW 4-22	6120	AAC	72,100	64	AC Restoration	\$ 794,000.00
2026	PGD	AP MAIN	4215	AC	32,858	64	AC Restoration	\$ 362,000.00
2027	PGD	AP MAIN	4206	AC	194,550	64	AC Restoration	\$ 2,140,000.00
2027	PGD	TW D	160	AAC	2,534	64	AC Restoration	\$ 28,000.00
2029	PGD	AP MAIN	4220	AC	31,145	64	AC Restoration	\$ 343,000.00
2029	PGD	RW 4-22	6130	AC	25,150	64	AC Restoration	\$ 277,000.00

Appendix C

Technical Exhibits








195 AC VAR 1 1	215 AC VAR 1 1	1105 AC VAR 2 11	4405 AC VAR 1 4	4410 AC VAR 1 3
4415 AC VAR 1 2	4220 AC VAR 1 8	6125 AC VAR 2 10	6130 AC VAR 2 6	6310 AC VAR 2 8

LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID
- 4105 — SECTION NUMBER
- AC — PAVEMENT TYPE
- 100' X 50' — TYPICAL SAMPLE UNIT INFORMATION
- 5 14 — FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH
- 100 — RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE
- 605 — NUMBER OF SAMPLE UNITS IN SECTION
- 100 — NUMBER OF SAMPLE UNITS TO BE INSPECTED
- 605 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100 — INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 166
AC: 162 PCC: 4

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.




CONSTRUCTION SINCE LAST INSPECTION
& ANTICIPATED CONSTRUCTION ACTIVITY

CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2016	TW A	NEW CONSTRUCTION - AC / 4" P-401, 12" P-211, 10" P-211
2016	TW C	OVERLAY / 4" P-401
2018	AP MAIN	NEW CONSTRUCTION - AC
2018	AP MAIN	NEW CONSTRUCTION - PCC
2020	RW 15-33, TW D, TW E, TW G, TW H	PAVEMENT REHABILITATION
2021	RW 4-22	PAVEMENT REHABILITATION

LEGEND


- PROJECTS YEAR 2013
- PROJECTS YEAR 2014
- PROJECTS YEAR 2015
- PROJECTS YEAR 2016
- PROJECTS YEAR 2017
- PROJECTS YEAR 2018
- PROJECTS YEAR 2019
- PROJECTS YEAR 2020
- PROJECTS YEAR 2021
- PROJECTS YEAR 2022

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.



Appendix D


Inspection Photograph Documentation



RW 4-22, Section 6105, Sample Unit387 - Medium Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering



RW 4-22, Section 6105, Sample Unit313 - Low Severity (41) Alligator Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering



RW 4-22, Section 6105, Sample Unit337 - Low Severity (41) Alligator Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering



RW 4-22, Section 6125, Sample Unit291 - (42) Bleeding, Low Severity (52) Raveling, and Low Severity (57) Weathering




RW 9-27, Section 6305, Sample Unit 345 - Low Severity (48) Longitudinal & Transverse Cracking, Medium Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Medium Severity (52) Raveling



RW 9-27, Section 6305, Sample Unit 327 - Medium Severity (52) Raveling



RW 15-33, Section 6210, Sample Unit 348 - Low Severity (43) Block Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering



RW 15-33, Section 6210, Sample Unit 397 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering



RW 15-33, Section 6210, Sample Unit 380 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, and Medium Severity (57) Weathering




TWA, Section 330, Sample Unit 203 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering



TWC, Section 310, Sample Unit 308 - Low Severity (41) Alligator Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering



TWD, Section 115, Sample Unit 114 - Low Severity (41) Alligator Cracking, Low Severity (48) Longitudinal & Transverse Cracking, and Low Severity (57) Weathering



AP MAIN, Section 4205, Sample Unit 200 - (73) Shrinkage Cracking



AP S, Section 4105, Sample Unit 405 - Low Severity (43) Block Cracking, Low and Medium Severity (52) Raveling

Appendix E

Inspection Distress Details

Re-Inspection Report

FDOT

Generated Date 12/14/2018

Page 1 of 57

Network:	PGD	Name:	PUNTA GORDA AIRPORT			
Branch:	AP MAIN	Name:	MAIN APRON	Use:	APRON	Area: 694,981 SqFt
Section:	4205	of 8	From: -	To: -	Last Const.: 1/1/2009	
Surface:	PCC	Family:	FDOT-SAPMP-PR-AP-PCC	Zone:	Category:	Rank: P
Area:	278,175 SqFt	Length:	600 Ft	Width:	300 Ft	
Slabs:	927	Slab Length:	25 Ft	Slab Width:	12 Ft	Joint Length: 21,300 Ft
Shoulder:		Street Type:		Grade:	0	Lanes: 0
Section Comments:	INCLUDES PRIOR SECITONS 360/198					

Work Date:	1/1/1942	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2009	Work Type:	Surface Reconstruction - PCC	Code:	SR-PC	Is Major M&R: True

Last Insp. Date: 12/3/2018 **TotalSamples:** 27 **Surveyed:** 3

Conditions: PCI: 87

Inspection Comments:

Sample Number:	200	Type:	R	Area:	20.00 Slabs	PCI: 89
-----------------------	-----	--------------	---	--------------	-------------	----------------

Sample Comments:

74	JOINT SPALL	L	1.00	Slabs
73	SHRINKAGE CR	N	7.00	Slabs
63	LINEAR CR	L	1.00	Slabs

Sample Number:	302	Type:	R	Area:	20.00 Slabs	PCI: 83
-----------------------	-----	--------------	---	--------------	-------------	----------------

Sample Comments:

74	JOINT SPALL	L	2.00	Slabs
73	SHRINKAGE CR	N	19.00	Slabs

Sample Number:	305	Type:	R	Area:	20.00 Slabs	PCI: 89
-----------------------	-----	--------------	---	--------------	-------------	----------------

Sample Comments:

74	JOINT SPALL	L	2.00	Slabs
73	SHRINKAGE CR	N	10.00	Slabs

Network:	PGD			Name:	PUNTA GORDA AIRPORT									
Branch:	AP MAIN		Name:	MAIN APRON		Use:	APRON		Area:	694,981 SqFt				
Section:	4206		of	8		From:	-		To:	-		Last Const.:	1/1/2009	
Surface:	AC		Family:	FDOT-SAPMP-PR-AP-AAC		Zone:			Category:			Rank:	P	
Area:	194,550 SqFt		Length:	950 Ft		Width:	300 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1942		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Work Date:	1/1/2009		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True		
Last Insp. Date:	12/3/2018		TotalSamples:	40		Surveyed:	5							
Conditions:	PCI: 77													
Inspection Comments:														
Sample Number:	093		Type:	R		Area:	5850.00 SqFt		PCI:	79				
Sample Comments:														
48	L & T CR		L	190.00 Ft										
57	WEATHERING		L	5250.00 SqFt										
52	RAVELING		L	600.00 SqFt										
Sample Number:	152		Type:	R		Area:	5000.00 SqFt		PCI:	80				
Sample Comments:														
48	L & T CR		L	6.00 Ft										
57	WEATHERING		L	4400.00 SqFt										
52	RAVELING		L	600.00 SqFt										
42	BLEEDING		N	3.00 SqFt										
49	OIL SPILLAGE		N	5.00 SqFt										
Sample Number:	253		Type:	R		Area:	5000.00 SqFt		PCI:	76				
Sample Comments:														
48	L & T CR		L	30.00 Ft										
52	RAVELING		L	500.00 SqFt										
49	OIL SPILLAGE		N	10.00 SqFt										
57	WEATHERING		L	4400.00 SqFt										
57	WEATHERING		M	100.00 SqFt										
Sample Number:	301		Type:	R		Area:	4875.00 SqFt		PCI:	78				
Sample Comments:														
48	L & T CR		L	38.00 Ft										
57	WEATHERING		L	4075.00 SqFt										
52	RAVELING		L	800.00 SqFt										
Sample Number:	305		Type:	R		Area:	5000.00 SqFt		PCI:	73				
Sample Comments:														
48	L & T CR		L	6.00 Ft										
52	RAVELING		L	500.00 SqFt										
57	WEATHERING		M	4500.00 SqFt										

Network:	PGD			Name:	PUNTA GORDA AIRPORT				
Branch:	AP MAIN		Name:	MAIN APRON		Use:	APRON	Area:	694,981 SqFt
Section:	4208	of	8	From:	-	To:	-	Last Const.:	12/25/1995
Surface:	PCC	Family:	FDOT-SAPMP-PR-AP-PCC	Zone:		Category:		Rank:	P
Area:	10,625 SqFt	Length:	300 Ft	Width:	30 Ft				
Slabs:	74	Slab Length:	12 Ft	Slab Width:	12 Ft	Joint Length:	1,170 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1995	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	12/3/2018	TotalSamples:	4	Surveyed:	1				
Conditions:	PCI:	63							
Inspection Comments:									
Sample Number:	402	Type:	R	Area:	16.00 Slabs	PCI:	63		
Sample Comments:									
75	CORNER SPALL	M	3.00	Slabs					
74	JOINT SPALL	L	11.00	Slabs					
73	SHRINKAGE CR	N	11.00	Slabs					
74	JOINT SPALL	M	4.00	Slabs					
70	SCALING	L	1.00	Slabs					

Network:	PGD		Name:	PUNTA GORDA AIRPORT							
Branch:	AP MAIN		Name:	MAIN APRON		Use:	APRON	Area:	694,981 SqFt		
Section:	4210	of 8	From:	-			To:	-		Last Const.:	1/1/2007
Surface:	AC	Family:	FDOT-SAPMP-PR-AP-AC		Zone:		Category:		Rank:	P	
Area:	14,657 SqFt		Length:	200 Ft		Width:	75 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2007		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	88									
Inspection Comments:											
Sample Number:	202	Type:	R	Area:	3750.00 SqFt		PCI:	88			
Sample Comments:											
57	WEATHERING		L	3550.00	SqFt						
52	RAVELING		L	200.00	SqFt						

Network:	PGD		Name:	PUNTA GORDA AIRPORT								
Branch:	AP MAIN		Name:	MAIN APRON		Use:	APRON	Area:	694,981 SqFt			
Section:	4215	of	8	From:	-			To:	-		Last Const.:	1/1/2007
Surface:	AC	Family:	FDOT-SAPMP-PR-AP-AC		Zone:				Category:	Rank: P		
Area:	32,858 SqFt		Length:	440 Ft		Width:	75 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2007		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True	
Last Insp. Date:	12/3/2018		TotalSamples:	9		Surveyed:	1					
Conditions:	PCI: 76											
Inspection Comments:												
Sample Number:	204	Type:	R	Area:	3750.00 SqFt			PCI:	76			
Sample Comments:												
57	WEATHERING		L	3350.00	SqFt							
48	L & T CR		L	86.00	Ft							
50	PATCHING		L	100.00	SqFt							
52	RAVELING		L	300.00	SqFt							

Network:	PGD			Name:	PUNTA GORDA AIRPORT							
Branch:	AP MAIN		Name:	MAIN APRON		Use:	APRON	Area:	694,981 SqFt			
Section:	4220		of	8	From:	-		To:	-		Last Const.:	1/1/2009
Surface:	AC		Family:	FDOT-SAPMP-PR-AP-AC		Zone:			Category:	Rank: P		
Area:	31,145 SqFt		Length:	430 Ft		Width:	75 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2009		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	8		Surveyed:	1					
Conditions:	PCI: 80											
Inspection Comments:												
Sample Number:	405		Type:	R		Area:	3750.00 SqFt		PCI:	80		
Sample Comments:												
57	WEATHERING		L	3250.00 SqFt								
48	L & T CR		L	12.00 Ft								
52	RAVELING		L	500.00 SqFt								

Network:	PGD		Name:	PUNTA GORDA AIRPORT						
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	319,635 SqFt		
Section:	4305	of 2	From:	-		To:	-		Last Const.:	12/25/1999
Surface:	AC	Family:	C9N59-GA-AP-AC		Zone:			Category:	Rank: P	
Area:	221,433 SqFt		Length:	1,065 Ft		Width:	200 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	12/25/1999		Work Type: New Construction - Initial			Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	12/3/2018		TotalSamples:	46		Surveyed:	6			
Conditions:	PCI:	56								
Inspection Comments:										
Sample Number:	151	Type:	R	Area:	4850.00 SqFt		PCI:	44		
Sample Comments:										
57	WEATHERING		M	3348.00 SqFt						
43	BLOCK CR		L	392.00 SqFt						
52	RAVELING		L	1500.00 SqFt						
48	L & T CR		M	184.00 Ft						
56	SWELLING		L	80.00 SqFt						
48	L & T CR		L	550.00 Ft						
50	PATCHING		M	2.00 SqFt						
Sample Number:	156	Type:	R	Area:	4850.00 SqFt		PCI:	64		
Sample Comments:										
52	RAVELING		L	975.00 SqFt						
48	L & T CR		L	398.00 Ft						
57	WEATHERING		M	3875.00 SqFt						
45	DEPRESSION		L	45.00 SqFt						
Sample Number:	209	Type:	R	Area:	3929.00 SqFt		PCI:	72		
Sample Comments:										
48	L & T CR		L	215.00 Ft						
57	WEATHERING		M	2929.00 SqFt						
52	RAVELING		L	1000.00 SqFt						
Sample Number:	300	Type:	R	Area:	4850.00 SqFt		PCI:	46		
Sample Comments:										
52	RAVELING		L	1000.00 SqFt						
56	SWELLING		L	500.00 SqFt						
48	L & T CR		L	200.00 Ft						
48	L & T CR		M	86.00 Ft						
43	BLOCK CR		L	1966.00 SqFt						
57	WEATHERING		M	3850.00 SqFt						
Sample Number:	308	Type:	R	Area:	3880.00 SqFt		PCI:	55		
Sample Comments:										
48	L & T CR		L	625.00 Ft						
48	L & T CR		M	64.00 Ft						
57	WEATHERING		M	3380.00 SqFt						
52	RAVELING		L	500.00 SqFt						
Sample Number:	352	Type:	R	Area:	4850.00 SqFt		PCI:	60		
Sample Comments:										
56	SWELLING		L	35.00 SqFt						
48	L & T CR		M	100.00 Ft						
57	WEATHERING		M	4365.00 SqFt						
52	RAVELING		L	485.00 SqFt						
48	L & T CR		L	475.00 Ft						

Network:	PGD			Name:	PUNTA GORDA AIRPORT							
Branch:	AP N		Name:	NORTH APRON		Use:	APRON		Area:	319,635 SqFt		
Section:	4320		of	2		From:	-		To:	-		
Surface:	AC		Family:	C9N59-GA-AP-AC		Zone:			Category:			
Area:	98,202 SqFt		Length:	830 Ft		Width:	140 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1999		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2007		Work Type:	Surface Treatment - Slurry Seal				Code:	ST-SS		Is Major M&R:	False
Last Insp. Date:	12/3/2018		TotalSamples:	21		Surveyed:	3					
Conditions:	PCI: 59											
Inspection Comments:												
Sample Number:	110		Type:	R		Area:	3528.00 SqFt		PCI:	71		
Sample Comments:												
48	L & T CR		M	80.00 Ft								
48	L & T CR		L	262.00 Ft								
57	WEATHERING		L	3528.00 SqFt								
Sample Number:	254		Type:	R		Area:	6400.00 SqFt		PCI:	57		
Sample Comments:												
48	L & T CR		M	300.00 Ft								
52	RAVELING		L	6400.00 SqFt								
48	L & T CR		L	442.00 Ft								
Sample Number:	407		Type:	R		Area:	3400.00 SqFt		PCI:	52		
Sample Comments:												
43	BLOCK CR		L	3400.00 SqFt								
56	SWELLING		L	25.00 SqFt								
52	RAVELING		L	3000.00 SqFt								
57	WEATHERING		M	400.00 SqFt								

Network:	PGD			Name:	PUNTA GORDA AIRPORT									
Branch:	AP S		Name:	SOUTH GA APRON		Use:	APRON		Area:	192,015 SqFt				
Section:	4105		of	1		From:	-		To:	-		Last Const.:	1/1/1992	
Surface:	AC		Family:	FDOT-SAPMP-PR-AP-AC		Zone:			Category:			Rank:	P	
Area:	192,015 SqFt			Length:	845 Ft		Width:	200 Ft						
Slabs:				Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:				Street Type:			Grade:	0		Lanes:	0			
Section Comments:														
Work Date:	1/1/1992			Work Type:	BUILT			Code:	IMPORTED			Is Major M&R:	True	
Last Insp. Date:	12/3/2018			TotalSamples:	38			Surveyed:	4					
Conditions:	PCI: 53													
Inspection Comments:														
Sample Number:	152		Type:	R		Area:	5000.00 SqFt			PCI:	54			
Sample Comments:														
48	L & T CR		L	283.00		Ft								
43	BLOCK CR		L	1100.00		SqFt								
52	RAVELING		L	885.00		SqFt								
52	RAVELING		M	1101.00		SqFt								
56	SWELLING		L	16.00		SqFt								
Sample Number:	156		Type:	R		Area:	5000.00 SqFt			PCI:	61			
Sample Comments:														
48	L & T CR		L	168.00		Ft								
43	BLOCK CR		L	100.00		SqFt								
52	RAVELING		L	660.00		SqFt								
52	RAVELING		M	320.00		SqFt								
56	SWELLING		L	12.00		SqFt								
48	L & T CR		M	100.00		Ft								
Sample Number:	250		Type:	R		Area:	4500.00 SqFt			PCI:	59			
Sample Comments:														
48	L & T CR		M	70.00		Ft								
57	WEATHERING		L	3375.00		SqFt								
48	L & T CR		L	343.00		Ft								
43	BLOCK CR		L	101.00		SqFt								
52	RAVELING		L	1125.00		SqFt								
56	SWELLING		L	18.00		SqFt								
Sample Number:	405		Type:	R		Area:	6000.00 SqFt			PCI:	42			
Sample Comments:														
52	RAVELING		L	348.00		SqFt								
43	BLOCK CR		L	2900.00		SqFt								
48	L & T CR		L	450.00		Ft								
52	RAVELING		M	2700.00		SqFt								
50	PATCHING		L	8.00		SqFt								

Network:	PGD			Name:	PUNTA GORDA AIRPORT											
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY	Area:	834,019 SqFt							
Section:	6205 of 5		From:	-			To:	-			Last Const.:	1/1/2002				
Surface:	AAC		Family:	FDOT-SAPMP-PR-RW-AAC		Zone:				Category:				Rank:	P	
Area:	6,582 SqFt			Length:	75 Ft		Width:	87 Ft								
Slabs:				Slab Length:	Ft		Slab Width:	Ft			Joint Length:	Ft				
Shoulder:				Street Type:			Grade:	0			Lanes:	0				
Section Comments:																
Work Date:	1/1/1979			Work Type:	BUILT			Code:	IMPORTED			Is Major M&R:	True			
Work Date:	1/1/1985			Work Type:	OVERLAY			Code:	IMPORTED			Is Major M&R:	True			
Work Date:	1/1/2002			Work Type:	Mill and Overlay			Code:	ML-OL			Is Major M&R:	True			
Last Insp. Date:	12/3/2018			TotalSamples:	1			Surveyed:	1							
Conditions:	PCI: 65															
Inspection Comments:																
Sample Number:	299		Type:	R		Area:	6582.00 SqFt			PCI:	65					
Sample Comments:																
48	L & T CR			L	167.00 Ft											
50	PATCHING			L	6.00 SqFt											
57	WEATHERING			M	4876.00 SqFt											
48	L & T CR			M	14.00 Ft											
52	RAVELING			L	1700.00 SqFt											

Network:	PGD		Name:	PUNTA GORDA AIRPORT							
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY	Area:	834,019 SqFt		
Section:	6210 of 5		From:	-		To:	-		Last Const.:	1/1/2002	
Surface:	AAC		Family:	FDOT-SAPMP-PR-RW-AAC		Zone:	Category:		Rank:	P	
Area:	494,128 SqFt		Length:	4,945 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1983		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2002		Work Type: Mill and Overlay				Code:	ML-OL		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	99		Surveyed:	20				
Conditions:	PCI: 59										
Inspection Comments:											
Sample Number:	300		Type:	R		Area:	5000.00 SqFt		PCI:	65	
Sample Comments:											
48	L & T CR		M	20.00 Ft							
57	WEATHERING		M	3000.00 SqFt							
48	L & T CR		L	262.00 Ft							
56	SWELLING		L	25.00 SqFt							
52	RAVELING		L	2000.00 SqFt							
Sample Number:	306		Type:	R		Area:	5000.00 SqFt		PCI:	61	
Sample Comments:											
52	RAVELING		L	2500.00 SqFt							
57	WEATHERING		L	2500.00 SqFt							
48	L & T CR		M	15.00 Ft							
56	SWELLING		L	30.00 SqFt							
48	L & T CR		L	451.00 Ft							
Sample Number:	312		Type:	R		Area:	5000.00 SqFt		PCI:	65	
Sample Comments:											
52	RAVELING		L	1750.00 SqFt							
48	L & T CR		L	361.00 Ft							
57	WEATHERING		M	3250.00 SqFt							
56	SWELLING		L	275.00 SqFt							
Sample Number:	319		Type:	R		Area:	5000.00 SqFt		PCI:	58	
Sample Comments:											
48	L & T CR		L	455.00 Ft							
48	L & T CR		M	20.00 Ft							
57	WEATHERING		M	4000.00 SqFt							
56	SWELLING		L	238.00 SqFt							
52	RAVELING		L	1000.00 SqFt							
Sample Number:	325		Type:	R		Area:	5000.00 SqFt		PCI:	60	
Sample Comments:											
56	SWELLING		L	188.00 SqFt							
52	RAVELING		L	1500.00 SqFt							
48	L & T CR		L	380.00 Ft							
48	L & T CR		M	32.00 Ft							
52	RAVELING		M	25.00 SqFt							
Sample Number:	330		Type:	R		Area:	5000.00 SqFt		PCI:	61	
Sample Comments:											
48	L & T CR		L	361.00 Ft							
48	L & T CR		M	10.00 Ft							
57	WEATHERING		M	3500.00 SqFt							
52	RAVELING		L	1500.00 SqFt							
56	SWELLING		L	325.00 SqFt							

Sample Number: 335		Type:	R	Area:		5000.00 SqFt	PCI: 59
Sample Comments:							
52	RAVELING		L	1600.00	SqFt		
57	WEATHERING		M	3400.00	SqFt		
56	SWELLING		L	350.00	SqFt		
48	L & T CR		L	417.00	Ft		
48	L & T CR		M	50.00	Ft		
Sample Number: 342		Type:	R	Area:		5000.00 SqFt	PCI: 60
Sample Comments:							
52	RAVELING		L	1600.00	SqFt		
52	RAVELING		M	25.00	SqFt		
48	L & T CR		M	50.00	Ft		
56	SWELLING		L	400.00	SqFt		
48	L & T CR		L	395.00	Ft		
Sample Number: 345		Type:	R	Area:		5000.00 SqFt	PCI: 56
Sample Comments:							
48	L & T CR		M	68.00	Ft		
57	WEATHERING		M	3400.00	SqFt		
48	L & T CR		L	532.00	Ft		
56	SWELLING		L	325.00	SqFt		
52	RAVELING		L	1600.00	SqFt		
Sample Number: 348		Type:	R	Area:		5000.00 SqFt	PCI: 39
Sample Comments:							
52	RAVELING		L	2000.00	SqFt		
56	SWELLING		L	275.00	SqFt		
57	WEATHERING		M	3000.00	SqFt		
48	L & T CR		M	66.00	Ft		
43	BLOCK CR		L	340.00	SqFt		
48	L & T CR		L	375.00	Ft		
53	RUTTING		L	512.00	SqFt		
Sample Number: 353		Type:	R	Area:		5000.00 SqFt	PCI: 57
Sample Comments:							
57	WEATHERING		M	3275.00	SqFt		
48	L & T CR		L	325.00	Ft		
56	SWELLING		L	400.00	SqFt		
48	L & T CR		M	100.00	Ft		
52	RAVELING		L	1725.00	SqFt		
Sample Number: 357		Type:	R	Area:		5000.00 SqFt	PCI: 59
Sample Comments:							
48	L & T CR		M	20.00	Ft		
57	WEATHERING		M	3400.00	SqFt		
52	RAVELING		L	1600.00	SqFt		
56	SWELLING		L	300.00	SqFt		
48	L & T CR		L	430.00	Ft		
Sample Number: 363		Type:	R	Area:		5000.00 SqFt	PCI: 62
Sample Comments:							
48	L & T CR		M	80.00	Ft		
56	SWELLING		L	250.00	SqFt		
57	WEATHERING		M	3400.00	SqFt		
48	L & T CR		L	221.00	Ft		
52	RAVELING		L	1600.00	SqFt		
Sample Number: 368		Type:	R	Area:		5000.00 SqFt	PCI: 59
Sample Comments:							
52	RAVELING		L	1600.00	SqFt		
57	WEATHERING		M	3400.00	SqFt		
48	L & T CR		M	50.00	Ft		
56	SWELLING		L	350.00	SqFt		
48	L & T CR		L	400.00	Ft		

Sample Number: 372		Type:	R	Area:		5000.00 SqFt	PCI:	61
Sample Comments:								
57	WEATHERING		M	3500.00	SqFt			
48	L & T CR		L	331.00	Ft			
52	RAVELING		L	1500.00	SqFt			
48	L & T CR		M	50.00	Ft			
56	SWELLING		L	325.00	SqFt			
Sample Number: 376		Type:	R	Area:		5000.00 SqFt	PCI:	62
Sample Comments:								
57	WEATHERING		M	3400.00	SqFt			
48	L & T CR		M	50.00	Ft			
52	RAVELING		L	1600.00	SqFt			
48	L & T CR		L	284.00	Ft			
56	SWELLING		L	130.00	SqFt			
Sample Number: 380		Type:	R	Area:		5000.00 SqFt	PCI:	60
Sample Comments:								
48	L & T CR		L	368.00	Ft			
48	L & T CR		M	50.00	Ft			
56	SWELLING		L	275.00	SqFt			
57	WEATHERING		M	3000.00	SqFt			
52	RAVELING		L	2000.00	SqFt			
Sample Number: 386		Type:	R	Area:		5000.00 SqFt	PCI:	69
Sample Comments:								
56	SWELLING		L	150.00	SqFt			
52	RAVELING		L	1000.00	SqFt			
48	L & T CR		L	277.00	Ft			
52	RAVELING		M	25.00	SqFt			
Sample Number: 392		Type:	R	Area:		5000.00 SqFt	PCI:	61
Sample Comments:								
48	L & T CR		L	310.00	Ft			
52	RAVELING		L	1000.00	SqFt			
56	SWELLING		L	163.00	SqFt			
57	WEATHERING		M	4000.00	SqFt			
48	L & T CR		M	76.00	Ft			
Sample Number: 397		Type:	R	Area:		5000.00 SqFt	PCI:	52
Sample Comments:								
57	WEATHERING		M	3400.00	SqFt			
52	RAVELING		L	1600.00	SqFt			
56	SWELLING		M	40.00	SqFt			
56	SWELLING		L	154.00	SqFt			
48	L & T CR		M	36.00	Ft			
48	L & T CR		L	490.00	Ft			

Network:	PGD		Name:	PUNTA GORDA AIRPORT										
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY		Area:	834,019 SqFt				
Section:	6215		of	5		From:	-		To:	-		Last Const.:	1/1/2002	
Surface:	AAC		Family:	FDOT-SAPMP-PR-RW-AAC		Zone:			Category:			Rank:	P	
Area:	253,378 SqFt		Length:	9,890 Ft		Width:			25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1983		Work Type:	BUILT					Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/2002		Work Type:	Mill and Overlay					Code:	ML-OL		Is Major M&R:	True	
Last Insp. Date:	12/3/2018		TotalSamples:	51		Surveyed:	11							
Conditions:	PCI: 68													
Inspection Comments:														
Sample Number:	104		Type:	R		Area:	5000.00 SqFt		PCI:	69				
Sample Comments:														
52	RAVELING		L	2900.00 SqFt										
57	WEATHERING		L	2100.00 SqFt										
48	L & T CR		L	114.00 Ft										
Sample Number:	120		Type:	R		Area:	5000.00 SqFt		PCI:	67				
Sample Comments:														
56	SWELLING		L	40.00 SqFt										
57	WEATHERING		L	3750.00 SqFt										
48	L & T CR		L	197.00 Ft										
48	L & T CR		M	40.00 Ft										
52	RAVELING		L	1250.00 SqFt										
Sample Number:	128		Type:	R		Area:	5000.00 SqFt		PCI:	69				
Sample Comments:														
52	RAVELING		L	1500.00 SqFt										
56	SWELLING		L	87.00 SqFt										
48	L & T CR		L	174.00 Ft										
57	WEATHERING		L	3500.00 SqFt										
Sample Number:	152		Type:	R		Area:	5000.00 SqFt		PCI:	63				
Sample Comments:														
56	SWELLING		L	359.00 SqFt										
48	L & T CR		M	85.00 Ft										
52	RAVELING		L	1600.00 SqFt										
48	L & T CR		L	221.00 Ft										
57	WEATHERING		L	3400.00 SqFt										
Sample Number:	176		Type:	R		Area:	5000.00 SqFt		PCI:	65				
Sample Comments:														
48	L & T CR		L	218.00 Ft										
52	RAVELING		L	1600.00 SqFt										
56	SWELLING		L	46.00 SqFt										
57	WEATHERING		M	3400.00 SqFt										
48	L & T CR		M	97.00 Ft										
Sample Number:	192		Type:	R		Area:	5000.00 SqFt		PCI:	65				
Sample Comments:														
52	RAVELING		L	1600.00 SqFt										
57	WEATHERING		M	3400.00 SqFt										
56	SWELLING		L	29.00 SqFt										
48	L & T CR		L	296.00 Ft										
48	L & T CR		M	38.00 Ft										
Sample Number:	512		Type:	R		Area:	5000.00 SqFt		PCI:	72				
Sample Comments:														

57	WEATHERING	L	4150.00	SqFt
52	RAVELING	L	850.00	SqFt
56	SWELLING	L	105.00	SqFt
48	L & T CR	L	182.00	Ft
<hr/>				
Sample Number: 524		Type: R	Area: 5000.00	PCI: 71
Sample Comments:				
48	L & T CR	L	151.00	Ft
56	SWELLING	L	79.00	SqFt
52	RAVELING	L	1250.00	SqFt
57	WEATHERING	L	3750.00	SqFt
<hr/>				
Sample Number: 540		Type: R	Area: 5000.00	PCI: 66
Sample Comments:				
45	DEPRESSION	L	1.00	SqFt
56	SWELLING	L	126.00	SqFt
48	L & T CR	L	147.00	Ft
57	WEATHERING	M	4066.00	SqFt
52	RAVELING	L	934.00	SqFt
<hr/>				
Sample Number: 564		Type: R	Area: 5000.00	PCI: 66
Sample Comments:				
56	SWELLING	L	80.00	SqFt
48	L & T CR	L	320.00	Ft
57	WEATHERING	M	4250.00	SqFt
52	RAVELING	L	750.00	SqFt
<hr/>				
Sample Number: 584		Type: R	Area: 5000.00	PCI: 70
Sample Comments:				
56	SWELLING	L	7.00	SqFt
52	RAVELING	L	1000.00	SqFt
48	L & T CR	M	18.00	Ft
52	RAVELING	M	129.00	SqFt
48	L & T CR	L	181.00	Ft

Network:	PGD		Name:	PUNTA GORDA AIRPORT						
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY	Area:	834,019 SqFt	
Section:	6220 of 5		From:	-		To:	-		Last Const.:	1/1/2002
Surface:	AC		Family:	FDOT-SAPMP-PR-RW-AC		Zone:			Category:	Rank: P
Area:	53,287 SqFt		Length:	530 Ft		Width:	100 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	1/1/2002		Work Type:	New Construction - Initial				Code:	NU-IN	
Last Insp. Date:	12/3/2018		TotalSamples:	11		Surveyed:	3			
Conditions:	PCI: 66									
Inspection Comments:										
Sample Number:	287		Type:	R		Area:	5000.00 SqFt		PCI:	69
Sample Comments:										
56	SWELLING		L	35.00 SqFt						
52	RAVELING		L	1992.00 SqFt						
57	WEATHERING		L	3008.00 SqFt						
48	L & T CR		L	151.00 Ft						
Sample Number:	291		Type:	R		Area:	5000.00 SqFt		PCI:	58
Sample Comments:										
52	RAVELING		M	1000.00 SqFt						
48	L & T CR		L	171.00 Ft						
52	RAVELING		L	1240.00 SqFt						
56	SWELLING		L	75.00 SqFt						
Sample Number:	295		Type:	R		Area:	5000.00 SqFt		PCI:	70
Sample Comments:										
56	SWELLING		L	150.00 SqFt						
57	WEATHERING		L	3750.00 SqFt						
52	RAVELING		L	1250.00 SqFt						
48	L & T CR		L	138.00 Ft						

Network:	PGD			Name:	PUNTA GORDA AIRPORT							
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY		Area:	834,019 SqFt		
Section:	6225 of 5		From:	-		To:	-		Last Const.:	1/1/2002		
Surface:	AC		Family:	FDOT-SAPMP-PR-RW-AC		Zone:			Category:	Rank: P		
Area:	26,644 SqFt		Length:	1,066 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	1/1/2002		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	6		Surveyed:	2					
Conditions:	PCI: 83											
Inspection Comments:												
Sample Number:	092		Type:	R		Area:	5000.00 SqFt		PCI:	83		
Sample Comments:												
56	SWELLING		L	2.00 SqFt								
48	L & T CR		L	10.00 Ft								
57	WEATHERING		L	4700.00 SqFt								
52	RAVELING		L	300.00 SqFt								
Sample Number:	496		Type:	R		Area:	5475.00 SqFt		PCI:	83		
Sample Comments:												
57	WEATHERING		L	4654.00 SqFt								
52	RAVELING		L	821.00 SqFt								

Network:	PGD	Name:	PUNTA GORDA AIRPORT							
Branch:	RW 4-22	Name:	RUNWAY 4-22		Use:	RUNWAY	Area:	1,079,250 SqFt		
Section:	6105	of	6	From:	-	To:	-	Last Const.:	1/1/2000	
Surface:	AAC	Family:	FDOT-SAPMP-PR-RW-AAC	Zone:		Category:		Rank:	T	
Area:	520,000 SqFt		Length:	5,200 Ft		Width:	100 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	1/1/1979	Work Type:				BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1985	Work Type:				OVERLAY	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2000	Work Type:				Mill and Overlay	Code:	ML-OL	Is Major M&R:	True
Last Insp. Date: 12/3/2018										
Conditions:		PCI:	50	TotalSamples:	104	Surveyed: 21				
Inspection Comments:										
Sample Number:	301	Type:	R	Area:	5000.00 SqFt		PCI:	51		
Sample Comments:										
56	SWELLING	L	25.00	SqFt						
57	WEATHERING	M	2400.00	SqFt						
52	RAVELING	L	2600.00	SqFt						
41	ALLIGATOR CR	L	60.00	SqFt						
48	L & T CR	L	150.00	Ft						
53	RUTTING	L	240.00	SqFt						
Sample Number:	304	Type:	R	Area:	5000.00 SqFt		PCI:	52		
Sample Comments:										
53	RUTTING	L	450.00	SqFt						
52	RAVELING	L	3750.00	SqFt						
41	ALLIGATOR CR	L	17.00	SqFt						
48	L & T CR	L	267.00	Ft						
57	WEATHERING	M	1250.00	SqFt						
Sample Number:	307	Type:	R	Area:	5000.00 SqFt		PCI:	61		
Sample Comments:										
53	RUTTING	L	250.00	SqFt						
57	WEATHERING	M	4250.00	SqFt						
52	RAVELING	L	750.00	SqFt						
48	L & T CR	L	250.00	Ft						
Sample Number:	313	Type:	R	Area:	5000.00 SqFt		PCI:	42		
Sample Comments:										
50	PATCHING	M	4.00	SqFt						
41	ALLIGATOR CR	L	103.00	SqFt						
52	RAVELING	L	850.00	SqFt						
53	RUTTING	L	700.00	SqFt						
48	L & T CR	L	180.00	Ft						
57	WEATHERING	M	4146.00	SqFt						
Sample Number:	319	Type:	R	Area:	5000.00 SqFt		PCI:	35		
Sample Comments:										
41	ALLIGATOR CR	M	80.00	SqFt						
52	RAVELING	L	750.00	SqFt						
41	ALLIGATOR CR	L	38.00	SqFt						
50	PATCHING	L	19.00	SqFt						
48	L & T CR	L	219.00	Ft						
57	WEATHERING	M	4231.00	SqFt						
53	RUTTING	L	1000.00	SqFt						
Sample Number:	325	Type:	R	Area:	5000.00 SqFt		PCI:	42		
Sample Comments:										

57	WEATHERING	M	4050.00	SqFt
53	RUTTING	L	800.00	SqFt
41	ALLIGATOR CR	L	21.00	SqFt
52	RAVELING	L	950.00	SqFt
41	ALLIGATOR CR	M	36.00	SqFt
48	L & T CR	L	188.00	Ft
<hr/>				
Sample Number: 331		Type: R	Area: 5000.00 SqFt	PCI: 49
Sample Comments:				
48	L & T CR	M	25.00	Ft
53	RUTTING	L	360.00	SqFt
50	PATCHING	L	460.00	SqFt
48	L & T CR	L	248.00	Ft
52	RAVELING	L	454.00	SqFt
57	WEATHERING	M	4086.00	SqFt
<hr/>				
Sample Number: 332		Type: R	Area: 5000.00 SqFt	PCI: 41
Sample Comments:				
57	WEATHERING	M	3791.00	SqFt
48	L & T CR	M	25.00	Ft
50	PATCHING	L	540.00	SqFt
52	RAVELING	L	669.00	SqFt
41	ALLIGATOR CR	L	26.00	SqFt
53	RUTTING	L	550.00	SqFt
48	L & T CR	L	146.00	Ft
<hr/>				
Sample Number: 337		Type: R	Area: 5000.00 SqFt	PCI: 53
Sample Comments:				
53	RUTTING	L	400.00	SqFt
57	WEATHERING	M	4250.00	SqFt
52	RAVELING	L	750.00	SqFt
48	L & T CR	L	129.00	Ft
41	ALLIGATOR CR	L	32.00	SqFt
<hr/>				
Sample Number: 343		Type: R	Area: 5000.00 SqFt	PCI: 61
Sample Comments:				
52	RAVELING	L	440.00	SqFt
50	PATCHING	L	600.00	SqFt
48	L & T CR	M	24.00	Ft
48	L & T CR	L	157.00	Ft
57	WEATHERING	M	3960.00	SqFt
<hr/>				
Sample Number: 349		Type: R	Area: 5000.00 SqFt	PCI: 41
Sample Comments:				
57	WEATHERING	M	3959.00	SqFt
48	L & T CR	L	235.00	Ft
41	ALLIGATOR CR	L	68.00	SqFt
53	RUTTING	L	384.00	SqFt
50	PATCHING	L	342.00	SqFt
48	L & T CR	M	25.00	Ft
52	RAVELING	L	699.00	SqFt
<hr/>				
Sample Number: 355		Type: R	Area: 5000.00 SqFt	PCI: 37
Sample Comments:				
53	RUTTING	L	937.00	SqFt
50	PATCHING	L	63.00	SqFt
48	L & T CR	L	176.00	Ft
52	RAVELING	L	741.00	SqFt
48	L & T CR	M	25.00	Ft
41	ALLIGATOR CR	L	88.00	SqFt
57	WEATHERING	M	4196.00	SqFt
<hr/>				
Sample Number: 361		Type: R	Area: 5000.00 SqFt	PCI: 39
Sample Comments:				
50	PATCHING	L	40.00	SqFt
48	L & T CR	L	210.00	Ft
57	WEATHERING	M	4216.00	SqFt
53	RUTTING	L	860.00	SqFt

52	RAVELING	L	744.00	SqFt
48	L & T CR	M	23.00	Ft
41	ALLIGATOR CR	L	106.00	SqFt
Sample Number: 367 Type: R Area: 5000.00 SqFt PCI: 53				
Sample Comments:				
53	RUTTING	L	800.00	SqFt
48	L & T CR	L	230.00	Ft
57	WEATHERING	M	4250.00	SqFt
52	RAVELING	L	750.00	SqFt
Sample Number: 373 Type: R Area: 5000.00 SqFt PCI: 53				
Sample Comments:				
53	RUTTING	L	400.00	SqFt
48	L & T CR	L	251.00	Ft
57	WEATHERING	M	4000.00	SqFt
48	L & T CR	M	30.00	Ft
52	RAVELING	L	1000.00	SqFt
Sample Number: 377 Type: R Area: 5000.00 SqFt PCI: 44				
Sample Comments:				
53	RUTTING	L	664.00	SqFt
48	L & T CR	M	25.00	Ft
50	PATCHING	L	170.00	SqFt
52	RAVELING	L	1100.00	SqFt
48	L & T CR	L	166.00	Ft
57	WEATHERING	M	3730.00	SqFt
Sample Number: 381 Type: R Area: 5000.00 SqFt PCI: 49				
Sample Comments:				
53	RUTTING	L	350.00	SqFt
52	RAVELING	L	670.00	SqFt
57	WEATHERING	M	3797.00	SqFt
50	PATCHING	L	533.00	SqFt
48	L & T CR	L	180.00	Ft
48	L & T CR	M	91.00	Ft
Sample Number: 387 Type: R Area: 5000.00 SqFt PCI: 42				
Sample Comments:				
53	RUTTING	L	800.00	SqFt
52	RAVELING	L	1150.00	SqFt
48	L & T CR	L	255.00	Ft
57	WEATHERING	M	3850.00	SqFt
41	ALLIGATOR CR	L	60.00	SqFt
48	L & T CR	M	50.00	Ft
Sample Number: 393 Type: R Area: 5000.00 SqFt PCI: 64				
Sample Comments:				
57	WEATHERING	M	4250.00	SqFt
52	RAVELING	L	750.00	SqFt
48	L & T CR	L	229.00	Ft
56	SWELLING	L	15.00	SqFt
48	L & T CR	M	50.00	Ft
Sample Number: 400 Type: R Area: 5000.00 SqFt PCI: 71				
Sample Comments:				
48	L & T CR	L	243.00	Ft
52	RAVELING	L	750.00	SqFt
57	WEATHERING	M	4250.00	SqFt
Sample Number: 402 Type: R Area: 5000.00 SqFt PCI: 72				
Sample Comments:				
52	RAVELING	L	1300.00	SqFt
48	L & T CR	L	197.00	Ft
57	WEATHERING	M	3700.00	SqFt

Network:	PGD			Name:	PUNTA GORDA AIRPORT					
Branch:	RW 4-22		Name:	RUNWAY 4-22		Use:	RUNWAY	Area:	1,079,250 SqFt	
Section:	6110 of 6		From:	-		To:	-		Last Const.:	1/1/2000
Surface:	AAC		Family:	FDOT-SAPMP-PR-RW-AAC		Zone:	Category:		Rank:	P
Area:	262,500 SqFt		Length:	10,500 Ft		Width:	25 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1979		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1985		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/2000		Work Type: Mill and Overlay				Code:	ML-OL		Is Major M&R: True
Last Insp. Date:	12/3/2018		TotalSamples:	52		Surveyed:	11			
Conditions:	PCI: 77									
Inspection Comments:										
Sample Number:	104		Type:	R		Area:	5000.00 SqFt		PCI:	76
Sample Comments:										
57	WEATHERING		L		4109.00 SqFt					
52	RAVELING		L		891.00 SqFt					
48	L & T CR		L		241.00 Ft					
Sample Number:	124		Type:	R		Area:	5000.00 SqFt		PCI:	80
Sample Comments:										
50	PATCHING		L		2.00 SqFt					
48	L & T CR		L		7.00 Ft					
57	WEATHERING		L		4398.00 SqFt					
52	RAVELING		L		600.00 SqFt					
Sample Number:	144		Type:	R		Area:	5000.00 SqFt		PCI:	85
Sample Comments:										
52	RAVELING		L		250.00 SqFt					
57	WEATHERING		L		4750.00 SqFt					
48	L & T CR		L		16.00 Ft					
Sample Number:	168		Type:	R		Area:	5000.00 SqFt		PCI:	71
Sample Comments:										
50	PATCHING		M		8.00 SqFt					
52	RAVELING		L		500.00 SqFt					
57	WEATHERING		L		4492.00 SqFt					
48	L & T CR		L		233.00 Ft					
Sample Number:	188		Type:	R		Area:	5000.00 SqFt		PCI:	68
Sample Comments:										
48	L & T CR		M		104.00 Ft					
57	WEATHERING		L		4500.00 SqFt					
52	RAVELING		L		500.00 SqFt					
48	L & T CR		L		295.00 Ft					
Sample Number:	504		Type:	R		Area:	5000.00 SqFt		PCI:	77
Sample Comments:										
57	WEATHERING		L		4150.00 SqFt					
48	L & T CR		L		109.00 Ft					
52	RAVELING		L		850.00 SqFt					
Sample Number:	520		Type:	R		Area:	5000.00 SqFt		PCI:	71
Sample Comments:										
52	RAVELING		L		2100.00 SqFt					
48	L & T CR		L		62.00 Ft					
57	WEATHERING		L		2900.00 SqFt					

Sample Number: 536		Type:	R	Area:	5000.00 SqFt	PCI:	80
Sample Comments:							
48	L & T CR		L	143.00	Ft		
57	WEATHERING		L	4750.00	SqFt		
52	RAVELING		L	250.00	SqFt		
Sample Number: 552		Type:	R	Area:	5000.00 SqFt	PCI:	78
Sample Comments:							
57	WEATHERING		L	4750.00	SqFt		
48	L & T CR		L	179.00	Ft		
52	RAVELING		L	250.00	SqFt		
Sample Number: 568		Type:	R	Area:	5000.00 SqFt	PCI:	85
Sample Comments:							
57	WEATHERING		L	4750.00	SqFt		
48	L & T CR		L	14.00	Ft		
52	RAVELING		L	250.00	SqFt		
Sample Number: 596		Type:	R	Area:	5000.00 SqFt	PCI:	80
Sample Comments:							
48	L & T CR		L	66.00	Ft		
52	RAVELING		L	500.00	SqFt		
57	WEATHERING		L	4500.00	SqFt		

Network:	PGD			Name:	PUNTA GORDA AIRPORT				
Branch:	RW 4-22		Name:	RUNWAY 4-22		Use:	RUNWAY	Area:	1,079,250 SqFt
Section:	6115	of 6	From:	-			To:	-	Last Const.: 1/1/2000
Surface:	AAC	Family:	FDOT-SAPMP-PR-RW-AAC	Zone:				Category:	Rank: P
Area:	149,200 SqFt		Length:	1,492 Ft		Width:	100 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0
Section Comments:									
Work Date:	1/1/1985		Work Type: BUILT			Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/2000		Work Type: MILL and OVERLAY			Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	12/3/2018		TotalSamples:	30		Surveyed:	5		
Conditions:	PCI: 67								
Inspection Comments:									
Sample Number:	406	Type:	R	Area:	5000.00 SqFt		PCI:	67	
Sample Comments:									
48	L & T CR		M	50.00	Ft				
57	WEATHERING		M	3250.00	SqFt				
52	RAVELING		L	1750.00	SqFt				
48	L & T CR		L	143.00	Ft				
Sample Number:	412	Type:	R	Area:	5000.00 SqFt		PCI:	64	
Sample Comments:									
52	RAVELING		M	50.00	SqFt				
48	L & T CR		M	35.00	Ft				
48	L & T CR		L	247.00	Ft				
41	ALLIGATOR CR		L	5.00	SqFt				
52	RAVELING		L	1500.00	SqFt				
Sample Number:	418	Type:	R	Area:	5000.00 SqFt		PCI:	67	
Sample Comments:									
57	WEATHERING		M	3700.00	SqFt				
52	RAVELING		L	1300.00	SqFt				
48	L & T CR		L	166.00	Ft				
48	L & T CR		M	50.00	Ft				
Sample Number:	423	Type:	R	Area:	5000.00 SqFt		PCI:	73	
Sample Comments:									
52	RAVELING		M	300.00	SqFt				
52	RAVELING		L	700.00	SqFt				
48	L & T CR		L	176.00	Ft				
Sample Number:	431	Type:	R	Area:	5000.00 SqFt		PCI:	65	
Sample Comments:									
56	SWELLING		L	11.00	SqFt				
48	L & T CR		L	426.00	Ft				
57	WEATHERING		M	2250.00	SqFt				
52	RAVELING		L	2750.00	SqFt				

Network:	PGD		Name:	PUNTA GORDA AIRPORT						
Branch:	RW 4-22		Name:	RUNWAY 4-22		Use:	RUNWAY	Area:	1,079,250 SqFt	
Section:	6120 of 6		From:	-		To:	-		Last Const.:	1/1/2000
Surface:	AAC		Family:	FDOT-SAPMP-PR-RW-AAC		Zone:	Category:		Rank:	P
Area:	72,100 SqFt		Length:	2,884 Ft		Width:	25 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1985		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/2000		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	12/3/2018		TotalSamples:	14		Surveyed:	3			
Conditions:	PCI: 78									
Inspection Comments:										
Sample Number:	204		Type:	R		Area:	5000.00 SqFt		PCI:	77
Sample Comments:										
57	WEATHERING		L		4750.00 SqFt					
52	RAVELING		L		250.00 SqFt					
48	L & T CR		L		220.00 Ft					
Sample Number:	224		Type:	R		Area:	5000.00 SqFt		PCI:	79
Sample Comments:										
57	WEATHERING		L		4750.00 SqFt					
52	RAVELING		L		250.00 SqFt					
48	L & T CR		L		173.00 Ft					
Sample Number:	624		Type:	R		Area:	5000.00 SqFt		PCI:	80
Sample Comments:										
48	L & T CR		L		148.00 Ft					
57	WEATHERING		L		4750.00 SqFt					
52	RAVELING		L		250.00 SqFt					

Network:	PGD		Name:	PUNTA GORDA AIRPORT				
Branch:	RW 4-22		Name:	RUNWAY 4-22		Use: RUNWAY	Area:	1,079,250 SqFt
Section:	6125	of 6	From:	-		To:	-	Last Const.: 1/1/2007
Surface:	AC	Family:	FDOT-SAPMP-PR-RW-AC	Zone:		Category:		Rank: P
Area:	50,300 SqFt		Length:	500 Ft		Width:	100 Ft	
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft
Shoulder:	Street Type:			Grade:	0		Lanes:	0
Section Comments:								
Work Date:	1/1/2007		Work Type: New Construction - Initial			Code:	NU-IN	Is Major M&R: True
Last Insp. Date:	12/3/2018		TotalSamples:	10		Surveyed:	2	
Conditions:	PCI: 58							
Inspection Comments:								
Sample Number:	291	Type:	R	Area:	5000.00 SqFt		PCI:	64
Sample Comments:								
45	DEPRESSION	L	36.00	SqFt				
45	DEPRESSION	M	40.00	SqFt				
48	L & T CR	L	119.00	Ft				
52	RAVELING	L	500.00	SqFt				
57	WEATHERING	L	4500.00	SqFt				
42	BLEEDING	N	18.00	SqFt				
Sample Number:	296	Type:	R	Area:	5000.00 SqFt		PCI:	53
Sample Comments:								
45	DEPRESSION	L	8.00	SqFt				
48	L & T CR	L	44.00	Ft				
41	ALLIGATOR CR	L	22.00	SqFt				
57	WEATHERING	L	4000.00	SqFt				
52	RAVELING	L	1000.00	SqFt				
53	RUTTING	L	400.00	SqFt				

Network:	PGD			Name:	PUNTA GORDA AIRPORT								
Branch:	RW 4-22		Name:	RUNWAY 4-22		Use:	RUNWAY	Area:	1,079,250 SqFt				
Section:	6130		of	6	From:	-		To:	-		Last Const.:	1/1/2007	
Surface:	AC		Family:	FDOT-SAPMP-PR-RW-AC		Zone:			Category:			Rank:	P
Area:	25,150 SqFt		Length:	500 Ft		Width:	50 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/2007			Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:	12/3/2018			TotalSamples:	6			Surveyed:	2				
Conditions:	PCI:		82										
Inspection Comments:													
Sample Number:	092		Type:	R		Area:	5000.00 SqFt		PCI:	84			
Sample Comments:													
48	L & T CR		L	4.00		Ft							
52	RAVELING		L	350.00		SqFt							
52	RAVELING		M	47.00		SqFt							
Sample Number:	492		Type:	R		Area:	5000.00 SqFt		PCI:	79			
Sample Comments:													
45	DEPRESSION		L	70.00		SqFt							
52	RAVELING		L	350.00		SqFt							
48	L & T CR		L	1.00		Ft							
52	RAVELING		M	18.00		SqFt							

Network:	PGD		Name:		PUNTA GORDA AIRPORT										
Branch:	RW 9-27		Name:		RUNWAY 9-27		Use:	RUNWAY	Area:	184,602 SqFt					
Section:	6305		of 2		From:		-		To:		-		Last Const.:	1/1/2006	
Surface:	AC		Family:		FDOT-SAPMP-PR-RW-AAC		Zone:		Category:		Rank:		T		
Area:	151,500 SqFt		Length:		2,525 Ft		Width:		60 Ft						
Slabs:			Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft		
Shoulder:			Street Type:				Grade:		0		Lanes:		0		
Section Comments:															
Work Date:	1/1/1942		Work Type:		New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Work Date:	1/1/2006		Work Type:		Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True		
Last Insp. Date:	12/3/2018		TotalSamples:		50		Surveyed:		10						
Conditions:	PCI: 60														
Inspection Comments:															
Sample Number:	302		Type:	R	Area:		3000.00 SqFt		PCI:		63				
Sample Comments:															
48	L & T CR		L	110.00		Ft									
52	RAVELING		L	1960.00		SqFt									
52	RAVELING		M	200.00		SqFt									
48	L & T CR		M	50.00		Ft									
Sample Number:	307		Type:	R	Area:		3000.00 SqFt		PCI:		62				
Sample Comments:															
48	L & T CR		M	50.00		Ft									
57	WEATHERING		M	900.00		SqFt									
52	RAVELING		L	2100.00		SqFt									
48	L & T CR		L	115.00		Ft									
Sample Number:	312		Type:	R	Area:		3000.00 SqFt		PCI:		66				
Sample Comments:															
48	L & T CR		L	161.00		Ft									
57	WEATHERING		M	750.00		SqFt									
52	RAVELING		L	2250.00		SqFt									
Sample Number:	317		Type:	R	Area:		3000.00 SqFt		PCI:		62				
Sample Comments:															
48	L & T CR		M	70.00		Ft									
48	L & T CR		L	127.00		Ft									
57	WEATHERING		M	900.00		SqFt									
52	RAVELING		L	2100.00		SqFt									
Sample Number:	322		Type:	R	Area:		3000.00 SqFt		PCI:		62				
Sample Comments:															
57	WEATHERING		M	900.00		SqFt									
48	L & T CR		M	50.00		Ft									
48	L & T CR		L	112.00		Ft									
52	RAVELING		L	2100.00		SqFt									
Sample Number:	327		Type:	R	Area:		3000.00 SqFt		PCI:		62				
Sample Comments:															
48	L & T CR		L	123.00		Ft									
52	RAVELING		M	56.00		SqFt									
52	RAVELING		L	2150.00		SqFt									
48	L & T CR		M	50.00		Ft									
Sample Number:	332		Type:	R	Area:		3000.00 SqFt		PCI:		67				
Sample Comments:															
52	RAVELING		M	104.00		SqFt									
52	RAVELING		L	2027.00		SqFt									
48	L & T CR		L	195.00		Ft									

Sample Number:		337	Type:	R	Area:	3000.00 SqFt	PCI:	62
Sample Comments:								
48	L & T CR		L		202.00 Ft			
57	WEATHERING		M		900.00 SqFt			
48	L & T CR		M		50.00 Ft			
52	RAVELING		L		2100.00 SqFt			
Sample Number:		342	Type:	R	Area:	3000.00 SqFt	PCI:	65
Sample Comments:								
48	L & T CR		L		197.00 Ft			
52	RAVELING		M		100.00 SqFt			
52	RAVELING		L		2500.00 SqFt			
Sample Number:		345	Type:	R	Area:	3000.00 SqFt	PCI:	33
Sample Comments:								
52	RAVELING		M		1500.00 SqFt			
50	PATCHING		L		550.00 SqFt			
45	DEPRESSION		L		42.00 SqFt			
48	L & T CR		M		12.00 Ft			
48	L & T CR		L		49.00 Ft			
52	RAVELING		L		950.00 SqFt			

Network:	PGD		Name:	PUNTA GORDA AIRPORT						
Branch:	RW 9-27		Name:	RUNWAY 9-27		Use:	RUNWAY	Area:	184,602 SqFt	
Section:	6310 of 2		From:	-		To:	-		Last Const.:	1/1/2006
Surface:	AC		Family:	FDOT-SAPMP-PR-RW-AAC		Zone:	Category:		Rank:	P
Area:	33,102 SqFt		Length:	338 Ft		Width:	60 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	1/1/1942		Work Type:	New Construction - AC				Code:	NC-AC	
Work Date:	1/1/2006		Work Type:	Complete Reconstruction - AC				Code:	CR-AC	
Is Major M&R: True										
Last Insp. Date:	12/3/2018		TotalSamples:	8		Surveyed:	2			
Conditions:	PCI: 86									
Inspection Comments:										
Sample Number:	350		Type:	R		Area:	3000.00 SqFt		PCI:	84
Sample Comments:										
48	L & T CR		L	14.00 Ft						
52	RAVELING		L	150.00 SqFt						
57	WEATHERING		L	2850.00 SqFt						
Sample Number:	352		Type:	R		Area:	3000.00 SqFt		PCI:	88
Sample Comments:										
52	RAVELING		L	150.00 SqFt						
57	WEATHERING		L	2850.00 SqFt						

Network:	PGD		Name:		PUNTA GORDA AIRPORT						
Branch:	TL T-HANG		Name:	TAXILANE TO T-HANGARS		Use:	TAXILANE	Area:	79,013 SqFt		
Section:	4505	of 1	From:	-			To:	-	Last Const.:	1/1/2006	
Surface:	AC	Family:	DEFAULT		Zone:		Category:		Rank:	P	
Area:	79,013 SqFt		Length:	2,835 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	1/1/2006		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	15		Surveyed:					2
Conditions:	PCI: 81										
Inspection Comments:											
Sample Number:	100	Type:	R	Area:		5234.00 SqFt		PCI:	81		
Sample Comments:											
48	L & T CR		L	22.00 Ft							
52	RAVELING		L	523.00 SqFt							
57	WEATHERING		L	4711.00 SqFt							
Sample Number:	301	Type:	R	Area:		5000.00 SqFt		PCI:	80		
Sample Comments:											
48	L & T CR		L	85.00 Ft							
52	RAVELING		L	500.00 SqFt							
57	WEATHERING		L	4500.00 SqFt							

Network:	PGD		Name:		PUNTA GORDA AIRPORT					
Branch:	TW A		Name:		TAXIWAY A	Use:	TAXIWAY	Area:	433,031 SqFt	
Section:	330	of 2	From:	-			To:	-	Last Const.: 1/1/2009	
Surface:	AAC	Family:	FDOT-SAPMP-PR-TW-AAC		Zone:			Category:	Rank: P	
Area:	271,000 SqFt		Length:	2,325 Ft		Width:	60 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1984		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/2009		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	12/3/2018		TotalSamples:	47		Surveyed:	5			
Conditions:	PCI: 50									
Inspection Comments:										
Sample Number:	203	Type:	R	Area:	3750.00 SqFt		PCI:	53		
Sample Comments:										
53	RUTTING		L	216.00	SqFt					
56	SWELLING		L	25.00	SqFt					
48	L & T CR		L	148.00	Ft					
57	WEATHERING		L	3350.00	SqFt					
41	ALLIGATOR CR		L	14.00	SqFt					
52	RAVELING		L	400.00	SqFt					
Sample Number:	211	Type:	R	Area:	6000.00 SqFt		PCI:	48		
Sample Comments:										
41	ALLIGATOR CR		L	122.00	SqFt					
48	L & T CR		L	217.00	Ft					
52	RAVELING		L	599.00	SqFt					
50	PATCHING		M	10.00	SqFt					
57	WEATHERING		L	5391.00	SqFt					
53	RUTTING		L	506.00	SqFt					
Sample Number:	218	Type:	R	Area:	6000.00 SqFt		PCI:	43		
Sample Comments:										
53	RUTTING		L	900.00	SqFt					
52	RAVELING		L	600.00	SqFt					
48	L & T CR		L	206.00	Ft					
57	WEATHERING		L	5400.00	SqFt					
48	L & T CR		M	29.00	Ft					
41	ALLIGATOR CR		L	74.00	SqFt					
Sample Number:	228	Type:	R	Area:	6000.00 SqFt		PCI:	61		
Sample Comments:										
52	RAVELING		L	1000.00	SqFt					
45	DEPRESSION		L	532.00	SqFt					
48	L & T CR		L	17.00	Ft					
57	WEATHERING		L	5000.00	SqFt					
Sample Number:	239	Type:	R	Area:	6000.00 SqFt		PCI:	48		
Sample Comments:										
41	ALLIGATOR CR		L	88.00	SqFt					
52	RAVELING		L	901.00	SqFt					
52	RAVELING		M	60.00	SqFt					
48	L & T CR		L	107.00	Ft					
53	RUTTING		L	1000.00	SqFt					

Network:	PGD			Name:	PUNTA GORDA AIRPORT								
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY	Area:	38,414 SqFt				
Section:	365		of	1	From:	-		To:	-		Last Const.:	1/1/2009	
Surface:	AAC		Family:	FDOT-SAPMP-PR-TW-AAC		Zone:			Category:			Rank:	T
Area:	38,414 SqFt		Length:	295 Ft		Width:	90 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:			0	
Section Comments:													
Work Date:	1/1/2006		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	1/1/2009		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True	
Last Insp. Date:	12/3/2018		TotalSamples:	8		Surveyed:	1						
Conditions:	PCI:		67										
Inspection Comments:													
Sample Number:	103		Type:	R		Area:	4542.00 SqFt		PCI:	67			
Sample Comments:													
57	WEATHERING		L	3842.00		SqFt							
48	L & T CR		L	23.00		Ft							
52	RAVELING		L	700.00		SqFt							
53	RUTTING		L	99.00		SqFt							

Network:	PGD			Name:	PUNTA GORDA AIRPORT					
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	234,749 SqFt	
Section:	305 of 4		From:	-		To:	-		Last Const.:	1/1/1993
Surface:	AAC		Family:	FDOT-SAPMP-PR-TW-AAC		Zone:	Category:		Rank:	T
Area:	48,969 SqFt		Length:	428 Ft		Width:	50 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	1/1/1966		Work Type:	BUILT		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1983		Work Type:	OVERLAY		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1993		Work Type:	OVERLAY		Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	11		Surveyed:	2			
Conditions:	PCI: 72									
Inspection Comments:										
Sample Number:	303		Type:	R		Area:	4500.00 SqFt		PCI:	77
Sample Comments:										
57	WEATHERING		L	4275.00 SqFt						
52	RAVELING		L	225.00 SqFt						
48	L & T CR		L	191.00 Ft						
Sample Number:	306		Type:	R		Area:	4500.00 SqFt		PCI:	67
Sample Comments:										
52	RAVELING		L	225.00 SqFt						
48	L & T CR		L	153.00 Ft						
41	ALLIGATOR CR		L	36.00 SqFt						
57	WEATHERING		L	4275.00 SqFt						

Network:	PGD	Name:		PUNTA GORDA AIRPORT					
Branch:	TW C	Name:		TAXIWAY C		Use:	TAXIWAY	Area:	234,749 SqFt
Section:	310	of	4	From:	-	To:	-	Last Const.:	1/1/2009
Surface:	AAC	Family:	FDOT-SAPMP-PR-TW-AAC	Zone:		Category:		Rank:	P
Area:	158,559 SqFt	Length:	2,405 Ft	Width:	60 Ft				
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:	Street Type:	Grade:	0	Lanes:	0				
Section Comments:									
Work Date:	1/1/1977	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2009	Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R:	True
Last Insp. Date: 12/3/2018									
TotalSamples:		30	Surveyed:		4				
Conditions:	PCI:	58							
Inspection Comments:									
Sample Number:	302	Type:	R	Area:	6000.00 SqFt	PCI:	53		
Sample Comments:									
48	L & T CR	L	10.00	Ft					
52	RAVELING	L	900.00	SqFt					
57	WEATHERING	L	5100.00	SqFt					
53	RUTTING	L	700.00	SqFt					
45	DEPRESSION	L	40.00	SqFt					
Sample Number:	308	Type:	R	Area:	6000.00 SqFt	PCI:	47		
Sample Comments:									
57	WEATHERING	L	5100.00	SqFt					
52	RAVELING	L	900.00	SqFt					
48	L & T CR	L	36.00	Ft					
53	RUTTING	L	1150.00	SqFt					
41	ALLIGATOR CR	L	76.00	SqFt					
Sample Number:	317	Type:	R	Area:	3300.00 SqFt	PCI:	55		
Sample Comments:									
57	WEATHERING	L	2970.00	SqFt					
53	RUTTING	L	770.00	SqFt					
52	RAVELING	L	330.00	SqFt					
Sample Number:	322	Type:	R	Area:	4500.00 SqFt	PCI:	81		
Sample Comments:									
57	WEATHERING	L	3600.00	SqFt					
52	RAVELING	L	900.00	SqFt					

Network:	PGD			Name:	PUNTA GORDA AIRPORT						
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	234,749 SqFt		
Section:	315 of 4		From:	-			To:	-		Last Const.:	9/1/2016
Surface:	AAC		Family:	FDOT-SAPMP-PR-TW-AAC		Zone:	Category:		Rank: P		
Area:	23,546 SqFt		Length:	600 Ft		Width:	75 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1977		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2009		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Work Date:	9/1/2016		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Last Insp. Date:	3/9/2015		TotalSamples:	32		Surveyed:	4				
Conditions:	PCI: 84		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	302		Type:	R		Area:	6000.00 SqFt		PCI:		
Sample Comments:											
48	LONGITUDINAL/TRANSVERSE CRACKING		L	6.00 Ft							
52	RAVELING		L	300.00 SqFt							
57	WEATHERING		L	5700.00 SqFt							
Sample Number:	308		Type:	R		Area:	6000.00 SqFt		PCI:		
Sample Comments:											
48	LONGITUDINAL/TRANSVERSE CRACKING		L	21.00 Ft							
52	RAVELING		L	105.00 SqFt							
57	WEATHERING		L	5600.00 SqFt							
52	RAVELING		L	295.00 SqFt							
Sample Number:	317		Type:	R		Area:	6000.00 SqFt		PCI:		
Sample Comments:											
48	LONGITUDINAL/TRANSVERSE CRACKING		L	17.00 Ft							
52	RAVELING		L	300.00 SqFt							
57	WEATHERING		L	5700.00 SqFt							
Sample Number:	324		Type:	R		Area:	4500.00 SqFt		PCI:		
Sample Comments:											
48	LONGITUDINAL/TRANSVERSE CRACKING		L	14.00 Ft							
52	RAVELING		L	450.00 SqFt							
57	WEATHERING		L	4050.00 SqFt							

Network:	PGD			Name:	PUNTA GORDA AIRPORT				
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	234,749 SqFt
Section:	350	of	4	From:	-	To:	-	Last Const.:	1/1/1993
Surface:	AAC	Family:	FDOT-SAPMP-PR-TW-AAC	Zone:		Category:		Rank:	P
Area:	3,675 SqFt	Length:	60 Ft	Width:	25 Ft				
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:	Street Type:	Grade:	0	Lanes:	0				
Section Comments:									
Work Date:	1/1/1993	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1993	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date: 12/3/2018									
TotalSamples:		1		Surveyed: 1					
Conditions:	PCI:	62							
Inspection Comments:									
Sample Number:	312	Type:	R	Area:	3675.00 SqFt	PCI:	62		
Sample Comments:									
52	RAVELING	L	735.00	SqFt					
50	PATCHING	L	146.00	SqFt					
57	WEATHERING	L	2794.00	SqFt					
48	L & T CR	M	100.00	Ft					
48	L & T CR	L	179.00	Ft					

Network:	PGD		Name:	PUNTA GORDA AIRPORT								
Branch:	TW D	Name:	TAXIWAY D		Use:	TAXIWAY	Area:	364,992 SqFt				
Section:	102	of 8	From:	-		To:	-		Last Const.:	1/1/2002		
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC		Zone:	Category:		Rank:	P			
Area:	83,519 SqFt		Length:	1,400 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	1/1/2002		Work Type:			New Construction - Initial		Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	17		Surveyed:	3					
Conditions:	PCI: 36											
Inspection Comments:												
Sample Number:	085		Type:	R		Area:	4560.00 SqFt		PCI:	66		
Sample Comments:												
56	SWELLING		L	45.00 SqFt								
52	RAVELING		L	500.00 SqFt								
48	L & T CR		L	380.00 Ft								
57	WEATHERING		L	4060.00 SqFt								
Sample Number:	094		Type:	R		Area:	5108.00 SqFt		PCI:	27		
Sample Comments:												
52	RAVELING		L	749.00 SqFt								
57	WEATHERING		L	4243.00 SqFt								
50	PATCHING		L	116.00 SqFt								
48	L & T CR		L	398.00 Ft								
41	ALLIGATOR CR		L	364.00 SqFt								
55	SLIPPAGE CR		N	160.00 SqFt								
53	RUTTING		L	875.00 SqFt								
Sample Number:	096		Type:	R		Area:	5000.00 SqFt		PCI:	17		
Sample Comments:												
53	RUTTING		M	800.00 SqFt								
52	RAVELING		L	1000.00 SqFt								
41	ALLIGATOR CR		L	878.00 SqFt								
57	WEATHERING		L	4000.00 SqFt								
53	RUTTING		L	800.00 SqFt								
48	L & T CR		L	51.00 Ft								

Network:	PGD			Name:	PUNTA GORDA AIRPORT				
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	364,992 SqFt
Section:	115	of	8	From:	-	To:	-	Last Const.:	1/1/1993
Surface:	AAC	Family:	FDOT-SAPMP-PR-TW-AAC	Zone:		Category:		Rank:	P
Area:	214,000 SqFt		Length:	4,280 Ft		Width:	50 Ft		
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1983		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1993		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1993		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	12/3/2018		TotalSamples:	43		Surveyed:	5		
Conditions:	PCI:	35							
Inspection Comments:									
Sample Number:	107	Type:	R	Area:	5000.00 SqFt		PCI:	36	
Sample Comments:									
56	SWELLING	L	15.00	SqFt					
41	ALLIGATOR CR	L	220.00	SqFt					
48	L & T CR	M	100.00	Ft					
57	WEATHERING	L	4000.00	SqFt					
52	RAVELING	L	1000.00	SqFt					
48	L & T CR	L	291.00	Ft					
53	RUTTING	L	1400.00	SqFt					
Sample Number:	114	Type:	R	Area:	5000.00 SqFt		PCI:	11	
Sample Comments:									
56	SWELLING	L	10.00	SqFt					
41	ALLIGATOR CR	L	340.00	SqFt					
57	WEATHERING	L	4250.00	SqFt					
48	L & T CR	M	77.00	Ft					
52	RAVELING	L	750.00	SqFt					
53	RUTTING	H	1400.00	SqFt					
48	L & T CR	L	406.00	Ft					
Sample Number:	122	Type:	R	Area:	5000.00 SqFt		PCI:	33	
Sample Comments:									
41	ALLIGATOR CR	L	338.00	SqFt					
57	WEATHERING	L	4000.00	SqFt					
52	RAVELING	L	1000.00	SqFt					
48	L & T CR	L	284.00	Ft					
48	L & T CR	M	66.00	Ft					
53	RUTTING	L	1400.00	SqFt					
Sample Number:	134	Type:	R	Area:	5000.00 SqFt		PCI:	41	
Sample Comments:									
41	ALLIGATOR CR	L	140.00	SqFt					
57	WEATHERING	L	3500.00	SqFt					
53	RUTTING	L	100.00	SqFt					
48	L & T CR	M	177.00	Ft					
56	SWELLING	L	60.00	SqFt					
48	L & T CR	L	276.00	Ft					
52	RAVELING	L	1500.00	SqFt					
Sample Number:	145	Type:	R	Area:	5000.00 SqFt		PCI:	55	
Sample Comments:									
48	L & T CR	M	140.00	Ft					
52	RAVELING	L	1000.00	SqFt					
41	ALLIGATOR CR	L	36.00	SqFt					
57	WEATHERING	L	4000.00	SqFt					

48	L & T CR	L	441.00	Ft
56	SWELLING	L	60.00	SqFt

Network:	PGD	Name:		PUNTA GORDA AIRPORT				
Branch:	TW D	Name:	TAXIWAY D		Use:	TAXIWAY	Area:	364,992 SqFt
Section:	120	of 8	From:	-		To:	-	
Surface:	AAC	Family:	FDOT-SAPMP-PR-TW-AAC		Zone:	Category:	Rank:	P
Area:	43,181 SqFt		Length:	725 Ft		Width:	50 Ft	
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1983		Work Type: BUILT			Code:	IMPORTED	
Work Date:	1/1/1993		Work Type: OVERLAY			Code:	IMPORTED	
Last Insp. Date: 12/3/2018								
Conditions:	PCI:	58	TotalSamples:		8	Surveyed:	2	
Inspection Comments:								
Sample Number:	149	Type:	R	Area:		6028.00 SqFt	PCI:	59
Sample Comments:								
57	WEATHERING		M	3918.00 SqFt				
56	SWELLING		L	25.00 SqFt				
48	L & T CR		M	280.00 Ft				
52	RAVELING		L	2110.00 SqFt				
48	L & T CR		L	127.00 Ft				
Sample Number:	152	Type:	R	Area:		5651.00 SqFt	PCI:	57
Sample Comments:								
52	RAVELING		L	500.00 SqFt				
57	WEATHERING		L	5151.00 SqFt				
56	SWELLING		M	9.00 SqFt				
56	SWELLING		L	75.00 SqFt				
48	L & T CR		M	167.00 Ft				
48	L & T CR		L	405.00 Ft				

Network:	PGD	Name:		PUNTA GORDA AIRPORT					
Branch:	TW D	Name:	TAXIWAY D		Use:	TAXIWAY	Area:	364,992 SqFt	
Section:	155	of 8	From:	-	To:	-	Last Const.:	1/1/1993	
Surface:	AAC	Family:	FDOT-SAPMP-PR-TW-AC	Zone:		Category:	Rank:	P	
Area:	4,146 SqFt	Length:	90 Ft	Width:	25 Ft				
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:	Street Type:	Grade:	0	Lanes:	0				
Section Comments:									
Work Date:	1/1/1992	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1993	Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Last Insp. Date:	12/3/2018	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI: 64								
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	4146.00 SqFt	PCI:	64		
Sample Comments:									
43	BLOCK CR	L	58.00	SqFt					
52	RAVELING	L	622.00	SqFt					
57	WEATHERING	L	3524.00	SqFt					
56	SWELLING	L	15.00	SqFt					
48	L & T CR	M	8.00	Ft					
48	L & T CR	L	195.00	Ft					

Network:	PGD			Name:	PUNTA GORDA AIRPORT								
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY		Area:	364,992 SqFt			
Section:	160		of	8	From:	-		To:	-		Last Const.:	1/1/1993	
Surface:	AAC		Family:	FDOT-SAPMP-PR-TW-AAC		Zone:			Category:			Rank:	P
Area:	2,534 SqFt		Length:	65 Ft		Width:	27 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1993		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1993		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True	
Last Insp. Date: 12/3/2018													
Conditions:	PCI: 78		TotalSamples:	1		Surveyed:	1						
Inspection Comments:													
Sample Number:	100		Type:	R		Area:	2534.00 SqFt		PCI:	78			
Sample Comments:													
52	RAVELING		L	300.00 SqFt									
57	WEATHERING		L	2234.00 SqFt									
48	L & T CR		L	98.00 Ft									

Network:	PGD			Name:	PUNTA GORDA AIRPORT									
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	364,992 SqFt					
Section:	172		of	8	From:	-		To:	-		Last Const.:	1/1/1992		
Surface:	AC		Family:	FDOT-SAPMP-PR-TW-AC		Zone:			Category:			Rank:	P	
Area:	3,508 SqFt		Length:	55 Ft		Width:	60 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1992			Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True		
Last Insp. Date:	12/3/2018			TotalSamples:	1			Surveyed:	1					
Conditions:	PCI:		58											
Inspection Comments:														
Sample Number:	109		Type:	R		Area:	3508.00 SqFt		PCI:	58				
Sample Comments:														
56	SWELLING		L	18.00		SqFt								
57	WEATHERING		L	3157.00		SqFt								
52	RAVELING		L	351.00		SqFt								
48	L & T CR		L	76.00		Ft								
48	L & T CR		M	108.00		Ft								
43	BLOCK CR		L	499.00		SqFt								

Network:	PGD		Name:	PUNTA GORDA AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	364,992 SqFt		
Section:	180	of 8	From:	-			To:	-		Last Const.:	1/1/1993
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC		Zone:				Category:	Rank: P	
Area:	10,800 SqFt		Length:	300 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1993		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:		77								
Inspection Comments:											
Sample Number:	101	Type:	R	Area:	5400.00 SqFt		PCI:	77			
Sample Comments:											
57	WEATHERING		L	4900.00 SqFt							
48	L & T CR		L	229.00 Ft							
52	RAVELING		L	500.00 SqFt							

Network:	PGD		Name:	PUNTA GORDA AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	364,992 SqFt		
Section:	195	of 8	From:	-			To:	-		Last Const.:	1/1/1993
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC		Zone:				Category:	Rank: P	
Area:	3,304 SqFt		Length:	52 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1993		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 69										
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	3304.00 SqFt		PCI:	69			
Sample Comments:											
54	SHOVING	M	3.00	SqFt							
48	L & T CR	L	105.00	Ft							
57	WEATHERING	L	2808.00	SqFt							
52	RAVELING	L	496.00	SqFt							
48	L & T CR	M	3.00	Ft							

Network:	PGD			Name:	PUNTA GORDA AIRPORT							
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY		Area:	89,853 SqFt		
Section:	410		of 2	From:	-		To:	-		Last Const.:	1/1/2006	
Surface:	AC		Family:	FDOT-SAPMP-PR-TW-AC		Zone:			Category:	Rank: P		
Area:	19,242 SqFt		Length:	895 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2006		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 78											
Inspection Comments:												
Sample Number:	301		Type:	R		Area:	5000.00 SqFt		PCI:	78		
Sample Comments:												
48	L & T CR		L	182.00 Ft								
57	WEATHERING		L	4750.00 SqFt								
52	RAVELING		L	250.00 SqFt								

Network:	PGD			Name:	PUNTA GORDA AIRPORT						
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	89,853 SqFt		
Section:	415		of	2	From:	-		To:	-		
Surface:	AC		Family:	FDOT-SAPMP-PR-TW-AC		Zone:	Category:		Rank: P		
Area:	70,611 SqFt		Length:	4,588 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2004		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	15		Surveyed:	2				
Conditions:	PCI: 83										
Inspection Comments:											
Sample Number:	105		Type:	R		Area:	5000.00 SqFt		PCI:	83	
Sample Comments:											
52	RAVELING		L	50.00 SqFt							
57	WEATHERING		M	200.00 SqFt							
48	L & T CR		L	59.00 Ft							
57	WEATHERING		L	4750.00 SqFt							
Sample Number:	109		Type:	R		Area:	4375.00 SqFt		PCI:	83	
Sample Comments:											
52	RAVELING		L	50.00 SqFt							
57	WEATHERING		M	150.00 SqFt							
48	L & T CR		L	61.00 Ft							
57	WEATHERING		L	4175.00 SqFt							

Network:	PGD			Name:	PUNTA GORDA AIRPORT						
Branch:	TW E1		Name:	TAXIWAY E1		Use:	TAXIWAY	Area:	7,748 SqFt		
Section:	450	of	1	From:	-	To:	-	Last Const.:	1/1/2010		
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC		Zone:	Category:	Rank:	P			
Area:	7,748 SqFt	Length:	200 Ft		Width:	30 Ft					
Slabs:	Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:	Grade:		0		Lanes:	0				
Section Comments:											
Work Date:	1/1/2010		Work Type:			New Construction - Initial		Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	62									
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	4545.00 SqFt		PCI:	62			
Sample Comments:											
48	L & T CR		L	45.00 Ft							
52	RAVELING		M	50.00 SqFt							
52	RAVELING		L	4495.00 SqFt							
56	SWELLING		L	7.00 SqFt							

Network:	PGD			Name:	PUNTA GORDA AIRPORT				
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	50,341 SqFt
Section:	1105	of	1	From:	-	To:	-	Last Const.:	12/25/1999
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC	Zone:		Category:		Rank:	P
Area:	50,341 SqFt	Length:	750 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1999	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	12/3/2018	TotalSamples:	11	Surveyed:	2				
Conditions:	PCI: 62								
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	4412.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	M	70.00 Ft						
48	L & T CR	L	377.00 Ft						
57	WEATHERING	M	3750.00 SqFt						
52	RAVELING	L	662.00 SqFt						
Sample Number:	107	Type:	R	Area:	5032.00 SqFt	PCI:	60		
Sample Comments:									
56	SWELLING	L	7.00 SqFt						
57	WEATHERING	M	4026.00 SqFt						
48	L & T CR	L	277.00 Ft						
48	L & T CR	M	216.00 Ft						
52	RAVELING	L	1006.00 SqFt						

Network:	PGD			Name:	PUNTA GORDA AIRPORT				
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY	Area:	34,930 SqFt
Section:	110	of	1	From:	-	To:	-	Last Const.:	1/1/1993
Surface:	AAC	Family:	FDOT-SAPMP-PR-TW-AAC		Zone:		Category:		Rank: P
Area:	34,930 SqFt		Length:	505 Ft		Width:	50 Ft		
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1988		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1993		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1993		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	12/3/2018		TotalSamples:	5		Surveyed:	2		
Conditions:	PCI: 54								
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	5651.00 SqFt		PCI:	72	
Sample Comments:									
52	RAVELING	L	848.00	SqFt					
57	WEATHERING	L	4803.00	SqFt					
56	SWELLING	L	49.00	SqFt					
48	L & T CR	L	307.00	Ft					
Sample Number:	104	Type:	R	Area:	8778.00 SqFt		PCI:	43	
Sample Comments:									
41	ALLIGATOR CR	L	184.00	SqFt					
56	SWELLING	L	116.00	SqFt					
52	RAVELING	L	1756.00	SqFt					
53	RUTTING	L	924.00	SqFt					
48	L & T CR	M	54.00	Ft					
48	L & T CR	L	275.00	Ft					
57	WEATHERING	L	7022.00	SqFt					

Network:	PGD			Name:	PUNTA GORDA AIRPORT						
Branch:	TW N T-HAN		Name:	TAXIWAY TO NORTH T-HANGARS		Use:	TAXIWAY	Area:	6,938 SqFt		
Section:	215	of 1	From:	-			To:	-		Last Const.:	1/1/1989
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC		Zone:				Category:	Rank: P	
Area:	6,938 SqFt		Length:	250 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1989		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI:	35									
Inspection Comments:											
Sample Number:	100	Type:	R	Area:	6938.00 SqFt		PCI:	35			
Sample Comments:											
52	RAVELING	L	6934.00	SqFt							
45	DEPRESSION	M	192.00	SqFt							
48	L & T CR	L	244.00	Ft							
45	DEPRESSION	H	100.00	SqFt							
50	PATCHING	M	4.00	SqFt							
53	RUTTING	L	65.00	SqFt							
45	DEPRESSION	L	89.00	SqFt							
41	ALLIGATOR CR	L	15.00	SqFt							

Network:		PGD		Name:		PUNTA GORDA AIRPORT						
Branch:	TW T-HANG		Name:	TAXIWAY TO T-HANGARS		Use:	TAXIWAY	Area:	132,726 SqFt			
Section:	4405		of	6	From:	-		To:	-		Last Const.:	1/1/1992
Surface:	AC		Family:	FDOT-SAPMP-PR-TW-AC		Zone:			Category:	Rank: P		
Area:	22,295 SqFt		Length:	300 Ft		Width:	75 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1992		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 62											
Inspection Comments:												
Sample Number:	100		Type:	R		Area:	6192.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		L	217.00		Ft						
53	RUTTING		L	40.00		SqFt						
57	WEATHERING		M	4334.00		SqFt						
43	BLOCK CR		L	213.00		SqFt						
52	RAVELING		L	1858.00		SqFt						

Network:		PGD		Name:		PUNTA GORDA AIRPORT						
Branch:	TW T-HANG		Name:	TAXIWAY TO T-HANGARS		Use:	TAXIWAY	Area:	132,726 SqFt			
Section:	4410		of	6	From:	-		To:	-		Last Const.:	1/1/1990
Surface:	AC		Family:	FDOT-SAPMP-PR-TW-AC		Zone:			Category:	Rank: P		
Area:	15,629 SqFt		Length:	234 Ft		Width:	66 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1990		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	3		Surveyed:	1					
Conditions:	PCI: 59											
Inspection Comments:												
Sample Number:	106		Type:	R		Area:	5069.00 SqFt		PCI:	59		
Sample Comments:												
45	DEPRESSION		L	24.00 SqFt								
52	RAVELING		M	100.00 SqFt								
52	RAVELING		L	1985.00 SqFt								
50	PATCHING		L	9.00 SqFt								
57	WEATHERING		M	2877.00 SqFt								
48	L & T CR		L	258.00 Ft								
50	PATCHING		M	98.00 SqFt								

Network:	PGD		Name:	PUNTA GORDA AIRPORT							
Branch:	TW T-HANG		Name:	TAXIWAY TO T-HANGARS		Use:	TAXIWAY	Area:	132,726 SqFt		
Section:	4415	of 6	From:	-			To:	-		Last Const.:	12/25/1999
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC		Zone:				Category:	Rank: P	
Area:	7,080 SqFt		Length:	184 Ft		Width:	30 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	12/25/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI: 80										
Inspection Comments:											
Sample Number:	200	Type:	R	Area:	3379.00 SqFt		PCI:	80			
Sample Comments:											
57	WEATHERING		L	3179.00 SqFt							
48	L & T CR		L	83.00 Ft							
52	RAVELING		L	200.00 SqFt							
56	SWELLING		L	3.00 SqFt							

Network:	PGD		Name:		PUNTA GORDA AIRPORT							
Branch:	TW T-HANG		Name:	TAXIWAY TO T-HANGARS		Use:	TAXIWAY	Area:	132,726 SqFt			
Section:	4420		of	6	From:	-		To:	-		Last Const.:	1/1/1992
Surface:	AC		Family:	FDOT-SAPMP-PR-TW-AC		Zone:			Category:	Rank: T		
Area:	45,846 SqFt		Length:	519 Ft		Width:	30 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1992		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Last Insp. Date:	12/3/2018		TotalSamples:	11		Surveyed:	3					
Conditions:	PCI: 62											
Inspection Comments:												
Sample Number:	201		Type:	R		Area:	3750.00 SqFt		PCI:	58		
Sample Comments:												
50	PATCHING		M	182.00 SqFt								
50	PATCHING		L	32.00 SqFt								
48	L & T CR		L	215.00 Ft								
57	WEATHERING		M	2829.00 SqFt								
52	RAVELING		L	707.00 SqFt								
48	L & T CR		H	12.00 Ft								
Sample Number:	303		Type:	R		Area:	3750.00 SqFt		PCI:	66		
Sample Comments:												
52	RAVELING		L	2245.00 SqFt								
57	WEATHERING		M	1497.00 SqFt								
50	PATCHING		L	8.00 SqFt								
48	L & T CR		L	194.00 Ft								
Sample Number:	400		Type:	R		Area:	5695.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		H	7.00 Ft								
57	WEATHERING		M	3417.00 SqFt								
52	RAVELING		L	2278.00 SqFt								
48	L & T CR		L	523.00 Ft								

Network:	PGD		Name:	PUNTA GORDA AIRPORT								
Branch:	TW T-HANG		Name:	TAXIWAY TO T-HANGARS		Use:	TAXIWAY		Area:	132,726 SqFt		
Section:	4425 of 6		From:	-			To:	-			Last Const.:	1/1/1992
Surface:	AC		Family:	FDOT-SAPMP-PR-TW-AC		Zone:				Category:	Rank: P	
Area:	27,208 SqFt		Length:	475 Ft		Width:	30 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0			Lanes:	0			
Section Comments:												
Work Date:	1/1/1992		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	6		Surveyed:	2					
Conditions:	PCI: 64											
Inspection Comments:												
Sample Number:	500		Type:	R		Area:	5258.00 SqFt		PCI:	62		
Sample Comments:												
50	PATCHING		M	60.00 SqFt								
52	RAVELING		L	2003.00 SqFt								
57	WEATHERING		M	3005.00 SqFt								
48	L & T CR		L	185.00 Ft								
48	L & T CR		H	26.00 Ft								
Sample Number:	601		Type:	R		Area:	4500.00 SqFt		PCI:	67		
Sample Comments:												
48	L & T CR		L	327.00 Ft								
50	PATCHING		L	4.00 SqFt								
52	RAVELING		L	4496.00 SqFt								

Network:	PGD		Name:	PUNTA GORDA AIRPORT							
Branch:	TW T-HANG		Name:	TAXIWAY TO T-HANGARS		Use:	TAXIWAY	Area:	132,726 SqFt		
Section:	4430	of 6	From:	-			To:	-		Last Const.:	1/1/2003
Surface:	AC	Family:	FDOT-SAPMP-PR-TW-AC		Zone:				Category:	Rank: P	
Area:	14,668 SqFt		Length:	500 Ft		Width:	30 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2003		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	12/3/2018		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI: 68										
Inspection Comments:											
Sample Number:	702	Type:	R	Area:	3575.00 SqFt		PCI:	68			
Sample Comments:											
57	WEATHERING		M	100.00	SqFt						
48	L & T CR		L	270.00	Ft						
57	WEATHERING		L	1975.00	SqFt						
52	RAVELING		L	1500.00	SqFt						