## FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION AND SPACEPORTS OFFICE







Florida Department of Transportation

## Statewide Airfield Pavement Management Program

#### Prepared by:

FDOT Aviation and Spaceports Office 605 Suwannee Street Tallahassee, Florida 32399-0450

















OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS



## **Table of Contents**

Executive Summary10
Program Background10
Summary of Results11Pavement Condition Index (Latest Inspection)11Forecasted Pavement Condition Index 2020-202912Major Rehabilitation Planning 2020-202913
Summary of Ormond Beach Municipal Airport14
Chapter 1 – Introduction16
1.1 Background16
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-201916
1.3 Organization181.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager181.3.2 Participating Florida Public-Use and Publicly Owned Airports181.3.3 Florida Department of Transportation District Offices181.3.4 Consultant18
1.4 Purpose of Airport Pavement Evaluation Report20
1.5 History of the Program
1.6 Federal Aviation Administration (FAA)22
1.7 FDOT SAPMP Objectives and Components221.7.1 Program Objectives221.7.2 Program Components22
1.8 References
Chapter 2 – Methodology28
2.1 Airfield Pavement Database28
2.2 Airfield Pavement System Inventory       28         2.2.1 Pavement Management Program Network Definition Terminology       29
2.3 Airfield Pavement Structure
2.4 Airfield Pavement Work History       33         2.4.1 Airfield Pavement Record Keeping       33
2.5 Airfield Pavement Traffic33
2.6 Airfield Pavement Condition Index (PCI) Survey332.6.1 PCI Survey Methodology332.6.2 Pavement Distress Types35



2.6.3 PCI Survey Inspection Procedures392.6.4 Updates to the ASTM D5340-1240
Chapter 3 – Airfield Pavement System Inventory43
3.1 Airfield Pavement Network Information       43         3.1.1 Previous and/or Anticipated Airfield Pavement Construction       43         3.1.2 Estimated Pavement Age       45         3.1.3 Functional Use Classification       47         3.1.4 Pavement Surface Type       48         3.1.5 Pavement System Inventory Details       49
Chapter 4 – Airfield Pavement Condition54
4.1 Airfield Pavement Condition Index (Latest Inspection)       54         4.1.1 Network-Level Analysis       54         4.1.2 Branch-Level Analysis       54         4.1.3 Section-Level Analysis       56         4.2 Summary of Pavement Condition Evaluation Results       59         4.2.1 Network-Level Observations       59         4.2.2 Branch-Level Observations       59
4.3 Forecasted Pavement Conditions614.3.1 Performance Models and Prediction Curves614.3.2 Branch-Level Pavement Condition Forecast614.3.3 Section-Level Pavement Condition Forecast634.3.4 Forecasted PCI Considerations66
Chapter 5 – Localized Maintenance and Repair Planning68
5.1 Localized Maintenance and Repair68
5.2 Localized Maintenance and Repair Policy69
5.3 Localized Maintenance and Repair Analysis and Recommendations73
Chapter 6 – Major Rehabilitation Planning77
6.1 Major Rehabilitation776.1.1 Critical PCI796.1.2 FDOT Recommended Minimum Service-Level PCI79
6.2 Major Rehabilitation Policy806.2.1 Major Rehabilitation Pavement SectionDevelopment806.2.2 Major Rehabilitation Planning-Level Unit Costs82
6.3 Major Rehabilitation Needs
Chapter 7 – Conclusion86
7.1 Recommendations867.1.1 Continued PCI Survey Inspections867.1.2 Localized Maintenance and Repair86



7.1.3 Major Rehabilitation	86
7.1.4 Pavement Management System	
7.2 Supporting Documents	87
001 – Airfield Pavement Network Definition Exhibit	87
002 – Airfield Pavement System Inventory Exhibit	87
003 - Airfield Pavement Condition Index Exhibit	87
004 – Airfield Pavement Major Rehabilitation Exhibit	87
Inspection Photograph Documentation	87
7.3 Conclusion	88





Appendix A Airfield Pavement Analysis Tables

Appendix B Airfield Pavement Localized Maintenance and Repair and Major

Rehabilitation

Appendix C Technical Exhibits

Appendix D Inspection Photograph Documentation

Appendix E Inspection Distress Details



## **List of Figures**

Figure E-4 Major Rehabilitation Planning Annual Budget 2020-202913
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts17
Figure 1.7.2 (a) Typical Pavement Condition Life Cycle23
Figure 1.7.2 (b) General Pavement Treatments by Condition Range24
Figures 1.7.2 (c) Flexible Asphalt Concrete25
Figures 1.7.2 (d) Rigid Portland Cement Concrete25
Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit44
Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit45
Figure 3.1.2 Average Age of Pavements at Inspection46
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area47
Figure 3.1.4 (a) Pavement Surface Type by Area (SF)48
Figure 3.1.4 (b) Pavement Surface Type by Area (%)49
Figure 4.1.1 Latest Condition – Overall Network54
Figure 4.1.2 (a) Latest Condition – Runway Pavements55
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements55
Figure 4.1.2 (c) Latest Condition – Apron Pavements56
Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit58
Figure 4.2.2 Pavement Condition Summary by Facility Use60
Figure 4.3.2 (a) Forecasted Runway Pavement Performance61
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance
Figure 4.3.2 (c) Forecasted Apron Pavement Performance
Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI77
Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI78
Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year84
Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit84



## **List of Tables**

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level11
Table E-2 Pavement Condition Index Forecast 2020-202912
Table E-3 Major Rehabilitation Planning 2020-202913
Table 2.2.1 Airfield Pavement Database Network Definition Terminology30
Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields 35
Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete- Surfaced Airfields
Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete- Surfaced Airfields
Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields
Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete- Surfaced Airfields
Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete- Surfaced Airfields
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete39
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete
Table 2.6.4 Summary of Updates to ASTM D5340-1241
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction43
Table 3.1.5 Pavement System Inventory Details
Table 4.1.3 Latest Pavement Condition Index Summary57
Table 4.3.3 Forecasted PCI 2020-202964
Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete69
Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete70
Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete72



Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete
Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level
Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level
Table 5.3 (c) Summary of Localized Maintenance75
Table 6.1.2 FDOT Recommended Minimum Service-Level PCI79
Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete
Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete
Table 6.2.2 Reliever (RL) Major Rehabilitation Planning-Level Unit Cost by Pavement Type
Table 6.3.1 10-Year Major Rehabilitation Needs83



# **Executive Summary**





## **Executive Summary**

#### Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the documented procedures set forth by ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.





### Summary of Results

#### Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) - Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
OMN	RUNWAY 8-26	RUNWAY	6105	292,950	100	Good
OMN	RUNWAY 17-35	RUNWAY	6205	329,912	73	Satisfactory
OMN	RUNWAY 17-35	RUNWAY	6210	10,188	72	Satisfactory
OMN	RUNWAY 17-35	RUNWAY	6215	30,400	100	Good
OMN	TAXIWAY A	TAXIWAY	100	149,004	93	Good
OMN	TAXIWAY A	TAXIWAY	102	2,434	100	Good
OMN	TAXIWAY A	TAXIWAY	105	4,550	94	Good
OMN	TAXIWAY A	TAXIWAY	110	8,089	90	Good
OMN	TAXIWAY A	TAXIWAY	112	3,083	100	Good
OMN	TAXIWAY A	TAXIWAY	115	8,054	94	Good
OMN	TAXIWAY A	TAXIWAY	117	3,118	100	Good
OMN	TAXIWAY B	TAXIWAY	205	21,323	37	Very Poor
OMN	TAXIWAY B	TAXIWAY	210	9,023	94	Good
OMN	TAXIWAY C	TAXIWAY	305	35,470	94	Good
OMN	TAXIWAY D	TAXIWAY	405	74,127	38	Very Poor
OMN	TAXIWAY D	TAXIWAY	410	14,057	94	Good
OMN	TAXIWAY E	TAXIWAY	505	56,507	38	Very Poor
OMN	TAXIWAY E	TAXIWAY	510	29,167	94	Good
OMN	TAXIWAY F	TAXIWAY	605	41,694	46	Poor
OMN	TAXIWAY F	TAXIWAY	650	6,273	36	Very Poor
OMN	TAXIWAY G	TAXIWAY	700	144,093	91	Good
OMN	TAXIWAY G2	TAXIWAY	705	9,003	94	Good
OMN	TAXIWAY G3	TAXIWAY	710	8,999	94	Good
OMN	TAXIWAY TO T-HANGARS	TAXIWAY	2004	17,255	9	Failed
OMN	WEST APRON	APRON	4102	22,255	28	Very Poor
OMN	WEST APRON	APRON	4105	164,592	61	Fair
OMN	CENTER APRON	APRON	4204	5,932	30	Very Poor
OMN	CENTER APRON	APRON	4205	141,436	33	Very Poor
OMN	EAST APRON - HANGAR AREA	APRON	4305	52,638	28	Very Poor
OMN	AP T HANG	APRON	4410	54,829	68	Fair
OMN	RUN-UP APRON	APRON	5110	28,383	94	Good
OMN	RUN-UP APRON	APRON	5115	28,289	91	Good
OMN	RUN-UP APRON	APRON	5120	40,182	94	Good
OMN	RUN-UP APRON	APRON	5125	40,187	94	Good





#### Forecasted Pavement Condition Index 2020-2029

Table E-2 Pavement Condition Index Forecast 2020-2029

Network		Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
OMN	AP CENTER	4204	30	29	29	29	28	28	28	27	27	27	26
OMN	AP CENTER	4205	33	30	28	26	24	22	20	17	15	13	11
OMN	AP E	4305	28	27	27	26	26	26	25	25	25	24	24
OMN	AP RU	5110	94	91	89	87	85	82	80	78	76	74	73
OMN	AP RU	5115	91	88	86	84	82	80	78	76	74	72	70
OMN	AP RU	5120	94	91	89	87	85	82	80	78	76	74	73
OMN	AP RU	5125	94	91	89	87	85	82	80	78	76	74	73
OMN	AP T HANG	4410	68	66	65	64	63	62	61	60	59	58	57
OMN	AP W	4102	28	27	27	26	26	26	25	25	25	24	24
OMN	AP W	4105	61	60	59	58	57	56	56	55	54	54	53
OMN	RW 17-35	6205	73	71	70	69	68	67	66	65	65	64	63
OMN	RW 17-35	6210	72	70	69	68	67	66	66	65	64	63	62
OMN	RW 17-35	6215	100	98	96	93	91	89	87	85	82	81	79
OMN	RW 8-26	6105	100	98	96	93	91	89	87	85	82	81	79
OMN	TW A	100	93	91	89	88	86	85	83	82	80	79	77
OMN	TW A	102	100	98	96	94	93	91	89	88	86	85	83
OMN	TW A	105	94	91	89	87	85	84	82	80	79	77	76
OMN	TW A	110	90	88	86	85	83	82	80	79	77	76	75
OMN	TW A	112	100	98	96	94	93	91	89	88	86	85	83
OMN	TW A	115	94	92	90	89	87	86	84	83	81	80	78
OMN	TW A	117	100	98	96	94	93	91	89	88	86	85	83
OMN	TW B	205	37	35	33	31	29	27	25	23	21	19	17
OMN	TW B	210	94	92	90	89	87	86	84	83	81	80	78
OMN	TW C	305	94	92	90	89	87	86	84	83	81	80	78
OMN	TW D	405	38	36	34	32	30	28	26	24	22	20	18
OMN	TW D	410	94	92	90	89	87	86	84	83	81	80	78
OMN	TW E	505	38	36	34	32	30	28	26	24	22	20	18
OMN	TW E	510	94	92	90	89	87	86	84	83	81	80	78
OMN	TW F	605	46	45	44	43	43	42	41	41	40	40	39
OMN	TW F	650	36	35	35	35	34	34	34	34	34	33	33
OMN	TW G	700	91	89	87	86	84	83	81	80	78	77	76
OMN	TW G2	705	94	92	90	89	87	86	84	83	81	80	78
OMN	TW G3	710	94	92	90	89	87	86	84	83	81	80	78
OMN	TW T-HANG	2004	9	7	6	5	4	3	2	1	0	0	0






#### Major Rehabilitation Planning 2020-2029

Table E-3 Major Rehabilitation Planning 2020-2029

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	OMN	AP CENTER	4204	AC	5,932	29	AC Reconstruction	\$ 75,000.00
2020	OMN	AP CENTER	4205	AAC	141,436	30	AC Reconstruction	\$ 1,768,000.00
2020	OMN	AP E	4305	AC	52,638	27	AC Reconstruction	\$ 658,000.00
2020	OMN	AP W	4102	AC	22,255	27	AC Reconstruction	\$ 279,000.00
2020	OMN	AP W	4105	AC	164,592	60	AC Restoration	\$ 1,564,000.00
2020	OMN	TW B	205	AAC	21,323	35	AC Reconstruction	\$ 267,000.00
2020	OMN	TW D	405	AAC	74,127	36	AC Reconstruction	\$ 927,000.00
2020	OMN	TW E	505	AAC	56,507	36	AC Reconstruction	\$ 707,000.00
2020	OMN	TW F	605	AC	41,694	45	AC Restoration	\$ 455,000.00
2020	OMN	TW F	650	AC	6,273	35	AC Reconstruction	\$ 79,000.00
2020	OMN	TW T-HANG	2004	PCC	17,255	7	PCC Reconstruction	\$ 346,000.00
2022	OMN	AP T HANG	4410	AC	54,829	64	AC Restoration	\$ 521,000.00
2027	OMN	RW 17-35	6210	AAC	10,188	64	AC Restoration	\$ 97,000.00
2028	OMN	RW 17-35	6205	AAC	329,912	64	AC Restoration	\$ 3,135,000.00

<sup>\*</sup>All planning cost values have been rounded to the nearest thousand-dollar.

Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029



Airport Pavement Evaluation Report 2019

Ormond Beach Municipal Airport (OMN)





#### Summary of Ormond Beach Municipal Airport

Ormond Beach Municipal Airport was inspected in January of 2019 – the overall weighted PCI value was 73, a condition rating of Satisfactory. The results of the maintenance, repair, and major rehabilitation analysis identified \$1,115,890 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$10,878,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$7,125,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.









## **Chapter 1 – Introduction**

#### 1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

#### 1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating publicuse airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.





#### 1.3 Organization

#### 1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

#### 1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

#### 1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

#### 1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys," evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.





A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- Research and evaluation of existing record documentation was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- An update to the existing Network Definition Map was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- A functional pavement evaluation with PCI Survey inspections was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- Condition Analysis was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- Maintenance, Repair, and Rehabilitation Planning was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." Planninglevel unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.





#### 1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

#### 1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.





During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER<sup>™</sup> (currently known as PAVER<sup>™</sup>) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER<sup>™</sup> system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (http://www.dot.state.fl.us/aviation/pavement.shtm) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys." The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.





#### 1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management **Program (PMP)**"). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications."

#### 1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC150/5380-7B "Airport Pavement Management Program (PMP)" an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

#### 1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- An objective and repeatable system for evaluating pavement condition.
- Procedures for predicting future pavement condition.
- Procedures for modeling both past and future pavement performance conditions.
- Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

#### 1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data



- F. Pavement Performance Modeling for the Prediction/Forecast of PCI
- G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements' past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and costeffective manner. Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, which is based on the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.




Figure 1.7.2 (a) Typical Pavement Condition Life Cycle

\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).


Figure 1.7.2 (b) General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall





composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

Figure 1.7.2 (b) General Pavement Treatments by Condition Range



Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in Figures 1.7.2 (a) and 1.7.2 (b), however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7.2 (c) and 1.7.2 (d), depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.



Figures 1.7.2 (c) Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabiliation	40-64	50	S	Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figures 1.7.2 (d) Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabiliation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.





#### 1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."
- FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program."
- FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements."
- FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation."
- Department of the Air Force, Air Force Civil Engineer Center "Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements."
- Unified Facilities Criteria (UFC) 3-260-16FA 16 "Airfield Pavement Condition Survey Procedures Pavements."
- Unified Facilities Criteria (UFC) 3-260-03 "Airfield Pavement Evaluation."
- Pavement Management for Airports, Roads, and Parking Lots 2<sup>nd</sup> Edition, M.Y. Shahin.



# **Chapter 2**





### **Chapter 2 – Methodology**

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

#### 2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER<sup>TM</sup> (formerly MicroPAVER<sup>TM</sup>); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER<sup>™</sup> can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER<sup>TM</sup> database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER<sup>TM</sup> version 6.5 to a version 7.0.

#### 2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.





A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's Aerial Photo Look Up System (APLUS). This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

#### 2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

#### **Pavement Network**

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement branches, which are typically comprised of one or many pavement sections. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

#### **Pavement Branch**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

#### **Pavement Section**

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related





infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a "parent" pavement network.

#### **Pavement Sample Unit**

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (±8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet (±2,000 ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	"Tallahassee International Airport – Airfield Pavements"
Branch Name	Commonly defined asset name as established by Airport and by use	"Runway 18-36"
Branch ID	Codified shorthand name for commonly defined asset established for database identification	"RW 18-36" RW, Branch Use, "Runway" 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following:  Pavement Composition Construction Work History Aircraft Traffic Condition Records	"6105"
Sample Unit	A numeric identification of an area of pavement (5,000±2,000 SF of AC or 20±8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	"300"





#### 2.3 Airfield Pavement Structure

#### 2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

#### Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

#### Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

#### Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

#### Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.





#### Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

#### Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

#### Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

#### Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 8 inches in thickness.

#### Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 8 inches in thickness.

#### Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.





#### 2.4 Airfield Pavement Work History

#### 2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

- 1. Location and Limits of Work.
- Types and Severity of Distresses Repaired.
- 3. Type of Work.
- 4. Cost of Work.
- 5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

#### 2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular 150/5320-6F Airport Pavement Design and **Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

#### 2.6 Airfield Pavement Condition Index (PCI) Survey

#### 2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)," the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method

**Airport Pavement Evaluation Report** 

2019

Ormond Beach Municipal Airport (OMN)





can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.





#### 2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2 (a) Pavement Distress Types - Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age





Table 2.6.2 (b) Pavement Distresses Possible Causes - Flexible Asphalt Concrete-Surfaced Airfields

	Classification by Possible Causes									
Load	Load Climate / Durability		Others							
<ul> <li>Alligator Cracking</li> <li>Corrugation</li> <li>Depression</li> <li>Patching of Load-based distress</li> <li>Polished Aggregate</li> <li>Rutting</li> <li>Slippage Cracking</li> </ul>	<ul> <li>Bleeding</li> <li>Block Cracking</li> <li>Joint Reflection Cracking</li> <li>L/T Cracking</li> <li>Patching of climate / durability-caused distresses</li> <li>Shoving from PCC</li> <li>Raveling</li> <li>Weathering</li> <li>Swelling</li> </ul>	<ul> <li>Alligator Cracking</li> <li>Depression</li> <li>Patching of moisture / drainage caused distress</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	Oil Spillage Jet Blast Erosion Polished Aggregate							

Table 2.6.2 (c) Pavement Distresses Possible Effects - Flexible Asphalt Concrete-Surfaced Air fields

Classification by Possible Effects									
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements						
<ul> <li>Corrugation</li> <li>Depression</li> <li>Rutting</li> <li>Shoving of asphalt pavement</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	<ul> <li>Bleeding</li> <li>Depression</li> <li>Polished Aggregate</li> <li>Rutting</li> </ul>	Block Cracking     Joint Reflection     Cracking     L/T Cracking     Slippage     Cracking	All Distresses						





Table 2.6.2 (d) Pavement Distresses - Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms				
Blowup	Climate / ASR				
Corner Break	Load Repetition / Curling Stresses				
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses				
Durability Cracking	Freeze-Thaw Cycling				
Joint Seal Damage	Material Deterioration / Construction Quality / Age				
Small Patch	Pavement Repair				
Large Patch/Utility Cut	Utility / Pavement Repair				
Popout	Freeze-Thaw Cycling / ASR / Material Quality				
Pumping	Load Repetition / Poor Joint Sealant				
Scaling	Construction Quality / Freeze-Thaw Cycling				
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer				
Shattered Slab	Overloading				
Shrinkage Cracking	Construction Quality / Climate				
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars				
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars				
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction				





Table 2.6.2 (e) Pavement Distresses Possible Causes - Rigid Portland Cement Concrete-Surfaced Airfields

	Classification by Possible Causes									
Load	Climate / Durability	Moisture / Drainage	Others							
<ul> <li>Corner Break</li> <li>Shattered Slab</li> <li>L/T/D Cracking</li> <li>Pumping</li> <li>Patching of Load-associated distress</li> <li>Spalling</li> </ul>	<ul> <li>Blowup</li> <li>"D" Cracking</li> <li>Joint Seal Damage</li> <li>Popouts</li> <li>Scaling</li> <li>Patch of Climate/Durability-associated distress</li> <li>Shrinkage Cracking</li> <li>Spalling</li> <li>L/T/D Cracking</li> </ul>	<ul> <li>Corner Break</li> <li>Shattered Slab</li> <li>Pumping</li> <li>Patching of Moisture/Drainage- associated distress</li> </ul>	Settlement     / Faulting							

Table 2.6.2 (f) Pavement Distresses Possible Effects - Rigid Portland Cement Concrete-Surfaced Airfields

	Classification by Possible Effects									
Roughness Skid / Hydroplaning Potential		FOD Potential	Rate of Deterioration and Maintenance Requirements							
<ul> <li>Blowup</li> <li>Corner Break</li> <li>L/T/D Cracking</li> <li>Shattered Slab</li> <li>Settlement / Faulting</li> <li>Spalling</li> </ul>	<ul> <li>Settlement / Faulting</li> <li>Spalling</li> </ul>	Corner Break L/T/D Cracking "D" Cracking Joint Seal Damage Shattered Slab Popouts Scaling	All distresses							





# 2.6.3 PCI Survey Inspection Procedures

# Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following Tables 2.6.3 (a) and (b) define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total	Sample Units to Inspect						
Sample Units in Section	Runways	Taxiways, Aprons, and Others					
1 - 4	1	1					
5 - 10	2	1					
11 - 15	3	2					
16 - 30	5	3					
31 - 40	7	4					
41 - 50	8	5					
51 or more	20% but ≤20	10% but ≤10					

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in	Sample Units to Inspect						
Section	Runways	Taxiways, Aprons, and Others					
1 - 3	1	1					
4 - 6	2	1					
7 - 10	3	2					
11 - 15	4	2					
16 - 20	5	3					
21 - 30	7	3					
31 - 40	8	4					
41 - 50	10	5					
51 or more	20% but ≤20	10% but ≤10					





# 2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

#### Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering." Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling," the PCI deduction is not as high as the former "Weathering and Raveling." Therefore, areas identified only as "(57) Weathering" based on current ASTM standards, which were previously identified as "(52) Weathering and Raveling," may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

# Rigid Portland Cement Concrete Pavement Distress Updates

The previous methodology defined "(70) Scaling" as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included Alkali-Silica Reaction, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as "(76) Alkali-Silica Reaction / ASR." As a result, the previous "(70) Scaling" numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded "(70) Scaling," and currently do not exhibit "(76) Alkali-Silica Reactivity / ASR" may potentially see an increase in PCI. Additionally, "(73) Shrinkage Cracks" has been redefined as "(73) Shrinkage Cracking". Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage can be caused by both atmospheric conditions and construction. Plastic shrinkage caused by atmospheric conditions develops when there is rapid loss of water in the surface of recently placed pavement. High winds or low humidity are contributing factors to evaporation. These shrinkage cracks can appear as a series of parallel cracks, usually 1 to 3 feet apart and do not extend very deep into the pavement's surface. Plastic shrinkage caused by construction can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.





## Table 2.6.4 Summary of Updates to ASTM D5340-12

Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/ APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Crazing - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Crazing - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Crazing - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Crazing' may now be identified as 'Shrinkage Cracking'



# **Chapter 3**





# Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

#### 3.1 Airfield Pavement Network Information

## 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following Table 3.1.1 summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. Figure 3.1.1 (a) and Figure 3.1.1 (b) provides an inset view of the 2019 Airfield Pavement Network Definition Exhibit and the 2019 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.

Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction


Year	General Work Description
	<b>AP RU, TW A, TW D, TW E</b> - New Construction: 4" P-401, 6" P-211, 12" P-152
2013	TW B - Reconstruction
	TW C - Reconstruction: 2" P-401, 6" P-211, 12" P-152
	<b>AP RU</b> - New Construction: 2" P-401, 6" P-219, 6" P-154, 12" P-152
2016	TW A - Mill and Overlay: 2" Mill, P-401 Overlay
	TW G, TW G2, TW G3 - New Construction: 4" P-401, 6" P-219, 6" P-154, 12" P-152
2019	RW 17-35, RW 8-26, TW A - Reconstruction

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.





Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit




The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.





Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit



The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.


# 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, Figure 3.1.2 summarizes the average age of the pavement sections at the time of the PCI survey inspection. Age is determined to be the number of years since any major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.





Figure 3.1.2 Average Age of Pavements at Inspection



The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.






# 3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. Figure 3.1.3 summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







# 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following Figures 3.1.4 (a) and (b) summarize the applicable pavement types observed at this specific airport's airfield.





Figure 3.1.4 (a) Pavement Surface Type by Area (SF)





Figure 3.1.4 (b) Pavement Surface Type by Area (%)



# 3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.





## Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
OMN	CENTER APRON	AP CENTER	APRON	4204	285	22	5,932	AC	7/31/2008
OMN	CENTER APRON	AP CENTER	APRON	4205	600	218	141,436	AAC	1/1/1992
OMN	EAST APRON - HANGAR AREA	AP E	APRON	4305	342	150	52,638	AC	1/1/1984
OMN	RUN-UP APRON	AP RU	APRON	5110	300	100	28,383	AC	1/1/2013
OMN	RUN-UP APRON	AP RU	APRON	5115	300	100	28,289	AC	1/1/2013
OMN	RUN-UP APRON	AP RU	APRON	5120	385	105	40,182	AC	1/1/2016
OMN	RUN-UP APRON	AP RU	APRON	5125	385	105	40,187	AC	1/1/2016
OMN	AP T HANG	AP T HANG	APRON	4410	2,000	25	54,829	AC	1/1/2005
OMN	WEST APRON	AP W	APRON	4102	670	34	22,255	AC	1/1/1992
OMN	WEST APRON	AP W	APRON	4105	835	180	164,592	AC	1/1/1992
OMN	RUNWAY 17-35	RW 17-35	RUNWAY	6205	3,300	100	329,912	AAC	1/1/2008
OMN	RUNWAY 17-35	RW 17-35	RUNWAY	6210	100	100	10,188	AAC	1/1/2008
OMN	RUNWAY 17-35	RW 17-35	RUNWAY	6215	300	100	30,400	AC	1/1/2019
OMN	RUNWAY 8-26	RW 8-26	RUNWAY	6105	4,000	75	292,950	AC	1/1/2019
OMN	TAXIWAY A	TW A	TAXIWAY	100	4,250	35	149,004	AC	1/1/2013
OMN	TAXIWAY A	TW A	TAXIWAY	102	51	48	2,434	AC	1/1/2019
OMN	TAXIWAY A	TW A	TAXIWAY	105	130	35	4,550	AAC	1/1/2016
OMN	TAXIWAY A	TW A	TAXIWAY	110	194	40	8,089	AC	1/1/2013
OMN	TAXIWAY A	TW A	TAXIWAY	112	51	60	3,083	AC	1/1/2019
OMN	TAXIWAY A	TW A	TAXIWAY	115	193	40	8,054	AC	1/1/2013
OMN	TAXIWAY A	TW A	TAXIWAY	117	52	60	3,118	AC	1/1/2019
OMN	TAXIWAY B	TW B	TAXIWAY	205	495	40	21,323	AAC	1/1/1977
OMN	TAXIWAY B	TW B	TAXIWAY	210	143	120	9,023	AC	1/1/2013
OMN	TAXIWAY C	TW C	TAXIWAY	305	1,160	50	35,470	AC	1/1/2013
OMN	TAXIWAY D	TW D	TAXIWAY	405	2,160	45	74,127	AAC	1/1/1984

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

Ormond Beach Municipal Airport (OMN)





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
OMN	TAXIWAY D	TW D	TAXIWAY	410	200	40	14,057	AC	1/1/2013
OMN	TAXIWAY E	TW E	TAXIWAY	505	2,060	35	56,507	AAC	1/1/1990
OMN	TAXIWAY E	TW E	TAXIWAY	510	800	35	29,167	AC	1/1/2013
OMN	TAXIWAY F	TW F	TAXIWAY	605	1,040	40	41,694	AC	1/1/1984
OMN	TAXIWAY F	TW F	TAXIWAY	650	130	40	6,273	AC	1/1/1984
OMN	TAXIWAY G	TW G	TAXIWAY	700	4,190	35	144,093	AC	1/1/2016
OMN	TAXIWAY G2	TW G2	TAXIWAY	705	230	35	9,003	AC	1/1/2016
OMN	TAXIWAY G3	TW G3	TAXIWAY	710	230	35	8,999	AC	1/1/2016
OMN	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	2004	640	22	17,255	PCC	1/1/1992





## PAGE INTENTIONALLY LEFT BLANK



# **Chapter 4**





# **Chapter 4 – Airfield Pavement** Condition

The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

# 4.1 Airfield Pavement Condition Index (Latest Inspection)

# 4.1.1 Network-Level Analysis

The following Figure 4.1.1 summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.




Figure 4.1.1 Latest Condition - Overall Network

#### 4.1.2 Branch-Level Analysis

The following Figures 4.1.2 (a) through (c) summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.





Figure 4.1.2 (a) Latest Condition - Runway Pavements



Figure 4.1.2 (b) Latest Condition - Taxiway Pavements









Figure 4.1.2 (c) Latest Condition - Apron Pavements



# 4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement. Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.

2019






Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
OMN	AP CENTER	CENTER APRON	APRON	4204	5,932	AC	30	Very Poor	100%	0%	0%	1	2
OMN	AP CENTER	CENTER APRON	APRON	4205	141,436	AAC	33	Very Poor	81%	18%	1%	4	26
OMN	AP E	EAST APRON - HANGAR AREA	APRON	4305	52,638	AC	28	Very Poor	56%	37%	7%	3	11
OMN	AP RU	RUN-UP APRON	APRON	5110	28,383	AC	94	Good	100%	0%	0%	1	5
OMN	AP RU	RUN-UP APRON	APRON	5115	28,289	AC	91	Good	100%	0%	0%	1	6
OMN	AP RU	RUN-UP APRON	APRON	5120	40,182	AC	94	Good	100%	0%	0%	1	8
OMN	AP RU	RUN-UP APRON	APRON	5125	40,187	AC	94	Good	100%	0%	0%	1	8
OMN	AP T HANG	AP T HANG	APRON	4410	54,829	AC	68	Fair	59%	29%	12%	2	11
OMN	AP W	WEST APRON	APRON	4102	22,255	AC	28	Very Poor	72%	0%	28%	1	7
OMN	AP W	WEST APRON	APRON	4105	164,592	AC	61	Fair	96%	0%	4%	4	39
OMN	RW 17-35	RUNWAY 17-35	RUNWAY	6205	329,912	AAC	73	Satisfactory	86%	0%	14%	14	66
OMN	RW 17-35	RUNWAY 17-35	RUNWAY	6210	10,188	AAC	72	Satisfactory	77%	0%	23%	1	2
OMN	RW 17-35	RUNWAY 17-35	RUNWAY	6215	30,400	AC	100	Good	0%	0%	0%	0	0
OMN	RW 8-26	RUNWAY 8-26	RUNWAY	6105	292,950	AC	100	Good	0%	0%	0%	0	0
OMN	TW A	TAXIWAY A	TAXIWAY	100	149,004	AC	93	Good	100%	0%	0%	5	41
OMN	TW A	TAXIWAY A	TAXIWAY	102	2,434	AC	100	Good	0%	0%	0%	0	0
OMN	TW A	TAXIWAY A	TAXIWAY	105	4,550	AAC	94	Good	100%	0%	0%	1	1
OMN	TW A	TAXIWAY A	TAXIWAY	110	8,089	AC	90	Good	100%	0%	0%	1	2
OMN	TW A	TAXIWAY A	TAXIWAY	112	3,083	AC	100	Good	0%	0%	0%	0	0
OMN	TW A	TAXIWAY A	TAXIWAY	115	8,054	AC	94	Good	100%	0%	0%	1	2
OMN	TW A	TAXIWAY A	TAXIWAY	117	3,118	AC	100	Good	0%	0%	0%	0	0
OMN	TW B	TAXIWAY B	TAXIWAY	205	21,323	AAC	37	Very Poor	86%	0%	14%	2	5
OMN	TW B	TAXIWAY B	TAXIWAY	210	9,023	AC	94	Good	100%	0%	0%	1	2
OMN	TW C	TAXIWAY C	TAXIWAY	305	35,470	AC	94	Good	100%	0%	0%	2	9
OMN	TW D	TAXIWAY D	TAXIWAY	405	74,127	AAC	38	Very Poor	79%	0%	21%	5	16
OMN	TW D	TAXIWAY D	TAXIWAY	410	14,057	AC	94	Good	100%	0%	0%	1	3
OMN	TW E	TAXIWAY E	TAXIWAY	505	56,507	AAC	38	Very Poor	97%	0%	3%	3	16
OMN	TW E	TAXIWAY E	TAXIWAY	510	29,167	AC	94	Good	100%	0%	0%	1	8
OMN	TW F	TAXIWAY F	TAXIWAY	605	41,694	AC	46	Poor	97%	0%	3%	2	10
OMN	TW F	TAXIWAY F	TAXIWAY	650	6,273	AC	36	Very Poor	87%	0%	13%	1	1
OMN	TW G	TAXIWAY G	TAXIWAY	700	144,093	AC	91	Good	59%	0%	41%	4	39
OMN	TW G2	TAXIWAY G2	TAXIWAY	705	9,003	AC	94	Good	100%	0%	0%	1	2
OMN	TW G3	TAXIWAY G3	TAXIWAY	710	8,999	AC	94	Good	100%	0%	0%	1	2
OMN	TW T-HANG	TAXIWAY TO T-HANGARS	TAXIWAY	2004	17,255	PCC	9	Failed	10%	86%	4%	1	3





Figure 4.1.3 is an inset view of the 2019 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits.** 

Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit







# 4.2 Summary of Pavement Condition Evaluation Results

#### 4.2.1 Network-Level Observations

The field PCI Survey performed at Ormond Beach Municipal Airport (OMN) was completed in January 2019. The resulting overall area-weighted average PCI value was 73 representing a condition rating of Satisfactory. Ormond Beach Municipal Airport is serviced by two runways; Runway 8-26 is 75-ft wide and 4,005-ft long and Runway 17-35 is 100-ft wide and 3,704-ft long. Runway 8-26, portions of the connecting taxiways, and a portion of runway 17-35 were not inspected due to recent construction. The PCI for these areas has been set to 100, a condition rating of Good.

Based on the FAA 5010 Report as of 09/12/2019 the Airport has reported 127,000 operations for 12 months ending 02/08/2018.

#### 4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and samplelevel may be referenced for all pavements assessed as part of this System Update. The branchlevel observations discussed are limited to select branches based on use and condition.

#### Runway 17-35

Runway 17-35 consists of 3 sections constructed of AC and AAC. The last construction years range from 2008 to 2019. The area-weighted average PCI for Runway 17-35 is 75 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Runway 17-35 consist of Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

#### Taxiway B

Taxiway B consists of 2 sections constructed of AC and AAC. The last construction years range from 1977 to 2013. The area-weighted average PCI for Taxiway B is 51 representing a Poor condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway B consist of Block Cracking, Depression, Raveling, Swelling, and Weathering.

#### Taxiway D

Taxiway D consists of 2 sections constructed of AC and AAC. The last construction years range from 1984 to 2013. The area-weighted average PCI for Taxiway D is 46 representing a Poor condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway D consist of Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Shoving, Swelling, and Weathering.





# Taxiwav E

Taxiway E consists of 2 sections constructed of AC and AAC. The last construction years range from 1990 to 2013. The area-weighted average PCI for Taxiway E is 57 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway E consist of Block Cracking, Patching, Raveling, Swelling, and Weathering.

#### Taxiway F

Taxiway F consists of 2 sections constructed of AC. The last construction year for Taxiway F was 1984. The area-weighted average PCI for Taxiway F is 44 representing a Poor condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway F consist of Block Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, and Swelling.

#### Center Apron

The Center Apron consists of 2 sections constructed of AC and AAC. The last construction years range from 1992 to 2008. The area-weighted average PCI for the Center Apron is 32 representing a Very Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on the Center Apron consist of Alligator Cracking, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, and Raveling.

#### West Apron

The West Apron consists of 2 sections constructed of AC. The last construction year for West Apron was 1992. The area-weighted average PCI for the West Apron is 57 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on the West Apron consist of Block Cracking, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Swelling, and Weathering.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Area-Weighted Average PCI	Condition Rating
Runway	86	Good
Taxiway	73	Satisfactory
Apron	57	Fair





## 4.3 Forecasted Pavement Conditions

#### 4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to developed forecasted PCI values based on historic trends and statistical models.

#### 4.3.2 Branch-Level Pavement Condition Forecast

The following Figures 4.3.2 (a) through (c) depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2020 through January 2029.




Figure 4.3.2 (a) Forecasted Runway Pavement Performance



Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance







## 4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.





#### Table 4.3.3 Forecasted PCI 2020-2029

Network	Donal ID	Section	Last PCI	Forecasted PCI									
ID	Branch ID	ID	Last PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
OMN	AP CENTER	4204	30	29	29	29	28	28	28	27	27	27	26
OMN	AP CENTER	4205	33	30	28	26	24	22	20	17	15	13	11
OMN	AP E	4305	28	27	27	26	26	26	25	25	25	24	24
OMN	AP RU	5110	94	91	89	87	85	82	80	78	76	74	73
OMN	AP RU	5115	91	88	86	84	82	80	78	76	74	72	70
OMN	AP RU	5120	94	91	89	87	85	82	80	78	76	74	73
OMN	AP RU	5125	94	91	89	87	85	82	80	78	76	74	73
OMN	AP T HANG	4410	68	66	65	64	63	62	61	60	59	58	57
OMN	AP W	4102	28	27	27	26	26	26	25	25	25	24	24
OMN	AP W	4105	61	60	59	58	57	56	56	55	54	54	53
OMN	RW 17-35	6205	73	71	70	69	68	67	66	65	65	64	63
OMN	RW 17-35	6210	72	70	69	68	67	66	66	65	64	63	62
OMN	RW 17-35	6215	100	98	96	93	91	89	87	85	82	81	79
OMN	RW 8-26	6105	100	98	96	93	91	89	87	85	82	81	79
OMN	TW A	100	93	91	89	88	86	85	83	82	80	79	77
OMN	TW A	102	100	98	96	94	93	91	89	88	86	85	83
OMN	TW A	105	94	91	89	87	85	84	82	80	79	77	76
OMN	TW A	110	90	88	86	85	83	82	80	79	77	76	75
OMN	TW A	112	100	98	96	94	93	91	89	88	86	85	83
OMN	TW A	115	94	92	90	89	87	86	84	83	81	80	78
OMN	TW A	117	100	98	96	94	93	91	89	88	86	85	83
OMN	TW B	205	37	35	33	31	29	27	25	23	21	19	17
OMN	TW B	210	94	92	90	89	87	86	84	83	81	80	78
OMN	TW C	305	94	92	90	89	87	86	84	83	81	80	78
OMN	TW D	405	38	36	34	32	30	28	26	24	22	20	18

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

Ormond Beach Municipal Airport (OMN)





Network	Branch ID	Section	Lest DCI	Forecasted PCI									
ID	ID Branch ID	ID	Last PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
OMN	TW D	410	94	92	90	89	87	86	84	83	81	80	78
OMN	TW E	505	38	36	34	32	30	28	26	24	22	20	18
OMN	TW E	510	94	92	90	89	87	86	84	83	81	80	78
OMN	TW F	605	46	45	44	43	43	42	41	41	40	40	39
OMN	TW F	650	36	35	35	35	34	34	34	34	34	33	33
OMN	TW G	700	91	89	87	86	84	83	81	80	78	77	76
OMN	TW G2	705	94	92	90	89	87	86	84	83	81	80	78
OMN	TW G3	710	94	92	90	89	87	86	84	83	81	80	78
OMN	TW T-HANG	2004	9	7	6	5	4	3	2	1	0	0	0





#### 4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA AC 150/5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements to determine structural and/or functional conditions at the time of project.









# Chapter 5 - Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- Localized Maintenance and Repair includes patching and crack sealing.
- > Global Treatments include surface seals and rejuvenators for flexible pavements.
- > Major Rehabilitation includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

# 5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distressed pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety ("stopgap") measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

# Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

# **Localized Preventive Maintenance and Repair**

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.





# 5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in Table 5.2 (a) and Table 5.2 (b), for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and the FDOT Airfield Pavement Distress Repair Manual. Additionally, the Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2 (a) Localized Maintenance and Repair - Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft





Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L&TCR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2 (b) Localized Maintenance and Repair - Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt

# Ormond Beach Municipal Airport (OMN)





Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT – SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt





Table 5.2 (c) Localized Repair Planning-Level Unit Costs - Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$9.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$4.00	SqFt

Table 5.2 (d) Localized M&R Planning-Level Unit Costs - Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$150.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

<sup>\*</sup>PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.





## 5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in 5.2 Localized M&R Policy. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. Appendix B provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to nearterm Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3 (a)** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost	
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	1,730	SqFt	\$	15,560.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	235	SqFt	\$	930.00
FDOT - SURFACE SEAL	PREVENTIVE	141,710	SqFt	\$	77,950.00
FDOT - SLAB REPLACEMENT - PCC	STOPGAP	10,560	SqFt	\$	316,800.00
FDOT - CRACK SEALING - AC	STOPGAP	72,080	Ft	\$	216,240.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	17,290	SqFt	\$	155,580.00
FDOT - SURFACE SEAL	STOPGAP	404,880	SqFt	\$	222,690.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	26,395	SqFt	\$	105,580.00
FDOT - JOINT SEAL - PCC	STOPGAP	685	Ft	\$	1,880.00
FDOT - CRACK SEALING - PCC	STOPGAP	630	Ft	\$	2,680.00





The following Table 5.3 (b) provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved "End Condition" of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
OMN	AP CENTER	4204	5,932	30	59	\$ 6,180.00
OMN	AP CENTER	4205	141,436	33	65	\$ 272,320.00
OMN	AP E	4305	52,638	28	61	\$ 103,950.00
OMN	AP RU	5110	28,383	94	94	\$ -
OMN	AP RU	5115	28,289	91	91	\$ -
OMN	AP RU	5120	40,182	94	94	\$ -
OMN	AP RU	5125	40,187	94	94	\$ -
OMN	AP T HANG	4410	54,829	68	92	\$ 25,370.00
OMN	AP W	4102	22,255	28	55	\$ 27,270.00
OMN	AP W	4105	164,592	61	71	\$ 50,330.00
OMN	RW 17-35	6205	329,912	73	87	\$ 58,740.00
OMN	RW 17-35	6210	10,188	72	83	\$ 1,090.00
OMN	RW 17-35	6215	30,400	100	100	\$ -
OMN	RW 8-26	6105	292,950	100	100	\$ -
OMN	TW A	100	149,004	93	93	\$ -
OMN	TW A	102	2,434	100	100	\$ -
OMN	TW A	105	4,550	94	94	\$ -
OMN	TW A	110	8,089	90	94	\$ 90.00
OMN	TW A	112	3,083	100	100	\$ -
OMN	TW A	115	8,054	94	94	\$ -
OMN	TW A	117	3,118	100	100	\$ -
OMN	TW B	205	21,323	37	59	\$ 31,160.00
OMN	TW B	210	9,023	94	94	\$ -
OMN	TW C	305	35,470	94	94	\$ -
OMN	TW D	405	74,127	38	63	\$ 87,010.00
OMN	TW D	410	14,057	94	94	\$ -
OMN	TW E	505	56,507	38	61	\$ 82,410.00
OMN	TW E	510	29,167	94	94	\$ -
OMN	TW F	605	41,694	46	63	\$ 34,100.00
OMN	TW F	650	6,273	36	55	\$ 5,600.00
OMN	TW G	700	144,093	91	92	\$ 9,180.00
OMN	TW G2	705	9,003	94	94	\$ -





Network ID	Branch ID Section ID Area (SF)		Start Condition	End Condition	Cost		
OMN	TW G3	710	8,999	94	94	\$ -	
OMN	TW T-HANG	2004	17,255	9	58	\$ 321,360.00	

The following **Table 5.3 (c)** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (c) Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 94,440.00
Stopgap	\$ 1,021,450.00
Planning-Level Localized M&R Needs =	\$ 1,115,890.00



# **Chapter 6**






# Chapter 6 – Major Rehabilitation **Planning**

#### 6.1 Major Rehabilitation


Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. Figures 6.1 (a) and 6.1 (b) depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI





Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI







#### 6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The Critical PCI concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

- 1. Develop a pavement performance model and refine a prediction model for the pavements considered.
- 2. Select a localized maintenance and repair policy to be used in developing a work
- Apply the selected localized policy to the pavement sections for a range of PCI.
- 4. Compute the unit cost per area for each PCI range.
- 5. Plot the cost versus the PCI.
- 6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

#### 6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended *Minimum Service-Level PCI* for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. Table 6.1.2 summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration			
Runway	75	Aircraft Fleet Mix Changes Primary Runway			
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations			
Aprons / Run-Ups / Ramps	65	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)			





## 6.2 Major Rehabilitation Policy

#### 6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA AC 150/5320-6F "Airport Pavement Design and Evaluation." It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following Tables 6.2.1 (a) and (b) provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average RL Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation - Flexible Asphalt Concrete

Rehabilitation Type	Reliever (RL) Airport				
AC Restoration  Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.	75% Mill and Overlay P-101 AC Milling (3") P-603 Bituminous Tack P-401 (HMA) (3")				
PCI = 41 to 65	25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (4") Excludes any paved shoulder features.				
AC Reconstruction	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8")				
Full-depth asphalt pavement section reconstruction.	P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (4") Excludes any paved shoulder features.				
PCI = 40 or less					





Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation - Rigid Portland Cement Concrete

Rehabilitation Type	Reliever (RL) Airport
PCC Restoration  Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.  PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (15")  *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction  Full-depth rigid pavement section reconstruction.  PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (6") P-501 Rigid PCC (14")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

The recommendations identified in the Major Rehabilitation Needs consider the FAA AC 150/5370-10H Standard Specifications for Construction of Airports when determining the appropriate materials and methods implemented for construction projects, such as pavement rehabilitation, on airports. It should be noted that the AC 150/5370-10H Standard Specifications for Construction of Airports was updated in December of 2018. Design-level determination of project specific specifications based on the AC should be developed by the Airport when performing applicable construction projects.





#### 6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 Reliever (RL) Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	e Asphalt Cost Per SF	Rigid Portland Cement Concrete Cost per SF		
Restoration	41 to 65	\$ 9.50	\$	13.50	
Reconstruction	0 to 40	\$ 12.50	\$	20.00	

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

### 6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a payement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

#### 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level





investigation, and budgetary constraints. The following Table 6.3.1 summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.

Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	OMN	AP CENTER	4204	AC	5,932	29	AC Reconstruction	\$ 75,000.00
2020	OMN	AP CENTER	4205	AAC	141,436	30	AC Reconstruction	\$ 1,768,000.00
2020	OMN	AP E	4305	AC	52,638	27	AC Reconstruction	\$ 658,000.00
2020	OMN	AP W	4102	AC	22,255	27	AC Reconstruction	\$ 279,000.00
2020	OMN	AP W	4105	AC	164,592	60	AC Restoration	\$ 1,564,000.00
2020	OMN	TW B	205	AAC	21,323	35	AC Reconstruction	\$ 267,000.00
2020	OMN	TW D	405	AAC	74,127	36	AC Reconstruction	\$ 927,000.00
2020	OMN	TW E	505	AAC	56,507	36	AC Reconstruction	\$ 707,000.00
2020	OMN	TW F	605	AC	41,694	45	AC Restoration	\$ 455,000.00
2020	OMN	TW F	650	AC	6,273	35	AC Reconstruction	\$ 79,000.00
2020	OMN	TW T-HANG	2004	PCC	17,255	7	PCC Reconstruction	\$ 346,000.00
2022	OMN	AP T HANG	4410	AC	54,829	64	AC Restoration	\$ 521,000.00
2027	OMN	RW 17-35	6210	AAC	10,188	64	AC Restoration	\$ 97,000.00
2028	OMN	RW 17-35	6205	AAC	329,912	64	AC Restoration	\$ 3,135,000.00

<sup>\*</sup>All values have been rounded to the nearest thousand-dollar.

The following Figure 6.3.1 (a) summarizes the section-level major rehabilitation needs for a 10year period between 2020 and 2029. Figure 6.3.1 (b) provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in Appendix C Technical Exhibits. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.





Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year





Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit





# **Chapter 7**





# **Chapter 7 – Conclusion**

#### 7.1 Recommendations

#### 7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and reinspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

#### 7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2020-2029. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

## 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- Develop a detailed preventive maintenance program for the airport.
- Further refine and implement the identified 10-year major rehabilitation needs.
- Maintain detailed records on pavement maintenance, construction, and inspection.
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).





## 7.2 Supporting Documents

#### 001 - Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in Appendix A **Pavement Analysis Tables.** 

#### 002 - Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in is located in Appendix C Technical Exhibits. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

#### 003 - Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in Appendix C Technical Exhibits. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in Appendix E Inspection Distress Details) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

#### 004 - Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation.

#### Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in Appendix D Inspection Photograph Documentation. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.

**Statewide Airfield Pavement Management Program** 

**Airport Pavement Evaluation Report** 

2019

Ormond Beach Municipal Airport (OMN)






#### 7.3 Conclusion

The FDOT SAPMP Update Phase 2 2018-2019 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars 150/5380-7B "Airport Pavement Management Program (PMP)" and 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."



# Appendix A

Airfield Pavement Analysis Tables







#### Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
OMN	CENTER APRON	AP CENTER	APRON	4204	285	22	5,932	AC	7/31/2008
OMN	CENTER APRON	AP CENTER	APRON	4205	600	218	141,436	AAC	1/1/1992
OMN	EAST APRON - HANGAR AREA	AP E	APRON	4305	342	150	52,638	AC	1/1/1984
OMN	RUN-UP APRON	AP RU	APRON	5110	300	100	28,383	AC	1/1/2013
OMN	RUN-UP APRON	AP RU	APRON	5115	300	100	28,289	AC	1/1/2013
OMN	RUN-UP APRON	AP RU	APRON	5120	385	105	40,182	AC	1/1/2016
OMN	RUN-UP APRON	AP RU	APRON	5125	385	105	40,187	AC	1/1/2016
OMN	AP T HANG	AP T HANG	APRON	4410	2,000	25	54,829	AC	1/1/2005
OMN	WEST APRON	AP W	APRON	4102	670	34	22,255	AC	1/1/1992
OMN	WEST APRON	AP W	APRON	4105	835	180	164,592	AC	1/1/1992
OMN	RUNWAY 17-35	RW 17-35	RUNWAY	6205	3,300	100	329,912	AAC	1/1/2008
OMN	RUNWAY 17-35	RW 17-35	RUNWAY	6210	100	100	10,188	AAC	1/1/2008
OMN	RUNWAY 17-35	RW 17-35	RUNWAY	6215	300	100	30,400	AC	1/1/2019
OMN	RUNWAY 8-26	RW 8-26	RUNWAY	6105	4,000	75	292,950	AC	1/1/2019
OMN	TAXIWAY A	TW A	TAXIWAY	100	4,250	35	149,004	AC	1/1/2013
OMN	TAXIWAY A	TW A	TAXIWAY	102	51	48	2,434	AC	1/1/2019
OMN	TAXIWAY A	TW A	TAXIWAY	105	130	35	4,550	AAC	1/1/2016
OMN	TAXIWAY A	TW A	TAXIWAY	110	194	40	8,089	AC	1/1/2013
OMN	TAXIWAY A	TW A	TAXIWAY	112	51	60	3,083	AC	1/1/2019
OMN	TAXIWAY A	TW A	TAXIWAY	115	193	40	8,054	AC	1/1/2013
OMN	TAXIWAY A	TW A	TAXIWAY	117	52	60	3,118	AC	1/1/2019
OMN	TAXIWAY B	TW B	TAXIWAY	205	495	40	21,323	AAC	1/1/1977
OMN	TAXIWAY B	TW B	TAXIWAY	210	143	120	9,023	AC	1/1/2013
OMN	TAXIWAY C	TW C	TAXIWAY	305	1,160	50	35,470	AC	1/1/2013
OMN	TAXIWAY D	TW D	TAXIWAY	405	2,160	45	74,127	AAC	1/1/1984
OMN	TAXIWAY D	TW D	TAXIWAY	410	200	40	14,057	AC	1/1/2013
OMN	TAXIWAY E	TW E	TAXIWAY	505	2,060	35	56,507	AAC	1/1/1990
OMN	TAXIWAY E	TW E	TAXIWAY	510	800	35	29,167	AC	1/1/2013
OMN	TAXIWAY F	TW F	TAXIWAY	605	1,040	40	41,694	AC	1/1/1984
OMN	TAXIWAY F	TW F	TAXIWAY	650	130	40	6,273	AC	1/1/1984
OMN	TAXIWAY G	TW G	TAXIWAY	700	4,190	35	144,093	AC	1/1/2016
OMN	TAXIWAY G2	TW G2	TAXIWAY	705	230	35	9,003	AC	1/1/2016
OMN	TAXIWAY G3	TW G3	TAXIWAY	710	230	35	8,999	AC	1/1/2016
OMN	TAXIWAY TO T-HANGARS	TW T-HANG	TAXIWAY	2004	640	22	17,255	PCC	1/1/1992





Table A-2 Pavement Condition Index Summary (Last Inspection) - Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
OMN	RUNWAY 8-26	RUNWAY	6105	292,950	100	Good
OMN	RUNWAY 17-35	RUNWAY	6205	329,912	73	Satisfactory
OMN	RUNWAY 17-35	RUNWAY	6210	10,188	72	Satisfactory
OMN	RUNWAY 17-35	RUNWAY	6215	30,400	100	Good
OMN	TAXIWAY A	TAXIWAY	100	149,004	93	Good
OMN	TAXIWAY A	TAXIWAY	102	2,434	100	Good
OMN	TAXIWAY A	TAXIWAY	105	4,550	94	Good
OMN	TAXIWAY A	TAXIWAY	110	8,089	90	Good
OMN	TAXIWAY A	TAXIWAY	112	3,083	100	Good
OMN	TAXIWAY A	TAXIWAY	115	8,054	94	Good
OMN	TAXIWAY A	TAXIWAY	117	3,118	100	Good
OMN	TAXIWAY B	TAXIWAY	205	21,323	37	Very Poor
OMN	TAXIWAY B	TAXIWAY	210	9,023	94	Good
OMN	TAXIWAY C	TAXIWAY	305	35,470	94	Good
OMN	TAXIWAY D	TAXIWAY	405	74,127	38	Very Poor
OMN	TAXIWAY D	TAXIWAY	410	14,057	94	Good
OMN	TAXIWAY E	TAXIWAY	505	56,507	38	Very Poor
OMN	TAXIWAY E	TAXIWAY	510	29,167	94	Good
OMN	TAXIWAY F	TAXIWAY	605	41,694	46	Poor
OMN	TAXIWAY F	TAXIWAY	650	6,273	36	Very Poor
OMN	TAXIWAY G	TAXIWAY	700	144,093	91	Good
OMN	TAXIWAY G2	TAXIWAY	705	9,003	94	Good
OMN	TAXIWAY G3	TAXIWAY	710	8,999	94	Good
OMN	TAXIWAY TO T-HANGARS	TAXIWAY	2004	17,255	9	Failed
OMN	WEST APRON	APRON	4102	22,255	28	Very Poor
OMN	WEST APRON	APRON	4105	164,592	61	Fair
OMN	CENTER APRON	APRON	4204	5,932	30	Very Poor
OMN	CENTER APRON	APRON	4205	141,436	33	Very Poor
OMN	EAST APRON - HANGAR AREA	APRON	4305	52,638	28	Very Poor
OMN	AP T HANG	APRON	4410	54,829	68	Fair
OMN	RUN-UP APRON	APRON	5110	28,383	94	Good
OMN	RUN-UP APRON	APRON	5115	28,289	91	Good
OMN	RUN-UP APRON	APRON	5120	40,182	94	Good
OMN	RUN-UP APRON	APRON	5125	40,187	94	Good





#### Table A-3 Forecasted PCI 2020-2029

Network		Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
OMN	AP CENTER	4204	30	29	29	29	28	28	28	27	27	27	26
OMN	AP CENTER	4205	33	30	28	26	24	22	20	17	15	13	11
OMN	AP E	4305	28	27	27	26	26	26	25	25	25	24	24
OMN	AP RU	5110	94	91	89	87	85	82	80	78	76	74	73
OMN	AP RU	5115	91	88	86	84	82	80	78	76	74	72	70
OMN	AP RU	5120	94	91	89	87	85	82	80	78	76	74	73
OMN	AP RU	5125	94	91	89	87	85	82	80	78	76	74	73
OMN	AP T HANG	4410	68	66	65	64	63	62	61	60	59	58	57
OMN	AP W	4102	28	27	27	26	26	26	25	25	25	24	24
OMN	AP W	4105	61	60	59	58	57	56	56	55	54	54	53
OMN	RW 17-35	6205	73	71	70	69	68	67	66	65	65	64	63
OMN	RW 17-35	6210	72	70	69	68	67	66	66	65	64	63	62
OMN	RW 17-35	6215	100	98	96	93	91	89	87	85	82	81	79
OMN	RW 8-26	6105	100	98	96	93	91	89	87	85	82	81	79
OMN	TW A	100	93	91	89	88	86	85	83	82	80	79	77
OMN	TW A	102	100	98	96	94	93	91	89	88	86	85	83
OMN	TW A	105	94	91	89	87	85	84	82	80	79	77	76
OMN	TW A	110	90	88	86	85	83	82	80	79	77	76	75
OMN	TW A	112	100	98	96	94	93	91	89	88	86	85	83
OMN	TW A	115	94	92	90	89	87	86	84	83	81	80	78
OMN	TW A	117	100	98	96	94	93	91	89	88	86	85	83
OMN	TW B	205	37	35	33	31	29	27	25	23	21	19	17
OMN	TW B	210	94	92	90	89	87	86	84	83	81	80	78
OMN	TW C	305	94	92	90	89	87	86	84	83	81	80	78
OMN	TW D	405	38	36	34	32	30	28	26	24	22	20	18
OMN	TW D	410	94	92	90	89	87	86	84	83	81	80	78
OMN	TW E	505	38	36	34	32	30	28	26	24	22	20	18
OMN	TW E	510	94	92	90	89	87	86	84	83	81	80	78
OMN	TW F	605	46	45	44	43	43	42	41	41	40	40	39
OMN	TW F	650	36	35	35	35	34	34	34	34	34	33	33
OMN	TW G	700	91	89	87	86	84	83	81	80	78	77	76
OMN	TW G2	705	94	92	90	89	87	86	84	83	81	80	78
OMN	TW G3	710	94	92	90	89	87	86	84	83	81	80	78
OMN	TW T-HANG	2004	9	7	6	5	4	3	2	1	0	0	0

#### **Work History Report**

Page 1 of 7

Pavement Database: FDOT

Network: ORMOND BEACH	Branch: AP CE	NTER CENT	ER APRON	Section:	4204 Surface:AC
<b>L.C.D.</b> 7/31/2008 <b>Use:</b> APRON	Rank: T L	ength: 285	.00 (Ft) <b>Wi</b>	dth: 22.0	0 (Ft) <b>True Area:</b> 5932.000001 (SqFt
Work Date   Work   Work	Description	Cost	Thickness (in)	Major M&R	Comments
7/31/2008 NU-IN New Constru	ction - Initial	0.00	0.00	<b>V</b>	

Network: ORMOND BEACH **Branch:** AP CENTER CENTER APRON Section: 4205 Surface: AAC L.C.D. 1/1/1992 Use: APRON Rank: T Length: 600.00 (Ft) Width: 218.00 (Ft) True Area: 141436.0000 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R 1/1/1992 IMPORT OVERLAY 0.00 0.00 1992: AC OVERLAY ~ ED 1/1/1979 IMPORT BUILT 0.00 1.00 ~ 1979: 1" TYPE S1 AC OVERLAY PLACED ON EXISTING AC ON BA

Network: ORMOND BEACH Branch: AP E EAST APRON - H Section: 4305 Surface: AC Rank: P Width: 150.00 (Ft) True Area: 52638.00001 (SqFt L.C.D. 1/1/1984 Use: APRON Length: 342.00 (Ft) Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R 1/1/1984 IMPORT BUILT ESTIMATE 1984 AC PAVEMENT. 0.00 0.00 ED SOIL: SP.

Network: ORMOND BEACH Branch: AP RU RUN-UP APRON Section: 5110 Surface: AC **L.C.D.** 1/1/2013 Use: APRON Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 28383.00000 (SqFt Work Thickness Major Work Date Comments Work Description Cost M&R Code (in) 1/1/2013 NU-IN 4" P401, 6" P211, 12" P152 New Construction - Initial 0.00 0.00 ~

Network: ORMOND BEACH Branch: AP RU RUN-UP APRON Section: 5115 Surface: AC **L.C.D.** 1/1/2013 Use: APRON Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 28289.00000 (SqFt Work **Thickness** Major **Work Date Work Description** Cost Comments Code (in) M&R 1/1/2013 NU-IN New Construction - Initial 0.00 0.00 4" P401, 6" P211, 12" P152 

Network: ORMOND BEACH Branch: AP RU **RUN-UP APRON** Section: 5120 Surface: AC L.C.D. 1/1/2016 Use: APRON Rank: P Length: 385.00 (Ft) Width: 105.00 (Ft) True Area: 40182.00001 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2016 New Construction - AC NC-AC ightharpoons

Network: ORMOND BEACH **RUN-UP APRON** Branch: AP RU Section: 5125 Surface: AC **L.C.D.** 1/1/2016 Use: APRON Rank: P Length: 385.00 (Ft) Width: 105.00 (Ft) True Area: 40187.00001 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments M&R Code (in) 1/1/2016 NC-AC New Construction - AC ~

ED

#### **Work History Report**

Page 2 of 7

Pavement Database: FDOT

Network: ORMOND BEACH Branch: AP T HANG AP T HANG Section: 4410 Surface: AC **L.C.D.** 1/1/2005 Use: APRON Rank: P **Length:** 2,000.00 (Ft) Width: 25.00 (Ft) True Area: 54829.00001 (SqFt Work Thickness Major **Work Date** Cost **Work Description Comments** Code (in) M&R 1/1/2005 NC-AC New Construction - AC 0.00 

Network: ORMOND BEACH Branch: AP W WEST APRON Section: 4102 Surface: AC L.C.D. 1/1/1992 Use: APRON Rank: P Length: 670.00 (Ft) Width: 34.00 (Ft) True Area: 22255.00000 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/1992 IMPORT BUILT 0.00 2.00 1992: 2" P-401 ON 6" RECLAIMED ~ PAVEMENT BASE. SOIL: SP.

Network: ORMOND BEACH Branch: AP W WEST APRON Section: 4105 Surface: AC **L.C.D.** 1/1/1992 Use: APRON Rank: T Length: 835.00 (Ft) Width: 180.00 (Ft) True Area: 164592.0000 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments M&R Code (in) 1/1/1992 IMPORT BUILT 1992: SEAL ON 2" P-401 ON 6" 0.002.00 ~ RECLAIMED PAVEMENT BASE, S

Network: ORMOND BEACH Branch: RW 17-35 **RUNWAY 17-35** Section: 6205 Surface: AAC **L.C.D.** 1/1/2008 Use: RUNWAY Rank: P Length: 3,300.00 (Ft) Width: 100.00 (Ft) True Area: 329912.0001 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	ML-OL	Mill and Overlay	0.00	0.00	<b>V</b>	
1/1/1983	IMPORT ED	OVERLAY	0.00	2.50		1983: 2.5" P-401 ON 1" - 3.5" LEVELING COURSE
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<b>V</b>	1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS

Network: ORMOND BEACH Branch: RW 17-35 **RUNWAY 17-35** Section: 6210 Surface: AAC **L.C.D.** 1/1/2008 Use: RUNWAY 100.00 (Ft) Width: 100.00 (Ft) True Area: 10188.00000 (SqFt Rank: P Length:

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	ML-OL	Mill and Overlay	0.00	0.00	<b>V</b>	
1/1/1973	IMPORT ED	OVERLAY	0.00	0.00		ASSUME: 1973 AC OVERLAY
1/1/1943	IMPORT ED	BUILT	0.00	1.00		1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS

**RUNWAY 17-35** Network: ORMOND BEACH Branch: RW 17-35 Section: 6215 Surface: AC 300.00 (Ft) Width: 100.00 (Ft) True Area: 30400.00000 (SqFt **L.C.D.** 1/1/2019 Use: RUNWAY Rank: P Length:

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	
1/1/2008	ML-OL	Mill and Overlay	0.00	0.00		
1/1/1973	IMPORT	OVERLAY	0.00	0.00		ASSUME: 1973 AC OVERLAY
	ED					
1/1/1943	IMPORT	BUILT	0.00	1.00		1943: 1" DOUBLE BITUMINOUS
	ED					SURFACE ON 6" LIME ROCK BAS

PAVER 7.0 TM Pavement Management System

1/1/2013

NU-IN

Page 3 of 7

4" P401, 6" P211, 12" P152

		Pavement Database:	FDOT						
Network:	Network: ORMOND BEACH Branch: RW 8-26 RUNWAY 8-26 Section: 6105 Surface: AC								
L.C.D. 1/1/2019 Use: RUNWAY Rank: S Length: 4,000.00 (Ft) Width: 75.00 (Ft) True Area: 292950.0000 (SqFt									
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/2019 1/1/1977	CR-AC IMPORT ED	Complete Reconstruction - AC OVERLAY	0.00 0.00	0.00	<b>Y</b>	1977: VARIABLE THICKNESS TYPE 1 ASPHALT CONCRETE			
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<b>V</b>	1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS			
Network:	Network: ORMOND BEACH Branch: TW A TAXIWAY A Section: 100 Surface: AC								
<b>L.C.D.</b> 1/1/20	013 Us	se: TAXIWAY Rank: P L	ength: 4,250	.00 (Ft) Wie	dth: 35.0	0 (Ft) <b>True Area:</b> 149004.0000 (SqFt			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<b>V</b>	4" P401, 6" P211, 12" P152			
	ı								
Network:	ORMONE	BEACH Branch: TW A	TAXIV	WAY A	Section:	102 Surface:AC			
<b>L.C.D.</b> 1/1/20	019 U:	se: TAXIWAY Rank: P L	ength: 51	.00 (Ft) Wie	dth: 48.0	0 (Ft) <b>True Area:</b> 2434.000000 (SqFt			
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/2019	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>~</b>				
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00		4" P401, 6" P211, 12" P152			
17172015			0.00	0.00	<u> </u>				
Network: L.C.D. 1/1/20	016 Us	D BEACH Branch: TW A	TAXIV	WAY A .00 (Ft) Wi	Section:	105 <b>Surface:</b> AAC 0 (Ft) <b>True Area:</b> 4550.000001 (SqFt			
Network:		D BEACH Branch: TW A	TAXIV	WAY A	Section:				
Network: L.C.D. 1/1/20	016 U: Work Code	D BEACH Branch: TW A se: TAXIWAY Rank: P L	TAXIV	WAY A .00 (Ft) Wi	Section: dth: 35.0 Major M&R	0 (Ft) True Area: 4550.000001 (SqFt			
Network: L.C.D. 1/1/20 Work Date	016 U: Work Code	D BEACH Branch: TW A se: TAXIWAY Rank: P L Work Description	TAXIVength: 130	WAY A .00 (Ft) Wi Thickness (in)	Section: dth: 35.0 Major M&R	0 (Ft) True Area: 4550.000001 (SqFt  Comments			
Network: L.C.D. 1/1/20 Work Date 1/1/2016	Work Code ML-OV NU-IN	BEACH Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial	TAXIV ength: 130  Cost  0.00 0.00	WAY A .00 (Ft) Wid Thickness (in) 0.00	Section: dth: 35.0 Major M&R	0 (Ft) <b>True Area:</b> 4550.000001 (SqFt <b>Comments</b> 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152			
Network: L.C.D. 1/1/20 Work Date 1/1/2016 1/1/2013	Work Code ML-OV NU-IN	BEACH Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial  BEACH Branch: TW A	TAXIV ength: 130 Cost 0.00 0.00 TAXIV	WAY A .00 (Ft) Wi Thickness (in) 0.00 0.00	Section: dth: 35.0 Major M&R  Section:	0 (Ft) <b>True Area:</b> 4550.000001 (SqFt <b>Comments</b> 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152			
Network: L.C.D. 1/1/2 Work Date 1/1/2016 1/1/2013	Work Code ML-OV NU-IN	BEACH Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial  BEACH Branch: TW A	TAXIV ength: 130 Cost 0.00 0.00 TAXIV	WAY A .00 (Ft) Wid Thickness (in) 0.00 0.00	Section: dth: 35.0 Major M&R  Section:	0 (Ft) True Area: 4550.000001 (SqFt  Comments  2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC			
Network: L.C.D. 1/1/20 Work Date 1/1/2016 1/1/2013  Network: L.C.D. 1/1/20	Work Code ML-OV NU-IN  ORMONE 013 Us Work	BEACH Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial  BEACH Branch: TW A se: TAXIWAY Rank: P L	TAXIV ength: 130  Cost  0.00 0.00  TAXIV ength: 194	WAY A .00 (Ft) Wi Thickness (in) 0.00 0.00  WAY A .00 (Ft) Wi Thickness	Section: dth: 35.0 Major M&R  Section: dth: 40.0 Major	0 (Ft) True Area: 4550.000001 (SqFt  Comments  2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC 0 (Ft) True Area: 8089.000002 (SqFt			
Network: L.C.D. 1/1/20 Work Date 1/1/2016 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013	Work Code ML-OV NU-IN  ORMONI 013 Us Work Code NU-IN	BEACH Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial  BEACH Branch: TW A se: TAXIWAY Rank: P L Work Description New Construction - Initial	TAXIVength: 130  Cost  0.00 0.00  TAXIVength: 194  Cost  0.00	WAY A .00 (Ft) Wide Thickness (in) 0.00 0.00 WAY A .00 (Ft) Wide Thickness (in) 0.00	Section: dth: 35.0 Major M&R  Section: dth: 40.0 Major M&R	Comments 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface: AC 0 (Ft) True Area: 8089.000002 (SqFt  Comments 4" P401, 6" P211, 12" P152			
Network: L.C.D. 1/1/20 Work Date 1/1/2016 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network:	Work Code ML-OV NU-IN  ORMONE  Work Code  NU-IN	BEACH Branch: TW A se: TAXIWAY Rank: P L  Work Description  MILL and OVERLAY New Construction - Initial  BEACH Branch: TW A se: TAXIWAY Rank: P L  Work Description  New Construction - Initial	TAXIV ength: 130  Cost  0.00 0.00  TAXIV ength: 194  Cost  0.00  TAXIV	WAY A .00 (Ft) Wid Thickness (in)  0.00 0.00  WAY A .00 (Ft) Wid Thickness (in)  0.00	Section: dth: 35.0 Major M&R  Section: dth: 40.0 Major M&R  Section:	Comments 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC 0 (Ft) True Area: 8089.000002 (SqFt Comments 4" P401, 6" P211, 12" P152			
Network: L.C.D. 1/1/20 Work Date 1/1/2016 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20	Work Code ML-OV NU-IN  ORMONE  Work Code  NU-IN	D BEACH Branch: TW A se: TAXIWAY Rank: P L  Work Description  MILL and OVERLAY New Construction - Initial  D BEACH Branch: TW A se: TAXIWAY Rank: P L  Work Description  New Construction - Initial  D BEACH Branch: TW A se: TAXIWAY Rank: P L	TAXIV ength: 130  Cost  0.00 0.00  TAXIV ength: 194  Cost  0.00  TAXIV ength: 51	WAY A .00 (Ft) Wid Thickness (in)  0.00 0.00  WAY A .00 (Ft) Wid Thickness (in)  0.00	Section: dth: 35.0  Major M&R  Section: dth: 40.0  Major M&R  Section: dth: 60.0  Major	Comments 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC 0 (Ft) True Area: 8089.000002 (SqFt  Comments 4" P401, 6" P211, 12" P152  112 Surface:AC 0 (Ft) True Area: 3083.000000 (SqFt			
Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20 Work Date	Work Code ML-OV NU-IN  ORMONE 013 Us Work Code NU-IN  ORMONE 019 Us Work Code	BEACH Branch: TW A  se: TAXIWAY Rank: P L  Work Description  MILL and OVERLAY New Construction - Initial  BEACH Branch: TW A  se: TAXIWAY Rank: P L  Work Description  New Construction - Initial  BEACH Branch: TW A  se: TAXIWAY Rank: P L  Work Description	TAXIVength: 130  Cost  0.00 0.00  TAXIVength: 194  Cost  0.00  TAXIVength: 51  Cost	WAY A .00 (Ft) Wide Thickness (in)  0.00 0.00  WAY A .00 (Ft) Wide Thickness (in)  0.00  WAY A .00 (Ft) Wide Thickness (in)	Section: dth: 35.0 Major M&R  Section: dth: 40.0 Major M&R  Section: dth: 60.0 Major M&R	Comments 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC 0 (Ft) True Area: 8089.000002 (SqFt Comments 4" P401, 6" P211, 12" P152			
Network: L.C.D. 1/1/20 Work Date 1/1/2016 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20	Work Code ML-OV NU-IN  ORMONE 013 Us Work Code NU-IN  ORMONE 019 Us Work	D BEACH Branch: TW A se: TAXIWAY Rank: P L  Work Description  MILL and OVERLAY New Construction - Initial  D BEACH Branch: TW A se: TAXIWAY Rank: P L  Work Description  New Construction - Initial  D BEACH Branch: TW A se: TAXIWAY Rank: P L	TAXIV ength: 130  Cost  0.00 0.00  TAXIV ength: 194  Cost  0.00  TAXIV ength: 51	WAY A .00 (Ft) Wie Thickness (in)  0.00 0.00  WAY A .00 (Ft) Wie Thickness (in)  0.00  WAY A .00 (Ft) Wie Thickness	Section: dth: 35.0  Major M&R  Section: dth: 40.0  Major M&R  Section: dth: 60.0  Major	Comments 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC 0 (Ft) True Area: 8089.000002 (SqFt  Comments 4" P401, 6" P211, 12" P152  112 Surface:AC 0 (Ft) True Area: 3083.000000 (SqFt			
Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2019	Work Code ML-OV NU-IN  ORMONE 013 Us Work Code NU-IN  ORMONE 019 Us Work Code CR-AC	BEACH Branch: TW A  se: TAXIWAY Rank: P L  Work Description  MILL and OVERLAY New Construction - Initial  DEACH Branch: TW A  se: TAXIWAY Rank: P L  Work Description  New Construction - Initial  DEACH Branch: TW A  se: TAXIWAY Rank: P L  Work Description  Complete Reconstruction - AC	TAXIVength: 130  Cost  0.00 0.00  TAXIVength: 194  Cost  0.00  TAXIVength: 51  Cost  0.00	WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A .00 (Ft) Wi Thickness (in)  0.00	Section: dth: 35.0 Major M&R  Section: dth: 40.0 Major M&R  Section: dth: 60.0 Major M&R	Comments 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC 0 (Ft) True Area: 8089.000002 (SqFt  Comments 4" P401, 6" P211, 12" P152  112 Surface:AC 0 (Ft) True Area: 3083.000000 (SqFt  Comments			
Network: L.C.D. 1/1/20 Work Date 1/1/2016 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2019 1/1/2013  Network:	Work Code ML-OV NU-IN  ORMONE 013 U: Work Code NU-IN  Work Code CR-AC NU-IN	BEACH Branch: TW A  See: TAXIWAY Rank: P L  Work Description  MILL and OVERLAY New Construction - Initial  DEACH Branch: TW A  See: TAXIWAY Rank: P L  Work Description  New Construction - Initial  DEACH Branch: TW A  See: TAXIWAY Rank: P L  Work Description  Complete Reconstruction - AC  New Construction - Initial	TAXIVength: 130  Cost  0.00 0.00  TAXIVength: 194  Cost  0.00  TAXIVength: 51  Cost  0.00  TAXIV	WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A	Section: dth: 35.0 Major M&R  Section: dth: 40.0 Major M&R  Section: dth: 60.0 Major M&R  Section:	Comments 2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface:AC 0 (Ft) True Area: 8089.000002 (SqFt  Comments 4" P401, 6" P211, 12" P152  112 Surface:AC 0 (Ft) True Area: 3083.000000 (SqFt  Comments 4" P401, 6" P211, 12" P152  115 Surface:AC			
Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013  Network: L.C.D. 1/1/20 Work Date 1/1/2013	Work Code ML-OV NU-IN  ORMONE 013 U: Work Code NU-IN  Work Code CR-AC NU-IN	BEACH Branch: TW A  See: TAXIWAY Rank: P L  Work Description  MILL and OVERLAY New Construction - Initial  DEACH Branch: TW A  See: TAXIWAY Rank: P L  Work Description  New Construction - Initial  DEACH Branch: TW A  See: TAXIWAY Rank: P L  Work Description  Complete Reconstruction - AC  New Construction - Initial	TAXIVength: 130  Cost  0.00 0.00  TAXIVength: 194  Cost  0.00  TAXIVength: 51  Cost  0.00  TAXIV	WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A .00 (Ft) Wi Thickness (in)  0.00  WAY A	Section: dth: 35.0 Major M&R  Section: dth: 40.0 Major M&R  Section: dth: 60.0 Major M&R  Section:	Comments  2" MILL, P-401 OVERLAY 4" P401, 6" P211, 12" P152  110 Surface: AC 0 (Ft) True Area: 8089.000002 (SqFt  Comments  4" P401, 6" P211, 12" P152  112 Surface: AC 0 (Ft) True Area: 3083.000000 (SqFt  Comments  4" P401, 6" P211, 12" P152			

Pavement Management System PAVER 7.0 TM

0.00

0.00

**Y** 

New Construction - Initial

#### **Work History Report**

Page 4 of 7

Pavement Database: FDOT

Network	ORMONE	) BEACH	Branch: TW A	TAXIV	WAY A	Section:	117 Surface:AC
<b>L.C.D.</b> 1/1/	2019 Us	se: TAXIWAY	Rank: P L	ength: 52	.00 (Ft) Wi	<b>dth:</b> 60.0	0 (Ft) <b>True Area:</b> 3118.000000 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comments
					(111)	MICH	
1/1/2019	CR-AC	Complete Reco	nstruction - AC	0.00	( )	V	

Network: ORMOND BEACH Branch: TW B TAXIWAY B Section: 205 Surface: AAC Use: TAXIWAY Rank: P Length: 495.00 (Ft) Width: 40.00 (Ft) True Area: 21323.00000 (SqFt **L.C.D.** 1/1/1977

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1977	IMPORT ED	OVERLAY	0.00	0.00	الثا	1977: TYPE 1 ASPHALT CONCRETE (NO THICNESS INFO).
1/1/1943	IMPORT ED	BUILT	0.00	1.00		1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS

Network: ORMOND BEACH Branch: TW B TAXIWAY B Section: 210 Surface:AC

**L.C.D.** 1/1/2013 Use: TAXIWAY Rank: P Length: 143.00 (Ft) Width: 120.00 (Ft) True Area: 9023.000002 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	
1/1/1977	IMPORT ED	OVERLAY	0.00	0.00		1977: AC OVERLAY (NO THICKNESS INFO)
1/1/1943	IMPORT ED	BUILT	0.00	1.00		1943: 1" AC SURFACE ON 6" LIME ROCK BASE

Network: ORMOND BEACH TAXIWAY C Branch: TW C Section: 305 Surface:AC L.C.D. 1/1/2013 Use: TAXIWAY Rank: P **Length:** 1,160.00 (Ft) **Width:** 50.00 (Ft) **True Area:** 35470.00001 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	2" P401, 6" P211, 12" P152
1/2/1990	OL-AS	Overlay - AC Structural	0.00	0.00		
1/1/1990	IMPORT ED	BUILT	0.00	2.00		1990: 2" P-401 OVERLAY PLACED ON EXISTING 6" AC ON 6" CRUSH

Network: ORMOND BEACH Branch: TW D TAXIWAY D Section: 405 Surface: AAC **L.C.D.** 1/1/1984 Use: TAXIWAY Rank: P Length: 2,160.00 (Ft) Width: 45.00 (Ft) True Area: 74127.00002 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	IMPORT ED	OVERLAY	0.00	3.00	<u> </u>	1984: 3" RECYCLED HOT MIX AC. SOIL SP.
1/1/1943	IMPORT ED	BUILT	0.00	1.00	انت	1943: 1" BITUMINOUS SURFACE ON 6" LIME ROCK BASE

Network: ORMOND BEACH Branch: TW D TAXIWAY D Section: 410 Surface:AC

L.C.D. 1/1/2013 Use: TAXIWAY Rank: P Length: 200.00 (Ft) Width: 40.00 (Ft) True Area: 14057.00000 (SqFt

Н	L.C.D. 1/1/2	015 08	c. IAMIWAI Kaik, I	ciigtii. 200	.00 (11) 111	utii. +0.0	o (11) True Area: 14037.00000 (5q11
Work Date Work Code			Work Description	Cost	Thickness (in)	Major M&R	Comments
	1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	>	4" P401, 6" P211, 12" P152

PAVER 7.0 TM Pavement Management System

10/4/2019
-----------

# **Work History Report**

Page 5 of 7

Pavement Database: FDOT

Favement Database: FDO1								
Network: ORMOND BEACH Branch: TW E TAXIWAY E Section: 505 Surface: AA								
<b>L.C.D.</b> 1/1/1	990 Us	se: TAXIWAY Rank: P L	ength: 2,060	.00 (Ft) Wi	dth: 35.0	0 (Ft) <b>True Area:</b> 56507.00001 (SqFt		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments		
1/1/1990	IMPORT ED	OVERLAY	0.00	2.00	<b>V</b>	1990: 2" P-401 OVERLAY. SOIL: SP.		
1/1/1943	IMPORT ED	BUILT	0.00	4.50		1943: 4.5" AC ON 5" TAN SHELL ON 6" DARK GREY SAND		
Network:	ORMOND	BEACH Branch: TW E	TAXIV	WAY E	Section:	510 Surface:AC		
<b>L.C.D.</b> 1/1/2	013 Us	se: TAXIWAY Rank: P	ength: 800	.00 (Ft) Wi	dth: 35.0	0 (Ft) <b>True Area:</b> 29167.00000 (SqFt		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments		
1/1/2013		New Construction - Initial	0.00	0.00		4" P401, 6" P211, 12" P152		
Network: L.C.D. 1/1/1			TAXIV ength: 1,040	WAY F	Section:	605 <b>Surface:</b> AC 0 (Ft) <b>True Area:</b> 41694.00001 (SqFt		
	Work		<u> </u>	Thickness	Major			
Work Date	Code IMPORT	Work Description	Cost	(in)	M&R	Comments  1984: 2" RECYCLED HOT MIX ON		
1/1/1984	ED	BUILI	0.00	2.00	<b>&gt;</b>	6" LIME ROCK BASE ON 2" WORK		
	0.00.100.100							
Network: L.C.D. 1/1/1				WAY F .00 (Ft) <b>Wi</b>	Section:	650 <b>Surface:</b> AC 0 (Ft) <b>True Area:</b> 6273.000001 (SqFt		
Work Date	Work	Work Description	Cost	Thickness	Major	Comments		
1/1/1984	Code IMPORT	•	0.00	(in) 2.00	M&R ✓	1984: 2" RECYCLED HOT MIX ON		
1/1/1/04	ED	BOILT	0.00	2.00		6" LIME ROCK BASE ON 2" WORK		
Network:	OPMOND	D BEACH Branch: TW G2	) TAVI	WAY G2	Section:	705 Surface:AC		
L.C.D. 1/1/2						0 (Ft) <b>True Area:</b> 9003.000002 (SqFt		
Work Date	Work	Work Description	Cost	Thickness	Major	Comments		
1/1/2016	Code NC-AC	New Construction - AC	Cost	(in)	M&R ✓	Comments		
					<u> </u>			
Network:	ORMOND	BEACH Branch: TW G3	3 TAXIV	WAY G3	Section:	710 Surface:AC		
<b>L.C.D.</b> 1/1/2		se: TAXIWAY Rank: P L	ength: 230			0 (Ft) <b>True Area:</b> 8999.000002 (SqFt		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments		
1/1/2016	NC-AC	New Construction - AC			<b>V</b>			
Network:	ORMOND	D BEACH Branch: TW G	ТАУП	WAY G	Section:	700 Surface:AC		
L.C.D. 1/1/2			1AA1 ength: 4,190			700 Surface: AC 0 (Ft) True Area: 144093.0000 (SqFt		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments		
	Coul			(111)	111011			

10/4/2019	Work History Report	Page 6 of 7
	Pavement Database: FDOT	

Network: ORMOND BEACH		BEACH I	Branch: TW T-F	HANG TAXIV	WAY TO T-	Section:	2004 Surface:PCC	
<b>L.C.D.</b> 1/1/1992 <b>Use:</b> TAXIWAY			se: TAXIWAY	Rank: P Lo	ength: 640	.00 (Ft) Wie	dth: 22.0	0 (Ft) <b>True Area:</b> 17255.00000 (SqFt
	Work Date	Work Code	Work De	scription	Cost	Thickness (in)	Major M&R	Comments
	1/1/1992	NU-IN	New Construction	New Construction - Initial		0.00	<b>V</b>	

# **Work History Report**

Page 7 of 7

## Pavement Database: FDOT

#### **Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	15	1,288,788.00	1.50	0.98
Complete Reconstruction - AC	7	376,478.00	0.00	0.00
Mill and Overlay	4	375,050.00	0.00	0.00
New Construction - AC	6	297,293.00	0.00	0.00
New Construction - Initial	13	301,415.00	0.00	0.00
OVERLAY	9	965,866.00	0.83	1.20
Overlay - AC Structural	1	35,470.00	0.00	0.00

# **Branch Condition Report**

Page 1 of 2

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP CENTE	2	885.00	120.00	147,368.00	APRON	31.50	1.50	32.88
AP E	1	342.00	150.00	52,638.00	APRON	28.00	0.00	28.00
AP RU	4	1,370.00	102.50	137,041.00	APRON	93.25	1.30	93.38
AP T HANG	1	2,000.00	25.00	54,829.00	APRON	68.00	0.00	68.00
AP W	2	1,505.00	107.00	186,847.00	APRON	44.50	16.50	57.07
RW 17-35	3	3,700.00	100.00	370,500.00	RUNWAY	81.67	12.97	75.19
RW 8-26	1	4,000.00	75.00	292,950.00	RUNWAY	100.00	0.00	100.00
TW A	7	4,921.00	45.43	178,332.00	TAXIWAY	95.86	3.80	93.27
TW B	2	638.00	80.00	30,346.00	TAXIWAY	65.50	28.50	53.95
TW C	1	1,160.00	50.00	35,470.00	TAXIWAY	94.00	0.00	94.00
TW D	2	2,360.00	42.50	88,184.00	TAXIWAY	66.00	28.00	46.93
TW E	2	2,860.00	35.00	85,674.00	TAXIWAY	66.00	28.00	57.06
TW F	2	1,170.00	40.00	47,967.00	TAXIWAY	41.00	5.00	44.69
TW G	1	4,190.00	35.00	144,093.00	TAXIWAY	91.00	0.00	91.00
TW G2	1	230.00	35.00	9,003.00	TAXIWAY	94.00	0.00	94.00
TW G3	1	230.00	35.00	8,999.00	TAXIWAY	94.00	0.00	94.00
TW T-HAN	1	640.00	22.00	17,255.00	TAXIWAY	9.00	0.00	9.00

10/4/2019	Branch Condition Report	Page 2 of 2
	Pavement Database: FDOT	

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	10	578,723.00	62.10	28.51	57.90
RUNWAY	4	663,450.00	86.25	13.75	86.14
TAXIWAY	20	645,323.00	76.50	28.66	73.97
ALL	34	1,887,496.00	73.41	28.41	73.32

Pavement Database: FDOT

#### NetworkId: OMN

1 uvement Dutu		Networkia. Omin								
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspec tion	PCI
AP CENTER	4204	7/31/2008	AC	APRON	Т	0	5,932.00	1/28/2019	11	30
AP CENTER	4205	1/1/1992	AAC	APRON	Т	0	141,436.00	1/28/2019	27	33
AP E	4305	1/1/1984	AC	APRON	Р	0	52,638.00	1/28/2019	35	28
AP RU	5110	1/1/2013	AC	APRON	Р	0	28,383.00	1/28/2019	6	94
AP RU	5115	1/1/2013	AC	APRON	Р	0	28,289.00	1/28/2019	6	91
AP RU	5120	1/1/2016	AC	APRON	Р	0	40,182.00	1/28/2019	3	94
AP RU	5125	1/1/2016	AC	APRON	Р	0	40,187.00	1/28/2019	3	94
AP T HANG	4410	1/1/2005	AC	APRON	Р	0	54,829.00	1/28/2019	14	68
AP W	4102	1/1/1992	AC	APRON	Р	0	22,255.00	1/28/2019	27	28
AP W	4105	1/1/1992	AC	APRON	Т	0	164,592.00	1/28/2019	27	61
RW 17-35	6205	1/1/2008	AAC	RUNWAY	Р	0	329,912.00	1/28/2019	11	73
RW 17-35	6210	1/1/2008	AAC	RUNWAY	Р	0	10,188.00	1/28/2019	11	72
RW 17-35	6215	1/1/2019	AC	RUNWAY	Р	0	30,400.00	1/1/2019	0	100
RW 8-26	6105	1/1/2019	AC	RUNWAY	S	0	292,950.00	1/1/2019	0	100
TW A	100	1/1/2013	AC	TAXIWAY	Р	0	149,004.00	1/28/2019	6	93
TW A	102	1/1/2019	AC	TAXIWAY	Р	0	2,434.00	1/1/2019	0	100
TW A	105	1/1/2016	AAC	TAXIWAY	Р	0	4,550.00	1/28/2019	3	94
TW A	110	1/1/2013	AC	TAXIWAY	Р	0	8,089.00	1/28/2019	6	90
TW A	112	1/1/2019	AC	TAXIWAY	Р	0	3,083.00	1/1/2019	0	100
TW A	115	1/1/2013	AC	TAXIWAY	Р	0	8,054.00	1/28/2019	6	94
TW A	117	1/1/2019	AC	TAXIWAY	Р	0	3,118.00	1/1/2019	0	100
TW B	205	1/1/1977	AAC	TAXIWAY	Р	0	21,323.00	1/28/2019	42	37
TW B	210	1/1/2013	AC	TAXIWAY	Р	0	9,023.00	1/28/2019	6	94
TW C	305	1/1/2013	AC	TAXIWAY	Р	0	35,470.00	1/28/2019	6	94
TW D	405	1/1/1984	AAC	TAXIWAY	Р	0	74,127.00	1/28/2019	35	38
TW D	410	1/1/2013	AC	TAXIWAY	Р	0	14,057.00	1/28/2019	6	94
TW E	505	1/1/1990	AAC	TAXIWAY	Р	0	56,507.00	1/28/2019	29	38
TW E	510	1/1/2013	AC	TAXIWAY	Р	0	29,167.00	1/28/2019	6	94
TW F	605	1/1/1984	AC	TAXIWAY	Р	0	41,694.00	1/28/2019	35	46
TW F	650	1/1/1984	AC	TAXIWAY	Р	0	6,273.00	1/28/2019	35	36
TW G	700	1/1/2016	AC	TAXIWAY	Р	0	144,093.00	1/28/2019	3	91
TW G2	705	1/1/2016	AC	TAXIWAY	Р	0	9,003.00	1/28/2019	3	94
TW G3	710	1/1/2016	AC	TAXIWAY	Р	0	8,999.00	1/28/2019	3	94
TW T-HANG	2004	1/1/1992	PCC	TAXIWAY	Р	0	17,255.00	1/28/2019	27	9


Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		331,985.00	5	100.00	0.00	100.00
03-05	3	247,014.00	6	93.50	1.12	92.25
06-10	6	309,536.00	9	93.11	1.45	93.14
11-15	12	400,861.00	4	60.75	17.85	71.65
26-30	27	402,045.00	5	33.80	16.77	43.86
31-35	35	174,732.00	4	37.00	6.40	36.82
41-50	42	21,323.00	1	37.00	0.00	37.00
ALL	13	1,887,496.00	34	73.41	28.41	73.32



# Appendix B

Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation



Ormond Beach Municipal Airport (OMN)





#### Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
OMN	AP CENTER	4204	48	L&TCR	Medium	808.92	Ft	13.6%	FDOT - CRACK SEALING - AC	809.1	Ft	\$ 3.00	\$ 2,430.00
OMN	AP CENTER	4204	52	RAVELING	Low	5527.59	SqFt	93.2%	FDOT - SURFACE SEAL	5527.3	SqFt	\$ 0.55	\$ 3,050.00
OMN	AP CENTER	4204	52	RAVELING	High	172.55	SqFt	2.9%	FDOT - PATCHING - AC PARTIAL DEPTH	172.2	SqFt	\$ 4.00	\$ 700.00
OMN	AP CENTER	4205	41	ALLIGATOR CR	Medium	3470.39	SqFt	2.5%	FDOT - PATCHING - AC FULL DEPTH	3711.4	SqFt	\$ 9.00	\$ 33,410.00
OMN	AP CENTER	4205	43	BLOCK CR	Medium	27176.94	SqFt	19.2%	FDOT - CRACK SEALING - AC	8283.5	Ft	\$ 3.00	\$ 24,860.00
OMN	AP CENTER	4205	45	DEPRESSION	Low	526.79	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	623.2	SqFt	\$ 9.00	\$ 5,610.00
OMN	AP CENTER	4205	48	L&TCR	Medium	3075.26	Ft	2.2%	FDOT - CRACK SEALING - AC	3075.1	Ft	\$ 3.00	\$ 9,230.00
OMN	AP CENTER	4205	50	PATCHING	Medium	2857.93	SqFt	2.0%	FDOT - PATCHING - AC FULL DEPTH	3077.4	SqFt	\$ 9.00	\$ 27,700.00
OMN	AP CENTER	4205	50	PATCHING	High	1646.34	SqFt	1.2%	FDOT - PATCHING - AC FULL DEPTH	1813.7	SqFt	\$ 9.00	\$ 16,330.00
OMN	AP CENTER	4205	52	RAVELING	Low	97822.53	SqFt	69.2%	FDOT - SURFACE SEAL	97822.4	SqFt	\$ 0.55	\$ 53,810.00
OMN	AP CENTER	4205	52	RAVELING	Medium	25188.2	SqFt	17.8%	FDOT - PATCHING - AC PARTIAL DEPTH	25188.6	SqFt	\$ 4.00	\$ 100,760.00
OMN	AP CENTER	4205	52	RAVELING	High	151.45	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	151.8	SqFt	\$ 4.00	\$ 610.00
OMN	AP E	4305	41	ALLIGATOR CR	Low	163.83	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	219.6	SqFt	\$ 9.00	\$ 1,980.00
OMN	AP E	4305	41	ALLIGATOR CR	Medium	3021.32	SqFt	5.7%	FDOT - PATCHING - AC FULL DEPTH	3246.4	SqFt	\$ 9.00	\$ 29,220.00
OMN	AP E	4305	41	ALLIGATOR CR	High	29.28	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	54.9	SqFt	\$ 9.00	\$ 500.00
OMN	AP E	4305	43	BLOCK CR	Medium	28531.57	SqFt	54.2%	FDOT - CRACK SEALING - AC	8696.5	Ft	\$ 3.00	\$ 26,090.00
OMN	AP E	4305	45	DEPRESSION	Low	573.29	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	673.8	SqFt	\$ 9.00	\$ 6,070.00
OMN	AP E	4305	45	DEPRESSION	Medium	152.09	SqFt	0.3%	FDOT - PATCHING - AC FULL DEPTH	205.6	SqFt	\$ 9.00	\$ 1,860.00
OMN	AP E	4305	50	PATCHING	Medium	1181.66	SqFt	2.2%	FDOT - PATCHING - AC FULL DEPTH	1324	SqFt	\$ 9.00	\$ 11,920.00
OMN	AP E	4305	52	RAVELING	Low	47823.73	SqFt	90.9%	FDOT - SURFACE SEAL	47824.1	SqFt	\$ 0.55	\$ 26,310.00
OMN	AP T HANG	4410	41	ALLIGATOR CR	High	55.11	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	89.3	SqFt	\$ 9.00	\$ 810.00
OMN	AP T HANG	4410	45	DEPRESSION	Low	523.99	SqFt	1.0%	FDOT - PATCHING - AC FULL DEPTH	620	SqFt	\$ 9.00	\$ 5,590.00
OMN	AP T HANG	4410	52	RAVELING	Low	32794.84	SqFt	59.8%	FDOT - SURFACE SEAL	32794.4	SqFt	\$ 0.55	\$ 18,040.00
OMN	AP T HANG	4410	52	RAVELING	Medium	231.64	SqFt	0.4%	FDOT - PATCHING - AC PARTIAL DEPTH	231.4	SqFt	\$ 4.00	\$ 930.00
OMN	AP W	4102	43	BLOCK CR	Medium	22255.03	SqFt	100.0%	FDOT - CRACK SEALING - AC	6783.5	Ft	\$ 3.00	\$ 20,350.00
OMN	AP W	4102	49	OIL SPILLAGE	N/A	231.42	SqFt	1.0%	FDOT - PATCHING - AC PARTIAL DEPTH	297.1	SqFt	\$ 4.00	\$ 1,190.00
OMN	AP W	4102	52	RAVELING	Low	9917.54	SqFt	44.6%	FDOT - SURFACE SEAL	9917.9	SqFt	\$ 0.55	\$ 5,460.00
OMN	AP W	4102	52	RAVELING	Medium	66.09	SqFt	0.3%	FDOT - PATCHING - AC PARTIAL DEPTH	65.7	SqFt	\$ 4.00	\$ 270.00
OMN	AP W	4105	48	L&TCR	Medium	5349.25	Ft	3.3%	FDOT - CRACK SEALING - AC	5349.1	Ft	\$ 3.00	\$ 16,050.00
OMN	AP W	4105	49	OIL SPILLAGE	N/A	365.76	SqFt	0.2%	FDOT - PATCHING - AC PARTIAL DEPTH	446.7	SqFt	\$ 4.00	\$ 1,790.00
OMN	AP W	4105	52	RAVELING	Low	58521.55	SqFt	35.6%	FDOT - SURFACE SEAL	58521.2	SqFt	\$ 0.55	\$ 32,190.00
OMN	AP W	4105	52	RAVELING	Medium	73.19	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	73.2	SqFt	\$ 4.00	\$ 300.00
OMN	RW 17-35	6205	52	RAVELING	Low	106787.79	SqFt	32.4%	FDOT - SURFACE SEAL	106787.7	SqFt	\$ 0.55	\$ 58,740.00
OMN	RW 17-35	6210	52	RAVELING	Low	1964.09	SqFt	19.3%	FDOT - SURFACE SEAL	1964.4	SqFt	\$ 0.55	\$ 1,090.00
OMN	TW A	110	52	RAVELING	Low	162.21	SqFt	2.0%	FDOT - SURFACE SEAL	162.5	SqFt	\$ 0.55	\$ 90.00
OMN	TW B	205	43	BLOCK CR	Medium	20714.61	SqFt	97.2%	FDOT - CRACK SEALING - AC	6314	Ft	\$ 3.00	\$ 18,950.00
OMN	TW B	205	45	DEPRESSION	Low	27.45	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	52.7	SqFt	\$ 9.00	\$ 480.00

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

Ormond Beach Municipal Airport (OMN)





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
OMN	TW B	205	52	RAVELING	Low	21322.98	SqFt	100.0%	FDOT - SURFACE SEAL	21323.3	SqFt	\$ 0.55	\$ 11,730.00
OMN	TW D	405	43	BLOCK CR	Medium	19641.98	SqFt	26.5%	FDOT - CRACK SEALING - AC	5986.9	Ft	\$ 3.00	\$ 17,970.00
OMN	TW D	405	45	DEPRESSION	Low	352.52	SqFt	0.5%	FDOT - PATCHING - AC FULL DEPTH	431.6	SqFt	\$ 9.00	\$ 3,890.00
OMN	TW D	405	48	L&TCR	Medium	5070.28	Ft	6.8%	FDOT - CRACK SEALING - AC	5070.2	Ft	\$ 3.00	\$ 15,220.00
OMN	TW D	405	50	PATCHING	Medium	836.79	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	956.9	SqFt	\$ 9.00	\$ 8,620.00
OMN	TW D	405	52	RAVELING	Low	61459.56	SqFt	82.9%	FDOT - SURFACE SEAL	61459.8	SqFt	\$ 0.55	\$ 33,810.00
OMN	TW D	405	54	SHOVING	High	82.34	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	122.7	SqFt	\$ 9.00	\$ 1,110.00
OMN	TW D	405	56	SWELLING	Medium	606.22	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	709.3	SqFt	\$ 9.00	\$ 6,390.00
OMN	TW E	505	43	BLOCK CR	Medium	56274.69	SqFt	99.6%	FDOT - CRACK SEALING - AC	17152.6	Ft	\$ 3.00	\$ 51,460.00
OMN	TW E	505	52	RAVELING	Low	56269.31	SqFt	99.6%	FDOT - SURFACE SEAL	56269.4	SqFt	\$ 0.55	\$ 30,950.00
OMN	TW F	605	43	BLOCK CR	Medium	8469.04	SqFt	20.3%	FDOT - CRACK SEALING - AC	2581.4	Ft	\$ 3.00	\$ 7,750.00
OMN	TW F	605	48	L&TCR	Medium	1136.15	Ft	2.7%	FDOT - CRACK SEALING - AC	1136.2	Ft	\$ 3.00	\$ 3,410.00
OMN	TW F	605	52	RAVELING	Low	41694.01	SqFt	100.0%	FDOT - SURFACE SEAL	41694	SqFt	\$ 0.55	\$ 22,940.00
OMN	TW F	650	43	BLOCK CR	Medium	2672.03	SqFt	42.6%	FDOT - CRACK SEALING - AC	814.3	Ft	\$ 3.00	\$ 2,450.00
OMN	TW F	650	48	L&TCR	Medium	27	Ft	0.4%	FDOT - CRACK SEALING - AC	26.9	Ft	\$ 3.00	\$ 90.00
OMN	TW F	650	52	RAVELING	Low	4519.98	SqFt	72.1%	FDOT - SURFACE SEAL	4519.8	SqFt	\$ 0.55	\$ 2,490.00
OMN	TW F	650	56	SWELLING	Medium	34.98	SqFt	0.6%	FDOT - PATCHING - AC FULL DEPTH	62.4	SqFt	\$ 9.00	\$ 570.00
OMN	TW G	700	45	DEPRESSION	Low	895.13	SqFt	0.6%	FDOT - PATCHING - AC FULL DEPTH	1019.3	SqFt	\$ 9.00	\$ 9,180.00
OMN	TW T-HANG	2004	65	JT SEAL DMG	High	39	Slabs	100.0%	FDOT - JOINT SEAL - PCC	682.1	Ft	\$ 2.75	\$ 1,880.00
OMN	TW T-HANG	2004	72	SHAT. SLAB	Low	15	Slabs	38.5%	FDOT - CRACK SEALING - PCC	629.9	Ft	\$ 4.25	\$ 2,680.00
OMN	TW T-HANG	2004	72	SHAT. SLAB	Medium	24	Slabs	61.5%	FDOT - SLAB REPLACEMENT - PCC	10560.5	SqFt	\$ 30.00	\$ 316,800.00





Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	OMN	AP CENTER	4204	AC	5,932	29	AC Reconstruction	\$ 75,000.00
2020	OMN	AP CENTER	4205	AAC	141,436	30	AC Reconstruction	\$ 1,768,000.00
2020	OMN	AP E	4305	AC	52,638	27	AC Reconstruction	\$ 658,000.00
2020	OMN	AP W	4102	AC	22,255	27	AC Reconstruction	\$ 279,000.00
2020	OMN	AP W	4105	AC	164,592	60	AC Restoration	\$ 1,564,000.00
2020	OMN	TW B	205	AAC	21,323	35	AC Reconstruction	\$ 267,000.00
2020	OMN	TW D	405	AAC	74,127	36	AC Reconstruction	\$ 927,000.00
2020	OMN	TW E	505	AAC	56,507	36	AC Reconstruction	\$ 707,000.00
2020	OMN	TW F	605	AC	41,694	45	AC Restoration	\$ 455,000.00
2020	OMN	TW F	650	AC	6,273	35	AC Reconstruction	\$ 79,000.00
2020	OMN	TW T-HANG	2004	PCC	17,255	7	PCC Reconstruction	\$ 346,000.00
2022	OMN	AP T HANG	4410	AC	54,829	64	AC Restoration	\$ 521,000.00
2027	OMN	RW 17-35	6210	AAC	10,188	64	AC Restoration	\$ 97,000.00
2028	OMN	RW 17-35	6205	AAC	329,912	64	AC Restoration	\$ 3,135,000.00



## Appendix C

Technical Exhibits

**LEGEND** 

SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES. INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.


AC: 66 PCC: 1

TYPICAL APRON BRANCH ID









#### **LEGEND**

PROJECTS	YEAR	2013
PROJECTS	YEAR	2014
PROJECTS	YEAR	2015
PROJECTS	YEAR	2016
PROJECTS	YEAR	2017
PROJECTS	YEAR	2018
PROJECTS	YEAR	2019
PROJECTS	YEAR	2020
PROJECTS	YEAR	2021
PROJECTS	YEAR	2022

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

FDOT

- TYPICAL TAXIWAY BRANCH ID - TYPICAL APRON BRANCH ID

PCI 86-100 GOOD PCI 71-85 SATISFACTORY


PCI 11-25 SERIOUS


PCI 0-10 FAILED

**LEGEND** 

SECTION NO. "PCI NO."

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.








### Appendix D

Inspection Photograph Documentation









RW 17-35, Section 6205, Sample Unit 159 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, and Low Severity (57) Weathering



RW 17-35, Section 6205, Sample Unit 165 - Low Severity (52) Raveling, Low Severity (56) Swelling, and Low Severity (57) Weathering







TW A, Section 100, Sample Unit 107 - Low Severity (57) Weathering



TW G, Section 700, Sample Unit 115 - Low Severity (45) Depression and Low Severity (57) Weathering





TW D, Section 405, Sample Unit 101 - Medium Severity (43) Block Cracking and Low Severity (52) Raveling



TW E, Section 505, Sample Unit 107 - Medium Severity (43) Block Cracking and Low Severity (52) Raveling





TW T-HANG, Section 2004, Sample Unit 602 - High Severity (65) Joint Seal Damage and Low Severity (72) Shattered Slab



AP CENTER, Section 4205, Sample Unit 111 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (50) Patching, Low Severity (52) Raveling, and Medium Severity (52) Raveling








AP E, Section 4305, Sample Unit 101 - Medium Severity (41) Alligator Cracking, High Severity (41) Alligator Cracking, and Low Severity (52) Raveling



# Appendix E

Inspection Distress Details



### **Re-Inspection Report**

**FDOT** 

**Sample Comments:** 

50

43

48

48

52

RAVELING

PATCHING

BLOCK CR

L & T CR

L & T CR

RAVELING

Cenerated Date 10/4/2019 Page 1 of 34

Generated Date		10/4/2019					rage 1 01 34
Network: OM	ÍN		Name:	ORMOND BEACH	MUNICIPAL A	IRPORT	
Branch: AP	CENTER	Name:	CENTER APRON	Use: A	PRON	Area:	147,368 SqFt
Section: 4204		of 2 From	1: -		То: -		<b>Last Const.:</b> 7/31/2008
Surface: AC	Family:	: C9N59-RL-AP-AC	Zone:		Category:		Rank: T
Area:	5,932 SqFt	Length:	285 Ft	Width:	22 Ft		
Slabs:	Slab L	ength:	Ft Slab W	idth:	Ft	Joint Length	r: Ft
Shoulder:	Street	Type:	Grade:	0		Lanes: 0	
Section Comment	ts:						
Work Date: 7/31	/2008	Work Type: New Con	struction - Initial	Code	: NU-IN	Is Major	r M&R: True
Last Insp. Date:	1/28/2019	TotalSamp	les: 2	Surveyed:	1		
Conditions: PC	CI: 30						
Inspection Comm	ients:						
Sample Number:	115 <b>T</b>	ype: R	Area:	3300.00 SqFt	PCI: 3	0	

3075.00 SqFt

129.00 SqFt

98.00 SqFt

96.00 SqFt

129.00 Ft

450.00 Ft

L

L

L

L

M

Н

<b>Branch:</b> AP CENTER	N	ame: CENT	ER APRON	Use:	APRON	Area:	147,368 SqFt	
Section: 4205	of 2	From:	_		То: -		Last Const.: 1/	1/1992
		9-RL-AP-AAC-APG	7one:		Category:		Rank: T	
	· ·		600 Ft	Width:	218 Ft		Tunk. 1	
Area: 141,436 S	_	ength:						
	Slab Length:	Ft	Slab Wid	th:	Ft	Jo	int Length: Ft	
Shoulder: S	Street Type:		Grade:	0		La	nnes: 0	
Section Comments:								
<b>Work Date:</b> 1/1/1979	Work Typ	e: BUILT		C	ode: IMPORTED		Is Major M&R: True	
<b>Work Date:</b> 1/1/1992	Work Typ	e: OVERLAY		C	ode: IMPORTED		Is Major M&R: True	
<b>Last Insp. Date:</b> 1/28/2019		TotalSamples:	26	Surveye	ed: 4			
Conditions: PCI: 33								
<b>Inspection Comments:</b>								
Sample Number: 102	Type:	R A	Area:	5452.00 SqFt	PCI: 4	12		
_	Type.	K F	il ca.	3432.00 Sqrt	TCI.	-2		
Sample Comments:								
52 RAVELING	L	5161.00						
50 PATCHING	Н	250.00						
52 RAVELING	H M	17.00						
52 RAVELING 48 L & T CR	L IVI	24.00 283.00	-					
48 L & T CR	M	250.00						
Sample Number: 111	Type:			6024.00 SqFt	PCI: 1	7		
Sample Comments:	J			1				
Sample Comments.								
43 BLOCK CR	L	660.00						
41 ALLIGATOR CR	M	527.00						
50 PATCHING	L	452.00						
52 RAVELING	L	2400.00						
48 L & T CR	L	50.00						
45 DEPRESSION	L	80.00						
52 RAVELING	M	1600.00	-					
43 BLOCK CR	M	2621.00	SqFt					
Sample Number: 205	Type:	R A	Area:	5001.00 SqFt	PCI: 4	2		
Sample Comments:								
52 RAVELING	Н	6.00	SqFt					
50 PATCHING	L	67.00						
48 L & T CR	M	217.00	Ft					
50 PATCHING	M	434.00	SqFt					
43 BLOCK CR	M	256.00	SqFt					
52 RAVELING	L	4494.00	SqFt					
48 L & T CR	L	80.00						
Sample Number: 209	Type:	R A	Area:	5001.00 SqFt	PCI: 3	2		
Sample Comments:								
-		• • • • • • • • • • • • • • • • • • • •	C E					
52 RAVELING	L	2800.00						
_	L L	2800.00 3751.00						
52 RAVELING			SqFt					

Network:	: OMN				Nan	ne: ORN	MOND BEA	CH MUNICIPA	L AIRPO	RT			
Branch:	AP E		Name:	EAST AREA		N - HANGAR	Use:	APRON	Aı	rea:	:	52,638 SqFt	
Section:	4305	of 1		From:	-			То: -				Last Const.:	1/1/1984
Surface:	AC	Family: C9	N59-RL	-AP-AC	Zon	e:		Category	:			Rank: P	
Area:	52,638	8 SqFt	Lengt	th:	342 F	t	Width:	150 1	Ft				
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Le	ngth:	I	- Et
Shoulder	:	Street Type:				Grade: 0				Lanes:	0		
Section C	Comments:												
Work Da	ite: 1/1/1984	Work	Type: B	UILT			C	ode: IMPORT	ED	Is M	lajor N	/I&R: True	
Last Insp	<b>Date:</b> 1/28/2019		Tot	alSamples:	11		Surveye	ed: 3					
Condition	ns: PCI: 28												
Inspectio	n Comments:												
Sample N	Number: 101	Туре:	R	A	\rea:	6927	.00 SqFt	PCI:	: 17				
Sample C	Comments:												
43 BI	LOCK CR		M	4254.00	SqFt								
45 DI	EPRESSION		L	50.00	SqFt								
	ATCHING		M	400.00									
	AVELING		L	5297.00									
	ATCHING		L	1230.00									
	LLIGATOR CR		Н	10.00									
	LLIGATOR CR		M	1033.00									
45 DI	EPRESSION		M	52.00	SqFt								
Sample N	Number: 102	Type:	R	A	\rea:	6156	.00 SqFt	PCI:	32				
Sample C	Comments:												
50 PA	ATCHING		M	4.00	SqFt								
43 BI	LOCK CR		L	3050.00	SqFt								
43 BI	LOCK CR		M	3050.00									
	EPRESSION		L	130.00									
	AVELING		L	6152.00									
	LLIGATOR CR		L	56.00									
	Number: 201 Comments:	Type:	R	A	Area:	4914	.00 SqFt	PCI:	38				
_			T	4002.00	CaE4								
	AVELING LOCK CR		L M	4902.00 2451.00									
	LOCK CR LOCK CR		L	2451.00									
	ATCHING		L	12.00									
	EPRESSION		L	16.00									

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** AP RU RUN-UP APRON Use: APRON Area: 137,041 SqFt Name: 5110 Section: of 4 From: **Last Const.:** 1/1/2013 To: -Surface: AC Family: C9N59-RL-AP-AC Zone: Category: Rank: P 100 Ft Area: 28,383 SqFt Length: 300 Ft Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 5 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 6227.00 SqFt **PCI:** 94 Sample Number: 501 Type: Area: **Sample Comments:** 

57

WEATHERING

L

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** AP RU Name: RUN-UP APRON Use: APRON Area: 137,041 SqFt 5115 Section: of 4 **Last Const.:** 1/1/2013 From: To: -Surface: AC Family: C9N59-RL-AP-AC Zone: Category: Rank: P 100 Ft Area: 28,289 SqFt Length: 300 Ft Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 6 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 5000.00 SqFt **PCI:** 91 Sample Number: 501 Type: Area: **Sample Comments:** 57 WEATHERING L 5000.00 SqFt

L

7.00 Ft

48

L & T CR

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** AP RU RUN-UP APRON Use: APRON Area: 137,041 SqFt Name: Section: 5120 of 4 **Last Const.:** 1/1/2016 From: To: -Surface: AC Family: C9N59-RL-AP-AC Zone: Category: Rank: P 105 Ft Area: 40,182 SqFt Length: 385 Ft Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2016 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 8 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 5500.00 SqFt **PCI:** 94 Sample Number: 502 Type: Area: **Sample Comments:** 

57

WEATHERING

L

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** AP RU RUN-UP APRON Use: APRON Area: 137,041 SqFt Name: 5125 Section: of 4 **Last Const.:** 1/1/2016 From: To: -Surface: AC Family: C9N59-RL-AP-AC Zone: Category: Rank: P 105 Ft Area: 40,187 SqFt Length: 385 Ft Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2016 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 8 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 5500.00 SqFt **PCI:** 94 Sample Number: 505 Type: Area: **Sample Comments:** 

57

WEATHERING

L

Network	: OMN			Nai	ne: ORMO	ND BEAG	CH MUNICIPAL	AIRPORT			
Branch:	AP T HANG		Name:	AP T HANG		Use:	APRON	Area:	54	1,829 SqFt	
Section:	4410	of	1 <b>F</b>	rom: -			То: -			Last Const.:	1/1/2005
Surface:	AC	Family:	C9N59-RL-AP	-AC Zor	ie:		Category:			Rank: P	
Area:	54,82	9 SqFt	Length:	2,000	Ft <b>W</b>	idth:	25 Ft				
Slabs:		Slab Len	gth:	Ft	Slab Width:		Ft	Joint L	ength:	Ft	
Shoulder	:	Street Ty	pe:		Grade: 0			Lanes:	0		
Section C	Comments:										
Work Da	nte: 1/1/2005	Wo	ork Type: New	Construction - AC	•	Co	ode: NC-AC	Is N	Aajor Mo	&R: True	
Last Insp	Date: 1/28/2019	)	TotalSa	amples: 11		Surveye	<b>d:</b> 2				
Condition	ns: PCI: 68										
Inspectio	on Comments:										
Sample N	Number: 102	Тур	e: R	Area:	4941.00	SqFt	PCI:	82			
Sample (	Comments:										
52 R.	AVELING		L	988.00 SqFt							
48 L	& T CR		L	21.00 Ft							
	Number: 303	Тур	e: R	Area:	5000.00	SqFt	PCI:	54			
Sample N											
•	Comments:										
Sample (	Comments: LLIGATOR CR		Н	10.00 SqFt							
Sample (41 A) 45 D	LLIGATOR CR EPRESSION		H L	95.00 SqFt							
Sample (41 A) 45 D) 52 R.	LLIGATOR CR EPRESSION AVELING			95.00 SqFt 4958.00 SqFt							
Sample C 41 A 45 D 52 R 48 L	LLIGATOR CR EPRESSION		L	95.00 SqFt							

ORMOND BEACH MUNICIPAL AIRPORT Network: OMN Name: **Branch:** AP W WEST APRON Use: APRON 186,847 SqFt Name: Area: of 2 Section: 4102 **Last Const.:** 1/1/1992 From: To: -Surface: ACFamily: C9N59-RL-AP-AC Zone: Category: Rank: P 670 Ft Area: 22,255 SqFt Length: Width: 34 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1992 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 7 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 28 Sample Number: 101 Type: R 3366.00 SqFt Area: **Sample Comments:** 52 RAVELING L 1500.00 SqFt 49 OIL SPILLAGE N 35.00 SqFt BLOCK CR 43 M 3366.00 SqFt RAVELING 52 10.00 SqFt M

**SWELLING** 

L

815.00 SqFt

Network: OMN		Name:	ORMOND BEAC	CH MUNICIPAL AIF	RPORT	
Branch: AP W	Name:	WEST APRON	Use:	APRON	Area:	186,847 SqFt
Section: 4105	of 2	From: -		То: -		Last Const.: 1/1/1992
Surface: AC	Family: C9N59-RL-A	AP-AC Zone:		Category:		Rank: T
<b>Area:</b> 164,592	2 SqFt Length	: 835 Ft	Width:	180 Ft		
Slabs:	Slab Length:	Ft Slab Wi	idth:	Ft	Joint Lengt	h: Ft
Shoulder:	Street Type:	Grade:	0		Lanes: (	)
Section Comments:	••					
<b>Work Date:</b> 1/1/1992	Work Type: BU	ILT	Co	ode: IMPORTED	Is Majo	r M&R: True
<b>Last Insp. Date:</b> 1/28/2019	Total	Samples: 39	Surveye	<b>d:</b> 4		
Conditions: PCI: 61		•	•			
Inspection Comments:						
	T	<u> </u>	5000 00 C E	DOI CA		
Sample Number: 102	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 64		
Sample Comments:						
57 WEATHERING	L	3400.00 SqFt				
52 RAVELING	L	1600.00 SqFt				
48 L & T CR	L	395.00 Ft				
48 L & T CR	M	130.00 Ft				
Sample Number: 205	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 63		
Sample Comments:						
52 RAVELING	M	8.00 SqFt				
49 OIL SPILLAGE	N	24.00 SqFt				
48 L & T CR	M	144.00 Ft				
48 L & T CR	L	300.00 Ft				
52 RAVELING	L	1492.00 SqFt				
Sample Number: 307	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 57		
Sample Comments:						
52 RAVELING	L	1458.00 SqFt				
50 PATCHING	L	42.00 SqFt				
48 L & T CR	L	401.00 Ft				
48 L & T CR	M	181.00 Ft				
49 OIL SPILLAGE	N	16.00 SqFt				
57 WEATHERING	L	3500.00 SqFt				
Sample Number: 403	Type: R	Area:	3000.00 SqFt	<b>PCI:</b> 59		
Sample Comments:						
40 I 0 T CD	L	195.00 Ft				
48 L & T CR						
57 WEATHERING	L	1150.00 SqFt				
	L M	1150.00 SqFt 130.00 Ft				

Network:	OMN				Na	me: OR	MOND BE	ACH M	IUNICIPAL A	IRPOR'	Γ			
Branch:	RW 17-35		Na	ame: RUN	WAY 1	7-35	Use	: RU	JNWAY	Area	a: 3	370,500	SqFt	
Section: 62	205	of 3	3	From:	-				То: -			Last	Const.:	1/1/2008
Surface: A	AC		9N59 PC	-RL-RW-AAC-	Zo	ne:			Category:			Ran	<b>k:</b> P	
Area:	329,912	2 SqFt	L	ength:	3,300	Ft	Width:		100 Ft					
Slabs:		Slab Length	1:	Ft		Slab Width:			Ft		Joint Length:		F	t
Shoulder:		Street Type:	:			Grade: 0					Lanes: 0			
Section Com	ments:													
Work Date:	1/1/1943	Work	Тур	e: BUILT				Code:	IMPORTED		Is Major	M&R:	True	
Work Date:	1/1/1983	Work	Тур	e: OVERLAY				Code:	IMPORTED		Is Major	M&R:	True	
Work Date:			Тур	e: Mill and Overla	ay				ML-OL		Is Major	M&R:	True	
=	ite: 1/28/2019			<b>TotalSamples:</b>	66		Surve	yed: 1	14					
Conditions:	<b>PCI:</b> 73													
Inspection Co	omments:													
Sample Num	ber: 103	Type:		R	Area:	5000	0.00 SqFt		PCI: 7	'8				
Sample Com	ments:													
57 WEAT	ΓHERING		L	3300.00	SqFt									
52 RAVE	ELING		L	1700.00	SqFt									
Sample Num Sample Com		Type:		R	Area:	5000	0.00 SqFt		PCI: 7	<b>'</b> 4				
_			т	2400.00	C-E4									
57 WEAT 48 L&T	THERING CR		L L	3400.00 36.00	-									
	ELING		L	1600.00										
Sample Num	ber: 112	Type:		R	Area:	5000	0.00 SqFt		PCI:	<b>'</b> 6				
Sample Com	ments:													
52 RAVE	ELING		L	1100.00	SqFt									
48 L&T	CR		L	112.00	Ft									
	THERING		L	3900.00										
Sample Num		Type:		R	Area:	5000	0.00 SqFt		PCI: 7	'3				
Sample Com	ments:													
	ELING		L	1600.00	-									
18 L&T 57 WEAT	CR THERING		L L	95.00										
Sample Num		Type:		3400.00	Area:		0.00 SqFt		PCI: 7	12				
Sample Com		Type.		K	Aica.	3000	0.00 Sqrt		TCI.	3				
7 WEA	ΓHERING		L	3400.00										
	ELING		L	1600.00										
48 L&T		Tr	L	88.00		500	0.00 8-12		DCI. 7	12				
Sample Num Sample Com		Type:		R	Area:	5000	0.00 SqFt		PCI: 7	3				
52 RAVE	ELING		L	1600.00	SqFt									
18 L&T			L	71.00										
	THERING	nan .	L	3400.00			0.00.0.7:		DCT -					
Sample Num		Type:		R	Area:	5000	0.00 SqFt		PCI: 7	1				
Sample Com														
18 L&T			L	17.00										
	ELING THERING		L L	1100.00 3900.00										
Sample Num		Type:			Area:		0.00 SqFt		PCI: 7	'3				
Sample Num		- Jpc.				3000	bq1 t		101.	_				
				2.00	<i>c</i> =									
57 WEAT	ΓHERING		L	3400.00	SqFt									

48	L & T CR	I	_	55.00 Ft			
52	RAVELING	I	_	1600.00 SqFt			
Sam	ple Number: 139	Type:	R	Area:	5000.00 SqFt	PCI: 73	
Sam	ple Comments:						
		_					
48	L & T CR	I		64.00 Ft			
57	WEATHERING	I		3400.00 SqFt			
52	RAVELING	I		1600.00 SqFt			
Sam	ple Number: 142	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 72	
Sam	ple Comments:						
48	L & T CR	I	_	42.00 Ft			
56	SWELLING	I	_	16.00 SqFt			
57	WEATHERING	I	_	3400.00 SqFt			
52	RAVELING	I	_	1600.00 SqFt			
Sam	ple Number: 153	Type:	R	Area:	5000.00 SqFt	PCI: 70	
Sam	ple Comments:						
56	SWELLING	Ι	_	45.00 SqFt			
57	WEATHERING	I		3042.00 SqFt			
48	L & T CR	I	_	14.00 Ft			
52	RAVELING	I	_	1958.00 SqFt			
Sam	ple Number: 159	Type:	R	Area:	5000.00 SqFt	PCI: 68	
Sam	ple Comments:						
48	L & T CR	I	_	65.00 Ft			
56	SWELLING	I	_	375.00 SqFt			
52	RAVELING	I	_	1600.00 SqFt			
57	WEATHERING	I	_	3400.00 SqFt			
Sam	ple Number: 165	Туре:	R	Area:	5000.00 SqFt	<b>PCI:</b> 67	
Sam	ple Comments:						
48	L & T CR	I	_	21.00 Ft			
52	RAVELING	I	_	2100.00 SqFt			
57	WEATHERING	I	_	2900.00 SqFt			
56	SWELLING	I	_	625.00 SqFt			
Sam	ple Number: 171	Type:	R	Area:	5000.00 SqFt	PCI: 72	
Sam	ple Comments:						
57	WEATHERING	Ι	_	3100.00 SqFt			
56	SWELLING	I		130.00 SqFt			
52	RAVELING	I		1900.00 SqFt			
				•			

Network:	OMN				Name:	ORN	MOND BEA	CH MU	NICIPAL AI	RPORT			
Branch:	RW 17-35		Name:	RUNW	AY 17-35		Use:	RUN	WAY	Area:	370,50	0 SqFt	
Section:	6210	0	f 3	From: -	-			Т	o: -		Las	t Const.:	: 1/1/2008
Surface:	AAC	Family:	C9N59-RL-I APC	RW-AAC-	Zone:			C	ategory:		Rai	nk: P	
Area:	10,	,188 SqFt	Length	ı:	100 Ft		Width:		100 Ft				
Slabs:		Slab Len	ıgth:	Ft	Sla	ab Width:		F	t	Joint L	ength:	I	Ft
Shoulder:		Street T	ype:		Gı	rade: 0				Lanes:	0		
Section Co	omments:												
Work Date	e: 1/1/1943	W	ork Type: BU	ЛLТ			C	ode: 1	MPORTED	Is !	Major M&R	True	
Work Date	e: 1/1/1973	W	ork Type: OV	/ERLAY			C	ode: 1	MPORTED	Is I	Major M&R	True	
Work Date	e: 1/1/2008	W	ork Type: Mi	ll and Overlay	,		C	ode: 1	ML-OL	Is I	Major M&R	True	
Last Insp.	Date: 1/28/20	)19	Tota	Samples: 2	2		Surveye	ed: 1					
Conditions	s: PCI: 72	2											
Inspection	<b>Comments:</b>												
Sample Nu	ımber: 145	Тур	pe: R	A	rea:	5187	'.00 SqFt		PCI: 72	<u> </u>			
Sample Co	omments:												
56 SW	ELLING		L	150.00	SqFt								
48 L &	z T CR		L	58.00	Ft								
52 RA	VELING		L	1000.00	SqFt								
57 WE	EATHERING		L	4000.00	SaEt								

Netw	ork: OM	N					Nar	ne:	ORN	MOND BE	ACH N	MUNICIPAL	AIRI	PORT					
Bran	ch: RW	17-35		Na	me:	RUNV	VAY 17	7-35		Use	: RU	JNWAY		Area:		37	0,500	SqFt	
Section	on: 6215		of .	3	Fro	m:	-					To: -					Last	Const.:	1/1/2019
Surfa	ice: AC	Famil	y: C	9N59-	RL-RW-A	.C	Zon	ie:				Category:					Rank	: P	
Area	:	30,400 SqFt		Le	ength:		300 I	₹t		Width:		100 F	t						
Slabs	:	Slab	Length	1:		Ft		Slab W	idth:			Ft		Joi	int Len	gth:		I	<sup>7</sup> t
Shou	lder:	Stree	et Type	:				Grade:	0					La	nes:	0			
Section	on Comments	:																	
Worl	<b>Date:</b> 1/1/19	943	Work	к Туре	: BUILT						Code:	IMPORTI	ED		Is Ma	jor M	I&R:	True	
Worl	<b>Date:</b> 1/1/19	973	Work	к Туре	: OVERL	AY					Code:	IMPORTI	ED		Is Ma	jor M	l&R:	True	
Worl	<b>Date:</b> 1/1/20	008	Work	с Туре	: Mill and	Overla	y				Code:	ML-OL			Is Ma	jor M	I&R:	True	
Worl	<b>Date:</b> 1/1/20	)19	Work	к Туре	: Complet	e Recor	struction	on - AC			Code:	CR-AC			Is Ma	jor M	l&R:	True	
Last	Insp. Date:	12/4/2014			TotalSam	ples:	6			Surve	yed:	2							
	itions: PC					NC	TE: <mark>**</mark>	** Pre-Co	<mark>onstru</mark>	iction PCI	***								
Inspe	ection Comme	ents:																	
Samp	ole Number:	146	Type:		R	A	Area:		5000	0.00 SqFt		PCI:	76						
Samp	ole Comments	:																	
57	WEATHER	ING		L	3	500.00	SqFt												
48	LONGITUE CRACKING	DINAL/TRANSV 3	ERSE	L		4.00	-												
52	RAVELING	j		L	1	500.00	SqFt												
Samp	ole Number:	148	Type:		R	A	\rea:		5000	0.00 SqFt		PCI:	72						
Samp	ole Comments	:																	
56	SWELLING	j		L		22.00	SqFt												
57	WEATHER			L		500.00	-												
52	RAVELING	ì		L	1	500.00	SqFt												
48	LONGITUE CRACKING	DINAL/TRANSV 3	ERSE	L		88.00	Ft												

Network:	OMN				Nam	ne: ORN	MOND BEA	ACH M	IUNICIPAL AIF	RPORT				
Branch:	RW 8-26		Nam	e: RUNV	WAY 8-2	26	Use:	RU	JNWAY	Area:		292,950	SqFt	
Section:	6105	of 1		From:	-				То: -			Last	Const.:	1/1/2019
Surface:	AC F	amily: C9	9N59-R	L-RW-AC	Zone	e:			Category:			Ran	k: S	
Area:	292,950	SqFt	Len	gth:	4,000 F	t	Width:		75 Ft					
Slabs:		Slab Length:	:	Ft		Slab Width:			Ft	Jo	int Length	:	F	't
Shoulder		Street Type:				Grade: 0					anes: 0			
	Comments:													
Work Da	te: 1/1/1943	Work	Type:	BUILT			(	Code:	IMPORTED		Is Major	M&R:	True	
Work Da	te: 1/1/1977	Work	Type:	OVERLAY			(	Code:	IMPORTED		Is Major	M&R:	True	
Work Da	te: 1/1/2019	Work	Type:	Complete Recor	nstructio	n - AC		Code:	CR-AC		Is Major	M&R:	True	
Last Insp	. Date: 12/4/2014		T	otalSamples:	78		Survey	yed: 1	16					
Conditior Inspection	ns: PCI: 67 n Comments:			NO	OTE: **	* Pre-Constru	ction PCI	***						
	Number: 103	Type:	R		Area:	3750	).00 SqFt		PCI: 69					
_	Comments:	- 3 P - 1					1- :							
	ONGITUDINAL/TRA RACKING	NSVERSE	L	307.00	Ft									
	AVELING		L	3750.00	SqFt									
_	Number: 107	Type:	R	1	Area:	3750	0.00 SqFt		<b>PCI:</b> 69					
Sample C	Comments:													
	ONGITUDINAL/TRA	NSVERSE	L	182.00	Ft									
	RACKING AVELING		L	3750.00	SaFt									
	Number: 112	Type:	R		Area:	3750	).00 SqFt		PCI: 64					
-	Comments:	1 ype:	K	1	Area:	3/30	).00 SqFt		FCI: 04					
_														
	ONGITUDINAL/TRA RACKING	NSVERSE	L	138.00	Ft									
	AVELING		L	3750.00	SaFt									
	ONGITUDINAL/TRA	NSVERSE		15.00										
CF	RACKING													
Sample N	Number: 117	Type:	R	1	Area:	3750	0.00 SqFt		<b>PCI:</b> 69					
Sample C	Comments:													
52 R.A	AVELING		L	3750.00	SaFt									
	ONGITUDINAL/TRA	NSVERSE		169.00										
	RACKING													
Sample N	Number: 120	Туре:	R	1	Area:	3750	0.00 SqFt		<b>PCI:</b> 69					
Sample C	Comments:													
52 R.A	AVELING		L	3750.00	SaEt									
18 LC	AVELING ONGITUDINAL/TRA RACKING	NSVERSE		222.00	-									
	Sumber: 124	Type:	R		Area:	3750	0.00 SqFt		PCI: 64					
Sample C	Comments:													
52 R.A	AVELING		L	3750.00										
	ONGITUDINAL/TRA RACKING	NSVERSE	L	182.00										
18 LC	ONGITUDINAL/TRA RACKING	NSVERSE	M	11.00	Ft									
Sample N	Sumber: 128	Type:	R		Area:	3750	0.00 SqFt		<b>PCI:</b> 67					
_	Comments:	- <b>-</b>					=							
52 R.A	AVELING		L	3750.00	SaFt									
48 LC	ONGITUDINAL/TRA	NSVERSE		229.00	-									
	RACKING WELLING		L	22.00	SqFt									
, , , , , , , , , , , , , , , , , , ,	2221.10		_	22.00	⊃qı t									

Sample Number: 131         Type:         R         Area:         3750.00 SqFt         PCI:         69           Sample Comments:           48         LONGITUDINAL/TRANSVERSE (RACKING)         L         58.00 Ft         Sample CRACKING         L         100.00 Ft         Sample CRACKING         L         3750.00 SqFt         PCI:         69           52         RAVELING         L         3750.00 SqFt         PCI:         69           Sample Comments:           52         RAVELING         L         3750.00 SqFt         PCI:         69           Sample Comments:         L         3750.00 SqFt         PCI:         69           Sample Number: 146         Type:         R         Area:         3750.00 SqFt         PCI:         69           Sample Number: 146         Type:         R         Area:         3750.00 SqFt         PCI:         69           Sample Number: 151         Type:         R         Area:         3750.00 SqFt         PCI:         69           Sample Number: 151         Type:         R         Area:         3750.00 SqFt         PCI:         69           Sample Number: 151         Type:	
48 LONGITUDINAL/TRANSVERSE L 100.00 Ft CRACKING  48 LONGITUDINAL/TRANSVERSE L 100.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 136 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  52 RAVELING L 3750.00 SqFt  48 LONGITUDINAL/TRANSVERSE L 21.00 Ft CRACKING  48 LONGITUDINAL/TRANSVERSE L 250.00 Ft  CRACKING  Sample Number: 146 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 168.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 168.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 177.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
CRACKING	
CRACKING 52 RAVELING L 3750.00 SqFt  Sample Number: 136 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  52 RAVELING L 3750.00 SqFt 48 LONGITUDINAL/TRANSVERSE L 21.00 Ft CRACKING 48 LONGITUDINAL/TRANSVERSE L 250.00 Ft CRACKING  Sample Number: 146 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 168.00 Ft CRACKING 52 RAVELING L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 177.00 Ft CRACKING 52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
Sample Number:   136	
Sample Comments:	
Sample Number:   15   Type:   R   Area:   3750.00 SqFt   PCI:   69	
48 LONGITUDINAL/TRANSVERSE L 21.00 Ft CRACKING  48 LONGITUDINAL/TRANSVERSE L 250.00 Ft  Sample Number: 146 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 168.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 177.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
CRACKING  48 LONGITUDINAL/TRANSVERSE L CRACKING  Sample Number: 146	
CRACKING	
Sample Comments:	
48 LONGITUDINAL/TRANSVERSE L 168.00 Ft CRACKING 52 RAVELING L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 177.00 Ft CRACKING 52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 151 Type: R Area: 3750.00 SqFt PCI: 69  Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 177.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
Sample Number:         151         Type:         R         Area:         3750.00 SqFt         PCI:         69           Sample Comments:           48         LONGITUDINAL/TRANSVERSE L CRACKING         177.00 Ft CRACKING         52         RAVELING         L 3750.00 SqFt           52         RAVELING         L 3750.00 SqFt         PCI:         69	
Sample Comments:  48 LONGITUDINAL/TRANSVERSE L 177.00 Ft CRACKING  52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
48 LONGITUDINAL/TRANSVERSE L 177.00 Ft CRACKING 52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
CRACKING 52 RAVELING L 3750.00 SqFt  Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
Sample Number: 155 Type: R Area: 3750.00 SqFt PCI: 69	
Sample Comments:	
48 LONGITUDINAL/TRANSVERSE L 124.00 Ft CRACKING	
52 RAVELING L 3750.00 SqFt	
48 LONGITUDINAL/TRANSVERSE L 100.00 Ft CRACKING	
Sample Number: 161 Type: R Area: 3750.00 SqFt PCI: 67	
Sample Comments:	
48 LONGITUDINAL/TRANSVERSE L 209.00 Ft CRACKING	
56 SWELLING L 8.00 SqFt	
52 RAVELING L 3750.00 SqFt	
Sample Number: 166 Type: R Area: 3750.00 SqFt PCI: 64	
Sample Comments:	
52 RAVELING L 3750.00 SqFt	
48 LONGITUDINAL/TRANSVERSE L 92.00 Ft CRACKING	
48 LONGITUDINAL/TRANSVERSE M 20.00 Ft CRACKING	
Sample Number: 172 Type: R Area: 3750.00 SqFt PCI: 69	
Sample Comments:	
52 RAVELING L 3750.00 SqFt 48 LONGITUDINAL/TRANSVERSE L 187.00 Ft CRACKING	
Sample Number: 177 Type: R Area: 3750.00 SqFt PCI: 69	
Sample Comments:	
48 LONGITUDINAL/TRANSVERSE L 218.00 Ft CRACKING	
52 RAVELING L 3750.00 SqFt	

Network: OMN		Name	: ORMOND BEA	CH MUNICIPAL AIF	RPORT	
Branch: TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	78,332 SqFt
Section: 100	of 7	From: -		То: -		<b>Last Const.:</b> 1/1/2013
Surface: AC	Family: C9N59-RL-	TW-AC Zone:		Category:		Rank: P
<b>Area:</b> 149,004	4 SqFt Lengtl	4,250 Ft	Width:	35 Ft		
Slabs:	Slab Length:	Ft S	lab Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:	(	Grade: 0		Lanes: 0	
<b>Section Comments:</b>						
Work Date: 1/1/2013	Work Type: No	ew Construction - Initial	. С	ode: NU-IN	Is Major	M&R: True
<b>Last Insp. Date:</b> 1/28/2019	Tota	lSamples: 41	Surveye	<b>d:</b> 5		
Conditions: PCI: 93						
<b>Inspection Comments:</b>						
Sample Number: 101	Type: R	Area:	3939.00 SqFt	<b>PCI:</b> 90		
<b>Sample Comments:</b>						
48 L & T CR	L	18.00 Ft				
57 WEATHERING	L	3939.00 SqFt				
Sample Number: 107	Type: R	Area:	3500.00 SqFt	<b>PCI:</b> 94		
Sample Comments:						
57 WEATHERING	L	3500.00 SqFt				
Sample Number: 117	Type: R	Area:	3500.00 SqFt	<b>PCI:</b> 94		
Sample Comments:						
57 WEATHERING	L	3500.00 SqFt				
Sample Number: 127	Type: R	Area:	3500.00 SqFt	<b>PCI:</b> 94		
Sample Comments:						
57 WEATHERING	L	3500.00 SqFt				
Sample Number: 138	Type: R	Area:	3500.00 SqFt	<b>PCI:</b> 94		
<b>Sample Comments:</b>						
57 WEATHERING	L	3500.00 SqFt				

ORMOND BEACH MUNICIPAL AIRPORT Network: OMN Name: **Branch:** TW A TAXIWAY A Use: TAXIWAY 178,332 SqFt Name: Area: of 7 Section: 105 **Last Const.:** 1/1/2016 From: To: -Surface: AAC Family: C9N59-RL-TW-AAC-Zone: Category: Rank: P APC 4,550 SqFt Length: Width: 130 Ft 35 Ft Area: Ft Slabs: Slab Length: Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: 0 **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2016 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 1/28/2019 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** PCI: 94 Sample Number: 119 R 4550.00 SqFt Type: Area: **Sample Comments:** 

57 WEATHERING L 4550.00 SqFt

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** TW A TAXIWAY A Use: TAXIWAYArea: 178,332 SqFt Name: Section: 110 of 7 **Last Const.:** 1/1/2013 From: To: Surface: ACFamily: C9N59-RL-TW-AC Zone: Category: Rank: P 8,089 SqFt 194 Ft 40 Ft Area: Length: Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 4588.00 SqFt **PCI:** 90 Sample Number: 201 Type: Area: **Sample Comments:** 52 RAVELING L 92.00 SqFt

L

4496.00 SqFt

57

WEATHERING

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** TW A TAXIWAY A Use: TAXIWAYArea: 178,332 SqFt Name: Section: 115 of 7 From: To: **Last Const.:** 1/1/2013 Surface: ACFamily: C9N59-RL-TW-AC Zone: Category: Rank: P 193 Ft 40 Ft Area: 8,054 SqFt Length: Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 3500.00 SqFt **PCI:** 94 Sample Number: 200 Type: Area: **Sample Comments:** 

57 WEATHERING L 3500.00 SqFt

<b>Network:</b> OMN		Nai	me: ORMOND BEA	CH MUNICIPAL AIR	LPORT	
Branch: TW B	Nam	ne: TAXIWAY E	B Use:	TAXIWAY	Area:	30,346 SqFt
Section: 205	of 2	From: -		То: -		Last Const.: 1/1/1977
Surface: AAC	Family: C9N59-R APC	RL-TW-AAC- Zor	ne:	Category:		Rank: P
<b>Area:</b> 21,3	323 SqFt Len	ngth: 495 ]	Ft Width:	40 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:		Grade: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1943	Work Type:	BUILT	C	Code: IMPORTED	Is Major I	M&R: True
Work Date: 1/1/1977	Work Type:	OVERLAY	C	Code: IMPORTED	Is Major N	M&R: True
<b>Last Insp. Date:</b> 1/28/201		otalSamples: 5	Surveyo	ed: 2		
Last Insp. Date: 1/28/201 Conditions: PCI: 37		CotalSamples: 5	Surveyo	ed: 2		
Conditions: PCI: 37		<b>TotalSamples:</b> 5	Surveyo	ed: 2		
Conditions: PCI: 37 Inspection Comments:				PCI: 37		
Conditions: PCI: 37 Inspection Comments: Sample Number: 101			Surveyo 5323.00 SqFt			
Conditions: PCI: 37 Inspection Comments: Sample Number: 101 Sample Comments:		Area:				
Conditions: PCI: 37 Inspection Comments: Sample Number: 101 Sample Comments: 43 BLOCK CR	Type: R	Area: 5057.00 SqFt				
Conditions: PCI: 37 Inspection Comments: Sample Number: 101 Sample Comments: 43 BLOCK CR 56 SWELLING	Туре: К	S Area: 5057.00 SqFt 275.00 SqFt				
Conditions: PCI: 37 Inspection Comments:  Sample Number: 101 Sample Comments:  43 BLOCK CR 56 SWELLING 45 DEPRESSION	Type: R  M L	Area: 5057.00 SqFt				
Conditions: PCI: 37 Inspection Comments:  Sample Number: 101 Sample Comments:  43 BLOCK CR 56 SWELLING 45 DEPRESSION 52 RAVELING	Type: R  M L L	5057.00 SqFt 275.00 SqFt 12.00 SqFt 5323.00 SqFt				
Conditions: PCI: 37 Inspection Comments:  Sample Number: 101 Sample Comments:  43 BLOCK CR 56 SWELLING 45 DEPRESSION 52 RAVELING  Sample Number: 105	Type: R  M L L L L	5057.00 SqFt 275.00 SqFt 12.00 SqFt 5323.00 SqFt	5323.00 SqFt	<b>PCI:</b> 37		
Conditions: PCI: 37 Inspection Comments:  Sample Number: 101 Sample Comments:  43 BLOCK CR 56 SWELLING 45 DEPRESSION	Type: R  M L L L L	5057.00 SqFt 275.00 SqFt 12.00 SqFt 5323.00 SqFt	5323.00 SqFt	<b>PCI:</b> 37		
Conditions: PCI: 37 Inspection Comments:  Sample Number: 101 Sample Comments:  43 BLOCK CR 56 SWELLING 45 DEPRESSION 52 RAVELING Sample Number: 105 Sample Comments:	Type: R  M L L L Type: R	5057.00 SqFt 275.00 SqFt 12.00 SqFt 1323.00 SqFt 34 Area:	5323.00 SqFt	<b>PCI:</b> 37		

ORMOND BEACH MUNICIPAL AIRPORT Network: OMN Name: Branch: TW B TAXIWAY B Use: TAXIWAY 30,346 SqFt Name: Area: 210 of 2 **Last Const.:** 1/1/2013 Section: From: To: ACFamily: C9N59-RL-TW-AC Zone: Category: Rank: P Surface: Area: 9,023 SqFt Length: 143 Ft Width: 120 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1943 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Work Date:** 1/1/1977 Work Type: OVERLAY Code: IMPORTED Is Major M&R: True Work Date: 1/1/2013 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 5678.00 SqFt **PCI:** 94 Sample Number: 106 Type: Area:

**Sample Comments:** 

WEATHERING

57

L 5678.00 SqFt

Network:	OMN				Na	me: C	RMOND BE	EACH N	MUNICIPAL	AIRPORT	•		
Branch:	TW C		N	ame:	TAXIWAY	С	Use	: TA	AXIWAY	Area	:	35,470 SqF	t
Section: 30	05	of	1	Fro	m: -				То: -			Last Con	st.: 1/1/2013
Surface: A	AC	Family:	C9N59	-RL-TW-A	AC Zo	ne:			Category:			Rank: F	•
Area:	35,4	170 SqFt	I	ength:	1,160	Ft	Width:		50 Ft				
Slabs:		Slab Len	gth:		Ft	Slab Widt	h:		Ft		Joint Lengt	h:	Ft
Shoulder:		Street Ty	pe:			Grade:	0				Lanes:	0	
Section Com	iments:												
Work Date:	1/1/1990	Wo	ork Typ	e: BUILT				Code:	IMPORTE	D	Is Majo	or M&R: True	<b>:</b>
Work Date:	1/2/1990	Wo	ork Typ	e: Overlay	- AC Structur	al		Code:	OL-AS		Is Majo	or M&R: True	;
Work Date:	1/1/2013	Wo	ork Typ	e: Comple	te Reconstruct	ion - AC		Code:	CR-AC		Is Majo	or M&R: True	)
Last Insp. Da	ate: 1/28/201	19		TotalSam	ples: 9		Surve	eyed:	2				
Conditions:	<b>PCI:</b> 94												
Inspection C	Comments:												
Sample Num	nber: 103	Тур	e:	R	Area:	3	593.00 SqFt		PCI:	94			
Sample Com	nments:						·						
57 WEA	THERING		L	3	3593.00 SqFt								
Sample Num	nber: 106	Тур	e:	R	Area:	3	667.00 SqFt		PCI:	94			
Sample Com	iments:												

L

WEATHERING

57

Netw						Nam				UNICIPAL A				
Bran						WAY D		Use		XIWAY	Are	a: 8	8,184 SqFt	
Secti		of 2		From		-				То: -			Last Const.:	1/1/1984
Surfa	ace: AAC		9N5 .PC	9-RL-TW-AA	C-	Zone	e:			Category:			Rank: P	
Area	: 74,12	7 SqFt	1	Length:		2,160 F	t	Width:		45 Ft				
Slabs	S:	Slab Length	1:		Ft		Slab Width:			Ft		Joint Length:	F	₹t
Shou	lder:	Street Type	:				Grade: 0					Lanes: 0		
Secti	on Comments:													
Wor	k Date: 1/1/1943	Work	Тур	e: BUILT					Code:	IMPORTED	)	Is Major M	&R: True	
Wor	k Date: 1/1/1984	Work	Тур	oe: OVERLA	Y				Code:	IMPORTED	)	Is Major M	&R: True	
Last	Insp. Date: 1/28/2019	)		TotalSample	es:	16		Surve	yed: 5					
Conc	ditions: PCI: 38													
Inspe	ection Comments:													
Sam	ple Number: 101	Туре:		R		Area:	450	0.00 SqFt		PCI:	43			
	ple Comments:							1						
56	SWELLING		L			SqFt								
43	BLOCK CR		M			SqFt								
52 45	RAVELING DEPRESSION		L L			SqFt SqFt								
45 48	L & T CR		L M		50.00	-								
<del>1</del> 0 56	SWELLING		M			SqFt								
48	L & T CR		L		1.00									
Samj	ple Number: 103	Type:		R		Area:	450	0.00 SqFt		PCI:	38			
Samj	ple Comments:													
43	BLOCK CR		M	70	00.00	SqFt								
52	RAVELING		L			SqFt								
48	L & T CR		L		6.00									
48	L & T CR		M		0.00									
43 56	BLOCK CR SWELLING		L L			SqFt SqFt								
56	SWELLING		M			SqFt								
	ple Number: 107	Type:		R		Area:	450	0.00 SqFt		PCI:	34			
-	ple Comments:	• •						•						
50	PATCHING		L	5	0.00	SqFt								
56	SWELLING		L			SqFt								
52	RAVELING		L			SqFt								
50 48	PATCHING		M			SqFt								
48 43	L & T CR BLOCK CR		M M		31.00 00.00	Ft SqFt								
<del>1</del> 3 57	WEATHERING		L			SqFt								
48	L & T CR		L		0.00									
54	SHOVING		Н	2	25.00	SqFt								
45	DEPRESSION		L		6.00	SqFt								
	ple Number: 109 ple Comments:	Type:		R	1	Area:	450	0.00 SqFt		PCI:	38			
						_								
48 40	L & T CR		L		3.00									
48 43	L & T CR BLOCK CR		M M		8.00	Ft SqFt								
43 56	SWELLING		L			SqFt SqFt								
52	RAVELING		L			SqFt								
56	SWELLING		M			SqFt								
45	DEPRESSION		L	1		SqFt								
	ple Number: 113	Type:		R	1	Area:	4500	0.00 SqFt		PCI:	36			
Sami	ple Comments:													
J														
56 56	SWELLING SWELLING		L M			SqFt SqFt								

48	L & T CR	M 250.00	Ft
50	PATCHING	M 180.00	SqFt
50	PATCHING	L 40.00	SqFt
52	RAVELING	L 4280.00	SqFt
43	BLOCK CR	M 1600.00	SqFt

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** TW D TAXIWAY D Use: TAXIWAYArea: 88,184 SqFt Name: Section: 410 of 2 From: To: -**Last Const.:** 1/1/2013 Surface: ACFamily: C9N59-RL-TW-AC Zone: Category: Rank: P 200 Ft 40 Ft Area: 14,057 SqFt Length: Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 4292.00 SqFt **PCI:** 94 Sample Number: 115 Type: Area:

Sample Comments:

WEATHERING

57

4292.00 SqFt

L

	: OMN				ľ	Vame: (	ORMOND BE	ACH M	IUNICIPAL	AIRPOR	Т		
Branch:	TW E		N	ame:	TAXIWA	ΥE	Use	: TA	AXIWAY	Are	a:	85,674 SqFt	
Section:	505	0:	f 2	Fro	m: -				То: -			Last Const.:	1/1/1990
Surface:	AAC	Family:	C9N5 APC	9-RL-TW-A	AC- Z	Zone:			Category:			Rank: P	
Area:		56,507 SqFt	J	Length:	2,06	0 Ft	Width:		35 Ft				
Slabs:		Slab Len	gth:		Ft	Slab Widt	h:		Ft		Joint Length:	F	t
Shoulder	:	Street Ty	ype:			Grade:	0				Lanes: 0		
Section (	Comments:												
Work Da	ate: 1/1/1943	W	ork Typ	e: BUILT				Code:	IMPORTE	D	Is Major	M&R: True	
Work Da	ate: 1/1/1990	W	ork Typ	oe: OVERL	AY			Code:	IMPORTE	D	Is Major	M&R: True	
Last Insi	p. Date: 1/28	3/2019		TotalSam	ples: 16		Surve	yed:	3				
	ns: PCI:												
	on Comments												
				D.			450 00 G E		D.C.I.	40			
-	Number: 10	1 Туг	e:	R	Area	: 3	459.00 SqFt		PCI:	40			
Sample (	Comments:												
43 B	LOCK CR		M		459.00 Sq								
	AVELING		L	3	459.00 Sq								
56 S	WELLING		L		21.00 Sq	₹t							
Sample <b>N</b>	Number: 10	7 <b>Ty</b> r	e:	R	Area	: 3	501.00 SqFt		PCI:	40			
Sample (	Comments:												
52 R	AVELING		L	3	500.00 Sq	7t							
	WELLING		L	3	10.00 Sq.								
	LOCK CR		M	3	501.00 Sq.								
	Number: 11	1 <b>Ty</b> r		R	Area		501.00 SqFt		PCI:	34			
oumpie i	Comments:		,c.	K	71100		301.00 Sq1 t		101.	3.			
Sample (			L		50.00 Sq	7t							
_	WELLING				30.00 Bq								
56 S	WELLING ATCHING				42.00 Sal	7t							
56 S	WELLING ATCHING LOCK CR		L M	3	42.00 Sq. 458.00 Sq.								

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** TW E TAXIWAY E Use: TAXIWAYArea: 85,674 SqFt Name: 510 Section: of 2 From: To: **Last Const.:** 1/1/2013 Surface: ACFamily: C9N59-RL-TW-AC Zone: Category: Rank: P 800 Ft Area: 29,167 SqFt Length: Width: 35 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 8 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 3500.00 SqFt **PCI:** 94 Sample Number: 120 Type: Area: **Sample Comments:** 

57

WEATHERING

L

Netwo	rk:	OMN						Nai	me:	ORMO	OND BEA	CH MUN	ICIPAL	AIRPORT			
Branc	h:	TW F			]	Name:	TAXI	WAY I	7		Use:	TAXIV	VAY	Area:		47,967 SqI	-}t
Sectio	n:	605		of	2	F	rom:	-				To:	-			Last Co	nst.: 1/1/1984
Surfa	ce:	AC	Fa	amily:	C9N	59-RL-TW	-AC	Zoi	ne:			Cat	egory:			Rank:	P
Area:			41,694 S	SqFt		Length:		1,040	Ft	•	Width:		40 F	t			
Slabs:			S	Slab Leng	gth:		Ft		Slab Wio	lth:		Ft		J	oint Length	:	Ft
Shoul	der:		S	Street Ty	pe:				Grade:	0				I	Lanes: 0		
Sectio	n Cor	mments:															
Work	Date	: 1/1/198	34	Wo	ork Ty	ype: BUIL	Т				(	Code: IM	PORTE	ED	Is Major	M&R: Tru	ie
Last I	nsp. I	Date: 1	/28/2019			TotalSa	mples:	10			Survey	ed: 2					
Condi	tions:	: PCI:	: 46														
Inspec	ction (	Commen	its:														
Samp	le Nu	mber:	103	Тур	e:	R		Area:		4000.0	00 SqFt		PCI:	37			
Samp	le Coi	mments:															
48	L &	T CR			L	,	30.00	Ft									
56		ELLING			L			SqFt									
43		OCK CR			L		1625.00	-									
43		OCK CR			N		1625.00										
52		VELING			L		4000.00	-									
48		T CR			N		30.00										
Samp	le Nu	mber:	108	Тур	e:	R	4	Area:		4000.0	00 SqFt		PCI:	55			
Samp	le Coi	mments:															
48	L &	T CR			L	,	207.00	Ft									
48	L &	T CR			N	1	188.00	Ft									
56	SWI	ELLING			L	,	20.00	SqFt									
43	BLC	OCK CR			L	,	230.00	SqFt									
52	RAV	VELING			L	,	4000.00	SqFt									

ORMOND BEACH MUNICIPAL AIRPORT Network: OMN Name: Branch: TW F TAXIWAY F Use: TAXIWAY 47,967 SqFt Name: Area: Section: 650 of 2 **Last Const.:** 1/1/1984 From: To: Surface: AC Family: C9N59-RL-TW-AC Zone: Category: Rank: P Area: 6,273 SqFt Length: 130 Ft Width: 40 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1984 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 36 Sample Number: 100 Type: R 6273.00 SqFt Area: **Sample Comments:** 56 SWELLING L 116.00 SqFt BLOCK CR L 1145.00 SqFt 43 L & T CR 22.00 Ft 48 L L & T CR 27.00 Ft 48 M PATCHING 1753.00 SqFt 50 L BLOCK CR 2672.00 SqFt 43 M 56 **SWELLING** M 35.00 SqFt

52

RAVELING

L

Network: OMN		Name:	ORMOND DEA	CU MUNICIDAL AI	рр∧рт	
			OKMOND BEA	CH MUNICIPAL AI		
Branch: TW G	Name:	TAXIWAY G	Use:	TAXIWAY	Area:	144,093 SqFt
Section: 700	of 1	From: -		То: -		<b>Last Const.:</b> 1/1/2016
Surface: AC	Family: C9N59-RL-TV	V-AC Zone:		Category:		Rank: P
<b>Area:</b> 144,093	3 SqFt Length:	4,190 Ft	Width:	35 Ft		
Slabs:	Slab Length:	Ft Sla	ab Width:	Ft	Joint Length:	: Ft
Shoulder:	Street Type:	Gı	rade: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/2016	Work Type: New	Construction - AC	C	ode: NC-AC	Is Major	M&R: True
<b>Last Insp. Date:</b> 1/28/2019	TotalS	amples: 39	Surveye	ed: 4		
Conditions: PCI: 91						
Inspection Comments:						
Sample Number: 107	Type: R	Area:	3500.00 SqFt	<b>PCI</b> : 94	1	
Sample Comments:						
57 WEATHERING	L	3500.00 SqFt				
Sample Number: 115	Type: R	Area:	5275.00 SqFt	PCI: 84	1	
Sample Comments:						
57 WEATHERING	L	5275.00 SqFt				
45 DEPRESSION	L	98.00 SqFt				
Sample Number: 120	Type: R	Area:	3500.00 SqFt	<b>PCI:</b> 94	1	
Sample Comments:						
57 WEATHERING	L	3500.00 SqFt				
Sample Number: 134	Type: R	Area:	3500.00 SqFt	<b>PCI</b> : 94	1	
Sample Comments:						
57 WEATHERING	L	3500.00 SqFt				
		1				

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** TW G2 TAXIWAY G2 Use: TAXIWAYArea: 9,003 SqFt Name: **Section:** 705 of 1 To: **Last Const.:** 1/1/2016 From: Surface: ACFamily: C9N59-RL-TW-AC Zone: Category: Rank: P 9,003 SqFt 230 Ft Area: Length: Width: 35 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments:** Work Date: 1/1/2016 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 4078.00 SqFt **PCI:** 94 Sample Number: 201 Type: Area: **Sample Comments:** 

57

WEATHERING

L

OMN ORMOND BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** TW G3 TAXIWAY G3 Use: TAXIWAYArea: 8,999 SqFt Name: Section: 710 of 1 From: To: -**Last Const.:** 1/1/2016 Surface: ACFamily: C9N59-RL-TW-AC Zone: Category: Rank: P 8,999 SqFt 230 Ft Area: Length: Width: 35 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Lanes: Shoulder: Grade: **Section Comments: Work Date:** 1/1/2016 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 4924.00 SqFt **PCI:** 94 Sample Number: 300 Type: Area:

**Sample Comments:** 

57 WEATHERING L 4924.00 SqFt

ORMOND BEACH MUNICIPAL AIRPORT Network: OMN Name: **Branch:** TW T-HANG TAXIWAY TO T-HANGARS TAXIWAY 17,255 SqFt Name: Use: Area: **Section:** 2004 of 1 **Last Const.:** 1/1/1992 From: To: Surface: PCC Family: C9N59-RL-TW-PCC Zone: Category: Rank: P Area: 17,255 SqFt Length: 640 Ft Width: 22 Ft 39 Slabs: Slab Length: 22 Ft Slab Width: 20 Ft Joint Length: 682 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1992 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/28/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 9 **Inspection Comments: PCI**: 9 Sample Number: 602 Type: R 13.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 5.00 Slabs 65 JT SEAL DMG Η 13.00 Slabs SHAT. SLAB 72 L 5.00 Slabs

SHAT. SLAB

M

8.00 Slabs