FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION AND SPACEPORTS OFFICE

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report November 2019



Space Coast Regional Airport (TIX) Commercial Airport District 5







121

Florida Department of Transportation

Statewide Airfield Pavement Management Program

Prepared by:

FDOT Aviation and Spaceports Office 605 Suwannee Street Tallahassee, Florida 32399-0450

OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS



Table of Contents

Executive Summary	10
Program Background	10
Summary of Results Pavement Condition Index (Latest Inspection) Forecasted Pavement Condition Index 2020-2029 Major Rehabilitation Planning 2020-2029	11 13
Summary of Space Coast Regional Airport	16
Chapter 1 – Introduction	18
1.1 Background	18
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019	18
 1.3 Organization 1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager 1.3.2 Participating Florida Public-Use and Publicly Owned Airports 1.3.3 Florida Department of Transportation District Offices 1.3.4 Consultant 	20 20 20
1.4 Purpose of Airport Pavement Evaluation Report	
1.5 History of the Program	22
1.6 Federal Aviation Administration (FAA)	24
1.7 FDOT SAPMP Objectives and Components 1.7.1 Program Objectives 1.7.2 Program Components	24 24
1.8 References	28
Chapter 2 – Methodology	30
2.1 Airfield Pavement Database	30
2.2 Airfield Pavement System Inventory 2.2.1 Pavement Management Program Network Definition Terminology	30 31
2.3 Airfield Pavement Structure	
2.4 Airfield Pavement Work History 2.4.1 Airfield Pavement Record Keeping	
2.5 Airfield Pavement Traffic	35
2.6 Airfield Pavement Condition Index (PCI) Survey 2.6.1 PCI Survey Methodology 2.6.2 Pavement Distress Types	35



Chapter 3 - Airfield Pavement System Inventory 45 3.1 Airfield Pavement Network Information 45 3.1.1 Previous and/or Anticipated Airfield Pavement Construction 45 3.1.2 Estimated Pavement Age 47 3.1.3 Enternation 49 3.1.4 Pavement Surface Type. 50 3.1.5 Pavement System Inventory Details 51 Chapter 4 - Airfield Pavement Condition 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 56 4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 56 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Analysis 64 4.3 Forecasted Pavement Condition Forecast 64 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 3.4 Forecasted PCI Considerations 69 4.3.4 Direcasted PCI Considerations 69 5.1 Localized Maintenance and Repair Planning 71 5.1 Localized	2.6.3 PCI Survey Inspection Procedures 2.6.4 Updates to the ASTM D5340-12	41
3.1.1 Previous and/or Anticipated Airfield Pavement Construction 45 3.1.2 Estimated Pavement Age 47 3.1.3 Functional Use Classification 49 3.1.4 Pavement System Inventory Details 50 3.1.5 Pavement System Inventory Details 51 Chapter 4 – Airfield Pavement Condition 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 56 4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 58 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Branch-Level Observations 62 4.2.2 Branch-Level Observations 62 4.2.3 Forecasted Pavement Condition Forecast 64 4.3.1 Performance Models and Prediction Curves 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 72 5.3 Localized Maintenance and Repair Planning 80 6.11 Major Rehabilitation Planning		
3.1.1 Previous and/or Anticipated Airfield Pavement Construction 45 3.1.2 Estimated Pavement Age 47 3.1.3 Functional Use Classification 49 3.1.4 Pavement System Inventory Details 50 3.1.5 Pavement System Inventory Details 51 Chapter 4 – Airfield Pavement Condition 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 56 4.1.3 Section-Level Analysis 56 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.2 Branch-Level Observations 62 4.2.3 Forecasted Pavement Condition Forecast 64 4.3.4 Forecasted Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.3 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 72 5.3 Localized Maintenance and Repair Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.1.3 Alor Rehabilitation Planning 80 6.1.4 Major Rehabilitation Planning-Level Unit Co	3.1 Airfield Pavement Network Information	45
3.1.2 Estimated Pavement Age 47 3.1.3 Functional Use Classification 49 3.1.4 Pavement Surface Type 50 3.1.5 Pavement System Inventory Details 51 Chapter 4 – Airfield Pavement Condition 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 56 4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 56 4.1.3 Section-Level Analysis 56 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Ection-Level Pavement Condition Forecast 64 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabi		
3.1.3 Functional Use Classification 49 3.1.4 Pavement Surface Type 50 3.1.5 Pavement System Inventory Details 51 Chapter 4 – Airfield Pavement Condition 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 56 4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 58 4.2.5 Ummary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.2.3 Forecasted Pavement Condition Evaluation Results 62 4.3.1 Performance Models and Prediction Curves 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 80 6.1.1 Critical PCI 82 6.2.1 Major Rehabilitation Planning 80		
3.1.4 Pavement Surface Type. 50 3.1.5 Pavement System Inventory Details 51 Chapter 4 – Airfield Pavement Condition Index (Latest Inspection) 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 58 4.2 Summary of Pavement Condition Evaluation Results 62 4.2 Summary of Pavement Condition Evaluation Results 62 4.2 Summary of Pavement Condition S 64 4.3 Forecasted Pavement Condition Curves 64 4.3 Forecasted Pavement Condition Forecast 64 4.3.1 Performance Models and Prediction Curves 64 4.3.3 Excluse Pavement Condition Forecast 64 4.3.3 Excluse Pavement Condition Forecast 64 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning. 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1 Major Rehabilitation Planning 81.1 Critical PCI 82 <		
3.1.5 Pavement System Inventory Details 51 Chapter 4 – Airfield Pavement Condition 56 4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 56 4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 56 4.1.3 Section-Level Analysis 58 4.2 Stranch-Level Observations 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.4 Forecasted Pavement Condition Forecast 64 4.3.3 Particlevel Pavement Condition Forecast 64 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.2.1 Major Rehabilitation Planning 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 85		
4.1 Airfield Pavement Condition Index (Latest Inspection) 56 4.1.1 Network-Level Analysis 56 4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 58 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major R		
4.1.1 Network-Level Analysis 56 4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 58 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning. 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabil	Chapter 4 – Airfield Pavement Condition	56
4.1.2 Branch-Level Analysis 56 4.1.3 Section-Level Analysis 58 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2.1 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85	4.1 Airfield Pavement Condition Index (Latest Inspection)	56
4.1.3 Section-Level Analysis 58 4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.4 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.4 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 6.1 Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.2.2 Major Rehabilitation Planning-Level PCI 82 6.3 Major Rehabilitation Planning-Level Unit Cost	4.1.1 Network-Level Analysis	56
4.2 Summary of Pavement Condition Evaluation Results 62 4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3 Forecasted Pavement Conditions 64 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85	4.1.2 Branch-Level Analysis	
4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.1 Performance Models and Prediction Curves 64 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.4 Soction-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1 Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3 1 10-Year Unconstrained Budget Major Rehabilitation Needs 85	4.1.3 Section-Level Analysis	58
4.2.1 Network-Level Observations 62 4.2.2 Branch-Level Observations 62 4.3.1 Performance Models and Prediction Curves 64 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 64 4.3.4 Soction-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1 Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3 1 10-Year Unconstrained Budget Major Rehabilitation Needs 85	4.2 Summary of Pavement Condition Evaluation Results	62
4.2.2 Branch-Level Observations 62 4.3 Forecasted Pavement Conditions 64 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs <td< td=""><td>4.2.1 Network-Level Observations</td><td></td></td<>	4.2.1 Network-Level Observations	
4.3 Forecasted Pavement Conditions 64 4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 60 6.1 Major Rehabilitation Planning 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85		
4.3.1 Performance Models and Prediction Curves 64 4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 – Localized Maintenance and Repair Planning. 71 5.1 Localized Maintenance and Repair Planning. 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 73 5.3 Localized Maintenance and Repair Policy 74 5.3 Localized Maintenance and Repair Policy 75 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 – Major Rehabilitation Planning. 80 6.1 Major Rehabilitation 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 - Conclusion 90 </td <td></td> <td></td>		
4.3.2 Branch-Level Pavement Condition Forecast 64 4.3.3 Section-Level Pavement Condition Forecast 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 – Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 71 5.2 Localized Maintenance and Repair Policy 72 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 – Major Rehabilitation Planning 80 6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation		
4.3.3 Section-Level Pavement Condition Forecast. 66 4.3.4 Forecasted PCI Considerations 69 Chapter 5 - Localized Maintenance and Repair Planning 71 5.1 Localized Maintenance and Repair Planning 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 - Major Rehabilitation Planning 80 6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85		
4.3.4 Forecasted PCI Considerations 69 Chapter 5 – Localized Maintenance and Repair Planning. 71 5.1 Localized Maintenance and Repair 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 – Major Rehabilitation Planning 80 6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning 83 6.2.1 Major Rehabilitation Policy 83 6.2.1 Major Rehabilitation Policy 83 6.2.1 Major Rehabilitation Planning-Level PCI 82 6.3 Major Rehabilitation Planning-Level Unit Costs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 0 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90		
Chapter 5 – Localized Maintenance and Repair Planning. 71 5.1 Localized Maintenance and Repair 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 – Major Rehabilitation Planning 80 6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90		
5.1 Localized Maintenance and Repair 71 5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 – Major Rehabilitation Planning 80 6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Planning-Level Unit Costs 83 6.2.1 Major Rehabilitation Planning-Level Unit Costs 83 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	A Martin A	
5.2 Localized Maintenance and Repair Policy 72 5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 – Major Rehabilitation Planning 80 6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Policy 83 6.2.1 Major Rehabilitation Pavement Section Development 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	Chapter 5 – Localized Maintenance and Repair Planning	71
5.3 Localized Maintenance and Repair Analysis and Recommendations 76 Chapter 6 – Major Rehabilitation Planning 80 6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Policy 83 6.2.1 Major Rehabilitation Pavement Section Development 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	5.1 Localized Maintenance and Repair	71
Chapter 6 - Major Rehabilitation Planning.806.1 Major Rehabilitation806.1.1 Critical PCI826.1.2 FDOT Recommended Minimum Service-Level PCI826.2 Major Rehabilitation Policy836.2.1 Major Rehabilitation Pavement Section Development836.2.2 Major Rehabilitation Planning-Level Unit Costs856.3 Major Rehabilitation Needs856.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs85Chapter 7 - Conclusion907.1 Recommendations907.1.1 Continued PCI Survey Inspections90	5.2 Localized Maintenance and Repair Policy	72
6.1 Major Rehabilitation 80 6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Policy 83 6.2.1 Major Rehabilitation Pavement Section Development 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	5.3 Localized Maintenance and Repair Analysis and Recommendations	76
6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Policy 83 6.2.1 Major Rehabilitation Pavement Section Development 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	Chapter 6 – Major Rehabilitation Planning	80
6.1.1 Critical PCI 82 6.1.2 FDOT Recommended Minimum Service-Level PCI 82 6.2 Major Rehabilitation Policy 83 6.2.1 Major Rehabilitation Pavement Section Development 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	6.1 Major Rehabilitation	80
6.2 Major Rehabilitation Policy836.2.1 Major Rehabilitation Pavement Section Development836.2.2 Major Rehabilitation Planning-Level Unit Costs856.3 Major Rehabilitation Needs856.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs85Chapter 7 – Conclusion907.1 Recommendations907.1.1 Continued PCI Survey Inspections90	6.1.1 Critical PCI	
6.2.1 Major Rehabilitation Pavement Section Development. 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs. 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	6.1.2 FDOT Recommended Minimum Service-Level PCI	
6.2.1 Major Rehabilitation Pavement Section Development. 83 6.2.2 Major Rehabilitation Planning-Level Unit Costs. 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	6 2 Major Rehabilitation Policy	83
6.2.2 Major Rehabilitation Planning-Level Unit Costs 85 6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	6.2.1 Major Rehabilitation Pavement Section Development	83
6.3 Major Rehabilitation Needs 85 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90		
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs 85 Chapter 7 – Conclusion 90 7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90		
Chapter 7 – Conclusion		
7.1 Recommendations 90 7.1.1 Continued PCI Survey Inspections 90	6.3.1 TO-Year Unconstrained Budget Major Renabilitation Needs	
7.1.1 Continued PCI Survey Inspections90	Chapter 7 – Conclusion	90
7.1.1 Continued PCI Survey Inspections90	7.1 Recommendations	



7.1.3 Major Rehabilitation	90
7.1.4 Pavement Management System	
7.2 Supporting Documents	
001 – Airfield Pavement Network Definition Exhibit	91
002 – Airfield Pavement System Inventory Exhibit	91
003 – Airfield Pavement Condition Index Exhibit	91
004 – Airfield Pavement Major Rehabilitation Exhibit	91
Inspection Photograph Documentation	91
7.3 Conclusion	92



- Appendix A Airfield Pavement Analysis Tables
- Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
- Appendix C Technical Exhibits
- Appendix D Inspection Photograph Documentation
- Appendix E Inspection Distress Details



List of Figures

Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts
Figure 1.7.2 (a) Typical Pavement Condition Life Cycle25
Figure 1.7.2 (b) General Pavement Treatments by Condition Range
Figures 1.7.2 (c) Flexible Asphalt Concrete27
Figures 1.7.2 (d) Rigid Portland Cement Concrete27
Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit
Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit
Figure 3.1.2 Average Age of Pavements at Inspection48
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area
Figure 3.1.4 (a) Pavement Surface Type by Area (SF)50
Figure 3.1.4 (b) Pavement Surface Type by Area (%)
Figure 4.1.1 Latest Condition – Overall Network
Figure 4.1.2 (a) Latest Condition – Runway Pavements
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements
Figure 4.1.2 (c) Latest Condition – Apron Pavements
Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit
Figure 4.2.2 Pavement Condition Summary by Facility Use
Figure 4.3.2 (a) Forecasted Runway Pavement Performance
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance
Figure 4.3.2 (c) Forecasted Apron Pavement Performance
Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI80
Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI81
Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year
Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit



List of Tables

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level
Table E-2 Pavement Condition Index Forecast 2020-202913
Table E-3 Major Rehabilitation Planning 2020-2029 14
Table 2.2.1 Airfield Pavement Database Network Definition Terminology 32
Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields 37
Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete- Surfaced Airfields 38
Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete- Surfaced Airfields 38
Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields
Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete- Surfaced Airfields 40
Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete- Surfaced Airfields
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete41
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete
Table 2.6.4 Summary of Updates to ASTM D5340-12 43
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction
Table 3.1.5 Pavement System Inventory Details 52
Table 4.1.3 Latest Pavement Condition Index Summary 59
Table 4.3.3 Forecasted PCI 2020-2029
Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete
Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete
Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete75



Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete 75
Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level
Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level
Table 5.3 (c) Summary of Localized Maintenance 78
Table 6.1.2 FDOT Recommended Minimum Service-Level PCI 82
Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete 83
Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete 84
Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type
Table 6.3.1 10-Year Major Rehabilitation Needs 86



Executive Summary

Executive Summary

Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the documented procedures set forth by ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER[™] database system. •
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps. •
- Update airfield pavement performance models and pavement condition forecasting. •
- Identification of planning-level maintenance, repair, and major rehabilitation to address • pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.

Summary of Results

Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
тіх	RUNWAY 18-36	RUNWAY	6105	500,000	62	Fair
ТІХ	RUNWAY 18-36	RUNWAY	6110	250,000	57	Fair
ΤΙΧ	RUNWAY 18-36	RUNWAY	6125	100,000	62	Fair
ТІХ	RUNWAY 18-36	RUNWAY	6130	50,000	60	Fair
ΤΙΧ	RUNWAY 18-36	RUNWAY	6145	131,900	65	Fair
ΤΙΧ	RUNWAY 18-36	RUNWAY	6150	65,950	64	Fair
ΤΙΧ	RUNWAY 9-27	RUNWAY	6205	169,743	63	Fair
ΤΙΧ	RUNWAY 9-27	RUNWAY	6210	320,000	53	Poor
ΤΙΧ	TAXIWAY A	TAXIWAY	105	114,651	68	Fair
ΤΙΧ	TAXIWAY A	TAXIWAY	110	70,000	66	Fair
ΤΙΧ	TAXIWAY A	TAXIWAY	112	30,000	67	Fair
ТІХ	TAXIWAY A	TAXIWAY	115	50,000	67	Fair
ΤΙΧ	TAXIWAY A	TAXIWAY	120	90,638	65	Fair
ТІХ	TAXIWAY A2	TAXIWAY	125	35,137	65	Fair
тіх	TAXIWAY B	TAXIWAY	205	22,146	57	Fair
ΤΙΧ	TAXIWAY B	TAXIWAY	210	234,359	89	Good
ΤΙΧ	TAXIWAY C	TAXIWAY	305	46,879	68	Fair
ТІХ	TAXIWAY C	TAXIWAY	310	116,660	63	Fair
ΤΙΧ	TAXIWAY C	TAXIWAY	315	32,856	88	Good
ΤΙΧ	TAXIWAY D	TAXIWAY	404	26,461	65	Fair
ΤΙΧ	TAXIWAY D	TAXIWAY	408	7,500	65	Fair
ТІХ	TAXIWAY D	TAXIWAY	410	73,750	75	Satisfactory
ΤΙΧ	TAXIWAY E	TAXIWAY	505	32,371	72	Satisfactory
ΤΙΧ	TAXIWAY E	TAXIWAY	515	113,522	70	Fair
ТІХ	TAXIWAY E	TAXIWAY	525	8,165	94	Good
ΤΙΧ	TAXIWAY F	TAXIWAY	605	30,388	14	Serious
ТІХ	EAST APRON	APRON	4205	101,014	62	Fair
ТІХ	EAST APRON	APRON	4211	3,845	67	Fair
ΤΙΧ	EAST APRON	APRON	4214	52,187	56	Fair
ТІХ	EAST APRON	APRON	4215	82,925	45	Poor
ТІХ	EAST APRON	APRON	4216	48,836	82	Satisfactory
ТІХ	EAST APRON	APRON	4218	95,344	80	Satisfactory
ТІХ	EAST APRON	APRON	4219	8,237	56	Fair
ТІХ	EAST APRON	APRON	4220	8,168	83	Satisfactory

tewide Airfi nagement P	eld Pavement Airport Pavem rogram Evaluation Rep		Space Coast R Airport (TI	egional X)	10	FDO
Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
ΤΙΧ	EAST APRON	APRON	4221	5,405	71	Satisfactory
ΤΙΧ	EAST APRON	APRON	4225	8,700	69	Fair
ΤΙΧ	EAST APRON	APRON	4226	6,677	72	Satisfactory
ТІХ	EAST APRON	APRON	4227	6,560	89	Good
ΤΙΧ	EAST APRON	APRON	4228	11,100	89	Good
ΤΙΧ	EAST APRON	APRON	4229	16,315	88	Good
ΤΙΧ	EAST APRON	APRON	4230	9,576	77	Satisfactory
ΤΙΧ	EAST APRON	APRON	4232	9,960	79	Satisfactory
ΤΙΧ	EAST APRON	APRON	4235	93,090	99	Good
ΤΙΧ	EAST APRON	APRON	4240	7,020	91	Good
ΤΙΧ	EAST APRON	APRON	4241	8,553	91	Good
ТІХ	EAST APRON	APRON	4245	7,200	71	Satisfactory
ΤΙΧ	EAST APRON	APRON	4250	38,220	95	Good
ΤΙΧ	HELICOPTER APRON	APRON	4255	32,798	90	Good
ТІХ	HELICOPTER APRON	APRON	4260	364,740	97	Good
ТІХ	WEST APRON	APRON	4305	370,471	99	Good
ΤΙΧ	WEST APRON	APRON	4310	30,464	72	Satisfactory

Forecasted Pavement Condition Index 2020-2029

Table E-2 Pavement Condition Index Forecast 2020-2029

Network		Section	Last	Forecasted PCI								Forecasted							
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029						
тіх	AP E	4205	62	61	60	60	60	60	60	60	60	59	58						
ТІХ	AP E	4211	67	65	63	62	61	61	60	60	60	60	60						
ΤΙΧ	AP E	4214	56	54	51	48	44	40	36	32	28	26	25						
ΤΙΧ	AP E	4215	45	43	42	40	38	37	35	34	32	31	29						
ТІХ	AP E	4216	82	79	76	74	71	69	67	65	63	62	61						
ТІХ	AP E	4218	80	77	75	72	70	67	65	64	63	62	61						
ТІХ	AP E	4219	56	54	51	48	44	40	36	32	28	26	25						
тіх	AP E	4220	83	80	77	75	72	70	68	66	64	63	62						
ТІХ	AP E	4221	71	69	68	66	64	63	61	60	58	57	55						
ТІХ	AP E	4225	69	67	66	64	62	61	59	57	55	53	52						
ТІХ	AP E	4226	72	70	67	65	64	63	62	61	60	60	60						
ТІХ	AP E	4227	89	86	83	80	78	75	72	70	68	66	64						
тіх	AP E	4228	89	86	83	80	78	75	72	70	68	66	64						
ТІХ	AP E	4229	88	86	85	83	81	80	78	77	75	74	72						
ТІХ	AP E	4230	77	76	74	73	72	70	69	68	66	64	63						
ТІХ	AP E	4232	79	76	74	71	69	67	65	63	62	61	61						
тіх	AP E	4235	99	97	95	93	92	90	89	88	87	86	86						
тіх	AP E	4240	91	88	85	82	80	77	74	72	69	67	65						
тіх	AP E	4241	91	88	85	82	80	77	74	72	69	67	65						
тіх	AP E	4245	71	69	68	66	64	63	61	60	58	57	55						
тіх	AP E	4250	95	93	92	90	89	88	87	86	86	85	84						
тіх	AP HELI	4255	90	88	87	85	83	82	80	79	77	76	74						
тіх	AP HELI	4260	97	95	93	92	90	89	88	87	87	86	85						
ТІХ	AP W	4305	99	97	95	93	92	90	89	88	87	86	86						
тіх	AP W	4310	72	70	67	65	64	63	62	61	60	60	60						
тіх	RW 18-36	6105	62	59	57	56	55	54	54	54	53	52	51						
τιχ	RW 18-36	6110	57	55	54	54	54	54	52	52	51	51	50						
тіх	RW 18-36	6125	62	59	57	56	55	54	54	54	53	52	51						
ТІХ	RW 18-36	6130	60	58	56	55	54	54	54	53	52	52	51						
ТІХ	RW 18-36	6145	65	62	60	57	56	55	54	54	54	53	52						
ТІХ	RW 18-36	6150	64	61	59	57	55	54	54	54	54	52	52						
ТІХ	RW 9-27	6205	63	60	58	56	55	54	54	54	53	52	51						
ТІХ	RW 9-27	6210	53	52	51	51	50	50	49	48	48	47	47						
ТІХ	TW A	105	68	66	65	63	62	61	60	59	58	57	57						
ТІХ	TW A	110	66	64	63	62	61	60	59	58	57	56	56						

Statewide Airfield Pavement Airport Pavement **Management Program**

2019 **Evaluation Report**

Space Coast Regional Airport (TIX)



121

Network	Dranak ID	Section Last Forecasted PCI						Forecasted PCI							
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029		
ТІХ	TW A	112	67	65	64	63	61	60	59	58	58	57	56		
ΤΙΧ	TW A	115	67	65	64	63	61	60	59	58	58	57	56		
ТІХ	TW A	120	65	63	62	61	60	59	58	57	57	56	55		
ТІХ	TW A2	125	65	63	62	61	60	59	58	57	57	56	55		
ТІХ	TW B	205	57	56	55	55	54	53	53	52	52	51	51		
ΤΙΧ	TW B	210	89	86	84	82	79	77	75	73	71	69	68		
тіх	TW C	305	68	66	65	63	62	61	60	59	58	57	57		
ТІХ	TW C	310	63	62	60	59	58	58	57	56	55	55	54		
ТІХ	TW C	315	88	85	83	81	78	76	74	72	71	69	67		
тіх	TW D	404	65	63	62	61	60	59	58	57	57	56	55		
тіх	TW D	408	65	63	62	61	60	59	58	57	57	56	55		
ТІХ	TW D	410	75	73	71	69	68	66	65	63	62	61	60		
ТІХ	TW E	505	72	70	68	67	65	64	63	61	60	59	58		
ТІХ	TW E	515	70	68	67	65	64	62	61	60	59	58	57		
ТІХ	TW E	525	94	92	90	88	86	84	83	81	80	78	77		
тіх	TW F	605	14	10	4	0	0	0	0	0	0	0	0		

Major Rehabilitation Planning 2020-2029

Table E-3 Major Rehabilitation Planning 2020-2029


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ТІХ	AP E	4205	AAC	101,014	61	AC Restoration	\$ 1,112,000.00
2020	ΤΙΧ	AP E	4214	APC	52,187	54	AC Restoration	\$ 575,000.00
2020	ΤΙΧ	AP E	4215	AC	82,925	43	AC Restoration	\$ 1,070,000.00
2020	ΤΙΧ	AP E	4219	AAC	8,237	54	AC Restoration	\$ 91,000.00
2020	ΤΙΧ	RW 18-36	6105	AAC	500,000	59	AC Restoration	\$ 5,500,000.00
2020	ТІХ	RW 18-36	6110	AAC	250,000	55	AC Restoration	\$ 2,750,000.00
2020	ТІХ	RW 18-36	6125	AAC	100,000	59	AC Restoration	\$ 1,100,000.00
2020	ТІХ	RW 18-36	6130	AAC	50,000	58	AC Restoration	\$ 550,000.00
2020	ΤΙΧ	RW 18-36	6145	AAC	131,900	62	AC Restoration	\$ 1,451,000.00
2020	ТІХ	RW 18-36	6150	AAC	65,950	61	AC Restoration	\$ 726,000.00
2020	ΤΙΧ	RW 9-27	6205	AAC	169,743	60	AC Restoration	\$ 1,868,000.00
2020	ТІХ	RW 9-27	6210	AAC	320,000	52	AC Restoration	\$ 3,520,000.00
2020	ТІХ	TW A	110	AAC	70,000	64	AC Restoration	\$ 770,000.00
2020	ТІХ	TW A	120	AAC	90,638	63	AC Restoration	\$ 997,000.00
2020	ТІХ	TW A2	125	AAC	35,137	63	AC Restoration	\$ 387,000.00
2020	ТІХ	TW B	205	AAC	22,146	56	AC Restoration	\$ 244,000.00

Statewide Airfield Pavement Management Program		Airport Pavem Evaluation Rep		Space Coast Regional Airport (TIX)			Tel	FDC
Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ТІХ	TW C	310	AAC	116,660	62	AC Restoration	\$ 1,284,000.00
2020	ТІХ	TW D	404	AAC	26,461	63	AC Restoration	\$ 292,000.00
2020	ΤΙΧ	TW D	408	AAC	7,500	63	AC Restoration	\$ 83,000.00
2020	ТІХ	TW F	605	AAC	30,388	10	AC Reconstruction	\$ 426,000.00
2021	ТІХ	AP E	4211	AAC	3,845	63	AC Restoration	\$ 43,000.00
2021	ТІХ	TW A	112	AAC	30,000	64	AC Restoration	\$ 330,000.00
2021	ΤΙΧ	TW A	115	AAC	50,000	64	AC Restoration	\$ 550,000.00
2022	ТІХ	AP E	4225	PCC	8,700	64	PCC Restoration	\$ 148,000.00
2022	ΤΙΧ	TW A	105	AAC	114,651	63	AC Restoration	\$ 1,262,000.00
2022	ТІХ	TW C	305	AAC	46,879	63	AC Restoration	\$ 516,000.00
2023	ТІХ	AP E	4221	AC	5,405	64	AC Restoration	\$ 60,000.00
2023	ТІХ	AP E	4226	AAC	6,677	64	AC Restoration	\$ 74,000.00
2023	ΤΙΧ	AP E	4245	AC	7,200	64	AC Restoration	\$ 80,000.00
2023	ТІХ	AP W	4310	AAC	30,464	64	AC Restoration	\$ 336,000.00
2023	ΤΙΧ	TW E	515	AAC	113,522	64	AC Restoration	\$ 1,249,000.00
2024	ТІХ	TW E	505	AAC	32,371	64	AC Restoration	\$ 357,000.00
2026	ТІХ	AP E	4218	AAC	95,344	64	AC Restoration	\$ 1,049,000.00
2026	ТІХ	AP E	4232	AAC	9,960	63	AC Restoration	\$ 110,000.00
2026	ТІХ	TW D	410	AAC	73,750	63	AC Restoration	\$ 812,000.00
2027	ТІХ	AP E	4216	AAC	48,836	63	AC Restoration	\$ 538,000.00
2027	ΤΙΧ	AP E	4220	AAC	8,168	64	AC Restoration	\$ 90,000.00
2028	ТІХ	AP E	4230	PCC	9,576	64	PCC Restoration	\$ 163,000.00
2029	ТІХ	AP E	4227	AAC	6,560	64	AC Restoration	\$ 73,000.00
2029	ТІХ	AP E	4228	AAC	11,100	64	AC Restoration	\$ 123,000.00

*All planning cost values have been rounded to the nearest thousand-dollar.

FDOT

Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029



Summary of Space Coast Regional Airport

Space Coast Regional Airport was inspected in March of 2019 – the overall weighted PCI value was 72, a condition rating of Satisfactory. The results of the maintenance, repair, and major rehabilitation analysis identified \$1,503,090 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$32,759,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$24,796,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.



Chapter 1

Chapter 1 – Introduction

1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating publicuse airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.

Space Coast Regional Airport (TIX)






Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts

In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.

1.3 Organization

1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."** Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM *D5340-12* "*Standard Test Method for Airport Pavement Condition Index Surveys,*" evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular *150/5380-7B* "*Airport Pavement Management Program (PMP).*"

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- Research and evaluation of existing record documentation was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- An update to the existing Network Definition Map was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- A functional pavement evaluation with PCI Survey inspections was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- Condition Analysis was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- Maintenance, Repair, and Rehabilitation Planning was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.



1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.

2019

Space Coast Regional Airport (TIX)



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER[™] (currently known as PAVER[™]) was selected for implementation of the system update. MicroPAVER[™] was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER[™] system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER[™] system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (http://www.dot.state.fl.us/aviation/pavement.shtm) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER[™] and FieldInspector[™] with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys." The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.

1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management Program (PMP)"). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications."

1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC150/5380-7B "Airport Pavement Management Program (PMP)" an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:


1.7.2 Program Components


- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data



- F. Pavement Performance Modeling for the Prediction/Forecast of PCI
- G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements' past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and costeffective manner. Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, which is based on the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.






*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).

Figure 1.7.2 (b) General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall

FDOT

composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.





Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7.2 (a) and 1.7.2 (b)**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7.2 (c) and 1.7.2 (d), depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.


2019

Space Coast Regional Airport (TIX)



Figures 1.7.2 (c) Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabiliation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.



	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabiliation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."
- FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program."
- FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements."
- FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation."
- Department of the Air Force, Air Force Civil Engineer Center "Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements."
- Unified Facilities Criteria (UFC) 3-260-16FA 16 "Airfield Pavement Condition Survey Procedures Pavements."
- Unified Facilities Criteria (UFC) 3-260-03 "Airfield Pavement Evaluation."
- Pavement Management for Airports, Roads, and Parking Lots 2nd Edition, M.Y. Shahin.



Chapter 2



Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B** "Airport Pavement Management Program (PMP)."

2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER[™] (formerly MicroPAVER[™]); the current update has maintained the use of the PAVER[™] 7.0 version of the software. The PAVER[™] software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER[™] can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER[™] inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER[™] database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER[™] version 6.5 to a version 7.0.

2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.



A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a "parent" pavement network.

Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (± 8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ($\pm 2,000$ ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	"Tallahassee International Airport – Airfield Pavements"
Branch Name	Commonly defined asset name as established by Airport and by use	"Runway 18-36"
Branch ID	Codified shorthand name for commonly defined asset established for database identification	"RW 18-36" RW, Branch Use, "Runway" 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following: Pavement Composition Construction Work History Aircraft Traffic Condition Records	"6105"
Sample Unit	A numeric identification of an area of pavement (5,000±2,000 SF of AC or 20±8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	"300"

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

2.3 Airfield Pavement Structure

2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.



Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 8 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 8 inches in thickness.

Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.

2.4 Airfield Pavement Work History

2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

- 1. Location and Limits of Work.
- 2. Types and Severity of Distresses Repaired.
- 3. Type of Work.
- 4. Cost of Work.
- 5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.6 Airfield Pavement Condition Index (PCI) Survey

2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B** "Airport Pavement Management **Program (PMP)**," the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method 2019

Space Coast Regional Airport (TIX)



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.



2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms			
Alligator Cracking	Load / Fatigue			
Bleeding	Construction Quality/ Mix Design			
Block Cracking	Climate / Age			
Corrugation	Load / Construction Quality			
Depression	Load / Subsurface			
Jet Blast	Aircraft			
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load			
Longitudinal/Transverse Cracking	Climate / Construction Quality			
Oil Spillage	Aircraft / Vehicle			
Patching	Utility / Pavement Repair / Age			
Polished Aggregate	Repeated Traffic Loading			
Raveling	Climate / Age			
Rutting	Load / Fatigue			
Shoving	PCC Pavement Growth / Movement			
Slippage Cracking	Load / Pavement Bond / Mix Design			
Swelling	Climate / Subsurface			
Weathering	Climate / Age			



Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-SurfacedAirfields

Classification by Possible Causes								
Load	Climate / Durability	Moisture / Drainage	Others					
 Alligator Cracking Corrugation Depression Patching of Load-based distress Polished Aggregate Rutting Slippage Cracking 	 Bleeding Block Cracking Joint Reflection Cracking L/T Cracking Patching of climate / durability-caused distresses Shoving from PCC Raveling Weathering Swelling 	 Alligator Cracking Depression Patching of moisture / drainage caused distress Swelling Raveling Weathering 	 Oil Spillage Jet Blast Erosion Polished Aggregate 					

Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-SurfacedAirfields

Classification by Possible Effects									
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements						
 Corrugation Depression Rutting Shoving of asphalt pavement Swelling Raveling Weathering 	 Bleeding Depression Polished Aggregate Rutting 	 Block Cracking Joint Reflection Cracking L/T Cracking Slippage Cracking 	All Distresses						



Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms				
Blowup	Climate / ASR				
Corner Break	Load Repetition / Curling Stresses				
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses				
Durability Cracking	Freeze-Thaw Cycling				
Joint Seal Damage	Material Deterioration / Construction Quality / Age				
Small Patch	Pavement Repair				
Large Patch/Utility Cut	Utility / Pavement Repair				
Popout	Freeze-Thaw Cycling / ASR / Material Quality				
Pumping	Load Repetition / Poor Joint Sealant				
Scaling	Construction Quality / Freeze-Thaw Cycling				
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer				
Shattered Slab	Overloading				
Shrinkage Cracking	Construction Quality / Climate				
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars				
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars				
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction				



Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-
Surfaced Airfields

Classification by Possible Causes								
Load	Climate / Durability	Moisture / Drainage	Others					
 Corner Break Shattered Slab L/T/D Cracking Pumping Patching of Load- associated distress Spalling 	 Blowup "D" Cracking Joint Seal Damage Popouts Scaling Patch of Climate/Durability- associated distress Shrinkage Cracking Spalling L/T/D Cracking 	 Corner Break Shattered Slab Pumping Patching of Moisture/Drainage- associated distress 	Settlement / Faulting					

Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-
Surfaced Airfields

	Classification by Possible Effects									
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements							
 Blowup Corner Break L/T/D Cracking Shattered Slab Settlement / Faulting Spalling 	 Settlement / Faulting Spalling 	 Corner Break L/T/D Cracking "D" Cracking Joint Seal Damage Shattered Slab Popouts Scaling 	All distresses							



2.6.3 PCI Survey Inspection Procedures

Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total	Sample Units to Inspect				
Sample Units in Section	Runways	Taxiways, Aprons, and Others			
1 - 4	1	1			
5 - 10	2	1			
11 - 15	3	2			
16 - 30	5	3			
31 - 40	7	4			
41 - 50	8	5			
51 or more	20% but ≤20	10% but ≤10			

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total	Sample Units to Inspect				
Sample Units in Section	Runways	Taxiways, Aprons, and Others			
1 - 3	1	1			
4 - 6	2	1			
7 - 10	3	2			
11 - 15	4	2			
16 - 20	5	3			
21 - 30	7	3			
31 - 40	8	4			
41 - 50	10	5			
51 or more	20% but ≤20	10% but ≤10			



2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering." Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling," the PCI deduction is not as high as the former "Weathering and Raveling." Therefore, areas identified only as "(57) Weathering" based on current ASTM standards, which were previously identified as "(52) Weathering and Raveling," may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

Rigid Portland Cement Concrete Pavement Distress Updates

The previous methodology defined "(70) Scaling" as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included Alkali-Silica Reaction, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as "(76) Alkali-Silica Reaction / ASR." As a result, the previous "(70) Scaling" numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded "(70) Scaling," and currently do not exhibit "(76) Alkali-Silica Reactivity / ASR" may potentially see an increase in PCI. Additionally, "(73) Shrinkage Cracks" has been redefined as "(73) Shrinkage Cracking". Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage can be caused by both atmospheric conditions and construction. Plastic shrinkage caused by atmospheric conditions develops when there is rapid loss of water in the surface of recently placed pavement. High winds or low humidity are contributing factors to evaporation. These shrinkage cracks can appear as a series of parallel cracks, usually 1 to 3 feet apart and do not extend very deep into the pavement's surface. Plastic shrinkage caused by construction can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/ APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Crazing - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Crazing - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Crazing - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Crazing' may now be identified as 'Shrinkage Cracking'

Statewide Airfield Pavement Management Program



Chapter 3

Space Coast Regional Airport (TIX)



Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1 (a)** and **Figure 3.1.1 (b)** provides an inset view of the 2019 Airfield Pavement Network Definition Exhibit and the 2019 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.


Year	General Work Description						
2013	TW B, TW C - Mill and Overlay: 1.5" Mill and Overlay						
	AP E - Mill and Overlay: Variable Depth						
2014	AP W - New Construction: 14" P-501, 6" P-211, 20" P-152						
2014	AP W - Mill and Overlay						
	TW E - New Construction						
2045	AP E - New Construction: 14" P-501, 6" P-211, Compacted Sand Subgrade						
2015	AP E - Mill and Overlay						

Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction


The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.








The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.







The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections at the time of the PCI survey inspection. Age is determined to be the number of years since any major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.





The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.

Statewide Airfield Pavement
Management ProgramAirport Pavement
Evaluation Report2019



3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.




Figure 3.1.3 Airfield Pavement Functional Classification Use by Area



3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.





Figure 3.1.4 (a) Pavement Surface Type by Area (SF)







3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.

Statewide Airfield Pavement
Management ProgramAirport Pavement
Evaluation Report

ment 2019



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ΤΙΧ	EAST APRON	AP E	APRON	4205	784	188	101,014	AAC	1/1/2008
TIX	EAST APRON	AP E	APRON	4211	100	38	3,845	AAC	6/1/2002
ΤΙΧ	EAST APRON	AP E	APRON	4214	1,100	35	52,187	APC	6/1/2002
ΤΙΧ	EAST APRON	AP E	APRON	4215	300	150	82,925	AC	1/1/1971
ΤΙΧ	EAST APRON	AP E	APRON	4216	300	150	48,836	AAC	1/1/2008
ТІХ	EAST APRON	AP E	APRON	4218	525	137	95,344	AAC	1/1/2008
ΤΙΧ	EAST APRON	AP E	APRON	4219	55	151	8,237	AAC	1/1/2015
ТІХ	EAST APRON	AP E	APRON	4220	300	45	8,168	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4221	200	25	5,405	AC	1/1/2008
ТІХ	EAST APRON	AP E	APRON	4225	400	20	8,700	PCC	1/1/1991
ΤΙΧ	EAST APRON	AP E	APRON	4226	325	40	6,677	AAC	1/1/2014
ΤΙΧ	EAST APRON	AP E	APRON	4227	325	40	6,560	AAC	1/1/2014
ΤΙΧ	EAST APRON	AP E	APRON	4228	400	30	11,100	AAC	1/1/2014
TIX	EAST APRON	AP E	APRON	4229	820	20	16,315	AC	1/1/2012
ΤΙΧ	EAST APRON	AP E	APRON	4230	400	20	9,576	PCC	1/1/1991
ΤΙΧ	EAST APRON	AP E	APRON	4232	1,000	162	9,960	AAC	1/1/2014
ΤΙΧ	EAST APRON	AP E	APRON	4235	495	178	93,090	PCC	1/1/2015
TIX	EAST APRON	AP E	APRON	4240	250	30	7,020	AAC	1/1/2014
ΤΙΧ	EAST APRON	AP E	APRON	4241	350	25	8,553	AAC	1/1/2014
ΤΙΧ	EAST APRON	AP E	APRON	4245	350	20	7,200	AC	1/1/2003
ΤΙΧ	EAST APRON	AP E	APRON	4250	190	200	38,220	PCC	1/1/2011
ΤΙΧ	HELICOPTER APRON	AP HELI	APRON	4255	475	70	32,798	AC	1/1/2012
ΤΙΧ	HELICOPTER APRON	AP HELI	APRON	4260	744	510	364,740	PCC	1/1/2012
ΤΙΧ	WEST APRON	AP W	APRON	4305	1,600	500	370,471	PCC	1/1/2014
ΤΙΧ	WEST APRON	AP W	APRON	4310	68	400	30,464	AAC	1/1/2014

Statewide Air Management	field Pavement Airport Paver Program Evaluation R					oast Regional ort (TIX)			FDOT
Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ΤΙΧ	RUNWAY 18-36	RW 18-36	RUNWAY	6105	5,000	100	500,000	AAC	6/1/2002
ТІХ	RUNWAY 18-36	RW 18-36	RUNWAY	6110	10,000	25	250,000	AAC	6/1/2002
ТІХ	RUNWAY 18-36	RW 18-36	RUNWAY	6125	1,000	100	100,000	AAC	6/1/2002
ΤΙΧ	RUNWAY 18-36	RW 18-36	RUNWAY	6130	2,000	25	50,000	AAC	6/1/2002
ΤΙΧ	RUNWAY 18-36	RW 18-36	RUNWAY	6145	1,319	100	131,900	AAC	6/1/2002
ΤΙΧ	RUNWAY 18-36	RW 18-36	RUNWAY	6150	2,600	25	65,950	AAC	6/1/2002
ΤΙΧ	RUNWAY 9-27	RW 9-27	RUNWAY	6205	1,650	100	169,743	AAC	1/1/1998
ΤΙΧ	RUNWAY 9-27	RW 9-27	RUNWAY	6210	3,200	100	320,000	AAC	1/1/1998
ΤΙΧ	TAXIWAY A	TW A	TAXIWAY	105	2,200	50	114,651	AAC	6/1/2002
ΤΙΧ	TAXIWAY A	TW A	TAXIWAY	110	1,400	50	70,000	AAC	6/1/2002
ΤΙΧ	TAXIWAY A	TW A	TAXIWAY	112	600	50	30,000	AAC	6/1/2002
ΤΙΧ	TAXIWAY A	TW A	TAXIWAY	115	1,000	50	50,000	AAC	6/1/2002
ΤΙΧ	TAXIWAY A	TW A	TAXIWAY	120	1,800	50	90,638	AAC	6/1/2002
ΤΙΧ	TAXIWAY A2	TW A2	TAXIWAY	125	600	500	35,137	AAC	6/1/2002
ТІХ	TAXIWAY B	TW B	TAXIWAY	205	400	50	22,146	AAC	6/1/2002
ΤΙΧ	TAXIWAY B	TW B	TAXIWAY	210	4,600	50	234,359	AAC	1/1/2013
ΤΙΧ	TAXIWAY C	TW C	TAXIWAY	305	700	65	46,879	AAC	1/1/2004
ТІХ	TAXIWAY C	TW C	TAXIWAY	310	2,300	50	116,660	AAC	1/1/1986
ТІХ	TAXIWAY C	TW C	TAXIWAY	315	600	50	32,856	AAC	1/1/2013
ТІХ	TAXIWAY D	TW D	TAXIWAY	404	400	50	26,461	AAC	1/1/2000
ΤΙΧ	TAXIWAY D	TW D	TAXIWAY	408	150	50	7,500	AAC	1/1/2000
ТІХ	TAXIWAY D	TW D	TAXIWAY	410	1,450	50	73,750	AAC	1/1/2000
TIX	TAXIWAY E	TW E	TAXIWAY	505	600	50	32,371	AAC	1/1/1998
ТІХ	TAXIWAY E	TW E	TAXIWAY	515	2,640	50	113,522	AAC	1/1/2003
TIX	TAXIWAY E	TW E	TAXIWAY	525	100	85	8,165	AC	1/1/2014
ΤΙΧ	TAXIWAY F	TW F	TAXIWAY	605	580	50	30,388	AAC	1/1/1998



2019





PAGE INTENTIONALLY LEFT BLANK

Statewide Airfield Pavement Management Program



Chapter 4



Chapter 4 – Airfield Pavement Condition

The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement rehabilitation.

4.1 Airfield Pavement Condition Index (Latest Inspection)

4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.




Figure 4.1.1 Latest Condition – Overall Network

4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (c)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.










Figure 4.1.2 (b) Latest Condition – Taxiway Pavements









4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement. **Appendix C Technical Exhibits** provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
ТІХ	AP E	EAST APRON	APRON	4205	101,014	AAC	62	Fair	98%	0%	2%	3	20
ТІХ	AP E	EAST APRON	APRON	4211	3,845	AAC	67	Fair	100%	0%	0%	1	1
ТІХ	AP E	EAST APRON	APRON	4214	52,187	APC	56	Fair	100%	0%	0%	2	13
ТІХ	AP E	EAST APRON	APRON	4215	82,925	AC	45	Poor	81%	0%	19%	3	19
ТІХ	AP E	EAST APRON	APRON	4216	48,836	AAC	82	Satisfactory	100%	0%	0%	1	9
ТІХ	AP E	EAST APRON	APRON	4218	95,344	AAC	80	Satisfactory	100%	0%	0%	3	18
ТІХ	AP E	EAST APRON	APRON	4219	8,237	AAC	56	Fair	100%	0%	0%	1	2
ТІХ	AP E	EAST APRON	APRON	4220	8,168	AAC	83	Satisfactory	100%	0%	0%	1	2
ТІХ	AP E	EAST APRON	APRON	4221	5,405	AC	71	Satisfactory	100%	0%	0%	1	1
ТІХ	AP E	EAST APRON	APRON	4225	8,700	PCC	69	Fair	0%	85%	15%	1	2
ТІХ	AP E	EAST APRON	APRON	4226	6,677	AAC	72	Satisfactory	100%	0%	0%	1	2
ТІХ	AP E	EAST APRON	APRON	4227	6,560	AAC	89	Good	100%	0%	0%	1	2
ТІХ	AP E	EAST APRON	APRON	4228	11,100	AAC	89	Good	100%	0%	0%	1	3
ТІХ	AP E	EAST APRON	APRON	4229	16,315	AC	88	Good	100%	0%	0%	1	3
ТІХ	AP E	EAST APRON	APRON	4230	9,576	PCC	77	Satisfactory	0%	80%	20%	1	5
ТІХ	AP E	EAST APRON	APRON	4232	9,960	AAC	79	Satisfactory	100%	0%	0%	1	3
ТІХ	AP E	EAST APRON	APRON	4235	93,090	PCC	99	Good	0%	0%	100%	3	22
ТІХ	AP E	EAST APRON	APRON	4240	7,020	AAC	91	Good	100%	0%	0%	1	2
ТІХ	AP E	EAST APRON	APRON	4241	8,553	AAC	91	Good	100%	0%	0%	1	3
ТІХ	AP E	EAST APRON	APRON	4245	7,200	AC	71	Satisfactory	100%	0%	0%	1	2
ТІХ	AP E	EAST APRON	APRON	4250	38,220	PCC	95	Good	0%	0%	100%	2	12
ТІХ	AP HELI	HELICOPTER APRON	APRON	4255	32,798	AC	90	Good	100%	0%	0%	1	5
ТІХ	AP HELI	HELICOPTER APRON	APRON	4260	364,740	PCC	97	Good	0%	0%	100%	10	97
ТІХ	AP W	WEST APRON	APRON	4305	370,471	PCC	99	Good	0%	0%	100%	9	88
ТІХ	AP W	WEST APRON	APRON	4310	30,464	AAC	72	Satisfactory	100%	0%	0%	1	9
ТІХ	RW 18-36	RUNWAY 18-36	RUNWAY	6105	500,000	AAC	62	Fair	99%	0%	1%	20	100
ТІХ	RW 18-36	RUNWAY 18-36	RUNWAY	6110	250,000	AAC	57	Fair	98%	0%	2%	10	50
ТІХ	RW 18-36	RUNWAY 18-36	RUNWAY	6125	100,000	AAC	62	Fair	98%	0%	2%	5	20
ТІХ	RW 18-36	RUNWAY 18-36	RUNWAY	6130	50,000	AAC	60	Fair	97%	0%	3%	2	10
ТІХ	RW 18-36	RUNWAY 18-36	RUNWAY	6145	131,900	AAC	65	Fair	97%	0%	3%	5	26
ТІХ	RW 18-36	RUNWAY 18-36	RUNWAY	6150	65,950	AAC	64	Fair	98%	0%	2%	3	14
ТІХ	RW 9-27	RUNWAY 9-27	RUNWAY	6205	169,743	AAC	63	Fair	98%	0%	2%	7	34
ТІХ	RW 9-27	RUNWAY 9-27	RUNWAY	6210	320,000	AAC	53	Poor	74%	0%	26%	13	64
ТІХ	TW A	TAXIWAY A	TAXIWAY	105	114,651	AAC	68	Fair	96%	0%	4%	4	22
ТІХ	TW A	TAXIWAY A	TAXIWAY	110	70,000	AAC	66	Fair	100%	0%	0%	3	14
ТІХ	TW A	TAXIWAY A	TAXIWAY	112	30,000	AAC	67	Fair	100%	0%	0%	2	6
ТІХ	TW A	TAXIWAY A	TAXIWAY	115	50,000	AAC	67	Fair	98%	0%	2%	2	10

Table 4.1.3 Latest Pavement Condition Index Summary



11

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
ТІХ	TW A	TAXIWAY A	TAXIWAY	120	90,638	AAC	65	Fair	96%	0%	4%	3	17
ТІХ	TW A2	TAXIWAY A2	TAXIWAY	125	35,137	AAC	65	Fair	97%	0%	3%	2	7
ТІХ	TW B	TAXIWAY B	TAXIWAY	205	22,146	AAC	57	Fair	100%	0%	0%	1	4
ТІХ	TW B	TAXIWAY B	TAXIWAY	210	234,359	AAC	89	Good	91%	0%	9%	7	47
ТІХ	TW C	TAXIWAY C	TAXIWAY	305	46,879	AAC	68	Fair	96%	0%	4%	2	9
ТІХ	TW C	TAXIWAY C	TAXIWAY	310	116,660	AAC	63	Fair	100%	0%	0%	4	24
ТІХ	TW C	TAXIWAY C	TAXIWAY	315	32,856	AAC	88	Good	92%	0%	8%	2	7
ТІХ	TW D	TAXIWAY D	TAXIWAY	404	26,461	AAC	65	Fair	100%	0%	0%	1	5
ТІХ	TW D	TAXIWAY D	TAXIWAY	408	7,500	AAC	65	Fair	100%	0%	0%	2	2
ТІХ	TW D	TAXIWAY D	TAXIWAY	410	73,750	AAC	75	Satisfactory	100%	0%	0%	3	15
ТІХ	TW E	TAXIWAY E	TAXIWAY	505	32,371	AAC	72	Satisfactory	100%	0%	0%	2	6
ТІХ	TW E	TAXIWAY E	TAXIWAY	515	113,522	AAC	70	Fair	97%	0%	3%	5	27
ТІХ	TW E	TAXIWAY E	TAXIWAY	525	8,165	AC	94	Good	100%	0%	0%	1	2
ТІХ	TW F	TAXIWAY F	TAXIWAY	605	30,388	AAC	14	Serious	73%	27%	0%	2	6






121

Space Coast Regional Airport (TIX) FDOT

Figure 4.1.3 is an inset view of the 2019 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits.**







4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The field PCI Survey performed at Space Coast Regional Airport (TIX) was completed in March 2019. The resulting overall area-weighted average PCI value was 72 representing a condition rating of Satisfactory. Space Coast Regional Airport is serviced by two runways; Runway 9-27 is 100-ft wide and 5,000-ft long and Runway 18-36 is 150-ft wide and 7,319-ft long.

Based on the FAA 5010 Report as of 09/12/2019 the Airport has reported 87,332 operations for 12 months ending 12/31/2018.

4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

Runway 18-36

Runway 18-36 consists of 6 sections constructed of AAC. The last construction year for Runway 18-36 was 2002. The area-weighted average PCI for Runway 18-36 is 61 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Runway 18-36 consist of Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, and Weathering.

Runway 9-27

Runway 9-27 consists of 2 sections constructed of AAC. The last construction year for Runway 9-27 was 1998. The area-weighted average PCI for Runway 9-27 is 56 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Runway 9-27 consist of Block Cracking, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Taxiway A

Taxiway A consists of 5 sections constructed of AAC. The last construction year for Taxiway A was 2002. The area-weighted average PCI for Taxiway A is 66 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway A consist of Block Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, and Weathering.

Taxiway C

Taxiway C consists of 3 sections constructed of AAC. The last construction years range from 1986 to 2013. The area-weighted average PCI for Taxiway C is 68 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway C consist of Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, and Weathering.



Taxiway F

Taxiway F consists of 1 section constructed of AAC. The last construction year for Taxiway F was 1998. The area-weighted average PCI for Taxiway F is 14 representing a Serious condition rating. The pavement distresses observed were related to Climate and Load distress classifications. Distresses observed on Taxiway F consist of Alligator Cracking, Block Cracking, Patching, and Raveling.

East Apron

The East Apron consists of 21 sections constructed of AC, AAC, APC, and PCC. The last construction years range from 1971 to 2015. The area-weighted average PCI for East Apron is 74 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on East Apron consist of Block Cracking, Joint Reflection Cracking, Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, Weathering, Linear Cracking, Small Patch, Faulting, Shattered Slab, and Shrinkage Cracking.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Area-Weighted Average PCI	Condition Rating
Runway	59	Fair
Taxiway	71	Satisfactory
Apron	86	Good


4.3 Forecasted Pavement Conditions

4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to developed forecasted PCI values based on historic trends and statistical models.

4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2020 through January 2029.













Figure 4.3.2 (c) Forecasted Apron Pavement Performance





4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.

Space Coast Regional Airport (TIX)



141

Statewide Airfield Pavement
Management ProgramAirport Pavement
Evaluation Report

2019

Table 4.3.3 Forecasted PCI 2020-2029

Network	Branch ID	Section	Last PCI	Forecasted PCI											
ID	Branch ID	ID	Lasirui	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029		
ΤΙΧ	AP E	4205	62	61	60	60	60	60	60	60	60	59	58		
ТІХ	AP E	4211	67	65	63	62	61	61	60	60	60	60	60		
ΤΙΧ	AP E	4214	56	54	51	48	44	40	36	32	28	26	25		
ТІХ	AP E	4215	45	43	42	40	38	37	35	34	32	31	29		
ΤΙΧ	AP E	4216	82	79	76	74	71	69	67	65	63	62	61		
ТІХ	AP E	4218	80	77	75	72	70	67	65	64	63	62	61		
ΤΙΧ	AP E	4219	56	54	51	48	44	40	36	32	28	26	25		
ТІХ	AP E	4220	83	80	77	75	72	70	68	66	64	63	62		
ΤΙΧ	AP E	4221	71	69	68	66	64	63	61	60	58	57	55		
ТІХ	AP E	4225	69	67	66	64	62	61	59	57	55	53	52		
ΤΙΧ	AP E	4226	72	70	67	65	64	63	62	61	60	60	60		
ΤΙΧ	AP E	4227	89	86	83	80	78	75	72	70	68	66	64		
ΤΙΧ	AP E	4228	89	86	83	80	78	75	72	70	68	66	64		
ΤΙΧ	AP E	4229	88	86	85	83	81	80	78	77	75	74	72		
ΤΙΧ	AP E	4230	77	76	74	73	72	70	69	68	66	64	63		
ТІХ	AP E	4232	79	76	74	71	69	67	65	63	62	61	61		
ΤΙΧ	AP E	4235	99	97	95	93	92	90	89	88	87	86	86		
ТІХ	AP E	4240	91	88	85	82	80	77	74	72	69	67	65		
ТІХ	AP E	4241	91	88	85	82	80	77	74	72	69	67	65		
ТІХ	AP E	4245	71	69	68	66	64	63	61	60	58	57	55		
ΤΙΧ	AP E	4250	95	93	92	90	89	88	87	86	86	85	84		
ТІХ	AP HELI	4255	90	88	87	85	83	82	80	79	77	76	74		
ΤΙΧ	AP HELI	4260	97	95	93	92	90	89	88	87	87	86	85		
ТІХ	AP W	4305	99	97	95	93	92	90	89	88	87	86	86		
ΤΙΧ	AP W	4310	72	70	67	65	64	63	62	61	60	60	60		

Statewide Airfield Pavement Management Program		Airport Pavemo Evaluation Rep							Coast Region rport (TIX)	al			FDOT
Network	Branch ID	Section	Last PCI		Forecasted PCI								
ID		ID		2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ТІХ	RW 18-36	6105	62	59	57	56	55	54	54	54	53	52	51
ΤΙΧ	RW 18-36	6110	57	55	54	54	54	54	52	52	51	51	50
ΤΙΧ	RW 18-36	6125	62	59	57	56	55	54	54	54	53	52	51
ТІХ	RW 18-36	6130	60	58	56	55	54	54	54	53	52	52	51
ΤΙΧ	RW 18-36	6145	65	62	60	57	56	55	54	54	54	53	52
ТІХ	RW 18-36	6150	64	61	59	57	55	54	54	54	54	52	52
ТІХ	RW 9-27	6205	63	60	58	56	55	54	54	54	53	52	51
ТІХ	RW 9-27	6210	53	52	51	51	50	50	49	48	48	47	47
ТІХ	TW A	105	68	66	65	63	62	61	60	59	58	57	57
ТІХ	TW A	110	66	64	63	62	61	60	59	58	57	56	56
ТІХ	TW A	112	67	65	64	63	61	60	59	58	58	57	56
ТІХ	TW A	115	67	65	64	63	61	60	59	58	58	57	56
ТІХ	TW A	120	65	63	62	61	60	59	58	57	57	56	55
ТІХ	TW A2	125	65	63	62	61	60	59	58	57	57	56	55
ТІХ	TW B	205	57	56	55	55	54	53	53	52	52	51	51
ТІХ	TW B	210	89	86	84	82	79	77	75	73	71	69	68
ТІХ	TW C	305	68	66	65	63	62	61	60	59	58	57	57
ТІХ	TW C	310	63	62	60	59	58	58	57	56	55	55	54
ТІХ	TW C	315	88	85	83	81	78	76	74	72	71	69	67
ТІХ	TW D	404	65	63	62	61	60	59	58	57	57	56	55
ТІХ	TW D	408	65	63	62	61	60	59	58	57	57	56	55
ТІХ	TW D	410	75	73	71	69	68	66	65	63	62	61	60
ТІХ	TW E	505	72	70	68	67	65	64	63	61	60	59	58
ТІХ	TW E	515	70	68	67	65	64	62	61	60	59	58	57
ТІХ	TW E	525	94	92	90	88	86	84	83	81	80	78	77
тіх	TW F	605	14	10	4	0	0	0	0	0	0	0	0



4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA *AC 150/5320-6F Airport Pavement Design and Evaluation* and *AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements* to determine structural and/or functional conditions at the time of project.

Statewide Airfield Pavement Management Program



Chapter 5



Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- > Localized Maintenance and Repair includes patching and crack sealing.
- > Global Treatments include surface seals and rejuvenators for flexible pavements.
- Major Rehabilitation includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distressed pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety ("stopgap") measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.



5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2 (a)** and **Table 5.2 (b)**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA *AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements"* and the *FDOT Airfield Pavement Distress Repair Manual.* Additionally, the *Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements* was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft

Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete

Statewide Airfield Pavement Airport Pavement **Management Program**

2019 **Evaluation Report**

Space Coast Regional Airport (TIX)



Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L&TCR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

Space Coast Regional Airport (TIX)



111

Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT – SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$12.50	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$5.50	SqFt

Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$185.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in 5.2 Localized M&R Policy. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. Appendix B provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to nearterm Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3 (a)** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planr	ning Material Cost
FDOT - SURFACE SEAL	PREVENTIVE	502,400	SqFt	\$	276,320.00
FDOT - CRACK SEALING - AC	PREVENTIVE	2,490	Ft	\$	7,460.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	20	SqFt	\$	90.00
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	215	SqFt	\$	2,650.00
FDOT - CRACK SEALING - PCC	PREVENTIVE	100	Ft	\$	420.00
FDOT - PATCHING - PCC PARTIAL DEPTH	PREVENTIVE	30	SqFt	\$	1,900.00
FDOT - SURFACE SEAL	STOPGAP	1,193,710	SqFt	\$	656,550.00
FDOT - CRACK SEALING - AC	STOPGAP	38,885	Ft	\$	116,650.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	77,005	SqFt	\$	423,530.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	1,405	SqFt	\$	17,520.00

Table 5.3 (a) Summary of	f Airport Localized	M&R Planning Cost and	Quantity at Network Level
--------------------------	---------------------	-----------------------	---------------------------

Space Coast Regional Airport (TIX)

FDOT

The following **Table 5.3 (b)** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved "End Condition" of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
ТІХ	AP E	4205	101,014	62	67	\$ 14,760.00
ТІХ	AP E	4211	3,845	67	77	\$ 1,570.00
ТІХ	AP E	4214	52,187	56	66	\$ 17,900.00
ТІХ	AP E	4215	82,925	43	61	\$ 300,720.00
ТІХ	AP E	4216	48,836	82	92	\$ 6,720.00
ТІХ	AP E	4218	95,344	80	88	\$ 13,110.00
ΤΙΧ	AP E	4219	8,237	56	61	\$ 2,510.00
ТІХ	AP E	4220	8,168	83	89	\$ 230.00
ТІХ	AP E	4221	5,405	71	83	\$ 890.00
ТІХ	AP E	4225	8,700	69	69	\$ 220.00
ТІХ	AP E	4226	6,677	72	75	\$ 40.00
ТІХ	AP E	4227	6,560	89	92	\$ 40.00
ТІХ	AP E	4228	11,100	89	91	\$ 70.00
ТІХ	AP E	4229	16,315	88	90	\$ 90.00
ТІХ	AP E	4230	9,576	77	77	\$-
ТІХ	AP E	4232	9,960	79	83	\$ 110.00
ТІХ	AP E	4235	93,090	99	99	\$-
ТІХ	AP E	4240	7,020	91	94	\$ 40.00
ТІХ	AP E	4241	8,553	91	94	\$ 50.00
ТІХ	AP E	4245	7,200	71	96	\$ 3,970.00
ТІХ	AP E	4250	38,220	95	95	\$-
тіх	AP HELI	4255	32,798	90	90	\$-
ТІХ	AP HELI	4260	364,740	97	97	\$ 2,110.00
ТІХ	AP W	4305	370,471	99	100	\$-
ТІХ	AP W	4310	30,464	72	87	\$ 7,100.00
ТІХ	RW 18-36	6105	500,000	62	74	\$ 159,060.00
тіх	RW 18-36	6110	250,000	57	70	\$ 94,230.00
ТІХ	RW 18-36	6125	100,000	62	74	\$ 26,080.00
тіх	RW 18-36	6130	50,000	60	70	\$ 20,510.00
ТІХ	RW 18-36	6145	131,900	65	76	\$ 55,950.00
тіх	RW 18-36	6150	65,950	64	76	\$ 37,260.00
ТІХ	RW 9-27	6205	169,743	63	73	\$ 47,140.00

Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
ΤΙΧ	RW 9-27	6210	320,000	53	65	\$ 107,380.00
ΤΙΧ	TW A	105	114,651	68	75	\$ 66,430.00
ΤΙΧ	TW A	110	70,000	66	74	\$ 38,510.00
ΤΙΧ	TW A	112	30,000	67	78	\$ 17,410.00
ΤΙΧ	TW A	115	50,000	67	77	\$ 29,010.00
ΤΙΧ	TW A	120	90,638	65	74	\$ 53,910.00
ΤΙΧ	TW A2	125	35,137	65	78	\$ 14,220.00
ΤΙΧ	TW B	205	22,146	57	67	\$ 12,190.00
тіх	TW B	210	234,359	89	89	\$ 190.00
ΤΙΧ	TW C	305	46,879	68	79	\$ 20,540.00
ΤΙΧ	TW C	310	116,660	63	77	\$ 66,590.00
ΤΙΧ	TW C	315	32,856	88	88	\$-
ΤΙΧ	TW D	404	26,461	65	87	\$ 15,360.00
ΤΙΧ	TW D	408	7,500	65	87	\$ 4,580.00
ΤΙΧ	TW D	410	73,750	75	84	\$ 25,820.00
ΤΙΧ	TW E	505	32,371	72	85	\$ 12,110.00
ΤΙΧ	TW E	515	113,522	70	90	\$ 42,640.00
ΤΙΧ	TW E	525	8,165	94	94	\$-
ΤΙΧ	TW F	605	30,388	14	52	\$ 164,190.00

2019

Evaluation Report

Space Coast Regional Airport (TIX)

FDOT

Statewide Airfield Pavement Airport Pavement

Management Program

The following **Table 5.3 (c)** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (c) Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 288,840.00
Stopgap	\$ 1,214,250.00
Planning-Level Localized M&R Needs =	\$ 1,503,090.00

Statewide Airfield Pavement Management Program



Chapter 6

Space Coast Regional Airport (TIX)


FDOT

Chapter 6 – Major Rehabilitation Planning

6.1 Major Rehabilitation


Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1 (a) and 6.1 (b)** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI \leq Critical PCI





Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI





6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The *Critical PCI* concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

- 1. Develop a pavement performance model and refine a prediction model for the pavements considered.
- 2. Select a localized maintenance and repair policy to be used in developing a work plan.
- 3. Apply the selected localized policy to the pavement sections for a range of PCI.
- 4. Compute the unit cost per area for each PCI range.
- 5. Plot the cost versus the PCI.
- 6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended *Minimum Service-Level PCI* for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	70	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	65	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI



6.2 Major Rehabilitation Policy

6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA *AC 150/ 5320-6F "Airport Pavement Design and Evaluation."* It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following Tables 6.2.1 (a) and (b) provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average PR Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Rehabilitation Type	Commercial (PR) Airport
AC Restoration Combination of asphalt pavement milling and overlay with 25% of the areas subject to full- depth reconstruction.	75% Mill and Overlay P-101 AC Milling (4") P-603 Bituminous Tack P-401 (HMA) (4")
PCI = 41 to 65	25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (6") <i>Excludes any paved shoulder features.</i>
AC Reconstruction	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8")
Full-depth asphalt pavement section reconstruction.	P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (6")
PCI = 40 or less	Excludes any paved shoulder features.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible AsphaltConcrete





Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland CementConcrete

Rehabilitation Type	Commercial (PR) Airport
 PCC Restoration Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels. PCI = 41 to 65 	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (16") *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction Full-depth rigid pavement section reconstruction. PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (6") P-501 Rigid PCC (17")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design-level rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

The recommendations identified in the Major Rehabilitation Needs consider the FAA AC 150/5370-10H Standard Specifications for Construction of Airports when determining the appropriate materials and methods implemented for construction projects, such as pavement rehabilitation, on airports. It should be noted that the AC 150/5370-10H Standard Specifications for Construction of Airports was updated in December of 2018. Design-level determination of project specific specifications based on the AC should be developed by the Airport when performing applicable construction projects.



6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Rehabilitation Type	PCI Range	le Asphalt Cost Per SF	Rigid Portland Cement Concrete Cost per SF		
Restoration	41 to 65	\$ 11.00	\$	17.00	
Reconstruction	0 to 40	\$ 14.00	\$	23.00	

Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level

Space Coast Regional Airport (TIX) FDOT

rt (TIX)

investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ТІХ	AP E	4205	AAC	101,014	61	AC Restoration	\$ 1,112,000.00
2020	ТІХ	AP E	4214	APC	52,187	54	AC Restoration	\$ 575,000.00
2020	ТІХ	AP E	4215	AC	82,925	43	AC Restoration	\$ 1,070,000.00
2020	ТІХ	AP E	4219	AAC	8,237	54	AC Restoration	\$ 91,000.00
2020	ΤΙΧ	RW 18-36	6105	AAC	500,000	59	AC Restoration	\$ 5,500,000.00
2020	ТІХ	RW 18-36	6110	AAC	250,000	55	AC Restoration	\$ 2,750,000.00
2020	ΤΙΧ	RW 18-36	6125	AAC	100,000	59	AC Restoration	\$ 1,100,000.00
2020	ТІХ	RW 18-36	6130	AAC	50,000	58	AC Restoration	\$ 550,000.00
2020	ΤΙΧ	RW 18-36	6145	AAC	131,900	62	AC Restoration	\$ 1,451,000.00
2020	ТІХ	RW 18-36	6150	AAC	65,950	61	AC Restoration	\$ 726,000.00
2020	ΤΙΧ	RW 9-27	6205	AAC	169,743	60	AC Restoration	\$ 1,868,000.00
2020	ТІХ	RW 9-27	6210	AAC	320,000	52	AC Restoration	\$ 3,520,000.00
2020	ТІХ	TW A	110	AAC	70,000	64	AC Restoration	\$ 770,000.00
2020	ТІХ	TW A	120	AAC	90,638	63	AC Restoration	\$ 997,000.00
2020	ΤΙΧ	TW A2	125	AAC	35,137	63	AC Restoration	\$ 387,000.00
2020	ТІХ	TW B	205	AAC	22,146	56	AC Restoration	\$ 244,000.00
2020	ТІХ	TW C	310	AAC	116,660	62	AC Restoration	\$ 1,284,000.00
2020	ТІХ	TW D	404	AAC	26,461	63	AC Restoration	\$ 292,000.00
2020	ТІХ	TW D	408	AAC	7,500	63	AC Restoration	\$ 83,000.00
2020	тіх	TW F	605	AAC	30,388	10	AC Reconstruction	\$ 426,000.00
2021	ТІХ	AP E	4211	AAC	3,845	63	AC Restoration	\$ 43,000.00
2021	ΤΙΧ	TW A	112	AAC	30,000	64	AC Restoration	\$ 330,000.00
2021	ТІХ	TW A	115	AAC	50,000	64	AC Restoration	\$ 550,000.00
2022	тіх	AP E	4225	PCC	8,700	64	PCC Restoration	\$ 148,000.00
2022	ТІХ	TW A	105	AAC	114,651	63	AC Restoration	\$ 1,262,000.00
2022	ТІХ	TW C	305	AAC	46,879	63	AC Restoration	\$ 516,000.00
2023	ТІХ	AP E	4221	AC	5,405	64	AC Restoration	\$ 60,000.00
2023	ТІХ	AP E	4226	AAC	6,677	64	AC Restoration	\$ 74,000.00
2023	ТІХ	AP E	4245	AC	7,200	64	AC Restoration	\$ 80,000.00
2023	ΤΙΧ	AP W	4310	AAC	30,464	64	AC Restoration	\$ 336,000.00
2023	ТІХ	TW E	515	AAC	113,522	64	AC Restoration	\$ 1,249,000.00
2024	ТІХ	TW E	505	AAC	32,371	64	AC Restoration	\$ 357,000.00
2026	ΤΙΧ	AP E	4218	AAC	95,344	64	AC Restoration	\$ 1,049,000.00

Table 6.3.1 10-Year Major Rehabilitation Needs

Statewide Airfield Pavement Air Management Program Eva

Airport Pavement 2019 Evaluation Report

Space Coast Regional Airport (TIX)



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Pla	nning Cost
2026	ТІХ	AP E	4232	AAC	9,960	63	AC Restoration	\$	110,000.00
2026	ТІХ	TW D	410	AAC	73,750	63	AC Restoration	\$	812,000.00
2027	ТІХ	AP E	4216	AAC	48,836	63	AC Restoration	\$	538,000.00
2027	ТІХ	AP E	4220	AAC	8,168	64	AC Restoration	\$	90,000.00
2028	тіх	AP E	4230	PCC	9,576	64	PCC Restoration	\$	163,000.00
2029	ТІХ	AP E	4227	AAC	6,560	64	AC Restoration	\$	73,000.00
2029	ТІХ	AP E	4228	AAC	11,100	64	AC Restoration	\$	123,000.00

*All values have been rounded to the nearest thousand-dollar.

The following **Figure 6.3.1 (a)** summarizes the section-level major rehabilitation needs for a 10year period between 2020 and 2029. **Figure 6.3.1 (b)** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.





Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year







Statewide Airfield Pavement Management Program



Chapter 7



Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and reinspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2020-2029. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- Develop a detailed preventive maintenance program for the airport.
- Further refine and implement the identified 10-year major rehabilitation needs.
- Maintain detailed records on pavement maintenance, construction, and inspection.
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).

7.2 Supporting Documents

001 – Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

002 – Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the *Airport Response Form* provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

003 – Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER[™] software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

004 – Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation.** Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.





7.3 Conclusion


The FDOT SAPMP Update Phase 2 2018-2019 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars 150/5380-7B "Airport Pavement Management Program (PMP)" and 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

Statewide Airfield Pavement Management Program



Appendix A

Airfield Pavement Analysis Tables



Space Coast Regional Airport (TIX)



Table A-1 Pave	ement System	Inventory	Details
----------------	--------------	-----------	---------

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ТІХ	EAST APRON	AP E	APRON	4205	784	188	101,014	AAC	1/1/2008
ТІХ	EAST APRON	AP E	APRON	4211	100	38	3,845	AAC	6/1/2002
ТІХ	EAST APRON	AP E	APRON	4214	1,100	35	52,187	APC	6/1/2002
ТІХ	EAST APRON	AP E	APRON	4215	300	150	82,925	AC	1/1/1971
ТІХ	EAST APRON	AP E	APRON	4216	300	150	48,836	AAC	1/1/2008
ТІХ	EAST APRON	AP E	APRON	4218	525	137	95,344	AAC	1/1/2008
ТІХ	EAST APRON	AP E	APRON	4219	55	151	8,237	AAC	1/1/2015
ТІХ	EAST APRON	AP E	APRON	4220	300	45	8,168	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4221	200	25	5,405	AC	1/1/2008
ТІХ	EAST APRON	AP E	APRON	4225	400	20	8,700	PCC	1/1/1991
ТІХ	EAST APRON	AP E	APRON	4226	325	40	6,677	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4227	325	40	6,560	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4228	400	30	11,100	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4229	820	20	16,315	AC	1/1/2012
ТІХ	EAST APRON	AP E	APRON	4230	400	20	9,576	PCC	1/1/1991
ТІХ	EAST APRON	AP E	APRON	4232	1,000	162	9,960	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4235	495	178	93,090	PCC	1/1/2015
ТІХ	EAST APRON	AP E	APRON	4240	250	30	7,020	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4241	350	25	8,553	AAC	1/1/2014
ТІХ	EAST APRON	AP E	APRON	4245	350	20	7,200	AC	1/1/2003
ТІХ	EAST APRON	AP E	APRON	4250	190	200	38,220	PCC	1/1/2011
тіх	HELICOPTER APRON	AP HELI	APRON	4255	475	70	32,798	AC	1/1/2012
ТІХ	HELICOPTER APRON	AP HELI	APRON	4260	744	510	364,740	PCC	1/1/2012
ТІХ	WEST APRON	AP W	APRON	4305	1,600	500	370,471	PCC	1/1/2014
тіх	WEST APRON	AP W	APRON	4310	68	400	30,464	AAC	1/1/2014
ТІХ	RUNWAY 18-36	RW 18-36	RUNWAY	6105	5,000	100	500,000	AAC	6/1/2002
тіх	RUNWAY 18-36	RW 18-36	RUNWAY	6110	10,000	25	250,000	AAC	6/1/2002
тіх	RUNWAY 18-36	RW 18-36	RUNWAY	6125	1,000	100	100,000	AAC	6/1/2002
тіх	RUNWAY 18-36	RW 18-36	RUNWAY	6130	2,000	25	50,000	AAC	6/1/2002
ТІХ	RUNWAY 18-36	RW 18-36	RUNWAY	6145	1,319	100	131,900	AAC	6/1/2002
тіх	RUNWAY 18-36	RW 18-36	RUNWAY	6150	2,600	25	65,950	AAC	6/1/2002
тіх	RUNWAY 9-27	RW 9-27	RUNWAY	6205	1,650	100	169,743	AAC	1/1/1998
тіх	RUNWAY 9-27	RW 9-27	RUNWAY	6210	3,200	100	320,000	AAC	1/1/1998
тіх	ΤΑΧΙΨΑΥ Α	TW A	TAXIWAY	105	2,200	50	114,651	AAC	6/1/2002
ТІХ	ΤΑΧΙΨΑΥ Α	TW A	TAXIWAY	110	1,400	50	70,000	AAC	6/1/2002
ТІХ	ΤΑΧΙΨΑΥ Α	TW A	TAXIWAY	112	600	50	30,000	AAC	6/1/2002

Statewide Airfield Pavement
Management ProgramAirport Pavement
Evaluation Report

2019

Space Coast Regional Airport (TIX)



181

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
тіх	TAXIWAY A	TW A	TAXIWAY	115	1,000	50	50,000	AAC	6/1/2002
ТІХ	TAXIWAY A	TW A	TAXIWAY	120	1,800	50	90,638	AAC	6/1/2002
ТІХ	TAXIWAY A2	TW A2	TAXIWAY	125	600	500	35,137	AAC	6/1/2002
ТІХ	TAXIWAY B	TW B	TAXIWAY	205	400	50	22,146	AAC	6/1/2002
ТІХ	TAXIWAY B	TW B	TAXIWAY	210	4,600	50	234,359	AAC	1/1/2013
ТІХ	TAXIWAY C	TW C	TAXIWAY	305	700	65	46,879	AAC	1/1/2004
ТІХ	TAXIWAY C	TW C	TAXIWAY	310	2,300	50	116,660	AAC	1/1/1986
ТІХ	TAXIWAY C	TW C	TAXIWAY	315	600	50	32,856	AAC	1/1/2013
ТІХ	TAXIWAY D	TW D	TAXIWAY	404	400	50	26,461	AAC	1/1/2000
ТІХ	TAXIWAY D	TW D	TAXIWAY	408	150	50	7,500	AAC	1/1/2000
ТІХ	TAXIWAY D	TW D	TAXIWAY	410	1,450	50	73,750	AAC	1/1/2000
ТІХ	TAXIWAY E	TW E	TAXIWAY	505	600	50	32,371	AAC	1/1/1998
ТІХ	TAXIWAY E	TW E	TAXIWAY	515	2,640	50	113,522	AAC	1/1/2003
ТІХ	TAXIWAY E	TW E	TAXIWAY	525	100	85	8,165	AC	1/1/2014
ТІХ	TAXIWAY F	TW F	TAXIWAY	605	580	50	30,388	AAC	1/1/1998

Space Coast Regional Airport (TIX)



Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
тіх	RUNWAY 18-36	RUNWAY	6105	500,000	62	Fair
ТІХ	RUNWAY 18-36	RUNWAY	6110	250,000	57	Fair
ТІХ	RUNWAY 18-36	RUNWAY	6125	100,000	62	Fair
ТІХ	RUNWAY 18-36	RUNWAY	6130	50,000	60	Fair
тіх	RUNWAY 18-36	RUNWAY	6145	131,900	65	Fair
ТІХ	RUNWAY 18-36	RUNWAY	6150	65,950	64	Fair
ТІХ	RUNWAY 9-27	RUNWAY	6205	169,743	63	Fair
ТІХ	RUNWAY 9-27	RUNWAY	6210	320,000	53	Poor
тіх	ΤΑΧΙΨΑΥ Α	TAXIWAY	105	114,651	68	Fair
ТІХ	TAXIWAY A	TAXIWAY	110	70,000	66	Fair
тіх	ΤΑΧΙΨΑΥ Α	TAXIWAY	112	30,000	67	Fair
ТІХ	TAXIWAY A	TAXIWAY	115	50,000	67	Fair
тіх	ΤΑΧΙΨΑΥ Α	TAXIWAY	120	90,638	65	Fair
ТІХ	TAXIWAY A2	TAXIWAY	125	35,137	65	Fair
ТІХ	TAXIWAY B	TAXIWAY	205	22,146	57	Fair
ТІХ	TAXIWAY B	TAXIWAY	210	234,359	89	Good
ТІХ	TAXIWAY C	TAXIWAY	305	46,879	68	Fair
ТІХ	TAXIWAY C	TAXIWAY	310	116,660	63	Fair
ТІХ	TAXIWAY C	TAXIWAY	315	32,856	88	Good
ТІХ	TAXIWAY D	TAXIWAY	404	26,461	65	Fair
ТІХ	TAXIWAY D	TAXIWAY	408	7,500	65	Fair
ТІХ	TAXIWAY D	TAXIWAY	410	73,750	75	Satisfactory
ТІХ	TAXIWAY E	TAXIWAY	505	32,371	72	Satisfactory
ТІХ	TAXIWAY E	TAXIWAY	515	113,522	70	Fair
ТІХ	TAXIWAY E	TAXIWAY	525	8,165	94	Good
ТІХ	TAXIWAY F	TAXIWAY	605	30,388	14	Serious
ΤΙΧ	EAST APRON	APRON	4205	101,014	62	Fair
ТІХ	EAST APRON	APRON	4211	3,845	67	Fair
ТІХ	EAST APRON	APRON	4214	52,187	56	Fair
ТІХ	EAST APRON	APRON	4215	82,925	45	Poor
ТІХ	EAST APRON	APRON	4216	48,836	82	Satisfactory
ТІХ	EAST APRON	APRON	4218	95,344	80	Satisfactory
ТІХ	EAST APRON	APRON	4219	8,237	56	Fair
ТІХ	EAST APRON	APRON	4220	8,168	83	Satisfactory
ΤΙΧ	EAST APRON	APRON	4221	5,405	71	Satisfactory
ТІХ	EAST APRON	APRON	4225	8,700	69	Fair
ТІХ	EAST APRON	APRON	4226	6,677	72	Satisfactory

tewide Airfie nagement Pi	eld Pavement Airport Pavement Fogram Evaluation Rep		Space Coast R Airport (TI		- Sh	FD	
Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating	
ΤΙΧ	EAST APRON	APRON	4227	6,560	89	Good	
ΤΙΧ	EAST APRON	APRON	4228	11,100	89	Good	
ΤΙΧ	EAST APRON	APRON	4229	16,315	88	Good	
ΤΙΧ	EAST APRON	APRON	4230	9,576	77	Satisfactory	
ΤΙΧ	EAST APRON	APRON	4232	9,960	79	Satisfactory	
ΤΙΧ	EAST APRON	APRON	4235	93,090	99	Good	
ΤΙΧ	EAST APRON	APRON	4240	7,020	91	Good	
ΤΙΧ	EAST APRON	APRON	4241	8,553	91	Good	
ΤΙΧ	EAST APRON	APRON	4245	7,200	71	Satisfactory	
ΤΙΧ	EAST APRON	APRON	4250	38,220	95	Good	
ТІХ	HELICOPTER APRON	APRON	4255	32,798	90	Good	
ΤΙΧ	HELICOPTER APRON	APRON	4260	364,740	97	Good	
тіх	WEST APRON	APRON	4305	370,471	99	Good	
ΤΙΧ	WEST APRON	APRON	4310	30,464	72	Satisfactory	

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

Space Coast Regional Airport (TIX)



Table A-3 Forecasted PCI 2020-2029

Network		Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
тіх	AP E	4205	62	61	60	60	60	60	60	60	60	59	58
ТІХ	AP E	4211	67	65	63	62	61	61	60	60	60	60	60
ТІХ	AP E	4214	56	54	51	48	44	40	36	32	28	26	25
ТІХ	AP E	4215	45	43	42	40	38	37	35	34	32	31	29
ТІХ	AP E	4216	82	79	76	74	71	69	67	65	63	62	61
ТІХ	AP E	4218	80	77	75	72	70	67	65	64	63	62	61
ТІХ	AP E	4219	56	54	51	48	44	40	36	32	28	26	25
тіх	AP E	4220	83	80	77	75	72	70	68	66	64	63	62
тіх	AP E	4221	71	69	68	66	64	63	61	60	58	57	55
ТІХ	AP E	4225	69	67	66	64	62	61	59	57	55	53	52
тіх	AP E	4226	72	70	67	65	64	63	62	61	60	60	60
тіх	AP E	4227	89	86	83	80	78	75	72	70	68	66	64
ТІХ	AP E	4228	89	86	83	80	78	75	72	70	68	66	64
ТІХ	AP E	4229	88	86	85	83	81	80	78	77	75	74	72
ТІХ	AP E	4230	77	76	74	73	72	70	69	68	66	64	63
тіх	AP E	4232	79	76	74	71	69	67	65	63	62	61	61
ТІХ	AP E	4235	99	97	95	93	92	90	89	88	87	86	86
ТІХ	AP E	4240	91	88	85	82	80	77	74	72	69	67	65
ТІХ	AP E	4241	91	88	85	82	80	77	74	72	69	67	65
ТІХ	AP E	4245	71	69	68	66	64	63	61	60	58	57	55
ТІХ	AP E	4250	95	93	92	90	89	88	87	86	86	85	84
ТІХ	AP HELI	4255	90	88	87	85	83	82	80	79	77	76	74
ТІХ	AP HELI	4260	97	95	93	92	90	89	88	87	87	86	85
тіх	AP W	4305	99	97	95	93	92	90	89	88	87	86	86
ТІХ	AP W	4310	72	70	67	65	64	63	62	61	60	60	60
ТІХ	RW 18-36	6105	62	59	57	56	55	54	54	54	53	52	51
ТІХ	RW 18-36	6110	57	55	54	54	54	54	52	52	51	51	50
тіх	RW 18-36	6125	62	59	57	56	55	54	54	54	53	52	51
тіх	RW 18-36	6130	60	58	56	55	54	54	54	53	52	52	51
тіх	RW 18-36	6145	65	62	60	57	56	55	54	54	54	53	52
тіх	RW 18-36	6150	64	61	59	57	55	54	54	54	54	52	52
тіх	RW 9-27	6205	63	60	58	56	55	54	54	54	53	52	51
тіх	RW 9-27	6210	53	52	51	51	50	50	49	48	48	47	47
тіх	TW A	105	68	66	65	63	62	61	60	59	58	57	57
тіх	TW A	110	66	64	63	62	61	60	59	58	57	56	56
тіх	TW A	112	67	65	64	63	61	60	59	58	58	57	56
тіх	TW A	115	67	65	64	63	61	60	59	58	58	57	56

Statewide Airfield Pavement
Management ProgramAirport Pavement
Evaluation Report

2019

Space Coast Regional Airport (TIX)



181

Network	Brench ID	Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ТІХ	TW A	120	65	63	62	61	60	59	58	57	57	56	55
ТІХ	TW A2	125	65	63	62	61	60	59	58	57	57	56	55
ТІХ	TW B	205	57	56	55	55	54	53	53	52	52	51	51
тіх	TW B	210	89	86	84	82	79	77	75	73	71	69	68
ТІХ	TW C	305	68	66	65	63	62	61	60	59	58	57	57
тіх	TW C	310	63	62	60	59	58	58	57	56	55	55	54
тіх	TW C	315	88	85	83	81	78	76	74	72	71	69	67
тіх	TW D	404	65	63	62	61	60	59	58	57	57	56	55
ТІХ	TW D	408	65	63	62	61	60	59	58	57	57	56	55
тіх	TW D	410	75	73	71	69	68	66	65	63	62	61	60
ТІХ	TW E	505	72	70	68	67	65	64	63	61	60	59	58
тіх	TW E	515	70	68	67	65	64	62	61	60	59	58	57
тіх	TW E	525	94	92	90	88	86	84	83	81	80	78	77
тіх	TW F	605	14	10	4	0	0	0	0	0	0	0	0

Work History Report

Page 1 of 10

Pavement Database: FDOT Network: SPACE COAST REG Branch: AP E Section: 4205 EAST APRON Surface: AAC L.C.D. 1/1/2008 Use: APRON Rank: P Length: 784.00 (Ft) Width: 188.00 (Ft) True Area: 101014.0000 (SqFt Work Thickness Major Work Date Cost Work Description Comments Code (in) M&R 1/1/2008 ML-OV MILL and OVERLAY 0.00 0.00 Unknown \checkmark 1/1/1992 IMPORT REPAIR THIS FEATURE HAS A 1992 0.00 0.00 ED SLURRY SEAL 1/1/1968 IMPORT BUILT 0.00 1968: 3" AC ON 8" LIME ROCK 3.00 \checkmark ED BASE. SOIL: SP. Network: SPACE COAST REG EAST APRON Branch: AP E Section: 4211 Surface:AAC L.C.D. 6/1/2002 Use: APRON Rank: P Length: 100.00 (Ft) Width: 38.00 (Ft) True Area: 3845.000001 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 ~ 1/1/1971 NU-IN New Construction - Initial 0.00 0.00 \checkmark ESTIMATE 1971 AC Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4214 Surface:APC L.C.D. 6/1/2002 Use: APRON Rank: P Length: 1.100.00 (Ft) Width: 35.00 (Ft) True Area: 52187.00001 (SaFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 6/1/2002 ML-OV MILL and OVERLAY 0.00 0.00 Unknown \checkmark 1/1/1992 SS-SS Slurry Seal 0.00 0.00 Unknown 1/1/1971 OL-AC Overlay - AC 0.00 0.00 \checkmark Unknown 1/1/1943 NC-PC New Construction - PCC 0.00 0.00 \checkmark Est. initial construction Network: SPACE COAST REG EAST APRON Section: 4215 Branch: AP E Surface:AC L.C.D. 1/1/1971 Use: APRON Rank: P 300.00 (Ft) Width: 150.00 (Ft) True Area: 82925.00002 (SaFt Length: Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/1992 IMPORT REPAIR 0.00 0.00 THIS PAVEMENT HAS A 1992 ED SLURRY SEAL 1/1/1971 IMPORT BUILT 0.00 0.00 \checkmark ESTIMATE 1971 AC PAVEMENT ED Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4216 Surface:AAC L.C.D. 1/1/2008 Use: APRON Rank: P Length: 300.00 (Ft) Width: 150.00 (Ft) True Area: 48836.00001 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/2008 ML-OL Mill and Overlay 0.00 0.00 \checkmark 1/1/1971 NU-IN ESTIMATE 1971 AC New Construction - Initial 0.00 0.00 \checkmark Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4218 Surface:AAC L.C.D. 1/1/2008 Use: APRON Rank: P Length: 525.00 (Ft) Width: 137.00 (Ft) True Area: 95344.00002 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/2008 Mill and Overlay 0.00 0.00 ML-OL \checkmark 1/1/1971 NU-IN New Construction - Initial 0.00 0.00 ESTIMATE 1971 AC \checkmark

Work History Report

Page 2 of 10

Pavement Database: FDOT Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4219 Surface:AAC L.C.D. 1/1/2015 Use: APRON Rank: P Length: 55.00 (Ft) Width: 151.00 (Ft) True Area: 8237.000002 (SqFt Work Thickness Major Work Date Cost Work Description Comments Code (in) M&R 1/1/2015 ML-OV MILL and OVERLAY 0.00 0.00 Unknown \checkmark 1/1/1992 IMPORT REPAIR 0.00 0.00 THIS PAVEMENT HAS A 1992 ED SLURRY SEAL 1/1/1971 IMPORT BUILT 0.00 ESTIMATE 1971 AC PAVEMENT 0.00 \checkmark ED Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4220 Surface:AAC L.C.D. 1/1/2014 Use: APRON Rank: P Length: 300.00 (Ft) Width: 45.00 (Ft) True Area: 8168.000002 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/2014 ML-OV MILL and OVERLAY 0.00 0.00 ~ 1/1/1992 IMPORT REPAIR 0.00 0.00 THIS PAVEMENT HAS A 1992 ED SLURRY SEAL 1/1/1980 IMPORT BUILT 0.00 0.00 \checkmark ESTIMATE 1980 AC PAVEMENT ED Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4221 Surface:AC L.C.D. 1/1/2008 Use: APRON Rank: P Length: 200.00 (Ft) Width: 25.00 (Ft) True Area: 5405.000001 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/2008 NC-AC New Construction - AC 0.00 0.00 Unknown V Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4225 Surface:PCC L.C.D. 1/1/1991 Use: APRON Rank: P Length: 400.00 (Ft) Width: 20.00 (Ft) True Area: 8700.000002 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/1991 IMPORT BUILT 0.00 0.00 ESTIMATE 1991 PCC PAVEMENT \checkmark ED Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4226 Surface:AAC Rank: P **L.C.D.** 1/1/2014 Use: APRON 325.00 (Ft) Width: 40.00 (Ft) True Area: 6677.000002 (SqFt Length: Work Thickness Major Work Date Cost Work Description Comments Code (in) M&R ML-OV MILL and OVERLAY 1/1/2014 2014: Remove Existing AC and replac 0.00 0.00 1/1/1992 IMPORT REPAIR THIS PAVEMENT HAS A 1992 0.00 0.00 SLURRY SEAL ED 1/1/1985 IMPORT BUILT 0.00 0.00 \checkmark ESTIMATE 1985 AC PAVEMENT ED Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4227 Surface:AAC L.C.D. 1/1/2014 Use: APRON 325.00 (Ft) 40.00 (Ft) True Area: 6560.000002 (SqFt Rank: P Length: Width: Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/2014 ML-OV MILL and OVERLAY 0.00 2014: Remove Existing AC and replac 0.00 \checkmark IMPORT BUILT 1/1/1992 0.00 0.00 \checkmark 1992 SLURRY SEAL ON THIS ED PAVEMENT IMPORT OVERLAY 1/1/1988 0.00 ESTIMATE 1988 AC PAVEMENT 0.00 \checkmark ED

Work History Report

Pavement Database: FDOT

Page 3 of 10

Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4228 Surface:AAC L.C.D. 1/1/2014 Use: APRON Rank: P Length: 400.00 (Ft) Width: 30.00 (Ft) True Area: 11100.00000 (SqFt Work Thickness Major Work Date Cost Work Description Comments Code (in) M&R 1/1/2014 ML-OV MILL and OVERLAY 0.00 0.00 2014: Remove Existing AC and replac \checkmark 1992 SLURRY SEAL ON THIS 1/1/1992 IMPORT BUILT 0.00 0.00 \checkmark ED PAVEMENT 1/1/1988 IMPORT OVERLAY 0.00 ESTIMATE 1988 AC PAVEMENT 0.00 \checkmark ED Network: SPACE COAST REG EAST APRON Branch: AP E Section: 4229 Surface:AC **L.C.D.** 1/1/2012 Use: APRON Rank: P Length: 820.00 (Ft) Width: 20.00 (Ft) True Area: 16315.00000 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/2012 2012: 2" FDOT SP 12.5 Fine Mix, 6" NU-IN New Construction - Initial 0.00 0.00 \checkmark Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4230 Surface:PCC L.C.D. 1/1/1991 Use: APRON Rank: P Length: 400.00 (Ft) Width: 20.00 (Ft) True Area: 9576.000002 (SqFt Thickness Work Major Work Date Work Description Cost Comments Code (in) M&R 1/1/1991 IMPORT BUILT ESTIMATE 1991 PCC PAVEMENT 0.00 0.00 \checkmark ED Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4232 Surface:AAC L.C.D. 1/1/2014 Use: APRON Rank: P Length: 1,000.00 (Ft) Width: 162.00 (Ft) True Area: 9960.000003 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/2014 ML-OV MILL and OVERLAY 2014: 2" MILL AND 2" OL W/ FDOT 0.00 0.00 \checkmark 1/1/1992 IMPORT REPAIR THIS PAVEMENT HAS A 1992 0.000.00 ED SLURRY SEAL 1/1/1971 IMPORT BUILT 0.00 ESTIMATE 1971 AC PAVEMENT (0.00 \checkmark ED 8" ASPHALT ON 5" +/- SOIL CEME Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4235 Surface:PCC Rank: P L.C.D. 1/1/2015 Use: APRON Width: 178.00 (Ft) True Area: 93090.00002 (SqFt Length: 495.00 (Ft) Work Thickness Major Work Date Cost Work Description Comments Code (in) M&R 1/1/2015 NC-PC 14" P-501, 6" P-211, COMPACTED S New Construction - PCC 0.00 0.00 Network: SPACE COAST REG Branch: AP E EAST APRON Section: 4240 Surface:AAC L.C.D. 1/1/2014 Use: APRON Rank: P 250.00 (Ft) Width: 30.00 (Ft) True Area: 7020.000002 (SqFt Length: Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/2014 ML-OV MILL and OVERLAY 0.00 0.00 Remove 2" Existing and replace with ✓ 1/1/1987 IMPORT BUILT 0.00 0.00 \checkmark ESTIMATE 1987 AC PAVEMENT

ED

Work History Report

Page 4 of 10

Pavement Database: FDOT

Network:	SPACE CO	DAST REG Br	anch: AP E	EAST	APRON	Section:	4241 Surface:AAC
L.C.D. 1/1/2	014 Us	e: APRON R	ank: P I	ength: 350	.00 (Ft) Wi	dth: 25.0	0 (Ft) True Area: 8553.000002 (SqFt
Work Date	Work Code	Work Desc	ription	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ML-OV	MILL and OVERI	LAY	0.00	0.00		Remove 2" Existing and replace with
1/1/1987	IMPORT ED	BUILT		0.00	0.00		ESTIMATE 1987 AC PAVEMENT
	ED						
Network:	SPACE CO	DAST REG Br	anch: AP E	EAST	APRON	Section:	4245 Surface:AC
L.C.D. 1/1/2	003 Us	e: APRON R	ank: P I	ength: 350	.00 (Ft) Wi	dth: 20.0	0 (Ft) True Area: 7200.000002 (SqF
Work Date	Work Code	Work Desc	ription	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	NU-IN	New Construction	- Initial	0.00	0.00		
Network:	SPACE CO	DAST REG Br	anch: AP E	EAST	APRON	Section:	4250 Surface:PCC
L.C.D. 1/1/2	011 Us	e: APRON R	ank: P I	ength: 190	.00 (Ft) Wi	dth: 200.0	0 (Ft) True Area: 38220.00001 (SqFt
Work Date	Work	Work Desc	ription	Cost	Thickness	Major Ma D	Comments
1/1/2011	Code NU-IN	New Construction		0.00	(in) 0.00	M&R	
1/1/2011	NO-IN	New Construction	- IIItidi	0.00	0.00		
Network:	SPACE CO	DAST REG Br	anch: AP HE	LI HELIC	COPTER AP	Section:	4255 Surface:AC
L.C.D. 1/1/2	012 Us	e: APRON R	ank: P I	ength: 475	.00 (Ft) Wi	dth: 70.0	0 (Ft) True Area: 32798.00001 (SqFt
Work Date	Work Code	Work Desc	•	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	NU-IN	New Construction	- Initial	0.00	0.00		2012: 2" P-401, 8" LIMEROCK, 8" S
Network:			anch: AP HE	LI HELIC	COPTER AP	Section:	
L.C.D. 1/1/2		e: APRON R	ank: P I	ength: 744	、 <i>/</i>	dth: 510.0	0 (Ft) True Area: 364740.0001 (SqF
Work Date	Work Code	Work Desc	-	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	NU-IN	New Construction	- Initial	0.00	7.25		2012: 7.25" FDOT CONCRETE SPE
Network:	SPACE CO	DAST REG Br	anch: AP W	WEST	APRON	Section:	4305 Surface:PCC
L.C.D. 1/1/2	014 Us	e: APRON R	ank: P I	ength: 1,600	.00 (Ft) Wi	dth: 500.0	0 (Ft) True Area: 370471.0001 (SqF
Work Date	Work Code	Work Desc	ription	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	NU-IN	New Construction	- Initial	0.00	14.00		2014: 14" P-501, 6" P-211, COMPAC
Network:	SPACE CO	DAST REG Br	anch: AP W	WEST	APRON	Section:	4310 Surface:AAC
L.C.D. 1/1/2	014 Us	e: APRON R	ank: P I	ength: 68	.00 (Ft) Wi	dth: 400.0	0 (Ft) True Area: 30464.00000 (SqF
Work Date	Work Code	Work Desc	ription	Cost	Thickness (in)	Major M&R	Comments
1/1/2014		MILL and OVERI		0.00	0.00		PARTIAL OVERLAY FROM AP W
1/1/2004	ML-OV	MILL and OVERLAY		0.00	0.00		
1/1/1943			2/11	0.00	0.00		

Work History Report

Page 5 of 10

Pavement Database: FDOT Network: SPACE COAST REG Branch: RW 18-36 **RUNWAY 18-36** Section: 6105 Surface:AAC L.C.D. 6/1/2002 Use: RUNWAY Rank: P Length: 5,000.00 (Ft) Width: 100.00 (Ft) True Area: 500000.0001 (SqFt Work Thickness Major Work Date Cost Work Description Comments Code (in) M&R 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 \checkmark 1/1/1971 IMPORT OVERLAY 1971: MINIMUM 2" P-401 0.00 2.00 \checkmark ED OVERLAY. SOIL: SP. 1/1/1943 IMPORT BUILT 0.00 1943: 1" - 2" AC ON 8" LIME ROCK 1.00 \checkmark ED BASE Network: SPACE COAST REG Branch: RW 18-36 **RUNWAY 18-36** Section: 6110 Surface:AAC L.C.D. 6/1/2002 Use: RUNWAY Rank: P Length: 10,000.00 (Ft) Width: 25.00 (Ft) True Area: 250000.0000 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 ~ 1/1/1971 IMPORT OVERLAY 0.00 2.00 \checkmark 1971: MINIMUM 2" P-401 ED OVERLAY. SOIL: SP. 1/1/1943 IMPORT BUILT 0.00 1.00 1943: 1" - 2" AC ON 8" LIME ROCK \checkmark ED BASE Network: SPACE COAST REG Branch: RW 18-36 **RUNWAY 18-36** Section: 6125 Surface:AAC L.C.D. 6/1/2002 Use: RUNWAY Rank: P Length: 1,000.00 (Ft) Width: 100.00 (Ft) True Area: 100000.0000 (SqFt Work Thickness Major Work Date **Work Description** Cost Comments Code (in) M&R 6/1/2002 Mill and Overlay ML-OL 0.00 0.00 1/1/1971 IMPORT OVERLAY 0.00 3.00 1971: MINIMUM 3" P-401 \checkmark ED OVERLAY. SOIL: SP. 1/1/1967 IMPORT BUILT 0.00 1967: 2" - 3" AC ON 7" - 8" LIME 2.00 \checkmark ED ROCK BASE Network: SPACE COAST REG Branch: RW 18-36 **RUNWAY 18-36** Section: 6130 Surface: AAC L.C.D. 6/1/2002 Use: RUNWAY Rank: P Length: 2,000.00 (Ft) Width: 25.00 (Ft) True Area: 50000.00001 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 V IMPORT OVERLAY 1/1/1971 0.00 1971: MINIMUM 3" P-401 3.00 \checkmark ED OVERLAY. SOIL: SP. 1/1/1967 IMPORT BUILT 0.00 2.00 1967: 2" - 3" AC ON 7" - 8" LIME \checkmark ED ROCK BASE Network: SPACE COAST REG Branch: RW 18-36 **RUNWAY 18-36** Section: 6145 Surface:AAC L.C.D. 6/1/2002 Length: 1,319.00 (Ft) Width: 100.00 (Ft) True Area: 131900.0000 (SqFt Use: RUNWAY Rank: P Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 1/1/1971 NU-IN New Construction - Initial 0.00 0.00 \checkmark

Work History Report

Page 6 of 10

Pavement Database: FDOT Network: SPACE COAST REG Branch: RW 18-36 **RUNWAY 18-36** Section: 6150 Surface:AAC L.C.D. 6/1/2002 Use: RUNWAY Rank: P Length: 2,600.00 (Ft) Width: 25.00 (Ft) True Area: 65950.00002 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 \checkmark 1/1/1971 IMPORT OVERLAY 0.00 2.00 \checkmark 1971: MINIMUM 2" P-401 ED OVERLAY. SOIL: SP. 1/1/1967 IMPORT BUILT 0.00 1967: 2" - 3" AC ON 7" - 8" LIME 2.00 \checkmark ED ROCK BASE Network: SPACE COAST REG Branch: RW 9-27 RUNWAY 9-27 Section: 6205 Surface:AAC **L.C.D.** 1/1/1998 Use: RUNWAY Rank: S Length: 1,650.00 (Ft) Width: 100.00 (Ft) True Area: 169743.0000 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/1998 ML-OL Mill and Overlay 0.00 0.00 ~ 1/1/1976 IMPORT OVERLAY 0.00 1.50 \checkmark 1976: MINIMUM 1.5" P-401 ED OVERLAY. THIS PAVEMENT HAS 1/1/1943 IMPORT BUILT 0.00 3.00 \checkmark 1943: 3" - 4" AC ON 8" BASE ED Network: SPACE COAST REG Branch: RW 9-27 RUNWAY 9-27 Section: 6210 Surface:AAC L.C.D. 1/1/1998 Use: RUNWAY Rank: S Length: 3,200.00 (Ft) Width: 100.00 (Ft) True Area: 320000.0000 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/1998 1998 2.5" P401 OL-AS Overlay - AC Structural 0.00 2.50 1/1/1976 OL-AS Overlay - AC Structural 0.00 1.50 \checkmark 1976 1.5" P401 OVERLAY ON 1/1/1943 NC-AC New Construction - AC 0.00 3.50 1943 3.5" P401 ON 8" P211 Network: SPACE COAST REG Branch: TW A TAXIWAY A Section: 105 Surface:AAC L.C.D. 6/1/2002 Use: TAXIWAY Rank: P Length: 2,200.00 (Ft) Width: 50.00 (Ft) True Area: 114651.0000 (SqFt Work Major Thickness Work Date Work Description Cost Comments Code (in) M&R 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 V 1/1/1971 IMPORT OVERLAY 0.00 4.00 1971: MINIMUN 4" P-401 \checkmark ED OVERLAY. SOIL: SP. 1/1/1943 IMPORT BUILT 0.00 1.00 1943: 1" - 2" AC ON 8" BASE \checkmark ED Section: 110 Network: SPACE COAST REG Branch: TW A TAXIWAY A Surface:AAC L.C.D. 6/1/2002 Use: TAXIWAY Rank: P Length: 1,400.00 (Ft) Width: 50.00 (Ft) True Area: 70000.00002 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 6/1/2002 ML-OL Mill and Overlay 0.00 0.00 $|\checkmark|$ 1/1/1992 IMPORT REPAIR THERE IS A 1992 SLURRY SEAL 0.00 0.00 ED ON THIS FEATURE 1/1/1971 IMPORT OVERLAY 0.00 3.00 \checkmark 1971: MINIMUM 3" P-401 ED OVERLAY. SOIL: SP. 1/1/1943 IMPORT BUILT 1943: 1" - 2" AC ON 8" LIME ROCK 0.00 1.00 \checkmark ED BASE

Work History Report

Page 7 of 10

		Pavement Database:	FDOT			
Network:		DAST REG Branch: TW A		WAY A	Section:	
L.C.D. 6/1/2 Work Date	002 Us Work Code	se: TAXIWAY Rank: P L Work Description	Cost	.00 (Ft) Wid Thickness (in)	dth: 50.0 Major M&R	0 (Ft) True Area: 30000.00000 (Sql Comments
6/1/2002		Mill and Overlay	0.00	0.00		
1/1/1971		OVERLAY	0.00	3.00		1971: MINIMUN 3" P-401 OVERLAY. SOIL: SP.
1/1/1943	IMPORT ED	BUILT	0.00	1.00		1943: 1" - 2" AC ON 8" LIME ROCH BASE
Network:	SPACE CO	DAST REG Branch: TW A	TAXIV	WAY A	Section:	115 Surface:AAC
L.C.D. 6/1/2	002 Us	se: TAXIWAY Rank: P L	Length: 1,000	.00 (Ft) Wie	dth: 50.0	0 (Ft) True Area: 50000.00001 (Sq
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2002		Mill and Overlay	0.00	0.00		
1/1/1971	ED	OVERLAY	0.00	4.00		1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP.
1/1/1967	IMPORT ED	BOILI	0.00	2.00		1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE
Network:	SPACE CO	DAST REG Branch: TW A	TAXIV	WAY A	Section:	120 Surface:AAC
L.C.D. 6/1/2	002 Us	se: TAXIWAY Rank: P L	ength: 1,800	.00 (Ft) Wid	dth: 50.0	0 (Ft) True Area: 90638.00002 (Sq
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2002	ML-OL	Mill and Overlay	0.00	0.00		
1/1/1971	ED	OVERLAY	0.00	2.00		1971: MINIMUM 2" P-401 OVERLAY. SOIL: SP.
1/1/1967	IMPORT ED	BUILT	0.00	2.00		1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE
Notwork	SDACE CO	DAST REG Branch: TW A2) TAVI	WAY A2	Section:	125 Surface: AAC
L.C.D. 6/1/2					~~~~~~	0 (Ft) True Area: 35137.00001 (Sq
Work Date	Work Code			Thickness	Major	
		Work Description	Cost	(in)	M&R	Comments
5/1/2002	ML-OL	Mill and Overlay	Cost 0.00	× /	M&R ✓	Comments
1/1/1971	ML-OL IMPORT ED	Mill and Overlay OVERLAY	0.00	0.00 4.00	>	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP.
1/1/1971	ML-OL IMPORT	Mill and Overlay OVERLAY	0.00	0.00		1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP.
1/1/1971 1/1/1943	ML-OL IMPORT ED IMPORT ED	Mill and Overlay OVERLAY	0.00 0.00 0.00	0.00 4.00	>	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCI BASE
1/1/1971 1/1/1943 Network:	ML-OL IMPORT ED IMPORT ED	Mill and Overlay OVERLAY BUILT DAST REG Branch: TW B	0.00 0.00 0.00 TAXIV	0.00 4.00 1.00	Section:	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCI BASE 205 Surface: AAC
6/1/2002 1/1/1971 1/1/1943 Network: L.C.D. 6/1/2 Work Date	ML-OL IMPORT ED IMPORT ED	Mill and Overlay OVERLAY BUILT DAST REG Branch: TW B	0.00 0.00 0.00 TAXIV	0.00 4.00 1.00	Section:	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCI BASE
1/1/1971 1/1/1943 Network: L.C.D. 6/1/2	ML-OL IMPORT ED IMPORT ED SPACE CO 002 Us Work	Mill and Overlay OVERLAY BUILT DAST REG Branch: TW B se: TAXIWAY Rank: P L	0.00 0.00 0.00 TAXIV Length: 400	0.00 4.00 1.00 WAY B .00 (Ft) Wite Thickness	Section: dth: 50.0 Major	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCI BASE 205 Surface:AAC 0 (Ft) True Area: 22146.00000 (Sq
1/1/1971 1/1/1943 Network: L.C.D. 6/1/2 Work Date	ML-OL IMPORT ED IMPORT ED SPACE CO 002 Us Work Code ML-OL	Mill and Overlay OVERLAY BUILT DAST REG Branch: TW B se: TAXIWAY Rank: P L Work Description Mill and Overlay OVERLAY	0.00 0.00 0.00 TAXIV Length: 400	0.00 4.00 1.00 WAY B .00 (Ft) Wid Thickness (in)	Section: dth: 50.0 Major M&R	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCI BASE 205 Surface:AAC 0 (Ft) True Area: 22146.00000 (Sq

Work History Report

Page 8 of 10

Pavement Database: FDOT Network: SPACE COAST REG Branch: TW B TAXIWAY B Section: 210 Surface:AAC L.C.D. 1/1/2013 Use: TAXIWAY Rank: P Length: 4,600.00 (Ft) Width: 50.00 (Ft) True Area: 234359.0000 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/2013 ML-OV MILL and OVERLAY 0.00 1.50 2013: 1.5" Mill and Overlay \checkmark 1976 1.5" P401 OVERLAY. SEAL 1/1/1976 IMPORT OVERLAY 0.00 1.50 \checkmark ED COAT. 1/1/1943 IMPORT BUILT 0.00 1943 3.5" AC SURFACE ON 8" 3.50 \checkmark LIMEROCK BASE ED Network: SPACE COAST REG Branch: TW C TAXIWAY C Section: 305 Surface:AAC **L.C.D.** 1/1/2004 Use: TAXIWAY Rank: P Length: 700.00 (Ft) Width: 65.00 (Ft) True Area: 46879.00001 (SqFt Work Thickness Major Work Date Work Description Cost Comments (in) Code M&R 1/1/2004 ML-OL Mill and Overlay 0.00 0.00 ~ 1/1/1971 IMPORT OVERLAY 0.00 3.00 \checkmark 1971 3" P401 ED 1/1/1943 IMPORT BUILT 0.00 1.50 \checkmark 1943 1.5" AC SURFACE ON 8" ED LIMEROCK BASE Branch: TW C Network: SPACE COAST REG TAXIWAY C Section: 310 Surface:AAC L.C.D. 1/1/1986 Use: TAXIWAY Rank: P Length: 2,300.00 (Ft) Width: 50.00 (Ft) True Area: 116660.0000 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/1986 IMPORT OVERLAY 1986 1.5" AC SURFACE 0.00 1.50 \checkmark ED 1943 1.5" AC SURFACE ON 8" 1/1/1943 IMPORT BUILT 0.00 1.50 \checkmark LIMEROCK BASE ED Network: SPACE COAST REG Branch: TW C TAXIWAY C Section: 315 Surface:AAC **L.C.D.** 1/1/2013 Use: TAXIWAY Rank: P Width: 50.00 (Ft) True Area: 32856.00001 (SqFt Length: 600.00 (Ft) Work Thickness Major Work Date Work Description Cost Comments Code M&R (in) 1/1/2013 ML-OV MILL and OVERLAY 2013: 1.5" Mill and Overlay 0.00 0.00 IMPORT OVERLAY 1/1/1976 0.00 1976 1.5" P401 OVERLAY. 1.50 \checkmark ED EMULSION SEAL. 1/1/1943 IMPORT BUILT 0.00 1.50 1943 1.5" AC SURFACE ON 8" \checkmark LIMEROCK BASE ED Network: SPACE COAST REG Branch: TW D TAXIWAY D Section: 404 Surface:AAC L.C.D. 1/1/2000 Use: TAXIWAY Rank: T Length: 400.00 (Ft) Width: 50.00 (Ft) True Area: 26461.00000 (SqFt Work Thickness Major Work Date Work Description Cost Comments Code (in) M&R 1/1/2000 ML-OV MILL and OVERLAY 0.00 0.00 \checkmark IMPORT BUILT 1/1/1943 0.00 2.00 \checkmark 1943 2" AC ON 8" LIME ROCK ED BASE

10/4/2019

Work History Report

Page 9 of 10

Pavement	Database:	FDOT

Network:	SPACE CO	OAST REG Branch: TW D	TAXI	WAY D	Section:	408 Surface:AAC
L.C.D. 1/1/2	2000 Us	se: TAXIWAY Rank: P L	ength: 150	.00 (Ft) Wie	dth: 50.0	0 (Ft) True Area: 7500.000002 (SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OV	MILL and OVERLAY	0.00	0.00		
1/1/1943	NU-IN	New Construction - Initial	0.00	0.00		
Network:	SPACE CO	OAST REG Branch: TW D	TAXI	WAY D	Section:	410 Surface:AAC
L.C.D. 1/1/2	2000 Us	se: TAXIWAY Rank: P L	ength: 1,450	.00 (Ft) Wie	dth: 50.0	0 (Ft) True Area: 73750.00002 (SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OV	MILL and OVERLAY	0.00	0.00		
1/1/1985	IMPORT ED	BUILT	0.00	0.00		ESTIMATE 1985 AC PAVEMENT
Network:	SPACE CO	OAST REG Branch: TW E	TAXI	WAYE	Section:	505 Surface:AAC
L.C.D. 1/1/1					~~~~~~	0 (Ft) True Area: 32371.00000 (SqF
	Work			Thickness	Major	
Work Date	Code	Work Description	Cost	(in)	M&R	Comments
1/1/1998		MILL and OVERLAY	0.00	0.00		
1/1/1943	IMPORT ED	BUILT	0.00	2.00		ASSUME 1943 2" AC ON 8" LIMEROCK
Network:	SPACE CO	OAST REG Branch: TW E	TAXI	WAY E	Section:	515 Surface:AAC
L.C.D. 1/1/2	2003 Us	se: TAXIWAY Rank: P L	ength: 2,640	.00 (Ft) Wie	dth: 50.0	0 (Ft) True Area: 113522.0000 (SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	ML-OV	MILL and OVERLAY	0.00	0.00		
1/1/1943	IMPORT ED	BUILT	0.00	2.00		1943 2" AC ON 8" LIMEROCK
Network:	SPACE CO	OAST REG Branch: TW E	TAXI	WAY E	Section:	525 Surface:AC
L.C.D. 1/1/2	2014 Us	se: TAXIWAY Rank: P L	ength: 100	.00 (Ft) Wie	dth: 85.0	0 (Ft) True Area: 8165.000002 (SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	NU-IN	New Construction - Initial	0.00	0.00		
		OAST REG Branch: TW F		WAY F	Section:	
L.C.D. 1/1/1		se: TAXIWAY Rank: T L	ength: 580	ii		0 (Ft) True Area: 30388.00000 (SqF
	Work		Cost	Thickness	Major	Comments
Work Date	Code	Work Description		(in)	M&R	
1/1/1998	Code ML-OV	MILL and OVERLAY	0.00	0.00		
	Code	MILL and OVERLAY		、 <i>,</i>		1943: 2" AC ON 8" LIME ROCK BASE. SOIL: SP.

10/4/2019

Work History Report

Page 10 of 10

Pavement Database: FDOT

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	34	2,524,001.00	1.22	1.09
MILL and OVERLAY	38	2,706,680.00	0.04	0.24
New Construction - AC	2	325,405.00	1.75	1.75
New Construction - Initial	13	1,155,798.00	1.63	4.06
New Construction - PCC	2	145,277.00	0.00	0.00
OVERLAY	19	1,996,679.00	2.24	1.15
Overlay - AC	1	52,187.00	0.00	0.00
Overlay - AC Structural	2	640,000.00	2.00	0.50
REPAIR	7	286,981.00	0.00	0.00
Slurry Seal	1	52,187.00	0.00	0.00

10/4/2019		Pavement De		ondition Re	port		Page 1 of 2					
Branch IDNumber o SectionsAP E21AP HELI2		Sum Section Length (Ft)	n Avg Section True Ard Width (Ft) (SqFt)		Use	Average PCI	Standard Deviation PCI	Weighted Average PCI				
AP E	21	8,969.00	81.14	628,932.00	APRON	76.76	13.93	74.28				
AP HELI	2	1,219.00	290.00	397,538.00	APRON	93.50	3.50	96.42				
AP W	2	1,668.00	450.00	400,935.00	APRON	85.50	13.50	96.95				
RW 18-36	6	21,919.00	62.50	1,097,850.00	RUNWAY	61.67	2.62	61.25				
RW 9-27	2	4,850.00	100.00	489,743.00	RUNWAY	58.00	5.00	56.47				
TW A	5	7,000.00	50.00	355,289.00	TAXIWAY	66.60	1.02	66.62				
TW A2	1	600.00	500.00	35,137.00	TAXIWAY	65.00	0.00	65.00				
TW B	2	5,000.00	50.00	256,505.00	TAXIWAY	73.00	16.00	86.24				
TW C	3	3,600.00	55.00	196,395.00	TAXIWAY	73.00	10.80	68.38				
TW D	3	2,000.00	50.00	107,711.00	TAXIWAY	68.33	4.71	71.85				
TW E	3	3,340.00	61.67	154,058.00	TAXIWAY	78.67	10.87	71.69				
TW F	1	580.00	50.00	30,388.00	TAXIWAY	14.00	0.00	14.00				

10/4/2019 Branch Condition Report												
Pavement Database: FDOT												
Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI							
APRON	25	1,427,405.00	78.80	14.24	86.81							
RUNWAY	8	1,587,593.00	60.75	3.73	59.77							
TAXIWAY	18	1,135,483.00	67.67	16.14	71.08							
ALL	51	4,150,481.00	72.04	15.58	72.17							

Pavement Data	base: FDOT			Netw	vorkId:	: TIX				
		Last Const.			_ .		True Area	Last	Age At	
Branch ID	Section ID	Date	Surface	Use	капк	Lanes	(SqFt)	Inspection Date	inspec tion	PCI
AP E	4205	1/1/2008	AAC	APRON	Р	0	101,014.00	3/4/2019	11	62
AP E	4211	6/1/2002	AAC	APRON	Р	0	3,845.00	3/4/2019	17	67
AP E	4214	6/1/2002	APC	APRON	Р	0	52,187.00	3/4/2019	17	56
AP E	4215	1/1/1971	AC	APRON	Р	0	82,925.00	3/4/2019	48	45
AP E	4216	1/1/2008	AAC	APRON	Р	0	48,836.00	3/4/2019	11	82
AP E	4218	1/1/2008	AAC	APRON	Р	0	95,344.00	3/4/2019	11	80
AP E	4219	1/1/2015	AAC	APRON	Р	0	8,237.00	3/4/2019	4	56
AP E	4220	1/1/2014	AAC	APRON	Р	0	8,168.00		5	83
AP E	4221	1/1/2008	AC	APRON	Р	0	5,405.00		11	71
AP E	4225	1/1/1991	PCC	APRON	P	0	8,700.00	3/4/2019	28	69
AP E	4226	1/1/2014	AAC	APRON	P	0	6,677.00	3/4/2019	5	72
AP E	4227	1/1/2014	AAC	APRON	P	0	6,560.00	3/4/2019	5	89
AP E	4228	1/1/2014	AAC	APRON	P	0	11,100.00		5	89
AP E	4229	1/1/2012	AC	APRON	P	0	16,315.00		7	88
AP E	4230	1/1/1991	PCC	APRON	P	0	9,576.00	3/4/2019	28	77
AP E	4232	1/1/2014	AAC	APRON	P	0	9,960.00	3/4/2019	5	79
AP E	4235	1/1/2015	PCC	APRON	P	0	93,090.00	3/4/2019	4	99
APE	4240	1/1/2014	AAC	APRON	P	0	7,020.00		5	91
APE	4241	1/1/2014	AAC	APRON	P	0	8,553.00		5	91
APE	4245	1/1/2003	AC	APRON	P	0	7,200.00	3/4/2019	16	71
AP E	4250	1/1/2011	PCC	APRON	Р	0	38,220.00	3/4/2019	8	95
AP HELI	4255	1/1/2012	AC	APRON	Р	0	32,798.00		7	90
AP HELI	4260	1/1/2012	PCC	APRON	Р	0	364,740.00	3/4/2019	7	97
AP W	4305	1/1/2014	PCC	APRON	Р	0	370,471.00	3/4/2019	5	99
AP W	4310	1/1/2014	AAC	APRON	Р	0	30,464.00	3/4/2019	5	72
RW 18-36	6105	6/1/2002	AAC	RUNWAY	Р	0	500,000.00	3/4/2019	17	62
RW 18-36	6110	6/1/2002	AAC	RUNWAY	Р	0	250,000.00	3/4/2019	17	57
RW 18-36	6125	6/1/2002	AAC	RUNWAY	Р	0	100,000.00	3/4/2019	17	62
RW 18-36	6130	6/1/2002	AAC	RUNWAY	Р	0	50,000.00	3/4/2019	17	60
RW 18-36	6145	6/1/2002	AAC	RUNWAY	Р	0	131,900.00	3/4/2019	17	65
RW 18-36	6150	6/1/2002	AAC	RUNWAY	Р	0	65,950.00	3/4/2019	17	64
RW 9-27	6205	1/1/1998	AAC	RUNWAY	S	0	169,743.00	3/4/2019	21	63
RW 9-27	6210	1/1/1998	AAC	RUNWAY	S	0	320,000.00	3/4/2019	21	53
TW A	105	6/1/2002	AAC	TAXIWAY	Р	0	114,651.00	3/4/2019	17	68
TW A	110	6/1/2002	AAC	TAXIWAY	Р	0	70,000.00		17	66
TW A	112	6/1/2002	AAC	TAXIWAY	Р	0	30,000.00	3/4/2019	17	67
TW A	115	6/1/2002	AAC	TAXIWAY	Р	0	50,000.00	3/4/2019	17	67
TW A	120	6/1/2002	AAC	TAXIWAY	Р	0	90,638.00	3/4/2019	17	65
TW A2	125	6/1/2002	AAC	TAXIWAY	Р	0	35,137.00	3/4/2019	17	65
TW B	205	6/1/2002	AAC	TAXIWAY	Р	0	22,146.00	3/4/2019	17	57
TW B	210	1/1/2013	AAC	TAXIWAY	Р	0	234,359.00	3/4/2019	6	89
TW C	305	1/1/2004	AAC	TAXIWAY	P	0	46,879.00	3/4/2019	15	68
TW C	310	1/1/1986	AAC	TAXIWAY	Р	0	116,660.00		33	63
TW C	315	1/1/2013	AAC	TAXIWAY	Р	0	32,856.00	3/4/2019	6	88
TW D	404	1/1/2000	AAC	TAXIWAY	T	0	26,461.00	3/4/2019	19	65
TW D	408	1/1/2000	AAC	TAXIWAY	P	0	7,500.00		19	65
TW D	410	1/1/2000	AAC	TAXIWAY	P	0	73,750.00		19	75
TW E	505	1/1/1998	AAC	TAXIWAY	P	0	32,371.00		21	72
TWE	515	1/1/2003	AAC	TAXIWAY	P	0	113,522.00		16	70
TWE	525	1/1/2014	AC	TAXIWAY	P	0	8,165.00		5	94
		., ,, _ 0 14			<u> </u>	. ~	0,.00.00	0, 1/2010		

Pavement Management System

PAVER 7.0 TM

10/4/2019		Section Condition Rep	ort	Page 2 of 3				
TW F	605	1/1/1998 AAC TAXIWAY	T 0	30,388.00 3/4/2019	21 14			

10/4/2019

Section Condition Report (Summary)

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI								
03-05	5	568,465.00	12	84.50	12.22	95.43								
06-10	7	719,288.00	6	91.17	3.53	93.35								
11-15	12	297,478.00	5	72.60	7.47	72.16								
16-20	17	1,794,887.00	20	64.70	4.66	63.42								
21-25	21	552,502.00	4	50.50	22.12	55.04								
26-30	28	18,276.00	2	73.00	4.00	73.19								
31-35	33	116,660.00	1	63.00	0.00	63.00								
41-50	48	82,925.00	1	45.00	0.00	45.00								
ALL	14	4,150,481.00	51	72.04	15.58	72.17								

Pavement Database: FDOT

Statewide Airfield Pavement Management Program



Appendix B

Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation

Table B-1 Localized Maintenance	and Repair Needs	based on	Current	Condition
---------------------------------	------------------	----------	---------	-----------

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit (Cost	W	/ork Cost
ТІХ	AP E	4205	57	WEATHERING	Medium	26835.94	SqFt	26.6%	FDOT - SURFACE SEAL	26835.5	SqFt	\$	0.55	\$	14,760.00
ТІХ	AP E	4211	52	RAVELING	Low	141.98	SqFt	3.7%	FDOT - SURFACE SEAL	142.1	SqFt	\$	0.55	\$	80.00
ТІХ	AP E	4211	57	WEATHERING	Medium	2703.03	SqFt	70.3%	FDOT - SURFACE SEAL	2702.8	SqFt	\$	0.55	\$	1,490.00
ТІХ	AP E	4214	47	JT REF. CR	Medium	1043.73	Ft	2.0%	FDOT - CRACK SEALING - AC		Ft	\$	3.00	\$	3,140.00
ТІХ	AP E	4214	48	L & T CR	Medium	613.98	Ft	1.2%	FDOT - CRACK SEALING - AC	613.9	Ft	\$	3.00	\$	1,850.00
ТІХ	AP E	4214	52	RAVELING	Low	429.8	SqFt	0.8%	FDOT - SURFACE SEAL	429.5	SqFt	\$	0.55	\$	240.00
ТІХ	AP E	4214	57	WEATHERING	Medium	23023.68	SqFt	44.1%	FDOT - SURFACE SEAL	23024	SqFt	\$	0.55	\$	12,670.00
ТІХ	AP E	4215	52	RAVELING	Low	31390.04	SqFt	37.9%	FDOT - SURFACE SEAL	31389.7	SqFt	\$	0.55	\$	17,270.00
ТІХ	AP E	4215	52	RAVELING	Medium	51534.91	SqFt	62.2%	FDOT - PATCHING - AC PARTIAL DEPTH	51535.5	SqFt	\$	5.50	\$	283,450.00
ТІХ	AP E	4216	57	WEATHERING	Medium	12204.34	SqFt	25.0%	FDOT - SURFACE SEAL	12204.1	SqFt	\$	0.55	\$	6,720.00
ТІХ	AP E	4218	57	WEATHERING	Medium	23836.03	SqFt	25.0%	FDOT - SURFACE SEAL	23835.6	SqFt	\$	0.55	\$	13,110.00
ТІХ	AP E	4219	52	RAVELING	Low	4562.5	SqFt	55.4%	FDOT - SURFACE SEAL	4562.8	SqFt	\$	0.55	\$	2,510.00
ТІХ	AP E	4220	52	RAVELING	Low	406.77	SqFt	5.0%	FDOT - SURFACE SEAL	406.9	SqFt	\$	0.55	\$	230.00
ТІХ	AP E	4221	52	RAVELING	Low	106.99	SqFt	2.0%	FDOT - SURFACE SEAL	106.6	SqFt	\$	0.55	\$	60.00
ТІХ	AP E	4221	57	WEATHERING	Medium	1499.95	SqFt	27.8%	FDOT - SURFACE SEAL	1500.5	SqFt	\$	0.55	\$	830.00
ТІХ	AP E	4225	72	SHAT. SLAB	Low	1.85	Slabs	3.9%	FDOT - CRACK SEALING - PCC	49.9	Ft	\$	4.25	\$	220.00
ТІХ	AP E	4226	52	RAVELING	Low	58.02	SqFt	0.9%	FDOT - SURFACE SEAL	58.1	SqFt	\$	0.55	\$	40.00
ТІХ	AP E	4227	52	RAVELING	Low	64.48	SqFt	1.0%	FDOT - SURFACE SEAL	64.6	SqFt	\$	0.55	\$	40.00
ТІХ	AP E	4228	52	RAVELING	Low	110.01	SqFt	1.0%	FDOT - SURFACE SEAL	109.8	SqFt	\$	0.55	\$	70.00
ТІХ	AP E	4229	52	RAVELING	Low	162.1	SqFt	1.0%	FDOT - SURFACE SEAL	162.5	SqFt	\$	0.55	\$	90.00
ТІХ	AP E	4232	52	RAVELING	Low	186.97	SqFt	1.9%	FDOT - SURFACE SEAL	187.3	SqFt	\$	0.55	\$	110.00
ТІХ	AP E	4240	52	RAVELING	Low	69.86	SqFt	1.0%	FDOT - SURFACE SEAL	70	SqFt	\$	0.55	\$	40.00
ТІХ	AP E	4241	52	RAVELING	Low	86.11	SqFt	1.0%	FDOT - SURFACE SEAL	86.1	SqFt	\$	0.55	\$	50.00
ΤΙΧ	AP E	4245	52	RAVELING	Low	360.05	SqFt	5.0%	FDOT - SURFACE SEAL	359.5	SqFt	\$	0.55	\$	200.00
ТІХ	AP E	4245	57	WEATHERING	Medium	6840.03	SqFt	95.0%	FDOT - SURFACE SEAL	6840.5	SqFt	\$	0.55	\$	3,770.00
ТІХ	AP HELI	4260	74	JOINT SPALL	Low	29.28	Slabs	1.1%	FDOT - CRACK SEALING - PCC	47.9	Ft	\$	4.25	\$	210.00
ТІХ	AP HELI	4260	75	CORNER SPALL	Medium	9.76	Slabs	0.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	25.8	SqFt	\$7	2.00	\$	1,900.00
TIX	AP W	4310	48	L&TCR	Medium	240.62	Ft	0.8%	FDOT - CRACK SEALING - AC	240.5	Ft	\$	3.00	\$	730.00
ТІХ	AP W	4310	57	WEATHERING	Medium	11567.44	SqFt	38.0%	FDOT - SURFACE SEAL	11566.9	SqFt	\$	0.55	\$	6,370.00
ТІХ	RW 18-36	6105	48	L&TCR	Medium	8314.99	Ft	1.7%	FDOT - CRACK SEALING - AC	8315	Ft	\$			24,950.00
TIX	RW 18-36	6105	48	L&TCR	High	25	Ft	0.0%	FDOT - CRACK SEALING - AC	24.9	Ft	\$	3.00	\$	80.00
ТІХ	RW 18-36	6105	52	RAVELING	Low	29500	SqFt	5.9%	FDOT - SURFACE SEAL	29499.6	SqFt	\$	0.55	\$	16,230.00
ТІХ	RW 18-36	6105	52	RAVELING	Medium	199.99	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	200.2	SqFt		5.50	\$	1,100.00
ТІХ	RW 18-36	6105	52	RAVELING	High	14.96	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	15.1	SqFt	\$	5.50	\$	90.00
ТІХ	RW 18-36	6105	57	WEATHERING	Medium	212000.06	SqFt	42.4%	FDOT - SURFACE SEAL	211999.5	SqFt	\$	0.55	\$	116,610.00
ТІХ	RW 18-36	6110	48	L&TCR	Medium	7250	Ft	2.9%	FDOT - CRACK SEALING - AC	7250	Ft	\$		\$	21,750.00
ТІХ	RW 18-36	6110	52	RAVELING	Low	12225	SqFt	4.9%	FDOT - SURFACE SEAL	12224.6	SqFt	\$	0.55	\$	6,730.00




121

Statewide Airfield Pavement Airport Pavement **Management Program Evaluation Report**

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Uni	it Cost	
ТІХ	RW 18-36	6110	57	WEATHERING	Medium	119535.06	SqFt	47.8%	FDOT - SURFACE SEAL	119535.4	SqFt	\$	0.55	Γ
ТІХ	RW 18-36	6125	48	L&TCR	Medium	948	Ft	1.0%	FDOT - CRACK SEALING - AC	948.2	Ft	\$	3.00	Т
ТІХ	RW 18-36	6125	52	RAVELING	Low	3599.99	SqFt	3.6%	FDOT - SURFACE SEAL	3600.5	SqFt	\$	0.55	Γ
ТІХ	RW 18-36	6125	52	RAVELING	Medium	20.02	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	20.5	SqFt	\$	5.50	Г
ТІХ	RW 18-36	6125	57	WEATHERING	Medium	38400.04	SqFt	38.4%	FDOT - SURFACE SEAL	38400.3	SqFt	\$	0.55	
ТІХ	RW 18-36	6130	48	L&TCR	Medium	2250	Ft	4.5%	FDOT - CRACK SEALING - AC	2250	Ft	\$	3.00	Т
ТІХ	RW 18-36	6130	57	WEATHERING	Medium	25000.04	SqFt	50.0%	FDOT - SURFACE SEAL	25000.3	SqFt	\$	0.55	
ТІХ	RW 18-36	6145	48	L&TCR	Medium	58.83	Ft	0.0%	FDOT - CRACK SEALING - AC	58.7	Ft	\$	3.00	
ТІХ	RW 18-36	6145	50	PATCHING	Medium	151.99	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	205.6	SqFt	\$	12.50	
ТІХ	RW 18-36	6145	52	RAVELING	Low	5977.2	SqFt	4.5%	FDOT - SURFACE SEAL	5977.2	SqFt	\$	0.55	
ТІХ	RW 18-36	6145	57	WEATHERING	Medium	90711.89	SqFt	68.8%	FDOT - SURFACE SEAL	90711.8	SqFt	\$	0.55	
ТІХ	RW 18-36	6150	48	L&TCR	Medium	1918.54	Ft	2.9%	FDOT - CRACK SEALING - AC	1918.6	Ft	\$	3.00	
ТІХ	RW 18-36	6150	52	RAVELING	Low	1141.51	SqFt	1.7%	FDOT - SURFACE SEAL	1142.1	SqFt	\$	0.55	
ТІХ	RW 18-36	6150	57	WEATHERING	Medium	56117.43	SqFt	85.1%	FDOT - SURFACE SEAL	56117.7	SqFt	\$	0.55	
ТІХ	RW 9-27	6205	48	L&TCR	Medium	969.95	Ft	0.6%	FDOT - CRACK SEALING - AC	969.8	Ft	\$	3.00	
ТІХ	RW 9-27	6205	52	RAVELING	Low	12366.98	SqFt	7.3%	FDOT - SURFACE SEAL	12366.7	SqFt	\$	0.55	
ТІХ	RW 9-27	6205	57	WEATHERING	Medium	68018.44	SqFt	40.1%	FDOT - SURFACE SEAL	68018.2	SqFt	\$	0.55	
ТІХ	RW 9-27	6210	48	L & T CR	Medium	1550.75	Ft	0.5%	FDOT - CRACK SEALING - AC	1550.9	Ft	\$	3.00	
ТІХ	RW 9-27	6210	52	RAVELING	Low	34953.86	SqFt	10.9%	FDOT - SURFACE SEAL	34953.7	SqFt	\$	0.55	
ТІХ	RW 9-27	6210	56	SWELLING	Medium	492.34	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	585.6	SqFt	\$	12.50	
ТІХ	RW 9-27	6210	57	WEATHERING	Medium	138461.56	SqFt	43.3%	FDOT - SURFACE SEAL	138461.6	SqFt	\$	0.55	
ТІХ	TW A	105	48	L & T CR	Medium	1122.28	Ft	1.0%	FDOT - CRACK SEALING - AC	1122.4	Ft	\$	3.00	
ТІХ	TW A	105	57	WEATHERING	Medium	114651.04	SqFt	100.0%	FDOT - SURFACE SEAL	114650.7	SqFt	\$	0.55	
ТІХ	TW A	110	52	RAVELING	Low	933.34	SqFt	1.3%	FDOT - SURFACE SEAL	933.2	SqFt	\$	0.55	
ΤΙΧ	TW A	110	57	WEATHERING	Medium	69066.63	SqFt	98.7%	FDOT - SURFACE SEAL	69066.6	SqFt	\$	0.55	
ΤΙΧ	TW A	112	48	L & T CR	Medium	300	Ft	1.0%	FDOT - CRACK SEALING - AC	299.9	Ft	\$	3.00	
ТІХ	TW A	112	52	RAVELING	Low	599.98	SqFt	2.0%	FDOT - SURFACE SEAL	599.6	SqFt	\$	0.55	
ТІХ	TW A	112	57	WEATHERING	Medium	29400.01	SqFt	98.0%	FDOT - SURFACE SEAL	29399.5	SqFt	-	0.55	-
TIX	TW A	115	48	L & T CR	Medium	500	Ft	1.0%	FDOT - CRACK SEALING - AC	500	Ft	\$	3.00	-
ТІХ	TW A	115	52	RAVELING	Low	999.97	SqFt	2.0%	FDOT - SURFACE SEAL	1000	SqFt	\$	0.55	
TIX	TW A	115	57	WEATHERING	Medium	49000.01	SqFt	98.0%	FDOT - SURFACE SEAL	48999.5	SqFt	\$	0.55	
TIX	TW A	120	48	L&TCR	Medium	1650.95	Ft	1.8%	FDOT - CRACK SEALING - AC	1650.9	Ft	\$	3.00	+
ТІХ	TW A	120	52	RAVELING	Low	3406.45	SqFt	3.8%	FDOT - SURFACE SEAL	3406.8	SqFt		0.55	-
ТІХ	TW A	120	57	WEATHERING	Medium	85580.51	SqFt	94.4%	FDOT - SURFACE SEAL	85580.6	SqFt	\$		-
TIX	TW A2	125	48	L&TCR	Medium	593.83	Ft	1.7%	FDOT - CRACK SEALING - AC	593.8	Ft	-	3.00	
TIX	TW A2	125	52	RAVELING	Low	1006.53	SqFt	2.9%	FDOT - SURFACE SEAL	1006.4	SqFt	\$	0.55	
TIX	TW A2	125	57	WEATHERING	Medium	21567.97	SqFt	61.4%	FDOT - SURFACE SEAL	21567.7	SqFt	-	0.55	
ТІХ	TW B	205	52	RAVELING	Low	1107.28	SqFt	5.0%	FDOT - SURFACE SEAL	1107.6	SqFt	\$	0.55	-
ΤΙΧ	TW B	205	57	WEATHERING	Medium	21038.71	SqFt	95.0%	FDOT - SURFACE SEAL	21039.1	SqFt	\$	0.55	








121

Work Cost

Statewide Airfield Pavement Airport Pavement **Management Program Evaluation Report**

Network	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	
ID TIX	TW B	210	52	RAVELING	Low	329.7	SqFt	0.1%	FDOT - SURFACE SEAL	329.4	-
TIX	TW C	305	52	RAVELING	Low	1536.33	SaFt	3.3%	FDOT - SURFACE SEAL	1536	ł
TIX	TW C	305	57	WEATHERING	Medium	35792.37	SqFt	76.4%	FDOT - SURFACE SEAL	35792.2	f
TIX	TW C	310	48	L & T CR	Medium	3218.6	Ft	2.8%	FDOT - CRACK SEALING - AC	3218.5	ŀ
тіх	TW C	310	52	RAVELING	Low	55213.8	SqFt	47.3%	FDOT - SURFACE SEAL	55213.5	f
тіх	TW C	310	52	RAVELING	Medium	1170.36	SqFt	1.0%	FDOT - PATCHING - AC PARTIAL DEPTH	1170	F
тіх	TW C	310	57	WEATHERING	Medium	36575.12	SqFt	31.4%	FDOT - SURFACE SEAL	36574.7	٢
тіх	TW D	404	48	L&TCR	Medium	264.6	Ft	1.0%	FDOT - CRACK SEALING - AC	264.8	ľ
тіх	TW D	404	52	RAVELING	Low	1323.1	SqFt	5.0%	FDOT - SURFACE SEAL	1322.9	Ē
ТІХ	TW D	404	57	WEATHERING	Medium	25137.93	SqFt	95.0%	FDOT - SURFACE SEAL	25138	ſ
тіх	TW D	408	48	L&TCR	Medium	150	Ft	2.0%	FDOT - CRACK SEALING - AC	149.9	Γ
тіх	TW D	408	52	RAVELING	Low	375.98	SqFt	5.0%	FDOT - SURFACE SEAL	375.7	ſ
тіх	TW D	408	57	WEATHERING	Medium	7123.99	SqFt	95.0%	FDOT - SURFACE SEAL	7123.6	Γ
ТІХ	TW D	410	52	RAVELING	Low	1008.36	SqFt	1.4%	FDOT - SURFACE SEAL	1008.6	Γ
тіх	TW D	410	57	WEATHERING	Medium	45923.47	SqFt	62.3%	FDOT - SURFACE SEAL	45923.2	Γ
ТІХ	TW E	505	48	L&TCR	Medium	323.72	Ft	1.0%	FDOT - CRACK SEALING - AC	323.8	ſ
тіх	TW E	505	57	WEATHERING	Medium	20231.85	SqFt	62.5%	FDOT - SURFACE SEAL	20231.9	
ТІХ	TW E	515	45	DEPRESSION	Low	157.26	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	212.1	
тіх	TW E	515	52	RAVELING	Low	2207.25	SqFt	1.9%	FDOT - SURFACE SEAL	2207.7	
тіх	TW E	515	52	RAVELING	Medium	15.72	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	16.2	
ΤΙΧ	TW E	515	57	WEATHERING	Medium	70310.94	SqFt	61.9%	FDOT - SURFACE SEAL	70310.9	
ТІХ	TW F	605	41	ALLIGATOR CR	Medium	448.32	SqFt	1.5%	FDOT - PATCHING - AC FULL DEPTH	537.1	
тіх	TW F	605	41	ALLIGATOR CR	High	7.64	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	22.6	
ТІХ	TW F	605	43	BLOCK CR	Medium	26447.47	SqFt	87.0%	FDOT - CRACK SEALING - AC	8061.4	
тіх	TW F	605	50	PATCHING	Medium	25.51	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	49.5	
тіх	TW F	605	52	RAVELING	Medium	24048.08	SqFt	79.1%	FDOT - PATCHING - AC PARTIAL DEPTH	24047.7	
тіх	TW F	605	52	RAVELING	High	15.28	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	15.1	







121

Appendix B **B-3**

Dobabilitation T

141

Dianning



Statewide Airfield Pavement
Management ProgramAirport Pavement
Evaluation Report

ort Pavement	201	Q
uation Report	201	5

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ΤΙΧ	AP E	4205	AAC	101,014	61	AC Restoration	\$ 1,112,000.00
2020	ΤΙΧ	AP E	4214	APC	52,187	54	AC Restoration	\$ 575,000.00
2020	ΤΙΧ	AP E	4215	AC	82,925	43	AC Restoration	\$ 1,070,000.00
2020	тіх	AP E	4219	AAC	8,237	54	AC Restoration	\$ 91,000.00
2020	ΤΙΧ	RW 18-36	6105	AAC	500,000	59	AC Restoration	\$ 5,500,000.00
2020	ΤΙΧ	RW 18-36	6110	AAC	250,000	55	AC Restoration	\$ 2,750,000.00
2020	ΤΙΧ	RW 18-36	6125	AAC	100,000	59	AC Restoration	\$ 1,100,000.00
2020	ΤΙΧ	RW 18-36	6130	AAC	50,000	58	AC Restoration	\$ 550,000.00
2020	ΤΙΧ	RW 18-36	6145	AAC	131,900	62	AC Restoration	\$ 1,451,000.00
2020	ТІХ	RW 18-36	6150	AAC	65,950	61	AC Restoration	\$ 726,000.00
2020	ΤΙΧ	RW 9-27	6205	AAC	169,743	60	AC Restoration	\$ 1,868,000.00
2020	ΤΙΧ	RW 9-27	6210	AAC	320,000	52	AC Restoration	\$ 3,520,000.00
2020	ΤΙΧ	TW A	110	AAC	70,000	64	AC Restoration	\$ 770,000.00
2020	ΤΙΧ	TW A	120	AAC	90,638	63	AC Restoration	\$ 997,000.00
2020	ΤΙΧ	TW A2	125	AAC	35,137	63	AC Restoration	\$ 387,000.00
2020	ТІХ	TW B	205	AAC	22,146	56	AC Restoration	\$ 244,000.00
2020	ΤΙΧ	TW C	310	AAC	116,660	62	AC Restoration	\$ 1,284,000.00
2020	ΤΙΧ	TW D	404	AAC	26,461	63	AC Restoration	\$ 292,000.00
2020	ΤΙΧ	TW D	408	AAC	7,500	63	AC Restoration	\$ 83,000.00
2020	ТІХ	TW F	605	AAC	30,388	10	AC Reconstruction	\$ 426,000.00
2021	тіх	AP E	4211	AAC	3,845	63	AC Restoration	\$ 43,000.00
2021	тіх	TW A	112	AAC	30,000	64	AC Restoration	\$ 330,000.00
2021	ТІХ	TW A	115	AAC	50,000	64	AC Restoration	\$ 550,000.00
2022	ΤΙΧ	AP E	4225	PCC	8,700	64	PCC Restoration	\$ 148,000.00
2022	ΤΙΧ	TW A	105	AAC	114,651	63	AC Restoration	\$ 1,262,000.00
2022	тіх	TW C	305	AAC	46,879	63	AC Restoration	\$ 516,000.00

Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

DCI


Statewide A Managemen		Airport Pavement Evaluation Report	2019			[st Regional t (TIX)		FDOT
	Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost	
	2023	ТІХ	AP E	4221	AC	5,405	64	AC Restoration	\$ 60,000.00	
	2023	ТІХ	AP E	4226	AAC	6,677	64	AC Restoration	\$ 74,000.00	
	2023	ТІХ	AP E	4245	AC	7,200	64	AC Restoration	\$ 80,000.00	
	2023	ТІХ	AP W	4310	AAC	30,464	64	AC Restoration	\$ 336,000.00	
	2023	тіх	TW E	515	AAC	113,522	64	AC Restoration	\$ 1,249,000.00	
	2024	ТІХ	TW E	505	AAC	32,371	64	AC Restoration	\$ 357,000.00	
	2026	тіх	AP E	4218	AAC	95,344	64	AC Restoration	\$ 1,049,000.00	
	2026	ТІХ	AP E	4232	AAC	9,960	63	AC Restoration	\$ 110,000.00	
	2026	тіх	TW D	410	AAC	73,750	63	AC Restoration	\$ 812,000.00	
	2027	ТІХ	AP E	4216	AAC	48,836	63	AC Restoration	\$ 538,000.00	
	2027	тіх	AP E	4220	AAC	8,168	64	AC Restoration	\$ 90,000.00	
	2028	ТІХ	AP E	4230	PCC	9,576	64	PCC Restoration	\$ 163,000.00	
	2029	ТІХ	AP E	4227	AAC	6,560	64	AC Restoration	\$ 73,000.00	
	2029	ТІХ	AP E	4228	AAC	11,100	64	AC Restoration	\$ 123,000.00	

Statewide Airfield Pavement Management Program





Appendix C


Technical Exhibits











CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY


UCTION AR	LOCATION	WORK TYPE / PAVEMENT SECTION
13	тw в, тw с	MILL AND OVERLAY / 1.5" MILL AND OVERLAY
14	AP E	MILL AND OVERLAY - VARIABLE DEPTH
14	AP W	NEW CONSTRUCTION - PCC / 14" P-501, 6" P-211, 20" P-152
14	AP W	MILL AND OVERLAY
14	TW E	NEW CONSTRUCTION - AC
15	AP E	NEW CONSTRUCTION - PCC / 14" P-501, 6" P-211, COMPACTED SAND SUBGRADE
15	AP E	MILL AND OVERLAY

LEGEND


PROJECTS	YEAR	2013
PROJECTS	YEAR	2014
PROJECTS	YEAR	2015
PROJECTS	YEAR	2016
PROJECTS	YEAR	2017
PROJECTS	YEAR	2018
PROJECTS	YEAR	2019
PROJECTS	YEAR	2020
PROJECTS	YEAR	2021
PROJECTS	YEAR	2022


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.












RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.








W 13-31	TYPICAL	RUNWAY BRANCH ID
TWA	TYPICAL	TAXIWAY BRANCH ID
AP S	TYPICAL	APRON BRANCH ID

Statewide Airfield Pavement Management Program



Appendix D

Inspection Photograph Documentation



2019

Space Coast Regional Airport (TIX)





RUNWAY 9-27, Section 6210, Sample Unit 148 - Low Severity (43) Block Cracking, Low Severity (48) Longitudinal & Transverse Cracking, and Low Severity (57) Weathering



RW 9-27, Section 6210, Sample Unit 162 - Low Severity (43) Block Cracking, Low Severity (48) Longitudinal & Transverse Cracking, Medium Severity (48) Longitudinal & Transverse Cracking, Low Severity (57) Weathering, and Medium Severity (57) Weathering







RW 18-36, Section 6105, Sample Unit 386 - Severity (48) Longitudinal & Transverse Cracking, High Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Medium Severity (52) Raveling



RW 18-36, Section 6110, Sample Unit 176 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering





TW A, Section 120, Sample Unit 162 - Low Severity (48) Longitudinal & Transverse Cracking, Medium Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering



TW B, Section 205, Sample Unit 502 - Low Severity (43) Block Cracking, Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering







Appendix D D-4



TW F, Section 605, Sample Unit 301 - Medium Severity (43) Block Cracking, Low Severity (50) Patching, and Medium Severity (52) Raveling



AP E, Section 4205, Sample Unit 250 - Low Severity (43) Block Cracking, Low Severity (48) Longitudinal & Transverse Cracking, and Low Severity (57) Weathering



AP HELI, Section 4260, Sample Unit 643 - Low Severity (75) Corner Spall


FDOT

Statewide Airfield Pavement Management Program



Appendix E

Inspection Distress Details



Re-Inspection Report

FDO'														
-	rated Date	1	10/4/2019]	Page 1 of
Netw	ork: TIX				Nan	ne: SPA	ACE COAST	REGION	AL AIRPO	RT				
Bran	ch: AP E		Name:	EAST	APRO	N	Use:	APRO	N	Area:	6	28,932 \$	SqFt	
Sectio	on: 4205	of 2	21	From:				To:	-			Last (Const.:	1/1/2008
Surfa	ce: AAC	Family: C	9N59-PR	AP-AAC-APC	Zon	e:		Cat	egory:			Rank	: P	
Area	10	01,014 SqFt	Lengtl	h:	784 F	't	Width:		188 Ft					
Slabs	:	Slab Lengtl	1:	Ft		Slab Width:		Ft		Joir	nt Length:		Ft	
Shou	der:	Street Type	:			Grade: 0				Lar	nes: 0			
Sectio	on Comments:													
Work	Date: 1/1/1968	Work	« Type: BU	JILT			C	ode: IM	PORTED		Is Major I	M&R:	Гrue	
Work	Date: 1/1/1992	Work	« Type: RI	EPAIR			C	ode: IM	PORTED		Is Major 1	M&R: 1	False	
Work	Date: 1/1/2008	Work	Type: M	ILL and OVEI	RLAY		C	ode: MI	L-OV		Is Major I	M&R:	Гrue	
Cond	itione: DC1.	62												
	itions: PCI: ction Comments:	02												
Inspe			R	A	rea:	501	1.00 SqFt		PCI: 62					
Inspe Samp	ction Comments:		R	A	.rea:	501	1.00 SqFt		PCI: 62					
Inspe Samp Samp	ction Comments: le Number: 150		R	A 1400.00		501	1.00 SqFt		PCI: 62					
Inspe Samp Samp 43 57	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING		L M		SqFt	501	1.00 SqFt		PCI: 62					
Inspe Samp Samp 43 57 57	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING WEATHERING		L M L	1400.00 1511.00 3500.00	SqFt SqFt SqFt	501	1.00 SqFt		PCI: 62					
Inspe Samp Samp 43 57 57 48	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING WEATHERING L & T CR	Туре:	L M	1400.00 1511.00	SqFt SqFt SqFt	501	1.00 SqFt		PCI: 62					
Inspe Samp Samp 43 57 57 48	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING WEATHERING	Туре:	L M L	1400.00 1511.00 3500.00 25.00	SqFt SqFt SqFt		1.00 SqFt 0.00 SqFt		PCI: 62					
Inspe Samp Samp 43 57 57 48 Samp	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING WEATHERING L & T CR	Туре:	L M L L	1400.00 1511.00 3500.00 25.00	SqFt SqFt SqFt Ft									
Inspe Samp Samp 43 57 57 48 Samp	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING WEATHERING L & T CR le Number: 203	Туре: Туре:	L M L L	1400.00 1511.00 3500.00 25.00	SqFt SqFt SqFt Ft .rea:									
Inspe Samp 43 57 57 48 Samp 57	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING WEATHERING L & T CR le Number: 203 le Comments:	Туре: Туре:	L M L L R	1400.00 1511.00 3500.00 25.00	SqFt SqFt SqFt Ft srea:									
Inspe Samp 43 57 57 48 Samp 57 48	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING	Туре: Туре:	L M L L R	1400.00 1511.00 3500.00 25.00 A 4398.00	SqFt SqFt SqFt Ft rea: SqFt Ft									
Inspe Samp 43 57 57 48 Samp 57 48 57 48 57	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING L & T CR	Туре: Туре:	L M L L R	1400.00 1511.00 3500.00 25.00 A 4398.00 412.00 1466.00	SqFt SqFt SqFt Ft rea: SqFt Ft									
Inspe Samp Samp 43 57 57 48 Samp 57 57 48 57 55	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING L & T CR WEATHERING L & T CR	Туре: Туре:	L M L L R L L M	1400.00 1511.00 3500.00 25.00 A 4398.00 412.00 1466.00	SqFt SqFt Ft rea: SqFt Ft SqFt SqFt SqFt									
Inspe Samp Samp 43 57 57 48 Samp 57 48 57 56 50	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING L & T CR WEATHERING L & T CR WEATHERING SWELLING	Туре:	L M L L R L L M L	1400.00 1511.00 3500.00 25.00 A 4398.00 412.00 1466.00 5.00 36.00	SqFt SqFt Ft rea: SqFt Ft SqFt SqFt SqFt	590								
Inspe Samp 43 57 57 48 Samp 57 48 57 56 50 50 Samp	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING L & T CR WEATHERING SWELLING PATCHING	Туре:	L M L L R L L L L L L	1400.00 1511.00 3500.00 25.00 A 4398.00 412.00 1466.00 5.00 36.00	SqFt SqFt Ft rea: SqFt Ft SqFt SqFt SqFt SqFt	590	0.00 SqFt		PCI: 68					
Inspe Samp Samp 43 57 57 48 Samp 57 48 Samp 57 48 57 56 50 Samp Samp	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING L & T CR WEATHERING SWELLING PATCHING	Туре:	L M L L R L L L L L L	1400.00 1511.00 3500.00 25.00 A 4398.00 412.00 1466.00 5.00 36.00	SqFt SqFt Ft area: SqFt Ft SqFt SqFt SqFt SqFt SqFt area:	590	0.00 SqFt		PCI: 68					
Inspe Samp Samp 43 57 57 48 Samp 57 48 57 56 50 Samp	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING L & T CR WEATHERING SWELLING PATCHING le Number: 250 le Comments:	Туре:	L M L R R L L L L R R	1400.00 1511.00 3500.00 25.00 A 4398.00 412.00 1466.00 5.00 36.00 A	SqFt SqFt Ft area: SqFt SqFt SqFt SqFt SqFt SqFt SqFt Ft	590	0.00 SqFt		PCI: 68					
Inspe Samp Samp 43 57 57 48 Samp 57 48 57 56 50 Samp Samp 48	ction Comments: le Number: 150 le Comments: BLOCK CR WEATHERING L & T CR le Number: 203 le Comments: WEATHERING L & T CR WEATHERING SWELLING PATCHING le Number: 250 le Comments: L & T CR	Туре:	L M L R R L L L R R L L	1400.00 1511.00 3500.00 25.00 A 4398.00 412.00 1466.00 5.00 36.00 A 145.00	SqFt SqFt Ft area: SqFt SqFt SqFt SqFt sqFt rea: Ft SqFt	590	0.00 SqFt		PCI: 68					

Network:	TIX				Name:	SPACE COA	AST REGIONAL	AIRPORT		
Branch:	AP E		Name:	EAST A	PRON	U	se: APRON	Area:	628,932 SqFt	
Section:	4211	o	f 21	From: -			To: ·	-	Last Const	t.: 6/1/2002
Surface:	AAC	Family:	C9N59-PR-	AP-AAC-APC	Zone:		Catego	ory:	Rank: P	
Area:	3	3,845 SqFt	Lengtl	ı:	100 Ft	Width	: 3	38 Ft		
Slabs:		Slab Len	igth:	Ft	Slab V	Vidth:	Ft	Join	t Length:	Ft
Shoulder:		Street Ty	ype:		Grade	: 0		Lan	les: 0	
Section Co	omments:									
Work Date	e: 1/1/1971	W	ork Type: Ne	ew Construction	- Initial		Code: NU-I	Ň	Is Major M&R: True	
Work Date	e: 6/1/2002	W	ork Type: M	ill and Overlay			Code: ML-C	DL	Is Major M&R: True	
Last Insp.	Date: 3/4/20	19	Tota	ISamples: 1		Sur	veyed: 1			
Conditions	s: PCI: 6	57								
Inspection	Comments:									
Sample Nu	umber: 115	Тур	e: R	Ar	ea:	3845.00 SqF	t P	CI: 67		
Sample Co	omments:									
52 RA	VELING		L	142.00 \$	SqFt					
50 PA'	TCHING		L	1000.00	SqFt					
	EATHERING		М	2703.00	-					

Network: TIX		Name:	SPACE COAST R	EGIONAL AIRPORT	Γ	
Branch: AP E	Name:	EAST APRON	Use:	APRON	Area:	628,932 SqFt
Section: 4214	of 21	From: -		То: -		Last Const.: 6/1/2002
Surface: APC	Family: C9N59-PR-AF	P-AAC-APC Zone:		Category:		Rank: P
Area: 52,1	87 SqFt Length:	1,100 Ft	Width:	35 Ft		
Slabs:	Slab Length:	20 Ft Sla	ab Width:	12 Ft	Joint Lengtl	-2 Ft
Shoulder:	Street Type:	Gi	ade: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1943	Work Type: New	Construction - PCC	Со	de: NC-PC	Is Major	M&R: True
Work Date: 1/1/1971	Work Type: Over	lay - AC	Со	de: OL-AC	Is Major	M&R: True
Work Date: 1/1/1992	Work Type: Slurr	y Seal	Со	de: SS-SS	Is Major	M&R: False
Work Date: 6/1/2002	Work Type: MIL	L and OVERLAY	Со	de: ML-OV	Is Major	M&R: True
Last Insp. Date: 3/4/2019	TotalS	amples: 13	Surveyed	: 2		
Conditions: PCI: 56						
Inspection Comments:						
Sample Number: 106	Type: R	Area:	3500.00 SqFt	PCI: 58		
Sample Comments:						
52 RAVELING	L	70.00 SqFt				
48 L & T CR	L	502.00 Ft				
48 L & T CR	М	100.00 Ft				
57 WEATHERING	L	3430.00 SqFt				
Sample Number: 108	Type: R	Area:	5000.00 SqFt	PCI: 55		
Sample Comments:						
50 PATCHING	L	1250.00 SqFt				
47 JT REF. CR	М	170.00 Ft				
57 WEATHERING	М	3750.00 SqFt				
48 L & T CR	L	165.00 Ft				
47 JT REF. CR	L	265.00 Ft				

Network:	TIX			Nai	me: SPA	CE COAST	REGIONAL AIRP	ORT	
Branch:	AP E		Name:	EAST APRO	N	Use:	APRON	Area:	628,932 SqFt
Section:	4215	of	21	From: -			To: -		Last Const.: 1/1/1971
Surface:	AC	Family:	C9N59-PR-A	AP-AC Zor	ne:		Category:		Rank: P
Area:	82	2,925 SqFt	Length	: 300	Ft	Width:	150 Ft		
Slabs:		Slab Leng	th:	Ft	Slab Width:		Ft	Join	t Length: Ft
Shoulder:	:	Street Typ	be:		Grade: 0			Lane	es: 0
Section C	omments:								
Work Da	te: 1/1/1971	Woi	rk Type: BU	IILT		С	ode: IMPORTED]	s Major M&R: True
Work Da	te: 1/1/1992	Woi	rk Type: RE	PAIR		С	ode: IMPORTED		s Major M&R: False
Last Insp	. Date: 3/4/20	19	Tota	Samples: 19		Surveye	ed: 3		
Conditior	ns: PCI: 4	5							
Inspection	n Comments:								
Sample N	umber: 208	Туре	e: R	Area:	4032	.00 SqFt	PCI: 3	33	
Sample C	comments:								
56 SV	WELLING		L	403.00 SqFt					
	AVELING		М	4032.00 SqFt					
	& T CR		L	100.00 Ft					
Sample N	umber: 256	Туре	e: R	Area:	5000	.00 SqFt	PCI: 5	59	
Sample C	comments:								
52 RA	AVELING		L	4952.00 SqFt					
56 SV	WELLING		L	500.00 SqFt					
48 L	& T CR		L	197.00 Ft					
52 RA	AVELING		М	48.00 SqFt					
Sample N	umber: 304	Туре	e: R	Area:	4050	.00 SqFt	PCI: 3	38	
Sample C	comments:								
56 SV	WELLING		L	405.00 SqFt					
	AVELING		М	4050.00 SqFt					

Network:	TIX				Nam	e: SPA	CE COAST	REGIONAL A	AIRPORT			
Branch:	AP E		Name:	EAST	APRON	J	Use:	APRON	Ar	·ea:	628,932 SqFt	
Section: 42	16	0	f 21	From: -				To: -			Last Const.	: 1/1/2008
Surface: AA	AC	Family:	C9N59-PR-A	P-AAC-APC	Zon	e:		Categor	y:		Rank: P	
Area:	48,8	36 SqFt	Length:		300 F	t	Width:	150) Ft			
Slabs:		Slab Ler	ngth:	Ft		Slab Width:		Ft		Joint Lengtl	1:	Ft
Shoulder:		Street T	ype:			Grade: 0				Lanes: 0)	
Section Comm	nents:											
Work Date:	1/1/1971	W	ork Type: New	Construction	n - Initi	al	C	ode: NU-IN		Is Major	r M&R: True	
Work Date:	1/1/2008	W	ork Type: Mill	and Overlay			C	ode: ML-OI	<u>.</u>	Is Majo	r M&R: True	
Last Insp. Da	te: 3/4/2019)	Totals	Samples: 9)		Surveye	ed: 1				
Conditions:	PCI: 82											
Inspection Co	omments:											
Sample Numb	ber: 451	Туј	pe: R	Α	rea:	5250).00 SqFt	РС	T: 82			
Sample Comr	ments:											
57 WEAT	HERING		М	1312.00	SqFt							
48 L&T	CR		L	3.00	-							
57 WEAT	HERING		L	3938.00	SqFt							

Network:	TIX			Nan	ne: SPA	CE COAST	REGIONAL AIR	PORT		
Branch:	AP E		Name:	EAST APRO	N	Use:	APRON	Area:	628,932 SqFt	
Section: 4	4218	of 21]	From: -			To: -		Last Const.:	1/1/2008
Surface: A	AAC	Family: C9N	N59-PR-AF	P-AAC-APC Zon	e:		Category:		Rank: P	
Area:	95,344	4 SqFt	Length:	525 F	't	Width:	137 Ft			
Slabs:		Slab Length:		Ft	Slab Width:		Ft	Joi	nt Length: Ft	
Shoulder:		Street Type:			Grade: 0			La	nes: 0	
Section Con	nments:									
Work Date:	: 1/1/1971	Work T	ype: New	Construction - Init	ial	C	ode: NU-IN		Is Major M&R: True	
Work Date:	: 1/1/2008	Work I	ype: Mill	and Overlay		С	ode: ML-OL		Is Major M&R: True	
Last Insp. E	Date: 3/4/2019		TotalS	amples: 18		Surveye	d: 3			
Conditions:	PCI: 80									
Inspection (Comments:									
Sample Nur	nber: 101	Туре:	R	Area:	5000).00 SqFt	PCI:	76		
Sample Con	nments:									
57 WEA	ATHERING]	М	1250.00 SqFt						
	ATHERING		Ĺ	3750.00 SqFt						
48 L&	T CR]	L	223.00 Ft						
Sample Nur	nber: 200	Type:	R	Area:	6200	0.00 SqFt	PCI:	80		
Sample Con	nments:									
57 WEA	ATHERING]	М	1550.00 SqFt						
57 WEA	ATHERING]	L	4650.00 SqFt						
48 L&	T CR	1	L	58.00 Ft						
Sample Nur	nber: 252	Туре:	R	Area:	5000).00 SqFt	PCI:	82		
Sample Con	nments:									
57 WEA	ATHERING]	М	1250.00 SqFt						
48 L&'	T CR]	L	6.00 Ft						
57 WEA	ATHERING]	L	3750.00 SqFt						

Network:	TIX				Name:	SPACE	COAST R	EGIONAL AIRPO	ORT			
Branch:	AP E		Name:	EAST A	PRON		Use:	APRON	Area:	628,932	2 SqFt	
Section:	4219	0	f 21	From: -				To: -		Las	st Const.:	1/1/2015
Surface:	AAC	Family:	C9N59-PR-A	P-AAC-APC	Zone:			Category:		Rai	nk: P	
Area:		8,237 SqFt	Length:	:	55 Ft	W	idth:	151 Ft				
Slabs:		Slab Ler	ngth:	Ft	Slab '	Width:		Ft	Joint L	ength:	Ft	
Shoulder:		Street T	ype:		Grad	le: 0			Lanes:	0		
Section Co	mments:											
Work Date	e: 1/1/1971	W	ork Type: BU	ILT			Co	de: IMPORTED	Is	Major M&R:	: True	
Work Date	e: 1/1/1992	W	ork Type: REI	PAIR			Co	de: IMPORTED	Is]	Major M&R:	False	
Work Date	e: 1/1/2015	W	ork Type: MII	LL and OVER	LAY		Co	de: ML-OV	Is	Major M&R:	: True	
Last Insp.]	Date: 3/4/2	019	Total	Samples: 2			Surveyed	: 1				
Conditions	: PCI:	56										
Inspection	Comments:											
Sample Nu	mber: 260	Туј	pe: R	Ar	ea:	4091.00	SqFt	PCI: 5	6			
Sample Co	mments:											
48 L&	TCR		L	56.00 H	ŕt							
52 RAY	VELING		L	2266.00 \$	SqFt							
57 WE	ATHERING		L	1825.00 \$	SqFt							
43 BLC	OCK CR		L	2266.00 \$	aFt							

Network:	TIX			Na	me: SPA	CE COAST F	REGIONAL AIRP	ORT		
Branch:	AP E		Name:	EAST APRO	DN	Use:	APRON	Area:	628,93	2 SqFt
Section:	4220	of	21 I	From: -			То: -		La	st Const.: 1/1/2014
Surface:	AAC	Family:	C9N59-PR-AP	-AAC-APC Zo	ne:		Category:		Ra	nk: P
Area:	8,1	68 SqFt	Length:	300	Ft	Width:	45 Ft			
Slabs:		Slab Leng	gth:	Ft	Slab Width:		Ft	Joint L	ength:	Ft
Shoulder:		Street Ty	pe:		Grade: 0			Lanes:	0	
Section Co	omments:									
Work Date	e: 1/1/1980	Wo	rk Type: BUII	LT		Со	de: IMPORTED	Is I	Major M&R	: True
Work Date	e: 1/1/1992	Wo	rk Type: REP	AIR		Co	de: IMPORTED	Is I	Major M&R	: False
Work Date	e: 1/1/2014	Wo	rk Type: MILI	L and OVERLAY		Co	de: ML-OV	Isl	Major M&R	: True
Last Insp.	Date: 3/4/2019)	TotalS	amples: 2		Surveyed	l: 1			
Conditions	s: PCI: 83									
Inspection	Comments:									
Sample Nu	umber: 100	Туре	e: R	Area:	4418	3.00 SqFt	PCI:	33		
Sample Co	omments:									
57 WF	EATHERING		L	4180.00 SqFt						
3/ WE			L	8.00 Ft						
	k T CR		L	0.00 11						
48 L&	& T CR TCHING		L	18.00 SqFt						

Network:	TIX			Nan	ne: SPACE COA	ST REGIONAL AIRPO	ORT	
Branch:	AP E		Name:	EAST APRO	N Us	e: APRON	Area:	628,932 SqFt
Section:	4221	0	f 21	From: -		То: -		Last Const.: 1/1/2008
Surface:	AC	Family:	C9N59-PR-AP	P-AC Zon	ie:	Category:		Rank: P
Area:		5,405 SqFt	Length:	200 F	Ft Width:	25 Ft		
Slabs:		Slab Len	ıgth:	Ft	Slab Width:	Ft	Joint Length	: Ft
Shoulder:		Street Ty	ype:		Grade: 0		Lanes: 0	
Section Co	mments:							
Work Date	e: 1/1/2008	W	ork Type: New	Construction - AC		Code: NC-AC	Is Major	M&R: True
Last Insp.	Date: 3/4/2	2019	TotalS	amples: 1	Surv	eyed: 1		
Conditions	s: PCI:	71						
Inspection	Comments:							
-	Comments: imber: 253		pe: R	Area:	5405.00 SqFt	PCI: 7	1	
-	mber: 253		De: R	Area:	5405.00 SqFt	PCI: 7	1	
Sample Nu Sample Co	mber: 253		pe: R L		5405.00 SqFt	PCI: 7	1	
Sample Nu Sample Co 52 RA	imber: 253 omments:			Area: 107.00 SqFt 60.00 SqFt	5405.00 SqFt	PCI: 7	1	
Sample Nu Sample Co 52 RA 50 PAT	imber: 253 omments: VELING	3 Тур	L	107.00 SqFt	5405.00 SqFt	PCI: 7	1	
Sample Nu Sample Co 52 RA 50 PA 57 WE	umber: 253 omments: VELING ICHING	3 Тур	L L	107.00 SqFt 60.00 SqFt	5405.00 SqFt	PCI: 7	1	

Network:	TIX			Nai	me: SPACE COA	ST REGIONAL AIRPO	ORT	
Branch:	AP E		Name:	EAST APRO	N U	se: APRON	Area:	628,932 SqFt
Section:	4225	0	f 21 F	'rom: -		То: -		Last Const.: 1/1/1991
Surface:	PCC	Family:	C9N59-PR-AP	-PCC Zor	ie:	Category:		Rank: P
Area:		8,700 SqFt	Length:	400	Ft Width:	20 Ft		
Slabs:	48	Slab Ler	ngth:	12 Ft	Slab Width:	15 Ft	Joint Lengt	h: 780 Ft
Shoulder:		Street T	ype:		Grade: 0		Lanes:	0
Section Co	omments:							
Work Dat	te: 1/1/1991	W	ork Type: BUIL	T		Code: IMPORTED	Is Majo	or M&R: True
Last Insp.	Date: 3/4/	2019	TotalSa	mples: 2	Sur	veyed: 1		
Condition	s: PCI:	69						
Inspectior	n Comments:	:						
Sample N	umber: 202	2 Ty	pe: R	Area:	26.00 Slab	s PCI: 6	59	
Sample C	omments:							
63 LN	NEAR CR		L	14.00 Slabs				
73 SH	IRINKAGE (CR	Ν	2.00 Slabs				
	IAT. SLAB		L	1.00 Slabs				
71 FA	ULTING		L	1.00 Slabs				

Network:	TIX			I	Name:	SPACE COAST	REGION	AL AIRPOI	RT			
Branch:	AP E		Name:	EAST AP	RON	Use:	APRON	N	Area:	628	,932 SqFt	
Section:	4226	of	21 F	rom: -			To:	-]	Last Const.:	1/1/2014
Surface:	AAC	Family:	C9N59-PR-AP	AAC-APC	Zone:		Cat	egory:		1	Rank: P	
Area:	6,6	77 SqFt	Length:	32	25 Ft	Width:		40 Ft				
Slabs:		Slab Leng	th:	Ft	Slab Wid	th:	Ft		Joint L	ength:	F	t
Shoulder:		Street Typ	e:		Grade:	0			Lanes:	0		
Section Co	mments:											
Work Date	e: 1/1/1985	Wor	rk Type: BUIL	Т		C	Code: IM	PORTED	Is	Major Mð	&R: True	
Work Date	e: 1/1/1992	Wor	·k Type: REPA	JR		C	Code: IM	PORTED	Is	Major Mð	R: False	
Work Date	e: 1/1/2014	Wor	•k Type: MILI	and OVERLA	ΑY	C	Code: MI	L-OV	Is]	Major Mð	R: True	
Last Insp.]	Date: 3/4/2019)	TotalSa	mples: 2		Survey	e d: 1					
Conditions	: PCI: 72											
Inspection	Comments:											
Sample Nu	mber: 100	Туре	: R	Area	:	3570.00 SqFt		PCI: 72				
Sample Co	mments:											
48 L&	T CR		L	12.00 Ft								
52 RA	VELING		L	31.00 Sq	Ft							
50 PA7	ГCHING		L	461.00 Sq	Ft							

Network: TIX			Ν	ame: SPA	ACE COAST	REGIONAL AIRPC	ORT	
Branch: AP E		Name:	EAST APR	ON	Use:	APRON	Area:	628,932 SqFt
Section: 4227	of	f 21 I	rom: -			То: -		Last Const.: 1/1/2014
Surface: AAC	Family:	C9N59-PR-AP	-AAC-APC Z	one:		Category:		Rank: P
Area:	6,560 SqFt	Length:	325	5 Ft	Width:	40 Ft		
Slabs:	Slab Len	gth:	Ft	Slab Width:		Ft	Joint Lei	ngth: Ft
Shoulder:	Street Ty	pe:		Grade: 0			Lanes:	0
Section Comments:								
Work Date: 1/1/1988	We	ork Type: OVE	RLAY		C	ode: IMPORTED	Is M	ajor M&R: True
Work Date: 1/1/1992	We	ork Type: BUII	.T		C	ode: IMPORTED	Is M	ajor M&R: True
Work Date: 1/1/2014	We	ork Type: MILI	and OVERLA	Y	C	ode: ML-OV	Is M	ajor M&R: True
Last Insp. Date: 3/4/2	019	TotalS	amples: 2		Surveye	d: 1		
Conditions: PCI:	89							
Inspection Comments:								
Sample Number: 100	Тур	e: R	Area:	356	0.00 SqFt	PCI: 8	9	
Sample Comments:								
52 RAVELING		L	35.00 SqF	t				
50 PATCHING		L	18.00 SqF					
57 WEATHERING		L	3507.00 SqF	t				

Network:	TIX				Nam	e: SPA	CE COAST	REG	ONAL AIRPOI	RT			
Branch:	AP E		Name:	EAST A	PRON	1	Use:	AP	RON	Area:	628,932 S	qFt	
Section:	4228	of	21 F	rom: -					То: -		Last C	onst.:	1/1/2014
Surface:	AAC	Family:	C9N59-PR-AP	-AAC-APC	Zone	e:			Category:		Rank:	Р	
Area:	11,1	100 SqFt	Length:		400 F	t	Width:		30 Ft				
Slabs:		Slab Leng	gth:	Ft		Slab Width:			Ft	Joint Leng	gth:	Ft	
Shoulder:		Street Ty	pe:			Grade: 0				Lanes:	0		
Section Co	omments:												
Work Date	e: 1/1/1988	Wo	ork Type: OVE	RLAY			(Code:	IMPORTED	Is Ma	jor M&R: T	rue	
Work Date	e: 1/1/1992	Wo	ork Type: BUIL	T			(Code:	IMPORTED	Is Ma	jor M&R: T	rue	
Work Date	e: 1/1/2014	Wo	ork Type: MILI	and OVER	LAY		(Code:	ML-OV	Is Ma	jor M&R: T	rue	
Last Insp.	Date: 3/4/201	9	TotalSa	mples: 3			Survey	ed: 1					
Conditions	s: PCI: 89												
Inspection	Comments:												
Sample Nu	umber: 100	Тур	e: R	Ar	ea:	3734	1.00 SqFt		PCI: 89				
Sample Co	omments:						-						
57 WE	EATHERING		L	3697.00	SqFt								
52 RA	VELING		L	37.00	1								
48 L&	& T CR		L	5.00	Ft								

Network: TIX			Name:	SPACE COAST	REGIONAL AIRPOI	RT	
Branch: AP E		Name:	EAST APRON	Use:	APRON	Area:	628,932 SqFt
Section: 4229	of	21 Fr	om: -		To: -		Last Const.: 1/1/2012
Surface: AC	Family:	C9N59-PR-AP-A	AC Zone:		Category:		Rank: P
Area:	16,315 SqFt	Length:	820 Ft	Width:	20 Ft		
Slabs:	Slab Leng	gth:	Ft Slab	Width:	Ft	Joint Lengt	h: Ft
Shoulder:	Street Ty	pe:	Gra	de: 0		Lanes:)
Section Comments:							
Work Date: 1/1/201	12 Wo	rk Type: New C	onstruction - Initial	C	ode: NU-IN	Is Majo	r M&R: True
Last Insp. Date: 3	/4/2019	TotalSa	nples: 3	Surveye	d: 1		
Conditions: PCI:	: 88						
Inspection Commen	its:						
Sample Number: ´	750 Тур	e: R	Area:	5635.00 SqFt	PCI: 88		
Sample Comments:							
57 WEATHERI	NG	L	5579.00 SqFt				
48 L & T CR		L	19.00 Ft				
52 RAVELING		L	56.00 SqFt				

Network:	TIX			Na	me: SPA	CE COAST	REGIONAL AIR	PORT	
Branch:	AP E		Name:	EAST APRO	N	Use:	APRON	Area:	628,932 SqFt
Section:	4230	of	21	From: -			To: -		Last Const.: 1/1/1991
Surface:	PCC	Family:	C9N59-PR-A	P-PCC Zor	ne:		Category:		Rank: P
Area:		9,576 SqFt	Length:	400	Ft	Width:	20 Ft		
Slabs:	56	Slab Leng	th:	10 Ft	Slab Width:		17 Ft	Joint L	ength: 851 Ft
Shoulder:		Street Typ	be:		Grade: 0			Lanes:	0
Section Co	omments:								
Work Dat	te: 1/1/1991	Wo	rk Type: BUI	ILT		(Code: IMPORTE	D Is]	Major M&R: True
Last Insp.	. Date: 3/4/	2019	Total	Samples: 5		Survey	ed: 1		
Condition	s: PCI:	77							
nspection	n Comments	:							
Sample N	umber: 20	3 Туре	: R	Area:	1	3.00 Slabs	PCI:	77	
Sample Co	omments:								
73 SH	IRINKAGE (CR	Ν	6.00 Slabs					
53 LIN	NEAR CR		L	7.00 Slabs					

Network:	TIX				Na	me: SPA	ACE COAST	REG	IONAL AIRPOI	RT			
Branch:	AP E		Nam	e: EAS	T APRC	DN	Use:	A	PRON	Area:	628,932	2 SqFt	
Section:	4232	C	of 21	From:	-				То: -		Las	t Const.:	1/1/2014
Surface:	AAC	Family:	C9N59-P	R-AP-AAC-AI	PC Zor	ne:			Category:		Ran	k: P	
Area:		9,960 SqFt	Len	gth:	1,000	Ft	Width:		162 Ft				
Slabs:		Slab Lei	ngth:	F	į	Slab Width:			Ft	Joint Le	ngth:	Ft	-
Shoulder:		Street T	ype:			Grade: 0				Lanes:	0		
Section Co	omments:												
Work Dat	e: 1/1/1971	W	ork Type:	BUILT			(Code:	IMPORTED	Is M	ajor M&R:	True	
Work Dat	e: 1/1/1992	W	ork Type:	REPAIR			(Code:	IMPORTED	Is M	ajor M&R:	False	
Work Dat	e: 1/1/2014	W	ork Type:	MILL and OV	ERLAY		(Code:	ML-OV	Is M	ajor M&R:	True	
Last Insp.	Date: 3/4/	2019	Т	otalSamples:	3		Survey	ed:	1				
Condition	s: PCI:	79											
Inspection	Comments	:											
Sample N	umber: 353	3 Ty	pe: R		Area:	357	0.00 SqFt		PCI: 79				
Sample Co	omments:												
50 PA	TCHING		L	240.00) SqFt								
57 WI	EATHERING	ĩ	L	3263.00	1								
52 RA	VELING		L	67.00) SqFt								

Network:	TIX				Na	me: SPA	ACE COAST	REGIONAL AIF	RPORT	
Branch:	AP E		Ν	ame:	EAST APRC	N	Use:	APRON	Area:	628,932 SqFt
Section:	4235	(of 21	Fro	om: -			To: -		Last Const.: 1/1/2015
Surface:	PCC	Family:	C9N5	9-PR-AP-P	CC Zoi	ne:		Category:		Rank: P
Area:		93,090 SqFt		Length:	495	Ft	Width:	178 F	t	
Slabs:	413	Slab Le	ngth:		14 Ft	Slab Width:		15 Ft	Joint L	ength: 11,495 Ft
Shoulder:		Street T	ype:			Grade: 0			Lanes:	0
Section Co	omments:									
Work Dat	e: 1/1/2015	5 W	ork Ty	pe: New Co	onstruction - PC	C	С	ode: NC-PC	Is	Major M&R: True
Last Insp.	Date: 3/4	/2019		TotalSam	ples: 22		Surveye	d: 3		
Condition	s: PCI:	99								
Inspection	o Comment	s:								
Sample Nu	umber: 2	13 Ty	pe:	R	Area:	2	5.00 Slabs	PCI:	99	
Sample Co	omments:									
66 SM	IALL PATO	СН	L		1.00 Slabs					
Sample Nu	umber: 20	65 Ty	pe:	R	Area:	2	0.00 Slabs	PCI:	100	
Sample Co	omments:									
<no distre<="" td=""><td>ess></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></no>	ess>									
Sample Nu	umber: 30	64 Ty	pe:	R	Area:	2	4.00 Slabs	PCI:	99	
Sample Co	omments:									

Network:	TIX			Na	me: SPA	CE COAST	REGIONAL AIRPO	ORT	
Branch:	AP E		Name:	EAST APRO	N	Use:	APRON	Area:	628,932 SqFt
Section:	4240	of	21 F	rom: -			To: -		Last Const.: 1/1/2014
Surface:	AAC	Family:	C9N59-PR-AP-	AAC-APC Zo	ne:		Category:		Rank: P
Area:		7,020 SqFt	Length:	250	Ft	Width:	30 Ft		
Slabs:		Slab Leng	th:	Ft	Slab Width:		Ft	Joint Le	ngth: Ft
Shoulder:		Street Ty	be:		Grade: 0			Lanes:	0
Section Co	omments:								
Work Date	e: 1/1/1987	Wo	rk Type: BUIL	Т		C	ode: IMPORTED	Is M	ajor M&R: True
Work Date	e: 1/1/2014	Wo	rk Type: MILL	, and OVERLAY		С	ode: ML-OV	Is M	ajor M&R: True
Last Insp.	Date: 3/4/2	2019	TotalSa	mples: 2		Surveye	d: 1		
Conditions	s: PCI:	91							
Inspection	Comments:								
Sample Nu	umber: 202	Туре	: R	Area:	4020	0.00 SqFt	PCI: 9	91	
Sample Co	omments:								
57 WE	EATHERING		L	3980.00 SqFt					
52 RA	VELING		L	40.00 SqFt					

Network:	TIX			Na	me: SPA	CE COAST	REGIONAL AIRPO	ORT	
Branch:	AP E		Name:	EAST APRO	N	Use:	APRON	Area:	628,932 SqFt
Section:	4241	of	21 F	rom: -			То: -		Last Const.: 1/1/2014
Surface:	AAC	Family:	C9N59-PR-AP	-AAC-APC Zo	ne:		Category:		Rank: P
Area:		8,553 SqFt	Length:	350	Ft	Width:	25 Ft		
Slabs:		Slab Len	gth:	Ft	Slab Width:		Ft	Joint Len	gth: Ft
Shoulder:		Street Ty	pe:		Grade: 0			Lanes:	0
Section Co	omments:								
Work Dat	te: 1/1/1987	We	ork Type: BUIL	JΤ		Co	ode: IMPORTED	Is Ma	ajor M&R: True
Work Dat	te: 1/1/2014	Wo	ork Type: MILI	and OVERLAY		Co	ode: ML-OV	Is Ma	ajor M&R: True
Last Insp.	Date: 3/4/	2019	TotalSa	amples: 3		Surveye	d: 1		
Condition	s: PCI:	91							
Inspection	n Comments:	:							
Sample Nu	umber: 202	2 Тур	e: R	Area:	3180	0.00 SqFt	PCI: 9	1	
Sample Co	omments:								
52 RA	VELING		L	32.00 SqFt					
57 WE	EATHERING	Ĩ	L	3148.00 SqFt					

Network:	TIX				Name	e: SPA	ACE COAST	REGIONAL AIF	RPORT		
Branch:	AP E		Name:	EAST	APRON		Use:	APRON	Area:	628,932 SqF	⁷ t
Section:	4245	o	f 21	From:	-			To: -		Last Co	nst.: 1/1/2003
Surface:	AC	Family:	C9N59-PR-A	P-AC	Zone	:		Category:		Rank:	Р
Area:		7,200 SqFt	Length:		350 Ft		Width:	20 F	t		
Slabs:		Slab Len	gth:	Ft	:	Slab Width:		Ft	Joint	Length:	Ft
Shoulder:		Street Ty	pe:			Grade: 0			Lane	s: 0	
Section Co	omments:										
Work Date	e: 1/1/2003	W	ork Type: Nev	v Constructi	on - Initia	l	C	ode: NU-IN	Ι	s Major M&R: Tru	e
Last Insp.	Date: 3/4/2	019	Total	Samples:	2		Survey	ed: 1			
Conditions	s: PCI:	71									
Inspection	Comments:										
Sample Nu	imber: 200	Тур	e: R	I	rea:	360	0.00 SqFt	PCI:	71		
Sample Co	omments:										
57 WE	EATHERING		М	3420.00	SqFt						
	VELING		L	180.00	-						
48 L&	t T CR		L	12.00	Ft						

Network:	TIX			Ν	ame: SP	ACE COAST	REGIONAL AI	RPORT	
Branch:	AP E		Name:	EAST APR	.ON	Use:	APRON	Area:	628,932 SqFt
Section:	4250	(of 21	From: -			To: -		Last Const.: 1/1/2011
Surface:	PCC	Family:	C9N59-PR-	AP-PCC Z	one:		Category	:	Rank: P
Area:		38,220 SqFt	Lengt	h: 190) Ft	Width:	200 1	Ft	
Slabs:	182	Slab Le	ngth:	14 Ft	Slab Width	:	15 Ft	Joint	t Length: 4,858 Ft
Shoulder:		Street 7	уре:		Grade:	0		Lane	es: 0
Section Co	omments:								
Work Dat	te: 1/1/2011	. V	Vork Type: N	ew Construction - I	nitial	C	ode: NU-IN]	Is Major M&R: True
Last Insp.	Date: 3/4	/2019	Tot	alSamples: 12		Surveye	ed: 2		
Condition	s: PCI:	95							
Inspectior	n Comments	s:							
Sample N	umber: 30	00 Ty	pe: R	Area:		15.00 Slabs	PCI	96	
Sample C	omments:								
73 SH	RINKAGE	CR	Ν	4.00 Slat	08				
Sample N	umber: 50)1 Ty	pe: R	Area:		15.00 Slabs	PCI	94	
Sample C	omments:								

Network:	TIX			Nam	e: SPA	CE COAST	REGIONAL AIRPO	ORT	
Branch:	AP HELI		Name:	HELICOPTER	APRON	Use:	APRON	Area:	397,538 SqFt
Section:	4255	of 2	Fro	m: -			То: -		Last Const.: 1/1/2012
Surface:	AC	Family: C9	N59-PR-AP-A	C Zone	:		Category:		Rank: P
Area:	32,79	98 SqFt	Length:	475 F	t	Width:	70 Ft		
Slabs:		Slab Length:		Ft	Slab Width:		Ft	Joint Le	ngth: Ft
Shoulder:		Street Type:			Grade: 0			Lanes:	0
Section Co	omments:								
Work Dat	e: 1/1/2012	Work 7	ype: New Co	nstruction - Initi	al	С	ode: NU-IN	Is M	lajor M&R: True
Last Insp.	Date: 3/4/2019		TotalSam	ples: 5		Surveye	d: 1		
Condition	s: PCI: 90								
Inspection	Comments:								
Sample N	umber: 096	Туре:	R	Area:	700	0.00 SqFt	PCI: 9	00	
Sample Co	omments:								
57 WI	EATHERING		L 7	000.00 SqFt					
48 L &	& T CR		L	37.00 Ft					

Network: TIX			Name:	SPACE COAST	REGIONAL AIR	PORT		
Branch: AP HELI		Name:	HELICOPTER APRON	Use:	APRON	Are	ea: 39	7,538 SqFt
Section: 4260	of 2		From: -		To: -			Last Const.: 1/1/2012
Surface: PCC	Family: C9N	159-PR-A	AP-PCC Zone:		Category:			Rank: P
Area: 364,74	0 SqFt	Length	: 744 Ft	Width:	510 Ft			
Slabs: 2,596	Slab Length:		12 Ft Slab Wid	th:	12 Ft		Joint Length:	61,986 Ft
Shoulder:	Street Type:		Grade:	0			Lanes: 0	
Section Comments:								
Work Date: 1/1/2012	Work T	ype: Nev	w Construction - Initial	C	ode: NU-IN		Is Major M	I&R: True
Last Insp. Date: 3/4/2019		Total	Samples: 97	Surveye	d: 10			
Conditions: PCI: 97								
Inspection Comments:								
Sample Number: 146	Type:	R	Area:	21.00 Slabs	PCI:	100		
Sample Comments:								
<no distress=""></no>								
Sample Number: 199	Type:	R	Area:	21.00 Slabs	PCI:	100		
Sample Comments:								
<no distress=""></no>								
Sample Number: 244	Type:	R	Area:	28.00 Slabs	PCI:	99		
Sample Comments:								
66 SMALL PATCH	Ι		1.00 Slabs					
Sample Number: 346	Type:	R	Area:	28.00 Slabs	PCI:	84		
Sample Comments:								
74 JOINT SPALL	Ι	<u>ـ</u>	1.00 Slabs					
73 SHRINKAGE CR67 LARGE PATCH	N I		18.00 Slabs 4.00 Slabs					
67 LARGE PATCH Sample Number: 447	Туре:	R	4.00 Slabs	28.00 Slabs	PCI:	0/		
Sample Comments:	rype.	K	Alta.	28.00 51405	TCI.	74		
-	_	_						
73 SHRINKAGE CR	<u> </u>		12.00 Slabs	29.00.01.1	DCL	100		
Sample Number: 494	Туре:	R	Area:	28.00 Slabs	PCI:	100		
Sample Comments:								
<no distress=""></no>								
Sample Number: 643	Туре:	R	Area:	28.00 Slabs	PCI:	96		
Sample Comments:								
66 SMALL PATCH	I		1.00 Slabs 1.00 Slabs					
75 CORNER SPALL Sample Number: 646	Туре:	A R	Area:	28.00 Slabs	PCI:	94		
Sample Comments:	rype.	К	Aita.	20.00 51808	i ci;	77		
-	-							
74 JOINT SPALL73 SHRINKAGE CR	I N		2.00 Slabs 8.00 Slabs					
Sample Number: 795	Туре:	R	Area:	28.00 Slabs	PCI:	100		
Sample Comments:								
<no distress=""></no>								
Sample Number: 847	Туре:	R	Area:	28.00 Slabs	PCI:	100		
Sample Comments:	• •							
<no distress=""></no>								

<No Distress>

Network: TIX		Name:	SPACE COAST I	REGIONAL AIRPOI	RT	
Branch: AP W	Name:	WEST APRON	Use:	APRON	Area: 400,935 SqF	⁷ t
Section: 4305	of 2 F	rom: -		То: -	Last Co	nst.: 1/1/2014
Surface: PCC	Family: C9N59-PR-AP-	PCC Zone:		Category:	Rank:	Р
Area: 370,47	'l SqFt Length:	1,600 Ft	Width:	500 Ft		
Slabs: 1,647	Slab Length:	15 Ft Slab	Width:	15 Ft	Joint Length: 104,50	67 Ft
Shoulder:	Street Type:	Grad	e: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/2014	Work Type: New O	Construction - Initial	Co	de: NU-IN	Is Major M&R: Tru	e
Last Insp. Date: 3/4/2019	TotalSa	mples: 88	Surveyee	i: 9		
Conditions: PCI: 99						
Inspection Comments:						
Sample Number: 151	Type: R	Area:	20.00 Slabs	PCI: 10)	
Sample Comments:						
<no distress=""></no>						
Sample Number: 155	Type: R	Area:	20.00 Slabs	PCI: 99		
Sample Comments:						
73 SHRINKAGE CR	Ν	1.00 Slabs				
Sample Number: 203	Type: R	Area:	20.00 Slabs	PCI: 97		
Sample Comments:						
73 SHRINKAGE CR	Ν	3.00 Slabs				
Sample Number: 208	Type: R	Area:	20.00 Slabs	PCI: 10)	
Sample Comments:						
<no distress=""></no>						
Sample Number: 260	Type: R	Area:	20.00 Slabs	PCI: 99		
Sample Comments:						
73 SHRINKAGE CR	Ν	1.00 Slabs				
Sample Number: 263	Type: R	Area:	20.00 Slabs	PCI: 99		
Sample Comments:						
73 SHRINKAGE CR	Ν	1.00 Slabs				
Sample Number: 411	Type: R	Area:	20.00 Slabs	PCI: 10)	
Sample Comments:						
<no distress=""></no>						
Sample Number: 414	Type: R	Area:	20.00 Slabs	PCI: 95		
Sample Comments:						
66 SMALL PATCH	L	3.00 Slabs				
73 SHRINKAGE CR	N	3.00 Slabs				
Sample Number: 512	Type: R	Area:	20.00 Slabs	PCI: 99		
Sample Comments:						
73 SHRINKAGE CR	Ν	1.00 Slabs				

Network:	TIX				Name:	SPACE COAST	REGIONAL AIRP	ORT		
Branch:	AP W		Name:	WEST A	APRON	Use:	APRON	Area:	400,935 Sq	lFt
Section:	4310	0	f 2	From: -			To: -		Last Co	onst.: 1/1/2014
Surface:	AAC	Family:	C9N59-PR-AF	-AAC-APC	Zone:		Category:		Rank:	Р
Area:	3	30,464 SqFt	Length:		68 Ft	Width:	400 Ft			
Slabs:		Slab Ler	ıgth:	Ft	Slab W	idth:	Ft	Joint L	ength:	Ft
Shoulder:		Street T	ype:		Grade	: 0		Lanes:	0	
Section Cor	mments:									
Work Date:	: 1/1/1943	W	ork Type: New	Construction	- Initial	С	ode: NU-IN	Is N	Jajor M&R: Tr	ue
Work Date:	: 1/1/2004	W	ork Type: MIL	L and OVER	LAY	С	ode: ML-OV	Is N	Jajor M&R: Tr	ue
Work Date:	: 1/1/2014	W	ork Type: MIL	L and OVER	LAY	С	ode: ML-OV	Is N	Jajor M&R: Tr	ue
Last Insp. I	Date: 3/4/2	019	TotalS	amples: 9		Surveye	ed: 1			
Conditions:	PCI:	72								
Inspection (Comments:									
Sample Nu	mber: 215	Ту	pe: R	Ar	ea:	3292.00 SqFt	PCI:	72		
Sample Cor	mments:									
48 L&	T CR		L	50.00 I	Ft					
48 L&	T CR		М	26.00 I	Ft					
57 WEA	ATHERING		L	2042.00 \$	SqFt					
57 WEA	ATHERING		М	1250.00 \$	CaEt					

Netwo	ork: TIX			Nai	me: SPA	CE COAST I	REGIONAL AIRPO	DRT
Branc			Name:	RUNWAY 1		Use:	RUNWAY	Area: 1,097,850 SqFt
Sectio	n: 6105	of 6	<u>.</u>	From: -			То: -	Last Const.: 6/1/2002
Surfac				RW-AAC- Zoi	ne:		Category:	Rank: P
			PC				8 .	
Area:	500,000) SqFt	Lengt	h: 5,000	Ft	Width:	100 Ft	
Slabs:		Slab Length	:	Ft	Slab Width:		Ft	Joint Length: Ft
Should	der:	Street Type:	:		Grade: 0			Lanes: 0
Sectio	n Comments:							
Work	Date: 1/1/1943	Work	Type: BU	UILT		Ca	ode: IMPORTED	Is Major M&R: True
Work	Date: 1/1/1971	Work	Type: O	VERLAY		Co	de: IMPORTED	Is Major M&R: True
Work	Date: 6/1/2002	Work	Type: M	ill and Overlay		Co	de: ML-OL	Is Major M&R: True
Last I	nsp. Date: 3/4/2019		Tota	alSamples: 100		Surveyee	l: 20	
Condi	tions: PCI: 62							
Inspec	ction Comments:							
Sampl	le Number: 302	Туре:	R	Area:	5000	.00 SqFt	PCI: 5	9
Sampl	le Comments:							
52	RAVELING		L	500.00 SqFt				
56	SWELLING		L	15.00 SqFt				
57	WEATHERING		М	2200.00 SqFt				
57 48	WEATHERING L & T CR		L L	2300.00 SqFt 382.00 Ft				
48	L & T CR		M	150.00 Ft				
Sampl	le Number: 308	Type:	R	Area:	5000	.00 SqFt	PCI: 6	5
Sampl	le Comments:							
57	WEATHERING		L	2400.00 SqFt				
48	L & T CR		L	189.00 Ft				
48	L & T CR		М	100.00 Ft				
57 52	WEATHERING RAVELING		M L	2400.00 SqFt 200.00 SqFt				
	le Number: 311	Туре:	R	Area:	5000	0.00 SqFt	PCI: 6	5
	le Comments:	- , 1, - ,			2000	- 1- •	0	
-			T	200 00 g=E4				
52 57	RAVELING WEATHERING		L L	200.00 SqFt 2400.00 SqFt				
57	WEATHERING		M	2400.00 SqFt				
48	L & T CR		L	265.00 Ft				
48	L & T CR		M	50.00 Ft			n.cr -	2
-	le Number: 317	Туре:	R	Area:	5000	0.00 SqFt	PCI: 5	3
Sampl	le Comments:							
57 57	WEATHERING		L M	2350.00 SqFt				
57 48	WEATHERING L & T CR		M M	2300.00 SqFt 279.00 Ft				
48	L & T CR		L	229.00 Ft				
52	RAVELING		L	350.00 SqFt				
-	le Number: 323	Type:	R	Area:	5000	0.00 SqFt	PCI: 6	6
Sampl	le Comments:							
52	RAVELING		L	1000.00 SqFt				
48	L & T CR		М	65.00 Ft				
57 57	WEATHERING WEATHERING		L M	2000.00 SqFt 2000.00 SqFt				
37 48	L & T CR		L	252.00 Ft				
	le Number: 326	Туре:	R	Area:	5000	.00 SqFt	PCI: 6	5
-	le Comments:							
48	L & T CR		М	50.00 Ft				
48	L & T CR		L	259.00 Ft				

50	RAVELING		т	200.00 SqFt			
52 57	WEATHERING		L M	2500.00 SqFt			
57	WEATHERING		L	2300.00 SqFt			
Samn	ole Number: 329	Туре:	R	Area:	5000.00 SqFt	PCI: 66	
-	ole Comments:	J I ***			1		
-			_				
57 57	WEATHERING WEATHERING		L M	2350.00 SqFt 2400.00 SqFt			
52	RAVELING		L	2400.00 SqFt 250.00 SqFt			
48	L & T CR		L	356.00 Ft			
Samn	ole Number: 335	Туре:	R	Area:	5000.00 SqFt	PCI: 62	
-	ole Comments:				1		
-							
48	L & T CR		L	434.00 Ft			
56 52	SWELLING RAVELING		L L	15.00 SqFt 200.00 SqFt			
52 57	WEATHERING		M	2400.00 SqFt			
57	WEATHERING		L	2400.00 SqFt			
	ole Number: 341	Туре:	R	Area:	5000.00 SqFt	PCI: 67	
-	ole Comments:	- jper					
Samp							
52	RAVELING		L	1000.00 SqFt			
57 48	WEATHERING		L	2000.00 SqFt			
48 57	L & T CR WEATHERING		L M	338.00 Ft 2000.00 SqFt			
	ble Number: 347		R	Area:	5000.00 SqFt	PCI: 65	
-		Туре:	K	Alea.	5000.00 SqFt	I CI. 05	
Samp	ole Comments:						
57	WEATHERING		М	2400.00 SqFt			
57	WEATHERING		L	2400.00 SqFt			
52	RAVELING		L	200.00 SqFt			
48	L & T CR		L	405.00 Ft			
Samp	ble Number: 353	Туре:	R	Area:	5000.00 SqFt	PCI: 65	
Samp	ole Comments:						
57	WEATHERING		М	2400.00 SqFt			
57	WEATHERING		L	2400.00 SqFt			
52	RAVELING		L	200.00 SqFt			
48	L & T CR		L	386.00 Ft			
-	ble Number: 359	Туре:	R	Area:	5000.00 SqFt	PCI: 60	
Samp	ole Comments:						
48	L & T CR		L	404.00 Ft			
57	WEATHERING		М	2400.00 SqFt			
57	WEATHERING		L	2400.00 SqFt			
52	RAVELING		L	200.00 SqFt			
48	L & T CR		М	65.00 Ft			
-	ble Number: 365	Туре:	R	Area:	5000.00 SqFt	PCI: 59	
Samp	ole Comments:						
48	L & T CR		М	118.00 Ft			
57	WEATHERING		М	2400.00 SqFt			
48	L & T CR		L	424.00 Ft			
52	RAVELING		L	200.00 SqFt			
57	WEATHERING		L	2400.00 SqFt	5000.00.0.7	DCI 40	
	ble Number: 368	Туре:	R	Area:	5000.00 SqFt	PCI: 49	
Samp	ole Comments:						
57	WEATHERING		М	2400.00 SqFt			
57	WEATHERING		L	2400.00 SqFt			
48	L & T CR		М	391.00 Ft			
52 48	RAVELING L & T CR		L L	200.00 SqFt 91.00 Ft			
					5000 00 S-E		
-	ble Number: 371	Туре:	R	Area:	5000.00 SqFt	PCI: 60	
Samp	ole Comments:						
48	L & T CR		L	371.00 Ft			

48	L & T CR	М		-	
57	WEATHERING	М			
52	RAVELING	L	200.00 So		
57	WEATHERING	L	2400.00 So		
56	SWELLING	L	5.00 Sc		
Samj	ble Number: 376	Type:	R Are	: 5000.00 SqFt	PCI: 61
Samj	ole Comments:				
57	WEATHERING	L	2400.00 Sc	Ft	
57	WEATHERING	М			
48	L & T CR	L	287.00 Ft		
52	RAVELING	L	200.00 Sc	Ft	
48	L & T CR	М			
Sam	ole Number: 380	Туре:	R Are	: 5000.00 SqFt	PCI: 65
	ole Comments:			-	
		.,			
48	L & T CR	М			
48	L & T CR	L	388.00 Ft		
52	RAVELING	L	200.00 So		
52	RAVELING	М	10.00 Sc		
Samj	ole Number: 386	Type:	R Are	: 5000.00 SqFt	PCI: 56
Samj	ole Comments:				
48	L & T CR	L	405.00 Ft		
48	L & T CR	М	70.00 Ft		
52	RAVELING	Μ	30.00 Sc	Ft	
52	RAVELING	Н		Ft	
48	L & T CR	Н	5.00 Ft		
52	RAVELING	L	200.00 Sc	Ft	
Samj	ole Number: 393	Туре:	R Are	: 5000.00 SqFt	PCI: 66
Samj	ole Comments:				
57	WEATHERING	М	2600.00 So	Ft	
57	WEATHERING	L	2400.00 Sc		
56	SWELLING	L	20.00 Sc		
48	L & T CR	L	480.00 Ft		
Sam	ole Number: 397	Туре:	R Are	: 5000.00 SqFt	PCI: 63
-	ole Comments:			*	
57	WEATHERING	L	2400.00 So	Ft	
48	L & T CR	L	469.00 Ft	1 1	
40 57	WEATHERING	L M		Ft	
	RAVELING	L	200.00 Sc 200.00 Sc		
52					

NT -						DECIONAL ADDROR	
Netwo				Nam		REGIONAL AIRPORT	
Bran	ch: RW 18-36		Name:	RUNWAY 18	-36 Use:	RUNWAY A	Area: 1,097,850 SqFt
Sectio	on: 6110	of 6		From: -		То: -	Last Const.: 6/1/2002
Surfa	ce: AAC	•		RW-AAC- Zone	e:	Category:	Rank: P
•	250.000	APC		10,000 E	· · · · · · · · · · · · · · · · · · ·	25 E	
Area:		-	Lengt			25 Ft Ft	Ising Longth, Ed
Slabs		Slab Length:		Ft	Slab Width:	Ft	Joint Length: Ft
Shoul	aer: on Comments:	Street Type:			Grade: 0		Lanes: 0
Work	Date: 1/1/1943	Work 1	ype: Bu	JILT	С	ode: IMPORTED	Is Major M&R: True
Work	Date: 1/1/1971	Work T	Type: O	VERLAY	С	ode: IMPORTED	Is Major M&R: True
Work	Date: 6/1/2002	Work T	ype: M	ill and Overlay	С	ode: ML-OL	Is Major M&R: True
<u> </u>	D (2/4/2010			_	9		•
	insp. Date: 3/4/2019		Tota	dSamples: 50	Surveye	d: 10	
	itions: PCI: 57						
	ction Comments:				F000 00 7 7		
-	le Number: 100	Туре:	R	Area:	5000.00 SqFt	PCI: 60	
-	le Comments:						
48	L & T CR		L	387.00 Ft			
52 57	RAVELING WEATHERING		L M	500.00 SqFt 2300.00 SqFt			
57	WEATHERING		L	2200.00 SqFt			
48	L & T CR		M	50.00 Ft			
56	SWELLING]	L	5.00 SqFt			
Samp	le Number: 120	Type:	R	Area:	5000.00 SqFt	PCI: 55	
Samp	le Comments:						
57	WEATHERING]	М	2400.00 SqFt			
57	WEATHERING]	L	2400.00 SqFt			
48	L & T CR	1	М	100.00 Ft			
48	L & T CR		L	525.00 Ft			
52	RAVELING		L	200.00 SqFt			
56	SWELLING		L	20.00 SqFt	5000 00 G E		
•	le Number: 132	Туре:	R	Area:	5000.00 SqFt	PCI: 56	
Samp	le Comments:						
56	SWELLING]	L	15.00 SqFt			
48	L & T CR]	L	435.00 Ft			
52	RAVELING		L	250.00 SqFt			
57 48	WEATHERING L & T CR		L M	2350.00 SqFt 200.00 Ft			
48 57	L & I CR WEATHERING		M M	2400.00 Ft 2400.00 SqFt			
	le Number: 144	Туре:	R	Area:	5000.00 SqFt	PCI: 69	
-	le Comments:	~ 1			Ĩ		
57	WEATHERING	1	М	2500.00 SqFt			
57 57	WEATHERING		L	2500.00 SqFt 2500.00 SqFt			
48	L & T CR		L	413.00 Ft			
Samp	le Number: 176	Туре:	R	Area:	5000.00 SqFt	PCI: 51	
Samp	le Comments:						
57	WEATHERING]	L	2350.00 SqFt			
52	RAVELING		L	250.00 SqFt			
48	L & T CR		М	300.00 Ft			
57	WEATHERING		М	2400.00 SqFt			
56	SWELLING		L	5.00 SqFt			
48	L & T CR		L	422.00 Ft		DOI	
-	le Number: 504	Туре:	R	Area:	5000.00 SqFt	PCI: 55	
Samp	le Comments:						
48	L & T CR]	М	100.00 Ft			

57	WEATHERING	Μ	2400.00 SqFt			
57	WEATHERING	L	2350.00 SqFt			
52	RAVELING	L	250.00 SqFt			
48	L & T CR	L	512.00 Ft			
56	SWELLING	L	20.00 SqFt			
Samp	ple Number: 524	Туре:	R Area:	5000.00 SqFt	PCI: 61	
Samp	ple Comments:					
57	WEATHERING	L	2350.00 SqFt			
52	RAVELING	L	250.00 SqFt			
57	WEATHERING	М	2400.00 SqFt			
48	L & T CR	М	150.00 Ft			
48	L & T CR	L	334.00 Ft			
Sam	ple Number: 548	Туре:	R Area:	5000.00 SqFt	PCI: 56	
Samp	ple Comments:					
48	L & T CR	М	200.00 Ft			
+0 57	WEATHERING	M	2400.00 SqFt			
52	RAVELING	L	250.00 SqFt			
52 57	WEATHERING	L	2350.00 SqFt			
48	L & T CR	L	309.00 Ft			
40 56	SWELLING	L	6.00 SqFt			
	ple Number: 560	Туре:	R Area:	5000.00 SqFt	PCI: 58	
-		i ype.	K Alea.	5000.00 SqFt	ICI. 38	
Samp	ple Comments:					
52	RAVELING	L	250.00 SqFt			
48	L & T CR	М	200.00 Ft			
57	WEATHERING	М	2400.00 SqFt			
57	WEATHERING	L	2350.00 SqFt			
48	L & T CR	L	376.00 Ft			
Samp				5000 00 G E		
	ple Number: 592	Туре:	R Area:	5000.00 SqFt	PCI: 54	
Samp	ple Number: 592 ple Comments:	Туре:	R Area:	5000.00 SqFt	PCI: 54	
Samp 50		Туре: L	R Area: 98.00 SqFt	5000.00 SqFt	PCI: 54	
-	ple Comments:			5000.00 SqFt	PCI: 54	
50	ple Comments: PATCHING	L	98.00 SqFt 295.00 Ft	5000.00 SqFt	PCI: 54	
50 48	ple Comments: PATCHING L & T CR	L	98.00 SqFt	5000.00 SqFt	PCI: 54	
50 48 57	ple Comments: PATCHING L & T CR WEATHERING	L L L	98.00 SqFt 295.00 Ft 2350.00 SqFt 150.00 Ft	5000.00 SqFt	PCI: 54	
50 48 57 48	ple Comments: PATCHING L & T CR WEATHERING L & T CR	L L L M	98.00 SqFt 295.00 Ft 2350.00 SqFt 150.00 Ft 2307.00 SqFt	5000.00 SqFt	PCI: 54	
50 48 57 48 57	ple Comments: PATCHING L & T CR WEATHERING L & T CR WEATHERING	L L M M	98.00 SqFt 295.00 Ft 2350.00 SqFt 150.00 Ft	5000.00 SqFt	PCI: 54	

Netwo	ork: TIX			. <u> </u>		Nama		CECOAS	TDEC	GIONAL AIRP				<u> </u>
						Name:						1.005		
Branc				Name:		WAY 18-36	5	Use:		UNWAY	Area:		7,850 SqFt	- 11 12 0.04
Sectio		of			From:	-				То: -			Last Const.:	6/1/2002
Surfa	ce: AAC		C9N5 APC	59-PR-RW	√-AAC-	Zone:				Category:		I	Rank: P	
Area:	100,00	00 SqFt	1	Length:		1,000 Ft		Width:		100 Ft				
Slabs:		Slab Leng	th:		Ft	S	Slab Width:			Ft	J	Joint Length:	F	t
Shoul	der:	Street Typ	pe:			G	Grade: 0				J	Lanes: 0		
Sectio	n Comments:													
Work	Date: 1/1/1967	Wor	rk Ty	ype: BUIL	LT				Code:	IMPORTED)	Is Major M&	&R: True	
Work	Date: 1/1/1971	Wor	rk Ty	ype: OVEI	RLAY				Code:	IMPORTED)	Is Major M&	&R: True	
Work	Date: 6/1/2002	Wor	rk Ty	pe: Mill :	and Overla	ıy			Code:	ML-OL		Is Major M&	&R: True	
Last I	nsp. Date: 3/4/2019			TotalS	amples:	20		Surve	eyed: 5	5				
Condi	tions: PCI: 62													
Inspe	ction Comments:													
	le Number: 402	Туре		R		Area:	5000	0.00 SqFt		PCI: 0	67			
-	le Comments:	турс		ĸ	r	Area:	5000	.00 Sqr1		ru. v	57			
52	RAVELING		М	ſ	5.00) SqFt								
48	L & T CR		L		420.00									
52	RAVELING		L	r	50.00) SqFt								
48	L & T CR		М	í	12.00	Ft								
Samp	le Number: 406	Туре	e:	R		Area:	5000	0.00 SqFt		PCI: (60			
Samp	le Comments:													
57	WEATHERING		М	1	2400.00	SaFt								
48	L & T CR		M		50.00	-								
48	L & T CR		L		408.00									
52	RAVELING		L		200.00									
57	WEATHERING		L		2400.00									
Samp	le Number: 410	Туре	e:	R		Area:	5000	0.00 SqFt		PCI:	59			
Samp	le Comments:													
48	L & T CR		М	ì	125.00	/ Ft								
48	L & T CR		L		365.00) Ft								
57	WEATHERING		М	i	2400.00	-								
57	WEATHERING		L		2350.00									
56	SWELLING		L) SqFt								
52	RAVELING		L		250.00	SqFt								
-	le Number: 413	Туре	::	R	1	Area:	5000	0.00 SqFt		PCI: (63			
Samp	le Comments:													
52	RAVELING		L		200.00									
57	WEATHERING		Μ	i	2400.00									
56	SWELLING		L) SqFt								
57	WEATHERING		L		2400.00									
48	L & T CR		L		398.00	Ft								
Samp	le Number: 417	Туре	:	R	I	Area:	5000	0.00 SqFt		PCI: (61			
Samp	le Comments:													
57	WEATHERING		L		2400.00									
	L & T CR		Μ	í –	50.00	Ft								
48														
48 57	WEATHERING		Μ	ſ	2400.00									
	WEATHERING L & T CR RAVELING		M L L	r	2400.00 366.00 200.00) Ft								

Network:	TIX			Ν	ame: SF	PACE COAST	REGIONAL AIRPOF	ХT		
Branch:	RW 18-36		Name:	RUNWAY	18-36	Use:	RUNWAY	Area:	1,097,850 SqFt	
Section:	6130	of 6	-	From: -			To: -		Last Const.	: 6/1/2002
Surface:	AAC	Family: C9 AF	PN59-PR-RV PC	W-AAC- Z	one:		Category:		Rank: P	
Area:	50,000	0 SqFt	Length:	2,00	0 Ft	Width:	25 Ft			
Slabs:		Slab Length:	:	Ft	Slab Width	:	Ft	Joint Le	ength:	Ft
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Cor	mments:									
Work Date:	: 1/1/1967	Work	Type: BUI	LT		С	ode: IMPORTED	Is M	Iajor M&R: True	
Work Date:	: 1/1/1971	Work	Type: OVE	ERLAY		С	ode: IMPORTED	Is M	Iajor M&R: True	
Work Date:	: 6/1/2002	Work	Type: Mill	and Overlay		С	ode: ML-OL	Is M	Iajor M&R: True	
Last Insp. I	Date: 3/4/2019		TotalS	amples: 10		Surveye	ed: 2			
Conditions:	PCI: 60									
Inspection (Comments:									
Sample Nu	mber: 212	Туре:	R	Area	50	00.00 SqFt	PCI: 54			
Sample Cor	mments:									
57 WEA	ATHERING		М	2500.00 SqI	ł					
	ATHERING T CR		M L	2500.00 SqI 302.00 Ft	ft					
48 L&				-						
48 L & 56 SWI	T CR		L	302.00 Ft	řt					
48 L & 56 SWE 57 WEA	T CR ELLING		L L	302.00 Ft 50.00 SqF	řt					
48 L & 56 SWE 57 WE 48 L &	T CR ELLING ATHERING	Туре:	L L L	302.00 Ft 50.00 SqF 2500.00 SqF	ît ît	00.00 SqFt	PCI: 66			
48 L & 56 SWE 57 WE 48 L & Sample Nur	T CR ELLING ATHERING T CR mber: 600	Туре:	L L L M	302.00 Ft 50.00 SqF 2500.00 SqF 300.00 Ft	ît ît	00.00 SqFt	PCI: 66			
48 L & 56 SWE 57 WE 48 L & Sample Nui Sample Cor	T CR ELLING ATHERING T CR mber: 600	Туре:	L L L M	302.00 Ft 50.00 SqF 2500.00 SqF 300.00 Ft	ît ît	00.00 SqFt	PCI: 66			
48 L & 56 SWF 57 WEA 48 L & Sample Null Sample Corr 48 L &	T CR ELLING ATHERING T CR mber: 600 mments:	Туре:	L L M R	302.00 Ft 50.00 SqI 2500.00 SqI 300.00 Ft Area 150.00 Ft	St St 50	00.00 SqFt	PCI: 66			
48 L & 56 SWE 57 WE 48 L & Sample Nur Sample Cor 48 L & 57 WE	T CR ELLING ATHERING T CR mber: 600 mments: T CR	Туре:	L L M R	302.00 Ft 50.00 SqI 2500.00 SqI 300.00 Ft Area	řt st st st	00.00 SqFt	PCI: 66			

Network: TIX		Name:	SPACE COAST I	REGIONAL AIRPOI	RT
Branch: RW 18-36	Name	: RUNWAY 18-36	Use:	RUNWAY	Area: 1,097,850 SqFt
Section: 6145	of 6	From: -		To: -	Last Const.: 6/1/2002
Surface: AAC	Family: C9N59-PR APC	R-RW-AAC- Zone:		Category:	Rank: P
Area: 131,90	0 SqFt Leng	th: 1,319 Ft	Width:	100 Ft	
Slabs:	Slab Length:	Ft Slal	o Width:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Gra	de: 0		Lanes: 0
Section Comments:					
Work Date: 1/1/1971	Work Type: 1	New Construction - Initial	Co	ode: NU-IN	Is Major M&R: True
Work Date: 6/1/2002	Work Type: N	Mill and Overlay	Co	ode: ML-OL	Is Major M&R: True
Last Insp. Date: 3/4/2019	То	talSamples: 26	Surveye	1: 5	
Conditions: PCI: 65					
Inspection Comments:					
Sample Number: 421	Type: R	Area:	5000.00 SqFt	PCI: 59	
Sample Comments:					
57 WEATHERING	L	2400.00 SqFt			
48 L & T CR	М	12.00 Ft			
52 RAVELING	L	200.00 SqFt			
56 SWELLING	L	30.00 SqFt			
48 L & T CR	L	365.00 Ft			
57 WEATHERING	М	2400.00 SqFt			
Sample Number: 429	Type: R	Area:	5000.00 SqFt	PCI: 66	
Sample Comments:					
57 WEATHERING	L	2350.00 SqFt			
48 L & T CR	L	379.00 Ft			
52 RAVELING	L	250.00 SqFt			
57 WEATHERING	М	2400.00 SqFt			
Sample Number: 437	Type: R	Area:	5000.00 SqFt	PCI: 67	
Sample Comments:					
57 WEATHERING	L	2400.00 SqFt			
48 L & T CR	L	344.00 Ft			
57 WEATHERING	М	2400.00 SqFt			
52 RAVELING	L	200.00 SqFt			
Sample Number: 440	Type: R	Area:	5000.00 SqFt	PCI: 65	
Sample Comments:					
52 RAVELING	L	500.00 SqFt			
48 L & T CR	L	465.00 Ft			
56 SWELLING	L	35.00 SqFt			
57 WEATHERING	М	4500.00 SqFt			
Sample Number: 445	Type: R	Area:	6900.00 SqFt	PCI: 67	
Sample Comments:					
50 PATCHING	М	31.00 SqFt			
48 L & T CR	L	457.00 Ft			
52 RAVELING	L	69.00 SqFt			
57 WEATHERING	M	6800.00 SqFt			
		····· ··· ··· ··· ··· ··· ··· ··· ···			

	k: TIX				N	ame: SP	ACE COAST	Г REGI	ONAL AIRPO	ORT			
Branch			N	ame: F	RUNWAY		Use:		NWAY	Area:	1,097	7,850 SqFt	
Section	6150	of	6	From	: -				То: -			Last Const.:	6/1/2002
Surface	: AAC		C9N59 APC	9-PR-RW-AA	C- Zo	one:			Category:			Rank: P	
Area:	65,950	0 SqFt	I	Length:	2,600	Ft	Width:		25 Ft				
Slabs:		Slab Leng	th:		Ft	Slab Width:			Ft	Joint l	Length:	Ft	
Shoulde	er:	Street Typ	e:			Grade: ()			Lanes	: 0		
Section	Comments:												
Work F	Date: 1/1/1967	Woi	rk Typ	e: BUILT				Code:	IMPORTED	Is	Major Ma	&R: True	
Work [Date: 1/1/1971	Woi	·k Typ	e: OVERLAY	Ý			Code:	IMPORTED	Is	Major Ma	&R: True	
Work E	Date: 6/1/2002	Woi	·k Typ	e: Mill and O	verlay			Code:	ML-OL	Is	Major Ma	&R: True	
Last In:	sp. Date: 3/4/2019			TotalSample	es: 14		Survey	ed: 3					
Conditi	ons: PCI: 64												
Inspecti	ion Comments:												
Sample	Number: 220	Туре	:	R	Area:	500	0.00 SqFt		PCI: 6	7			
Sample	Comments:						-						
	L & T CR		М	10	0.00 Ft								
	WEATHERING		Μ		0.00 SqFt								
	L & T CR		L		6.00 Ft								
	RAVELING	Tour	L		0.00 SqFt		0.00 S-Et		DCL 5	0			
-	Number: 222	Туре	:	R	Area:	3/3	0.00 SqFt		PCI: 5	9			
Sample	Comments:												
	WEATHERING		L		2.00 SqFt								
	L&TCR		М		0.00 Ft								
	L & T CR		L		1.00 Ft								
	SWELLING		L		5.00 SqFt								
	WEATHERING		M		0.00 SqFt								
	RAVELING		L		8.00 SqFt								
1	Number: 618	Туре	:	R	Area:	500	00.00 SqFt		PCI: 6	5			
Sample	Comments:												
48 1	L & T CR		L	34	4.00 Ft								
	RAVELING		L		0.00 SqFt								
-	L&TCR		М		0.00 Ft								
18 1				10									
	WEATHERING		Μ	375	0.00 SqFt								

Netwo	ork: TIX			Nam	e: SPACE CO.	AST REG	IONAL AIRPOR	λΤ
Branc	h: RW 9-27		Name:	RUNWAY 9-2	27 U	se: RI	UNWAY	Area: 489,743 SqFt
Sectio	n: 6205	of	2	From: -			То: -	Last Const.: 1/1/1998
Surfac	ce: AAC		C9N59-PR- APC	RW-AAC- Zon	e:		Category:	Rank: S
Area:	169,743	3 SqFt	Lengtl	h: 1,650 F	t Width		100 Ft	
Slabs:		Slab Leng	gth:	Ft	Slab Width:		Ft	Joint Length: Ft
Shoul	der:	Street Typ			Grade: 0			Lanes: 0
	n Comments:	~						
Work	Date: 1/1/1943	Wo	rk Type: BU	UILT		Code:	IMPORTED	Is Major M&R: True
Work	Date: 1/1/1976	Wo	rk Type: O	VERLAY		Code:	IMPORTED	Is Major M&R: True
Work	Date: 1/1/1998	Wo	rk Type: M	ill and Overlay		Code:	ML-OL	Is Major M&R: True
Last I	nsp. Date: 3/4/2019		Tota	alSamples: 34	Sur	veyed:	7	
Condi	itions: PCI: 63							
Inspec	ction Comments:							
		T		A	5000 00 C T	4	DCL C	
-	le Number: 100	Туре	e: R	Area:	5000.00 SqF	ι	PCI: 62	
Sampl	le Comments:							
52	RAVELING		L	500.00 SqFt				
57	WEATHERING		М	2500.00 SqFt				
48	L & T CR		L	528.00 Ft				
57	WEATHERING		L	2000.00 SqFt				
-	le Number: 105	Туре	e: R	Area:	5000.00 SqF	t	PCI: 64	
Samp	le Comments:							
48	L & T CR		L	434.00 Ft				
57	WEATHERING		L	2400.00 SqFt				
52	RAVELING WEATHERING		L M	1600.00 SqFt				
57		T		1000.00 SqFt	5000 00 G T		DCI 50	
-	le Number: 114	Туре	e: R	Area:	5000.00 SqF	t	PCI: 58	
Samp	le Comments:							
48	L & T CR		L	289.00 Ft				
48	L & T CR		М	200.00 Ft				
57 52	WEATHERING		M	1125.00 SqFt				
52 57	RAVELING WEATHERING		L L	100.00 SqFt 3375.00 SqFt				
	le Number: 117	Туре		Area:	5000.00 SqF	t	PCI: 60	
-	le Comments:	rype		mica.	5555.55 541	•	1 01. 00	
-								
48	L & T CR		L	558.00 Ft				
57 56	WEATHERING SWELLING		L	2250.00 SqFt 10.00 SqFt				
56 57	WEATHERING		L M	2250.00 SqFt				
52	RAVELING		L	100.00 SqFt				
Samp	le Number: 122	Туре	e: R	Area:	5000.00 SqF	t	PCI: 66	
-	le Comments:	••			1			
-			т	100.00 0 5				
52 48	RAVELING L & T CR		L L	100.00 SqFt 396.00 Ft				
40 57	WEATHERING		L M	2250.00 SqFt				
57	WEATHERING		L	2250.00 SqFt				
Samp	le Number: 130	Туре	e: R	Area:	5000.00 SqF	t	PCI: 66	
Samp	le Comments:							
48	L & T CR		L	449.00 Ft				
57	WEATHERING		L	2500.00 SqFt				
57	WEATHERING		M	2450.00 SqFt				
52	RAVELING		L	50.00 SqFt				

Sam	ple Number: 134	Type: R	Area:	5000.00 SqFt	PCI: 64
Sam	ple Comments:				
52	RAVELING	L	100.00 SqFt		
57	WEATHERING	М	2450.00 SqFt		
57	WEATHERING	L	2450.00 SqFt		
48	L & T CR	L	423.00 Ft		
56	SWELLING	L	5.00 SqFt		

Network: TIX			Nama		REGIONAL AIRPO	DT
			Name:			
Branch: RW 9-27		Name:	RUNWAY 9-27	Use:	RUNWAY	Area: 489,743 SqFt
Section: 6210	of	2	From: -		To: -	Last Const.: 1/1/1998
Surface: AAC		C9N59-PR-RV APC	W-AAC- Zone:		Category:	Rank: S
Area: 32	20,000 SqFt	Length:	3,200 Ft	Width:	100 Ft	
Slabs: 34	Slab Lengt	-		Width:	50 Ft	Joint Length: 1,650 Ft
Shoulder:	Street Type		Grad		5011	Lanes: 0
Section Comments:	Street Type		Gra	uc. 0		
Work Date: 1/1/1943	Word	r Tunas Mari	Construction - AC		Code: NC-AC	Is Major M&R: True
work Date. 1/1/1/43		k Type. New	Construction - AC		coue. NC-AC	is major max. The
Work Date: 1/1/1976	Worl	k Type: Over	rlay - AC Structural	(Code: OL-AS	Is Major M&R: True
Work Date: 1/1/1998	Worl	k Type: Over	rlay - AC Structural	(Code: OL-AS	Is Major M&R: True
Last Insp. Date: 3/4/2	2019	TotalS	Samples: 64	Survey	red: 13	
Conditions: PCI:	53					
Inspection Comments:						
Sample Number: 136	Туре:	R	Area:	5000.00 SqFt	PCI: 49)
Sample Comments:						
57 WEATHERING		L	2400.00 SqFt			
43 BLOCK CR		L	1850.00 SqFt			
52 RAVELING		L	150.00 SqFt			
48 L & T CR57 WEATHERING		L M	286.00 Ft 2450.00 SqFt			
56 SWELLING		L	215.00 SqFt			
Sample Number: 141	Туре:	R	Area:	5000.00 SqFt	PCI: 47	7
Sample Comments:	•••					
52 RAVELING		L	200.00 SqFt			
57 WEATHERING		L	2400.00 SqFt			
48 L & T CR		L	105.00 Ft			
56 SWELLING		L	250.00 SqFt			
43 BLOCK CR		L	2500.00 SqFt			
57 WEATHERING Sample Number: 148		M R	2400.00 SqFt Area:	5000.00 SqFt	PCI: 44	1
Sample Comments:	Type.	К	Alca.	5000.00 SqFt	101. 4	t
•						
52 RAVELING		L	200.00 SqFt			
57 WEATHERING 56 SWELLING		L L	2400.00 SqFt 260.00 SqFt			
57 WEATHERING		M	2400.00 SqFt			
48 L & T CR		М	15.00 Ft			
43 BLOCK CR		L	2000.00 SqFt			
48 L & T CR Sample Number: 155	Туре:	L R	150.00 Ft Area:	5000.00 SqFt	PCI: 51	
Sample Comments:	i ype.	K	Aita.	5000.00 Sqrt	TCI. J	
57 WEATHERING		М	2450.00 SqFt			
48 L & T CR		L	549.00 Ft			
52 RAVELING		L	150.00 SqFt			
56 SWELLING 56 SWELLING		M L	40.00 SqFt 150.00 SqFt			
57 WEATHERING		L	2400.00 SqFt			
Sample Number: 162		R	Area:	5000.00 SqFt	PCI: 43	3
Sample Comments:						
56 SWELLING		М	10.00 SqFt			
57 WEATHERING		M	2400.00 SqFt			
48 L & T CR		L	400.00 Ft			
57 WEATHERING		L M	2350.00 SqFt			
48 L & T CR 52 RAVELING		M L	50.00 Ft 250.00 SqFt			
1011120110		-	5411			

43	BLOCK CR		L	700.0	00 SqFt			
56	SWELLING		L	850.0	00 SqFt			
Samp	ole Number: 165	Type:		R	Area:	5000.00 SqFt	PCI:	47
Samp	ole Comments:							
57	WEATHERING		М		00 SqFt			
48	L & T CR		L		00 Ft			
52	RAVELING SWELLING		L)0 SqFt)0 SqFt			
56 43	SWELLING BLOCK CR		L L		00 SqFt 00 SqFt			
48	L & T CR		M		0 Ft			
57	WEATHERING		L		00 SqFt			
Samp	ole Number: 169	Type:		R	Area:	5000.00 SqFt	PCI:	54
Samp	ole Comments:							
48	L & T CR		L		00 Ft			
52	RAVELING		L		00 SqFt			
57	WEATHERING		М		00 SqFt			
56	SWELLING		L L)0 SqFt)0 SqFt			
57	WEATHERING				•	5000.00 0 5	DOL	
-	ole Number: 176	Type:		R	Area:	5000.00 SqFt	PCI:	61
Samp	ole Comments:							
52	RAVELING		L		00 SqFt			
57	WEATHERING		L		00 SqFt			
56	SWELLING		L		00 SqFt			
48 57	L & T CR WEATHERING		L M		00 Ft 00 SqFt			
						5000.00 G E	DCI	
-	ble Number: 179	Туре:		R	Area:	5000.00 SqFt	PCI:	59
Samp	ole Comments:							
57	WEATHERING		L	2350.0	00 SqFt			
57	WEATHERING		М	2350.0	00 SqFt			
52	RAVELING		L		00 SqFt			
56	SWELLING		L		00 SqFt			
48	L & T CR		L		00 Ft			
48	L & T CR		М		00 Ft			
-	ble Number: 183	Type:		R	Area:	5000.00 SqFt	PCI:	55
Samp	ole Comments:							
52	RAVELING		L	200.0	00 SqFt			
48	L & T CR		М		00 Ft			
57	WEATHERING		М		00 SqFt			
56	SWELLING		L		00 SqFt			
48 57	L & T CR WEATHERING		L L		00 Ft 00 SqFt			
	ble Number: 186	Туре:		R 2100.	Area:	5000.00 SqFt	PCI:	51
-		Type.		K	Alta.	5000.00 Sqrt	TCI.	51
samp	ble Comments:							
48	L & T CR		L		00 Ft			
57	WEATHERING		М		00 SqFt			
52	RAVELING		L		00 SqFt			
56 48	SWELLING		L M		00 SqFt 00 Ft			
48 56	L & T CR SWELLING		M M		00 Ft 00 SqFt			
50 57	WEATHERING		L		0 SqFt 0 SqFt			
	ble Number: 190	Туре:		R 2550.	Area:	5000.00 SqFt	PCI:	64
-	ole Comments:	1,100					101	
-			т	1.00-				
57 48	WEATHERING		L L		00 SqFt 00 Ft			
48 56	L & T CR SWELLING		L L		0 Ft 00 SqFt			
52	RAVELING		L		0 SqFt			
57	WEATHERING		M		00 SqFt			
Samr	ole Number: 194	Туре:		R	Area:	5000.00 SqFt	PCI:	59
-	ole Comments:	v 1 · · ·				Ł		
-								
57	WEATHERING		М	250.0	00 SqFt			

48	L & T CR	L	391.00	Ft
52	RAVELING	L	2500.00	SqFt
57	WEATHERING	L	2250.00	SqFt
56	SWELLING	L	600.00	SqFt

Network: TIX		Name:	SPACE COAST P	EGIONAL AIRPOR	Γ	
	N 7					
Branch: TW A	Name:	TAXIWAY A	Use:		Area: 355,28	-
Section: 105	of 5 I	rom: -		То: -	Las	st Const.: 6/1/2002
Surface: AAC	Family: C9N59-PR-TW APC	AAC- Zone:		Category:	Ra	nk: P
Area: 114,65	1 SqFt Length:	2,200 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft Slab	Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:	Grad	le: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1943	Work Type: BUIL	Л	Cod	le: IMPORTED	Is Major M&R	: True
Work Date: 1/1/1971	Work Type: OVE	RLAY	Cod	le: IMPORTED	Is Major M&R	: True
Work Date: 6/1/2002	Work Type: Mill a	and Overlay	Cod	le: ML-OL	Is Major M&R	: True
Last Insp. Date: 3/4/2019	TotalS	amples: 22	Surveyed	: 4		
Conditions: PCI: 68						
Inspection Comments:						
Sample Number: 100	Type: R	Area:	5432.00 SqFt	PCI: 65		
Sample Comments:						
48 L & T CR	L	310.00 Ft				
57 WEATHERING48 L & T CR	M M	5432.00 SqFt 200.00 Ft				
Sample Number: 108	Type: R	Area:	5000.00 SqFt	PCI: 67		
Sample Comments:	Type. R	/ 11 ca.	5000.00 5411			
56 SWELLING	L	60.00 SqFt				
48 L&TCR	L	533.00 Ft				
57 WEATHERING	М	5000.00 SqFt				
Sample Number: 113	Type: R	Area:	5000.00 SqFt	PCI: 71		
Sample Comments:						
48 L & T CR	L	467.00 Ft				
56 SWELLING	L	25.00 SqFt				
57 WEATHERING	М	5000.00 SqFt				
Sample Number: 118	Type: R	Area:	5000.00 SqFt	PCI: 70		
Sample Comments:						
57 WEATHERING	М	5000.00 SqFt				
56 SWELLING	L	45.00 SqFt				
48 L & T CR	L	467.00 Ft				

Network: TIX		Name	: SPACE COAS	T REGIONAL AIRPO	DRT	
Branch: TW A	Name:	TAXIWAY A	Use	: TAXIWAY	Area:	355,289 SqFt
Section: 110	of 5	From: -		То: -		Last Const.: 6/1/200
Surface: AAC	Family: C9N59-PR-TW APC	W-AAC- Zone:		Category:		Rank: P
Area: 70,0	00 SqFt Length:	1,400 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft S	Slab Width:	Ft	Joint Le	ength: Ft
Shoulder:	Street Type:	•	Grade: 0		Lanes:	0
Section Comments:						
Work Date: 1/1/1943	Work Type: BUII	LT		Code: IMPORTED	Is N	Iajor M&R: True
Work Date: 1/1/1971	Work Type: OVE	ERLAY		Code: IMPORTED	Is N	Iajor M&R: True
Work Date: 1/1/1992	Work Type: REP.	AIR		Code: IMPORTED	Is N	Iajor M&R: False
Work Date: 6/1/2002	Work Type: Mill	and Overlay		Code: ML-OL	Is N	Iajor M&R: True
Last Insp. Date: 3/4/2019	TotalS	amples: 14	Surve	yed: 3		
Conditions: PCI: 66	TotalS	amples: 14	Surve	yed: 3		
Conditions: PCI: 66 inspection Comments:	TotalS Type: R	amples: 14 Area:	Surve	yed: 3	9	
Conditions: PCI: 66 Inspection Comments: Sample Number: 121				-	9	
Conditions: PCI: 66 Inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING	Type: R L	Area: 50.00 SqFt		-	9	
Conditions: PCI: 66 Inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING	Type: R L M	Area: 50.00 SqFt 4950.00 SqFt		-	9	
Conditions: PCI: 66 inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING 18 L & T CR	Type: R L M L	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft	5000.00 SqFt	PCI: 6		
Conditions: PCI: 66 Inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING 48 L & T CR Sample Number: 127	Type: R L M	Area: 50.00 SqFt 4950.00 SqFt		-		
Conditions: PCI: 66 nspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING 58 L & T CR 59 59 50 50 50 51 52 52 53 54 55 55 55 55 55 55 55 55 55	Type: R L M L M Type: R	50.00 SqFt 4950.00 SqFt 518.00 Ft Area:	5000.00 SqFt	PCI: 6		
Conditions: PCI: 66 inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING 58 L & T CR Sample Number: 127 Sample Comments: 58 L & T CR	Type: R L M L K Type: R L L	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft Area: 526.00 Ft	5000.00 SqFt	PCI: 6		
Conditions: PCI: 66 inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING 58 L & T CR Sample Comments: 58 L & T CR 59 WEATHERING	Type: R L M L M Type: R L M M L	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft Area: 526.00 Ft 4950.00 SqFt	5000.00 SqFt	PCI: 6		
Conditions: PCI: 66 nspection Comments: Sample Number: 121 Sample Comments: 2 RAVELING 7 WEATHERING 8 L & T CR 5 ample Comments: 8 L & T CR 7 WEATHERING 2 RAVELING	Type: R L M L K Type: R L L	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft Area: 526.00 Ft	5000.00 SqFt	PCI: 6		
Conditions: PCI: 66 nspection Comments: Sample Number: 121 Sample Comments: 2 RAVELING 7 WEATHERING 8 L & T CR 5 ample Comments: 8 L & T CR 7 WEATHERING 2 RAVELING 3 BLOCK CR	Type: R L M L M Type: R L M L L L L L L L L L L L L L L L L L L L L L L	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft Area: 526.00 Ft 4950.00 SqFt 50.00 SqFt	5000.00 SqFt	PCI: 6	3	
Conditions: PCI: 66 inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING 58 L & T CR 59 Sample Comments: 59 L & T CR 50 WEATHERING 50 RAVELING 52 RAVELING 53 BLOCK CR 53 Sample Number: 131	Type: R L M L M Type: R L M L L L L L L L L L L L L L L L L L L L L L L	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft Sz6.00 Ft 526.00 Ft 4950.00 SqFt 50.00 SqFt	5000.00 SqFt 5000.00 SqFt	PCI: 6	3	
Conditions: PCI: 66 Inspection Comments: Sample Number: 121 Sample Comments: 2 RAVELING 57 WEATHERING 48 L & T CR Sample Number: 127 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING 43 BLOCK CR Sample Number: 131 Sample Comments:	Type: R L M L M Type: R L M L L L L L L L L L L L L L L L L L L L L L L	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft S26.00 Ft 526.00 SqFt 50.00 SqFt	5000.00 SqFt 5000.00 SqFt	PCI: 6	3	
Inspection Comments: Sample Number: 121 Sample Comments: 52 RAVELING 57 WEATHERING 48 L & T CR Sample Number: 127 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING	Type: R L M Type: R L M L L Type: R Type: R	Area: 50.00 SqFt 4950.00 SqFt 518.00 Ft Sz6.00 Ft 526.00 Ft 4950.00 SqFt 50.00 SqFt	5000.00 SqFt 5000.00 SqFt	PCI: 6	3	

Network: TIX		Ν	ame: SPA	ACE COAST R	EGIONAL AIRPOR	RT	
Branch: TW A	Nar	ne: TAXIWAY	Υ Α	Use:	TAXIWAY	Area:	355,289 SqFt
Section: 112	of 5	From: -			То: -		Last Const.: 6/1/2002
Surface: AAC	Family: C9N59- APC	PR-TW-AAC- Z	Zone:		Category:		Rank: P
Area: 30,0	000 SqFt Le	ngth: 60	0 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft	Slab Width:		Ft	Joint Len	gth: Ft
Shoulder:	Street Type:		Grade: 0			Lanes:	0
Section Comments:							
Work Date: 1/1/1943	Work Type	: BUILT		Co	de: IMPORTED	Is Ma	jor M&R: True
Work Date: 1/1/1971	Work Type	OVERLAY		Co	de: IMPORTED	Is Ma	jor M&R: True
Work Date: 6/1/2002	Work Type	: Mill and Overlay		Co	de: ML-OL	Is Ma	jor M&R: True
Last Insp. Date: 3/4/2019)	FotalSamples: 6		Surveyed	: 2		
Conditions: PCI: 67							
Inspection Comments:							
Sample Number: 134	Type:	R Area	: 500	0.00 SqFt	PCI: 69		
Sample Comments:							
48 L & T CR	L	487.00 Ft					
57 WEATHERING	М	4950.00 SqI	⁷ t				
52 RAVELING	L	50.00 SqI	⁷ t				
Sample Number: 137	Type: I	R Area	: 500	0.00 SqFt	PCI: 64		
Sample Comments:							
48 L & T CR	L	350.00 Ft					
57 WEATHERING	М	4850.00 SqI	⁷ t				
48 L & T CR	М	100.00 Ft					

Network: TIX		Nan	ne: SPACE COAST	REGIONAL AIRPORT	Г	
Branch: TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area: 35	55,289 SqFt
Section: 115	of 5	From: -		To: -		Last Const.: 6/1/2002
Surface: AAC	Family: C9N59-PR- APC	TW-AAC- Zon	e:	Category:		Rank: P
Area: 50,0	00 SqFt Lengt	h: 1,000 H	ft Width:	50 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:		Grade: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1967	Work Type: B	UILT	(ode: IMPORTED	Is Major N	1&R: True
Work Date: 1/1/1971	Work Type: O	VERLAY	C	ode: IMPORTED	Is Major N	I&R: True
Work Date: 6/1/2002	Work Type: M	ill and Overlay	C	ode: ML-OL	Is Major N	I&R: True
Last Insp. Date: 3/4/2019	Tota	alSamples: 10	Survey	ed: 2		
Conditions: PCI: 67						
Inspection Comments:						
Sample Number: 143	Type: R	Area:	5000.00 SqFt	PCI: 70		
Sample Comments:						
48 L & T CR	М	100.00 Ft				
48 L & T CR	L	268.00 Ft				
57 WEATHERING	М	5000.00 SqFt				
Sample Number: 148	Type: R	Area:	5000.00 SqFt	PCI: 64		
Sample Comments:						
57 WEATHERING	М	4800.00 SqFt				
52 RAVELING	L	200.00 SqFt				
56 SWELLING	L	12.00 SqFt				
48 L & T CR	L	550.00 Ft				

Network: TIX		Nan	ne: SPACE COAST	REGIONAL AIRPOR	Т	
Branch: TW A	Nar	me: TAXIWAY A	Use:	TAXIWAY	Area: 3	355,289 SqFt
Section: 120	of 5	From: -		То: -		Last Const.: 6/1/2002
Surface: AAC	Family: C9N59- APC	PR-TW-AAC- Zon	e:	Category:		Rank: P
Area: 90,6	38 SqFt Le	ength: 1,800 F	ft Width:	50 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:		Grade: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1967	Work Type	: BUILT	(Code: IMPORTED	Is Major I	M&R: True
Work Date: 1/1/1971	Work Type	: OVERLAY	(Code: IMPORTED	Is Major I	M&R: True
Work Date: 6/1/2002	Work Type	: Mill and Overlay	(Code: ML-OL	Is Major 1	M&R: True
Last Insp. Date: 3/4/2019	[TotalSamples: 17	Survey	ed: 3		
Conditions: PCI: 65						
Inspection Comments:	Type: 1	R Area:	5000.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151	Туре: 1	R Area:	5000.00 SqFt	PCI: 75		
Conditions: PCI: 65 Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING	Type: I	R Area: 5000.00 SqFt	5000.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments:			5000.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING	M L	5000.00 SqFt	5000.00 SqFt 5007.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157	M L	5000.00 SqFt 327.00 Ft				
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments:	М L Туре: І	5000.00 SqFt 327.00 Ft R Area:				
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR	M L	5000.00 SqFt 327.00 Ft				
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments: 57 WEATHERING 48 L & T CR	M L Type: H L	5000.00 SqFt 327.00 Ft R Area: 5007.00 SqFt				
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments: 57 WEATHERING 48 L & T CR Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 162	M L Type: H M L	5000.00 SqFt 327.00 Ft R Area: 5007.00 SqFt 366.00 Ft	5007.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments: 57 WEATHERING	M L Type: H M L	5000.00 SqFt 327.00 Ft R Area: 5007.00 SqFt 366.00 Ft R Area:	5007.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 162 Sample Comments: 52 RAVELING	M L Type: I M L Type: I	5000.00 SqFt 327.00 Ft R Area: 5007.00 SqFt 366.00 Ft	5007.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 162 Sample Comments: 52 RAVELING 48 L & T CR	M L Type: I M L Type: I	5000.00 SqFt 327.00 Ft R Area: 5007.00 SqFt 366.00 Ft R Area: 619.00 SqFt	5007.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 162 Sample Comments: 52 RAVELING 48 L & T CR	M L Type: I M L Type: I L L	5000.00 SqFt 327.00 Ft R Area: 5007.00 SqFt 366.00 Ft R Area: 619.00 SqFt 561.00 Ft	5007.00 SqFt	PCI: 75		
Inspection Comments: Sample Number: 151 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 157 Sample Comments: 57 WEATHERING 48 L & T CR Sample Number: 162 Sample Comments: 52 RAVELING 48 L & T CR 56 SWELLING	M L Type: I M L L Type: I L L L	5000.00 SqFt 327.00 Ft R Area: 5007.00 SqFt 366.00 Ft R Area: 619.00 SqFt 561.00 Ft 125.00 SqFt	5007.00 SqFt	PCI: 75		

Network: TIX		Name:	SPACE COAST R	EGIONAL AIRPORT	
Branch: TW A2	Name:	TAXIWAY A2	Use:	TAXIWAY A	rea: 35,137 SqFt
Section: 125	of 1	From: -		То: -	Last Const.: 6/1/2002
Surface: AAC	Family: C9N59-PR-T APC	W-AAC- Zone:		Category:	Rank: P
Area: 35,1	37 SqFt Length:	600 Ft	Width:	500 Ft	
Slabs:	Slab Length:	Ft Slab	Width:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Grad	le: 0		Lanes: 0
Section Comments:					
Work Date: 1/1/1943	Work Type: BUI	LT	Coo	le: IMPORTED	Is Major M&R: True
Work Date: 1/1/1971	Work Type: OVI	ERLAY	Coo	le: IMPORTED	Is Major M&R: True
Work Date: 6/1/2002	Work Type: Mill	and Overlay	Coo	le: ML-OL	Is Major M&R: True
Last Insp. Date: 3/4/2019) Totals	Samples: 7	Surveyed	: 2	
Conditions: PCI: 65					
Inspection Comments:					
Sample Number: 300	Type: R	Area:	6780.00 SqFt	PCI: 64	
Sample Comments:					
52 RAVELING	L	339.00 SqFt			
57 WEATHERING	L	3220.00 SqFt			
56 SWELLING	L	10.00 SqFt			
48 L&TCR	L	209.00 Ft			
57 WEATHERING 48 L & T CR	M M	3221.00 SqFt 100.00 Ft			
			5054.00 SqFt	PCI: 67	
Sample Number: 303	Type: R				
Sample Number: 303 Sample Comments:	Type: R	Area:			
Sample Comments:			e oc noo eqri		
Sample Comments: 48 L&TCR	М	100.00 Ft			
Sample Comments: 48 L&TCR 56 SWELLING	M L	100.00 Ft 50.00 SqFt			
Sample Comments: 48 L&TCR	М	100.00 Ft			

Network:	TIX				Name:	SPAG	CE COAST	REGIONAL AIRP	ORT		
Branch:	TW B		Name:	TAXIW	AY B		Use:	TAXIWAY	Area:	256,505	SqFt
Section:	205	C	of 2	From: -				То: -		Last	Const.: 6/1/2002
Surface:	AAC	Family:	C9N59-PR-T APC	W-AAC-	Zone:			Category:		Ran	k: P
Area:		22,146 SqFt	Length	:	400 Ft		Width:	50 Ft			
Slabs:		Slab Lei	ngth:	Ft	Slab	Width:		Ft	Joint Le	ength:	Ft
Shoulder:		Street T	ype:		Gra	de: 0			Lanes:	0	
Section Co	omments:										
Work Dat	e: 1/1/194	3 W	ork Type: BU	ILT			(Code: IMPORTED	Is N	lajor M&R:	True
Work Dat	e: 1/1/197	5 W	ork Type: OV	ERLAY			(Code: IMPORTED	Is N	lajor M&R:	True
Work Dat	e: 6/1/2002	2 W	ork Type: Mil	ll and Overlay			(Code: ML-OL	Is N	lajor M&R:	True
Last Insp.	Date: 3/2	4/2019	Total	Samples: 4			Survey	ed: 1			
Condition	s: PCI:	57									
Inspection	Comment	s:									
Sample Nu	umber: 5	02 Ty	pe: R	Ar	ea:	5000.	00 SqFt	PCI: 5	57		
Sample Co	omments:										
52 RA	VELING		L	250.00 \$	SqFt						
	& T CR		L	250.00 H							
	OCK CR		L	2500.00 \$							
57 WE	EATHERIN	G	М	4750.00 \$	SqFt						

Network: TIX		Name:	SPACE COAST RE	GIONAL AIRPOR	RT
Branch: TW B	Name:	TAXIWAY B	Use: T	AXIWAY	Area: 256,505 SqFt
Section: 210	of 2 F	rom: -		То: -	Last Const.: 1/1/2013
Surface: AAC	Family: C9N59-PR-TW APC	V-AAC- Zone:		Category:	Rank: P
Area: 234,35	9 SqFt Length:	4,600 Ft	Width:	50 Ft	
Slabs:	Slab Length:	Ft Sla	ab Width:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Gi	rade: 0		Lanes: 0
Section Comments:					
Work Date: 1/1/1943	Work Type: BUIL	ΔT	Code	: IMPORTED	Is Major M&R: True
Work Date: 1/1/1976	Work Type: OVE	RLAY	Code	: IMPORTED	Is Major M&R: True
Work Date: 1/1/2013	Work Type: MILL	and OVERLAY	Code	: ML-OV	Is Major M&R: True
Last Insp. Date:3/4/2019Conditions:PCI:89Inspection Comments:	TotalSa	amples: 47	Surveyed:	7	
Sample Number: 500	Type: R	Area:	5537.00 SqFt	PCI: 92	
Sample Comments:	-		*		
57 WEATHERING	L	5537.00 SqFt			
48 L&TCR	L	3.00 Ft			
Sample Number: 506	Type: R	Area:	5001.00 SqFt	PCI: 94	
Sample Comments:	, r			/	
-	Ŧ	5001.00 C T			
57 WEATHERING	L	5001.00 SqFt	5000.00.0.5	DOT C	
Sample Number: 515	Type: R	Area:	5000.00 SqFt	PCI: 94	
Sample Comments:					
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 525	Type: R	Area:	5000.00 SqFt	PCI: 94	
Sample Comments:					
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 533	Type: R	Area:	5000.00 SqFt	PCI: 84	
Sample Comments:			-		
48 L & T CR	L	143.00 Ft			
57 WEATHERING	L	5000.00 SqFt			
56 SWELLING	L	15.00 SqFt			
Sample Number: 541 Sample Comments:	Type: R	Area:	5000.00 SqFt	PCI: 85	
-	т	50.00 S-E4			
52 RAVELING48 L & T CR	L L	50.00 SqFt 49.00 Ft			
56 SWELLING	L	25.00 SqFt			
57 WEATHERING	L	4950.00 SqFt			
Sample Number: 545	Type: R	Area:	5000.00 SqFt	PCI: 80	
Sample Comments:					
57 WEATHERING	L	5000.00 SqFt			
56 SWELLING	L	5.00 SqFt			
48 L & T CR	L	228.00 Ft			

Network:	TIX				Name:	SPACE COAST	F REGIONA	L AIRPORT				
Branch:	TW C		Name:	TAXIW	AY C	Use:	TAXIW	AY A	Area:	196	5,395 SqFt	
Section:	305	of	3	From: -			To:	-			Last Cons	it.: 1/1/2004
Surface:	AAC	Family:	C9N59-PR-T APC	ГW-AAC-	Zone:		Cate	gory:			Rank: P	
Area:	4	46,879 SqFt	Length	1:	700 Ft	Width:		65 Ft				
Slabs:		Slab Len	gth:	Ft	Slab Wi	dth:	Ft		Joint Le	ength:		Ft
Shoulder:		Street Ty	pe:		Grade:	0			Lanes:	0		
Section Cor	mments:											
Work Date:	: 1/1/1943	We	ork Type: BU	JILT			Code: IMP	ORTED	Is N	lajor Ma	&R: True	
Work Date:	: 1/1/1971	We	ork Type: OV	VERLAY			Code: IMP	ORTED	Is N	lajor Ma	&R: True	
Work Date:	: 1/1/2004	We	ork Type: Mi	ill and Overlay		(Code: ML-	OL	Is N	lajor Ma	&R: True	
Last Insp. I	Date: 3/4/2	019	Tota	ISamples: 9		Survey	red: 2					
		68	Tota	ISamples: 9		Survey	red: 2					
Conditions:		68	Tota	ISamples: 9		Survey	red: 2					
Conditions: Inspection (: PCI:	68		ISamples: 9	ea:	Survey		PCI: 69				
Conditions: Inspection (Sample Nur	: PCI: Comments: mber: 701	68		-	ea:			PCI: 69				
Conditions: Inspection (Sample Nui Sample Coi	: PCI: Comments: mber: 701	68 Тур		-				PCI: 69				
Conditions: Inspection (Sample Nur Sample Cor 57 WE4	: PCI: Comments: mber: 701 mments:	68 Тур	e: R	Ar	qFt			PCI: 69				
Conditions: Inspection (Sample Nur Sample Cor 57 WEA 56 SWE	: PCI: Comments: mber: 701 mments: ATHERING	68 Typ	e: R M	Ar 2375.00 S 10.00 S 2375.00 S	qFt qFt qFt			PCI: 69				
Conditions: Inspection (Sample Nur Sample Cor 57 WE/ 56 SWE 57 WE/ 48 L &	: PCI: Comments: mber: 701 mments: ATHERING ELLING ATHERING T CR	68 Typ	e: R M L	Ar 2375.00 S 10.00 S 2375.00 S 201.00 F	qFt qFt qFt t			PCI: 69				
Conditions: Inspection (Sample Nur Sample Cor 57 WE/ 56 SWE 57 WE/ 48 L &	: PCI: Comments: mber: 701 mments: ATHERING ELLING ATHERING	68 Typ	e: R M L L	Ar 2375.00 S 10.00 S 2375.00 S	qFt qFt qFt t			PCI: 69				
Conditions: Inspection (Sample Nur Sample Con 57 WE4 56 SWE 57 WE4 48 L & 52 RAV	: PCI: Comments: mber: 701 mments: ATHERING ELLING ATHERING T CR	б8	e: R M L L L L L	Ar 2375.00 S 10.00 S 2375.00 S 201.00 F	qFt iqFt iqFt it iqFt			PCI: 69 PCI: 67				
Conditions: Inspection (Sample Nur Sample Cor 57 WE/ 56 SWE 57 WE/ 48 L & 52 RAV Sample Nur	: PCI: Comments: mber: 701 mments: ATHERING ELLING ATHERING T CR VELING mber: 704	б8	e: R M L L L L L	Ar 2375.00 S 10.00 S 2375.00 S 201.00 F 250.00 S	qFt iqFt iqFt it iqFt	5000.00 SqFt						
Conditions: Inspection (Sample Nur Sample Cor 57 WE/ 56 SWF 57 WE/ 48 L & 52 RAV Sample Nur Sample Cor	: PCI: Comments: mber: 701 mments: ATHERING ELLING ATHERING T CR VELING mber: 704 mments:	б8	e: R M L L L L L	Ar 2375.00 S 10.00 S 2375.00 S 201.00 F 250.00 S Ar	iqFt iqFt iqFt it iqFt ea:	5000.00 SqFt						
Conditions: Inspection (Sample Nur Sample Cor 57 WE/ 56 SWF 57 WE/ 48 L & 52 RAV Sample Nur Sample Cor 56 SWF	: PCI: Comments: mber: 701 mments: ATHERING ELLING ATHERING T CR VELING mber: 704	68 Тур Тур	e: R M L L L L e: R	Ar 2375.00 S 10.00 S 2375.00 S 201.00 F 250.00 S Ar 30.00 S	iqFt iqFt iqFt iqFt ea:	5000.00 SqFt						
Conditions: Inspection (Sample Nur Sample Con 57 WE/ 56 SWF 57 WE/ 48 L & 52 RAV Sample Nur Sample Con 56 SWF 57 WE/	ELLING	68 Тур Тур	e: R M L L L L e: R L	Ar 2375.00 S 10.00 S 2375.00 S 201.00 F 250.00 S Ar	iqFt iqFt it iqFt iqFt iqFt iqFt	5000.00 SqFt						
Conditions: Inspection (Sample Nur Sample Cor 57 WE/ 56 SWE 57 WE/ 48 L & 52 RAV Sample Nur Sample Cor 56 SWE 57 WE/ 48 L &	E PCI: Comments: mber: 701 mments: ATHERING ATHERING T CR VELING mber: 704 mments: ELLING ATHERING	68 Тур Тур	e: R M L L L L e: R L M	Ar 2375.00 S 10.00 S 2375.00 S 201.00 F 250.00 S Ar 30.00 S 6571.00 S	iqFt iqFt it iqFt iqFt iqFt iqFt it	5000.00 SqFt						

Network: TIX			Name:	SPACE COAS	ST REGIONAL AIRPOI	RT
Branch: TW C	N	ame: TAXI	WAY C	Use	e: TAXIWAY	Area: 196,395 SqFt
Section: 310	of 3	From:	-		То: -	Last Const.: 1/1/1986
Surface: AAC	Family: C9N5 APC	9-PR-TW-AAC-	Zone:		Category:	Rank: P
Area: 116	,660 SqFt	Length:	2,300 Ft	Width:	50 Ft	
Slabs:	Slab Length:	Ft	Slab W	idth:	Ft	Joint Length: Ft
Shoulder:	Street Type:		Grade:	0		Lanes: 0
Section Comments:						
Work Date: 1/1/1943	Work Typ	pe: BUILT			Code: IMPORTED	Is Major M&R: True
Work Date: 1/1/1986	Work Typ	pe: OVERLAY			Code: IMPORTED	Is Major M&R: True
Last Insp. Date: 3/4/20	19	TotalSamples:	24	Surv	eyed: 4	
Conditions: PCI: 6	3					
nspection Comments:						
Sample Number: 701	Туре:	R A	Area:	5263.00 SqFt	PCI: 63	
Sample Comments:						
2 RAVELING	L	1013.00	SqFt			
2 RAVELING	М	200.00	SqFt			
18 L & T CR	М	200.00				
18 L & T CR	L	255.00				
Sample Number: 707	Туре:	R A	Area:	4672.00 SqFt	PCI: 62	
Sample Comments:						
18 L & T CR	М	150.00	Ft			
18 L & T CR	L	278.00	Ft			
2 RAVELING	L	4672.00	SqFt			
Sample Number: 714	Type:	R A	Area:	5000.00 SqFt	PCI: 66	
Sample Comments:						
48 L&TCR	М	100.00	Ft			
18 L & T CR	L	317.00				
2 RAVELING	L	1250.00				
7 WEATHERING	М	3750.00	SqFt			
Sample Number: 719	Туре:	R A	Area:	5000.00 SqFt	PCI: 62	
Sample Comments:						
48 L & T CR	М	100.00	Ft			
2 RAVELING	L	2500.00				
7 WEATHERING	М	2500.00				
18 L & T CR	L	436.00	Ft			

Network:	TIX						Nan	ne: S	PACE COAS	ST REG	IONAL AIF	PORT					
Branch:	TW C			N	lame:	TAXI	WAY C		Use	е: Тл	AXIWAY	A	rea:	1	96,395 Sq	Ft	
Section:	315		of	3	Fr	om:	-				То: -				Last Co	onst.:	1/1/2013
Surface:	AAC	F	amily:	C9N5 APC	59-PR-TW-	AAC-	Zon	e:			Category:				Rank:	Р	
Area:		32,856	SqFt		Length:		600 F	ťt	Width:		50 F	;					
Slabs:		5	Slab Len	gth:		Ft		Slab Width	ı:		Ft		Joint I	ength:		Ft	
Shoulder:		5	Street Ty	pe:				Grade:	0				Lanes:	0			
Section Co	mments:																
Work Date	e: 1/1/1943		Wo	ork Ty	pe: BUILT					Code:	IMPORTI	D	Is	Major 1	M&R: Tru	ue	
Work Date	e: 1/1/1976		Wo	ork Ty	pe: OVER	LAY				Code:	IMPORT	D	Is	Major 1	M&R: Tru	ue	
Work Date	e: 1/1/2013		Wo	ork Ty	pe: MILL :	and OVEI	RLAY			Code:	ML-OV		Is	Major 1	M&R: Tru	ue	
Conditions	Date: 3/4/ s: PCI: Comments	88			TotalSan	nples:	7		Surv	eyed:	2						
	mber: 72	3	Тур	e:	R	A	rea:	50	000.00 SqFt		PCI:	90					
Sample Co	omments:																
	ATHERING	Ĵ		L		5000.00	-										
	t CR			L		23.00	Ft										
Sample Nu	mber: 72	6	Тур	e:	R	Α	rea:	50	007.00 SqFt		PCI:	86					
Sample Co	omments:																
56 SW	ELLING			L		10.00	SqFt										
	ATHERING	3		L		5007.00											
48 L&	T CR			L		96.00	Ft										

Network:	TIX				Name	e: SPA	CE COAST	REGIONAL AIR	PORT		
Branch:	TW D		Name:	TAXIW	AY D		Use:	TAXIWAY	Area:	107,711 SqFt	
Section: 4	404	0	f 3 I	From: -				To: -		Last Cons	t.: 1/1/2000
Surface:	AAC	Family:	C9N59-PR-TW APC	-AAC-	Zone	:		Category:		Rank: T	
Area:		26,461 SqFt	Length:		400 Ft		Width:	50 Ft			
Slabs:		Slab Len	igth:	Ft		Slab Width:		Ft	Joint	Length:	Ft
Shoulder:		Street Ty	ype:			Grade: 0			Lanes	s: 0	
Section Cor	nments:										
Work Date:	: 1/1/1943	W	ork Type: BUII	LT			С	ode: IMPORTE	D Is	Major M&R: True	
Work Date:	: 1/1/2000	W	ork Type: MILI	and OVER	LAY		С	ode: ML-OV	Is	Major M&R: True	
Last Insp. I	Date: 3/4/	2019	TotalS	amples: 5			Surveye	ed: 1			
Conditions:	PCI:	65									
Inspection (Comments	:									
Sample Nur	mber: 40	2 Ty	pe: R	Ar	rea:	5000	0.00 SqFt	PCI:	65		
Sample Cor	mments:										
57 WEA	ATHERING	3	М	4750.00 \$	SqFt						
52 RAV	/ELING		L	250.00 \$	SqFt						
48 L &	T CR		М	50.00 H	Ft						
48 L&	T CR		L	160.00 H	Ft						

Network: TIX			Name	. SFACE COAST	REGIONAL AIRP	ORT		
Branch: TW D		Name:	TAXIWAY D	Use:	TAXIWAY	Area:	107,711 SqFt	
Section: 408	of 3	3	From: -		То: -		Last Const.	1/1/2000
Surface: AAC	•	9N59-PR-TV PC	W-AAC- Zone:		Category:		Rank: P	
Area:	7,500 SqFt	Length:	150 Ft	Width:	50 Ft			
Slabs:	Slab Length	:	Ft S	Slab Width:	Ft	Joint I	Length: 1	Ft
Shoulder:	Street Type	:	(Grade: 0		Lanes:	: 0	
Section Comments:								
Work Date: 1/1/1943	Work	Type: New	Construction - Initia	1 (Code: NU-IN	Is	Major M&R: True	
Work Date: 1/1/2000	Work	Type: MIL	L and OVERLAY	(Code: ML-OV	Is	Major M&R: True	
Last Insp. Date: 3/4/2	019	TotalS	Samples: 2	Survey	ed: 2			
Last Insp. Date: 3/4/2 Conditions: PCI:		TotalS	Samples: 2	Survey	ed: 2			
Conditions: PCI:		TotalS	Samples: 2	Survey	ed: 2			
Conditions: PCI: Inspection Comments:	65		-			65		
Conditions: PCI: Inspection Comments: Sample Number: 404	65	TotalS R	Samples: 2 Area:	Survey 3750.00 SqFt	ed: 2 PCI: 0	65		
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments:	65		-			65		
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L&TCR	65	R	Area: 75.00 Ft 3562.00 SqFt			65		
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L&TCR 57 WEATHERING	65	R	Area: 75.00 Ft			65		
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING	65	R M M	Area: 75.00 Ft 3562.00 SqFt			65		
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING 48 L & T CR	65	R M L	Area: 75.00 Ft 3562.00 SqFt 188.00 SqFt					
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING 48 L & T CR Sample Number: 405	65 Туре:	R M L L	Area: 75.00 Ft 3562.00 SqFt 188.00 SqFt 75.00 Ft	3750.00 SqFt	PCI: (
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING	65 Туре:	R M L L	Area: 75.00 Ft 3562.00 SqFt 188.00 SqFt 75.00 Ft	3750.00 SqFt	PCI: (
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING 48 L & T CR Sample Number: 405 Sample Comments:	65 Туре:	R M L L R	Area: 75.00 Ft 3562.00 SqFt 188.00 SqFt 75.00 Ft Area: 75.00 Ft	3750.00 SqFt	PCI: (
Conditions: PCI: Inspection Comments: Sample Number: 404 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING 48 L & T CR Sample Number: 405 Sample Comments: 48 L & T CR	65 Туре:	R M L L R L	Area: 75.00 Ft 3562.00 SqFt 188.00 SqFt 75.00 Ft Area:	3750.00 SqFt	PCI: (

Network: TE	Х			Nan	IIC. 5111	CE COAST	REGIONAL AIRPO				
Branch: TV	W D		Name:	TAXIWAY D)	Use:	TAXIWAY	Area:	107	7,711 SqFt	
Section: 410		of 3	3	From: -			То: -			Last Const.:	1/1/2000
Surface: AAC]		9N59-PR-T PC	W-AAC- Zon	ie:		Category:			Rank: P	
Area:	73,750	SqFt	Length	: 1,450 H	Ft	Width:	50 Ft				
Slabs:		Slab Length	ı:	Ft	Slab Width:		Ft	Joint	Length:	F	ťt
Shoulder:		Street Type	:		Grade: 0			Lanes	s: 0		
Section Commen	its:										
Work Date: 1/1/	/1985	Work	Type: BU	ILT		С	ode: IMPORTED	Is	s Major Ma	&R: True	
Work Date: 1/1/	/2000	Work	Type: MI	LL and OVERLAY		C	ode: ML-OV	Is	Major Ma	&R: True	
Last Insp. Date:	3/4/2019		Total	Samples: 15		Surveve	d: 3				
Last Insp. Date: Conditions: P			Total	Samples: 15		Surveye	d: 3				
Conditions: P	CI: 75		Total	Samples: 15		Surveye	d: 3				
Conditions: P Inspection Comn	CI: 75 nents:	Туре:			3750			0			
Conditions: P	CI: 75 nents: : 407	Туре:	Total R	Samples: 15 Area:	3750	Surveye	d: 3 PCI: 7	0			
Conditions: P Inspection Comm Sample Number: Sample Commen	CI: 75 nents: : 407 nts:	Туре:	R	- Area:	3750			0			
Conditions: P Inspection Comn Sample Number:	CI: 75 nents: : 407 nts:	Туре:			3750			0			
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L&TCR	CI: 75 nents: : 407 nts: ERING	Туре:	R	Area:	3750			0			
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L & T CR 57 WEATHE 52 RAVELIN	CI: 75 nents: : 407 nts: ERING	Туре: Туре:	R L M	Area: 156.00 Ft 3562.00 SqFt							
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L&TCR 57 WEATHE	CI: 75 nents: : 407 nts: ERING NG : 412		R L M L	Area: 156.00 Ft 3562.00 SqFt 188.00 SqFt		0.00 SqFt	PCI: 7				
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L & T CR 57 WEATHE 52 RAVELIN Sample Number:	CI: 75 ments: : 407 mts: ERING NG : 412 mts:		R L M L	Area: 156.00 Ft 3562.00 SqFt 188.00 SqFt		0.00 SqFt	PCI: 7				
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L & T CR 57 WEATHE 52 RAVELIN Sample Number: Sample Commen	CI: 75 ments: : 407 mts: ERING NG : 412 mts:		R L M L R	Area: 156.00 Ft 3562.00 SqFt 188.00 SqFt Area:		0.00 SqFt	PCI: 7				
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L & T CR 57 WEATHE 52 RAVELIN Sample Number: Sample Commen 48 L & T CR	CI: 75 nents: : 407 nts: ERING NG : 412 nts: ERING		R M L R L	Area: 156.00 Ft 3562.00 SqFt 188.00 SqFt Area: 239.00 Ft	5000	0.00 SqFt	PCI: 7	5			
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L & T CR 57 WEATHE 52 RAVELIN Sample Number: Sample Commen 48 L & T CR 57 WEATHE	CI: 75 ments: : 407 mts: ERING NG : 412 mts: ERING : 415	Туре:	R M L R L M	Area: 156.00 Ft 3562.00 SqFt 188.00 SqFt Area: 239.00 Ft 5000.00 SqFt	5000	0.00 SqFt	PCI: 7 PCI: 7	5			
Conditions: P Inspection Comm Sample Number: Sample Commen 48 L & T CR 57 WEATHE 52 RAVELIN Sample Number: Sample Commen 48 L & T CR 57 WEATHE Sample Number:	CI: 75 nents: : 407 nts: ERING NG : 412 nts: ERING : 415 nts:	Туре:	R M L R L M	Area: 156.00 Ft 3562.00 SqFt 188.00 SqFt Area: 239.00 Ft 5000.00 SqFt	5000	0.00 SqFt	PCI: 7 PCI: 7	5			

Network: TIX			Ν	ame: SPA	ACE COAST I	REGIONAL AIRPC	DRT		
Branch: TW E		Name:	TAXIWAY	Έ	Use:	TAXIWAY	Area:	154,058 SqFt	
Section: 505	of 3	3	From: -			То: -		Last Const.:	1/1/1998
Surface: AAC		9N59-PR-TV PC	W-AAC- Z	one:		Category:		Rank: P	
Area: 3	32,371 SqFt	Length:	600) Ft	Width:	50 Ft			
Slabs:	Slab Length	:	Ft	Slab Width:		Ft	Joint Lengt	h: Ft	
Shoulder:	Street Type	:		Grade: 0			Lanes:	0	
Section Comments:									
Work Date: 1/1/1943	Work	Type: BUI	LT		Co	ode: IMPORTED	Is Majo	or M&R: True	
Work Date: 1/1/1998	Work	Type: MIL	L and OVERLA	Y	Co	ode: ML-OV	Is Majo	or M&R: True	
Last Insp. Date: 3/4/2	2019	TotalS	Samples: 6		Surveye	d: 2			
Last Insp. Date: 3/4/2 Conditions: PCI:		TotalS	Samples: 6		Surveye	d: 2			
•	72	TotalS	Samples: 6		Surveye	d: 2			
Conditions: PCI:	72	TotalS R	Samples: 6 Area:	500	Surveyee	d: 2 PCI: 69	9		
Conditions: PCI: Inspection Comments:	72		-	500			9		
Conditions: PCI: Inspection Comments: Sample Number: 601 Sample Comments:	72 Туре:		- Area:				9		
Conditions: PCI: Inspection Comments: Sample Number: 601 Sample Comments: 57 WEATHERING	72 Туре:	R	-				9		
Conditions: PCI: Inspection Comments: Sample Number: 601 Sample Comments: 57 WEATHERING	72 Туре:	R	Area:	't			9		
Conditions: PCI: Inspection Comments: Sample Number: 601 Sample Comments: 57 WEATHERING 48 L&TCR	72 Туре:	R M L	Area: 1250.00 SqF 202.00 Ft	't			9		
Conditions: PCI: Inspection Comments: Sample Number: 601 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING	72 Туре:	R M L L	Area: 1250.00 SqF 202.00 Ft 3750.00 SqF	t t					
Conditions: PCI: Inspection Comments: Sample Number: 601 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING 48 L & T CR	72 Туре:	R M L L M	Area: 1250.00 SqF 202.00 Ft 3750.00 SqF 100.00 Ft	t t	0.00 SqFt	PCI: 6			
Conditions: PCI: Inspection Comments: Sample Number: 601 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING 48 L & T CR Sample Number: 603	72 Type: Type:	R M L L M	Area: 1250.00 SqF 202.00 Ft 3750.00 SqF 100.00 Ft	't 't 500	0.00 SqFt	PCI: 6			

Netwo	ork: TIX			Nan	ne: SPACE C	OAST I	REGIONAL AIRPO	ORT		
Branc	eh: TW E	I	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	154,058 SqFt	
Sectio	on: 515	of 3]	From: -			To: -		Last Const.:	1/1/2003
Surfa	ce: AAC	Family: C9N	59-PR-TV	W-AAC- Zon	e:		Category:		Rank: P	
		APC								
Area:	113,522	2 SqFt	Length:	2,640 F	ft Wid	th:	50 Ft			
Slabs:	:	Slab Length:		Ft	Slab Width:		Ft	Joir	nt Length: F	t
Shoul	der:	Street Type:			Grade: 0			Lar	nes: 0	
Sectio	on Comments:									
Work	Date: 1/1/1943	Work Ty	pe: BUI	LT		Co	ode: IMPORTED		Is Major M&R: True	
Work	Date: 1/1/2003	Work Ty	pe: MIL	L and OVERLAY		Co	ode: ML-OV		Is Major M&R: True	
Last I	nsp. Date: 3/4/2019		TotalS	amples: 27	S	urveyed	d: 5			
	itions: PCI: 70					-				
Inspec	ction Comments:									
	le Number: 599	Туре:	R	Area:	5825.00 S	aFt	PCI: 63	8		
-	le Comments:	rype:	к	Area:	5625.00 8	qr ι		J		
Samp	le Comments:									
52	RAVELING	L		115.00 SqFt						
57	WEATHERING	M		1330.00 SqFt						
56 48	SWELLING	L		5.00 SqFt 30.00 Ft						
48 50	L & T CR PATCHING	L		97.00 Ft						
50 57	WEATHERING	L		4283.00 SqFt						
45	DEPRESSION	L		30.00 SqFt						
	le Number: 604	Туре:	R	Area:	5328.00 S	aFt	PCI: 7.	3		
-	le Comments:	- , por			0020100 2	4		-		
52	RAVELING	L		107.00 SqFt						
48	L & T CR	L		6.00 Ft						
57	WEATHERING	N	[5221.00 SqFt						
Samp	le Number: 614	Type:	R	Area:	3500.00 S	qFt	PCI: 69	9		
Samp	le Comments:									
52	RAVELING	N	[3.00 SqFt						
52	RAVELING	L		59.00 SqFt						
48	L & T CR	L		84.00 Ft						
50	PATCHING	L		560.00 SqFt						
Samp	le Number: 620	Туре:	R	Area:	3500.00 S	qFt	PCI: 7	1		
Samp	le Comments:									
57	WEATHERING	N	1	3430.00 SqFt						
52	RAVELING	L		70.00 SqFt						
48	L & T CR	L		28.00 Ft						
Samp	le Number: 628	Type:	R	Area:	3500.00 S	qFt	PCI: 7	1		
Samp	le Comments:									
48	L & T CR	L		55.00 Ft						
52	RAVELING	L		70.00 SqFt						
57	WEATHERING	N	[3430.00 SqFt						

Network:	TIX			Name	e: SPACE COAST	REGIONAL AIRPO	DRT	
Branch:	TW E		Name:	TAXIWAY E	Use:	TAXIWAY	Area:	154,058 SqFt
Section:	525	0	f 3	From: -		То: -		Last Const.: 1/1/2014
Surface:	AC	Family:	C9N59-PR-T	W-AC Zone:	:	Category:		Rank: P
Area:		8,165 SqFt	Length:	100 Ft	Width:	85 Ft		
Slabs:		Slab Ler	ıgth:	Ft	Slab Width:	Ft	Joint Lengt	h: Ft
Shoulder:		Street T	ype:	(Grade: 0		Lanes:	0
Section Co	mments:							
Work Date	e: 1/1/2014	W	ork Type: Nev	v Construction - Initia	1	Code: NU-IN	Is Majo	or M&R: True
Last Insp.]	Date: 3/4/2	2019	Total	Samples: 2	Survey	ed: 1		
Conditions								
Inspection	Comments:							
Sample Nu	mber: 608	3 Tyj	pe: R	Area:	3666.00 SqFt	PCI: 9	4	
Sample Co	mments:							
57 WE.	ATHERING	ŕ	L	3666.00 SqFt				

Networ	k: TIX				Nan	ne: SPA	CE COAS	T REG	IONAL AIRP	ORT			
Branch	TW F		Name	TAXI	WAY F		Use	: TA	AXIWAY	Area	:	30,388 SqFt	
Section	605	0	f 1	From:	-				То: -			Last Const.:	1/1/1998
Surface	: AAC	Family:	C9N59-PR APC	-TW-AAC-	Zon	e:			Category:			Rank: T	
Area:		30,388 SqFt	Leng	th:	580 F	ŕt	Width:		50 Ft				
Slabs:		Slab Len	igth:	Ft		Slab Width:			Ft		Joint Length:	F	t
Shoulde	er:	Street Ty	ype:			Grade: 0					Lanes: 0		
Section	Comments:												
Work E	ate: 1/1/1943	W	ork Type: B	UILT				Code:	IMPORTEI)	Is Major	M&R: True	
Work E	ate: 1/1/1998	W	ork Type: N	IILL and OVE	RLAY			Code:	ML-OV		Is Major	M&R: True	
Conditi	sp. Date: 3/4/ ons: PCI: ion Comments	14	Tot	alSamples:	6			yed: 2					
Sample	Number: 30	1 Ty	e: R	A	Area:	5000	0.00 SqFt		PCI:	11			
Sample	Comments:												
52 1 52 1 43 1 50 1	PATCHING RAVELING RAVELING BLOCK CR PATCHING ALLIGATOR (ν D	M M H L M	4986.00 4.00 4899.00 9.00	SqFt SqFt SqFt								
	Number: 304				SqFt Area:	693().00 SqFt		PCI:	16			
-	Comments:	. 191		ľ	11 04 1	0750			101				
43 1 50 1 41 2 41 2 50 1	RAVELING BLOCK CR PATCHING ALLIGATOR (ALLIGATOR (PATCHING RAVELING		M M H M M H	84.00 9.00	SqFt SqFt SqFt								