

FLORIDA DEPARTMENT OF TRANSPORTATION
AVIATION AND SPACEPORTS OFFICE

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report November 2019



**Orlando Executive
Airport (ORL)**
Reliever Airport
District 5





Florida Department of Transportation

Statewide Airfield Pavement Management Program

Prepared by:

*FDOT Aviation and Spaceports Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*




OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS

Table of Contents


Executive Summary.....	10
Program Background.....	10
Summary of Results.....	11
Pavement Condition Index (Latest Inspection).....	11
Forecasted Pavement Condition Index 2020-2029	14
Major Rehabilitation Planning 2020-2029	16
Summary of Orlando Executive Airport.....	18
Chapter 1 – Introduction.....	20
1.1 Background	20
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019	20
1.3 Organization.....	22
1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager.....	22
1.3.2 Participating Florida Public-Use and Publicly Owned Airports	22
1.3.3 Florida Department of Transportation District Offices	22
1.3.4 Consultant.....	22
1.4 Purpose of Airport Pavement Evaluation Report	24
1.5 History of the Program.....	24
1.6 Federal Aviation Administration (FAA)	26
1.7 FDOT SAPMP Objectives and Components	26
1.7.1 Program Objectives.....	26
1.7.2 Program Components	26
1.8 References	30
Chapter 2 – Methodology	32
2.1 Airfield Pavement Database.....	32
2.2 Airfield Pavement System Inventory	32
2.2.1 Pavement Management Program Network Definition Terminology	33
2.3 Airfield Pavement Structure.....	35
2.3.1 Pavement Structure Types	35
2.4 Airfield Pavement Work History	37
2.4.1 Airfield Pavement Record Keeping	37
2.5 Airfield Pavement Traffic.....	37
2.6 Airfield Pavement Condition Index (PCI) Survey.....	37
2.6.1 PCI Survey Methodology.....	37
2.6.2 Pavement Distress Types.....	39

2.6.3 PCI Survey Inspection Procedures	43
2.6.4 Updates to the ASTM D5340-12.....	44
Chapter 3 – Airfield Pavement System Inventory	47
3.1 Airfield Pavement Network Information	47
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	47
3.1.2 Estimated Pavement Age	49
3.1.3 Functional Use Classification.....	51
3.1.4 Pavement Surface Type	52
3.1.5 Pavement System Inventory Details	53
Chapter 4 – Airfield Pavement Condition	60
4.1 Airfield Pavement Condition Index (Latest Inspection)	60
4.1.1 Network-Level Analysis	60
4.1.2 Branch-Level Analysis.....	60
4.1.3 Section-Level Analysis	62
4.2 Summary of Pavement Condition Evaluation Results	67
4.2.1 Network-Level Observations.....	67
4.2.2 Branch-Level Observations	67
4.3 Forecasted Pavement Conditions	69
4.3.1 Performance Models and Prediction Curves	69
4.3.2 Branch-Level Pavement Condition Forecast	69
4.3.3 Section-Level Pavement Condition Forecast	71
4.3.4 Forecasted PCI Considerations	75
Chapter 5 – Localized Maintenance and Repair Planning.....	77
5.1 Localized Maintenance and Repair	77
5.2 Localized Maintenance and Repair Policy	78
5.3 Localized Maintenance and Repair Analysis and Recommendations	82
Chapter 6 – Major Rehabilitation Planning.....	87
6.1 Major Rehabilitation	87
6.1.1 Critical PCI.....	89
6.1.2 FDOT Recommended Minimum Service-Level PCI	89
6.2 Major Rehabilitation Policy	90
6.2.1 Major Rehabilitation Pavement Section Development	90
6.2.2 Major Rehabilitation Planning-Level Unit Costs.....	92
6.3 Major Rehabilitation Needs.....	92
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs	92
Chapter 7 – Conclusion	97
7.1 Recommendations.....	97
7.1.1 Continued PCI Survey Inspections	97
7.1.2 Localized Maintenance and Repair.....	97

7.1.3 Major Rehabilitation.....	97
7.1.4 Pavement Management System.....	97
7.2 Supporting Documents	98
001 – Airfield Pavement Network Definition Exhibit	98
002 – Airfield Pavement System Inventory Exhibit.....	98
003 – Airfield Pavement Condition Index Exhibit.....	98
004 – Airfield Pavement Major Rehabilitation Exhibit.....	98
Inspection Photograph Documentation.....	98
7.3 Conclusion	99



Appendix A	Airfield Pavement Analysis Tables
Appendix B	Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
Appendix C	Technical Exhibits
Appendix D	Inspection Photograph Documentation
Appendix E	Inspection Distress Details



List of Figures

<i>Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029.....</i>	<i>18</i>
<i>Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts.....</i>	<i>21</i>
<i>Figure 1.7.2 (a) Typical Pavement Condition Life Cycle.....</i>	<i>27</i>
<i>Figure 1.7.2 (b) General Pavement Treatments by Condition Range</i>	<i>28</i>
<i>Figures 1.7.2 (c) Flexible Asphalt Concrete</i>	<i>29</i>
<i>Figures 1.7.2 (d) Rigid Portland Cement Concrete</i>	<i>29</i>
<i>Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit</i>	<i>48</i>
<i>Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit.....</i>	<i>49</i>
<i>Figure 3.1.2 Average Age of Pavements at Inspection.....</i>	<i>50</i>
<i>Figure 3.1.3 Airfield Pavement Functional Classification Use by Area</i>	<i>51</i>
<i>Figure 3.1.4 (a) Pavement Surface Type by Area (SF)</i>	<i>52</i>
<i>Figure 3.1.4 (b) Pavement Surface Type by Area (%)</i>	<i>53</i>
<i>Figure 4.1.1 Latest Condition – Overall Network</i>	<i>60</i>
<i>Figure 4.1.2 (a) Latest Condition – Runway Pavements.....</i>	<i>61</i>
<i>Figure 4.1.2 (b) Latest Condition – Taxiway Pavements</i>	<i>61</i>
<i>Figure 4.1.2 (c) Latest Condition – Apron Pavements.....</i>	<i>62</i>
<i>Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit.....</i>	<i>66</i>
<i>Figure 4.2.2 Pavement Condition Summary by Facility Use</i>	<i>68</i>
<i>Figure 4.3.2 (a) Forecasted Runway Pavement Performance</i>	<i>69</i>
<i>Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance.....</i>	<i>70</i>
<i>Figure 4.3.2 (c) Forecasted Apron Pavement Performance</i>	<i>70</i>
<i>Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, $PCI \leq$ Critical PCI.....</i>	<i>87</i>
<i>Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, $PCI >$ Critical PCI</i>	<i>88</i>
<i>Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year</i>	<i>95</i>
<i>Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit.....</i>	<i>95</i>

List of Tables

<i>Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level.....</i>	<i>11</i>
<i>Table E-2 Pavement Condition Index Forecast 2020-2029</i>	<i>14</i>
<i>Table E-3 Major Rehabilitation Planning 2020-2029</i>	<i>16</i>
<i>Table 2.2.1 Airfield Pavement Database Network Definition Terminology.....</i>	<i>34</i>
<i>Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>39</i>
<i>Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>40</i>
<i>Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>40</i>
<i>Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>41</i>
<i>Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>42</i>
<i>Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>42</i>
<i>Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete</i>	<i>43</i>
<i>Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete</i>	<i>43</i>
<i>Table 2.6.4 Summary of Updates to ASTM D5340-12</i>	<i>45</i>
<i>Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction</i>	<i>47</i>
<i>Table 3.1.5 Pavement System Inventory Details</i>	<i>54</i>
<i>Table 4.1.3 Latest Pavement Condition Index Summary</i>	<i>63</i>
<i>Table 4.3.3 Forecasted PCI 2020-2029.....</i>	<i>72</i>
<i>Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete</i>	<i>78</i>
<i>Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete</i>	<i>79</i>
<i>Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete</i>	<i>81</i>

<i>Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete</i>	<i>81</i>
<i>Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level</i>	<i>82</i>
<i>Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level</i>	<i>83</i>
<i>Table 5.3 (c) Summary of Localized Maintenance</i>	<i>85</i>
<i>Table 6.1.2 FDOT Recommended Minimum Service-Level PCI.....</i>	<i>89</i>
<i>Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete</i>	<i>90</i>
<i>Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete</i>	<i>91</i>
<i>Table 6.2.2 Reliever (RL) Major Rehabilitation Planning-Level Unit Cost by Pavement Type</i>	<i>92</i>
<i>Table 6.3.1 10-Year Major Rehabilitation Needs</i>	<i>93</i>



Executive Summary



Executive Summary

Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP)”** using the documented procedures set forth by ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.



Summary of Results

Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
ORL	RUNWAY 7-25	RUNWAY	6105	600,500	63	Fair
ORL	RUNWAY 7-25	RUNWAY	6110	300,250	64	Fair
ORL	RUNWAY 13-31	RUNWAY	6205	445,836	66	Fair
ORL	TAXIWAY A	TAXIWAY	104	11,949	66	Fair
ORL	TAXIWAY A	TAXIWAY	114	12,579	78	Satisfactory
ORL	TAXIWAY A	TAXIWAY	115	31,644	56	Fair
ORL	TAXIWAY A	TAXIWAY	116	11,579	63	Fair
ORL	TAXIWAY A	TAXIWAY	117	22,912	62	Fair
ORL	TAXIWAY A	TAXIWAY	118	12,843	94	Good
ORL	TAXIWAY A	TAXIWAY	119	8,568	89	Good
ORL	TAXIWAY A	TAXIWAY	125	257,040	67	Fair
ORL	TAXIWAY A	TAXIWAY	150	60,358	57	Fair
ORL	TAXIWAY A1	TAXIWAY	111	15,537	77	Satisfactory
ORL	TAXIWAY A1	TAXIWAY	112	14,428	57	Fair
ORL	TAXIWAY A2	TAXIWAY	120	30,935	65	Fair
ORL	TAXIWAY A3	TAXIWAY	130	56,163	67	Fair
ORL	TAXIWAY A4	TAXIWAY	140	15,668	63	Fair
ORL	TAXIWAY A5	TAXIWAY	405	37,049	65	Fair
ORL	TAXIWAY A5	TAXIWAY	425	9,443	71	Satisfactory
ORL	TAXIWAY A6	TAXIWAY	113	26,953	72	Satisfactory
ORL	TAXIWAY B	TAXIWAY	102	6,388	48	Poor
ORL	TAXIWAY B	TAXIWAY	103	57,000	55	Poor
ORL	TAXIWAY B	TAXIWAY	105	30,470	87	Good
ORL	TAXIWAY E	TAXIWAY	505	78,110	65	Fair
ORL	TAXIWAY E	TAXIWAY	530	46,191	93	Good
ORL	TAXIWAY E	TAXIWAY	540	21,326	94	Good
ORL	TAXIWAY E	TAXIWAY	545	9,618	88	Good
ORL	TAXIWAY E	TAXIWAY	550	52,982	91	Good
ORL	TAXIWAY E1	TAXIWAY	501	5,073	50	Poor
ORL	TAXIWAY E2	TAXIWAY	510	9,644	46	Poor
ORL	TAXIWAY E2	TAXIWAY	512	2,687	61	Fair
ORL	TAXIWAY E3	TAXIWAY	417	8,311	29	Very Poor
ORL	TAXIWAY E3	TAXIWAY	420	36,384	50	Poor
ORL	TAXIWAY E3	TAXIWAY	520	9,009	46	Poor



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
ORL	TAXIWAY E3	TAXIWAY	522	2,133	48	Poor
ORL	TAXIWAY E4	TAXIWAY	1070	130,837	50	Poor
ORL	TAXIWAY E4	TAXIWAY	1080	8,393	56	Fair
ORL	TAXIWAY E4	TAXIWAY	1105	6,580	70	Fair
ORL	TAXIWAY E4	TAXIWAY	1110	20,682	94	Good
ORL	TAXIWAY E5	TAXIWAY	560	5,540	65	Fair
ORL	TAXIWAY E5	TAXIWAY	565	9,465	94	Good
ORL	TAXIWAY E6	TAXIWAY	805	17,742	67	Fair
ORL	TAXIWAY E6	TAXIWAY	820	11,139	94	Good
ORL	TAXIWAY F	TAXIWAY	605	54,815	45	Poor
ORL	TAXIWAY G	TAXIWAY	705	30,099	54	Poor
ORL	TAXIWAY G	TAXIWAY	710	9,812	55	Poor
ORL	TAXIWAY H	TAXIWAY	806	62,452	52	Poor
ORL	TAXIWAY K	TAXIWAY	610	27,266	70	Fair
ORL	NORTH APRON	APRON	4105	200,966	6	Failed
ORL	NORTH APRON	APRON	4125	140,429	5	Failed
ORL	NORTH APRON	APRON	4140	237,860	25	Serious
ORL	NORTH APRON	APRON	4145	122,500	34	Very Poor
ORL	NORTH APRON	APRON	4155	337,449	49	Poor
ORL	NORTH APRON	APRON	4158	125,584	6	Failed
ORL	NORTH APRON	APRON	4165	27,156	7	Failed
ORL	NORTH APRON	APRON	4166	22,635	89	Good
ORL	NORTH APRON	APRON	4167	28,916	12	Serious
ORL	NORTH APRON	APRON	4168	24,538	0	Failed
ORL	NORTH APRON	APRON	4169	72,939	86	Good
ORL	NORTH APRON	APRON	4170	84,878	67	Fair
ORL	NORTH APRON	APRON	4175	42,594	76	Satisfactory
ORL	GA APRON	APRON	4205	608,614	49	Poor
ORL	GA APRON	APRON	4230	23,614	61	Fair
ORL	NE APRON	APRON	4305	52,643	23	Serious
ORL	NE APRON	APRON	4312	8,541	59	Fair
ORL	NE APRON	APRON	4315	24,518	77	Satisfactory
ORL	NE APRON	APRON	4320	53,040	77	Satisfactory
ORL	WEST APRON	APRON	4605	34,600	64	Fair
ORL	WEST APRON	APRON	4610	260,825	45	Poor
ORL	WEST APRON	APRON	4640	157,964	100	Good
ORL	WEST APRON	APRON	4645	24,864	100	Good
ORL	WEST APRON	APRON	4650	115,747	50	Poor
ORL	WEST APRON	APRON	4665	8,833	100	Good



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
ORL	WEST APRON	APRON	4670	10,856	58	Fair
ORL	WEST APRON	APRON	4675	1,760	100	Good
ORL	SE SEGMENT OF WEST APRON	APRON	4805	129,830	67	Fair
ORL	SE SEGMENT OF WEST APRON	APRON	4810	79,530	77	Satisfactory
ORL	RUN-UP APRONS	APRON	5110	25,880	75	Satisfactory
ORL	RUN-UP APRONS	APRON	5115	36,282	74	Satisfactory
ORL	RUN-UP APRONS	APRON	5120	41,840	75	Satisfactory



Forecasted Pavement Condition Index 2020-2029

Table E-2 Pavement Condition Index Forecast 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	AP GA	4205	49	48	47	46	45	44	43	41	40	39	38
ORL	AP GA	4230	61	60	59	58	57	56	56	55	54	54	53
ORL	AP N	4105	6	5	5	5	4	4	3	3	3	2	2
ORL	AP N	4125	5	4	4	4	3	3	2	2	2	1	1
ORL	AP N	4140	25	24	24	24	23	23	22	22	22	21	21
ORL	AP N	4145	34	33	32	31	30	30	29	29	29	28	28
ORL	AP N	4155	49	48	47	46	45	44	43	41	40	39	38
ORL	AP N	4158	6	4	2	0	0	0	0	0	0	0	0
ORL	AP N	4165	7	6	6	6	5	5	4	4	4	3	3
ORL	AP N	4166	89	87	84	82	80	78	76	74	72	71	69
ORL	AP N	4167	12	11	11	11	10	10	9	9	9	8	8
ORL	AP N	4168	0	0	0	0	0	0	0	0	0	0	0
ORL	AP N	4169	86	84	82	79	77	75	74	72	70	69	67
ORL	AP N	4170	67	65	64	63	62	61	60	59	58	57	57
ORL	AP N	4175	76	74	72	71	69	67	66	65	64	62	61
ORL	AP NE	4305	23	22	22	22	21	21	20	20	20	19	19
ORL	AP NE	4312	59	58	57	56	56	55	54	53	53	52	51
ORL	AP NE	4315	77	75	73	70	68	66	64	62	60	57	55
ORL	AP NE	4320	77	75	73	70	68	66	64	62	60	57	55
ORL	AP RU	5110	75	73	71	70	68	67	65	64	63	62	61
ORL	AP RU	5115	74	72	70	69	67	66	65	63	62	61	60
ORL	AP RU	5120	75	73	71	70	68	67	65	64	63	62	61
ORL	AP W	4605	64	63	62	61	60	59	58	57	56	56	55
ORL	AP W	4610	45	44	42	41	40	39	38	37	35	34	33
ORL	AP W	4640	100	98	96	93	91	89	87	85	82	80	78
ORL	AP W	4645	100	95	93	91	88	86	84	82	80	78	75
ORL	AP W	4650	50	49	48	47	46	45	44	43	42	40	39
ORL	AP W	4665	100	99	97	96	95	94	92	91	90	89	87
ORL	AP W	4670	58	57	56	55	55	54	53	53	52	51	50
ORL	AP W	4675	100	98	97	96	95	93	92	91	90	88	87
ORL	AP W SEGM	4805	67	65	63	60	58	56	54	52	50	47	45
ORL	AP W SEGM	4810	77	75	73	70	68	66	64	62	60	57	55
ORL	RW 13-31	6205	66	65	65	64	63	63	62	61	60	58	57
ORL	RW 7-25	6105	63	62	61	61	60	59	59	58	57	57	56
ORL	RW 7-25	6110	64	63	62	61	61	60	59	59	58	57	57



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	TW A	104	66	65	63	62	61	60	59	58	57	56	55
ORL	TW A	114	78	76	75	74	72	71	70	68	67	66	65
ORL	TW A	115	56	55	54	53	52	51	50	49	48	47	47
ORL	TW A	116	63	62	60	59	58	57	56	55	54	53	52
ORL	TW A	117	62	61	59	58	57	56	55	54	53	52	51
ORL	TW A	118	94	92	90	88	86	84	82	80	79	77	76
ORL	TW A	119	89	87	85	83	81	80	78	77	75	74	73
ORL	TW A	125	67	66	65	64	63	62	61	61	60	59	58
ORL	TW A	150	57	56	55	54	53	52	51	50	49	48	47
ORL	TW A1	111	77	75	74	73	72	70	69	68	67	66	65
ORL	TW A1	112	57	56	55	54	53	52	51	50	49	48	47
ORL	TW A2	120	65	64	63	62	61	60	60	59	58	57	56
ORL	TW A3	130	67	66	65	64	63	62	61	61	60	59	58
ORL	TW A4	140	63	62	60	59	58	57	56	55	54	53	52
ORL	TW A5	405	65	64	63	62	61	60	60	59	58	57	56
ORL	TW A5	425	71	70	69	67	66	66	65	64	63	62	61
ORL	TW A6	113	72	70	69	68	67	65	64	63	62	61	60
ORL	TW B	102	48	47	46	45	45	44	43	42	42	41	41
ORL	TW B	103	55	54	53	52	51	50	49	48	47	46	44
ORL	TW B	105	87	85	83	81	80	78	77	75	74	73	72
ORL	TW E	505	65	64	62	61	60	59	58	57	56	55	54
ORL	TW E	530	93	91	89	87	85	83	81	80	78	77	75
ORL	TW E	540	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E	545	88	86	84	82	81	79	78	76	75	73	72
ORL	TW E	550	91	89	87	85	83	81	80	78	77	75	74
ORL	TW E1	501	50	49	48	47	46	46	45	44	43	43	42
ORL	TW E2	510	46	45	44	43	43	42	42	41	40	40	39
ORL	TW E2	512	61	60	58	57	56	55	54	53	52	52	51
ORL	TW E3	417	29	28	28	28	28	28	28	28	28	28	28
ORL	TW E3	420	50	49	48	47	46	46	45	44	43	43	42
ORL	TW E3	520	46	45	44	43	43	42	42	41	40	40	39
ORL	TW E3	522	48	47	46	45	45	44	43	42	42	41	41
ORL	TW E4	1070	50	49	48	46	45	44	43	41	40	38	36
ORL	TW E4	1080	56	55	54	53	52	51	50	49	48	47	46
ORL	TW E4	1105	70	68	67	66	65	64	62	61	60	59	58
ORL	TW E4	1110	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E5	560	65	64	62	61	60	59	58	57	56	55	54
ORL	TW E5	565	94	92	90	88	86	84	82	80	79	77	76



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	TW E6	805	67	65	64	63	62	61	60	59	58	56	55
ORL	TW E6	820	94	92	90	89	87	86	84	83	81	80	78
ORL	TW F	605	45	44	43	43	42	41	41	40	40	39	39
ORL	TW G	705	54	53	52	51	50	49	48	47	47	46	45
ORL	TW G	710	55	54	53	52	51	50	49	48	47	47	46
ORL	TW H	806	52	51	50	49	48	47	47	46	45	44	44
ORL	TW K	610	70	68	67	66	65	64	62	61	60	59	58

Major Rehabilitation Planning 2020-2029


Table E-3 Major Rehabilitation Planning 2020-2029

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ORL	AP GA	4205	AC	608,614	48	AC Restoration	\$ 6,102,000.00
2020	ORL	AP GA	4230	AC	23,614	60	AC Restoration	\$ 225,000.00
2020	ORL	AP N	4105	AC	200,966	5	AC Reconstruction	\$ 2,513,000.00
2020	ORL	AP N	4125	AC	140,429	4	AC Reconstruction	\$ 1,756,000.00
2020	ORL	AP N	4140	AC	237,860	24	AC Reconstruction	\$ 2,974,000.00
2020	ORL	AP N	4145	AC	122,500	33	AC Reconstruction	\$ 1,532,000.00
2020	ORL	AP N	4155	AC	337,449	48	AC Restoration	\$ 3,384,000.00
2020	ORL	AP N	4158	AAC	125,584	4	AC Reconstruction	\$ 1,570,000.00
2020	ORL	AP N	4165	AC	27,156	6	AC Reconstruction	\$ 340,000.00
2020	ORL	AP N	4167	AC	28,916	11	AC Reconstruction	\$ 362,000.00
2020	ORL	AP N	4168	PCC	24,538	0	PCC Reconstruction	\$ 491,000.00
2020	ORL	AP NE	4305	AC	52,643	22	AC Reconstruction	\$ 659,000.00
2020	ORL	AP NE	4312	AC	8,541	58	AC Restoration	\$ 82,000.00
2020	ORL	AP W	4605	AC	34,600	63	AC Restoration	\$ 329,000.00
2020	ORL	AP W	4610	AC	260,825	44	AC Restoration	\$ 2,940,000.00
2020	ORL	AP W	4650	AC	115,747	49	AC Restoration	\$ 1,125,000.00
2020	ORL	AP W	4670	AC	10,856	57	AC Restoration	\$ 104,000.00
2020	ORL	RW 7-25	6105	AAC	600,500	62	AC Restoration	\$ 5,705,000.00
2020	ORL	RW 7-25	6110	AAC	300,250	63	AC Restoration	\$ 2,853,000.00
2020	ORL	TW A	104	AC	11,949	65	AC Restoration	\$ 114,000.00
2020	ORL	TW A	115	AC	31,644	55	AC Restoration	\$ 301,000.00
2020	ORL	TW A	116	AC	11,579	62	AC Restoration	\$ 111,000.00
2020	ORL	TW A	117	AC	22,912	61	AC Restoration	\$ 218,000.00
2020	ORL	TW A	150	AC	60,358	56	AC Restoration	\$ 574,000.00
2020	ORL	TW A1	112	AAC	14,428	56	AC Restoration	\$ 138,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ORL	TW A2	120	AAC	30,935	64	AC Restoration	\$ 294,000.00
2020	ORL	TW A4	140	AC	15,668	62	AC Restoration	\$ 149,000.00
2020	ORL	TW A5	405	AAC	37,049	64	AC Restoration	\$ 352,000.00
2020	ORL	TW B	102	AC	6,388	47	AC Restoration	\$ 66,000.00
2020	ORL	TW B	103	AAC	57,000	54	AC Restoration	\$ 542,000.00
2020	ORL	TW E	505	AC	78,110	64	AC Restoration	\$ 743,000.00
2020	ORL	TW E1	501	AC	5,073	49	AC Restoration	\$ 50,000.00
2020	ORL	TW E2	510	AC	9,644	45	AC Restoration	\$ 105,000.00
2020	ORL	TW E2	512	AC	2,687	60	AC Restoration	\$ 26,000.00
2020	ORL	TW E3	417	AC	8,311	28	AC Reconstruction	\$ 104,000.00
2020	ORL	TW E3	420	AC	36,384	49	AC Restoration	\$ 354,000.00
2020	ORL	TW E3	520	AC	9,009	45	AC Restoration	\$ 99,000.00
2020	ORL	TW E3	522	AC	2,133	47	AC Restoration	\$ 22,000.00
2020	ORL	TW E4	1070	AAC	130,837	49	AC Restoration	\$ 1,278,000.00
2020	ORL	TW E4	1080	AAC	8,393	55	AC Restoration	\$ 80,000.00
2020	ORL	TW E5	560	AC	5,540	64	AC Restoration	\$ 53,000.00
2020	ORL	TW F	605	AC	54,815	44	AC Restoration	\$ 613,000.00
2020	ORL	TW G	705	AC	30,099	53	AC Restoration	\$ 286,000.00
2020	ORL	TW G	710	AC	9,812	54	AC Restoration	\$ 94,000.00
2020	ORL	TW H	806	AC	62,452	51	AC Restoration	\$ 594,000.00
2021	ORL	AP N	4170	AC	84,878	64	AC Restoration	\$ 807,000.00
2021	ORL	AP W SEGM	4805	AAC	129,830	63	AC Restoration	\$ 1,234,000.00
2021	ORL	TW E6	805	AC	17,742	64	AC Restoration	\$ 169,000.00
2022	ORL	RW 13-31	6205	AC	445,836	64	AC Restoration	\$ 4,236,000.00
2022	ORL	TW A	125	AAC	257,040	64	AC Restoration	\$ 2,442,000.00
2022	ORL	TW A3	130	AAC	56,163	64	AC Restoration	\$ 534,000.00
2024	ORL	TW E4	1105	AC	6,580	64	AC Restoration	\$ 63,000.00
2024	ORL	TW K	610	AC	27,266	64	AC Restoration	\$ 260,000.00
2025	ORL	AP NE	4315	AAC	24,518	64	AC Restoration	\$ 233,000.00
2025	ORL	AP NE	4320	AAC	53,040	64	AC Restoration	\$ 504,000.00
2025	ORL	AP W SEGM	4810	AAC	79,530	64	AC Restoration	\$ 756,000.00
2025	ORL	TW A6	113	AC	26,953	64	AC Restoration	\$ 257,000.00
2026	ORL	AP RU	5110	AC	25,880	64	AC Restoration	\$ 246,000.00
2026	ORL	AP RU	5115	AC	36,282	63	AC Restoration	\$ 345,000.00
2026	ORL	AP RU	5120	AC	41,840	64	AC Restoration	\$ 398,000.00
2026	ORL	TW A5	425	AAC	9,443	64	AC Restoration	\$ 90,000.00
2027	ORL	AP N	4175	AC	42,594	64	AC Restoration	\$ 405,000.00

*All planning cost values have been rounded to the nearest thousand-dollar.


*Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029*

Summary of Orlando Executive Airport

Orlando Executive Airport was inspected in March 2019 – the overall weighted PCI value was 55, a condition rating of Poor. The results of the maintenance, repair, and major rehabilitation analysis identified \$8,426,960 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$55,385,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$42,406,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.

Chapter 1





Chapter 1 – Introduction

1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating public-use airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.



1.3 Organization

1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."** Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys,"** evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."**

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- ▶ **Research and evaluation of existing record documentation** was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- ▶ **An update to the existing Network Definition Map** was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- ▶ **A functional pavement evaluation with PCI Survey inspections** was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- ▶ **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- ▶ **Maintenance, Repair, and Rehabilitation Planning** was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.



1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA **AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."** The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.



1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and **150/5380-7B “Airport Pavement Management Program (PMP)”**). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.”

1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC **150/5380-7B “Airport Pavement Management Program (PMP)”** an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data




F. Pavement Performance Modeling for the Prediction/Forecast of PCI

G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements’ past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and cost-effective manner. **Figure 1.7.2 (a) Typical Pavement Condition Life Cycle**, which is based on the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”** **Figure 1.7.2 (a) Typical Pavement Condition Life Cycle**, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.

Figure 1.7.2 (a) Typical Pavement Condition Life Cycle




**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).*

Figure 1.7.2 (b) General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.





Figure 1.7.2 (b) General Pavement Treatments by Condition Range







Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7.2 (a) and 1.7.2 (b)**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7.2 (c) and 1.7.2 (d), depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.


Figures 1.7.2 (c) Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figures 1.7.2 (d) Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.




1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”
- FAA Advisory Circular 150/5380-7B “Airport Pavement Management Program.”
- FAA Advisory Circular 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”
- FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation.”
- Department of the Air Force, Air Force Civil Engineer Center “Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements.”
- Unified Facilities Criteria (UFC) 3-260-16FA 16 “Airfield Pavement Condition Survey Procedures Pavements.”
- Unified Facilities Criteria (UFC) 3-260-03 “Airfield Pavement Evaluation.”
- Pavement Management for Airports, Roads, and Parking Lots 2nd Edition, M.Y. Shahin.

Chapter 2





Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”**

2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.



A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a “parent” pavement network.

Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (± 8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ($\pm 2,000$ ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	“Tallahassee International Airport – Airfield Pavements”
Branch Name	Commonly defined asset name as established by Airport and by use	“Runway 18-36”
Branch ID	Codified shorthand name for commonly defined asset established for database identification	“RW 18-36” RW, Branch Use, “Runway” 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following: <ul style="list-style-type: none"> • Pavement Composition • Construction Work History • Aircraft Traffic • Condition Records 	“6105”
Sample Unit	A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	“300”



2.3 Airfield Pavement Structure

2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.



Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 8 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 8 inches in thickness.

Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.



2.4 Airfield Pavement Work History

2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

1. Location and Limits of Work.
2. Types and Severity of Distresses Repaired.
3. Type of Work.
4. Cost of Work.
5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.6 Airfield Pavement Condition Index (PCI) Survey

2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP),"** the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.



2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age



Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> Alligator Cracking Corrugation Depression Patching of Load-based distress Polished Aggregate Rutting Slippage Cracking 	<ul style="list-style-type: none"> Bleeding Block Cracking Joint Reflection Cracking L/T Cracking Patching of climate / durability-caused distresses Shoving from PCC Raveling Weathering Swelling 	<ul style="list-style-type: none"> Alligator Cracking Depression Patching of moisture / drainage caused distress Swelling Raveling Weathering 	<ul style="list-style-type: none"> Oil Spillage Jet Blast Erosion Polished Aggregate

Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> Corrugation Depression Rutting Shoving of asphalt pavement Swelling Raveling Weathering 	<ul style="list-style-type: none"> Bleeding Depression Polished Aggregate Rutting 	<ul style="list-style-type: none"> Block Cracking Joint Reflection Cracking L/T Cracking Slippage Cracking 	<ul style="list-style-type: none"> All Distresses



Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Blowup	Climate / ASR
Corner Break	Load Repetition / Curling Stresses
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
Durability Cracking	Freeze-Thaw Cycling
Joint Seal Damage	Material Deterioration / Construction Quality / Age
Small Patch	Pavement Repair
Large Patch/Utility Cut	Utility / Pavement Repair
Popout	Freeze-Thaw Cycling / ASR / Material Quality
Pumping	Load Repetition / Poor Joint Sealant
Scaling	Construction Quality / Freeze-Thaw Cycling
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer
Shattered Slab	Overloading
Shrinkage Cracking	Construction Quality / Climate
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction



Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> • Corner Break • Shattered Slab • L/T/D Cracking • Pumping • Patching of Load-associated distress • Spalling 	<ul style="list-style-type: none"> • Blowup • "D" Cracking • Joint Seal Damage • Popouts • Scaling • Patch of Climate/Durability-associated distress • Shrinkage Cracking • Spalling • L/T/D Cracking 	<ul style="list-style-type: none"> • Corner Break • Shattered Slab • Pumping • Patching of Moisture/Drainage-associated distress 	<ul style="list-style-type: none"> • Settlement / Faulting

Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> • Blowup • Corner Break • L/T/D Cracking • Shattered Slab • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Corner Break • L/T/D Cracking • "D" Cracking • Joint Seal Damage • Shattered Slab • Popouts • Scaling 	<ul style="list-style-type: none"> • All distresses



2.6.3 PCI Survey Inspection Procedures

Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10



2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured “(52) Weathering and Raveling” distress has been separated into two distresses “(52) Raveling” and “(57) Weathering.” Previously, areas that were recorded as “Weathering and Raveling” were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where “Weathering” only exists and does not meet the definition of “Raveling,” the PCI deduction is not as high as the former “Weathering and Raveling.” Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling,” may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

Rigid Portland Cement Concrete Pavement Distress Updates


The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR.” As a result, the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling,” and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, “(73) Shrinkage Cracks” has been redefined as “(73) Shrinkage Cracking”. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage can be caused by both atmospheric conditions and construction. Plastic shrinkage caused by atmospheric conditions develops when there is rapid loss of water in the surface of recently placed pavement. High winds or low humidity are contributing factors to evaporation. These shrinkage cracks can appear as a series of parallel cracks, usually 1 to 3 feet apart and do not extend very deep into the pavement’s surface. Plastic shrinkage caused by construction can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Distress Updates to Reflect ASTM 5340-12				
Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Cracking - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Cracking - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Cracking - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Cracking' may now be identified as 'Shrinkage Cracking'

Chapter 3





Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1 (a)** and **Figure 3.1.1 (b)** provides an inset view of the 2019 Airfield Pavement Network Definition Exhibit and the 2019 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.


Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Year	General Work Description
2015	TW A, TW B, TW E, TW E4, TW E5 - Mill and Overlay: 2" Mill and Variable Overlay P-401SP
	TW E6 - Reconstruction: 4" P-401, 10" P-219, Compacted Subgrade
2017	AP W - New Construction
2019	AP W - Mill and Overlay
	AP W - Reconstruction

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.




Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit



The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.

Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit




The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections at the time of the PCI survey inspection. Age is determined to be the number of years since any major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.



Figure 3.1.2 Average Age of Pavements at Inspection




The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.



3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.

Figure 3.1.4 (a) Pavement Surface Type by Area (SF)



*Figure 3.1.4 (b) Pavement Surface Type by Area (%)*

3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ORL	GA APRON	AP GA	APRON	4205	1,675	364	608,614	AC	1/1/1984
ORL	GA APRON	AP GA	APRON	4230	1,129	50	23,614	AC	12/25/1999
ORL	NORTH APRON	AP N	APRON	4105	500	370	200,966	AC	1/1/1979
ORL	NORTH APRON	AP N	APRON	4125	400	350	140,429	AC	1/1/1978
ORL	NORTH APRON	AP N	APRON	4140	1,000	200	237,860	AC	1/1/1979
ORL	NORTH APRON	AP N	APRON	4145	700	200	122,500	AC	1/1/1968
ORL	NORTH APRON	AP N	APRON	4155	3,985	200	337,449	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4158	580	215	125,584	AAC	1/1/2002
ORL	NORTH APRON	AP N	APRON	4165	270	100	27,156	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4166	440	50	22,635	AC	9/1/2012
ORL	NORTH APRON	AP N	APRON	4167	450	60	28,916	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4168	500	50	24,538	PCC	1/1/2005
ORL	NORTH APRON	AP N	APRON	4169	400	200	72,939	AC	9/1/2012
ORL	NORTH APRON	AP N	APRON	4170	850	100	84,878	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4175	250	165	42,594	AC	1/1/1960
ORL	NE APRON	AP NE	APRON	4305	500	100	52,643	AC	1/1/1984
ORL	NE APRON	AP NE	APRON	4312	450	20	8,541	AC	12/25/1999
ORL	NE APRON	AP NE	APRON	4315	600	40	24,518	AAC	1/1/2007
ORL	NE APRON	AP NE	APRON	4320	1,000	50	53,040	AAC	1/1/2007
ORL	RUN-UP APRONS	AP RU	APRON	5110	233	100	25,880	AC	1/1/2001
ORL	RUN-UP APRONS	AP RU	APRON	5115	255	130	36,282	AC	1/1/2001
ORL	RUN-UP APRONS	AP RU	APRON	5120	420	100	41,840	AC	1/1/2001
ORL	WEST APRON	AP W	APRON	4605	700	50	34,600	AC	1/1/2002
ORL	WEST APRON	AP W	APRON	4610	150	1,700	260,825	AC	1/1/1999
ORL	WEST APRON	AP W	APRON	4640	450	350	157,964	AAC	3/1/2019



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ORL	WEST APRON	AP W	APRON	4645	375	65	24,864	AC	12/1/2017
ORL	WEST APRON	AP W	APRON	4650	520	220	115,747	AC	12/1/1998
ORL	WEST APRON	AP W	APRON	4665	150	60	8,833	PCC	6/1/2019
ORL	WEST APRON	AP W	APRON	4670	110	100	10,856	AC	12/1/1998
ORL	WEST APRON	AP W	APRON	4675	44	40	1,760	PCC	3/1/2019
ORL	SE SEGMENT OF WEST APRON	AP W SEGM	APRON	4805	535	245	129,830	AAC	1/1/2001
ORL	SE SEGMENT OF WEST APRON	AP W SEGM	APRON	4810	400	200	79,530	AAC	1/1/2012
ORL	RUNWAY 13-31	RW 13-31	RUNWAY	6205	4,500	100	445,836	AC	1/1/1999
ORL	RUNWAY 7-25	RW 7-25	RUNWAY	6105	6,005	100	600,500	AAC	1/2/2001
ORL	RUNWAY 7-25	RW 7-25	RUNWAY	6110	12,010	25	300,250	AAC	1/2/2001
ORL	TAXIWAY A	TW A	TAXIWAY	104	195	65	11,949	AC	1/1/2001
ORL	TAXIWAY A	TW A	TAXIWAY	114	200	50	12,579	AC	1/1/1999
ORL	TAXIWAY A	TW A	TAXIWAY	115	870	38	31,644	AC	1/1/1984
ORL	TAXIWAY A	TW A	TAXIWAY	116	60	150	11,579	AC	1/1/1984
ORL	TAXIWAY A	TW A	TAXIWAY	117	390	35	22,912	AC	1/1/1984
ORL	TAXIWAY A	TW A	TAXIWAY	118	208	47	12,843	AAC	10/1/2015
ORL	TAXIWAY A	TW A	TAXIWAY	119	104	78	8,568	AAC	10/1/2015
ORL	TAXIWAY A	TW A	TAXIWAY	125	3,400	75	257,040	AAC	1/1/1997
ORL	TAXIWAY A	TW A	TAXIWAY	150	1,000	50	60,358	AC	1/1/1963
ORL	TAXIWAY A1	TW A1	TAXIWAY	111	200	125	15,537	AAC	1/1/1997
ORL	TAXIWAY A1	TW A1	TAXIWAY	112	190	75	14,428	AAC	1/1/1997
ORL	TAXIWAY A2	TW A2	TAXIWAY	120	387	75	30,935	AAC	1/1/1997
ORL	TAXIWAY A3	TW A3	TAXIWAY	130	600	75	56,163	AAC	1/1/1997
ORL	TAXIWAY A4	TW A4	TAXIWAY	140	397	30	15,668	AC	1/1/1999
ORL	TAXIWAY A5	TW A5	TAXIWAY	405	400	75	37,049	AAC	1/1/1997
ORL	TAXIWAY A5	TW A5	TAXIWAY	425	95	100	9,443	AAC	1/1/1997



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ORL	TAXIWAY A6	TW A6	TAXIWAY	113	640	35	26,953	AC	1/1/2001
ORL	TAXIWAY B	TW B	TAXIWAY	102	145	50	6,388	AC	1/1/1991
ORL	TAXIWAY B	TW B	TAXIWAY	103	760	75	57,000	AAC	1/1/1999
ORL	TAXIWAY B	TW B	TAXIWAY	105	435	75	30,470	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	505	1,822	40	78,110	AC	1/1/1983
ORL	TAXIWAY E	TW E	TAXIWAY	530	680	40	46,191	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	540	350	40	21,326	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	545	180	45	9,618	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	550	1,336	40	52,982	AAC	12/25/2015
ORL	TAXIWAY E1	TW E1	TAXIWAY	501	40	125	5,073	AC	1/1/1977
ORL	TAXIWAY E2	TW E2	TAXIWAY	510	140	40	9,644	AC	1/1/1983
ORL	TAXIWAY E2	TW E2	TAXIWAY	512	75	40	2,687	AC	1/1/1983
ORL	TAXIWAY E3	TW E3	TAXIWAY	417	42	200	8,311	AC	1/1/1977
ORL	TAXIWAY E3	TW E3	TAXIWAY	420	40	900	36,384	AC	1/1/1984
ORL	TAXIWAY E3	TW E3	TAXIWAY	520	225	40	9,009	AC	1/1/1983
ORL	TAXIWAY E3	TW E3	TAXIWAY	522	67	32	2,133	AC	1/1/1983
ORL	TAXIWAY E4	TW E4	TAXIWAY	1070	1,072	75	130,837	AAC	1/1/1977
ORL	TAXIWAY E4	TW E4	TAXIWAY	1080	80	50	8,393	AAC	1/1/1977
ORL	TAXIWAY E4	TW E4	TAXIWAY	1105	175	38	6,580	AC	1/1/1991
ORL	TAXIWAY E4	TW E4	TAXIWAY	1110	70	75	20,682	AAC	12/25/2015
ORL	TAXIWAY E5	TW E5	TAXIWAY	560	115	40	5,540	AC	1/1/1991
ORL	TAXIWAY E5	TW E5	TAXIWAY	565	140	40	9,465	AAC	10/1/2015
ORL	TAXIWAY E6	TW E6	TAXIWAY	805	185	40	17,742	AC	1/1/1984
ORL	TAXIWAY E6	TW E6	TAXIWAY	820	145	70	11,139	AC	12/25/2015
ORL	TAXIWAY F	TW F	TAXIWAY	605	1,300	40	54,815	AC	1/1/1984
ORL	TAXIWAY G	TW G	TAXIWAY	705	660	40	30,099	AC	1/1/1984




Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ORL	TAXIWAY G	TW G	TAXIWAY	710	215	40	9,812	AC	1/1/1988
ORL	TAXIWAY H	TW H	TAXIWAY	806	1,560	40	62,452	AC	1/1/1983
ORL	TAXIWAY K	TW K	TAXIWAY	610	500	50	27,266	AC	1/1/1999



PAGE INTENTIONALLY LEFT BLANK

Chapter 4





Chapter 4 – Airfield Pavement Condition


The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

4.1 Airfield Pavement Condition Index (Latest Inspection)

4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.

Figure 4.1.1 Latest Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (c)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.



Figure 4.1.2 (a) Latest Condition – Runway Pavements




Figure 4.1.2 (b) Latest Condition – Taxiway Pavements







Figure 4.1.2 (c) Latest Condition – Apron Pavements



4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement.

Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.



Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
ORL	AP GA	GA APRON	APRON	4205	608,614	AC	49	Poor	97%	0%	3%	10	118
ORL	AP GA	GA APRON	APRON	4230	23,614	AC	61	Fair	100%	0%	0%	1	6
ORL	AP N	NORTH APRON	APRON	4105	200,966	AC	6	Failed	78%	21%	1%	5	42
ORL	AP N	NORTH APRON	APRON	4125	140,429	AC	5	Failed	70%	30%	0%	3	27
ORL	AP N	NORTH APRON	APRON	4140	237,860	AC	25	Serious	96%	0%	4%	6	46
ORL	AP N	NORTH APRON	APRON	4145	122,500	AC	34	Very Poor	100%	0%	0%	3	27
ORL	AP N	NORTH APRON	APRON	4155	337,449	AC	49	Poor	100%	0%	0%	7	69
ORL	AP N	NORTH APRON	APRON	4158	125,584	AAC	6	Failed	96%	0%	4%	3	25
ORL	AP N	NORTH APRON	APRON	4165	27,156	AC	7	Failed	91%	0%	9%	1	5
ORL	AP N	NORTH APRON	APRON	4166	22,635	AC	89	Good	100%	0%	0%	1	6
ORL	AP N	NORTH APRON	APRON	4167	28,916	AC	12	Serious	60%	35%	5%	1	5
ORL	AP N	NORTH APRON	APRON	4168	24,538	PCC	0	Failed	8%	92%	0%	1	4
ORL	AP N	NORTH APRON	APRON	4169	72,939	AC	86	Good	100%	0%	0%	3	16
ORL	AP N	NORTH APRON	APRON	4170	84,878	AC	67	Fair	99%	0%	1%	3	18
ORL	AP N	NORTH APRON	APRON	4175	42,594	AC	76	Satisfactory	73%	0%	27%	2	9
ORL	AP NE	NE APRON	APRON	4305	52,643	AC	23	Serious	83%	9%	8%	2	11
ORL	AP NE	NE APRON	APRON	4312	8,541	AC	59	Fair	64%	0%	36%	1	2
ORL	AP NE	NE APRON	APRON	4315	24,518	AAC	77	Satisfactory	100%	0%	0%	1	5
ORL	AP NE	NE APRON	APRON	4320	53,040	AAC	77	Satisfactory	100%	0%	0%	2	14
ORL	AP RU	RUN-UP APRONS	APRON	5110	25,880	AC	75	Satisfactory	83%	0%	17%	1	5
ORL	AP RU	RUN-UP APRONS	APRON	5115	36,282	AC	74	Satisfactory	87%	0%	13%	1	7
ORL	AP RU	RUN-UP APRONS	APRON	5120	41,840	AC	75	Satisfactory	67%	0%	33%	1	8
ORL	AP W	WEST APRON	APRON	4605	34,600	AC	64	Fair	96%	0%	4%	1	7
ORL	AP W	WEST APRON	APRON	4610	260,825	AC	45	Poor	92%	0%	8%	6	58
ORL	AP W	WEST APRON	APRON	4640	157,964	AAC	100	Good	0%	0%	0%	0	34
ORL	AP W	WEST APRON	APRON	4645	24,864	AC	100	Good	0%	0%	0%	0	5
ORL	AP W	WEST APRON	APRON	4650	115,747	AC	50	Poor	94%	0%	6%	4	24
ORL	AP W	WEST APRON	APRON	4665	8,833	PCC	100	Good	6%	55%	39%	0	2
ORL	AP W	WEST APRON	APRON	4670	10,856	AC	58	Fair	89%	0%	11%	1	3
ORL	AP W	WEST APRON	APRON	4675	1,760	PCC	100	Good	0%	0%	0%	0	1
ORL	AP W SEGM	SE SEGMENT OF WEST APRON	APRON	4805	129,830	AAC	67	Fair	98%	0%	2%	3	26
ORL	AP W SEGM	SE SEGMENT OF WEST APRON	APRON	4810	79,530	AAC	77	Satisfactory	71%	0%	29%	3	15
ORL	RW 13-31	RUNWAY 13-31	RUNWAY	6205	445,836	AC	66	Fair	67%	0%	33%	18	89
ORL	RW 7-25	RUNWAY 7-25	RUNWAY	6105	600,500	AAC	63	Fair	93%	0%	7%	20	120
ORL	RW 7-25	RUNWAY 7-25	RUNWAY	6110	300,250	AAC	64	Fair	87%	0%	13%	12	60
ORL	TW A	TAXIWAY A	TAXIWAY	104	11,949	AC	66	Fair	76%	0%	24%	1	2
ORL	TW A	TAXIWAY A	TAXIWAY	114	12,579	AC	78	Satisfactory	100%	0%	0%	1	2



Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
ORL	TW A	TAXIWAY A	TAXIWAY	115	31,644	AC	56	Fair	100%	0%	0%	1	8
ORL	TW A	TAXIWAY A	TAXIWAY	116	11,579	AC	63	Fair	100%	0%	0%	1	3
ORL	TW A	TAXIWAY A	TAXIWAY	117	22,912	AC	62	Fair	100%	0%	0%	1	5
ORL	TW A	TAXIWAY A	TAXIWAY	118	12,843	AAC	94	Good	100%	0%	0%	1	3
ORL	TW A	TAXIWAY A	TAXIWAY	119	8,568	AAC	89	Good	100%	0%	0%	1	2
ORL	TW A	TAXIWAY A	TAXIWAY	125	257,040	AAC	67	Fair	68%	0%	32%	7	68
ORL	TW A	TAXIWAY A	TAXIWAY	150	60,358	AC	57	Fair	84%	0%	16%	2	12
ORL	TW A1	TAXIWAY A1	TAXIWAY	111	15,537	AAC	77	Satisfactory	100%	0%	0%	1	4
ORL	TW A1	TAXIWAY A1	TAXIWAY	112	14,428	AAC	57	Fair	68%	32%	0%	1	4
ORL	TW A2	TAXIWAY A2	TAXIWAY	120	30,935	AAC	65	Fair	86%	0%	14%	1	8
ORL	TW A3	TAXIWAY A3	TAXIWAY	130	56,163	AAC	67	Fair	74%	0%	26%	3	14
ORL	TW A4	TAXIWAY A4	TAXIWAY	140	15,668	AC	63	Fair	65%	0%	35%	1	4
ORL	TW A5	TAXIWAY A5	TAXIWAY	405	37,049	AAC	65	Fair	81%	0%	19%	1	8
ORL	TW A5	TAXIWAY A5	TAXIWAY	425	9,443	AAC	71	Satisfactory	96%	0%	4%	1	2
ORL	TW A6	TAXIWAY A6	TAXIWAY	113	26,953	AC	72	Satisfactory	81%	0%	19%	1	7
ORL	TW B	TAXIWAY B	TAXIWAY	102	6,388	AC	48	Poor	100%	0%	0%	1	1
ORL	TW B	TAXIWAY B	TAXIWAY	103	57,000	AAC	55	Poor	77%	0%	23%	2	15
ORL	TW B	TAXIWAY B	TAXIWAY	105	30,470	AAC	87	Good	100%	0%	0%	1	8
ORL	TW E	TAXIWAY E	TAXIWAY	505	78,110	AC	65	Fair	100%	0%	0%	3	19
ORL	TW E	TAXIWAY E	TAXIWAY	530	46,191	AAC	93	Good	100%	0%	0%	2	11
ORL	TW E	TAXIWAY E	TAXIWAY	540	21,326	AAC	94	Good	100%	0%	0%	1	5
ORL	TW E	TAXIWAY E	TAXIWAY	545	9,618	AAC	88	Good	100%	0%	0%	1	2
ORL	TW E	TAXIWAY E	TAXIWAY	550	52,982	AAC	91	Good	100%	0%	0%	2	13
ORL	TW E1	TAXIWAY E1	TAXIWAY	501	5,073	AC	50	Poor	93%	0%	7%	1	1
ORL	TW E2	TAXIWAY E2	TAXIWAY	510	9,644	AC	46	Poor	96%	0%	4%	1	2
ORL	TW E2	TAXIWAY E2	TAXIWAY	512	2,687	AC	61	Fair	90%	0%	10%	1	1
ORL	TW E3	TAXIWAY E3	TAXIWAY	417	8,311	AC	29	Very Poor	100%	0%	0%	1	2
ORL	TW E3	TAXIWAY E3	TAXIWAY	420	36,384	AC	50	Poor	47%	9%	44%	3	8
ORL	TW E3	TAXIWAY E3	TAXIWAY	520	9,009	AC	46	Poor	95%	0%	5%	1	2
ORL	TW E3	TAXIWAY E3	TAXIWAY	522	2,133	AC	48	Poor	79%	0%	21%	1	1
ORL	TW E4	TAXIWAY E4	TAXIWAY	1070	130,837	AAC	50	Poor	98%	0%	2%	4	31
ORL	TW E4	TAXIWAY E4	TAXIWAY	1080	8,393	AAC	56	Fair	100%	0%	0%	1	2
ORL	TW E4	TAXIWAY E4	TAXIWAY	1105	6,580	AC	70	Fair	95%	0%	5%	1	1
ORL	TW E4	TAXIWAY E4	TAXIWAY	1110	20,682	AAC	94	Good	100%	0%	0%	1	4
ORL	TW E5	TAXIWAY E5	TAXIWAY	560	5,540	AC	65	Fair	100%	0%	0%	1	1
ORL	TW E5	TAXIWAY E5	TAXIWAY	565	9,465	AAC	94	Good	100%	0%	0%	1	2
ORL	TW E6	TAXIWAY E6	TAXIWAY	805	17,742	AC	67	Fair	100%	0%	0%	1	4
ORL	TW E6	TAXIWAY E6	TAXIWAY	820	11,139	AC	94	Good	100%	0%	0%	1	3




Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
ORL	TW F	TAXIWAY F	TAXIWAY	605	54,815	AC	45	Poor	99%	0%	1%	2	13
ORL	TW G	TAXIWAY G	TAXIWAY	705	30,099	AC	54	Poor	80%	0%	20%	2	7
ORL	TW G	TAXIWAY G	TAXIWAY	710	9,812	AC	55	Poor	81%	0%	19%	1	2
ORL	TW H	TAXIWAY H	TAXIWAY	806	62,452	AC	52	Poor	100%	0%	0%	3	16
ORL	TW K	TAXIWAY K	TAXIWAY	610	27,266	AC	70	Fair	87%	0%	13%	1	6



Figure 4.1.3 is an inset view of the 2019 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits**.

Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit





4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The field PCI Survey performed at Orlando Executive Airport (ORL) was completed in March 2019. The resulting overall area-weighted average PCI value was 55 representing a condition rating of Poor. Orlando Executive Airport is serviced by two runways; Runway 7-25 is 150-ft wide and 6,004-ft long and Runway 13-31 is 100-ft wide and 4,625-ft long. Due to recent construction, a portion of the West Apron was not inspected. The recently rehabbed area will have a PCI of 100, a condition rating of Good.

Based on the FAA 5010 Report as of 09/12/2019 the Airport has reported 10*,483 operations for 12 months ending 08/17/2018.

4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

Runway 13-31

Runway 13-31 consists of 1 section constructed of AC. The last construction year for Runway 13-31 was 1999. The area-weighted average PCI for Runway 13-31 is 66, representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Runway 13-31 consist of Depression, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Runway 7-25

Runway 7-25 consists of 2 sections constructed of AAC. The last construction year for Runway 7-25 was 2001. The area-weighted average PCI for Runway 7-25 is 63 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Runway 7-25 consist of Depression, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Taxiway A

Taxiway A consists of 9 sections constructed of AC and AAC. The last construction years range from 1963 to 2015. The area-weighted average PCI for Taxiway A is 65 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway A consist of Bleeding, Block Cracking, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Taxiway H

Taxiway H consists of 1 section constructed of AC. The last construction year for Taxiway H was 1983. The area-weighted average PCI for Taxiway H is 52 representing a Poor condition rating. The pavement distress observed was related to Climate distress classifications. Distresses observed on Taxiway H consist of Block Cracking, Longitudinal & Transverse Cracking, and Raveling.



GA Apron

GA Apron consists of 2 sections constructed of AC. The last construction years range from 1984 to 1999. The area-weighted average PCI for GA Apron is 49 representing a Poor condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on GA Apron consist of Block Cracking, Longitudinal & Transverse Cracking, Raveling, and Swelling.

North Apron

North Apron consists of 13 sections constructed of AC, AAC, and PCC. The last construction years range from 1960 to 2012. The area-weighted average PCI for North Apron is 32 representing a Very Poor condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on North Apron consist of Alligator Cracking, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Swelling, Weathering, Joint Seal Damage, and Shattered Slab.

West Apron

West Apron consists of 8 sections constructed of AC, AAC, and PCC. The last construction years range from 1998 to 2019. The area-weighted average PCI for West Apron is 64 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on West Apron consist of Block Cracking, Depression, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Swelling, Weathering, Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Scaling, Faulting, Shattered Slab, Shrinkage Cracking, Joint Spall, and Corner Spall.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Area-Weighted Average PCI	Condition Rating
Runway	64	Fair
Taxiway	65	Fair
Apron	46	Poor



4.3 Forecasted Pavement Conditions

4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to develop forecasted PCI values based on historic trends and statistical models.

4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2020 through January 2029.

Figure 4.3.2 (a) Forecasted Runway Pavement Performance






Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance





4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.



Table 4.3.3 Forecasted PCI 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	AP GA	4205	49	48	47	46	45	44	43	41	40	39	38
ORL	AP GA	4230	61	60	59	58	57	56	56	55	54	54	53
ORL	AP N	4105	6	5	5	5	4	4	3	3	3	2	2
ORL	AP N	4125	5	4	4	4	3	3	2	2	2	1	1
ORL	AP N	4140	25	24	24	24	23	23	22	22	22	21	21
ORL	AP N	4145	34	33	32	31	30	30	29	29	29	28	28
ORL	AP N	4155	49	48	47	46	45	44	43	41	40	39	38
ORL	AP N	4158	6	4	2	0	0	0	0	0	0	0	0
ORL	AP N	4165	7	6	6	6	5	5	4	4	4	3	3
ORL	AP N	4166	89	87	84	82	80	78	76	74	72	71	69
ORL	AP N	4167	12	11	11	11	10	10	9	9	9	8	8
ORL	AP N	4168	0	0	0	0	0	0	0	0	0	0	0
ORL	AP N	4169	86	84	82	79	77	75	74	72	70	69	67
ORL	AP N	4170	67	65	64	63	62	61	60	59	58	57	57
ORL	AP N	4175	76	74	72	71	69	67	66	65	64	62	61
ORL	AP NE	4305	23	22	22	22	21	21	20	20	20	19	19
ORL	AP NE	4312	59	58	57	56	56	55	54	53	53	52	51
ORL	AP NE	4315	77	75	73	70	68	66	64	62	60	57	55
ORL	AP NE	4320	77	75	73	70	68	66	64	62	60	57	55
ORL	AP RU	5110	75	73	71	70	68	67	65	64	63	62	61
ORL	AP RU	5115	74	72	70	69	67	66	65	63	62	61	60
ORL	AP RU	5120	75	73	71	70	68	67	65	64	63	62	61
ORL	AP W	4605	64	63	62	61	60	59	58	57	56	56	55
ORL	AP W	4610	45	44	42	41	40	39	38	37	35	34	33
ORL	AP W	4640	100	98	96	93	91	89	87	85	82	80	78
ORL	AP W	4645	100	95	93	91	88	86	84	82	80	78	75



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	AP W	4650	50	49	48	47	46	45	44	43	42	40	39
ORL	AP W	4665	100	99	97	96	95	94	92	91	90	89	87
ORL	AP W	4670	58	57	56	55	55	54	53	53	52	51	50
ORL	AP W	4675	100	98	97	96	95	93	92	91	90	88	87
ORL	AP W SEGM	4805	67	65	63	60	58	56	54	52	50	47	45
ORL	AP W SEGM	4810	77	75	73	70	68	66	64	62	60	57	55
ORL	RW 13-31	6205	66	65	65	64	63	63	62	61	60	58	57
ORL	RW 7-25	6105	63	62	61	61	60	59	59	58	57	57	56
ORL	RW 7-25	6110	64	63	62	61	61	60	59	59	58	57	57
ORL	TW A	104	66	65	63	62	61	60	59	58	57	56	55
ORL	TW A	114	78	76	75	74	72	71	70	68	67	66	65
ORL	TW A	115	56	55	54	53	52	51	50	49	48	47	47
ORL	TW A	116	63	62	60	59	58	57	56	55	54	53	52
ORL	TW A	117	62	61	59	58	57	56	55	54	53	52	51
ORL	TW A	118	94	92	90	88	86	84	82	80	79	77	76
ORL	TW A	119	89	87	85	83	81	80	78	77	75	74	73
ORL	TW A	125	67	66	65	64	63	62	61	61	60	59	58
ORL	TW A	150	57	56	55	54	53	52	51	50	49	48	47
ORL	TW A1	111	77	75	74	73	72	70	69	68	67	66	65
ORL	TW A1	112	57	56	55	54	53	52	51	50	49	48	47
ORL	TW A2	120	65	64	63	62	61	60	60	59	58	57	56
ORL	TW A3	130	67	66	65	64	63	62	61	61	60	59	58
ORL	TW A4	140	63	62	60	59	58	57	56	55	54	53	52
ORL	TW A5	405	65	64	63	62	61	60	60	59	58	57	56
ORL	TW A5	425	71	70	69	67	66	66	65	64	63	62	61
ORL	TW A6	113	72	70	69	68	67	65	64	63	62	61	60
ORL	TW B	102	48	47	46	45	45	44	43	42	42	41	41
ORL	TW B	103	55	54	53	52	51	50	49	48	47	46	44




Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	TW B	105	87	85	83	81	80	78	77	75	74	73	72
ORL	TW E	505	65	64	62	61	60	59	58	57	56	55	54
ORL	TW E	530	93	91	89	87	85	83	81	80	78	77	75
ORL	TW E	540	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E	545	88	86	84	82	81	79	78	76	75	73	72
ORL	TW E	550	91	89	87	85	83	81	80	78	77	75	74
ORL	TW E1	501	50	49	48	47	46	46	45	44	43	43	42
ORL	TW E2	510	46	45	44	43	43	42	42	41	40	40	39
ORL	TW E2	512	61	60	58	57	56	55	54	53	52	52	51
ORL	TW E3	417	29	28	28	28	28	28	28	28	28	28	28
ORL	TW E3	420	50	49	48	47	46	46	45	44	43	43	42
ORL	TW E3	520	46	45	44	43	43	42	42	41	40	40	39
ORL	TW E3	522	48	47	46	45	45	44	43	42	42	41	41
ORL	TW E4	1070	50	49	48	46	45	44	43	41	40	38	36
ORL	TW E4	1080	56	55	54	53	52	51	50	49	48	47	46
ORL	TW E4	1105	70	68	67	66	65	64	62	61	60	59	58
ORL	TW E4	1110	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E5	560	65	64	62	61	60	59	58	57	56	55	54
ORL	TW E5	565	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E6	805	67	65	64	63	62	61	60	59	58	56	55
ORL	TW E6	820	94	92	90	89	87	86	84	83	81	80	78
ORL	TW F	605	45	44	43	43	42	41	41	40	40	39	39
ORL	TW G	705	54	53	52	51	50	49	48	47	47	46	45
ORL	TW G	710	55	54	53	52	51	50	49	48	47	47	46
ORL	TW H	806	52	51	50	49	48	47	47	46	45	44	44
ORL	TW K	610	70	68	67	66	65	64	62	61	60	59	58



4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA **AC 150/5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements** to determine structural and/or functional conditions at the time of project.

Chapter 5





Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- **Localized Maintenance and Repair** includes patching and crack sealing.
- **Global Treatments** include surface seals and rejuvenators for flexible pavements.
- **Major Rehabilitation** includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distressed pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety (“stopgap”) measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.



5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2 (a)** and **Table 5.2 (b)**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and the **FDOT Airfield Pavement Distress Repair Manual**. Additionally, the **Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements** was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft



Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L & T CR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt



Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$9.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$4.00	SqFt

Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$150.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in **5.2 Localized M&R Policy**. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. **Appendix B** provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to near-term Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3 (a)** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - SURFACE SEAL	PREVENTIVE	311,005	SqFt	\$ 171,060.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	6,400	SqFt	\$ 25,590.00
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	3,345	SqFt	\$ 30,090.00
FDOT - CRACK SEALING - AC	PREVENTIVE	1,180	Ft	\$ 3,540.00
FDOT - SURFACE SEAL	STOPGAP	2,032,885	SqFt	\$ 1,118,100.00
FDOT - JOINT SEAL - PCC	STOPGAP	1,745	Ft	\$ 4,790.00
FDOT - CRACK SEALING - AC	STOPGAP	198,100	Ft	\$ 594,290.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	1,356,070	SqFt	\$ 5,424,280.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	35,650	SqFt	\$ 320,820.00
FDOT - SLAB REPLACEMENT - PCC	STOPGAP	24,480	SqFt	\$ 734,400.00



The following **Table 5.3 (b)** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved “End Condition” of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
ORL	AP GA	4205	608,614	49	62	\$ 394,480.00
ORL	AP GA	4230	23,614	61	67	\$ 7,420.00
ORL	AP N	4105	200,966	6	56	\$ 1,520,570.00
ORL	AP N	4125	140,429	5	53	\$ 927,310.00
ORL	AP N	4140	237,860	25	50	\$ 966,350.00
ORL	AP N	4145	122,500	34	56	\$ 515,530.00
ORL	AP N	4155	337,449	49	61	\$ 567,910.00
ORL	AP N	4158	125,584	6	62	\$ 1,021,110.00
ORL	AP N	4165	27,156	7	53	\$ 166,770.00
ORL	AP N	4166	22,635	89	89	\$ -
ORL	AP N	4167	28,916	12	53	\$ 129,280.00
ORL	AP N	4168	24,538	0	100	\$ 739,190.00
ORL	AP N	4169	72,939	86	90	\$ 1,250.00
ORL	AP N	4170	84,878	67	83	\$ 38,340.00
ORL	AP N	4175	42,594	76	84	\$ 8,960.00
ORL	AP NE	4305	52,643	23	53	\$ 188,380.00
ORL	AP NE	4312	8,541	59	76	\$ 7,040.00
ORL	AP NE	4315	24,518	77	89	\$ 2,500.00
ORL	AP NE	4320	53,040	77	88	\$ 6,230.00
ORL	AP RU	5110	25,880	75	80	\$ 720.00
ORL	AP RU	5115	36,282	74	79	\$ 2,040.00
ORL	AP RU	5120	41,840	75	80	\$ 1,160.00
ORL	AP W	4605	34,600	64	83	\$ 19,330.00
ORL	AP W	4610	260,825	45	58	\$ 200,180.00
ORL	AP W	4640	157,964	100	100	\$ -
ORL	AP W	4645	24,864	100	100	\$ -
ORL	AP W	4650	115,747	50	61	\$ 70,830.00
ORL	AP W	4665	8,833	100	100	\$ -
ORL	AP W	4670	10,856	58	63	\$ 5,980.00
ORL	AP W	4675	1,760	100	100	\$ -
ORL	AP W SEGM	4805	129,830	67	75	\$ 47,380.00
ORL	AP W SEGM	4810	79,530	77	81	\$ 8,730.00
ORL	RW 13-31	6205	445,836	66	73	\$ 71,900.00



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
ORL	RW 7-25	6105	600,500	63	71	\$ 101,850.00
ORL	RW 7-25	6110	300,250	64	74	\$ 98,590.00
ORL	TW A	104	11,949	66	71	\$ 820.00
ORL	TW A	114	12,579	78	86	\$ 1,140.00
ORL	TW A	115	31,644	56	70	\$ 21,410.00
ORL	TW A	116	11,579	63	75	\$ 6,490.00
ORL	TW A	117	22,912	62	78	\$ 14,410.00
ORL	TW A	118	12,843	94	94	\$ -
ORL	TW A	119	8,568	89	89	\$ -
ORL	TW A	125	257,040	67	72	\$ 12,400.00
ORL	TW A	150	60,358	57	70	\$ 27,010.00
ORL	TW A1	111	15,537	77	92	\$ 2,600.00
ORL	TW A1	112	14,428	57	73	\$ 3,450.00
ORL	TW A2	120	30,935	65	65	\$ 8,960.00
ORL	TW A3	130	56,163	67	73	\$ 10,700.00
ORL	TW A4	140	15,668	63	68	\$ 440.00
ORL	TW A5	405	37,049	65	75	\$ 9,280.00
ORL	TW A5	425	9,443	71	81	\$ 1,440.00
ORL	TW A6	113	26,953	72	75	\$ 220.00
ORL	TW B	102	6,388	48	62	\$ 6,970.00
ORL	TW B	103	57,000	55	66	\$ 9,900.00
ORL	TW B	105	30,470	87	87	\$ -
ORL	TW E	505	78,110	65	77	\$ 44,030.00
ORL	TW E	530	46,191	93	93	\$ -
ORL	TW E	540	21,326	94	94	\$ -
ORL	TW E	545	9,618	88	88	\$ -
ORL	TW E	550	52,982	91	91	\$ -
ORL	TW E1	501	5,073	50	60	\$ 2,330.00
ORL	TW E2	510	9,644	46	57	\$ 6,670.00
ORL	TW E2	512	2,687	61	71	\$ 180.00
ORL	TW E3	417	8,311	29	55	\$ 33,830.00
ORL	TW E3	420	36,384	50	75	\$ 37,500.00
ORL	TW E3	520	9,009	46	63	\$ 7,490.00
ORL	TW E3	522	2,133	48	59	\$ 780.00
ORL	TW E4	1070	130,837	50	67	\$ 155,840.00
ORL	TW E4	1080	8,393	56	70	\$ 5,020.00
ORL	TW E4	1105	6,580	70	82	\$ 1,450.00
ORL	TW E4	1110	20,682	94	94	\$ -
ORL	TW E5	560	5,540	65	86	\$ 4,010.00




Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
ORL	TW E5	565	9,465	94	94	\$ -
ORL	TW E6	805	17,742	67	77	\$ 9,760.00
ORL	TW E6	820	11,139	94	94	\$ -
ORL	TW F	605	54,815	45	58	\$ 79,500.00
ORL	TW G	705	30,099	54	63	\$ 16,560.00
ORL	TW G	710	9,812	55	64	\$ 5,830.00
ORL	TW H	806	62,452	52	68	\$ 41,300.00
ORL	TW K	610	27,266	70	77	\$ 670.00

The following **Table 5.3 (c)** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (c) Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 230,280.00
Stopgap	\$ 8,196,680.00
Planning-Level Localized M&R Needs =	\$ 8,426,960.00

Chapter 6






Chapter 6 – Major Rehabilitation Planning

6.1 Major Rehabilitation


Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1 (a) and 6.1 (b)** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, $PCI \leq \text{Critical PCI}$





Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, $PCI > \text{Critical PCI}$





6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The **Critical PCI** concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

1. Develop a pavement performance model and refine a prediction model for the pavements considered.
2. Select a localized maintenance and repair policy to be used in developing a work plan.
3. Apply the selected localized policy to the pavement sections for a range of PCI.
4. Compute the unit cost per area for each PCI range.
5. Plot the cost versus the PCI.
6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended **Minimum Service-Level PCI** for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	65	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)



6.2 Major Rehabilitation Policy

6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA **AC 150/5320-6F "Airport Pavement Design and Evaluation."** It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following **Tables 6.2.1 (a) and (b)** provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average RL Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete

Rehabilitation Type	Reliever (RL) Airport
AC Restoration <i>Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.</i> PCI = 41 to 65	75% Mill and Overlay P-101 AC Milling (3") P-603 Bituminous Tack P-401 (HMA) (3") 25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (4") <i>Excludes any paved shoulder features.</i>
AC Reconstruction <i>Full-depth asphalt pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (4") <i>Excludes any paved shoulder features.</i>



Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete

Rehabilitation Type	Reliever (RL) Airport
PCC Restoration <i>Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.</i> PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (15") *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction <i>Full-depth rigid pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (6") P-501 Rigid PCC (14")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

The recommendations identified in the Major Rehabilitation Needs consider the **FAA AC 150/5370-10H Standard Specifications for Construction of Airports** when determining the appropriate materials and methods implemented for construction projects, such as pavement rehabilitation, on airports. It should be noted that the **AC 150/5370-10H Standard Specifications for Construction of Airports** was updated in December of 2018. Design-level determination of project specific specifications based on the AC should be developed by the Airport when performing applicable construction projects.



6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 Reliever (RL) Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Flexible Asphalt Concrete Cost Per SF	Rigid Portland Cement Concrete Cost per SF
Restoration	41 to 65	\$ 9.50	\$ 13.50
Reconstruction	0 to 40	\$ 12.50	\$ 20.00

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level



investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.

Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ORL	AP GA	4205	AC	608,614	48	AC Restoration	\$ 6,102,000.00
2020	ORL	AP GA	4230	AC	23,614	60	AC Restoration	\$ 225,000.00
2020	ORL	AP N	4105	AC	200,966	5	AC Reconstruction	\$ 2,513,000.00
2020	ORL	AP N	4125	AC	140,429	4	AC Reconstruction	\$ 1,756,000.00
2020	ORL	AP N	4140	AC	237,860	24	AC Reconstruction	\$ 2,974,000.00
2020	ORL	AP N	4145	AC	122,500	33	AC Reconstruction	\$ 1,532,000.00
2020	ORL	AP N	4155	AC	337,449	48	AC Restoration	\$ 3,384,000.00
2020	ORL	AP N	4158	AAC	125,584	4	AC Reconstruction	\$ 1,570,000.00
2020	ORL	AP N	4165	AC	27,156	6	AC Reconstruction	\$ 340,000.00
2020	ORL	AP N	4167	AC	28,916	11	AC Reconstruction	\$ 362,000.00
2020	ORL	AP N	4168	PCC	24,538	0	PCC Reconstruction	\$ 491,000.00
2020	ORL	AP NE	4305	AC	52,643	22	AC Reconstruction	\$ 659,000.00
2020	ORL	AP NE	4312	AC	8,541	58	AC Restoration	\$ 82,000.00
2020	ORL	AP W	4605	AC	34,600	63	AC Restoration	\$ 329,000.00
2020	ORL	AP W	4610	AC	260,825	44	AC Restoration	\$ 2,940,000.00
2020	ORL	AP W	4650	AC	115,747	49	AC Restoration	\$ 1,125,000.00
2020	ORL	AP W	4670	AC	10,856	57	AC Restoration	\$ 104,000.00
2020	ORL	RW 7-25	6105	AAC	600,500	62	AC Restoration	\$ 5,705,000.00
2020	ORL	RW 7-25	6110	AAC	300,250	63	AC Restoration	\$ 2,853,000.00
2020	ORL	TW A	104	AC	11,949	65	AC Restoration	\$ 114,000.00
2020	ORL	TW A	115	AC	31,644	55	AC Restoration	\$ 301,000.00
2020	ORL	TW A	116	AC	11,579	62	AC Restoration	\$ 111,000.00
2020	ORL	TW A	117	AC	22,912	61	AC Restoration	\$ 218,000.00
2020	ORL	TW A	150	AC	60,358	56	AC Restoration	\$ 574,000.00
2020	ORL	TW A1	112	AAC	14,428	56	AC Restoration	\$ 138,000.00
2020	ORL	TW A2	120	AAC	30,935	64	AC Restoration	\$ 294,000.00
2020	ORL	TW A4	140	AC	15,668	62	AC Restoration	\$ 149,000.00
2020	ORL	TW A5	405	AAC	37,049	64	AC Restoration	\$ 352,000.00
2020	ORL	TW B	102	AC	6,388	47	AC Restoration	\$ 66,000.00
2020	ORL	TW B	103	AAC	57,000	54	AC Restoration	\$ 542,000.00
2020	ORL	TW E	505	AC	78,110	64	AC Restoration	\$ 743,000.00
2020	ORL	TW E1	501	AC	5,073	49	AC Restoration	\$ 50,000.00
2020	ORL	TW E2	510	AC	9,644	45	AC Restoration	\$ 105,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ORL	TW E2	512	AC	2,687	60	AC Restoration	\$ 26,000.00
2020	ORL	TW E3	417	AC	8,311	28	AC Reconstruction	\$ 104,000.00
2020	ORL	TW E3	420	AC	36,384	49	AC Restoration	\$ 354,000.00
2020	ORL	TW E3	520	AC	9,009	45	AC Restoration	\$ 99,000.00
2020	ORL	TW E3	522	AC	2,133	47	AC Restoration	\$ 22,000.00
2020	ORL	TW E4	1070	AAC	130,837	49	AC Restoration	\$ 1,278,000.00
2020	ORL	TW E4	1080	AAC	8,393	55	AC Restoration	\$ 80,000.00
2020	ORL	TW E5	560	AC	5,540	64	AC Restoration	\$ 53,000.00
2020	ORL	TW F	605	AC	54,815	44	AC Restoration	\$ 613,000.00
2020	ORL	TW G	705	AC	30,099	53	AC Restoration	\$ 286,000.00
2020	ORL	TW G	710	AC	9,812	54	AC Restoration	\$ 94,000.00
2020	ORL	TW H	806	AC	62,452	51	AC Restoration	\$ 594,000.00
2021	ORL	AP N	4170	AC	84,878	64	AC Restoration	\$ 807,000.00
2021	ORL	AP W SEGM	4805	AAC	129,830	63	AC Restoration	\$ 1,234,000.00
2021	ORL	TW E6	805	AC	17,742	64	AC Restoration	\$ 169,000.00
2022	ORL	RW 13-31	6205	AC	445,836	64	AC Restoration	\$ 4,236,000.00
2022	ORL	TW A	125	AAC	257,040	64	AC Restoration	\$ 2,442,000.00
2022	ORL	TW A3	130	AAC	56,163	64	AC Restoration	\$ 534,000.00
2024	ORL	TW E4	1105	AC	6,580	64	AC Restoration	\$ 63,000.00
2024	ORL	TW K	610	AC	27,266	64	AC Restoration	\$ 260,000.00
2025	ORL	AP NE	4315	AAC	24,518	64	AC Restoration	\$ 233,000.00
2025	ORL	AP NE	4320	AAC	53,040	64	AC Restoration	\$ 504,000.00
2025	ORL	AP W SEGM	4810	AAC	79,530	64	AC Restoration	\$ 756,000.00
2025	ORL	TW A6	113	AC	26,953	64	AC Restoration	\$ 257,000.00
2026	ORL	AP RU	5110	AC	25,880	64	AC Restoration	\$ 246,000.00
2026	ORL	AP RU	5115	AC	36,282	63	AC Restoration	\$ 345,000.00
2026	ORL	AP RU	5120	AC	41,840	64	AC Restoration	\$ 398,000.00
2026	ORL	TW A5	425	AAC	9,443	64	AC Restoration	\$ 90,000.00
2027	ORL	AP N	4175	AC	42,594	64	AC Restoration	\$ 405,000.00

**All values have been rounded to the nearest thousand-dollar.*

The following **Figure 6.3.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2020 and 2029. **Figure 6.3.1 (b)** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.

Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year






Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit



Chapter 7





Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and re-inspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2020-2029. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- ▶ Develop a detailed preventive maintenance program for the airport.
- ▶ Further refine and implement the identified 10-year major rehabilitation needs.
- ▶ Maintain detailed records on pavement maintenance, construction, and inspection.
- ▶ Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



7.2 Supporting Documents

001 – Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

002 – Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the **Airport Response Form** provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

003 – Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

004 – Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation**. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.



7.3 Conclusion

The FDOT SAPMP Update Phase 2 2018-2019 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars **150/5380-7B “Airport Pavement Management Program (PMP)”** and **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** FDOT’s implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Appendix A

Airfield Pavement Analysis Tables



Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ORL	GA APRON	AP GA	APRON	4205	1,675	364	608,614	AC	1/1/1984
ORL	GA APRON	AP GA	APRON	4230	1,129	50	23,614	AC	12/25/1999
ORL	NORTH APRON	AP N	APRON	4105	500	370	200,966	AC	1/1/1979
ORL	NORTH APRON	AP N	APRON	4125	400	350	140,429	AC	1/1/1978
ORL	NORTH APRON	AP N	APRON	4140	1,000	200	237,860	AC	1/1/1979
ORL	NORTH APRON	AP N	APRON	4145	700	200	122,500	AC	1/1/1968
ORL	NORTH APRON	AP N	APRON	4155	3,985	200	337,449	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4158	580	215	125,584	AAC	1/1/2002
ORL	NORTH APRON	AP N	APRON	4165	270	100	27,156	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4166	440	50	22,635	AC	9/1/2012
ORL	NORTH APRON	AP N	APRON	4167	450	60	28,916	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4168	500	50	24,538	PCC	1/1/2005
ORL	NORTH APRON	AP N	APRON	4169	400	200	72,939	AC	9/1/2012
ORL	NORTH APRON	AP N	APRON	4170	850	100	84,878	AC	1/1/1984
ORL	NORTH APRON	AP N	APRON	4175	250	165	42,594	AC	1/1/1960
ORL	NE APRON	AP NE	APRON	4305	500	100	52,643	AC	1/1/1984
ORL	NE APRON	AP NE	APRON	4312	450	20	8,541	AC	12/25/1999
ORL	NE APRON	AP NE	APRON	4315	600	40	24,518	AAC	1/1/2007
ORL	NE APRON	AP NE	APRON	4320	1,000	50	53,040	AAC	1/1/2007
ORL	RUN-UP APRONS	AP RU	APRON	5110	233	100	25,880	AC	1/1/2001
ORL	RUN-UP APRONS	AP RU	APRON	5115	255	130	36,282	AC	1/1/2001
ORL	RUN-UP APRONS	AP RU	APRON	5120	420	100	41,840	AC	1/1/2001
ORL	WEST APRON	AP W	APRON	4605	700	50	34,600	AC	1/1/2002
ORL	WEST APRON	AP W	APRON	4610	150	1,700	260,825	AC	1/1/1999
ORL	WEST APRON	AP W	APRON	4640	450	350	157,964	AAC	3/1/2019
ORL	WEST APRON	AP W	APRON	4645	375	65	24,864	AC	12/1/2017
ORL	WEST APRON	AP W	APRON	4650	520	220	115,747	AC	12/1/1998
ORL	WEST APRON	AP W	APRON	4665	150	60	8,833	PCC	6/1/2019
ORL	WEST APRON	AP W	APRON	4670	110	100	10,856	AC	12/1/1998
ORL	WEST APRON	AP W	APRON	4675	44	40	1,760	PCC	3/1/2019
ORL	SE SEGMENT OF WEST APRON	AP W SEGM	APRON	4805	535	245	129,830	AAC	1/1/2001
ORL	SE SEGMENT OF WEST APRON	AP W SEGM	APRON	4810	400	200	79,530	AAC	1/1/2012
ORL	RUNWAY 13-31	RW 13-31	RUNWAY	6205	4,500	100	445,836	AC	1/1/1999
ORL	RUNWAY 7-25	RW 7-25	RUNWAY	6105	6,005	100	600,500	AAC	1/2/2001
ORL	RUNWAY 7-25	RW 7-25	RUNWAY	6110	12,010	25	300,250	AAC	1/2/2001
ORL	TAXIWAY A	TW A	TAXIWAY	104	195	65	11,949	AC	1/1/2001



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ORL	TAXIWAY A	TW A	TAXIWAY	114	200	50	12,579	AC	1/1/1999
ORL	TAXIWAY A	TW A	TAXIWAY	115	870	38	31,644	AC	1/1/1984
ORL	TAXIWAY A	TW A	TAXIWAY	116	60	150	11,579	AC	1/1/1984
ORL	TAXIWAY A	TW A	TAXIWAY	117	390	35	22,912	AC	1/1/1984
ORL	TAXIWAY A	TW A	TAXIWAY	118	208	47	12,843	AAC	10/1/2015
ORL	TAXIWAY A	TW A	TAXIWAY	119	104	78	8,568	AAC	10/1/2015
ORL	TAXIWAY A	TW A	TAXIWAY	125	3,400	75	257,040	AAC	1/1/1997
ORL	TAXIWAY A	TW A	TAXIWAY	150	1,000	50	60,358	AC	1/1/1963
ORL	TAXIWAY A1	TW A1	TAXIWAY	111	200	125	15,537	AAC	1/1/1997
ORL	TAXIWAY A1	TW A1	TAXIWAY	112	190	75	14,428	AAC	1/1/1997
ORL	TAXIWAY A2	TW A2	TAXIWAY	120	387	75	30,935	AAC	1/1/1997
ORL	TAXIWAY A3	TW A3	TAXIWAY	130	600	75	56,163	AAC	1/1/1997
ORL	TAXIWAY A4	TW A4	TAXIWAY	140	397	30	15,668	AC	1/1/1999
ORL	TAXIWAY A5	TW A5	TAXIWAY	405	400	75	37,049	AAC	1/1/1997
ORL	TAXIWAY A5	TW A5	TAXIWAY	425	95	100	9,443	AAC	1/1/1997
ORL	TAXIWAY A6	TW A6	TAXIWAY	113	640	35	26,953	AC	1/1/2001
ORL	TAXIWAY B	TW B	TAXIWAY	102	145	50	6,388	AC	1/1/1991
ORL	TAXIWAY B	TW B	TAXIWAY	103	760	75	57,000	AAC	1/1/1999
ORL	TAXIWAY B	TW B	TAXIWAY	105	435	75	30,470	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	505	1,822	40	78,110	AC	1/1/1983
ORL	TAXIWAY E	TW E	TAXIWAY	530	680	40	46,191	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	540	350	40	21,326	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	545	180	45	9,618	AAC	12/25/2015
ORL	TAXIWAY E	TW E	TAXIWAY	550	1,336	40	52,982	AAC	12/25/2015
ORL	TAXIWAY E1	TW E1	TAXIWAY	501	40	125	5,073	AC	1/1/1977
ORL	TAXIWAY E2	TW E2	TAXIWAY	510	140	40	9,644	AC	1/1/1983
ORL	TAXIWAY E2	TW E2	TAXIWAY	512	75	40	2,687	AC	1/1/1983
ORL	TAXIWAY E3	TW E3	TAXIWAY	417	42	200	8,311	AC	1/1/1977
ORL	TAXIWAY E3	TW E3	TAXIWAY	420	40	900	36,384	AC	1/1/1984
ORL	TAXIWAY E3	TW E3	TAXIWAY	520	225	40	9,009	AC	1/1/1983
ORL	TAXIWAY E3	TW E3	TAXIWAY	522	67	32	2,133	AC	1/1/1983
ORL	TAXIWAY E4	TW E4	TAXIWAY	1070	1,072	75	130,837	AAC	1/1/1977
ORL	TAXIWAY E4	TW E4	TAXIWAY	1080	80	50	8,393	AAC	1/1/1977
ORL	TAXIWAY E4	TW E4	TAXIWAY	1105	175	38	6,580	AC	1/1/1991
ORL	TAXIWAY E4	TW E4	TAXIWAY	1110	70	75	20,682	AAC	12/25/2015
ORL	TAXIWAY E5	TW E5	TAXIWAY	560	115	40	5,540	AC	1/1/1991
ORL	TAXIWAY E5	TW E5	TAXIWAY	565	140	40	9,465	AAC	10/1/2015
ORL	TAXIWAY E6	TW E6	TAXIWAY	805	185	40	17,742	AC	1/1/1984



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
ORL	TAXIWAY E6	TW E6	TAXIWAY	820	145	70	11,139	AC	12/25/2015
ORL	TAXIWAY F	TW F	TAXIWAY	605	1,300	40	54,815	AC	1/1/1984
ORL	TAXIWAY G	TW G	TAXIWAY	705	660	40	30,099	AC	1/1/1984
ORL	TAXIWAY G	TW G	TAXIWAY	710	215	40	9,812	AC	1/1/1988
ORL	TAXIWAY H	TW H	TAXIWAY	806	1,560	40	62,452	AC	1/1/1983
ORL	TAXIWAY K	TW K	TAXIWAY	610	500	50	27,266	AC	1/1/1999



Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
ORL	RUNWAY 7-25	RUNWAY	6105	600,500	63	Fair
ORL	RUNWAY 7-25	RUNWAY	6110	300,250	64	Fair
ORL	RUNWAY 13-31	RUNWAY	6205	445,836	66	Fair
ORL	TAXIWAY A	TAXIWAY	104	11,949	66	Fair
ORL	TAXIWAY A	TAXIWAY	114	12,579	78	Satisfactory
ORL	TAXIWAY A	TAXIWAY	115	31,644	56	Fair
ORL	TAXIWAY A	TAXIWAY	116	11,579	63	Fair
ORL	TAXIWAY A	TAXIWAY	117	22,912	62	Fair
ORL	TAXIWAY A	TAXIWAY	118	12,843	94	Good
ORL	TAXIWAY A	TAXIWAY	119	8,568	89	Good
ORL	TAXIWAY A	TAXIWAY	125	257,040	67	Fair
ORL	TAXIWAY A	TAXIWAY	150	60,358	57	Fair
ORL	TAXIWAY A1	TAXIWAY	111	15,537	77	Satisfactory
ORL	TAXIWAY A1	TAXIWAY	112	14,428	57	Fair
ORL	TAXIWAY A2	TAXIWAY	120	30,935	65	Fair
ORL	TAXIWAY A3	TAXIWAY	130	56,163	67	Fair
ORL	TAXIWAY A4	TAXIWAY	140	15,668	63	Fair
ORL	TAXIWAY A5	TAXIWAY	405	37,049	65	Fair
ORL	TAXIWAY A5	TAXIWAY	425	9,443	71	Satisfactory
ORL	TAXIWAY A6	TAXIWAY	113	26,953	72	Satisfactory
ORL	TAXIWAY B	TAXIWAY	102	6,388	48	Poor
ORL	TAXIWAY B	TAXIWAY	103	57,000	55	Poor
ORL	TAXIWAY B	TAXIWAY	105	30,470	87	Good
ORL	TAXIWAY E	TAXIWAY	505	78,110	65	Fair
ORL	TAXIWAY E	TAXIWAY	530	46,191	93	Good
ORL	TAXIWAY E	TAXIWAY	540	21,326	94	Good
ORL	TAXIWAY E	TAXIWAY	545	9,618	88	Good
ORL	TAXIWAY E	TAXIWAY	550	52,982	91	Good
ORL	TAXIWAY E1	TAXIWAY	501	5,073	50	Poor
ORL	TAXIWAY E2	TAXIWAY	510	9,644	46	Poor
ORL	TAXIWAY E2	TAXIWAY	512	2,687	61	Fair
ORL	TAXIWAY E3	TAXIWAY	417	8,311	29	Very Poor
ORL	TAXIWAY E3	TAXIWAY	420	36,384	50	Poor
ORL	TAXIWAY E3	TAXIWAY	520	9,009	46	Poor
ORL	TAXIWAY E3	TAXIWAY	522	2,133	48	Poor
ORL	TAXIWAY E4	TAXIWAY	1070	130,837	50	Poor
ORL	TAXIWAY E4	TAXIWAY	1080	8,393	56	Fair
ORL	TAXIWAY E4	TAXIWAY	1105	6,580	70	Fair



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
ORL	TAXIWAY E4	TAXIWAY	1110	20,682	94	Good
ORL	TAXIWAY E5	TAXIWAY	560	5,540	65	Fair
ORL	TAXIWAY E5	TAXIWAY	565	9,465	94	Good
ORL	TAXIWAY E6	TAXIWAY	805	17,742	67	Fair
ORL	TAXIWAY E6	TAXIWAY	820	11,139	94	Good
ORL	TAXIWAY F	TAXIWAY	605	54,815	45	Poor
ORL	TAXIWAY G	TAXIWAY	705	30,099	54	Poor
ORL	TAXIWAY G	TAXIWAY	710	9,812	55	Poor
ORL	TAXIWAY H	TAXIWAY	806	62,452	52	Poor
ORL	TAXIWAY K	TAXIWAY	610	27,266	70	Fair
ORL	NORTH APRON	APRON	4105	200,966	6	Failed
ORL	NORTH APRON	APRON	4125	140,429	5	Failed
ORL	NORTH APRON	APRON	4140	237,860	25	Serious
ORL	NORTH APRON	APRON	4145	122,500	34	Very Poor
ORL	NORTH APRON	APRON	4155	337,449	49	Poor
ORL	NORTH APRON	APRON	4158	125,584	6	Failed
ORL	NORTH APRON	APRON	4165	27,156	7	Failed
ORL	NORTH APRON	APRON	4166	22,635	89	Good
ORL	NORTH APRON	APRON	4167	28,916	12	Serious
ORL	NORTH APRON	APRON	4168	24,538	0	Failed
ORL	NORTH APRON	APRON	4169	72,939	86	Good
ORL	NORTH APRON	APRON	4170	84,878	67	Fair
ORL	NORTH APRON	APRON	4175	42,594	76	Satisfactory
ORL	GA APRON	APRON	4205	608,614	49	Poor
ORL	GA APRON	APRON	4230	23,614	61	Fair
ORL	NE APRON	APRON	4305	52,643	23	Serious
ORL	NE APRON	APRON	4312	8,541	59	Fair
ORL	NE APRON	APRON	4315	24,518	77	Satisfactory
ORL	NE APRON	APRON	4320	53,040	77	Satisfactory
ORL	WEST APRON	APRON	4605	34,600	64	Fair
ORL	WEST APRON	APRON	4610	260,825	45	Poor
ORL	WEST APRON	APRON	4640	157,964	100	Good
ORL	WEST APRON	APRON	4645	24,864	100	Good
ORL	WEST APRON	APRON	4650	115,747	50	Poor
ORL	WEST APRON	APRON	4665	8,833	100	Good
ORL	WEST APRON	APRON	4670	10,856	58	Fair
ORL	WEST APRON	APRON	4675	1,760	100	Good
ORL	SE SEGMENT OF WEST APRON	APRON	4805	129,830	67	Fair
ORL	SE SEGMENT OF WEST APRON	APRON	4810	79,530	77	Satisfactory



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
ORL	RUN-UP APRONS	APRON	5110	25,880	75	Satisfactory
ORL	RUN-UP APRONS	APRON	5115	36,282	74	Satisfactory
ORL	RUN-UP APRONS	APRON	5120	41,840	75	Satisfactory



Table A-3 Forecasted PCI 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	AP GA	4205	49	48	47	46	45	44	43	41	40	39	38
ORL	AP GA	4230	61	60	59	58	57	56	56	55	54	54	53
ORL	AP N	4105	6	5	5	5	4	4	3	3	3	2	2
ORL	AP N	4125	5	4	4	4	3	3	2	2	2	1	1
ORL	AP N	4140	25	24	24	24	23	23	22	22	22	21	21
ORL	AP N	4145	34	33	32	31	30	30	29	29	29	28	28
ORL	AP N	4155	49	48	47	46	45	44	43	41	40	39	38
ORL	AP N	4158	6	4	2	0	0	0	0	0	0	0	0
ORL	AP N	4165	7	6	6	6	5	5	4	4	4	3	3
ORL	AP N	4166	89	87	84	82	80	78	76	74	72	71	69
ORL	AP N	4167	12	11	11	11	10	10	9	9	9	8	8
ORL	AP N	4168	0	0	0	0	0	0	0	0	0	0	0
ORL	AP N	4169	86	84	82	79	77	75	74	72	70	69	67
ORL	AP N	4170	67	65	64	63	62	61	60	59	58	57	57
ORL	AP N	4175	76	74	72	71	69	67	66	65	64	62	61
ORL	AP NE	4305	23	22	22	22	21	21	20	20	20	19	19
ORL	AP NE	4312	59	58	57	56	56	55	54	53	53	52	51
ORL	AP NE	4315	77	75	73	70	68	66	64	62	60	57	55
ORL	AP NE	4320	77	75	73	70	68	66	64	62	60	57	55
ORL	AP RU	5110	75	73	71	70	68	67	65	64	63	62	61
ORL	AP RU	5115	74	72	70	69	67	66	65	63	62	61	60
ORL	AP RU	5120	75	73	71	70	68	67	65	64	63	62	61
ORL	AP W	4605	64	63	62	61	60	59	58	57	56	56	55
ORL	AP W	4610	45	44	42	41	40	39	38	37	35	34	33
ORL	AP W	4640	100	98	96	93	91	89	87	85	82	80	78
ORL	AP W	4645	100	95	93	91	88	86	84	82	80	78	75
ORL	AP W	4650	50	49	48	47	46	45	44	43	42	40	39
ORL	AP W	4665	100	99	97	96	95	94	92	91	90	89	87
ORL	AP W	4670	58	57	56	55	55	54	53	53	52	51	50
ORL	AP W	4675	100	98	97	96	95	93	92	91	90	88	87
ORL	AP W SEGM	4805	67	65	63	60	58	56	54	52	50	47	45
ORL	AP W SEGM	4810	77	75	73	70	68	66	64	62	60	57	55
ORL	RW 13-31	6205	66	65	65	64	63	63	62	61	60	58	57
ORL	RW 7-25	6105	63	62	61	61	60	59	59	58	57	57	56
ORL	RW 7-25	6110	64	63	62	61	61	60	59	59	58	57	57
ORL	TW A	104	66	65	63	62	61	60	59	58	57	56	55
ORL	TW A	114	78	76	75	74	72	71	70	68	67	66	65



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	TW A	115	56	55	54	53	52	51	50	49	48	47	47
ORL	TW A	116	63	62	60	59	58	57	56	55	54	53	52
ORL	TW A	117	62	61	59	58	57	56	55	54	53	52	51
ORL	TW A	118	94	92	90	88	86	84	82	80	79	77	76
ORL	TW A	119	89	87	85	83	81	80	78	77	75	74	73
ORL	TW A	125	67	66	65	64	63	62	61	61	60	59	58
ORL	TW A	150	57	56	55	54	53	52	51	50	49	48	47
ORL	TW A1	111	77	75	74	73	72	70	69	68	67	66	65
ORL	TW A1	112	57	56	55	54	53	52	51	50	49	48	47
ORL	TW A2	120	65	64	63	62	61	60	60	59	58	57	56
ORL	TW A3	130	67	66	65	64	63	62	61	61	60	59	58
ORL	TW A4	140	63	62	60	59	58	57	56	55	54	53	52
ORL	TW A5	405	65	64	63	62	61	60	60	59	58	57	56
ORL	TW A5	425	71	70	69	67	66	66	65	64	63	62	61
ORL	TW A6	113	72	70	69	68	67	65	64	63	62	61	60
ORL	TW B	102	48	47	46	45	45	44	43	42	42	41	41
ORL	TW B	103	55	54	53	52	51	50	49	48	47	46	44
ORL	TW B	105	87	85	83	81	80	78	77	75	74	73	72
ORL	TW E	505	65	64	62	61	60	59	58	57	56	55	54
ORL	TW E	530	93	91	89	87	85	83	81	80	78	77	75
ORL	TW E	540	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E	545	88	86	84	82	81	79	78	76	75	73	72
ORL	TW E	550	91	89	87	85	83	81	80	78	77	75	74
ORL	TW E1	501	50	49	48	47	46	46	45	44	43	43	42
ORL	TW E2	510	46	45	44	43	43	42	42	41	40	40	39
ORL	TW E2	512	61	60	58	57	56	55	54	53	52	52	51
ORL	TW E3	417	29	28	28	28	28	28	28	28	28	28	28
ORL	TW E3	420	50	49	48	47	46	46	45	44	43	43	42
ORL	TW E3	520	46	45	44	43	43	42	42	41	40	40	39
ORL	TW E3	522	48	47	46	45	45	44	43	42	42	41	41
ORL	TW E4	1070	50	49	48	46	45	44	43	41	40	38	36
ORL	TW E4	1080	56	55	54	53	52	51	50	49	48	47	46
ORL	TW E4	1105	70	68	67	66	65	64	62	61	60	59	58
ORL	TW E4	1110	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E5	560	65	64	62	61	60	59	58	57	56	55	54
ORL	TW E5	565	94	92	90	88	86	84	82	80	79	77	76
ORL	TW E6	805	67	65	64	63	62	61	60	59	58	56	55
ORL	TW E6	820	94	92	90	89	87	86	84	83	81	80	78



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
ORL	TW F	605	45	44	43	43	42	41	41	40	40	39	39
ORL	TW G	705	54	53	52	51	50	49	48	47	47	46	45
ORL	TW G	710	55	54	53	52	51	50	49	48	47	47	46
ORL	TW H	806	52	51	50	49	48	47	47	46	45	44	44
ORL	TW K	610	70	68	67	66	65	64	62	61	60	59	58

9/19/2019

Work History Report

Page 1 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: AP GA	GA APRON		Section: 4205	Surface: AC
L.C.D. 1/1/1984	Use: APRON	Rank: P	Length: 1,675.00 (Ft)	Width: 364.00 (Ft)	True Area: 608614.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
4/1/2007	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	1984 4" P401 AC SURFACE ON 6" P211 BASE ON 16" P152 SUBBASE
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP GA	GA APRON		Section: 4230	Surface: AC
L.C.D. 12/25/199	Use: APRON	Rank: P	Length: 1,129.00 (Ft)	Width: 50.00 (Ft)	True Area: 23614.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
4/1/2007	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4105	Surface: AC
L.C.D. 1/1/1979	Use: APRON	Rank: T	Length: 500.00 (Ft)	Width: 370.00 (Ft)	True Area: 200966.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLURRY SEAL
1/1/1979	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1979 2" P-401 8" P-211

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4125	Surface: AC
L.C.D. 1/1/1978	Use: APRON	Rank: P	Length: 400.00 (Ft)	Width: 350.00 (Ft)	True Area: 140429.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLURRY SEAL
1/1/1978	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1978 3" P-401 8" P-211

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4140	Surface: AC
L.C.D. 1/1/1979	Use: APRON	Rank: P	Length: 1,000.00 (Ft)	Width: 200.00 (Ft)	True Area: 237860.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLURRY SEAL
1/1/1979	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1979 2" P-401 8" P-211

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4145	Surface: AC
L.C.D. 1/1/1968	Use: APRON	Rank: P	Length: 700.00 (Ft)	Width: 200.00 (Ft)	True Area: 122500.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLURRY SEAL
1/1/1968	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1968 1.5" P-401 7" P-211

9/19/2019

Work History Report

Page 2 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4155	Surface: AC
L.C.D. 1/1/1984	Use: APRON	Rank: P	Length: 3,985.00 (Ft)	Width: 200.00 (Ft)	True Area: 337449.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/1984	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1984 SLURRY SEAL 2" P-401 6" P-211

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4158	Surface: AAC
L.C.D. 1/1/2002	Use: APRON	Rank: P	Length: 580.00 (Ft)	Width: 215.00 (Ft)	True Area: 125584.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/2002	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1984	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4165	Surface: AC
L.C.D. 1/1/1984	Use: APRON	Rank: P	Length: 270.00 (Ft)	Width: 100.00 (Ft)	True Area: 27156.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/1984	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1984 SLURRY SEAL EST 1984 BIT

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4166	Surface: AC
L.C.D. 9/1/2012	Use: APRON	Rank: P	Length: 440.00 (Ft)	Width: 50.00 (Ft)	True Area: 22635.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2012	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	SEPT 2012 COMPLETED - RECONS
1/1/1984	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1984 SLURRY SEAL EST 1984 BIT

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4167	Surface: AC
L.C.D. 1/1/1984	Use: APRON	Rank: P	Length: 450.00 (Ft)	Width: 60.00 (Ft)	True Area: 28916.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/1984	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4168	Surface: PCC
L.C.D. 1/1/2005	Use: APRON	Rank: P	Length: 500.00 (Ft)	Width: 50.00 (Ft)	True Area: 24538.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	(BLDG REMOVED) FOOTING FOU

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4169	Surface: AC
L.C.D. 9/1/2012	Use: APRON	Rank: P	Length: 400.00 (Ft)	Width: 200.00 (Ft)	True Area: 72939.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
9/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	(OLD GRASS AREA) SEPT. 2012 C

9/19/2019

Work History Report

Page 3 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4170	Surface: AC
L.C.D. 1/1/1984	Use: APRON	Rank: P	Length: 850.00 (Ft)	Width: 100.00 (Ft)	True Area: 84878.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/1984	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP N	NORTH APRON		Section: 4175	Surface: AC
L.C.D. 1/1/1960	Use: APRON	Rank: P	Length: 250.00 (Ft)	Width: 165.00 (Ft)	True Area: 42594.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
8/1/2012	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EAST SIDE OF NORTH RAMP WAS
1/1/1960	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1960 BIT

Network: ORLANDO EXECUT		Branch: AP NE	NE APRON		Section: 4305	Surface: AC
L.C.D. 1/1/1984	Use: APRON	Rank: P	Length: 500.00 (Ft)	Width: 100.00 (Ft)	True Area: 52643.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1984 BIT

Network: ORLANDO EXECUT		Branch: AP NE	NE APRON		Section: 4312	Surface: AC
L.C.D. 12/25/199	Use: APRON	Rank: P	Length: 450.00 (Ft)	Width: 20.00 (Ft)	True Area: 8541.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP NE	NE APRON		Section: 4315	Surface: AAC
L.C.D. 1/1/2007	Use: APRON	Rank: P	Length: 600.00 (Ft)	Width: 40.00 (Ft)	True Area: 24518.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP NE	NE APRON		Section: 4320	Surface: AAC
L.C.D. 1/1/2007	Use: APRON	Rank: P	Length: 1,000.00 (Ft)	Width: 50.00 (Ft)	True Area: 53040.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1984	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: AP RU	RUN-UP APRON		Section: 5110	Surface: AC
L.C.D. 1/1/2001	Use: APRON	Rank: P	Length: 233.00 (Ft)	Width: 100.00 (Ft)	True Area: 25880.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2001	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/ 6" P-154

9/19/2019

Work History Report

Page 4 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: AP RU		RUN-UP APRON		Section: 5115	Surface: AC
L.C.D. 1/1/2001	Use: APRON	Rank: P	Length: 255.00 (Ft)	Width: 130.00 (Ft)	True Area: 36282.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2001	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/ 6" P-154	

Network: ORLANDO EXECUT		Branch: AP RU		RUN-UP APRON		Section: 5120	Surface: AC
L.C.D. 1/1/2001	Use: APRON	Rank: P	Length: 420.00 (Ft)	Width: 100.00 (Ft)	True Area: 41840.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2001	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/ 6" P-154	

Network: ORLANDO EXECUT		Branch: AP W SEGM SE SEGMENT OF		Section: 4805		Surface: AAC	
L.C.D. 1/1/2001		Use: APRON	Rank: P	Length: 535.00 (Ft)	Width: 245.00 (Ft)	True Area: 129830.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	4" AC/6" P-211/6" P-154	
1/1/2001	SR-AC	Surface Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>		
1/1/1960	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: ORLANDO EXECUT		Branch: AP W SEGM SE SEGMENT OF		Section: 4810		Surface: AAC	
L.C.D. 1/1/2012		Use: APRON	Rank: P	Length: 400.00 (Ft)	Width: 200.00 (Ft)	True Area: 79530.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2012	ML-OL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	EST 1960 AC OVERLAY OF 1940s PCC PAVEMENT IS SCHEDULED FOR REHABILITATION	
1/1/1960	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1960	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

Network: ORLANDO EXECUT		Branch: AP W		WEST APRON		Section: 4605	Surface: AC
L.C.D. 1/1/2002	Use: APRON	Rank: P	Length: 700.00 (Ft)	Width: 50.00 (Ft)	True Area: 34600.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	4" AC/6" P-211/6" P-154 ESTIMATE 1942 AC PAVEMENT NO HISTORY KNOWN FOR THIS SECTION. IT IS PLANNED FOR RE	
1/1/2002	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

Network: ORLANDO EXECUT		Branch: AP W		WEST APRON		Section: 4610	Surface: AC
L.C.D. 1/1/1999	Use: APRON	Rank: P	Length: 150.00 (Ft)	Width: 1700.00 (Ft)	True Area: 260825.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1999 RECONSTRUCTION OR OVERLAY PLANNED	
1/1/1999	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		

9/19/2019

Work History Report

Page 5 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT Branch: AP W WEST APRON Section: 4640 Surface: AAC
 L.C.D. 3/1/2019 Use: APRON Rank: P Length: 450.00 (Ft) Width: 350.00 (Ft) True Area: 157964.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
3/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401 HMA OVERLAY ON PREP
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
12/1/1998	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/6" P-154
1/1/1997	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC SURFACE ON 10" P211 BASE ON 6" P154 SUBBASE

Network: ORLANDO EXECUT Branch: AP W WEST APRON Section: 4645 Surface: AC
 L.C.D. 12/1/2017 Use: APRON Rank: P Length: 375.00 (Ft) Width: 65.00 (Ft) True Area: 24864.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/1/2017	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT Branch: AP W WEST APRON Section: 4650 Surface: AC
 L.C.D. 12/1/1998 Use: APRON Rank: P Length: 520.00 (Ft) Width: 220.00 (Ft) True Area: 115747.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
12/1/1998	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/6" P-154
1/2/1997	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	OLD PCC PAVEMENT
1/1/1997	NC-PC	New Construction - PCC	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC OVERLAY

Network: ORLANDO EXECUT Branch: AP W WEST APRON Section: 4665 Surface: PCC
 L.C.D. 6/1/2019 Use: APRON Rank: P Length: 150.00 (Ft) Width: 60.00 (Ft) True Area: 8833.000002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2019	CR-PC	Complete Reconstruction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1997	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT Branch: AP W WEST APRON Section: 4670 Surface: AC
 L.C.D. 12/1/1998 Use: APRON Rank: P Length: 110.00 (Ft) Width: 100.00 (Ft) True Area: 10856.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
12/1/1998	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/6" P-154
1/1/1997	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC SURFACE ON 10" P211 BASE ON 6" P154 SUBBASE

Network: ORLANDO EXECUT Branch: AP W WEST APRON Section: 4675 Surface: PCC
 L.C.D. 3/1/2019 Use: APRON Rank: P Length: 44.00 (Ft) Width: 40.00 (Ft) True Area: 1760.000000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
3/1/2019	CR-PC	Complete Reconstruction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
12/1/1998	SR-AC	Surface Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/6" P-154
1/1/1997	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC SURFACE ON 10" P211 BASE ON 6" P154 SUBBASE

9/19/2019

Work History Report

Page 6 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: RW 13-31	RUNWAY 13-31	Section: 6205	Surface:AC	
L.C.D. 1/1/1999	Use: RUNWAY	Rank: P	Length: 4,500.00 (Ft)	Width: 100.00 (Ft)	True Area: 445836.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1999	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1999 RESURFACING PLANNED

Network: ORLANDO EXECUT

Branch: RW 7-25

RUNWAY 7-25

Section: 6105

Surface: AAC

L.C.D. 1/2/2001

Use: RUNWAY

Rank: T

Length: 6,005.00 (Ft)

Width: 100.00 (Ft)

True Area: 600500.0001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/2/2001	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1.5 - 3"
1/1/2001	MI-CO	Cold Milling	0.00	0.00	<input type="checkbox"/>	3" MAX
1/1/1977	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	UNKNOWN DATE 2" P401 AC SURFACE ON 8" P211 BASE

Network: ORLANDO EXECUT		Branch: RW 7-25	RUNWAY 7-25	Section: 6110	Surface: AAC	
L.C.D. 1/2/2001	Use: RUNWAY	Rank: P	Length: 12,010.00 (Ft)	Width: 25.00 (Ft)	True Area: 300250.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/2/2001	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1.5-3"
1/1/2001	MI-CO	Cold Milling	0.00	0.00	<input type="checkbox"/>	3" MAX
1/1/1977	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1977 1.5-3" P-401 O ON 2" P-401 8" P-211

Network: ORLANDO EXECUT		Branch: TW A	TAXIWAY A	Section: 104	Surface:AC	
L.C.D. 1/1/2001	Use: TAXIWAY	Rank: P	Length: 195.00 (Ft)	Width: 65.00 (Ft)	True Area: 11949.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2001	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/6" P-154

Network: ORLANDO EXECUT		Branch: TW A1	TAXIWAY A1	Section: 111	Surface: AAC	
L.C.D. 1/1/1997	Use: TAXIWAY	Rank: P	Length: 200.00 (Ft)	Width: 125.00 (Ft)	True Area: 15537.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1997	OL-AS	Overlay - AC Structural	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC OVERLAY
1/1/1960	NU-IN	New Construction - Initial	0.00	3.00	<input checked="" type="checkbox"/>	1960: 3" P401 AC SURFACE ON 10-

Network: ORLANDO EXECUT		Branch: TW A1	TAXIWAY A1	Section: 112	Surface: AAC	
L.C.D. 1/1/1997	Use: TAXIWAY	Rank: P	Length: 190.00 (Ft)	Width: 75.00 (Ft)	True Area: 14428.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1997	OL-AS	Overlay - AC Structural	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC OVERLAY
1/1/1960	NU-IN	New Construction - Initial	0.00	3.00	<input checked="" type="checkbox"/>	1960: 3" P401 AC SURFACE ON 10-

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 114		Surface: AC			
L.C.D. 1/1/1999		Use: TAXIWAY		Rank: P		Length: 200.00 (Ft)		Width: 50.00 (Ft)		True Area: 12579.00000 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments				
1/1/1999	IMPORT ED	BUILT		0.00	0.00	<input checked="" type="checkbox"/>	1999 RESURFACING OR RECONSTRUCTION PLANNED				

9/19/2019

Work History Report

Page 7 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 115	Surface: AC
L.C.D. 1/1/1984		Use: TAXIWAY		Rank: P	Length: 870.00 (Ft)	Width: 38.00 (Ft)	True Area: 31644.00000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P-401 8" P-211	

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 116	Surface: AC
L.C.D. 1/1/1984		Use: TAXIWAY		Rank: P	Length: 60.00 (Ft)	Width: 150.00 (Ft)	True Area: 11579.00000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P-401 8" P-211	

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 117	Surface: AC
L.C.D. 1/1/1984		Use: TAXIWAY		Rank: P	Length: 390.00 (Ft)	Width: 35.00 (Ft)	True Area: 22912.00000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P-401 8" P-211	

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 118	Surface: AAC
L.C.D. 10/1/2015		Use: TAXIWAY		Rank: P	Length: 208.00 (Ft)	Width: 47.00 (Ft)	True Area: 12843.00000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
10/1/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Mill 2" Overlay 2.5" P-401SP	
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P-401 8" P-211	

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 119	Surface: AAC
L.C.D. 10/1/2015		Use: TAXIWAY		Rank: P	Length: 104.00 (Ft)	Width: 78.00 (Ft)	True Area: 8568.000002 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
10/1/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill and 2.5" P-401SP Overlay	
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P-401 8" P-211	

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 125	Surface: AAC
L.C.D. 1/1/1997		Use: TAXIWAY		Rank: P	Length: 3,400.00 (Ft)	Width: 75.00 (Ft)	True Area: 257040.0000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC OVERLAY	
1/1/1960	NU-IN	New Construction - Initial	0.00	3.00	<input checked="" type="checkbox"/>	1960: 3" P401 AC SURFACE ON 10-	

Network: ORLANDO EXECUT		Branch: TW A		TAXIWAY A		Section: 150	Surface: AC
L.C.D. 1/1/1963		Use: TAXIWAY		Rank: P	Length: 1,000.00 (Ft)	Width: 50.00 (Ft)	True Area: 60358.00001 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
4/1/2007	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00	<input type="checkbox"/>		
1/1/1963	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1963 2" P-401 8" P-211	

9/19/2019

Work History Report

Page 8 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: TW A2		TAXIWAY A2		Section: 120	Surface: AAC
L.C.D. 1/1/1997		Use: TAXIWAY	Rank: P	Length: 387.00 (Ft)	Width: 75.00 (Ft)	True Area: 30935.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC OVERLAY	
1/1/1960	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1960 3" P401 AC SURFACE ON 10-18" P211 BASE	

Network: ORLANDO EXECUT		Branch: TW A3		TAXIWAY A3		Section: 130	Surface: AAC
L.C.D. 1/1/1997		Use: TAXIWAY	Rank: P	Length: 600.00 (Ft)	Width: 75.00 (Ft)	True Area: 56163.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1997 2" P401 AC OVERLAY	
1/1/1960	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1960 3" P401 AC PAVEMENT ON 10-18" P211 BASE	

Network: ORLANDO EXECUT		Branch: TW A4		TAXIWAY A4		Section: 140	Surface: AC
L.C.D. 1/1/1999		Use: TAXIWAY	Rank: P	Length: 397.00 (Ft)	Width: 30.00 (Ft)	True Area: 15668.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1999	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/8" P-211/6" P-154	

Network: ORLANDO EXECUT		Branch: TW A5		TAXIWAY A5		Section: 405	Surface: AAC
L.C.D. 1/1/1997		Use: TAXIWAY	Rank: P	Length: 400.00 (Ft)	Width: 75.00 (Ft)	True Area: 37049.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1997 AC OVERLAY	
1/1/1960	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	EST 1960 AC PAVEMENT SECTION UNKNOWN	

Network: ORLANDO EXECUT		Branch: TW A5		TAXIWAY A5		Section: 425	Surface: AAC
L.C.D. 1/1/1997		Use: TAXIWAY	Rank: P	Length: 95.00 (Ft)	Width: 100.00 (Ft)	True Area: 9443.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1997	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1997 TAPERED AC OVERLAY	
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P401 AC SURFACE ON 6" P211 BASE ON 16" P152 SUBBASE	

Network: ORLANDO EXECUT		Branch: TW A6		TAXIWAY A6		Section: 113	Surface: AC
L.C.D. 1/1/2001		Use: TAXIWAY	Rank: P	Length: 640.00 (Ft)	Width: 35.00 (Ft)	True Area: 26953.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2001	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/6" P-211/6" P-154	

9/19/2019

Work History Report

Page 9 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: TW B		TAXIWAY B		Section: 102	Surface: AC
L.C.D. 1/1/1991		Use: TAXIWAY	Rank: P	Length: 145.00 (Ft)	Width: 50.00 (Ft)	True Area: 6388.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2003	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1991 4" P401 AC SURFACE ON 6" P211 BASE ON 6" P154 SUBBASE	
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>		

Network: ORLANDO EXECUT		Branch: TW B		TAXIWAY B		Section: 103	Surface: AAC
L.C.D. 1/1/1999		Use: TAXIWAY	Rank: P	Length: 760.00 (Ft)	Width: 75.00 (Ft)	True Area: 57000.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1999	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1999 RESURFACING OR RECONSTRUCTION PLANNED 1991 4" P401 AC SURFACE ON 6" P211 BASE ON 6" P154 SUBBASE	
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>		

Network: ORLANDO EXECUT		Branch: TW B		TAXIWAY B		Section: 105	Surface: AAC
L.C.D. 12/25/201		Use: TAXIWAY	Rank: P	Length: 435.00 (Ft)	Width: 75.00 (Ft)	True Area: 30470.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/25/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2" MILL and VAR. DEPTH P-401SP 1997 2" P401 AC OVERLAY	
1/1/1997	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1960	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1960 3" P401 AC SURFACE ON 10-18" P211 BASE	

Network: ORLANDO EXECUT		Branch: TW E1		TAXIWAY E1		Section: 501	Surface: AC
L.C.D. 1/1/1977		Use: TAXIWAY	Rank: T	Length: 40.00 (Ft)	Width: 125.00 (Ft)	True Area: 5073.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1977	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1977 AC PAVEMENT	

Network: ORLANDO EXECUT		Branch: TW E2		TAXIWAY E2		Section: 510	Surface: AC
L.C.D. 1/1/1983		Use: TAXIWAY	Rank: P	Length: 140.00 (Ft)	Width: 40.00 (Ft)	True Area: 9644.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" P-401 7" P-211	

Network: ORLANDO EXECUT		Branch: TW E2		TAXIWAY E2		Section: 512	Surface: AC
L.C.D. 1/1/1983		Use: TAXIWAY	Rank: P	Length: 75.00 (Ft)	Width: 40.00 (Ft)	True Area: 2687.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1983	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

9/19/2019

Work History Report

Page 10 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: TW E3		TAXIWAY E3		Section: 417	Surface: AC
L.C.D. 1/1/1977		Use: TAXIWAY	Rank: P	Length: 42.00 (Ft)	Width: 200.00 (Ft)	True Area: 8311.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1977	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1977 AC PAVEMENT	

Network: ORLANDO EXECUT		Branch: TW E3		TAXIWAY E3		Section: 420	Surface: AC
L.C.D. 1/1/1984		Use: TAXIWAY	Rank: P	Length: 40.00 (Ft)	Width: 900.00 (Ft)	True Area: 36384.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1984 2" P-401 6" P-211	

Network: ORLANDO EXECUT		Branch: TW E3		TAXIWAY E3		Section: 520	Surface: AC
L.C.D. 1/1/1983		Use: TAXIWAY	Rank: P	Length: 225.00 (Ft)	Width: 40.00 (Ft)	True Area: 9009.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" P-401 7" P-211	

Network: ORLANDO EXECUT		Branch: TW E3		TAXIWAY E3		Section: 522	Surface: AC
L.C.D. 1/1/1983		Use: TAXIWAY	Rank: P	Length: 67.00 (Ft)	Width: 32.00 (Ft)	True Area: 2133.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1983	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: ORLANDO EXECUT		Branch: TW E4		TAXIWAY E4		Section: 1070	Surface: AAC
L.C.D. 1/1/1977		Use: TAXIWAY	Rank: P	Length: 1,072.00 (Ft)	Width: 75.00 (Ft)	True Area: 130837.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1977	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1977 4" P401 AC OVERLAY	
1/1/1977	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	UNKNOWN DATE 2" P401 AC ON 6" P211 BASE	

Network: ORLANDO EXECUT		Branch: TW E4		TAXIWAY E4		Section: 1080	Surface: AAC
L.C.D. 1/1/1977		Use: TAXIWAY	Rank: P	Length: 80.00 (Ft)	Width: 50.00 (Ft)	True Area: 8393.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1977	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1977 4" P401 AC OVERLAY	
1/1/1977	IMPORT ED	OVERLAY	0.00	6.00	<input checked="" type="checkbox"/>	UNKNOWN DATE 2' P401 SURFACE ON 6" P211 BASE	

Network: ORLANDO EXECUT		Branch: TW E4		TAXIWAY E4		Section: 1105	Surface: AC
L.C.D. 1/1/1991		Use: TAXIWAY	Rank: T	Length: 175.00 (Ft)	Width: 38.00 (Ft)	True Area: 6580.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" BASE	

9/19/2019

Work History Report

Page 11 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: TW E4		TAXIWAY E4		Section: 1110	Surface: AAC
L.C.D. 12/25/201		Use: TAXIWAY		Rank: T	Length: 70.00 (Ft)	Width: 75.00 (Ft)	True Area: 20682.00000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/25/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2015: 2" MILL AND OVERLAY	
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" BASE	

Network: ORLANDO EXECUT		Branch: TW E		TAXIWAY E		Section: 505	Surface: AC
L.C.D. 1/1/1983		Use: TAXIWAY		Rank: P	Length: 1,822.00 (Ft)	Width: 40.00 (Ft)	True Area: 78110.00002 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" P-401 7" P-211	

Network: ORLANDO EXECUT		Branch: TW E		TAXIWAY E		Section: 530	Surface: AAC
L.C.D. 12/25/201		Use: TAXIWAY		Rank: P	Length: 680.00 (Ft)	Width: 40.00 (Ft)	True Area: 46191.00001 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/25/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2015: 2" MILL AND OVERLAY	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" P-401 7" P-211	

Network: ORLANDO EXECUT		Branch: TW E		TAXIWAY E		Section: 540	Surface: AAC
L.C.D. 12/25/201		Use: TAXIWAY		Rank: P	Length: 350.00 (Ft)	Width: 40.00 (Ft)	True Area: 21326.00000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/25/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2015: 2" MILL AND OVERLAY	
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" SUBGRADE	

Network: ORLANDO EXECUT		Branch: TW E		TAXIWAY E		Section: 545	Surface: AAC
L.C.D. 12/25/201		Use: TAXIWAY		Rank: P	Length: 180.00 (Ft)	Width: 45.00 (Ft)	True Area: 9618.000002 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/25/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2015: 2" MILL AND OVERLAY	
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 TRIPLE COAT P625 SURFACE TREATMENT	
1/1/1978	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1978 3" P401 AC SURFACE ON 8" P211 BASE	

Network: ORLANDO EXECUT		Branch: TW E		TAXIWAY E		Section: 550	Surface: AAC
L.C.D. 12/25/201		Use: TAXIWAY		Rank: P	Length: 1,336.00 (Ft)	Width: 40.00 (Ft)	True Area: 52982.00001 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/25/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2015: 2" MILL AND OVERLAY	
1/1/1984	IMPORT ED	REPAIR	0.00	0.00	<input type="checkbox"/>	1984 SLURRY SEAL	
1/1/1979	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1979 2" P-401 8" P-211	

9/19/2019

Work History Report

Page 12 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT		Branch: TW E5	TAXIWAY E5	Section: 560	Surface:AC	
L.C.D. 1/1/1991	Use: TAXIWAY	Rank: P	Length: 115.00 (Ft)	Width: 40.00 (Ft)	True Area: 5540.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" SUBGRADE

Network: ORLANDO EXECUT		Branch: TW E5	TAXIWAY E5	Section: 565	Surface:AAC	
L.C.D. 10/1/2015	Use: TAXIWAY	Rank: P	Length: 140.00 (Ft)	Width: 40.00 (Ft)	True Area: 9465.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
10/1/2015	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill and 2.5" P-401SP Overlay
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" SUBGRADE

Network: ORLANDO EXECUT		Branch: TW E6	TAXIWAY E6	Section: 805	Surface:AC	
L.C.D. 1/1/1984	Use: TAXIWAY	Rank: P	Length: 185.00 (Ft)	Width: 40.00 (Ft)	True Area: 17742.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	1984 4' P-401 6" P-211
1/1/1984	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT		Branch: TW E6	TAXIWAY E6		Section: 820	Surface:AC
L.C.D. 12/25/201	Use: TAXIWAY	Rank: P	Length: 145.00 (Ft)	Width: 70.00 (Ft)	True Area: 11139.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/2015	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 10" P-219 CRUSHED CON
1/1/1999	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	RECONSTRUCTION PLANNED IN 1999 SECTION UNKNOWN

Network: ORLANDO EXECUT		Branch: TW F	TAXIWAY F	Section: 605	Surface:AC	
L.C.D. 1/1/1984	Use: TAXIWAY	Rank: P	Length: 1,300.00 (Ft)	Width: 40.00 (Ft)	True Area: 54815.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P-401 6" P-211

Network: ORLANDO EXECUT		Branch: TW G	TAXIWAY G	Section: 705	Surface:AC	
L.C.D. 1/1/1984	Use: TAXIWAY	Rank: P	Length: 660.00 (Ft)	Width: 40.00 (Ft)	True Area: 30099.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1984	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1984 4" P-401 6" P-211

Network: ORLANDO EXECUT		Branch: TW G		TAXIWAY G		Section: 710		Surface:AC	
L.C.D. 1/1/1988		Use: TAXIWAY		Rank: P		Length: 215.00 (Ft)		Width: 40.00 (Ft) True Area: 9812.000002 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments		
1/1/1988	IMPORT ED	BUILT		0.00	0.00	<input checked="" type="checkbox"/>	EST 1988 BIT		

9/19/2019

Work History Report

Page 13 of 14

Pavement Database: FDOT

Network: ORLANDO EXECUT **Branch:** TW H TAXIWAY H **Section:** 806 **Surface:** AC
L.C.D. 1/1/1983 **Use:** TAXIWAY **Rank:** P **Length:** 1,560.00 (Ft) **Width:** 40.00 (Ft) **True Area:** 62452.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EST 1983 AC PAVEMENT
1/1/1983	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORLANDO EXECUT **Branch:** TW K TAXIWAY K **Section:** 610 **Surface:** AC
L.C.D. 1/1/1999 **Use:** TAXIWAY **Rank:** P **Length:** 500.00 (Ft) **Width:** 50.00 (Ft) **True Area:** 27266.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1999	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" AC/ 8" P-211/ 6" P-154

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	54	4,271,266.00	2.32	1.64
Cold Milling	2	900,750.00	0.00	0.00
Complete Reconstruction - AC	6	352,941.00	2.67	1.89
Complete Reconstruction - PCC	2	10,593.00	0.00	0.00
Crack Sealing - AC	1	17,742.00	0.00	0.00
MILL and OVERLAY	14	652,781.00	0.00	0.00
New Construction - AC	3	555,578.00	0.00	0.00
New Construction - Initial	22	978,016.00	1.68	1.87
New Construction - PCC	1	115,747.00	2.00	0.00
OVERLAY	10	474,420.00	1.40	1.80
Overlay - AC Structural	6	1,303,502.00	1.00	1.00
REPAIR	6	764,355.00	0.00	0.00
Surface Reconstruction - AC	2	131,590.00	4.00	0.00
Surface Treatment - Seal Coat	17	1,787,359.00	0.00	0.00
Surface Treatment - Slurry Seal	3	692,586.00	0.00	0.00

9/19/2019

Branch Condition Report

Page 1 of 2

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP GA	2	2,804.00	207.00	632,228.00	APRON	55.00	6.00	49.45
AP N	13	10,325.00	173.85	1,468,444.00	APRON	35.54	32.39	32.04
AP NE	4	2,550.00	52.50	138,742.00	APRON	59.00	22.05	55.40
AP RU	3	908.00	110.00	104,002.00	APRON	74.67	0.47	74.65
AP W	8	2,499.00	323.12	615,449.00	APRON	77.13	23.45	64.52
AP W SEG	2	935.00	222.50	209,360.00	APRON	72.00	5.00	70.80
RW 13-31	1	4,500.00	100.00	445,836.00	RUNWAY	66.00	0.00	66.00
RW 7-25	2	18,015.00	62.50	900,750.00	RUNWAY	63.50	0.50	63.33
TW A	9	6,427.00	65.33	429,472.00	TAXIWAY	70.22	12.93	65.95
TW A1	2	390.00	100.00	29,965.00	TAXIWAY	67.00	10.00	67.37
TW A2	1	387.00	75.00	30,935.00	TAXIWAY	65.00	0.00	65.00
TW A3	1	600.00	75.00	56,163.00	TAXIWAY	67.00	0.00	67.00
TW A4	1	397.00	30.00	15,668.00	TAXIWAY	63.00	0.00	63.00
TW A5	2	495.00	87.50	46,492.00	TAXIWAY	68.00	3.00	66.22
TW A6	1	640.00	35.00	26,953.00	TAXIWAY	72.00	0.00	72.00
TW B	3	1,340.00	66.67	93,858.00	TAXIWAY	63.33	16.98	64.91
TW E	5	4,368.00	41.00	208,227.00	TAXIWAY	86.20	10.80	81.86
TW E1	1	40.00	125.00	5,073.00	TAXIWAY	50.00	0.00	50.00
TW E2	2	215.00	40.00	12,331.00	TAXIWAY	53.50	7.50	49.27
TW E3	4	374.00	293.00	55,837.00	TAXIWAY	43.25	8.35	46.15
TW E4	4	1,397.00	59.50	166,492.00	TAXIWAY	67.50	16.93	56.56
TW E5	2	255.00	40.00	15,005.00	TAXIWAY	79.50	14.50	83.29
TW E6	2	330.00	55.00	28,881.00	TAXIWAY	80.50	13.50	77.41
TW F	1	1,300.00	40.00	54,815.00	TAXIWAY	45.00	0.00	45.00
TW G	2	875.00	40.00	39,911.00	TAXIWAY	54.50	0.50	54.25
TW H	1	1,560.00	40.00	62,452.00	TAXIWAY	52.00	0.00	52.00
TW K	1	500.00	50.00	27,266.00	TAXIWAY	70.00	0.00	70.00

9/19/2019

Branch Condition Report

Page 2 of 2

Pavement Database: FDOT

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	32	3,168,225.00	56.03	30.98	46.81
RUNWAY	3	1,346,586.00	64.33	1.25	64.22
TAXIWAY	45	1,405,796.00	66.36	16.41	65.01
ALL	80	5,920,607.00	62.15	23.67	55.09

Pavement Database: FDOT

NetworkId: ORL

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP GA	4205	1/1/1984	AC	APRON	P	0	608,614.00	3/4/2019	35	49
AP GA	4230	12/25/1999	AC	APRON	P	0	23,614.00	3/4/2019	20	61
AP N	4105	1/1/1979	AC	APRON	T	0	200,966.00	3/4/2019	40	6
AP N	4125	1/1/1978	AC	APRON	P	0	140,429.00	3/4/2019	41	5
AP N	4140	1/1/1979	AC	APRON	P	0	237,860.00	3/4/2019	40	25
AP N	4145	1/1/1968	AC	APRON	P	0	122,500.00	3/4/2019	51	34
AP N	4155	1/1/1984	AC	APRON	P	0	337,449.00	3/4/2019	35	49
AP N	4158	1/1/2002	AAC	APRON	P	0	125,584.00	3/4/2019	17	6
AP N	4165	1/1/1984	AC	APRON	P	0	27,156.00	3/4/2019	35	7
AP N	4166	9/1/2012	AC	APRON	P	0	22,635.00	3/4/2019	7	89
AP N	4167	1/1/1984	AC	APRON	P	0	28,916.00	3/4/2019	35	12
AP N	4168	1/1/2005	PCC	APRON	P	0	24,538.00	3/4/2019	14	0
AP N	4169	9/1/2012	AC	APRON	P	0	72,939.00	3/4/2019	7	86
AP N	4170	1/1/1984	AC	APRON	P	0	84,878.00	3/4/2019	35	67
AP N	4175	1/1/1960	AC	APRON	P	0	42,594.00	3/4/2019	59	76
AP NE	4305	1/1/1984	AC	APRON	P	0	52,643.00	3/4/2019	35	23
AP NE	4312	12/25/1999	AC	APRON	P	0	8,541.00	3/4/2019	20	59
AP NE	4315	1/1/2007	AAC	APRON	P	0	24,518.00	3/4/2019	12	77
AP NE	4320	1/1/2007	AAC	APRON	P	0	53,040.00	3/4/2019	12	77
AP RU	5110	1/1/2001	AC	APRON	P	0	25,880.00	3/4/2019	18	75
AP RU	5115	1/1/2001	AC	APRON	P	0	36,282.00	3/4/2019	18	74
AP RU	5120	1/1/2001	AC	APRON	P	0	41,840.00	3/4/2019	18	75
AP W	4605	1/1/2002	AC	APRON	P	0	34,600.00	3/4/2019	17	64
AP W	4610	1/1/1999	AC	APRON	P	0	260,825.00	3/4/2019	20	45
AP W	4640	3/1/2019	AAC	APRON	P	0	157,964.00	3/1/2019	0	100
AP W	4645	12/1/2017	AC	APRON	P	0	24,864.00	12/1/2017	0	100
AP W	4650	12/1/1998	AC	APRON	P	0	115,747.00	3/4/2019	21	50
AP W	4665	6/1/2019	PCC	APRON	P	0	8,833.00	6/1/2019	0	100
AP W	4670	12/1/1998	AC	APRON	P	0	10,856.00	3/4/2019	21	58
AP W	4675	3/1/2019	PCC	APRON	P	0	1,760.00	3/1/2019	0	100
AP W SEGM	4805	1/1/2001	AAC	APRON	P	0	129,830.00	3/4/2019	18	67
AP W SEGM	4810	1/1/2012	AAC	APRON	P	0	79,530.00	3/4/2019	7	77
RW 13-31	6205	1/1/1999	AC	RUNWAY	P	0	445,836.00	3/4/2019	20	66
RW 7-25	6105	1/2/2001	AAC	RUNWAY	T	0	600,500.00	3/4/2019	18	63
RW 7-25	6110	1/2/2001	AAC	RUNWAY	P	0	300,250.00	3/4/2019	18	64
TW A	104	1/1/2001	AC	TAXIWAY	P	0	11,949.00	3/4/2019	18	66
TW A	114	1/1/1999	AC	TAXIWAY	P	0	12,579.00	3/4/2019	20	78
TW A	115	1/1/1984	AC	TAXIWAY	P	0	31,644.00	3/4/2019	35	56
TW A	116	1/1/1984	AC	TAXIWAY	P	0	11,579.00	3/4/2019	35	63
TW A	117	1/1/1984	AC	TAXIWAY	P	0	22,912.00	3/4/2019	35	62
TW A	118	10/1/2015	AAC	TAXIWAY	P	0	12,843.00	3/4/2019	4	94
TW A	119	10/1/2015	AAC	TAXIWAY	P	0	8,568.00	3/4/2019	4	89
TW A	125	1/1/1997	AAC	TAXIWAY	P	0	257,040.00	3/4/2019	22	67
TW A	150	1/1/1963	AC	TAXIWAY	P	0	60,358.00	3/4/2019	56	57
TW A1	111	1/1/1997	AAC	TAXIWAY	P	0	15,537.00	3/4/2019	22	77
TW A1	112	1/1/1997	AAC	TAXIWAY	P	0	14,428.00	3/4/2019	22	57
TW A2	120	1/1/1997	AAC	TAXIWAY	P	0	30,935.00	3/4/2019	22	65
TW A3	130	1/1/1997	AAC	TAXIWAY	P	0	56,163.00	3/4/2019	22	67
TW A4	140	1/1/1999	AC	TAXIWAY	P	0	15,668.00	3/4/2019	20	63

TW A5	405	1/1/1997	AAC	TAXIWAY	P	0	37,049.00	3/4/2019	22	65
TW A5	425	1/1/1997	AAC	TAXIWAY	P	0	9,443.00	3/4/2019	22	71
TW A6	113	1/1/2001	AC	TAXIWAY	P	0	26,953.00	3/4/2019	18	72
TW B	102	1/1/1991	AC	TAXIWAY	P	0	6,388.00	3/4/2019	28	48
TW B	103	1/1/1999	AAC	TAXIWAY	P	0	57,000.00	3/4/2019	20	55
TW B	105	12/25/2015	AAC	TAXIWAY	P	0	30,470.00	3/4/2019	4	87
TW E	505	1/1/1983	AC	TAXIWAY	P	0	78,110.00	3/4/2019	36	65
TW E	530	12/25/2015	AAC	TAXIWAY	P	0	46,191.00	3/4/2019	4	93
TW E	540	12/25/2015	AAC	TAXIWAY	P	0	21,326.00	3/4/2019	4	94
TW E	545	12/25/2015	AAC	TAXIWAY	P	0	9,618.00	3/4/2019	4	88
TW E	550	12/25/2015	AAC	TAXIWAY	P	0	52,982.00	3/4/2019	4	91
TW E1	501	1/1/1977	AC	TAXIWAY	T	0	5,073.00	3/4/2019	42	50
TW E2	510	1/1/1983	AC	TAXIWAY	P	0	9,644.00	3/4/2019	36	46
TW E2	512	1/1/1983	AC	TAXIWAY	P	0	2,687.00	3/4/2019	36	61
TW E3	417	1/1/1977	AC	TAXIWAY	P	0	8,311.00	3/4/2019	42	29
TW E3	420	1/1/1984	AC	TAXIWAY	P	0	36,384.00	3/4/2019	35	50
TW E3	520	1/1/1983	AC	TAXIWAY	P	0	9,009.00	3/4/2019	36	46
TW E3	522	1/1/1983	AC	TAXIWAY	P	0	2,133.00	3/4/2019	36	48
TW E4	1070	1/1/1977	AAC	TAXIWAY	P	0	130,837.00	3/4/2019	42	50
TW E4	1080	1/1/1977	AAC	TAXIWAY	P	0	8,393.00	3/4/2019	42	56
TW E4	1105	1/1/1991	AC	TAXIWAY	T	0	6,580.00	3/4/2019	28	70
TW E4	1110	12/25/2015	AAC	TAXIWAY	T	0	20,682.00	3/4/2019	4	94
TW E5	560	1/1/1991	AC	TAXIWAY	P	0	5,540.00	3/4/2019	28	65
TW E5	565	10/1/2015	AAC	TAXIWAY	P	0	9,465.00	3/4/2019	4	94
TW E6	805	1/1/1984	AC	TAXIWAY	P	0	17,742.00	3/4/2019	35	67
TW E6	820	12/25/2015	AC	TAXIWAY	P	0	11,139.00	3/4/2019	4	94
TW F	605	1/1/1984	AC	TAXIWAY	P	0	54,815.00	3/4/2019	35	45
TW G	705	1/1/1984	AC	TAXIWAY	P	0	30,099.00	3/4/2019	35	54
TW G	710	1/1/1988	AC	TAXIWAY	P	0	9,812.00	3/4/2019	31	55
TW H	806	1/1/1983	AC	TAXIWAY	P	0	62,452.00	3/4/2019	36	52
TW K	610	1/1/1999	AC	TAXIWAY	P	0	27,266.00	3/4/2019	20	70

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		193,421.00	4	100.00	0.00	100.00
03-05	4	223,284.00	10	91.80	2.68	91.68
06-10	7	175,104.00	3	84.00	5.10	82.30
11-15	13	102,096.00	3	51.33	36.30	58.49
16-20	19	2,184,997.00	18	62.39	15.72	59.19
21-25	22	547,198.00	9	64.11	7.59	63.07
26-30	28	18,508.00	3	61.00	9.42	60.91
31-35	35	1,354,643.00	14	47.07	18.70	48.24
36-40	37	602,861.00	8	43.63	18.10	27.54
41-50	42	293,043.00	5	38.00	18.88	28.01
50+	55	225,452.00	3	55.67	17.17	48.09
ALL	23	5,920,607.00	80	62.15	23.67	55.09

Appendix B

Airfield Pavement Localized Maintenance and Repair and
Major Rehabilitation



Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
ORL	AP GA	4205	43	BLOCK CR	Medium	45184.96	SqFt	7.4%	FDOT - CRACK SEALING - AC	13772.3	Ft	\$ 3.00	\$ 41,320.00
ORL	AP GA	4205	48	L & T CR	Medium	8933.27	Ft	1.5%	FDOT - CRACK SEALING - AC	8933.4	Ft	\$ 3.00	\$ 26,800.00
ORL	AP GA	4205	52	RAVELING	Low	545562.45	SqFt	89.6%	FDOT - SURFACE SEAL	545562.3	SqFt	\$ 0.55	\$ 300,070.00
ORL	AP GA	4205	52	RAVELING	Medium	6570.29	SqFt	1.1%	FDOT - PATCHING - AC PARTIAL DEPTH	6570.3	SqFt	\$ 4.00	\$ 26,290.00
ORL	AP GA	4230	52	RAVELING	Low	13489.87	SqFt	57.1%	FDOT - SURFACE SEAL	13489.3	SqFt	\$ 0.55	\$ 7,420.00
ORL	AP N	4105	41	ALLIGATOR CR	Low	1599.73	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	1764.2	SqFt	\$ 9.00	\$ 15,890.00
ORL	AP N	4105	43	BLOCK CR	Medium	38842.75	SqFt	19.3%	FDOT - CRACK SEALING - AC	11839.2	Ft	\$ 3.00	\$ 35,520.00
ORL	AP N	4105	43	BLOCK CR	High	155443.14	SqFt	77.4%	FDOT - PATCHING - AC PARTIAL DEPTH	155442.7	SqFt	\$ 4.00	\$ 621,780.00
ORL	AP N	4105	50	PATCHING	Medium	4453.46	SqFt	2.2%	FDOT - PATCHING - AC FULL DEPTH	4726.4	SqFt	\$ 9.00	\$ 42,540.00
ORL	AP N	4105	52	RAVELING	Medium	107492.72	SqFt	53.5%	FDOT - PATCHING - AC PARTIAL DEPTH	107492.7	SqFt	\$ 4.00	\$ 429,980.00
ORL	AP N	4105	52	RAVELING	High	88392.91	SqFt	44.0%	FDOT - PATCHING - AC PARTIAL DEPTH	88393.2	SqFt	\$ 4.00	\$ 353,580.00
ORL	AP N	4105	53	RUTTING	Medium	2363.32	SqFt	1.2%	FDOT - PATCHING - AC FULL DEPTH	2363.8	SqFt	\$ 9.00	\$ 21,280.00
ORL	AP N	4125	41	ALLIGATOR CR	Medium	2724.78	SqFt	1.9%	FDOT - PATCHING - AC FULL DEPTH	2938.6	SqFt	\$ 9.00	\$ 26,450.00
ORL	AP N	4125	43	BLOCK CR	Medium	75454.37	SqFt	53.7%	FDOT - CRACK SEALING - AC	22998.4	Ft	\$ 3.00	\$ 69,000.00
ORL	AP N	4125	43	BLOCK CR	High	62249.85	SqFt	44.3%	FDOT - PATCHING - AC PARTIAL DEPTH	62249.9	SqFt	\$ 4.00	\$ 249,000.00
ORL	AP N	4125	52	RAVELING	Medium	132045.19	SqFt	94.0%	FDOT - PATCHING - AC PARTIAL DEPTH	132045.2	SqFt	\$ 4.00	\$ 528,190.00
ORL	AP N	4125	52	RAVELING	High	8383.79	SqFt	6.0%	FDOT - PATCHING - AC PARTIAL DEPTH	8384	SqFt	\$ 4.00	\$ 33,540.00
ORL	AP N	4125	53	RUTTING	Medium	2347.5	SqFt	1.7%	FDOT - PATCHING - AC FULL DEPTH	2347.6	SqFt	\$ 9.00	\$ 21,130.00
ORL	AP N	4140	43	BLOCK CR	Medium	221607.5	SqFt	93.2%	FDOT - CRACK SEALING - AC	67545.9	Ft	\$ 3.00	\$ 202,640.00
ORL	AP N	4140	52	RAVELING	Low	54416.95	SqFt	22.9%	FDOT - SURFACE SEAL	54417	SqFt	\$ 0.55	\$ 29,930.00
ORL	AP N	4140	52	RAVELING	Medium	142811.8	SqFt	60.0%	FDOT - PATCHING - AC PARTIAL DEPTH	142811.3	SqFt	\$ 4.00	\$ 571,250.00
ORL	AP N	4140	52	RAVELING	High	40631.29	SqFt	17.1%	FDOT - PATCHING - AC PARTIAL DEPTH	40631.6	SqFt	\$ 4.00	\$ 162,530.00
ORL	AP N	4145	50	PATCHING	Medium	4604.69	SqFt	3.8%	FDOT - PATCHING - AC FULL DEPTH	4881.4	SqFt	\$ 9.00	\$ 43,940.00
ORL	AP N	4145	52	RAVELING	Medium	117712.51	SqFt	96.1%	FDOT - PATCHING - AC PARTIAL DEPTH	117713.1	SqFt	\$ 4.00	\$ 470,850.00
ORL	AP N	4145	52	RAVELING	High	182.77	SqFt	0.2%	FDOT - PATCHING - AC PARTIAL DEPTH	183	SqFt	\$ 4.00	\$ 740.00
ORL	AP N	4155	43	BLOCK CR	Medium	37922.55	SqFt	11.2%	FDOT - CRACK SEALING - AC	11558.7	Ft	\$ 3.00	\$ 34,680.00
ORL	AP N	4155	52	RAVELING	Low	236689.78	SqFt	70.1%	FDOT - SURFACE SEAL	236689.8	SqFt	\$ 0.55	\$ 130,190.00
ORL	AP N	4155	52	RAVELING	Medium	100759.24	SqFt	29.9%	FDOT - PATCHING - AC PARTIAL DEPTH	100758.8	SqFt	\$ 4.00	\$ 403,040.00
ORL	AP N	4158	43	BLOCK CR	High	125584.05	SqFt	100.0%	FDOT - PATCHING - AC PARTIAL DEPTH	125583.6	SqFt	\$ 4.00	\$ 502,340.00
ORL	AP N	4158	45	DEPRESSION	Low	1656.35	SqFt	1.3%	FDOT - PATCHING - AC FULL DEPTH	1824.5	SqFt	\$ 9.00	\$ 16,420.00
ORL	AP N	4158	52	RAVELING	Medium	109353.15	SqFt	87.1%	FDOT - PATCHING - AC PARTIAL DEPTH	109352.7	SqFt	\$ 4.00	\$ 437,420.00
ORL	AP N	4158	52	RAVELING	High	16230.79	SqFt	12.9%	FDOT - PATCHING - AC PARTIAL DEPTH	16230.9	SqFt	\$ 4.00	\$ 64,930.00
ORL	AP N	4165	43	BLOCK CR	Medium	19731.86	SqFt	72.7%	FDOT - CRACK SEALING - AC	6014.4	Ft	\$ 3.00	\$ 18,050.00
ORL	AP N	4165	43	BLOCK CR	High	7424.08	SqFt	27.3%	FDOT - PATCHING - AC PARTIAL DEPTH	7423.9	SqFt	\$ 4.00	\$ 29,700.00
ORL	AP N	4165	45	DEPRESSION	Low	1021.17	SqFt	3.8%	FDOT - PATCHING - AC FULL DEPTH	1153.9	SqFt	\$ 9.00	\$ 10,390.00
ORL	AP N	4165	52	RAVELING	Medium	27156.05	SqFt	100.0%	FDOT - PATCHING - AC PARTIAL DEPTH	27156.3	SqFt	\$ 4.00	\$ 108,630.00
ORL	AP N	4167	41	ALLIGATOR CR	Low	906.32	SqFt	3.1%	FDOT - PATCHING - AC FULL DEPTH	1031.2	SqFt	\$ 9.00	\$ 9,290.00
ORL	AP N	4167	41	ALLIGATOR CR	Medium	828.61	SqFt	2.9%	FDOT - PATCHING - AC FULL DEPTH	948.3	SqFt	\$ 9.00	\$ 8,540.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
ORL	AP N	4167	43	BLOCK CR	Medium	20275.76	SqFt	70.1%	FDOT - CRACK SEALING - AC	6180.1	Ft	\$ 3.00	\$ 18,550.00
ORL	AP N	4167	45	DEPRESSION	Low	448.86	SqFt	1.6%	FDOT - PATCHING - AC FULL DEPTH	538.2	SqFt	\$ 9.00	\$ 4,850.00
ORL	AP N	4167	52	RAVELING	Medium	21984.75	SqFt	76.0%	FDOT - PATCHING - AC PARTIAL DEPTH	21985.3	SqFt	\$ 4.00	\$ 87,940.00
ORL	AP N	4167	52	RAVELING	High	25.94	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	25.8	SqFt	\$ 4.00	\$ 110.00
ORL	AP N	4168	65	JT SEAL DMG	High	51	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1741.8	Ft	\$ 2.75	\$ 4,790.00
ORL	AP N	4168	72	SHAT. SLAB	Medium	38.25	Slabs	75.0%	FDOT - SLAB REPLACEMENT - PCC	18360	SqFt	\$ 30.00	\$ 550,800.00
ORL	AP N	4168	72	SHAT. SLAB	High	12.75	Slabs	25.0%	FDOT - SLAB REPLACEMENT - PCC	6120.4	SqFt	\$ 30.00	\$ 183,600.00
ORL	AP N	4169	52	RAVELING	Low	2267.53	SqFt	3.1%	FDOT - SURFACE SEAL	2268	SqFt	\$ 0.55	\$ 1,250.00
ORL	AP N	4170	45	DEPRESSION	Low	16.15	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	36.6	SqFt	\$ 9.00	\$ 330.00
ORL	AP N	4170	52	RAVELING	Low	17649.8	SqFt	20.8%	FDOT - SURFACE SEAL	17649.6	SqFt	\$ 0.55	\$ 9,710.00
ORL	AP N	4170	57	WEATHERING	Medium	51449.34	SqFt	60.6%	FDOT - SURFACE SEAL	51449.3	SqFt	\$ 0.55	\$ 28,300.00
ORL	AP N	4175	45	DEPRESSION	Low	506.55	SqFt	1.2%	FDOT - PATCHING - AC FULL DEPTH	600.6	SqFt	\$ 9.00	\$ 5,410.00
ORL	AP N	4175	52	RAVELING	Low	6438.65	SqFt	15.1%	FDOT - SURFACE SEAL	6439	SqFt	\$ 0.55	\$ 3,550.00
ORL	AP NE	4305	43	BLOCK CR	Medium	46771.34	SqFt	88.9%	FDOT - CRACK SEALING - AC	14255.9	Ft	\$ 3.00	\$ 42,770.00
ORL	AP NE	4305	45	DEPRESSION	Low	359.62	SqFt	0.7%	FDOT - PATCHING - AC FULL DEPTH	440.2	SqFt	\$ 9.00	\$ 3,960.00
ORL	AP NE	4305	50	PATCHING	Medium	5663.75	SqFt	10.8%	FDOT - PATCHING - AC FULL DEPTH	5970.7	SqFt	\$ 9.00	\$ 53,740.00
ORL	AP NE	4305	50	PATCHING	High	207.85	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	270.2	SqFt	\$ 9.00	\$ 2,430.00
ORL	AP NE	4305	52	RAVELING	Low	29454.04	SqFt	56.0%	FDOT - SURFACE SEAL	29454.4	SqFt	\$ 0.55	\$ 16,200.00
ORL	AP NE	4305	52	RAVELING	Medium	17261.11	SqFt	32.8%	FDOT - PATCHING - AC PARTIAL DEPTH	17261	SqFt	\$ 4.00	\$ 69,050.00
ORL	AP NE	4305	52	RAVELING	High	56.19	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	56	SqFt	\$ 4.00	\$ 230.00
ORL	AP NE	4312	45	DEPRESSION	Low	526.36	SqFt	6.2%	FDOT - PATCHING - AC FULL DEPTH	623.2	SqFt	\$ 9.00	\$ 5,610.00
ORL	AP NE	4312	52	RAVELING	Low	1489.73	SqFt	17.4%	FDOT - SURFACE SEAL	1489.7	SqFt	\$ 0.55	\$ 820.00
ORL	AP NE	4312	57	WEATHERING	Medium	1092.43	SqFt	12.8%	FDOT - SURFACE SEAL	1092.5	SqFt	\$ 0.55	\$ 610.00
ORL	AP NE	4315	52	RAVELING	Low	4543.12	SqFt	18.5%	FDOT - SURFACE SEAL	4543.5	SqFt	\$ 0.55	\$ 2,500.00
ORL	AP NE	4320	52	RAVELING	Low	11315.24	SqFt	21.3%	FDOT - SURFACE SEAL	11315	SqFt	\$ 0.55	\$ 6,230.00
ORL	AP RU	5110	52	RAVELING	Low	1296.3	SqFt	5.0%	FDOT - SURFACE SEAL	1296	SqFt	\$ 0.55	\$ 720.00
ORL	AP RU	5115	52	RAVELING	Low	3707.63	SqFt	10.2%	FDOT - SURFACE SEAL	3708.2	SqFt	\$ 0.55	\$ 2,040.00
ORL	AP RU	5120	52	RAVELING	Low	2095.09	SqFt	5.0%	FDOT - SURFACE SEAL	2094.7	SqFt	\$ 0.55	\$ 1,160.00
ORL	AP W	4605	49	OIL SPILLAGE	N/A	41.55	SqFt	0.1%	FDOT - PATCHING - AC PARTIAL DEPTH	71	SqFt	\$ 4.00	\$ 290.00
ORL	AP W	4605	52	RAVELING	Low	6920.01	SqFt	20.0%	FDOT - SURFACE SEAL	6920.1	SqFt	\$ 0.55	\$ 3,810.00
ORL	AP W	4605	57	WEATHERING	Medium	27680.04	SqFt	80.0%	FDOT - SURFACE SEAL	27680.5	SqFt	\$ 0.55	\$ 15,230.00
ORL	AP W	4610	43	BLOCK CR	Medium	53927.19	SqFt	20.7%	FDOT - CRACK SEALING - AC	16437	Ft	\$ 3.00	\$ 49,320.00
ORL	AP W	4610	45	DEPRESSION	Low	1042.48	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	1176.5	SqFt	\$ 9.00	\$ 10,590.00
ORL	AP W	4610	52	RAVELING	Low	255021.36	SqFt	97.8%	FDOT - SURFACE SEAL	255021.8	SqFt	\$ 0.55	\$ 140,270.00
ORL	AP W	4650	43	BLOCK CR	Medium	5879.03	SqFt	5.1%	FDOT - CRACK SEALING - AC	1792	Ft	\$ 3.00	\$ 5,380.00
ORL	AP W	4650	45	DEPRESSION	Low	144.45	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	197	SqFt	\$ 9.00	\$ 1,780.00
ORL	AP W	4650	52	RAVELING	Low	115747.02	SqFt	100.0%	FDOT - SURFACE SEAL	115746.5	SqFt	\$ 0.55	\$ 63,670.00
ORL	AP W	4670	52	RAVELING	Low	10856.05	SqFt	100.0%	FDOT - SURFACE SEAL	10856.5	SqFt	\$ 0.55	\$ 5,980.00
ORL	AP W SEGM	4805	52	RAVELING	Low	2341.9	SqFt	1.8%	FDOT - SURFACE SEAL	2342.2	SqFt	\$ 0.55	\$ 1,290.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
ORL	AP W SEGM	4805	57	WEATHERING	Medium	83794.78	SqFt	64.5%	FDOT - SURFACE SEAL	83794.9	SqFt	\$ 0.55	\$ 46,090.00
ORL	AP W SEGM	4810	45	DEPRESSION	Low	776.19	SqFt	1.0%	FDOT - PATCHING - AC FULL DEPTH	892.3	SqFt	\$ 9.00	\$ 8,040.00
ORL	AP W SEGM	4810	49	OIL SPILLAGE	N/A	19.16	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	40.9	SqFt	\$ 4.00	\$ 170.00
ORL	AP W SEGM	4810	52	RAVELING	Low	939.04	SqFt	1.2%	FDOT - SURFACE SEAL	938.6	SqFt	\$ 0.55	\$ 520.00
ORL	RW 13-31	6205	45	DEPRESSION	Low	1023.76	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	1156	SqFt	\$ 9.00	\$ 10,410.00
ORL	RW 13-31	6205	48	L & T CR	Medium	1018.93	Ft	0.2%	FDOT - CRACK SEALING - AC	1019	Ft	\$ 3.00	\$ 3,060.00
ORL	RW 13-31	6205	52	RAVELING	Low	58772.35	SqFt	13.2%	FDOT - SURFACE SEAL	58772	SqFt	\$ 0.55	\$ 32,330.00
ORL	RW 13-31	6205	52	RAVELING	Medium	6356.09	SqFt	1.4%	FDOT - PATCHING - AC PARTIAL DEPTH	6356.1	SqFt	\$ 4.00	\$ 25,430.00
ORL	RW 13-31	6205	56	SWELLING	Medium	43.7	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	74.3	SqFt	\$ 9.00	\$ 670.00
ORL	RW 7-25	6105	45	DEPRESSION	Low	162.1	SqFt	0.0%	FDOT - PATCHING - AC FULL DEPTH	217.4	SqFt	\$ 9.00	\$ 1,960.00
ORL	RW 7-25	6105	48	L & T CR	Medium	7266.04	Ft	1.2%	FDOT - CRACK SEALING - AC	7266.1	Ft	\$ 3.00	\$ 21,800.00
ORL	RW 7-25	6105	52	RAVELING	Low	87450.85	SqFt	14.6%	FDOT - SURFACE SEAL	87450.3	SqFt	\$ 0.55	\$ 48,100.00
ORL	RW 7-25	6105	52	RAVELING	Medium	2810.35	SqFt	0.5%	FDOT - PATCHING - AC PARTIAL DEPTH	2810.5	SqFt	\$ 4.00	\$ 11,250.00
ORL	RW 7-25	6105	57	WEATHERING	Medium	34054.32	SqFt	5.7%	FDOT - SURFACE SEAL	34054.9	SqFt	\$ 0.55	\$ 18,740.00
ORL	RW 7-25	6110	48	L & T CR	Medium	149.51	Ft	0.1%	FDOT - CRACK SEALING - AC	149.6	Ft	\$ 3.00	\$ 450.00
ORL	RW 7-25	6110	52	RAVELING	Low	74736.09	SqFt	24.9%	FDOT - SURFACE SEAL	74736	SqFt	\$ 0.55	\$ 41,110.00
ORL	RW 7-25	6110	52	RAVELING	Medium	14257.55	SqFt	4.8%	FDOT - PATCHING - AC PARTIAL DEPTH	14257.9	SqFt	\$ 4.00	\$ 57,030.00
ORL	TW A	104	52	RAVELING	Low	1489.62	SqFt	12.5%	FDOT - SURFACE SEAL	1489.7	SqFt	\$ 0.55	\$ 820.00
ORL	TW A	114	52	RAVELING	Low	2057.74	SqFt	16.4%	FDOT - SURFACE SEAL	2058.1	SqFt	\$ 0.55	\$ 1,140.00
ORL	TW A	115	48	L & T CR	Medium	843.83	Ft	2.7%	FDOT - CRACK SEALING - AC	843.8	Ft	\$ 3.00	\$ 2,540.00
ORL	TW A	115	52	RAVELING	Low	31222.12	SqFt	98.7%	FDOT - SURFACE SEAL	31221.8	SqFt	\$ 0.55	\$ 17,180.00
ORL	TW A	115	52	RAVELING	Medium	421.95	SqFt	1.3%	FDOT - PATCHING - AC PARTIAL DEPTH	422	SqFt	\$ 4.00	\$ 1,690.00
ORL	TW A	116	48	L & T CR	Medium	38.62	Ft	0.3%	FDOT - CRACK SEALING - AC	38.7	Ft	\$ 3.00	\$ 120.00
ORL	TW A	116	52	RAVELING	Low	11578.95	SqFt	100.0%	FDOT - SURFACE SEAL	11578.7	SqFt	\$ 0.55	\$ 6,370.00
ORL	TW A	117	48	L & T CR	Medium	598.69	Ft	2.6%	FDOT - CRACK SEALING - AC	598.8	Ft	\$ 3.00	\$ 1,800.00
ORL	TW A	117	52	RAVELING	Low	22911.95	SqFt	100.0%	FDOT - SURFACE SEAL	22912.1	SqFt	\$ 0.55	\$ 12,610.00
ORL	TW A	125	52	RAVELING	Low	22531.34	SqFt	8.8%	FDOT - SURFACE SEAL	22531	SqFt	\$ 0.55	\$ 12,400.00
ORL	TW A	150	48	L & T CR	Medium	1008.83	Ft	1.7%	FDOT - CRACK SEALING - AC	1008.9	Ft	\$ 3.00	\$ 3,030.00
ORL	TW A	150	52	RAVELING	Low	25921.76	SqFt	43.0%	FDOT - SURFACE SEAL	25921.7	SqFt	\$ 0.55	\$ 14,260.00
ORL	TW A	150	57	WEATHERING	Medium	17654.43	SqFt	29.3%	FDOT - SURFACE SEAL	17655	SqFt	\$ 0.55	\$ 9,720.00
ORL	TW A1	111	52	RAVELING	Low	778.88	SqFt	5.0%	FDOT - SURFACE SEAL	779.3	SqFt	\$ 0.55	\$ 430.00
ORL	TW A1	111	57	WEATHERING	Medium	3936.04	SqFt	25.3%	FDOT - SURFACE SEAL	3936.4	SqFt	\$ 0.55	\$ 2,170.00
ORL	TW A1	112	41	ALLIGATOR CR	Medium	76.96	SqFt	0.5%	FDOT - PATCHING - AC FULL DEPTH	116.3	SqFt	\$ 9.00	\$ 1,050.00
ORL	TW A1	112	48	L & T CR	Medium	92.32	Ft	0.6%	FDOT - CRACK SEALING - AC	92.2	Ft	\$ 3.00	\$ 280.00
ORL	TW A1	112	52	RAVELING	Low	3847.45	SqFt	26.7%	FDOT - SURFACE SEAL	3847	SqFt	\$ 0.55	\$ 2,120.00
ORL	TW A2	120	52	RAVELING	Low	1443.66	SqFt	4.7%	FDOT - SURFACE SEAL	1443.4	SqFt	\$ 0.55	\$ 800.00
ORL	TW A2	120	52	RAVELING	Medium	2037.61	SqFt	6.6%	FDOT - PATCHING - AC PARTIAL DEPTH	2037.6	SqFt	\$ 4.00	\$ 8,160.00
ORL	TW A3	130	45	DEPRESSION	Low	489.11	SqFt	0.9%	FDOT - PATCHING - AC FULL DEPTH	582.3	SqFt	\$ 9.00	\$ 5,240.00
ORL	TW A3	130	48	L & T CR	Medium	3.9	Ft	0.0%	FDOT - CRACK SEALING - AC	3.9	Ft	\$ 3.00	\$ 20.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
ORL	TW A3	130	52	RAVELING	Low	9880.95	SqFt	17.6%	FDOT - SURFACE SEAL	9881.3	SqFt	\$ 0.55	\$ 5,440.00
ORL	TW A4	140	52	RAVELING	Low	785.44	SqFt	5.0%	FDOT - SURFACE SEAL	785.8	SqFt	\$ 0.55	\$ 440.00
ORL	TW A5	405	48	L & T CR	Medium	197.6	Ft	0.5%	FDOT - CRACK SEALING - AC	197.5	Ft	\$ 3.00	\$ 600.00
ORL	TW A5	405	52	RAVELING	Low	1758.61	SqFt	4.8%	FDOT - SURFACE SEAL	1758.8	SqFt	\$ 0.55	\$ 970.00
ORL	TW A5	405	52	RAVELING	Medium	1926.52	SqFt	5.2%	FDOT - PATCHING - AC PARTIAL DEPTH	1926.7	SqFt	\$ 4.00	\$ 7,710.00
ORL	TW A5	425	52	RAVELING	Low	943.99	SqFt	10.0%	FDOT - SURFACE SEAL	944	SqFt	\$ 0.55	\$ 520.00
ORL	TW A5	425	57	WEATHERING	Medium	1670.99	SqFt	17.7%	FDOT - SURFACE SEAL	1670.6	SqFt	\$ 0.55	\$ 920.00
ORL	TW A6	113	52	RAVELING	Low	385.03	SqFt	1.4%	FDOT - SURFACE SEAL	385.4	SqFt	\$ 0.55	\$ 220.00
ORL	TW B	102	52	RAVELING	Low	5387.98	SqFt	84.4%	FDOT - SURFACE SEAL	5388.4	SqFt	\$ 0.55	\$ 2,970.00
ORL	TW B	102	52	RAVELING	Medium	999.97	SqFt	15.7%	FDOT - PATCHING - AC PARTIAL DEPTH	1000	SqFt	\$ 4.00	\$ 4,000.00
ORL	TW B	103	45	DEPRESSION	Low	121.63	SqFt	0.2%	FDOT - PATCHING - AC FULL DEPTH	170.1	SqFt	\$ 9.00	\$ 1,530.00
ORL	TW B	103	52	RAVELING	Low	8549.99	SqFt	15.0%	FDOT - SURFACE SEAL	8549.8	SqFt	\$ 0.55	\$ 4,710.00
ORL	TW B	103	57	WEATHERING	Medium	6650.05	SqFt	11.7%	FDOT - SURFACE SEAL	6649.9	SqFt	\$ 0.55	\$ 3,660.00
ORL	TW E	505	48	L & T CR	Medium	351.51	Ft	0.5%	FDOT - CRACK SEALING - AC	351.4	Ft	\$ 3.00	\$ 1,060.00
ORL	TW E	505	52	RAVELING	Low	78110.04	SqFt	100.0%	FDOT - SURFACE SEAL	78110.5	SqFt	\$ 0.55	\$ 42,970.00
ORL	TW E1	501	48	L & T CR	Medium	29.99	Ft	0.6%	FDOT - CRACK SEALING - AC	29.9	Ft	\$ 3.00	\$ 90.00
ORL	TW E1	501	52	RAVELING	Low	4057.99	SqFt	80.0%	FDOT - SURFACE SEAL	4058	SqFt	\$ 0.55	\$ 2,240.00
ORL	TW E2	510	48	L & T CR	Medium	44.29	Ft	0.5%	FDOT - CRACK SEALING - AC	44.3	Ft	\$ 3.00	\$ 140.00
ORL	TW E2	510	52	RAVELING	Low	9289.58	SqFt	96.3%	FDOT - SURFACE SEAL	9289.3	SqFt	\$ 0.55	\$ 5,110.00
ORL	TW E2	510	52	RAVELING	Medium	354.35	SqFt	3.7%	FDOT - PATCHING - AC PARTIAL DEPTH	354.1	SqFt	\$ 4.00	\$ 1,420.00
ORL	TW E2	512	48	L & T CR	Medium	8.99	Ft	0.3%	FDOT - CRACK SEALING - AC	8.9	Ft	\$ 3.00	\$ 30.00
ORL	TW E2	512	52	RAVELING	Low	268.99	SqFt	10.0%	FDOT - SURFACE SEAL	269.1	SqFt	\$ 0.55	\$ 150.00
ORL	TW E3	417	48	L & T CR	Medium	368.96	Ft	4.4%	FDOT - CRACK SEALING - AC	369.1	Ft	\$ 3.00	\$ 1,110.00
ORL	TW E3	417	52	RAVELING	Medium	8178.63	SqFt	98.4%	FDOT - PATCHING - AC PARTIAL DEPTH	8178.4	SqFt	\$ 4.00	\$ 32,720.00
ORL	TW E3	420	45	DEPRESSION	Low	365.43	SqFt	1.0%	FDOT - PATCHING - AC FULL DEPTH	446.7	SqFt	\$ 9.00	\$ 4,020.00
ORL	TW E3	420	45	DEPRESSION	Medium	984.79	SqFt	2.7%	FDOT - PATCHING - AC FULL DEPTH	1115.1	SqFt	\$ 9.00	\$ 10,040.00
ORL	TW E3	420	45	DEPRESSION	High	310.97	SqFt	0.9%	FDOT - PATCHING - AC FULL DEPTH	386.4	SqFt	\$ 9.00	\$ 3,480.00
ORL	TW E3	420	48	L & T CR	Medium	225.46	Ft	0.6%	FDOT - CRACK SEALING - AC	225.4	Ft	\$ 3.00	\$ 680.00
ORL	TW E3	420	52	RAVELING	Low	35036.31	SqFt	96.3%	FDOT - SURFACE SEAL	35036.5	SqFt	\$ 0.55	\$ 19,280.00
ORL	TW E3	520	48	L & T CR	Medium	210.83	Ft	2.3%	FDOT - CRACK SEALING - AC	211	Ft	\$ 3.00	\$ 640.00
ORL	TW E3	520	52	RAVELING	Low	7533.12	SqFt	83.6%	FDOT - SURFACE SEAL	7533.7	SqFt	\$ 0.55	\$ 4,150.00
ORL	TW E3	520	52	RAVELING	Medium	674.68	SqFt	7.5%	FDOT - PATCHING - AC PARTIAL DEPTH	674.9	SqFt	\$ 4.00	\$ 2,700.00
ORL	TW E3	522	48	L & T CR	Medium	100.23	Ft	4.7%	FDOT - CRACK SEALING - AC	100.4	Ft	\$ 3.00	\$ 310.00
ORL	TW E3	522	52	RAVELING	Low	851.96	SqFt	39.9%	FDOT - SURFACE SEAL	852.5	SqFt	\$ 0.55	\$ 470.00
ORL	TW E4	1070	48	L & T CR	Medium	2100.75	Ft	1.6%	FDOT - CRACK SEALING - AC	2100.7	Ft	\$ 3.00	\$ 6,310.00
ORL	TW E4	1070	52	RAVELING	Low	108355.12	SqFt	82.8%	FDOT - SURFACE SEAL	108354.9	SqFt	\$ 0.55	\$ 59,600.00
ORL	TW E4	1070	52	RAVELING	Medium	22481.83	SqFt	17.2%	FDOT - PATCHING - AC PARTIAL DEPTH	22481.5	SqFt	\$ 4.00	\$ 89,930.00
ORL	TW E4	1080	48	L & T CR	Medium	131.36	Ft	1.6%	FDOT - CRACK SEALING - AC	131.2	Ft	\$ 3.00	\$ 400.00
ORL	TW E4	1080	52	RAVELING	Low	8393.05	SqFt	100.0%	FDOT - SURFACE SEAL	8392.6	SqFt	\$ 0.55	\$ 4,620.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
ORL	TW E4	1105	52	RAVELING	Low	2631.99	SqFt	40.0%	FDOT - SURFACE SEAL	2631.8	SqFt	\$ 0.55	\$ 1,450.00
ORL	TW E5	560	52	RAVELING	Low	5263.01	SqFt	95.0%	FDOT - SURFACE SEAL	5262.5	SqFt	\$ 0.55	\$ 2,900.00
ORL	TW E5	560	52	RAVELING	Medium	276.96	SqFt	5.0%	FDOT - PATCHING - AC PARTIAL DEPTH	276.6	SqFt	\$ 4.00	\$ 1,110.00
ORL	TW E6	805	52	RAVELING	Low	17742.05	SqFt	100.0%	FDOT - SURFACE SEAL	17742.2	SqFt	\$ 0.55	\$ 9,760.00
ORL	TW F	605	48	L & T CR	Medium	685.2	Ft	1.3%	FDOT - CRACK SEALING - AC	685	Ft	\$ 3.00	\$ 2,060.00
ORL	TW F	605	52	RAVELING	Low	41111.25	SqFt	75.0%	FDOT - SURFACE SEAL	41111.7	SqFt	\$ 0.55	\$ 22,620.00
ORL	TW F	605	52	RAVELING	Medium	13703.75	SqFt	25.0%	FDOT - PATCHING - AC PARTIAL DEPTH	13703.5	SqFt	\$ 4.00	\$ 54,820.00
ORL	TW G	705	52	RAVELING	Low	30099.02	SqFt	100.0%	FDOT - SURFACE SEAL	30099.1	SqFt	\$ 0.55	\$ 16,560.00
ORL	TW G	710	52	RAVELING	Low	9689.35	SqFt	98.8%	FDOT - SURFACE SEAL	9689.7	SqFt	\$ 0.55	\$ 5,330.00
ORL	TW G	710	52	RAVELING	Medium	122.6	SqFt	1.3%	FDOT - PATCHING - AC PARTIAL DEPTH	122.7	SqFt	\$ 4.00	\$ 500.00
ORL	TW H	806	48	L & T CR	Medium	2315.91	Ft	3.7%	FDOT - CRACK SEALING - AC	2315.9	Ft	\$ 3.00	\$ 6,950.00
ORL	TW H	806	52	RAVELING	Low	62451.99	SqFt	100.0%	FDOT - SURFACE SEAL	62452.2	SqFt	\$ 0.55	\$ 34,350.00
ORL	TW K	610	48	L & T CR	Medium	156.79	Ft	0.6%	FDOT - CRACK SEALING - AC	156.8	Ft	\$ 3.00	\$ 480.00
ORL	TW K	610	52	RAVELING	Low	340.79	SqFt	1.3%	FDOT - SURFACE SEAL	341.2	SqFt	\$ 0.55	\$ 190.00



Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ORL	AP GA	4205	AC	608,614	48	AC Restoration	\$ 6,102,000.00
2020	ORL	AP GA	4230	AC	23,614	60	AC Restoration	\$ 225,000.00
2020	ORL	AP N	4105	AC	200,966	5	AC Reconstruction	\$ 2,513,000.00
2020	ORL	AP N	4125	AC	140,429	4	AC Reconstruction	\$ 1,756,000.00
2020	ORL	AP N	4140	AC	237,860	24	AC Reconstruction	\$ 2,974,000.00
2020	ORL	AP N	4145	AC	122,500	33	AC Reconstruction	\$ 1,532,000.00
2020	ORL	AP N	4155	AC	337,449	48	AC Restoration	\$ 3,384,000.00
2020	ORL	AP N	4158	AAC	125,584	4	AC Reconstruction	\$ 1,570,000.00
2020	ORL	AP N	4165	AC	27,156	6	AC Reconstruction	\$ 340,000.00
2020	ORL	AP N	4167	AC	28,916	11	AC Reconstruction	\$ 362,000.00
2020	ORL	AP N	4168	PCC	24,538	0	PCC Reconstruction	\$ 491,000.00
2020	ORL	AP NE	4305	AC	52,643	22	AC Reconstruction	\$ 659,000.00
2020	ORL	AP NE	4312	AC	8,541	58	AC Restoration	\$ 82,000.00
2020	ORL	AP W	4605	AC	34,600	63	AC Restoration	\$ 329,000.00
2020	ORL	AP W	4610	AC	260,825	44	AC Restoration	\$ 2,940,000.00
2020	ORL	AP W	4650	AC	115,747	49	AC Restoration	\$ 1,125,000.00
2020	ORL	AP W	4670	AC	10,856	57	AC Restoration	\$ 104,000.00
2020	ORL	RW 7-25	6105	AAC	600,500	62	AC Restoration	\$ 5,705,000.00
2020	ORL	RW 7-25	6110	AAC	300,250	63	AC Restoration	\$ 2,853,000.00
2020	ORL	TW A	104	AC	11,949	65	AC Restoration	\$ 114,000.00
2020	ORL	TW A	115	AC	31,644	55	AC Restoration	\$ 301,000.00
2020	ORL	TW A	116	AC	11,579	62	AC Restoration	\$ 111,000.00
2020	ORL	TW A	117	AC	22,912	61	AC Restoration	\$ 218,000.00
2020	ORL	TW A	150	AC	60,358	56	AC Restoration	\$ 574,000.00
2020	ORL	TW A1	112	AAC	14,428	56	AC Restoration	\$ 138,000.00
2020	ORL	TW A2	120	AAC	30,935	64	AC Restoration	\$ 294,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	ORL	TW A4	140	AC	15,668	62	AC Restoration	\$ 149,000.00
2020	ORL	TW A5	405	AAC	37,049	64	AC Restoration	\$ 352,000.00
2020	ORL	TW B	102	AC	6,388	47	AC Restoration	\$ 66,000.00
2020	ORL	TW B	103	AAC	57,000	54	AC Restoration	\$ 542,000.00
2020	ORL	TW E	505	AC	78,110	64	AC Restoration	\$ 743,000.00
2020	ORL	TW E1	501	AC	5,073	49	AC Restoration	\$ 50,000.00
2020	ORL	TW E2	510	AC	9,644	45	AC Restoration	\$ 105,000.00
2020	ORL	TW E2	512	AC	2,687	60	AC Restoration	\$ 26,000.00
2020	ORL	TW E3	417	AC	8,311	28	AC Reconstruction	\$ 104,000.00
2020	ORL	TW E3	420	AC	36,384	49	AC Restoration	\$ 354,000.00
2020	ORL	TW E3	520	AC	9,009	45	AC Restoration	\$ 99,000.00
2020	ORL	TW E3	522	AC	2,133	47	AC Restoration	\$ 22,000.00
2020	ORL	TW E4	1070	AAC	130,837	49	AC Restoration	\$ 1,278,000.00
2020	ORL	TW E4	1080	AAC	8,393	55	AC Restoration	\$ 80,000.00
2020	ORL	TW E5	560	AC	5,540	64	AC Restoration	\$ 53,000.00
2020	ORL	TW F	605	AC	54,815	44	AC Restoration	\$ 613,000.00
2020	ORL	TW G	705	AC	30,099	53	AC Restoration	\$ 286,000.00
2020	ORL	TW G	710	AC	9,812	54	AC Restoration	\$ 94,000.00
2020	ORL	TW H	806	AC	62,452	51	AC Restoration	\$ 594,000.00
2021	ORL	AP N	4170	AC	84,878	64	AC Restoration	\$ 807,000.00
2021	ORL	AP W SEGM	4805	AAC	129,830	63	AC Restoration	\$ 1,234,000.00
2021	ORL	TW E6	805	AC	17,742	64	AC Restoration	\$ 169,000.00
2022	ORL	RW 13-31	6205	AC	445,836	64	AC Restoration	\$ 4,236,000.00
2022	ORL	TW A	125	AAC	257,040	64	AC Restoration	\$ 2,442,000.00
2022	ORL	TW A3	130	AAC	56,163	64	AC Restoration	\$ 534,000.00
2024	ORL	TW E4	1105	AC	6,580	64	AC Restoration	\$ 63,000.00
2024	ORL	TW K	610	AC	27,266	64	AC Restoration	\$ 260,000.00



Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2025	ORL	AP NE	4315	AAC	24,518	64	AC Restoration	\$ 233,000.00
2025	ORL	AP NE	4320	AAC	53,040	64	AC Restoration	\$ 504,000.00
2025	ORL	AP W SEGM	4810	AAC	79,530	64	AC Restoration	\$ 756,000.00
2025	ORL	TW A6	113	AC	26,953	64	AC Restoration	\$ 257,000.00
2026	ORL	AP RU	5110	AC	25,880	64	AC Restoration	\$ 246,000.00
2026	ORL	AP RU	5115	AC	36,282	63	AC Restoration	\$ 345,000.00
2026	ORL	AP RU	5120	AC	41,840	64	AC Restoration	\$ 398,000.00
2026	ORL	TW A5	425	AAC	9,443	64	AC Restoration	\$ 90,000.00
2027	ORL	AP N	4175	AC	42,594	64	AC Restoration	\$ 405,000.00

Appendix C

Technical Exhibits





001 - AIRFIELD PAVEMENT
NETWORK DEFINITION EXHIBIT

Airport Pavement Evaluation Report


2019

Statewide Airfield Pavement
Management Program

ORLANDO EXECUTIVE AIRPORT - ORL



GRAPHIC SCALE IN FEET
0 150 300 600




LEGEND

- RW 13-31** — TYPICAL RUNWAY BRANCH ID
- TW A** — TYPICAL TAXIWAY BRANCH ID
- AP S** — TYPICAL APRON BRANCH ID
- 4105** — SECTION NUMBER
AAC — PAVEMENT TYPE
50' X 75' — TYPICAL SAMPLE UNIT INFORMATION
1 1 — FLEXIBLE (AC) PAVEMENT NO. OF SLABS AND SLAB SIZE
1 1 — RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE
1 1 — NUMBER OF SAMPLE UNITS IN SECTION
1 1 — NUMBER OF SAMPLE UNITS TO BE INSPECTED
- 605** — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100** — INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 195
AC: 194 PCC: 1

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.





CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2015	TW A, TW B, TW E, TW E4, TW E5	MILL AND OVERLAY / 2" MILL AND VARIABLE OVERLAY P-401SP
2015	TW E6	RECONSTRUCTION - AC / 4" P-401, 10" P-219, COMPACTED SUBGRADE
2017	AP W	NEW CONSTRUCTION - AC
2019	AP W	MILL AND OVERLAY
2019	AP W	RECONSTRUCTION - PCC

PROJECTS	YEAR	2013
PROJECTS	YEAR	2014
PROJECTS	YEAR	2015
PROJECTS	YEAR	2016
PROJECTS	YEAR	2017
PROJECTS	YEAR	2018
PROJECTS	YEAR	2019
PROJECTS	YEAR	2020
PROJECTS	YEAR	2021
PROJECTS	YEAR	2022

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT
MATCH PUBLISHED RUNWAY LENGTHS.

FY 2020 AP GA: 4205 AC RESTORATION \$6.1 M	FY 2020 AP GA: 4230 AC RESTORATION \$0.23 M	FY 2020 AP N: 4105 AC RECONSTRUCTION \$2.51 M	FY 2020 AP N: 4125 AC RECONSTRUCTION \$1.76 M	FY 2020 AP N: 4140 AC RECONSTRUCTION \$2.97 M	FY 2020 AP N: 4145 AC RECONSTRUCTION \$1.53 M
FY 2020 AP N: 4155 AC RESTORATION \$3.38 M	FY 2020 AP N: 4158 AC RECONSTRUCTION \$1.57 M	FY 2020 AP N: 4165 AC RECONSTRUCTION \$0.34 M	FY 2020 AP N: 4167 AC RECONSTRUCTION \$0.36 M	FY 2020 AP N: 4168 PCC RECONSTRUCTION \$0.49 M	FY 2020 AP NE: 4305 AC RECONSTRUCTION \$0.66 M
FY 2020 AP NE: 4312 AC RESTORATION \$0.08 M	FY 2020 AP W: 4605 AC RESTORATION \$0.33 M	FY 2020 AP W: 4610 AC RESTORATION \$2.94 M	FY 2020 AP W: 4650 AC RESTORATION \$1.13 M	FY 2020 AP W: 4670 AC RESTORATION \$0.1 M	

FY 2020 RW 7-25: 6105 AC RESTORATION \$5.71 M	FY 2020 RW 7-25: 6110 AC RESTORATION \$2.85 M	FY 2020 TW A: 104 AC RESTORATION \$0.11 M	FY 2020 TW A: 115 AC RESTORATION \$0.3 M	FY 2020 TW A: 116 AC RESTORATION \$0.11 M	FY 2020 TW A: 117 AC RESTORATION \$0.22 M	FY 2020 TW A: 150 AC RESTORATION \$0.57 M
FY 2020 TW A1: 112 AC RESTORATION \$0.14 M	FY 2020 TW A2: 120 AC RESTORATION \$0.29 M	FY 2020 TW A4: 140 AC RESTORATION \$0.15 M	FY 2020 TW A5: 405 AC RESTORATION \$0.35 M	FY 2020 TW B: 102 AC RESTORATION \$0.07 M	FY 2020 TW B: 103 AC RESTORATION \$0.54 M	FY 2020 TW E: 505 AC RESTORATION \$0.74 M
FY 2020 TW E1: 501 AC RESTORATION \$0.05 M	FY 2020 TW E2: 510 AC RESTORATION \$0.11 M	FY 2020 TW E2: 512 AC RESTORATION \$0.03 M	FY 2020 TW E3: 417 AC RECONSTRUCTION \$0.1 M	FY 2020 TW E3: 420 AC RESTORATION \$0.35 M	FY 2020 TW E3: 520 AC RESTORATION \$0.1 M	FY 2020 TW E3: 522 AC RESTORATION \$0.02 M
FY 2020 TW E4: 1070 AC RESTORATION \$1.28 M	FY 2020 TW E4: 1080 AC RESTORATION \$0.08 M	FY 2020 TW E5: 560 AC RESTORATION \$0.05 M	FY 2020 TW F: 605 AC RESTORATION \$0.61 M	FY 2020 TW G: 705 AC RESTORATION \$0.29 M	FY 2020 TW G: 710 AC RESTORATION \$0.09 M	FY 2020 TW H: 806 AC RESTORATION \$0.59 M
FY 2022 TW A3: 130 AC RESTORATION \$0.53 M	FY 2024 TW E4: 1105 AC RESTORATION \$0.06 M	FY 2024 TW K: 610 AC RESTORATION \$0.26 M	FY 2025 AP NE: 4315 AC RESTORATION \$0.23 M	FY 2025 AP NE: 4320 AC RESTORATION \$0.5 M	FY 2025 AP W SEGM: 4810 AC RESTORATION \$0.76 M	FY 2025 TW A6: 113 AC RESTORATION \$0.26 M



- LEGEND**
- RW 13-31: TYPICAL RUNWAY BRANCH ID
 - TW A: TYPICAL TAXIWAY BRANCH ID
 - AP S: TYPICAL APRON BRANCH ID

PROGRAM YEAR

2020	2025
2021	2026
2022	2027
2023	2028
2024	2029

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.



004 - AIRFIELD PAVEMENT
MAJOR REHABILITATION EXHIBIT

Appendix D

Inspection Photograph Documentation




RW 7-25, Section 6105, Sample Unit 361 - Medium Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, and Low Severity (57) Weathering



RW 7-25, Section 6105, Sample Unit 403 - Low Severity (48) Longitudinal & Transverse Cracking, Medium Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering



RW 13-31, Section 6205, Sample Unit 156 – Low Severity (52) Raveling, Medium Severity (56) Swelling, and Low Severity (57) Weathering



RW 13-31, Section 6205, Sample Unit 159 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering



TWA, Section 125, Sample Unit 166 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, Low Severity (56) Swelling, and Low Severity (57) Weathering



TWE, Section 505, Sample Unit 112 - Medium Severity (48) Longitudinal & Transverse Cracking, and Low Severity (52) Raveling



TWE3, Section 420, Sample Unit 405 - Medium Severity (45) Depression, Medium Severity (48) Longitudinal & Transverse Cracking, and Low Severity (52) Raveling



TWF, Section 605, Sample Unit 611 - Low Severity (43) Block Cracking, and Low Severity (52) Raveling.



AP GA, Section 4205, Sample Unit 109 - Medium Severity (43) Block Cracking, Low Severity (52) Raveling, and Low Severity (56) Swelling



AP N, Section 4125, Sample Unit 513 - Medium Severity (43) Block Cracking and Medium Severity (52) Raveling



AP N, Section 4125, Sample Unit 210 - Medium Severity (41) Alligator Cracking, Medium Severity (52) Raveling, and Medium Severity (53) Rutting



AP W, Section 4610, Sample Unit 531 - Medium Severity (43) Block Cracking, Low Severity (52) Raveling, and Low Severity (56) Swelling

Appendix E

Inspection Distress Details

Re-Inspection Report

FDOT

Generated Date 9/19/2019

Page 1 of 86

Network:	ORL	Name:					ORLANDO EXECUTIVE AIRPORT		
Branch:	AP GA	Name:	GA APRON	Use:	APRON	Area:	632,228 SqFt		
Section:	4205	of	2	From:	-	To:	-	Last Const.:	1/1/1984
Surface:	AC	Family:	C9N59-RL-AP-AC	Zone:		Category:		Rank:	P
Area:	608,614 SqFt	Length:	1,675 Ft	Width:		364 Ft			
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1984	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	4/1/2007	Work Type:			Surface Treatment - Slurry Seal	Code:	ST-SS	Is Major M&R:	False
Last Insp. Date:	3/4/2019	TotalSamples:		118	Surveyed:		10		
Conditions:	PCI:	49							
Inspection Comments:									
Sample Number:	109	Type:	R	Area:	5000.00 SqFt	PCI:	40		
Sample Comments:									
56	SWELLING	L	50.00	SqFt					
52	RAVELING	L	5000.00	SqFt					
43	BLOCK CR	L	3250.00	SqFt					
43	BLOCK CR	M	1750.00	SqFt					
Sample Number:	154	Type:	R	Area:	5000.00 SqFt	PCI:	47		
Sample Comments:									
43	BLOCK CR	L	4500.00	SqFt					
52	RAVELING	L	5000.00	SqFt					
43	BLOCK CR	M	500.00	SqFt					
Sample Number:	165	Type:	R	Area:	5000.00 SqFt	PCI:	51		
Sample Comments:									
52	RAVELING	L	5000.00	SqFt					
43	BLOCK CR	M	150.00	SqFt					
43	BLOCK CR	L	4850.00	SqFt					
Sample Number:	209	Type:	R	Area:	5000.00 SqFt	PCI:	41		
Sample Comments:									
52	RAVELING	M	250.00	SqFt					
43	BLOCK CR	L	4500.00	SqFt					
43	BLOCK CR	M	500.00	SqFt					
52	RAVELING	L	4750.00	SqFt					
56	SWELLING	L	100.00	SqFt					
Sample Number:	251	Type:	R	Area:	5000.00 SqFt	PCI:	47		
Sample Comments:									
43	BLOCK CR	L	4500.00	SqFt					
52	RAVELING	L	3000.00	SqFt					
56	SWELLING	L	100.00	SqFt					
43	BLOCK CR	M	500.00	SqFt					
Sample Number:	305	Type:	R	Area:	5000.00 SqFt	PCI:	51		
Sample Comments:									
48	L & T CR	M	775.00	Ft					
52	RAVELING	L	5000.00	SqFt					
Sample Number:	314	Type:	R	Area:	5000.00 SqFt	PCI:	47		
Sample Comments:									
43	BLOCK CR	L	4800.00	SqFt					
52	RAVELING	L	5000.00	SqFt					

43	BLOCK CR	M	200.00	SqFt
56	SWELLING	L	270.00	SqFt
<hr/>				
Sample Number: 359		Type: R	Area: 5000.00	PCI: 56
Sample Comments:				
43	BLOCK CR	L	4640.00	SqFt
52	RAVELING	L	5000.00	SqFt
48	L & T CR	L	38.00	Ft
<hr/>				
Sample Number: 400		Type: R	Area: 6400.00	PCI: 52
Sample Comments:				
43	BLOCK CR	M	320.00	SqFt
56	SWELLING	L	25.00	SqFt
43	BLOCK CR	L	6080.00	SqFt
52	RAVELING	L	3500.00	SqFt
<hr/>				
Sample Number: 413		Type: R	Area: 6400.00	PCI: 52
Sample Comments:				
52	RAVELING	M	320.00	SqFt
52	RAVELING	L	6080.00	SqFt
43	BLOCK CR	L	6400.00	SqFt

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	AP GA		Name:	GA APRON		Use:	APRON	Area:	632,228 SqFt		
Section:	4230	of 2	From:	-			To:	-		Last Const.:	12/25/1999
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	P	
Area:	23,614 SqFt		Length:	1,129 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	12/25/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Work Date:	4/1/2007		Work Type:	Surface Treatment - Slurry Seal			Code:	ST-SS		Is Major M&R:	False
Last Insp. Date: 3/4/2019											
TotalSamples: 6											
Surveyed: 1											
Conditions: PCI: 61											
Inspection Comments:											
Sample Number:	202	Type:	R	Area:	3501.00 SqFt		PCI:	61			
Sample Comments:											
52	RAVELING		L	2000.00 SqFt							
48	L & T CR		L	161.00 Ft							
43	BLOCK CR		L	1750.00 SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT												
Branch:	AP N		Name:	NORTH APRON		Use:	APRON		Area:	1,468,444 SqFt							
Section:	4105		of	13	From:	-		To:	-		Last Const.:	1/1/1979					
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:	Rank:		T					
Area:	200,966 SqFt		Length:	500 Ft		Width:	370 Ft										
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft								
Shoulder:	Street Type:				Grade:	0		Lanes:	0								
Section Comments:																	
Work Date:	1/1/1979		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1984		Work Type:				REPAIR		Code:	IMPORTED		Is Major M&R:	False				
Last Insp. Date:													3/4/2019	TotalSamples:	42	Surveyed:	5
Conditions:	PCI:		6														
Inspection Comments:																	
Sample Number:	102		Type:	R		Area:	5000.00 SqFt		PCI:	8							
Sample Comments:																	
52	RAVELING		M		4372.00	SqFt											
43	BLOCK CR		H		4372.00	SqFt											
56	SWELLING		L		200.00	SqFt											
50	PATCHING		M		550.00	SqFt											
50	PATCHING		L		78.00	SqFt											
Sample Number:	205		Type:	R		Area:	5000.00 SqFt		PCI:	5							
Sample Comments:																	
43	BLOCK CR		H		5000.00	SqFt											
52	RAVELING		H		5000.00	SqFt											
Sample Number:	208		Type:	R		Area:	5000.00 SqFt		PCI:	4							
Sample Comments:																	
53	RUTTING		M		294.00	SqFt											
50	PATCHING		M		4.00	SqFt											
53	RUTTING		L		406.00	SqFt											
43	BLOCK CR		M		4832.00	SqFt											
52	RAVELING		H		4996.00	SqFt											
41	ALLIGATOR CR		L		164.00	SqFt											
Sample Number:	302		Type:	R		Area:	5000.00 SqFt		PCI:	5							
Sample Comments:																	
43	BLOCK CR		H		5000.00	SqFt											
52	RAVELING		H		1000.00	SqFt											
52	RAVELING		M		4000.00	SqFt											
Sample Number:	408		Type:	R		Area:	5000.00 SqFt		PCI:	8							
Sample Comments:																	
52	RAVELING		M		5000.00	SqFt											
41	ALLIGATOR CR		L		35.00	SqFt											
43	BLOCK CR		H		4965.00	SqFt											

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT										
Branch:	AP N		Name:	NORTH APRON		Use:	APRON		Area:	1,468,444 SqFt					
Section:	4125		of	13		From:	-		To:	-		Last Const.:	1/1/1978		
Surface:	AC		Family:	C9N59-RL-AP-AC			Zone:				Category:	Rank: P			
Area:	140,429 SqFt			Length:	400 Ft		Width:	350 Ft							
Slabs:				Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:				Street Type:			Grade:	0		Lanes:	0				
Section Comments:															
Work Date:	1/1/1978			Work Type:	BUILT					Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1984			Work Type:	REPAIR					Code:	IMPORTED		Is Major M&R:	False	
Last Insp. Date:	3/4/2019			TotalSamples:	27		Surveyed:	3							
Conditions:	PCI: 5														
Inspection Comments:															
Sample Number:	210		Type:	R		Area:	6750.00 SqFt			PCI:	1				
Sample Comments:															
53	RUTTING		L	665.00 SqFt											
52	RAVELING		M	6750.00 SqFt											
41	ALLIGATOR CR		M	325.00 SqFt											
53	RUTTING		M	280.00 SqFt											
43	BLOCK CR		H	6425.00 SqFt											
Sample Number:	511		Type:	R		Area:	5000.00 SqFt			PCI:	8				
Sample Comments:															
52	RAVELING		M	4500.00 SqFt											
52	RAVELING		H	500.00 SqFt											
43	BLOCK CR		H	500.00 SqFt											
43	BLOCK CR		M	4500.00 SqFt											
Sample Number:	513		Type:	R		Area:	5000.00 SqFt			PCI:	8				
Sample Comments:															
43	BLOCK CR		H	500.00 SqFt											
43	BLOCK CR		M	4500.00 SqFt											
52	RAVELING		H	500.00 SqFt											
52	RAVELING		M	4500.00 SqFt											

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	AP N		Name:	NORTH APRON		Use:	APRON	Area:	1,468,444 SqFt		
Section:	4140	of	13	From:	-	To:	-	Last Const.:	1/1/1979		
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:	Category:		Rank:	P		
Area:	237,860 SqFt		Length:	1,000 Ft		Width:	200 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0	Lanes:		0			
Section Comments:											
Work Date:	1/1/1979		Work Type:			BUILT		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1984		Work Type:			REPAIR		Code:	IMPORTED	Is Major M&R:	False
Work Date:	8/1/2012		Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	3/4/2019		TotalSamples:	46		Surveyed:		6			
Conditions:	PCI:	25									
Inspection Comments:											
Sample Number:	517	Type:	R	Area:	5600.00 SqFt		PCI:	19			
Sample Comments:											
48	L & T CR		L	113.00 Ft							
43	BLOCK CR		L	492.00 SqFt							
43	BLOCK CR		M	3360.00 SqFt							
52	RAVELING		H	5600.00 SqFt							
Sample Number:	561	Type:	R	Area:	5000.00 SqFt		PCI:	29			
Sample Comments:											
52	RAVELING		M	2500.00 SqFt							
52	RAVELING		L	2500.00 SqFt							
43	BLOCK CR		M	5000.00 SqFt							
Sample Number:	614	Type:	R	Area:	5000.00 SqFt		PCI:	22			
Sample Comments:											
43	BLOCK CR		M	5000.00 SqFt							
52	RAVELING		M	5000.00 SqFt							
56	SWELLING		L	200.00 SqFt							
Sample Number:	619	Type:	R	Area:	5000.00 SqFt		PCI:	29			
Sample Comments:											
52	RAVELING		L	2500.00 SqFt							
52	RAVELING		M	2500.00 SqFt							
43	BLOCK CR		M	5000.00 SqFt							
Sample Number:	667	Type:	R	Area:	5000.00 SqFt		PCI:	29			
Sample Comments:											
43	BLOCK CR		M	5000.00 SqFt							
52	RAVELING		M	2500.00 SqFt							
52	RAVELING		L	2500.00 SqFt							
Sample Number:	712	Type:	R	Area:	7183.00 SqFt		PCI:	22			
Sample Comments:											
43	BLOCK CR		M	7183.00 SqFt							
52	RAVELING		M	7183.00 SqFt							
56	SWELLING		L	718.00 SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT									
Branch:	AP N		Name:	NORTH APRON		Use:	APRON		Area:	1,468,444 SqFt				
Section:	4145		of	13		From:	-		To:	-		Last Const.:	1/1/1968	
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:			Rank:	P	
Area:	122,500 SqFt			Length:	700 Ft			Width:	200 Ft					
Slabs:				Slab Length:	Ft			Slab Width:	Ft			Joint Length:	Ft	
Shoulder:				Street Type:				Grade:	0			Lanes:	0	
Section Comments:														
Work Date:	1/1/1968			Work Type:	BUILT			Code:	IMPORTED			Is Major M&R:	True	
Work Date:	1/1/1984			Work Type:	REPAIR			Code:	IMPORTED			Is Major M&R:	False	
Work Date:	8/1/2012			Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC			Is Major M&R:	False	
Last Insp. Date:	3/4/2019			TotalSamples:	27			Surveyed:	3					
Conditions:	PCI: 34													
Inspection Comments:														
Sample Number:	363		Type:	R		Area:	5000.00 SqFt			PCI:	31			
Sample Comments:														
52	RAVELING		H	20.00 SqFt										
48	L & T CR		L	166.00 Ft										
50	PATCHING		M	504.00 SqFt										
52	RAVELING		M	4476.00 SqFt										
Sample Number:	416		Type:	R		Area:	4204.00 SqFt			PCI:	38			
Sample Comments:														
52	RAVELING		M	4204.00 SqFt										
48	L & T CR		L	108.00 Ft										
Sample Number:	466		Type:	R		Area:	4204.00 SqFt			PCI:	33			
Sample Comments:														
48	L & T CR		L	55.00 Ft										
43	BLOCK CR		L	1700.00 SqFt										
52	RAVELING		M	4204.00 SqFt										

Network:		ORL		Name:		ORLANDO EXECUTIVE AIRPORT																									
Branch:		AP N		Name:		NORTH APRON		Use:		APRON		Area:		1,468,444 SqFt																	
Section:		4155		of 13		From:		-		To:		-		Last Const.: 1/1/1984																	
Surface:		AC		Family:		C9N59-RL-AP-AC		Zone:		Category:		Rank:		P																	
Area:		337,449 SqFt		Length:		3,985 Ft		Width:		200 Ft																					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																			
Shoulder:		Street Type:		Grade:		0		Lanes:		0																					
Section Comments:																															
Work Date:				1/1/1984				Work Type:				BUILT				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				8/1/2012				Work Type:				Surface Treatment - Seal Coat				Code:				ST-SC				Is Major M&R:				False			
Last Insp. Date:				3/4/2019				TotalSamples:				69				Surveyed:				7											
Conditions:				PCI:				49																							
Inspection Comments:																															
Sample Number:		106		Type:		R		Area:		5000.00 SqFt		PCI:		59																	
Sample Comments:																															
43		BLOCK CR		L		5000.00 SqFt																									
52		RAVELING		L		5000.00 SqFt																									
Sample Number:		113		Type:		R		Area:		5000.00 SqFt		PCI:		54																	
Sample Comments:																															
43		BLOCK CR		M		50.00 SqFt																									
52		RAVELING		L		5000.00 SqFt																									
43		BLOCK CR		L		4950.00 SqFt																									
Sample Number:		166		Type:		R		Area:		5000.00 SqFt		PCI:		33																	
Sample Comments:																															
52		RAVELING		M		5000.00 SqFt																									
48		L & T CR		L		499.00 Ft																									
43		BLOCK CR		L		400.00 SqFt																									
Sample Number:		169		Type:		R		Area:		4961.00 SqFt		PCI:		33																	
Sample Comments:																															
43		BLOCK CR		L		1422.00 SqFt																									
48		L & T CR		L		268.00 Ft																									
52		RAVELING		M		4961.00 SqFt																									
Sample Number:		210		Type:		R		Area:		5000.00 SqFt		PCI:		59																	
Sample Comments:																															
52		RAVELING		L		5000.00 SqFt																									
43		BLOCK CR		L		5000.00 SqFt																									
Sample Number:		254		Type:		R		Area:		3699.00 SqFt		PCI:		42																	
Sample Comments:																															
52		RAVELING		L		3699.00 SqFt																									
43		BLOCK CR		M		3699.00 SqFt																									
Sample Number:		264		Type:		R		Area:		4700.00 SqFt		PCI:		59																	
Sample Comments:																															
52		RAVELING		L		4700.00 SqFt																									
43		BLOCK CR		L		4700.00 SqFt																									

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	1,468,444 SqFt			
Section:	4158	of 13	From:	-		To:	-		Last Const.:	1/1/2002	
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC	Zone:			Category:	Rank: P			
Area:	125,584 SqFt	Length:	580 Ft		Width:	215 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1984		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2002		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Work Date:	8/1/2012		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date: 3/4/2019											
		TotalSamples:	25		Surveyed:		3				
Conditions: PCI: 6											
Inspection Comments:											
Sample Number:	151	Type:	R	Area:	4995.00 SqFt		PCI:	5			
Sample Comments:											
43	BLOCK CR	H	4995.00	SqFt							
52	RAVELING	H	1499.00	SqFt							
52	RAVELING	M	3496.00	SqFt							
Sample Number:	350	Type:	R	Area:	5000.00 SqFt		PCI:	5			
Sample Comments:											
43	BLOCK CR	H	5000.00	SqFt							
52	RAVELING	H	500.00	SqFt							
52	RAVELING	M	4500.00	SqFt							
Sample Number:	651	Type:	R	Area:	5472.00 SqFt		PCI:	8			
Sample Comments:											
43	BLOCK CR	H	5472.00	SqFt							
45	DEPRESSION	L	204.00	SqFt							
52	RAVELING	M	5472.00	SqFt							

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	AP N		Name:	NORTH APRON		Use:	APRON	Area:	1,468,444 SqFt		
Section:	4165	of 13	From:	-			To:	-		Last Const.:	1/1/1984
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	P	
Area:	27,156 SqFt		Length:	270 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1984		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	8/1/2012		Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	3/4/2019		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI:		7								
Inspection Comments:											
Sample Number:	653	Type:	R	Area:	5505.00 SqFt		PCI:	7			
Sample Comments:											
45	DEPRESSION	L	207.00	SqFt							
43	BLOCK CR	H	1505.00	SqFt							
43	BLOCK CR	M	4000.00	SqFt							
52	RAVELING	M	5505.00	SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	1,468,444 SqFt	
Section:	4166	of 13	From:	-	To:	-	Last Const.:	9/1/2012	
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:	Rank: P	
Area:	22,635 SqFt	Length:	440 Ft		Width:	50 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1984	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	9/1/2012	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	3/4/2019	TotalSamples:	6		Surveyed:	1			
Conditions:	PCI: 89								
Inspection Comments:									
Sample Number:	609	Type:	R	Area:	3500.00 SqFt		PCI:	89	
Sample Comments:									
48	L & T CR	L	34.00 Ft						
57	WEATHERING	L	3500.00 SqFt						

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT					
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	1,468,444 SqFt		
Section:	4167	of	13	From:	-	To:	-	Last Const.:	1/1/1984	
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	P
Area:	28,916 SqFt		Length:	450 Ft		Width:	60 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1984		Work Type:			New Construction - Initial		Code:	NU-IN	
Work Date:	8/1/2012		Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	
Work Date:	8/1/2012		Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	
Work Date:	8/1/2012		Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	
Last Insp. Date:	3/4/2019		TotalSamples:	5		Surveyed:	1			
Conditions:	PCI: 12									
Inspection Comments:										
Sample Number:	507	Type:	R	Area:	6700.00 SqFt		PCI:	12		
Sample Comments:										
41	ALLIGATOR CR		L	210.00	SqFt					
43	BLOCK CR		M	4698.00	SqFt					
52	RAVELING		H	6.00	SqFt					
45	DEPRESSION		L	104.00	SqFt					
52	RAVELING		M	5094.00	SqFt					
50	PATCHING		L	1600.00	SqFt					
41	ALLIGATOR CR		M	192.00	SqFt					

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT			
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	1,468,444 SqFt
Section:	4168	of 13	From:	-	To:	-	Last Const.:	1/1/2005
Surface:	PCC	Family:	C9N59-RL-AP-PCC	Zone:		Category:	Rank:	P
Area:	24,538 SqFt	Length:	500 Ft	Width:	50 Ft			
Slabs:	51	Slab Length:	20 Ft	Slab Width:	24 Ft	Joint Length:	1,742 Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/2005	Work Type: New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	3/4/2019	TotalSamples:	4	Surveyed:	1			
Conditions:	PCI:							
Inspection Comments:								
Sample Number:	558	Type:	R	Area:	12.00 Slabs	PCI:		
Sample Comments:								
72	SHAT. SLAB	H	3.00	Slabs				
72	SHAT. SLAB	M	9.00	Slabs				
65	JT SEAL DMG	H	12.00	Slabs				

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT								
Branch:	AP N		Name:	NORTH APRON		Use:	APRON		Area:	1,468,444 SqFt			
Section:	4169		of	13	From:	-		To:	-		Last Const.:	9/1/2012	
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:			Rank:	P
Area:	72,939 SqFt		Length:	400 Ft		Width:	200 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	9/1/2012		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:	3/4/2019		TotalSamples:	16		Surveyed:	3						
Conditions:	PCI:	86											
Inspection Comments:													
Sample Number:	309		Type:	R		Area:	6190.00 SqFt		PCI:	89			
Sample Comments:													
48	L & T CR		L	85.00 Ft									
57	WEATHERING		L	6190.00 SqFt									
Sample Number:	357		Type:	R		Area:	5000.00 SqFt		PCI:	85			
Sample Comments:													
57	WEATHERING		L	4750.00 SqFt									
48	L & T CR		L	8.00 Ft									
52	RAVELING		L	250.00 SqFt									
Sample Number:	456		Type:	R		Area:	5151.00 SqFt		PCI:	84			
Sample Comments:													
48	L & T CR		L	39.00 Ft									
57	WEATHERING		L	4893.00 SqFt									
52	RAVELING		L	258.00 SqFt									

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT									
Branch:	AP N		Name:	NORTH APRON		Use:	APRON		Area:	1,468,444 SqFt				
Section:	4170		of	13		From:	-		To:	-		Last Const.:	1/1/1984	
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:			Rank:	P	
Area:	84,878 SqFt		Length:	850 Ft		Width:			100 Ft					
Slabs:			Slab Length:			Ft	Slab Width:			Ft	Joint Length:			Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1984			Work Type: New Construction - AC					Code:	NC-AC		Is Major M&R: True		
Work Date:	8/1/2012			Work Type: Surface Treatment - Seal Coat					Code:	ST-SC		Is Major M&R: False		
Last Insp. Date:	3/4/2019			TotalSamples:	18		Surveyed: 3							
Conditions:	PCI: 67													
Inspection Comments:														
Sample Number:	656		Type:	R		Area:	4253.00 SqFt		PCI:	70				
Sample Comments:														
45	DEPRESSION		L	3.00 SqFt										
57	WEATHERING		M	3828.00 SqFt										
52	RAVELING		L	425.00 SqFt										
48	L & T CR		L	149.00 Ft										
Sample Number:	810		Type:	R		Area:	6578.00 SqFt		PCI:	71				
Sample Comments:														
48	L & T CR		L	57.00 Ft										
57	WEATHERING		M	4342.00 SqFt										
57	WEATHERING		L	1578.00 SqFt										
52	RAVELING		L	658.00 SqFt										
Sample Number:	906		Type:	R		Area:	4957.00 SqFt		PCI:	59				
Sample Comments:														
43	BLOCK CR		L	2340.00 SqFt										
52	RAVELING		L	2200.00 SqFt										
57	WEATHERING		M	1400.00 SqFt										
57	WEATHERING		L	1357.00 SqFt										

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT									
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	1,468,444 SqFt					
Section:	4175	of 13	From:	-		To:	-		Last Const.:	1/1/1960			
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:	Category:		Rank:		P			
Area:	42,594 SqFt	Length:	250 Ft		Width:	165 Ft							
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:		Street Type:			Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	1/1/1960		Work Type:			BUILT		Code:	IMPORTED		Is Major M&R:	True	
Work Date:	8/1/2012		Work Type:			Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	3/4/2019		TotalSamples:	9		Surveyed:		2					
Conditions:	PCI: 76												
Inspection Comments:													
Sample Number:	101	Type:	R	Area:	4923.00 SqFt		PCI:	68					
Sample Comments:													
56	SWELLING		L	32.00	SqFt								
52	RAVELING		L	1250.00	SqFt								
57	WEATHERING		L	3673.00	SqFt								
48	L & T CR		L	161.00	Ft								
45	DEPRESSION		L	118.00	SqFt								
Sample Number:	400	Type:	R	Area:	5000.00 SqFt		PCI:	84					
Sample Comments:													
57	WEATHERING		L	4750.00	SqFt								
48	L & T CR		L	19.00	Ft								
52	RAVELING		L	250.00	SqFt								

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	AP NE		Name:	NE APRON		Use:	APRON	Area:	138,742 SqFt			
Section:	4305		of	4	From:	-		To:	-	Last Const.:	1/1/1984	
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	P	
Area:	52,643 SqFt		Length:	500 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1984		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	11		Surveyed:	2					
Conditions:	PCI:	23										
Inspection Comments:												
Sample Number:	350		Type:	R		Area:	5242.00 SqFt		PCI:	32		
Sample Comments:												
43	BLOCK CR		M	5242.00 SqFt								
53	RUTTING		L	150.00 SqFt								
56	SWELLING		L	486.00 SqFt								
52	RAVELING		L	5242.00 SqFt								
Sample Number:	404		Type:	R		Area:	4127.00 SqFt		PCI:	11		
Sample Comments:												
43	BLOCK CR		M	3082.00 SqFt								
52	RAVELING		H	10.00 SqFt								
50	PATCHING		H	37.00 SqFt								
45	DEPRESSION		L	64.00 SqFt								
52	RAVELING		M	3072.00 SqFt								
50	PATCHING		M	1008.00 SqFt								

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	AP NE		Name:	NE APRON		Use:	APRON	Area:	138,742 SqFt		
Section:	4312	of 4	From:	-			To:	-		Last Const.:	12/25/1999
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:	Rank: P	
Area:	8,541 SqFt		Length:	450 Ft		Width:	20 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	12/25/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	59									
Inspection Comments:											
Sample Number:	307	Type:	R	Area:	4300.00 SqFt		PCI:	59			
Sample Comments:											
48	L & T CR		L	194.00 Ft							
52	RAVELING		L	750.00 SqFt							
45	DEPRESSION		L	265.00 SqFt							
57	WEATHERING		L	3000.00 SqFt							
57	WEATHERING		M	550.00 SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT									
Branch:	AP NE		Name:	NE APRON		Use:	APRON		Area:	138,742 SqFt				
Section:	4315		of	4		From:	-		To:	-		Last Const.:	1/1/2007	
Surface:	AAC		Family:	C9N59-RL-AP-AAC-APC		Zone:			Category:			Rank:	P	
Area:	24,518 SqFt		Length:	600 Ft		Width:	40 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	12/25/1999		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Work Date:	1/1/2007		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	3/4/2019		TotalSamples:	5		Surveyed:	1							
Conditions:	PCI: 77													
Inspection Comments:														
Sample Number:	151		Type:	R		Area:	4857.00 SqFt		PCI:	77				
Sample Comments:														
52	RAVELING		L	900.00 SqFt										
57	WEATHERING		L	3957.00 SqFt										
48	L & T CR		L	76.00 Ft										

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	AP NE		Name:	NE APRON		Use:	APRON	Area:	138,742 SqFt		
Section:	4320	of	4	From:	-	To:	-	Last Const.:	1/1/2007		
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC		Zone:		Category:		Rank:	P	
Area:	53,040 SqFt		Length:	1,000 Ft		Width:	50 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1984		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2007		Work Type:	Mill and Overlay			Code:	ML-OL		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	14		Surveyed:	2				
Conditions:	PCI: 77										
Inspection Comments:											
Sample Number:	252	Type:	R	Area:	4000.00 SqFt		PCI:	79			
Sample Comments:											
52	RAVELING		L	800.00	SqFt						
57	WEATHERING		L	3200.00	SqFt						
48	L & T CR		L	2.00	Ft						
Sample Number:	301	Type:	R	Area:	3500.00 SqFt		PCI:	75			
Sample Comments:											
48	L & T CR		L	108.00	Ft						
52	RAVELING		L	800.00	SqFt						
57	WEATHERING		L	2700.00	SqFt						

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	AP RU		Name:	RUN-UP APRONS		Use:	APRON	Area:	104,002 SqFt	
Section:	5110	of 3	From:	-			To:	-	Last Const.:	1/1/2001
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	P
Area:	25,880 SqFt	Length:	233 Ft		Width:	100 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2001		Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	5		Surveyed:	1			
Conditions:	PCI:	75								
Inspection Comments:										
Sample Number:	302	Type:	R	Area:	5750.00 SqFt		PCI:	75		
Sample Comments:										
52	RAVELING	L	288.00 SqFt							
56	SWELLING	L	100.00 SqFt							
48	L & T CR	L	168.00 Ft							
57	WEATHERING	L	5462.00 SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	AP RU		Name:	RUN-UP APRONS		Use:	APRON	Area:	104,002 SqFt
Section:	5115	of 3	From:	-			To:	-	Last Const.: 1/1/2001
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank: P
Area:	36,282 SqFt		Length:	255 Ft		Width:	130 Ft		
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/2001		Work Type: New Construction - Initial			Code:	NU-IN		Is Major M&R: True
Last Insp. Date:	3/4/2019		TotalSamples:	7		Surveyed:	1		
Conditions:	PCI: 74								
Inspection Comments:									
Sample Number:	202	Type:	R	Area:	6850.00 SqFt		PCI:	74	
Sample Comments:									
52	RAVELING		L	700.00 SqFt					
48	L & T CR		L	251.00 Ft					
57	WEATHERING		L	6150.00 SqFt					
56	SWELLING		L	100.00 SqFt					

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	AP RU		Name:	RUN-UP APRONS		Use:	APRON		Area:	104,002 SqFt	
Section:	5120		of	3		From:	-		To:	-	
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:	Rank: P	
Area:	41,840 SqFt		Length:	420 Ft		Width:	100 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2001		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	3/4/2019		TotalSamples:	8		Surveyed:	1				
Conditions:	PCI: 75										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	6750.00 SqFt		PCI:	75	
Sample Comments:											
57	WEATHERING		L	6412.00 SqFt							
52	RAVELING		L	338.00 SqFt							
56	SWELLING		L	325.00 SqFt							
48	L & T CR		L	169.00 Ft							

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	AP W	Name:	WEST APRON		Use:	APRON	Area:	615,449 SqFt		
Section:	4605	of	8	From:	-	To:	-	Last Const.:	1/1/2002	
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	P
Area:	34,600 SqFt		Length:	700 Ft		Width:	50 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1942		Work Type:			BUILT		Code:	IMPORTED	
Work Date:	1/1/1942		Work Type:			OVERLAY		Code:	IMPORTED	
Work Date:	1/1/2002		Work Type:			Complete Reconstruction - AC		Code:	CR-AC	
Work Date:	1/1/2015		Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	
Is Major M&R: False										
Last Insp. Date:	3/4/2019		TotalSamples:	7		Surveyed:	1			
Conditions:	PCI: 64									
Inspection Comments:										
Sample Number:	282	Type:	R	Area:	5000.00 SqFt		PCI:	64		
Sample Comments:										
49	OIL SPILLAGE		N	6.00 SqFt						
57	WEATHERING		M	4000.00 SqFt						
48	L & T CR		L	156.00 Ft						
43	BLOCK CR		L	78.00 SqFt						
52	RAVELING		L	1000.00 SqFt						

Network:	ORL		Name:		ORLANDO EXECUTIVE AIRPORT									
Branch:	AP W		Name:		WEST APRON		Use:	APRON	Area:	615,449 SqFt				
Section:	4610	of 8		From:	-			To:	-		Last Const.:	1/1/1999		
Surface:	AC	Family:		C9N59-RL-AP-AC		Zone:		Category:		Rank:		P		
Area:	260,825 SqFt		Length:		150 Ft		Width:		1,700 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:	Street Type:				Grade:		0		Lanes:		0			
Section Comments:														
Work Date:	1/1/1999		Work Type:					BUILT		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2015		Work Type:					Surface Treatment - Seal Coat		Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	3/4/2019		TotalSamples:		58		Surveyed:		6					
Conditions:	PCI:		45											
Inspection Comments:														
Sample Number:	421	Type:	R	Area:		4307.00 SqFt		PCI:		38				
Sample Comments:														
50	PATCHING	L		369.00 SqFt										
43	BLOCK CR	M		2363.00 SqFt										
52	RAVELING	L		3938.00 SqFt										
43	BLOCK CR	L		1575.00 SqFt										
Sample Number:	424	Type:	R	Area:		4307.00 SqFt		PCI:		34				
Sample Comments:														
45	DEPRESSION	L		104.00 SqFt										
43	BLOCK CR	L		2757.00 SqFt										
43	BLOCK CR	M		1500.00 SqFt										
52	RAVELING	L		4257.00 SqFt										
56	SWELLING	L		75.00 SqFt										
50	PATCHING	L		50.00 SqFt										
Sample Number:	434	Type:	R	Area:		4307.00 SqFt		PCI:		51				
Sample Comments:														
48	L & T CR	L		118.00 Ft										
52	RAVELING	L		4307.00 SqFt										
56	SWELLING	L		100.00 SqFt										
43	BLOCK CR	L		3700.00 SqFt										
Sample Number:	439	Type:	R	Area:		4307.00 SqFt		PCI:		54				
Sample Comments:														
43	BLOCK CR	L		4307.00 SqFt										
52	RAVELING	L		4307.00 SqFt										
56	SWELLING	L		129.00 SqFt										
Sample Number:	531	Type:	R	Area:		3793.00 SqFt		PCI:		38				
Sample Comments:														
52	RAVELING	L		3793.00 SqFt										
43	BLOCK CR	L		2276.00 SqFt										
56	SWELLING	L		303.00 SqFt										
43	BLOCK CR	M		1517.00 SqFt										
Sample Number:	542	Type:	R	Area:		5000.00 SqFt		PCI:		55				
Sample Comments:														
52	RAVELING	L		4840.00 SqFt										
50	PATCHING	L		160.00 SqFt										
43	BLOCK CR	L		4840.00 SqFt										

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	AP W		Name:	WEST APRON		Use:	APRON		Area:	615,449 SqFt		
Section:	4640		of	8	From:	-		To:	-		Last Const.:	3/1/2019
Surface:	AAC		Family:	C9N59-RL-AP-AAC-APC		Zone:			Category:	Rank: P		
Area:	157,964 SqFt		Length:	450 Ft		Width:	350 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	1/1/1997		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	12/1/1998		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R: True		
Work Date:	1/1/2015		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False		
Work Date:	3/1/2019		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True		
Last Insp. Date:	1/15/2015		TotalSamples:	16		Surveyed:	3					
Conditions:	PCI: 62		NOTE: *** Pre-Construction PCI ***									
Inspection Comments:												
Sample Number:	514		Type:	R		Area:	4489.00 SqFt		PCI:	62		
Sample Comments:												
57	WEATHERING		M	4489.00 SqFt								
43	BLOCK CRACKING		L	1044.00 SqFt								
43	BLOCK CRACKING		L	550.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	276.00 Ft								
Sample Number:	612		Type:	R		Area:	5000.00 SqFt		PCI:	69		
Sample Comments:												
48	LONGITUDINAL/TRANSVERSE CRACKING		L	437.00 Ft								
57	WEATHERING		M	5000.00 SqFt								
56	SWELLING		L	292.00 SqFt								
Sample Number:	812		Type:	R		Area:	4243.00 SqFt		PCI:	54		
Sample Comments:												
57	WEATHERING		M	4243.00 SqFt								
43	BLOCK CRACKING		L	4243.00 SqFt								
56	SWELLING		L	424.00 SqFt								

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	AP W	Name:	WEST APRON		Use:	APRON	Area:	615,449 SqFt			
Section:	4650	of 8	From:	-		To:	-		Last Const.:	12/1/1998	
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:			Category:	Rank: P		
Area:	115,747 SqFt		Length:	520 Ft		Width:	220 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1997		Work Type: New Construction - PCC				Code:	NC-PC		Is Major M&R:	True
Work Date:	1/2/1997		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	12/1/1998		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Work Date:	1/1/2015		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	3/4/2019		TotalSamples:	24		Surveyed:	4				
Conditions:	PCI: 50										
Inspection Comments:											
Sample Number:	306	Type:	R	Area:	5597.00 SqFt		PCI:	47			
Sample Comments:											
52	RAVELING	L	5597.00 SqFt								
43	BLOCK CR	L	5037.00 SqFt								
43	BLOCK CR	M	560.00 SqFt								
Sample Number:	503	Type:	R	Area:	4983.00 SqFt		PCI:	45			
Sample Comments:											
43	BLOCK CR	M	498.00 SqFt								
45	DEPRESSION	L	25.00 SqFt								
43	BLOCK CR	L	4485.00 SqFt								
52	RAVELING	L	4983.00 SqFt								
Sample Number:	701	Type:	R	Area:	6000.00 SqFt		PCI:	54			
Sample Comments:											
43	BLOCK CR	L	6000.00 SqFt								
45	DEPRESSION	L	1.00 SqFt								
56	SWELLING	L	150.00 SqFt								
52	RAVELING	L	6000.00 SqFt								
Sample Number:	804	Type:	R	Area:	4250.00 SqFt		PCI:	54			
Sample Comments:											
43	BLOCK CR	L	4250.00 SqFt								
56	SWELLING	L	225.00 SqFt								
52	RAVELING	L	4250.00 SqFt								

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT								
Branch:	AP W		Name:	WEST APRON		Use:	APRON	Area:	615,449 SqFt			
Section:	4665	of	8	From:	-	To:	-	Last Const.:	6/1/2019			
Surface:	PCC	Family:	C9N59-RL-AP-PCC		Zone:		Category:		Rank:	P		
Area:	8,833 SqFt		Length:	150 Ft		Width:	60 Ft					
Slabs:	27	Slab Length:	12 Ft		Slab Width:	30 Ft		Joint Length:	840 Ft			
Shoulder:		Street Type:			Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	1/1/1997		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	6/1/2019		Work Type:	Complete Reconstruction - PCC				Code:	CR-PC		Is Major M&R:	True
Last Insp. Date:	1/15/2015		TotalSamples:	6		Surveyed:	1					
Conditions:	PCI: 31		NOTE:	*** Pre-Construction PCI ***								
Inspection Comments:												
Sample Number:	911	Type:	R	Area:	27.00 Slabs		PCI:	31				
Sample Comments:												
63	LINEAR CRACKING		L	17.00	Slabs							
72	SHATTERED SLAB		L	1.00	Slabs							
75	CORNER SPALLING		M	1.00	Slabs							
75	CORNER SPALLING		H	1.00	Slabs							
74	JOINT SPALLING		H	5.00	Slabs							
63	LINEAR CRACKING		M	1.00	Slabs							
74	JOINT SPALLING		M	4.00	Slabs							
73	SHRINKAGE CRACKING		N	17.00	Slabs							
75	CORNER SPALLING		L	2.00	Slabs							
70	SCALING		L	27.00	Slabs							
74	JOINT SPALLING		L	6.00	Slabs							
65	JOINT SEAL DAMAGE		H	27.00	Slabs							
63	LINEAR CRACKING		M	1.00	Slabs							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT								
Branch:	AP W		Name:	WEST APRON		Use:	APRON		Area:	615,449 SqFt			
Section:	4670		of	8	From:	-		To:	-		Last Const.:	12/1/1998	
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:	Rank:		P	
Area:	10,856 SqFt		Length:	110 Ft		Width:	100 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	1/1/1997		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/1/1998		Work Type:				Complete Reconstruction - AC		Code:	CR-AC		Is Major M&R:	True
Work Date:	1/1/2015		Work Type:				Surface Treatment - Seal Coat		Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	3/4/2019		TotalSamples:	3		Surveyed:	1						
Conditions:	PCI:		58										
Inspection Comments:													
Sample Number:	813		Type:	R		Area:	3600.00 SqFt		PCI:	58			
Sample Comments:													
48	L & T CR		L	97.00		Ft							
52	RAVELING		L	3600.00		SqFt							
56	SWELLING		L	120.00		SqFt							
43	BLOCK CR		L	1520.00		SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	AP W		Name:	WEST APRON		Use:	APRON	Area:	615,449 SqFt		
Section:	4675 of 8		From:	-		To:	-		Last Const.:	3/1/2019	
Surface:	PCC		Family:	C9N59-RL-AP-PCC		Zone:			Rank:	P	
Area:	1,760 SqFt		Length:	44 Ft		Width:	40 Ft				
Slabs:	30		Slab Length:	10 Ft		Slab Width:	11 Ft		Joint Length:	252 Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1997		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/1/1998		Work Type: Surface Reconstruction - AC				Code:	SR-AC		Is Major M&R:	True
Work Date:	1/1/2015		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	3/1/2019		Work Type: Complete Reconstruction - PCC				Code:	CR-PC		Is Major M&R:	True
Last Insp. Date:	1/15/2015		TotalSamples:	16		Surveyed:	3				
Conditions:	PCI: 62		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	514		Type:	R		Area:	4489.00 SqFt		PCI:	62	
Sample Comments:											
48	LONGITUDINAL/TRANSVERSE CRACKING		L	276.00 Ft							
57	WEATHERING		M	4489.00 SqFt							
43	BLOCK CRACKING		L	550.00 SqFt							
43	BLOCK CRACKING		L	1044.00 SqFt							
Sample Number:	612		Type:	R		Area:	5000.00 SqFt		PCI:	69	
Sample Comments:											
56	SWELLING		L	292.00 SqFt							
57	WEATHERING		M	5000.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	437.00 Ft							
Sample Number:	812		Type:	R		Area:	4243.00 SqFt		PCI:	54	
Sample Comments:											
43	BLOCK CRACKING		L	4243.00 SqFt							
57	WEATHERING		M	4243.00 SqFt							
56	SWELLING		L	424.00 SqFt							

Network:	ORL		Name:		ORLANDO EXECUTIVE AIRPORT											
Branch:	AP W SEGM		Name:		SE SEGMENT OF WEST APRON		Use:	APRON	Area:	209,360 SqFt						
Section:	4805		of 2		From:		-		To:		-		Last Const.:		1/1/2001	
Surface:	AAC		Family:		C9N59-RL-AP-AAC-APC		Zone:		Category:		Rank:		P			
Area:	129,830 SqFt		Length:		535 Ft		Width:		245 Ft							
Slabs:			Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:			Street Type:				Grade:		0		Lanes:		0			
Section Comments:																
Work Date:	1/1/1960		Work Type:		New Construction - Initial				Code:	NU-IN		Is Major M&R:		True		
Work Date:	1/1/2001		Work Type:		Surface Reconstruction - AC				Code:	SR-AC		Is Major M&R:		True		
Work Date:	1/1/2015		Work Type:		Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:		False		
Last Insp. Date:	3/4/2019		TotalSamples:		26		Surveyed:		3							
Conditions:	PCI:		67													
Inspection Comments:																
Sample Number:	207		Type:	R		Area:		4500.00 SqFt		PCI:		66				
Sample Comments:																
43	BLOCK CR		L	150.00		SqFt										
48	L & T CR		L	475.00		Ft										
57	WEATHERING		M	4500.00		SqFt										
Sample Number:	211		Type:	R		Area:		5357.00 SqFt		PCI:		70				
Sample Comments:																
52	RAVELING		L	268.00		SqFt										
48	L & T CR		L	172.00		Ft										
57	WEATHERING		M	5089.00		SqFt										
Sample Number:	315		Type:	R		Area:		5000.00 SqFt		PCI:		64				
Sample Comments:																
57	WEATHERING		L	5000.00		SqFt										
48	L & T CR		L	176.00		Ft										
42	BLEEDING		N	7.00		SqFt										
56	SWELLING		L	8.00		SqFt										
43	BLOCK CR		L	1500.00		SqFt										

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT					
Branch:	AP W SEGM		Name:	SE SEGMENT OF WEST APRON		Use:	APRON	Area:	209,360 SqFt
Section:	4810	of 2	From:	-			To:	-	
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC		Zone:		Category:	Rank: P	
Area:	79,530 SqFt	Length:	400 Ft		Width:	200 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:		Street Type:			Grade:	0		Lanes:	0
Section Comments:									
Work Date:	1/1/1960	Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True	
Work Date:	1/1/1960	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True	
Work Date:	1/1/2012	Work Type: Mill and Overlay				Code:	ML-OL	Is Major M&R: True	
Last Insp. Date:	3/4/2019	TotalSamples:	15		Surveyed:	3			
Conditions:	PCI: 77								
Inspection Comments:									
Sample Number:	138	Type:	R	Area:	6100.00 SqFt		PCI:	85	
Sample Comments:									
57	WEATHERING	L	6039.00 SqFt						
48	L & T CR	L	129.00 Ft						
52	RAVELING	L	61.00 SqFt						
Sample Number:	290	Type:	R	Area:	5000.00 SqFt		PCI:	73	
Sample Comments:									
45	DEPRESSION	L	144.00 SqFt						
48	L & T CR	L	256.00 Ft						
57	WEATHERING	L	4975.00 SqFt						
52	RAVELING	L	25.00 SqFt						
Sample Number:	394	Type:	R	Area:	5500.00 SqFt		PCI:	73	
Sample Comments:									
49	OIL SPILLAGE	N	4.00 SqFt						
57	WEATHERING	L	5390.00 SqFt						
45	DEPRESSION	L	18.00 SqFt						
52	RAVELING	L	110.00 SqFt						
48	L & T CR	L	264.00 Ft						

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	RW 13-31	Name:	RUNWAY 13-31	Use:	RUNWAY	Area:	445,836 SqFt			
Section:	6205	of	1	From:	-	To:	-	Last Const.:	1/1/1999	
Surface:	AC	Family:	C9N59-RL-RW-AC	Zone:		Category:		Rank:	P	
Area:	445,836 SqFt	Length:	4,500 Ft	Width:	100 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0			
Section Comments:										
Work Date:	1/1/1999	Work Type:			New Construction - AC		Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	3/4/2019	TotalSamples:	89	Surveyed:	18					
Conditions:	PCI: 66									
Inspection Comments:										
Sample Number:	108	Type:	R	Area:	5000.00 SqFt	PCI:	40			
Sample Comments:										
45	DEPRESSION	L	211.00	SqFt						
52	RAVELING	L	874.00	SqFt						
56	SWELLING	L	140.00	SqFt						
52	RAVELING	M	1150.00	SqFt						
48	L & T CR	M	60.00	Ft						
48	L & T CR	L	185.00	Ft						
56	SWELLING	M	5.00	SqFt						
Sample Number:	115	Type:	R	Area:	5000.00 SqFt	PCI:	64			
Sample Comments:										
52	RAVELING	L	500.00	SqFt						
56	SWELLING	L	450.00	SqFt						
48	L & T CR	L	180.00	Ft						
48	L & T CR	M	50.00	Ft						
57	WEATHERING	L	4500.00	SqFt						
Sample Number:	122	Type:	R	Area:	5000.00 SqFt	PCI:	68			
Sample Comments:										
56	SWELLING	L	539.00	SqFt						
48	L & T CR	L	194.00	Ft						
52	RAVELING	L	500.00	SqFt						
57	WEATHERING	L	4500.00	SqFt						
Sample Number:	129	Type:	R	Area:	5000.00 SqFt	PCI:	62			
Sample Comments:										
52	RAVELING	L	1800.00	SqFt						
52	RAVELING	M	160.00	SqFt						
48	L & T CR	M	100.00	Ft						
56	SWELLING	L	200.00	SqFt						
48	L & T CR	L	115.00	Ft						
Sample Number:	138	Type:	R	Area:	5000.00 SqFt	PCI:	74			
Sample Comments:										
57	WEATHERING	L	4750.00	SqFt						
56	SWELLING	L	164.00	SqFt						
48	L & T CR	L	175.00	Ft						
52	RAVELING	L	250.00	SqFt						
Sample Number:	142	Type:	R	Area:	5000.00 SqFt	PCI:	77			
Sample Comments:										
48	L & T CR	L	166.00	Ft						
56	SWELLING	L	40.00	SqFt						
52	RAVELING	L	500.00	SqFt						
57	WEATHERING	L	4500.00	SqFt						
Sample Number:	145	Type:	R	Area:	5000.00 SqFt	PCI:	73			
Sample Comments:										

57	WEATHERING	L	4500.00	SqFt
48	L & T CR	L	182.00	Ft
56	SWELLING	L	155.00	SqFt
52	RAVELING	L	500.00	SqFt
Sample Number: 152 Type: R Area: 6887.00 SqFt PCI: 70				
Sample Comments:				
57	WEATHERING	L	6198.00	SqFt
56	SWELLING	L	230.00	SqFt
48	L & T CR	L	351.00	Ft
52	RAVELING	L	689.00	SqFt
Sample Number: 156 Type: R Area: 5000.00 SqFt PCI: 61				
Sample Comments:				
48	L & T CR	L	371.00	Ft
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	500.00	SqFt
56	SWELLING	M	4.00	SqFt
57	WEATHERING	L	4500.00	SqFt
Sample Number: 159 Type: R Area: 5000.00 SqFt PCI: 59				
Sample Comments:				
56	SWELLING	L	525.00	SqFt
57	WEATHERING	L	4500.00	SqFt
52	RAVELING	L	500.00	SqFt
48	L & T CR	L	616.00	Ft
Sample Number: 163 Type: R Area: 5000.00 SqFt PCI: 61				
Sample Comments:				
57	WEATHERING	L	4250.00	SqFt
48	L & T CR	L	518.00	Ft
56	SWELLING	L	300.00	SqFt
52	RAVELING	L	750.00	SqFt
Sample Number: 169 Type: R Area: 5000.00 SqFt PCI: 63				
Sample Comments:				
48	L & T CR	L	467.00	Ft
57	WEATHERING	L	3900.00	SqFt
56	SWELLING	L	250.00	SqFt
52	RAVELING	L	1100.00	SqFt
Sample Number: 175 Type: R Area: 5000.00 SqFt PCI: 67				
Sample Comments:				
56	SWELLING	L	425.00	SqFt
57	WEATHERING	L	4500.00	SqFt
48	L & T CR	L	338.00	Ft
52	RAVELING	L	500.00	SqFt
Sample Number: 182 Type: R Area: 5000.00 SqFt PCI: 73				
Sample Comments:				
56	SWELLING	L	300.00	SqFt
52	RAVELING	L	500.00	SqFt
48	L & T CR	L	177.00	Ft
57	WEATHERING	L	4500.00	SqFt
Sample Number: 185 Type: R Area: 5000.00 SqFt PCI: 71				
Sample Comments:				
57	WEATHERING	L	4500.00	SqFt
56	SWELLING	L	375.00	SqFt
52	RAVELING	L	500.00	SqFt
48	L & T CR	L	195.00	Ft
Sample Number: 191 Type: R Area: 5000.00 SqFt PCI: 66				
Sample Comments:				
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	600.00	SqFt
57	WEATHERING	L	4500.00	SqFt

48	L & T CR	L	189.00	Ft		
Sample Number: 195		Type: R	Area: 5000.00 SqFt		PCI: 71	
Sample Comments:						
57	WEATHERING	L	4500.00	SqFt		
52	RAVELING	L	500.00	SqFt		
48	L & T CR	L	227.00	Ft		
56	SWELLING	L	300.00	SqFt		
Sample Number: 198		Type: R	Area: 5000.00 SqFt		PCI: 64	
Sample Comments:						
57	WEATHERING	L	3850.00	SqFt		
52	RAVELING	L	1150.00	SqFt		
48	L & T CR	L	435.00	Ft		
56	SWELLING	L	400.00	SqFt		

Network:	ORL		Name:		ORLANDO EXECUTIVE AIRPORT							
Branch:	RW 7-25		Name:		RUNWAY 7-25		Use:	RUNWAY	Area:	900,750 SqFt		
Section:	6105		of 2		From:	-		To:	-		Last Const.:	1/2/2001
Surface:	AAC		Family:	C9N59-RL-RW-AAC-APC		Zone:			Category:	Rank: T		
Area:	600,500 SqFt		Length:	6,005 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1977		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2001		Work Type: Cold Milling					Code:	MI-CO		Is Major M&R:	False
Work Date:	1/2/2001		Work Type: Overlay - AC Structural					Code:	OL-AS		Is Major M&R:	True
Last Insp. Date: 3/4/2019												
			TotalSamples:	120		Surveyed: 20						
Conditions:	PCI: 63											
Inspection Comments:												
Sample Number:	300		Type:	R		Area:	5000.00 SqFt		PCI:	59		
Sample Comments:												
48	L & T CR		M	10.00 Ft								
56	SWELLING		L	45.00 SqFt								
57	WEATHERING		M	2171.00 SqFt								
45	DEPRESSION		L	27.00 SqFt								
57	WEATHERING		L	1447.00 SqFt								
52	RAVELING		L	1382.00 SqFt								
48	L & T CR		L	257.00 Ft								
Sample Number:	306		Type:	R		Area:	5000.00 SqFt		PCI:	66		
Sample Comments:												
48	L & T CR		L	429.00 Ft								
57	WEATHERING		L	4500.00 SqFt								
56	SWELLING		L	40.00 SqFt								
52	RAVELING		L	500.00 SqFt								
Sample Number:	312		Type:	R		Area:	5000.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		L	401.00 Ft								
52	RAVELING		M	268.00 SqFt								
56	SWELLING		L	50.00 SqFt								
48	L & T CR		M	50.00 Ft								
52	RAVELING		L	473.00 SqFt								
Sample Number:	316		Type:	R		Area:	5000.00 SqFt		PCI:	63		
Sample Comments:												
52	RAVELING		L	500.00 SqFt								
56	SWELLING		L	50.00 SqFt								
57	WEATHERING		L	4500.00 SqFt								
48	L & T CR		M	15.00 Ft								
48	L & T CR		L	350.00 Ft								
Sample Number:	321		Type:	R		Area:	5000.00 SqFt		PCI:	63		
Sample Comments:												
48	L & T CR		M	50.00 Ft								
56	SWELLING		L	100.00 SqFt								
48	L & T CR		L	293.00 Ft								
52	RAVELING		L	1628.00 SqFt								
57	WEATHERING		L	3372.00 SqFt								
Sample Number:	328		Type:	R		Area:	5000.00 SqFt		PCI:	59		
Sample Comments:												
48	L & T CR		M	100.00 Ft								
57	WEATHERING		L	4500.00 SqFt								

56	SWELLING	L	313.00	SqFt
48	L & T CR	L	423.00	Ft
52	RAVELING	L	500.00	SqFt
Sample Number: 335 Type: R Area: 5000.00 SqFt PCI: 63				
Sample Comments:				
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	50.00	SqFt
57	WEATHERING	L	4500.00	SqFt
48	L & T CR	L	304.00	Ft
48	L & T CR	M	150.00	Ft
Sample Number: 342 Type: R Area: 5000.00 SqFt PCI: 63				
Sample Comments:				
48	L & T CR	M	100.00	Ft
48	L & T CR	L	315.00	Ft
56	SWELLING	L	125.00	SqFt
57	WEATHERING	L	4500.00	SqFt
52	RAVELING	L	500.00	SqFt
Sample Number: 350 Type: R Area: 5000.00 SqFt PCI: 63				
Sample Comments:				
48	L & T CR	M	130.00	Ft
48	L & T CR	L	298.00	Ft
57	WEATHERING	L	4500.00	SqFt
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	63.00	SqFt
Sample Number: 356 Type: R Area: 5000.00 SqFt PCI: 59				
Sample Comments:				
52	RAVELING	L	350.00	SqFt
48	L & T CR	M	150.00	Ft
56	SWELLING	L	100.00	SqFt
57	WEATHERING	L	4650.00	SqFt
48	L & T CR	L	420.00	Ft
Sample Number: 361 Type: R Area: 5000.00 SqFt PCI: 57				
Sample Comments:				
56	SWELLING	L	175.00	SqFt
57	WEATHERING	L	4750.00	SqFt
52	RAVELING	L	250.00	SqFt
48	L & T CR	M	100.00	Ft
48	L & T CR	L	495.00	Ft
Sample Number: 371 Type: R Area: 5000.00 SqFt PCI: 67				
Sample Comments:				
48	L & T CR	L	278.00	Ft
48	L & T CR	M	100.00	Ft
57	WEATHERING	L	4500.00	SqFt
56	SWELLING	L	18.00	SqFt
52	RAVELING	L	500.00	SqFt
Sample Number: 379 Type: R Area: 5000.00 SqFt PCI: 63				
Sample Comments:				
52	RAVELING	L	480.00	SqFt
52	RAVELING	M	200.00	SqFt
48	L & T CR	L	392.00	Ft
48	L & T CR	M	60.00	Ft
56	SWELLING	L	20.00	SqFt
Sample Number: 384 Type: R Area: 5000.00 SqFt PCI: 69				
Sample Comments:				
48	L & T CR	L	303.00	Ft
57	WEATHERING	L	4500.00	SqFt
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	65.00	SqFt

Sample Number: 391		Type: R	Area: 5000.00 SqFt		PCI: 68
Sample Comments:					
48	L & T CR	M	50.00	Ft	
56	SWELLING	L	50.00	SqFt	
57	WEATHERING	L	4500.00	SqFt	
52	RAVELING	L	500.00	SqFt	
48	L & T CR	L	233.00	Ft	
Sample Number: 397		Type: R	Area: 5000.00 SqFt		PCI: 67
Sample Comments:					
48	L & T CR	L	444.00	Ft	
52	RAVELING	L	2500.00	SqFt	
57	WEATHERING	L	2500.00	SqFt	
56	SWELLING	L	10.00	SqFt	
Sample Number: 403		Type: R	Area: 5000.00 SqFt		PCI: 57
Sample Comments:					
56	SWELLING	L	50.00	SqFt	
48	L & T CR	M	55.00	Ft	
52	RAVELING	L	500.00	SqFt	
57	WEATHERING	L	4500.00	SqFt	
48	L & T CR	L	566.00	Ft	
Sample Number: 409		Type: R	Area: 5000.00 SqFt		PCI: 59
Sample Comments:					
48	L & T CR	L	491.00	Ft	
56	SWELLING	L	60.00	SqFt	
57	WEATHERING	L	4500.00	SqFt	
48	L & T CR	M	50.00	Ft	
52	RAVELING	L	500.00	SqFt	
Sample Number: 412		Type: R	Area: 5000.00 SqFt		PCI: 61
Sample Comments:					
48	L & T CR	M	40.00	Ft	
52	RAVELING	L	500.00	SqFt	
56	SWELLING	L	75.00	SqFt	
48	L & T CR	L	375.00	Ft	
57	WEATHERING	L	4500.00	SqFt	
Sample Number: 418		Type: R	Area: 5000.00 SqFt		PCI: 64
Sample Comments:					
48	L & T CR	L	521.00	Ft	
52	RAVELING	L	1500.00	SqFt	
57	WEATHERING	M	3500.00	SqFt	
56	SWELLING	L	25.00	SqFt	

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	RW 7-25		Name:	RUNWAY 7-25		Use:	RUNWAY		Area:	900,750 SqFt	
Section:	6110 of 2		From:	-		To:	-		Last Const.:	1/2/2001	
Surface:	AAC		Family:	C9N59-RL-RW-AAC-APC		Zone:			Category:	Rank: P	
Area:	300,250 SqFt		Length:	12,010 Ft		Width:	25 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1977		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2001		Work Type: Cold Milling				Code:	MI-CO		Is Major M&R:	False
Work Date:	1/2/2001		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Last Insp. Date: 3/4/2019											
			TotalSamples:	60		Surveyed: 12					
Conditions:	PCI: 64										
Inspection Comments:											
Sample Number:	100		Type:	R		Area:	5000.00 SqFt		PCI:	67	
Sample Comments:											
52	RAVELING		M	165.00 SqFt							
52	RAVELING		L	2868.00 SqFt							
48	L & T CR		L	119.00 Ft							
56	SWELLING		L	15.00 SqFt							
Sample Number:	124		Type:	R		Area:	5000.00 SqFt		PCI:	69	
Sample Comments:											
56	SWELLING		L	450.00 SqFt							
52	RAVELING		L	535.00 SqFt							
48	L & T CR		L	279.00 Ft							
57	WEATHERING		L	4465.00 SqFt							
Sample Number:	152		Type:	R		Area:	5000.00 SqFt		PCI:	70	
Sample Comments:											
48	L & T CR		L	244.00 Ft							
56	SWELLING		L	250.00 SqFt							
57	WEATHERING		L	4180.00 SqFt							
52	RAVELING		L	820.00 SqFt							
Sample Number:	176		Type:	R		Area:	5000.00 SqFt		PCI:	65	
Sample Comments:											
52	RAVELING		L	915.00 SqFt							
57	WEATHERING		L	4085.00 SqFt							
56	SWELLING		L	75.00 SqFt							
48	L & T CR		L	424.00 Ft							
Sample Number:	196		Type:	R		Area:	5000.00 SqFt		PCI:	66	
Sample Comments:											
52	RAVELING		M	176.00 SqFt							
48	L & T CR		L	222.00 Ft							
52	RAVELING		L	2272.00 SqFt							
56	SWELLING		L	75.00 SqFt							
Sample Number:	216		Type:	R		Area:	5125.00 SqFt		PCI:	62	
Sample Comments:											
48	L & T CR		L	454.00 Ft							
52	RAVELING		M	330.00 SqFt							
48	L & T CR		M	10.00 Ft							
52	RAVELING		L	1026.00 SqFt							
56	SWELLING		L	20.00 SqFt							
Sample Number:	500		Type:	R		Area:	5000.00 SqFt		PCI:	52	
Sample Comments:											

52	RAVELING	M	1680.00	SqFt
52	RAVELING	L	790.00	SqFt
56	SWELLING	L	50.00	SqFt
48	L & T CR	L	243.00	Ft
<hr/>				
Sample Number: 524		Type: R	Area: 5000.00	PCI: 66
Sample Comments:				
52	RAVELING	L	820.00	SqFt
56	SWELLING	L	500.00	SqFt
57	WEATHERING	L	4180.00	SqFt
48	L & T CR	L	369.00	Ft
<hr/>				
Sample Number: 552		Type: R	Area: 5000.00	PCI: 66
Sample Comments:				
48	L & T CR	L	351.00	Ft
57	WEATHERING	L	4180.00	SqFt
56	SWELLING	L	200.00	SqFt
52	RAVELING	L	820.00	SqFt
<hr/>				
Sample Number: 568		Type: R	Area: 5000.00	PCI: 61
Sample Comments:				
56	SWELLING	L	400.00	SqFt
48	L & T CR	L	524.00	Ft
57	WEATHERING	L	4180.00	SqFt
52	RAVELING	L	820.00	SqFt
<hr/>				
Sample Number: 596		Type: R	Area: 5000.00	PCI: 65
Sample Comments:				
56	SWELLING	L	96.00	SqFt
52	RAVELING	M	140.00	SqFt
48	L & T CR	L	105.00	Ft
52	RAVELING	L	2360.00	SqFt
<hr/>				
Sample Number: 616		Type: R	Area: 5125.00	PCI: 65
Sample Comments:				
56	SWELLING	L	35.00	SqFt
48	L & T CR	L	338.00	Ft
48	L & T CR	M	20.00	Ft
52	RAVELING	M	370.00	SqFt
52	RAVELING	L	951.00	SqFt

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	429,472 SqFt		
Section:	104	of	9	From:	-			To:	-		
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:				Category:		
Area:	11,949 SqFt		Length:	195 Ft		Width:	65 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0			Lanes:	0		
Section Comments:											
Work Date:	1/1/2001		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	66									
Inspection Comments:											
Sample Number:	098	Type:	R	Area:	6016.00 SqFt		PCI:	66			
Sample Comments:											
57	WEATHERING		L	5266.00	SqFt						
56	SWELLING		L	331.00	SqFt						
48	L & T CR		L	440.00	Ft						
52	RAVELING		L	750.00	SqFt						

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW A	Name:	TAXIWAY A		Use:	TAXIWAY	Area:	429,472 SqFt		
Section:	114	of	9	From:	-	To:	-	Last Const.:	1/1/1999	
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	12,579 SqFt		Length:	200 Ft		Width:	50 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1999		Work Type:			BUILT		Code:	IMPORTED	
								Is Major M&R:	True	
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed:	1			
Conditions:	PCI:	78								
Inspection Comments:										
Sample Number:	102	Type:	R	Area:	6113.00 SqFt		PCI:	78		
Sample Comments:										
52	RAVELING		L	1000.00 SqFt						
57	WEATHERING		L	5113.00 SqFt						
48	L & T CR		L	162.00 Ft						

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	429,472 SqFt		
Section:	115	of 9	From:	-			To:	-		Last Const.:	1/1/1984
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	31,644 SqFt		Length:	870 Ft		Width:	38 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1984		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	8		Surveyed:	1				
Conditions:	PCI:	56									
Inspection Comments:											
Sample Number:	106	Type:	R	Area:	3750.00 SqFt		PCI:	56			
Sample Comments:											
48	L & T CR		M	100.00 Ft							
48	L & T CR		L	335.00 Ft							
52	RAVELING		M	50.00 SqFt							
52	RAVELING		L	3700.00 SqFt							

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW A	Name:	TAXIWAY A		Use:	TAXIWAY	Area:	429,472 SqFt		
Section:	116	of	9	From:	-	To:	-	Last Const.:	1/1/1984	
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	11,579 SqFt	Length:	60 Ft	Width:	150 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:		Street Type:		Grade:	0	Lanes:	0			
Section Comments:										
Work Date:	1/1/1984	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True	
Last Insp. Date:	3/4/2019	TotalSamples:	3	Surveyed:	1					
Conditions:	PCI:	63								
Inspection Comments:										
Sample Number:	114	Type:	R	Area:	2998.00 SqFt	PCI:	63			
Sample Comments:										
52	RAVELING	L	2998.00	SqFt						
48	L & T CR	M	10.00	Ft						
48	L & T CR	L	329.00	Ft						

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	429,472 SqFt		
Section:	117	of 9	From:	-			To:	-		Last Const.:	1/1/1984
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	22,912 SqFt		Length:	390 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1984		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI:	62									
Inspection Comments:											
Sample Number:	119	Type:	R	Area:	4516.00 SqFt		PCI:	62			
Sample Comments:											
52	RAVELING		L	4516.00 SqFt							
48	L & T CR		L	307.00 Ft							
48	L & T CR		M	118.00 Ft							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT					
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	429,472 SqFt	
Section:	118	of	9	From:	-	To:	-	Last Const.:	10/1/2015	
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:	P	
Area:	12,843 SqFt		Length:	208 Ft		Width:	47 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	1/1/1984		Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	10/1/2015		Work Type:			MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	3		Surveyed:				1
Conditions:	PCI:	94								
Inspection Comments:										
Sample Number:	111	Type:	R	Area:	4885.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	4885.00 SqFt						

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	429,472 SqFt		
Section:	119	of	9	From:	-	To:	-	Last Const.:	10/1/2015
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	8,568 SqFt	Length:	104 Ft	Width:	78 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1984	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	10/1/2015	Work Type:			MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/4/2019	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI: 89								
Inspection Comments:									
Sample Number:	113	Type:	R	Area:	3415.00 SqFt	PCI:	89		
Sample Comments:									
48	L & T CR	L	30.00 Ft						
57	WEATHERING	L	3415.00 SqFt						

Network:		ORL		Name:		ORLANDO EXECUTIVE AIRPORT																	
Branch:		TW A		Name:		TAXIWAY A		Use:		TAXIWAY		Area:		429,472 SqFt									
Section:		125		of		9		From:		-		To:		-		Last Const.:		1/1/1997					
Surface:		AAC		Family:		C9N59-RL-TW-AAC-APC		Zone:				Category:				Rank:		P					
Area:		257,040 SqFt		Length:		3,400 Ft		Width:		75 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				1/1/1960				Work Type:				New Construction - Initial				Code:		NU-IN		Is Major M&R:		True	
Work Date:				1/1/1997				Work Type:				Overlay - AC Structural				Code:		OL-AS		Is Major M&R:		True	
Last Insp. Date:				3/4/2019				TotalSamples:				68				Surveyed:				7			
Conditions:				PCI:				67															
Inspection Comments:																							
Sample Number:				116				Type:		R		Area:				3750.00 SqFt				PCI:		62	
Sample Comments:																							
42		BLEEDING				N				10.00		SqFt											
56		SWELLING				L				175.00		SqFt											
48		L & T CR				L				310.00		Ft											
52		RAVELING				L				400.00		SqFt											
57		WEATHERING				L				3350.00		SqFt											
Sample Number:				126				Type:		R		Area:				3750.00 SqFt				PCI:		73	
Sample Comments:																							
52		RAVELING				L				400.00		SqFt											
48		L & T CR				L				161.00		Ft											
57		WEATHERING				L				3350.00		SqFt											
56		SWELLING				L				50.00		SqFt											
Sample Number:				134				Type:		R		Area:				3750.00 SqFt				PCI:		70	
Sample Comments:																							
57		WEATHERING				L				3637.00		SqFt											
52		RAVELING				L				113.00		SqFt											
56		SWELLING				L				163.00		SqFt											
48		L & T CR				L				193.00		Ft											
Sample Number:				141				Type:		R		Area:				3750.00 SqFt				PCI:		70	
Sample Comments:																							
52		RAVELING				L				400.00		SqFt											
57		WEATHERING				L				3350.00		SqFt											
56		SWELLING				L				300.00		SqFt											
48		L & T CR				L				153.00		Ft											
Sample Number:				149				Type:		R		Area:				3750.00 SqFt				PCI:		71	
Sample Comments:																							
52		RAVELING				L				400.00		SqFt											
57		WEATHERING				L				3350.00		SqFt											
48		L & T CR				L				215.00		Ft											
56		SWELLING				L				25.00		SqFt											
Sample Number:				158				Type:		R		Area:				3750.00 SqFt				PCI:		62	
Sample Comments:																							
48		L & T CR				L				177.00		Ft											
56		SWELLING				L				650.00		SqFt											
52		RAVELING				L				188.00		SqFt											
57		WEATHERING				L				3562.00		SqFt											
Sample Number:				166				Type:		R		Area:				3750.00 SqFt				PCI:		62	
Sample Comments:																							
57		WEATHERING				L				3350.00		SqFt											

52	RAVELING	L	400.00	SqFt
56	SWELLING	L	700.00	SqFt
48	L & T CR	L	176.00	Ft

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT																
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	429,472 SqFt											
Section:	150		of	9		From:	-		To:	-		Last Const.:	1/1/1963								
Surface:	AC		Family:	C9N59-RL-TW-AC			Zone:				Category:	Rank: P									
Area:	60,358 SqFt			Length:	1,000 Ft			Width:	50 Ft												
Slabs:	Slab Length:			Ft			Slab Width:			Ft			Joint Length:			Ft					
Shoulder:	Street Type:						Grade:			0			Lanes:			0					
Section Comments:																					
Work Date:	1/1/1963			Work Type:					BUILT			Code:	IMPORTED			Is Major M&R:	True				
Work Date:	4/1/2007			Work Type:					Surface Treatment - Slurry Seal					Code:	ST-SS			Is Major M&R:	False		
Last Insp. Date:	3/4/2019			TotalSamples:	12			Surveyed:			2										
Conditions:	PCI: 57																				
Inspection Comments:																					
Sample Number:	450		Type:	R		Area:	6966.00 SqFt			PCI:	60										
Sample Comments:																					
56	SWELLING		L	1050.00		SqFt															
57	WEATHERING		M	3500.00		SqFt															
52	RAVELING		L	139.00		SqFt															
48	L & T CR		L	260.00		Ft															
57	WEATHERING		L	3327.00		SqFt															
Sample Number:	506		Type:	R		Area:	5000.00 SqFt			PCI:	52										
Sample Comments:																					
43	BLOCK CR		L	1300.00		SqFt															
48	L & T CR		M	200.00		Ft															
48	L & T CR		L	266.00		Ft															
52	RAVELING		L	5000.00		SqFt															

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY	Area:	29,965 SqFt
Section:	111	of	2	From:	-		To:	-	Last Const.: 1/1/1997
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:				Category:	Rank: P
Area:	15,537 SqFt		Length:	200 Ft		Width:	125 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1960		Work Type: New Construction - Initial				Code:	NU-IN	
Work Date:	1/1/1997		Work Type: Overlay - AC Structural				Code:	OL-AS	
Is Major M&R: True									
Last Insp. Date:	3/4/2019		TotalSamples:	4		Surveyed:	1		
Conditions:	PCI: 77								
Inspection Comments:									
Sample Number:	105	Type:	R	Area:	3750.00 SqFt		PCI:	77	
Sample Comments:									
52	RAVELING		L	188.00 SqFt					
48	L & T CR		L	7.00 Ft					
57	WEATHERING		L	2612.00 SqFt					
57	WEATHERING		M	950.00 SqFt					

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY	Area:	29,965 SqFt
Section:	112	of	2	From:	-	To:	-	Last Const.:	1/1/1997
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:	P
Area:	14,428 SqFt		Length:	190 Ft		Width:	75 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1960		Work Type: New Construction - Initial				Code:	NU-IN	
Work Date:	1/1/1997		Work Type: Overlay - AC Structural				Code:	OL-AS	
Is Major M&R: True									
Last Insp. Date:	3/4/2019		TotalSamples:	4		Surveyed:	1		
Conditions:	PCI: 57								
Inspection Comments:									
Sample Number:	109	Type:	R	Area:	3750.00 SqFt		PCI:	57	
Sample Comments:									
52	RAVELING		L	1000.00 SqFt					
41	ALLIGATOR CR		M	20.00 SqFt					
57	WEATHERING		L	2750.00 SqFt					
48	L & T CR		M	24.00 Ft					
48	L & T CR		L	266.00 Ft					

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY	Area:	30,935 SqFt
Section:	120	of	1	From:	-	To:	-	Last Const.:	1/1/1997
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	30,935 SqFt	Length:	387 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1960	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1997	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/4/2019	TotalSamples:	8	Surveyed:	1				
Conditions:	PCI: 65								
Inspection Comments:									
Sample Number:	204	Type:	R	Area:	3750.00 SqFt	PCI:	65		
Sample Comments:									
52	RAVELING	L	175.00	SqFt					
56	SWELLING	L	125.00	SqFt					
48	L & T CR	L	412.00	Ft					
52	RAVELING	M	247.00	SqFt					

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW A3	Name:	TAXIWAY A3		Use:	TAXIWAY	Area:	56,163 SqFt	
Section:	130	of	1	From:	-	To:	-	Last Const.:	1/1/1997
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	56,163 SqFt	Length:	600 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1960	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1997	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/4/2019	TotalSamples:	14	Surveyed:	3				
Conditions:	PCI: 67								
Inspection Comments:									
Sample Number:	304	Type:	R	Area:	3750.00 SqFt	PCI:	72		
Sample Comments:									
57	WEATHERING	L	3375.00	SqFt					
48	L & T CR	M	1.00	Ft					
52	RAVELING	L	375.00	SqFt					
48	L & T CR	L	158.00	Ft					
56	SWELLING	L	5.00	SqFt					
Sample Number:	311	Type:	R	Area:	3820.00 SqFt	PCI:	74		
Sample Comments:									
52	RAVELING	L	400.00	SqFt					
57	WEATHERING	L	3420.00	SqFt					
48	L & T CR	L	128.00	Ft					
56	SWELLING	L	75.00	SqFt					
Sample Number:	500	Type:	R	Area:	6782.00 SqFt	PCI:	61		
Sample Comments:									
57	WEATHERING	L	5032.00	SqFt					
45	DEPRESSION	L	125.00	SqFt					
56	SWELLING	L	395.00	SqFt					
48	L & T CR	L	503.00	Ft					
52	RAVELING	L	1750.00	SqFt					

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW A4		Name:	TAXIWAY A4		Use:	TAXIWAY	Area:	15,668 SqFt		
Section:	140	of	1	From:	-	To:	-	Last Const.:	1/1/1999		
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	15,668 SqFt	Length:	397 Ft		Width:	30 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	63									
Inspection Comments:											
Sample Number:	402	Type:	R	Area:	3012.00 SqFt		PCI:	63			
Sample Comments:											
52	RAVELING	L	151.00	SqFt							
57	WEATHERING	L	2861.00	SqFt							
48	L & T CR	L	265.00	Ft							
56	SWELLING	L	372.00	SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	TW A5		Name:	TAXIWAY A5		Use:	TAXIWAY	Area:	46,492 SqFt
Section:	405	of	2	From:	-	To:	-	Last Const.:	1/1/1997
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:	P
Area:	37,049 SqFt		Length:	400 Ft		Width:	75 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	1/1/1960		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1997		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	3/4/2019		TotalSamples:	8		Surveyed: 1			
Conditions:	PCI:	65							
Inspection Comments:									
Sample Number:	404	Type:	R	Area:	3750.00 SqFt		PCI:	65	
Sample Comments:									
52	RAVELING		M	195.00 SqFt					
48	L & T CR		M	20.00 Ft					
52	RAVELING		L	178.00 SqFt					
48	L & T CR		L	180.00 Ft					
56	SWELLING		L	188.00 SqFt					

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	TW A5		Name:	TAXIWAY A5		Use:	TAXIWAY	Area:	46,492 SqFt
Section:	425	of	2	From:	-	To:	-	Last Const.:	1/1/1997
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:	P
Area:	9,443 SqFt	Length:	95 Ft		Width:	100 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1984		Work Type: BUILT				Code:	IMPORTED	
Work Date:	1/1/1997		Work Type: OVERLAY				Code:	IMPORTED	
Is Major M&R: True									
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed:	1		
Conditions:	PCI: 71								
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	3611.00 SqFt		PCI:	71	
Sample Comments:									
56	SWELLING		L	5.00	SqFt				
57	WEATHERING		M	639.00	SqFt				
57	WEATHERING		L	2611.00	SqFt				
48	L & T CR		L	142.00	Ft				
52	RAVELING		L	361.00	SqFt				

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW A6		Name:	TAXIWAY A6		Use:	TAXIWAY	Area:	26,953 SqFt		
Section:	113	of	1	From:	-			To:	-		
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:				Category:		
Area:	26,953 SqFt		Length:	640 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2001		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	7		Surveyed:	1				
Conditions:	PCI:	72									
Inspection Comments:											
Sample Number:	403	Type:	R	Area:	3500.00 SqFt		PCI:	72			
Sample Comments:											
48	L & T CR		L	181.00 Ft							
52	RAVELING		L	50.00 SqFt							
56	SWELLING		L	75.00 SqFt							
57	WEATHERING		L	3450.00 SqFt							

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT										
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	93,858 SqFt					
Section:	102		of	3		From:	-		To:	-		Last Const.:	1/1/1991	
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Category:			Rank:	P	
Area:	6,388 SqFt		Length:	145 Ft		Width:	50 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1991		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2003		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False		
Last Insp. Date: 3/4/2019														
TotalSamples: 1														
Surveyed: 1														
Conditions:	PCI: 48													
Inspection Comments:														
Sample Number:	100		Type:	R		Area:	6388.00 SqFt		PCI:	48				
Sample Comments:														
42	BLEEDING		N	1.00		SqFt								
52	RAVELING		L	5388.00		SqFt								
43	BLOCK CR		L	2900.00		SqFt								
52	RAVELING		M	1000.00		SqFt								
48	L & T CR		L	253.00		Ft								

Network:	ORL		Name:		ORLANDO EXECUTIVE AIRPORT							
Branch:	TW B		Name:		TAXIWAY B		Use:	TAXIWAY	Area:	93,858 SqFt		
Section:	103 of 3		From:		-		To:		-		Last Const.:	1/1/1999
Surface:	AAC		Family:		C9N59-RL-TW-AAC-APC		Zone:		Category:		Rank: P	
Area:	57,000 SqFt		Length:		760 Ft		Width:		75 Ft			
Slabs:			Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft	
Shoulder:			Street Type:				Grade:		0		Lanes: 0	
Section Comments:												
Work Date:	1/1/1991		Work Type: BUILT					Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1999		Work Type: OVERLAY					Code:	IMPORTED		Is Major M&R: True	
Last Insp. Date:	3/4/2019		TotalSamples:		15		Surveyed:		2			
Conditions:	PCI: 55											
Inspection Comments:												
Sample Number:	180		Type:	R		Area:		3750.00 SqFt		PCI: 55		
Sample Comments:												
48	L & T CR		L		295.00 Ft							
50	PATCHING		L		6.00 SqFt							
45	DEPRESSION		L		16.00 SqFt							
52	RAVELING		L		562.00 SqFt							
57	WEATHERING		L		2744.00 SqFt							
57	WEATHERING		M		438.00 SqFt							
56	SWELLING		L		213.00 SqFt							
Sample Number:	190		Type:	R		Area:		3750.00 SqFt		PCI: 56		
Sample Comments:												
57	WEATHERING		M		437.00 SqFt							
56	SWELLING		L		300.00 SqFt							
48	L & T CR		L		407.00 Ft							
57	WEATHERING		L		2750.00 SqFt							
52	RAVELING		L		563.00 SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY		Area:	93,858 SqFt	
Section:	105 of 3		From:	-			To:	-		Last Const.:	12/25/2015
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	30,470 SqFt		Length:	435 Ft		Width:	75 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1960		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/1997		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True	
Work Date:	12/25/2015		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True	
Last Insp. Date:	3/4/2019		TotalSamples:	8		Surveyed:	1				
Conditions:	PCI: 87										
Inspection Comments:											
Sample Number:	198		Type:	R		Area:	3750.00 SqFt		PCI:	87	
Sample Comments:											
48	L & T CR		L	89.00 Ft							
57	WEATHERING		L	3750.00 SqFt							

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW E	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	208,227 SqFt	
Section:	505	of	5	From:	-	To:	-	Last Const.:	1/1/1983
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	78,110 SqFt	Length:	1,822 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1983	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	3/4/2019	TotalSamples:	19	Surveyed:	3				
Conditions:	PCI: 65								
Inspection Comments:									
Sample Number:	107	Type:	R	Area:	4000.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	M	36.00 Ft						
48	L & T CR	L	370.00 Ft						
52	RAVELING	L	4000.00 SqFt						
Sample Number:	112	Type:	R	Area:	4000.00 SqFt	PCI:	62		
Sample Comments:									
48	L & T CR	L	460.00 Ft						
52	RAVELING	L	4000.00 SqFt						
48	L & T CR	M	18.00 Ft						
Sample Number:	118	Type:	R	Area:	4000.00 SqFt	PCI:	69		
Sample Comments:									
48	L & T CR	L	318.00 Ft						
52	RAVELING	L	4000.00 SqFt						

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	208,227 SqFt		
Section:	530		of	5	From:	-		To:	-	Last Const.:	12/25/2015
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:		P
Area:	46,191 SqFt		Length:	680 Ft		Width:	40 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1983		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Work Date:	12/25/2015		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True	
Last Insp. Date:	3/4/2019		TotalSamples:	11		Surveyed:		2			
Conditions:	PCI: 93										
Inspection Comments:											
Sample Number:	125		Type:	R		Area:	4000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	4000.00 SqFt							
Sample Number:	128		Type:	R		Area:	3000.00 SqFt		PCI:	92	
Sample Comments:											
50	PATCHING		L	4.00 SqFt							
57	WEATHERING		L	2996.00 SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT								
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY		Area:	208,227 SqFt			
Section:	540		of	5	From:	-		To:	-		Last Const.:	12/25/2015	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:	Rank:		P	
Area:	21,326 SqFt		Length:	350 Ft		Width:	40 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1991		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/25/2015		Work Type:				MILL and OVERLAY		Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	5		Surveyed:	1						
Conditions:	PCI: 94												
Inspection Comments:													
Sample Number:	131		Type:	R		Area:	5000.00 SqFt		PCI:	94			
Sample Comments:													
57	WEATHERING		L	5000.00 SqFt									

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	208,227 SqFt
Section:	545	of	5	From:	-		To:	-	Last Const.: 12/25/2015
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:	P
Area:	9,618 SqFt		Length:	180 Ft		Width:	45 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1978		Work Type: BUILT				Code:	IMPORTED	
Work Date:	1/1/1984		Work Type: REPAIR				Code:	IMPORTED	
Work Date:	12/25/2015		Work Type: MILL and OVERLAY				Code:	ML-OV	
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed:	1		
Conditions:	PCI: 88								
Inspection Comments:									
Sample Number:	104	Type:	R	Area:	5385.00 SqFt		PCI:	88	
Sample Comments:									
48	L & T CR		L	106.00 Ft					
57	WEATHERING		L	5385.00 SqFt					

Network:	ORL		Name:		ORLANDO EXECUTIVE AIRPORT								
Branch:	TW E		Name:		TAXIWAY E		Use:	TAXIWAY	Area:	208,227 SqFt			
Section:	550	of	5	From:	-			To:	-	Last Const.:	12/25/2015		
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC		Zone:		Category:		Rank:		P		
Area:	52,982 SqFt		Length:		1,336 Ft		Width:		40 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:		0				
Section Comments:													
Work Date:	1/1/1979		Work Type:					BUILT		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1984		Work Type:					REPAIR		Code:	IMPORTED	Is Major M&R:	False
Work Date:	12/25/2015		Work Type:					MILL and OVERLAY		Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:		13		Surveyed:		2				
Conditions:	PCI:		91										
Inspection Comments:													
Sample Number:	137	Type:	R	Area:	4000.00 SqFt		PCI:		91				
Sample Comments:													
48	L & T CR		L	8.00 Ft									
57	WEATHERING		L	4000.00 SqFt									
Sample Number:	146	Type:	R	Area:	4000.00 SqFt		PCI:		92				
Sample Comments:													
48	L & T CR		L	2.00 Ft									
57	WEATHERING		L	4000.00 SqFt									

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT					
Branch:	TW E1		Name:	TAXIWAY E1		Use:	TAXIWAY	Area:	5,073 SqFt
Section:	501	of	1	From:	-	To:	-	Last Const.:	1/1/1977
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	T
Area:	5,073 SqFt	Length:	40 Ft	Width:	125 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1977	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/4/2019	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI:	50							
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	5073.00 SqFt	PCI:	50		
Sample Comments:									
48	L & T CR	L	136.00	Ft					
52	RAVELING	L	4058.00	SqFt					
48	L & T CR	M	30.00	Ft					
43	BLOCK CR	L	2190.00	SqFt					
57	WEATHERING	L	1015.00	SqFt					
56	SWELLING	L	110.00	SqFt					

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT				
Branch:	TW E2		Name:	TAXIWAY E2		Use:	TAXIWAY	Area:	12,331 SqFt
Section:	510	of	2	From:	-	To:	-	Last Const.:	1/1/1983
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	9,644 SqFt	Length:	140 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1983	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/4/2019	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	46							
Inspection Comments:									
Sample Number:	201	Type:	R	Area:	6531.00 SqFt	PCI:	46		
Sample Comments:									
52	RAVELING	L	6291.00	SqFt					
52	RAVELING	M	240.00	SqFt					
56	SWELLING	L	80.00	SqFt					
48	L & T CR	L	360.00	Ft					
43	BLOCK CR	L	3740.00	SqFt					
48	L & T CR	M	30.00	Ft					

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW E2		Name:	TAXIWAY E2		Use:	TAXIWAY	Area:	12,331 SqFt		
Section:	512	of 2	From:	-			To:	-		Last Const.:	1/1/1983
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	2,687 SqFt		Length:	75 Ft		Width:	40 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1983		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI:	61									
Inspection Comments:											
Sample Number:	300	Type:	R	Area:	2687.00 SqFt		PCI:	61			
Sample Comments:											
52	RAVELING	L	269.00	SqFt							
56	SWELLING	L	44.00	SqFt							
48	L & T CR	L	200.00	Ft							
57	WEATHERING	L	2418.00	SqFt							
48	L & T CR	M	9.00	Ft							

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW E3		Name:	TAXIWAY E3		Use:	TAXIWAY	Area:	55,837 SqFt		
Section:	417	of 4	From:	-			To:	-		Last Const.:	1/1/1977
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Category:	Rank: P	
Area:	8,311 SqFt		Length:	42 Ft		Width:	200 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	1/1/1977		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Last Insp. Date:	3/4/2019		TotalSamples:		2		Surveyed:		1		
Conditions:	PCI:		29								
Inspection Comments:											
Sample Number:	411	Type:	R	Area:	5023.00 SqFt		PCI:	29			
Sample Comments:											
50	PATCHING		L	80.00 SqFt							
48	L & T CR		L	560.00 Ft							
52	RAVELING		M	4943.00 SqFt							
48	L & T CR		M	223.00 Ft							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW E3		Name:	TAXIWAY E3		Use:	TAXIWAY		Area:	55,837 SqFt		
Section:	420 of 4		From:	-		To:	-		Last Const.:	1/1/1984		
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Category:	Rank: P		
Area:	36,384 SqFt		Length:	40 Ft		Width:	900 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1984		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	8		Surveyed:	3					
Conditions:	PCI: 50											
Inspection Comments:												
Sample Number:	405		Type:	R		Area:	4000.00 SqFt		PCI:	39		
Sample Comments:												
48	L & T CR		L	300.00 Ft								
53	RUTTING		L	60.00 SqFt								
45	DEPRESSION		M	355.00 SqFt								
52	RAVELING		L	4000.00 SqFt								
45	DEPRESSION		L	49.00 SqFt								
48	L & T CR		M	87.00 Ft								
Sample Number:	406		Type:	R		Area:	4000.00 SqFt		PCI:	42		
Sample Comments:												
52	RAVELING		L	4000.00 SqFt								
45	DEPRESSION		H	120.00 SqFt								
45	DEPRESSION		M	25.00 SqFt								
45	DEPRESSION		L	77.00 SqFt								
48	L & T CR		L	248.00 Ft								
Sample Number:	410		Type:	R		Area:	6039.00 SqFt		PCI:	63		
Sample Comments:												
45	DEPRESSION		L	15.00 SqFt								
50	PATCHING		L	520.00 SqFt								
52	RAVELING		L	5519.00 SqFt								
48	L & T CR		L	326.00 Ft								

Network:		ORL		Name:		ORLANDO EXECUTIVE AIRPORT					
Branch:	TW E3		Name:	TAXIWAY E3		Use:	TAXIWAY		Area:	55,837 SqFt	
Section:	520		of	4		From:	-		To:	-	
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Category:		
Area:	9,009 SqFt		Length:	225 Ft		Width:	40 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1983		Work Type:				BUILT		Code:	IMPORTED	
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI: 46										
Inspection Comments:											
Sample Number:	401		Type:	R		Area:	4273.00 SqFt		PCI:	46	
Sample Comments:											
50	PATCHING		L	380.00 SqFt							
56	SWELLING		L	84.00 SqFt							
52	RAVELING		L	3573.00 SqFt							
52	RAVELING		M	320.00 SqFt							
48	L & T CR		L	477.00 Ft							
48	L & T CR		M	100.00 Ft							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW E3		Name:	TAXIWAY E3		Use:	TAXIWAY	Area:	55,837 SqFt			
Section:	522	of	4	From:	-			To:	-		Last Const.:	1/1/1983
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:		Category:	Rank: P			
Area:	2,133 SqFt		Length:	67 Ft		Width:	32 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:		0			
Section Comments:												
Work Date:	1/1/1983			Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	3/4/2019			TotalSamples:		1		Surveyed:		1		
Conditions:	PCI:		48									
Inspection Comments:												
Sample Number:	500		Type:	R		Area:	2128.00 SqFt		PCI:	48		
Sample Comments:												
56	SWELLING		L	300.00		SqFt						
57	WEATHERING		L	1278.00		SqFt						
48	L & T CR		M	100.00		Ft						
48	L & T CR		L	284.00		Ft						
52	RAVELING		L	850.00		SqFt						

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW E4		Name:	TAXIWAY E4		Use:	TAXIWAY		Area:	166,492 SqFt		
Section:	1070		of	4	From:	-		To:	-		Last Const.:	1/1/1977
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:	Rank:		P
Area:	130,837 SqFt		Length:	1,072 Ft		Width:	75 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1977		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1977		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	31		Surveyed:	4					
Conditions:	PCI: 50											
Inspection Comments:												
Sample Number:	119		Type:	R		Area:	6500.00 SqFt		PCI:	43		
Sample Comments:												
48	L & T CR		L	740.00 Ft								
48	L & T CR		M	165.00 Ft								
56	SWELLING		L	15.00 SqFt								
52	RAVELING		L	4200.00 SqFt								
52	RAVELING		M	2300.00 SqFt								
Sample Number:	302		Type:	R		Area:	3750.00 SqFt		PCI:	61		
Sample Comments:												
48	L & T CR		L	440.00 Ft								
52	RAVELING		L	3750.00 SqFt								
42	BLEEDING		N	3.00 SqFt								
48	L & T CR		M	50.00 Ft								
Sample Number:	312		Type:	R		Area:	3750.00 SqFt		PCI:	51		
Sample Comments:												
48	L & T CR		L	420.00 Ft								
56	SWELLING		L	30.00 SqFt								
48	L & T CR		M	20.00 Ft								
52	RAVELING		M	375.00 SqFt								
52	RAVELING		L	3375.00 SqFt								
Sample Number:	316		Type:	R		Area:	3750.00 SqFt		PCI:	52		
Sample Comments:												
52	RAVELING		M	375.00 SqFt								
52	RAVELING		L	3375.00 SqFt								
48	L & T CR		L	383.00 Ft								
56	SWELLING		L	20.00 SqFt								
48	L & T CR		M	50.00 Ft								

Network:		ORL		Name:		ORLANDO EXECUTIVE AIRPORT																									
Branch:		TW E4		Name:		TAXIWAY E4		Use:		TAXIWAY		Area:		166,492 SqFt																	
Section:		1080		of 4		From:		-		To:		-		Last Const.: 1/1/1977																	
Surface:		AAC		Family:		C9N59-RL-TW-AAC-APC		Zone:		Category:		Rank:		P																	
Area:		8,393 SqFt		Length:		80 Ft		Width:		50 Ft																					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																			
Shoulder:		Street Type:		Grade:		0		Lanes:		0																					
Section Comments:																															
Work Date:				1/1/1977				Work Type:				BUILT				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				1/1/1977				Work Type:				OVERLAY				Code:				IMPORTED				Is Major M&R:				True			
Last Insp. Date:				3/4/2019				TotalSamples:				2				Surveyed:				1											
Conditions:				PCI:				56																							
Inspection Comments:																															
Sample Number:				100				Type:		R		Area:				4281.00 SqFt				PCI:				56							
Sample Comments:																															
48		L & T CR				L		428.00 Ft																							
48		L & T CR				M		67.00 Ft																							
43		BLOCK CR				L		420.00 SqFt																							
52		RAVELING				L		4281.00 SqFt																							

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW E4	Name:	TAXIWAY E4		Use:	TAXIWAY	Area:	166,492 SqFt		
Section:	1105	of	4	From:	-	To:	-	Last Const.:	1/1/1991	
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:	Category:		Rank:	T	
Area:	6,580 SqFt		Length:	175 Ft		Width:	38 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	1/1/1991	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:		True
Last Insp. Date:	3/4/2019	TotalSamples:		1	Surveyed:		1			
Conditions:	PCI:	70								
Inspection Comments:										
Sample Number:	100	Type:	R	Area:	6580.00 SqFt		PCI:	70		
Sample Comments:										
48	L & T CR		L	222.00 Ft						
52	RAVELING		L	2632.00 SqFt						
56	SWELLING		L	25.00 SqFt						
57	WEATHERING		L	3948.00 SqFt						

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW E4		Name:	TAXIWAY E4		Use:	TAXIWAY		Area:	166,492 SqFt	
Section:	1110		of	4		From:	-		To:	-	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:		
Area:	20,682 SqFt		Length:	70 Ft		Width:	75 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1991		Work Type:				BUILT		Code:	IMPORTED	
Work Date:	12/25/2015		Work Type:				MILL and OVERLAY		Code:	ML-OV	
Last Insp. Date:	3/4/2019		TotalSamples:	4		Surveyed:		1			
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	104		Type:	R		Area:	4994.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	4994.00 SqFt							

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW E5	Name:	TAXIWAY E5	Use:	TAXIWAY	Area:	15,005 SqFt		
Section:	560	of	2	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	5,540 SqFt	Length:	115 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1991	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	3/4/2019	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI:	65							
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	5540.00 SqFt	PCI:	65		
Sample Comments:									
48	L & T CR	L	18.00 Ft						
52	RAVELING	M	277.00 SqFt						
52	RAVELING	L	5263.00 SqFt						

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT					
Branch:	TW E5		Name:	TAXIWAY E5		Use:	TAXIWAY	Area:	15,005 SqFt	
Section:	565	of 2	From:	-			To:	-	Last Const.: 10/1/2015	
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	9,465 SqFt		Length:	140 Ft		Width:	40 Ft			
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1991		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	10/1/2015		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed: 1				
Conditions:	PCI:	94								
Inspection Comments:										
Sample Number:	102	Type:	R	Area:	5179.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	5179.00 SqFt						

Network:		ORL		Name:		ORLANDO EXECUTIVE AIRPORT								
Branch:	TW E6		Name:	TAXIWAY E6		Use:	TAXIWAY	Area:	28,881 SqFt					
Section:	805		of	2		From:	-		To:	-		Last Const.:	1/1/1984	
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Category:			Rank:	P	
Area:	17,742 SqFt		Length:	185 Ft		Width:	40 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1984		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2017		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False		
Last Insp. Date:	3/4/2019		TotalSamples:	4		Surveyed:	1							
Conditions:	PCI: 67													
Inspection Comments:														
Sample Number:	801		Type:	R		Area:	4010.00 SqFt		PCI:	67				
Sample Comments:														
48	L & T CR		L	394.00 Ft										
52	RAVELING		L	4010.00 SqFt										

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW E6		Name:	TAXIWAY E6		Use:	TAXIWAY	Area:	28,881 SqFt		
Section:	820 of 2		From:	-		To:	-		Last Const.:	12/25/2015	
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Rank:	P	
Area:	11,139 SqFt		Length:	145 Ft		Width:	70 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1999		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/25/2015		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	3		Surveyed:	1				
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	101		Type:	R		Area:	3178.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	3178.00 SqFt							

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT									
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY		Area:	54,815 SqFt				
Section:	605		of	1		From:	-		To:	-		Last Const.:	1/1/1984	
Surface:	AC		Family:	C9N59-RL-TW-AC			Zone:				Category:	Rank: P		
Area:	54,815 SqFt			Length:	1,300 Ft		Width:	40 Ft						
Slabs:	Slab Length:			Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:	Street Type:			Grade:		0			Lanes:			0		
Section Comments:														
Work Date:	1/1/1984			Work Type: BUILT				Code:	IMPORTED			Is Major M&R: True		
Last Insp. Date:	3/4/2019			TotalSamples:	13		Surveyed:	2						
Conditions:	PCI:	45												
Inspection Comments:														
Sample Number:	602		Type:	R		Area:	4000.00 SqFt		PCI:	48				
Sample Comments:														
43	BLOCK CR		L	40.00 SqFt										
48	L & T CR		L	740.00 Ft										
56	SWELLING		L	14.00 SqFt										
48	L & T CR		M	100.00 Ft										
52	RAVELING		L	4000.00 SqFt										
Sample Number:	611		Type:	R		Area:	4000.00 SqFt		PCI:	42				
Sample Comments:														
52	RAVELING		M	2000.00 SqFt										
48	L & T CR		L	427.00 Ft										
43	BLOCK CR		L	350.00 SqFt										
52	RAVELING		L	2000.00 SqFt										

Network:	ORL			Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY		Area:	39,911 SqFt	
Section:	705		of	2		From:	-		To:	-	
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Category:	Rank: P	
Area:	30,099 SqFt		Length:	660 Ft		Width:	40 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1984		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Last Insp. Date:	3/4/2019		TotalSamples:	7		Surveyed:	2				
Conditions:	PCI:	54									
Inspection Comments:											
Sample Number:	701		Type:	R		Area:	4005.00 SqFt		PCI:	58	
Sample Comments:											
56	SWELLING		L	225.00 SqFt							
43	BLOCK CR		L	216.00 SqFt							
52	RAVELING		L	4005.00 SqFt							
48	L & T CR		L	417.00 Ft							
Sample Number:	705		Type:	R		Area:	4000.00 SqFt		PCI:	51	
Sample Comments:											
43	BLOCK CR		L	1294.00 SqFt							
56	SWELLING		L	600.00 SqFt							
48	L & T CR		L	341.00 Ft							
52	RAVELING		L	4000.00 SqFt							

Network:	ORL		Name:	ORLANDO EXECUTIVE AIRPORT							
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY	Area:	39,911 SqFt		
Section:	710	of 2	From:	-			To:	-		Last Const.:	1/1/1988
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	9,812 SqFt		Length:	215 Ft		Width:	40 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1988		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	3/4/2019		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	55									
Inspection Comments:											
Sample Number:	707	Type:	R	Area:	4000.00 SqFt		PCI:	55			
Sample Comments:											
56	SWELLING		L	325.00	SqFt						
48	L & T CR		L	510.00	Ft						
52	RAVELING		L	3950.00	SqFt						
52	RAVELING		M	50.00	SqFt						

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW H	Name:	TAXIWAY H	Use:	TAXIWAY	Area:	62,452 SqFt		
Section:	806	of	1	From:	-	To:	-	Last Const.:	1/1/1983
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	62,452 SqFt	Length:	1,560 Ft	Width:		40 Ft			
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1983	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2015	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	3/4/2019	TotalSamples:	16	Surveyed:	3				
Conditions:	PCI: 52								
Inspection Comments:									
Sample Number:	112	Type:	R	Area:	4000.00 SqFt	PCI:	46		
Sample Comments:									
48	L & T CR	L	46.00	Ft					
48	L & T CR	M	445.00	Ft					
52	RAVELING	L	4000.00	SqFt					
43	BLOCK CR	L	590.00	SqFt					
Sample Number:	122	Type:	R	Area:	4000.00 SqFt	PCI:	55		
Sample Comments:									
43	BLOCK CR	L	2000.00	SqFt					
52	RAVELING	L	4000.00	SqFt					
48	L & T CR	L	256.00	Ft					
Sample Number:	130	Type:	R	Area:	4000.00 SqFt	PCI:	53		
Sample Comments:									
48	L & T CR	L	403.00	Ft					
43	BLOCK CR	L	1400.00	SqFt					
52	RAVELING	L	4000.00	SqFt					

Network:	ORL	Name:	ORLANDO EXECUTIVE AIRPORT						
Branch:	TW K	Name:	TAXIWAY K	Use:	TAXIWAY	Area:	27,266 SqFt		
Section:	610	of	1	From:	-	To:	-	Last Const.:	1/1/1999
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	27,266 SqFt	Length:	500 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1999	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	3/4/2019	TotalSamples:	6	Surveyed:	1				
Conditions:	PCI:	70							
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	4000.00 SqFt	PCI:	70		
Sample Comments:									
48	L & T CR	L	154.00	Ft					
52	RAVELING	L	50.00	SqFt					
48	L & T CR	M	23.00	Ft					
56	SWELLING	L	65.00	SqFt					
57	WEATHERING	L	3950.00	SqFt					