FLORIDA DEPARTMENT OF TRANSPORTATION

AVIATION AND SPACEPORTS OFFICE







Florida Department of Transportation

Statewide Airfield Pavement Management Program

Prepared by:

FDOT Aviation and Spaceports Office 605 Suwannee Street Tallahassee, Florida 32399-0450

















OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS



Table of Contents


| Executive Summary10 |
|--|
| Program Background10 |
| Summary of Results11Pavement Condition Index (Latest Inspection)11Forecasted Pavement Condition Index 2020-202913Major Rehabilitation Planning 2020-202915 |
| Summary of Gainesville Regional Airport18 |
| Chapter 1 – Introduction20 |
| 1.1 Background20 |
| 1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-201920 |
| 1.3 Organization221.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager221.3.2 Participating Florida Public-Use and Publicly Owned Airports221.3.3 Florida Department of Transportation District Offices221.3.4 Consultant22 |
| 1.4 Purpose of Airport Pavement Evaluation Report24 |
| 1.5 History of the Program |
| 1.6 Federal Aviation Administration (FAA)26 |
| 1.7 FDOT SAPMP Objectives and Components261.7.1 Program Objectives261.7.2 Program Components26 |
| 1.8 References30 |
| Chapter 2 – Methodology32 |
| 2.1 Airfield Pavement Database32 |
| 2.2 Airfield Pavement System Inventory 32 2.2.1 Pavement Management Program Network Definition Terminology 33 |
| 2.3 Airfield Pavement Structure |
| 2.4 Airfield Pavement Work History |
| 2.5 Airfield Pavement Traffic37 |
| 2.6 Airfield Pavement Condition Index (PCI) Survey372.6.1 PCI Survey Methodology372.6.2 Pavement Distress Types39 |



| 2.6.3 PCI Survey Inspection Procedures | |
|---|----|
| Chapter 3 – Airfield Pavement System Inventory | 47 |
| | |
| 3.1 Airfield Pavement Network Information | |
| 3.1.2 Estimated Pavement Age | |
| 3.1.3 Functional Use Classification. | |
| 3.1.4 Pavement Surface Type | |
| 3.1.5 Pavement System Inventory Details | |
| Chapter 4 – Airfield Pavement Condition | 60 |
| 4.1 Airfield Pavement Condition Index (Latest Inspection) | 60 |
| 4.1.1 Network-Level Analysis | |
| 4.1.2 Branch-Level Analysis | |
| 4.1.3 Section-Level Analysis | 63 |
| 4.2 Summary of Pavement Condition Evaluation Results | 68 |
| 4.2.1 Network-Level Observations. | 68 |
| 4.2.2 Branch-Level Observations | |
| 4.3 Forecasted Pavement Conditions | 70 |
| 4.3.1 Performance Models and Prediction Curves | |
| 4.3.2 Branch-Level Pavement Condition Forecast | |
| 4.3.3 Section-Level Pavement Condition Forecast | |
| 4.3.4 Forecasted PCI Considerations | 77 |
| | |
| Chapter 5 – Localized Maintenance and Repair Planning | |
| 5.1 Localized Maintenance and Repair | |
| 5.2 Localized Maintenance and Repair Policy | |
| 5.3 Localized Maintenance and Repair Analysis and Recommendations | 84 |
| Chapter 6 – Major Rehabilitation Planning | 89 |
| 6.1 Major Rehabilitation | 89 |
| 6.1.1 Critical PCI | 91 |
| 6.1.2 FDOT Recommended Minimum Service-Level PCI | 91 |
| 6.2 Major Rehabilitation Policy | 92 |
| 6.2.1 Major Rehabilitation Pavement Section Development | |
| 6.2.2 Major Rehabilitation Planning-Level Unit Costs | |
| 6.3 Major Rehabilitation Needs | 94 |
| 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs | 94 |
| Chapter 7 – Conclusion | 99 |
| 7.1 Recommendations | 99 |
| 7.1.1 Continued PCI Survey Inspections | |
| 7.1.2 Localized Maintenance and Repair | |



| 7.1.3 Major Rehabilitation | 99 |
|--|-----|
| 7.1.4 Pavement Management System | |
| | |
| 7.2 Supporting Documents | 100 |
| 001 – Airfield Pavement Network Definition Exhibit | 100 |
| 002 – Airfield Pavement System Inventory Exhibit | 100 |
| 003 – Airfield Pavement Condition Index Exhibit | 100 |
| 004 – Airfield Pavement Major Rehabilitation Exhibit | 100 |
| Inspection Photograph Documentation | 100 |
| 7.2 Canalysian | 404 |
| 7.3 Conclusion | 101 |





Appendix A Airfield Pavement Analysis Tables

Appendix B Airfield Pavement Localized Maintenance and Repair and Major

Rehabilitation

Appendix C Technical Exhibits

Appendix D Inspection Photograph Documentation

Appendix E Inspection Distress Details



List of Figures

| Figure E-4 Major Rehabilitation Planning Annual Budget 2020-202917 |
|--|
| Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts21 |
| Figure 1.7.2 (a) Typical Pavement Condition Life Cycle27 |
| Figure 1.7.2 (b) General Pavement Treatments by Condition Range28 |
| Figures 1.7.2 (c) Flexible Asphalt Concrete29 |
| Figures 1.7.2 (d) Rigid Portland Cement Concrete29 |
| Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit48 |
| Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit49 |
| Figure 3.1.2 Average Age of Pavements at Inspection50 |
| Figure 3.1.3 Airfield Pavement Functional Classification Use by Area51 |
| Figure 3.1.4 (a) Pavement Surface Type by Area (SF)52 |
| Figure 3.1.4 (b) Pavement Surface Type by Area (%)53 |
| Figure 4.1.1 Latest Condition – Overall Network60 |
| Figure 4.1.2 (a) Latest Condition – Runway Pavements61 |
| Figure 4.1.2 (b) Latest Condition – Taxiway Pavements61 |
| Figure 4.1.2 (c) Latest Condition – Apron Pavements62 |
| Figure 4.1.2 (d) Latest Condition – Taxilane Pavements62 |
| Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit67 |
| Figure 4.2.2 Pavement Condition Summary by Facility Use69 |
| Figure 4.3.2 (a) Forecasted Runway Pavement Performance70 |
| Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance71 |
| Figure 4.3.2 (c) Forecasted Apron Pavement Performance |
| Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI89 |
| Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI90 |
| Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year97 |
| Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit97 |



List of Tables

| Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level11 |
|---|
| Table E-2 Pavement Condition Index Forecast 2020-202913 |
| Table E-3 Major Rehabilitation Planning 2020-202915 |
| Table 2.2.1 Airfield Pavement Database Network Definition Terminology34 |
| Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields 39 |
| Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete- Surfaced Airfields |
| Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete- Surfaced Airfields |
| Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields41 |
| Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete- Surfaced Airfields |
| Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields |
| Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete43 |
| Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete43 |
| Table 2.6.4 Summary of Updates to ASTM D5340-1245 |
| Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction47 |
| Table 3.1.5 Pavement System Inventory Details54 |
| Table 4.1.3 Latest Pavement Condition Index Summary64 |
| Table 4.3.3 Forecasted PCI 2020-202973 |
| Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete80 |
| Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete81 |
| Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete83 |



| Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete83 |
|---|
| Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level84 |
| Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level85 |
| Table 5.3 (c) Summary of Localized Maintenance87 |
| Table 6.1.2 FDOT Recommended Minimum Service-Level PCI91 |
| Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete |
| Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete |
| Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type94 |
| Table 6.3.1 10-Year Major Rehabilitation Needs95 |



Executive Summary





Executive Summary

Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the documented procedures set forth by ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.





Summary of Results

Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) - Section Level

| Network ID | Branch Name | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|--|------------|------------------|-----------|-----|---------------------|
| GNV | RUNWAY 7-25 | RUNWAY | 6105 | 415,800 | 89 | Good |
| GNV | RUNWAY 11-29 | RUNWAY | 6201 | 12,282 | 88 | Good |
| GNV | RUNWAY 11-29 | RUNWAY | 6202 | 34,697 | 52 | Poor |
| GNV | RUNWAY 11-29 | RUNWAY | 6205 | 630,300 | 72 | Satisfactory |
| GNV | RUNWAY 11-29 | RUNWAY | 6207 | 17,349 | 70 | Fair |
| GNV | RUNWAY 11-29 | RUNWAY | 6210 | 315,150 | 76 | Satisfactory |
| GNV | RUNWAY 11-29 | RUNWAY | 6225 | 100,100 | 66 | Fair |
| GNV | RUNWAY 11-29 | RUNWAY | 6230 | 50,050 | 76 | Satisfactory |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 605 | 28,681 | 86 | Good |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 610 | 8,448 | 79 | Satisfactory |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 715 | 65,848 | 91 | Good |
| GNV | TAXIWAY A | TAXIWAY | 104 | 13,820 | 89 | Good |
| GNV | TAXIWAY A | TAXIWAY | 105 | 80,019 | 30 | Very Poor |
| GNV | TAXIWAY A | TAXIWAY | (IWAY 108 6,264 | | 72 | Satisfactory |
| GNV | TAXIWAY A | TAXIWAY | TAXIWAY 110 50,2 | | 89 | Good |
| GNV | TAXIWAY A | TAXIWAY | 115 | 22,645 | 60 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 117 | 9,679 | 69 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 119 | 4,962 | 59 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 120 | 98,695 | 91 | Good |
| GNV | TAXIWAY A | TAXIWAY | 130 | 11,380 | 64 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 135 | 20,258 | 60 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 140 | 32,303 | 37 | Very Poor |
| GNV | TAXIWAY A | TAXIWAY | 143 | 5,547 | 46 | Poor |
| GNV | TAXIWAY A | TAXIWAY | 147 | 3,947 | 58 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 149 | 4,225 | 68 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 152 | 3,939 | 85 | Satisfactory |
| GNV | TAXIWAY A | TAXIWAY | 153 | 4,523 | 82 | Satisfactory |
| GNV | TAXIWAY A | TAXIWAY | 154 | 4,561 | 53 | Poor |
| GNV | TAXIWAY B | TAXIWAY | 203 | 8,026 | 90 | Good |
| GNV | TAXIWAY B | TAXIWAY | 205 | 129,976 | 89 | Good |
| GNV | TAXIWAY B | TAXIWAY | 206 | 7,137 | 87 | Good |
| GNV | TAXIWAY B | TAXIWAY | 208 | 18,964 | 81 | Satisfactory |
| GNV | TAXIWAY B | TAXIWAY | 210 | 11,878 | 53 | Poor |
| GNV | TAXIWAY C | TAXIWAY | 304 | 17,460 | 89 | Good |





| Network ID | Branch Name | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|----------------------------------|------------|---------------|-----------|-----|---------------------|
| GNV | TAXIWAY C | TAXIWAY | 305 | 110,122 | 75 | Satisfactory |
| GNV | TAXIWAY C | TAXIWAY | 307 | 44,526 | 61 | Fair |
| GNV | TAXIWAY C | TAXIWAY | 315 | 22,886 | 81 | Satisfactory |
| GNV | TAXIWAY D | TAXIWAY | 410 | 20,831 | 80 | Satisfactory |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TAXIWAY | 505 | 491,892 | 86 | Good |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TAXIWAY | 510 | 75,075 | 89 | Good |
| GNV | TAXIWAY E1 | TAXIWAY | 515 | 19,914 | 65 | Fair |
| GNV | TAXIWAY E1 | TAXIWAY | 517 | 15,325 | 90 | Good |
| GNV | TAXIWAY E2 | TAXIWAY | 520 | 19,417 | 73 | Satisfactory |
| GNV | TAXIWAY E2 | TAXIWAY | 522 | 15,698 | 91 | Good |
| GNV | TAXIWAY E3 | TAXIWAY | 530 | 28,702 | 69 | Fair |
| GNV | TAXIWAY E3 | TAXIWAY | 532 | 20,853 | 89 | Good |
| GNV | TAXIWAY E4 | TAXIWAY | 540 | 29,074 | 66 | Fair |
| GNV | TAXIWAY E4 | TAXIWAY | 542 | 17,460 | 90 | Good |
| GNV | TAXIWAY E5 | TAXIWAY | 550 | 19,373 | 77 | Satisfactory |
| GNV | TAXIWAY E5 | TAXIWAY | 552 | 9,790 | 91 | Good |
| GNV | TL T-HANGAR | TAXILANE | 3105 | 52,426 | 63 | Fair |
| GNV | SOUTH APRONS | APRON | 4105 | 66,500 | 75 | Satisfactory |
| GNV | SOUTH APRONS | APRON | 4110 | 126,000 | 88 | Good |
| GNV | SOUTH APRONS | APRON | 4115 | 35,000 | 84 | Satisfactory |
| GNV | SOUTH APRONS | APRON | 4120 | 12,825 | 86 | Good |
| GNV | SOUTH APRONS | APRON | 4125 | 22,290 | 80 | Satisfactory |
| GNV | SOUTH APRONS | APRON | 4130 | 8,760 | 88 | Good |
| GNV | SOUTH APRONS | APRON | 4135 | 70,723 | 100 | Good |
| GNV | NORTH APRONS | APRON | 4203 | 23,039 | 64 | Fair |
| GNV | NORTH APRONS | APRON | 4205 | 189,798 | 72 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4210 | 49,872 | 62 | Fair |
| GNV | NORTH APRONS | APRON | 4215 | 76,639 | 82 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4220 | 53,200 | 46 | Poor |
| GNV | NORTH APRONS | APRON | 4222 | 13,199 | 66 | Fair |
| GNV | NORTH APRONS | APRON | 4226 | 97,393 | 73 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4228 | 14,420 | 58 | Fair |
| GNV | NORTH APRONS | APRON | 4230 | 36,283 | 77 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4240 | 130,329 | 70 | Fair |
| GNV | NORTH APRONS | APRON | 4241 | 21,600 | 76 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4245 | 15,617 | 70 | Fair |
| GNV | NORTH APRONS | APRON | 4250 | 145,100 | 77 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4255 | 125,665 | 72 | Satisfactory |





| Network ID | Branch Name | Branch Use | Section Area (SF) | | PCI | Condition Rating |
|------------|-----------------------|------------|-------------------|---------|-----|---------------------|
| GNV | NORTH APRONS | APRON | 4260 | 104,561 | 74 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4270 | 32,960 | 79 | Satisfactory |
| GNV | SOUTHWEST APRON | APRON | 4305 | 32,431 | 65 | Fair |
| GNV | SOUTHWEST APRON | APRON | 4310 | 12,201 | 29 | Very Poor |
| GNV | SOUTHWEST APRON | APRON | 4315 | 23,585 | 55 | Poor |
| GNV | SOUTHWEST APRON | APRON | 4320 | 21,340 | 73 | Satisfactory |
| GNV | SOUTHWEST APRON | APRON | 4325 | 72,728 | 64 | Fair |
| GNV | SOUTHWEST APRON | APRON | 4330 | 61,003 | 76 | Satisfactory |
| GNV | RUN UP APRON AT RW 25 | APRON | 5105 | 9,793 | 87 | Good |
| GNV | RUN UP APRON AT RW 7 | APRON | 5205 | 7,974 | 50 | Poor |

Forecasted Pavement Condition Index 2020-2029

Table E-2 Pavement Condition Index Forecast 2020-2029

| Network | Branch ID | Section | Last | Forecasted PCI | | | | | | | | | |
|---------|-----------|---------|------|----------------|------|------|------|------|------|------|------|------|------|
| ID | Dianchid | ID | PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | AP N | 4203 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4205 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 |
| GNV | AP N | 4210 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 | 59 | 59 | 58 |
| GNV | AP N | 4215 | 82 | 79 | 77 | 74 | 71 | 69 | 67 | 65 | 64 | 62 | 61 |
| GNV | AP N | 4220 | 46 | 43 | 39 | 34 | 31 | 28 | 26 | 24 | 22 | 19 | 17 |
| GNV | AP N | 4222 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4226 | 73 | 71 | 68 | 66 | 65 | 63 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP N | 4228 | 58 | 56 | 54 | 52 | 49 | 45 | 41 | 37 | 33 | 29 | 27 |
| GNV | AP N | 4230 | 77 | 75 | 72 | 70 | 67 | 66 | 64 | 63 | 62 | 61 | 60 |
| GNV | AP N | 4240 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4241 | 76 | 74 | 71 | 69 | 67 | 65 | 63 | 62 | 61 | 61 | 60 |
| GNV | AP N | 4245 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4250 | 77 | 75 | 72 | 70 | 67 | 66 | 64 | 63 | 62 | 61 | 60 |
| GNV | AP N | 4255 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 |
| GNV | AP N | 4260 | 74 | 72 | 69 | 67 | 65 | 64 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP N | 4270 | 79 | 77 | 76 | 74 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | AP RU 25 | 5105 | 87 | 84 | 82 | 79 | 76 | 73 | 71 | 69 | 67 | 65 | 63 |
| GNV | AP RU 7 | 5205 | 50 | 48 | 47 | 45 | 44 | 42 | 40 | 39 | 37 | 36 | 34 |
| GNV | AP S | 4105 | 75 | 73 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 |
| GNV | AP S | 4110 | 88 | 87 | 86 | 85 | 85 | 84 | 83 | 82 | 82 | 81 | 80 |
| GNV | AP S | 4115 | 84 | 83 | 82 | 81 | 81 | 80 | 79 | 78 | 77 | 76 | 75 |
| GNV | AP S | 4120 | 86 | 83 | 81 | 78 | 75 | 72 | 70 | 68 | 66 | 64 | 63 |





| Network | | Section | Last | | | | | Forecas | sted PCI | | | | |
|---------|-----------|---------|------|------|------|------|------|---------|----------|------|------|------|------|
| ID | Branch ID | ID | PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | AP S | 4125 | 80 | 77 | 75 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 |
| GNV | AP S | 4130 | 88 | 85 | 83 | 80 | 77 | 74 | 72 | 69 | 67 | 65 | 64 |
| GNV | AP S | 4135 | 100 | 98 | 96 | 94 | 92 | 91 | 90 | 89 | 88 | 87 | 86 |
| GNV | AP SW | 4305 | 65 | 63 | 62 | 61 | 61 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP SW | 4310 | 29 | 27 | 26 | 24 | 23 | 21 | 19 | 18 | 16 | 15 | 13 |
| GNV | AP SW | 4315 | 55 | 53 | 52 | 50 | 49 | 47 | 45 | 44 | 42 | 41 | 39 |
| GNV | AP SW | 4320 | 73 | 71 | 68 | 66 | 65 | 63 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP SW | 4325 | 64 | 62 | 61 | 59 | 58 | 56 | 54 | 53 | 51 | 50 | 48 |
| GNV | AP SW | 4330 | 76 | 74 | 73 | 71 | 70 | 68 | 66 | 65 | 63 | 62 | 60 |
| GNV | RW 11-29 | 6201 | 88 | 85 | 83 | 81 | 80 | 78 | 77 | 76 | 74 | 72 | 69 |
| GNV | RW 11-29 | 6202 | 52 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 46 | 46 |
| GNV | RW 11-29 | 6205 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 | 54 | 54 |
| GNV | RW 11-29 | 6207 | 70 | 68 | 65 | 62 | 59 | 57 | 56 | 55 | 54 | 54 | 54 |
| GNV | RW 11-29 | 6210 | 76 | 74 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 |
| GNV | RW 11-29 | 6225 | 66 | 63 | 61 | 58 | 56 | 55 | 54 | 54 | 54 | 54 | 52 |
| GNV | RW 11-29 | 6230 | 76 | 74 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 |
| GNV | RW 7-25 | 6105 | 89 | 86 | 84 | 82 | 80 | 79 | 78 | 76 | 74 | 72 | 70 |
| GNV | TL T-HANG | 3105 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 |
| GNV | TW A | 104 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW A | 105 | 30 | 27 | 24 | 20 | 16 | 11 | 6 | 0 | 0 | 0 | 0 |
| GNV | TW A | 108 | 72 | 70 | 69 | 67 | 65 | 64 | 63 | 62 | 60 | 59 | 59 |
| GNV | TW A | 110 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW A | 115 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 | 53 |
| GNV | TW A | 117 | 69 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 |
| GNV | TW A | 119 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 | 53 | 52 |
| GNV | TW A | 120 | 91 | 89 | 86 | 84 | 81 | 79 | 77 | 75 | 73 | 71 | 69 |
| GNV | TW A | 130 | 64 | 63 | 62 | 61 | 61 | 60 | 59 | 59 | 58 | 57 | 56 |
| GNV | TW A | 135 | 60 | 59 | 58 | 57 | 57 | 56 | 55 | 54 | 53 | 51 | 50 |
| GNV | TW A | 140 | 37 | 35 | 32 | 29 | 25 | 22 | 18 | 14 | 11 | 7 | 3 |
| GNV | TW A | 143 | 46 | 44 | 42 | 40 | 38 | 35 | 32 | 30 | 26 | 23 | 19 |
| GNV | TW A | 147 | 58 | 57 | 56 | 55 | 54 | 53 | 52 | 51 | 49 | 48 | 46 |
| GNV | TW A | 149 | 68 | 66 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 | 57 |
| GNV | TW A | 152 | 85 | 83 | 80 | 78 | 76 | 74 | 72 | 70 | 69 | 67 | 66 |
| GNV | TW A | 153 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 | 64 |
| GNV | TW A | 154 | 53 | 52 | 51 | 51 | 50 | 49 | 49 | 48 | 47 | 45 | 44 |
| GNV | TW B | 203 | 90 | 88 | 85 | 83 | 80 | 78 | 76 | 74 | 72 | 70 | 69 |
| GNV | TW B | 205 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW B | 206 | 87 | 85 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 |





| Network | Branch ID | Section | Last | | | | | Forecas | sted PCI | | | | |
|---------|--------------|---------|------|------|------|------|------|---------|----------|------|------|------|------|
| ID | Branch ID | ID | PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | TW B | 208 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | TW B | 210 | 53 | 52 | 51 | 51 | 50 | 49 | 49 | 48 | 47 | 45 | 44 |
| GNV | TW C | 304 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW C | 305 | 75 | 74 | 72 | 71 | 70 | 69 | 68 | 67 | 66 | 65 | 65 |
| GNV | TW C | 307 | 61 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 |
| GNV | TW C | 315 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | TW CONN E | 605 | 86 | 84 | 83 | 81 | 79 | 78 | 76 | 75 | 74 | 73 | 71 |
| GNV | TW CONN E | 610 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 |
| GNV | TW CONN W | 715 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |
| GNV | TW D | 410 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 | 64 | 63 |
| GNV | TW E | 505 | 86 | 84 | 83 | 81 | 79 | 78 | 76 | 75 | 74 | 73 | 71 |
| GNV | TW E | 510 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 | 73 |
| GNV | TW E1 | 515 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 | 57 | 56 | 55 |
| GNV | TW E1 | 517 | 90 | 88 | 86 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 |
| GNV | TW E2 | 520 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 | 61 | 60 | 59 |
| GNV | TW E2 | 522 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |
| GNV | TW E3 | 530 | 69 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 |
| GNV | TW E3 | 532 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 | 73 |
| GNV | TW E4 | 540 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 | 56 |
| GNV | TW E4 | 542 | 90 | 88 | 86 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 |
| GNV | TW E5 | 550 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 | 61 |
| GNV | TW E5 | 552 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |

Major Rehabilitation Planning 2020-2029

Table E-3 Major Rehabilitation Planning 2020-2029

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Pla | nning Cost |
|-----------------|---------------|-----------|---------------|---------|--------------|---------------|------------------------|-----|------------|
| 2020 | GNV | AP N | 4203 | AAC | 23,039 | 63 | AC Restoration | \$ | 254,000.00 |
| 2020 | GNV | AP N | 4210 | APC | 49,872 | 61 | AC Restoration | \$ | 549,000.00 |
| 2020 | GNV | AP N | 4220 | APC | 53,200 | 43 | AC Restoration | \$ | 695,000.00 |
| 2020 | GNV | AP N | 4222 | AAC | 13,199 | 64 | AC Restoration | \$ | 146,000.00 |
| 2020 | GNV | AP N | 4228 | AAC | 14,420 | 56 | AC Restoration | \$ | 159,000.00 |
| 2020 | GNV | AP RU 7 | 5205 | AC | 7,974 | 48 | AC Restoration | \$ | 91,000.00 |
| 2020 | GNV | AP SW | 4305 | AAC | 32,431 | 63 | AC Restoration | \$ | 357,000.00 |
| 2020 | GNV | AP SW | 4310 | AC | 12,201 | 27 | AC Reconstruction | \$ | 171,000.00 |
| 2020 | GNV | AP SW | 4315 | AC | 23,585 | 53 | AC Restoration | \$ | 260,000.00 |
| 2020 | GNV | AP SW | 4325 | AC | 72,728 | 62 | AC Restoration | \$ | 800,000.00 |





| Program | Network | _ | Section Surface Area PCI Rehabilitation | | | | | | |
|---------|---------|-----------|---|---------|---------|--------|-------------------|-----------------|--|
| Year | ID | Branch ID | ID | Surface | (SF) | Before | Туре | Planning Cost | |
| 2020 | GNV | RW 11-29 | 6202 | AAC | 34,697 | 51 | AC Restoration | \$ 382,000.00 | |
| 2020 | GNV | RW 11-29 | 6225 | AAC | 100,100 | 63 | AC Restoration | \$ 1,102,000.00 | |
| 2020 | GNV | TL T-HANG | 3105 | AAC | 52,426 | 62 | AC Restoration | \$ 577,000.00 | |
| 2020 | GNV | TW A | 105 | AAC | 80,019 | 27 | AC Reconstruction | \$ 1,121,000.00 | |
| 2020 | GNV | TW A | 115 | AAC | 22,645 | 59 | AC Restoration | \$ 250,000.00 | |
| 2020 | GNV | TW A | 119 | AAC | 4,962 | 58 | AC Restoration | \$ 55,000.00 | |
| 2020 | GNV | TW A | 130 | AC | 11,380 | 63 | AC Restoration | \$ 126,000.00 | |
| 2020 | GNV | TW A | 135 | AC | 20,258 | 59 | AC Restoration | \$ 223,000.00 | |
| 2020 | GNV | TW A | 140 | AC | 32,303 | 35 | AC Reconstruction | \$ 453,000.00 | |
| 2020 | GNV | TW A | 143 | AC | 5,547 | 44 | AC Restoration | \$ 70,000.00 | |
| 2020 | GNV | TW A | 147 | AC | 3,947 | 57 | AC Restoration | \$ 44,000.00 | |
| 2020 | GNV | TW A | 154 | AAC | 4,561 | 52 | AC Restoration | \$ 51,000.00 | |
| 2020 | GNV | TW B | 210 | AAC | 11,878 | 52 | AC Restoration | \$ 131,000.00 | |
| 2020 | GNV | TW C | 307 | AAC | 44,526 | 60 | AC Restoration | \$ 490,000.00 | |
| 2020 | GNV | TW E1 | 515 | AAC | 19,914 | 64 | AC Restoration | \$ 220,000.00 | |
| 2020 | GNV | TW E4 | 540 | AAC | 29,074 | 64 | AC Restoration | \$ 320,000.00 | |
| 2022 | GNV | AP N | 4240 | AAC | 130,329 | 64 | AC Restoration | \$ 1,434,000.00 | |
| 2022 | GNV | AP N | 4245 | AAC | 15,617 | 64 | AC Restoration | \$ 172,000.00 | |
| 2022 | GNV | RW 11-29 | 6205 | AAC | 630,300 | 64 | AC Restoration | \$ 6,934,000.00 | |
| 2022 | GNV | RW 11-29 | 6207 | AAC | 17,349 | 62 | AC Restoration | \$ 191,000.00 | |
| 2022 | GNV | TW A | 117 | AAC | 9,679 | 64 | AC Restoration | \$ 107,000.00 | |
| 2022 | GNV | TW A | 149 | AAC | 4,225 | 64 | AC Restoration | \$ 47,000.00 | |
| 2022 | GNV | TW E3 | 530 | AAC | 28,702 | 64 | AC Restoration | \$ 316,000.00 | |
| 2023 | GNV | AP N | 4205 | AAC | 189,798 | 64 | AC Restoration | \$ 2,088,000.00 | |
| 2023 | GNV | AP N | 4255 | AAC | 125,665 | 64 | AC Restoration | \$ 1,383,000.00 | |
| 2024 | GNV | AP N | 4226 | AAC | 97,393 | 63 | AC Restoration | \$ 1,072,000.00 | |
| 2024 | GNV | AP N | 4260 | AAC | 104,561 | 64 | AC Restoration | \$ 1,151,000.00 | |
| 2024 | GNV | AP S | 4105 | AAC | 66,500 | 64 | AC Restoration | \$ 732,000.00 | |
| 2024 | GNV | AP SW | 4320 | AAC | 21,340 | 63 | AC Restoration | \$ 235,000.00 | |
| 2024 | GNV | RW 11-29 | 6210 | AAC | 315,150 | 64 | AC Restoration | \$ 3,467,000.00 | |
| 2024 | GNV | RW 11-29 | 6230 | AAC | 50,050 | 64 | AC Restoration | \$ 551,000.00 | |
| 2024 | GNV | TW A | 108 | AAC | 6,264 | 64 | AC Restoration | \$ 69,000.00 | |
| 2025 | GNV | AP N | 4230 | AAC | 36,283 | 64 | AC Restoration | \$ 400,000.00 | |
| 2025 | GNV | AP N | 4241 | AAC | 21,600 | 63 | AC Restoration | \$ 238,000.00 | |
| 2025 | GNV | AP N | 4250 | AAC | 145,100 | 64 | AC Restoration | \$ 1,597,000.00 | |
| 2025 | GNV | TW E2 | 520 | AAC | 19,417 | 63 | AC Restoration | \$ 214,000.00 | |
| 2026 | GNV | AP S | 4125 | AAC | 22,290 | 64 | AC Restoration | \$ 246,000.00 | |
| 2027 | GNV | AP N | 4215 | APC | 76,639 | 64 | AC Restoration | \$ 844,000.00 | |






| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost |
|-----------------|---------------|-----------|---------------|---------|--------------|---------------|------------------------|---------------|
| 2027 | GNV | AP SW | 4330 | AC | 61,003 | 63 | AC Restoration | \$ 672,000.00 |
| 2027 | GNV | TW E5 | 550 | AAC | 19,373 | 63 | AC Restoration | \$ 214,000.00 |
| 2028 | GNV | AP S | 4120 | AAC | 12,825 | 64 | AC Restoration | \$ 142,000.00 |
| 2028 | GNV | TW CONN E | 610 | AAC | 8,448 | 63 | AC Restoration | \$ 93,000.00 |
| 2028 | GNV | TW D | 410 | AAC | 20,831 | 64 | AC Restoration | \$ 230,000.00 |
| 2029 | GNV | AP N | 4270 | AC | 32,960 | 63 | AC Restoration | \$ 363,000.00 |
| 2029 | GNV | AP RU 25 | 5105 | AAC | 9,793 | 63 | AC Restoration | \$ 108,000.00 |
| 2029 | GNV | AP S | 4130 | AAC | 8,760 | 64 | AC Restoration | \$ 97,000.00 |
| 2029 | GNV | TW A | 153 | AAC | 4,523 | 64 | AC Restoration | \$ 50,000.00 |
| 2029 | GNV | TW B | 208 | AAC | 18,964 | 63 | AC Restoration | \$ 209,000.00 |
| 2029 | GNV | TW C | 315 | AAC | 22,886 | 63 | AC Restoration | \$ 252,000.00 |

*All planning cost values have been rounded to the nearest thousand-dollar.

Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029



Airport Pavement Evaluation Report

2019

Gainesville Regional Airport (GNV)





Summary of Gainesville Regional Airport

Gainesville Regional Airport was inspected in April 2019 – the overall weighted PCI value was 76, a condition rating of Satisfactory. The results of the maintenance, repair, and major rehabilitation analysis identified \$1,290,450 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$35,015,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$9,097,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.









Chapter 1 – Introduction

1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating publicuse airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.





1.3 Organization

1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys," evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.





A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- Research and evaluation of existing record documentation was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- An update to the existing Network Definition Map was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- A functional pavement evaluation with PCI Survey inspections was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- Condition Analysis was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- Maintenance, Repair, and Rehabilitation Planning was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." Planninglevel unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.





1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.





During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER[™] (currently known as PAVER[™]) was selected for implementation of the system update. MicroPAVER[™] was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (http://www.dot.state.fl.us/aviation/pavement.shtm) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys." The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.





1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management **Program (PMP)**"). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications."

1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC150/5380-7B "Airport Pavement Management Program (PMP)" an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- An objective and repeatable system for evaluating pavement condition.
- Procedures for predicting future pavement condition.
- Procedures for modeling both past and future pavement performance conditions.
- Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data





- F. Pavement Performance Modeling for the Prediction/Forecast of PCI
- G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements' past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and costeffective manner. Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, which is based on the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.




Figure 1.7.2 (a) Typical Pavement Condition Life Cycle


*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).

Figure 1.7.2 (b) General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

Figure 1.7.2 (b) General Pavement Treatments by Condition Range



Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in Figures 1.7.2 (a) and 1.7.2 (b), however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.


Figures 1.7.2 (c) and 1.7.2 (d), depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.





| | PCI Range | Representative PCI | Representative Pavement Surface | Rehabilitation Activities |
|--------------------------|-----------|--------------------|------------------------------------|---|
| Routine Maintenance | 86-100 | 90 | | Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching. |
| Pavement Preservation | 65-85 | 70 | | Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing. |
| Major Rehabiliation | 40-64 | 50 | B | Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction. |
| Major Reconstruction | 0-39 | 15 | | Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction. |

Figures 1.7.2 (d) Rigid Portland Cement Concrete







1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."
- FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program."
- FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements."
- FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation."
- Department of the Air Force, Air Force Civil Engineer Center "Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements."
- Unified Facilities Criteria (UFC) 3-260-16FA 16 "Airfield Pavement Condition Survey Procedures Pavements."
- Unified Facilities Criteria (UFC) 3-260-03 "Airfield Pavement Evaluation."
- Pavement Management for Airports, Roads, and Parking Lots 2nd Edition, M.Y. Shahin.



Chapter 2





Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVERTM (formerly MicroPAVERTM); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER[™] can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVERTM database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVERTM version 6.5 to a version 7.0.

2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.





A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's Aerial Photo Look Up System (APLUS). This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement branches, which are typically comprised of one or many pavement sections. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related





infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a "parent" pavement network.

Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (±8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet (±2,000 ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

| PMS Network Level | Common Definition | Airport Example | |
|-------------------|--|---|--|
| Network | Overall pavement assets maintained by the Airport | "Tallahassee International Airport – Airfield Pavements" | |
| Branch Name | Commonly defined asset name as established by Airport and by use | "Runway 18-36" | |
| Branch ID | Codified shorthand name for commonly defined asset established for database identification | "RW 18-36" RW, Branch Use, "Runway" 18-36, Runway Facility | |
| Section ID | Codified identification for pavement asset that is distinct by the following: Pavement Composition Construction Work History Aircraft Traffic Condition Records | "6105" | |
| Sample Unit | A numeric identification of an area of pavement (5,000±2,000 SF of AC or 20±8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12. | "300" | |





2.3 Airfield Pavement Structure

2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.





Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 8 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 8 inches in thickness.

Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.





2.4 Airfield Pavement Work History

2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

- 1. Location and Limits of Work.
- Types and Severity of Distresses Repaired.
- 3. Type of Work.
- 4. Cost of Work.
- 5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular 150/5320-6F Airport Pavement Design and **Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.6 Airfield Pavement Condition Index (PCI) Survey

2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)," the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method





can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.





2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2 (a) Pavement Distress Types - Flexible Asphalt Concrete-Surfaced Airfields

| Distress | Common Distress Mechanisms | | | |
|----------------------------------|---|--|--|--|
| Alligator Cracking | Load / Fatigue | | | |
| Bleeding | Construction Quality/ Mix Design | | | |
| Block Cracking | Climate / Age | | | |
| Corrugation | Load / Construction Quality | | | |
| Depression | Load / Subsurface | | | |
| Jet Blast | Aircraft | | | |
| Joint Reflection - Cracking | Climate / Subsurface Pavement / Traffic Load | | | |
| Longitudinal/Transverse Cracking | Climate / Construction Quality | | | |
| Oil Spillage | Aircraft / Vehicle | | | |
| Patching | Utility / Pavement Repair / Age | | | |
| Polished Aggregate | Repeated Traffic Loading | | | |
| Raveling | Climate / Age | | | |
| Rutting | Load / Fatigue | | | |
| Shoving | PCC Pavement Growth / Movement | | | |
| Slippage Cracking | Load / Pavement Bond / Mix Design | | | |
| Swelling | Climate / Subsurface | | | |
| Weathering | Climate / Age | | | |



Table 2.6.2 (b) Pavement Distresses Possible Causes - Flexible Asphalt Concrete-Surfaced Airfields

| | Classification by Possible Causes | | | | | | | | |
|--|---|---|---|--|--|--|--|--|--|
| Load | Climate / Durability | Moisture / Drainage Othe | | | | | | | |
| Alligator Cracking Corrugation Depression Patching of Load-based distress Polished Aggregate Rutting Slippage Cracking | Bleeding Block Cracking Joint Reflection Cracking L/T Cracking Patching of climate / durability-caused distresses Shoving from PCC Raveling Weathering Swelling | Alligator Cracking Depression Patching of moisture / drainage caused distress Swelling Raveling Weathering | Oil Spillage Jet Blast Erosion Polished Aggregate | | | | | | |

Table 2.6.2 (c) Pavement Distresses Possible Effects - Flexible Asphalt Concrete-Surfaced Air fields

| Classification by Possible Effects | | | | | | | | | |
|---|---|---|---|--|--|--|--|--|--|
| Roughness | Skid / Hydroplaning Potential | FOD Potential | Rate of Deterioration and Maintenance Requirements | | | | | | |
| Corrugation Depression Rutting Shoving of asphalt pavement Swelling Raveling Weathering | Bleeding Depression Polished Aggregate Rutting | Block Cracking Joint Reflection Cracking L/T Cracking Slippage Cracking | All Distresses | | | | | | |





Table 2.6.2 (d) Pavement Distresses - Rigid Portland Cement Concrete-Surfaced Airfields

| Distress | Common Distress Mechanisms | | | |
|------------------------------|---|--|--|--|
| Blowup | Climate / ASR | | | |
| Corner Break | Load Repetition / Curling Stresses | | | |
| Linear Cracking | Load Repetition / Curling Stresses / Shrinkage Stresses | | | |
| Durability Cracking | Freeze-Thaw Cycling | | | |
| Joint Seal Damage | Material Deterioration / Construction Quality / Age | | | |
| Small Patch | Pavement Repair | | | |
| Large Patch/Utility Cut | Utility / Pavement Repair | | | |
| Popout | Freeze-Thaw Cycling / ASR / Material Quality | | | |
| Pumping | Load Repetition / Poor Joint Sealant | | | |
| Scaling | Construction Quality / Freeze-Thaw Cycling | | | |
| Faulting | Subgrade Quality / ASR / Inadequate Load Transfer | | | |
| Shattered Slab | Overloading | | | |
| Shrinkage Cracking | Construction Quality / Climate | | | |
| Joint Spalling | Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars | | | |
| Corner Spalling | Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars | | | |
| Alkali-Silica Reaction (ASR) | Construction Quality / Climate / Chemical Reaction | | | |





Table 2.6.2 (e) Pavement Distresses Possible Causes - Rigid Portland Cement Concrete-Surfaced Airfields

| | Classification by Possible Causes | | | | | | | | | |
|---|--|---|---------------------------|--|--|--|--|--|--|--|
| Load | Climate / Durability | Moisture / Drainage | Others | | | | | | | |
| Corner Break Shattered Slab L/T/D Cracking Pumping Patching of Load-associated distress Spalling | Blowup "D" Cracking Joint Seal Damage Popouts Scaling Patch of Climate/Durability-associated distress Shrinkage Cracking Spalling L/T/D Cracking | Corner Break Shattered Slab Pumping Patching of Moisture/Drainage- associated distress | Settlement / Faulting | | | | | | | |

Table 2.6.2 (f) Pavement Distresses Possible Effects - Rigid Portland Cement Concrete-Surfaced Airfields

| Classification by Possible Effects | | | | | | | | | | |
|---|---|---|---|--|--|--|--|--|--|--|
| Roughness | Skid / Hydroplaning Potential | FOD Potential | Rate of Deterioration and Maintenance Requirements | | | | | | | |
| Blowup Corner Break L/T/D Cracking Shattered Slab Settlement / Faulting Spalling | Settlement / Faulting Spalling | Corner Break L/T/D Cracking "D" Cracking Joint Seal Damage Shattered Slab Popouts Scaling | All distresses | | | | | | | |





2.6.3 PCI Survey Inspection Procedures

Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following Tables 2.6.3 (a) and (b) define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

| Number of Total | Sample Units to Inspect | | | | |
|----------------------------|-------------------------|------------------------------|--|--|--|
| Sample Units in Section | Runways | Taxiways, Aprons, and Others | | | |
| 1 - 4 | 1 | 1 | | | |
| 5 - 10 | 2 | 1 | | | |
| 11 - 15 | 3 | 2 | | | |
| 16 - 30 | 5 | 3 | | | |
| 31 - 40 | 7 | 4 | | | |
| 41 - 50 | 8 | 5 | | | |
| 51 or more | 20% but ≤20 | 10% but ≤10 | | | |

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

| Number of Total Sample Units in | Sample Units to Inspect | | | | |
|------------------------------------|-------------------------|------------------------------|--|--|--|
| Section | Runways | Taxiways, Aprons, and Others | | | |
| 1 - 3 | 1 | 1 | | | |
| 4 - 6 | 2 | 1 | | | |
| 7 - 10 | 3 | 2 | | | |
| 11 - 15 | 4 | 2 | | | |
| 16 - 20 | 5 | 3 | | | |
| 21 - 30 | 7 | 3 | | | |
| 31 - 40 | 8 | 4 | | | |
| 41 - 50 | 10 | 5 | | | |
| 51 or more | 20% but ≤20 | 10% but ≤10 | | | |





2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering." Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling," the PCI deduction is not as high as the former "Weathering and Raveling." Therefore, areas identified only as "(57) Weathering" based on current ASTM standards, which were previously identified as "(52) Weathering and Raveling," may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

Rigid Portland Cement Concrete Pavement Distress Updates

The previous methodology defined "(70) Scaling" as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included Alkali-Silica Reaction, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as "(76) Alkali-Silica Reaction / ASR." As a result, the previous "(70) Scaling" numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded "(70) Scaling," and currently do not exhibit "(76) Alkali-Silica Reactivity / ASR" may potentially see an increase in PCI. Additionally, "(73) Shrinkage Cracks" has been redefined as "(73) Shrinkage Cracking". Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage can be caused by both atmospheric conditions and construction. Plastic shrinkage caused by atmospheric conditions develops when there is rapid loss of water in the surface of recently placed pavement. High winds or low humidity are contributing factors to evaporation. These shrinkage cracks can appear as a series of parallel cracks, usually 1 to 3 feet apart and do not extend very deep into the pavement's surface. Plastic shrinkage caused by construction can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

| Use and | Updated Distress | Former Distress in Prior to | Deduction | Potential Effect | |
|----------------------------|---|---|-----------|---|--|
| Surface Type | | 5340-10 | Curve | | |
| AC/AAC/ APC Airfield | (52) Raveling - Low | (52) Weathering and Raveling - Low | No Change | N/A | |
| | (52) Raveling - Medium | (52) Weathering and Raveling - Medium | No Change | N/A | |
| | (52) Raveling - High | (52) Weathering and Raveling - High | No Change | N/A | |
| | (57) Weathering - Low | N/A – was part of 'Weathering and Raveling' | New | Increase in PCI with no maintenance | |
| | (57) Weathering - Medium | N/A – was part of 'Weathering and Raveling' | New | Increase in PCI with no maintenance | |
| | (57) Weathering - High | N/A – was part of 'Weathering and Raveling' | New | Increase in PCI with no maintenance | |
| PCC Airfield | (70) Scaling - Low | (70) Scaling, Map Cracking, and Crazing - Low | New | Increase in PCI with no maintenance | |
| | (70) Scaling - Medium | (70) Scaling, Map Cracking, and Crazing - Medium | New | Increase in PCI with no maintenance | |
| | (70) Scaling - High | (70) Scaling, Map Cracking, and Crazing - High | New | Increase in PCI with no maintenance | |
| | (76) Alkali Silica Reaction – Low | N/A – was part of 'Scaling, Map Cracking, and Crazing' | New | Increase in PCI with no maintenance | |
| | (76) Alkali Silica Reaction – Medium | N/A – was part of 'Scaling, Map Cracking, and Crazing' | New | Increase in PCI with no maintenance | |
| | (76) Alkali Silica Reaction – High | N/A – was part of 'Scaling, Map Cracking, and Crazing' | New | Increase in PCI with no maintenance | |
| | (73) Shrinkage Cracking | (73) Shrinkage Cracking | No Change | Prior distress types identified as 'Scaling, Map Cracking, and Crazing' may now be identified as 'Shrinkage Cracking' | |



Chapter 3





Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following Table 3.1.1 summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. Figure 3.1.1 (a) and Figure 3.1.1 (b) provides an inset view of the 2019 Airfield Pavement Network Definition Exhibit and the 2019 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in Appendix C Technical Exhibits.


Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

| Year | General Work Description |
|-------|---|
| 204.4 | TW E, TW E1-TW E5, TW CONN E - Reconstruction: 4" P-401, 11" P-211 Recompacted Limerock |
| 2014 | TW CONN W - New Construction: 4" P-401, 12" P-211, 12" P-160, 12" P-152 |
| 2015 | RW 11-29, TW A, TW B, TW C - Mill and Overlay: 1.5" Mill and Overlay |
| 2015 | RW 7-25 - Mill and Overlay: 0.5"-1" Mill and 3" Overlay |
| 2016 | AP S - New Construction: 12" P-501, 6" P-203 |

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.




Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit



The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.



Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit



The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.


3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, Figure 3.1.2 summarizes the average age of the pavement sections at the time of the PCI survey inspection. Age is determined to be the number of years since any major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.





Figure 3.1.2 Average Age of Pavements at Inspection



The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.






3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. Figure 3.1.3 summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following Figures 3.1.4 (a) and (b) summarize the applicable pavement types observed at this specific airport's airfield.





Figure 3.1.4 (a) Pavement Surface Type by Area (SF)



Figure 3.1.4 (b) Pavement Surface Type by Area (%)



3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. Appendix A includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.





Table 3.1.5 Pavement System Inventory Details

| Network ID | Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | Area (SF) | Surface Type | Est. Last Construction Date |
|---------------|-----------------------|-----------|------------|---------------|----------------|---------------|--------------|-----------------|-----------------------------------|
| GNV | NORTH APRONS | AP N | APRON | 4203 | 350 | 50 | 23,039 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4205 | 500 | 350 | 189,798 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4210 | 335 | 130 | 49,872 | APC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4215 | 300 | 200 | 76,639 | APC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4220 | 249 | 200 | 53,200 | APC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4222 | 175 | 100 | 13,199 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4226 | 120 | 100 | 97,393 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4228 | 120 | 100 | 14,420 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4230 | 402 | 100 | 36,283 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4240 | 650 | 200 | 130,329 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4241 | 400 | 60 | 21,600 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4245 | 150 | 100 | 15,617 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4250 | 702 | 200 | 145,100 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4255 | 545 | 200 | 125,665 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4260 | 400 | 250 | 104,561 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4270 | 1,500 | 35 | 32,960 | AC | 7/1/2010 |
| GNV | RUN UP APRON AT RW 25 | AP RU 25 | APRON | 5105 | 175 | 50 | 9,793 | AAC | 7/1/2009 |
| GNV | RUN UP APRON AT RW 7 | AP RU 7 | APRON | 5205 | 175 | 50 | 7,974 | AC | 1/1/1980 |
| GNV | SOUTH APRONS | AP S | APRON | 4105 | 630 | 100 | 66,500 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4110 | 700 | 180 | 126,000 | PCC | 1/1/1978 |
| GNV | SOUTH APRONS | AP S | APRON | 4115 | 700 | 50 | 35,000 | PCC | 1/1/1978 |
| GNV | SOUTH APRONS | AP S | APRON | 4120 | 135 | 90 | 12,825 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4125 | 230 | 95 | 22,290 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4130 | 220 | 40 | 8,760 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4135 | 305 | 230 | 70,723 | PCC | 1/1/2016 |





| Network ID | Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | Area (SF) | Surface Type | Est. Last Construction Date |
|---------------|-----------------|-----------|------------|---------------|----------------|---------------|--------------|-----------------|-----------------------------------|
| GNV | SOUTHWEST APRON | AP SW | APRON | 4305 | 250 | 125 | 32,431 | AAC | 1/1/2005 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4310 | 100 | 70 | 12,201 | AC | 12/25/1999 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4315 | 210 | 70 | 23,585 | AC | 12/25/1999 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4320 | 100 | 100 | 21,340 | AAC | 7/1/2010 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4325 | 1,250 | 50 | 72,728 | AC | 7/1/2010 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4330 | 300 | 150 | 61,003 | AC | 1/1/2009 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6201 | 228 | 50 | 12,282 | AAC | 1/1/2015 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6202 | 404 | 100 | 34,697 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6205 | 4,470 | 100 | 630,300 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6207 | 600 | 25 | 17,349 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6210 | 8,200 | 25 | 315,150 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6225 | 1,000 | 100 | 100,100 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6230 | 2,000 | 25 | 50,050 | AAC | 2/1/2005 |
| GNV | RUNWAY 7-25 | RW 7-25 | RUNWAY | 6105 | 4,000 | 80 | 415,800 | AAC | 9/1/2015 |
| GNV | TL T-HANGAR | TL T-HANG | TAXILANE | 3105 | 1,800 | 20 | 52,426 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 104 | 480 | 56 | 13,820 | AAC | 1/1/2015 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 105 | 1,486 | 50 | 80,019 | AAC | 1/1/1973 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 108 | 100 | 50 | 6,264 | AAC | 1/1/2005 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 110 | 430 | 50 | 50,240 | AAC | 1/1/2012 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 115 | 370 | 50 | 22,645 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 117 | 202 | 50 | 9,679 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 119 | 202 | 50 | 4,962 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 120 | 1,880 | 50 | 98,695 | AAC | 1/1/2012 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 130 | 380 | 40 | 11,380 | AC | 1/1/1979 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 135 | 500 | 40 | 20,258 | AC | 1/1/1980 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 140 | 925 | 35 | 32,303 | AC | 1/1/1992 |





| Network ID | Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | Area (SF) | Surface Type | Est. Last Construction Date |
|---------------|-------------------------------------|-----------|------------|---------------|----------------|---------------|--------------|-----------------|-----------------------------------|
| GNV | TAXIWAY A | TW A | TAXIWAY | 143 | 100 | 35 | 5,547 | AC | 1/1/1992 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 147 | 99 | 40 | 3,947 | AC | 1/1/1980 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 149 | 109 | 40 | 4,225 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 152 | 65 | 50 | 3,939 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 153 | 65 | 50 | 4,523 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 154 | 65 | 50 | 4,561 | AAC | 7/1/2009 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 203 | 300 | 50 | 8,026 | AAC | 1/1/2015 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 205 | 2,571 | 50 | 129,976 | AAC | 7/1/2009 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 206 | 320 | 35 | 7,137 | AAC | 1/1/2015 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 208 | 450 | 45 | 18,964 | AAC | 7/1/2009 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 210 | 50 | 50 | 11,878 | AAC | 1/1/2005 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 304 | 400 | 50 | 17,460 | AAC | 1/1/2015 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 305 | 2,000 | 50 | 110,122 | AC | 3/1/2011 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 307 | 275 | 70 | 44,526 | AAC | 7/1/2010 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 315 | 275 | 70 | 22,886 | AAC | 7/1/2010 |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TW CONN E | TAXIWAY | 605 | 200 | 100 | 28,681 | AC | 1/1/2014 |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TW CONN E | TAXIWAY | 610 | 200 | 100 | 8,448 | AAC | 7/1/2009 |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TW CONN W | TAXIWAY | 715 | 300 | 205 | 65,848 | AC | 1/1/2014 |
| GNV | TAXIWAY D | TW D | TAXIWAY | 410 | 358 | 50 | 20,831 | AAC | 7/1/2009 |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TW E | TAXIWAY | 505 | 6,475 | 75 | 491,892 | AC | 1/1/2014 |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TW E | TAXIWAY | 510 | 1,000 | 75 | 75,075 | AC | 1/1/2014 |
| GNV | TAXIWAY E1 | TW E1 | TAXIWAY | 515 | 200 | 105 | 19,914 | AAC | 1/1/2005 |
| GNV | TAXIWAY E1 | TW E1 | TAXIWAY | 517 | 100 | 87 | 15,325 | AC | 1/1/2014 |
| GNV | TAXIWAY E2 | TW E2 | TAXIWAY | 520 | 195 | 125 | 19,417 | AAC | 1/1/2005 |
| GNV | TAXIWAY E2 | TW E2 | TAXIWAY | 522 | 110 | 87 | 15,698 | AC | 1/1/2014 |
| GNV | TAXIWAY E3 | TW E3 | TAXIWAY | 530 | 150 | 175 | 28,702 | AAC | 1/1/2005 |

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

Gainesville Regional Airport (GNV)





| Network ID | Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | Area (SF) | Surface Type | Est. Last Construction Date |
|---------------|-------------|-----------|------------|---------------|----------------|---------------|--------------|-----------------|-----------------------------------|
| GNV | TAXIWAY E3 | TW E3 | TAXIWAY | 532 | 100 | 137 | 20,853 | AC | 1/1/2014 |
| GNV | TAXIWAY E4 | TW E4 | TAXIWAY | 540 | 200 | 155 | 29,074 | AAC | 1/1/2005 |
| GNV | TAXIWAY E4 | TW E4 | TAXIWAY | 542 | 87 | 113 | 17,460 | AC | 1/1/2014 |
| GNV | TAXIWAY E5 | TW E5 | TAXIWAY | 550 | 150 | 75 | 19,373 | AAC | 1/1/2005 |
| GNV | TAXIWAY E5 | TW E5 | TAXIWAY | 552 | 140 | 70 | 9,790 | AC | 1/1/2014 |





PAGE INTENTIONALLY LEFT BLANK



Chapter 4





Chapter 4 – Airfield Pavement Condition

The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

4.1 Airfield Pavement Condition Index (Latest Inspection)

4.1.1 Network-Level Analysis

The following Figure 4.1.1 summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.




Figure 4.1.1 Latest Condition - Overall Network

4.1.2 Branch-Level Analysis

The following Figures 4.1.2 (a) through (d) summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.



Figure 4.1.2 (a) Latest Condition - Runway Pavements




Figure 4.1.2 (b) Latest Condition - Taxiway Pavements







Figure 4.1.2 (c) Latest Condition - Apron Pavements



Figure 4.1.2 (d) Latest Condition - Taxilane Pavements







4.1.3 Section-Level Analysis

The following Table 4.1.3 provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement. Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.





Table 4.1.3 Latest Pavement Condition Index Summary

| Network ID | Branch ID | Branch Name | Branch Use | Section ID | Area (SF) | Surface | PCI | PCI Rating | PCI % Climate | PCI % Load | PCI % Other | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|-----------------------|------------|------------|-----------|---------|-----|--------------|---------------|------------|-------------|------------------------|-------------------------------|
| GNV | AP N | NORTH APRONS | APRON | 4203 | 23,039 | AAC | 64 | Fair | 100% | 0% | 0% | 1 | 4 |
| GNV | AP N | NORTH APRONS | APRON | 4205 | 189,798 | AAC | 72 | Satisfactory | 97% | 0% | 3% | 5 | 41 |
| GNV | AP N | NORTH APRONS | APRON | 4210 | 49,872 | APC | 62 | Fair | 90% | 0% | 10% | 1 | 9 |
| GNV | AP N | NORTH APRONS | APRON | 4215 | 76,639 | APC | 82 | Satisfactory | 50% | 0% | 50% | 3 | 16 |
| GNV | AP N | NORTH APRONS | APRON | 4220 | 53,200 | APC | 46 | Poor | 30% | 63% | 7% | 2 | 11 |
| GNV | AP N | NORTH APRONS | APRON | 4222 | 13,199 | AAC | 66 | Fair | 100% | 0% | 0% | 1 | 3 |
| GNV | AP N | NORTH APRONS | APRON | 4226 | 97,393 | AAC | 73 | Satisfactory | 100% | 0% | 0% | 3 | 20 |
| GNV | AP N | NORTH APRONS | APRON | 4228 | 14,420 | AAC | 58 | Fair | 100% | 0% | 0% | 1 | 3 |
| GNV | AP N | NORTH APRONS | APRON | 4230 | 36,283 | AAC | 77 | Satisfactory | 100% | 0% | 0% | 1 | 9 |
| GNV | AP N | NORTH APRONS | APRON | 4240 | 130,329 | AAC | 70 | Fair | 97% | 0% | 3% | 3 | 29 |
| GNV | AP N | NORTH APRONS | APRON | 4241 | 21,600 | AAC | 76 | Satisfactory | 99% | 0% | 1% | 1 | 5 |
| GNV | AP N | NORTH APRONS | APRON | 4245 | 15,617 | AAC | 70 | Fair | 92% | 0% | 8% | 1 | 3 |
| GNV | AP N | NORTH APRONS | APRON | 4250 | 145,100 | AAC | 77 | Satisfactory | 100% | 0% | 0% | 3 | 29 |
| GNV | AP N | NORTH APRONS | APRON | 4255 | 125,665 | AAC | 72 | Satisfactory | 100% | 0% | 0% | 3 | 25 |
| GNV | AP N | NORTH APRONS | APRON | 4260 | 104,561 | AAC | 74 | Satisfactory | 100% | 0% | 0% | 3 | 22 |
| GNV | AP N | NORTH APRONS | APRON | 4270 | 32,960 | AC | 79 | Satisfactory | 99% | 0% | 1% | 1 | 7 |
| GNV | AP RU 25 | RUN UP APRON AT RW 25 | APRON | 5105 | 9,793 | AAC | 87 | Good | 100% | 0% | 0% | 1 | 2 |
| GNV | AP RU 7 | RUN UP APRON AT RW 7 | APRON | 5205 | 7,974 | AC | 50 | Poor | 99% | 0% | 1% | 1 | 2 |
| GNV | AP S | SOUTH APRONS | APRON | 4105 | 66,500 | AAC | 75 | Satisfactory | 77% | 0% | 23% | 2 | 14 |
| GNV | AP S | SOUTH APRONS | APRON | 4110 | 126,000 | PCC | 88 | Good | 15% | 0% | 85% | 2 | 15 |
| GNV | AP S | SOUTH APRONS | APRON | 4115 | 35,000 | PCC | 84 | Satisfactory | 0% | 0% | 100% | 2 | 8 |
| GNV | AP S | SOUTH APRONS | APRON | 4120 | 12,825 | AAC | 86 | Good | 100% | 0% | 0% | 1 | 2 |
| GNV | AP S | SOUTH APRONS | APRON | 4125 | 22,290 | AAC | 80 | Satisfactory | 65% | 0% | 35% | 1 | 5 |
| GNV | AP S | SOUTH APRONS | APRON | 4130 | 8,760 | AAC | 88 | Good | 76% | 0% | 24% | 1 | 2 |
| GNV | AP S | SOUTH APRONS | APRON | 4135 | 70,723 | PCC | 100 | Good | 14% | 75% | 11% | 2 | 15 |
| GNV | AP SW | SOUTHWEST APRON | APRON | 4305 | 32,431 | AAC | 65 | Fair | 48% | 49% | 3% | 1 | 6 |
| GNV | AP SW | SOUTHWEST APRON | APRON | 4310 | 12,201 | AC | 29 | Very Poor | 100% | 0% | 0% | 1 | 3 |
| GNV | AP SW | SOUTHWEST APRON | APRON | 4315 | 23,585 | AC | 55 | Poor | 100% | 0% | 0% | 1 | 4 |
| GNV | AP SW | SOUTHWEST APRON | APRON | 4320 | 21,340 | AAC | 73 | Satisfactory | 79% | 0% | 21% | 1 | 5 |
| GNV | AP SW | SOUTHWEST APRON | APRON | 4325 | 72,728 | AC | 64 | Fair | 54% | 0% | 46% | 3 | 17 |
| GNV | AP SW | SOUTHWEST APRON | APRON | 4330 | 61,003 | AC | 76 | Satisfactory | 100% | 0% | 0% | 2 | 13 |
| GNV | RW 11-29 | RUNWAY 11-29 | RUNWAY | 6201 | 12,282 | AAC | 88 | Good | 100% | 0% | 0% | 1 | 3 |
| GNV | RW 11-29 | RUNWAY 11-29 | RUNWAY | 6202 | 34,697 | AAC | 52 | Poor | 79% | 11% | 10% | 2 | 7 |
| GNV | RW 11-29 | RUNWAY 11-29 | RUNWAY | 6205 | 630,300 | AAC | 72 | Satisfactory | 97% | 0% | 3% | 20 | 126 |
| GNV | RW 11-29 | RUNWAY 11-29 | RUNWAY | 6207 | 17,349 | AAC | 70 | Fair | 96% | 0% | 4% | 1 | 3 |
| GNV | RW 11-29 | RUNWAY 11-29 | RUNWAY | 6210 | 315,150 | AAC | 76 | Satisfactory | 95% | 0% | 5% | 13 | 64 |
| GNV | RW 11-29 | RUNWAY 11-29 | RUNWAY | 6225 | 100,100 | AAC | 66 | Fair | 99% | 0% | 1% | 5 | 20 |

2019





| Network ID | Branch ID | Branch Name | Branch Use | Section ID | Area (SF) | Surface | PCI | PCI Rating | PCI % Climate | PCI % Load | PCI % Other | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|-------------------------------------|------------|------------|-----------|---------|-----|--------------|---------------|------------|-------------|------------------------|-------------------------------|
| GNV | RW 11-29 | RUNWAY 11-29 | RUNWAY | 6230 | 50,050 | AAC | 76 | Satisfactory | 100% | 0% | 0% | 3 | 12 |
| GNV | RW 7-25 | RUNWAY 7-25 | RUNWAY | 6105 | 415,800 | AAC | 89 | Good | 92% | 0% | 8% | 17 | 83 |
| GNV | TL T-HANG | TL T-HANGAR | TAXILANE | 3105 | 52,426 | AAC | 63 | Fair | 100% | 0% | 0% | 3 | 11 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 104 | 13,820 | AAC | 89 | Good | 86% | 0% | 14% | 1 | 3 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 105 | 80,019 | AAC | 30 | Very Poor | 73% | 24% | 3% | 3 | 16 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 108 | 6,264 | AAC | 72 | Satisfactory | 92% | 0% | 8% | 1 | 1 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 110 | 50,240 | AAC | 89 | Good | 100% | 0% | 0% | 2 | 10 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 115 | 22,645 | AAC | 60 | Fair | 93% | 0% | 7% | 1 | 4 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 117 | 9,679 | AAC | 69 | Fair | 100% | 0% | 0% | 1 | 2 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 119 | 4,962 | AAC | 59 | Fair | 100% | 0% | 0% | 1 | 1 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 120 | 98,695 | AAC | 91 | Good | 100% | 0% | 0% | 3 | 20 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 130 | 11,380 | AC | 64 | Fair | 100% | 0% | 0% | 1 | 3 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 135 | 20,258 | AC | 60 | Fair | 100% | 0% | 0% | 1 | 5 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 140 | 32,303 | AC | 37 | Very Poor | 100% | 0% | 0% | 2 | 9 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 143 | 5,547 | AC | 46 | Poor | 98% | 0% | 2% | 1 | 1 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 147 | 3,947 | AC | 58 | Fair | 98% | 0% | 2% | 1 | 1 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 149 | 4,225 | AAC | 68 | Fair | 100% | 0% | 0% | 1 | 1 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 152 | 3,939 | AAC | 85 | Satisfactory | 100% | 0% | 0% | 1 | 1 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 153 | 4,523 | AAC | 82 | Satisfactory | 100% | 0% | 0% | 1 | 1 |
| GNV | TW A | TAXIWAY A | TAXIWAY | 154 | 4,561 | AAC | 53 | Poor | 100% | 0% | 0% | 1 | 1 |
| GNV | TW B | TAXIWAY B | TAXIWAY | 203 | 8,026 | AAC | 90 | Good | 100% | 0% | 0% | 1 | 2 |
| GNV | TW B | TAXIWAY B | TAXIWAY | 205 | 129,976 | AAC | 89 | Good | 100% | 0% | 0% | 3 | 26 |
| GNV | TW B | TAXIWAY B | TAXIWAY | 206 | 7,137 | AAC | 87 | Good | 100% | 0% | 0% | 1 | 2 |
| GNV | TW B | TAXIWAY B | TAXIWAY | 208 | 18,964 | AAC | 81 | Satisfactory | 100% | 0% | 0% | 1 | 5 |
| GNV | TW B | TAXIWAY B | TAXIWAY | 210 | 11,878 | AAC | 53 | Poor | 89% | 0% | 11% | 1 | 2 |
| GNV | TW C | TAXIWAY C | TAXIWAY | 304 | 17,460 | AAC | 89 | Good | 100% | 0% | 0% | 2 | 4 |
| GNV | TW C | TAXIWAY C | TAXIWAY | 305 | 110,122 | AC | 75 | Satisfactory | 64% | 0% | 36% | 3 | 22 |
| GNV | TW C | TAXIWAY C | TAXIWAY | 307 | 44,526 | AAC | 61 | Fair | 96% | 0% | 4% | 2 | 12 |
| GNV | TW C | TAXIWAY C | TAXIWAY | 315 | 22,886 | AAC | 81 | Satisfactory | 100% | 0% | 0% | 1 | 5 |
| GNV | TW CONN E | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 605 | 28,681 | AC | 86 | Good | 93% | 0% | 7% | 1 | 6 |
| GNV | TW CONN E | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 610 | 8,448 | AAC | 79 | Satisfactory | 93% | 0% | 7% | 1 | 2 |
| GNV | TW CONN W | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 715 | 65,848 | AC | 91 | Good | 100% | 0% | 0% | 2 | 14 |
| GNV | TW D | TAXIWAY D | TAXIWAY | 410 | 20,831 | AAC | 80 | Satisfactory | 100% | 0% | 0% | 1 | 4 |
| GNV | TW E | TAXIWAY E - PARALLEL RW 11-29 | TAXIWAY | 505 | 491,892 | AC | 86 | Good | 93% | 0% | 7% | 10 | 129 |
| GNV | TW E | TAXIWAY E - PARALLEL RW 11-29 | TAXIWAY | 510 | 75,075 | AC | 89 | Good | 100% | 0% | 0% | 3 | 20 |
| GNV | TW E1 | TAXIWAY E1 | TAXIWAY | 515 | 19,914 | AAC | 65 | Fair | 94% | 0% | 6% | 1 | 4 |
| GNV | TW E1 | TAXIWAY E1 | TAXIWAY | 517 | 15,325 | AC | 90 | Good | 100% | 0% | 0% | 1 | 3 |
| GNV | TW E2 | TAXIWAY E2 | TAXIWAY | 520 | 19,417 | AAC | 73 | Satisfactory | 89% | 0% | 11% | 1 | 4 |

Statewide Airfield Pavement
Management Program
Airport Pavement
Evaluation Report

2019

Gainesville Regional Airport (GNV)






| Network ID | Branch ID | Branch Name | Branch Use | Section ID | Area (SF) | Surface | PCI | PCI Rating | PCI % Climate | PCI % Load | PCI % Other | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|-------------|------------|------------|-----------|---------|-----|--------------|---------------|------------|-------------|------------------------|-------------------------------|
| GNV | TW E2 | TAXIWAY E2 | TAXIWAY | 522 | 15,698 | AC | 91 | Good | 100% | 0% | 0% | 1 | 3 |
| GNV | TW E3 | TAXIWAY E3 | TAXIWAY | 530 | 28,702 | AAC | 69 | Fair | 89% | 0% | 11% | 1 | 5 |
| GNV | TW E3 | TAXIWAY E3 | TAXIWAY | 532 | 20,853 | AC | 89 | Good | 100% | 0% | 0% | 1 | 4 |
| GNV | TW E4 | TAXIWAY E4 | TAXIWAY | 540 | 29,074 | AAC | 66 | Fair | 84% | 0% | 16% | 1 | 5 |
| GNV | TW E4 | TAXIWAY E4 | TAXIWAY | 542 | 17,460 | AC | 90 | Good | 100% | 0% | 0% | 1 | 4 |
| GNV | TW E5 | TAXIWAY E5 | TAXIWAY | 550 | 19,373 | AAC | 77 | Satisfactory | 96% | 0% | 4% | 1 | 4 |
| GNV | TW E5 | TAXIWAY E5 | TAXIWAY | 552 | 9,790 | AC | 91 | Good | 100% | 0% | 0% | 1 | 2 |



Figure 4.1.3 is an inset view of the 2019 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits.**

Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit







4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The field PCI Survey performed at Gainesville Regional Airport (GNV) was completed in April of 2019. The resulting overall area-weighted average PCI value was 76 representing a condition rating of Satisfactory. Gainesville Regional Airport is serviced by two runways; Runway 7-25 is 100-ft wide and 4,158-ft long and Runway 11-29 is 150-ft wide and 7,504-ft long.

Based on the FAA 5010 Report as of 09/12/2019 the Airport has reported 62,726 operations for 12 months ending 09/20/2018.

4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and samplelevel may be referenced for all pavements assessed as part of this System Update. The branchlevel observations discussed are limited to select branches based on use and condition.

Runway 7-25

Runway 7-25 consists of 1 section constructed of AAC. The last construction year for Runway 7-25 was 2015. The area-weighted average PCI for Runway 7-25 is 89 representing a Good condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Runway 7-25 consist of Longitudinal & Transverse Cracking, Swelling, and Weathering.

Runway 11-29

Runway 11-29 consists of 7 sections constructed of AA. The last construction years range from 2005 to 2015. The area-weighted average PCI for Runway 11-29 is 72 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Runway 11-29 consist of Alligator Cracking, Bleeding, Depression, Jet Blast Erosion, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Taxiway A

Taxiway A consists of 17 sections constructed of AC and AAC. The last construction years range from 1973 to 2015. The area-weighted average PCI for Taxiway A is 65 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on Taxiway A consist of Alligator Cracking, Bleeding, Block Cracking, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Rutting, Swelling, and Weathering.

Taxiway C

Taxiway C consists of 4 sections constructed of AC and AAC. The last construction years range from 2010 to 2015. The area-weighted average PCI for Taxiway C is 73 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway C consist of Bleeding, Block Cracking, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.





North Aprons

The North Aprons consists of 16 sections constructed of AC, AAC, and APC. The last construction year for North Aprons was 2010. The area-weighted average PCI for North Aprons is 71 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on North Aprons consist of Alligator Cracking, Bleeding, Block Cracking, Depression, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Swelling, and Weathering.

Many sections with the North Aprons were seal coated which has begun to exhibit spider cracking over a large portion of the sealed area. The seal coat cracking is considered raveling and is causing an accelerated deterioration. Specific areas of the apron used by executive type aircraft displayed areas of Alligator Cracking. Alligator cracking is a load classified distress type and typically indicates the pavement is structurally inadequate for the traffic utilizing the pavement.

South Aprons

The South Aprons consists of 7 sections constructed of AAC and PCC. The last construction years range from 1978 to 2016. The area-weighted average PCI for South Aprons is 86 representing a Good condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on South Aprons consist of Bleeding, Joint Reflection Cracking, Longitudinal & Transverse Cracking, Oil Spillage, Weathering, Joint Seal Damage, Shrinkage Cracking, Joint Spall, and Corner Spall.

Figure 4.2.2 Pavement Condition Summary by Facility Use

| Facility Use | Area-Weighted Average PCI | Condition Rating |
|--------------|---------------------------|------------------|
| Runway | 76 | Satisfactory |
| Taxiway | 79 | Satisfactory |
| Apron | 73 | Satisfactory |
| Taxilane | 63 | Fair |





4.3 Forecasted Pavement Conditions

4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to developed forecasted PCI values based on historic trends and statistical models.

4.3.2 Branch-Level Pavement Condition Forecast

The following Figures 4.3.2 (a) through (c) depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2020 through January 2029.




Figure 4.3.2 (a) Forecasted Runway Pavement Performance



Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance







4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.





Table 4.3.3 Forecasted PCI 2020-2029

| Network | Draugh ID | Section | Last PCI | | | | | Forecas | sted PCI | | | | |
|---------|-----------|---------|----------|------|------|------|------|---------|----------|------|------|------|------|
| ID | Branch ID | ID | Last PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | AP N | 4203 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4205 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 |
| GNV | AP N | 4210 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 | 59 | 59 | 58 |
| GNV | AP N | 4215 | 82 | 79 | 77 | 74 | 71 | 69 | 67 | 65 | 64 | 62 | 61 |
| GNV | AP N | 4220 | 46 | 43 | 39 | 34 | 31 | 28 | 26 | 24 | 22 | 19 | 17 |
| GNV | AP N | 4222 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4226 | 73 | 71 | 68 | 66 | 65 | 63 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP N | 4228 | 58 | 56 | 54 | 52 | 49 | 45 | 41 | 37 | 33 | 29 | 27 |
| GNV | AP N | 4230 | 77 | 75 | 72 | 70 | 67 | 66 | 64 | 63 | 62 | 61 | 60 |
| GNV | AP N | 4240 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4241 | 76 | 74 | 71 | 69 | 67 | 65 | 63 | 62 | 61 | 61 | 60 |
| GNV | AP N | 4245 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4250 | 77 | 75 | 72 | 70 | 67 | 66 | 64 | 63 | 62 | 61 | 60 |
| GNV | AP N | 4255 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 |
| GNV | AP N | 4260 | 74 | 72 | 69 | 67 | 65 | 64 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP N | 4270 | 79 | 77 | 76 | 74 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | AP RU 25 | 5105 | 87 | 84 | 82 | 79 | 76 | 73 | 71 | 69 | 67 | 65 | 63 |
| GNV | AP RU 7 | 5205 | 50 | 48 | 47 | 45 | 44 | 42 | 40 | 39 | 37 | 36 | 34 |
| GNV | AP S | 4105 | 75 | 73 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 |
| GNV | AP S | 4110 | 88 | 87 | 86 | 85 | 85 | 84 | 83 | 82 | 82 | 81 | 80 |
| GNV | AP S | 4115 | 84 | 83 | 82 | 81 | 81 | 80 | 79 | 78 | 77 | 76 | 75 |
| GNV | AP S | 4120 | 86 | 83 | 81 | 78 | 75 | 72 | 70 | 68 | 66 | 64 | 63 |
| GNV | AP S | 4125 | 80 | 77 | 75 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 |
| GNV | AP S | 4130 | 88 | 85 | 83 | 80 | 77 | 74 | 72 | 69 | 67 | 65 | 64 |
| GNV | AP S | 4135 | 100 | 98 | 96 | 94 | 92 | 91 | 90 | 89 | 88 | 87 | 86 |





| Network | Down all ID | Section | Last DOL | | | | | Foreca | sted PCI | | | | |
|---------|-------------|---------|----------|------|------|------|------|--------|----------|------|------|------|------|
| ID | Branch ID | ID | Last PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | AP SW | 4305 | 65 | 63 | 62 | 61 | 61 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP SW | 4310 | 29 | 27 | 26 | 24 | 23 | 21 | 19 | 18 | 16 | 15 | 13 |
| GNV | AP SW | 4315 | 55 | 53 | 52 | 50 | 49 | 47 | 45 | 44 | 42 | 41 | 39 |
| GNV | AP SW | 4320 | 73 | 71 | 68 | 66 | 65 | 63 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP SW | 4325 | 64 | 62 | 61 | 59 | 58 | 56 | 54 | 53 | 51 | 50 | 48 |
| GNV | AP SW | 4330 | 76 | 74 | 73 | 71 | 70 | 68 | 66 | 65 | 63 | 62 | 60 |
| GNV | RW 11-29 | 6201 | 88 | 85 | 83 | 81 | 80 | 78 | 77 | 76 | 74 | 72 | 69 |
| GNV | RW 11-29 | 6202 | 52 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 46 | 46 |
| GNV | RW 11-29 | 6205 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 | 54 | 54 |
| GNV | RW 11-29 | 6207 | 70 | 68 | 65 | 62 | 59 | 57 | 56 | 55 | 54 | 54 | 54 |
| GNV | RW 11-29 | 6210 | 76 | 74 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 |
| GNV | RW 11-29 | 6225 | 66 | 63 | 61 | 58 | 56 | 55 | 54 | 54 | 54 | 54 | 52 |
| GNV | RW 11-29 | 6230 | 76 | 74 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 |
| GNV | RW 7-25 | 6105 | 89 | 86 | 84 | 82 | 80 | 79 | 78 | 76 | 74 | 72 | 70 |
| GNV | TL T-HANG | 3105 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 |
| GNV | TW A | 104 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW A | 105 | 30 | 27 | 24 | 20 | 16 | 11 | 6 | 0 | 0 | 0 | 0 |
| GNV | TW A | 108 | 72 | 70 | 69 | 67 | 65 | 64 | 63 | 62 | 60 | 59 | 59 |
| GNV | TW A | 110 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW A | 115 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 | 53 |
| GNV | TW A | 117 | 69 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 |
| GNV | TW A | 119 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 | 53 | 52 |
| GNV | TW A | 120 | 91 | 89 | 86 | 84 | 81 | 79 | 77 | 75 | 73 | 71 | 69 |
| GNV | TW A | 130 | 64 | 63 | 62 | 61 | 61 | 60 | 59 | 59 | 58 | 57 | 56 |
| GNV | TW A | 135 | 60 | 59 | 58 | 57 | 57 | 56 | 55 | 54 | 53 | 51 | 50 |
| GNV | TW A | 140 | 37 | 35 | 32 | 29 | 25 | 22 | 18 | 14 | 11 | 7 | 3 |
| GNV | TW A | 143 | 46 | 44 | 42 | 40 | 38 | 35 | 32 | 30 | 26 | 23 | 19 |
| | | | | | | | | | | | | | |





| Network | | Section | | | | | | Forecas | sted PCI | | | | |
|---------|-----------|---------|----------|------|------|------|------|---------|----------|------|------|------|------|
| ID | Branch ID | ID | Last PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | TW A | 147 | 58 | 57 | 56 | 55 | 54 | 53 | 52 | 51 | 49 | 48 | 46 |
| GNV | TW A | 149 | 68 | 66 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 | 57 |
| GNV | TW A | 152 | 85 | 83 | 80 | 78 | 76 | 74 | 72 | 70 | 69 | 67 | 66 |
| GNV | TW A | 153 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 | 64 |
| GNV | TW A | 154 | 53 | 52 | 51 | 51 | 50 | 49 | 49 | 48 | 47 | 45 | 44 |
| GNV | TW B | 203 | 90 | 88 | 85 | 83 | 80 | 78 | 76 | 74 | 72 | 70 | 69 |
| GNV | TW B | 205 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW B | 206 | 87 | 85 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 |
| GNV | TW B | 208 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | TW B | 210 | 53 | 52 | 51 | 51 | 50 | 49 | 49 | 48 | 47 | 45 | 44 |
| GNV | TW C | 304 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW C | 305 | 75 | 74 | 72 | 71 | 70 | 69 | 68 | 67 | 66 | 65 | 65 |
| GNV | TW C | 307 | 61 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 |
| GNV | TW C | 315 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | TW CONN E | 605 | 86 | 84 | 83 | 81 | 79 | 78 | 76 | 75 | 74 | 73 | 71 |
| GNV | TW CONN E | 610 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 |
| GNV | TW CONN W | 715 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |
| GNV | TW D | 410 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 | 64 | 63 |
| GNV | TW E | 505 | 86 | 84 | 83 | 81 | 79 | 78 | 76 | 75 | 74 | 73 | 71 |
| GNV | TW E | 510 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 | 73 |
| GNV | TW E1 | 515 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 | 57 | 56 | 55 |
| GNV | TW E1 | 517 | 90 | 88 | 86 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 |
| GNV | TW E2 | 520 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 | 61 | 60 | 59 |
| GNV | TW E2 | 522 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |
| GNV | TW E3 | 530 | 69 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 |
| GNV | TW E3 | 532 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 | 73 |
| GNV | TW E4 | 540 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 | 56 |

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

Gainesville Regional Airport (GNV)





| Network | Branch ID | Section | Loot DCI | Forecasted PCI | | | | | | | | | |
|---------|-----------|---------|----------|----------------|------|------|------|------|------|------|------|------|------|
| ID | Branch ID | ID | Last PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | TW E4 | 542 | 90 | 88 | 86 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 |
| GNV | TW E5 | 550 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 | 61 |
| GNV | TW E5 | 552 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |





4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA AC 150/5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements to determine structural and/or functional conditions at the time of project.







Chapter 5 - Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- Localized Maintenance and Repair includes patching and crack sealing.
- > Global Treatments include surface seals and rejuvenators for flexible pavements.
- > Major Rehabilitation includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distressed pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety ("stopgap") measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.





5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in Table 5.2 (a) and Table 5.2 (b), for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and the FDOT Airfield Pavement Distress Repair Manual. Additionally, the Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis - it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2 (a) Localized Maintenance and Repair - Flexible Asphalt Concrete

| Distress | Severity | Description | Code | Work Type | Work Unit |
|----------|----------|--------------|------------|------------------------------------|-----------|
| 41 | Low | ALLIGATOR CR | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 41 | Medium | ALLIGATOR CR | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 41 | High | ALLIGATOR CR | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 42 | N/A | BLEEDING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 43 | Low | BLOCK CR | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 43 | Medium | BLOCK CR | FDOT-CS-AC | FDOT - CRACK SEALING - AC | Ft |
| 43 | High | BLOCK CR | FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | SqFt |
| 44 | Low | CORRUGATION | FDOT-ML-AC | FDOT - MILLING - AC | SqFt |
| 44 | Medium | CORRUGATION | FDOT-ML-AC | FDOT - MILLING - AC | SqFt |
| 44 | High | CORRUGATION | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 45 | Low | DEPRESSION | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 45 | Medium | DEPRESSION | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 45 | High | DEPRESSION | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 46 | N/A | JET BLAST | FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | SqFt |
| 47 | Low | JT REF. CR | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 47 | Medium | JT REF. CR | FDOT-CS-AC | FDOT - CRACK SEALING - AC | Ft |
| 47 | High | JT REF. CR | FDOT-CS-AC | FDOT - CRACK SEALING - AC | Ft |





| Distress | Severity | Description | Code | Work Type | Work Unit |
|----------|----------|--------------|------------|------------------------------------|-----------|
| 48 | Low | L&TCR | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 48 | Medium | L&TCR | FDOT-CS-AC | FDOT - CRACK SEALING - AC | Ft |
| 48 | High | L&TCR | FDOT-CS-AC | FDOT - CRACK SEALING - AC | Ft |
| 49 | N/A | OIL SPILLAGE | FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | SqFt |
| 50 | Low | PATCHING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 50 | Medium | PATCHING | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 50 | High | PATCHING | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 51 | N/A | POLISHED AG | FDOT-SS-LO | FDOT - SURFACE SEAL | SqFt |
| 52 | Low | RAVELING | FDOT-SS-LO | FDOT - SURFACE SEAL | SqFt |
| 52 | Medium | RAVELING | FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | SqFt |
| 52 | High | RAVELING | FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | SqFt |
| 53 | Low | RUTTING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 53 | Medium | RUTTING | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 53 | High | RUTTING | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 54 | Low | SHOVING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 54 | Medium | SHOVING | FDOT-ML-AC | FDOT - MILLING - AC | SqFt |
| 54 | High | SHOVING | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 55 | N/A | SLIPPAGE CR | FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | SqFt |
| 56 | Low | SWELLING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 56 | Medium | SWELLING | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 56 | High | SWELLING | FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | SqFt |
| 57 | Low | WEATHERING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 57 | Medium | WEATHERING | FDOT-SS-LO | FDOT - SURFACE SEAL | SqFt |
| 57 | High | WEATHERING | FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | SqFt |

Table 5.2 (b) Localized Maintenance and Repair - Rigid Portland Cement Concrete

| Distress | Severity | Description | Code | Work Type | Work Unit |
|----------|----------|--------------|------------|-------------------------------------|-----------|
| 61 | Low | BLOW-UP | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 61 | Medium | BLOW-UP | FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | SqFt |
| 61 | High | BLOW-UP | FDOT-SL-PC | FDOT - SLAB REPLACEMENT - PCC | SqFt |
| 62 | Low | CORNER BREAK | FDOT-CS-PC | FDOT - CRACK SEALING - PCC | Ft |
| 62 | Medium | CORNER BREAK | FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | SqFt |
| 62 | High | CORNER BREAK | FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | SqFt |
| 63 | Low | LINEAR CR | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 63 | Medium | LINEAR CR | FDOT-CS-PC | FDOT - CRACK SEALING - PCC | Ft |
| 63 | High | LINEAR CR | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |





| Distress | Severity | Description | Code | Work Type | Work Unit |
|----------|----------|--------------|------------|-------------------------------------|-----------|
| 64 | Low | DURABIL. CR | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 64 | Medium | DURABIL. CR | FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | SqFt |
| 64 | High | DURABIL. CR | FDOT-SL-PC | FDOT - SLAB REPLACEMENT - PCC | SqFt |
| 65 | Low | JT SEAL DMG | FDOT-JS-PC | FDOT - JOINT SEAL - PCC | Ft |
| 65 | Medium | JT SEAL DMG | FDOT-JS-PC | FDOT - JOINT SEAL - PCC | Ft |
| 65 | High | JT SEAL DMG | FDOT-JS-PC | FDOT - JOINT SEAL - PCC | Ft |
| 66 | Low | SMALL PATCH | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 66 | Medium | SMALL PATCH | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 66 | High | SMALL PATCH | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 67 | Low | LARGE PATCH | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 67 | Medium | LARGE PATCH | FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | SqFt |
| 67 | High | LARGE PATCH | FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | SqFt |
| 68 | N/A | POPOUTS | FDOT-PO-FL | FDOT - POPOUT FILLER | SqFt |
| 69 | N/A | PUMPING | FDOT-SB-PC | FDOT – SLAB STABILIZATION - PCC | SqFt |
| 70 | Low | SCALING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 70 | Medium | SCALING | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 70 | High | SCALING | FDOT-SL-PC | FDOT - SLAB REPLACEMENT - PCC | SqFt |
| 71 | Low | FAULTING | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 71 | Medium | FAULTING | FDOT-GR-PP | FDOT - GRINDING (LOCALIZED) | Ft |
| 71 | High | FAULTING | FDOT-GR-PP | FDOT - GRINDING (LOCALIZED) | Ft |
| 72 | Low | SHAT. SLAB | FDOT-CS-PC | FDOT - CRACK SEALING - PCC | Ft |
| 72 | Medium | SHAT. SLAB | FDOT-SL-PC | FDOT - SLAB REPLACEMENT - PCC | SqFt |
| 72 | High | SHAT. SLAB | FDOT-SL-PC | FDOT - SLAB REPLACEMENT - PCC | SqFt |
| 73 | N/A | SHRINKAGE CR | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 74 | Low | JOINT SPALL | FDOT-CS-PC | FDOT - CRACK SEALING - PCC | Ft |
| 74 | Medium | JOINT SPALL | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 74 | High | JOINT SPALL | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 75 | Low | CORNER SPALL | FDOT-CS-PC | FDOT - CRACK SEALING - PCC | Ft |
| 75 | Medium | CORNER SPALL | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 75 | High | CORNER SPALL | FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | SqFt |
| 76 | Low | ASR | FDOT-MO-PV | FDOT - MONITOR | N/A |
| 76 | Medium | ASR | FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | SqFt |
| 76 | High | ASR | FDOT-SL-PC | FDOT - SLAB REPLACEMENT - PCC | SqFt |





Table 5.2 (c) Localized Repair Planning-Level Unit Costs - Flexible Asphalt Concrete

| Code | Name | Cost | Units |
|------------|------------------------------------|---------|-------|
| FDOT-SS-LO | FDOT - SURFACE SEAL | \$0.55 | SqFt |
| FDOT-ML-AC | FDOT - MILLING - AC | \$2.00 | SqFt |
| FDOT-GR-PP | FDOT - GRINDING (LOCALIZED) | \$2.00 | Ft |
| FDOT-CS-AC | FDOT - CRACK SEALING - AC | \$3.00 | Ft |
| FDOT-MO-PV | FDOT - MONITOR | \$0.00 | SqFt |
| FDOT-PA-AF | FDOT - PATCHING - AC FULL DEPTH | \$12.50 | SqFt |
| FDOT-PA-AP | FDOT - PATCHING - AC PARTIAL DEPTH | \$5.50 | SqFt |

Table 5.2 (d) Localized M&R Planning-Level Unit Costs - Rigid Portland Cement Concrete

| Code | Name | Cost | Units |
|------------|-------------------------------------|----------|-------|
| FDOT-PA-PF | FDOT - PATCHING - PCC FULL DEPTH | \$185.00 | SqFt |
| FDOT-SL-PC | FDOT - SLAB REPLACEMENT - PCC | \$30.00 | SqFt |
| FDOT-SB-PC | FDOT - SLAB STABILIZATION - PCC | \$30.00 | SqFt |
| FDOT-PA-PP | FDOT - PATCHING - PCC PARTIAL DEPTH | \$72.00 | SqFt |
| FDOT-PO-FL | FDOT - POPOUT FILLER | \$0.05 | SqFt |
| FDOT-GR-PP | FDOT - GRINDING (LOCALIZED) | \$2.00 | Ft |
| FDOT-CS-PC | FDOT - CRACK SEALING - PCC | \$4.25 | Ft |
| FDOT-MO-PV | FDOT - MONITOR | \$0.00 | N/A |
| FDOT-JS-PC | FDOT - JOINT SEAL - PCC | \$2.75 | Ft |

^{*}PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.





5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in 5.2 Localized M&R Policy. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. Appendix B provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to nearterm Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3 (a)** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

| Work Description | Work Category | Rough Estimate of Work Quantity | Work Units | Pla | nning Material Cost |
|-------------------------------------|------------------|---------------------------------------|---------------|-----|------------------------|
| FDOT - SURFACE SEAL | PREVENTIVE | 541,735 | SqFt | \$ | 297,960.00 |
| FDOT - CRACK SEALING - AC | PREVENTIVE | 55 | Ft | \$ | 170.00 |
| FDOT - PATCHING - AC FULL DEPTH | PREVENTIVE | 695 | SqFt | \$ | 8,650.00 |
| FDOT - PATCHING - AC PARTIAL DEPTH | PREVENTIVE | 6,260 | SqFt | \$ | 34,430.00 |
| FDOT - JOINT SEAL - PCC | PREVENTIVE | 5,860 | Ft | \$ | 16,120.00 |
| FDOT - CRACK SEALING - PCC | PREVENTIVE | 55 | Ft | \$ | 240.00 |
| FDOT - PATCHING - PCC PARTIAL DEPTH | PREVENTIVE | 80 | SqFt | \$ | 5,750.00 |
| FDOT - PATCHING - AC FULL DEPTH | STOPGAP | 7,395 | SqFt | \$ | 92,410.00 |
| FDOT - SURFACE SEAL | STOPGAP | 324,940 | SqFt | \$ | 178,720.00 |
| FDOT - PATCHING - AC PARTIAL DEPTH | STOPGAP | 118,110 | SqFt | \$ | 649,600.00 |
| FDOT - CRACK SEALING - AC | STOPGAP | 2,135 | Ft | \$ | 6,400.00 |





The following Table 5.3 (b) provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved "End Condition" of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

| Network ID | Branch ID | Section ID | Area (SF) | Start Condition | End Condition | Cost |
|------------|-----------|------------|-----------|-----------------|---------------|-----------------|
| GNV | AP N | 4203 | 23,039 | 64 | 69 | \$ 2,540.00 |
| GNV | AP N | 4205 | 189,798 | 72 | 79 | \$ 20,880.00 |
| GNV | AP N | 4210 | 49,872 | 62 | 66 | \$ 6,570.00 |
| GNV | AP N | 4215 | 76,639 | 82 | 96 | \$ 12,680.00 |
| GNV | AP N | 4220 | 53,200 | 46 | 77 | \$ 57,910.00 |
| GNV | AP N | 4222 | 13,199 | 66 | 71 | \$ 2,390.00 |
| GNV | AP N | 4226 | 97,393 | 73 | 84 | \$ 22,350.00 |
| GNV | AP N | 4228 | 14,420 | 58 | 78 | \$ 29,380.00 |
| GNV | AP N | 4230 | 36,283 | 77 | 90 | \$ 4,000.00 |
| GNV | AP N | 4240 | 130,329 | 70 | 78 | \$ 12,770.00 |
| GNV | AP N | 4241 | 21,600 | 76 | 79 | \$ 2,050.00 |
| GNV | AP N | 4245 | 15,617 | 70 | 80 | \$ 1,300.00 |
| GNV | AP N | 4250 | 145,100 | 77 | 90 | \$ 15,970.00 |
| GNV | AP N | 4255 | 125,665 | 72 | 84 | \$ 34,300.00 |
| GNV | AP N | 4260 | 104,561 | 74 | 82 | \$ 7,430.00 |
| GNV | AP N | 4270 | 32,960 | 79 | 83 | \$ 2,550.00 |
| GNV | AP RU 25 | 5105 | 9,793 | 87 | 91 | \$ 270.00 |
| GNV | AP RU 7 | 5205 | 7,974 | 50 | 62 | \$ 5,140.00 |
| GNV | AP S | 4105 | 66,500 | 75 | 79 | \$ 1,830.00 |
| GNV | AP S | 4110 | 126,000 | 88 | 90 | \$ 17,700.00 |
| GNV | AP S | 4115 | 35,000 | 84 | 87 | \$ 4,430.00 |
| GNV | AP S | 4120 | 12,825 | 86 | 91 | \$ 710.00 |
| GNV | AP S | 4125 | 22,290 | 80 | 85 | \$ 1,230.00 |
| GNV | AP S | 4130 | 8,760 | 88 | 92 | \$ 580.00 |
| GNV | AP S | 4135 | 70,723 | 100 | 100 | \$ - |
| GNV | AP SW | 4305 | 32,431 | 65 | 91 | \$ 21,070.00 |
| GNV | AP SW | 4310 | 12,201 | 29 | 50 | \$ 68,230.00 |
| GNV | AP SW | 4315 | 23,585 | 55 | 71 | \$ 17,230.00 |
| GNV | AP SW | 4320 | 21,340 | 73 | 73 | \$ - |
| GNV | AP SW | 4325 | 72,728 | 64 | 69 | \$ 40,010.00 |
| GNV | AP SW | 4330 | 61,003 | 76 | 100 | \$ 33,560.00 |
| GNV | RW 11-29 | 6201 | 12,282 | 88 | 88 | \$ - |
| GNV | RW 11-29 | 6202 | 34,697 | 52 | 62 | \$ 40,550.00 |
| | | | | | | |





| Network ID | Branch ID | Section ID | Area (SF) | Start Condition | End Condition | Cost |
|------------|-----------|------------|-----------|-----------------|---------------|------------------|
| GNV | RW 11-29 | 6205 | 630,300 | 72 | 78 | \$ 85,380.00 |
| GNV | RW 11-29 | 6207 | 17,349 | 70 | 85 | \$ 2,770.00 |
| GNV | RW 11-29 | 6210 | 315,150 | 76 | 80 | \$ 10,790.00 |
| GNV | RW 11-29 | 6225 | 100,100 | 66 | 76 | \$ 38,370.00 |
| GNV | RW 11-29 | 6230 | 50,050 | 76 | 79 | \$ 2,790.00 |
| GNV | RW 7-25 | 6105 | 415,800 | 89 | 89 | \$ - |
| GNV | TL T-HANG | 3105 | 52,426 | 63 | 68 | \$ 13,570.00 |
| GNV | TW A | 104 | 13,820 | 89 | 89 | \$ - |
| GNV | TW A | 105 | 80,019 | 30 | 50 | \$ 418,710.00 |
| GNV | TW A | 108 | 6,264 | 72 | 83 | \$ 3,450.00 |
| GNV | TW A | 110 | 50,240 | 89 | 90 | \$ 280.00 |
| GNV | TW A | 115 | 22,645 | 60 | 78 | \$ 12,740.00 |
| GNV | TW A | 117 | 9,679 | 69 | 82 | \$ 5,330.00 |
| GNV | TW A | 119 | 4,962 | 59 | 72 | \$ 2,690.00 |
| GNV | TW A | 120 | 98,695 | 91 | 91 | \$ - |
| GNV | TW A | 130 | 11,380 | 64 | 70 | \$ 5,010.00 |
| GNV | TW A | 135 | 20,258 | 60 | 70 | \$ 16,170.00 |
| GNV | TW A | 140 | 32,303 | 37 | 62 | \$ 125,150.00 |
| GNV | TW A | 143 | 5,547 | 46 | 64 | \$ 16,670.00 |
| GNV | TW A | 147 | 3,947 | 58 | 63 | \$ 110.00 |
| GNV | TW A | 149 | 4,225 | 68 | 73 | \$ 120.00 |
| GNV | TW A | 152 | 3,939 | 85 | 90 | \$ 220.00 |
| GNV | TW A | 153 | 4,523 | 82 | 87 | \$ 130.00 |
| GNV | TW A | 154 | 4,561 | 53 | 62 | \$ 2,820.00 |
| GNV | TW B | 203 | 8,026 | 90 | 90 | \$ - |
| GNV | TW B | 205 | 129,976 | 89 | 89 | \$ - |
| GNV | TW B | 206 | 7,137 | 87 | 87 | \$ - |
| GNV | TW B | 208 | 18,964 | 81 | 85 | \$ 730.00 |
| GNV | TW B | 210 | 11,878 | 53 | 61 | \$ 320.00 |
| GNV | TW C | 304 | 17,460 | 89 | 89 | \$ - |
| GNV | TW C | 305 | 110,122 | 75 | 77 | \$ 810.00 |
| GNV | TW C | 307 | 44,526 | 61 | 76 | \$ 24,650.00 |
| GNV | TW C | 315 | 22,886 | 81 | 85 | \$ 260.00 |
| GNV | TW CONN E | 605 | 28,681 | 86 | 86 | \$ - |
| GNV | TW CONN E | 610 | 8,448 | 79 | 83 | \$ 240.00 |
| GNV | TW CONN W | 715 | 65,848 | 91 | 91 | \$ - |
| GNV | TW D | 410 | 20,831 | 80 | 82 | \$ 5,730.00 |
| GNV | TW E | 505 | 491,892 | 86 | 86 | \$ - |
| GNV | TW E | 510 | 75,075 | 89 | 89 | \$ - |





| Network ID | Branch ID | Section ID | Area (SF) | Start Condition | End Condition | Cost |
|------------|-----------|------------|-----------|-----------------|---------------|----------------|
| GNV | TW E1 | 515 | 19,914 | 65 | 67 | \$ 100.00 |
| GNV | TW E1 | 517 | 15,325 | 90 | 90 | \$ - |
| GNV | TW E2 | 520 | 19,417 | 73 | 77 | \$ 540.00 |
| GNV | TW E2 | 522 | 15,698 | 91 | 91 | \$ - |
| GNV | TW E3 | 530 | 28,702 | 69 | 73 | \$ 800.00 |
| GNV | TW E3 | 532 | 20,853 | 89 | 89 | \$ - |
| GNV | TW E4 | 540 | 29,074 | 66 | 71 | \$ 4,820.00 |
| GNV | TW E4 | 542 | 17,460 | 90 | 90 | \$ - |
| GNV | TW E5 | 550 | 19,373 | 77 | 82 | \$ 1,070.00 |
| GNV | TW E5 | 552 | 9,790 | 91 | 91 | \$ - |

The following Table 5.3 (c) provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (c) Summary of Localized Maintenance

| Work Category | Cost |
|--------------------------------------|--------------------|
| Preventive | \$ 363,320.00 |
| Stopgap | \$ 927,130.00 |
| Planning-Level Localized M&R Needs = | \$ 1,290,450.00 |



Chapter 6






Chapter 6 – Major Rehabilitation **Planning**

6.1 Major Rehabilitation


Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. Figures 6.1 (a) and 6.1 (b) depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI





Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI







6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The Critical PCI concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

- 1. Develop a pavement performance model and refine a prediction model for the pavements considered.
- 2. Select a localized maintenance and repair policy to be used in developing a work
- Apply the selected localized policy to the pavement sections for a range of PCI.
- 4. Compute the unit cost per area for each PCI range.
- 5. Plot the cost versus the PCI.
- 6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended *Minimum Service-Level PCI* for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. Table 6.1.2 summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

| Branch Use | FDOT Recommended PCI | Additional Consideration |
|--------------------------|----------------------|--|
| Runway | 75 | Aircraft Fleet Mix Changes Primary Runway |
| Taxiway / Taxilane | 70 | Aircraft Fleet Mix Changes Expected Operations |
| Aprons / Run-Ups / Ramps | 65 | Ground Service Equipment Non-Aircraft Operations (e.g. fueling) |





6.2 Major Rehabilitation Policy

6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA AC 150/5320-6F "Airport Pavement Design and Evaluation." It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following Tables 6.2.1 (a) and (b) provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average PR Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation - Flexible Asphalt Concrete

| Rehabilitation Type | Commercial (PR) Airport |
|---|--|
| AC Restoration Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction. PCI = 41 to 65 | 75% Mill and Overlay P-101 AC Milling (4") P-603 Bituminous Tack P-401 (HMA) (4") 25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") |
| | P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (6") Excludes any paved shoulder features. |
| AC Reconstruction Full-depth asphalt pavement section | P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime |
| reconstruction. PCI = 40 or less | P-603 Bituminous Tack P-401 HMA (6") Excludes any paved shoulder features. |



Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation - Rigid Portland Cement Concrete

| Rehabilitation Type | Commercial (PR) Airport |
|--|---|
| PCC Restoration Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels. PCI = 41 to 65 | P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (16") *Select Slabs (25%) **Crack Seal and Limited Patching |
| PCC Reconstruction Full-depth rigid pavement section reconstruction. PCI = 40 or less | P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (6") P-501 Rigid PCC (17") |

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

The recommendations identified in the Major Rehabilitation Needs consider the FAA AC 150/5370-10H Standard Specifications for Construction of Airports when determining the appropriate materials and methods implemented for construction projects, such as pavement rehabilitation, on airports. It should be noted that the AC 150/5370-10H Standard Specifications for Construction of Airports was updated in December of 2018. Design-level determination of project specific specifications based on the AC should be developed by the Airport when performing applicable construction projects.





6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type

| Rehabilitation Type | PCI Range | Flexible Asphalt Concrete Cost Per SF | | tland Cement Cost per SF |
|---------------------|-----------|--|----|-----------------------------|
| Restoration | 41 to 65 | \$ 11.00 | \$ | 17.00 |
| Reconstruction | 0 to 40 | \$ 14.00 | \$ | 23.00 |

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a payement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level





investigation, and budgetary constraints. The following Table 6.3.1 summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.

Table 6.3.1 10-Year Major Rehabilitation Needs

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost |
|-----------------|---------------|-----------|---------------|---------|--------------|---------------|------------------------|-----------------|
| 2020 | GNV | AP N | 4203 | AAC | 23,039 | 63 | AC Restoration | \$ 254,000.00 |
| 2020 | GNV | AP N | 4210 | APC | 49,872 | 61 | AC Restoration | \$ 549,000.00 |
| 2020 | GNV | AP N | 4220 | APC | 53,200 | 43 | AC Restoration | \$ 695,000.00 |
| 2020 | GNV | AP N | 4222 | AAC | 13,199 | 64 | AC Restoration | \$ 146,000.00 |
| 2020 | GNV | AP N | 4228 | AAC | 14,420 | 56 | AC Restoration | \$ 159,000.00 |
| 2020 | GNV | AP RU 7 | 5205 | AC | 7,974 | 48 | AC Restoration | \$ 91,000.00 |
| 2020 | GNV | AP SW | 4305 | AAC | 32,431 | 63 | AC Restoration | \$ 357,000.00 |
| 2020 | GNV | AP SW | 4310 | AC | 12,201 | 27 | AC Reconstruction | \$ 171,000.00 |
| 2020 | GNV | AP SW | 4315 | AC | 23,585 | 53 | AC Restoration | \$ 260,000.00 |
| 2020 | GNV | AP SW | 4325 | AC | 72,728 | 62 | AC Restoration | \$ 800,000.00 |
| 2020 | GNV | RW 11-29 | 6202 | AAC | 34,697 | 51 | AC Restoration | \$ 382,000.00 |
| 2020 | GNV | RW 11-29 | 6225 | AAC | 100,100 | 63 | AC Restoration | \$ 1,102,000.00 |
| 2020 | GNV | TL T-HANG | 3105 | AAC | 52,426 | 62 | AC Restoration | \$ 577,000.00 |
| 2020 | GNV | TW A | 105 | AAC | 80,019 | 27 | AC Reconstruction | \$ 1,121,000.00 |
| 2020 | GNV | TW A | 115 | AAC | 22,645 | 59 | AC Restoration | \$ 250,000.00 |
| 2020 | GNV | TW A | 119 | AAC | 4,962 | 58 | AC Restoration | \$ 55,000.00 |
| 2020 | GNV | TW A | 130 | AC | 11,380 | 63 | AC Restoration | \$ 126,000.00 |
| 2020 | GNV | TW A | 135 | AC | 20,258 | 59 | AC Restoration | \$ 223,000.00 |
| 2020 | GNV | TW A | 140 | AC | 32,303 | 35 | AC Reconstruction | \$ 453,000.00 |
| 2020 | GNV | TW A | 143 | AC | 5,547 | 44 | AC Restoration | \$ 70,000.00 |
| 2020 | GNV | TW A | 147 | AC | 3,947 | 57 | AC Restoration | \$ 44,000.00 |
| 2020 | GNV | TW A | 154 | AAC | 4,561 | 52 | AC Restoration | \$ 51,000.00 |
| 2020 | GNV | TW B | 210 | AAC | 11,878 | 52 | AC Restoration | \$ 131,000.00 |
| 2020 | GNV | TW C | 307 | AAC | 44,526 | 60 | AC Restoration | \$ 490,000.00 |
| 2020 | GNV | TW E1 | 515 | AAC | 19,914 | 64 | AC Restoration | \$ 220,000.00 |
| 2020 | GNV | TW E4 | 540 | AAC | 29,074 | 64 | AC Restoration | \$ 320,000.00 |
| 2022 | GNV | AP N | 4240 | AAC | 130,329 | 64 | AC Restoration | \$ 1,434,000.00 |
| 2022 | GNV | AP N | 4245 | AAC | 15,617 | 64 | AC Restoration | \$ 172,000.00 |
| 2022 | GNV | RW 11-29 | 6205 | AAC | 630,300 | 64 | AC Restoration | \$ 6,934,000.00 |
| 2022 | GNV | RW 11-29 | 6207 | AAC | 17,349 | 62 | AC Restoration | \$ 191,000.00 |
| 2022 | GNV | TW A | 117 | AAC | 9,679 | 64 | AC Restoration | \$ 107,000.00 |
| 2022 | GNV | TW A | 149 | AAC | 4,225 | 64 | AC Restoration | \$ 47,000.00 |
| 2022 | GNV | TW E3 | 530 | AAC | 28,702 | 64 | AC Restoration | \$ 316,000.00 |





| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost |
|-----------------|---------------|-----------|---------------|---------|--------------|---------------|------------------------|-----------------|
| 2023 | GNV | AP N | 4205 | AAC | 189,798 | 64 | AC Restoration | \$ 2,088,000.00 |
| 2023 | GNV | AP N | 4255 | AAC | 125,665 | 64 | AC Restoration | \$ 1,383,000.00 |
| 2024 | GNV | AP N | 4226 | AAC | 97,393 | 63 | AC Restoration | \$ 1,072,000.00 |
| 2024 | GNV | AP N | 4260 | AAC | 104,561 | 64 | AC Restoration | \$ 1,151,000.00 |
| 2024 | GNV | AP S | 4105 | AAC | 66,500 | 64 | AC Restoration | \$ 732,000.00 |
| 2024 | GNV | AP SW | 4320 | AAC | 21,340 | 63 | AC Restoration | \$ 235,000.00 |
| 2024 | GNV | RW 11-29 | 6210 | AAC | 315,150 | 64 | AC Restoration | \$ 3,467,000.00 |
| 2024 | GNV | RW 11-29 | 6230 | AAC | 50,050 | 64 | AC Restoration | \$ 551,000.00 |
| 2024 | GNV | TW A | 108 | AAC | 6,264 | 64 | AC Restoration | \$ 69,000.00 |
| 2025 | GNV | AP N | 4230 | AAC | 36,283 | 64 | AC Restoration | \$ 400,000.00 |
| 2025 | GNV | AP N | 4241 | AAC | 21,600 | 63 | AC Restoration | \$ 238,000.00 |
| 2025 | GNV | AP N | 4250 | AAC | 145,100 | 64 | AC Restoration | \$ 1,597,000.00 |
| 2025 | GNV | TW E2 | 520 | AAC | 19,417 | 63 | AC Restoration | \$ 214,000.00 |
| 2026 | GNV | AP S | 4125 | AAC | 22,290 | 64 | AC Restoration | \$ 246,000.00 |
| 2027 | GNV | AP N | 4215 | APC | 76,639 | 64 | AC Restoration | \$ 844,000.00 |
| 2027 | GNV | AP SW | 4330 | AC | 61,003 | 63 | AC Restoration | \$ 672,000.00 |
| 2027 | GNV | TW E5 | 550 | AAC | 19,373 | 63 | AC Restoration | \$ 214,000.00 |
| 2028 | GNV | AP S | 4120 | AAC | 12,825 | 64 | AC Restoration | \$ 142,000.00 |
| 2028 | GNV | TW CONN E | 610 | AAC | 8,448 | 63 | AC Restoration | \$ 93,000.00 |
| 2028 | GNV | TW D | 410 | AAC | 20,831 | 64 | AC Restoration | \$ 230,000.00 |
| 2029 | GNV | AP N | 4270 | AC | 32,960 | 63 | AC Restoration | \$ 363,000.00 |
| 2029 | GNV | AP RU 25 | 5105 | AAC | 9,793 | 63 | AC Restoration | \$ 108,000.00 |
| 2029 | GNV | AP S | 4130 | AAC | 8,760 | 64 | AC Restoration | \$ 97,000.00 |
| 2029 | GNV | TW A | 153 | AAC | 4,523 | 64 | AC Restoration | \$ 50,000.00 |
| 2029 | GNV | TW B | 208 | AAC | 18,964 | 63 | AC Restoration | \$ 209,000.00 |
| 2029 | GNV | TW C | 315 | AAC | 22,886 | 63 | AC Restoration | \$ 252,000.00 |

*All values have been rounded to the nearest thousand-dollar.

The following Figure 6.3.1 (a) summarizes the section-level major rehabilitation needs for a 10year period between 2020 and 2029. Figure 6.3.1 (b) provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in Appendix C Technical Exhibits. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.






Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year



Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit





Chapter 7





Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and reinspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2020-2029. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- Develop a detailed preventive maintenance program for the airport.
- Further refine and implement the identified 10-year major rehabilitation needs.
- Maintain detailed records on pavement maintenance, construction, and inspection.
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).





7.2 Supporting Documents

001 - Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in Appendix A **Pavement Analysis Tables.**

002 - Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in is located in Appendix C Technical Exhibits. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

003 - Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in Appendix C Technical Exhibits. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in Appendix E Inspection Distress Details) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

004 - Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation.

Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in Appendix D Inspection Photograph Documentation. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report

2019

Gainesville Regional Airport (GNV)





7.3 Conclusion

The FDOT SAPMP Update Phase 2 2018-2019 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars 150/5380-7B "Airport Pavement Management Program (PMP)" and 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."



Appendix A

Airfield Pavement Analysis Tables








Table A-1 Pavement System Inventory Details

| Network ID | Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | Area (SF) | Surface Type | Est. Last Construction Date |
|------------|-----------------------|-----------|---------------|---------------|----------------|---------------|--------------|-----------------|-----------------------------------|
| GNV | NORTH APRONS | AP N | APRON | 4203 | 350 | 50 | 23,039 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4205 | 500 | 350 | 189,798 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4210 | 335 | 130 | 49,872 | APC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4215 | 300 | 200 | 76,639 | APC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4220 | 249 | 200 | 53,200 | APC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4222 | 175 | 100 | 13,199 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4226 | 120 | 100 | 97,393 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4228 | 120 | 100 | 14,420 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4230 | 402 | 100 | 36,283 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4240 | 650 | 200 | 130,329 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4241 | 400 | 60 | 21,600 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4245 | 150 | 100 | 15,617 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4250 | 702 | 200 | 145,100 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4255 | 545 | 200 | 125,665 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4260 | 400 | 250 | 104,561 | AAC | 7/1/2010 |
| GNV | NORTH APRONS | AP N | APRON | 4270 | 1,500 | 35 | 32,960 | AC | 7/1/2010 |
| GNV | RUN UP APRON AT RW 25 | AP RU 25 | APRON | 5105 | 175 | 50 | 9,793 | AAC | 7/1/2009 |
| GNV | RUN UP APRON AT RW 7 | AP RU 7 | APRON | 5205 | 175 | 50 | 7,974 | AC | 1/1/1980 |
| GNV | SOUTH APRONS | AP S | APRON | 4105 | 630 | 100 | 66,500 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4110 | 700 | 180 | 126,000 | PCC | 1/1/1978 |
| GNV | SOUTH APRONS | AP S | APRON | 4115 | 700 | 50 | 35,000 | PCC | 1/1/1978 |
| GNV | SOUTH APRONS | AP S | APRON | 4120 | 135 | 90 | 12,825 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4125 | 230 | 95 | 22,290 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4130 | 220 | 40 | 8,760 | AAC | 7/1/2009 |
| GNV | SOUTH APRONS | AP S | APRON | 4135 | 305 | 230 | 70,723 | PCC | 1/1/2016 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4305 | 250 | 125 | 32,431 | AAC | 1/1/2005 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4310 | 100 | 70 | 12,201 | AC | 12/25/1999 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4315 | 210 | 70 | 23,585 | AC | 12/25/1999 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4320 | 100 | 100 | 21,340 | AAC | 7/1/2010 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4325 | 1,250 | 50 | 72,728 | AC | 7/1/2010 |
| GNV | SOUTHWEST APRON | AP SW | APRON | 4330 | 300 | 150 | 61,003 | AC | 1/1/2009 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6201 | 228 | 50 | 12,282 | AAC | 1/1/2015 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6202 | 404 | 100 | 34,697 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6205 | 4,470 | 100 | 630,300 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6207 | 600 | 25 | 17,349 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6210 | 8,200 | 25 | 315,150 | AAC | 2/1/2005 |





| Network ID | Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | Area (SF) | Surface Type | Est. Last Construction Date |
|------------|--|-----------|---------------|---------------|----------------|---------------|--------------|-----------------|-----------------------------------|
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6225 | 1,000 | 100 | 100,100 | AAC | 2/1/2005 |
| GNV | RUNWAY 11-29 | RW 11-29 | RUNWAY | 6230 | 2,000 | 25 | 50,050 | AAC | 2/1/2005 |
| GNV | RUNWAY 7-25 | RW 7-25 | RUNWAY | 6105 | 4,000 | 80 | 415,800 | AAC | 9/1/2015 |
| GNV | TL T-HANGAR | TL T-HANG | TAXILANE | 3105 | 1,800 | 20 | 52,426 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 104 | 480 | 56 | 13,820 | AAC | 1/1/2015 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 105 | 1,486 | 50 | 80,019 | AAC | 1/1/1973 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 108 | 100 | 50 | 6,264 | AAC | 1/1/2005 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 110 | 430 | 50 | 50,240 | AAC | 1/1/2012 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 115 | 370 | 50 | 22,645 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 117 | 202 | 50 | 9,679 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 119 | 202 | 50 | 4,962 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 120 | 1,880 | 50 | 98,695 | AAC | 1/1/2012 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 130 | 380 | 40 | 11,380 | AC | 1/1/1979 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 135 | 500 | 40 | 20,258 | AC | 1/1/1980 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 140 | 925 | 35 | 32,303 | AC | 1/1/1992 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 143 | 100 | 35 | 5,547 | AC | 1/1/1992 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 147 | 99 | 40 | 3,947 | AC | 1/1/1980 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 149 | 109 | 40 | 4,225 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 152 | 65 | 50 | 3,939 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 153 | 65 | 50 | 4,523 | AAC | 7/1/2009 |
| GNV | TAXIWAY A | TW A | TAXIWAY | 154 | 65 | 50 | 4,561 | AAC | 7/1/2009 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 203 | 300 | 50 | 8,026 | AAC | 1/1/2015 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 205 | 2,571 | 50 | 129,976 | AAC | 7/1/2009 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 206 | 320 | 35 | 7,137 | AAC | 1/1/2015 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 208 | 450 | 45 | 18,964 | AAC | 7/1/2009 |
| GNV | TAXIWAY B | TW B | TAXIWAY | 210 | 50 | 50 | 11,878 | AAC | 1/1/2005 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 304 | 400 | 50 | 17,460 | AAC | 1/1/2015 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 305 | 2,000 | 50 | 110,122 | AC | 3/1/2011 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 307 | 275 | 70 | 44,526 | AAC | 7/1/2010 |
| GNV | TAXIWAY C | TW C | TAXIWAY | 315 | 275 | 70 | 22,886 | AAC | 7/1/2010 |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TW CONN E | TAXIWAY | 605 | 200 | 100 | 28,681 | AC | 1/1/2014 |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TW CONN E | TAXIWAY | 610 | 200 | 100 | 8,448 | AAC | 7/1/2009 |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TW CONN W | TAXIWAY | 715 | 300 | 205 | 65,848 | AC | 1/1/2014 |
| GNV | TAXIWAY D | TW D | TAXIWAY | 410 | 358 | 50 | 20,831 | AAC | 7/1/2009 |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TW E | TAXIWAY | 505 | 6,475 | 75 | 491,892 | AC | 1/1/2014 |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TW E | TAXIWAY | 510 | 1,000 | 75 | 75,075 | AC | 1/1/2014 |
| GNV | TAXIWAY E1 | TW E1 | TAXIWAY | 515 | 200 | 105 | 19,914 | AAC | 1/1/2005 |

Statewide Airfield Pavement Management ProgramAirport Pavement Evaluation Report

2019

Gainesville Regional Airport (GNV)





| Network ID | Branch Name | Branch ID | Branch Use | Section ID | Length (FT) | Width (FT) | Area (SF) | Surface Type | Est. Last Construction Date |
|------------|-------------|-----------|---------------|---------------|----------------|---------------|--------------|-----------------|-----------------------------------|
| GNV | TAXIWAY E1 | TW E1 | TAXIWAY | 517 | 100 | 87 | 15,325 | AC | 1/1/2014 |
| GNV | TAXIWAY E2 | TW E2 | TAXIWAY | 520 | 195 | 125 | 19,417 | AAC | 1/1/2005 |
| GNV | TAXIWAY E2 | TW E2 | TAXIWAY | 522 | 110 | 87 | 15,698 | AC | 1/1/2014 |
| GNV | TAXIWAY E3 | TW E3 | TAXIWAY | 530 | 150 | 175 | 28,702 | AAC | 1/1/2005 |
| GNV | TAXIWAY E3 | TW E3 | TAXIWAY | 532 | 100 | 137 | 20,853 | AC | 1/1/2014 |
| GNV | TAXIWAY E4 | TW E4 | TAXIWAY | 540 | 200 | 155 | 29,074 | AAC | 1/1/2005 |
| GNV | TAXIWAY E4 | TW E4 | TAXIWAY | 542 | 87 | 113 | 17,460 | AC | 1/1/2014 |
| GNV | TAXIWAY E5 | TW E5 | TAXIWAY | 550 | 150 | 75 | 19,373 | AAC | 1/1/2005 |
| GNV | TAXIWAY E5 | TW E5 | TAXIWAY | 552 | 140 | 70 | 9,790 | AC | 1/1/2014 |





Table A-2 Pavement Condition Index Summary (Last Inspection) - Section Level

| Network ID | Branch Name | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|---------------|-------------------------------------|------------|---------------|-----------|-----|---------------------|
| GNV | RUNWAY 7-25 | RUNWAY | 6105 | 415,800 | 89 | Good |
| GNV | RUNWAY 11-29 | RUNWAY | 6201 | 12,282 | 88 | Good |
| GNV | RUNWAY 11-29 | RUNWAY | 6202 | 34,697 | 52 | Poor |
| GNV | RUNWAY 11-29 | RUNWAY | 6205 | 630,300 | 72 | Satisfactory |
| GNV | RUNWAY 11-29 | RUNWAY | 6207 | 17,349 | 70 | Fair |
| GNV | RUNWAY 11-29 | RUNWAY | 6210 | 315,150 | 76 | Satisfactory |
| GNV | RUNWAY 11-29 | RUNWAY | 6225 | 100,100 | 66 | Fair |
| GNV | RUNWAY 11-29 | RUNWAY | 6230 | 50,050 | 76 | Satisfactory |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 605 | 28,681 | 86 | Good |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 610 | 8,448 | 79 | Satisfactory |
| GNV | CONNECTOR TAXIWAY FROM TW E TO S AP | TAXIWAY | 715 | 65,848 | 91 | Good |
| GNV | TAXIWAY A | TAXIWAY | 104 | 13,820 | 89 | Good |
| GNV | TAXIWAY A | TAXIWAY | 105 | 80,019 | 30 | Very Poor |
| GNV | TAXIWAY A | TAXIWAY | 108 | 6,264 | 72 | Satisfactory |
| GNV | TAXIWAY A | TAXIWAY | 110 | 50,240 | 89 | Good |
| GNV | TAXIWAY A | TAXIWAY | 115 | 22,645 | 60 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 117 | 9,679 | 69 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 119 | 4,962 | 59 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 120 | 98,695 | 91 | Good |
| GNV | TAXIWAY A | TAXIWAY | 130 | 11,380 | 64 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 135 | 20,258 | 60 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 140 | 32,303 | 37 | Very Poor |
| GNV | TAXIWAY A | TAXIWAY | 143 | 5,547 | 46 | Poor |
| GNV | TAXIWAY A | TAXIWAY | 147 | 3,947 | 58 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 149 | 4,225 | 68 | Fair |
| GNV | TAXIWAY A | TAXIWAY | 152 | 3,939 | 85 | Satisfactory |
| GNV | TAXIWAY A | TAXIWAY | 153 | 4,523 | 82 | Satisfactory |
| GNV | TAXIWAY A | TAXIWAY | 154 | 4,561 | 53 | Poor |
| GNV | TAXIWAY B | TAXIWAY | 203 | 8,026 | 90 | Good |
| GNV | TAXIWAY B | TAXIWAY | 205 | 129,976 | 89 | Good |
| GNV | TAXIWAY B | TAXIWAY | 206 | 7,137 | 87 | Good |
| GNV | TAXIWAY B | TAXIWAY | 208 | 18,964 | 81 | Satisfactory |
| GNV | TAXIWAY B | TAXIWAY | 210 | 11,878 | 53 | Poor |
| GNV | TAXIWAY C | TAXIWAY | 304 | 17,460 | 89 | Good |
| GNV | TAXIWAY C | TAXIWAY | 305 | 110,122 | 75 | Satisfactory |
| GNV | TAXIWAY C | TAXIWAY | 307 | 44,526 | 61 | Fair |
| GNV | TAXIWAY C | TAXIWAY | 315 | 22,886 | 81 | Satisfactory |

Statewide Airfield Pavement Management ProgramAirport Pavement Evaluation Report

2019

Gainesville Regional Airport (GNV)





| Notwork | | | Section | | | 0 |
|---------------|-------------------------------|------------|---------|-----------|-----|---------------------|
| Network ID | Branch Name | Branch Use | ID | Area (SF) | PCI | Condition Rating |
| GNV | TAXIWAY D | TAXIWAY | 410 | 20,831 | 80 | Satisfactory |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TAXIWAY | 505 | 491,892 | 86 | Good |
| GNV | TAXIWAY E - PARALLEL RW 11-29 | TAXIWAY | 510 | 75,075 | 89 | Good |
| GNV | TAXIWAY E1 | TAXIWAY | 515 | 19,914 | 65 | Fair |
| GNV | TAXIWAY E1 | TAXIWAY | 517 | 15,325 | 90 | Good |
| GNV | TAXIWAY E2 | TAXIWAY | 520 | 19,417 | 73 | Satisfactory |
| GNV | TAXIWAY E2 | TAXIWAY | 522 | 15,698 | 91 | Good |
| GNV | TAXIWAY E3 | TAXIWAY | 530 | 28,702 | 69 | Fair |
| GNV | TAXIWAY E3 | TAXIWAY | 532 | 20,853 | 89 | Good |
| GNV | TAXIWAY E4 | TAXIWAY | 540 | 29,074 | 66 | Fair |
| GNV | TAXIWAY E4 | TAXIWAY | 542 | 17,460 | 90 | Good |
| GNV | TAXIWAY E5 | TAXIWAY | 550 | 19,373 | 77 | Satisfactory |
| GNV | TAXIWAY E5 | TAXIWAY | 552 | 9,790 | 91 | Good |
| GNV | TL T-HANGAR | TAXILANE | 3105 | 52,426 | 63 | Fair |
| GNV | SOUTH APRONS | APRON | 4105 | 66,500 | 75 | Satisfactory |
| GNV | SOUTH APRONS | APRON | 4110 | 126,000 | 88 | Good |
| GNV | SOUTH APRONS | APRON | 4115 | 35,000 | 84 | Satisfactory |
| GNV | SOUTH APRONS | APRON | 4120 | 12,825 | 86 | Good |
| GNV | SOUTH APRONS | APRON | 4125 | 22,290 | 80 | Satisfactory |
| GNV | SOUTH APRONS | APRON | 4130 | 8,760 | 88 | Good |
| GNV | SOUTH APRONS | APRON | 4135 | 70,723 | 100 | Good |
| GNV | NORTH APRONS | APRON | 4203 | 23,039 | 64 | Fair |
| GNV | NORTH APRONS | APRON | 4205 | 189,798 | 72 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4210 | 49,872 | 62 | Fair |
| GNV | NORTH APRONS | APRON | 4215 | 76,639 | 82 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4220 | 53,200 | 46 | Poor |
| GNV | NORTH APRONS | APRON | 4222 | 13,199 | 66 | Fair |
| GNV | NORTH APRONS | APRON | 4226 | 97,393 | 73 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4228 | 14,420 | 58 | Fair |
| GNV | NORTH APRONS | APRON | 4230 | 36,283 | 77 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4240 | 130,329 | 70 | Fair |
| GNV | NORTH APRONS | APRON | 4241 | 21,600 | 76 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4245 | 15,617 | 70 | Fair |
| GNV | NORTH APRONS | APRON | 4250 | 145,100 | 77 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4255 | 125,665 | 72 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4260 | 104,561 | 74 | Satisfactory |
| GNV | NORTH APRONS | APRON | 4270 | 32,960 | 79 | Satisfactory |
| GNV | SOUTHWEST APRON | APRON | 4305 | 32,431 | 65 | Fair |
| GNV | SOUTHWEST APRON | APRON | 4310 | 12,201 | 29 | Very Poor |

Statewide Airfield Pavement Management ProgramAirport Pavement Evaluation Report

2019





| Network ID | Branch Name | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|---------------|-----------------------|------------|---------------|-----------|-----|---------------------|
| GNV | SOUTHWEST APRON | APRON | 4315 | 23,585 | 55 | Poor |
| GNV | SOUTHWEST APRON | APRON | 4320 | 21,340 | 73 | Satisfactory |
| GNV | SOUTHWEST APRON | APRON | 4325 | 72,728 | 64 | Fair |
| GNV | SOUTHWEST APRON | APRON | 4330 | 61,003 | 76 | Satisfactory |
| GNV | RUN UP APRON AT RW 25 | APRON | 5105 | 9,793 | 87 | Good |
| GNV | RUN UP APRON AT RW 7 | APRON | 5205 | 7,974 | 50 | Poor |





Table A-3 Forecasted PCI 2020-2029

| Network | | Section | Last | | | | | Forecas | sted PCI | | | | |
|---------|-----------|---------|------|------|------|------|------|---------|----------|------|------|------|------|
| ID | Branch ID | ID | PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | AP N | 4203 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4205 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 |
| GNV | AP N | 4210 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 | 59 | 59 | 58 |
| GNV | AP N | 4215 | 82 | 79 | 77 | 74 | 71 | 69 | 67 | 65 | 64 | 62 | 61 |
| GNV | AP N | 4220 | 46 | 43 | 39 | 34 | 31 | 28 | 26 | 24 | 22 | 19 | 17 |
| GNV | AP N | 4222 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4226 | 73 | 71 | 68 | 66 | 65 | 63 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP N | 4228 | 58 | 56 | 54 | 52 | 49 | 45 | 41 | 37 | 33 | 29 | 27 |
| GNV | AP N | 4230 | 77 | 75 | 72 | 70 | 67 | 66 | 64 | 63 | 62 | 61 | 60 |
| GNV | AP N | 4240 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4241 | 76 | 74 | 71 | 69 | 67 | 65 | 63 | 62 | 61 | 61 | 60 |
| GNV | AP N | 4245 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 | 60 |
| GNV | AP N | 4250 | 77 | 75 | 72 | 70 | 67 | 66 | 64 | 63 | 62 | 61 | 60 |
| GNV | AP N | 4255 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 | 60 |
| GNV | AP N | 4260 | 74 | 72 | 69 | 67 | 65 | 64 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP N | 4270 | 79 | 77 | 76 | 74 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | AP RU 25 | 5105 | 87 | 84 | 82 | 79 | 76 | 73 | 71 | 69 | 67 | 65 | 63 |
| GNV | AP RU 7 | 5205 | 50 | 48 | 47 | 45 | 44 | 42 | 40 | 39 | 37 | 36 | 34 |
| GNV | AP S | 4105 | 75 | 73 | 70 | 68 | 66 | 64 | 63 | 62 | 61 | 60 | 60 |
| GNV | AP S | 4110 | 88 | 87 | 86 | 85 | 85 | 84 | 83 | 82 | 82 | 81 | 80 |
| GNV | AP S | 4115 | 84 | 83 | 82 | 81 | 81 | 80 | 79 | 78 | 77 | 76 | 75 |
| GNV | AP S | 4120 | 86 | 83 | 81 | 78 | 75 | 72 | 70 | 68 | 66 | 64 | 63 |
| GNV | AP S | 4125 | 80 | 77 | 75 | 72 | 70 | 68 | 66 | 64 | 63 | 62 | 61 |
| GNV | AP S | 4130 | 88 | 85 | 83 | 80 | 77 | 74 | 72 | 69 | 67 | 65 | 64 |
| GNV | AP S | 4135 | 100 | 98 | 96 | 94 | 92 | 91 | 90 | 89 | 88 | 87 | 86 |
| GNV | AP SW | 4305 | 65 | 63 | 62 | 61 | 61 | 60 | 60 | 60 | 60 | 60 | 60 |
| GNV | AP SW | 4310 | 29 | 27 | 26 | 24 | 23 | 21 | 19 | 18 | 16 | 15 | 13 |
| GNV | AP SW | 4315 | 55 | 53 | 52 | 50 | 49 | 47 | 45 | 44 | 42 | 41 | 39 |
| GNV | AP SW | 4320 | 73 | 71 | 68 | 66 | 65 | 63 | 62 | 61 | 61 | 60 | 60 |
| GNV | AP SW | 4325 | 64 | 62 | 61 | 59 | 58 | 56 | 54 | 53 | 51 | 50 | 48 |
| GNV | AP SW | 4330 | 76 | 74 | 73 | 71 | 70 | 68 | 66 | 65 | 63 | 62 | 60 |
| GNV | RW 11-29 | 6201 | 88 | 85 | 83 | 81 | 80 | 78 | 77 | 76 | 74 | 72 | 69 |
| GNV | RW 11-29 | 6202 | 52 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 46 | 46 |
| GNV | RW 11-29 | 6205 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 | 54 | 54 |
| GNV | RW 11-29 | 6207 | 70 | 68 | 65 | 62 | 59 | 57 | 56 | 55 | 54 | 54 | 54 |
| GNV | RW 11-29 | 6210 | 76 | 74 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 |
| GNV | RW 11-29 | 6225 | 66 | 63 | 61 | 58 | 56 | 55 | 54 | 54 | 54 | 54 | 52 |





| Network | | Section | Last | | | | | Forecas | sted PCI | | | | |
|---------|-----------|---------|------|------|------|------|------|---------|----------|------|------|------|------|
| ID | Branch ID | ID | PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | RW 11-29 | 6230 | 76 | 74 | 72 | 70 | 67 | 64 | 62 | 59 | 57 | 55 | 54 |
| GNV | RW 7-25 | 6105 | 89 | 86 | 84 | 82 | 80 | 79 | 78 | 76 | 74 | 72 | 70 |
| GNV | TL T-HANG | 3105 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 |
| GNV | TW A | 104 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW A | 105 | 30 | 27 | 24 | 20 | 16 | 11 | 6 | 0 | 0 | 0 | 0 |
| GNV | TW A | 108 | 72 | 70 | 69 | 67 | 65 | 64 | 63 | 62 | 60 | 59 | 59 |
| GNV | TW A | 110 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW A | 115 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 | 53 |
| GNV | TW A | 117 | 69 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 |
| GNV | TW A | 119 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 | 53 | 52 |
| GNV | TW A | 120 | 91 | 89 | 86 | 84 | 81 | 79 | 77 | 75 | 73 | 71 | 69 |
| GNV | TW A | 130 | 64 | 63 | 62 | 61 | 61 | 60 | 59 | 59 | 58 | 57 | 56 |
| GNV | TW A | 135 | 60 | 59 | 58 | 57 | 57 | 56 | 55 | 54 | 53 | 51 | 50 |
| GNV | TW A | 140 | 37 | 35 | 32 | 29 | 25 | 22 | 18 | 14 | 11 | 7 | 3 |
| GNV | TW A | 143 | 46 | 44 | 42 | 40 | 38 | 35 | 32 | 30 | 26 | 23 | 19 |
| GNV | TW A | 147 | 58 | 57 | 56 | 55 | 54 | 53 | 52 | 51 | 49 | 48 | 46 |
| GNV | TW A | 149 | 68 | 66 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 | 57 |
| GNV | TW A | 152 | 85 | 83 | 80 | 78 | 76 | 74 | 72 | 70 | 69 | 67 | 66 |
| GNV | TW A | 153 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 | 64 |
| GNV | TW A | 154 | 53 | 52 | 51 | 51 | 50 | 49 | 49 | 48 | 47 | 45 | 44 |
| GNV | TW B | 203 | 90 | 88 | 85 | 83 | 80 | 78 | 76 | 74 | 72 | 70 | 69 |
| GNV | TW B | 205 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW B | 206 | 87 | 85 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 |
| GNV | TW B | 208 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | TW B | 210 | 53 | 52 | 51 | 51 | 50 | 49 | 49 | 48 | 47 | 45 | 44 |
| GNV | TW C | 304 | 89 | 87 | 84 | 82 | 80 | 77 | 75 | 73 | 71 | 70 | 68 |
| GNV | TW C | 305 | 75 | 74 | 72 | 71 | 70 | 69 | 68 | 67 | 66 | 65 | 65 |
| GNV | TW C | 307 | 61 | 60 | 59 | 58 | 57 | 56 | 56 | 55 | 54 | 54 | 53 |
| GNV | TW C | 315 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 |
| GNV | TW CONN E | 605 | 86 | 84 | 83 | 81 | 79 | 78 | 76 | 75 | 74 | 73 | 71 |
| GNV | TW CONN E | 610 | 79 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 |
| GNV | TW CONN W | 715 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |
| GNV | TW D | 410 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 67 | 65 | 64 | 63 |
| GNV | TW E | 505 | 86 | 84 | 83 | 81 | 79 | 78 | 76 | 75 | 74 | 73 | 71 |
| GNV | TW E | 510 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 | 73 |
| GNV | TW E1 | 515 | 65 | 64 | 62 | 61 | 60 | 59 | 58 | 57 | 57 | 56 | 55 |
| GNV | TW E1 | 517 | 90 | 88 | 86 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 |
| GNV | TW E2 | 520 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 | 61 | 60 | 59 |

Statewide Airfield Pavement Management ProgramAirport Pavement Evaluation Report

2019





| Network | Branch ID | Section | Last | Forecasted PCI | | | | | | | | | |
|---------|-----------|---------|------|----------------|------|------|------|------|------|------|------|------|------|
| ID | Branch ID | ID | PCI | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| GNV | TW E2 | 522 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |
| GNV | TW E3 | 530 | 69 | 67 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 |
| GNV | TW E3 | 532 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 | 73 |
| GNV | TW E4 | 540 | 66 | 64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 | 56 |
| GNV | TW E4 | 542 | 90 | 88 | 86 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 |
| GNV | TW E5 | 550 | 77 | 75 | 73 | 71 | 69 | 68 | 66 | 65 | 63 | 62 | 61 |
| GNV | TW E5 | 552 | 91 | 89 | 87 | 85 | 84 | 82 | 80 | 79 | 77 | 76 | 75 |

1/1/1942

NU-IN

New Construction - Initial

Work History Report

Page 1 of 17

Pavement Database: FDOT

| Network: | GAINESV | TLLE REGI Branch: A | PΝ | NORT | H APRONS | Section: | 4203 Surface: | ·AAC |
|--|---|--|--|---|---|---|--|-----------|
| L.C.D. 7/1/2 | | se: APRON Rank: P | | | | | 0 (Ft) True Area: 23039.00 | |
| Work Date | Work Code | Work Description | | Cost | Thickness (in) | Major M&R | Comments | |
| 7/2/2010 | SU-DB | Surface Treatment - Double | e | 0.00 | 0.00 | | | |
| 7/1/2010 | MLOI | Bitum. | | 0.00 | 0.00 | | | |
| 7/1/2010 1/1/2002 | ML-OL MI-CO | Mill and Overlay Cold Milling | | 0.00 | 0.00 1.50 | | | |
| 1/1/2002 | OL-AS | Overlay - AC Structural | | 0.00 | 1.50 | <u></u> | | |
| 1/1/2002 | IMPORT | - | | 0.00 | 3.00 | | 1972 3" P-401 OL | |
| 1/1/19/2 | ED | BUILI | | 0.00 | 3.00 | V . | 1972 3 F-401 OL | |
| | I | | | | | | | |
| Network: | GAINESV | TLLE REGI Branch: A | PΝ | NORT | H APRONS | Section: | 4205 Surface: | :AAC |
| L.C.D. 7/1/2 | 010 Us | se: APRON Rank: P | L | ength: 500 | .00 (Ft) Wie | dth: 350.0 | 0 (Ft) True Area: 189798.0 | 000 (SqFt |
| Work Date | Work Code | Work Description | | Cost | Thickness (in) | Major M&R | Comments | |
| 7/2/2010 | SU-DB | Surface Treatment - Double Bitum. | е | 0.00 | 0.00 | | | |
| 7/1/2010 | ML-OL | Mill and Overlay | | 0.00 | 0.00 | | | |
| 1/1/2002 | MI-CO | Cold Milling | | 0.00 | 1.50 | | | |
| 1/1/2002 | OL-AS | Overlay - AC Structural | | 0.00 | 1.50 | ~ | | |
| 1/1/1001 | IMPORT | DILLIT | | 0.00 | 2.00 | | 1981 2" P-401 8" P-211 | |
| 1/1/1981 | IMPORT | BUILI | | 0.00 | 2.00 | ✓ | 1961 2 1-401 6 1-211 | |
| 1/1/1981 | ED | BUILI | | 0.00 | 2.00 | <u> </u> | 1701 2 1-401 0 1-211 | |
| | ED | | D.N. | | | | | A DC |
| Network: | ED GAINESV | TLLE REGI Branch: A | | NORT | H APRONS | Section: | 4210 Surface: | |
| | ED GAINESV 010 Us | | | NORT | H APRONS .00 (Ft) Wie | Section: | | |
| Network: | ED GAINESV | TLLE REGI Branch: A | | NORT | H APRONS | Section: | 4210 Surface: | |
| Network: L.C.D. 7/1/2 | ED GAINESV 010 Us Work | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double | Lo | NORT assemble 335 | H APRONS .00 (Ft) Wie | Section: dth: 130.0 Major | 4210 Surface: 0 (Ft) True Area: 49872.000 | |
| Network: L.C.D. 7/1/2 Work Date | GAINESV 010 Us Work Code SU-DB | TILLE REGI Branch: A se: APRON Rank: P Work Description | Lo | NORT ength: 335 Cost | H APRONS .00 (Ft) Wid Thickness (in) | Section: dth: 130.0 Major M&R | 4210 Surface: 0 (Ft) True Area: 49872.000 | |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 | GAINESV 010 Us Work Code SU-DB | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. | Lo | NORT ength: 335 Cost 0.00 | H APRONS .00 (Ft) Wid Thickness (in) 0.00 | Section: dth: 130.0 Major M&R | 4210 Surface: 0 (Ft) True Area: 49872.000 | |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY | Lo | NORT ength: 335 Cost 0.00 0.00 | H APRONS .00 (Ft) Wid Thickness (in) 0.00 0.00 | Section: dth: 130.0 Major M&R | 4210 Surface: 0 (Ft) True Area: 49872.000 | |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT | Lo | NORT ength: 335 Cost 0.00 0.00 0.00 | H APRONS .00 (Ft) Wid Thickness (in) 0.00 0.00 4.00 | Section: dth: 130.0 Major M&R | 4210 Surface: 0 (Ft) True Area: 49872.000 Comments | |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY | Lo | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 0.00 | H APRONS .00 (Ft) Wid Thickness (in) 0.00 4.00 6.00 | Section: dth: 130.0 Major M&R | 4210 Surface: 0 (Ft) True Area: 49872.00 Comments 194- 6" PCC | |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED IMPORT | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT | Lo | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 0.00 | H APRONS .00 (Ft) Wid Thickness (in) 0.00 4.00 6.00 | Section: dth: 130.0 Major M&R | 4210 Surface: 0 (Ft) True Area: 49872.00 Comments 194- 6" PCC | |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED IMPORT ED | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT | E e | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 0.00 0.00 | H APRONS .00 (Ft) Wid Thickness (in) 0.00 4.00 6.00 | Section: dth: 130.0 Major M&R | 4210 Surface: 0 (Ft) True Area: 49872.000 Comments 194- 6" PCC 1973 5" P-401 OL | 001 (SqFt |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED IMPORT ED GAINESV | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT OVERLAY | e P N | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 0.00 NORT | H APRONS .00 (Ft) Wickness (in) 0.00 4.00 6.00 5.00 | Section: dth: 130.0 Major M&R V V Section: | 4210 Surface: 0 (Ft) True Area: 49872.000 Comments 194- 6" PCC 1973 5" P-401 OL | :APC |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 1/1/1973 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED IMPORT ED GAINESV | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT OVERLAY TILLE REGI Branch: A | e P N | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 0.00 NORT | H APRONS .00 (Ft) Wickness (in) 0.00 4.00 6.00 5.00 | Section: dth: 130.0 Major M&R V V Section: | 4210 Surface: 0 (Ft) True Area: 49872.000 Comments 194- 6" PCC 1973 5" P-401 OL 4215 Surface: | :APC |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 1/1/1973 Network: L.C.D. 7/1/2 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED IMPORT ED GAINESV 010 Us Work | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT OVERLAY TILLE REGI Branch: A se: APRON Rank: P | Lo L | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 NORT ength: 300 | H APRONS .00 (Ft) Wio Thickness (in) 0.00 4.00 6.00 5.00 H APRONS .00 (Ft) Wio Thickness | Section: dth: 130.0 Major M&R V Section: dth: 200.0 Major | 4210 Surface: 0 (Ft) True Area: 49872.000 Comments 194- 6" PCC 1973 5" P-401 OL 4215 Surface: 0 (Ft) True Area: 76639.000 | :APC |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 1/1/1973 Network: L.C.D. 7/1/2 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED IMPORT ED GAINESV 010 Us Work Code | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT OVERLAY TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double | Lo L | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 0.00 NORT ength: 300 Cost | H APRONS .00 (Ft) Wio Thickness (in) 0.00 4.00 6.00 5.00 H APRONS .00 (Ft) Wio Thickness (in) | Section: dth: 130.0 Major M&R V Section: dth: 200.0 Major | 4210 Surface: 0 (Ft) True Area: 49872.000 Comments 194- 6" PCC 1973 5" P-401 OL 4215 Surface: 0 (Ft) True Area: 76639.000 | :APC |
| Network: L.C.D. 7/1/2 Work Date 7/2/2010 7/1/2010 1/1/2005 1/1/1973 1/1/1973 Network: L.C.D. 7/1/2 Work Date 7/2/2010 | GAINESV 010 Us Work Code SU-DB ML-OV ML-OV IMPORT ED IMPORT ED GAINESV 010 Us Work Code LC-DB | TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. MILL and OVERLAY MILL and OVERLAY BUILT OVERLAY TILLE REGI Branch: A se: APRON Rank: P Work Description Surface Treatment - Double Bitum. | Lo L | NORT ength: 335 Cost 0.00 0.00 0.00 0.00 0.00 NORT ength: 300 Cost 0.00 | H APRONS .00 (Ft) Wie Thickness (in) 0.00 4.00 6.00 5.00 H APRONS .00 (Ft) Wie Thickness (in) 0.00 | Section: dth: 130.0 Major M&R V Section: dth: 200.0 Major | 4210 Surface: 0 (Ft) True Area: 49872.000 Comments 194- 6" PCC 1973 5" P-401 OL 4215 Surface: 0 (Ft) True Area: 76639.000 | :APC |

Pavement Management System PAVER 7.0 TM

0.00

0.00

1942 6" PCC

7/1/2010

1/1/2002

1/1/2002

1/1/1981

ML-OL Mill and Overlay

Overlay - AC Structural

MI-CO Cold Milling

OL-AS

ED

IMPORT BUILT

Work History Report

Page 2 of 17

Pavement Database: FDOT

| Network: | GAINESV | TLLE REGI Branch: AP N | NORT | H APRONS | Section: | 4220 Surface: APC |
|---------------------|--------------|-----------------------------------|------------|----------------|--------------|---|
| L.C.D. 7/1/2 | 010 Us | se: APRON Rank: P L | ength: 249 | .00 (Ft) Wie | dth: 200.0 | 00 (Ft) True Area: 53200.00001 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2010 | ML-OL | Mill and Overlay | 0.00 | 0.00 | ~ | |
| 1/1/2002 | MI-CO | Cold Milling | 0.00 | 1.50 | | |
| 1/1/2002 | OL-AS | Overlay - AC Structural | 0.00 | 1.50 | | |
| 1/1/1972 | IMPORT ED | BUILT | 0.00 | 0.00 | | EST 1972 BIT ON PCC |
| | | | | | | |
| Network: | GAINESV | TILLE REGI Branch: AP N | NORT | H APRONS | Section: | 4222 Surface: AAC |
| L.C.D. 7/1/2 | 010 Us | se: APRON Rank: P L | ength: 175 | .00 (Ft) Wie | dth: 100.0 | 00 (Ft) True Area: 13199.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |

 Network:
 GAINESVILLE REGI
 Branch:
 AP N
 NORTH APRONS
 Section:
 4226
 Surface:AAC

 L.C.D. 7/1/2010
 Use:
 APRON
 Rank:
 P
 Length:
 120.00 (Ft)
 Width:
 100.00 (Ft)
 True Area:
 97393.00002 (SqFt

0.00

0.00

0.00

0.00

0.00

1.50

1.50

2.00

~

1981 2" P-401 8" P-211

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------------------|------|----------------|--------------|----------|
| 7/2/2010 | SU-DB | Surface Treatment - Double | 0.00 | 0.00 | | |
| | | Bitum. | | | | |
| 7/1/2010 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | | |
| 1/1/2002 | CR-AC | Complete Reconstruction - AC | 0.00 | 3.00 | ~ | |
| 1/1/1960 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |

 Network:
 GAINESVILLE REGI
 Branch:
 AP N
 NORTH APRONS
 Section:
 4228
 Surface:AAC

 L.C.D. 7/1/2010
 Use:
 APRON
 Rank:
 P
 Length:
 120.00 (Ft)
 Width:
 100.00 (Ft)
 True Area:
 14420.00000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------------------|------|----------------|--------------|----------|
| 7/1/2010 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | < | |
| 1/1/2002 | CR-AC | Complete Reconstruction - AC | 0.00 | 3.00 | V | |
| 1/1/1960 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |

Page 3 of 17

Pavement Database: FDOT

| Network: | | | nch: APN | | H APRONS | Section: | | Surface:AAC 36283.00001 (SqFt |
|-----------|--------------|---------------------|----------|------|----------------|--------------|--------------|----------------------------------|
| Work Date | Work Code | Work Descri | | Cost | Thickness (in) | Major M&R | | ments |
| 7/2/2010 | SU-DB | Surface Treatment - | Double | 0.00 | 0.00 | | | |
| | | Bitum. | | | | | | |
| 7/1/2010 | ML-OV | MILL and OVERLA | AY | 0.00 | 0.00 | ~ | | |
| 1/1/2005 | ML-OV | MILL and OVERLA | AY | 0.00 | 0.00 | V | | |
| 1/1/1980 | IMPORT | BUILT | | 0.00 | 0.00 | | EST 1980 BIT | |
| | ED | | | | | | | |

| Network: | GAINESV | TLLE REGI Branch: AP N | NORT | H APRONS | Section: | 4240 Surface:AAC |
|---------------------|--------------|-----------------------------------|------------|----------------|--------------|--|
| L.C.D. 7/1/2 | 010 Us | se: APRON Rank: P L | ength: 650 | .00 (Ft) Wie | dth: 200.0 | 0 (Ft) True Area: 130329.0000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2010 | ML-OL | Mill and Overlay | 0.00 | 0.00 | ~ | |
| 1/1/2002 | MI-CO | Cold Milling | 0.00 | 1.50 | | |
| 1/1/2002 | OL-AS | Overlay - AC Structural | 0.00 | 1.50 | | |
| 1/1/1980 | IMPORT ED | BUILT | 0.00 | 0.00 | | EST 1980 BIT |

| Network: | GAINESV | TLLE REGI Branch: AP N | NORT | H APRONS | Section: | 4241 Surface:AAC |
|--------------|--------------|-----------------------------------|------------|----------------|--------------|--|
| L.C.D. 7/1/2 | 010 Us | se: APRON Rank: P L | ength: 400 | .00 (Ft) Wie | dth: 60.0 | 0 (Ft) True Area: 21600.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2010 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | | |
| 1/1/2005 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | | |
| 1/1/1980 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |

| Network: | GAINESV | ILLE REGI Branch: AP N | NORT | H APRONS | Section: | 4245 Surface: AAC |
|---------------------|--------------|------------------------------|------------|----------------|--------------|--|
| L.C.D. 7/1/2 | 010 Us | se: APRON Rank: P L | ength: 150 | .00 (Ft) Wie | dth: 100.0 | 0 (Ft) True Area: 15617.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | SU-DB | Surface Treatment - Double | 0.00 | 0.00 | | |
| | | Bitum. | | | | |
| 7/1/2010 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | ~ | |
| 1/1/2002 | CR-AC | Complete Reconstruction - AC | 0.00 | 3.00 | | |
| 1/1/1960 | IMPORT | BUILT | 0.00 | 0.00 | | EST 1960 BIT |
| | ED | | <u>!</u> | | | |

Page 4 of 17

Pavement Database: FDOT

| Network: GAINESVILLE REGI Branch: AP N | | | | H APRONS | Section: | |
|--|--------------|-----------------------------------|------------|----------------|--------------|-------------------------------------|
| L.C.D. 7/1/2010 Use: APRON Rank: P Length: 702.00 (Ft) Width: 200.00 (Ft) True Area: 145100. | | | | | | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2010 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | | |
| 1/1/2002 | SS-CT | Surface Seal - Coal Tar | 0.00 | 0.00 | | |
| 1/1/1979 | IMPORT | BUILT | 0.00 | 1.50 | | 1979 1.5" P-401 6" P-211 4" P-152 |
| | ED | | ı | | | |
| | | | | | | |
| Network: | GAINESV | TILLE REGI Branch: AP N | NORT | H APRONS | Section: | 4255 Surface:AAC |
| L.C.D. 7/1/2 | 010 Us | se: APRON Rank: P L | ength: 545 | .00 (Ft) Wie | dth: 200.0 | 0 (Ft) True Area: 125665,0000 (SqFt |

| 1 (00) 01 111 | 0.11.120 | ibbb itboi biunem in it | 110111 | 1111110110 | 500000 | .zee |
|---------------------|---|----------------------------|--------|----------------|--------------|--|
| L.C.D. 7/1/2 | L.C.D. 7/1/2010 Use: APRON Rank: P Length: 545.00 (Ft) Width: 200.00 (Ft) | | | | | 0 (Ft) True Area: 125665.0000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | SU-DB | Surface Treatment - Double | 0.00 | 0.00 | | |
| | | Bitum. | | | | |
| 7/1/2010 | ML-OL | Mill and Overlay | 0.00 | 0.00 | | |
| 1/2/2002 | OL-AS | Overlay - AC Structural | 0.00 | 1.50 | V | |
| 1/1/2002 | MI-CO | Cold Milling | 0.00 | 1.50 | | |
| 1/1/1985 | IMPORT | BUILT | 0.00 | 0.00 | | EST 1985 BIT OL |
| | ED | | I | | | |

Network: GAINESVILLE REGI Branch: AP N NORTH APRONS Section: 4260 Surface: AAC **L.C.D.** 7/1/2010 Use: APRON Rank: P Length: 400.00 (Ft) Width: 250.00 (Ft) True Area: 104561.0000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|----------------------------|------|-------------------|--------------|-------------------------------|
| 7/2/2010 | SU-DB | Surface Treatment - Double | 0.00 | 0.00 | | |
| | | Bitum. | | | | |
| 7/1/2010 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | | |
| 1/1/1992 | IMPORT | BUILT | 0.00 | 2.00 | | 1992 2" P401 AC SURFACE ON 8" |
| | ED | | | | _ | P211 BASE ON 12" P152 SUBBASE |

Network: GAINESVILLE REGI Branch: AP N NORTH APRONS Section: 4270 Surface: AC **L.C.D.** 7/1/2010 Use: APRON Rank: P **Length:** 1,500.00 (Ft) Width: 35.00 (Ft) True Area: 32960.00001 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** M&R Code (in) 7/2/2010 ST-SS Surface Treatment - Slurry Seal 0.00 0.00 7/1/2010 NC-AC New Construction - AC 0.000.00 ~ 1/1/1992 NU-IN New Construction - Initial

Network: GAINESVILLE REGI Branch: AP RU 25 RUN UP APRON Section: 5105 Surface: AAC **L.C.D.** 7/1/2009 Use: APRON 175.00 (Ft) Width: 50.00 (Ft) True Area: 9793.000002 (SqFt Rank: P Length:

0.00

0.00

~

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|--|
| 7/1/2009 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | ~ | |
| 1/1/1981 | IMPORT ED | BUILT | 0.00 | 1.50 | | 1981 1.5" P-401 6" P-211 12" SUBGRADE |

PAVER 7.0 TM Pavement Management System

ED

ED

Work History Report

Page 5 of 17

Pavement Database: FDOT

| Network: | GAINESV | ILLE REGI | Branch: AP RU | 7 RUN U | JP APRON | Section: | 5205 Surface:AC |
|--------------------|--------------|-----------|---------------|------------|--------------------|------------------|--|
| L.C.D. 1/1/ | 1980 Us | se: APRON | Rank: P L | ength: 175 | .00 (Ft) Wi | dth: 50.0 | 0 (Ft) True Area: 7974.000002 (SqFt |
| Work Date | Work Code | Work | Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1980 | IMPORT ED | BUILT | | 0.00 | 0.00 | V | EST 1980 BIT |

Network: GAINESVILLE REGI Branch: APS SOUTH APRONS Section: 4105 Surface: AAC L.C.D. 7/1/2009 Use: APRON Rank: P 630.00 (Ft) Width: 100.00 (Ft) True Area: 66500.00002 (SqFt Length: Work Thickness Major **Work Date Work Description** Cost **Comments** M&R Code (in) 7/1/2009 ML-OV MILL and OVERLAY 0.00 0.00 ~ IMPORT BUILT 1/1/1978 0.00 5.00 V 1978 5" P-401 11" P-211 6" P-154 ED

Network: GAINESVILLE REGI Branch: APS SOUTH APRONS Section: 4110 Surface:PCC **L.C.D.** 1/1/1978 Use: APRON Rank: P Length: 700.00 (Ft) Width: 180.00 (Ft) True Area: 126000.0000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|----------------------|------|----------------|--------------|--|
| 1/1/2005 | JS-SI | Joint Seal - Silicon | 0.00 | 0.00 | | |
| 1/1/1978 | IMPORT ED | BUILT | 0.00 | 12.00 | _ · | 1978 12" P-501 11" P-211 12" SUBGRADE |

Network: GAINESVILLE REGI SOUTH APRONS Section: 4115 Branch: AP S Surface:PCC **L.C.D.** 1/1/1978 Use: APRON Rank: P Length: 700.00 (Ft) Width: 50.00 (Ft) True Area: 35000.00001 (SqFt Work Thickness Major Work Date **Work Description** Cost Comments Code (in) M&R 1/1/2005 JS-SI Joint Seal - Silicon 0.00 0.00 1/1/1978 IMPORT BUILT 0.001978 8" P-501 11" P-211 12" 8.00 ~ SUBGRADE

Network: GAINESVILLE REGI Branch: APS SOUTH APRONS Section: 4120 Surface: AAC Width: 90.00 (Ft) True Area: 12825.00000 (SqFt L.C.D. 7/1/2009 Use: APRON Rank: P Length: 135.00 (Ft) Work Thickness Major **Work Date Work Description** Cost Comments Code M&R (in) 7/1/2009 ML-OV MILL and OVERLAY 0.00 0.00 ~ IMPORT BUILT 1/1/1978 0.002.00 1978 2" P-401 8" P-211 6" P-154 V

Network: GAINESVILLE REGI Branch: APS SOUTH APRONS Section: 4125 Surface: AAC **L.C.D.** 7/1/2009 Use: APRON Rank: P 230.00 (Ft) Width: 95.00 (Ft) True Area: 22290.00000 (SqFt Length:

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|---|
| 7/1/2009 | ML-OL | Mill and Overlay | 0.00 | 0.00 | > | |
| 1/1/1988 | IMPORT ED | REPAIR | 0.00 | 0.00 | | 1988 SEAL COAT |
| 1/1/1981 | IMPORT ED | OVERLAY | 0.00 | 4.00 | | 1981 4" P-401 OL |
| 1/1/1978 | IMPORT ED | BUILT | 0.00 | 2.00 | > | 1978 2" P-401 11" P-211 12" SUBGRADE |

PAVER 7.0 TM Pavement Management System

Page 6 of 17

Pavement Database: FDOT

| Network: | GAINESV | VILLE REGI Branch: AP S | SOUT | H APRONS | Section: | 4130 Surface:AAC | |
|--|---|--|--|--|---|--|--|
| L.C.D. 7/1/2 | 009 Us | se: APRON Rank: P I | Length: 220 | .00 (Ft) Wi | dth: 40.0 | 00 (Ft) True Area: 8760.000002 (SqFt | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments | |
| 7/1/2009 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | V | | |
| 1/1/1988 | IMPORT ED | REPAIR | 0.00 | 0.00 | | 1988 SEAL COAT | |
| 1/1/1978 | IMPORT ED | BUILT | 0.00 | 2.00 | | 1978 2" P-401 11" P-211 12" SUBGRADE | |
| Network: GAINESVILLE REGI Branch: AP S SOUTH APRONS Section: 4135 Surface:PG | | | | | | | |
| L.C.D. 1/1/2 | 016 Us | se: APRON Rank: P | Length: 305 | .00 (Ft) Wi | dth: 230.0 | 00 (Ft) True Area: 70723.00002 (SqFt | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments | |
| 1/1/2016 | NC-PC | New Construction - PCC | | | V | 12" P-501, 6" P-306 | |
| | | | | | | | |
| | | VILLE REGI Branch: AP SV | | HWEST AP | Section: | | |
| L.C.D. 1/1/2 | | se: APRON Rank: P I | Length: 250 | | | 0 (Ft) True Area: 32431.00000 (SqFt | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments | |
| 1/1/2005 | | MILL and OVERLAY | 0.00 | 0.00 | > | | |
| 1/1/1991 | IMPORT ED | BUILT | 0.00 | 2.00 | > | 1991 2" P-401 8" P-211 12" P-152 | |
| | l | | | | | | |
| | | | | | | | |
| Network: | GAINESV | VILLE REGI Branch: AP SV | V SOUT | HWEST AP | Section: | 4310 Surface:AC | |
| Network: L.C.D. 12/25 | | | | | | 4310 Surface: AC 0 (Ft) True Area: 12201.00000 (SqFt | |
| | | | | | | | |
| L.C.D. 12/25 | 5/199 Us Work | Work Description Surface Treatment - Double | Length: 100 | .00 (Ft) Wi | dth: 70.0 | 0 (Ft) True Area: 12201.00000 (SqFt | |
| L.C.D. 12/25 Work Date | Work Code LC-DB | se: APRON Rank: P I Work Description | Cost | .00 (Ft) Wid Thickness (in) | Major M&R | 0 (Ft) True Area: 12201.00000 (SqFt | |
| L.C.D. 12/25 Work Date 7/2/2010 | Work Code LC-DB | Work Description Surface Treatment - Double Bitum. | Cost 0.00 | Thickness (in) | dth: 70.0 | 0 (Ft) True Area: 12201.00000 (SqFt | |
| Work Date 7/2/2010 12/25/1999 | Work Code LC-DB | Work Description Surface Treatment - Double Bitum. | Cost 0.00 0.00 | Thickness (in) | Major M&R | O (Ft) True Area: 12201.00000 (SqFt Comments | |
| Work Date 7/2/2010 12/25/1999 | Work Code LC-DB NU-IN | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV | Cost 0.00 0.00 V SOUT | Thickness (in) 0.00 0.00 HWEST AP | Major M&R | 0 (Ft) True Area: 12201.00000 (SqFt Comments | |
| Work Date 7/2/2010 12/25/1999 Network: | Work Code LC-DB NU-IN | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV | Cost 0.00 0.00 V SOUT | Thickness (in) 0.00 0.00 HWEST AP | Major M&R | 0 (Ft) True Area: 12201.00000 (SqFt Comments 4315 Surface: AC | |
| Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 | Work Code LC-DB NU-IN GAINESV 5/199 Us | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SW See: APRON Rank: P I Work Description Surface Treatment - Double | Cost 0.00 0.00 V SOUT ength: 210 | Thickness (in) 0.00 0.00 HWEST AP .00 (Ft) Wir | Major M&R Section: dth: 70.0 | Comments 4315 Surface: AC 0 (Ft) True Area: 23585.00000 (SqFt | |
| Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 Work Date | Work Code LC-DB NU-IN GAINESV 5/199 Us Work Code | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SW Se: APRON Rank: P I Work Description | Cost 0.00 V SOUT Cost 210 Cost | Thickness (in) 0.00 0.00 HWEST AP .00 (Ft) Win Thickness (in) | Major M&R Section: dth: 70.0 | Comments 4315 Surface: AC 0 (Ft) True Area: 23585.00000 (SqFt | |
| Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 Work Date 7/2/2010 12/25/1999 | Work Code LC-DB NU-IN GAINESV 5/199 Us Work Code LC-DB NU-IN | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV Se: APRON Rank: P I Work Description Surface Treatment - Double Bitum. New Construction - Initial | Cost 0.00 V SOUT Cost 0.00 Cost 0.00 Cost 0.00 Cost 0.00 | Thickness (in) 0.00 0.00 HWEST AP 0.00 (Ft) Wichness (in) 0.00 0.00 | dth: 70.0 Major M&R Section: dth: 70.0 Major M&R | Comments | |
| Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 Work Date 7/2/2010 12/25/1999 Network: | Work Code LC-DB NU-IN GAINESV Work Code LC-DB NU-IN | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV See: APRON Rank: P I Work Description Surface Treatment - Double Bitum. New Construction - Initial | Cost 0.00 V SOUT Cength: 210 Cost 0.00 Cost 0.00 Cost Cost 0.00 SOUT | HWEST AP 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 | Major M&R Section: Major M&R Section: | Comments Surface: AC (Ft) True Area: 12201.00000 (SqFt Comments 4315 Surface: AC (Ft) True Area: 23585.00000 (SqFt Comments 4320 Surface: AAC | |
| Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 Work Date 7/2/2010 12/25/1999 | Work Code LC-DB NU-IN GAINESV Code LC-DB NU-IN GAINESV O10 US Work | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV See: APRON Rank: P I Work Description Surface Treatment - Double Bitum. New Construction - Initial | Cost 0.00 V SOUT Cength: 210 Cost 0.00 Cost 0.00 Cost Cost 0.00 SOUT | Thickness (in) 0.00 0.00 HWEST AP 0.00 (Ft) Wi Thickness (in) 0.00 0.00 HWEST AP 0.00 (Ft) Wi Thickness (in) | Section: dth: 70.0 Major M&R Section: dth: 70.0 Major M&R Section: dth: 100.0 Major | Comments | |
| Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 Work Date 7/2/2010 12/25/1999 Network: L.C.D. 7/1/2 Work Date | Work Code LC-DB NU-IN GAINESV 6/199 Us Work Code LC-DB NU-IN GAINESV | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV See: APRON Rank: P I Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV See: APRON Rank: P I SV See: APRON Rank: P I See: A | Cost 0.00 V SOUT Cost 0.00 Cost 0.00 Cost 0.00 Cost 0.00 Cost 100 | Thickness (in) 0.00 0.00 HWEST AP 0.00 (Ft) Wi Thickness (in) 0.00 0.00 HWEST AP | section: Major M&R Section: dth: 70.0 Major M&R Section: dth: 100.0 | Comments 4315 Surface: AC 0 (Ft) True Area: 23585.00000 (SqFt Comments 4320 Surface: AAC 0 (Ft) True Area: 21340.00000 (SqFt | |
| L.C.D. 12/25 Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 Work Date 7/2/2010 12/25/1999 Network: L.C.D. 7/1/2 | Work Code LC-DB NU-IN GAINESV Code LC-DB NU-IN GAINESV O10 US Work | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV Se: APRON Rank: P I Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV Se: APRON Rank: P I Work Description | Cost | Thickness (in) O.00 HWEST AP O.00 Thickness (in) O.00 HWEST AP O.00 Thickness (in) HWEST AP | section: dth: 70.0 Major M&R Section: dth: 70.0 Major M&R Section: dth: 100.0 Major M&R | Comments | |
| Work Date 7/2/2010 12/25/1999 Network: L.C.D. 12/25 Work Date 7/2/2010 12/25/1999 Network: L.C.D. 7/1/2 Work Date 6/1/2018 | Work Code LC-DB NU-IN GAINESV 6/199 Us Work Code LC-DB NU-IN GAINESV Work Code ST-SC | Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV See: APRON Rank: P I Work Description Surface Treatment - Double Bitum. New Construction - Initial VILLE REGI Branch: AP SV See: APRON Rank: P I Work Description Surface Treatment - See: APRON Rank: P I Work Description Surface Treatment - Seel Coat | Cost 0.00 V SOUT Cost 0.00 Cost 0.00 Cost 0.00 Cost 0.00 Cost 0.00 Cost 0.00 | Thickness (in) O.00 HWEST AP O.00 (Ft) Wie Thickness (in) O.00 HWEST AP O.00 (Ft) Wie Thickness (in) O.00 O.00 | Section: dth: 70.0 Major M&R Section: dth: 70.0 Major M&R Section: dth: 100.0 Major | Comments | |

Page 7 of 17

Pavement Database: FDOT

| Network | GAINESV | VILLE REGI Branch: AP SW | V SOUT | HWEST AP | Section: | 4325 | Surface:AC |
|--------------------|--------------|-----------------------------------|---------------|----------------|--------------|-------------------|-------------------|
| L.C.D. 7/1/ | 2010 U | se: APRON Rank: P I | Length: 1,250 | .00 (Ft) Wi | dth: 50.0 | 0 (Ft) True Area: | 72728.00002 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Com | ments |
| 7/2/2010 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | | |
| 7/1/2010 | NC-AC | New Construction - AC | 0.00 | 0.00 | | | |
| 12/25/1999 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | | |

Network: GAINESVILLE REGI Branch: AP SW SOUTHWEST AP Section: 4330 Surface: AC L.C.D. 1/1/2009 Use: APRON Rank: P Length: 300.00 (Ft) Width: 150.00 (Ft) True Area: 61003.00001 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments Code M&R (in) 1/1/2009 NU-IN New Construction - Initial 0.00 EST 2009 CONSTRUCTION 0.00

Network: GAINESVILLE REGI Branch: RW 11-29 **RUNWAY 11-29** Section: 6201 Surface: AAC **L.C.D.** 1/1/2015 Use: RUNWAY Rank: P Length: 228.00 (Ft) Width: 50.00 (Ft) True Area: 12282.00000 (SqFt Work Major Thickness Work Date **Work Description** Cost Comments Code (in) M&R 1/1/2015 ML-OV MILL and OVERLAY 0.00 0.00 2/1/2005 ML-OL Mill and Overlay 0.00 0.00 1/1/2005 PA-AD Patching - AC Deep 0.000.00 1/1/1973 IMPORT BUILT EST 1973 BIT OL 0.00 0.00 ~ ED

Network: GAINESVILLE REGI Branch: RW 11-29 **RUNWAY 11-29** Section: 6202 Surface: AAC **L.C.D.** 2/1/2005 Use: RUNWAY Rank: P Length: 404.00 (Ft) Width: 100.00 (Ft) True Area: 34697.00001 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code M&R (in) 2/1/2005 ML-OL Mill and Overlay 0.00 0.00 ~ 1/1/2005 Patching - AC Deep 0.00 0.00 PA-AD 1/1/1973 IMPORT BUILT EST 1973 BIT OL 0.00 0.00 ~ ED

 Network:
 GAINESVILLE REGI
 Branch:
 RW 11-29
 RUNWAY 11-29
 Section:
 6205
 Surface:AAC

 L.C.D. 2/1/2005
 Use:
 RUNWAY
 Rank:
 P
 Length:
 4,470.00 (Ft)
 Width:
 100.00 (Ft)
 True Area:
 630300.0001 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|--------------------|------|----------------|--------------|--------------------------------|
| 2/1/2005 | ML-OL | Mill and Overlay | 0.00 | 0.00 | > | |
| 1/1/2005 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | | |
| 1/1/1973 | IMPORT ED | BUILT | 0.00 | 3.00 | | 1973 3" P-401 OL |
| 1/1/1973 | IMPORT ED | OVERLAY | 0.00 | 2.00 | > | 2" P-401 8" P-211 6" STAB BASE |

Page 8 of 17

Pavement Database: FDOT

| Network: GAINESVILLE REGI | | | anch: RW 11- | 29 RUNW | /AY 11-29 | Section: | 6207 | Surface: AAC |
|---------------------------|--------------|--------------------|--------------|------------|----------------|--------------|-------------------|-------------------|
| L.C.D. 2/1/2 | 005 Us | se: RUNWAY Ra | ank: P Lo | ength: 600 | .00 (Ft) Wie | dth: 25.0 | 0 (Ft) True Area: | 17349.00000 (SqFt |
| Work Date | Work Code | Work Descr | ription | Cost | Thickness (in) | Major M&R | Com | ments |
| 2/1/2005 | ML-OL | Mill and Overlay | | 0.00 | 0.00 | V | | |
| 1/1/2005 | PA-AD | Patching - AC Deep | p | 0.00 | 0.00 | | | |
| 1/1/1973 | IMPORT | BUILT | | 0.00 | 0.00 | | EST 1973 BIT OL | |
| | ED | | | | | | | |

 Network:
 GAINESVILLE REGI
 Branch:
 RW 11-29
 RUNWAY 11-29
 Section:
 6210
 Surface:AAC

 L.C.D. 2/1/2005
 Use:
 RUNWAY
 Rank:
 P
 Length:
 8,200.00 (Ft)
 Width:
 25.00 (Ft)
 True Area:
 315150.0000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|--------------------|------|----------------|--------------|--------------------------------|
| 2/1/2005 | ML-OL | Mill and Overlay | 0.00 | 0.00 | V | |
| 1/1/2005 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | | |
| 1/1/1973 | IMPORT ED | BUILT | 0.00 | 2.00 | | 1973 1-2" P-401 OL |
| 1/1/1973 | IMPORT ED | OVERLAY | 0.00 | 2.00 | | 2" P-401 8" P-211 6" STAB BASE |

 Network:
 GAINESVILLE REGI
 Branch:
 RW 11-29
 RUNWAY 11-29
 Section:
 6225
 Surface:AAC

 L.C.D. 2/1/2005
 Use:
 RUNWAY
 Rank:
 P
 Length:
 1,000.00 (Ft)
 Width:
 100.00 (Ft)
 True Area:
 100100.0000 (SqFt

| v | Vork Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|----|-----------|--------------|--------------------|------|----------------|--------------|--------------------------------|
| 2/ | 1/2005 | ML-OL | Mill and Overlay | 0.00 | 0.00 | V | |
| 1/ | 1/2005 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | | |
| 1/ | 1/1998 | | OVERLAY | 0.00 | 0.00 | | 1998 MILL EXISTING AND |
| | | ED | | l | | | RESURFACE WITH P401 AC |
| 1/ | 1/1983 | IMPORT | BUILT | 0.00 | 4.00 | | 1983 4" P401 AC SURFACE ON 13" |
| | | ED | | | | | P211 BASE ON 51" P152 SUBBASE |

 Network:
 GAINESVILLE REGI
 Branch:
 RW 11-29
 RUNWAY 11-29
 Section:
 6230
 Surface:AAC

 L.C.D. 2/1/2005
 Use:
 RUNWAY
 Rank:
 P
 Length:
 2,000.00 (Ft)
 Width:
 25.00 (Ft)
 True Area:
 50050.00001 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|--------------------|------|----------------|--------------|---|
| 2/1/2005 | ML-OL | Mill and Overlay | 0.00 | 0.00 | > | |
| 1/1/2005 | PA-AD | Patching - AC Deep | 0.00 | 0.00 | | |
| 1/1/1998 | IMPORT ED | OVERLAY | 0.00 | 0.00 | | 1998 MILL AND RESURFACE WITH P401 AC |
| 1/1/1983 | IMPORT ED | BUILT | 0.00 | 4.00 | | 1983 4" P401 AC SURFACE ON 13" P211 BASE ON 51" P152 SUBBASE |

 Network:
 GAINESVILLE REGI
 Branch:
 RW 7-25
 RUNWAY 7-25
 Section:
 6105
 Surface:AAC

 L.C.D. 9/1/2015
 Use:
 RUNWAY
 Rank:
 S
 Length:
 4,000.00 (Ft)
 Width:
 80.00 (Ft)
 True Area:
 415800.0001 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|---------------------------------|
| 9/1/2015 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | Y | 0.5"-1.0" MILL 3" P-401 OVERLAY |
| 1/1/1972 | IMPORT | BUILT | 0.00 | 1.50 | | 1972 1.5" P-401 OL |
| | ED | | | | | |

ED

Work History Report

Page 9 of 17

SUBGRADE

Pavement Database: FDOT

| Network: | GAINESV | ILLE REGI Branch: TL T-H | IANG TLT-F | IANGAR | Section: | 3105 Surface:AAC |
|---------------------|--------------|-----------------------------------|--------------|---------------------|------------------|--|
| L.C.D. 7/1/2 | 009 Us | se: TAXILAN Rank: P L | ength: 1,800 | .00 (Ft) Wid | 1th: 20.0 | 0 (Ft) True Area: 52426.00001 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2018 | CS-AC | Crack Sealing - AC | 0.00 | 0.00 | | |
| 7/2/2009 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2009 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | ~ : | |
| 1/1/1991 | IMPORT ED | BUILT | 0.00 | 0.00 | | EST 1991 BIT |

Network: GAINESVILLE REGI Branch: TW A TAXIWAY A Section: 104 Surface: AAC **L.C.D.** 1/1/2015 Use: TAXIWAY Rank: P Length: 480.00 (Ft) Width: 56.00 (Ft) True Area: 13820.00000 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2015 ML-OV MILL and OVERLAY 0.00 0.00 12/25/2011 Crack Sealing - AC 0.00 CS-AC 0.00 1/1/1973 IMPORT OVERLAY 0.00 1973 2" P-401 OL 2.00 ~ ED1/1/1968 IMPORT BUILT 0.002.00 1968 2" P-401 8" P-211 6"

| Work Date | Code | Work Description | Cost | (in) | M&R | Comments |
|------------|--------------|--------------------|------|------|-----|---------------------------------------|
| 12/25/2011 | CS-AC | Crack Sealing - AC | 0.00 | 0.00 | | |
| 1/1/1973 | IMPORT ED | OVERLAY | 0.00 | 2.00 | | 1973 2" P-401 OL |
| 1/1/1968 | IMPORT ED | BUILT | 0.00 | 2.00 | | 1968 2" P-401 8" P-211 6" SUBGRADE |

Network: GAINESVILLE REGI Branch: TW A TAXIWAY A Section: 108 Surface:AAC

L.C.D. 1/1/2005 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 50.00 (Ft) True Area: 6264.000001 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|----------------------------------|
| 1/1/2005 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | V | |
| 1/1/1991 | IMPORT ED | BUILT | 0.00 | 2.00 | | 1991 2" P-401 8" P-211 12" P-154 |

Network: GAINESVILLE REGI Branch: TW A TAXIWAY A Section: 110 Surface: AAC

L.C.D. 1/1/2012 Use: TAXIWAY Rank: P Length: 430.00 (Ft) Width: 50.00 (Ft) True Area: 50240.00001 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments Code M&R (in) 1/1/2012 MILL and OVERLAY M&O, 4" P-401 OVER MIN. 6" LIM ML-OV 0.00 0.00 ~ 1/1/1973 IMPORT OVERLAY 1973 2" P-401 OL 0.00 2.00 ~ ED 1/1/1968 IMPORT BUILT 0.00 1968 2" P-401 8" P-211 6" 2.00 ~ ED SUBGRADE

Page 10 of 17

Pavement Database: FDOT

| Network: | GAINESV | TILLE REGI Branch: TW A | TAXI | WAY A | Section: | Surface: AAC |
|---|---|--|--|--|---|---|
| L.C.D. 7/1/2 | 009 Us | se: TAXIWAY Rank: P L | ength: 370 | .00 (Ft) Wie | dth: 50.0 | 0 (Ft) True Area: 22645.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2009 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2009 | ML-OL | Mill and Overlay | 0.00 | 0.00 | | |
| 1/1/2002 | MI-CO | Cold Milling | 0.00 | 1.50 | | |
| 1/1/2002 | OL-AS | Overlay - AC Structural | 0.00 | 1.50 | ~ | |
| 1/1/1973 | IMPORT | BUILT | 0.00 | 4.00 | | 1973 4" P-401 8" P-211 2" SUBBASE |
| | ED | | | | | 6" STAB BASE |
| Network: | GAINESV | TILLE REGI Branch: TW A | TAXIV | WAY A | Section: | 117 Surface: AAC |
| L.C.D. 7/1/2 | | | | | | 0 (Ft) True Area: 9679.000002 (SqFt |
| | Work | | I | Thickness | Major | |
| Work Date | Code | Work Description | Cost | (in) | M&R | Comments |
| 7/2/2009 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2009 | ML-OL | Mill and Overlay | 0.00 | 0.00 | ~ | |
| 1/1/2002 | MI-CO | Cold Milling | 0.00 | 1.50 | | |
| 1/1/2002 | OL-AS | Overlay - AC Structural | 0.00 | 1.50 | | |
| 1/1/1973 | IMPORT ED | BUILT | 0.00 | 0.00 | | EST 1973 BIT SECTION UNKNOWN |
| | ED | | | | | UNKNOWN |
| | | | | | | |
| Network: | GAINESV | TILLE REGI Branch: TW A | TAXI | WAY A | Section: | 119 Surface:AAC |
| Network: L.C.D. 7/1/2 | | | | | | 119 Surface: AAC 0 (Ft) True Area: 4962.000001 (SqFt |
| | | | | | | |
| L.C.D. 7/1/2 | 009 Us Work | se: TAXIWAY Rank; P L | ength: 202 | .00 (Ft) Wie | dth: 50.0 Major | 0 (Ft) True Area: 4962.000001 (SqFt |
| L.C.D. 7/1/2 Work Date | 009 Us Work Code | se: TAXIWAY Rank: P L | ength: 202 | .00 (Ft) Wid Thickness (in) | dth: 50.0 Major M&R | 0 (Ft) True Area: 4962.000001 (SqFt |
| L.C.D. 7/1/2 Work Date 7/1/2009 | 009 Us Work Code ML-OV | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. | Cost 0.00 | Thickness (in) | dth: 50.0 Major M&R | 0 (Ft) True Area: 4962.000001 (SqFt |
| Work Date 7/1/2009 7/1/2009 | Work Code ML-OV SU-DB | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. | Cost 0.00 0.00 | 0.00 (Ft) Wid Thickness (in) 0.00 0.00 | Major M&R | O (Ft) True Area: 4962.000001 (SqFt Comments 1972 1 1/2" P401 AC PAVEMENT |
| Work Date 7/1/2009 7/1/2009 1/1/1972 | Work Code ML-OV SU-DB IMPORT ED | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. | Cost 0.00 0.00 0.00 | 0.00 (Ft) Wid Thickness (in) 0.00 0.00 | Major M&R | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE |
| L.C.D. 7/1/2 Work Date 7/1/2009 7/1/2009 1/1/1972 Network: | Work Code ML-OV SU-DB IMPORT ED | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT VILLE REGI Branch: TW A | Cost 0.00 0.00 0.00 TAXIV | .00 (Ft) Win Thickness (in) 0.00 0.00 0.50 | Major M&R | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE |
| L.C.D. 7/1/2 Work Date 7/1/2009 7/1/2009 1/1/1972 Network: | Work Code ML-OV SU-DB IMPORT ED | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT VILLE REGI Branch: TW A | Cost 0.00 0.00 0.00 TAXIV | .00 (Ft) Win Thickness (in) 0.00 0.00 0.50 | Major M&R | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC |
| Work Date 7/1/2009 7/1/2009 1/1/1972 Network: L.C.D. 1/1/2 | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT VILLE REGI Branch: TW A se: TAXIWAY Rank: P L | Cost 0.00 0.00 0.00 TAXIVength: 1,880 | 0.00 (Ft) Width 1.00 | Major M&R Section: dth: 50.0 | 0 (Ft) True Area: 4962.000001 (SqFt Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt |
| Work Date 7/1/2009 7/1/2009 1/1/1972 Network: L.C.D. 1/1/2 Work Date | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work Code | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT VILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description | Cost 0.00 0.00 TAXIVength: 1,880 | No (Ft) Width | Major M&R W Section: dth: 50.0 Major M&R | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt |
| Network: L.C.D. 1/1/2 Work Date 7/1/2009 1/1/1972 Network: L.C.D. 1/1/2 Work Date 1/1/2012 1/1/1972 | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work Code ML-OV NU-IN | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT VILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial | Cost O.00 0.00 0.00 TAXIVength: 1,880 Cost 0.00 0.00 | No (Ft) Width | Section: dth: 50.0 Major M&R Section: dth: 50.0 Major M&R V | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt Comments M&O, 4" P-401 OVER MIN. 6" LIM |
| Network: 1/1/2012 1/1/1972 Network: L.C.D. 1/1/2 Work Date 1/1/2012 1/1/1972 | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work Code ML-OV NU-IN | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT VILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial | Cost TAXIV ength: 1,880 Cost 0.00 TAXIV | No (Ft) Wide | Section: Section: Section: | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt Comments M&O, 4" P-401 OVER MIN. 6" LIM |
| Network: L.C.D. 1/1/2 Work Date 7/1/2009 1/1/1972 Network: L.C.D. 1/1/2 Work Date 1/1/2012 1/1/1972 | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work Code ML-OV NU-IN GAINESV | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT VILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial | Cost TAXIV ength: 1,880 Cost 0.00 TAXIV | No (Ft) Wide | Section: Major M&R Section: dth: 50.0 Major M&R Section: dth: 40.0 | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt Comments M&O, 4" P-401 OVER MIN. 6" LIM |
| Network: L.C.D. 1/1/2 Work Date 7/1/2009 7/1/2009 1/1/1972 Network: L.C.D. 1/1/2 Work Date 1/1/2012 1/1/1972 Network: L.C.D. 1/1/1 Work Date | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work Code ML-OV NU-IN GAINESV 979 Us Work Code | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT MILLE REGI Branch: TW A Se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial MILLE REGI Branch: TW A Se: TAXIWAY Rank: P L Work Description | Cost TAXIV ength: 1,880 Cost 0.00 TAXIV | No (Ft) Wide | Section: Section: Section: | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt Comments M&O, 4" P-401 OVER MIN. 6" LIM |
| Network: L.C.D. 1/1/2 Work Date 7/1/2009 1/1/1972 Network: L.C.D. 1/1/2 Work Date 1/1/2012 1/1/1972 Network: L.C.D. 1/1/1 Work Date 1/2/25/2011 | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work Code ML-OV NU-IN GAINESV 979 Us Work Code ST-SC | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT TILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial TILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description Surface Treatment - Seal Coat | Cost Cost 0.00 0.00 0.00 TAXIVength: 1,880 Cost 0.00 0.00 TAXIVength: 380 Cost 0.00 0.00 | ### Continuation of the image is a continuation of the image i | Section: dth: 50.0 Major M&R Section: dth: 50.0 Major M&R Section: dth: 40.0 Major M&R | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt Comments M&O, 4" P-401 OVER MIN. 6" LIM 130 Surface:AC 0 (Ft) True Area: 11380.00000 (SqFt Comments |
| Network: L.C.D. 1/1/2 Work Date 7/1/2009 7/1/2009 1/1/1972 Network: L.C.D. 1/1/2 Work Date 1/1/2012 1/1/1972 Network: L.C.D. 1/1/1 Work Date | Work Code ML-OV SU-DB IMPORT ED GAINESV 012 Us Work Code ML-OV NU-IN GAINESV 979 Us Work Code | Work Description MILL and OVERLAY Surface Treatment - Double Bitum. BUILT TILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description MILL and OVERLAY New Construction - Initial TILLE REGI Branch: TW A se: TAXIWAY Rank: P L Work Description Surface Treatment - Seal Coat | Cost Cost 0.00 0.00 0.00 TAXIVength: 1,880 Cost 0.00 0.00 TAXIVength: 380 Cost | ### Company of the co | Section: Major M&R Section: dth: 50.0 Major M&R Section: dth: 40.0 Major | Comments 1972 1 1/2" P401 AC PAVEMENT ON UNKNOWN BASE 120 Surface:AAC 0 (Ft) True Area: 98695.00003 (SqFt Comments M&O, 4" P-401 OVER MIN. 6" LIM 130 Surface:AC 0 (Ft) True Area: 11380.00000 (SqFt |

8/23/2019

Work History Report

Page 11 of 17

Pavement Database: FDOT

| | | Pavement Database: | FDOT | | | |
|------------------------|----------------|---|--------------|----------------------|--------------|--|
| Network: | GAINESV | ILLE REGI Branch: TW A | TAXI | WAY A | Section: | 135 Surface:AC |
| L.C.D. 1/1/1 | 980 Us | se: TAXIWAY Rank: P L | ength: 500 | .00 (Ft) Wie | dth: 40.0 | 0 (Ft) True Area: 20258.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 12/25/2011 1/1/1980 | ST-SC NU-IN | Surface Treatment - Seal Coat New Construction - Initial | 0.00 0.00 | 0.00 | | EST 1980 BIT SECTION UNKNOW |
| | | | | | | |
| Network: | GAINESV | ILLE REGI Branch: TW A | TAXIV | WAY A | Section: | 140 Surface:AC |
| L.C.D. 1/1/1 | 992 Us | e: TAXIWAY Rank: P L | ength: 925 | () | dth: 35.0 | 0 (Ft) True Area: 32303.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1992 | IMPORT ED | BUILT | 0.00 | 2.00 | V | 1992 2" P401 SURFACE ON 8' P211 BASE ON 12" P154 SUBBASE |
| | | | | | | |
| | | ILLE REGI Branch: TW A | | WAY A | Section: | |
| L.C.D. 1/1/1 | | se: TAXIWAY Rank: P L | ength: 100 | . , | | 0 (Ft) True Area: 5547.000001 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1992 | IMPORT ED | BUILT | 0.00 | 2.00 | | 1992 2" P401 AC SURFACE ON 8' P211 BASE ON 12" P152 SUBBASE |
| | | | | | | |
| | | ILLE REGI Branch: TW A | | WAY A | Section: | |
| L.C.D. 1/1/1 | 980 Us Work | se: TAXIWAY Rank: P L | ength: 99 | .00 (Ft) Wid | | 0 (Ft) True Area: 3947.000001 (SqFt |
| Work Date | Work Code | Work Description | Cost | (in) | Major M&R | Comments |
| 7/2/2009 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 1/1/1980 | IMPORT | | 0.00 | 0.00 | | EST 1980 AC SECTION UNKNOWN |
| | ED | | ! | | | |
| Network: | GAINESV | ILLE REGI Branch: TW A | TAXI | WAY A | Section: | 149 Surface: AAC |
| L.C.D. 7/1/2 | 009 Us | se: TAXIWAY Rank: P L | ength: 109 | .00 (Ft) Wi o | dth: 40.0 | 0 (Ft) True Area: 4225.000001 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2009 | SU-DB | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2009 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | | |
| 1/1/1980 | IMPORT ED | BUILT | 0.00 | 0.00 | | EST 1980 BIT |
| - | - | | | | | |

 Network:
 GAINESVILLE REGI
 Branch:
 TW A
 TAXIWAY A
 Section:
 152
 Surface:AAC

 L.C.D. 7/1/2009
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 65.00 (Ft)
 Width:
 50.00 (Ft)
 True Area:
 3939.000001 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|----------------------------|------|----------------|--------------|-----------------------------------|
| 7/2/2009 | SU-DB | Surface Treatment - Double | 0.00 | 0.00 | | |
| | | Bitum. | | | | |
| 7/1/2009 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | ✓: | |
| 1/1/1979 | IMPORT | BUILT | 0.00 | 1.50 | V | 1979 1.5" P-401 6" P-211 4" P-152 |
| | ED | | | | | |

Page 12 of 17

Pavement Database: FDOT

| Network: | Network: GAINESVILLE REGI Branch: TW A | | | WAY A | Section: | 153 Surface:AAC |
|---------------------|--|-----------------------------------|-----------|----------------|------------------|--|
| L.C.D. 7/1/2 | 009 Us | se: TAXIWAY Rank: P L | ength: 65 | .00 (Ft) Wi | dth: 50.0 | 0 (Ft) True Area: 4523.000001 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2009 | | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2009 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | ~ | |
| 1/1/1979 | IMPORT ED | BUILT | 0.00 | 1.50 | > | 1979 1.5" P-401 6" P-211 4" P-152 |

Network: GAINESVILLE REGI Branch: TW A TAXIWAY A Section: 154 Surface: AAC **L.C.D.** 7/1/2009 Use: TAXIWAY Rank: P Length: 65.00 (Ft) Width: 50.00 (Ft) True Area: 4561.000001 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 7/2/2009 SU-DB Surface Treatment - Double 0.00 0.00 7/1/2009 MILL and OVERLAY ML-OV 0.000.00 ~ IMPORT BUILT 1/1/1979 0.00 0.00 ~ EST 1979 BIT SECTION ED UNKNOWN

Network: GAINESVILLE REGI Branch: TW B TAXIWAY B Section: 203 Surface:AAC

L.C.D. 1/1/2015 Use: TAXIWAY Rank: P Length: 300.00 (Ft) Width: 50.00 (Ft) True Area: 8026.000002 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|---------------------|
| 1/1/2015 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | V | 1.5" Mill & Overlay |
| 7/1/2009 | ML-OL | Mill and Overlay | 0.00 | 0.00 | | |
| 1/1/1972 | IMPORT | BUILT | 0.00 | 1.50 | | 1972 1.5" P-401 OL |
| | ED | | | | | |

 Network:
 GAINESVILLE REGI
 Branch:
 TW B
 TAXIWAY B
 Section:
 205
 Surface:AAC

 L.C.D. 7/1/2009
 Use:
 TAXIWAY B
 Length:
 2,571.00 (Ft)
 Width:
 50.00 (Ft)
 True Area:
 129976.0000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|--------------------|
| 7/1/2009 | ML-OL | Mill and Overlay | 0.00 | 0.00 | V | |
| 1/1/1972 | IMPORT | BUILT | 0.00 | 1.50 | | 1972 1.5" P-401 OL |
| | ED | | | | | |

Network: GAINESVILLE REGI Branch: TW B TAXIWAY B Section: 206 Surface:AAC L.C.D. 1/1/2015 Use: TAXIWAY Rank: P Length: 320.00 (Ft) Width: 35.00 (Ft) True Area: 7137.000002 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|--------------------------------------|
| 1/1/2015 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | V | |
| 7/1/2009 | ML-OL | Mill and Overlay | 0.00 | 0.00 | > | |
| 1/1/1996 | IMPORT ED | OVERLAY | 0.00 | 2.00 | | 1996 2" P401 RESURFACE |
| 1/1/1996 | IMPORT ED | OVERLAY | 0.00 | 0.00 | | UNKNOWN ORIGINAL PAVEMENT |
| 1/1/1972 | IMPORT ED | BUILT | 0.00 | 0.50 | | 1972 1 1/2" AC SURFACE MILLED OFF |

Page 13 of 17

Pavement Database: FDOT

| | | ILLE REGI Branch: TW B | | WAY B | Section: | |
|---------------------|--------------|------------------------|------------|----------------------|--------------|--|
| L.C.D. 7/1/2 | 009 Us | se: TAXIWAY Rank: P L | ength: 450 | .00 (Ft) Wi o | dth: 45.0 | 0 (Ft) True Area: 18964.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2009 | ML-OL | Mill and Overlay | 0.00 | 0.00 | V | |
| 1/1/1996 | IMPORT ED | OVERLAY | 0.00 | 2.00 | | 1996 2" P401 RESURFACE |
| 1/1/1996 | IMPORT ED | OVERLAY | 0.00 | 0.00 | | UNKNOWN ORIGINAL PAVEMENT |
| 1/1/1972 | IMPORT ED | BUILT | 0.00 | 0.50 | | 1972 1 1/2" AC SURFACE MILLED OFF |

Network: GAINESVILLE REGI TAXIWAY B Branch: TW B Section: 210 Surface: AAC **L.C.D.** 1/1/2005 Use: TAXIWAY Rank: P Length: 50.00 (Ft) Width: 50.00 (Ft) True Area: 11878.00000 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2005 ML-OL Mill and Overlay 0.00 0.00 **Y** 1/1/1973 IMPORT BUILT 0.00 2.00 ~ 1973 1-2" P-401 OL ED

Network: GAINESVILLE REGI Branch: TW C TAXIWAY C Section: 304 Surface: AAC

L.C.D. 1/1/2015 Use: TAXIWAY Rank: P Length: 400.00 (Ft) Width: 50.00 (Ft) True Area: 17460.00000 (SqFt

W. J. D. d. Work Work W. J. D. d. d. Thickness Major

| | Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|---|-----------|--------------|------------------------------|------|----------------|--------------|--------------------------------|
| Ī | 1/1/2015 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | > | 1.5" Mill & Overlay |
| | 3/1/2011 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | > | 4" P-401 OVER APPROX 11-12" LI |
| | 1/1/1976 | IMPORT | BUILT | 0.00 | 3.00 | | 1976 3" P-401 9" P-211 6" STAB |
| | | ED | | 1 | | | BASE |

 Network:
 GAINESVILLE REGI
 Branch:
 TW C
 TAXIWAY C
 Section:
 305
 Surface:AC

 L.C.D. 3/1/2011
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 2,000.00 (Ft)
 Width:
 50.00 (Ft)
 True Area:
 110122.0000 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------------------|------|----------------|--------------|--|
| 3/1/2011 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | V | 4" P-401 OVER APPROX 11-12" LI |
| 1/1/1976 | IMPORT ED | BUILT | 0.00 | 3.00 | <u> </u> | 1976 3" P-401 9" P-211 6" STAB BASE |

 Network:
 GAINESVILLE REGI
 Branch:
 TW C
 TAXIWAY C
 Section:
 307
 Surface:AAC

 L.C.D. 7/1/2010
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 275.00 (Ft)
 Width:
 70.00 (Ft)
 True Area:
 44526.00001 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|----------------------------|------|----------------|--------------|-----------------------------------|
| 7/2/2010 | LC-DB | Surface Treatment - Double | 0.00 | 0.00 | | |
| | | Bitum. | | | | |
| 7/1/2010 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | | |
| 1/1/1976 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | 1976 3" P-401 9" P-211 6" STAB BA |

Page 14 of 17

Pavement Database: FDOT

| Network: | GAINESV | ILLE REGI Branch: TW C | TAXIV | WAY C | Section: | 315 Surface:AAC |
|---------------------|--------------|-----------------------------------|------------|----------------|--------------|--|
| L.C.D. 7/1/2 | 010 Us | se: TAXIWAY Rank: P L | ength: 275 | .00 (Ft) Wi | dth: 70.0 | 0 (Ft) True Area: 22886.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/2/2010 | | Surface Treatment - Double Bitum. | 0.00 | 0.00 | | |
| 7/1/2010 | | MILL and OVERLAY | 0.00 | 0.00 | > | |
| 1/1/1976 | IMPORT ED | BUILT | 0.00 | 3.00 | > | 1976 3" P-401 9" P-211 6" STAB BASE |

Network: GAINESVILLE REGI Branch: TW CONN E CONNECTOR TA Section: 605 Surface: AC Use: TAXIWAY Rank: P Length: 200.00 (Ft) Width: 100.00 (Ft) True Area: 28681.00000 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2014 4" P-401, 11" (AVG DEPTH) P-211 R CR-AC Complete Reconstruction - AC 0.00 0.00 **** 1/1/1981 IMPORT BUILT 0.00 4.00 ~ 1981 4" P-401 12" P-211 12" ED **SUBGRADE**

Network: GAINESVILLE REGI Branch: TW CONN E CONNECTOR TA Section: 610 Surface: AAC L.C.D. 7/1/2009 Use: TAXIWAY Rank: P 200.00 (Ft) Width: 100.00 (Ft) True Area: 8448.000002 (SqFt Length: Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 7/1/2009 ML-OL Mill and Overlay 0.00 0.00 NU-IN 1/1/1981 New Construction - Initial 0.00 0.00 ~

Network: GAINESVILLE REGI Branch: TW CONN W CONNECTOR TA Section: 715 Surface: AC L.C.D. 1/1/2014 Use: TAXIWAY Rank: P 300.00 (Ft) Width: 205.00 (Ft) True Area: 65848.00002 (SqFt Length: Thickness Work Major Work Date **Work Description** Cost Comments Code (in) M&R 1/1/2014 NU-IN 4" P-401, 12" P-211, 12" P-160, 12" E New Construction - Initial 0.00 0.00

Network: GAINESVILLE REGI Branch: TW D TAXIWAY D Section: 410 Surface: AAC L.C.D. 7/1/2009 Use: TAXIWAY Rank: P Length: 358.00 (Ft) Width: 50.00 (Ft) True Area: 20831.00000 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments M&R Code (in) 7/1/2009 ML-OL Mill and Overlay 0.00 0.00 IMPORT BUILT 1/1/1972 0.001972 1.5" P-401 OL 1.50 ~ ED

Network: GAINESVILLE REGI Branch: TW E1 TAXIWAY E1 Section: 515 Surface: AAC **L.C.D.** 1/1/2005 Width: 105.00 (Ft) True Area: 19914.00000 (SqFt Use: TAXIWAY Rank: P Length: 200.00 (Ft) Work **Thickness** Major **Work Date** Cost **Work Description** Comments Code (in) M&R 1/1/2005 MILL and OVERLAY ML-OV 0.00 0.00 1/1/1998 IMPORT OVERLAY 1998 MILL EXISTING AND 0.00 0.00 ~ RESURFACE WITH P401 AC ED 1/1/1983 IMPORT BUILT 1983 4" P401 AC SURFACE ON 13" 0.00 4.00 ED P211 BASE

| 8 | /23 | /20 | 19 |
|---|-----|-----|----|
| | | | |

1/1/1978

IMPORT BUILT

ED

Work History Report

Page 15 of 17

1978 3" P-401 11" P-211 6" P-154

Pavement Database: FDOT

| Network: | GAINESV | TLLE REGI | Branch: TW E1 | TAXIV | WAY E1 | Section: | 517 Surface:AC |
|---------------------|--------------|---------------|-----------------|------------|---------------------|--------------|---|
| L.C.D. 1/1/2 | 2014 Us | se: TAXIWAY | Rank: P L | ength: 100 | .00 (Ft) W i | idth: 87.0 | 00 (Ft) True Area: 15325.00000 (SqFt |
| Work Date | Work Code | Work D | escription | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2014 | CR-AC | Complete Reco | nstruction - AC | 0.00 | 0.00 | V | 2014: 4" P401 11" (AVG. DEPTH) P2 |
| 1/1/1978 | NU-IN | New Construct | ion - Initial | 0.00 | 0.00 | V | |

Network: GAINESVILLE REGI Branch: TW E2 TAXIWAY E2 Section: 520 Surface: AAC **L.C.D.** 1/1/2005 Use: TAXIWAY Rank: P Length: 195.00 (Ft) Width: 125.00 (Ft) True Area: 19417.00000 (SqFt Work Thickness Major Work Date **Work Description** Cost Comments Code M&R (in) 1/1/2005 ML-OV MILL and OVERLAY 0.00 0.00

0.00

3.00

~

Network: GAINESVILLE REGI Branch: TW E2 TAXIWAY E2 Section: 522 Surface:AC L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 110.00 (Ft) Width: 87.00 (Ft) True Area: 15698.00000 (SqFt Work Thickness Major **Work Date Work Description** Comments Cost Code M&R (in) 1/1/2014 2014: 4" P401 11" (AVG. DEPTH) P2 CR-AC Complete Reconstruction - AC 0.00 0.00 ~ 1/1/1978 NU-IN New Construction - Initial 0.00 0.00

 Network:
 GAINESVILLE REGI
 Branch:
 TW E3
 TAXIWAY E3
 Section:
 530
 Surface:AAC

 L.C.D. 1/1/2005
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 150.00 (Ft)
 Width:
 175.00 (Ft)
 True Area:
 28702.00000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|----------------------------------|
| 1/1/2005 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | ~ | |
| 1/1/1978 | IMPORT | BUILT | 0.00 | 3.00 | | 1978 3" P-401 11" P-211 6" P-154 |
| | ED | | | | | |

Network: GAINESVILLE REGI Branch: TW E3 TAXIWAY E3 Section: 532 Surface:AC L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 137.00 (Ft) True Area: 20853.00000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------------------|------|----------------|--------------|-----------------------------------|
| 1/1/2014 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | V | 2014: 4" P401 11" (AVG. DEPTH) P2 |
| 1/1/2005 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |
| 1/1/1978 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |

Network: GAINESVILLE REGI Branch: TW E4 TAXIWAY E4 Section: 540 Surface:AAC L.C.D. 1/1/2005 Use: TAXIWAY Rank: P Length: 200.00 (Ft) Width: 155.00 (Ft) True Area: 29074.00000 (SqFt

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|------------------|------|----------------|--------------|----------------------------------|
| 1/1/2005 | ML-OV | MILL and OVERLAY | 0.00 | 0.00 | > | |
| 1/1/1978 | IMPORT | BUILT | 0.00 | 3.00 | > | 1978 3" P-401 11" P-211 6" P-154 |
| | ED | | l | | | |

| 8 | /23 | /20 | 119 | |
|---|-----|-----|-----|--|
| U | | / 4 | ,,, | |

Page 16 of 17

Pavement Database: FDOT

| Network: | GAINESV | TLLE REGI Branch: TW E4 | TAXIV | WAY E4 | Section: | 542 Surface:AC |
|---------------------|--------------|------------------------------|-----------|----------------|--------------|--|
| L.C.D. 1/1/2 | 014 Us | se: TAXIWAY Rank: P L | ength: 87 | .00 (Ft) Wi | dth: 113.0 | 0 (Ft) True Area: 17460.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2014 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | V | 2014: 4" P401 11" (AVG. DEPTH) P2 |
| 1/1/2005 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |
| 1/1/1978 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |

Branch: TW E Network: GAINESVILLE REGI TAXIWAY E - PA Section: 505 Surface: AC L.C.D. 1/1/2014 Use: TAXIWAY Rank: P **Length:** 6,475.00 (Ft) **Width:** 75.00 (Ft) True Area: 491892.0001 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2014 2014: 4" P401 11" (AVG. DEPTH) P2 CR-AC Complete Reconstruction - AC 0.00 0.00 ~ 1/1/1978 IMPORT BUILT 0.00 3.00 ~ 1978 3" P-401 11" P-211 6" P-154 ED

Network: GAINESVILLE REGI Branch: TW E TAXIWAY E - PA Section: 510 Surface: AC L.C.D. 1/1/2014 **Length:** 1,000.00 (Ft) Width: 75.00 (Ft) True Area: 75075.00002 (SqFt Use: TAXIWAY Rank: P Work Thickness Major **Work Date Work Description** Cost **Comments** Code M&R (in) 1/1/2014 2014: 4" P401 11" (AVG. DEPTH) P2 CR-AC Complete Reconstruction - AC 0.00 0.00 ~ 1/1/1998 IMPORT OVERLAY 0.00 0.00 ~ 1998 MILL EXISTING AND ED OVERLAY WITH P401 AC SURFA 1/1/1983 IMPORT BUILT 1983 4" P401 AC SURFACE ON 13" 0.00 4.00 ED P211 BASE

Network: GAINESVILLE REGI Branch: TW E5 **TAXIWAY E5** Section: 550 Surface: AAC L.C.D. 1/1/2005 Use: TAXIWAY Rank: P Length: 150.00 (Ft) Width: 75.00 (Ft) True Area: 19373.00000 (SqFt Work Major Thickness Work Date **Work Description** Cost Comments Code M&R (in) 1/1/2005 ML-OV MILL and OVERLAY 0.00 0.00 **Y** IMPORT BUILT 1/1/1978 0.00 3.00 1978 3" P-401 11" P-211 6" P-154 ED

Network: GAINESVILLE REGI Branch: TW E5 TAXIWAY E5 Section: 552 Surface:AC L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 140.00 (Ft) Width: 70.00 (Ft) True Area: 9790.000002 (SqFt Thickness Work Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2014 2014: 4" P401 11" (AVG. DEPTH) P2 CR-AC 0.00 Complete Reconstruction - AC 0.00 ~ 1/1/2005 NU-IN New Construction - Initial 0.00 0.00 ~ NU-IN 1/1/1978 New Construction - Initial 0.00 0.00 V

Page 17 of 17

Pavement Database: FDOT

Summary:

| Work Description | Section Count | Area Total (SqFt) | Thickness Avg (in) | Thickness STD (in) |
|-----------------------------------|------------------|-------------------|-----------------------|--------------------|
| BUILT | 61 | 4,153,852.00 | 2.13 | 2.06 |
| Cold Milling | 8 | 567,554.00 | 1.50 | 0.00 |
| Complete Reconstruction - AC | 13 | 929,786.00 | 0.69 | 1.26 |
| Crack Sealing - AC | 3 | 146,265.00 | 0.00 | 0.00 |
| Joint Seal - Silicon | 3 | 237,639.00 | 0.00 | 0.00 |
| Mill and Overlay | 63 | 3,664,173.00 | 0.06 | 0.50 |
| New Construction - AC | 2 | 105,688.00 | 0.00 | 0.00 |
| New Construction - Initial | 23 | 798,873.00 | 0.00 | 0.00 |
| New Construction - PCC | 1 | 70,723.00 | 0.00 | 0.00 |
| OVERLAY | 15 | 1,459,032.00 | 1.53 | 1.50 |
| Overlay - AC Structural | 8 | 567,554.00 | 1.50 | 0.00 |
| Patching - AC Deep | 7 | 1,159,928.00 | 0.00 | 0.00 |
| REPAIR | 2 | 31,050.00 | 0.00 | 0.00 |
| Slab Replacement - PCC | 1 | 76,639.00 | 0.00 | 0.00 |
| Surface Seal - Coal Tar | 1 | 145,100.00 | 0.00 | 0.00 |
| Surface Treatment - Double Bitum. | 28 | 1,369,128.00 | 0.00 | 0.00 |
| Surface Treatment - Seal Coat | 3 | 52,978.00 | 0.00 | 0.00 |
| Surface Treatment - Slurry Seal | 1 | 32,960.00 | 0.00 | 0.00 |

| 8/23/2019 |
|-----------|
|-----------|

Branch Condition Report

Page 1 of 2

Pavement Database: FDOT

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | Standard Deviation PCI | Weighted Average PCI |
|-----------|--------------------|----------------------------|---------------------------|---------------------|----------|----------------|------------------------------|----------------------------|
| AP N | 16 | 6,898.00 | 148.44 | 1,129,675.00 | APRON | 69.88 | 8.76 | 71.70 |
| AP RU 25 | 1 | 175.00 | 50.00 | 9,793.00 | APRON | 87.00 | 0.00 | 87.00 |
| AP RU 7 | 1 | 175.00 | 50.00 | 7,974.00 | APRON | 50.00 | 0.00 | 50.00 |
| AP S | 7 | 2,920.00 | 112.14 | 342,098.00 | APRON | 85.86 | 7.22 | 86.95 |
| AP SW | 6 | 2,210.00 | 94.17 | 223,288.00 | APRON | 60.33 | 15.55 | 65.42 |
| RW 11-29 | 7 | 16,902.00 | 60.71 | 1,159,928.00 | RUNWAY | 71.43 | 10.18 | 72.28 |
| RW 7-25 | 1 | 4,000.00 | 80.00 | 415,800.00 | RUNWAY | 89.00 | 0.00 | 89.00 |
| TL T-HANG | 1 | 1,800.00 | 20.00 | 52,426.00 | TAXILANE | 63.00 | 0.00 | 63.00 |
| TW A | 17 | 7,458.00 | 46.24 | 377,007.00 | TAXIWAY | 65.41 | 17.55 | 65.55 |
| TW B | 5 | 3,691.00 | 46.00 | 175,981.00 | TAXIWAY | 80.00 | 13.86 | 85.67 |
| TW C | 4 | 2,950.00 | 60.00 | 194,994.00 | TAXIWAY | 76.50 | 10.23 | 73.76 |
| TW CONN | 2 | 400.00 | 100.00 | 37,129.00 | TAXIWAY | 82.50 | 3.50 | 84.41 |
| TW CONN | 1 | 300.00 | 205.00 | 65,848.00 | TAXIWAY | 91.00 | 0.00 | 91.00 |
| TW D | 1 | 358.00 | 50.00 | 20,831.00 | TAXIWAY | 80.00 | 0.00 | 80.00 |
| TW E | 2 | 7,475.00 | 75.00 | 566,967.00 | TAXIWAY | 87.50 | 1.50 | 86.40 |
| TW E1 | 2 | 300.00 | 96.00 | 35,239.00 | TAXIWAY | 77.50 | 12.50 | 75.87 |
| TW E2 | 2 | 305.00 | 106.00 | 35,115.00 | TAXIWAY | 82.00 | 9.00 | 81.05 |
| TW E3 | 2 | 250.00 | 156.00 | 49,555.00 | TAXIWAY | 79.00 | 10.00 | 77.42 |
| TW E4 | 2 | 287.00 | 134.00 | 46,534.00 | TAXIWAY | 78.00 | 12.00 | 75.01 |
| TW E5 | 2 | 290.00 | 72.50 | 29,163.00 | TAXIWAY | 84.00 | 7.00 | 81.70 |

| 8/23/2019 | Branch Condition Report | Page 2 of 2 |
|-----------|-------------------------|-------------|
| | Pavement Database: FDOT | |

| Use Category | Number of Sections | Total Area (SqFt) | Arithmetic Average PCI | Average STD PCI | Weighted Average PCI |
|--------------|--------------------|-------------------|---------------------------|-----------------|-------------------------|
| APRON | 31 | 1,712,828.00 | 71.55 | 13.89 | 73.91 |
| RUNWAY | 8 | 1,575,728.00 | 73.63 | 11.16 | 76.69 |
| TAXILANE | 1 | 52,426.00 | 63.00 | 0.00 | 63.00 |
| TAXIWAY | 42 | 1,634,363.00 | 74.52 | 15.75 | 79.04 |
| ALL | 82 | 4,975,345.00 | 73.17 | 14.68 | 76.36 |

| Pavement Database: FDOT | NetworkId: GNV |
|-------------------------|----------------|
|-------------------------|----------------|

| r avement Data | | | | | 1,00,, | voi kiu. | 01 17 | | | |
|----------------|------------|---------------------|---------|----------|--------|----------|---------------------|----------------------------|--------------------------|----------|
| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspec tion | PCI |
| AP N | 4203 | 7/1/2010 | AAC | APRON | Р | 0 | 23,039.00 | 4/10/2019 | 9 | 64 |
| AP N | 4205 | 7/1/2010 | AAC | APRON | Р | 0 | 189,798.00 | 4/10/2019 | 9 | 72 |
| AP N | 4210 | 7/1/2010 | APC | APRON | Р | 0 | 49,872.00 | 4/10/2019 | 9 | 62 |
| AP N | 4215 | 7/1/2010 | APC | APRON | Р | 0 | 76,639.00 | 4/10/2019 | 9 | 82 |
| AP N | 4220 | 7/1/2010 | APC | APRON | Р | 0 | 53,200.00 | 4/10/2019 | 9 | 46 |
| AP N | 4222 | 7/1/2010 | AAC | APRON | Р | 0 | 13,199.00 | 4/10/2019 | 9 | 66 |
| AP N | 4226 | 7/1/2010 | AAC | APRON | P | 0 | 97,393.00 | 4/10/2019 | 9 | |
| AP N | 4228 | 7/1/2010 | AAC | APRON | P | 0 | 14,420.00 | 4/10/2019 | 9 | |
| AP N | 4230 | 7/1/2010 | AAC | APRON | P | 0 | 36,283.00 | | 9 | 77 |
| AP N | 4240 | 7/1/2010 | AAC | APRON | P | 0 | 130,329.00 | | 9 | 70 |
| AP N | 4241 | 7/1/2010 | AAC | APRON | Р | 0 | 21,600.00 | 4/10/2019 | 9 | 76 |
| AP N | 4245 | 7/1/2010 | AAC | APRON | P | 0 | 15,617.00 | 4/10/2019 | 9 | 70 |
| AP N | 4250 | 7/1/2010 | AAC | APRON | P | 0 | 145,100.00 | 4/10/2019 | 9 | |
| AP N | 4255 | 7/1/2010 | AAC | APRON | Р | 0 | 125,665.00 | 4/10/2019 | 9 | |
| AP N | | | | | Р | | 104,561.00 | | 9 | 74 |
| | 4260 | 7/1/2010 | AAC | APRON | | 0 | - | 4/10/2019 | | |
| AP N | 4270 | 7/1/2010 | AC | APRON | P P | 0 | 32,960.00 | 4/10/2019 | 9 | |
| AP RU 25 | 5105 | 7/1/2009 | AAC | APRON | | 0 | 9,793.00 | 4/10/2019 | 10 | |
| AP RU 7 | 5205 | 1/1/1980 | AC | APRON | P | 0 | 7,974.00 | | 39 | |
| AP S | 4105 | 7/1/2009 | AAC | APRON | P P | 0 | 66,500.00 | 4/10/2019 | 10 | 75 88 |
| AP S | 4110 | 1/1/1978 | PCC | APRON | | 0 | 126,000.00 | 4/10/2019 | 41 | |
| AP S | 4115 | 1/1/1978 | PCC | APRON | Р | 0 | 35,000.00 | | 41 | 84 |
| AP S | 4120 | 7/1/2009 | AAC | APRON | Р | 0 | 12,825.00 | 4/10/2019 | 10 | 86 |
| AP S | 4125 | 7/1/2009 | AAC | APRON | P | 0 | 22,290.00 | 4/10/2019 | 10 | 80 |
| AP S | 4130 | 7/1/2009 | AAC | APRON | P | 0 | 8,760.00 | 4/10/2019 | 10 | 88 |
| AP S | 4135 | 1/1/2016 | PCC | APRON | Р | 0 | 70,723.00 | 4/10/2019 | 3 | |
| AP SW | 4305 | 1/1/2005 | AAC | APRON | Р | 0 | 32,431.00 | 4/10/2019 | 14 | |
| AP SW | 4310 | 12/25/1999 | AC | APRON | Р | 0 | 12,201.00 | 4/10/2019 | 20 | |
| AP SW | 4315 | 12/25/1999 | AC | APRON | Р | 0 | 23,585.00 | 4/10/2019 | 20 | 55 |
| AP SW | 4320 | 7/1/2010 | AAC | APRON | Р | 0 | 21,340.00 | 4/10/2019 | 9 | 73 |
| AP SW | 4325 | 7/1/2010 | AC | APRON | Р | 0 | 72,728.00 | 4/10/2019 | 9 | 64 |
| AP SW | 4330 | 1/1/2009 | AC | APRON | Р | 0 | 61,003.00 | 4/10/2019 | 10 | 76 |
| RW 11-29 | 6201 | 1/1/2015 | AAC | RUNWAY | Р | 0 | 12,282.00 | 4/10/2019 | 4 | 88 |
| RW 11-29 | 6202 | 2/1/2005 | AAC | RUNWAY | Р | 0 | 34,697.00 | 4/10/2019 | 14 | 52 |
| RW 11-29 | 6205 | 2/1/2005 | AAC | RUNWAY | Р | 0 | 630,300.00 | 4/10/2019 | 14 | 72 |
| RW 11-29 | 6207 | 2/1/2005 | AAC | RUNWAY | Р | 0 | 17,349.00 | 4/10/2019 | 14 | 70 |
| RW 11-29 | 6210 | 2/1/2005 | AAC | RUNWAY | Р | 0 | 315,150.00 | 4/10/2019 | 14 | 76 |
| RW 11-29 | 6225 | 2/1/2005 | AAC | RUNWAY | Р | 0 | 100,100.00 | 4/10/2019 | 14 | 66 |
| RW 11-29 | 6230 | 2/1/2005 | AAC | RUNWAY | Р | 0 | 50,050.00 | | 14 | |
| RW 7-25 | 6105 | 9/1/2015 | AAC | RUNWAY | S | 0 | 415,800.00 | 4/10/2019 | 4 | 89 |
| TL T-HANG | 3105 | 7/1/2009 | AAC | TAXILANE | Р | 0 | 52,426.00 | 4/10/2019 | 10 | 63 |
| TW A | 104 | 1/1/2015 | AAC | TAXIWAY | Р | 0 | 13,820.00 | 4/10/2019 | 4 | 89 |
| TW A | 105 | 1/1/1973 | AAC | TAXIWAY | Р | 0 | 80,019.00 | 4/10/2019 | 46 | 30 |
| TW A | 108 | 1/1/2005 | AAC | TAXIWAY | Р | 0 | 6,264.00 | | 14 | |
| TW A | 110 | 1/1/2012 | AAC | TAXIWAY | Р | 0 | 50,240.00 | | 7 | |
| TW A | 115 | 7/1/2009 | AAC | TAXIWAY | P | 0 | 22,645.00 | | 10 | |
| TW A | 117 | 7/1/2009 | AAC | TAXIWAY | P | 0 | 9,679.00 | | 10 | |
| TW A | 119 | 7/1/2009 | AAC | TAXIWAY | P | 0 | 4,962.00 | | 10 | |
| TW A | 120 | 1/1/2012 | AAC | TAXIWAY | P | 0 | 98,695.00 | | 7 | |
| TW A | 130 | 1/1/1979 | AC | TAXIWAY | P | 0 | 11,380.00 | | 40 | |
| TW A | 135 | 1/1/1980 | AC | TAXIWAY | P | 0 | 20,258.00 | | 39 | |
| TW A | 140 | 1/1/1980 | | TAXIWAY | Р | 0 | | 4/10/2019 | 27 | |
| liw v | 170 | 1/1/1992 | 1 70 | LIVVIVI | I '- | ı | 52,505.00 | 4/10/2019 | 21 | 31 |

| 8/23/2019 | | Section | Section Condition Report | | | | | | | |
|-----------|-----|----------|--------------------------|---------|---|---|------------|-----------|----|----|
| TW A | 143 | 1/1/1992 | AC | TAXIWAY | Р | 0 | 5,547.00 | 4/10/2019 | 27 | 46 |
| TW A | 147 | 1/1/1980 | AC | TAXIWAY | Р | 0 | 3,947.00 | 4/10/2019 | 39 | 58 |
| TW A | 149 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 4,225.00 | 4/10/2019 | 10 | 68 |
| TW A | 152 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 3,939.00 | 4/10/2019 | 10 | 85 |
| TW A | 153 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 4,523.00 | 4/10/2019 | 10 | 82 |
| TW A | 154 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 4,561.00 | 4/10/2019 | 10 | 53 |
| TW B | 203 | 1/1/2015 | AAC | TAXIWAY | Р | 0 | 8,026.00 | 4/10/2019 | 4 | 90 |
| TW B | 205 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 129,976.00 | 4/10/2019 | 10 | 89 |
| TW B | 206 | 1/1/2015 | AAC | TAXIWAY | Р | 0 | 7,137.00 | 4/10/2019 | 4 | 87 |
| TW B | 208 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 18,964.00 | 4/10/2019 | 10 | 81 |
| TW B | 210 | 1/1/2005 | AAC | TAXIWAY | Р | 0 | 11,878.00 | 4/10/2019 | 14 | 53 |
| TW C | 304 | 1/1/2015 | AAC | TAXIWAY | Р | 0 | 17,460.00 | 4/10/2019 | 4 | 89 |
| TW C | 305 | 3/1/2011 | AC | TAXIWAY | Р | 0 | 110,122.00 | 4/10/2019 | 8 | 75 |
| TW C | 307 | 7/1/2010 | AAC | TAXIWAY | Р | 0 | 44,526.00 | 4/10/2019 | 9 | 61 |
| TW C | 315 | 7/1/2010 | AAC | TAXIWAY | Р | 0 | 22,886.00 | 4/10/2019 | 9 | 81 |
| TW CONN E | 605 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 28,681.00 | 4/10/2019 | 5 | 86 |
| TW CONN E | 610 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 8,448.00 | 4/10/2019 | 10 | 79 |
| TW CONN W | 715 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 65,848.00 | 4/10/2019 | 5 | 91 |
| TW D | 410 | 7/1/2009 | AAC | TAXIWAY | Р | 0 | 20,831.00 | 4/10/2019 | 10 | 80 |
| TW E | 505 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 491,892.00 | 4/10/2019 | 5 | 86 |
| TW E | 510 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 75,075.00 | 4/10/2019 | 5 | 89 |
| TW E1 | 515 | 1/1/2005 | AAC | TAXIWAY | Р | 0 | 19,914.00 | 4/10/2019 | 14 | 65 |
| TW E1 | 517 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 15,325.00 | 4/10/2019 | 5 | 90 |
| TW E2 | 520 | 1/1/2005 | AAC | TAXIWAY | Р | 0 | 19,417.00 | 4/10/2019 | 14 | 73 |
| TW E2 | 522 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 15,698.00 | 4/10/2019 | 5 | 91 |
| TW E3 | 530 | 1/1/2005 | AAC | TAXIWAY | Р | 0 | 28,702.00 | 4/10/2019 | 14 | 69 |
| TW E3 | 532 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 20,853.00 | 4/10/2019 | 5 | 89 |
| TW E4 | 540 | 1/1/2005 | AAC | TAXIWAY | Р | 0 | 29,074.00 | 4/10/2019 | 14 | 66 |
| TW E4 | 542 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 17,460.00 | 4/10/2019 | 5 | 90 |
| TW E5 | 550 | 1/1/2005 | AAC | TAXIWAY | Р | 0 | 19,373.00 | 4/10/2019 | 14 | 77 |
| TW E5 | 552 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 9,790.00 | 4/10/2019 | 5 | 91 |

Pavement Database: FDOT

| Age Category | Average Age at Inspection | Total Area (SqFt) | Number of Sections | Arithmetic Average PCI | Standard Deviation PCI | Weighted Average PCI |
|--------------|---------------------------|-------------------|-----------------------|---------------------------|---------------------------|-------------------------|
| 03-05 | 5 | 1,285,870.00 | 16 | 89.69 | 3.08 | 88.54 |
| 06-10 | 9 | 2,016,562.00 | 41 | 73.46 | 10.40 | 74.34 |
| 11-15 | 14 | 1,314,699.00 | 14 | 68.00 | 7.45 | 71.54 |
| 16-20 | 20 | 35,786.00 | 2 | 42.00 | 13.00 | 46.14 |
| 26-30 | 27 | 37,850.00 | 2 | 41.50 | 4.50 | 38.32 |
| 36-40 | 39 | 43,559.00 | 4 | 58.00 | 5.10 | 59.03 |
| 41-50 | 43 | 241,019.00 | 3 | 67.33 | 26.45 | 68.16 |
| ALL | 13 | 4,975,345.00 | 82 | 73.17 | 14.68 | 76.36 |



Appendix B

Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation








Table B-1 Localized Maintenance and Repair Needs based on Current Condition

| Network ID | Branch ID | Section ID | Distress Code | Description | Severity | Distress Qty | Distress Unit | Percent Distress | Work Description | Work Qty | Work Unit | Unit Cost | W | ork Cost |
|------------|-----------|------------|---------------|--------------|----------|--------------|---------------|------------------|------------------------------------|----------|-----------|-----------|----|-----------|
| GNV | AP N | 4203 | 52 | RAVELING | Low | 4609.21 | SqFt | 20.0% | FDOT - SURFACE SEAL | 4609.1 | SqFt | \$ 0.55 | \$ | 2,540.00 |
| GNV | AP N | 4205 | 52 | RAVELING | Low | 37959.58 | SqFt | 20.0% | FDOT - SURFACE SEAL | 37960 | SqFt | \$ 0.55 | \$ | 20,880.00 |
| GNV | AP N | 4210 | 45 | DEPRESSION | Low | 52.96 | SqFt | 0.1% | FDOT - PATCHING - AC FULL DEPTH | 86.1 | SqFt | \$ 12.50 | \$ | 1,080.00 |
| GNV | AP N | 4210 | 52 | RAVELING | Low | 9974.38 | SqFt | 20.0% | FDOT - SURFACE SEAL | 9974.9 | SqFt | \$ 0.55 | \$ | 5,490.00 |
| GNV | AP N | 4215 | 45 | DEPRESSION | Low | 88.05 | SqFt | 0.1% | FDOT - PATCHING - AC FULL DEPTH | 130.2 | SqFt | \$ 12.50 | \$ | 1,630.00 |
| GNV | AP N | 4215 | 45 | DEPRESSION | Medium | 299.24 | SqFt | 0.4% | FDOT - PATCHING - AC FULL DEPTH | 372.4 | SqFt | \$ 12.50 | \$ | 4,670.00 |
| GNV | AP N | 4215 | 49 | OIL SPILLAGE | N/A | 340.35 | SqFt | 0.4% | FDOT - PATCHING - AC PARTIAL DEPTH | 418.7 | SqFt | \$ 5.50 | \$ | 2,310.00 |
| GNV | AP N | 4215 | 52 | RAVELING | Low | 7393.95 | SqFt | 9.7% | FDOT - SURFACE SEAL | 7393.7 | SqFt | \$ 0.55 | \$ | 4,070.00 |
| GNV | AP N | 4220 | 41 | ALLIGATOR CR | Low | 968.97 | SqFt | 1.8% | FDOT - PATCHING - AC FULL DEPTH | 1097.9 | SqFt | \$ 12.50 | \$ | 13,730.00 |
| GNV | AP N | 4220 | 41 | ALLIGATOR CR | Medium | 2083.68 | SqFt | 3.9% | FDOT - PATCHING - AC FULL DEPTH | 2271.2 | SqFt | \$ 12.50 | \$ | 28,400.00 |
| GNV | AP N | 4220 | 45 | DEPRESSION | Low | 684.05 | SqFt | 1.3% | FDOT - PATCHING - AC FULL DEPTH | 793.3 | SqFt | \$ 12.50 | \$ | 9,920.00 |
| GNV | AP N | 4220 | 52 | RAVELING | Low | 10640.02 | SqFt | 20.0% | FDOT - SURFACE SEAL | 10640.1 | SqFt | \$ 0.55 | \$ | 5,860.00 |
| GNV | AP N | 4222 | 52 | RAVELING | Low | 4339.36 | SqFt | 32.9% | FDOT - SURFACE SEAL | 4338.9 | SqFt | \$ 0.55 | \$ | 2,390.00 |
| GNV | AP N | 4226 | 52 | RAVELING | Low | 40250.35 | SqFt | 41.3% | FDOT - SURFACE SEAL | 40250.6 | SqFt | \$ 0.55 | \$ | 22,140.00 |
| GNV | AP N | 4226 | 52 | RAVELING | Medium | 37.14 | SqFt | 0.0% | FDOT - PATCHING - AC PARTIAL DEPTH | 37.7 | SqFt | \$ 5.50 | \$ | 210.00 |
| GNV | AP N | 4228 | 50 | PATCHING | Medium | 1637.62 | SqFt | 11.4% | FDOT - PATCHING - AC FULL DEPTH | 1804 | SqFt | \$ 12.50 | \$ | 22,560.00 |
| GNV | AP N | 4228 | 52 | RAVELING | Low | 12389.05 | SqFt | 85.9% | FDOT - SURFACE SEAL | 12389.3 | SqFt | \$ 0.55 | \$ | 6,820.00 |
| GNV | AP N | 4230 | 52 | RAVELING | Low | 7256.6 | SqFt | 20.0% | FDOT - SURFACE SEAL | 7257 | SqFt | \$ 0.55 | \$ | 4,000.00 |
| GNV | AP N | 4240 | 45 | DEPRESSION | Low | 34.88 | SqFt | 0.0% | FDOT - PATCHING - AC FULL DEPTH | 62.4 | SqFt | \$ 12.50 | \$ | 790.00 |
| GNV | AP N | 4240 | 52 | RAVELING | Low | 21767.96 | SqFt | 16.7% | FDOT - SURFACE SEAL | 21767.9 | SqFt | \$ 0.55 | \$ | 11,980.00 |
| GNV | AP N | 4241 | 45 | DEPRESSION | Low | 21.64 | SqFt | 0.1% | FDOT - PATCHING - AC FULL DEPTH | 44.1 | SqFt | \$ 12.50 | \$ | 560.00 |
| GNV | AP N | 4241 | 52 | RAVELING | Low | 2700.02 | SqFt | 12.5% | FDOT - SURFACE SEAL | 2699.6 | SqFt | \$ 0.55 | \$ | 1,490.00 |
| GNV | AP N | 4245 | 48 | L & T CR | Medium | 54.33 | Ft | 0.4% | FDOT - CRACK SEALING - AC | 54.5 | Ft | \$ 3.00 | \$ | 170.00 |
| GNV | AP N | 4245 | 52 | RAVELING | Low | 2036.96 | SqFt | 13.0% | FDOT - SURFACE SEAL | 2036.5 | SqFt | \$ 0.55 | \$ | 1,130.00 |
| GNV | AP N | 4250 | 52 | RAVELING | Low | 29020.04 | SqFt | 20.0% | FDOT - SURFACE SEAL | 29019.5 | SqFt | \$ 0.55 | \$ | 15,970.00 |
| GNV | AP N | 4255 | 52 | RAVELING | Low | 54737.61 | SqFt | 43.6% | FDOT - SURFACE SEAL | 54737.7 | SqFt | \$ 0.55 | \$ | 30,110.00 |
| GNV | AP N | 4255 | 52 | RAVELING | Medium | 761.12 | SqFt | 0.6% | FDOT - PATCHING - AC PARTIAL DEPTH | 761 | SqFt | \$ 5.50 | \$ | 4,190.00 |
| GNV | AP N | 4260 | 52 | RAVELING | Low | 13491.7 | SqFt | 12.9% | FDOT - SURFACE SEAL | 13491.5 | SqFt | \$ 0.55 | \$ | 7,430.00 |
| GNV | AP N | 4270 | 45 | DEPRESSION | Low | 37.46 | SqFt | 0.1% | FDOT - PATCHING - AC FULL DEPTH | 65.7 | SqFt | \$ 12.50 | \$ | 830.00 |
| GNV | AP N | 4270 | 52 | RAVELING | Low | 3121.86 | SqFt | 9.5% | FDOT - SURFACE SEAL | 3121.5 | SqFt | \$ 0.55 | \$ | 1,720.00 |
| GNV | AP RU 25 | 5105 | 57 | WEATHERING | Medium | 489.76 | SqFt | 5.0% | FDOT - SURFACE SEAL | 489.8 | SqFt | \$ 0.55 | \$ | 270.00 |
| GNV | AP RU 7 | 5205 | 43 | BLOCK CR | Medium | 398.7 | SqFt | 5.0% | FDOT - CRACK SEALING - AC | 121.4 | Ft | \$ 3.00 | \$ | 370.00 |
| GNV | AP RU 7 | 5205 | 45 | DEPRESSION | Low | 11.73 | SqFt | 0.2% | FDOT - PATCHING - AC FULL DEPTH | 30.1 | SqFt | \$ 12.50 | \$ | 380.00 |
| GNV | AP RU 7 | 5205 | 52 | RAVELING | Low | 7974.01 | SqFt | 100.0% | FDOT - SURFACE SEAL | 7973.9 | SqFt | \$ 0.55 | \$ | 4,390.00 |
| GNV | AP S | 4105 | 57 | WEATHERING | Medium | 3324.97 | SqFt | 5.0% | FDOT - SURFACE SEAL | 3325 | SqFt | \$ 0.55 | \$ | 1,830.00 |
| GNV | AP S | 4110 | 65 | JT SEAL DMG | Low | 157.5 | Slabs | 50.0% | FDOT - JOINT SEAL - PCC | 5859.9 | Ft | \$ 2.75 | \$ | 16,120.00 |
| GNV | AP S | 4110 | 74 | JOINT SPALL | Low | 7.5 | Slabs | 2.4% | FDOT - CRACK SEALING - PCC | 12.5 | Ft | \$ 4.25 | \$ | 60.00 |
| GNV | AP S | 4110 | 75 | CORNER SPALL | Low | 7.5 | Slabs | 2.4% | FDOT - CRACK SEALING - PCC | 12.5 | Ft | \$ 4.25 | \$ | 60.00 |

Statewide Airfield Pavement
Management Program
Airport Pavement
Evaluation Report

2019





| Network ID | Branch ID | Section ID | Distress Code | Description | Severity | Distress Qty | Distress Unit | Percent Distress | Work Description | Work Qty | Work Unit | Unit Cost | V | Vork Cost |
|------------|-----------|------------|---------------|--------------|----------|--------------|---------------|------------------|-------------------------------------|----------|-----------|-----------|----|------------|
| GNV | AP S | 4110 | 75 | CORNER SPALL | Medium | 7.5 | Slabs | 2.4% | FDOT - PATCHING - PCC PARTIAL DEPTH | 20.5 | SqFt | \$ 72.00 | \$ | 1,460.00 |
| GNV | AP S | 4115 | 74 | JOINT SPALL | Low | 18.48 | Slabs | 9.5% | FDOT - CRACK SEALING - PCC | 30.2 | Ft | \$ 4.25 | \$ | 130.00 |
| GNV | AP S | 4115 | 74 | JOINT SPALL | Medium | 9.24 | Slabs | 4.8% | FDOT - PATCHING - PCC PARTIAL DEPTH | 59.2 | SqFt | \$ 72.00 | \$ | 4,300.00 |
| GNV | AP S | 4120 | 57 | WEATHERING | Medium | 1283.6 | SqFt | 10.0% | FDOT - SURFACE SEAL | 1283.1 | SqFt | \$ 0.55 | \$ | 710.00 |
| GNV | AP S | 4125 | 57 | WEATHERING | Medium | 2228.99 | SqFt | 10.0% | FDOT - SURFACE SEAL | 2229.2 | SqFt | \$ 0.55 | \$ | 1,230.00 |
| GNV | AP S | 4130 | 49 | OIL SPILLAGE | N/A | 32.83 | SqFt | 0.4% | FDOT - PATCHING - AC PARTIAL DEPTH | 60.3 | SqFt | \$ 5.50 | \$ | 330.00 |
| GNV | AP S | 4130 | 57 | WEATHERING | Medium | 437.98 | SqFt | 5.0% | FDOT - SURFACE SEAL | 438.1 | SqFt | \$ 0.55 | \$ | 250.00 |
| GNV | AP SW | 4305 | 41 | ALLIGATOR CR | Medium | 197.41 | SqFt | 0.6% | FDOT - PATCHING - AC FULL DEPTH | 258.3 | SqFt | \$ 12.50 | \$ | 3,230.00 |
| GNV | AP SW | 4305 | 57 | WEATHERING | Medium | 32431.02 | SqFt | 100.0% | FDOT - SURFACE SEAL | 32430.6 | SqFt | \$ 0.55 | \$ | 17,840.00 |
| GNV | AP SW | 4310 | 43 | BLOCK CR | Medium | 1220.09 | SqFt | 10.0% | FDOT - CRACK SEALING - AC | 372.1 | Ft | \$ 3.00 | \$ | 1,120.00 |
| GNV | AP SW | 4310 | 52 | RAVELING | Medium | 12201 | SqFt | 100.0% | FDOT - PATCHING - AC PARTIAL DEPTH | 12200.9 | SqFt | \$ 5.50 | \$ | 67,110.00 |
| GNV | AP SW | 4315 | 48 | L&TCR | Medium | 1415.88 | Ft | 6.0% | FDOT - CRACK SEALING - AC | 1416 | Ft | \$ 3.00 | \$ | 4,250.00 |
| GNV | AP SW | 4315 | 52 | RAVELING | Low | 23585.02 | SqFt | 100.0% | FDOT - SURFACE SEAL | 23584.8 | SqFt | \$ 0.55 | \$ | 12,980.00 |
| GNV | AP SW | 4325 | 57 | WEATHERING | Medium | 72727.98 | SqFt | 100.0% | FDOT - SURFACE SEAL | 72728.5 | SqFt | \$ 0.55 | \$ | 40,010.00 |
| GNV | AP SW | 4330 | 52 | RAVELING | Low | 9151.37 | SqFt | 15.0% | FDOT - SURFACE SEAL | 9151.5 | SqFt | \$ 0.55 | \$ | 5,040.00 |
| GNV | AP SW | 4330 | 57 | WEATHERING | Medium | 51851.59 | SqFt | 85.0% | FDOT - SURFACE SEAL | 51851.9 | SqFt | \$ 0.55 | \$ | 28,520.00 |
| GNV | RW 11-29 | 6202 | 41 | ALLIGATOR CR | Low | 66.2 | SqFt | 0.2% | FDOT - PATCHING - AC FULL DEPTH | 103.3 | SqFt | \$ 12.50 | \$ | 1,290.00 |
| GNV | RW 11-29 | 6202 | 45 | DEPRESSION | Low | 3.44 | SqFt | 0.0% | FDOT - PATCHING - AC FULL DEPTH | 15.1 | SqFt | \$ 12.50 | \$ | 190.00 |
| GNV | RW 11-29 | 6202 | 46 | JET BLAST | N/A | 69.75 | SqFt | 0.2% | FDOT - PATCHING - AC PARTIAL DEPTH | 70 | SqFt | \$ 5.50 | \$ | 390.00 |
| GNV | RW 11-29 | 6202 | 52 | RAVELING | Low | 344.98 | SqFt | 1.0% | FDOT - SURFACE SEAL | 345.5 | SqFt | \$ 0.55 | \$ | 190.00 |
| GNV | RW 11-29 | 6202 | 52 | RAVELING | Medium | 6997.94 | SqFt | 20.2% | FDOT - PATCHING - AC PARTIAL DEPTH | 6997.6 | SqFt | \$ 5.50 | \$ | 38,490.00 |
| GNV | RW 11-29 | 6205 | 52 | RAVELING | Low | 155218.49 | SqFt | 24.6% | FDOT - SURFACE SEAL | 155218.8 | SqFt | \$ 0.55 | \$ | 85,380.00 |
| GNV | RW 11-29 | 6207 | 52 | RAVELING | Low | 3643.26 | SqFt | 21.0% | FDOT - SURFACE SEAL | 3643.6 | SqFt | \$ 0.55 | \$ | 2,010.00 |
| GNV | RW 11-29 | 6207 | 57 | WEATHERING | Medium | 1370.57 | SqFt | 7.9% | FDOT - SURFACE SEAL | 1370.3 | SqFt | \$ 0.55 | \$ | 760.00 |
| GNV | RW 11-29 | 6210 | 52 | RAVELING | Low | 1512.76 | SqFt | 0.5% | FDOT - SURFACE SEAL | 1512.3 | SqFt | \$ 0.55 | \$ | 840.00 |
| GNV | RW 11-29 | 6210 | 57 | WEATHERING | Medium | 18077.02 | SqFt | 5.7% | FDOT - SURFACE SEAL | 18076.9 | SqFt | \$ 0.55 | \$ | 9,950.00 |
| GNV | RW 11-29 | 6225 | 45 | DEPRESSION | Low | 3.98 | SqFt | #VALUE! | FDOT - PATCHING - AC FULL DEPTH | 16.2 | SqFt | \$ 12.50 | \$ | 200.00 |
| GNV | RW 11-29 | 6225 | 52 | RAVELING | Low | 18128.36 | SqFt | 18.1% | FDOT - SURFACE SEAL | 18128.6 | SqFt | \$ 0.55 | \$ | 9,980.00 |
| GNV | RW 11-29 | 6225 | 52 | RAVELING | Medium | 3940.99 | SqFt | 3.9% | FDOT - PATCHING - AC PARTIAL DEPTH | 3940.7 | SqFt | \$ 5.50 | \$ | 21,680.00 |
| GNV | RW 11-29 | 6225 | 57 | WEATHERING | Medium | 11822.86 | SqFt | 11.8% | FDOT - SURFACE SEAL | 11823.1 | SqFt | \$ 0.55 | \$ | 6,510.00 |
| GNV | RW 11-29 | 6230 | 57 | WEATHERING | Medium | 5057.1 | SqFt | 10.1% | FDOT - SURFACE SEAL | 5056.9 | SqFt | \$ 0.55 | \$ | 2,790.00 |
| GNV | TL T-HANG | 3105 | 52 | RAVELING | Low | 24659.37 | SqFt | 47.0% | FDOT - SURFACE SEAL | 24659 | SqFt | \$ 0.55 | \$ | 13,570.00 |
| GNV | TW A | 105 | 41 | ALLIGATOR CR | Low | 795.78 | SqFt | 1.0% | FDOT - PATCHING - AC FULL DEPTH | 913.9 | SqFt | \$ 12.50 | \$ | 11,420.00 |
| GNV | TW A | 105 | 52 | RAVELING | Low | 6620.99 | SqFt | 8.3% | FDOT - SURFACE SEAL | 6620.9 | SqFt | \$ 0.55 | \$ | 3,650.00 |
| GNV | TW A | 105 | 52 | RAVELING | Medium | 73387.48 | SqFt | 91.7% | FDOT - PATCHING - AC PARTIAL DEPTH | 73387.3 | SqFt | \$ 5.50 | \$ | 403,640.00 |
| GNV | TW A | 108 | 57 | WEATHERING | Medium | 6263.95 | SqFt | 100.0% | FDOT - SURFACE SEAL | 6263.5 | SqFt | \$ 0.55 | \$ | 3,450.00 |
| GNV | TW A | 110 | 57 | WEATHERING | Medium | 502.35 | SqFt | 1.0% | FDOT - SURFACE SEAL | 502.7 | SqFt | \$ 0.55 | \$ | 280.00 |
| GNV | TW A | 115 | 48 | L&TCR | Medium | 90.29 | Ft | 0.4% | FDOT - CRACK SEALING - AC | 90.2 | Ft | \$ 3.00 | \$ | 280.00 |
| GNV | TW A | 115 | 52 | RAVELING | Low | 22645.01 | SqFt | 100.0% | FDOT - SURFACE SEAL | 22645.1 | SqFt | \$ 0.55 | \$ | 12,460.00 |

Statewide Airfield Pavement
Management Program
Airport Pavement
Evaluation Report

2019





| Network ID | Branch ID | Section ID | Distress Code | Description | Severity | Distress Qty | Distress Unit | Percent Distress | Work Description | Work Qty | Work Unit | Uni | t Cost | V | Vork Cost |
|------------|-----------|------------|---------------|-------------|----------|--------------|---------------|------------------|------------------------------------|----------|-----------|-----|--------|----|------------|
| GNV | TW A | 117 | 52 | RAVELING | Low | 9679.02 | SqFt | 100.0% | FDOT - SURFACE SEAL | 9678.9 | SqFt | \$ | 0.55 | \$ | 5,330.00 |
| GNV | TW A | 119 | 52 | RAVELING | Low | 4874.01 | SqFt | 98.2% | FDOT - SURFACE SEAL | 4873.9 | SqFt | \$ | 0.55 | \$ | 2,690.00 |
| GNV | TW A | 130 | 52 | RAVELING | Low | 9104.01 | SqFt | 80.0% | FDOT - SURFACE SEAL | 9104.1 | SqFt | \$ | 0.55 | \$ | 5,010.00 |
| GNV | TW A | 135 | 52 | RAVELING | Low | 19245.12 | SqFt | 95.0% | FDOT - SURFACE SEAL | 19244.8 | SqFt | \$ | 0.55 | \$ | 10,590.00 |
| GNV | TW A | 135 | 52 | RAVELING | Medium | 1012.88 | SqFt | 5.0% | FDOT - PATCHING - AC PARTIAL DEPTH | 1012.9 | SqFt | \$ | 5.50 | \$ | 5,580.00 |
| GNV | TW A | 140 | 52 | RAVELING | Low | 1845.9 | SqFt | 5.7% | FDOT - SURFACE SEAL | 1846 | SqFt | \$ | 0.55 | \$ | 1,020.00 |
| GNV | TW A | 140 | 57 | WEATHERING | Medium | 8767.96 | SqFt | 27.1% | FDOT - SURFACE SEAL | 8768.3 | SqFt | \$ | 0.55 | \$ | 4,830.00 |
| GNV | TW A | 140 | 57 | WEATHERING | High | 21689.17 | SqFt | 67.1% | FDOT - PATCHING - AC PARTIAL DEPTH | 21689.3 | SqFt | \$ | 5.50 | \$ | 119,300.00 |
| GNV | TW A | 143 | 52 | RAVELING | Low | 2797 | SqFt | 50.4% | FDOT - SURFACE SEAL | 2796.5 | SqFt | \$ | 0.55 | \$ | 1,540.00 |
| GNV | TW A | 143 | 52 | RAVELING | Medium | 2749.96 | SqFt | 49.6% | FDOT - PATCHING - AC PARTIAL DEPTH | 2750.2 | SqFt | \$ | 5.50 | \$ | 15,130.00 |
| GNV | TW A | 147 | 52 | RAVELING | Low | 196.98 | SqFt | 5.0% | FDOT - SURFACE SEAL | 197 | SqFt | \$ | 0.55 | \$ | 110.00 |
| GNV | TW A | 149 | 52 | RAVELING | Low | 210.97 | SqFt | 5.0% | FDOT - SURFACE SEAL | 211 | SqFt | \$ | 0.55 | \$ | 120.00 |
| GNV | TW A | 152 | 52 | RAVELING | Low | 393.96 | SqFt | 10.0% | FDOT - SURFACE SEAL | 394 | SqFt | \$ | 0.55 | \$ | 220.00 |
| GNV | TW A | 153 | 52 | RAVELING | Low | 226.04 | SqFt | 5.0% | FDOT - SURFACE SEAL | 226 | SqFt | \$ | 0.55 | \$ | 130.00 |
| GNV | TW A | 154 | 45 | DEPRESSION | Low | 6.03 | SqFt | 0.1% | FDOT - PATCHING - AC FULL DEPTH | 19.4 | SqFt | \$ | 12.50 | \$ | 250.00 |
| GNV | TW A | 154 | 48 | L&TCR | Medium | 20.01 | Ft | 0.4% | FDOT - CRACK SEALING - AC | 20 | Ft | \$ | 3.00 | \$ | 60.00 |
| GNV | TW A | 154 | 52 | RAVELING | Low | 4560.99 | SqFt | 100.0% | FDOT - SURFACE SEAL | 4560.7 | SqFt | \$ | 0.55 | \$ | 2,510.00 |
| GNV | TW B | 208 | 57 | WEATHERING | Medium | 1325.36 | SqFt | 7.0% | FDOT - SURFACE SEAL | 1325 | SqFt | \$ | 0.55 | \$ | 730.00 |
| GNV | TW B | 210 | 48 | L&TCR | Medium | 59.84 | Ft | 0.5% | FDOT - CRACK SEALING - AC | 59.7 | Ft | \$ | 3.00 | \$ | 180.00 |
| GNV | TW B | 210 | 52 | RAVELING | Low | 237.56 | SqFt | 2.0% | FDOT - SURFACE SEAL | 237.9 | SqFt | \$ | 0.55 | \$ | 140.00 |
| GNV | TW C | 305 | 52 | RAVELING | Low | 1468.31 | SqFt | 1.3% | FDOT - SURFACE SEAL | 1468.2 | SqFt | \$ | 0.55 | \$ | 810.00 |
| GNV | TW C | 307 | 48 | L&TCR | Medium | 51.8 | Ft | 0.1% | FDOT - CRACK SEALING - AC | 51.8 | Ft | \$ | 3.00 | \$ | 160.00 |
| GNV | TW C | 307 | 52 | RAVELING | Low | 44525.99 | SqFt | 100.0% | FDOT - SURFACE SEAL | 44526 | SqFt | \$ | 0.55 | \$ | 24,490.00 |
| GNV | TW C | 315 | 52 | RAVELING | Low | 457.68 | SqFt | 2.0% | FDOT - SURFACE SEAL | 457.5 | SqFt | \$ | 0.55 | \$ | 260.00 |
| GNV | TW CONN E | 610 | 57 | WEATHERING | Medium | 421.62 | SqFt | 5.0% | FDOT - SURFACE SEAL | 422 | SqFt | \$ | 0.55 | \$ | 240.00 |
| GNV | TW D | 410 | 52 | RAVELING | Medium | 1041.52 | SqFt | 5.0% | FDOT - PATCHING - AC PARTIAL DEPTH | 1042 | SqFt | \$ | 5.50 | \$ | 5,730.00 |
| GNV | TW E1 | 515 | 52 | RAVELING | Low | 180.4 | SqFt | 0.9% | FDOT - SURFACE SEAL | 180.8 | SqFt | \$ | 0.55 | \$ | 100.00 |
| GNV | TW E2 | 520 | 57 | WEATHERING | Medium | 972.63 | SqFt | 5.0% | FDOT - SURFACE SEAL | 973.1 | SqFt | \$ | 0.55 | \$ | 540.00 |
| GNV | TW E3 | 530 | 57 | WEATHERING | Medium | 1437.84 | SqFt | 5.0% | FDOT - SURFACE SEAL | 1438.1 | SqFt | \$ | 0.55 | \$ | 800.00 |
| GNV | TW E4 | 540 | 52 | RAVELING | Low | 8760.53 | SqFt | 30.1% | FDOT - SURFACE SEAL | 8760.8 | SqFt | \$ | 0.55 | \$ | 4,820.00 |
| GNV | TW E5 | 550 | 57 | WEATHERING | Medium | 1937.29 | SqFt | 10.0% | FDOT - SURFACE SEAL | 1937.5 | SqFt | \$ | 0.55 | \$ | 1,070.00 |





Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost |
|--------------|------------|-----------|------------|---------|-----------|------------|---------------------|-----------------|
| 2020 | GNV | AP N | 4203 | AAC | 23,039 | 63 | AC Restoration | \$ 254,000.00 |
| 2020 | GNV | AP N | 4210 | APC | 49,872 | 61 | AC Restoration | \$ 549,000.00 |
| 2020 | GNV | AP N | 4220 | APC | 53,200 | 43 | AC Restoration | \$ 695,000.00 |
| 2020 | GNV | AP N | 4222 | AAC | 13,199 | 64 | AC Restoration | \$ 146,000.00 |
| 2020 | GNV | AP N | 4228 | AAC | 14,420 | 56 | AC Restoration | \$ 159,000.00 |
| 2020 | GNV | AP RU 7 | 5205 | AC | 7,974 | 48 | AC Restoration | \$ 91,000.00 |
| 2020 | GNV | AP SW | 4305 | AAC | 32,431 | 63 | AC Restoration | \$ 357,000.00 |
| 2020 | GNV | AP SW | 4310 | AC | 12,201 | 27 | AC Reconstruction | \$ 171,000.00 |
| 2020 | GNV | AP SW | 4315 | AC | 23,585 | 53 | AC Restoration | \$ 260,000.00 |
| 2020 | GNV | AP SW | 4325 | AC | 72,728 | 62 | AC Restoration | \$ 800,000.00 |
| 2020 | GNV | RW 11-29 | 6202 | AAC | 34,697 | 51 | AC Restoration | \$ 382,000.00 |
| 2020 | GNV | RW 11-29 | 6225 | AAC | 100,100 | 63 | AC Restoration | \$ 1,102,000.00 |
| 2020 | GNV | TL T-HANG | 3105 | AAC | 52,426 | 62 | AC Restoration | \$ 577,000.00 |
| 2020 | GNV | TW A | 105 | AAC | 80,019 | 27 | AC Reconstruction | \$ 1,121,000.00 |
| 2020 | GNV | TW A | 115 | AAC | 22,645 | 59 | AC Restoration | \$ 250,000.00 |
| 2020 | GNV | TW A | 119 | AAC | 4,962 | 58 | AC Restoration | \$ 55,000.00 |
| 2020 | GNV | TW A | 130 | AC | 11,380 | 63 | AC Restoration | \$ 126,000.00 |
| 2020 | GNV | TW A | 135 | AC | 20,258 | 59 | AC Restoration | \$ 223,000.00 |
| 2020 | GNV | TW A | 140 | AC | 32,303 | 35 | AC Reconstruction | \$ 453,000.00 |
| 2020 | GNV | TW A | 143 | AC | 5,547 | 44 | AC Restoration | \$ 70,000.00 |
| 2020 | GNV | TW A | 147 | AC | 3,947 | 57 | AC Restoration | \$ 44,000.00 |
| 2020 | GNV | TW A | 154 | AAC | 4,561 | 52 | AC Restoration | \$ 51,000.00 |
| 2020 | GNV | TW B | 210 | AAC | 11,878 | 52 | AC Restoration | \$ 131,000.00 |
| 2020 | GNV | TW C | 307 | AAC | 44,526 | 60 | AC Restoration | \$ 490,000.00 |
| 2020 | GNV | TW E1 | 515 | AAC | 19,914 | 64 | AC Restoration | \$ 220,000.00 |
| 2020 | GNV | TW E4 | 540 | AAC | 29,074 | 64 | AC Restoration | \$ 320,000.00 |





| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost |
|--------------|------------|-----------|------------|---------|-----------|------------|---------------------|-----------------|
| 2022 | GNV | AP N | 4240 | AAC | 130,329 | 64 | AC Restoration | \$ 1,434,000.00 |
| 2022 | GNV | AP N | 4245 | AAC | 15,617 | 64 | AC Restoration | \$ 172,000.00 |
| 2022 | GNV | RW 11-29 | 6205 | AAC | 630,300 | 64 | AC Restoration | \$ 6,934,000.00 |
| 2022 | GNV | RW 11-29 | 6207 | AAC | 17,349 | 62 | AC Restoration | \$ 191,000.00 |
| 2022 | GNV | TW A | 117 | AAC | 9,679 | 64 | AC Restoration | \$ 107,000.00 |
| 2022 | GNV | TW A | 149 | AAC | 4,225 | 64 | AC Restoration | \$ 47,000.00 |
| 2022 | GNV | TW E3 | 530 | AAC | 28,702 | 64 | AC Restoration | \$ 316,000.00 |
| 2023 | GNV | AP N | 4205 | AAC | 189,798 | 64 | AC Restoration | \$ 2,088,000.00 |
| 2023 | GNV | AP N | 4255 | AAC | 125,665 | 64 | AC Restoration | \$ 1,383,000.00 |
| 2024 | GNV | AP N | 4226 | AAC | 97,393 | 63 | AC Restoration | \$ 1,072,000.00 |
| 2024 | GNV | AP N | 4260 | AAC | 104,561 | 64 | AC Restoration | \$ 1,151,000.00 |
| 2024 | GNV | AP S | 4105 | AAC | 66,500 | 64 | AC Restoration | \$ 732,000.00 |
| 2024 | GNV | AP SW | 4320 | AAC | 21,340 | 63 | AC Restoration | \$ 235,000.00 |
| 2024 | GNV | RW 11-29 | 6210 | AAC | 315,150 | 64 | AC Restoration | \$ 3,467,000.00 |
| 2024 | GNV | RW 11-29 | 6230 | AAC | 50,050 | 64 | AC Restoration | \$ 551,000.00 |
| 2024 | GNV | TW A | 108 | AAC | 6,264 | 64 | AC Restoration | \$ 69,000.00 |
| 2025 | GNV | AP N | 4230 | AAC | 36,283 | 64 | AC Restoration | \$ 400,000.00 |
| 2025 | GNV | AP N | 4241 | AAC | 21,600 | 63 | AC Restoration | \$ 238,000.00 |
| 2025 | GNV | AP N | 4250 | AAC | 145,100 | 64 | AC Restoration | \$ 1,597,000.00 |
| 2025 | GNV | TW E2 | 520 | AAC | 19,417 | 63 | AC Restoration | \$ 214,000.00 |
| 2026 | GNV | AP S | 4125 | AAC | 22,290 | 64 | AC Restoration | \$ 246,000.00 |
| 2027 | GNV | AP N | 4215 | APC | 76,639 | 64 | AC Restoration | \$ 844,000.00 |
| 2027 | GNV | AP SW | 4330 | AC | 61,003 | 63 | AC Restoration | \$ 672,000.00 |
| 2027 | GNV | TW E5 | 550 | AAC | 19,373 | 63 | AC Restoration | \$ 214,000.00 |
| 2028 | GNV | AP S | 4120 | AAC | 12,825 | 64 | AC Restoration | \$ 142,000.00 |
| 2028 | GNV | TW CONN E | 610 | AAC | 8,448 | 63 | AC Restoration | \$ 93,000.00 |
| 2028 | GNV | TW D | 410 | AAC | 20,831 | 64 | AC Restoration | \$ 230,000.00 |

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019






| Program Year Network ID | | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost |
|-------------------------|-----|-----------|------------|---------|-----------|------------|---------------------|---------------|
| 2029 | GNV | AP N | 4270 | AC | 32,960 | 63 | AC Restoration | \$ 363,000.00 |
| 2029 | GNV | AP RU 25 | 5105 | AAC | 9,793 | 63 | AC Restoration | \$ 108,000.00 |
| 2029 | GNV | AP S | 4130 | AAC | 8,760 | 64 | AC Restoration | \$ 97,000.00 |
| 2029 | GNV | TW A | 153 | AAC | 4,523 | 64 | AC Restoration | \$ 50,000.00 |
| 2029 | GNV | TW B | 208 | AAC | 18,964 | 63 | AC Restoration | \$ 209,000.00 |
| 2029 | GNV | TW C | 315 | AAC | 22,886 | 63 | AC Restoration | \$ 252,000.00 |




Appendix C

Technical Exhibits









APS












Appendix D

Inspection Photograph Documentation









RW 7-25, Section 6105, Sample Unit 543 - Low Severity (48) Longitudinal & Transverse Cracking and Low Severity (57) Weathering



RW 7-25, Section 6105, Sample Unit 574 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (56) Swelling, and Low Severity (57) Weathering







RW 11-29, Section 6202, Sample Unit 298 - (46) Jet Blast Erosion, Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering



RW 11-29, Section 6225, Sample Unit 440 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, Low Severity (57) Weathering







TW A, Section 105, Sample Unit 109 - Low Severity (41) Alligator Cracking, Low Severity (48) Longitudinal & Transverse Cracking, and Medium Severity (52) Raveling



TW E, Section 505, Sample Unit 559 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (56) Swelling, and Low Severity (57) Weathering







AP N, Section 4220, Sample Unit 109 - Medium Severity (41) Alligator Cracking, Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering




AP S, Section 4105, Sample Unit 151 - Low Severity (47) Joint Reflection Cracking, Low Severity (48) Longitudinal & Transverse Cracking, and Low Severity (57) Weathering



Appendix E

Inspection Distress Details



Re-Inspection Report

FDOT

Page 1 of 87

| Generated | Date | | 8/23/201 | 9 | | | | | | | | Page 1 of 8/ |
|--------------|------------------|-------------|----------------|------------------|-----------------|--------------|-------|--------------|---------|-----------|------------|--------------|
| Network: | GNV | | | | Name: | GAINESVILI | E REG | IONAL AIRPOI | RT | | | |
| Branch: | AP N | | Nam | e: NORT | H APRONS | Use | e: AF | PRON | Area: | 1,129,67 | 5 SqFt | |
| Section: | 4203 | | of 16 | From: | - | | | То: - | | La | st Const.: | 7/1/2010 |
| Surface: | AAC | Family: | C9N59-P | R-AP-AAC-APC | Zone: | | | Category: | | Ra | nk: P | |
| Area: | | 23,039 SqFt | Len | igth: | 350 Ft | Width: | | 50 Ft | | | | |
| Slabs: | | Slab Le | ength: | Ft | Slab V | Vidth: | | Ft | Joint 1 | Length: | F | ft |
| Shoulder: | | Street 7 | Гуре: | | Grade | e: 0 | | | Lanes | : 0 | | |
| Section Con | mments: | | | | | | | | | | | |
| Work Date | : 1/1/1972 | . v | Vork Type: | BUILT | | | Code: | IMPORTED | Is | Major M&R | : True | |
| Work Date | : 1/1/2002 | . v | Vork Type: | Cold Milling | | | Code: | MI-CO | Is | Major M&R | : False | |
| Work Date | : 1/1/2002 | . v | Vork Type: | Overlay - AC Str | ructural | | Code: | OL-AS | Is | Major M&R | : True | |
| Work Date | : 7/1/2010 | v | Vork Type: | Mill and Overlay | 7 | | Code: | ML-OL | Is | Major M&R | : True | |
| Work Date | : 7/2/2010 | v | Vork Type: | Surface Treatme | nt - Double Bit | um. | Code: | SU-DB | Is | Major M&R | : False | |
| Last Insp. l | Date: 4/1 | 0/2019 | T | otalSamples: | 4 | Surve | eyed: | 1 | | | | |
| Conditions | : PCI: | 64 | | | | | | | | | | |
| Inspection | Comments | s: | | | | | | | | | | |
| Sample Nu | mber: 50 | 00 Ty | y pe: R | . A | rea: | 6738.00 SqFt | | PCI: 64 | | | | |
| Sample Co | mments: | | | | | | | | | | | |
| 48 L& | T CR | | L | 481.00 | Ft | | | | | | | |
| 52 RAV | VELING | | L | 1348.00 | SqFt | | | | | | | |
| | ATHERIN | G | L | 5390.00 | SqFt | | | | | | | |
| 43 BLC | OCK CR | | L | 1344.00 | | | | | | | | |

| Netwo | ork: GNV | | | | | Nam | e: GA | INESVILL | E REG | IONAL AIR | PORT | | | |
|----------|------------------------|-----------|--------|------------|------------------|----------|-------------|-----------|-------|-----------|------|---------------|--------------|----------|
| Branc | ch: AP N | | N | ame: | NORTI | H APRO | ONS | Use | : AI | PRON | Are | a: 1,1 | 29,675 SqFt | |
| Sectio | on: 4205 | 0 | f 16 | F | rom: - | | | | | То: - | | | Last Const.: | 7/1/2010 |
| Surfa | ce: AAC | Family: | C9N5 | 9-PR-AP- | -AAC-APC | Zone | : | | | Category: | | | Rank: P | |
| Area: | 189 | ,798 SqFt |] | Length: | | 500 Ft | | Width: | | 350 Ft | t | | | |
| Slabs | : | Slab Len | gth: | | Ft | | Slab Width: | | | Ft | | Joint Length: | F | t |
| Shoul | der: | Street T | ype: | | | | Grade: 0 | | | | | Lanes: 0 | | |
| Sectio | on Comments: | | | | | | | | | | | | | |
| Work | Date: 1/1/1981 | W | ork Ty | pe: BUIL | T | | | | Code: | IMPORTE | ED | Is Major I | M&R: True | |
| Work | Date: 1/1/2002 | W | ork Ty | pe: Cold | Milling | | | | Code: | MI-CO | | Is Major I | M&R: False | |
| Work | Date: 1/1/2002 | W | ork Ty | pe: Overl | ay - AC Str | uctural | | | Code: | OL-AS | | Is Major I | M&R: True | |
| Work | Date: 7/1/2010 | W | ork Ty | pe: Mill a | and Overlay | | | | Code: | ML-OL | | Is Major I | M&R: True | |
| Work | Date: 7/2/2010 | W | ork Ty | pe: Surfac | ce Treatmer | nt - Dou | ble Bitum. | | Code: | SU-DB | | Is Major I | M&R: False | |
| Last l | Insp. Date: 4/10/2 | 019 | | TotalSa | imples: 4 | 11 | | Surve | yed: | 5 | | | | |
| Cond | itions: PCI: 7 | 2 | | | | | | | | | | | | |
| Inspe | ction Comments: | | | | | | | | | | | | | |
| Samp | le Number: 306 | Туј | oe: | R | A | rea: | 3250 | 0.00 SqFt | | PCI: | 76 | | | |
| Samp | le Comments: | | | | | | | | | | | | | |
| 52 | RAVELING | | L | | 650.00 | SaFt | | | | | | | | |
| 48 | L & T CR | | L | | 65.00 | - | | | | | | | | |
| 57 | WEATHERING | | L | | 2600.00 | SqFt | | | | | | | | |
| Samp | le Number: 353 | Тур | e: | R | A | rea: | 5000 | 0.00 SqFt | | PCI: | 72 | | | |
| Samp | le Comments: | | | | | | | | | | | | | |
| 48 | L & T CR | | L | | 344.00 | Ft | | | | | | | | |
| 52 | RAVELING | | L | | 1000.00 | | | | | | | | | |
| 57 | WEATHERING | | L | | 4000.00 | • | | | | | | | | |
| - | le Number: 407 | Тур | e: | R | A | rea: | 5000 | 0.00 SqFt | | PCI: | 76 | | | |
| Samp | le Comments: | | | | | | | | | | | | | |
| 57 | WEATHERING | | L | | 4000.00 | SqFt | | | | | | | | |
| 52 | RAVELING | | L | | 1000.00 | | | | | | | | | |
| 48 | L & T CR | | L | | 136.00 | | | | | | | | | |
| _ | le Number: 451 | Тур | e: | R | A | rea: | 5000 | 0.00 SqFt | | PCI: | 71 | | | |
| Samp | le Comments: | | | | | | | | | | | | | |
| 52 | RAVELING | | L | | 1000.00 | - | | | | | | | | |
| 48 | L & T CR | | L | | 366.00 | | | | | | | | | |
| 57 | WEATHERING | 700 | L | n | 4000.00 | | 500 | 0.00 0.5: | | D.C.T | 67 | | | |
| _ | le Number: 505 | Тур | e: | R | A | rea: | 5000 | 0.00 SqFt | | PCI: | 0/ | | | |
| samp | le Comments: | | | | | | | | | | | | | |
| 48 | L & T CR | | L | | 432.00 | | | | | | | | | |
| 52 56 | RAVELING | | L | | 1000.00 | | | | | | | | | |
| 56 57 | SWELLING WEATHERING | | L L | | 13.00 4000.00 | | | | | | | | | |
| | | | | | | | | | | | | | | |

| Network: GNV | | Name: | GAINESVILLE RE | GIONAL AIRPORT | | |
|---------------------------|----------------------|--------------------------|----------------|----------------|-------------------|-----------------|
| Branch: AP N | Name: | NORTH APRONS | Use: | APRON A | rea: 1,129,675 Sq | Ft |
| Section: 4210 | of 16 F | rom: - | | То: - | Last Co | onst.: 7/1/2010 |
| Surface: APC | Family: C9N59-PR-AP- | AAC-APC Zone: | | Category: | Rank: | P |
| Area: 49,8 | 372 SqFt Length: | 335 Ft | Width: | 130 Ft | | |
| Slabs: | Slab Length: | Ft Slab V | Width: | Ft | Joint Length: | Ft |
| Shoulder: | Street Type: | Grade | e: 0 | | Lanes: 0 | |
| Section Comments: | | | | | | |
| Work Date: 1/1/1973 | Work Type: BUIL | Γ | Code | e: IMPORTED | Is Major M&R: Tr | ue |
| Work Date: 1/1/1973 | Work Type: OVER | LAY | Code | e: IMPORTED | Is Major M&R: Tr | ue |
| Work Date: 1/1/2005 | Work Type: MILL | and OVERLAY | Code | e: ML-OV | Is Major M&R: Tr | ue |
| Work Date: 7/1/2010 | Work Type: MILL | and OVERLAY | Code | e: ML-OV | Is Major M&R: Tr | ue |
| Work Date: 7/2/2010 | Work Type: Surfac | e Treatment - Double Bir | tum. Code | e: SU-DB | Is Major M&R: Fa | lse |
| Last Insp. Date: 4/10/201 | 19 TotalSa | mples: 9 | Surveyed: | 1 | | |
| Conditions: PCI: 62 | | | | | | |
| Inspection Comments: | | | | | | |
| Sample Number: 250 | Type: R | Area: | 5650.00 SqFt | PCI: 62 | | |
| Sample Comments: | | | | | | |
| 52 RAVELING | L | 1130.00 SqFt | | | | |
| 45 DEPRESSION | L | 6.00 SqFt | | | | |
| 48 L & T CR | L | 326.00 Ft | | | | |
| 42 BLEEDING | N | 61.00 SqFt | | | | |
| 57 WEATHERING | L | 4520.00 SqFt | | | | |
| 43 BLOCK CR | L | 612.00 SqFt | | | | |

| Network: GNV | | Name: | GAINESVILLER | EGIONAL AIRPORT | | |
|---|---|--|------------------------------------|-----------------|------------|-----------------------|
| Branch: AP N | Name: | NORTH APRONS | Use: | APRON | Area: | 1,129,675 SqFt |
| Section: 4215 | of 16 I | From: - | | То: - | | Last Const.: 7/1/2010 |
| Surface: APC | Family: C9N59-PR-AP | -AAC-APC Zone: | | Category: | | Rank: P |
| Area: 76,639 | SqFt Length: | 300 Ft | Width: | 200 Ft | | |
| Slabs: | Slab Length: | Ft Slab | Width: | Ft | Joint Leng | th: Ft |
| Shoulder: | Street Type: | Grade | e: 0 | | Lanes: | 0 |
| Section Comments: | | | | | | |
| Work Date: 1/1/1942 | Work Type: New | Construction - Initial | Coo | de: NU-IN | Is Maj | or M&R: True |
| Work Date: 1/1/2002 | Work Type: Joint | Seal - Silicon | Coo | de: JS-SI | Is Maj | or M&R: False |
| Work Date: 1/1/2002 | Work Type: Slab | Replacement - PCC | Coo | de: SL-PC | Is Maj | or M&R: False |
| Work Date: 7/1/2010 | Work Type: MILI | and OVERLAY | Coo | de: ML-OV | Is Maj | or M&R: True |
| Work Date: 7/2/2010 | Work Type: Surfa | ce Treatment - Double Bi | tum Co. | de: LC-DB | Is Mai | or M&R: False |
| | J P | ee Treatment Boaste Bi | tuin. | ue. LC-DB | 18 Maj | of Max. False |
| Last Insp. Date: 4/10/2019 | | amples: 16 | Surveyed | | is Maj | of Mark. Paise |
| Last Insp. Date: 4/10/2019 | | | | | 15 Мај | or max. Paise |
| Last Insp. Date: 4/10/2019 | | | | | 15 Maj | of Max. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 | | | | | 15 (via) | of Meek. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 | TotalSa | amples: 16 | Surveyed | : 3 | 15 (viaj | of Mer. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: | TotalSa | amples: 16 | Surveyed | : 3 | 15 Maj | of Mer. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING | TotalSa | Area: | Surveyed | : 3 | 15 Maj | of Mex. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING Sample Number: 152 | TotalS: Type: R | Area: 612.00 SqFt | Surveyed 3060.00 SqFt | PCI: 86 | 15 Waj | of Meet. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING Sample Number: 152 Sample Comments: | TotalS: Type: R | Area: 612.00 SqFt Area: | Surveyed 3060.00 SqFt | PCI: 86 | 15 Maj | of Mex. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: | TotalSa Type: R L Type: R | Area: 612.00 SqFt | Surveyed 3060.00 SqFt | PCI: 86 | 15 Waj | of Mex. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING Sample Number: 152 Sample Comments: 49 OIL SPILLAGE 45 DEPRESSION | TotalSa Type: R L Type: R N M L | Area: 612.00 SqFt Area: 58.00 SqFt 51.00 SqFt 88.00 SqFt | Surveyed 3060.00 SqFt | PCI: 86 | 15 Maj | of Mex. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING Sample Number: 152 Sample Comments: 49 OIL SPILLAGE 45 DEPRESSION 52 RAVELING | TotalSa Type: R L Type: R N M | Area: 612.00 SqFt | Surveyed 3060.00 SqFt | PCI: 86 | 15 Waj | of Meek. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING Sample Number: 152 Sample Comments: 49 OIL SPILLAGE 45 DEPRESSION 52 RAVELING 45 DEPRESSION 52 RAVELING 45 DEPRESSION 53 RAVELING 54 DEPRESSION 55 RAVELING 56 DEPRESSION 57 RAVELING 58 RAVELING 59 RAVELING 50 DEPRESSION 50 Sample Number: 204 | TotalSa Type: R L Type: R N M L | Area: 612.00 SqFt Area: 58.00 SqFt 51.00 SqFt 88.00 SqFt | Surveyed 3060.00 SqFt | PCI: 86 | 15 Maj | of Meet. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING Sample Number: 152 Sample Comments: 49 OIL SPILLAGE 45 DEPRESSION 52 RAVELING 45 DEPRESSION 52 RAVELING 45 DEPRESSION 53 RAVELING 54 DEPRESSION 55 RAVELING 56 DEPRESSION 57 RAVELING 58 RAVELING 59 RAVELING 50 DEPRESSION 50 Sample Number: 204 | TotalSa Type: R L Type: R N M L L L | Area: 612.00 SqFt Area: 58.00 SqFt 51.00 SqFt 88.00 SqFt 15.00 SqFt | Surveyed 3060.00 SqFt 4400.00 SqFt | PCI: 86 | 15 Maj | of Mex. Paise |
| Last Insp. Date: 4/10/2019 Conditions: PCI: 82 Inspection Comments: Sample Number: 106 Sample Comments: 52 RAVELING Sample Number: 152 Sample Comments: 49 OIL SPILLAGE 45 DEPRESSION 52 RAVELING | TotalSa Type: R L Type: R N M L L L | Area: 612.00 SqFt Area: 58.00 SqFt 51.00 SqFt 88.00 SqFt 15.00 SqFt | Surveyed 3060.00 SqFt 4400.00 SqFt | PCI: 86 | 15 Maj | of Mex. Paise |

| Network: GNV | | Name: | GAINESVILLE R | EGIGIAIE IIIG GR | 1 |
|--|--|--|--------------------------|------------------|-----------------------------|
| Branch: AP N | Name: | NORTH APRONS | Use: | APRON | Area: 1,129,675 SqFt |
| Section: 4220 | of 16 | From: - | | То: - | Last Const.: 7/1/2010 |
| Surface: APC | Family: C9N59-PR-Al | P-AAC-APC Zone: | | Category: | Rank: P |
| Area: 53,200 | SqFt Length: | 249 Ft | Width: | 200 Ft | |
| Slabs: | Slab Length: | Ft Slal | Width: | Ft | Joint Length: Ft |
| Shoulder: | Street Type: | Gra | de: 0 | | Lanes: 0 |
| Section Comments: | | | | | |
| Work Date: 1/1/1972 | Work Type: BUI | LT | Со | de: IMPORTED | Is Major M&R: True |
| Work Date: 1/1/2002 | Work Type: Over | rlay - AC Structural | Со | de: OL-AS | Is Major M&R: True |
| Work Date: 1/1/2002 | Work Type: Cold | l Milling | Со | de: MI-CO | Is Major M&R: False |
| Work Date: 7/1/2010 | Work Type: Mill | and Overlay | Со | de: ML-OL | Is Major M&R: True |
| Work Date: 7/2/2010 | Work Type: Surf | ace Treatment - Double l | Bitum. Co | de: SU-DB | Is Major M&R: False |
| | | | | | |
| Last Insp. Date: 4/10/2019 | TotalS | Samples: 11 | Surveyed | l: 2 | |
| - | TotalS | Samples: 11 | Surveyed | l : 2 | |
| Conditions: PCI: 46 | TotalS | samples: 11 | Surveyed | 1 : 2 | |
| Conditions: PCI: 46 Inspection Comments: | TotalS Type: R | Samples: 11 Area: | Surveyed 3400.00 SqFt | PCI: 21 | |
| Conditions: PCI: 46 nspection Comments: Sample Number: 109 | | | | | |
| Conditions: PCI: 46 nspection Comments: Sample Number: 109 Sample Comments: | | Area: | | | |
| Conditions: PCI: 46 nspection Comments: Cample Number: 109 Cample Comments: | Type: R | | | | |
| Conditions: PCI: 46 nspection Comments: Cample Number: 109 Cample Comments: ALLIGATOR CR 8 L & T CR | Type: R | Area: 329.00 SqFt | | | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: ALLIGATOR CR BL & T CR C | Type: R M L | Area: 329.00 SqFt 70.00 Ft | | | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: H ALLIGATOR CR H8 L & T CR H8 L & T CR H8 | Type: R M L L L | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt | | | |
| Conditions: PCI: 46 Inspection Comments: Comple Number: 109 Comple Comments: ALLIGATOR CR BE L & T CR COMMENTE C | Type: R M L L L L L L | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt 108.00 SqFt | | | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: I ALLIGATOR CR IS L&T CR IS RAVELING IS WEATHERING IS ALLIGATOR CR IS DEPRESSION | Type: R M L L L L | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt | | | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: 1 ALLIGATOR CR 12 RAVELING 17 WEATHERING 11 ALLIGATOR CR 12 BALLIGATOR CR 13 DEPRESSION 14 DEPRESSION 15 DEPRESSION 16 PATCHING | Type: R M L L L L L L | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt 108.00 SqFt | | | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: 41 ALLIGATOR CR 48 L & T CR 52 RAVELING 57 WEATHERING 41 ALLIGATOR CR 45 DEPRESSION 50 PATCHING Sample Number: 158 | Type: R M L L L L L L L | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt 108.00 SqFt 70.00 SqFt | 3400.00 SqFt | PCI: 21 | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: H ALLIGATOR CR H L & T CR H AVELING H ALLIGATOR CR H ALLIGATOR | Type: R M L L L L L L L | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt 108.00 SqFt 70.00 SqFt | 3400.00 SqFt | PCI: 21 | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: 41 ALLIGATOR CR 48 L & T CR 52 RAVELING 57 WEATHERING 41 ALLIGATOR CR 45 DEPRESSION 50 PATCHING Sample Number: 158 Sample Comments: 41 ALLIGATOR CR | Type: R M L L L L L L L R | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt 108.00 SqFt 70.00 SqFt Area: | 3400.00 SqFt | PCI: 21 | |
| Inspection Comments: Sample Number: 109 Sample Comments: 41 ALLIGATOR CR 48 L & T CR 52 RAVELING 57 WEATHERING 41 ALLIGATOR CR 45 DEPRESSION 50 PATCHING Sample Number: 158 Sample Comments: 41 ALLIGATOR CR | Type: R M L L L L L L R | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt 108.00 SqFt 70.00 SqFt Area: | 3400.00 SqFt | PCI: 21 | |
| Conditions: PCI: 46 Inspection Comments: Sample Number: 109 Sample Comments: 41 ALLIGATOR CR 48 L & T CR 52 RAVELING 57 WEATHERING 41 ALLIGATOR CR 45 DEPRESSION 50 PATCHING Sample Number: 158 Sample Comments: 41 ALLIGATOR CR 57 WEATHERING | Type: R M L L L L L L L L L L L L L L L L L L | Area: 329.00 SqFt 70.00 Ft 680.00 SqFt 2650.00 SqFt 117.00 SqFt 108.00 SqFt 70.00 SqFt Area: 36.00 SqFt 3820.00 SqFt | 3400.00 SqFt | PCI: 21 | |

| Network: | GNV | | | | Name: | GAINESVILI | E REG | IONAL AIRPOF | RT | | | |
|------------|---------------------|------------|-----------|-------------------|-----------------|--------------|-------|--------------|-------|------------|--------------|----------|
| Branch: | AP N | | Name | e: NORT | H APRONS | Use | e: AF | PRON | Area: | 1,1 | 29,675 SqFt | |
| Section: | 4222 | C | of 16 | From: - | | | | To: - | | | Last Const.: | 7/1/2010 |
| Surface: | AAC | Family: | C9N59-P | R-AP-AAC-APC | Zone: | | | Category: | | | Rank: P | |
| Area: | 13 | 3,199 SqFt | Len | gth: | 175 Ft | Width: | | 100 Ft | | | | |
| Slabs: | | Slab Lei | ngth: | Ft | Slab V | Width: | | Ft | Join | t Length: | F | t |
| Shoulder: | | Street T | ype: | | Grade | : 0 | | | Lane | es: 0 | | |
| Section Co | omments: | | | | | | | | | | | |
| Work Date | e: 1/1/1981 | W | ork Type: | BUILT | | | Code: | IMPORTED |] | ls Major I | M&R: True | |
| Work Date | e: 1/1/2002 | W | ork Type: | Overlay - AC Str | uctural | | Code: | OL-AS |] | ls Major I | M&R: True | |
| Work Date | e: 1/1/2002 | W | ork Type: | Cold Milling | | | Code: | MI-CO |] | ls Major I | M&R: False | |
| Work Date | e: 7/1/2010 | W | ork Type: | Mill and Overlay | | | Code: | ML-OL |] | ls Major I | M&R: True | |
| Work Date | e: 7/2/2010 | W | ork Type: | Surface Treatment | nt - Double Bit | um. | Code: | SU-DB |] | ls Major I | M&R: False | |
| Last Insp. | Date: 4/10/2 | 2019 | To | otalSamples: 3 | <u> </u> | Surv | eyed: | 1 | | | | |
| Conditions | s: PCI: 6 | 66 | | | | | | | | | | |
| Inspection | Comments: | | | | | | | | | | | |
| Sample Nu | ımber: 259 | Ty | pe: R | A | rea: | 3650.00 SqFt | | PCI: 66 | | | | |
| Sample Co | omments: | | | | | | | | | | | |
| 48 L& | t T CR | | L | 81.00 | Ft | | | | | | | |
| 43 BL | OCK CR | | L | 1136.00 | SqFt | | | | | | | |
| 52 RA | VELING | | L | 1200.00 | SqFt | | | | | | | |

| Netwoi | rk: GNV | | | | | Name | GA | INESVILLI | E REG | IONAL AIR | PORT | | | | | |
|---------|----------------|-------------|-------|-------------------|----------------|------------|-------------|-----------|--------|-----------|------|---------|---------|--------------------|--------|----------|
| Branch | a: AP N | | | Name: | NORTI | I APRO | NS | Use: | AF | PRON | A | rea: | 1,1 | 29,675 S | qFt | |
| Section | ı: 4226 | | of 1 | 6 | From: - | | | | | To: - | | | | Last C | onst.: | 7/1/2010 |
| Surfac | e: AAC | Family | : C | 9N59-PR- <i>A</i> | AP-AAC-APC | Zone: | : | | | Category: | | | | Rank: | P | |
| Area: | | 97,393 SqFt | | Length | : | 120 Ft | | Width: | | 100 F | t | | | | | |
| Slabs: | | Slab I | ength | : | Ft | 5 | Slab Width: | | | Ft | | Joint I | Length: | | Ft | |
| Should | er: | Street | Type: | | | | Grade: 0 | | | | | Lanes | : 0 | | | |
| Section | Comments: | | | | | | | | | | | | | | | |
| Work l | Date: 1/1/1960 | | Work | Type: Ne | w Construction | n - Initia | 1 | | Code: | NU-IN | | Is | Major N | M&R: T | rue | |
| Work l | Date: 1/1/2002 | | Work | Type: Co | mplete Recons | truction | - AC | | Code: | CR-AC | | Is | Major N | M&R: T | rue | |
| Work l | Date: 7/1/2010 | | Work | Type: MI | LL and OVER | LAY | | | Code: | ML-OV | | Is | Major N | M&R: T | rue | |
| Work l | Date: 7/2/2010 | | Work | Type: Sur | rface Treatmen | ıt - Doul | ole Bitum. | (| Code: | SU-DB | | Is | Major N | M&R: F: | alse | |
| Last In | sp. Date: 4/10 | 0/2019 | | Total | Samples: 2 | 0 | | Survey | yed: 3 | 3 | | | | | | |
| Condit | ions: PCI: | 73 | | | | | | | | | | | | | | |
| Inspect | tion Comments | | | | | | | | | | | | | | | |
| Sample | e Number: 10 | 4 1 | ype: | R | A | rea: | 500 | 0.00 SqFt | | PCI: | 76 | | | | | |
| • | e Comments: | | . 1 | | | | | 1 | | | | | | | | |
| 57 | WEATHERING | j | | L | 4000.00 | SqFt | | | | | | | | | | |
| 48 | L & T CR | | | L | 180.00 | | | | | | | | | | | |
| 52 | RAVELING | | | L | 1000.00 | SqFt | | | | | | | | | | |
| Sample | Number: 10 | 7 1 | ype: | R | A | rea: | 460 | 5.00 SqFt | | PCI: | 76 | | | | | |
| Sample | e Comments: | | | | | | | | | | | | | | | |
| 57 | WEATHERING | j | | L | 3684.00 | SqFt | | | | | | | | | | |
| | RAVELING | | | L | 921.00 | | | | | | | | | | | |
| 48 | L & T CR | | | L | 90.00 | | | | | | | | | | | |
| Sample | e Number: 15 | r 0 | ype: | R | A | rea: | 350 | 0.00 SqFt | | PCI: | 64 | | | | | |
| Sample | e Comments: | | | | | | | | | | | | | | | |
| 48 | L & T CR | | | L | 265.00 | Ft | | | | | | | | | | |
| 52 | RAVELING | | | L | 3495.00 | SqFt | | | | | | | | | | |
| | DANELDIC | | | | | | | | | | | | | | | |

5.00 SqFt

M

52

RAVELING

| Network: | GNV | | | Name: | GAINESVILLE | REGIONAL AIRP | ORT | | |
|--------------|-------------------|---------------|----------------|---------------------------|--------------|---------------|---------|-----------------|--------------|
| Branch: | AP N | | Name: | NORTH APRONS | Use: | APRON | Area: | 1,129,675 SqFt | |
| Section: | 4228 | 0 | f 16 F | rom: - | | То: - | | Last Cons | t.: 7/1/2010 |
| Surface: | AAC | Family: | C9N59-PR-AP | -AAC-APC Zone: | | Category: | | Rank: P | |
| Area: | | 14,420 SqFt | Length: | 120 Ft | Width: | 100 Ft | | | |
| Slabs: | | Slab Lei | ngth: | Ft Slab | Width: | Ft | Joint 1 | Length: | Ft |
| Shoulder: | | Street T | ype: | Grad | de: 0 | | Lanes | : 0 | |
| Section Co | mments: | | | | | | | | |
| Work Date | : 1/1/1960 | W | ork Type: New | Construction - Initial | (| Code: NU-IN | Is | Major M&R: True | |
| Work Date | : 1/1/2002 | W | ork Type: Comp | olete Reconstruction - AC | C (| Code: CR-AC | Is | Major M&R: True | |
| Work Date | e: 7/1/2010 | W | ork Type: MILI | and OVERLAY | (| Code: ML-OV | Is | Major M&R: True | |
| Last Insp. 1 | Date: 4/10 | 0/2019 | TotalSa | amples: 3 | Survey | ed: 1 | | | |
| Conditions | : PCI: | 58 | | | | | | | |
| Inspection | Comments | : | | | | | | | |
| Sample Nu | mber: 102 | 2 Ty] | pe: R | Area: | 5389.00 SqFt | PCI: | 58 | | |
| Sample Co | mments: | • | • | | • | | | | |
| 50 PAT | ГСНING | | L | 147.00 SqFt | | | | | |
| 48 L& | TCR | | L | 72.00 Ft | | | | | |
| 50 PA7 | ГСНING | | M | 612.00 SqFt | | | | | |
| 52 RA | VELING | | L | 4630.00 SqFt | | | | | |

| Network: GNV | | | Nai | me: GA | INESVILLE R | EGIONAL AIRPOI | RT | |
|----------------------------------|-------------|-----------------|--------------------|--------------|-------------|----------------|----------|-----------------------|
| Branch: AP N | Ţ | Name: | NORTH APP | RONS | Use: | APRON | Area: | 1,129,675 SqFt |
| Section: 4230 | C | of 16 | From: - | | | То: - | | Last Const.: 7/1/2010 |
| Surface: AAC | Family: | C9N59-PR-AF | P-AAC-APC Zoi | ne: | | Category: | | Rank: P |
| Area: | 36,283 SqFt | Length: | 402 | Ft | Width: | 100 Ft | | |
| Slabs: | Slab Lei | ngth: | Ft | Slab Width: | | Ft | Joint Le | ngth: Ft |
| Shoulder: | Street T | ype: | | Grade: 0 | | | Lanes: | 0 |
| Section Comments: | | | | | | | | |
| Work Date: 1/1/19 | 80 W | ork Type: BUII | LT | | Со | de: IMPORTED | Is M | ajor M&R: True |
| Work Date: 1/1/20 | 05 W | ork Type: MIL | L and OVERLAY | | Со | de: ML-OV | Is M | ajor M&R: True |
| Work Date: 7/1/20 | 10 W | ork Type: MIL | L and OVERLAY | | Со | de: ML-OV | Is M | ajor M&R: True |
| Work Date: 7/2/20 | 10 W | ork Type: Surfa | ace Treatment - Do | ouble Bitum. | Со | de: SU-DB | Is M | ajor M&R: False |
| Last Insp. Date: 4 | 10/2019 | TotalS | amples: 9 | | Surveyed | : 1 | | |
| Conditions: PCI Inspection Comme | | | | | | | | |
| Sample Number: | 300 Ty | pe: R | Area: | 500 | 0.00 SqFt | PCI: 77 | | |
| Sample Comments: | | | | | | | | |
| 52 RAVELING | | L | 1000.00 SqFt | | | | | |
| 57 WEATHERI | NG | L | 4000.00 SqFt | | | | | |
| 48 L & T CR | | L | 46.00 Ft | | | | | |

| Network: GNV | | Name: | GAINESVILLE RE | GIONAL AIRPORT | |
|---|----------------------------|---|------------------------------|----------------|-----------------------------|
| Branch: AP N | Name: | NORTH APRONS | Use: | APRON A | rea: 1,129,675 SqFt |
| Section: 4240 | of 16 F | rom: - | | То: - | Last Const.: 7/1/201 |
| Surface: AAC | Family: C9N59-PR-AP | AAC-APC Zone: | | Category: | Rank: P |
| Area: 130,329 | SqFt Length: | 650 Ft | Width: | 200 Ft | |
| Slabs: | Slab Length: | Ft Slab | Width: | Ft | Joint Length: Ft |
| Shoulder: | Street Type: | Gra | de: 0 | | Lanes: 0 |
| Section Comments: | | | | | |
| Work Date: 1/1/1980 | Work Type: BUIL | T | Code | : IMPORTED | Is Major M&R: True |
| Work Date: 1/1/2002 | Work Type: Overl | ay - AC Structural | Code | : OL-AS | Is Major M&R: True |
| Work Date: 1/1/2002 | Work Type: Cold | Milling | Code | : MI-CO | Is Major M&R: False |
| Work Date: 7/1/2010 | Work Type: Mill a | nd Overlay | Code | : ML-OL | Is Major M&R: True |
| Work Date: 7/2/2010 | Work Type: Surfa | ce Treatment - Double F | Bitum. Code | : SU-DB | Is Major M&R: False |
| Last Insp. Date: 4/10/2019 | TotalSa | amples: 29 | Surveyed: | 3 | |
| Conditions: PCI: 70 | | | | | |
| Inspection Comments: | | | | | |
| Sample Number: 200 | Type: R | Area: | 5000.00 SqFt | PCI: 75 | |
| Sample Comments: | | | | | |
| 52 RAVELING | L | 1000.00 SqFt | | | |
| 57 WEATHERING | L | 4000.00 SqFt | | | |
| | | | | | |
| | L | 12.00 SqFt | | | |
| 56 SWELLING | L L | 12.00 SqFt 115.00 Ft | | | |
| 56 SWELLING 48 L & T CR | | - | 5768.00 SqFt | PCI: 59 | |
| 56 SWELLING 48 L & T CR Sample Number: 208 | L | 115.00 Ft | 5768.00 SqFt | PCI: 59 | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: | L | 115.00 Ft Area: | 5768.00 SqFt | PCI: 59 | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: 52 RAVELING | Type: R | 115.00 Ft | 5768.00 SqFt | PCI: 59 | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: 52 RAVELING 48 L & T CR | Type: R | 115.00 Ft Area: 1000.00 SqFt | 5768.00 SqFt | PCI: 59 | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: 52 RAVELING 48 L & T CR 45 DEPRESSION | Type: R L L L | 115.00 Ft Area: 1000.00 SqFt 64.00 Ft | 5768.00 SqFt | PCI: 59 | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: 52 RAVELING 48 L & T CR 45 DEPRESSION 43 BLOCK CR | Type: R L L L L | 115.00 Ft Area: 1000.00 SqFt 64.00 Ft 4.00 SqFt | 5768.00 SqFt 4200.00 SqFt | PCI: 59 | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: 52 RAVELING 48 L & T CR 45 DEPRESSION 43 BLOCK CR Sample Number: 456 | Type: R L L L L L | 115.00 Ft Area: 1000.00 SqFt 64.00 Ft 4.00 SqFt 3650.00 SqFt | | | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: 52 RAVELING 48 L & T CR 45 DEPRESSION 43 BLOCK CR Sample Number: 456 Sample Comments: | Type: R L L L L L | 115.00 Ft Area: 1000.00 SqFt 64.00 Ft 4.00 SqFt 3650.00 SqFt | | | |
| 56 SWELLING 48 L & T CR Sample Number: 208 Sample Comments: 52 RAVELING 48 L & T CR 45 DEPRESSION 43 BLOCK CR Sample Number: 456 Sample Comments: | Type: R L L L L L Type: R | 115.00 Ft Area: 1000.00 SqFt 64.00 Ft 4.00 SqFt 3650.00 SqFt Area: | | | |

| Network: GN | IV | | Name: | GAINESVILLE | REGIONAL AIRPO | ORT | | |
|------------------|---------------|-------------------|------------------------|--------------|----------------|------------|----------------|----------|
| Branch: AP | N | Name: | NORTH APRONS | Use: | APRON | Area: | 1,129,675 SqFt | |
| Section: 4241 | | of 16 F | om: - | | То: - | | Last Const.: | 7/1/2010 |
| Surface: AAC | Family: | C9N59-PR-AP- | AAC-APC Zone: | | Category: | | Rank: P | |
| Area: | 21,600 SqFt | Length: | 400 Ft | Width: | 60 Ft | | | |
| Slabs: | Slab Le | ength: | Ft Slab | Width: | Ft | Joint Leng | gth: I | ₹t |
| Shoulder: | Street | Гуре: | Grae | de: 0 | | Lanes: | 0 | |
| Section Commen | ts: | | | | | | | |
| Work Date: 1/1/ | 1980 V | Vork Type: New (| Construction - Initial | C | ode: NU-IN | Is Ma | jor M&R: True | |
| Work Date: 1/1/ | 2005 V | Vork Type: MILL | and OVERLAY | C | ode: ML-OV | Is Ma | jor M&R: True | |
| Work Date: 7/1/ | 2010 V | Vork Type: MILL | and OVERLAY | C | ode: ML-OV | Is Ma | jor M&R: True | |
| Work Date: 7/2/ | 2010 V | Vork Type: Surfac | e Treatment - Double B | Bitum. Co | ode: SU-DB | Is Ma | jor M&R: False | |
| Last Insp. Date: | 4/10/2019 | TotalSa | mples: 5 | Surveye | d: 1 | | | |
| Conditions: P | CI: 76 | | | | | | | |
| Inspection Comn | nents: | | | | | | | |
| Sample Number: | 155 Ty | ype: R | Area: | 4000.00 SqFt | PCI: 7 | 6 | | |
| Sample Commen | ts: | | | | | | | |
| 57 WEATHE | RING | L | 3500.00 SqFt | | | | | |
| 45 DEPRESS | | L | 4.00 SqFt | | | | | |
| 52 RAVELIN | IG | L | 500.00 SqFt | | | | | |
| 48 L & T CR | | L | 189.00 Ft | | | | | |

| Network: | GNV | | | | Name: | GAINESVILLE | REGIONAL AIRPO | DRT | | | |
|--------------|-------------|------------|----------------|---------------|----------------|--------------|----------------|---------|----------|-------------|----------|
| | | | Name | NODTI | APRONS | | APRON | | 1 120 / | (75 C-E4 | |
| Branch: | AP N | | Name: | NORTH | APKONS | Use: | | Area: | 1,129,0 | 675 SqFt | |
| Section: | 4245 | of | f 16 | From: - | | | To: - | | L | ast Const.: | 7/1/2010 |
| Surface: | AAC | Family: | C9N59-PR-A | P-AAC-APC | Zone: | | Category: | | R | Rank: P | |
| Area: | 1 | 5,617 SqFt | Length: | | 150 Ft | Width: | 100 Ft | | | | |
| Slabs: | | Slab Len | gth: | Ft | Slab Wi | dth: | Ft | Joint L | ength: | F | t |
| Shoulder: | | Street Ty | pe: | | Grade: | 0 | | Lanes: | 0 | | |
| Section Con | nments: | | | | | | | | | | |
| Work Date: | : 1/1/1960 | W | ork Type: BUI | LT | | (| Code: IMPORTED | Is N | 1ajor M& | R: True | |
| Work Date: | : 1/1/2002 | W | ork Type: Con | nplete Recons | ruction - AC | (| Code: CR-AC | Is N | 1ajor M& | R: True | |
| Work Date: | : 7/1/2010 | W | ork Type: MII | L and OVER | LAY | (| Code: ML-OV | Is N | Iajor M& | R: True | |
| Work Date: | : 7/2/2010 | W | ork Type: Surf | ace Treatmen | - Double Bitur | n. (| Code: SU-DB | Is N | Iajor M& | R: False | |
| Last Insp. I | Date: 4/10/ | 2019 | Totals | Samples: 3 | | Survey | ed: 1 | | | | |
| Conditions: | PCI: | 70 | | | | | | | | | |
| Inspection (| Comments: | | | | | | | | | | |
| Sample Nui | mber: 301 | Тур | oe: R | Ar | ea: | 5750.00 SqFt | PCI: 7 | 0 | | | |
| Sample Cor | | | | | | 1 | | | | | |
| 48 L& | T CR | | M | 20.00 | 7 + | | | | | | |
| | ATHERING | | L | 5000.00 | | | | | | | |
| | T CR | | L | 201.00 | 1 | | | | | | |
| | EDING | | N | 30.00 | | | | | | | |
| | /ELING | | L | 750.00 | 1 | | | | | | |

| Network: GNV | | Name: | GAINESVILLE I | REGIONAL AIRPOR | T | | |
|---|---------------------------------------|--|----------------------------|-----------------|-------|------------------|--------------|
| Branch: AP N | Name: | NORTH APRONS | Use: | APRON | Area: | 1,129,675 SqFt | |
| Section: 4250 | of 16 | From: - | | То: - | | Last Cons | t.: 7/1/2010 |
| Surface: AAC | Family: C9N59-PR- | AP-AAC-APC Zone: | | Category: | | Rank: P | |
| Area: 145,100 | SqFt Lengt | h: 702 Ft | Width: | 200 Ft | | | |
| Slabs: | Slab Length: | Ft Slat | Width: | Ft | Joint | Length: | Ft |
| Shoulder: | Street Type: | Gra | de: 0 | | Lanes | : 0 | |
| Section Comments: | | | | | | | |
| Work Date: 1/1/1979 | Work Type: B | JILT | Co | ode: IMPORTED | Is | Major M&R: True | |
| Work Date: 1/1/2002 | Work Type: Su | rface Seal - Coal Tar | Co | ode: SS-CT | Is | Major M&R: False | |
| Work Date: 7/1/2010 | Work Type: M | ILL and OVERLAY | Co | ode: ML-OV | Is | Major M&R: True | |
| Work Date: 7/2/2010 | Work Type: Su | rface Treatment - Double I | Bitum. Co | ode: SU-DB | Is | Major M&R: False | |
| Last Insp. Date: 4/10/2019 | Tota | alSamples: 29 | Surveye | d· 3 | | | |
| | | | Surveye | u. 3 | | | |
| - | | • | Surveye | u. <i>5</i> | | | |
| Conditions: PCI: 77 | | | Surveye | u. 3 | | | |
| Conditions: PCI: 77 Inspection Comments: | Type: R | Area: | 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 | | | | | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: | | | | | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING | Type: R L L | Area: 17.00 Ft 4000.00 SqFt | | | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING | Type: R L L L L | Area: 17.00 Ft | 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING | Type: R L L | Area: 17.00 Ft 4000.00 SqFt | | | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 | Type: R L L L L | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt | 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 Sample Comments: | Type: R L L L L | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt | 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 Sample Comments: 52 RAVELING | Type: R L L L L Type: R | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt Area: | 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 Sample Comments: 52 RAVELING 48 L & T CR | Type: R L L L L Type: R | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt Area: | 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 Sample Comments: 52 RAVELING 48 L & T CR 57 WEATHERING | Type: R L L L L Type: R | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 1000.00 SqFt 18.00 Ft | 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 Sample Comments: 52 RAVELING 48 L & T CR 57 WEATHERING 59 WEATHERING 50 Sample Number: 255 | Type: R L L L Type: R | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 1000.00 SqFt 18.00 Ft 4000.00 SqFt | 5000.00 SqFt 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 Sample Comments: 52 RAVELING 48 L & T CR 57 WEATHERING | Type: R L L L Type: R | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 1000.00 SqFt 18.00 Ft 4000.00 SqFt Area: | 5000.00 SqFt 5000.00 SqFt | PCI: 78 | | | |
| Conditions: PCI: 77 Inspection Comments: Sample Number: 157 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 209 Sample Comments: 52 RAVELING 48 L & T CR 57 WEATHERING 52 RAVELING 53 RAVELING 54 L & T CR 55 WEATHERING 55 WEATHERING 56 Sample Number: 255 Sample Comments: | Type: R L L L Type: R L L L Type: R | Area: 17.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 1000.00 SqFt 18.00 Ft 4000.00 SqFt | 5000.00 SqFt 5000.00 SqFt | PCI: 78 | | | |

| Network: GNV | | Name: | | | T | | | |
|--|---|---|---------------------------|---------------|--------------------|------------------------------|--|--|
| Branch: AP N | Name: | NORTH APRONS | Use: | APRON | Area: 1, | 129,675 SqFt | | |
| Section: 4255 | of 16 | From: - | | То: - | | Last Const.: 7/1/2010 | | |
| Surface: AAC | Family: C9N59-PR-A | P-AAC-APC Zone: | | Category: | | Rank: P | | |
| Area: 125,66 | 5 SqFt Length: | 545 Ft | Width: | 200 Ft | | | | |
| Slabs: | Slab Length: | Ft Sla | b Width: | Ft | Joint Length | : Ft | | |
| Shoulder: | Street Type: | Gr | ade: 0 | | Lanes: 0 | | | |
| Section Comments: | | | | | | | | |
| Work Date: 1/1/1985 | Work Type: BU | ILT | Co | ode: IMPORTED | Is Major | M&R: True | | |
| Work Date: 1/1/2002 | Work Type: Cole | d Milling | Co | ode: MI-CO | Is Major | M&R: False | | |
| Work Date: 1/2/2002 | Work Type: Ove | erlay - AC Structural | Co | ode: OL-AS | Is Major | M&R: True | | |
| Work Date: 7/1/2010 | Work Type: Mil | l and Overlay | Сс | ode: ML-OL | Is Major M&R: True | | | |
| Work Date: 7/2/2010 | Work Type: Sur | face Treatment - Double | Bitum. Co | ode: SU-DB | Is Major | M&R: False | | |
| | | | | | | | | |
| Last Insp. Date: 4/10/2019 | Totals | Samples: 25 | Surveyed | d: 3 | | | | |
| = | Totals | Samples: 25 | Surveyed | d: 3 | | | | |
| Conditions: PCI: 72 | Totals | Samples: 25 | Surveyed | d: 3 | | | | |
| Conditions: PCI: 72 Inspection Comments: | Totals Type: R | Samples: 25 Area: | Surveyed 5000.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 | | | | | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: | | | | | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING | Type: R L L | Area: 290.00 Ft 4000.00 SqFt | | | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING | Type: R | Area: 290.00 Ft | | | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING | Type: R L L | Area: 290.00 Ft 4000.00 SqFt | | | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 | Type: R L L L L | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt | 5000.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 Sample Comments: | Type: R L L L L | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt Area: | 5000.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 Sample Comments: 57 WEATHERING | Type: R L L L L Type: R | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt | 5000.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 Sample Comments: 57 WEATHERING 48 L & T CR | Type: R L L L L Type: R | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt Area: | 5000.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 Sample Comments: 57 WEATHERING 48 L & T CR 59 RAVELING | Type: R L L L L Type: R | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 4850.00 SqFt 219.00 Ft | 5000.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 Sample Comments: 57 WEATHERING 48 L & T CR 52 RAVELING Sample Number: 351 | Type: R L L L Type: R | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 4850.00 SqFt 219.00 Ft 1200.00 SqFt | 5000.00 SqFt 6050.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 Sample Comments: 57 WEATHERING 48 L & T CR 52 RAVELING Sample Number: 351 Sample Comments: | Type: R L L L Type: R | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 4850.00 SqFt 219.00 Ft 1200.00 SqFt | 5000.00 SqFt 6050.00 SqFt | PCI: 74 | | | | |
| Conditions: PCI: 72 Inspection Comments: Sample Number: 103 Sample Comments: 48 L & T CR 57 WEATHERING 52 RAVELING Sample Number: 200 Sample Comments: 57 WEATHERING 48 L & T CR | Type: R L L L Type: R Type: R Type: R | Area: 290.00 Ft 4000.00 SqFt 1000.00 SqFt Area: 4850.00 SqFt 219.00 Ft 1200.00 SqFt Area: | 5000.00 SqFt 6050.00 SqFt | PCI: 74 | | | | |

| | GNV | | | Name: | GAINESVI | LLE REG | IONAL AIRPOR | T | | | |
|---|--|--------------|---------------------------------|--|-------------|----------------|----------------|---------|----------|-------------|----------|
| Branch: | AP N | | Name: | NORTH APRON | s t | se: Al | PRON | Area: | 1,129,6 | 575 SqFt | |
| Section: | 4260 | of 16 |) | From: - | | | То: - | | L | ast Const.: | 7/1/2010 |
| Surface: | AAC | Family: C9 | N59-PR-AI | P-AAC-APC Zone: | | | Category: | | R | ank: P | |
| Area: | 104,561 | 1 SqFt | Length: | 400 Ft | Width | : | 250 Ft | | | | |
| Slabs: | | Slab Length: | | Ft Sla | ab Width: | | Ft | Joint L | ength: | F | į |
| Shoulder: | | Street Type: | | Gi | rade: 0 | | | Lanes: | 0 | | |
| Section Co | omments: | | | | | | | | | | |
| Work Date | e: 1/1/1992 | Work | Гуре: BUI | LT | | Code: | IMPORTED | Is | Major M& | R: True | |
| Work Date | e: 7/1/2010 | Work | Гуре: MIL | L and OVERLAY | | Code: | ML-OV | Is l | Major M& | R: True | |
| Work Date | Work Date: 7/2/2010 Work Type: Surface Treatment - Double Bi | | | | | Code: | SU-DB | Is | Major M& | R: False | |
| Last Insp. | Date: 4/10/2019 | | TotalS | Samples: 22 | Su | veyed: | 3 | | | | |
| Conditions | s: PCI: 74 | | | | | | | | | | |
| Inspection | Comments: | | | | | | | | | | |
| Sample Nu | umber: 102 | Type: | R | Area: | 3500.00 Sql | | PCI: 81 | | | | |
| Sample Co | omments: | | | | | | | | | | |
| | | | L | 500.00 SqFt | | | | | | | |
| 52 RA | VELING | | _ | 500.00 Sq1 t | | | | | | | |
| | VELING & T CR | | L | 5.00 Ft | | | | | | | |
| 48 L & | | | | • | | | | | | | |
| 48 L & 57 WE | t T CR | | L | 5.00 Ft | 5700.00 Sql | | PCI: 66 | | | | |
| 48 L & 57 WE Sample Nu | t T CR EATHERING umber: 250 | | L L | 5.00 Ft 3000.00 SqFt | 5700.00 Sql | ₹t | PCI: 66 | | | | |
| 48 L & 57 WE Sample Nu Sample Co | t T CR EATHERING umber: 250 | Туре: | L L | 5.00 Ft 3000.00 SqFt | 5700.00 Sql | [?] t | PCI: 66 | | | | |
| 48 L & 57 WE Sample Nu Sample Co | EATHERING umber: 250 pmments: | Type: | L L R | 5.00 Ft 3000.00 SqFt Area: | 5700.00 Sql | Pt | PCI: 66 | | | | |
| 48 L & 57 WE Sample Nu Sample Co 52 RA 43 BLo | ET CR EATHERING Imber: 250 Domments: VELING | Туре: | L L L L L | 5.00 Ft 3000.00 SqFt Area: 700.00 SqFt 855.00 SqFt 64.00 Ft | 5700.00 Sql | ₹t | PCI: 66 | | | | |
| 48 L & 57 WE Sample No 52 RA 43 BL 48 L & 48 | E T CR EATHERING Imber: 250 Dimments: VELING OCK CR | Туре: | L L R L L | 5.00 Ft 3000.00 SqFt Area: 700.00 SqFt 855.00 SqFt | 5700.00 Sql | rt | PCI: 66 | | | | |
| 48 L & Sample No. Sample Co. 52 RA 43 BLo. 48 L & S57 WE | E T CR EATHERING Imber: 250 Dimments: VELING OCK CR E T CR | Туре: | L L L L L | 5.00 Ft 3000.00 SqFt Area: 700.00 SqFt 855.00 SqFt 64.00 Ft | 5700.00 Sql | | PCI: 66 | | | | |
| 48 L & 57 WE Sample No Sample Co 52 RA 43 BL0 48 L & 57 WE Sample No Sample | ET CR EATHERING Imber: 250 Domments: VELING OCK CR E T CR EATHERING Imber: 401 | Туре: | L R L L L L | 5.00 Ft 3000.00 SqFt Area: 700.00 SqFt 855.00 SqFt 64.00 Ft 5000.00 SqFt | · | | | | | | |
| 48 L & Sample No Sample Co S2 RA 43 BL 48 L & S7 WE Sample No Sample Co Sample Co Sample Co Sample Co | ET CR EATHERING Imber: 250 Domments: VELING OCK CR E T CR EATHERING Imber: 401 | Type: | L R L L L L | 5.00 Ft 3000.00 SqFt Area: 700.00 SqFt 855.00 SqFt 64.00 Ft 5000.00 SqFt | · | | | | | | |
| 48 L & 57 WE Sample Co 52 RA 43 BL & 48 L & 57 WE Sample Co 53 WE Sample Co 57 WE 57 WE | ET CR EATHERING umber: 250 pmments: VELING OCK CR ET CR EATHERING umber: 401 pmments: | Type: | L R L L L L R | 5.00 Ft 3000.00 SqFt Area: 700.00 SqFt 855.00 SqFt 64.00 Ft 5000.00 SqFt Area: | · | | | | | | |

| Network: | GNV | | | | Name: | GAINESVILLE | REGIONAL AI | RPORT | | | |
|---|------------------|--------------|-----------------|----------------|-------------|--------------|-------------|--------------------|-------------|------------|----------|
| Branch: | AP N | | Name: | NORTH A | PRONS | Use: | APRON | Area: | 1,129,67 | 5 SqFt | |
| Section: | 4270 | (| of 16 F | rom: - | | | То: - | | Las | st Const.: | 7/1/2010 |
| Surface: | AC | Family: | C9N59-PR-AP | -AC Z | Zone: | | Category | : | Ra | nk: P | |
| Area: | | 32,960 SqFt | Length: | 1,50 | 0 Ft | Width: | 35 | Ft | | | |
| Slabs: | | Slab Le | ngth: | Ft | Slab Wio | dth: | Ft | Joint | Length: | Ft | t |
| Shoulder: | | Street T | ype: | | Grade: | 0 | | Lane | s: 0 | | |
| Section Co | mments: | | | | | | | | | | |
| Work Date: 1/1/1992 Work Type: New Construction - Initial | | | | | (| Code: NU-IN | I | s Major M&R | : True | | |
| Work Date | : 7/1/2010 |) W | ork Type: New | Construction - | AC | (| Code: NC-AC | Is Major M&R: True | | | |
| Work Date | : 7/2/2010 |) W | ork Type: Surfa | ce Treatment - | Slurry Seal | (| Code: ST-SS | I | s Major M&R | : False | |
| Last Insp. l | Date: 4/1 | 0/2019 | TotalSa | amples: 7 | | Survey | ed: 1 | | | | |
| Conditions | : PCI: | 79 | | | | | | | | | |
| nspection | Comments | s: | | | | | | | | | |
| Sample Nu | mber: 45 | 50 Ty | pe: R | Area | : | 5279.00 SqFt | PCI | : 79 | | | |
| Sample Co | mments: | | - | | | - | | | | | |
| 15 DEF | PRESSION | I | L | 6.00 SqI | ₹t | | | | | | |
| 57 WE. | ATHERIN | G | L | 4779.00 SqI | ₹t | | | | | | |
| | T CR | | L | 162.00 Ft | | | | | | | |
| 52 RAV | VELING | | L | 500.00 SqI | ?t | | | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: 9,793 SqFt Branch: AP RU 25 RUN UP APRON AT RW 25 APRON Name: Use: Area: 5105 of 1 From: Section: To: -Last Const.: 7/1/2009 AAC Family: C9N59-PR-AP-AAC-APC Zone: Category: Rank: P Surface: Area: 9,793 SqFt Length: 175 Ft Width: 50 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1981 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 7/1/2009 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 87 Sample Number: 101 Type: Area: 4979.00 SqFt **Sample Comments:** 57 WEATHERING M 249.00 SqFt L & T CR L 14.00 Ft 48

L

4730.00 SqFt

WEATHERING

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** AP RU 7 RUN UP APRON AT RW 7 Use: APRON Area: 7,974 SqFt Name: **Section:** 5205 of 1 From: **Last Const.:** 1/1/1980 To: -Surface: ACFamily: C9N59-PR-AP-AC Zone: Category: Rank: P Area: 7,974 SqFt Length: 175 Ft Width: 50 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1980 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 4060.00 SqFt **PCI:** 50 Sample Number: 100 Type: R Area: **Sample Comments:** 43 BLOCK CR L 3857.00 SqFt 45 DEPRESSION L 6.00 SqFt

BLOCK CR

RAVELING

M

L

203.00 SqFt

4060.00 SqFt

43

| Network: GNV | | | Name: | GAINESVILLE | REGIONAL AIRPO | RT | |
|---|-----------------|-----------------------|---|--------------|----------------|------------|-----------------------|
| Branch: AP S | | Name: | SOUTH APRONS | S Use: | APRON | Area: | 342,098 SqFt |
| Section: 4105 | of 7 | | From: - | | То: - | | Last Const.: 7/1/2009 |
| Surface: AAC | Family: C91 | N59-PR-A | P-AAC-APC Zone: | | Category: | | Rank: P |
| Area: 6 | 56,500 SqFt | Length: | 630 Ft | Width: | 100 Ft | | |
| Slabs: | Slab Length: | | Ft Sla | ıb Width: | Ft | Joint Leng | gth: Ft |
| Shoulder: | Street Type: | | Gr | rade: 0 | | Lanes: | 0 |
| Section Comments: | | | | | | | |
| Work Date: 1/1/1978 | Work 7 | Гуре: BUI | ILT | C | Code: IMPORTED | Is Ma | jor M&R: True |
| Work Date: 7/1/2009 | Work 7 | Гуре: MIL | LL and OVERLAY | C | Code: ML-OV | Is Ma | jor M&R: True |
| Last Insp. Date: 4/10/ | 2019 | Totals | Samples: 14 | Surveyo | nd. 2 | | |
| | | | Jampics. 17 | Surveyo | cu. 2 | | |
| Conditions: PCI: | | Total | Samples. 14 | Surveyo | eu. 2 | | |
| | 75 | Total | затрез. 14 | Surveyo | cu. 2 | | |
| Inspection Comments: | 75 | | | | | | |
| Inspection Comments: Sample Number: 105 | 75 | R | Area: | 5000.00 SqFt | PCI: 76 | ; | |
| Inspection Comments: | 75 | | | | | ; | |
| Inspection Comments: Sample Number: 105 Sample Comments: | 75 Type: | | | | | ; | |
| Inspection Comments: Sample Number: 105 Sample Comments: | 75 Type: | R | Area: | | | j | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L&TCR | 75 Type: | R L | Area: 7.00 Ft | | | i . | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING | 75 Type: | R L L | Area: 7.00 Ft 4750.00 SqFt | | | j | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING | 75 Type: | R L L M | 7.00 Ft 4750.00 SqFt 250.00 SqFt | | | | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 42 BLEEDING | 75 Type: | R L L M N | 7.00 Ft 4750.00 SqFt 250.00 SqFt 117.00 SqFt | 5000.00 SqFt | PCI: 76 | | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 42 BLEEDING Sample Number: 151 | Type: | R L L M N | 7.00 Ft 4750.00 SqFt 250.00 SqFt 117.00 SqFt | 5000.00 SqFt | PCI: 76 | | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 42 BLEEDING Sample Number: 151 Sample Comments: | Type: | R L L M N R | 7.00 Ft 4750.00 SqFt 250.00 SqFt 117.00 SqFt Area: | 5000.00 SqFt | PCI: 76 | | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 42 BLEEDING Sample Number: 151 Sample Comments: 48 L & T CR | Type: | R L L M N R | 7.00 Ft 4750.00 SqFt 250.00 SqFt 117.00 SqFt Area: 169.00 Ft 2.00 SqFt | 5000.00 SqFt | PCI: 76 | | |
| Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 42 BLEEDING Sample Number: 151 Sample Comments: 48 L & T CR 48 L & T CR 49 BLEEDING | Type: | R L L M N R | 7.00 Ft 4750.00 SqFt 250.00 SqFt 117.00 SqFt Area: | 5000.00 SqFt | PCI: 76 | | |

| Network: | GNV | | | Nam | ne: GAl | NESVILLE I | REGIONAL AIRPO | RT | | |
|--------------------------------------|---|-----------|-------------|---|-------------|---------------|----------------|-----------------|-------------------------|----------|
| Branch: | AP S | | Name: | SOUTH APRO | ONS | Use: | APRON | Area: | 342,098 SqFt | |
| Section: | 4110 | of | f 7 | From: - | | | То: - | | Last Const.: | 1/1/1978 |
| Surface: | PCC | Family: | C9N59-PR-AI | P-PCC Zon | e: | | Category: | | Rank: P | |
| Area: | 126, | 000 SqFt | Length: | 700 F | 't | Width: | 180 Ft | | | |
| Slabs: | 315 | Slab Len | gth: | 20 Ft | Slab Width: | | 20 Ft | Joint L | ength: 11,720 Ft | |
| Shoulder: | | Street Ty | ype: | | Grade: 0 | | | Lanes: | 0 | |
| Section Co | mments: | | | | | | | | | |
| Work Date: 1/1/1978 Work Type: BUILT | | | LT | | C | ode: IMPORTED | Is N | Major M&R: True | | |
| Work Date | Work Date: 1/1/2005 Work Type: Joint Seal - Silic | | | Seal - Silicon | | C | ode: JS-SI | Is N | Major M&R: False | |
| Last Insp. | Date: 4/10/20 | 119 | TotalS | amples: 15 | | Surveye | d: 2 | | | |
| Conditions | : PCI: 88 | 3 | | | | | | | | |
| Inspection | Comments: | | | | | | | | | |
| Sample Nu | mber: 250 | Typ | oe: R | Area: | 21 | 1.00 Slabs | PCI: 96 |) | | |
| Sample Co | mments: | | | | | | | | | |
| 73 SHI | RINKAGE CR | | N | 6.00 Slabs | | | | | | |
| Sample Nu | imber: 253 | Тур | e: R | Area: | 21 | 1.00 Slabs | PCI: 80 |) | | |
| Sample Co | mments: | | | | | | | | | |
| 75 COI 74 JOI | SEAL DMG RNER SPALL NT SPALL | | L M L | 21.00 Slabs 1.00 Slabs 1.00 Slabs | | | | | | |
| | RNER SPALL RINKAGE CR | | L N | 1.00 Slabs 15.00 Slabs | | | | | | |

| Network: GNV | | Name: | GAINESVILLE RE | EGIONAL AIRPORT | • | | |
|-----------------------------------|----------------------|----------------|----------------|-----------------|---------------------|------------------------------|--|
| Branch: AP S | Name: | SOUTH APRONS | Use: | APRON | Area: 3 | 42,098 SqFt | |
| Section: 4115 | of 7 | rom: - | | То: - | | Last Const.: 1/1/1978 | |
| Surface: PCC | Family: C9N59-PR-AP- | PCC Zone: | | Category: | | Rank: P | |
| Area: 35,00 | 0 SqFt Length: | 700 Ft | Width: | 50 Ft | | | |
| Slabs: 194 | Slab Length: | 12 Ft Slab | Width: | 15 Ft | Joint Length: | 4,500 Ft | |
| Shoulder: | Street Type: | Grad | le: 0 | | Lanes: 0 | | |
| Section Comments: | | | | | | | |
| Work Date: 1/1/1978 | Work Type: BUIL | Γ | Cod | e: IMPORTED | Is Major I | M&R: True | |
| Work Date: 1/1/2005 | Work Type: Joint S | Seal - Silicon | Cod | e: JS-SI | Is Major M&R: False | | |
| Last Insp. Date: 4/10/2019 | TotalSa | mples: 8 | Surveyed: | 2 | | | |
| Conditions: PCI: 84 | | | | | | | |
| Inspection Comments: | | | | | | | |
| Sample Number: 352 | Type: R | Area: | 18.00 Slabs | PCI: 89 | | | |
| Sample Comments: | | | | | | | |
| 73 SHRINKAGE CR | N | 8.00 Slabs | | | | | |
| 74 JOINT SPALL | M | 1.00 Slabs | | | | | |
| Sample Number: 356 | Type: R | Area: | 24.00 Slabs | PCI: 80 | | | |
| Sample Comments: | | | | | | | |
| 73 SHRINKAGE CR | N | 18.00 Slabs | | | | | |
| 74 JOINT SPALL | L | 4.00 Slabs | | | | | |
| 74 JOINT SPALL | M | 1.00 Slabs | | | | | |

GAINESVILLE REGIONAL AIRPORT Network: GNV Name: 342,098 SqFt **Branch:** AP S SOUTH APRONS Use: APRON Name: Area: 4120 of 7 Section: From: To: -Last Const.: 7/1/2009 AAC Family: C9N59-PR-AP-AAC-APC Zone: Category: Rank: P Surface: Area: 12,825 SqFt Length: 135 Ft Width: 90 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1978 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 7/1/2009 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 86 Sample Number: 157 Type: Area: 6075.00 SqFt **Sample Comments:** BLEEDING N 1.00 SqFt 42 L & T CR L 15.00 Ft 48 WEATHERING L 57 5467.00 SqFt WEATHERING 57 M 608.00 SqFt

| Network: GNV | | Name: | GAINESVILLE | REGIONAL AIRPOF | RT | | |
|--------------------------|----------------------|---------------|--------------|-----------------|----------|--------------|------------------|
| Branch: AP S | Name: | SOUTH APRONS | Use: | APRON | Area: | 342,098 S | qFt |
| Section: 4125 | of 7 F | rom: - | | То: - | | Last C | Const.: 7/1/2009 |
| Surface: AAC | Family: C9N59-PR-AP- | AAC-APC Zone: | | Category: | | Rank: | P |
| Area: 22, | 290 SqFt Length: | 230 Ft | Width: | 95 Ft | | | |
| Slabs: | Slab Length: | Ft Slal | b Width: | Ft | Joint Le | ength: | Ft |
| Shoulder: | Street Type: | Gra | nde: 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | |
| Work Date: 1/1/1978 | Work Type: BUIL | Γ | C | ode: IMPORTED | Is N | Iajor M&R: T | rue |
| Work Date: 1/1/1981 | Work Type: OVER | RLAY | C | ode: IMPORTED | Is N | Iajor M&R: T | rue |
| Work Date: 1/1/1988 | Work Type: REPA | IR | C | ode: IMPORTED | Is M | Iajor M&R: F | alse |
| Work Date: 7/1/2009 | Work Type: Mill a | nd Overlay | C | ode: ML-OL | Is N | Iajor M&R: T | rue |
| Last Insp. Date: 4/10/20 |)19 TotalSa | mples: 5 | Surveye | ed: 1 | | | |
| Conditions: PCI: 80 | 0 | | | | | | |
| Inspection Comments: | | | | | | | |
| Sample Number: 452 | Type: R | Area: | 4750.00 SqFt | PCI: 80 | | | |
| Sample Comments: | | | | | | | |
| 48 L & T CR | L | 2.00 Ft | | | | | |
| 57 WEATHERING | M | 475.00 SqFt | | | | | |
| 57 WEATHERING | L | 4275.00 SqFt | | | | | |
| 42 BLEEDING | N | 67.00 SqFt | | | | | |

| Network: | GNV | | | | Nan | ne: GA | INESVILLE | REGI | ONAL AIRPOI | RT | | | |
|--------------|-------------------|------------|---------------|------------|-------|-------------|-----------|---------------|-------------|---------|------------|-------------|----------|
| Branch: | AP S | | Name: | SOUTH | I APR | ONS | Use: | AP | RON | Area: | 342,098 | SqFt | |
| Section: | 4130 | 0 | of 7 | From: - | | | , | | То: - | | Last | Const.: | 7/1/2009 |
| Surface: | AAC | Family: | C9N59-PR-A | P-AAC-APC | Zon | ie: | | 1 | Category: | | Ran | k: P | |
| Area: | | 8,760 SqFt | Length: | | 220 F | ∄t | Width: | | 40 Ft | | | | |
| Slabs: | | Slab Ler | ngth: | Ft | | Slab Width: | | Ţ | Ft | Joint L | ength: | F | t |
| Shoulder: | | Street T | ype: | | | Grade: 0 | | | | Lanes: | 0 | | |
| Section Cor | mments: | | | | | | | | | | | | |
| Work Date: | : 1/1/1978 | W | ork Type: BUI | .LT | | | C | ode: | IMPORTED | Is N | Major M&R: | True | |
| Work Date: | : 1/1/1988 | W | ork Type: REP | 'AIR | | | C | ode: | IMPORTED | Is N | Major M&R: | False | |
| Work Date: | 7/1/2009 | W | ork Type: MIL | L and OVER | LAY | | C | ode: | ML-OV | Is N | Major M&R: | True | |
| Last Insp. I | Date: 4/10 | /2019 | Total | Samples: 2 | 2 | | Surveye | e d: 1 | | | | | |
| Conditions: | : PCI: | 88 | | | | | | | | | | | |
| Inspection (| Comments: | | | | | | | | | | | | |
| Sample Nu | mber: 400 |) Ty | pe: R | A | rea: | 400 | 0.00 SqFt | | PCI: 88 | | | | |
| Sample Cor | mments: | | | | | | | | | | | | |
| 57 WE | ATHERING | † | L | 3800.00 | SqFt | | | | | | | | |
| | ATHERING | ŗ | M | 200.00 | SqFt | | | | | | | | |
| | EEDING | | N | 1.00 | | | | | | | | | |
| 49 OIL | SPILLAGE | | N | 15.00 | SaFt | | | | | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** AP S SOUTH APRONS Use: APRON Area: 342,098 SqFt Name: Section: 4135 of 7 **Last Const.:** 1/1/2016 From: To: -Surface: PCC Family: C9N59-PR-AP-PCC Zone: Category: Rank: P Area: 70,723 SqFt Length: 305 Ft Width: 230 Ft Slabs: Slab Length: 12 Ft Slab Width: 15 Ft Joint Length: 377 9,754 Ft Shoulder: **Street Type:** Grade: 0 Lanes: **Section Comments:** Work Date: 1/1/2016 Work Type: New Construction - PCC Code: NC-PC Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 15 Surveyed: 2 **Conditions:** PCI: **Inspection Comments: PCI:** 100 Sample Number: 401 Type: R 24.00 Slabs Area: **Sample Comments:** <No Distress>

24.00 Slabs

PCI: 100

Sample Comments:

Sample Number: 453

R

Area:

Type:

<No Distress>

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: 223,288 SqFt Branch: AP SW SOUTHWEST APRON Use: APRON Name: Area: 4305 of 6 Section: From: To: -**Last Const.:** 1/1/2005 AAC Family: C9N59-PR-AP-AAC-APC Zone: Category: Rank: P Surface: Area: 32,431 SqFt Length: 250 Ft Width: 125 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1991 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2005 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 6 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 65 Sample Number: 100 Type: Area: 5750.00 SqFt **Sample Comments:** WEATHERING M 5750.00 SqFt 57 L & T CR L 36.00 Ft 48 SWELLING L 56 15.00 SqFt

ALLIGATOR CR

M

35.00 SqFt

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: 223,288 SqFt Branch: AP SW SOUTHWEST APRON Use: APRON Name: Area: 4310 of 6 **Last Const.:** 12/25/1999 Section: From: To: -ACFamily: C9N59-PR-AP-AC Zone: Category: Rank: P Surface: Area: 12,201 SqFt Length: 100 Ft Width: 70 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 12/25/1999 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 7/2/2010 Work Type: Surface Treatment - Double Bitum. Code: LC-DB Is Major M&R: False **Last Insp. Date:** 4/10/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 29 Sample Number: 102 Type: Area: 5500.00 SqFt **Sample Comments:** BLOCK CR M 550.00 SqFt 43 RAVELING 5500.00 SqFt 52 M BLOCK CR L 4950.00 SqFt 43

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: 223,288 SqFt Branch: AP SW SOUTHWEST APRON Use: APRON Name: Area: 4315 of 6 **Last Const.:** 12/25/1999 Section: From: To: -ACFamily: C9N59-PR-AP-AC Zone: Category: Rank: P Surface: Area: 23,585 SqFt Length: 210 Ft Width: 70 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 12/25/1999 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 7/2/2010 Work Type: Surface Treatment - Double Bitum. Code: LC-DB Is Major M&R: False **Last Insp. Date:** 4/10/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 5497.00 SqFt **PCI:** 55 Sample Number: 202 Type: Area: **Sample Comments:** L & T CR L 252.00 Ft 48 RAVELING L 5497.00 SqFt 52 L & T CR 330.00 Ft 48 M BLOCK CR 184.00 SqFt 43 L

GNV Network: GAINESVILLE REGIONAL AIRPORT Name: 223,288 SqFt AP SW SOUTHWEST APRON APRON Branch: Name: Use: Area: 4320 Section: of 6 From: To: -Last Const.: 7/1/2010 AAC Family: C9N59-PR-AP-AAC-APC Zone: Category: Rank: P Surface: Area: 21,340 SqFt Length: 100 Ft Width: 100 Ft Slab Width: Slab Length: Ft Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 12/25/1999 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 7/1/2010 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True Work Date: 6/1/2018 Work Type: Surface Treatment - Seal Coat Code: ST-SC Is Major M&R: False **Last Insp. Date:** 4/10/2019 **TotalSamples:** 5 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 73 Sample Number: 402 Type: 4461.00 SqFt Area: **Sample Comments:** L & T CR L 391.00 Ft 48

SWELLING

56

L

100.00 SqFt

| Network: | GNV | | | Name: | GA | INESVILLE | REGIONAL AIRF | PORT | | | |
|--------------|-----------------|--------------|-------------|------------------------|------------|-----------|---------------|-------|-------------|--------------|----------|
| Branch: | AP SW | | Name: | SOUTHWEST A | APRON | Use: | APRON | Area: | 22. | 3,288 SqFt | |
| Section: 4 | 4325 | of 6 |] | From: - | | | То: - | | | Last Const.: | 7/1/2010 |
| Surface: | AC | Family: C | 9N59-PR-AI | P-AC Zone: | | | Category: | | | Rank: P | |
| Area: | 72,72 | 8 SqFt | Length: | 1,250 Ft | | Width: | 50 Ft | | | | |
| Slabs: | | Slab Length | : | Ft S | lab Width: | | Ft | Jo | int Length: | F | t |
| Shoulder: | | Street Type: | | G | rade: 0 | | | La | anes: 0 | | |
| Section Con | nments: | | | | | | | | | | |
| Work Date: | : 12/25/1999 | Work | Type: New | Construction - Initial | | C | ode: NU-IN | | Is Major M | &R: True | |
| Work Date: | : 7/1/2010 | Work | Type: New | Construction - AC | | C | ode: NC-AC | | Is Major M | &R: True | |
| Work Date: | : 7/2/2010 | Work | Type: Surfa | ace Treatment - Doubl | e Bitum. | C | ode: SU-DB | | Is Major M | &R: False | |
| Last Insp. D | Date: 4/10/2019 |) | TotalS | amples: 17 | | Surveye | d: 3 | | | | |
| Conditions: | PCI: 64 | | | | | | | | | | |
| Inspection (| Comments: | | | | | | | | | | |
| Sample Nur | mber: 100 | Type: | R | Area: | 3900 | 5.00 SqFt | PCI: | 67 | | | |
| Sample Con | nments: | | | | | | | | | | |
| 57 WEA | ATHERING | | M | 3906.00 SqFt | | | | | | | |
| | ELLING | | L | 715.00 SqFt | | | | | | | |
| 48 L& | T CR | | L | 51.00 Ft | | | | | | | |
| Sample Nur | mber: 200 | Type: | R | Area: | 3804 | 4.00 SqFt | PCI: | 70 | | | |
| Sample Con | nments: | | | | | | | | | | |
| 48 L& | T CR | | L | 82.00 Ft | | | | | | | |
| 56 SWE | ELLING | | L | 540.00 SqFt | | | | | | | |
| 57 WEA | ATHERING | | M | 3804.00 SqFt | | | | | | | |
| Sample Nur | mber: 204 | Type: | R | Area: | 5600 | 0.00 SqFt | PCI: | 59 | | | |
| Sample Con | nments: | | | | | | | | | | |
| 48 L& | T CR | | L | 299.00 Ft | | | | | | | |
| 54 SHO | VING | | L | 25.00 SqFt | | | | | | | |
| 51 5110 | | | | | | | | | | | |
| | ATHERING | | M | 5600.00 SqFt | | | | | | | |

| Network: | GNV | | | Name: | GAINESVILLE | REGIONAL AIRPO | ORT | |
|------------------------|-------------------|-------------|------------|---------------------------|--------------|----------------|--------------|-----------------------|
| Branch: | AP SW | | Name: | SOUTHWEST A | PRON Use: | APRON | Area: | 223,288 SqFt |
| Section: | 4330 | of | 6 | From: - | | То: - | | Last Const.: 1/1/2009 |
| Surface: | AC | Family: (| C9N59-PR- | AP-AC Zone: | | Category: | | Rank: P |
| Area: | 61,0 | 03 SqFt | Lengt | h: 300 Ft | Width: | 150 Ft | | |
| Slabs: | | Slab Lengt | h: | Ft S | lab Width: | Ft | Joint Lengtl | h: Ft |
| Shoulder: | | Street Type | e : | G | rade: 0 | | Lanes: 0 |) |
| Section Co | mments: | | | | | | | |
| Work Date | : 1/1/2009 | Wor | k Type: N | ew Construction - Initial | (| Code: NU-IN | Is Major | r M&R: True |
| Last Insp. l | Date: 4/10/201 | 9 | Tota | alSamples: 13 | Survey | ed: 2 | | |
| Conditions | : PCI : 76 | | | | | | | |
| Inspection | Comments: | | | | | | | |
| Sample Nu | mber: 101 | Type: | R | Area: | 4599.00 SqFt | PCI: 7 | 6 | |
| Sample Co | mments: | | | | | | | |
| 52 RAV | VELING | | L | 690.00 SqFt | | | | |
| 57 WE. | ATHERING | | M | 3909.00 SqFt | | | | |
| | | Type: | R | Area: | 5000.00 SqFt | PCI: 7 | 6 | |
| Sample Nu | mber: 251 | J 1 | | | | | | |
| | | J.P. | | | | | | |
| Sample Nu Sample Co | | 71 | M | 4250.00 SqFt | | | | |

| Network: | GNV | | | | Nam | e: GAl | NESVILLE | REGIO | NAL AIRPO | RT | | | |
|------------|---------------------|-------------|--------------------|------------------|---------|-------------|-----------|---------|-----------|---------|-----------|-------------|----------------|
| Branch: | RW 11- | 29 | Name: | RUNW | /AY 11- | 29 | Use: | RUN | WAY | Area: | 1,159,9 | 28 SqFt | |
| Section: | 6201 | | of 7 | From: - | - | | | To |): - | | L | ast Const.: | 1/1/2015 |
| Surface: | AAC | Family: | C9N59-PR-RV APC | W-AAC- | Zone | : | | Ca | ntegory: | | R | ank: P | |
| Area: | | 12,282 SqFt | Length: | | 228 Ft | | Width: | | 50 Ft | | | | |
| Slabs: | | Slab Lo | ength: | Ft | | Slab Width: | | Ft | | Joint L | ength: | H | ⁷ t |
| Shoulder: | | Street | Гуре: | | | Grade: 0 | | | | Lanes: | 0 | | |
| Section Co | omments: | | | | | | | | | | | | |
| Work Dat | te: 1/1/1973 | V | Work Type: BUI | LT | | | C | ode: II | MPORTED | Is I | Major M&l | R: True | |
| Work Dat | te: 1/1/2005 | V | Work Type: Patc | hing - AC Do | eep | | C | ode: P | A-AD | Is I | Major M&l | R: False | |
| Work Dat | te: 2/1/2005 | V | Vork Type: Mill | and Overlay | I | | C | ode: N | IL-OL | Is I | Major M&l | R: True | |
| Work Dat | te: 1/1/2015 | V | Vork Type: MIL | L and OVEF | RLAY | | C | ode: M | IL-OV | Is I | Major M&l | R: True | |
| Last Insp. | Date: 4/1 | 0/2019 | Totals | Samples: 3 | 3 | | Surveye | ed: 1 | | | | | |
| Condition | s: PCI: | 88 | | | | | | | | | | | |
| Inspection | Comments | : | | | | | | | | | | | |
| Sample N | umber: 29 | 5 T | ype: R | A | rea: | 5000 | 0.00 SqFt | | PCI: 88 | 3 | | | |
| Sample Co | omments: | | | | | | | | | | | | |
| | & T CR EATHERING | G | L L | 98.00 5000.00 | | | | | | | | | |

| Network: | GNV | | | | Name: | GAINESVILLE | EREGIONAL | AIRPORT | | | |
|---|---|--------------|---------------------|--|--|----------------------------|------------|---------|-------------|-------------|-----------------|
| Branch: | RW 11-29 | | Name: | RUNW | AY 11-29 | Use: | RUNWA | Y Ar | ea: | 1,159,928 S | qFt |
| Section: 62 | 202 | of 7 | i | From: - | | | To: | _ | | Last C | Const.: 2/1/200 |
| Surface: AA | AC | | 9N59-PR-R PC | tW-AAC- | Zone: | | Categ | ory: | | Rank: | P |
| Area: | 34,69 | 97 SqFt | Length | : | 404 Ft | Width: | 1 | 00 Ft | | | |
| Slabs: | | Slab Length | : | Ft | Slab Wi | idth: | Ft | | Joint Lengt | h: | Ft |
| Shoulder: | | Street Type: | : | | Grade: | 0 | | | Lanes: | 0 | |
| Section Comn | ments: | | | | | | | | | | |
| Work Date: | 1/1/1973 | Work | Type: BU | ILT | | | Code: IMPO | ORTED | Is Majo | or M&R: T | rue |
| Work Date: | 1/1/2005 | Work | Type: Pate | ching - AC De | ep | (| Code: PA-A | D | Is Majo | or M&R: F | alse |
| Work Date: 2 | 2/1/2005 | Work | Type: Mil | ll and Overlay | | • | Code: ML-C | DL | Is Majo | or M&R: T | rue |
| Conditions: | PCI: 52 | 9 | Total | Samples: 7 | | Survey | red: 2 | | | | |
| Conditions: Inspection Co | PCI: 52 omments: | Type: | Total R | | ·ea: | Survey 4956.00 SqFt | | PCI: 52 | | | |
| | PCI: 52 omments: ber: 298 | | | | | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm | PCI: 52 omments: ber: 298 | | R | Ar 19.00 S | rea: SqFt | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI | PCI: 52 comments: ber: 298 ments: GATOR CR LAST | | R L N | 19.00 S 20.00 S | r ea: SqFt SqFt | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING | | R L N L | 19.00 S 20.00 S 4857.00 S | r ea: SqFt SqFt SqFt | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEEI | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING DING | | R L N L N | 19.00 S 20.00 S 4857.00 S 1.00 S | r ea: SqFt SqFt SqFt SqFt | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEEI 52 RAVE | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING DING ELING | | R L N L N L N L | 19.00 S 20.00 S 4857.00 S 1.00 S 99.00 S | rea: SqFt SqFt SqFt SqFt SqFt | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEET 52 RAVE 48 L&T | PCI: 52 comments: ber: 298 ments: GATOR CR LAST FHERING DING ELING CR | | R L N L N L L L | 19.00 S 20.00 S 4857.00 S 1.00 S 99.00 S 603.00 I | sqFt sqFt sqFt sqFt sqFt sqFt | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEEI 52 RAVE 48 L & T 45 DEPRI | PCI: 52 comments: ber: 298 ments: GATOR CR LAST FHERING DING ELING CR ESSION | | R L N L N L L L L | 19.00 \$ 20.00 \$ 4857.00 \$ 1.00 \$ 99.00 \$ 603.00 I 1.00 \$ | sqFt sqFt sqFt sqFt sqFt sqFt Ft | | | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIG 46 JET BI 57 WEAT 42 BLEEI 52 RAVE 48 L & T 45 DEPRI 56 SWEL | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING DING ELING CR ESSION LLING | Туре: | R L N L N L L L L | 19.00 \$ 20.00 \$ 4857.00 \$ 1.00 \$ 99.00 \$ 603.00 I 1.00 \$ 150.00 \$ | r ea: SqFt SqFt SqFt SqFt Ft SqFt | 4956.00 SqFt | F | | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEEI 52 RAVE 48 L & T 45 DEPRI 56 SWEL Sample Numb | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING DING ELING CR ESSION LLING ber: 300 | | R L N L N L L L L | 19.00 \$ 20.00 \$ 4857.00 \$ 1.00 \$ 99.00 \$ 603.00 I 1.00 \$ 150.00 \$ | sqFt sqFt sqFt sqFt sqFt sqFt Ft | | F | PCI: 52 | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEEI 52 RAVE 48 L & T 45 DEPRI 56 SWEL Sample Numb Sample Comm | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING DING ELING CR ESSION LING ber: 300 ments: | Туре: | R L N L N L L L L R | 19.00 S 20.00 S 4857.00 S 1.00 S 99.00 S 603.00 I 1.00 S | rea: SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt | 4956.00 SqFt | F | | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEEI 52 RAVE 48 L & T 45 DEPRI 56 SWEL Sample Numb Sample Comm 42 BLEEI | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING DING ELING CR ESSION LING ber: 300 ments: DING | Туре: | R L N L N L L L L R | 19.00 S 20.00 S 4857.00 S 1.00 S 99.00 S 603.00 I 1.00 S 150.00 S | rea: SqFt SqFt SqFt SqFt SqFt SqFt Tea: | 4956.00 SqFt | F | | | | |
| Conditions: Inspection Co Sample Numb Sample Comm 41 ALLIC 46 JET BI 57 WEAT 42 BLEEI 52 RAVE 48 L & T 45 DEPRI 56 SWEL Sample Numb Sample Comm 42 BLEEI | PCI: 52 comments: ber: 298 ments: GATOR CR LAST THERING DING ELING CR ESSION LING ber: 300 ments: DING LING | Туре: | R L N L N L L L L R | 19.00 S 20.00 S 4857.00 S 1.00 S 99.00 S 603.00 I 1.00 S | rea: SqFt SqFt SqFt SqFt Ft SqFt SqFt SqFt S | 4956.00 SqFt | F | | | | |

| Network: GNV | | Name: | GAINESVILLE RE | GIONAL AIRPORT | |
|---|--------------------------|------------------------------|----------------|----------------|-----------------------|
| Branch: RW 11-29 | Name: | RUNWAY 11-29 | | RUNWAY Area | a: 1,159,928 SqFt |
| Section: 6205 | | From: - | 056. | To: - | Last Const.: 2/1/2005 |
| | | | | | |
| Surface: AAC Fa | mily: C9N59-PR-RV APC | W-AAC- Zone: | | Category: | Rank: P |
| Area: 630,300 S | qFt Length: | 4,470 Ft | Width: | 100 Ft | |
| | lab Length: | Ft Slab | Width: | Ft | Joint Length: Ft |
| Shoulder: S | treet Type: | Grad | le: 0 | | Lanes: 0 |
| Section Comments: | | | | | |
| Work Date: 1/1/1973 | Work Type: BUI | LT | Code | : IMPORTED | Is Major M&R: True |
| Work Date: 1/1/1973 | Work Type: OVE | ERLAY | Code | e: IMPORTED | Is Major M&R: True |
| Work Date: 1/1/2005 | Work Type: Patc | hing - AC Deep | Code | e: PA-AD | Is Major M&R: False |
| Work Date: 2/1/2005 | Work Type: Mill | - | | e: ML-OL | Is Major M&R: True |
| Last Insp. Date: 4/10/2019 | TotalS | samples: 126 | Surveyed: | 20 | |
| Conditions: PCI: 72 | | | | | |
| Inspection Comments: | | | | | |
| Sample Number: 305 | Type: R | Area: | 5000.00 SqFt | PCI: 77 | |
| Sample Comments: | | | | | |
| 48 L & T CR | L | 180.00 Ft | | | |
| 57 WEATHERING | L | 4400.00 SqFt | | | |
| 56 SWELLING52 RAVELING | L L | 20.00 SqFt 600.00 SqFt | | | |
| Sample Number: 312 | Type: R | Area: | 5000.00 SqFt | PCI: 73 | |
| Sample Comments: | · - | - | 1 | | |
| 48 L & T CR | L | 296.00 Ft | | | |
| 57 WEATHERING | L | 3750.00 SqFt | | | |
| 52 RAVELING | L | 1250.00 SqFt | | | |
| Sample Number: 319 | Type: R | Area: | 5000.00 SqFt | PCI: 70 | |
| Sample Comments: | | | | | |
| 52 RAVELING | L | 1250.00 SqFt | | | |
| 57 WEATHERING | L | 3750.00 SqFt | | | |
| 48 L & T CR | L | 389.00 Ft | 5000 00 G F: | DCI 71 | |
| Sample Number: 326 | Type: R | Area: | 5000.00 SqFt | PCI: 71 | |
| Sample Comments: | | | | | |
| 56 SWELLING | L | 5.00 SqFt | | | |
| 52 RAVELING57 WEATHERING | L L | 1250.00 SqFt 3750.00 SqFt | | | |
| 48 L & T CR | L | 343.00 Ft | | | |
| Sample Number: 332 | Type: R | Area: | 5000.00 SqFt | PCI: 74 | |
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 3750.00 SqFt | | | |
| 52 RAVELING | L | 1250.00 SqFt | | | |
| 48 L&TCR | L | 243.00 Ft | | | |
| 56 SWELLING Sample Number: 339 | Type: R | 7.00 SqFt Area: | 5000.00 SqFt | PCI: 75 | |
| Sample Comments: | Type. K | Aiva; | Jooo.oo sqri | 1 CI. /3 | |
| _ | _ | 1050.00 7 7 | | | |
| 52 RAVELING 48 L & T CR | L L | 1250.00 SqFt 171.00 Ft | | | |
| 57 WEATHERING | L L | 3750.00 SqFt | | | |
| Sample Number: 345 | Type: R | Area: | 5000.00 SqFt | PCI: 75 | |
| Sample Comments: | | | - | | |
| 57 WEATHERING | L | 3750.00 SqFt | | | |
| | £ | 5,50.00 Sqrt | | | |

| 48 | L & T CR | | L | 199.00 Ft | | | |
|------------|------------------------|---|--------|-----------------------------|---------------|----------------|--|
| 52 | RAVELING | | L | 1250.00 SqFt | | | |
| Samp | le Number: 351 | Type: | R | Area: | 5000.00 SqFt | PCI: 75 | |
| Samp | le Comments: | | | | | | |
| 57 | WEATHERING | | L | 3700.00 SqFt | | | |
| 48 | L & T CR | | L | 220.00 Ft | | | |
| 52 | RAVELING | | L | 1300.00 SqFt | | | |
| - | le Number: 358 | Type: | R | Area: | 5000.00 SqFt | PCI: 75 | |
| Samp | le Comments: | | | | | | |
| 57 | WEATHERING | | L | 3700.00 SqFt | | | |
| 48 | L & T CR RAVELING | | L L | 264.00 Ft 1300.00 SqFt | | | |
| 52 Same | le Number: 365 | Type: | R | Area: | 5000.00 SqFt | PCI: 71 | |
| _ | ele Comments: | Type. | K | Alea. | 3000.00 Sqrt | rci. /1 | |
| _ | | | | | | | |
| 52 57 | RAVELING WEATHERING | | L | 1800.00 SqFt | | | |
| 37 48 | L & T CR | | L L | 3200.00 SqFt 369.00 Ft | | | |
| Samp | le Number: 372 | Type: | R | Area: | 5000.00 SqFt | PCI: 72 | |
| _ | le Comments: | , , , , , , , , , , , , , , , , , , , | | | 1 | | |
| • | | | т | 2200 00 C-E4 | | | |
| 57 48 | WEATHERING L & T CR | | L L | 3200.00 SqFt 344.00 Ft | | | |
| 52 | RAVELING | | L | 1800.00 SqFt | | | |
| Samp | le Number: 377 | Type: | R | Area: | 5000.00 SqFt | PCI: 74 | |
| Samp | le Comments: | | | | | | |
| 52 | RAVELING | | L | 1500.00 SqFt | | | |
| 48 | L & T CR | | L | 270.00 Ft | | | |
| 57 | WEATHERING | | L | 3500.00 SqFt | | | |
| _ | le Number: 383 | Type: | R | Area: | 5000.00 SqFt | PCI: 71 | |
| Samp | le Comments: | | | | | | |
| 57 | WEATHERING | | L | 3000.00 SqFt | | | |
| 48 52 | L & T CR RAVELING | | L L | 319.00 Ft 2000.00 SqFt | | | |
| | lle Number: 390 | Type: | R | Area: | 5000.00 SqFt | PCI: 70 | |
| | le Comments: | Type. | K | All ca. | 3000.00 Sqf t | 101. 70 | |
| _ | | | т | 277 00 E | | | |
| 48 52 | L & T CR RAVELING | | L L | 377.00 Ft 1000.00 SqFt | | | |
| 57 | WEATHERING | | L | 4000.00 SqFt | | | |
| Samp | le Number: 397 | Type: | R | Area: | 5000.00 SqFt | PCI: 69 | |
| Samp | le Comments: | | | | | | |
| 48 | L & T CR | | L | 419.00 Ft | | | |
| 52 | RAVELING | | L | 1100.00 SqFt | | | |
| 57 | WEATHERING | | L | 3900.00 SqFt | | | |
| _ | le Number: 405 | Type: | R | Area: | 5000.00 SqFt | PCI: 68 | |
| Samp | le Comments: | | | | | | |
| 57 | WEATHERING | | L | 4400.00 SqFt | | | |
| 48 | L & T CR | | L | 441.00 Ft | | | |
| 52 | RAVELING | | L | 600.00 SqFt | 5000 00 G Fr | DOI 74 | |
| _ | de Number: 410 | Type: | R | Area: | 5000.00 SqFt | PCI: 74 | |
| Samp | le Comments: | | | | | | |
| 52 | RAVELING | | L | 600.00 SqFt | | | |
| 57 48 | WEATHERING L & T CR | | L L | 4400.00 SqFt 270.00 Ft | | | |
| | le Number: 415 | Type: | R | Area: | 5000.00 SqFt | PCI: 70 | |
| _ | le Comments: | ı ype. | IV. | Aita. | 5000.00 Sqrt | 101. /0 | |
| _ | | | | | | | |
| 52 57 | RAVELING WEATHERING | | L L | 800.00 SqFt 4200.00 SqFt | | | |
| 51 | WLATHEMINU | | L | 7200.00 SYF1 | | | |

| 48 | L & T CR | L | | 382.00 Ft | | |
|------|-----------------|-------|---|--------------|--------------|----------------|
| Samp | ple Number: 423 | Type: | R | Area: | 5000.00 SqFt | PCI: 68 |
| Samp | ple Comments: | | | | | |
| 52 | RAVELING | L | | 800.00 SqFt | | |
| 57 | WEATHERING | L | | 4200.00 SqFt | | |
| 48 | L & T CR | L | | 440.00 Ft | | |
| Samp | ple Number: 429 | Type: | R | Area: | 5300.00 SqFt | PCI: 70 |
| Samp | ple Comments: | | | | | |
| 56 | SWELLING | L | | 15.00 SqFt | | |
| 57 | WEATHERING | L | | 3300.00 SqFt | | |
| 52 | RAVELING | L | | 2000.00 SqFt | | |
| 48 | L & T CR | L | | 378.00 Ft | | |

| | | | | | | Name: | GAIN | NESVILLE | REGIONAL AIR | PORT | | |
|------------|--------------------|-----------|----------|--------------------|--------------------|----------|---------------|----------|--------------|-------|--------------|---------------------|
| ranch: | RW 11- | 29 | | Name: | RUNW | AY 11-29 | | Use: | RUNWAY | Area: | 1,159,92 | 8 SqFt |
| ection: | 6207 | | of | 7 1 | From: - | | | | То: - | | La | st Const.: 2/1/2005 |
| urface: | AAC | Fan | | C9N59-PR-RV APC | V-AAC- | Zone: | | | Category: | | Ra | nk: P |
| rea: | | 17,349 Sq | Ft | Length: | | 600 Ft | | Width: | 25 Ft | | | |
| labs: | | Sla | ab Leng | th: | Ft | Slab | Width: | | Ft | Join | t Length: | Ft |
| houlder: | | Stı | reet Typ | e: | | Gra | ide: 0 | | | Lan | es: 0 | |
| ection Co | mments: | | | | | | | | | | | |
| Vork Date | : 1/1/1973 | | Woi | rk Type: BUII | LT | | | Co | ode: IMPORTE | D | Is Major M&R | : True |
| Vork Date | : 1/1/2005 | | Woi | rk Type: Patch | ning - AC De | еер | | Co | ode: PA-AD | | Is Major M&R | : False |
| Vork Date | e: 2/1/2005 | | Woi | rk Type: Mill | and Overlay | | | Co | ode: ML-OL | | Is Major M&R | : True |
| ast Insp. | Date: 4/1 | 0/2019 | | TotalS | amples: 3 | } | | Surveye | d: 1 | | | |
| Conditions | : PCI: | 70 | | | | | | | | | | |
| nspection | Comments | : | | | | | | | | | | |
| ample Nu | ımber: 50 | 0 | Туре | : R | A | rea: | 5000. | 00 SqFt | PCI: | 70 | | |
| ample Co | mments: | | | | | | | | | | | |
| 8 L& | TCR | | | L | 127.00 | Ft | | | | | | |
| | ELLING | | | L | 12.00 | 1 | | | | | | |
| | ATHERIN | | | M | | SqFt | | | | | | |
| | ATHERING VELING | 3 | | L L | 3555.00 1050.00 | | | | | | | |

| Networ | rk: GNV | | | | Nan | ne: GA | INESVILI | E REG | IONAL AIRPO | ORT | | |
|------------------|--------------------------|------------|-----------|-------------------|----------------|-------------------------|------------|---------|-------------|----------------|--------------------|--------------------|
| Branch | | | Name | e: RUN | WAY 11 | | Use | | UNWAY | Area: | 1,159,928 | 28 SqFt |
| ection | n: 6210 | of | 7 | From: | - | | | | То: - | | | st Const.: 2/1/200 |
| Surface | | Family: | C9N59-PI | R-RW-AAC- | Zon | ie: | | | Category: | | | ınk: P |
| | 215.1 | | APC | | - 200 | | | | 25 174 | | | |
| Area: | 313,13 | 50 SqFt | Leng | o . | 8,200 I | | Width: | | 25 Ft | Loint | · 4L . | ₽4 |
| Slabs: Should | • | Slab Lengt | | Ft | | Slab Width: Grade: 0 | | | Ft | Joint Lanes | t Length: es: 0 | Ft |
| | ler: n Comments: | Street Typ | ie: | | | Graue. U | | | | Lanc | s: 0 | |
| | Date: 1/1/1973 | Wor | ork Type: | BUILT | | | | Code: | IMPORTED |) I | Is Major M&R: | : True |
| Work? | Date: 1/1/1973 | Wor | rk Type: | OVERLAY | | | | Code: | IMPORTED |) I | Is Major M&R: | : True |
| Work! | Date: 1/1/2005 | Wor | rk Type: | Patching - AC D | Deep | | | Code: | PA-AD | I | Is Major M&R: | : False |
| Work! | Date: 2/1/2005 | Wor | rk Type: | Mill and Overla | ay | | | Code: | ML-OL | I _′ | Is Major M&R: | : True |
| Last Ir | nsp. Date: 4/10/2019 | 9 | Te | otalSamples: | 64 | | Surve | eyed: 1 | 13 | | | |
| Conditi | tions: PCI: 76 | | | | | | | | | | | |
| Inspect | tion Comments: | | | | | | | | | | | |
| Sample | e Number: 116 | Туре: | e: R | i | Area: | 500 | 00.00 SqFt | | PCI: 8 | 83 | | |
| Sample | e Comments: | | | | | | | | | | | |
| | WEATHERING | | L | 4750.00 | | | | | | | | |
| | WEATHERING | | M | 250.00 |) SqFt | | | | | | | |
| | L & T CR SWELLING | | L L | 98.00 10.00 |) Ft) SqFt | | | | | | | |
| | e Number: 136 | Type: | | | Area: | 500 | 00.00 SqFt | | PCI: 8 | 87 | | |
| - | e Comments: | - J 1 | • | | 110 | - | J.00 2-T | | ¥ ~ | .2 | | |
| • | | | т | 122.00 | T74 | | | | | | | |
| | L & T CR SWELLING | | L L | 123.00 25.00 |) Ft) SqFt | | | | | | | |
| | WEATHERING | | L M | 150.00 | | | | | | | | |
| | WEATHERING | | L | 4850.00 | | | | | | | | |
| Sample | e Number: 156 | Type: | e: R | | Area: | 500 | 00.00 SqFt | | PCI: 7 | 76 | | |
| Sample | e Comments: | | | | | | | | | | | |
| 57 | WEATHERING | | L | 4850.00 | SqFt | | | | | | | |
| 57 | WEATHERING | | M | 150.00 |) SqFt | | | | | | | |
| | L & T CR | | L | 278.00 |) Ft | | | | | | | |
| - | e Number: 168 | Type: | e: R | | Area: | 5000 | 00.00 SqFt | | PCI: 7 | 17 | | |
| Sample | e Comments: | | | | | | | | | | | |
| | L & T CR | | L | 262.00 | | | | | | | | |
| 57 | WEATHERING | | M | 150.00 |) SqFt | | | | | | | |
| | WEATHERING | | L | 4850.00 | | | | | | | | |
| _ | e Number: 188 | Type: | e: R | A | Area: | 5000 | 00.00 SqFt | | PCI: 7 | /4 | | |
| _ | e Comments: | | | - 32 00 | | | | | | | | |
| | L & T CR | | L M | 332.00 | | | | | | | | |
| | WEATHERING WEATHERING | | M L | 150.00 4850.00 | | | | | | | | |
| | e Number: 224 | Type: | | | Area: | 375 | 50.00 SqFt | | PCI: 7 | 74 | | |
| _ | e Comments: | <i>.</i> . | • | | 110 | | J.00 = 1 | | * - | 7 | | |
| | WEATHERING | | L | 3000.00 | · SaFt | | | | | | | |
| | L & T CR | | L L | 205.00 | - | | | | | | | |
| | WEATHERING | | M | 750.00 | | | | | | | | |
| Sample | e Number: 508 | Type: | e: R | I | Area: | 500 | 00.00 SqFt | | PCI: 7 | 75 | | |
| Sample | e Comments: | | | | | | | | | | | |
| 57 | WEATHERING | | M | 235.00 | SqFt | | | | | | | |
| | WEATHERING | | L | 4465.00 | | | | | | | | |

| 56 | SWELLING | | L | 26.00 SqFt | | | |
|------|-----------------|-------|---|--------------|--------------|---------|--|
| 48 | L & T CR | | L | 135.00 Ft | | | |
| 52 | RAVELING | | L | 300.00 SqFt | | | |
| Samp | ole Number: 524 | Type: | R | Area: | 5000.00 SqFt | PCI: 75 | |
| Samp | ole Comments: | | | | | | |
| 48 | L & T CR | | L | 262.00 Ft | | | |
| 56 | SWELLING | | L | 12.00 SqFt | | | |
| 57 | WEATHERING | | M | 250.00 SqFt | | | |
| 57 | WEATHERING | | L | 4750.00 SqFt | | | |
| Samp | ole Number: 548 | Type: | R | Area: | 5000.00 SqFt | PCI: 74 | |
| Samp | ole Comments: | | | | | | |
| 56 | SWELLING | | L | 25.00 SqFt | | | |
| 57 | WEATHERING | | L | 4850.00 SqFt | | | |
| 57 | WEATHERING | | M | 150.00 SqFt | | | |
| 56 | SWELLING | | L | 35.00 SqFt | | | |
| 48 | L & T CR | | L | 256.00 Ft | | | |
| Samp | ole Number: 560 | Type: | R | Area: | 5000.00 SqFt | PCI: 72 | |
| Samp | ole Comments: | | | | | | |
| 57 | WEATHERING | | M | 150.00 SqFt | | | |
| 57 | WEATHERING | | L | 4850.00 SqFt | | | |
| 48 | L & T CR | | L | 410.00 Ft | | | |
| Samp | ole Number: 580 | Type: | R | Area: | 5000.00 SqFt | PCI: 77 | |
| Samp | ole Comments: | | | | | | |
| 48 | L & T CR | | L | 260.00 Ft | | | |
| 57 | WEATHERING | | M | 150.00 SqFt | | | |
| 57 | WEATHERING | | L | 4850.00 SqFt | | | |
| Samp | ole Number: 604 | Type: | R | Area: | 5000.00 SqFt | PCI: 77 | |
| Samp | ole Comments: | | | | | | |
| 57 | WEATHERING | | M | 150.00 SqFt | | | |
| 57 | WEATHERING | | L | 4850.00 SqFt | | | |
| 48 | L & T CR | | L | 268.00 Ft | | | |
| Samp | ole Number: 624 | Type: | R | Area: | 3750.00 SqFt | PCI: 73 | |
| Samp | ole Comments: | | | | | | |
| 48 | L & T CR | | L | 234.00 Ft | | | |
| 57 | WEATHERING | | M | 900.00 SqFt | | | |
| 57 | WEATHERING | | L | 2850.00 SqFt | | | |

| Branch: | RW 11-29 | | Name | DIMI | WAY 11 | -29 | Use | . DI | NWAY | Area: | 1,159,92 | 2 SaFt |
|------------|---------------------|--------------|---------------|-------------------|---------|-------------|--|--------|----------------|-------------|--------------|-------------------|
| | | | | | | -29 | Use | | | Area: | | |
| Section: | 6225 | of 7 | | | - | | | | То: - | | | st Const.: 2/1/20 |
| Surface: | AAC | | 9N59-PR PC | -RW-AAC- | Zon | e: | | | Category: | | Ra | nk: P |
| Area: | 100,10 | 0 SqFt | Leng | th: | 1,000 F | it . | Width: | | 100 Ft | | | |
| Slabs: | | Slab Length | : | Ft | | Slab Width: | | | Ft | J | oint Length: | Ft |
| Shoulder: | | Street Type: | | | | Grade: 0 | | | | I | Lanes: 0 | |
| Section Co | omments: | | | | | | | | | | | |
| Work Date | e: 1/1/1983 | Work | Type: I | BUILT | | | | Code: | IMPORTED | | Is Major M&R | : True |
| Work Date | e: 1/1/1998 | Work | Type: (| OVERLAY | | | | Code: | IMPORTED | | Is Major M&R | : True |
| Work Date | e: 1/1/2005 | Work | Type: F | atching - AC I | Эеер | | | Code: | PA-AD | | Is Major M&R | : False |
| Work Date | e: 2/1/2005 | Work | Type: N | Mill and Overla | У | | | Code: | ML-OL | | Is Major M&R | : True |
| Last Insp. | Date: 4/10/2019 | | To | talSamples: | 20 | | Surve | yed: 5 | | | | |
| Conditions | s: PCI: 66 | | | | | | | | | | | |
| Inspection | Comments: | | | | | | | | | | | |
| Sample Nu | ımber: 431 | Type: | R | | Area: | 5000 | 0.00 SqFt | | PCI: 68 | 3 | | |
| Sample Co | omments: | | | | | | | | | | | |
| | EATHERING | | M | 750.00 | | | | | | | | |
| | VELING | | L | 400.00 | | | | | | | | |
| | z T CR EATHERING | | L L | 317.00 3850.00 | | | | | | | | |
| | imber: 435 | Type: | R | | Area: | 5000 |).00 SqFt | | PCI: 6' | 7 | | |
| Sample Co | | 1 у ре. | 10 | 1 | | 5000 | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | 101. 0 | , | | |
| _ | VELING | | L | 800.00 | SaEt | | | | | | | |
| | T CR | | L | 343.00 | - | | | | | | | |
| | EATHERING | | M | 750.00 | | | | | | | | |
| | ATHERING | | L | 3450.00 | | | | | | | | |
| Sample Nu | ımber: 440 | Type: | R | | Area: | 5000 | 0.00 SqFt | | PCI: 69 | | | |
| Sample Co | | | | | | | - | | | | | |
| 57 WE | EATHERING | | M | 750.00 | SqFt | | | | | | | |
| | EATHERING | | L | 3050.00 | | | | | | | | |
| | VELING | | L | 1200.00 | SqFt | | | | | | | |
| | PRESSION | | L | | SqFt | | | | | | | |
| | t T CR | | L | 284.00 | Ft | | | | | | | |
| _ | ımber: 444 | Type: | R | A | Area: | 5000 | 0.00 SqFt | | PCI: 60 | 5 | | |
| Sample Co | | | | | | | | | | | | |
| | T CR | | L | 358.00 | | | | | | | | |
| | EATHERING | | L | 3250.00 | | | | | | | | |
| | VELING EATHERING | | L M | 1000.00 750.00 | | | | | | | | |
| | ımber: 449 | Type: | R | | Area: | 5400 |).00 SqFt | | PCI: 63 | 3 | | |
| Sample Co | | V 1 | | | | | 1 | | | | | |
| 48 L& | z T CR | | L | 279.00 | Ft | | | | | | | |
| | VELING | | M | 1000.00 | | | | | | | | |
| | | | | | | | | | | | | |

| Network: GNV | | Name: | GAINESVILLER | REGIONAL AIRPO | RT | | |
|--|---|---|----------------------------|----------------|-------|------------------|----------|
| Branch: RW 11-29 | Name: | RUNWAY 11-29 | Use: | RUNWAY | Area: | 1,159,928 SqFt | |
| Section: 6230 | of 7 | From: - | | То: - | | Last Const.: | 2/1/2005 |
| Surface: AAC | Family: C9N59-PR-APC | -RW-AAC- Zone: | | Category: | | Rank: P | |
| Area: 50, | 050 SqFt Lengt | h: 2,000 Ft | Width: | 25 Ft | | | |
| Slabs: | Slab Length: | Ft Slab | Width: | Ft | Joint | Length: Ft | |
| Shoulder: | Street Type: | Grae | de: 0 | | Lanes | : 0 | |
| Section Comments: | | | | | | | |
| Work Date: 1/1/1983 | Work Type: B | UILT | Со | ode: IMPORTED | Is | Major M&R: True | |
| Work Date: 1/1/1998 | Work Type: O | VERLAY | Со | ode: IMPORTED | Is | Major M&R: True | |
| Work Date: 1/1/2005 | Work Type: Pa | atching - AC Deep | Со | ode: PA-AD | Is | Major M&R: False | |
| Work Date: 2/1/2005 | Work Type: M | Iill and Overlay | Со | ode: ML-OL | Is | Major M&R: True | |
| | | | | | | | |
| Last Insp. Date: 4/10/20 |)19 Tot : | alSamples: 12 | Surveyed | l : 3 | | | |
| _ | | alSamples: 12 | Surveyed | 1: 3 | | | |
| Conditions: PCI: 76 | | alSamples: 12 | Surveyed | 1: 3 | | | |
| Conditions: PCI: 76 | 5 | | | | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 | | Area: | Surveyed | PCI: 81 | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: | Type: R | Area: | | | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING | 5 | | | | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L&TCR | Type: R | Area: 4850.00 SqFt | | | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING | Type: R L L | Area: 4850.00 SqFt 180.00 Ft | | | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING Sample Number: 632 | Type: R L L L M | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt | 5000.00 SqFt | PCI: 81 | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING Sample Number: 632 Sample Comments: | Type: R L L L M | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt | 5000.00 SqFt | PCI: 81 | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L&TCR 57 WEATHERING Sample Number: 632 Sample Comments: 48 L&TCR | Type: R L L M Type: R | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt Area: 289.00 Ft 3637.00 SqFt | 5000.00 SqFt | PCI: 81 | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L&TCR 57 WEATHERING Sample Number: 632 Sample Comments: 48 L&TCR 57 WEATHERING | Type: R L L M Type: R | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt Area: | 5000.00 SqFt | PCI: 81 | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING Sample Number: 632 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 57 WEATHERING | Type: R L L M Type: R | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt Area: 289.00 Ft 3637.00 SqFt | 5000.00 SqFt | PCI: 81 | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING Sample Number: 632 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 WEATHERING 50 WEATHERING 50 WEATHERING 50 WEATHERING | Type: R L L M Type: R | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt Area: 289.00 Ft 3637.00 SqFt 113.00 SqFt | 5000.00 SqFt 3750.00 SqFt | PCI: 81 | | | |
| Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L&TCR 57 WEATHERING Sample Number: 632 Sample Comments: 48 L&TCR 57 WEATHERING | Type: R L L M Type: R | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt Area: 289.00 Ft 3637.00 SqFt 113.00 SqFt | 5000.00 SqFt 3750.00 SqFt | PCI: 81 | | | |
| Conditions: PCI: 76 Inspection Comments: Sample Number: 240 Sample Comments: 57 WEATHERING 48 L & T CR 57 WEATHERING Sample Number: 632 Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 WEATHERING 50 Sample Number: 644 Sample Comments: | Type: R L L M Type: R L L M Type: R | Area: 4850.00 SqFt 180.00 Ft 150.00 SqFt Area: 289.00 Ft 3637.00 SqFt 113.00 SqFt Area: | 5000.00 SqFt 3750.00 SqFt | PCI: 81 | | | |

| Netwo | rk: GNV | | | Nai | me: GAINESVIL | LE REGIONAL AIRPO | RT |
|------------------|------------------------------|--------------|-----------------|--------------------------|---------------|-------------------|------------------------------|
| Branc | h: RW 7-25 | | Name: | RUNWAY 7 | -25 Us | e: RUNWAY | Area: 415,800 SqFt |
| Section | n: 6105 | of 1 | | From: - | | То: - | Last Const.: 9/1/2015 |
| Surfac | ee: AAC | | 9N59-PR-R PC | W-AAC- Zoi | ne: | Category: | Rank: S |
| Area: | 415,80 | 00 SqFt | Length | : 4,000 | Ft Width: | 80 Ft | |
| Slabs: | | Slab Length | | Ft | Slab Width: | Ft | Joint Length: Ft |
| Should | | Street Type: | | | Grade: 0 | | Lanes: 0 |
| Section | n Comments: | | | | | | |
| | Date: 1/1/1972 | | Type: BU | | | Code: IMPORTED | Is Major M&R: True |
| | Date: 9/1/2015 | | | LL and OVERLAY | | Code: ML-OV | Is Major M&R: True |
| | nsp. Date: 4/10/2019 | 9 | 1 otal | Samples: 83 | Surv | veyed: 17 | |
| | tions: PCI: 89 | | | | | | |
| | tion Comments: | | | | | | |
| _ | e Number: 500 | Type: | R | Area: | 5000.00 SqFt | PCI: 89 | |
| Sampl | e Comments: | | | | | | |
| 48 | L & T CR | | L | 40.00 Ft | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | 5000 00 G F | DCI 00 | |
| _ | e Number: 507 | Туре: | R | Area: | 5000.00 SqFt | PCI: 89 | |
| _ | e Comments: | | | | | | |
| 57 1 8 | WEATHERING L & T CR | | L L | 5000.00 SqFt 81.00 Ft | | | |
| | e Number: 511 | Type: | R | Area: | 5000.00 SqFt | PCI: 89 | |
| _ | e Comments: | | | | • | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | |
| 48 | L & T CR | | L | 64.00 Ft | | | |
| Sampl | e Number: 514 | Type: | R | Area: | 5000.00 SqFt | PCI: 88 | |
| Sampl | e Comments: | | | | | | |
| 48 | L & T CR | | L | 89.00 Ft | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | |
| Sampl | e Number: 518 | Type: | R | Area: | 5000.00 SqFt | PCI: 89 | |
| Sampl | e Comments: | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | |
| 48 | L & T CR | | L | 72.00 Ft | | | |
| - | e Number: 521 | Type: | R | Area: | 5000.00 SqFt | PCI: 92 | |
| Sampl | e Comments: | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | |
| 48 | L & T CR | T | L | 2.00 Ft | 5000 00 G F | DCI. 01 | |
| _ | e Number: 525 e Comments: | Туре: | R | Area: | 5000.00 SqFt | PCI : 91 | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | |
| 48 | L & T CR | | L | 12.00 Ft | | | |
| Sampl | e Number: 528 | Type: | R | Area: | 5000.00 SqFt | PCI: 89 | |
| Sampl | e Comments: | | | | | | |
| 48 | L & T CR | | L | 61.00 Ft | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | |
| _ | e Number: 534 | Type: | R | Area: | 5000.00 SqFt | PCI: 89 | |
| Sampl | e Comments: | | | | | | |
| 48 | L & T CR | | L | 45.00 Ft | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | |

| Sample Number: 543 | Type: R | Area: | 5000.00 SqFt | PCI: 88 | |
|-------------------------|---------|--------------|--------------|----------------|--|
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 5000.00 SqFt | | | |
| 48 L & T CR | L | 99.00 Ft | | | |
| Sample Number: 551 | Type: R | Area: | 5000.00 SqFt | PCI: 90 | |
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 5000.00 SqFt | | | |
| 48 L & T CR | L | 21.00 Ft | | | |
| Sample Number: 556 | Type: R | Area: | 5000.00 SqFt | PCI: 88 | |
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 5000.00 SqFt | | | |
| 48 L & T CR | L | 87.00 Ft | | | |
| Sample Number: 561 | Type: R | Area: | 5000.00 SqFt | PCI: 89 | |
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 5000.00 SqFt | | | |
| 48 L & T CR | L | 49.00 Ft | | | |
| Sample Number: 567 | Type: R | Area: | 5000.00 SqFt | PCI: 89 | |
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 5000.00 SqFt | | | |
| 48 L & T CR | L | 68.00 Ft | | | |
| Sample Number: 570 | Type: R | Area: | 5000.00 SqFt | PCI: 89 | |
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 5000.00 SqFt | | | |
| 48 L & T CR | L | 69.00 Ft | | | |
| Sample Number: 574 | Type: R | Area: | 5000.00 SqFt | PCI: 87 | |
| Sample Comments: | | | | | |
| 56 SWELLING | L | 2.00 SqFt | | | |
| 57 WEATHERING | L | 5000.00 SqFt | | | |
| 48 L & T CR | L | 87.00 Ft | | | |
| Sample Number: 581 | Type: R | Area: | 5800.00 SqFt | PCI: 89 | |
| Sample Comments: | | | | | |
| 57 WEATHERING | L | 5800.00 SqFt | | | |
| 48 L & T CR | L | 73.00 Ft | | | |
| | | | | | |

| | | Name: | GAINES VILLE | REGIONAL AIRPOR | T | |
|---|----------------------------|---|-----------------------------------|-----------------|----------|---------------------------------------|
| Branch: TL T-HANG | Name: | TL T-HANGAR | Use: | TAXILANE | Area: | 52,426 SqFt |
| Section: 3105 | of 1 | From: - | | То: - | | Last Const.: 7/1/20 |
| Surface: AAC | Family: C9N59-PR-TV APC | W-AAC- Zone: | | Category: | | Rank: P |
| Area: 52,426 | 6 SqFt Length: | 1,800 Ft | Width: | 20 Ft | | |
| Slabs: | Slab Length: | Ft Sla | b Width: | Ft | Joint Le | ngth: Ft |
| Shoulder: | Street Type: | Gr | nde: 0 | | Lanes: | 0 |
| Section Comments: | | | | | | |
| Work Date: 1/1/1991 | Work Type: BUI | LT | C | ode: IMPORTED | Is M | ajor M&R: True |
| Work Date: 7/1/2009 | Work Type: MIL | L and OVERLAY | C | ode: ML-OV | Is M | ajor M&R: True |
| Work Date: 7/2/2009 | Work Type: Surf | ace Treatment - Double | Bitum. C | ode: SU-DB | Is M | ajor M&R: False |
| Work Date: 1/1/2018 | Work Type: Crac | k Sealing - AC | C | ode: CS-AC | Is M | ajor M&R: False |
| | • • | | | | | |
| Last Insp. Date: 4/10/2019 | | Samples: 11 | Surveye | | | |
| Conditions: PCI: 63 | | | | | | · · · · · · · · · · · · · · · · · · · |
| • | | | | | | |
| Conditions: PCI: 63 Inspection Comments: | TotalS | Samples: 11 | Surveye | d: 3 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 | TotalS | Samples: 11 | Surveye | d: 3 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 Sample Comments: 48 L&TCR | Totals Type: R | Area: 564.00 Ft | Surveye | d: 3 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 Sample Comments: 48 L & T CR 52 RAVELING | Totals Type: R L L | Area: 564.00 Ft 3000.00 SqFt | Surveye 5000.00 SqFt | d: 3 PCI: 70 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 Sample Comments: 48 L & T CR 52 RAVELING Sample Number: 302 Sample Comments: 43 BLOCK CR | Type: R L L Type: R | Area: 564.00 Ft 3000.00 SqFt Area: | Surveye 5000.00 SqFt | d: 3 PCI: 70 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 Sample Comments: 48 L & T CR 52 RAVELING Sample Number: 302 Sample Comments: 43 BLOCK CR 52 RAVELING | Type: R L L Type: R | Area: 564.00 Ft 3000.00 SqFt Area: 4680.00 SqFt 1872.00 SqFt | Surveye 5000.00 SqFt 4680.00 SqFt | PCI: 70 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 Sample Comments: 48 L & T CR 52 RAVELING Sample Number: 302 Sample Comments: 43 BLOCK CR 52 RAVELING Sample Number: 400 | Type: R L L Type: R | Area: 564.00 Ft 3000.00 SqFt Area: | Surveye 5000.00 SqFt | d: 3 PCI: 70 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 Sample Comments: 48 L & T CR 52 RAVELING Sample Number: 302 Sample Comments: 43 BLOCK CR 52 RAVELING | Type: R L L Type: R | Area: 564.00 Ft 3000.00 SqFt Area: 4680.00 SqFt 1872.00 SqFt | Surveye 5000.00 SqFt 4680.00 SqFt | PCI: 70 | | |
| Conditions: PCI: 63 Inspection Comments: Sample Number: 201 Sample Comments: 48 L & T CR 52 RAVELING Sample Number: 302 Sample Comments: 43 BLOCK CR 52 RAVELING Sample Number: 400 | Type: R L L Type: R | Area: 564.00 Ft 3000.00 SqFt Area: 4680.00 SqFt 1872.00 SqFt | Surveye 5000.00 SqFt 4680.00 SqFt | PCI: 70 | | |

| Network: | GNV | | | | Nan | ne: GA | INESVILLE | REG | IONAL AIRPOR | RT | | | |
|-------------------|--------------------|-------------|-----------------|-----------------|-------|----------------|-----------|------|--------------|-----------|-----------|-----------|----------|
| Branch: | TW A | | Name | : TAXI | WAY A | | Use: | TA | AXIWAY | Area: | 377,00 | 7 SqFt | |
| Section: | 104 | | of 17 | From: | - | | | | To: - | | Las | t Const.: | 1/1/2015 |
| Surface: | AAC | Family: | C9N59-PR APC | -TW-AAC- | Zon | e: | | | Category: | | Rai | nk: P | |
| Area: | | 13,820 SqFt | Leng | th: | 480 I | ² t | Width: | | 56 Ft | | | | |
| Slabs: | | Slab Le | ength: | Ft | | Slab Width: | | | Ft | Joint Lei | ngth: | F | t |
| Shoulder: | | Street 7 | Гуре: | | | Grade: 0 | | | | Lanes: | 0 | | |
| Section Co | omments: | | | | | | | | | | | | |
| Work Dat | e: 1/1/1968 | V | Vork Type: I | BUILT | | | C | ode: | IMPORTED | Is M | ajor M&R: | True | |
| Work Dat | e: 1/1/1973 | V | Vork Type: (| OVERLAY | | | C | ode: | IMPORTED | Is M | ajor M&R: | True | |
| Work Dat | e: 12/25/201 | 11 V | Vork Type: (| Crack Sealing - | AC | | C | ode: | CS-AC | Is M | ajor M&R: | False | |
| Work Dat | e: 1/1/2015 | v | Vork Type: N | MILL and OVE | RLAY | | C | ode: | ML-OV | Is M | ajor M&R: | True | |
| Last Insp. | Date: 4/10 | 0/2019 | То | talSamples: | 3 | | Surveye | ed: | 1 | | | | |
| Condition | s: PCI: | 89 | | | | | | | | | | | |
| Inspection | Comments: | : | | | | | | | | | | | |
| Sample Ni | umber: 101 | 1 Ty | pe: R | A | Area: | 500 | 0.00 SqFt | | PCI: 89 | | | | |
| Sample Co | omments: | | | | | | | | | | | | |
| 48 L <i>&</i> | Ł T CR | | L | 11.00 | Ft | | | | | | | | |
| | ELLING | | L | | SqFt | | | | | | | | |
| 57 WE | EATHERING | ì | L | 5000.00 | SqFt | | | | | | | | |

| N | 1 CNIV | | - | CAREOUH LE DI | COLONIAL AIRPORT | |
|--------|-------------------------|----------------------|--------------------|---------------|------------------|------------------------------|
| Netwo | | | Name | | EGIONAL AIRPORT | |
| Branc | ch: TW A | Name: | TAXIWAY A | Use: | TAXIWAY Are | ea: 377,007 SqFt |
| Sectio | on: 105 | of 17 | From: - | | To: - | Last Const.: 1/1/1973 |
| Surfac | ce: AAC | Family: C9N59-PR-APC | TW-AAC- Zone: | | Category: | Rank: P |
| Area: | 80,019 | 9 SqFt Lengt | h: 1,486 Ft | Width: | 50 Ft | |
| Slabs: | : | Slab Length: | Ft S | Slab Width: | Ft | Joint Length: Ft |
| Shoul | der: | Street Type: | • | Grade: 0 | | Lanes: 0 |
| Sectio | on Comments: | | | | | |
| Work | Date: 1/1/1968 | Work Type: B | UILT | Cod | e: IMPORTED | Is Major M&R: True |
| Work | Date: 1/1/1973 | Work Type: O | VERLAY | Cod | e: IMPORTED | Is Major M&R: True |
| Work | Date: 12/25/2011 | Work Type: C | rack Sealing - AC | Cod | e: CS-AC | Is Major M&R: False |
| Last I | nsp. Date: 4/10/2019 | Tot | alSamples: 16 | Surveyed: | 3 | |
| Condi | itions: PCI: 30 | | | | | |
| Inspec | ction Comments: | | | | | |
| Samp | le Number: 103 | Type: R | Area: | 5083.00 SqFt | PCI: 33 | |
| Samp! | le Comments: | | | | | |
| 42 | BLEEDING | N | 104.00 SqFt | | | |
| 48 | L & T CR | L | 424.00 Ft | | | |
| 52 | RAVELING | M | 5083.00 SqFt | | | |
| Sampl | le Number: 109 | Type: R | Area: | 5000.00 SqFt | PCI: 27 | |
| Sampl | le Comments: | | | | | |
| 53 | RUTTING | L | 60.00 SqFt | | | |
| 52 | RAVELING | M | 5000.00 SqFt | | | |
| 48 | L & T CR | L | 644.00 Ft | | | |
| 41 | ALLIGATOR CR | L | 150.00 SqFt | | | |
| Sampl | le Number: 115 | Type: R | Area: | 5000.00 SqFt | PCI: 30 | |
| Samp | le Comments: | | | | | |
| 43 | BLOCK CR | L | 813.00 SqFt | | | |
| 53 | RUTTING | L | 54.00 SqFt | | | |
| 52 | RAVELING | M | 3750.00 SqFt | | | |
| 52 | RAVELING | L | 1248.00 SqFt | | | |
| 48 | L & T CR | L | 465.00 Ft | | | |
| 50 | PATCHING | L | 2.00 SqFt | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** TW A TAXIWAY A Use: TAXIWAY 377,007 SqFt Name: Area: of 17 Section: 108 **Last Const.:** 1/1/2005 From: To: -Surface: AAC Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P APC Width: 50 Ft 6,264 SqFt Length: 100 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: 0 **Section Comments:** Work Type: BUILT Work Date: 1/1/1991 Code: IMPORTED Is Major M&R: True Work Date: 1/1/2005 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 72 Sample Number: 100 R 6264.00 SqFt Type: Area: **Sample Comments:** 57 WEATHERING M 6264.00 SqFt SWELLING 56 L 65.00 SqFt 48 L & T CR L 294.00 Ft

| Network: | GNV | | | | Name: | GAI | NESVILLE | REGIO | ONAL AIRP | ORT | | | |
|--------------------|---------------------------------------|-----------|-----------------|--------------|--------|----------|----------|-------|-----------|-------|--------------|-------------|----------------|
| Branch: | TW A | | Name: | TAXIV | VAY A | | Use: | TAX | KIWAY | Area: | : | 377,007 SqF | ft |
| Section: 11 | 0 | of | f 17 | From: | | | | 7 | Го: - | | | Last Cor | nst.: 1/1/2012 |
| Surface: A | AC | Family: | C9N59-PR APC | -TW-AAC- | Zone: | | | (| Category: | | | Rank: | P |
| Area: | 50 | ,240 SqFt | Leng | h: | 430 Ft | | Width: | | 50 Ft | | | | |
| Slabs: | | Slab Len | gth: | Ft | Sla | b Width: | | F | 7t | J | oint Length: | | Ft |
| Shoulder: | | Street Ty | pe: | | Gra | ade: 0 | | | | L | anes: 0 | | |
| Section Comm | ments: | | | | | | | | | | | | |
| Work Date: | 1/1/1968 | Wo | ork Type: B | UILT | | | C | ode: | IMPORTED |) | Is Major | M&R: Tru | e |
| Work Date: | 1/1/1973 | We | ork Type: C | VERLAY | | | C | ode: | IMPORTEI |) | Is Major | M&R: Tru | e |
| Work Date: | 1/1/2012 | We | ork Type: M | IILL and OVE | RLAY | | C | ode: | ML-OV | | Is Major | M&R: Tru | e |
| Last Insp. Da | te: 4/10/2 | 019 | Tot | alSamples: | 10 | | Surveye | ed: 2 | | | | | |
| Conditions: | PCI: 8 | 9 | | | | | | | | | | | |
| Inspection Co | omments: | | | | | | | | | | | | |
| Sample Numb | ber: 119 | Тур | e: R | A | rea: | 5000 | .00 SqFt | | PCI: | 88 | | | |
| Sample Comr | ments: | | | | | | | | | | | | |
| 48 L & T | CR | | L | 15.00 | Ft | | | | | | | | |
| | THERING | | M | 100.00 | SqFt | | | | | | | | |
| 57 WEAT | THERING | | L | 4900.00 | SqFt | | | | | | | | |
| Sample Numb | ber: 125 | Тур | e: R | A | rea: | 5000 | .00 SqFt | | PCI: | 89 | | | |
| Sample Comr | ments: | | | | | | | | | | | | |
| 48 L & T | CR | | L | 25.00 | Ft | | | | | | | | |
| 57 WEAT | THERING | | L | 5000.00 | SqFt | | | | | | | | |
| 57 WEAT | · · · · · · · · · · · · · · · · · · · | | | 9.00 | | | | | | | | | |

| Network: | GNV | | | | Name: | GAINESVILL | E REG | IONAL AIRPOR | RT | | | |
|--------------|---------------|-----------|------------------|-----------------|-------------------|--------------|-------|----------------|---------|-----------|------------|----------|
| Branch: | TW A | | Name: | TAXIV | VAY A | Use | TA | AXIWAY | Area: | 377,00 | 7 SqFt | |
| Section: | 115 | of | f 17 | From: - | | | | То: - | | Las | st Const.: | 7/1/2009 |
| Surface: | AAC | Family: | C9N59-PR- APC | TW-AAC- | Zone: | | | Category: | | Ra | nk: P | |
| Area: | 22, | 645 SqFt | Lengtl | h: | 370 Ft | Width: | | 50 Ft | | | | |
| Slabs: | | Slab Len | gth: | Ft | Slab Wie | dth: | | Ft | Joint I | Length: | F | t |
| Shoulder: | | Street Ty | pe: | | Grade: | 0 | | | Lanes | : 0 | | |
| Section Cor | nments: | | | | | | | | | | | |
| Work Date: | : 1/1/1973 | W | ork Type: BU | JILT | | | Code: | IMPORTED | Is | Major M&R | : True | |
| Work Date: | : 1/1/2002 | W | ork Type: Ov | verlay - AC Str | ructural | | Code: | OL-AS | Is | Major M&R | : True | |
| Work Date: | : 1/1/2002 | W | ork Type: Co | old Milling | | | Code: | MI-CO | Is | Major M&R | : False | |
| Work Date: | : 7/1/2009 | W | ork Type: M | ill and Overlay | , | | Code: | ML-OL | Is | Major M&R | : True | |
| Work Date: | : 7/2/2009 | W | ork Type: Su | ırface Treatmer | nt - Double Bitun | 1. | Code: | SU-DB | Is | Major M&R | : False | |
| Last Insp. I | Date: 4/10/20 | 119 | Tota | alSamples: | 1 | Surve | yed: | 1 | | | | |
| Conditions: | PCI: 60 |) | | | | | | | | | | |
| Inspection (| Comments: | | | | | | | | | | | |
| Sample Nui | mber: 101 | Тур | e: R | A | rea: | 5017.00 SqFt | | PCI: 60 | | | | |
| Sample Cor | mments: | | | | | | | | | | | |
| 52 RAV | /ELING | | L | 5017.00 | SqFt | | | | | | | |
| 56 SWE | ELLING | | L | 67.00 | SqFt | | | | | | | |
| 48 L& | T CR | | M | 20.00 | Ft | | | | | | | |
| 48 L & | T CR | | L | 308.00 | Ft | | | | | | | |

| Network: | GNV | | | | Name: | GAl | INESVILLE | REGI | ONAL AIRPOI | RT | | | |
|--------------|-------------------|-------------|-----------------|------------------|-------------|----------|-----------|--------------|-------------|-----------|-----------|---------|----------|
| Branch: | TW A | | Name | e: TAXIV | WAY A | | Use: | TA | XIWAY | Area: | 377,007 | SqFt | |
| Section: | 117 | C | f 17 | From: | - | | | | То: - | | Last | Const.: | 7/1/2009 |
| Surface: | AAC | Family: | C9N59-PI APC | R-TW-AAC- | Zone: | | | | Category: | | Ran | k: P | |
| Area: | | 9,679 SqFt | Leng | gth: | 202 Ft | | Width: | | 50 Ft | | | | |
| Slabs: | | Slab Lei | ngth: | Ft | Sla | b Width: | | | Ft | Joint Len | igth: | F | t |
| Shoulder: | | Street T | ype: | | Gr | rade: 0 | | | | Lanes: | 0 | | |
| Section Co | mments: | | | | | | | | | | | | |
| Work Date | : 1/1/1973 | W | ork Type: | BUILT | | | (| Code: | IMPORTED | Is Ma | ajor M&R: | True | |
| Work Date | : 1/1/2002 | W | ork Type: | Overlay - AC St | ructural | | (| Code: | OL-AS | Is Ma | ajor M&R: | True | |
| Work Date | : 1/1/2002 | W | ork Type: | Cold Milling | | | (| Code: | MI-CO | Is Ma | ajor M&R: | False | |
| Work Date | : 7/1/2009 | W | ork Type: | Mill and Overlay | y | | (| Code: | ML-OL | Is Ma | ajor M&R: | True | |
| Work Date | : 7/2/2009 | W | ork Type: | Surface Treatme | nt - Double | Bitum. | (| Code: | SU-DB | Is Ma | ajor M&R: | False | |
| Last Insp. 1 | Date: 4/10 |)/2019 | To | otalSamples: | 2 | | Survey | ed: 1 | | | | | |
| Conditions | : PCI: | 69 | | | | | | | | | | | |
| Inspection | Comments | : | | | | | | | | | | | |
| Sample Nu | mber: 100 | 0 Ty | pe: R | A | rea: | 5411 | 1.00 SqFt | | PCI: 69 |) | | | |
| Sample Co | mments: | | | | | | | | | | | | |
| 48 L& | T CR | | L | 359.00 | Ft | | | | | | | | |
| 52 RAV | VELING | | L | 5411.00 | SqFt | | | | | | | | |

| Network: | GNV | | | | Name: | GAI | NESVILLE | REGIO | NAL AIRPO | RT | | | |
|------------|-------------------|---------------------|--------------------|---------------|-----------|------------|----------|-------|-----------|---------|-----------|------------|----------|
| Branch: | TW A | | Name: | TAXIW | AY A | | Use: | TAX | IWAY | Area: | 377,00 | 7 SqFt | |
| Section: | 119 | 0 | of 17 | From: - | | | | Т | o: - | | La | st Const.: | 7/1/2009 |
| Surface: | AAC | Family: | C9N59-PR-TV APC | W-AAC- | Zone: | | | C | Category: | | Ra | nk: P | |
| Area: | | 4,962 SqFt | Length: | | 202 Ft | | Width: | | 50 Ft | | | | |
| Slabs: | | Slab Lei | ngth: | Ft | Sl | lab Width: | | F | t | Joint 1 | Length: | F | ₹t |
| Shoulder: | | Street T | ype: | | G | rade: 0 | | | | Lanes | : 0 | | |
| Section Co | mments: | | | | | | | | | | | | |
| Work Date | e: 1/1/1972 | W | Vork Type: BUI | LT | | | C | ode: | IMPORTED | Is | Major M&R | : True | |
| Work Date | e: 7/1/2009 | W | ork Type: MIL | L and OVER | LAY | | C | ode: | ML-OV | Is | Major M&R | : True | |
| Work Date | e: 7/1/2009 | W | ork Type: Surf | face Treatmen | t - Doubl | e Bitum. | C | ode: | SU-DB | Is | Major M&R | : False | |
| Last Insp. | Date: 4/10 | 0/2019 | Totals | Samples: 1 | | | Surveye | ed: 1 | | | | | |
| Conditions | s: PCI: | 59 | | | | | | | | | | | |
| Inspection | Comments | : | | | | | | | | | | | |
| Sample Nu | ımber: 10 | $\overline{0}$ Ty | pe: R | Aı | ea: | 4962 | .00 SqFt | | PCI: 59 |) | | | |
| Sample Co | omments: | | | | | | | | | | | | |
| 52 RA | VELING | | L | 4874.00 | SqFt | | | | | | | | |
| 48 L & | z T CR | | L | 343.00 | Ft | | | | | | | | |
| 50 PA | TCHING | | L | 88.00 | SqFt | | | | | | | | |
| 43 BL | OCK CR | | L | 470.00 | SaFt | | | | | | | | |

| Network: | GNV | | | | Na | me: G | AINESVILLE | REGI | ONAL AIR | PORT | | | | |
|-----------------|----------------------|--------------|--------------|------------|-------------------------|------------|------------|---------------|-----------|------|---------|---------|----------------------|----------|
| Branch: | TW A | | Na | ıme: | TAXIWAY | A | Use: | TA | XIWAY | Ar | ea: | 37 | 77,007 SqFt | |
| Section: | 120 | of | 17 | Fron | n: - | | | | То: - | | | | Last Const.: | 1/1/2012 |
| Surface: | AAC | Family: | C9N59 APC | PR-TW-A | AC- Zo | ne: | | | Category: | | | | Rank: P | |
| Area: | | 98,695 SqFt | L | ength: | 1,880 | Ft | Width: | | 50 Ft | | | | | |
| Slabs: | | Slab Len | gth: | | Ft | Slab Width | : | | Ft | | Joint L | ength: | F | t |
| Shoulder: | | Street Ty | pe: | | | Grade: |) | | | | Lanes: | 0 | | |
| Section Co | omments: | | | | | | | | | | | | | |
| Work Date | e: 1/1/1972 | Wo | ork Typ | e: New Cor | nstruction - Ini | itial | C | Code: | NU-IN | | Is N | Aajor N | 1&R: True | |
| Work Date | e: 1/1/2012 | Wo | ork Typ | e: MILL an | d OVERLAY | | C | ode: | ML-OV | | Is N | Aajor N | 1&R: True | |
| Conditions | Date: 4/10 s: PCI: | 91 | | TotalSamp | oles: 20 | | Surveyo | e d: 3 | | | | | | |
| Sample Nu | umber: 130 | 0 Typ | e: | R | Area: | 50 | 00.00 SqFt | | PCI: | 90 | | | | |
| Sample Co | omments: | | | | | | | | | | | | | |
| | t CR EATHERING | ì | L L | 50 | 18.00 Ft 000.00 SqFt | | | | | | | | | |
| Sample Nu | ımber: 139 | 9 Typ | e: | R | Area: | 50 | 00.00 SqFt | | PCI: | 92 | | | | |
| Sample Co | omments: | | | | | | | | | | | | | |
| Sample Co | | j | L | 50 | 000.00 SqFt | | | | | | | | | |
| 57 WE | EATHERING & T CR | | L | | 6.00 Ft | | | | | | | | | |
| 57 WE 48 L & | | 6 Тур | | R | Area: | 50 | 00.00 SqFt | | PCI: | 90 | | | | |
| 57 WE 48 L & | t T CR umber: 140 | 6 Тур | | R | | 50 | 00.00 SqFt | | PCI: | 90 | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** TW A TAXIWAY A Use: TAXIWAY 377,007 SqFt Name: Area: 130 of 17 **Last Const.:** 1/1/1979 Section: From: To: Surface: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Area: 11,380 SqFt Length: 380 Ft Width: 40 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1979 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 12/25/2011 Work Type: Surface Treatment - Seal Coat Code: ST-SC Is Major M&R: False **Last Insp. Date:** 4/10/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 64 **Inspection Comments:** R 3380.00 SqFt **PCI:** 64 Sample Number: 150 Type: Area: **Sample Comments:** L & T CR L 459.00 Ft 48 RAVELING L 2704.00 SqFt 52 57 WEATHERING L 676.00 SqFt

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: Branch: TW A TAXIWAY A Use: TAXIWAY 377,007 SqFt Name: Area: 135 of 17 Section: From: To: **Last Const.:** 1/1/1980 Surface: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Area: 20,258 SqFt Length: 500 Ft Width: 40 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1980 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 12/25/2011 Work Type: Surface Treatment - Seal Coat Code: ST-SC Is Major M&R: False **Last Insp. Date:** 4/10/2019 **TotalSamples:** 5 Surveyed: 1 **Conditions: PCI:** 60 **Inspection Comments:** R 4000.00 SqFt **PCI:** 60 Sample Number: 154 Type: Area: **Sample Comments:** RAVELING L 3800.00 SqFt 52 RAVELING M 200.00 SqFt 52 L & T CR L 439.00 Ft 48

| Netwo | rk: | GNV | | | | | | Nai | me: | GAI | NESVILLE | REGIO | NAL AIR | PORT | | | | |
|---------|--------|------------------|--------|-----------|--------|-----------|---------|-------|----------|-------|----------|--------|----------|------|----------|---------|--------------|----------|
| Brancl | ı: | TW A | | |] | Name: | TAXI | WAY A | A | | Use: | TAX | IWAY | Ar | ea: | 3 | 77,007 SqFt | |
| Section | ı: 1 | 140 | | of | f 17 | F | rom: | - | | | | T | o: - | | | | Last Const.: | 1/1/1992 |
| Surfac | e: / | AC | | Family: | C9N | 59-PR-TW | -AC | Zor | ie: | | | C | ategory: | | | | Rank: P | |
| Area: | | | 32,303 | 3 SqFt | | Length: | | 925 | Ft | | Width: | | 35 F | t | | | | |
| Slabs: | | | | Slab Len | gth: | | Ft | | Slab Wid | th: | | Ft | | | Joint Le | ength: | F | `t |
| Should | ler: | | | Street Ty | pe: | | | | Grade: | 0 | | | | | Lanes: | 0 | | |
| Section | ı Con | nments: | | | | | | | | | | | | | | | | |
| Work | Date: | : 1/1/1992 | 2 | W | ork Ty | ype: BUIL | T | | | | C | ode: I | MPORTE | ED | Is N | 1ajor N | M&R: True | |
| Last Ir | ısp. D | Date: 4/1 | 0/2019 | | | TotalSa | mples: | 9 | | | Surveye | d: 2 | | | | | | |
| Condit | ions: | PCI: | 37 | | | | | | | | | | | | | | | |
| Inspec | tion (| Comment | s: | | | | | | | | | | | | | | | |
| Sample | e Nur | mber: 15 | 58 | Тур | e: | R | A | rea: | : | 3500. | 00 SqFt | | PCI: | 37 | | | | |
| Sample | e Con | mments: | | | | | | | | | | | | | | | | |
| 48 | L & ' | T CR | | | L | | 177.00 | Ft | | | | | | | | | | |
| 57 | WEA | ATHERIN | G | | Н |] | 2350.00 | SqFt | | | | | | | | | | |
| | | ATHERIN | G | | N | | 950.00 | - | | | | | | | | | | |
| 52 | RAV | /ELING | | | L | | 200.00 | SqFt | | | | | | | | | | |
| Sample | e Nur | mber: 16 | 51 | Typ | e: | R | A | rea: | : | 3500. | 00 SqFt | | PCI: | 37 | | | | |
| Sample | e Con | mments: | | | | | | | | | | | | | | | | |
| 57 | WEA | ATHERIN | G | | N | 1 | 950.00 | SqFt | | | | | | | | | | |
| 57 | WEA | ATHERIN | G | | Н | [| 2350.00 | - | | | | | | | | | | |
| 52 | RAV | /ELING | | | L | | 200.00 | SqFt | | | | | | | | | | |
| 48 | L & ' | T CR | | | L | | 108.00 | Ft | | | | | | | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** TW A TAXIWAY A Use: TAXIWAY Area: 377,007 SqFt Name: Section: 143 of 17 **Last Const.:** 1/1/1992 From: To: Surface: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Area: 5,547 SqFt Length: 100 Ft Width: 35 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1992 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 1 Surveyed: 1 **Conditions: PCI:** 46 **Inspection Comments:** 5547.00 SqFt **PCI:** 46 Sample Number: 100 Type: R Area: **Sample Comments:** 52 RAVELING L 2797.00 SqFt 56 **SWELLING** L 18.00 SqFt RAVELING 52 M 2750.00 SqFt

359.00 Ft

L

L & T CR

48

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: Branch: TW A TAXIWAY A Use: TAXIWAY 377,007 SqFt Name: Area: 147 of 17 Section: From: To: **Last Const.:** 1/1/1980 Surface: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P 99 Ft Area: 3,947 SqFt Length: Width: 40 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1980 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 7/2/2009 Work Type: Surface Treatment - Double Bitum. Code: SU-DB Is Major M&R: False **Last Insp. Date:** 4/10/2019 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 3947.00 SqFt **PCI:** 58 Sample Number: 100 Type: Area: **Sample Comments:** RAVELING L 197.00 SqFt 52 SWELLING L 2.00 SqFt 56 BLOCK CR L 3947.00 SqFt 43

GNV Network: GAINESVILLE REGIONAL AIRPORT Name: Branch: TW A TAXIWAY A Use: TAXIWAY 377,007 SqFt Name: Area: 149 of 17 From: Section: To: -Last Const.: 7/1/2009 Family: C9N59-PR-TW-AAC-Zone: Rank: P Surface: $\mathsf{A}\mathsf{A}\mathsf{C}$ Category: APC Width: 4,225 SqFt Length: 109 Ft 40 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1980 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 7/1/2009 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True Work Date: 7/2/2009 Work Type: Surface Treatment - Double Bitum. Code: SU-DB Is Major M&R: False TotalSamples: 1 **Last Insp. Date:** 4/10/2019 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 100 R **PCI:** 68 Type: Area: 4225.00 SqFt **Sample Comments:** 52 RAVELING L 211.00 SqFt

48

L & T CR

L

540.00 Ft

| Network: | GNV | | | | Nan | ne: GAl | NESVILLE | REGIC | NAL AIRPO | RT | | | |
|--------------|------------|------------|----------------|-----------------|----------|-------------|-----------|-------|-----------|---------|------------|---------|----------|
| Branch: | TW A | | Nam | e: TAXI | WAY A | 1 | Use: | TAX | IWAY | Area: | 377,007 \$ | SqFt | |
| Section: | 152 | 0 | f 17 | From: | - | | | Т | `o: - | | Last (| Const.: | 7/1/2009 |
| Surface: | AAC | Family: | C9N59-P APC | R-TW-AAC- | Zon | e: | | C | Category: | | Rank | : P | |
| Area: | | 3,939 SqFt | Len | gth: | 65 I | ₹t | Width: | | 50 Ft | | | | |
| Slabs: | | Slab Len | igth: | Ft | | Slab Width: | | F | 't | Joint I | Length: | F | t |
| Shoulder: | | Street T | ype: | | | Grade: 0 | | | | Lanes: | : 0 | | |
| Section Cor | mments: | | | | | | | | | | | | |
| Work Date | : 1/1/1979 | W | ork Type: | BUILT | | | C | ode: | IMPORTED | Is | Major M&R: | True | |
| Work Date | : 7/1/2009 | W | ork Type: | MILL and OVE | RLAY | | C | ode: | ML-OV | Is | Major M&R: | True | |
| Work Date | : 7/2/2009 | W | ork Type: | Surface Treatme | ent - Do | uble Bitum. | C | ode: | SU-DB | Is | Major M&R: | False | |
| Last Insp. I | Date: 4/10 | /2019 | Te | otalSamples: | 1 | | Surveye | ed: 1 | | | | | |
| Conditions: | : PCI: | 85 | | | | | | | | | | | |
| Inspection (| Comments: | | | | | | | | | | | | |
| Sample Nu | mber: 100 | Ty | pe: R | | Area: | 3939 | 9.00 SqFt | | PCI: 85 | 5 | | | |
| Sample Co | mments: | | | | | | | | | | | | |
| 52 RAV | VELING | | L | 394.00 | SqFt | | | | | | | | |
| | T CR | | L | 118.00 | | | | | | | | | |

| Network: | GNV | | | | Nan | ne: GAI | NESVILLE | REGIO | ONAL AIRPOI | RT | | | | |
|---|------------|------------|------------------|----------------|---------|----------------|-------------|-------|-------------|----------|--------------------|---------------|--|--|
| Branch: | TW A | | Name: | TAXIV | VAY A | | Use: | TA | XIWAY | Area: | 377,007 Se | qFt | | |
| Section: | 153 | of | f 17 | From: - | - | | | ŗ | То: - | | Last C | onst.: 7/1/20 | | |
| Surface: | AAC | Family: | C9N59-PR- APC | TW-AAC- | Zon | e: | | • | Category: | | Rank: | P | | |
| Area: | | 4,523 SqFt | Lengt | h: | 65 F | ⁷ t | Width: | | 50 Ft | | | | | |
| Slabs: | | Slab Len | igth: | Ft | | Slab Width: | | 1 | Ft | Joint L | ength: | Ft | | |
| Shoulder: | | Street Ty | ype: | | | Grade: 0 | | | | Lanes: | 0 | | | |
| Section Cor | mments: | | | | | | | | | | | | | |
| Work Date: 1/1/1979 Work Type: BUILT | | | | | | | C | ode: | IMPORTED | Is N | Is Major M&R: True | | | |
| Work Date: 7/1/2009 Work Type: MILL and OVERI | | | | | RLAY | | Code: ML-OV | | | Is N | Is Major M&R: True | | | |
| Work Date | : 7/2/2009 | W | ork Type: S | ırface Treatme | nt - Do | uble Bitum. | C | ode: | SU-DB | Is N | Major M&R: Fa | alse | | |
| Last Insp. I | Date: 4/10 | /2019 | Tot | alSamples: | 1 | | Surveye | ed: 1 | | | | | | |
| Conditions: | : PCI: | 82 | | | | | | | | | | | | |
| Inspection (| Comments: | | | | | | | | | | | | | |
| Sample Nu | mber: 100 | Typ | e: R | A | rea: | 4523 | 3.00 SqFt | | PCI: 82 | <u> </u> | | | | |
| Sample Co | mments: | | | | | | | | | | | | | |
| 48 L& | T CR | | L | 188.00 | Ft | | | | | | | | | |
| | VELING | | L | 226.00 | | | | | | | | | | |

| NT / I | CNIII | | | | N T | CADIFOLIU I | DECL | ONLL AIRRO | N.T. | | |
|------------|--------------------|---------------|--------------------|--------------|----------------|--------------|----------------|------------|-----------|----------------|----------------|
| Network: | GNV | | | | Name: | GAINESVILLI | REGIO | ONAL AIRPO | ORT | | |
| Branch: | TW A | | Name: | TAXIW | AY A | Use: | TA. | XIWAY | Area: | 377,007 SqF | t |
| Section: | 154 | 0: | f 17 F | rom: - | | | , | То: - | | Last Con | nst.: 7/1/2009 |
| Surface: | AAC | Family: | C9N59-PR-TW APC | /-AAC- | Zone: | | • | Category: | | Rank: I |) |
| Area: | | 4,561 SqFt | Length: | | 65 Ft | Width: | | 50 Ft | | | |
| Slabs: | | Slab Len | gth: | Ft | Slab Wi | dth: |] | Ft | Joint Ler | ngth: | Ft |
| Shoulder: | | Street Ty | ype: | | Grade: | 0 | | | Lanes: | 0 | |
| Section Co | omments: | | | | | | | | | | |
| Work Date | e: 1/1/1979 | W | ork Type: BUIL | LT . | | | Code: | IMPORTED | Is M | ajor M&R: True | |
| Work Date | e: 7/1/2009 | W | ork Type: MILI | and OVERI | AY | (| Code: | ML-OV | Is Ma | ajor M&R: True | |
| Work Date | e: 7/2/2009 | W | ork Type: Surfa | ce Treatment | - Double Bitun | n. | Code: | SU-DB | Is Ma | ajor M&R: Fals | e |
| Last Insp. | Date: 4/10 | 0/2019 | TotalSa | amples: 1 | | Survey | / ed: 1 | | | | |
| Conditions | s: PCI: | 53 | | | | | | | | | |
| Inspection | Comments | : | | | | | | | | | |
| Sample Nu | umber: 10 | 0 Ty r | e: R | Arc | ea: | 4561.00 SqFt | | PCI: 53 | 3 | | |
| Sample Co | omments: | | | | | • | | | | | |
| 48 L& | Ł T CR | | L | 146.00 F | t | | | | | | |
| 52 RA | VELING | | L | 4561.00 S | qFt | | | | | | |
| 48 L & | t T CR | | M | 20.00 F | t | | | | | | |
| 45 DE | PRESSION | | L | 6.00 S | qFt | | | | | | |
| 43 BL0 | OCK CR | | L | 3085.00 S | qFt | | | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: Branch: TW B TAXIWAY B Use: TAXIWAY 175,981 SqFt Name: Area: 203 From: Section: of 5 To: -Last Const.: 1/1/2015 Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P Surface: $\mathsf{A}\mathsf{A}\mathsf{C}$ APC Width: 8,026 SqFt Length: 300 Ft 50 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1972 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 7/1/2009 Work Type: Mill and Overlay Code: ML-OL Is Major M&R: True Work Date: 1/1/2015 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **TotalSamples:** 2 **Last Insp. Date:** 4/10/2019 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 228 R 4118.00 SqFt **PCI:** 90 Type: Area: **Sample Comments:** 48 L & T CR 18.00 Ft

48 L & T CR L 18.00 Ft 57 WEATHERING L 4118.00 SqFt

| Network: | GNV | | | Na | me: GAI | NESVILLE I | REGIONAL AI | RPORT | | | | |
|--------------------------|---------------------|------------|-------------------|--------------------------|-------------|------------|-------------|----------------|-----------|---------|--------------|----------|
| Branch: | TW B | | Name: | TAXIWAY I | 3 | Use: | TAXIWAY | Area | 1: | 175, | 981 SqFt | |
| Section: | 205 | of | 5 | From: - | | | То: - | | | 1 | Last Const.: | 7/1/2009 |
| Surface: | AAC | | C9N59-PR-T APC | W-AAC- Zon | ne: | | Category: | | | 1 | Rank: P | |
| Area: | 129,9 | 976 SqFt | Length: | 2,571 | Ft | Width: | 50 I | ⁷ t | | | | |
| Slabs: | | Slab Lengt | th: | Ft | Slab Width: | | Ft | | Joint Lei | ngth: | F | t |
| Shoulder: | | Street Typ | e: | | Grade: 0 | | | | Lanes: | 0 | | |
| Section Co | omments: | | | | | | | | | | | |
| Work Date | re: 1/1/1972 | Wor | k Type: BUI | ILT | | Co | ode: IMPORT | ED | Is M | ajor M& | R: True | |
| Work Date | e: 7/1/2009 | Wor | k Type: Mill | l and Overlay | | Co | ode: ML-OL | | Is M | ajor M& | R: True | |
| Conditions Inspection | s: PCI: 89 |) | | | | | | | | | | |
| Sample Nu | umber: 206 | Туре: | : R | Area: | 5000 | .00 SqFt | PCI: | 91 | | | | |
| Sample Co | omments: | | | | | | | | | | | |
| | & T CR EATHERING | | L L | 14.00 Ft 5000.00 SqFt | | | | | | | | |
| Sample Nu | umber: 214 | Type: | : R | Area: | 5000 | .00 SqFt | PCI: | 89 | | | | |
| Sample Co | omments: | | | | | | | | | | | |
| | EATHERING & T CR | | L L | 5000.00 SqFt 74.00 Ft | | | | | | | | |
| Sample Nu | umber: 225 | Type: | : R | Area: | 5000 | .00 SqFt | PCI: | 88 | | | | |
| Sample Co | omments: | | | | | | | | | | | |
| | | | | | | | | | | | | |

| Network: | GNV | | | | Nan | ne: GA | INESVILLE | REG | IONAL AIRPOR | RT | | | |
|--------------|------------------|------------|-----------------|------------------|-------|-------------|-----------|-------|----------------|-----------|----------|------------|----------|
| Branch: | TW B | | Name: | TAXI | WAY B | | Use: | TA | AXIWAY | Area: | 175,981 | SqFt | |
| Section: | 206 | | of 5 | From: | - | | | | То: - | | Last | Const.: | 1/1/2015 |
| Surface: | AAC | Family: | C9N59-PR APC | -TW-AAC- | Zon | e: | | | Category: | | Rank | : P | |
| Area: | | 7,137 SqFt | Lengt | h: | 320 F | 't | Width: | | 35 Ft | | | | |
| Slabs: | | Slab Le | ength: | Ft | | Slab Width: | | | Ft | Joint Len | gth: | Ft | |
| Shoulder: | | Street 7 | Гуре: | | | Grade: 0 | ı | | | Lanes: | 0 | | |
| Section Con | mments: | | | | | | | | | | | | |
| Work Date: | : 1/1/1972 | V | Vork Type: B | UILT | | | C | Code: | IMPORTED | Is Ma | jor M&R: | True | |
| Work Date: | : 1/1/1996 | V | Vork Type: O | VERLAY | | | (| Code: | IMPORTED | Is Ma | jor M&R: | True | |
| Work Date: | : 1/1/1996 | V | Vork Type: O | VERLAY | | | (| Code: | IMPORTED | Is Ma | jor M&R: | True | |
| Work Date: | : 7/1/2009 | V | Vork Type: M | Iill and Overla | y | | (| Code: | ML-OL | Is Ma | jor M&R: | True | |
| Work Date: | : 1/1/2015 | v | Vork Type: M | IILL and OVE | RLAY | | (| Code: | ML-OV | Is Ma | jor M&R: | True | |
| Last Insp. I | Date: 4/10 | /2019 | Tot | alSamples: | 2 | | Survey | ed: | 1 | | | | |
| Conditions: | : PCI: | 87 | | | | | | | | | | | |
| Inspection (| Comments: | | | | | | | | | | | | |
| Sample Nur | mber: 099 | Ту | pe: R | I | Area: | 334 | 2.00 SqFt | | PCI: 87 | | | | |
| Sample Cor | mments: | | | | | | | | | | | | |
| | T CR ATHERING | | L L | 78.00 3342.00 | | | | | | | | | |

| Network: | GNV | | | | Name | GAI | NESVILLE I | REGI | IONAL AIRPOR | RT | | | |
|------------|------------------|--------------|------------------|-----------------|--------|------------|------------|-------|----------------|----------|----------|------------|-------------|
| Branch: | TW B | | Name: | TAXI | WAY B | | Use: | TA | XIWAY | Area: | 175 | 5,981 SqFt | |
| Section: | 208 | (| of 5 | From: | - | | | | То: - | | | Last Const | .: 7/1/2009 |
| Surface: | AAC | Family: | C9N59-PR- APC | -TW-AAC- | Zone: | | | | Category: | | | Rank: P | |
| Area: | | 18,964 SqFt | Lengt | h: | 450 Ft | | Width: | | 45 Ft | | | | |
| Slabs: | | Slab Le | ength: | Ft | S | lab Width: | | | Ft | Joint Le | ength: | | Ft |
| Shoulder: | | Street T | Гуре: | | (| Grade: 0 | | | | Lanes: | 0 | | |
| Section Co | mments: | | | | | | | | | | | | |
| Work Date | : 1/1/1972 | . v | Vork Type: B | UILT | | | C | ode: | IMPORTED | Is N | Iajor Ma | &R: True | |
| Work Date | : 1/1/1996 | , v | Vork Type: O | VERLAY | | | C | ode: | IMPORTED | Is N | Iajor Mo | &R: True | |
| Work Date | e: 1/1/1996 | , v | Vork Type: O | VERLAY | | | C | ode: | IMPORTED | Is N | Iajor M | &R: True | |
| Work Date | e: 7/1/2009 | v | Vork Type: M | Iill and Overla | y | | C | ode: | ML-OL | Is N | Iajor M | &R: True | |
| Last Insp. | Date: 4/1 | 0/2019 | Tot | alSamples: | 5 | | Surveye | ed: 1 | 1 | | | | |
| Conditions | : PCI: | 81 | | | | | | | | | | | |
| Inspection | Comments | s: | | | | | | | | | | | |
| Sample Nu | mber: 10 |)2 Ty | pe: R | A | Area: | 4307 | 7.00 SqFt | | PCI: 81 | | | | |
| Sample Co | mments: | | | | | | | | | | | | |
| 48 L& | TCR | | L | 124.00 | Ft | | | | | | | | |
| | ATHERIN | | M | 301.00 | | | | | | | | | |
| 57 WE | ATHERIN | G | L | 4006.00 | SqFt | | | | | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: Branch: TW B TAXIWAY B Use: TAXIWAY 175,981 SqFt Name: Area: 210 of 5 Section: From: To: -Last Const.: 1/1/2005 Surface: AAC Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P APC Width: 50 Ft 11,878 SqFt Length: 50 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** 0 Lanes: Grade: **Section Comments:** Work Date: 1/1/1973 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2005 Work Type: Mill and Overlay Code: ML-OL Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 201 R **PCI:** 53 Type: Area: 6750.00 SqFt **Sample Comments:** 48 L & T CR M 34.00 Ft RAVELING L 135.00 SqFt 52 57 WEATHERING L 6615.00 SqFt 48 L & T CR L 665.00 Ft 56 SWELLINGL 165.00 SqFt BLOCK CR L 110.00 SqFt 43

| Network: GNV | | | | Name: | GAl | NESVILLE | REGI | IONAL AIR | PORT | | | |
|---------------------------|----------------|-----------------|-----------------|-------------|-----------|-----------|-------|-----------|------|---------------|--------------|----------|
| Branch: TW C | | Name | : TAXIW | /AY C | | Use: | TA | AXIWAY | Area | : 1 | 94,994 SqFt | |
| Section: 304 | 0 | f 4 | From: - | | | | | То: - | | | Last Const.: | 1/1/2015 |
| Surface: AAC | Family: | C9N59-PR APC | -TW-AAC- | Zone: | | | | Category: | | | Rank: P | |
| Area: | 17,460 SqFt | Leng | th: | 400 Ft | | Width: | | 50 Ft | | | | |
| Slabs: | Slab Lei | ngth: | Ft | SI | ab Width: | | | Ft | | Joint Length: | F | t |
| Shoulder: | Street T | ype: | | G | rade: 0 | | | | | Lanes: 0 | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: 1/1/197 | 6 W | ork Type: I | BUILT | | | (| Code: | IMPORTE | D | Is Major N | M&R: True | |
| Work Date: 3/1/201 | 1 W | ork Type: (| Complete Recons | struction - | AC | (| Code: | CR-AC | | Is Major N | M&R: True | |
| Work Date: 1/1/201 | 5 W | ork Type: 1 | MILL and OVER | LAY | | (| Code: | ML-OV | | Is Major N | M&R: True | |
| Last Insp. Date: 4/ | 10/2019 | То | talSamples: 4 | | | Survey | ed: 2 | 2 | | | | |
| Conditions: PCI: | 89 | | | | | | | | | | | |
| Inspection Commen | ts: | | | | | | | | | | | |
| Sample Number: 3 | 22 Ty] | pe: R | A | rea: | 4718 | 3.00 SqFt | | PCI: | 91 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 L & T CR | | L | 6.00 | Ft | | | | | | | | |
| 57 WEATHERIN | NG | L | 4718.00 | SqFt | | | | | | | | |
| Sample Number: 3 | 23 Ty] | pe: R | A | rea: | 4100 | 0.00 SqFt | | PCI: | 87 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 WEATHERIN | 1G | L | 4100.00 | SqFt | | | | | | | | |
| 48 L & T CR | | L | 91.00 | | | | | | | | | |

| | rk: GNV | | | | Name: | GAINES | VILLE R | EGIONAL AII | RPORT | | | |
|---|---|--------------|-----------------------|---|--|----------|----------|-------------|-------|---------------|--------------|-------------|
| Brancl | h: TW C | | Name: | TAXIW | AY C | | Use: | TAXIWAY | Are | ea: | 194,994 SqFt | |
| Section | n: 305 | of 4 | | From: - | | | | То: - | | | Last Const | .: 3/1/2011 |
| Surfac | e: AC | Family: C9 | N59-PR- | TW-AC | Zone: | | | Category: | | | Rank: P | |
| Area: | 110,12 | 22 SqFt | Lengtl | h: 2, | 000 Ft | Wie | dth: | 50 F | t | | | |
| Slabs: | | Slab Length: | | Ft | Sla | b Width: | | Ft | | Joint Length: | : | Ft |
| Should | ler: | Street Type: | | | Gr | ade: 0 | | | | Lanes: 0 | | |
| Section | n Comments: | | | | | | | | | | | |
| Work | Date: 1/1/1976 | Work | Type: BU | JILT | | | Co | de: IMPORT | ED | Is Major | M&R: True | |
| Work | Date: 3/1/2011 | Work | Type: Co | omplete Recons | ruction - A | AC | Со | de: CR-AC | | Is Major | M&R: True | |
| Last Iı | 1sp. Date: 4/10/2019 | 9 | Tota | alSamples: 22 | 2 | - | Surveyed | l: 3 | | | | |
| Condi | tions: PCI: 75 | | | | | | | | | | | |
| Inspec | tion Comments: | | | | | | | | | | | |
| | | | | | | | | | | | | |
| Sampl | e Number: 308 | Type: | R | Ar | ea: | 5000.00 | SqFt | PCI: | 79 | | | |
| • | e Number: 308 e Comments: | Туре: | R | Ar | ea: | 5000.00 | SqFt | PCI: | 79 | | | |
| Sampl | | Туре: | R N | Ar 1.00 S | | 5000.00 | SqFt | PCI: | 79 | | | |
| Sampl | e Comments: | Туре: | | | SqFt | 5000.00 | SqFt | PCI: | 79 | | | |
| Sampl 42 52 | e Comments: BLEEDING | Туре: | N | 1.00 | SqFt SqFt | 5000.00 | SqFt | PCI: | 79 | | | |
| Sampl 42 52 48 | e Comments: BLEEDING RAVELING | Туре: | N L | 1.00 S 100.00 S | SqFt SqFt Ft | 5000.00 | SqFt | PCI: | 79 | | | |
| Sampl 42 52 48 57 | e Comments: BLEEDING RAVELING L & T CR | Type: | N L L | 1.00 S 100.00 S 184.00 I 4900.00 S | SqFt SqFt Ft | 5000.00 | | PCI: | | | | |
| Sampl 42 52 48 57 Sampl | e Comments: BLEEDING RAVELING L & T CR WEATHERING | | N L L L | 1.00 S 100.00 S 184.00 I 4900.00 S | SqFt SqFt SqFt SqFt | | | | | | | |
| Sampl 42 52 48 57 Sampl | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 | | N L L L | 1.00 S 100.00 S 184.00 I 4900.00 S | SqFt SqFt SqFt SqFt | | | | | | | |
| Sampl 42 52 48 57 Sampl Sampl 42 52 | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 e Comments: BLEEDING RAVELING | | N L L L | 1.00 S 100.00 S 184.00 I 4900.00 S | SqFt SqFt SqFt ea: | | | | | | | |
| Sampl 42 52 48 57 Sampl Sampl 42 52 | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 e Comments: BLEEDING | | N L L L R | 1.00 S 100.00 S 184.00 I 4900.00 S Ar | SqFt SqFt SqFt ea: SqFt SqFt | | | | | | | |
| Sampl 42 52 48 57 Sampl Sampl 42 52 48 | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 e Comments: BLEEDING RAVELING | | N L L L R | 1.00 S 100.00 S 184.00 J 4900.00 S Ar 6.00 S 100.00 S | SqFt SqFt ea: SqFt SqFt SqFt | | | | | | | |
| Sampl 42 52 48 57 Sampl Sampl 42 52 48 57 | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 e Comments: BLEEDING RAVELING L & T CR | | N L L L R | 1.00 S 100.00 S 184.00 I 4900.00 S Ar 6.00 S 100.00 S 106.00 I 4900.00 S | SqFt SqFt ea: SqFt SqFt SqFt | | SqFt | | 83 | | | |
| Sampl 42 52 48 57 Sampl Sampl 42 52 48 57 Sampl | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 e Comments: BLEEDING RAVELING L & T CR WEATHERING | Туре: | N L L L R | 1.00 S 100.00 S 184.00 I 4900.00 S Ar 6.00 S 100.00 S 106.00 I 4900.00 S | SqFt SqFt SqFt ea: SqFt SqFt SqFt SqFt | 5000.00 | SqFt | PCI: | 83 | | | |
| Sampl 42 52 48 57 Sampl Sampl 42 52 48 57 Sampl Sampl | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 e Comments: BLEEDING RAVELING L & T CR WEATHERING E Number: 327 | Туре: | N L L L R | 1.00 S 100.00 S 184.00 I 4900.00 S Ar 6.00 S 100.00 S 106.00 I 4900.00 S | SqFt SqFt ea: SqFt SqFt SqFt ct SqFt ct sqFt | 5000.00 | SqFt | PCI: | 83 | | | |
| Sampl 42 52 48 57 Sampl Sampl 42 52 48 57 Sampl | BLEEDING RAVELING L & T CR WEATHERING e Number: 318 e Comments: BLEEDING RAVELING L & T CR WEATHERING e Number: 327 e Comments: | Туре: | N L L R N L L L R | 1.00 S 100.00 S 184.00 I 4900.00 S Ar 6.00 S 100.00 S 106.00 I 4900.00 S | SqFt SqFt ea: SqFt cqFt cqFt cqFt cqFt cqFt cqFt | 5000.00 | SqFt | PCI: | 83 | | | |

| Network: GNV | | Name: | GAINESVILLE | REGIONAL AIRPOR | TT | |
|---|----------------------------|--|---------------|-----------------|--------------|-----------------------|
| Branch: TW C | Name: | TAXIWAY C | Use: | TAXIWAY | Area: | 194,994 SqFt |
| Section: 307 | of 4 | From: - | | То: - | | Last Const.: 7/1/2010 |
| Surface: AAC | Family: C9N59-PR-APC | -TW-AAC- Zone: | | Category: | | Rank: P |
| Area: 44,52 | 26 SqFt Lengt | h: 275 Ft | Width: | 70 Ft | | |
| Slabs: | Slab Length: | Ft Sla | b Width: | Ft | Joint Lengtl | h: Ft |
| Shoulder: | Street Type: | Gr | ade: 0 | | Lanes: |) |
| Section Comments: | | | | | | |
| Work Date: 1/1/1976 | Work Type: N | ew Construction - Initial | C | ode: NU-IN | Is Majo | r M&R: True |
| Work Date: 7/1/2010 | Work Type: M | IILL and OVERLAY | C | ode: ML-OV | Is Majo | r M&R: True |
| Work Date: 7/2/2010 | Work Type: S | urface Treatment - Double | Bitum. | ode: LC-DB | Is Majo | r M&R: False |
| | | | | | | |
| Last Insp. Date: 4/10/201 | 9 Tot | alSamples: 12 | Surveye | ed: 2 | | |
| - | 9 Tot | alSamples: 12 | Surveyo | ed: 2 | | |
| Conditions: PCI: 61 | 9 Tot | alSamples: 12 | Surveyo | ed: 2 | | |
| Conditions: PCI: 61 Inspection Comments: | | alSamples: 12 | | | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 | 9 Tot | | Surveyo | PCI: 59 | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: | | | | | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING | Type: R N L | Area: 10.00 SqFt 50.00 SqFt | | | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING 48 L & T CR | Type: R N L M | Area: 10.00 SqFt 50.00 SqFt 9.00 Ft | | | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING 48 L & T CR 48 L & T CR | Type: R N L M L | Area: 10.00 SqFt 50.00 SqFt 9.00 Ft 421.00 Ft | | | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING 48 L & T CR 48 L & T CR 52 RAVELING | Type: R N L M L L L | Area: 10.00 SqFt 50.00 SqFt 9.00 Ft 421.00 Ft 4234.00 SqFt | 4234.00 SqFt | PCI: 59 | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING 48 L & T CR 48 L & T CR 52 RAVELING Sample Number: 337 | Type: R N L M L | Area: 10.00 SqFt 50.00 SqFt 9.00 Ft 421.00 Ft | | | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING 48 L & T CR 48 L & T CR 52 RAVELING | Type: R N L M L L L | Area: 10.00 SqFt 50.00 SqFt 9.00 Ft 421.00 Ft 4234.00 SqFt | 4234.00 SqFt | PCI: 59 | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING 48 L & T CR 48 L & T CR 52 RAVELING Sample Number: 337 | Type: R N L M L L L | Area: 10.00 SqFt 50.00 SqFt 9.00 Ft 421.00 Ft 4234.00 SqFt | 4234.00 SqFt | PCI: 59 | | |
| Conditions: PCI: 61 Inspection Comments: Sample Number: 331 Sample Comments: 42 BLEEDING 56 SWELLING 48 L & T CR 48 L & T CR 52 RAVELING Sample Number: 337 Sample Comments: | Type: R N L M L L Type: R | Area: 10.00 SqFt 50.00 SqFt 9.00 Ft 421.00 Ft 4234.00 SqFt Area: | 4234.00 SqFt | PCI: 59 | | |

| Network: | GNV | | | | Nar | ne: GA | INESVILLE | REGI | IONAL AIRPOR | RT | | | |
|-------------------------|------------------------|------------|--------------|---------------|----------|--------------|-----------|---------------|----------------|------------|----------|---------|----------|
| Branch: | TW C | | Name: | TAXI | IWAY C | | Use: | TA | XIWAY | Area: | 194,994 | SqFt | |
| Section: | 315 | of | f 4 | From: | - | | | | То: - | | Last | Const.: | 7/1/2010 |
| Surface: | AAC | Family: | C9N59-PR- | TW-AAC- | Zor | ie: | | | Category: | | Ran | k: P | |
| Area: | 22 | 2,886 SqFt | Lengtl | h: | 275 1 | Ft | Width: | | 70 Ft | | | | |
| Slabs: | | Slab Len | gth: | Ft | | Slab Width: | | | Ft | Joint Leng | çth: | F | t |
| Shoulder: | : | Street Ty | pe: | | | Grade: 0 | | | | Lanes: | 0 | | |
| Section C | omments: | | | | | | | | | | | | |
| Work Dat | te: 1/1/1976 | Wo | ork Type: Bl | JILT | | | C | ode: | IMPORTED | Is Maj | jor M&R: | True | |
| Work Da | te: 7/1/2010 | Wo | ork Type: M | ILL and OVE | ERLAY | | C | ode: | ML-OV | Is Maj | jor M&R: | True | |
| Work Da | te: 7/2/2010 | Wo | ork Type: Su | ırface Treatm | ent - Do | ouble Bitum. | C | ode: | SU-DB | Is Maj | jor M&R: | False | |
| Last Insp | . Date: 4/10/2 | 2019 | Tota | alSamples: | 5 | | Surveye | e d: 1 | | | | | |
| Condition Inspection | ns: PCI: 8 n Comments: | 31 | | | | | | | | | | | |
| Sample N | lumber: 303 | Тур | e: R | | Area: | 500 | 0.00 SqFt | | PCI: 81 | | | | |
| Sample C | Comments: | | | | | | | | | | | | |
| 48 L & | & T CR | | L | 155.00 | Ft | | | | | | | | |
| | EATHERING | | L | 4900.00 | | | | | | | | | |
| 52 RA | AVELING | | L | 100.00 | SaFt | | | | | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: Branch: TW CONN E CONNECTOR TAXIWAY TAXIWAY 37,129 SqFt Name: Use: Area: FROM TW E TO S AP Section: 605 of 2 To: -Last Const.: 1/1/2014 From: AC C9N59-PR-TW-AC Rank: P Surface: Family: Zone: Category: 200 Ft Width: 100 Ft Area: 28,681 SqFt Length: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Grade: 0 Lanes: Shoulder: **Section Comments:** Work Date: 1/1/1981 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2014 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 6 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** PCI: 86 Sample Number: 200 R 4527.00 SqFt Type: Area: **Sample Comments:** 56 SWELLING L 5.00 SqFt

L & T CR

WEATHERING

48 57 L

L

100.00 Ft

4527.00 SqFt

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: 37,129 SqFt **Branch:** TW CONN E CONNECTOR TAXIWAY TAXIWAY Name: Use: Area: FROM TW E TO S AP Section: 610 of 2 To: -Last Const.: 7/1/2009 From: C9N59-PR-TW-AAC-Rank: P Surface: AAC Family: Zone: Category: APC 8,448 SqFt Length: 200 Ft Width: 100 Ft Area: Slab Width: Slabs: Slab Length: Ft Ft Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: 0 **Section Comments:** Work Date: 1/1/1981 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Type: Mill and Overlay Work Date: 7/1/2009 Code: ML-OL Is Major M&R: True TotalSamples: 2 **Last Insp. Date:** 4/10/2019 Surveyed: 1 **Conditions: PCI:** 79 **Inspection Comments:** 3587.00 SqFt **PCI:** 79 Sample Number: 204 Type: R Area: **Sample Comments:**

L & T CR L 119.00 Ft 56 **SWELLING** L 10.00 SqFt 57 WEATHERING L 3408.00 SqFt 57 WEATHERING M 179.00 SqFt

| Network: | GNV | | | Name | : GAINESVILL | E REGIONAL AIRPO | ORT | |
|--------------|-----------------|-----------|-------------|--------------------------|--------------|------------------|-------------|-----------------------|
| Branch: | TW CONN W | I | Name: | CONNECTOR FROM TW E T | | : TAXIWAY | Area: | 65,848 SqFt |
| Section: | 715 | of | 1 | From: - | | То: - | | Last Const.: 1/1/2014 |
| Surface: | AC | Family: | C9N59-PR | -TW-AC Zone: | | Category: | | Rank: P |
| Area: | 65,84 | 8 SqFt | Lengt | th: 300 Ft | Width: | 205 Ft | | |
| Slabs: | | Slab Len | gth: | Ft S | Slab Width: | Ft | Joint Lengt | h: Ft |
| Shoulder: | | Street Ty | pe: | | Grade: 0 | | Lanes: |) |
| Section Con | mments: | | | | | | | |
| Work Date | : 1/1/2014 | Wo | ork Type: N | ew Construction - Initia | 1 | Code: NU-IN | Is Majo | r M&R: True |
| Last Insp. 1 | Date: 4/10/2019 |) | Tot | alSamples: 14 | Surve | eyed: 2 | | |
| Conditions | PCI : 91 | | | | | | | |
| Inspection | Comments: | | | | | | | |
| Sample Nu | mber: 101 | Тур | e: R | Area: | 5000.00 SqFt | PCI: 9 | 92 | |
| Sample Co | mments: | | | | | | | |
| 57 WE. | ATHERING | | L | 5000.00 SqFt | | | | |
| 40 T 0 | T CR | | L | 5.00 Ft | | | | |
| 48 L & | | Тур | e: R | Area: | 5000.00 SqFt | PCI: 9 | 90 | |
| | mber: 155 | - J P | | | | | | |
| Sample Nu | | - J P | | | | | | |
| Sample Nu | | - 7 P | L | 5000.00 SqFt | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** TW D TAXIWAY D Use: TAXIWAY 20,831 SqFt Name: Area: Section: 410 of 1 Last Const.: 7/1/2009 From: To: -Surface: AAC Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P APC Width: 50 Ft 20,831 SqFt Length: 358 Ft Area: Ft Slabs: Slab Length: Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: 0 **Section Comments:** Work Type: BUILT Work Date: 1/1/1972 Code: IMPORTED Is Major M&R: True Code: ML-OL Work Date: 7/1/2009 Work Type: Mill and Overlay Is Major M&R: True **Last Insp. Date:** 4/10/2019 TotalSamples: 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** PCI: 80 Sample Number: 102 R 5000.00 SqFt Type: Area: **Sample Comments:** 52 RAVELING M 250.00 SqFt 48 L & T CR L 206.00 Ft

| Netwo | ork: GNV | | | Name: | GAINESVILLE RI | EGIONAL AIRPORT | |
|--------------|--------------------------------|-------------|------------|---------------------------|-----------------|-----------------|------------------------------|
| Branc | eh: TW E | | Name: | TAXIWAY E - PA | ARALLEL RW Use: | TAXIWAY Arc | ea: 566,967 SqFt |
| Section | n: 505 | of 2 | 2 F | From: - | | То: - | Last Const.: 1/1/2014 |
| Surfac | ce: AC | Family: C | 9N59-PR-TW | V-AC Zone: | | Category: | Rank: P |
| Area: | 49 | 91,892 SqFt | Length: | 6,475 Ft | Width: | 75 Ft | |
| Slabs: | | Slab Length | ı : | Ft Sla | b Width: | Ft | Joint Length: Ft |
| Should | der: | Street Type | : | Gr | rade: 0 | | Lanes: 0 |
| Section | n Comments: | | | | | | |
| Work | Date: 1/1/1978 | Work | Type: BUIL | T | Coc | le: IMPORTED | Is Major M&R: True |
| | Date: 1/1/2014 | | | plete Reconstruction - A | | le: CR-AC | Is Major M&R: True |
| | nsp. Date: 4/10/ | | TotalSa | amples: 129 | Surveyed | : 10 | |
| | | 86 | | | | | |
| Inspec | ction Comments: | | | | | | |
| - | le Number: 503 | Type: | R | Area: | 4466.00 SqFt | PCI: 90 | |
| Sampl | le Comments: | | | | | | |
| 48 | L & T CR | | L | 17.00 Ft | | | |
| 57 | WEATHERING | | L | 4466.00 SqFt | 4500.00.5.= | | |
| _ | le Number: 510 | Type: | R | Area: | 4500.00 SqFt | PCI: 91 | |
| Sampl | le Comments: | | | | | | |
| 57 | WEATHERING | | L | 4500.00 SqFt | | | |
| 48 Sample | L & T CR le Number: 517 | Tames | L R | 6.00 Ft | 3750.00 SqFt | PCI: 91 | |
| _ | le Comments: | Type: | К | Area: | 3730.00 SqFt | FCI; 91 | |
| _ | | | | | | | |
| 57 48 | WEATHERING L & T CR | | L L | 3750.00 SqFt 8.00 Ft | | | |
| | le Number: 531 | Type: | R | Area: | 3750.00 SqFt | PCI: 90 | |
| _ | le Comments: | 7,700 | | | | /0 | |
| 57 48 | WEATHERING L & T CR | | L L | 3750.00 SqFt 24.00 Ft | | | |
| Sampl | le Number: 545 | Type: | R | Area: | 3750.00 SqFt | PCI: 81 | |
| Sampl | le Comments: | | | | | | |
| 57 48 | WEATHERING L & T CR | | L L | 3750.00 SqFt 173.00 Ft | | | |
| Sampl | le Number: 559 | Type: | R | Area: | 3750.00 SqFt | PCI: 78 | |
| _ | le Comments: | | | | | | |
| 48 | L & T CR | | L | 195.00 Ft | | | |
| 57 | WEATHERING | | L | 3750.00 SqFt | | | |
| 56 | SWELLING | Т | L | 6.00 SqFt | 2750 00 C-E4 | DCI. 02 | |
| _ | le Number: 573 le Comments: | Type: | R | Area: | 3750.00 SqFt | PCI: 83 | |
| 56 | SWELLING | | L | 8.00 SqFt | | | |
| 57 | WEATHERING | | L L | 3750.00 SqFt | | | |
| 48 Sampl | L & T CR le Number: 587 | Type: | R | 125.00 Ft Area: | 3750.00 SqFt | PCI: 89 | |
| _ | le Comments: | 1 ype: | K | Aita. | 3730.00 Sqrt | 1 (1, 0) | |
| _ | | | T | 57.00 E | | | |
| 48 57 | L & T CR WEATHERING | | L L | 57.00 Ft 3750.00 SqFt | | | |
| Sampl | le Number: 608 | Type: | R | Area: | 3750.00 SqFt | PCI: 80 | |
| Sampl | le Comments: | | | | | | |
| 48 | L & T CR | | L | 190.00 Ft | | | |
| 57 | WEATHERING | | L | 3750.00 SqFt | | | |

| Sample Nu | mber: 622 | Type: | R | A | rea: | 3750.00 SqFt | PCI: | 86 |
|-----------|-----------|-------|---|---------|------|--------------|------|----|
| Sample Co | mments: | | | | | | | |
| 48 L & | TCR | L | | 96.00 | Ft | | | |
| 57 WE. | ATHERING | L | | 3750.00 | SqFt | | | |

| | | | | | Nan | me: GAI | NESVILLE | REGIONAL A | IRPORT | | | | |
|--|---|-------------|---------------|--------------------------------------|---|----------------|----------|-------------|----------------|--------------|---------|---------|----------|
| Branch: | TW E | | Nai | me: TAX 11-2 | | E - PARALLEL I | RW Use: | TAXIWAY | Arc | ea: | 566,967 | SqFt | |
| Section: | 510 | of | f 2 | From: | - | | | То: - | | | Last | Const.: | 1/1/2014 |
| Surface: | AC | Family: | C9N59- | PR-TW-AC | Zon | ie: | | Category | /: | | Rank | : P | |
| Area: | , | 75,075 SqFt | Le | ength: | 1,000 F | Ft | Width: | 75 | Ft | | | | |
| Slabs: | | Slab Len | gth: | I | ⁷ t | Slab Width: | | Ft | | Joint Lengtl | h: | Ft | |
| Shoulder: | | Street Ty | pe: | | | Grade: 0 | | | | Lanes: (|) | | |
| Section Cor | nments: | | | | | | | | | | | | |
| Work Date: | : 1/1/1983 | Wo | ork Type | : BUILT | | | C | Code: IMPOR | TED | Is Majo | r M&R: | True | |
| Work Date: | : 1/1/1998 | Wo | ork Type | : OVERLAY | | | C | Code: IMPOR | TED | Is Majo | r M&R: | True | |
| Work Date: | : 1/1/2014 | Wo | ork Type | : Complete Rec | onstruction | on - AC | C | Code: CR-AC | | Is Majo | r M&R: | True | |
| Last Insp. I | Date: 4/10 | /2019 | , | TotalSamples: | 20 | | Survey | ed: 3 | | | | | |
| _ | | | | _ | | | - | | | | | | |
| Conditions: | PCI: | 89 | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Inspection (| Comments: | | oe: | R | Area: | 3750 | .00 SqFt | PC | I: 92 | | | | |
| Inspection (| Comments: | | oe: | R | Area: | 3750 | .00 SqFt | PC | I: 92 | | | | |
| Inspection (Sample Nui Sample Con | Comments: | | oe:] | | Area: | 3750 | .00 SqFt | PC | I: 92 | | | | |
| Inspection (Sample Nur Sample Cor 48 L & | Comments: mber: 634 mments: | Тур | | 4.0 | | 3750 | 00 SqFt | PC | i: 92 | | | | |
| Inspection (Sample Num Sample Con 48 L & 57 WEA | Comments: mber: 634 mments: T CR ATHERING | Тур | L L | 4.0 | 0 Ft | | .00 SqFt | | i: 92 i: 89 | | | | |
| Inspection C Sample Nur Sample Cor 48 L & 57 WEA Sample Nur | Comments: mber: 634 mments: T CR ATHERING mber: 641 | Тур | L L | 4.0 3750.0 | 0 Ft 0 SqFt | | | | | | | | |
| Sample Nur Sample Cor 48 L & 57 WEA Sample Nur Sample Cor | Comments: mber: 634 mments: T CR ATHERING mber: 641 | Тур | L L | 4.0 3750.0 R | 0 Ft 0 SqFt | | | | | | | | |
| Sample Nur Sample Cor 48 L & 57 WEA Sample Nur Sample Cor 48 L & | Comments: mber: 634 mments: T CR ATHERING mber: 641 mments: | Тур | L L | 4.0 3750.0 R | 00 Ft 00 SqFt Area: | | | | | | | | |
| Sample Nur Sample Cor 48 L & 57 WEA Sample Cor 8ample Cor 48 L & 57 WEA | Comments: mber: 634 mments: T CR ATHERING mber: 641 mments: T CR ATHERING | Тур | L L De: | 4.0 3750.0 R | 00 Ft 00 SqFt Area: | 3750 | | PC | | | | | |
| Inspection C Sample Nur Sample Cor 48 L & 57 WEA Sample Cor 48 L & 57 WEA Sample Nur Sample Nur 57 WEA | Comments: mber: 634 mments: T CR ATHERING mber: 641 mments: T CR ATHERING | Тур | L L De: | 4.0 3750.0 R 32.0 3750.0 | 0 Ft 0 SqFt Area: 0 Ft 0 SqFt | 3750 | 00 SqFt | PC | í: 89 | | | | |
| 57 WEA Sample Nur Sample Cor 48 L & 57 WEA Sample Nur Sample Cor | Comments: mber: 634 mments: T CR ATHERING mber: 641 mments: T CR ATHERING | Тур | L L De: | 4.0 3750.0 R 32.0 3750.0 | 0 Ft 0 SqFt Area: 0 Ft 0 SqFt | 3750 | 00 SqFt | PC | í: 89 | | | | |

| Network: | GNV | | | | Name: | GAI | NESVILLE | REGI | ONAL AIRPOF | RT | | | |
|------------|------------------|--------------|--------------------|-------------|-------|-----------|-----------|---------------|-------------|----------|-----------|-----------|----------|
| Branch: | TW E1 | | Name: | TAXIWA | Y E1 | | Use: | TA | XIWAY | Area: | 35,239 | 9 SqFt | |
| Section: | 515 | C | of 2 | From: - | | | | | To: - | | Las | t Const.: | 1/1/2005 |
| Surface: | AAC | Family: | C9N59-PR-TV APC | V-AAC- | Zone: | | | | Category: | | Rai | ık: P | |
| Area: | | 19,914 SqFt | Length: | 2 | 00 Ft | | Width: | | 105 Ft | | | | |
| Slabs: | | Slab Le | ngth: | Ft | SI | ab Width: | | | Ft | Joint Le | ngth: | I | Ft |
| Shoulder: | | Street T | ype: | | Gi | rade: 0 | | | | Lanes: | 0 | | |
| Section Co | mments: | | | | | | | | | | | | |
| Work Date | e: 1/1/1983 | W | Vork Type: BUII | LT | | | C | ode: | IMPORTED | Is M | ajor M&R: | True | |
| Work Date | e: 1/1/1998 | W | Vork Type: OVE | RLAY | | | C | ode: | IMPORTED | Is M | ajor M&R: | True | |
| Work Date | e: 1/1/2005 | W | Vork Type: MIL | L and OVERL | AY | | C | ode: | ML-OV | Is M | ajor M&R: | True | |
| Last Insp. | Date: 4/1 | 0/2019 | TotalS | samples: 4 | | | Surveye | e d: 1 | | | | | |
| Conditions | s: PCI: | 65 | | | | | | | | | | | |
| Inspection | Comments | s: | | | | | | | | | | | |
| Sample Nu | ımber: 10 |)1 Ty | pe: R | Are | a: | 5520 | 0.00 SqFt | | PCI: 65 | | | | |
| Sample Co | omments: | | | | | | | | | | | | |
| 52 RA | VELING | | L | 50.00 So | ηFt | | | | | | | | |
| 57 WE | EATHERIN | G | L | 5194.00 Sc | qFt | | | | | | | | |
| 48 L & | t T CR | | L | 651.00 Ft | , | | | | | | | | |
| 56 SW | ELLING | | L | 30.00 Sc | ιFt | | | | | | | | |

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** TW E1 TAXIWAY E1 Use: TAXIWAY 35,239 SqFt Name: Area: 517 of 2 Last Const.: 1/1/2014 Section: From: To: Surface: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Area: 15,325 SqFt Length: 100 Ft Width: 87 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1978 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2014 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 4600.00 SqFt **PCI:** 90 Sample Number: 103 Type: Area: **Sample Comments:** 57 WEATHERING L 4600.00 SqFt

L

22.00 Ft

L & T CR

48

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: Branch: TW E2 TAXIWAY E2 Use: TAXIWAY 35,115 SqFt Name: Area: 520 of 2 **Last Const.:** 1/1/2005 Section: From: To: -Surface: AAC Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P APC Width: 19,417 SqFt Length: 195 Ft 125 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: **Section Comments:** Work Date: 1/1/1978 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2005 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 TotalSamples: 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 201 R 5310.00 SqFt **PCI:** 73 Type: Area: **Sample Comments:** 56 SWELLING L 55.00 SqFt WEATHERING M 57 266.00 SqFt 57 WEATHERING L 5044.00 SqFt 48 L & T CR L 278.00 Ft

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** TW E2 TAXIWAY E2 Use: TAXIWAY 35,115 SqFt Name: Area: 522 of 2 Last Const.: 1/1/2014 Section: From: To: Surface: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Area: 15,698 SqFt Length: 110 Ft Width: 87 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1978 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2014 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 4500.00 SqFt **PCI:** 91 Sample Number: 203 Type: Area: **Sample Comments:** 57 WEATHERING L 4500.00 SqFt BLEEDING N 42 5.00 SqFt L & T CR L 48 8.00 Ft

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: 49,555 SqFt **Branch:** TW E3 TAXIWAY E3 Use: TAXIWAY Name: Area: 530 of 2 From: **Last Const.:** 1/1/2005 Section: To: -Surface: AAC Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P APC Width: 28,702 SqFt Length: 150 Ft 175 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** 0 Lanes: 0 Grade: **Section Comments:** Work Date: 1/1/1978 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2005 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 5 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI**: 69 Sample Number: 301 R 5310.00 SqFt Type: Area: **Sample Comments:** 56 SWELLING L 68.00 SqFt WEATHERING L 5044.00 SqFt 57 48 L & T CR L 378.00 Ft 57 WEATHERING M 266.00 SqFt

| Network: | GNV | | | | Nan | ne: | GAINESVIL | LE REG | IONAL AIRP | ORT | | |
|--------------|------------|-------------|--------------|---------------|-----------|----------|--------------|--------|------------|-------|--------------|---------------------|
| Branch: | TW E3 | | Name: | TAXI | WAY E | 3 | Us | se: T | AXIWAY | Area: | 49,55 | 55 SqFt |
| Section: 5 | 532 | (| of 2 | From: | - | | | | То: - | | La | st Const.: 1/1/2014 |
| Surface: A | AC | Family: | C9N59-PR- | ΓW-AC | Zon | e: | | | Category: | | Ra | ınk: P |
| Area: | | 20,853 SqFt | Lengtl | ı: | 100 F | t | Width: | | 137 Ft | | | |
| Slabs: | | Slab Le | ngth: | Ft | | Slab Wid | lth: | | Ft | Jo | int Length: | Ft |
| Shoulder: | | Street T | ype: | | | Grade: | 0 | | | La | nes: 0 | |
| Section Con | nments: | | | | | | | | | | | |
| Work Date: | : 1/1/1978 | W | ork Type: No | ew Constructi | on - Init | ial | | Code: | NU-IN | | Is Major M&R | t: True |
| Work Date: | : 1/1/2005 | W | ork Type: No | ew Constructi | on - Init | ial | | Code: | NU-IN | | Is Major M&R | : True |
| Work Date: | : 1/1/2014 | W | ork Type: Co | omplete Reco | nstructio | n - AC | | Code: | CR-AC | | Is Major M&R | : True |
| Last Insp. D | Date: 4/10 | 0/2019 | Tota | lSamples: | 4 | | Sur | veyed: | 1 | | | |
| Conditions: | PCI: | 89 | | | | | | | | | | |
| Inspection (| Comments | : | | | | | | | | | | |
| Sample Nun | mber: 303 | 3 Ty | pe: R | | Area: | | 4509.00 SqFt | t | PCI: | 39 | | |
| Sample Con | nments: | | | | | | | | | | | |

L 48.00 Ft L 4509.00 SqFt

48

57

L & T CR

WEATHERING

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: **Branch:** TW E4 TAXIWAY E4 Use: TAXIWAY 46,534 SqFt Name: Area: 540 of 2 From: **Last Const.:** 1/1/2005 Section: To: -Surface: AAC Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P APC Width: 29,074 SqFt Length: 200 Ft 155 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** 0 Lanes: Grade: **Section Comments:** Work Date: 1/1/1978 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2005 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 **TotalSamples:** 5 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** PCI: 66 Sample Number: 401 R Type: Area: 5310.00 SqFt **Sample Comments:** 56 SWELLING L 180.00 SqFt RAVELING L 1600.00 SqFt 52 48 L & T CR L 393.00 Ft 57 WEATHERING L 3710.00 SqFt

| Network: | GNV | | | | Nan | ne: | GAINESVILL | E REG | IONAL AIRPO | ORT | | |
|---------------|-----------|-------------|-------------|-------------|--------------|----------|--------------|-------|-------------|---------|-----------|---------------------|
| Branch: | TW E4 | | Name | : TA | XIWAY E | 4 | Use | TA | XIWAY | Area: | 46,53 | 4 SqFt |
| Section: 5 | 542 | (| of 2 | From: | - | | | | То: - | | La | st Const.: 1/1/2014 |
| Surface: A | AC | Family: | C9N59-PR | -TW-AC | Zon | e: | | | Category: | | Ra | nk: P |
| Area: | | 17,460 SqFt | Leng | th: | 87 F | řt . | Width: | | 113 Ft | | | |
| Slabs: | | Slab Le | ngth: | | Ft | Slab Wid | th: | | Ft | Joint 1 | Length: | Ft |
| Shoulder: | | Street T | ype: | | | Grade: | 0 | | | Lanes | : 0 | |
| Section Com | iments: | | | | | | | | | | | |
| Work Date: | 1/1/1978 | V | ork Type: 1 | New Constru | ction - Init | ial | | Code: | NU-IN | Is | Major M&R | : True |
| Work Date: | 1/1/2005 | V | ork Type: 1 | New Constru | ction - Init | ial | | Code: | NU-IN | Is | Major M&R | : True |
| Work Date: | 1/1/2014 | V | ork Type: (| Complete Re | construction | n - AC | | Code: | CR-AC | Is | Major M&R | : True |
| Last Insp. Da | ate: 4/10 | 0/2019 | То | talSamples: | 4 | | Surve | yed: | 1 | | | |
| Conditions: | PCI: | 90 | | | | | | | | | | |
| Inspection C | Comments | : | | | | | | | | | | |
| Sample Num | nber: 40 | 4 Ty | pe: R | | Area: | 4 | 5445.00 SqFt | | PCI: 9 | 00 | | |
| Sample Com | nments: | | | | | | | | | | | |

 L & T CR
 L
 38.00 Ft

 WEATHERING
 L
 5445.00 SqFt

48

57

GNV GAINESVILLE REGIONAL AIRPORT Network: Name: 29,163 SqFt **Branch:** TW E5 TAXIWAY E5 Use: TAXIWAY Name: Area: 550 of 2 **Last Const.:** 1/1/2005 Section: From: To: -Surface: AAC Family: C9N59-PR-TW-AAC-Zone: Category: Rank: P APC Width: 19,373 SqFt Length: 150 Ft 75 Ft Area: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: **Section Comments:** Work Date: 1/1/1978 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2005 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/10/2019 TotalSamples: 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** PCI: 77 Sample Number: 501 R 5310.00 SqFt Type: Area: **Sample Comments:** 48 L & T CR L 196.00 Ft SWELLING L 5.00 SqFt 56 57 WEATHERING M 531.00 SqFt

57

WEATHERING

L

4779.00 SqFt

| Network: | GNV | Name: GAINESVILLE REGIONAL AIRPORT | | | | | | | | | | |
|--|------------|------------------------------------|----------|--------------|---------------|----------------|-------------|---------------|--------------------|--------------------|-------------|---------------|
| Branch: | TW E5 | | Name | : TAX | XIWAY E | 5 | Use: | TAXIW | AY | Area: | 29,163 SqFt | |
| Section: | 552 | 0 | f 2 | From: | - | | | To: | | | Last Cons | st.: 1/1/2014 |
| Surface: | AC | Family: | C9N59-PF | t-TW-AC | Zone | e: | | Cate | gory: | | Rank: P | |
| Area: | | 9,790 SqFt | Leng | th: | 140 F | t | Width: | | 70 Ft | | | |
| Slabs: | | Slab Len | igth: | F | ₹t | Slab Width: | | Ft | | Joint Length | ı: | Ft |
| Shoulder: | | Street T | ype: | | | Grade: 0 | | | | Lanes: 0 | | |
| Section Co | mments: | | | | | | | | | | | |
| Work Date: 1/1/1978 Work Type: New Construction - Initia | | | | | al | Code: NU-IN | | | Is Major M&R: True | | | |
| Work Date: 1/1/2005 Work Type: New Construction - Ini | | | | | ction - Initi | al | Code: NU-IN | | | Is Major M&R: True | | |
| Work Date: 1/1/2014 Work Type: Complete Recons | | | | construction | n - AC | AC Code: CR-AC | | | Is Major M&R: True | | | |
| Last Insp. 1 | Date: 4/10 | /2019 | To | talSamples: | 2 | | Surveye | e d: 1 | | | | |
| Conditions | : PCI: | 91 | | | | | | | | | | |
| nspection | Comments: | | | | | | | | | | | |
| Sample Nu | mber: 504 | 1 Tyj | pe: R | | Area: | 5124 | 4.00 SqFt | | PCI: 91 | | | |
| Sample Co | mments: | | | | | | | | | | | |
| 57 WE. | ATHERING | i | L | 5124.0 | 0 SqFt | | | | | | | |
| 18 L& | T CR | | L | | 0 Ft | | | | | | | |