# FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION AND SPACEPORTS OFFICE

# Statewide Airfield Pavement Management Program









Florida Department of Transportation

# Statewide Airfield Pavement Management Program

#### Prepared by:

FDOT Aviation and Spaceports Office 605 Suwannee Street Tallahassee, Florida 32399-0450

















OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS



# **Table of Contents**


Executive Summary10
Program Background10
Summary of Results11Pavement Condition Index (Latest Inspection)11Forecasted Pavement Condition Index 2020-202914Major Rehabilitation Planning 2020-202917
Summary of Jacksonville International Airport18
Chapter 1 – Introduction20
1.1 Background20
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-201920
1.3 Organization221.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager221.3.2 Participating Florida Public-Use and Publicly Owned Airports221.3.3 Florida Department of Transportation District Offices221.3.4 Consultant22
1.4 Purpose of Airport Pavement Evaluation Report24
1.5 History of the Program24
1.6 Federal Aviation Administration (FAA)26
1.7 FDOT SAPMP Objectives and Components261.7.1 Program Objectives261.7.2 Program Components26
1.8 References30
Chapter 2 – Methodology32
2.1 Airfield Pavement Database32
2.2 Airfield Pavement System Inventory       32         2.2.1 Pavement Management Program Network Definition Terminology       33
2.3 Airfield Pavement Structure
2.4 Airfield Pavement Work History
2.5 Airfield Pavement Traffic37
2.6 Airfield Pavement Condition Index (PCI) Survey372.6.1 PCI Survey Methodology372.6.2 Pavement Distress Types39



2.6.3 PCI Survey Inspection Procedures	
2.6.4 Updates to the ASTM D5340-12	44
Chapter 3 – Airfield Pavement System Inventory	47
3.1 Airfield Pavement Network Information	47
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	
3.1.2 Estimated Pavement Age	
3.1.3 Functional Use Classification	
3.1.4 Pavement Surface Type	
Chapter 4 – Airfield Pavement Condition	60
4.1 Airfield Pavement Condition Index (Latest Inspection)	60
4.1.1 Network-Level Analysis	
4.1.2 Branch-Level Analysis	
4.1.3 Section-Level Analysis	62
4.2 Summary of Pavement Condition Evaluation Results	66
4.2.1 Network-Level Observations	
4.2.2 Branch-Level Observations	66
4.3 Forecasted Pavement Conditions	68
4.3.1 Performance Models and Prediction Curves	
4.3.2 Branch-Level Pavement Condition Forecast	
4.3.3 Section-Level Pavement Condition Forecast	
4.3.4 Forecasted PCI Considerations	75
Chapter 5 – Localized Maintenance and Repair Planning	77
5.1 Localized Maintenance and Repair	
5.2 Localized Maintenance and Repair Policy	78
5.3 Localized Maintenance and Repair Analysis and Recommendations	82
Chapter 6 – Major Rehabilitation Planning	87
6.1 Major Rehabilitation	87
6.1.1 Critical PCI	
6.1.2 FDOT Recommended Minimum Service-Level PCI	
6.2 Major Rehabilitation Policy	90
6.2.1 Major Rehabilitation Pavement Section Development	
6.2.2 Major Rehabilitation Planning-Level Unit Costs	
6.3 Major Rehabilitation Needs	92
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs	
Chapter 7 – Conclusion	97
7.1 Recommendations	97
7.1.1 Continued PCI Survey Inspections	
7.1.2 Localized Maintenance and Repair	



7.1.3 Major Rehabilitation	97
7.1.4 Pavement Management System	
7.2 Supporting Documents	
001 – Airfield Pavement Network Definition Exhibit	
002 – Airfield Pavement System Inventory Exhibit	98
003 – Airfield Pavement Condition Index Exhibit	98
004 – Airfield Pavement Major Rehabilitation Exhibit	98
Inspection Photograph Documentation	98
7.3 Conclusion	99





Appendix A Airfield Pavement Analysis Tables

Appendix B Airfield Pavement Localized Maintenance and Repair and Major

Rehabilitation

Appendix C Technical Exhibits

Appendix D Inspection Photograph Documentation

Appendix E Inspection Distress Details



# **List of Figures**

Figure E-4 Major Rehabilitation Planning Annual Budget 2020-202918
Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts21
Figure 1.7.2 (a) Typical Pavement Condition Life Cycle27
Figure 1.7.2 (b) General Pavement Treatments by Condition Range28
Figures 1.7.2 (c) Flexible Asphalt Concrete29
Figures 1.7.2 (d) Rigid Portland Cement Concrete29
Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit48
Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit49
Figure 3.1.2 Average Age of Pavements at Inspection50
Figure 3.1.3 Airfield Pavement Functional Classification Use by Area51
Figure 3.1.4 (a) Pavement Surface Type by Area (SF)52
Figure 3.1.4 (b) Pavement Surface Type by Area (%)53
Figure 4.1.1 Latest Condition – Overall Network
Figure 4.1.2 (a) Latest Condition – Runway Pavements61
Figure 4.1.2 (b) Latest Condition – Taxiway Pavements61
Figure 4.1.2 (c) Latest Condition – Apron Pavements
Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit66
Figure 4.2.2 Pavement Condition Summary by Facility Use
Figure 4.3.2 (a) Forecasted Runway Pavement Performance
Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance
Figure 4.3.2 (c) Forecasted Apron Pavement Performance
Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI87
Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI88
Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year94
Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit95



# **List of Tables**

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level11
Table E-2 Pavement Condition Index Forecast 2020-202914
Table E-3 Major Rehabilitation Planning 2020-202917
Table 2.2.1 Airfield Pavement Database Network Definition Terminology34
Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields 39
Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete- Surfaced Airfields
Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete- Surfaced Airfields
Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields41
Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete- Surfaced Airfields
Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete- Surfaced Airfields
Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete43
Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete43
Table 2.6.4 Summary of Updates to ASTM D5340-1245
Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction47
Table 3.1.5 Pavement System Inventory Details54
Table 4.1.3 Latest Pavement Condition Index Summary63
Table 4.3.3 Forecasted PCI 2020-202971
Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete78
Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete79
Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete81



Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete81
Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level82
Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level83
Table 5.3 (c) Summary of Localized Maintenance85
Table 6.1.2 FDOT Recommended Minimum Service-Level PCI89
Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete
Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete
Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type92
Table 6.3.1 10-Year Major Rehabilitation Needs93



# **Executive Summary**





# **Executive Summary**

#### Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the documented procedures set forth by ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.





#### Summary of Results

#### Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) - Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
JAX	RUNWAY 8-26	RUNWAY	6105	1,000,000	89	Good
JAX	RUNWAY 8-26	RUNWAY	6110	500,000	83	Satisfactory
JAX	RUNWAY 14-32	RUNWAY	6205	25,000	82	Satisfactory
JAX	RUNWAY 14-32	RUNWAY	6207	50,000	87	Good
JAX	RUNWAY 14-32	RUNWAY	6210	330,000	92	Good
JAX	RUNWAY 14-32	RUNWAY	6215	622,500	93	Good
JAX	RUNWAY 14-32	RUNWAY	6220	30,000	89	Good
JAX	RUNWAY 14-32	RUNWAY	6225	60,000	94	Good
JAX	RUNWAY 14-32	RUNWAY	6230	37,500	90	Good
JAX	TAXIWAY A	TAXIWAY	105	54,448	79	Satisfactory
JAX	TAXIWAY A	TAXIWAY	110	168,750	81	Satisfactory
JAX	TAXIWAY A	TAXIWAY	115	118,125	84	Satisfactory
JAX	TAXIWAY A	TAXIWAY	120	271,875	80	Satisfactory
JAX	TAXIWAY A	TAXIWAY	125	136,875	74	Satisfactory
JAX	TAXIWAY B	TAXIWAY	805	253,320	82	Satisfactory
JAX	TAXIWAY B	TAXIWAY	810	136,875	81	Satisfactory
JAX	TAXIWAY C	TAXIWAY	1480	24,260	73	Satisfactory
JAX	TAXIWAY C	TAXIWAY	1490	50,660	75	Satisfactory
JAX	TAXIWAY E	TAXIWAY	1670	29,143	78	Satisfactory
JAX	TAXIWAY E	TAXIWAY	1680	59,400	80	Satisfactory
JAX	TAXIWAY F	TAXIWAY	1145	30,320	90	Good
JAX	TAXIWAY F	TAXIWAY	1150	18,725	86	Good
JAX	TAXIWAY F	TAXIWAY	1155	98,961	30	Very Poor
JAX	TAXIWAY F	TAXIWAY	1170	27,436	82	Satisfactory
JAX	TAXIWAY F	TAXIWAY	1175	39,074	93	Good
JAX	TAXIWAY G	TAXIWAY	1020	29,478	78	Satisfactory
JAX	TAXIWAY G	TAXIWAY	1025	19,138	85	Satisfactory
JAX	TAXIWAY G	TAXIWAY	1030	35,019	89	Good
JAX	TAXIWAY G	TAXIWAY	1032	44,449	94	Good
JAX	TAXIWAY G	TAXIWAY	1035	7,929	92	Good
JAX	TAXIWAY G	TAXIWAY	1040	14,096	89	Good
JAX	TAXIWAY G	TAXIWAY	1045	14,480	53	Poor
JAX	TAXIWAY G	TAXIWAY	1060	133,822	91	Good
JAX	TAXIWAY H	TAXIWAY	550	208,460	88	Good





Network	Branch Name	Branch	Section	Area	PCI	Condition
ID		Use	ID	(SF)		Rating
JAX	TAXIWAY H	TAXIWAY	555	127,293	70	Fair
JAX	TAXIWAY H	TAXIWAY	557	38,685	80	Satisfactory
JAX	TAXIWAY J	TAXIWAY	740	136,242	87	Good
JAX	TAXIWAY J	TAXIWAY	745	94,986	82	Satisfactory
JAX	TAXIWAY J	TAXIWAY	750	21,670	69	Fair
JAX	TAXIWAY J	TAXIWAY	755	13,125	73	Satisfactory
JAX	TAXIWAY J	TAXIWAY	760	21,750	70	Fair
JAX	TAXIWAY J	TAXIWAY	765	123,159	97	Good
JAX	TAXIWAYK	TAXIWAY	1320	107,334	85	Satisfactory
JAX	TAXIWAY L	TAXIWAY	205	25,258	78	Satisfactory
JAX	TAXIWAY L	TAXIWAY	210	28,620	84	Satisfactory
JAX	TAXIWAY L	TAXIWAY	215	18,195	77	Satisfactory
JAX	TAXIWAY L	TAXIWAY	220	25,304	83	Satisfactory
JAX	TAXIWAY L	TAXIWAY	225	52,307	81	Satisfactory
JAX	TAXIWAY N	TAXIWAY	305	221,250	87	Good
JAX	TAXIWAY N	TAXIWAY	310	180,075	90	Good
JAX	TAXIWAY N	TAXIWAY	312	131,250	89	Good
JAX	TAXIWAY N	TAXIWAY	315	45,000	93	Good
JAX	TAXIWAY P	TAXIWAY	640	60,825	70	Fair
JAX	TAXIWAY P	TAXIWAY	641	8,909	87	Good
JAX	TAXIWAY P	TAXIWAY	650	133,322	96	Good
JAX	TAXIWAY P	TAXIWAY	655	79,579	94	Good
JAX	TAXIWAY P	TAXIWAY	660	126,658	99	Good
JAX	TAXIWAY Q	TAXIWAY	560	115,700	85	Satisfactory
JAX	TAXIWAY R	TAXIWAY	570	43,767	86	Good
JAX	TAXIWAY R	TAXIWAY	575	111,623	88	Good
JAX	TAXIWAY R	TAXIWAY	576	29,713	86	Good
JAX	TAXIWAYS	TAXIWAY	1285	140,346	81	Satisfactory
JAX	TAXIWAYS	TAXIWAY	1290	28,370	78	Satisfactory
JAX	TAXIWAYT	TAXIWAY	1282	59,457	97	Good
JAX	TAXIWAY U	TAXIWAY	390	52,557	91	Good
JAX	TAXIWAY V	TAXIWAY	905	78,127	100	Good
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	910	134,973	67	Fair
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	915	8,630	89	Good
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	920	23,852	86	Good
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2715	8,530	31	Very Poor
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2720	10,052	83	Satisfactory
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2772	33,940	67	Fair
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2774	50,906	82	Satisfactory
			=: • •	12,000		

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

# Jacksonville International Airport (JAX)





Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2775	38,593	48	Poor
JAX	CARGO AND AIR CARGO APRONS	APRON	4105	296,070	83	Satisfactory
JAX	CARGO AND AIR CARGO APRONS	APRON	4110	27,040	33	Very Poor
JAX	CARGO AND AIR CARGO APRONS	APRON	4118	198,059	88	Good
JAX	CARGO AND AIR CARGO APRONS	APRON	4120	212,550	78	Satisfactory
JAX	CARGO AND AIR CARGO APRONS	APRON	4125	84,968	48	Poor
JAX	CARGO AND AIR CARGO APRONS	APRON	4135	32,378	61	Fair
JAX	GA APRON	APRON	4205	76,140	89	Good
JAX	TERMINAL APRON	APRON	4305	36,141	79	Satisfactory
JAX	TERMINAL APRON	APRON	4310	144,838	79	Satisfactory
JAX	TERMINAL APRON	APRON	4315	146,950	86	Good
JAX	HOLDING APRON BETWEEN RWS 4, 13	APRON	4405	150,030	85	Satisfactory
JAX	TERMINAL APRON	APRON	4410	95,567	95	Good
JAX	TERMINAL APRON	APRON	4412	24,650	97	Good
JAX	TERMINAL APRON	APRON	4415	101,704	99	Good
JAX	TERMINAL APRON	APRON	4420	195,814	94	Good
JAX	TERMINAL APRON	APRON	4425	643,219	93	Good
JAX	TERMINAL APRON	APRON	4430	361,365	68	Fair
JAX	TERMINAL APRON	APRON	4435	625,548	88	Good
JAX	TERMINAL APRON	APRON	4440	121,630	97	Good
JAX	TERMINAL APRON	APRON	4445	312,670	76	Satisfactory
JAX	GA APRON	APRON	5105	127,653	49	Poor
JAX	GA APRON	APRON	5110	239,174	68	Fair
JAX	GA APRON	APRON	5115	28,389	62	Fair





#### Forecasted Pavement Condition Index 2020-2029

Table E-2 Pavement Condition Index Forecast 2020-2029

Network		Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	AP CARGO	4105	83	82	81	80	80	79	78	77	76	74	73
JAX	AP CARGO	4110	33	31	30	28	27	25	24	22	20	19	17
JAX	AP CARGO	4118	88	87	86	85	85	84	83	83	82	81	80
JAX	AP CARGO	4120	78	77	76	75	73	72	71	69	68	66	65
JAX	AP CARGO	4125	48	46	44	43	41	39	37	36	34	33	31
JAX	AP CARGO	4135	61	59	58	56	54	52	50	48	47	45	43
JAX	AP GA	4205	89	87	86	84	83	81	80	78	76	75	73
JAX	AP GA	5105	49	47	46	44	43	41	40	38	36	35	33
JAX	AP GA	5110	68	66	65	63	62	60	59	57	55	54	52
JAX	AP GA	5115	62	60	59	57	56	54	53	51	49	48	46
JAX	AP HOLD	4405	85	84	83	83	82	81	80	79	78	77	76
JAX	AP TERM	4305	79	78	77	76	75	73	72	71	69	68	66
JAX	AP TERM	4310	79	78	77	76	75	73	72	71	69	68	66
JAX	AP TERM	4315	86	85	84	84	83	82	81	81	80	79	78
JAX	AP TERM	4410	95	93	92	91	89	88	87	87	86	85	84
JAX	AP TERM	4412	97	95	93	92	91	89	88	87	87	86	85
JAX	AP TERM	4415	99	97	95	93	92	91	89	88	87	87	86
JAX	AP TERM	4420	94	92	91	90	89	88	87	86	85	85	84
JAX	AP TERM	4425	93	92	90	89	88	87	86	86	85	84	83
JAX	AP TERM	4430	68	66	65	63	61	60	58	56	54	53	51
JAX	AP TERM	4435	88	87	86	85	85	84	83	83	82	81	80
JAX	AP TERM	4440	97	95	93	92	91	89	88	87	87	86	85
JAX	AP TERM	4445	76	75	73	72	71	69	68	66	65	63	61
JAX	RW 14-32	6205	82	81	79	78	76	75	73	71	69	67	65
JAX	RW 14-32	6207	87	86	85	84	83	82	81	80	79	77	76
JAX	RW 14-32	6210	92	91	91	91	90	90	90	90	90	89	89
JAX	RW 14-32	6215	93	92	92	91	91	90	90	90	90	90	90
JAX	RW 14-32	6220	89	88	88	87	87	86	85	85	84	83	81
JAX	RW 14-32	6225	94	93	92	92	91	91	91	90	90	90	90
JAX	RW 14-32	6230	90	89	89	89	89	88	88	87	87	86	86
JAX	RW 8-26	6105	89	88	88	87	87	86	85	85	84	83	81
JAX	RW 8-26	6110	83	82	81	79	78	76	75	73	71	69	67
JAX	TW A	105	79	78	76	74	73	71	69	67	64	62	60
JAX	TW A	110	81	80	78	77	75	73	72	70	68	65	63
JAX	TW A	115	84	83	82	80	79	78	76	74	73	71	69

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

# Jacksonville International Airport (JAX)





Network		Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	TW A	120	80	79	77	75	74	72	70	68	66	64	62
JAX	TW A	125	74	72	70	68	66	64	62	60	57	55	52
JAX	TW AP	910	67	66	65	64	64	63	62	61	61	60	59
JAX	TW AP	915	89	87	85	84	82	80	79	77	76	75	73
JAX	TW AP	920	86	84	83	81	79	78	77	75	74	73	71
JAX	TW AP	2715	31	28	25	21	18	14	10	6	3	0	0
JAX	TW AP	2720	83	81	80	78	77	76	74	73	72	71	70
JAX	TW AP	2772	67	65	63	61	58	56	53	51	48	46	43
JAX	TW AP	2774	82	81	79	78	76	75	73	71	69	67	65
JAX	TW AP	2775	48	46	43	41	38	35	33	30	28	26	24
JAX	TW B	805	82	81	79	78	76	75	73	71	69	67	65
JAX	TW B	810	81	80	78	77	75	73	72	70	68	65	63
JAX	TW C	1480	73	71	69	67	65	63	61	58	56	53	51
JAX	TW C	1490	75	73	71	70	68	65	63	61	59	56	54
JAX	TW E	1670	78	76	75	73	71	69	67	65	63	61	58
JAX	TW E	1680	80	79	77	75	74	72	70	68	66	64	62
JAX	TW F	1145	90	89	89	89	89	88	88	87	87	86	86
JAX	TW F	1150	86	85	84	83	82	81	79	78	77	75	73
JAX	TW F	1155	30	27	24	20	16	13	9	5	2	0	0
JAX	TW F	1170	82	81	79	78	76	75	73	71	69	67	65
JAX	TW F	1175	93	92	92	91	91	90	90	90	90	90	90
JAX	TW G	1020	78	76	75	73	71	69	67	65	63	61	58
JAX	TW G	1025	85	84	83	82	81	79	78	76	75	73	71
JAX	TW G	1030	89	87	85	84	82	80	79	77	76	75	73
JAX	TW G	1032	94	92	90	88	86	85	83	81	80	78	77
JAX	TW G	1035	92	90	88	86	85	83	81	80	78	77	75
JAX	TW G	1040	89	87	85	84	82	80	79	77	76	75	73
JAX	TW G	1045	53	52	52	51	50	49	49	48	47	46	44
JAX	TW G	1060	91	90	90	90	90	90	89	89	89	89	89
JAX	TW H	550	88	87	87	86	85	84	83	82	81	80	78
JAX	TW H	555	70	68	66	64	62	59	57	54	52	49	47
JAX	TW H	557	80	79	77	75	74	72	70	68	66	64	62
JAX	TW J	740	87	86	85	84	83	82	81	80	79	77	76
JAX	TW J	745	82	81	79	78	76	75	73	71	69	67	65
JAX	TW J	750	69	67	65	63	60	58	56	53	51	48	46
JAX	TW J	755	73	71	69	67	65	63	61	58	56	53	51
JAX	TW J	760	70	68	66	64	62	59	57	54	52	49	47
JAX	TW J	765	97	96	94	94	93	92	92	91	91	90	90

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019

# Jacksonville International Airport (JAX)





Network		Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	TW K	1320	85	84	83	82	81	79	78	76	75	73	71
JAX	TW L	205	78	76	75	73	71	69	67	65	63	61	58
JAX	TW L	210	84	83	82	80	79	78	76	74	73	71	69
JAX	TW L	215	77	75	74	72	70	68	66	64	61	59	57
JAX	TW L	220	83	82	81	79	78	76	75	73	71	69	67
JAX	TW L	225	81	80	78	77	75	73	72	70	68	65	63
JAX	TW N	305	87	86	85	84	83	82	81	80	79	77	76
JAX	TW N	310	90	89	89	89	89	88	88	87	87	86	86
JAX	TW N	312	89	88	88	87	87	86	85	85	84	83	81
JAX	TW N	315	93	92	92	91	91	90	90	90	90	90	90
JAX	TW P	640	70	68	66	64	62	59	57	54	52	49	47
JAX	TW P	641	87	86	85	84	83	82	81	80	79	77	76
JAX	TW P	650	96	95	94	93	92	92	91	91	91	90	90
JAX	TW P	655	94	93	92	92	91	91	91	90	90	90	90
JAX	TW P	660	99	97	96	95	94	93	92	92	91	91	91
JAX	TW Q	560	85	84	83	82	81	79	78	76	75	73	71
JAX	TW R	570	86	85	84	83	82	81	79	78	77	75	73
JAX	TW R	575	88	87	87	86	85	84	83	82	81	80	78
JAX	TW R	576	86	85	84	83	82	81	79	78	77	75	73
JAX	TW S	1285	81	80	78	77	75	73	72	70	68	65	63
JAX	TW S	1290	78	76	75	73	71	69	67	65	63	61	58
JAX	TW T	1282	97	96	94	94	93	92	92	91	91	90	90
JAX	TW U	390	91	90	90	90	90	90	89	89	89	89	89
JAX	TW V	905	100	98	97	95	94	93	93	92	91	91	91





#### Major Rehabilitation Planning 2020-2029

Table E-3 Major Rehabilitation Planning 2020-2029

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	JAX	AP CARGO	4110	AC	27,040	31	AC Reconstruction	\$ 379,000.00
2020	JAX	AP CARGO	4125	PCC	84,968	46	PCC Restoration	\$ 1,610,000.00
2020	JAX	AP CARGO	4135	PCC	32,378	59	PCC Restoration	\$ 551,000.00
2020	JAX	AP GA	5105	AC	127,653	47	AC Restoration	\$ 1,484,000.00
2020	JAX	AP GA	5115	AC	28,389	60	AC Restoration	\$ 313,000.00
2020	JAX	TW AP	2715	AC	8,530	28	AC Reconstruction	\$ 120,000.00
2020	JAX	TW AP	2775	PCC	38,593	46	PCC Restoration	\$ 743,000.00
2020	JAX	TW F	1155	AC	98,961	27	AC Reconstruction	\$ 1,386,000.00
2020	JAX	TW G	1045	AAC	14,480	52	AC Restoration	\$ 160,000.00
2020	JAX	TW H	555	PCC	127,293	68	PCC Restoration	\$ 2,165,000.00
2021	JAX	TW AP	2772	PCC	33,940	63	PCC Restoration	\$ 577,000.00
2022	JAX	AP GA	5110	AC	239,174	63	AC Restoration	\$ 2,631,000.00
2022	JAX	AP TERM	4430	PCC	361,365	63	PCC Restoration	\$ 6,144,000.00
2022	JAX	TW AP	910	AC	134,973	64	AC Restoration	\$ 1,485,000.00
2022	JAX	TW J	750	PCC	21,670	63	PCC Restoration	\$ 369,000.00
2022	JAX	TW J	760	PCC	21,750	64	PCC Restoration	\$ 370,000.00
2022	JAX	TW P	640	PCC	60,825	64	PCC Restoration	\$ 1,035,000.00
2024	JAX	TW A	125	PCC	136,875	64	PCC Restoration	\$ 2,327,000.00
2024	JAX	TW C	1480	PCC	24,260	63	PCC Restoration	\$ 413,000.00
2024	JAX	TW J	755	PCC	13,125	63	PCC Restoration	\$ 224,000.00
2025	JAX	TW C	1490	PCC	50,660	63	PCC Restoration	\$ 862,000.00
2026	JAX	TW L	215	PCC	18,195	64	PCC Restoration	\$ 310,000.00
2027	JAX	TW A	105	PCC	54,448	64	PCC Restoration	\$ 926,000.00
2027	JAX	TW E	1670	PCC	29,143	63	PCC Restoration	\$ 496,000.00
2027	JAX	TW G	1020	PCC	29,478	63	PCC Restoration	\$ 502,000.00
2027	JAX	TW L	205	PCC	25,258	63	PCC Restoration	\$ 430,000.00
2027	JAX	TW S	1290	PCC	28,370	63	PCC Restoration	\$ 483,000.00
2028	JAX	AP TERM	4445	PCC	312,670	63	PCC Restoration	\$ 5,316,000.00
2028	JAX	TW A	120	PCC	271,875	64	PCC Restoration	\$ 4,622,000.00
2028	JAX	TW E	1680	PCC	59,400	64	PCC Restoration	\$ 1,010,000.00
2028	JAX	TW H	557	PCC	38,685	64	PCC Restoration	\$ 658,000.00
2029	JAX	TW A	110	PCC	168,750	63	PCC Restoration	\$ 2,869,000.00
2029	JAX	TW B	810	PCC	136,875	63	PCC Restoration	\$ 2,327,000.00
2029	JAX	TW L	225	PCC	52,307	63	PCC Restoration	\$ 890,000.00
2029	JAX	TW S	1285	PCC	140,346	63	PCC Restoration	\$ 2,386,000.00

\*All planning cost values have been rounded to the nearest thousand-dollar.





Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029



#### Summary of Jacksonville International Airport

Jacksonville International Airport was inspected in April 2019 – the overall weighted PCI value was 83, a condition rating of Satisfactory. The results of the maintenance, repair, and major rehabilitation analysis identified \$1,432,760 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$48,573,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$8,911,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.









# **Chapter 1 – Introduction**

#### 1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.

In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

#### 1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating publicuse airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.



Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.





#### 1.3 Organization

#### 1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

#### 1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

#### 1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

#### 1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys," evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.

**Airport Pavement Evaluation Report**  2019

Jacksonville International Airport (JAX)





A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- Research and evaluation of existing record documentation was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- An update to the existing Network Definition Map was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- A functional pavement evaluation with PCI Survey inspections was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- Condition Analysis was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- Maintenance, Repair, and Rehabilitation Planning was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." Planninglevel unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.





#### 1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

#### 1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.





During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER<sup>™</sup> (currently known as PAVER<sup>™</sup>) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER<sup>™</sup> system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (http://www.dot.state.fl.us/aviation/pavement.shtm) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys." The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.





#### 1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management **Program (PMP)**"). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications."

#### 1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC150/5380-7B "Airport Pavement Management Program (PMP)" an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

#### 1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- An objective and repeatable system for evaluating pavement condition.
- Procedures for predicting future pavement condition.
- Procedures for modeling both past and future pavement performance conditions.
- Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

#### 1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data





- F. Pavement Performance Modeling for the Prediction/Forecast of PCI
- G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements' past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and costeffective manner. Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, which is based on the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)." Figure 1.7.2 (a) Typical Pavement Condition Life Cycle, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.




Figure 1.7.2 (a) Typical Pavement Condition Life Cycle

\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).


Figure 1.7.2 (b) General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall





composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.

Figure 1.7.2 (b) General Pavement Treatments by Condition Range



Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in Figures 1.7.2 (a) and 1.7.2 (b), however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7.2 (c) and 1.7.2 (d), depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.



Figures 1.7.2 (c) Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabiliation	40-64	50	B	Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figures 1.7.2 (d) Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabiliation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.





#### 1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."
- FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program."
- FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements."
- FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation."
- Department of the Air Force, Air Force Civil Engineer Center "Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements."
- Unified Facilities Criteria (UFC) 3-260-16FA 16 "Airfield Pavement Condition Survey Procedures Pavements."
- Unified Facilities Criteria (UFC) 3-260-03 "Airfield Pavement Evaluation."
- Pavement Management for Airports, Roads, and Parking Lots 2<sup>nd</sup> Edition, M.Y. Shahin.



# **Chapter 2**





### **Chapter 2 – Methodology**

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)."

#### 2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER<sup>TM</sup> (formerly MicroPAVER<sup>TM</sup>); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER<sup>TM</sup> database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER<sup>TM</sup> version 6.5 to a version 7.0.

#### 2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.





A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's Aerial Photo Look Up System (APLUS). This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

#### 2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

#### **Pavement Network**

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement branches, which are typically comprised of one or many pavement sections. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

#### **Pavement Branch**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

#### **Pavement Section**

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related





infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a "parent" pavement network.

#### **Pavement Sample Unit**

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (±8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet (±2,000 ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	"Tallahassee International Airport – Airfield Pavements"
Branch Name	Commonly defined asset name as established by Airport and by use	"Runway 18-36"
Branch ID	Codified shorthand name for commonly defined asset established for database identification	"RW 18-36" RW, Branch Use, "Runway" 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following:  Pavement Composition Construction Work History Aircraft Traffic Condition Records	"6105"
Sample Unit	A numeric identification of an area of pavement (5,000±2,000 SF of AC or 20±8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	"300"





#### 2.3 Airfield Pavement Structure

#### 2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

#### Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

#### Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

#### Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

#### Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.





# Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

#### Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

#### Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

#### Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 8 inches in thickness.

# Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 8 inches in thickness.

# Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.





# 2.4 Airfield Pavement Work History

#### 2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

- 1. Location and Limits of Work.
- Types and Severity of Distresses Repaired.
- 3. Type of Work.
- 4. Cost of Work.
- 5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

#### 2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular 150/5320-6F Airport Pavement Design and **Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

# 2.6 Airfield Pavement Condition Index (PCI) Survey

# 2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)," the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method

**Statewide Airfield Pavement Management Program** 

**Airport Pavement Evaluation Report** 

2019

Jacksonville International Airport (JAX)





can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.





# 2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2 (a) Pavement Distress Types - Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms			
Alligator Cracking	Load / Fatigue			
Bleeding	Construction Quality/ Mix Design			
Block Cracking	Climate / Age			
Corrugation	Load / Construction Quality			
Depression	Load / Subsurface			
Jet Blast	Aircraft			
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load			
Longitudinal/Transverse Cracking	Climate / Construction Quality			
Oil Spillage	Aircraft / Vehicle			
Patching	Utility / Pavement Repair / Age			
Polished Aggregate	Repeated Traffic Loading			
Raveling	Climate / Age			
Rutting	Load / Fatigue			
Shoving	PCC Pavement Growth / Movement			
Slippage Cracking	Load / Pavement Bond / Mix Design			
Swelling	Climate / Subsurface			
Weathering	Climate / Age			





Table 2.6.2 (b) Pavement Distresses Possible Causes - Flexible Asphalt Concrete-Surfaced Airfields

	Classification by Poss	sible Causes	
Load	Climate / Durability	Moisture / Drainage	Others
<ul> <li>Alligator Cracking</li> <li>Corrugation</li> <li>Depression</li> <li>Patching of Load-based distress</li> <li>Polished Aggregate</li> <li>Rutting</li> <li>Slippage Cracking</li> </ul>	<ul> <li>Bleeding</li> <li>Block Cracking</li> <li>Joint Reflection Cracking</li> <li>L/T Cracking</li> <li>Patching of climate / durability-caused distresses</li> <li>Shoving from PCC</li> <li>Raveling</li> <li>Weathering</li> <li>Swelling</li> </ul>	<ul> <li>Alligator Cracking</li> <li>Depression</li> <li>Patching of moisture / drainage caused distress</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	Oil Spillage Jet Blast Erosion Polished Aggregate

Table 2.6.2 (c) Pavement Distresses Possible Effects - Flexible Asphalt Concrete-Surfaced Air fields

Classification by Possible Effects									
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements						
<ul> <li>Corrugation</li> <li>Depression</li> <li>Rutting</li> <li>Shoving of asphalt pavement</li> <li>Swelling</li> <li>Raveling</li> <li>Weathering</li> </ul>	<ul> <li>Bleeding</li> <li>Depression</li> <li>Polished Aggregate</li> <li>Rutting</li> </ul>	Block Cracking     Joint Reflection     Cracking     L/T Cracking     Slippage     Cracking	All Distresses						



Table 2.6.2 (d) Pavement Distresses - Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms			
Blowup	Climate / ASR			
Corner Break	Load Repetition / Curling Stresses			
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses			
Durability Cracking	Freeze-Thaw Cycling			
Joint Seal Damage	Material Deterioration / Construction Quality / Age			
Small Patch	Pavement Repair			
Large Patch/Utility Cut	Utility / Pavement Repair			
Popout	Freeze-Thaw Cycling / ASR / Material Quality			
Pumping	Load Repetition / Poor Joint Sealant			
Scaling	Construction Quality / Freeze-Thaw Cycling			
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer			
Shattered Slab	Overloading			
Shrinkage Cracking	Construction Quality / Climate			
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars			
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars			
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction			





Table 2.6.2 (e) Pavement Distresses Possible Causes - Rigid Portland Cement Concrete-Surfaced Airfields

	Classification by Pos	sible Causes	
Load	Climate / Durability	Moisture / Drainage	Others
<ul> <li>Corner Break</li> <li>Shattered Slab</li> <li>L/T/D Cracking</li> <li>Pumping</li> <li>Patching of Load-associated distress</li> <li>Spalling</li> </ul>	<ul> <li>Blowup</li> <li>"D" Cracking</li> <li>Joint Seal Damage</li> <li>Popouts</li> <li>Scaling</li> <li>Patch of Climate/Durability-associated distress</li> <li>Shrinkage Cracking</li> <li>Spalling</li> <li>L/T/D Cracking</li> </ul>	<ul> <li>Corner Break</li> <li>Shattered Slab</li> <li>Pumping</li> <li>Patching of Moisture/Drainage- associated distress</li> </ul>	Settlement     / Faulting

Table 2.6.2 (f) Pavement Distresses Possible Effects - Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Effects									
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements						
Blowup Corner Break L/T/D Cracking Shattered Slab Settlement / Faulting Spalling	<ul> <li>Settlement / Faulting</li> <li>Spalling</li> </ul>	Corner Break L/T/D Cracking "D" Cracking Joint Seal Damage Shattered Slab Popouts Scaling	All distresses						





#### 2.6.3 PCI Survey Inspection Procedures

#### Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following Tables 2.6.3 (a) and (b) define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total	Sample Units to Inspect				
Sample Units in Section	Runways	Taxiways, Aprons, and Others			
1 - 4	1	1			
5 - 10	2	1			
11 - 15	3	2			
16 - 30	5	3			
31 - 40	7	4			
41 - 50	8	5			
51 or more	20% but ≤20	10% but ≤10			

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in	Sample Units to Inspect				
Section	Runways	Taxiways, Aprons, and Others			
1 - 3	1	1			
4 - 6	2	1			
7 - 10	3	2			
11 - 15	4	2			
16 - 20	5	3			
21 - 30	7	3			
31 - 40	8	4			
41 - 50	10	5			
51 or more	20% but ≤20	10% but ≤10			





# 2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

#### Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured "(52) Weathering and Raveling" distress has been separated into two distresses "(52) Raveling" and "(57) Weathering." Previously, areas that were recorded as "Weathering and Raveling" were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where "Weathering" only exists and does not meet the definition of "Raveling," the PCI deduction is not as high as the former "Weathering and Raveling." Therefore, areas identified only as "(57) Weathering" based on current ASTM standards, which were previously identified as "(52) Weathering and Raveling," may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

# Rigid Portland Cement Concrete Pavement Distress Updates

The previous methodology defined "(70) Scaling" as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included Alkali-Silica Reaction, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as "(76) Alkali-Silica Reaction / ASR." As a result, the previous "(70) Scaling" numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded "(70) Scaling," and currently do not exhibit "(76) Alkali-Silica Reactivity / ASR" may potentially see an increase in PCI. Additionally, "(73) Shrinkage Cracks" has been redefined as "(73) Shrinkage Cracking". Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage can be caused by both atmospheric conditions and construction. Plastic shrinkage caused by atmospheric conditions develops when there is rapid loss of water in the surface of recently placed pavement. High winds or low humidity are contributing factors to evaporation. These shrinkage cracks can appear as a series of parallel cracks, usually 1 to 3 feet apart and do not extend very deep into the pavement's surface. Plastic shrinkage caused by construction can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.





Table 2.6.4 Summary of Updates to ASTM D5340-12

Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/ APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Crazing - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Crazing - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Crazing - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Crazing'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Crazing' may now be identified as 'Shrinkage Cracking'



# **Chapter 3**





# Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

#### 3.1 Airfield Pavement Network Information

#### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following Table 3.1.1 summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. Figure 3.1.1 (a) and Figure 3.1.1 (b) provides an inset view of the 2019 Airfield Pavement Network Definition Exhibit and the 2019 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.


Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Year	General Work Description
2013	TW J, TW P, TW V - New Construction: 16" P-501, 6" P-306, 6" Porous Agg. Blanket, Ext. P-152
2016	AP GA, TW AP, TW G - Reconstruction: Full depth mill, Base course rehabilitation, 4" P-401 Overlay
2017	TW AP - Mill and Overlay

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.



Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit




The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.





Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit



The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.


#### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, Figure 3.1.2 summarizes the average age of the pavement sections at the time of the PCI survey inspection. Age is determined to be the number of years since any major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.





Figure 3.1.2 Average Age of Pavements at Inspection



The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.






#### 3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. Figure 3.1.3 summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







# 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following Figures 3.1.4 (a) and (b) summarize the applicable pavement types observed at this specific airport's airfield.


**Airfield Pavement Surface Type by Area (SF)** 12,000,000 10,853,230 10,000,000 Area (Square Feet) 8,000,000 6,000,000 4,000,000 2,000,000 874,835 24,532 **PCC - Portland Cement** AAC - Asphalt Concrete AC - Asphalt Concrete Overlaid on AC Concrete Pavement Surface Type

Figure 3.1.4 (a) Pavement Surface Type by Area (SF)





Figure 3.1.4 (b) Pavement Surface Type by Area (%)



# 3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. Appendix A includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.





#### Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4105	695	426	296,070	PCC	1/1/1989
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4110	260	104	27,040	AC	1/1/1994
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4118	429	425	198,059	PCC	1/1/2000
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4120	413	515	212,550	PCC	1/1/1981
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4125	413	200	84,968	PCC	1/1/1968
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4135	265	120	32,378	PCC	5/1/2007
JAX	GA APRON	AP GA	APRON	4205	282	270	76,140	AC	1/1/2016
JAX	GA APRON	AP GA	APRON	5105	420	225	127,653	AC	1/1/2006
JAX	GA APRON	AP GA	APRON	5110	925	280	239,174	AC	1/1/2006
JAX	GA APRON	AP GA	APRON	5115	165	170	28,389	AC	1/1/2006
JAX	HOLDING APRON BETWEEN RWS 4, 13	AP HOLD	APRON	4405	533	281	150,030	PCC	1/1/1992
JAX	TERMINAL APRON	AP TERM	APRON	4305	210	180	36,141	PCC	1/1/1985
JAX	TERMINAL APRON	AP TERM	APRON	4310	580	250	144,838	PCC	1/1/1985
JAX	TERMINAL APRON	AP TERM	APRON	4315	570	250	146,950	PCC	1/1/1985
JAX	TERMINAL APRON	AP TERM	APRON	4410	642	150	95,567	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4412	125	105	24,650	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4415	360	285	101,704	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4420	660	310	195,814	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4425	1,020	630	643,219	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4430	820	440	361,365	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4435	1,040	600	625,548	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4440	810	150	121,630	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4445	875	355	312,670	PCC	1/1/1991
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6205	500	50	25,000	PCC	1/1/1996
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6207	1,000	50	50,000	PCC	1/1/1996





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6210	6,600	50	330,000	PCC	1/1/2000
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6215	13,200	50	622,500	PCC	1/1/2000
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6220	600	50	30,000	PCC	1/1/1996
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6225	1,200	50	60,000	PCC	1/1/1996
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6230	750	50	37,500	PCC	1/1/1996
JAX	RUNWAY 8-26	RW 8-26	RUNWAY	6105	10,000	100	1,000,000	PCC	1/1/1994
JAX	RUNWAY 8-26	RW 8-26	RUNWAY	6110	20,000	25	500,000	PCC	1/1/1994
JAX	TAXIWAY A	TW A	TAXIWAY	105	875	75	54,448	PCC	1/1/1983
JAX	TAXIWAY A	TW A	TAXIWAY	110	2,100	75	168,750	PCC	1/1/1989
JAX	TAXIWAY A	TW A	TAXIWAY	115	1,575	75	118,125	PCC	1/1/2000
JAX	TAXIWAY A	TW A	TAXIWAY	120	3,670	75	271,875	PCC	1/1/1985
JAX	TAXIWAY A	TW A	TAXIWAY	125	1,780	75	136,875	PCC	1/1/1994
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	910	1,245	108	134,973	AC	1/1/2006
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	915	190	70	8,630	AC	1/1/2016
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	920	210	90	23,852	AC	1/1/2016
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2715	160	45	8,530	AC	1/1/1994
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2720	180	50	10,052	AAC	1/1/2017
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2772	450	50	33,940	PCC	1/1/1981
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2774	450	75	50,906	PCC	1/1/1981
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2775	450	75	38,593	PCC	1/1/1968
JAX	TAXIWAY B	TW B	TAXIWAY	805	3,275	75	253,320	PCC	1/1/1985
JAX	TAXIWAY B	TW B	TAXIWAY	810	1,825	75	136,875	PCC	1/1/1994
JAX	TAXIWAY C	TW C	TAXIWAY	1480	176	90	24,260	PCC	1/1/1994
JAX	TAXIWAY C	TW C	TAXIWAY	1490	488	90	50,660	PCC	1/1/1994
JAX	TAXIWAY E	TW E	TAXIWAY	1670	176	90	29,143	PCC	1/1/1994
JAX	TAXIWAY E	TW E	TAXIWAY	1680	488	90	59,400	PCC	1/1/1985

Jacksonville International Airport (JAX)





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
JAX	TAXIWAY F	TW F	TAXIWAY	1145	176	94	30,320	PCC	1/1/1985
JAX	TAXIWAY F	TW F	TAXIWAY	1150	125	75	18,725	PCC	1/1/1985
JAX	TAXIWAY F	TW F	TAXIWAY	1155	1,320	75	98,961	AC	1/1/1968
JAX	TAXIWAY F	TW F	TAXIWAY	1170	222	90	27,436	PCC	1/1/1994
JAX	TAXIWAY F	TW F	TAXIWAY	1175	266	90	39,074	PCC	1/1/1985
JAX	TAXIWAY G	TW G	TAXIWAY	1020	176	90	29,478	PCC	1/1/1985
JAX	TAXIWAY G	TW G	TAXIWAY	1025	125	75	19,138	PCC	1/1/1985
JAX	TAXIWAY G	TW G	TAXIWAY	1030	700	50	35,019	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1032	870	50	44,449	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1035	190	35	7,929	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1040	150	60	14,096	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1045	223	60	14,480	AAC	1/1/2001
JAX	TAXIWAY G	TW G	TAXIWAY	1060	515	150	133,822	PCC	1/1/1994
JAX	TAXIWAY H	TW H	TAXIWAY	550	488	160	208,460	PCC	1/1/1994
JAX	TAXIWAY H	TW H	TAXIWAY	555	1,540	75	127,293	PCC	1/1/1985
JAX	TAXIWAY H	TW H	TAXIWAY	557	615	60	38,685	PCC	1/1/2007
JAX	TAXIWAY J	TW J	TAXIWAY	740	550	150	136,242	PCC	1/1/1994
JAX	TAXIWAY J	TW J	TAXIWAY	745	1,760	75	94,986	PCC	1/1/1989
JAX	TAXIWAY J	TW J	TAXIWAY	750	265	75	21,670	PCC	1/1/1982
JAX	TAXIWAY J	TW J	TAXIWAY	755	175	75	13,125	PCC	1/1/1968
JAX	TAXIWAY J	TW J	TAXIWAY	760	290	75	21,750	PCC	1/1/1984
JAX	TAXIWAY J	TW J	TAXIWAY	765	1,020	110	123,159	PCC	1/1/2013
JAX	TAXIWAY K	TW K	TAXIWAY	1320	795	92	107,334	PCC	1/1/1992
JAX	TAXIWAY L	TW L	TAXIWAY	205	244	90	25,258	PCC	1/1/1994
JAX	TAXIWAY L	TW L	TAXIWAY	210	244	90	28,620	PCC	1/1/1983
JAX	TAXIWAY L	TW L	TAXIWAY	215	206	90	18,195	PCC	1/1/1983

Jacksonville International Airport (JAX)





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
JAX	TAXIWAY L	TW L	TAXIWAY	220	240	90	25,304	PCC	1/1/1992
JAX	TAXIWAY L	TW L	TAXIWAY	225	488	90	52,307	PCC	1/1/1992
JAX	TAXIWAY N	TW N	TAXIWAY	305	2,950	75	221,250	PCC	1/1/1992
JAX	TAXIWAY N	TW N	TAXIWAY	310	2,451	75	180,075	PCC	1/1/1998
JAX	TAXIWAY N	TW N	TAXIWAY	312	1,775	75	131,250	PCC	1/1/2000
JAX	TAXIWAY N	TW N	TAXIWAY	315	525	75	45,000	PCC	1/1/1996
JAX	TAXIWAY P	TW P	TAXIWAY	640	811	75	60,825	PCC	1/1/1982
JAX	TAXIWAY P	TW P	TAXIWAY	641	250	75	8,909	PCC	1/1/1994
JAX	TAXIWAY P	TW P	TAXIWAY	650	550	140	133,322	PCC	1/1/1992
JAX	TAXIWAY P	TW P	TAXIWAY	655	1,500	75	79,579	PCC	1/1/1992
JAX	TAXIWAY P	TW P	TAXIWAY	660	1,050	100	126,658	PCC	1/1/2013
JAX	TAXIWAY Q	TW Q	TAXIWAY	560	690	90	115,700	PCC	1/1/1996
JAX	TAXIWAY R	TW R	TAXIWAY	570	380	90	43,767	PCC	1/1/1996
JAX	TAXIWAY R	TW R	TAXIWAY	575	1,210	75	111,623	PCC	1/1/1996
JAX	TAXIWAY R	TW R	TAXIWAY	576	240	115	29,713	PCC	1/1/1991
JAX	TAXIWAY S	TW S	TAXIWAY	1285	1,385	75	140,346	PCC	1/1/1989
JAX	TAXIWAYS	TW S	TAXIWAY	1290	220	100	28,370	PCC	1/1/1989
JAX	TAXIWAYT	TW T	TAXIWAY	1282	487	148	59,457	PCC	1/1/2012
JAX	TAXIWAY U	TW U	TAXIWAY	390	488	90	52,557	PCC	1/1/1998
JAX	TAXIWAY V	TW V	TAXIWAY	905	785	100	78,127	PCC	1/1/2013





#### PAGE INTENTIONALLY LEFT BLANK



# **Chapter 4**





# **Chapter 4 – Airfield Pavement** Condition

The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

# 4.1 Airfield Pavement Condition Index (Latest Inspection)

#### 4.1.1 Network-Level Analysis

The following Figure 4.1.1 summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.




Figure 4.1.1 Latest Condition - Overall Network

#### 4.1.2 Branch-Level Analysis

The following Figures 4.1.2 (a) through (c) summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.





Figure 4.1.2 (a) Latest Condition - Runway Pavements



Figure 4.1.2 (b) Latest Condition - Taxiway Pavements







Figure 4.1.2 (c) Latest Condition - Apron Pavements



#### 4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement. Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.

2019





#### Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
JAX	AP CARGO	CARGO AND AIR CARGO APRONS	APRON	4105	296,070	PCC	83	Satisfactory	11%	9%	80%	3	24
JAX	AP CARGO	CARGO AND AIR CARGO APRONS	APRON	4110	27,040	AC	33	Very Poor	89%	0%	11%	1	6
JAX	AP CARGO	CARGO AND AIR CARGO APRONS	APRON	4118	198,059	PCC	88	Good	0%	0%	100%	3	17
JAX	AP CARGO	CARGO AND AIR CARGO APRONS	APRON	4120	212,550	PCC	78	Satisfactory	0%	0%	100%	2	15
JAX	AP CARGO	CARGO AND AIR CARGO APRONS	APRON	4125	84,968	PCC	48	Poor	2%	35%	63%	2	8
JAX	AP CARGO	CARGO AND AIR CARGO APRONS	APRON	4135	32,378	PCC	61	Fair	3%	45%	52%	2	7
JAX	AP GA	GA APRON	APRON	4205	76,140	AC	89	Good	100%	0%	0%	2	15
JAX	AP GA	GA APRON	APRON	5105	127,653	AC	49	Poor	52%	9%	39%	3	28
JAX	AP GA	GA APRON	APRON	5110	239,174	AC	68	Fair	97%	0%	3%	5	45
JAX	AP GA	GA APRON	APRON	5115	28,389	AC	62	Fair	77%	0%	23%	2	6
JAX	AP HOLD	HOLDING APRON BETWEEN RWS 4, 13	APRON	4405	150,030	PCC	85	Satisfactory	0%	0%	100%	3	24
JAX	AP TERM	TERMINAL APRON	APRON	4305	36,141	PCC	79	Satisfactory	0%	0%	100%	1	3
JAX	AP TERM	TERMINAL APRON	APRON	4310	144,838	PCC	79	Satisfactory	0%	0%	100%	2	12
JAX	AP TERM	TERMINAL APRON	APRON	4315	146,950	PCC	86	Good	0%	0%	100%	2	12
JAX	AP TERM	TERMINAL APRON	APRON	4410	95,567	PCC	95	Good	0%	0%	100%	2	12
JAX	AP TERM	TERMINAL APRON	APRON	4412	24,650	PCC	97	Good	0%	0%	100%	1	2
JAX	AP TERM	TERMINAL APRON	APRON	4415	101,704	PCC	99	Good	0%	0%	100%	2	12
JAX	AP TERM	TERMINAL APRON	APRON	4420	195,814	PCC	94	Good	0%	0%	100%	4	24
JAX	AP TERM	TERMINAL APRON	APRON	4425	643,219	PCC	93	Good	0%	0%	100%	9	89
JAX	AP TERM	TERMINAL APRON	APRON	4430	361,365	PCC	68	Fair	5%	8%	87%	4	36
JAX	AP TERM	TERMINAL APRON	APRON	4435	625,548	PCC	88	Good	0%	7%	93%	10	86
JAX	AP TERM	TERMINAL APRON	APRON	4440	121,630	PCC	97	Good	0%	0%	100%	4	19
JAX	AP TERM	TERMINAL APRON	APRON	4445	312,670	PCC	76	Satisfactory	7%	0%	93%	4	28
JAX	RW 14-32	RUNWAY 14-32	RUNWAY	6205	25,000	PCC	82	Satisfactory	0%	0%	100%	1	2
JAX	RW 14-32	RUNWAY 14-32	RUNWAY	6207	50,000	PCC	87	Good	0%	0%	100%	2	4
JAX	RW 14-32	RUNWAY 14-32	RUNWAY	6210	330,000	PCC	92	Good	0%	0%	100%	7	27
JAX	RW 14-32	RUNWAY 14-32	RUNWAY	6215	622,500	PCC	93	Good	0%	0%	100%	12	51
JAX	RW 14-32	RUNWAY 14-32	RUNWAY	6220	30,000	PCC	89	Good	0%	0%	100%	1	3
JAX	RW 14-32	RUNWAY 14-32	RUNWAY	6225	60,000	PCC	94	Good	0%	0%	100%	2	6
JAX	RW 14-32	RUNWAY 14-32	RUNWAY	6230	37,500	PCC	90	Good	0%	0%	100%	1	3
JAX	RW 8-26	RUNWAY 8-26	RUNWAY	6105	1,000,000	PCC	89	Good	0%	0%	100%	16	80
JAX	RW 8-26	RUNWAY 8-26	RUNWAY	6110	500,000	PCC	83	Satisfactory	0%	0%	100%	8	40
JAX	TW A	TAXIWAY A	TAXIWAY	105	54,448	PCC	79	Satisfactory	0%	0%	100%	2	4
JAX	TW A	TAXIWAY A	TAXIWAY	110	168,750	PCC	81	Satisfactory	0%	0%	100%	3	13
JAX	TW A	TAXIWAY A	TAXIWAY	115	118,125	PCC	84	Satisfactory	0%	0%	100%	2	9
JAX	TW A	TAXIWAY A	TAXIWAY	120	271,875	PCC	80	Satisfactory	0%	26%	74%	4	21
JAX	TW A	TAXIWAY A	TAXIWAY	125	136,875	PCC	74	Satisfactory	0%	34%	66%	2	10

Jacksonville International Airport (JAX)





Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	910	134,973	AC	67	Fair	100%	0%	0%	3	26
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	915	8,630	AC	89	Good	100%	0%	0%	1	2
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	920	23,852	AC	86	Good	100%	0%	0%	1	4
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	2715	8,530	AC	31	Very Poor	81%	12%	7%	1	2
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	2720	10,052	AAC	83	Satisfactory	100%	0%	0%	1	2
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	2772	33,940	PCC	67	Fair	0%	0%	100%	1	4
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	2774	50,906	PCC	82	Satisfactory	10%	0%	90%	2	6
JAX	TW AP	TAXIWAYS WITHIN APRONS	TAXIWAY	2775	38,593	PCC	48	Poor	0%	45%	55%	1	3
JAX	TW B	TAXIWAY B	TAXIWAY	805	253,320	PCC	82	Satisfactory	0%	0%	100%	3	19
JAX	TW B	TAXIWAY B	TAXIWAY	810	136,875	PCC	81	Satisfactory	10%	0%	90%	2	10
JAX	TW C	TAXIWAY C	TAXIWAY	1480	24,260	PCC	73	Satisfactory	7%	0%	93%	1	2
JAX	TW C	TAXIWAY C	TAXIWAY	1490	50,660	PCC	75	Satisfactory	8%	0%	92%	2	4
JAX	TW E	TAXIWAY E	TAXIWAY	1670	29,143	PCC	78	Satisfactory	0%	0%	100%	1	4
JAX	TW E	TAXIWAY E	TAXIWAY	1680	59,400	PCC	80	Satisfactory	10%	0%	90%	2	8
JAX	TW F	TAXIWAY F	TAXIWAY	1145	30,320	PCC	90	Good	0%	0%	100%	1	6
JAX	TW F	TAXIWAY F	TAXIWAY	1150	18,725	PCC	86	Good	14%	0%	86%	1	3
JAX	TW F	TAXIWAY F	TAXIWAY	1155	98,961	AC	30	Very Poor	79%	9%	12%	3	18
JAX	TW F	TAXIWAY F	TAXIWAY	1170	27,436	PCC	82	Satisfactory	0%	0%	100%	1	4
JAX	TW F	TAXIWAY F	TAXIWAY	1175	39,074	PCC	93	Good	0%	0%	100%	1	4
JAX	TW G	TAXIWAY G	TAXIWAY	1020	29,478	PCC	78	Satisfactory	0%	0%	100%	1	6
JAX	TW G	TAXIWAY G	TAXIWAY	1025	19,138	PCC	85	Satisfactory	0%	0%	100%	1	3
JAX	TW G	TAXIWAY G	TAXIWAY	1030	35,019	AC	89	Good	100%	0%	0%	2	7
JAX	TW G	TAXIWAY G	TAXIWAY	1032	44,449	AC	94	Good	100%	0%	0%	2	9
JAX	TW G	TAXIWAY G	TAXIWAY	1035	7,929	AC	92	Good	100%	0%	0%	1	2
JAX	TW G	TAXIWAY G	TAXIWAY	1040	14,096	AC	89	Good	100%	0%	0%	1	3
JAX	TW G	TAXIWAY G	TAXIWAY	1045	14,480	AAC	53	Poor	63%	23%	14%	1	3
JAX	TW G	TAXIWAY G	TAXIWAY	1060	133,822	PCC	91	Good	0%	0%	100%	2	10
JAX	TW H	TAXIWAY H	TAXIWAY	550	208,460	PCC	88	Good	0%	12%	88%	3	18
JAX	TW H	TAXIWAY H	TAXIWAY	555	127,293	PCC	70	Fair	0%	23%	77%	2	11
JAX	TW H	TAXIWAY H	TAXIWAY	557	38,685	PCC	80	Satisfactory	0%	0%	100%	1	4
JAX	TW J	TAXIWAY J	TAXIWAY	740	136,242	PCC	87	Good	0%	0%	100%	2	12
JAX	TW J	TAXIWAY J	TAXIWAY	745	94,986	PCC	82	Satisfactory	0%	0%	100%	2	8
JAX	TW J	TAXIWAY J	TAXIWAY	750	21,670	PCC	69	Fair	6%	12%	82%	1	2
JAX	TW J	TAXIWAY J	TAXIWAY	755	13,125	PCC	73	Satisfactory	0%	0%	100%	1	1
JAX	TW J	TAXIWAY J	TAXIWAY	760	21,750	PCC	70	Fair	6%	0%	94%	1	2
JAX	TW J	TAXIWAY J	TAXIWAY	765	123,159	PCC	97	Good	0%	0%	100%	3	19
JAX	TW K	TAXIWAY K	TAXIWAY	1320	107,334	PCC	85	Satisfactory	0%	0%	100%	3	18
JAX	TW L	TAXIWAY L	TAXIWAY	205	25,258	PCC	78	Satisfactory	0%	0%	100%	1	3

Statewide Airfield Pavement
Management Program
Airport Pavement
Evaluation Report

2019

Jacksonville International Airport (JAX)





Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
JAX	TW L	TAXIWAY L	TAXIWAY	210	28,620	PCC	84	Satisfactory	0%	0%	100%	1	3
JAX	TW L	TAXIWAY L	TAXIWAY	215	18,195	PCC	77	Satisfactory	0%	0%	100%	1	2
JAX	TW L	TAXIWAY L	TAXIWAY	220	25,304	PCC	83	Satisfactory	0%	0%	100%	1	4
JAX	TW L	TAXIWAY L	TAXIWAY	225	52,307	PCC	81	Satisfactory	0%	0%	100%	2	9
JAX	TW N	TAXIWAY N	TAXIWAY	305	221,250	PCC	87	Good	0%	0%	100%	5	36
JAX	TW N	TAXIWAY N	TAXIWAY	310	180,075	PCC	90	Good	0%	0%	100%	2	14
JAX	TW N	TAXIWAY N	TAXIWAY	312	131,250	PCC	89	Good	0%	0%	100%	2	10
JAX	TW N	TAXIWAY N	TAXIWAY	315	45,000	PCC	93	Good	0%	0%	100%	1	3
JAX	TW P	TAXIWAY P	TAXIWAY	640	60,825	PCC	70	Fair	7%	0%	93%	1	5
JAX	TW P	TAXIWAY P	TAXIWAY	641	8,909	PCC	87	Good	15%	0%	85%	1	1
JAX	TW P	TAXIWAY P	TAXIWAY	650	133,322	PCC	96	Good	0%	0%	100%	3	19
JAX	TW P	TAXIWAY P	TAXIWAY	655	79,579	PCC	94	Good	0%	0%	100%	2	15
JAX	TW P	TAXIWAY P	TAXIWAY	660	126,658	PCC	99	Good	85%	0%	15%	3	19
JAX	TW Q	TAXIWAY Q	TAXIWAY	560	115,700	PCC	85	Satisfactory	0%	0%	100%	2	9
JAX	TW R	TAXIWAY R	TAXIWAY	570	43,767	PCC	86	Good	0%	0%	100%	1	4
JAX	TW R	TAXIWAY R	TAXIWAY	575	111,623	PCC	88	Good	0%	0%	100%	2	7
JAX	TW R	TAXIWAY R	TAXIWAY	576	29,713	PCC	86	Good	0%	0%	100%	1	3
JAX	TW S	TAXIWAY S	TAXIWAY	1285	140,346	PCC	81	Satisfactory	0%	0%	100%	3	12
JAX	TW S	TAXIWAY S	TAXIWAY	1290	28,370	PCC	78	Satisfactory	0%	14%	86%	1	2
JAX	TW T	TAXIWAYT	TAXIWAY	1282	59,457	PCC	97	Good	0%	0%	100%	2	7
JAX	TW U	TAXIWAY U	TAXIWAY	390	52,557	PCC	91	Good	0%	0%	100%	1	5
JAX	TW V	TAXIWAY V	TAXIWAY	905	78,127	PCC	100	Good	0%	0%	100%	2	10





Figure 4.1.3 is an inset view of the 2019 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits.** 

Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit

# 4.2 Summary of Pavement Condition Evaluation Results

#### 4.2.1 Network-Level Observations

The field PCI Survey performed at Jacksonville International Airport (JAX) was completed in April 2019. The resulting overall area-weighted average PCI value was 83 representing a condition rating of Satisfactory. Jacksonville International Airport is serviced by two runways; Runway 8-26 is 150-ft wide and 10,000-ft long and Runway 14-32 is 150-ft wide and 7,701-ft long.

Based on the FAA 5010 Report as of 09/12/2019 the Airport has reported 108,637 operations for 12 months ending 05/31/2019.

#### 4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and samplelevel may be referenced for all pavements assessed as part of this System Update. The branchlevel observations discussed are limited to select branches based on use and condition.





#### Runway 8-26

Runway 8-26 consists of 2 sections constructed of PCC. The last construction year for Runway 8-26 was 1994. The area-weighted average PCI for Runway 8-26 is 87 representing a Good condition rating. The pavement distresses observed were related to Other distress classifications. Distresses observed on Runway 8-26 consist of Small Patch, Large Patch/Utility Cut, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### Runway 14-32

Runway 14-32 consists of 7 sections constructed of PCC. The last construction years range from 1996 to 2000. The area-weighted average PCI for Runway 14-32 is 92 representing a Good condition rating. The pavement distresses observed were related to Other distress classifications. Distresses observed on Runway 14-32 consist of Small Patch, Large Patch/Utility Cut, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### Taxiway A

Taxiway A consists of 5 sections constructed of PCC. The last construction years range from 1983 to 2000. The area-weighted average PCI for Taxiway A is 79 representing a Satisfactory condition rating. The pavement distresses observed were related to Load and Other distress classifications. Distresses observed on Taxiway A consist of Corner Break, Linear Cracking, Small Patch, Large Patch/Utility Cut, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### Taxiway H

Taxiway H consists of 3 sections constructed of PCC. The last construction years range from 1985 to 2007. The area-weighted average PCI for Taxiway H is 81 representing a Satisfactory condition rating. The pavement distresses observed were related to Load and Other distress classifications. Distresses observed on Taxiway H consist of Corner Break, Linear Cracking, Small Patch, Large Patch/Utility Cut, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### Taxiway N

Taxiway N consists of 4 sections constructed of PCC. The last construction years range from 1992 to 2000. The area-weighted average PCI for Taxiway N is 88 representing a Good condition rating. The pavement distresses observed were related to Other distress classifications. Distresses observed on Taxiway N consist of Small Patch, Scaling, Shrinkage Cracking, Joint Spall, and Corner Spall.

# Terminal Apron

The Terminal Apron consists of 12 sections constructed of PCC. The last construction years range from 1985 to 2007. The area-weighted average PCI for the Terminal Apron is 86 representing a Good condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on the Terminal Apron consist of Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Faulting, Shrinkage Cracking, Joint Spall, and Corner Spall.

# Cargo and Air Cargo Aprons

The Cargo and Air Cargo Aprons consists of 6 sections constructed of AC and PCC. The last construction years range from 1968 to 2007. The area-weighted average PCI for the Cargo and





Air Cargo Aprons is 76 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on the Cargo and Air Cargo Aprons consist of Block Cracking, Depression, Raveling, Corner Break, Linear Cracking, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Scaling, Shattered Slab, Shrinkage Cracking, Joint Spall, and Corner Spall.

#### GA Apron

The GA Apron consists of 4 sections constructed of AC. The last construction years range from 2006 to 2016. The area-weighted average PCI for the GA Apron is 65 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other distress classifications. Distresses observed on the GA Apron consist of Alligator Cracking. Block Cracking, Depression, Longitudinal & Transverse Cracking, Oil Spillage, Patching, Raveling, Swelling, and Weathering.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Area-Weighted Average PCI	Condition Rating
Runway	89	Good
Taxiway	82	Satisfactory
Apron	82	Satisfactory

#### 4.3 Forecasted Pavement Conditions

#### 4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to developed forecasted PCI values based on historic trends and statistical models.

#### 4.3.2 Branch-Level Pavement Condition Forecast

The following Figures 4.3.2 (a) through (c) depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2020 through January 2029.





Figure 4.3.2 (a) Forecasted Runway Pavement Performance




Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance









Figure 4.3.2 (c) Forecasted Apron Pavement Performance



#### 4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.





Table 4.3.3 Forecasted PCI 2020-2029

Network	Duranah ID	Section	L POL					Forecas	sted PCI				
ID	Branch ID	ID	Last PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	AP CARGO	4105	83	82	81	80	80	79	78	77	76	74	73
JAX	AP CARGO	4110	33	31	30	28	27	25	24	22	20	19	17
JAX	AP CARGO	4118	88	87	86	85	85	84	83	83	82	81	80
JAX	AP CARGO	4120	78	77	76	75	73	72	71	69	68	66	65
JAX	AP CARGO	4125	48	46	44	43	41	39	37	36	34	33	31
JAX	AP CARGO	4135	61	59	58	56	54	52	50	48	47	45	43
JAX	AP GA	4205	89	87	86	84	83	81	80	78	76	75	73
JAX	AP GA	5105	49	47	46	44	43	41	40	38	36	35	33
JAX	AP GA	5110	68	66	65	63	62	60	59	57	55	54	52
JAX	AP GA	5115	62	60	59	57	56	54	53	51	49	48	46
JAX	AP HOLD	4405	85	84	83	83	82	81	80	79	78	77	76
JAX	AP TERM	4305	79	78	77	76	75	73	72	71	69	68	66
JAX	AP TERM	4310	79	78	77	76	75	73	72	71	69	68	66
JAX	AP TERM	4315	86	85	84	84	83	82	81	81	80	79	78
JAX	AP TERM	4410	95	93	92	91	89	88	87	87	86	85	84
JAX	AP TERM	4412	97	95	93	92	91	89	88	87	87	86	85
JAX	AP TERM	4415	99	97	95	93	92	91	89	88	87	87	86
JAX	AP TERM	4420	94	92	91	90	89	88	87	86	85	85	84
JAX	AP TERM	4425	93	92	90	89	88	87	86	86	85	84	83
JAX	AP TERM	4430	68	66	65	63	61	60	58	56	54	53	51
JAX	AP TERM	4435	88	87	86	85	85	84	83	83	82	81	80
JAX	AP TERM	4440	97	95	93	92	91	89	88	87	87	86	85
JAX	AP TERM	4445	76	75	73	72	71	69	68	66	65	63	61
JAX	RW 14-32	6205	82	81	79	78	76	75	73	71	69	67	65
JAX	RW 14-32	6207	87	86	85	84	83	82	81	80	79	77	76





Network	Branch ID	Section	Last PCI					Forecas	sted PCI				
ID	Branch ID	ID	Last PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	RW 14-32	6210	92	91	91	91	90	90	90	90	90	89	89
JAX	RW 14-32	6215	93	92	92	91	91	90	90	90	90	90	90
JAX	RW 14-32	6220	89	88	88	87	87	86	85	85	84	83	81
JAX	RW 14-32	6225	94	93	92	92	91	91	91	90	90	90	90
JAX	RW 14-32	6230	90	89	89	89	89	88	88	87	87	86	86
JAX	RW 8-26	6105	89	88	88	87	87	86	85	85	84	83	81
JAX	RW 8-26	6110	83	82	81	79	78	76	75	73	71	69	67
JAX	TW A	105	79	78	76	74	73	71	69	67	64	62	60
JAX	TW A	110	81	80	78	77	75	73	72	70	68	65	63
JAX	TW A	115	84	83	82	80	79	78	76	74	73	71	69
JAX	TW A	120	80	79	77	75	74	72	70	68	66	64	62
JAX	TW A	125	74	72	70	68	66	64	62	60	57	55	52
JAX	TW AP	910	67	66	65	64	64	63	62	61	61	60	59
JAX	TW AP	915	89	87	85	84	82	80	79	77	76	75	73
JAX	TW AP	920	86	84	83	81	79	78	77	75	74	73	71
JAX	TW AP	2715	31	28	25	21	18	14	10	6	3	0	0
JAX	TW AP	2720	83	81	80	78	77	76	74	73	72	71	70
JAX	TW AP	2772	67	65	63	61	58	56	53	51	48	46	43
JAX	TW AP	2774	82	81	79	78	76	75	73	71	69	67	65
JAX	TW AP	2775	48	46	43	41	38	35	33	30	28	26	24
JAX	TW B	805	82	81	79	78	76	75	73	71	69	67	65
JAX	TW B	810	81	80	78	77	75	73	72	70	68	65	63
JAX	TW C	1480	73	71	69	67	65	63	61	58	56	53	51
JAX	TW C	1490	75	73	71	70	68	65	63	61	59	56	54
JAX	TW E	1670	78	76	75	73	71	69	67	65	63	61	58
JAX	TW E	1680	80	79	77	75	74	72	70	68	66	64	62
JAX	TW F	1145	90	89	89	89	89	88	88	87	87	86	86

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019





Network	Branch ID	Section	Last PCI					Forecas	sted PCI				
ID	Branch ID	ID	Last PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	TW F	1150	86	85	84	83	82	81	79	78	77	75	73
JAX	TW F	1155	30	27	24	20	16	13	9	5	2	0	0
JAX	TW F	1170	82	81	79	78	76	75	73	71	69	67	65
JAX	TW F	1175	93	92	92	91	91	90	90	90	90	90	90
JAX	TW G	1020	78	76	75	73	71	69	67	65	63	61	58
JAX	TW G	1025	85	84	83	82	81	79	78	76	75	73	71
JAX	TW G	1030	89	87	85	84	82	80	79	77	76	75	73
JAX	TW G	1032	94	92	90	88	86	85	83	81	80	78	77
JAX	TW G	1035	92	90	88	86	85	83	81	80	78	77	75
JAX	TW G	1040	89	87	85	84	82	80	79	77	76	75	73
JAX	TW G	1045	53	52	52	51	50	49	49	48	47	46	44
JAX	TW G	1060	91	90	90	90	90	90	89	89	89	89	89
JAX	TW H	550	88	87	87	86	85	84	83	82	81	80	78
JAX	TW H	555	70	68	66	64	62	59	57	54	52	49	47
JAX	TW H	557	80	79	77	75	74	72	70	68	66	64	62
JAX	TW J	740	87	86	85	84	83	82	81	80	79	77	76
JAX	TW J	745	82	81	79	78	76	75	73	71	69	67	65
JAX	TW J	750	69	67	65	63	60	58	56	53	51	48	46
JAX	TW J	755	73	71	69	67	65	63	61	58	56	53	51
JAX	TW J	760	70	68	66	64	62	59	57	54	52	49	47
JAX	TW J	765	97	96	94	94	93	92	92	91	91	90	90
JAX	TW K	1320	85	84	83	82	81	79	78	76	75	73	71
JAX	TW L	205	78	76	75	73	71	69	67	65	63	61	58
JAX	TW L	210	84	83	82	80	79	78	76	74	73	71	69
JAX	TW L	215	77	75	74	72	70	68	66	64	61	59	57
JAX	TW L	220	83	82	81	79	78	76	75	73	71	69	67
JAX	TW L	225	81	80	78	77	75	73	72	70	68	65	63

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019





Network	Daniel ID	Section	L ( DOI					Forecas	sted PCI				
ID	Branch ID	ID	Last PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	TW N	305	87	86	85	84	83	82	81	80	79	77	76
JAX	TW N	310	90	89	89	89	89	88	88	87	87	86	86
JAX	TW N	312	89	88	88	87	87	86	85	85	84	83	81
JAX	TW N	315	93	92	92	91	91	90	90	90	90	90	90
JAX	TW P	640	70	68	66	64	62	59	57	54	52	49	47
JAX	TW P	641	87	86	85	84	83	82	81	80	79	77	76
JAX	TW P	650	96	95	94	93	92	92	91	91	91	90	90
JAX	TW P	655	94	93	92	92	91	91	91	90	90	90	90
JAX	TW P	660	99	97	96	95	94	93	92	92	91	91	91
JAX	TW Q	560	85	84	83	82	81	79	78	76	75	73	71
JAX	TW R	570	86	85	84	83	82	81	79	78	77	75	73
JAX	TW R	575	88	87	87	86	85	84	83	82	81	80	78
JAX	TW R	576	86	85	84	83	82	81	79	78	77	75	73
JAX	TW S	1285	81	80	78	77	75	73	72	70	68	65	63
JAX	TW S	1290	78	76	75	73	71	69	67	65	63	61	58
JAX	TW T	1282	97	96	94	94	93	92	92	91	91	90	90
JAX	TW U	390	91	90	90	90	90	90	89	89	89	89	89
JAX	TW V	905	100	98	97	95	94	93	93	92	91	91	91





#### 4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA AC 150/5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements to determine structural and/or functional conditions at the time of project.









# Chapter 5 - Localized Maintenance and **Repair Planning**

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- Localized Maintenance and Repair includes patching and crack sealing.
- > Global Treatments include surface seals and rejuvenators for flexible pavements.
- > Major Rehabilitation includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

## 5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distressed pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety ("stopgap") measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

# Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

#### **Localized Preventive Maintenance and Repair**

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.





# 5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in Table 5.2 (a) and Table 5.2 (b), for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA AC 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and the FDOT Airfield Pavement Distress Repair Manual. Additionally, the Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2 (a) Localized Maintenance and Repair - Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft





Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L&TCR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L&TCR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2 (b) Localized Maintenance and Repair - Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt





Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT – SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt





#### Table 5.2 (c) Localized Repair Planning-Level Unit Costs - Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$12.50	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$5.50	SqFt

Table 5.2 (d) Localized M&R Planning-Level Unit Costs - Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$185.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

<sup>\*</sup>PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.





# 5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in 5.2 Localized M&R Policy. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. Appendix B provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to nearterm Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3 (a)** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Pla	nning Material Cost
FDOT - CRACK SEALING - PCC	PREVENTIVE	2,250	Ft	\$	9,560.00
FDOT - JOINT SEAL - PCC	PREVENTIVE	71,815	Ft	\$	197,480.00
FDOT - PATCHING - PCC FULL DEPTH	PREVENTIVE	1,475	SqFt	\$	272,430.00
FDOT - SURFACE SEAL	PREVENTIVE	52,585	SqFt	\$	28,930.00
FDOT - PATCHING - AC PARTIAL DEPTH	PREVENTIVE	10,135	SqFt	\$	55,730.00
FDOT - CRACK SEALING - AC	PREVENTIVE	665	Ft	\$	1,990.00
FDOT - PATCHING - PCC PARTIAL DEPTH	PREVENTIVE	1,350	SqFt	\$	96,960.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	9,815	SqFt	\$	122,640.00
FDOT - SURFACE SEAL	STOPGAP	174,815	SqFt	\$	96,150.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	14,445	SqFt	\$	79,440.00
FDOT - CRACK SEALING - AC	STOPGAP	8,605	Ft	\$	25,810.00
FDOT - PATCHING - PCC PARTIAL DEPTH	STOPGAP	170	SqFt	\$	11,900.00
FDOT - JOINT SEAL - PCC	STOPGAP	7,330	Ft	\$	20,150.00
FDOT - CRACK SEALING - PCC	STOPGAP	870	Ft	\$	3,680.00
FDOT - PATCHING - PCC FULL DEPTH	STOPGAP	2,220	SqFt	\$	409,910.00





The following Table 5.3 (b) provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved "End Condition" of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
JAX	AP CARGO	4105	296,070	83	84	\$ 36,850.00
JAX	AP CARGO	4110	27,040	33	59	\$ 72,920.00
JAX	AP CARGO	4118	198,059	88	88	\$ 40.00
JAX	AP CARGO	4120	212,550	78	79	\$ 3,050.00
JAX	AP CARGO	4125	84,968	48	62	\$ 334,190.00
JAX	AP CARGO	4135	32,378	61	65	\$ 107,540.00
JAX	AP GA	4205	76,140	89	89	\$ -
JAX	AP GA	5105	127,653	49	62	\$ 118,090.00
JAX	AP GA	5110	239,174	68	75	\$ 84,670.00
JAX	AP GA	5115	28,389	62	69	\$ 12,050.00
JAX	AP HOLD	4405	150,030	85	85	\$ 60.00
JAX	AP TERM	4305	36,141	79	82	\$ 620.00
JAX	AP TERM	4310	144,838	79	81	\$ 2,510.00
JAX	AP TERM	4315	146,950	86	86	\$ 50.00
JAX	AP TERM	4410	95,567	95	95	\$ 50.00
JAX	AP TERM	4412	24,650	97	97	\$ -
JAX	AP TERM	4415	101,704	99	99	\$ 50.00
JAX	AP TERM	4420	195,814	94	96	\$ 4,250.00
JAX	AP TERM	4425	643,219	93	93	\$ 4,300.00
JAX	AP TERM	4430	361,365	68	72	\$ 253,080.00
JAX	AP TERM	4435	625,548	88	88	\$ 3,610.00
JAX	AP TERM	4440	121,630	97	97	\$ 40.00
JAX	AP TERM	4445	312,670	76	80	\$ 28,530.00
JAX	RW 14-32	6205	25,000	82	82	\$ 20.00
JAX	RW 14-32	6207	50,000	87	87	\$ 20.00
JAX	RW 14-32	6210	330,000	92	92	\$ 370.00
JAX	RW 14-32	6215	622,500	93	94	\$ 1,120.00
JAX	RW 14-32	6220	30,000	89	89	\$ -
JAX	RW 14-32	6225	60,000	94	94	\$ -
JAX	RW 14-32	6230	37,500	90	90	\$ 50.00
JAX	RW 8-26	6105	1,000,000	89	89	\$ 110.00
JAX	RW 8-26	6110	500,000	83	84	\$ 5,080.00
JAX	TW A	105	54,448	79	79	\$ 130.00





Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
JAX	TW A	110	168,750	81	81	\$ 150.00
JAX	TW A	115	118,125	84	84	\$ -
JAX	TW A	120	271,875	80	82	\$ 6,800.00
JAX	TW A	125	136,875	74	74	\$ 190.00
JAX	TW AP	910	134,973	67	69	\$ 1,700.00
JAX	TW AP	915	8,630	89	89	\$ -
JAX	TW AP	920	23,852	86	86	\$ -
JAX	TW AP	2715	8,530	31	54	\$ 14,970.00
JAX	TW AP	2720	10,052	83	88	\$ 280.00
JAX	TW AP	2772	33,940	67	70	\$ 830.00
JAX	TW AP	2774	50,906	82	84	\$ 3,970.00
JAX	TW AP	2775	38,593	48	55	\$ 4,000.00
JAX	TW B	805	253,320	82	85	\$ 5,050.00
JAX	TW B	810	136,875	81	82	\$ 14,070.00
JAX	TW C	1480	24,260	73	75	\$ 2,830.00
JAX	TW C	1490	50,660	75	79	\$ 8,790.00
JAX	TW E	1670	29,143	78	78	\$ 60.00
JAX	TW E	1680	59,400	80	82	\$ 8,100.00
JAX	TW F	1145	30,320	90	90	\$ -
JAX	TW F	1150	18,725	86	88	\$ 1,550.00
JAX	TW F	1155	98,961	30	51	\$ 97,270.00
JAX	TW F	1170	27,436	82	82	\$ -
JAX	TW F	1175	39,074	93	93	\$ -
JAX	TW G	1020	29,478	78	79	\$ 21,810.00
JAX	TW G	1025	19,138	85	85	\$ 20.00
JAX	TW G	1030	35,019	89	89	\$ -
JAX	TW G	1032	44,449	94	94	\$ -
JAX	TW G	1035	7,929	92	92	\$ -
JAX	TW G	1040	14,096	89	89	\$ -
JAX	TW G	1045	14,480	53	71	\$ 8,840.00
JAX	TW G	1060	133,822	91	91	\$ 60.00
JAX	TW H	550	208,460	88	89	\$ 1,010.00
JAX	TW H	555	127,293	70	74	\$ 111,320.00
JAX	TW H	557	38,685	80	80	\$ 70.00
JAX	TW J	740	136,242	87	87	\$ -
JAX	TW J	745	94,986	82	82	\$ 30.00
JAX	TW J	750	21,670	69	71	\$ 3,550.00
JAX	TW J	755	13,125	73	76	\$ 620.00
JAX	TW J	760	21,750	70	75	\$ 4,170.00





Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
JAX	TW J	765	123,159	97	97	\$ 40.00
JAX	TW K	1320	107,334	85	85	\$ -
JAX	TW L	205	25,258	78	81	\$ 810.00
JAX	TW L	210	28,620	84	84	\$ 20.00
JAX	TW L	215	18,195	77	77	\$ 60.00
JAX	TW L	220	25,304	83	83	\$ -
JAX	TW L	225	52,307	81	81	\$ 150.00
JAX	TW N	305	221,250	87	88	\$ 1,770.00
JAX	TW N	310	180,075	90	91	\$ 3,290.00
JAX	TW N	312	131,250	89	89	\$ -
JAX	TW N	315	45,000	93	94	\$ 590.00
JAX	TW P	640	60,825	70	76	\$ 13,270.00
JAX	TW P	641	8,909	87	89	\$ 3,240.00
JAX	TW P	650	133,322	96	96	\$ 120.00
JAX	TW P	655	79,579	94	94	\$ 50.00
JAX	TW P	660	126,658	99	100	\$ 9,210.00
JAX	TW Q	560	115,700	85	86	\$ 1,060.00
JAX	TW R	570	43,767	86	90	\$ 1,680.00
JAX	TW R	575	111,623	88	91	\$ 2,320.00
JAX	TW R	576	29,713	86	86	\$ -
JAX	TW S	1285	140,346	81	81	\$ 200.00
JAX	TW S	1290	28,370	78	78	\$ 100.00
JAX	TW T	1282	59,457	97	97	\$ 80.00
JAX	TW U	390	52,557	91	91	\$ 30.00
JAX	TW V	905	78,127	100	100	\$ -

The following Table 5.3 (c) provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (c) Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 663,080.00
Stopgap	\$ 769,680.00
Planning-Level Localized M&R Needs =	\$ 1,432,760.00



# **Chapter 6**






# Chapter 6 – Major Rehabilitation **Planning**

## 6.1 Major Rehabilitation


Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. Figures 6.1 (a) and 6.1 (b) depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, PCI ≤ Critical PCI





Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, PCI > Critical PCI







#### 6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The Critical PCI concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

- 1. Develop a pavement performance model and refine a prediction model for the pavements considered.
- 2. Select a localized maintenance and repair policy to be used in developing a work
- Apply the selected localized policy to the pavement sections for a range of PCI.
- 4. Compute the unit cost per area for each PCI range.
- 5. Plot the cost versus the PCI.
- 6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

#### 6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended *Minimum Service-Level PCI* for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. Table 6.1.2 summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	70	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	65	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)





# 6.2 Major Rehabilitation Policy

#### 6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA AC 150/5320-6F "Airport Pavement Design and Evaluation." It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following Tables 6.2.1 (a) and (b) provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average PR Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation - Flexible Asphalt Concrete

Rehabilitation Type	Commercial (PR) Airport
AC Restoration  Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.	75% Mill and Overlay P-101 AC Milling (4") P-603 Bituminous Tack P-401 (HMA) (4")
PCI = 41 to 65	25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (6")  Excludes any paved shoulder features.
AC Reconstruction  Full-depth asphalt pavement section reconstruction.	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (6")
PCI = 40 or less	Excludes any paved shoulder features.



Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation - Rigid Portland Cement Concrete

Rehabilitation Type	Commercial (PR) Airport
PCC Restoration  Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.  PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (16")  *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction  Full-depth rigid pavement section reconstruction.  PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (6") P-501 Rigid PCC (17")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA AC 150/5380-7B Airport Pavement Management Program (PMP) and AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in AC 5320-6F Airport Pavement Design and Evaluation and AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

The recommendations identified in the Major Rehabilitation Needs consider the FAA AC 150/5370-10H Standard Specifications for Construction of Airports when determining the appropriate materials and methods implemented for construction projects, such as pavement rehabilitation, on airports. It should be noted that the AC 150/5370-10H Standard Specifications for Construction of Airports was updated in December of 2018. Design-level determination of project specific specifications based on the AC should be developed by the Airport when performing applicable construction projects.





#### 6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 Commercial Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	le Asphalt Cost Per SF	Rigid Portland Cement Concrete Cost per SF		
Restoration	41 to 65	\$ 11.00	\$	17.00	
Reconstruction	0 to 40	\$ 14.00	\$	23.00	

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

## 6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a payement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

#### 6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level





investigation, and budgetary constraints. The following Table 6.3.1 summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.

Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	JAX	AP CARGO	4110	AC	27,040	31	AC Reconstruction	\$ 379,000.00
2020	JAX	AP CARGO	4125	PCC	84,968	46	PCC Restoration	\$ 1,610,000.00
2020	JAX	AP CARGO	4135	PCC	32,378	59	PCC Restoration	\$ 551,000.00
2020	JAX	AP GA	5105	AC	127,653	47	AC Restoration	\$ 1,484,000.00
2020	JAX	AP GA	5115	AC	28,389	60	AC Restoration	\$ 313,000.00
2020	JAX	TW AP	2715	AC	8,530	28	AC Reconstruction	\$ 120,000.00
2020	JAX	TW AP	2775	PCC	38,593	46	PCC Restoration	\$ 743,000.00
2020	JAX	TW F	1155	AC	98,961	27	AC Reconstruction	\$ 1,386,000.00
2020	JAX	TW G	1045	AAC	14,480	52	AC Restoration	\$ 160,000.00
2020	JAX	TW H	555	PCC	127,293	68	PCC Restoration	\$ 2,165,000.00
2021	JAX	TW AP	2772	PCC	33,940	63	PCC Restoration	\$ 577,000.00
2022	JAX	AP GA	5110	AC	239,174	63	AC Restoration	\$ 2,631,000.00
2022	JAX	AP TERM	4430	PCC	361,365	63	PCC Restoration	\$ 6,144,000.00
2022	JAX	TW AP	910	AC	134,973	64	AC Restoration	\$ 1,485,000.00
2022	JAX	TW J	750	PCC	21,670	63	PCC Restoration	\$ 369,000.00
2022	JAX	TW J	760	PCC	21,750	64	PCC Restoration	\$ 370,000.00
2022	JAX	TW P	640	PCC	60,825	64	PCC Restoration	\$ 1,035,000.00
2024	JAX	TW A	125	PCC	136,875	64	PCC Restoration	\$ 2,327,000.00
2024	JAX	TW C	1480	PCC	24,260	63	PCC Restoration	\$ 413,000.00
2024	JAX	TW J	755	PCC	13,125	63	PCC Restoration	\$ 224,000.00
2025	JAX	TW C	1490	PCC	50,660	63	PCC Restoration	\$ 862,000.00
2026	JAX	TW L	215	PCC	18,195	64	PCC Restoration	\$ 310,000.00
2027	JAX	TW A	105	PCC	54,448	64	PCC Restoration	\$ 926,000.00
2027	JAX	TW E	1670	PCC	29,143	63	PCC Restoration	\$ 496,000.00
2027	JAX	TW G	1020	PCC	29,478	63	PCC Restoration	\$ 502,000.00
2027	JAX	TW L	205	PCC	25,258	63	PCC Restoration	\$ 430,000.00
2027	JAX	TW S	1290	PCC	28,370	63	PCC Restoration	\$ 483,000.00
2028	JAX	AP TERM	4445	PCC	312,670	63	PCC Restoration	\$ 5,316,000.00
2028	JAX	TW A	120	PCC	271,875	64	PCC Restoration	\$ 4,622,000.00
2028	JAX	TW E	1680	PCC	59,400	64	PCC Restoration	\$ 1,010,000.00
2028	JAX	TW H	557	PCC	38,685	64	PCC Restoration	\$ 658,000.00
2029	JAX	TW A	110	PCC	168,750	63	PCC Restoration	\$ 2,869,000.00
2029	JAX	TW B	810	PCC	136,875	63	PCC Restoration	\$ 2,327,000.00
2029	JAX	TW L	225	PCC	52,307	63	PCC Restoration	\$ 890,000.00
2029	JAX	TW S	1285	PCC	140,346	63	PCC Restoration	\$ 2,386,000.00

\*All values have been rounded to the nearest thousand-dollar.





The following Figure 6.3.1 (a) summarizes the section-level major rehabilitation needs for a 10year period between 2020 and 2029. Figure 6.3.1 (b) provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in Appendix C **Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.


Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year







Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit





# **Chapter 7**





# **Chapter 7 – Conclusion**

#### 7.1 Recommendations

#### 7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and reinspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

## 7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2020-2029. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

# 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- Develop a detailed preventive maintenance program for the airport.
- Further refine and implement the identified 10-year major rehabilitation needs.
- Maintain detailed records on pavement maintenance, construction, and inspection.
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).





# 7.2 Supporting Documents

#### 001 - Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in Appendix A **Pavement Analysis Tables.** 

### 002 - Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit in is located in Appendix C Technical Exhibits. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

#### 003 - Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in Appendix C Technical Exhibits. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in Appendix E Inspection Distress Details) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

## 004 - Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation.

## Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in Appendix D Inspection Photograph Documentation. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.

**Statewide Airfield Pavement Management Program** 

**Airport Pavement Evaluation Report**  2019

Jacksonville International Airport (JAX)






#### 7.3 Conclusion

The FDOT SAPMP Update Phase 2 2018-2019 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars 150/5380-7B "Airport Pavement Management Program (PMP)" and 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements." FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."



# Appendix A

Airfield Pavement Analysis Tables







#### Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4105	695	426	296,070	PCC	1/1/1989
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4110	260	104	27,040	AC	1/1/1994
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4118	429	425	198,059	PCC	1/1/2000
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4120	413	515	212,550	PCC	1/1/1981
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4125	413	200	84,968	PCC	1/1/1968
JAX	CARGO AND AIR CARGO APRONS	AP CARGO	APRON	4135	265	120	32,378	PCC	5/1/2007
JAX	GA APRON	AP GA	APRON	4205	282	270	76,140	AC	1/1/2016
JAX	GA APRON	AP GA	APRON	5105	420	225	127,653	AC	1/1/2006
JAX	GA APRON	AP GA	APRON	5110	925	280	239,174	AC	1/1/2006
JAX	GA APRON	AP GA	APRON	5115	165	170	28,389	AC	1/1/2006
JAX	HOLDING APRON BETWEEN RWS 4, 13	AP HOLD	APRON	4405	533	281	150,030	PCC	1/1/1992
JAX	TERMINAL APRON	AP TERM	APRON	4305	210	180	36,141	PCC	1/1/1985
JAX	TERMINAL APRON	AP TERM	APRON	4310	580	250	144,838	PCC	1/1/1985
JAX	TERMINAL APRON	AP TERM	APRON	4315	570	250	146,950	PCC	1/1/1985
JAX	TERMINAL APRON	AP TERM	APRON	4410	642	150	95,567	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4412	125	105	24,650	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4415	360	285	101,704	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4420	660	310	195,814	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4425	1,020	630	643,219	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4430	820	440	361,365	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4435	1,040	600	625,548	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4440	810	150	121,630	PCC	12/11/2007
JAX	TERMINAL APRON	AP TERM	APRON	4445	875	355	312,670	PCC	1/1/1991
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6205	500	50	25,000	PCC	1/1/1996
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6207	1,000	50	50,000	PCC	1/1/1996
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6210	6,600	50	330,000	PCC	1/1/2000
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6215	13,200	50	622,500	PCC	1/1/2000
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6220	600	50	30,000	PCC	1/1/1996
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6225	1,200	50	60,000	PCC	1/1/1996
JAX	RUNWAY 14-32	RW 14-32	RUNWAY	6230	750	50	37,500	PCC	1/1/1996
JAX	RUNWAY 8-26	RW 8-26	RUNWAY	6105	10,000	100	1,000,000	PCC	1/1/1994
JAX	RUNWAY 8-26	RW 8-26	RUNWAY	6110	20,000	25	500,000	PCC	1/1/1994
JAX	TAXIWAY A	TW A	TAXIWAY	105	875	75	54,448	PCC	1/1/1983
JAX	TAXIWAY A	TW A	TAXIWAY	110	2,100	75	168,750	PCC	1/1/1989
JAX	TAXIWAY A	TW A	TAXIWAY	115	1,575	75	118,125	PCC	1/1/2000





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
JAX	TAXIWAY A	TW A	TAXIWAY	120	3,670	75	271,875	PCC	1/1/1985
JAX	TAXIWAY A	TW A	TAXIWAY	125	1,780	75	136,875	PCC	1/1/1994
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	910	1,245	108	134,973	AC	1/1/2006
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	915	190	70	8,630	AC	1/1/2016
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	920	210	90	23,852	AC	1/1/2016
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2715	160	45	8,530	AC	1/1/1994
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2720	180	50	10,052	AAC	1/1/2017
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2772	450	50	33,940	PCC	1/1/1981
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2774	450	75	50,906	PCC	1/1/1981
JAX	TAXIWAYS WITHIN APRONS	TW AP	TAXIWAY	2775	450	75	38,593	PCC	1/1/1968
JAX	TAXIWAY B	TW B	TAXIWAY	805	3,275	75	253,320	PCC	1/1/1985
JAX	TAXIWAY B	TW B	TAXIWAY	810	1,825	75	136,875	PCC	1/1/1994
JAX	TAXIWAY C	TW C	TAXIWAY	1480	176	90	24,260	PCC	1/1/1994
JAX	TAXIWAY C	TW C	TAXIWAY	1490	488	90	50,660	PCC	1/1/1994
JAX	TAXIWAY E	TW E	TAXIWAY	1670	176	90	29,143	PCC	1/1/1994
JAX	TAXIWAY E	TW E	TAXIWAY	1680	488	90	59,400	PCC	1/1/1985
JAX	TAXIWAY F	TW F	TAXIWAY	1145	176	94	30,320	PCC	1/1/1985
JAX	TAXIWAY F	TW F	TAXIWAY	1150	125	75	18,725	PCC	1/1/1985
JAX	TAXIWAY F	TW F	TAXIWAY	1155	1,320	75	98,961	AC	1/1/1968
JAX	TAXIWAY F	TW F	TAXIWAY	1170	222	90	27,436	PCC	1/1/1994
JAX	TAXIWAY F	TW F	TAXIWAY	1175	266	90	39,074	PCC	1/1/1985
JAX	TAXIWAY G	TW G	TAXIWAY	1020	176	90	29,478	PCC	1/1/1985
JAX	TAXIWAY G	TW G	TAXIWAY	1025	125	75	19,138	PCC	1/1/1985
JAX	TAXIWAY G	TW G	TAXIWAY	1030	700	50	35,019	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1032	870	50	44,449	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1035	190	35	7,929	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1040	150	60	14,096	AC	1/1/2016
JAX	TAXIWAY G	TW G	TAXIWAY	1045	223	60	14,480	AAC	1/1/2001
JAX	TAXIWAY G	TW G	TAXIWAY	1060	515	150	133,822	PCC	1/1/1994
JAX	TAXIWAY H	TW H	TAXIWAY	550	488	160	208,460	PCC	1/1/1994
JAX	TAXIWAY H	TW H	TAXIWAY	555	1,540	75	127,293	PCC	1/1/1985
JAX	TAXIWAY H	TW H	TAXIWAY	557	615	60	38,685	PCC	1/1/2007
JAX	TAXIWAY J	TW J	TAXIWAY	740	550	150	136,242	PCC	1/1/1994
JAX	TAXIWAY J	TW J	TAXIWAY	745	1,760	75	94,986	PCC	1/1/1989
JAX	TAXIWAY J	TW J	TAXIWAY	750	265	75	21,670	PCC	1/1/1982
JAX	TAXIWAY J	TW J	TAXIWAY	755	175	75	13,125	PCC	1/1/1968

**Statewide Airfield Pavement Management Program**Airport Pavement Evaluation Report

2019





Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
JAX	TAXIWAY J	TW J	TAXIWAY	760	290	75	21,750	PCC	1/1/1984
JAX	TAXIWAY J	TW J	TAXIWAY	765	1,020	110	123,159	PCC	1/1/2013
JAX	TAXIWAY K	TW K	TAXIWAY	1320	795	92	107,334	PCC	1/1/1992
JAX	TAXIWAY L	TW L	TAXIWAY	205	244	90	25,258	PCC	1/1/1994
JAX	TAXIWAY L	TW L	TAXIWAY	210	244	90	28,620	PCC	1/1/1983
JAX	TAXIWAY L	TW L	TAXIWAY	215	206	90	18,195	PCC	1/1/1983
JAX	TAXIWAY L	TW L	TAXIWAY	220	240	90	25,304	PCC	1/1/1992
JAX	TAXIWAY L	TW L	TAXIWAY	225	488	90	52,307	PCC	1/1/1992
JAX	TAXIWAY N	TW N	TAXIWAY	305	2,950	75	221,250	PCC	1/1/1992
JAX	TAXIWAY N	TW N	TAXIWAY	310	2,451	75	180,075	PCC	1/1/1998
JAX	TAXIWAY N	TW N	TAXIWAY	312	1,775	75	131,250	PCC	1/1/2000
JAX	TAXIWAY N	TW N	TAXIWAY	315	525	75	45,000	PCC	1/1/1996
JAX	TAXIWAY P	TW P	TAXIWAY	640	811	75	60,825	PCC	1/1/1982
JAX	TAXIWAY P	TW P	TAXIWAY	641	250	75	8,909	PCC	1/1/1994
JAX	TAXIWAY P	TW P	TAXIWAY	650	550	140	133,322	PCC	1/1/1992
JAX	TAXIWAY P	TW P	TAXIWAY	655	1,500	75	79,579	PCC	1/1/1992
JAX	TAXIWAY P	TW P	TAXIWAY	660	1,050	100	126,658	PCC	1/1/2013
JAX	TAXIWAY Q	TW Q	TAXIWAY	560	690	90	115,700	PCC	1/1/1996
JAX	TAXIWAY R	TW R	TAXIWAY	570	380	90	43,767	PCC	1/1/1996
JAX	TAXIWAY R	TW R	TAXIWAY	575	1,210	75	111,623	PCC	1/1/1996
JAX	TAXIWAY R	TW R	TAXIWAY	576	240	115	29,713	PCC	1/1/1991
JAX	TAXIWAY S	TW S	TAXIWAY	1285	1,385	75	140,346	PCC	1/1/1989
JAX	TAXIWAY S	TW S	TAXIWAY	1290	220	100	28,370	PCC	1/1/1989
JAX	TAXIWAY T	TW T	TAXIWAY	1282	487	148	59,457	PCC	1/1/2012
JAX	TAXIWAY U	TW U	TAXIWAY	390	488	90	52,557	PCC	1/1/1998
JAX	TAXIWAY V	TW V	TAXIWAY	905	785	100	78,127	PCC	1/1/2013





Table A-2 Pavement Condition Index Summary (Last Inspection) - Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
JAX	RUNWAY 8-26	RUNWAY	6105	1,000,000	89	Good
JAX	RUNWAY 8-26	RUNWAY	6110	500,000	83	Satisfactory
JAX	RUNWAY 14-32	RUNWAY	6205	25,000	82	Satisfactory
JAX	RUNWAY 14-32	RUNWAY	6207	50,000	87	Good
JAX	RUNWAY 14-32	RUNWAY	6210	330,000	92	Good
JAX	RUNWAY 14-32	RUNWAY	6215	622,500	93	Good
JAX	RUNWAY 14-32	RUNWAY	6220	30,000	89	Good
JAX	RUNWAY 14-32	RUNWAY	6225	60,000	94	Good
JAX	RUNWAY 14-32	RUNWAY	6230	37,500	90	Good
JAX	TAXIWAY A	TAXIWAY	105	54,448	79	Satisfactory
JAX	TAXIWAY A	TAXIWAY	110	168,750	81	Satisfactory
JAX	TAXIWAY A	TAXIWAY	115	118,125	84	Satisfactory
JAX	TAXIWAY A	TAXIWAY	120	271,875	80	Satisfactory
JAX	TAXIWAY A	TAXIWAY	125	136,875	74	Satisfactory
JAX	TAXIWAY B	TAXIWAY	805	253,320	82	Satisfactory
JAX	TAXIWAY B	TAXIWAY	810	136,875	81	Satisfactory
JAX	TAXIWAY C	TAXIWAY	1480	24,260	73	Satisfactory
JAX	TAXIWAY C	TAXIWAY	1490	50,660	75	Satisfactory
JAX	TAXIWAY E	TAXIWAY	1670	29,143	78	Satisfactory
JAX	TAXIWAY E	TAXIWAY	1680	59,400	80	Satisfactory
JAX	TAXIWAY F	TAXIWAY	1145	30,320	90	Good
JAX	TAXIWAY F	TAXIWAY	1150	18,725	86	Good
JAX	TAXIWAY F	TAXIWAY	1155	98,961	30	Very Poor
JAX	TAXIWAY F	TAXIWAY	1170	27,436	82	Satisfactory
JAX	TAXIWAY F	TAXIWAY	1175	39,074	93	Good
JAX	TAXIWAY G	TAXIWAY	1020	29,478	78	Satisfactory
JAX	TAXIWAY G	TAXIWAY	1025	19,138	85	Satisfactory
JAX	TAXIWAY G	TAXIWAY	1030	35,019	89	Good
JAX	TAXIWAY G	TAXIWAY	1032	44,449	94	Good
JAX	TAXIWAY G	TAXIWAY	1035	7,929	92	Good
JAX	TAXIWAY G	TAXIWAY	1040	14,096	89	Good
JAX	TAXIWAY G	TAXIWAY	1045	14,480	53	Poor
JAX	TAXIWAY G	TAXIWAY	1060	133,822	91	Good
JAX	TAXIWAY H	TAXIWAY	550	208,460	88	Good
JAX	TAXIWAY H	TAXIWAY	555	127,293	70	Fair
JAX	TAXIWAY H	TAXIWAY	557	38,685	80	Satisfactory
JAX	TAXIWAY J	TAXIWAY	740	136,242	87	Good

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019





Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
JAX	TAXIWAY J	TAXIWAY	745	94,986	82	Satisfactory
JAX	TAXIWAY J	TAXIWAY	750	21,670	69	Fair
JAX	TAXIWAY J	TAXIWAY	755	13,125	73	Satisfactory
JAX	TAXIWAY J	TAXIWAY	760	21,750	70	Fair
JAX	TAXIWAY J	TAXIWAY	765	123,159	97	Good
JAX	TAXIWAY K	TAXIWAY	1320	107,334	85	Satisfactory
JAX	TAXIWAY L	TAXIWAY	205	25,258	78	Satisfactory
JAX	TAXIWAY L	TAXIWAY	210	28,620	84	Satisfactory
JAX	TAXIWAY L	TAXIWAY	215	18,195	77	Satisfactory
JAX	TAXIWAY L	TAXIWAY	220	25,304	83	Satisfactory
JAX	TAXIWAY L	TAXIWAY	225	52,307	81	Satisfactory
JAX	TAXIWAY N	TAXIWAY	305	221,250	87	Good
JAX	TAXIWAY N	TAXIWAY	310	180,075	90	Good
JAX	TAXIWAY N	TAXIWAY	312	131,250	89	Good
JAX	TAXIWAY N	TAXIWAY	315	45,000	93	Good
JAX	TAXIWAY P	TAXIWAY	640	60,825	70	Fair
JAX	TAXIWAY P	TAXIWAY	641	8,909	87	Good
JAX	TAXIWAY P	TAXIWAY	650	133,322	96	Good
JAX	TAXIWAY P	TAXIWAY	655	79,579	94	Good
JAX	TAXIWAY P	TAXIWAY	660	126,658	99	Good
JAX	TAXIWAY Q	TAXIWAY	560	115,700	85	Satisfactory
JAX	TAXIWAY R	TAXIWAY	570	43,767	86	Good
JAX	TAXIWAY R	TAXIWAY	575	111,623	88	Good
JAX	TAXIWAY R	TAXIWAY	576	29,713	86	Good
JAX	TAXIWAY S	TAXIWAY	1285	140,346	81	Satisfactory
JAX	TAXIWAY S	TAXIWAY	1290	28,370	78	Satisfactory
JAX	TAXIWAY T	TAXIWAY	1282	59,457	97	Good
JAX	TAXIWAY U	TAXIWAY	390	52,557	91	Good
JAX	TAXIWAY V	TAXIWAY	905	78,127	100	Good
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	910	134,973	67	Fair
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	915	8,630	89	Good
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	920	23,852	86	Good
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2715	8,530	31	Very Poor
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2720	10,052	83	Satisfactory
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2772	33,940	67	Fair
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2774	50,906	82	Satisfactory
JAX	TAXIWAYS WITHIN APRONS	TAXIWAY	2775	38,593	48	Poor
JAX	CARGO AND AIR CARGO APRONS	APRON	4105	296,070	83	Satisfactory
JAX	CARGO AND AIR CARGO APRONS	APRON	4110	27,040	33	Very Poor

Statewide Airfield Pavement Management Program Airport Pavement Evaluation Report

2019





Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating	
JAX	CARGO AND AIR CARGO APRONS	APRON	4118	198,059	88	Good	
JAX	CARGO AND AIR CARGO APRONS	APRON	4120	212,550	78	Satisfactory	
JAX	CARGO AND AIR CARGO APRONS	APRON	4125	84,968	48	Poor	
JAX	CARGO AND AIR CARGO APRONS	APRON	4135	4135 32,378		Fair	
JAX	GA APRON	APRON	4205	76,140	89	Good	
JAX	TERMINAL APRON	APRON	4305	36,141	79	Satisfactory	
JAX	TERMINAL APRON	APRON	4310	144,838	79	Satisfactory	
JAX	TERMINAL APRON	APRON	4315	146,950	86	Good	
JAX	HOLDING APRON BETWEEN RWS 4, 13	APRON	4405	150,030	85	Satisfactory	
JAX	TERMINAL APRON	APRON	4410	95,567	95	Good	
JAX	TERMINAL APRON	APRON	4412	24,650	97	Good	
JAX	TERMINAL APRON	APRON	4415	101,704	99	Good	
JAX	TERMINAL APRON	APRON	4420	195,814	94	Good	
JAX	TERMINAL APRON	APRON	4425	643,219	93	Good	
JAX	TERMINAL APRON	APRON	4430	361,365	68	Fair	
JAX	TERMINAL APRON	APRON	4435	625,548	88	Good	
JAX	TERMINAL APRON	APRON	4440	121,630	97	Good	
JAX	TERMINAL APRON	APRON	4445	312,670	76	Satisfactory	
JAX	GA APRON	APRON	5105	127,653	49	Poor	
JAX	GA APRON	APRON	5110	239,174	68	Fair	
JAX	GA APRON	APRON	5115	28,389	62	Fair	





#### Table A-3 Forecasted PCI 2020-2029

Network		Section	Last	Forecasted PCI									
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	AP CARGO	4105	83	82	81	80	80	79	78	77	76	74	73
JAX	AP CARGO	4110	33	31	30	28	27	25	24	22	20	19	17
JAX	AP CARGO	4118	88	87	86	85	85	84	83	83	82	81	80
JAX	AP CARGO	4120	78	77	76	75	73	72	71	69	68	66	65
JAX	AP CARGO	4125	48	46	44	43	41	39	37	36	34	33	31
JAX	AP CARGO	4135	61	59	58	56	54	52	50	48	47	45	43
JAX	AP GA	4205	89	87	86	84	83	81	80	78	76	75	73
JAX	AP GA	5105	49	47	46	44	43	41	40	38	36	35	33
JAX	AP GA	5110	68	66	65	63	62	60	59	57	55	54	52
JAX	AP GA	5115	62	60	59	57	56	54	53	51	49	48	46
JAX	AP HOLD	4405	85	84	83	83	82	81	80	79	78	77	76
JAX	AP TERM	4305	79	78	77	76	75	73	72	71	69	68	66
JAX	AP TERM	4310	79	78	77	76	75	73	72	71	69	68	66
JAX	AP TERM	4315	86	85	84	84	83	82	81	81	80	79	78
JAX	AP TERM	4410	95	93	92	91	89	88	87	87	86	85	84
JAX	AP TERM	4412	97	95	93	92	91	89	88	87	87	86	85
JAX	AP TERM	4415	99	97	95	93	92	91	89	88	87	87	86
JAX	AP TERM	4420	94	92	91	90	89	88	87	86	85	85	84
JAX	AP TERM	4425	93	92	90	89	88	87	86	86	85	84	83
JAX	AP TERM	4430	68	66	65	63	61	60	58	56	54	53	51
JAX	AP TERM	4435	88	87	86	85	85	84	83	83	82	81	80
JAX	AP TERM	4440	97	95	93	92	91	89	88	87	87	86	85
JAX	AP TERM	4445	76	75	73	72	71	69	68	66	65	63	61
JAX	RW 14-32	6205	82	81	79	78	76	75	73	71	69	67	65
JAX	RW 14-32	6207	87	86	85	84	83	82	81	80	79	77	76
JAX	RW 14-32	6210	92	91	91	91	90	90	90	90	90	89	89
JAX	RW 14-32	6215	93	92	92	91	91	90	90	90	90	90	90
JAX	RW 14-32	6220	89	88	88	87	87	86	85	85	84	83	81
JAX	RW 14-32	6225	94	93	92	92	91	91	91	90	90	90	90
JAX	RW 14-32	6230	90	89	89	89	89	88	88	87	87	86	86
JAX	RW 8-26	6105	89	88	88	87	87	86	85	85	84	83	81
JAX	RW 8-26	6110	83	82	81	79	78	76	75	73	71	69	67
JAX	TW A	105	79	78	76	74	73	71	69	67	64	62	60
JAX	TW A	110	81	80	78	77	75	73	72	70	68	65	63
JAX	TW A	115	84	83	82	80	79	78	76	74	73	71	69
JAX	TW A	120	80	79	77	75	74	72	70	68	66	64	62
JAX	TW A	125	74	72	70	68	66	64	62	60	57	55	52





Network		Section	Last					Forecas	sted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	TW AP	910	67	66	65	64	64	63	62	61	61	60	59
JAX	TW AP	915	89	87	85	84	82	80	79	77	76	75	73
JAX	TW AP	920	86	84	83	81	79	78	77	75	74	73	71
JAX	TW AP	2715	31	28	25	21	18	14	10	6	3	0	0
JAX	TW AP	2720	83	81	80	78	77	76	74	73	72	71	70
JAX	TW AP	2772	67	65	63	61	58	56	53	51	48	46	43
JAX	TW AP	2774	82	81	79	78	76	75	73	71	69	67	65
JAX	TW AP	2775	48	46	43	41	38	35	33	30	28	26	24
JAX	TW B	805	82	81	79	78	76	75	73	71	69	67	65
JAX	TW B	810	81	80	78	77	75	73	72	70	68	65	63
JAX	TW C	1480	73	71	69	67	65	63	61	58	56	53	51
JAX	TW C	1490	75	73	71	70	68	65	63	61	59	56	54
JAX	TW E	1670	78	76	75	73	71	69	67	65	63	61	58
JAX	TW E	1680	80	79	77	75	74	72	70	68	66	64	62
JAX	TW F	1145	90	89	89	89	89	88	88	87	87	86	86
JAX	TW F	1150	86	85	84	83	82	81	79	78	77	75	73
JAX	TW F	1155	30	27	24	20	16	13	9	5	2	0	0
JAX	TW F	1170	82	81	79	78	76	75	73	71	69	67	65
JAX	TW F	1175	93	92	92	91	91	90	90	90	90	90	90
JAX	TW G	1020	78	76	75	73	71	69	67	65	63	61	58
JAX	TW G	1025	85	84	83	82	81	79	78	76	75	73	71
JAX	TW G	1030	89	87	85	84	82	80	79	77	76	75	73
JAX	TW G	1032	94	92	90	88	86	85	83	81	80	78	77
JAX	TW G	1035	92	90	88	86	85	83	81	80	78	77	75
JAX	TW G	1040	89	87	85	84	82	80	79	77	76	75	73
JAX	TW G	1045	53	52	52	51	50	49	49	48	47	46	44
JAX	TW G	1060	91	90	90	90	90	90	89	89	89	89	89
JAX	TW H	550	88	87	87	86	85	84	83	82	81	80	78
JAX	TW H	555	70	68	66	64	62	59	57	54	52	49	47
JAX	TW H	557	80	79	77	75	74	72	70	68	66	64	62
JAX	TW J	740	87	86	85	84	83	82	81	80	79	77	76
JAX	TW J	745	82	81	79	78	76	75	73	71	69	67	65
JAX	TW J	750	69	67	65	63	60	58	56	53	51	48	46
JAX	TW J	755	73	71	69	67	65	63	61	58	56	53	51
JAX	TW J	760	70	68	66	64	62	59	57	54	52	49	47
JAX	TW J	765	97	96	94	94	93	92	92	91	91	90	90
JAX	TW K	1320	85	84	83	82	81	79	78	76	75	73	71
JAX	TW L	205	78	76	75	73	71	69	67	65	63	61	58

2019





Network		Section	Last					Forecas	ted PCI				
ID	Branch ID	ID	PCI	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
JAX	TW L	210	84	83	82	80	79	78	76	74	73	71	69
JAX	TW L	215	77	75	74	72	70	68	66	64	61	59	57
JAX	TW L	220	83	82	81	79	78	76	75	73	71	69	67
JAX	TW L	225	81	80	78	77	75	73	72	70	68	65	63
JAX	TW N	305	87	86	85	84	83	82	81	80	79	77	76
JAX	TW N	310	90	89	89	89	89	88	88	87	87	86	86
JAX	TW N	312	89	88	88	87	87	86	85	85	84	83	81
JAX	TW N	315	93	92	92	91	91	90	90	90	90	90	90
JAX	TW P	640	70	68	66	64	62	59	57	54	52	49	47
JAX	TW P	641	87	86	85	84	83	82	81	80	79	77	76
JAX	TW P	650	96	95	94	93	92	92	91	91	91	90	90
JAX	TW P	655	94	93	92	92	91	91	91	90	90	90	90
JAX	TW P	660	99	97	96	95	94	93	92	92	91	91	91
JAX	TW Q	560	85	84	83	82	81	79	78	76	75	73	71
JAX	TW R	570	86	85	84	83	82	81	79	78	77	75	73
JAX	TW R	575	88	87	87	86	85	84	83	82	81	80	78
JAX	TW R	576	86	85	84	83	82	81	79	78	77	75	73
JAX	TW S	1285	81	80	78	77	75	73	72	70	68	65	63
JAX	TW S	1290	78	76	75	73	71	69	67	65	63	61	58
JAX	TW T	1282	97	96	94	94	93	92	92	91	91	90	90
JAX	TW U	390	91	90	90	90	90	90	89	89	89	89	89
JAX	TW V	905	100	98	97	95	94	93	93	92	91	91	91

10/3/2019	
-----------	--

Page 1 of 16

Pavement Database: FDOT

	Network: JACKSONVILLE IN			Branch: AP CA	RGO CARG	O AND AI	Section:	4105 Surface:PCC
l	<b>L.C.D.</b> 1/1/1989 <b>Use:</b> APRON			Rank: P L	ength: 695	.00 (Ft) Wi	dth: 426.0	0 (Ft) <b>True Area:</b> 296070.0000 (SqFt
	Work Date	Work Code	Work 1	Description	Cost	Thickness (in)	Major M&R	Comments
	1/1/1989	IMPORT ED	BUILT		0.00	16.00	<b>V</b>	1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A

Network: JACKSONVILLE IN		Branch: AP CARGO CA		RGO AND AI Section:		4110 Surface:AC	
<b>L.C.D.</b> 1/1/1	994 Us	se: APRON	Rank: P L	ength: 260	.00 (Ft) <b>Wi</b>	dth: 104.0	0 (Ft) <b>True Area:</b> 27040.00000 (SqFt
Work Date	Work Code	Work 1	Description	Cost	Thickness (in)	Major M&R	Comments

l	Network: JACKSONVILLE IN		IVILLE IN	Branch: AP CA	RGO CARG	O AND AI	Section:	4118 Surface:PCC
l	<b>L.C.D.</b> 1/1/20	000 Us	se: APRON	Rank: P I	ength: 429	.00 (Ft) Wi	dth: 425.0	00 (Ft) <b>True Area:</b> 198059.0000 (Sq
	Work Date	Work Code	Work l	Description	Cost	Thickness (in)	Major M&R	Comments

Network:	JACKSON	VILLE IN	Branch: AP CA	RGO CA	RGO AND .	Al Se	ection: 4	-120 Surface:PCC
<b>L.C.D.</b> 1/1/19	981 Us	se: APRON	Rank: P L	ength:	413.00 (Ft)	Width:	515.00	(Ft) <b>True Area:</b> 212550.0000 (SqFt
Work Date	Work Code	Work	Description	Cost	Thickn (in)		lajor I&R	Comments
1/1/1981	IMPORT ED	BUILT		0	.00	6.00		1981: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A

Network:	Network: JACKSONVILLE IN		Branch: AP CARGO		CARG	RGO AND AI		Section:	4125	25 Surface:PCC	
<b>L.C.D.</b> 1/1/1	968 Us	se: APRON	Rank: P	Length:	413	.00 (Ft)	Widtl	h: 200.0	0 (Ft) True A	Area: 84968.00002 (SqFt	
Work Date	Work Code	Work	Description	Co	ost	Thickne (in)		Major M&R		Comments	
1/1/1968	IMPORT ED	BUILT			0.00	13	.00	<b>V</b>	1968: 13" PC SUBBASE	C ON 6" STABILIZED	

Network: JACKSONVILLE IN		IVILLE IN	Branch: AP CA	RGO CARG	O AND AI	Section:	4135	Surface:PCC
<b>L.C.D.</b> 5/1/20	007 Us	se: APRON	Rank: P L	ength: 265	.00 (Ft) Wi	dth: 120.0	0 (Ft) True A	rea: 32378.00000 (SqFt
Work Date	Work Code	Work 1	Description	Cost	Thickness (in)	Major M&R	C	Comments
5/1/2007	NU-IN	New Construc	ction - Initial	0.00	0.00	<b>Y</b>		

ı	Network:	Network: JACKSONVILLE IN		Branch: AP GA	GA AI	PRON	Section:	4205 Surface:AC
	<b>L.C.D.</b> 1/1/2016 <b>Use:</b> APRON		e: APRON	Rank: P L	ength: 282	.00 (Ft) <b>Wi</b>	dth: 270.0	0 (Ft) <b>True Area:</b> 76140.00002 (SqFt
	Work Date	Work Code	Work l	Description	Cost	Thickness (in)	Major M&R	Comments
	1/1/2016	CR-AC	Complete Rec	onstruction - AC	0.00	0.00	<b>V</b>	Full depth mill, base course rehabilitat
	1/1/1968	IMPORT ED	BUILT		0.00	1.00		1968: 1" P-401 ON 7.5" P-211
		LD						

Page 2 of 16

Pavement Database: FDOT

		Pave	ment Databas	e: FDOT			
Network:	JACKSON	IVILLE IN	Branch: AP C	GA GAA	PRON	Section:	5105 Surface:AC
<b>L.C.D.</b> 1/1/20	006 Us	se: APRON	Rank: P	Length: 420	0.00 (Ft) Wi	idth: 225.0	0 (Ft) <b>True Area:</b> 127653.0000 (SqFt
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	NC-AC	New Constru	ction - AC	0.00	0.00	<b>&gt;</b>	
Network:		5110 Surface:AC					
<b>L.C.D.</b> 1/1/2		se: APRON	Rank: P	Length: 925	· ` ´		0 (Ft) True Area: 239174.0000 (SqFt
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	NC-AC	New Constru	ction - AC	0.00	0.00	>	
Network:		IVILLE IN	Branch: AP G		PRON 5.00 (Ft) Wi	Section:	5115 <b>Surface:</b> AC 0 (Ft) <b>True Area:</b> 28389.00000 (SqFt
Work Date	Work Code		Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	NC-AC	New Constru	ction - AC	0.00	0.00	<b>V</b>	
Network:			Branch: AP H		DING APRO	Section:	
<b>L.C.D.</b> 1/1/1		e: APRON	Rank: P	Length: 533	. ,	ı	0 (Ft) <b>True Area:</b> 150030.0000 (SqFt
Work Date	Work	Work	Description	Cost	Thickness	Major M&R	Comments
	Code IMPORT				(in)	Mak	

Network: L.C.D. 1/1/1		IVILLE IN se: APRON	Branch: AP TEI		INAL APR .00 (Ft) <b>Wi</b>	Section: dth: 180.0	4305 <b>Surface:</b> PCC 0 (Ft) <b>True Area:</b> 36141.00001 (SqFt
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1985	IMPORT ED	BUILT		0.00	16.00	<b>&gt;</b>	1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A

	JACKSON		Branch: AP TEI		IINAL APR	Section:		Surface:PCC
<b>L.C.D.</b> 1/1/2	1985 Us	se: APRON	Rank: P L	ength: 580	.00 (Ft) <b>Wi</b>	dth: 250.0	0 (Ft) True Area:	144838.0000 (SqFt
Work Date	Work Code	Work	Description	Cost	Thickness (in)	Major M&R	Com	ments
1/1/1985	IMPORT	BUILT		0.00	16.00	<b>V</b>	1985: 16" PCC ON	16"
	ED						ECONOCRETE O	N 6" CRUSHED A

l	Network: JACKSONVILLE IN		<b>Branch:</b> AP TERM T		MINAL APR	Section:	4315 Surface:PCC	
l	<b>L.C.D.</b> 1/1/1	985 Us	se: APRON	Rank: P	Length: 57	0.00 (Ft) <b>W</b> i	idth: 250.0	0 (Ft) <b>True Area:</b> 146950.0000 (SqFt
	Work Date	Work Code	Work	Work Description		Thickness (in)	Major M&R	Comments
	1/1/1985	IMPORT ED	BUILT		0.00	16.00	<b>V</b>	1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A

Pavement Database: FDOT

Network: JAC	Network: JACKSONVILLE IN Branch: AP TERM TERMINAL APR Section: 4410 Surface:PCC									
<b>L.C.D.</b> 12/11/200		e: APRON Rank:					(Ft) <b>True Area:</b> 95567.00002 (SqF			
Work Date	Vork	Work Descripti		Cost	Thickness	Major	Comments			
(	Code IC-PC	New Construction - PC		0.00	(in) 0.00	M&R	Comments			
12/11/2007 N	ic-PC	New Construction - PC		0.00	0.00					
Network: JAC	CKSON	VILLE IN <b>Branch</b>	: AP TE	RM TERM	IINAL APR	Section: 4	412 Surface:PCC			
<b>L.C.D.</b> 12/11/200	0 Use	e: APRON Rank:	P L	ength: 125	.00 (Ft) Wi	dth: 105.00	(Ft) <b>True Area:</b> 24650.00000 (SqF			
Work Date	Vork	Work Descripti	on	Cost	Thickness	Major	Comments			
(	Code IC-PC	New Construction - PC		0.00	(in) 0.00	M&R ✓	Comments			
12/11/2007	ic-i c	New Construction - 1 C		0.00	0.00					
Network: JAC	CKSON	VILLE IN Branch	: AP TE	RM TERM	IINAL APR	Section: 4	415 Surface:PCC			
<b>L.C.D.</b> 12/11/20	0 Use	e: APRON Rank:	P L	ength: 360	.00 (Ft) Wi	dth: 285.00	(Ft) <b>True Area:</b> 101704.0000 (SqF			
Work Date	Work	Work Descripti	on	Cost	Thickness	Major	Comments			
	Code IC-PC	New Construction - PC		0.00	(in) 0.00	M&R ✓				
12/11/2007	.510	2.0. Construction 1 C		0.00	0.00					
Network: JAC	CKSON	VILLE IN Branch	: AP TE	RM TERM	IINAL APR	Section: 4	420 Surface:PCC			
<b>L.C.D.</b> 12/11/20	0 Use	e: APRON Rank:	P L	ength: 660	.00 (Ft) <b>Wi</b>	dth: 310.00	(Ft) <b>True Area:</b> 195814.0000 (SqF			
Work Date	Work	Work Descripti	on	Cost	Thickness	Major M.e.D	Comments			
	Code IC-PC	New Construction - PC	C	0.00	(in) 0.00	M&R ✓				
	ı			0.00						
Network: JAC	CKSON		: AP TE	I	IINAL APR	Section: 4	425 Surface:PCC			
Network: JAC L.C.D. 12/11/200			: AP TE	I	IINAL APR					
L.C.D. 12/11/200	0 Use Work	VILLE IN Branch e: APRON Rank:	ı: AP TEI	RM TERM	IINAL APR .00 (Ft) Wi Thickness	Section: 4 dth: 630.00 Major				
L.C.D. 12/11/200 Work Date V	0 Use Work Code	VILLE IN Branch	: AP TEI P L	RM TERM ength: 1,020	IINAL APR .00 (Ft) <b>Wi</b>	Section: 4 dth: 630.00 Major M&R	(Ft) <b>True Area:</b> 643219.0001 (SqF			
L.C.D. 12/11/200 Work Date V	0 Use Work Code	VILLE IN Branch e: APRON Rank: Work Descripti	: AP TEI P L	RM TERM ength: 1,020 Cost	IINAL APR .00 (Ft) Wi Thickness (in)	Section: 4 dth: 630.00 Major	(Ft) <b>True Area:</b> 643219.0001 (SqF			
L.C.D. 12/11/200 Work Date V	O Use Work Code	VILLE IN Branch e: APRON Rank: Work Descripti New Construction - PC	: AP TEI P L	RM TERM ength: 1,020 Cost 0.00	IINAL APR .00 (Ft) Wi Thickness (in)	Section: 4 dth: 630.00 Major M&R	(Ft) True Area: 643219.0001 (SqF Comments			
<b>L.C.D.</b> 12/11/200  Work Date V (12/11/2007 N	Work Code C-PC	VILLE IN Branch e: APRON Rank: Work Descripti New Construction - PC	P L on C a: AP TE	RM TERM ength: 1,020 Cost 0.00  RM TERM	IINAL APR .00 (Ft) Wi Thickness (in) 0.00	Section: 4 dth: 630.00 Major M&R	(Ft) True Area: 643219.0001 (SqF  Comments  430 Surface: PCC			
L.C.D. 12/11/200  Work Date V (12/11/2007 N  Network: JAC L.C.D. 12/11/200  Work Date V	Work Code IC-PC CKSON 0 Use	VILLE IN Branch e: APRON Rank: Work Descripti New Construction - PC VILLE IN Branch	P L O O C C P L	RM TERM ength: 1,020 Cost 0.00  RM TERM	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness	Section: 4 dth: 630.00 Major M&R  Section: 4 dth: 440.00 Major	(Ft) True Area: 643219.0001 (SqF  Comments  430 Surface: PCC			
L.C.D. 12/11/200   Work Date   V   12/11/2007   N   Network: JAC   L.C.D. 12/11/200   Work Date   V	Work Code CKSON Use Work Code	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:	P L on P L on C P L	RM TERM ength: 1,020 Cost 0.00  RM TERM ength: 820	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi	Section: 4 dth: 630.00 Major M&R  Section: 4 dth: 440.00 Major M&R	(Ft) True Area: 643219.0001 (SqF  Comments  430 Surface:PCC (Ft) True Area: 361365.0001 (SqF			
L.C.D. 12/11/200   Work Date   V   12/11/2007   N   Network: JAC   L.C.D. 12/11/200   Work Date   V	Work Code CKSON Use Work Code	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti	P L on P L on C P L	RM TERM ength: 1,020 Cost 0.00  RM TERM ength: 820 Cost	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in)	Section: 4 dth: 630.00 Major M&R  Section: 4 dth: 440.00 Major	(Ft) True Area: 643219.0001 (SqF  Comments  430 Surface:PCC (Ft) True Area: 361365.0001 (SqF			
L.C.D. 12/11/200   Work Date   V   12/11/2007   N   Network: JAC   L.C.D. 12/11/200   Work Date   V	Work Code IC-PC Use Work Code IC-PC III-PC IC-PC III-PC IC-PC III-PC IC-PC III-PC III-P	VILLE IN Branch e: APRON Rank:  Work Descripti  New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti  New Construction - PC	P L on P L on C P L	RM TERM ength: 1,020 Cost 0.00  RM TERM ength: 820 Cost 0.00	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in)	Section: 4 dth: 630.00 Major M&R  Section: 4 dth: 440.00 Major M&R	(Ft) True Area: 643219.0001 (SqF			
L.C.D. 12/11/200  Work Date   V C C C C C C C C C C C C C C C C C C	Work Code CCKSON USO Work Code CCPC CCKSON	VILLE IN Branch e: APRON Rank:  Work Descripti  New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti  New Construction - PC	P L  on  C  P L  on  C  AP TEI  on	RM TERM ength: 1,020 Cost 0.00  RM TERM ength: 820 Cost 0.00	IINAL APR  .00 (Ft) Wi  Thickness (in)  0.00  IINAL APR  .00 (Ft) Wi  Thickness (in)  0.00	Section: 4 dth: 630.00 Major M&R Section: 4 dth: 440.00 Major M&R	(Ft) True Area: 643219.0001 (SqF			
L.C.D. 12/11/200  Work Date   V	Work Code CKSON Use CKSON	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC	P L  on  C  AP TE  P L  on  C  AP TE  P L  on	RM TERM ength: 1,020  Cost  0.00  RM TERM ength: 820  Cost  0.00  RM TERM	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness	Section: 4 dth: 630.00 Major M&R Section: 4 dth: 440.00 Major M&R Section: 4 dth: 600.00 Major	(Ft) True Area: 643219.0001 (SqF			
L.C.D. 12/11/200  Work Date   V	Work Code CKSON Use CKSON	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:	P L  on  C  :: AP TEI  P L  on  C  :: AP TEI  P L  on	RM TERM ength: 1,020 Cost 0.00  RM TERM ength: 820 Cost 0.00  RM TERM ength: 1,040	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR	Section: 4 dth: 630.00 Major M&R Section: 4 dth: 440.00 Major M&R Section: 4 dth: 600.00	(Ft) True Area: 643219.0001 (SqF  Comments  430 Surface:PCC (Ft) True Area: 361365.0001 (SqF  Comments  435 Surface:PCC (Ft) True Area: 625548.0001 (SqF			
L.C.D. 12/11/200  Work Date   V	Work Code CKSON Use CKSON	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti	P L  on  C  :: AP TEI  P L  on  C  :: AP TEI  P L  on	RM TERM ength: 1,020 Cost 0.00  RM TERM ength: 820 Cost 0.00  RM TERM ength: 1,040 Cost	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in)	Section: 4 dth: 630.00 Major M&R Section: 4 dth: 440.00 Major M&R Section: 4 dth: 600.00 Major M&R	(Ft) True Area: 643219.0001 (SqF  Comments  430 Surface:PCC (Ft) True Area: 361365.0001 (SqF  Comments  435 Surface:PCC (Ft) True Area: 625548.0001 (SqF			
L.C.D. 12/11/200  Work Date   V	Work Code CCKSON USC Work Code CCPC CCKSON USC Work Code CCPC CCKSON USC Work COde CCPC	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC	P L  on  C  :: AP TEI  P L  on  C  :: AP TEI  P L  on	RM TERM ength: 1,020  Cost  0.00  RM TERM ength: 820  Cost  0.00  RM TERM ength: 1,040  Cost  0.00	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in)	Section: 4 dth: 630.00 Major M&R Section: 4 dth: 440.00 Major M&R Section: 4 dth: 600.00 Major M&R	Comments			
L.C.D. 12/11/2007   Work Date   V C C   12/11/2007   N   Network: JAC   L.C.D. 12/11/2007   N   Network: JAC   L.C.D. 12/11/2007   N   Network: JAC   L.C.D. 12/11/2007   N   N   Network Date   V C C   12/11/2007   N   N   N   N   N   N   N   N   N	Work Code CKSON Use CKSON Use CKSON CCKSON CCCCSON CCCCCSON CCCCSON CCCCCSON CCCCCSON CCCCCSON CCCCCSON CCCCCSON CCCCCCCCCC	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC	P L  on  C  :: AP TEI  P L  on  C  :: AP TEI  c  c  :: AP TEI  c  c  c  :: AP TEI  c  c  c  c  c  c  c  c  c  c  c  c  c	RM TERM ength: 1,020  Cost  0.00  RM TERM ength: 820  Cost  0.00  RM TERM ength: 1,040  Cost  0.00  RM TERM	IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR .00 (Ft) Wi Thickness (in) 0.00 IINAL APR	Section: 4 dth: 630.00 Major M&R Section: 4 dth: 440.00 Major M&R Section: 4 dth: 600.00 Major M&R Section: 4	Comments			
L.C.D. 12/11/2007   North Date   V C C	Work Code CKSON USO Work Code CCKSON USO CKSON USO Work Code CCKSON USO Work COde USO Work COde USO Work COde USO Work	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC	P L  on  C  :: AP TEI  P L  on  C  :: AP TEI  P L  on  C  :: AP TEI  P L  on	RM TERM ength: 1,020  Cost  0.00  RM TERM ength: 820  Cost  0.00  RM TERM ength: 1,040  Cost  0.00  Cost  0.00	IINAL APR .00 (Ft) Wi Thickness (in) 0.00  IINAL APR .00 (Ft) Wi Thickness (in) 0.00  IINAL APR .00 (Ft) Wi Thickness (in) 0.00	Section: 4 dth: 630.00 Major M&R  Section: 4 dth: 440.00 Major M&R  Section: 4 dth: 600.00 Major M&R  Section: 4 dth: 150.00 Major	Comments   Surface: PCC			
L.C.D. 12/11/2007   North Date   V C C	Work Code CKSON USO Work Code CCKSON USO CKSON USO Work Code USO Work Code USO Work Code USO Work Code	VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:  Work Descripti New Construction - PC  VILLE IN Branch e: APRON Rank:	P L  on  C  : AP TE  P L  on  C  : AP TE  P L  on  C  : AP TE  P L  on	RM TERM ength: 1,020  Cost  0.00  RM TERM ength: 820  Cost  0.00  RM TERM ength: 1,040  Cost  0.00  RM TERM ength: 1,040  Cost  0.00	IINAL APR .00 (Ft) Wi Thickness (in) 0.00  IINAL APR .00 (Ft) Wi Thickness (in) 0.00  IINAL APR .00 (Ft) Wi Thickness (in) 0.00	Section: 4 dth: 630.00 Major M&R  Section: 4 dth: 440.00 Major M&R  Section: 4 dth: 600.00 Major M&R  Section: 4 dth: 150.00	Comments			

Page 4 of 16

Pavement Database: FDOT

	Network: JACKSONVILLE IN			Branch: AP TE	RM TERM	INAL APR	Section:	4445 Surface:PCC
1	<b>L.C.D.</b> 1/1/1991 <b>Use:</b> APRON		Rank: P L	ength: 875	.00 (Ft) Wi	dth: 355.0	0 (Ft) <b>True Area:</b> 312670.0000 (SqFt	
	Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments
	1/1/1991	NC-PC	New Construc	ction - PCC	0.00	16.00	<b>V</b>	Original Construction of Previous Sect
	1/1/1983	NC-PC	New Construc	ction - PCC	0.00	16.00	<b>&gt;</b>	Original Construction of Previous Sect
	1/1/1979	NC-PC	New Construc	ction - PCC	0.00	16.00		Original Construction of Previous Sect

Network: JACKSONVILLE IN Branch: RW 14-32 **RUNWAY 14-32** Surface:PCC Section: 6205 L.C.D. 1/1/1996 Use: RUNWAY Rank: P 500.00 (Ft) Width: 50.00 (Ft) True Area: 25000.00000 (SqFt Length: Work Thickness Major **Work Date Work Description** Cost **Comments** Code M&R (in) 1/1/1996 IMPORT BUILT 0.00 16.00 1996: 16" P-501 ON 6" P-306 ON 6" ~ ED P-154

Network: JACKSONVILLE IN Branch: RW 14-32 **RUNWAY 14-32** Section: 6207 Surface:PCC L.C.D. 1/1/1996 Use: RUNWAY Rank: P **Length:** 1,000.00 (Ft) **Width:** 50.00 (Ft) True Area: 50000.00001 (SqFt Work Thickness Major Work Date **Work Description** Cost **Comments** Code M&R (in) 1/1/1996 IMPORT BUILT 1996: 16" P-501 ON 6" P-306 ON 6" 0.00 16.00 ~ ED P-154

Network: JACKSONVILLE IN Branch: RW 14-32 **RUNWAY 14-32** Section: 6210 Surface:PCC **L.C.D.** 1/1/2000 Use: RUNWAY Rank: P **Length:** 6,600.00 (Ft) **Width:** 50.00 (Ft) **True Area:** 330000.0001 (SqFt) Work Thickness Major Work Date **Work Description** Cost **Comments** Code M&R (in) 16" PCC/6" ECONOCONCR. BASE/ 1/1/2000 SR-PC Surface Reconstruction - PCC 0.00 0.00 1977: 16" PCC ON 6" 1/1/1977 IMPORT BUILT 0.0016.00 ~ ECONOCRETE ON 6" CRUSHED A

 Network:
 JACKSONVILLE IN
 Branch:
 RW 14-32
 RUNWAY 14-32
 Section:
 6215
 Surface:PCC

 L.C.D. 1/1/2000
 Use:
 RUNWAY
 Rank:
 P
 Length:
 13,200.00 (Ft)
 Width:
 50.00 (Ft)
 True Area:
 622500.0001 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	SR-PC	Surface Reconstruction - PCC	0.00	0.00	<b>V</b>	16" PCC/6" ECONOCONCR. BASE/
1/1/1968	IMPORT ED	BUILT	0.00	13.00		1968: 13" PCC ON 6" STABILIZED SUB-BASE

Network: JACKSONVILLE IN Branch: RW 14-32 **RUNWAY 14-32** Section: 6220 Surface:PCC **L.C.D.** 1/1/1996 Use: RUNWAY Rank: P Length: 600.00 (Ft) **Width:** 50.00 (Ft) True Area: 30000.00000 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments Code M&R (in) 1/1/1996 IMPORT BUILT 0.00 16.00 1996: 16" P-501 ON 6" P-306 ON 6" ~ P-154 ED

Network: JACKSONVILLE IN Branch: RW 14-32 **RUNWAY 14-32** Section: 6225 Surface:PCC **L.C.D.** 1/1/1996 Use: RUNWAY Rank: P **Length:** 1,200.00 (Ft) Width: 50.00 (Ft) True Area: 60000.00001 (SqFt Thickness Work Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/1996 IMPORT BUILT 0.00 16.00 1996: 16" P-501 ON 6" P-306 ON 6" ~ ED P-154

Page 5 of 16

Pavement Database: FDOT

Network: JACKSONVILLE IN Branch: RW 14-32 **RUNWAY 14-32** Section: 6230 Surface:PCC L.C.D. 1/1/1996 Use: RUNWAY Rank: P Length: 750.00 (Ft) Width: 50.00 (Ft) True Area: 37500.00001 (SqFt Work Thickness Major **Work Date** Work Description Cost **Comments** Code (in) M&R 1/1/1996 IMPORT BUILT 0.00 16.00 1996: 16" P-501 ON 6" P-306 ON 6" ~ ED

Network: JACKSONVILLE IN Branch: RW 8-26 RUNWAY 8-26 Section: 6105 Surface:PCC **L.C.D.** 1/1/1994 Length: 10,000.00 (Ft) Width: 100.00 (Ft) True Area: 1000000.000 (SqFt Use: RUNWAY Rank: P Work Thickness Major Work Date **Work Description** Cost **Comments** Code (in) M&R 1/1/1994 IMPORT BUILT 0.00 1994: 16" PCC ON 6" 16.00 ~ ECONOCRETE ON 6" CRUSHED A

Network: JACKSONVILLE IN Branch: RW 8-26 RUNWAY 8-26 Section: 6110 Surface:PCC 25.00 (Ft) True Area: 500000.0001 (SqFt L.C.D. 1/1/1994 Use: RUNWAY Rank: P **Length:** 20,000.00 (Ft) **Width:** Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/1994 IMPORT BUILT 1994: 16" PCC ON 6" 0.00 16.00 ED ECONOCRETE ON 6" CRUSHED A

Network: JACKSONVILLE IN Branch: TW A TAXIWAY A Section: 105 Surface:PCC L.C.D. 1/1/1983 Use: TAXIWAY Rank: P Length: 875.00 (Ft) Width: 75.00 (Ft) True Area: 54448.00001 (SqFt Thickness Work Major **Work Date Work Description** Cost **Comments** 

Work DateWork CodeWork DescriptionCostThickness (in)Major M&RComments1/1/1983IMPORT EDBUILT0.0016.00Image: 1983: 16" PCC ON 6" ECONOCRETE BASE ON 6" CRUS

Network: JACKSONVILLE IN Branch: TW A TAXIWAY A Section: 110 Surface: PCC L.C.D. 1/1/1989 Use: TAXIWAY Rank: P Length: 2,100.00 (Ft) Width: 75.00 (Ft) True Area: 168750.0000 (SqFt

Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R 1/1/1989 IMPORT BUILT 0.00 16.00 ~ 1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A ED

Network: JACKSONVILLE IN Branch: TW A TAXIWAY A Section: 115 Surface: PCC L.C.D. 1/1/2000 Use: TAXIWAY Rank: P Length: 1,575.00 (Ft) Width: 75.00 (Ft) True Area: 118125.0000 (SqFt

Work Thickness Major **Work Date Work Description** Cost **Comments** Code M&R (in) 1/1/2000 Surface Reconstruction - PCC SR-PC 0.00 0.00 16" PCC/6" ECONOCONCR. BASE/ ~ IMPORT BUILT 1/1/1999 0.00 0.00 ~ RECONSTRUCTION SCHEDULED IN 1999. NEW SECTION UNKNOW ED

Network: JACKSONVILLE IN Branch: TW A TAXIWAY A Section: 120 Surface: PCC L.C.D. 1/1/1985 Use: TAXIWAY Rank: P Length: 3,670.00 (Ft) Width: 75.00 (Ft) True Area: 271875.0000 (SqFt

Thickness Work Major Work Date **Work Description** Cost **Comments** M&R Code (in) 1/1/1985 IMPORT BUILT 0.00 16.00 1985: 16" PCC ON 6" ~ ECONOCRETE ON 6" CRUSHED A ED

Page 6 of 16

Pavement Database: FDOT

Ī	Network: JACKSONVILLE IN			Branch: TW A	TAXIV	WAY A	Section:	125 Surface:PCC
	<b>L.C.D.</b> 1/1/1994 <b>Use:</b> TAXIWA			Rank: P L	ength: 1,780	.00 (Ft) Wi	<b>dth:</b> 75.0	0 (Ft) <b>True Area:</b> 136875.0000 (SqFt
	Work Date   Work   Work		Work D	escription	Cost	Thickness (in)	Major M&R	Comments
	1/1/1994	IMPORT ED	BUILT		0.00	16.00	<b>&gt;</b>	1994: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A

	Network: JACKSONVILLE IN		<b>Branch:</b> TW AP TAXIV		XIWAYS	WAYS WIT Section: 2		2715 Surface:AC		
ı	<b>L.C.D.</b> 1/1/1	994 Us	se: TAXIWAY	Rank: P L	ength:	160.00 (Ft	) Wi	idth: 45.0	00 (Ft) <b>Tru</b>	e Area: 8530.000002 (SqFt
	Work Date	Work Date Work Code Work		escription	Cost	_	kness in)	Major M&R		Comments
	1/1/1994	IMPORT ED	BUILT		0	.00	3.00	<b>V</b>	1994: 3" P-	401 ON 11" P-211

Network: JACKSONVILLE IN			Branch: TW AP TAXIWAYS			Γ Se	ction:	2720	Surface: AAC
<b>L.C.D.</b> 1/1/2	017 Us	e: TAXIWAY	Rank: P L	ength: 18	0.00 (Ft)	Width:	50.0	0 (Ft) True Area:	10052.00000 (SqFt
Work Date   Work   Work		escription	Cost	Thicknes (in)		ajor &R	Comi	ments	
1/1/2017	ML-OV	MILL and OV	ERLAY	0.00	0.0	00	<u> </u>		
1/1/1992	IMPORT	BUILT		0.00	3.0	00	<b>/</b>	1992: 3" P-401 ON	11" P-211
	ED			ı					

Network:	Network: JACKSONVILLE IN			TAXI	WAYS WIT	Section:	2772 Surface:PCC		
<b>L.C.D.</b> 1/1/1	981 Us	se: TAXIWAY	Rank: P L	ength: 450	0.00 (Ft) <b>V</b>	<b>Vidth:</b> 50.0	0 (Ft) True Area:	33940.00001 (SqFt	
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Com	ments	
1/1/1981	IMPORT ED	BUILT		0.00	16.0		1981: 16" PCC ON	I 6" N 6" CRUSHED A	

l	Network: JACKSONVILLE IN			Branch: TW AP TAXI			WAYS WIT Section: 27			2774	2774 Surface:PCC		
l	<b>L.C.D.</b> 1/1/19	981 Us	se: TAXIWAY	Rank: P I	ength:	450	.00 (Ft)	Wid	lth: 75.0	00 (Ft)	True Area:	50906.00001 (SqFt	
	Work Date	Work Code	Work D	escription	Cos	t	Thicknotin)	ess	Major M&R		Comments		
	1/1/1981	IMPORT	BUILT			0.00	16	5.00	<b>V</b>	1981:	16" PCC ON	6"	

ı	Network: JACKSONVILLE IN			Branch: TW AF	TAXI	WAYS WIT	Section:	2775 Surface:PCC		
	<b>L.C.D.</b> 1/1/19	968 Us	se: TAXIWAY	Rank: P L	ength: 450	0.00 (Ft) <b>W</b> i	idth: 75.0	0 (Ft) True Area: 38	3593.00001 (SqFt	
	Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comme	nts	
	1/1/1968	IMPORT ED	BUILT		0.00	16.00	_ <u></u>	1968: 16" PCC ON 6" ECONOCRETE ON 6		

Network:	JACKSON	IVILLE IN	Branch: TW AP	TAXIV	WAYS WIT	Section: 9	910	Surface:AC
<b>L.C.D.</b> 1/1/2	006 Us	se: TAXIWAY	Rank: P L	ength: 1,245	.00 (Ft) Wi	dth: 108.00	(Ft) True Area:	134973.0000 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Com	ments
1/1/2006	NU-IN	New Construct	ion - Initial	0.00	0.00	>		

Page 7 of 16

Pavement Database: FDOT

I	Network:	JACKSON	IVILLE IN <b>Branch:</b> TW AF	TAXIV	WAYS WIT	Section:	915 Surface:AC
l	<b>L.C.D.</b> 1/1/20	016 Us	se: TAXIWAY Rank: P L	ength: 190	.00 (Ft) Wi	dth: 70.0	0 (Ft) <b>True Area:</b> 8630.000002 (SqFt
	Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
	1/1/2016	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	Full depth mill, base course rehabilitat
	1/1/2006	NU-IN	New Construction - Initial	0.00	0.00	>	

Network: JACKSONVILLE IN Branch: TW AP TAXIWAYS WIT Section: 920 Surface: AC L.C.D. 1/1/2016 Use: TAXIWAY Rank: P Length: 210.00 (Ft) Width: 90.00 (Ft) True Area: 23852.00000 (SqFt Thickness Work Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2016 CR-AC Complete Reconstruction - AC 0.00 0.00 Full depth mill, base course rehabilitat 1/1/2006 NU-IN New Construction - Initial 0.00 0.00 ~

Network: JACKSONVILLE IN Branch: TW B TAXIWAY B Section: 805 Surface:PCC **Length:** 3,275.00 (Ft) L.C.D. 1/1/1985 Use: TAXIWAY Rank: P Width: 75.00 (Ft) True Area: 253320.0000 (SqFt Thickness Work Major Work Date **Work Description** Cost Comments Code (in) M&R 1/1/1985 IMPORT BUILT 1985: 16" PCC ON 6" 0.00 16.00 ~ ECONOCRETE ON 6" CRUSHED A

Network: JACKSONVILLE IN Branch: TW B TAXIWAY B Section: 810 Surface:PCC **L.C.D.** 1/1/1994 Width: Use: TAXIWAY Rank: P **Length:** 1,825.00 (Ft) 75.00 (Ft) True Area: 136875.0000 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments Code M&R (in) 1/1/1994 IMPORT BUILT 1994: 16" P-501 ON 6" P-306 ON 6" 0.00 16.00

Work Thickness Major **Work Date Work Description** Cost Comments Code M&R (in) 1/1/1994 IMPORT BUILT 0.00 16.00 1994: 16" P-501 ON 6" P-306 ON P-~ ED 154

Network: JACKSONVILLE IN Branch: TW C TAXIWAY C Section: 1490 Surface: PCC L.C.D. 1/1/1994 Use: TAXIWAY Rank: P Length: 488.00 (Ft) Width: 90.00 (Ft) True Area: 50660.00001 (SqFt

Thickness Work Major **Work Date** Work Description Cost Comments Code (in) M&R 1/1/1994 IMPORT BUILT 1994: 16" P-501 ON 6" P-306 ON 6" 0.00 16.00 **\** ED P-154

 Network:
 JACKSONVILLE IN
 Branch:
 TW E
 TAXIWAY E
 Section:
 1670
 Surface:
 PCC

 L.C.D.
 1/1/1994
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 176.00 (Ft)
 Width:
 90.00 (Ft)
 True Area:
 29143.00000 (SqFt)

ш				8	( )		\ \ 1
	Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
	1/1/1994	IMPORT ED	BUILT	0.00	16.00		1994: 16" P-501 ON 6" P-306 ON 6" P-154

Page 8 of 16

Pavement Database: FDOT

Network:			Branch: TW E		WAY E	Section:		Surface:PCC
<b>L.C.D.</b> 1/1/19		se: TAXIWAY	Rank: P L	ength: 488	, ,		0 (Ft)	True Area: 59400.00001 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R		Comments
1/1/1985	NU-IN	New Constructi	on - Initial	0.00	0.00	<b>V</b>		
		Tiew Collisiracti		0.00	0.00			
Network:	JACKSON		Branch: TW F		WAY F	Section:	1145	Surface:PCC
Network: L.C.D. 1/1/19			Branch: TW F	TAXIV	WAY F	Section:		Surface:PCC True Area: 30320.00000 (SqFt

	Work Date	Code	``	ork Description	Cost	(in)	M&R	Comm	icits
_	1/1/1985	IMPORT ED	BUILT		0.00	16.00		1985: 16" PCC ON 6 ECONOCRETE ON	
	Network:	JACKSON	VILLE I	N Branch: TW F	TAXI	WAY F	Section:	1150	Surface:PCC

- 1	11001101111		· · · · · · · · · · · · · · · · · · ·	214110111 1 1	11111		50000	34114001100
	<b>L.C.D.</b> 1/1/19	985 Us	se: TAXIWAY	Rank: P L	ength: 125	.00 (Ft) Wi	dth: 75.0	00 (Ft) <b>True Area:</b> 18725.00000 (SqFt
	Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comments
	1/1/1985	IMPORT ED	BUILT		0.00	16.00		1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A

Network:	JACKSON	IVILLE IN	Branch: TW F	TAXIV	WAY F	Section:	1155 Surface:AC
<b>L.C.D.</b> 1/1/1	968 Us	se: TAXIWAY	Rank: P Lo	ength: 1,320	.00 (Ft) Wi	dth: 75.0	00 (Ft) <b>True Area:</b> 98961.00003 (SqFt
	Work				Thickness	Major	
Work Date	Code	Work D	escription	Cost	(in)	M&R	Comments

Network:	JACKSON	IVILLE IN	Branch: TW F	T.	AXIV	WAY F		Section:	1170		Surface:PCC
<b>L.C.D.</b> 1/1/1	994 Us	se: TAXIWAY	Rank: P L	ength:	222	.00 (Ft)	Widt	t <b>h:</b> 90.0	0 (Ft)	True Area:	27436.00000 (SqFt
Work Date	Work Code	Work D	escription	Cost	į	Thickne (in)	ss	Major M&R		Comi	nents
1/1/1994	IMPORT	DIHLT			0.00	16	.00		1004	1004 · 16" D	501 ON 6" P-306

	Network:	JACKSON	VILLE IN	Branch: TW F	TAXI	WAY F	Section:	1175 Surface	:PCC
ı	<b>L.C.D.</b> 1/1/19	985 Us	e: TAXIWAY	Rank: P L	ength: 266	6.00 (Ft) W	idth: 90.0	0 (Ft) <b>True Area:</b> 39074.00	0001 (SqFt
	Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comments	
	1/1/1985	IMPORT ED	BUILT		0.00	16.00		1985: 16" PCC ON 6" ECONOCRETE ON 6" CRU	ISHED A

l	Network:	JACKSON	IVILLE IN	Branch: TW G	TAX	IWAY G		Section:	1020		Surface:PCC
	<b>L.C.D.</b> 1/1/19	985 Us	se: TAXIWAY	Rank: P L	ength: 17	6.00 (Ft)	Widt	t <b>h:</b> 90.0	0 (Ft)	True Area:	29478.00000 (SqFt
	Work Date	Work Code	Work D	escription	Cost	Thicknotin)	ess	Major M&R		Comi	nents
	1/1/1985	IMPORT ED	BUILT		0.0	16	5.00			16" PCC ON OCRETE O	6" N 6" CRUSHED A

12/25/1999

NU-IN

New Construction - Initial

#### **Work History Report**

Page 9 of 16

Pavement Database: FDOT

Network: JACKSONVILLE IN Branch: TW G TAXIWAY G Section: 1025 Surface:PCC **L.C.D.** 1/1/1985 Use: TAXIWAY Rank: P Length: 125.00 (Ft) Width: 75.00 (Ft) True Area: 19138.00000 (SqFt Thickness Work Major **Work Date** Work Description Cost **Comments** Code (in) M&R 1/1/1985 IMPORT BUILT 0.00 16.00 1985: 16" PCC ON 6" ~ ECONOCRETE ON 6" CRUSHED A ED Network: JACKSONVILLE IN Branch: TW G TAXIWAY G Section: 1030 Surface:AC **L.C.D.** 1/1/2016 Use: TAXIWAY Rank: P 700.00 (Ft) Width: 50.00 (Ft) True Area: 35019.00001 (SqFt Length: Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2016 CR-AC Complete Reconstruction - AC 0.00 Full depth mill, base course rehabilitat 0.00 V 1/2/2001 ST-SS Surface Treatment - Slurry Seal 0.00 0.00 1/1/2001 OL-AS Overlay - AC Structural 0.00 2.00 ~ 1/1/1968 IMPORT BUILT 0.00 3.00 V 1968: 3" P-401 ON 8.5" P-211 ED Network: JACKSONVILLE IN Branch: TW G TAXIWAY G Section: 1032 Surface: AC L.C.D. 1/1/2016 Use: TAXIWAY Rank: P Length: 870.00 (Ft) Width: 50.00 (Ft) True Area: 44449.00001 (SqFt Work Thickness Major Work Date **Work Description** Cost Comments Code (in) M&R 1/1/2016 CR-AC Complete Reconstruction - AC 0.00 0.00 ~ Full depth mill, base course rehabilitat 1/2/2001 ST-SS Surface Treatment - Slurry Seal 0.00 0.00 1/1/2001 OL-AS Overlay - AC Structural 0.00 2.00 ~ 1/1/1968 IMPORT BUILT 0.00 1.00 V 1968: 1" P-401 ON 7.5" P-211 ED Network: JACKSONVILLE IN Branch: TW G Section: 1035 Surface:AC TAXIWAY G **L.C.D.** 1/1/2016 Use: TAXIWAY Rank: P Length: 190.00 (Ft) Width: 35.00 (Ft) True Area: 7929.000002 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/2016 Full depth mill, base course rehabilitat CR-AC Complete Reconstruction - AC 0.00 0.00 ~ 1/1/2001 ST-SS Surface Treatment - Slurry Seal 0.00 0.00 12/25/1999 NU-IN New Construction - Initial 0.00 0.00 ~ Network: JACKSONVILLE IN Branch: TW G TAXIWAY G Section: 1040 Surface: AC **L.C.D.** 1/1/2016 Use: TAXIWAY Rank: P 150.00 (Ft) Width: 60.00 (Ft) True Area: 14096.00000 (SaFt Length: Thickness Work Major **Work Date Work Description** Cost Comments Code M&R (in) 1/1/2016 Complete Reconstruction - AC Full depth mill, base course rehabilitat CR-AC 0.00 0.00 **V** 1/2/2001 ST-SS Surface Treatment - Slurry Seal 0.00 0.00 1/1/2001 OL-AS Overlay - AC Structural 0.00 2.00 ~

Pavement Management System PAVER 7.0 TM

0.00

0.00

~

Page 10 of 16

Pavement Database: FDOT

		Pavement Database:	TD01			
Network:	JACKSON	NVILLE IN Branch: TW G	TAXIV	WAY G	Section:	1045 Surface: AAC
<b>L.C.D.</b> 1/1/2	001 Us	se: TAXIWAY Rank: P L	ength: 223	.00 (Ft) <b>Wi</b> o	dth: 60.0	0 (Ft) <b>True Area:</b> 14480.00000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		
1/2/2001	ST-SS	Surface Treatment - Slurry Seal	0.00	0.00		
1/1/2001	OL-AS	Overlay - AC Structural	0.00	2.00		
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<b>V</b>	
N. d. I	IA CIZCON	WHIEDI B I TWO	TANI	WAN C	G 4:	1000 G & DCC
		WILLE IN Branch: TW G		WAY G	Section:	
<b>L.C.D.</b> 1/1/1		se: TAXIWAY Rank: P L	ength: 515	` '		0 (Ft) <b>True Area:</b> 133822.0000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1994	IMPORT	BUILT	0.00	16.00	<b>V</b>	1994: 16" P-501 ON 6" P306 ON 6"
	ED					P154
N. d l.	IA CIZGON	WHIEDI D TWII	TAVI	V A X/ II	G 4*	550 G. G
Network:				WAY H	Section:	
<b>L.C.D.</b> 1/1/1		se: TAXIWAY Rank: P L	ength: 488	. ,		0 (Ft) <b>True Area:</b> 208460.0000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
	~~~					
1/1/1994	IMPORT	BUILT	0.00	16.00	<b>~</b>	1994: 16" P-501 ON 6" P-306 ON 6"
1/1/1994		BUILT	0.00	16.00	<b>V</b>	1994: 16" P-501 ON 6" P-306 ON 6" P-154
	IMPORT ED					P-154
Network:	IMPORT ED JACKSON	NVILLE IN Branch: TW H	TAXIV	WAY H	Section:	P-154  Surface:PCC
	JACKSON 985 Us	NVILLE IN Branch: TW H		WAY H .00 (Ft) Wid	Section: dth: 75.0 Major	P-154
Network: L.C.D. 1/1/1	IMPORT ED JACKSON 985 Us	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L	TAXIV	WAY H .00 (Ft) <b>Wi</b> o	Section:	P-154  555 Surface:PCC 0 (Ft) True Area: 127293.0000 (SqFt
Network: L.C.D. 1/1/1 Work Date	JACKSON 985 Us Work Code	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description Slab Replacement - PCC	TAXIV ength: 1,540 Cost	VAY H .00 (Ft) Wid Thickness (in)	Section: dth: 75.0 Major	P-154  555
Network: L.C.D. 1/1/1 Work Date 1/1/2012	JACKSON 985 Us Work Code SL-PC	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description Slab Replacement - PCC	TAXIV ength: 1,540 Cost	WAY H .00 (Ft) Wich	Section: dth: 75.0 Major M&R	P-154  555
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985	JACKSON 985 Us Work Code SL-PC IMPORT ED	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description Slab Replacement - PCC BUILT	TAXIV ength: 1,540  Cost  0.00 0.00	VAY H .00 (Ft) Wid Thickness (in) 0.00 16.00	Section: dth: 75.0 Major M&R	P-154  Surface:PCC 0 (Ft) True Area: 127293.0000 (SqFt  Comments  ISOLATED SLAB REPAIR 22" P-501 1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985	JACKSON 985 Us Work Code SL-PC IMPORT ED	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description Slab Replacement - PCC BUILT  NVILLE IN Branch: TW H	TAXIV ength: 1,540  Cost  0.00 0.00	WAY H .00 (Ft) Wic Thickness (in) 0.00 16.00	Section: dth: 75.0 Major M&R  Section:	P-154  555 Surface:PCC 0 (Ft) True Area: 127293.0000 (SqFt  Comments  ISOLATED SLAB REPAIR 22" P-501 1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  557 Surface:PCC
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985	JACKSON 985 Us Work Code SL-PC IMPORT ED  JACKSON 007 Us	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description Slab Replacement - PCC BUILT  NVILLE IN Branch: TW H	TAXIV ength: 1,540  Cost  0.00 0.00	VAY H .00 (Ft) Wio Thickness (in) 0.00 16.00  VAY H .00 (Ft) Wio	Section: dth: 75.0 Major M&R  Section: dth: 60.0	P-154  Surface:PCC 0 (Ft) True Area: 127293.0000 (SqFt  Comments  ISOLATED SLAB REPAIR 22" P-501 1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985	JACKSON 985 Us Work Code SL-PC IMPORT ED	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description Slab Replacement - PCC BUILT  NVILLE IN Branch: TW H	TAXIV ength: 1,540  Cost  0.00 0.00	WAY H .00 (Ft) Wic Thickness (in) 0.00 16.00	Section: dth: 75.0 Major M&R  Section:	P-154  555 Surface:PCC 0 (Ft) True Area: 127293.0000 (SqFt  Comments  ISOLATED SLAB REPAIR 22" P-501 1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  557 Surface:PCC
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985 Network: L.C.D. 1/1/2	JACKSON 985 Us Work Code SL-PC IMPORT ED  JACKSON 007 Us Work	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description Slab Replacement - PCC BUILT  NVILLE IN Branch: TW H se: TAXIWAY Rank: P L	TAXIV ength: 1,540 Cost 0.00 0.00 TAXIV ength: 615	WAY H .00 (Ft) Wickness (in) 0.00 16.00 WAY H .00 (Ft) Wickness	Section: dth: 75.0 Major M&R  Section: dth: 60.0 Major	P-154  555
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985 Network: L.C.D. 1/1/2 Work Date	JACKSON 985 Us Work Code SL-PC IMPORT ED  JACKSON 007 Us Work Code SR-PC IMPORT	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Slab Replacement - PCC BUILT  NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Surface Reconstruction - PCC	TAXIV ength: 1,540  Cost  0.00 0.00  TAXIV ength: 615  Cost	WAY H .00 (Ft) Wide Thickness (in) 0.00 16.00 WAY H .00 (Ft) Wide Thickness (in)	Section: dth: 75.0 Major M&R  Section: dth: 60.0 Major M&R	P-154  555
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985 Network: L.C.D. 1/1/2 Work Date 1/1/2007	JACKSON 985 Us Work Code SL-PC IMPORT ED  JACKSON 007 Us Work Code SR-PC	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Slab Replacement - PCC BUILT  NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Surface Reconstruction - PCC	TAXIV ength: 1,540  Cost  0.00 0.00  TAXIV ength: 615  Cost  0.00	WAY H .00 (Ft) Wid Thickness (in) 0.00 16.00  WAY H .00 (Ft) Wid Thickness (in) 0.00	Section:  dth: 75.0  Major M&R  Section:  dth: 60.0  Major M&R  V	P-154  555 Surface:PCC 0 (Ft) True Area: 127293.0000 (SqFt  Comments  ISOLATED SLAB REPAIR 22" P-501 1985: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  557 Surface:PCC 0 (Ft) True Area: 38685.00001 (SqFt  Comments
Network: L.C.D. 1/1/1  Work Date 1/1/2012 1/1/1985  Network: L.C.D. 1/1/2  Work Date 1/1/2007 1/1/1985	JACKSON 985 Us Work Code SL-PC IMPORT ED  JACKSON 007 Us Work Code SR-PC IMPORT ED	NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Slab Replacement - PCC BUILT  NVILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Surface Reconstruction - PCC BUILT	TAXIVength: 1,540  Cost  0.00 0.00  TAXIVength: 615  Cost  0.00 0.00	WAY H .00 (Ft) Wic Thickness (in) 0.00 16.00  WAY H .00 (Ft) Wic Thickness (in) 0.00 16.00	Section: dth: 75.0 Major M&R  Section: dth: 60.0 Major M&R  V	P-154  555
Network: L.C.D. 1/1/1  Work Date  1/1/2012  1/1/1985  Network: L.C.D. 1/1/2  Work Date  1/1/2007  1/1/1985	JACKSON  985 Us  Work Code SL-PC IMPORT ED  JACKSON  007 Us  Work Code SR-PC IMPORT ED	WOILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Slab Replacement - PCC BUILT  WILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Surface Reconstruction - PCC BUILT	TAXIV ength: 1,540  Cost  0.00 0.00  TAXIV ength: 615  Cost  0.00 0.00  TAXIV	WAY H .00 (Ft) Win Thickness (in) 0.00 16.00  WAY H .00 (Ft) Win Thickness (in) 0.00 16.00	Section:  dth: 75.0  Major M&R  Section:  dth: 60.0  Major M&R  Section:	P-154  555
Network: L.C.D. 1/1/1  Work Date 1/1/2012 1/1/1985  Network: L.C.D. 1/1/2  Work Date 1/1/2007 1/1/1985	JACKSON 985 Us Work Code SL-PC IMPORT ED  JACKSON 007 Us Work Code SR-PC IMPORT ED  JACKSON 994 Us Work	WOILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Slab Replacement - PCC BUILT  WILLE IN Branch: TW H se: TAXIWAY Rank: P L Work Description  Surface Reconstruction - PCC BUILT	TAXIV ength: 1,540  Cost  0.00 0.00  TAXIV ength: 615  Cost  0.00 0.00	WAY H .00 (Ft) Wickness (in) 0.00 16.00  WAY H .00 (Ft) Wickness (in) 0.00 16.00  WAY J .00 (Ft) Wickness	Section:  dth: 75.0  Major M&R  Section:  dth: 60.0  Major M&R  Section:  dth: 150.0  Major	P-154  555
Network: L.C.D. 1/1/1 Work Date 1/1/2012 1/1/1985  Network: L.C.D. 1/1/2 Work Date 1/1/2007 1/1/1985  Network: L.C.D. 1/1/1	JACKSON 985 Us Work Code SL-PC IMPORT ED  JACKSON 007 Us Work Code SR-PC IMPORT ED  JACKSON 994 Us	WORK Description  Slab Replacement - PCC BUILT  Work Description  SVILLE IN Branch: TW H  See: TAXIWAY Rank: P L  Work Description  Surface Reconstruction - PCC BUILT  SUILLE IN Branch: TW J  See: TAXIWAY Rank: P L  Work Description	TAXIV ength: 1,540  Cost  0.00 0.00  TAXIV ength: 615  Cost  0.00 0.00  TAXIV ength: 550	WAY H .00 (Ft) Wie Thickness (in) 0.00 16.00  WAY H .00 (Ft) Wie Thickness (in) 0.00 16.00  WAY J .00 (Ft) Wie	Section: dth: 75.0 Major M&R  Section: dth: 60.0 Major M&R  Section: dth: 150.0	P-154  555

1	Λ	/3	17	Λ	1	(
	"	/.T	ΙL	١,		-

Page 11 of 16

Pavement Database: FDOT

Network: JACk	SONVILLE IN	Branch: TW J	TAXIV	WAY J	Section:	745 Surface:PCC
<b>L.C.D.</b> 1/1/1989	Use: TAXIWAY	Rank: P L	ength: 1,760	.00 (Ft) Wi	dth: 75.0	0 (Ft) <b>True Area:</b> 94986.00002 (SqFt
Work Date	ork de Work D	escription	Cost	Thickness (in)	Major M&R	Comments
1/1/1989 IMP	ORT BUILT		0.00	16.00	<b>~</b>	1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
						ECONOCRETE ON 0 CROSHED A
Network: JACK	SONVILLE IN	Branch: TW J	TAXIV	WAY J	Section:	750 Surface:PCC
L.C.D. 1/1/1982	Use: TAXIWAY	Rank: P L	ength: 265	` ′		0 (Ft) True Area: 21670.00000 (SqFt
Work Date Co	ae	escription	Cost	Thickness (in)	Major M&R	Comments
1/1/1982 IMP	ORT BUILT D		0.00	16.00	<b>&gt;</b>	1982: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: JACK		Branch: TW J		WAY J	Section:	~~~~~~~~~~~
L.C.D. 1/1/1968	Use: TAXIWAY		ength: 175	.00 (Ft) Wi	Major	0 (Ft) <b>True Area:</b> 13125.00000 (SqFt
Work Date Co	de Work L	escription	Cost	(in)	M&R	Comments
1/1/1968 IMP	ORT BUILT D		0.00	13.00	<b>&gt;</b>	1968: 13" PCC ON 6" STABILIZED SUBBASE
Network: JACK		Branch: TW J		WAY J	Section:	
L.C.D. 1/1/1984	Use: TAXIWAY		I	.00 (Ft) Wi	dth: 75.0 Major	0 (Ft) <b>True Area:</b> 21750.00000 (SqFt
Work Date Co	de Work I	escription	Cost	(in)	M&R	Comments
1/1/1984 IMP	ORT BUILT D		0.00	16.00	<b>&gt;</b>	1984: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: JACk L.C.D. 1/1/2013	SONVILLE IN Use: TAXIWAY	Branch: TW J	TAXIV ength: 1,020	WAY J	Section:	765 <b>Surface:</b> PCC 0 (Ft) <b>True Area:</b> 123159.0000 (SqFt
W	ork		<u> </u>	Thickness	Major	,
	ae	escription	Cost	(in)	M&R	Comments
1/1/2013 NU	-IN New Construct	ion - initial	0.00	0.00		16"PCC P501,6" ECONOCRETE BA
Network: JACk	SONVILLE IN	Branch: TW K	TAXIV	WAY K	Section:	1320 Surface:PCC
<b>L.C.D.</b> 1/1/1992	Use: TAXIWAY	Rank: P L	ength: 795	.00 (Ft) Wi	<b>dth:</b> 92.0	0 (Ft) <b>True Area:</b> 107334.0000 (SqFt
Work Date	ork ode Work E	escription	Cost	Thickness (in)	Major M&R	Comments
1/1/1992 IMP	ORT BUILT		0.00	16.00	V	1992: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
E	ט					ECONOCKETE ON 6" CKUSHED A
Network: JACk	SONVILLE IN	Branch: TW L	TAXIV	WAY L	Section:	205 Surface:PCC
<b>L.C.D.</b> 1/1/1994	Use: TAXIWAY	Rank: P L	ength: 244	, ,		0 (Ft) <b>True Area:</b> 25258.00000 (SqFt
Work Date Co	ork de Work E	escription	Cost	Thickness (in)	Major M&R	Comments
1/1/1994 IMP	ORT BUILT		0.00	16.00	<b>V</b>	1994: 16" P-501 ON 6" P-306 ON 6" P-154
Е					<u> </u>	

Page 12 of 16

Pavement Database: FDOT

Pavement Database:	FDOT			
Network: JACKSONVILLE IN Branch: TW L	TAXIV	WAY L	Section:	210 Surface:PCC
L.C.D. 1/1/1983 Use: TAXIWAY Rank: P Lo	ength: 244	.00 (Ft) <b>Wi</b> o	<b>dth:</b> 90.0	0 (Ft) <b>True Area:</b> 28620.00000 (SqFt
Work Date   Work Code   Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1983 IMPORT BUILT ED	0.00	16.00		1983: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: JACKSONVILLE IN Branch: TW L	TAXIV	WAY L	Section:	215 Surface:PCC
	ength: 206	· /		0 (Ft) <b>True Area:</b> 18195.00000 (SqFt
Work Date   Work Code   Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1983 IMPORT BUILT ED	0.00	16.00		1983: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: JACKSONVILLE IN Branch: TW L	TAXIV	WAY L	Section:	220 Surface:PCC
	ength: 240			0 (Ft) <b>True Area:</b> 25304.00000 (SqFt
Work Date   Work Code   Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992 IMPORT BUILT ED	0.00	16.00	<b>V</b> :	1992: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: JACKSONVILLE IN Branch: TW L	TAYI	WAY L	Section:	225 Surface:PCC
				0 (Ft) <b>True Area:</b> 52307.00001 (SqFt
Work Date   Work   Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992 IMPORT BUILT ED	0.00	16.00	<b>V</b>	1992: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Network: JACKSONVILLE IN Branch: TW N  L.C.D. 1/1/1992 Use: TAXIWAY Rank: P Lo	TAXIV ength: 2,950	WAY N .00 (Ft) <b>Wi</b> o	Section: dth: 75.0	305 Surface:PCC 0 (Ft) True Area: 221250.0000 (SqFt
Work Date   Work   Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992 IMPORT BUILT ED	0.00	16.00	<b>V</b>	1992: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
N. I. LOWGONWILLERY D. T. T.	m . 3***	V/ A V/ A V	g .:	310
Network: JACKSONVILLE IN Branch: TW N  L.C.D. 1/1/1998 Use: TAXIWAY Rank: P Lo	TAXIV ength: 2,451	VAY N 00 (Ft) <b>Wi</b> d	Section: dth: 75.0	310 Surface:PCC 0 (Ft) True Area: 180075.0000 (SqFt
Work Date   Work   Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1998 IMPORT BUILT ED	0.00	16.00	V	1998: 16" PCC ON 6" ECONOCRETE
Network: JACKSONVILLE IN Branch: TW N		WAY N	Section:	
Work	ength: 1,775	Thickness	dth: 75.0 Major	0 (Ft) True Area: 131250.0000 (SqFt
Work Date Code Work Description  1/1/2000 SR-PC Surface Reconstruction - PCC	Cost 0.00	(in) 0.00	M&R ✓	Comments  16" PCC/6" ECONOCONCR. BASE/
1/1/1995 IMPORT BUILT ED	0.00	16.00		1995: 16" P-501 ON 6" P-306 ON 6" P-154
LD .				- 10 .

1	Λ	13	/20	11	(
		7.7	/ ZI	,,	•

Page 13 of 16

Pavement Database: FDOT

Network: L.C.D. 1/1/1		VILLE IN	Branch: TW N Rank: P L		VAY N .00 (Ft) <b>Wi</b> o	Section: dth: 75.0	315 <b>Surface:</b> PCC 0 (Ft) <b>True Area:</b> 45000.00001 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comments
1/1/1996	IMPORT ED	BUILT		0.00	13.00		13" P501 PCC PAVEMENT ON 6" P306 STABILIZED SUBBASE ON 6"
Network:	JACKSON	IVILLE IN	Branch: TW P	TAXIV	VAY P	Section:	640 Surface:PCC
<b>L.C.D.</b> 1/1/1	982 Us	e: TAXIWAY	Rank: P L	ength: 811	.00 (Ft) Wi	dth: 75.0	0 (Ft) True Area: 60825.00001 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comments
1/1/1982	IMPORT ED	BUILT		0.00	16.00	<b>V</b>	1982: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A

l	Network:	JACKSON	IVILLE IN	Branch: TW P	TAX	WAY P	Section:	641 Surface:PCC
	<b>L.C.D.</b> 1/1/1	994 Us	se: TAXIWAY	Rank: P L	ength: 25	0.00 (Ft) <b>W</b>	idth: 75.0	00 (Ft) <b>True Area:</b> 8909.000002 (SqFt
	Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comments
Π	1/1/1994	IMPORT	RUILT		0.00	16.00	<b>\</b>	EST 1994: 16" P-501 ON 6" P-306

	Network:	JACKSON	IVILLE IN	Branch: TW P	TAXI	WAY P	Section:	650 Surface:PCC
ı	<b>L.C.D.</b> 1/1/19	992 Us	se: TAXIWAY	Rank: P L	ength: 550	.00 (Ft) <b>W</b>	<b>idth:</b> 140.0	0 (Ft) <b>True Area:</b> 133322.0000 (SqFt
	Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Comments
	1/1/1992	IMPORT	BUILT		0.00	16.00		1992: 16" PCC ON 6"
		ED						ECONOCRETE ON 6" CRUSHED A

Network:	JACKSON	IVILLE IN	Branch: TW P	TAXI	WAY P	Section:	655	Surface:PCC
<b>L.C.D.</b> 1/1/1	992 Us	se: TAXIWAY	Rank: P L	ength: 1,500	.00 (Ft) W	idth: 75.0	0 (Ft) True Area:	79579.00002 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Com	ments
1/1/1992	IMPORT ED	BUILT		0.00	16.00	_ <u> </u>	1992: 16" PCC ON	I 6" N 6" CRUSHED A

Network:	JACKSON	IVILLE IN	Branch: TW P	TAXIV	WAY P	Section:	660	Surface:PCC
<b>L.C.D.</b> 1/1/2	2013 Us	se: TAXIWAY	Rank: P L	ength: 1,050	.00 (Ft) Wi	dth: 100.0	0 (Ft) True Area:	126658.0000 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Com	ments
1/1/2013	NU-IN	New Construct	ion - Initial	0.00	0.00	>	16"PCC P501,6" E	CONOCRETE BA

Network:	JACKSON	IVILLE IN	Branch: TW Q	TAXI	WAY Q	Section:	560	Surface:PCC
<b>L.C.D.</b> 1/1/19	996 Us	se: TAXIWAY	Rank: P L	ength: 690	0.00 (Ft) <b>V</b>	<b>Vidth:</b> 90.0	00 (Ft) True Area	: 115700.0000 (SqFt
Work Date	Work Code	Work D	escription	Cost	Thickness (in)	Major M&R	Com	nments
1/1/1996	NU-IN	New Construct	ion - Initial	0.00	13.0	0	1996: 13" P-501 o	n 6" P-306 on 6" P-

Page 14 of 16

Pavement Database: FDOT

Network:	JACKSON	NVILLE IN Branc	eh: TW R	TAXI	WAY R	Section:	570 Surface:PCC
<b>L.C.D.</b> 1/1/1	996 Us	se: TAXIWAY Rank	k: P L	ength: 380	.00 (Ft) Wi	dth: 90.0	0 (Ft) <b>True Area:</b> 43767.00001 (Sq
Work Date	Work Code	Work Descrip	tion	Cost	Thickness (in)	Major M&R	Comments
1/1/1996	IMPORT ED	BUILT		0.00	16.00	<b>V</b>	1996: 16" P-501 ON 6" P-306 ON 6" P-154
Network:	JACKSON	NVILLE IN Branc	ch: TW R	TAXI	WAY R	Section:	575 Surface:PCC
<b>L.C.D.</b> 1/1/1	996 U	se: TAXIWAY Rank	k: P L	ength: 1,210	.00 (Ft) Wi	dth: 75.0	0 (Ft) <b>True Area:</b> 111623.0000 (Sq
Work Date	Work Code	Work Descrip	tion	Cost	Thickness (in)	Major M&R	Comments
1/1/1996	IMPORT ED	BUILT		0.00	16.00		1996: 16" P-501 ON 6" P-306 ON 6" P-154
Network:	JACKSON	NVILLE IN <b>Branc</b>	eh: TW R	TAXI	WAY R	Section:	576 Surface:PCC
<b>L.C.D.</b> 1/1/1	991 U	se: TAXIWAY Rank	k: P L	ength: 240	.00 (Ft) Wi	dth: 115.0	0 (Ft) <b>True Area:</b> 29713.00000 (Sq
Work Date	Work Code	Work Descrip	tion	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT		0.00	16.00		1991: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
N. d d.	IA CIVICON	Dalle Di Dana	L. TWG	T 4 3/13	WAW C	S	1205 C
- 10011101-110			ch: TW S		WAY S	Section:	
- 10011101-110	989 U	NVILLE IN Branc se: TAXIWAY Rank		TAXIV ength: 1,385	.00 (Ft) <b>Wi</b>	<b>dth:</b> 75.0	1285 <b>Surface:</b> PCC 0 (Ft) <b>True Area:</b> 140346.0000 (Sq
L.C.D. 1/1/1			k: P L				
Network: L.C.D. 1/1/1 Work Date 1/1/1989	989 Us Work	se: TAXIWAY Rank Work Descrip	k: P L	ength: 1,385	.00 (Ft) Wi	dth: 75.0 Major	0 (Ft) <b>True Area:</b> 140346.0000 (Sq
L.C.D. 1/1/1 Work Date	989 Use Work Code IMPORT	se: TAXIWAY Rank Work Descrip	k: P L	ength: 1,385	.00 (Ft) Wi Thickness (in)	dth: 75.0 Major M&R	0 (Ft) <b>True Area:</b> 140346.0000 (Sq <b>Comments</b> 1989: 16" PCC ON 6"
Work Date 1/1/1989	989 Use Work Code IMPORT ED	Work Descrip	k: P L	Cost 0.00	.00 (Ft) Wi Thickness (in)	dth: 75.0 Major M&R	0 (Ft) True Area: 140346.0000 (Sq Comments 1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A
Work Date 1/1/1989 Network:	989 US Work Code IMPORT ED	Work Description	tion  ch: TW S	Cost 0.00  TAXIV	Thickness (in) 16.00	Major M&R	Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  1290  Surface: PCC
Work Date 1/1/1989 Network:	989 Use Work Code IMPORT ED JACKSON 989 Use Work	Work Descript BUILT  NVILLE IN Brance	c: P L tion ch: TW S c: P L	Cost 0.00  TAXIV	Thickness (in) 16.00	Major M&R	Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  1290  Surface: PCC
Network: L.C.D. 1/1/1  Work Date	989 US Work Code IMPORT ED  JACKSON 989 US Work	Work Descript BUILT  NVILLE IN Brance se: TAXIWAY Rank Work Descript	c: P L tion ch: TW S c: P L	Cost 0.00  TAXIVength: 220	Thickness (in)  16.00  WAY S  .00 (Ft) Wi  Thickness	Major M&R  Section: dth: 100.0  Major	O (Ft) True Area: 140346.0000 (Sq. Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  1290 Surface: PCC O (Ft) True Area: 28370.00000 (Sq. Comments)  1989: 16" PCC ON 6"
Network: 2C.D. 1/1/1 Work Date	989 US Work Code IMPORT ED  JACKSON 989 US Work Code IMPORT	Work Descript BUILT  NVILLE IN Brance se: TAXIWAY Rank Work Descript	c: P L tion ch: TW S c: P L	Cost  TAXIVength: 220  Cost	WAY S  .00 (Ft) Wi Thickness (in)  16.00  WAY S  .00 (Ft) Wi Thickness (in)	Major M&R  Section: dth: 100.0  Major M&R	0 (Ft) True Area: 140346.0000 (Sc Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED  1290 Surface:PCC 0 (Ft) True Area: 28370.00000 (Sc  Comments  1989: 16" PCC ON 6"
Network: L.C.D. 1/1/1 Work Date 1/1/1989  Network: L.C.D. 1/1/1 Work Date 1/1/1989	989 US Work Code IMPORT ED  JACKSON 989 US Work Code IMPORT ED  JACKSON	Work Descript BUILT  NVILLE IN Brance se: TAXIWAY Rank Work Descript BUILT  NVILLE IN Brance	c: P L tion ch: TW S c: P L tion	Cost 0.00  TAXIV ength: 220  Cost 0.00	WAY S  Output  Thickness (in)  16.00  WAY S  Output  Thickness (in)  16.00	Major M&R  Section:  dth: 100.0  Major M&R  Section:	Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  1290 Surface: PCC 0 (Ft) True Area: 28370.00000 (Sq.  Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  1282 Surface: PCC
Network:  Network:  Network:  Network:  Network:	989 US Work Code IMPORT ED  JACKSON 989 US Work Code IMPORT ED  JACKSON	Work Descript BUILT  NVILLE IN Brances: TAXIWAY Rank Work Descript BUILT	c: P L tion ch: TW S c: P L tion	Cost 0.00  TAXIV ength: 220  Cost 0.00	WAY S  OO (Ft) Wi  Thickness (in)  16.00  WAY S  OO (Ft) Wi  Thickness (in)  16.00  WAY T	Major M&R  Section: dth: 100.0  Major M&R  V  Section: dth: 148.0	0 (Ft) True Area: 140346.0000 (Sc.  Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED  1290 Surface:PCC 0 (Ft) True Area: 28370.00000 (Sc.  Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED  1282 Surface:PCC
Network: L.C.D. 1/1/1 Work Date 1/1/1989  Network: L.C.D. 1/1/1 Work Date 1/1/1989  Network: L.C.D. 1/1/2 Work Date	989 Use Work Code IMPORT ED Work Code IMPORT ED JACKSON 912 Use Work Code Work Code Code	Work Descript BUILT  NVILLE IN Brance See: TAXIWAY Ranke Work Descript BUILT  NVILLE IN Brance See: TAXIWAY Ranke Work Descript BUILT	ch: TW S ch: TW T ch: TW T ch: TW T	Cost 0.00  TAXIVength: 220  Cost 0.00  TAXIVength: 487  Cost	WAY S  OO (Ft) Wi  Thickness (in)  16.00  WAY S  OO (Ft) Wi  Thickness (in)  16.00  WAY T  OO (Ft) Wi  Thickness (in)	Section: dth: 100.0 Major M&R  Section: dth: 148.0 Major M&R	Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  1290 Surface: PCC 0 (Ft) True Area: 28370.00000 (Sq  Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED A  1282 Surface: PCC 0 (Ft) True Area: 59457.00001 (Sq  Comments
Network: C.D. 1/1/1  Work Date  /1/1989  Network: C.D. 1/1/1  Work Date  /1/1989  Network: C.D. 1/1/2	989 US Work Code IMPORT ED  JACKSON 989 US Work Code IMPORT ED  JACKSON 012 US Work	Work Descript BUILT  NVILLE IN Brance See: TAXIWAY Rank Work Descript BUILT  NVILLE IN Brance See: TAXIWAY Rank See: TAXIWAY Rank	ch: TW S ch: TW T ch: TW T ch: TW T	Cost	WAY S  OO (Ft) Wi  Thickness (in)  16.00  WAY S  OO (Ft) Wi  Thickness (in)  16.00  WAY T  OO (Ft) Wi  Thickness	Section: dth: 100.0 Major M&R  Section: dth: 148.0 Major	Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED  1290 Surface:PCC 0 (Ft) True Area: 28370.00000 (Sc  Comments  1989: 16" PCC ON 6" ECONOCRETE ON 6" CRUSHED  1282 Surface:PCC 0 (Ft) True Area: 59457.00001 (Sc

l	Network: JACKSONVILLE IN		Branch: TW U TAXIW			VAY U Section: 39			390 Surface:PCC		
	<b>L.C.D.</b> 1/1/19	998 Us	se: TAXIWAY	Rank: P L	ength:	488	.00 (Ft)	Width:	90.0	0 (Ft) True Area:	52557.00001 (SqFt
	Work Date	Work Code	Work D	escription	Со	st	Thicknes (in)		ajor [&R	Com	ments
	1/1/1998	IMPORT ED	BUILT			0.00	16.0	00	<b>/</b> ]:	1998: 16" P-501 O	N 6" P-306 ON 6"

10/3/2019	Work History Report	Page 15 of 16
	Pavement Database: FDOT	

Network: JACKSONVILLE IN		Branch: TW V TA		WAY V	Section:	905 Surface:PCC	
<b>L.C.D.</b> 1/1/2013 <b>Use:</b> TAXIWAY		Rank: P L	ength: 785	.00 (Ft) Wi	idth: 100.0	0 (Ft) <b>True Area:</b> 78127.00002 (SqFt	
Work Dat	Work Code	Work I	Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construct	ion - Initial	0.00	0.00	<b>Y</b>	16"PCC P501,6" ECONOCRETE BA

Page 16 of 16

Pavement Database: FDOT

#### **Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	71	7,878,316.00	14.23	4.52
Complete Reconstruction - AC	7	210,115.00	0.00	0.00
MILL and OVERLAY	1	10,052.00	0.00	0.00
New Construction - AC	3	395,216.00	0.00	0.00
New Construction - Initial	14	996,898.00	2.07	5.11
New Construction - PCC	11	3,107,507.00	4.36	7.13
Overlay - AC Structural	4	108,044.00	2.00	0.00
Slab Replacement - PCC	1	127,293.00	0.00	0.00
Surface Reconstruction - PCC	5	1,240,560.00	0.00	0.00
Surface Treatment - Seal Coat	1	14,480.00	0.00	0.00
Surface Treatment - Slurry Seal	5	115,973.00	0.00	0.00

10/3/2019
-----------

## **Branch Condition Report**

Page 1 of 2

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP CARGO	6	2,475.00	298.33	851,065.00	APRON	65.17	19.79	76.99
AP GA	4	1,792.00	236.25	471,356.00	APRON	67.00	14.44	65.89
AP HOLD	1	533.00	281.00	150,030.00	APRON	85.00	0.00	85.00
AP TERM	12	7,712.00	308.75	2,810,096.00	APRON	87.58	9.58	86.08
RW 14-32	7	23,850.00	50.00	1,155,000.00	RUNWAY	89.57	3.81	92.07
RW 8-26	2	30,000.00	62.50	1,500,000.00	RUNWAY	86.00	3.00	87.00
TW A	5	10,000.00	75.00	750,073.00	TAXIWAY	79.60	3.26	79.69
TW AP	8	3,335.00	70.37	309,476.00	TAXIWAY	69.13	19.19	68.70
TW B	2	5,100.00	75.00	390,195.00	TAXIWAY	81.50	0.50	81.65
TW C	2	664.00	90.00	74,920.00	TAXIWAY	74.00	1.00	74.35
TW E	2	664.00	90.00	88,543.00	TAXIWAY	79.00	1.00	79.34
TW F	5	2,109.00	84.80	214,516.00	TAXIWAY	76.20	23.40	61.49
TW G	8	2,949.00	71.25	298,411.00	TAXIWAY	83.88	12.55	87.63
TW H	3	2,643.00	98.33	374,438.00	TAXIWAY	79.33	7.36	81.05
TW J	6	4,060.00	93.33	410,932.00	TAXIWAY	79.67	10.09	86.55
TW K	1	795.00	92.00	107,334.00	TAXIWAY	85.00	0.00	85.00
TW L	5	1,422.00	90.00	149,684.00	TAXIWAY	80.60	2.73	80.92
TW N	4	7,701.00	75.00	577,575.00	TAXIWAY	89.75	2.17	88.86
TW P	5	4,161.00	93.00	409,293.00	TAXIWAY	89.20	10.38	92.48
TW Q	1	690.00	90.00	115,700.00	TAXIWAY	85.00	0.00	85.00
TW R	3	1,830.00	93.33	185,103.00	TAXIWAY	86.67	0.94	87.21
TW S	2	1,605.00	87.50	168,716.00	TAXIWAY	79.50	1.50	80.50
TW T	1	487.00	148.00	59,457.00	TAXIWAY	97.00	0.00	97.00
TW U	1	488.00	90.00	52,557.00	TAXIWAY	91.00	0.00	91.00
TW V	1	785.00	100.00	78,127.00	TAXIWAY	100.00	0.00	100.00

10/3/2019	Branch Condition Report	Page 2 of 2
	Pavement Database: FDOT	

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	23	4,282,547.00	78.04	17.33	82.01
RUNWAY	9	2,655,000.00	88.78	3.94	89.20
TAXIWAY	65	4,815,050.00	81.12	13.19	82.88
ALL	97	11,752,597.00	81.10	14.04	83.99

Pavement Database: FDOT

#### NetworkId: JAX

	wase. TDOI				1.00,	voi kiu.				
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspec tion	PCI
AP CARGO	4105	1/1/1989	PCC	APRON	Р	0	296,070.00	4/29/2019	30	83
AP CARGO	4110	1/1/1994	AC	APRON	Р	0	27,040.00	4/29/2019	25	33
AP CARGO	4118	1/1/2000	PCC	APRON	Р	0	198,059.00	4/29/2019	19	88
AP CARGO	4120	1/1/1981	PCC	APRON	P	0	212,550.00	4/29/2019	38	78
AP CARGO	4125	1/1/1968	PCC	APRON	Р	0	84,968.00	4/29/2019	51	48
AP CARGO	4135	5/1/2007	PCC	APRON	Р	0	32,378.00		12	
AP GA	4205	1/1/2016	AC	APRON	P	0	76,140.00	4/29/2019	3	
AP GA	5105	1/1/2010	AC	APRON	P	0	127,653.00	4/29/2019	13	
AP GA	5110	1/1/2006	AC	APRON	P	0	239,174.00	4/29/2019	13	
AP GA	5115	1/1/2006	AC	APRON	P	0	28,389.00	4/29/2019	13	
	<u> </u>			1	<u> </u>					
AP HOLD	4405	1/1/1992	PCC	APRON	Р	0	150,030.00	4/29/2019	27	85
AP TERM	4305	1/1/1985	PCC	APRON	Р	0	36,141.00	4/29/2019	34	79
AP TERM	4310	1/1/1985	PCC	APRON	Р	0	144,838.00	4/29/2019	34	79
AP TERM	4315	1/1/1985	PCC	APRON	Р	0	146,950.00	4/29/2019	34	86
AP TERM	4410	12/11/2007	PCC	APRON	Р	0	95,567.00	4/29/2019	12	95
AP TERM	4412	12/11/2007	PCC	APRON	Р	0	24,650.00	4/29/2019	12	97
AP TERM	4415	12/11/2007	PCC	APRON	Р	0	101,704.00	4/29/2019	12	99
AP TERM	4420	12/11/2007	PCC	APRON	Р	0	195,814.00	4/29/2019	12	
AP TERM	4425	12/11/2007	PCC	APRON	Р	0	643,219.00	4/29/2019	12	
AP TERM	4430	12/11/2007	PCC	APRON	Р	0	361,365.00	4/29/2019	12	
AP TERM	4435	12/11/2007	PCC	APRON	P	0	625,548.00	4/29/2019	12	
AP TERM	4440	12/11/2007	PCC	APRON	P	0	121,630.00	4/29/2019	12	
AP TERM	4445	1/1/1991	PCC	APRON	Р	0	312,670.00	4/29/2019	28	
RW 14-32	6205	1/1/1996	PCC	RUNWAY	l P	0	25,000.00	4/29/2019	23	
RW 14-32	6207	1/1/1996	PCC	RUNWAY	Р		50,000.00	4/29/2019	23	
						0				
RW 14-32	6210	1/1/2000	PCC	RUNWAY	Р	0	330,000.00	4/29/2019	19	
RW 14-32	6215	1/1/2000	PCC	RUNWAY	Р	0	622,500.00	4/29/2019	19	
RW 14-32	6220	1/1/1996	PCC	RUNWAY	Р	0	30,000.00	4/29/2019	23	
RW 14-32	6225	1/1/1996	PCC	RUNWAY	Р	0	60,000.00	4/29/2019	23	
RW 14-32	6230	1/1/1996	PCC	RUNWAY	Р	0	37,500.00		23	
RW 8-26	6105	1/1/1994	PCC	RUNWAY	Р	0	1,000,000.	4/29/2019	25	
RW 8-26	6110	1/1/1994	PCC	RUNWAY	Р	0	500,000.00	4/29/2019	25	83
TW A	105	1/1/1983	PCC	TAXIWAY	Р	0	54,448.00	4/29/2019	36	
TW A	110	1/1/1989	PCC	TAXIWAY	Р	0	168,750.00	4/29/2019	30	81
TW A	115	1/1/2000	PCC	TAXIWAY	Р	0	118,125.00	4/29/2019	19	84
TW A	120	1/1/1985	PCC	TAXIWAY	Р	0	271,875.00	4/29/2019	34	80
TW A	125	1/1/1994	PCC	TAXIWAY	Р	0	136,875.00	4/29/2019	25	74
TW AP	2715	1/1/1994	AC	TAXIWAY	Р	0	8,530.00	4/29/2019	25	31
TW AP	2720	1/1/2017	AAC	TAXIWAY	Р	0	10,052.00	4/29/2019	2	
TW AP	2772	1/1/1981	PCC	TAXIWAY	Р	0	33,940.00	4/29/2019	38	
TW AP	2774	1/1/1981	PCC	TAXIWAY	Р	0	50,906.00		38	
TW AP	2775	1/1/1968	PCC	TAXIWAY	Р	0	38,593.00	4/29/2019	51	48
TW AP	910	1/1/2006	AC	TAXIWAY	P	0	134,973.00	4/29/2019	13	
TW AP	915	1/1/2016	AC	TAXIWAY	P	0	8,630.00	4/29/2019	3	
TW AP	920	1/1/2016		TAXIWAY	Р	0	23,852.00		3	
<del></del>	<del>;</del>	1/1/1985	PCC	TAXIWAY	P	0		4/29/2019	34	
TW B	805 810	1/1/1905	PCC	TAXIWAY	P	0	253,320.00 136,875.00	4/29/2019	25	
						1				
TW C	1480	1/1/1994	PCC	TAXIWAY	Р	0	24,260.00	4/29/2019	25	
TW C	1490	1/1/1994	PCC	TAXIWAY	Р	0	50,660.00		25	
TW E	1670	1/1/1994	PCC	TAXIWAY	Р	0	29,143.00	4/29/2019	25	78

Section	$C_0$	ndition	R	enort
Section	VU	naiuvi	1 17	วมบา เ

TW E	1680	1/1/1985	PCC	TAXIWAY	Р	0	59,400.00	4/29/2019	34	80
TW F	1145	1/1/1985	PCC	TAXIWAY	Р	0	30,320.00	4/29/2019	34	90
TW F	1150	1/1/1985	PCC	TAXIWAY	Р	0	18,725.00	4/29/2019	34	86
TW F	1155	1/1/1968	AC	TAXIWAY	Р	0	98,961.00	4/29/2019	51	30
TW F	1170	1/1/1994	PCC	TAXIWAY	Р	0	27,436.00	4/29/2019	25	82
TW F	1175	1/1/1985	PCC	TAXIWAY	Р	0	39,074.00	4/29/2019	34	93
TW G	1020	1/1/1985	PCC	TAXIWAY	Р	0	29,478.00	4/29/2019	34	78
TW G	1025	1/1/1985	PCC	TAXIWAY	Р	0	19,138.00	4/29/2019	34	85
TW G	1030	1/1/2016	AC	TAXIWAY	Р	0	35,019.00	4/29/2019	3	89
TW G	1032	1/1/2016	AC	TAXIWAY	Р	0	44,449.00	4/29/2019	3	94
TW G	1035	1/1/2016	AC	TAXIWAY	Р	0	7,929.00	4/29/2019	3	92
TW G	1040	1/1/2016	AC	TAXIWAY	Р	0	14,096.00	4/29/2019	3	89
TW G	1045	1/1/2001	AAC	TAXIWAY	Р	0	14,480.00	4/29/2019	18	53
TW G	1060	1/1/1994	PCC	TAXIWAY	Р	0	133,822.00	4/29/2019	25	91
TW H	550	1/1/1994	PCC	TAXIWAY	Р	0	208,460.00	4/29/2019	25	88
TW H	555	1/1/1985	PCC	TAXIWAY	Р	0	127,293.00	4/29/2019	34	70
TW H	557	1/1/2007	PCC	TAXIWAY	Р	0	38,685.00	4/29/2019	12	80
TW J	740	1/1/1994	PCC	TAXIWAY	Р	0	136,242.00	4/29/2019	25	87
TW J	745	1/1/1989	PCC	TAXIWAY	Р	0	94,986.00	4/29/2019	30	82
TW J	750	1/1/1982	PCC	TAXIWAY	Р	0	21,670.00	4/29/2019	37	69
TW J	755	1/1/1968	PCC	TAXIWAY	Р	0	13,125.00	4/29/2019	51	73
TW J	760	1/1/1984	PCC	TAXIWAY	Р	0	21,750.00	4/29/2019	35	70
TW J	765	1/1/2013	PCC	TAXIWAY	Р	0	123,159.00	4/29/2019	6	97
TW K	1320	1/1/1992	PCC	TAXIWAY	Р	0	107,334.00	4/29/2019	27	85
TW L	205	1/1/1994	PCC	TAXIWAY	Р	0	25,258.00	4/29/2019	25	78
TW L	210	1/1/1983	PCC	TAXIWAY	Р	0	28,620.00	4/29/2019	36	84
TW L	215	1/1/1983	PCC	TAXIWAY	Р	0	18,195.00	4/29/2019	36	77
TW L	220	1/1/1992	PCC	TAXIWAY	Р	0	25,304.00	4/29/2019	27	83
TW L	225	1/1/1992	PCC	TAXIWAY	Р	0	52,307.00	4/29/2019	27	81
TW N	305	1/1/1992	PCC	TAXIWAY	Р	0	221,250.00	4/29/2019	27	87
TW N	310	1/1/1998	PCC	TAXIWAY	Р	0	180,075.00	4/29/2019	21	90
TW N	312	1/1/2000	PCC	TAXIWAY	Р	0	131,250.00	4/29/2019	19	89
TW N	315	1/1/1996	PCC	TAXIWAY	Р	0	45,000.00	4/29/2019	23	93
TW P	640	1/1/1982	PCC	TAXIWAY	Р	0	60,825.00	4/29/2019	37	70
TW P	641	1/1/1994	PCC	TAXIWAY	Р	0	8,909.00	4/29/2019	25	87
TW P	650	1/1/1992	PCC	TAXIWAY	Р	0	133,322.00	4/29/2019	27	96
TW P	655	1/1/1992	PCC	TAXIWAY	Р	0	79,579.00	4/29/2019	27	94
TW P	660	1/1/2013	PCC	TAXIWAY	Р	0	126,658.00	4/29/2019	6	99
TW Q	560	1/1/1996	PCC	TAXIWAY	Р	0	115,700.00	4/29/2019	23	85
TW R	570	1/1/1996	PCC	TAXIWAY	Р	0	43,767.00	4/29/2019	23	86
TW R	575	1/1/1996	PCC	TAXIWAY	Р	0	111,623.00	4/29/2019	23	88
TW R	576	1/1/1991	PCC	TAXIWAY	Р	0	29,713.00	4/29/2019	28	86
TW S	1285	1/1/1989	PCC	TAXIWAY	Р	0	140,346.00	4/29/2019	30	81
TW S	1290	1/1/1989	PCC	TAXIWAY	Р	0	28,370.00	4/29/2019	30	78
TW T	1282	1/1/2012	PCC	TAXIWAY	Р	0	59,457.00	4/29/2019	7	97
TW U	390	1/1/1998	PCC	TAXIWAY	Р	0	52,557.00	4/29/2019	21	91
TW V	905	1/1/2013	PCC	TAXIWAY	Р	0	78,127.00	4/29/2019	6	100

## **Section Condition Report (Summary)**


Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02	2	10,052.00	1	83.00	0.00	83.00
03-05	3	210,115.00	7	89.71	2.37	89.83
06-10	6	387,401.00	4	98.25	1.30	98.26
11-15	12	2,770,749.00	14	79.86	16.25	82.86
16-20	19	1,414,414.00	6	83.17	13.80	90.53
21-25	24	3,204,732.00	26	80.96	15.23	85.74
26-30	28	1,840,031.00	14	84.14	5.29	83.52
31-35	34	1,198,302.00	13	81.38	6.51	80.57
36-40	37	481,154.00	8	75.75	5.91	76.66
50+	51	235,647.00	4	49.75	15.30	41.83
ALL	24	11,752,597.00	97	81.10	14.04	83.99



# Appendix B

Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation



2019





Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	٧	Vork Cost
JAX	AP CARGO	4105	65	JT SEAL DMG	Low	279.74	Slabs	59.0%	FDOT - JOINT SEAL - PCC	13316.9	Ft	\$ 2.75	\$	36,630.00
JAX	AP CARGO	4105	74	JOINT SPALL	Low	31.08	Slabs	6.6%	FDOT - CRACK SEALING - PCC	50.9	Ft	\$ 4.25	\$	220.00
JAX	AP CARGO	4110	43	BLOCK CR	Medium	5408	SqFt	20.0%	FDOT - CRACK SEALING - AC	1648.3	Ft	\$ 3.00	\$	4,950.00
JAX	AP CARGO	4110	45	DEPRESSION	Low	832.05	SqFt	3.1%	FDOT - PATCHING - AC FULL DEPTH	952.6	SqFt	\$ 12.50	\$	11,910.00
JAX	AP CARGO	4110	52	RAVELING	Low	18719.95	SqFt	69.2%	FDOT - SURFACE SEAL	18719.5	SqFt	\$ 0.55	\$	10,300.00
JAX	AP CARGO	4110	52	RAVELING	Medium	8319.96	SqFt	30.8%	FDOT - PATCHING - AC PARTIAL DEPTH	8320.5	SqFt	\$ 5.50	\$	45,760.00
JAX	AP CARGO	4118	74	JOINT SPALL	Low	5.28	Slabs	abs 1.7% FDOT - CRACK SEALING - PCC		8.5	Ft	\$ 4.25	\$	40.00
JAX	AP CARGO	4120	66	SMALL PATCH	Medium	13.68	Slabs	ilabs 4.0% FDOT - PATCHING - PCC PARTIAL DEPTH		36.6	SqFt	\$ 72.00	\$	2,660.00
JAX	AP CARGO	4120	74	JOINT SPALL	Low	54.72	Slabs	s 16.0% FDOT - CRACK SEALING - PCC		89.9	Ft	\$ 4.25	\$	390.00
JAX	AP CARGO	4125	63	LINEAR CR	Medium	6.95	Slabs	5.3% FDOT - CRACK SEALING - PCC		173.6	Ft	\$ 4.25	\$	740.00
JAX	AP CARGO	4125	65	JT SEAL DMG	Low	76.42	Slabs	57.9%	57.9% FDOT - JOINT SEAL - PCC		Ft	\$ 2.75	\$	9,550.00
JAX	AP CARGO	4125	66	SMALL PATCH	Medium	34.74	Slabs	26.3% FDOT - PATCHING - PCC PARTIAL DEPTH		93.7	SqFt	\$ 72.00	\$	6,740.00
JAX	AP CARGO	4125	67	LARGE PATCH	Medium	13.89	Slabs	10.5%	10.5% FDOT - PATCHING - PCC FULL DEPTH		SqFt	\$ 185.00	\$	316,260.00
JAX	AP CARGO	4125	72	SHAT. SLAB	Low	3.47	Slabs	2.6%	FDOT - CRACK SEALING - PCC	173.6	Ft	\$ 4.25	\$	740.00
JAX	AP CARGO	4125	74	JOINT SPALL	Low	17.37	Slabs	13.2%	FDOT - CRACK SEALING - PCC	28.5	Ft	\$ 4.25	\$	130.00
JAX	AP CARGO	4125	75	CORNER SPALL	Low	3.47	Slabs	2.6%	FDOT - CRACK SEALING - PCC	5.6	Ft	\$ 4.25	\$	30.00
JAX	AP CARGO	4135	62	CORNER BREAK	Low	6.86	Slabs	4.8%	FDOT - CRACK SEALING - PCC	56.1	Ft	\$ 4.25	\$	240.00
JAX	AP CARGO	4135	65	JT SEAL DMG	Low	144	Slabs	100.0%	.0% FDOT - JOINT SEAL - PCC		Ft	\$ 2.75	\$	10,610.00
JAX	AP CARGO	4135	66	SMALL PATCH	Medium	10.29	Slabs	7.1%	.1% FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.00	\$	2,000.00
JAX	AP CARGO	4135	67	LARGE PATCH	Medium	6.86	Slabs	4.8% FDOT - PATCHING - PCC FULL DEPTH		505.9	SqFt	\$ 185.00	\$	93,650.00
JAX	AP CARGO	4135	72	SHAT. SLAB	Low	6.86	Slabs	4.8% FDOT - CRACK SEALING - PCC		205.7	Ft	\$ 4.25	\$	880.00
JAX	AP CARGO	4135	74	JOINT SPALL	Low	10.29	Slabs	7.1%	7.1% FDOT - CRACK SEALING - PCC		Ft	\$ 4.25	\$	80.00
JAX	AP CARGO	4135	75	CORNER SPALL	Low	10.29	Slabs	7.1%	7.1% FDOT - CRACK SEALING - PCC		Ft	\$ 4.25	\$	80.00
JAX	AP GA	5105	41	ALLIGATOR CR	Low	290.41	SqFt	0.2%	.2% FDOT - PATCHING - AC FULL DEPTH		SqFt	\$ 12.50	\$	4,540.00
JAX	AP GA	5105	45	DEPRESSION	Low	1665.39	SqFt	1.3%	1.3% FDOT - PATCHING - AC FULL DEPTH		SqFt	\$ 12.50	\$	22,930.00
JAX	AP GA	5105	45	DEPRESSION	Medium	5500.04	SqFt	4.3%	4.3% FDOT - PATCHING - AC FULL DEPTH		SqFt	\$ 12.50	\$	72,540.00
JAX	AP GA	5105	49	OIL SPILLAGE	N/A	230.56	SqFt	0.2%	0.2% FDOT - PATCHING - AC PARTIAL DEPTH		SqFt	\$ 5.50	\$	1,630.00
JAX	AP GA	5105	52	RAVELING	Low	29891.27	SqFt	23.4% FDOT - SURFACE SEAL		29891.4	SqFt	\$ 0.55	\$	16,450.00
JAX	AP GA	5110	48	L&TCR	Medium	660.6	Ft	0.3%	FDOT - CRACK SEALING - AC	660.8	Ft	\$ 3.00	\$	1,990.00
JAX	AP GA	5110	49	OIL SPILLAGE	N/A	18.3	SqFt	0.0%	FDOT - PATCHING - AC PARTIAL DEPTH	39.8	SqFt	\$ 5.50	\$	220.00
JAX	AP GA	5110	52	RAVELING	Low	48994.52	SqFt	20.5% FDOT - SURFACE SEAL		48994.1	SqFt	\$ 0.55	\$	26,950.00
JAX	AP GA	5110	52	RAVELING	Medium	10092.46	SqFt	4.2% FDOT - PATCHING - AC PARTIAL DEPTH		10092.2	SqFt	\$ 5.50	\$	55,510.00
JAX	AP GA	5115	45	DEPRESSION	Low	149.08	SqFt	0.5% FDOT - PATCHING - AC FULL DEPTH		202.4	SqFt	\$ 12.50	\$	2,530.00
JAX	AP GA	5115	52	RAVELING	Low	17295.77	SqFt	60.9% FDOT - SURFACE SEAL		17295.5	SqFt	\$ 0.55	\$	9,520.00
JAX	AP HOLD	4405	74	JOINT SPALL	Low	7.73	Slabs	1.7% FDOT - CRACK SEALING - PCC 12		12.8	Ft	\$ 4.25	\$	60.00
JAX	AP TERM	4305	66	SMALL PATCH	Medium	2.9	Slabs	5.0% FDOT - PATCHING - PCC PARTIAL DEPTH 7.5		SqFt	\$ 72.00	\$	570.00	
JAX	AP TERM	4305	74	JOINT SPALL	Low	5.8	Slabs	abs 10.0% FDOT - CRACK SEALING - PCC 9.5		Ft	\$ 4.25	\$	50.00	
JAX	AP TERM	4310	66	SMALL PATCH	Medium	11.6	Slabs	bs 5.0% FDOT - PATCHING - PCC PARTIAL DEPTH		31.2	SqFt	\$ 72.00	\$	2,250.00

2019





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	W	Vork Cost
JAX	AP TERM	4310	74	JOINT SPALL	Low	29	Slabs	12.5%	FDOT - CRACK SEALING - PCC	47.6	Ft	\$ 4.25	\$	210.00
JAX	AP TERM	4310	75	CORNER SPALL	Low	5.8	Slabs	2.5%	FDOT - CRACK SEALING - PCC	9.5	Ft	\$ 4.25	\$	50.00
JAX	AP TERM	4315	75	CORNER SPALL	Low	5.88	Slabs	2.5%	FDOT - CRACK SEALING - PCC	9.5	Ft	\$ 4.25	\$	50.00
JAX	AP TERM	4410	74	JOINT SPALL	Low	6.28	Slabs	2.5%	FDOT - CRACK SEALING - PCC	10.2	Ft	\$ 4.25	\$	50.00
JAX	AP TERM	4415	74	JOINT SPALL	Low	6.2	Slabs	2.4%	FDOT - CRACK SEALING - PCC	10.2	Ft	\$ 4.25	\$	50.00
JAX	AP TERM	4420	66	SMALL PATCH	Medium	6.45	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	17.2	SqFt	\$ 72.00	\$	1,250.00
JAX	AP TERM	4420	74	JOINT SPALL	Medium	6.45	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.00	\$	3,000.00
JAX	AP TERM	4425	74	JOINT SPALL	Low	34.77	Slabs	2.2%	FDOT - CRACK SEALING - PCC		Ft	\$ 4.25	\$	250.00
JAX	AP TERM	4425	74	JOINT SPALL	Medium	8.69	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	56	SqFt	\$ 72.00	\$	4,050.00
JAX	AP TERM	4430	63	LINEAR CR	Medium	7.22	Slabs	1.3%	FDOT - CRACK SEALING - PCC	180.8	Ft	\$ 4.25	\$	770.00
JAX	AP TERM	4430	65	JT SEAL DMG	Low	578	Slabs	100.0%	FDOT - JOINT SEAL - PCC	27604	Ft	\$ 2.75	\$	75,920.00
JAX	AP TERM	4430	66	SMALL PATCH	Medium	21.67	Slabs	3.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	58.1	SqFt	\$ 72.00	\$	4,200.00
JAX	AP TERM	4430	67	LARGE PATCH	Medium	7.22	Slabs	1.3%	FDOT - PATCHING - PCC FULL DEPTH	889.1	SqFt	\$ 185.00	\$	164,450.00
JAX	AP TERM	4430	74	JOINT SPALL	Low	101.15	Slabs	17.5%	FDOT - CRACK SEALING - PCC	166	Ft	\$ 4.25	\$	710.00
JAX	AP TERM	4430	74	JOINT SPALL	Medium	14.45	Slabs	2.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	93.7	SqFt	\$ 72.00	\$	6,720.00
JAX	AP TERM	4430	75	CORNER SPALL	Low	43.35	Slabs	7.5%	FDOT - CRACK SEALING - PCC	71.2	Ft	\$ 4.25	\$	310.00
JAX	AP TERM	4435	74	JOINT SPALL	Low	7.63	Slabs	0.5%	FDOT - CRACK SEALING - PCC		Ft	\$ 4.25	\$	60.00
JAX	AP TERM	4435	74	JOINT SPALL	Medium	7.63	Slabs	0.5%	FDOT - PATCHING - PCC PARTIAL DEPTH	49.5	SqFt	\$ 72.00	\$	3,550.00
JAX	AP TERM	4440	74	JOINT SPALL	Low	5	Slabs	1.6%	FDOT - CRACK SEALING - PCC	8.2	Ft	\$ 4.25	\$	40.00
JAX	AP TERM	4445	65	JT SEAL DMG	Low	126.58	Slabs	25.3%	FDOT - JOINT SEAL - PCC	5979.7	Ft	\$ 2.75	\$	16,450.00
JAX	AP TERM	4445	66	SMALL PATCH	Medium	37.97	Slabs	7.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	102.3	SqFt	\$ 72.00	\$	7,360.00
JAX	AP TERM	4445	74	JOINT SPALL	Low	50.63	Slabs	10.1%	FDOT - CRACK SEALING - PCC	83	Ft	\$ 4.25	\$	360.00
JAX	AP TERM	4445	74	JOINT SPALL	Medium	6.33	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	40.9	SqFt	\$ 72.00	\$	2,950.00
JAX	AP TERM	4445	75	CORNER SPALL	Low	25.32	Slabs	5.1%	FDOT - CRACK SEALING - PCC	41.7	Ft	\$ 4.25	\$	180.00
JAX	AP TERM	4445	75	CORNER SPALL	Medium	6.33	Slabs	1.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	17.2	SqFt	\$ 72.00	\$	1,230.00
JAX	RW 14-32	6205	75	CORNER SPALL	Low	2	Slabs	5.0%	FDOT - CRACK SEALING - PCC	3.3	Ft	\$ 4.25	\$	20.00
JAX	RW 14-32	6207	74	JOINT SPALL	Low	2	Slabs	2.5%	FDOT - CRACK SEALING - PCC	3.3	Ft	\$ 4.25	\$	20.00
JAX	RW 14-32	6210	74	JOINT SPALL	Low	44	Slabs	8.3%	FDOT - CRACK SEALING - PCC	72.2	Ft	\$ 4.25	\$	310.00
JAX	RW 14-32	6210	75	CORNER SPALL	Low	8	Slabs	1.5%	FDOT - CRACK SEALING - PCC	13.1	Ft	\$ 4.25	\$	60.00
JAX	RW 14-32	6215	66	SMALL PATCH	Medium	4.22	Slabs	0.4%	0.4% FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.00	\$	820.00
JAX	RW 14-32	6215	74	JOINT SPALL	Low	33.76	Slabs	3.4%	FDOT - CRACK SEALING - PCC	55.5	Ft	\$ 4.25	\$	240.00
JAX	RW 14-32	6215	75	CORNER SPALL	Low	8.44	Slabs	0.9%			Ft	\$ 4.25	\$	60.00
JAX	RW 14-32	6230	74	JOINT SPALL	Low	6	Slabs	10.0%	FDOT - CRACK SEALING - PCC	9.8	Ft	\$ 4.25	\$	50.00
JAX	RW 8-26	6105	74	JOINT SPALL	Low	15	Slabs	0.9%	FDOT - CRACK SEALING - PCC	24.6	Ft	\$ 4.25	\$	110.00
JAX	RW 8-26	6110	66	SMALL PATCH	Medium	24.39	Slabs	3.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	65.7	SqFt	\$ 72.00	\$	4,730.00
JAX	RW 8-26	6110	74	JOINT SPALL	Low	39.02	Slabs	4.9% FDOT - CRACK SEALING - PCC		64	Ft	\$ 4.25	\$	280.00
JAX	RW 8-26	6110	75	CORNER SPALL	Low	9.76	Slabs	1.2%	FDOT - CRACK SEALING - PCC	16.1	Ft	\$ 4.25	\$	70.00
JAX	TW A	105	74	JOINT SPALL	Low	15.47	Slabs	17.8%	FDOT - CRACK SEALING - PCC	25.3	Ft	\$ 4.25	\$	110.00
JAX	TW A	105	75	CORNER SPALL	Low	1.93	Slabs	2.2%	FDOT - CRACK SEALING - PCC	3.3	Ft	\$ 4.25	\$	20.00

2019





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	W	ork Cost
JAX	TW A	110	74	JOINT SPALL	Low	17.14	Slabs	6.4%	FDOT - CRACK SEALING - PCC	28.2	Ft	\$ 4.25	\$	120.00
JAX	TW A	110	75	CORNER SPALL	Low	4.29	Slabs	1.6%	FDOT - CRACK SEALING - PCC	6.9	Ft	\$ 4.25	\$	30.00
JAX	TW A	120	62	CORNER BREAK	Low	20.71	Slabs	4.8%	FDOT - CRACK SEALING - PCC	170	Ft	\$ 4.25	\$	730.00
JAX	TW A	120	66	SMALL PATCH	Medium	31.07	Slabs	7.1%	FDOT - PATCHING - PCC PARTIAL DEPTH	84	SqFt	\$ 72.00	\$	6,030.00
JAX	TW A	120	74	JOINT SPALL	Low	5.18	Slabs	1.2%	FDOT - CRACK SEALING - PCC	8.5	Ft	\$ 4.25	\$	40.00
JAX	TW A	125	74	JOINT SPALL	Low	15.64	Slabs	7.1%	FDOT - CRACK SEALING - PCC	25.6	Ft	\$ 4.25	\$	110.00
JAX	TW A	125	75	CORNER SPALL	Low	10.43	Slabs	4.8%	FDOT - CRACK SEALING - PCC	17.1	Ft	\$ 4.25	\$	80.00
JAX	TW AP	910	52	RAVELING	Low	706.44	SqFt	0.5%	FDOT - SURFACE SEAL	706.1	SqFt	\$ 0.55	\$	390.00
JAX	TW AP	910	57	WEATHERING	Medium	2379.04	SqFt	1.8%	FDOT - SURFACE SEAL	2378.8	SqFt	\$ 0.55	\$	1,310.00
JAX	TW AP	2715	41	ALLIGATOR CR	Low	62.54	SqFt	0.7%	FDOT - PATCHING - AC FULL DEPTH	98	SqFt	\$ 12.50	\$	1,230.00
JAX	TW AP	2715	43	BLOCK CR	Medium	2132.98	SqFt	25.0%	FDOT - CRACK SEALING - AC	650.3	Ft	\$ 3.00	\$	1,960.00
JAX	TW AP	2715	52	RAVELING	Low	7100.84	SqFt	83.3%	FDOT - SURFACE SEAL	7101	SqFt	\$ 0.55	\$	3,910.00
JAX	TW AP	2715	52	RAVELING	Medium	1429.12	SqFt	16.8%	FDOT - PATCHING - AC PARTIAL DEPTH	1429.5	SqFt	\$ 5.50	\$	7,870.00
JAX	TW AP	2720	52	RAVELING	Low	501.92	SqFt	5.0%	FDOT - SURFACE SEAL	501.6	SqFt	\$ 0.55	\$	280.00
JAX	TW AP	2772	66	SMALL PATCH	Medium	3.38	Slabs	6.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.6	SqFt	\$ 72.00	\$	660.00
JAX	TW AP	2772	74	JOINT SPALL	Low	16.88	Slabs	31.3%	FDOT - CRACK SEALING - PCC	27.6	Ft	\$ 4.25	\$	120.00
JAX	TW AP	2772	75	CORNER SPALL	Low	6.75	Slabs	12.5%	FDOT - CRACK SEALING - PCC	11.2	Ft	\$ 4.25	\$	50.00
JAX	TW AP	2774	65	JT SEAL DMG	Low	47.25	Slabs	58.3%	58.3% FDOT - JOINT SEAL - PCC		Ft	\$ 2.75	\$	3,490.00
JAX	TW AP	2774	66	SMALL PATCH	Medium	2.25	Slabs	2.8%	2.8% FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.00	\$	440.00
JAX	TW AP	2774	74	JOINT SPALL	Low	4.5	Slabs	5.6%	5.6% FDOT - CRACK SEALING - PCC		Ft	\$ 4.25	\$	40.00
JAX	TW AP	2775	63	LINEAR CR	Medium	2.21	Slabs	3.6%	FDOT - CRACK SEALING - PCC	55.5	Ft	\$ 4.25	\$	240.00
JAX	TW AP	2775	66	SMALL PATCH	Medium	11.07	Slabs	17.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	30.1	SqFt	\$ 72.00	\$	2,150.00
JAX	TW AP	2775	72	SHAT. SLAB	Low	2.21	Slabs	3.6%	FDOT - CRACK SEALING - PCC	110.6	Ft	\$ 4.25	\$	480.00
JAX	TW AP	2775	74	JOINT SPALL	Low	13.29	Slabs	21.4%	FDOT - CRACK SEALING - PCC	21.7	Ft	\$ 4.25	\$	100.00
JAX	TW AP	2775	74	JOINT SPALL	Medium	2.21	Slabs	3.6%	FDOT - PATCHING - PCC PARTIAL DEPTH	14	SqFt	\$ 72.00	\$	1,030.00
JAX	TW B	805	66	SMALL PATCH	Medium	25.78	Slabs	6.4%	FDOT - PATCHING - PCC PARTIAL DEPTH	68.9	SqFt	\$ 72.00	\$	5,000.00
JAX	TW B	805	75	CORNER SPALL	Low	6.44	Slabs	1.6%	FDOT - CRACK SEALING - PCC	10.5	Ft	\$ 4.25	\$	50.00
JAX	TW B	810	65	JT SEAL DMG	Low	123.19	Slabs	56.3%	FDOT - JOINT SEAL - PCC	5090.6	Ft	\$ 2.75	\$	14,000.00
JAX	TW B	810	74	JOINT SPALL	Low	9.12	Slabs	4.2%	FDOT - CRACK SEALING - PCC	15.1	Ft	\$ 4.25	\$	70.00
JAX	TW C	1480	65	JT SEAL DMG	Low	39	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1001.3	Ft	\$ 2.75	\$	2,760.00
JAX	TW C	1480	74	JOINT SPALL	Low	6.96	Slabs	17.9%	FDOT - CRACK SEALING - PCC	11.5	Ft	\$ 4.25	\$	50.00
JAX	TW C	1480	75	CORNER SPALL	Low	2.79	Slabs	7.1%	FDOT - CRACK SEALING - PCC	4.6	Ft	\$ 4.25	\$	20.00
JAX	TW C	1490	65	JT SEAL DMG	Low	81	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2935.7	Ft	\$ 2.75	\$	8,080.00
JAX	TW C	1490	66	SMALL PATCH	Medium	3.38	Slabs	4.2%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.6	SqFt	\$ 72.00	\$	660.00
JAX	TW C	1490	74	JOINT SPALL	Low	3.38	Slabs	4.2%	FDOT - CRACK SEALING - PCC	5.6	Ft	\$ 4.25	\$	30.00
JAX	TW C	1490	75	CORNER SPALL	Low	1.69	Slabs	2.1%	FDOT - CRACK SEALING - PCC	2.6	Ft	\$ 4.25	\$	20.00
JAX	TW E	1670	74	JOINT SPALL	Low	4.95	Slabs	10.5%	FDOT - CRACK SEALING - PCC	8.2	Ft	\$ 4.25	\$	40.00
JAX	TW E	1670	75	CORNER SPALL	Low	2.47	Slabs	5.3%	FDOT - CRACK SEALING - PCC	3.9	Ft	\$ 4.25	\$	20.00
JAX	TW E	1680	65	JT SEAL DMG	Low	95	Slabs	100.0%	FDOT - JOINT SEAL - PCC	2935.7	Ft	\$ 2.75	\$	8,080.00

2019





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	W	ork Cost
JAX	TW E	1680	74	JOINT SPALL	Low	2.38	Slabs	2.5%	FDOT - CRACK SEALING - PCC	3.9	Ft	\$ 4.25	\$	20.00
JAX	TW F	1150	65	JT SEAL DMG	Low	30	Slabs	100.0%	FDOT - JOINT SEAL - PCC	549.9	Ft	\$ 2.75	\$	1,520.00
JAX	TW F	1150	74	JOINT SPALL	Low	3	Slabs	10.0%	FDOT - CRACK SEALING - PCC	4.9	Ft	\$ 4.25	\$	30.00
JAX	TW F	1155	43	BLOCK CR	Medium	15364.62	SqFt	15.5%	FDOT - CRACK SEALING - AC	4683.1	Ft	\$ 3.00	\$	14,050.00
JAX	TW F	1155	45	DEPRESSION	Low	123.14	SqFt	0.1%	0.1% FDOT - PATCHING - AC FULL DEPTH		SqFt	\$ 12.50	\$	2,150.00
JAX	TW F	1155	48	L & T CR	Medium	1618.57	Ft	1.6%	FDOT - CRACK SEALING - AC	1618.4	Ft	\$ 3.00	\$	4,860.00
JAX	TW F	1155	52	RAVELING	Low	94562.78	SqFt	95.6%	FDOT - SURFACE SEAL	94563.1	SqFt	\$ 0.55	\$	52,010.00
JAX	TW F	1155	52	RAVELING	Medium	4398.24	SqFt	4.4%	FDOT - PATCHING - AC PARTIAL DEPTH	4398.1	SqFt	\$ 5.50	\$	24,200.00
JAX	TW G	1020	70	SCALING	Medium	2.95	Slabs	5.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	302.5	SqFt	\$ 72.00	\$	21,780.00
JAX	TW G	1020	74	JOINT SPALL	Low	2.95	Slabs	5.0%	FDOT - CRACK SEALING - PCC	4.9	Ft	\$ 4.25	\$	30.00
JAX	TW G	1025	74	JOINT SPALL	Low	1.55	Slabs	5.0%	FDOT - CRACK SEALING - PCC	2.6	Ft	\$ 4.25	\$	20.00
JAX	TW G	1045	41	ALLIGATOR CR	Low	120.66	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	169	SqFt	\$ 12.50	\$	2,120.00
JAX	TW G	1045	45	DEPRESSION	Low	162.86	SqFt	1.1%	FDOT - PATCHING - AC FULL DEPTH	218.5	SqFt	\$ 12.50	\$	2,730.00
JAX	TW G	1045	52	RAVELING	Low	7240.02	SqFt	50.0%	FDOT - SURFACE SEAL	7239.8	SqFt	\$ 0.55	\$	3,990.00
JAX	TW G	1060	74	JOINT SPALL	Low	7.38	Slabs	3.5%	FDOT - CRACK SEALING - PCC	12.1	Ft	\$ 4.25	\$	60.00
JAX	TW H	550	74	JOINT SPALL	Low	9.28	Slabs	2.8%	FDOT - CRACK SEALING - PCC	15.1	Ft	\$ 4.25	\$	70.00
JAX	TW H	550	75	CORNER SPALL	Low	4.64	Slabs	1.4%	FDOT - CRACK SEALING - PCC	7.6	Ft	\$ 4.25	\$	40.00
JAX	TW H	550	75	CORNER SPALL	Medium	4.64	Slabs	1.4%	FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.00	\$	900.00
JAX	TW H	555	62	CORNER BREAK	Low	14.23	Slabs	7.0%	.0% FDOT - CRACK SEALING - PCC		Ft	\$ 4.25	\$	500.00
JAX	TW H	555	66	SMALL PATCH	Medium	14.23	Slabs	7.0%	% FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.00	\$	2,760.00
JAX	TW H	555	67	LARGE PATCH	Medium	4.74	Slabs	2.3%	FDOT - PATCHING - PCC FULL DEPTH	583.4	SqFt	\$ 185.00	\$	107,990.00
JAX	TW H	555	74	JOINT SPALL	Low	9.49	Slabs	4.7%	FDOT - CRACK SEALING - PCC	15.4	Ft	\$ 4.25	\$	70.00
JAX	TW H	557	74	JOINT SPALL	Low	7.15	Slabs	11.5%	FDOT - CRACK SEALING - PCC	11.8	Ft	\$ 4.25	\$	50.00
JAX	TW H	557	75	CORNER SPALL	Low	2.38	Slabs	3.9%	FDOT - CRACK SEALING - PCC	3.9	Ft	\$ 4.25	\$	20.00
JAX	TW J	745	75	CORNER SPALL	Low	3.9	Slabs	2.6%	FDOT - CRACK SEALING - PCC	6.2	Ft	\$ 4.25	\$	30.00
JAX	TW J	750	62	CORNER BREAK	Low	1.67	Slabs	4.8%	FDOT - CRACK SEALING - PCC	13.8	Ft	\$ 4.25	\$	60.00
JAX	TW J	750	65	JT SEAL DMG	Low	35	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1250	Ft	\$ 2.75	\$	3,440.00
JAX	TW J	750	74	JOINT SPALL	Low	6.67	Slabs	19.1%	FDOT - CRACK SEALING - PCC	10.8	Ft	\$ 4.25	\$	50.00
JAX	TW J	755	66	SMALL PATCH	Medium	3	Slabs	14.3%	FDOT - PATCHING - PCC PARTIAL DEPTH	8.6	SqFt	\$ 72.00	\$	590.00
JAX	TW J	755	74	JOINT SPALL	Low	3	Slabs	14.3%	FDOT - CRACK SEALING - PCC	4.9	Ft	\$ 4.25	\$	30.00
JAX	TW J	760	65	JT SEAL DMG	Low	35	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1375	Ft	\$ 2.75	\$	3,790.00
JAX	TW J	760	66	SMALL PATCH	Medium	1.67	Slabs	4.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	4.3	SqFt	\$ 72.00	\$	330.00
JAX	TW J	760	74	JOINT SPALL	Low	3.33	Slabs	9.5%	FDOT - CRACK SEALING - PCC	5.6	Ft	\$ 4.25	\$	30.00
JAX	TW J	760	75	CORNER SPALL	Low	1.67	Slabs	4.8%	FDOT - CRACK SEALING - PCC	2.6	Ft	\$ 4.25	\$	20.00
JAX	TW J	765	74	JOINT SPALL	Low	4.38	Slabs	1.4%	FDOT - CRACK SEALING - PCC	7.2	Ft	\$ 4.25	\$	40.00
JAX	TW L	205	66	SMALL PATCH	Medium	4	Slabs	10.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	10.8	SqFt	\$ 72.00	\$	780.00
JAX	TW L	205	74	JOINT SPALL	Low	4	Slabs	10.0%	FDOT - CRACK SEALING - PCC	6.6	Ft	\$ 4.25	\$	30.00
JAX	TW L	210	74	JOINT SPALL	Low	1.92	Slabs	4.2%	FDOT - CRACK SEALING - PCC	3.3	Ft	\$ 4.25	\$	20.00
JAX	TW L	215	74	JOINT SPALL	Low	4.58	Slabs	15.8%	FDOT - CRACK SEALING - PCC	7.6	Ft	\$ 4.25	\$	40.00

2019





Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Co	st	Wo	ork Cost
JAX	TW L	215	75	CORNER SPALL	Low	1.53	Slabs	5.3%	FDOT - CRACK SEALING - PCC	2.6	Ft	\$ 4.	25	\$	20.00
JAX	TW L	225	74	JOINT SPALL	Low	21.38	Slabs	12.5%	FDOT - CRACK SEALING - PCC	35.1	Ft	\$ 4.	25	\$	150.00
JAX	TW N	305	66	SMALL PATCH	Medium	6.85	Slabs	1.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	18.3	SqFt	\$ 72.	00	\$	1,330.00
JAX	TW N	305	74	JOINT SPALL	Low	54.8	Slabs	8.0%	FDOT - CRACK SEALING - PCC	89.9	Ft	\$ 4.	25	\$	390.00
JAX	TW N	305	75	CORNER SPALL	Low	6.85	Slabs	1.0%	FDOT - CRACK SEALING - PCC	11.2	Ft	\$ 4.	25	\$	50.00
JAX	TW N	310	74	JOINT SPALL	Low	13.71	Slabs	4.8%	% FDOT - CRACK SEALING - PCC		Ft	\$ 4.	25	\$	100.00
JAX	TW N	310	74	JOINT SPALL	Medium	6.86	Slabs	2.4%	FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.	00	\$	3,190.00
JAX	TW N	315	66	SMALL PATCH	Medium	2.88	Slabs	4.0%	FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.	00	\$	560.00
JAX	TW N	315	75	CORNER SPALL	Low	2.88	Slabs	4.0%	FDOT - CRACK SEALING - PCC		Ft	\$ 4.	25	\$	30.00
JAX	TW P	640	65	JT SEAL DMG	Low	97	Slabs	100.0%	FDOT - JOINT SEAL - PCC		Ft	\$ 2.	75	\$	10,950.00
JAX	TW P	640	74	JOINT SPALL	Low	18.48	Slabs	19.1%	FDOT - CRACK SEALING - PCC		Ft	\$ 4.	25	\$	130.00
JAX	TW P	640	74	JOINT SPALL	Medium	4.62	Slabs	4.8%	FDOT - PATCHING - PCC PARTIAL DEPTH	30.1	SqFt	\$ 72.	00	\$	2,150.00
JAX	TW P	640	75	CORNER SPALL	Low	4.62	Slabs	4.8%	FDOT - CRACK SEALING - PCC	7.6	Ft	\$ 4.	25	\$	40.00
JAX	TW P	641	65	JT SEAL DMG	Low	14	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1174.9	Ft	\$ 2.	75	\$	3,240.00
JAX	TW P	650	74	JOINT SPALL	Low	11.47	Slabs	2.8%	FDOT - CRACK SEALING - PCC	18.7	Ft	\$ 4.	25	\$	80.00
JAX	TW P	650	75	CORNER SPALL	Low	5.74	Slabs	1.4%	FDOT - CRACK SEALING - PCC	9.5	Ft	\$ 4.	25	\$	40.00
JAX	TW P	655	74	JOINT SPALL	Low	6.15	Slabs	2.5%	FDOT - CRACK SEALING - PCC	10.2	Ft	\$ 4.	25	\$	50.00
JAX	TW P	660	65	JT SEAL DMG	Low	115.83	Slabs	34.8%	FDOT - JOINT SEAL - PCC	3348.4	Ft	\$ 2.	75	\$	9,210.00
JAX	TW Q	560	66	SMALL PATCH	Medium	3.89	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH	10.8	SqFt	\$ 72.	00	\$	760.00
JAX	TW Q	560	74	JOINT SPALL	Low	27.22	Slabs	13.0%	FDOT - CRACK SEALING - PCC	44.6	Ft	\$ 4.	25	\$	190.00
JAX	TW Q	560	75	CORNER SPALL	Low	15.56	Slabs	7.4%	FDOT - CRACK SEALING - PCC	25.6	Ft	\$ 4.	25	\$	110.00
JAX	TW R	570	66	SMALL PATCH	Medium	2.42	Slabs	3.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	6.5	SqFt	\$ 72.	00	\$	470.00
JAX	TW R	570	74	JOINT SPALL	Low	7.27	Slabs	9.1%	FDOT - CRACK SEALING - PCC	11.8	Ft	\$ 4.	25	\$	60.00
JAX	TW R	570	74	JOINT SPALL	Medium	2.42	Slabs	3.0%	FDOT - PATCHING - PCC PARTIAL DEPTH	16.2	SqFt	\$ 72.	00	\$	1,130.00
JAX	TW R	570	75	CORNER SPALL	Low	2.42	Slabs	3.0%	FDOT - CRACK SEALING - PCC	3.9	Ft	\$ 4.	25	\$	20.00
JAX	TW R	575	66	SMALL PATCH	Medium	3.38	Slabs	1.9%	FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.	00	\$	660.00
JAX	TW R	575	74	JOINT SPALL	Low	10.13	Slabs	5.7%	FDOT - CRACK SEALING - PCC		Ft	\$ 4.	25	\$	80.00
JAX	TW R	575	74	JOINT SPALL	Medium	3.38	Slabs	1.9%	1.9% FDOT - PATCHING - PCC PARTIAL DEPTH		SqFt	\$ 72.	00	\$	1,580.00
JAX	TW S	1285	74	JOINT SPALL	Low	27.69	Slabs	12.3%	FDOT - CRACK SEALING - PCC	45.3	Ft	\$ 4.	25	\$	200.00
JAX	TW S	1290	62	CORNER BREAK	Low	1.67	Slabs	3.7%	FDOT - CRACK SEALING - PCC	13.8	Ft	\$ 4.	25	\$	60.00
JAX	TW S	1290	74	JOINT SPALL	Low	5	Slabs	11.1% FDOT - CRACK SEALING - PCC		8.2	Ft	\$ 4.	25	\$	40.00
JAX	TW T	1282	74	JOINT SPALL	Low	3.31	Slabs	2.2%	2.2% FDOT - CRACK SEALING - PCC 5.6		Ft	\$ 4.	25	\$	30.00
JAX	TW T	1282	75	CORNER SPALL	Low	6.62	Slabs	4.4%	FDOT - CRACK SEALING - PCC	10.8	Ft	\$ 4.	25	\$	50.00
JAX	TW U	390	74	JOINT SPALL	Low	3.43	Slabs	3.6%	FDOT - CRACK SEALING - PCC	5.6	Ft	\$ 4.	25	\$	30.00





Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	JAX	AP CARGO	4110	AC	27,040	31	AC Reconstruction	\$ 379,000.00
2020	JAX	AP CARGO	4125	PCC	84,968	46	PCC Restoration	\$ 1,610,000.00
2020	JAX	AP CARGO	4135	PCC	32,378	59	PCC Restoration	\$ 551,000.00
2020	JAX	AP GA	5105	AC	127,653	47	AC Restoration	\$ 1,484,000.00
2020	JAX	AP GA	5115	AC	28,389	60	AC Restoration	\$ 313,000.00
2020	JAX	TW AP	2715	AC	8,530	28	AC Reconstruction	\$ 120,000.00
2020	JAX	TW AP	2775	PCC	38,593	46	PCC Restoration	\$ 743,000.00
2020	JAX	TW F	1155	AC	98,961	27	AC Reconstruction	\$ 1,386,000.00
2020	JAX	TW G	1045	AAC	14,480	52	AC Restoration	\$ 160,000.00
2020	JAX	TW H	555	PCC	127,293	68	PCC Restoration	\$ 2,165,000.00
2021	JAX	TW AP	2772	PCC	33,940	63	PCC Restoration	\$ 577,000.00
2022	JAX	AP GA	5110	AC	239,174	63	AC Restoration	\$ 2,631,000.00
2022	JAX	AP TERM	4430	PCC	361,365	63	PCC Restoration	\$ 6,144,000.00
2022	JAX	TW AP	910	AC	134,973	64	AC Restoration	\$ 1,485,000.00
2022	JAX	TW J	750	PCC	21,670	63	PCC Restoration	\$ 369,000.00
2022	JAX	TW J	760	PCC	21,750	64	PCC Restoration	\$ 370,000.00
2022	JAX	TW P	640	PCC	60,825	64	PCC Restoration	\$ 1,035,000.00
2024	JAX	TW A	125	PCC	136,875	64	PCC Restoration	\$ 2,327,000.00
2024	JAX	TW C	1480	PCC	24,260	63	PCC Restoration	\$ 413,000.00
2024	JAX	TW J	755	PCC	13,125	63	PCC Restoration	\$ 224,000.00
2025	JAX	TW C	1490	PCC	50,660	63	PCC Restoration	\$ 862,000.00
2026	JAX	TW L	215	PCC	18,195	64	PCC Restoration	\$ 310,000.00
2027	JAX	TW A	105	PCC	54,448	64	PCC Restoration	\$ 926,000.00
2027	JAX	TW E	1670	PCC	29,143	63	PCC Restoration	\$ 496,000.00
2027	JAX	TW G	1020	PCC	29,478	63	PCC Restoration	\$ 502,000.00
2027	JAX	TW L	205	PCC	25,258	63	PCC Restoration	\$ 430,000.00

2019






Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2027	JAX	TW S	1290	PCC	28,370	63	PCC Restoration	\$ 483,000.00
2028	JAX	AP TERM	4445	PCC	312,670	63	PCC Restoration	\$ 5,316,000.00
2028	JAX	TW A	120	PCC	271,875	64	PCC Restoration	\$ 4,622,000.00
2028	JAX	TW E	1680	PCC	59,400	64	PCC Restoration	\$ 1,010,000.00
2028	JAX	TW H	557	PCC	38,685	64	PCC Restoration	\$ 658,000.00
2029	JAX	TW A	110	PCC	168,750	63	PCC Restoration	\$ 2,869,000.00
2029	JAX	TW B	810	PCC	136,875	63	PCC Restoration	\$ 2,327,000.00
2029	JAX	TW L	225	PCC	52,307	63	PCC Restoration	\$ 890,000.00
2029	JAX	TW S	1285	PCC	140,346	63	PCC Restoration	\$ 2,386,000.00




## Appendix C

Technical Exhibits

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.







310 PCC 21 SLABS @ 25 X 25 2 14

CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2013	TW J, TW P, TW V	NEW CONSTRUCTION — PCC / 16" PCC P-501, 6" ECONOCRETE BASE P-306, 6" POROUS AGG. BLANKET, EXT. P-152
2016	AP GA, TW AP, TW G	RECONSTRUCTION - AC / FULL DEPTH MILL, BASE COURSE REHABILITATION, 4" P-401 OVERLAY
2017	TW AP	MILL AND OVERLAY

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.


PROJECTS YEAR 2022


PROJECTS YEAR 2015 PROJECTS YEAR 2016

PROJECTS YEAR 2017 PROJECTS YEAR 2018 PROJECTS YEAR 2019 PROJECTS YEAR 2020

FDOT

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.








## Appendix D

Inspection Photograph Documentation







RW 8-26, Section 6105, Sample Unit 377 - (73) Shrinkage Cracking



RW 8-26, Section 6110, Sample Unit 524 - Low Severity (67) Large Patch/Utility Cut







RW 14-32, Section 6207, Sample Unit 500 - (73) Shrinkage Cracking



RW 14-32, Section 6215, Sample Unit 102 – Low Severity (74) Joint Spall







TWA, Section 125, Sample Unit 149 - Low Severity (63) Linear Cracking and Low Severity (66) Small Patch



TWH, Section 555, Sample Unit 101 - Low Severity (62) Corner Break







TWN, Section 305, Sample Unit 134 - Low Severity (66) Small Patch



AP CARGO, Section 4125, Sample Unit 201 - Low Severity (63) Linear Cracking, Low Severity (65) Joint Seal Damage, and Low Severity (66) Small Patch.







AP GA, Section 5105, Sample Unit 89 - Medium Severity (45) Depression, Low Severity (48) Longitudinal & Transverse Cracking, and Low Severity (57) Weathering




 $AP\,TERM,\,Section\,4430,\,Sample\,\,Unit\,405\,-\,Low\,Severity\,(65)\,Joint\,Seal\,\,Damage,\,Medium\,Severity\,(66)\,Small\,\,Patch,\,Medium\,\,Severity\,(67)\,Large\,\,Patch/\,Utility\,\,Cut,\,\,and\,\,Low\,\,Severity\,\,(74)\,\,Joint\,\,Spall\,.$ 



## Appendix E

Inspection Distress Details



## **Re-Inspection Report**

**FDOT** 

JOINT SPALL

SHRINKAGE CR

74

73

Generated Date 10/3/2019 Page 1 of 99

Generat	ed Date			10/3	/2019										Page 1 of 99
Network	: JA	X					Nar	ne: JAC	KSONVILI	LE INTER	NATIONAI	AIRPORT			
Branch:	AP	CARGO		1	Name:	CARC APRC		O AIR CARGO	Use:	APRO	N	Area:	8	851,065 SqFt	
Section:	4105		of	f 6	Fre	om:	-			To:	-			Last Const.:	1/1/1989
Surface:	PCC		Family:	C9N:	59-PR-AP-P	CC	Zor	ie:		Cat	egory:			Rank: P	
Area:		296,07	0 SqFt		Length:		695 1	Ft	Width:		426 Ft				
Slabs:	474		Slab Len	gth:		25 Ft		Slab Width:		25 Ft		Joint 1	Length:	22,565 F	't
Shoulde	r:		Street Ty	pe:				Grade: 0				Lanes	: 0		
Section (	Commen	ts:													
Work D	ate: 1/1/	1989	W	ork Ty	pe: BUILT				(	Code: IM	IPORTED	Is	Major	M&R: True	
Last Ins	p. Date:	4/29/2019	)		TotalSan	nples:	24		Survey	red: 3					
Conditio	ons: Po	CI: 83													
Inspection	on Comn	nents:													
Sample 1	Number:	101	Тур	e:	R		\rea:	20	0.00 Slabs		PCI: 90				
_	Commen														
73 S	HRINKA	GE CR		N		9.00	Slabs								
	T SEAL I			L			Slabs								
74 J	OINT SP.	ALL		L		1.00	Slabs								
Sample 1	Number:	205	Тур	e:	R	A	Area:	16	5.00 Slabs		<b>PCI:</b> 79				
Sample	Commen	ts:													
73 S	HRINKA	GE CR		N		9.00	Slabs								
	OINT SP.	ALL		L		2.00	Slabs								
63 L	INEAR (	CR		L		1.00	Slabs								
65 J	T SEAL I	OMG		L		16.00	Slabs								
70 S	CALING	-		L		1.00	Slabs								
Sample	Number:	402	Тур	e:	R	A	Area:	25	5.00 Slabs		<b>PCI:</b> 81				
Sample	Commen	ts:													
67 L	ARGE P.	ATCH		L		1.00	Slabs								
66 S	MALL P	ATCH		L		7.00	Slabs								

1.00 Slabs

18.00 Slabs

L

N

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** AP CARGO CARGO AND AIR CARGO Use: APRON 851,065 SqFt Name: Area: APRONS Section: 4110 of 6 From: To: -**Last Const.:** 1/1/1994 AC C9N59-PR-AP-AC Rank: P Surface: Family: Zone: Category: 27,040 SqFt 260 Ft Width: 104 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: 0 Lanes: 0 **Section Comments:** Work Date: 1/1/1994 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 6 Surveyed: 1 **Conditions: PCI:** 33 **Inspection Comments:** Sample Number: 201 Type: R Area: 5200.00 SqFt **PCI:** 33 **Sample Comments:** 43 BLOCK CR M 1040.00 SqFt BLOCK CR 4160.00 SqFt 43 L 1600.00 SqFt RAVELING M 52

160.00 SqFt

3600.00 SqFt

L

L

DEPRESSION

RAVELING

45

52

Network:	: JAX			Name:	JACKSONVIL	LE INTERNATIONA	AL AIRPORT	
Branch:	AP CARGO		Name:	CARGO AND AI APRONS	R CARGO Use	: APRON	Area:	851,065 SqFt
Section:	4118	of	6	From: -		То: -		Last Const.: 1/1/2000
Surface:	PCC	Family: (	C9N59-PR-2	AP-PCC Zone:		Category:		Rank: P
Area:	198,05	9 SqFt	Length	429 Ft	Width:	425 Ft		
Slabs:	317	Slab Lengt	h:	25 Ft Sla	ab Width:	25 Ft	Joint Length	: 13,732 Ft
Shoulder	:	Street Type	e:	Gi	rade: 0		Lanes: 0	
Section C	Comments:							
Work Da	ite: 1/1/2000	Wor	k Type: Ne	ew Construction - Initial		Code: NU-IN	Is Major	M&R: True
Last Insp	Date: 4/29/2019	)	Tota	lSamples: 17	Surve	yed: 3		
Condition	ns: PCI: 88							
Inspection	n Comments:	Tyne	R	Area	20.00 Slabs	PCI- S	27	
Inspection Sample N		Туре:	R	Area:	20.00 Slabs	PCI: 8	37	
Inspection Sample N Sample C	n Comments:	Туре:	R L	Area:	20.00 Slabs	PCI: 8	37	
Sample N Sample C	n Comments: Number: 103 Comments:	Туре:			20.00 Slabs	PCI: 8	37	
Sample N Sample C 66 SM 73 SF	Number: 103 Comments: MALL PATCH	Туре:	L N	1.00 Slabs	20.00 Slabs 25.00 Slabs	PCI: 8		
Sample N Sample C 66 SN 73 SF Sample N	Number: 103 Comments: MALL PATCH HRINKAGE CR		L N	1.00 Slabs 15.00 Slabs				
Inspection Sample N Sample C 66 SN 73 SF Sample N Sample C	n Comments: Number: 103 Comments: MALL PATCH HRINKAGE CR Number: 200		L N	1.00 Slabs 15.00 Slabs				
Sample N Sample C 66 SM 73 SF Sample N Sample C	n Comments: Number: 103 Comments: MALL PATCH HRINKAGE CR Number: 200 Comments:		L N R	1.00 Slabs 15.00 Slabs Area:			36	
Inspection Sample N Sample C 66 SN 73 SF Sample N Sample C 73 SF Sample C	n Comments: Number: 103 Comments: MALL PATCH HRINKAGE CR Number: 200 Comments: HRINKAGE CR	Туре:	L N R	1.00 Slabs 15.00 Slabs Area: 25.00 Slabs	25.00 Slabs	PCI: {	36	
Inspection Sample N Sample C 66 SN 73 SF Sample N Sample C 73 SF Sample C Sample C	n Comments: Number: 103 Comments: MALL PATCH HRINKAGE CR Number: 200 Comments: HRINKAGE CR	Туре:	L N R	1.00 Slabs 15.00 Slabs Area: 25.00 Slabs	25.00 Slabs	PCI: {	36	

Networl	k: JAX			Name:	JACKSONVIL	LE INTERNATIONA	L AIRPORT	
Branch	: AP CARGO	)	Name:	CARGO AND AIR APRONS	CARGO Use:	APRON	Area:	851,065 SqFt
Section	: 4120	of	6 <b>F</b>	From: -		То: -		Last Const.: 1/1/1981
Surface	: PCC	Family:	C9N59-PR-AP	-PCC Zone:		Category:		Rank: P
Area:	212,5	550 SqFt	Length:	413 Ft	Width:	515 Ft		
Slabs:	342	Slab Leng	th:	25 Ft Slat	Width:	25 Ft	Joint Length	: 16,088 Ft
Shoulde	er:	Street Typ	e:	Gra	de: 0		Lanes: 0	
Section	Comments:							
Work D	Date: 1/1/1981	Wor	rk Type: BUIL	T	(	Code: IMPORTED	Is Major	M&R: True
Last Ins	sp. Date: 4/29/20	10	Totals	1 15		.1. 2		<del></del>
	sp. Date. 4/29/20	19	Totaisa	amples: 15	Survey	rea: 2		
Conditi	-		TotalSa	ampies: 15	Survey	/ea: 2		
Conditi	-		Totalsa	ampies: 15	Survey	/ea: 2		
Condition Inspecti	ons: PCI: 78			Area:	25.00 Slabs	PCI: 77	1	
Condition Inspection Sample	ons: PCI: 78			•			7	
Condition Inspection Sample Sample	ons: PCI: 78 ion Comments: Number: 301			•			,	
Condition Inspection Sample Sample 74	ons: PCI: 78 ion Comments:  Number: 301 Comments:		: R	Area: 3.00 Slabs 5.00 Slabs			1	
Condition Inspection Sample Sample 74 J 70 S 73 S	ons: PCI: 78 ion Comments: Number: 301 Comments: JOINT SPALL SCALING SHRINKAGE CR		: R  L L N	Area:  3.00 Slabs 5.00 Slabs 25.00 Slabs			7	
Condition Inspection Sample Sample 74 J 70 S 73 S	ons: PCI: 78 ion Comments:  Number: 301 Comments:  JOINT SPALL SCALING		: R	Area: 3.00 Slabs 5.00 Slabs			,	
Conditional Condit	ons: PCI: 78 ion Comments:  Number: 301 Comments:  JOINT SPALL SCALING SHRINKAGE CR		: R  L L N M	Area:  3.00 Slabs 5.00 Slabs 25.00 Slabs				
Condition Inspection Sample Sample 74 3770 5873 66 58	ons: PCI: 78 ion Comments: Number: 301 Comments: JOINT SPALL SCALING SHRINKAGE CR SMALL PATCH	Туре	: R  L L N M	Area:  3.00 Slabs 5.00 Slabs 25.00 Slabs 1.00 Slabs	25.00 Slabs	PCI: 77		
Condition Inspection Sample Sample 74 J 70 S 73 S 66 S Sample Sample Sample	ons: PCI: 78 ion Comments:  Number: 301 Comments:  JOINT SPALL SCALING SHRINKAGE CR SMALL PATCH Number: 303	Туре	: R  L L N M	Area:  3.00 Slabs 5.00 Slabs 25.00 Slabs 1.00 Slabs	25.00 Slabs	PCI: 77		
Condition Inspection Sample Sample Sample Sample Sample Sample Sample Sample 74 J	ons: PCI: 78 ion Comments: Number: 301 Comments: JOINT SPALL SCALING SHRINKAGE CR SMALL PATCH Number: 303 Comments:	Туре	: R  L L N M : R	Area:  3.00 Slabs 5.00 Slabs 25.00 Slabs 1.00 Slabs Area:	25.00 Slabs	PCI: 77		
Condition Inspection Sample Sa	ons: PCI: 78 ion Comments: Number: 301 Comments: JOINT SPALL SCALING SHRINKAGE CR SMALL PATCH Number: 303 Comments: JOINT SPALL	Туре	: R  L L N M : R	3.00 Slabs 5.00 Slabs 25.00 Slabs 1.00 Slabs  Area:	25.00 Slabs	PCI: 77		

Network:	JAX				Name:	JAC	KSONVILLI	E INTERNATIONA	AL AIRPORT		
Branch:	AP CARGO		Name:	CARC	GO AND AII ONS	R CARGO	Use:	APRON	Area:	851,065 SqFt	
Section:	4125	of 6	Fro	m:	-			То: -		Last Const.:	1/1/1968
Surface:	PCC	Family: C	9N59-PR-AP-P	CC	Zone:			Category:		Rank: P	
Area:	84,96	58 SqFt	Length:		413 Ft		Width:	200 Ft			
Slabs:	132	Slab Length	:	25 Ft	Sla	b Width:		25 Ft	Joint Lei	ngth: 5,995 F	t
Shoulder:		Street Type:			Gr	ade: 0			Lanes:	0	
Section Co		V 1									
Work Date	<b>e:</b> 1/1/1968	Work	Type: BUILT				C	ode: IMPORTED	Is M	ajor M&R: True	
Last Insp.	Date: 4/29/2019 s: PCI: 48	)	TotalSam	ples:	8		Surveye	<b>d:</b> 2			
	Comments:										
Sample Nu	umber: 201	Type:	R	A	Area:	22	.00 Slabs	PCI: 4	13		
Sample Co	omments:										
72 SH	AT. SLAB		L	1.00	Slabs						
66 SM	IALL PATCH		M	7.00	Slabs						
	RINKAGE CR		N		Slabs						
	NEAR CR		M		Slabs						
	RNER SPALL		L		Slabs						
	INT SPALL		L		Slabs						
	NEAR CR		L		Slabs						
	RGE PATCH		M								
	SEAL DMG		L		Slabs						
	IALL PATCH	Т	L R		Slabs	1.6	.00 Slabs	PCI: 5			
Sample No	umber: 405	Туре:	K	F	Area:	10	.00 Slabs	rci: 3	55		
-	RINKAGE CR		N	16.00	Slabs						
	NEAR CR		N M		Slabs						
	NEAR CR INT SPALL		M L		Slabs						
	IALL PATCH		L		Slabs						
	IALL PATCH		M	3.00							
UU SIVI	IALL FAIUT		1 <b>V1</b>	3.00	SIAUS						

Network:	: JAX				Name: JAC	CKSONVILL	E INTERNA	TIONAL	AIRPORT		
Branch:	AP CARGO		Name:	CARGO APRON	O AND AIR CARGO NS	Use:	APRON		Area:	851,065 SqFt	
Section:	4135	of	6 I	rom: -			To:	-		Last Const.:	5/1/2007
Surface:	PCC	Family:	C9N59-PR-AP	-PCC	Zone:		Categ	ory:		Rank: P	
Area:	32,37	8 SqFt	Length:		265 Ft	Width:	1	20 Ft			
Slabs:	144	Slab Leng	gth:	15 Ft	Slab Width:		15 Ft		Joint Leng	<b>gth:</b> 3,855 Ft	-
Shoulder:	:	Street Ty	pe:		Grade: 0				Lanes:	0	
Section C	Comments:	·	•								
	te: 5/1/2007	Wo	ork Type: New	Construction	n - Initial	C	ode: NU-I	N	Is Maj	or M&R: True	
Last Insp	o. Date: 4/29/2019	)	TotalS	amples: 7	,	Surveye	ed: 2				
Condition				•		v					
	n Comments:										
•	Number: 250	Тур	e: R	Aı	rea: 18	8.00 Slabs	P	PCI: 86			
Sample C	Comments:										
66 SN	MALL PATCH		L	1.00	Slabs						
73 SF	HRINKAGE CR		N	11.00	Slabs						
74 JO	DINT SPALL		L	1.00	Slabs						
65 JT	SEAL DMG		L	18.00	Slabs						
Sample N	Number: 451	Тур	e: R	Aı	rea: 24	4.00 Slabs	P	PCI: 42			
Sample C	Comments:										
67 LA	ARGE PATCH		M	2.00	Slabs						
	ORNER BREAK		L	2.00							
	MALL PATCH		M	3.00							
65 JT	SEAL DMG		L		Slabs						
	ORNER SPALL		L		Slabs						
74 JO	DINT SPALL		L	2.00	Slabs						
73 SF	HRINKAGE CR		N		Slabs						
63 LI	NEAR CR		L	10.00							
	HAT. SLAB		L	2.00							
(( C)	AALL DATESH		т	2.00	C1 1						

SMALL PATCH

66

L

Network: JAX		Name:	JACKSONVILLE INTER	RNATIONAL AIRPORT	
Branch: AP GA	Name:	GA APRON	Use: APRO	ON Area:	471,356 SqFt
Section: 4205	of 4	From: -	To	<b>:</b> -	<b>Last Const.:</b> 1/1/2016
Surface: AC	Family: C9N59-PR-AF	P-AC Zone:	Ca	ntegory:	Rank: P
<b>Area:</b> 76,	140 SqFt Length:	282 Ft	Width:	270 Ft	
Slabs:	Slab Length:	Ft Slab V	Vidth: Ft	Joint I	Length: Ft
Shoulder:	Street Type:	Grade	: 0	Lanes	: 0
<b>Section Comments:</b>					
<b>Work Date:</b> 1/1/1968	Work Type: BUII	LT	Code: IN	MPORTED Is	Major M&R: True
Work Date: 1/1/2016	Work Type: Com	plete Reconstruction - AC	Code: C	R-AC Is	Major M&R: True
Last Insp. Date: 4/29/20	019 TotalS	amples: 15	Surveyed: 2		
Conditions: PCI: 89	)				
<b>Inspection Comments:</b>					
Sample Number: 100	Type: R	Area:	6000.00 SqFt	PCI: 89	
<b>Sample Comments:</b>					
48 L & T CR	L	63.00 Ft			
57 WEATHERING	L	6000.00 SqFt			
Sample Number: 203	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 89	
<b>Sample Comments:</b>					
48 L & T CR	L	44.00 Ft			
57 WEATHERING	L	5000.00 SqFt			

Network: JAX		Name:	JACKSONVILLE	INTERNATIONA	L AIRPORT	
Branch: AP GA	Name:	GA APRON	Use:	APRON	Area:	471,356 SqFt
Section: 5105	of 4	'rom: -		То: -		<b>Last Const.:</b> 1/1/2006
Surface: AC F	Family: C9N59-PR-AP	-AC Zone:		Category:		Rank: P
<b>Area:</b> 127,653	SqFt Length:	420 Ft	Width:	225 Ft		
Slabs:	Slab Length:	Ft Slab	Width:	Ft	Joint Leng	<b>5th:</b> Ft
Shoulder:	Street Type:	Gra	<b>de:</b> 0		Lanes:	0
Section Comments:						
Work Date: 1/1/2006	Work Type: New	Construction - AC	Со	de: NC-AC	Is Ma	ior M&R: True
<b>Last Insp. Date:</b> 4/29/2019	TotalSa	amples: 28	Surveyed	1: 3		
Conditions: PCI: 49						
Inspection Comments:						
Sample Number: 089	Type: R	Area:	5747.00 SqFt	PCI: 33		
Sample Comments:			•			
41 ALLIGATOR CR	L	34.00 SqFt				
45 DEPRESSION	M	644.00 SqFt				
48 L & T CR	L	890.00 Ft				
57 WEATHERING	L	4747.00 SqFt				
52 RAVELING	L	1000.00 SqFt				
43 BLOCK CR	L	208.00 SqFt				
Sample Number: 198	Type: R	Area:	5600.00 SqFt	<b>PCI:</b> 63		
Sample Comments:						
45 DEPRESSION	L	140.00 SqFt				
48 L & T CR	L	426.00 Ft				
57 WEATHERING	L	4100.00 SqFt				
52 RAVELING	L	1500.00 SqFt				
49 OIL SPILLAGE	N	9.00 SqFt				
Sample Number: 499	Type: R	Area:	3600.00 SqFt	<b>PCI:</b> 52		
Sample Comments:						
57 WEATHERING	L	2600.00 SqFt				
48 L & T CR	L	499.00 Ft				
52 RAVELING	L	1000.00 SqFt				
49 OIL SPILLAGE	N	18.00 SqFt				
56 SWELLING	L	23.00 SqFt				
45 DEPRESSION	L	55.00 SqFt				

Netwo	ork: JAX			Name:	JACKSONVILLI	E INTERNATION	AL AIRPORT	
Branc	ch: AP GA		Name:	GA APRON	Use:	APRON	Area:	471,356 SqFt
Section	on: 5110	of 4		From: -		То: -		<b>Last Const.:</b> 1/1/2006
Surfa	ce: AC Fam	nily: C9N	N59-PR-A	AP-AC Zone:		Category:		Rank: P
Area:	239,174 SqI	Ft	Length:	925 Ft	Width:	280 Ft		
Slabs	_	ab Length:	-		Width:	Ft	Joint I	Length: Ft
Shoul		reet Type:		Grad			Lanes:	_
	on Comments:	-JF -						•
Work	<b>Date:</b> 1/1/2006	Work T	ype: Nev	w Construction - AC	Co	ode: NC-AC	Is	Major M&R: True
Last 1	Insp. Date: 4/29/2019		Total	Samples: 45	Surveyed	<b>d:</b> 5		
	itions: PCI: 68			-				
	ction Comments:							
	ole Number: 108	Type:	R	Area:	5668.00 SqFt	PCI:	74	
-	ole Comments:				•			
52	RAVELING		M	180.00 SqFt				
52	RAVELING		L	500.00 SqFt				
48 50	L & T CR PATCHING		L L	238.00 Ft 32.00 SqFt				
				-	7600 00 G-Et	DCI.		
_	ole Number: 200 ole Comments:	Type:	R	Area:	5600.00 SqFt	PCI:	68	
48	L & T CR	1	L	442.00 Ft				
57	WEATHERING		L	5096.00 SqFt				
52	RAVELING	I	L	500.00 SqFt				
50	PATCHING		L	4.00 SqFt				
Samp	ole Number: 305	Type:	R	Area:	5600.00 SqFt	PCI:	67	
Samp	ele Comments:							
48	L & T CR		M	72.00 Ft				
48	L & T CR		L	378.00 Ft				
52 52	RAVELING		L M	500.00 SqFt				
52	RAVELING		M	280.00 SqFt				
_	ole Number: 402	Type:	R	Area:	5600.00 SqFt	PCI:	72	
Samp	le Comments:							
52	RAVELING	1	M	280.00 SqFt				
52	RAVELING		L	600.00 SqFt				
48	L & T CR		L	311.00 Ft				
49	OIL SPILLAGE		N	2.00 SqFt				
_	ole Number: 507	Type:	R	Area:	3600.00 SqFt	PCI:	51	
Samp	le Comments:							
48	L & T CR	J	L	257.00 Ft				
43	BLOCK CR		L	1500.00 SqFt				
52	RAVELING		M	360.00 SqFt				
52	RAVELING	I	L	3240.00 SqFt				

Netw	ork: JAX			Name:	JACKSONVILL	E INTERNATIONA	L AIRPORT	
Bran	ch: AP GA		Name:	GA APRON	Use:	APRON	Area:	471,356 SqFt
Section	on: 5115	of 4	4	From: -		То: -		<b>Last Const.:</b> 1/1/2006
Surfa	ace: AC	Family: C	9N59-PR- <i>A</i>	AP-AC Zone:		Category:		Rank: P
Area	: 28,38	39 SqFt	Length	: 165 Ft	Width:	170 Ft		
Slabs	<b>:</b> :	Slab Length	ı:	Ft SI	lab Width:	Ft	Joint Leng	gth: Ft
Shou	lder:	Street Type	:	G	rade: 0		Lanes:	0
Section	on Comments:							
Worl	k Date: 1/1/2006	Work	Type: Ne	w Construction - AC	C	ode: NC-AC	Is Maj	jor M&R: True
Last	Insp. Date: 4/29/2019	)	Tota	Samples: 6	Surveye	ed: 2		
Cond	litions: PCI: 62							
Inspe	ection Comments:							
Samj	ole Number: 409	Type:	R	Area:	5600.00 SqFt	PCI: 64	4	
Samp	ole Comments:							
52	RAVELING		L	3400.00 SqFt				
56	SWELLING		L	292.00 SqFt				
57	WEATHERING		L	2200.00 SqFt				
48	L & T CR		L	465.00 Ft				
Samp	ole Number: 510	Type:	R	Area:	3920.00 SqFt	PCI: 59	9	
Sami	ole Comments:							
~								
52	RAVELING		L	2400.00 SqFt				
_	RAVELING SWELLING		L L	2400.00 SqFt 178.00 SqFt				
52								
52 56	SWELLING		L	178.00 SqFt				

Network	: JAX			Name:	JACKSONVILI	E INTERNATIONA	AL AIRPORT	
Branch:	AP HOLD		Name:	HOLDING APRO RWS 4, 13	ON BETWEEN Use:	APRON	Area:	150,030 SqFt
Section:	4405	of 1	l F	rom: -		То: -		<b>Last Const.:</b> 1/1/1992
Surface:	PCC	Family: C	9N59-PR-AP-	-PCC Zone:		Category:		Rank: P
Area:	150,03	30 SqFt	Length:	533 Ft	Width:	281 Ft		
Slabs:	464	Slab Length	ı:	17 Ft SI:	ab Width:	19 Ft	Joint Le	ength: 15,879 Ft
Shoulder	:	Street Type	:	G	rade: 0		Lanes:	0
Section C	Comments:							
Work Da	ite: 1/1/1992	Work	Type: BUIL	T	(	Code: IMPORTED	Is M	Iajor M&R: True
Last Insp	o. Date: 4/29/201	9	TotalSa	imples: 24	Survey	ed: 3		
Condition	ns: PCI: 85							
Inspectio	n Comments:							
Sample N	Number: 104	Type:	R	Area:	20.00 Slabs	PCI: 8	34	
Sample C	Comments:							
73 SI	HRINKAGE CR		N	20.00 Slabs				
74 JC	DINT SPALL		L	1.00 Slabs				
Sample N	Number: 301	Type:	R	Area:	20.00 Slabs	PCI: 8	34	
Sample C	Comments:							
66 SI	MALL PATCH		L	2.00 Slabs				
73 SI	HRINKAGE CR		N	20.00 Slabs				
Sample N	Number: 307	Type:	R	Area:	20.00 Slabs	PCI: 8	36	
Sample C	Comments:							
73 SI	HRINKAGE CR		N	20.00 Slabs				

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** AP TERM TERMINAL APRON Use: APRON 2,810,096 SqFt Name: Area: of 12 Section: 4305 **Last Const.:** 1/1/1985 From: To: -Surface: PCC Family: C9N59-PR-AP-PCC Zone: Category: Rank: P Area: 36,141 SqFt Length: 210 Ft Width: 180 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 2,634 Ft 58 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1985 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 79 **Inspection Comments: PCI:** 79 Sample Number: 101 Type: R 20.00 Slabs Area: **Sample Comments:** 66 SMALL PATCH M 1.00 Slabs SHRINKAGE CR N 18.00 Slabs 73

SMALL PATCH

JOINT SPALL

66

74

L

L

2.00 Slabs

Network:	JAX				Name: J.	ACKSONVILL	E INTERNATIONAL	L AIRPORT		
Branch:	AP TERM		Name:	TERMI	NAL APRON	Use:	APRON	Area:	2,810,096 SqFt	
Section: 4	4310	of 12	. Fr	om: -			То: -		Last Const.:	1/1/1985
Surface: I	PCC	Family: C9	N59-PR-AP-I	PCC	Zone:		Category:		Rank: P	
Area:	144,83	38 SqFt	Length:		580 Ft	Width:	250 Ft			
Slabs: 2	232	Slab Length:		25 Ft	Slab Widtl	n:	25 Ft	Joint Leng	<b>gth:</b> 10,770 Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Con	nments:									
Work Date:	: 1/1/1985	Work '	Гуре: BUILT	Γ		C	ode: IMPORTED	Is Maj	jor M&R: True	
G 11.1	D.CI 50	9	TotalSar	p.co.	2	Surveye	u. 2			
Conditions: Inspection (	Comments:									
Inspection (	Comments:	Туре:	R		rea:	20.00 Slabs	PCI: 76	i e		
Inspection (	Comments:			•				;		
Inspection ( Sample Nur Sample Con	Comments:	Туре:		A						
Inspection ( Sample Nur Sample Con 73 SHR 66 SMA	Comments: mber: 102 mments: ALINKAGE CR ALL PATCH	Туре:	R N M	A 20.00 2.00	rea: Slabs Slabs			i .		
Inspection ( Sample Nur Sample Con 73 SHR 66 SMA	Comments: mber: 102 mments: LINKAGE CR	Туре:	R N	A 20.00	rea: Slabs Slabs					
Inspection C Sample Nur Sample Con 73 SHR 66 SMA 74 JOIN	Comments: mber: 102 mments: EINKAGE CR ALL PATCH NT SPALL	Туре:	R N M	20.00 2.00 3.00	rea: Slabs Slabs					
Inspection C Sample Nur Sample Con 73 SHR 66 SMA 74 JOIN Sample Nur	Comments:  mber: 102  mments:  LINKAGE CR  ALL PATCH  NT SPALL  mber: 204	Туре:	R N M L	20.00 2.00 3.00	rea: Slabs Slabs Slabs	20.00 Slabs	<b>PCI:</b> 76			
Inspection C Sample Nur Sample Com 73 SHR 66 SMA 74 JOIN Sample Nur Sample Com	Comments:  mber: 102  mments:  LINKAGE CR  ALL PATCH  NT SPALL  mber: 204	Туре:	R N M L	20.00 2.00 3.00 A	rea: Slabs Slabs Slabs	20.00 Slabs	<b>PCI:</b> 76			
Inspection C Sample Nur Sample Con 73 SHR 66 SMA 74 JOIN Sample Nur Sample Con 75 COR	Comments: mber: 102 mments:  INKAGE CR ALL PATCH NT SPALL mber: 204 mments:	Туре:	R N M L R	20.00 2.00 3.00 A	rea: Slabs Slabs Slabs rea:	20.00 Slabs	<b>PCI:</b> 76			

74

JOINT SPALL

L

Netw	ork: JAX					Name:	JAC	CKSONVILL	E INTERN	NATIONAL	AIRPORT			
Bran	ch: AP TERM		Na	me:	TERM	INAL APRON		Use:	APRON	1	Area:	2,8	10,096 SqFt	
Section	on: 4315	of	12	Fro	m:	-			To:	-			Last Const.:	1/1/1985
Surfa	ice: PCC	Family:	C9N59	-PR-AP-P	CC	Zone:			Cate	egory:			Rank: P	
Area	: 146,9	50 SqFt	L	ength:		570 Ft		Width:		250 Ft				
Slabs	235	Slab Leng	gth:		25 Ft	Slab W	Vidth:		25 Ft		Joint Le	ngth:	10,580 Ft	
Shou	lder:	Street Typ	pe:			Grade	: 0				Lanes:	0		
Section	on Comments:													
Worl	<b>Cate:</b> 1/1/1985	Wo	rk Typ	e: BUILT				C	ode: IM	PORTED	Is N	Iajor N	M&R: True	
Last	Insp. Date: 4/29/201	9		TotalSam	ples:	12		Surveye	d: 2					
Cond	litions: PCI: 86				•			·						
	ection Comments:													
	ole Number: 102	Туре	e:	R	A	rea:	20	0.00 Slabs		PCI: 86				
_	ole Comments:	J.F.												
73	SHRINKAGE CR		N		12.00	Slabs								
70	SCALING		L			Slabs								
66	SMALL PATCH		L		1.00	Slabs								
75	CORNER SPALL		L		1.00	Slabs								
Samp	ole Number: 204	Туре	e:	R	A	rea:	20	0.00 Slabs		<b>PCI:</b> 86				
Samr	ole Comments:													
73	SHRINKAGE CR		N		20.00	Slabs								

Network:	JAX			Nam	ie: JACKSONVII	LE INTERNATIO	NAL AI	RPORT		
Branch:	AP TERM		Name:	TERMINAL A	APRON Use	: APRON	Ar	rea:	2,810,096 Sq	Ft
Section:	4410	of	12	From: -		То: -			Last Co	nst.: 12/11/2007
Surface:	PCC	Family:	C9N59-PR-A	P-PCC Zone	e:	Category:			Rank:	P
Area:	95,5	567 SqFt	Length:	642 Ft	t Width:	150 H	t			
Slabs:	251	Slab Lengtl	h:	20 Ft	Slab Width:	19 Ft		Joint Leng	<b>gth:</b> 9,0	91 Ft
Shoulder:		Street Type	<b>:</b>		Grade: 0			Lanes:	0	
Section Co	omments:									
Work Dot	e: 12/11/2007	Ward	Tuna. Nau	v Construction - PCC	7	Code: NC-PC		Is Ma	jor M&R: Tr	le .
WOLK Date	e: 12/11/2007	WOLL	k Type. Nev	v Construction - 1 CC				15 1114	joi wax. iii	
Last Insp.	<b>Date:</b> 4/29/20	19		Samples: 12		yed: 2		13 1714	gor Mark. Th	
Last Insp.	<b>Date:</b> 4/29/20	19						15 771	Jor Mark. 110	
Last Insp. Conditions Inspection	Date: 4/29/20 s: PCI: 95	19	Totals				95	19.77	Jor Mark. 110	
Last Insp. Conditions Inspection	Date: 4/29/20 s: PCI: 95 Comments:	19	Totals	Samples: 12	Surve	yed: 2	95		jor meet.	
Last Insp. Conditions Inspection Sample Nu Sample Co	Date: 4/29/20 s: PCI: 95 Comments:	19	Totals	Samples: 12	Surve	yed: 2	95		jor meet.	
Last Insp. Conditions Inspection Sample Nu Sample Co	Date: 4/29/20 s: PCI: 95 Comments: umber: 108	19	Totals	Samples: 12  Area:	Surve	yed: 2	95		jor meet.	
Last Insp. Conditions Inspection Sample Nu Sample Co 74 JOI 73 SH	Date: 4/29/20 s: PCI: 95 Comments: umber: 108 omments:	19	Totals R L N	Samples: 12  Area:  1.00 Slabs	Surve	yed: 2			jor meet.	
Last Insp. Conditions Inspection Sample Nu Sample Co 74 JOI 73 SH	Date: 4/29/20 s: PCI: 95 Comments: umber: 108 omments: INT SPALL RINKAGE CR	Type:	Totals R L N	Area:  1.00 Slabs 5.00 Slabs	Surve 20.00 Slabs	yed: 2 PCI:			jor meet.	

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** AP TERM Name: TERMINAL APRON Use: APRON Area: 2,810,096 SqFt Section: 4412 of 12 **Last Const.:** 12/11/2007 From: To: -PCC Surface: Family: C9N59-PR-AP-PCC Zone: Category: Rank: P Area: 24,650 SqFt Length: 125 Ft Width: 105 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 820 Ft 36 **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 12/11/2007 Work Type: New Construction - PCC Code: NC-PC Is Major M&R: True TotalSamples: 2 **Last Insp. Date:** 4/29/2019 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 97 Sample Number: 207 Type: R 26.00 Slabs Area:

**Sample Comments:** 

SHRINKAGE CR

N

4.00 Slabs

73

Network:	JAX			Name:	JACKSONVILL	E INTERNATION	AL AIRPORT		
Branch:	AP TERM		Name:	TERMINAL APRO	N Use:	APRON	Area:	2,810,096 SqFt	
Section:	4415	of	12	From: -		То: -		Last Const.: 12/1	1/2007
Surface:	PCC	Family:	C9N59-PR-A	P-PCC Zone:		Category:		Rank: P	
Area:	101	,704 SqFt	Length:	360 Ft	Width:	285 Ft			
Slabs:	254	Slab Leng	gth:	20 Ft Slab	Width:	20 Ft	Joint	<b>Length:</b> 9,615 Ft	
Shoulder:	:	Street Typ	pe:	Grad	le: 0		Lane	s: 0	
Section Co	omments:								
Work Dat	te: 12/11/2007	Wo	rk Type: New	Construction - PCC	C	ode: NC-PC	Is	Major M&R: True	
Last Insp.	. Date: 4/29/20	)19	Totals	amples: 12	Surveye	ed: 2			
Condition	s: PCI: 9	9							
Inspection	n Comments:								
Sample N	umber: 200	Туре	: R	Area:	17.00 Slabs	PCI:	99		
Sample C	omments:								
Sumple C			NT	1.00 Slabs					
-	IRINKAGE CR		N	1100 51405					
73 SH	IRINKAGE CR umber: 401	Туре		Area:	24.00 Slabs	PCI:	99		
73 SH Sample N		Туре			24.00 Slabs	PCI:	99		

Netwo	rk: JAX			N	ame: J	ACKSONVILL	E INTERNA	TIONAL	AIRPORT			
Brancl	h: AP TERM		Name	e: TERMINA	L APRON	Use:	APRON		Area:	2,81	0,096 SqFt	
Section	n: 4420	of	12	From: -			To: -				Last Const.:	12/11/2007
Surfac	ee: PCC	Family:	C9N59-PI	R-AP-PCC Z	one:		Catego	ry:			Rank: P	
Area:	195,814	4 SqFt	Leng	gth: 66	0 Ft	Width:	31	0 Ft				
Slabs:	490	Slab Lengtl	h:	20 Ft	Slab Widt	h:	20 Ft		Joint Le	ength:	19,490 Ft	
Should	ler:	Street Type	e:		Grade:	0			Lanes:	0		
Section	n Comments:											
Work	Date: 12/11/2007	Worl	k Type:	New Construction - I	PCC	C	Code: NC-P		Is M	Iajor M	I&R: True	
Last Iı	nsp. Date: 4/29/2019		To	otalSamples: 24		Surveye	ed: 4					
Condi	tions: PCI: 94											
Inspec	tion Comments:											
Sampl	e Number: 201	Type:	R	Area	:	20.00 Slabs	P	CI: 97				
Sampl	e Comments:											
73	SHRINKAGE CR		N	3.00 Slal	bs							
Sampl	e Number: 302	Type:	R	Area		20.00 Slabs	P	CI: 97				
Sampl	e Comments:											
73	SHRINKAGE CR		N	3.00 Slal	os							
Sampl	e Number: 500	Type:	R	Area	;	16.00 Slabs	P	CI: 87				
Sampl	e Comments:											
66	SMALL PATCH		L	2.00 Slal	os							
74	JOINT SPALL		M	1.00 Slal	os							
66	SMALL PATCH		M	1.00 Slal	os							
73	SHRINKAGE CR		N	2.00 Slal	os							
Sampl	e Number: 602	Type:	R	Area:	:	20.00 Slabs	P	CI: 94				
Sampl	e Comments:											
73	SHRINKAGE CR		N	8.00 Slal	ne.							

Network: JAX			Name:	JACKSONVILL	E INTERNATION	IAL AIRPOR	T
Branch: AP TERM	1	Name:	TERMINAL APRON	Use:	APRON	Area:	2,810,096 SqFt
Section: 4425 Surface: PCC	•	59-PR-A			To: - Category:		<b>Last Const.:</b> 12/11/2007 <b>Rank:</b> P
Area: 643,27 Slabs: 1,608	19 SqFt  Slab Length:	Length	: 1,020 Ft 20 Ft <b>Slab Wi</b> o	Width:	630 Ft 20 Ft	Joi	nt Length: 62,610 Ft
Shoulder:	Street Type:		Grade:	0	2011		nes: 0
Section Comments:	J.F						
Work Date: 12/11/2007	Work Ty	pe: Nev	v Construction - PCC	C	ode: NC-PC		Is Major M&R: True
<b>Last Insp. Date:</b> 4/29/201	9	Total	Samples: 89	Surveye	<b>d:</b> 9		
<b>Conditions:</b> PCI: 93							
Inspection Comments:							
Sample Number: 458	Type:	R	Area:	20.00 Slabs	PCI:	100	
<b>Sample Comments:</b>							
<no distress=""></no>							
Sample Number: 511	Type:	R	Area:	20.00 Slabs	PCI:	96	
Sample Comments:							
<ul><li>74 JOINT SPALL</li><li>73 SHRINKAGE CR</li></ul>	L N		1.00 Slabs 2.00 Slabs				
Sample Number: 555	Type:	R	Area:	20.00 Slabs	PCI:	85	
Sample Comments:	1 урс.	10	1110111	20.00 51405	1011	0.5	
73 SHRINKAGE CR	N		15.00 Slabs				
74 JOINT SPALL	M		1.00 Slabs				
Sample Number: 558	Туре:	R	Area:	20.00 Slabs	PCI:	95	
<b>Sample Comments:</b>							
73 SHRINKAGE CR	N		7.00 Slabs				
Sample Number: 602	Type:	R	Area:	20.00 Slabs	PCI:	93	
<b>Sample Comments:</b>							
73 SHRINKAGE CR	N		10.00 Slabs				
Sample Number: 610	Type:	R	Area:	20.00 Slabs	PCI:	92	
Sample Comments:							
74 JOINT SPALL	L		1.00 Slabs				
<ul><li>73 SHRINKAGE CR</li><li>66 SMALL PATCH</li></ul>	N L		1.00 Slabs 1.00 Slabs				
71 FAULTING	L		1.00 Slabs				
Sample Number: 704	Type:	R	Area:	20.00 Slabs	PCI:	89	
Sample Comments:							
73 SHRINKAGE CR	N		14.00 Slabs				
Sample Number: 759	Type:	R	Area:	20.00 Slabs	PCI:	93	
Sample Comments:							
<ul><li>73 SHRINKAGE CR</li><li>74 JOINT SPALL</li></ul>	N L		4.00 Slabs 2.00 Slabs				
66 SMALL PATCH	L		1.00 Slabs				
Sample Number: 811	Туре:	R	Area:	25.00 Slabs	PCI:	94	
Sample Comments:							
73 SHRINKAGE CR	N		10.00 Slabs				

Netwo	ork: JAX			Name:	JACKSONVILLI	EINTERNATION	IAL AIRPORT	
Branc	ch: AP TERM	N	ame: TERM	IINAL APRON	Use:	APRON	Area:	2,810,096 SqFt
Section	on: 4430	of 12	From:	-		То: -		<b>Last Const.:</b> 12/11/2007
Surfa	ce: PCC Fa	amily: C9N5	9-PR-AP-PCC	Zone:		Category:		Rank: P
Area:	361,365 \$	-	Length:	820 Ft	Width:	440 Ft		
Slabs		Slab Length:	25 Ft	Slab Wi		25 Ft	Joint Le	ength: 27,604 Ft
Shoul		Street Type:	20 11	Grade:	0	20 11	Lanes:	0
	on Comments:	street Type.		Grade.	Ü		Lancs.	·
	<b>Date:</b> 12/11/2007	Work Typ	pe: New Construction	on - PCC		ode: NC-PC	Is M	Major M&R: True
Last l	Insp. Date: 4/29/2019		TotalSamples:	36	Surveye	d: 4		
Cond	itions: PCI: 68							
Inspe	ction Comments:							
Samp	le Number: 302	Type:	R	\rea:	20.00 Slabs	PCI:	77	
_	le Comments:	. 1						
•		÷	20.00	C1 1				
65 74	JT SEAL DMG JOINT SPALL	L L		Slabs Slabs				
73	SHRINKAGE CR	N N	20.00					
75	CORNER SPALL	L	1.00	Slabs				
66	SMALL PATCH	L		Slabs				
Samp	le Number: 405	Type:	R	Area:	20.00 Slabs	PCI:	54	
_	le Comments:	• •						
_			1.00	CI I				
63 75	LINEAR CR CORNER SPALL	M L		Slabs Slabs				
66	SMALL PATCH	M M	3.00					
73	SHRINKAGE CR	N	20.00					
66	SMALL PATCH	L	2.00					
74	JOINT SPALL	L	3.00	Slabs				
74	JOINT SPALL	M	1.00	Slabs				
71	FAULTING	L	1.00	Slabs				
67	LARGE PATCH	M	1.00	Slabs				
70 65	SCALING JT SEAL DMG	L L	1.00	Slabs Slabs				
					20.00.01.1	DCI.	(0)	
	le Number: 505	Type:	R	Area:	20.00 Slabs	PCI:	69	
	le Comments:							
74	JOINT SPALL	L		Slabs				
74	JOINT SPALL	M		Slabs				
65 66	JT SEAL DMG SMALL PATCH	L L		Slabs Slabs				
73	SHRINKAGE CR	N		Slabs				
75	CORNER SPALL	L		Slabs				
Samp	le Number: 604	Type:	R	Area:	20.00 Slabs	PCI:	73	
Samp	le Comments:							
75	CORNER SPALL	L	2.00	Slabs				
73 73	SHRINKAGE CR	N N		Slabs				
70	SCALING	L		Slabs				
74	JOINT SPALL	L		Slabs				
65	JT SEAL DMG	L		Slabs				

Netwo	ork: JAX				Nan	ne: JA	CKSONVILI	LE INTERNATI	ONAL	AIRPORT			
Branc	h: AP TERM		Name	: TERN	IINAL A	APRON	Use:	APRON		Area:	2,8	10,096 SqFt	
Sectio	n: 4435	of 1	2	From:	-			То: -				Last Const.:	12/11/2007
Surfac	ce: PCC	Family: C	9N59-PR	-AP-PCC	Zon	ie:		Category	<b>:</b>			Rank: P	
Area:	625,54	8 SqFt	Leng	th:	1,040 F		Width:	600	Ft				
Slabs:	1,564	Slab Length	:	20 Ft		Slab Width	:	20 Ft		Joint Le	ength:	60,760 Ft	
Shoul	der:	Street Type:				Grade:	0			Lanes:	0		
Sectio	n Comments:												
Work	<b>Date:</b> 12/11/2007	Work	Type: N	New Constructi	on - PC	С	(	Code: NC-PC		Is N	Iajor N	1&R: True	
Last I	nsp. Date: 4/29/2019	)	To	talSamples:	86		Survey	red: 10					
Condi	itions: PCI: 88												
Inspec	ction Comments:												
Samp	le Number: 507	Type:	R	1	Area:		20.00 Slabs	PCI	: 91				
Samp	le Comments:												
73	SHRINKAGE CR		N	10.00	Slabs								
74	JOINT SPALL		L		Slabs								
Samp	le Number: 560	Type:	R		Area:		20.00 Slabs	PCI	: 85				
Samp	le Comments:												
67	LARGE PATCH		L		Slabs								
73	SHRINKAGE CR		N	16.00	Slabs								
_	le Number: 602	Type:	R	1	Area:		20.00 Slabs	PCI	: 92				
Samp	le Comments:												
73	SHRINKAGE CR		N	7.00									
67	LARGE PATCH	Trmos	L R		Slabs		20.00 Slabs	DCI	: 87				
_	le Number: 604 le Comments:	Туре:	K	1	Area:		20.00 Slaus	TCI	. 07				
_			N	19.00	C1-1-								
73	SHRINKAGE CR le Number: 609	Type:	N R		Slabs Area:		20.00 Slabs	PCI	: 84				
_	le Comments:	Type.	K	1	Ai ca.		20.00 Slaus	101	. 07				
_			N	14.00	G1 1								
73 66	SHRINKAGE CR SMALL PATCH		N L	14.00	Slabs Slabs								
74	JOINT SPALL		M		Slabs								
Samp	le Number: 661	Type:	R	1	Area:		20.00 Slabs	PCI	: 92				
Samp	le Comments:												
73	SHRINKAGE CR		N	11.00	Slabs								
Samp	le Number: 702	Type:	R	1	Area:		20.00 Slabs	PCI	: 97				
Samp	le Comments:												
67	LARGE PATCH		L	1.00	Slabs								
Samp	le Number: 754	Type:	R	1	Area:		20.00 Slabs	PCI	: 87				
Samp	le Comments:												
73	SHRINKAGE CR		N		Slabs								
70	SCALING		L		Slabs								
_	le Number: 761	Type:	R	1	Area:		25.00 Slabs	PCI	: 86				
Samp	le Comments:												
73	SHRINKAGE CR		N		Slabs								
_	le Number: 858	Type:	R	1	Area:		20.00 Slabs	PCI	: 77				
Samp	le Comments:												
67	LARGE PATCH		L		Slabs								
63 66	LINEAR CR SMALL PATCH		L L	1.00	Slabs Slabs								
73	SHRINKAGE CR		N N		Slabs								

Network:	JAX			Nam	ne: JACK	KSONVILL	E INTERNATION	AL AIRPORT			
Branch:	AP TERM		Name:	TERMINAL A	APRON	Use:	APRON	Area:	2,81	0,096 SqFt	
Section:	4440	of 12	2 F	rom: -			То: -			Last Const.:	12/11/2007
Surface:	PCC	Family: C9	N59-PR-AP-	PCC Zon	e:		Category:			Rank: P	
Area:	121,63	30 SqFt	Length:	810 F	t	Width:	150 Ft				
Slabs:	320	Slab Length:		20 Ft	Slab Width:		19 Ft	Joint	Length:	11,510 Ft	
Shoulder:		Street Type:			Grade: 0			Lanes	: 0		
Section Co	omments:										
Work Dat	e: 12/11/2007	Work	Type: New 0	Construction - PCC	2	C	Code: NC-PC	Is	Major M	I&R: True	
Last Insp.	Date: 4/29/2019	9	TotalSa	mples: 19		Surveye	ed: 4				
Condition	s: PCI: 97										
Inspection	Comments:										
Sample Nu	umber: 103	Type:	R	Area:	16.	00 Slabs	PCI:	95			
Sample Co	omments:										
73 SH	RINKAGE CR		N	3.00 Slabs							
	NT SPALL		L	1.00 Slabs							
Sample Nu	umber: 107	Type:	R	Area:	16.	00 Slabs	PCI:	97			
Sample Co	omments:										
70 SC.	ALING		L	1.00 Slabs							
73 SH	RINKAGE CR		N	1.00 Slabs							
Sample Nu	umber: 203	Type:	R	Area:	16.	00 Slabs	PCI:	97			
Sample Co	omments:										
73 SH	RINKAGE CR		N	3.00 Slabs							
Sample Nu	umber: 207	Type:	R	Area:	16.	00 Slabs	PCI:	99			
Sample Co	omments:										
73 SH	RINKAGE CR		N	1.00 Slabs							

Networ	·k: JAX				Namas	IACKCONVIII	I E INIT	EDNATIO	JAI AIDI	DODT		
Networ	·K: JAX				Name:	JACKSONVIL	LEINI	ERNATIO	NAL AIRI	PORT		
Branch	: AP TERM		Name:	TERM	INAL APRON	Use:	AP:	RON	Area	a: 2,81	0,096 SqFt	
Section	: 4445	of 12	Fr	om: -			,	То: -			Last Const.:	1/1/1991
Surface	e: PCC	Family: C9N	N59-PR-AP-I	PCC	Zone:			Category:			Rank: P	
Area:	312,670	) SqFt	Length:		875 Ft	Width:		355 Ft				
Slabs:	500	Slab Length:		25 Ft	Slab W	idth:	25	Ft		Joint Length:	23,620 Ft	
Should	er:	Street Type:			Grade:	0				Lanes: 0		
Section	Comments:	V I										
Work I	Date: 1/1/1979	Work T	ype: New C	Construction	n - PCC		Code:	NC-PC		Is Major M	&R: True	
Work I	Date: 1/1/1983	Work T	ype: New C	Construction	n - PCC		Code:	NC-PC		Is Major M	&R: True	
Work I	Date: 1/1/1991	Work T	ype: New C	Construction	n - PCC	(	Code:	NC-PC		Is Major M	&R: True	
Last In	sp. Date: 4/29/2019		TotalSaı	mples: 2	28	Survey	yed: 4					
Conditi	ions: PCI: 76											
Inspect	tion Comments:											
Sample	Number: 092	Type:	R	A	rea:	20.00 Slabs		PCI:	72			
_	e Comments:											
75	CORNER SPALL	1	M	1.00	Slabs							
73	SHRINKAGE CR	1	N	20.00	Slabs							
65	JT SEAL DMG	1	_		Slabs							
	SMALL PATCH		M		Slabs							
	JOINT SPALL			2.00	Slabs							
Sample	Number: 104	Type:	R	A	rea:	20.00 Slabs		PCI:	78			
Sample	e Comments:											
73	SHRINKAGE CR	1	N	14.00	Slabs							
74	JOINT SPALL	]	_	3.00	Slabs							
	SMALL PATCH		M		Slabs							
74	JOINT SPALL	1	M	1.00	Slabs							
Sample	Number: 403	Type:	R	A	rea:	20.00 Slabs		PCI:	78			
Sample	Comments:											
74	JOINT SPALL	1		2.00	Slabs							
	CORNER SPALL			3.00								
73	SHRINKAGE CR	1	N	20.00	Slabs							
Sample	Number: 804	Type:	R	A	rea:	19.00 Slabs		PCI:	79			
Sample	Comments:											
66	SMALL PATCH	1	M	1.00	Slabs							
	JOINT SPALL	1	_	1.00	Slabs							
73	SHRINKAGE CR	1	N	17.00								
	CORNER SPALL		_	1.00								
66	SMALL PATCH	]	: 	1.00	Slabs							

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** RW 14-32 **RUNWAY 14-32** Use: RUNWAY 1,155,000 SqFt Name: Area: Section: 6205 of 7 From: To: -**Last Const.:** 1/1/1996 Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 25,000 SqFt Length: 500 Ft Width: 50 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 40 1,450 Ft 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1996 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 82 **Inspection Comments: PCI:** 82 Sample Number: 301 Type: R 20.00 Slabs Area: **Sample Comments:** 75 CORNER SPALL L 1.00 Slabs LARGE PATCH L 5.00 Slabs 67

L

N

3.00 Slabs

1.00 Slabs

70

73

SCALING

SHRINKAGE CR

Network:	JAX				Name:	JACKSONVILI	LE INTERNATION	AL AIRPORT			
Branch:	RW 14-32		Name:	RUNW	AY 14-32	Use:	RUNWAY	Area:	1,15	55,000 SqFt	
Section:	6207	of 7	Fr	om: -			То: -			Last Const.:	1/1/1996
Surface:	PCC	Family: C9N	N59-PR-RW-	TW-PCC	Zone:		Category:			Rank: P	
Area:	50,00	00 SqFt	Length:	1,	,000 Ft	Width:	50 Ft				
Slabs:	80	Slab Length:		25 Ft	Slab	Width:	25 Ft	Join	t Length:	2,950 Ft	
Shoulder:	:	Street Type:			Grac	<b>le:</b> 0		Lan	<b>es:</b> 0		
Section Co	omments:										
Work Dat	te: 1/1/1996	Work T	ype: BUILT	Γ		(	Code: IMPORTE	)	Is Major M	I&R: True	
Last Insp.	. Date: 4/29/201	9	TotalSaı	mples: 4		Survey	red: 2				
Last Insp. Condition		9	TotalSai	mples: 4		Survey	red: 2				
Condition		9	TotalSai	mples: 4		Survey	ed: 2				
Condition	ns: PCI: 87		TotalSai		·ea:	Survey 20.00 Slabs	PCI:	91			
Condition	n Comments:  Tumber: 100	у Туре:						91			
Condition Inspection Sample No	n Comments:  Tumber: 100		R		ea:			91			
Condition Inspection Sample No Sample Co	ns: PCI: 87 n Comments: fumber: 100 comments:	Type:	R	Ar	rea: Slabs			91			
Condition Inspection Sample No Sample Co 73 SH 67 LA	ns: PCI: 87 n Comments: fumber: 100 comments:	Type:	R	3.00 S	rea: Slabs						
Condition Inspection Sample No Sample Co 73 SH 67 LA	ns: PCI: 87 n Comments: umber: 100 comments: HRINKAGE CR ARGE PATCH umber: 500	Type:	R N	3.00 S	r <b>ea:</b> Slabs Slabs	20.00 Slabs	PCI:				
Condition Inspection Sample No Sample Co 73 SH 67 LA Sample No Sample Co	ns: PCI: 87 n Comments: umber: 100 comments: HRINKAGE CR ARGE PATCH umber: 500	Type:	R N L	3.00 S	rea: Slabs Slabs rea:	20.00 Slabs	PCI:				
Condition Inspection Sample No Sample Co 73 SH 67 LA Sample No Sample Co 67 LA	n Comments: umber: 100 comments: HRINKAGE CR ARGE PATCH umber: 500 comments:	Type:	R N E	3.00 : 2.00 : Ar	rea: Slabs Slabs rea:	20.00 Slabs	PCI:				

Network: JAX		Name:	JACKSONVILLE IN	TERNATIONAL AI	RPORT
Branch: RW 14-32	Name:	RUNWAY 14-32	Use: R	UNWAY A	rea: 1,155,000 SqFt
Section: 6210	of 7 Fr	om: -		То: -	Last Const.: 1/1/2000
Surface: PCC Fami	ily: C9N59-PR-RW-	TW-PCC Zone:		Category:	Rank: P
<b>Area:</b> 330,000 SqF	-	6,600 Ft	Width:	50 Ft	
_	Length:	25 Ft Slab W		5 Ft	Joint Length: 19,750 Ft
	eet Type:	Grade:		, 11	Lanes: 0
Section Comments:	eet Type.	Graue.	Ü		Lanes. 0
Work Date: 1/1/1977	Work Type: BUILT		Code	IMPORTED	Is Major M&R: True
Work Date: 1/1/2000		e Reconstruction - PCC		SR-PC	Is Major M&R: True
<b>Last Insp. Date:</b> 4/29/2019	TotalSan	nples: 27	Surveyed:	7	
Conditions: PCI: 92					
<b>Inspection Comments:</b>					
Sample Number: 303	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 97	
Sample Comments:					
66 SMALL PATCH	L	1.00 Slabs			
73 SHRINKAGE CR	N	2.00 Slabs			
Sample Number: 308	Type: R	Area:	20.00 Slabs	PCI: 98	
Sample Comments:					
73 SHRINKAGE CR	N	2.00 Slabs			
Sample Number: 312	Type: R	Area:	20.00 Slabs	PCI: 92	
Sample Comments:					
74 JOINT SPALL	L	2.00 Slabs			
73 SHRINKAGE CR	N	2.00 Slabs			
66 SMALL PATCH	L	4.00 Slabs			
Sample Number: 316	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 96	
Sample Comments:					
73 SHRINKAGE CR	N	2.00 Slabs			
66 SMALL PATCH	L	2.00 Slabs			
Sample Number: 320	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 87	
Sample Comments:					
73 SHRINKAGE CR	N	10.00 Slabs			
66 SMALL PATCH	L	1.00 Slabs			
74 JOINT SPALL	L	3.00 Slabs			
Sample Number: 324	Type: R	Area:	20.00 Slabs	PCI: 88	
Sample Comments:					
66 SMALL PATCH	L	4.00 Slabs			
75 CORNER SPALL	L	1.00 Slabs			
<ul><li>73 SHRINKAGE CR</li><li>74 JOINT SPALL</li></ul>	N L	3.00 Slabs 3.00 Slabs			
Sample Number: 328	Type: R	Area:	12.00 Slabs	<b>PCI:</b> 86	
Sample Comments:	, p			- 22.	
-	T	2.00 - 51-1			
<ul><li>74 JOINT SPALL</li><li>75 CORNER SPALL</li></ul>	L L	3.00 Slabs 1.00 Slabs			
73 SHRINKAGE CR	N	3.00 Slabs			

Network: JAX		Name:	JACKSONVILLE IN	TERNATIONAL	AIRPORT
Branch: RW 14-32	Name:	RUNWAY 14-32	Use: RI	UNWAY	Area: 1,155,000 SqFt
Section: 6215	of 7 Fre	om: -		То: -	Last Const.: 1/1/2000
Surface: PCC Fa	amily: C9N59-PR-RW-7	TW-PCC Zone:		Category:	Rank: P
<b>Area:</b> 622,500 Se	SqFt Length:	13,200 Ft	Width:	50 Ft	
	Slab Length:	25 Ft Slab W		5 Ft	<b>Joint Length:</b> 39,550 Ft
	Street Type:	Grade:	: 0		Lanes: 0
Section Comments:					
<b>Work Date:</b> 1/1/1968	Work Type: BUILT		Code:	: IMPORTED	Is Major M&R: True
Work Date: 1/1/2000	Work Type: Surface	e Reconstruction - PCC		: SR-PC	Is Major M&R: True
<b>Last Insp. Date:</b> 4/29/2019	TotalSan	nples: 51	Surveyed:	12	
Conditions: PCI: 93					
Inspection Comments:					
Sample Number: 102	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 91	
Sample Comments:					
73 SHRINKAGE CR	N	8.00 Slabs			
74 JOINT SPALL  Sample Number: 107	Type: R	2.00 Slabs  Area:	20.00 Slabs	PCI: 97	
Sample Comments:	Type.	Aica.	20.00 51005	1 CI. 7,	
73 SHRINKAGE CR	N	4.00 Slabs			
Sample Number: 113	Type: R	Area:	20.00 Slabs	PCI: 85	
Sample Comments:	Type.	/ 11 VIII •	20.00 Since	101. 00	
73 SHRINKAGE CR	N	13.00 Slabs			
74 JOINT SPALL	L L	1.00 Slabs			
66 SMALL PATCH	M	1.00 Slabs			
Sample Number: 119	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 95	
Sample Comments:					
<ul><li>74 JOINT SPALL</li><li>73 SHRINKAGE CR</li></ul>	L N	2.00 Slabs 2.00 Slabs			
Sample Number: 123	Type: R	Area:	20.00 Slabs	PCI: 98	
Sample Comments:		131 000	20.00 2.00		
73 SHRINKAGE CR	N	2.00 Slabs			
Sample Number: 127	Type: R	Area:	16.00 Slabs	PCI: 93	
Sample Comments:	V E				
74 JOINT SPALL	L	1.00 Slabs			
75 CORNER SPALL	L	1.00 Slabs			
73 SHRINKAGE CR	N P	2.00 Slabs	20.00.01.1		
Sample Number: 505	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 94	
Sample Comments:					
73 SHRINKAGE CR	N	9.00 Slabs			
Sample Number: 510	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 94	
Sample Comments:					
73 SHRINKAGE CR	N	9.00 Slabs			
Sample Number: 515	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 90	
Sample Comments:					
<ul><li>75 CORNER SPALL</li><li>73 SHRINKAGE CR</li></ul>	L N	1.00 Slabs 9.00 Slabs			
74 JOINT SPALL	L L	1.00 Slabs			
Sample Number: 517	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 96	
Sample Comments:					

73 SHRINKAGE CR	N	5.00 Slabs			
Sample Number: 521	Type: R	Area:	20.00 Slabs	PCI: 93	
<b>Sample Comments:</b>					
73 SHRINKAGE CR	N	8.00 Slabs			
74 JOINT SPALL	L	1.00 Slabs			
Sample Number: 525	Type: R	Area:	20.00 Slabs	PCI: 95	
<b>Sample Comments:</b>					
73 SHRINKAGE CR	N	7.00 Slabs			

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** RW 14-32 **RUNWAY 14-32** Use: RUNWAY Area: 1,155,000 SqFt Name: Section: 6220 of 7 **Last Const.:** 1/1/1996 From: To: -PCC Surface: Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 30,000 SqFt Length: 600 Ft Width: 50 Ft Slabs: 48 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,750 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1996 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 89 Sample Number: 302 Type: R 16.00 Slabs Area: **Sample Comments:** SMALL PATCH L 1.00 Slabs

66

67

LARGE PATCH

L

Network: JAX		Name:	JACKSONVILLE	EINTERNATIONAL	AIRPORT	
Branch: RW 14-32	Name:	RUNWAY 14-32	Use:	RUNWAY	Area: 1	,155,000 SqFt
Section: 6225	of 7 <b>F</b>	rom: -		То: -		Last Const.: 1/1/1996
Surface: PCC	Family: C9N59-PR-RW	7-TW-PCC Zone:		Category:		Rank: P
Area: 60,0	000 SqFt Length:	1,200 Ft	Width:	50 Ft		
Slabs: 96	Slab Length:	25 Ft Slab V	Vidth:	25 Ft	Joint Length	3,550 Ft
Shoulder:	Street Type:	Grade	: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1996	Work Type: BUIL	Т	Co	ode: IMPORTED	Is Major	M&R: True
<b>Last Insp. Date:</b> 4/29/201	9 TotalSa	amples: 6	Surveyed	<b>l:</b> 2		
Conditions: PCI: 94						
Conditions: PCI: 94 Inspection Comments:						
Inspection Comments:	Type: R	Area:	16.00 Slabs	<b>PCI:</b> 96		
Inspection Comments: Sample Number: 101	Type: R	Area:	16.00 Slabs	PCI: 96		
Inspection Comments:  Sample Number: 101  Sample Comments:	Type: R	Area:	16.00 Slabs	PCI: 96		
Inspection Comments:  Sample Number: 101  Sample Comments:	<b>V1</b>		16.00 Slabs	PCI: 96		
Inspection Comments: Sample Number: 101 Sample Comments: 66 SMALL PATCH 73 SHRINKAGE CR	L	2.00 Slabs	16.00 Slabs	PCI: 96		
Inspection Comments:  Sample Number: 101  Sample Comments:  66 SMALL PATCH	L N	2.00 Slabs 2.00 Slabs				

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** RW 14-32 **RUNWAY 14-32** Use: RUNWAY Area: 1,155,000 SqFt Name: Section: 6230 of 7 **Last Const.:** 1/1/1996 From: To: -PCC Surface: Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 37,500 SqFt Length: 750 Ft Width: 50 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 60 2,200 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1996 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 90 Sample Number: 519 Type: R 20.00 Slabs Area: **Sample Comments:** 

73

74

SHRINKAGE CR

JOINT SPALL

N

L

9.00 Slabs

Netwo	ork: JAX			Name:	JACKSONVILL	E INTERNATIONA	L AIRPORT	
Branc			Name:	RUNWAY 8-26	Use:	RUNWAY	Area:	1,500,000 SqFt
Section		of 2		From: -	036.	To: -		Last Const.: 1/1/1994
Surfac				RW-TW-PCC Zone:		Category:		Rank: P
Area:		•	Lengt		Width:	100 Ft		Naiik. 1
Slabs:		Slab Length	_		Width:	25 Ft	Joint Lei	ngth: 69,900 Ft
Should	, and the second second	Street Type:		Gra		20 11	Lanes:	0
	n Comments:	-Jp-						·
	<b>Date:</b> 1/1/1994	Work	Type: B	шт		ode: IMPORTED	Is M	ajor M&R: True
							15 IVI	ajoi wiek. True
	nsp. Date: 4/29/2019	)	Tota	alSamples: 80	Surveye	e <b>d:</b> 16		
Condi								
	ction Comments:							
_	le Number: 301	Type:	R	Area:	20.00 Slabs	PCI: 88	3	
Sampl	le Comments:							
74 72	JOINT SPALL SHRINKAGE CR		L N	1.00 Slabs 13.00 Slabs				
73 Samul	le Number: 304	Type:	N R	Area:	20.00 Slabs	<b>PCI:</b> 93	<u> </u>	
_	le Comments:	1 ype:	А	Area:	20.00 51808	i C1; 93	,	
_			<b>3.</b> 7	10.00 ~ .				
73	SHRINKAGE CR	T	N	10.00 Slabs	20.00.01.1	BCI. 07	<u> </u>	
_	le Number: 308	Type:	R	Area:	20.00 Slabs	PCI: 86	)	
_	le Comments:							
73 66	SHRINKAGE CR SMALL PATCH		N L	18.00 Slabs 1.00 Slabs				
	le Number: 313	Type:	R	Area:	20.00 Slabs	<b>PCI:</b> 91		
_	le Comments:	Type.	10	711011	20.00 51465	101.	•	
_			N	11.00 (1.1				
73 66	SHRINKAGE CR SMALL PATCH		N L	11.00 Slabs 1.00 Slabs				
Sampl	le Number: 318	Type:	R	Area:	20.00 Slabs	PCI: 87	7	
Sampl	le Comments:							
73	SHRINKAGE CR		N	17.00 Slabs				
Sampl	le Number: 324	Type:	R	Area:	20.00 Slabs	PCI: 92	2	
_	le Comments:	- <b>-</b>						
66	SMALL PATCH		L	1.00 Slabs				
73	SHRINKAGE CR		N	10.00 Slabs				
Sampl	le Number: 329	Type:	R	Area:	20.00 Slabs	<b>PCI</b> : 94	1	
Sampl	le Comments:							
73	SHRINKAGE CR		N	8.00 Slabs				
Sampl	le Number: 336	Type:	R	Area:	20.00 Slabs	<b>PCI</b> : 93	3	
Sampl	le Comments:							
73	SHRINKAGE CR		N	10.00 Slabs				
Sampl	le Number: 346	Type:	R	Area:	20.00 Slabs	PCI: 93	3	
Sampl	le Comments:							
74	JOINT SPALL		L	1.00 Slabs				
73	SHRINKAGE CR		N	8.00 Slabs				
Sampl	le Number: 351	Type:	R	Area:	20.00 Slabs	<b>PCI</b> : 96	5	
Sampl	le Comments:							
73	SHRINKAGE CR		N	6.00 Slabs				
Sampl	le Number: 356	Type:	R	Area:	20.00 Slabs	PCI: 86	5	
Sampl	le Comments:							
73	SHRINKAGE CR		N	17.00 Slabs				

74	JOINT SPALL	I	_	1.00 Slabs			
Sam	ple Number: 361	Type:	R	Area:	20.00 Slabs	PCI: 85	
Sam	ple Comments:						
73	SHRINKAGE CR	1	N.	20.00 Slabs			
66	SMALL PATCH	I	_	1.00 Slabs			
Sam	ple Number: 365	Type:	R	Area:	20.00 Slabs	PCI: 86	
Sam	ple Comments:						
73	SHRINKAGE CR	1	1	20.00 Slabs			
Sam	ple Number: 369	Туре:	R	Area:	20.00 Slabs	PCI: 85	
Sam	ple Comments:						
66	SMALL PATCH	Ι	_	1.00 Slabs			
73	SHRINKAGE CR	1	1	20.00 Slabs			
Sam	ple Number: 373	Type:	R	Area:	20.00 Slabs	PCI: 86	
Sam	ple Comments:						
73	SHRINKAGE CR	1	N .	20.00 Slabs			
Sam	ple Number: 377	Type:	R	Area:	20.00 Slabs	PCI: 85	
Sam	ple Comments:						
73	SHRINKAGE CR	1	N	20.00 Slabs			
66	SMALL PATCH	I	_	1.00 Slabs			

Netwo	rk: JAX			Nan	ne: JACK	SONVILLI	E INTERNATIC	NAL AII	RPORT		
Brancl	h: RW 8-26		Name:	RUNWAY 8-	26	Use:	RUNWAY	Ar	ea: 1,5	500,000 SqFt	
Section	n: 6110	of 2	2	From: -			То: -			Last Const.:	1/1/1994
Surfac	e: PCC	Family: C	9N59-PR-I	RW-TW-PCC Zon	e:		Category:			Rank: P	
Area:	500,00	0 SqFt	Length	20,000 F	it <b>V</b>	Width:	25 F	t			
Slabs:	800	Slab Length	1:	25 Ft	Slab Width:		25 Ft		Joint Length:	19,975 F	t
Should	ler:	Street Type	:		Grade: 0				Lanes: 0		
Section	n Comments:										
Work	<b>Date:</b> 1/1/1994	Work	<b>Type:</b> BU	JILT		Co	ode: IMPORT	ED	Is Major	M&R: True	
Last II	nsp. Date: 4/29/2019	)	Tota	lSamples: 40		Surveye	<b>d:</b> 8				
Condi	tions: PCI: 83										
Inspec	tion Comments:										
Sampl	e Number: 104	Type:	R	Area:	20.0	0 Slabs	PCI:	87			
Sampl	e Comments:										
73	SHRINKAGE CR		N	17.00 Slabs							
	e Number: 120	Type:	R	Area:	20.0	0 Slabs	PCI:	81			
_	e Comments:	rype.	K	mica.	20.0	. J. Diaos	ı cı.	01			
_			_								
75 56	CORNER SPALL SMALL PATCH		L M	1.00 Slabs 1.00 Slabs							
13	SHRINKAGE CR		N N	20.00 Slabs							
	e Number: 128	Type:	R	Area:	24.0	0 Slabs	PCI:	83			
-	e Comments:	- <b>J F</b> • •									
75	CORNER SPALL		L	1.00 Slabs							
73	SHRINKAGE CR		N	24.00 Slabs							
	JOINT SPALL		L	1.00 Slabs							
_	e Number: 148	Type:	R	Area:	20.0	00 Slabs	PCI:	85			
Sampl	e Comments:										
56	SMALL PATCH		L	1.00 Slabs							
73	SHRINKAGE CR		N	20.00 Slabs							
-	e Number: 172	Type:	R	Area:	20.0	00 Slabs	PCI:	82			
Sampl	e Comments:										
56	SMALL PATCH		M	1.00 Slabs							
56	SMALL PATCH		L	1.00 Slabs							
73	SHRINKAGE CR		N	19.00 Slabs							
_	e Number: 524	Type:	R	Area:	20.0	0 Slabs	PCI:	80			
sampl	e Comments:										
73	SHRINKAGE CR		N	19.00 Slabs							
	JOINT SPALL LARGE PATCH		L L	2.00 Slabs 1.00 Slabs							
		Temar	L R		20.0	0 Slabs	PCI:	01			
-	e Number: 540	Type:	Х	Area:	20.0	o siaus	rci:	71			
_	e Comments:										
73	SHRINKAGE CR		N	7.00 Slabs							
74 56	JOINT SPALL SMALL PATCH		L L	2.00 Slabs 1.00 Slabs							
	e Number: 564	Type:	R	Area:	20.0	0 Slabs	PCI:	75			
_	e Comments:	- ) Pv-		. 11 011	20.0	1400	101.				
73	SHRINKAGE CR		N	20.00 Slabs							
73 66	SMALL PATCH		M	3.00 Slabs							
66	SMALL PATCH		L	1.00 Slabs							
74	JOINT SPALL		L	3.00 Slabs							

				_	•	_		
Netwo	rk: JAX			Name:	JACKSONVILI	LE INTERNATIONA	L AIRPORT	
Branc	h: TW A		Name:	TAXIWAY A	Use:	TAXIWAY	Area:	750,073 SqFt
Section	n: 105	of	5 I	From: -		То: -		<b>Last Const.:</b> 1/1/1983
Surfac	e: PCC	Family:	C9N59-PR-RV	V-TW-PCC Zone:		Category:		Rank: P
Area:		54,448 SqFt	Length:	875 Ft	Width:	75 Ft		
Slabs:	87	Slab Lengt	th:	25 Ft Sla	b Width:	25 Ft	Joint Lengt	<b>h:</b> 4,300 Ft
Should	ler:	Street Typ	e:	Gr	ade: 0		Lanes:	0
Section	n Comments:							
Work	<b>Date:</b> 1/1/1983	Wor	k Type: BUII	LT	(	Code: IMPORTED	Is Majo	r M&R: True
Last I	1sp. Date: 4/2	9/2019	TotalS	amples: 4	Survey	ved: 2		
Condi	tions: PCI:	79						
Inspec	tion Comments	s:						
Sampl	e Number: 10	00 Type:	: R	Area:	21.00 Slabs	PCI: 81		
Sampl	e Comments:							
73	SHRINKAGE	CR	N	21.00 Slabs				
74	JOINT SPALL		L	4.00 Slabs				
Sampl	e Number: 10	)3 Type:	: R	Area:	24.00 Slabs	PCI: 76	i	
Sampl	e Comments:							
75	CORNER SPA	LL	L	1.00 Slabs				
67	LARGE PATC	CH .	L	1.00 Slabs				
73	SHRINKAGE	CR	N	24.00 Slabs				
74	JOINT SPALL	,	L	4.00 Slabs				

Netw	ork: JAX			Name:	JACKSONVILLI	E INTERNATIONAL	AIRPORT	
Bran	ch: TW A	N	ame:	TAXIWAY A	Use:	TAXIWAY	Area:	750,073 SqFt
Secti	on: 110	of 5	Fr	om: -		То: -		<b>Last Const.:</b> 1/1/1989
Surfa	ace: PCC	Family: C9N5	9-PR-RW-	TW-PCC Zone:		Category:		Rank: P
Area	: 168,75	0 SqFt 1	Length:	2,100 Ft	Width:	75 Ft		
Slabs	s: 270	Slab Length:		25 Ft Slal	b Width:	25 Ft	Joint L	ength: 10,425 Ft
Shou	lder:	Street Type:		Gra	nde: 0		Lanes:	0
Secti	on Comments:							
Worl	k Date: 1/1/1989	Work Typ	pe: BUILT	[	Co	ode: IMPORTED	Is I	Major M&R: True
Last	Insp. Date: 4/29/2019	1	TotalSar	mples: 13	Surveye	<b>d:</b> 3		
Cond	litions: PCI: 81							
Inspe	ection Comments:							
Samı	ple Number: 106	Type:	R	Area:	21.00 Slabs	<b>PCI:</b> 81		
Samp	ple Comments:							
74	JOINT SPALL	L		1.00 Slabs				
67	LARGE PATCH	L		1.00 Slabs				
73	SHRINKAGE CR	N		21.00 Slabs				
Samp	ple Number: 110	Type:	R	Area:	21.00 Slabs	<b>PCI:</b> 79		
Samp	ple Comments:							
73	SHRINKAGE CR	N		21.00 Slabs				
66	SMALL PATCH	L		2.00 Slabs				
75	CORNER SPALL	L		1.00 Slabs				
74	JOINT SPALL	L		2.00 Slabs				
Samp	ple Number: 115	Type:	R	Area:	21.00 Slabs	PCI: 82		
Samp	ple Comments:							
74	JOINT SPALL	L		1.00 Slabs				
66	SMALL PATCH	L		3.00 Slabs				
73	SHRINKAGE CR	N		21.00 Slabs				

Network: JAX		Name:	JACKSONVILLE	E INTERNATIONAL	AIRPORT	
Branch: TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	750,073 SqFt
Section: 115	of 5	rom: -		То: -		Last Const.: 1/1/2000
Surface: PCC	Family: C9N59-PR-RW	-TW-PCC Zone:		Category:		Rank: P
<b>Area:</b> 118,1	25 SqFt Length:	1,575 Ft	Width:	75 Ft		
<b>Slabs:</b> 189	Slab Length:	25 Ft Slab	Width:	25 Ft	Joint Length	: 7,800 Ft
Shoulder:	Street Type:	Grad	<b>de:</b> 0		Lanes: 0	
<b>Section Comments:</b>						
Work Date: 1/1/1999	Work Type: BUIL	T	Co	ode: IMPORTED	Is Major	M&R: True
Work Date: 1/1/2000	Work Type: Surfa	ce Reconstruction - PCC	Co	ode: SR-PC	Is Major	M&R: True
<b>Last Insp. Date:</b> 4/29/201	9 TotalSa	mples: 9	Surveyed	d: 2		
Conditions: PCI: 84						
<b>Inspection Comments:</b>						
Sample Number: 118	Type: R	Area:	21.00 Slabs	PCI: 85		
Sample Comments:						
66 SMALL PATCH	L	1.00 Slabs				
73 SHRINKAGE CR	N	21.00 Slabs				
Sample Number: 123	Type: R	Area:	21.00 Slabs	<b>PCI:</b> 83		
<b>Sample Comments:</b>						
67 LARGE PATCH	L	1.00 Slabs				
66 SMALL PATCH	L	1.00 Slabs				
73 SHRINKAGE CR	N	19.00 Slabs				

Network: JAX		Name:	JACKSONVILL	E INTERNATIONAL	AIRPORT
Branch: TW A	Name:	TAXIWAY A	Use:	TAXIWAY	<b>Area:</b> 750,073 SqFt
Section: 120	of 5	rom: -		То: -	<b>Last Const.:</b> 1/1/1985
Surface: PCC	Family: C9N59-PR-RV	V-TW-PCC Zone:		Category:	Rank: P
Area: 271,87	75 SqFt Length:	3,670 Ft	Width:	75 Ft	
<b>Slabs:</b> 435	Slab Length:	25 Ft Slab	Width:	25 Ft	<b>Joint Length:</b> 18,275 Ft
Shoulder:	Street Type:	Grad	<b>le:</b> 0		Lanes: 0
Section Comments:					
Work Date: 1/1/1985	Work Type: BUII	T	C	ode: IMPORTED	Is Major M&R: True
Last Insp. Date: 4/29/2019	9 TotalS	amples: 21	Surveye	ed: 4	
Conditions: PCI: 80					
Inspection Comments:					
Sample Number: 128	Type: R	Area:	21.00 Slabs	PCI: 83	
Sample Comments:					
3 SHRINKAGE CR	N	14.00 Slabs			
66 SMALL PATCH	M	1.00 Slabs			
66 SMALL PATCH	L	3.00 Slabs			
4 JOINT SPALL	L	1.00 Slabs	21 00 01 1	DCI (0	
Sample Number: 135	Type: R	Area:	21.00 Slabs	<b>PCI:</b> 68	
Sample Comments:					
6 SMALL PATCH	L	2.00 Slabs			
66 SMALL PATCH	M	2.00 Slabs			
73 SHRINKAGE CR	N	17.00 Slabs			
LINEAR CR	L	2.00 Slabs			
62 CORNER BREAK	L	4.00 Slabs			
Sample Number: 141	Type: R	Area:	21.00 Slabs	<b>PCI:</b> 90	
Sample Comments:					
73 SHRINKAGE CR	N	13.00 Slabs			
Sample Number: 145	Type: R	Area:	21.00 Slabs	<b>PCI:</b> 79	
Sample Comments:					
73 SHRINKAGE CR	N	21.00 Slabs			
66 SMALL PATCH	L	3.00 Slabs			
66 SMALL PATCH	M	3.00 Slabs			

Network: JA	X				Nan	ne: JAC	KSONVILL	E INTERN	ATIONAL	AIRPORT			
Branch: TV	W A		Name:	TAXIV	VAY A		Use:	TAXIW	AY	Area:	75	50,073 SqFt	
Section: 125		of 5	Fr	om: -				To:	-			Last Const.	: 1/1/1994
Surface: PCC		Family: C9	N59-PR-RW-	-TW-PCC	Zon	e:		Cate	gory:			Rank: P	
Area:	136,875	5 SqFt	Length:	1	1,780 F	it .	Width:		75 Ft				
<b>Slabs:</b> 219		Slab Length		25 Ft		Slab Width:		25 Ft		Joint 1	Length:	8,825	Ft
Shoulder:		Street Type:				Grade: 0				Lanes	_		
Section Commen	ıte•	Street Type.				Grauc. v				Lunes			
Work Date: 1/1/	/1994	Work	Type: BUILT	Γ			C	ode: IMP	ORTED	Is	Major M	<b>1&amp;R:</b> True	
Last Insp. Date:	4/29/2019		TotalSa	mples:	10		Surveye	d· 2					
Last msp. Date.	7/27/2017		1 OtalSal	inpics.	10		Surveye	u. 2					
C I'' D	CT 74												
Conditions: P													
Conditions: P Inspection Comr													
	ments:	Type:	R	A	rea:	21	.00 Slabs		PCI: 73				
Inspection Comp	ments: : 149	Туре:	R	A	rea:	21	.00 Slabs		PCI: 73				
Sample Number Sample Commer	nents: : 149 nts:	Туре:				21	.00 Slabs		<b>PCI:</b> 73				
Inspection Comr	: 149 hts:	Туре:	N	21.00		21	.00 Slabs		PCI: 73				
Sample Number: Sample Commer 73 SHRINKA 70 SCALING	nents: : 149 nts: AGE CR	Туре:		21.00 1.00	Slabs	21	.00 Slabs		PCI: 73				
Sample Number: Sample Commer  73 SHRINKA 70 SCALING 63 LINEAR	nents: : 149 nts: AGE CR GCR	Туре:	N L	21.00 1.00	Slabs Slabs Slabs	21	.00 Slabs		PCI: 73				
Sample Number: Sample Commer  73 SHRINKA 70 SCALING 63 LINEAR 6 66 SMALL F	nents: : 149 nts: AGE CR G CR PATCH	Туре:	N L L	21.00 1.00 6.00 2.00	Slabs Slabs Slabs		.00 Slabs		PCI: 73				
Sample Number: Sample Commer  73 SHRINKA 70 SCALING 63 LINEAR	nents: : 149 nts: AGE CR CR PATCH : 155		N L L L	21.00 1.00 6.00 2.00	Slabs Slabs Slabs Slabs								
Sample Number: Sample Commer  73 SHRINKA 70 SCALING 63 LINEAR 66 SMALL F  Sample Number: Sample Commer	nents: : 149 nts: AGE CR GCR PATCH : 155		N L L L	21.00 1.00 6.00 2.00	Slabs Slabs Slabs Slabs rea:								
Sample Number: Sample Commer  73 SHRINKA 70 SCALING 63 LINEAR 66 SMALL F  Sample Number: Sample Commer  73 SHRINKA	nents: : 149 nts: AGE CR CR PATCH : 155 nts: AGE CR		N L L L R	21.00 1.00 6.00 2.00 <b>A</b>	Slabs Slabs Slabs Slabs rea:								
Sample Number: Sample Commer  73 SHRINKA 70 SCALING 63 LINEAR 66 SMALL F  Sample Number: Sample Commer  73 SHRINKA	nents: : 149 nts: AGE CR CR PATCH : 155 nts: AGE CR SPALL		N L L L R	21.00 1.00 6.00 2.00 <b>A</b> 21.00 2.00	Slabs Slabs Slabs Slabs								

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 309,476 SqFt **Branch:** TW AP TAXIWAYS WITHIN APRONS Use: TAXIWAY Name: Area: Section: 2715 of 8 **Last Const.:** 1/1/1994 From: To: Surface: AC Family: C9N59-PR-TW-AC Zone: Category: Rank: P Area: 8,530 SqFt Length: 160 Ft Width: 45 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1994 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 31 **Inspection Comments: PCI:** 31 Sample Number: 100 Type: R 4775.00 SqFt Area: **Sample Comments:** 43 BLOCK CR L 3546.00 SqFt 56 SWELLING L 239.00 SqFt BLOCK CR 1194.00 SqFt 43 M RAVELING 52 L 3975.00 SqFt

41

52

ALLIGATOR CR

RAVELING

L

M

35.00 SqFt

800.00 SqFt

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 309,476 SqFt **Branch:** TW AP TAXIWAYS WITHIN APRONS Use: TAXIWAY Name: Area: 2720 of 8 Last Const.: 1/1/2017 Section: From: To: AAC Family: C9N59-PR-TW-AC Zone: Category: Rank: P Surface: Area: 10,052 SqFt Length: 180 Ft Width: 50 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1992 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2017 Work Type: MILL and OVERLAY Code: ML-OV Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 83 Sample Number: 101 Type: Area: 4526.00 SqFt **Sample Comments:** RAVELING L 226.00 SqFt 52 L & T CR L 84.00 Ft 48

57

WEATHERING

L

4300.00 SqFt

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 309,476 SqFt **Branch:** TW AP TAXIWAYS WITHIN APRONS Use: TAXIWAY Name: Area: 2772 of 8 **Last Const.:** 1/1/1981 Section: From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 33,940 SqFt Length: 450 Ft Width: 50 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 54 1,300 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1981 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions: PCI:** 67 **Inspection Comments: PCI:** 67 Sample Number: 101 Type: R 16.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 16.00 Slabs 70 **SCALING** L 9.00 Slabs SMALL PATCH 66 L 1.00 Slabs CORNER SPALL L 2.00 Slabs

75 74

66

JOINT SPALL

SMALL PATCH

L

M

5.00

Slabs

Network: JAX		Name:	JACKSONVILLE	EINTERNATIONAL	AIRPORT	
Branch: TW AP	Name:	TAXIWAYS WITH	IIN APRONS Use:	TAXIWAY	Area: 3	09,476 SqFt
Section: 2774	of 8	rom: -		То: -		Last Const.: 1/1/1981
Surface: PCC	Family: C9N59-PR-RW	V-TW-PCC Zone:		Category:		Rank: P
<b>Area:</b> 50,9	06 SqFt Length:	450 Ft	Width:	75 Ft		
Slabs: 81	Slab Length:	25 Ft Slab	Width:	25 Ft	Joint Length:	2,175 Ft
Shoulder:	Street Type:	Grae	<b>de:</b> 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1981	Work Type: BUIL	Т	Со	ode: IMPORTED	Is Major I	M&R: True
Last Insp. Date: 4/29/201	9 TotalSa	amples: 6	Surveyed	1: 2		
•	Totalisa	impres.	Surveyee			
Conditions: PCI: 82	) I viaise	impresi 0	Surveyee			
Conditions: PCI: 82 Inspection Comments:		•				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100	Type: R	Area:	21.00 Slabs	PCI: 83		
Conditions: PCI: 82 Inspection Comments: Sample Number: 100		•				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR		Area:				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR	Type: R	Area:				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR 65 JT SEAL DMG 66 SMALL PATCH	Type: R	Area: 11.00 Slabs 21.00 Slabs 1.00 Slabs				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR 65 JT SEAL DMG 66 SMALL PATCH	Type: R  N L	Area: 11.00 Slabs 21.00 Slabs				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR 65 JT SEAL DMG 66 SMALL PATCH 66 SMALL PATCH	Type: R  N L M	Area: 11.00 Slabs 21.00 Slabs 1.00 Slabs				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR 65 JT SEAL DMG 66 SMALL PATCH 66 SMALL PATCH 74 JOINT SPALL	Type: R  N L M L	Area:  11.00 Slabs 21.00 Slabs 1.00 Slabs 2.00 Slabs				
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR 65 JT SEAL DMG 66 SMALL PATCH 66 SMALL PATCH 74 JOINT SPALL Sample Number: 102	Type: R  N L M L L L	Area:  11.00 Slabs 21.00 Slabs 1.00 Slabs 2.00 Slabs 2.00 Slabs	21.00 Slabs	PCI: 83		
Conditions: PCI: 82 Inspection Comments: Sample Number: 100 Sample Comments: 73 SHRINKAGE CR 65 JT SEAL DMG 66 SMALL PATCH 66 SMALL PATCH	Type: R  N L M L L L	Area:  11.00 Slabs 21.00 Slabs 1.00 Slabs 2.00 Slabs 2.00 Slabs	21.00 Slabs	PCI: 83		

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: Branch: TW AP TAXIWAYS WITHIN APRONS Use: TAXIWAY 309,476 SqFt Name: Area: 2775 of 8 Section: From: To: **Last Const.:** 1/1/1968 Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Rank: P Category: Area: 38,593 SqFt Length: 450 Ft Width: 75 Ft 25 Ft Slab Width: Slab Length: Joint Length: Slabs: 62 25 Ft 2,175 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1968 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 48 Sample Number: 102 Type: R 28.00 Slabs Area: **Sample Comments:** 70 SCALING L 2.00 Slabs 74 JOINT SPALL M 1.00 Slabs JOINT SPALL 74 L 6.00 Slabs 73 SHRINKAGE CR N 18.00 Slabs LINEAR CR 1.00 Slabs 63 M 66 SMALL PATCH L 5.00 Slabs 66 SMALL PATCH M 5.00 Slabs 67 LARGE PATCH L 4.00 Slabs

63

72

LINEAR CR

SHAT. SLAB

L

L

9.00 Slabs

Networl	c: JAX				Nai	me: JACK	SONVILL	E INTERNATION	AL AIRPOR	T		
Branch:	TW.	AP		Name:	TAXIWAYS	WITHIN APRON	NS Use:	TAXIWAY	Area:	3	09,476 SqFt	
Section:	910		of	8	From: -			То: -			Last Const.:	1/1/2006
Surface	: AC		Family:	C9N59-PR-T	W-AC Zoi	ne:		Category:			Rank: P	
Area:		134,97	3 SqFt	Length	: 1,245	Ft V	Width:	108 Ft				
Slabs:			Slab Leng	gth:	Ft	Slab Width:		Ft	Joi	int Length:	Ft	
Shoulde	r:		Street Typ	pe:		Grade: 0			La	nes: 0		
Section	Comments	:										
Work D	ate: 1/1/20	006	Wo	rk Type: Nev	w Construction - Ini	tial	(	Code: NU-IN		Is Major I	M&R: True	
Last Ins	p. Date:	4/29/2019	)	Total	Samples: 26		Survey	ed: 3				
Conditio	ons: PC	I: 67										
Inspecti	on Comme	nts:										
Sample	Number:	098	Туре	e: R	Area:	4970.0	00 SqFt	PCI:	65			
Sample	Comments	:										
57 V	VEATHER	ING		L	4970.00 SqFt							
48 I	& T CR			L	825.00 Ft							
Sample	Number:	103	Туре	e: R	Area:	5853.0	00 SqFt	PCI:	66			
Sample	Comments	:										
57 V	VEATHER.	ING		L	5560.00 SqFt							
48 I	& T CR			L	672.00 Ft							
57 V	VEATHER	ING		M	293.00 SqFt							
Sample	Number:	113	Туре	e: R	Area:	5800.0	00 SqFt	PCI:	69			
Sample	Comments	:										
50 F	ATCHING	Í		L	40.00 SqFt							
52 F	RAVELING	ì		L	87.00 SqFt							
57 V	VEATHER	ING		L	5673.00 SqFt							
48 I	& T CR			L	443.00 Ft							

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 309,476 SqFt Branch: TW AP TAXIWAYS WITHIN APRONS Use: TAXIWAY Name: Area: 915 of 8 **Last Const.:** 1/1/2016 Section: From: To: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Surface: Area: 8,630 SqFt Length: 190 Ft Width: 70 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2006 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2016 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 89 Sample Number: 096 Type: Area: 4675.00 SqFt **Sample Comments:** WEATHERING L 4675.00 SqFt 57

L

63.00 Ft

L & T CR

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 309,476 SqFt Branch: TW AP TAXIWAYS WITHIN APRONS Use: TAXIWAY Name: Area: 920 of 8 **Last Const.:** 1/1/2016 Section: From: To: ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Surface: Area: 23,852 SqFt Length: 210 Ft Width: 90 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2006 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2016 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 86 Sample Number: 125 Type: Area: 5665.00 SqFt **Sample Comments:** WEATHERING L 5665.00 SqFt 57

L

137.00 Ft

L & T CR

Network:	JAX			Nan	ne: JAC	CKSONVILI	E INTERN.	ATIONAI	L AIRPORT		
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIW	AY	Area:	390,195 SqFt	
Section:	805	of 2	F	rom: -			To:	-		Last Const.:	1/1/1985
Surface:	PCC	Family: C9N	159-PR-RW	-TW-PCC Zon	e:		Categ	gory:		Rank: P	
Area:	253,32	0 SqFt	Length:	3,275 F	't	Width:		75 Ft			
Slabs:	406	Slab Length:		25 Ft	Slab Width:		25 Ft		Joint Le	ength: 16,300 F	t
Shoulder:		Street Type:			Grade: 0				Lanes:	0	
Section Co	mments:										
Work Date	e: 1/1/1985	Work T	ype: BUIL	Т		(	Code: IMP	ORTED	Is M	Iajor M&R: True	
Last Insp. 1	Date: 4/29/2019	)	TotalSa	mples: 19		Survey	ed: 3				
Conditions	s: <b>PCI</b> : 82										
Inspection	Comments:										
Sample Nu	ımber: 102	Type:	R	Area:	2	1.00 Slabs		PCI: 82			
Sample Co	omments:										
75 COI	RNER SPALL	I		1.00 Slabs							
	ALL PATCH	I		1.00 Slabs							
	ALL PATCH		M	1.00 Slabs							
	RINKAGE CR		<b>N</b>	16.00 Slabs							
_	ımber: 108	Type:	R	Area:	2	1.00 Slabs		<b>PCI</b> : 86			
Sample Co	omments:										
73 SHI	RINKAGE CR	1	N	21.00 Slabs							
Sample Nu	ımber: 114	Туре:	R	Area:	2	1.00 Slabs		<b>PCI:</b> 79	1		
Sample Co	omments:										
73 SHI	RINKAGE CR	1	N	17.00 Slabs							
	ALL PATCH	N	M	3.00 Slabs							
66 SM.	ALL PATCH	I	_	6.00 Slabs							

Network	: JAX			Na	me: JACKSC	NVILLE	E INTERNATIONAL	AIRPORT			
Branch:	TW B		Name:	TAXIWAY I	3	Use:	TAXIWAY	Area:	390,195	SqFt	
Section:	810	of	2	From: -			То: -		Last	Const.:	1/1/1994
Surface:	PCC	Family:	C9N59-PR-F	RW-TW-PCC Zor	ne:		Category:		Ran	k: P	
Area:	13	36,875 SqFt	Length	1,825	Ft Wi	dth:	75 Ft				
Slabs:	219	Slab Leng	th:	25 Ft	Slab Width:		25 Ft	Joint Le	ngth:	9,050 Ft	
Shoulder	r:	Street Typ	e:		Grade: 0			Lanes:	0		
Section (	Comments:										
Work Da	fork Date: 1/1/1994 Work Type: BUILT						ode: IMPORTED	Is M	ajor M&R:	True	
Last Insi	p. Date: 4/29/	/2010	TF - 4 - 1	ICamples 10		Surveye	1. 2				
			LOTA								
	•		1 ota	lSamples: 10		Surveye	a: 2				
Conditio	ons: PCI:	81	1 ota	isamples: 10		surveye	<b>a:</b> 2				
Conditio	•	81	1 ota	isampies: 10		Surveye	<b>a:</b> 2				
Conditio Inspectio	ons: PCI:	81		Area:	27.00		PCI: 80				
Conditio Inspection Sample I	ons: PCI:	81		•							
Conditio Inspectio Sample I Sample (	ons: PCI: on Comments: Number: 119	81		•	27.00						
Conditio Inspection Sample I Sample (	ons: PCI: on Comments: Number: 119 Comments:	Type	:: R	Area:	27.00						
Condition Inspection Sample Sample Condition  65 Jr. 73 S.	ons: PCI: on Comments: Number: 119 Comments:	Type	∷ R L	Area:	27.00						
Condition Inspection Sample I Sample ( 65 Jr. 73 S. 74 Jo	ons: PCI: on Comments: Number: 119 Comments: I SEAL DMG HRINKAGE C	Type	: R L N	Area: 27.00 Slabs 27.00 Slabs	27.00						
Condition Inspection Sample Condition Sa	ons: PCI: on Comments: Number: 119 Comments: I SEAL DMG HRINKAGE C DINT SPALL	Type	E R  L  N  L  L  L	27.00 Slabs 27.00 Slabs 1.00 Slabs	27.00	Slabs					
Conditio Inspection Sample I Sample C 65 J7 73 S 74 J0 70 S Sample I	ons: PCI: on Comments: Number: 119 Comments: If SEAL DMG HRINKAGE C DINT SPALL CALING	Type	E R  L  N  L  L  L	Area:  27.00 Slabs 27.00 Slabs 1.00 Slabs 4.00 Slabs	27.00	Slabs	PCI: 80				
Condition Inspection Sample Condition	ns: PCI: on Comments: Number: 119 Comments: Γ SEAL DMG HRINKAGE C DINT SPALL CALING Number: 127	Type	E R  L  N  L  L  L	Area:  27.00 Slabs 27.00 Slabs 1.00 Slabs 4.00 Slabs	27.00	Slabs	PCI: 80				
Conditio Inspection Sample Condition Sam	Number: 119 Comments: FSEAL DMG HRINKAGE C DINT SPALL CALING Number: 127 Comments:	Type	:: R  L N L L :: R	Area:  27.00 Slabs 27.00 Slabs 1.00 Slabs 4.00 Slabs Area:	27.00	Slabs	PCI: 80				

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW C TAXIWAY C Use: TAXIWAY 74,920 SqFt Name: Area: Section: 1480 of 2 **Last Const.:** 1/1/1994 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 24,260 SqFt Length: 176 Ft Width: 90 Ft 39 Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,001 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1994 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 73 **Inspection Comments: PCI:** 73 Sample Number: 101 Type: R 28.00 Slabs Area: **Sample Comments:** 75 CORNER SPALL L 2.00 Slabs 74 JOINT SPALL L 5.00 Slabs JT SEAL DMG L 65 28.00 Slabs SHRINKAGE CR

N

L

73

70

SCALING

28.00 Slabs

Netwo	rk: JAX		Nan	ne: JACKSONVILL	E INTERNATIONA	L AIRPORT	
Brancl	h: TW C	Nai	ne: TAXIWAY C	Use:	TAXIWAY	Area:	74,920 SqFt
Section	n: 1490	of 2	From: -		То: -		<b>Last Const.:</b> 1/1/1994
Surfac	e: PCC	Family: C9N59-	PR-RW-TW-PCC Zon	e:	Category:		Rank: P
Area:	50	,660 SqFt Le	ngth: 488 F	t Width:	90 Ft		
Slabs:	81	Slab Length:	25 Ft	Slab Width:	25 Ft	Joint Length:	2,936 Ft
Should	ler:	Street Type:		Grade: 0		Lanes: 0	
Section	n Comments:						
Work	Date: 1/1/1994	Work Type	BUILT	C	Code: IMPORTED	Is Major	M&R: True
Last Ir	rsp. Date: 4/29/20	)19	TotalSamples: 4	Survey	ed: 2		
Condit	tions: PCI: 7	5	-				
Inspec	tion Comments:						
	e Number: 100	Type:	Area:	28.00 Slabs	PCI: 72	<u> </u>	
	e Comments:	••					
73	SHRINKAGE CR	N	28.00 Slabs				
	SMALL PATCH	M	2.00 Slabs				
74	JOINT SPALL	L	2.00 Slabs				
75	CORNER SPALL	L	1.00 Slabs				
70	SCALING	L	14.00 Slabs				
	JT SEAL DMG	L	28.00 Slabs				
65					DCI. 70	`	
	e Number: 102	Type:	Area:	20.00 Slabs	<b>PCI:</b> 79	,	
Sample	e Number: 102 e Comments:	Type:	Area:	20.00 Slabs	PCI: /9	,	
Sample Sample		Type: 1	Area:	20.00 Slabs	PCI: /9	,	
Sample Sample	e Comments:	••		20.00 Slabs	PCI: /9	,	

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 88,543 SqFt **Branch:** TW E TAXIWAY E Use: TAXIWAY Name: Area: Section: 1670 of 2 **Last Const.:** 1/1/1994 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 29,143 SqFt Length: 176 Ft Width: 90 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,001 Ft 47 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1994 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions: PCI:** 78 **Inspection Comments: PCI:** 78 Sample Number: 100 Type: R 19.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 19.00 Slabs 70 SCALING L 2.00 Slabs CORNER SPALL L 1.00 Slabs 75

JOINT SPALL

74

L

Network:	JAX			Name:	JACKSONVILL	E INTERNATIONA	L AIRPORT	
Branch:	TW E		Name:	TAXIWAY E	Use:	TAXIWAY	Area:	88,543 SqFt
Section:	1680	of	2 F	rom: -		То: -		<b>Last Const.:</b> 1/1/1985
Surface:	PCC	Family:	C9N59-PR-RW	-TW-PCC Zone:		Category:		Rank: P
Area:	59	9,400 SqFt	Length:	488 Ft	Width:	90 Ft		
Slabs:	95	Slab Lengt	th:	25 Ft Sla	b Width:	25 Ft	Joint Length:	2,936 Ft
Shoulder:	:	Street Typ	e:	Gra	ade: 0		Lanes: 0	
Section C	Comments:							
Work Da	te: 1/1/1985	Wor	k Type: New (	Construction - Initial	C	ode: NU-IN	Is Major	M&R: True
Last Insp	Date: 4/29/2	2019	TotalSa	mples: 8	Surveye	<b>d:</b> 2		
Condition	ns: PCI: 8	80						
Inspection	n Comments:							
	n Comments:	Type	: R	Area:	20.00 Slabs	PCI: 8	1	
Sample N		Туре	: R	Area:	20.00 Slabs	PCI: 8	1	
Sample N	Number: 100	Туре	: R	Area:	20.00 Slabs	PCI: 8	1	
Sample N Sample C	Number: 100	Туре			20.00 Slabs	PCI: 8	1	
Sample N Sample C 70 SC 65 JT	Tumber: 100 Comments:		L	5.00 Slabs	20.00 Slabs	PCI: 8	1	
Sample N Sample C 70 SC 65 JT 73 SF	Number: 100 Comments: CALING SEAL DMG		L L N	5.00 Slabs 20.00 Slabs	20.00 Slabs 20.00 Slabs	PCI: 8		
Sample N Sample C 70 SC 65 JT 73 SF Sample N	Number: 100 Comments: CALING SEAL DMG HRINKAGE CR	t .	L L N	5.00 Slabs 20.00 Slabs 20.00 Slabs				
Sample N Sample C 70 SC 65 JT 73 SF Sample N Sample C	Number: 100 Comments: CALING SEAL DMG HRINKAGE CR	t .	L L N	5.00 Slabs 20.00 Slabs 20.00 Slabs				
Sample N Sample C 70 SC 65 JT 73 SF Sample N Sample C 70 SC	Number: 100 Comments: CALING SEAL DMG HRINKAGE CR Number: 102 Comments:	t .	L L N	5.00 Slabs 20.00 Slabs 20.00 Slabs Area:				
Sample N Sample C 70 SC 65 JT 73 SF Sample N Sample C 70 SC 65 JT	Number: 100 Comments: CALING SEAL DMG HRINKAGE CR Number: 102 Comments:	Туре	L L N	5.00 Slabs 20.00 Slabs 20.00 Slabs  Area:				

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW F TAXIWAY F Use: TAXIWAY Area: 214,516 SqFt Name: **Section:** 1145 of 5 **Last Const.:** 1/1/1985 From: To: PCC Surface: Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P 94 Ft Area: 30,320 SqFt Length: 176 Ft Width: Slabs: 49 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,054 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1985 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 6 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 90 Sample Number: 101 Type: R 16.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 9.00 Slabs

L

1.00 Slabs

66

SMALL PATCH

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW F TAXIWAY F Use: TAXIWAY 214,516 SqFt Name: Area: **Section:** 1150 of 5 **Last Const.:** 1/1/1985 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 18,725 SqFt Length: 125 Ft Width: 75 Ft Slabs: 30 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 550 Ft **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1985 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 86 **Inspection Comments: PCI:** 86 Sample Number: 100 Type: R 20.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 12.00 Slabs 65 JT SEAL DMG L 20.00 Slabs

JOINT SPALL

74

L

Netwo	rk: JAX			N	ame: JAC	CKSONVILL	E INTERNATION	IAL AIRPORT		
Brancl	h: TW F		Name:	TAXIWAY	F	Use:	TAXIWAY	Area:	214,516 Sq	ıFt
Section	n: 1155	of 5	F	rom: -			То: -		Last Co	onst.: 1/1/1968
Surfac	e: AC	Family: C9	N59-PR-TW	-AC Zo	one:		Category:		Rank:	P
Area:	98,9	61 SqFt	Length:	1,320	Ft	Width:	75 Ft			
Slabs:		Slab Length:	:	Ft	Slab Width:		Ft	Joint	Length:	Ft
Should	ler:	Street Type:			Grade: 0			Lanes	: 0	
Section	n Comments:	• • • • • • • • • • • • • • • • • • • •								
Work	<b>Date:</b> 1/1/1968	Work	Type: BUIL	T		C	ode: IMPORTEI	) Is	Major M&R: Tr	rue
Last Ir	nsp. Date: 4/29/201	9	TotalSa	amples: 18		Surveye	ed: 3			
	tions: PCI: 30			•		•				
	tion Comments:									
	e Number: 102	Type:	R	Area:	562	5.00 SqFt	PCI:	27		
_	e Comments:	-71						_,		
			_							
	RAVELING		L	5375.00 SqFi	-					
	L & T CR		M	91.00 Ft						
	RUTTING L & T CR		L L	148.00 SqFi 200.00 Ft						
	BLOCK CR		L	3700.00 Ft	<u>-</u>					
	SWELLING		L	588.00 SqF						
	BLOCK CR		M	925.00 SqF						
	RAVELING		M	250.00 SqF						
	e Number: 106	Туре:	R	Area:		5.00 SqFt	PCI:	33		
_	e Comments:	Type.	K	m ca.	302	3.00 Bq1 t	101.	33		
_				2500 00 G F						
	BLOCK CR		L	3780.00 SqF						
	BLOCK CR L & T CR		M	945.00 SqF 77.00 Ft						
	RAVELING		L	77.00 Ft 5375.00 SqFt	_					
	SWELLING		L L	844.00 SqF						
	RAVELING		M	250.00 SqF						
	L & T CR		M	45.00 Ft	•					
	e Number: 116	Type:	R	Area:	562	5.00 SqFt	PCI:	31		
Sampl	e Comments:	•				•				
52	RAVELING		M	250.00 SqF	:					
	BLEEDING		N	6.00 SqF						
	DEPRESSION		L	21.00 SqF						
56	SWELLING		L	695.00 SqF						
48	L & T CR		M	140.00 Ft						
43	BLOCK CR		M	750.00 SqF						
	L & T CR		L	255.00 Ft						
	BLOCK CR		L	3000.00 SqF						
52	RAVELING		L	5375.00 SqF						

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW F TAXIWAY F Use: TAXIWAY Area: 214,516 SqFt Name: **Section:** 1170 of 5 **Last Const.:** 1/1/1994 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P 90 Ft Area: 27,436 SqFt Length: 222 Ft Width: Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,286 Ft 44 **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1994 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions: PCI:** 82 **Inspection Comments: PCI:** 82 Sample Number: 101 Type: R 16.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 16.00 Slabs SMALL PATCH L 2.00 Slabs 66

SCALING

70

L

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW F TAXIWAY F Use: TAXIWAY Area: 214,516 SqFt Name: **Section:** 1175 of 5 **Last Const.:** 1/1/1985 From: To: C9N59-PR-RW-TW-PCC Surface: PCC Family: Zone: Category: Rank: P 90 Ft Area: 39,074 SqFt Length: 266 Ft Width: Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,559 Ft 63 **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1985 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 93 Sample Number: 103 Type: R 20.00 Slabs Area:

**Sample Comments:** 

SHRINKAGE CR

N

10.00 Slabs

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW G TAXIWAY G Use: TAXIWAY 298,411 SqFt Name: Area: of 8 Section: 1020 **Last Const.:** 1/1/1985 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 29,478 SqFt Length: 176 Ft Width: 90 Ft Slabs: Slab Length: 20 Ft Slab Width: 25 Ft Joint Length: 1,160 Ft 59 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1985 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 6 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 78 Sample Number: 100 Type: R 20.00 Slabs Area: **Sample Comments:** 70 SCALING M 1.00 Slabs 70 **SCALING** L 3.00 Slabs

SHRINKAGE CR

JOINT SPALL

N

L

20.00 Slabs

1.00 Slabs

73

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW G TAXIWAY G Use: TAXIWAY 298,411 SqFt Name: Area: **Section:** 1025 of 8 **Last Const.:** 1/1/1985 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 19,138 SqFt Length: 125 Ft Width: 75 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 550 Ft 31 **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1985 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 85 **Inspection Comments: PCI:** 85 Sample Number: 100 Type: R 20.00 Slabs Area: **Sample Comments:** 66 SMALL PATCH L 4.00 Slabs 74 JOINT SPALL L 1.00 Slabs

SHRINKAGE CR

73

N

Network: JAX		Name:	JACKSONVILL	E INTERNATIONAL	AIRPORT	
Branch: TW G	Name:	TAXIWAY G	Use:	TAXIWAY	Area:	298,411 SqFt
Section: 1030	of 8 Fro	om: -		То: -		Last Const.: 1/1/2016
Surface: AC	Family: C9N59-PR-TW-A	AC Zone:		Category:		Rank: P
Area: 35,0	)19 SqFt Length:	700 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft Slab	Width:	Ft	Joint Le	ength: Ft
Shoulder:	Street Type:	Gra	<b>de:</b> 0		Lanes:	0
Section Comments:						
Work Date: 1/1/1968	Work Type: BUILT		C	Code: IMPORTED	Is N	Major M&R: True
Work Date: 1/1/2001	Work Type: Overlay	- AC Structural	C	Code: OL-AS	Is M	Major M&R: True
Work Date: 1/2/2001	Work Type: Surface	Treatment - Slurry Se	eal C	Code: ST-SS	Is M	Major M&R: False
Work Date: 1/1/2016	Work Type: Comple	te Reconstruction - A	C C	Code: CR-AC	Is M	Major M&R: True
<b>Last Insp. Date:</b> 4/29/201	19 TotalSam	ples: 7	Surveye	ed: 2		
Conditions: PCI: 89						
Inspection Comments:						
Sample Number: 101	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 91		
Sample Comments:						
48 L & T CR	L	12.00 Ft				
57 WEATHERING	L	5000.00 SqFt				
Sample Number: 105	Type: R	Area:	5008.00 SqFt	PCI: 88		
Sample Comments:						
48 L & T CR	L	38.00 Ft				
57 WEATHERING	L :	5007.00 SqFt				
50 PATCHING	L	1.00 SqFt				
42 BLEEDING	N	1.00 SqFt				

Network	: JAX					Nam	ie:	JACKSONVI	LLE IN	TERNATIO	NAL AIRI	PORT			
Branch:	TW G		Na	me:	TAXIV	VAY G		Us	<b>e:</b> T <i>A</i>	AXIWAY	Area	a:	298,4	11 SqFt	
Section:	1032		of 8	Fro	m:	-				То: -			La	st Const.	: 1/1/2016
Surface:	AC	Family:	C9N59	-PR-TW-A	<b>AC</b>	Zone	e:			Category:			Ra	nk: P	
Area:		44,449 SqFt	L	ength:		870 F	t	Width:		50 F	į				
Slabs:		Slab Le	ength:		Ft		Slab Wid	th:		Ft		Joint Len	igth:		Ft
Shoulder	:	Street T	Гуре:				Grade:	0				Lanes:	0		
Section (	Comments:														
Work Da	ate: 1/1/1968	3 <b>v</b>	Vork Typ	e: BUILT					Code:	IMPORTE	ED .	Is Ma	ajor M&F	R: True	
Work Da	ate: 1/1/2001	ı v	Vork Type	e: Overlay	- AC Sta	ructural			Code:	OL-AS		Is Ma	ajor M&F	R: True	
Work Da	ate: 1/2/2001	ı v	Vork Type	e: Surface	Treatme	nt - Sluı	rry Seal		Code:	ST-SS		Is Ma	ajor M&F	R: False	
Work Da	ate: 1/1/2016	5 <b>v</b>	Vork Type	e: Comple	te Recon	structio	n - AC		Code:	CR-AC		Is Ma	ajor M&F	R: True	
Last Insp	p. Date: 4/2	29/2019		TotalSam	ples:	9		Surv	eyed:	2					
Conditio	ns: PCI:	94													
Inspectio	on Comment	s:													
Sample N	Number: 10	08 Ty	pe:	R	A	rea:	:	5000.00 SqFt		PCI:	94				
Sample (	Comments:														
57 W	/EATHERIN	G	L		5000.00	SqFt									
Sample I	Number: 1	12 <b>Ty</b>	pe:	R	A	rea:	:	5000.00 SqFt		PCI:	94				
Sample (	Comments:														
57 W	/EATHERIN	G	L		5000.00	SqFt									

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 298,411 SqFt Branch: TW G TAXIWAY G Use: TAXIWAY Name: Area: of 8 1035 Section: From: To: Last Const.: 1/1/2016 ACFamily: C9N59-PR-TW-AC Zone: Category: Rank: P Surface: Area: 7,929 SqFt Length: 190 Ft Width: 35 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 12/25/1999 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2001 Work Type: Surface Treatment - Slurry Seal Code: ST-SS Is Major M&R: False Work Date: 1/1/2016 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R 4509.00 SqFt **PCI:** 92 Sample Number: 400 Type: Area: **Sample Comments:** 57 WEATHERING L 4509.00 SqFt

L & T CR

48

L

5.00 Ft

Network:	JAX				Name:	JAC	KSONVILLE	E INTE	RNATION	IAL AIRPORT			
Branch:	TW G		Name:	TAXI	WAY G		Use:	TAX	IWAY	Area:	298	3,411 SqFt	
Section: 1	040	of	8	From:	-			T	0: -			Last Const.:	1/1/2016
Surface: A	<b>C</b>	Family:	C9N59-PR-	TW-AC	Zone:			C	ategory:			Rank: P	
Area:	14,09	6 SqFt	Lengtl	h:	150 Ft		Width:		60 Ft				
Slabs:		Slab Leng	gth:	Ft	Sla	b Width:		Ft		Joint	Length:	F	t
Shoulder:		Street Ty	pe:		Gr	rade: 0				Lane	s: 0		
Section Com	ments:												
Work Date:	12/25/1999	Wo	ork Type: Ne	ew Construction	on - Initial		Co	ode: 1	NU-IN	I	Major M	&R: True	
Work Date:	1/1/2001	Wo	ork Type: Ov	verlay - AC St	ructural		Co	ode: (	DL-AS	Is	Major M	&R: True	
Work Date:	1/2/2001	Wo	ork Type: Su	rface Treatme	ent - Slurry S	Seal	Co	ode: S	ST-SS	Is	Major M	&R: False	
Work Date:	1/1/2016	Wo	ork Type: Co	omplete Recon	struction - A	AC	Co	ode: (	CR-AC	I	s Major M	&R: True	
Last Insp. Da	ate: 4/29/2019	)	Tota	lSamples:	3		Surveyed	<b>d:</b> 1					
Conditions:	<b>PCI:</b> 89												
Inspection C	comments:												
Sample Num	nber: 200	Тур	e: R	Α	Area:	4780	0.00 SqFt		PCI:	89			
Sample Com	ments:												
57 WEA	THERING		L	4780.00	SqFt								
48 L & T	T CR		L	49.00	Ft								

Network:	JAX			Nar	ne: JAC	CKSONVILLE	E INTERNAT	IONAL AIRPOR	Т	
Branch:	TW G		Name:	TAXIWAY C	<u>;</u>	Use:	TAXIWAY	Area:	298,411 SqF	t
Section:	1045	of	. 8	From: -			То: -		Last Con	st.: 1/1/200
Surface:	AAC	Family:	C9N59-PR-TV APC	W-AAC- Zon	ie:		Categor	y:	Rank: F	•
Area:	14,4	480 SqFt	Length:	223 I	Ft	Width:	60	Ft		
Slabs:		Slab Leng	gth:	Ft	Slab Width:		Ft	Join	nt Length:	Ft
Shoulder:		Street Ty	pe:		Grade: 0			Lar	nes: 0	
Section Co	omments:									
Work Dat	re: 12/25/1999	Wo	ork Type: New	Construction - Init	tial	Co	ode: NU-IN		Is Major M&R: True	<del></del>
Work Dat	e: 1/1/2001	Wo	ork Type: Ove	rlay - AC Structura	1	Co	ode: OL-AS		Is Major M&R: True	<del></del>
Work Dat	e: 1/2/2001	Wo	ork Type: Surf	ace Treatment - Slu	ırry Seal	Co	ode: ST-SS		Is Major M&R: Fals	e
Work Dat	e: 1/1/2013	Wo	ork Type: Surf	ace Treatment - Sea	al Coat	Co	ode: ST-SC		Is Major M&R: Fals	e
Condition	Date: 4/29/20 s: PCI: 53 Comments:		Totals	Samples: 3		Surveye	<b>d:</b> 1			
Sample Ni	umber: 302	Тур	e: R	Area:	4800	0.00 SqFt	PC	I: 53		
Sample Co	omments:									
41 AL	LIGATOR CR		L	40.00 SqFt						
	TCHING		L	11.00 SqFt						
	VELING		L	2400.00 SqFt						
	PRESSION		L	54.00 SqFt						
	TELL DIC									
56 SW	VELLING OCK CR		L L	75.00 SqFt 283.00 SqFt						

Network: JAX		Name:	JACKSONVILL	E INTERNATIONAL	AIRPORT	
Branch: TW G	Name:	TAXIWAY G	Use:	TAXIWAY	Area: 2	298,411 SqFt
Section: 1060	of 8	rom: -		То: -		Last Const.: 1/1/1994
Surface: PCC	Family: C9N59-PR-RW	V-TW-PCC Zone:		Category:		Rank: P
Area: 133,	,822 SqFt Length:	515 Ft	Width:	150 Ft		
<b>Slabs:</b> 214	Slab Length:	25 Ft Slab	Width:	25 Ft	Joint Length:	5,515 Ft
Shoulder:	Street Type:	Grad	de: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1994	Work Type: BUIL	Т	C	ode: IMPORTED	Is Major	M&R: True
<b>Last Insp. Date:</b> 4/29/20	)19 TotalSa	amples: 10	Surveye	ed: 2		
Conditions: PCI: 91	1	•				
	1					
Inspection Comments:		Area:				
Inspection Comments: Sample Number: 102	1 Type: R	Area:	31.00 Slabs	PCI: 92		
Inspection Comments: Sample Number: 102 Sample Comments:	Type: R					
Inspection Comments:  Sample Number: 102  Sample Comments:  73 SHRINKAGE CR	Type: R	14.00 Slabs				
Inspection Comments: Sample Number: 102 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL	Type: R	14.00 Slabs 1.00 Slabs				
Inspection Comments: Sample Number: 102 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH	Type: R  N L	14.00 Slabs				
Inspection Comments: Sample Number: 102 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH Sample Number: 104	Type: R  N L L	14.00 Slabs 1.00 Slabs 1.00 Slabs	31.00 Slabs	<b>PCI:</b> 92		
Inspection Comments: Sample Number: 102 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH Sample Number: 104 Sample Comments:	Type: R  N L L	14.00 Slabs 1.00 Slabs 1.00 Slabs	31.00 Slabs	<b>PCI:</b> 92		
Inspection Comments: Sample Number: 102 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH Sample Number: 104 Sample Comments: 66 SMALL PATCH	Type: R  N L L Type: R	14.00 Slabs 1.00 Slabs 1.00 Slabs Area:	31.00 Slabs	<b>PCI:</b> 92		
Inspection Comments: Sample Number: 102 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH Sample Number: 104 Sample Comments: 66 SMALL PATCH	Type: R  N L L Type: R	14.00 Slabs 1.00 Slabs 1.00 Slabs  Area:	31.00 Slabs	<b>PCI:</b> 92		

Netw	ork: JAX			Name:	JACKSONVILL	E INTERNATIONAL	AIRPORT	
Bran	ch: TW H		Name:	TAXIWAY H	Use:	TAXIWAY	Area:	374,438 SqFt
Section	on: 550	of 3	]	From: -		То: -		Last Const.: 1/1/1994
Surfa	nce: PCC	Family: C9N	N59-PR-RV	V-TW-PCC Zone:		Category:		Rank: P
Area	: 208,46	50 SqFt	Length:	488 Ft	Width:	160 Ft		
Slabs	: 334	Slab Length:		25 Ft Sla	ıb Width:	25 Ft	Joint Le	ength: 5,598 Ft
Shou	lder:	Street Type:		Gr	rade: 0		Lanes:	0
Section	on Comments:	••						
Worl	<b>C Date:</b> 1/1/1994	Work T	ype: BUII	LT	C	ode: IMPORTED	Is N	Major M&R: True
Last	Insp. Date: 4/29/2019	)	TotalS	amples: 18	Surveye	ed: 3		
Cond	litions: PCI: 88							
Inspe	ection Comments:							
Samp	ole Number: 103	Type:	R	Area:	24.00 Slabs	PCI: 94		
Samp	ole Comments:							
75	CORNER SPALL	I	_	1.00 Slabs				
74	JOINT SPALL	I		1.00 Slabs				
73	SHRINKAGE CR	1	N	5.00 Slabs				
Samp	ole Number: 111	Type:	R	Area:	24.00 Slabs	<b>PCI:</b> 90		
Samp	ole Comments:							
73	SHRINKAGE CR	1	N	11.00 Slabs				
66	SMALL PATCH	I		6.00 Slabs				
Samp	ole Number: 115	Type:	R	Area:	24.00 Slabs	PCI: 81		
Samp	ole Comments:							
73	SHRINKAGE CR	1	N	13.00 Slabs				
63	LINEAR CR	I		1.00 Slabs				
74	JOINT SPALL	I		1.00 Slabs				
75	CORNER SPALL	1	M	1.00 Slabs				
66	SMALL PATCH	I		3.00 Slabs				

Network: JAX		Name:	JACKSONVILLE	E INTERNATIONAL	L AIRPORT	
Branch: TW H	Name:	TAXIWAY H	Use:	TAXIWAY	Area:	374,438 SqFt
Section: 555	of 3	From: -		То: -		<b>Last Const.:</b> 1/1/1985
Surface: PCC	Family: C9N59-PR-R	W-TW-PCC Zone:		Category:		Rank: P
Area: 127,29	93 SqFt Length:	1,540 Ft	Width:	75 Ft		
<b>Slabs:</b> 204	Slab Length:	25 Ft Slab V	Vidth:	25 Ft	Joint Length	7,625 Ft
Shoulder:	Street Type:	Grade	e: 0		Lanes: 0	)
Section Comments:						
Work Date: 1/1/1985	Work Type: BUI	LT	Co	ode: IMPORTED	Is Major	r M&R: True
Work Date: 1/1/2012	Work Type: Slab	Replacement - PCC	Co	ode: SL-PC	Is Major	r M&R: False
Last Insp. Date: 4/29/2019	O Totals	Samples: 11	Surveyed	d· 2		
-	) I otals	samples.	Surveyed			
Conditions: PCI: 70	y Total.	ampres. 11	Surveyed	2		
Conditions: PCI: 70 Inspection Comments:						
Conditions: PCI: 70 Inspection Comments: Sample Number: 101	Type: R	Area:	22.00 Slabs	PCI: 69		
Conditions: PCI: 70 Inspection Comments: Sample Number: 101						
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments:						
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments: 66 SMALL PATCH	Type: R	Area:				
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments: 66 SMALL PATCH 67 LARGE PATCH	Type: R	Area:				
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK	Type: R  M M	Area: 1.00 Slabs 1.00 Slabs				
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK 73 SHRINKAGE CR	Type: R  M M L	Area:  1.00 Slabs 1.00 Slabs 2.00 Slabs				
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK 73 SHRINKAGE CR 74 JOINT SPALL	Type: R  M M L N	Area:  1.00 Slabs 1.00 Slabs 2.00 Slabs 20.00 Slabs				
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH	Type: R  M M L N L	Area:  1.00 Slabs 1.00 Slabs 2.00 Slabs 20.00 Slabs 1.00 Slabs				
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH Sample Number: 105	Type: R  M M L N L L L	Area:  1.00 Slabs 1.00 Slabs 2.00 Slabs 20.00 Slabs 1.00 Slabs 5.00 Slabs	22.00 Slabs	PCI: 69		
Conditions: PCI: 70 Inspection Comments: Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH Sample Number: 105 Sample Comments:	Type: R  M M L N L L L	Area:  1.00 Slabs 1.00 Slabs 2.00 Slabs 20.00 Slabs 1.00 Slabs 5.00 Slabs	22.00 Slabs	PCI: 69		
Conditions: PCI: 70 Inspection Comments:  Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH  Sample Number: 105 Sample Comments:  62 CORNER BREAK	Type: R  M M L N L L Type: R	Area:  1.00 Slabs 1.00 Slabs 2.00 Slabs 20.00 Slabs 1.00 Slabs 5.00 Slabs  Area:	22.00 Slabs	PCI: 69		
Conditions: PCI: 70 Inspection Comments:  Sample Number: 101 Sample Comments:  66 SMALL PATCH 67 LARGE PATCH 62 CORNER BREAK 73 SHRINKAGE CR 74 JOINT SPALL 66 SMALL PATCH  Sample Number: 105 Sample Comments:	Type: R  M M L N L L Type: R	Area:  1.00 Slabs 1.00 Slabs 2.00 Slabs 20.00 Slabs 1.00 Slabs 5.00 Slabs Area:	22.00 Slabs	PCI: 69		

73 63 SHRINKAGE CR

LINEAR CR

N L

18.00 Slabs

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 374,438 SqFt Branch: TW H TAXIWAY H Use: TAXIWAY Name: Area: of 3 557 Section: From: To: Last Const.: 1/1/2007 PCC Family: C9N59-PR-RW-TW-PCC Zone: Rank: P Surface: Category: Area: 38,685 SqFt Length: 615 Ft Width: 60 Ft Slab Length: 25 Ft Slab Width: Joint Length: Slabs: 62 25 Ft 2,277 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1985 Work Type: BUILT Code: IMPORTED Is Major M&R: True Work Date: 1/1/2007 Work Type: Surface Reconstruction - PCC Code: SR-PC Is Major M&R: True **Last Insp. Date:** 4/29/2019 TotalSamples: 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** R **PCI:** 80 Sample Number: 101 Type: Area: 26.00 Slabs **Sample Comments:** JOINT SPALL L 3.00 Slabs 74 CORNER SPALL L 1.00 75 Slabs 70 SCALING L 2.00 Slabs SHRINKAGE CR N 73 22.00 Slabs

Network: JAX		Name:	JACKSONVILLI	E INTERNATIONAL	AIRPORT	
Branch: TW J	Name:	TAXIWAY J	Use:	TAXIWAY	Area:	410,932 SqFt
Section: 740	of 6 Fi	om: -		То: -		Last Const.: 1/1/1994
Surface: PCC	Family: C9N59-PR-RW	-TW-PCC Zone:		Category:		Rank: P
Area: 136,24	42 SqFt Length:	550 Ft	Width:	150 Ft		
<b>Slabs:</b> 218	Slab Length:	25 Ft Slab V	Vidth:	25 Ft	Joint Length	5,900 Ft
Shoulder:	Street Type:	Grade	e: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1994	Work Type: BUIL	Γ	Co	ode: IMPORTED	Is Major	M&R: True
<b>Last Insp. Date:</b> 4/29/201	9 TotalSa	mples: 12	Surveye	<b>d:</b> 2		
Conditions: PCI: 87						
Inspection Comments:						
Inspection Comments: Sample Number: 102	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 81		
	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 81		
Sample Number: 102	Type: R	Area:	24.00 Slabs	PCI: 81		
Sample Number: 102 Sample Comments:	V1		24.00 Slabs	<b>PCI:</b> 81		
Sample Number: 102 Sample Comments: 73 SHRINKAGE CR	N	17.00 Slabs	24.00 Slabs 24.00 Slabs	PCI: 81		
Sample Number: 102 Sample Comments: 73 SHRINKAGE CR 67 LARGE PATCH	N L	17.00 Slabs 6.00 Slabs				

Network:	JAX					Name:	JAC	KSONVILL	E INTERN	NATIONAL	AIRPORT				
Branch:	TW J		N	Name:	TAXIWA	AY J		Use:	TAXIW	/AY	Area:		410,9	32 SqFt	
Section:	745	0	f 6	Fre	om: -				To:	-			La	ast Const	.: 1/1/1989
Surface:	PCC	Family:	C9N5	59-PR-RW-	TW-PCC	Zone:			Cate	egory:			R	ank: P	
Area:		94,986 SqFt		Length:	1,7	760 Ft		Width:		75 Ft					
Slabs:	152	Slab Lei	ngth:		25 Ft	Slab	Width:		25 Ft		Joint	Length	:	8,725	Ft
Shoulder	:	Street T	ype:			Grad	le: 0				Lanes	s: 0			
Section C	comments:														
Work Da	to: 1/1/1080	· ·	ault Tr	DIHLT	,				ode: IM	DODTED	To	Maian	мот	R: True	
	1/1/1909	W	ork ry	pe: BUILT				C	oue. IIVI	FORTED	18	Major	MIXI	. IIuc	
			ork 1y							FORTED	18	s Major	MA	A. IIuc	
Last Insp	. Date: 4/29		ork 1y	TotalSan				Surveye		FORTED		s Major	MA	. True	
Last Insp Condition	. Date: 4/29	9/2019 82	ork Ty							FORTED	18	- Major	MAI	C. True	
Last Insp Condition	. Date: 4/29	9/2019 82				ea:	21				18	S Major	WICH	. True	
Last Insp Condition Inspection Sample N	Date: 4/29 ns: PCI: n Comments	9/2019 82		TotalSan	mples: 8	ea:	21	Surveye		PCI: 81	18	S Major	Mer	. True	
Last Insp Condition Inspection Sample N Sample C	Date: 4/29 ns: PCI: n Comments Tumber: 10	9/2019 82 : 1 <b>Ty</b>		TotalSan	mples: 8		21	Surveye			18	з мајог	Mer	. True	
Last Insp Condition Inspection Sample N Sample C	n. Date: 4/29 ns: PCI: n Comments dumber: 10	9/2019 82 : 1 <b>Ty</b>	pe:	TotalSan	nples: 8	labs	21	Surveye			18	з ма <b>ј</b> ог	Mer	. True	
Last Insp Condition Inspection Sample N Sample C 73 SF 66 SM	n. Date: 4/29 ns: PCI: n Comments fumber: 10 Comments:	9/2019 82 : 1 <b>Ty</b>	pe:	TotalSan	Are	labs labs	21	Surveye			18	s Major	Mai	X. Hue	
Last Insp Condition Inspection Sample N Sample C 73 SF 66 SM 67 LA	n. Date: 4/29 ns: PCI: n Comments fumber: 10 Comments: HRINKAGE ( MALL PATC)	9/2019 82 : 1 <b>Ty</b> CR H	pe: N L L	TotalSan	Are 21.00 SI 3.00 SI	labs labs labs		Surveye				s Major	Meet	X. Hue	
Last Insp Condition Inspection Sample N Sample C 73 SF 66 SN 67 LA Sample N	n. Date: 4/29 ns: PCI: n Comments fumber: 10 Comments: HRINKAGE ( MALL PATC) ARGE PATC	9/2019 82 : 1 <b>Ty</b> J CR H	pe: N L L	<b>TotalSan</b>	Are  21.00 SI 3.00 SI 1.00 SI	labs labs labs		Surveye		PCI: 81		з мајог	Meet	X. Hue	
Last Insp Condition Inspection Sample N Sample C 73 SF 66 SM 67 LA Sample N Sample C	n. Date: 4/29 ns: PCI: n Comments fumber: 10 Comments: HRINKAGE O MALL PATCI ARGE PATCI	9/2019 82 : 1 Ty	pe: N L L	<b>TotalSan</b>	Are  21.00 SI 3.00 SI 1.00 SI	labs labs labs		Surveye		PCI: 81		з мајог	Meet	X. Hue	

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW J TAXIWAY J Use: TAXIWAY 410,932 SqFt Name: Area: 750 of 6 **Last Const.:** 1/1/1982 Section: From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 21,670 SqFt Length: 265 Ft Width: 75 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 35 1,250 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1982 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 69 **Inspection Comments: PCI:** 69 Sample Number: 111 Type: R 21.00 Slabs Area: **Sample Comments:** 65 JT SEAL DMG L 21.00 Slabs JOINT SPALL L 4.00 Slabs 74 CORNER BREAK 62 L 1.00 Slabs

N

L

L

21.00

10.00 Slabs

4.00 Slabs

Slabs

SHRINKAGE CR

SMALL PATCH

SCALING

73 70

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 410,932 SqFt **Branch:** TW J TAXIWAY J Use: TAXIWAY Name: Area: Section: 755 of 6 **Last Const.:** 1/1/1968 From: To: -Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 13,125 SqFt Length: 175 Ft Width: 75 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 800 Ft 21 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1968 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 1 Surveyed: 1 **Conditions: PCI:** 73 **Inspection Comments: PCI:** 73 Sample Number: 112 Type: R 21.00 Slabs Area: **Sample Comments:** 70 SCALING L 5.00 Slabs SMALL PATCH M 3.00 Slabs 66 JOINT SPALL Slabs 74 L 3.00 73 SHRINKAGE CR N 21.00 Slabs

1.00 Slabs

L

SMALL PATCH

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: Branch: TW J TAXIWAY J Use: TAXIWAY 410,932 SqFt Name: Area: 760 of 6 **Last Const.:** 1/1/1984 Section: From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 21,750 SqFt Length: 290 Ft Width: 75 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 35 1,375 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1984 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 70 **Inspection Comments: PCI:** 70 Sample Number: 113 Type: R 21.00 Slabs Area: **Sample Comments:** 74 JOINT SPALL L 2.00 Slabs SMALL PATCH L 3.00 Slabs 66 CORNER SPALL 75 L 1.00 Slabs JT SEAL DMG L 21.00 Slabs 65 LARGE PATCH L 2.00 Slabs 67 SHRINKAGE CR N 18.00 Slabs

73 66

SMALL PATCH

M

Network:	JAX			Name:	JACKSONVILLI	E INTERNATIONAL	L AIRPORT	
Branch:	TW J		Name:	TAXIWAY J	Use:	TAXIWAY	Area:	410,932 SqFt
Section: 765	5	of	6	From: -		То: -		Last Const.: 1/1/201
Surface: PC	CC	Family: (	C9N59-PR-	RW-TW-PCC Zone:		Category:		Rank: P
Area:	123,1:	59 SqFt	Lengtl	1,020 Ft	Width:	110 Ft		
Slabs: 324	4	Slab Lengt	th:	19 Ft Slab Wi	dth:	20 Ft	Joint Leng	<b>9th:</b> 10,385 Ft
Shoulder:		Street Type	e:	Grade:	0		Lanes:	0
Section Comm	nents:							
Work Date: 1	1/1/2013	Wor	k Type: No	ew Construction - Initial	Co	ode: NU-IN	Is Ma	jor M&R: True
Last Insp. Dat	te: 4/29/201	9	Tota	dSamples: 19	Surveye	<b>d:</b> 3		
Conditions:	<b>PCI:</b> 97							
Inspection Co	mments:							
Sample Numb	er: 107	Type:	: R	Area:	20.00 Slabs	<b>PCI:</b> 10	0	
Sample Comn	nents:							
<no distress=""></no>								
Sample Numb	er: 110	Туре:	R	Area:	30.00 Slabs	<b>PCI:</b> 94		
	nents:							
Sample Comn								
_	Е РАТСН		L	1.00 Slabs				
67 LARGI			L N	1.00 Slabs 4.00 Slabs				
67 LARGI 73 SHRIN	Е РАТСН							
67 LARGI 73 SHRIN	E PATCH KAGE CR SPALL	Туре:	N L	4.00 Slabs	24.00 Slabs	<b>PCI:</b> 99		
67 LARGI 73 SHRIN 74 JOINT	E PATCH IKAGE CR SPALL Der: 114	Туре:	N L	4.00 Slabs 1.00 Slabs	24.00 Slabs	<b>PCI:</b> 99		

Network: JAX		Name:	JACKSONVILLE II	NTERNATIONAL	AIRPORT	
Branch: TW K	Name:	TAXIWAY K	Use:	ΓΑΧΙWΑΥ	Area:	107,334 SqFt
Section: 1320	of 1 F	rom: -		То: -		<b>Last Const.:</b> 1/1/1992
Surface: PCC	Family: C9N59-PR-RW	-TW-PCC Zone:		Category:		Rank: P
<b>Area:</b> 107,33	4 SqFt Length:	795 Ft	Width:	92 Ft		
<b>Slabs:</b> 332	Slab Length:	17 Ft Slab	Width:	19 Ft	Joint Length	7,265 Ft
Shoulder:	Street Type:	Grad	<b>e:</b> 0		Lanes: 0	
<b>Section Comments:</b>						
<b>Work Date:</b> 1/1/1992	Work Type: BUIL	Γ	Code	e: IMPORTED	Is Major	M&R: True
<b>Last Insp. Date:</b> 4/29/2019	TotalSa	mples: 18	Surveyed:	3		
Conditions: PCI: 85						
Inspection Comments:						
Sample Number: 101	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 86		
Sample Comments:						
73 SHRINKAGE CR	N	20.00 Slabs				
Sample Number: 104	Type: R	Area:	20.00 Slabs	PCI: 86		
Sample Comments:						
73 SHRINKAGE CR	N	20.00 Slabs				
Sample Number: 107	Type: R	Area:	20.00 Slabs	PCI: 84		
Sample Comments:						
73 SHRINKAGE CR 66 SMALL PATCH	N L	20.00 Slabs 3.00 Slabs				
5 SINIED I MICH	L	5.00 51405				

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW L TAXIWAY L Use: TAXIWAY 149,684 SqFt Name: Area: Section: 205 of 5 **Last Const.:** 1/1/1994 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P 90 Ft Area: 25,258 SqFt Length: 244 Ft Width: Slabs: 40 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,423 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1994 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 78 **Inspection Comments: PCI:** 78 Sample Number: 100 Type: R 20.00 Slabs Area: **Sample Comments:** 66 SMALL PATCH M 2.00 Slabs 74 JOINT SPALL L 2.00 Slabs

73

SHRINKAGE CR

N

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW L TAXIWAY L Use: TAXIWAY 149,684 SqFt Name: Area: Section: 210 of 5 **Last Const.:** 1/1/1983 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P 90 Ft Area: 28,620 SqFt Length: 244 Ft Width: Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 46 1,423 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1983 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 84 **Inspection Comments: PCI:** 84 Sample Number: 102 Type: R 24.00 Slabs Area: **Sample Comments:** 74 JOINT SPALL L 1.00 Slabs SMALL PATCH L 5.00 Slabs 66

SHRINKAGE CR

73

N

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW L TAXIWAY L Use: TAXIWAY 149,684 SqFt Name: Area: Section: 215 of 5 **Last Const.:** 1/1/1983 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 18,195 SqFt Length: 206 Ft Width: 90 Ft Slabs: 29 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,187 Ft 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1983 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 77 **Inspection Comments: PCI:** 77 Sample Number: 105 Type: R 19.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 19.00 Slabs 75 CORNER SPALL L 1.00 Slabs

JOINT SPALL

SCALING

74

70

L

L

3.00 Slabs

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW L TAXIWAY L Use: TAXIWAY Area: 149,684 SqFt Name: Section: 220 of 5 **Last Const.:** 1/1/1992 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P 90 Ft Area: 25,304 SqFt Length: 240 Ft Width: Slabs: Slab Length: 17 Ft Slab Width: 19 Ft Joint Length: 78 2,077 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1992 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions: PCI:** 83 **Inspection Comments: PCI:** 83 Sample Number: 103 Type: R 20.00 Slabs Area: **Sample Comments:** 

73 SHRINKAGE CR N 20.00 Slabs

66

SMALL PATCH

L

Network: JAX		Name:	JACKSONVILLE	INTERNATIONAL	AIRPORT	
Branch: TW L	Name:	TAXIWAY L	Use:	TAXIWAY	Area:	149,684 SqFt
Section: 225	of 5	From: -		То: -		<b>Last Const.:</b> 1/1/1992
Surface: PCC	Family: C9N59-PR-R	W-TW-PCC Zone:		Category:		Rank: P
Area: 52,30	07 SqFt Length	: 488 Ft	Width:	90 Ft		
<b>Slabs:</b> 171	Slab Length:	17 Ft Slab	Width:	18 Ft	Joint Length	: 4,446 Ft
Shoulder:	Street Type:	Grac	le: 0		Lanes: 0	
<b>Section Comments:</b>						
Work Date: 1/1/1992	Work Type: BU	ILT	Coo	de: IMPORTED	Is Major	M&R: True
<b>Last Insp. Date:</b> 4/29/2019	9 <b>Total</b>	Samples: 9	Surveyed	: 2		
Last Insp. Date: 4/29/2019 Conditions: PCI: 81	9 Total	Samples: 9	Surveyed	: 2		
Conditions: PCI: 81	9 <b>Total</b>	Samples: 9	Surveyed	: 2		
Conditions: PCI: 81 Inspection Comments:	9 Total  Type: R	Samples: 9  Area:	Surveyed 20.00 Slabs	: 2 PCI: 78		
Conditions: PCI: 81 Inspection Comments: Sample Number: 101						
Conditions: PCI: 81 Inspection Comments: Sample Number: 101 Sample Comments:						
Conditions: PCI: 81 Inspection Comments: Sample Number: 101 Sample Comments: 73 SHRINKAGE CR	Type: R	Area:				
Conditions: PCI: 81 Inspection Comments: Sample Number: 101 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL	Type: R	Area:				
Conditions: PCI: 81 Inspection Comments: Sample Number: 101 Sample Comments: 73 SHRINKAGE CR 74 JOINT SPALL 70 SCALING	Type: R  N L	Area: 20.00 Slabs 4.00 Slabs				
Conditions: PCI: 81 Inspection Comments:  Sample Number: 101 Sample Comments:  73 SHRINKAGE CR 74 JOINT SPALL 70 SCALING  Sample Number: 105	Type: R  N L L	Area:  20.00 Slabs 4.00 Slabs 5.00 Slabs	20.00 Slabs	<b>PCI:</b> 78		
Conditions: PCI: 81 Inspection Comments:  Sample Number: 101 Sample Comments:  73 SHRINKAGE CR 74 JOINT SPALL	Type: R  N L L	Area:  20.00 Slabs 4.00 Slabs 5.00 Slabs	20.00 Slabs	<b>PCI:</b> 78		
Conditions: PCI: 81 Inspection Comments:  Sample Number: 101 Sample Comments:  73 SHRINKAGE CR 74 JOINT SPALL 70 SCALING  Sample Number: 105 Sample Comments:	Type: R  N L L Type: R	Area:  20.00 Slabs 4.00 Slabs 5.00 Slabs  Area:	20.00 Slabs	<b>PCI:</b> 78		

Network: JAX		Name: JA	CKSONVILLE	INTERNATIONAL AIR	PORT
Branch: TW N	Name:	TAXIWAY N	Use:	TAXIWAY Are	
Section: 305	of 4 Fro	om: -		То: -	Last Const.: 1/1/1992
Surface: PCC Fam				Category:	Rank: P
<b>Area:</b> 221,250 SqF	•	2,950 Ft	Width:	75 Ft	
_	b Length:	17 Ft Slab Width:		19 Ft	Joint Length: 21,634 Ft
	eet Type:	Grade: 0			Lanes: 0
Section Comments:	<b>.</b> 1				
Work Date: 1/1/1992	Work Type: BUILT		Coo	de: IMPORTED	Is Major M&R: True
<b>Last Insp. Date:</b> 4/29/2019	TotalSam	iples: 36	Surveyed	• 5	
Conditions: PCI: 87	Total	presi 50	Sarveyea	•	
Inspection Comments:					
	7F	<b>.</b>	20.00 GL 1	DCII. 02	
Sample Number: 128 Sample Comments:	Type: R	Area: 2	20.00 Slabs	<b>PCI</b> : 92	
-					
74 JOINT SPALL	L	1.00 Slabs 7.00 Slabs			
<ul><li>73 SHRINKAGE CR</li><li>66 SMALL PATCH</li></ul>	N L	1.00 Slabs			
Sample Number: 134	Type: R		20.00 Slabs	PCI: 84	
Sample Comments:					
74 JOINT SPALL	L	3.00 Slabs			
66 SMALL PATCH	L	1.00 Slabs			
73 SHRINKAGE CR	N	8.00 Slabs			
70 SCALING 66 SMALL PATCH	L M	1.00 Slabs 1.00 Slabs			
Sample Number: 141	Type: R		20.00 Slabs	<b>PCI:</b> 91	
Sample Comments:	- J.P				
74 JOINT SPALL	L	1.00 Slabs			
66 SMALL PATCH	L L	1.00 Slabs			
73 SHRINKAGE CR	N	9.00 Slabs			
Sample Number: 149	Type: R	Area: 2	20.00 Slabs	<b>PCI:</b> 91	
Sample Comments:					
73 SHRINKAGE CR	N	7.00 Slabs			
66 SMALL PATCH	L	1.00 Slabs			
74 JOINT SPALL	L	2.00 Slabs			
Sample Number: 159	Type: R	Area: 2	20.00 Slabs	<b>PCI</b> : 79	
Sample Comments:					
75 CORNER SPALL	L	1.00 Slabs			
73 SHRINKAGE CR	N	20.00 Slabs			
66 SMALL PATCH 74 JOINT SPALL	L L	5.00 Slabs 1.00 Slabs			
, . VOINT STREET		1.00 Sidos			

Network:	JAX			Name	: JACKSO	VILLE INT	ERNATIONAI	L AIRPORT	
Branch:	TW N	1	Name:	TAXIWAY N		Use: TA	XIWAY	Area:	577,575 SqFt
Section:	310	of 4	Fı	rom: -		,	То: -		<b>Last Const.:</b> 1/1/1998
Surface:	PCC	Family: C9N:	59-PR-RW	-TW-PCC Zone:	:	•	Category:		Rank: P
Area:	180,07:	5 SqFt	Length:	2,451 Ft	Wid	h:	75 Ft		
Slabs:	288	Slab Length:		25 Ft .	Slab Width:	25 ]	Ft	Joint Lengt	<b>h:</b> 12,180 Ft
Shoulder:	:	Street Type:		•	Grade: 0			Lanes: (	)
Section Co	omments:								
Work Dat	te: 1/1/1998	Work Ty	pe: BUIL	Γ		Code:	IMPORTED	Is Majo	r M&R: True
Last Insp.	. Date: 4/29/2019		TotalSa	mples: 14	S	rveyed: 2			
Condition	s: PCI: 90								
Inspection	n Comments:								
Sample N	umber: 102	Type:	R	Area:	21.00 S	abs	<b>PCI</b> : 91		
Sample C	omments:								
74 JO	INT SPALL	M	[	1.00 Slabs					
74 JO	INT SPALL	L		2.00 Slabs					
73 SH	IRINKAGE CR	N		3.00 Slabs					
Sample N	umber: 108	Туре:	R	Area:	21.00 S	abs	PCI: 89		
Sample C	omments:								
73 SH	IRINKAGE CR	N		15.00 Slabs					

Network:	JAX			Name:	JACK	SONVILLI	E INTERNATIO	NAL AIRPORT		
Branch:	TW N		Name:	TAXIWAY N		Use:	TAXIWAY	Area:	577,	575 SqFt
Section:	312	of 4	4 I	rom: -			То: -		I	ast Const.: 1/1/2000
Surface:	PCC	Family: C	9N59-PR-RW	/-TW-PCC Zone:			Category:		F	Rank: P
Area:	131,25	0 SqFt	Length:	1,775 Ft		Width:	75 Ft			
Slabs:	210	Slab Length	ı:	25 Ft Slal	Width:		25 Ft	Join	t Length:	8,800 Ft
Shoulder:		Street Type	:	Gra	<b>de:</b> 0			Lane	es: 0	
Section Co	omments:									
Work Dat	e: 1/1/1995	Work	Type: BUIL	Т		Co	ode: IMPORTE	D I	Is Major M&	R: True
Work Dat	e: 1/1/2000	Work	Type: Surfa	ce Reconstruction - PC		Co	ode: SR-PC	]	ls Major M&	R: True
Last Insp.	Date: 4/29/2019	)	TotalSa	amples: 10		Surveye	<b>d:</b> 2			
Condition	s: PCI: 89									
Inspection	Comments:									
Sample N	umber: 119	Type:	R	Area:	21.	00 Slabs	PCI:	86		
Sample Co	omments:									
73 SH	RINKAGE CR		N	21.00 Slabs						
Sample N	umber: 124	Type:	R	Area:	21.	00 Slabs	PCI:	92		
	omments.									
Sample Co	omments.									

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW N TAXIWAY N Use: TAXIWAY 577,575 SqFt Name: Area: Section: 315 of 4 **Last Const.:** 1/1/1996 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 45,000 SqFt Length: 525 Ft Width: 75 Ft Slabs: 72 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 2,550 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1996 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 93 **Inspection Comments: PCI:** 93 Sample Number: 115 Type: R 25.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 5.00 Slabs 75 CORNER SPALL L 1.00 Slabs

1.00 Slabs

M

SMALL PATCH

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW P TAXIWAY P Use: TAXIWAY 409,293 SqFt Name: Area: 640 of 5 **Last Const.:** 1/1/1982 Section: From: To: -Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 60,825 SqFt Length: 811 Ft Width: 75 Ft Slabs: 97 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 3,980 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1982 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 5 Surveyed: 1 **Conditions: PCI:** 70 **Inspection Comments: PCI:** 70 Sample Number: 122 Type: R 21.00 Slabs Area: **Sample Comments:** 74 JOINT SPALL M 1.00 Slabs 75 CORNER SPALL L 1.00 Slabs L 66 SMALL PATCH 4.00 Slabs SHRINKAGE CR N 21.00 Slabs 73 74 JOINT SPALL L 4.00 Slabs

JT SEAL DMG

65

L

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW P TAXIWAY P Use: TAXIWAY Area: 409,293 SqFt Name: Section: 641 of 5 **Last Const.:** 1/1/1994 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P 8,909 SqFt Area: Length: 250 Ft Width: 75 Ft Slabs: 14 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,175 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1994 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 1 Surveyed: 1 **Conditions: PCI:** 87 **Inspection Comments: PCI:** 87 Sample Number: 120 Type: R 15.00 Slabs Area: **Sample Comments:** 

73

65

SHRINKAGE CR

JT SEAL DMG

N

L

11.00 Slabs

Network: JAX		Name:	JACKSONVILLE I	NTERNATIONAL	AIRPORT	
Branch: TW P	Name:	TAXIWAY P	Use:	TAXIWAY	Area:	409,293 SqFt
Section: 650	of 5 Fi	om: -		То: -		Last Const.: 1/1/1992
Surface: PCC	Family: C9N59-PR-RW	-TW-PCC Zone:		Category:		Rank: P
Area: 133,3	322 SqFt Length:	550 Ft	Width:	140 Ft		
<b>Slabs:</b> 413	Slab Length:	17 Ft Slab V	Width:	19 Ft	Joint Length	7,892 Ft
Shoulder:	Street Type:	Grade	e: 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/1992	Work Type: BUIL	Γ	Code	e: IMPORTED	Is Major	r M&R: True
<b>Last Insp. Date:</b> 4/29/201	19 TotalSa	mples: 19	Surveyed:	3		
Conditions: PCI: 96						
Inspection Comments:						
Sample Number: 105	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 96		
Sample Comments:						
74 JOINT SPALL	L	1.00 Slabs				
73 SHRINKAGE CR	N	3.00 Slabs				
Sample Number: 107	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 96		
Sample Comments:						
74 JOINT SPALL	L	1.00 Slabs				
73 SHRINKAGE CR	N	3.00 Slabs				
Sample Number: 109	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 97		
Sample Comments:						
75 CORNER SPALL	L	1.00 Slabs				
73 SHRINKAGE CR	N	2.00 Slabs				

Network:	JAX			Name:	JACKSONVILL	E INTERNATIONAL	AIRPORT	
Branch:	TW P		Name:	TAXIWAY P	Use:	TAXIWAY	Area:	409,293 SqFt
Section:	655	0	f 5	From: -		То: -		Last Const.: 1/1/1992
Surface:	PCC	Family:	C9N59-PR-R	W-TW-PCC Zone:		Category:		Rank: P
Area:	,	79,579 SqFt	Length	: 1,500 Ft	Width:	75 Ft		
Slabs:	246	Slab Len	igth:	17 Ft Sla	b Width:	19 Ft	Joint Lengt	<b>h:</b> 10,964 Ft
Shoulder	:	Street T	ype:	Gr	ade: 0		Lanes:	0
Section C	Comments:							
Work Da	te: 1/1/1992	W	ork Type: BU	ILT	C	ode: IMPORTED	Is Majo	r M&R: True
Last Insp	. Date: 4/29	/2019	Total	Samples: 15	Surveye	ed: 2		
Condition	ns: PCI:	94						
Inspection	n Comments:							
Sample N	lumber: 101	Туј	pe: R	Area:	20.00 Slabs	PCI: 97		
Sample C	Comments:							
66 SN	MALL PATCH	I	L	1.00 Slabs				
73 SI	HRINKAGE C	R	N	2.00 Slabs				
Sample N	umber: 108	Туј	oe: R	Area:	20.00 Slabs	<b>PCI:</b> 91		
Sample C	Comments:							
74 JC	OINT SPALL		L	1.00 Slabs				

Network: JAX		Name:	JACKSONVILLE IN	TERNATIONAL A	IRPORT	
Branch: TW P	Name:	TAXIWAY P	Use: TA	AXIWAY A	Area:	409,293 SqFt
Section: 660	of 5	om: -		То: -		<b>Last Const.:</b> 1/1/2013
Surface: PCC	Family: C9N59-PR-RW	-TW-PCC Zone:		Category:		Rank: P
<b>Area:</b> 126,6	558 SqFt Length:	1,050 Ft	Width:	100 Ft		
<b>Slabs:</b> 333	Slab Length:	19 Ft Slab W	Vidth: 20	Ft	Joint Length	9,626 Ft
Shoulder:	Street Type:	Grade	: 0		Lanes: 0	
<b>Section Comments:</b>						
Work Date: 1/1/2013	Work Type: New O	Construction - Initial	Code:	NU-IN	Is Major	M&R: True
<b>Last Insp. Date:</b> 4/29/201	19 TotalSa	mples: 19	Surveyed:	3		
Conditions: PCI: 99						
<b>Inspection Comments:</b>						
Sample Number: 112	Type: R	Area:	20.00 Slabs	<b>PCI:</b> 100		
Sample Comments:						
<no distress=""></no>						
Sample Number: 118	Type: R	Area:	25.00 Slabs	<b>PCI:</b> 100		
Sample Comments:						
<no distress=""></no>						
Sample Number: 122	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 97		
Sample Comments:						
66 SMALL PATCH	L	1.00 Slabs				
65 JT SEAL DMG	L	24.00 Slabs				

			Name:	JACKSONVILLI	E INTERNATION	NAL AIRPORT		
Branch: TW Q		Name: TAXI	WAY Q	Use:	TAXIWAY	Area:	115,700 SqFt	
Section: 560	of 1	From:	-		То: -		Last Const.:	1/1/1996
Surface: PCC	Family: C9N	59-PR-RW-TW-PCC	Zone:		Category:		Rank: P	
Area: 1	15,700 SqFt	Length:	690 Ft	Width:	90 Ft			
Slabs: 210	Slab Length:	22 Ft	Slab W	/idth:	25 Ft	Joint I	Length: 4,527 Ft	
Shoulder:	Street Type:		Grade:			Lanes:	_	
	Street Type.		Grade.	. 0		Lanes.	. 0	
<b>Section Comments:</b>								
Work Date: 1/1/1996	Work T	ype: New Construction	on - Initial	C	ode: NU-IN	Is	Major M&R: True	
I I D 1/20	/2010	T-4-101	0	6	1. 2			
Last Insp. Date: 4/29		TotalSamples:	9	Surveye	<b>a:</b> 2			
Conditions: PCI:	85							
<b>Inspection Comments:</b>								
		R A	Area:	30.00 Slabs	PCI:	82		
Sample Number: 100		R A	Area:	30.00 Slabs	PCI:	82		
Sample Number: 100 Sample Comments:	Type:			30.00 Slabs	PCI:	82		
Sample Number: 100 Sample Comments: 73 SHRINKAGE O	Type:	J 15.00	Slabs	30.00 Slabs	PCI:	82		
Sample Number: 100 Sample Comments: 73 SHRINKAGE C	Type:  CR N	N 15.00 L 6.00	Slabs Slabs	30.00 Slabs	PCI:	82		
Sample Number: 100 Sample Comments: 73 SHRINKAGE C 74 JOINT SPALL 66 SMALL PATCE	Type:  CR N L H L	N 15.00 6.00 3.00	Slabs Slabs	30.00 Slabs	PCI:	82		
Sample Number: 100 Sample Comments: 73 SHRINKAGE C 74 JOINT SPALL 66 SMALL PATCE	Type:  TR  I  L  L  L	15.00 2 6.00 3.00 3.00	Slabs Slabs Slabs	30.00 Slabs	PCI:			
Sample Number: 100 Sample Comments: 73 SHRINKAGE C 74 JOINT SPALL 66 SMALL PATCH 75 CORNER SPAL	Type:  TR  I  L  L  L	15.00 2 6.00 3.00 3.00	Slabs Slabs Slabs Slabs					
Sample Number: 100 Sample Comments: 73 SHRINKAGE C 74 JOINT SPALL 66 SMALL PATCH 75 CORNER SPAL Sample Number: 104 Sample Comments:	Type:  Type:  Type:  Type:	N 15.00 6.00 3.00 R A	Slabs Slabs Slabs Area:					
Sample Number: 100 Sample Comments: 73 SHRINKAGE C 74 JOINT SPALL 66 SMALL PATCH 75 CORNER SPAL Sample Number: 104 Sample Comments:	Type:  Type:  Type:  Type:	R 15.00 R 15.00 R 15.00 R 1.00	Slabs Slabs Slabs Slabs					
Sample Number: 100 Sample Comments: 73 SHRINKAGE C 74 JOINT SPALL 66 SMALL PATCH 75 CORNER SPAL Sample Number: 104 Sample Comments: 74 JOINT SPALL	Type:  Type:  Type:  Type:  Type:	R 1.00 R 1.00 R 1.00 R 1.00 R 8.00	Slabs Slabs Slabs Slabs					

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: 185,103 SqFt **Branch:** TW R TAXIWAY R Use: TAXIWAY Name: Area: Section: 570 of 3 **Last Const.:** 1/1/1996 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 43,767 SqFt Length: 380 Ft Width: 90 Ft Slabs: Slab Length: 22 Ft Slab Width: 25 Ft Joint Length: 80 2,453 Ft 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1996 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 4 Surveyed: 1 **Conditions: PCI:** 86 **Inspection Comments: PCI:** 86 Sample Number: 100 Type: R 33.00 Slabs Area: **Sample Comments:** 66 SMALL PATCH M 1.00 Slabs CORNER SPALL L 1.00 Slabs 75 SHRINKAGE CR N 73 12.00 Slabs JOINT SPALL 74 L 3.00 Slabs

1.00 Slabs

M

JOINT SPALL

Netwo	rk: JAX			Nar	me: JAC	KSONVILL	E INTERNATION.	AL AIRPORT	
Branc	h: TW R		Name:	TAXIWAY F	}	Use:	TAXIWAY	Area:	185,103 SqFt
Section	n: 575	of 3	Fı	rom: -			То: -		<b>Last Const.:</b> 1/1/19
Surfac	e: PCC	Family: C9N	59-PR-RW	-TW-PCC Zon	ne:		Category:		Rank: P
Area:	111,62	23 SqFt	Length:	1,210 1	Ft	Width:	75 Ft		
Slabs:	179	Slab Length:		25 Ft	Slab Width:		25 Ft	Joint Lengt	<b>h:</b> 5,975 Ft
Should	der:	Street Type:			Grade: 0			Lanes:	)
Section	n Comments:								
Work	<b>Date:</b> 1/1/1996	Work T	ype: BUIL	Γ		C	ode: IMPORTED	Is Majo	r M&R: True
Last I	nsp. Date: 4/29/201	9	TotalSa	mples: 7		Surveye	ed: 2		
Condi	tions: PCI: 88								
Inspec	ction Comments:								
Sampl	e Number: 101	Type:	R	Area:	32	2.00 Slabs	PCI: 8	39	
Sampl	e Comments:								
66	SMALL PATCH	I	,	1.00 Slabs					
74	JOINT SPALL	N	1	1.00 Slabs					
73	SHRINKAGE CR	N	1	12.00 Slabs					
74	JOINT SPALL	L	,	1.00 Slabs					
66	SMALL PATCH	N	1	1.00 Slabs					
Sampl	e Number: 104	Type:	R	Area:	21	.00 Slabs	PCI: 8	38	
Sampl	e Comments:								
73	SHRINKAGE CR	N	1	12.00 Slabs					
74	JOINT SPALL	L	,	2.00 Slabs					

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW R TAXIWAY R Use: TAXIWAY Area: 185,103 SqFt Name: Section: 576 of 3 **Last Const.:** 1/1/1991 From: To: -Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 29,713 SqFt Length: 240 Ft Width: 115 Ft Slabs: 48 Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,853 Ft **Street Type:** 0 Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1991 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 86 Sample Number: 107 Type: R 20.00 Slabs Area: **Sample Comments:** 

73

66

SHRINKAGE CR

SMALL PATCH

N

L

17.00 Slabs

Network:	: JAX			Nam	ie: JA	CKSONVIL	LE INTER	NATION	AL AIRP	ORT		
Branch:	TW S	N	Tame: T	AXIWAY S		Use:	: TAXI	WAY	Area	1:	168,716 SqFt	
Section:	1285	of 2	From:	-			To	: -			Last Const.:	1/1/1989
Surface:	PCC	Family: C9N5	9-PR-RW-TW-	-PCC Zone	e:		Ca	tegory:			Rank: P	
Area:	140,346	SqFt 1	Length:	1,385 F	t	Width:		75 Ft				
Slabs:	225	Slab Length:	2:	5 Ft	Slab Width:	•	25 Ft			Joint Length:	6,850 Ft	
Shoulder	:	Street Type:			Grade: 0	)				Lanes: 0		
Section C	Comments:											
Work Da	te: 1/1/1989	Work Typ	pe: BUILT				Code: IN	1PORTEI	)	Is Major	M&R: True	
Last Insp	Date: 4/29/2019		TotalSample	es: 12		Survey	yed: 3					
Condition	ns: PCI: 81											
Inspectio	n Comments:											
Sample N	Number: 101	Type:	R	Area:	2	20.00 Slabs		PCI:	83			
Sample C	Comments:											
70 SC	CALING	L		1.00 Slabs								
	HRINKAGE CR	N		0.00 Slabs								
	DINT SPALL	L		1.00 Slabs								
Sample N	Number: 105	Type:	R	Area:	2	21.00 Slabs		PCI:	82			
Sample C	Comments:											
	DINT SPALL	L		3.00 Slabs								
73 SI	HRINKAGE CR	N	2	1.00 Slabs								
Sample N	Number: 108	Type:	R	Area:	2	24.00 Slabs		PCI:	79			
Sample C	Comments:											
74 JC	DINT SPALL	L		4.00 Slabs								
	CALING	L		2.00 Slabs								
73 SI	HRINKAGE CR	N	24	4.00 Slabs								

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW S TAXIWAY S Use: TAXIWAY 168,716 SqFt Name: Area: Section: 1290 of 2 **Last Const.:** 1/1/1989 From: To: -Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 28,370 SqFt Length: 220 Ft Width: 100 Ft Slabs: Slab Length: 25 Ft Slab Width: 25 Ft Joint Length: 1,440 Ft 45 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1989 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 78 **Inspection Comments: PCI:** 78 Sample Number: 101 Type: R 27.00 Slabs Area: **Sample Comments:** 74 JOINT SPALL L 2.00 Slabs 74 JOINT SPALL L 1.00 Slabs 70 **SCALING** L 2.00 Slabs CORNER BREAK L Slabs 62 1.00

SHRINKAGE CR

SMALL PATCH

73

66

N

L

23.00

Slabs

Network: JAX				Name:	JACKSONVILL	E INTERNATION.	AL AIRPORT	
Branch: TW T		Name:	TAXIWA	AY T	Use:	TAXIWAY	Area:	59,457 SqFt
Section: 1282	of 1	Fı	om: -			То: -		Last Const.: 1/1/2012
Surface: PCC	Family: C91	N59-PR-RW	-TW-PCC	Zone:		Category:		Rank: P
Area:	59,457 SqFt	Length:	4	187 Ft	Width:	148 Ft		
<b>Slabs:</b> 149	Slab Length:		19 Ft	Slab Wid	lth:	21 Ft	Joint Length:	: 6,591 Ft
Shoulder:	Street Type:			Grade:	0		Lanes: 0	
Section Comments:								
Work Date: 1/1/2012	Work 7	Type: New C	Construction	- Initial	C	ode: NU-IN	Is Major	M&R: True
Last Insp. Date: 4/29	/2019	TotalSa	mples: 7		Surveye	<b>d:</b> 2		
Conditions: PCI:	97							
Conditions: PCI: Inspection Comments:								
Inspection Comments:		R	Are	ea:	20.00 Slabs	PCI:	98	
Inspection Comments: Sample Number: 102		R	Are	ea:	20.00 Slabs	PCI:	98	
Inspection Comments: Sample Number: 102 Sample Comments:	. Type:	R L	1.00 S		20.00 Slabs	PCI:	98	
Inspection Comments: Sample Number: 102 Sample Comments: 75 CORNER SPAL	Type:			labs	20.00 Slabs 25.00 Slabs	PCI: 9		
Inspection Comments: Sample Number: 102 Sample Comments: 75 CORNER SPAL Sample Number: 105	Type:	L	1.00 S	labs				
Inspection Comments: Sample Number: 102 Sample Comments:	Type:	L	1.00 S	labs				

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:** TW U TAXIWAY U Use: TAXIWAY 52,557 SqFt Name: Area: **Section:** 390 of 1 **Last Const.:** 1/1/1998 From: To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 52,557 SqFt Length: 488 Ft Width: 90 Ft Slabs: Slab Length: 22 Ft Slab Width: 25 Ft Joint Length: 96 3,175 Ft **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/1998 Work Type: BUILT Code: IMPORTED Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 5 Surveyed: 1 **Conditions: PCI:** 91 **Inspection Comments: PCI:** 91 Sample Number: 101 Type: R 28.00 Slabs Area: **Sample Comments:** 73 SHRINKAGE CR N 13.00 Slabs SMALL PATCH L 1.00 Slabs 66

JOINT SPALL

74

L

JACKSONVILLE INTERNATIONAL AIRPORT Network: JAX Name: **Branch:**  $TW\;V$ TAXIWAY V Use: TAXIWAY 78,127 SqFt Name: Area: Section: 905 of 1 From: **Last Const.:** 1/1/2013 To: Surface: PCC Family: C9N59-PR-RW-TW-PCC Zone: Category: Rank: P Area: 78,127 SqFt Length: 785 Ft Width: 100 Ft Slabs: 206 Slab Length: 19 Ft Slab Width: 20 Ft Joint Length: 7,172 Ft 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2013 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 4/29/2019 **TotalSamples:** 10 Surveyed: 2 **Conditions:** PCI: **Inspection Comments: PCI:** 100 Sample Number: 103 Type: R 20.00 Slabs Area: **Sample Comments:** <No Distress>

20.00 Slabs

**PCI:** 100

**Sample Comments:** 

Sample Number: 107

R

Area:

Type:

<No Distress>