

Statewide Airfield Pavement Management Program

**Airport Pavement
Evaluation Report
November 2019**



**Jacksonville Executive
at Craig Airport (CRG)**
Reliever Airport
District 2





Florida Department of Transportation

Statewide Airfield Pavement Management Program

Prepared by:

*FDOT Aviation and Spaceports Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*




OFFICE OF FREIGHT, LOGISTICS & PASSENGER OPERATIONS

Table of Contents


Executive Summary.....	10
Program Background.....	10
Summary of Results.....	11
Pavement Condition Index (Latest Inspection).....	11
Forecasted Pavement Condition Index 2020-2029	13
Major Rehabilitation Planning 2020-2029	15
Summary of Jacksonville Executive at Craig Airport	16
Chapter 1 – Introduction.....	18
1.1 Background	18
1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019	18
1.3 Organization.....	20
1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager.....	20
1.3.2 Participating Florida Public-Use and Publicly Owned Airports	20
1.3.3 Florida Department of Transportation District Offices	20
1.3.4 Consultant.....	20
1.4 Purpose of Airport Pavement Evaluation Report	22
1.5 History of the Program.....	22
1.6 Federal Aviation Administration (FAA)	24
1.7 FDOT SAPMP Objectives and Components	24
1.7.1 Program Objectives.....	24
1.7.2 Program Components	24
1.8 References	28
Chapter 2 – Methodology	30
2.1 Airfield Pavement Database.....	30
2.2 Airfield Pavement System Inventory	30
2.2.1 Pavement Management Program Network Definition Terminology	31
2.3 Airfield Pavement Structure.....	33
2.3.1 Pavement Structure Types	33
2.4 Airfield Pavement Work History	35
2.4.1 Airfield Pavement Record Keeping	35
2.5 Airfield Pavement Traffic.....	35
2.6 Airfield Pavement Condition Index (PCI) Survey.....	35
2.6.1 PCI Survey Methodology.....	35
2.6.2 Pavement Distress Types.....	37

2.6.3 PCI Survey Inspection Procedures	41
2.6.4 Updates to the ASTM D5340-12.....	42
Chapter 3 – Airfield Pavement System Inventory	45
3.1 Airfield Pavement Network Information	45
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	45
3.1.2 Estimated Pavement Age	47
3.1.3 Functional Use Classification.....	49
3.1.4 Pavement Surface Type	50
3.1.5 Pavement System Inventory Details	51
Chapter 4 – Airfield Pavement Condition	57
4.1 Airfield Pavement Condition Index (Latest Inspection)	57
4.1.1 Network-Level Analysis	57
4.1.2 Branch-Level Analysis.....	57
4.1.3 Section-Level Analysis	60
4.2 Summary of Pavement Condition Evaluation Results	64
4.2.1 Network-Level Observations.....	64
4.2.2 Branch-Level Observations	64
4.3 Forecasted Pavement Conditions	66
4.3.1 Performance Models and Prediction Curves	66
4.3.2 Branch-Level Pavement Condition Forecast	66
4.3.3 Section-Level Pavement Condition Forecast	68
4.3.4 Forecasted PCI Considerations	72
Chapter 5 – Localized Maintenance and Repair Planning.....	74
5.1 Localized Maintenance and Repair	74
5.2 Localized Maintenance and Repair Policy	75
5.3 Localized Maintenance and Repair Analysis and Recommendations	79
Chapter 6 – Major Rehabilitation Planning.....	84
6.1 Major Rehabilitation	84
6.1.1 Critical PCI.....	86
6.1.2 FDOT Recommended Minimum Service-Level PCI	86
6.2 Major Rehabilitation Policy	87
6.2.1 Major Rehabilitation Pavement Section Development	87
6.2.2 Major Rehabilitation Planning-Level Unit Costs.....	89
6.3 Major Rehabilitation Needs.....	89
6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs	89
Chapter 7 – Conclusion	95
7.1 Recommendations.....	95
7.1.1 Continued PCI Survey Inspections	95
7.1.2 Localized Maintenance and Repair.....	95

7.1.3 Major Rehabilitation.....	95
7.1.4 Pavement Management System.....	95
7.2 Supporting Documents	96
001 – Airfield Pavement Network Definition Exhibit	96
002 – Airfield Pavement System Inventory Exhibit.....	96
003 – Airfield Pavement Condition Index Exhibit.....	96
004 – Airfield Pavement Major Rehabilitation Exhibit.....	96
Inspection Photograph Documentation.....	96
7.3 Conclusion	97



Appendix A	Airfield Pavement Analysis Tables
Appendix B	Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation
Appendix C	Technical Exhibits
Appendix D	Inspection Photograph Documentation
Appendix E	Inspection Distress Details



List of Figures

<i>Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029.....</i>	<i>16</i>
<i>Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts.....</i>	<i>19</i>
<i>Figure 1.7.2 (a) Typical Pavement Condition Life Cycle.....</i>	<i>25</i>
<i>Figure 1.7.2 (b) General Pavement Treatments by Condition Range</i>	<i>26</i>
<i>Figures 1.7.2 (c) Flexible Asphalt Concrete</i>	<i>27</i>
<i>Figures 1.7.2 (d) Rigid Portland Cement Concrete</i>	<i>27</i>
<i>Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit</i>	<i>46</i>
<i>Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit.....</i>	<i>47</i>
<i>Figure 3.1.2 Average Age of Pavements at Inspection.....</i>	<i>48</i>
<i>Figure 3.1.3 Airfield Pavement Functional Classification Use by Area</i>	<i>49</i>
<i>Figure 3.1.4 (a) Pavement Surface Type by Area (SF)</i>	<i>50</i>
<i>Figure 3.1.4 (b) Pavement Surface Type by Area (%)</i>	<i>51</i>
<i>Figure 4.1.1 Latest Condition – Overall Network</i>	<i>57</i>
<i>Figure 4.1.2 (a) Latest Condition – Runway Pavements.....</i>	<i>58</i>
<i>Figure 4.1.2 (b) Latest Condition – Taxiway Pavements</i>	<i>58</i>
<i>Figure 4.1.2 (c) Latest Condition – Apron Pavements</i>	<i>59</i>
<i>Figure 4.1.2 (d) Latest Condition – Taxilane Pavements</i>	<i>59</i>
<i>Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit.....</i>	<i>63</i>
<i>Figure 4.2.2 Pavement Condition Summary by Facility Use</i>	<i>65</i>
<i>Figure 4.3.2 (a) Forecasted Runway Pavement Performance</i>	<i>66</i>
<i>Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance.....</i>	<i>67</i>
<i>Figure 4.3.2 (c) Forecasted Apron Pavement Performance</i>	<i>67</i>
<i>Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, $PCI \leq$ Critical PCI.....</i>	<i>84</i>
<i>Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, $PCI >$ Critical PCI</i>	<i>85</i>
<i>Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year</i>	<i>92</i>
<i>Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit.....</i>	<i>93</i>

List of Tables

<i>Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level.....</i>	<i>11</i>
<i>Table E-2 Pavement Condition Index Forecast 2020-2029</i>	<i>13</i>
<i>Table E-3 Major Rehabilitation Planning 2020-2029</i>	<i>15</i>
<i>Table 2.2.1 Airfield Pavement Database Network Definition Terminology.....</i>	<i>32</i>
<i>Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>37</i>
<i>Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>38</i>
<i>Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields</i>	<i>38</i>
<i>Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>39</i>
<i>Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>40</i>
<i>Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields</i>	<i>40</i>
<i>Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete</i>	<i>41</i>
<i>Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete</i>	<i>41</i>
<i>Table 2.6.4 Summary of Updates to ASTM D5340-12</i>	<i>43</i>
<i>Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction</i>	<i>45</i>
<i>Table 3.1.5 Pavement System Inventory Details</i>	<i>52</i>
<i>Table 4.1.3 Latest Pavement Condition Index Summary</i>	<i>61</i>
<i>Table 4.3.3 Forecasted PCI 2020-2029.....</i>	<i>69</i>
<i>Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete</i>	<i>75</i>
<i>Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete</i>	<i>76</i>
<i>Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete</i>	<i>78</i>

<i>Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete</i>	<i>78</i>
<i>Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level</i>	<i>79</i>
<i>Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level</i>	<i>80</i>
<i>Table 5.3 (c) Summary of Localized Maintenance</i>	<i>82</i>
<i>Table 6.1.2 FDOT Recommended Minimum Service-Level PCI.....</i>	<i>86</i>
<i>Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete</i>	<i>87</i>
<i>Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete</i>	<i>88</i>
<i>Table 6.2.2 Reliever (RL) Major Rehabilitation Planning-Level Unit Cost by Pavement Type</i>	<i>89</i>
<i>Table 6.3.1 10-Year Major Rehabilitation Needs</i>	<i>91</i>





Executive Summary



Executive Summary

Program Background

Airport airfield pavement infrastructure facilities represent a large capital investment in the Florida Airport System. Timely and appropriate maintenance and strategic rehabilitation are essential as repair costs increase significantly in proportion to deterioration. Airport pavement distresses can also contribute to the development of loose debris and decreased ride quality, which can be a safety concern for aircraft operations.

In 2016, the Florida Department of Transportation (FDOT) Aviation and Spaceports Office (ASO) selected Kimley-Horn and Associates, Inc. with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2016 through fiscal year 2019. The SAPMP has 95 public use airport facilities throughout the seven FDOT Districts that participate in the system update. The results of this system update for this specific airport are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP)”** using the documented procedures set forth by ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Pavement deterioration, in accordance with the ASTM D5340-12, was characterized in terms of distinct distress types, severity level of distress, and quantity of distress. This information is utilized to calculate a PCI numeric that represents the overall condition of the pavement in a numeric index that ranges from 0 (a condition category of FAILED) to 100 (GOOD). The PCI methodology analyzes an overall measure of the pavement condition and provides an indication of the degree of maintenance, repair, or rehabilitation efforts that will be required to sustain functional pavement.

The tasks required for the system update at each participating airport consist of the following:

- Obtain recent and anticipated airfield pavement construction work data.
- Update airport airfield pavement system inventory records (construction history, identification, geometry, and facility classification).
- Perform PCI Survey Inspections at each participating airport.
- Update the FDOT SAPMP PAVER™ database system.
- Update the FDOT SAPMP GIS Airfield Navigation GPS enabled Maps.
- Update airfield pavement performance models and pavement condition forecasting.
- Identification of planning-level maintenance, repair, and major rehabilitation to address pavement needs based on functional PCI analysis.
- Development of planning-level opinion of probable construction costs for pavement rehabilitation.



Summary of Results

Pavement Condition Index (Latest Inspection)

Table E-1 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
CRG	RUNWAY 5-23	RUNWAY	6105	363,800	68	Fair
CRG	RUNWAY 5-23	RUNWAY	6110	25,800	100	Good
CRG	RUNWAY 14-32	RUNWAY	6205	45,000	100	Good
CRG	RUNWAY 14-32	RUNWAY	6210	355,800	100	Good
CRG	TAXIWAY A	TAXIWAY	105	74,656	57	Fair
CRG	TAXIWAY A	TAXIWAY	110	6,423	100	Good
CRG	TAXIWAY A	TAXIWAY	120	37,712	72	Satisfactory
CRG	TAXIWAY A1	TAXIWAY	130	22,201	84	Satisfactory
CRG	TAXIWAY A2	TAXIWAY	132	3,131	69	Fair
CRG	TAXIWAY A2	TAXIWAY	135	6,046	57	Fair
CRG	TAXIWAY A3	TAXIWAY	142	13,123	100	Good
CRG	TAXIWAY A3	TAXIWAY	145	4,606	72	Satisfactory
CRG	TAXIWAY A3	TAXIWAY	150	4,850	81	Satisfactory
CRG	TAXIWAY A4	TAXIWAY	160	5,193	66	Fair
CRG	TAXIWAY A4	TAXIWAY	165	5,091	100	Good
CRG	TAXIWAY A5	TAXIWAY	170	5,011	100	Good
CRG	TAXIWAY A5	TAXIWAY	175	5,069	55	Poor
CRG	TAXIWAY A5	TAXIWAY	180	8,126	64	Fair
CRG	TAXIWAY A5	TAXIWAY	185	13,533	100	Good
CRG	TAXIWAY B	TAXIWAY	215	29,838	77	Satisfactory
CRG	TAXIWAY B	TAXIWAY	225	59,500	55	Poor
CRG	TAXIWAY B	TAXIWAY	227	5,899	70	Fair
CRG	TAXIWAY B	TAXIWAY	230	3,679	81	Satisfactory
CRG	TAXIWAY B	TAXIWAY	235	26,915	68	Fair
CRG	TAXIWAY B1	TAXIWAY	210	7,110	59	Fair
CRG	TAXIWAY B2	TAXIWAY	220	3,863	81	Satisfactory
CRG	TAXIWAY B2	TAXIWAY	240	11,812	69	Fair
CRG	TAXIWAY B2	TAXIWAY	242	4,802	82	Satisfactory
CRG	TAXIWAY B2	TAXIWAY	243	6,422	42	Poor
CRG	TAXIWAY B3	TAXIWAY	244	3,380	70	Fair
CRG	TAXIWAY B4	TAXIWAY	245	9,056	31	Very Poor
CRG	TAXIWAY B4	TAXIWAY	250	15,426	67	Fair
CRG	TAXIWAY B4	TAXIWAY	265	3,169	80	Satisfactory
CRG	TAXIWAY B5	TAXIWAY	255	4,433	51	Poor



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
CRG	TAXIWAY B5	TAXIWAY	260	5,545	80	Satisfactory
CRG	TAXIWAY C	TAXIWAY	305	24,696	100	Good
CRG	TAXIWAY C	TAXIWAY	310	5,648	100	Good
CRG	TAXIWAY C	TAXIWAY	320	16,569	57	Fair
CRG	TAXIWAY D	TAXIWAY	455	12,087	80	Satisfactory
CRG	TAXIWAY D	TAXIWAY	460	29,215	78	Satisfactory
CRG	TAXIWAY E	TAXIWAY	505	14,164	100	Good
CRG	TAXIWAY F	TAXIWAY	605	9,632	100	Good
CRG	TAXIWAY F	TAXIWAY	610	5,562	100	Good
CRG	TAXIWAY G	TAXIWAY	765	65,079	73	Satisfactory
CRG	TAXIWAY G	TAXIWAY	770	9,691	75	Satisfactory
CRG	TAXILANE A3	TAXILANE	153	69,029	100	Good
CRG	TAXILANE A3	TAXILANE	155	19,174	79	Satisfactory
CRG	SOUTH APRON	APRON	4105	185,265	100	Good
CRG	SOUTH APRON	APRON	4115	15,813	100	Good
CRG	NORTH APRON	APRON	4205	24,445	100	Good
CRG	NORTH APRON	APRON	4210	265,650	100	Good
CRG	NORTH APRON	APRON	4215	22,406	100	Good
CRG	NORTH APRON	APRON	4220	27,322	30	Very Poor
CRG	NW APRON	APRON	4305	41,023	63	Fair
CRG	NW APRON	APRON	4310	204,437	100	Good
CRG	NW APRON	APRON	4320	56,781	100	Good
CRG	SOUTHWEST APRON	APRON	4405	8,887	12	Serious
CRG	SOUTHWEST APRON	APRON	4406	2,417	86	Good
CRG	SOUTHWEST APRON	APRON	4407	14,286	56	Fair
CRG	SOUTHWEST APRON	APRON	4410	12,829	100	Good
CRG	SOUTHWEST APRON	APRON	4415	23,211	68	Fair
CRG	SOUTHWEST APRON	APRON	4420	12,167	67	Fair
CRG	SOUTHWEST APRON	APRON	4430	4,074	26	Very Poor
CRG	SOUTHWEST APRON	APRON	4435	20,729	74	Satisfactory
CRG	FAA APRON	APRON	4505	147,450	80	Satisfactory
CRG	FAA APRON	APRON	4510	6,400	78	Satisfactory
CRG	RUN-UP APRON AT RW 23	APRON	5105	12,030	73	Satisfactory
CRG	RUN-UP APRON AT RW 23	APRON	5110	6,117	100	Good
CRG	RUN-UP APRON AT RW 5	APRON	5205	22,135	77	Satisfactory
CRG	RUN-UP APRON AT RW 14	APRON	5310	24,645	71	Satisfactory



Forecasted Pavement Condition Index 2020-2029

Table E-2 Pavement Condition Index Forecast 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
CRG	AP FAA	4505	80	78	76	74	73	71	69	68	66	65	64
CRG	AP FAA	4510	78	77	75	74	73	72	70	69	68	66	65
CRG	AP N	4205	100	96	94	92	90	88	85	83	81	79	77
CRG	AP N	4210	100	96	94	92	90	88	85	83	81	79	77
CRG	AP N	4215	100	96	94	91	89	87	85	82	80	78	76
CRG	AP N	4220	30	29	29	29	28	28	28	27	27	27	26
CRG	AP NW	4305	63	62	61	60	59	58	57	57	56	55	54
CRG	AP NW	4310	100	96	94	92	90	88	85	83	81	79	77
CRG	AP NW	4320	100	96	94	92	90	88	85	83	81	79	77
CRG	AP RU RW 5	5205	77	75	73	72	70	68	67	66	64	63	62
CRG	AP RU RW14	5310	71	69	67	65	63	60	58	56	54	52	50
CRG	AP RU RW23	5105	73	71	70	68	67	65	64	63	62	61	60
CRG	AP RU RW23	5110	100	97	95	93	91	89	86	84	82	80	78
CRG	AP S	4105	100	96	94	92	90	88	85	83	81	79	77
CRG	AP S	4115	100	96	94	92	90	88	85	83	81	79	77
CRG	AP SW	4405	12	11	9	8	7	6	4	3	2	0	0
CRG	AP SW	4406	86	85	83	82	81	80	78	77	76	74	73
CRG	AP SW	4407	56	55	54	54	53	52	51	51	50	49	48
CRG	AP SW	4410	100	97	95	93	91	89	86	84	82	80	78
CRG	AP SW	4415	68	67	65	64	63	62	61	60	59	58	57
CRG	AP SW	4420	67	66	64	63	62	61	60	59	58	58	57
CRG	AP SW	4430	26	25	25	25	24	24	23	23	23	22	22
CRG	AP SW	4435	74	72	70	68	66	63	61	59	57	55	53
CRG	RW 14-32	6205	100	97	94	92	89	87	85	83	81	80	78
CRG	RW 14-32	6210	100	97	94	92	89	87	85	83	81	80	78
CRG	RW 5-23	6105	68	67	66	65	64	64	63	62	61	61	60
CRG	RW 5-23	6110	100	97	94	92	89	87	85	83	81	80	78
CRG	TL A3	153	100	98	96	94	93	91	89	88	86	85	83
CRG	TL A3	155	79	78	76	75	73	72	71	69	68	67	66
CRG	TW A	105	57	56	55	54	53	52	51	51	50	48	47
CRG	TW A	110	100	97	95	92	90	88	86	84	83	81	79
CRG	TW A	120	72	71	69	68	67	66	64	63	62	61	60
CRG	TW A1	130	84	82	81	80	78	77	75	74	73	71	70
CRG	TW A2	132	69	68	67	66	65	64	63	62	61	61	60
CRG	TW A2	135	57	56	55	54	53	52	51	50	49	48	48



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
CRG	TW A3	142	100	97	95	92	90	88	86	84	83	81	79
CRG	TW A3	145	72	71	69	68	67	66	64	63	62	61	60
CRG	TW A3	150	81	79	78	76	75	74	72	71	70	69	68
CRG	TW A4	160	66	65	64	63	62	61	61	60	59	58	57
CRG	TW A4	165	100	96	94	91	89	87	85	84	82	80	79
CRG	TW A5	170	100	96	94	91	89	87	85	84	82	80	79
CRG	TW A5	175	55	54	53	52	51	50	49	48	47	46	44
CRG	TW A5	180	64	63	62	61	60	60	59	58	57	56	56
CRG	TW A5	185	100	97	95	92	90	88	86	84	83	81	79
CRG	TW B	215	77	76	74	73	71	70	69	68	66	65	64
CRG	TW B	225	55	54	53	52	51	50	49	48	47	46	44
CRG	TW B	227	70	69	68	67	66	65	64	63	62	61	61
CRG	TW B	230	81	79	78	76	75	74	72	71	70	69	68
CRG	TW B	235	68	67	65	64	63	62	61	60	59	57	56
CRG	TW B1	210	59	58	57	56	55	54	53	52	51	50	49
CRG	TW B2	220	81	79	78	76	75	74	72	71	70	69	68
CRG	TW B2	240	69	68	66	65	64	63	62	61	59	58	57
CRG	TW B2	242	82	80	79	77	76	75	73	72	71	70	69
CRG	TW B2	243	42	41	39	37	36	34	32	30	28	26	24
CRG	TW B3	244	70	69	68	67	66	65	64	63	62	61	61
CRG	TW B4	245	31	29	27	25	23	21	19	17	14	12	10
CRG	TW B4	250	67	66	65	64	63	62	61	61	60	59	58
CRG	TW B4	265	80	78	77	76	74	73	72	71	69	68	67
CRG	TW B5	255	51	50	49	48	47	47	46	45	44	44	43
CRG	TW B5	260	80	79	77	76	74	73	72	70	69	68	66
CRG	TW C	305	100	97	95	92	90	88	86	84	83	81	79
CRG	TW C	310	100	97	95	92	90	88	86	84	83	81	79
CRG	TW C	320	57	56	55	54	53	52	51	51	50	48	47
CRG	TW D	455	80	79	77	76	74	73	72	70	69	68	66
CRG	TW D	460	78	77	75	74	72	71	70	69	67	66	65
CRG	TW E	505	100	97	95	92	90	88	86	84	83	81	79
CRG	TW F	605	100	97	95	92	90	88	86	84	83	81	79
CRG	TW F	610	100	97	95	92	90	88	86	84	83	81	79
CRG	TW G	765	73	72	70	69	68	66	65	64	63	62	61
CRG	TW G	770	75	74	72	71	70	68	67	66	65	63	62




Major Rehabilitation Planning 2020-2029

Table E-3 Major Rehabilitation Planning 2020-2029

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	CRG	AP N	4220	AC	27,322	29	AC Reconstruction	\$ 342,000.00
2020	CRG	AP NW	4305	AC	41,023	62	AC Restoration	\$ 390,000.00
2020	CRG	AP SW	4405	PCC	8,887	11	PCC Reconstruction	\$ 178,000.00
2020	CRG	AP SW	4407	AC	14,286	55	AC Restoration	\$ 136,000.00
2020	CRG	AP SW	4430	AC	4,074	25	AC Reconstruction	\$ 51,000.00
2020	CRG	TW A	105	AAC	74,656	56	AC Restoration	\$ 710,000.00
2020	CRG	TW A2	135	AC	6,046	56	AC Restoration	\$ 58,000.00
2020	CRG	TW A5	175	AAC	5,069	54	AC Restoration	\$ 49,000.00
2020	CRG	TW A5	180	AAC	8,126	63	AC Restoration	\$ 78,000.00
2020	CRG	TW B	225	AAC	59,500	54	AC Restoration	\$ 566,000.00
2020	CRG	TW B1	210	AC	7,110	58	AC Restoration	\$ 68,000.00
2020	CRG	TW B2	243	AAC	6,422	41	AC Restoration	\$ 79,000.00
2020	CRG	TW B4	245	AAC	9,056	29	AC Reconstruction	\$ 114,000.00
2020	CRG	TW B5	255	AC	4,433	50	AC Restoration	\$ 43,000.00
2020	CRG	TW C	320	AAC	16,569	56	AC Restoration	\$ 158,000.00
2021	CRG	AP SW	4420	AC	12,167	64	AC Restoration	\$ 116,000.00
2021	CRG	TW A4	160	AAC	5,193	64	AC Restoration	\$ 50,000.00
2022	CRG	AP SW	4415	AC	23,211	64	AC Restoration	\$ 221,000.00
2022	CRG	TW B	235	AC	26,915	64	AC Restoration	\$ 256,000.00
2022	CRG	TW B4	250	AAC	15,426	64	AC Restoration	\$ 147,000.00
2023	CRG	AP RU RW14	5310	AAC	24,645	63	AC Restoration	\$ 235,000.00
2023	CRG	RW 5-23	6105	AAC	363,800	64	AC Restoration	\$ 3,457,000.00
2023	CRG	TW B2	240	AC	11,812	64	AC Restoration	\$ 113,000.00
2024	CRG	AP SW	4435	AAC	20,729	63	AC Restoration	\$ 197,000.00
2024	CRG	TW A2	132	AAC	3,131	64	AC Restoration	\$ 30,000.00
2025	CRG	AP RU RW23	5105	AC	12,030	64	AC Restoration	\$ 115,000.00
2025	CRG	TW A	120	AC	37,712	64	AC Restoration	\$ 359,000.00
2025	CRG	TW A3	145	AC	4,606	64	AC Restoration	\$ 44,000.00
2025	CRG	TW B	227	AAC	5,899	64	AC Restoration	\$ 57,000.00
2025	CRG	TW B3	244	AAC	3,380	64	AC Restoration	\$ 33,000.00
2026	CRG	TW G	765	AC	65,079	64	AC Restoration	\$ 619,000.00
2027	CRG	AP RU RW 5	5205	AC	22,135	64	AC Restoration	\$ 211,000.00
2028	CRG	TW G	770	AC	9,691	63	AC Restoration	\$ 93,000.00
2029	CRG	AP FAA	4505	AC	147,450	64	AC Restoration	\$ 1,401,000.00
2029	CRG	TW B	215	AC	29,838	64	AC Restoration	\$ 284,000.00

*All planning cost values have been rounded to the nearest thousand-dollar.


*Figure E-4 Major Rehabilitation Planning Annual Budget 2020-2029*

Summary of Jacksonville Executive at Craig Airport

Jacksonville Executive at Craig Airport was inspected in May of 2019 – the overall weighted PCI value was 84, a condition rating of Satisfactory. The results of the maintenance, repair, and major rehabilitation analysis identified \$276,690 in localized M&R needs based on current conditions and a 10-Year major rehabilitation need of \$11,058,000 based on forecasted conditions. The current major rehabilitation needs based on the latest inspection consist of \$3,020,000 for pavements below critical condition.

Localized maintenance and repair identified within this report are categorized as preventive or stopgap; the FDOT SAPMP has defined maintenance policies based on FAA recommendations. Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Such activities could include: mill and hot-mix asphalt overlay, rigid pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the airport use this as a planning tool for future project development and prioritization – all localized maintenance and repair and major rehabilitation recommendations should be considered as planning-level only. All final localized maintenance, repair, and major rehabilitation is subject to change based on airport prioritization and further design-level evaluation.

Chapter 1





Chapter 1 – Introduction

1.1 Background

The State of Florida has 128 public airports of which 100 public-use airports are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS) that are vital to the Florida economy as well as the economy of the United States. The Florida Aviation System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the entire State. Air travel is essential to tourism, Florida's number one industry.

There are millions of square feet of pavement infrastructure that consists of runways, taxiways, aprons, ramps, and other areas of airports that are vital to the support and safety of aircraft operations. Timely pavement maintenance, repair and major rehabilitation of these pavements will support the airport in operating safely, efficiently, economically and without excessive down time.


In general, adherence to the FAA Advisory Circulars are mandatory for all projects funded with federal grant monies through the Airport Improvement Program (AIP) and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The Florida Department of Transportation (FDOT) performs the Statewide Airfield Pavement Management Program (SAPMP) System Updates for the benefit of participating public-use and publicly owned airports through the Aviation and Spaceports Office (ASO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for the participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and pavement facilities that are subject for project consideration. A network-level evaluation can be supportive in the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

1.2 Statewide Airfield Pavement Management Program (SAPMP) Update 2018-2019

In 1992, the FDOT established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation and Spaceport Offices, and airport operators a system to proactively manage airport airfield pavement infrastructure within the Florida Aviation System. The SAPMP performs network-level Pavement Condition Index (PCI) survey inspections for airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Commercial (PR). Currently, the program consists of 95 actively participating public-use airports with pavement facilities and provides users with comprehensive data to better manage pavement assets.

Figure 1.2 Florida Aviation System (Facilities with Pavement) and FDOT Districts



In 2016, the Florida Department of Transportation Aviation and Spaceports Office contracted Kimley-Horn and Associates, Inc. along with subconsultants Airfield Pavement Management Systems, LLC and AVCON, Inc. to provide professional services in support of FDOT in the continued efforts of performing a system update to the SAPMP. This work is to be completed from fiscal year 2016 through fiscal year 2019.



1.3 Organization

1.3.1 Florida Department of Transportation Aviation and Spaceports Office Program Manager

The FDOT Aviation and Spaceports Office (ASO) Aviation Engineering Manager serves as the Program Manager (ASO-PM) for the SAPMP. The ASO-PM monitors the work performed by the designated Consultant for the program. The ASO-PM has review and approval authority for each program task and manages the program's day-to-day details and pertinent updates.

The ASO-PM reports updates and milestones to the FDOT State Aviation and Spaceports Manager and Development Administrator.

1.3.2 Participating Florida Public-Use and Publicly Owned Airports

The airports are the end-user and beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."** Individual participating airports will be provided a final Airport Pavement Evaluation Report by the designated Consultant that is specific to each airport's airfield pavement condition index survey. The ASO-PM has full authority and final approval of each report prior to finalization. In advance of each PCI survey and prior to completion of each Airport Pavement Evaluation Report, participating airports are asked to provide the necessary record documentation for the proper analysis efforts. Relevant record documentation artifacts may consist of but are not limited to: Airport Layout Plans (ALP), Construction Bid Tabulations, As-Built Construction Drawings, Engineer's Reports, and/or field pavement inspection reports.

1.3.3 Florida Department of Transportation District Offices

The seven (7) FDOT District Offices, specifically the Aviation representatives (currently the Freight and Logistics personnel), provide essential support to the SAPMP update and the ASO-PM. Each District supports the SAPMP's on-going efforts by providing local construction cost information throughout the State. The construction cost information, typically consisting of plans and bid tabulations, are used as the basis of the development maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. Each District Office receives copies of individual Airport Pavement Evaluation Reports for the participating airport facilities located within their respective Districts.

1.3.4 Consultant

The Consultant, Kimley-Horn and Associates, Inc., provides technical and administrative support to the ASO-PM for the SAPMP update. The support consists of airfield pavement system inventory updates, performance of PCI Surveys in accordance with ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys,"** evaluation and reporting of the pavement condition in accordance with the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP)."**

The Consultant Team consists of Kimley-Horn, Airfield Pavement Management Systems, LLC., and AVCON, Inc.



A brief description of the general scope of work undertaken to update the SAPMP includes but is not limited to:

- ▶ **Research and evaluation of existing record documentation** was performed to identify construction projects that have taken place since the most recent major update of the SAPMP. This data is used to update the pavement inventory and network definition.
- ▶ **An update to the existing Network Definition Map** was made to reflect geometric changes, pavement composition updates, and section characterization. Furthermore, an update to the PCI Survey sample units were made to reflect the field investigation efforts.
- ▶ **A functional pavement evaluation with PCI Survey inspections** was completed on all airfield pavements maintained by the Airport. The PCI Survey procedure, as defined by ASTM D5340-12, was used as the basis of the functional pavement evaluation. For this specific evaluation, the sample units defined by prior studies were inspected as to better develop performance models for prediction curves. Pavement subject to construction or anticipated construction during scheduled PCI Survey inspection or within 2 years were omitted from inspection based on confirmation of airport personnel.
- ▶ **Condition Analysis** was performed based on the distress data observed, rated, measured, and recorded in accordance with the ASTM D5340-12 for the calculation of PCI values and ratings. The results of the current condition analysis were used in concert with the historic PCI Survey data and construction work history to develop performance models to forecast future PCI values for each section for a 10-year study duration.
- ▶ **Maintenance, Repair, and Rehabilitation Planning** was performed predicated on the results of the condition analysis with updated policies and planning-level unit costs. The policies, or M&R policies, have been updated to reflect standard practices for maintenance, repair, and major rehabilitation as defined by the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** Planning-level unit costs were developed based on representative construction bid tabulations provided by participating airports. The bid tabulations consisted of limited airfield pavement construction projects that took place between 2009 and 2015 at participating airports.



1.4 Purpose of Airport Pavement Evaluation Report

The individual airport airfield pavement evaluation report discusses the work performed, a summary of findings, condition analysis results, and recommendations for maintenance, repair, and major rehabilitation (M&R) planning associated with the SAPMP system update. It also briefly describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, schedules, and safety requirements were implemented during the performance of this work.

The purpose of this Airfield Pavement Evaluation Report is to achieve the following:

- Describe the goals, procedures, and purpose of the SAPMP
- Provide a brief technical explanation of the pavement management methodology, standard practices, and objectives
- Analyze pavement distresses data for the determination of pavement conditions and for identification of airfield pavement maintenance, repair, and major rehabilitation needs based on functional PCI trends

The identification of rehabilitation needs has been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19; the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with FAA **AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT Statewide Airfield Pavement Management Program is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

1.5 History of the Program

In 1992, the FDOT implemented the SAPMP to understand the pavement conditions at public airports in the FAS, systematically update pavement infrastructure information, and assist airport operators with recommendations of pavement maintenance, repair, and major rehabilitation needs. The 1992 SAPMP implementation provided the FDOT and the participating airports valuable information for establishing and performing timely and appropriate pavement rehabilitation.



During the 1992-1993 implementation and again during the 1998-1999 updates; the SAPMP performed the development with proprietary software for pavement management system analysis. This development allowed for the creation of pavement management database file system populated with airport attributes and condition data. The pavement management database was used to establish maintenance, repair, and rehabilitation policies; consider planning-level unit costs; and develop recommendations for performing pavement maintenance. This system, known as AIRPAV, was initially developed during the 1992-1993 SAPMP implementation for the analysis of distress data. The AIRPAV system was used again in the 1998-1999 SAPMP update.

In 2004, the SAPMP system update included the review of the AIRPAV software compared to other industry available non-proprietary software packages. As a result of this review, MicroPAVER™ (currently known as PAVER™) was selected for implementation of the system update. MicroPAVER™ was developed by the U.S. Army Corps of Engineers Construction Engineering Research Laboratory for pavement management. Data from the 1998-1999 FDOT SAPMP update, which was built upon the initial 1992-1993 implementation of AIRPAV, was reviewed and converted to be compatible with the MicroPAVER™ system. This data conversion included all documented pavement facilities, classifications, types, histories, geometries, PCI condition data and pertinent attributes gathered from airport feedback at the time. This information was used to develop the inventory of each participating airport's pavement facilities in a consistent format. This was the development of Airfield Pavement Network Definition Exhibits. These inventory exhibits visually depicted the branch, section, and sample units that were based upon the pavement construction history and composition information provided by each airport.

In the 2006-2008 system update, the SAPMP was updated again with continued use of the MicroPAVER™ system. Based on the distress data collected, a maintenance repair and major rehabilitation planning program was developed for each airport. As part of this SAPMP update, the procedures for the inspection and the collection of the pavement distress data were documented, and an interactive website (<http://www.dot.state.fl.us/aviation/pavement.shtm>) was established for input of data.

In the 2010-2012 system update, the SAPMP was updated using new global positioning system (GPS) integrated technology to digitally collect pavement distress data. Interactive geographic information system (GIS) map files were developed from updated Airfield Pavement Network Definition Exhibits to aid pavement condition inspectors in the collection of sample distress data. The data collected was utilized to develop pavement performance models to predict future pavement PCI values and make recommendations for major rehabilitation.

In the 2013-2015 system update, the SAPMP integrated PAVER™ and FieldInspector™ with the use of GPS and GIS capable field tablets. Furthermore, the update included continued adherence to the ASTM **D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys."** The ASTM update consisted of refinement of distress definition types and deduction values for select asphalt concrete and Portland Cement Concrete distresses.



1.6 Federal Aviation Administration (FAA)

Currently, airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program to be eligible for funding (FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and **150/5380-7B “Airport Pavement Management Program (PMP)”**). This program requires detailed inspection of airfield pavement conditions by trained personnel. The inspections are required to be performed at least once a year using the PASER method or every three years if the pavement is inspected as defined by the PCI survey procedure in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

In general, adherence to the Advisory Circulars are mandatory for all projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.”

1.7 FDOT SAPMP Objectives and Components

The FDOT SAPMP is a program that provides the FAS support in implementing and/or maintaining a network-level Pavement Management Program in a consistent and regularly scheduled manner.

In accordance with FAA AC **150/5380-7B “Airport Pavement Management Program (PMP)”** an effective Pavement Management Program consists of a system that achieves specific objectives. The FDOT SAPMP objectives are as follows:

1.7.1 Program Objectives

- 1 A systematic means for collecting and storing information regarding existing pavement structure and condition.
- 2 An objective and repeatable system for evaluating pavement condition.
- 3 Procedures for predicting future pavement condition.
- 4 Procedures for modeling both past and future pavement performance conditions.
- 5 Procedures to determine the budget requirements to meet management objectives, such as the maintenance, repair, and major rehabilitation budget required to keep a pavement at a specified PCI level or the budget required to improve to target PCI level.
- 6 Procedures for formulating and prioritizing maintenance, repair, and major rehabilitation projects.

The objectives are accomplished by the following components:

1.7.2 Program Components

- A. Database
- B. Pavement Inventory
- C. Pavement Structure
- D. Pavement Work History
- E. Pavement Condition Data




F. Pavement Performance Modeling for the Prediction/Forecast of PCI

G. Maintenance, Repair, and Major Rehabilitation Policies and Budget Simulation

A well-maintained network-level pavement management program may provide airport staff a better understanding of the airfield pavement performance for developing and planning for specific maintenance, repair, and major rehabilitation projects. The understanding of specific distress types and severities will assist the airport in addressing pavement maintenance and repair with the appropriate treatments as defined by the FAA Advisory Circular **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** The development of projects with an understanding of system inventory, deterioration details, and pavement condition forecasts may assist airport staff in developing practical rehabilitation actions and budgets. Furthermore, the understanding of pavements’ past performance and forecasted condition may assist airport staff in addressing pavement rehabilitation in a timely and cost-effective manner. **Figure 1.7.2 (a) Typical Pavement Condition Life Cycle**, which is based on the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”** **Figure 1.7.2 (a) Typical Pavement Condition Life Cycle**, depicts a general duration of a pavement section and identifies the ideal condition to perform rehabilitative treatments at an optimal cost rather than allowing significant increase in rate of deterioration that would result in increased costs.

Figure 1.7.2 (a) Typical Pavement Condition Life Cycle




**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements (AC vs PCC).*

Figure 1.7.2 (b) General Pavement Treatments by Condition Range depicts generic flexible asphalt concrete (AC) pavement treatments that are effective at specific condition ranges. This graphic is a general concept and will vary based on pavement surface type and overall



composition. The intent is to convey various treatment types that would be effective based on the condition of the pavement along the deterioration model.





Figure 1.7.2 (b) General Pavement Treatments by Condition Range







Pavement maintenance, repair, and major rehabilitation would be quite anticipatory if all pavements behaved as depicted in **Figures 1.7.2 (a) and 1.7.2 (b)**, however pavement condition performance vary significantly based on several factors. Factors that contribute to a pavement section's condition and deterioration performance may include: functional design life, material type, material construction quality, climatic conditions, aircraft loading type and frequency, non-aircraft loading type and frequency, maintenance history, subgrade conditions, and other infrastructure in the vicinity. The list of factors is not all-inclusive of all factors that may contribute to a pavement's life cycle, it is intended to clarify that unique conditions certainly will affect a pavement's deterioration.

Figures 1.7.2 (c) and 1.7.2 (d), depict visual conditions of pavement facilities, for both AC and PCC respectively, with approximated PCI ranges and corresponding repair and rehabilitation measures.


Figures 1.7.2 (c) Flexible Asphalt Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require surface treatments (seal coat), thin overlays, and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions, may require major rehabilitation such as pavement mill and overlay or partial full-depth reconstruction.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.

Figures 1.7.2 (d) Rigid Portland Cement Concrete

	PCI Range	Representative PCI	Representative Pavement Surface	Rehabilitation Activities
Routine Maintenance	86-100	90		Pavements with PCI values above 85, or 'Good', may require periodic joint/crack sealing and local patching.
Pavement Preservation	65-85	70		Pavements with PCI conditions ranging from 'Fair' to 'Satisfactory' may require patches and/or joint/crack sealing.
Major Rehabilitation	40-64	50		Pavements that have deteriorated below a PCI 65 (but above 39), or within the range of 'Very Poor' to 'Fair' conditions may require major rehabilitation such as slab replacement and PCC restoration activity.
Major Reconstruction	0-39	15		Pavements that have deteriorated below a PCI 40, or within the range of 'Failed' to 'Very Poor' conditions, may require major reconstruction.




1.8 References

The following reference documents were referenced as specific guidelines and procedures for maintaining airport pavements; establishing an effective pavement maintenance program; and identifying specific pavement distresses, probable causes of distresses, inspection guidelines, and recommended methods of repair:

- ASTM D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”
- FAA Advisory Circular 150/5380-7B “Airport Pavement Management Program.”
- FAA Advisory Circular 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”
- FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation.”
- Department of the Air Force, Air Force Civil Engineer Center “Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements.”
- Unified Facilities Criteria (UFC) 3-260-16FA 16 “Airfield Pavement Condition Survey Procedures Pavements.”
- Unified Facilities Criteria (UFC) 3-260-03 “Airfield Pavement Evaluation.”
- Pavement Management for Airports, Roads, and Parking Lots 2nd Edition, M.Y. Shahin.

Chapter 2





Chapter 2 – Methodology

An effective pavement management program incorporates the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA Advisory Circular **150/5380-7B “Airport Pavement Management Program (PMP).”**

2.1 Airfield Pavement Database

The SAPMP program has historically utilized PAVER™ (formerly MicroPAVER™); the current update has maintained the use of the PAVER™ 7.0 version of the software. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and the U.S. Navy to meet the objectives of an effective pavement management system. The SAPMP consists of a network-level database of the airport's airfield pavement facilities that are part of the program. PAVER™ can achieve the following pavement management objectives: a manageable inventory system, the analysis of the current condition of pavements in accordance with the ASTM D5340, the development of pavement performance models to forecast conditions, and the development of maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure that consists of networks, branches, and sections, with the section being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database. These elements typically consist of pavement inventory characteristics, pavement structure, work history, historic condition records, and analytical customization.

The SAPMP System Update consisted of the conversion of the previous database from a PAVER™ version 6.5 to a version 7.0.

2.2 Airfield Pavement System Inventory

An airfield pavement system inventory typically maintains the location of all runways, taxiways, and aprons; geometric characteristics; type of pavement structure, year of construction and/or last major rehabilitation; and general composition details of the pavement.

The pavement inventory for an airport's airfield is an assembly of pavement infrastructure information that builds an inventory of branches and sections that codifies the airport's airfield pavement network. General geometry characteristics, estimated length, width, functional classification, pavement surface type, and operational function are among the characteristics identified at this initial phase in the pavement management process. The development of a pavement inventory that reasonably reflects the airport's airfield pavement facilities that are maintained by the airport provides a defined scope of the inspection and analysis efforts. As in the past, the SAPMP scope of work is specific to the airport-maintained airfield pavements as defined in the field network definition exhibits presented to current airport personnel.



A critical input to the pavement system inventory and network definition in the development of the SAPMP update is the date of last major rehabilitation/construction performed on the pavement assets that would set the asset at a PCI of 100 and a condition rating of Good. The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include; pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction.

Aerial imagery was obtained through the FDOT Surveying & Mapping Office's *Aerial Photo Look Up System (APLUS)*. This spatially projected imagery was utilized with computer-aided drafting software (AutoCAD) in concert with geographical information system software (ArcGIS) to develop a planning-level representative model that reasonably reflects the pavement assets at the airport.

2.2.1 Pavement Management Program Network Definition Terminology

There are several terms that are common in the communication of the results of the SAPMP System Update, these terms are defined as follows:

Pavement Network

A pavement network is a logical unit for organizing pavements into a structure for pavement management. A network will typically consist of one or more pavement *branches*, which are typically comprised of one or many pavement *sections*. The network is the starting point of the hierarchy of pavement management organization. For example, a network can be all the pavements within an airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual airport's airfield pavement facilities maintained by the airport.

The SAPMP System Update consists of research and evaluation of existing record documentation for the participating airports' airfield facilities. The pavement network is typically limited to the pavement facilities subject to aircraft use that is also maintained by the airport owner and eligible for public funding.

Pavement Branch

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement of a network with distinct functional classification. For example, within an airfield each runway, taxiway, or apron is considered a branch. A branch must consist of at least one section.

Pavement Section

A pavement section, also known as a feature, is the most specific management unit when considering the application and selection of maintenance, repair, and/or major rehabilitation treatments on an area of pavement within a branch. Each branch consists of at least one section, but may consist of more if pavement feature characteristics are distinct throughout the branch. Characteristics considered when subdividing branches into sections include, but are not limited to: pavement structure, type, age, condition, and function; traffic composition and frequency (current and future); geometric location; construction history; and other related



infrastructure features (e.g. drainage). A pavement section is defined as a subordinate of a pavement branch, which is a subordinate of a “parent” pavement network.

Pavement Sample Unit

A pavement sample unit is a subdivision of a pavement section that has a standard size range: twenty (20) continuous slabs (± 8 slabs) for Portland Cement Concrete (PCC) pavement and 5,000 contiguous square feet ($\pm 2,000$ ft²) for flexible asphalt concrete (AC) or porous friction course pavements.

Table 2.2.1 Airfield Pavement Database Network Definition Terminology

PMS Network Level	Common Definition	Airport Example
Network	Overall pavement assets maintained by the Airport	“Tallahassee International Airport – Airfield Pavements”
Branch Name	Commonly defined asset name as established by Airport and by use	“Runway 18-36”
Branch ID	Codified shorthand name for commonly defined asset established for database identification	“RW 18-36” RW, Branch Use, “Runway” 18-36, Runway Facility
Section ID	Codified identification for pavement asset that is distinct by the following: <ul style="list-style-type: none"> • Pavement Composition • Construction Work History • Aircraft Traffic • Condition Records 	“6105”
Sample Unit	A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	“300”



2.3 Airfield Pavement Structure

2.3.1 Pavement Structure Types

Airport airfield pavements are constructed to provide adequate support for the loads imposed by aircraft and produce a firm, stable, smooth, all-year, all-weather surface free of debris or other particles that may be blown or dislocated by propeller wash or jet blast. Typical pavement planning and design requires coordination of factors that include but are not limited to; subgrade conditions, material layer types, aircraft fleet mix (type, frequency, and traffic growth), and functional use. A pavement structure is composed of constructed layers that consist of subgrade, subbase, base course, structural courses, and surfaces courses. For the FDOT SAPMP, two major pavement structure types are classified for evaluation and analysis: Flexible Asphalt Concrete Surface and Rigid Portland Cement Concrete Surface. Additionally, Composite Structures known as Whitetopping Pavements are also present at limited airports within the Florida Airports System; these unique pavement structures are evaluated separately.

Flexible Asphalt Concrete Surface

A pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP consists of three (3) asphalt concrete surface types: Asphalt Concrete (AC), Asphalt Concrete Overlaid on Asphalt Concrete (AAC), and Asphalt Concrete Overlaid on Portland Cement Concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Flexible airfield pavement sections are AAC when a pavement rehabilitation consists of a pavement milling operation and a resurfacing of asphalt layers; or a direct overlay of asphalt concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing Rigid PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.



Rigid Portland Cement Concrete Surface

A pavement comprised of aggregate mixture with a Portland Cement binder. The FDOT SAPMP recognizes Portland Cement Concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface must provide a texture of nonskid qualities, prevent the infiltration of surface water into the subgrade, and provide structural support to the airplanes. Rigid pavement construction requires the layout of appropriately designed joint spacing.

Composite Structure – Whitetopping Pavement

A composite pavement comprised of relatively thin Portland Cement Concrete overlaid on an existing flexible asphalt concrete pavement structure. There are three (3) types of Whitetopping Pavements; Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

Conventional Whitetopping (WHT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible AC pavement section area. The modified PCC layer is typically greater than 8 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The modified PCC layer is typically between 4 and 8 inches in thickness.

Ultra-Thin Whitetopping (UTW)

A composite pavement structure consisting of a modified PCC overlaid on an existing flexible asphalt concrete pavement section. The Portland Cement Concrete layer is typically between 2 and 4 inches in thickness.



2.4 Airfield Pavement Work History

2.4.1 Airfield Pavement Record Keeping

It is strongly recommended that airports maintain records of all airfield construction and maintenance related to the pavement facilities. A history of all maintenance and repair performed and its associated costs (construction and soft costs) can provide valuable information on the effectiveness of various treatments on pavements. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities. The records should consist of the following:

1. Location and Limits of Work.
2. Types and Severity of Distresses Repaired.
3. Type of Work.
4. Cost of Work.
5. Supporting Documents (contract documents, construction drawings, specifications, bid tabulations, repair product, photograph records, etc.).

2.5 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually through increased roughness and/or fatigue cracking caused by successive and heavy aircraft traffic.

This study does not consist of a study or analysis of each individual airport's airfield aircraft fleet mix or traffic operations. However, it is strongly recommended that airports incorporate the requirements of FAA Advisory Circular **150/5320-6F Airport Pavement Design and Evaluation** when developing design-level rehabilitation activities. The AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.6 Airfield Pavement Condition Index (PCI) Survey

2.6.1 PCI Survey Methodology

In adherence to the FAA Advisory Circular **150/5380-7B "Airport Pavement Management Program (PMP),"** the FDOT SAPMP utilizes the PCI Survey Method of inspection to collect pavement distress data and analyze the condition. The PCI Survey Inspection procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The survey inspection consists primarily of visual inspection of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

A visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can be an indicator of structural distress. The functional condition analysis assesses the rating of the operational surface. A visual PCI Survey Inspection does not predict the remaining structural life of a pavement section, or its ability to support loads. The functional condition determined by the PCI method



can provide a cost-effective means to plan for pavement rehabilitation projects. The timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of; subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.



2.6.2 Pavement Distress Types

For each section, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard. The standard identifies 17 distinct flexible asphalt concrete distress types and 16 distinct rigid Portland Cement Concrete distress types.

Table 2.6.2 (a) Pavement Distress Types – Flexible Asphalt Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Alligator Cracking	Load / Fatigue
Bleeding	Construction Quality/ Mix Design
Block Cracking	Climate / Age
Corrugation	Load / Construction Quality
Depression	Load / Subsurface
Jet Blast	Aircraft
Joint Reflection - Cracking	Climate / Subsurface Pavement / Traffic Load
Longitudinal/Transverse Cracking	Climate / Construction Quality
Oil Spillage	Aircraft / Vehicle
Patching	Utility / Pavement Repair / Age
Polished Aggregate	Repeated Traffic Loading
Raveling	Climate / Age
Rutting	Load / Fatigue
Shoving	PCC Pavement Growth / Movement
Slippage Cracking	Load / Pavement Bond / Mix Design
Swelling	Climate / Subsurface
Weathering	Climate / Age



Table 2.6.2 (b) Pavement Distresses Possible Causes – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> Alligator Cracking Corrugation Depression Patching of Load-based distress Polished Aggregate Rutting Slippage Cracking 	<ul style="list-style-type: none"> Bleeding Block Cracking Joint Reflection Cracking L/T Cracking Patching of climate / durability-caused distresses Shoving from PCC Raveling Weathering Swelling 	<ul style="list-style-type: none"> Alligator Cracking Depression Patching of moisture / drainage caused distress Swelling Raveling Weathering 	<ul style="list-style-type: none"> Oil Spillage Jet Blast Erosion Polished Aggregate

Table 2.6.2 (c) Pavement Distresses Possible Effects – Flexible Asphalt Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> Corrugation Depression Rutting Shoving of asphalt pavement Swelling Raveling Weathering 	<ul style="list-style-type: none"> Bleeding Depression Polished Aggregate Rutting 	<ul style="list-style-type: none"> Block Cracking Joint Reflection Cracking L/T Cracking Slippage Cracking 	<ul style="list-style-type: none"> All Distresses



Table 2.6.2 (d) Pavement Distresses – Rigid Portland Cement Concrete-Surfaced Airfields

Distress	Common Distress Mechanisms
Blowup	Climate / ASR
Corner Break	Load Repetition / Curling Stresses
Linear Cracking	Load Repetition / Curling Stresses / Shrinkage Stresses
Durability Cracking	Freeze-Thaw Cycling
Joint Seal Damage	Material Deterioration / Construction Quality / Age
Small Patch	Pavement Repair
Large Patch/Utility Cut	Utility / Pavement Repair
Popout	Freeze-Thaw Cycling / ASR / Material Quality
Pumping	Load Repetition / Poor Joint Sealant
Scaling	Construction Quality / Freeze-Thaw Cycling
Faulting	Subgrade Quality / ASR / Inadequate Load Transfer
Shattered Slab	Overloading
Shrinkage Cracking	Construction Quality / Climate
Joint Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Corner Spalling	Load Repetition / Infiltration of Incompressible Material / Deterioration of Dowel (Load Transfer) Bars
Alkali-Silica Reaction (ASR)	Construction Quality / Climate / Chemical Reaction



Table 2.6.2 (e) Pavement Distresses Possible Causes – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Causes			
Load	Climate / Durability	Moisture / Drainage	Others
<ul style="list-style-type: none"> • Corner Break • Shattered Slab • L/T/D Cracking • Pumping • Patching of Load-associated distress • Spalling 	<ul style="list-style-type: none"> • Blowup • "D" Cracking • Joint Seal Damage • Popouts • Scaling • Patch of Climate/Durability-associated distress • Shrinkage Cracking • Spalling • L/T/D Cracking 	<ul style="list-style-type: none"> • Corner Break • Shattered Slab • Pumping • Patching of Moisture/Drainage-associated distress 	<ul style="list-style-type: none"> • Settlement / Faulting

Table 2.6.2 (f) Pavement Distresses Possible Effects – Rigid Portland Cement Concrete-Surfaced Airfields

Classification by Possible Effects			
Roughness	Skid / Hydroplaning Potential	FOD Potential	Rate of Deterioration and Maintenance Requirements
<ul style="list-style-type: none"> • Blowup • Corner Break • L/T/D Cracking • Shattered Slab • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Settlement / Faulting • Spalling 	<ul style="list-style-type: none"> • Corner Break • L/T/D Cracking • "D" Cracking • Joint Seal Damage • Shattered Slab • Popouts • Scaling 	<ul style="list-style-type: none"> • All distresses



2.6.3 PCI Survey Inspection Procedures

Inspection Sampling Rate

The FDOT SAPMP performs PCI Survey Inspections on sample units defined in the previous update. The sample units are subject to change at the discretion of the inspection personnel and/or to major pavement rehabilitation treatments. Furthermore, access to the sample units based on accessibility or impacts to operations may affect the overall sampling rate effort at each airport. The following **Tables 2.6.3 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve a greater statistical confidence should the airport have the available resources to perform PCI Survey Inspections independent of the FDOT SAPMP.

Table 2.6.3 (a) Recommended Sample Rate Schedule for Flexible Asphalt Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10

Table 2.6.3 (b) Recommended Sample Rate Schedule for Rigid Portland Cement Concrete

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10



2.6.4 Updates to the ASTM D5340-12

Airfield pavement distresses and conditions were surveyed in accordance with the methods outlined in FAA Advisory Circular 150/5380-6C and ASTM D5340-12. These procedures define distress type, severity, and quantity for sampling areas within each defined pavement section area to analyze and determine the PCI value and condition rating. During the 2013-2015 System Update, the incorporation of the significant changes to the ASTM D5340 (version D5340-12) resulted in adjusted pavement condition indices on pavement sections subject to the distress types updated. Furthermore, the revision of the PCI deduction curves and the separation of distress types from the original, such as Weathering and Raveling, have in select cases increased the PCI value of the section without any rehabilitation performed.

Flexible Asphalt Concrete Pavement Distress Updates

The previous methodology which featured “(52) Weathering and Raveling” distress has been separated into two distresses “(52) Raveling” and “(57) Weathering.” Previously, areas that were recorded as “Weathering and Raveling” were considered as one distress with a high deduction. Based on the updated methodology, in certain situations where “Weathering” only exists and does not meet the definition of “Raveling,” the PCI deduction is not as high as the former “Weathering and Raveling.” Therefore, areas identified only as “(57) Weathering” based on current ASTM standards, which were previously identified as “(52) Weathering and Raveling,” may be subject to an improvement in PCI. In instances where pavement PCI has increased due to this update, it is not due to an improvement in actual condition, however indicative of the adjusted distress deterioration effects.

Rigid Portland Cement Concrete Pavement Distress Updates


The previous methodology defined “(70) Scaling” as a distress that consisted of surface deterioration caused by construction defects, material defects, and environmental factors. The distress included *Alkali-Silica Reaction*, also known as ASR. The current methodology has separated Alkali-Silica Reaction as a distress identified as “(76) Alkali-Silica Reaction / ASR.” As a result, the previous “(70) Scaling” numerical deduction contribution to the PCI has been reduced. Previous inspections that recorded “(70) Scaling,” and currently do not exhibit “(76) Alkali-Silica Reactivity / ASR” may potentially see an increase in PCI. Additionally, “(73) Shrinkage Cracks” has been redefined as “(73) Shrinkage Cracking”. Shrinkage Cracking is characterized in two forms; drying shrinkage and plastic shrinkage. Drying shrinkage occurs over time as moisture leaves the pavement, it develops when hardened pavement continues to shrink as excess water not needed for cement hydration evaporates. It forms when subsurface resistance to the shrinkage is present and may extend through the entire depth of the slab. Plastic shrinkage can be caused by both atmospheric conditions and construction. Plastic shrinkage caused by atmospheric conditions develops when there is rapid loss of water in the surface of recently placed pavement. High winds or low humidity are contributing factors to evaporation. These shrinkage cracks can appear as a series of parallel cracks, usually 1 to 3 feet apart and do not extend very deep into the pavement’s surface. Plastic shrinkage caused by construction can form from over finishing/overworking of the pavement during construction. These shrinkage cracks appear as a series of inter-connected hairline cracks, or pattern cracking, and are often observed throughout the majority of the slab surface. This condition is also referred to as map cracking or crazing.



Table 2.6.4 Summary of Updates to ASTM D5340-12

Distress Updates to Reflect ASTM 5340-12				
Use and Surface Type	Updated Distress	Former Distress in Prior to 5340-10	Deduction Curve	Potential Effect
AC/AAC/APC Airfield	(52) Raveling - Low	(52) Weathering and Raveling - Low	No Change	N/A
	(52) Raveling - Medium	(52) Weathering and Raveling - Medium	No Change	N/A
	(52) Raveling - High	(52) Weathering and Raveling - High	No Change	N/A
	(57) Weathering - Low	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - Medium	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
	(57) Weathering - High	N/A – was part of 'Weathering and Raveling'	New	Increase in PCI with no maintenance
PCC Airfield	(70) Scaling - Low	(70) Scaling, Map Cracking, and Cracking - Low	New	Increase in PCI with no maintenance
	(70) Scaling - Medium	(70) Scaling, Map Cracking, and Cracking - Medium	New	Increase in PCI with no maintenance
	(70) Scaling - High	(70) Scaling, Map Cracking, and Cracking - High	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Low	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – Medium	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(76) Alkali Silica Reaction – High	N/A – was part of 'Scaling, Map Cracking, and Cracking'	New	Increase in PCI with no maintenance
	(73) Shrinkage Cracking	(73) Shrinkage Cracking	No Change	Prior distress types identified as 'Scaling, Map Cracking, and Cracking' may now be identified as 'Shrinkage Cracking'

Chapter 3





Chapter 3 – Airfield Pavement System Inventory

A significant element of an effective airfield pavement management system is the appropriate record keeping of changes due to construction or operational use of the pavement facilities. This chapter discusses the inventory data collected from the airport and summarizes network-level characteristics of the airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation for any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the airport, the following **Table 3.1.1** summarizes the airfield pavement construction projects that have been incorporated into the SAPMP database system since the 2013-2015 System Update. **Figure 3.1.1 (a)** and **Figure 3.1.1 (b)** provides an inset view of the 2019 Airfield Pavement Network Definition Exhibit and the 2019 Airfield Pavement System Inventory Exhibits that depict the updated network details for the airport reflected in the PAVER Database. Large format exhibits are referenced in **Appendix C Technical Exhibits**.


Table 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Year	General Work Description
2014	AP SW - Reconstruction
2018	AP N - Reconstruction
	AP N, AP NW, AP S, TW A4, TW A5 - Overlay
2019	AP RU RW23, RW 14-32, RW 5-23 - Mill and Overlay: Variable Mill and 2" P-401 Overlay
	TW A, TW A3, TW A5, TW C, TW E, TW F - Mill and Overlay: Variable Mill and 2" P-401 Overlay
	AP SW - Mill and Overlay
	TL A3 - New Construction: 4" P-401, 6" P-211, 12" Stabilized Subgrade

The airport provided a limited combination of record drawings, reports, and staff input that was pertinent information in developing the construction history of the airport's pavements from inception. Major rehabilitation/construction activities performed in the last 24-months or anticipated in the next 24-months are assumed to restore the PCI to 100. These activities include: pavement overlay, mill and replace, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI Survey and actual conditions may vary. Furthermore, any localized maintenance or repair performed that would improve the PCI will be considered in the condition analysis, if performed within inspection areas.




Figure 3.1.1 (a) 2019 Airfield Pavement Network Definition Exhibit



The Airfield Pavement Network Definition Exhibit provides details to the PCI Survey inspection efforts. The exhibit identifies the pavement facilities, surface type, section definition, and sample unit delineation.




Figure 3.1.1 (b) 2019 Airfield Pavement System Inventory Exhibit



The Airfield Pavement System Inventory Exhibit provides details to the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, observed in the field.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of a 20-year period. Design inputs typically require subgrade soil conditions, pavement section layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of the historic airfield pavement construction, **Figure 3.1.2** summarizes the average age of the pavement sections at the time of the PCI survey inspection. Age is determined to be the number of years since any major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

*Figure 3.1.2 Average Age of Pavements at Inspection*


The estimation of the pavement age is based on information requested and provided by participating airports. Additionally, data collected in the prior system updates since 1992 have been relied upon.



3.1.3 Functional Use Classification

Pavements are subject to varying aircraft loading patterns based on utilization and overall operations. For this SAPMP Update, the following categories of airfield functional use have been identified and associated with the following possible pavement branch facilities: Apron, Runway, Taxiway, and Taxilane. **Figure 3.1.3** summarizes the identified pavements' functional use by area in square feet. The pavement areas reviewed exclude shoulder pavement facilities.

Figure 3.1.3 Airfield Pavement Functional Classification Use by Area







3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), asphalt concrete (AC), asphalt concrete overlaid on asphalt concrete (AAC), and asphalt concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database throughout the years, the pavement surface types have been assigned to the various pavement sections in accordance to its work history composition. The following **Figures 3.1.4 (a) and (b)** summarize the applicable pavement types observed at this specific airport's airfield.

Figure 3.1.4 (a) Pavement Surface Type by Area (SF)



*Figure 3.1.4 (b) Pavement Surface Type by Area (%)*

3.1.5 Pavement System Inventory Details

The following **Table 3.1.5** displays the section-level details assembled as part of this update. The section-level details are based on the record documentation provided by the airports to FDOT and from SAPMP System Updates. The details assembled rely on the accuracy and the adequacy of data provided; however, it should be noted that characteristics such as pavement areas may be based on aerial interpretation of spatially projected imagery. The accuracy of data is presented with the intention of a network planning-level document; should the airport elect to perform rehabilitation work, it is recommended that further investigation be performed at the project level for construction purposes.

In summary, the scope of the pavement inventory update resulted in the updating of select existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix A** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit which visually summarize the results of the Airfield Pavement System Inventory analysis and reporting.



Table 3.1.5 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
CRG	FAA APRON	AP FAA	APRON	4505	400	370	147,450	AC	1/1/2004
CRG	FAA APRON	AP FAA	APRON	4510	125	50	6,400	PCC	1/1/2004
CRG	NORTH APRON	AP N	APRON	4205	200	75	24,445	AAC	7/1/2018
CRG	NORTH APRON	AP N	APRON	4210	750	300	265,650	AAC	7/1/2018
CRG	NORTH APRON	AP N	APRON	4215	310	76	22,406	AC	7/1/2018
CRG	NORTH APRON	AP N	APRON	4220	1,370	20	27,322	AC	12/25/1994
CRG	NW APRON	AP NW	APRON	4305	200	187	41,023	AC	1/1/1991
CRG	NW APRON	AP NW	APRON	4310	900	200	204,437	AAC	7/1/2018
CRG	NW APRON	AP NW	APRON	4320	2,040	20	56,781	AAC	7/1/2018
CRG	RUN-UP APRON AT RW 5	AP RU RW 5	APRON	5205	809	75	22,135	AC	1/1/2003
CRG	RUN-UP APRON AT RW 14	AP RU RW14	APRON	5310	73	200	24,645	AAC	1/1/2010
CRG	RUN-UP APRON AT RW 23	AP RU RW23	APRON	5105	150	80	12,030	AC	1/1/2005
CRG	RUN-UP APRON AT RW 23	AP RU RW23	APRON	5110	80	76	6,117	AAC	1/1/2019
CRG	SOUTH APRON	AP S	APRON	4105	580	250	185,265	AAC	7/1/2018
CRG	SOUTH APRON	AP S	APRON	4115	100	160	15,813	AAC	7/1/2018
CRG	SOUTHWEST APRON	AP SW	APRON	4405	150	60	8,887	PCC	12/25/1999
CRG	SOUTHWEST APRON	AP SW	APRON	4406	98	25	2,417	PCC	1/1/2014
CRG	SOUTHWEST APRON	AP SW	APRON	4407	245	60	14,286	AC	12/25/1999
CRG	SOUTHWEST APRON	AP SW	APRON	4410	350	35	12,829	AAC	1/1/2019
CRG	SOUTHWEST APRON	AP SW	APRON	4415	275	78	23,211	AC	1/1/2002
CRG	SOUTHWEST APRON	AP SW	APRON	4420	100	100	12,167	AC	12/25/1994
CRG	SOUTHWEST APRON	AP SW	APRON	4430	59	59	4,074	AC	1/1/2006
CRG	SOUTHWEST APRON	AP SW	APRON	4435	570	35	20,729	AAC	1/1/2007
CRG	RUNWAY 14-32	RW 14-32	RUNWAY	6205	375	100	45,000	AAC	1/1/2019
CRG	RUNWAY 14-32	RW 14-32	RUNWAY	6210	3,558	100	355,800	AAC	1/1/2019



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
CRG	RUNWAY 5-23	RW 5-23	RUNWAY	6105	3,638	100	363,800	AAC	1/1/2011
CRG	RUNWAY 5-23	RW 5-23	RUNWAY	6110	258	100	25,800	AAC	1/1/2019
CRG	TAXILANE A3	TL A3	TAXILANE	153	800	80	69,029	AC	1/1/2019
CRG	TAXILANE A3	TL A3	TAXILANE	155	550	35	19,174	AC	1/1/2007
CRG	TAXIWAY A	TW A	TAXIWAY	105	2,300	35	74,656	AAC	1/1/2010
CRG	TAXIWAY A	TW A	TAXIWAY	110	120	50	6,423	AAC	1/1/2019
CRG	TAXIWAY A	TW A	TAXIWAY	120	2,120	35	37,712	AC	1/1/2005
CRG	TAXIWAY A1	TW A1	TAXIWAY	130	425	30	22,201	AC	1/1/2005
CRG	TAXIWAY A2	TW A2	TAXIWAY	132	60	35	3,131	AAC	1/1/2010
CRG	TAXIWAY A2	TW A2	TAXIWAY	135	145	35	6,046	AC	1/1/1991
CRG	TAXIWAY A3	TW A3	TAXIWAY	142	247	50	13,123	AAC	1/1/2019
CRG	TAXIWAY A3	TW A3	TAXIWAY	145	132	35	4,606	AC	1/1/2001
CRG	TAXIWAY A3	TW A3	TAXIWAY	150	85	35	4,850	AAC	1/1/2010
CRG	TAXIWAY A4	TW A4	TAXIWAY	160	100	40	5,193	AAC	1/1/2010
CRG	TAXIWAY A4	TW A4	TAXIWAY	165	100	40	5,091	AAC	7/1/2018
CRG	TAXIWAY A5	TW A5	TAXIWAY	170	100	40	5,011	AAC	7/1/2018
CRG	TAXIWAY A5	TW A5	TAXIWAY	175	100	40	5,069	AAC	1/1/2010
CRG	TAXIWAY A5	TW A5	TAXIWAY	180	202	40	8,126	AAC	1/1/2010
CRG	TAXIWAY A5	TW A5	TAXIWAY	185	257	50	13,533	AAC	1/1/2019
CRG	TAXIWAY B	TW B	TAXIWAY	215	2,120	35	29,838	AC	1/1/2005
CRG	TAXIWAY B	TW B	TAXIWAY	225	1,555	35	59,500	AAC	1/1/2010
CRG	TAXIWAY B	TW B	TAXIWAY	227	170	35	5,899	AAC	1/1/2003
CRG	TAXIWAY B	TW B	TAXIWAY	230	135	50	3,679	AAC	1/1/2011
CRG	TAXIWAY B	TW B	TAXIWAY	235	700	35	26,915	AC	1/1/2003
CRG	TAXIWAY B1	TW B1	TAXIWAY	210	163	40	7,110	AC	12/25/1994
CRG	TAXIWAY B2	TW B2	TAXIWAY	220	175	50	3,863	AAC	1/1/2011




Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
CRG	TAXIWAY B2	TW B2	TAXIWAY	240	335	35	11,812	AC	1/1/2003
CRG	TAXIWAY B2	TW B2	TAXIWAY	242	75	35	4,802	AAC	1/1/2010
CRG	TAXIWAY B2	TW B2	TAXIWAY	243	180	35	6,422	AAC	12/25/1994
CRG	TAXIWAY B3	TW B3	TAXIWAY	244	55	35	3,380	AAC	1/1/2010
CRG	TAXIWAY B4	TW B4	TAXIWAY	245	175	40	9,056	AAC	1/2/1984
CRG	TAXIWAY B4	TW B4	TAXIWAY	250	405	35	15,426	AAC	1/1/2010
CRG	TAXIWAY B4	TW B4	TAXIWAY	265	150	50	3,169	AAC	1/1/2011
CRG	TAXIWAY B5	TW B5	TAXIWAY	255	210	40	4,433	AC	1/1/1991
CRG	TAXIWAY B5	TW B5	TAXIWAY	260	2,120	35	5,545	AC	1/1/2005
CRG	TAXIWAY C	TW C	TAXIWAY	305	400	60	24,696	AAC	1/1/2019
CRG	TAXIWAY C	TW C	TAXIWAY	310	40	136	5,648	AAC	1/1/2019
CRG	TAXIWAY C	TW C	TAXIWAY	320	209	80	16,569	AAC	12/25/2010
CRG	TAXIWAY D	TW D	TAXIWAY	455	495	35	12,087	AC	1/1/2005
CRG	TAXIWAY D	TW D	TAXIWAY	460	360	35	29,215	AC	1/1/2005
CRG	TAXIWAY E	TW E	TAXIWAY	505	270	50	14,164	AAC	1/1/2019
CRG	TAXIWAY F	TW F	TAXIWAY	605	164	60	9,632	AAC	1/1/2019
CRG	TAXIWAY F	TW F	TAXIWAY	610	125	44	5,562	AAC	1/1/2019
CRG	TAXIWAY G	TW G	TAXIWAY	765	1,885	35	65,079	AC	1/1/2003
CRG	TAXIWAY G	TW G	TAXIWAY	770	250	35	9,691	AC	1/1/2004



PAGE INTENTIONALLY LEFT BLANK

Chapter 4





Chapter 4 – Airfield Pavement Condition


The examination of specific distress types (with causes attributed to load, climate, or other defined distress mechanism), determination of the severity of distress, and determination of the quantity of distress manifestation are required in the computation of a PCI value. The PCI provides valuable information that can be used to determine the existing condition of the pavement, possible cause of the pavement deterioration, and eventually aid in the planning of the rehabilitation of pavements. It should be noted that the PCI method of pavement condition evaluation is strictly a visual and functional evaluation. Further evaluation of the pavement condition may be necessary for design and/or project-level determination of pavement rehabilitation.

4.1 Airfield Pavement Condition Index (Latest Inspection)

4.1.1 Network-Level Analysis

The following **Figure 4.1.1** summarizes the network-level pavement condition analysis based on the most recent PCI Survey inspection results.

Figure 4.1.1 Latest Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a) through (d)** summarize the branch-level pavement condition analysis based on the most recent PCI Survey inspection results; the following Figures provide overall branch-level conditions by branch use.



Figure 4.1.2 (a) Latest Condition – Runway Pavements




Figure 4.1.2 (b) Latest Condition – Taxiway Pavements






Figure 4.1.2 (c) Latest Condition – Apron Pavements





Figure 4.1.2 (d) Latest Condition – Taxiway Pavements





4.1.3 Section-Level Analysis

The following **Table 4.1.3** provides details for each pavement section of its area-weighted average PCI and the percent of distress which is related to load, climate, or other factors. The amount of distress attributed to the various causes provides insight into maintenance, repair, and rehabilitation needs. Load-related distress indicates that pavements are reaching the end of their structural design life, and for those pavements exhibiting a significant amount of these distress types, rehabilitation should be planned to strengthen or reconstruct the pavement.

Appendix C Technical Exhibits provides a technical exhibit that graphically depicts the PCI values and ratings determined from this SAPMP System Update.

Any pavement facilities subject to pavement construction within the past 2 years or anticipated for construction within the next year may have been omitted from inspection. Pavement subject to major rehabilitation will be set to a PCI of 100.



Table 4.1.3 Latest Pavement Condition Index Summary

Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
CRG	AP FAA	FAA APRON	APRON	4505	147,450	AC	80	Satisfactory	61%	0%	39%	5	30
CRG	AP FAA	FAA APRON	APRON	4510	6,400	PCC	78	Satisfactory	30%	0%	70%	1	3
CRG	AP N	NORTH APRON	APRON	4205	24,445	AAC	100	Good	0%	0%	0%	0	0
CRG	AP N	NORTH APRON	APRON	4210	265,650	AAC	100	Good	0%	0%	0%	0	0
CRG	AP N	NORTH APRON	APRON	4215	22,406	AC	100	Good	0%	0%	0%	0	0
CRG	AP N	NORTH APRON	APRON	4220	27,322	AC	30	Very Poor	56%	38%	6%	2	7
CRG	AP NW	NW APRON	APRON	4305	41,023	AC	63	Fair	95%	0%	5%	1	8
CRG	AP NW	NW APRON	APRON	4310	204,437	AAC	100	Good	0%	0%	0%	0	0
CRG	AP NW	NW APRON	APRON	4320	56,781	AAC	100	Good	0%	0%	0%	0	0
CRG	AP RU RW 5	RUN-UP APRON AT RW 5	APRON	5205	22,135	AC	77	Satisfactory	100%	0%	0%	1	5
CRG	AP RU RW14	RUN-UP APRON AT RW 14	APRON	5310	24,645	AAC	71	Satisfactory	84%	0%	16%	2	6
CRG	AP RU RW23	RUN-UP APRON AT RW 23	APRON	5105	12,030	AC	73	Satisfactory	100%	0%	0%	1	3
CRG	AP RU RW23	RUN-UP APRON AT RW 23	APRON	5110	6,117	AAC	100	Good	0%	0%	0%	0	0
CRG	AP S	SOUTH APRON	APRON	4105	185,265	AAC	100	Good	0%	0%	0%	0	0
CRG	AP S	SOUTH APRON	APRON	4115	15,813	AAC	100	Good	0%	0%	0%	0	0
CRG	AP SW	SOUTHWEST APRON	APRON	4405	8,887	PCC	12	Serious	7%	82%	11%	1	2
CRG	AP SW	SOUTHWEST APRON	APRON	4406	2,417	PCC	86	Good	97%	0%	3%	1	1
CRG	AP SW	SOUTHWEST APRON	APRON	4407	14,286	AC	56	Fair	92%	0%	8%	1	4
CRG	AP SW	SOUTHWEST APRON	APRON	4410	12,829	AAC	100	Good	0%	0%	0%	0	0
CRG	AP SW	SOUTHWEST APRON	APRON	4415	23,211	AC	68	Fair	84%	0%	16%	1	5
CRG	AP SW	SOUTHWEST APRON	APRON	4420	12,167	AC	67	Fair	100%	0%	0%	1	3
CRG	AP SW	SOUTHWEST APRON	APRON	4430	4,074	AC	26	Very Poor	41%	0%	59%	1	2
CRG	AP SW	SOUTHWEST APRON	APRON	4435	20,729	AAC	74	Satisfactory	75%	0%	25%	1	6
CRG	RW 14-32	RUNWAY 14-32	RUNWAY	6205	45,000	AAC	100	Good	0%	0%	0%	0	0
CRG	RW 14-32	RUNWAY 14-32	RUNWAY	6210	355,800	AAC	100	Good	0%	0%	0%	0	0
CRG	RW 5-23	RUNWAY 5-23	RUNWAY	6105	363,800	AAC	68	Fair	95%	0%	5%	15	73
CRG	RW 5-23	RUNWAY 5-23	RUNWAY	6110	25,800	AAC	100	Good	0%	0%	0%	0	0
CRG	TL A3	TAXILANE A3	TAXILANE	153	69,029	AC	100	Good	0%	0%	0%	0	0
CRG	TL A3	TAXILANE A3	TAXILANE	155	19,174	AC	79	Satisfactory	95%	0%	5%	1	5
CRG	TW A	TAXIWAY A	TAXIWAY	105	74,656	AAC	57	Fair	86%	0%	14%	4	20
CRG	TW A	TAXIWAY A	TAXIWAY	110	6,423	AAC	100	Good	0%	0%	0%	0	0
CRG	TW A	TAXIWAY A	TAXIWAY	120	37,712	AC	72	Satisfactory	76%	0%	24%	3	10
CRG	TW A1	TAXIWAY A1	TAXIWAY	130	22,201	AC	84	Satisfactory	100%	0%	0%	1	5
CRG	TW A2	TAXIWAY A2	TAXIWAY	132	3,131	AAC	69	Fair	100%	0%	0%	1	1
CRG	TW A2	TAXIWAY A2	TAXIWAY	135	6,046	AC	57	Fair	96%	0%	4%	1	1
CRG	TW A3	TAXIWAY A3	TAXIWAY	142	13,123	AAC	100	Good	0%	0%	0%	0	0
CRG	TW A3	TAXIWAY A3	TAXIWAY	145	4,606	AC	72	Satisfactory	100%	0%	0%	1	1




Network ID	Branch ID	Branch Name	Branch Use	Section ID	Area (SF)	Surface	PCI	PCI Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
CRG	TW A3	TAXIWAY A3	TAXIWAY	150	4,850	AAC	81	Satisfactory	100%	0%	0%	1	1
CRG	TW A4	TAXIWAY A4	TAXIWAY	160	5,193	AAC	66	Fair	96%	0%	4%	1	1
CRG	TW A4	TAXIWAY A4	TAXIWAY	165	5,091	AAC	100	Good	0%	0%	0%	0	0
CRG	TW A5	TAXIWAY A5	TAXIWAY	170	5,011	AAC	100	Good	0%	0%	0%	0	0
CRG	TW A5	TAXIWAY A5	TAXIWAY	175	5,069	AAC	55	Poor	73%	0%	27%	1	1
CRG	TW A5	TAXIWAY A5	TAXIWAY	180	8,126	AAC	64	Fair	67%	0%	33%	1	2
CRG	TW A5	TAXIWAY A5	TAXIWAY	185	13,533	AAC	100	Good	0%	0%	0%	0	0
CRG	TW B	TAXIWAY B	TAXIWAY	215	29,838	AC	77	Satisfactory	99%	0%	1%	1	8
CRG	TW B	TAXIWAY B	TAXIWAY	225	59,500	AAC	55	Poor	93%	0%	7%	4	16
CRG	TW B	TAXIWAY B	TAXIWAY	227	5,899	AAC	70	Fair	99%	0%	1%	1	1
CRG	TW B	TAXIWAY B	TAXIWAY	230	3,679	AAC	81	Satisfactory	100%	0%	0%	1	1
CRG	TW B	TAXIWAY B	TAXIWAY	235	26,915	AC	68	Fair	78%	0%	22%	2	7
CRG	TW B1	TAXIWAY B1	TAXIWAY	210	7,110	AC	59	Fair	83%	0%	17%	1	2
CRG	TW B2	TAXIWAY B2	TAXIWAY	220	3,863	AAC	81	Satisfactory	100%	0%	0%	1	1
CRG	TW B2	TAXIWAY B2	TAXIWAY	240	11,812	AC	69	Fair	100%	0%	0%	1	3
CRG	TW B2	TAXIWAY B2	TAXIWAY	242	4,802	AAC	82	Satisfactory	100%	0%	0%	1	1
CRG	TW B2	TAXIWAY B2	TAXIWAY	243	6,422	AAC	42	Poor	75%	13%	12%	1	1
CRG	TW B3	TAXIWAY B3	TAXIWAY	244	3,380	AAC	70	Fair	92%	0%	8%	1	1
CRG	TW B4	TAXIWAY B4	TAXIWAY	245	9,056	AAC	31	Very Poor	76%	15%	9%	1	2
CRG	TW B4	TAXIWAY B4	TAXIWAY	250	15,426	AAC	67	Fair	91%	0%	9%	1	4
CRG	TW B4	TAXIWAY B4	TAXIWAY	265	3,169	AAC	80	Satisfactory	100%	0%	0%	1	1
CRG	TW B5	TAXIWAY B5	TAXIWAY	255	4,433	AC	51	Poor	80%	0%	20%	1	1
CRG	TW B5	TAXIWAY B5	TAXIWAY	260	5,545	AC	80	Satisfactory	83%	0%	17%	1	1
CRG	TW C	TAXIWAY C	TAXIWAY	305	24,696	AAC	100	Good	0%	0%	0%	0	0
CRG	TW C	TAXIWAY C	TAXIWAY	310	5,648	AAC	100	Good	0%	0%	0%	0	0
CRG	TW C	TAXIWAY C	TAXIWAY	320	16,569	AAC	57	Fair	94%	0%	6%	1	4
CRG	TW D	TAXIWAY D	TAXIWAY	455	12,087	AC	80	Satisfactory	70%	0%	30%	1	3
CRG	TW D	TAXIWAY D	TAXIWAY	460	29,215	AC	78	Satisfactory	93%	0%	7%	2	8
CRG	TW E	TAXIWAY E	TAXIWAY	505	14,164	AAC	100	Good	0%	0%	0%	0	0
CRG	TW F	TAXIWAY F	TAXIWAY	605	9,632	AAC	100	Good	0%	0%	0%	0	0
CRG	TW F	TAXIWAY F	TAXIWAY	610	5,562	AAC	100	Good	0%	0%	0%	0	0
CRG	TW G	TAXIWAY G	TAXIWAY	765	65,079	AC	73	Satisfactory	100%	0%	0%	3	18
CRG	TW G	TAXIWAY G	TAXIWAY	770	9,691	AC	75	Satisfactory	100%	0%	0%	1	2



Figure 4.1.3 is an inset view of the 2019 Airfield Pavement Condition Index Exhibit that visually represents the results of the latest PCI Survey inspection. A large format exhibit is located in **Appendix C Technical Exhibits**.

Figure 4.1.3 2019 Airfield Pavement Condition Index Exhibit





4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The field PCI Survey performed at Jacksonville Executive at Craig Airport (CRG) was completed in May 2019. The resulting overall area-weighted average PCI value was 84 representing a condition rating of Satisfactory. Jacksonville Executive at Craig Airport is serviced by two runways; Runway 5-23 is 100-ft wide and 4,004-ft long and Runway 14-32 is 100-ft wide and 4,008-ft long. Due to recent construction, Runway 14-32, portions of Taxiway A connectors, and multiple apron areas were not inspected. The PCI has been set to 100, a condition rating of Good.

Based on the FAA 5010 Report as of 09/12/2019 the Airport has reported 158,769 operations for 12 months ending 02/07/2018.

4.2.2 Branch-Level Observations

The following branch-level observations are intended to be an overall summary of select pavement facilities identified during the PCI Survey; further detail at the section and sample-level may be referenced for all pavements assessed as part of this System Update. The branch-level observations discussed are limited to select branches based on use and condition.

Runway 5-23

Runway 5-23 consists of 2 sections constructed of AAC. The last construction years range from 2011 to 2019. The area-weighted average PCI for Runway 5-23 is 70 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Runway 5-23 consist of Bleeding, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Taxiway A

Taxiway A consists of 3 sections constructed of AC and AAC. The last construction years range from 2005 to 2019. The area-weighted average PCI for Taxiway A is 64 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway A consist of Bleeding, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

Taxiway B

Taxiway B consists of 5 sections constructed of AC and AAC. The last construction years range from 2003 to 2011. The area-weighted average PCI for Taxiway B is 64 representing a Fair condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on Taxiway B consist of Bleeding, Depression, Longitudinal & Transverse Cracking, Patching, Raveling, Swelling, and Weathering.

Taxiway B4

Taxiway B4 consists of 3 sections constructed of AAC. The last construction years range from 1984 to 2011. The area-weighted average PCI for Taxiway B4 is 56 representing a Fair condition rating. The pavement distresses observed were related to Climate, Load, and Other



distress classifications. Distresses observed on Taxiway B4 consist of Alligator Cracking, Block Cracking, Longitudinal & Transverse Cracking, Raveling, Swelling, and Weathering.

FAA Apron

FAA Apron consists of 2 sections constructed of AC and PCC. The last construction year for FAA Apron was 2004. The area-weighted average PCI for FAA Apron is 79 representing a Satisfactory condition rating. The pavement distresses observed were related to Climate and Other distress classifications. Distresses observed on FAA Apron consist of Bleeding, Depression, Longitudinal & Transverse Cracking, Raveling, Weathering, Joint Seal Damage, Small Patch, Large Patch/Utility Cut, Shrinkage Cracking, Joint Spall, and Corner Spall.

Figure 4.2.2 Pavement Condition Summary by Facility Use

Facility Use	Area-Weighted Average PCI	Condition Rating
Runway	85	Satisfactory
Taxiway	72	Satisfactory
Apron	90	Good
Taxilane	95	Good



4.3 Forecasted Pavement Conditions

4.3.1 Performance Models and Prediction Curves

Pavement Performance Models are developed from the distress data and historic construction records collected for the SAPMP. This data is consolidated in a database and organized by inspection/construction date, pavement type, age, and pavement use. The pavement Performance Models are used to develop broad Prediction Curves, alternatively known as deterioration curves or family curves. These Prediction Curves are utilized to develop forecasted PCI values based on historic trends and statistical models.

4.3.2 Branch-Level Pavement Condition Forecast

The following **Figures 4.3.2 (a) through (c)** depict the branch-level pavement condition forecast by Branch Use (Runway, Taxiway, and/or Apron). The forecasted conditions are for a 10-year duration starting in January 2020 through January 2029.

Figure 4.3.2 (a) Forecasted Runway Pavement Performance






Figure 4.3.2 (b) Forecasted Taxiway Pavement Performance





Figure 4.3.2 (c) Forecasted Apron Pavement Performance





4.3.3 Section-Level Pavement Condition Forecast

The following **Table 4.3.3** provides detail to the forecasted PCI values for each section inspected. Please note the forecasted Branch- and Section-Level PCI's are for planning purposes and are subject to the sensitivities in changes in traffic and maintenance frequency. Airport staff should perform annual visual condition assessments to maintain recent understanding of pavement conditions.



Table 4.3.3 Forecasted PCI 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
CRG	AP FAA	4505	80	78	76	74	73	71	69	68	66	65	64
CRG	AP FAA	4510	78	77	75	74	73	72	70	69	68	66	65
CRG	AP N	4205	100	96	94	92	90	88	85	83	81	79	77
CRG	AP N	4210	100	96	94	92	90	88	85	83	81	79	77
CRG	AP N	4215	100	96	94	91	89	87	85	82	80	78	76
CRG	AP N	4220	30	29	29	29	28	28	28	27	27	27	26
CRG	AP NW	4305	63	62	61	60	59	58	57	57	56	55	54
CRG	AP NW	4310	100	96	94	92	90	88	85	83	81	79	77
CRG	AP NW	4320	100	96	94	92	90	88	85	83	81	79	77
CRG	AP RU RW 5	5205	77	75	73	72	70	68	67	66	64	63	62
CRG	AP RU RW14	5310	71	69	67	65	63	60	58	56	54	52	50
CRG	AP RU RW23	5105	73	71	70	68	67	65	64	63	62	61	60
CRG	AP RU RW23	5110	100	97	95	93	91	89	86	84	82	80	78
CRG	AP S	4105	100	96	94	92	90	88	85	83	81	79	77
CRG	AP S	4115	100	96	94	92	90	88	85	83	81	79	77
CRG	AP SW	4405	12	11	9	8	7	6	4	3	2	0	0
CRG	AP SW	4406	86	85	83	82	81	80	78	77	76	74	73
CRG	AP SW	4407	56	55	54	54	53	52	51	51	50	49	48
CRG	AP SW	4410	100	97	95	93	91	89	86	84	82	80	78
CRG	AP SW	4415	68	67	65	64	63	62	61	60	59	58	57
CRG	AP SW	4420	67	66	64	63	62	61	60	59	58	58	57
CRG	AP SW	4430	26	25	25	25	24	24	23	23	23	22	22
CRG	AP SW	4435	74	72	70	68	66	63	61	59	57	55	53
CRG	RW 14-32	6205	100	97	94	92	89	87	85	83	81	80	78
CRG	RW 14-32	6210	100	97	94	92	89	87	85	83	81	80	78



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
CRG	RW 5-23	6105	68	67	66	65	64	64	63	62	61	61	60
CRG	RW 5-23	6110	100	97	94	92	89	87	85	83	81	80	78
CRG	TL A3	153	100	98	96	94	93	91	89	88	86	85	83
CRG	TL A3	155	79	78	76	75	73	72	71	69	68	67	66
CRG	TW A	105	57	56	55	54	53	52	51	51	50	48	47
CRG	TW A	110	100	97	95	92	90	88	86	84	83	81	79
CRG	TW A	120	72	71	69	68	67	66	64	63	62	61	60
CRG	TW A1	130	84	82	81	80	78	77	75	74	73	71	70
CRG	TW A2	132	69	68	67	66	65	64	63	62	61	61	60
CRG	TW A2	135	57	56	55	54	53	52	51	50	49	48	48
CRG	TW A3	142	100	97	95	92	90	88	86	84	83	81	79
CRG	TW A3	145	72	71	69	68	67	66	64	63	62	61	60
CRG	TW A3	150	81	79	78	76	75	74	72	71	70	69	68
CRG	TW A4	160	66	65	64	63	62	61	61	60	59	58	57
CRG	TW A4	165	100	96	94	91	89	87	85	84	82	80	79
CRG	TW A5	170	100	96	94	91	89	87	85	84	82	80	79
CRG	TW A5	175	55	54	53	52	51	50	49	48	47	46	44
CRG	TW A5	180	64	63	62	61	60	60	59	58	57	56	56
CRG	TW A5	185	100	97	95	92	90	88	86	84	83	81	79
CRG	TW B	215	77	76	74	73	71	70	69	68	66	65	64
CRG	TW B	225	55	54	53	52	51	50	49	48	47	46	44
CRG	TW B	227	70	69	68	67	66	65	64	63	62	61	61
CRG	TW B	230	81	79	78	76	75	74	72	71	70	69	68
CRG	TW B	235	68	67	65	64	63	62	61	60	59	57	56
CRG	TW B1	210	59	58	57	56	55	54	53	52	51	50	49
CRG	TW B2	220	81	79	78	76	75	74	72	71	70	69	68
CRG	TW B2	240	69	68	66	65	64	63	62	61	59	58	57




Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
CRG	TW B2	242	82	80	79	77	76	75	73	72	71	70	69
CRG	TW B2	243	42	41	39	37	36	34	32	30	28	26	24
CRG	TW B3	244	70	69	68	67	66	65	64	63	62	61	61
CRG	TW B4	245	31	29	27	25	23	21	19	17	14	12	10
CRG	TW B4	250	67	66	65	64	63	62	61	61	60	59	58
CRG	TW B4	265	80	78	77	76	74	73	72	71	69	68	67
CRG	TW B5	255	51	50	49	48	47	47	46	45	44	44	43
CRG	TW B5	260	80	79	77	76	74	73	72	70	69	68	66
CRG	TW C	305	100	97	95	92	90	88	86	84	83	81	79
CRG	TW C	310	100	97	95	92	90	88	86	84	83	81	79
CRG	TW C	320	57	56	55	54	53	52	51	51	50	48	47
CRG	TW D	455	80	79	77	76	74	73	72	70	69	68	66
CRG	TW D	460	78	77	75	74	72	71	70	69	67	66	65
CRG	TW E	505	100	97	95	92	90	88	86	84	83	81	79
CRG	TW F	605	100	97	95	92	90	88	86	84	83	81	79
CRG	TW F	610	100	97	95	92	90	88	86	84	83	81	79
CRG	TW G	765	73	72	70	69	68	66	65	64	63	62	61
CRG	TW G	770	75	74	72	71	70	68	67	66	65	63	62



4.3.4 Forecasted PCI Considerations

As FDOT continues to update the SAPMP with future PCI Survey inspections and assembly of airfield pavement construction work history, the performance models will be further refined. With the refinement of additional PCI and work history data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the Florida Airports System. Forecasted or predicted pavement conditions for the airport are intended for planning purposes only. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in FAA **AC 150/5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements** to determine structural and/or functional conditions at the time of project.

Chapter 5





Chapter 5 – Localized Maintenance and Repair Planning

General Maintenance and Rehabilitation (M&R) methods are characterized under three broad categories: localized maintenance and repair, global treatments, and major rehabilitation.

- **Localized Maintenance and Repair** includes patching and crack sealing.
- **Global Treatments** include surface seals and rejuvenators for flexible pavements.
- **Major Rehabilitation** includes overlays, significant slab replacement, and reconstruction.

This chapter discusses the FDOT SAPMP Localized Maintenance and Repair Planning approach. Proactive localized maintenance and repair, specifically preservation, is highly recommended to the airports. However, it is certainly recognized that once pavements have deteriorated below a certain condition, the facility would benefit from a more substantial rehabilitation in lieu of localized efforts. Chapter 6 Major Rehabilitation Planning discusses the addressing of pavements through timely rehabilitation once it has deteriorated below a critical PCI where localized repairs may not be as cost effective.

5.1 Localized Maintenance and Repair

Localized maintenance and repair is best applied as a conservation measure and is oftentimes applied to slow the rate of deterioration of distressed pavements; however, may be applied as a temporary corrective measure in isolated areas. Localized maintenance and repair can be applied either as a safety (“stopgap”) measure or preventive measure. Example distress types subject to localized preventive maintenance and repair may consist of low-severity longitudinal and transverse cracking and low-severity weathering. In many cases however, localized stopgap repair is applied as a safety measure to address high-severity distress manifestations when major rehabilitation is not funded for a given section with a PCI value below critical PCI. Some agencies may elect to define both types; preventative and stopgap, as localized maintenance.

Localized Stopgap/Safety Maintenance and Repair

Localized Stopgap or Safety Maintenance and Repair is defined as the localized distress repair needed to keep pavements operational in a safe condition. These activities are typically applied to high-severity distresses or distresses affecting operational activities. Typical pavement section PCIs will range from 0 to 65.

Localized Preventive Maintenance and Repair

Localized Preventive Maintenance and Repair is defined as distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching. Typical pavement section PCIs will be above 65.



5.2 Localized Maintenance and Repair Policy

The resulting Localized Maintenance and Repair recommendations are identified based on the policy defined in **Table 5.2 (a)** and **Table 5.2 (b)**, for flexible asphalt concrete and rigid Portland cement concrete pavements, respectively. The activities identified were based on the research of practical pavement treatments in consideration of the FAA **AC 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements”** and the **FDOT Airfield Pavement Distress Repair Manual**. Additionally, the **Engineering Technical Letter (ETL) 14-3: Preventive Maintenance Plan (PMP) for Airfield Pavements** was referenced for conservative application of pavement treatments. The Localized Maintenance and Repair Policy and associated planning-level unit costs were developed in consideration of a network-level analysis – it is strictly intended to provide a glimpse of the condition of the airport pavements with a limited PCI survey effort.

The developed Localized Maintenance and Repair Policy and associated planning-level unit costs were based on a statewide consideration of pavement treatments and review of state construction costs for both Airfield Pavements and from the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities was factored in the determination of conservative planning-level unit costs. The identified Localized maintenance activities for both preventive and stopgap activities are based on a statewide network approach; project-specific evaluation and maintenance quantities should be developed prior to any construction.

Table 5.2 (a) Localized Maintenance and Repair – Flexible Asphalt Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
41	Low	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	Medium	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
41	High	ALLIGATOR CR	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
42	N/A	BLEEDING	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Low	BLOCK CR	FDOT-MO-PV	FDOT - MONITOR	N/A
43	Medium	BLOCK CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
43	High	BLOCK CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
44	Low	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	Medium	CORRUGATION	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
44	High	CORRUGATION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Low	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	Medium	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
45	High	DEPRESSION	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
46	N/A	JET BLAST	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
47	Low	JT REF. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
47	Medium	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
47	High	JT REF. CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft



Distress	Severity	Description	Code	Work Type	Work Unit
48	Low	L & T CR	FDOT-MO-PV	FDOT - MONITOR	N/A
48	Medium	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
48	High	L & T CR	FDOT-CS-AC	FDOT - CRACK SEALING - AC	Ft
49	N/A	OIL SPILLAGE	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
50	Low	PATCHING	FDOT-MO-PV	FDOT - MONITOR	N/A
50	Medium	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
50	High	PATCHING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
51	N/A	POLISHED AG	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Low	RAVELING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
52	Medium	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
52	High	RAVELING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
53	Low	RUTTING	FDOT-MO-PV	FDOT - MONITOR	N/A
53	Medium	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
53	High	RUTTING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
54	Low	SHOVING	FDOT-MO-PV	FDOT - MONITOR	N/A
54	Medium	SHOVING	FDOT-ML-AC	FDOT - MILLING - AC	SqFt
54	High	SHOVING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
55	N/A	SLIPPAGE CR	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt
56	Low	SWELLING	FDOT-MO-PV	FDOT - MONITOR	N/A
56	Medium	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
56	High	SWELLING	FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	SqFt
57	Low	WEATHERING	FDOT-MO-PV	FDOT - MONITOR	N/A
57	Medium	WEATHERING	FDOT-SS-LO	FDOT - SURFACE SEAL	SqFt
57	High	WEATHERING	FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	SqFt

Table 5.2 (b) Localized Maintenance and Repair – Rigid Portland Cement Concrete

Distress	Severity	Description	Code	Work Type	Work Unit
61	Low	BLOW-UP	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
61	Medium	BLOW-UP	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
61	High	BLOW-UP	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
62	Low	CORNER BREAK	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
62	Medium	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
62	High	CORNER BREAK	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
63	Low	LINEAR CR	FDOT-MO-PV	FDOT - MONITOR	N/A
63	Medium	LINEAR CR	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
63	High	LINEAR CR	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt



Distress	Severity	Description	Code	Work Type	Work Unit
64	Low	DURABIL. CR	FDOT-MO-PV	FDOT - MONITOR	N/A
64	Medium	DURABIL. CR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
64	High	DURABIL. CR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
65	Low	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	Medium	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
65	High	JT SEAL DMG	FDOT-JS-PC	FDOT - JOINT SEAL - PCC	Ft
66	Low	SMALL PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
66	Medium	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
66	High	SMALL PATCH	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
67	Low	LARGE PATCH	FDOT-MO-PV	FDOT - MONITOR	N/A
67	Medium	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
67	High	LARGE PATCH	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
68	N/A	POPOUTS	FDOT-PO-FL	FDOT - POPOUT FILLER	SqFt
69	N/A	PUMPING	FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	SqFt
70	Low	SCALING	FDOT-MO-PV	FDOT - MONITOR	N/A
70	Medium	SCALING	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
70	High	SCALING	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
71	Low	FAULTING	FDOT-MO-PV	FDOT - MONITOR	N/A
71	Medium	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
71	High	FAULTING	FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	Ft
72	Low	SHAT. SLAB	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
72	Medium	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
72	High	SHAT. SLAB	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt
73	N/A	SHRINKAGE CR	FDOT-MO-PV	FDOT - MONITOR	N/A
74	Low	JOINT SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
74	Medium	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
74	High	JOINT SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	Low	CORNER SPALL	FDOT-CS-PC	FDOT - CRACK SEALING - PCC	Ft
75	Medium	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
75	High	CORNER SPALL	FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	SqFt
76	Low	ASR	FDOT-MO-PV	FDOT - MONITOR	N/A
76	Medium	ASR	FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	SqFt
76	High	ASR	FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	SqFt



Table 5.2 (c) Localized Repair Planning-Level Unit Costs – Flexible Asphalt Concrete

Code	Name	Cost	Units
FDOT-SS-LO	FDOT - SURFACE SEAL	\$0.55	SqFt
FDOT-ML-AC	FDOT - MILLING - AC	\$2.00	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-AC	FDOT - CRACK SEALING - AC	\$3.00	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	SqFt
FDOT-PA-AF	FDOT - PATCHING - AC FULL DEPTH	\$9.00	SqFt
FDOT-PA-AP	FDOT - PATCHING - AC PARTIAL DEPTH	\$4.00	SqFt

Table 5.2 (d) Localized M&R Planning-Level Unit Costs – Rigid Portland Cement Concrete

Code	Name	Cost	Units
FDOT-PA-PF	FDOT - PATCHING - PCC FULL DEPTH	\$150.00	SqFt
FDOT-SL-PC	FDOT - SLAB REPLACEMENT - PCC	\$30.00	SqFt
FDOT-SB-PC	FDOT - SLAB STABILIZATION - PCC	\$30.00	SqFt
FDOT-PA-PP	FDOT - PATCHING - PCC PARTIAL DEPTH	\$72.00	SqFt
FDOT-PO-FL	FDOT - POPOUT FILLER	\$0.05	SqFt
FDOT-GR-PP	FDOT - GRINDING (LOCALIZED)	\$2.00	Ft
FDOT-CS-PC	FDOT - CRACK SEALING - PCC	\$4.25	Ft
FDOT-MO-PV	FDOT - MONITOR	\$0.00	N/A
FDOT-JS-PC	FDOT - JOINT SEAL - PCC	\$2.75	Ft

*PCC Patching (Full Depth and Partial Depth) consider high-early-strength and high-performing repair material.



5.3 Localized Maintenance and Repair Analysis and Recommendations

The SAPMP provides a planning-level estimation of Localized Maintenance and Repair based on the results of the latest PCI Survey Inspection performed at the airport. Based on the limited sample units inspected, a statistical extrapolation of distresses at the section level is used to estimate the quantities of recommended repair activities based on the policies defined in **5.2 Localized M&R Policy**. The PCI Survey Inspections did not consist of 100% inspection of all sample units; therefore, the section-level distress quantities used to estimate the Localized Maintenance and Repair needs are for conceptual planning purposes. The accuracy of the extrapolated distresses, and therefore work quantities, is subject to the amount of sample units inspected and the concentration of distress types observed in sample units. **Appendix B** provides the estimated Localized Maintenance and Repair based on this SAPMP's PCI Survey Inspection efforts. Localized Preventive Maintenance and Repair is typically applied to pavements that are in a condition at or above the Critical PCI of 65. Localized Stopgap Maintenance and Repair is typically applied to pavements that are below the Critical PCI of 65. It is recommended that airport staff evaluate the application of Localized Maintenance and Repair in concert with the planning of Major Rehabilitation efforts identified in Chapter 6 Major Rehabilitation Planning. Pavements with Stopgap recommendations that are subject to near-term Major Rehabilitation efforts may remove the need to perform localized maintenance efforts.

The following **Table 5.3 (a)** summarizes the anticipated Localized Maintenance and Repair efforts based on the PCI Survey Inspection efforts performed at this airport as part of this SAPMP System Update. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (a) Summary of Airport Localized M&R Planning Cost and Quantity at Network Level

Work Description	Work Category	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
FDOT - PATCHING - AC FULL DEPTH	PREVENTIVE	4,260	SqFt	\$ 38,330.00
FDOT - CRACK SEALING - AC	PREVENTIVE	2,755	Ft	\$ 8,270.00
FDOT - SURFACE SEAL	PREVENTIVE	209,650	SqFt	\$ 115,310.00
FDOT - CRACK SEALING - PCC	PREVENTIVE	15	Ft	\$ 60.00
FDOT - JOINT SEAL - PCC	PREVENTIVE	1,075	Ft	\$ 2,960.00
FDOT - SURFACE SEAL	STOPGAP	68,210	SqFt	\$ 37,520.00
FDOT - PATCHING - AC FULL DEPTH	STOPGAP	4,140	SqFt	\$ 37,220.00
FDOT - PATCHING - AC PARTIAL DEPTH	STOPGAP	3,235	SqFt	\$ 12,930.00
FDOT - CRACK SEALING - AC	STOPGAP	3,975	Ft	\$ 11,930.00
FDOT - JOINT SEAL - PCC	STOPGAP	750	Ft	\$ 2,070.00
FDOT - PATCHING - PCC FULL DEPTH	STOPGAP	10	SqFt	\$ 970.00
FDOT - CRACK SEALING - PCC	STOPGAP	30	Ft	\$ 120.00
FDOT - SLAB REPLACEMENT - PCC	STOPGAP	300	SqFt	\$ 9,000.00



The following **Table 5.3 (b)** provides further breakdown of the anticipated planning-level cost at the section level for the pavements exhibiting distresses that would benefit from Localized M&R. The table shows the approximate improved “End Condition” of the section after the application of Localized M&R. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (b) Summary of Airport Localized M&R Planning Cost and Quantity at Section Level

Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
CRG	AP FAA	4505	147,450	80	89	\$ -
CRG	AP FAA	4510	6,400	78	83	\$ -
CRG	AP N	4205	24,445	100	100	\$ -
CRG	AP N	4210	265,650	100	100	\$ -
CRG	AP N	4215	22,406	100	100	\$ -
CRG	AP N	4220	27,322	30	67	\$ -
CRG	AP NW	4305	41,023	63	68	\$ -
CRG	AP NW	4310	204,437	100	100	\$ -
CRG	AP NW	4320	56,781	100	100	\$ -
CRG	AP RU RW 5	5205	22,135	77	100	\$ -
CRG	AP RU RW 14	5310	24,645	71	72	\$ -
CRG	AP RU RW 23	5105	12,030	73	91	\$ -
CRG	AP RU RW 23	5110	6,117	100	100	\$ -
CRG	AP S	4105	185,265	100	100	\$ -
CRG	AP S	4115	15,813	100	100	\$ -
CRG	AP SW	4405	8,887	12	47	\$ -
CRG	AP SW	4406	2,417	86	98	\$ -
CRG	AP SW	4407	14,286	56	62	\$ -
CRG	AP SW	4410	12,829	100	100	\$ -
CRG	AP SW	4415	23,211	68	77	\$ -
CRG	AP SW	4420	12,167	67	81	\$ -
CRG	AP SW	4430	4,074	26	68	\$ -
CRG	AP SW	4435	20,729	74	76	\$ -
CRG	RW 14-32	6205	45,000	100	100	\$ -
CRG	RW 14-32	6210	355,800	100	100	\$ -
CRG	RW 5-23	6105	363,800	68	74	\$ -
CRG	RW 5-23	6110	25,800	100	100	\$ -
CRG	TL A3	153	69,029	100	100	\$ -
CRG	TL A3	155	19,174	79	85	\$ -
CRG	TW A	105	74,656	57	63	\$ -
CRG	TW A	110	6,423	100	100	\$ -
CRG	TW A	120	37,712	72	91	\$ -
CRG	TW A1	130	22,201	84	90	\$ -



Network ID	Branch ID	Section ID	Area (SF)	Start Condition	End Condition	Cost
CRG	TW A2	132	3,131	69	74	\$ -
CRG	TW A2	135	6,046	57	69	\$ -
CRG	TW A3	142	13,123	100	100	\$ -
CRG	TW A3	145	4,606	72	96	\$ -
CRG	TW A3	150	4,850	81	86	\$ -
CRG	TW A4	160	5,193	66	73	\$ -
CRG	TW A4	165	5,091	100	100	\$ -
CRG	TW A5	170	5,011	100	100	\$ -
CRG	TW A5	175	5,069	55	64	\$ -
CRG	TW A5	180	8,126	64	70	\$ -
CRG	TW A5	185	13,533	100	100	\$ -
CRG	TW B	215	29,838	77	100	\$ -
CRG	TW B	225	59,500	55	62	\$ -
CRG	TW B	227	5,899	70	84	\$ -
CRG	TW B	230	3,679	81	89	\$ -
CRG	TW B	235	26,915	68	91	\$ -
CRG	TW B1	210	7,110	59	66	\$ -
CRG	TW B2	220	3,863	81	90	\$ -
CRG	TW B2	240	11,812	69	93	\$ -
CRG	TW B2	242	4,802	82	87	\$ -
CRG	TW B2	243	6,422	42	53	\$ -
CRG	TW B3	244	3,380	70	75	\$ -
CRG	TW B4	245	9,056	31	52	\$ -
CRG	TW B4	250	15,426	67	70	\$ -
CRG	TW B4	265	3,169	80	83	\$ -
CRG	TW B5	255	4,433	51	60	\$ -
CRG	TW B5	260	5,545	80	85	\$ -
CRG	TW C	305	24,696	100	100	\$ -
CRG	TW C	310	5,648	100	100	\$ -
CRG	TW C	320	16,569	57	67	\$ -
CRG	TW D	455	12,087	80	83	\$ -
CRG	TW D	460	29,215	78	82	\$ -
CRG	TW E	505	14,164	100	100	\$ -
CRG	TW F	605	9,632	100	100	\$ -
CRG	TW F	610	5,562	100	100	\$ -
CRG	TW G	765	65,079	73	87	\$ -
CRG	TW G	770	9,691	75	89	\$ -




The following **Table 5.3 (c)** provides a summary of the anticipated planning-level costs for Localized Preventive Maintenance and Repair and Localized Stopgap Maintenance and Repair. The following table depicts planning-level costs rounded to the nearest ten dollars.

Table 5.3 (c) Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 164,930.00
Stopgap	\$ 111,760.00
<i>Planning-Level Localized M&R Needs =</i>	<i>\$ 276,690.00</i>

Chapter 6






Chapter 6 – Major Rehabilitation Planning

6.1 Major Rehabilitation


Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section to meet the traffic demand. Major rehabilitation is recommended when a pavement section falls below the Critical PCI value that is defined during the system customization or if a pavement section has a significant observation of load-related distress. Observation of any load-related distress potentially indicates that the section may be structurally deficient or that the aircraft loads being applied to the pavement section are different than what the section was designed for. **Figures 6.1 (a) and 6.1 (b)** depict the decision process for major rehabilitation project identification with the assumption of available funds. Should funding be unavailable for pavement sections in need of major rehabilitation, the airport may elect to apply the appropriate localized stopgap repair.

Figures 6.1 (a) Major Rehabilitation Planning Decision Diagram, $PCI \leq \text{Critical PCI}$





Figures 6.1 (b) Major Rehabilitation Planning Decision Diagram, $PCI > \text{Critical } PCI$





6.1.1 Critical PCI

For the FDOT SAPMP the development of a major rehabilitation program is based on the Critical PCI concept. The **Critical PCI** concept assumes that it is more cost-effective to maintain pavements above, rather than below their critical PCI. It is assumed that once a pavement section deteriorates to the Critical PCI value that it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance. This method includes defining the Critical PCI and introducing major rehabilitation work types.

Identification of annual and long-range Major Rehabilitation work plans are typically based on the Critical PCI concept. The Critical PCI is defined as the PCI value at which the rate of loss (deterioration) increases with time, or the cost of applying localized maintenance and repair increases or is not effective. A Critical PCI is usually within a range of 55 and 70; the following procedure is standard approach in developing a specific Critical PCI:

1. Develop a pavement performance model and refine a prediction model for the pavements considered.
2. Select a localized maintenance and repair policy to be used in developing a work plan.
3. Apply the selected localized policy to the pavement sections for a range of PCI.
4. Compute the unit cost per area for each PCI range.
5. Plot the cost versus the PCI.
6. Determine the Critical PCI based on the point where the cost is insignificant.

The FDOT SAPMP defines the Critical PCI at 65 – this is based on the historic trends in pavement performance and Statewide planning efforts.

6.1.2 FDOT Recommended Minimum Service-Level PCI

The FDOT has recommended **Minimum Service-Level PCI** for airports' airfield pavements based on the following characteristics; airport type within FDOT SAPMP, branch use, and expected aircraft operations. For the purposes of Major Rehabilitation, the Critical PCI is typically the threshold condition that triggers major construction, however it is recommended that the airports maintain the Minimum Service-Level PCI with a combination of Localized Maintenance and Repair and timely Major Rehabilitation. **Table 6.1.2** summarizes the FDOT Recommended Minimum Service-Level PCI.

Table 6.1.2 FDOT Recommended Minimum Service-Level PCI

Branch Use	FDOT Recommended PCI	Additional Consideration
Runway	75	Aircraft Fleet Mix Changes Primary Runway
Taxiway / Taxilane	65	Aircraft Fleet Mix Changes Expected Operations
Aprons / Run-Ups / Ramps	65	Ground Service Equipment Non-Aircraft Operations (e.g. fueling)



6.2 Major Rehabilitation Policy

6.2.1 Major Rehabilitation Pavement Section Development

The review of the existing as-built record documentation within the participating airports' archives was used as the basis of the conceptual pavement design sections. Refinement of the pavement section layers was performed in consideration of the FAA **AC 150/ 5320-6F "Airport Pavement Design and Evaluation."** It should be noted that no subsurface geotechnical investigation, ALTA/ACSM Survey, topographic survey, utilities survey, environmental, or site specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this report. The following **Tables 6.2.1 (a) and (b)** provide details on the conceptual pavement sections developed for this study.

Major rehabilitation is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Restoration). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Restoration for AC, AAC, and APC flexible pavement types and PCC Reconstruction and PCC Restoration for PCC rigid pavement types. The pavement sections have been based on the average RL Airport Type requirements; no pavement design has been performed in accordance with AC 150/5320-6F for the determined conceptual sections.

Table 6.2.1 (a) Conceptual Pavement Section for Major Rehabilitation – Flexible Asphalt Concrete

Rehabilitation Type	Reliever (RL) Airport
AC Restoration <i>Combination of asphalt pavement milling and overlay with 25% of the areas subject to full-depth reconstruction.</i> PCI = 41 to 65	75% Mill and Overlay P-101 AC Milling (3") P-603 Bituminous Tack P-401 (HMA) (3") 25% AC Reconstruction P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (4") <i>Excludes any paved shoulder features.</i>
AC Reconstruction <i>Full-depth asphalt pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-152 Subgrade (12") P-211 Base (8") P-602 Bituminous Prime P-603 Bituminous Tack P-401 HMA (4") <i>Excludes any paved shoulder features.</i>



Table 6.2.1 (b) Conceptual Pavement Section for Major Rehabilitation – Rigid Portland Cement Concrete

Rehabilitation Type	Reliever (RL) Airport
PCC Restoration <i>Restoration of PCC pavement with a combination of crack sealing, joint seal replacement, and replacement of 25% of slab panels.</i> PCI = 41 to 65	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (if needed, typical) (6") P-501 Rigid PCC (15") *Select Slabs (25%) **Crack Seal and Limited Patching
PCC Reconstruction <i>Full-depth rigid pavement section reconstruction.</i> PCI = 40 or less	P-101 Pavement Removal P-605 Joint Seal Repair P-152 Subgrade (12") P-211 Base (6") P-501 Rigid PCC (14")

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets.

In compliance with FAA Grant Assurances 11 and 19, the FDOT SAPMP provides airports with airfield pavement evaluation reports in accordance with **FAA AC 150/5380-7B Airport Pavement Management Program (PMP)** and **AC 150/5380-6C Guidelines and Procedures for Maintenance of Airport Pavements**. The application of the results of a PCI survey are for planning purposes and are limited to the visual observation of deteriorated pavements in limited sampling; design-level investigation is recommended in accordance with the FAA procedures defined in **AC 5320-6F Airport Pavement Design and Evaluation** and **AC 150/5370-11B Use of Nondestructive Testing in the Evaluation of Airport Pavements**. The aforementioned ACs provide the design-level material properties of in-situ pavement and subgrade layers for the determination of appropriate rehabilitation actions. The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer in performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

The recommendations identified in the Major Rehabilitation Needs consider the **FAA AC 150/5370-10H Standard Specifications for Construction of Airports** when determining the appropriate materials and methods implemented for construction projects, such as pavement rehabilitation, on airports. It should be noted that the **AC 150/5370-10H Standard Specifications for Construction of Airports** was updated in December of 2018. Design-level determination of project specific specifications based on the AC should be developed by the Airport when performing applicable construction projects.



6.2.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinion of probable construction unit costs developed for this System Update was based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets. Neither FDOT nor the Consultant Team has control over the cost of labor, materials, equipment, or over the Contractor's methods of determining prices or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to FDOT at this time and represent only the Consultant Team's judgment as a design professional familiar with the construction industry. This report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Table 6.2.2 Reliever (RL) Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Flexible Asphalt Concrete Cost Per SF	Rigid Portland Cement Concrete Cost per SF
Restoration	41 to 65	\$ 9.50	\$ 13.50
Reconstruction	0 to 40	\$ 12.50	\$ 20.00

Planning-level opinion of probable construction unit costs consider factors for non-pavement improvements, QA/QC testing, and administrative costs.

6.3 Major Rehabilitation Needs

The objective of the major pavement rehabilitation needs analysis is to provide planning-level projects within an airport's airfield pavement network. Major rehabilitation activities are recommended when a pavement section has deteriorated below the Critical PCI value, a point at which localized maintenance and repair activities may not be the most cost-effective solution. In addition, major rehabilitation is also recommended when the Section PCI is at or above the Critical PCI but the section has significant load-related PCI distresses. Identification of rehabilitation needs is done at the Airfield Pavement Network Definition's section level. This however does not limit the airport from further refining limits of project planning areas.

Major rehabilitation is identified within the FDOT SAPMP as major construction activity that would result in an improvement or resetting of the pavement section's PCI to a value of 100. Major rehabilitation recommendations (AC Restoration, AC Reconstruction, PCC Restoration, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance to the FAA Advisory Circulars will be required. Recommendations identified within this planning document do not imply final design.

6.3.1 10-Year Unconstrained Budget Major Rehabilitation Needs

An unconstrained budget (unlimited budget) is performed for a 10-year duration to identify pavement rehabilitation needs based on current or forecasted PCI values deteriorating below the Critical PCI. FDOT recognizes airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. The intent of the 10-Year Major Rehabilitation Needs analysis is to identify pavements that will warrant rehabilitation. It is highly recommended that airport staff utilize this information in support of the development of a practical Capital Improvement Program based on priorities, further design/project-level



investigation, and budgetary constraints. The following **Table 6.3.1** summarizes all identified section-level major rehabilitation needs forecasted for the next 10-year period. It should be noted that the following table depicts planning-level costs and have been rounded for planning purposes.



Table 6.3.1 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	CRG	AP N	4220	AC	27,322	29	AC Reconstruction	\$ 342,000.00
2020	CRG	AP NW	4305	AC	41,023	62	AC Restoration	\$ 390,000.00
2020	CRG	AP SW	4405	PCC	8,887	11	PCC Reconstruction	\$ 178,000.00
2020	CRG	AP SW	4407	AC	14,286	55	AC Restoration	\$ 136,000.00
2020	CRG	AP SW	4430	AC	4,074	25	AC Reconstruction	\$ 51,000.00
2020	CRG	TW A	105	AAC	74,656	56	AC Restoration	\$ 710,000.00
2020	CRG	TW A2	135	AC	6,046	56	AC Restoration	\$ 58,000.00
2020	CRG	TW A5	175	AAC	5,069	54	AC Restoration	\$ 49,000.00
2020	CRG	TW A5	180	AAC	8,126	63	AC Restoration	\$ 78,000.00
2020	CRG	TW B	225	AAC	59,500	54	AC Restoration	\$ 566,000.00
2020	CRG	TW B1	210	AC	7,110	58	AC Restoration	\$ 68,000.00
2020	CRG	TW B2	243	AAC	6,422	41	AC Restoration	\$ 79,000.00
2020	CRG	TW B4	245	AAC	9,056	29	AC Reconstruction	\$ 114,000.00
2020	CRG	TW B5	255	AC	4,433	50	AC Restoration	\$ 43,000.00
2020	CRG	TW C	320	AAC	16,569	56	AC Restoration	\$ 158,000.00
2021	CRG	AP SW	4420	AC	12,167	64	AC Restoration	\$ 116,000.00
2021	CRG	TW A4	160	AAC	5,193	64	AC Restoration	\$ 50,000.00
2022	CRG	AP SW	4415	AC	23,211	64	AC Restoration	\$ 221,000.00
2022	CRG	TW B	235	AC	26,915	64	AC Restoration	\$ 256,000.00
2022	CRG	TW B4	250	AAC	15,426	64	AC Restoration	\$ 147,000.00
2023	CRG	AP RU RW14	5310	AAC	24,645	63	AC Restoration	\$ 235,000.00
2023	CRG	RW 5-23	6105	AAC	363,800	64	AC Restoration	\$ 3,457,000.00
2023	CRG	TW B2	240	AC	11,812	64	AC Restoration	\$ 113,000.00
2024	CRG	AP SW	4435	AAC	20,729	63	AC Restoration	\$ 197,000.00
2024	CRG	TW A2	132	AAC	3,131	64	AC Restoration	\$ 30,000.00
2025	CRG	AP RU RW23	5105	AC	12,030	64	AC Restoration	\$ 115,000.00
2025	CRG	TW A	120	AC	37,712	64	AC Restoration	\$ 359,000.00
2025	CRG	TW A3	145	AC	4,606	64	AC Restoration	\$ 44,000.00
2025	CRG	TW B	227	AAC	5,899	64	AC Restoration	\$ 57,000.00
2025	CRG	TW B3	244	AAC	3,380	64	AC Restoration	\$ 33,000.00
2026	CRG	TW G	765	AC	65,079	64	AC Restoration	\$ 619,000.00
2027	CRG	AP RU RW 5	5205	AC	22,135	64	AC Restoration	\$ 211,000.00
2028	CRG	TW G	770	AC	9,691	63	AC Restoration	\$ 93,000.00
2029	CRG	AP FAA	4505	AC	147,450	64	AC Restoration	\$ 1,401,000.00
2029	CRG	TW B	215	AC	29,838	64	AC Restoration	\$ 284,000.00

*All values have been rounded to the nearest thousand-dollar.



The following **Figure 6.3.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2020 and 2029. **Figure 6.3.1 (b)** provides an inset view of Airfield Pavement Major Rehabilitation Exhibit, a large format exhibit is located in **Appendix C Technical Exhibits**. The exhibit graphically depicts the Major Rehabilitation Needs with rounded costs.

Figure 6.3.1 (a) 10-Year Major Rehabilitation Needs by Program Year








Figure 6.3.1 (b) 10-Year Major Rehabilitation Needs by Program Year Exhibit



Chapter 7





Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Survey Inspections

It is recommended that the airport continue to perform regularly scheduled PCI Survey inspections in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of the airfield pavement facilities.

A high priority should be considered for continuous maintenance record keeping and re-inspection of all the airport's maintained pavement facilities to ensure continued safe aircraft operations. A series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be completely prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is the significant factor in pavement deterioration.

It is recommended that airport sponsors coordinate with their respective Airport Maintenance staff and Airport Engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 – Major Rehabilitation Planning identified major pavement rehabilitation project needs from 2020-2029. The identification of the rehabilitation needs was performed at the section level for manageable project areas with the assumption of an unconstrained budget scenario. Given the uncertainty in the airport-specific budget information and prioritization goals, the unconstrained budget scenario was performed to evaluate the worst-case scenario and identify all the inspected pavements' needs in a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets; further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the airport:

- ▶ Develop a detailed preventive maintenance program for the airport.
- ▶ Further refine and implement the identified 10-year major rehabilitation needs.
- ▶ Maintain detailed records on pavement maintenance, construction, and inspection.
- ▶ Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



7.2 Supporting Documents

001 – Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The exhibit is intended for planning purposes only – further detail on facilities can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A Pavement Analysis Tables**.

002 – Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Appendix C Technical Exhibits**. The exhibit depicts any recent and/or anticipated construction activity within the airfield pavement facilities reported by airport staff. The exhibit is intended to schematically identify the pavement limits of works and general work description. The information reported on the **Airport Response Form** provided by each participating airport was used as the basis of the changes; furthermore, changes are confirmed at the airport with airport staff during the in-brief and debrief meeting.

003 – Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Appendix C Technical Exhibits**. The exhibit is a visual summary of the latest conditions calculated from the results of the PCI Survey performed at the airport. The analysis of the distresses surveyed in accordance with the ASTM D5340-12 (referenced in **Appendix E Inspection Distress Details**) were analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the exhibit and graphically represented using the standard ASTM D5340-12 colors for condition rating categories.

004 – Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Appendix C Technical Exhibits**. The exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. The area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B Airfield Pavement Localized Maintenance and Repair and Major Rehabilitation**.

Inspection Photograph Documentation

Representative field conditions from the PCI Survey are documented with digital photographs located in **Appendix D Inspection Photograph Documentation**. Select photographs are provided with limited caption on the distresses observed – the Appendix does not contain photographs for every sample unit.



7.3 Conclusion

The FDOT SAPMP Update Phase 2 2018-2019 was completed for the airport on behalf of the FDOT ASO in accordance with the Advisory Circulars **150/5380-7B “Airport Pavement Management Program (PMP)”** and **150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements.”** FDOT’s implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM **D5340-12 “Standard Test Method for Airport Pavement Condition Index Surveys.”**

Appendix A

Airfield Pavement Analysis Tables



Table A-1 Pavement System Inventory Details

Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
CRG	FAA APRON	AP FAA	APRON	4505	400	370	147,450	AC	1/1/2004
CRG	FAA APRON	AP FAA	APRON	4510	125	50	6,400	PCC	1/1/2004
CRG	NORTH APRON	AP N	APRON	4205	200	75	24,445	AAC	7/1/2018
CRG	NORTH APRON	AP N	APRON	4210	750	300	265,650	AAC	7/1/2018
CRG	NORTH APRON	AP N	APRON	4215	310	76	22,406	AC	7/1/2018
CRG	NORTH APRON	AP N	APRON	4220	1,370	20	27,322	AC	12/25/1994
CRG	NW APRON	AP NW	APRON	4305	200	187	41,023	AC	1/1/1991
CRG	NW APRON	AP NW	APRON	4310	900	200	204,437	AAC	7/1/2018
CRG	NW APRON	AP NW	APRON	4320	2,040	20	56,781	AAC	7/1/2018
CRG	RUN-UP APRON AT RW 5	AP RU RW 5	APRON	5205	809	75	22,135	AC	1/1/2003
CRG	RUN-UP APRON AT RW 14	AP RU RW14	APRON	5310	73	200	24,645	AAC	1/1/2010
CRG	RUN-UP APRON AT RW 23	AP RU RW23	APRON	5105	150	80	12,030	AC	1/1/2005
CRG	RUN-UP APRON AT RW 23	AP RU RW23	APRON	5110	80	76	6,117	AAC	1/1/2019
CRG	SOUTH APRON	AP S	APRON	4105	580	250	185,265	AAC	7/1/2018
CRG	SOUTH APRON	AP S	APRON	4115	100	160	15,813	AAC	7/1/2018
CRG	SOUTHWEST APRON	AP SW	APRON	4405	150	60	8,887	PCC	12/25/1999
CRG	SOUTHWEST APRON	AP SW	APRON	4406	98	25	2,417	PCC	1/1/2014
CRG	SOUTHWEST APRON	AP SW	APRON	4407	245	60	14,286	AC	12/25/1999
CRG	SOUTHWEST APRON	AP SW	APRON	4410	350	35	12,829	AAC	1/1/2019
CRG	SOUTHWEST APRON	AP SW	APRON	4415	275	78	23,211	AC	1/1/2002
CRG	SOUTHWEST APRON	AP SW	APRON	4420	100	100	12,167	AC	12/25/1994
CRG	SOUTHWEST APRON	AP SW	APRON	4430	59	59	4,074	AC	1/1/2006
CRG	SOUTHWEST APRON	AP SW	APRON	4435	570	35	20,729	AAC	1/1/2007
CRG	RUNWAY 14-32	RW 14-32	RUNWAY	6205	375	100	45,000	AAC	1/1/2019
CRG	RUNWAY 14-32	RW 14-32	RUNWAY	6210	3,558	100	355,800	AAC	1/1/2019
CRG	RUNWAY 5-23	RW 5-23	RUNWAY	6105	3,638	100	363,800	AAC	1/1/2011
CRG	RUNWAY 5-23	RW 5-23	RUNWAY	6110	258	100	25,800	AAC	1/1/2019
CRG	TAXILANE A3	TL A3	TAXILANE	153	800	80	69,029	AC	1/1/2019
CRG	TAXILANE A3	TL A3	TAXILANE	155	550	35	19,174	AC	1/1/2007
CRG	TAXIWAY A	TWA	TAXIWAY	105	2,300	35	74,656	AAC	1/1/2010
CRG	TAXIWAY A	TWA	TAXIWAY	110	120	50	6,423	AAC	1/1/2019
CRG	TAXIWAY A	TWA	TAXIWAY	120	2,120	35	37,712	AC	1/1/2005
CRG	TAXIWAY A1	TWA1	TAXIWAY	130	425	30	22,201	AC	1/1/2005
CRG	TAXIWAY A2	TWA2	TAXIWAY	132	60	35	3,131	AAC	1/1/2010



Network ID	Branch Name	Branch ID	Branch Use	Section ID	Length (FT)	Width (FT)	Area (SF)	Surface Type	Est. Last Construction Date
CRG	TAXIWAY A2	TWA2	TAXIWAY	135	145	35	6,046	AC	1/1/1991
CRG	TAXIWAY A3	TWA3	TAXIWAY	142	247	50	13,123	AAC	1/1/2019
CRG	TAXIWAY A3	TWA3	TAXIWAY	145	132	35	4,606	AC	1/1/2001
CRG	TAXIWAY A3	TWA3	TAXIWAY	150	85	35	4,850	AAC	1/1/2010
CRG	TAXIWAY A4	TWA4	TAXIWAY	160	100	40	5,193	AAC	1/1/2010
CRG	TAXIWAY A4	TWA4	TAXIWAY	165	100	40	5,091	AAC	7/1/2018
CRG	TAXIWAY A5	TWA5	TAXIWAY	170	100	40	5,011	AAC	7/1/2018
CRG	TAXIWAY A5	TWA5	TAXIWAY	175	100	40	5,069	AAC	1/1/2010
CRG	TAXIWAY A5	TWA5	TAXIWAY	180	202	40	8,126	AAC	1/1/2010
CRG	TAXIWAY A5	TWA5	TAXIWAY	185	257	50	13,533	AAC	1/1/2019
CRG	TAXIWAY B	TWB	TAXIWAY	215	2,120	35	29,838	AC	1/1/2005
CRG	TAXIWAY B	TWB	TAXIWAY	225	1,555	35	59,500	AAC	1/1/2010
CRG	TAXIWAY B	TWB	TAXIWAY	227	170	35	5,899	AAC	1/1/2003
CRG	TAXIWAY B	TWB	TAXIWAY	230	135	50	3,679	AAC	1/1/2011
CRG	TAXIWAY B	TWB	TAXIWAY	235	700	35	26,915	AC	1/1/2003
CRG	TAXIWAY B1	TWB1	TAXIWAY	210	163	40	7,110	AC	12/25/1994
CRG	TAXIWAY B2	TWB2	TAXIWAY	220	175	50	3,863	AAC	1/1/2011
CRG	TAXIWAY B2	TWB2	TAXIWAY	240	335	35	11,812	AC	1/1/2003
CRG	TAXIWAY B2	TWB2	TAXIWAY	242	75	35	4,802	AAC	1/1/2010
CRG	TAXIWAY B2	TWB2	TAXIWAY	243	180	35	6,422	AAC	12/25/1994
CRG	TAXIWAY B3	TWB3	TAXIWAY	244	55	35	3,380	AAC	1/1/2010
CRG	TAXIWAY B4	TWB4	TAXIWAY	245	175	40	9,056	AAC	1/2/1984
CRG	TAXIWAY B4	TWB4	TAXIWAY	250	405	35	15,426	AAC	1/1/2010
CRG	TAXIWAY B4	TWB4	TAXIWAY	265	150	50	3,169	AAC	1/1/2011
CRG	TAXIWAY B5	TWB5	TAXIWAY	255	210	40	4,433	AC	1/1/1991
CRG	TAXIWAY B5	TWB5	TAXIWAY	260	2,120	35	5,545	AC	1/1/2005
CRG	TAXIWAY C	TWC	TAXIWAY	305	400	60	24,696	AAC	1/1/2019
CRG	TAXIWAY C	TWC	TAXIWAY	310	40	136	5,648	AAC	1/1/2019
CRG	TAXIWAY C	TWC	TAXIWAY	320	209	80	16,569	AAC	12/25/2010
CRG	TAXIWAY D	TWD	TAXIWAY	455	495	35	12,087	AC	1/1/2005
CRG	TAXIWAY D	TWD	TAXIWAY	460	360	35	29,215	AC	1/1/2005
CRG	TAXIWAY E	TWE	TAXIWAY	505	270	50	14,164	AAC	1/1/2019
CRG	TAXIWAY F	TWF	TAXIWAY	605	164	60	9,632	AAC	1/1/2019
CRG	TAXIWAY F	TWF	TAXIWAY	610	125	44	5,562	AAC	1/1/2019
CRG	TAXIWAY G	TWG	TAXIWAY	765	1,885	35	65,079	AC	1/1/2003
CRG	TAXIWAY G	TWG	TAXIWAY	770	250	35	9,691	AC	1/1/2004



Table A-2 Pavement Condition Index Summary (Last Inspection) – Section Level

Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
CRG	RUNWAY 5-23	RUNWAY	6105	363,800	68	Fair
CRG	RUNWAY 5-23	RUNWAY	6110	25,800	100	Good
CRG	RUNWAY 14-32	RUNWAY	6205	45,000	100	Good
CRG	RUNWAY 14-32	RUNWAY	6210	355,800	100	Good
CRG	TAXIWAY A	TAXIWAY	105	74,656	57	Fair
CRG	TAXIWAY A	TAXIWAY	110	6,423	100	Good
CRG	TAXIWAY A	TAXIWAY	120	37,712	72	Satisfactory
CRG	TAXIWAY A1	TAXIWAY	130	22,201	84	Satisfactory
CRG	TAXIWAY A2	TAXIWAY	132	3,131	69	Fair
CRG	TAXIWAY A2	TAXIWAY	135	6,046	57	Fair
CRG	TAXIWAY A3	TAXIWAY	142	13,123	100	Good
CRG	TAXIWAY A3	TAXIWAY	145	4,606	72	Satisfactory
CRG	TAXIWAY A3	TAXIWAY	150	4,850	81	Satisfactory
CRG	TAXIWAY A4	TAXIWAY	160	5,193	66	Fair
CRG	TAXIWAY A4	TAXIWAY	165	5,091	100	Good
CRG	TAXIWAY A5	TAXIWAY	170	5,011	100	Good
CRG	TAXIWAY A5	TAXIWAY	175	5,069	55	Poor
CRG	TAXIWAY A5	TAXIWAY	180	8,126	64	Fair
CRG	TAXIWAY A5	TAXIWAY	185	13,533	100	Good
CRG	TAXIWAY B	TAXIWAY	215	29,838	77	Satisfactory
CRG	TAXIWAY B	TAXIWAY	225	59,500	55	Poor
CRG	TAXIWAY B	TAXIWAY	227	5,899	70	Fair
CRG	TAXIWAY B	TAXIWAY	230	3,679	81	Satisfactory
CRG	TAXIWAY B	TAXIWAY	235	26,915	68	Fair
CRG	TAXIWAY B1	TAXIWAY	210	7,110	59	Fair
CRG	TAXIWAY B2	TAXIWAY	220	3,863	81	Satisfactory
CRG	TAXIWAY B2	TAXIWAY	240	11,812	69	Fair
CRG	TAXIWAY B2	TAXIWAY	242	4,802	82	Satisfactory
CRG	TAXIWAY B2	TAXIWAY	243	6,422	42	Poor
CRG	TAXIWAY B3	TAXIWAY	244	3,380	70	Fair
CRG	TAXIWAY B4	TAXIWAY	245	9,056	31	Very Poor
CRG	TAXIWAY B4	TAXIWAY	250	15,426	67	Fair
CRG	TAXIWAY B4	TAXIWAY	265	3,169	80	Satisfactory
CRG	TAXIWAY B5	TAXIWAY	255	4,433	51	Poor
CRG	TAXIWAY B5	TAXIWAY	260	5,545	80	Satisfactory
CRG	TAXIWAY C	TAXIWAY	305	24,696	100	Good
CRG	TAXIWAY C	TAXIWAY	310	5,648	100	Good



Network ID	Branch Name	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
CRG	TAXIWAY C	TAXIWAY	320	16,569	57	Fair
CRG	TAXIWAY D	TAXIWAY	455	12,087	80	Satisfactory
CRG	TAXIWAY D	TAXIWAY	460	29,215	78	Satisfactory
CRG	TAXIWAY E	TAXIWAY	505	14,164	100	Good
CRG	TAXIWAY F	TAXIWAY	605	9,632	100	Good
CRG	TAXIWAY F	TAXIWAY	610	5,562	100	Good
CRG	TAXIWAY G	TAXIWAY	765	65,079	73	Satisfactory
CRG	TAXIWAY G	TAXIWAY	770	9,691	75	Satisfactory
CRG	TAXILANE A3	TAXILANE	153	69,029	100	Good
CRG	TAXILANE A3	TAXILANE	155	19,174	79	Satisfactory
CRG	SOUTH APRON	APRON	4105	185,265	100	Good
CRG	SOUTH APRON	APRON	4115	15,813	100	Good
CRG	NORTH APRON	APRON	4205	24,445	100	Good
CRG	NORTH APRON	APRON	4210	265,650	100	Good
CRG	NORTH APRON	APRON	4215	22,406	100	Good
CRG	NORTH APRON	APRON	4220	27,322	30	Very Poor
CRG	NW APRON	APRON	4305	41,023	63	Fair
CRG	NW APRON	APRON	4310	204,437	100	Good
CRG	NW APRON	APRON	4320	56,781	100	Good
CRG	SOUTHWEST APRON	APRON	4405	8,887	12	Serious
CRG	SOUTHWEST APRON	APRON	4406	2,417	86	Good
CRG	SOUTHWEST APRON	APRON	4407	14,286	56	Fair
CRG	SOUTHWEST APRON	APRON	4410	12,829	100	Good
CRG	SOUTHWEST APRON	APRON	4415	23,211	68	Fair
CRG	SOUTHWEST APRON	APRON	4420	12,167	67	Fair
CRG	SOUTHWEST APRON	APRON	4430	4,074	26	Very Poor
CRG	SOUTHWEST APRON	APRON	4435	20,729	74	Satisfactory
CRG	FAA APRON	APRON	4505	147,450	80	Satisfactory
CRG	FAA APRON	APRON	4510	6,400	78	Satisfactory
CRG	RUN-UP APRON AT RW 23	APRON	5105	12,030	73	Satisfactory
CRG	RUN-UP APRON AT RW 23	APRON	5110	6,117	100	Good
CRG	RUN-UP APRON AT RW 5	APRON	5205	22,135	77	Satisfactory
CRG	RUN-UP APRON AT RW 14	APRON	5310	24,645	71	Satisfactory



Table A-3 Forecasted PCI 2020-2029

Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
CRG	AP FAA	4505	80	78	76	74	73	71	69	68	66	65	64
CRG	AP FAA	4510	78	77	75	74	73	72	70	69	68	66	65
CRG	AP N	4205	100	96	94	92	90	88	85	83	81	79	77
CRG	AP N	4210	100	96	94	92	90	88	85	83	81	79	77
CRG	AP N	4215	100	96	94	91	89	87	85	82	80	78	76
CRG	AP N	4220	30	29	29	29	28	28	28	27	27	27	26
CRG	AP NW	4305	63	62	61	60	59	58	57	57	56	55	54
CRG	AP NW	4310	100	96	94	92	90	88	85	83	81	79	77
CRG	AP NW	4320	100	96	94	92	90	88	85	83	81	79	77
CRG	AP RU RW 5	5205	77	75	73	72	70	68	67	66	64	63	62
CRG	AP RU RW14	5310	71	69	67	65	63	60	58	56	54	52	50
CRG	AP RU RW23	5105	73	71	70	68	67	65	64	63	62	61	60
CRG	AP RU RW23	5110	100	97	95	93	91	89	86	84	82	80	78
CRG	AP S	4105	100	96	94	92	90	88	85	83	81	79	77
CRG	AP S	4115	100	96	94	92	90	88	85	83	81	79	77
CRG	AP SW	4405	12	11	9	8	7	6	4	3	2	0	0
CRG	AP SW	4406	86	85	83	82	81	80	78	77	76	74	73
CRG	AP SW	4407	56	55	54	54	53	52	51	51	50	49	48
CRG	AP SW	4410	100	97	95	93	91	89	86	84	82	80	78
CRG	AP SW	4415	68	67	65	64	63	62	61	60	59	58	57
CRG	AP SW	4420	67	66	64	63	62	61	60	59	58	58	57
CRG	AP SW	4430	26	25	25	25	24	24	23	23	23	22	22
CRG	AP SW	4435	74	72	70	68	66	63	61	59	57	55	53
CRG	RW 14-32	6205	100	97	94	92	89	87	85	83	81	80	78
CRG	RW 14-32	6210	100	97	94	92	89	87	85	83	81	80	78
CRG	RW 5-23	6105	68	67	66	65	64	64	63	62	61	61	60
CRG	RW 5-23	6110	100	97	94	92	89	87	85	83	81	80	78
CRG	TLA3	153	100	98	96	94	93	91	89	88	86	85	83
CRG	TLA3	155	79	78	76	75	73	72	71	69	68	67	66
CRG	TWA	105	57	56	55	54	53	52	51	51	50	48	47
CRG	TWA	110	100	97	95	92	90	88	86	84	83	81	79
CRG	TWA	120	72	71	69	68	67	66	64	63	62	61	60
CRG	TWA1	130	84	82	81	80	78	77	75	74	73	71	70
CRG	TWA2	132	69	68	67	66	65	64	63	62	61	61	60
CRG	TWA2	135	57	56	55	54	53	52	51	50	49	48	48
CRG	TWA3	142	100	97	95	92	90	88	86	84	83	81	79
CRG	TWA3	145	72	71	69	68	67	66	64	63	62	61	60



Network ID	Branch ID	Section ID	Last PCI	Forecasted PCI									
				2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
CRG	TWA3	150	81	79	78	76	75	74	72	71	70	69	68
CRG	TWA4	160	66	65	64	63	62	61	61	60	59	58	57
CRG	TWA4	165	100	96	94	91	89	87	85	84	82	80	79
CRG	TWA5	170	100	96	94	91	89	87	85	84	82	80	79
CRG	TWA5	175	55	54	53	52	51	50	49	48	47	46	44
CRG	TWA5	180	64	63	62	61	60	60	59	58	57	56	56
CRG	TWA5	185	100	97	95	92	90	88	86	84	83	81	79
CRG	TWB	215	77	76	74	73	71	70	69	68	66	65	64
CRG	TWB	225	55	54	53	52	51	50	49	48	47	46	44
CRG	TWB	227	70	69	68	67	66	65	64	63	62	61	61
CRG	TWB	230	81	79	78	76	75	74	72	71	70	69	68
CRG	TWB	235	68	67	65	64	63	62	61	60	59	57	56
CRG	TWB1	210	59	58	57	56	55	54	53	52	51	50	49
CRG	TWB2	220	81	79	78	76	75	74	72	71	70	69	68
CRG	TWB2	240	69	68	66	65	64	63	62	61	59	58	57
CRG	TWB2	242	82	80	79	77	76	75	73	72	71	70	69
CRG	TWB2	243	42	41	39	37	36	34	32	30	28	26	24
CRG	TWB3	244	70	69	68	67	66	65	64	63	62	61	61
CRG	TWB4	245	31	29	27	25	23	21	19	17	14	12	10
CRG	TWB4	250	67	66	65	64	63	62	61	61	60	59	58
CRG	TWB4	265	80	78	77	76	74	73	72	71	69	68	67
CRG	TWB5	255	51	50	49	48	47	47	46	45	44	44	43
CRG	TWB5	260	80	79	77	76	74	73	72	70	69	68	66
CRG	TWC	305	100	97	95	92	90	88	86	84	83	81	79
CRG	TWC	310	100	97	95	92	90	88	86	84	83	81	79
CRG	TWC	320	57	56	55	54	53	52	51	51	50	48	47
CRG	TWD	455	80	79	77	76	74	73	72	70	69	68	66
CRG	TWD	460	78	77	75	74	72	71	70	69	67	66	65
CRG	TWE	505	100	97	95	92	90	88	86	84	83	81	79
CRG	TWF	605	100	97	95	92	90	88	86	84	83	81	79
CRG	TWF	610	100	97	95	92	90	88	86	84	83	81	79
CRG	TWG	765	73	72	70	69	68	66	65	64	63	62	61
CRG	TWG	770	75	74	72	71	70	68	67	66	65	63	62

10/3/2019

Work History Report

Page 1 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: AP FAA	FAA APRON	Section: 4505	Surface: AC	
L.C.D. 1/1/2004	Use: APRON	Rank: T	Length: 400.00 (Ft)	Width: 370.00 (Ft)	True Area: 147450.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2004	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1983 BIT OL SECTION UNKNOWN
1/1/1983	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP FAA	FAA APRON	Section: 4510	Surface: PCC	
L.C.D. 1/1/2004	Use: APRON	Rank: P	Length: 125.00 (Ft)	Width: 50.00 (Ft)	True Area: 6400.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2004	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP N	NORTH APRON	Section: 4205	Surface: AAC	
L.C.D. 7/1/2018	Use: APRON	Rank: P	Length: 200.00 (Ft)	Width: 75.00 (Ft)	True Area: 24445.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	EST 1947 BIT SECTION UNKNOWN
1/1/1947	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP N	NORTH APRON	Section: 4210	Surface: AAC	
L.C.D. 7/1/2018	Use: APRON	Rank: P	Length: 750.00 (Ft)	Width: 300.00 (Ft)	True Area: 265650.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	EMULSION SEAL 1983 2" P-401 6" P-211 4" P-154
1/2/1983	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP N	NORTH APRON	Section: 4215	Surface: AC	
L.C.D. 7/1/2018	Use: APRON	Rank: S	Length: 310.00 (Ft)	Width: 76.00 (Ft)	True Area: 22406.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP N	NORTH APRON	Section: 4220	Surface: AC	
L.C.D. 12/25/199	Use: APRON	Rank: S	Length: 1,370.00 (Ft)	Width: 20.00 (Ft)	True Area: 27322.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP NW	NW APRON	Section: 4305	Surface: AC	
L.C.D. 1/1/1991	Use: APRON	Rank: P	Length: 200.00 (Ft)	Width: 187.00 (Ft)	True Area: 41023.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" BIT 6" LIMEROCK

10/3/2019

Work History Report

Page 2 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: AP NW	NW APRON		Section: 4310	Surface: AAC
L.C.D. 7/1/2018	Use: APRON	Rank: P	Length: 900.00 (Ft)	Width: 200.00 (Ft)	True Area: 204437.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	EST 1960 BIT SECTION UNKNOWN
1/1/1960	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP NW	NW APRON		Section: 4320	Surface: AAC
L.C.D. 7/1/2018	Use: APRON	Rank: P	Length: 2,040.00 (Ft)	Width: 20.00 (Ft)	True Area: 56781.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP RU RW 5	RUN-UP APRON		Section: 5205	Surface: AC
L.C.D. 1/1/2003	Use: APRON	Rank: T	Length: 809.00 (Ft)	Width: 75.00 (Ft)	True Area: 22135.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OL ON EXISTING SECTION
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP RU RW14	RUN-UP APRON		Section: 5310	Surface: AAC
L.C.D. 1/1/2010	Use: APRON	Rank: P	Length: 73.00 (Ft)	Width: 200.00 (Ft)	True Area: 24645.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 6" P-211 6" P-154
1/1/1991	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP RU RW23	RUN-UP APRON		Section: 5105	Surface: AC
L.C.D. 1/1/2005	Use: APRON	Rank: P	Length: 150.00 (Ft)	Width: 80.00 (Ft)	True Area: 12030.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP RU RW23	RUN-UP APRON		Section: 5110	Surface: AAC
L.C.D. 1/1/2019	Use: APRON	Rank: P	Length: 80.00 (Ft)	Width: 76.00 (Ft)	True Area: 6117.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 3 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: AP S	SOUTH APRON		Section: 4105	Surface: AAC
L.C.D. 7/1/2018	Use: APRON	Rank: P	Length: 580.00 (Ft)	Width: 250.00 (Ft)	True Area: 185265.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	EMULSION SEAL 1986 1.5" P-401 P-403 LEVELING ON EXISTING BIT
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/2/1986	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1986	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP S	SOUTH APRON		Section: 4115	Surface: AAC
L.C.D. 7/1/2018	Use: APRON	Rank: P	Length: 100.00 (Ft)	Width: 160.00 (Ft)	True Area: 15813.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	EMULSION SEAL EST 1986 BIT SECTION UNKNOWN
1/1/2007	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1986	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4405	Surface: PCC
L.C.D. 12/25/199	Use: APRON	Rank: S	Length: 150.00 (Ft)	Width: 60.00 (Ft)	True Area: 8887.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4406	Surface: PCC
L.C.D. 1/1/2014	Use: APRON	Rank: S	Length: 98.00 (Ft)	Width: 25.00 (Ft)	True Area: 2417.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	CR-PC	Complete Reconstruction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4407	Surface: AC
L.C.D. 12/25/199	Use: APRON	Rank: P	Length: 245.00 (Ft)	Width: 60.00 (Ft)	True Area: 14286.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4410	Surface: AAC
L.C.D. 1/1/2019	Use: APRON	Rank: S	Length: 350.00 (Ft)	Width: 35.00 (Ft)	True Area: 12829.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4415	Surface: AC
L.C.D. 1/1/2002	Use: APRON	Rank: S	Length: 275.00 (Ft)	Width: 78.00 (Ft)	True Area: 23211.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 4 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4420	Surface: AC
L.C.D. 12/25/1994	Use: APRON	Rank: S	Length: 100.00 (Ft)	Width: 100.00 (Ft)	True Area: 12167.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4430	Surface: AC
L.C.D. 1/1/2006	Use: APRON	Rank: S	Length: 59.00 (Ft)	Width: 59.00 (Ft)	True Area: 4074.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2006	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: AP SW	SOUTHWEST AP		Section: 4435	Surface: AAC
L.C.D. 1/1/2007	Use: APRON	Rank: S	Length: 570.00 (Ft)	Width: 35.00 (Ft)	True Area: 20729.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: RW 14-32	RUNWAY 14-32		Section: 6205	Surface: AAC
L.C.D. 1/1/2019	Use: RUNWAY	Rank: P	Length: 375.00 (Ft)	Width: 100.00 (Ft)	True Area: 45000.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill with 2" P-401 ov
1/1/2005	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	5.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: RW 14-32	RUNWAY 14-32		Section: 6210	Surface: AAC
L.C.D. 1/1/2019	Use: RUNWAY	Rank: P	Length: 3,558.00 (Ft)	Width: 100.00 (Ft)	True Area: 355800.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (additional mill a
1/1/2005	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	5.00	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 5 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: RW 5-23	RUNWAY 5-23		Section: 6105	Surface: AAC
L.C.D. 1/1/2011	Use: RUNWAY	Rank: S	Length: 3,638.00 (Ft)	Width: 100.00 (Ft)	True Area: 363800.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL 1971 1.5" P-401 OL 2" P-401 LEVELING 1942 5" BIT 6" STAB BASE
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	5.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: RW 5-23	RUNWAY 5-23		Section: 6110	Surface: AAC
L.C.D. 1/1/2019	Use: RUNWAY	Rank: P	Length: 258.00 (Ft)	Width: 100.00 (Ft)	True Area: 25800.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill with 2" P-401 ov 1991 2" P-401 OL 1971 1.5" P-401 2" P-401 LEVELING 1942 5" BIT 6" STAB BASE
1/1/2005	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1971	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	5.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TL A3	TAXILANE A3		Section: 153	Surface: AC
L.C.D. 1/1/2019	Use: TAXILAN	Rank: P	Length: 800.00 (Ft)	Width: 80.00 (Ft)	True Area: 69029.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	4" P-401 (2 LIFTS) OVER 6" P-211 L

Network: JACKSONVILLE EX		Branch: TL A3	TAXILANE A3		Section: 155	Surface: AC
L.C.D. 1/1/2007	Use: TAXILAN	Rank: P	Length: 550.00 (Ft)	Width: 35.00 (Ft)	True Area: 19174.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW A	TAXIWAY A		Section: 105	Surface: AAC
L.C.D. 1/1/2010	Use: TAXIWAY	Rank: P	Length: 2,300.00 (Ft)	Width: 35.00 (Ft)	True Area: 74656.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 2"+ P-401 OL 1971 3.5" P-401 OL
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1971	IMPORT ED	BUILT	0.00	3.50	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 6 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: TW A	TAXIWAY A		Section: 110	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 120.00 (Ft)	Width: 50.00 (Ft)	True Area: 6423.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/2005	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1991 2"+ P-401 OL
1/1/1971	IMPORT ED	BUILT	0.00	3.50	<input checked="" type="checkbox"/>	1971 3.5" P-401 OL

Network: JACKSONVILLE EX		Branch: TW A1	TAXIWAY A1		Section: 130	Surface: AC
L.C.D. 1/1/2005	Use: TAXIWAY	Rank: S	Length: 425.00 (Ft)	Width: 30.00 (Ft)	True Area: 22201.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW A	TAXIWAY A		Section: 120	Surface: AC
L.C.D. 1/1/2005	Use: TAXIWAY	Rank: P	Length: 2,120.00 (Ft)	Width: 35.00 (Ft)	True Area: 37712.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW A2	TAXIWAY A2		Section: 132	Surface: AAC
L.C.D. 1/1/2010	Use: TAXIWAY	Rank: P	Length: 60.00 (Ft)	Width: 35.00 (Ft)	True Area: 3131.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" P-154

Network: JACKSONVILLE EX		Branch: TW A2	TAXIWAY A2		Section: 135	Surface: AC
L.C.D. 1/1/1991	Use: TAXIWAY	Rank: P	Length: 145.00 (Ft)	Width: 35.00 (Ft)	True Area: 6046.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" P-154

Network: JACKSONVILLE EX		Branch: TW A3	TAXIWAY A3		Section: 142	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 247.00 (Ft)	Width: 50.00 (Ft)	True Area: 13123.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/2005	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2001	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 7 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX Branch: TW A3 TAXIWAY A3 Section: 145 Surface: AC
 L.C.D. 1/1/2001 Use: TAXIWAY Rank: P Length: 132.00 (Ft) Width: 35.00 (Ft) True Area: 4606.000001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2001	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX Branch: TW A3 TAXIWAY A3 Section: 150 Surface: AAC
 L.C.D. 1/1/2010 Use: TAXIWAY Rank: P Length: 85.00 (Ft) Width: 35.00 (Ft) True Area: 4850.000001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2001	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX Branch: TW A4 TAXIWAY A4 Section: 160 Surface: AAC
 L.C.D. 1/1/2010 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 40.00 (Ft) True Area: 5193.000001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL
1/1/1971	IMPORT ED	BUILT	0.00	3.50	<input checked="" type="checkbox"/>	1971 3.5" P-401 OL

Network: JACKSONVILLE EX Branch: TW A4 TAXIWAY A4 Section: 165 Surface: AAC
 L.C.D. 7/1/2018 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 40.00 (Ft) True Area: 5091.000001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" P-401 6" P-211 4" P-154

Network: JACKSONVILLE EX Branch: TW A5 TAXIWAY A5 Section: 170 Surface: AAC
 L.C.D. 7/1/2018 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 40.00 (Ft) True Area: 5011.000001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2018	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1983	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1983 2" P-401 6" P-211 4" P-154

Network: JACKSONVILLE EX Branch: TW A5 TAXIWAY A5 Section: 175 Surface: AAC
 L.C.D. 1/1/2010 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 40.00 (Ft) True Area: 5069.000001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL
1/1/1971	IMPORT ED	BUILT	0.00	3.50	<input checked="" type="checkbox"/>	1971 3.5" P-401 OL

10/3/2019

Work History Report

Page 8 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: TW A5	TAXIWAY A5		Section: 180	Surface: AAC
L.C.D. 1/1/2010	Use: TAXIWAY	Rank: P	Length: 202.00 (Ft)	Width: 40.00 (Ft)	True Area: 8126.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1971	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW A5	TAXIWAY A5		Section: 185	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 257.00 (Ft)	Width: 50.00 (Ft)	True Area: 13533.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/2005	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1971	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1971 1.5" P-401 OL

Network: JACKSONVILLE EX		Branch: TW B1	TAXIWAY B1		Section: 210	Surface: AC
L.C.D. 12/25/199	Use: TAXIWAY	Rank: P	Length: 163.00 (Ft)	Width: 40.00 (Ft)	True Area: 7110.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1994	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B	TAXIWAY B		Section: 215	Surface: AC
L.C.D. 1/1/2005	Use: TAXIWAY	Rank: P	Length: 2,120.00 (Ft)	Width: 35.00 (Ft)	True Area: 29838.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B2	TAXIWAY B2		Section: 220	Surface: AAC
L.C.D. 1/1/2011	Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 50.00 (Ft)	True Area: 3863.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2003	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B2	TAXIWAY B2		Section: 240	Surface: AC
L.C.D. 1/1/2003	Use: TAXIWAY	Rank: S	Length: 335.00 (Ft)	Width: 35.00 (Ft)	True Area: 11812.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 9 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: TW B2	TAXIWAY B2	Section: 242	Surface: AAC	
L.C.D. 1/1/2010	Use: TAXIWAY	Rank: P	Length: 75.00 (Ft)	Width: 35.00 (Ft)	True Area: 4802.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2003	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B2	TAXIWAY B2	Section: 243	Surface: AAC	
L.C.D. 12/25/199	Use: TAXIWAY	Rank: S	Length: 180.00 (Ft)	Width: 35.00 (Ft)	True Area: 6422.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1994	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
12/24/1994	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B	TAXIWAY B	Section: 225	Surface: AAC	
L.C.D. 1/1/2010	Use: TAXIWAY	Rank: P	Length: 1,555.00 (Ft)	Width: 35.00 (Ft)	True Area: 59500.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B	TAXIWAY B	Section: 227	Surface: AAC	
L.C.D. 1/1/2003	Use: TAXIWAY	Rank: P	Length: 170.00 (Ft)	Width: 35.00 (Ft)	True Area: 5899.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1991	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B	TAXIWAY B	Section: 230	Surface: AAC	
L.C.D. 1/1/2011	Use: TAXIWAY	Rank: P	Length: 135.00 (Ft)	Width: 50.00 (Ft)	True Area: 3679.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2003	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OL ON EXISTING SECTION

Network: JACKSONVILLE EX		Branch: TW B	TAXIWAY B	Section: 235	Surface: AC	
L.C.D. 1/1/2003	Use: TAXIWAY	Rank: T	Length: 700.00 (Ft)	Width: 35.00 (Ft)	True Area: 26915.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OL ON EXISTING SECTION

10/3/2019

Work History Report

Page 10 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: TW B3	TAXIWAY B3	Section: 244	Surface: AAC	
L.C.D. 1/1/2010	Use: TAXIWAY	Rank: P	Length: 55.00 (Ft)	Width: 35.00 (Ft)	True Area: 3380.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B4	TAXIWAY B4	Section: 245	Surface: AAC	
L.C.D. 1/2/1984	Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 40.00 (Ft)	True Area: 9056.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/2/1984	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	EXISTING BIT
1/1/1984	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1984 1.5" P-401 2" P-403 LEVELING

Network: JACKSONVILLE EX		Branch: TW B4	TAXIWAY B4	Section: 250	Surface: AAC	
L.C.D. 1/1/2010	Use: TAXIWAY	Rank: P	Length: 405.00 (Ft)	Width: 35.00 (Ft)	True Area: 15426.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 2" BIT OL
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/2/1971	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1971	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B4	TAXIWAY B4	Section: 265	Surface: AAC	
L.C.D. 1/1/2011	Use: TAXIWAY	Rank: P	Length: 150.00 (Ft)	Width: 50.00 (Ft)	True Area: 3169.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 2" BIT OL
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/2/1971	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1971	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW B5	TAXIWAY B5	Section: 255	Surface: AC	
L.C.D. 1/1/1991	Use: TAXIWAY	Rank: P	Length: 210.00 (Ft)	Width: 40.00 (Ft)	True Area: 4433.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1991 BIT SECTION UNKNOWN

Network: JACKSONVILLE EX		Branch: TW B5	TAXIWAY B5	Section: 260	Surface: AC	
L.C.D. 1/1/2005	Use: TAXIWAY	Rank: P	Length: 2,120.00 (Ft)	Width: 35.00 (Ft)	True Area: 5545.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 11 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: TW C	TAXIWAY C		Section: 305	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 400.00 (Ft)	Width: 60.00 (Ft)	True Area: 24696.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL
1/1/1971	IMPORT ED	OVERLAY	0.00	3.50	<input checked="" type="checkbox"/>	1971 3.5" P-401 OL
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942 1.5" BIT 6" LIMEROCK

Network: JACKSONVILLE EX		Branch: TW C	TAXIWAY C		Section: 310	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 40.00 (Ft)	Width: 136.00 (Ft)	True Area: 5648.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/2005	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL
1/1/1971	IMPORT ED	OVERLAY	0.00	3.50	<input checked="" type="checkbox"/>	1971 3.5" P-401 OL
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942 1.5" BIT 6" LIMEROCK

Network: JACKSONVILLE EX		Branch: TW C	TAXIWAY C		Section: 320	Surface: AAC
L.C.D. 12/25/201	Use: TAXIWAY	Rank: P	Length: 209.00 (Ft)	Width: 80.00 (Ft)	True Area: 16569.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/2010	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL
1/1/1971	IMPORT ED	OVERLAY	0.00	3.50	<input checked="" type="checkbox"/>	1971 3.5" P-401 OL
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942 1.5" BIT 6" LIMEROCK

Network: JACKSONVILLE EX		Branch: TW D	TAXIWAY D		Section: 455	Surface: AC
L.C.D. 1/1/2005	Use: TAXIWAY	Rank: P	Length: 495.00 (Ft)	Width: 35.00 (Ft)	True Area: 12087.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	OL-AS	Overlay - AC Structural	0.00	2.00	<input checked="" type="checkbox"/>	1991 2" P-401 OL
1/1/1970	NC-AC	New Construction - AC	0.00	1.50	<input checked="" type="checkbox"/>	1970 1.5" TYPE 2 BIT 6" LIMEROCK

Network: JACKSONVILLE EX		Branch: TW D	TAXIWAY D		Section: 460	Surface: AC
L.C.D. 1/1/2005	Use: TAXIWAY	Rank: P	Length: 360.00 (Ft)	Width: 35.00 (Ft)	True Area: 29215.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1999	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

10/3/2019

Work History Report

Page 12 of 13

Pavement Database: FDOT

Network: JACKSONVILLE EX		Branch: TW E	TAXIWAY E		Section: 505	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 270.00 (Ft)	Width: 50.00 (Ft)	True Area: 14164.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" P-154

Network: JACKSONVILLE EX		Branch: TW F	TAXIWAY F		Section: 605	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 164.00 (Ft)	Width: 60.00 (Ft)	True Area: 9632.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/1991	IMPORT ED	BUILT	0.00	4.00	<input checked="" type="checkbox"/>	1991 4" P-401 6" P-211 6" P-154

Network: JACKSONVILLE EX		Branch: TW F	TAXIWAY F		Section: 610	Surface: AAC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 125.00 (Ft)	Width: 44.00 (Ft)	True Area: 5562.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	ML-OV	MILL and OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	Variable asphalt mill (depth post-mill)
1/1/1991	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1971	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW G	TAXIWAY G		Section: 765	Surface: AC
L.C.D. 1/1/2003	Use: TAXIWAY	Rank: P	Length: 1,885.00 (Ft)	Width: 35.00 (Ft)	True Area: 65079.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1991	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1970	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: JACKSONVILLE EX		Branch: TW G	TAXIWAY G		Section: 770	Surface: AC
L.C.D. 1/1/2004	Use: TAXIWAY	Rank: P	Length: 250.00 (Ft)	Width: 35.00 (Ft)	True Area: 9691.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2004	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	2004 4" P-401 RECON
1/1/1970	NC-AC	New Construction - AC	0.00	1.50	<input checked="" type="checkbox"/>	1970 1.5" TYPE 2 BIT, 6" LIMEROC

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	31	1,820,884.00	2.47	1.83
Complete Reconstruction - AC	9	338,657.00	0.44	1.26
Complete Reconstruction - PCC	1	2,417.00	0.00	0.00
MILL and OVERLAY	37	1,609,411.00	0.00	0.00
New Construction - AC	24	573,911.00	0.12	0.41
New Construction - Initial	15	252,290.00	0.00	0.00
OVERLAY	22	1,806,221.00	2.11	0.58
Overlay - AC Structural	17	905,585.00	0.12	0.47
Surface Treatment - Seal Coat	4	651,993.00	0.00	0.00

10/3/2019

Branch Condition Report

Page 1 of 2

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP FAA	2	525.00	210.00	153,850.00	APRON	79.00	1.00	79.92
AP N	4	2,630.00	117.75	339,823.00	APRON	82.50	30.31	94.37
AP NW	3	3,140.00	135.67	302,241.00	APRON	87.67	17.44	94.98
AP RU RW	1	809.00	75.00	22,135.00	APRON	77.00	0.00	77.00
AP RU RW1	1	73.00	200.00	24,645.00	APRON	71.00	0.00	71.00
AP RU RW2	2	230.00	78.00	18,147.00	APRON	86.50	13.50	82.10
AP S	2	680.00	205.00	201,078.00	APRON	100.00	0.00	100.00
AP SW	8	1,847.00	56.50	98,600.00	APRON	61.13	27.50	65.22
RW 14-32	2	3,933.00	100.00	400,800.00	RUNWAY	100.00	0.00	100.00
RW 5-23	2	3,896.00	100.00	389,600.00	RUNWAY	84.00	16.00	70.12
TL A3	2	1,350.00	57.50	88,203.00	TAXILANE	89.50	10.50	95.43
TW A	3	4,540.00	40.00	118,791.00	TAXIWAY	76.33	17.82	64.09
TW A1	1	425.00	30.00	22,201.00	TAXIWAY	84.00	0.00	84.00
TW A2	2	205.00	35.00	9,177.00	TAXIWAY	63.00	6.00	61.09
TW A3	3	464.00	40.00	22,579.00	TAXIWAY	84.33	11.67	90.21
TW A4	2	200.00	40.00	10,284.00	TAXIWAY	83.00	17.00	82.83
TW A5	4	659.00	42.50	31,739.00	TAXIWAY	79.75	20.50	83.60
TW B	5	4,680.00	38.00	125,831.00	TAXIWAY	70.20	8.93	64.46
TW B1	1	163.00	40.00	7,110.00	TAXIWAY	59.00	0.00	59.00
TW B2	4	765.00	38.75	26,899.00	TAXIWAY	68.50	16.13	66.60
TW B3	1	55.00	35.00	3,380.00	TAXIWAY	70.00	0.00	70.00
TW B4	3	730.00	41.67	27,651.00	TAXIWAY	59.33	20.73	56.70
TW B5	2	2,330.00	37.50	9,978.00	TAXIWAY	65.50	14.50	67.12
TW C	3	649.00	92.00	46,913.00	TAXIWAY	85.67	20.27	84.81
TW D	2	855.00	35.00	41,302.00	TAXIWAY	79.00	1.00	78.59
TW E	1	270.00	50.00	14,164.00	TAXIWAY	100.00	0.00	100.00
TW F	2	289.00	52.00	15,194.00	TAXIWAY	100.00	0.00	100.00
TW G	2	2,135.00	35.00	74,770.00	TAXIWAY	74.00	1.00	73.26

10/3/2019**Branch Condition Report****Page 2 of 2***Pavement Database: FDOT*

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	23	1,160,519.00	76.57	25.33	90.09
RUNWAY	4	790,400.00	92.00	13.86	85.27
TAXILANE	2	88,203.00	89.50	10.50	95.43
TAXIWAY	41	607,963.00	75.68	17.56	72.40
ALL	70	2,647,085.00	77.30	20.59	84.77

Pavement Database: FDOT

NetworkId: CRG

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP FAA	4505	1/1/2004	AC	APRON	T	0	147,450.00	5/1/2019	15	80
AP FAA	4510	1/1/2004	PCC	APRON	P	0	6,400.00	5/1/2019	15	78
AP N	4205	7/1/2018	AAC	APRON	P	0	24,445.00	7/1/2018	0	100
AP N	4210	7/1/2018	AAC	APRON	P	0	265,650.00	7/1/2018	0	100
AP N	4215	7/1/2018	AC	APRON	S	0	22,406.00	7/1/2018	0	100
AP N	4220	12/25/1994	AC	APRON	S	0	27,322.00	5/1/2019	25	30
AP NW	4305	1/1/1991	AC	APRON	P	0	41,023.00	5/1/2019	28	63
AP NW	4310	7/1/2018	AAC	APRON	P	0	204,437.00	7/1/2018	0	100
AP NW	4320	7/1/2018	AAC	APRON	P	0	56,781.00	7/1/2018	0	100
AP RU RW 5	5205	1/1/2003	AC	APRON	T	0	22,135.00	5/1/2019	16	77
AP RU RW14	5310	1/1/2010	AAC	APRON	P	0	24,645.00	5/1/2019	9	71
AP RU RW23	5105	1/1/2005	AC	APRON	P	0	12,030.00	5/1/2019	14	73
AP RU RW23	5110	1/1/2019	AAC	APRON	P	0	6,117.00	1/1/2019	0	100
AP S	4105	7/1/2018	AAC	APRON	P	0	185,265.00	7/1/2018	0	100
AP S	4115	7/1/2018	AAC	APRON	P	0	15,813.00	7/1/2018	0	100
AP SW	4405	12/25/1999	PCC	APRON	S	0	8,887.00	5/1/2019	20	12
AP SW	4406	1/1/2014	PCC	APRON	S	0	2,417.00	5/1/2019	5	86
AP SW	4407	12/25/1999	AC	APRON	P	0	14,286.00	5/1/2019	20	56
AP SW	4410	1/1/2019	AAC	APRON	S	0	12,829.00	1/1/2019	0	100
AP SW	4415	1/1/2002	AC	APRON	S	0	23,211.00	5/1/2019	17	68
AP SW	4420	12/25/1994	AC	APRON	S	0	12,167.00	5/1/2019	25	67
AP SW	4430	1/1/2006	AC	APRON	S	0	4,074.00	5/1/2019	13	26
AP SW	4435	1/1/2007	AAC	APRON	S	0	20,729.00	5/1/2019	12	74
RW 14-32	6205	1/1/2019	AAC	RUNWAY	P	0	45,000.00	1/1/2019	0	100
RW 14-32	6210	1/1/2019	AAC	RUNWAY	P	0	355,800.00	1/1/2019	0	100
RW 5-23	6105	1/1/2011	AAC	RUNWAY	S	0	363,800.00	5/1/2019	8	68
RW 5-23	6110	1/1/2019	AAC	RUNWAY	P	0	25,800.00	1/1/2019	0	100
TL A3	153	1/1/2019	AC	TAXILANE	P	0	69,029.00	1/1/2019	0	100
TL A3	155	1/1/2007	AC	TAXILANE	P	0	19,174.00	5/1/2019	12	79
TW A	105	1/1/2010	AAC	TAXIWAY	P	0	74,656.00	5/1/2019	9	57
TW A	110	1/1/2019	AAC	TAXIWAY	P	0	6,423.00	1/1/2019	0	100
TW A	120	1/1/2005	AC	TAXIWAY	P	0	37,712.00	5/1/2019	14	72
TW A1	130	1/1/2005	AC	TAXIWAY	S	0	22,201.00	5/1/2019	14	84
TW A2	132	1/1/2010	AAC	TAXIWAY	P	0	3,131.00	5/1/2019	9	69
TW A2	135	1/1/1991	AC	TAXIWAY	P	0	6,046.00	5/1/2019	28	57
TW A3	142	1/1/2019	AAC	TAXIWAY	P	0	13,123.00	1/1/2019	0	100
TW A3	145	1/1/2001	AC	TAXIWAY	P	0	4,606.00	5/1/2019	18	72
TW A3	150	1/1/2010	AAC	TAXIWAY	P	0	4,850.00	5/1/2019	9	81
TW A4	160	1/1/2010	AAC	TAXIWAY	P	0	5,193.00	5/1/2019	9	66
TW A4	165	7/1/2018	AAC	TAXIWAY	P	0	5,091.00	7/1/2018	0	100
TW A5	170	7/1/2018	AAC	TAXIWAY	P	0	5,011.00	7/1/2018	0	100
TW A5	175	1/1/2010	AAC	TAXIWAY	P	0	5,069.00	5/1/2019	9	55
TW A5	180	1/1/2010	AAC	TAXIWAY	P	0	8,126.00	5/1/2019	9	64
TW A5	185	1/1/2019	AAC	TAXIWAY	P	0	13,533.00	1/1/2019	0	100
TW B	215	1/1/2005	AC	TAXIWAY	P	0	29,838.00	5/1/2019	14	77
TW B	225	1/1/2010	AAC	TAXIWAY	P	0	59,500.00	5/1/2019	9	55
TW B	227	1/1/2003	AAC	TAXIWAY	P	0	5,899.00	5/1/2019	16	70
TW B	230	1/1/2011	AAC	TAXIWAY	P	0	3,679.00	5/1/2019	8	81

TW B	235	1/1/2003	AC	TAXIWAY	T	0	26,915.00	5/1/2019	16	68
TW B1	210	12/25/1994	AC	TAXIWAY	P	0	7,110.00	5/1/2019	25	59
TW B2	220	1/1/2011	AAC	TAXIWAY	P	0	3,863.00	5/1/2019	8	81
TW B2	240	1/1/2003	AC	TAXIWAY	S	0	11,812.00	5/1/2019	16	69
TW B2	242	1/1/2010	AAC	TAXIWAY	P	0	4,802.00	5/1/2019	9	82
TW B2	243	12/25/1994	AAC	TAXIWAY	S	0	6,422.00	5/1/2019	25	42
TW B3	244	1/1/2010	AAC	TAXIWAY	P	0	3,380.00	5/1/2019	9	70
TW B4	245	1/2/1984	AAC	TAXIWAY	P	0	9,056.00	5/1/2019	35	31
TW B4	250	1/1/2010	AAC	TAXIWAY	P	0	15,426.00	5/1/2019	9	67
TW B4	265	1/1/2011	AAC	TAXIWAY	P	0	3,169.00	5/1/2019	8	80
TW B5	255	1/1/1991	AC	TAXIWAY	P	0	4,433.00	5/1/2019	28	51
TW B5	260	1/1/2005	AC	TAXIWAY	P	0	5,545.00	5/1/2019	14	80
TW C	305	1/1/2019	AAC	TAXIWAY	P	0	24,696.00	1/1/2019	0	100
TW C	310	1/1/2019	AAC	TAXIWAY	P	0	5,648.00	1/1/2019	0	100
TW C	320	12/25/2010	AAC	TAXIWAY	P	0	16,569.00	5/1/2019	9	57
TW D	455	1/1/2005	AC	TAXIWAY	P	0	12,087.00	5/1/2019	14	80
TW D	460	1/1/2005	AC	TAXIWAY	P	0	29,215.00	5/1/2019	14	78
TW E	505	1/1/2019	AAC	TAXIWAY	P	0	14,164.00	1/1/2019	0	100
TW F	605	1/1/2019	AAC	TAXIWAY	P	0	9,632.00	1/1/2019	0	100
TW F	610	1/1/2019	AAC	TAXIWAY	P	0	5,562.00	1/1/2019	0	100
TW G	765	1/1/2003	AC	TAXIWAY	P	0	65,079.00	5/1/2019	16	73
TW G	770	1/1/2004	AC	TAXIWAY	P	0	9,691.00	5/1/2019	15	75

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		1,392,255.00	23	100.00	0.00	100.00
03-05	5	2,417.00	1	86.00	0.00	86.00
06-10	9	599,858.00	16	69.00	9.51	65.41
11-15	14	356,146.00	13	73.54	14.09	77.56
16-20	17	182,830.00	9	62.78	18.74	67.44
21-25	25	53,021.00	4	49.50	14.43	43.83
26-30	28	51,502.00	3	57.00	4.90	61.26
31-35	35	9,056.00	1	31.00	0.00	31.00
ALL	10	2,647,085.00	70	77.30	20.59	84.77

Appendix B

Airfield Pavement Localized Maintenance and Repair and
Major Rehabilitation



Table B-1 Localized Maintenance and Repair Needs based on Current Condition

Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
CRG	AP FAA	4505	45	DEPRESSION	Low	2348.36	SqFt	1.6%	FDOT - PATCHING - AC FULL DEPTH	2547.8	SqFt	\$ 9.00	\$ 22,930.00
CRG	AP FAA	4505	52	RAVELING	Low	6498.6	SqFt	4.4%	FDOT - SURFACE SEAL	6498.2	SqFt	\$ 0.55	\$ 3,580.00
CRG	AP FAA	4510	65	JT SEAL DMG	Medium	64	Slabs	100.0%	FDOT - JOINT SEAL - PCC	1075.1	Ft	\$ 2.75	\$ 2,960.00
CRG	AP FAA	4510	74	JOINT SPALL	Low	2.67	Slabs	4.2%	FDOT - CRACK SEALING - PCC	4.3	Ft	\$ 4.25	\$ 20.00
CRG	AP FAA	4510	75	CORNER SPALL	Low	5.33	Slabs	8.3%	FDOT - CRACK SEALING - PCC	8.9	Ft	\$ 4.25	\$ 40.00
CRG	AP N	4220	41	ALLIGATOR CR	Low	1356.58	SqFt	5.0%	FDOT - PATCHING - AC FULL DEPTH	1509.1	SqFt	\$ 9.00	\$ 13,580.00
CRG	AP N	4220	41	ALLIGATOR CR	High	103.33	SqFt	0.4%	FDOT - PATCHING - AC FULL DEPTH	148.5	SqFt	\$ 9.00	\$ 1,340.00
CRG	AP N	4220	45	DEPRESSION	Low	460.8	SqFt	1.7%	FDOT - PATCHING - AC FULL DEPTH	551.1	SqFt	\$ 9.00	\$ 4,970.00
CRG	AP N	4220	50	PATCHING	Medium	198.16	SqFt	0.7%	FDOT - PATCHING - AC FULL DEPTH	258.3	SqFt	\$ 9.00	\$ 2,330.00
CRG	AP N	4220	52	RAVELING	Low	23807.72	SqFt	87.1%	FDOT - SURFACE SEAL	23807.6	SqFt	\$ 0.55	\$ 13,100.00
CRG	AP N	4220	52	RAVELING	Medium	3230.03	SqFt	11.8%	FDOT - PATCHING - AC PARTIAL DEPTH	3230.3	SqFt	\$ 4.00	\$ 12,930.00
CRG	AP NW	4305	52	RAVELING	Low	6153.73	SqFt	15.0%	FDOT - SURFACE SEAL	6153.7	SqFt	\$ 0.55	\$ 3,390.00
CRG	AP RU RW 5	5205	52	RAVELING	Low	6975.88	SqFt	31.5%	FDOT - SURFACE SEAL	6976.1	SqFt	\$ 0.55	\$ 3,840.00
CRG	AP RU RW 5	5205	57	WEATHERING	Medium	15159.14	SqFt	68.5%	FDOT - SURFACE SEAL	15158.8	SqFt	\$ 0.55	\$ 8,340.00
CRG	AP RU RW14	5310	52	RAVELING	Low	110.87	SqFt	0.5%	FDOT - SURFACE SEAL	110.9	SqFt	\$ 0.55	\$ 70.00
CRG	AP RU RW23	5105	52	RAVELING	Low	4531.61	SqFt	37.7%	FDOT - SURFACE SEAL	4531.6	SqFt	\$ 0.55	\$ 2,500.00
CRG	AP SW	4405	62	CORNER BREAK	Low	0.2	Slabs	10.0%	FDOT - CRACK SEALING - PCC	1.6	Ft	\$ 4.25	\$ 10.00
CRG	AP SW	4405	62	CORNER BREAK	Medium	0.2	Slabs	10.0%	FDOT - PATCHING - PCC FULL DEPTH	6.5	SqFt	\$ 150.00	\$ 970.00
CRG	AP SW	4405	63	LINEAR CR	Medium	0.4	Slabs	20.0%	FDOT - CRACK SEALING - PCC	7.9	Ft	\$ 4.25	\$ 40.00
CRG	AP SW	4405	65	JT SEAL DMG	High	2	Slabs	100.0%	FDOT - JOINT SEAL - PCC	750	Ft	\$ 2.75	\$ 2,070.00
CRG	AP SW	4405	72	SHAT. SLAB	Low	0.4	Slabs	20.0%	FDOT - CRACK SEALING - PCC	16.1	Ft	\$ 4.25	\$ 70.00
CRG	AP SW	4405	72	SHAT. SLAB	Medium	0.8	Slabs	40.0%	FDOT - SLAB REPLACEMENT - PCC	300.3	SqFt	\$ 30.00	\$ 9,000.00
CRG	AP SW	4405	75	CORNER SPALL	Low	0.2	Slabs	10.0%	FDOT - CRACK SEALING - PCC	0.3	Ft	\$ 4.25	\$ 10.00
CRG	AP SW	4407	48	L & T CR	Medium	610.24	Ft	4.3%	FDOT - CRACK SEALING - AC	610.2	Ft	\$ 3.00	\$ 1,840.00
CRG	AP SW	4407	52	RAVELING	Low	1466.48	SqFt	10.3%	FDOT - SURFACE SEAL	1466	SqFt	\$ 0.55	\$ 810.00
CRG	AP SW	4415	45	DEPRESSION	Low	224.1	SqFt	1.0%	FDOT - PATCHING - AC FULL DEPTH	288.5	SqFt	\$ 9.00	\$ 2,600.00
CRG	AP SW	4415	52	RAVELING	Low	3481.69	SqFt	15.0%	FDOT - SURFACE SEAL	3482.1	SqFt	\$ 0.55	\$ 1,920.00
CRG	AP SW	4420	50	PATCHING	Medium	487.61	SqFt	4.0%	FDOT - PATCHING - AC FULL DEPTH	580.2	SqFt	\$ 9.00	\$ 5,230.00
CRG	AP SW	4420	52	RAVELING	Low	4668.42	SqFt	38.4%	FDOT - SURFACE SEAL	4668.3	SqFt	\$ 0.55	\$ 2,570.00
CRG	AP SW	4430	45	DEPRESSION	Low	82.88	SqFt	2.0%	FDOT - PATCHING - AC FULL DEPTH	123.8	SqFt	\$ 9.00	\$ 1,120.00
CRG	AP SW	4430	45	DEPRESSION	Medium	1077.04	SqFt	26.4%	FDOT - PATCHING - AC FULL DEPTH	1213.1	SqFt	\$ 9.00	\$ 10,920.00
CRG	AP SW	4430	52	RAVELING	Low	1629.98	SqFt	40.0%	FDOT - SURFACE SEAL	1629.7	SqFt	\$ 0.55	\$ 900.00
CRG	AP SW	4430	57	WEATHERING	Medium	2443.95	SqFt	60.0%	FDOT - SURFACE SEAL	2444.5	SqFt	\$ 0.55	\$ 1,350.00
CRG	AP SW	4435	45	DEPRESSION	Low	142.19	SqFt	0.7%	FDOT - PATCHING - AC FULL DEPTH	193.8	SqFt	\$ 9.00	\$ 1,750.00
CRG	RW 5-23	6105	48	L & T CR	Medium	2435.04	Ft	0.7%	FDOT - CRACK SEALING - AC	2435	Ft	\$ 3.00	\$ 7,310.00
CRG	RW 5-23	6105	52	RAVELING	Low	19819.8	SqFt	5.5%	FDOT - SURFACE SEAL	19819.6	SqFt	\$ 0.55	\$ 10,910.00
CRG	RW 5-23	6105	57	WEATHERING	Medium	5820.8	SqFt	1.6%	FDOT - SURFACE SEAL	5821.1	SqFt	\$ 0.55	\$ 3,210.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
CRG	TL A3	155	52	RAVELING	Low	1862.59	SqFt	9.7%	FDOT - SURFACE SEAL	1862.2	SqFt	\$ 0.55	\$ 1,030.00
CRG	TW A	105	48	L & T CR	Medium	1381.27	Ft	1.9%	FDOT - CRACK SEALING - AC	1381.2	Ft	\$ 3.00	\$ 4,150.00
CRG	TW A	105	52	RAVELING	Low	4795	SqFt	6.4%	FDOT - SURFACE SEAL	4795.3	SqFt	\$ 0.55	\$ 2,640.00
CRG	TW A	120	52	RAVELING	Low	13289.02	SqFt	35.2%	FDOT - SURFACE SEAL	13289.1	SqFt	\$ 0.55	\$ 7,310.00
CRG	TW A	120	57	WEATHERING	Medium	24422.99	SqFt	64.8%	FDOT - SURFACE SEAL	24423.3	SqFt	\$ 0.55	\$ 13,440.00
CRG	TW A1	130	52	RAVELING	Low	1268.63	SqFt	5.7%	FDOT - SURFACE SEAL	1269.1	SqFt	\$ 0.55	\$ 700.00
CRG	TW A2	132	52	RAVELING	Low	82.99	SqFt	2.7%	FDOT - SURFACE SEAL	82.9	SqFt	\$ 0.55	\$ 50.00
CRG	TW A2	135	48	L & T CR	Medium	164.99	Ft	2.7%	FDOT - CRACK SEALING - AC	165	Ft	\$ 3.00	\$ 500.00
CRG	TW A2	135	52	RAVELING	Low	1209	SqFt	20.0%	FDOT - SURFACE SEAL	1208.8	SqFt	\$ 0.55	\$ 670.00
CRG	TW A2	135	57	WEATHERING	Medium	4836.98	SqFt	80.0%	FDOT - SURFACE SEAL	4837.3	SqFt	\$ 0.55	\$ 2,670.00
CRG	TW A3	145	52	RAVELING	Low	461.02	SqFt	10.0%	FDOT - SURFACE SEAL	460.7	SqFt	\$ 0.55	\$ 260.00
CRG	TW A3	145	57	WEATHERING	Medium	4144.97	SqFt	90.0%	FDOT - SURFACE SEAL	4145.2	SqFt	\$ 0.55	\$ 2,280.00
CRG	TW A3	150	52	RAVELING	Low	243.05	SqFt	5.0%	FDOT - SURFACE SEAL	243.3	SqFt	\$ 0.55	\$ 140.00
CRG	TW A4	160	48	L & T CR	Medium	72.01	Ft	1.4%	FDOT - CRACK SEALING - AC	71.9	Ft	\$ 3.00	\$ 220.00
CRG	TW A4	160	52	RAVELING	Low	275.02	SqFt	5.3%	FDOT - SURFACE SEAL	274.5	SqFt	\$ 0.55	\$ 160.00
CRG	TW A5	175	45	DEPRESSION	Low	40.04	SqFt	0.8%	FDOT - PATCHING - AC FULL DEPTH	70	SqFt	\$ 9.00	\$ 630.00
CRG	TW A5	175	48	L & T CR	Medium	73	Ft	1.4%	FDOT - CRACK SEALING - AC	73.2	Ft	\$ 3.00	\$ 220.00
CRG	TW A5	175	52	RAVELING	Low	251.98	SqFt	5.0%	FDOT - SURFACE SEAL	251.9	SqFt	\$ 0.55	\$ 140.00
CRG	TW A5	180	45	DEPRESSION	Low	74.27	SqFt	0.9%	FDOT - PATCHING - AC FULL DEPTH	113	SqFt	\$ 9.00	\$ 1,020.00
CRG	TW A5	180	52	RAVELING	Low	162.54	SqFt	2.0%	FDOT - SURFACE SEAL	162.5	SqFt	\$ 0.55	\$ 90.00
CRG	TW B	215	52	RAVELING	Low	9377.63	SqFt	31.4%	FDOT - SURFACE SEAL	9377.5	SqFt	\$ 0.55	\$ 5,160.00
CRG	TW B	215	57	WEATHERING	Medium	20460.36	SqFt	68.6%	FDOT - SURFACE SEAL	20460	SqFt	\$ 0.55	\$ 11,260.00
CRG	TW B	225	48	L & T CR	Medium	210.79	Ft	0.4%	FDOT - CRACK SEALING - AC	211	Ft	\$ 3.00	\$ 640.00
CRG	TW B	225	52	RAVELING	Low	2968.15	SqFt	5.0%	FDOT - SURFACE SEAL	2968.7	SqFt	\$ 0.55	\$ 1,640.00
CRG	TW B	227	52	RAVELING	Low	295.04	SqFt	5.0%	FDOT - SURFACE SEAL	294.9	SqFt	\$ 0.55	\$ 170.00
CRG	TW B	227	57	WEATHERING	Medium	5604.01	SqFt	95.0%	FDOT - SURFACE SEAL	5603.7	SqFt	\$ 0.55	\$ 3,090.00
CRG	TW B	230	52	RAVELING	Low	110.01	SqFt	3.0%	FDOT - SURFACE SEAL	109.8	SqFt	\$ 0.55	\$ 70.00
CRG	TW B	230	57	WEATHERING	Medium	183.96	SqFt	5.0%	FDOT - SURFACE SEAL	184.1	SqFt	\$ 0.55	\$ 110.00
CRG	TW B	235	45	DEPRESSION	Low	535.18	SqFt	2.0%	FDOT - PATCHING - AC FULL DEPTH	631.8	SqFt	\$ 9.00	\$ 5,700.00
CRG	TW B	235	52	RAVELING	Low	9098.95	SqFt	33.8%	FDOT - SURFACE SEAL	9098.7	SqFt	\$ 0.55	\$ 5,010.00
CRG	TW B	235	57	WEATHERING	Medium	17816.1	SqFt	66.2%	FDOT - SURFACE SEAL	17816.4	SqFt	\$ 0.55	\$ 9,800.00
CRG	TW B1	210	48	L & T CR	Medium	152.85	Ft	2.2%	FDOT - CRACK SEALING - AC	152.9	Ft	\$ 3.00	\$ 460.00
CRG	TW B1	210	52	RAVELING	Low	1777.55	SqFt	25.0%	FDOT - SURFACE SEAL	1777.1	SqFt	\$ 0.55	\$ 980.00
CRG	TW B2	220	57	WEATHERING	Medium	772.96	SqFt	20.0%	FDOT - SURFACE SEAL	772.9	SqFt	\$ 0.55	\$ 430.00
CRG	TW B2	240	52	RAVELING	Low	6394.52	SqFt	54.1%	FDOT - SURFACE SEAL	6394.8	SqFt	\$ 0.55	\$ 3,520.00
CRG	TW B2	240	57	WEATHERING	Medium	4582.73	SqFt	38.8%	FDOT - SURFACE SEAL	4582.2	SqFt	\$ 0.55	\$ 2,530.00
CRG	TW B2	242	57	WEATHERING	Medium	335.94	SqFt	7.0%	FDOT - SURFACE SEAL	335.8	SqFt	\$ 0.55	\$ 190.00
CRG	TW B2	243	52	RAVELING	Low	3493	SqFt	54.4%	FDOT - SURFACE SEAL	3492.9	SqFt	\$ 0.55	\$ 1,930.00
CRG	TW B2	243	57	WEATHERING	Medium	1164.01	SqFt	18.1%	FDOT - SURFACE SEAL	1163.6	SqFt	\$ 0.55	\$ 650.00



Network ID	Branch ID	Section ID	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
CRG	TW B3	244	52	RAVELING	Low	168.78	SqFt	5.0%	FDOT - SURFACE SEAL	169	SqFt	\$ 0.55	\$ 100.00
CRG	TW B4	245	41	ALLIGATOR CR	Low	103.98	SqFt	1.2%	FDOT - PATCHING - AC FULL DEPTH	148.5	SqFt	\$ 9.00	\$ 1,350.00
CRG	TW B4	245	43	BLOCK CR	Medium	3999.12	SqFt	44.2%	FDOT - CRACK SEALING - AC	1218.8	Ft	\$ 3.00	\$ 3,660.00
CRG	TW B4	245	48	L & T CR	Medium	35.99	Ft	0.4%	FDOT - CRACK SEALING - AC	36.1	Ft	\$ 3.00	\$ 110.00
CRG	TW B4	245	52	RAVELING	Low	3663.17	SqFt	40.5%	FDOT - SURFACE SEAL	3663	SqFt	\$ 0.55	\$ 2,020.00
CRG	TW B4	245	57	WEATHERING	Medium	5392.83	SqFt	59.6%	FDOT - SURFACE SEAL	5392.7	SqFt	\$ 0.55	\$ 2,970.00
CRG	TW B4	250	57	WEATHERING	Medium	771.34	SqFt	5.0%	FDOT - SURFACE SEAL	771.8	SqFt	\$ 0.55	\$ 430.00
CRG	TW B4	265	57	WEATHERING	Medium	158.01	SqFt	5.0%	FDOT - SURFACE SEAL	158.2	SqFt	\$ 0.55	\$ 90.00
CRG	TW B5	255	48	L & T CR	Medium	41.99	Ft	1.0%	FDOT - CRACK SEALING - AC	42	Ft	\$ 3.00	\$ 130.00
CRG	TW B5	255	52	RAVELING	Low	1108.04	SqFt	25.0%	FDOT - SURFACE SEAL	1107.6	SqFt	\$ 0.55	\$ 610.00
CRG	TW B5	260	45	DEPRESSION	Low	3.98	SqFt	0.1%	FDOT - PATCHING - AC FULL DEPTH	16.2	SqFt	\$ 9.00	\$ 150.00
CRG	TW B5	260	52	RAVELING	Low	299.99	SqFt	5.4%	FDOT - SURFACE SEAL	300.3	SqFt	\$ 0.55	\$ 170.00
CRG	TW C	320	48	L & T CR	Medium	83.69	Ft	0.5%	FDOT - CRACK SEALING - AC	83.7	Ft	\$ 3.00	\$ 260.00
CRG	TW C	320	52	RAVELING	Low	1882.82	SqFt	11.4%	FDOT - SURFACE SEAL	1882.6	SqFt	\$ 0.55	\$ 1,040.00
CRG	TW D	455	52	RAVELING	Low	121.09	SqFt	1.0%	FDOT - SURFACE SEAL	121.6	SqFt	\$ 0.55	\$ 70.00
CRG	TW D	460	52	RAVELING	Low	897.28	SqFt	3.1%	FDOT - SURFACE SEAL	897.7	SqFt	\$ 0.55	\$ 500.00
CRG	TW G	765	48	L & T CR	Medium	247.93	Ft	0.4%	FDOT - CRACK SEALING - AC	248	Ft	\$ 3.00	\$ 750.00
CRG	TW G	765	52	RAVELING	Low	16734.65	SqFt	25.7%	FDOT - SURFACE SEAL	16734.7	SqFt	\$ 0.55	\$ 9,210.00
CRG	TW G	770	52	RAVELING	Low	2348.04	SqFt	24.2%	FDOT - SURFACE SEAL	2347.6	SqFt	\$ 0.55	\$ 1,300.00



Table B-2 10-Year Major Rehabilitation Planning Needs at Section Level

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2020	CRG	AP N	4220	AC	27,322	29	AC Reconstruction	\$ 342,000.00
2020	CRG	AP NW	4305	AC	41,023	62	AC Restoration	\$ 390,000.00
2020	CRG	AP SW	4405	PCC	8,887	11	PCC Reconstruction	\$ 178,000.00
2020	CRG	AP SW	4407	AC	14,286	55	AC Restoration	\$ 136,000.00
2020	CRG	AP SW	4430	AC	4,074	25	AC Reconstruction	\$ 51,000.00
2020	CRG	TW A	105	AAC	74,656	56	AC Restoration	\$ 710,000.00
2020	CRG	TW A2	135	AC	6,046	56	AC Restoration	\$ 58,000.00
2020	CRG	TW A5	175	AAC	5,069	54	AC Restoration	\$ 49,000.00
2020	CRG	TW A5	180	AAC	8,126	63	AC Restoration	\$ 78,000.00
2020	CRG	TW B	225	AAC	59,500	54	AC Restoration	\$ 566,000.00
2020	CRG	TW B1	210	AC	7,110	58	AC Restoration	\$ 68,000.00
2020	CRG	TW B2	243	AAC	6,422	41	AC Restoration	\$ 79,000.00
2020	CRG	TW B4	245	AAC	9,056	29	AC Reconstruction	\$ 114,000.00
2020	CRG	TW B5	255	AC	4,433	50	AC Restoration	\$ 43,000.00
2020	CRG	TW C	320	AAC	16,569	56	AC Restoration	\$ 158,000.00
2021	CRG	AP SW	4420	AC	12,167	64	AC Restoration	\$ 116,000.00
2021	CRG	TW A4	160	AAC	5,193	64	AC Restoration	\$ 50,000.00
2022	CRG	AP SW	4415	AC	23,211	64	AC Restoration	\$ 221,000.00
2022	CRG	TW B	235	AC	26,915	64	AC Restoration	\$ 256,000.00
2022	CRG	TW B4	250	AAC	15,426	64	AC Restoration	\$ 147,000.00
2023	CRG	AP RU RW14	5310	AAC	24,645	63	AC Restoration	\$ 235,000.00
2023	CRG	RW 5-23	6105	AAC	363,800	64	AC Restoration	\$ 3,457,000.00
2023	CRG	TW B2	240	AC	11,812	64	AC Restoration	\$ 113,000.00
2024	CRG	AP SW	4435	AAC	20,729	63	AC Restoration	\$ 197,000.00
2024	CRG	TW A2	132	AAC	3,131	64	AC Restoration	\$ 30,000.00
2025	CRG	AP RU RW23	5105	AC	12,030	64	AC Restoration	\$ 115,000.00





Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost
2025	CRG	TW A	120	AC	37,712	64	AC Restoration	\$ 359,000.00
2025	CRG	TW A3	145	AC	4,606	64	AC Restoration	\$ 44,000.00
2025	CRG	TW B	227	AAC	5,899	64	AC Restoration	\$ 57,000.00
2025	CRG	TW B3	244	AAC	3,380	64	AC Restoration	\$ 33,000.00
2026	CRG	TW G	765	AC	65,079	64	AC Restoration	\$ 619,000.00
2027	CRG	AP RU RW 5	5205	AC	22,135	64	AC Restoration	\$ 211,000.00
2028	CRG	TW G	770	AC	9,691	63	AC Restoration	\$ 93,000.00
2029	CRG	AP FAA	4505	AC	147,450	64	AC Restoration	\$ 1,401,000.00
2029	CRG	TW B	215	AC	29,838	64	AC Restoration	\$ 284,000.00

Appendix C

Technical Exhibits





105 AAC 100' X 35' 4 20	110 AAC VAR. 0 1	120 AAC 100' X 35' 3 10	130 AAC VAR. 1 5	132 AAC VAR. 1 1	135 AAC VAR. 1 1	142 AAC VAR. 0 3	145 AAC VAR. 1 1
150 AAC VAR. 1 1	153 AAC VAR. 0 12	155 AAC 100' X 35' 1 8	160 AAC VAR. 0 1	165 AAC VAR. 0 1	170 AAC VAR. 0 1	175 AAC VAR. 1 1	180 AAC VAR. 1 2
185 AAC VAR. 0 3	210 AAC VAR. 1 2	215 AAC 100' X 35' 1 8	220 AAC VAR. 1 1	225 AAC 100' X 35' 4 18	227 AAC 188' X 35' 1 1	230 AAC VAR. 1 1	235 AAC 100' X 35' 2 7
240 AAC 100' X 35' 1 3	242 AAC VAR. 1 1	243 AAC VAR. 1 1	244 AAC VAR. 1 1	245 AAC 100' X 35' 1 2	250 AAC VAR. 1 4	255 AAC VAR. 1 1	260 AAC VAR. 1 1
265 AAC VAR. 1 1	305 AAC VAR. 0 8	310 AAC VAR. 0 1	320 AAC VAR. 1 4	455 AAC VAR. 1 3	460 AAC 100' X 35' 2 8	505 AAC VAR. 0 3	605 AAC VAR. 0 2
610 AAC VAR. 0 1	765 AAC 100' X 35' 3 18	770 AAC VAR. 1 2	4105 AAC 100' X 50' 0 3	4115 AAC VAR. 0 4	4205 AAC VAR. 0 3	4210 AAC 100' X 50' 0 54	4215 AAC VAR. 0 5
4220 AAC VAR. 2 7	4305 AAC VAR. 1 8	4310 AAC 100' X 50' 0 42	4320 AAC VAR. 0 12	4405 AAC VAR. 1 2	4406 AAC 15' X 35' X 12.5' 1 1	4407 AAC VAR. 1 4	4410 AAC VAR. 0 3
4415 AAC VAR. 1 3	4420 AAC 100' X 50' 1 3	4430 AAC VAR. 1 2	4435 AAC 100' X 35' 1 6	4505 AAC VAR. 8 30	4510 AAC VAR. 1 3	5105 AAC 80' X 50' 1 3	5110 AAC VAR. 0 1
5205 AAC 83.2' X 50' 1 5	5310 AAC VAR. 2 8	6105 AAC 100' X 50' 15 73	6110 AAC 100' X 40' 0 6	6205 AAC 100' X 50' 0 9	6210 AAC 100' X 50' 2 71		

LEGEND


- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- 4105 SECTION NUMBER
AAC Pavement Type
100' X 50' TYPICAL SAMPLE UNIT INFORMATION
FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH
RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE
15 NUMBER OF SAMPLE UNITS IN SECTION
14 NUMBER OF SAMPLE UNITS TO BE INSPECTED
- 605 SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100 INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 79
AC: 76 PCC: 3

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

CONSTRUCTION SINCE LAST INSPECTION
& ANTICIPATED CONSTRUCTION ACTIVITY

CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2014	AP SW	COMPLETE RECONSTRUCTION - PCC
2018	AP N	COMPLETE RECONSTRUCTION - AC
2018	AP N, AP NW, AP S, TW A4, TW A5	OVERLAY - AC STRUCTURAL
2019	AP RU RW23, RW 14-32, RW 5-23, TW A, TW A3, TW A5, TW C, TW E, TW F	MILL AND OVERLAY / VARIABLE MILL WITH 2" P-401 OVERLAY
2019	AP SW	MILL AND OVERLAY
2019	TL A3	NEW CONSTRUCTION - AC / 4" P-401, 6" P-211, 12" STABILIZED SUBBASE



GRAPHIC SCALE IN FEET
0 100 200 400

105 AAC 100' X 35' 4 20 VAR. 0 1	110 AAC 100' X 35' 3 10 VAR. 1 5	120 AAC 100' X 35' 3 10 VAR. 1 5	130 AAC 100' X 35' 3 10 VAR. 1 5	132 AAC 100' X 35' 3 10 VAR. 1 5	135 AAC 100' X 35' 3 10 VAR. 1 5	142 AAC 100' X 35' 3 10 VAR. 1 5	145 AAC 100' X 35' 3 10 VAR. 1 5
150 AAC 100' X 35' 1 1 VAR. 0 12	153 AAC 100' X 35' 1 1 VAR. 0 12	155 AAC 100' X 35' 1 1 VAR. 0 12	160 AAC 100' X 35' 1 1 VAR. 0 12	165 AAC 100' X 35' 1 1 VAR. 0 12	170 AAC 100' X 35' 1 1 VAR. 0 12	175 AAC 100' X 35' 1 1 VAR. 0 12	180 AAC 100' X 35' 1 1 VAR. 0 12
185 AAC 100' X 35' 0 3 VAR. 0 3	210 AAC 100' X 35' 1 2 VAR. 1 2	215 AAC 100' X 35' 1 2 VAR. 1 2	220 AAC 100' X 35' 1 2 VAR. 1 2	225 AAC 100' X 35' 1 2 VAR. 1 2	227 AAC 100' X 35' 1 2 VAR. 1 2	230 AAC 100' X 35' 1 2 VAR. 1 2	235 AAC 100' X 35' 1 2 VAR. 1 2
240 AAC 100' X 35' 1 3 VAR. 1 3	242 AAC 100' X 35' 1 3 VAR. 1 3	243 AAC 100' X 35' 1 3 VAR. 1 3	244 AAC 100' X 35' 1 3 VAR. 1 3	245 AAC 100' X 35' 1 3 VAR. 1 3	250 AAC 100' X 35' 1 3 VAR. 1 3	255 AAC 100' X 35' 1 3 VAR. 1 3	260 AAC 100' X 35' 1 3 VAR. 1 3
265 AAC 100' X 35' 1 1 VAR. 1 1	305 AAC 100' X 35' 0 5 VAR. 0 5	310 AAC 100' X 35' 0 1 VAR. 0 1	320 AAC 100' X 35' 1 4 VAR. 1 4	455 AAC 100' X 35' 1 3 VAR. 1 3	460 AAC 100' X 35' 2 8 VAR. 2 8	505 AAC 100' X 35' 0 3 VAR. 0 3	605 AAC 100' X 35' 0 2 VAR. 0 2
610 AAC 100' X 35' 0 1 VAR. 0 1	765 AAC 100' X 35' 3 18 VAR. 3 18	770 AAC 100' X 35' 1 2 VAR. 1 2	4105 AAC 100' X 35' 0 4 VAR. 0 4	4115 AAC 100' X 35' 0 4 VAR. 0 4	4205 AAC 100' X 35' 0 5 VAR. 0 5	4210 AAC 100' X 35' 0 5 VAR. 0 5	4215 AAC 100' X 35' 0 5 VAR. 0 5
4220 AAC 100' X 35' 2 7 VAR. 2 7	4305 AAC 100' X 35' 1 8 VAR. 1 8	4310 AAC 100' X 35' 0 45 VAR. 0 45	4320 AAC 100' X 35' 0 12 VAR. 0 12	4405 AAC 100' X 35' 1 2 VAR. 1 2	4406 AAC 100' X 35' 1 1 VAR. 1 1	4407 AAC 100' X 35' 1 4 VAR. 1 4	4410 AAC 100' X 35' 0 3 VAR. 0 3
4415 AAC 100' X 35' 1 3 VAR. 1 3	4420 AAC 100' X 35' 1 3 VAR. 1 3	4430 AAC 100' X 35' 1 2 VAR. 1 2	4435 AAC 100' X 35' 1 6 VAR. 1 6	4505 AAC 100' X 35' 5 30 VAR. 5 30	4510 AAC 100' X 35' 1 3 VAR. 1 3	5105 AAC 100' X 35' 1 3 VAR. 1 3	5110 AAC 100' X 35' 0 1 VAR. 0 1
5205 AAC 83.2' X 50' 1 5 VAR. 1 5	5310 AAC 100' X 50' 2 8 VAR. 2 8	6105 AAC 100' X 50' 15 73 VAR. 15 73	6110 AAC 100' X 40' 0 6 VAR. 0 6	6205 AAC 100' X 50' 0 9 VAR. 0 9	6210 AAC 100' X 50' 0 71 VAR. 0 71		

LEGEND

- PROJECTS YEAR 2013
- PROJECTS YEAR 2014
- PROJECTS YEAR 2015
- PROJECTS YEAR 2016
- PROJECTS YEAR 2017
- PROJECTS YEAR 2018
- PROJECTS YEAR 2019
- PROJECTS YEAR 2020
- PROJECTS YEAR 2021
- PROJECTS YEAR 2022

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT
MATCH PUBLISHED RUNWAY LENGTHS.





002 - AIRFIELD PAVEMENT
SYSTEM INVENTORY EXHIBIT

Statewide Airfield Pavement
Management Program

2019

JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT - CRG





FY 2020 AP NW: 4305 AC RESTORATION \$0.39 M	FY 2020 AP SW: 4407 AC RESTORATION \$0.14 M	FY 2020 TW A: 105 AC RESTORATION \$0.71 M	FY 2020 TW A2: 135 AC RESTORATION \$0.06 M
FY 2020 TW A5: 175 AC RESTORATION \$0.05 M	FY 2020 TW A5: 180 AC RESTORATION \$0.08 M	FY 2020 TW B4: 245 AC RECONSTRUCTION \$0.11 M	FY 2020 TW B5: 255 AC RESTORATION \$0.04 M
FY 2020 TW C: 320 AC RESTORATION \$0.16 M	FY 2021 TW A4: 160 AC RESTORATION \$0.05 M	FY 2024 TW A2: 132 AC RESTORATION \$0.03 M	FY 2025 TW A: 120 AC RESTORATION \$0.36 M
FY 2025 TW A3: 145 AC RESTORATION \$0.04 M	FY 2025 TW B: 227 AC RESTORATION \$0.06 M	FY 2025 TW B3: 244 AC RESTORATION \$0.03 M	FY 2029 TW B: 215 AC RESTORATION \$0.28 M

LEGEND

RW 13-31 — TYPICAL RUNWAY BRANCH ID
TW A — TYPICAL TAXIWAY BRANCH ID
AP S — TYPICAL APRON BRANCH ID

PROGRAM YEAR

2020	2025
2021	2026
2022	2027
2023	2028
2024	2029

"PROGRAM YEAR"
"BRANCH"/"SECTION"
"REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

Appendix D

Inspection Photograph Documentation



RW 5-23, Section 6105, Sample Unit 135 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (57) Weathering, and Medium Severity (57) Weathering



RW 5-23, Section 6105, Sample Unit 168 - (42) Bleeding, Low Severity (48) Longitudinal & Transverse Cracking, and Low Severity (57) Weathering



TWA, Section 105, Sample Unit 158 - Low Severity (48) Longitudinal & Transverse Cracking, Low Severity (52) Raveling, and Low Severity (57) Weathering



TWB, Section 225, Sample Unit 120 - Low Severity (50) Patching, Low Severity (52) Raveling, and Low Severity (57) Weathering



TW B4, Section 245, Sample Unit 407 - Low Severity (41) Alligator Cracking, Medium Severity (43) Block Cracking, Low Severity (52) Raveling, and Medium Severity (57) Weathering



AP FAA, Section 4505, Sample Unit 603 - Low Severity (45) Depression, Low Severity (52) Raveling, and Low Severity (57) Weathering



AP N, Section 4220, Sample Unit 600 - Medium Severity (52) Raveling



AP SW, Section 4405, Sample Unit 101 - Medium Severity (72) Shattered Slab

Appendix E

Inspection Distress Details

Re-Inspection Report

FDOT

Generated Date 10/3/2019

Page 1 of 73

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT
-----------------	-----	--------------	---

Branch:	AP FAA	Name:	FAA APRON	Use:	APRON	Area:	153,850 SqFt
----------------	--------	--------------	-----------	-------------	-------	--------------	--------------

Section: 4505 of 2 **From:** - **To:** - **Last Const.:** 1/1/2004

Surface: AC **Family:** C9N59-RL-AP-AC **Zone:** **Category:** **Rank:** T

Area: 147,450 SqFt **Length:** 400 Ft **Width:** 370 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments: This apron was reconstructed on 2005. Section enlarged.

Work Date: 1/1/1983 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Work Date: 1/1/2004 **Work Type:** Complete Reconstruction - AC **Code:** CR-AC **Is Major M&R:** True

Last Insp. Date: 5/1/2019 **TotalSamples:** 30 **Surveyed:** 5

Conditions: PCI: 80

Inspection Comments:

Sample Number: 201 **Type:** R **Area:** 5000.00 SqFt **PCI:** 77

Sample Comments:

45	DEPRESSION	L	125.00	SqFt
57	WEATHERING	L	4750.00	SqFt
52	RAVELING	L	250.00	SqFt
42	BLEEDING	N	1.00	SqFt

Sample Number: 303 **Type:** R **Area:** 5000.00 SqFt **PCI:** 83

Sample Comments:

52	RAVELING	L	250.00	SqFt
57	WEATHERING	L	4750.00	SqFt
45	DEPRESSION	L	50.00	SqFt

Sample Number: 603 **Type:** R **Area:** 5000.00 SqFt **PCI:** 75

Sample Comments:

57	WEATHERING	L	4800.00	SqFt
45	DEPRESSION	L	150.00	SqFt
52	RAVELING	L	200.00	SqFt

Sample Number: 701 **Type:** R **Area:** 4550.00 SqFt **PCI:** 77

Sample Comments:

57	WEATHERING	L	4368.00	SqFt
45	DEPRESSION	L	66.00	SqFt
52	RAVELING	L	182.00	SqFt
48	L & T CR	L	16.00	Ft

Sample Number: 703 **Type:** R **Area:** 5000.00 SqFt **PCI:** 86

Sample Comments:

57	WEATHERING	L	4800.00	SqFt
52	RAVELING	L	200.00	SqFt
48	L & T CR	L	1.00	Ft

Network:

CRG

Name:

JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT

Branch:

AP FAA

Name:

FAA APRON

Use:

APRON

Area:

153,850 SqFt

Section:

4510

of

2

From:

-

To:

-

Last Const.:

1/1/2004

Surface:

PCC

Family:

C9N59-RL-AP-PCC

Zone:

Category:

Rank:

P

Area:

6,400 SqFt

Length:

125 Ft

Width:

50 Ft

Slabs:

64

Slab Length:

10 Ft

Slab Width:

10 Ft

Joint Length:

1,075 Ft

Shoulder:

Street Type:

Grade:

0

Lanes:

0

Section Comments:

Work Date:

1/1/2004

Work Type:

New Construction - Initial

Code:

NU-IN

Is Major M&R:

True

Last Insp. Date:

5/1/2019

TotalSamples:

3

Surveyed:

1

Conditions:

PCI:

78

Inspection Comments:

Sample Number:

852

Type:

R

Area:

24.00 Slabs

PCI:

78

Sample Comments:

75

CORNER SPALL

L

2.00

Slabs

67

LARGE PATCH

L

1.00

Slabs

66

SMALL PATCH

L

1.00

Slabs

74

JOINT SPALL

L

1.00

Slabs

65

JT SEAL DMG

M

24.00

Slabs

73

SHRINKAGE CR

N

13.00

Slabs

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	AP N	Name:	NORTH APRON		Use:	APRON	Area:	339,823 SqFt	
Section:	4205	of	4	From:	-	To:	-	Last Const.:	7/1/2018
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC	Zone:		Category:		Rank:	P
Area:	24,445 SqFt	Length:	200 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1947	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	7/1/2018	Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Last Insp. Date:	2/26/2015	TotalSamples:	4	Surveyed:	1				
Conditions:	PCI:	NOTE:	*** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	705	Type:	R	Area:	6427.00 SqFt	PCI:			
Sample Comments:									
50	PATCHING	H	128.00	SqFt					
45	DEPRESSION	M	9.00	SqFt					
50	PATCHING	M	1.00	SqFt					
45	DEPRESSION	M	65.00	SqFt					
45	DEPRESSION	L	4.00	SqFt					
50	PATCHING	H	42.00	SqFt					
41	ALLIGATOR CRACKING	M	65.00	SqFt					
45	DEPRESSION	M	1.00	SqFt					
52	RAVELING	L	420.00	SqFt					
45	DEPRESSION	M	50.00	SqFt					
45	DEPRESSION	M	8.00	SqFt					
45	DEPRESSION	L	4.00	SqFt					
50	PATCHING	H	333.00	SqFt					
50	PATCHING	M	9.00	SqFt					
50	PATCHING	M	2.00	SqFt					
45	DEPRESSION	L	16.00	SqFt					
45	DEPRESSION	M	1.00	SqFt					
45	DEPRESSION	L	8.00	SqFt					
45	DEPRESSION	L	1.00	SqFt					
45	DEPRESSION	L	6.00	SqFt					
45	DEPRESSION	H	32.00	SqFt					
43	BLOCK CRACKING	M	4600.00	SqFt					
41	ALLIGATOR CRACKING	L	160.00	SqFt					
45	DEPRESSION	L	2.00	SqFt					
45	DEPRESSION	M	1.00	SqFt					

Network:		CRG		Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	AP N		Name:		NORTH APRON		Use:	APRON	Area:	339,823 SqFt			
Section:	4210		of 4		From:	-		To:	-		Last Const.:	7/1/2018	
Surface:	AAC		Family:	C9N59-RL-AP-AAC-APC		Zone:			Category:	Rank:		P	
Area:	265,650 SqFt		Length:	750 Ft		Width:	300 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	1/1/1983		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/2/1983		Work Type:				Surface Treatment - Seal Coat		Code:	ST-SC		Is Major M&R:	False
Work Date:	7/1/2018		Work Type:				Overlay - AC Structural		Code:	OL-AS		Is Major M&R:	True
Last Insp. Date:	2/26/2015		TotalSamples:	54		Surveyed:	6						
Conditions:	PCI: 51		NOTE: *** Pre-Construction PCI ***										
Inspection Comments:													
Sample Number:	107		Type:	R		Area:	5000.00 SqFt		PCI:	50			
Sample Comments:													
56	SWELLING		L	12.00 SqFt									
57	WEATHERING		L	4000.00 SqFt									
43	BLOCK CRACKING		L	5000.00 SqFt									
45	DEPRESSION		L	16.00 SqFt									
56	SWELLING		L	36.00 SqFt									
52	RAVELING		L	1000.00 SqFt									
Sample Number:	202		Type:	R		Area:	5000.00 SqFt		PCI:	59			
Sample Comments:													
52	RAVELING		L	5000.00 SqFt									
43	BLOCK CRACKING		L	5000.00 SqFt									
Sample Number:	209		Type:	R		Area:	5000.00 SqFt		PCI:	44			
Sample Comments:													
45	DEPRESSION		L	63.00 SqFt									
45	DEPRESSION		L	32.00 SqFt									
56	SWELLING		L	400.00 SqFt									
45	DEPRESSION		L	12.00 SqFt									
57	WEATHERING		L	4000.00 SqFt									
52	RAVELING		L	1000.00 SqFt									
43	BLOCK CRACKING		L	5000.00 SqFt									
Sample Number:	304		Type:	R		Area:	5000.00 SqFt		PCI:	56			
Sample Comments:													
45	DEPRESSION		L	10.00 SqFt									
43	BLOCK CRACKING		L	5000.00 SqFt									
52	RAVELING		L	5000.00 SqFt									
56	SWELLING		L	30.00 SqFt									
Sample Number:	406		Type:	R		Area:	5000.00 SqFt		PCI:	49			
Sample Comments:													
43	BLOCK CRACKING		L	5000.00 SqFt									
56	SWELLING		L	8.00 SqFt									
56	SWELLING		L	150.00 SqFt									
52	RAVELING		L	1000.00 SqFt									
57	WEATHERING		L	4000.00 SqFt									
Sample Number:	610		Type:	R		Area:	5335.00 SqFt		PCI:	50			
Sample Comments:													
48	LONGITUDINAL/TRANSVERSE CRACKING		L	118.00 Ft									
52	RAVELING		L	5335.00 SqFt									
43	BLOCK CRACKING		L	4001.00 SqFt									

56	SWELLING	L	300.00	SqFt
45	DEPRESSION	L	20.00	SqFt

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP N	Name:	NORTH APRON	Use:	APRON	Area:	339,823 SqFt		
Section:	4215	of	4	From:	-	To:	-	Last Const.:	7/1/2018
Surface:	AC	Family:	C9N59-RL-AP-AC	Zone:		Category:		Rank:	S
Area:	22,406 SqFt	Length:	310 Ft	Width:	76 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1994	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	7/1/2018	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	2/26/2015	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI: 35	NOTE:	*** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	500	Type:	R	Area:	2960.00 SqFt	PCI:	35		
Sample Comments:									
43	BLOCK CRACKING	L	1480.00	SqFt					
43	BLOCK CRACKING	M	1480.00	SqFt					
45	DEPRESSION	L	4.00	SqFt					
52	RAVELING	M	592.00	SqFt					
45	DEPRESSION	L	4.00	SqFt					
52	RAVELING	L	2368.00	SqFt					
45	DEPRESSION	L	1.00	SqFt					

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP N	Name:	NORTH APRON	Use:	APRON	Area:	339,823 SqFt		
Section:	4220	of	4	From:	-	To:	-	Last Const.:	12/25/1994
Surface:	AC	Family:	C9N59-RL-AP-AC	Zone:		Category:		Rank:	S
Area:	27,322 SqFt	Length:	1,370 Ft	Width:	20 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1994	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	5/1/2019	TotalSamples:	7	Surveyed:	2				
Conditions:	PCI: 30								
Inspection Comments:									
Sample Number:	502	Type:	R	Area:	3323.00 SqFt	PCI:	30		
Sample Comments:									
52	RAVELING	M	350.00	SqFt					
43	BLOCK CR	L	700.00	SqFt					
50	PATCHING	M	40.00	SqFt					
52	RAVELING	L	2913.00	SqFt					
50	PATCHING	L	20.00	SqFt					
41	ALLIGATOR CR	L	90.00	SqFt					
45	DEPRESSION	L	102.00	SqFt					
48	L & T CR	L	356.00	Ft					
Sample Number:	600	Type:	R	Area:	3021.00 SqFt	PCI:	30		
Sample Comments:									
45	DEPRESSION	L	5.00	SqFt					
50	PATCHING	M	6.00	SqFt					
41	ALLIGATOR CR	H	24.00	SqFt					
48	L & T CR	L	92.00	Ft					
41	ALLIGATOR CR	L	225.00	SqFt					
52	RAVELING	L	2615.00	SqFt					
52	RAVELING	M	400.00	SqFt					

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	AP NW		Name:	NW APRON		Use:	APRON		Area:	302,241 SqFt		
Section:	4305		of	3	From:	-		To:	-		Last Const.:	1/1/1991
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:	Rank: P		
Area:	41,023 SqFt		Length:	200 Ft		Width:	187 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1991		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	8		Surveyed:	1					
Conditions:	PCI: 63											
Inspection Comments:												
Sample Number:	551	Type:	R	Area:	6793.00 SqFt		PCI:	63				
Sample Comments:												
48	L & T CR		L	773.00 Ft								
57	WEATHERING		L	5774.00 SqFt								
52	RAVELING		L	1019.00 SqFt								
56	SWELLING		L	50.00 SqFt								

Network:		CRG		Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT													
Branch:		AP NW		Name:		NW APRON		Use:		APRON		Area:		302,241 SqFt					
Section:		4310		of		3		From:		-		To:		-		Last Const.:		7/1/2018	
Surface:		AAC		Family:		C9N59-RL-AP-AAC-APC		Zone:				Category:				Rank:		P	
Area:		204,437 SqFt		Length:		900 Ft		Width:		200 Ft									
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft					
Shoulder:				Street Type:				Grade:		0		Lanes:		0					
Section Comments:																			
Work Date:		1/1/1960		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		7/1/2018		Work Type:		Overlay - AC Structural		Code:		OL-AS		Is Major M&R:		True					
Last Insp. Date:		2/26/2015		TotalSamples:		41		Surveyed:		5									
Conditions:		PCI: 35		NOTE:		*** Pre-Construction PCI ***													
Inspection Comments:																			
Sample Number:		204		Type:		R		Area:		5000.00 SqFt		PCI:		16					
Sample Comments:																			
52	RAVELING			L	704.00	SqFt													
57	WEATHERING			M	3986.00	SqFt													
43	BLOCK CRACKING			L	2562.00	SqFt													
50	PATCHING			H	8.00	SqFt													
43	BLOCK CRACKING			M	800.00	SqFt													
50	PATCHING			H	2.00	SqFt													
50	PATCHING			M	300.00	SqFt													
41	ALLIGATOR CRACKING			M	1328.00	SqFt													
45	DEPRESSION			L	4.00	SqFt													
45	DEPRESSION			L	9.00	SqFt													
Sample Number:		251		Type:		R		Area:		5000.00 SqFt		PCI:		54					
Sample Comments:																			
43	BLOCK CRACKING			L	5000.00	SqFt													
52	RAVELING			L	750.00	SqFt													
57	WEATHERING			M	4250.00	SqFt													
Sample Number:		351		Type:		R		Area:		5409.00 SqFt		PCI:		54					
Sample Comments:																			
52	RAVELING			L	811.00	SqFt													
43	BLOCK CRACKING			L	5409.00	SqFt													
57	WEATHERING			M	4598.00	SqFt													
Sample Number:		507		Type:		R		Area:		5148.00 SqFt		PCI:		35					
Sample Comments:																			
45	DEPRESSION			L	15.00	SqFt													
45	DEPRESSION			L	12.00	SqFt													
45	DEPRESSION			L	27.00	SqFt													
45	DEPRESSION			L	30.00	SqFt													
43	BLOCK CRACKING			L	4148.00	SqFt													
45	DEPRESSION			L	12.00	SqFt													
45	DEPRESSION			L	14.00	SqFt													
52	RAVELING			M	1030.00	SqFt													
52	RAVELING			L	4118.00	SqFt													
43	BLOCK CRACKING			M	1000.00	SqFt													
45	DEPRESSION			L	36.00	SqFt													
Sample Number:		554		Type:		R		Area:		4900.00 SqFt		PCI:		14					
Sample Comments:																			
45	DEPRESSION			M	40.00	SqFt													
45	DEPRESSION			L	12.00	SqFt													
41	ALLIGATOR CRACKING			L	180.00	SqFt													
45	DEPRESSION			L	4.00	SqFt													
52	RAVELING			M	1960.00	SqFt													
45	DEPRESSION			L	8.00	SqFt													

52	RAVELING	L	2940.00	SqFt
41	ALLIGATOR CRACKING	M	54.00	SqFt
45	DEPRESSION	M	4.00	SqFt
43	BLOCK CRACKING	L	4666.00	SqFt
45	DEPRESSION	M	16.00	SqFt
45	DEPRESSION	M	54.00	SqFt

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP NW		Name:	NW APRON		Use:	APRON	Area:	302,241 SqFt	
Section:	4320 of 3		From:	-		To:	-		Last Const.:	7/1/2018
Surface:	AAC		Family:	C9N59-RL-AP-AAC-APC		Zone:			Rank:	P
Area:	56,781 SqFt		Length:	2,040 Ft		Width:	20 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	12/25/1994		Work Type:	New Construction - AC				Code:	NC-AC	
Work Date:	7/1/2018		Work Type:	Overlay - AC Structural				Code:	OL-AS	
Last Insp. Date:	2/26/2015		Total Samples:	12		Surveyed:	3			
Conditions:	PCI: 34		NOTE: *** Pre-Construction PCI ***							
Inspection Comments:										
Sample Number:	100		Type:	R		Area:	5028.00 SqFt		PCI:	50
Sample Comments:										
43	BLOCK CRACKING		L	4755.00 SqFt						
50	PATCHING		L	45.00 SqFt						
52	RAVELING		L	4755.00 SqFt						
50	PATCHING		M	102.00 SqFt						
50	PATCHING		L	90.00 SqFt						
50	PATCHING		L	36.00 SqFt						
Sample Number:	302		Type:	R		Area:	5327.00 SqFt		PCI:	29
Sample Comments:										
43	BLOCK CRACKING		L	5161.00 SqFt						
41	ALLIGATOR CRACKING		L	166.00 SqFt						
52	RAVELING		L	3196.00 SqFt						
52	RAVELING		M	2131.00 SqFt						
45	DEPRESSION		M	20.00 SqFt						
Sample Number:	404		Type:	R		Area:	4948.00 SqFt		PCI:	23
Sample Comments:										
52	RAVELING		M	1979.00 SqFt						
52	RAVELING		L	2969.00 SqFt						
41	ALLIGATOR CRACKING		L	114.00 SqFt						
45	DEPRESSION		M	152.00 SqFt						
48	LONGITUDINAL/TRANSVERSE CRACKING		L	114.00 Ft						
48	LONGITUDINAL/TRANSVERSE CRACKING		M	62.00 Ft						
45	DEPRESSION		M	16.00 SqFt						
43	BLOCK CRACKING		L	4834.00 SqFt						

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP RU RW 5		Name:	RUN-UP APRON AT RW 5		Use:	APRON		Area:	22,135 SqFt	
Section:	5205 of 1		From:	-			To:	-		Last Const.:	1/1/2003
Surface:	AC		Family:	C9N59-RL-AP-AC		Zone:			Category:	Rank: T	
Area:	22,135 SqFt		Length:	809 Ft		Width:	75 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:	This apron was removed and relocated on 2005.										
Work Date:	1/1/1991		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2003		Work Type:	Complete Reconstruction - AC			Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI: 77										
Inspection Comments:											
Sample Number:	302		Type:	R		Area:	4125.00 SqFt		PCI:	77	
Sample Comments:											
57	WEATHERING		M	2825.00 SqFt							
52	RAVELING		L	1300.00 SqFt							

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP RU RW14	Name:	RUN-UP APRON AT RW 14		Use:	APRON	Area:	24,645 SqFt	
Section:	5310	of	1	From:	-	To:	-	Last Const.:	1/1/2010
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC	Zone:		Category:		Rank:	P
Area:	24,645 SqFt	Length:	73 Ft	Width:	200 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1991	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2010	Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	5/1/2019	TotalSamples:	6	Surveyed:	2				
Conditions:	PCI: 71								
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	4113.00 SqFt	PCI:	71		
Sample Comments:									
52	RAVELING	L	41.00 SqFt						
48	L & T CR	L	245.00 Ft						
56	SWELLING	L	75.00 SqFt						
57	WEATHERING	L	4072.00 SqFt						
Sample Number:	201	Type:	R	Area:	5000.00 SqFt	PCI:	70		
Sample Comments:									
48	L & T CR	L	380.00 Ft						
56	SWELLING	L	100.00 SqFt						
57	WEATHERING	L	5000.00 SqFt						

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP RU RW23		Name:	RUN-UP APRON AT RW 23		Use:	APRON	Area:	18,147 SqFt	
Section:	5105	of 2	From:	-			To:	-	Last Const.:	1/1/2005
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	P
Area:	12,030 SqFt	Length:	150 Ft		Width:	80 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2005		Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	3		Surveyed:	1			
Conditions:	PCI:	73								
Inspection Comments:										
Sample Number:	401	Type:	R	Area:	3982.00 SqFt		PCI:	73		
Sample Comments:										
52	RAVELING	L	1500.00 SqFt							
48	L & T CR	L	24.00 Ft							
57	WEATHERING	L	2482.00 SqFt							

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	AP RU RW23		Name:	RUN-UP APRON AT RW 23		Use:	APRON		Area:	18,147 SqFt	
Section:	5110 of 2		From:	-		To:	-		Last Const.:	1/1/2019	
Surface:	AAC		Family:	C9N59-RL-AP-AAC-APC		Zone:			Category:	Rank: P	
Area:	6,117 SqFt		Length:	80 Ft		Width:	76 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2005		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Work Date:	1/1/2019		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True	
Last Insp. Date:	2/26/2015		TotalSamples:	4		Surveyed:		1			
Conditions:	PCI: 74		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	401		Type:	R		Area:	4000.00 SqFt		PCI:	74	
Sample Comments:											
52	RAVELING		L	1200.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	21.00 Ft							
57	WEATHERING		L	2800.00 SqFt							

Network:	CRG	Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT					
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	201,078 SqFt	
Section:	4105	of 2	From:	-	To:	-	Last Const.:	7/1/2018	
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC	Zone:		Category:	Rank:	P	
Area:	185,265 SqFt	Length:	580 Ft	Width:	250 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1986	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/2/1986	Work Type:			Surface Treatment - Seal Coat	Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2010	Work Type:			Surface Treatment - Seal Coat	Code:	ST-SC	Is Major M&R:	False
Work Date:	7/1/2018	Work Type:			Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Last Insp. Date:	2/26/2015	TotalSamples:	37	Surveyed:	5				
Conditions:	PCI: 54	NOTE: *** Pre-Construction PCI ***							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	5000.00 SqFt	PCI:	51		
Sample Comments:									
43	BLOCK CRACKING	M	500.00 SqFt						
52	RAVELING	L	1500.00 SqFt						
57	WEATHERING	L	3500.00 SqFt						
43	BLOCK CRACKING	L	4500.00 SqFt						
Sample Number:	200	Type:	R	Area:	5000.00 SqFt	PCI:	54		
Sample Comments:									
57	WEATHERING	L	3500.00 SqFt						
43	BLOCK CRACKING	L	5000.00 SqFt						
52	RAVELING	L	1500.00 SqFt						
Sample Number:	203	Type:	R	Area:	5000.00 SqFt	PCI:	54		
Sample Comments:									
43	BLOCK CRACKING	L	5000.00 SqFt						
52	RAVELING	L	500.00 SqFt						
57	WEATHERING	L	4500.00 SqFt						
Sample Number:	404	Type:	R	Area:	5000.00 SqFt	PCI:	54		
Sample Comments:									
52	RAVELING	L	500.00 SqFt						
57	WEATHERING	L	4500.00 SqFt						
43	BLOCK CRACKING	L	5000.00 SqFt						
Sample Number:	600	Type:	R	Area:	4114.00 SqFt	PCI:	54		
Sample Comments:									
57	WEATHERING	L	3291.00 SqFt						
45	DEPRESSION	L	6.00 SqFt						
43	BLOCK CRACKING	L	4114.00 SqFt						
52	RAVELING	L	823.00 SqFt						

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT									
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	201,078 SqFt					
Section:	4115	of 2	From:	-		To:	-		Last Const.:	7/1/2018			
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC		Zone:	Category:		Rank:		P			
Area:	15,813 SqFt		Length:	100 Ft		Width:	160 Ft						
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:	Street Type:				Grade:	0		Lanes:	0				
Section Comments:													
Work Date:	1/1/1986		Work Type:			BUILT		Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/2007		Work Type:			Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Work Date:	7/1/2018		Work Type:			Overlay - AC Structural			Code:	OL-AS		Is Major M&R:	True
Last Insp. Date:	2/26/2015		TotalSamples:	4		Surveyed:	1						
Conditions:	PCI: 30		NOTE: *** Pre-Construction PCI ***										
Inspection Comments:													
Sample Number:	506	Type:	R	Area:	3550.00 SqFt		PCI:	30					
Sample Comments:													
43	BLOCK CRACKING		L	252.00	SqFt								
49	OIL SPILLAGE		N	16.00	SqFt								
52	RAVELING		H	4.00	SqFt								
52	RAVELING		L	532.00	SqFt								
45	DEPRESSION		L	10.00	SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	82.00	Ft								
41	ALLIGATOR CRACKING		L	90.00	SqFt								
43	BLOCK CRACKING		L	330.00	SqFt								
45	DEPRESSION		L	55.00	SqFt								
45	DEPRESSION		L	21.00	SqFt								
53	RUTTING		L	90.00	SqFt								
43	BLOCK CRACKING		L	702.00	SqFt								
45	DEPRESSION		L	8.00	SqFt								
45	DEPRESSION		M	49.00	SqFt								
49	OIL SPILLAGE		N	9.00	SqFt								
41	ALLIGATOR CRACKING		L	25.00	SqFt								
45	DEPRESSION		L	12.00	SqFt								
41	ALLIGATOR CRACKING		M	18.00	SqFt								

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP SW	Name:	SOUTHWEST APRON	Use:	APRON	Area:	98,600 SqFt		
Section:	4405	of	8	From:	-	To:	-	Last Const.:	12/25/1999
Surface:	PCC	Family:	C9N59-RL-AP-PCC	Zone:		Category:		Rank:	S
Area:	8,887 SqFt	Length:	150 Ft	Width:	60 Ft				
Slabs:	2	Slab Length:	15 Ft	Slab Width:	25 Ft	Joint Length:	750 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1999	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	5/1/2019	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	12							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	10.00 Slabs	PCI:	12		
Sample Comments:									
72	SHAT. SLAB	M	4.00	Slabs					
72	SHAT. SLAB	L	2.00	Slabs					
62	CORNER BREAK	M	1.00	Slabs					
73	SHRINKAGE CR	N	6.00	Slabs					
63	LINEAR CR	M	2.00	Slabs					
67	LARGE PATCH	L	1.00	Slabs					
62	CORNER BREAK	L	1.00	Slabs					
65	JT SEAL DMG	H	10.00	Slabs					
75	CORNER SPALL	L	1.00	Slabs					
63	LINEAR CR	L	1.00	Slabs					

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	AP SW		Name:	SOUTHWEST APRON		Use:	APRON	Area:	98,600 SqFt		
Section:	4407	of 8	From:	-			To:	-			
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:				
Area:	14,286 SqFt		Length:	245 Ft		Width:	60 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	12/25/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	56									
Inspection Comments:											
Sample Number:	204	Type:	R	Area:	3020.00 SqFt		PCI:	56			
Sample Comments:											
56	SWELLING		L	62.00	SqFt						
52	RAVELING		L	310.00	SqFt						
57	WEATHERING		L	2710.00	SqFt						
48	L & T CR		M	129.00	Ft						
48	L & T CR		L	300.00	Ft						

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	AP SW	Name:	SOUTHWEST APRON	Use:	APRON	Area:	98,600 SqFt		
Section:	4410	of	8	From:	-	To:	-	Last Const.:	1/1/2019
Surface:	AAC	Family:	C9N59-RL-AP-AAC-APC	Zone:		Category:		Rank:	S
Area:	12,829 SqFt	Length:	350 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1994	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2019	Work Type:	MILL and OVERLAY			Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	2/26/2015	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI: 42	NOTE:	*** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	5184.00 SqFt	PCI:	42		
Sample Comments:									
45	DEPRESSION	L	6.00	SqFt					
45	DEPRESSION	M	30.00	SqFt					
45	DEPRESSION	M	40.00	SqFt					
52	RAVELING	M	518.00	SqFt					
45	DEPRESSION	L	6.00	SqFt					
45	DEPRESSION	L	12.00	SqFt					
48	LONGITUDINAL/TRANSVERSE CRACKING	M	131.00	Ft					
45	DEPRESSION	M	12.00	SqFt					
45	DEPRESSION	L	24.00	SqFt					
45	DEPRESSION	M	9.00	SqFt					
45	DEPRESSION	L	9.00	SqFt					
52	RAVELING	L	4666.00	SqFt					
48	LONGITUDINAL/TRANSVERSE CRACKING	L	450.00	Ft					

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	AP SW		Name:	SOUTHWEST APRON		Use:	APRON	Area:	98,600 SqFt		
Section:	4415	of	8	From:	-	To:	-	Last Const.:	1/1/2002		
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:		Rank:	S	
Area:	23,211 SqFt		Length:	275 Ft		Width:	78 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2002		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI:	68									
Inspection Comments:											
Sample Number:	301	Type:	R	Area:	5800.00 SqFt		PCI:	68			
Sample Comments:											
52	RAVELING	L	870.00		SqFt						
45	DEPRESSION	L	56.00		SqFt						
48	L & T CR	L	65.00		Ft						
50	PATCHING	L	420.00		SqFt						
57	WEATHERING	L	4510.00		SqFt						

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	AP SW		Name:	SOUTHWEST APRON		Use:	APRON	Area:	98,600 SqFt		
Section:	4420	of 8	From:	-			To:	-			
Surface:	AC	Family:	C9N59-RL-AP-AC		Zone:		Category:				
Area:	12,167 SqFt		Length:	100 Ft		Width:	100 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	12/25/1994		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	3		Surveyed:	1				
Conditions:	PCI:	67									
Inspection Comments:											
Sample Number:	101	Type:	R	Area:	4991.00 SqFt		PCI:	67			
Sample Comments:											
50	PATCHING	L	4.00 SqFt								
50	PATCHING	M	200.00 SqFt								
48	L & T CR	L	104.00 Ft								
52	RAVELING	L	1915.00 SqFt								
57	WEATHERING	L	2872.00 SqFt								

Network: CRG		Name: JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT	
Branch: AP SW	Name: SOUTHWEST APRON	Use: APRON	Area: 98,600 SqFt
Section: 4430	of 8	From: -	To: -
Surface: AC	Family: C9N59-RL-AP-AC	Zone:	Category: Rank: S
Area: 4,074 SqFt	Length: 59 Ft	Width: 59 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 1/1/2006	Work Type: New Construction - Initial	Code: NU-IN	Is Major M&R: True
Last Insp. Date: 5/1/2019	TotalSamples: 2	Surveyed: 1	
Conditions: PCI: 26			
Inspection Comments:			
Sample Number: 200	Type: R	Area: 1967.00 SqFt	PCI: 26
Sample Comments:			
48	L & T CR	L	86.00 Ft
56	SWELLING	L	20.00 SqFt
45	DEPRESSION	M	520.00 SqFt
52	RAVELING	L	787.00 SqFt
57	WEATHERING	M	1180.00 SqFt
45	DEPRESSION	L	40.00 SqFt

Network: CRG		Name: JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT	
Branch: AP SW	Name: SOUTHWEST APRON	Use: APRON	Area: 98,600 SqFt
Section: 4435	of 8	From: -	To: -
Surface: AAC	Family: C9N59-RL-AP-AAC-APC	Zone:	Category: Rank: S
Area: 20,729 SqFt	Length: 570 Ft	Width: 35 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 12/25/1999	Work Type: New Construction - Initial	Code: NU-IN	Is Major M&R: True
Work Date: 1/1/2007	Work Type: Overlay - AC Structural	Code: OL-AS	Is Major M&R: True
Last Insp. Date: 5/1/2019	TotalSamples: 6	Surveyed: 1	
Conditions: PCI: 74			
Inspection Comments:			
Sample Number: 601	Type: R	Area: 3500.00 SqFt	PCI: 74
Sample Comments:			
57	WEATHERING	L	3500.00 SqFt
45	DEPRESSION	L	24.00 SqFt
56	SWELLING	L	20.00 SqFt
48	L & T CR	L	162.00 Ft

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	RW 14-32		Name:	RUNWAY 14-32		Use:	RUNWAY	Area:	400,800 SqFt
Section:	6205	of 2	From:	-			To:	-	Last Const.: 1/1/2019
Surface:	AAC	Family:	C9N59-RL-RW-AAC-APC		Zone:		Category:		Rank: P
Area:	45,000 SqFt		Length:	375 Ft		Width:	100 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:			Grade:		0	Lanes:		0
Section Comments:									
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2005		Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R: True
Work Date:	1/1/2019		Work Type: MILL and OVERLAY				Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	2/26/2015		TotalSamples:	9		Surveyed: 2			
Conditions:	PCI: 66		NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	103	Type:	R	Area:		5000.00 SqFt	PCI:		65
Sample Comments:									
52	RAVELING	L	500.00 SqFt						
48	LONGITUDINAL/TRANSVERSE CRACKING	L	507.00 Ft						
56	SWELLING	L	26.00 SqFt						
57	WEATHERING	L	4500.00 SqFt						
Sample Number:	106	Type:	R	Area:		5000.00 SqFt	PCI:		67
Sample Comments:									
52	RAVELING	L	250.00 SqFt						
56	SWELLING	L	31.00 SqFt						
48	LONGITUDINAL/TRANSVERSE CRACKING	L	50.00 Ft						
48	LONGITUDINAL/TRANSVERSE CRACKING	L	232.00 Ft						
48	LONGITUDINAL/TRANSVERSE CRACKING	M	54.00 Ft						
57	WEATHERING	L	4750.00 SqFt						

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	RW 14-32		Name:	RUNWAY 14-32		Use:	RUNWAY	Area:	400,800 SqFt			
Section:	6210		of	2	From:	-		To:	-		Last Const.:	1/1/2019
Surface:	AAC		Family:	C9N59-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	355,800 SqFt		Length:	3,558 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1991		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2005		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Work Date:	1/1/2019		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	2/26/2015		TotalSamples:	71		Surveyed:	15					
Conditions:	PCI: 55		NOTE: *** Pre-Construction PCI ***									
Inspection Comments:												
Sample Number:	109		Type:	R		Area:	5000.00 SqFt		PCI:	62		
Sample Comments:												
42	BLEEDING		N	10.00 SqFt								
52	RAVELING		L	250.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	399.00 Ft								
57	WEATHERING		L	4750.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	250.00 Ft								
Sample Number:	114		Type:	R		Area:	5000.00 SqFt		PCI:	57		
Sample Comments:												
48	LONGITUDINAL/TRANSVERSE CRACKING		L	629.00 Ft								
52	RAVELING		L	250.00 SqFt								
42	BLEEDING		N	1.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		M	100.00 Ft								
56	SWELLING		L	8.00 SqFt								
57	WEATHERING		L	4750.00 SqFt								
Sample Number:	120		Type:	R		Area:	5000.00 SqFt		PCI:	59		
Sample Comments:												
52	RAVELING		L	250.00 SqFt								
57	WEATHERING		L	4750.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	522.00 Ft								
42	BLEEDING		N	4.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		M	100.00 Ft								
56	SWELLING		L	18.00 SqFt								
Sample Number:	125		Type:	R		Area:	5000.00 SqFt		PCI:	53		
Sample Comments:												
52	RAVELING		L	250.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		M	50.00 Ft								
57	WEATHERING		L	4750.00 SqFt								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	561.00 Ft								
48	LONGITUDINAL/TRANSVERSE CRACKING		L	150.00 Ft								

56	SWELLING	L	71.00	SqFt		
Sample Number: 128		Type: R	Area: 5000.00	SqFt	PCI: 56	
Sample Comments:						
48	LONGITUDINAL/TRANSVERSE CRACKING	L	678.00	Ft		
57	WEATHERING	L	4750.00	SqFt		
56	SWELLING	L	26.00	SqFt		
52	RAVELING	L	250.00	SqFt		
48	LONGITUDINAL/TRANSVERSE CRACKING	M	100.00	Ft		
42	BLEEDING	N	3.00	SqFt		
Sample Number: 132		Type: R	Area: 5000.00	SqFt	PCI: 50	
Sample Comments:						
48	LONGITUDINAL/TRANSVERSE CRACKING	M	100.00	Ft		
56	SWELLING	L	42.00	SqFt		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	469.00	Ft		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	363.00	Ft		
42	BLEEDING	N	17.00	SqFt		
57	WEATHERING	L	4750.00	SqFt		
52	RAVELING	L	250.00	SqFt		
Sample Number: 138		Type: R	Area: 5000.00	SqFt	PCI: 55	
Sample Comments:						
52	RAVELING	L	250.00	SqFt		
48	LONGITUDINAL/TRANSVERSE CRACKING	M	82.00	Ft		
57	WEATHERING	L	4750.00	SqFt		
56	SWELLING	L	18.00	SqFt		
42	BLEEDING	N	6.00	SqFt		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	700.00	Ft		
Sample Number: 144		Type: R	Area: 5000.00	SqFt	PCI: 53	
Sample Comments:						
42	BLEEDING	N	8.00	SqFt		
57	WEATHERING	L	4750.00	SqFt		
52	RAVELING	L	250.00	SqFt		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	100.00	Ft		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	356.00	Ft		
48	LONGITUDINAL/TRANSVERSE CRACKING	M	100.00	Ft		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	335.00	Ft		
56	SWELLING	L	22.00	SqFt		
Sample Number: 147		Type: R	Area: 5000.00	SqFt	PCI: 52	
Sample Comments:						
42	BLEEDING	N	16.00	SqFt		
48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00	Ft		
56	SWELLING	L	71.00	SqFt		
57	WEATHERING	L	4750.00	SqFt		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	343.00	Ft		
48	LONGITUDINAL/TRANSVERSE CRACKING	L	302.00	Ft		
52	RAVELING	L	250.00	SqFt		
Sample Number: 151		Type: R	Area: 5000.00	SqFt	PCI: 48	
Sample Comments:						
56	SWELLING	L	67.00	SqFt		
52	RAVELING	L	250.00	SqFt		

48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00	Ft
42	BLEEDING	N	20.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	329.00	Ft
57	WEATHERING	L	4750.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	512.00	Ft
<hr/>				
Sample Number: 156		Type: R	Area: 5000.00	SqFt PCI: 61
Sample Comments:				
56	SWELLING	L	38.00	SqFt
52	RAVELING	L	250.00	SqFt
57	WEATHERING	L	4750.00	SqFt
42	BLEEDING	N	12.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	562.00	Ft
<hr/>				
Sample Number: 163		Type: R	Area: 5000.00	SqFt PCI: 53
Sample Comments:				
48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00	Ft
42	BLEEDING	N	10.00	SqFt
56	SWELLING	L	61.00	SqFt
57	WEATHERING	L	4750.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	315.00	Ft
52	RAVELING	L	250.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	371.00	Ft
<hr/>				
Sample Number: 170		Type: R	Area: 5000.00	SqFt PCI: 56
Sample Comments:				
48	LONGITUDINAL/TRANSVERSE CRACKING	L	376.00	Ft
56	SWELLING	L	39.00	SqFt
57	WEATHERING	L	4750.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	400.00	Ft
56	SWELLING	L	100.00	SqFt
52	RAVELING	L	250.00	SqFt
<hr/>				
Sample Number: 174		Type: R	Area: 5000.00	SqFt PCI: 52
Sample Comments:				
42	BLEEDING	N	9.00	SqFt
56	SWELLING	L	50.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00	Ft
52	RAVELING	L	250.00	SqFt
57	WEATHERING	L	4750.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	414.00	Ft
42	BLEEDING	N	9.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	250.00	Ft
<hr/>				
Sample Number: 179		Type: R	Area: 5800.00	SqFt PCI: 60
Sample Comments:				
52	RAVELING	L	290.00	SqFt
56	SWELLING	L	11.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	M	50.00	Ft
57	WEATHERING	L	5510.00	SqFt
48	LONGITUDINAL/TRANSVERSE CRACKING	L	576.00	Ft

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT										
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	389,600 SqFt					
Section:	6105		of	2		From:	-		To:	-		Last Const.:	1/1/2011	
Surface:	AAC		Family:	C9N59-RL-RW-AAC-APC		Zone:			Category:			Rank:	S	
Area:	363,800 SqFt		Length:	3,638 Ft		Width:	100 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1991		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2011		Work Type:	MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True		
Last Insp. Date:	5/1/2019		TotalSamples:	73		Surveyed:	15							
Conditions:	PCI: 68													
Inspection Comments:														
Sample Number:	101		Type:	R		Area:	5000.00 SqFt		PCI:	75				
Sample Comments:														
52	RAVELING		L	1240.00 SqFt										
57	WEATHERING		L	3760.00 SqFt										
48	L & T CR		L	244.00 Ft										
Sample Number:	106		Type:	R		Area:	5000.00 SqFt		PCI:	67				
Sample Comments:														
42	BLEEDING		N	6.00 SqFt										
52	RAVELING		L	50.00 SqFt										
48	L & T CR		M	50.00 Ft										
48	L & T CR		L	402.00 Ft										
57	WEATHERING		L	4950.00 SqFt										
Sample Number:	112		Type:	R		Area:	5000.00 SqFt		PCI:	62				
Sample Comments:														
52	RAVELING		L	78.00 SqFt										
57	WEATHERING		L	4922.00 SqFt										
56	SWELLING		L	35.00 SqFt										
42	BLEEDING		N	20.00 SqFt										
48	L & T CR		M	100.00 Ft										
48	L & T CR		L	368.00 Ft										
Sample Number:	115		Type:	R		Area:	5000.00 SqFt		PCI:	69				
Sample Comments:														
56	SWELLING		L	25.00 SqFt										
48	L & T CR		L	350.00 Ft										
57	WEATHERING		L	4900.00 SqFt										
52	RAVELING		L	100.00 SqFt										
42	BLEEDING		N	14.00 SqFt										
Sample Number:	121		Type:	R		Area:	5000.00 SqFt		PCI:	70				
Sample Comments:														
42	BLEEDING		N	3.00 SqFt										
57	WEATHERING		L	3000.00 SqFt										
52	RAVELING		L	2000.00 SqFt										
48	L & T CR		L	302.00 Ft										
56	SWELLING		L	25.00 SqFt										
Sample Number:	129		Type:	R		Area:	5000.00 SqFt		PCI:	58				
Sample Comments:														
48	L & T CR		M	50.00 Ft										

48	L & T CR	L	556.00	Ft
42	BLEEDING	N	1.00	SqFt
57	WEATHERING	L	4750.00	SqFt
56	SWELLING	L	63.00	SqFt
57	WEATHERING	M	250.00	SqFt
Sample Number: 135 Type: R Area: 5000.00 SqFt PCI: 61				
Sample Comments:				
57	WEATHERING	L	4750.00	SqFt
56	SWELLING	L	50.00	SqFt
57	WEATHERING	M	250.00	SqFt
48	L & T CR	M	75.00	Ft
48	L & T CR	L	482.00	Ft
Sample Number: 140 Type: R Area: 5000.00 SqFt PCI: 70				
Sample Comments:				
48	L & T CR	L	267.00	Ft
48	L & T CR	M	50.00	Ft
42	BLEEDING	N	11.00	SqFt
57	WEATHERING	M	250.00	SqFt
57	WEATHERING	L	4750.00	SqFt
Sample Number: 143 Type: R Area: 5000.00 SqFt PCI: 65				
Sample Comments:				
57	WEATHERING	L	4750.00	SqFt
48	L & T CR	L	402.00	Ft
57	WEATHERING	M	250.00	SqFt
42	BLEEDING	N	11.00	SqFt
48	L & T CR	M	100.00	Ft
Sample Number: 149 Type: R Area: 5000.00 SqFt PCI: 76				
Sample Comments:				
52	RAVELING	L	36.00	SqFt
42	BLEEDING	N	5.00	SqFt
57	WEATHERING	L	4964.00	SqFt
48	L & T CR	L	312.00	Ft
Sample Number: 154 Type: R Area: 5000.00 SqFt PCI: 72				
Sample Comments:				
57	WEATHERING	M	100.00	SqFt
57	WEATHERING	L	4900.00	SqFt
48	L & T CR	L	323.00	Ft
42	BLEEDING	N	28.00	SqFt
Sample Number: 157 Type: R Area: 5000.00 SqFt PCI: 64				
Sample Comments:				
57	WEATHERING	L	4950.00	SqFt
48	L & T CR	M	27.00	Ft
48	L & T CR	L	445.00	Ft
57	WEATHERING	M	50.00	SqFt
42	BLEEDING	N	15.00	SqFt
Sample Number: 163 Type: R Area: 5000.00 SqFt PCI: 76				
Sample Comments:				
57	WEATHERING	M	50.00	SqFt
42	BLEEDING	N	1.00	SqFt
48	L & T CR	L	323.00	Ft
57	WEATHERING	L	4950.00	SqFt
Sample Number: 168 Type: R Area: 5000.00 SqFt PCI: 61				
Sample Comments:				
48	L & T CR	M	50.00	Ft
52	RAVELING	L	50.00	SqFt
42	BLEEDING	N	23.00	SqFt
48	L & T CR	L	461.00	Ft
56	SWELLING	L	5.00	SqFt
57	WEATHERING	L	4950.00	SqFt

Sample Number:		171	Type:	R	Area:	5000.00 SqFt	PCI:	80
Sample Comments:								
48	L & T CR		L		92.00 Ft			
57	WEATHERING		L		4468.00 SqFt			
52	RAVELING		L		532.00 SqFt			

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	RW 5-23	Name:	RUNWAY 5-23	Use:	RUNWAY	Area:	389,600 SqFt		
Section:	6110	of	2	From:	-	To:	-	Last Const.:	1/1/2019
Surface:	AAC	Family:	C9N59-RL-RW-AAC-APC	Zone:		Category:		Rank:	P
Area:	25,800 SqFt	Length:	258 Ft	Width:	100 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1942	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1971	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1991	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2005	Work Type:	MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True		
Work Date:	1/1/2019	Work Type:	MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True		
Last Insp. Date: 2/26/2015									
TotalSamples: 4									
Surveyed: 1									
Conditions:	PCI: 60	NOTE: *** Pre-Construction PCI ***							
Inspection Comments:									
Sample Number:	179	Type:	R	Area:	5000.00 SqFt	PCI:	60		
Sample Comments:									
48	LONGITUDINAL/TRANSVERSE CRACKING	L	735.00	Ft					
57	WEATHERING	L	4750.00	SqFt					
56	SWELLING	L	21.00	SqFt					
52	RAVELING	L	250.00	SqFt					

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TL A3	Name:	TAXILANE A3	Use:	TAXILANE	Area:	88,203 SqFt		
Section:	155	of	2	From:	-	To:	-	Last Const.:	1/1/2007
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	19,174 SqFt	Length:	550 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2007	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	5/1/2019	TotalSamples:	5	Surveyed:	1				
Conditions:	PCI:	79							
Inspection Comments:									
Sample Number:	103	Type:	R	Area:	3603.00 SqFt	PCI:	79		
Sample Comments:									
56	SWELLING	L	5.00	SqFt					
48	L & T CR	L	94.00	Ft					
52	RAVELING	L	350.00	SqFt					
57	WEATHERING	L	3253.00	SqFt					

Network:	CRG	Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT			
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	118,791 SqFt
Section:	105	of 3	From:	-	To:	-	Last Const.: 1/1/2010
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:	Category:		Rank: P
Area:	74,656 SqFt	Length:	2,300 Ft	Width:	35 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1971	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2010	Work Type: MILL and OVERLAY			Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	5/1/2019	TotalSamples:	20	Surveyed:	4		
Conditions:	PCI: 57						
Inspection Comments:							
Sample Number:	146	Type:	R	Area:	3500.00 SqFt	PCI:	60
Sample Comments:							
56	SWELLING	L	35.00	SqFt			
48	L & T CR	L	456.00	Ft			
57	WEATHERING	L	3325.00	SqFt			
52	RAVELING	L	175.00	SqFt			
Sample Number:	150	Type:	R	Area:	3180.00 SqFt	PCI:	57
Sample Comments:							
48	L & T CR	M	97.00	Ft			
56	SWELLING	L	120.00	SqFt			
52	RAVELING	L	159.00	SqFt			
57	WEATHERING	L	3021.00	SqFt			
48	L & T CR	L	307.00	Ft			
Sample Number:	158	Type:	R	Area:	3500.00 SqFt	PCI:	53
Sample Comments:							
48	L & T CR	L	450.00	Ft			
56	SWELLING	L	200.00	SqFt			
57	WEATHERING	L	3325.00	SqFt			
52	RAVELING	L	175.00	SqFt			
48	L & T CR	M	106.00	Ft			
Sample Number:	160	Type:	R	Area:	4035.00 SqFt	PCI:	56
Sample Comments:							
56	SWELLING	L	210.00	SqFt			
52	RAVELING	L	404.00	SqFt			
48	L & T CR	L	431.00	Ft			
57	WEATHERING	L	3631.00	SqFt			
48	L & T CR	M	60.00	Ft			

Network:	CRG		Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW A		Name:		TAXIWAY A		Use:	TAXIWAY	Area:	118,791 SqFt	
Section:	110		of 3		From: -		To: -		Last Const.: 1/1/2019		
Surface:	AAC		Family:		C9N59-RL-TW-AAC-APC		Zone:		Category:		Rank: P
Area:	6,423 SqFt		Length:		120 Ft		Width:		50 Ft		
Slabs:			Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:			Street Type:				Grade: 0		Lanes: 0		
Section Comments:											
Work Date:	1/1/1971		Work Type: BUILT					Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1991		Work Type: OVERLAY					Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/2005		Work Type: MILL and OVERLAY					Code:	ML-OV		Is Major M&R: True
Work Date:	1/1/2019		Work Type: MILL and OVERLAY					Code:	ML-OV		Is Major M&R: True
Last Insp. Date:	2/26/2015		TotalSamples:		24		Surveyed: 4				
Conditions:	PCI: 65		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	146		Type:	R		Area:		3500.00 SqFt		PCI:	71
Sample Comments:											
48	LONGITUDINAL/TRANSVERSE CRACKING		L	255.00 Ft							
57	WEATHERING		L	3325.00 SqFt							
52	RAVELING		L	175.00 SqFt							
Sample Number:	153		Type:	R		Area:		3500.00 SqFt		PCI:	69
Sample Comments:											
52	RAVELING		L	350.00 SqFt							
56	SWELLING		L	22.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	246.00 Ft							
57	WEATHERING		L	3150.00 SqFt							
Sample Number:	161		Type:	R		Area:		3500.00 SqFt		PCI:	56
Sample Comments:											
56	SWELLING		L	26.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		M	16.00 Ft							
52	RAVELING		L	175.00 SqFt							
57	WEATHERING		L	3325.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	440.00 Ft							
Sample Number:	163		Type:	R		Area:		3500.00 SqFt		PCI:	64
Sample Comments:											
57	WEATHERING		L	2975.00 SqFt							
52	RAVELING		L	525.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	344.00 Ft							
56	SWELLING		L	40.00 SqFt							

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	118,791 SqFt		
Section:	120 of 3		From:	-		To:	-		Last Const.:	1/1/2005	
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Rank:	P	
Area:	37,712 SqFt		Length:	2,120 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2005		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	10		Surveyed:	3				
Conditions:	PCI: 72										
Inspection Comments:											
Sample Number:	214		Type:	R		Area:	3500.00 SqFt		PCI:	77	
Sample Comments:											
52	RAVELING		L	1100.00 SqFt							
57	WEATHERING		M	2400.00 SqFt							
Sample Number:	216		Type:	R		Area:	3500.00 SqFt		PCI:	62	
Sample Comments:											
52	RAVELING		L	1100.00 SqFt							
57	WEATHERING		M	2400.00 SqFt							
42	BLEEDING		N	215.00 SqFt							
Sample Number:	219		Type:	R		Area:	3500.00 SqFt		PCI:	76	
Sample Comments:											
57	WEATHERING		M	2000.00 SqFt							
52	RAVELING		L	1500.00 SqFt							

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY	Area:	22,201 SqFt			
Section:	130	of	1	From:	-	To:	-	Last Const.:	1/1/2005			
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	S		
Area:	22,201 SqFt		Length:	425 Ft		Width:	30 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:		Street Type:		Grade:	0		Lanes:	0				
Section Comments:												
Work Date:	1/1/2005			Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/1/2019			TotalSamples:	5			Surveyed:	1			
Conditions:	PCI:	84										
Inspection Comments:												
Sample Number:	501	Type:	R	Area:	3500.00 SqFt			PCI:	84			
Sample Comments:												
52	RAVELING	L	200.00 SqFt									
48	L & T CR	L	19.00 Ft									
57	WEATHERING	L	3300.00 SqFt									

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	TW A2	Name:	TAXIWAY A2	Use:	TAXIWAY	Area:	9,177 SqFt
Section:	132	of 2	From:	-	To:	-	Last Const.: 1/1/2010
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	3,131 SqFt	Length:	60 Ft	Width:	35 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:	Street Type:	Grade:	0	Lanes:	0		
Section Comments:							
Work Date:	1/1/1991	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2010	Work Type:	MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1		
Conditions:	PCI: 69						
Inspection Comments:							
Sample Number:	700	Type:	R	Area:	3131.00 SqFt	PCI:	69
Sample Comments:							
48	L & T CR	L	62.00 Ft				
57	WEATHERING	L	2663.00 SqFt				
50	PATCHING	L	385.00 SqFt				
52	RAVELING	L	83.00 SqFt				

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY	Area:	9,177 SqFt		
Section:	135	of	2	From:	-	To:	-	Last Const.:	1/1/1991		
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	6,046 SqFt		Length:	145 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1991		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI:	57									
Inspection Comments:											
Sample Number:	701	Type:	R	Area:	6046.00 SqFt		PCI:	57			
Sample Comments:											
52	RAVELING	L	1209.00	SqFt							
57	WEATHERING	M	4837.00	SqFt							
56	SWELLING	L	75.00	SqFt							
48	L & T CR	L	645.00	Ft							
48	L & T CR	M	165.00	Ft							

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW A3		Name:	TAXIWAY A3		Use:	TAXIWAY		Area:	22,579 SqFt	
Section:	142 of 3		From:	-			To:	-		Last Const.:	1/1/2019
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank: P		
Area:	13,123 SqFt		Length:	247 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	1/1/2001		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	1/1/2005		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True	
Work Date:	1/1/2019		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R: True	
Last Insp. Date:	2/26/2015		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI: 68		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	103		Type:	R		Area:	3586.00 SqFt		PCI:	68	
Sample Comments:											
52	RAVELING		L	1168.00 SqFt							
57	WEATHERING		L	1753.00 SqFt							
50	PATCHING		L	665.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	5.00 Ft							

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW A3	Name:	TAXIWAY A3	Use:	TAXIWAY	Area:	22,579 SqFt		
Section:	145	of	3	From:	-	To:	-	Last Const.:	1/1/2001
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	4,606 SqFt	Length:	132 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2001	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI:	72							
Inspection Comments:									
Sample Number:	103	Type:	R	Area:	4606.00 SqFt	PCI:	72		
Sample Comments:									
57	WEATHERING	M	4145.00	SqFt					
52	RAVELING	L	461.00	SqFt					
48	L & T CR	L	16.00	Ft					

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW A3		Name:	TAXIWAY A3		Use:	TAXIWAY	Area:	22,579 SqFt		
Section:	150 of 3		From:	-		To:	-		Last Const.:	1/1/2010	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:	P	
Area:	4,850 SqFt		Length:	85 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2001		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 81										
Inspection Comments:											
Sample Number:	104		Type:	R		Area:	4850.00 SqFt		PCI:	81	
Sample Comments:											
52	RAVELING		L		243.00 SqFt						
57	WEATHERING		L		4607.00 SqFt						
42	BLEEDING		N		1.00 SqFt						
48	L & T CR		L		121.00 Ft						

Network:	CRG	Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT			
Branch:	TW A4	Name:	TAXIWAY A4	Use:	TAXIWAY	Area:	10,284 SqFt
Section:	160	of 2	From:	-	To:	-	Last Const.: 1/1/2010
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	5,193 SqFt	Length:	100 Ft	Width:	40 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:	Street Type:	Grade:	0	Lanes:	0		
Section Comments:							
Work Date:	1/1/1971	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2010	Work Type: MILL and OVERLAY			Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1		
Conditions:	PCI: 66						
Inspection Comments:							
Sample Number:	100	Type:	R	Area:	5193.00 SqFt	PCI:	66
Sample Comments:							
52	RAVELING	L	275.00 SqFt				
48	L & T CR	M	72.00 Ft				
57	WEATHERING	L	4918.00 SqFt				
48	L & T CR	L	332.00 Ft				
56	SWELLING	L	25.00 SqFt				

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	TW A4	Name:	TAXIWAY A4	Use:	TAXIWAY	Area:	10,284 SqFt
Section:	165	of 2	From:	-	To:	-	Last Const.: 7/1/2018
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	5,091 SqFt	Length:	100 Ft	Width:	40 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:	Grade:	0	Lanes:	0	
Section Comments:							
Work Date:	1/1/1983	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	7/1/2018	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Last Insp. Date:	2/26/2015	TotalSamples:	1	Surveyed:	1		
Conditions:	PCI: 36	NOTE: *** Pre-Construction PCI ***					
Inspection Comments:							
Sample Number:	101	Type:	R	Area:	5091.00 SqFt	PCI:	36
Sample Comments:							
52	RAVELING	M	1018.00	SqFt			
43	BLOCK CRACKING	M	2545.00	SqFt			
43	BLOCK CRACKING	L	2546.00	SqFt			
52	RAVELING	L	4073.00	SqFt			

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW A5	Name:	TAXIWAY A5	Use:	TAXIWAY	Area:	31,739 SqFt		
Section:	170	of	4	From:	-	To:	-	Last Const.:	7/1/2018
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	5,011 SqFt	Length:	100 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1983	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	7/1/2018	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True		
Last Insp. Date:	2/26/2015	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI: 41	NOTE:	*** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	201	Type:	R	Area:	5011.00 SqFt	PCI:	41		
Sample Comments:									
52	RAVELING	L	4009.00	SqFt					
52	RAVELING	M	1002.00	SqFt					
43	BLOCK CRACKING	L	5011.00	SqFt					
53	RUTTING	L	16.00	SqFt					

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW A5	Name:	TAXIWAY A5	Use:	TAXIWAY	Area:	31,739 SqFt		
Section:	175	of	4	From:	-	To:	-	Last Const.:	1/1/2010
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	5,069 SqFt	Length:	100 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1971	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1991	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2010	Work Type:	MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True		
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI: 55								
Inspection Comments:									
Sample Number:	200	Type:	R	Area:	5069.00 SqFt	PCI:	55		
Sample Comments:									
56	SWELLING	L	150.00	SqFt					
42	BLEEDING	N	24.00	SqFt					
52	RAVELING	L	252.00	SqFt					
57	WEATHERING	L	4817.00	SqFt					
48	L & T CR	M	73.00	Ft					
48	L & T CR	L	307.00	Ft					
45	DEPRESSION	L	40.00	SqFt					

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT					
Branch:	TW A5	Name:	TAXIWAY A5		Use:	TAXIWAY	Area:	31,739 SqFt
Section:	180	of 4	From:	-	To:	-	Last Const.:	1/1/2010
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:	Rank:	P
Area:	8,126 SqFt	Length:	202 Ft	Width:	40 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1971	Work Type: BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1991	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2010	Work Type: MILL and OVERLAY			Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	5/1/2019	TotalSamples:	2	Surveyed:	1			
Conditions:	PCI: 64							
Inspection Comments:								
Sample Number:	203	Type:	R	Area:	3500.00 SqFt	PCI:	64	
Sample Comments:								
45	DEPRESSION	L	32.00 SqFt					
56	SWELLING	L	100.00 SqFt					
48	L & T CR	L	207.00 Ft					
52	RAVELING	L	70.00 SqFt					
57	WEATHERING	L	3430.00 SqFt					

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT									
Branch:	TW A5		Name:	TAXIWAY A5		Use:	TAXIWAY		Area:	31,739 SqFt				
Section:	185		of	4		From:	-		To:	-		Last Const.:	1/1/2019	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	13,533 SqFt		Length:	257 Ft		Width:	50 Ft							
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:			Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0					
Section Comments:														
Work Date:	1/1/1971		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True			
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True			
Work Date:	1/1/2005		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True			
Work Date:	1/1/2019		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True			
Last Insp. Date:	2/26/2015		TotalSamples:	5		Surveyed:	1							
Conditions:	PCI: 89		NOTE: *** Pre-Construction PCI ***											
Inspection Comments:														
Sample Number:	201		Type:	R		Area:	3500.00 SqFt		PCI:	89				
Sample Comments:														
48	LONGITUDINAL/TRANSVERSE CRACKING		L	35.00 Ft										
57	WEATHERING		L	3500.00 SqFt										

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	125,831 SqFt			
Section:	215	of	5	From:	-			To:	-		Last Const.:	1/1/2005
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:				Category:	Rank: P		
Area:	29,838 SqFt		Length:	2,120 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft			Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0			Lanes:	0	
Section Comments:												
Work Date:	1/1/2005		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:	5/1/2019		TotalSamples:	8		Surveyed:	1					
Conditions:	PCI:	77										
Inspection Comments:												
Sample Number:	106	Type:	R	Area:	3500.00 SqFt			PCI:	77			
Sample Comments:												
52	RAVELING	L	1100.00 SqFt									
42	BLEEDING	N	5.00 SqFt									
57	WEATHERING	M	2400.00 SqFt									

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	125,831 SqFt		
Section:	225	of	5	From:	-	To:	-	Last Const.:	1/1/2010		
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P		
Area:	59,500 SqFt		Length:	1,555 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:			Grade:		0	Lanes:		0		
Section Comments:											
Work Date:	1/1/1991		Work Type:			New Construction - Initial		Code:	NU-IN	Is Major M&R:	True
Work Date:	1/1/2010		Work Type:			MILL and OVERLAY		Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	16		Surveyed:		4			
Conditions:	PCI:		55								
Inspection Comments:											
Sample Number:	109		Type:	R		Area:	4900.00 SqFt		PCI:	56	
Sample Comments:											
57	WEATHERING		L	4655.00 SqFt							
48	L & T CR		M	32.00 Ft							
56	SWELLING		L	40.00 SqFt							
48	L & T CR		L	626.00 Ft							
42	BLEEDING		N	2.00 SqFt							
52	RAVELING		L	245.00 SqFt							
Sample Number:	114		Type:	R		Area:	3500.00 SqFt		PCI:	61	
Sample Comments:											
57	WEATHERING		L	3325.00 SqFt							
52	RAVELING		L	175.00 SqFt							
48	L & T CR		L	463.00 Ft							
56	SWELLING		L	25.00 SqFt							
Sample Number:	120		Type:	R		Area:	3500.00 SqFt		PCI:	44	
Sample Comments:											
52	RAVELING		L	173.00 SqFt							
48	L & T CR		M	30.00 Ft							
50	PATCHING		L	41.00 SqFt							
56	SWELLING		L	135.00 SqFt							
57	WEATHERING		L	3286.00 SqFt							
48	L & T CR		L	659.00 Ft							
Sample Number:	124		Type:	R		Area:	5600.00 SqFt		PCI:	57	
Sample Comments:											
48	L & T CR		L	975.00 Ft							
52	RAVELING		L	280.00 SqFt							
56	SWELLING		L	29.00 SqFt							
57	WEATHERING		L	5320.00 SqFt							

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW B	Name:	TAXIWAY B	Use:	TAXIWAY	Area:	125,831 SqFt		
Section:	227	of	5	From:	-	To:	-	Last Const.:	1/1/2003
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	5,899 SqFt	Length:	170 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/25/1991	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2003	Work Type:	MILL and OVERLAY		Code:	ML-OV	Is Major M&R:	True	
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI:	70							
Inspection Comments:									
Sample Number:	125	Type:	R	Area:	5899.00 SqFt	PCI:	70		
Sample Comments:									
48	L & T CR	L	303.00	Ft					
52	RAVELING	L	295.00	SqFt					
57	WEATHERING	M	5604.00	SqFt					
42	BLEEDING	N	9.00	SqFt					

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW B	Name:	TAXIWAY B		Use:	TAXIWAY	Area:	125,831 SqFt	
Section:	230	of 5	From:	-	To:	-	Last Const.:	1/1/2011	
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:	Rank:	P	
Area:	3,679 SqFt	Length:	135 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:	This apron was removed and relocated on 2005.								
Work Date:	1/1/1991	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2003	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Work Date:	1/1/2011	Work Type:	MILL and OVERLAY			Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI: 81								
Inspection Comments:									
Sample Number:	132	Type:	R	Area:	3679.00 SqFt	PCI:	81		
Sample Comments:									
57	WEATHERING	L	3385.00 SqFt						
48	L & T CR	L	41.00 Ft						
57	WEATHERING	M	184.00 SqFt						
52	RAVELING	L	110.00 SqFt						

Network:		CRG		Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT													
Branch:		TW B		Name:		TAXIWAY B		Use:		TAXIWAY		Area:		125,831 SqFt					
Section:		235		of		5		From:		-		To:		-		Last Const.:		1/1/2003	
Surface:		AC		Family:		C9N59-RL-TW-AC		Zone:				Category:				Rank:		T	
Area:		26,915 SqFt		Length:		700 Ft		Width:		35 Ft									
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft							
Shoulder:		Street Type:		Grade:		0		Lanes:		0									
Section Comments:		This apron was removed and relocated on 2005.																	
Work Date:		1/1/1991		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		1/1/2003		Work Type:		Complete Reconstruction - AC		Code:		CR-AC		Is Major M&R:		True					
Last Insp. Date:		5/1/2019		TotalSamples:		7		Surveyed:		2									
Conditions:		PCI:		68															
Inspection Comments:																			
Sample Number:		126		Type:		R		Area:		4200.00 SqFt		PCI:		68					
Sample Comments:																			
45		DEPRESSION		L		150.00 SqFt													
57		WEATHERING		M		3400.00 SqFt													
48		L & T CR		L		12.00 Ft													
42		BLEEDING		N		4.00 SqFt													
52		RAVELING		L		800.00 SqFt													
Sample Number:		130		Type:		R		Area:		3343.00 SqFt		PCI:		69					
Sample Comments:																			
48		L & T CR		L		59.00 Ft													
57		WEATHERING		M		1593.00 SqFt													
52		RAVELING		L		1750.00 SqFt													

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW B1		Name:	TAXIWAY B1		Use:	TAXIWAY	Area:	7,110 SqFt		
Section:	210	of	1	From:	-	To:	-	Last Const.:	12/25/1994		
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	7,110 SqFt		Length:	163 Ft		Width:	40 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	12/25/1994		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	59									
Inspection Comments:											
Sample Number:	302	Type:	R	Area:	4000.00 SqFt		PCI:	59			
Sample Comments:											
48	L & T CR		L	345.00	Ft						
52	RAVELING		L	1000.00	SqFt						
56	SWELLING		L	225.00	SqFt						
48	L & T CR		M	86.00	Ft						
57	WEATHERING		L	3000.00	SqFt						

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	26,899 SqFt		
Section:	220 of 4		From:	-		To:	-		Last Const.:	1/1/2011	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	3,863 SqFt		Length:	175 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2003		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/2011		Work Type:	MILL and OVERLAY			Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 81										
Inspection Comments:											
Sample Number:	500		Type:	R		Area:	3863.00 SqFt		PCI:	81	
Sample Comments:											
57	WEATHERING		L	3090.00 SqFt							
57	WEATHERING		M	773.00 SqFt							
48	L & T CR		L	35.00 Ft							

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	26,899 SqFt		
Section:	240	of	4	From:	-	To:	-	Last Const.:	1/1/2003		
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	S	
Area:	11,812 SqFt		Length:	335 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2003		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	3		Surveyed:	1				
Conditions:	PCI:	69									
Inspection Comments:											
Sample Number:	502	Type:	R	Area:	3325.00 SqFt		PCI:	69			
Sample Comments:											
42	BLEEDING	N	1.00 SqFt								
57	WEATHERING	M	1290.00 SqFt								
52	RAVELING	L	1800.00 SqFt								
48	L & T CR	L	67.00 Ft								

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW B2	Name:	TAXIWAY B2	Use:	TAXIWAY	Area:	26,899 SqFt		
Section:	242	of	4	From:	-	To:	-	Last Const.:	1/1/2010
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	4,802 SqFt	Length:	75 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2003	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2010	Work Type:	MILL and OVERLAY		Code:	ML-OV	Is Major M&R:	True	
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI:	82							
Inspection Comments:									
Sample Number:	504	Type:	R	Area:	4803.00 SqFt	PCI:	82		
Sample Comments:									
57	WEATHERING	L	4467.00	SqFt					
57	WEATHERING	M	336.00	SqFt					
48	L & T CR	L	111.00	Ft					

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT					
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	26,899 SqFt	
Section:	243	of 4	From:	-			To:	-	Last Const.: 12/25/1994	
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:				Category:	Rank: S	
Area:	6,422 SqFt		Length:	180 Ft		Width:	35 Ft			
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	12/24/1994		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True
Work Date:	12/25/1994		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R: True
Last Insp. Date:	5/1/2019		TotalSamples:	1		Surveyed: 1				
Conditions:	PCI: 42									
Inspection Comments:										
Sample Number:	098		Type:	R		Area:	6422.00 SqFt		PCI:	42
Sample Comments:										
57	WEATHERING		M	1164.00 SqFt						
56	SWELLING		L	466.00 SqFt						
43	BLOCK CR		L	4657.00 SqFt						
53	RUTTING		L	63.00 SqFt						
52	RAVELING		L	3493.00 SqFt						
50	PATCHING		L	1765.00 SqFt						

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW B3		Name:	TAXIWAY B3		Use:	TAXIWAY	Area:	3,380 SqFt		
Section:	244 of 1		From:	-		To:	-		Last Const.:	1/1/2010	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:	Category:		Rank:	P	
Area:	3,380 SqFt		Length:	55 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	12/25/1999		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 70										
Inspection Comments:											
Sample Number:	205		Type:	R		Area:	3385.00 SqFt		PCI:	70	
Sample Comments:											
42	BLEEDING		N	4.00 SqFt							
48	L & T CR		L	215.00 Ft							
57	WEATHERING		L	3216.00 SqFt							
56	SWELLING		L	30.00 SqFt							
52	RAVELING		L	169.00 SqFt							

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	TW B4	Name:	TAXIWAY B4	Use:	TAXIWAY	Area:	27,651 SqFt
Section:	245	of 3	From:	-	To:	-	Last Const.: 1/2/1984
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:	Rank: P
Area:	9,056 SqFt	Length:	175 Ft	Width:	40 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1984	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/2/1984	Work Type: Overlay - AC Structural			Code:	OL-AS	Is Major M&R: True
Last Insp. Date:	5/1/2019	TotalSamples:	2	Surveyed:	1		
Conditions:	PCI: 31						
Inspection Comments:							
Sample Number:	407	Type:	R	Area:	4529.00 SqFt	PCI:	31
Sample Comments:							
52	RAVELING	L	1832.00	SqFt			
41	ALLIGATOR CR	L	52.00	SqFt			
48	L & T CR	L	5.00	Ft			
56	SWELLING	L	300.00	SqFt			
43	BLOCK CR	L	2213.00	SqFt			
43	BLOCK CR	M	2000.00	SqFt			
57	WEATHERING	M	2697.00	SqFt			
48	L & T CR	M	18.00	Ft			

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	TW B4	Name:	TAXIWAY B4	Use:	TAXIWAY	Area:	27,651 SqFt
Section:	250	of 3	From:	-	To:	-	Last Const.: 1/1/2010
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	15,426 SqFt	Length:	405 Ft	Width:	35 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:	Grade:	0	Lanes:	0	
Section Comments:							
Work Date:	1/1/1971	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R: True
Work Date:	1/2/1971	Work Type:	Overlay - AC Structural		Code:	OL-AS	Is Major M&R: True
Work Date:	1/1/1991	Work Type:	OVERLAY		Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2010	Work Type:	MILL and OVERLAY		Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	5/1/2019	TotalSamples:	4	Surveyed:	1		
Conditions:	PCI: 67						
Inspection Comments:							
Sample Number:	402	Type:	R	Area:	3500.00 SqFt	PCI:	67
Sample Comments:							
57	WEATHERING	M	175.00 SqFt				
43	BLOCK CR	L	190.00 SqFt				
48	L & T CR	L	196.00 Ft				
56	SWELLING	L	50.00 SqFt				
57	WEATHERING	L	3325.00 SqFt				

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	TW B4	Name:	TAXIWAY B4	Use:	TAXIWAY	Area:	27,651 SqFt
Section:	265	of 3	From:	-	To:	-	Last Const.: 1/1/2011
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	3,169 SqFt	Length:	150 Ft	Width:	50 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:	Street Type:	Grade:	0	Lanes:	0		
Section Comments:							
Work Date:	1/1/1971	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R: True
Work Date:	1/2/1971	Work Type:	Overlay - AC Structural		Code:	OL-AS	Is Major M&R: True
Work Date:	1/1/1991	Work Type:	OVERLAY		Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2011	Work Type:	MILL and OVERLAY		Code:	ML-OV	Is Major M&R: True
Last Insp. Date:	5/1/2019	TotalSamples:	1	Surveyed:	1		
Conditions:	PCI: 80						
Inspection Comments:							
Sample Number:	400	Type:	R	Area:	3169.00 SqFt	PCI:	80
Sample Comments:							
57	WEATHERING	M	158.00 SqFt				
48	L & T CR	L	119.00 Ft				
57	WEATHERING	L	3011.00 SqFt				

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT									
Branch:	TW B5		Name:	TAXIWAY B5		Use:	TAXIWAY	Area:	9,978 SqFt					
Section:	255		of	2		From:	-		To:	-		Last Const.:	1/1/1991	
Surface:	AC		Family:	C9N59-RL-TW-AC		Zone:			Category:			Rank:	P	
Area:	4,433 SqFt		Length:	210 Ft		Width:	40 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1991			Work Type:	BUILT			Code:	IMPORTED			Is Major M&R:	True	
Last Insp. Date:	5/1/2019			TotalSamples:	1			Surveyed:	1					
Conditions:	PCI:		51											
Inspection Comments:														
Sample Number:	101		Type:	R		Area:	4433.00 SqFt		PCI:	51				
Sample Comments:														
48	L & T CR		M	42.00 Ft										
56	SWELLING		L	393.00 SqFt										
57	WEATHERING		L	3325.00 SqFt										
48	L & T CR		L	680.00 Ft										
52	RAVELING		L	1108.00 SqFt										

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW B5		Name:	TAXIWAY B5		Use:	TAXIWAY	Area:	9,978 SqFt			
Section:	260	of	2	From:	-	To:	-	Last Const.:	1/1/2005			
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:		Category:		Rank:	P		
Area:	5,545 SqFt		Length:	2,120 Ft		Width:	35 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:		Street Type:			Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	1/1/2005			Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/1/2019			TotalSamples:	1			Surveyed:	1			
Conditions:	PCI:	80										
Inspection Comments:												
Sample Number:	100	Type:	R	Area:	5545.00 SqFt			PCI:	80			
Sample Comments:												
42	BLEEDING	N	30.00	SqFt								
45	DEPRESSION	L	4.00	SqFt								
48	L & T CR	L	30.00	Ft								
57	WEATHERING	L	5245.00	SqFt								
52	RAVELING	L	300.00	SqFt								

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	TW C	Name:	TAXIWAY C	Use:	TAXIWAY	Area:	46,913 SqFt
Section:	305	of 3	From:	-	To:	-	Last Const.: 1/1/2019
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	24,696 SqFt	Length:	400 Ft	Width:	60 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:	Street Type:	Grade:	0	Lanes:	0		
Section Comments:	Part of this section was removed on 2005						
Work Date:	1/1/1942	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1971	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1991	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2019	Work Type:	MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True
Last Insp. Date:	2/26/2015	TotalSamples:	4	Surveyed:	1		
Conditions:	PCI: 42	NOTE: *** Pre-Construction PCI ***					
Inspection Comments:							
Sample Number:	304	Type:	R	Area:	2481.00 SqFt	PCI:	42
Sample Comments:							
56	SWELLING	L	126.00 SqFt				
56	SWELLING	L	58.00 SqFt				
48	LONGITUDINAL/TRANSVERSE CRACKING	M	182.00 Ft				
52	RAVELING	L	2481.00 SqFt				
48	LONGITUDINAL/TRANSVERSE CRACKING	L	356.00 Ft				

Network:	CRG		Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	46,913 SqFt		
Section:	310 of 3		From:	-		To:	-		Last Const.:	1/1/2019	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Rank:	P	
Area:	5,648 SqFt		Length:	40 Ft		Width:	136 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1991		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2005		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Work Date:	1/1/2019		Work Type: MILL and OVERLAY				Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	2/26/2015		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI:	56	NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	300		Type:	R		Area:	5560.00 SqFt		PCI:	56	
Sample Comments:											
57	WEATHERING		L	4923.00 SqFt							
52	RAVELING		L	259.00 SqFt							
56	SWELLING		L	34.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	54.00 Ft							
48	LONGITUDINAL/TRANSVERSE CRACKING		M	17.00 Ft							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	433.00 Ft							
50	PATCHING		L	378.00 SqFt							

Network: CRG		Name: JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT	
Branch: TW C	Name: TAXIWAY C	Use: TAXIWAY	Area: 46,913 SqFt
Section: 320	of 3	From: -	To: -
Surface: AAC	Family: C9N59-RL-TW-AAC-APC	Zone:	Category: Rank: P
Area: 16,569 SqFt	Length: 209 Ft	Width: 80 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments: Part of this section was removed on 2005			
Work Date: 1/1/1942	Work Type: BUILT	Code: IMPORTED	Is Major M&R: True
Work Date: 1/1/1971	Work Type: OVERLAY	Code: IMPORTED	Is Major M&R: True
Work Date: 1/1/1991	Work Type: OVERLAY	Code: IMPORTED	Is Major M&R: True
Work Date: 12/25/2010	Work Type: MILL and OVERLAY	Code: ML-OV	Is Major M&R: True
Last Insp. Date: 5/1/2019	TotalSamples: 4	Surveyed: 1	
Conditions: PCI: 57			
Inspection Comments:			
Sample Number: 405	Type: R	Area: 3960.00 SqFt	PCI: 57
Sample Comments:			
52	RAVELING	L	450.00 SqFt
56	SWELLING	L	45.00 SqFt
48	L & T CR	M	20.00 Ft
42	BLEEDING	N	2.00 SqFt
48	L & T CR	L	120.00 Ft
50	PATCHING	L	720.00 SqFt
57	WEATHERING	L	2790.00 SqFt

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT				
Branch:	TW D	Name:	TAXIWAY D	Use:	TAXIWAY	Area:	41,302 SqFt
Section:	455	of 2	From:	-	To:	-	Last Const.: 1/1/2005
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:	Rank: P
Area:	12,087 SqFt	Length:	495 Ft	Width:	35 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1970	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R: True
Work Date:	1/1/1991	Work Type: Overlay - AC Structural			Code:	OL-AS	Is Major M&R: True
Work Date:	1/1/2005	Work Type: Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R: True
Last Insp. Date:	5/1/2019	TotalSamples:	3	Surveyed: 1			
Conditions:	PCI: 80						
Inspection Comments:							
Sample Number:	402	Type:	R	Area:	4790.00 SqFt	PCI:	80
Sample Comments:							
56	SWELLING	L	132.00 SqFt				
57	WEATHERING	L	4742.00 SqFt				
48	L & T CR	L	95.00 Ft				
52	RAVELING	L	48.00 SqFt				

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	41,302 SqFt		
Section:	460	of	2	From:	-		To:	-		Last Const.:	1/1/2005
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:			Category:	Rank: P		
Area:	29,215 SqFt		Length:	360 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	12/25/1999		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/2005		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	8		Surveyed:	2				
Conditions:	PCI: 78										
Inspection Comments:											
Sample Number:	407	Type:	R	Area:	3500.00 SqFt		PCI:	79			
Sample Comments:											
52	RAVELING	L	35.00 SqFt								
48	L & T CR	L	146.00 Ft								
57	WEATHERING	L	3465.00 SqFt								
Sample Number:	410	Type:	R	Area:	3500.00 SqFt		PCI:	77			
Sample Comments:											
48	L & T CR	L	109.00 Ft								
52	RAVELING	L	180.00 SqFt								
57	WEATHERING	L	3320.00 SqFt								
56	SWELLING	L	26.00 SqFt								

Network:	CRG			Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY		Area:	14,164 SqFt	
Section:	505 of 1		From:	-		To:	-		Last Const.:	1/1/2019	
Surface:	AAC		Family:	C9N59-RL-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	14,164 SqFt		Length:	270 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1991		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2019		Work Type:	MILL and OVERLAY			Code:	ML-OV		Is Major M&R:	True
Last Insp. Date:	2/26/2015		TotalSamples:	3		Surveyed:	1				
Conditions:	PCI: 60		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	501		Type:	R		Area:	3533.00 SqFt		PCI:	60	
Sample Comments:											
52	RAVELING		M	805.00 SqFt							
52	RAVELING		L	1413.00 SqFt							
48	LONGITUDINAL/TRANSVERSE CRACKING		L	233.00 Ft							

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW F	Name:	TAXIWAY F	Use:	TAXIWAY	Area:	15,194 SqFt			
Section:	605	of 2	From:	-	To:	-	Last Const.:	1/1/2019		
Surface:	AAC	Family:	C9N59-RL-TW-AAC-APC	Zone:		Category:		Rank:	P	
Area:	9,632 SqFt	Length:	164 Ft	Width:	60 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0			
Section Comments:										
Work Date:	1/1/1991	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True	
Work Date:	1/1/2019	Work Type:			MILL and OVERLAY	Code:	ML-OV	Is Major M&R:	True	
Last Insp. Date:	2/26/2015	TotalSamples:	3	Surveyed:						1
Conditions:	PCI: 61	NOTE: *** Pre-Construction PCI ***								
Inspection Comments:										
Sample Number:	601	Type:	R	Area:	3500.00 SqFt	PCI:	61			
Sample Comments:										
52	RAVELING	M	156.00	SqFt						
48	LONGITUDINAL/TRANSVERSE CRACKING	L	240.00	Ft						
52	RAVELING	L	2675.00	SqFt						
48	LONGITUDINAL/TRANSVERSE CRACKING	M	52.00	Ft						

Network:	CRG	Name:		JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT							
Branch:	TW G	Name:	TAXIWAY G		Use:	TAXIWAY	Area:	74,770 SqFt			
Section:	765	of 2	From:	-	To:	-	Last Const.:	1/1/2003			
Surface:	AC	Family:	C9N59-RL-TW-AC		Zone:	Category:	Rank:	P			
Area:	65,079 SqFt	Length:	1,885 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0	Lanes:	0				
Section Comments:											
Work Date:	1/1/1970		Work Type:			New Construction - AC		Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1991		Work Type:			Overlay - AC Structural		Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2003		Work Type:			Complete Reconstruction - AC		Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	5/1/2019		TotalSamples:	18		Surveyed:		3			
Conditions:	PCI: 73										
Inspection Comments:											
Sample Number:	302	Type:	R	Area:	3500.00 SqFt		PCI:	76			
Sample Comments:											
48	L & T CR		L	2.00 Ft							
52	RAVELING		L	1100.00 SqFt							
57	WEATHERING		L	2400.00 SqFt							
Sample Number:	308	Type:	R	Area:	3500.00 SqFt		PCI:	69			
Sample Comments:											
42	BLEEDING		N	8.00 SqFt							
52	RAVELING		L	800.00 SqFt							
48	L & T CR		L	56.00 Ft							
48	L & T CR		M	40.00 Ft							
57	WEATHERING		L	2700.00 SqFt							
Sample Number:	314	Type:	R	Area:	3500.00 SqFt		PCI:	75			
Sample Comments:											
52	RAVELING		L	800.00 SqFt							
48	L & T CR		L	105.00 Ft							
57	WEATHERING		L	2700.00 SqFt							

Network:	CRG	Name:	JACKSONVILLE EXECUTIVE AT CRAIG AIRPORT						
Branch:	TW G	Name:	TAXIWAY G	Use:	TAXIWAY	Area:	74,770 SqFt		
Section:	770	of	2	From:	-	To:	-	Last Const.:	1/1/2004
Surface:	AC	Family:	C9N59-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	9,691 SqFt	Length:	250 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:	This section was removed on 2005								
Work Date:	1/1/1970	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2004	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	5/1/2019	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI: 75								
Inspection Comments:									
Sample Number:	317	Type:	R	Area:	6191.00 SqFt	PCI:	75		
Sample Comments:									
48	L & T CR	L	93.00	Ft					
57	WEATHERING	L	4691.00	SqFt					
52	RAVELING	L	1500.00	SqFt					