

2021

Statewide Airfield Pavement Management Program



# Airport Pavement Evaluation Report

PMP - Pompano Beach Airpark | *District 4*



---

*Florida Department of Transportation*

---

# ***Statewide Airfield Pavement Management Program***

## **Airport Pavement Evaluation Report**

**Prepared by:**

*FDOT Aviation Office  
605 Suwannee Street  
Tallahassee, Florida 32399-0450*

**Website:** [FDOT Aviation Office](#)

**Interactive Web Application:** [FDOT SAPMP Interactive Web Application](#)

# TABLE OF CONTENTS

<b>EXECUTIVE SUMMARY .....</b>	<b>1</b>
<i>Program Background .....</i>	<i>1</i>
<i>Current Pavement Conditions .....</i>	<i>2</i>
<i>Forecasted Pavement Conditions .....</i>	<i>5</i>
<i>Major Rehabilitation Planning 2021-2030 .....</i>	<i>7</i>
 <b>CHAPTER 1 – INTRODUCTION .....</b>	 <b>10</b>
1.1 Background .....	10
1.2 Stakeholders .....	12
1.3 General Scope of Work .....	12
1.4 FDOT SAPMP Objectives .....	13
 <b>CHAPTER 2 – METHODOLOGY .....</b>	 <b>16</b>
2.1 Airfield Pavement Database .....	16
2.2 Airfield Pavement Record Keeping (Historical Records Research) .....	17
2.3 Airfield Pavement Structure .....	17
2.4 Airfield Pavement Traffic .....	19
2.5 Pavement Management Program Network Definition Terminology .....	19
2.5.1 Pavement Network Identification .....	19
2.5.2 Pavement Branch Identification .....	19
2.5.3 Pavement Section Identification .....	20
2.5.4 Pavement Sample Unit Identification .....	20
2.5.5 Terminology Summary .....	20
2.6 Airfield PCI Survey Methodology .....	20
2.6.1 Pavement Distress Types .....	21
2.6.2 PCI Survey Procedures .....	22
 <b>CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY .....</b>	 <b>25</b>
3.1 Airfield Pavement Network Information .....	25
3.1.1 Previous and/or Anticipated Airfield Pavement Construction .....	25
3.1.2 Estimated Pavement Age .....	28
3.1.3 Functional Use .....	30
3.1.4 Pavement Surface Type .....	30
3.1.5 Pavement System Inventory Details .....	31
 <b>CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS .....</b>	 <b>35</b>
4.1 Airfield Pavement Condition Index .....	35
4.1.1 Network-Level Analysis .....	35
4.1.2 Branch-Level Analysis .....	35
4.1.3 Section-Level Analysis .....	38
4.2 Summary of Pavement Condition Evaluation Results .....	42
4.2.1 Network-Level Observations .....	42
4.2.2 Branch-Level Observations .....	42

<b>CHAPTER 5 – SAPMP CUSTOMIZATION</b>	<b>54</b>
<b>5.1 Network-Level Customization</b>	<b>54</b>
<b>5.2 Pavement Condition Forecasts</b>	<b>54</b>
5.2.1 Forecasting PCI Considerations	55
5.2.2 Performance Models	55
5.2.3 Branch-Level Pavement Condition Forecast	55
5.2.4 Section-Level Pavement Condition Forecast	56
<b>5.3 Critical PCI Value</b>	<b>58</b>
<b>5.4 Localized Maintenance and Repair</b>	<b>61</b>
5.4.1 Localized Maintenance and Repair Approach	61
5.4.2 Localized Work Types	62
5.4.3 Localized Maintenance Planning-Level Unit Costs	64
5.4.4 Localized Maintenance and Repair Policy	65
<b>5.5 Major Rehabilitation</b>	<b>70</b>
5.5.1 Major Rehabilitation Pavement Section Development	70
5.5.2 Major Rehabilitation Planning-Level Unit Costs	72
<b>CHAPTER 6 – M&amp;R PLANNING AND BUDGET SCENARIO ANALYSIS</b>	<b>74</b>
<b>6.1 Localized Maintenance and Repair Analysis and Recommendations</b>	<b>74</b>
<b>6.2 Major Rehabilitation Needs</b>	<b>77</b>
6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs	77
<b>CHAPTER 7 – CONCLUSION</b>	<b>82</b>
<b>7.1 Recommendations</b>	<b>82</b>
7.1.1 Continued PCI Surveys	82
7.1.2 Localized Maintenance and Repair	82
7.1.3 Major Rehabilitation	82
7.1.4 Pavement Management System	82
<b>7.2 Supporting Documents</b>	<b>83</b>
Airfield Pavement Network Definition Exhibit	83
Airfield Pavement System Inventory Exhibit	83
Airfield Pavement Estimated Age Exhibit	83
Airfield Pavement Condition Index Exhibit	83
Airfield Pavement Major Rehabilitation Exhibit	83
Inspection Photograph Documentation	83
<b>7.3 Conclusion</b>	<b>84</b>
<b>7.4 References</b>	<b>84</b>



## **APPENDIX**


*Appendix A: Airfield Pavement Analysis*

*Appendix B: Maintenance and Rehabilitation Planning Needs*

*Appendix C: Technical Exhibits*

*Appendix D: Inspection Photograph Documentation*

*Appendix E: Inspection Distress Details*



## LIST OF TABLES

Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level.....	3
Table E.2: Forecasted PCI Values 2021-2030 – Section-Level .....	5
Table E.3: Major Rehabilitation Planning 2021-2030.....	7
Table 1.2: FDOT SAPMP Stakeholders .....	12
Table 2.5.5: SAPMP Terminology .....	20
Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete.....	21
Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete.....	22
Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete.....	22
Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete .....	23
Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction .....	25
Table 3.1.5: Pavement System Inventory Details.....	32
Table 4.1.2: Latest Condition Summary – Branch-Level.....	38
Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level.....	39
Table 5.2.4: Forecasted PCI Values 2021-2030 – Section-Level.....	56
Table 5.3 (a): AIP Handbook PCI Requirements.....	59
Table 5.3 (b): Critical PCI Values by Branch Use.....	59
Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete.....	64
Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete.....	64
Table 5.4.4 (a): Localized Preventive Maintenance and Repair Policy .....	65
Table 5.4.4 (b): Localized Stopgap Maintenance and Repair Policy.....	67
Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation .....	71
Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type.....	72
Table 6.1 (a): Year 1 Summary of Localized Maintenance .....	74
Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary .....	75
Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary.....	75
Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs .....	78



## LIST OF FIGURES

Figure E.1: PCI Rating .....	1
Figure E.2: Latest Condition Summary – Branch-Level .....	2
Figure E.3: Major Rehabilitation Planning Annual Budget 2021-2030 .....	8
Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts .....	11
Figure 1.4: Typical Pavement Condition Life Cycle .....	14
Figure 2: FDOT SAPMP General Process .....	16
Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit .....	26
Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit .....	27
Figure 3.1.2 (a): Age of Pavements at PCI Survey .....	28
Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit .....	29
Figure 3.1.3: Airfield Pavement Branch Use by Area (SF) .....	30
Figure 3.1.4: Airfield Pavement Surface Type by Area (SF) .....	31
Figure 4.1.1: Latest Condition – Overall Network .....	35
Figure 4.1.2 (a): Latest Condition Summary – Branch-Level .....	35
Figure 4.1.2 (b): Latest Condition – Runway .....	36
Figure 4.1.2 (c): Latest Condition – Taxiway .....	36
Figure 4.1.2 (d): Latest Condition – Taxilane .....	37
Figure 4.1.2 (e): Latest Condition – Apron .....	37
Figure 4.1.3: Airfield Pavement Condition Index Exhibit .....	41
Figure 5.2.3: Forecasted Branch-Level Pavement Performance .....	55
Figure 5.3 (a): General Pavement Treatments by Condition Range .....	58
Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical } PCI$ .....	60
Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical } PCI$ .....	60
Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year .....	79
Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit .....	80



# Executive Summary





# Executive Summary

## Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). This work is to be completed from fiscal year 2020 through fiscal year 2021. The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Pompano Beach Airpark's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-12, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section as graphically depicted in **Figure E.1**.


*Figure E.1: PCI Rating*

Color	Range	Condition Rating
	86-100	Good
	71-85	Satisfactory
	56-70	Fair
	41-55	Poor
	26-40	Very Poor
	11-25	Serious
	0-10	Failed

## Current Pavement Conditions

In November 2020, approximately 4.3 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Pompano Beach Airpark (PMP). In general, airfield pavements at PMP are in Satisfactory condition with an area-weighted PCI of 74. The area-weighted average PCI values of the runways, taxiways, taxilanes, and aprons are 76, 77, 40, and 73, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for PMP.

*Figure E.2: Latest Condition Summary – Branch-Level*





*Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	RW 10-28	Runway	6105	271,200	64	Fair
PMP	RW 10-28	Runway	6115	58,320	85	Satisfactory
PMP	RW 15-33	Runway	6305	220,900	89	Good
PMP	RW 15-33	Runway	6310	441,800	90	Good
PMP	RW 15-33	Runway	6325	25,000	82	Satisfactory
PMP	RW 15-33	Runway	6330	50,000	92	Good
PMP	RW 6-24	Runway	6205	335,952	60	Fair
PMP	RW 6-24	Runway	6210	167,976	62	Fair
PMP	RW 6-24	Runway	6220	35,000	91	Good
PMP	RW 6-24	Runway	6225	17,500	91	Good
PMP	TW A	Taxiway	105	61,729	90	Good
PMP	TW A	Taxiway	115	13,967	47	Poor
PMP	TW B	Taxiway	210	104,085	59	Fair
PMP	TW C	Taxiway	305	26,289	64	Fair
PMP	TW C	Taxiway	350	6,807	92	Good
PMP	TW C	Taxiway	360	9,668	92	Good
PMP	TW D	Taxiway	405	90,211	100	Good
PMP	TW D	Taxiway	410	12,212	92	Good
PMP	TW D	Taxiway	412	24,824	83	Satisfactory
PMP	TW D	Taxiway	415	36,063	82	Satisfactory
PMP	TW D	Taxiway	420	20,401	40	Very Poor
PMP	TW E	Taxiway	505	12,246	89	Good
PMP	TW F	Taxiway	610	120,125	59	Fair
PMP	TW F	Taxiway	612	15,275	93	Good
PMP	TW F	Taxiway	615	8,519	95	Good
PMP	TW F	Taxiway	620	8,073	89	Good
PMP	TW G	Taxiway	710	15,387	89	Good
PMP	TW G	Taxiway	715	17,469	90	Good
PMP	TW G	Taxiway	720	151,212	92	Good
PMP	TW G	Taxiway	725	33,591	86	Good
PMP	TW G1	Taxiway	700	21,726	90	Good
PMP	TW G3	Taxiway	730	15,789	93	Good
PMP	TW G4	Taxiway	740	12,199	92	Good
PMP	TW G5	Taxiway	750	16,699	91	Good
PMP	TW K	Taxiway	1110	89,261	92	Good
PMP	TW K	Taxiway	1115	7,373	83	Satisfactory
PMP	TW K	Taxiway	1120	14,097	90	Good
PMP	TW L	Taxiway	1202	21,209	62	Fair
PMP	TW L	Taxiway	1205	13,025	51	Poor
PMP	TW L	Taxiway	1210	152,867	60	Fair
PMP	TW L	Taxiway	1215	14,829	87	Good
PMP	TW M	Taxiway	1305	27,738	68	Fair
PMP	TW M	Taxiway	1306	29,856	81	Satisfactory
PMP	TW M	Taxiway	1310	24,002	82	Satisfactory
PMP	TW M	Taxiway	1315	16,359	69	Fair

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	TW M	Taxiway	1320	69,823	64	Fair
PMP	TW M	Taxiway	1322	30,907	93	Good
PMP	TW M	Taxiway	1325	8,073	90	Good
PMP	TW M	Taxiway	1330	12,988	64	Fair
PMP	TW N	Taxiway	1405	33,887	79	Satisfactory
PMP	TL T-HANG	Taxilane	4305	31,764	36	Very Poor
PMP	TL T-HANG	Taxilane	4310	49,387	27	Very Poor
PMP	TL T-HANG	Taxilane	4315	57,861	44	Poor
PMP	TL T-HANG	Taxilane	4320	16,033	34	Very Poor
PMP	TL T-HANG	Taxilane	4325	16,764	81	Satisfactory
PMP	AP N	Apron	4205	72,380	58	Fair
PMP	AP RU 33	Apron	5105	14,310	86	Good
PMP	AP RU 33	Apron	5110	20,490	57	Fair
PMP	AP S	Apron	4105	215,925	62	Fair
PMP	AP S	Apron	4107	3,846	86	Good
PMP	AP S	Apron	4110	26,025	47	Poor
PMP	AP S	Apron	4112	135,533	90	Good
PMP	AP S	Apron	4125	105,525	37	Very Poor
PMP	AP S	Apron	4130	71,613	55	Poor
PMP	AP S	Apron	4135	128,753	93	Good
PMP	AP SW	Apron	4405	118,367	87	Good
PMP	AP SW	Apron	4410	63,093	81	Satisfactory
PMP	AP SW	Apron	4415	93,557	100	Good



## Forecasted Pavement Conditions

**Table E.2** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

*Table E.2: Forecasted PCI Values 2021-2030 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI									
				2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
PMP	RW 10-28	6105	64	63	61	59	57	55	53	51	49	47	45
PMP	RW 10-28	6115	85	84	82	80	78	76	74	72	70	68	66
PMP	RW 15-33	6305	89	88	86	84	82	80	78	76	74	72	70
PMP	RW 15-33	6310	90	89	87	85	83	81	79	77	75	73	71
PMP	RW 15-33	6325	82	82	80	79	77	76	74	73	72	71	69
PMP	RW 15-33	6330	92	91	90	88	86	84	83	81	80	78	77
PMP	RW 6-24	6205	60	59	57	55	53	51	49	47	45	43	41
PMP	RW 6-24	6210	62	61	59	57	55	53	51	49	47	45	43
PMP	RW 6-24	6220	91	90	88	86	84	82	80	78	76	74	72
PMP	RW 6-24	6225	91	90	88	86	84	82	80	78	76	74	72
PMP	TW A	105	90	89	87	85	83	81	79	78	76	75	73
PMP	TW A	115	47	46	44	42	39	36	33	30	27	24	21
PMP	TW B	210	59	59	57	56	54	53	51	49	47	45	42
PMP	TW C	305	64	64	63	62	61	61	60	59	58	58	57
PMP	TW C	350	92	91	89	86	84	82	81	79	77	76	74
PMP	TW C	360	92	91	89	86	84	82	81	79	77	76	74
PMP	TW D	405	100	99	96	93	91	88	86	84	82	80	79
PMP	TW D	410	92	91	89	86	84	82	81	79	77	76	74
PMP	TW D	412	83	82	81	79	77	76	74	73	72	70	69
PMP	TW D	415	82	81	80	78	76	75	74	72	71	70	69
PMP	TW D	420	40	39	36	33	30	27	24	21	18	15	12
PMP	TW E	505	89	88	86	84	82	80	79	77	75	74	73
PMP	TW F	610	59	59	57	56	54	53	51	49	47	45	42
PMP	TW F	612	93	92	90	87	85	83	81	80	78	76	75
PMP	TW F	615	95	94	91	89	87	85	83	81	79	77	76
PMP	TW F	620	89	88	86	84	82	80	79	77	75	74	73
PMP	TW G	710	89	88	86	84	83	81	79	77	76	74	73
PMP	TW G	715	90	89	87	85	83	82	80	78	77	75	74
PMP	TW G	720	92	91	89	87	85	83	81	80	78	77	75
PMP	TW G	725	86	85	83	82	80	78	77	75	74	72	71
PMP	TW G1	700	90	89	87	85	83	82	80	78	77	75	74
PMP	TW G3	730	93	92	90	88	86	84	82	80	79	77	76

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI									
				2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
PMP	TW G4	740	92	91	89	87	85	83	81	80	78	77	75
PMP	TW G5	750	91	90	88	86	84	82	81	79	77	76	74
PMP	TW K	1110	92	91	89	87	85	83	81	80	78	77	75
PMP	TW K	1115	83	82	81	79	77	76	74	73	72	70	69
PMP	TW K	1120	90	89	87	85	83	82	80	78	77	75	74
PMP	TW L	1202	62	62	61	59	58	56	55	53	51	49	47
PMP	TW L	1205	51	51	51	50	50	50	49	49	48	48	47
PMP	TW L	1210	60	60	58	57	55	54	52	50	48	46	44
PMP	TW L	1215	87	86	84	82	80	79	77	76	74	73	72
PMP	TW M	1305	68	68	67	66	65	64	63	62	61	60	60
PMP	TW M	1306	81	80	79	77	76	74	73	71	70	69	68
PMP	TW M	1310	82	81	80	78	77	75	74	72	71	70	68
PMP	TW M	1315	69	69	68	67	66	65	64	63	62	61	60
PMP	TW M	1320	64	64	63	61	60	59	57	56	54	53	51
PMP	TW M	1322	93	92	90	88	86	84	82	80	79	77	76
PMP	TW M	1325	90	89	87	85	83	81	79	78	76	75	73
PMP	TW M	1330	64	64	63	61	60	59	57	56	54	53	51
PMP	TW N	1405	79	79	77	75	74	73	71	70	69	68	67
PMP	TL T-HANG	4305	36	36	35	34	33	31	30	29	27	26	24
PMP	TL T-HANG	4310	27	27	25	24	22	20	19	17	16	14	12
PMP	TL T-HANG	4315	44	44	43	43	42	41	41	40	39	38	37
PMP	TL T-HANG	4320	34	33	30	26	23	20	17	14	11	8	5
PMP	TL T-HANG	4325	81	80	79	77	76	74	73	72	70	69	68
PMP	AP N	4205	58	58	56	55	54	53	52	51	49	48	47
PMP	AP RU 33	5105	86	85	83	80	78	76	74	72	70	68	67
PMP	AP RU 33	5110	57	57	56	54	53	52	51	50	49	47	46
PMP	AP S	4105	62	62	60	59	58	56	55	54	53	52	51
PMP	AP S	4107	86	86	85	84	83	82	81	80	79	78	77
PMP	AP S	4110	47	47	47	46	45	45	44	44	43	43	42
PMP	AP S	4112	90	89	87	85	83	81	79	77	76	74	72
PMP	AP S	4125	37	37	37	36	36	35	35	34	34	33	33
PMP	AP S	4130	55	55	54	52	51	50	49	48	47	45	44
PMP	AP S	4135	93	92	90	88	86	84	82	80	78	76	74
PMP	AP SW	4405	87	87	86	85	84	83	82	81	80	79	78
PMP	AP SW	4410	81	81	80	79	78	77	76	75	74	73	72
PMP	AP SW	4415	100	98	97	96	95	94	93	92	91	90	89



## Major Rehabilitation Planning 2021-2030

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Based on FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$17.37M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$15.47M and localized maintenance needs for Year 1 are \$0.15M.

*Table E.3: Major Rehabilitation Planning 2021-2030*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2021	PMP	RW 10-28	6105	AAC	271,200	63	AC Rehabilitation	\$ 1,899,000
2021	PMP	RW 6-24	6205	AAC	335,952	59	AC Rehabilitation	\$ 2,352,000
2021	PMP	RW 6-24	6210	AAC	167,976	61	AC Rehabilitation	\$ 1,176,000
2021	PMP	TW A	115	AAC	13,967	46	AC Reconstruction	\$ 147,000
2021	PMP	TW B	210	AAC	104,085	59	AC Rehabilitation	\$ 729,000
2021	PMP	TW C	305	AC	26,289	64	AC Rehabilitation	\$ 185,000
2021	PMP	TW D	420	AAC	20,401	39	AC Reconstruction	\$ 215,000
2021	PMP	TW F	610	AAC	120,125	59	AC Rehabilitation	\$ 841,000
2021	PMP	TW L	1202	AAC	21,209	62	AC Rehabilitation	\$ 149,000
2021	PMP	TW L	1205	AC	13,025	51	AC Reconstruction	\$ 137,000
2021	PMP	TW L	1210	AAC	152,867	60	AC Rehabilitation	\$ 1,071,000
2021	PMP	TW M	1305	AC	27,738	68	AC Rehabilitation	\$ 195,000
2021	PMP	TW M	1315	AC	16,359	69	AC Rehabilitation	\$ 115,000
2021	PMP	TW M	1320	AAC	69,823	64	AC Rehabilitation	\$ 489,000
2021	PMP	TW M	1330	AAC	12,988	64	AC Rehabilitation	\$ 91,000
2021	PMP	TL T-HANG	4305	AC	31,764	36	AC Reconstruction	\$ 334,000
2021	PMP	TL T-HANG	4310	AC	49,387	27	AC Reconstruction	\$ 519,000
2021	PMP	TL T-HANG	4315	AC	57,861	44	AC Reconstruction	\$ 608,000
2021	PMP	TL T-HANG	4320	APC	16,033	33	AC Reconstruction	\$ 169,000


# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2021	PMP	AP N	4205	AAC	72,380	58	AC Rehabilitation	\$ 507,000
2021	PMP	AP RU 33	5110	AAC	20,490	57	AC Rehabilitation	\$ 144,000
2021	PMP	AP S	4105	AAC	215,925	62	AC Rehabilitation	\$ 1,512,000
2021	PMP	AP S	4110	AC	26,025	47	AC Reconstruction	\$ 274,000
2021	PMP	AP S	4125	AC	105,525	37	AC Reconstruction	\$ 1,109,000
2021	PMP	AP S	4130	AAC	71,613	55	AC Rehabilitation	\$ 502,000
2028	PMP	TW N	1405	AC	33,887	69	AC Rehabilitation	\$ 238,000
2029	PMP	RW 10-28	6115	AAC	58,320	68	AC Rehabilitation	\$ 409,000
2029	PMP	TW M	1306	AC	29,856	69	AC Rehabilitation	\$ 209,000
2029	PMP	TL T-HANG	4325	AAC	16,764	69	AC Rehabilitation	\$ 118,000
2029	PMP	AP RU 33	5105	AAC	14,310	68	AC Rehabilitation	\$ 101,000
2030	PMP	RW 15-33	6325	AC	25,000	69	AC Rehabilitation	\$ 176,000
2030	PMP	TW D	412	AAC	24,824	69	AC Rehabilitation	\$ 174,000
2030	PMP	TW D	415	AAC	36,063	69	AC Rehabilitation	\$ 253,000
2030	PMP	TW K	1115	AC	7,373	69	AC Rehabilitation	\$ 52,000
2030	PMP	TW M	1310	AC	24,002	68	AC Rehabilitation	\$ 169,000

\*All planning cost values have been rounded up to the nearest thousand dollars.

Figure E.3: Major Rehabilitation Planning Annual Budget 2021-2030





# Chapter 1: Introduction





# Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida's economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation (GA) airports are important to businesses throughout the State as air travel is essential to tourism, Florida's most prominent industry.

## 1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as GA, Reliever (RL), and Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding per FAA Advisory Circular 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management Program (PMP)". The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-12 "Standard Test Method for Airport Pavement Condition Index Surveys".

In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).


The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are under consideration for projects. A network-level evaluation can support the identification of

# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

*Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts*



## 1.2 Stakeholders

Ultimately, the SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

*Table 1.2: FDOT SAPMP Stakeholders*

Role	Description
<b>FAA Orlando Airports District Office (Orlando ADO)</b>	Key Stakeholder; local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation).
<b>Florida Department of Transportation (FDOT)</b>	Key Stakeholder; the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System.
<b>FDOT District Offices</b>	The seven FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of the development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes.
<b>Participating Public-Use and Publicly Owned Airports</b>	The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment.
<b>Aviation Office Program Manager (AO-PM)</b>	FDOT AO Airport Engineering Manager; oversees and manages the overall Program System Update.

## 1.3 General Scope of Work

The SAPMP is limited to performing tasks in the adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- » Research and evaluation of existing record documentation;
- » Establishment of a pavement system inventory;
- » Development of a pavement network definition map and supplemental GIS model;
- » Functional pavement evaluations via the PCI assessment method;
- » Customization of PAVER™ software including prioritization, policies, and performance models;
- » Analysis of condition data; and
- » Maintenance, repair, and rehabilitation planning.



## 1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.


A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:

- » Assist airports in meeting the requirements of Public Law 103-305;
- » Assist airports in complying with FAA Grant Assurances 11 and 19;
- » Provide airports with functional pavement condition in accordance with ASTM D5340-12 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- » Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- » Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets that have reached critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.

*Figure 1.4: Typical Pavement Condition Life Cycle*



*\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.*



## Chapter 2: Methodology






## Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.

*Figure 2: FDOT SAPMP General Process*



### 2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- » Create a manageable inventory system;
- » Analyze the current condition of pavements in accordance with the ASTM D5340;
- » Develop pavement performance models to forecast conditions; and
- » Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database and typically consist of pavement inventory

characteristics, pavement structure, work history, historic condition records, and analytical customization.

## 2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance related to the pavement facilities. An airport should maintain detailed records of maintenance (routine, emergency, and proactive) activities, which should consist of:

- » Location and limits of work;
- » Types and severities of repaired distresses;
- » Work type and cost; and
- » Supporting Documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- » Date of last construction/rehabilitation
- » Work type performed
- » Comments for documenting pavement cross-section
- » Pavement surface type
- » Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

## 2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.

## **Asphalt Concrete**

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

### ***Asphalt Concrete (AC)***

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

### ***Asphalt Concrete Overlaid on Asphalt Concrete (AAC)***

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

### ***Asphalt Concrete Overlaid on Portland Cement Concrete (APC)***

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

## **Portland Cement Concrete**

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

### ***Portland Cement Concrete (PCC)***

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

## **Composite Structure – Whitetopping Pavement**

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WHT), Thin (TWT), and Ultra-Thin (UTW).

### ***Conventional Whitetopping (WHT)***

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.



### ***Thin Whitetopping (TWT)***

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

### ***Ultra-Thin Whitetopping (UTW)***

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

## **2.4 Airfield Pavement Traffic**

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of PMP's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

## **2.5 Pavement Management Program Network Definition Terminology**

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units called samples. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the PCI to a value of 100 and reestablish limits for the samples.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

### **2.5.1 Pavement Network Identification**

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

### **2.5.2 Pavement Branch Identification**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.

### 2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

### 2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs ( $\pm 8$  slabs) for PCC pavement and 5,000 contiguous square feet ( $\pm 2,000$  SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

### 2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

*Table 2.5.5: SAPMP Terminology*

SAPMP Terminology	Common Definition	Airport Example
<b>Network</b>	Totality of pavement assets maintained by the Airport.	"Tallahassee International Airport – Airfield Pavements"
<b>Branch Name</b>	Commonly defined asset name as established by Airport and by use.	"Runway 18-36"
<b>Branch ID</b>	Codified shorthand name for commonly defined asset established for database identification.	"RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility
<b>Section ID</b>	Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition.	"6105"
<b>Sample Unit</b>	A numeric identification of an area of pavement (5,000 $\pm$ 2,000 SF of AC or 20 $\pm$ 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-12.	"300"

## 2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g. cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-12. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

### 2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-12 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a) and 2.6.1 (b)** identify these distresses and their common causes or mechanisms.

*Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete*

Distress Mechanism	Distress Type
Load	Alligator Cracking Rutting
Climate/Durability	Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering
Construction/Material	Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling
Other	Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching



*Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete*

Distress Mechanism	Distress Type
<b>Load</b>	Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks
<b>Climate/Durability</b>	Blowup Durability "D" Cracking Joint Seal Damage Popouts
<b>Construction/Material</b>	Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking
<b>Other</b>	Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching

## 2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.


*Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete*

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10



*Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete*

Number of Total Sample Units in Section	Sample Units to Inspect	
	Runways	Taxiways, Aprons, and Others
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI survey to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.

A photograph of a long, straight airfield runway stretching towards the horizon under a bright blue sky filled with fluffy white clouds. The runway has a dark asphalt surface with a central white dashed line and yellow edge lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Chapter 3: Airfield Pavement System Inventory**

A horizontal band of yellow chevron patterns pointing to the right, set against a dark background, located below the chapter title.A close-up, low-angle view of the runway pavement, showing the texture of the asphalt and the white dashed line. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.



## Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing airfield pavement network definition exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

### 3.1 Airfield Pavement Network Information

#### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2016.


*Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction*

Construction Year	Location	Work Type / Pavement Section
2018	TW D	Mill and Overlay   Variable Mill, 2.5" P-401
	TL T-HANG, TW F	Mill and Overlay
	TW G, TW G3, TW G4, TW G5	New Construction - AC
	TW M	Complete Reconstruction - AC   2" P-401, 8" P-211, 12" P-154-5.1
2019	AP SW	New Construction - PCC
2021	TW D	Mill and Overlay   1" Mill, 2.5" P-401

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

**Figure 3.1.1 (a)**, the Airfield Pavement Network Definition Exhibit provides details of the PCI assessment efforts. The exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.





RECENT & ANTICIPATED CONSTRUCTION ACTIVITY

CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2018	TW D	Mill and Overlay   Variable Mill, 2.5" P-401
	TL T-HANG, TW F	Mill and Overlay
	TW G, TW G3, TW G4, TW G5	New Construction - AC
	TW M	Complete Reconstruction - AC   2" P-401, 8" P-211, 12" P-154-5.1
2019	AP SW	New Construction - PCC
2021	TW D	Mill and Overlay   1" Mill, 2.5" P-401

**LEGEND**

RW 13-31 TYPICAL RUNWAY BRANCH ID

TW A TYPICAL TAXIWAY BRANCH ID

AP S TYPICAL APRON BRANCH ID

**PROJECT YEAR**

2016	2021
2017	2022
2018	2023
2019	2024
2020	2025


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.




### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.

*Figure 3.1.2 (a): Age of Pavements at PCI Survey*






### 3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed “functional use” or “branch use.” For this SAPMP System Update, the following categories of pavement functional use are identified: Runway, Taxiway, Taxilane, and Apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.

*Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)*




### 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four common types of pavement: Portland cement concrete (PCC), Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at PMP.



*Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)*



### 3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the airfield pavement network definition exhibit and the airfield pavement system inventory exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

**Table 3.1.5** displays the section-level pavement inventory data. The data is based on the record documentation provided by the airports and from previous updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

*Table 3.1.5: Pavement System Inventory Details*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
PMP	RW 10-28	Runway	6105	271,200	AAC	1/1/2000
PMP	RW 10-28	Runway	6115	58,320	AAC	1/1/2012
PMP	RW 15-33	Runway	6305	220,900	AAC	1/1/2012
PMP	RW 15-33	Runway	6310	441,800	AAC	1/1/2012
PMP	RW 15-33	Runway	6325	25,000	AC	6/1/2012
PMP	RW 15-33	Runway	6330	50,000	AC	6/1/2012
PMP	RW 6-24	Runway	6205	335,952	AAC	1/1/2001
PMP	RW 6-24	Runway	6210	167,976	AAC	1/1/2001
PMP	RW 6-24	Runway	6220	35,000	AAC	1/1/2012
PMP	RW 6-24	Runway	6225	17,500	AAC	1/1/2012
PMP	TW A	Taxiway	105	61,729	AAC	11/1/2012
PMP	TW A	Taxiway	115	13,967	AAC	1/1/1997
PMP	TW B	Taxiway	210	104,085	AAC	1/1/1972
PMP	TW C	Taxiway	305	26,289	AC	1/1/1970
PMP	TW C	Taxiway	350	6,807	AAC	11/1/2012
PMP	TW C	Taxiway	360	9,668	AAC	11/1/2012
PMP	TW D	Taxiway	405	90,211	AAC	1/1/2021
PMP	TW D	Taxiway	410	12,212	AAC	5/1/2018
PMP	TW D	Taxiway	412	24,824	AAC	5/1/2018
PMP	TW D	Taxiway	415	36,063	AAC	11/1/2012
PMP	TW D	Taxiway	420	20,401	AAC	1/1/2008
PMP	TW E	Taxiway	505	12,246	AAC	1/1/2012
PMP	TW F	Taxiway	610	120,125	AAC	1/1/1972
PMP	TW F	Taxiway	612	15,275	AAC	5/1/2018
PMP	TW F	Taxiway	615	8,519	AAC	5/1/2018
PMP	TW F	Taxiway	620	8,073	AAC	1/1/2012
PMP	TW G	Taxiway	710	15,387	AC	6/1/2012
PMP	TW G	Taxiway	715	17,469	AC	6/1/2014
PMP	TW G	Taxiway	720	151,212	AC	5/1/2018
PMP	TW G	Taxiway	725	33,591	AC	6/1/2012
PMP	TW G1	Taxiway	700	21,726	AC	6/1/2012
PMP	TW G3	Taxiway	730	15,789	AC	5/1/2018
PMP	TW G4	Taxiway	740	12,199	AC	5/1/2018
PMP	TW G5	Taxiway	750	16,699	AC	5/1/2018
PMP	TW K	Taxiway	1110	89,261	AC	11/1/2012
PMP	TW K	Taxiway	1115	7,373	AC	6/1/2014
PMP	TW K	Taxiway	1120	14,097	AC	6/1/2012
PMP	TW L	Taxiway	1202	21,209	AAC	1/1/1996
PMP	TW L	Taxiway	1205	13,025	AC	1/1/1972
PMP	TW L	Taxiway	1210	152,867	AAC	1/1/1996
PMP	TW L	Taxiway	1215	14,829	AAC	6/1/2012
PMP	TW M	Taxiway	1305	27,738	AC	1/1/1970
PMP	TW M	Taxiway	1306	29,856	AC	11/1/2012
PMP	TW M	Taxiway	1310	24,002	AC	1/1/1999

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
PMP	TW M	Taxiway	1315	16,359	AC	1/1/1999
PMP	TW M	Taxiway	1320	69,823	AAC	1/1/2001
PMP	TW M	Taxiway	1322	30,907	AC	5/1/2018
PMP	TW M	Taxiway	1325	8,073	AAC	1/1/2012
PMP	TW M	Taxiway	1330	12,988	AAC	1/1/2001
PMP	TW N	Taxiway	1405	33,887	AC	1/1/2004
PMP	TL T-HANG	Taxilane	4305	31,764	AC	12/25/1999
PMP	TL T-HANG	Taxilane	4310	49,387	AC	12/25/1999
PMP	TL T-HANG	Taxilane	4315	57,861	AC	12/25/1999
PMP	TL T-HANG	Taxilane	4320	16,033	APC	12/25/1999
PMP	TL T-HANG	Taxilane	4325	16,764	AAC	6/1/2018
PMP	AP N	Apron	4205	72,380	AAC	1/1/1972
PMP	AP RU 33	Apron	5105	14,310	AAC	6/1/2012
PMP	AP RU 33	Apron	5110	20,490	AAC	1/1/1996
PMP	AP S	Apron	4105	215,925	AAC	1/1/1997
PMP	AP S	Apron	4107	3,846	PCC	1/1/2015
PMP	AP S	Apron	4110	26,025	AC	1/1/1960
PMP	AP S	Apron	4112	135,533	AC	5/17/2013
PMP	AP S	Apron	4125	105,525	AC	12/25/1999
PMP	AP S	Apron	4130	71,613	AAC	1/1/2015
PMP	AP S	Apron	4135	128,753	AC	1/1/2015
PMP	AP SW	Apron	4405	118,367	PCC	1/1/2015
PMP	AP SW	Apron	4410	63,093	PCC	1/1/2012
PMP	AP SW	Apron	4415	93,557	PCC	7/1/2019



A photograph of a long, straight airfield runway stretching towards the horizon under a bright blue sky with scattered white clouds. The runway has a central white dashed line and side yellow lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Chapter 4: Airfield Pavement Condition Analysis**

A close-up photograph of the runway pavement surface, showing a concrete slab with a yellow chevron marking. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

## Chapter 4 – Airfield Pavement Condition Analysis


Distress type, severity, and extent are required in the computation of a PCI value. The PCI provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for design- and/or project-level determination of pavement rehabilitation needs.

### 4.1 Airfield Pavement Condition Index

#### 4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 53% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 38% of inspected pavements are in Fair condition, and the remaining 9% of inspected pavement assets are in Poor or worse condition.


*Figure 4.1.1: Latest Condition – Overall Network*




#### 4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(e)** summarize branch-level pavement conditions according to the most recent PCI assessment results.


*Figure 4.1.2 (a): Latest Condition Summary – Branch-Level*



*Figure 4.1.2 (b): Latest Condition – Runway*




*Figure 4.1.2 (c): Latest Condition – Taxiway*






*Figure 4.1.2 (d): Latest Condition – Taxiway*



*Figure 4.1.2 (e): Latest Condition – Apron*



**Table 4.1.2** details the branch-level condition for each airfield pavement branch.

*Table 4.1.2: Latest Condition Summary – Branch-Level*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
RW 10-28	Runway	2	329,520	68	Fair
RW 15-33	Runway	4	737,700	90	Good
RW 6-24	Runway	4	556,428	64	Fair
TW A	Taxiway	2	75,696	82	Satisfactory
TW B	Taxiway	1	104,085	59	Fair
TW C	Taxiway	3	42,764	75	Satisfactory
TW D	Taxiway	5	183,711	87	Good
TW E	Taxiway	1	12,246	89	Good
TW F	Taxiway	4	151,992	66	Fair
TW G	Taxiway	4	217,659	91	Good
TW G1	Taxiway	1	21,726	90	Good
TW G3	Taxiway	1	15,789	93	Good
TW G4	Taxiway	1	12,199	92	Good
TW G5	Taxiway	1	16,699	91	Good
TW K	Taxiway	3	110,731	91	Good
TW L	Taxiway	4	201,930	62	Fair
TW M	Taxiway	8	219,746	74	Satisfactory
TW N	Taxiway	1	33,887	79	Satisfactory
TL T-HANG	Taxilane	5	171,809	40	Very Poor
AP N	Apron	1	72,380	58	Fair
AP RU 33	Apron	2	34,800	69	Fair
AP S	Apron	7	687,220	68	Fair
AP SW	Apron	3	275,017	90	Good

#### 4.1.3 Section-Level Analysis

**Table 4.1.3** provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.

Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.



Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
PMP	RW 10-28	Runway	6105	271,200	AAC	64	Fair	95	0	5	11	54
PMP	RW 10-28	Runway	6115	58,320	AAC	85	Satisfactory	100	0	0	3	12
PMP	RW 15-33	Runway	6305	220,900	AAC	89	Good	100	0	0	8	44
PMP	RW 15-33	Runway	6310	441,800	AAC	90	Good	100	0	0	18	88
PMP	RW 15-33	Runway	6325	25,000	AC	82	Satisfactory	100	0	0	2	5
PMP	RW 15-33	Runway	6330	50,000	AC	92	Good	100	0	0	2	10
PMP	RW 6-24	Runway	6205	335,952	AAC	60	Fair	97	0	3	15	68
PMP	RW 6-24	Runway	6210	167,976	AAC	62	Fair	100	0	0	8	34
PMP	RW 6-24	Runway	6220	35,000	AAC	91	Good	100	0	0	2	7
PMP	RW 6-24	Runway	6225	17,500	AAC	91	Good	100	0	0	1	4
PMP	TW A	Taxiway	105	61,729	AAC	90	Good	100	0	0	2	11
PMP	TW A	Taxiway	115	13,967	AAC	47	Poor	85	0	15	1	3
PMP	TW B	Taxiway	210	104,085	AAC	59	Fair	98	0	2	3	20
PMP	TW C	Taxiway	305	26,289	AC	64	Fair	90	0	10	2	5
PMP	TW C	Taxiway	350	6,807	AAC	92	Good	100	0	0	1	1
PMP	TW C	Taxiway	360	9,668	AAC	92	Good	100	0	0	1	2
PMP	TW D	Taxiway	405	90,211	AAC	100	Good	0	0	0	0	0
PMP	TW D	Taxiway	410	12,212	AAC	92	Good	100	0	0	1	2
PMP	TW D	Taxiway	412	24,824	AAC	83	Satisfactory	100	0	0	1	4
PMP	TW D	Taxiway	415	36,063	AAC	82	Satisfactory	100	0	0	2	9
PMP	TW D	Taxiway	420	20,401	AAC	40	Very Poor	38	55	7	1	4
PMP	TW E	Taxiway	505	12,246	AAC	89	Good	100	0	0	1	3
PMP	TW F	Taxiway	610	120,125	AAC	59	Fair	98	0	2	3	24
PMP	TW F	Taxiway	612	15,275	AAC	93	Good	100	0	0	1	3
PMP	TW F	Taxiway	615	8,519	AAC	95	Good	100	0	0	1	2
PMP	TW F	Taxiway	620	8,073	AAC	89	Good	100	0	0	1	2
PMP	TW G	Taxiway	710	15,387	AC	89	Good	100	0	0	1	4
PMP	TW G	Taxiway	715	17,469	AC	90	Good	100	0	0	1	4
PMP	TW G	Taxiway	720	151,212	AC	92	Good	100	0	0	3	30
PMP	TW G	Taxiway	725	33,591	AC	86	Good	100	0	0	1	9
PMP	TW G1	Taxiway	700	21,726	AC	90	Good	100	0	0	1	4
PMP	TW G3	Taxiway	730	15,789	AC	93	Good	100	0	0	1	3
PMP	TW G4	Taxiway	740	12,199	AC	92	Good	88	0	12	1	3
PMP	TW G5	Taxiway	750	16,699	AC	91	Good	100	0	0	1	3
PMP	TW K	Taxiway	1110	89,261	AC	92	Good	100	0	0	3	25
PMP	TW K	Taxiway	1115	7,373	AC	83	Satisfactory	81	0	19	1	2
PMP	TW K	Taxiway	1120	14,097	AC	90	Good	100	0	0	1	3
PMP	TW L	Taxiway	1202	21,209	AAC	62	Fair	90	0	10	1	4
PMP	TW L	Taxiway	1205	13,025	AC	51	Poor	100	0	0	1	3
PMP	TW L	Taxiway	1210	152,867	AAC	60	Fair	100	0	0	3	26
PMP	TW L	Taxiway	1215	14,829	AAC	87	Good	100	0	0	1	3
PMP	TW M	Taxiway	1305	27,738	AC	68	Fair	100	0	0	1	6
PMP	TW M	Taxiway	1306	29,856	AC	81	Satisfactory	100	0	0	2	6
PMP	TW M	Taxiway	1310	24,002	AC	82	Satisfactory	95	0	5	2	7

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
PMP	TW M	Taxiway	1315	16,359	AC	69	Fair	100	0	0	1	3
PMP	TW M	Taxiway	1320	69,823	AAC	64	Fair	93	0	7	3	14
PMP	TW M	Taxiway	1322	30,907	AC	93	Good	100	0	0	2	6
PMP	TW M	Taxiway	1325	8,073	AAC	90	Good	100	0	0	1	2
PMP	TW M	Taxiway	1330	12,988	AAC	64	Fair	100	0	0	1	3
PMP	TW N	Taxiway	1405	33,887	AC	79	Satisfactory	100	0	0	1	6
PMP	TL T-HANG	Taxilane	4305	31,764	AC	36	Very Poor	98	0	2	1	7
PMP	TL T-HANG	Taxilane	4310	49,387	AC	27	Very Poor	94	0	6	2	10
PMP	TL T-HANG	Taxilane	4315	57,861	AC	44	Poor	66	28	6	2	15
PMP	TL T-HANG	Taxilane	4320	16,033	APC	34	Very Poor	96	0	4	1	4
PMP	TL T-HANG	Taxilane	4325	16,764	AAC	81	Satisfactory	100	0	0	1	4
PMP	AP N	Apron	4205	72,380	AAC	58	Fair	61	0	39	2	14
PMP	AP RU 33	Apron	5105	14,310	AAC	86	Good	100	0	0	1	3
PMP	AP RU 33	Apron	5110	20,490	AAC	57	Fair	88	0	12	1	4
PMP	AP S	Apron	4105	215,925	AAC	62	Fair	97	0	3	5	44
PMP	AP S	Apron	4107	3,846	PCC	86	Good	84	0	16	1	1
PMP	AP S	Apron	4110	26,025	AC	47	Poor	100	0	0	1	5
PMP	AP S	Apron	4112	135,533	AC	90	Good	68	0	32	3	27
PMP	AP S	Apron	4125	105,525	AC	37	Very Poor	88	0	12	3	25
PMP	AP S	Apron	4130	71,613	AAC	55	Poor	89	0	11	2	12
PMP	AP S	Apron	4135	128,753	AC	93	Good	68	0	32	3	26
PMP	AP SW	Apron	4405	118,367	PCC	87	Good	94	0	6	3	30
PMP	AP SW	Apron	4410	63,093	PCC	81	Satisfactory	62	15	23	3	22
PMP	AP SW	Apron	4415	93,557	PCC	100	Good	0	0	0	0	0

\* Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.





## 4.2 Summary of Pavement Condition Evaluation Results

### 4.2.1 Network-Level Observations

The PCI assessment for Pompano Beach Airpark (PMP) was performed in November 2020. The overall area-weighted average PCI value of the network was 74, representing a condition rating of Satisfactory. Portions of Taxiway D from Taxiway B to Runway 6-24 were not inspected due to upcoming pavement rehabilitation in 2021.

Based on the FAA 5010 Report as of 03/25/2021, the Airport has reported 169,722 operations for 12 months ending 05/01/2018.

### 4.2.2 Branch-Level Observations

The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the airport's airfield pavement network. Representative distress photographs of selected sections are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

#### Runways

##### *RW 10-28*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 10-28	RUNWAY	2	329,520	68	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 18% Satisfactory (71-85 PCI), 82% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6105	AAC	271,200	64	Fair
6115	AAC	58,320	85	Satisfactory

RW 10-28 consists of 2 flexible pavement sections, totaling 329,520 sf. The last major construction dates range from 2000 to 2012, resulting in an area-weighted average age at inspection of 19 years old. Overall, RW 10-28 is in Fair condition with an area-weighted average PCI of 68.

### RW 15-33

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 15-33	RUNWAY	4	737,700	90	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 97% Good (86-100 PCI), 3% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6305	AAC	220,900	89	Good
6310	AAC	441,800	90	Good
6325	AC	25,000	82	Satisfactory
6330	AC	50,000	92	Good

RW 15-33 consists of 4 flexible pavement sections, totaling 737,700 sf. The last major construction date for the branch was 2012, resulting in an area-weighted average age at inspection of 9 years old. Overall, RW 15-33 is in Good condition with an area-weighted average PCI of 90.

### RW 6-24

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 6-24	RUNWAY	4	556,428	64	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 9% Good (86-100 PCI), 91% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6205	AAC	335,952	60	Fair
6210	AAC	167,976	62	Fair
6220	AAC	35,000	91	Good
6225	AAC	17,500	91	Good

RW 6-24 consists of 4 flexible pavement sections, totaling 556,428 sf. The last major construction dates range from 2001 to 2012, resulting in an area-weighted average age at inspection of 19 years old. Overall, RW 6-24 is in Fair condition with an area-weighted average PCI of 64.

## **Taxiways**

### ***TW A***

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	2	75,696	82	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 82% Good (86-100 PCI), 18% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
105	AAC	61,729	90	Good
115	AAC	13,967	47	Poor


TW A consists of 2 flexible pavement sections, totaling 75,696 sf. The last major construction dates range from 1997 to 2012, resulting in an area-weighted average age at inspection of 11 years old. Overall, TW A is in Satisfactory condition with an area-weighted average PCI of 82.

### ***TW B***

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW B	TAXIWAY	1	104,085	59	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).





Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
210	AAC	104,085	59	Fair

TW B consists of 1 flexible pavement section, totaling 104,085 sf. The last major construction date for the branch was 1972, resulting in an area-weighted average age at inspection of 49 years old. Overall, TW B is in Fair condition with an area-weighted average PCI of 59.

### TW C

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW C	TAXIWAY	3	42,764	75	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 39% Good (86-100 PCI), 61% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
305	AC	26,289	64	Fair
350	AAC	6,807	92	Good
360	AAC	9,668	92	Good

TW C consists of 3 flexible pavement sections, totaling 42,764 sf. The last major construction dates range from 1970 to 2012, resulting in an area-weighted average age at inspection of 34 years old. Overall, TW C is in Satisfactory condition with an area-weighted average PCI of 75.

### TW D

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW D	TAXIWAY	5	183,711	87	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the

subsequent table, the distribution is as follows: 56% Good (86-100 PCI), 33% Satisfactory (71-85 PCI), 11% Very Poor (26-40 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
405	AAC	90,211	100	Good
410	AAC	12,212	92	Good
412	AAC	24,824	83	Satisfactory
415	AAC	36,063	82	Satisfactory
420	AAC	20,401	40	Very Poor

TW D consists of 5 flexible pavement sections, totaling 183,711 sf. The last major construction dates range from 2008 to 2021, resulting in an area-weighted average age at inspection of 4 years old. Overall, TW D is in Good condition with an area-weighted average PCI of 87.

### TW E

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW E	TAXIWAY	1	12,246	89	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
505	AAC	12,246	89	Good

TW E consists of 1 flexible pavement section, totaling 12,246 sf. The last major construction date for the branch was 2012, resulting in an area-weighted average age at inspection of 9 years old. Overall, TW E is in Good condition with an area-weighted average PCI of 89.

### TW F

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW F	TAXIWAY	4	151,992	66	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 21% Good (86-100 PCI), 79% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
610	AAC	120,125	59	Fair
612	AAC	15,275	93	Good
615	AAC	8,519	95	Good
620	AAC	8,073	89	Good

TW F consists of 4 flexible pavement sections, totaling 151,992 sf. The last major construction dates range from 1972 to 2018, resulting in an area-weighted average age at inspection of 40 years old. Overall, TW F is in Fair condition with an area-weighted average PCI of 66.

### TW G

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW G	TAXIWAY	4	217,659	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
710	AC	15,387	89	Good
715	AC	17,469	90	Good
720	AC	151,212	92	Good
725	AC	33,591	86	Good

TW G consists of 4 flexible pavement sections, totaling 217,659 sf. The last major construction dates range from 2012 to 2018, resulting in an area-weighted average age at inspection of 4 years old. Overall, TW G is in Good condition with an area-weighted average PCI of 91.

### TW K

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW K	TAXIWAY	3	110,731	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 93% Good (86-100 PCI), 7% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
1110	AC	89,261	92	Good
1115	AC	7,373	83	Satisfactory
1120	AC	14,097	90	Good

TW K consists of 3 flexible pavement sections, totaling 110,731 sf. The last major construction dates range from 2012 to 2014, resulting in an area-weighted average age at inspection of 8 years old. Overall, TW K is in Good condition with an area-weighted average PCI of 91.

### TW L

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW L	TAXIWAY	4	201,930	62	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 7% Good (86-100 PCI), 87% Fair (56-70 PCI), 6% Poor (41-55 PCI).





Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
1202	AAC	21,209	62	Fair
1205	AC	13,025	51	Poor
1210	AAC	152,867	60	Fair
1215	AAC	14,829	87	Good

TW L consists of 4 flexible pavement sections, totaling 201,930 sf. The last major construction dates range from 1972 to 2012, resulting in an area-weighted average age at inspection of 25 years old. Overall, TW L is in Fair condition with an area-weighted average PCI of 62.

### *TW M*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW M	TAXIWAY	8	219,746	74	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 18% Good (86-100 PCI), 25% Satisfactory (71-85 PCI), 57% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
1305	AC	27,738	68	Fair
1306	AC	29,856	81	Satisfactory
1310	AC	24,002	82	Satisfactory
1315	AC	16,359	69	Fair
1320	AAC	69,823	64	Fair
1322	AC	30,907	93	Good
1325	AAC	8,073	90	Good
1330	AAC	12,988	64	Fair


TW M consists of 8 flexible pavement sections, totaling 219,746 sf. The last major construction dates range from 1970 to 2018, resulting in an area-weighted average age at inspection of 20 years old. Overall, TW M is in Satisfactory condition with an area-weighted average PCI of 74.

## Taxilanes

### *TL T-HANG*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL T-HANG	TAXILANE	5	171,809	40	Very Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 10% Satisfactory (71-85 PCI), 34% Poor (41-55 PCI), 56% Very Poor (26-40 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4305	AC	31,764	36	Very Poor
4310	AC	49,387	27	Very Poor
4315	AC	57,861	44	Poor
4320	APC	16,033	34	Very Poor
4325	AAC	16,764	81	Satisfactory


TL T-HANG consists of 5 flexible pavement sections, totaling 171,809 sf. The last major construction dates range from 1999 to 2018, resulting in an area-weighted average age at inspection of 19 years old. Overall, TL T-HANG is in Very Poor condition with an area-weighted average PCI of 40.

## Aprons

### *AP N*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP N	APRON	1	72,380	58	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4205	AAC	72,380	58	Fair

AP N consists of 1 flexible pavement section, totaling 72,380 sf. The last major construction date for the branch was 1972, resulting in an area-weighted average age at inspection of 49 years old. Overall, AP N is in Fair condition with an area-weighted average PCI of 58.

### AP RU 33

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU 33	APRON	2	34,800	69	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 41% Good (86-100 PCI), 59% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5105	AAC	14,310	86	Good
5110	AAC	20,490	57	Fair

AP RU 33 consists of 2 flexible pavement sections, totaling 34,800 sf. The last major construction dates range from 1996 to 2012, resulting in an area-weighted average age at inspection of 18 years old. Overall, AP RU 33 is in Fair condition with an area-weighted average PCI of 69.

### AP S

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP S	APRON	7	687,220	68	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 40% Good (86-100 PCI), 31% Fair (56-70 PCI), 14% Poor (41-55 PCI), 15% Very Poor (26-40 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4105	AAC	215,925	62	Fair
4107	PCC	3,846	86	Good
4110	AC	26,025	47	Poor
4112	AC	135,533	90	Good
4125	AC	105,525	37	Very Poor
4130	AAC	71,613	55	Poor
4135	AC	128,753	93	Good

AP S consists of 6 flexible and 1 rigid pavement sections, totaling 687,220 sf. The last major construction dates range from 1960 to 2015, resulting in an area-weighted average age at inspection of 16 years old. Overall, AP S is in Fair condition with an area-weighted average PCI of 68.

### AP SW

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP SW	APRON	3	275,017	90	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 77% Good (86-100 PCI), 23% Satisfactory (71-85 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4405	PCC	118,367	87	Good
4410	PCC	63,093	81	Satisfactory
4415	PCC	93,557	100	Good

AP SW consists of 3 rigid pavement sections, totaling 275,017 sf. The last major construction dates range from 2012 to 2019, resulting in an area-weighted average age at inspection of 5 years old. Overall, AP SW is in Good condition with an area-weighted average PCI of 90.





# Chapter 5: SAPMP Customization



## Chapter 5 – SAPMP Customization

Once the PAVER™ database is populated with inventory and condition data including PCI and rank, it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors plays a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

### 5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- » The “Network” field identifies the airport being analyzed;
- » The “Airport Classification” field classifies the Airport according to the type and volume of aircraft traffic;
  - “GA” for General Aviation, community airports
  - “RL” for Regional Relievers
  - “PR” for Primary/Commercial airports
- » The “District” field identifies the FDOT District to which the Airport belongs;
- » The “FAA ADO Area” is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists);
- » The “Inspection Phase” denotes which phase of the SAPMP the airport is surveyed, Phase 1 or Phase 2; and
- » The “CFASPP Center” identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an airport falls within.

### 5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.

### 5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. Forecasting of pavement condition for the Airport is intended for planning purposes only. **The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.** Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.


### 5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into “groups” or “families” according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

### 5.2.3 Branch-Level Pavement Condition Forecast

**Figure 5.2.3** depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2021 through 2030.

*Figure 5.2.3: Forecasted Branch-Level Pavement Performance*





### 5.2.4 Section-Level Pavement Condition Forecast

**Table 5.2.4** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

*Table 5.2.4: Forecasted PCI Values 2021-2030 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI									
				2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
PMP	RW 10-28	6105	64	63	61	59	57	55	53	51	49	47	45
PMP	RW 10-28	6115	85	84	82	80	78	76	74	72	70	68	66
PMP	RW 15-33	6305	89	88	86	84	82	80	78	76	74	72	70
PMP	RW 15-33	6310	90	89	87	85	83	81	79	77	75	73	71
PMP	RW 15-33	6325	82	82	80	79	77	76	74	73	72	71	69
PMP	RW 15-33	6330	92	91	90	88	86	84	83	81	80	78	77
PMP	RW 6-24	6205	60	59	57	55	53	51	49	47	45	43	41
PMP	RW 6-24	6210	62	61	59	57	55	53	51	49	47	45	43
PMP	RW 6-24	6220	91	90	88	86	84	82	80	78	76	74	72
PMP	RW 6-24	6225	91	90	88	86	84	82	80	78	76	74	72
PMP	TW A	105	90	89	87	85	83	81	79	78	76	75	73
PMP	TW A	115	47	46	44	42	39	36	33	30	27	24	21
PMP	TW B	210	59	59	57	56	54	53	51	49	47	45	42
PMP	TW C	305	64	64	63	62	61	61	60	59	58	58	57
PMP	TW C	350	92	91	89	86	84	82	81	79	77	76	74
PMP	TW C	360	92	91	89	86	84	82	81	79	77	76	74
PMP	TW D	405	100	99	96	93	91	88	86	84	82	80	79
PMP	TW D	410	92	91	89	86	84	82	81	79	77	76	74
PMP	TW D	412	83	82	81	79	77	76	74	73	72	70	69
PMP	TW D	415	82	81	80	78	76	75	74	72	71	70	69
PMP	TW D	420	40	39	36	33	30	27	24	21	18	15	12
PMP	TW E	505	89	88	86	84	82	80	79	77	75	74	73
PMP	TW F	610	59	59	57	56	54	53	51	49	47	45	42
PMP	TW F	612	93	92	90	87	85	83	81	80	78	76	75
PMP	TW F	615	95	94	91	89	87	85	83	81	79	77	76
PMP	TW F	620	89	88	86	84	82	80	79	77	75	74	73
PMP	TW G	710	89	88	86	84	83	81	79	77	76	74	73
PMP	TW G	715	90	89	87	85	83	82	80	78	77	75	74
PMP	TW G	720	92	91	89	87	85	83	81	80	78	77	75
PMP	TW G	725	86	85	83	82	80	78	77	75	74	72	71
PMP	TW G1	700	90	89	87	85	83	82	80	78	77	75	74
PMP	TW G3	730	93	92	90	88	86	84	82	80	79	77	76
PMP	TW G4	740	92	91	89	87	85	83	81	80	78	77	75
PMP	TW G5	750	91	90	88	86	84	82	81	79	77	76	74
PMP	TW K	1110	92	91	89	87	85	83	81	80	78	77	75
PMP	TW K	1115	83	82	81	79	77	76	74	73	72	70	69
PMP	TW K	1120	90	89	87	85	83	82	80	78	77	75	74
PMP	TW L	1202	62	62	61	59	58	56	55	53	51	49	47
PMP	TW L	1205	51	51	51	50	50	50	49	49	48	48	47




Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI									
				2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
PMP	TW L	1210	60	60	58	57	55	54	52	50	48	46	44
PMP	TW L	1215	87	86	84	82	80	79	77	76	74	73	72
PMP	TW M	1305	68	68	67	66	65	64	63	62	61	60	60
PMP	TW M	1306	81	80	79	77	76	74	73	71	70	69	68
PMP	TW M	1310	82	81	80	78	77	75	74	72	71	70	68
PMP	TW M	1315	69	69	68	67	66	65	64	63	62	61	60
PMP	TW M	1320	64	64	63	61	60	59	57	56	54	53	51
PMP	TW M	1322	93	92	90	88	86	84	82	80	79	77	76
PMP	TW M	1325	90	89	87	85	83	81	79	78	76	75	73
PMP	TW M	1330	64	64	63	61	60	59	57	56	54	53	51
PMP	TW N	1405	79	79	77	75	74	73	71	70	69	68	67
PMP	TL T-HANG	4305	36	36	35	34	33	31	30	29	27	26	24
PMP	TL T-HANG	4310	27	27	25	24	22	20	19	17	16	14	12
PMP	TL T-HANG	4315	44	44	43	43	42	41	41	40	39	38	37
PMP	TL T-HANG	4320	34	33	30	26	23	20	17	14	11	8	5
PMP	TL T-HANG	4325	81	80	79	77	76	74	73	72	70	69	68
PMP	AP N	4205	58	58	56	55	54	53	52	51	49	48	47
PMP	AP RU 33	5105	86	85	83	80	78	76	74	72	70	68	67
PMP	AP RU 33	5110	57	57	56	54	53	52	51	50	49	47	46
PMP	AP S	4105	62	62	60	59	58	56	55	54	53	52	51
PMP	AP S	4107	86	86	85	84	83	82	81	80	79	78	77
PMP	AP S	4110	47	47	47	46	45	45	44	44	43	43	42
PMP	AP S	4112	90	89	87	85	83	81	79	77	76	74	72
PMP	AP S	4125	37	37	37	36	36	35	35	34	34	33	33
PMP	AP S	4130	55	55	54	52	51	50	49	48	47	45	44
PMP	AP S	4135	93	92	90	88	86	84	82	80	78	76	74
PMP	AP SW	4405	87	87	86	85	84	83	82	81	80	79	78
PMP	AP SW	4410	81	81	80	79	78	77	76	75	74	73	72
PMP	AP SW	4415	100	98	97	96	95	94	93	92	91	90	89

## 5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.

*Figure 5.3 (a): General Pavement Treatments by Condition Range*



Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous updates, the critical PCI value was set to 65 for all functional uses. Based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 69 will be considered for Rehabilitation and sections between PCI Values 0 to 54 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP and/or PFC eligibility for project planning. Moving forward, the critical PCI value will now be defined at 69 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

*Table 5.3 (a): AIP Handbook PCI Requirements*

PCI Requirements for Airfield Pavement Projects	
Airfield Pavement Project Type	PCI Requirement
Reconstruction	PCI < 55 (Poor)
Rehabilitation	PCI < 70 (Fair)
Maintenance	N/A

\*Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

*Table 5.3 (b): Critical PCI Values by Branch Use*

Branch Use		
Runway	Taxiway	Apron
69	69	69

**Figures 5.3 (b) and 5.3 (c)** depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram,  $PCI < \text{Critical } PCI$





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram,  $PCI \geq \text{Critical } PCI$





## 5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation M&R methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly, and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 “Airport Foreign Object Debris (FOD) Management” provides additional guidance for developing and managing an airport FOD program.

### 5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety (“stopgap”) measure. The two types of localized maintenance are described below in further detail.

- » Localized Preventive Maintenance and Repair
  - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- » Localized Stopgap/Safety Maintenance and Repair
  - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

### 5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

#### **AC Crack Sealing**

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

#### **AC Full-Depth Patching**

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

#### **AC Partial-Depth AC Patching**

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

#### **Grinding**

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

#### **Monitor Pavement**

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.

### **PCC Crack Sealing**

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

### **PCC Full-Depth Patching**

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

### **PCC Joint Seal**

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

### **PCC Partial-Depth Patching**

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

### **PCC Slab Replacement**

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

### **Surface Seal**

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

### 5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

**Tables 5.4.3 (a) and (b)** display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

*Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete*

Localized Work Type	General Aviation Costs	Work Type Unit
AC Crack Sealing	\$ 3.00	LF
AC Full-Depth Patching	\$ 7.50	SF
AC Partial-Depth Patching	\$ 3.75	SF
Monitor Pavement	-	-
Surface Seal	\$ 0.50	SF

*Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete*

Localized Work Type	General Aviation Costs	Work Type Unit
Grinding	\$ 2.00	SF
Monitor Pavement	-	-
PCC Crack Sealing	\$ 5.00	LF
PCC Joint Seal	\$ 3.25	LF
PCC Full-Depth Patching	\$ 50.00	SF
PCC Partial-Depth Patching	\$ 125.00	SF
PCC Slab Replacement	\$ 38.75	SF

\*PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.



#### 5.4.4 Localized Maintenance and Repair Policy

The resulting Localized Maintenance recommendations are identified based on the policy defined in **Tables 5.4.4 (a) and (b)**. **Table 5.4.4 (a)** depicts the localized preventive maintenance policy for AC and PCC pavements. **Table 5.4.4 (b)** depicts the localized stopgap maintenance policy for AC and PCC pavements.

*Table 5.4.4 (a): Localized Preventive Maintenance and Repair Policy*

Distress	Severity	Localized Work Type	Work Type Unit
Alligator Cracking	Low	Monitor Pavement	-
Alligator Cracking	Medium	AC Full-Depth Patching	SF
Alligator Cracking	High	AC Full-Depth Patching	SF
Bleeding	N/A	Monitor Pavement	-
Block Cracking	Low	Monitor Pavement	-
Block Cracking	Medium	AC Crack Sealing	LF
Block Cracking	High	AC Crack Sealing	LF
Corrugation	Low	Monitor Pavement	-
Corrugation	Medium	AC Full-Depth Patching	SF
Corrugation	High	AC Full-Depth Patching	SF
Depression	Low	Monitor Pavement	-
Depression	Medium	AC Full-Depth Patching	SF
Depression	High	AC Full-Depth Patching	SF
Jet Blast	N/A	Monitor Pavement	-
Jt. Reflective Cracking	Low	Monitor Pavement	-
Jt. Reflective Cracking	Medium	AC Crack Sealing	LF
Jt. Reflective Cracking	High	AC Crack Sealing	LF
L&T Cracking	Low	Monitor Pavement	-
L&T Cracking	Medium	AC Crack Sealing	LF
L&T Cracking	High	AC Crack Sealing	LF
Oil Spillage	N/A	Monitor Pavement	-
Patching	Low	Monitor Pavement	-
Patching	Medium	AC Full-Depth Patching	SF
Patching	High	AC Full-Depth Patching	SF
Polished Aggregate	N/A	Monitor Pavement	-
Raveling	Low	Surface Seal	SF
Raveling	Medium	Surface Seal	SF
Raveling	High	AC Partial-Depth Patching	SF
Rutting	Low	Monitor Pavement	-
Rutting	Medium	AC Full-Depth Patching	SF

Distress	Severity	Localized Work Type	Work Type Unit
Rutting	High	AC Full-Depth Patching	SF
Shoving	Low	Monitor Pavement	-
Shoving	Medium	AC Partial-Depth Patching	SF
Shoving	High	AC Full-Depth Patching	SF
Slippage Cracking	N/A	AC Full-Depth Patching	SF
Swelling	Low	Monitor Pavement	-
Swelling	Medium	AC Full-Depth Patching	SF
Swelling	High	AC Full-Depth Patching	SF
Weathering	Low	Monitor Pavement	-
Weathering	Medium	Surface Seal	SF
Weathering	High	AC Partial-Depth Patching	SF
Blow-up	Low	PCC Full-Depth Patching	SF
Blow-up	Medium	PCC Full-Depth Patching	SF
Blow-up	High	PCC Slab Replacement	SF
Corner Break	Low	Monitor Pavement	-
Corner Break	Medium	PCC Full-Depth Patching	SF
Corner Break	High	PCC Full-Depth Patching	SF
Linear Cracking	Low	Monitor Pavement	-
Linear Cracking	Medium	PCC Crack Sealing	LF
Linear Cracking	High	PCC Full-Depth Patching	SF
Durability Cracking	Low	Monitor Pavement	-
Durability Cracking	Medium	PCC Full-Depth Patching	SF
Durability Cracking	High	PCC Slab Replacement	SF
Jt. Seal Damage	Low	PCC Joint Seal	LF
Jt. Seal Damage	Medium	PCC Joint Seal	LF
Jt. Seal Damage	High	PCC Joint Seal	LF
Small Patch	Low	Monitor Pavement	-
Small Patch	Medium	PCC Partial-Depth Patching	SF
Small Patch	High	PCC Partial-Depth Patching	SF
Large Patch	Low	Monitor Pavement	-
Large Patch	Medium	PCC Full-Depth Patching	SF
Large Patch	High	PCC Full-Depth Patching	SF
Popouts	N/A	Monitor Pavement	-
Pumping	N/A	Monitor Pavement	-
Scaling	Low	Monitor Pavement	-
Scaling	Medium	PCC Partial-Depth Patching	SF

Distress	Severity	Localized Work Type	Work Type Unit
Scaling	High	PCC Slab Replacement	SF
Faulting	Low	Monitor Pavement	-
Faulting	Medium	Grinding	SF
Faulting	High	PCC Slab Replacement	SF
Shattered Slab	Low	PCC Crack Sealing	LF
Shattered Slab	Medium	PCC Slab Replacement	SF
Shattered Slab	High	PCC Slab Replacement	SF
Shrinkage Cracking	N/A	Monitor Pavement	-
Joint Spall	Low	Monitor Pavement	-
Joint Spall	Medium	PCC Partial-Depth Patching	SF
Joint Spall	High	PCC Partial-Depth Patching	SF
Corner Spall	Low	Monitor Pavement	-
Corner Spall	Medium	PCC Partial-Depth Patching	SF
Corner Spall	High	PCC Partial-Depth Patching	SF
ASR	Low	Monitor Pavement	-
ASR	Medium	PCC Slab Replacement	SF
ASR	High	PCC Slab Replacement	SF

*Table 5.4.4 (b): Localized Stopgap Maintenance and Repair Policy*

Distress	Severity	Localized Work Type	Work Type Unit
Alligator Cracking	Low	Monitor Pavement	-
Alligator Cracking	Medium	AC Full-Depth Patching	SF
Alligator Cracking	High	AC Full-Depth Patching	SF
Bleeding	N/A	Monitor Pavement	-
Block Cracking	Low	Monitor Pavement	-
Block Cracking	Medium	Monitor Pavement	-
Block Cracking	High	AC Crack Sealing	LF
Corrugation	Low	Monitor Pavement	-
Corrugation	Medium	Monitor Pavement	-
Corrugation	High	AC Full-Depth Patching	SF
Depression	Low	Monitor Pavement	-
Depression	Medium	Monitor Pavement	-
Depression	High	AC Full-Depth Patching	SF
Jet Blast	N/A	Monitor Pavement	-
Jt. Reflective Cracking	Low	Monitor Pavement	-

Distress	Severity	Localized Work Type	Work Type Unit
Jt. Reflective Cracking	Medium	Monitor Pavement	-
Jt. Reflective Cracking	High	AC Crack Sealing	LF
L&T Cracking	Low	Monitor Pavement	-
L&T Cracking	Medium	Monitor Pavement	-
L&T Cracking	High	AC Crack Sealing	LF
Oil Spillage	N/A	Monitor Pavement	-
Patching	Low	Monitor Pavement	-
Patching	Medium	Monitor Pavement	-
Patching	High	AC Full-Depth Patching	SF
Polished Aggregate	N/A	Monitor Pavement	-
Raveling	Low	Monitor Pavement	-
Raveling	Medium	Monitor Pavement	-
Raveling	High	AC Partial-Depth Patching	SF
Rutting	Low	Monitor Pavement	-
Rutting	Medium	Monitor Pavement	-
Rutting	High	AC Full-Depth Patching	SF
Shoving	Low	Monitor Pavement	-
Shoving	Medium	Monitor Pavement	-
Shoving	High	AC Full-Depth Patching	SF
Slippage Cracking	N/A	AC Full-Depth Patching	SF
Swelling	Low	Monitor Pavement	-
Swelling	Medium	Monitor Pavement	-
Swelling	High	AC Full-Depth Patching	SF
Weathering	Low	Monitor Pavement	-
Weathering	Medium	Monitor Pavement	-
Weathering	High	Surface Seal	SF
Blow-up	Low	Monitor Pavement	-
Blow-up	Medium	PCC Full-Depth Patching	SF
Blow-up	High	PCC Slab Replacement	SF
Corner Break	Low	Monitor Pavement	-
Corner Break	Medium	PCC Full-Depth Patching	SF
Corner Break	High	PCC Full-Depth Patching	SF
Linear Cracking	Low	Monitor Pavement	-
Linear Cracking	Medium	PCC Crack Sealing	LF
Linear Cracking	High	PCC Crack Sealing	LF
Durability Cracking	Low	Monitor Pavement	-



Distress	Severity	Localized Work Type	Work Type Unit
Durability Cracking	Medium	PCC Full-Depth Patching	SF
Durability Cracking	High	PCC Slab Replacement	SF
Jt. Seal Damage	Low	Monitor Pavement	-
Jt. Seal Damage	Medium	Monitor Pavement	-
Jt. Seal Damage	High	PCC Joint Seal	LF
Small Patch	Low	Monitor Pavement	-
Small Patch	Medium	Monitor Pavement	-
Small Patch	High	PCC Partial-Depth Patching	SF
Large Patch	Low	Monitor Pavement	-
Large Patch	Medium	Monitor Pavement	-
Large Patch	High	PCC Full-Depth Patching	SF
Popouts	N/A	Monitor Pavement	-
Pumping	N/A	Monitor Pavement	-
Scaling	Low	Monitor Pavement	-
Scaling	Medium	Monitor Pavement	-
Scaling	High	PCC Slab Replacement	SF
Faulting	Low	Monitor Pavement	-
Faulting	Medium	Monitor Pavement	-
Faulting	High	PCC Slab Replacement	SF
Shattered Slab	Low	Monitor Pavement	-
Shattered Slab	Medium	PCC Crack Sealing	LF
Shattered Slab	High	PCC Slab Replacement	SF
Shrinkage Cracking	N/A	Monitor Pavement	-
Joint Spall	Low	Monitor Pavement	-
Joint Spall	Medium	PCC Partial-Depth Patching	SF
Joint Spall	High	PCC Partial-Depth Patching	SF
Corner Spall	Low	Monitor Pavement	-
Corner Spall	Medium	PCC Partial-Depth Patching	SF
Corner Spall	High	PCC Partial-Depth Patching	SF
ASR	Low	Monitor Pavement	-
ASR	Medium	PCC Slab Replacement	SF
ASR	High	PCC Slab Replacement	SF

## 5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

### 5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types; and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average GA Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

*Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation*

Rehabilitation Type	General Aviation Pavement Section
<b>AC Reconstruction</b>	
<p><i>Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.</i></p> <p><b>PCI = 54 or less</b></p>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (6")
	Prime Coat
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
<b>AC Rehabilitation</b>	
<p><i>Combination of asphalt pavement milling and replacement overlay with 25% of the areas subject to full-depth reconstruction.</i></p> <p><b>PCI = 55 to 69</b></p>	<b>25% AC Reconstruction</b>
	<b>Mill and Overlay</b>
	AC Milling (3")
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
<b>PCC Reconstruction</b>	
<p><i>Full-depth rigid pavement section reconstruction.</i></p> <p><b>PCI = 54 or less</b></p>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (6")
	Limerock Base Course (6")
	P-501 PCC Pavement (8")
	PCC Joint Seal
<b>PCC Rehabilitation</b>	
<p><i>Rehabilitation of PCC pavement with a combination of crack sealing, joint seal replacement, limited patching, and replacement of 25% of slab panels.</i></p> <p><b>PCI = 55 to 69</b></p>	<b>25% Slab Replacement</b>
	<b>Joint and Crack Seal</b>
	<b>Limited Patching</b>

*The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.*

### **Reconstruction (AC or PCC)**

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

### **AC Rehabilitation**

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 25% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value above 54. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

### **PCC Rehabilitation**

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 25% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value above 54.

#### **5.5.2 Major Rehabilitation Planning-Level Unit Costs**


Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.

Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.


*Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type*

<b>Rehabilitation Type</b>	<b>PCI Range</b>	<b>Asphalt Concrete Cost per SF</b>	<b>Portland Cement Concrete Cost Per SF</b>
Rehabilitation	55 to 69	\$ 7.00	\$ 14.00
Reconstruction	0 to 54	\$ 10.50	\$ 22.25





# **Chapter 6: M&R Planning and Budget Scenario Analysis**





## Chapter 6 – M&R Planning and Budget Scenario Analysis

### 6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist airport staff in determining an annual budget allocation for maintenance activities that will help maintain airport pavements above the critical PCI value and extend the life of the pavement.

**Table 6.1 (a)** provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (a): Year 1 Summary of Localized Maintenance*

Work Category	Cost
Preventive	\$ 136,420
Stopgap	\$ 15,730
<b>Planning-Level Localized M&amp;R Needs =</b>	<b>\$ 152,150</b>

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of Major Rehabilitation efforts identified through the major rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

**Table 6.1 (b)** summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary*

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	Surface Seal	20,891	SF	\$ 10,520
	PCC Joint Seal	38,733	LF	\$ 125,900
Localized Stopgap Maintenance	AC Partial-Depth Patching	413	SF	\$ 1,570
	AC Full-Depth Patching	1,887	SF	\$ 14,160

**Table 6.1 (c)** provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved “End Condition” PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary*

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
PMP	RW 10-28	6105	271,200	64	64	\$ -
PMP	RW 10-28	6115	58,320	85	85	\$ -
PMP	RW 15-33	6305	220,900	89	91	\$ 4,150
PMP	RW 15-33	6310	441,800	90	92	\$ 2,330
PMP	RW 15-33	6325	25,000	82	82	\$ -
PMP	RW 15-33	6330	50,000	92	92	\$ -
PMP	RW 6-24	6205	335,952	60	60	\$ -
PMP	RW 6-24	6210	167,976	62	62	\$ -
PMP	RW 6-24	6220	35,000	91	94	\$ 470
PMP	RW 6-24	6225	17,500	91	91	\$ -
PMP	TW A	105	61,729	90	90	\$ -
PMP	TW A	115	13,967	47	47	\$ -
PMP	TW B	210	104,085	59	59	\$ -
PMP	TW C	305	26,289	64	64	\$ -
PMP	TW C	350	6,807	92	92	\$ -
PMP	TW C	360	9,668	92	92	\$ -
PMP	TW D	405	90,211	100	100	\$ -
PMP	TW D	410	12,212	92	92	\$ -
PMP	TW D	412	24,824	83	83	\$ -
PMP	TW D	415	36,063	82	82	\$ -
PMP	TW D	420	20,401	40	40	\$ -
PMP	TW E	505	12,246	89	89	\$ -
PMP	TW F	610	120,125	59	59	\$ -
PMP	TW F	612	15,275	93	93	\$ -
PMP	TW F	615	8,519	95	95	\$ -
PMP	TW F	620	8,073	89	89	\$ -
PMP	TW G	710	15,387	89	90	\$ 10
PMP	TW G	715	17,469	90	90	\$ -

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
PMP	TW G	720	151,212	92	92	\$ -
PMP	TW G	725	33,591	86	89	\$ 840
PMP	TW G1	700	21,726	90	91	\$ 50
PMP	TW G3	730	15,789	93	93	\$ -
PMP	TW G4	740	12,199	92	92	\$ -
PMP	TW G5	750	16,699	91	91	\$ -
PMP	TW K	1110	89,261	92	92	\$ -
PMP	TW K	1115	7,373	83	87	\$ 190
PMP	TW K	1120	14,097	90	90	\$ -
PMP	TW L	1202	21,209	62	62	\$ -
PMP	TW L	1205	13,025	51	51	\$ -
PMP	TW L	1210	152,867	60	60	\$ -
PMP	TW L	1215	14,829	87	92	\$ 750
PMP	TW M	1305	27,738	68	68	\$ -
PMP	TW M	1306	29,856	81	83	\$ 100
PMP	TW M	1310	24,002	82	83	\$ 50
PMP	TW M	1315	16,359	69	69	\$ -
PMP	TW M	1320	69,823	64	64	\$ -
PMP	TW M	1322	30,907	93	93	\$ -
PMP	TW M	1325	8,073	90	90	\$ -
PMP	TW M	1330	12,988	64	64	\$ -
PMP	TW N	1405	33,887	79	84	\$ 850
PMP	TL T-HANG	4305	31,764	36	38	\$ 450
PMP	TL T-HANG	4310	49,387	27	27	\$ -
PMP	TL T-HANG	4315	57,861	44	53	\$ 14,420
PMP	TL T-HANG	4320	16,033	34	34	\$ -
PMP	TL T-HANG	4325	16,764	81	81	\$ -
PMP	AP N	4205	72,380	58	58	\$ -
PMP	AP RU 33	5105	14,310	86	91	\$ 720
PMP	AP RU 33	5110	20,490	57	57	\$ -
PMP	AP S	4105	215,925	62	62	\$ -
PMP	AP S	4107	3,846	86	98	\$ 940
PMP	AP S	4110	26,025	47	47	\$ -
PMP	AP S	4112	135,533	90	90	\$ -
PMP	AP S	4125	105,525	37	37	\$ 850
PMP	AP S	4130	71,613	55	55	\$ -
PMP	AP S	4135	128,753	93	93	\$ -
PMP	AP SW	4405	118,367	87	99	\$ 104,530
PMP	AP SW	4410	63,093	81	93	\$ 20,430
PMP	AP SW	4415	93,557	100	100	\$ -

## 6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b) and (c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

### 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- » An estimation of current pavement condition;
- » Major pavement rehabilitation needs based on condition and policies; and
- » Planning-level cost estimates for the major rehabilitation needs.

**Table 6.2.1 (a)** summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.


*Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2021	PMP	RW 10-28	6105	AAC	271,200	63	AC Rehabilitation	\$ 1,899,000
2021	PMP	RW 6-24	6205	AAC	335,952	59	AC Rehabilitation	\$ 2,352,000
2021	PMP	RW 6-24	6210	AAC	167,976	61	AC Rehabilitation	\$ 1,176,000
2021	PMP	TW A	115	AAC	13,967	46	AC Reconstruction	\$ 147,000
2021	PMP	TW B	210	AAC	104,085	59	AC Rehabilitation	\$ 729,000
2021	PMP	TW C	305	AC	26,289	64	AC Rehabilitation	\$ 185,000
2021	PMP	TW D	420	AAC	20,401	39	AC Reconstruction	\$ 215,000
2021	PMP	TW F	610	AAC	120,125	59	AC Rehabilitation	\$ 841,000
2021	PMP	TW L	1202	AAC	21,209	62	AC Rehabilitation	\$ 149,000
2021	PMP	TW L	1205	AC	13,025	51	AC Reconstruction	\$ 137,000
2021	PMP	TW L	1210	AAC	152,867	60	AC Rehabilitation	\$ 1,071,000
2021	PMP	TW M	1305	AC	27,738	68	AC Rehabilitation	\$ 195,000
2021	PMP	TW M	1315	AC	16,359	69	AC Rehabilitation	\$ 115,000
2021	PMP	TW M	1320	AAC	69,823	64	AC Rehabilitation	\$ 489,000
2021	PMP	TW M	1330	AAC	12,988	64	AC Rehabilitation	\$ 91,000
2021	PMP	TL T-HANG	4305	AC	31,764	36	AC Reconstruction	\$ 334,000
2021	PMP	TL T-HANG	4310	AC	49,387	27	AC Reconstruction	\$ 519,000
2021	PMP	TL T-HANG	4315	AC	57,861	44	AC Reconstruction	\$ 608,000
2021	PMP	TL T-HANG	4320	APC	16,033	33	AC Reconstruction	\$ 169,000
2021	PMP	AP N	4205	AAC	72,380	58	AC Rehabilitation	\$ 507,000
2021	PMP	AP RU 33	5110	AAC	20,490	57	AC Rehabilitation	\$ 144,000
2021	PMP	AP S	4105	AAC	215,925	62	AC Rehabilitation	\$ 1,512,000
2021	PMP	AP S	4110	AC	26,025	47	AC Reconstruction	\$ 274,000
2021	PMP	AP S	4125	AC	105,525	37	AC Reconstruction	\$ 1,109,000
2021	PMP	AP S	4130	AAC	71,613	55	AC Rehabilitation	\$ 502,000
2028	PMP	TW N	1405	AC	33,887	69	AC Rehabilitation	\$ 238,000
2029	PMP	RW 10-28	6115	AAC	58,320	68	AC Rehabilitation	\$ 409,000
2029	PMP	TW M	1306	AC	29,856	69	AC Rehabilitation	\$ 209,000
2029	PMP	TL T-HANG	4325	AAC	16,764	69	AC Rehabilitation	\$ 118,000
2029	PMP	AP RU 33	5105	AAC	14,310	68	AC Rehabilitation	\$ 101,000
2030	PMP	RW 15-33	6325	AC	25,000	69	AC Rehabilitation	\$ 176,000
2030	PMP	TW D	412	AAC	24,824	69	AC Rehabilitation	\$ 174,000
2030	PMP	TW D	415	AAC	36,063	69	AC Rehabilitation	\$ 253,000
2030	PMP	TW K	1115	AC	7,373	69	AC Rehabilitation	\$ 52,000
2030	PMP	TW M	1310	AC	24,002	68	AC Rehabilitation	\$ 169,000

**Figure 6.2.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2021 and 2030. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.



*Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year*







# Chapter 7: Conclusion





## Chapter 7 – Conclusion

### 7.1 Recommendations

#### 7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-12 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective airport maintenance staff and airport engineer when developing project-level maintenance and repair efforts.

#### 7.1.3 Major Rehabilitation

**Chapter 6** also identified major pavement rehabilitation project needs from 2021-2030. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

#### 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- » Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in **Section 6.1**;
- » Further refine and implement the identified 10-year major rehabilitation needs provided in **Section 6.2**;
- » Maintain detailed records on pavement maintenance, construction, and inspection; and
- » Maintain records on major pavement construction projects (year, scope, cost, and construction documents).

## 7.2 Supporting Documents

### Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-12. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

### Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

### Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

### Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-12 (referenced in **Appendix E**), with results being analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-12 condition rating categories.

### Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

### Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.



## 7.3 Conclusion

The FDOT SAPMP System Update Phase 1 2020-2021 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-12.

## 7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- » ASTM D5340-12, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- » AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- » AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- » AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- » Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- » Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- » Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.

A photograph of a long, straight asphalt runway stretching towards the horizon under a bright blue sky with scattered white clouds. The runway has a central white dashed line and yellow edge lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Appendix A: Airfield Pavement Analysis**

A close-up, low-angle view of the runway pavement, showing a white dashed line and yellow chevron markings. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

*Table A.1: Pavement System Inventory Details*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
PMP	RW 10-28	Runway	6105	271,200	AAC	1/1/2000
PMP	RW 10-28	Runway	6115	58,320	AAC	1/1/2012
PMP	RW 15-33	Runway	6305	220,900	AAC	1/1/2012
PMP	RW 15-33	Runway	6310	441,800	AAC	1/1/2012
PMP	RW 15-33	Runway	6325	25,000	AC	6/1/2012
PMP	RW 15-33	Runway	6330	50,000	AC	6/1/2012
PMP	RW 6-24	Runway	6205	335,952	AAC	1/1/2001
PMP	RW 6-24	Runway	6210	167,976	AAC	1/1/2001
PMP	RW 6-24	Runway	6220	35,000	AAC	1/1/2012
PMP	RW 6-24	Runway	6225	17,500	AAC	1/1/2012
PMP	TW A	Taxiway	105	61,729	AAC	11/1/2012
PMP	TW A	Taxiway	115	13,967	AAC	1/1/1997
PMP	TW B	Taxiway	210	104,085	AAC	1/1/1972
PMP	TW C	Taxiway	305	26,289	AC	1/1/1970
PMP	TW C	Taxiway	350	6,807	AAC	11/1/2012
PMP	TW C	Taxiway	360	9,668	AAC	11/1/2012
PMP	TW D	Taxiway	405	90,211	AAC	1/1/2021
PMP	TW D	Taxiway	410	12,212	AAC	5/1/2018
PMP	TW D	Taxiway	412	24,824	AAC	5/1/2018
PMP	TW D	Taxiway	415	36,063	AAC	11/1/2012
PMP	TW D	Taxiway	420	20,401	AAC	1/1/2008
PMP	TW E	Taxiway	505	12,246	AAC	1/1/2012
PMP	TW F	Taxiway	610	120,125	AAC	1/1/1972
PMP	TW F	Taxiway	612	15,275	AAC	5/1/2018
PMP	TW F	Taxiway	615	8,519	AAC	5/1/2018
PMP	TW F	Taxiway	620	8,073	AAC	1/1/2012
PMP	TW G	Taxiway	710	15,387	AC	6/1/2012
PMP	TW G	Taxiway	715	17,469	AC	6/1/2014
PMP	TW G	Taxiway	720	151,212	AC	5/1/2018
PMP	TW G	Taxiway	725	33,591	AC	6/1/2012
PMP	TW G1	Taxiway	700	21,726	AC	6/1/2012
PMP	TW G3	Taxiway	730	15,789	AC	5/1/2018
PMP	TW G4	Taxiway	740	12,199	AC	5/1/2018
PMP	TW G5	Taxiway	750	16,699	AC	5/1/2018
PMP	TW K	Taxiway	1110	89,261	AC	11/1/2012
PMP	TW K	Taxiway	1115	7,373	AC	6/1/2014
PMP	TW K	Taxiway	1120	14,097	AC	6/1/2012
PMP	TW L	Taxiway	1202	21,209	AAC	1/1/1996
PMP	TW L	Taxiway	1205	13,025	AC	1/1/1972
PMP	TW L	Taxiway	1210	152,867	AAC	1/1/1996
PMP	TW L	Taxiway	1215	14,829	AAC	6/1/2012
PMP	TW M	Taxiway	1305	27,738	AC	1/1/1970
PMP	TW M	Taxiway	1306	29,856	AC	11/1/2012
PMP	TW M	Taxiway	1310	24,002	AC	1/1/1999



# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
PMP	TW M	Taxiway	1315	16,359	AC	1/1/1999
PMP	TW M	Taxiway	1320	69,823	AAC	1/1/2001
PMP	TW M	Taxiway	1322	30,907	AC	5/1/2018
PMP	TW M	Taxiway	1325	8,073	AAC	1/1/2012
PMP	TW M	Taxiway	1330	12,988	AAC	1/1/2001
PMP	TW N	Taxiway	1405	33,887	AC	1/1/2004
PMP	TL T-HANG	Taxilane	4305	31,764	AC	12/25/1999
PMP	TL T-HANG	Taxilane	4310	49,387	AC	12/25/1999
PMP	TL T-HANG	Taxilane	4315	57,861	AC	12/25/1999
PMP	TL T-HANG	Taxilane	4320	16,033	APC	12/25/1999
PMP	TL T-HANG	Taxilane	4325	16,764	AAC	6/1/2018
PMP	AP N	Apron	4205	72,380	AAC	1/1/1972
PMP	AP RU 33	Apron	5105	14,310	AAC	6/1/2012
PMP	AP RU 33	Apron	5110	20,490	AAC	1/1/1996
PMP	AP S	Apron	4105	215,925	AAC	1/1/1997
PMP	AP S	Apron	4107	3,846	PCC	1/1/2015
PMP	AP S	Apron	4110	26,025	AC	1/1/1960
PMP	AP S	Apron	4112	135,533	AC	5/17/2013
PMP	AP S	Apron	4125	105,525	AC	12/25/1999
PMP	AP S	Apron	4130	71,613	AAC	1/1/2015
PMP	AP S	Apron	4135	128,753	AC	1/1/2015
PMP	AP SW	Apron	4405	118,367	PCC	1/1/2015
PMP	AP SW	Apron	4410	63,093	PCC	1/1/2012
PMP	AP SW	Apron	4415	93,557	PCC	7/1/2019

*Table A.2: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	RW 10-28	Runway	6105	271,200	64	Fair
PMP	RW 10-28	Runway	6115	58,320	85	Satisfactory
PMP	RW 15-33	Runway	6305	220,900	89	Good
PMP	RW 15-33	Runway	6310	441,800	90	Good
PMP	RW 15-33	Runway	6325	25,000	82	Satisfactory
PMP	RW 15-33	Runway	6330	50,000	92	Good
PMP	RW 6-24	Runway	6205	335,952	60	Fair
PMP	RW 6-24	Runway	6210	167,976	62	Fair
PMP	RW 6-24	Runway	6220	35,000	91	Good
PMP	RW 6-24	Runway	6225	17,500	91	Good
PMP	TW A	Taxiway	105	61,729	90	Good
PMP	TW A	Taxiway	115	13,967	47	Poor
PMP	TW B	Taxiway	210	104,085	59	Fair
PMP	TW C	Taxiway	305	26,289	64	Fair
PMP	TW C	Taxiway	350	6,807	92	Good
PMP	TW C	Taxiway	360	9,668	92	Good
PMP	TW D	Taxiway	405	90,211	100	Good
PMP	TW D	Taxiway	410	12,212	92	Good
PMP	TW D	Taxiway	412	24,824	83	Satisfactory
PMP	TW D	Taxiway	415	36,063	82	Satisfactory
PMP	TW D	Taxiway	420	20,401	40	Very Poor
PMP	TW E	Taxiway	505	12,246	89	Good
PMP	TW F	Taxiway	610	120,125	59	Fair
PMP	TW F	Taxiway	612	15,275	93	Good
PMP	TW F	Taxiway	615	8,519	95	Good
PMP	TW F	Taxiway	620	8,073	89	Good
PMP	TW G	Taxiway	710	15,387	89	Good
PMP	TW G	Taxiway	715	17,469	90	Good
PMP	TW G	Taxiway	720	151,212	92	Good
PMP	TW G	Taxiway	725	33,591	86	Good
PMP	TW G1	Taxiway	700	21,726	90	Good
PMP	TW G3	Taxiway	730	15,789	93	Good
PMP	TW G4	Taxiway	740	12,199	92	Good
PMP	TW G5	Taxiway	750	16,699	91	Good
PMP	TW K	Taxiway	1110	89,261	92	Good
PMP	TW K	Taxiway	1115	7,373	83	Satisfactory
PMP	TW K	Taxiway	1120	14,097	90	Good
PMP	TW L	Taxiway	1202	21,209	62	Fair
PMP	TW L	Taxiway	1205	13,025	51	Poor
PMP	TW L	Taxiway	1210	152,867	60	Fair
PMP	TW L	Taxiway	1215	14,829	87	Good
PMP	TW M	Taxiway	1305	27,738	68	Fair
PMP	TW M	Taxiway	1306	29,856	81	Satisfactory
PMP	TW M	Taxiway	1310	24,002	82	Satisfactory
PMP	TW M	Taxiway	1315	16,359	69	Fair



# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
PMP	TW M	Taxiway	1320	69,823	64	Fair
PMP	TW M	Taxiway	1322	30,907	93	Good
PMP	TW M	Taxiway	1325	8,073	90	Good
PMP	TW M	Taxiway	1330	12,988	64	Fair
PMP	TW N	Taxiway	1405	33,887	79	Satisfactory
PMP	TL T-HANG	Taxilane	4305	31,764	36	Very Poor
PMP	TL T-HANG	Taxilane	4310	49,387	27	Very Poor
PMP	TL T-HANG	Taxilane	4315	57,861	44	Poor
PMP	TL T-HANG	Taxilane	4320	16,033	34	Very Poor
PMP	TL T-HANG	Taxilane	4325	16,764	81	Satisfactory
PMP	AP N	Apron	4205	72,380	58	Fair
PMP	AP RU 33	Apron	5105	14,310	86	Good
PMP	AP RU 33	Apron	5110	20,490	57	Fair
PMP	AP S	Apron	4105	215,925	62	Fair
PMP	AP S	Apron	4107	3,846	86	Good
PMP	AP S	Apron	4110	26,025	47	Poor
PMP	AP S	Apron	4112	135,533	90	Good
PMP	AP S	Apron	4125	105,525	37	Very Poor
PMP	AP S	Apron	4130	71,613	55	Poor
PMP	AP S	Apron	4135	128,753	93	Good
PMP	AP SW	Apron	4405	118,367	87	Good
PMP	AP SW	Apron	4410	63,093	81	Satisfactory
PMP	AP SW	Apron	4415	93,557	100	Good

*Table A.3: Forecasted PCI Values 2021-2030 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI									
				2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
PMP	RW 10-28	6105	64	63	61	59	57	55	53	51	49	47	45
PMP	RW 10-28	6115	85	84	82	80	78	76	74	72	70	68	66
PMP	RW 15-33	6305	89	88	86	84	82	80	78	76	74	72	70
PMP	RW 15-33	6310	90	89	87	85	83	81	79	77	75	73	71
PMP	RW 15-33	6325	82	82	80	79	77	76	74	73	72	71	69
PMP	RW 15-33	6330	92	91	90	88	86	84	83	81	80	78	77
PMP	RW 6-24	6205	60	59	57	55	53	51	49	47	45	43	41
PMP	RW 6-24	6210	62	61	59	57	55	53	51	49	47	45	43
PMP	RW 6-24	6220	91	90	88	86	84	82	80	78	76	74	72
PMP	RW 6-24	6225	91	90	88	86	84	82	80	78	76	74	72
PMP	TW A	105	90	89	87	85	83	81	79	78	76	75	73
PMP	TW A	115	47	46	44	42	39	36	33	30	27	24	21
PMP	TW B	210	59	59	57	56	54	53	51	49	47	45	42
PMP	TW C	305	64	64	63	62	61	61	60	59	58	58	57
PMP	TW C	350	92	91	89	86	84	82	81	79	77	76	74
PMP	TW C	360	92	91	89	86	84	82	81	79	77	76	74
PMP	TW D	405	100	99	96	93	91	88	86	84	82	80	79
PMP	TW D	410	92	91	89	86	84	82	81	79	77	76	74
PMP	TW D	412	83	82	81	79	77	76	74	73	72	70	69
PMP	TW D	415	82	81	80	78	76	75	74	72	71	70	69
PMP	TW D	420	40	39	36	33	30	27	24	21	18	15	12
PMP	TW E	505	89	88	86	84	82	80	79	77	75	74	73
PMP	TW F	610	59	59	57	56	54	53	51	49	47	45	42
PMP	TW F	612	93	92	90	87	85	83	81	80	78	76	75
PMP	TW F	615	95	94	91	89	87	85	83	81	79	77	76
PMP	TW F	620	89	88	86	84	82	80	79	77	75	74	73
PMP	TW G	710	89	88	86	84	83	81	79	77	76	74	73
PMP	TW G	715	90	89	87	85	83	82	80	78	77	75	74
PMP	TW G	720	92	91	89	87	85	83	81	80	78	77	75
PMP	TW G	725	86	85	83	82	80	78	77	75	74	72	71
PMP	TW G1	700	90	89	87	85	83	82	80	78	77	75	74
PMP	TW G3	730	93	92	90	88	86	84	82	80	79	77	76
PMP	TW G4	740	92	91	89	87	85	83	81	80	78	77	75
PMP	TW G5	750	91	90	88	86	84	82	81	79	77	76	74
PMP	TW K	1110	92	91	89	87	85	83	81	80	78	77	75
PMP	TW K	1115	83	82	81	79	77	76	74	73	72	70	69
PMP	TW K	1120	90	89	87	85	83	82	80	78	77	75	74
PMP	TW L	1202	62	62	61	59	58	56	55	53	51	49	47
PMP	TW L	1205	51	51	51	50	50	50	49	49	48	48	47
PMP	TW L	1210	60	60	58	57	55	54	52	50	48	46	44
PMP	TW L	1215	87	86	84	82	80	79	77	76	74	73	72
PMP	TW M	1305	68	68	67	66	65	64	63	62	61	60	60
PMP	TW M	1306	81	80	79	77	76	74	73	71	70	69	68
PMP	TW M	1310	82	81	80	78	77	75	74	72	71	70	68

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI									
				2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
PMP	TW M	1315	69	69	68	67	66	65	64	63	62	61	60
PMP	TW M	1320	64	64	63	61	60	59	57	56	54	53	51
PMP	TW M	1322	93	92	90	88	86	84	82	80	79	77	76
PMP	TW M	1325	90	89	87	85	83	81	79	78	76	75	73
PMP	TW M	1330	64	64	63	61	60	59	57	56	54	53	51
PMP	TW N	1405	79	79	77	75	74	73	71	70	69	68	67
PMP	TL T-HANG	4305	36	36	35	34	33	31	30	29	27	26	24
PMP	TL T-HANG	4310	27	27	25	24	22	20	19	17	16	14	12
PMP	TL T-HANG	4315	44	44	43	43	42	41	41	40	39	38	37
PMP	TL T-HANG	4320	34	33	30	26	23	20	17	14	11	8	5
PMP	TL T-HANG	4325	81	80	79	77	76	74	73	72	70	69	68
PMP	AP N	4205	58	58	56	55	54	53	52	51	49	48	47
PMP	AP RU 33	5105	86	85	83	80	78	76	74	72	70	68	67
PMP	AP RU 33	5110	57	57	56	54	53	52	51	50	49	47	46
PMP	AP S	4105	62	62	60	59	58	56	55	54	53	52	51
PMP	AP S	4107	86	86	85	84	83	82	81	80	79	78	77
PMP	AP S	4110	47	47	47	46	45	45	44	44	43	43	42
PMP	AP S	4112	90	89	87	85	83	81	79	77	76	74	72
PMP	AP S	4125	37	37	37	36	36	35	35	34	34	33	33
PMP	AP S	4130	55	55	54	52	51	50	49	48	47	45	44
PMP	AP S	4135	93	92	90	88	86	84	82	80	78	76	74
PMP	AP SW	4405	87	87	86	85	84	83	82	81	80	79	78
PMP	AP SW	4410	81	81	80	79	78	77	76	75	74	73	72
PMP	AP SW	4415	100	98	97	96	95	94	93	92	91	90	89

3/3/2021

## Work History Report

Page 1 of 13

Pavement Database: FDOT

Network: POMPANO BEACH		Branch: AP N	NORTH APRON -		Section: 4205	Surface: AAC
L.C.D. 1/1/1972	Use: APRON	Rank: P	Length: 785.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 72380.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: AP RU 33	RUN-UP APRON		Section: 5105	Surface: AAC
L.C.D. 6/1/2012	Use: APRON	Rank: P	Length: 100.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 14310.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED 1950 BIT SECTION U
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1950	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: AP RU 33	RUN-UP APRON		Section: 5110	Surface: AAC
L.C.D. 1/1/1996	Use: APRON	Rank: P	Length: 200.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 20490.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1996	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Estimated Construction Date
1/1/1950	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: AP S	SOUTH APRON		Section: 4105	Surface: AAC
L.C.D. 1/1/1997	Use: APRON	Rank: P	Length: 2,225.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 215925.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1997	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1997 STRUCTURAL AC OVERLAY
1/1/1970	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	EST 1970 AC PAVEMENT

Network: POMPANO BEACH		Branch: AP S	SOUTH APRON		Section: 4107	Surface: PCC
L.C.D. 1/1/2015	Use: APRON	Rank: P	Length: 110.00 (Ft)	Width: 35.00 (Ft)	Est. Area: 3846.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: AP S	SOUTH APRON		Section: 4110	Surface: AC
L.C.D. 1/1/1960	Use: APRON	Rank: P	Length: 450.00 (Ft)	Width: 45.00 (Ft)	Est. Area: 26025.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1960	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1960 BIT SECTION UNKNOWN

Network: POMPANO BEACH		Branch: AP S	SOUTH APRON		Section: 4112	Surface: AC
L.C.D. 5/17/2013	Use: APRON	Rank: P	Length: 900.00 (Ft)	Width: 150.00 (Ft)	Est. Area: 135533.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/17/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	



3/3/2021

## Work History Report

Page 2 of 13

Pavement Database: FDOT

Network: POMPANO BEACH Branch: AP S SOUTH APRON Section: 4125 Surface: AC  
 L.C.D. 12/25/1999 Use: APRON Rank: P Length: 209.00 (Ft) Width: 500.00 (Ft) Est. Area: 105525.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH Branch: AP S SOUTH APRON Section: 4130 Surface: AAC  
 L.C.D. 1/1/2015 Use: APRON Rank: P Length: 500.00 (Ft) Width: 150.00 (Ft) Est. Area: 71613.00002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH Branch: AP S SOUTH APRON Section: 4135 Surface: AC  
 L.C.D. 1/1/2015 Use: APRON Rank: P Length: 1,300.00 (Ft) Width: 100.00 (Ft) Est. Area: 128753.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH Branch: AP SW SOUTHWEST AP Section: 4405 Surface: PCC  
 L.C.D. 1/1/2015 Use: APRON Rank: P Length: 685.00 (Ft) Width: 355.00 (Ft) Est. Area: 118367.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-PC	New Construction - PCC			<input checked="" type="checkbox"/>	

Network: POMPANO BEACH Branch: AP SW SOUTHWEST AP Section: 4410 Surface: PCC  
 L.C.D. 1/1/2012 Use: APRON Rank: P Length: 1,000.00 (Ft) Width: 50.00 (Ft) Est. Area: 63093.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED CONSTRUCTION

Network: POMPANO BEACH Branch: AP SW SOUTHWEST AP Section: 4415 Surface: PCC  
 L.C.D. 7/1/2019 Use: APRON Rank: P Length: 545.00 (Ft) Width: 310.00 (Ft) Est. Area: 93557.00002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	NC-PC	New Construction - PCC			<input checked="" type="checkbox"/>	

Network: POMPANO BEACH Branch: RW 10-28 RUNWAY 10-28 Section: 6105 Surface: AAC  
 L.C.D. 1/1/2000 Use: RUNWAY Rank: P Length: 935.00 (Ft) Width: 100.00 (Ft) Est. Area: 271200.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2000	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1968	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1968 1.5" BIT 6" LIMEROCK

3/3/2021

## Work History Report

Page 3 of 13

Pavement Database: FDOT

Network: POMPANO BEACH		Branch: RW 10-28	RUNWAY 10-28		Section: 6115	Surface: AAC
L.C.D. 1/1/2012	Use: RUNWAY	Rank: P	Length: 225.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 58320.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1968 1.5" BIT 6" LIMEROCK
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1968	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: RW 15-33	RUNWAY 15-33		Section: 6305	Surface: AAC
L.C.D. 1/1/2012	Use: RUNWAY	Rank: P	Length: 4,220.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 220900.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1969 1.5" P-401 OL ON EXISTING R/W
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1969	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: RW 15-33	RUNWAY 15-33		Section: 6310	Surface: AAC
L.C.D. 1/1/2012	Use: RUNWAY	Rank: P	Length: 8,400.00 (Ft)	Width: 25.00 (Ft)	Est. Area: 441800.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1969 1.5" P-401 OL ON EXISTING R/W
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1969	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: RW 15-33	RUNWAY 15-33		Section: 6325	Surface: AC
L.C.D. 6/1/2012	Use: RUNWAY	Rank: P	Length: 500.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 25000.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401, 8" P-211 LIMEROCK, 12"
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	

Network: POMPANO BEACH		Branch: RW 15-33	RUNWAY 15-33		Section: 6330	Surface: AC
L.C.D. 6/1/2012	Use: RUNWAY	Rank: P	Length: 500.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 50000.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401, 8" P-211 LIMEROCK BAS
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	

Network: POMPANO BEACH		Branch: RW 6-24	RUNWAY 6-24		Section: 6205	Surface: AAC
L.C.D. 1/1/2001	Use: RUNWAY	Rank: P	Length: 2,875.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 335952.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING R/W
1/1/2001	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

3/3/2021

## Work History Report

Page 4 of 13

Pavement Database: FDOT

Network: POMPANO BEACH		Branch: RW 6-24	RUNWAY 6-24		Section: 6210	Surface: AAC
L.C.D. 1/1/2001	Use: RUNWAY	Rank: P	Length: 6,100.00 (Ft)	Width: 25.00 (Ft)	Est. Area: 167976.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING R/W
1/1/2001	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: RW 6-24	RUNWAY 6-24		Section: 6220	Surface: AAC
L.C.D. 1/1/2012	Use: RUNWAY	Rank: P	Length: 350.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 35000.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1972	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1969	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1969 P-401 OL ON EXISTING

Network: POMPANO BEACH		Branch: RW 6-24	RUNWAY 6-24		Section: 6225	Surface: AAC
L.C.D. 1/1/2012	Use: RUNWAY	Rank: P	Length: 750.00 (Ft)	Width: 25.00 (Ft)	Est. Area: 17500.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1972	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TL T-HANG T-HANGAR TAX	Section: 4305		Surface: AC	
L.C.D. 12/25/199	Use: TAXILAN	Rank: P	Length: 675.00 (Ft)	Width: 25.00 (Ft)	Est. Area: 31764.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TL T-HANG T-HANGAR TAX	Section: 4310		Surface: AC	
L.C.D. 12/25/199	Use: TAXILAN	Rank: P	Length: 1,850.00 (Ft)	Width: 25.00 (Ft)	Est. Area: 49387.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TL T-HANG T-HANGAR TAX	Section: 4315		Surface: AC	
L.C.D. 12/25/199	Use: TAXILAN	Rank: P	Length: 2,530.00 (Ft)	Width: 18.00 (Ft)	Est. Area: 57861.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

3/3/2021

## Work History Report

Page 5 of 13

Pavement Database: FDOT

Network: POMPANO BEACH		Branch: TL T-HANG T-HANGAR TAX		Section: 4320		Surface: APC
L.C.D. 12/25/199	Use: TAXILAN	Rank: P	Length: 200.00 (Ft)	Width: 40.00 (Ft)	Est. Area: 16033.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED INITIAL CONSTRUCT
1/1/1972	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TL T-HANG T-HANGAR TAX		Section: 4325		Surface: AAC
L.C.D. 6/1/2018	Use: TAXILAN	Rank: P	Length: 405.00 (Ft)	Width: 55.00 (Ft)	Est. Area: 16764.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW A TAXIWAY A		Section: 105		Surface: AAC
L.C.D. 11/1/2012	Use: TAXIWAY	Rank: P	Length: 1,500.00 (Ft)	Width: 40.00 (Ft)	Est. Area: 61729.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1968 1.5" BIT 6" LIMEROCK
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1968	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW A TAXIWAY A		Section: 115		Surface: AAC
L.C.D. 1/1/1997	Use: TAXIWAY	Rank: P	Length: 350.00 (Ft)	Width: 40.00 (Ft)	Est. Area: 13967.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1997: AC OVERLAY
1/1/1997	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1950	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW B TAXIWAY B		Section: 210		Surface: AAC
L.C.D. 1/1/1972	Use: TAXIWAY	Rank: P	Length: 2,190.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 104085.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW C TAXIWAY C		Section: 305		Surface: AC
L.C.D. 1/1/1970	Use: TAXIWAY	Rank: P	Length: 650.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 26289.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EST 1970 BIT SECTION UNKNOWN
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

3/3/2021

## Work History Report

Page 6 of 13

Pavement Database: FDOT

Network: POMPANO BEACH		Branch: TW C	TAXIWAY C		Section: 350	Surface: AAC
L.C.D. 11/1/2012	Use: TAXIWAY	Rank: P	Length: 212.00 (Ft)	Width: 40.00 (Ft)	Est. Area: 6807.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401 MILL AND OVERLAY
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1970 BIT SECTION UNKNOWN

Network: POMPANO BEACH		Branch: TW C	TAXIWAY C		Section: 360	Surface: AAC
L.C.D. 11/1/2012	Use: TAXIWAY	Rank: P	Length: 132.00 (Ft)	Width: 40.00 (Ft)	Est. Area: 9668.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401 MILL AND OVERLAY
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1968	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1968 1.5" BIT 6" LIMEROCK

Network: POMPANO BEACH		Branch: TW D	TAXIWAY D		Section: 405	Surface: AAC
L.C.D. 1/1/2021	Use: TAXIWAY	Rank: P	Length: 1,464.00 (Ft)	Width: 35.00 (Ft)	Est. Area: 90211.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1" Mill, 2.5" P-401
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING

Network: POMPANO BEACH		Branch: TW D	TAXIWAY D		Section: 410	Surface: AAC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 180.00 (Ft)	Width: 80.00 (Ft)	Est. Area: 12212.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Variable Mill, 2.5" P-401
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING

Network: POMPANO BEACH		Branch: TW D	TAXIWAY D		Section: 412	Surface: AAC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 560.00 (Ft)	Width: 35.00 (Ft)	Est. Area: 24824.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Variable Mill, 2.5" P-401
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING



3/3/2021

## Work History Report

Page 7 of 13

Pavement Database: FDOT

Network: POMPANO BEACH Branch: TW D TAXIWAY D Section: 415 Surface: AAC  
 L.C.D. 11/1/2012 Use: TAXIWAY Rank: P Length: 400.00 (Ft) Width: 50.00 (Ft) Est. Area: 36063.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401 MILL AND OVERLAY
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING

Network: POMPANO BEACH Branch: TW D TAXIWAY D Section: 420 Surface: AAC  
 L.C.D. 1/1/2008 Use: TAXIWAY Rank: P Length: 200.00 (Ft) Width: 95.00 (Ft) Est. Area: 20401.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1972	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH Branch: TW E TAXIWAY E Section: 505 Surface: AAC  
 L.C.D. 1/1/2012 Use: TAXIWAY Rank: P Length: 200.00 (Ft) Width: 40.00 (Ft) Est. Area: 12246.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1968	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1968 1.5" BIT 6" LIMEROCK

Network: POMPANO BEACH Branch: TW F TAXIWAY F Section: 610 Surface: AAC  
 L.C.D. 1/1/1972 Use: TAXIWAY Rank: P Length: 2,515.00 (Ft) Width: 50.00 (Ft) Est. Area: 120125.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1972	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING

Network: POMPANO BEACH Branch: TW F TAXIWAY F Section: 612 Surface: AAC  
 L.C.D. 5/1/2018 Use: TAXIWAY Rank: P Length: 300.00 (Ft) Width: 50.00 (Ft) Est. Area: 15275.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1972	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL ON EXISTING

3/3/2021

## Work History Report

Page 8 of 13

Pavement Database: FDOT

Network: POMPAN BEACH		Branch: TW F	TAXIWAY F		Section: 615	Surface: AAC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 125.00 (Ft)	Width: 55.00 (Ft)	Est. Area: 8519.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1972	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1969	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1969 1.5" P-401 OL ON EXISTING

Network: POMPAN BEACH		Branch: TW F	TAXIWAY F		Section: 620	Surface: AAC
L.C.D. 1/1/2012	Use: TAXIWAY	Rank: P	Length: 140.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 8073.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1972 1.5" P-401 OL
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1972	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1969	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1969 1.5" P-401 OL ON EXISTING

Network: POMPAN BEACH		Branch: TW G1	TAXIWAY G1		Section: 700	Surface: AC
L.C.D. 6/1/2012	Use: TAXIWAY	Rank: P	Length: 600.00 (Ft)	Width: 35.00 (Ft)	Est. Area: 21726.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401, 8" P-211 LIMEROCK BAS

Network: POMPAN BEACH		Branch: TW G3	TAXIWAY G3		Section: 730	Surface: AC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 148.00 (Ft)	Width: 75.00 (Ft)	Est. Area: 15789.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: POMPAN BEACH		Branch: TW G4	TAXIWAY G4		Section: 740	Surface: AC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 139.00 (Ft)	Width: 70.00 (Ft)	Est. Area: 12199.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: POMPAN BEACH		Branch: TW G5	TAXIWAY G5		Section: 750	Surface: AC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 150.00 (Ft)	Width: 100.00 (Ft)	Est. Area: 16699.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

3/3/2021

## Work History Report

Page 9 of 13

Pavement Database: FDOT

Network: POMPANO BEACH		Branch: TW G	TAXIWAY G		Section: 710	Surface: AC
L.C.D. 6/1/2012	Use: TAXIWAY	Rank: P	Length: 260.00 (Ft)	Width: 55.00 (Ft)	Est. Area: 15387.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401, 8" P-211 LIMEROCK BAS

Network: POMPANO BEACH		Branch: TW G	TAXIWAY G		Section: 715	Surface: AC
L.C.D. 6/1/2014	Use: TAXIWAY	Rank: P	Length: 350.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 17469.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2014	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW G	TAXIWAY G		Section: 720	Surface: AC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 2,975.00 (Ft)	Width: 35.00 (Ft)	Est. Area: 151212.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	NC-AC	New Construction - AC			<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW G	TAXIWAY G		Section: 725	Surface: AC
L.C.D. 6/1/2012	Use: TAXIWAY	Rank: P	Length: 835.00 (Ft)	Width: 35.00 (Ft)	Est. Area: 33591.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401, 8" P-211 LIMEROCK BAS

Network: POMPANO BEACH		Branch: TW K	TAXIWAY K		Section: 1110	Surface: AC
L.C.D. 11/1/2012	Use: TAXIWAY	Rank: P	Length: 2,500.00 (Ft)	Width: 35.00 (Ft)	Est. Area: 89261.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW K	TAXIWAY K		Section: 1115	Surface: AC
L.C.D. 6/1/2014	Use: TAXIWAY	Rank: P	Length: 150.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 7373.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2014	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW K	TAXIWAY K		Section: 1120	Surface: AC
L.C.D. 6/1/2012	Use: TAXIWAY	Rank: P	Length: 280.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 14097.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	

3/3/2021

## Work History Report

Page 10 of 13

Pavement Database: FDOT

Network: POMPANO BEACH		Branch: TW L	TAXIWAY L		Section: 1202	Surface: AAC
L.C.D. 1/1/1996	Use: TAXIWAY	Rank: P	Length: 290.00 (Ft)	Width: 75.00 (Ft)	Est. Area: 21209.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Estimated Construction Date EST 1950 BIT SECTION UNKNOWN
1/1/1996	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1950	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW L	TAXIWAY L		Section: 1205	Surface: AC
L.C.D. 1/1/1972	Use: TAXIWAY	Rank: P	Length: 260.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 13025.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1972	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW L	TAXIWAY L		Section: 1210	Surface: AAC
L.C.D. 1/1/1996	Use: TAXIWAY	Rank: P	Length: 2,550.00 (Ft)	Width: 60.00 (Ft)	Est. Area: 152867.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Estimated Construction Date EST 1950 BIT SECTION UNKNOWN
1/1/1996	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1950	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW L	TAXIWAY L		Section: 1215	Surface: AAC
L.C.D. 6/1/2012	Use: TAXIWAY	Rank: P	Length: 250.00 (Ft)	Width: 60.00 (Ft)	Est. Area: 14829.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
7/1/2008	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1950	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW M	TAXIWAY M		Section: 1305	Surface: AC
L.C.D. 1/1/1970	Use: TAXIWAY	Rank: P	Length: 884.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 27738.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1970 AC PAVEMENT
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPANO BEACH		Branch: TW M	TAXIWAY M		Section: 1306	Surface: AC
L.C.D. 11/1/2012	Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 29856.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	

3/3/2021

## Work History Report

Page 11 of 13

Pavement Database: FDOT

Network: POMPAN BEACH		Branch: TW M	TAXIWAY M		Section: 1310	Surface:AC
L.C.D. 1/1/1999	Use: TAXIWAY	Rank: P	Length: 900.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 24002.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1999 AC PAVEMENT
1/1/1999	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPAN BEACH		Branch: TW M	TAXIWAY M		Section: 1315	Surface:AC
L.C.D. 1/1/1999	Use: TAXIWAY	Rank: P	Length: 125.00 (Ft)	Width: 110.00 (Ft)	Est. Area: 16359.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1999 AC PAVEMENT
1/1/1999	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPAN BEACH		Branch: TW M	TAXIWAY M		Section: 1320	Surface:AAC
L.C.D. 1/1/2001	Use: TAXIWAY	Rank: P	Length: 1,270.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 69823.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EST 1970 BIT SECTION UNKNOWN
1/1/2001	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPAN BEACH		Branch: TW M	TAXIWAY M		Section: 1322	Surface:AC
L.C.D. 5/1/2018	Use: TAXIWAY	Rank: P	Length: 360.00 (Ft)	Width: 54.00 (Ft)	Est. Area: 30907.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2018	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401, 8" P-211, 12" P-154-5.1
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1970 BIT SECTION UNKNOWN

Network: POMPAN BEACH		Branch: TW M	TAXIWAY M		Section: 1325	Surface:AAC
L.C.D. 1/1/2012	Use: TAXIWAY	Rank: P	Length: 140.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 8073.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
7/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1970	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: POMPAN BEACH		Branch: TW M	TAXIWAY M		Section: 1330	Surface:AAC
L.C.D. 1/1/2001	Use: TAXIWAY	Rank: P	Length: 245.00 (Ft)	Width: 50.00 (Ft)	Est. Area: 12988.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EST 1970 BIT SECTION UNKNOWN
1/1/2001	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	



3/3/2021

**Work History Report**

Page 12 of 13

*Pavement Database: FDOT*

**Network:** POMPANO BEACH    **Branch:** TW N    TAXIWAY N    **Section:** 1405    **Surface:** AC  
**L.C.D.** 1/1/2004    **Use:** TAXIWAY    **Rank:** P    **Length:** 420.00 (Ft)    **Width:** 50.00 (Ft)    **Est. Area:** 33887.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2010	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	ESTIMATED CONSTRUCTION
1/1/2004	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

**Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	32	2,736,189.00	0.84	0.74
Complete Reconstruction - AC	1	30,907.00	0.00	0.00
Mill and Overlay	34	2,318,472.00	0.00	0.00
New Construction - AC	9	376,616.00	0.00	0.00
New Construction - Initial	23	941,126.00	0.00	0.00
New Construction - PCC	4	231,803.00	0.00	0.00
OVERLAY	5	281,484.00	0.90	0.73
Overlay - AC Structural	1	16,033.00	0.00	0.00
Surface Treatment - Seal Coat	42	2,806,581.00	0.00	0.00

3/3/2021

**Branch Condition Report**

Page 1 of 2

*Pavement Database: FDOT*

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	Est. Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP N	1	785.00	100.00	72,380.00	APRON	58.00	0.00	58.00
AP RU 33	2	300.00	100.00	34,800.00	APRON	71.50	14.50	68.93
AP S	7	5,694.00	154.29	687,220.00	APRON	67.14	20.82	68.33
AP SW	3	2,230.00	238.33	275,017.00	APRON	89.33	7.93	90.05
RW 10-28	2	1,160.00	100.00	329,520.00	RUNWAY	74.50	10.50	67.72
RW 15-33	4	13,620.00	56.25	737,700.00	RUNWAY	88.25	3.77	89.56
RW 6-24	4	10,075.00	62.50	556,428.00	RUNWAY	76.00	15.02	63.53
TL T-HANG	5	5,660.00	32.60	171,809.00	TAXILANE	44.40	19.09	40.31
TW A	2	1,850.00	40.00	75,696.00	TAXIWAY	68.50	21.50	82.07
TW B	1	2,190.00	50.00	104,085.00	TAXIWAY	59.00	0.00	59.00
TW C	3	994.00	43.33	42,764.00	TAXIWAY	82.67	13.20	74.79
TW D	5	2,804.00	59.00	183,711.00	TAXIWAY	79.40	20.76	86.97
TW E	1	200.00	40.00	12,246.00	TAXIWAY	89.00	0.00	89.00
TW F	4	3,080.00	51.25	151,992.00	TAXIWAY	84.00	14.59	66.03
TW G	4	4,420.00	43.75	217,659.00	TAXIWAY	89.25	2.17	90.70
TW G1	1	600.00	35.00	21,726.00	TAXIWAY	90.00	0.00	90.00
TW G3	1	148.00	75.00	15,789.00	TAXIWAY	93.00	0.00	93.00
TW G4	1	139.00	70.00	12,199.00	TAXIWAY	92.00	0.00	92.00
TW G5	1	150.00	100.00	16,699.00	TAXIWAY	91.00	0.00	91.00
TW K	3	2,930.00	45.00	110,731.00	TAXIWAY	88.33	3.86	91.15
TW L	4	3,350.00	61.25	201,930.00	TAXIWAY	65.00	13.36	61.61
TW M	8	4,224.00	58.00	219,746.00	TAXIWAY	76.38	10.87	74.19
TW N	1	420.00	50.00	33,887.00	TAXIWAY	79.00	0.00	79.00

**3/3/2021****Branch Condition Report****Page 2 of 2***Pavement Database: FDOT*

<b>Use Category</b>	<b>Number of Sections</b>	<b>Total Area (SqFt)</b>	<b>Arithmetic Average PCI</b>	<b>Average STD PCI</b>	<b>Weighted Average PCI</b>
APRON	13	1,069,417.00	72.23	19.43	73.23
RUNWAY	10	1,623,648.00	80.60	12.54	76.21
TAXILANE	5	171,809.00	44.40	19.09	40.31
TAXIWAY	40	1,420,860.00	80.10	15.12	77.40
ALL	68	4,285,734.00	76.04	18.59	74.42

Pavement Database: FDOT

NetworkId: PMP

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	Est. Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP N	4205	1/1/1972	AAC	APRON	P	0	72,380.00	11/30/2020	48	58
AP RU 33	5105	6/1/2012	AAC	APRON	P	0	14,310.00	11/30/2020	8	86
AP RU 33	5110	1/1/1996	AAC	APRON	P	0	20,490.00	11/30/2020	24	57
AP S	4105	1/1/1997	AAC	APRON	P	0	215,925.00	11/30/2020	23	62
AP S	4107	1/1/2015	PCC	APRON	P	0	3,846.00	11/30/2020	5	86
AP S	4110	1/1/1960	AC	APRON	P	0	26,025.00	11/30/2020	60	47
AP S	4112	5/17/2013	AC	APRON	P	0	135,533.00	11/30/2020	7	90
AP S	4125	12/25/1999	AC	APRON	P	0	105,525.00	11/30/2020	21	37
AP S	4130	1/1/2015	AAC	APRON	P	0	71,613.00	11/30/2020	5	55
AP S	4135	1/1/2015	AC	APRON	P	0	128,753.00	11/30/2020	5	93
AP SW	4405	1/1/2015	PCC	APRON	P	0	118,367.00	11/30/2020	5	87
AP SW	4410	1/1/2012	PCC	APRON	P	0	63,093.00	11/30/2020	8	81
AP SW	4415	7/1/2019	PCC	APRON	P	0	93,557.00	7/1/2019	0	100
RW 10-28	6105	1/1/2000	AAC	RUNWAY	P	0	271,200.00	11/30/2020	20	64
RW 10-28	6115	1/1/2012	AAC	RUNWAY	P	0	58,320.00	11/30/2020	8	85
RW 15-33	6305	1/1/2012	AAC	RUNWAY	P	0	220,900.00	11/30/2020	8	89
RW 15-33	6310	1/1/2012	AAC	RUNWAY	P	0	441,800.00	11/30/2020	8	90
RW 15-33	6325	6/1/2012	AC	RUNWAY	P	0	25,000.00	11/30/2020	8	82
RW 15-33	6330	6/1/2012	AC	RUNWAY	P	0	50,000.00	11/30/2020	8	92
RW 6-24	6205	1/1/2001	AAC	RUNWAY	P	0	335,952.00	11/30/2020	19	60
RW 6-24	6210	1/1/2001	AAC	RUNWAY	P	0	167,976.00	11/30/2020	19	62
RW 6-24	6220	1/1/2012	AAC	RUNWAY	P	0	35,000.00	11/30/2020	8	91
RW 6-24	6225	1/1/2012	AAC	RUNWAY	P	0	17,500.00	11/30/2020	8	91
TL T-HANG	4305	12/25/1999	AC	TAXILANE	P	0	31,764.00	11/30/2020	21	36
TL T-HANG	4310	12/25/1999	AC	TAXILANE	P	0	49,387.00	11/30/2020	21	27
TL T-HANG	4315	12/25/1999	AC	TAXILANE	P	0	57,861.00	11/30/2020	21	44
TL T-HANG	4320	12/25/1999	APC	TAXILANE	P	0	16,033.00	11/30/2020	21	34



TL T-HANG	4325	6/1/2018	AAC	TAXILANE	P	0	16,764.00	11/30/2020	2	81
TW A	105	11/1/2012	AAC	TAXIWAY	P	0	61,729.00	11/30/2020	8	90
TW A	115	1/1/1997	AAC	TAXIWAY	P	0	13,967.00	11/30/2020	23	47
TW B	210	1/1/1972	AAC	TAXIWAY	P	0	104,085.00	11/30/2020	48	59
TW C	305	1/1/1970	AC	TAXIWAY	P	0	26,289.00	11/30/2020	50	64
TW C	350	11/1/2012	AAC	TAXIWAY	P	0	6,807.00	11/30/2020	8	92
TW C	360	11/1/2012	AAC	TAXIWAY	P	0	9,668.00	11/30/2020	8	92
TW D	405	1/1/2021	AAC	TAXIWAY	P	0	90,211.00	1/1/2021	0	100
TW D	410	5/1/2018	AAC	TAXIWAY	P	0	12,212.00	11/30/2020	2	92
TW D	412	5/1/2018	AAC	TAXIWAY	P	0	24,824.00	11/30/2020	2	83
TW D	415	11/1/2012	AAC	TAXIWAY	P	0	36,063.00	11/30/2020	8	82
TW D	420	1/1/2008	AAC	TAXIWAY	P	0	20,401.00	11/30/2020	12	40
TW E	505	1/1/2012	AAC	TAXIWAY	P	0	12,246.00	11/30/2020	8	89
TW F	610	1/1/1972	AAC	TAXIWAY	P	0	120,125.00	11/30/2020	48	59
TW F	612	5/1/2018	AAC	TAXIWAY	P	0	15,275.00	11/30/2020	2	93
TW F	615	5/1/2018	AAC	TAXIWAY	P	0	8,519.00	11/30/2020	2	95
TW F	620	1/1/2012	AAC	TAXIWAY	P	0	8,073.00	11/30/2020	8	89
TW G	710	6/1/2012	AC	TAXIWAY	P	0	15,387.00	11/30/2020	8	89
TW G	715	6/1/2014	AC	TAXIWAY	P	0	17,469.00	11/30/2020	6	90
TW G	720	5/1/2018	AC	TAXIWAY	P	0	151,212.00	11/30/2020	2	92
TW G	725	6/1/2012	AC	TAXIWAY	P	0	33,591.00	11/30/2020	8	86
TW G1	700	6/1/2012	AC	TAXIWAY	P	0	21,726.00	11/30/2020	8	90
TW G3	730	5/1/2018	AC	TAXIWAY	P	0	15,789.00	11/30/2020	2	93
TW G4	740	5/1/2018	AC	TAXIWAY	P	0	12,199.00	11/30/2020	2	92
TW G5	750	5/1/2018	AC	TAXIWAY	P	0	16,699.00	11/30/2020	2	91
TW K	1110	11/1/2012	AC	TAXIWAY	P	0	89,261.00	11/30/2020	8	92
TW K	1115	6/1/2014	AC	TAXIWAY	P	0	7,373.00	11/30/2020	6	83
TW K	1120	6/1/2012	AC	TAXIWAY	P	0	14,097.00	11/30/2020	8	90

TW L	1202	1/1/1996	AAC	TAXIWAY	P	0	21,209.00	11/30/2020	24	62
TW L	1205	1/1/1972	AC	TAXIWAY	P	0	13,025.00	11/30/2020	48	51
TW L	1210	1/1/1996	AAC	TAXIWAY	P	0	152,867.00	11/30/2020	24	60
TW L	1215	6/1/2012	AAC	TAXIWAY	P	0	14,829.00	11/30/2020	8	87
TW M	1305	1/1/1970	AC	TAXIWAY	P	0	27,738.00	11/30/2020	50	68
TW M	1306	11/1/2012	AC	TAXIWAY	P	0	29,856.00	11/30/2020	8	81
TW M	1310	1/1/1999	AC	TAXIWAY	P	0	24,002.00	11/30/2020	21	82
TW M	1315	1/1/1999	AC	TAXIWAY	P	0	16,359.00	11/30/2020	21	69
TW M	1320	1/1/2001	AAC	TAXIWAY	P	0	69,823.00	11/30/2020	19	64
TW M	1322	5/1/2018	AC	TAXIWAY	P	0	30,907.00	11/30/2020	2	93
TW M	1325	1/1/2012	AAC	TAXIWAY	P	0	8,073.00	11/30/2020	8	90
TW M	1330	1/1/2001	AAC	TAXIWAY	P	0	12,988.00	11/30/2020	19	64
TW N	1405	1/1/2004	AC	TAXIWAY	P	0	33,887.00	11/30/2020	16	79

*Pavement Database: FDOT*

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02	2	488,168.00	12	92.08	5.35	94.32
03-05	5	322,579.00	4	80.25	14.82	82.28
06-10	8	1,447,704.00	26	88.04	3.55	88.76
11-15	12	20,401.00	1	40.00	0.00	40.00
16-20	19	891,826.00	6	65.50	6.21	62.69
21-25	22	725,389.00	12	51.42	15.79	52.76
41-50	49	363,642.00	6	59.83	5.27	59.56
50+	60	26,025.00	1	47.00	0.00	47.00
ALL	14	4,285,734.00	68	76.04	18.59	74.42



# **Appendix B: Maintenance and Rehabilitation Planning Needs**



Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
PMP	RW 15-33	6305	WEATHERING	Medium	8,284	SF	3.8%	Preventive	Surface Seal	8,284	SF	\$ 0.50	\$ 4,150
PMP	RW 15-33	6310	RAVELING	Low	589	SF	0.1%	Preventive	Surface Seal	589	SF	\$ 0.50	\$ 300
PMP	RW 15-33	6310	RAVELING	Medium	5	SF		Preventive	Surface Seal	5	SF	\$ 0.50	\$ 10
PMP	RW 15-33	6310	WEATHERING	Medium	4,050	SF	0.9%	Preventive	Surface Seal	4,049	SF	\$ 0.50	\$ 2,030
PMP	RW 6-24	6220	RAVELING	Low	940	SF	2.7%	Preventive	Surface Seal	940	SF	\$ 0.50	\$ 470
PMP	TW G	710	RAVELING	Low	11	SF	0.1%	Preventive	Surface Seal	11	SF	\$ 0.50	\$ 10
PMP	TW G	725	WEATHERING	Medium	1,680	SF	5.0%	Preventive	Surface Seal	1,679	SF	\$ 0.50	\$ 840
PMP	TW G1	700	WEATHERING	Medium	87	SF	0.4%	Preventive	Surface Seal	87	SF	\$ 0.50	\$ 50
PMP	TW K	1115	WEATHERING	Medium	368	SF	5.0%	Preventive	Surface Seal	368	SF	\$ 0.50	\$ 190
PMP	TW L	1215	WEATHERING	Medium	1,484	SF	10.0%	Preventive	Surface Seal	1,483	SF	\$ 0.50	\$ 750
PMP	TW M	1306	RAVELING	Low	183	SF	0.6%	Preventive	Surface Seal	183	SF	\$ 0.50	\$ 100
PMP	TW M	1310	RAVELING	Low	86	SF	0.4%	Preventive	Surface Seal	86	SF	\$ 0.50	\$ 50
PMP	TW N	1405	RAVELING	Low	1,694	SF	5.0%	Preventive	Surface Seal	1,694	SF	\$ 0.50	\$ 850
PMP	AP RU 33	5105	WEATHERING	Medium	1,432	SF	10.0%	Preventive	Surface Seal	1,432	SF	\$ 0.50	\$ 720
PMP	AP S	4107	JT SEAL DMG	High	12	Slabs	100.0%	Preventive	PCC Joint Seal	288	LF	\$ 3.25	\$ 940
PMP	AP SW	4405	JT SEAL DMG	High	552	Slabs	100.0%	Preventive	PCC Joint Seal	32,161	LF	\$ 3.25	\$ 104,530
PMP	AP SW	4410	JT SEAL DMG	High	336	Slabs	100.0%	Preventive	PCC Joint Seal	6,284	LF	\$ 3.25	\$ 20,430
PMP	TL T-HANG	4305	RAVELING	High	118	SF	0.4%	Stopgap	AC Partial-Depth Patching	118	SF	\$ 3.75	\$ 450
PMP	TL T-HANG	4315	ALLIGATOR CR	Medium	1,717	SF	3.0%	Stopgap	AC Full-Depth Patching	1,887	SF	\$ 7.50	\$ 14,160
PMP	TL T-HANG	4315	RAVELING	High	70	SF	0.1%	Stopgap	AC Partial-Depth Patching	70	SF	\$ 3.75	\$ 270
PMP	AP S	4125	RAVELING	High	225	SF	0.2%	Stopgap	AC Partial-Depth Patching	225	SF	\$ 3.75	\$ 850



*Table B.2: Section-Level 10-Year Major Rehabilitation Needs*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2021	PMP	RW 10-28	6105	AAC	271,200	63	AC Rehabilitation	\$ 1,899,000
2021	PMP	RW 6-24	6205	AAC	335,952	59	AC Rehabilitation	\$ 2,352,000
2021	PMP	RW 6-24	6210	AAC	167,976	61	AC Rehabilitation	\$ 1,176,000
2021	PMP	TW A	115	AAC	13,967	46	AC Reconstruction	\$ 147,000
2021	PMP	TW B	210	AAC	104,085	59	AC Rehabilitation	\$ 729,000
2021	PMP	TW C	305	AC	26,289	64	AC Rehabilitation	\$ 185,000
2021	PMP	TW D	420	AAC	20,401	39	AC Reconstruction	\$ 215,000
2021	PMP	TW F	610	AAC	120,125	59	AC Rehabilitation	\$ 841,000
2021	PMP	TW L	1202	AAC	21,209	62	AC Rehabilitation	\$ 149,000
2021	PMP	TW L	1205	AC	13,025	51	AC Reconstruction	\$ 137,000
2021	PMP	TW L	1210	AAC	152,867	60	AC Rehabilitation	\$ 1,071,000
2021	PMP	TW M	1305	AC	27,738	68	AC Rehabilitation	\$ 195,000
2021	PMP	TW M	1315	AC	16,359	69	AC Rehabilitation	\$ 115,000
2021	PMP	TW M	1320	AAC	69,823	64	AC Rehabilitation	\$ 489,000
2021	PMP	TW M	1330	AAC	12,988	64	AC Rehabilitation	\$ 91,000
2021	PMP	TL T-HANG	4305	AC	31,764	36	AC Reconstruction	\$ 334,000
2021	PMP	TL T-HANG	4310	AC	49,387	27	AC Reconstruction	\$ 519,000
2021	PMP	TL T-HANG	4315	AC	57,861	44	AC Reconstruction	\$ 608,000
2021	PMP	TL T-HANG	4320	APC	16,033	33	AC Reconstruction	\$ 169,000
2021	PMP	AP N	4205	AAC	72,380	58	AC Rehabilitation	\$ 507,000
2021	PMP	AP RU 33	5110	AAC	20,490	57	AC Rehabilitation	\$ 144,000
2021	PMP	AP S	4105	AAC	215,925	62	AC Rehabilitation	\$ 1,512,000
2021	PMP	AP S	4110	AC	26,025	47	AC Reconstruction	\$ 274,000
2021	PMP	AP S	4125	AC	105,525	37	AC Reconstruction	\$ 1,109,000
2021	PMP	AP S	4130	AAC	71,613	55	AC Rehabilitation	\$ 502,000
2028	PMP	TW N	1405	AC	33,887	69	AC Rehabilitation	\$ 238,000
2029	PMP	RW 10-28	6115	AAC	58,320	68	AC Rehabilitation	\$ 409,000
2029	PMP	TW M	1306	AC	29,856	69	AC Rehabilitation	\$ 209,000
2029	PMP	TL T-HANG	4325	AAC	16,764	69	AC Rehabilitation	\$ 118,000
2029	PMP	AP RU 33	5105	AAC	14,310	68	AC Rehabilitation	\$ 101,000


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2030	PMP	RW 15-33	6325	AC	25,000	69	AC Rehabilitation	\$ 176,000
2030	PMP	TW D	412	AAC	24,824	69	AC Rehabilitation	\$ 174,000
2030	PMP	TW D	415	AAC	36,063	69	AC Rehabilitation	\$ 253,000
2030	PMP	TW K	1115	AC	7,373	69	AC Rehabilitation	\$ 52,000
2030	PMP	TW M	1310	AC	24,002	68	AC Rehabilitation	\$ 169,000




# Appendix C: Technical Exhibits







RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2018	TW D	Mill and Overlay   Variable Mill, 2.5" P-401
	TL T-HANG, TW F	Mill and Overlay
	TW G, TW G3, TW G4, TW G5	New Construction - AC
	TW M	Complete Reconstruction - AC   2" P-401, 8" P-211, 12" P-154-5.1
2019	AP SW	New Construction - PCC
2021	TW D	Mill and Overlay   1" Mill, 2.5" P-401

**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID

TW A — TYPICAL TAXIWAY BRANCH ID


AP S — TYPICAL APRON BRANCH ID

**PROJECT YEAR**

2016	2021
2017	2022
2018	2023
2019	2024
2020	2025

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.









305 PCI = 64	350 PCI = 92	360 PCI = 92	410 PCI = 92	412 PCI = 83	415 PCI = 82	420 PCI = 40
612 PCI = 93	615 PCI = 95	620 PCI = 89	710 PCI = 89	715 PCI = 90	720 PCI = 92	730 PCI = 93
740 PCI = 92	750 PCI = 91	1110 PCI = 92	1115 PCI = 83	1120 PCI = 90	1205 PCI = 51	1210 PCI = 60
1215 PCI = 87	1305 PCI = 68	1306 PCI = 81	1310 PCI = 82	1315 PCI = 69	1322 PCI = 93	1330 PCI = 64
1405 PCI = 79	4105 PCI = 62	4107 PCI = 86	4110 PCI = 47	4125 PCI = 37	4320 PCI = 34	5105 PCI = 86
5110 PCI = 57	6220 PCI = 91	6225 PCI = 91				


**LEGEND**



RW 13-31



TW A



AP S



TYPICAL RUNWAY BRANCH ID










TYPICAL TAXIWAY BRANCH ID



TYPICAL APRON BRANCH ID

**2020 PAVEMENT CONDITION INDEX**

	PCI 86-100 Good
	PCI 71-85 Satisfactory
	PCI 56-70 Fair
	PCI 41-55 Poor
	PCI 26-40 Very Poor
	PCI 11-25 Serious
	PCI 0-10 Failed

"SECTION ID"  
"PCI VALUE"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



TW C:305 2021   AC REHAB \$0.19 M	TW D:420 2021   AC RECON \$0.22 M	TW L:1205 2021   AC RECON \$0.14 M	TW L:1210 2021   AC REHAB \$1.07 M
TW M:1305 2021   AC REHAB \$0.20 M	TW M:1315 2021   AC REHAB \$0.12 M	TW M:1330 2021   AC REHAB \$0.09 M	AP S:4105 2021   AC REHAB \$1.51 M
AP S:4110 2021   AC RECON \$0.27 M	TL T-HANG:4315 2021   AC RECON \$0.61 M	TL T-HANG:4320 2021   AC RECON \$0.17 M	TW M:1306 2029   AC REHAB \$0.21 M
TW D:412 2030   AC REHAB \$0.17 M	TW D:415 2030   AC REHAB \$0.25 M	TW K:1115 2030   AC REHAB \$0.05 M	TW M:1310 2030   AC REHAB \$0.17 M

**LEGEND**

- RW 13-31 ← TYPICAL RUNWAY BRANCH ID
- TW A ← TYPICAL TAXIWAY BRANCH ID
- AP S ← TYPICAL APRON BRANCH ID

<b>PROGRAM YEAR</b>	
<span style="display: inline-block; width: 30px; height: 30px; background-color: #ffcc00; border: 1px solid black;"></span> 2021	<span style="display: inline-block; width: 30px; height: 30px; background-color: #99cc33; border: 1px solid black;"></span> 2026
<span style="display: inline-block; width: 30px; height: 30px; background-color: #ccccff; border: 1px solid black;"></span> 2022	<span style="display: inline-block; width: 30px; height: 30px; background-color: #6666ff; border: 1px solid black;"></span> 2027
<span style="display: inline-block; width: 30px; height: 30px; background-color: #ffff00; border: 1px solid black;"></span> 2023	<span style="display: inline-block; width: 30px; height: 30px; background-color: #99ff99; border: 1px solid black;"></span> 2028
<span style="display: inline-block; width: 30px; height: 30px; background-color: #ff66cc; border: 1px solid black;"></span> 2024	<span style="display: inline-block; width: 30px; height: 30px; background-color: #996699; border: 1px solid black;"></span> 2029
<span style="display: inline-block; width: 30px; height: 30px; background-color: #66cccc; border: 1px solid black;"></span> 2025	<span style="display: inline-block; width: 30px; height: 30px; background-color: #cc0000; border: 1px solid black;"></span> 2030

"BRANCH:" "SECTION"  
 "YEAR" "REHAB ACTIVITY"  
 "EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





# Appendix D: Inspection Photograph Documentation







RW 6-24, Section 6205, Sample Unit 378 – Longitudinal and Transverse Cracking



RW 6-24, Section 6210, Sample Unit 556 – Vicinity





RW 10-28, Section 6105, Sample Unit 117 - Raveling



RW 10-28, Section 6105, Sample Unit 152 - Vicinity





RW 15-33, Section 6305, Sample Unit 340 - Vicinity



RW 15-33, Section 6310, Sample Unit 117 - Longitudinal & Transverse Cracking





TW D, Section 420, Sample Unit 410 - Alligator Cracking



TW F, Section 610, Sample Unit 601 - Longitudinal & Transverse Cracking and Raveling





TW G, Section 720, Sample Unit 718 - Vicinity



TW K, Section 1115, Sample Unit 128 – Vicinity





TW L, Section 1205, Sample Unit 113 - Vicinity



TW M, Section 1320, Sample Unit 198 - Depression





AP N, Section 4205, Sample Unit 109 - Depression and Longitudinal & Transverse Cracking




AP S, Section 4105, Sample Unit 514 - Vicinity





AP S, Section 4130, Sample Unit 305 - Block Cracking



AP S, Section 4130, Sample Unit 305 - Depression





# **Appendix E: Inspection Distress Details**



# Re-Inspection Report

FDOT

Generated Date 3/3/2021

Page 1 of 71

<b>Network:</b>	PMP	<b>Name:</b>	POMPANO BEACH AIRPARK			
<b>Branch:</b>	AP N	<b>Name:</b>	NORTH APRON - OLD RW	<b>Use:</b>	APRON	<b>Area:</b> 72,380 SqFt
<b>Section:</b>	4205	of 1	<b>From:</b> -	<b>To:</b> -	<b>Last Const.:</b> 1/1/1972	
<b>Surface:</b>	AAC	<b>Family:</b>	CA653-GA-AP-AAC-APC	<b>Zone:</b>	<b>Category:</b>	<b>Rank:</b> P
<b>Area:</b>	72,380 SqFt	<b>Length:</b>	785 Ft	<b>Width:</b>	100 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b> Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b> 0

## Section Comments:

<b>Work Date:</b>	1/1/1972	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	7/1/2008	<b>Work Type:</b>	Surface Treatment - Seal Coat	<b>Code:</b>	ST-SC	<b>Is Major M&amp;R:</b>	False

**Last Insp. Date:** 11/30/2020 **TotalSamples:** 14 **Surveyed:** 2

**Conditions:** PCI: 58

## Inspection Comments:

<b>Sample Number:</b>	103	<b>Type:</b>	R	<b>Area:</b>	4909.00 SqFt	<b>PCI:</b>	65
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

## Sample Comments:

48	L & T CR	L	427.00	Ft
48	L & T CR	M	50.00	Ft
57	WEATHERING	L	4664.00	SqFt
57	WEATHERING	M	245.00	SqFt

<b>Sample Number:</b>	109	<b>Type:</b>	R	<b>Area:</b>	5593.00 SqFt	<b>PCI:</b>	52
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

## Sample Comments:

45	DEPRESSION	L	68.00	SqFt
48	L & T CR	L	924.00	Ft
56	SWELLING	M	448.00	SqFt
57	WEATHERING	L	5593.00	SqFt



Network:		PMP		Name:		POMPANO BEACH AIRPARK							
Branch:	AP RU 33		Name:	RUN-UP APRON 33		Use:	APRON	Area:	34,800 SqFt				
Section:	5105		of	2		From:	-		To:	-	Last Const.:	6/1/2012	
Surface:	AAC		Family:	CA653-GA-AP-AAC-APC		Zone:			Category:			Rank:	P
Area:	14,310 SqFt		Length:	100 Ft		Width:	100 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1950		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True	
Work Date:	7/1/2008		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False	
Work Date:	6/1/2012		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True	
Last Insp. Date:	11/30/2020		TotalSamples:	3		Surveyed:	1						
Conditions:	PCI: 86												
Inspection Comments:													
Sample Number:	333		Type:	R		Area:	6975.00 SqFt		PCI:	86			
Sample Comments:													
48	L & T CR		L	17.00 Ft									
57	WEATHERING		L	6277.00 SqFt									
57	WEATHERING		M	698.00 SqFt									

Network:		PMP		Name:		POMPANO BEACH AIRPARK								
Branch:	AP RU 33		Name:	RUN-UP APRON 33		Use:	APRON	Area:	34,800 SqFt					
Section:	5110		of	2		From:	-		To:	-		Last Const.:	1/1/1996	
Surface:	AAC		Family:	CA653-GA-AP-AAC-APC		Zone:			Category:			Rank:	P	
Area:	20,490 SqFt		Length:	200 Ft		Width:	100 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1950		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Work Date:	1/1/1996		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True		
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1							
Conditions:	PCI: 57													
Inspection Comments:														
Sample Number:	332		Type:	R		Area:	6249.00 SqFt		PCI:	57				
Sample Comments:														
48	L & T CR		L	899.00		Ft								
52	RAVELING		L	1875.00		SqFt								
56	SWELLING		L	174.00		SqFt								
57	WEATHERING		L	4374.00		SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK						
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	687,220 SqFt		
Section:	4105	of 7	From:	-		To:	-		Last Const.:	1/1/1997
Surface:	AAC	Family:	CA653-GA-AP-AAC-APC	Zone:			Category:	Rank: P		
Area:	215,925 SqFt	Length:	2,225 Ft	Width:	100 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1970	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/1997	Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True		
Last Insp. Date:	11/30/2020	TotalSamples:	44	Surveyed:	5					
Conditions:	PCI: 62									
Inspection Comments:										
Sample Number:	310	Type:	R	Area:	5000.00 SqFt	PCI:	62			
Sample Comments:										
48	L & T CR	L	578.00	Ft						
48	L & T CR	M	29.00	Ft						
52	RAVELING	L	5000.00	SqFt						
Sample Number:	320	Type:	R	Area:	5000.00 SqFt	PCI:	60			
Sample Comments:										
48	L & T CR	L	298.00	Ft						
50	PATCHING	L	2200.00	SqFt						
52	RAVELING	L	2800.00	SqFt						
Sample Number:	329	Type:	R	Area:	5000.00 SqFt	PCI:	54			
Sample Comments:										
43	BLOCK CR	L	216.00	SqFt						
48	L & T CR	L	410.00	Ft						
48	L & T CR	M	60.00	Ft						
52	RAVELING	L	5000.00	SqFt						
56	SWELLING	L	136.00	SqFt						
Sample Number:	514	Type:	R	Area:	5200.00 SqFt	PCI:	66			
Sample Comments:										
48	L & T CR	L	612.00	Ft						
52	RAVELING	L	5200.00	SqFt						
Sample Number:	525	Type:	R	Area:	6000.00 SqFt	PCI:	69			
Sample Comments:										
48	L & T CR	L	536.00	Ft						
52	RAVELING	L	3700.00	SqFt						
56	SWELLING	L	70.00	SqFt						

Network:	PMP			Name:	POMPANO BEACH AIRPARK							
Branch:	AP S		Name:	SOUTH APRON		Use:	APRON		Area:	687,220 SqFt		
Section:	4107		of	7	From:	-		To:	-		Last Const.:	1/1/2015
Surface:	PCC		Family:	CA653-GA-AP-PCC		Zone:			Category:	Rank: P		
Area:	3,846 SqFt		Length:	110 Ft		Width:	35 Ft					
Slabs:	12		Slab Length:	20 Ft		Slab Width:	16 Ft		Joint Length:	288 Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2015		Work Type:	New Construction - PCC				Code:	NC-PC		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 86											
Inspection Comments:												
Sample Number:	712		Type:	R		Area:	14.00 Slabs		PCI:	86		
Sample Comments:												
65	JT SEAL DMG		H	14.00		Slabs						
74	JOINT SPALL		L	1.00		Slabs						



Network:	PMP			Name:	POMPANO BEACH AIRPARK						
Branch:	AP S		Name:	SOUTH APRON		Use:	APRON	Area:	687,220 SqFt		
Section:	4110	of 7	From:	-			To:	-	Last Const.:	1/1/1960	
Surface:	AC	Family:	CA653-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	26,025 SqFt		Length:	450 Ft		Width:	45 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1960		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI:	47									
Inspection Comments:											
Sample Number:	713	Type:	R	Area:	5228.00 SqFt		PCI:	47			
Sample Comments:											
43	BLOCK CR	L	4705.00		SqFt						
43	BLOCK CR	M	523.00		SqFt						
52	RAVELING	L	5228.00		SqFt						

Network:		PMP		Name:		POMPANO BEACH AIRPARK																									
Branch:		AP S		Name:		SOUTH APRON		Use:		APRON		Area:		687,220 SqFt																	
Section:		4112		of 7		From:		-		To:		-		Last Const.:		5/17/2013															
Surface:		AC		Family:		CA653-GA-AP-AC		Zone:		Category:		Rank:		P																	
Area:		135,533 SqFt		Length:		900 Ft		Width:		150 Ft																					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																			
Shoulder:		Street Type:		Grade:		0		Lanes:		0																					
Section Comments:																															
Work Date:				5/17/2013				Work Type:				New Construction - Initial				Code:				NU-IN				Is Major M&R:				True			
Last Insp. Date:				11/30/2020				TotalSamples:				27				Surveyed:				3											
Conditions:				PCI:				90																							
Inspection Comments:																															
Sample Number:				722				Type:		R		Area:				5000.00 SqFt				PCI:				92							
Sample Comments:																															
48		L & T CR		L		3.00		Ft																							
57		WEATHERING		L		5000.00		SqFt																							
Sample Number:				818				Type:		R		Area:				5000.00 SqFt				PCI:				94							
Sample Comments:																															
57		WEATHERING		L		5000.00		SqFt																							
Sample Number:				915				Type:		R		Area:				5000.00 SqFt				PCI:				84							
Sample Comments:																															
45		DEPRESSION		L		52.00		SqFt																							
48		L & T CR		L		5.00		Ft																							
49		OIL SPILLAGE		N		1.00		SqFt																							
57		WEATHERING		L		5000.00		SqFt																							

Network:	PMP			Name:	POMPANO BEACH AIRPARK							
Branch:	AP S		Name:	SOUTH APRON		Use:	APRON		Area:	687,220 SqFt		
Section:	4125		of	7		From:	-		To:	-		
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Category:			
Area:	105,525 SqFt		Length:	209 Ft		Width:	500 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1999			Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	11/30/2020			TotalSamples:	25		Surveyed:	3				
Conditions:	PCI: 37											
Inspection Comments:												
Sample Number:	201		Type:	R		Area:	5000.00 SqFt		PCI:	41		
Sample Comments:												
43	BLOCK CR		L	4750.00 SqFt								
43	BLOCK CR		M	250.00 SqFt								
49	OIL SPILLAGE		N	4.00 SqFt								
52	RAVELING		L	4000.00 SqFt								
52	RAVELING		M	1000.00 SqFt								
Sample Number:	403		Type:	R		Area:	5000.00 SqFt		PCI:	28		
Sample Comments:												
43	BLOCK CR		L	4124.00 SqFt								
45	DEPRESSION		L	56.00 SqFt								
45	DEPRESSION		M	130.00 SqFt								
50	PATCHING		L	12.00 SqFt								
50	PATCHING		M	864.00 SqFt								
52	RAVELING		L	3683.00 SqFt								
52	RAVELING		M	409.00 SqFt								
52	RAVELING		H	32.00 SqFt								
Sample Number:	501		Type:	R		Area:	5000.00 SqFt		PCI:	42		
Sample Comments:												
43	BLOCK CR		L	4750.00 SqFt								
43	BLOCK CR		M	250.00 SqFt								
52	RAVELING		L	4000.00 SqFt								
52	RAVELING		M	1000.00 SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK					
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	687,220 SqFt	
Section:	4130	of 7	From:	-	To:	-	Last Const.:	1/1/2015	
Surface:	AAC	Family:	CA653-GA-AP-AAC-APC	Zone:		Category:	Rank:	P	
Area:	71,613 SqFt	Length:	500 Ft	Width:	150 Ft				
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:	Street Type:	Grade:	0	Lanes:	0				
Section Comments:									
Work Date:	12/25/1999	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Work Date:	1/1/2015	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	11/30/2020	TotalSamples:	12	Surveyed:	2				
Conditions:	PCI:	55							
Inspection Comments:									
Sample Number:	206	Type:	R	Area:	5000.00 SqFt	PCI:	54		
Sample Comments:									
43	BLOCK CR	L	2625.00	SqFt					
48	L & T CR	L	98.00	Ft					
50	PATCHING	L	189.00	SqFt					
52	RAVELING	L	25.00	SqFt					
57	WEATHERING	L	4786.00	SqFt					
Sample Number:	305	Type:	R	Area:	6800.00 SqFt	PCI:	55		
Sample Comments:									
43	BLOCK CR	L	4100.00	SqFt					
45	DEPRESSION	L	100.00	SqFt					
48	L & T CR	L	112.00	Ft					
57	WEATHERING	L	6800.00	SqFt					



Network:	PMP			Name:	POMPANO BEACH AIRPARK									
Branch:	AP S		Name:	SOUTH APRON		Use:	APRON		Area:	687,220 SqFt				
Section:	4135		of	7		From:	-		To:	-		Last Const.:	1/1/2015	
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Category:			Rank:	P	
Area:	128,753 SqFt		Length:	1,300 Ft		Width:			100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2015		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Last Insp. Date:	11/30/2020		TotalSamples:	26		Surveyed:	3							
Conditions:	PCI: 93													
Inspection Comments:														
Sample Number:	105		Type:	R		Area:	5000.00 SqFt		PCI:	91				
Sample Comments:														
49	OIL SPILLAGE		N	46.00 SqFt										
57	WEATHERING		L	5000.00 SqFt										
Sample Number:	203		Type:	R		Area:	5000.00 SqFt		PCI:	94				
Sample Comments:														
57	WEATHERING		L	5000.00 SqFt										
Sample Number:	401		Type:	R		Area:	5000.00 SqFt		PCI:	94				
Sample Comments:														
57	WEATHERING		L	5000.00 SqFt										

Network:	PMP		Name:	POMPANO BEACH AIRPARK						
Branch:	AP SW	Name:	SOUTHWEST APRON		Use:	APRON	Area:	275,017 SqFt		
Section:	4405	of 3	From:	-		To:	-		Last Const.:	1/1/2015
Surface:	PCC	Family:	CA653-GA-AP-PCC		Zone:	Category:		Rank:		P
Area:	118,367 SqFt		Length:	685 Ft		Width:	355 Ft			
Slabs:	552	Slab Length:	15 Ft		Slab Width:	14 Ft		Joint Length:	32,161 Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:	0		
Section Comments:										
Work Date:	1/1/2015		Work Type: New Construction - PCC			Code:	NC-PC		Is Major M&R: True	
Last Insp. Date:	11/30/2020		TotalSamples:	30		Surveyed:	3			
Conditions:	PCI: 87									
Inspection Comments:										
Sample Number:	256	Type:	R	Area:	20.00 Slabs		PCI:	88		
Sample Comments:										
65	JT SEAL DMG		H	20.00 Slabs						
Sample Number:	455	Type:	R	Area:	20.00 Slabs		PCI:	86		
Sample Comments:										
65	JT SEAL DMG		H	20.00 Slabs						
73	SHRINKAGE CR		N	2.00 Slabs						
Sample Number:	602	Type:	R	Area:	25.00 Slabs		PCI:	88		
Sample Comments:										
65	JT SEAL DMG		H	25.00 Slabs						

Network:	PMP		Name:	POMPANO BEACH AIRPARK								
Branch:	AP SW		Name:	SOUTHWEST APRON		Use:	APRON	Area:	275,017 SqFt			
Section:	4410		of	3	From:	-		To:	-		Last Const.:	1/1/2012
Surface:	PCC		Family:	CA653-GA-AP-PCC		Zone:			Category:	Rank: P		
Area:	63,093 SqFt		Length:	1,000 Ft		Width:	50 Ft					
Slabs:	336		Slab Length:	12 Ft		Slab Width:	15 Ft		Joint Length:	6,283 Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2012		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	22		Surveyed:	3					
Conditions:	PCI:	81										
Inspection Comments:												
Sample Number:	302		Type:	R		Area:	18.00 Slabs		PCI:	83		
Sample Comments:												
65	JT SEAL DMG		H	18.00 Slabs								
66	SMALL PATCH		L	2.00 Slabs								
73	SHRINKAGE CR		N	1.00 Slabs								
74	JOINT SPALL		L	1.00 Slabs								
Sample Number:	351		Type:	R		Area:	18.00 Slabs		PCI:	76		
Sample Comments:												
62	CORNER BREAK		L	1.00 Slabs								
65	JT SEAL DMG		H	18.00 Slabs								
74	JOINT SPALL		L	3.00 Slabs								
75	CORNER SPALL		L	1.00 Slabs								
Sample Number:	453		Type:	R		Area:	18.00 Slabs		PCI:	83		
Sample Comments:												
62	CORNER BREAK		L	1.00 Slabs								
65	JT SEAL DMG		H	18.00 Slabs								

Network:	PMP			Name:	POMPANO BEACH AIRPARK						
Branch:	RW 10-28		Name:	RUNWAY 10-28		Use:	RUNWAY	Area:	329,520 SqFt		
Section:	6105 of 2		From:	-			To:	-			
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P	
Area:	271,200 SqFt		Length:	935 Ft		Width:	100 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1968		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2000		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	54		Surveyed:	11				
Conditions:	PCI: 64										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	5000.00 SqFt		PCI:	66	
Sample Comments:											
48	L & T CR		L	109.00 Ft							
50	PATCHING		L	1250.00 SqFt							
52	RAVELING		L	3750.00 SqFt							
Sample Number:	106		Type:	R		Area:	5000.00 SqFt		PCI:	65	
Sample Comments:											
48	L & T CR		L	108.00 Ft							
50	PATCHING		L	4.00 SqFt							
52	RAVELING		L	4996.00 SqFt							
56	SWELLING		L	25.00 SqFt							
Sample Number:	110		Type:	R		Area:	5000.00 SqFt		PCI:	64	
Sample Comments:											
48	L & T CR		L	322.00 Ft							
50	PATCHING		L	2.00 SqFt							
52	RAVELING		L	4998.00 SqFt							
56	SWELLING		L	35.00 SqFt							
Sample Number:	117		Type:	R		Area:	5000.00 SqFt		PCI:	69	
Sample Comments:											
48	L & T CR		L	372.00 Ft							
52	RAVELING		L	5000.00 SqFt							
Sample Number:	124		Type:	R		Area:	5000.00 SqFt		PCI:	67	
Sample Comments:											
48	L & T CR		L	376.00 Ft							
52	RAVELING		L	5000.00 SqFt							
56	SWELLING		L	15.00 SqFt							
Sample Number:	127		Type:	R		Area:	5000.00 SqFt		PCI:	66	
Sample Comments:											
48	L & T CR		L	76.00 Ft							
52	RAVELING		L	5000.00 SqFt							
56	SWELLING		L	50.00 SqFt							
Sample Number:	131		Type:	R		Area:	5000.00 SqFt		PCI:	61	
Sample Comments:											
48	L & T CR		L	91.00 Ft							
48	L & T CR		M	35.00 Ft							
50	PATCHING		L	1250.00 SqFt							
52	RAVELING		L	3750.00 SqFt							



Sample Number: 134		Type:	R	Area:		5000.00 SqFt	PCI: 64
Sample Comments:							
48	L & T CR		L	225.00	Ft		
52	RAVELING		L	5000.00	SqFt		
56	SWELLING		L	150.00	SqFt		
Sample Number: 141		Type:	R	Area:		5000.00 SqFt	PCI: 61
Sample Comments:							
48	L & T CR		L	328.00	Ft		
52	RAVELING		L	4960.00	SqFt		
52	RAVELING		M	40.00	SqFt		
56	SWELLING		L	50.00	SqFt		
Sample Number: 146		Type:	R	Area:		5000.00 SqFt	PCI: 60
Sample Comments:							
48	L & T CR		L	322.00	Ft		
50	PATCHING		L	450.00	SqFt		
52	RAVELING		L	4550.00	SqFt		
56	SWELLING		L	100.00	SqFt		
Sample Number: 152		Type:	R	Area:		5000.00 SqFt	PCI: 59
Sample Comments:							
48	L & T CR		L	530.00	Ft		
52	RAVELING		L	4984.00	SqFt		
52	RAVELING		M	16.00	SqFt		
56	SWELLING		L	100.00	SqFt		

Network:	PMP		Name:		POMPANO BEACH AIRPARK							
Branch:	RW 10-28		Name:	RUNWAY 10-28		Use:	RUNWAY	Area:	329,520 SqFt			
Section:	6115		of	2	From:	-		To:	-		Last Const.:	1/1/2012
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	58,320 SqFt		Length:	225 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1968		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False		
Work Date:	1/1/2012		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R: True		
Last Insp. Date:	11/30/2020		TotalSamples:	12		Surveyed:	3					
Conditions:	PCI: 85											
Inspection Comments:												
Sample Number:	156		Type:	R		Area:	5000.00 SqFt		PCI:	72		
Sample Comments:												
50	PATCHING		L	1300.00 SqFt								
57	WEATHERING		L	3700.00 SqFt								
Sample Number:	166		Type:	R		Area:	5002.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	7.00 Ft								
57	WEATHERING		L	5002.00 SqFt								
Sample Number:	169		Type:	R		Area:	5200.00 SqFt		PCI:	92		
Sample Comments:												
48	L & T CR		L	6.00 Ft								
57	WEATHERING		L	5200.00 SqFt								

Network:	PMP			Name:	POMPANO BEACH AIRPARK							
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY	Area:	737,700 SqFt			
Section:	6305		of	4	From:	-		To:	-		Last Const.:	1/1/2012
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	220,900 SqFt		Length:	4,220 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1969			Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2008			Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2012			Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020			TotalSamples:	44		Surveyed:	8				
Conditions:	PCI: 89											
Inspection Comments:												
Sample Number:	303		Type:	R		Area:	5000.00 SqFt		PCI:	86		
Sample Comments:												
48	L & T CR		L	48.00 Ft								
57	WEATHERING		L	4750.00 SqFt								
57	WEATHERING		M	250.00 SqFt								
Sample Number:	310		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
57	WEATHERING		L	4750.00 SqFt								
57	WEATHERING		M	250.00 SqFt								
Sample Number:	316		Type:	R		Area:	5000.00 SqFt		PCI:	86		
Sample Comments:												
48	L & T CR		L	27.00 Ft								
57	WEATHERING		L	4750.00 SqFt								
57	WEATHERING		M	250.00 SqFt								
Sample Number:	320		Type:	R		Area:	5000.00 SqFt		PCI:	86		
Sample Comments:												
48	L & T CR		L	37.00 Ft								
57	WEATHERING		L	4750.00 SqFt								
57	WEATHERING		M	250.00 SqFt								
Sample Number:	325		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
57	WEATHERING		L	4750.00 SqFt								
57	WEATHERING		M	250.00 SqFt								
Sample Number:	329		Type:	R		Area:	5000.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	16.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	333		Type:	R		Area:	5000.00 SqFt		PCI:	87		
Sample Comments:												
42	BLEEDING		N	2.00 SqFt								
48	L & T CR		L	13.00 Ft								
57	WEATHERING		L	4750.00 SqFt								
57	WEATHERING		M	250.00 SqFt								
Sample Number:	340		Type:	R		Area:	5000.00 SqFt		PCI:	92		
Sample Comments:												
48	L & T CR		L	2.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY	Area:	737,700 SqFt		
Section:	6310 of 4		From:	-		To:	-		Last Const.:	1/1/2012	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P	
Area:	441,800 SqFt		Length:	8,400 Ft		Width:	25 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1969		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2008		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2012		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	88		Surveyed:	18				
Conditions:	PCI: 90										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	5000.00 SqFt		PCI:	90	
Sample Comments:											
48	L & T CR		L	32.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	107		Type:	R		Area:	5000.00 SqFt		PCI:	88	
Sample Comments:											
48	L & T CR		L	6.00 Ft							
57	WEATHERING		L	4700.00 SqFt							
57	WEATHERING		M	300.00 SqFt							
Sample Number:	112		Type:	R		Area:	5000.00 SqFt		PCI:	90	
Sample Comments:											
48	L & T CR		L	23.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	117		Type:	R		Area:	5000.00 SqFt		PCI:	89	
Sample Comments:											
48	L & T CR		L	21.00 Ft							
57	WEATHERING		L	4980.00 SqFt							
57	WEATHERING		M	20.00 SqFt							
Sample Number:	122		Type:	R		Area:	5000.00 SqFt		PCI:	89	
Sample Comments:											
48	L & T CR		L	13.00 Ft							
57	WEATHERING		L	4975.00 SqFt							
57	WEATHERING		M	25.00 SqFt							
Sample Number:	127		Type:	R		Area:	5000.00 SqFt		PCI:	92	
Sample Comments:											
48	L & T CR		L	6.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	132		Type:	R		Area:	5000.00 SqFt		PCI:	86	
Sample Comments:											
48	L & T CR		L	37.00 Ft							
57	WEATHERING		L	4700.00 SqFt							
57	WEATHERING		M	300.00 SqFt							
Sample Number:	137		Type:	R		Area:	5000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							



Sample Number: 142		Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
48	L & T CR		L	20.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Sample Number: 500		Type:	R	Area:	5000.00 SqFt	PCI:	92
Sample Comments:							
48	L & T CR		L	6.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Sample Number: 505		Type:	R	Area:	5000.00 SqFt	PCI:	88
Sample Comments:							
48	L & T CR		L	15.00 Ft			
57	WEATHERING		L	4920.00 SqFt			
57	WEATHERING		M	80.00 SqFt			
Sample Number: 511		Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR		L	7.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Sample Number: 515		Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
52	RAVELING		L	120.00 SqFt			
57	WEATHERING		L	4880.00 SqFt			
Sample Number: 520		Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR		L	13.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Sample Number: 524		Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
52	RAVELING		M	1.00 SqFt			
57	WEATHERING		L	4999.00 SqFt			
Sample Number: 530		Type:	R	Area:	5000.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING		L	5000.00 SqFt			
Sample Number: 535		Type:	R	Area:	5000.00 SqFt	PCI:	92
Sample Comments:							
57	WEATHERING		L	4900.00 SqFt			
57	WEATHERING		M	100.00 SqFt			
Sample Number: 541		Type:	R	Area:	5000.00 SqFt	PCI:	92
Sample Comments:							
48	L & T CR		L	2.00 Ft			
57	WEATHERING		L	5000.00 SqFt			

Network:		PMP		Name:		POMPANO BEACH AIRPARK																	
Branch:		RW 15-33		Name:		RUNWAY 15-33		Use:		RUNWAY		Area:		737,700 SqFt									
Section:		6325		of		4		From:		-		To:		-		Last Const.:		6/1/2012					
Surface:		AC		Family:		CA653-GA-RW-AC		Zone:				Category:				Rank:		P					
Area:		25,000 SqFt		Length:		500 Ft		Width:		50 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				7/1/2008				Work Type:				Surface Treatment - Seal Coat				Code:		ST-SC		Is Major M&R:		False	
Work Date:				6/1/2012				Work Type:				New Construction - Initial				Code:		NU-IN		Is Major M&R:		True	
Last Insp. Date:				11/30/2020				TotalSamples:				5				Surveyed:				2			
Conditions:				PCI:				82															
Inspection Comments:																							
Sample Number:		344		Type:		R		Area:		5000.00 SqFt		PCI:		80									
Sample Comments:																							
48		L & T CR		L		32.00 Ft																	
50		PATCHING		L		300.00 SqFt																	
57		WEATHERING		L		4700.00 SqFt																	
Sample Number:		347		Type:		R		Area:		5000.00 SqFt		PCI:		85									
Sample Comments:																							
48		L & T CR		L		45.00 Ft																	
50		PATCHING		L		68.00 SqFt																	
57		WEATHERING		L		4932.00 SqFt																	

Network:		PMP		Name:		POMPANO BEACH AIRPARK							
Branch:	RW 15-33		Name:	RUNWAY 15-33		Use:	RUNWAY	Area:	737,700 SqFt				
Section:	6330		of	4	From:	-		To:	-		Last Const.:	6/1/2012	
Surface:	AC		Family:	CA653-GA-RW-AC		Zone:			Category:	Rank:			P
Area:	50,000 SqFt		Length:	500 Ft		Width:	50 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	7/1/2008		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False	
Work Date:	6/1/2012		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:	11/30/2020		TotalSamples:	10		Surveyed:	2						
Conditions:	PCI:		92										
Inspection Comments:													
Sample Number:	146		Type:	R		Area:	5000.00 SqFt		PCI:	94			
Sample Comments:													
57	WEATHERING		L	5000.00 SqFt									
Sample Number:	545		Type:	R		Area:	5000.00 SqFt		PCI:	90			
Sample Comments:													
48	L & T CR		L	18.00 Ft									
57	WEATHERING		L	5000.00 SqFt									

Network:	PMP		Name:	POMPANO BEACH AIRPARK										
Branch:	RW 6-24		Name:	RUNWAY 6-24		Use:	RUNWAY	Area:	556,428 SqFt					
Section:	6205		of	4		From:	-		To:	-		Last Const.:	1/1/2001	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	335,952 SqFt		Length:	2,875 Ft		Width:	100 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1972		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2001		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True		
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False		
Last Insp. Date:	11/30/2020		TotalSamples:	68		Surveyed:	15							
Conditions:	PCI: 60													
Inspection Comments:														
Sample Number:	302		Type:	R		Area:	5000.00 SqFt		PCI:	63				
Sample Comments:														
48	L & T CR		L	677.00 Ft										
52	RAVELING		L	500.00 SqFt										
57	WEATHERING		L	4500.00 SqFt										
Sample Number:	306		Type:	R		Area:	5000.00 SqFt		PCI:	62				
Sample Comments:														
48	L & T CR		L	698.00 Ft										
52	RAVELING		L	500.00 SqFt										
57	WEATHERING		L	4500.00 SqFt										
Sample Number:	309		Type:	R		Area:	5000.00 SqFt		PCI:	63				
Sample Comments:														
48	L & T CR		L	648.00 Ft										
52	RAVELING		L	500.00 SqFt										
57	WEATHERING		L	4500.00 SqFt										
Sample Number:	312		Type:	R		Area:	5000.00 SqFt		PCI:	56				
Sample Comments:														
48	L & T CR		L	539.00 Ft										
48	L & T CR		M	12.00 Ft										
50	PATCHING		L	744.00 SqFt										
52	RAVELING		L	426.00 SqFt										
57	WEATHERING		L	3830.00 SqFt										
Sample Number:	316		Type:	R		Area:	5000.00 SqFt		PCI:	60				
Sample Comments:														
45	DEPRESSION		L	12.00 SqFt										
48	L & T CR		L	581.00 Ft										
50	PATCHING		L	50.00 SqFt										
52	RAVELING		L	495.00 SqFt										
57	WEATHERING		L	4455.00 SqFt										
Sample Number:	323		Type:	R		Area:	5000.00 SqFt		PCI:	60				
Sample Comments:														
48	L & T CR		L	395.00 Ft										
48	L & T CR		M	87.00 Ft										
50	PATCHING		L	113.00 SqFt										
52	RAVELING		L	489.00 SqFt										
57	WEATHERING		L	4399.00 SqFt										
Sample Number:	330		Type:	R		Area:	5000.00 SqFt		PCI:	67				
Sample Comments:														

48	L & T CR	L	483.00	Ft
52	RAVELING	L	500.00	SqFt
57	WEATHERING	L	4500.00	SqFt
<b>Sample Number:</b> 337 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 63				
<b>Sample Comments:</b>				
48	L & T CR	L	504.00	Ft
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	63.00	SqFt
57	WEATHERING	L	4500.00	SqFt
<b>Sample Number:</b> 343 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 57				
<b>Sample Comments:</b>				
45	DEPRESSION	L	12.00	SqFt
48	L & T CR	L	800.00	Ft
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	20.00	SqFt
57	WEATHERING	L	4500.00	SqFt
<b>Sample Number:</b> 346 <b>Type:</b> R <b>Area:</b> 6700.00 SqFt <b>PCI:</b> 54				
<b>Sample Comments:</b>				
48	L & T CR	L	908.00	Ft
48	L & T CR	M	20.00	Ft
50	PATCHING	L	75.00	SqFt
52	RAVELING	L	662.00	SqFt
57	WEATHERING	L	5963.00	SqFt
<b>Sample Number:</b> 358 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 63				
<b>Sample Comments:</b>				
48	L & T CR	L	441.00	Ft
48	L & T CR	M	35.00	Ft
52	RAVELING	L	500.00	SqFt
57	WEATHERING	L	4500.00	SqFt
<b>Sample Number:</b> 362 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 63				
<b>Sample Comments:</b>				
48	L & T CR	L	442.00	Ft
48	L & T CR	M	50.00	Ft
52	RAVELING	L	500.00	SqFt
57	WEATHERING	L	4500.00	SqFt
<b>Sample Number:</b> 370 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 58				
<b>Sample Comments:</b>				
48	L & T CR	L	587.00	Ft
48	L & T CR	M	28.00	Ft
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	20.00	SqFt
57	WEATHERING	L	4500.00	SqFt
<b>Sample Number:</b> 374 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 55				
<b>Sample Comments:</b>				
48	L & T CR	L	703.00	Ft
48	L & T CR	M	12.00	Ft
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	20.00	SqFt
57	WEATHERING	L	4500.00	SqFt
<b>Sample Number:</b> 378 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 53				
<b>Sample Comments:</b>				
43	BLOCK CR	L	900.00	SqFt
48	L & T CR	L	549.00	Ft
48	L & T CR	M	50.00	Ft
52	RAVELING	L	2500.00	SqFt
57	WEATHERING	L	2500.00	SqFt



Network:		PMP		Name:		POMPANO BEACH AIRPARK							
Branch:	RW 6-24		Name:	RUNWAY 6-24		Use:	RUNWAY	Area:	556,428 SqFt				
Section:	6210		of	4	From:	-		To:	-		Last Const.:	1/1/2001	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P			
Area:	167,976 SqFt		Length:	6,100 Ft		Width:	25 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1972		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2001		Work Type:				Mill and Overlay		Code:	ML-OVL		Is Major M&R:	True
Work Date:	1/1/2010		Work Type:				Surface Treatment - Seal Coat		Code:	ST-SC		Is Major M&R:	False
Last Insp. Date: 11/30/2020													
		TotalSamples:		34		Surveyed:		8					
Conditions:	PCI: 62												
Inspection Comments:													
Sample Number:	104		Type:	R		Area:	5000.00 SqFt		PCI:	65			
Sample Comments:													
48	L & T CR		L	586.00 Ft									
52	RAVELING		L	500.00 SqFt									
57	WEATHERING		L	4500.00 SqFt									
Sample Number:	132		Type:	R		Area:	5000.00 SqFt		PCI:	59			
Sample Comments:													
48	L & T CR		L	596.00 Ft									
48	L & T CR		M	12.00 Ft									
52	RAVELING		L	250.00 SqFt									
57	WEATHERING		L	4750.00 SqFt									
Sample Number:	164		Type:	R		Area:	5000.00 SqFt		PCI:	68			
Sample Comments:													
48	L & T CR		L	314.00 Ft									
48	L & T CR		M	25.00 Ft									
52	RAVELING		L	250.00 SqFt									
57	WEATHERING		L	4750.00 SqFt									
Sample Number:	512		Type:	A		Area:	5000.00 SqFt		PCI:	48			
Sample Comments:													
48	L & T CR		L	184.00 Ft									
48	L & T CR		M	30.00 Ft									
50	PATCHING		L	3639.00 SqFt									
52	RAVELING		L	136.00 SqFt									
57	WEATHERING		L	1225.00 SqFt									
Sample Number:	540		Type:	R		Area:	5000.00 SqFt		PCI:	56			
Sample Comments:													
48	L & T CR		L	759.00 Ft									
50	PATCHING		L	960.00 SqFt									
52	RAVELING		L	202.00 SqFt									
57	WEATHERING		L	3838.00 SqFt									
Sample Number:	556		Type:	R		Area:	3325.00 SqFt		PCI:	59			
Sample Comments:													
48	L & T CR		L	576.00 Ft									
52	RAVELING		L	166.00 SqFt									
57	WEATHERING		L	3159.00 SqFt									
Sample Number:	568		Type:	R		Area:	5000.00 SqFt		PCI:	63			
Sample Comments:													
48	L & T CR		L	651.00 Ft									

52

RAVELING

L

250.00

SqFt

57

WEATHERING

L

4750.00

SqFt

Sample Number:

576

Type:

R

Area:

5025.00

SqFt

PCI:

64

Sample Comments:

48

L & T CR

L

628.00

Ft

52

RAVELING

L

251.00

SqFt

57

WEATHERING

L

4774.00

SqFt

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	RW 6-24		Name:	RUNWAY 6-24		Use:	RUNWAY		Area:	556,428 SqFt	
Section:	6220		of	4		From:	-		To:	-	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:		
Area:	35,000 SqFt		Length:	350 Ft		Width:	100 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1969		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1972		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2012		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	7		Surveyed:	2				
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	349		Type:	R		Area:	5000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5000.00		SqFt					
Sample Number:	354		Type:	R		Area:	5800.00 SqFt		PCI:	88	
Sample Comments:											
52	RAVELING		L	290.00		SqFt					
57	WEATHERING		L	5510.00		SqFt					

Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	RW 6-24		Name:	RUNWAY 6-24		Use:	RUNWAY	Area:	556,428 SqFt			
Section:	6225		of	4	From:	-		To:	-		Last Const.:	1/1/2012
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	17,500 SqFt		Length:	750 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1972		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2012		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 91											
Inspection Comments:												
Sample Number:	148		Type:	R		Area:	4375.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	8.00 Ft								
57	WEATHERING		L	4375.00 SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK								
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	171,809 SqFt			
Section:	4305	of	5	From:	-			To:	-		Last Const.:	12/25/1999
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:				Category:	Rank: P		
Area:	31,764 SqFt		Length:	675 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	12/25/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:	11/30/2020		TotalSamples:	7		Surveyed:	1					
Conditions:	PCI:	36										
Inspection Comments:												
Sample Number:	601	Type:	R	Area:	4845.00 SqFt		PCI:	36				
Sample Comments:												
43	BLOCK CR	L	4569.00	SqFt								
45	DEPRESSION	L	18.00	SqFt								
50	PATCHING	L	248.00	SqFt								
50	PATCHING	M	28.00	SqFt								
52	RAVELING	L	3641.00	SqFt								
52	RAVELING	M	910.00	SqFt								
52	RAVELING	H	18.00	SqFt								



Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	171,809 SqFt			
Section:	4310		of	5	From:	-		To:	-		Last Const.:	12/25/1999
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:	Rank: P		
Area:	49,387 SqFt		Length:	1,850 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1999		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	10		Surveyed:	2					
Conditions:	PCI: 27											
Inspection Comments:												
Sample Number:	402		Type:	R		Area:	6346.00 SqFt		PCI:	29		
Sample Comments:												
43	BLOCK CR		L	5033.00 SqFt								
45	DEPRESSION		L	44.00 SqFt								
50	PATCHING		L	1040.00 SqFt								
50	PATCHING		M	273.00 SqFt								
52	RAVELING		L	10.00 SqFt								
52	RAVELING		M	5023.00 SqFt								
Sample Number:	500		Type:	R		Area:	4375.00 SqFt		PCI:	23		
Sample Comments:												
43	BLOCK CR		L	2580.00 SqFt								
45	DEPRESSION		L	80.00 SqFt								
48	L & T CR		L	47.00 Ft								
50	PATCHING		M	48.00 SqFt								
52	RAVELING		M	4327.00 SqFt								

Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	171,809 SqFt			
Section:	4315		of	5	From:	-		To:	-		Last Const.:	12/25/1999
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:	Rank: P		
Area:	57,861 SqFt		Length:	2,530 Ft		Width:	18 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1999		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	15		Surveyed:	2					
Conditions:	PCI: 44											
Inspection Comments:												
Sample Number:	308		Type:	R		Area:	3449.00 SqFt		PCI:	65		
Sample Comments:												
48	L & T CR		L	201.00 Ft								
48	L & T CR		M	15.00 Ft								
52	RAVELING		L	1724.00 SqFt								
57	WEATHERING		L	1725.00 SqFt								
Sample Number:	700		Type:	R		Area:	4000.00 SqFt		PCI:	25		
Sample Comments:												
41	ALLIGATOR CR		M	221.00 SqFt								
43	BLOCK CR		L	3473.00 SqFt								
45	DEPRESSION		L	98.00 SqFt								
50	PATCHING		L	62.00 SqFt								
50	PATCHING		M	244.00 SqFt								
52	RAVELING		L	3685.00 SqFt								
52	RAVELING		H	9.00 SqFt								

Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	171,809 SqFt			
Section:	4320		of	5	From:	-		To:	-		Last Const.:	12/25/1999
Surface:	APC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	16,033 SqFt		Length:	200 Ft		Width:	40 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1972		Work Type:	New Construction - PCC				Code:	NC-PC		Is Major M&R:	True
Work Date:	12/25/1999		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 34											
Inspection Comments:												
Sample Number:	208		Type:	R		Area:	3500.00 SqFt		PCI:	34		
Sample Comments:												
42	BLEEDING		N	24.00 SqFt								
47	JT REF. CR		M	456.00 Ft								
48	L & T CR		L	177.00 Ft								
48	L & T CR		M	80.00 Ft								
52	RAVELING		L	688.00 SqFt								
52	RAVELING		M	59.00 SqFt								
57	WEATHERING		L	2753.00 SqFt								

Network:	PMP			Name:	POMPANO BEACH AIRPARK					
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	171,809 SqFt	
Section:	4325	of	5	From:	-	To:	-	Last Const.:	6/1/2018	
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P	
Area:	16,764 SqFt		Length:	405 Ft		Width:	55 Ft			
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:	Ft
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	12/25/1999		Work Type: New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Work Date:	6/1/2018		Work Type: Mill and Overlay			Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1			
Conditions:	PCI:	81								
Inspection Comments:										
Sample Number:	602	Type:	R	Area:	4682.00 SqFt		PCI:	81		
Sample Comments:										
48	L & T CR		L	223.00 Ft						
57	WEATHERING		L	4682.00 SqFt						

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	75,696 SqFt		
Section:	105 of 2		From:	-		To:	-		Last Const.:	11/1/2012	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Rank:	P	
Area:	61,729 SqFt		Length:	1,500 Ft		Width:	40 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1968		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	11/1/2012		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	11		Surveyed:	2				
Conditions:	PCI: 90										
Inspection Comments:											
Sample Number:	101		Type:	R		Area:	5000.00 SqFt		PCI:	90	
Sample Comments:											
48	L & T CR		L	35.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	200		Type:	R		Area:	5000.00 SqFt		PCI:	91	
Sample Comments:											
48	L & T CR		L	11.00 Ft							
57	WEATHERING		L	5000.00 SqFt							



Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	75,696 SqFt		
Section:	115 of 2		From:	-		To:	-		Last Const.:	1/1/1997	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	13,967 SqFt		Length:	350 Ft		Width:	40 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1950		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1997		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date: 11/30/2020											
TotalSamples:			3		Surveyed: 1						
Conditions:	PCI: 47										
Inspection Comments:											
Sample Number:	106		Type:	R		Area:	5399.00 SqFt		PCI:	47	
Sample Comments:											
43	BLOCK CR		L	300.00 SqFt							
45	DEPRESSION		L	108.00 SqFt							
48	L & T CR		L	680.00 Ft							
50	PATCHING		L	13.00 SqFt							
52	RAVELING		L	800.00 SqFt							
57	WEATHERING		L	4127.00 SqFt							
57	WEATHERING		M	459.00 SqFt							

Network:	PMP		Name:		POMPANO BEACH AIRPARK							
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	104,085 SqFt			
Section:	210		of	1	From:	-		To:	-		Last Const.:	1/1/1972
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	104,085 SqFt		Length:	2,190 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1972		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2008		Work Type: Surface Treatment - Seal Coat					Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	20		Surveyed:	3					
Conditions:	PCI: 59											
Inspection Comments:												
Sample Number:	706		Type:	R		Area:	5000.00 SqFt		PCI:	58		
Sample Comments:												
48	L & T CR		L	370.00 Ft								
48	L & T CR		M	271.00 Ft								
52	RAVELING		L	1250.00 SqFt								
57	WEATHERING		L	3750.00 SqFt								
Sample Number:	712		Type:	R		Area:	5000.00 SqFt		PCI:	65		
Sample Comments:												
48	L & T CR		L	397.00 Ft								
48	L & T CR		M	120.00 Ft								
52	RAVELING		L	1250.00 SqFt								
57	WEATHERING		L	3750.00 SqFt								
Sample Number:	719		Type:	R		Area:	6822.00 SqFt		PCI:	55		
Sample Comments:												
45	DEPRESSION		L	52.00 SqFt								
48	L & T CR		L	779.00 Ft								
48	L & T CR		M	333.00 Ft								
50	PATCHING		L	400.00 SqFt								
57	WEATHERING		L	6422.00 SqFt								

Network:	PMP	Name:		POMPANO BEACH AIRPARK							
Branch:	TW C	Name:	TAXIWAY C		Use:	TAXIWAY	Area:	42,764 SqFt			
Section:	305	of 3	From:	-	To:	-	Last Const.:	1/1/1970			
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:	Rank: P			
Area:	26,289 SqFt		Length:	650 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0	Lanes:	0				
Section Comments:											
Work Date:	1/1/1970		Work Type:			BUILT		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2010		Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	5		Surveyed:	2				
Conditions:	PCI: 64										
Inspection Comments:											
Sample Number:	300		Type:	R		Area:	6163.00 SqFt		PCI:	63	
Sample Comments:											
45	DEPRESSION		L	87.00 SqFt							
48	L & T CR		L	578.00 Ft							
52	RAVELING		L	924.00 SqFt							
57	WEATHERING		L	5239.00 SqFt							
Sample Number:	303		Type:	R		Area:	5000.00 SqFt		PCI:	67	
Sample Comments:											
48	L & T CR		L	187.00 Ft							
50	PATCHING		L	2.00 SqFt							
52	RAVELING		L	4998.00 SqFt							

Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	42,764 SqFt			
Section:	350		of	3	From:	-		To:	-		Last Const.:	11/1/2012
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	6,807 SqFt		Length:	212 Ft		Width:	40 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1970		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat					Code:	ST-SC		Is Major M&R:	False
Work Date:	11/1/2012		Work Type: Mill and Overlay					Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 92											
Inspection Comments:												
Sample Number:	308		Type:	R		Area:	6807.00 SqFt		PCI:	92		
Sample Comments:												
48	L & T CR		L	3.00 Ft								
57	WEATHERING		L	6807.00 SqFt								

Network:		PMP		Name:		POMPANO BEACH AIRPARK			
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	42,764 SqFt
Section:	360	of	3	From:	-	To:	-	Last Const.:	11/1/2012
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	9,668 SqFt	Length:	132 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1968	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2010	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	11/1/2012	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	11/30/2020	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	92							
Inspection Comments:									
Sample Number:	306	Type:	R	Area:	5073.00 SqFt	PCI:	92		
Sample Comments:									
48	L & T CR	L	5.00 Ft						
57	WEATHERING	L	5073.00 SqFt						



Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	183,711 SqFt		
Section:	405 of 5		From:	-		To:	-		Last Const.:	1/1/2021	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	90,211 SqFt		Length:	1,464 Ft		Width:	35 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1972		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2008		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2021		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/8/2017		TotalSamples:	20		Surveyed:	3				
Conditions:	PCI: 63		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	404		Type:	R		Area:	5000.00 SqFt		PCI:	65	
Sample Comments:											
48	L & T CR		L	410.00 Ft							
48	L & T CR		M	5.00 Ft							
52	RAVELING		L	500.00 SqFt							
57	WEATHERING		L	4500.00 SqFt							
Sample Number:	413		Type:	R		Area:	5000.00 SqFt		PCI:	59	
Sample Comments:											
48	L & T CR		L	595.00 Ft							
52	RAVELING		L	350.00 SqFt							
53	RUTTING		L	132.00 SqFt							
57	WEATHERING		L	4650.00 SqFt							
Sample Number:	420		Type:	R		Area:	5000.00 SqFt		PCI:	65	
Sample Comments:											
48	L & T CR		L	565.00 Ft							
52	RAVELING		L	1000.00 SqFt							
57	WEATHERING		L	4000.00 SqFt							

Network:		PMP		Name:		POMPANO BEACH AIRPARK									
Branch:		TW D		Name:		TAXIWAY D		Use:		TAXIWAY		Area:		183,711 SqFt	
Section:		410		of 5		From:		-		To:		-		Last Const.: 5/1/2018	
Surface:		AAC		Family:		CA653-GA-TW-AAC-APC		Zone:		Category:		Rank:		P	
Area:		12,212 SqFt		Length:		180 Ft		Width:		80 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date:		1/1/1972		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/2008		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Work Date:		7/1/2008		Work Type:		Surface Treatment - Seal Coat		Code:		ST-SC		Is Major M&R:		False	
Work Date:		5/1/2018		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Last Insp. Date:		11/30/2020		TotalSamples:		2		Surveyed:		1					
Conditions:		PCI: 92													
Inspection Comments:															
Sample Number:		416		Type:		R		Area:		5815.00 SqFt		PCI:		92	
Sample Comments:															
48		L & T CR		L		4.00 Ft									
57		WEATHERING		L		5815.00 SqFt									

Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	183,711 SqFt			
Section:	412		of	5	From:	-		To:	-		Last Const.:	5/1/2018
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	24,824 SqFt		Length:	560 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1972		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2008		Work Type: Mill and Overlay					Code:	ML-OVL		Is Major M&R:	True
Work Date:	5/1/2018		Work Type: Mill and Overlay					Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 83											
Inspection Comments:												
Sample Number:	414		Type:	R		Area:	5621.00 SqFt		PCI:	83		
Sample Comments:												
50	PATCHING		L	420.00 SqFt								
57	WEATHERING		L	5201.00 SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	183,711 SqFt		
Section:	415	of 5	From:	-		To:	-		Last Const.:	11/1/2012	
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	36,063 SqFt		Length:	400 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1972		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2008		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	11/1/2012		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	9		Surveyed: 2					
Conditions:	PCI: 82										
Inspection Comments:											
Sample Number:	420	Type:	R	Area:	4431.00 SqFt		PCI:	86			
Sample Comments:											
48	L & T CR		L	17.00 Ft							
50	PATCHING		L	60.00 SqFt							
57	WEATHERING		L	4372.00 SqFt							
Sample Number:	522	Type:	R	Area:	4088.00 SqFt		PCI:	78			
Sample Comments:											
48	L & T CR		L	7.00 Ft							
50	PATCHING		L	391.00 SqFt							
57	WEATHERING		L	3697.00 SqFt							

Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	183,711 SqFt			
Section:	420		of	5	From:	-		To:	-		Last Const.:	1/1/2008
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	20,401 SqFt		Length:	200 Ft		Width:	95 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1972		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2008		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	7/1/2008		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 40											
Inspection Comments:												
Sample Number:	410		Type:	R		Area:	5000.00 SqFt		PCI:	40		
Sample Comments:												
41	ALLIGATOR CR		L	423.00 SqFt								
48	L & T CR		L	372.00 Ft								
56	SWELLING		L	100.00 SqFt								
57	WEATHERING		L	4750.00 SqFt								
57	WEATHERING		M	250.00 SqFt								



Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	12,246 SqFt			
Section:	505		of	1	From:	-		To:	-		Last Const.:	1/1/2012
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	12,246 SqFt		Length:	200 Ft		Width:	40 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1968		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat					Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2012		Work Type: Mill and Overlay					Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	3		Surveyed:	1					
Conditions:	PCI: 89											
Inspection Comments:												
Sample Number:	500		Type:	R		Area:	4537.00 SqFt		PCI:	89		
Sample Comments:												
48	L & T CR		L	49.00 Ft								
57	WEATHERING		L	4537.00 SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	151,992 SqFt		
Section:	610 of 4		From:	-		To:	-		Last Const.:	1/1/1972	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	120,125 SqFt		Length:	2,515 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1972		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	24		Surveyed:	3				
Conditions:	PCI: 59										
Inspection Comments:											
Sample Number:	601		Type:	R		Area:	5000.00 SqFt		PCI:	55	
Sample Comments:											
48	L & T CR		L	336.00 Ft							
48	L & T CR		M	156.00 Ft							
50	PATCHING		L	175.00 SqFt							
52	RAVELING		L	463.00 SqFt							
52	RAVELING		M	195.00 SqFt							
57	WEATHERING		L	4167.00 SqFt							
Sample Number:	609		Type:	R		Area:	5000.00 SqFt		PCI:	61	
Sample Comments:											
48	L & T CR		L	457.00 Ft							
48	L & T CR		M	156.00 Ft							
52	RAVELING		L	500.00 SqFt							
56	SWELLING		L	20.00 SqFt							
57	WEATHERING		L	4500.00 SqFt							
Sample Number:	625		Type:	R		Area:	5000.00 SqFt		PCI:	62	
Sample Comments:											
48	L & T CR		L	494.00 Ft							
48	L & T CR		M	88.00 Ft							
52	RAVELING		L	500.00 SqFt							
57	WEATHERING		L	4500.00 SqFt							

Network:		PMP		Name:		POMPANO BEACH AIRPARK									
Branch:		TW F		Name:		TAXIWAY F		Use:		TAXIWAY		Area:		151,992 SqFt	
Section:		612		of 4		From:		-		To:		-		Last Const.: 5/1/2018	
Surface:		AAC		Family:		CA653-GA-TW-AAC-APC		Zone:		Category:		Rank:		P	
Area:		15,275 SqFt		Length:		300 Ft		Width:		50 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date:		1/1/1972		Work Type:		New Construction - Initial		Code:		NU-IN		Is Major M&R:		True	
Work Date:		1/1/2008		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Work Date:		5/1/2018		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Last Insp. Date:		11/30/2020		TotalSamples:		3		Surveyed:		1					
Conditions:		PCI: 93													
Inspection Comments:															
Sample Number:		616		Type:		R		Area:		6575.00 SqFt		PCI:		93	
Sample Comments:															
48		L & T CR		L		4.00 Ft									
57		WEATHERING		L		3288.00 SqFt									

Network:	PMP			Name:	POMPANO BEACH AIRPARK				
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	151,992 SqFt
Section:	615	of 4	From:	-			To:	-	Last Const.: 5/1/2018
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC		Zone:	Category:		Rank: P	
Area:	8,519 SqFt		Length:	125 Ft		Width:	55 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1969		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1972		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2012		Work Type: Mill and Overlay				Code:	ML-OVL	Is Major M&R: True
Work Date:	5/1/2018		Work Type: Mill and Overlay				Code:	ML-OVL	Is Major M&R: True
Last Insp. Date:	11/30/2020		TotalSamples:	2		Surveyed:	1		
Conditions:	PCI: 95								
Inspection Comments:									
Sample Number:	614	Type:	R	Area:	3392.00 SqFt		PCI:	95	
Sample Comments:									
57	WEATHERING		L	1696.00 SqFt					

Network:		PMP		Name:		POMPANO BEACH AIRPARK									
Branch:		TW F		Name:		TAXIWAY F		Use:		TAXIWAY		Area:		151,992 SqFt	
Section:		620		of 4		From:		-		To:		-		Last Const.: 1/1/2012	
Surface:		AAC		Family:		CA653-GA-TW-AAC-APC		Zone:		Category:		Rank:		P	
Area:		8,073 SqFt		Length:		140 Ft		Width:		50 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date:		1/1/1969		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/1972		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/2010		Work Type:		Surface Treatment - Seal Coat		Code:		ST-SC		Is Major M&R:		False	
Work Date:		1/1/2012		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Last Insp. Date:		11/30/2020		TotalSamples:		2		Surveyed:		1					
Conditions:		PCI: 89													
Inspection Comments:															
Sample Number:		612		Type:		R		Area:		4500.00 SqFt		PCI:		89	
Sample Comments:															
48		L & T CR		L		74.00 Ft									
57		WEATHERING		L		4500.00 SqFt									



Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY	Area:	217,659 SqFt		
Section:	710	of	4	From:	-	To:	-	Last Const.:	6/1/2012		
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	15,387 SqFt		Length:	260 Ft		Width:	55 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	6/1/2012		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	89									
Inspection Comments:											
Sample Number:	251	Type:	R	Area:	4306.00 SqFt		PCI:	89			
Sample Comments:											
48	L & T CR		L	39.00 Ft							
52	RAVELING		L	3.00 SqFt							
57	WEATHERING		L	2152.00 SqFt							

Network:	PMP			Name:	POMPANO BEACH AIRPARK							
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY		Area:	217,659 SqFt		
Section:	715 of 4		From:	-			To:	-		Last Const.:	6/1/2014	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:	Rank: P		
Area:	17,469 SqFt		Length:	350 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	6/1/2014		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 90											
Inspection Comments:												
Sample Number:	147		Type:	R		Area:	5534.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	25.00 Ft								
57	WEATHERING		L	5534.00 SqFt								

Network:	PMP	Name:		POMPANO BEACH AIRPARK						
Branch:	TW G	Name:	TAXIWAY G	Use:	TAXIWAY	Area:	217,659 SqFt			
Section:	720	of	4	From:	-	To:	-	Last Const.:	5/1/2018	
Surface:	AC	Family:	CA653-GA-TW-AC	Zone:		Category:		Rank:	P	
Area:	151,212 SqFt	Length:	2,975 Ft	Width:	35 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0			
Section Comments:										
Work Date:	5/1/2018	Work Type:			New Construction - AC		Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	11/30/2020	TotalSamples:	30	Surveyed:	3					
Conditions:	PCI:	92								
Inspection Comments:										
Sample Number:	718	Type:	R	Area:	5250.00 SqFt	PCI:	93			
Sample Comments:										
48	L & T CR	L	6.00 Ft							
57	WEATHERING	L	2625.00 SqFt							
Sample Number:	723	Type:	R	Area:	4395.00 SqFt	PCI:	88			
Sample Comments:										
48	L & T CR	L	7.00 Ft							
50	PATCHING	L	60.00 SqFt							
57	WEATHERING	L	2168.00 SqFt							
Sample Number:	729	Type:	R	Area:	4641.00 SqFt	PCI:	95			
Sample Comments:										
57	WEATHERING	L	2320.00 SqFt							

Network:	PMP			Name:	POMPANO BEACH AIRPARK								
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY	Area:	217,659 SqFt				
Section:	725	of	4	From:	-			To:	-		Last Const.:	6/1/2012	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P		
Area:	33,591 SqFt		Length:	835 Ft		Width:	35 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	6/1/2012			Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:	11/30/2020			TotalSamples:	9			Surveyed:	1				
Conditions:	PCI:	86											
Inspection Comments:													
Sample Number:	709	Type:	R	Area:	3500.00 SqFt			PCI:	86				
Sample Comments:													
48	L & T CR		L	40.00 Ft									
57	WEATHERING		L	3325.00 SqFt									
57	WEATHERING		M	175.00 SqFt									

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW G1		Name:	TAXIWAY G1		Use:	TAXIWAY	Area:	21,726 SqFt		
Section:	700	of	1	From:	-	To:	-	Last Const.:	6/1/2012		
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	21,726 SqFt		Length:	600 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	6/1/2012		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	90									
Inspection Comments:											
Sample Number:	701	Type:	R	Area:	4989.00 SqFt		PCI:	90			
Sample Comments:											
48	L & T CR	L	7.00 Ft								
57	WEATHERING	L	4969.00 SqFt								
57	WEATHERING	M	20.00 SqFt								



Network:	PMP			Name:	POMPANO BEACH AIRPARK						
Branch:	TW G3		Name:	TAXIWAY G3		Use:	TAXIWAY	Area:	15,789 SqFt		
Section:	730	of 1		From:	-		To:	-		Last Const.:	5/1/2018
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:	Rank: P	
Area:	15,789 SqFt		Length:	148 Ft		Width:	75 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:		0		Lanes:		0
Section Comments:											
Work Date:	5/1/2018		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Last Insp. Date:	11/30/2020		TotalSamples:	3		Surveyed:		1			
Conditions:	PCI: 93										
Inspection Comments:											
Sample Number:	700	Type:	R	Area:	5245.00 SqFt		PCI:		93		
Sample Comments:											
48	L & T CR		L	6.00 Ft							
57	WEATHERING		L	2622.00 SqFt							

Network:	PMP			Name:	POMPANO BEACH AIRPARK					
Branch:	TW G4		Name:	TAXIWAY G4		Use:	TAXIWAY	Area:	12,199 SqFt	
Section:	740 of 1		From:	-		To:	-		Last Const.:	5/1/2018
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Rank:	P
Area:	12,199 SqFt		Length:	139 Ft		Width:	70 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date: 5/1/2018			Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True
Last Insp. Date: 11/30/2020			TotalSamples: 3		Surveyed: 1					
Conditions: PCI: 92										
Inspection Comments:										
Sample Number:	701	Type:	R	Area:	4012.00 SqFt		PCI:	92		
Sample Comments:										
48	L & T CR		L	1.00 Ft						
56	SWELLING		L	1.00 SqFt						
57	WEATHERING		L	2006.00 SqFt						

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW G5		Name:	TAXIWAY G5		Use:	TAXIWAY	Area:	16,699 SqFt		
Section:	750	of	1	From:	-	To:	-	Last Const.:	5/1/2018		
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	16,699 SqFt	Length:	150 Ft		Width:	100 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	5/1/2018		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	3		Surveyed:	1				
Conditions:	PCI:	91									
Inspection Comments:											
Sample Number:	700	Type:	R	Area:	5538.00 SqFt		PCI:	91			
Sample Comments:											
48	L & T CR	L	33.00 Ft								
57	WEATHERING	L	2769.00 SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK										
Branch:	TW K		Name:	TAXIWAY K		Use:	TAXIWAY	Area:	110,731 SqFt					
Section:	1110		of	3		From:	-		To:	-		Last Const.:	11/1/2012	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:			Rank:	P	
Area:	89,261 SqFt		Length:	2,500 Ft		Width:	35 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False		
Work Date:	11/1/2012		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Last Insp. Date:	11/30/2020		TotalSamples:	25		Surveyed:	3							
Conditions:	PCI: 92													
Inspection Comments:														
Sample Number:	102		Type:	R		Area:	3772.00 SqFt		PCI:	91				
Sample Comments:														
48	L & T CR		L	9.00 Ft										
57	WEATHERING		L	3772.00 SqFt										
Sample Number:	113		Type:	R		Area:	3500.00 SqFt		PCI:	94				
Sample Comments:														
57	WEATHERING		L	3500.00 SqFt										
Sample Number:	121		Type:	R		Area:	3500.00 SqFt		PCI:	91				
Sample Comments:														
48	L & T CR		L	9.00 Ft										
57	WEATHERING		L	3500.00 SqFt										

Network:		PMP		Name:		POMPANO BEACH AIRPARK											
Branch:		TW K		Name:		TAXIWAY K		Use:		TAXIWAY		Area:		110,731 SqFt			
Section:		1115		of 3		From:		-		To:		-		Last Const.:		6/1/2014	
Surface:		AC		Family:		CA653-GA-TW-AC		Zone:		Category:		Rank:		P			
Area:		7,373 SqFt		Length:		150 Ft		Width:		50 Ft							
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft					
Shoulder:		Street Type:		Grade:		0		Lanes:		0							
Section Comments:																	
Work Date:		1/1/2010		Work Type:		Surface Treatment - Seal Coat		Code:		ST-SC		Is Major M&R:		False			
Work Date:		6/1/2014		Work Type:		New Construction - AC		Code:		NC-AC		Is Major M&R:		True			
Last Insp. Date:		11/30/2020		TotalSamples:		2		Surveyed:		1							
Conditions:		PCI:		83													
Inspection Comments:																	
Sample Number:		128		Type:		R		Area:		3629.00 SqFt		PCI:		83			
Sample Comments:																	
48		L & T CR		L		18.00 Ft											
56		SWELLING		L		40.00 SqFt											
57		WEATHERING		L		3448.00 SqFt											
57		WEATHERING		M		181.00 SqFt											

Network:		PMP		Name:		POMPANO BEACH AIRPARK																	
Branch:		TW K		Name:		TAXIWAY K		Use:		TAXIWAY		Area:		110,731 SqFt									
Section:		1120		of 3		From:		-		To:		-		Last Const.:		6/1/2012							
Surface:		AC		Family:		CA653-GA-TW-AC		Zone:				Category:				Rank:		P					
Area:		14,097 SqFt		Length:		280 Ft		Width:		50 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				1/1/2010				Work Type:				Surface Treatment - Seal Coat				Code:		ST-SC		Is Major M&R:		False	
Work Date:				6/1/2012				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:		True	
Last Insp. Date:				11/30/2020				TotalSamples:				3				Surveyed:				1			
Conditions:				PCI:				90															
Inspection Comments:																							
Sample Number:		131		Type:		R		Area:		5859.00 SqFt		PCI:		90									
Sample Comments:																							
48		L & T CR		L		36.00 Ft																	
57		WEATHERING		L		5859.00 SqFt																	



Network:	PMP			Name:	POMPANO BEACH AIRPARK				
Branch:	TW L		Name:	TAXIWAY L		Use:	TAXIWAY	Area:	201,930 SqFt
Section:	1202	of	4	From:	-	To:	-	Last Const.:	1/1/1996
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	21,209 SqFt	Length:	290 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1950	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1996	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Work Date:	1/1/2010	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Last Insp. Date: 11/30/2020									
		TotalSamples:	4	Surveyed:		1			
Conditions:	PCI:	62							
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	5024.00 SqFt	PCI:	62		
Sample Comments:									
48	L & T CR	L	323.00	Ft					
48	L & T CR	M	60.00	Ft					
52	RAVELING	M	150.00	SqFt					
56	SWELLING	L	102.00	SqFt					
57	WEATHERING	L	4874.00	SqFt					

Network:	PMP			Name:	POMPANO BEACH AIRPARK					
Branch:	TW L		Name:	TAXIWAY L		Use:	TAXIWAY	Area:	201,930 SqFt	
Section:	1205	of 4	From:	-			To:	-	Last Const.:	1/1/1972
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P
Area:	13,025 SqFt	Length:	260 Ft		Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft			Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0			Lanes:	0	
Section Comments:										
Work Date:	1/1/1972		Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	3		Surveyed:	1			
Conditions:	PCI:	51								
Inspection Comments:										
Sample Number:	113	Type:	R	Area:	3750.00 SqFt		PCI:	51		
Sample Comments:										
48	L & T CR	L	224.00		Ft					
48	L & T CR	M	231.00		Ft					
50	PATCHING	L	280.00		SqFt					
52	RAVELING	L	1214.00		SqFt					
57	WEATHERING	L	2256.00		SqFt					

Network:		PMP		Name:		POMPANO BEACH AIRPARK																	
Branch:		TW L		Name:		TAXIWAY L		Use:		TAXIWAY		Area:		201,930 SqFt									
Section:		1210		of 4		From:		-		To:		-		Last Const.: 1/1/1996									
Surface:		AAC		Family:		CA653-GA-TW-AAC-APC		Zone:		Category:		Rank:		P									
Area:		152,867 SqFt		Length:		2,550 Ft		Width:		60 Ft													
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft											
Shoulder:		Street Type:		Grade:		0		Lanes:		0													
Section Comments:																							
Work Date:				1/1/1950				Work Type:				BUILT				Code:		IMPORTED		Is Major M&R:		True	
Work Date:				1/1/1996				Work Type:				Mill and Overlay				Code:		ML-OVL		Is Major M&R:		True	
Work Date:				1/1/2010				Work Type:				Surface Treatment - Seal Coat				Code:		ST-SC		Is Major M&R:		False	
Last Insp. Date:				11/30/2020				TotalSamples:				26				Surveyed:				3			
Conditions:				PCI:				60															
Inspection Comments:																							
Sample Number:		211		Type:		R		Area:		6000.00 SqFt		PCI:		58									
Sample Comments:																							
48	L & T CR			L		532.00 Ft																	
48	L & T CR			M		25.00 Ft																	
52	RAVELING			L		1500.00 SqFt																	
52	RAVELING			M		300.00 SqFt																	
57	WEATHERING			L		4200.00 SqFt																	
Sample Number:		216		Type:		R		Area:		6000.00 SqFt		PCI:		61									
Sample Comments:																							
48	L & T CR			L		434.00 Ft																	
48	L & T CR			M		35.00 Ft																	
50	PATCHING			L		1000.00 SqFt																	
52	RAVELING			L		1500.00 SqFt																	
57	WEATHERING			L		3500.00 SqFt																	
Sample Number:		222		Type:		R		Area:		6000.00 SqFt		PCI:		60									
Sample Comments:																							
48	L & T CR			L		696.00 Ft																	
52	RAVELING			L		1500.00 SqFt																	
52	RAVELING			M		300.00 SqFt																	
57	WEATHERING			L		4200.00 SqFt																	

Network:		PMP		Name:		POMPANO BEACH AIRPARK						
Branch:	TW L		Name:	TAXIWAY L		Use:	TAXIWAY	Area:	201,930 SqFt			
Section:	1215		of	4	From:	-		To:	-		Last Const.:	6/1/2012
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	14,829 SqFt		Length:	250 Ft		Width:	60 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1950		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	7/1/2008		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	6/1/2012		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	3		Surveyed:	1					
Conditions:	PCI: 87											
Inspection Comments:												
Sample Number:	233		Type:	R		Area:	6207.00 SqFt		PCI:	87		
Sample Comments:												
48	L & T CR		L	4.00 Ft								
57	WEATHERING		L	5586.00 SqFt								
57	WEATHERING		M	621.00 SqFt								

Network:	PMP		Name:	POMPANO BEACH AIRPARK										
Branch:	TW M		Name:	TAXIWAY M		Use:	TAXIWAY	Area:	219,746 SqFt					
Section:	1305		of	8		From:	-		To:	-		Last Const.:	1/1/1970	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:			Rank:	P	
Area:	27,738 SqFt		Length:	884 Ft		Width:	50 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1970		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False		
Last Insp. Date:	11/30/2020		TotalSamples:	6		Surveyed:	1							
Conditions:	PCI: 68													
Inspection Comments:														
Sample Number:	104		Type:	R		Area:	4000.00 SqFt		PCI:	68				
Sample Comments:														
48	L & T CR		L	351.00 Ft										
52	RAVELING		L	1600.00 SqFt										
57	WEATHERING		L	2400.00 SqFt										

Network:	PMP		Name:	POMPANO BEACH AIRPARK							
Branch:	TW M		Name:	TAXIWAY M		Use:	TAXIWAY	Area:	219,746 SqFt		
Section:	1306	of	8	From:	-	To:	-	Last Const.:	11/1/2012		
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P	
Area:	29,856 SqFt		Length:	300 Ft		Width:	50 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	11/1/2012		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	6		Surveyed:	2				
Conditions:	PCI: 81										
Inspection Comments:											
Sample Number:	108	Type:	R	Area:	6535.00 SqFt		PCI:	86			
Sample Comments:											
50	PATCHING	L	279.00	SqFt							
57	WEATHERING	L	6256.00	SqFt							
Sample Number:	211	Type:	R	Area:	4096.00 SqFt		PCI:	74			
Sample Comments:											
48	L & T CR	L	6.00	Ft							
50	PATCHING	L	412.00	SqFt							
52	RAVELING	L	65.00	SqFt							
57	WEATHERING	L	3619.00	SqFt							



Network:	PMP			Name:	POMPANO BEACH AIRPARK						
Branch:	TW M		Name:	TAXIWAY M		Use:	TAXIWAY	Area:	219,746 SqFt		
Section:	1310	of	8	From:	-	To:	-	Last Const.:	1/1/1999		
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:	Rank: P			
Area:	24,002 SqFt		Length:	900 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:			Grade:	0	Lanes:		0			
Section Comments:											
Work Date:	1/1/1999		Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True	
Work Date:	1/1/2010		Work Type:			Surface Treatment - Seal Coat	Code:	ST-SC	Is Major M&R:		False
Last Insp. Date:	11/30/2020		TotalSamples:	7		Surveyed:		2			
Conditions:	PCI: 82										
Inspection Comments:											
Sample Number:	114	Type:	R	Area:	3500.00 SqFt		PCI:	86			
Sample Comments:											
48	L & T CR		L	66.00 Ft							
50	PATCHING		L	14.00 SqFt							
57	WEATHERING		L	3486.00 SqFt							
Sample Number:	116	Type:	R	Area:	3500.00 SqFt		PCI:	78			
Sample Comments:											
48	L & T CR		L	159.00 Ft							
52	RAVELING		L	25.00 SqFt							
56	SWELLING		L	4.00 SqFt							
57	WEATHERING		L	3475.00 SqFt							

Network:		PMP		Name:		POMPANO BEACH AIRPARK									
Branch:		TW M		Name:		TAXIWAY M		Use:		TAXIWAY		Area:		219,746 SqFt	
Section:		1315		of 8		From:		-		To:		-		Last Const.: 1/1/1999	
Surface:		AC		Family:		CA653-GA-TW-AC		Zone:		Category:		Rank:		P	
Area:		16,359 SqFt		Length:		125 Ft		Width:		110 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date:		1/1/1999		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/2010		Work Type:		Surface Treatment - Seal Coat		Code:		ST-SC		Is Major M&R:		False	
Last Insp. Date:		11/30/2020		TotalSamples:		3		Surveyed:		1					
Conditions:		PCI: 69													
Inspection Comments:															
Sample Number:		200		Type:		R		Area:		5981.00 SqFt		PCI:		69	
Sample Comments:															
42	BLEEDING			N		6.00 SqFt									
48	L & T CR			L		332.00 Ft									
50	PATCHING			L		118.00 SqFt									
52	RAVELING			L		586.00 SqFt									
57	WEATHERING			L		5277.00 SqFt									

Network:	PMP		Name:	POMPANO BEACH AIRPARK								
Branch:	TW M		Name:	TAXIWAY M		Use:	TAXIWAY	Area:	219,746 SqFt			
Section:	1320		of	8	From:	-		To:	-		Last Const.:	1/1/2001
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	69,823 SqFt		Length:	1,270 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1970		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2001		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	14		Surveyed:	3					
Conditions:	PCI: 64											
Inspection Comments:												
Sample Number:	198		Type:	R		Area:	5687.00 SqFt		PCI:	64		
Sample Comments:												
45	DEPRESSION		L	95.00 SqFt								
48	L & T CR		L	290.00 Ft								
52	RAVELING		L	5687.00 SqFt								
Sample Number:	202		Type:	R		Area:	5000.00 SqFt		PCI:	64		
Sample Comments:												
48	L & T CR		L	475.00 Ft								
50	PATCHING		L	144.00 SqFt								
52	RAVELING		L	4856.00 SqFt								
Sample Number:	206		Type:	R		Area:	5000.00 SqFt		PCI:	64		
Sample Comments:												
48	L & T CR		L	300.00 Ft								
48	L & T CR		M	50.00 Ft								
52	RAVELING		L	5000.00 SqFt								

Network:	PMP			Name:	POMPANO BEACH AIRPARK				
Branch:	TW M		Name:	TAXIWAY M		Use:	TAXIWAY	Area:	219,746 SqFt
Section:	1322	of	8	From:	-	To:	-	Last Const.:	5/1/2018
Surface:	AC	Family:	CA653-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	30,907 SqFt	Length:	360 Ft	Width:	54 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1970	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2010	Work Type:	Surface Treatment - Seal Coat	Code:	ST-SC	Is Major M&R:	False		
Work Date:	5/1/2018	Work Type:	Complete Reconstruction - AC	Code:	CR-AC	Is Major M&R:	True		
Last Insp. Date:	11/30/2020	TotalSamples:	6	Surveyed:	2				
Conditions:	PCI:	93							
Inspection Comments:									
Sample Number:	214	Type:	R	Area:	4212.00 SqFt	PCI:	90		
Sample Comments:									
48	L & T CR	L	40.00 Ft						
57	WEATHERING	L	2106.00 SqFt						
Sample Number:	218	Type:	R	Area:	6256.00 SqFt	PCI:	95		
Sample Comments:									
57	WEATHERING	L	3128.00 SqFt						

Network:	PMP		Name:	POMPANO BEACH AIRPARK								
Branch:	TW M		Name:	TAXIWAY M		Use:	TAXIWAY		Area:	219,746 SqFt		
Section:	1325		of	8	From:	-		To:	-		Last Const.:	1/1/2012
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank:		P
Area:	8,073 SqFt		Length:	140 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1970		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	7/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2012		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	11/30/2020		TotalSamples:	2		Surveyed:	1					
Conditions:	PCI: 90											
Inspection Comments:												
Sample Number:	212		Type:	R		Area:	4500.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	33.00 Ft								
57	WEATHERING		L	4500.00 SqFt								

Network:	PMP			Name:	POMPANO BEACH AIRPARK							
Branch:	TW M		Name:	TAXIWAY M		Use:	TAXIWAY	Area:	219,746 SqFt			
Section:	1330		of	8	From:	-		To:	-		Last Const.:	1/1/2001
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	12,988 SqFt		Length:	245 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1970		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2001		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	1/1/2010		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	11/30/2020		TotalSamples:	3		Surveyed:	1					
Conditions:	PCI: 64											
Inspection Comments:												
Sample Number:	221		Type:	R		Area:	5000.00 SqFt		PCI:	64		
Sample Comments:												
48	L & T CR		L	506.00 Ft								
50	PATCHING		L	300.00 SqFt								
52	RAVELING		L	4700.00 SqFt								



Network:	PMP		Name:	POMPANO BEACH AIRPARK										
Branch:	TW N		Name:	TAXIWAY N		Use:	TAXIWAY	Area:	33,887 SqFt					
Section:	1405		of	1		From:	-		To:	-		Last Const.:	1/1/2004	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:			Rank:	P	
Area:	33,887 SqFt		Length:	420 Ft		Width:	50 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2004		Work Type: New Construction - Initial					Code:	NU-IN		Is Major M&R: True			
Work Date:	1/1/2010		Work Type: Surface Treatment - Seal Coat					Code:	ST-SC		Is Major M&R: False			
Last Insp. Date:	11/30/2020		TotalSamples:	6		Surveyed:		1						
Conditions:	PCI: 79													
Inspection Comments:														
Sample Number:	203		Type:	R		Area:	5000.00 SqFt		PCI:	79				
Sample Comments:														
48	L & T CR		L	161.00 Ft										
52	RAVELING		L	250.00 SqFt										
57	WEATHERING		L	4750.00 SqFt										



FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE

