FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE 2022

Statewide Airfield Pavement Management Program



Airport Pavement Evaluation Report

EVB - New Smyrna Beach Municipal Airport | District 5



Florida Department of Transportation

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report

Prepared by:

FDOT Aviation Office 605 Suwannee Street Tallahassee, Florida 32399-0450

Website: FDOT Aviation Office


Interactive Web Application: FDOT SAPMP Interactive Web Application



TABLE OF CONTENTS

| EXECUTIVE SUMMARY | 1 |
|--|----|
| Program Background | 1 |
| Current Pavement Conditions | 3 |
| Forecasted Pavement Conditions | 5 |
| Major Rehabilitation Planning 2023-2032 | 7 |
| CHAPTER 1 – INTRODUCTION | 11 |
| 1.1 Background | 11 |
| 1.2 Stakeholders | |
| 1.3 General Scope of Work | |
| 1.4 FDOT SAPMP Objectives | 14 |
| CHAPTER 2 – METHODOLOGY | 17 |
| 2.1 Airfield Pavement Database | 17 |
| 2.2 Airfield Pavement Record Keeping (Historical Records Research) | 18 |
| 2.3 Airfield Pavement Structure | |
| 2.3.1 Asphalt Concrete | 19 |
| 2.3.2 Portland Cement Concrete | |
| 2.3.3 Composite Structure – Whitetopping Pavement | 19 |
| 2.4 Airfield Pavement Traffic | |
| 2.5 Pavement Management Program Network Definition Terminology | 20 |
| 2.5.1 Pavement Network Identification | 20 |
| 2.5.2 Pavement Branch Identification | 20 |
| 2.5.3 Pavement Section Identification | 21 |
| 2.5.4 Pavement Sample Unit Identification | 21 |
| 2.5.5 Terminology Summary | 21 |
| 2.6 Airfield PCI Survey Methodology | 21 |
| 2.6.1 Pavement Distress Types | 22 |
| 2.6.2 PCI Survey Procedures | 23 |
| 2.7 Airfield PASER Survey Methodology | |
| 2.7.1 PASER Rating for Airfield Rigid Pavements | 24 |
| CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY | 27 |
| 3.1 Airfield Pavement Network Information | 27 |
| 3.1.1 Previous and/or Anticipated Airfield Pavement Construction | 27 |
| 3.1.2 Estimated Pavement Age | 30 |
| 3.1.3 Functional Use | |
| 3.1.4 Pavement Surface Type | |
| 3.1.5 Pavement System Inventory Details | |
| CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS | 37 |
| 4.1 Airfield Pavement Condition Index | 37 |
| 4.1.1 Network-Level Analysis | 37 |
| 4.1.2 Branch-Level Analysis | 37 |

| 4.1.3 Section-Level Analysis | 40 |
|---|----------------|
| 4.2 Summary of Pavement Condition Evaluation Results | |
| 4.2.1 Network-Level Observations | |
| 4.2.2 Branch-Level Observations | 45 |
| CHAPTER 5 – SAPMP CUSTOMIZATION | 54 |
| 5.1 Network-Level Customization | |
| 5.2 Pavement Condition Forecasts | |
| 5.2.1 Forecasting PCI Considerations | |
| 5.2.2 Performance Models | |
| 5.2.3 Branch-Level Pavement Condition Forecast | |
| 5.2.4 Section-Level Pavement Condition Forecast | |
| 5.3 Critical PCI Value | |
| 5.4 Localized Maintenance and Repair | |
| 5.4.1 Localized Maintenance and Repair Approach | |
| 5.4.2 Localized Work Types | |
| 5.4.3 Localized Maintenance Planning-Level Unit Costs | |
| 5.4.4 Localized Maintenance and Repair Policy | |
| 5.5 Major Rehabilitation | |
| 5.5.1 Major Rehabilitation Pavement Section Development | |
| 5.5.2 Major Rehabilitation Planning-Level Unit Costs | 09 |
| CHAPTER 6 - M&R PLANNING AND BUDGET SCENARIO ANALYSIS | |
| 6.1 Localized Maintenance and Repair Analysis and Recommendations | |
| 6.2 Major Rehabilitation Needs | |
| 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs | |
| 6.2.2 Major Rehabilitation Needs – Whitetopping Pavements | 78 |
| CHAPTER 7 – CONCLUSION | 80 |
| 7.1 Recommendations | |
| 7.1.1 Continued PCI Surveys | |
| 7.1.2 Localized Maintenance and Repair | |
| 7.1.3 Major Rehabilitat <mark>io</mark> n | |
| 7.1.4 Pavement Management System | |
| 7.2 Supporting Documents | 81 |
| Airfield Pavement Network Definition Exhibit | |
| Airfield Pavement System Inventory Exhibit | |
| Airfield Pavement Estimated Age Exhibit | |
| Airfield Pavement Condition Index Exhibit | |
| | |
| Airfield PASER Surface Rating Exhibit | 81 |
| Airfield PASER Surface Rating Exhibit | 81 81 |
| Airfield PASER Surface Rating Exhibit | 81 81 82 |
| Airfield PASER Surface Rating Exhibit | 81 81 82 |
| Airfield PASER Surface Rating Exhibit | 818282 |



LIST OF TABLES

| Table E.1 (a): Pavement Condition Index Summary (Current PCI Survey) - Section Level | 3 |
|---|----|
| Table E.1 (b): PASER Surface Rating - Section Level - Whitetopping Pavements | 5 |
| Table E.2: Forecasted PCI Values 2023-2032 – Section-Level | |
| Table E.3: Major Rehabilitation Planning 2023-2032 | 7 |
| Table 1.2: FDOT SAPMP Stakeholders | 13 |
| Table 2.5.5: SAPMP Terminology | 21 |
| Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete | 22 |
| Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete | 23 |
| Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete | 23 |
| Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete | 24 |
| Table 2.7.1: PASER Rating for Airfield Rigid Pavement | 25 |
| Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction | 27 |
| Table 3.1.5: Pavement System Inventory Details | 33 |
| Table 4.1.2: Current Condition Summary – Branch-Level | 40 |
| Table 4.1.3 (a): Latest Pavement Condition Index Summary – Section-Level | 41 |
| Table 4.1.3 (b): Latest PASER Surface Rating - Section Level - Whitetopping Pavements | 42 |
| Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level | 56 |
| Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects | 59 |
| Table 5.3 (b): Critical PCI Values by Branch Use | 59 |
| Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete | 64 |
| Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs - Portland Cement Concrete | 64 |
| Table 5.4.4: AC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy | 65 |
| Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy | 66 |
| Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation | 68 |
| Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type | 69 |
| Table 6.1 (a): Year 1 Summary of Localized Maintenance | |
| Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary | 72 |
| Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary | 72 |
| Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs | 75 |
| Table 6.2.2: Section-Level Major Rehabilitation Needs – Whitetopping Pavements | 78 |

LIST OF FIGURES

| Figure E.1 (a): PCI Rating | 1 |
|--|----|
| Figure E.1 (b): PASER Rating | 2 |
| Figure E.2: Current Condition Summary – Branch-Level | 3 |
| Figure E.3: 10-Year Major Rehabilitation Needs by Program Year | 9 |
| Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts | 12 |
| Figure 1.4: Pavement Life and the Effect of Treatments | 15 |
| Figure 2: FDOT SAPMP General Process | 17 |
| Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit | 28 |
| Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit | |
| Figure 3.1.2 (a): Age of Pavements at PCI Survey | 30 |
| Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit | 31 |
| Figure 3.1.3: Airfield Pavement Branch Use by Area (SF) | 32 |
| Figure 3.1.4: Airfield Pavement Surface Type by Area (SF) | 33 |
| Figure 4.1.1: Current Condition – Overall Network | |
| Figure 4.1.2 (a): Current Condition Summary – Branch-Level | 37 |
| Figure 4.1.2 (b): Current Condition – Runway | 38 |
| Figure 4.1.2 (c): Current Condition – Taxiway | 38 |
| Figure 4.1.2 (d): Current Condition – Taxilane | |
| Figure 4.1.2 (e): Current Condition – Apron | 39 |
| Figure 4.1.3 (a): Airfield Pavement Condition Index Exhibit | 43 |
| Figure 4.1.3 (b): Airfield PASER Surface Rating Exhibit - Whitetopping | 44 |
| Figure 5.2.3: Forecasted Branch-Level Pavement Performance | 55 |
| Figure 5.3 (a): Pavement Life and the Effect of Treatments | 58 |
| Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, PCI < Critical PCI | 60 |
| Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, PCI ≥ Critical PCI | |
| Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year | 76 |
| Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit | 77 |



Executive Summary

Executive Summary

Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. New Smyrna Beach Municipal Airport's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section. This is graphically depicted in **Figure E.1 (a)**.

Figure E.1 (a): PCI Rating

| Color | Range | Condition Rating |
|-------|--------|---------------------|
| | 86-100 | Good |
| | 71-85 | Satisfactory |
| | 56-70 | Fair |
| | 41-55 | Poor |
| | 26-40 | Very Poor |
| | 11-25 | Serious |
| | 0-10 | Failed |



New Smyrna Beach Municipal Airport has a unique composite pavement section known as "whitetopping" within their airport pavement system inventory. Whitetopping is a pavement construction technique otherwise known as "Concrete Overlay" that does not adhere to the current FAA AC 150/5320-6 guidance for concrete overlays and therefore is not suitable to be evaluated using the PCI methodology. Based on the guidance stated in FAA AC 150/5320-17A "Airfield Pavement Surface Evaluation and Rating Manuals", the FDOT SAPMP has adopted the PASER Manual in Appendix B of the Advisory Circular for specific use on the whitetopping pavements.

PASER is a visual rating system that utilizes a 0 to 5 rating scale, with a value of 5 representing new pavement and a value of 1 representing a failed pavement. This is graphically depicted in **Figure E.1 (b)**.

Figure E.1 (b): PASER Rating

| Color | PASER Value | Surface Rating |
|-------|-------------|----------------|
| | 5 | Excellent |
| | 4 | Good |
| | 3 | Fair |
| | 2 | Poor |
| | 1 | Failed |



Current Pavement Conditions

In January 2022, approximately 2.5 million square feet of pavement was assessed as part of the airside pavement network PCI survey at New Smyrna Beach Municipal Airport (EVB). In general, airfield pavements at EVB are in Fair condition with an area-weighted PCI of 70. The area-weighted average PCI values of the runways, taxiways, taxilanes, and aprons are 68, 81, 75, and 49, respectively. **Figure E.2** and **Table E.1 (a)** summarize the current PCI values for EVB, while **Table E.1 (b)** summarizes the PASER surface ratings for the whitetopping pavements.




Figure E.2: Current Condition Summary - Branch-Level

Table E.1 (a): Pavement Condition Index Summary (Current PCI Survey) - Section Level

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|----------------------------|------------|-----------|-----------|------------------|
| EVB | RW 2-20 | Runway | 6405 | 78,400 | 33 | Very Poor |
| EVB | RW 2-20 | Runway | 6425 | 254,789 | 34 | Very Poor |
| EVB | RW 2-20 | Runway | 6427 | 11,862 | 89 | Good |
| EVB | RW 2-20 | Runway | 6430 | 5,000 | 38 | Very Poor |
| EVB | RW 2-20 | Runway | 6435 | 12,472 | 83 | Satisfactory |
| EVB | RW 2-20 | RW 2-20 Runway 6450 25,000 | | 34 | Very Poor | |
| EVB | RW 7-25 | Runway | 6202 | 18,750 | 76 | Satisfactory |
| EVB | RW 7-25 | Runway | 6205 | 324,750 | 89 | Good |
| EVB | RW 7-25 | Runway | 6210 | 11,378 | 84 | Satisfactory |
| EVB | RW 7-25 | Runway | 6215 | 7,125 | 91 | Good |
| EVB | RW 7-25 | Runway | 6220 | 13,125 | 88 | Good |
| EVB | RW 11-29 | Runway | 6105 | 323,925 | 81 | Satisfactory |
| EVB | TW A | Taxiway | 102 | 22,287 | 85 | Satisfactory |
| EVB | TW A | Taxiway | 105 | 93,280 | 51 | Poor |
| EVB | TW A | Taxiway | 110 | 16,319 | 82 | Satisfactory |
| EVB | TW A | Taxiway | 115 | 5,905 | 86 | Good |



Airport Pavement Evaluation Report Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|------------|------------|-----------|-----|------------------|
| EVB | TW A | Taxiway | 125 | 4,303 | 52 | Poor |
| EVB | TW B | Taxiway | 210 | 67,896 | 73 | Satisfactory |
| EVB | TW B | Taxiway | 215 | 105,867 | 64 | Fair |
| EVB | TW C | Taxiway | 310 | 13,657 | 33 | Very Poor |
| EVB | TW C | Taxiway | 312 | 12,746 | 100 | Good |
| EVB | TW C | Taxiway | 314 | 57,036 | 100 | Good |
| EVB | TW C | Taxiway | 315 | 24,500 | 100 | Good |
| EVB | TW C | Taxiway | 325 | 5,247 | 59 | Fair |
| EVB | TW C | Taxiway | 330 | 44,997 | 100 | Good |
| EVB | TW C | Taxiway | 345 | 86,977 | 86 | Good |
| EVB | TW D | Taxiway | 405 | 50,628 | 68 | Fair |
| EVB | TW D | Taxiway | 415 | 7,000 | 23 | Serious |
| EVB | TW D | Taxiway | 425 | 27,118 | 89 | Good |
| EVB | TW D | Taxiway | 427 | 40,335 | 90 | Good |
| EVB | TW D | Taxiway | 430 | 84,969 | 88 | Good |
| EVB | TW E | Taxiway | 505 | 17,197 | 91 | Good |
| EVB | TW E | Taxiway | 510 | 24,594 | 90 | Good |
| EVB | TW E | Taxiway | 515 | 52,494 | 84 | Satisfactory |
| EVB | TW E | Taxiway | 520 | 27,412 | 91 | Good |
| EVB | TW E | Taxiway | 530 | 76,505 | 94 | Good |
| EVB | TW F | Taxiway | 610 | 28,075 | 100 | Good |
| EVB | TL T-HANG | Taxilane | 4320 | 31,261 | 64 | Fair |
| EVB | TL T-HANG | Taxilane | 4340 | 8,491 | 85 | Satisfactory |
| EVB | TL T-HANG | Taxilane | 4360 | 11,098 | 100 | Good |
| EVB | AP | Apron | 4102 | 20,539 | 4 | Failed |
| EVB | AP | Apron | 4103 | 9,336 | 100 | Good |
| EVB | AP | Apron | 4104 | 3,872 | 43 | Poor |
| EVB | AP | Apron | 4105 | 6,440 | 9 | Failed |
| EVB | AP | Apron | 4106 | 3,540 | 100 | Good |
| EVB | AP | Apron | 4107 | 12,117 | 100 | Good |
| EVB | AP | Apron | 4108 | 8,757 | 100 | Good |
| EVB | AP | Apron | 4110 | 1,950 | 7 | Failed |
| EVB | AP | Apron | 4115 | 8,775 | 1 | Failed |
| EVB | AP | Apron | 4124 | 6,450 | 73 | Satisfactory |
| EVB | AP | Apron | 4127 | 1,560 | 87 | Good |
| EVB | AP | Apron | 4128 | 6,565 | 100 | Good |
| EVB | AP | Apron | 4129 | 2,070 | 100 | Good |
| EVB | AP | Apron | 4130 | 23,150 | 47 | Poor |
| EVB | AP | Apron | 4132 | 17,074 | 23 | Serious |
| EVB | AP | Apron | 4135 | 4,290 | 33 | Very Poor |
| EVB | AP | Apron | 4140 | 37,036 | 35 | Very Poor |
| EVB | AP | Apron | 4145 | 17,888 | 65 | Fair |
| EVB | AP | Apron | 4160 | 10,001 | 41 | Poor |
| EVB | AP | Apron | 4165 | 9,517 | 10 | Failed |
| EVB | AP | Apron | 4190 | 38,656 90 | | Good |
| EVB | AP RU | Apron | 5105 | 46,282 | 32 | Very Poor |



| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating | |
|------------|-----------|------------|------------|-----------|-----|------------------|--|
| EVB | AP S | Apron | 4215 | 56,450 | 9 | Failed | |
| EVB | AP S | Apron | 4225 | 44,991 | 100 | Good | |
| EVB | AP SE | Apron | 4220 | 8,835 | 1 | Failed | |

Table E.1 (b): PASER Surface Rating - Section Level - Whitetopping Pavements

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PASER Value | Surface Rating |
|------------|-----------|------------|------------|-------------|----------------|----------------|
| EVB | TW C | Taxiway | 305 | 48,858 | 4 | Good |
| EVB | AP | Apron | 4120 | 14,180 | 2 | Poor |
| EVB | AP | Apron | 4121 | 12,650 | 2 | Poor |
| EVB | AP | Apron | 4125 | 17,693 | 3 | Fair |
| EVB | AP | Apron | 4126 | 12,548 | 3 | Fair |
| EVB | AP | Apron | 4150 | 4150 45,150 | | Fair |
| EVB | AP | Apron | 4154 | 7,400 | 4 | Good |
| EVB | AP | Apron | 4155 | 3,500 | 3 | Fair |

Forecasted Pavement Conditions

Table E.2 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

Table E.2: Forecasted PCI Values 2023-2032 - Section-Level

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|---------------|--------------|---------------|----------------|------|------|------|------|------|------|------|------|------|------|
| EVB | RW 2-20 | 6405 | 33 | 32 | 31 | 30 | 29 | 27 | 26 | 25 | 24 | 23 | 22 |
| EVB | RW 2-20 | 6425 | 34 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 25 | 24 | 23 |
| EVB | RW 2-20 | 6427 | 89 | 87 | 85 | 83 | 81 | 80 | 78 | 76 | 75 | 73 | 71 |
| EVB | RW 2-20 | 6430 | 38 | 38 | 37 | 37 | 36 | 36 | 35 | 35 | 34 | 33 | 32 |
| EVB | RW 2-20 | 6435 | 83 | 80 | 78 | 76 | 74 | 72 | 71 | 69 | 67 | 65 | 63 |
| EVB | RW 2-20 | 6450 | 34 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 25 | 24 | 23 |
| EVB | RW 7-25 | 6202 | 76 | 73 | 71 | 69 | 67 | 65 | 64 | 62 | 60 | 58 | 56 |
| EVB | RW 7-25 | 6205 | 89 | 86 | 84 | 82 | 80 | 78 | 77 | 75 | 73 | 71 | 69 |
| EVB | RW 7-25 | 6210 | 84 | 81 | 79 | 77 | 75 | 73 | 72 | 70 | 68 | 66 | 64 |
| EVB | RW 7-25 | 6215 | 91 | 88 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 73 | 71 |
| EVB | RW 7-25 | 6220 | 88 | 85 | 83 | 81 | 79 | 77 | 76 | 74 | 72 | 70 | 68 |
| EVB | RW 11-29 | 6105 | 81 | 78 | 76 | 74 | 72 | 70 | 69 | 67 | 65 | 63 | 61 |
| EVB | TW A | 102 | 85 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 |



Airport Pavement Evaluation Report Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|---------------|--------------|---------------|----------------|------|------|------|------|------|------|------|------|------|------|
| EVB | TW A | 105 | 51 | 50 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 47 | 46 |
| EVB | TW A | 110 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 71 | 70 | 68 | 67 |
| EVB | TW A | 115 | 86 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 |
| EVB | TW A | 125 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| EVB | TW B | 210 | 73 | 71 | 70 | 69 | 68 | 66 | 65 | 64 | 64 | 63 | 62 |
| EVB | TW B | 215 | 64 | 63 | 62 | 61 | 60 | 60 | 59 | 58 | 58 | 57 | 56 |
| EVB | TW C | 310 | 33 | 31 | 30 | 28 | 27 | 25 | 24 | 22 | 20 | 19 | 17 |
| EVB | TW C | 312 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 314 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 315 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 325 | 59 | 58 | 57 | 57 | 56 | 56 | 55 | 55 | 54 | 54 | 53 |
| EVB | TW C | 330 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 345 | 86 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 |
| EVB | TW D | 405 | 68 | 66 | 65 | 64 | 64 | 63 | 62 | 61 | 60 | 60 | 59 |
| EVB | TW D | 415 | 23 | 21 | 19 | 17 | 15 | 13 | 11 | 9 | 8 | 6 | 4 |
| EVB | TW D | 425 | 89 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 |
| EVB | TW D | 427 | 90 | 87 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 72 |
| EVB | TW D | 430 | 88 | 85 | 83 | 81 | 80 | 78 | 76 | 75 | 74 | 72 | 71 |
| EVB | TW E | 505 | 91 | 88 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 |
| EVB | TW E | 510 | 90 | 87 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 72 |
| EVB | TWE | 515 | 84 | 81 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 69 |
| EVB | TW E | 520 | 91 | 88 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 |
| EVB | TW E | 530 | 94 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 | 76 | 75 |
| EVB | TW F | 610 | 100 | 94 | 92 | 89 | 87 | 85 | 84 | 82 | 80 | 78 | 77 |
| EVB | TL T-HANG | 4320 | 64 | 63 | 62 | 61 | 60 | 60 | 59 | 58 | 58 | 57 | 56 |
| EVB | TL T-HANG | 4340 | 85 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 |
| EVB | TL T-HANG | 4360 | 100 | 94 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| EVB | AP | 4102 | 4 | 3 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | 4103 | 100 | 97 | 94 | 92 | 90 | 88 | 85 | 83 | 81 | 79 | 78 |
| EVB | AP | 4104 | 43 | 42 | 42 | 41 | 41 | 41 | 40 | 40 | 39 | 39 | 39 |
| EVB | AP | 4105 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 |
| EVB | AP | 4106 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4107 | 100 | 94 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 77 | 75 |
| EVB | AP | 4108 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4110 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 | 0 | 0 |
| EVB | AP | 4115 | 1 70 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | 4124 | 73 | 71 | 70 | 68 | 67 | 66 | 64 | 63 | 62 | 60 | 59 |
| EVB | AP | 4127 | 87 | 86 | 85 | 84 | 83 | 82 | 81 | 80 | 79 | 78 | 77 |
| EVB | AP | 4128 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4129 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4130 | 47 | 46 | 45 | 44 | 43 | 42 | 41 | 40 | 39 | 38 | 37 |
| EVB | AP | 4132 | 23 | 22 | 21 | 20 | 19 | 18 | 17 | 16 | 15 | 14 | 13 |
| EVB | AP | 4135 | 33 | 32 | 32 | 31 | 30 | 30 | 29 | 28 | 28 | 27 | 26 |
| EVB | AP | 4140 | 35 | 34 | 34 | 33 | 33 | 32 | 32 | 31 | 31 | 30 | 29 |
| EVB | AP | 4145 | 65 | 63 | 62 | 61 | 59 | 58 | 57 | 56 | 55 | 54 | 53 |
| EVB | AP | 4160 | 41 | 40 | 40 | 40 | 39 | 39 | 38 | 38 | 38 | 37 | 37 |



| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|---------------|--------------|---------------|----------------|------|------|------|------|------|------|------|------|------|------|
| EVB | AP | 4165 | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| EVB | AP | 4190 | 90 | 89 | 88 | 87 | 86 | 85 | 84 | 83 | 82 | 81 | 80 |
| EVB | AP RU | 5105 | 32 | 31 | 31 | 30 | 29 | 29 | 28 | 27 | 26 | 26 | 25 |
| EVB | AP S | 4215 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 |
| EVB | AP S | 4225 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP SE | 4220 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$28.00M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$15.67M and localized maintenance needs for Year 1 are \$1.17M.

Table E.3: Major Rehabilitation Planning 2023-2032

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | nning Cost Estimate |
|-----------------|---------------|--------------|---------------|---------|--------------|---------------|------------------------|------------------------|
| 2023 | EVB | RW 2-20 | 6405 | AC | 78,400 | 32 | AC Reconstruction | \$ 1,255,000 |
| 2023 | EVB | RW 2-20 | 6425 | AC | 254,789 | 33 | AC Reconstruction | \$ 4,077,000 |
| 2023 | EVB | RW 2-20 | 6430 | AC | 5,000 | 38 | AC Reconstruction | \$ 80,000 |
| 2023 | EVB | RW 2-20 | 6450 | AC | 25,000 | 33 | AC Reconstruction | \$ 400,000 |
| 2023 | EVB | TW A | 105 | AC | 93,280 | 50 | AC Reconstruction | \$ 1,493,000 |
| 2023 | EVB | TW A | 125 | AC | 4,303 | 51 | AC Reconstruction | \$ 69,000 |
| 2023 | EVB | TW B | 215 | AC | 105,867 | 63 | AC Rehabilitation | \$ 953,000 |
| 2023 | EVB | TW C | 310 | AC | 13,657 | 31 | AC Reconstruction | \$ 219,000 |
| 2023 | EVB | TW C | 325 | AC | 5,247 | 58 | AC Rehabilitation | \$ 48,000 |
| 2023 | EVB | TW D | 405 | AC | 50,628 | 66 | AC Rehabilitation | \$ 456,000 |




Airport Pavement Evaluation Report Statewide Airfield Pavement Management Program

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost Estimate | |
|-----------------|---------------|--------------|---------------|---------|--------------|---------------|------------------------|---------------------------|-----------|
| 2023 | EVB | TW D | 415 | AC | 7,000 | 21 | AC Reconstruction | \$ | 112,000 |
| 2023 | EVB | TL T-HANG | 4320 | AC | 31,261 | 63 | AC Rehabilitation | \$ | 282,000 |
| 2023 | EVB | AP | 4102 | PCC | 20,539 | 3 | PCC Reconstruction | \$ | 596,000 |
| 2023 | EVB | AP | 4104 | AC | 3,872 | 42 | AC Reconstruction | \$ | 62,000 |
| 2023 | EVB | AP | 4105 | PCC | 6,440 | 8 | PCC Reconstruction | \$ | 187,000 |
| 2023 | EVB | AP | 4110 | PCC | 1,950 | 6 | PCC Reconstruction | \$ | 57,000 |
| 2023 | EVB | AP | 4115 | PCC | 8,775 | 0 | PCC Reconstruction | \$ | 255,000 |
| 2023 | EVB | AP | 4130 | PCC | 23,150 | 46 | PCC Reconstruction | \$ | 672,000 |
| 2023 | EVB | AP | 4132 | PCC | 17,074 | 22 | PCC Reconstruction | \$ | 496,000 |
| 2023 | EVB | AP | 4135 | AC | 4,290 | 32 | AC Reconstruction | \$ | 69,000 |
| 2023 | EVB | AP | 4140 | AC | 37,036 | 34 | AC Reconstruction | \$ | 593,000 |
| 2023 | EVB | AP | 4145 | AC | 17,888 | 63 | AC Rehabilitation | \$ | 161,000 |
| 2023 | EVB | AP | 4160 | AC | 10,001 | 40 | AC Reconstruction | \$ | 161,000 |
| 2023 | EVB | AP | 4165 | PCC | 9,517 | 9 | PCC Reconstruction | \$ | 276,000 |
| 2023 | EVB | AP RU | 5105 | AC | 46,282 | 31 | AC Reconstruction | \$ | 741,000 |
| 2023 | EVB | AP S | 4215 | PCC | 56,450 | 8 | PCC Reconstruction | \$ | 1,638,000 |
| 2023 | EVB | AP SE | 4220 | PCC | 8,835 | 0 | PCC Reconstruction | \$ | 257,000 |
| 2024 | EVB | TW B | 210 | AC | 67,896 | 70 | AC Rehabilitation | \$ | 642,000 |
| 2025 | EVB | RW 7-25 | 6202 | AAC | 18,750 | 69 | AC Rehabilitation | \$ | 187,000 |
| 2028 | EVB | RW 11-29 | 6105 | AAC | 323,925 | 69 | AC Rehabilitation | \$ | 3,721,000 |
| 2029 | EVB | RW 2-20 | 6435 | AAC | 12,472 | 69 | AC Rehabilitation | \$ | 151,000 |
| 2029 | EVB | RW 7-25 | 6210 | AAC | 11,378 | 70 | AC Rehabilitation | \$ | 138,000 |
| 2030 | EVB | TW A | 110 | AC | 16,319 | 70 | AC Rehabilitation | \$ | 207,000 |
| 2031 | EVB | RW 7-25 | 6220 | AAC | 13,125 | 70 | AC Rehabilitation | \$ | 175,000 |
| 2031 | EVB | TW E | 515 | AC | 52,494 | 70 | AC Rehabilitation | \$ | 699,000 |
| 2032 | EVB | RW 7-25 | 6205 | AAC | 324,750 | 69 | AC Rehabilitation | \$ | 4,535,000 |
| 2032 | EVB | TW A | 102 | AC | 22,287 | 69 | AC Rehabilitation | \$ | 312,000 |
| 2032 | EVB | TW A | 115 | AC | 5,905 | 70 | AC Rehabilitation | \$ | 83,000 |
| 2032 | EVB | TW C | 345 | AC | 86,977 | 70 | AC Rehabilitation | \$ | 1,215,000 |
| 2032 | EVB | TL T-HANG | 4340 | AC | 8,491 | 69 | AC Rehabilitation | \$ | 119,000 |
| 2032 | EVB | AP | 4124 | PCC | 6,450 | 59 | PCC Rehabilitation | \$ | 151,000 |


^{*}All planning cost values have been rounded up to the nearest thousand dollars.



Figure E.3: 10-Year Major Rehabilitation Needs by Program Year







Chapter 1: Introduction

Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida's economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida's most prominent industry.

1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management Program (PMP)". The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".


In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are



under consideration for projects. A network-level evaluation can support the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts





1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

Table 1.2: FDOT SAPMP Stakeholders

| Role | Description | | | |
|---|---|--|--|--|
| FAA Orlando Airports District Office (Orlando ADO) | Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation). | | | |
| Florida Department of Transportation (FDOT) | Key Stakeholder: the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airpor System. | | | |
| FDOT District Offices | The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. | | | |
| Participating Public-Use and Publicly-Owned Airports | The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment. | | | |
| Aviation Office Program Manager (AO-PM) | FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update. | | | |

1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- Research and evaluation of existing record documentation;
- Establishment of a pavement system inventory;
- Development of a pavement network definition map and supplemental GIS model;
- Functional pavement evaluations via the PCI assessment method;
- Customization of PAVER[™] software including prioritization, policies, and performance models;
- Analysis of condition data; and
- Maintenance, repair, and rehabilitation planning.



1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.

A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:

- Assist airports in meeting the requirements of Public Law 103-305;
- Assist airports in complying with FAA Grant Assurances 11 and 19;
- Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.



\$1.00 for Preservation Here Good 86-100 Critical PCI Satisfactory 71-85 Gain in Pavement Life from -Fair **Preservation Treatments** 56-70 Poor 41-55 **Very Poor** 26-40 **Serious** 11-25 Will Cost >>\$5.00 for Reconstruction Here **Failed**

Figure 1.4: Pavement Life and the Effect of Treatments

Time

FAA Eligibilty Thresholds: -70: Routine Maintenance 55-70: Rehabilitation Eligible <55: Reconstruction Eligible

*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements

0-10



Chapter 2: Methodology

Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.




Figure 2: FDOT SAPMP General Process

2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- Create a manageable inventory system;
- Analyze the current condition of pavements in accordance with ASTM D5340-20;
- Develop pavement performance models to forecast conditions; and
- Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVERTM inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVERTM database and typically consist of pavement inventory



characteristics, pavement structure, work history, historic condition records, and analytical customization.

2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- Location and limits of work;
- Types and severities of repaired distresses;
- >> Work type and cost; and
- Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- Date of last construction/rehabilitation
- Work type performed
- Comments for documenting pavement cross-section
- Pavement surface type
- Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.



2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

<u>Asphalt Concrete Overlaid on Portland Cement Concrete (APC)</u>

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

Conventional Whitetopping (WT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.



Thin Whitetopping (TWT)

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

Ultra-Thin Whitetopping (UWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

2.4 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of EVB's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.5 Pavement Management Program Network Definition Terminology

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

2.5.1 Pavement Network Identification

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

2.5.2 Pavement Branch Identification

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.



2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs (±8 slabs) for PCC pavement and 5,000 contiguous square feet (±2,000 SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

| SAPMP Terminology | Common Definition | Airport Example | | |
|-------------------|---|---|--|--|
| Network | Totality of pavement assets maintained by the Airport. | "Tallahassee International Airport – Airfield Pavements" | | |
| Branch Name | Commonly defined asset name as established by Airport and by use. | "Runway 18-36" | | |
| | Codified shorthand name for commonly | "RW 18-36" | | |
| Branch ID | defined asset established for database identification. | RW, Branch Use, "Runway" "Runway 18-36", Runway Facility | | |
| Section ID | Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition. | "6105" | | |
| Sample Unit | A numeric identification of an area of pavement (5,000 ± 2,000 SF of AC or 20 ± 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20. | "300" | | |

Table 2.5.5: SAPMP Terminology

2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.



Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

Table 2.6.1 (a): Pavement Distress Types - Asphalt Concrete

| Distress Mechanism | Distress Type |
|-----------------------|--|
| Load | Alligator Cracking Rutting |
| Climate/Durability | Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering |
| Construction/Material | Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling |
| Other | Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching |



Table 2.6.1 (b): Pavement Distress Types - Portland Cement Concrete

| Distress Mechanism | Distress Type |
|-----------------------|---|
| Load | Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks |
| Climate/Durability | Blowup Durability "D" Cracking Joint Seal Damage Popouts |
| Construction/Material | Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking |
| Other | Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching |

2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a)** and **(b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.

Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete

| Number of Total Sample Units in Section | Runway Sampling Rate | Taxiways, Aprons, and Others Sampling Rate |
|---|----------------------|--|
| 1 - 4 | 1 | 1 |
| 5 - 10 | 2 | 1 |
| 11 - 15 | 3 | 2 |
| 16 - 30 | 5 | 3 |
| 31 - 40 | 7 | 4 |
| 41 - 50 | 8 | 5 |
| 51 or more | 20% but ≤ 20 | 10% but ≤ 10 |

10% but ≤ 10

| Number of Total Sample Units in Section | Runway Sampling Rate | Taxiways, Aprons, and Others Sampling Rate |
|---|----------------------|--|
| 1 - 3 | 1 | 1 |
| 4 - 6 | 2 | 1 |
| 7 - 10 | 3 | 2 |
| 11 - 15 | 4 | 2 |
| 16 - 20 | 5 | 3 |
| 21 - 30 | 7 | 3 |
| 31 - 40 | 8 | 4 |
| 41 - 50 | 10 | 5 |
| | | |

Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.

20% but ≤ 20

2.7 Airfield PASER Survey Methodology

51 or more

Of the 95 participating airports, there are three (3) airports, including EVB, that have a unique composite pavement section known as "whitetopping" within their airfield pavement system inventory that deviates from the current FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation." Whitetopping is a pavement construction technique otherwise known as "Concrete Overlay" that does not adhere to the current FAA AC 150/5320-6 guidance for concrete overlays based on material specification, documented concrete strength, concrete minimum thickness, joint type, joint sealant, joint layout, and load transfer. Therefore, it is recognized that the ASTM D5340-20 (current version) may not be suitable to utilize as means to evaluate condition for the whitetopping concrete overlays.

The FAA recommends the <u>PA</u>vement <u>S</u>urface <u>E</u>valuation and <u>R</u>ating (PASER) procedure to evaluate the surface condition of rigid concrete and flexible concrete pavement facilities when it is not possible to complete a more detailed PCI Survey as part of a more comprehensive pavement maintenance management program. PASER was developed for the FAA by the Engineering Professional Development, College of Engineering, University of Wisconsin-Madison. Based on the guidance stated in FAA AC 150/5320-17A "Airfield Pavement Surface Evaluation and Rating Manuals", the FDOT SAPMP has adopted the PASER Manual in Appendix B of the Advisory Circular for specific use on the whitetopping pavements.

2.7.1 PASER Rating for Airfield Rigid Pavements

For the FDOT SAPMP, the PASER system will be limited to concrete overlay pavement sections, identified as whitetopping. PASER is a visual rating system that utilizes a 0 to 5 rating scale, with a value of 5 representing new pavement (or recent major concrete rehabilitation, like-new




condition, typically less than 5 years old, and/or no maintenance required) and a value of 1 representing extensive full-depth joint repairs or slab replacements, extensive patching and one (1) complete overlay, and/or complete reconstruction needed. The PASER condition ratings are assigned by monitoring the type and amount of visual deterioration/distress within a defined feature (section). The PASER system interprets the visual observations into a condition rating. **Table 2.7.1. PASER Rating for Airfield Rigid Pavement** provides an organization of the PASER rating system for airfield pavements constructed with a rigid concrete surface layer.

Each rating in the PASER value has a corresponding surface rating written descriptor (Excellent, Good, Fair, Poor, Failed). The PASER surface rating is not based on the ASTM D5430-20. They should not be confused with the formal definitions of the PCI survey method.

Table 2.7.1: PASER Rating for Airfield Rigid Pavement

| PASER Value | Surface Rating | Visual Distress | General Conditions | Treatment Measures |
|----------------|-------------------|---|--|---|
| 5 | Excellent | None. | New pavement or recent major concrete rehabilitation. Likenew condition. Less than 5 years old. No maintenance required. | No maintenance required. |
| 4 | Good | Hairline or sealed cracks 1/8" wide or less. Map cracking. Pop-outs. | Concrete over 5 years old. Signs of wear. Minor spot repair of cracks or joint sealant. | Minor routine maintenance, crack or joint sealing. |
| 3 | Fair | Several slabs broken into two pieces by slab cracks. Corner cracking on several slabs, 1/4" wide with no spalling. Joint sealant mostly in good condition, less than 10% needing replacement. Several patches in fair to good condition. Map cracking or scaling on 10% or less of the surface area. Slight faulting, less than 1/4", in several locations. | First sign of significant slab cracking, corner cracking, scaling, or faulting. Several patches. Joint sealant repair required. Isolated repair of joint or patch. | More crack or joint sealing. Isolated joint repairs or slab patching. |
| 2 | Poor | Many slab cracks, some breaking the slab into three or more pieces. Cracks open 1/8" or cracks with spalling. D-cracks at several joints. Sealant failure over 10% of joints. Several patches in fair to poor condition with cracks in patch and uneven surface. Faulting 1/4" to 1/2" in several locations. Severe or extensive scaling. | Needs sealant replacement on more than 10% of cracks or joints. Partial depth or full-depth joint repairs or patch replacement. Repair faulted joints. Replace or overlay slabs with severe scaling. Bonded or unbonded concrete overlay. | Extensive crack or joint sealing. Repair severe joint deterioration. Partial and full-depth slab repairs. |
| 1 | Failed | Many wide cracks with failed sealant and grass. Extensive crack and joint spalling. Slabs extensively cracked or shattered. Many corner breaks with spalling. D-cracks with spalling. Patches in poor condition with spalling. Numerous faults over 1/2". | Extensive full-depth joint repairs or slab replacements. Extensive patching and complete overlay. Complete reconstruction. | Reconstruction. |





Chapter 3: Airfield Pavement System Inventory

Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.

Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction


| Construction Year | Location | Work Type / Pavement Section |
|-------------------|-----------|--|
| 2018 | TW E | Complete Reconstruction - AC 2" P-401, Rework Existing 8" Limerock Base |
| 2019 | AP | Complete Reconstruction - PCC |
| | AP, TW F | New Construction - AC |
| 2020 | AP | Complete Reconstruction - PCC |
| | AP, AP S | New Construction - PCC |
| 2021 | TL T-HANG | New Construction - AC |
| | TW C | New Construction - AC |
| 2022 | AP, TW C | Complete Reconstruction - AC 4" P-401, 6" P-211 |
| | TW C | Complete Reconstruction - AC Cold milling existing asphalt full depth 2", excavate 2" existing P-211, regrade existing P-211 |

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.


Figure 3.1.1 (a), the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.











3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.





Figure 3.1.2 (a): Age of Pavements at PCI Survey





3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed "functional use" or "branch use." For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.




Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)

3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC). EVB is one of three airports participating in the FDOT SAPMP that also have one (1) uncommon type of composite pavement, known as Whitetopping (WT), consisting of PCC overlaid on AC.

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at EVB.








Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)

3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

Table 3.1.5 displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

Surface **Estimate of Last Network ID Branch ID Branch Use Section ID** Area (SF) **Construction Date** Type **EVB** RW 2-20 Runway 6405 78,400 AC 1/1/1943 **EVB** RW 2-20 Runway 6425 254,789 AC 1/1/1943 **EVB** RW 2-20 11,862 1/1/2014 Runway 6427 AC RW 2-20 AC **EVB** Runway 6430 5,000 1/1/1977 RW 2-20 Runway 6435 12,472 AAC 1/1/2014 **EVB** RW 2-20 25,000 AC 1/1/1977 **EVB** Runway 6450 **EVB** RW 7-25 Runway 6202 18.750 AAC 1/1/2008 RW 7-25 324,750 AAC 1/1/2016 **EVB** Runway 6205

Table 3.1.5: Pavement System Inventory Details



Airport Pavement Evaluation Report Statewide Airfield Pavement Management Program


| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|-----------------|---------------------------------------|
| EVB | RW 7-25 | Runway | 6210 | 11,378 | AAC | 1/1/2008 |
| EVB | RW 7-25 | Runway | 6215 | 7,125 | AAC | 1/1/2016 |
| EVB | RW 7-25 | Runway | 6220 | 13,125 | AAC | 1/1/2016 |
| EVB | RW 11-29 | Runway | 6105 | 323,925 | AAC | 1/1/2014 |
| EVB | TW A | Taxiway | 102 | 22,287 | AC | 1/1/2011 |
| EVB | TW A | Taxiway | 105 | 93,280 | AC | 1/1/1977 |
| EVB | TW A | Taxiway | 110 | 16,319 | AC | 7/1/2011 |
| EVB | TW A | Taxiway | 115 | 5,905 | AC | 1/1/2014 |
| EVB | TW A | Taxiway | 125 | 4,303 | AC | 1/1/2002 |
| EVB | TW B | Taxiway | 210 | 67,896 | AC | 1/1/2002 |
| EVB | TW B | Taxiway | 215 | 105,867 | AC | 1/1/2002 |
| EVB | TW C | Taxiway | 305 | 48,858 | WT | 1/1/2002 |
| EVB | TW C | Taxiway | 310 | 13,657 | AC | 1/1/2002 |
| EVB | TW C | Taxiway | 312 | 12,746 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 314 | 57,036 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 315 | 24,500 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 325 | 5,247 | AC | 1/1/2002 |
| EVB | TW C | Taxiway | 330 | 44,997 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 345 | 86,977 | AC | 1/1/2012 |
| EVB | TW D | Taxiway | 405 | 50,628 | AC | 1/1/2002 |
| EVB | TW D | Taxiway | 415 | 7,000 | AC | 1/1/1943 |
| EVB | TW D | Taxiway | 425 | 27,118 | AC | 1/1/2014 |
| EVB | TW D | Taxiway | 427 | 40,335 | AC | 1/1/2014 |
| EVB | TW D | Taxiway | 430 | 84,969 | AAC | 1/1/2016 |
| EVB | TW E | Taxiway | 505 | 17,197 | AC | 1/1/2014 |
| EVB | TW E | Taxiway | 510 | 24,594 | AC | 1/1/2014 |
| EVB | TW E | Taxiway | 515 | 52,494 | AC | 7/1/2011 |
| EVB | TW E | Taxiway | 520 | 27,412 | AC | 1/1/2014 |
| EVB | TW E | Taxiway | 530 | 76,505 | AC | 1/1/2018 |
| EVB | TW F | Taxiway | 610 | 28,075 | AC | 12/1/2020 |
| EVB | TL T-HANG | Taxilane | 4320 | 31,261 | AC | 1/1/2002 |
| EVB | TL T-HANG | Taxilane | 4340 | 8,491 | AC | 1/1/2010 |
| EVB | TL T-HANG | Taxilane | 4360 | 11,098 | AC | 3/1/2021 |
| EVB | AP | Apron | 4102 | 20,539 | PCC | 1/1/1984 |
| EVB | AP | Apron | 4103 | 9,336 | AC | 4/1/2022 |
| EVB | AP | Apron | 4104 | 3,872 | AC | 1/1/1984 |
| EVB | AP | Apron | 4105 | 6,440 | PCC | 1/1/1965 |
| EVB | AP | Apron | 4106 | 3,540 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4107 | 12,117 | AC | 12/1/2020 |
| EVB | AP | Apron | 4108 | 8,757 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4110 | 1,950 | PCC | 1/1/1980 |
| EVB | AP | Apron | 4115 | 8,775 | PCC | 1/1/1975 |
| EVB | AP | Apron | 4120 | 14,180 | WT | 1/1/2002 |
| EVB | AP | Apron | 4121 | 12,650 | WT | 1/1/2002 |
| EVB | AP | Apron | 4124 | 6,450 | PCC | 1/1/2002 |
| EVB | AP | Apron | 4125 | 24,143 | WT | 1/1/2002 |



Airport Pavement Evaluation Report Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|-----------------|---------------------------------------|
| EVB | AP | Apron | 4126 | 12,548 | WT | 1/1/2002 |
| EVB | AP | Apron | 4127 | 1,560 | PCC | 1/1/2019 |
| EVB | AP | Apron | 4128 | 6,565 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4129 | 2,070 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4130 | 23,150 | PCC | 1/1/1997 |
| EVB | AP | Apron | 4132 | 17,074 | PCC | 1/1/1997 |
| EVB | AP | Apron | 4135 | 4,290 | AC | 1/1/1975 |
| EVB | AP | Apron | 4140 | 37,036 | AC | 1/1/1980 |
| EVB | AP | Apron | 4145 | 17,888 | AC | 1/1/1986 |
| EVB | AP | Apron | 4150 | 45,150 | WT | 1/1/2002 |
| EVB | AP | Apron | 4154 | 7,400 | WT | 1/1/2002 |
| EVB | AP | Apron | 4155 | 3,500 | WT | 1/1/2002 |
| EVB | AP | Apron | 4160 | 10,001 | AC | 1/1/1975 |
| EVB | AP | Apron | 4165 | 9,517 | PCC | 1/1/1991 |
| EVB | AP | Apron | 4190 | 38,656 | PCC | 1/1/2012 |
| EVB | AP RU | Apron | 5105 | 46,282 | AC | 1/1/1943 |
| EVB | AP S | Apron | 4215 | 56,450 | PCC | 1/1/1943 |
| EVB | AP S | Apron | 4225 | 44,991 | PCC | 12/1/2020 |
| EVB | AP SE | Apron | 4220 | 8,835 | PCC | 12/25/1999 |





Chapter 4: Airfield Pavement Condition Analysis

Chapter 4 – Airfield Pavement Condition Analysis

The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for designand/or project-level determination of pavement rehabilitation needs. It should be noted that the condition information summarized in this chapter, unless specifically identified, excludes whitetopping pavement, as whitetopping is evaluated based on the PASER surface rating methodology as detailed in **Section 2.7 Airfield PASER Survey Methodology**.

4.1 Airfield Pavement Condition Index

4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 63% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 8% of inspected pavements are in Fair condition and the remaining 29% of inspected pavements are in Poor or worse condition.

42% 21% 8% 5% 18% 1% 5%

Good Satisfactory Fair Poor Very Poor Serious Failed

Figure 4.1.1: Current Condition - Overall Network

4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(e)** summarize branch-level pavement conditions according to the most recent PCI assessment results.




Figure 4.1.2 (a): Current Condition Summary - Branch-Level








Figure 4.1.2 (c): Current Condition - Taxiway










Figure 4.1.2 (e): Current Condition - Apron






Table 4.1.2 details the branch-level condition for each airfield pavement branch.

Number of Branch Area Area-Weighted Branch ID **Condition Rating Branch Use** Sections Avg PCI (SF) RW 2-20 Runway 6 387,523 37 Very Poor RW 7-25 5 Good Runway 375,128 88 RW 11-29 Runway 1 323,925 81 Satisfactory TW A 5 61 Fair Taxiway 142,094 TW B **Taxiway** 2 173,763 68 Fair TW C 7 Good Taxiway 245,160 90 TW D Taxiway 5 210,050 82 Satisfactory TW E Taxiway 5 198,202 90 Good TW F Taxiway 1 28.075 100 Good TL T-HANG 3 75 Satisfactory Taxilane 50,850 ΑP Apron 21 249.583 53 Very Poor AP RU Apron 1 46,282 32 AP S 101,441 Apron 2 AP SE Apron 1 8,835 1 Failed

Table 4.1.2: Current Condition Summary - Branch-Level

4.1.3 Section-Level Analysis

Table 4.1.3 (a) provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3 (a)** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.

Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.

The results of the PASER surface rating for whitetopping pavements are presented separately in **Table 4.1.3 (b)** and **Figure 4.1.3 (b)**.



Table 4.1.3 (a): Latest Pavement Condition Index Summary - Section-Level


| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface | PCI | Condition Rating | PCI % Climate | PCI % Load | PCI % Other | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|------------|------------|-----------|---------|-----|------------------|---------------|------------|-------------|---------------------------|----------------------------------|
| EVB | RW 2-20 | Runway | 6405 | 78,400 | AC | 33 | Very Poor | 74 | 23 | 3 | 5 | 16 |
| EVB | RW 2-20 | Runway | 6425 | 254,789 | AC | 34 | Very Poor | 92 | 7 | 1 | 12 | 51 |
| EVB | RW 2-20 | Runway | 6427 | 11,862 | AC | 89 | Good | 100 | 0 | 0 | 12 | 3 |
| EVB | RW 2-20 | Runway | 6430 | 5,000 | AC | 38 | Very Poor | 100 | 0 | 0 | 1 | 1 |
| EVB | RW 2-20 | Runway | 6435 | 12,472 | AAC | 83 | Satisfactory | 100 | 0 | 0 | 1 | 2 |
| EVB | RW 2-20 | Runway | 6450 | 25,000 | AC | 34 | Very Poor | 100 | 0 | 0 | 2 | 5 |
| EVB | RW 7-25 | Runway | 6202 | 18,750 | AAC | 76 | Satisfactory | 100 | 0 | 0 | 2 | 5 |
| EVB | RW 7-25 | Runway | 6205 | 324,750 | AAC | 89 | Good | 94 | 0 | 6 | 18 | 86 |
| EVB | RW 7-25 | Runway | 6210 | 11,378 | AAC | 84 | Satisfactory | 100 | 0 | 0 | 1 | 3 |
| EVB | RW 7-25 | Runway | 6215 | 7,125 | AAC | 91 | Good | 100 | 0 | 0 | 1 | 2 |
| EVB | RW 7-25 | Runway | 6220 | 13,125 | AAC | 88 | Good | 100 | 0 | 0 | 1 | 3 |
| EVB | RW 11-29 | Runway | 6105 | 323,925 | AAC | 81 | Satisfactory | 96 | 0 | 4 | 18 | 86 |
| EVB | TW A | Taxiway | 102 | 22,287 | AC | 85 | Satisfactory | 100 | 0 | 0 | 1 | 5 |
| EVB | TW A | Taxiway | 105 | 93,280 | AC | 51 | Poor | 96 | 0 | 4 | 3 | 23 |
| EVB | TW A | Taxiway | 110 | 16,319 | AC | 82 | Satisfactory | 100 | 0 | 0 | 1 | 3 |
| EVB | TW A | Taxiway | 115 | 5,905 | AC | 86 | Good | 100 | 0 | 0 | 1 | 2 |
| EVB | TW A | Taxiway | 125 | 4,303 | AC | 52 | Poor | 97 | 0 | 3 | 1 | 1 |
| EVB | TW B | Taxiway | 210 | 67,896 | AC | 73 | Satisfactory | 100 | 0 | 0 | 3 | 18 |
| EVB | TW B | Taxiway | 215 | 105,867 | AC | 64 | Fair | 97 | 0 | 3 | 4 | 28 |
| EVB | TW C | Taxiway | 310 | 13,657 | AC | 33 | Very Poor | 87 | 0 | 13 | 1 | 3 |
| EVB | TW C | Taxiway | 312 | 12,746 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | TW C | Taxiway | 314 | 57,036 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | TW C | Taxiway | 315 | 24,500 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | TW C | Taxiway | 325 | 5,247 | AC | 59 | Fair | 70 | 0 | 30 | 1 | 1 |
| EVB | TW C | Taxiway | 330 | 44,997 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | TW C | Taxiway | 345 | 86,977 | AC | 86 | Good | 87 | 0 | 13 | 3 | 22 |
| EVB | TW D | Taxiway | 405 | 50,628 | AC | 68 | Fair | 100 | 0 | 0 | 3 | 11 |
| EVB | TW D | Taxiway | 415 | 7,000 | AC | 23 | Serious | 100 | 0 | 0 | 1 | 2 |
| EVB | TW D | Taxiway | 425 | 27,118 | AC | 89 | Good | 100 | 0 | 0 | 1 | 7 |
| EVB | TW D | Taxiway | 427 | 40,335 | AC | 90 | Good | 100 | 0 | 0 | 2 | 11 |
| EVB | TW D | Taxiway | 430 | 84,969 | AAC | 88 | Good | 100 | 0 | 0 | 3 | 21 |
| EVB | TW E | Taxiway | 505 | 17,197 | AC | 91 | Good | 100 | 0 | 0 | 1 | 5 |
| EVB | TW E | Taxiway | 510 | 24,594 | AC | 90 | Good | 100 | 0 | 0 | 1 | 7 |
| EVB | TW E | Taxiway | 515 | 52,494 | AC | 84 | Satisfactory | 100 | 0 | 0 | 2 | 13 |
| EVB | TW E | Taxiway | 520 | 27,412 | AC | 91 | Good | 100 | 0 | 0 | 1 | 8 |
| EVB | TW E | Taxiway | 530 | 76,505 | AC | 94 | Good | 100 | 0 | 0 | 2 | 14 |
| EVB | TW F | Taxiway | 610 | 28,075 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | TL T-HANG | Taxilane | 4320 | 31,261 | AC | 64 | Fair | 100 | 0 | 0 | 2 | 7 |
| EVB | TL T-HANG | Taxilane | 4340 | 8,491 | AC | 85 | Satisfactory | 100 | 0 | 0 | 1 | 2 |
| EVB | TL T-HANG | Taxilane | 4360 | 11,098 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | Apron | 4102 | 20,539 | PCC | 4 | Failed | 6 | 80 | 14 | 1 | 4 |


| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface | PCI | Condition Rating | PCI % Climate | PCI % Load | PCI % Other | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|------------|------------|-----------|---------|-----|------------------|---------------|------------|-------------|---------------------------|----------------------------------|
| EVB | AP | Apron | 4103 | 9,336 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | Apron | 4104 | 3,872 | AC | 43 | Poor | 100 | 0 | 0 | 1 | 1 |
| EVB | AP | Apron | 4105 | 6,440 | PCC | 9 | Failed | 9 | 91 | 0 | 1 | 1 |
| EVB | AP | Apron | 4106 | 3,540 | PCC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | Apron | 4107 | 12,117 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | Apron | 4108 | 8,757 | PCC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | Apron | 4110 | 1,950 | PCC | 7 | Failed | 9 | 91 | 0 | 1 | 1 |
| EVB | AP | Apron | 4115 | 8,775 | PCC | 1 | Failed | 7 | 91 | 2 | 1 | 1 |
| EVB | AP | Apron | 4124 | 6,450 | PCC | 73 | Satisfactory | 38 | 41 | 21 | 1 | 2 |
| EVB | AP | Apron | 4127 | 1,560 | PCC | 87 | Good | 90 | 0 | 10 | 1 | 2 |
| EVB | AP | Apron | 4128 | 6,565 | PCC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | Apron | 4129 | 2,070 | PCC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | Apron | 4130 | 23,150 | PCC | 47 | Poor | 15 | 44 | 41 | 1 | 5 |
| EVB | AP | Apron | 4132 | 17,074 | PCC | 23 | Serious | 11 | 72 | 17 | 1 | 5 |
| EVB | AP | Apron | 4135 | 4,290 | AC | 33 | Very Poor | 76 | 21 | 3 | 1 | 1 |
| EVB | AP | Apron | 4140 | 37,036 | AC | 35 | Very Poor | 100 | 0 | 0 | 2 | 9 |
| EVB | AP | Apron | 4145 | 17,888 | AC | 65 | Fair | 100 | 0 | 0 | 1 | 4 |
| EVB | AP | Apron | 4160 | 10,001 | AC | 41 | Poor | 92 | 0 | 8 | 1 | 2 |
| EVB | AP | Apron | 4165 | 9,517 | PCC | 10 | Failed | 0 | 52 | 48 | 1 | 1 |
| EVB | AP | Apron | 4190 | 38,656 | PCC | 90 | Good | 18 | 0 | 82 | 3 | 10 |
| EVB | AP RU | Apron | 5105 | 46,282 | AC | 32 | Very Poor | 100 | 0 | 0 | 1 | 10 |
| EVB | AP S | Apron | 4215 | 56,450 | PCC | 9 | Failed | 6 | 76 | 18 | 2 | 7 |
| EVB | AP S | Apron | 4225 | 44,991 | PCC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| EVB | AP SE | Apron | 4220 | 8,835 | PCC | 1 | Failed | 6 | 92 | 2 | 2 | 2 |

^{*}Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.

Table 4.1.3 (b): Latest PASER Surface Rating - Section Level - Whitetopping Pavements

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface | PASER Value | Surface Rating | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|------------|------------|-----------|---------|-------------|----------------|------------------------|-------------------------------|
| EVB | TW C | Taxiway | 305 | 48,858 | WT | 4 | Good | 2 | 10 |
| EVB | AP | Apron | 4120 | 14,180 | WT | 2 | Poor | 1 | 3 |
| EVB | AP | Apron | 4121 | 12,650 | WT | 2 | Poor | 1 | 2 |
| EVB | AP | Apron | 4125 | 17,693 | WT | 3 | Fair | 1 | 3 |
| EVB | AP | Apron | 4126 | 12,548 | WT | 3 | Fair | 1 | 3 |
| EVB | AP | Apron | 4150 | 45,150 | WT | 3 | Fair | 2 | 9 |
| EVB | AP | Apron | 4154 | 7,400 | WT | 4 | Good | 1 | 2 |
| EVB | AP | Apron | 4155 | 3,500 | WT | 3 | Fair | 1 | 1 |





4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The PCI assessment for New Smyrna Beach Municipal Airport (EVB) was performed in January 2022. The overall area-weighted average PCI value of the network was 70, representing a condition rating of Fair. A portion of the airfield pavement was not inspected due to recent construction in 2020, 2021, and 2022. These areas include portions of Taxiway C, the main Apron, South Apron, Taxiway F, and the T-Hangar Taxilanes between Taxiway C and E.

Based on the FAA 5010 Report as of 11/14/2022, the Airport has reported 130,986 operations for 12 months ending 8/14/2018.

4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

Runways

RW 11-29

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| RW 11-29 | RUNWAY | 1 | 323,925 | 81 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 6105 | AAC | 323,925 | 81 | Satisfactory |


RW 11-29 consists of 1 flexible pavement section, totaling 323,925 sf. The last major construction date for the branch was 2014, resulting in an area-weighted average age at inspection of 8 years old. Overall, RW 11-29 is in Satisfactory condition with an area-weighted average PCI of 81.



RW 2-20

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| RW 2-20 | RUNWAY | 6 | 387,523 | 37 | Very Poor |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 3% Good (86-100 PCI), 3% Satisfactory (71-85 PCI), 94% Very Poor (26-40 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 6405 | AC | 78,400 | 33 | Very Poor |
| 6425 | AC | 254,789 | 34 | Very Poor |
| 6427 | AC | 11,862 | 89 | Good |
| 6430 | AC | 5,000 | 38 | Very Poor |
| 6435 | AAC | 12,472 | 83 | Satisfactory |
| 6450 | AC | 25,000 | 34 | Very Poor |

RW 2-20 consists of 6 flexible pavement sections, totaling 387,523 sf. The last major construction dates range from 1943 to 2014, resulting in an area-weighted average age at inspection of 72 years old. Overall, RW 2-20 is in Very Poor condition with an area-weighted average PCI of 37.

RW 7-25

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| RW 7-25 | RUNWAY | 5 | 375,128 | 88 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 92% Good (86-100 PCI), 8% Satisfactory (71-85 PCI).





| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 6202 | AAC | 18,750 | 76 | Satisfactory |
| 6205 | AAC | 324,750 | 89 | Good |
| 6210 | AAC | 11,378 | 84 | Satisfactory |
| 6215 | AAC | 7,125 | 91 | Good |
| 6220 | AAC | 13,125 | 88 | Good |

RW 7-25 consists of 5 flexible pavement sections, totaling 375,128 sf. The last major construction dates range from 2008 to 2016, resulting in an area-weighted average age at inspection of 7 years old. Overall, RW 7-25 is in Good condition with an area-weighted average PCI of 88.

Taxiways

TW A

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| TW A | TAXIWAY | 5 | 142,094 | 61 | Fair |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 4% Good (86-100 PCI), 27% Satisfactory (71-85 PCI), 69% Poor (41-55 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 102 | AC | 22,287 | 85 | Satisfactory |
| 105 | AC | 93,280 | 51 | Poor |
| 110 | AC | 16,319 | 82 | Satisfactory |
| 115 | AC | 5,905 | 86 | Good |
| 125 | AC | 4,303 | 52 | Poor |

TW A consists of 5 flexible pavement sections, totaling 142,094 sf. The last major construction dates range from 1977 to 2014, resulting in an area-weighted average age at inspection of 33 years old. Overall, TW A is in Fair condition with an area-weighted average PCI of 61.



TW B

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| TW B | TAXIWAY | 2 | 173,763 | 68 | Fair |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 39% Satisfactory (71-85 PCI), 61% Fair (56-70 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 210 | AC | 67,896 | 73 | Satisfactory |
| 215 | AC | 105,867 | 64 | Fair |

TW B consists of 2 flexible pavement sections, totaling 173,763 sf. The last major construction date for the branch was 2002, resulting in an area-weighted average age at inspection of 20 years old. Overall, TW B is in Fair condition with an area-weighted average PCI of 68.

TW C

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| TW C | TAXIWAY | 7 | 245,160 | 90 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 92% Good (86-100 PCI), 2% Fair (56-70 PCI), 6% Very Poor (26-40 PCI).





| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 310 | AC | 13,657 | 33 | Very Poor |
| 312 | AC | 12,746 | 100 | Good |
| 314 | AC | 57,036 | 100 | Good |
| 315 | AC | 24,500 | 100 | Good |
| 325 | AC | 5,247 | 59 | Fair |
| 330 | AC | 44,997 | 100 | Good |
| 345 | AC | 86,977 | 86 | Good |

TW C consists of 7 flexible pavement sections, totaling 245,160 sf. The last major construction dates range from 2002 to 2022, resulting in an area-weighted average age at inspection of 5 years old. Overall, TW C is in Good condition with an area-weighted average PCI of 90.

| Section ID | Surface Type | Section Area (SF) | PASER Value | Surface Rating |
|------------|--------------|----------------------|-------------|-------------------|
| 305 | WT | 48,858 | 4 | Good |

TW C whitetopping pavement consists of 1 whitetopping concrete overlay pavement section, totaling 48,858 sf. The last major construction date for the whitetopping section was 2002, resulting in an age of 20 years old. Overall, TW C whitetopping pavement is in Good condition with a PASER value of 4 (out of 5).

TW D

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| TW D | TAXIWAY | 5 | 210,050 | 82 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 73% Good (86-100 PCI), 24% Fair (56-70 PCI), 3% Serious (11-25 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 405 | AC | 50,628 | 68 | Fair |
| 415 | AC | 7,000 | 23 | Serious |
| 425 | AC | 27,118 | 89 | Good |
| 427 | AC | 40,335 | 90 | Good |
| 430 | AAC | 84,969 | 88 | Good |




TW D consists of 5 flexible pavement sections, totaling 210,050 sf. The last major construction dates range from 1943 to 2016, resulting in an area-weighted average age at inspection of 13 years old. Overall, TW D is in Satisfactory condition with an area-weighted average PCI of 82.

TW E

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| TW E | TAXIWAY | 5 | 198,202 | 90 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 74% Good (86-100 PCI), 26% Satisfactory (71-85 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 505 | AC | 17,197 | 91 | Good |
| 510 | AC | 24,594 | 90 | Good |
| 515 | AC | 52,494 | 84 | Satisfactory |
| 520 | AC | 27,412 | 91 | Good |
| 530 | AC | 76,505 | 94 | Good |

TW E consists of 5 flexible pavement sections, totaling 198,202 sf. The last major construction dates range from 2011 to 2018, resulting in an area-weighted average age at inspection of 7 years old. Overall, TW E is in Good condition with an area-weighted average PCI of 90.

<u>Aprons</u>


AP

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| AP | APRON | 21 | 249,583 | 53 | Poor |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 33% Good (86-100 PCI), 3% Satisfactory (71-85 PCI), 7% Fair (56-70 PCI), 15% Poor (41-55 PCI), 17% Very Poor (26-40 PCI), 7% Serious (11-25 PCI), 18% Failed (0-10 PCI).



Statewide Airfield Pavement Management Program



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 4102 | PCC | 20,539 | 4 | Failed |
| 4103 | AC | 9,336 | 100 | Good |
| 4104 | AC | 3,872 | 43 | Poor |
| 4105 | PCC | 6,440 | 9 | Failed |
| 4106 | PCC | 3,540 | 100 | Good |
| 4107 | AC | 12,117 | 100 | Good |
| 4108 | PCC | 8,757 | 100 | Good |
| 4110 | PCC | 1,950 | 7 | Failed |
| 4115 | PCC | 8,775 | 1 | Failed |
| 4124 | PCC | 6,450 | 73 | Satisfactory |
| 4127 | PCC | 1,560 | 87 | Good |
| 4128 | PCC | 6,565 | 100 | Good |
| 4129 | PCC | 2,070 | 100 | Good |
| 4130 | PCC | 23,150 | 47 | Poor |
| 4132 | PCC | 17,074 | 23 | Serious |
| 4135 | AC | 4,290 | 33 | Very Poor |
| 4140 | AC | 37,036 | 35 | Very Poor |
| 4145 | AC | 17,888 | 65 | Fair |
| 4160 | AC | 10,001 | 41 | Poor |
| 4165 | PCC | 9,517 | 10 | Failed |
| 4190 | PCC | 38,656 | 90 | Good |

AP consists of 7 flexible and 14 rigid pavement sections, totaling 249,583 sf. The last major construction dates range from 1965 to 2022, resulting in an area-weighted average age at inspection of 26 years old. Overall, AP is in Poor condition with an area-weighted average PCI of 53.

| Section ID | Surface Type | Section Area (SF) | PASER Value | Surface Rating |
|------------|--------------|----------------------|-------------|-------------------|
| 4120 | WT | 14,180 | 2 | Poor |
| 4121 | WT | 12,650 | 2 | Poor |
| 4125 | WT | 24,143 | 3 | Fair |
| 4126 | WT | 12,548 | 3 | Fair |
| 4150 | WT | 45,150 | 3 | Fair |
| 4154 | WT | 7,400 | 4 | Good |
| 4155 | WT | 3,500 | 3 | Fair |




Statewide Airfield Pavement Management Program

AP whitetopping pavement consists of 7 whitetopping concrete overlay pavement sections, totaling 131,121 sf. The last major construction date for the whitetopping sections was 2002, resulting in an area-weighted average age of 20 years old. Overall, AP Whitetopping pavement is in Fair condition with an area-weighted average PASER value of 3 (out of 5).

AP S

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area- Weighted Avg PCI | Branch Condition Rating |
|-----------|---------------|--------------------|---------------------|----------------------------------|-------------------------------|
| AP S | APRON | 2 | 101,441 | 49 | Poor |


The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 44% Good (86-100 PCI), 56% Failed (0-10 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|----------------------|-----|---------------------|
| 4215 | PCC | 56,450 | 9 | Failed |
| 4225 | PCC | 44,991 | 100 | Good |

AP S consists of 2 rigid pavement sections, totaling 101,441 sf. The last major construction dates range from 1943 to 2020, resulting in an area-weighted average age at inspection of 44 years old. Overall, AP S is in Poor condition with an area-weighted average PCI of 49.





Chapter 5: SAPMP Customization

Chapter 5 – SAPMP Customization

Once the PAVERTM database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- The "Network" field identifies the airport being analyzed;
- The "Airport Classification" field classifies the Airport according to the type and volume of aircraft traffic;
 - o "GA" for General Aviation, community airports
 - o "RL" for Regional Relievers
 - o "PR" for Primary/Commercial airports
- The "District" field identifies the FDOT District to which the Airport belongs;
- The "FAA ADO Area" is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists):
- The "Inspection Phase" denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- The "CFASPP Center" identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation for airfield pavements not including whitetopping pavements.



5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.

5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into "groups" or "families" according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

5.2.3 Branch-Level Pavement Condition Forecast

Figure 5.2.3 depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.




Figure 5.2.3: Forecasted Branch-Level Pavement Performance



5.2.4 Section-Level Pavement Condition Forecast

Table 5.2.4 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

Table 5.2.4: Forecasted PCI Values 2023-2032 - Section-Level

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|---------------|--------------|---------------|----------------|------|------|------|------|------|------|------|------|------|------|
| EVB | RW 2-20 | 6405 | 33 | 32 | 31 | 30 | 29 | 27 | 26 | 25 | 24 | 23 | 22 |
| EVB | RW 2-20 | 6425 | 34 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 25 | 24 | 23 |
| EVB | RW 2-20 | 6427 | 89 | 87 | 85 | 83 | 81 | 80 | 78 | 76 | 75 | 73 | 71 |
| EVB | RW 2-20 | 6430 | 38 | 38 | 37 | 37 | 36 | 36 | 35 | 35 | 34 | 33 | 32 |
| EVB | RW 2-20 | 6435 | 83 | 80 | 78 | 76 | 74 | 72 | 71 | 69 | 67 | 65 | 63 |
| EVB | RW 2-20 | 6450 | 34 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 25 | 24 | 23 |
| EVB | RW 7-25 | 6202 | 76 | 73 | 71 | 69 | 67 | 65 | 64 | 62 | 60 | 58 | 56 |
| EVB | RW 7-25 | 6205 | 89 | 86 | 84 | 82 | 80 | 78 | 77 | 75 | 73 | 71 | 69 |
| EVB | RW 7-25 | 6210 | 84 | 81 | 79 | 77 | 75 | 73 | 72 | 70 | 68 | 66 | 64 |
| EVB | RW 7-25 | 6215 | 91 | 88 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 73 | 71 |
| EVB | RW 7-25 | 6220 | 88 | 85 | 83 | 81 | 79 | 77 | 76 | 74 | 72 | 70 | 68 |
| EVB | RW 11-29 | 6105 | 81 | 78 | 76 | 74 | 72 | 70 | 69 | 67 | 65 | 63 | 61 |
| EVB | TW A | 102 | 85 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 |
| EVB | TW A | 105 | 51 | 50 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 47 | 46 |
| EVB | TW A | 110 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 71 | 70 | 68 | 67 |
| EVB | TW A | 115 | 86 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 |
| EVB | TW A | 125 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| EVB | TW B | 210 | 73 | 71 | 70 | 69 | 68 | 66 | 65 | 64 | 64 | 63 | 62 |
| EVB | TW B | 215 | 64 | 63 | 62 | 61 | 60 | 60 | 59 | 58 | 58 | 57 | 56 |
| EVB | TW C | 310 | 33 | 31 | 30 | 28 | 27 | 25 | 24 | 22 | 20 | 19 | 17 |
| EVB | TW C | 312 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 314 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 315 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 325 | 59 | 58 | 57 | 57 | 56 | 56 | 55 | 55 | 54 | 54 | 53 |
| EVB | TW C | 330 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 345 | 86 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 |
| EVB | TW D | 405 | 68 | 66 | 65 | 64 | 64 | 63 | 62 | 61 | 60 | 60 | 59 |
| EVB | TW D | 415 | 23 | 21 | 19 | 17 | 15 | 13 | 11 | 9 | 8 | 6 | 4 |
| EVB | TW D | 425 | 89 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 |
| EVB | TW D | 427 | 90 | 87 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 72 |
| EVB | TW D | 430 | 88 | 85 | 83 | 81 | 80 | 78 | 76 | 75 | 74 | 72 | 71 |
| EVB | TW E | 505 | 91 | 88 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 |
| EVB | TW E | 510 | 90 | 87 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 72 |
| EVB | TW E | 515 | 84 | 81 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 69 |
| EVB | TW E | 520 | 91 | 88 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 |
| EVB | TW E | 530 | 94 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 | 76 | 75 |
| EVB | TW F | 610 | 100 | 94 | 92 | 89 | 87 | 85 | 84 | 82 | 80 | 78 | 77 |
| EVB | TL T-HANG | 4320 | 64 | 63 | 62 | 61 | 60 | 60 | 59 | 58 | 58 | 57 | 56 |
| EVB | TL T-HANG | 4340 | 85 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 |

Airport Pavement Evaluation Report Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|---------------|--------------|---------------|----------------|------|------|------|------|------|------|------|------|------|------|
| EVB | TL T-HANG | 4360 | 100 | 94 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| EVB | AP | 4102 | 4 | 3 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | 4103 | 100 | 97 | 94 | 92 | 90 | 88 | 85 | 83 | 81 | 79 | 78 |
| EVB | AP | 4104 | 43 | 42 | 42 | 41 | 41 | 41 | 40 | 40 | 39 | 39 | 39 |
| EVB | AP | 4105 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 |
| EVB | AP | 4106 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4107 | 100 | 94 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 77 | 75 |
| EVB | AP | 4108 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4110 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 | 0 | 0 |
| EVB | AP | 4115 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | 4124 | 73 | 71 | 70 | 68 | 67 | 66 | 64 | 63 | 62 | 60 | 59 |
| EVB | AP | 4127 | 87 | 86 | 85 | 84 | 83 | 82 | 81 | 80 | 79 | 78 | 77 |
| EVB | AP | 4128 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4129 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4130 | 47 | 46 | 45 | 44 | 43 | 42 | 41 | 40 | 39 | 38 | 37 |
| EVB | AP | 4132 | 23 | 22 | 21 | 20 | 19 | 18 | 17 | 16 | 15 | 14 | 13 |
| EVB | AP | 4135 | 33 | 32 | 32 | 31 | 30 | 30 | 29 | 28 | 28 | 27 | 26 |
| EVB | AP | 4140 | 35 | 34 | 34 | 33 | 33 | 32 | 32 | 31 | 31 | 30 | 29 |
| EVB | AP | 4145 | 65 | 63 | 62 | 61 | 59 | 58 | 57 | 56 | 55 | 54 | 53 |
| EVB | AP | 4160 | 41 | 40 | 40 | 40 | 39 | 39 | 38 | 38 | 38 | 37 | 37 |
| EVB | AP | 4165 | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| EVB | AP | 4190 | 90 | 89 | 88 | 87 | 86 | 85 | 84 | 83 | 82 | 81 | 80 |
| EVB | AP RU | 5105 | 32 | 31 | 31 | 30 | 29 | 29 | 28 | 27 | 26 | 26 | 25 |
| EVB | AP S | 4215 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 |
| EVB | AP S | 4225 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP SE | 4220 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |



5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.




Figure 5.3 (a): Pavement Life and the Effect of Treatments

FAA Eligibilty Thresholds: >70: Routine Maintenance 55-70: Rehabilitation Eligible <55: Reconstruction Eligible

*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.

Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will



integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3** (b).

Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects

| Airfield Pavement Project Type | PCI Requirement | | | |
|--------------------------------|-----------------|--|--|--|
| Reconstruction | PCI < 55 (Poor) | | | |
| Rehabilitation | PCI < 70 (Fair) | | | |
| Maintenance | N/A | | | |

^{*}Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

Table 5.3 (b): Critical PCI Values by Branch Use

| Runway | Taxiway | Apron |
|--------|---------|-------|
| 70 | 70 | 70 |

Figures 5.3 (b) and **5.3 (c)** depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.







Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, PCI ≥ Critical PCI



5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 "Airport Foreign Object Debris (FOD) Management" provides additional guidance for developing and managing an airport FOD program.

For planning-level maintenance and repair consideration, concrete overlays should be treated like a rigid pavement section composed of portland cement concrete. However, no planning-level recommendations with estimated maintenance and repair quantities for whitetopping pavements will be provided herein.

5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety ("stopgap") measure. The two (2) types of localized maintenance are described below in further detail.

- Localized Preventive Maintenance and Repair
 - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- \(\) Localized Stopgap/Safety Maintenance and Repair



 Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

AC Crack Sealing

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

AC Full-Depth Patching

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

AC Partial-Depth AC Patching

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

<u>Grinding</u>

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.



Monitor Pavement

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.

PCC Crack Sealing

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

PCC Full-Depth Patching

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

PCC Joint Seal

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

PCC Partial-Depth Patching

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

PCC Slab Replacement

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

Surface Seal

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a



repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Tables 5.4.3 (a) and **(b)** display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs - Asphalt Concrete

| Localized Work Type | General | Aviation Costs | Work Type Unit | | |
|---------------------------|---------|----------------|----------------|--|--|
| AC Crack Sealing | \$ | 4.00 | LF | | |
| AC Full-Depth Patching | \$ | 10.00 | SF | | |
| AC Partial-Depth Patching | \$ | 4.75 | SF | | |
| Surface Seal | \$ | 0.75 | SF | | |

Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs - Portland Cement Concrete

| Localized Work Type | Genera | I Aviation Costs | Work Type Unit |
|----------------------------|--------|------------------|----------------|
| Grinding | \$ | 2.00 | SF |
| PCC Crack Sealing | \$ | 7.00 | LF |
| PCC Joint Seal | \$ | 4.25 | LF |
| PCC Full-Depth Patching | \$ | 50.00 | SF |
| PCC Partial-Depth Patching | \$ | 169.00 | SF |
| PCC Slab Replacement | \$ | 51.50 | SF |

^{*}PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.



5.4.4 Localized Maintenance and Repair Policy

Table 5.4.4 and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.

Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy

| Distress | Severity | Description | AC Preventive Work Type | AC Stopgap Work Type |
|----------|----------|-------------------------|---------------------------|---------------------------|
| 41 | Low | Alligator Cracking | Monitor Pavement | Monitor Pavement |
| 41 | Medium | Alligator Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 41 | High | Alligator Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 42 | N/A | Bleeding | Monitor Pavement | Monitor Pavement |
| 43 | Low | Block Cracking | Monitor Pavement | Monitor Pavement |
| 43 | Medium | Block Cracking | AC Crack Sealing | Monitor Pavement |
| 43 | High | Block Cracking | AC Crack Sealing | AC Crack Sealing |
| 44 | Low | Corrugation | Monitor Pavement | Monitor Pavement |
| 44 | Medium | Corrugation | AC Full Depth Patching | Monitor Pavement |
| 44 | High | Corrugation | AC Full Depth Patching | AC Full Depth Patching |
| 45 | Low | Depression | Monitor Pavement | Monitor Pavement |
| 45 | Medium | Depression | AC Full Depth Patching | Monitor Pavement |
| 45 | High | Depression | AC Full Depth Patching | AC Full Depth Patching |
| 46 | N/A | Jet Blast | Monitor Pavement | Monitor Pavement |
| 47 | Low | Jt. Reflective Cracking | Monitor Pavement | Monitor Pavement |
| 47 | Medium | Jt. Reflective Cracking | AC Crack Sealing | Monitor Pavement |
| 47 | High | Jt. Reflective Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 48 | Low | L&T Cracking | Monitor Pavement | Monitor Pavement |
| 48 | Medium | L&T Cracking | AC Crack Sealing | Monitor Pavement |
| 48 | High | L&T Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 49 | N/A | Oil Spillage | Monitor Pavement | Monitor Pavement |
| 50 | Low | Patching | Monitor Pavement | Monitor Pavement |
| 50 | Medium | Patching | AC Full Depth Patching | Monitor Pavement |
| 50 | High | Patching | AC Full Depth Patching | AC Full Depth Patching |
| 51 | N/A | Polished Aggregate | Monitor Pavement | Monitor Pavement |
| 52 | Low | Raveling | Surface Seal | Monitor Pavement |
| 52 | Medium | Raveling | Surface Seal | Monitor Pavement |
| 52 | High | Raveling | AC Partial Depth Patching | AC Partial Depth Patching |
| 53 | Low | Rutting | Monitor Pavement | Monitor Pavement |
| 53 | Medium | Rutting | AC Full Depth Patching | Monitor Pavement |
| 53 | High | Rutting | AC Full Depth Patching | AC Full Depth Patching |
| 54 | Low | Shoving | Monitor Pavement | Monitor Pavement |
| 54 | Medium | Shoving | AC Partial Depth Patching | Monitor Pavement |



| Distress | Severity | Description | AC Preventive Work Type | AC Stopgap Work Type |
|----------|----------|-------------------|---------------------------|------------------------|
| 54 | High | Shoving | AC Full Depth Patching | AC Full Depth Patching |
| 55 | N/A | Slippage Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 56 | Low | Swelling | Monitor Pavement | Monitor Pavement |
| 56 | Medium | Swelling | AC Full Depth Patching | Monitor Pavement |
| 56 | High | Swelling | AC Full Depth Patching | AC Full Depth Patching |
| 57 | Low | Weathering | Monitor Pavement | Monitor Pavement |
| 57 | Medium | Weathering | Surface Seal | Monitor Pavement |
| 57 | High | Weathering | AC Partial Depth Patching | Surface Seal |

Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy

| Distress | Severity | Description | PCC Preventive Work Type | PCC Stopgap Work Type |
|----------|----------|---------------------|----------------------------|----------------------------|
| 61 | Low | Blow-up | PCC Full Depth Patching | Monitor Pavement |
| 61 | Medium | Blow-up | PCC Full Depth Patching | PCC Full Depth Patching |
| 61 | High | Blow-up | PCC Slab Replacement | PCC Slab Replacement |
| 62 | Low | Corner Break | Monitor Pavement | Monitor Pavement |
| 62 | Medium | Corner Break | PCC Full Depth Patching | PCC Full Depth Patching |
| 62 | High | Corner Break | PCC Full Depth Patching | PCC Full Depth Patching |
| 63 | Low | Linear Cracking | Monitor Pavement | Monitor Pavement |
| 63 | Medium | Linear Cracking | PCC Crack Sealing | PCC Crack Sealing |
| 63 | High | Linear Cracking | PCC Full Depth Patching | PCC Crack Sealing |
| 64 | Low | Durability Cracking | Monitor Pavement | Monitor Pavement |
| 64 | Medium | Durability Cracking | PCC Full Depth Patching | PCC Full Depth Patching |
| 64 | High | Durability Cracking | PCC Slab Replacement | PCC Slab Replacement |
| 65 | Low | Jt. Seal Damage | PCC Joint Seal | Monitor Pavement |
| 65 | Medium | Jt. Seal Damage | PCC Joint Seal | Monitor Pavement |
| 65 | High | Jt. Seal Damage | PCC Joint Seal | PCC Joint Seal |
| 66 | Low | Small Patch | Monitor Pavement | Monitor Pavement |
| 66 | Medium | Small Patch | PCC Partial Depth Patching | Monitor Pavement |
| 66 | High | Small Patch | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 67 | Low | Large Patch | Monitor Pavement | Monitor Pavement |
| 67 | Medium | Large Patch | PCC Full Depth Patching | Monitor Pavement |
| 67 | High | Large Patch | PCC Full Depth Patching | PCC Full Depth Patching |
| 68 | N/A | Popouts | Monitor Pavement | Monitor Pavement |
| 69 | N/A | Pumping | Monitor Pavement | Monitor Pavement |
| 70 | Low | Scaling | Monitor Pavement | Monitor Pavement |
| 70 | Medium | Scaling | PCC Slab Replacement | Monitor Pavement |
| 70 | High | Scaling | PCC Slab Replacement | PCC Slab Replacement |
| 71 | Low | Faulting | Monitor Pavement | Monitor Pavement |
| 71 | Medium | Faulting | Grinding | Monitor Pavement |

Statewide Airfield Pavement Management Program

| Distress | Severity | Description | PCC Preventive Work Type | PCC Stopgap Work Type |
|----------|----------|--------------------|----------------------------|----------------------------|
| 71 | High | Faulting | PCC Slab Replacement | PCC Slab Replacement |
| 72 | Low | Shattered Slab | PCC Crack Sealing | Monitor Pavement |
| 72 | Medium | Shattered Slab | PCC Slab Replacement | PCC Crack Sealing |
| 72 | High | Shattered Slab | PCC Slab Replacement | PCC Slab Replacement |
| 73 | N/A | Shrinkage Cracking | Monitor Pavement | Monitor Pavement |
| 74 | Low | Joint Spall | Monitor Pavement | Monitor Pavement |
| 74 | Medium | Joint Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 74 | High | Joint Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 75 | Low | Corner Spall | Monitor Pavement | Monitor Pavement |
| 75 | Medium | Corner Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 75 | High | Corner Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 76 | Low | ASR | Monitor Pavement | Monitor Pavement |
| 76 | Medium | ASR | PCC Slab Replacement | PCC Slab Replacement |
| 76 | High | ASR | PCC Slab Replacement | PCC Slab Replacement |

5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100, or a PASER value to 5, and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay. Policies and recommendations related to the whitetopping pavement will be presented in **Section 6.2.2 Major Rehabilitation Needs – Whitetopping Pavements**.

5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average General Aviation Airport Type requirements; no pavement design has been performed in



accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation

| Rehabilitation Type | General Aviation Pavement Section | | |
|--|--------------------------------------|--|--|
| AC Reconstruction | | | |
| | Pavement Removal | | |
| | Unclassified Excavation | | |
| Full-depth asphalt pavement section reconstruction. Removal of existing | Subgrade Stabilization (12") | | |
| pavement section and construction of a new section. | Limerock Base Course (6") | | |
| | Prime Coat | | |
| PCI < 55 | Tack Coat | | |
| | P-401 Surface Course (3") | | |
| | Excludes any paved shoulder features | | |
| AC Rehabilitation | | | |
| | 15% AC Reconstruction | | |
| Combination of asphalt pavement milling and replacement overlay with 15% | Mill and Overlay | | |
| of the areas subject to full-depth reconstruction. | AC Milling (3") | | |
| | Tack Coat | | |
| PCI = 55 to 70 | P-401 Surface Course (3") | | |
| | Excludes any paved shoulder features | | |
| PCC Reconstruction | | | |
| | Pavement Removal | | |
| | Unclassified Excavation | | |
| Full-depth rigid pavement section reconstruction. | Subgrade Stabilization (6") | | |
| PCI < 55 | Limerock Base Course (6") | | |
| | P-501 PCC Pavement (8") | | |
| | PCC Joint Seal | | |
| PCC Rehabilitation | | | |
| Rehabilitation of PCC pavement with a combination of crack sealing, joint | 15% Slab Replacement | | |
| seal replacement, limited patching, and replacement of 15% of slab panels. | Joint and Crack Seal | | |
| PCI = 55 to 70 | Limited Patching | | |

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.



Reconstruction (AC or PCC)

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

AC Rehabilitation

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

PCC Rehabilitation

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.

5.5.2 Major Rehabilitation Planning-Level Unit Costs


Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.

Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.

Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type

| Rehabilitation Type | PCI Range | Asphalt Concrete Cost per SF | Portland Cement Concrete Cost Per SF |
|------------------------|--------------|------------------------------|--------------------------------------|
| Rehabilitation | 55 to 70 | \$9.00 | \$15.00 |
| Reconstruction | 0 to 55 | \$16.00 | \$29.00 |





Planning and Budget Scenario Analysis

Chapter 6 – M&R Planning and Budget Scenario Analysis

6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

Table 6.1 (a) provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (a): Year 1 Summary of Localized Maintenance

| Work Category | Cost | | |
|--------------------------------------|------|-----------|--|
| Preventive | \$ | 87,910 | |
| Stopgap | \$ | 1,079,290 | |
| Planning-Level Localized M&R Needs = | \$ | 1,167,200 | |

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

Table 6.1 (b) summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

| Table 6.1 (b): Year | 1 Localized Maintenance by | Work Type Summary |
|---------------------|----------------------------|-------------------|
|---------------------|----------------------------|-------------------|

| Localized Maintenance Category | Localized Work Type | Rough Estimate of Work Quantity | Work Units | anning erial Cost |
|----------------------------------|----------------------------|---------------------------------|---------------|----------------------|
| | AC Crack Sealing | 453 | LF | \$ 1,830 |
| Localized Preventive Maintenance | Surface Seal | 71,450 | SF | \$ 53,660 |
| Localized Preventive Maintenance | PCC Joint Seal | 5,434 | LF | \$ 23,110 |
| | PCC Partial-Depth Patching | 54 | SF | \$ 9,310 |
| | AC Crack Sealing | 373 | LF | \$ 1,510 |
| | AC Partial-Depth Patching | 139 | SF | \$ 660 |
| | AC Full-Depth Patching | 1,276 | SF | \$ 12,760 |
| Localized Stongen Maintenance | PCC Crack Sealing | 5,396 | LF | \$ 37,840 |
| Localized Stopgap Maintenance | PCC Joint Seal | 13,461 | LF | \$ 57,240 |
| | PCC Partial-Depth Patching | 380 | SF | \$ 64,250 |
| | PCC Full-Depth Patching | 1,139 | SF | \$ 56,940 |
| | PCC Slab Replacement | 16,468 | SF | \$ 848,090 |

Table 6.1 (c) provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved "End Condition" PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary

| Network ID | Branch ID | Section ID | Area (SF) | Start PCI | End PCI | Cost |
|------------|-----------|------------|-----------|-----------|---------|--------------|
| EVB | RW 2-20 | 6405 | 78,400 | 33 | 33 | \$ - |
| EVB | RW 2-20 | 6425 | 254,789 | 34 | 34 | \$ 12,060 |
| EVB | RW 2-20 | 6427 | 11,862 | 89 | 92 | \$ 180 |
| EVB | RW 2-20 | 6430 | 5,000 | 38 | 38 | \$ - |
| EVB | RW 2-20 | 6435 | 12,472 | 83 | 88 | \$ 1,410 |
| EVB | RW 2-20 | 6450 | 25,000 | 34 | 34 | \$ - |
| EVB | RW 7-25 | 6202 | 18,750 | 76 | 91 | \$ 7,040 |
| EVB | RW 7-25 | 6205 | 324,750 | 89 | 90 | \$ 390 |
| EVB | RW 7-25 | 6210 | 11,378 | 84 | 89 | \$ 860 |
| EVB | RW 7-25 | 6215 | 7,125 | 91 | 91 | \$ - |
| EVB | RW 7-25 | 6220 | 13,125 | 88 | 88 | \$ - |
| EVB | RW 11-29 | 6105 | 323,925 | 81 | 85 | \$ 15,670 |
| EVB | TW A | 102 | 22,287 | 85 | 94 | \$ 1,680 |
| EVB | TW A | 105 | 93,280 | 51 | 51 | \$ - |
| EVB | TW A | 110 | 16,319 | 82 | 90 | \$ 2,450 |
| EVB | TW A | 115 | 5,905 | 86 | 89 | \$ 230 |
| EVB | TW A | 125 | 4,303 | 52 | 52 | \$ - |
| EVB | TW B | 210 | 67,896 | 73 | 78 | \$ 9,790 |
| EVB | TW B | 215 | 105,867 | 64 | 64 | \$ - |
| EVB | TW C | 310 | 13,657 | 33 | 33 | \$ - |

| Network ID | Branch ID | Section ID | Area (SF) | Start PCI | End PCI | Cost |
|------------|-----------|------------|-----------|-----------|---------|---------------|
| EVB | TW C | 312 | 12,746 | 100 | 100 | \$ - |
| EVB | TW C | 314 | 57,036 | 100 | 100 | \$ - |
| EVB | TW C | 315 | 24,500 | 100 | 100 | \$ - |
| EVB | TW C | 325 | 5,247 | 59 | 59 | \$ - |
| EVB | TW C | 330 | 44,997 | 100 | 100 | \$ - |
| EVB | TW C | 345 | 86,977 | 86 | 90 | \$ 5,590 |
| EVB | TW D | 405 | 50,628 | 68 | 68 | \$ - |
| EVB | TW D | 415 | 7,000 | 23 | 37 | \$ 1,290 |
| EVB | TW D | 425 | 27,118 | 89 | 89 | \$ - |
| EVB | TW D | 427 | 40,335 | 90 | 90 | \$ - |
| EVB | TW D | 430 | 84,969 | 88 | 88 | \$ - |
| EVB | TW E | 505 | 17,197 | 91 | 94 | \$ 650 |
| EVB | TW E | 510 | 24,594 | 90 | 90 | \$ - |
| EVB | TW E | 515 | 52,494 | 84 | 93 | \$ 7,880 |
| EVB | TW E | 520 | 27,412 | 91 | 94 | \$ 1,030 |
| EVB | TW E | 530 | 76,505 | 94 | 94 | \$ - |
| EVB | TW F | 610 | 28,075 | 100 | 100 | \$ - |
| EVB | TL T-HANG | 4320 | 31,261 | 64 | 64 | \$ - |
| EVB | TL T-HANG | 4340 | 8,491 | 85 | 90 | \$ 640 |
| EVB | TL T-HANG | 4360 | 11,098 | 100 | 100 | \$ - |
| EVB | AP | 4102 | 20,539 | 4 | 31 | \$ 267,940 |
| EVB | AP | 4103 | 9,336 | 100 | 100 | \$ - |
| EVB | AP | 4104 | 3,872 | 43 | 43 | \$ - |
| EVB | AP | 4105 | 6,440 | 9 | 34 | \$ 2,760 |
| EVB | AP | 4106 | 3,540 | 100 | 100 | \$ - |
| EVB | AP | 4107 | 12,117 | 100 | 100 | \$ - |
| EVB | AP | 4108 | 8,757 | 100 | 100 | \$ - |
| EVB | AP | 4110 | 1,950 | 7 | 39 | \$ 2,340 |
| EVB | AP | 4115 | 8,775 | 1 | 39 | \$ 79,080 |
| EVB | AP | 4124 | 6,450 | 73 | 83 | \$ 4,900 |
| EVB | AP | 4127 | 1,560 | 87 | 99 | \$ 1,890 |
| EVB | AP | 4128 | 6,565 | 100 | 100 | \$ - |
| EVB | AP | 4129 | 2,070 | 100 | 100 | \$ - |
| EVB | AP | 4130 | 23,150 | 47 | 66 | \$ 16,400 |
| EVB | AP | 4132 | 17,074 | 23 | 51 | \$ 12,560 |
| EVB | AP | 4135 | 4,290 | 33 | 40 | \$ 700 |
| EVB | AP | 4140 | 37,036 | 35 | 36 | \$ 660 |
| EVB | AP | 4145 | 17,888 | 65 | 65 | \$ - |
| EVB | AP | 4160 | 10,001 | 41 | 45 | \$ 90 |
| EVB | AP | 4165 | 9,517 | 10 | 19 | \$ 11,710 |
| EVB | AP | 4190 | 38,656 | 90 | 94 | \$ 25,610 |
| EVB | AP RU | 5105 | 46,282 | 32 | 37 | \$ 130 |
| EVB | AP S | 4215 | 56,450 | 9 | 33 | \$ 447,980 |
| EVB | AP S | 4225 | 44,991 | 100 | 100 | \$ - |
| EVB | AP SE | 4220 | 8,835 | 1 | 55 | \$ 223,440 |



6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b)** and **(c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- An estimation of current pavement condition;
-) Major pavement rehabilitation needs based on condition and policies; and
- >> Planning-level cost estimates for the major rehabilitation needs.

Table 6.2.1 (a) summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.



Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs


| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | ning Cost timate |
|-----------------|---------------|--------------|---------------|---------|--------------|---------------|------------------------|---------------------|
| 2023 | EVB | RW 2-20 | 6405 | AC | 78,400 | 32 | AC Reconstruction | \$ 1,255,000 |
| 2023 | EVB | RW 2-20 | 6425 | AC | 254,789 | 33 | AC Reconstruction | \$ 4,077,000 |
| 2023 | EVB | RW 2-20 | 6430 | AC | 5,000 | 38 | AC Reconstruction | \$ 80,000 |
| 2023 | EVB | RW 2-20 | 6450 | AC | 25,000 | 33 | AC Reconstruction | \$ 400,000 |
| 2023 | EVB | TW A | 105 | AC | 93,280 | 50 | AC Reconstruction | \$ 1,493,000 |
| 2023 | EVB | TW A | 125 | AC | 4,303 | 51 | AC Reconstruction | \$ 69,000 |
| 2023 | EVB | TW B | 215 | AC | 105,867 | 63 | AC Rehabilitation | \$ 953,000 |
| 2023 | EVB | TW C | 310 | AC | 13,657 | 31 | AC Reconstruction | \$ 219,000 |
| 2023 | EVB | TW C | 325 | AC | 5,247 | 58 | AC Rehabilitation | \$ 48,000 |
| 2023 | EVB | TW D | 405 | AC | 50,628 | 66 | AC Rehabilitation | \$ 456,000 |
| 2023 | EVB | TW D | 415 | AC | 7,000 | 21 | AC Reconstruction | \$ 112,000 |
| 2023 | EVB | TL T-HANG | 4320 | AC | 31,261 | 63 | AC Rehabilitation | \$ 282,000 |
| 2023 | EVB | AP | 4102 | PCC | 20,539 | 3 | PCC Reconstruction | \$ 596,000 |
| 2023 | EVB | AP | 4104 | AC | 3,872 | 42 | AC Reconstruction | \$ 62,000 |
| 2023 | EVB | AP | 4105 | PCC | 6,440 | 8 | PCC Reconstruction | \$ 187,000 |
| 2023 | EVB | AP | 4110 | PCC | 1,950 | 6 | PCC Reconstruction | \$ 57,000 |
| 2023 | EVB | AP | 4115 | PCC | 8,775 | 0 | PCC Reconstruction | \$ 255,000 |
| 2023 | EVB | AP | 4130 | PCC | 23,150 | 46 | PCC Reconstruction | \$ 672,000 |
| 2023 | EVB | AP | 4132 | PCC | 17,074 | 22 | PCC Reconstruction | \$ 496,000 |
| 2023 | EVB | AP | 4135 | AC | 4,290 | 32 | AC Reconstruction | \$ 69,000 |
| 2023 | EVB | AP | 4140 | AC | 37,036 | 34 | AC Reconstruction | \$ 593,000 |
| 2023 | EVB | AP | 4145 | AC | 17,888 | 63 | AC Rehabilitation | \$ 161,000 |
| 2023 | EVB | AP | 4160 | AC | 10,001 | 40 | AC Reconstruction | \$ 161,000 |
| 2023 | EVB | AP | 4165 | PCC | 9,517 | 9 | PCC Reconstruction | \$ 276,000 |
| 2023 | EVB | AP RU | 5105 | AC | 46,282 | 31 | AC Reconstruction | \$ 741,000 |
| 2023 | EVB | AP S | 4215 | PCC | 56,450 | 8 | PCC Reconstruction | \$ 1,638,000 |
| 2023 | EVB | AP SE | 4220 | PCC | 8,835 | 0 | PCC Reconstruction | \$ 257,000 |
| 2024 | EVB | TW B | 210 | AC | 67,896 | 70 | AC Rehabilitation | \$ 642,000 |
| 2025 | EVB | RW 7-25 | 6202 | AAC | 18,750 | 69 | AC Rehabilitation | \$ 187,000 |
| 2028 | EVB | RW 11-29 | 6105 | AAC | 323,925 | 69 | AC Rehabilitation | \$ 3,721,000 |
| 2029 | EVB | RW 2-20 | 6435 | AAC | 12,472 | 69 | AC Rehabilitation | \$ 151,000 |
| 2029 | EVB | RW 7-25 | 6210 | AAC | 11,378 | 70 | AC Rehabilitation | \$ 138,000 |
| 2030 | EVB | TW A | 110 | AC | 16,319 | 70 | AC Rehabilitation | \$ 207,000 |
| 2031 | EVB | RW 7-25 | 6220 | AAC | 13,125 | 70 | AC Rehabilitation | \$ 175,000 |
| 2031 | EVB | TW E | 515 | AC | 52,494 | 70 | AC Rehabilitation | \$ 699,000 |
| 2032 | EVB | RW 7-25 | 6205 | AAC | 324,750 | 69 | AC Rehabilitation | \$ 4,535,000 |
| 2032 | EVB | TW A | 102 | AC | 22,287 | 69 | AC Rehabilitation | \$ 312,000 |
| 2032 | EVB | TW A | 115 | AC | 5,905 | 70 | AC Rehabilitation | \$ 83,000 |
| 2032 | EVB | TW C | 345 | AC | 86,977 | 70 | AC Rehabilitation | \$ 1,215,000 |
| 2032 | EVB | TL T-HANG | 4340 | AC | 8,491 | 69 | AC Rehabilitation | \$ 119,000 |
| 2032 | EVB | AP | 4124 | PCC | 6,450 | 59 | PCC Rehabilitation | \$ 151,000 |

Figure 6.2.1 (a) summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

\$18,000,000 \$16,000,000 \$15,665,000 \$14,000,000 \$12,000,000 \$10,000,000 \$8,000,000 \$6,415,000 \$6,000,000 \$3,721,000 \$4,000,000 \$2,000,000 \$874,000 \$642,000 \$289,000 \$207,000 \$187,000 \$-\$-\$0 2023 2031 2032 2024 2025 2026 2027 2028 2029 2030

Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year





6.2.2 Major Rehabilitation Needs – Whitetopping Pavements

Major rehabilitation for whitetopping concrete overlays is divided into two policy categories as part of this program: Full-Depth Reconstruction (Reconstruction) and Intermediate-Level Major Rehabilitation (Rehabilitation).

- » Rehabilitation is recommended for whitetopping pavement with a PASER rating of 'Poor'.
- Reconstruction is recommended for whitetopping pavement with a PASER rating of 'Failed'.

Major rehabilitation is recommended based on current PASER Surface Rating as no formal PASER rating forecasting is performed. The conceptual pavement sections and unit costs developed for the whitetopping pavement is consistent with that which was developed for PCC pavement and presented in **Chapter 5.5 Major Rehabilitation**.

Table 6.2.2 summarizes section-level major rehabilitation for the whitetopping pavements. **Figure 6.2.1** (b) graphically depicts the major rehabilitation needs for the whitetopping pavements. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.

Table 6.2.2: Section-Level Major Rehabilitation Needs - Whitetopping Pavements

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PASER Value Before | Rehabilitation Type | lanning Cost stimate |
|-----------------|---------------|--------------|---------------|---------|--------------|--------------------------|------------------------|----------------------------|
| 2023 | EVB | AP | 4120 | WT | 14,180 | 2 | PCC Rehabilitation | \$ 213,000 |
| 2023 | EVB | AP | 4121 | WT | 12,650 | 2 | PCC Rehabilitation | \$ 190,000 |





Chapter 7: Conclusion

Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in Section 6.1;
- Further refine and implement the identified 10-year major rehabilitation needs provided in Section 6.2;
- Maintain detailed records on pavement maintenance, construction, and inspection; and
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



7.2 Supporting Documents

Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVERTM software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

Airfield PASER Surface Rating Exhibit

The Airfield PASER Surface Rating Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions of the airfield whitetopping pavements reported from the PASER assessment performed at the Airport. The PASER values are identified in the Exhibit and graphically represented using the standard PASER surface rating categories.

Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.



Airfield Pavement Major Rehabilitation Exhibit – Whitetopping Pavements

The Airfield Pavement Major Rehabilitation Exhibit – Whitetopping Pavements is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the PASER surface rating and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation.

Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.

7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.



- Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.





Pavement Analysis

Table A.1: Pavement System Inventory Details

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|-----------------|---------------------------------------|
| EVB | RW 2-20 | Runway | 6405 | 78,400 | AC | 1/1/1943 |
| EVB | RW 2-20 | Runway | 6425 | 254,789 | AC | 1/1/1943 |
| EVB | RW 2-20 | Runway | 6427 | 11,862 | AC | 1/1/2014 |
| EVB | RW 2-20 | Runway | 6430 | 5,000 | AC | 1/1/1977 |
| EVB | RW 2-20 | Runway | 6435 | 12,472 | AAC | 1/1/2014 |
| EVB | RW 2-20 | Runway | 6450 | 25,000 | AC | 1/1/1977 |
| EVB | RW 7-25 | Runway | 6202 | 18,750 | AAC | 1/1/2008 |
| EVB | RW 7-25 | Runway | 6205 | 324,750 | AAC | 1/1/2016 |
| EVB | RW 7-25 | Runway | 6210 | 11,378 | AAC | 1/1/2008 |
| EVB | RW 7-25 | Runway | 6215 | 7,125 | AAC | 1/1/2016 |
| EVB | RW 7-25 | Runway | 6220 | 13,125 | AAC | 1/1/2016 |
| EVB | RW 11-29 | Runway | 6105 | 323,925 | AAC | 1/1/2014 |
| EVB | TW A | Taxiway | 102 | 22,287 | AC | 1/1/2011 |
| EVB | TW A | Taxiway | 105 | 93,280 | AC | 1/1/1977 |
| EVB | TW A | Taxiway | 110 | 16,319 | AC | 7/1/2011 |
| EVB | TW A | Taxiway | 115 | 5,905 | AC | 1/1/2014 |
| EVB | TW A | Taxiway | 125 | 4,303 | AC | 1/1/2002 |
| EVB | TW B | Taxiway | 210 | 67,896 | AC | 1/1/2002 |
| EVB | TW B | Taxiway | 215 | 105,867 | AC | 1/1/2002 |
| EVB | TW C | Taxiway | 305 | 48,858 | WT | 1/1/2002 |
| EVB | TW C | Taxiway | 310 | 13,657 | AC | 1/1/2002 |
| EVB | TW C | Taxiway | 312 | 12,746 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 314 | 57,036 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 315 | 24,500 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 325 | 5,247 | AC | 1/1/2002 |
| EVB | TW C | Taxiway | 330 | 44,997 | AC | 4/1/2022 |
| EVB | TW C | Taxiway | 345 | 86,977 | AC | 1/1/2012 |
| EVB | TW D | Taxiway | 405 | 50,628 | AC | 1/1/2002 |
| EVB | TW D | Taxiway | 415 | 7,000 | AC | 1/1/1943 |
| EVB | TW D | Taxiway | 425 | 27,118 | AC | 1/1/2014 |
| EVB | TW D | Taxiway | 427 | 40,335 | AC | 1/1/2014 |
| EVB | TW D | Taxiway | 430 | 84,969 | AAC | 1/1/2016 |
| EVB | TW E | Taxiway | 505 | 17,197 | AC | 1/1/2014 |
| EVB | TW E | Taxiway | 510 | 24,594 | AC | 1/1/2014 |
| EVB | TW E | Taxiway | 515 | 52,494 | AC | 7/1/2011 |
| EVB | TW E | Taxiway | 520 | 27,412 | AC | 1/1/2014 |
| EVB | TW E | Taxiway | 530 | 76,505 | AC | 1/1/2018 |
| EVB | TW F | Taxiway | 610 | 28,075 | AC | 12/1/2020 |
| EVB | TL T-HANG | Taxilane | 4320 | 31,261 | AC | 1/1/2002 |
| EVB | TL T-HANG | Taxilane | 4340 | 8,491 | AC | 1/1/2010 |
| EVB | TL T-HANG | Taxilane | 4360 | 11,098 | AC | 3/1/2021 |
| EVB | AP | Apron | 4102 | 20,539 | PCC | 1/1/1984 |
| EVB | AP | Apron | 4103 | 9,336 | AC | 4/1/2022 |
| EVB | AP | Apron | 4104 | 3,872 | AC | 1/1/1984 |

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|-----------------|---------------------------------------|
| EVB | AP | Apron | 4105 | 6,440 | PCC | 1/1/1965 |
| EVB | AP | Apron | 4106 | 3,540 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4107 | 12,117 | AC | 12/1/2020 |
| EVB | AP | Apron | 4108 | 8,757 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4110 | 1,950 | PCC | 1/1/1980 |
| EVB | AP | Apron | 4115 | 8,775 | PCC | 1/1/1975 |
| EVB | AP | Apron | 4120 | 14,180 | WT | 1/1/2002 |
| EVB | AP | Apron | 4121 | 12,650 | WT | 1/1/2002 |
| EVB | AP | Apron | 4124 | 6,450 | PCC | 1/1/2002 |
| EVB | AP | Apron | 4125 | 24,143 | WT | 1/1/2002 |
| EVB | AP | Apron | 4126 | 12,548 | WT | 1/1/2002 |
| EVB | AP | Apron | 4127 | 1,560 | PCC | 1/1/2019 |
| EVB | AP | Apron | 4128 | 6,565 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4129 | 2,070 | PCC | 12/1/2020 |
| EVB | AP | Apron | 4130 | 23,150 | PCC | 1/1/1997 |
| EVB | AP | Apron | 4132 | 17,074 | PCC | 1/1/1997 |
| EVB | AP | Apron | 4135 | 4,290 | AC | 1/1/1975 |
| EVB | AP | Apron | 4140 | 37,036 | AC | 1/1/1980 |
| EVB | AP | Apron | 4145 | 17,888 | AC | 1/1/1986 |
| EVB | AP | Apron | 4150 | 45,150 | WT | 1/1/2002 |
| EVB | AP | Apron | 4154 | 7,400 | WT | 1/1/2002 |
| EVB | AP | Apron | 4155 | 3,500 | WT | 1/1/2002 |
| EVB | AP | Apron | 4160 | 10,001 | AC | 1/1/1975 |
| EVB | AP | Apron | 4165 | 9,517 | PCC | 1/1/1991 |
| EVB | AP | Apron | 4190 | 38,656 | PCC | 1/1/2012 |
| EVB | AP RU | Apron | 5105 | 46,282 | AC | 1/1/1943 |
| EVB | AP S | Apron | 4215 | 56,450 | PCC | 1/1/1943 |
| EVB | AP S | Apron | 4225 | 44,991 | PCC | 12/1/2020 |
| EVB | AP SE | Apron | 4220 | 8,835 | PCC | 12/25/1999 |



Table A.2: Pavement Condition Index Summary (Current PCI Survey) - Section Level

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|------------|------------|-----------|-----|------------------|
| EVB | RW 2-20 | Runway | 6405 | 78,400 | 33 | Very Poor |
| EVB | RW 2-20 | Runway | 6425 | 254,789 | 34 | Very Poor |
| EVB | RW 2-20 | Runway | 6427 | 11,862 | 89 | Good |
| EVB | RW 2-20 | Runway | 6430 | 5,000 | 38 | Very Poor |
| EVB | RW 2-20 | Runway | 6435 | 12,472 | 83 | Satisfactory |
| EVB | RW 2-20 | Runway | 6450 | 25,000 | 34 | Very Poor |
| EVB | RW 7-25 | Runway | 6202 | 18,750 | 76 | Satisfactory |
| EVB | RW 7-25 | Runway | 6205 | 324,750 | 89 | Good |
| EVB | RW 7-25 | Runway | 6210 | 11,378 | 84 | Satisfactory |
| EVB | RW 7-25 | Runway | 6215 | 7,125 | 91 | Good |
| EVB | RW 7-25 | Runway | 6220 | 13,125 | 88 | Good |
| EVB | RW 11-29 | Runway | 6105 | 323,925 | 81 | Satisfactory |
| EVB | TW A | Taxiway | 102 | 22,287 | 85 | Satisfactory |
| EVB | TW A | Taxiway | 105 | 93,280 | 51 | Poor |
| EVB | TW A | Taxiway | 110 | 16,319 | 82 | Satisfactory |
| EVB | TW A | Taxiway | 115 | 5,905 | 86 | Good |
| EVB | TW A | Taxiway | 125 | 4,303 | 52 | Poor |
| EVB | TW B | Taxiway | 210 | 67,896 | 73 | Satisfactory |
| EVB | TW B | Taxiway | 215 | 105,867 | 64 | Fair |
| EVB | TW C | Taxiway | 310 | 13,657 | 33 | Very Poor |
| EVB | TW C | Taxiway | 312 | 12,746 | 100 | Good |
| EVB | TW C | Taxiway | 314 | 57,036 | 100 | Good |
| EVB | TW C | Taxiway | 315 | 24,500 | 100 | Good |
| EVB | TW C | Taxiway | 325 | 5,247 | 59 | Fair |
| EVB | TW C | Taxiway | 330 | 44,997 | 100 | Good |
| EVB | TW C | Taxiway | 345 | 86,977 | 86 | Good |
| EVB | TW D | Taxiway | 405 | 50,628 | 68 | Fair |
| EVB | TW D | Taxiway | 415 | 7,000 | 23 | Serious |
| EVB | TW D | Taxiway | 425 | 27,118 | 89 | Good |
| EVB | TW D | Taxiway | 427 | 40,335 | 90 | Good |
| EVB | TW D | Taxiway | 430 | 84,969 | 88 | Good |
| EVB | TW E | Taxiway | 505 | 17,197 | 91 | Good |
| EVB | TW E | Taxiway | 510 | 24,594 | 90 | Good |
| EVB | TW E | Taxiway | 515 | 52,494 | 84 | Satisfactory |
| EVB | TW E | Taxiway | 520 | 27,412 | 91 | Good |
| EVB | TW E | Taxiway | 530 | 76,505 | 94 | Good |
| EVB | TW F | Taxiway | 610 | 28,075 | 100 | Good |
| EVB | TL T-HANG | Taxilane | 4320 | 31,261 | 64 | Fair |
| EVB | TL T-HANG | Taxilane | 4340 | 8,491 | 85 | Satisfactory |
| EVB | TL T-HANG | Taxilane | 4360 | 11,098 | 100 | Good |
| EVB | AP | Apron | 4102 | 20,539 | 4 | Failed |
| EVB | AP | Apron | 4103 | 9,336 | 100 | Good |
| EVB | AP | Apron | 4104 | 3,872 | 43 | Poor |
| EVB | AP | Apron | 4105 | 6,440 | 9 | Failed |

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|------------|------------|-----------|-----|------------------|
| EVB | AP | Apron | 4106 | 3,540 | 100 | Good |
| EVB | AP | Apron | 4107 | 12,117 | 100 | Good |
| EVB | AP | Apron | 4108 | 8,757 | 100 | Good |
| EVB | AP | Apron | 4110 | 1,950 | 7 | Failed |
| EVB | AP | Apron | 4115 | 8,775 | 1 | Failed |
| EVB | AP | Apron | 4124 | 6,450 | 73 | Satisfactory |
| EVB | AP | Apron | 4127 | 1,560 | 87 | Good |
| EVB | AP | Apron | 4128 | 6,565 | 100 | Good |
| EVB | AP | Apron | 4129 | 2,070 | 100 | Good |
| EVB | AP | Apron | 4130 | 23,150 | 47 | Poor |
| EVB | AP | Apron | 4132 | 17,074 | 23 | Serious |
| EVB | AP | Apron | 4135 | 4,290 | 33 | Very Poor |
| EVB | AP | Apron | 4140 | 37,036 | 35 | Very Poor |
| EVB | AP | Apron | 4145 | 17,888 | 65 | Fair |
| EVB | AP | Apron | 4160 | 10,001 | 41 | Poor |
| EVB | AP | Apron | 4165 | 9,517 | 10 | Failed |
| EVB | AP | Apron | 4190 | 38,656 | 90 | Good |
| EVB | AP RU | Apron | 5105 | 46,282 | 32 | Very Poor |
| EVB | AP S | Apron | 4215 | 56,450 | 9 | Failed |
| EVB | AP S | Apron | 4225 | 44,991 | 100 | Good |
| EVB | AP SE | Apron | 4220 | 8,835 | 1 | Failed |

Table A.3: PASER Surface Rating - Section Level - Whitetopping Pavements

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PASER Value | Surface Rating |
|------------|-----------|------------|------------|-----------|----------------|----------------|
| EVB | TW C | Taxiway | 305 | 48,858 | 4 | Good |
| EVB | AP | Apron | 4120 | 14,180 | 2 | Poor |
| EVB | AP | Apron | 4121 | 12,650 | 2 | Poor |
| EVB | AP | Apron | 4125 | 17,693 | 3 | Fair |
| EVB | AP | Apron | 4126 | 12,548 | 3 | Fair |
| EVB | AP | Apron | 4150 | 45,150 | 3 | Fair |
| EVB | AP | Apron | 4154 | 7,400 | 4 | Good |
| EVB | AP | Apron | 4155 | 3,500 | 3 | Fair |

Table A.4: Forecasted PCI Values 2023-2032 - Section-Level

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|---------------|--------------|---------------|----------------|------|----------|----------|----------|----------|----------|----------|----------|----------|----------|
| EVB | RW 2-20 | 6405 | 33 | 32 | 31 | 30 | 29 | 27 | 26 | 25 | 24 | 23 | 22 |
| EVB | RW 2-20 | 6425 | 34 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 25 | 24 | 23 |
| EVB | RW 2-20 | 6427 | 89 | 87 | 85 | 83 | 81 | 80 | 78 | 76 | 75 | 73 | 71 |
| EVB | RW 2-20 | 6430 | 38 | 38 | 37 | 37 | 36 | 36 | 35 | 35 | 34 | 33 | 32 |
| EVB | RW 2-20 | 6435 | 83 | 80 | 78 | 76 | 74 | 72 | 71 | 69 | 67 | 65 | 63 |
| EVB | RW 2-20 | 6450 | 34 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 25 | 24 | 23 |
| EVB | RW 7-25 | 6202 | 76 | 73 | 71 | 69 | 67 | 65 | 64 | 62 | 60 | 58 | 56 |
| EVB | RW 7-25 | 6205 | 89 | 86 | 84 | 82 | 80 | 78 | 77 | 75 | 73 | 71 | 69 |
| EVB | RW 7-25 | 6210 | 84 | 81 | 79 | 77 | 75 | 73 | 72 | 70 | 68 | 66 | 64 |
| EVB | RW 7-25 | 6215 | 91 | 88 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 73 | 71 |
| EVB | RW 7-25 | 6220 | 88 | 85 | 83 | 81 | 79 | 77 | 76 | 74 | 72 | 70 | 68 |
| EVB | RW 11-29 | 6105 | 81 | 78 | 76 | 74 | 72 | 70 | 69 | 67 | 65 | 63 | 61 |
| EVB | TW A | 102 | 85 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 |
| EVB | TW A | 105 | 51 | 50 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 47 | 46 |
| EVB | TW A | 110 | 82 | 80 | 78 | 76 | 75 | 73 | 72 | 71 | 70 | 68 | 67 |
| EVB | TW A | 115 | 86 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 |
| EVB | TW A | 125 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| EVB | TW B | 210 | 73 | 71 | 70 | 69 | 68 | 66 | 65 | 64 | 64 | 63 | 62 |
| EVB | TW B | 215 | 64 | 63 | 62 | 61 | 60 | 60 | 59 | 58 | 58 | 57 | 56 |
| EVB | TW C | 310 | 33 | 31 | 30 | 28 | 27 | 25 | 24 | 22 | 20 | 19 | 17 |
| EVB | TW C | 312 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 314 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 315 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 325 | 59 | 58 | 57 | 57 | 56 | 56 | 55 | 55 | 54 | 54 | 53 |
| EVB | TW C | 330 | 100 | 97 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 81 | 79 |
| EVB | TW C | 345 | 86 | 83 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 |
| EVB | TW D | 405 | 68 | 66 | 65 | 64 | 64 | 63 | 62 | 61 | 60 | 60 | 59 |
| EVB | TW D | 415 | 23 | 21 | 19 | 17 | 15 | 13 | 11 | 9 | 8 | 6 | 4 |
| EVB | TW D | 425 | 89 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 |
| EVB | TW D | 427 | 90 | 87 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 72 |
| EVB | TW D | 430 | 88 | 85 | 83 | 81 | 80 | 78 | 76 | 75 | 74 | 72 | 71 |
| EVB | TWE | 505 | 91 | 88 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 |
| EVB | TW E | 510 | 90 | 87 | 85 | 83 | 81 | 80 | 78 | 77 | 75 | 74 | 72 |
| EVB | TW E | 515 | 84 | 81 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 69 |
| EVB | TWE | 520 | 91 | 88 | 86 | 84 | 82 | 81 | 79 | 77 | 76 | 74 | 73 |
| EVB | TWE | 530 | 94 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 | 76 | 75 |
| EVB EVB | TW F | 610 4320 | 100 | 94 | 92 62 | 89 61 | 87 60 | 85 60 | 84 59 | 82 58 | 80 58 | 78 57 | 77 56 |
| EVB | TL T-HANG | 4340 | 85 | 82 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 |
| EVB | TL T-HANG | 4340 | 100 | 94 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 70 | 77 |
| EVB | AP | 4360 | 4 | 3 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | 4102 | 100 | 97 | 94 | 92 | 90 | 88 | 85 | 83 | 81 | 79 | 78 |
| EVB | AP | 4103 | 43 | 42 | 42 | 41 | 41 | 41 | 40 | 40 | 39 | 39 | 39 |
| | | | | | | | | | | | | | |
| EVB | AP | 4105 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 |

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|---------------|--------------|---------------|----------------|------|------|------|------|------|------|------|------|------|------|
| EVB | AP | 4106 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4107 | 100 | 94 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 77 | 75 |
| EVB | AP | 4108 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4110 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 | 0 | 0 |
| EVB | AP | 4115 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| EVB | AP | 4124 | 73 | 71 | 70 | 68 | 67 | 66 | 64 | 63 | 62 | 60 | 59 |
| EVB | AP | 4127 | 87 | 86 | 85 | 84 | 83 | 82 | 81 | 80 | 79 | 78 | 77 |
| EVB | AP | 4128 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4129 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP | 4130 | 47 | 46 | 45 | 44 | 43 | 42 | 41 | 40 | 39 | 38 | 37 |
| EVB | AP | 4132 | 23 | 22 | 21 | 20 | 19 | 18 | 17 | 16 | 15 | 14 | 13 |
| EVB | AP | 4135 | 33 | 32 | 32 | 31 | 30 | 30 | 29 | 28 | 28 | 27 | 26 |
| EVB | AP | 4140 | 35 | 34 | 34 | 33 | 33 | 32 | 32 | 31 | 31 | 30 | 29 |
| EVB | AP | 4145 | 65 | 63 | 62 | 61 | 59 | 58 | 57 | 56 | 55 | 54 | 53 |
| EVB | AP | 4160 | 41 | 40 | 40 | 40 | 39 | 39 | 38 | 38 | 38 | 37 | 37 |
| EVB | AP | 4165 | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| EVB | AP | 4190 | 90 | 89 | 88 | 87 | 86 | 85 | 84 | 83 | 82 | 81 | 80 |
| EVB | AP RU | 5105 | 32 | 31 | 31 | 30 | 29 | 29 | 28 | 27 | 26 | 26 | 25 |
| EVB | AP S | 4215 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | 0 |
| EVB | AP S | 4225 | 100 | 98 | 97 | 96 | 95 | 94 | 93 | 92 | 91 | 90 | 89 |
| EVB | AP SE | 4220 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |



| 1 | 1 | /1 | 7 | 12 | Λ | 7 | 7 |
|---|---|----|---|----|---|---|---|
| | | / | • | ΙL | " | L | L |

Page 1 of 11

Pavement Database: FDOT

| Network: 1 | NEW SMY | YRNA BEA | Branch: APR | .U | RUN- | UP APRON | Section | : 5105 | Surface:AC |
|----------------------|---------------|--------------|-------------------|---------|-------|-------------------|-------------------|----------------|-------------------------------------|
| L.C.D. 1/1/19 | 943 Us | se: APRON | Rank: P | Length: | 325 | .00 (Ft) V | Vidth: 150 | 0.00 (Ft) | True Area: 46282.00001 (SqFt |
| Work Date | Work Code | Work | Description | Co | st | Thickness (in) | Major M&R | | Comments |
| 1/1/1943 | NU-IN | New Construc | ction - Initial | | 0.00 | 0.0 | | | |
| | | | | | | | | | |
| Network: 1 | NEW SMY | YRNA BEA | Branch: AP S | | SOUT | H APRON | | 1: 4215 | Surface:PCC |
| L.C.D. 1/1/19 | 943 Us | se: APRON | Rank: P | Length: | 585 | .00 (Ft) V | Vidth: 96 | 5.00 (Ft) | True Area: 56450.00001 (SqFt |
| Work Date | Work Code | Work | Description | Co | st | Thickness (in) | Major M&R | | Comments |
| 1/1/1943 | NU-IN | New Construc | ction - Initial | | 0.00 | 0.0 | | | |
| | | | | | | | | | |
| Network: | NEW SMY | YRNA BEA | Branch: AP S | | SOUT | H APRON | Section | : 4225 | Surface:PCC |
| L.C.D. 12/1/2 | 2020 Us | se: APRON | Rank: P | Length: | 540 | .00 (Ft) V | Vidth: 80 | 0.00 (Ft) | True Area: 44991.00001 (SqFt |
| Work Date | Work | Work | Description | Co | | Thickness | Major | | Comments |
| | Code | | • | | | (in) | M&R | | Comments |
| 12/1/2020 | NC-PC | New Construc | ction - PCC | | 0.00 | 0.0 | | | |
| N. d. I. I | VIEW CN | ZDNIA DE A | D 1 4DG | Г | COLUE | HEACT AD | g .: | 4220 | C & DCC |
| | | YRNA BEA | Branch: AP S | | | HEAST AP | | 4220 | Surface:PCC |
| L.C.D. 12/25 | | se: APRON | Rank: P | Length: | 3/5 | | | | True Area: 8835.000002 (SqFt |
| Work Date | Work Code | Work | Description | Co | st | Thickness (in) | Major M&R | | Comments |
| 12/25/1999 | NU-IN | New Construc | ction - Initial | | 0.00 | 0.0 | 0 | | |
| | | | | | | | | | |
| Network: | NEW SMY | YRNA BEA | Branch: AP | | APRO | N | Section | : 4102 | Surface:PCC |
| L.C.D. 1/1/19 | 984 Us | se: APRON | Rank: P | Length: | 110 | .00 (Ft) V | Vidth: 187 | 7.00 (Ft) | True Area: 20539.00000 (SqFt |
| Work Date | Work | Work | Description | Co | ost | Thickness | | | Comments |
| 1/1/1984 | Code NU-IN | New Construc | • | | 0.00 | (in) 0.0 | M&R 0 ✓ | | Comments |
| 1/1/1964 | NU-IN | New Construc | zuon - initiai | | 0.00 | 0.0 | | | |
| Network: | NEW SMY | YRNA BEA | Branch: AP | | APRO | N | Section | • 4103 | Surface: AC |
| L.C.D. 4/1/20 | | se: APRON | Rank: P | Length: | | | | | True Area: 9336.000002 (SqFt |
| E.C.D. 4/1/20 | Work | | | Length. | | Thickness | | _ ` ′ | 11uc Arca. 7550.000002 (Sqr t |
| Work Date | Code | Work | Description | Co | st | (in) | M&R | | Comments |
| 4/1/2022 | CR-AC | Complete Rec | construction - AC | , | 0.00 | 0.0 | 0 | 4" P- | 401, 6" P-211 |
| 1/1/1984 | NU-IN | New Construc | ction - Initial | | 0.00 | 0.0 | 0 | | |
| | | | | | | | | | |
| Network: | | | Branch: AP | | APRO | | Section | | Surface:AC |
| L.C.D. 1/1/19 | | se: APRON | Rank: P | Length: | 52 | . , | | .00 (Ft) | True Area: 3872.000001 (SqFt |
| Work Date | Work Code | Work | Description | Co | st | Thickness (in) | Major M&R | | Comments |
| 1/1/1984 | NU-IN | New Construc | ction - Initial | | 0.00 | 0.0 | | | |
| | | | | | | | | | |
| Network: | NEW SMY | YRNA BEA | Branch: AP | | APRO | N | Section | : 4105 | Surface:PCC |
| L.C.D. 1/1/19 | 065 Us | se: APRON | Rank: P | Length: | 72 | .00 (Ft) V | Vidth: 50 | 0.00 (Ft) | True Area: 6440.000001 (SqFt |
| | Work | Wast | | | | Thickness | | _ ` ′ | ``` |
| Work Date | Code | | Description | Co | | (in) | M&R | | Comments |
| 1/1/1965 | NU-IN | New Construc | ction - Initial | | 0.00 | 0.0 | | | |

| 1 | 1 | /1 | 7 | 12 | Λ | 1 | 1 |
|---|----|----|-----|----|---|---|-----|
| | н. | / | - / | ΙZ | " | Z | · Z |

Page 2 of 11

Pavement Database: FDOT

| Network: | NEW SMY | YRNA BEA Branch: AP | APRO | N | Section: 410 | O6 Surface:PCC |
|---|--|--|------------------|--|--|--|
| L.C.D. 12/1/2 | 2020 Us | se: APRON Rank: P | Length: 118 | 3.00 (Ft) Wid | lth: 30.00 (1 | Ft) True Area: 3540.000001 (SqFt |
| W. I D. | Work | W. J. D | Cont | Thickness | Major | Comments |
| Work Date | Code | Work Description | Cost | (in) | M&R | Comments |
| 12/1/2020 | CR-PC | Complete Reconstruction - Po | | | | |
| 1/1/1965 | NU-IN | New Construction - Initial | 0.00 | 0.00 | V | |
| Ni.d I . | NEW CM | VDNA DEA - Doorde AD | A DD O | NI. | C - 4 414 | 07 G GA.C |
| | | YRNA BEA Branch: AP | APRO | | Section: 410 | |
| L.C.D. 12/1/2 | Work | se: APRON Rank: P | Length: 160 | 7.00 (Ft) Wid Thickness | | Ft) True Area: 12117.00000 (SqFt |
| Work Date | Code | Work Description | Cost | (in) | Major M&R | Comments |
| 12/1/2020 | NC-AC | New Construction - AC | 0.00 | 0.00 | V : | |
| | | | | | - | |
| Network: | NEW SMY | YRNA BEA Branch: AP | APRO | N | Section: 410 | O8 Surface:PCC |
| L.C.D. 12/1/2 | 2020 Us | se: APRON Rank: P | Length: 97 | 7.00 (Ft) Wid | lth: 85.00 (| Ft) True Area: 8757.000002 (SqFt |
| Work Date | Work | Work Description | Cost | Thickness | Major Med | Comments |
| 12/1/2020 | Code NC-PC | New Construction - PCC | 0.00 | (in) 0.00 | M&R | |
| 12/1/2020 | 1,616 | The Wilder Compared C | 3,00 | 0.00 | V | |
| Network: | NEW SMY | YRNA BEA Branch: AP | APRO | N | Section: 41 | 10 Surface:PCC |
| L.C.D. 1/1/19 | 980 Us | se: APRON Rank: P | Length: 75 | 5.00 (Ft) Wi d | lth: 25.00 (| Ft) True Area: 1950.000000 (SqFt |
| W I D (| Work | W ID '' | _ | Thickness | Major | , , , |
| Work Date | Code | Work Description | Cost | (in) | M&R | Comments |
| 1/1/1980 | NU-IN | New Construction - Initial | 0.00 | 0.00 | V | |
| | | | | | | |
| | NEW CM | ZDNA DEA B I AB | A DD O | NI. | G 41 41 | as a suppose |
| | | YRNA BEA Branch: AP | APRO | | Section: 41 | |
| Network: L.C.D. 1/1/19 | 975 Us | YRNA BEA Branch: AP se: APRON Rank: P | | .00 (Ft) Wi c | lth: 48.00 (1 | Surface:PCC Ft) True Area: 8775.000002 (SqFt |
| | | | | | | |
| L.C.D. 1/1/1 | 975 Us Work Code | se: APRON Rank: P | Length: 140 | Thickness (in) | 1th: 48.00 (1 | Ft) True Area: 8775.000002 (SqFt |
| L.C.D. 1/1/19 Work Date | 975 Us Work Code | we: APRON Rank: P Work Description | Length: 140 | Thickness (in) | Major M&R | Ft) True Area: 8775.000002 (SqFt |
| L.C.D. 1/1/19 Work Date 1/1/1975 | 975 Us Work Code NU-IN | we: APRON Rank: P Work Description | Length: 140 | Thickness (in) | Major M&R | Ft) True Area: 8775.000002 (SqFt Comments |
| L.C.D. 1/1/19 Work Date 1/1/1975 | Work Code NU-IN | Work Description New Construction - Initial | Cost O.00 APRO | Thickness (in) 0.00 | Major M&R Section: 412 | Ft) True Area: 8775.000002 (SqFt Comments |
| L.C.D. 1/1/19 Work Date 1/1/1975 Network: | Work Code NU-IN NEW SMY 002 Us | Work Description New Construction - Initial YRNA BEA Branch: AP See: APRON Rank: P | Cost | Thickness (in) 0.00 (Ft) Wid 0.00 N 0.00 (Ft) Wid Thickness | Major M&R Section: 412 Ith: 25.00 (1) Major | Comments 20 Surface: PCC Ft) True Area: 14180.00000 (SqFt |
| L.C.D. 1/1/19 Work Date 1/1/1975 Network: L.C.D. 1/1/20 Work Date | Work Code NU-IN NEW SMY 002 Us Work Code | Work Description New Construction - Initial YRNA BEA Branch: AP See: APRON Rank: P Work Description | Cost | Thickness (in) 0.00 (Ft) Wid 0.00 (Ft) Wid Thickness (in) | Major M&R Section: 412 Ith: 25.00 (1) Major M&R | Comments Surface:PCC |
| L.C.D. 1/1/19 Work Date 1/1/1975 Network: L.C.D. 1/1/29 Work Date 1/1/2002 | Work Code NU-IN NEW SMY 002 Us Work Code OL-PC | Work Description New Construction - Initial YRNA BEA Branch: AP See: APRON Rank: P | Cost | Thickness (in) 0.00 (Ft) Wide Thickness (in) 0.00 Thickness (in) 0.00 | Major M&R | Comments 20 Surface: PCC Ft) True Area: 14180.00000 (SqFt |
| L.C.D. 1/1/19 Work Date 1/1/1975 Network: L.C.D. 1/1/20 Work Date | Work Code NU-IN NEW SMY 002 Us Work Code | Work Description New Construction - Initial WRNA BEA Branch: AP See: APRON Rank: P Work Description Overlay - PCC | Cost | Thickness (in) 0.00 (Ft) Wid 0.00 (Ft) Wid Thickness (in) | Major M&R Section: 412 Ith: 25.00 (1) Major M&R | Comments 20 Surface: PCC Ft) True Area: 14180.00000 (SqFt |
| Network: L.C.D. 1/1/19 Network: L.C.D. 1/1/20 Work Date 1/1/2002 1/1/1997 | Work Code NU-IN NEW SMY 002 Work Code OL-PC NU-IN | Work Description New Construction - Initial WRNA BEA Branch: AP See: APRON Rank: P Work Description Overlay - PCC | Cost | 0.00 (Ft) Wide Thickness (in) 0.00 ON 0.00 (Ft) Wide Thickness (in) 0.00 0.00 | Major M&R | Comments 20 Surface:PCC Ft) True Area: 14180.00000 (SqFt Comments |
| Network: L.C.D. 1/1/19 Network: L.C.D. 1/1/20 Work Date 1/1/2002 1/1/1997 | Work Code NU-IN NEW SMY 002 Us Work Code OL-PC NU-IN | Work Description New Construction - Initial WRNA BEA Branch: AP Ree: APRON Rank: P Work Description Overlay - PCC New Construction - Initial | Cost | 0.00 (Ft) Wide Thickness (in) 0.00 ON Thickness (in) 0.00 ON | Major M&R | Comments 20 Surface:PCC Ft) True Area: 14180.00000 (SqFt Comments 21 Surface:PCC |
| L.C.D. 1/1/19 Work Date 1/1/1975 Network: L.C.D. 1/1/2 Work Date 1/1/2002 1/1/1997 Network: L.C.D. 1/1/24 | Work Code NU-IN NEW SMY 002 Us Work Code OL-PC NU-IN | Work Description New Construction - Initial WRNA BEA Branch: AP See: APRON Rank: P Work Description Overlay - PCC New Construction - Initial WRNA BEA Branch: AP See: APRON Rank: P | Cost | 0.00 (Ft) Wide Thickness (in) 0.00 ON 0.00 (Ft) Wide Thickness (in) 0.00 0.00 | Major M&R | Comments 20 Surface:PCC Ft) True Area: 14180.00000 (SqFt Comments 21 Surface:PCC Ft) True Area: 12650.00000 (SqFt |
| L.C.D. 1/1/19 Work Date 1/1/1975 Network: L.C.D. 1/1/20 Work Date 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date | Work Code NU-IN NEW SMY 002 Us Work Code OL-PC NU-IN NEW SMY 002 Us Work Code OK-PC NU-IN | Work Description New Construction - Initial YRNA BEA Branch: AP Se: APRON Rank: P Work Description Overlay - PCC New Construction - Initial YRNA BEA Branch: AP se: APRON Rank: P Work Description | Cost | 0.00 (Ft) Wide Thickness (in) 0.00 | Major M&R | Comments 20 Surface:PCC Ft) True Area: 14180.00000 (SqFt Comments 21 Surface:PCC |
| L.C.D. 1/1/19 Work Date 1/1/1975 Network: L.C.D. 1/1/20 Work Date 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date 1/1/2002 | Work Code NU-IN NEW SMY 002 Us Work Code OL-PC NU-IN NEW SMY 002 Us Work Code OL-PC | Work Description New Construction - Initial WRNA BEA Branch: AP Ree: APRON Rank: P Work Description Overlay - PCC New Construction - Initial WRNA BEA Branch: AP Ree: APRON Rank: P Work Description Overlay - PCC | Cost | 7.00 (Ft) Wich Thickness (in) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0. | Major M&R | Comments 20 Surface:PCC Ft) True Area: 14180.00000 (SqFt Comments 21 Surface:PCC Ft) True Area: 12650.00000 (SqFt |
| Network: L.C.D. 1/1/20 Work Date 1/1/1975 Network: L.C.D. 1/1/20 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date | Work Code NU-IN NEW SMY 002 Us Work Code OL-PC NU-IN NEW SMY 002 Us Work Code OK-PC NU-IN | Work Description New Construction - Initial YRNA BEA Branch: AP Se: APRON Rank: P Work Description Overlay - PCC New Construction - Initial YRNA BEA Branch: AP se: APRON Rank: P Work Description | Cost | 0.00 (Ft) Wide Thickness (in) 0.00 | Major M&R | Comments 20 Surface:PCC Ft) True Area: 14180.00000 (SqFt Comments 21 Surface:PCC Ft) True Area: 12650.00000 (SqFt |

| 1 | 1 | /1 | 7 | 12 | Λ | 1 | 1 |
|---|----|----|-----|----|---|---|-----|
| | н. | / | - / | ΙZ | " | Z | · Z |

Page 3 of 11

Pavement Database: FDOT

| | | Pavement Data | base: | FDOT | | | | |
|---------------------|--------------|--------------------------------------|-------|-------------|-------------------|--------------|----------------------|-------------------------------------|
| Network: | NEW SM | YRNA BEA Branch: A | ĄΡ | APRO | N | Section: 4 | 4124 | Surface:PCC |
| L.C.D. 1/1/2 | | se: APRON Rank: P | | | | | | True Area: 6450.000001 (SqFt |
| Work Date | Work Code | Work Description | | Cost | Thickness (in) | Major M&R | , | Comments |
| 1/1/2002 | CR-PC | Complete Reconstruction | - PCC | 0.00 | 0.00 | V : | | |
| 1/1/1997 | NU-IN | New Construction - Initial | | 0.00 | 0.00 | V | | |
| | | | | | | | | |
| | | YRNA BEA Branch : A | | APRO | | Section: | | Surface:PCC |
| L.C.D. 1/1/2 | | se: APRON Rank: P | L | ength: 100 | , , | 1 | 0 (Ft) | True Area: 17693.00000 (SqFt |
| Work Date | Work Code | Work Description | | Cost | Thickness (in) | Major M&R | | Comments |
| 1/1/2002 | OL-PC | Overlay - PCC | | 0.00 | 0.00 | V | | |
| 1/1/1997 | NU-IN | New Construction - Initial | | 0.00 | 0.00 | V | | |
| N | | TOTAL DEL | | | N.T. | g :• | 410 : | 0.0.00 |
| | | YRNA BEA Branch: A | | APRO | | Section: | | Surface:PCC |
| L.C.D. 1/1/2 | Work | se: APRON Rank: P | L | ength: 250 | .00 (Ft) Wid | 1 | 0 (Ft) | True Area: 12548.00000 (SqFt |
| Work Date | Code | Work Description | | Cost | (in) | Major M&R | | Comments |
| 1/1/2002 | OL-PC | Overlay - PCC | | 0.00 | 0.00 | V | | |
| 1/1/1997 | NU-IN | New Construction - Initial | | 0.00 | 0.00 | | | |
| N . | NEW CLO | WINDER DE L | | 4 PD 6 | N.T. | G .: | 4105 | G & DGG |
| | | YRNA BEA Branch: A | | APRO | | Section: | | Surface:PCC |
| L.C.D. 1/1/2 | Work | se: APRON Rank: P | L | ength: 102 | .00 (Ft) Wio | | J (Ft) | True Area: 1560.000000 (SqFt |
| Work Date | Code | Work Description | | Cost | (in) | Major M&R | | Comments |
| 1/1/2019 | CR-PC | Complete Reconstruction - | | 0.00 | 0.00 | \ | | |
| 1/1/1997 | NU-IN | New Construction - Initial | | 0.00 | 0.00 | V | | |
| Notrocale | NEW CMS | YRNA BEA Branch: A | ı D | APRO | NT. | Section: | 4120 | Surface:PCC |
| L.C.D. 12/1/ | | YRNA BEA Branch: A se: APRON Rank: P | | | | | | True Area: 6565.000002 (SqFt |
| | Work | Se. AFRON Kalik, F | L | engui. 101 | Thickness | Major | J (1 ⁻ 1) | True Area. 0303.000002 (Sqrt |
| Work Date | Code | Work Description | | Cost | (in) | M&R | | Comments |
| 12/1/2020 | NC-PC | New Construction - PCC | | 0.00 | 0.00 | V | | |
| | | | | | | | | |
| | | YRNA BEA Branch: A | | APRO | | Section: | | Surface:PCC |
| L.C.D. 12/1/ | | se: APRON Rank: P | L | ength: 90 | . , | | 0 (Ft) | True Area: 2070.000000 (SqFt |
| Work Date | Work Code | Work Description | | Cost | Thickness (in) | Major M&R | | Comments |
| 12/1/2020 | NC-PC | New Construction - PCC | | 0.00 | 0.00 | | | |
| | | | | | | | | |
| | | YRNA BEA Branch: A | | APRO | | Section: | | Surface:PCC |
| L.C.D. 1/1/1 | 997 Us | se: APRON Rank: P | L | ength: 100 | .00 (Ft) Wie | dth: 245.00 | 0 (Ft) | True Area: 23150.00000 (SqFt |
| | 1 | , contract number | | Cligan. 100 | ` ' | 1 | | |
| Work Date | Work Code | Work Description | | Cost | Thickness (in) | Major M&R | | Comments |

| 1 | 1 | /1 | 7 | 12 | Λ | 1 | 1 |
|---|----|----|-----|----|---|---|-----|
| | н. | / | - / | ΙZ | " | Z | · Z |

Page 4 of 11

Pavement Database: FDOT

| Network: | NEW SM | YRNA BEA | Branch: AP | | APRO | N | Se | ction: 4 | 1132 | | Surface:PCC |
|--|--|--|---|---------|---|--|--|--|--------------|-----------------|--|
| L.C.D. 1/1/19 | 997 Us | se: APRON | Rank: P | Length: | 55 | .00 (Ft) V | Vidth: | 340.00 | (Ft) | True Area: | 17074.00000 (SqFt |
| W I D (| Work | *** 1 | D | | | Thickness | M | ajor | | | , |
| Work Date | Code | | Description | C | ost | (in) | M | &R | | Comn | nents |
| 1/1/1997 | NU-IN | New Constru | ction - Initial | | 0.00 | 0.0 | 0 | / : | | | |
| | | | | | | | - | | | | |
| | | YRNA BEA | Branch: AP | | APRO | | | ction: 4 | | | Surface:AC |
| L.C.D. 1/1/1 | | se: APRON | Rank: P | Length: | 88 | . , | Vidth: | | (Ft) | True Area: | 4290.000001 (SqFt |
| Work Date | Work Code | Work | Description | C | ost | Thickness (in) | | ajor &R | | Comn | nents |
| 1/1/1975 | | New Constru | ction - Initial | | 0.00 | 0.0 | | 7 | | | |
| | | | | | | | | | | | |
| Network: | NEW SM | YRNA BEA | Branch: AP | | APRO | N | Se | ction: 4 | 140 | | Surface:AC |
| L.C.D. 1/1/19 | 980 Us | se: APRON | Rank: P | Length: | 930 | .00 (Ft) V | Vidth: | 40.00 | (Ft) | True Area: | 37036.00001 (SqFt |
| Work Date | Work | Work | Description | C | ost | Thickness | | ajor | | Comn | nents |
| | Code | New Constru | | | | (in) | _ | &R | | Comin | nents |
| 1/1/1980 | NU-IN | New Constru | ction - Initial | | 0.00 | 0.0 | | | | | |
| Notwork: | NEW CM | YRNA BEA | Branch: AP | | APRO | N | C - | ction: 4 | 11/15 | | Surface:AC |
| | | | | T | | | | | | T A | |
| L.C.D. 1/1/19 | Work | se: APRON | Rank: P | Length: | 300 | .00 (Ft) V | Vidth: | | (Ft) | True Area: | 17888.00000 (SqFt |
| Work Date | Code | Work | Description | C | ost | (in) | | ajor &R | | Comn | nents |
| 1/1/1986 | NU-IN | New Constru | ction - Initial | | 0.00 | 0.0 | 0 | / : | | | |
| | | | | | | | | | | | |
| Network: | NEW SM | YRNA BEA | Branch: AP | | APRO | N | Se | ction: 4 | 150 | | Surface:PCC |
| L.C.D. 1/1/2 | 002 Us | | | | | | | | | | |
| | | se: APRON | Rank: P | Length: | 903 | .00 (Ft) V | Vidth: | 50.00 | (Ft) | True Area: | 45150.00001 (SqFt |
| Work Date | Work | | Rank: P Description | | 903 ost | Thickness | M | ajor | (Ft) | True Area: | \ \ 1 |
| | Code | Work | Description | | ost | Thickness (in) | M M | ajor [&R | (Ft) | | \ \ 1 |
| Work Date 1/1/2002 1/1/1997 | | | Description | | | Thickness | M M | ajor &R | (Ft) | | \ \ 1 |
| 1/1/2002 | Code OL-PC | Work Overlay - PC | Description | | 0.00 | Thickness (in) | M M | ajor [&R | (Ft) | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| 1/1/2002 1/1/1997 | Code OL-PC NU-IN | Work Overlay - PC | Description | | 0.00 | Thickness (in) 0.0 0.0 | M M 0 | ajor &R | | | \ \ 1 |
| 1/1/2002 1/1/1997 | Code OL-PC NU-IN NEW SM | Work Overlay - PC New Constru | Description C ction - Initial | | 0.00 0.00 APRO | Thickness (in) 0.0 0.0 | See | ajor &R | 1154 | Comn | nents Surface:PCC |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/2 | Code OL-PC NU-IN NEW SM 002 Us Work | Work Overlay - PC New Constru YRNA BEA se: APRON | Description C ction - Initial Branch: AP Rank: P | Co | 0.00 0.00 APRO | Thickness (in) 0.0 0.0 | See Vidth: | ajor &R | 1154 | Comm | Surface:PCC 7400.000002 (SqFt |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date | Code OL-PC NU-IN NEW SMY 002 Us Work Code | Work Overlay - PC New Constru YRNA BEA se: APRON Work | Description C ction - Initial Branch: AP Rank: P Description | Co | 0.00 0.00 APRO 148 | Thickness (in) 0.0 0.0 N .00 (Ft) V Thickness (in) | Seevidth: | ajor &R | 1154 | Comn | Surface:PCC 7400.000002 (SqFt |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date 1/1/2002 | Code OL-PC NU-IN NEW SM 002 Us Work Code OL-PC | Work Overlay - PC New Constru YRNA BEA se: APRON Work Overlay - PC | Description C ction - Initial Branch: AP Rank: P Description C | Co | 0.00 0.00 0.00 APRO 148 0st | Thickness (in) 0.0 0.0 N .00 (Ft) V Thickness (in) 0.0 | See Width: | ajor d&R del del | 1154 | Comm | Surface:PCC 7400.000002 (SqFt |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date | Code OL-PC NU-IN NEW SMY 002 Us Work Code | Work Overlay - PC New Constru YRNA BEA se: APRON Work | Description C ction - Initial Branch: AP Rank: P Description C | Co | 0.00 0.00 APRO 148 | Thickness (in) 0.0 0.0 N .00 (Ft) V Thickness (in) | See Width: | ajor &R | 1154 | Comm | Surface:PCC 7400.000002 (SqFt |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date 1/1/2002 1/1/1997 | OL-PC NU-IN NEW SM 002 Us Work Code OL-PC NU-IN | Work Overlay - PC New Constru YRNA BEA se: APRON Work Overlay - PC New Constru | Description C ction - Initial Branch: AP Rank: P Description C ction - Initial | Co | 0.00 0.00 0.00 APRO 148 0st 0.00 0.00 | Thickness (in) 0.0 0.0 N .00 (Ft) V Thickness (in) 0.0 0.0 | See Vidth: | ajor &R ction: 4 50.00 ajor &R | 1154 (Ft) | Comm | Surface:PCC 7400.000002 (SqFt |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/2 Work Date 1/1/2002 1/1/1997 Network: | Code OL-PC NU-IN NEW SM' 002 Us Work Code OL-PC NU-IN | Work Overlay - PC New Constru YRNA BEA se: APRON Work Overlay - PC New Constru | Description C ction - Initial Branch: AP Rank: P Description C ction - Initial Branch: AP | Length: | 0.00 0.00 APRO 148 0st 0.00 0.00 | Thickness (in) 0.0 0.0 N | See Vidth: See See See See See See See See See Se | ajor (&R) ction: 4 50.00 ajor (&R) | H154 (Ft) | Comm | Surface:PCC 7400.000002 (SqFt nents |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date 1/1/2002 1/1/1997 | Code OL-PC NU-IN NEW SMY 002 Us Work Code OL-PC NU-IN NEW SMY 002 Us | Work Overlay - PC New Constru YRNA BEA se: APRON Work Overlay - PC New Constru YRNA BEA se: APRON | Description C ction - Initial Branch: AP Rank: P Description C ction - Initial Branch: AP Rank: P | Co | 0.00 0.00 APRO 148 0st 0.00 0.00 | Thickness (in) 0.0 0.0 N | See Vidth: | ajor &R ction: 4 50.00 ajor &R ction: 4 50.00 | H154 (Ft) | Comm | Surface:PCC 7400.000002 (SqFt nents |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/2 Work Date 1/1/2002 1/1/1997 Network: | Code OL-PC NU-IN NEW SM' 002 Us Work Code OL-PC NU-IN | Work Overlay - PC New Constru YRNA BEA se: APRON Work Overlay - PC New Constru YRNA BEA se: APRON | Description C ction - Initial Branch: AP Rank: P Description C ction - Initial Branch: AP | Length: | 0.00 0.00 APRO 148 0st 0.00 0.00 | Thickness (in) 0.0 0.0 N | See Vidth: | ajor (&R) ction: 4 50.00 ajor (&R) | H154 (Ft) | Comm | Surface:PCC 7400.000002 (SqFt nents Surface:PCC 3500.000001 (SqFt |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/2 Work Date 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 | Code OL-PC NU-IN NEW SMY 002 Us Work Code OL-PC NU-IN NEW SMY 002 Us Work | Work Overlay - PC New Constru YRNA BEA se: APRON Work Overlay - PC New Constru YRNA BEA se: APRON | Description C ction - Initial Branch: AP Rank: P Description C ction - Initial Branch: AP Rank: P Description | Length: | 0.00 0.00 0.00 APRO 148 0.00 0.00 APRO 70 | Thickness (in) 0.0 0.0 N .00 (Ft) V Thickness (in) 0.0 N .00 (Ft) V Thickness (in) 0.0 | See Vidth: See Vidth: See Vidth: | ajor &R ction: 4 50.00 ajor &R ction: 4 50.00 ajor ajor &R | H154 (Ft) | True Area: Comm | Surface:PCC 7400.000002 (SqFt nents Surface:PCC 3500.000001 (SqFt |
| 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date 1/1/2002 1/1/1997 Network: L.C.D. 1/1/20 Work Date | NEW SMY OL-PC NU-IN Work Code OL-PC NU-IN NEW SMY O02 Us Work Code OK-PC NU-IN | Work Overlay - PC New Constru YRNA BEA se: APRON Work Overlay - PC New Constru YRNA BEA se: APRON Work Work | Description C ction - Initial Branch: AP Rank: P Description C ction - Initial Branch: AP Rank: P Description C | Length: | 0.00 0.00 APRO 148 0.00 0.00 APRO 70 0st | Thickness (in) 0.0 0.0 N .00 (Ft) V Thickness (in) 0.0 N .00 (Ft) V Thickness (in) | See Vidth: See Vidth: See MM MO See Vidth: See MM MO See Vidth: See MM | ajor &R ction: 4 50.00 ajor &R ction: 4 50.00 ajor &R | H154 (Ft) | True Area: Comm | Surface:PCC 7400.000002 (SqFt nents Surface:PCC 3500.000001 (SqFt |

Page 5 of 11

Pavement Database: FDOT

| Network: | NEW SM | YRNA BEA | Branch: AP | APRO | N | Section: | 4160 Surface:AC |
|--|---|---|---|--|---|---|---|
| L.C.D. 1/1/1 | | se: APRON | | | | | 0 (Ft) True Area: 10001.00000 (SqFt |
| L.C.D. 1/1/1 | | Se. AFRON | Kalik, F I | Tengui. 23 | ` ′ | - | (Ft) True Area: 10001.00000 (Sqrt |
| Work Date | Work Code | Work | Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1975 | | New Construc | ction - AC | 0.00 | 0.00 | V | |
| 1/1/19/3 | ne ne | riew construc | thon 71C | 0.00 | 0.00 | | |
| N | NIEW CM | ZDNIA DEA | D 1 4D | 4 DD O | N T | G | 41/5 G C DOG |
| Network: | NEW SM | YRNA BEA | Branch: AP | APRO | | Section: | 4165 Surface:PCC |
| L.C.D. 1/1/1 | 991 Us | se: APRON | Rank: P I | ength: 228 | .00 (Ft) Wie | dth: 40.0 | 0 (Ft) True Area: 9517.000002 (SqFt |
| Work Date | Work | Work | Description | Cost | Thickness | Major | Comments |
| | Code | | | | (in) | M&R | Comments |
| 1/1/1991 | NU-IN | New Construc | ction - Initial | 0.00 | 0.00 | V | |
| | | | | | | | |
| Network: | NEW SM | YRNA BEA | Branch: AP | APRO | N | Section: | 4190 Surface:PCC |
| L.C.D. 1/1/2 | 012 Us | se: APRON | Rank: P I | ength: 1,025 | .00 (Ft) Wie | dth: 30.0 | 0 (Ft) True Area: 38656.00001 (SqFt |
| W. I D. | Work | XX 71 | D | Cont | Thickness | Major | G |
| Work Date | Code | Work | Description | Cost | (in) | M&R | Comments |
| 1/1/2012 | NU-IN | New Construc | ction - Initial | 0.00 | 0.00 | < | |
| | J | | | | | | |
| Network: | NEW SM | YRNA BEA | Branch: RW 11 | -29 RUNV | VAY 11-29 | Section: | 6105 Surface:AAC |
| L.C.D. 1/1/2 | 014 Us | se: RUNWAY | Rank: P I | ength: 4,319 | .00 (Ft) Wie | dth: 75.0 | 0 (Ft) True Area: 323925.0000 (SqFt |
| | Work | | | | Thickness | Major | · · · |
| Work Date | Code | Work | Description | Cost | (in) | M&R | Comments |
| 1/1/2014 | ML-OVL | Mill and Over | rlay | 0.00 | 0.00 | V : | VARIABLE MILL (CORRECT GRA |
| 1/1/1977 | NU-IN | New Construc | ction - Initial | 0.00 | 0.00 | | |
| | | | citon - minai | 0.00 | 0.00 | | |
| | | | ction - initial | 0.00 | 0.00 | | |
| Network: | NEW SM | | | | | | 6405 Surface: AC |
| | | YRNA BEA | Branch: RW 2- | 20 RUNV | VAY 2-20 | Section: | |
| Network: L.C.D. 1/1/1 | 943 Us | | Branch: RW 2- | 20 RUNV | VAY 2-20 .00 (Ft) Wi o | Section: | 6405 Surface: AC 0 (Ft) True Area: 78400.00002 (SqFt |
| | 943 Us Work | YRNA BEA se: RUNWAY | Branch: RW 2- | 20 RUNV | VAY 2-20 .00 (Ft) Wid | Section: dth: 100.00 | |
| L.C.D. 1/1/19 Work Date | 943 Us Work Code | YRNA BEA se: RUNWAY Work | Branch: RW 2- Rank: P I | 20 RUNV ength: 850 | VAY 2-20 .00 (Ft) Wid Thickness (in) | Section: dth: 100.00 Major M&R | 0 (Ft) True Area: 78400.00002 (SqFt |
| L.C.D. 1/1/1 | 943 Us Work | YRNA BEA se: RUNWAY | Branch: RW 2- Rank: P I | 20 RUNV | VAY 2-20 .00 (Ft) Wid | Section: dth: 100.00 | 0 (Ft) True Area: 78400.00002 (SqFt |
| L.C.D. 1/1/19 Work Date 1/1/1943 | 943 Us Work Code NU-IN | YRNA BEA se: RUNWAY Work New Construct | Branch: RW 2- Rank: P I Description | 20 RUNV ength: 850 Cost 0.00 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 | Section: dth: 100.00 Major M&R | 0 (Ft) True Area: 78400.00002 (SqFt Comments |
| L.C.D. 1/1/19 Work Date 1/1/1943 Network: | 943 Use Work Code NU-IN | YRNA BEA se: RUNWAY Work New Construct YRNA BEA | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- | 20 RUNV ength: 850 Cost 0.00 20 RUNV | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 | Section: dth: 100.00 Major M&R Section: | 0 (Ft) True Area: 78400.00002 (SqFt Comments 6425 Surface: AC |
| L.C.D. 1/1/19 Work Date 1/1/1943 | 943 Us Work Code NU-IN NEW SMY 943 Us | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid | Section: dth: 100.00 Major M&R Section: dth: 100.00 | 0 (Ft) True Area: 78400.00002 (SqFt Comments |
| L.C.D. 1/1/19 Work Date 1/1/1943 Network: | 943 Us Work Code NU-IN NEW SMY 943 Us Work | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major | 0 (Ft) True Area: 78400.00002 (SqFt Comments 6425 Surface: AC |
| Work Date 1/1/1943 Network: L.C.D. 1/1/1 Work Date | 943 Us Work Code NU-IN NEW SM 943 Us Work Code | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work | Branch: RW 2-Rank: P I Description ction - Initial Branch: RW 2-Rank: P I Description | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R | 0 (Ft) True Area: 78400.00002 (SqFt Comments 6425 Surface:AC 0 (Ft) True Area: 254789.0000 (SqFt |
| Work Date 1/1/1943 Network: L.C.D. 1/1/1 | 943 Us Work Code NU-IN NEW SMY 943 Us Work | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY | Branch: RW 2-Rank: P I Description ction - Initial Branch: RW 2-Rank: P I Description | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major | 0 (Ft) True Area: 78400.00002 (SqFt Comments 6425 Surface:AC 0 (Ft) True Area: 254789.0000 (SqFt |
| Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/1943 | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work New Construct | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 | VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R | 0 (Ft) True Area: 78400.00002 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments |
| Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/1943 | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work | Branch: RW 2-Rank: P I Description ction - Initial Branch: RW 2-Rank: P I Description | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R | 0 (Ft) True Area: 78400.00002 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments |
| Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/1943 | 943 Us Work Code NU-IN NEW SM 943 Us Work Code NU-IN | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work New Construct | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: | 0 (Ft) True Area: 78400.00002 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments |
| Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/20 | 943 Us Work Code NU-IN NEW SM 943 Us Work Code NU-IN | YRNA BEA se: RUNWAY Work YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: | Comments 6425 Surface:AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface:AC 0 (Ft) True Area: 11862.00000 (SqFt |
| Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/22 Work Date | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN NEW SMY 014 Us Work Code | YRNA BEA se: RUNWAY Work YRNA BEA se: RUNWAY Work YRNA BEA Se: RUNWAY Work Work | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 Cost | VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wide Thickness (in) | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R | Comments Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface: AC 0 (Ft) True Area: 11862.00000 (SqFt Comments |
| Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/20 | 943 Us Work Code NU-IN NEW SM 943 Us Work Code NU-IN NEW SM 014 Us Work | YRNA BEA se: RUNWAY Work YRNA BEA se: RUNWAY Work YRNA BEA Se: RUNWAY Work Work | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 | VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wide Thickness (in) | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major | Comments 6425 Surface:AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface:AC 0 (Ft) True Area: 11862.00000 (SqFt |
| Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/22 Work Date | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN NEW SMY 014 Us Work Code | YRNA BEA se: RUNWAY Work YRNA BEA se: RUNWAY Work YRNA BEA Se: RUNWAY Work Work | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description construction - AC | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 Cost | VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wide Thickness (in) | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R | Comments Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface: AC 0 (Ft) True Area: 11862.00000 (SqFt Comments |
| Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/1943 Network: 1/1/1943 Network: L.C.D. 1/1/2 Work Date 1/1/2014 | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN NEW SMY 014 Us Work Code CR-AC | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work YRNA BEA se: RUNWAY Work Complete Rec | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description construction - AC | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 Cost 120 Cost 0.00 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R V | Comments Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface: AC 0 (Ft) True Area: 11862.00000 (SqFt Comments |
| Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/1943 Network: 1/1/1943 Network: L.C.D. 1/1/20 Work Date 1/1/2014 1/1/1943 | Work Code NU-IN NEW SM 943 Us Work Code NU-IN NEW SM 014 Us Work Code CR-AC NU-IN | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work YRNA BEA se: RUNWAY Work Complete Rec | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description construction - AC | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 Cost 0.00 0.00 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R V | Comments Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface: AC 0 (Ft) True Area: 11862.00000 (SqFt Comments Remove Existing Asphalt and Rework |
| Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/20 Work Date 1/1/2014 1/1/1943 Network: | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN NEW SMY 014 Us Work Code CR-AC NU-IN | WORK New Construct YRNA BEA See: RUNWAY Work New Construct YRNA BEA See: RUNWAY Work Complete Rec New Construct YRNA BEA | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description construction - AC ction - Initial | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 Cost 0.00 20 RUNV | VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: | Comments 6425 Surface:AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface:AC 0 (Ft) True Area: 11862.00000 (SqFt Comments Remove Existing Asphalt and Rework 6430 Surface:AC |
| Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/2943 Network: L.C.D. 1/1/2943 Network: L.C.D. 1/1/2943 Network: L.C.D. 1/1/1943 | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN NEW SMY 014 Us Work Code CR-AC NU-IN NEW SMY 977 Us | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work Complete Rec New Construct YRNA BEA se: RUNWAY | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description construction - AC ction - Initial Branch: RW 2- Rank: P I Branch: RW 2- Rank: P I | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 Cost 0.00 20 RUNV | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 0.00 VAY 2-20 .00 (Ft) Wid VAY 2-20 .00 (Ft) Wid | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major MdR W Section: dth: 100.00 | Comments Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6425 Surface: AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface: AC 0 (Ft) True Area: 11862.00000 (SqFt Comments Remove Existing Asphalt and Rework |
| Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/19 Work Date 1/1/1943 Network: L.C.D. 1/1/20 Work Date 1/1/2014 1/1/1943 Network: | 943 Us Work Code NU-IN NEW SMY 943 Us Work Code NU-IN NEW SMY 014 Us Work Code CR-AC NU-IN | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work Complete Rec New Construct YRNA BEA se: RUNWAY | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description construction - AC ction - Initial | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 Cost 0.00 20 RUNV | VAY 2-20 .00 (Ft) Wide Thickness (in) 0.00 VAY 2-20 | Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: dth: 100.00 Major M&R Section: | Comments 6425 Surface:AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface:AC 0 (Ft) True Area: 11862.00000 (SqFt Comments Remove Existing Asphalt and Rework 6430 Surface:AC |
| Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/1943 Network: L.C.D. 1/1/2943 Network: L.C.D. 1/1/2943 Network: L.C.D. 1/1/2943 Network: L.C.D. 1/1/1943 | 943 Use Work Code NU-IN NEW SMY 943 Use Work Code NU-IN NEW SMY 014 Use Work Code CR-AC NU-IN NEW SMY 977 Use Work | YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work New Construct YRNA BEA se: RUNWAY Work Complete Rec New Construct YRNA BEA se: RUNWAY | Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description ction - Initial Branch: RW 2- Rank: P I Description construction - AC ction - Initial Branch: RW 2- Rank: P I Description | 20 RUNV ength: 850 Cost 0.00 20 RUNV ength: 2,700 Cost 0.00 20 RUNV ength: 120 Cost 0.00 0.00 20 RUNV ength: 150 | VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 0.00 VAY 2-20 .00 (Ft) Wid Thickness (in) 0.00 0.00 VAY 2-20 .00 (Ft) Wid Thickness | Section: dth: 100.00 Major M&R Major M&R Major M&R Major M&R Major More Major More Major More Major More Major More Major | Comments 6425 Surface:AC 0 (Ft) True Area: 254789.0000 (SqFt Comments 6427 Surface:AC 0 (Ft) True Area: 11862.00000 (SqFt Comments Remove Existing Asphalt and Rework 6430 Surface:AC 0 (Ft) True Area: 5000.000001 (SqFt |

Page 6 of 11

Pavement Database: FDOT

Network: NEW SMYRNA BEA Branch: RW 2-20 RUNWAY 2-20 Section: 6435 Surface: AAC L.C.D. 1/1/2014 Use: RUNWAY Rank: P Length: 125.00 (Ft) Width: 100.00 (Ft) True Area: 12472.00000 (SqFt Work Thickness Major **Work Date** Cost **Work Description Comments** Code (in) M&R 1/1/2014 ML-OVL Mill and Overlay 0.00 0.00 VARIABLE ML&OL (FROM RW 11-1/1/1977 NU-IN New Construction - Initial 0.00 0.00 ~

Network: NEW SMYRNA BEA Branch: RW 2-20 RUNWAY 2-20 Section: 6450 Surface: AC Width: 100.00 (Ft) True Area: 25000.00000 (SqFt **L.C.D.** 1/1/1977 Use: RUNWAY Rank: P Length: 250.00 (Ft) Thickness Work Major **Work Date Work Description** Cost **Comments** Code (in) M&R 1/1/1977 NC-AC New Construction - AC 0.00 0.00

Network: NEW SMYRNA BEA Branch: RW 7-25 RUNWAY 7-25 Section: 6202 Surface: AAC L.C.D. 1/1/2008 Use: RUNWAY Rank: P 75.00 (Ft) Width: 250.00 (Ft) True Area: 18750.00000 (SqFt Length: Work Thickness Major **Work Date** Cost **Work Description Comments** Code M&R (in) 1/1/2008 ML-OVL Mill and Overlay 0.00 0.00 V 1/1/1943 NU-IN New Construction - Initial 0.00 0.00

 Network:
 NEW SMYRNA BEA
 Branch:
 RW 7-25
 RUNWAY 7-25
 Section:
 6205
 Surface:AAC

 L.C.D. 1/1/2016
 Use:
 RUNWAY
 Rank:
 P
 Length:
 4,470.00 (Ft)
 Width:
 75.00 (Ft)
 True Area:
 324750.0000 (SqFt

| Wo | ork Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|------|----------|--------------|----------------------------|------|----------------|--------------|----------|
| 1/1/ | /2016 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | < | |
| 1/1/ | /1989 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |

 Network:
 NEW SMYRNA BEA
 Branch:
 RW 7-25
 RUNWAY 7-25
 Section:
 6210
 Surface:AAC

 L.C.D. 1/1/2008
 Use:
 RUNWAY
 Rank:
 P
 Length:
 75.00 (Ft)
 Width:
 150.00 (Ft)
 True Area:
 11378.00000 (SqFt)

Thickness Work Major **Work Date Work Description** Cost Comments Code (in) M&R 1/1/2008 ML-OVL Mill and Overlay 0.00 0.00 1/1/1943 NU-IN New Construction - Initial 0.00 0.00V

 Network:
 NEW SMYRNA BEA
 Branch:
 RW 7-25
 RUNWAY 7-25
 Section:
 6215
 Surface:AAC

 L.C.D. 1/1/2016
 Use:
 RUNWAY
 Rank:
 P
 Length:
 95.00 (Ft)
 Width:
 75.00 (Ft)
 True Area:
 7125.000002 (SqFt)

Thickness Work Major **Work Date** Work Description Cost Comments Code (in) M&R 1/1/2016 ML-OVL Mill and Overlay 0.00 0.00 1/1/1943 NU-IN New Construction - Initial 0.000.00 V

 Network:
 NEW SMYRNA BEA
 Branch:
 RW 7-25
 RUNWAY 7-25
 Section:
 6220
 Surface:AAC

 L.C.D. 1/1/2016
 Use:
 RUNWAY
 Rank:
 P
 Length:
 175.00 (Ft)
 Width:
 75.00 (Ft)
 True Area:
 13125.00000 (SqFt)

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
|-----------|--------------|----------------------------|------|----------------|--------------|----------|
| 1/1/2016 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | V | |
| 1/1/1943 | NU-IN | New Construction - Initial | 0.00 | 0.00 | ~ : | |

Page 7 of 11

Pavement Database: FDOT

| | | 1 avement Database. | 1001 | | | |
|---|-------------------------------------|--|-----------------------|---------------------------------------|--------------------------|---|
| Network: N | | YRNA BEA Branch: TL T-F | HANG T-HAN | NGAR TAX | Section: | 4320 Surface:AC |
| L.C.D. 1/1/200 | | se: TAXILAN Rank: P I | ength: 1,300 | . , | | 0 (Ft) True Area: 31261.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2002 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | V | |
| Network: N | IEW SMY | YRNA BEA Branch: TL T-F | HANG T-HA | NGAR TAX | Section: | 4340 Surface:AC |
| L.C.D. 1/1/201 | 10 Us | e: TAXILAN Rank: P | ength: 340 | .00 (Ft) Wid | dth: 25.0 | 0 (Ft) True Area: 8491.000002 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2010 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |
| Network: N | IEW SMY | YRNA BEA Branch: TL T-F | HANG T-HAI | NGAR TAX | Section: | 4360 Surface:AC |
| L.C.D. 3/1/202 | 21 Us | se: TAXILAN Rank: P I | ength: 463 | .00 (Ft) Wid | dth: 22.0 | 0 (Ft) True Area: 11098.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 3/1/2021 | NC-AC | New Construction - AC | 0.00 | 0.00 | V | |
| | | | | | _ | |
| Network: N | | | | WAY A | Section: | |
| L.C.D. 1/1/201 | Work | se: TAXIWAY Rank: P I | Length: 465 | .00 (Ft) Wid | Major | 0 (Ft) True Area: 22287.00000 (SqFt |
| Work Date | Code | Work Description | Cost | (in) | M&R | Comments |
| 1/1/2011 | NU-IN | New Construction - Initial | 0.00 | 0.00 | V | |
| Network: N | IEW SMY | YRNA BEA Branch: TW A | TAXIV | WAY A | Section: | 105 Surface:AC |
| L.C.D. 1/1/197 | 77 Us | se: TAXIWAY Rank: P I | ength: 2,580 | .00 (Ft) Wid | lth: 40.0 | 0 (Ft) True Area: 93280.00002 (SqFt |
| Work Date | Work | Work Description | Cost | Thickness | Major | Comments |
| | Code NC-AC | New Construction - AC | 0.00 | (in) 0.00 | M&R ✓ | 0.000 |
| | | | | | | |
| Network: N | EW SMY | YRNA BEA Branch: TW A | TAXIV | WAY A | Section: | 110 Surface:AC |
| L.C.D. 7/1/201 | 11 Us | e: TAXIWAY Rank: P I | ength: 400 | .00 (Ft) Wid | dth: 40.0 | 0 (Ft) True Area: 16319.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2011 | NU-IN | New Construction - Initial | 0.00 | 0.00 | V | |
| Network: N | IFW SMY | /RNA BEA Branch: TW A | TAXIV | WAY A | Section: | 115 Surface:AC |
| L.C.D. 1/1/201 | | | | | lth: 100.0 | |
| | *** | | | Thickness | Major | Comments |
| Work Date | Work Code | Work Description | Cost | (in) | M&R | Comments |
| 1/1/2014 | | Complete Reconstruction - AC | 0.00 | (in) 0.00 | M&R | Remove Existing Asphalt and Rework |
| 1/1/2014 | Code | - | | ` , | | |
| 1/1/2014 1/1/1977 | Code CR-AC NU-IN | Complete Reconstruction - AC New Construction - Initial | 0.00 | 0.00 | Y | Remove Existing Asphalt and Rework |
| 1/1/2014 1/1/1977 Network: N | Code CR-AC NU-IN NEW SMY | Complete Reconstruction - AC New Construction - Initial VRNA BEA Branch: TW A | 0.00 0.00 | 0.00 0.00 WAY A | Section: | Remove Existing Asphalt and Rework 125 Surface: AC |
| 1/1/2014 1/1/1977 | Code CR-AC NU-IN JEW SMY 02 Us Work | Complete Reconstruction - AC New Construction - Initial VRNA BEA Branch: TW A | 0.00 0.00 | 0.00 0.00 WAY A .00 (Ft) Wic | Section: Ith: 40.0 Major | Remove Existing Asphalt and Rework |
| 1/1/2014 1/1/1977 Network: N L.C.D. 1/1/200 Work Date | Code CR-AC NU-IN NEW SMY | Complete Reconstruction - AC New Construction - Initial VRNA BEA Branch: TW A se: TAXIWAY Rank: P I | 0.00 0.00 TAXIV | 0.00 0.00 WAY A | Section: | Remove Existing Asphalt and Rework 125 Surface: AC 0 (Ft) True Area: 4303.000001 (SqFt |

| 1 | 1 | /1 | 7 | 12 | Λ | 1 | 1 |
|---|----|----|-----|----|---|---|-----|
| | н. | / | - / | ΙZ | " | Z | · Z |

Work

Code

CR-AC

Work Description

Complete Reconstruction - AC

Work Date

4/1/2022

Work History Report

Page 8 of 11

Pavement Database: FDOT

| | | T avement Database. | TD01 | | | |
|----------------------|----------------|--|-----------------------|--------------------|---------------------|--|
| Network: | NEW SMY | YRNA BEA Branch: TW B | TAXI | WAY B | Section: | 210 Surface: AC |
| L.C.D. 1/1/20 | 002 Us | se: TAXIWAY Rank: P L | ength: 35 | .00 (Ft) Wi | dth: 1850.00 | O (Ft) True Area: 67896.00002 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2002 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | Y | |
| Network: | NEW SMY | YRNA BEA Branch: TW B | TAXI | WAY B | Section: | 215 Surface:AC |
| L.C.D. 1/1/20 | 002 Us | se: TAXIWAY Rank: P L | ength: 35 | .00 (Ft) Wi | dth: 2990.00 | 0 (Ft) True Area: 105867.0000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2002 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | V | |
| | | | | | | |
| | | YRNA BEA Branch: TW C | | WAY C | Section: | |
| Work Date | Work | se: TAXIWAY Rank: P L Work Description | ength: 988 Cost | Thickness | Major | O (Ft) True Area: 48858.00001 (SqFt |
| 1/1/2002 | Code OL-PC | Overlay - PCC | 0.00 | (in) 0.00 | M&R ✓ | |
| 1/1/1997 | NU-IN | New Construction - Initial | 0.00 | 0.00 | | |
| | | | | | | |
| | | YRNA BEA Branch: TW C | | WAY C | Section: | |
| L.C.D. 1/1/20 | 002 Us Work | se: TAXIWAY Rank: P L | ength: 308 | Thickness | dth: 43.00 Major | O (Ft) True Area: 13657.00000 (SqFt |
| Work Date | Code | Work Description | Cost | (in) | M&R | Comments |
| 1/1/2002 | NC-AC | New Construction - AC | 0.00 | 0.00 | V | |
| Network: | NEW SM | YRNA BEA Branch: TW C | TAXI | WAY C | Section: | 312 Surface:AC |
| L.C.D. 4/1/20 | | | | | | 0 (Ft) True Area: 12746.00000 (SqFt |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 4/1/2022 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | | 4" P-401, 6" P-211 |
| 1/1/2002 | NC-AC | New Construction - AC | 0.00 | 0.00 | | |
| Notword- | NEW CM | YRNA BEA Branch: TW C | TAVD | WAY C | Section: | 314 Surface:AC |
| L.C.D. 4/1/20 | | | 1AA1v ength: 1,010 | | | 514 Surface: AC 0 (Ft) True Area: 57036.00001 (SqFt |
| Work Date | Work | Work Description | Cost | Thickness | Major | Comments |
| 4/1/2022 | Code NC-AC | New Construction - AC | 0.00 | (in) 0.00 | M&R ✓ | Comments |
| 11 11 2022 | IIC-AC | Ton Constitution - AC | 0.00 | 0.00 | <u> </u> | |
| Network: | NEW SMY | YRNA BEA Branch: TW C | TAXI | WAY C | Section: | 315 Surface:AC |
| L.C.D. 4/1/20 | 022 Us | se: TAXIWAY Rank: P L | ength: 700 | .00 (Ft) Wi | dth: 35.00 | 0 (Ft) True Area: 24500.00000 (SqFt |

1/1/2002 CR-AC Complete Reconstruction - AC 0.00 2.00

0.00

Cost

Thickness

(in)

0.00

Major

M&R

~

Comments

Cold milling existing asphalt full dept

| 1 | 1 | 11 | 7 | 12 | Λ | 1 | 1 |
|---|---|----|-----|----|---|---|---|
| | | / | - / | ΙZ | u | Z | Z |

Page 9 of 11

Pavement Database: FDOT

| Ī | Network: | NEW SMY | YRNA BEA | Branch: TW C | TAXIV | WAY C | Section: | 325 | Surface:AC |
|---|----------------------|--------------|---------------|------------------|-----------|----------------|--------------|-----------------|------------------------------|
| ı | L.C.D. 1/1/20 | 002 Us | se: TAXIWAY | Rank: P L | ength: 88 | .00 (Ft) Wi | dth: 69.00 | 0 (Ft) T | True Area: 5247.000001 (SqFt |
| | Work Date | Work Code | Work D | escription | Cost | Thickness (in) | Major M&R | | Comments |
| _ | 1/1/2002 | CR-AC | Complete Reco | onstruction - AC | 0.00 | 2.00 | Y | | |
| Ī | Notwork | NEW CM | ZDNA DEA | Propolit TWC | TAND | WAVC | Sections | 220 | Surface: A.C. |

| 1 | Network: NEW SWITKINA DEA | | IKNA DEA DIANCII ; I W C | IAAI | WAIC | Section: | Surface:AC |
|---|--|--------------|---------------------------------|--------------------------|----------------|--------------|--|
| | L.C.D. 4/1/2022 Use: TAXIWAY | | e: TAXIWAY Rank: P L | Y Rank: P Length: 1,215. | | dth: 35.0 | 0 (Ft) True Area: 44997.00001 (SqFt |
| | Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| | 4/1/2022 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | > | Cold milling existing asphalt full dept |
| | 1/1/2002 | CR-AC | Complete Reconstruction - AC | 0.00 | 2.00 | | |

| | Network: | NEW SMY | YRNA BEA | Branch: TW C | TAXI | WAY C | Sec | tion: 345 | Surface:AC |
|---|----------------------|--------------|---------------|---------------|--------------|-------------------|----------|------------|-------------------------------------|
| ı | L.C.D. 1/1/20 | 012 Us | se: TAXIWAY | Rank: P L | ength: 1,125 | .00 (Ft) V | Vidth: | 70.00 (Ft) | True Area: 86977.00002 (SqFt |
| | Work Date | Work Code | Work D | escription | Cost | Thickness (in) | Ma Me | | Comments |
| | 1/1/2012 | NU-IN | New Construct | ion - Initial | 0.00 | 0.0 | 00 |]: | |

| Network: | NEW SMY | YRNA BEA | Branch: TW D | TAXI | WAY D | Se | ection: 4 | 405 | | Surface: AC | ! |
|----------------------|--------------|---------------|------------------|--------------|------------------|--------|--------------|--------|------------|-------------|-------|
| L.C.D. 1/1/20 | 002 Us | se: TAXIWAY | Rank: P L | ength: 1,200 | 0.00 (Ft) | Width: | 35.00 |) (Ft) | True Area: | 50628.00001 | (SqFt |
| Work Date | Work Code | Work D | escription | Cost | Thicknes (in) | | Iajor 1&R | | Comi | ments | |
| 1/1/2002 | CR-AC | Complete Reco | onstruction - AC | 0.00 | 2.0 | 00 | > | | | | |

| Network: | NEW SMY | YRNA BEA | Branch: TW D | TAX | KIWAY | D | Section | n: 415 | | Surface:AC |
|----------------------|--------------|---------------|---------------|----------|----------|--------------|--------------|-----------|------------|-------------------|
| L.C.D. 1/1/19 | 943 Us | se: TAXIWAY | Rank: P I | ength: 1 | 40.00 (F | t) Wi | idth: 5 | 0.00 (Ft) | True Area: | 7000.000002 (SqFt |
| Work Date | Work Code | Work D | escription | Cost | | kness in) | Major M&R | | Comi | nents |
| 1/1/1943 | NU-IN | New Construct | ion - Initial | 0.0 | 00 | 0.00 | > | | | |

| | Network: NEW SMYRNA BEA | | Branch: TW D | TAXI | WAY D | Section: | 425 Surface:AC | |
|---|--|--------------|---------------|------------------|-------------|-------------------|--|------------------------------------|
| | L.C.D. 1/1/2014 Use: TAXIWAY | | Rank: P L | ength: 700 | .00 (Ft) Wi | dth: 35.0 | 0 (Ft) True Area: 27118.00000 (SqFt | |
| | Work Date | Work Code | Work D | escription | Cost | Thickness (in) | Major M&R | Comments |
| | | | | | | (111) | MIXIX | |
| ľ | 1/1/2014 | | Complete Reco | onstruction - AC | 0.00 | () | | Remove Existing Asphalt and Rework |

| ı | Network: NEW SMYRNA BEA | | YRNA BEA Branch: TW D | TAXIV | WAY D | Section: | 427 Surface:AC |
|-------------------------|--------------------------------|------------------|------------------------------|----------------|--------------|--|------------------------------------|
| I. | L.C.D. 1/1/2 | 014 Us | se: TAXIWAY Rank: P L | .00 (Ft) Wi | dth: 35.0 | 0 (Ft) True Area: 40335.00001 (SqFt | |
| Work Date Work Work | | Work Description | Cost | Thickness (in) | Major M&R | Comments | |
| | 1/1/2014 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | V | Remove Existing Asphalt and Rework |
| | 1/1/1943 | NU-IN | New Construction - Initial | 0.00 | 0.00 | > | |

Page 10 of 11

Pavement Database: FDOT

| | Network: | NEW SMY | YRNA BEA | Branch: TW D | TAXIV | WAY D | Section: | 430 | Surface:AAC |
|---|--|--------------|-----------------|---------------|--------------|---------------------|--------------|--------|------------------------------------|
| | L.C.D. 1/1/2016 Use: TAXIWAY | | | Rank: P Lo | ength: 2,100 | .00 (Ft) W i | idth: 50.0 | 0 (Ft) | True Area: 84969.00002 (SqF |
| | Work Date | Work Code | Work D | escription | Cost | Thickness (in) | Major M&R | | Comments |
| Ī | 1/1/2016 | ML-OVL | Mill and Overla | ay | 0.00 | 0.00 | V | | |
| | 1/1/1943 | NU-IN | New Construct | ion - Initial | 0.00 | 0.00 | | | |

Network: NEW SMYRNA BEA Branch: TW E TAXIWAY E Section: 505 Surface: AC Width: 500.00 (Ft) True Area: 17197.00000 (SqFt L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 35.00 (Ft) Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R 1/1/2014 CR-AC Complete Reconstruction - AC 0.00 0.00 Remove Existing 1 1/2" AC, Rework 1/1/1943 NU-IN New Construction - Initial 0.00 0.00 ~

Network: NEW SMYRNA BEA Branch: TW E TAXIWAY E Section: 510 Surface: AC L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 35.00 (Ft) Width: 720.00 (Ft) True Area: 24594.00000 (SqFt Thickness Work Major Work Date **Work Description** Cost Comments Code (in) M&R 1/1/2014 Remove Existing 1 1/2" AC, Rework Complete Reconstruction - AC 0.00 CR-AC 0.00 ~ 1/1/1943 0.00 0.00 NU-IN New Construction - Initial **V**

Network: NEW SMYRNA BEA Branch: TW E TAXIWAY E Section: 515 Surface: AC L.C.D. 7/1/2011 Use: TAXIWAY Rank: P Length: 50.00 (Ft) Width: 1050.00 (Ft) True Area: 52494.00001 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments Code M&R (in) 7/1/2011 NU-IN New Construction - Initial 0.00 0.00 V

Network: NEW SMYRNA BEA TAXIWAY E Branch: TW E Section: 520 Surface: AC **L.C.D.** 1/1/2014 Width: 900.00 (Ft) True Area: 27412.00000 (SqFt Use: TAXIWAY Rank: P Length: 35.00 (Ft) Thickness Work Major **Work Date Work Description** Cost Comments M&R Code (in) 2" P-401, 8" P-211, 8" P-152 1/1/2014 NU-IN New Construction - Initial 0.00 0.00

 Network:
 NEW SMYRNA BEA
 Branch:
 TW E
 TAXIWAY E
 Section:
 530
 Surface:AC

 L.C.D.
 1/1/2018
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 2,100.00 (Ft)
 Width:
 35.00 (Ft)
 True Area:
 76505.00002 (SqFt)

Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R 2" P-401, REWORK EXIST. 8" LIME 1/1/2018 CR-AC Complete Reconstruction - AC 0.00 0.00 **~** 1/1/1940 NC-AC New Construction - AC 0.00 0.00

Network: NEW SMYRNA BEA Branch: TW F TAXIWAY F Section: 610 Surface:AC

L.C.D. 12/1/2020 Use: TAXIWAY Rank: P Length: 415.00 (Ft) Width: 52.00 (Ft) True Area: 28075.00000 (SqFt

| Ī | Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments | |
|---|-----------|--------------|-----------------------|------|----------------|--------------|----------|--|
| 1 | 12/1/2020 | NC-AC | New Construction - AC | 0.00 | 0.00 | V | | |

Work History Report

Page 11 of 11

Pavement Database: FDOT

Summary:

| Work Description | Section Count | Area Total (SqFt) | Thickness Avg (in) | Thickness STD (in) |
|-------------------------------|------------------|-------------------|-----------------------|--------------------|
| Complete Reconstruction - AC | 18 | 625,491.00 | 0.78 | 0.97 |
| Complete Reconstruction - PCC | 3 | 11,550.00 | 0.00 | 0.00 |
| Mill and Overlay | 8 | 796,494.00 | 0.00 | 0.00 |
| New Construction - AC | 11 | 344,515.00 | 0.00 | 0.00 |
| New Construction - Initial | 51 | 1,965,596.00 | 0.00 | 0.00 |
| New Construction - PCC | 4 | 62,383.00 | 0.00 | 0.00 |
| Overlay - PCC | 8 | 161,979.00 | 0.00 | 0.00 |

| 1 | 1 | 11 | 7 | 12 | 022 |
|---|---|-----|---|-----|-----|
| | | / I | 1 | ızı | VZZ |

Branch Condition Report

Page 1 of 2

Pavement Database: FDOT

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | Standard Deviation PCI | Weighted Average PCI |
|-----------|--------------------|----------------------------|---------------------------|---------------------|----------|----------------|------------------------------|----------------------------|
| AP | 21 | 4,218.00 | 94.19 | 249,583.00 | APRON | 55.62 | 37.22 | 53.05 |
| AP RU | 1 | 325.00 | 150.00 | 46,282.00 | APRON | 32.00 | 0.00 | 32.00 |
| AP S | 2 | 1,125.00 | 88.00 | 101,441.00 | APRON | 54.50 | 45.50 | 49.36 |
| AP SE | 1 | 375.00 | 25.00 | 8,835.00 | APRON | 1.00 | 0.00 | 1.00 |
| RW 11-29 | 1 | 4,319.00 | 75.00 | 323,925.00 | RUNWAY | 81.00 | 0.00 | 81.00 |
| RW 2-20 | 6 | 4,195.00 | 100.00 | 387,523.00 | RUNWAY | 51.83 | 24.27 | 37.11 |
| RW 7-25 | 5 | 4,890.00 | 125.00 | 375,128.00 | RUNWAY | 85.60 | 5.31 | 88.20 |
| TL T-HANG | 3 | 2,103.00 | 24.00 | 50,850.00 | TAXILANE | 83.00 | 14.76 | 75.36 |
| TW A | 5 | 3,585.00 | 51.60 | 142,094.00 | TAXIWAY | 71.20 | 16.14 | 61.38 |
| TW B | 2 | 70.00 | 2,420.00 | 173,763.00 | TAXIWAY | 68.50 | 4.50 | 67.52 |
| TW C | 7 | 4,816.00 | 49.57 | 245,160.00 | TAXIWAY | 82.57 | 24.61 | 90.42 |
| TW D | 5 | 5,240.00 | 41.00 | 210,050.00 | TAXIWAY | 71.60 | 25.63 | 81.53 |
| TW E | 5 | 2,255.00 | 641.00 | 198,202.00 | TAXIWAY | 90.00 | 3.29 | 90.18 |
| TW F | 1 | 415.00 | 52.00 | 28,075.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |

| 11/17/2022 | Branch Condition Report | Page 2 of 2 |
|------------|-------------------------|-------------|
| | Pavement Database: FDOT | |

| Use Category | Number of Sections | Total Area (SqFt) | Arithmetic Average PCI | Average STD PCI | Weighted Average PCI |
|--------------|-----------------------|-------------------|---------------------------|-----------------|-------------------------|
| APRON | 25 | 406,141.00 | 52.40 | 38.22 | 48.60 |
| RUNWAY | 12 | 1,086,576.00 | 68.33 | 24.08 | 67.83 |
| TAXILANE | 3 | 50,850.00 | 83.00 | 14.76 | 75.36 |
| TAXIWAY | 25 | 997,344.00 | 79.16 | 20.84 | 80.64 |
| ALL | 65 | 2,540,911.00 | 67.05 | 31.57 | 69.94 |

Pavement Database: FDOT


NetworkId: EVB

| Pavement Date | abase: FDO1 | | | | пен | : EVB | | | | | |
|---------------|-------------|---------------------|---------|----------|------|-------|---------------------|----------------------------|--------------------------|-----|--|
| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspec tion | | |
| AP | 4102 | 1/1/1984 | PCC | APRON | Р | 0 | 20,539.00 | 1/24/2022 | 38 | 4 | |
| AP | 4103 | 4/1/2022 | AC | APRON | P | 0 | 9,336.00 | 4/1/2022 | 0 | 100 | |
| AP | 4104 | 1/1/1984 | AC | APRON | Р | 0 | 3,872.00 | 1/24/2022 | 38 | | |
| AP | 4105 | 1/1/1965 | PCC | APRON | P | 0 | 6,440.00 | 1/24/2022 | 57 | 9 | |
| AP | 4106 | 12/1/2020 | PCC | APRON | P | 0 | 3,540.00 | 12/1/2020 | 0 | 100 | |
| AP | 4107 | 12/1/2020 | AC | APRON | P | 0 | 12,117.00 | 12/1/2020 | 0 | 100 | |
| AP | 4108 | 12/1/2020 | PCC | APRON | P | 0 | 8,757.00 | 12/1/2020 | 0 | 100 | |
| AP | 4110 | 1/1/1980 | PCC | APRON | P | 0 | 1,950.00 | 1/24/2022 | 42 | 7 | |
| AP | 4115 | 1/1/1900 | PCC | APRON | P | 0 | 8,775.00 | 1/24/2022 | 47 | 1 | |
| AP | 4124 | 1/1/2002 | PCC | APRON | P | 0 | 6,450.00 | 1/24/2022 | 20 | | |
| AP | 4127 | | PCC | | Р | | | | | 87 | |
| | | 1/1/2019 | | APRON | P | 0 | 1,560.00 | 1/24/2022 | 3 | | |
| AP | 4128 | 12/1/2020 | PCC | APRON | | 0 | 6,565.00 | 12/1/2020 | 0 | 100 | |
| AP | 4129 | 12/1/2020 | PCC | APRON | Р | 0 | 2,070.00 | 12/1/2020 | 0 | 100 | |
| AP | 4130 | 1/1/1997 | PCC | APRON | Р | 0 | 23,150.00 | 1/24/2022 | 25 | 47 | |
| AP | 4132 | 1/1/1997 | PCC | APRON | Р | 0 | 17,074.00 | 1/24/2022 | 25 | | |
| AP | 4135 | 1/1/1975 | AC | APRON | P | 0 | 4,290.00 | 1/24/2022 | 47 | 33 | |
| AP | 4140 | 1/1/1980 | AC | APRON | Р | 0 | 37,036.00 | 1/24/2022 | 42 | 35 | |
| AP | 4145 | 1/1/1986 | AC | APRON | P | 0 | 17,888.00 | 1/24/2022 | 36 | 65 | |
| AP | 4160 | 1/1/1975 | AC | APRON | Р | 0 | 10,001.00 | 1/24/2022 | 47 | 41 | |
| AP | 4165 | 1/1/1991 | PCC | APRON | Р | 0 | 9,517.00 | 1/24/2022 | 31 | 10 | |
| AP | 4190 | 1/1/2012 | PCC | APRON | Р | 0 | 38,656.00 | 1/24/2022 | 10 | | |
| AP RU | 5105 | 1/1/1943 | AC | APRON | Р | 0 | 46,282.00 | 1/24/2022 | 79 | 32 | |
| AP S | 4215 | 1/1/1943 | PCC | APRON | Р | 0 | 56,450.00 | 1/24/2022 | 79 | 9 | |
| AP S | 4225 | 12/1/2020 | PCC | APRON | Р | 0 | 44,991.00 | 12/1/2020 | 0 | 100 | |
| AP SE | 4220 | 12/25/1999 | PCC | APRON | Р | 0 | 8,835.00 | 1/24/2022 | 23 | 1 | |
| RW 11-29 | 6105 | 1/1/2014 | AAC | RUNWAY | Р | 0 | 323,925.00 | 1/24/2022 | 8 | 81 | |
| RW 2-20 | 6405 | 1/1/1943 | AC | RUNWAY | Р | 0 | 78,400.00 | 1/24/2022 | 79 | 33 | |
| RW 2-20 | 6425 | 1/1/1943 | AC | RUNWAY | Р | 0 | 254,789.00 | 1/24/2022 | 79 | 34 | |
| RW 2-20 | 6427 | 1/1/2014 | AC | RUNWAY | Р | 0 | 11,862.00 | 1/24/2022 | 8 | 89 | |
| RW 2-20 | 6430 | 1/1/1977 | AC | RUNWAY | Р | 0 | 5,000.00 | 1/24/2022 | 45 | 38 | |
| RW 2-20 | 6435 | 1/1/2014 | AAC | RUNWAY | Р | 0 | 12,472.00 | 1/24/2022 | 8 | 83 | |
| RW 2-20 | 6450 | 1/1/1977 | AC | RUNWAY | Р | 0 | 25,000.00 | 1/24/2022 | 45 | | |
| RW 7-25 | 6202 | 1/1/2008 | AAC | RUNWAY | Р | 0 | 18,750.00 | 1/24/2022 | 14 | 76 | |
| RW 7-25 | 6205 | 1/1/2016 | AAC | RUNWAY | Р | 0 | 324,750.00 | 1/24/2022 | 6 | 89 | |
| RW 7-25 | 6210 | 1/1/2008 | AAC | RUNWAY | Р | 0 | 11,378.00 | 1/24/2022 | 14 | 84 | |
| RW 7-25 | 6215 | 1/1/2016 | AAC | RUNWAY | Р | 0 | 7,125.00 | 1/24/2022 | 6 | 91 | |
| RW 7-25 | 6220 | 1/1/2016 | AAC | RUNWAY | Р | 0 | 13,125.00 | 1/24/2022 | 6 | 88 | |
| TL T-HANG | 4320 | 1/1/2002 | AC | TAXILANE | Р | 0 | 31,261.00 | 1/24/2022 | 20 | 64 | |
| TL T-HANG | 4340 | 1/1/2010 | AC | TAXILANE | Р | 0 | 8,491.00 | | 12 | | |
| TL T-HANG | 4360 | 3/1/2021 | AC | TAXILANE | Р | 0 | 11,098.00 | | 0 | 100 | |
| TW A | 102 | 1/1/2011 | AC | TAXIWAY | Р | 0 | 22,287.00 | 1/24/2022 | 11 | 85 | |
| TW A | 105 | 1/1/1977 | AC | TAXIWAY | Р | 0 | 93,280.00 | 1/24/2022 | 45 | | |
| TW A | 110 | 7/1/2011 | AC | TAXIWAY | P | 0 | 16,319.00 | 1/24/2022 | 11 | 82 | |
| TW A | 115 | 1/1/2014 | AC | TAXIWAY | P | 0 | 5,905.00 | 1/24/2022 | 8 | 86 | |
| TW A | 125 | 1/1/2002 | AC | TAXIWAY | Р | 0 | 4,303.00 | | 20 | | |
| TW B | 210 | 1/1/2002 | AC | TAXIWAY | Р | 0 | 67,896.00 | 1/24/2022 | 20 | | |
| TW B | 215 | 1/1/2002 | AC | TAXIWAY | P | 0 | 105,867.00 | 1/24/2022 | 20 | | |
| TW C | 310 | 1/1/2002 | AC | TAXIWAY | Р | 0 | 13,657.00 | 1/24/2022 | 20 | | |
| TW C | 312 | 4/1/2022 | AC | TAXIWAY | P | 0 | 12,746.00 | | 0 | | |
| TW C | 314 | 4/1/2022 | | TAXIWAY | P | 0 | 57,036.00 | | | | |
| 1 | | , | | 1 | 1 - | | 1 , | | ' | | |

| 11/17/2022 | | Section | | | Page 2 | 2 of 3 | | | | |
|------------|-----|-----------|-----|---------|--------|--------|-----------|-----------|----|-----|
| TW C | 315 | 4/1/2022 | AC | TAXIWAY | Р | 0 | 24,500.00 | 4/1/2022 | 0 | 100 |
| TW C | 325 | 1/1/2002 | AC | TAXIWAY | Р | 0 | 5,247.00 | 1/24/2022 | 20 | 59 |
| TW C | 330 | 4/1/2022 | AC | TAXIWAY | Р | 0 | 44,997.00 | 4/1/2022 | 0 | 100 |
| TW C | 345 | 1/1/2012 | AC | TAXIWAY | Р | 0 | 86,977.00 | 1/24/2022 | 10 | 86 |
| TW D | 405 | 1/1/2002 | AC | TAXIWAY | Р | 0 | 50,628.00 | 1/24/2022 | 20 | 68 |
| TW D | 415 | 1/1/1943 | AC | TAXIWAY | Р | 0 | 7,000.00 | 1/24/2022 | 79 | 23 |
| TW D | 425 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 27,118.00 | 1/24/2022 | 8 | 89 |
| TW D | 427 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 40,335.00 | 1/24/2022 | 8 | 90 |
| TW D | 430 | 1/1/2016 | AAC | TAXIWAY | Р | 0 | 84,969.00 | 1/24/2022 | 6 | 88 |
| TW E | 505 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 17,197.00 | 1/24/2022 | 8 | 91 |
| TW E | 510 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 24,594.00 | 1/24/2022 | 8 | 90 |
| TW E | 515 | 7/1/2011 | AC | TAXIWAY | Р | 0 | 52,494.00 | 1/24/2022 | 11 | 84 |
| TW E | 520 | 1/1/2014 | AC | TAXIWAY | Р | 0 | 27,412.00 | 1/24/2022 | 8 | 91 |
| TW E | 530 | 1/1/2018 | AC | TAXIWAY | Р | 0 | 76,505.00 | 1/24/2022 | 4 | 94 |
| TW F | 610 | 12/1/2020 | AC | TAXIWAY | Р | 0 | 28,075.00 | 12/1/2020 | 0 | 100 |

Pavement Database: FDOT

| Age Category | Average Age at Inspection | Total Area (SqFt) | Number of Sections | Arithmetic Average PCI | Standard Deviation PCI | Weighted Average PCI |
|--------------|---------------------------|-------------------|-----------------------|---------------------------|---------------------------|-------------------------|
| 00-02 | | 265,828.00 | 13 | 100.00 | 0.00 | 100.00 |
| 03-05 | 4 | 78,065.00 | 2 | 90.50 | 3.50 | 93.86 |
| 06-10 | 8 | 1,046,422.00 | 15 | 88.13 | 2.87 | 86.29 |
| 11-15 | 12 | 129,719.00 | 6 | 82.67 | 3.14 | 82.83 |
| 16-20 | 20 | 285,309.00 | 8 | 60.75 | 12.37 | 65.30 |
| 21-25 | 24 | 49,059.00 | 3 | 23.67 | 18.79 | 30.36 |
| 31-35 | 31 | 9,517.00 | 1 | 10.00 | 0.00 | 10.00 |
| 36-40 | 37 | 42,299.00 | 3 | 37.33 | 25.22 | 33.37 |
| 41-50 | 45 | 185,332.00 | 8 | 30.00 | 15.99 | 41.37 |
| 50+ | 75 | 449,361.00 | 6 | 23.33 | 10.75 | 29.95 |
| ALL | 21 | 2,540,911.00 | 65 | 67.05 | 31.57 | 69.94 |



Planning Needs

Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

| Network ID | Branch ID | Section ID | Description | Severity | Distress Qty | Distress Unit | Distress Density | Policy Type | Localized Work Type | Work Qty | Work Unit | Ur | nit Cost | W | ork Cost |
|------------|-----------|------------|--------------|----------|--------------|---------------|------------------|-------------|----------------------------|----------|-----------|----|----------|----|----------|
| EVB | RW 2-20 | 6427 | WEATHERING | Medium | 237 | SF | 2.0% | Preventive | Surface Seal | 237 | SF | \$ | 0.75 | \$ | 180 |
| EVB | RW 2-20 | 6435 | WEATHERING | Medium | 1,870 | SF | 15.0% | Preventive | Surface Seal | 1,870 | SF | \$ | 0.75 | \$ | 1,410 |
| EVB | RW 7-25 | 6202 | WEATHERING | Medium | 9,375 | SF | 50.0% | Preventive | Surface Seal | 9,375 | SF | \$ | 0.75 | \$ | 7,040 |
| EVB | RW 7-25 | 6205 | L & T CR | Medium | 96 | LF | 0.0% | Preventive | AC Crack Sealing | 96 | LF | \$ | 4.00 | \$ | 390 |
| EVB | RW 7-25 | 6210 | WEATHERING | Medium | 1,138 | SF | 10.0% | Preventive | Surface Seal | 1,138 | SF | \$ | 0.75 | \$ | 860 |
| EVB | RW 11-29 | 6105 | L & T CR | Medium | 34 | LF | 0.0% | Preventive | AC Crack Sealing | 34 | LF | \$ | 4.00 | \$ | 140 |
| EVB | RW 11-29 | 6105 | WEATHERING | Medium | 20,702 | SF | 6.4% | Preventive | Surface Seal | 20,702 | SF | \$ | 0.75 | \$ | 15,530 |
| EVB | TW A | 102 | RAVELING | Low | 2,229 | SF | 10.0% | Preventive | Surface Seal | 2,229 | SF | \$ | 0.75 | \$ | 1,680 |
| EVB | TW A | 110 | WEATHERING | Medium | 3,263 | SF | 20.0% | Preventive | Surface Seal | 3,264 | SF | \$ | 0.75 | \$ | 2,450 |
| EVB | TW A | 115 | WEATHERING | Medium | 296 | SF | 5.0% | Preventive | Surface Seal | 296 | SF | \$ | 0.75 | \$ | 230 |
| EVB | TW B | 210 | L & T CR | Medium | 323 | LF | 0.5% | Preventive | AC Crack Sealing | 323 | LF | \$ | 4.00 | \$ | 1,300 |
| EVB | TW B | 210 | RAVELING | Low | 2,263 | SF | 3.3% | Preventive | Surface Seal | 2,264 | SF | \$ | 0.75 | \$ | 1,700 |
| EVB | TW B | 210 | WEATHERING | Medium | 9,053 | SF | 13.3% | Preventive | Surface Seal | 9,053 | SF | \$ | 0.75 | \$ | 6,790 |
| EVB | TW C | 345 | WEATHERING | Medium | 7,446 | SF | 8.6% | Preventive | Surface Seal | 7,445 | SF | \$ | 0.75 | \$ | 5,590 |
| EVB | TW E | 505 | WEATHERING | Medium | 860 | SF | 5.0% | Preventive | Surface Seal | 860 | SF | \$ | 0.75 | \$ | 650 |
| EVB | TW E | 515 | WEATHERING | Medium | 10,499 | SF | 20.0% | Preventive | Surface Seal | 10,499 | SF | \$ | 0.75 | \$ | 7,880 |
| EVB | TW E | 520 | WEATHERING | Medium | 1,369 | SF | 5.0% | Preventive | Surface Seal | 1,369 | SF | \$ | 0.75 | \$ | 1,030 |
| EVB | TL T-HANG | 4340 | WEATHERING | Medium | 849 | SF | 10.0% | Preventive | Surface Seal | 849 | SF | \$ | 0.75 | \$ | 640 |
| EVB | AP | 4124 | JT SEAL DMG | High | 52 | Slabs | 100.0% | Preventive | PCC Joint Seal | 920 | LF | \$ | 4.25 | \$ | 3,920 |
| EVB | AP | 4124 | CORNER SPALL | Medium | 2 | Slabs | 4.2% | Preventive | PCC Partial-Depth Patching | 5 | SF | \$ | 169.00 | \$ | 990 |
| EVB | AP | 4127 | JT SEAL DMG | High | 52 | Slabs | 100.0% | Preventive | PCC Joint Seal | 444 | LF | \$ | 4.25 | \$ | 1,890 |
| EVB | AP | 4190 | JT SEAL DMG | Low | 258 | Slabs | 100.0% | Preventive | PCC Joint Seal | 4,070 | LF | \$ | 4.25 | \$ | 17,300 |
| EVB | AP | 4190 | JOINT SPALL | Medium | 5 | Slabs | 2.1% | Preventive | PCC Partial-Depth Patching | 34 | SF | \$ | 169.00 | \$ | 5,870 |
| EVB | AP | 4190 | CORNER SPALL | Medium | 5 | Slabs | 2.1% | Preventive | PCC Partial-Depth Patching | 14 | SF | \$ | 169.00 | \$ | 2,450 |
| EVB | RW 2-20 | 6425 | PATCHING | High | 1,070 | SF | 0.4% | Stopgap | AC Full-Depth Patching | 1,206 | SF | \$ | 10.00 | \$ | 12,060 |
| EVB | TW D | 415 | BLOCK CR | High | 1,050 | SF | 15.0% | Stopgap | AC Crack Sealing | 320 | LF | \$ | 4.00 | \$ | 1,290 |
| EVB | AP | 4102 | CORNER BREAK | Medium | 14 | Slabs | 20.0% | Stopgap | PCC Full-Depth Patching | 459 | SF | \$ | 50.00 | \$ | 22,930 |
| EVB | AP | 4102 | JT SEAL DMG | High | 71 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 2,132 | LF | \$ | 4.25 | \$ | 9,060 |
| EVB | AP | 4102 | SHAT. SLAB | Medium | 14 | Slabs | 20.0% | Stopgap | PCC Crack Sealing | 483 | LF | \$ | 7.00 | \$ | 3,380 |
| EVB | AP | 4102 | SHAT. SLAB | High | 14 | Slabs | 20.0% | Stopgap | PCC Slab Replacement | 4,089 | SF | \$ | 51.50 | \$ | 210,620 |
| EVB | AP | 4102 | JOINT SPALL | Medium | 14 | Slabs | 20.0% | Stopgap | PCC Partial-Depth Patching | 92 | SF | \$ | 169.00 | \$ | 15,500 |
| EVB | AP | 4102 | CORNER SPALL | Medium | 14 | Slabs | 20.0% | Stopgap | PCC Partial-Depth Patching | 39 | SF | \$ | 169.00 | \$ | 6,460 |
| EVB | AP | 4105 | LINEAR CR | Medium | 1 | Slabs | 7.1% | Stopgap | PCC Crack Sealing | 21 | LF | \$ | 7.00 | \$ | 150 |
| EVB | AP | 4105 | JT SEAL DMG | High | 13 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 202 | LF | \$ | 4.25 | \$ | 860 |
| EVB | AP | 4105 | SHAT. SLAB | Medium | 6 | Slabs | 42.9% | Stopgap | PCC Crack Sealing | 251 | LF | \$ | 7.00 | \$ | 1,760 |
| EVB | AP | 4110 | LINEAR CR | Medium | 2 | Slabs | 25.0% | Stopgap | PCC Crack Sealing | 34 | LF | \$ | 7.00 | \$ | 240 |
| EVB | AP | 4110 | JT SEAL DMG | High | 9 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 160 | LF | \$ | 4.25 | \$ | 690 |
| EVB | AP | 4110 | SHAT. SLAB | Medium | 7 | Slabs | 75.0% | Stopgap | PCC Crack Sealing | 202 | LF | \$ | 7.00 | \$ | 1,420 |
| EVB | AP | 4115 | CORNER BREAK | Medium | 1 | Slabs | 3.9% | Stopgap | PCC Full-Depth Patching | 26 | SF | \$ | 50.00 | \$ | 1,310 |
| EVB | AP | 4115 | LINEAR CR | Medium | 2 | Slabs | 11.5% | Stopgap | PCC Crack Sealing | 51 | LF | \$ | 7.00 | \$ | 360 |
| EVB | AP | 4115 | JT SEAL DMG | High | 21 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 476 | LF | \$ | 4.25 | \$ | 2,030 |
| EVB | AP | 4115 | SHAT. SLAB | Medium | 13 | Slabs | 61.5% | Stopgap | PCC Crack Sealing | 543 | LF | \$ | 7.00 | \$ | 3,800 |
| EVB | AP | 4115 | SHAT. SLAB | High | 3 | Slabs | 15.4% | Stopgap | PCC Slab Replacement | 1,374 | SF | \$ | 51.50 | \$ | 70,720 |
| EVB | AP | 4115 | JOINT SPALL | Medium | 1 | Slabs | 3.9% | Stopgap | PCC Partial-Depth Patching | 5 | SF | \$ | 169.00 | \$ | 890 |
| EVB | AP | 4130 | LINEAR CR | Medium | 14 | Slabs | 12.5% | Stopgap | PCC Crack Sealing | 200 | LF | \$ | 7.00 | \$ | 1,400 |

Airport Pavement Evaluation Report Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Section ID | Description | Severity | Distress Qty | Distress Unit | Distress Density | Policy Type | Localized Work Type | Work Qty | Work Unit | Unit Cost | ٧ | Vork Cost |
|------------|-----------|------------|--------------|----------|--------------|---------------|------------------|-------------|----------------------------|----------|-----------|-----------|----|-----------|
| EVB | AP | 4130 | JT SEAL DMG | High | 110 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 3,038 | LF | \$ 4.25 | \$ | 12,920 |
| EVB | AP | 4130 | CORNER SPALL | Medium | 5 | Slabs | 4.2% | Stopgap | PCC Partial-Depth Patching | 12 | SF | \$ 169.00 | \$ | 2,090 |
| EVB | AP | 4132 | LINEAR CR | Medium | 17 | Slabs | 38.9% | Stopgap | PCC Crack Sealing | 334 | LF | \$ 7.00 | \$ | 2,350 |
| EVB | AP | 4132 | JT SEAL DMG | High | 43 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 1,475 | LF | \$ 4.25 | \$ | 6,270 |
| EVB | AP | 4132 | SHAT. SLAB | Medium | 5 | Slabs | 11.1% | Stopgap | PCC Crack Sealing | 191 | LF | \$ 7.00 | \$ | 1,340 |
| EVB | AP | 4132 | JOINT SPALL | Medium | 2 | Slabs | 5.6% | Stopgap | PCC Partial-Depth Patching | 15 | SF | \$ 169.00 | \$ | 2,610 |
| EVB | AP | 4135 | ALLIGATOR CR | Medium | 40 | SF | 0.9% | Stopgap | AC Full-Depth Patching | 70 | SF | \$ 10.00 | \$ | 700 |
| EVB | AP | 4140 | RAVELING | High | 139 | SF | 0.4% | Stopgap | AC Partial-Depth Patching | 139 | SF | \$ 4.75 | \$ | 660 |
| EVB | AP | 4160 | BLOCK CR | High | 71 | SF | 0.7% | Stopgap | AC Crack Sealing | 22 | LF | \$ 4.00 | \$ | 90 |
| EVB | AP | 4165 | LARGE PATCH | High | 2 | Slabs | 9.1% | Stopgap | PCC Full-Depth Patching | 216 | SF | \$ 50.00 | \$ | 10,810 |
| EVB | AP | 4165 | SHAT. SLAB | Medium | 3 | Slabs | 13.6% | Stopgap | PCC Crack Sealing | 129 | LF | \$ 7.00 | \$ | 910 |
| EVB | AP RU | 5105 | BLOCK CR | High | 103 | SF | 0.2% | Stopgap | AC Crack Sealing | 32 | LF | \$ 4.00 | \$ | 130 |
| EVB | AP S | 4215 | CORNER BREAK | Medium | 7 | Slabs | 5.0% | Stopgap | PCC Full-Depth Patching | 228 | SF | \$ 50.00 | \$ | 11,390 |
| EVB | AP S | 4215 | LINEAR CR | Medium | 11 | Slabs | 7.5% | Stopgap | PCC Crack Sealing | 212 | LF | \$ 7.00 | \$ | 1,490 |
| EVB | AP S | 4215 | JT SEAL DMG | High | 141 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 4,935 | LF | \$ 4.25 | \$ | 20,980 |
| EVB | AP S | 4215 | SMALL PATCH | High | 4 | Slabs | 2.5% | Stopgap | PCC Partial-Depth Patching | 10 | SF | \$ 169.00 | \$ | 1,610 |
| EVB | AP S | 4215 | SHAT. SLAB | Medium | 56 | Slabs | 40.0% | Stopgap | PCC Crack Sealing | 2,256 | LF | \$ 7.00 | \$ | 15,800 |
| EVB | AP S | 4215 | SHAT. SLAB | High | 18 | Slabs | 12.5% | Stopgap | PCC Slab Replacement | 7,050 | SF | \$ 51.50 | \$ | 363,080 |
| EVB | AP S | 4215 | JOINT SPALL | Medium | 18 | Slabs | 12.5% | Stopgap | PCC Partial-Depth Patching | 114 | SF | \$ 169.00 | \$ | 19,240 |
| EVB | AP S | 4215 | JOINT SPALL | High | 7 | Slabs | 5.0% | Stopgap | PCC Partial-Depth Patching | 57 | SF | \$ 169.00 | \$ | 9,620 |
| EVB | AP S | 4215 | CORNER SPALL | Medium | 11 | Slabs | 7.5% | Stopgap | PCC Partial-Depth Patching | 28 | SF | \$ 169.00 | \$ | 4,810 |
| EVB | AP SE | 4220 | CORNER BREAK | Medium | 3 | Slabs | 5.0% | Stopgap | PCC Full-Depth Patching | 84 | SF | \$ 50.00 | \$ | 4,200 |
| EVB | AP SE | 4220 | CORNER BREAK | High | 4 | Slabs | 7.5% | Stopgap | PCC Full-Depth Patching | 126 | SF | \$ 50.00 | \$ | 6,300 |
| EVB | AP SE | 4220 | LINEAR CR | Medium | 7 | Slabs | 12.5% | Stopgap | PCC Crack Sealing | 85 | LF | \$ 7.00 | \$ | 600 |
| EVB | AP SE | 4220 | JT SEAL DMG | High | 52 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 1,042 | LF | \$ 4.25 | \$ | 4,430 |
| EVB | AP SE | 4220 | SHAT. SLAB | Medium | 16 | Slabs | 30.0% | Stopgap | PCC Crack Sealing | 406 | LF | \$ 7.00 | \$ | 2,840 |
| EVB | AP SE | 4220 | SHAT. SLAB | High | 23 | Slabs | 45.0% | Stopgap | PCC Slab Replacement | 3,955 | SF | \$ 51.50 | \$ | 203,670 |
| EVB | AP SE | 4220 | JOINT SPALL | Medium | 1 | Slabs | 2.5% | Stopgap | PCC Partial-Depth Patching | 9 | SF | \$ 169.00 | \$ | 1,420 |



Table B.2: Section-Level 10-Year Major Rehabilitation Needs

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | ning Cost stimate |
|--------------|------------|-----------|------------|---------|-----------|---------------|---------------------|----------------------|
| 2023 | EVB | RW 2-20 | 6405 | AC | 78,400 | 32 | AC Reconstruction | \$ 1,255,000 |
| 2023 | EVB | RW 2-20 | 6425 | AC | 254,789 | 33 | AC Reconstruction | \$ 4,077,000 |
| 2023 | EVB | RW 2-20 | 6430 | AC | 5,000 | 38 | AC Reconstruction | \$ 80,000 |
| 2023 | EVB | RW 2-20 | 6450 | AC | 25,000 | 33 | AC Reconstruction | \$ 400,000 |
| 2023 | EVB | TW A | 105 | AC | 93,280 | 50 | AC Reconstruction | \$ 1,493,000 |
| 2023 | EVB | TW A | 125 | AC | 4,303 | 51 | AC Reconstruction | \$ 69,000 |
| 2023 | EVB | TW B | 215 | AC | 105,867 | 63 | AC Rehabilitation | \$ 953,000 |
| 2023 | EVB | TW C | 310 | AC | 13,657 | 31 | AC Reconstruction | \$ 219,000 |
| 2023 | EVB | TW C | 325 | AC | 5,247 | 58 | AC Rehabilitation | \$ 48,000 |
| 2023 | EVB | TW D | 405 | AC | 50,628 | 66 | AC Rehabilitation | \$ 456,000 |
| 2023 | EVB | TW D | 415 | AC | 7,000 | 21 | AC Reconstruction | \$ 112,000 |
| 2023 | EVB | TL T-HANG | 4320 | AC | 31,261 | 63 | AC Rehabilitation | \$ 282,000 |
| 2023 | EVB | AP | 4102 | PCC | 20,539 | 3 | PCC Reconstruction | \$ 596,000 |
| 2023 | EVB | AP | 4104 | AC | 3,872 | 42 | AC Reconstruction | \$ 62,000 |
| 2023 | EVB | AP | 4105 | PCC | 6,440 | 8 | PCC Reconstruction | \$ 187,000 |
| 2023 | EVB | AP | 4110 | PCC | 1,950 | 6 | PCC Reconstruction | \$ 57,000 |
| 2023 | EVB | AP | 4115 | PCC | 8,775 | 0 | PCC Reconstruction | \$ 255,000 |
| 2023 | EVB | AP | 4130 | PCC | 23,150 | 46 | PCC Reconstruction | \$ 672,000 |
| 2023 | EVB | AP | 4132 | PCC | 17,074 | 22 | PCC Reconstruction | \$ 496,000 |
| 2023 | EVB | AP | 4135 | AC | 4,290 | 32 | AC Reconstruction | \$ 69,000 |
| 2023 | EVB | AP | 4140 | AC | 37,036 | 34 | AC Reconstruction | \$ 593,000 |
| 2023 | EVB | AP | 4145 | AC | 17,888 | 63 | AC Rehabilitation | \$ 161,000 |
| 2023 | EVB | AP | 4160 | AC | 10,001 | 40 | AC Reconstruction | \$ 161,000 |
| 2023 | EVB | AP | 4165 | PCC | 9,517 | 9 | PCC Reconstruction | \$ 276,000 |
| 2023 | EVB | AP RU | 5105 | AC | 46,282 | 31 | AC Reconstruction | \$ 741,000 |
| 2023 | EVB | AP S | 4215 | PCC | 56,450 | 8 | PCC Reconstruction | \$ 1,638,000 |
| 2023 | EVB | AP SE | 4220 | PCC | 8,835 | 0 | PCC Reconstruction | \$ 257,000 |
| 2024 | EVB | TW B | 210 | AC | 67,896 | 70 | AC Rehabilitation | \$ 642,000 |
| 2025 | EVB | RW 7-25 | 6202 | AAC | 18,750 | 69 | AC Rehabilitation | \$ 187,000 |
| 2028 | EVB | RW 11-29 | 6105 | AAC | 323,925 | 69 | AC Rehabilitation | \$ 3,721,000 |

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost Estimate | |
|--------------|------------|-----------|------------|---------|-----------|---------------|---------------------|---------------------------|-----------|
| 2029 | EVB | RW 2-20 | 6435 | AAC | 12,472 | 69 | AC Rehabilitation | \$ | 151,000 |
| 2029 | EVB | RW 7-25 | 6210 | AAC | 11,378 | 70 | AC Rehabilitation | \$ | 138,000 |
| 2030 | EVB | TW A | 110 | AC | 16,319 | 70 | AC Rehabilitation | \$ | 207,000 |
| 2031 | EVB | RW 7-25 | 6220 | AAC | 13,125 | 70 | AC Rehabilitation | \$ | 175,000 |
| 2031 | EVB | TW E | 515 | AC | 52,494 | 70 | AC Rehabilitation | \$ | 699,000 |
| 2032 | EVB | RW 7-25 | 6205 | AAC | 324,750 | 69 | AC Rehabilitation | \$ | 4,535,000 |
| 2032 | EVB | TW A | 102 | AC | 22,287 | 69 | AC Rehabilitation | \$ | 312,000 |
| 2032 | EVB | TW A | 115 | AC | 5,905 | 70 | AC Rehabilitation | \$ | 83,000 |
| 2032 | EVB | TW C | 345 | AC | 86,977 | 70 | AC Rehabilitation | \$ | 1,215,000 |
| 2032 | EVB | TL T-HANG | 4340 | AC | 8,491 | 69 | AC Rehabilitation | \$ | 119,000 |
| 2032 | EVB | AP | 4124 | PCC | 6,450 | 59 | PCC Rehabilitation | \$ | 151,000 |

^{*}All planning cost values have been rounded up to the nearest thousand dollars.

Table B.3: Section-Level Major Rehabilitation Needs - Whitetopping Pavements

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PASER Value Before | Rehabilitation Type | Planning Cost Estimate | |
|--------------|------------|-----------|------------|---------|--------------|-----------------------|---------------------|---------------------------|--|
| 2023 | EVB | AP | 4120 | WT | 14,180 | 2 | PCC Rehabilitation | \$ 213,000 | |
| 2023 | EVB | AP | 4121 | WT | 12,650 | 2 | PCC Rehabilitation | \$ 190,000 | |


^{*}All planning cost values have been rounded up to the nearest thousand dollars.







Appendix C: Technical Exhibits






















Photograph Documentation




RW 2-20, Section 6405, Sample Unit 107 - Block Cracking



RW 2-20, Section 6425, Sample Unit 128 - Block Cracking





RW 7-25, Section 6202, Sample Unit 103 - Weathering



RW 7-25, Section 6205, Sample Unit 167 - Vicinity





RW 11-29, Section 6105, Sample Unit 119 - Patching



RW 11-29, Section 6105, Sample Unit 170 - Longitudinal & Transverse Cracking






TW A, Section 105, Sample Unit 133 - Vicinity



TW B, Section 215, Sample Unit 123 - Longitudinal & Transverse Cracking





TW C, Section 310, Sample Unit 135 - Longitudinal & Transverse Cracking



TW D, Section 415, Sample Unit 98 - Block Cracking






AP, Section 4102, Sample Unit 101 - Vicinity



AP, Section 4115, Sample Unit 101 - Shattered Slab






AP, Section 4121, Sample Unit 100 (Whitetopping) - Slab Cracking



AP, Section 4155, Sample Unit 102 (Whitetopping) - Slab Cracking





Appendix E: Inspection Distress Details

Re-Inspection Report

FDOT

62

63

65

72

72

72

73

74

75

CORNER BREAK

LINEAR CR

JT SEAL DMG

SHAT. SLAB

SHAT. SLAB

SHAT. SLAB

JOINT SPALL

SHRINKAGE CR

CORNER SPALL

M

L

Н

L

M

Η

N

M

M

3.00 Slabs

3.00 Slabs

15.00 Slabs

6.00 Slabs

3.00 Slabs

3.00 Slabs

4.00 Slabs

3.00 Slabs

| FDOI | | | | | | | | | | D 1 - 6 ((|
|---|---------|--------------|-------------|---------|---------------|-------------|--------------------|--------------|--------------|--------------|
| Generated Dat | e | | 11/17/2022 | | | | | | | Page 1 of 60 |
| Network: I | EVB | | | | Name: | NEW SMYRNA | BEACH MUNICIP | PAL AIRPORT | | |
| Branch: | AP | | Name: | APRO | N | Use: | APRON | Area: | 362,704 SqFt | |
| Section: 410 | 2 | of | 28 | From: - | | | То: - | | Last Const.: | 1/1/1984 |
| Surface: PCC | C F | Family: | CA653-GA | -AP-PCC | Zone: | | Category: | | Rank: P | |
| Area: | 20,539 | SqFt | Lengt | h: | 110 Ft | Width: | 187 Ft | | | |
| Slabs: 71 | | Slab Leng | gth: | 16 Ft | Slab W | idth: | 18 Ft | Joint Length | : 2,131 F | t |
| Shoulder: | | Street Type: | | | Grade: | 0 | | Lanes: 0 | | |
| Section Comm | ents: | | | | | | | | | |
| Work Date: 1/1/1984 Work Type: New Construction | | | n - Initial | C | ode: NU-IN | Is Major | Is Major M&R: True | | | |
| Last Insp. Date: 1/24/2022 TotalSamples: 4 | | | 1 | Surveye | e d: 1 | | | | | |
| Conditions: | PCI: 4 | | | | | | | | | |
| Inspection Con | nments: | | | | | | | | | |
| Sample Numbe | er: 101 | Тур | e: R | A | rea: | 15.00 Slabs | PCI: 4 | 1 | | |
| Sample Comm | ents: | | | | | | | | | |
| 62 CORNE | R BREAK | | L | 2.00 | Slabs | | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: 362,704 SqFt **Branch:** AP APRON Use: **APRON** Name: Area: 4103 of 28 **Last Const.:** 4/1/2022 Section: From: To: -ACFamily: CA653-GA-AP-AC Zone: Category: Rank: P Surface: Area: 9,336 SqFt Length: 50 Ft Width: 187 Ft Slab Width: Slabs: 32 Slab Length: 16 Ft 18 Ft Joint Length: 867 Ft **Shoulder: Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1984 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 4/1/2022 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **TotalSamples:** 4 **Last Insp. Date:** 3/11/2019 Surveyed: 1 **Conditions:** PCI: NOTE: *** Pre-Construction PCI *** **Inspection Comments:** Sample Number: 101 Type: R 25.00 Slabs PCI: 5 Area: **Sample Comments:** CORNER BREAK L 62 3.00 Slabs 62 CORNER BREAK M 6.00 Slabs 62 CORNER BREAK Η 4.00 Slabs 63 LINEAR CR L 3.00 Slabs 63 LINEAR CR M 1.00 Slabs 65 JT SEAL DMG Н 25.00 Slabs 71 **FAULTING** 1.00 L Slabs 72 SHAT. SLAB L 5.00 Slabs 72 SHAT. SLAB M 11.00 Slabs 73 SHRINKAGE CR 15.00 N Slabs 74 JOINT SPALL 1.00 Slabs L 74 JOINT SPALL 4.00 Slabs M 74 JOINT SPALL Н 1.00 Slabs 75 CORNER SPALL L 4.00Slabs

75

CORNER SPALL

M

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** AP APRON Use: APRON 362,704 SqFt Area: Name: Section: 4104 of 28 From: To: -Last Const.: 1/1/1984 Surface: AC Family: CA653-GA-AP-AC Zone: Category: Rank: P 3,872 SqFt 52 Ft Width: 81 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: Street Type: Grade: Lanes: **Section Comments:** Work Date: 1/1/1984 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 3872.00 SqFt **PCI:** 43 Sample Number: 251 Type: R Area: **Sample Comments:** BLOCK CR L 3155.00 SqFt 43

BLOCK CR

PATCHING

RAVELING

43

50

52

M

L

L

559.00 SqFt

158.00 SqFt

3714.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP APRON Use: APRON 362,704 SqFt Branch: Area: Name: Section: 4105 of 28 From: To: -**Last Const.:** 1/1/1965 Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P 6,440 SqFt 72 Ft Width: 50 Ft Area: Length: Slab Length: 20 Ft Slab Width: Joint Length: Slabs: 13 25 Ft 202 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1965 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** PCI: 9 Sample Number: 101 Type: R Area: 14.00 Slabs **Sample Comments:** CORNER BREAK L 1.00 Slabs 62 LINEAR CR M 1.00 Slabs 63

JT SEAL DMG

SHAT. SLAB

SHAT. SLAB

65

72

72

Η

L

M

14.00

Slabs

7.00 Slabs

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: 362,704 SqFt **Branch:** AP APRON Use: **APRON** Name: Area: 4106 of 28 **Last Const.:** 12/1/2020 Section: From: To: Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P Area: 3,540 SqFt Length: 118 Ft Width: 30 Ft Slab Width: Slabs: 7 Slab Length: 20 Ft 25 Ft Joint Length: 171 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1965 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 12/1/2020 Work Type: Complete Reconstruction - PCC Code: CR-PC Is Major M&R: True **Last Insp. Date:** 3/11/2019 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: NOTE: *** Pre-Construction PCI *** **Inspection Comments:** Sample Number: 101 Type: R 25.00 Slabs PCI: 9 Area: **Sample Comments:** 63 LINEAR CR M 1.00 Slabs 65 JT SEAL DMG Η 25.00 Slabs 66 SMALL PATCH M 1.00 Slabs **PUMPING** 69 N 3.00 Slabs 71 **FAULTING** L 1.00 Slabs 72 SHAT. SLAB L 8.00 Slabs 72 SHAT. SLAB 15.00 Slabs M 72 SHAT. SLAB Н 1.00 Slabs 73 SHRINKAGE CR N 7.00 Slabs

74

JOINT SPALL

L

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** AP APRON Use: APRON 362,704 SqFt Area: Name: Section: 4110 of 28 From: To: -**Last Const.:** 1/1/1980 Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P 1,950 SqFt 75 Ft Width: 25 Ft Area: Length: 9 Slab Length: 12 Ft Slab Width: Joint Length: 160 Ft Slabs: 18 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1980 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 7 Sample Number: 103 Type: R Area: 8.00 Slabs **Sample Comments:** CORNER BREAK L 1.00 Slabs 62

LINEAR CR

JT SEAL DMG

SHAT. SLAB

63

65

72

M

Η

M

2.00 Slabs

8.00 Slabs

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP APRON APRON 362,704 SqFt **Branch:** Use: Name: Area: Section: 4115 of 28 From: To: -**Last Const.:** 1/1/1975 Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P 8,775 SqFt 140 Ft 48 Ft Area: Length: Width: Slab Length: 17 Ft Slab Width: Slabs: 21 25 Ft Joint Length: 476 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1975 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True TotalSamples: 1 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 101 Type: R 26.00 Slabs **PCI:** 1 Area: **Sample Comments:** CORNER BREAK L 1.00 Slabs 62 CORNER BREAK 62 M 1.00 Slabs LINEAR CR 63 L 1.00 Slabs 63 LINEAR CR M 3.00 Slabs 65 JT SEAL DMG Η 26.00 Slabs 72 SHAT. SLAB L 2.00 Slabs

16.00

4.00

M

Н

M

Slabs

Slabs

1.00 Slabs

72

72

74

SHAT. SLAB

SHAT. SLAB

JOINT SPALL

NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: EVB Name: APRON APRON 362,704 SqFt **Branch:** AP Use: Name: Area: Section: 4124 of 28 From: To: -**Last Const.:** 1/1/2002 Surface: PCC Family: DEFAULT Zone: Category: Rank: P 6,450 SqFt Area: Length: 100 Ft Width: 60 Ft Slab Length: Slab Width: Slabs: 52 12 Ft 10 Ft Joint Length: 920 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1997 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2002 Work Type: Complete Reconstruction - PCC Code: CR-PC Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 101 Type: R Area: 24.00 Slabs **PCI:** 73 **Sample Comments:** CORNER BREAK L 1.00 Slabs 62 63 LINEAR CR L 3.00 Slabs JT SEAL DMG Η 65 24.00 Slabs JOINT SPALL 74 L 1.00 Slabs 75 CORNER SPALL L 1.00 Slabs

75

CORNER SPALL

M

1.00

Slabs

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP APRON Use: APRON 362,704 SqFt **Branch:** Area: Name: Section: 4127 of 28 From: To: -Last Const.: 1/1/2019 Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P 1,560 SqFt 102 Ft Width: 15 Ft Area: Length: Slab Length: 5 Ft Slab Width: Joint Length: Slabs: 52 6 Ft 444 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Code: NU-IN Work Date: 1/1/1997 Work Type: New Construction - Initial Is Major M&R: True Work Type: Complete Reconstruction - PCC Work Date: 1/1/2019 Code: CR-PC Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 100 Type: R Area: 24.00 Slabs **PCI:** 87 **Sample Comments:**

JT SEAL DMG

JOINT SPALL

65

74

Н

L

24.00 Slabs

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP APRON Use: APRON 362,704 SqFt Branch: Area: Name: Section: 4130 of 28 From: To: -**Last Const.:** 1/1/1997 Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P 23,150 SqFt 100 Ft Width: 245 Ft Area: Length: Slab Length: 14 Ft Slab Width: Slabs: 110 15 Ft Joint Length: 3,038 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1997 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **TotalSamples:** 5 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions:** PCI: **Inspection Comments: PCI:** 47 Sample Number: 500 Type: R Area: 24.00 Slabs **Sample Comments:** LINEAR CR L 4.00 Slabs 63 LINEAR CR M 3.00 Slabs 63 JT SEAL DMG 65 Η 24.00 Slabs

71

73

75

75

FAULTING

SHRINKAGE CR

CORNER SPALL

CORNER SPALL

L

N

L

M

4.00 Slabs

1.00 Slabs

1.00 Slabs

Slabs

24.00

NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: EVB Name: AP APRON APRON 362,704 SqFt **Branch:** Use: Name: Area: Section: 4132 of 28 From: To: -**Last Const.:** 1/1/1997 Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P 17,074 SqFt 55 Ft 340 Ft Area: Length: Width: Slab Length: 20 Ft Slab Width: Slabs: 43 20 Ft Joint Length: 1,475 Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1997 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **TotalSamples:** 5 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 402 Type: R 18.00 Slabs **PCI:** 23 Area: **Sample Comments:**

Slabs

Slabs

Slabs

Slabs

Slabs

Slabs

2.00 Slabs

1.00 Slabs

18.00

2.00

2.00

8.00

2.00

CORNER BREAK L 1.00 Slabs 62 LINEAR CR L 2.00 Slabs 63 LINEAR CR 63 M 7.00

Η

L

L

L

M

L

M

65

66

67

70

72

74

74

JT SEAL DMG

SMALL PATCH

LARGE PATCH

SCALING

SHAT. SLAB

JOINT SPALL

JOINT SPALL

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP APRON Use: APRON 362,704 SqFt Branch: Area: Name: Section: 4135 of 28 From: To: -**Last Const.:** 1/1/1975 Surface: AC Family: CA653-GA-AP-AC Zone: Category: Rank: P 4,290 SqFt 88 Ft Width: 47 Ft Area: Length: Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1975 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True TotalSamples: 1 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions: PCI:** 33 **Inspection Comments:** 4290.00 SqFt Sample Number: 200 Type: R Area: **PCI:** 33 **Sample Comments:** ALLIGATOR CR 40.00 SqFt 41 M BLOCK CR M 728.00 SqFt 43 **DEPRESSION** 45 L 24.00 SqFt L & T CR 349.00 Ft

48

50

52

PATCHING

RAVELING

M

L

L

462.00 SqFt

| Network: EVB | | | Name: | NEW SMYRNA | BEACH MUNIC | IPAL AIRPORT | | |
|--|--------------------|--|--|---------------------|---------------|--------------|-----------------|----------|
| Branch: AP | N | Jame: APRO | N | Use: | APRON | Area: | 362,704 SqFt | |
| Section: 4140 | of 28 | From: | - | | То: - | | Last Const.: | 1/1/1980 |
| Surface: AC | Family: CA65 | 3-GA-AP-AC | Zone: | | Category: | | Rank: P | |
| Area: 37, | ,036 SqFt | Length: | 930 Ft | Width: | 40 Ft | | | |
| Slabs: | Slab Length: | Ft | Slab Widt | h: | Ft | Joint L | ength: F | t |
| Shoulder: | Street Type: | | Grade: | 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | | |
| Work Date: 1/1/1980 | Work Typ | pe: New Construction | on - Initial | C | ode: NU-IN | Is N | Major M&R: True | |
| | | | | | 1 2 | | | |
| Last Insp. Date: 1/24/20 | 02.2. | TotalSamples: | 9 | Surveve | ed: / | | | |
| | | TotalSamples: | 9 | Surveye | ed: 2 | | | |
| Conditions: PCI: 3: | | TotalSamples: | 9 | Surveye | e d: 2 | | | |
| Conditions: PCI: 3: Inspection Comments: | 5 | <u>.</u> | | | | | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 | | • | | Surveye 482.00 SqFt | PCI: | 38 | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 | 5 | <u>.</u> | | | | 38 | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 Sample Comments: | 5 | <u>.</u> | Area: 4 | | | 38 | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 Sample Comments: 43 BLOCK CR | 5 Type: | R A | Area: 4 SqFt | | | 38 | | |
| Inspection Comments: Sample Number: 202 Sample Comments: 43 BLOCK CR | Type: | R A482.00 90.00 | Area: 4 SqFt SqFt | | | 38 | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 Sample Comments: 43 BLOCK CR 52 RAVELING 57 WEATHERING | Type: M L | R 4482.00 90.00 4392.00 | Area: 4 SqFt SqFt SqFt | | | | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 Sample Comments: 43 BLOCK CR 52 RAVELING 57 WEATHERING Sample Number: 316 | Type: M L M | R 4482.00 90.00 4392.00 | Area: 4 SqFt SqFt SqFt | 482.00 SqFt | PCI: | | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 Sample Comments: 43 BLOCK CR 52 RAVELING 57 WEATHERING Sample Number: 316 Sample Comments: | Type: M L M | R 4482.00 90.00 4392.00 | Area: 4 SqFt SqFt SqFt Area: 4 | 482.00 SqFt | PCI: | | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 Sample Comments: 43 BLOCK CR 52 RAVELING 57 WEATHERING Sample Number: 316 Sample Comments: | Type: M L M Type: | R 4482.00 90.00 4392.00 R A | Area: 4 SqFt SqFt SqFt Area: 4 | 482.00 SqFt | PCI: | | | |
| Conditions: PCI: 3: Inspection Comments: Sample Number: 202 Sample Comments: 43 BLOCK CR 52 RAVELING 57 WEATHERING Sample Number: 316 Sample Comments: 43 BLOCK CR | Type: M L M Type: | R 4482.00 90.00 4392.00 R 4073.00 | Area: 4 SqFt SqFt SqFt 4 SqFt SqFt SqFt SqFt | 482.00 SqFt | PCI: | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: Branch: AP APRON Use: APRON 362,704 SqFt Area: Name: Section: 4145 of 28 From: To: -**Last Const.:** 1/1/1986 Surface: AC Family: CA653-GA-AP-AC Zone: Category: Rank: P 17,888 SqFt 500 Ft Width: 35 Ft Area: Length: Slab Width: Slabs: Slab Length: Ft Joint Length: Ft Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1986 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 TotalSamples: 4 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 5125.00 SqFt **PCI:** 65 Sample Number: 565 Type: R Area: **Sample Comments:** L 385.00 Ft L & T CR 48 L & T CR M 64.00 Ft 48

769.00 SqFt

4356.00 SqFt

L

L

RAVELING

WEATHERING

52

57

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP APRON Use: APRON 362,704 SqFt Branch: Area: Name: Section: 4160 of 28 From: To: -**Last Const.:** 1/1/1975 Surface: AC Family: CA653-GA-AP-AC Zone: Category: Rank: P 10,001 SqFt 25 Ft Width: 270 Ft Area: Length: Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1975 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **TotalSamples:** 2 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions: PCI:** 41 **Inspection Comments:** 4475.00 SqFt **PCI:** 41 Sample Number: 219 Type: R Area: **Sample Comments:** BLOCK CR L 774.00 SqFt 43 BLOCK CR Η 32.00 SqFt 43 DEPRESSION 45 L 16.00 SqFt

48

52

52

54

L & T CR

RAVELING

RAVELING

SHOVING

L

L

M

L

634.00 Ft

4251.00 SqFt

224.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP APRON APRON 362,704 SqFt **Branch:** Use: Name: Area: Section: 4165 of 28 From: To: -**Last Const.:** 1/1/1991 Surface: PCC Family: CA653-GA-AP-PCC Zone: Category: Rank: P 9,517 SqFt 228 Ft 40 Ft Area: Length: Width: Slab Length: 20 Ft Slab Width: Slabs: 23 21 Ft Joint Length: 622 Ft **Shoulder: Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1991 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True TotalSamples: 1 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 100 Type: R 22.00 Slabs **PCI:** 10 Area: **Sample Comments:** L LINEAR CR 3.00 Slabs 63 LARGE PATCH Η 67 2.00 Slabs 70 **SCALING** M 7.00 Slabs

71

72

72

73

74

75

FAULTING

SHAT. SLAB

SHAT. SLAB

JOINT SPALL

SHRINKAGE CR

CORNER SPALL

L

L

M

N

L

L

4.00

15.00

3.00

19.00

1.00

Slabs

Slabs

Slabs

Slabs

Slabs

3.00 Slabs

| Network: EVB | | Name: | NEW SMYRNA BE | ACH MUNICIPAL A | IRPORT |
|----------------------------|---------------------|------------------------|-----------------|-----------------|------------------------|
| Branch: AP | Name: | APRON | Use: A | APRON Ar | rea: 362,704 SqFt |
| Section: 4190 | of 28 | rom: - | | То: - | Last Const.: 1/1/2012 |
| Surface: PCC | Family: CA653-GA-AF | P-PCC Zone: | | Category: | Rank: P |
| Area: 38,65 | 56 SqFt Length: | 1,025 Ft | Width: | 30 Ft | |
| Slabs: 258 | Slab Length: | 10 Ft Slab W | 'idth: 1 | 5 Ft | Joint Length: 4,070 Ft |
| Shoulder: | Street Type: | Grade: | 0 | | Lanes: 0 |
| Section Comments: | | | | | |
| Work Date: 1/1/2012 | Work Type: New | Construction - Initial | Code | : NU-IN | Is Major M&R: True |
| Last Insp. Date: 1/24/2022 | 2 TotalS: | amples: 10 | Surveyed: | 3 | |
| Conditions: PCI: 90 | | • | • | | |
| Inspection Comments: | | | | | |
| Sample Number: 600 | Type: R | Area: | 12.00 Slabs | PCI: 98 | |
| Sample Comments: | Type. K | 711011 | 12.00 51465 | 101. 30 | |
| 65 JT SEAL DMG | L | 12.00 Slabs | | | |
| Sample Number: 603 | Type: R | Area: | 20.00 Slabs | PCI: 94 | |
| Sample Comments: | Type. | 211011 | 20.00 51465 | 101. 7. | |
| 65 JT SEAL DMG | L | 20.00 Slabs | | | |
| 74 JOINT SPALL | M | 1.00 Slabs | | | |
| Sample Number: 608 | Type: R | Area: | 16.00 Slabs | PCI: 78 | |
| Sample Comments: | | | | | |
| 55 JT SEAL DMG | L | 16.00 Slabs | | | |
| 71 FAULTING | L | 2.00 Slabs | | | |
| 74 JOINT SPALL | L | 1.00 Slabs | | | |
| 75 CORNER SPALL | L | 1.00 Slabs | | | |
| 75 CORNER SPALL | M | 1.00 Slabs | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: AP RU RUN-UP APRON Use: APRON 46,282 SqFt **Branch:** Area: Name: Section: 5105 of 1 From: To: -**Last Const.:** 1/1/1943 Surface: AC Family: CA653-GA-AP-AC Zone: Category: Rank: P 46,282 SqFt 325 Ft Width: 150 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1943 Code: NU-IN Work Type: New Construction - Initial Is Major M&R: True **TotalSamples:** 10 Surveyed: 1 **Last Insp. Date:** 1/24/2022 **Conditions:** PCI: **Inspection Comments:** 4500.00 SqFt **PCI:** 32 Sample Number: 101 Type: R Area: **Sample Comments:** BLOCK CR 4490.00 SqFt 43 M

BLOCK CR

RAVELING

RAVELING

43

52

52

Η

L

M

10.00 SqFt

4050.00 SqFt

| Netwo | ork: EVB | | | | Nan | ne: NEV | V SMYRNA | BEACH MU | INICIPA | AL AIRPORT | | | |
|---------|-----------------------|--------------|---------|-----------------|-----------|-------------|-----------|------------|----------|------------|-------------|----------------------|----------|
| Branc | h: AP S | | Name: | SOUT | TH APR | .ON | Use: | APRON | | Area: | 10 |)1,441 SqFt | |
| Section | n: 4215 | of 2 | | From: | - | | | To: - | | | | Last Const.: | 1/1/1943 |
| Surfac | e: PCC | Family: C. | A653-GA | -AP-PCC | Zon | ie: | | Catego | ry: | | | Rank: P | |
| Area: | 56,4 | 50 SqFt | Lengt | h: | 585 I | Ft | Width: | 9 | 6 Ft | | | | |
| Slabs: | | Slab Length | _ | 20 Ft | | Slab Width: | | 20 Ft | | Joint L | ength• | 4,935 Ft | |
| Should | | · · | | 2011 | | Grade: 0 | | 2011 | | Lanes: | 0 | 1,755 11 | |
| | n Comments: | Street Type: | | | | Grade: 0 | | | | Lanes: | U | | |
| | Date: 1/1/1943 | Work | Type: N | ew Construction | on - Init | tial | | ode: NU-IN | J | Is N | Maior V | 1&R: True | |
| | | | | | | | | | <u> </u> | | - Lujor III | | |
| Last I | nsp. Date: 1/24/202 | 22 | Tota | alSamples: | 7 | | Surveye | ed: 2 | | | | | |
| Condi | tions: PCI: 9 | | | | | | | | | | | | |
| Inspec | ction Comments: | | | | | | | | | | | | |
| Samnl | le Number: 301 | Type: | R | | Area: | 20 | .00 Slabs | P | CI: 8 | | | | |
| | | Type. | K | F | Aica. | 20 | .00 Slaus | 1 | CI. 0 | | | | |
| Sampi | le Comments: | | | | | | | | | | | | |
| 62 | CORNER BREAK | | M | 2.00 | Slabs | | | | | | | | |
| 63 | LINEAR CR | | L | 4.00 | Slabs | | | | | | | | |
| 63 | LINEAR CR | | M | 3.00 | Slabs | | | | | | | | |
| 65 | JT SEAL DMG | | Н | 20.00 | Slabs | | | | | | | | |
| 66 | SMALL PATCH | | Н | 1.00 | Slabs | | | | | | | | |
| 72 | SHAT. SLAB | | L | 3.00 | Slabs | | | | | | | | |
| 72 | SHAT. SLAB | | M | 5.00 | Slabs | | | | | | | | |
| 72 | SHAT. SLAB | | Н | 5.00 | Slabs | | | | | | | | |
| 73 | SHRINKAGE CR | | N | 6.00 | Slabs | | | | | | | | |
| 74 | JOINT SPALL | | L | 1.00 | Slabs | | | | | | | | |
| 74 | JOINT SPALL | | M | 3.00 | Slabs | | | | | | | | |
| 75 | CORNER SPALL | | M | 3.00 | Slabs | | | | | | | | |
| Sampl | le Number: 304 | Type: | R | A | Area: | 20 | .00 Slabs | P | CI: 10 | 0 | | | |
| Sampl | le Comments: | | | | | | | | | | | | |
| 62 | CORNER BREAK | | L | 1.00 | Slabs | | | | | | | | |
| 63 | LINEAR CR | | L | 2.00 | Slabs | | | | | | | | |
| 65 | JT SEAL DMG | | H | 20.00 | Slabs | | | | | | | | |
| 72 | SHAT. SLAB | | L | 7.00 | Slabs | | | | | | | | |
| 72 | SHAT. SLAB | | M | 11.00 | Slabs | | | | | | | | |
| 73 | SHRINKAGE CR | | N | 3.00 | Slabs | | | | | | | | |
| 74 | JOINT SPALL | | M | | Slabs | | | | | | | | |
| 74 | JOINT SPALL | | H | | Slabs | | | | | | | | |
| 75 | CORNER SPALL | | L | | Slabs | | | | | | | | |

| Networ | k: EVB | | | | Nar | ne: | NEW SMYRN | A BEACH | MUNICIP | 'AL AIRPORT | | |
|---------|-----------------------|--------------|-----------|--------------|-----------|----------|-------------|---------|---------|--------------|--------------|------------|
| Branch | : AP SE | | Name: | SOUT | HEAST | ΓAPRON | Use: | APRO | N | Area: | 8,835 SqFt | |
| Section | : 4220 | of 1 | | From: | - | | | То | : - | | Last Const.: | 12/25/1999 |
| Surface | : PCC | Family: C. | A653-GA-A | P-PCC | Zon | ie: | | Ca | tegory: | | Rank: P | |
| Area: | | 8,835 SqFt | Length: | | 375 I | ₹t | Width: | | 25 Ft | | | |
| Slabs: | 52 | Slab Length | : | 13 Ft | | Slab Wid | th: | 13 Ft | | Joint Length | : 1,042 Ft | |
| Should | er: | Street Type: | | | | Grade: | 0 | | | Lanes: 0 | | |
| Section | Comments: | | | | | | | | | | | |
| | Date: 12/25/199 | 09 Work | Tyne: New | Construction | on - Init | ial | | Code: N | I I-IN | Is Major | M&R: True | |
| | Jacc. 12/23/177 | WOIR | Type: New | Constructiv | JII 11111 | .141 | | couc. 1 | O 11 V | 13 1/14/01 | WICK. True | |
| Last In | sp. Date: 1/24 | /2022 | Totals | Samples: | 2 | | Surve | yed: 2 | | | | |
| Conditi | ions: PCI: | 1 | | | | | | | | | | |
| Inspect | ion Comments: | | | | | | | | | | | |
| Sample | Number: 100 | Type: | R | A | Area: | | 16.00 Slabs | | PCI: 0 | 1 | | |
| Sample | Comments: | | | | | | | | | | | |
| 62 | CORNER BREA | AK | Н | 1.00 | Slabs | | | | | | | |
| 63 | LINEAR CR | | L | 1.00 | Slabs | | | | | | | |
| 65 | JT SEAL DMG | | H | 16.00 | Slabs | | | | | | | |
| 72 | SHAT. SLAB | | M | 2.00 | Slabs | | | | | | | |
| 72 | SHAT. SLAB | | H | 13.00 | Slabs | | | | | | | |
| 73 | SHRINKAGE C | CR | N | 1.00 | Slabs | | | | | | | |
| Sample | Number: 101 | Type: | R | A | Area: | | 24.00 Slabs | | PCI: 2 | : | | |
| Sample | Comments: | | | | | | | | | | | |
| 62 | CORNER BREA | AK | M | 2.00 | Slabs | | | | | | | |
| 62 | CORNER BREA | ΑK | H | 2.00 | Slabs | | | | | | | |
| 63 | LINEAR CR | | L | 1.00 | Slabs | | | | | | | |
| 63 | LINEAR CR | | M | 5.00 | Slabs | | | | | | | |
| 65 | JT SEAL DMG | | H | 24.00 | Slabs | | | | | | | |
| 72 | SHAT. SLAB | | L | 1.00 | Slabs | | | | | | | |
| 72 | SHAT. SLAB | | M | 10.00 | Slabs | | | | | | | |
| 72 | SHAT. SLAB | | Н | 5.00 | Slabs | | | | | | | |
| | SHRINKAGE C | CR | N | 3.00 | Slabs | | | | | | | |
| 74 . | JOINT SPALL | | L | 1.00 | Slabs | | | | | | | |

M 1.00 Slabs

74

JOINT SPALL

| Netwo | ork: EVB | | | Name: | NEW SMYRNA E | BEACH MUNICIPA | L AIRPORT |
|------------|---------------------------|--------------|---------|-----------------------------|----------------|----------------|---------------------------|
| Branc | ch: RW 11-29 | | Name: | RUNWAY 11-29 | Use: | RUNWAY | Area: 323,925 SqFt |
| Section | on: 6105 | of 1 | | From: - | | То: - | Last Const.: 1/1/2014 |
| Surfa | ce: AAC | Family: C. | A653-GA | -RW-AAC- Zone: | | Category: | Rank: P |
| | | | PC | | | <i>.</i> | |
| Area: | | 25 SqFt | Leng | • | Width: | 75 Ft | |
| Slabs | | Slab Length | | | Width: | Ft | Joint Length: Ft |
| Shoul | der: | Street Type: | : | Gra | de: 0 | | Lanes: 0 |
| Section | on Comments: | | | | | | |
| Work | Date: 1/1/1977 | Work | Type: N | lew Construction - Initial | Coo | de: NU-IN | Is Major M&R: True |
| Work | Date: 1/1/2014 | Work | Type: M | fill and Overlay | Coo | de: ML-OVL | Is Major M&R: True |
| Last 1 | Insp. Date: 1/24/2022 | 2 | Tot | alSamples: 86 | Surveyed | : 18 | |
| Cond | itions: PCI: 81 | | | | | | |
| Inspe | ction Comments: | | | | | | |
| Samp | le Number: 102 | Type: | R | Area: | 3750.00 SqFt | PCI: 84 | |
| • | le Comments: | • • | | | - | | |
| 48 | L & T CR | | L | 37.00 Ft | | | |
| 48 56 | SWELLING | | L L | 5.00 Ft 5.00 SqFt | | | |
| 57 | WEATHERING | | L | 3562.00 SqFt | | | |
| 57 | WEATHERING | | M | 188.00 SqFt | | | |
| _ | le Number: 107 | Type: | R | Area: | 3750.00 SqFt | PCI: 76 | |
| Samp | le Comments: | | | | | | |
| 48 | L & T CR | | L | 202.00 Ft | | | |
| 57 | WEATHERING | | L M | 3562.00 SqFt | | | |
| 57 Samm | WEATHERING le Number: 111 | Tymas | R | 188.00 SqFt Area: | 2750 00 S a Et | PCI: 80 | |
| - | le Comments: | Туре: | K | Area: | 3750.00 SqFt | FCI: 80 | |
| _ | | | | | | | |
| 48 | L & T CR | | L | 137.00 Ft | | | |
| 57 57 | WEATHERING WEATHERING | | L M | 3562.00 SqFt 188.00 SqFt | | | |
| Samp | le Number: 115 | Type: | R | Area: | 3750.00 SqFt | PCI: 81 | |
| Samp | le Comments: | | | | - | | |
| 48 | L & T CR | | L | 114.00 Ft | | | |
| 57 | WEATHERING | | L | 3562.00 SqFt | | | |
| 57 | WEATHERING | | M | 188.00 SqFt | | | |
| _ | le Number: 119 | Type: | R | Area: | 3750.00 SqFt | PCI: 78 | |
| Samp | le Comments: | | | | | | |
| 48 | L & T CR | | L | 15.00 Ft | | | |
| 50 | PATCHING | | L | 172.00 SqFt | | | |
| 57 57 | WEATHERING WEATHERING | | L M | 3399.00 SqFt 179.00 SqFt | | | |
| | le Number: 125 | Туре: | R | Area: | 3750.00 SqFt | PCI: 82 | |
| _ | le Comments: | - ypc. | IX. | 122 041 | 2,20,00 Sq1 t | 101. 02 | |
| 48 | L & T CR | | L | 137.00 Ft | | | |
| 57 | WEATHERING | | L | 3745.00 SqFt | | | |
| 57 | WEATHERING | | M | 5.00 SqFt | | | |
| _ | le Number: 131 | Type: | R | Area: | 3750.00 SqFt | PCI: 77 | |
| Samp | le Comments: | | | | | | |
| 48 | L & T CR | | L | 175.00 Ft | | | |
| 57 | WEATHERING | | L | 3562.00 SqFt | | | |
| 57 | WEATHERING | T | M | 188.00 SqFt | 2750 00 C E | DOL 50 | |
| _ | le Number: 135 | Type: | R | Area: | 3750.00 SqFt | PCI: 78 | |
| Samp | le Comments: | | | | | | |

| 48 | L & T CR | | L | 137.00 | Ft | | | |
|----------|-----------------|-------|--------|----------|-------|--------------|--------|----|
| 57 | WEATHERING | | L | 3188.00 | | | | |
| 57 | WEATHERING | | M | 562.00 | | | | |
| | | | | | | 2550 00 G F: | D.C.I. | 02 |
| Samp | ole Number: 139 | Type: | | R A | Area: | 3750.00 SqFt | PCI: | 83 |
| Samp | ole Comments: | | | | | | | |
| | | | | | | | | |
| 48 | L & T CR | | L | 53.00 | | | | |
| 57 | WEATHERING | | L | 3188.00 | | | | |
| 57 | WEATHERING | | M | 562.00 | SqFt | | | |
| Samn | ole Number: 143 | Type: | | R A | Area: | 3750.00 SqFt | PCI: | 83 |
| _ | | JF | | | | 1 | | |
| Samp | ole Comments: | | | | | | | |
| 48 | L & T CR | | L | 50.00 | Et | | | |
| 57 | WEATHERING | | L | 3188.00 | | | | |
| 57 | WEATHERING | | M | 562.00 | | | | |
| | | | | | Sqrt | | | |
| Samp | ole Number: 147 | Type: | | R A | Area: | 3750.00 SqFt | PCI: | 86 |
| Samp | ole Comments: | | | | | | | |
| | | | | | | | | |
| 48 | L & T CR | | L | 25.00 | | | | |
| 57 | WEATHERING | | L | 3562.00 | | | | |
| 57 | WEATHERING | | M | 188.00 | SqFt | | | |
| Samn | ole Number: 155 | Type: | | | \rea: | 3750.00 SqFt | PCI: | 86 |
| _ | | rype. | | <i>F</i> | u ca. | 3730.00 Sq11 | 1 (1, | |
| Samp | ole Comments: | | | | | | | |
| 48 | L & T CR | | L | 33.00 | Et | | | |
| 48 57 | WEATHERING | | L | 3562.00 | | | | |
| 57 | | | L M | | | | | |
| | WEATHERING | | | 188.00 | SqFt | | | |
| Samp | ole Number: 161 | Type: | | R A | Area: | 3750.00 SqFt | PCI: | 79 |
| Samn | ole Comments: | | | | | | | |
| Sump | or comments. | | | | | | | |
| 48 | L & T CR | | L | 143.00 | Ft | | | |
| 57 | WEATHERING | | L | 3562.00 | SqFt | | | |
| 57 | WEATHERING | | M | 188.00 | | | | |
| Samn | ole Number: 165 | Type: | | | \rea: | 3750.00 SqFt | PCI: | 86 |
| _ | | Type. | | K F | Mea. | 3730.00 Sqrt | ICI. | 80 |
| Samp | ole Comments: | | | | | | | |
| 40 | I O TOD | | | 46.00 | T. | | | |
| 48 | L & T CR | | L | 46.00 | | | | |
| 57 | WEATHERING | | L | 3562.00 | | | | |
| 57 | WEATHERING | | M | 188.00 | SqFt | | | |
| Samp | ole Number: 170 | Type: | | R A | \rea: | 3750.00 SqFt | PCI: | 79 |
| Samn | ole Comments: | | | | | | | |
| Samp | de Comments. | | | | | | | |
| 48 | L & T CR | | L | 79.00 | Ft | | | |
| 48 | L & T CR | | M | 7.00 | | | | |
| 57 | WEATHERING | | L | 3562.00 | | | | |
| 57 | WEATHERING | | M | 188.00 | | | | |
| | | T | | | | 2750 00 C E | DOI | 01 |
| Samp | ole Number: 175 | Type: | | R A | Area: | 3750.00 SqFt | PCI: | 81 |
| Samp | ole Comments: | | | | | | | |
| | T 0 m | | | | _ | | | |
| 48 | L & T CR | | L | 122.00 | | | | |
| 57 | WEATHERING | | L | 3562.00 | | | | |
| 57 | WEATHERING | | M | 188.00 | SqFt | | | |
| Samp | ole Number: 181 | Type: | | R A | Area: | 3750.00 SqFt | PCI: | 73 |
| _ | | | | | | 1 | | |
| samp | ole Comments: | | | | | | | |
| 48 | L & T CR | | L | 267.00 | Ft | | | |
| 57 | WEATHERING | | L | 3562.00 | | | | |
| 57 | WEATHERING | | M | 188.00 | | | | |
| | | 7E | | | | 2750 00 C E | D.C.I | 77 |
| Samp | ole Number: 184 | Type: | | R A | Area: | 3750.00 SqFt | PCI: | 11 |
| Samp | ole Comments: | | | | | | | |
| | | | | | _ | | | |
| 48 | L & T CR | | L | 185.00 | | | | |
| 57 | WEATHERING | | L | 3562.00 | - | | | |
| 57 | WEATHERING | | M | 188.00 | SqFt | | | |
| | | | | | | | | |

| Network: EVB | | Name: | NEW SMYRNA | BEACH MUNICIPA | AL AIRPORT | |
|---|------------------|------------------------------|---------------|----------------|---------------|------------------------------|
| Branch: RW 2-20 | Name: | RUNWAY 2-20 | Use: | RUNWAY | Area: | 387,523 SqFt |
| Section: 6405 | of 6 | From: - | | То: - | | Last Const.: 1/1/1943 |
| Surface: AC Far | mily: CA653-GA-R | W-AC Zone: | | Category: | | Rank: P |
| Area: 78,400 Sc | qFt Length: | 850 Ft | Width: | 100 Ft | | |
| Slabs: Sl | ab Length: | Ft Slab | Width: | Ft | Joint Length: | Ft |
| Shoulder: St | treet Type: | Grad | de: 0 | | Lanes: 0 | |
| Section Comments: | | | | | | |
| Work Date: 1/1/1943 | Work Type: New | Construction - Initial | C | ode: NU-IN | Is Major | M&R: True |
| Last Insp. Date: 1/24/2022 | TotalS | Samples: 16 | Surveye | d: 5 | | |
| Conditions: PCI: 33 | | | | | | |
| Inspection Comments: | | | | | | |
| Sample Number: 102 | Type: R | Area: | 5000.00 SqFt | PCI: 32 | 2 | |
| Sample Comments: | турс. К | Airea. | 3000.00 Sq1 t | 101. 3. | _ | |
| 43 BLOCK CR | M | 5000.00 SqFt | | | | |
| 45 DEPRESSION | L | 68.00 SqFt | | | | |
| 52 RAVELING | L | 4500.00 SqFt | | | | |
| 52 RAVELING | M | 500.00 SqFt | 5000 00 G F: | DCI 2 | 7 | |
| Sample Number: 104 Sample Comments: | Type: R | Area: | 5000.00 SqFt | PCI: 3' | / | |
| - | | 5000 00 G F | | | | |
| 43 BLOCK CR52 RAVELING | M L | 5000.00 SqFt 4500.00 SqFt | | | | |
| 52 RAVELING | M | 500.00 SqFt | | | | |
| Sample Number: 107 | Type: R | Area: | 5000.00 SqFt | PCI: 3' | 7 | |
| Sample Comments: | | | | | | |
| 43 BLOCK CR | M | 5000.00 SqFt | | | | |
| 52 RAVELING | L | 4500.00 SqFt | | | | |
| 52 RAVELING | M | 500.00 SqFt | | | | |
| Sample Number: 111 | Type: R | Area: | 5000.00 SqFt | PCI: 32 | 2 | |
| Sample Comments: | | | | | | |
| 43 BLOCK CR | M | 5000.00 SqFt | | | | |
| 45 DEPRESSION | L | 72.00 SqFt | | | | |
| 52 RAVELING | L | 4500.00 SqFt | | | | |
| 52 RAVELING | M | 500.00 SqFt | | | | |
| Sample Number: 114 | Type: R | Area: | 3400.00 SqFt | PCI: 2' | 7 | |
| Sample Comments: | | | | | | |
| 43 BLOCK CR | M | 3400.00 SqFt | | | | |
| 52 RAVELING | L | 3060.00 SqFt | | | | |
| 52 RAVELING | M | 340.00 SqFt | | | | |
| 53 RUTTING | L | 85.00 SqFt | | | | |
| 53 RUTTING | M | 85.00 SqFt | | | | |

| Netwo | ork: EVB | | | | Nar | ne: NI | EW SMYRN. | A BEACH MUNIC | IPAL AI | RPORT | | | |
|----------|--------------------------------|--------------|---------|--------------------|--------------|------------|------------|---------------|---------|----------|---------|-------------|--------------|
| Branc | ch: RW 2-20 | | Name: | RUNV | VAY 2- | -20 | Use: | RUNWAY | Arc | ea: | 38 | 87,523 SqFt | |
| Sectio | on: 6425 | of 6 | | From: | - | | | То: - | | | | Last Cons | t.: 1/1/1943 |
| Surfa | ce: AC | Family: CA | A653-GA | -RW-AC | Zon | ie: | | Category: | | | | Rank: P | |
| Area: | 254,78 | 39 SqFt | Lengt | h: | 2,700 I | Ft | Width: | 100 Ft | | | | | |
| Slabs | : | Slab Length | : | Ft | | Slab Width | : | Ft | | Joint Le | ngth: | | Ft |
| Shoul | lder: | Street Type: | | | | Grade: |) | | | Lanes: | 0 | | |
| Sectio | on Comments: | • • | | | | | | | | | | | |
| | | 33 71 | 7F N | | т ' | . 1 | | C. L. MILDI | | T. A. | r | 40D. T | |
| | Date: 1/1/1943 | | | ew Construction | | tial | | Code: NU-IN | | 1s N | lajor N | 1&R: True | |
| | Insp. Date: 1/24/2022 | 2 | Tot | alSamples: | 51 | | Survey | yed: 12 | | | | | |
| Condi | itions: PCI: 34 | | | | | | | | | | | | |
| Inspe | ction Comments: | | | | | | | | | | | | |
| Samp | le Number: 120 | Type: | R | A | Area: | 50 | 00.00 SqFt | PCI: | 37 | | | | |
| Samp | le Comments: | | | | | | | | | | | | |
| 43 | BLOCK CR | | M | 5000.00 | SqFt | | | | | | | | |
| 52 | RAVELING | | L | 4500.00 | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 500.00 | SqFt | | | | | | | | |
| Samp | le Number: 124 | Type: | R | A | Area: | 50 | 00.00 SqFt | PCI: | 37 | | | | |
| Samp | le Comments: | | | | | | | | | | | | |
| 43 | BLOCK CR | | M | 5000.00 | SaFt | | | | | | | | |
| 52 | RAVELING | | L | 4500.00 | | | | | | | | | |
| 52 | RAVELING | | M | 500.00 | SqFt | | | | | | | | |
| Samp | le Number: 128 | Type: | R | A | Area: | 50 | 00.00 SqFt | PCI: | 37 | | | | |
| Samp | le Comments: | | | | | | | | | | | | |
| 43 | BLOCK CR | | M | 5000.00 | SqFt | | | | | | | | |
| 52 | RAVELING | | L | 5000.00 | - | | | | | | | | |
| 53 | RUTTING | | L | 75.00 | SqFt | | | | | | | | |
| _ | le Number: 132 | Type: | R | A | Area: | 50 | 00.00 SqFt | PCI: | 37 | | | | |
| Samp | le Comments: | | | | | | | | | | | | |
| 43 | BLOCK CR | | M | 4998.00 | | | | | | | | | |
| 50 52 | PATCHING RAVELING | | H L | 4998.00 | SqFt SqFt | | | | | | | | |
| | lle Number: 136 | Type: | R | | Area: | 50 | 00.00 SqFt | PCI: | 38 | | | | |
| - | le Comments: | Type. | K | F | Mea. | 30 | 00.00 Sqrt | rci. | 36 | | | | |
| _ | | | | 2000.00 | G E | | | | | | | | |
| 43 43 | BLOCK CR BLOCK CR | | L M | 3000.00 2000.00 | | | | | | | | | |
| 45 | DEPRESSION | | L | 90.00 | - | | | | | | | | |
| 52 | RAVELING | | L | 5000.00 | | | | | | | | | |
| Samp | le Number: 143 | Type: | R | A | Area: | 50 | 00.00 SqFt | PCI: | 34 | | | | |
| Samp | le Comments: | | | | | | | | | | | | |
| 43 | BLOCK CR | | M | 5000.00 | SqFt | | | | | | | | |
| 52 | RAVELING | | L | 4000.00 | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 1000.00 | | | | | | | | | |
| Samp | le Number: 146 | Type: | R | A | Area: | 50 | 00.00 SqFt | PCI: | 29 | | | | |
| Samp | le Comments: | | | | | | | | | | | | |
| 43 | BLOCK CR | | M | 5000.00 | - | | | | | | | | |
| 52 | RAVELING | | L | 3500.00 | | | | | | | | | |
| 52 53 | RAVELING RUTTING | | M L | 1500.00 60.00 | | | | | | | | | |
| | | Т | | | | 50 | 00 00 S=E4 | DCI. | 22 | | | | |
| _ | le Number: 153 le Comments: | Type: | R | A | Area: | 50 | 00.00 SqFt | PCI: | 33 | | | | |
| _ | | | М | 5000.00 | C-F | | | | | | | | |
| 43 52 | BLOCK CR RAVELING | | M L | 5000.00 3750.00 | | | | | | | | | |
| 52 | RAVELING | | M | 1250.00 | | | | | | | | | |
| | | | | 0 | 1 | | | | | | | | |

| Sample Number: 158 | Type: R | Area: | 5000.00 SqFt | PCI: 32 | |
|--------------------|---------|--------------|--------------|---------|--|
| Sample Comments: | •• | | • | | |
| 43 BLOCK CR | M | 4994.00 SqFt | | | |
| 50 PATCHING | M | 6.00 SqFt | | | |
| 52 RAVELING | L | 4245.00 SqFt | | | |
| 52 RAVELING | M | 749.00 SqFt | | | |
| Sample Number: 164 | Type: R | Area: | 5000.00 SqFt | PCI: 32 | |
| Sample Comments: | | | | | |
| 43 BLOCK CR | M | 4976.00 SqFt | | | |
| 50 PATCHING | M | 24.00 SqFt | | | |
| 52 RAVELING | L | 3981.00 SqFt | | | |
| 52 RAVELING | M | 995.00 SqFt | | | |
| Sample Number: 168 | Type: R | Area: | 5000.00 SqFt | PCI: 26 | |
| Sample Comments: | | | | | |
| 43 BLOCK CR | M | 4750.00 SqFt | | | |
| 50 PATCHING | Н | 250.00 SqFt | | | |
| 52 RAVELING | L | 3325.00 SqFt | | | |
| 52 RAVELING | M | 1425.00 SqFt | | | |
| Sample Number: 178 | Type: R | Area: | 5000.00 SqFt | PCI: 32 | |
| Sample Comments: | | | | | |
| 43 BLOCK CR | M | 5000.00 SqFt | | | |
| 45 DEPRESSION | L | 110.00 SqFt | | | |
| 52 RAVELING | L | 4000.00 SqFt | | | |
| 52 RAVELING | M | 1000.00 SqFt | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: RW 2-20 RUNWAY 2-20 Use: RUNWAY 387,523 SqFt **Branch:** Area: Name: Section: 6427 of 6 From: To: -**Last Const.:** 1/1/2014 Surface: AC Family: CA653-GA-RW-AC Zone: Category: Rank: P Width: 100 Ft Area: 11,862 SqFt Length: 120 Ft Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Code: NU-IN Work Date: 1/1/1943 Work Type: New Construction - Initial Is Major M&R: True Work Date: 1/1/2014 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 171 Type: R Area: 4858.00 SqFt **PCI:** 89 **Sample Comments:** L & T CR L 4.00 Ft 48 57 WEATHERING L 4761.00 SqFt

WEATHERING

57

M

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: RW 2-20 RUNWAY 2-20 Use: RUNWAY 387,523 SqFt **Branch:** Area: Name: Section: 6430 of 6 From: To: -**Last Const.:** 1/1/1977 Surface: AC Family: CA653-GA-RW-AC Zone: Category: Rank: P 5,000 SqFt 150 Ft Width: 100 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: Street Type: Grade: Lanes: **Section Comments:** Work Date: 1/1/1977 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 1/24/2022 TotalSamples: 1 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 5000.00 SqFt Sample Number: 142 Type: R Area: **PCI:** 38 **Sample Comments:** BLOCK CR 3000.00 SqFt 43 M

L & T CR

RAVELING

RAVELING

48

52

52

M

L

M

106.00 Ft

4250.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: RW 2-20 RUNWAY 2-20 Use: RUNWAY 387,523 SqFt **Branch:** Area: Name: Section: 6435 of 6 From: To: -**Last Const.:** 1/1/2014 Surface: AAC Family: CA653-GA-RW-AAC-Zone: Category: Rank: P Area: 12,472 SqFt Length: 125 Ft Width: 100 Ft Ft Slab Width: Ft Ft Slabs: Slab Length: Joint Length: Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1977 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2014 Work Type: Mill and Overlay Code: ML-OVL Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 2 Surveyed: 1 PCI: **Conditions: Inspection Comments:** Sample Number: 138 6230.00 SqFt **PCI:** 83 Type: R Area: **Sample Comments:** 48 L & T CR L 114.00 Ft WEATHERING L 5296.00 SqFt 57 57 WEATHERING M 934.00 SqFt

| Network: | EVB | | | Nar | ne: NEV | V SMYRNA | BEACH MUNIC | IPAL AIRPORT | | | |
|--|--|------------|---------------|---|-------------|-----------|-------------|--------------|---------|--------------|----------|
| Branch: | RW 2-20 | | Name: | RUNWAY 2- | -20 | Use: | RUNWAY | Area: | 38 | 7,523 SqFt | |
| Section: | 6450 | of | 6 Fr | om: - | | | То: - | | | Last Const.: | 1/1/1977 |
| Surface: | AC | Family: | CA653-GA-RW | -AC Zon | ne: | | Category: | | | Rank: P | |
| Area: | 25,0 | 000 SqFt | Length: | 250 I | Ft | Width: | 100 Ft | | | | |
| Slabs: | | Slab Lengt | th: | Ft | Slab Width: | | Ft | Joint L | ength: | F | t |
| Shoulder: | | Street Typ | e: | | Grade: 0 | | | Lanes: | 0 | | |
| Section Co | omments: | | | | | | | | | | |
| Work Date | e: 1/1/1977 | Wor | k Type: New C | onstruction - AC | | C | ode: NC-AC | Is | Major M | &R: True | |
| Last Insp. | Date: 1/24/202 | 22 | TotalSa | nples: 5 | | Surveye | d: 2 | | | | |
| Conditions | s: PCI: 34 | | | | | | | | | | |
| Inspection | Comments: | | | | | | | | | | |
| | | | | | | | | | | | |
| Sample Nu | umber: 148 | Type | : R | Area: | 5000 | .00 SqFt | PCI: | 32 | | | |
| • | | Туре | : R | Area: | 5000 | 0.00 SqFt | PCI: | 32 | | | |
| Sample Co | | Туре | R M | Area: 5000.00 SqFt | 5000 | 0.00 SqFt | PCI: | 32 | | | |
| Sample Co | omments: | Туре | | | 5000 | 0.00 SqFt | PCI: | 32 | | | |
| Sample Co 43 BLC 52 RA | omments: OCK CR | Туре | M | 5000.00 SqFt | 5000 | 0.00 SqFt | PCI: | 32 | | | |
| Sample Co 43 BLG 52 RA 52 RA | omments: OCK CR VELING | Туре | M L M | 5000.00 SqFt 3500.00 SqFt | | 0.00 SqFt | PCI: | | | | |
| Sample Co 43 BLC 52 RA 52 RA Sample Nu | OCK CR VELING VELING umber: 150 | | M L M | 5000.00 SqFt 3500.00 SqFt 1500.00 SqFt | | • | | | | | |
| Sample Co 43 BLC 52 RA 52 RA Sample Nu Sample Co | OCK CR VELING VELING umber: 150 | | M L M | 5000.00 SqFt 3500.00 SqFt 1500.00 SqFt | | • | | | | | |
| Sample Co 43 BLG 52 RA 52 RA 52 RA Sample Nu Sample Co 43 BLG | OCK CR VELING VELING umber: 150 | | M L M | 5000.00 SqFt 3500.00 SqFt 1500.00 SqFt Area: | | • | | | | | |
| Sample Co 43 BLG 52 RA 52 RA 52 RA Sample Nu Sample Co 43 BLG 43 BLG | OCK CR VELING VELING umber: 150 omments: | | M L M | 5000.00 SqFt 3500.00 SqFt 1500.00 SqFt Area: | | • | | | | | |

| Network: EVB | | Name: | NEW SMYRNA | BEACH MUNICIPA | L AIRPORT | |
|---|------------------------|--|--------------|----------------|--------------|-----------------------|
| Branch: RW 7-25 | Name | : RUNWAY 7-25 | Use: | RUNWAY | Area: | 375,128 SqFt |
| Section: 6202 | of 5 | From: - | | То: - | | Last Const.: 1/1/2008 |
| Surface: AAC | Family: CA653-GA | A-RW-AAC- Zone: | | Category: | | Rank: P |
| Area: 18, | 750 SqFt Leng | th: 75 Ft | Width: | 250 Ft | | |
| Slabs: | Slab Length: | Ft Slab | Width: | Ft | Joint Lengtl | h: Ft |
| Shoulder: | Street Type: | Grad | le: 0 | | Lanes: |) |
| Section Comments: | | | | | | |
| Work Date: 1/1/1943 | Work Type: 1 | New Construction - Initial | Co | ode: NU-IN | Is Majo | r M&R: True |
| Work Date: 1/1/2008 | Work Type: 1 | Mill and Overlay | Co | ode: ML-OVL | Is Majo | r M&R: True |
| Last Insp. Date: 1/24/20 | 22 To | talSamples: 5 | Surveye | d: 2 | | |
| Conditions: PCI: 76 | j | | | | | |
| Inspection Comments: | | | | | | |
| | | | | DCI. 76 | | |
| Sample Number: 101 | Type: R | Area: | 3750.00 SqFt | PCI: 76 | | |
| Sample Number: 101 Sample Comments: | Type: R | Area: | 3750.00 SqFt | PCI: /0 | | |
| • | Type: R | Area: 24.00 Ft | 3750.00 SqFt | PCI: /6 | | |
| Sample Comments: | | | 3750.00 SqFt | PCI: /0 | | |
| Sample Comments: 48 L & T CR | L | 24.00 Ft | 3750.00 SqFt | PCI: /6 | | |
| Sample Comments: 48 L & T CR 57 WEATHERING | L L | 24.00 Ft 1875.00 SqFt | 3750.00 SqFt | PCI: 76 | | |
| Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING | L L M | 24.00 Ft 1875.00 SqFt 1875.00 SqFt | | | | |
| Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING Sample Number: 103 | L L M | 24.00 Ft 1875.00 SqFt 1875.00 SqFt | | | | |
| Sample Comments: 48 L & T CR 57 WEATHERING 57 WEATHERING Sample Number: 103 Sample Comments: | L L M Type: R | 24.00 Ft 1875.00 SqFt 1875.00 SqFt Area: | | | | |

| Network | : EVB | | | | | Namo | e: NEW | SMYRN | A BEA | CH MUNIC | IPAL A | IRPOR | T | | | |
|-----------------|------------------------|------------------------|---------|-------------|-----------------|---------------|-------------|----------|----------------|-------------|--------|-------|---------|--------------|---------|-------------|
| Branch: | RW 7-25 | | Na | ime: | RUNV | WAY 7-2. | 5 | Use: | RU | JNWAY | Ar | ·ea: | | 375,128 | SqFt | |
| Section: | 6205 | of 5 | 5 | Fro | m: | - | | | | То: - | | | | Las | t Const | .: 1/1/2016 |
| Surface: | AAC | | | -GA-RW-A | AAC- | Zone | : | | | Category: | | | | Rar | ık: P | |
| A | 224.74 | | PC • | | | 4 470 E4 | | W: J4L . | | 75 D4 | | | | | | |
| Area: Slabs: | 324,73 | 50 SqFt Slab Length | | ength: | Ft | 4,470 Ft | Slab Width: | Width: | | 75 Ft Ft | | Loin | t Lengt | h• | | Ft |
| Shoulder | r• | Street Type: | | | Γt | | Grade: 0 | | | rt | | Land | _ | 0 | | rt |
| | Comments: | Street Type. | • | | | | Grade. 0 | | | | | Dan | cs. | J | | |
| | ate: 1/1/1989 | Work | Тур | e: New Co | nstructi | on - Initia | ıl | • | Code: | NU-IN | |] | Is Majo | r M&R: | True | |
| Work D | ate: 1/1/2016 | Work | Тур | e: Mill and | Overla | ıy | | (| Code: | ML-OVL | |] | Is Majo | r M&R: | True | |
| Last Ins | p. Date: 1/24/2022 | 2 | | TotalSam | ples: | 86 | | Survey | / ed: 1 | .8 | | | | | | |
| Conditio | ons: PCI: 89 | | | | | | | | | | | | | | | |
| Inspection | on Comments: | | | | | | | | | | | | | | | |
| Sample | Number: 108 | Type: | | R | A | Area: | 3750. | 00 SqFt | | PCI: | 94 | | | | | |
| Sample | Comments: | | | | | | | | | | | | | | | |
| 57 V | VEATHERING | | L | 3 | 750.00 | SqFt | | | | | | | | | | |
| Sample | Number: 114 | Type: | | R | I | Area: | 3750. | 00 SqFt | | PCI: | 89 | | | | | |
| Sample | Comments: | | | | | | | | | | | | | | | |
| | . & T CR | | L | | 35.00 | Ft | | | | | | | | | | |
| | VEATHERING | | L | | 750.00 | SqFt | | | | | | | | | | |
| _ | Number: 120 | Type: | | R | A | Area: | 3750. | 00 SqFt | | PCI: | 90 | | | | | |
| Sample | Comments: | | | | | | | | | | | | | | | |
| | & T CR | | L | 2 | 15.00 | | | | | | | | | | | |
| | VEATHERING Number: 126 | Туре: | L | R | 750.00 | Sqrt Area: | 3750 | 00 SqFt | | PCI: | 80 | | | | | |
| _ | Comments: | Type. | | K | 1 | Aica. | 3730. | oo sqrt | | TCI. | 69 | | | | | |
| 48 L | . & T CR | | L | | 15.00 | Ft | | | | | | | | | | |
| | WELLING VEATHERING | | L L | 2 | 4.00 750.00 | SqFt | | | | | | | | | | |
| | Number: 132 | Type: | | R | | Area: | 3750 | 00 SqFt | | PCI: | 89 | | | | | |
| _ | Comments: | 1 Jpc. | | | 1 | 11 041 | 3730. | oo sqrt | | 101. | 0) | | | | | |
| _ | . & T CR | | L | | 22.00 | Et | | | | | | | | | | |
| | WELLING | | L | | | SqFt | | | | | | | | | | |
| | VEATHERING | | L | | 750.00 | | | | | | | | | | | |
| _ | Number: 138 | Type: | | R | A | Area: | 3750. | 00 SqFt | | PCI: | 83 | | | | | |
| Sample | Comments: | | | | | | | | | | | | | | | |
| | & T CR | | L | | 68.00 | | | | | | | | | | | |
| | . & T CR VEATHERING | | M L | 3 | 10.00 750.00 | | | | | | | | | | | |
| | Number: 141 | Type: | | R | | Area: | 3750. | 00 SqFt | | PCI: | 89 | | | | | |
| Sample | Comments: | | | | | | | | | | | | | | | |
| 48 L | . & T CR | | L | | 42.00 | Ft | | | | | | | | | | |
| | VEATHERING | | L | 3 | 750.00 | | | | | | | | | | | |
| _ | Number: 145 | Type: | | R | A | Area: | 3750. | 00 SqFt | | PCI: | 82 | | | | | |
| Sample | Comments: | | | | | | | | | | | | | | | |
| | & T CR | | L | | 82.00 | | | | | | | | | | | |
| | . & T CR VEATHERING | | M L | 3 | 10.00 750.00 | | | | | | | | | | | |
| | Number: 150 | Type: | | R | | Area: | 3750. | 00 SqFt | | PCI: | 89 | | | | | |
| _ | Comments: | - 1 Pr. | | | 1 | | 2,20. | | | - 020 | | | | | | |
| P | y | | | | | | | | | | | | | | | |

| 48 | L & T CR | | L | 61.00 |) Ft | | | | |
|----------|------------------------|--------|--------|------------------|--------|---------------|------|----|--|
| 57 | WEATHERING | | L | 3750.00 |) SqFt | | | | |
| Samp | ole Number: 154 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 89 | |
| Samp | ole Comments: | | | | | | | | |
| 48 | L & T CR | | т | 41.00 |) E+ | | | | |
| 57 | WEATHERING | | L L | 3750.00 | | | | | |
| | ole Number: 158 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 00 | |
| - | ole Comments: | Type. | | K | Aica. | 3730.00 Sq1 t | 101. | 70 | |
| | | | | | | | | | |
| 48 | L & T CR | | L | 16.00 | | | | | |
| 57 | WEATHERING | | L | 3750.00 |) SqFt | | | | |
| Samp | ole Number: 162 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 90 | |
| Samp | ole Comments: | | | | | | | | |
| 48 | L & T CR | | L | 25.00 |) Ft | | | | |
| 57 | WEATHERING | | L | 3725.00 | | | | | |
| Samp | ole Number: 167 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 90 | |
| Samp | ole Comments: | | | | | | | | |
| _ | | | т | 12.0 |) F: | | | | |
| 48 57 | L & T CR WEATHERING | | L L | 12.00 3750.00 | | | | | |
| | ole Number: 171 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 04 | |
| | | 1 ype: | | K | Area: | 3/30.00 SqFt | rci: | 94 | |
| Samp | ole Comments: | | | | | | | | |
| 57 | WEATHERING | | L | 3750.00 |) SqFt | | | | |
| Samp | ole Number: 176 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 90 | |
| Samp | ole Comments: | | | | | | | | |
| 48 | L & T CR | | L | 25.00 |) Ft | | | | |
| 57 | WEATHERING | | L | 3750.00 | | | | | |
| Samr | ole Number: 181 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 87 | |
| _ | ole Comments: | - J P | | | | 7,7,111 | | • | |
| | | | | | | | | | |
| 48 | L & T CR | | L | 78.00 | | | | | |
| 57 | WEATHERING | | L | 3750.00 | | | | | |
| - | ole Number: 186 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 89 | |
| Samp | ole Comments: | | | | | | | | |
| 48 | L & T CR | | L | 58.00 |) Ft | | | | |
| 57 | WEATHERING | | L | 3750.00 | | | | | |
| Samp | ole Number: 191 | Type: | | R | Area: | 3750.00 SqFt | PCI: | 91 | |
| Samp | ole Comments: | | | | | | | | |
| 48 | L & T CR | | L | 9 00 |) Ft | | | | |
| 57 | WEATHERING | | L | 3750.00 | | | | | |
| | | | | | | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: RW 7-25 RUNWAY 7-25 Use: RUNWAY **Branch:** Area: 375,128 SqFt Name: Section: 6210 of 5 From: To: -**Last Const.:** 1/1/2008 Surface: AAC Family: CA653-GA-RW-AAC-Zone: Category: Rank: P Area: 11,378 SqFt Length: 75 Ft Width: 150 Ft Ft Slab Width: Ft Ft Slabs: Slab Length: Joint Length: Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1943 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2008 Work Type: Mill and Overlay Code: ML-OVL Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 3 Surveyed: 1 PCI: **Conditions: Inspection Comments:** Sample Number: 197 3750.00 SqFt **PCI:** 84 Type: R Area: **Sample Comments:** 48 L & T CR L 41.00 Ft WEATHERING L 3375.00 SqFt 57 57 WEATHERING M 375.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: RW 7-25 RUNWAY 7-25 Use: RUNWAY 375,128 SqFt **Branch:** Area: Name: Section: 6215 of 5 From: To: -**Last Const.:** 1/1/2016 CA653-GA-RW-AAC-Surface: AAC Family: Zone: Category: Rank: P Area: 7,125 SqFt Length: 95 Ft Width: 75 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1943 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2016 Work Type: Mill and Overlay Code: ML-OVL Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 106 R 3375.00 SqFt **PCI:** 91 Type: Area: **Sample Comments:** 48 L & T CR L 5.00 Ft

L

3375.00 SqFt

57

WEATHERING

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: RW 7-25 RUNWAY 7-25 Use: RUNWAY 375,128 SqFt **Branch:** Area: Name: Section: 6220 of 5 From: To: -**Last Const.:** 1/1/2016 CA653-GA-RW-AAC-Surface: AAC Family: Zone: Category: Rank: P Area: 13,125 SqFt Length: 175 Ft Width: 75 Ft Slab Length: Ft Slab Width: Ft Joint Length: Ft Slabs: Shoulder: **Street Type:** Grade: Lanes: **Section Comments: Work Date:** 1/1/1943 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2016 Work Type: Mill and Overlay Code: ML-OVL Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 194 R 3750.00 SqFt **PCI:** 88 Type: Area: **Sample Comments:** 48 L & T CR L 65.00 Ft L 57 WEATHERING 3750.00 SqFt

| Netwo | ork: EVB | | | | Na | me: NE | W SMYRNA | BEACH MUN | ICIPAL AI | RPORT | | | |
|--|--|-------------|---------------------------|------------|---|-------------|-----------|------------|-----------|-----------|---------|-------------|----------|
| Branc | h: TL T-I | HANG | N | lame: | T-HANGAR | TAXILANES | Use: | TAXILANE | Arc | ea: | 50,8 | 850 SqFt | |
| Section | n: 4320 | | of 3 | Fr | om: - | | | То: - | | | L | ast Const.: | 1/1/2002 |
| Surfac | ce: AC | Famil | y: CA65 | 3-GA-TW- | -AC Zo | ne: | | Category | : | | R | Rank: P | |
| Area: | | 31,261 SqFt |] | Length: | 1,300 | Ft | Width: | 25 | Ft | | | | |
| Slabs: | | Slab | Length: | | Ft | Slab Width: | | Ft | | Joint Len | gth: | F | ; |
| Should | der: | Stree | et Type: | | | Grade: 0 | | | | Lanes: | 0 | | |
| Section | n Comments: | | | | | | | | | | | | |
| Work | Date: 1/1/2002 | 2 | Work Typ | pe: Comple | ete Reconstructi | ion - AC | C | ode: CR-AC | | Is Ma | ijor M& | R: True | |
| Last I | nsp. Date: 1/2 | 24/2022 | | TotalSan | mples: 7 | | Surveye | ed: 2 | | | | | |
| | p. 2 acc | | | - 0000 | p | | Sur (c) c | | | | | | |
| Condi | tions PCI | 64 | | | | | | | | | | | |
| Condi | | | | | | | | | | | | | |
| | tions: PCI: | | | | | | | | | | | | |
| Inspec | | ts: | Type: | R | Area: | 5000 |).00 SqFt | PCI | : 69 | | | | |
| Inspec Sampl | ction Comment | ts: | Type: | R | Area: | 5000 |).00 SqFt | PCI | : 69 | | | | |
| Inspec Sampl Sampl | etion Comment | ts: | Type: | R | Area: | 5000 | 0.00 SqFt | PCI | : 69 | | | | |
| Inspec | etion Comment le Number: 1 le Comments: | ts: | | | | 5000 |).00 SqFt | PCI | : 69 | | | | |
| Inspec Sampl Sampl 48 48 | tion Comment le Number: 1 le Comments: L & T CR | ts: | L | | 136.00 Ft | |).00 SqFt | PCI | : 69 | | | | |
| Sample Sample 48 48 52 | etion Comment le Number: 1 le Comments: L&TCR L&TCR | 60 | L M | | 136.00 Ft 100.00 Ft | |).00 SqFt | PCI | : 69 | | | | |
| Sample Sample 48 48 52 57 | etion Comment le Number: 1 le Comments: L & T CR L & T CR RAVELING | 60 I/G | L M L | | 136.00 Ft 100.00 Ft 1000.00 SqFt | | 0.00 SqFt | | : 69 | | | | |
| Sampl 48 48 52 57 Sampl | le Number: 1 le Comments: L & T CR L & T CR RAVELING WEATHERIN | 60 I/G | L M L L | | 136.00 Ft 100.00 Ft 1000.00 SqFt 4000.00 SqFt | | | | | | | | |
| Sample Sa | le Number: 1 le Comments: L & T CR L & T CR RAVELING WEATHERIN le Number: 2 | 60 I/G | L M L L | | 136.00 Ft 100.00 Ft 1000.00 SqFt 4000.00 SqFt | | | | | | | | |
| Sampl 48 48 52 57 Sampl | le Number: 1 le Comments: L & T CR L & T CR RAVELING WEATHERIN le Number: 2 le Comments: | 60 I/G | L M L L Type: | R | 136.00 Ft 100.00 Ft 1000.00 SqFt 4000.00 SqFt Area: | | | | | | | | |
| Sample Sample 48 48 52 57 Sample Sample 48 | tion Comment le Number: 1 le Comments: L & T CR L & T CR RAVELING WEATHERIN le Number: 2 le Comments: L & T CR | 60 I/G | L M L L Type: | R | 136.00 Ft 100.00 Ft 1000.00 SqFt 4000.00 SqFt Area: 522.00 Ft | 4172 | | | | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TL T-HANG T-HANGAR TAXILANES Use: TAXILANE 50,850 SqFt **Branch:** Area: Name: Section: 4340 of 3 From: To: -**Last Const.:** 1/1/2010 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 8,491 SqFt 340 Ft Width: 25 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: Street Type: Grade: Lanes: **Section Comments:** Work Date: 1/1/2010 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 4241.00 SqFt **PCI:** 85 Sample Number: 300 Type: R Area: **Sample Comments:**

L

L

M

48

57

57

L & T CR WEATHERING

WEATHERING

32.00 Ft

3817.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW A **Branch:** TAXIWAY A Use: TAXIWAY 142,094 SqFt Area: Name: Section: 102 of 5 From: To: -**Last Const.:** 1/1/2011 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 22,287 SqFt 465 Ft Width: 38 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2011 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 5 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 3500.00 SqFt **PCI:** 85 Sample Number: 102 Type: R Area: **Sample Comments:**

RAVELING

WEATHERING

52

57

L

L

350.00 SqFt

| Network: | EVB | | | Nam | ne: NEW SMYRNA | BEACH MUNICI | PAL AIRPORT | |
|--------------|-----------------|-------------|-----------|---------------------|----------------|--------------|-------------|-----------------------------|
| Branch: | TW A | | Name: | TAXIWAY A | Use: | TAXIWAY | Area: | 142,094 SqFt |
| Section: 1 | 105 | of : | 5 | From: - | | То: - | | Last Const.: 1/1/197 |
| Surface: A | AC | Family: C | A653-GA-7 | TW-AC Zon | e: | Category: | | Rank: P |
| Area: | 93,280 |) SqFt | Length | 2,580 F | t Width: | 40 Ft | | |
| Slabs: | | Slab Lengtl | 1: | Ft | Slab Width: | Ft | Joint | Length: Ft |
| Shoulder: | | Street Type | : | | Grade: 0 | | Lanes | s: 0 |
| Section Con | nments: | | | | | | | |
| Work Date: | 1/1/1977 | Work | Type: Nev | v Construction - AC | (| Code: NC-AC | Is | s Major M&R: True |
| Last Insp. D | Date: 1/24/2022 | | Total | Samples: 23 | Survey | ed: 3 | | |
| Conditions: | PCI: 51 | | | | | | | |
| Inspection (| Comments: | | | | | | | |
| Sample Nun | nber: 113 | Type: | R | Area: | 4000.00 SqFt | PCI: | 54 | |
| Sample Con | | | | | | | | |
| 48 L& | T CR | | L | 279.00 Ft | | | | |
| 48 L&' | T CR | | M | 212.00 Ft | | | | |
| | ELING | | L | 4000.00 SqFt | | | | |
| | LLING | | L | 32.00 SqFt | | | | |
| Sample Nun | nber: 122 | Type: | R | Area: | 4000.00 SqFt | PCI: | 48 | |
| Sample Con | nments: | | | | | | | |
| 48 L&' | T CR | | L | 333.00 Ft | | | | |
| 48 L& | T CR | | M | 40.00 Ft | | | | |
| 50 PAT | CHING | | M | 360.00 SqFt | | | | |
| 52 RAV | ELING | | L | 3640.00 SqFt | | | | |
| 56 SWE | ELLING | | L | 158.00 SqFt | | | | |
| Sample Nun | nber: 133 | Type: | R | Area: | 4000.00 SqFt | PCI: | 52 | |
| Sample Con | nments: | | | | | | | |
| 43 BLO | CK CR | | L | 2000.00 SqFt | | | | |
| 48 L& | | | L | 142.00 Ft | | | | |
| 48 L& | T CR | | M | 100.00 Ft | | | | |
| | ELING | | L | 4000.00 SqFt | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW A **Branch:** TAXIWAY A Use: TAXIWAY 142,094 SqFt Area: Name: Section: 110 of 5 From: To: -**Last Const.:** 7/1/2011 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 16,319 SqFt 400 Ft Width: 40 Ft Area: Length: Slab Width: Slabs: Slab Length: Ft Joint Length: Ft Ft Shoulder: Street Type: Grade: Lanes: **Section Comments:** Work Date: 7/1/2011 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 3 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 5081.00 SqFt **PCI:** 82 Sample Number: 128 Type: R Area: **Sample Comments:** L & T CR L 19.00 Ft 48

WEATHERING

WEATHERING

57

57

L

M

4065.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW A TAXIWAY A Use: TAXIWAY 142,094 SqFt Branch: Area: Name: Section: 115 of 5 From: To: -**Last Const.:** 1/1/2014 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 5,905 SqFt 60 Ft Width: 100 Ft Area: Length: Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1977 Code: NU-IN Work Type: New Construction - Initial Is Major M&R: True Work Date: 1/1/2014 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 224 Type: R Area: 2953.00 SqFt **PCI:** 86 **Sample Comments:** L & T CR L 28.00 Ft 48 57 WEATHERING L 2805.00 SqFt WEATHERING M 148.00 SqFt

57

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW A TAXIWAY A Use: TAXIWAY 142,094 SqFt **Branch:** Area: Name: Section: 125 of 5 From: To: **Last Const.:** 1/1/2002 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 4,303 SqFt 80 Ft Width: 40 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2002 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True TotalSamples: 1 Surveyed: 1 **Last Insp. Date:** 1/24/2022 **Conditions:** PCI: **Inspection Comments:** 4303.00 SqFt **PCI:** 52 Sample Number: 108 Type: R Area: **Sample Comments:** L 314.00 Ft L & T CR 48 187.00 Ft L & T CR M 48 RAVELING 3873.00 SqFt 52 L

52

RAVELING

SWELLING

M

L

430.00 SqFt

| Netw | ork: EVB | | | | Name | : NEW | V SMYRNA | BEACH MUNICI | PAL AIRPO | RT | | |
|-------|------------------|-------------|----------|-----------|----------------------|-------------|----------|--------------|-----------|-------------|--------------|----------|
| Bran | ch: TW B | | | Name: | TAXIWAY B | | Use: | TAXIWAY | Area: | 1 | 73,763 SqFt | |
| Secti | on: 210 | | of 2 | | From: - | | | То: - | | | Last Const.: | 1/1/2002 |
| Surfa | ace: AC | Fami | ly: CA | A653-GA-T | W-AC Zone: | | | Category: | | | Rank: P | |
| Area | : | 67,896 SqFt | | Length: | 35 Ft | | Width: | 1,850 Ft | | | | |
| Slabs | s: | Slab | Length: | | Ft S | Slab Width: | | Ft | Jo | int Length: | F | t |
| Shou | lder: | Stre | et Type: | | • | Grade: 0 | | | La | nes: 0 | | |
| Secti | on Comments: | | | | | | | | | | | |
| Wor | k Date: 1/1/2002 | | Work | Type: Con | plete Reconstruction | - AC | C | Code: CR-AC | | Is Major | M&R: True | |
| Last | Insp. Date: 1/2 | 4/2022 | | Totals | Samples: 18 | | Surveyo | ed: 3 | | | | |
| Cond | litions: PCI: | 73 | | | | | | | | | | |
| Inspe | ection Comments | : : | | | | | | | | | | |
| Samj | ple Number: 10 |)2 | Type: | R | Area: | 3500 | .00 SqFt | PCI: | 73 | | | |
| Samj | ple Comments: | | | | | | | | | | | |
| 48 | L & T CR | | | L | 212.00 Ft | | | | | | | |
| 52 | RAVELING | | | L | 350.00 SqFt | | | | | | | |
| 57 | WEATHERING | G | | L | 3150.00 SqFt | | | | | | | |
| Samj | ple Number: 10 | 9 | Type: | R | Area: | 3500 | .00 SqFt | PCI: | 73 | | | |
| Samj | ple Comments: | | | | | | | | | | | |
| 48 | L & T CR | | | L | 212.00 Ft | | | | | | | |
| 57 | WEATHERING | G | | L | 2800.00 SqFt | | | | | | | |
| 57 | WEATHERING | G | | M | 700.00 SqFt | | | | | | | |
| Samp | ple Number: 11 | 4 | Type: | R | Area: | 3500 | .00 SqFt | PCI: | 72 | | | |
| Samp | ple Comments: | | | | | | | | | | | |
| 48 | L & T CR | | | L | 150.00 Ft | | | | | | | |
| 48 | L & T CR | | | M | 50.00 Ft | | | | | | | |
| 57 | WEATHERING | G | | L | 2800.00 SqFt | | | | | | | |
| 57 | WEATHERING | G | | M | 700.00 SqFt | | | | | | | |

| Networl | k: EVB | | | Nai | ne: NEV | v SMYRNA | BEACH MUNIC | PAL AIRPORT | |
|----------|---------------------|--------------|-----------|-----------------------|-------------|-----------|-------------|-------------|-----------------------|
| Branch | : TW B | | Name: | TAXIWAY E | 3 | Use: | TAXIWAY | Area: | 173,763 SqFt |
| Section: | : 215 | of 2 | | From: - | | | То: - | | Last Const.: 1/1/2002 |
| Surface | : AC | Family: CA | 653-GA-T | W-AC Zor | ie: | | Category: | | Rank: P |
| Area: | 105,86 | 67 SqFt | Length: | 35] | Ft | Width: | 2,990 Ft | | |
| Slabs: | | Slab Length: | _ | Ft | Slab Width: | | Ft | Joint L | ength: Ft |
| Shoulde | er: | Street Type: | | | Grade: 0 | | | Lanes: | 0 |
| Section | Comments: | | | | | | | | |
| Work D | Date: 1/1/2002 | Work | Гуре: Cor | nplete Reconstruction | on - AC | Co | ode: CR-AC | Is I | Major M&R: True |
| Last Ins | sp. Date: 1/24/2022 | 2 | Total | Samples: 28 | | Surveye | d: 4 | | |
| Conditi | ions: PCI: 64 | | | | | | | | |
| Inspecti | ion Comments: | | | | | | | | |
| Sample | Number: 123 | Type: | R | Area: | 3500 | 0.00 SqFt | PCI: | 61 | |
| Sample | Comments: | | | | | | | | |
| 48 I | L & T CR | | L | 278.00 Ft | | | | | |
| 48 I | L & T CR | | M | 100.00 Ft | | | | | |
| | SWELLING | | L | 40.00 SqFt | | | | | |
| 57 Y | WEATHERING | | L | 2800.00 SqFt | | | | | |
| 57 Y | WEATHERING | | M | 700.00 SqFt | | | | | |
| Sample | Number: 133 | Type: | R | Area: | 3500 | 0.00 SqFt | PCI: | 66 | |
| Sample | Comments: | | | | | | | | |
| 48 I | L & T CR | | L | 200.00 Ft | | | | | |
| 48 I | L & T CR | | M | 100.00 Ft | | | | | |
| | WEATHERING | | L | 2800.00 SqFt | | | | | |
| 57 Y | WEATHERING | | M | 700.00 SqFt | | | | | |
| Sample | Number: 138 | Type: | R | Area: | 3500 | 0.00 SqFt | PCI: | 64 | |
| Sample | Comments: | | | | | | | | |
| 48 I | L & T CR | | L | 294.00 Ft | | | | | |
| 48 I | L & T CR | | M | 6.00 Ft | | | | | |
| 57 V | WEATHERING | | L | 2800.00 SqFt | | | | | |
| 57 Y | WEATHERING | | M | 700.00 SqFt | | | | | |
| Sample | Number: 143 | Type: | R | Area: | 3500 | 0.00 SqFt | PCI: | 66 | |
| Sample | Comments: | | | | | | | | |
| | L & T CR | | L | 249.00 Ft | | | | | |
| | L & T CR | | M | 70.00 Ft | | | | | |
| 57 V | WEATHERING | | L | 2800.00 SqFt | | | | | |
| 57 V | WEATHERING | | M | 700.00 SqFt | | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW C TAXIWAY C Use: TAXIWAY 294,018 SqFt **Branch:** Area: Name: Section: 310 of 8 From: To: **Last Const.:** 1/1/2002 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 13,657 SqFt 308 Ft Width: 43 Ft Area: Length: Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2002 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **TotalSamples:** 3 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 5376.00 SqFt Sample Number: 135 Type: R Area: **PCI:** 33 **Sample Comments:** L 136.00 Ft L & T CR 48 L & T CR M 600.00 Ft 48 PATCHING 410.00 SqFt 50 L 52 RAVELING L 4821.00 SqFt

52

54

54

RAVELING

SHOVING

SHOVING

M

L

M

145.00 SqFt

40.00 SqFt

| Networ | k: EVB | | | | Na | me: NEV | W SMYRNA | BEACH MUNICI | PAL AIRPO | RT | | |
|--|--|-------------|---|---|--|----------------|--------------|--------------|-----------|--------------|------------|----------|
| Branch | : TW C | | Na | ame: TA | XIWAY | C | Use: | TAXIWAY | Area: | 294,0 | 18 SqFt | |
| Section | : 312 | | of 8 | From: | - | | | То: - | | La | st Const.: | 4/1/2022 |
| Surface | : AC | Family: | CA653 | 3-GA-TW-AC | Zo | ne: | | Category: | | Ra | nk: P | |
| Area: | | 12,746 SqFt | L | ength: | 370 | Ft | Width: | 35 Ft | | | | |
| Slabs: | | Slab L | ength: | | Ft | Slab Width: | | Ft | Joi | int Length: | F | t |
| Shoulde | er: | Street ' | Туре: | | | Grade: 0 | | | La | nes: 0 | | |
| Section | Comments: | | | | | | | | | | | |
| Work D | Date: 1/1/2002 | | Work Typ | e: New Constru | ction - A | 2 | C | ode: NC-AC | | Is Major M&F | R: True | |
| Work D | Date: 4/1/2022 | | Work Typ | e: Complete Re | constructi | on - AC | C | ode: CR-AC | | Is Major M&F | R: True | |
| Last In | sp. Date: 3/1 | 1/2019 | | TotalSamples | 9 | | Surveye | d: 2 | | | | |
| Conditi | ons: PCI: | 44 | | | NOTE: * | ** Pre-Constru | ction PCI ** | ** | | | | |
| | | | | | | | | | | | | |
| Inspecti | ion Comments | S: | | | | | | | | | | |
| | ion Comments Number: 13 | | ype: | R | Area: | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample | | | ype: | R | Area: | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample Sample | Number: 13 | | ype: | | Area: | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample Sample 48 1 | Number: 13 Comments: L & T CR L & T CR | | | 63. 478. | 00 Ft 00 Ft | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample Sample 48 1 48 1 52 1 | Number: 13 Comments: L & T CR L & T CR RAVELING | | L M L | 63. 478. 4083. | 00 Ft 00 Ft 00 SqFt | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample Sample 48 1 48 1 52 1 52 1 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING | | L M L M | 63. 478. 4083. 105. | 00 Ft 00 Ft 00 SqFt 00 SqFt | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample Sample 48 1 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING | | L M L M L | 63. 478. 4083. 105. 40. | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample Sample 48 1 48 1 52 1 52 1 54 8 54 8 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SHOVING | | L M L M L | 63. 478. 4083. 105. 40. | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt 00 SqFt | 4188 | 3.00 SqFt | PCI: | 38 | | | |
| Sample Sample 48 1 52 1 552 1 554 5 56 5 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SHOVING SWELLING | 35 T | L M L M L M | 63. 478. 4083. 105. 40. 14. | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt 00 SqFt 00 SqFt | | | | | | | |
| Sample Sample 48 1 48 1 52 1 54 8 554 8 56 8 Sample | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SHOVING SWELLING Number: 14 | 35 T | L M L M L | 63. 478. 4083. 105. 40. | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt 00 SqFt | | 3.00 SqFt | PCI: | | | | |
| Sample Sample 48 148 152 152 154 155 156 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SHOVING SWELLING Number: 14 Comments: | 35 T | L M L M L M L | 63. 478. 4083. 105. 40. 14. 8. | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt 00 SqFt Area: | | | | | | | |
| Sample 8 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SHOVING SWELLING Number: 14 Comments: L & T CR | 35 T | L M L M L M L ype: | 63. 478. 4083. 105. 40. 14. 8. | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt 00 SqFt Area: | | | | | | | |
| Sample Sample 48 148 152 154 155 156 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SWELLING Number: 14 Comments: L & T CR L & T CR | 35 T | L M L M L M L ype: | 63. 478. 4083. 105. 40. 14. 8. R | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt 00 SqFt Area: | | | | | | | |
| Sample 8 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SWELLING Number: 14 Comments: L & T CR L & T CR L & T CR RAVELING | 35 T | L M L M L M L ype: | R 63. 478. 4083. 105. 40. 14. 8. R 268. 220. 350. | 00 Ft 000 Ft 000 SqFt 000 SqFt 000 SqFt 000 SqFt Area: 000 Ft 000 SqFt | | | | | | | |
| Sample Sample 48 | Number: 13 Comments: L & T CR L & T CR RAVELING RAVELING SHOVING SWELLING Number: 14 Comments: L & T CR L & T CR | 35 T | L M L M L M L ype: | R 268. 220. 350. 60. | 00 Ft 00 Ft 00 SqFt 00 SqFt 00 SqFt 00 SqFt Area: | | | | | | | |

| Netw | ork: EVB | | | | N | ame: NE | W SMYRNA | BEACH MUNIC | IPAL AIRPOR | Γ | | |
|---|---|----------------|-------------|-----------|---|------------------|---------------|-------------|-------------|------------|--------------|----------|
| Bran | ch: TW C | | : | Name: | TAXIWAY | C | Use: | TAXIWAY | Area: | 294, | 018 SqFt | |
| Section | on: 315 | o | of 8 | Fı | rom: - | | | То: - | | I | Last Const.: | 4/1/2022 |
| Surfa | ce: AC | Family: | CA6 | 53-GA-TW | -AC Z | one: | | Category: | | I | Rank: P | |
| Area | 2 | 4,500 SqFt | | Length: | 70 | 0 Ft | Width: | 35 Ft | | | | |
| Slabs | : | Slab Lei | ngth: | | Ft | Slab Width: | | Ft | Joint | t Length: | Ft | |
| Shoul | der: | Street T | ype: | | | Grade: 0 | | | Lane | es: 0 | | |
| Section | on Comments: | | | | | | | | | | | |
| Work | Date: 1/1/2002 | W | ork T | ype: Comp | lete Reconstruc | etion - AC | Co | ode: CR-AC | 1 | s Major M& | R: True | |
| Work | Date: 4/1/2022 | W | ork T | ype: Comp | lete Reconstruc | etion - AC | Co | ode: CR-AC | 1 | s Major M& | R: True | |
| | | | | | | | | | | | | |
| Last | Insp. Date: 3/11/2 | 2019 | | TotalSa | mples: 12 | | Surveye | d: 2 | | | | |
| | • | 2019 70 | | TotalSa | • | *** Pre-Constru | • | | | | | |
| Cond | • | | | TotalSa | • | *** Pre-Constru | • | | | | | |
| Cond Inspe | itions: PCI: | | pe: | TotalSa | • | | • | | 71 | | | |
| Cond Inspe Samp | itions: PCI: | 70 | pe: | | NOTE: | | ection PCI ** | * | 71 | | | |
| Cond Inspe Samp Samp | itions: PCI: ction Comments: le Number: 146 | 70 | pe: | R | NOTE: | | ection PCI ** | * | 71 | | | |
| Cond Inspe Samp Samp | itions: PCI: ction Comments: le Number: 146 le Comments: | 70 | | R | NOTE: | 3500 | ection PCI ** | * | 71 | | | |
| Cond Inspe Samp Samp 48 52 | itions: PCI: ction Comments: le Number: 146 le Comments: L & T CR | 70 | L | R | NOTE: Area: 243.00 Ft | 3500 't | ection PCI ** | * | 71 | | | |
| Cond Inspe Samp Samp 48 52 57 | itions: PCI: ction Comments: le Number: 146 le Comments: L & T CR RAVELING | 70 | L L L | R | NOTE: Area: 243.00 Ft 525.00 SqF | 3500 St St | ection PCI ** | * | | | | |
| Cond Inspe Samp Samp 48 52 57 Samp | itions: PCI: ction Comments: le Number: 146 le Comments: L & T CR RAVELING WEATHERING | 70 Ty J | L L L | R | Area: 243.00 Ft 525.00 SqF 2975.00 SqF | 3500 St St | oction PCI ** | * PCI: | | | | |
| Cond Inspe Samp Samp 48 52 57 Samp | itions: PCI: ction Comments: le Number: 146 le Comments: L & T CR RAVELING WEATHERING le Number: 154 | 70 Ty J | L L L | R R | Area: 243.00 Ft 525.00 SqF 2975.00 SqF | 3500 St St | oction PCI ** | * PCI: | | | | |
| Cond Inspe Samp Samp 48 52 57 Samp | itions: PCI: ction Comments: le Number: 146 le Comments: L & T CR RAVELING WEATHERING le Number: 154 le Comments: | 70 Ty J | L L L | R R | 243.00 Ft 525.00 SqF 2975.00 SqF | 3500 St. 3500 | oction PCI ** | * PCI: | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW C TAXIWAY C Use: TAXIWAY 294,018 SqFt Branch: Area: Name: Section: 325 of 8 From: To: **Last Const.:** 1/1/2002 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 5,247 SqFt 88 Ft Width: 69 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2002 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True TotalSamples: 1 **Last Insp. Date:** 1/24/2022 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 5247.00 SqFt Sample Number: 112 Type: R Area: **PCI:** 59 **Sample Comments:** L 301.00 Ft L & T CR 48 L & T CR M 57.00 Ft 48

66.00 SqFt

26.00 SqFt

4198.00 SqFt

1049.00 SqFt

L

M

L

M

SHOVING

SHOVING

WEATHERING

WEATHERING

54

54

57

57

| Netwo | k: EVB | | | | Nan | ne: NE | W SMYRNA | A BEACH MUNICIP. | AL AIRPOR | Γ | |
|---------|----------------|--------------|----------|--------------|---------------|----------------|--------------|------------------|-----------|-------------------|----------------|
| Branch | TW C | | Nai | me: T | AXIWAY C | , | Use: | TAXIWAY | Area: | 294,018 SqFt | |
| Section | 330 | C | of 8 | From: | - | | | То: - | | Last Const.: | 4/1/2022 |
| Surfac | e: AC | Family: | CA653- | GA-TW-AC | Zon | e: | | Category: | | Rank: P | |
| Area: | | 44,997 SqFt | Le | ength: | 1,215 F | ² t | Width: | 35 Ft | | | |
| Slabs: | | Slab Le | ngth: | | Ft | Slab Width: | | Ft | Join | t Length: | ⁷ t |
| Should | er: | Street T | ype: | | | Grade: 0 | | | Lane | es: 0 | |
| Section | Comments: | | | | | | | | | | |
| Work 1 | Date: 1/1/2002 | W | ork Type | : Complete F | Reconstructio | on - AC | (| Code: CR-AC |] | s Major M&R: True | |
| Work 1 | Date: 4/1/2022 | . W | ork Type | : Complete F | Reconstructio | on - AC | (| Code: CR-AC |] | s Major M&R: True | |
| Last In | sp. Date: 3/1 | 1/2019 | | TotalSample | s: 13 | | Survey | red: 3 | | | |
| Condit | ions: PCI: | 67 | | | NOTE: ** | * Pre-Constru | ection PCI * | *** | | | |
| Inspec | tion Comments | s: | | | | | | | | | |
| Sample | Number: 10 |)2 Ty | pe: | R | Area: | 350 | 0.00 SqFt | PCI: 7 | 0 | | |
| Sample | e Comments: | | | | | | | | | | |
| 48 | L & T CR | | L | 27 | 9.00 Ft | | | | | | |
| | RAVELING | | L | | 4.00 SqFt | | | | | | |
| | RAVELING | | M | | 6.00 SqFt | | | | | | |
| Sample | Number: 10 |)5 Ty | pe: | R | Area: | 350 | 0.00 SqFt | PCI: 6 | 6 | | |
| Sample | e Comments: | | | | | | | | | | |
| | L & T CR | | L | | 5.00 Ft | | | | | | |
| | RAVELING | | L | | 0.00 SqFt | | | | | | |
| 57 | WEATHERIN | G | M | | 0.00 SqFt | | | | | | |
| Sample | Number: 10 | 08 Ty | pe: | R | Area: | 350 | 0.00 SqFt | PCI: 6: | 5 | | |
| Sample | e Comments: | | | | | | | | | | |
| 48 | L & T CR | | L | 30 | 0.00 Ft | | | | | | |
| 52 | RAVELING | | L | | 0.00 SqFt | | | | | | |
| 57 | WEATHERIN | G | M | 40 | 0.00 SqFt | | | | | | |

| Network: EVB | | Name: | NEW SMYRNA | BEACH MUNICIPA | AL AIRPORT | |
|---|-----------------------|---|------------------------------|----------------|-------------|-----------------------|
| Branch: TW C | Name: | TAXIWAY C | Use: | TAXIWAY | Area: | 294,018 SqFt |
| Section: 345 | of 8 | From: - | | То: - | | Last Const.: 1/1/2012 |
| Surface: AC | Family: CA653-GA- | TW-AC Zone: | | Category: | | Rank: P |
| Area: 86,97 | 77 SqFt Length | : 1,125 Ft | Width: | 70 Ft | | |
| Slabs: | Slab Length: | Ft Slab | Width: | Ft | Joint Lengt | th: Ft |
| Shoulder: | Street Type: | Grae | de: 0 | | Lanes: | 0 |
| Section Comments: | | | | | | |
| Work Date: 1/1/2012 | Work Type: Ne | w Construction - Initial | C | ode: NU-IN | Is Majo | or M&R: True |
| Last Insp. Date: 1/24/2022 | 2 Total | Samples: 22 | Surveye | ed: 3 | | |
| Conditions: PCI: 86 | | r | | | | |
| | | | | | | |
| Inspection Comments: | | | | | | |
| Sample Number: 352 | Type: R | Area: | 3750.00 SqFt | PCI: 82 | 2 | |
| | | | | | | |
| Sample Comments: | | | | | | |
| Sample Comments: 45 DEPRESSION | L | 45.00 SqFt | | | | |
| • | L L | 45.00 SqFt 3375.00 SqFt | | | | |
| 45 DEPRESSION | | - | | | | |
| 45 DEPRESSION 57 WEATHERING | L | 3375.00 SqFt | 3750.00 SqFt | PCI: 9 | I | |
| 45 DEPRESSION 57 WEATHERING 57 WEATHERING | L M | 3375.00 SqFt 375.00 SqFt | 3750.00 SqFt | PCI: 9 | I | |
| 45 DEPRESSION 57 WEATHERING 57 WEATHERING Sample Number: 361 Sample Comments: | L M Type: R | 3375.00 SqFt 375.00 SqFt Area: | 3750.00 SqFt | PCI: 9 | I | |
| 45 DEPRESSION 57 WEATHERING 57 WEATHERING Sample Number: 361 | L M | 3375.00 SqFt 375.00 SqFt | 3750.00 SqFt | PCI: 9 | I | |
| 45 DEPRESSION 57 WEATHERING 57 WEATHERING Sample Number: 361 Sample Comments: 57 WEATHERING 57 WEATHERING | L M Type: R | 3375.00 SqFt 375.00 SqFt Area: 3562.00 SqFt | 3750.00 SqFt 5455.00 SqFt | PCI: 9 | | |
| 45 DEPRESSION 57 WEATHERING 57 WEATHERING Sample Number: 361 Sample Comments: 57 WEATHERING | L M Type: R L M | 3375.00 SqFt 375.00 SqFt Area: 3562.00 SqFt 188.00 SqFt | • | | | |
| 45 DEPRESSION 57 WEATHERING 57 WEATHERING 58 WEATHERING 58 Sample Number: 361 59 WEATHERING 50 WEATHERING 50 WEATHERING 51 WEATHERING 52 WEATHERING 53 WEATHERING 54 WEATHERING 55 WEATHERING 56 WEATHERING 57 WEATHERING 58 Sample Number: 371 58 Sample Comments: | Type: R L M Type: R | 3375.00 SqFt 375.00 SqFt Area: 3562.00 SqFt 188.00 SqFt Area: | • | | | |
| 45 DEPRESSION 57 WEATHERING 57 WEATHERING Sample Number: 361 Sample Comments: 57 WEATHERING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 Sample Number: 371 | L M Type: R L M | 3375.00 SqFt 375.00 SqFt Area: 3562.00 SqFt 188.00 SqFt | • | | | |

| Network: E | VB | | | | | Name: | NEW | SMYRNA | BEACH MU | JNICIPAI | L AIRPORT | | | |
|------------------|-----------|-----------|--------|-----------|--------------|-------------|--------|---------|-----------|---------------|-----------|---------|----------------------|----------|
| Branch: T | W D | | Na | ame: | TAXIWA | Y D | | Use: | TAXIWA | Y | Area: | 2 | 10,050 SqFt | |
| Section: 405 | | of | 5 | Fro | m: - | | | | To: | - | | | Last Const.: | 1/1/2002 |
| Surface: AC | | Family: | CA653 | 3-GA-TW-A | AC | Zone: | | | Catego | ory: | | | Rank: P | |
| Area: | 50,62 | 8 SqFt | I | ength: | 1,2 | 00 Ft | , | Width: | 3 | 35 Ft | | | | |
| Slabs: | | Slab Leng | gth: | | Ft | Slab W | Vidth: | | Ft | | Joint L | ength: | F | t |
| Shoulder: | | Street Ty | pe: | | | Grade | : 0 | | | | Lanes: | 0 | | |
| Section Comme | nts: | | | | | | | | | | | | | |
| Work Date: 1/1 | /2002 | Wo | rk Typ | e: Comple | te Reconstru | iction - AC | | C | ode: CR-A | С | Is 1 | Major N | 1&R: True | |
| Last Insp. Date: | 1/24/2022 | | | TotalSam | ples: 11 | | | Surveye | ed: 3 | | | | | |
| Conditions: 1 | PCI: 68 | | | | | | | | | | | | | |
| Inspection Com | ments: | | | | | | | | | | | | | |
| Sample Number | : 301 | Туре | | R | Are | ı: | 4049.0 | 00 SqFt | P | CI: 64 | | | | |
| Sample Comme | | | | | | | | 1 | | | | | | |
| 48 L&TCF | <u>.</u> | | L | | 347.00 Ft | | | | | | | | | |
| 48 L & T CF | | | M | | 25.00 Ft | | | | | | | | | |
| 57 WEATH | | | L | | 025.00 Sc | | | | | | | | | |
| 57 WEATH | ERING | | M | 2 | 024.00 Sc | Ft | | | | | | | | |
| Sample Number | : 304 | Туре | e: | R | Are | ı: | 3500.0 | 00 SqFt | P | CI: 70 | | | | |
| Sample Comme | nts: | | | | | | | | | | | | | |
| 48 L & T CF | t. | | L | | 187.00 Ft | | | | | | | | | |
| 48 L & T CF | 1 | | M | | 25.00 Ft | | | | | | | | | |
| 57 WEATH | | | L | | 625.00 Sc | | | | | | | | | |
| 57 WEATH | ERING | | M | | 875.00 Sc | Ft | | | | | | | | |
| Sample Number | : 306 | Туре | e: | R | Are | ı: | 3500. | 00 SqFt | P | CI: 70 | | | | |
| Sample Comme | nts: | | | | | | | | | | | | | |
| 48 L & T CF | | | L | | 185.00 Ft | | | | | | | | | |
| 48 L & T CF | 1 | | M | | 15.00 Ft | | | | | | | | | |
| 57 WEATH | ERING | | L | 2 | 625.00 Sc | Ft | | | | | | | | |
| 57 WEATH | PING | | M | | 875.00 Sc | | | | | | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW D TAXIWAY D Use: TAXIWAY 210,050 SqFt **Branch:** Area: Name: Section: 415 of 5 From: To: -**Last Const.:** 1/1/1943 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 7,000 SqFt 140 Ft Width: 50 Ft Area: Length: Slabs: Slab Length: Ft Slab Width: Joint Length: Ft Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1943 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 2 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 3500.00 SqFt **PCI:** 23 Sample Number: 98 Type: R Area: **Sample Comments:** BLOCK CR 2975.00 SqFt 43 M

BLOCK CR

RAVELING

RAVELING

43

52

52

Η

L

M

525.00 SqFt

3325.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW D TAXIWAY D Use: TAXIWAY 210,050 SqFt **Branch:** Area: Name: Section: 425 of 5 From: To: **Last Const.:** 1/1/2014 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 27,118 SqFt 700 Ft Width: 35 Ft Area: Length: Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/1943 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True Work Date: 1/1/2014 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 7 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 124 Type: R Area: 3500.00 SqFt **PCI:** 89 **Sample Comments:** L & T CR L 31.00 Ft 48

WEATHERING

L

3500.00 SqFt

57

| Network: | EVB | | | Name: | NEW SMYRNA | BEACH MUNICIP | AL AIRPORT | |
|--------------|------------------|-----------|--------------|--------------------------|--------------|----------------|------------|-----------------------|
| Branch: | TW D | | Name: | TAXIWAY D | Use: | TAXIWAY | Area: | 210,050 SqFt |
| Section: 4 | 427 | of | 5 | From: - | | То: - | | Last Const.: 1/1/2014 |
| Surface: | AC | Family: | CA653-GA-T | W-AC Zone: | | Category: | | Rank: P |
| Area: | 40,33 | 35 SqFt | Length: | 1,100 Ft | Width: | 35 Ft | | |
| Slabs: | | Slab Leng | gth: | Ft Sla | b Width: | Ft | Joint Lei | ngth: Ft |
| Shoulder: | | Street Ty | pe: | Gr | ade: 0 | | Lanes: | 0 |
| Section Con | nments: | | | | | | | |
| Work Date: | 1/1/1943 | Wo | rk Type: New | Construction - Initial | C | ode: NU-IN | Is M | ajor M&R: True |
| Work Date: | 1/1/2014 | Wo | rk Type: Com | plete Reconstruction - A | AC C | ode: CR-AC | Is M | ajor M&R: True |
| Last Insp. D | Date: 1/24/2022 | 2 | TotalS | amples: 11 | Surveye | ed: 2 | | |
| Conditions: | PCI: 90 | | | | | | | |
| Inspection (| Comments: | | | | | | | |
| Sample Nur | nber: 135 | Турс | e: R | Area: | 3500.00 SqFt | PCI: 9 | 0 | |
| Sample Con | nments: | | | | | | | |
| 48 L& | T CR | | L | 17.00 Ft | | | | |
| 57 WEA | ATHERING | | L | 3500.00 SqFt | | | | |
| Sample Nur | nber: 138 | Турс | e: R | Area: | 3846.00 SqFt | PCI : 9 | 1 | |
| Sample Con | nments: | | | | | | | |
| 48 L& | T CR | | L | 8.00 Ft | | | | |
| 57 WEA | ATHERING | | L | 3846.00 SqFt | | | | |

| Network: EVB | | Name: | NEW SMYRNA I | BEACH MUNICIPA | AL AIRPORT | | |
|---|-------------------------------|---|------------------------------|----------------|------------|------------------|-------|
| Branch: TW D | Name: | TAXIWAY D | Use: | TAXIWAY | Area: | 210,050 SqFt | |
| Section: 430 | of 5 | From: - | | То: - | | Last Const.: 1/1 | /2016 |
| Surface: AAC | Family: CA653-GA- | TW-AAC- Zone: | | Category: | | Rank: P | |
| Area: 84,9 | 69 SqFt Length | 2,100 Ft | Width: | 50 Ft | | | |
| Slabs: | Slab Length: | Ft Slab | Width: | Ft | Joint Lo | ength: Ft | |
| Shoulder: | Street Type: | Grad | e: 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | |
| Work Date: 1/1/1943 | Work Type: Ne | w Construction - Initial | Со | ode: NU-IN | Is N | Major M&R: True | |
| Work Date: 1/1/2016 | Work Type: Mi | ll and Overlay | Со | ode: ML-OVL | Is N | Major M&R: True | |
| Last Insp. Date: 1/24/202 | TE 4.1 | | | | | | |
| Last 111sp. Date. 1/24/202 | 22 Total | lSamples: 21 | Surveyed | l : 3 | | | |
| Conditions: PCI: 88 | 22 I otal | iSamples: 21 | Surveyed | 1: 3 | | | |
| | 22 I otal | ISamples: 21 | Surveyed | 1: 3 | | | |
| Conditions: PCI: 88 Inspection Comments: | | Area: | · | PCI: 89 |) | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 | | | Surveyed 5441.00 SqFt | |) | | |
| Conditions: PCI: 88 | | | · | |) | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: | Type: R | Area: | · | |) | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING | Type: R | Area: 73.00 Ft | · | | | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: 48 L&TCR | Type: R L L | Area: 73.00 Ft 5441.00 SqFt | 5441.00 SqFt | PCI: 89 | | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING Sample Number: 111 Sample Comments: | Type: R L L | Area: 73.00 Ft 5441.00 SqFt | 5441.00 SqFt | PCI: 89 | | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING Sample Number: 111 Sample Comments: | Type: R L L Type: R | 73.00 Ft 5441.00 SqFt Area: | 5441.00 SqFt | PCI: 89 | | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING Sample Number: 111 Sample Comments: 48 L & T CR | Type: R L L Type: R | 73.00 Ft 5441.00 SqFt Area: | 5441.00 SqFt | PCI: 89 | 5 | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING Sample Number: 111 Sample Comments: 48 L & T CR 57 WEATHERING | Type: R L L Type: R L L L | 73.00 Ft 5441.00 SqFt Area: 91.00 Ft 3500.00 SqFt | 5441.00 SqFt 3500.00 SqFt | PCI: 89 | 5 | | |
| Conditions: PCI: 88 Inspection Comments: Sample Number: 105 Sample Comments: 48 L & T CR 57 WEATHERING Sample Comments: 48 L & T CR 57 WEATHERING Sample Comments: 48 L & T CR 57 WEATHERING Sample Number: 115 | Type: R L L Type: R L L L | 73.00 Ft 5441.00 SqFt Area: 91.00 Ft 3500.00 SqFt | 5441.00 SqFt 3500.00 SqFt | PCI: 89 | 5 | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW E TAXIWAY E Use: TAXIWAY 198,202 SqFt Branch: Area: Name: Section: 505 of 5 From: To: **Last Const.:** 1/1/2014 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 17,197 SqFt 35 Ft Width: 500 Ft Area: Length: Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Code: NU-IN Work Date: 1/1/1943 Work Type: New Construction - Initial Is Major M&R: True Work Type: Complete Reconstruction - AC Work Date: 1/1/2014 Code: CR-AC Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 5 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 101 Type: R Area: 3500.00 SqFt **PCI:** 91 **Sample Comments:**

57 WEATHERING L 3325.00 SqFt 57 WEATHERING M 175.00 SqFt

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: TW E TAXIWAY E Use: TAXIWAY 198,202 SqFt Branch: Area: Name: Section: 510 of 5 From: To: **Last Const.:** 1/1/2014 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 24,594 SqFt 35 Ft Width: 720 Ft Area: Length: Slab Length: Ft Slab Width: Joint Length: Ft Slabs: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Code: NU-IN Work Date: 1/1/1943 Work Type: New Construction - Initial Is Major M&R: True Work Date: 1/1/2014 Work Type: Complete Reconstruction - AC Code: CR-AC Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 7 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** Sample Number: 108 Type: R Area: 3500.00 SqFt **PCI:** 90 **Sample Comments:**

L & T CR

WEATHERING

48

57

L

L

21.00 Ft

| Network: EVB | | Name: | NEW SMYRNA I | BEACH MUNICIPA | L AIRPORT | |
|-----------------------------------|---------------------|------------------------|--------------|----------------|--------------|-----------------------|
| Branch: TW E | Name: | TAXIWAY E | Use: | TAXIWAY | Area: | 198,202 SqFt |
| Section: 515 | of 5 | rom: - | | То: - | | Last Const.: 7/1/2011 |
| Surface: AC | Family: CA653-GA-TV | V-AC Zone: | | Category: | | Rank: P |
| Area: 52,494 | 4 SqFt Length: | 50 Ft | Width: | 1,050 Ft | | |
| Slabs: | Slab Length: | Ft Slab W | idth: | Ft | Joint Length | : Ft |
| Shoulder: | Street Type: | Grade: | : 0 | | Lanes: 0 | |
| Section Comments: | | | | | | |
| Work Date: 7/1/2011 | Work Type: New | Construction - Initial | Со | de: NU-IN | Is Major | M&R: True |
| Last Insp. Date: 1/24/2022 | TotalSa | amples: 13 | Surveyed | l : 2 | | |
| Conditions: PCI: 84 | | | | | | |
| Inspection Comments: | | | | | | |
| Sample Number: 116 | Type: R | Area: | 3500.00 SqFt | PCI: 86 | | |
| Sample Comments: | | | | | | |
| 57 WEATHERING | L | 2800.00 SqFt | | | | |
| 57 WEATHERING | M | 700.00 SqFt | | | | |
| Sample Number: 123 | Type: R | Area: | 3500.00 SqFt | PCI: 83 | | |
| Sample Comments: | | | | | | |
| 48 L & T CR | L | 10.00 Ft | | | | |
| 57 WEATHERING | L | 2800.00 SqFt | | | | |
| 57 WEATHERING | M | 700.00 SqFt | | | | |

EVB NEW SMYRNA BEACH MUNICIPAL AIRPORT Network: Name: **Branch:** TW E TAXIWAY E Use: TAXIWAY 198,202 SqFt Area: Name: Section: 520 of 5 From: To: -**Last Const.:** 1/1/2014 Surface: AC Family: CA653-GA-TW-AC Zone: Category: Rank: P 27,412 SqFt 35 Ft Width: 900 Ft Area: Length: Slab Width: Slabs: Slab Length: Ft Joint Length: Ft Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2014 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 1/24/2022 **TotalSamples:** 8 Surveyed: 1 **Conditions:** PCI: **Inspection Comments:** 3503.00 SqFt **PCI:** 91 Sample Number: 201 Type: R Area: **Sample Comments:**

WEATHERING

WEATHERING

57 57 L

M

3328.00 SqFt

| Network: | EVB | | | | Nan | ne: NEV | W SMYRNA | BEACH MU | NICIPAL | AIRPORT | | |
|--------------|------------|-------------------------------------|---------|------------|-----------------|-----------------|-----------|------------|---------|--------------|--------------|---------------|
| Branch: | TW E | | N | ame: | TAXIWAY E | | Use: | TAXIWAY | Ι. | Area: | 198,202 SqFt | |
| Section: 5 | 530 | 0 | f 5 | Fro | m: - | | | То: - | | | Last Con | st.: 1/1/2018 |
| Surface: | AC | Family: | CA65 | 3-GA-TW-A | C Zon | e: | | Catego | ry: | | Rank: P | |
| Area: | | 76,505 SqFt |] | Length: | 2,100 F | t | Width: | 3 | 5 Ft | | | |
| Slabs: | | Slab Lei | igth: | | Ft | Slab Width: | | Ft | | Joint Length | ı: | Ft |
| Shoulder: | | Street T | ype: | | | Grade: 0 | | | | Lanes: 0 | | |
| Section Con | nments: | | | | | | | | | | | |
| Work Date: | : 1/1/1940 | W | ork Typ | e: New Co | nstruction - AC | | C | Code: NC-A | | Is Major | M&R: True | |
| Work Date: | : 1/1/2018 | W | ork Typ | e: Complet | e Reconstructio | n - AC | C | Code: CR-A | C | Is Major | M&R: True | |
| Last Insp. D | Date: 1/24 | 1/2022 | | TotalSamp | ples: 14 | | Surveye | ed: 2 | | | | |
| Conditions: | PCI: | 94 | | | | | | | | | | |
| Inspection (| Comments: | : | | | | | | | | | | |
| Sample Nur | mber: 202 | $\mathbf{T}\mathbf{y}_{\mathbf{j}}$ | pe: | R | Area: | 5168 | 3.00 SqFt | PO | CI: 94 | | | |
| Sample Con | mments: | | | | | | | | | | | |
| 57 WEA | ATHERING | ì | L | 5 | 168.00 SqFt | | | | | | | |
| Sample Nur | mber: 209 | 9 Ty] | pe: | R | Area: | 5075 | 5.00 SqFt | PC | CI: 94 | | | |
| Sample Con | nments: | | | | | | | | | | | |

WEATHERING

57

L



FLORIDA DEPARTMENT OF TRANSPORTATION | **AVIATION OFFICE**

