





Florida Department of Transportation

# Statewide Airfield Pavement Management Program

# **Airport Pavement Evaluation Report**

#### Prepared by:

FDOT Aviation Office 605 Suwannee Street Tallahassee, Florida 32399-0450

Website: FDOT Aviation Office


Interactive Web Application: FDOT SAPMP Interactive Web Application



# TABLE OF CONTENTS

EXECUTIVE SUMMARY	1
Program Background	
Current Pavement Conditions	
Forecasted Pavement Conditions	
Major Rehabilitation Planning 2023-2032	5
CHAPTER 1 – INTRODUCTION	
1.1 Background	
1.2 Stakeholders	
1.3 General Scope of Work	10
1.4 FDOT SAPMP Objectives	11
CHAPTER 2 – METHODOLOGY	14
2.1 Airfield Pavement Database	
2.2 Airfield Pavement Record Keeping (Historical Records Research)	15
2.3 Airfield Pavement Structure	15
2.3.1 Asphalt Concrete	
2.3.2 Portland Cement Concrete	
2.3.3 Composite Structure – Whitetopping Pavement	
2.4 Airfield Pavement Traffic	
2.5 Pavement Management Program Network Definition Terminology	
2.5.1 Pavement Network Identification	
2.5.2 Pavement Branch Identification	17
2.5.3 Pavement Section Identification	
2.5.4 Pavement Sample Unit Identification	18
2.5.5 Terminology Summary	
2.6 Airfield PCI Survey Methodology	18
2.6.1 Pavement Distress Types	
2.6.2 PCI Survey Procedures	20
CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY	23
3.1 Airfield Pavement Network Information	
3.1.1 Previous and/or Anticipated Airfield Pavement Construction	23
3.1.2 Estimated Pavement Age	
3.1.3 Functional Use	
3.1.4 Pavement Surface Type	29
3.1.5 Pavement System Inventory Details	30
CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS	33
4.1 Airfield Pavement Condition Index	33
4.1.1 Network-Level Analysis	33
4.1.2 Branch-Level Analysis	33
4.1.3 Section-Level Analysis	
4.2 Summary of Pavement Condition Evaluation Results	40

	40
4.2.2 Branch-Level Observations	
CHAPTER 5 – SAPMP CUSTOMIZATION	
5.1 Network-Level Customization	
5.2 Pavement Condition Forecasts	
5.2.1 Forecasting PCI Considerations	
5.2.2 Performance Models	
5.2.3 Branch-Level Pavement Condition Forecast	
5.2.4 Section-Level Pavement Condition Forecast	
5.3 Critical PCI Value	
5.4 Localized Maintenance and Repair	
5.4.1 Localized Maintenance and Repair Approach	
5.4.2 Localized Work Types	
5.4.3 Localized Maintenance Planning-Level Unit Costs	
5.4.4 Localized Maintenance and Repair Policy	
5.5 Major Rehabilitation	
5.5.1 Major Rehabilitation Pavement Section Development	
5.5.2 Major Rehabilitation Planning-Level Unit Costs	08
CHAPTER 6 - M&R PLANNING AND BUDGET SCENARIO ANALYSIS	70
6.1 Localized Maintenance and Repair Analysis and Recommendations	70
6.1 Localized Maintenance and Repair Analysis and Recommendations 6.2 Major Rehabilitation Needs	
	72
6.2 Major Rehabilitation Needs	<b>.72</b>
6.2 Major Rehabilitation Needs	727277
6.2 Major Rehabilitation Needs	72727777
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations	<b>727777777777</b>
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair	<b>72777777</b>
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation	7277777777
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation 7.1.4 Pavement Management System	7277777777
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation 7.1.4 Pavement Management System 7.2 Supporting Documents	727777777777
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations	7277777777777777
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation 7.1.4 Pavement Management System 7.2 Supporting Documents Airfield Pavement Network Definition Exhibit Airfield Pavement System Inventory Exhibit	72777777777777777777
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation 7.1.4 Pavement Management System 7.1.5 Supporting Documents Airfield Pavement Network Definition Exhibit Airfield Pavement System Inventory Exhibit Airfield Pavement Estimated Age Exhibit	72777777777777777878
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation 7.1.4 Pavement Management System 7.2 Supporting Documents Airfield Pavement Network Definition Exhibit Airfield Pavement System Inventory Exhibit Airfield Pavement Estimated Age Exhibit Airfield Pavement Condition Index Exhibit	72777777777777787878
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation 7.1.4 Pavement Management System.  7.2 Supporting Documents Airfield Pavement Network Definition Exhibit Airfield Pavement Estimated Age Exhibit Airfield Pavement Condition Index Exhibit Airfield Pavement Major Rehabilitation Exhibit	7277777777777878787878
6.2 Major Rehabilitation Needs 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs  CHAPTER 7 – CONCLUSION 7.1 Recommendations 7.1.1 Continued PCI Surveys 7.1.2 Localized Maintenance and Repair 7.1.3 Major Rehabilitation 7.1.4 Pavement Management System 7.2 Supporting Documents Airfield Pavement Network Definition Exhibit Airfield Pavement System Inventory Exhibit Airfield Pavement Estimated Age Exhibit Airfield Pavement Condition Index Exhibit	



# LIST OF TABLES

2
3
5
.10
.18
.19
.20
.20
.21
.23
.30
.36
.38
.55
.57
.57
.62
.62
.63
.64
.66
.68
.70
.71
.71
.73

# LIST OF FIGURES

Figure E.1: PCI Rating	1
Figure E.2: Current Condition Summary – Branch-Level	2
Figure E.3: 10-Year Major Rehabilitation Needs by Program Year	6
Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts	9
Figure 1.4: Pavement Life and the Effect of Treatments	12
Figure 2: FDOT SAPMP General Process	14
Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit	25
Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit	26
Figure 3.1.2 (a): Age of Pavements at PCI Survey	27
Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit	28
Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)	29
Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)	30
Figure 4.1.1: Current Condition – Overall Network	33
Figure 4.1.2 (a): Current Condition Summary – Branch-Level	33
Figure 4.1.2 (b): Current Condition – Runway	34
Figure 4.1.2 (c): Current Condition – Taxiway	34
Figure 4.1.2 (d): Current Condition – Apron	35
Figure 4.1.3: Airfield Pavement Condition Index Exhibit	39
Figure 5.2.3: Forecasted Branch-Level Pavement Performance	54
Figure 5.3 (a): Pavement Life and the Effect of Treatments	56
Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, PCI < Critical PCI	58
Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, PCI ≥ Critical PCI	58
Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year	74
Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit	75



**Executive Summary** 

# **Executive Summary**

# **Program Background**

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Key West International Airport's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section. This is graphically depicted in **Figure E.1**.

Figure E.1: PCI Rating

Color	Range	Condition Rating
	86-100	Good
	71-85	Satisfactory
	56-70	Fair
	41-55	Poor
	26-40	Very Poor
	11-25	Serious
	0-10	Failed



#### **Current Pavement Conditions**

In October 2022, approximately 1.8 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Key West International Airport (EYW). In general, airfield pavements at EYW are in Satisfactory condition with an area-weighted PCI of 82. The area-weighted average PCI values of the runways, taxiways, and aprons are 86, 96, and 73, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for EYW.




Figure E.2: Current Condition Summary - Branch-Level

Table E.1: Pavement Condition Index Summary (Current PCI Survey) - Section Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
EYW	RW 9-27	Runway	6105	480,000	86	Good
EYW	RW 9-27	Runway	6115	12,600	81	Satisfactory
EYW	RW 9-27	Runway	6120	18,000	100	Good
EYW	TW A	Taxiway	100	167,850	100	Good
EYW	TW A	Taxiway	105	11,729	73	Satisfactory
EYW	TW A	Taxiway	110	57,185	100	Good
EYW	TW A1	Taxiway	130	19,096	90	Good
EYW	TW A1	Taxiway	135	20,821	39	Very Poor
EYW	TW A2	Taxiway	120	8,949	100	Good
EYW	TW A2	Taxiway	125	16,030	100	Good
EYW	TW A3	Taxiway	140	9,075	100	Good
EYW	TW A3	Taxiway	145	25,387	100	Good
EYW	TW A4	Taxiway	160	6,462	100	Good
EYW	TW A4	Taxiway	165	11,930	100	Good
EYW	TW B1	Taxiway	215	7,765	100	Good
EYW	TW B10	Taxiway	260	8,893	100	Good
EYW	TW B11	Taxiway	265	5,749	100	Good



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
EYW	TW B11	Taxiway	267	3,067	91	Good
EYW	TW B12	Taxiway	Taxiway 270 11,359		100	Good
EYW	TW B2	Taxiway	220	3,779	100	Good
EYW	TW B3	Taxiway	225	3,864	100	Good
EYW	TW B4	Taxiway	230	3,864	100	Good
EYW	TW B5	Taxiway	235	7,125	100	Good
EYW	TW B6	Taxiway	240	6,842	100	Good
EYW	TW B7	Taxiway	245	6,819	100	Good
EYW	TW B8	Taxiway	250	6,972	100	Good
EYW	TW B9	Taxiway	255	5,828	100	Good
EYW	TW B9	Taxiway	257	3,071	73	Satisfactory
EYW	AP GA	Apron	4130	29,979	39	Very Poor
EYW	AP GA	Apron	4145	144,422	41	Poor
EYW	AP GA	Apron	4150	18,084	31	Very Poor
EYW	AP GA	Apron	4155	48,170	52	Poor
EYW	AP GA	Apron	4205	75,458	61	Fair
EYW	AP GA	Apron	4215	58,338	57	Fair
EYW	AP GA	Apron	4220	13,765	52	Poor
EYW	AP GA	Apron	4225	78,577	100	Good
EYW	AP TERM	Apron	4105	34,810	40	Very Poor
EYW	AP TERM	Apron	4160	336,953	98	Good

#### **Forecasted Pavement Conditions**

**Table E.2** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

Table E.2: Forecasted PCI Values 2023-2032 - Section-Level

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
EYW	RW 9-27	6105	86	85	83	81	79	77	75	73	71	69	67
EYW	RW 9-27	6115	81	80	78	77	75	74	72	71	69	68	66
EYW	RW 9-27	6120	100	99	98	97	96	95	94	94	93	92	92
EYW	TW A	100	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A	105	73	72	70	68	67	65	64	62	61	60	59
EYW	TW A	110	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A1	130	90	88	86	84	81	79	77	75	73	71	70
EYW	TW A1	135	39	38	36	34	32	29	26	23	20	16	11
EYW	TW A2	120	100	96	93	91	89	86	84	82	80	77	75



# **Airport Pavement Evaluation Report** Statewide Airfield Pavement Management Program

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
EYW	TW A2	125	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A3	140	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A3	145	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A4	160	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A4	165	100	96	93	91	89	86	84	82	80	77	75
EYW	TW B1	215	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B10	260	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B11	265	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B11	267	91	91	90	90	89	89	89	88	88	88	87
EYW	TW B12	270	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B2	220	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B3	225	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B4	230	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B5	235	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B6	240	100	96	93	91	89	86	84	82	80	77	75
EYW	TW B7	245	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B8	250	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B9	255	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B9	257	73	72	71	69	68	66	65	63	61	59	57
EYW	AP GA	4130	39	38	36	34	32	30	28	25	23	20	17
EYW	AP GA	4145	41	40	38	36	34	32	30	28	26	23	21
EYW	AP GA	4150	31	30	28	26	25	23	21	20	18	16	15
EYW	AP GA	4155	52	51	50	48	47	45	44	42	40	39	37
EYW	AP GA	4205	61	60	58	56	55	53	51	50	48	46	45
EYW	AP GA	4215	57	56	54	52	51	49	47	46	44	42	41
EYW	AP GA	4220	52	51	49	47	46	44	42	41	39	37	36
EYW	AP GA	4225	100	95	92	89	86	84	81	79	77	75	73
EYW	AP TERM	4105	40	39	37	35	33	31	29	27	24	22	19
EYW	AP TERM	4160	98	97	96	95	94	93	92	91	90	89	88



# Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$22.20M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$11.33M and localized maintenance needs for Year 1 are \$0.14M.


**Program** Network **Branch** Section PCI Rehabilitation **Planning Cost** Area **Surface** Before **Estimate** Year ID ID ID (SF) **Type EYW** TW A1 AC Reconstruction 2023 135 AAC 20,821 38 636,000 AC Reconstruction 2023 **EYW** AP GA 4130 AAC 29,979 38 \$ 915,000 \$ **EYW** AP GA 4145 AAC 144,422 40 AC Reconstruction 4,405,000 2023 AC Reconstruction 2023 **EYW** AP GA 4150 AC 18,084 30 \$ 552,000 2023 **EYW** AP GA 4155 AAC 48,170 51 AC Reconstruction \$ 1,470,000 2023 **EYW** AP GA 4205 AC 75,458 60 AC Rehabilitation \$ 1,057,000 **EYW** 4215 AC \$ 2023 AP GA 58,338 56 AC Rehabilitation 817,000 2023 **EYW** AP GA 4220 AC 13,765 51 AC Reconstruction \$ 420,000 **EYW** AP TERM 4105 \$ 2023 AAC 34,810 39 AC Reconstruction 1,062,000 2024 **EYW** TW A 105 AAC 11,729 70 AC Rehabilitation \$ 173,000 2025 **EYW** TW B9 257 **PCC** 3,071 69 **PCC** Rehabilitation \$ 104,000 \$ 2030 **EYW** RW 9-27 6115 AC 12,600 69 AC Rehabilitation 249,000 \$ 2031 **EYW** RW 9-27 6105 AAC 480,000 69 AC Rehabilitation 9,929,000 2032 **EYW** TW A1 130 AAC 19,096 AC Rehabilitation 415,000

Table E.3: Major Rehabilitation Planning 2023-2032



<sup>\*</sup>All planning cost values have been rounded up to the nearest thousand dollars.

Figure E.3: 10-Year Major Rehabilitation Needs by Program Year







**Chapter 1: Introduction** 

# **Chapter 1 – Introduction**

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida's economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida's most prominent industry.

## 1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management Program (PMP)". The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".


In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are



under consideration for projects. A network-level evaluation can support the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts





#### 1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

Table 1.2: FDOT SAPMP Stakeholders

Role	Description
FAA Orlando Airports District Office (Orlando ADO)	Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation).
Florida Department of Transportation (FDOT)	Key Stakeholder: the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System.
FDOT District Offices	The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes.
Participating Public-Use and Publicly-Owned Airports	The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment.
Aviation Office Program Manager (AO-PM)	FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update.

# 1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- Research and evaluation of existing record documentation;
- Establishment of a pavement system inventory;
- Development of a pavement network definition map and supplemental GIS model;
- Functional pavement evaluations via the PCI assessment method;
- Customization of PAVER<sup>™</sup> software including prioritization, policies, and performance models;
- Analysis of condition data; and
- Maintenance, repair, and rehabilitation planning.



# 1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.

A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:

- Assist airports in meeting the requirements of Public Law 103-305;
- Assist airports in complying with FAA Grant Assurances 11 and 19;
- Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts:
- Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.






Figure 1.4: Pavement Life and the Effect of Treatments

FAA Eligibilty Thresholds: -70: Routine Maintenance 55-70: Rehabilitation Eligible <55: Reconstruction Eligible

\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements



**Chapter 2: Methodology** 

# **Chapter 2 – Methodology**

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.




Figure 2: FDOT SAPMP General Process

## 2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- Create a manageable inventory system;
- Analyze the current condition of pavements in accordance with ASTM D5340-20;
- Develop pavement performance models to forecast conditions; and
- Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER<sup>TM</sup> inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER<sup>TM</sup> database and typically consist of pavement inventory



characteristics, pavement structure, work history, historic condition records, and analytical customization.

## 2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- Location and limits of work;
- Types and severities of repaired distresses;
- Work type and cost; and
- Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- Date of last construction/rehabilitation
- Work type performed
- Comments for documenting pavement cross-section
- Pavement surface type
- Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

#### 2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.



#### 2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

#### **Asphalt Concrete (AC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

### Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

#### <u>Asphalt Concrete Overlaid on Portland Cement Concrete (APC)</u>

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

#### 2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

#### Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

## 2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

## **Conventional Whitetopping (WT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.



### **Thin Whitetopping (TWT)**

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

### **Ultra-Thin Whitetopping (UWT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

#### 2.4 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of EYW's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

## 2.5 Pavement Management Program Network Definition Terminology

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

#### 2.5.1 Pavement Network Identification

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

#### 2.5.2 Pavement Branch Identification

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.



#### 2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

#### 2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs (±8 slabs) for PCC pavement and 5,000 contiguous square feet (±2,000 SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

#### 2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

SAPMP Terminology	Common Definition	Airport Example
Network	Totality of pavement assets maintained by the Airport.	"Tallahassee International Airport – Airfield Pavements"
Branch Name	Commonly defined asset name as established by Airport and by use.	"Runway 18-36"
Branch ID	Codified shorthand name for commonly defined asset established for database identification.	"RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility
Section ID	Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition.	"6105"
Sample Unit	A numeric identification of an area of pavement (5,000 ± 2,000 SF of AC or 20 ± 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20.	"300"

Table 2.5.5: SAPMP Terminology

# 2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.



Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

#### 2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

Table 2.6.1 (a): Pavement Distress Types - Asphalt Concrete

Distress Mechanism	Distress Type
Load	Alligator Cracking Rutting
Climate/Durability	Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering
Construction/Material	Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling
Other	Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching



Table 2.6.1 (b): Pavement Distress Types - Portland Cement Concrete

Distress Mechanism	Distress Type	
Load	Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks	
Climate/Durability	Blowup Durability "D" Cracking Joint Seal Damage Popouts	
Construction/Material	Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking	
Other	Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching	

#### 2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a)** and **(b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.


Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10

Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.



Chapter 3: Airfield Pavement System Inventory

# Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

#### 3.1 Airfield Pavement Network Information

#### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.

Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction

Construction Year	Location	Work Type / Pavement Section
2018	RW 9-27	New Construction - AC   9" P-401, Rework Existing Base
	RW 9-27	New Construction - PCC   13" P-501, Rework Existing Base
	RW 9-27	Mill and Overlay   0.5" Mill, Variable Depth P-401 Overlay
	TW A1, TW A2, TW A3, TW A4	Mill and Overlay
	AP TERM	Complete Reconstruction - PCC   13"P-501, Rework Existing Base
	TW B9, B11	Complete Reconstruction - PCC
2021	AP GA, TW A, TW A4	Mill and Overlay   Variable Depth Mill, Variable Depth P-401 Overlay
	TW A2, TW A3	Mill and Overlay   Variable Depth Mill, Variable Depth P-401 Overlay; Fillet Widening (7" P-401, 9" P-211)
	TW B1, TW B2, TW B3, TW B4, TW B5	Complete Reconstruction - AC   4" P-401, Rework Existing Base; Fillet Widening (4" P-401, 8" P-211)
	TW B6	Mill and Overlay   Variable Depth Mill, Variable Depth P-401 Overlay; Fillet Widening (4" P-401, 8" P-211)
	TW B7, TW B8	Complete Reconstruction - AC   4" P-401, 8" P-211
	TW B9, TW B10, TW B11, TW B12	Complete Reconstruction - AC   7" P-401, Rework Existing Base; Fillet Widening (7" P-401, 9" P-211)

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

Figure 3.1.1 (a), the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions,



# Airport Pavement Evaluation Report


Statewide Airfield Pavement Management Program

and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.





RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



AC AP GA 4215 2 11

4225~

400 401 402 403 404 500 501 502 503

TW A1

135
2 5


TW A

102 103 104 105 106 107 108 109 1 0 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 42 143 144 145 146 147

AC AP GA 4220 1 3

502 503 504

602 603 604 605



# **LEGEND**

- TYPICAL RUNWAY BRANCH ID - TYPICAL TAXIWAY BRANCH ID

AAC
AP TERM
4105
1 7

600

TYPICAL APRON BRANCH ID PAVEMENT SURFACE TYPE ---- PAVEMENT BRANCH ID SECTION NUMBER

> NUMBER OF SAMPLE UNITS IN SECTION NUMBER OF SAMPLE UNITS TO BE INSPECTED



216 215 214 213 212 211 210 209 208 207 206 205 204 203 202 201

316 315 314 313 312 311 310 309 308 307 306 305 304 303 302 301

510 509 508 507 506 505 504 503

PCC AP TERM 4160 8 71

616 653 615 614 613 612 611

AAC AP GA 4130

<u>16</u> 915

AAC AP GA 4145

SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.




TOTAL SAMPLES INSPECTED = 51 AC: 39 PCC: 12

INSPECTED SAMPLE UNITS.

FDOT





#### RECENT & ANTICIPATED CONSTRUCTION ACTIVITY

CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2018	RW 9-27	New Construction - AC   9" P-401, Rework Existing Base
	RW 9-27	New Construction - PCC   13" P-501, Rework Existing Base
	RW 9-27	Mill and Overlay   0.5" Mill, Variable Depth P-401 Overlay
	TW A1, TW A2, TW A3, TW A4	Mill and Overlay
	AP TERM	Complete Reconstruction - PCC   13"P-501, Rework Existing Base
	TW B9, TW B11	Complete Reconstruction - PCC
	AP GA, TW A,	Mill and Overlay   Variable Depth Mill,
	TW A4	Variable Depth P-401 Overlay
	TW A2, TW A3,	Mill and Overlay   Variable Depth Mill, Variable Depth P-401 Overlay; Fillet
		Widening (7" P-401, 9" P-211)
	TW B1, TW B2,	Complete Reconstruction - AC   4" P-401,
	TW B3, TW B4,	Rework Existing Base; Fillet Widening (4"
2021	TW B5	P-401, 8" P-211)
2021	TW B6	Mill and Overlay   Variable Depth Mill, Variable Depth P-401 Overlay; Fillet Widening (4" P-401, 8" P-211)
	TW B7, TW B8	Complete Reconstruction - AC   4" P-401, 8" P-211
	TW B9, TW B10, TW B11, TW B12	Complete Reconstruction - AC   7" P-401, Rework Existing Base; Fillet Widening (7" P-401, 9" P-211)



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.






Figure 3.1.2 (a): Age of Pavements at PCI Survey









RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

#### 3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed "functional use" or "branch use." For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.





Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)


#### 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at EYW.







#### 3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

**Table 3.1.5** displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

**Surface Estimate of Last Network ID Branch ID Branch Use Section ID** Area (SF) Type **Construction Date EYW** RW 9-27 Runway 6105 480,000 AAC 4/1/2018 **EYW** RW 9-27 AC 1/1/2018 Runway 6115 12,600 **EYW** PCC RW 9-27 6120 Runway 18,000 1/1/2018 **EYW** TW A 100 167,850 AAC 11/1/2021 Taxiway **EYW** TW A AAC Taxiway 105 11,729 1/1/2003 **EYW** TW A Taxiway 110 57,185 AAC 11/1/2021 **EYW** TW A1 Taxiway 130 19.096 AAC 4/1/2018 TW A1 **EYW** Taxiway 135 20,821 AAC 1/1/2003


Table 3.1.5: Pavement System Inventory Details



## **Airport Pavement Evaluation Report** Statewide Airfield Pavement Management Program

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
EYW	TW A2	Taxiway	120	8,949	AAC	11/1/2021
EYW	TW A2	Taxiway	125	16,030	AAC	11/1/2021
EYW	TW A3	Taxiway	140	9,075	AAC	11/1/2021
EYW	TW A3	Taxiway	145	25,387	AAC	11/1/2021
EYW	TW A4	Taxiway	160	6,462	AAC	11/1/2021
EYW	TW A4	Taxiway	165	11,930	AAC	11/1/2021
EYW	TW B1	Taxiway	215	7,765	AC	11/1/2021
EYW	TW B10	Taxiway	260	8,893	AC	11/1/2021
EYW	TW B11	Taxiway	265	5,749	AC	11/1/2021
EYW	TW B11	Taxiway	267	3,067	PCC	10/1/2018
EYW	TW B12	Taxiway	270	11,359	AC	11/1/2021
EYW	TW B2	Taxiway	220	3,779	AC	11/1/2021
EYW	TW B3	Taxiway	225	3,864	AC	11/1/2021
EYW	TW B4	Taxiway	230	3,864	AC	11/1/2021
EYW	TW B5	Taxiway	235	7,125	AC	11/1/2021
EYW	TW B6	Taxiway	240	6,842	AAC	11/1/2021
EYW	TW B7	Taxiway	245	6,819	AC	11/1/2021
EYW	TW B8	Taxiway	250	6,972	AC	11/1/2021
EYW	TW B9	Taxiway	255	5,828	AC	11/1/2021
EYW	TW B9	Taxiway	257	3,071	PCC	10/1/2018
EYW	AP GA	Apron	4130	29,979	AAC	1/1/2003
EYW	AP GA	Apron	4145	144,422	AAC	1/1/2003
EYW	AP GA	Apron	4150	18,084	AC	1/1/2003
EYW	AP GA	Apron	4155	48,170	AAC	1/1/2005
EYW	AP GA	Apron	4205	75,458	AC	1/1/2003
EYW	AP GA	Apron	4215	58,338	AC	1/1/2006
EYW	AP GA	Apron	4220	13,765	AC	1/1/2005
EYW	AP GA	Apron	4225	78,577	AAC	11/1/2021
EYW	AP TERM	Apron	4105	34,810	AAC	1/1/2003
EYW	AP TERM	Apron	4160	336,953	PCC	10/1/2018





**Chapter 4: Airfield Pavement Condition Analysis** 

### Chapter 4 – Airfield Pavement Condition Analysis

The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for designand/or project-level determination of pavement rehabilitation needs.

#### 4.1 Airfield Pavement Condition Index

#### 4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 75% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 7% of inspected pavements are in Fair condition and the remaining 18% of inspected pavements are in Poor or worse condition.

Figure 4.1.1: Current Condition - Overall Network



#### 4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(d)** summarize branch-level pavement conditions according to the most recent PCI assessment results.




Figure 4.1.2 (a): Current Condition Summary - Branch-Level









Figure 4.1.2 (c): Current Condition - Taxiway





#### Statewide Airfield Pavement Management Program



Figure 4.1.2 (d): Current Condition - Apron



**Table 4.1.2** details the branch-level condition for each airfield pavement branch.

Table 4.1.2: Current Condition Summary - Branch-Level

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
RW 9-27	Runway	3	510,600	86	Good
RW 9-27	Runway	3	510,600	86	Good
RW 9-27	Runway	3	510,600	86	Good
TW A	Taxiway	3	236,764	99	Good
TW A	Taxiway	3	236,764	99	Good
TW A	Taxiway	3	236,764	99	Good
TW A1	Taxiway	2	39,917	63	Fair
TW A1	Taxiway	2	39,917	63	Fair
TW A2	Taxiway	2	24,979	100	Good
TW A2	Taxiway	2	24,979	100	Good
TW A3	Taxiway	2	34,462	100	Good
TW A3	Taxiway	2	34,462	100	Good
TW A4	Taxiway	2	18,392	100	Good
TW A4	Taxiway	2	18,392	100	Good
TW B1	Taxiway	1	7,765	100	Good
TW B10	Taxiway	1	8,893	100	Good
TW B11	Taxiway	2	8,816	97	Good
TW B11	Taxiway	2	8,816	97	Good
TW B12	Taxiway	1	11,359	100	Good
TW B2	Taxiway	1	3,779	100	Good
TW B3	Taxiway	1	3,864	100	Good
TW B4	Taxiway	1	3,864	100	Good
TW B5	Taxiway	1	7,125	100	Good
TW B6	Taxiway	1	6,842	100	Good
TW B7	Taxiway	1	6,819	100	Good
TW B8	Taxiway	1	6,972	100	Good
TW B9	Taxiway	2	8,899	91	Good
TW B9	Taxiway	2	8,899	91	Good
AP GA	Apron	8	466,793	57	Fair
AP GA	Apron	8	466,793	57	Fair
AP GA	Apron	8	466,793	57	Fair
AP GA	Apron	8	466,793	57	Fair
AP GA	Apron	8	466,793	57	Fair
AP GA	Apron	8	466,793	57	Fair
AP GA	Apron	8	466,793	57	Fair
AP GA	Apron	8	466,793	57	Fair
AP TERM	Apron	2	371,763	93	Good
AP TERM	Apron	2	371,763	93	Good



#### 4.1.3 Section-Level Analysis

**Table 4.1.3** provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.

Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.




Table 4.1.3: Latest Pavement Condition Index Summary - Section-Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
EYW	RW 9-27	Runway	6105	480,000	AAC	86	Good	73	0	27	20	96
EYW	RW 9-27	Runway	6115	12,600	AC	81	Satisfactory	100	0	0	1	2
EYW	RW 9-27	Runway	6120	18,000	PCC	100	Good	40	21	39	2	5
EYW	TW A	Taxiway	100	167,850	AAC	100	Good	0	0	0	0	0
EYW	TW A	Taxiway	105	11,729	AAC	73	Satisfactory	100	0	0	1	3
EYW	TW A	Taxiway	110	57,185	AAC	100	Good	0	0	0	0	0
EYW	TW A1	Taxiway	130	19,096	AAC	90	Good	100	0	0	1	4
EYW	TW A1	Taxiway	135	20,821	AAC	39	Very Poor	49	40	11	2	5
EYW	TW A2	Taxiway	120	8,949	AAC	100	Good	0	0	0	0	0
EYW	TW A2	Taxiway	125	16,030	AAC	100	Good	0	0	0	0	0
EYW	TW A3	Taxiway	140	9,075	AAC	100	Good	0	0	0	0	0
EYW	TW A3	Taxiway	145	25,387	AAC	100	Good	0	0	0	0	0
EYW	TW A4	Taxiway	160	6,462	AAC	100	Good	0	0	0	0	0
EYW	TW A4	Taxiway	165	11,930	AAC	100	Good	0	0	0	0	0
EYW	TW B1	Taxiway	215	7,765	AC	100	Good	0	0	0	0	0
EYW	TW B10	Taxiway	260	8,893	AC	100	Good	0	0	0	0	0
EYW	TW B11	Taxiway	265	5,749	AC	100	Good	0	0	0	0	0
EYW	TW B11	Taxiway	267	3,067	PCC	91	Good	79	0	21	1	1
EYW	TW B12	Taxiway	270	11,359	AC	100	Good	0	0	0	0	0
EYW	TW B2	Taxiway	220	3,779	AC	100	Good	0	0	0	0	0
EYW	TW B3	Taxiway	225	3,864	AC	100	Good	0	0	0	0	0
EYW	TW B4	Taxiway	230	3,864	AC	100	Good	0	0	0	0	0
EYW	TW B5	Taxiway	235	7,125	AC	100	Good	0	0	0	0	0
EYW	TW B6	Taxiway	240	6,842	AAC	100	Good	0	0	0	0	0
EYW	TW B7	Taxiway	245	6,819	AC	100	Good	0	0	0	0	0
EYW	TW B8	Taxiway	250	6,972	AC	100	Good	0	0	0	0	0
EYW	TW B9	Taxiway	255	5,828	AC	100	Good	0	0	0	0	0
EYW	TW B9	Taxiway	257	3,071	PCC	73	Satisfactory	0	0	100	1	1
EYW	AP GA	Apron	4130	29,979	AAC	39	Very Poor	91	0	9	1	7
EYW	AP GA	Apron	4145	144,422	AAC	41	Poor	81	0	19	3	30
EYW	AP GA	Apron	4150	18,084	AC	31	Very Poor	59	27	14	1	4
EYW	AP GA	Apron	4155	48,170	AAC	52	Poor	43	32	25	2	11
EYW	AP GA	Apron	4205	75,458	AC	61	Fair	89	0	11	3	18
EYW	AP GA	Apron	4215	58,338	AC	57	Fair	61	16	23	2	11
EYW	AP GA	Apron	4220	13,765	AC	52	Poor	72	0	28	1	3
EYW	AP GA	Apron	4225	78,577	AAC	100	Good	0	0	0	0	0
EYW	AP TERM	Apron	4105	34,810	AAC	40	Very Poor	79	0	21	1	7
EYW	AP TERM	Apron	4160	336,953	PCC	98	Good	52	0	48	8	71

<sup>\*</sup>Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.







RW 13-31 TYPICAL RUNWAY BRANCH ID

PCI 86-100 Good PCI 71-85 Satisfactory PCI 56-70 Fair PCI 41-55 Poor PCI 26-40 Very Poor PCI 11-25 Serious PCI 0-10 Failed

TYPICAL TAXIWAY BRANCH ID — TYPICAL APRON BRANCH ID





#### **4.2 Summary of Pavement Condition Evaluation Results**

#### 4.2.1 Network-Level Observations

The PCI assessment for Key West International Airport (EYW) was performed in October 2022. The overall area-weighted average PCI value of the network was 82, representing a condition rating of Satisfactory. A portion of the airfield pavement was not inspected due to recent construction in 2021. These areas include portions of the GA Apron, Taxiway A, Taxiway A2, Taxiway A3, Taxiway A4, and associated taxiway connectors.

Based on the FAA 5010 Report as of 11/13/2022, the Airport has reported 66,550 operations for 12 months ending 12/31/2021.

#### 4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

#### **Runways**

#### RW 9-27

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
RW 9-27	RUNWAY	3	510,600	86	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 98% Good (86-100 PCI), 2% Satisfactory (71-85 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6105	AAC	480,000	86	Good
6115	AC	12,600	81	Satisfactory
6120	PCC	18,000	100	Good




RW 9-27 consists of 2 flexible and 1 rigid pavement sections, totaling 510,600 sf. The last major construction date for the branch was 2018, resulting in an area-weighted average age at inspection of 5 years old. Overall, RW 9-27 is in Good condition with an area-weighted average PCI of 86.

#### **Taxiways**

#### TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	3	236,764	99	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 95% Good (86-100 PCI), 5% Satisfactory (71-85 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
100	AAC	167,850	100	Good
105	AAC	11,729	73	Satisfactory
110	AAC	57,185	100	Good

TW A consists of 3 flexible pavement sections, totaling 236,764 sf. The last major construction dates range from 2003 to 2021, resulting in an area-weighted average age at inspection of 1 years old. Overall, TW A is in Good condition with an area-weighted average PCI of 99.

#### **TW A1**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW A1	TAXIWAY	2	39,917	63	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 48% Good (86-100 PCI), 52% Very Poor (26-40 PCI).






Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
130	AAC	19,096	90	Good
135	AAC	20,821	39	Very Poor

TW A1 consists of 2 flexible pavement sections, totaling 39,917 sf. The last major construction dates range from 2003 to 2018, resulting in an area-weighted average age at inspection of 12 years old. Overall, TW A1 is in Fair condition with an area-weighted average PCI of 63.

#### **TW A2**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW A2	TAXIWAY	2	24,979	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
120	AAC	8,949	100	Good
125	AAC	16,030	100	Good

TW A2 consists of 2 flexible pavement sections, totaling 24,979 sf. The last major construction date for the branch was 2021. Overall, TW A2 is in Good condition with an area-weighted average PCI of 100.


#### TW A3

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW A3	TAXIWAY	2	34,462	100	Good



Statewide Airfield Pavement Management Program

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
140	AAC	9,075	100	Good
145	AAC	25,387	100	Good

TW A3 consists of 2 flexible pavement sections, totaling 34,462 sf. The last major construction date for the branch was 2021. Overall, TW A3 is in Good condition with an area-weighted average PCI of 100.

#### **TW A4**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW A4	TAXIWAY	2	18,392	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
160	AAC	6,462	100	Good
165	AAC	11,930	100	Good

TW A4 consists of 2 flexible pavement sections, totaling 18,392 sf. The last major construction date for the branch was 2021. Overall, TW A4 is in Good condition with an area-weighted average PCI of 100.



Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B1	TAXIWAY	1	7,765	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
215	AC	7,765	100	Good

TW B1 consists of 1 flexible pavement section, totaling 7,765 sf. The last major construction date for the branch was 2021. Overall, TW B1 is in Good condition with an area-weighted average PCI of 100.

#### TW B10

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B10	TAXIWAY	1	8,893	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
260	AC	8,893	100	Good

TW B10 consists of 1 flexible pavement section, totaling 8,893 sf. The last major construction date for the branch was 2021. Overall, TW B10 is in Good condition with an area-weighted average PCI of 100.



Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B11	TAXIWAY	2	8,816	97	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
265	AC	5,749	100	Good
267	PCC	3,067	91	Good

TW B11 consists of 1 flexible and 1 rigid pavement sections, totaling 8,816 sf. The last major construction dates range from 2018 to 2021, resulting in an area-weighted average age at inspection of 1 years old. Overall, TW B11 is in Good condition with an area-weighted average PCI of 97.

#### **TW B12**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B12	TAXIWAY	1	11,359	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
270	AC	11,359	100	Good

TW B12 consists of 1 flexible pavement section, totaling 11,359 sf. The last major construction date for the branch was 2021. Overall, TW B12 is in Good condition with an area-weighted average PCI of 100.



Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B2	TAXIWAY	1	3,779	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
220	AC	3,779	100	Good

TW B2 consists of 1 flexible pavement section, totaling 3,779 sf. The last major construction date for the branch was 2021. Overall, TW B2 is in Good condition with an area-weighted average PCI of 100.

#### **TW B3**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B3	TAXIWAY	1	3,864	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
225	AC	3,864	100	Good

TW B3 consists of 1 flexible pavement section, totaling 3,864 sf. The last major construction date for the branch was 2021. Overall, TW B3 is in Good condition with an area-weighted average PCI of 100.



Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B4	TAXIWAY	1	3,864	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
230	AC	3,864	100	Good

TW B4 consists of 1 flexible pavement section, totaling 3,864 sf. The last major construction date for the branch was 2021. Overall, TW B4 is in Good condition with an area-weighted average PCI of 100.

#### **TW B5**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B5	TAXIWAY	1	7,125	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
235	AC	7,125	100	Good

TW B5 consists of 1 flexible pavement section, totaling 7,125 sf. The last major construction date for the branch was 2021. Overall, TW B5 is in Good condition with an area-weighted average PCI of 100.



Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B6	TAXIWAY	1	6,842	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
240	AAC	6,842	100	Good

TW B6 consists of 1 flexible pavement section, totaling 6,842 sf. The last major construction date for the branch was 2021. Overall, TW B6 is in Good condition with an area-weighted average PCI of 100.

#### **TW B7**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B7	TAXIWAY	1	6,819	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
245	AC	6,819	100	Good

TW B7 consists of 1 flexible pavement section, totaling 6,819 sf. The last major construction date for the branch was 2021. Overall, TW B7 is in Good condition with an area-weighted average PCI of 100.



Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
TW B8	TAXIWAY	1	6,972	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
250	AC	6,972	100	Good

TW B8 consists of 1 flexible pavement section, totaling 6,972 sf. The last major construction date for the branch was 2021. Overall, TW B8 is in Good condition with an area-weighted average PCI of 100.

#### **TW B9**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating	
TW B9	TAXIWAY	2	8,899	91	Good	

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 65% Good (86-100 PCI), 35% Satisfactory (71-85 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating	
255	AC	5,828	100	Good	
257	PCC	3,071	73	Satisfactory	

TW B9 consists of 1 flexible and 1 rigid pavement sections, totaling 8,899 sf. The last major construction dates range from 2018 to 2021, resulting in an area-weighted average age at inspection of 1 years old. Overall, TW B9 is in Good condition with an area-weighted average PCI of 91.



#### **Aprons**

#### AP GA

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
AP GA	APRON	8	466,793	57	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 17% Good (86-100 PCI), 29% Fair (56-70 PCI), 44% Poor (41-55 PCI), 10% Very Poor (26-40 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4130	AAC	29,979	39	Very Poor
4145	AAC	144,422	41	Poor
4150	AC	18,084	31	Very Poor
4155	AAC	48,170	52	Poor
4205	AC	75,458 61		Fair
4215	AC	58,338	57	Fair
4220	AC	13,765 52		Poor
4225	AAC		100	Good


AP GA consists of 8 flexible pavement sections, totaling 466,793 sf. The last major construction dates range from 2003 to 2021, resulting in an area-weighted average age at inspection of 16 years old. Overall, AP GA is in Fair condition with an area-weighted average PCI of 57.



#### **AP TERM**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area- Weighted Avg PCI	Branch Condition Rating
AP TERM	APRON	2	371,763	93	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 91% Good (86-100 PCI), 9% Very Poor (26-40 PCI).



Section ID	Surface Type	Section Area (SF)	PGI	
4105	AAC	34,810	40	Very Poor
4160	PCC	336,953	98	Good

AP TERM consists of 1 flexible and 1 rigid pavement sections, totaling 371,763 sf. The last major construction dates range from 2003 to 2018, resulting in an area-weighted average age at inspection of 5 years old. Overall, AP TERM is in Good condition with an area-weighted average PCI of 93.





# Chapter 5: SAPMP Customization

#### **Chapter 5 – SAPMP Customization**

Once the PAVER<sup>TM</sup> database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

#### 5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- The "Network" field identifies the airport being analyzed;
- The "Airport Classification" field classifies the Airport according to the type and volume of aircraft traffic;
  - o "GA" for General Aviation, community airports
  - "RL" for Regional Relievers
  - "PR" for Primary/Commercial airports
- The "District" field identifies the FDOT District to which the Airport belongs;
- The "FAA ADO Area" is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists):
- The "Inspection Phase" denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- The "CFASPP Center" identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

#### **5.2 Pavement Condition Forecasts**

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.



#### 5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans. Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.

#### 5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into "groups" or "families" according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

#### 5.2.3 Branch-Level Pavement Condition Forecast

**Figure 5.2.3** depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.




Figure 5.2.3: Forecasted Branch-Level Pavement Performance



#### 5.2.4 Section-Level Pavement Condition Forecast

**Table 5.2.4** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

Table 5.2.4: Forecasted PCI Values 2023-2032 - Section-Level

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
EYW	RW 9-27	6105	86	85	83	81	79	77	75	73	71	69	67
EYW	RW 9-27	6115	81	80	78	77	75	74	72	71	69	68	66
EYW	RW 9-27	6120	100	99	98	97	96	95	94	94	93	92	92
EYW	TW A	100	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A	105	73	72	70	68	67	65	64	62	61	60	59
EYW	TW A	110	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A1	130	90	88	86	84	81	79	77	75	73	71	70
EYW	TW A1	135	39	38	36	34	32	29	26	23	20	16	11
EYW	TW A2	120	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A2	125	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A3	140	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A3	145	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A4	160	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A4	165	100	96	93	91	89	86	84	82	80	77	75
EYW	TW B1	215	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B10	260	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B11	265	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B11	267	91	91	90	90	89	89	89	88	88	88	87
EYW	TW B12	270	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B2	220	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B3	225	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B4	230	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B5	235	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B6	240	100	96	93	91	89	86	84	82	80	77	75
EYW	TW B7	245	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B8	250	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B9	255	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B9	257	73	72	71	69	68	66	65	63	61	59	57
EYW	AP GA	4130	39	38	36	34	32	30	28	25	23	20	17
EYW	AP GA	4145	41	40	38	36	34	32	30	28	26	23	21
EYW	AP GA	4150	31	30	28	26	25	23	21	20	18	16	15
EYW	AP GA	4155	52	51	50	48	47	45	44	42	40	39	37
EYW	AP GA	4205	61	60	58	56	55	53	51	50	48	46	45
EYW	AP GA	4215	57	56	54	52	51	49	47	46	44	42	41
EYW	AP GA	4220	52	51	49	47	46	44	42	41	39	37	36
EYW	AP GA	4225	100	95	92	89	86	84	81	79	77	75	73
EYW	AP TERM	4105	40	39	37	35	33	31	29	27	24	22	19
EYW	AP TERM	4160	98	97	96	95	94	93	92	91	90	89	88



#### 5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.




Figure 5.3 (a): Pavement Life and the Effect of Treatments

FAA Eligibilty Thresholds: ->70: Routine Maintenance 55-70: Rehabilitation Eligible <-55: Reconstruction Eligible

\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.

Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will



integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects

Airfield Pavement Project Type	PCI Requirement		
Reconstruction	PCI < 55 (Poor)		
Rehabilitation	PCI < 70 (Fair)		
Maintenance	N/A		

<sup>\*</sup>Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

Table 5.3 (b): Critical PCI Values by Branch Use

Runway	Taxiway	Apron
70	70	70

**Figures 5.3 (b)** and **5.3 (c)** depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, PCI < Critical PCI





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, PCI ≥ Critical PCI



#### 5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 "Airport Foreign Object Debris (FOD) Management" provides additional guidance for developing and managing an airport FOD program.

#### 5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety ("stopgap") measure. The two (2) types of localized maintenance are described below in further detail.

- Localized Preventive Maintenance and Repair
  - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- \( \) Localized Stopgap/Safety Maintenance and Repair
  - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.



#### 5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

#### **AC Crack Sealing**

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

#### **AC Full-Depth Patching**

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

#### **AC Partial-Depth AC Patching**

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

#### **Grinding**

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

#### **Monitor Pavement**

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.



#### **PCC Crack Sealing**

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

#### PCC Full-Depth Patching

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

#### **PCC Joint Seal**

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

#### **PCC Partial-Depth Patching**

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

#### **PCC Slab Replacement**

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

#### Surface Seal

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.



#### 5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

**Tables 5.4.3 (a)** and **(b)** display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs - Asphalt Concrete

Localized Work Type	Primary/C	Commercial Costs	Work Type Unit
AC Crack Sealing	\$	4.00	LF
AC Full-Depth Patching	\$	18.75	SF
AC Partial-Depth Patching	\$	6.50	SF
Surface Seal	\$	0.75	SF

Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs - Portland Cement Concrete

Localized Work Type	Primary/Commercial Costs		Work Type Unit	
Grinding	\$	2.00	SF	
PCC Crack Sealing	\$	7.00	LF	
PCC Joint Seal	\$	4.25	LF	
PCC Full-Depth Patching	\$	75.00	SF	
PCC Partial-Depth Patching	\$	169.00	SF	
PCC Slab Replacement	\$	51.50	SF	

<sup>\*</sup>PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.

#### 5.4.4 Localized Maintenance and Repair Policy

**Table 5.4.4** and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.



## **Airport Pavement Evaluation Report** Statewide Airfield Pavement Management Program

Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
41	Low	Alligator Cracking	Monitor Pavement	Monitor Pavement
41	Medium	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
41	High	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
42	N/A	Bleeding	Monitor Pavement	Monitor Pavement
43	Low	Block Cracking	Monitor Pavement	Monitor Pavement
43	Medium	Block Cracking	AC Crack Sealing	Monitor Pavement
43	High	Block Cracking	AC Crack Sealing	AC Crack Sealing
44	Low	Corrugation	Monitor Pavement	Monitor Pavement
44	Medium	Corrugation	AC Full Depth Patching	Monitor Pavement
44	High	Corrugation	AC Full Depth Patching	AC Full Depth Patching
45	Low	Depression	Monitor Pavement	Monitor Pavement
45	Medium	Depression	AC Full Depth Patching	Monitor Pavement
45	High	Depression	AC Full Depth Patching	AC Full Depth Patching
46	N/A	Jet Blast	Monitor Pavement	Monitor Pavement
47	Low	Jt. Reflective Cracking	Monitor Pavement	Monitor Pavement
47	Medium	Jt. Reflective Cracking	AC Crack Sealing	Monitor Pavement
47	High	Jt. Reflective Cracking	AC Full Depth Patching	AC Full Depth Patching
48	Low	L&T Cracking	Monitor Pavement	Monitor Pavement
48	Medium	L&T Cracking	AC Crack Sealing	Monitor Pavement
48	High	L&T Cracking	AC Full Depth Patching	AC Full Depth Patching
49	N/A	Oil Spillage	Monitor Pavement	Monitor Pavement
50	Low	Patching	Monitor Pavement	Monitor Pavement
50	Medium	Patching	AC Full Depth Patching	Monitor Pavement
50	High	Patching	AC Full Depth Patching	AC Full Depth Patching
51	N/A	Polished Aggregate	Monitor Pavement	Monitor Pavement
52	Low	Raveling	Surface Seal	Monitor Pavement
52	Medium	Raveling	Surface Seal	Monitor Pavement
52	High	Raveling	AC Partial Depth Patching	AC Partial Depth Patching
53	Low	Rutting	Monitor Pavement	Monitor Pavement
53	Medium	Rutting	AC Full Depth Patching	Monitor Pavement
53	High	Rutting	AC Full Depth Patching	AC Full Depth Patching
54	Low	Shoving	Monitor Pavement	Monitor Pavement
54	Medium	Shoving	AC Partial Depth Patching	Monitor Pavement
54	High	Shoving	AC Full Depth Patching	AC Full Depth Patching
55	N/A	Slippage Cracking	AC Full Depth Patching	AC Full Depth Patching
56	Low	Swelling	Monitor Pavement	Monitor Pavement
56	Medium	Swelling	AC Full Depth Patching	Monitor Pavement
56	High	Swelling	AC Full Depth Patching	AC Full Depth Patching

## **Airport Pavement Evaluation Report** Statewide Airfield Pavement Management Program

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
57	Low	Weathering	Monitor Pavement	Monitor Pavement
57	Medium	Weathering	Surface Seal	Monitor Pavement
57	High	Weathering	AC Partial Depth Patching	Surface Seal

Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
61	Low	Blow-up	PCC Full Depth Patching	Monitor Pavement
61	Medium	Blow-up	PCC Full Depth Patching	PCC Full Depth Patching
61	High	Blow-up	PCC Slab Replacement	PCC Slab Replacement
62	Low	Corner Break	Monitor Pavement	Monitor Pavement
62	Medium	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
62	High	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
63	Low	Linear Cracking	Monitor Pavement	Monitor Pavement
63	Medium	Linear Cracking	PCC Crack Sealing	PCC Crack Sealing
63	High	Linear Cracking	PCC Full Depth Patching	PCC Crack Sealing
64	Low	Durability Cracking	Monitor Pavement	Monitor Pavement
64	Medium	Durability Cracking	PCC Full Depth Patching	PCC Full Depth Patching
64	High	Durability Cracking	PCC Slab Replacement	PCC Slab Replacement
65	Low	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	Medium	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	High	Jt. Seal Damage	PCC Joint Seal	PCC Joint Seal
66	Low	Small Patch	Monitor Pavement	Monitor Pavement
66	Medium	Small Patch	PCC Partial Depth Patching	Monitor Pavement
66	High	Small Patch	PCC Partial Depth Patching	PCC Partial Depth Patching
67	Low	Large Patch	Monitor Pavement	Monitor Pavement
67	Medium	Large Patch	PCC Full Depth Patching	Monitor Pavement
67	High	Large Patch	PCC Full Depth Patching	PCC Full Depth Patching
68	N/A	Popouts	Monitor Pavement	Monitor Pavement
69	N/A	Pumping	Monitor Pavement	Monitor Pavement
70	Low	Scaling	Monitor Pavement	Monitor Pavement
70	Medium	Scaling	PCC Slab Replacement	Monitor Pavement
70	High	Scaling	PCC Slab Replacement	PCC Slab Replacement
71	Low	Faulting	Monitor Pavement	Monitor Pavement
71	Medium	Faulting	Grinding	Monitor Pavement
71	High	Faulting	PCC Slab Replacement	PCC Slab Replacement
72	Low	Shattered Slab	PCC Crack Sealing	Monitor Pavement
72	Medium	Shattered Slab	PCC Slab Replacement	PCC Crack Sealing
72	High	Shattered Slab	PCC Slab Replacement	PCC Slab Replacement
73	N/A	Shrinkage Cracking	Monitor Pavement	Monitor Pavement

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
74	Low	Joint Spall	Monitor Pavement	Monitor Pavement
74	Medium	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
74	High	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	Low	Corner Spall	Monitor Pavement	Monitor Pavement
75	Medium	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	High	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
76	Low	ASR	Monitor Pavement	Monitor Pavement
76	Medium	ASR	PCC Slab Replacement	PCC Slab Replacement
76	High	ASR	PCC Slab Replacement	PCC Slab Replacement

### 5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

### 5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average Primary/Commercial Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.



Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation

Rehabilitation Type	Primary/Commercial Pavement Section			
AC Reconstruction				
	Pavement Removal			
	Unclassified Excavation			
	Subgrade Stabilization (12")			
Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.	Limerock Base Course (8")			
pavement section and construction of a new section.	Prime Coat			
PCI < 55	Tack Coat			
	P-403 Stabilized Base Course (5")			
	P-401 Surface Course (4")			
	Excludes any paved shoulder features			
AC Rehabilitation				
	15% AC Reconstruction			
Combination of country in a compact milling and replacement available with	Mill and Overlay			
Combination of asphalt pavement milling and replacement overlay with 15% of the areas subject to full-depth reconstruction.	AC Milling (4")			
	Tack Coat			
PCI = 55 to 70	P-401 Surface Course (4")			
	Excludes any paved shoulder features			
PCC Reconstruction				
	Pavement Removal			
	Unclassified Excavation			
	Subgrade Stabilization (12")			
Full-depth rigid pavement section reconstruction.	Limerock Base Course (6")			
	Prime Coat			
PCI < 55	Tack Coat			
	P-403 Stabilized Base Course (5")			
	P-501 PCC Pavement (17")			
	PCC Joint Seal			
PCC Rehabilitation				
Rehabilitation of PCC pavement with a combination of crack sealing, joint	15% Slab Replacement			
seal replacement, limited patching, and replacement of 15% of slab panels.	Joint and Crack Seal			
PCI = 55 to 70	Limited Patching			



The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.

#### Reconstruction (AC or PCC)

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

#### **AC Rehabilitation**

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

#### **PCC** Rehabilitation

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.



#### 5.5.2 Major Rehabilitation Planning-Level Unit Costs


Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.

Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.

Table 5.5.2: PR Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Asphalt Concrete Cost per SF	Portland Cement Concrete Cost Per SF
Rehabilitation	55 to 70	\$14.00	\$30.50
Reconstruction	0 to 55	\$30.50	\$60.00





**Planning and Budget Scenario Analysis** 

# Chapter 6 – M&R Planning and Budget Scenario Analysis

### 6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

**Table 6.1 (a)** provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (a): Year 1 Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 123,940
Stopgap	\$ 19,600
Planning-Level Localized M&R Needs =	\$ 143,540

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

**Table 6.1 (b)** summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	anning erial Cost
	Surface Seal	1,962	SF	\$ 1,490
	AC Full-Depth Patching	252	SF	\$ 4,730
Localized Preventive Maintenance	PCC Joint Seal	23,699	LF	\$ 100,730
	PCC Partial-Depth Patching	70	SF	\$ 11,820
	PCC Full-Depth Patching	69	SF	\$ 5,170
Localized Stopgap Maintenance	AC Full-Depth Patching	1,044	SF	\$ 19,600

Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary

**Table 6.1 (c)** provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved "End Condition" PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
EYW	RW 9-27	6105	480,000	86	86	\$ 5,630
EYW	RW 9-27	6115	12,600	81	90	\$ 170
EYW	RW 9-27	6120	18,000	100	100	\$ -
EYW	TW A	100	167,850	100	100	\$ -
EYW	TW A	105	11,729	73	76	\$ 420
EYW	TW A	110	57,185	100	100	\$ -
EYW	TW A1	130	19,096	90	90	\$ -
EYW	TW A1	135	20,821	39	39	\$ -
EYW	TW A2	120	8,949	100	100	\$ -
EYW	TW A2	125	16,030	100	100	\$ -
EYW	TW A3	140	9,075	100	100	\$ -
EYW	TW A3	145	25,387	100	100	\$ -
EYW	TW A4	160	6,462	100	100	\$ -
EYW	TW A4	165	11,930	100	100	\$ -
EYW	TW B1	215	7,765	100	100	\$ -
EYW	TW B10	260	8,893	100	100	\$ -
EYW	TW B11	265	5,749	100	100	\$ -
EYW	TW B11	267	3,067	91	98	\$ 1,310
EYW	TW B12	270	11,359	100	100	\$ -
EYW	TW B2	220	3,779	100	100	\$ -
EYW	TW B3	225	3,864	100	100	\$ -
EYW	TW B4	230	3,864	100	100	\$ -
EYW	TW B5	235	7,125	100	100	\$ -
EYW	TW B6	240	6,842	100	100	\$ -
EYW	TW B7	245	6,819	100	100	\$ -
EYW	TW B8	250	6,972	100	100	\$ -
EYW	TW B9	255	5,828	100	100	\$ -
EYW	TW B9	257	3,071	73	94	\$ 7,900



Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
EYW	AP GA	4130	29,979	39	42	\$ 2,530
EYW	AP GA	4145	144,422	41	41	\$ -
EYW	AP GA	4150	18,084	31	44	\$ 9,350
EYW	AP GA	4155	48,170	52	53	\$ 7,700
EYW	AP GA	4205	75,458	61	61	\$ -
EYW	AP GA	4215	58,338	57	57	\$ -
EYW	AP GA	4220	13,765	52	52	\$ -
EYW	AP GA	4225	78,577	100	100	\$ -
EYW	AP TERM	4105	34,810	40	40	\$ -
EYW	AP TERM	4160	336,953	98	99	\$ 108,500

### **6.2 Major Rehabilitation Needs**

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b)** and **(c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

#### 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- An estimation of current pavement condition;
- Major pavement rehabilitation needs based on condition and policies; and
- Planning-level cost estimates for the major rehabilitation needs.



## Statewide Airfield Pavement Management Program


**Table 6.2.1 (a)** summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.

Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	nning Cost Stimate
2023	EYW	TW A1	135	AAC	20,821	38	AC Reconstruction	\$ 636,000
2023	EYW	AP GA	4130	AAC	29,979	38	AC Reconstruction	\$ 915,000
2023	EYW	AP GA	4145	AAC	144,422	40	AC Reconstruction	\$ 4,405,000
2023	EYW	AP GA	4150	AC	18,084	30	AC Reconstruction	\$ 552,000
2023	EYW	AP GA	4155	AAC	48,170	51	AC Reconstruction	\$ 1,470,000
2023	EYW	AP GA	4205	AC	75,458	60	AC Rehabilitation	\$ 1,057,000
2023	EYW	AP GA	4215	AC	58,338	56	AC Rehabilitation	\$ 817,000
2023	EYW	AP GA	4220	AC	13,765	51	AC Reconstruction	\$ 420,000
2023	EYW	AP TERM	4105	AAC	34,810	39	AC Reconstruction	\$ 1,062,000
2024	EYW	TW A	105	AAC	11,729	70	AC Rehabilitation	\$ 173,000
2025	EYW	TW B9	257	PCC	3,071	69	PCC Rehabilitation	\$ 104,000
2030	EYW	RW 9-27	6115	AC	12,600	69	AC Rehabilitation	\$ 249,000
2031	EYW	RW 9-27	6105	AAC	480,000	69	AC Rehabilitation	\$ 9,929,000
2032	EYW	TW A1	130	AAC	19,096	70	AC Rehabilitation	\$ 415,000


**Figure 6.2.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year











RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



**Chapter 7: Conclusion** 

## **Chapter 7 – Conclusion**

#### 7.1 Recommendations

#### 7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

#### 7.1.3 Major Rehabilitation

**Chapter 6** also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

#### 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in Section 6.1;
- Further refine and implement the identified 10-year major rehabilitation needs provided in Section 6.2;
- Maintain detailed records on pavement maintenance, construction, and inspection; and
- Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



## 7.2 Supporting Documents

#### Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

#### Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

#### Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

#### Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVER<sup>TM</sup> software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

#### Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

#### Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.



#### 7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

#### 7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.





**Pavement Analysis** 

Table A.1: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
EYW	RW 9-27	Runway	6105	480,000	AAC	4/1/2018
EYW	RW 9-27	Runway	6115	12,600	AC	1/1/2018
EYW	RW 9-27	Runway	6120	18,000	PCC	1/1/2018
EYW	TW A	Taxiway	100	167,850	AAC	11/1/2021
EYW	TW A	Taxiway	105	11,729	AAC	1/1/2003
EYW	TW A	Taxiway	110	57,185	AAC	11/1/2021
EYW	TW A1	Taxiway	130	19,096	AAC	4/1/2018
EYW	TW A1	Taxiway	135	20,821	AAC	1/1/2003
EYW	TW A2	Taxiway	120	8,949	AAC	11/1/2021
EYW	TW A2	Taxiway	125	16,030	AAC	11/1/2021
EYW	TW A3	Taxiway	140	9,075	AAC	11/1/2021
EYW	TW A3	Taxiway	145	25,387	AAC	11/1/2021
EYW	TW A4	Taxiway	160	6,462	AAC	11/1/2021
EYW	TW A4	Taxiway	165	11,930	AAC	11/1/2021
EYW	TW B1	Taxiway	215	7,765	AC	11/1/2021
EYW	TW B10	Taxiway	260	8,893	AC	11/1/2021
EYW	TW B11	Taxiway	265	5,749	AC	11/1/2021
EYW	TW B11	Taxiway	267	3,067	PCC	10/1/2018
EYW	TW B12	Taxiway	270	11,359	AC	11/1/2021
EYW	TW B2	Taxiway	220	3,779	AC	11/1/2021
EYW	TW B3	Taxiway	225	3,864	AC	11/1/2021
EYW	TW B4	Taxiway	230	3,864	AC	11/1/2021
EYW	TW B5	Taxiway	235	7,125	AC	11/1/2021
EYW	TW B6	Taxiway	240	6,842	AAC	11/1/2021
EYW	TW B7	Taxiway	245	6,819	AC	11/1/2021
EYW	TW B8	Taxiway	250	6,972	AC	11/1/2021
EYW	TW B9	Taxiway	255	5,828	AC	11/1/2021
EYW	TW B9	Taxiway	257	3,071	PCC	10/1/2018
EYW	AP GA	Apron	4130	29,979	AAC	1/1/2003
EYW	AP GA	Apron	4145	144,422	AAC	1/1/2003
EYW	AP GA	Apron	4150	18,084	AC	1/1/2003
EYW	AP GA	Apron	4155	48,170	AAC	1/1/2005
EYW	AP GA	Apron	4205	75,458	AC	1/1/2003
EYW	AP GA	Apron	4215	58,338	AC	1/1/2006
EYW	AP GA	Apron	4220	13,765	AC	1/1/2005
EYW	AP GA	Apron	4225	78,577	AAC	11/1/2021
EYW	AP TERM	Apron	4105	34,810	AAC	1/1/2003
EYW	AP TERM	Apron	4160	336,953	PCC	10/1/2018

Table A.2: Pavement Condition Index Summary (Current PCI Survey) - Section Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
EYW	RW 9-27	Runway	6105	480,000	86	Good
EYW	RW 9-27	Runway	6115	12,600	81	Satisfactory
EYW	RW 9-27	Runway	6120	18,000	100	Good
EYW	TW A	Taxiway	100	167,850	100	Good
EYW	TW A	Taxiway	105	11,729	73	Satisfactory
EYW	TW A	Taxiway	110	57,185	100	Good
EYW	TW A1	Taxiway	130	19,096	90	Good
EYW	TW A1	Taxiway	135	20,821	39	Very Poor
EYW	TW A2	Taxiway	120	8,949	100	Good
EYW	TW A2	Taxiway	125	16,030	100	Good
EYW	TW A3	Taxiway	140	9,075	100	Good
EYW	TW A3	Taxiway	145	25,387	100	Good
EYW	TW A4	Taxiway	160	6,462	100	Good
EYW	TW A4	Taxiway	165	11,930	100	Good
EYW	TW B1	Taxiway	215	7,765	100	Good
EYW	TW B10	Taxiway	260	8,893	100	Good
EYW	TW B11	Taxiway	265	5,749	100	Good
EYW	TW B11	Taxiway	267	3,067	91	Good
EYW	TW B12	Taxiway	270	11,359	100	Good
EYW	TW B2	Taxiway	220	3,779	100	Good
EYW	TW B3	Taxiway	225	3,864	100	Good
EYW	TW B4	Taxiway	230	3,864	100	Good
EYW	TW B5	Taxiway	235	7,125	100	Good
EYW	TW B6	Taxiway	240	6,842	100	Good
EYW	TW B7	Taxiway	245	6,819	100	Good
EYW	TW B8	Taxiway	250	6,972	100	Good
EYW	TW B9	Taxiway	255	5,828	100	Good
EYW	TW B9	Taxiway	257	3,071	73	Satisfactory
EYW	AP GA	Apron	4130	29,979	39	Very Poor
EYW	AP GA	Apron	4145	144,422	41	Poor
EYW	AP GA	Apron	4150	18,084	31	Very Poor
EYW	AP GA	Apron	4155	48,170	52	Poor
EYW	AP GA	Apron	4205	75,458	61	Fair
EYW	AP GA	Apron	4215	58,338	57	Fair
EYW	AP GA	Apron	4220	13,765	52	Poor
EYW	AP GA	Apron	4225	78,577	100	Good
EYW	AP TERM	Apron	4105	34,810	40	Very Poor
EYW	AP TERM	Apron	4160	336,953	98	Good

Table A.3: Forecasted PCI Values 2023-2032 - Section-Level

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
EYW	RW 9-27	6105	86	85	83	81	79	77	75	73	71	69	67
EYW	RW 9-27	6115	81	80	78	77	75	74	72	71	69	68	66
EYW	RW 9-27	6120	100	99	98	97	96	95	94	94	93	92	92
EYW	TW A	100	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A	105	73	72	70	68	67	65	64	62	61	60	59
EYW	TW A	110	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A1	130	90	88	86	84	81	79	77	75	73	71	70
EYW	TW A1	135	39	38	36	34	32	29	26	23	20	16	11
EYW	TW A2	120	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A2	125	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A3	140	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A3	145	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A4	160	100	96	93	91	89	86	84	82	80	77	75
EYW	TW A4	165	100	96	93	91	89	86	84	82	80	77	75
EYW	TW B1	215	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B10	260	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B11	265	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B11	267	91	91	90	90	89	89	89	88	88	88	87
EYW	TW B12	270	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B2	220	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B3	225	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B4	230	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B5	235	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B6	240	100	96	93	91	89	86	84	82	80	77	75
EYW	TW B7	245	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B8	250	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B9	255	100	96	94	92	90	88	86	84	83	81	79
EYW	TW B9	257	73	72	71	69	68	66	65	63	61	59	57
EYW	AP GA	4130	39	38	36	34	32	30	28	25	23	20	17
EYW	AP GA	4145	41	40	38	36	34	32	30	28	26	23	21
EYW	AP GA	4150	31	30	28	26	25	23	21	20	18	16	15
EYW	AP GA	4155	52	51	50	48	47	45	44	42	40	39	37
EYW	AP GA	4205	61	60	58	56	55	53	51	50	48	46	45
EYW	AP GA	4215	57	56	54	52	51	49	47	46	44	42	41
EYW	AP GA	4220	52	51	49	47	46	44	42	41	39	37	36
EYW	AP GA	4225	100	95	92	89	86	84	81	79	77	75	73
EYW	AP TERM	4105	40	39	37	35	33	31	29	27	24	22	19
EYW	AP TERM	4160	98	97	96	95	94	93	92	91	90	89	88

Page 1 of 9

Pavement Database: FDOT

Network:	KEY WES	ST INTERN Branch: AP GA			Section:	
<b>L.C.D.</b> 1/1/2	003 Us	se: APRON Rank: P I	Length: 300	.00 (Ft) Wid	dth: 100.0	0 (Ft) <b>True Area:</b> 29979.00000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50	<b>~</b>	
1/1/1989	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		1989 P-625 SEALCOAT
1/1/1980	IMPORT	BUILT	0.00	2.00		1980 2" P-401 8" P-211
	ED		•			
Network:	KEY WES	T INTERN <b>Branch:</b> AP GA	A GA Al	PRON	Section:	4145 Surface: AAC
L.C.D. 1/1/2	003 Us	se: APRON Rank: P I	Length: 430	.00 (Ft) Wie	dth: 338.0	0 (Ft) <b>True Area:</b> 144422.0000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2005	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1989	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		1989 P-625 SEALCOAT
1/1/1977	IMPORT		0.00	2.00		1977 2" P-401 6" P-211
2, 2, 2, 7, 7	ED		0.50	2.00	· .	
Network:	KEY WES	T INTERN Branch: AP GA	GA Al	PRON	Section:	4150 Surface:AC
<b>L.C.D.</b> 1/1/2	003 Us	se: APRON Rank: P	Length: 480	.00 (Ft) Wie	dth: 30.0	0 (Ft) <b>True Area:</b> 18084.00000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness	Major	Comments
	Couc			(in)	M&R	
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	M&R	
1/1/2003		New Construction - Initial	0.00	( )		
	NU-IN	New Construction - Initial  T INTERN Branch: AP GA		0.00		4155 Surface:AAC
	NU-IN KEY WES	T INTERN Branch: AP GA	A GA Al	0.00 PRON	Section:	4155 <b>Surface:</b> AAC 0 (Ft) <b>True Area:</b> 48170.00001 (SqFt
Network:	NU-IN KEY WES	T INTERN Branch: AP GA	A GA Al	0.00 PRON	Section:	
Network: L.C.D. 1/1/2	NU-IN KEY WES 005 Us Work Code	T INTERN Branch: AP GA	A GA Al	0.00 PRON .00 (Ft) Wid	Section: dth: 75.0 Major	0 (Ft) <b>True Area:</b> 48170.00001 (SqFt
Network: L.C.D. 1/1/2 Work Date	NU-IN KEY WES 005 Us Work Code	T INTERN Branch: AP GA se: APRON Rank: P I Work Description	A GA Al Length: 600	PRON .00 (Ft) Wid Thickness (in)	Section: dth: 75.0 Major M&R	0 (Ft) <b>True Area:</b> 48170.00001 (SqFt
Network: L.C.D. 1/1/2 Work Date 1/1/2005	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL	T INTERN Branch: AP GA se: APRON Rank: P I Work Description Mill and Overlay	GA Al Length: 600  Cost  0.00	PRON .00 (Ft) Wid Thickness (in) 0.00	Section: dth: 75.0 Major M&R	0 (Ft) <b>True Area:</b> 48170.00001 (SqFt
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL  OL-AS	TINTERN Branch: AP GA  se: APRON Rank: P I  Work Description  Mill and Overlay  Overlay - AC Structural  Surface Treatment - Seal Coat	GA Al Gength: 600  Cost  0.00 0.00	0.00 PRON .00 (Ft) Wid Thickness (in) 0.00 1.50	Section: dth: 75.0 Major M&R	0 (Ft) True Area: 48170.00001 (SqFt  Comments
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL  OL-AS  ST-SC	TINTERN Branch: AP GA  se: APRON Rank: P I  Work Description  Mill and Overlay  Overlay - AC Structural  Surface Treatment - Seal Coat	GA Al Length: 600  Cost  0.00 0.00 0.00	0.00 PRON .00 (Ft) Wid Thickness (in) 0.00 1.50 0.00	Section: dth: 75.0 Major M&R	Comments  1989 P-625 SEALCOAT
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989 1/1/1977	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED	TINTERN Branch: AP GA se: APRON Rank: P I Work Description Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00	0.00 PRON 00 (Ft) Wid Thickness (in) 0.00 1.50 0.00 2.00	Section: dth: 75.0 Major M&R  V	0 (Ft) True Area: 48170.00001 (SqFt  Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989 1/1/1977 Network:	NU-IN  KEY WES  005 Us  Work Code  ML-OVL OL-AS ST-SC IMPORT ED	T INTERN Branch: AP GA  se: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  ST INTERN Branch: AP GA	GA Al  cength: 600  Cost  0.00  0.00  0.00  0.00  GA Al	0.00 PRON .00 (Ft) Wid Thickness (in) 0.00 1.50 0.00 2.00 PRON	Section:  Section:  Major M&R   Section:	0 (Ft) True Area: 48170.00001 (SqFt  Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989 1/1/1977	NU-IN  KEY WES  005 Us  Work Code  ML-OVL OL-AS ST-SC IMPORT ED  KEY WES  003 Us	T INTERN Branch: AP GA  se: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  ST INTERN Branch: AP GA	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00	0.00 PRON .00 (Ft) Wid Thickness (in) 0.00 1.50 0.00 2.00 PRON .00 (Ft) Wid	Section: dth: 75.0 Major M&R  V  V  Section: dth: 70.0	0 (Ft) True Area: 48170.00001 (SqFt  Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211
Network: L.C.D. 1/1/2  Work Date  1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2  Work Date	NU-IN  KEY WES  005 Us  Work Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED  KEY WES  003 Us  Work Code	TINTERN Branch: AP GA se: APRON Rank: P  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  TINTERN Branch: AP GA se: APRON Rank: P  Work Description	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00  A GA Al Length: 1,325  Cost	0.00  PRON  .00 (Ft) Wid  Thickness (in)  0.00  1.50  0.00  2.00  PRON  .00 (Ft) Wid  Thickness (in)	Section:  Section:  Major M&R   Section:	Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2 Work Date 1/1/2015	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED  KEY WES  003 Us  Work  Code  ST-SC	RET INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  ST INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Surface Treatment - Seal Coat	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00  Cost  Cost  Cost  Cost  Cost  Cost	0.00  PRON  .00 (Ft) Wid  Thickness (in)  0.00  1.50 0.00 2.00  PRON .00 (Ft) Wid  Thickness	Section: dth: 75.0 Major M&R  V  Section: dth: 70.0 Major M&R	0 (Ft) True Area: 48170.00001 (SqFt  Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt
Network: L.C.D. 1/1/2  Work Date  1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2  Work Date	NU-IN  KEY WES  005 Us  Work Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED  KEY WES  003 Us  Work Code	TINTERN Branch: AP GA se: APRON Rank: P  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  TINTERN Branch: AP GA se: APRON Rank: P  Work Description	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00  A GA Al Length: 1,325  Cost	0.00  PRON  .00 (Ft) Wid  Thickness (in)  0.00  1.50  0.00  2.00  PRON  .00 (Ft) Wid  Thickness (in)	Section: dth: 75.0 Major M&R  V  Section: dth: 70.0 Major	Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2 Work Date 1/1/2015	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED  KEY WES  003 Us  Work  Code  ST-SC	RET INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  ST INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Surface Treatment - Seal Coat	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00  Cost  Cost  Cost  Cost  Cost  Cost	PRON .00 (Ft) Wid Thickness (in)  0.00 1.50 0.00 2.00  PRON .00 (Ft) Wid Thickness (in)  0.00	Section: dth: 75.0 Major M&R  V  Section: dth: 70.0 Major M&R	Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt
Network: L.C.D. 1/1/2  Work Date  1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2  Work Date  1/1/2015 1/1/2003	NU-IN  KEY WES  005 Us  Work Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED  KEY WES  003 Us  Work Code  ST-SC  NU-IN	RET INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  ST INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Surface Treatment - Seal Coat	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00  A GA Al Length: 1,325  Cost  0.00 0.00	PRON .00 (Ft) Wid Thickness (in)  0.00 1.50 0.00 2.00  PRON .00 (Ft) Wid Thickness (in)  0.00 0.00	Section: dth: 75.0 Major M&R  V  Section: dth: 70.0 Major M&R	Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt  Comments  Grip Flex
Network: L.C.D. 1/1/2  Work Date  1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2  Work Date  1/1/2015 1/1/2003	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED  KEY WES  003 Us  Work  Code  ST-SC  NU-IN	RET INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  ST INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Surface Treatment - Seal Coat New Construction - Initial	GA Al  Length: 600  Cost  0.00 0.00 0.00 0.00  Cost  Cost	PRON  .00 (Ft) Wid  Thickness (in)  0.00  1.50 0.00 2.00  PRON  .00 (Ft) Wid  Thickness (in)  0.00 0.00  PRON	Section: dth: 75.0 Major M&R  Section: dth: 70.0 Major M&R  Section:	Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt  Comments  Grip Flex
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2 Work Date 1/1/2015 1/1/2003  Network:	NU-IN  KEY WES  005 Us  Work  Code  ML-OVL  OL-AS  ST-SC  IMPORT  ED  KEY WES  003 Us  Work  Code  ST-SC  NU-IN	RET INTERN Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  BY Branch: AP GAR  Ree: APRON Rank: P I  Work Description  Surface Treatment - Seal Coat New Construction - Initial	GA Al  Length: 600  Cost  0.00 0.00 0.00 0.00  Cost  Cost	PRON  .00 (Ft) Wid  Thickness (in)  0.00  1.50 0.00 2.00  PRON  .00 (Ft) Wid  Thickness (in)  0.00 0.00  PRON	Section: dth: 75.0 Major M&R  Section: dth: 70.0 Major M&R  Section:	Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt  Comments  Grip Flex  4215 Surface:AC
Network: L.C.D. 1/1/2 Work Date 1/1/2005 1/1/2003 1/1/1989 1/1/1977  Network: L.C.D. 1/1/2 Work Date 1/1/2015 1/1/2003  Network: L.C.D. 1/1/2	NU-IN  KEY WES  005 Us  Work Code  ML-OVL OL-AS ST-SC IMPORT ED  KEY WES  003 Us  Work Code  ST-SC NU-IN  KEY WES  006 Us  Work	RET INTERN Branch: AP GAR  See: APRON Rank: P I  Work Description  Mill and Overlay Overlay - AC Structural Surface Treatment - Seal Coat BUILT  ST INTERN Branch: AP GAR  See: APRON Rank: P I  Work Description  Surface Treatment - Seal Coat New Construction - Initial  ST INTERN Branch: AP GAR  See: APRON Rank: P I	GA Al Length: 600  Cost  0.00 0.00 0.00 0.00 0.00  Cost  GA Al Length: 1,325  Cost  0.00 0.00 0.00 0.00	PRON .00 (Ft) Wid Thickness (in)  0.00 1.50 0.00 2.00  PRON .00 (Ft) Wid Thickness (in)  0.00 0.00  PRON .00 (Ft) Wid Thickness (in)  0.00 0.00  PRON .00 (Ft) Wid Thickness	Section: dth: 75.0 Major M&R  V Section: dth: 70.0 Major M&R  Section: dth: 113.0 Major	Comments  1989 P-625 SEALCOAT 1977 2" P-401 6" P-211  4205 Surface:AC 0 (Ft) True Area: 75458.00002 (SqFt  Comments  Grip Flex  4215 Surface:AC 0 (Ft) True Area: 58338.00001 (SqFt

Page 2 of 9

Pavement Database: FDOT

Network:	KEY WES	T INTERN	Branch: AP	GA	GA	A A F	PRON		Section:	4220		Surface:AC
<b>L.C.D.</b> 1/1/2	005 Us	se: APRON	Rank: P	L	ength:	209	.00 (Ft)	Wid	th: 65.0	0 (Ft)	True Area:	13765.00000 (SqFt
Work Date	Work Code	Work	Description		Cost		Thickne (in)	ess	Major M&R		Com	ments
1/1/2005	NC-AC	New Constru	ction - AC		0	.00	0	0.00				

**Network:** KEY WEST INTERN Branch: AP GA GA APRON Section: 4225 Surface: AAC **L.C.D.** 11/1/2021 Use: APRON Rank: P Width: 67.00 (Ft) True Area: 78577.00002 (SqFt **Length:** 1,305.00 (Ft) Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R 11/1/2021 ML-OVL Mill and Overlay 0.00 Variable Depth Mill, Variable Depth P 0.00 ~ 1/1/2015 ST-SC Surface Treatment - Seal Coat 0.000.00 Grip Flex 1/1/2003 New Construction - Initial NU-IN 0.000.00 ~

 Network:
 KEY WEST INTERN
 Branch:
 AP TERM
 TERMINAL APR
 Section:
 4105
 Surface:AAC

 L.C.D. 1/1/2003
 Use:
 APRON
 Rank:
 P
 Length:
 153.00 (Ft)
 Width:
 220.00 (Ft)
 True Area:
 34810.00001 (SqFt

 Work Date
 Work Code
 Work Description
 Cost
 Thickness (in)
 Major M&R
 Comments

 1/1/2005
 ST-SC
 Surface Treatment - Seal Coat
 0.00
 0.00
 0.00

Work Date	Code	Work Description	Cost	(in)	Major M&R	Comments
1/1/2005	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1989	IMPORT ED	BUILT	0.00	3.00		1989 3" P-401 6" P-211 12" P-154

 Network:
 KEY WEST INTERN
 Branch:
 AP TERM
 TERMINAL APR
 Section:
 4160
 Surface:
 PCC

 L.C.D. 10/1/2018
 Use:
 APRON
 Rank:
 P
 Length:
 493.00 (Ft)
 Width:
 911.00 (Ft)
 True Area:
 336953.0001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
10/1/2018	CR-PC	Complete Reconstruction - PCC	0.00	0.00	<b>V</b>	13"P-501, Rework Existing Base
1/1/2005	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1989	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		1989 P-625 SEALCOAT
1/1/1980	IMPORT	BUILT	0.00	2.00		1980 2" P-401 8" P-211
	ED					

 Network:
 KEY WEST INTERN
 Branch:
 RW 9-27
 RUNWAY 9-27
 Section:
 6105
 Surface:AAC

 L.C.D. 4/1/2018
 Use:
 RUNWAY
 Rank:
 P
 Length:
 4,800.00 (Ft)
 Width:
 100.00 (Ft)
 True Area:
 480000.0001 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
4/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b>	0.5" Mill, Variable Depth P-401 Overl
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1979	IMPORT ED	OVERLAY	0.00	2.50		1979 2.5" TO 6" P-401
1/1/1954	IMPORT ED	OVERLAY	0.00	2.00		1954 2" P-401 8" P-211
1/1/1952	IMPORT ED	BUILT	0.00	17.00		1952 17" P-154

1	1	11	7	12	Λ	1	1
		/	- /	ΙZ	u	Z	Z

Page 3 of 9

Pavement Database: FDOT

**Network:** KEY WEST INTERN Branch: RW 9-27 RUNWAY 9-27 Section: 6115 Surface: AC L.C.D. 1/1/2018 Use: RUNWAY Rank: P Length: 126.00 (Ft) Width: 100.00 (Ft) True Area: 12600.00000 (SqFt Work Thickness Major **Work Date** Cost **Work Description** Comments Code (in) M&R 1/1/2018 NC-AC New Construction - AC 0.00 9" P-401, Rework Existing Base 

**Network:** KEY WEST INTERN Branch: RW 9-27 RUNWAY 9-27 Section: 6120 Surface:PCC **L.C.D.** 1/1/2018 Width: 120.00 (Ft) True Area: 18000.00000 (SqFt Use: RUNWAY Rank: P Length: 150.00 (Ft) Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R NC-PC 1/1/2018 New Construction - PCC 0.00 0.00 13" P-501, Rework Existing Base ~

Network: KEY WEST INTERN Branch: TW A TAXIWAY A Section: 100 Surface:AAC L.C.D. 11/1/2021 Use: TAXIWAY Rank: P Length: 3,357.00 (Ft) Width: 50.00 (Ft) True Area: 167850.0000 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b>	Variable Depth Mill, Variable Depth P
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1979		OVERLAY	0.00	2.00		1979 2" P-401
1/1/1957	ED IMPORT ED	BUILT	0.00	8.00		1957 1.5 P-401 8" P-211

Network: KEY WEST INTERN Branch: TW A TAXIWAY A Section: 105 Surface:AAC

L.C.D. 1/1/2003 Use: TAXIWAY Rank: P Length: 250.00 (Ft) Width: 50.00 (Ft) True Area: 11729.00000 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50	<b>~</b>	
1/1/1979	IMPORT ED	OVERLAY	0.00	2.00		1979 2" P-401
1/1/1957	IMPORT ED	BUILT	0.00	8.00		1957 1.5 P-401 8" P-211

Network: KEY WEST INTERN Branch: TW A TAXIWAY A Section: 110 Surface:AAC

L.C.D. 11/1/2021 Use: TAXIWAY Rank: P Length: 1,160.00 (Ft) Width: 50.00 (Ft) True Area: 57185.00001 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b>	Variable Depth Mill, Variable Depth P
1/11/2003	OL-AS	Overlay - AC Structural	0.00	1.50	<b>~</b>	
1/1/1979	IMPORT	BUILT	0.00	2.00	<b>~</b>	1979 2" P-401 8" P-211 17" P-152
	ED					

Page 4 of 9

Pavement Database: FDOT

Network: L.C.D. 4/1/2		T INTERN Branch: TW A1 e: TAXIWAY Rank: P L		WAY A1 .00 (Ft) <b>Wi</b> o	Section:	~~~~~~
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
4/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b>	
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50	<b>~</b>	
1/1/1979	IMPORT ED	OVERLAY	0.00	2.00	<b>V</b>	1979 2" P-401
1/1/1957	IMPORT ED	BUILT	0.00	1.50	<b>V</b>	1957 1.5" P-401 8" P-211 17" P-152

Network: KEY WEST INTERN Branch: TW A1 TAXIWAY A1 Section: 135 Surface: AAC **L.C.D.** 1/1/2003 Use: TAXIWAY Rank: P Length: 127.00 (Ft) Width: 150.00 (Ft) True Area: 20821.00000 (SqFt Thickness Work Major **Work Date Work Description** Cost Comments Code (in) M&R 1/1/2003 OL-AS Overlay - AC Structural 0.00 1.50 ~ IMPORT OVERLAY 1/1/1979 0.00 1979 2" P-401 2.00 ~ ED IMPORT BUILT 1/1/1957 0.00 1.50 1957 1.5" P-401 8" P-211 17" P-152 ~ ED

Network: KEY WEST INTERN Branch: TW A2 TAXIWAY A2 Section: 120 Surface: AAC **L.C.D.** 11/1/2021 Use: TAXIWAY Rank: P Length: 105.00 (Ft) Width: 85.00 (Ft) True Area: 8949.000002 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code (in) M&R 11/1/2021 ML-OVL Mill and Overlay 0.00 0.00 Variable Depth Mill, Variable Depth P 4/1/2018 ML-OVL Mill and Overlay 0.00 0.00 ~ 1/1/2003 OL-AS Overlay - AC Structural 0.00 1.50 ~ 1/1/1979 IMPORT OVERLAY 0.00 2.00 1979 2" P-401 ED IMPORT BUILT 1/1/1957 0.00 1.50 V 1957 1.5" P-401 8" P-211 17" P-152 ED

Network: KEY WEST INTERN Branch: TW A2 TAXIWAY A2 Section: 125 Surface: AAC L.C.D. 11/1/2021 Use: TAXIWAY Rank: P Width: 90.00 (Ft) True Area: 16030.00000 (SqFt Length: 133.00 (Ft) Work Thickness Major **Work Date Work Description** Cost Comments M&R Code (in) 11/1/2021 ML-OVL Mill and Overlay 0.00 0.00 **Y** Variable Depth Mill, Variable Depth P 1/1/2003 OL-AS Overlay - AC Structural 0.001.50 ~ 1/1/1979 IMPORT OVERLAY 1979 2" P-401 0.00 2.00 ~ ED 1/1/1957 IMPORT BUILT 1957 1.5" P-401 8" P-211 17" P-152 0.00 1.50 ED

Page 5 of 9

Pavement Database: FDOT

Network: L.C.D. 11/1/		T INTERN Branch: TW A3		WAY A3 .00 (Ft) <b>Wi</b> o	Section:	140 <b>Surface:</b> AAC 0 (Ft) <b>True Area:</b> 9075.000002 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b> :	Variable Depth Mill, Variable Depth P
4/1/2018	ML-OVL	Mill and Overlay	0.00	0.00		
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1979	IMPORT ED	OVERLAY	0.00	2.00		1979 2" P-401
1/1/1957	IMPORT ED	BUILT	0.00	1.50		1957 1.5" P-401 8" P-211 17" P-152

TAXIWAY A3 **Network:** KEY WEST INTERN Branch: TW A3 Section: 145 Surface: AAC **L.C.D.** 11/1/2021 Use: TAXIWAY Rank: P Length: 190.00 (Ft) Width: 125.00 (Ft) True Area: 25387.00000 (SqFt Work Thickness Major **Work Date Work Description** Cost Comments Code (in) M&R 11/1/2021 ML-OVL Mill and Overlay Variable Depth Mill, Variable Depth P 0.00 0.00 **\** 1/1/2003 Overlay - AC Structural OL-AS 0.00 1.50 ~ 1/1/1979 IMPORT OVERLAY 0.002.00 ~ 1979 2" P-401 ED IMPORT BUILT 1/1/1957 1957 1.5" P-401 8" P-211 17" P-152 0.001.50 ED

Network: KEY WEST INTERN Branch: TW A4 TAXIWAY A4 Section: 160 Surface:AAC

L.C.D. 11/1/2021 Use: TAXIWAY Rank: P Length: 95.00 (Ft) Width: 60.00 (Ft) True Area: 6462.000001 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b>	Variable Depth Mill, Variable Depth P
4/1/2018	ML-OVL	Mill and Overlay	0.00	0.00		
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1979	IMPORT ED	OVERLAY	0.00	2.00		1979 2" P-401
1/1/1957	IMPORT ED	BUILT	0.00	1.50		1957 1.5" P-401 8" P-211 17" P-152

 Network:
 KEY WEST INTERN
 Branch:
 TW A4
 TAXIWAY A4
 Section:
 165
 Surface:AAC

 L.C.D. 11/1/2021
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 145.00 (Ft)
 Width:
 60.00 (Ft)
 True Area:
 11930.00000 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b>	Variable Depth Mill, Variable Depth P
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1979	IMPORT ED	OVERLAY	0.00	2.00		1979 2" P-401
1/1/1957	IMPORT ED	BUILT	0.00	1.50	<b>V</b>	1957 1.5" P-401 8" P-211 17" P-152

Page 6 of 9

Pavement Database: FDOT

**Network:** KEY WEST INTERN Branch: TW B10 Section: 260 Surface: AC TAXIWAY B10 **L.C.D.** 11/1/2021 Use: TAXIWAY Rank: P Length: 109.00 (Ft) Width: 60.00 (Ft) True Area: 8893.000002 (SqFt Work Thickness Major **Work Date** Cost **Work Description** Comments Code (in) M&R 11/1/2021 CR-AC Complete Reconstruction - AC 0.00 0.00 7" P-401, Rework Existing Base; Fille ~ 1/1/2014 CR-PC Complete Reconstruction - PCC 0.000.00 1/1/2003 NC-AC New Construction - AC 0.00 0.00 ~

**Network:** KEY WEST INTERN Section: 265 Branch: TW B11 TAXIWAY B11 Surface: AC **L.C.D.** 11/1/2021 Use: TAXIWAY Rank: P Length: 220.00 (Ft) Width: 30.00 (Ft) True Area: 5749.000001 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code M&R (in) 11/1/2021 CR-AC Complete Reconstruction - AC 0.00 0.00 7" P-401, Rework Existing Base; Fille ~ 1/1/2003 NU-IN New Construction - Initial 0.00 0.00 ~

Network: KEY WEST INTERN Branch: TW B11 TAXIWAY B11 Section: 267 Surface:PCC L.C.D. 10/1/2018 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 33.00 (Ft) True Area: 3067.000000 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	PA-PC	Patching - PCC	0.00	0.00		Fillet Widening (13" P-501, 6" P-211)
10/1/2018	CR-PC	Complete Reconstruction - PCC	0.00	0.00		
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00		

 Network:
 KEY WEST INTERN
 Branch:
 TW B1
 TAXIWAY B1
 Section:
 215
 Surface:AC

 L.C.D. 11/1/2021
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 96.00 (Ft)
 Width:
 60.00 (Ft)
 True Area:
 7765.000002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	4" P-401, Rework Existing Base; Fille
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		Grip Flex
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00		

 Network:
 KEY WEST INTERN
 Branch:
 TW B12
 TAXIWAY B12
 Section:
 270
 Surface:AC

 L.C.D. 11/1/2021
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 240.00 (Ft)
 Width:
 100.00 (Ft)
 True Area:
 11359.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	7" P-401, Rework Existing Base; Fille
1/1/2003	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/1979	IMPORT	OVERLAY	0.00	2.00		1979 2" P-401
	ED					
1/1/1957	IMPORT	BUILT	0.00	1.50		1957 1.5" P-401 8" P-211 17" P-152
	ED					

Network: KEY WEST INTERN Branch: TW B2 TAXIWAY B2 Section: 220 Surface:AC

L.C.D. 11/1/2021 Use: TAXIWAY Rank: P Length: 55.00 (Ft) Width: 60.00 (Ft) True Area: 3779.000001 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness Major M&R		Comments	
11/1/2021	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	4" P-401, Rework Existing Base; Fille	
1/1/2015	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		Grip Flex	
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00			

1/1/2003

NU-IN

New Construction - Initial

Use: TAXIWAY Rank: P

**L.C.D.** 11/1/2021

#### **Work History Report**

Page 7 of 9

Pavement Database: FDOT

**Network:** KEY WEST INTERN Branch: TW B3 TAXIWAY B3 Section: 225 Surface: AC **L.C.D.** 11/1/2021 Use: TAXIWAY Rank: P Length: 55.00 (Ft) Width: 60.00 (Ft) True Area: 3864.000001 (SqFt Work Thickness Major **Work Date** Cost **Work Description** Comments Code (in) M&R 11/1/2021 CR-AC Complete Reconstruction - AC 0.00 0.00 4" P-401, Rework Existing Base; Fille ~ 1/1/2015 ST-SC Surface Treatment - Seal Coat 0.000.00 Grip Flex 1/1/2003 NU-IN New Construction - Initial 0.00 0.00 ~

Network: KEY WEST INTERN Section: 230 Branch: TW B4 TAXIWAY B4 Surface: AC **L.C.D.** 11/1/2021 Use: TAXIWAY Rank: P Length: 55.00 (Ft) Width: 60.00 (Ft) True Area: 3864.000001 (SqFt Work Thickness Major **Work Date Work Description** Cost **Comments** Code M&R (in) 11/1/2021 CR-AC Complete Reconstruction - AC 0.00 0.00 4" P-401, Rework Existing Base; Fille ~ 1/1/2015 ST-SC Surface Treatment - Seal Coat 0.00 0.00 Grip Flex

Network: KEY WEST INTERN Branch: TW B5 TAXIWAY B5 Section: 235 Surface:AC

L.C.D. 11/1/2021 Use: TAXIWAY Rank: P Length: 252.00 (Ft) Width: 60.00 (Ft) True Area: 7125.000002 (SqFt

0.00

0.00

V

190.00 (Ft) Width: 60.00 (Ft) True Area: 6972.000002 (SqFt

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>~</b>	4" P-401, Rework Existing Base; Fille
1/1/2006	NC-AC	New Construction - AC	0.00	0.00		

Network: KEY WEST INTERN Branch: TW B6 TAXIWAY B6 Section: 240 Surface: AAC

L.C.D. 11/1/2021 Use: TAXIWAY Rank: P Length: 210.00 (Ft) Width: 60.00 (Ft) True Area: 6842.000002 (SqFt

Work	Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/20	021	ML-OVL	Mill and Overlay	0.00	0.00	<b>V</b>	Variable Depth Mill, Variable Depth P
1/1/200	05	ML-OVL	Mill and Overlay	0.00	0.00		
1/1/200	03	OL-AS	Overlay - AC Structural	0.00	1.50		
1/1/198	89	ST-SC	Surface Treatment - Seal Coat	0.00	0.00		1989 P-625 SEALCOAT
1/1/197	77	IMPORT	BUILT	0.00	2.00		1977 2" P-401 6" P-211
		ED					

 Network:
 KEY WEST INTERN
 Branch:
 TW B7
 TAXIWAY B7
 Section:
 245
 Surface:
 AC

 L.C.D. 11/1/2021
 Use:
 TAXIWAY
 Rank:
 P
 Length:
 135.00 (Ft)
 Width:
 60.00 (Ft)
 True Area:
 6819.000002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	4" P-401, 8" P-211
1/1/2014	CR-PC	Complete Reconstruction - PCC	0.00	0.00		
1/1/2003	NC-AC	New Construction - AC	0.00	0.00		

Network: KEY WEST INTERN Branch: TW B8 TAXIWAY B8 Section: 250 Surface: AC

Length:

V	<b>Vork Date</b>	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1	1/1/2021	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	4" P-401, 8" P-211
1/	/1/2014	CR-PC	Complete Reconstruction - PCC	0.00	0.00		
1/	/1/2003	NC-AC	New Construction - AC	0.00	0.00		

11/17/2022
------------

Page 8 of 9

Pavement Database: FDOT

Network:	KEY WES	T INTERN Branch: TW B9	TAXIV	WAY B9	Section:	255 Surface:AC
<b>L.C.D.</b> 11/1/	2021 Us	se: TAXIWAY Rank: P Lo	ength: 225	.00 (Ft) Wi	<b>dth:</b> 30.0	0 (Ft) <b>True Area:</b> 5828.000001 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2021	CR-AC	Complete Reconstruction - AC	0.00	0.00	<b>V</b>	7" P-401, Rework Existing Base; Fille
10/1/2018	CR-PC	Complete Reconstruction - PCC	0.00	0.00		
1/1/2014	CR-PC	Complete Reconstruction - PCC	0.00	0.00		
1/1/2003	NC-AC	New Construction - AC	0.00	0.00		

Network: L.C.D. 10/1/		T INTERN <b>Branch:</b> TW B9		WAY B9 .00 (Ft) <b>Wi</b> o	Section:	257 <b>Surface:</b> PCC 0 (Ft) <b>True Area:</b> 3071.000000 (SqFt
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2021	PA-PC	Patching - PCC	0.00	0.00		Fillet Widening (13" P-501, 6" P-211)
10/1/2018	CR-PC	Complete Reconstruction - PCC	0.00	0.00		
1/1/2014	CR-PC	Complete Reconstruction - PCC	0.00	0.00		
1/1/2003	NC-AC	New Construction - AC	0.00	0.00		

Page 9 of 9

Pavement Database: FDOT

### Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	19	1,447,049.00	3.24	3.78
Complete Reconstruction - AC	11	72,017.00	0.00	0.00
Complete Reconstruction - PCC	9	380,502.00	0.00	0.00
Mill and Overlay	17	966,881.00	0.00	0.00
New Construction - AC	9	123,411.00	0.00	0.00
New Construction - Initial	9	200,207.00	0.00	0.00
New Construction - PCC	1	18,000.00	0.00	0.00
OVERLAY	13	1,268,688.00	2.04	0.13
Overlay - AC Structural	19	1,447,049.00	1.50	0.00
Patching - PCC	2	6,138.00	0.00	0.00
Surface Treatment - Seal Coat	15	1,285,837.00	0.00	0.00

1	1	/1	7	/2	ሰ	1
1		/ I	1	ľZI	U 2	<u> </u>

## **Branch Condition Report**

Page 1 of 2

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP GA	8	5,283.00	107.25	466,793.00	APRON	54.13	19.70	57.11
AP TERM	2	646.00	565.50	371,763.00	APRON	69.00	29.00	92.57
RW 9-27	3	5,076.00	106.67	510,600.00	RUNWAY	89.00	8.04	86.37
TW A	3	4,767.00	50.00	236,764.00	TAXIWAY	91.00	12.73	98.66
TW A1	2	240.00	150.00	39,917.00	TAXIWAY	64.50	25.50	63.40
TW A2	2	238.00	87.50	24,979.00	TAXIWAY	100.00	0.00	100.00
TW A3	2	299.00	95.00	34,462.00	TAXIWAY	100.00	0.00	100.00
TW A4	2	240.00	60.00	18,392.00	TAXIWAY	100.00	0.00	100.00
TW B1	1	96.00	60.00	7,765.00	TAXIWAY	100.00	0.00	100.00
TW B10	1	109.00	60.00	8,893.00	TAXIWAY	100.00	0.00	100.00
TW B11	2	320.00	31.50	8,816.00	TAXIWAY	95.50	4.50	96.87
TW B12	1	240.00	100.00	11,359.00	TAXIWAY	100.00	0.00	100.00
TW B2	1	55.00	60.00	3,779.00	TAXIWAY	100.00	0.00	100.00
TW B3	1	55.00	60.00	3,864.00	TAXIWAY	100.00	0.00	100.00
TW B4	1	55.00	60.00	3,864.00	TAXIWAY	100.00	0.00	100.00
TW B5	1	252.00	60.00	7,125.00	TAXIWAY	100.00	0.00	100.00
TW B6	1	210.00	60.00	6,842.00	TAXIWAY	100.00	0.00	100.00
TW B7	1	135.00	60.00	6,819.00	TAXIWAY	100.00	0.00	100.00
TW B8	1	190.00	60.00	6,972.00	TAXIWAY	100.00	0.00	100.00
TW B9	2	330.00	30.00	8,899.00	TAXIWAY	86.50	13.50	90.68

11/17/2022	Branch Condition Report	Page 2 of 2
	Pavement Database: FDOT	

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	10	838,556.00	57.10	22.67	72.83
RUNWAY	3	510,600.00	89.00	8.04	86.37
TAXIWAY	25	439,511.00	94.64	13.63	95.70
ALL	38	1,788,667.00	84.32	23.01	82.32

Pavement Database: FDOT

NetworkId: EYW

Pavement Data	base: FDOT				Netu	vorkId.	EYW			
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspec tion	
AP GA	4130	1/1/2003	AAC	APRON	Р	0	29,979.00	10/10/202 2	19	39
AP GA	4145	1/1/2003	AAC	APRON	Р	0	144,422.00	10/10/202 2	19	41
AP GA	4150	1/1/2003	AC	APRON	Р	0	18,084.00	10/10/202 2	19	31
AP GA	4155	1/1/2005	AAC	APRON	Р	0	48,170.00	10/10/202 2	17	52
AP GA	4205	1/1/2003	AC	APRON	Р	0	75,458.00	10/10/202 2	19	61
AP GA	4215	1/1/2006	AC	APRON	Р	0	58,338.00	10/10/202 2	16	57
AP GA	4220	1/1/2005	AC	APRON	Р	0	13,765.00	10/10/202 2	17	52
AP GA	4225	11/1/2021	AAC	APRON	Р	0	78,577.00	11/1/2021	0	100
AP TERM	4105	1/1/2003	AAC	APRON	Р	0	34,810.00	10/10/202 2	19	40
AP TERM	4160	10/1/2018	PCC	APRON	Р	0	336,953.00	10/10/202 2	4	98
RW 9-27	6105	4/1/2018	AAC	RUNWAY	Р	0	480,000.00	10/10/202 2	4	86
RW 9-27	6115	1/1/2018	AC	RUNWAY	Р	0	12,600.00	10/10/202 2	4	81
RW 9-27	6120	1/1/2018	PCC	RUNWAY	Р	0	18,000.00	10/10/202 2	4	100
TW A	100	11/1/2021	AAC	TAXIWAY	Р	0	167,850.00	11/1/2021	0	100
TW A	105	1/1/2003	AAC	TAXIWAY	Р	0	11,729.00	10/10/202	19	73
TW A	110	11/1/2021	AAC	TAXIWAY	Р	0	57,185.00	11/1/2021	0	100
TW A1	130	4/1/2018	AAC	TAXIWAY	Р	0	19,096.00	10/10/202	4	90
TW A1	135	1/1/2003	AAC	TAXIWAY	Р	0	20,821.00	10/10/202 2	19	39
TW A2	120	11/1/2021	AAC	TAXIWAY	Р	0	8,949.00	11/1/2021	0	100
TW A2	125	11/1/2021	AAC	TAXIWAY	Р	0	16,030.00		0	100
TW A3 TW A3	140 145	11/1/2021 11/1/2021	AAC AAC	TAXIWAY TAXIWAY	P P	0	9,075.00 25,387.00	11/1/2021 11/1/2021	0	100 100
TW A4	160	11/1/2021	AAC	TAXIWAY	Р	0		11/1/2021	0	100
TW A4	165	11/1/2021	AAC	TAXIWAY	P	0	11,930.00		0	
TW B1	215	11/1/2021	AC	TAXIWAY	P	0	7,765.00		0	100
TW B10	260	11/1/2021	AC	TAXIWAY	Р	0	8,893.00		0	100
TW B11	265	11/1/2021	AC	TAXIWAY	P _	0	5,749.00	11/1/2021 10/10/202	0	
TW B11	267	10/1/2018	PCC	TAXIWAY	P	0	3,067.00	2	4	
TW B12	270	11/1/2021	AC	TAXIWAY	Р	0	11,359.00	11/1/2021	0	
TW B2	220	11/1/2021	AC	TAXIWAY	P	0	3,779.00	11/1/2021	0	100
TW B3	225	11/1/2021	AC	TAXIWAY	P	0	3,864.00	11/1/2021	0	100
TW B4	230	11/1/2021	AC	TAXIWAY	P	0	3,864.00		0	
TW B5	235	11/1/2021	AC	TAXIWAY	P	0	7,125.00		0	
TW B6	240	11/1/2021	AAC	TAXIWAY	Р	0	6,842.00	11/1/2021	0	100

## **Section Condition Report**

Page	2	ωf	4
1 420	4	UΙ	•

TW B7	245	11/1/2021	AC	TAXIWAY	Р	0	6,819.00	11/1/2021	0	100
TW B8	250	11/1/2021	AC	TAXIWAY	Р	0	6,972.00	11/1/2021	0	100
TW B9	255	11/1/2021	AC	TAXIWAY	Р	0	5,828.00	11/1/2021	0	100
TW B9	257	10/1/2018	PCC	TAXIWAY	Р	0	3,071.00	10/10/202 2	4	73

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		460,304.00	21	100.00	0.00	100.00
03-05	4	872,787.00	7	88.43	8.73	90.91
16-20	18	455,576.00	10	48.50	12.12	47.98
ALL	6	1,788,667.00	38	84.32	23.01	82.32



**Planning Needs** 

Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
EYW	RW 9-27	6105	SLIPPAGE CR	N/A	192	SF	0.0%	Preventive	AC Full-Depth Patching	252	SF	\$ 18.75	\$ 4,730
EYW	RW 9-27	6105	WEATHERING	Medium	1,200	SF	0.3%	Preventive	Surface Seal	1,200	SF	\$ 0.75	\$ 900
EYW	RW 9-27	6115	RAVELING	Medium	214	SF	1.7%	Preventive	Surface Seal	214	SF	\$ 0.75	\$ 170
EYW	TW A	105	WEATHERING	Medium	547	SF	4.7%	Preventive	Surface Seal	548	SF	\$ 0.75	\$ 420
EYW	TW B11	267	JT SEAL DMG	Medium	14	Slabs	100.0%	Preventive	PCC Joint Seal	307	LF	\$ 4.25	\$ 1,310
EYW	TW B9	257	LARGE PATCH	Medium	1	Slabs	5.6%	Preventive	PCC Full-Depth Patching	69	SF	\$ 75.00	\$ 5,170
EYW	TW B9	257	JOINT SPALL	High	2	Slabs	11.1%	Preventive	PCC Partial-Depth Patching	16	SF	\$ 169.00	\$ 2,730
EYW	AP TERM	4160	JT SEAL DMG	Low	599	Slabs	40.0%	Preventive	PCC Joint Seal	23,392	LF	\$ 4.25	\$ 99,420
EYW	AP TERM	4160	JOINT SPALL	Medium	8	Slabs	0.6%	Preventive	PCC Partial-Depth Patching	54	SF	\$ 169.00	\$ 9,090
EYW	AP GA	4130	SLIPPAGE CR	N/A	92	SF	0.3%	Stopgap	AC Full-Depth Patching	135	SF	\$ 18.75	\$ 2,530
EYW	AP GA	4150	ALLIGATOR CR	Medium	412	SF	2.3%	Stopgap	AC Full-Depth Patching	498	SF	\$ 18.75	\$ 9,350
EYW	AP GA	4155	ALLIGATOR CR	Medium	24	SF	0.1%	Stopgap	AC Full-Depth Patching	47	SF	\$ 18.75	\$ 900
EYW	AP GA	4155	DEPRESSION	High	32	SF	0.1%	Stopgap	AC Full-Depth Patching	59	SF	\$ 18.75	\$ 1,110
EYW	AP GA	4155	SLIPPAGE CR	N/A	238	SF	0.5%	Stopgap	AC Full-Depth Patching	305	SF	\$ 18.75	\$ 5,710

Table B.2: Section-Level 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type		nning Cost Stimate
2023	EYW	TW A1	135	AAC	20,821	38	AC Reconstruction	\$	636,000
2023	EYW	AP GA	4130	AAC	29,979	38	AC Reconstruction	\$	915,000
2023	EYW	AP GA	4145	AAC	144,422	40	AC Reconstruction	\$	4,405,000
2023	EYW	AP GA	4150	AC	18,084	30	AC Reconstruction	\$	552,000
2023	EYW	AP GA	4155	AAC	48,170	51	AC Reconstruction	\$	1,470,000
2023	EYW	AP GA	4205	AC	75,458	60	AC Rehabilitation	\$	1,057,000
2023	EYW	AP GA	4215	AC	58,338	56	AC Rehabilitation	\$	817,000
2023	EYW	AP GA	4220	AC	13,765	51	AC Reconstruction	\$	420,000
2023	EYW	AP TERM	4105	AAC	34,810	39	AC Reconstruction	\$	1,062,000
2024	EYW	TW A	105	AAC	11,729	70	AC Rehabilitation	\$	173,000
2025	EYW	TW B9	257	PCC	3,071	69	PCC Rehabilitation	\$	104,000
2030	EYW	RW 9-27	6115	AC	12,600	69	AC Rehabilitation	\$ 249,000	
2031	EYW	RW 9-27	6105	AAC	480,000	69	AC Rehabilitation	\$ 9,929,000	
2032	EYW	TW A1	130	AAC	19,096	70	AC Rehabilitation	\$	415,000

<sup>\*</sup>All planning cost values have been rounded up to the nearest thousand dollars.






## Appendix C: Technical Exhibits



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



AC AP GA 4215 2 11

4225~

400 401 402 403 404 500 501 502 503

TW A1

135
2 5


TW A

102 103 104 105 106 107 108 109 1 0 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 42 143 144 145 146 147

AC AP GA 4220 1 3

502 503 504

602 603 604 605



## **LEGEND**

- TYPICAL RUNWAY BRANCH ID - TYPICAL TAXIWAY BRANCH ID

AAC
AP TERM
4105
1 7

600

TYPICAL APRON BRANCH ID PAVEMENT SURFACE TYPE ---- PAVEMENT BRANCH ID SECTION NUMBER

> NUMBER OF SAMPLE UNITS IN SECTION NUMBER OF SAMPLE UNITS TO BE INSPECTED



216 215 214 213 212 211 210 209 208 207 206 205 204 203 202 201

316 315 314 313 312 311 310 309 308 307 306 305 304 303 302 301

510 509 508 507 506 505 504 503

PCC AP TERM 4160 8 71

616 653 615 614 613 612 611

AAC AP GA 4130

<u>16</u> 915

AAC AP GA 4145

SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.




TOTAL SAMPLES INSPECTED = 51 AC: 39 PCC: 12

INSPECTED SAMPLE UNITS.

FDOT








## RECENT & ANTICIPATED CONSTRUCTION ACTIVITY


CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION					
	RW 9-27	New Construction - AC   9" P-401, Rework Existing Base					
	RW 9-27	New Construction - PCC   13" P-501, Rework Existing Base					
2018	RW 9-27	Mill and Overlay   0.5" Mill, Variable Depth P-401 Overlay					
	TW A1, TW A2, TW A3, TW A4	Mill and Overlay					
	AP TERM	Complete Reconstruction - PCC   13"P-501, Rework Existing Base					
	TW B9, TW B11	Complete Reconstruction - PCC					
	AP GA, TW A,	Mill and Overlay   Variable Depth Mill,					
	TW A4	Mill and Overlay   Variable Depth Mill,					
	TW A2, TW A3,						
	1111 /12, 111 /10,	Variable Depth P-401 Overlay; Fillet					
		Widening (7" P-401, 9" P-211)					
	TW B1, TW B2,	Complete Reconstruction - AC   4" P-401,					
	TW B3, TW B4,	Rework Existing Base; Fillet Widening (4"					
2021	TW B5	P-401, 8" P-211)					
		Mill and Overlay   Variable Depth Mill,					
	TW B6	Variable Depth P-401 Overlay; Fillet					
		Widening (4" P-401, 8" P-211)					
	TW B7, TW B8	Complete Reconstruction - AC   4" P-401, 8" P-211					
	TW B9, TW B10, TW B11, TW B12	Complete Reconstruction - AC   7" P-401, Rework Existing Base; Fillet Widening (7" P-401, 9" P-211)					




RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.








RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.




RW 13-31 TYPICAL RUNWAY BRANCH ID


PCI 86-100 Good PCI 71-85 Satisfactory PCI 56-70 Fair PCI 41-55 Poor PCI 26-40 Very Poor PCI 11-25 Serious PCI 0-10 Failed

TYPICAL TAXIWAY BRANCH ID — TYPICAL APRON BRANCH ID












RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





RW 9-27, Section 6105, Sample Unit 127 - Slippage Cracking



RW 9-27, Section 6105, Sample Unit 172 - Longitudinal & Transverse Cracking





RW 9-27, Section 6115, Sample Unit 105 - Vicinity



RW 9-27, Section 6115, Sample Unit 105 - Raveling






RW 9-27, Section 6120, Sample Unit 103 - Vicinity



TW A, Section 100, Sample Unit 100 - Patching






TW A1, Section 105, Sample Unit 107 - Raveling



TW B9, Section 257, Sample Unit 201 - Joint Spall





AP GA, Section 4145, Sample Unit 313 - Depression



AP GA, Section 4155, Sample Unit 816 - Slippage Cracking






AP TERM, Section 4105, Sample Unit 500 - Block Cracking



AP TERM, Section 4106, Sample Unit 109 - Joint Seal Damage





## Appendix E: Inspection Distress Details

**FDOT** 

50

50

52

52

55

56

PATCHING

PATCHING

RAVELING

RAVELING

SWELLING

SLIPPAGE CR

L

M

L

M

N

L

 $20.00 \;\; SqFt$ 

14.00 SqFt

3882.00 SqFt

1294.00 SqFt

16.00 SqFt

5.00 SqFt

rdoi											D 1 C44
Generated l	Date		11/17/2022								Page 1 of 44
Network:	EYW			Name	: KEY	WEST INT	ERNATIONAL AI	RPORT			
Branch:	AP GA		Name:	GA APRON		Use:	APRON	Area:	466,	793 SqFt	
Section: 4	4130	of	8 F	rom: -			То: -		I	ast Const.:	1/1/2003
Surface:	AAC	Family:	CA653-PR-AP-	-AAC-APC Zone:			Category:		F	Rank: P	
Area:	29,9	79 SqFt	Length:	300 Ft		Width:	100 Ft				
Slabs:		Slab Len	gth:	Ft S	Slab Width:		Ft	Joint L	ength:	F	t
Shoulder:		Street Ty	pe:	(	Grade: 0			Lanes:	0		
Section Con	nments:										
Work Date:	: 1/1/1980	Wo	ork Type: BUIL	T		Co	ode: IMPORTED	Is I	Major M&	R: True	
Work Date:	: 1/1/1989	Wo	ork Type: Surfa	ce Treatment - Seal	Coat	Co	ode: ST-SC	Is I	Major M&	R: False	
Work Date:	: 1/1/2003	Wo	ork Type: Overl	ay - AC Structural		Co	ode: OL-AS	Is I	Major M&	R: True	
Work Date:	: 1/1/2005	Wo	ork Type: Surfa	ce Treatment - Seal	Coat	Co	ode: ST-SC	Is I	Major M&	R: False	
Last Insp. D	Date: 10/10/20	22	TotalSa	imples: 7		Surveye	<b>d:</b> 1				
Conditions:	PCI: 39										
Inspection (	Comments:										
Sample Nur	mber: 711	Тур	e: R	Area:	5210	.00 SqFt	PCI: 3	9			
Sample Cor	mments:										
43 BLO	OCK CR		L	504.00 SqFt							
43 BLO	OCK CR		M	56.00 SqFt							
	RESSION		L	20.00 SqFt							
				1							

Network: EYW		Name:	KEY WEST INTE	RNATIONAL AIRPOR	RT
Branch: AP GA	Name:	GA APRON			rea: 466,793 SqFt
Section: 4145	of 8	From: -		То: -	<b>Last Const.:</b> 1/1/2003
Surface: AAC	Family: CA653-PR-A	P-AAC-APC Zone:		Category:	Rank: P
Area: 144,4	22 SqFt Length	430 Ft	Width:	338 Ft	
Slabs:	Slab Length:	Ft Slab W	Vidth:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade	: 0		Lanes: 0
Section Comments:	••				
Work Date: 1/1/1977	Work Type: BU	ILT	Cod	le: IMPORTED	Is Major M&R: True
Work Date: 1/1/1989	Work Type: Sur	face Treatment - Seal Coat	Cod	le: ST-SC	Is Major M&R: False
Work Date: 1/1/2003	Work Type: Ove	erlay - AC Structural	Cod	le: OL-AS	Is Major M&R: True
Work Date: 1/1/2005	Work Type: Sur	face Treatment - Seal Coat	Cod	le: ST-SC	Is Major M&R: False
Last Insp. Date: 10/10/20 Conditions: PCI: 41 Inspection Comments:	22 Total	Samples: 30	Surveyed:	: 3	
Sample Number: 313	Type: R	Area:	5000.00 SqFt	PCI: 39	
Sample Comments:					
43 BLOCK CR	L	5000.00 SqFt			
45 DEPRESSION	L	327.00 SqFt			
49 OIL SPILLAGE	N	10.00 SqFt			
52 RAVELING	L	3750.00 SqFt			
52 RAVELING	M	1250.00 SqFt			
Sample Number: 512	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 37	
Sample Comments:					
•					
42 BLEEDING	N	20.00 SqFt			
42 BLEEDING 43 BLOCK CR	L	4500.00 SqFt			
42 BLEEDING 43 BLOCK CR 43 BLOCK CR	L M	4500.00 SqFt 500.00 SqFt			
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION	L M L	4500.00 SqFt 500.00 SqFt 10.00 SqFt			
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE	L M L N	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt			
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING	L M L N L	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 3750.00 SqFt			
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING 52 RAVELING	L M L N L	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 4750.00 SqFt 3750.00 SqFt 1250.00 SqFt	5000 00 SaFt	<b>PCI</b> • 40	
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING 52 RAVELING 53 RAVELING 54 Sample Number: 715	L M L N L	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 3750.00 SqFt	5000.00 SqFt	<b>PCI</b> : 49	
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING 52 RAVELING 53 Sample Number: 715 54 Sample Comments:	L M L N L M Type: R	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 3750.00 SqFt 1250.00 SqFt  Area:	5000.00 SqFt	<b>PCI</b> : 49	
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING 52 RAVELING 52 RAVELING 53 Sample Number: 715 54 Sample Comments:	Type: R	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 3750.00 SqFt 1250.00 SqFt  Area:	5000.00 SqFt	PCI: 49	
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING 52 RAVELING 52 RAVELING 53 Sample Number: 715 54 Sample Comments: 42 BLEEDING 45 DEPRESSION	L M L N L M Type: R	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 3750.00 SqFt 1250.00 SqFt  Area:  6.00 SqFt 81.00 SqFt	5000.00 SqFt	PCI: 49	
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING 52 RAVELING 52 RAVELING 53 Sample Number: 715 54 Sample Comments: 42 BLEEDING 45 DEPRESSION 45 DEPRESSION	L M L N L M M Type: R	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 3750.00 SqFt 1250.00 SqFt  Area:  6.00 SqFt 81.00 SqFt 35.00 SqFt	5000.00 SqFt	<b>PCI</b> : 49	
42 BLEEDING 43 BLOCK CR 43 BLOCK CR 45 DEPRESSION 49 OIL SPILLAGE 52 RAVELING 52 RAVELING 52 RAVELING 53 Sample Number: 715 54 Sample Comments: 42 BLEEDING 45 DEPRESSION	L M L N L M Type: R	4500.00 SqFt 500.00 SqFt 10.00 SqFt 40.00 SqFt 3750.00 SqFt 1250.00 SqFt  Area:  6.00 SqFt 81.00 SqFt	5000.00 SqFt	<b>PCI:</b> 49	

EYW KEY WEST INTERNATIONAL AIRPORT Network: Name: **Branch:** AP GA GA APRON Use: APRON 466,793 SqFt Name: Area: Section: 4150 of 8 **Last Const.:** 1/1/2003 From: To: -Surface: AC Family: CA653-PR-AP-AC Zone: Category: Rank: P 480 Ft Area: 18,084 SqFt Length: Width: 30 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2003 Work Type: New Construction - Initial Code: NU-IN Is Major M&R: True **Last Insp. Date:** 10/10/2022 TotalSamples: 4 Surveyed: 1 **Conditions: PCI:** 31 **Inspection Comments: PCI:** 31 Sample Number: 114 Type: R 6753.00 SqFt Area: **Sample Comments:** 154.00 SqFt 41 ALLIGATOR CR M 5594.00 SqFt 43 BLOCK CR L DEPRESSION L 353.00 SqFt 45 PATCHING L 50 969.00 SqFt PATCHING 50 M 36.00 SqFt

RAVELING

52

L

5748.00 SqFt

Network: EYW		Name:	KEY WEST INTE	ERNATIONAL AIR	PORT	
Branch: AP GA	Name:	GA APRON	Use:	APRON	Area:	466,793 SqFt
Section: 4155	of 8	rom: -		То: -		<b>Last Const.:</b> 1/1/2005
Surface: AAC	Family: CA653-PR-AP-	-AAC-APC Zone:		Category:		Rank: P
<b>Area:</b> 48,17	0 SqFt Length:	600 Ft	Width:	75 Ft		
Slabs:	Slab Length:	Ft Slab V	Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:	Grad	e: 0		Lanes: 0	
Section Comments:						
<b>Work Date:</b> 1/1/1977	Work Type: BUIL	Т	Со	de: IMPORTED	Is Major	M&R: True
<b>Work Date:</b> 1/1/1989	Work Type: Surfa	ce Treatment - Seal Coat	Со	de: ST-SC	Is Major	M&R: False
Work Date: 1/1/2003	Work Type: Overl	ay - AC Structural	Со	de: OL-AS	Is Major	M&R: True
<b>Work Date:</b> 1/1/2005	Work Type: Mill a	and Overlay	Co	de: ML-OVL	Is Major	M&R: True
<b>Last Insp. Date:</b> 10/10/202	2 TotalSa	amples: 11	Surveyed	l: 2		
Conditions: PCI: 52						
Inspection Comments:						
Sample Number: 316	Type: R	Area:	3848.00 SqFt	PCI: 55		
Sample Comments:						
41 ALLIGATOR CR	L	20.00 SqFt				
45 DEPRESSION	L	20.00 SqFt				
48 L & T CR	L	284.00 Ft				
52 RAVELING	L	385.00 SqFt				
53 RUTTING	L	88.00 SqFt				
57 WEATHERING	M	3463.00 SqFt				
Sample Number: 816	Type: A	Area:	5718.00 SqFt	PCI: 27		
Sample Comments:						
41 ALLIGATOR CR	L	42.00 SqFt				
41 ALLIGATOR CR	M	24.00 SqFt				
45 DEPRESSION	L	63.00 SqFt				
45 DEPRESSION	M	228.00 SqFt				
45 DEPRESSION	Н	32.00 SqFt				
48 L & T CR	L	372.00 Ft				
	L	185.00 SqFt				
50 PATCHING	M	30.00 SqFt				
50 PATCHING						
50 PATCHING	L	539.00 SqFt				
50 PATCHING 52 RAVELING		539.00 SqFt 238.00 SqFt				
50 PATCHING 52 RAVELING	L					

	ork: EYW			Name:	KEY WEST INT	ERNATIONAL AI	RPORT	
Bran	ch: AP GA		Name:	GA APRON	Use:	APRON	Area:	466,793 SqFt
Sectio	on: 4205	of 8		From: -		То: -		Last Const.: 1/1/2003
Surfa	ce: AC	Family: CA	.653-PR-A	AP-AC Zone:		Category:		Rank: P
Area:	75,45	58 SqFt	Length:	: 1,325 Ft	Width:	70 Ft		
Slabs	:	Slab Length:		Ft Slab V	Vidth:	Ft	Joint I	ength: Ft
Shoul	lder:	Street Type:		Grade	: 0		Lanes:	0
Sectio	on Comments:	V 1						
Work	x Date: 1/1/2003	Work 7		w Construction - Initial	C	ode: NU-IN	Is	Major M&R: True
Work	<b>Date:</b> 1/1/2015	Work 7		face Treatment - Seal Coat	C	ode: ST-SC	Is	Major M&R: False
Last 1	Insp. Date: 10/10/202	22	Total	Samples: 18	Surveye	ed: 3		
	itions: PCI: 61		2000	ampiest 10	Surveye			
	ction Comments:							
Samp	le Number: 316	Type:	R	Area:	4250.00 SqFt	PCI: 6	50	
Samp	le Comments:							
45	DEPRESSION		L	150.00 SqFt				
			L L	150.00 SqFt 142.00 Ft				
48	DEPRESSION			-				
48 52	DEPRESSION L & T CR		L	142.00 Ft				
48 52 52	DEPRESSION L & T CR RAVELING		L L	142.00 Ft 2125.00 SqFt				
48 52 52 57	DEPRESSION L & T CR RAVELING RAVELING		L L M	142.00 Ft 2125.00 SqFt 375.00 SqFt	4250.00 SqFt	PCI: 6	55	
48 52 52 57 <b>Samp</b>	DEPRESSION L & T CR RAVELING RAVELING WEATHERING		L L M L	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt	4250.00 SqFt	PCI: 6	55	
48 52 52 57 Samp	DEPRESSION L & T CR RAVELING RAVELING WEATHERING  Ole Number: 320	Туре:	L L M L	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt	4250.00 SqFt	PCI: 6	55	
48 52 52 57 <b>Samp</b> <b>Samp</b>	DEPRESSION L & T CR RAVELING RAVELING WEATHERING DIe Number: 320 DIe Comments:	Туре:	L L M L	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt  Area:	4250.00 SqFt	PCI: 6	55	
48 52 52 57 <b>Samp</b> <b>Samp</b> 48	DEPRESSION L & T CR RAVELING RAVELING WEATHERING  Ole Number: 320 Ole Comments: L & T CR	Туре:	L L M L R	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt  Area:  156.00 Ft 2125.00 SqFt	4250.00 SqFt	PCI: 6	55	
48 52 52 57 <b>Samp</b> 48 52	DEPRESSION L & T CR RAVELING RAVELING WEATHERING DIe Number: 320 DIE Comments: L & T CR RAVELING	Туре:	L L M L R	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt  Area:	4250.00 SqFt	PCI: 6	55	
48 52 52 57 <b>Samp</b> <b>Samp</b> 48 52 52	DEPRESSION L & T CR RAVELING RAVELING WEATHERING DIe Number: 320 DIE Comments: L & T CR RAVELING RAVELING RAVELING WEATHERING	Туре:	L L R L L M L L L L M L L	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt  Area:  156.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt	•			
48 52 57 <b>Samp</b> 48 52 52 57 <b>Samp</b>	DEPRESSION L & T CR RAVELING RAVELING WEATHERING DIe Number: 320 DIE Comments: L & T CR RAVELING RAVELING	Туре:	L L M L R	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt  Area:  156.00 Ft 2125.00 SqFt 375.00 SqFt	4250.00 SqFt 4517.00 SqFt	PCI: 6		
Samp 48 52 52 57 Samp	DEPRESSION L & T CR RAVELING RAVELING WEATHERING DIE Number: 320 DIE Comments: L & T CR RAVELING RAVELING RAVELING WEATHERING UE Number: 501 DIE Comments:	Туре:	L L R L L M L R	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt  Area:  156.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt Area:	•			
48 52 57 <b>Samp</b> 48 52 52 57 <b>Samp</b>	DEPRESSION L & T CR RAVELING RAVELING WEATHERING DIe Number: 320 DIE Comments: L & T CR RAVELING RAVELING RAVELING WEATHERING WEATHERING DIE Number: 501	Туре:	L L R L L M L L L L M L L	142.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt  Area:  156.00 Ft 2125.00 SqFt 375.00 SqFt 1750.00 SqFt	•			

Network:	EYW				Nan	ne: KEY	WEST INT	ERNATIONAI	AIRPO	ORT			
Branch:	AP GA		Name:	GA A	PRON		Use:	APRON		Area:	466	,793 SqFt	
Section:	4215	of 8		From:	-			То: -			]	Last Const.:	1/1/2006
Surface:	AC	Family: CA	\653-PR-Al	P-AC	Zon	e:		Category	:		]	Rank: P	
Area:	58,3	338 SqFt	Length:		634 F	it .	Width:	113	Ft				
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Len	gth:	Ft	i .
Shoulder:		Street Type:				Grade: 0				Lanes:	0		
Section Co	mments:	server Typer				0111110				Zanesv	Ü		
Work Date	e: 1/1/2006	Work '	Type: New	Constructi	on - AC		Co	ode: NC-AC		Is Ma	ajor M&	&R: True	
Last Insp.	<b>Date:</b> 10/10/20	)22	TotalS	amples:	11		Surveye	<b>d:</b> 2					
Conditions	s: <b>PCI</b> : 57												
	Comments:												
Sample Nu	ımber: 505	Type:	R	I	Area:	5500.	.00 SqFt	PCI	: 63				
Sample Co	omments:												
43 BL	OCK CR		L	312.00	SqFt								
45 DE	PRESSION		L	260.00	SqFt								
49 OII	SPILLAGE		N	40.00	SqFt								
52 RA	VELING		L	1375.00	SqFt								
57 WE	EATHERING		L	4125.00	SqFt								
Sample Nu	ımber: 603	Type:	R	I	Area:	5800	.00 SqFt	PCI	: 52				
Sample Co	omments:												
43 BL	OCK CR		L	600.00	SqFt								
45 DE	PRESSION		L	200.00	SqFt								
50 PA	TCHING		L	900.00	-								
52 RA	VELING		L	1222.00									
	VELING		M		SqFt								
					-								
53 RU	TTING		L	90.00	SqFt								

EYW KEY WEST INTERNATIONAL AIRPORT Network: Name: **Branch:** AP GA GA APRON Use: APRON 466,793 SqFt Name: Area: Section: 4220 of 8 **Last Const.:** 1/1/2005 From: To: -Surface: ACFamily: CA653-PR-AP-AC Zone: Category: Rank: P Area: 13,765 SqFt Length: 209 Ft Width: 65 Ft Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2005 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 10/10/2022 **TotalSamples:** 3 Surveyed: 1 **Conditions: PCI:** 52 **Inspection Comments:** 4101.00 SqFt **PCI:** 52 Sample Number: 706 Type: R Area: **Sample Comments:** 45 DEPRESSION M 90.00 SqFt 48 L & T CR L 169.00 Ft PATCHING L 50 100.00 SqFt RAVELING 52 L 1093.00 SqFt RAVELING 52 M 22.00 SqFt WEATHERING 2886.00 SqFt 57 M

Netwo	ork: EYW			N:	ame: K	EY WEST IN	ITERN	ATIONAL A	AIRPORT				
Branc	ch: AP GA	N	ame: C	GA APRON	J	Use	: AI	PRON	Area	ı:	466,79	3 SqFt	
Sectio		of 8	From:					To: -					11/1/2021
Surfac			3-PR-AP-AAC		one.			Category:				nk: P	11/1/2021
		•	Length:	1,305		Width:		67 Ft			Ra	IIK. 1	
Area: Slabs:		-	zengui.	1,505 Ft	Slab Width			Ft		Ioint I o	nath.	F	' <sub>4</sub>
		ab Length:		гі				гі		Joint Le	_	Г	ι
Should		treet Type:			Grade:	0				Lanes:	0		
Sectio	on Comments:												
Work	Date: 1/1/2003	Work Typ	e: New Const	truction - In	nitial		Code:	NU-IN		Is M	ajor M&R	: True	
Work	<b>Date:</b> 1/1/2015	Work Typ	e: Surface Tre	eatment - S	Seal Coat		Code:	ST-SC		Is M	ajor M&R	: False	
Work	<b>Date:</b> 11/1/2021	Work Typ	oe: Mill and O	verlay			Code:	ML-OVL		Is M	ajor M&R	: True	
Last I	Insp. Date: 7/29/2019		TotalSample	es: 35		Surve	yed: (	6					
Condi	itions: PCI: 55			NOTE:	*** Pre-Const	ruction PCI	***						
Inspec	ction Comments:												
Samp	le Number: 102	Type:	R	Area:	44	64.00 SqFt		PCI:	39				
_	le Comments:	V I				1 '							
	ALLIGATOR CR	ī	2	3 00 SaE	<del>t</del>								
41 42	BLEEDING	L N		3.00 SqFt 9.00 SqFt									
45	DEPRESSION	L		4.00 SqF									
48	L & T CR	L		6.00 Ft									
52	RAVELING	L		6.00 SqF									
52	RAVELING	M		6.00 SqF									
53	RUTTING	L		0.00 SqF		25 00 G F:		D.C.I.	<i>C</i> 1				
_	le Number: 108	Type:	R	Area:	42	25.00 SqFt		PCI:	61				
Samp	le Comments:												
42	BLEEDING	N		3.00 SqF	t								
48	L & T CR	L	15	9.00 Ft									
50	PATCHING	L		0.00 SqF									
52	RAVELING	L		0.00 SqF									
53	RUTTING	L		0.00 SqF									
57 57	WEATHERING WEATHERING	L M		5.00 SqFt 0.00 SqFt									
	le Number: 118	Type:	R	Area:		25.00 SqFt		PCI:	70				
_	le Comments:	Type.	K	Aica.	72	.23.00 Sqrt		TCI.	70				
42	BLEEDING	N		2.00 SqF	f								
48	L & T CR	L		1.00 Ft	-								
52	RAVELING	L		3.00 SqF	t								
57	WEATHERING	L		5.00 SqF									
57	WEATHERING	M		7.00 SqF									
_	le Number: 405	Type:	R	Area:	69	39.00 SqFt		PCI:	51				
Samp	le Comments:												
41	ALLIGATOR CR	L	2	0.00 SqF	t								
42	BLEEDING	N		5.00 SqF									
45	DEPRESSION	L		3.00 SqF	t								
48	L & T CR	L		3.00 Ft	4								
50 52	PATCHING RAVELING	L L		9.00 SqFt 2.00 SqFt									
52	RAVELING	M		8.00 SqF									
	le Number: 414	Type:	R	Area:		00.00 SqFt		PCI:	55				
_	le Comments:	-7 P**	-		30				- <del>-</del>				
48	L & T CR	L	7	2.00 Ft									
49	OIL SPILLAGE	N		3.00 SqF	t								
52	RAVELING	L		0.00 SqF									
52	RAVELING	M	125	0.00 SqF	t								

Samp	ole Number: 501	Type:	R	A	rea:	5000.00 SqFt	PCI:	56
Samp	ole Comments:							
48	L & T CR	L		58.00	Ft			
49	OIL SPILLAGE	N	Ī	10.00	SqFt			
52	RAVELING	L		3750.00	SqFt			
52	RAVELING	N	1	1250.00	SqFt			

Network:	EYW				Name:	KEY WEST IN	ΓERNA	ΓΙΟΝΑL AIRF	PORT		
Branch:	AP TERM		Name:	TERMI	NAL APRON	Use:	APR	ON	Area:	371,763	SqFt
Section: 4	1105	of	. 2	From: -			Т	o: -		Last	Const.: 1/1/2
Surface: A	AAC	Family:	CA653-PR-A	AP-AAC-APC	Zone:		C	ategory:		Ran	k: P
Area:	34,8	10 SqFt	Length	:	153 Ft	Width:		220 Ft			
Slabs:		Slab Leng	gth:	Ft	Slab Wi	idth:	F	t	Joint L	ength:	Ft
Shoulder:		Street Ty	pe:		Grade:	0			Lanes:	0	
Section Con	nments:										
Work Date:	1/1/1989	Wo	ork Type: BU	JILT		(	Code:	MPORTED	Is 1	Major M&R:	True
Work Date:	1/1/2003	Wo	ork Type: Ov	erlay - AC Stru	ıctural	(	Code: (	OL-AS	Is l	Major M&R:	True
Work Date:	1/1/2005	Wo	ork Type: Su	rface Treatmen	t - Seal Coat	(	Code: S	ST-SC	Is l	Major M&R:	False
Last Insp. D	Pate: 10/10/20	22	Tota	Samples: 7		Survey	<b>ed:</b> 1			,	,
Conditions:	<b>PCI:</b> 40										
Inspection (	Comments:										
Sample Nun	nber: 500	Тур	e: R	Aı	·ea:	5550.00 SqFt		<b>PCI:</b> 40			
Sample Con	nments:										
42 BLEI	EDING		N	21.00	SqFt						
43 BLO	CK CR		L	4995.00	SqFt						
43 BLO	CK CR		M	555.00	SqFt						
45 DEPI	RESSION		L	216.00	SqFt						
52 RAV	ELING		L	5550.00	SqFt						
56 SWE	LLING		L	60.00	•						

Network: EYW		Name:	KEY WEST INTER	NATIONAL AIRI	PORT		
Branch: AP TERM	Name:	TERMINAL APRON	Use: A	PRON	Area:	371,763 SqFt	
Section: 4160	of 2	rom: -		То: -		Last Const.:	10/1/2018
Surface: PCC Fam	ily: CA653-PR-AP-	PCC Zone:		Category:		Rank: P	
<b>Area:</b> 336,953 SqF	t Length:	493 Ft	Width:	911 Ft			
Slabs: 1,498 Slal	b Length:	15 Ft Slab Wid	<b>lth:</b> 1	5 Ft	Joint Leng	<b>th:</b> 58,479 Ft	
Shoulder: Stro	eet Type:	Grade:	0		Lanes:	0	
Section Comments:							
<b>Work Date:</b> 1/1/1980	Work Type: BUIL	Т	Code	: IMPORTED	Is Maj	or M&R: True	
<b>Work Date:</b> 1/1/1989	Work Type: Surface	ce Treatment - Seal Coat	Code	: ST-SC	Is Maj	or M&R: False	
Work Date: 1/1/2003	Work Type: Overl	ay - AC Structural	Code	: OL-AS	Is Maj	or M&R: True	
Work Date: 1/1/2005	Work Type: Surface	ce Treatment - Seal Coat	Code	: ST-SC	Is Maj	or M&R: False	
Work Date: 10/1/2018	Work Type: Comp	elete Reconstruction - PCC	Code	: CR-PC	Is Maj	or M&R: True	
Last Insp. Date: 10/10/2022	TotalSa	mples: 71	Surveyed:	8			
Conditions: PCI: 98							
Inspection Comments:							
Sample Number: 109	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 90			
Sample Comments:							
65 JT SEAL DMG	L	24.00 Slabs					
74 JOINT SPALL 74 JOINT SPALL	L M	2.00 Slabs 1.00 Slabs					
74 JOINT SPALL 75 CORNER SPALL	M L	1.00 Slabs					
Sample Number: 202	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 100	)		
Sample Comments:							
<no distress=""></no>							
Sample Number: 207	Type: R	Area:	24.00 Slabs	PCI: 100	)		
Sample Comments:	V E			2 100			
<no distress=""> Sample Number: 309</no>	Type: R	Arge	24.00 Slabs	PCI: 98			
_	Type: R	Area:	24.00 Stabs	ru: 98			
Sample Comments:							
65 JT SEAL DMG	L	24.00 Slabs					
Sample Number: 404	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 100	)		
Sample Comments:							
<no distress=""></no>							
Sample Number: 506	Type: R	Area:	24.00 Slabs	<b>PCI:</b> 98			
Sample Comments:							
65 JT SEAL DMG	L	24.00 Slabs					
Sample Number: 704	Type: R	Area:	18.00 Slabs	<b>PCI:</b> 100	)		
Sample Comments:							
<no distress=""></no>							
Sample Number: 708	Type: R	Area:	18.00 Slabs	PCI: 99			
Sample Comments:							
66 SMALL PATCH	L	1.00 Slabs					

Network: EYW		Name:	KEY WEST INTERN	NATIONAL AIRPO	DRT
Branch: RW 9-27	Name:	RUNWAY 9-27	Use: R	UNWAY	Area: 510,600 SqFt
Section: 6105	of 3	From: -		To: -	Last Const.: 4/1/2018
Surface: AAC Fam	ily: CA653-PR-RW	V-AAC- Zone:		Category:	Rank: P
<b>Area:</b> 480,000 SqF		4,800 Ft	Width:	100 Ft	
	b Length:	Ft Slab	Width:	Ft	Joint Length: Ft
Shoulder: Str	eet Type:	Grade	e: 0		Lanes: 0
<b>Section Comments:</b>					
<b>Work Date:</b> 1/1/1952	Work Type: BUIL	LT	Code	: IMPORTED	Is Major M&R: True
Work Date: 1/1/1954	Work Type: OVE	RLAY	Code	: IMPORTED	Is Major M&R: True
<b>Work Date:</b> 1/1/1979	Work Type: OVE	RLAY	Code	IMPORTED	Is Major M&R: True
Work Date: 1/1/2003	Work Type: Over	lay - AC Structural	Code	: OL-AS	Is Major M&R: True
Work Date: 4/1/2018	Work Type: Mill a	and Overlay	Code	: ML-OVL	Is Major M&R: True
<b>Last Insp. Date:</b> 10/10/2022	TotalSa	amples: 96	Surveyed:	20	
Conditions: PCI: 86					
Inspection Comments:					
Sample Number: 107	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 86	
Sample Comments:					
48 L & T CR	L	52.00 Ft			
<ul><li>57 WEATHERING</li><li>57 WEATHERING</li></ul>	L M	4750.00 SqFt 250.00 SqFt			
Sample Number: 112	Type: R	Area:	5000.00 SqFt	PCI: 88	
Sample Comments:	-JP**				
48 L & T CR	L	73.00 Ft			
56 SWELLING	L	5.00 SqFt			
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 117 Sample Comments:	Type: R	Area:	5000.00 SqFt	PCI: 84	
48 L & T CR	L	168.00 Ft			
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 122	Type: R	Area:	5000.00 SqFt	PCI: 84	
Sample Comments:					
48 L & T CR	L	159.00 Ft			
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 127	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 79	
Sample Comments:					
48 L & T CR	L	167.00 Ft			
55 SLIPPAGE CR	N	40.00 SqFt			
57 WEATHERING	L	5000.00 SqFt	5000 00 C-E4	DCI. 97	
Sample Number: 132 Sample Comments:	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 87	
-					
48 L & T CR 57 WEATHERING	L L	116.00 Ft 5000.00 SqFt			
Sample Number: 137	Type: R	Area:	5000.00 SqFt	PCI: 86	
Sample Comments:					
48 L & T CR	L	132.00 Ft			
57 WEATHERING	L	5000.00 SqFt			
Sample Number: 142	Type: R	Area:	5000.00 SqFt	<b>PCI:</b> 84	
Sample Comments:					

48	L & T CR		L	169.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Samn	le Number: 147	Type:	R	Area:	5000.00 SqFt	PCI: 84	
_		1 ypc.	10	711011	2000.00 Sq1 t	101. 01	
Samp	le Comments:						
48	L & T CR		L	173.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Samp	le Number: 152	Type:	R	Area:	5000.00 SqFt	PCI: 87	
Samp	le Comments:						
48	L & T CR		L	102.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Samp	le Number: 157	Type:	R	Area:	5000.00 SqFt	PCI: 85	
Samp	le Comments:						
48	L & T CR		L	157.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
	le Number: 162	Type:	R	Area:	5000.00 SqFt	PCI: 89	
_		- Jpc.	IX	mica.	2000.00 Bq1 t	101. 07	
Samp	le Comments:						
48	L & T CR		L	78.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Samp	le Number: 167	Type:	R	Area:	5000.00 SqFt	PCI: 89	
Samp	le Comments:						
40	I A TE CID			56.00 F:			
48 57	L & T CR WEATHERING		L L	56.00 Ft 5000.00 SqFt			
				-	5000 00 G F:	DCI 07	
_	le Number: 172	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 87	
Samp	le Comments:						
48	L & T CR		L	105.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Samp	le Number: 177	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 87	
Samp	le Comments:						
40	L & T CR		т	112.00 Ft			
48 57	WEATHERING		L L	5000.00 SqFt			
		Type			5000 00 SaEt	PCI: 88	
_	le Number: 182	Type:	R	Area:	5000.00 SqFt	1 (1. 00	
Samp	le Comments:						
48	L & T CR		L	98.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Samp	le Number: 187	Type:	R	Area:	5000.00 SqFt	PCI: 86	
Samp	le Comments:						
			т	120.00 E			
48 57	L & T CR WEATHERING		L L	128.00 Ft 5000.00 SqFt			
		Tr :		-	5000 00 C T	DCI. 07	
	le Number: 192	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 87	
Samp	le Comments:						
48	L & T CR		L	114.00 Ft			
57	WEATHERING		L	5000.00 SqFt			
Samp	le Number: 197	Type:	R	Area:	5000.00 SqFt	PCI: 86	
_	le Comments:				-		
				100 00 =			
48	L & T CR		L L	129.00 Ft			
57	WEATHERING			5000.00 SqFt	5000 00 G T:	DCI. 00	
_	le Number: 202	Type:	R	Area:	5000.00 SqFt	<b>PCI:</b> 90	
Samp	le Comments:						
48	L & T CR		L	29.00 Ft			
57	WEATHERING		L	5000.00 SqFt			

EYW KEY WEST INTERNATIONAL AIRPORT Network: Name: **Branch:** RW 9-27 RUNWAY 9-27 Use: RUNWAY Area: 510,600 SqFt Name: Section: 6115 of 3 To: -**Last Const.:** 1/1/2018 From: Surface: AC Family: CA653-PR-RW-AC Zone: Category: Rank: P 100 Ft Area: 12,600 SqFt Length: 126 Ft Width: Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft **Street Type:** Shoulder: Grade: Lanes: **Section Comments:** Work Date: 1/1/2018 Work Type: New Construction - AC Code: NC-AC Is Major M&R: True **Last Insp. Date:** 10/10/2022 **TotalSamples:** 2 Surveyed: 1 **Conditions: PCI:** 81 **Inspection Comments:** R 6000.00 SqFt **PCI:** 81 Sample Number: 105 Type: Area: **Sample Comments:** 48 L & T CR L 29.00 Ft RAVELING M 102.00 SqFt

52

57

WEATHERING

L

5898.00 SqFt

EYW KEY WEST INTERNATIONAL AIRPORT Network: Name: 510,600 SqFt **Branch:** RW 9-27 RUNWAY 9-27 Use: RUNWAY Name: Area: Section: 6120 of 3 From: **Last Const.:** 1/1/2018 To: -Surface: PCC Family: CA653-PR-RW-TW-PCC Zone: Category: Rank: P Area: 18,000 SqFt Length: 150 Ft Width: 120 Ft Slabs: Slab Length: 15 Ft Slab Width: 15 Ft Joint Length: 2,130 Ft 80 0 Shoulder: **Street Type:** Grade: Lanes: **Section Comments:** Work Date: 1/1/2018 Work Type: New Construction - PCC Code: NC-PC Is Major M&R: True **Last Insp. Date:** 10/10/2022 **TotalSamples:** 5 Surveyed: 2 **Conditions:** PCI: **Inspection Comments: PCI:** 100 Sample Number: 100 Type: R 16.00 Slabs Area: **Sample Comments:** <No Distress>

16.00 Slabs

**PCI:** 100

**Sample Comments:** 

Sample Number: 103

R

Area:

Type:

<No Distress>

Netwo	ork: EYW			N:	ame: KE	Y WEST IN	TERNATIONAL AIR	PORT			
Branc	h: TW A		Name:	TAXIWAY	A	Use:	TAXIWAY	Area:	236,764	SqFt	
Sectio	n: 100	of 3		From: -			То: -		Las	t Const.:	11/1/2021
Surfa	ce: AAC	Family: CA AP	A653-PR-T	W-AAC- Zo	one:		Category:		Ran	k: P	
Area:	167,850	SqFt	Length:	: 3,357	Ft	Width:	50 Ft				
Slabs		Slab Length:		Ft	Slab Width:		Ft	Joint	Length:	Ft	
Shoul	der:	Street Type:			Grade: 0			Lane	es: 0		
Sectio	n Comments:										
Work	<b>Date:</b> 1/1/1957	Work 7	Type: BU	ILT		(	Code: IMPORTED	I	s Major M&R:	True	
Work	<b>Date:</b> 1/1/1979	Work 7	Type: OV	ERLAY		C	Code: IMPORTED	I	s Major M&R:	True	
Work	<b>Date:</b> 1/1/2003	Work 7	Type: Ove	erlay - AC Structur	al	C	Code: OL-AS	I	s Major M&R:	True	
Work	<b>Date:</b> 11/1/2021	Work 7	Type: Mil	l and Overlay		(	Code: ML-OVL	I	s Major M&R:	True	
	nsp. Date: 7/29/2019		Total	Samples: 36		Survey					
	itions: PCI: 42			NOTE:	*** Pre-Constru	uction PCI *	**				
Inspe	ction Comments:										
_	le Number: 105	Type:	R	Area:	500	0.00 SqFt	<b>PCI:</b> 51				
Samp	le Comments:										
42	BLEEDING		N	4.00 SqFt							
48 52	L & T CR RAVELING		L L	244.00 Ft 500.00 SqFt							
53	RUTTING		L	1000.00 SqFt							
57	WEATHERING		M	4500.00 SqFt							
Samp	le Number: 111	Type:	R	Area:	500	0.00 SqFt	PCI: 25	i			
Samp	le Comments:										
48	L & T CR		L	563.00 Ft							
52	RAVELING		L	500.00 SqFt							
53	RUTTING		L	1220.00 SqFt							
53	RUTTING		M	210.00 SqFt							
53 56	RUTTING SWELLING		H	70.00 SqFt 50.00 SqFt							
57	WEATHERING		L M	4500.00 SqFt							
	le Number: 117	Type:	R	Area:		0.00 SqFt	PCI: 38	}			
_	le Comments:	J.F				1					
41	ALLIGATOR CR		L	8.00 SqFt							
48	L & T CR		L	534.00 Ft							
52	RAVELING		L	500.00 SqFt							
53	RUTTING		L	1400.00 SqFt							
56	SWELLING		L	100.00 SqFt							
57	WEATHERING		M	4500.00 SqFt							
_	le Number: 125	Type:	R	Area:	500	0.00 SqFt	<b>PCI:</b> 47	,			
_	le Comments:										
48	L & T CR		L	335.00 Ft							
52	RAVELING		L	500.00 SqFt							
53 57	RUTTING WEATHERING		L M	1500.00 SqFt 4500.00 SqFt							
	le Number: 131	Type:	R	4300.00 SqFt		3.00 SqFt	PCI: 49	)			
_	le Comments:	- J Per			333		- 52.				
42	BLEEDING		N	7.00 SqFt							
48	L & T CR		L	438.00 Ft							
52	RAVELING		L	953.00 SqFt							
32											
52	RAVELING		M	127.00 SqFt							

Samj	ple Number: 133	Type:	R	A	rea:	5588.00 SqFt	PCI:	41
Samj	ole Comments:							
48	L & T CR	Ι		465.00	Ft			
52	RAVELING	I		838.00	SqFt			
53	RUTTING	I	_	1223.00	SqFt			
53	RUTTING	N	M	77.00	SqFt			
57	WEATHERING	N	M	4750.00	SqFt			

Network:	EYW				Namo	e: KEY	WEST INT	ΓERN	ATIONAL AIRI	PORT			
Branch:	TW A		Name:	TAXIW	VAY A		Use:	TA	XIWAY	Area:	236,764	4 SqFt	
Section:	105	C	of 3	From: -					To: -		Las	t Const.:	1/1/2003
Surface:	AAC	Family:	CA653-PR-TV APC	V-AAC-	Zone	:			Category:		Rai	ık: P	
Area:		11,729 SqFt	Length:		250 Ft		Width:		50 Ft				
Slabs:		Slab Lei	ngth:	Ft		Slab Width:			Ft	Joint L	ength:	F	₹t
Shoulder:		Street T	ype:			Grade: 0				Lanes:	0		
Section Co	mments:												
Work Date	e: 1/1/1957	W	Vork Type: BUII	LT			C	Code:	IMPORTED	Is I	Major M&R:	True	
Work Date	e: 1/1/1979	W	ork Type: OVE	RLAY			C	Code:	IMPORTED	Is I	Major M&R:	True	
Work Date	e: 1/1/2003	3 W	ork Type: Over	lay - AC Str	uctural		C	Code:	OL-AS	Is I	Major M&R:	True	
Last Insp.	<b>Date:</b> 10/	10/2022	TotalS	samples: 3	;		Surveye	<b>ed:</b> 1					
Conditions	s: PCI:	73											
Inspection	Comments	s:											
Sample Nu	ımber: 10	00 Ty	pe: R		rea:	3750	0.00 SqFt		PCI: 73				
Sample Co	omments:												
48 L&	z T CR		L	168.00	Ft								
50 PA	TCHING		L	252.00	SqFt								
57 WE	ATHERIN	G	L	3323.00	SqFt								
57 WE	ATHERIN	G	M	175.00	SaFt								

Network:	EYW			Name:	KEY	WEST IN	ΓERN	ATIONAL A	AIRPORT		
Branch:	TW A	N	ame: TAX	IWAY A		Use:	TA	XIWAY	Area	: 2	36,764 SqFt
Section:	110	of 3	From:	-				То: -			Last Const.: 11/1/2
Surface:	AAC	Family: CA65: APC	3-PR-TW-AAC-	Zone:				Category:			Rank: P
Area:	57,1	185 SqFt I	Length:	1,160 Ft	,	Width:		50 Ft			
Slabs:		Slab Length:	F	t SI	ab Width:			Ft		Joint Length:	Ft
Shoulder:	:	Street Type:		G	rade: 0					Lanes: 0	
Section Co	omments:										
Work Dat	te: 1/1/1979	Work Typ	e: BUILT			(	Code:	IMPORTE	D	Is Major N	M&R: True
Work Dat	te: 1/11/2003	Work Typ	e: Overlay - AC	Structural		(	Code:	OL-AS		Is Major N	M&R: True
Work Dat	te: 11/1/2021	Work Typ	e: Mill and Over	ay		(	Code:	ML-OVL		Is Major N	M&R: True
Last Insp.	. Date: 7/29/20	19	TotalSamples:	12		Survey	<b>ed:</b> 3	}			
Condition	s: PCI: 42		N	OTE: *** P	re-Construc	tion PCI *	**				
Inspection	n Comments:										
Sample N	umber: 137	Type:	R	Area:	5002.0	00 SqFt		PCI:	23		
Sample C	omments:										
41 AL	LIGATOR CR	L		) SqFt							
	LEEDING	N		) SqFt							
	& T CR	L	559.0								
	& T CR	M		) Ft							
	TCHING	M		) SqFt							
	AVELING	L		) SqFt							
	JTTING	L		) SqFt							
	JTTING JTTING	M H		O SqFt							
	EATHERING	н L		) SqFt ) SqFt							
	EATHERING	M		) SqFt							
	umber: 140	Туре:	R	Area:	5000.0	00 SqFt		PCI:	64		
Sample C	omments:										
48 L &	& T CR	L	597.0	) Ft							
52 RA	AVELING	L	500.0	) SqFt							
52 RA	AVELING	M	12.0	) SqFt							
Sample N	umber: 144	Type:	R	Area:	5001.0	00 SqFt		PCI:	38		
Sample C	omments:										
48 L &	& T CR	L	535.0	) Ft							
	TCHING	L		) SqFt							
	JTTING	L		) SqFt							
	JTTING	M		) SqFt							
	EATHERING	L		) SqFt							
57 WI	EATHERING	M	3393.0	0 E							

Work Date: 1/1/1957 Work Type: BUILT  Work Date: 1/1/1979 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	NTERNATIONAL AIRPO	ORT	
Surface: AAC Family: CA653-PR-TW-AAC- Zone: APC  Area: 19,096 SqFt Length: 113 Ft Width: Slabs: Slab Length: Ft Slab Width: Shoulder: Street Type: Grade: 0  Section Comments:  Work Date: 1/1/1957 Work Type: BUILT  Work Date: 1/1/1979 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	: TAXIWAY	<b>Area:</b> 39,917 SqFt	
APC  Area: 19,096 SqFt Length: 113 Ft Width: Slabs: Slab Length: Ft Slab Width: Shoulder: Street Type: Grade: 0  Section Comments:  Work Date: 1/1/1957 Work Type: BUILT  Work Date: 1/1/1979 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	То: -	Last Cons	st.: 4/1/2018
Slabs: Slab Length: Ft Slab Width: Shoulder: Street Type: Grade: 0  Section Comments:  Work Date: 1/1/1957 Work Type: BUILT  Work Date: 1/1/2003 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	Category:	Rank: P	
Shoulder: Street Type: Grade: 0 Section Comments:  Work Date: 1/1/1957 Work Type: BUILT  Work Date: 1/1/1979 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	150 Ft		
Section Comments:  Work Date: 1/1/1957 Work Type: BUILT  Work Date: 1/1/1979 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	Ft	Joint Length:	Ft
Work Date: 1/1/1979 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:		Lanes: 0	
Work Date: 1/1/1979 Work Type: OVERLAY  Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt			
Work Date: 1/1/2003 Work Type: Overlay - AC Structural  Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Surve  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	Code: IMPORTED	Is Major M&R: True	
Work Date: 4/1/2018 Work Type: Mill and Overlay  Last Insp. Date: 10/10/2022 TotalSamples: 4 Surve  Conditions: PCI: 90  Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	Code: IMPORTED	Is Major M&R: True	
Last Insp. Date: 10/10/2022 TotalSamples: 4 Survey Conditions: PCI: 90 Inspection Comments: Sample Number: 100 Type: R Area: 3750.00 SqFt	Code: OL-AS	Is Major M&R: True	
Conditions: PCI: 90 Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	Code: ML-OVL	Is Major M&R: True	
Inspection Comments:  Sample Number: 100 Type: R Area: 3750.00 SqFt	eyed: 1		
Sample Number: 100 Type: R Area: 3750.00 SqFt			
VP.			
Sample Comments:	<b>PCI:</b> 90		
48 L & T CR L 22.00 Ft 57 WEATHERING L 3750.00 SqFt			

11011	ork: EYW					Nam	ie: K	EY WEST IN	NTERN	IATIONAL AIR	PORT				
Bran	ch: TW A	.1	1	Name:	TAXI	WAY A	1	Use	: TA	AXIWAY	Area:		39,917	SqFt	
Secti	on: 135		of 2	Froi	m:	-				То: -			Last	Const.:	1/1/2003
Surf	ace: AAC	Family	: CA6 APC	53-PR-TW-A	AC-	Zone	e:			Category:			Ran	k: P	
Area	:	20,821 SqFt		Length:		127 F	t	Width:		150 Ft					
Slab	s:	Slab L	ength:		Ft		Slab Width	ı:		Ft	J	oint Length:	:	Ft	
Shou	lder:	Street	Type:				Grade:	0			L	anes: 0			
Secti	on Comments:														
Wor	k <b>Date:</b> 1/1/195	57	Work Ty	ype: BUILT					Code:	IMPORTED		Is Major	M&R:	True	
Wor	k Date: 1/1/197	79	Work Ty	ype: OVERL	AY				Code:	IMPORTED		Is Major	M&R:	True	
Wor	k Date: 1/1/200	)3	Work Ty	ype: Overlay	- AC St	ructural			Code:	OL-AS		Is Major	M&R:	True	
	ection Commen	39 ts:													
Sam	ple Number: 1	ts:	`ype:	R	A	Area:	27	775.00 SqFt		PCI: 55	5				
Insp Sam Sam	ple Number: 1	ts:					27	775.00 SqFt		PCI: 55	5				
Sam Sam Sam	ple Number: 1	ts:	L	, .	444.00	SqFt	27	775.00 SqFt		PCI: 55	5				
Sam Sam Sam 43	ple Number: 1 ple Comments: BLOCK CR	ts:		, .		SqFt Ft	27	775.00 SqFt		PCI: 55	5				
Sam Sam Sam 43 48 53	ple Number: 1 ple Comments: BLOCK CR L & T CR	ts:	L L		444.00 94.00	SqFt Ft SqFt	27	775.00 SqFt		PCI: 55	5				
Sam Sam Sam 43 48 53 56	ple Number: 1 ple Comments:  BLOCK CR L & T CR RUTTING	ts:	L L L		444.00 94.00 40.00	SqFt Ft SqFt SqFt	27	775.00 SqFt		PCI: 55	5				
Sam Sam 13 18 53 56 57	ple Number: 1 ple Comments:  BLOCK CR L & T CR RUTTING SWELLING	ts: 104 <b>T</b> NG	L L L L	2	444.00 94.00 40.00 93.00	SqFt Ft SqFt SqFt SqFt	27	775.00 SqFt		PCI: 55	5				
Sam Sam 43 48 53 56 57 Sam	ple Number: 1 ple Comments: BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN	ts:   04	L L L L	2	94.00 94.00 40.00 93.00 081.00 694.00	SqFt Ft SqFt SqFt SqFt		775.00 SqFt		PCI: 55					
Sam Sam 43 48 53 56 57 Sam	ple Number: 1 ple Comments: BLOCK CR L & T CR RUTTING SWELLING WEATHERIN	ts:   04	L L L L L	, 2 , 2	94.00 94.00 40.00 93.00 081.00 694.00	SqFt Ft SqFt SqFt SqFt SqFt									
Samj Samj 43 48 553 566 57 Samj	ple Number: 1 ple Comments: BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN	ts: 104 T  NG NG 107 T	L L L L L	2 4 R	94.00 94.00 40.00 93.00 081.00 694.00	SqFt Ft SqFt SqFt SqFt SqFt									
Sam Sam 348 53 56 57 Sam Sam	ple Number: In ple Comments:  BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN Ple Number: In ple Comments:	ts: 104 T  NG NG 107 T	L L L L L M	2 2 R	444.00 94.00 40.00 93.00 081.00 694.00	SqFt Ft SqFt SqFt SqFt SqFt SqFt SqFt									
[Inspectation of the content of the	ple Number: 1 ple Comments: BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN ple Number: 1 ple Comments:	NG NG 107 T	L L L L L N	2 A R	444.00 94.00 40.00 93.00 081.00 694.00 A	SqFt Ft SqFt SqFt SqFt SqFt SqFt SqFt									
[Inspectation of the content of the	ple Number: In ple Comments:  BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN Ple Number: In ple Comments:  ALLIGATOR BLOCK CR	NG NG 107 T	L L L L M Sype:	2 A R	444.00 94.00 40.00 93.00 081.00 694.00 A	SqFt Ft SqFt SqFt SqFt SqFt SqFt SqFt Sq									
Sam Sam 43 48 53 56 57 Sam 41 43 45 48	ple Number: In ple Comments:  BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN Ple Number: In ple Comments:  ALLIGATOR BLOCK CR DEPRESSION	NG NG 107 T	L L L L N Yppe:	2 1 R	444.00 94.00 40.00 93.00 081.00 694.00 A 340.00 99.00	SqFt Ft SqFt SqFt SqFt SqFt SqFt SqFt Sq									
Samj Samj 43 48 53 56 57 Samj 41 43 44 48	ple Number: In ple Comments:  BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN Ple Number: In ple Comments:  ALLIGATOR BLOCK CR DEPRESSION L & T CR	NG NG 107 T	L L L L M Yype:	2 1 1 R	444.00 94.00 40.00 93.00 081.00 694.00 A 340.00 99.00 335.00	SqFt Ft SqFt SqFt SqFt SqFt SqFt SqFt Ft SqFt Ft									
Sam 43 448 553 566 557 Sam 41 43 445 448 448 448	ple Number: In ple Comments:  BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN Ple Number: In ple Comments:  ALLIGATOR BLOCK CR DEPRESSION L & T CR L & T CR	NG NG 107 T	L L L L M Yppe:	2 R	444.00 94.00 40.00 93.00 081.00 694.00 A 340.00 340.00 99.00 335.00 25.00	SqFt Ft SqFt SqFt SqFt SqFt SqFt SqFt Ft SqFt Sq									
Sami Sami 43 48 53 56 57 Sami 41 43 45 48 48 52 53	ple Number: In ple Comments:  BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN Ple Number: In ple Comments:  ALLIGATOR BLOCK CR DEPRESSION L & T CR L & T CR RAVELING	NG NG 107 T	L L L L L M Yppe:	2 R	444.00 94.00 40.00 93.00 081.00 694.00 A 340.00 99.00 335.00 25.00 294.00	SqFt Ft SqFt SqFt SqFt SqFt SqFt Ft SqFt Sq									
Sam Sam 43 48 53 56 57 57	ple Number: In ple Comments:  BLOCK CR L & T CR RUTTING SWELLING WEATHERIN WEATHERIN Ple Number: In ple Comments:  ALLIGATOR BLOCK CR DEPRESSION L & T CR L & T CR RAVELING RUTTING	ts: 104	L L L L M Yype:	2 R	444.00 94.00 93.00 081.00 694.00 A 340.00 99.00 335.00 25.00 294.00 136.00	SqFt Ft SqFt SqFt SqFt SqFt SqFt Ft SqFt Sq									

Network:	EYW					Name	e: KEY	Y WEST IN	ITERN	ATIONAL AIR	PORT			
Branch:	TW A2			Name:	TAXIV	VAY A2	2	Use	: TA	AXIWAY	Area:		24,979 SqFt	
Section:	120	0	f 2	Fr	om: -	-				To: -			Last Cons	t.: 11/1/2021
Surface:	AAC	Family:	CA6	553-PR-TW-	AAC-	Zone	:			Category:			Rank: P	
Area:		8,949 SqFt		Length:		105 Ft		Width:		85 Ft				
Slabs:		Slab Ler	ngth:		Ft		Slab Width:			Ft	Joint	Length	:	Ft
Shoulder:		Street T	ype:				Grade: 0				Lane	es: 0		
Section Co	omments:													
Work Date	<b>e:</b> 1/1/1957	W	ork T	ype: BUILT	Γ				Code:	IMPORTED	1	s Major	M&R: True	
Work Date	<b>e:</b> 1/1/1979	W	ork T	ype: OVER	LAY				Code:	IMPORTED	1	s Major	M&R: True	
Work Date	<b>e:</b> 1/1/2003	W	ork T	ype: Overla	y - AC Stı	uctural			Code:	OL-AS	I	s Major	M&R: True	
Work Date	<b>e:</b> 4/1/2018	W	ork T	ype: Mill ar	nd Overlay	7			Code:	ML-OVL	l	s Major	M&R: True	
Work Date	<b>e:</b> 11/1/2021	W	ork T	ype: Mill ar	nd Overlay	7			Code:	ML-OVL	1	s Major	M&R: True	
Last Insp.	<b>Date:</b> 3/23/	/2015		TotalSa	mples:	1		Surve	yed:	1				
Conditions	s: PCI:	68			NO	TE: ***	Pre-Constru	ction PCI	***					
Inspection	Comments:													
Sample Nu	umber: 301	Tyl	pe:	R	A	rea:	5617	7.00 SqFt		PCI: 68				
Sample Co	omments:													
	NGITUDINA ACKING	AL/TRANSVER	SE L	_	671.00	Ft								
	VELING		L	_	1123.00									
56 SW	ELLING		L	_	21.00	SqFt								

Network:	EYW				Name: F	KEY WEST INT	ERNATIO	NAL AIR	PORT			
Branch:	TW A2		Name:	TAXIWA	Y A2	Use:	TAXIW	AY	Area:	24,979	SqFt	
Section:	125	o	f 2	From: -			To:	-		Last	t Const.:	11/1/2021
Surface:	AAC	Family:	CA653-PR-TY APC	W-AAC-	Zone:		Cate	gory:		Ran	k: P	
Area:	16	,030 SqFt	Length:	1	33 Ft	Width:		90 Ft				
Slabs:		Slab Lei	ngth:	Ft	Slab Widt	h:	Ft		Joint Len	gth:	F	t
Shoulder:		Street T	ype:		Grade:	0			Lanes:	0		
Section Con	mments:											
Work Date:	: 1/1/1957	W	ork Type: BUI	LT		C	ode: IMP	ORTED	Is Ma	jor M&R:	True	
Work Date:	: 1/1/1979	W	ork Type: OVI	ERLAY		C	ode: IMP	ORTED	Is Ma	jor M&R:	True	
Work Date:	: 1/1/2003	W	ork Type: Ove	rlay - AC Struc	tural	C	ode: OL-	AS	Is Ma	jor M&R:	True	
Work Date:	: 11/1/2021	W	ork Type: Mill	and Overlay		C	ode: ML-	OVL	Is Ma	jor M&R:	True	
Last Insp. I	Date: 7/29/2	019	Totals	Samples: 2		Surveye	<b>d:</b> 1					
Conditions:	: PCI: 5	1		NOTE	: *** Pre-Cons	truction PCI *	**					
Inspection (	Comments:											
Sample Nui	mber: 301	Tyj	pe: R	Are	a: 5	267.00 SqFt		PCI: 51				
Sample Cor	mments:											
48 L&	T CR		L	812.00 Ft								
50 PAT	CHING		L	558.00 Sc	<sub>l</sub> Ft							
52 RAV	VELING		L	1284.00 Sc	<sub>l</sub> Ft							
57 WE	ATHERING		L	2415.00 Sc	ιFt							
57 WE	ATHERING		M	1010.00 Sc	ıFt							

Netwo	rk: EYW					Nan	ne: KE	Y WEST IN	TERN	ATIONAL AIRF	ORT				
Branc	h: TW A3		N	Name:	TAXI	WAY A	.3	Use	: TA	AXIWAY	Area:		34,462	2 SqFt	
Section	n: 140	0	f 2		From:	-				То: -			Las	t Const.:	11/1/2021
Surfac	ee: AAC	Family:	CA65	53-PR-T	W-AAC-	Zon	e:			Category:			Rai	ık: P	
Area:		9,075 SqFt		Length	:	109 F	<sup>7</sup> t	Width:		65 Ft					
Slabs:		Slab Len	ngth:		Ft		Slab Width:			Ft	J	oint Leng	th:	F	t
Should	ler:	Street T	ype:				Grade: 0				I	Lanes:	0		
Section	n Comments:														
Work	<b>Date:</b> 1/1/1957	W	ork Ty	pe: BU	ILT				Code:	IMPORTED		Is Maj	or M&R:	True	
Work	<b>Date:</b> 1/1/1979	W	ork Ty	pe: OV	ERLAY				Code:	IMPORTED		Is Maj	or M&R:	True	
Work	<b>Date:</b> 1/1/2003	W	ork Ty	pe: Ove	erlay - AC St	ructural			Code:	OL-AS		Is Maj	or M&R:	True	
Work	<b>Date:</b> 4/1/2018	W	ork Ty	pe: Mil	l and Overla	y			Code:	ML-OVL		Is Maj	or M&R:	True	
Work	<b>Date:</b> 11/1/2021	W W	ork Ty	pe: Mil	l and Overla	у			Code:	ML-OVL		Is Maj	or M&R:	True	
Last I	nsp. Date: 3/23	3/2015		Total	Samples:	2		Surve	yed: 4	4					
Condi	•				=		* Pre-Constri								
	tion Comments:														
Sampl	e Number: 10	1 Tyj	pe:	R	A	rea:	366	5.00 SqFt		PCI: 58					
Sampl	e Comments:														
15 18	DEPRESSION LONGITUDINA CRACKING	AL/TRANSVER	L SE L		14.00 357.00	-									
52	RAVELING		L		733.00	SqFt									
53	RUTTING		L		12.00	SqFt									
56	SWELLING		L			SqFt									
57	WEATHERING		L		2932.00		262	7.00 G E:		DCI 71					
-	e Number: 103 e Comments:	З Туј	pe:	R	P	rea:	362	5.00 SqFt		<b>PCI:</b> 71					
_			-		40.00	~ -									
45 45	DEPRESSION		L		18.00 10.00										
15 18	DEPRESSION L & T CR		L L		171.00										
52	RAVELING		L		363.00										
57	WEATHERING	ì	L		3263.00										
	e Number: 202			R		rea:	553	7.00 SqFt		PCI: 50					
Sampl	e Comments:														
12	BLEEDING		N		1.00	SqFt									
43	BLOCK CR		L		994.00										
48	L & T CR		L		115.00										
18	L & T CR		L		77.00										
52	RAVELING		L		4706.00	-									
52	RAVELING		M		831.00										
55	SLIPPAGE CR	n 25	N		16.00		21.5	0.00 G E:		DOI 10					
-	e Number: 300 e Comments:	О Туј	pe:	R	P	rea:	316	0.00 SqFt		<b>PCI:</b> 48					
_	BLEEDING		N		14.00	SaE+									
42 43	BLOCK CR		L L		14.00 2713.00										
+3 45	DEPRESSION		L L		24.00										
45 45	DEPRESSION		L		14.00										
43 48	L & T CR		L		138.00										
52	RAVELING		L		2713.00										
52	RAVELING		L		45.00	-									
- =			2		.2.00	- 7* *									

Network: EYW			Name:	KEY WEST INT	ERNATIONAL AIR	PORT		
Branch: TW A3	I	Name: TAXI	WAY A3	Use:	TAXIWAY	Area:	34,462 SqFt	
Section: 145	of 2	From:	-		То: -		Last Const.	: 11/1/202
Surface: AAC	Family: CA6 APC	53-PR-TW-AAC-	Zone:		Category:		Rank: P	
Area:	25,387 SqFt	Length:	190 Ft	Width:	125 Ft			
Slabs:	Slab Length:	Ft	Slab Wi	idth:	Ft	Joint Le	ngth:	Ft
Shoulder:	Street Type:		Grade:	0		Lanes:	0	
Section Comments:								
Work Date: 1/1/1957	Work Ty	ype: BUILT		Co	ode: IMPORTED	Is M	ajor M&R: True	
<b>Work Date:</b> 1/1/1979	Work Ty	ype: OVERLAY		Co	ode: IMPORTED	Is M	ajor M&R: True	
Work Date: 1/1/2003	Work Ty	ype: Overlay - AC S	tructural	Co	ode: OL-AS	Is M	ajor M&R: True	
Work Date: 11/1/2021	Work Ty	ype: Mill and Overla	у	Co	ode: ML-OVL	Is M	ajor M&R: True	
Last Insp. Date: 7/29	/2019	TotalSamples:	4	Surveye	<b>d:</b> 1			
Conditions: PCI:	43	NO	OTE: *** Pre-Co	onstruction PCI **	**			
Inspection Comments:								
Sample Number: 102	Type:	R	Area:	4500.00 SqFt	PCI: 43			
Sample Comments:								
41 ALLIGATOR C	R L	50.00	SqFt					
43 BLOCK CR	L		-					
48 L & T CR	L		•					
52 RAVELING	L	450.00	SqFt					
53 RUTTING	L	185.00	SqFt					
57 WEATHERING	N	1 4050.00	C - E4					

Netw	ork: EYW					Nai	ne: KE	Y WEST INT	ERN.	ATIONAL AIRI	PORT			
Bran	ch: TW A4		N	Vame:	TAXI	WAY A	.4	Use:	TA	XIWAY	Area:	18	,392 SqFt	
Section	on: 160	of	f 2		From:	-				To: -		]	Last Const.:	11/1/2021
Surfa	ce: AAC	Family:	CA65 APC	3-PR-T	W-AAC-	Zor	e:			Category:		:	Rank: P	
Area	:	6,462 SqFt		Length:		95 ]		Width:		60 Ft				
Slabs	:	Slab Len	gth:		Ft		Slab Width:			Ft	Jo	int Length:	F	t
Shou	lder:	Street Ty	pe:				Grade: 0				L	anes: 0		
Section	on Comments:													
Worl	<b>Date:</b> 1/1/1957	W	ork Ty	pe: BUI	LT			C	ode:	IMPORTED		Is Major Mé	R: True	
Worl	<b>Date:</b> 1/1/1979	W	ork Ty	pe: OVI	ERLAY			C	ode:	IMPORTED		Is Major M&	&R: True	
Worl	<b>Date:</b> 1/1/2003	Wo	ork Ty	pe: Ove	rlay - AC St	ructura	[	C	ode:	OL-AS		Is Major Mé	R: True	
Worl	<b>Date:</b> 4/1/2018	W	ork Ty	pe: Mill	and Overlag	y		C	ode:	ML-OVL		Is Major Mé	R: True	
Worl	<b>Date:</b> 11/1/2021	W	ork Ty	pe: Mill	and Overla	Y		C	ode:	ML-OVL		Is Major Mé	R: True	
Last	Insp. Date: 3/23/	2015		Totals	Samples:	12		Surveyo	ed: 3	3				
Cond	itions: PCI:	64			NO	TE: *	* Pre-Constru	ection PCI *	**					
Inspe	ction Comments:													
Samp	ole Number: 100	Тур	e:	R	A	rea:	375	0.00 SqFt		<b>PCI:</b> 61				
Samp	ole Comments:													
48	LONGITUDINA CRACKING	L/TRANSVERS	SE L		263.00	Ft								
52	RAVELING		L		3000.00	-								
52 55	RAVELING SLIPPAGE CRA	CKING	M N		188.00 12.00	-								
	ole Number: 301	Тур		R		rea:	375	0.00 SqFt		PCI: 57				
_	ole Comments:							1						
41	ALLIGATOR CI	RACKING	L		8.00	SqFt								
48	LONGITUDINA CRACKING				376.00	•								
52	RAVELING		L		750.00									
53 57	RUTTING WEATHERING		L L		9.00 3000.00	SqFt SqFt								
	ole Number: 600	Тур		R		rea:	650	2.00 SqFt		PCI: 69				
_	ole Comments:	- J P			1		330			- 32. 37				
42	BLEEDING		N		70.00	SaFt								
48	LONGITUDINA CRACKING	L/TRANSVERS			259.00	-								
48	LONGITUDINA CRACKING	L/TRANSVERS	SE L		89.00	Ft								
					650.00	C E								
52 57	RAVELING WEATHERING		L L		650.00 5852.00									

Netwo	rk: EYW				Nan	ie: KE	Y WEST INTER	RNATIONAL A	IRPORT			
Brancl	1: TW A4		Nam	e: TAXI	WAY A	4	Use:	TAXIWAY	Area:	18,3	392 SqFt	
Section	n: 165	0	of 2	From:	-			То: -		L	ast Const.:	11/1/202
Surfac	e: AAC	Family:	CA653-P APC	R-TW-AAC-	Zon	e:		Category:		R	ank: P	
Area:	11	,930 SqFt	Len	gth:	145 F	t	Width:	60 Ft				
Slabs:		Slab Ler	ngth:	Ft		Slab Width:		Ft	Joi	int Length:	F	
Should	ler:	Street T	ype:			Grade: 0			La	nes: 0		
Section	Comments:											
Work 1	Date: 1/1/1957	W	ork Type:	BUILT			Cod	e: IMPORTED	)	Is Major M&	R: True	
Work 1	<b>Date:</b> 1/1/1979	W	ork Type:	OVERLAY			Cod	e: IMPORTED	)	Is Major M&	R: True	
Work 1	Date: 1/1/2003	W	ork Type:	Overlay - AC St	ructural		Cod	e: OL-AS		Is Major M&	R: True	
Work 1	<b>Date:</b> 11/1/2021	W	ork Type:	Mill and Overla	y		Cod	e: ML-OVL		Is Major M&	R: True	
Last Ir	rsp. Date: 7/29/20	010	т	otalSamples:	0		Surveyed:	2				
	13p. Date. 1/27/20	019	1	otaisampies.	9		Sui reyeu.	2				
Condit			1	_		* Pre-Constru	action PCI ***	_				
Condit			1	_		* Pre-Constru		2				
Condit Inspec	ions: PCI: 5			NO				PCI:	41			
Condit Inspec	ions: PCI: 5	0		NO	)TE: **		action PCI ***		41			
Condit Inspec Sample Sample	tion Comments: e Number: 301	Тур		NO	)TE: **		action PCI ***		41			
Condit Inspec Sample Sample	tions: PCI: 5 tion Comments: e Number: 301 e Comments:	Тур	pe: R	10.00 8.00	Area: SqFt SqFt		action PCI ***		41			
Condit Inspec Sample Sample 41 42	tions: PCI: 5 tion Comments: e Number: 301 e Comments: ALLIGATOR CR	Тур	pe: R  L  N  L	10.00	Area: SqFt SqFt		action PCI ***		41			
Condit Inspec Sample Sample 41 42 43 48	ions: PCI: 5 tion Comments: e Number: 301 e Comments: ALLIGATOR CR BLEEDING BLOCK CR L & T CR	Тур	pe: R  L  N  L  L	10.00 8.00 660.00 574.00	Area: SqFt SqFt SqFt SqFt Ft		action PCI ***		41			
Condit Inspec Sample 41 42 43 48 52	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING	Тур	pe: R  L  N  L  L  L	10.00 8.00 660.00 574.00 825.00	Area:  SqFt SqFt SqFt Ft SqFt SqFt		action PCI ***		41			
Condit Inspec Sample Sample 41 42 43 48 52 53	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING	Тур	pe: R  L  N  L  L  L  L	10.00 8.00 660.00 574.00 825.00 237.00	SqFt SqFt SqFt Ft SqFt SqFt SqFt SqFt		action PCI ***		41			
Condit Inspec Sample 41 42 43 48 52 53 57	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING	Тур	pe: R  L  N  L  L  L  L  L	10.00 8.00 660.00 574.00 825.00 237.00 1238.00	SqFt SqFt SqFt SqFt Ft SqFt SqFt SqFt Sq		action PCI ***		41			
Condit Inspec Sample 41 42 43 48 52 53 57	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING	Тур	pe: R  L  N  L  L  L  L	10.00 8.00 660.00 574.00 825.00 237.00	SqFt SqFt SqFt SqFt Ft SqFt SqFt SqFt Sq	412:	5.00 SqFt		41			
Condit Inspec Sample 41 42 43 48 52 53 57 57 Sample	ions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING e Number: 600	Тур	pe: R L N L L L L L M	10.00 8.00 660.00 574.00 825.00 237.00 1238.00 2062.00	SqFt SqFt SqFt SqFt Ft SqFt SqFt SqFt Sq	412:	action PCI ***					
Conditions	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING	Тур	pe: R L N L L L L L M	10.00 8.00 660.00 574.00 825.00 237.00 1238.00 2062.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	412:	5.00 SqFt	PCI:				
Condit Inspec Sample 41 42 43 48 52 53 57 57 Sample Sample	ions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING e Number: 600	Тур	pe: R L N L L L L L M	10.00 8.00 660.00 574.00 825.00 237.00 1238.00 2062.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	412:	5.00 SqFt	PCI:				
Condit Inspect Sample 41 42 43 48 52 53 57 57 Sample 42	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING e Number: 600 e Comments:	Тур	pe: R L N L L L L L R Pe: R	10.00 8.00 660.00 574.00 825.00 237.00 1238.00 2062.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	412:	5.00 SqFt	PCI:				
Condit Inspec Sample 41 42 43 48 52 53 57 57 Sample 42 45	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING the Number: 600 e Comments:  BLEEDING	Тур	pe: R L N L L L L L R N N N	10.00 8.00 660.00 574.00 825.00 237.00 1238.00 2062.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	412:	5.00 SqFt	PCI:				
Condit Inspec Sample 41 42 43 48 52 53 57 57 Sample 42 45 48	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING TO Number: 600 e Comments:  BLEEDING DEPRESSION	Тур	pe: R  L N L L L L L R N N L L L L L L L L L	10.00 8.00 660.00 574.00 825.00 237.00 1238.00 2062.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	412:	5.00 SqFt	PCI:				
Condit Inspec Sample 41 42 43 48 52 53 57 57 Sample 42 45 48 52	tions: PCI: 5 tion Comments: e Number: 301 e Comments:  ALLIGATOR CR BLEEDING BLOCK CR L & T CR RAVELING RUTTING WEATHERING WEATHERING e Number: 600 e Comments:  BLEEDING DEPRESSION L & T CR	Тур	pe: R  L N L L L L L R N N L L L L L L L L L	10.00 8.00 660.00 574.00 825.00 237.00 1238.00 2062.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	412:	5.00 SqFt	PCI:				

Netwo	ork:	EYW						Nam	ne:	KEY	WEST IN	ITERN.	ATIONAL	AIRPOR	T				
Branc	·h·	TW B1			N:	ame:	TAXI	WAY B	1		Use	· TA	XIWAY	Ar	ea:		7,765	SaFt	
				C 1	114				1					Ai	ca.				11/1/2021
Sectio		15	-	of 1			rom:	-					To: -						11/1/2021
Surfa		AC .	Fam	-		3-PR-TW	-AC	Zon					Category:				Kan	k: P	
Area:			7,765 SqF			ength:	_	96 F			Width:		60 F	t		_			_
Slabs:				) Length:			Ft		Slab Wi				Ft			ength:		F	it
Shoul			Stre	eet Type:					Grade:	0					Lanes	: 0			
Sectio	on Com	ments:																	
Work	Date:	1/1/2003		Work	Тур	e: New (	Constructi	on - Initi	al			Code:	NU-IN		Is	Major I	M&R:	True	
Work	Date:	1/1/2015		Work	Тур	e: Surfac	ce Treatm	ent - Sea	l Coat			Code:	ST-SC		Is	Major I	M&R:	False	
Work	Date:	11/1/202	1	Work	Тур	e: Comp	lete Reco	nstructio	n - AC			Code:	CR-AC		Is	Major I	M&R:	True	
Last I	nsp. D	ate: 7/29	9/2019			TotalSa	mples:	35			Surve	yed: 6	5						
Condi	itions:	PCI:	55				NO	OTE: **	* Pre-Co	nstru	ction PCI	***							
Inspec	ction C	Comments	:																
Samp	le Num	nber: 10	2	Type:		R		Area:		4464	.00 SqFt		PCI:	39					
_		ments:		7.							1								
41		GATOR (	~R		L		33 00	SqFt											
41		GATOR C EDING	~I <b>\</b>		L N			SqFt SqFt											
45	DEPR	RESSION			L		144.00	SqFt											
48	L & T				L		356.00												
52		ELING			L		446.00	-											
52 53	RAVI RUT	ELING TING			M L		446.00 410.00	-											
		11NG 1 <b>ber:</b> 10	8	Type:	L	R		Area:		4225	.00 SqFt		PCI:	61					
_		ments:	O .	1 ype.		K	•	u va.		7443	.oo sqrt		101:	01					
_																			
42		EDING			N			SqFt											
48 50	L&T				L		159.00												
50 52		CHING ELING			L L		450.00 500.00												
53	RUT				L			SqFt											
57		THERING	Ĵ		L		755.00												
57		THERING			M		2520.00												
Samp	le Num	iber: 11	8	Type:		R		Area:		4225	.00 SqFt		PCI:	70					
Samp	le Com	nments:																	
42		EDING			N			SqFt											
48	L&T				L		231.00												
52 57		ELING THERING	÷		L L		423.00 845.00	-											
57		THERING			M		2957.00												
		iber: 40		Type:		R		Area:		6939	.00 SqFt		PCI:	51					
_		ments:		**							1								
41	ALLI	GATOR (	CR		L		20.00	SqFt											
42		EDING			N			SqFt											
45		RESSION			L		3.00	SqFt											
48	L & T				L		193.00												
50		CHING			L			SqFt											
52 52		ELING ELING			L M		2082.00 1388.00	-											
		iber: 41	4	Type:	-14	R		Area:		5000	0.00 SqFt		PCI:	55					
_		ments:	•	- ypc.			•			2000	.oo bqi t		101.	55					
48	L & T	ΓCR			L		72.00	Ft											
49		SPILLAGI	Ξ		N			SqFt											
52		ELING			L		3750.00	-											
52		ELING			M		1250.00												

Samp	ole Number: 501	Type:	R	A	rea:	5000.00 SqFt	PCI:	56
Samp	ole Comments:							
48	L & T CR	L		58.00	Ft			
49	OIL SPILLAGE	N	Ī	10.00	SqFt			
52	RAVELING	L		3750.00	SqFt			
52	RAVELING	N	1	1250.00	SqFt			

Network: E	YW		Name:	KEY WEST IN	ΓERNATIONAL AI	IRPORT		
Branch: TV	W B10	Name:	TAXIWAY B10	Use:	TAXIWAY	Area:	8,893 SqFt	
Section: 260	of	` 1 <b>F</b>	rom: -		То: -		Last Const.: 1	1/1/202
Surface: AC	Family:	CA653-PR-TW	-AC Zone:		Category:		Rank: P	
Area:	8,893 SqFt	Length:	109 Ft	Width:	60 Ft			
Slabs: 30	Slab Len	gth:	25 Ft SI:	ab Width:	12 Ft	Joint Length:	638 Ft	
Shoulder:	Street Ty	pe:	G	rade: 0		Lanes: 0		
Section Commer	nts:							
Work Date: 1/1	/2003 <b>W</b> o	ork Type: New 0	Construction - AC	(	Code: NC-AC	Is Major	M&R: True	
Work Date: 1/1	/2014 <b>W</b> o	ork Type: Comp	lete Reconstruction -	PCC (	Code: CR-PC	Is Major	M&R: True	
Work Date: 11/	1/2021 <b>W</b> o	ork Type: Comp	lete Reconstruction -	AC (	Code: CR-AC	Is Major	M&R: True	
Last Insp. Date:	7/29/2019	TotalSa	mples: 1	Survey	ed: 1			
Conditions: P	PCI: 61		NOTE: *** P	re-Construction PCI *	**			
Inspection Com	ments:							
Sample Number	: 401 <b>Typ</b>	e: R	Area:	6.00 Slabs	PCI:	61		
Sample Comme	nts:							
62 CORNER	BREAK	L	1.00 Slabs					
65 JT SEAL	DMG	H	6.00 Slabs					
67 LARGE F	PATCH	L	2.00 Slabs					
74 JOINT SE	PALL	L	1.00 Slabs					
74 JOINT SE		M	1.00 Slabs					

Network: EYW		Name:	KEY WEST INT	ERNATIONAL AIF	RPORT	
Branch: TW B11	Name:	TAXIWAY B11	Use:	TAXIWAY	Area:	8,816 SqFt
Section: 265	of 2	From: -		То: -		Last Const.: 11/1/202
Surface: AC F	Camily: CA653-PR-T	W-AC Zone:		Category:		Rank: P
Area: 5,749	SqFt Length	220 Ft	Width:	30 Ft		
Slabs:	Slab Length:	Ft Slat	Width:	Ft	Joint Length:	Ft
Shoulder:	Street Type:	Gra	<b>de:</b> 0		Lanes: 0	
Section Comments:						
Work Date: 1/1/2003	Work Type: New	w Construction - Initial	C	ode: NU-IN	Is Major I	M&R: True
Work Date: 11/1/2021	Work Type: Con	mplete Reconstruction - A	.C C	ode: CR-AC	Is Major I	M&R: True
Last Insp. Date: 7/29/2019	Total	Samples: 1	Surveye	<b>d:</b> 1		
	Total	_	Surveye e-Construction PCI **			
Conditions: PCI: 43	Total	_	•			
Conditions: PCI: 43 Inspection Comments:	Total  Type: R	_	•		3	
Conditions: PCI: 43 Inspection Comments: Sample Number: 500		NOTE: *** Pre	e-Construction PCI *	**	3	
Conditions: PCI: 43 Inspection Comments: Sample Number: 500 Sample Comments:	Type: R	NOTE: *** Pro	e-Construction PCI *	**	3	
Conditions: PCI: 43 Inspection Comments: Sample Number: 500 Sample Comments: 42 BLEEDING		NOTE: *** Pre	e-Construction PCI *	**	3	
Conditions: PCI: 43 Inspection Comments: Sample Number: 500 Sample Comments: 42 BLEEDING 45 DEPRESSION	Type: R	NOTE: *** Pro  Area:  70.00 SqFt	e-Construction PCI *	**	3	
Conditions: PCI: 43 Inspection Comments: Sample Number: 500 Sample Comments: 42 BLEEDING 45 DEPRESSION 48 L & T CR	Type: R  N L	NOTE: *** Pro  Area:  70.00 SqFt 232.00 SqFt	e-Construction PCI *	**	3	
Inspection Comments: Sample Number: 500 Sample Comments: 42 BLEEDING 45 DEPRESSION 48 L & T CR	Type: R  N L L	NOTE: *** Pro  Area:  70.00 SqFt 232.00 SqFt 235.00 Ft	e-Construction PCI *	**	3	
Conditions: PCI: 43 Inspection Comments: Sample Number: 500 Sample Comments: 42 BLEEDING 45 DEPRESSION 48 L & T CR 50 PATCHING	Type: R  N L L L	NOTE: *** Pro  Area:  70.00 SqFt 232.00 SqFt 235.00 Ft 620.00 SqFt	e-Construction PCI *	**	3	

Network:	EYW				Name	: KEY	WEST INT	TERNA	ATIONAL AIF	RPORT		
Branch:	TW B11		Name:	TAXIV	VAY B1	1	Use:	TA	XIWAY	Area:	8,816 SqFt	
Section:	267	C	of 2	From: -				-	То: -		Last Const.:	10/1/2018
Surface:	PCC	Family:	CA653-PR-	RW-TW-PCC	Zone:			•	Category:		Rank: P	
Area:		3,067 SqFt	Lengt	h:	100 Ft		Width:		33 Ft			
Slabs:	14	Slab Le	ngth:	15 Ft	5	Slab Width:		15 1	Ft	Joint Length:	307 F	t
Shoulder:		Street T	ype:		(	Grade: 0				Lanes: 0		
Section Co	omments:											
Work Dat	te: 1/1/2003	W	ork Type: No	ew Constructio	n - Initia	1	C	ode:	NU-IN	Is Major	M&R: True	
Work Dat	te: 10/1/2018	3 <b>W</b>	ork Type: Co	omplete Recons	struction	- PCC	C	ode:	CR-PC	Is Major	M&R: True	
Work Dat	te: 11/1/2021	W	ork Type: Pa	tching - PCC			C	ode:	PA-PC	Is Major	M&R: False	
Last Insp.	<b>Date:</b> 10/1	0/2022	Tota	alSamples:	[		Surveye	e <b>d:</b> 1				
Condition	s: PCI:	91										
Inspection	Comments:											
Sample N	umber: 201	l Ty	pe: R	A	rea:	18	3.00 Slabs		PCI: 9	1		
Sample Co	omments:											
65 JT	SEAL DMG		M	18.00	Slabs							
	INT SPALL		L		Slabs							

		Name:	KEY WEST INT	ERNATIONAL AIRI	PORT
Branch: TW B12	Name:	TAXIWAY B12	Use:	TAXIWAY	<b>Area:</b> 11,359 SqFt
Section: 270	of 1	From: -		То: -	Last Const.: 11/1/2021
Surface: AC	Family: CA653-PR-T	W-AC Zone:		Category:	Rank: P
Area: 11	,359 SqFt Length:	240 Ft	Width:	100 Ft	
Slabs:	Slab Length:	Ft Slab	Width:	Ft	Joint Length: Ft
Shoulder:	Street Type:	Grad	<b>le:</b> 0		Lanes: 0
Section Comments:					
Work Date: 1/1/1957	Work Type: BU	LT	C	ode: IMPORTED	Is Major M&R: True
<b>Work Date:</b> 1/1/1979	Work Type: OV	ERLAY	C	ode: IMPORTED	Is Major M&R: True
Work Date: 1/1/2003	Work Type: Ove	rlay - AC Structural	C	ode: OL-AS	Is Major M&R: True
Work Date: 11/1/2021	Work Type: Con	nplete Reconstruction - AC	C C	ode: CR-AC	Is Major M&R: True
Last Insp. Date: 7/29/20	019 Totals	Samples: 9	Surveye	ed: 2	
Conditions: PCI: 5	0	NOTE: *** Pre-	Construction PCI **	b sk	
<b>Inspection Comments:</b>					
Sample Number: 301	Type: R	Area:	4125.00 SqFt	<b>PCI:</b> 41	
Sample Comments:					
-	L	10.00 SqFt			
41 ALLIGATOR CR	L N	8.00 SqFt			
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR	N L	8.00 SqFt 660.00 SqFt			
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR	N L L	8.00 SqFt 660.00 SqFt 574.00 Ft			
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING	N L L L	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt			
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING	N L L L	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt			
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING	N L L L L	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt			
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING	N L L L L M	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt			
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 Sample Number: 600	N L L L L	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt	6501.00 SqFt	PCI: 55	
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 Sample Number: 600	N L L L L M	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt 2062.00 SqFt	6501.00 SqFt	PCI: 55	
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 Sample Number: 600 50 Sample Comments:	N L L L L M	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt 2062.00 SqFt	6501.00 SqFt	<b>PCI:</b> 55	
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 Sample Number: 600 50 Sample Comments:	N L L L L M Type: R	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt 2062.00 SqFt  Area:	6501.00 SqFt	PCI: 55	
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 WEATHERING 50 Sample Comments: 42 BLEEDING 45 DEPRESSION	N L L L L L M Type: R	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt 2062.00 SqFt  Area:	6501.00 SqFt	PCI: 55	
42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 Sample Number: 600 50 Sample Comments: 42 BLEEDING 45 DEPRESSION	N L L L L L M Type: R	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt 2062.00 SqFt  Area:  73.00 SqFt 105.00 SqFt	6501.00 SqFt	PCI: 55	
41 ALLIGATOR CR 42 BLEEDING 43 BLOCK CR 48 L & T CR 52 RAVELING 53 RUTTING 57 WEATHERING 57 WEATHERING 58 WEATHERING 59 WEATHERING 50 Sample Comments: 42 BLEEDING 45 DEPRESSION 48 L & T CR	N L L L M N R N R N R N R N L L L L L L L L R N L L L L	8.00 SqFt 660.00 SqFt 574.00 Ft 825.00 SqFt 237.00 SqFt 1238.00 SqFt 2062.00 SqFt  Area:  73.00 SqFt 105.00 SqFt 726.00 Ft	6501.00 SqFt	PCI: 55	

Netwo	ork:	EYW						Nam	ne:	KEY	WEST IN	NTERN	ATIONAL	AIRPOR	RT				
Branc	·h·	TW B2			N:	ame:	TAXI	WAY B	2		Use		XIWAY		rea:		3 779	) SqFt	
				C 1	114									Ai	ıca.				11/1/2021
Sectio		20	-	of 1			rom:	-					To: -						11/1/2021
Surfac		.C	Fam	-		B-PR-TW-	-AC	Zon					Category:				Kan	ık: P	
Area:			3,779 SqF			ength:	_	55 F			Width:		60 H	t				_	_
Slabs:				) Length:			Ft		Slab Wio				Ft			Length	:	l	-?t
Shoul			Stre	eet Type:					Grade:	0					Lane	<b>s:</b> 0			
Sectio	n Com	ments:																	
Work	Date:	1/1/2003		Work	Тур	e: New C	Constructi	on - Initi	ial			Code:	NU-IN		I	s Major	M&R:	True	
Work	Date:	1/1/2015		Work	Тур	e: Surfac	e Treatm	ent - Sea	l Coat			Code:	ST-SC		I	s Major	M&R:	False	
Work	Date:	11/1/202	1	Work	Тур	e: Comp	lete Reco	nstructio	n - AC			Code:	CR-AC		I	s Major	M&R:	True	
Last I	nsp. D	ate: 7/29	9/2019			TotalSa	mples:	35			Surve	yed: 6	5						
Condi	itions:	PCI:	55				NO	OTE: **	* Pre-Co	ıstru	ction PCI	***							
Inspec	ction C	omments	:																
Samp	le Num	ber: 10	2	Type:		R		Area:		4464	.00 SqFt		PCI:	39					
_		ments:		7.							1								
41		GATOR (	~R		L		33 00	SqFt											
42		GATOR C EDING	~I <b>\</b>		L N			SqFt SqFt											
45	DEPR	RESSION			L		144.00	SqFt											
48	L & T				L		356.00												
52		ELING			L		446.00	-											
52 52		ELING			M		446.00	-											
53	RUT		0	т	L	D	410.00			1225	00 G Ft		DCI.	<i>C</i> 1					
_		ber: 10	8	Type:		R	1	Area:		4225	.00 SqFt		PCI:	61					
Samp	le Com	ments:																	
42	BLEE	EDING			N		3.00	SqFt											
48	L & T				L		159.00												
50		CHING			L		450.00												
52		ELING			L		500.00	-											
53 57	RUTT		7		L L			SqFt											
57		THERING THERING			M		755.00 2520.00												
		ber: 11		Type:		R		Area:		4225	.00 SqFt		PCI:	70					
-		ments:	o	турс.		K	•	Aica.		7223	.00 Sq1 t		101.	70					
42	BLEE	EDING			N		2.00	SqFt											
48	L & T				L		231.00												
52		ELING			L		423.00	-											
57		THERING			L		845.00												
57		THERING			M	D.	2957.00			6025	.00 0 5		<b>*</b> ~~						
_		ber: 40	5	Type:		R	1	Area:		6939	.00 SqFt		PCI:	51					
-			S.D.				• • • •	a =											
41		GATOR (	CR		L			SqFt											
42		EDING			N			SqFt SqFt											
45 48	L & T	RESSION			L L		3.00 193.00	SqFt Ft											
50		CHING			L			SqFt											
52		ELING			L		2082.00												
52		ELING			M		1388.00	-											
Samp	le Num	ber: 41	4	Type:		R		Area:		5000	.00 SqFt		PCI:	55					
_		ments:									-								
48	L & T	CR			L		72.00	Ft											
49		PILLAGI	Ξ		N			SqFt											
52		ELING			L		3750.00												
52	RAVI	ELING			M		1250.00	SqFt											

Samp	ole Number: 501	Type:	R	A	rea:	5000.00 SqFt	PCI:	56
Samp	ole Comments:							
48	L & T CR	L		58.00	Ft			
49	OIL SPILLAGE	N	ſ	10.00	SqFt			
52	RAVELING	L		3750.00	SqFt			
52	RAVELING	M	1	1250.00	SqFt			

Netwo	rk:	EYW						Nam	ne:	KEY	WEST IN	NTERN	ATIONAL	AIRPOR	T				
Branc	h•	TW B3			N:	ame:	TAXI	WAY B	3		Use		XIWAY		·ea:		3,864	SaFt	
				C 1	110									Al	· Ca·				11/1/2021
Sectio		25		of 1			rom:	-					To: -						11/1/2021
Surfac		.C	Fami	-		3-PR-TW	-AC	Zono			****		Category:				Kan	k: P	
Area:			3,864 SqF			ength:	_	55 F			Width:		60 F	t		_		_	_
Slabs:				) Length:			Ft		Slab Wi				Ft			ength:		ŀ	<sup>7</sup> t
Should			Stre	et Type:					Grade:	0					Lanes	0			
Sectio	n Com	ments:																	
Work	Date:	1/1/2003		Work	Тур	e: New (	Constructi	on - Initi	al			Code:	NU-IN		Is	Major I	M&R:	True	
Work	Date:	1/1/2015		Work	Тур	e: Surfac	ce Treatm	ent - Sea	l Coat			Code:	ST-SC		Is	Major I	M&R:	False	
Work	Date:	11/1/202	1	Work	Тур	e: Comp	olete Reco	nstructio	n - AC			Code:	CR-AC		Is	Major I	M&R:	True	
Last I	nsp. Da	ate: 7/29	9/2019			TotalSa	mples:	35			Surve	yed: (	5						
Condi	tions:	PCI:	55				NO	OTE: **	* Pre-Co	nstru	ction PCI	***							
Inspec	ction C	omments	:																
Sampl	le Num	ber: 10	2	Type:		R		Area:		4464	.00 SqFt		PCI:	39					
_		ments:		. =							•								
41		GATOR (	CR		L		33.00	SqFt											
42		DING	-11		N			SqFt											
45		ESSION			L		144.00	SqFt											
48	L&T				L		356.00												
52		ELING ELING			L M		446.00	-											
52 53	RUTT				L		446.00 410.00	-											
		ber: 10	8	Type:		R		Area:		4225	5.00 SqFt		PCI:	61					
_		ments:		- J P							1- :			-					
_							• • •	~ -											
42 48	BLEE L & T	DING			N L		3.00 159.00	SqFt											
50		CK CHING			L		450.00												
52		ELING			L		500.00												
53	RUTT				L			SqFt											
57	WEA	THERING	j		L		755.00	SqFt											
57		THERING			M		2520.00	SqFt											
Sampl	le Num	ber: 11	8	Type:		R	1	Area:		4225	5.00 SqFt		PCI:	70					
Sampl	le Com	ments:																	
42		DING			N			SqFt											
48	L & T				L		231.00												
52		ELING			L		423.00	-											
57 57		THERINO THERINO			L M		845.00 2957.00												
		ber: 40		Type:	171	R		Area:		6030	0.00 SqFt		PCI:	51					
_		ments:	~	rype.		K	1	. x1 va.		0/37	.oo bqrt		101.	J 1					
41		GATOR (	TP.		L		20.00	SqFt											
42		DING	-1 <b>\</b>		N			SqFt SqFt											
45		ESSION			L			SqFt											
48	L & T				L		193.00												
50	PATO	CHING			L		9.00	SqFt											
52		ELING			L		2082.00	-											
52		ELING			M		1388.00												
_		ber: 41	4	Type:		R	1	Area:		5000	0.00 SqFt		PCI:	55					
Sampl	le Com	ments:																	
48	L & T				L		72.00												
49		PILLAGI	Ξ		N			SqFt											
52 52		ELING			L		3750.00												
52	KAVI	ELING			M		1250.00	sqrt											

Samp	ole Number: 501	Type:	R	A	rea:	5000.00 SqFt	PCI:	56
Samp	ole Comments:							
48	L & T CR	L		58.00	Ft			
49	OIL SPILLAGE	N	ſ	10.00	SqFt			
52	RAVELING	L		3750.00	SqFt			
52	RAVELING	M	1	1250.00	SqFt			

Netwo	ork: EYW			Name:	KEY WEST INTE	RNATIONAL A	IRPORT	
Branc			Name:		Use:	TAXIWAY	Area:	3,864 SqFt
Section		of 1	1100	From: -		To: -		Last Const.: 11/1/2021
Surfac			653-PR	-TW-AC Zone:		Category:		Rank: P
Area:		4 SqFt	Lengt		Width:	60 Ft		Nauk. 1
		_	Lenge				Ioint I or	4L . E4
Slabs:		Slab Length:				Ft	Joint Len	
Should		Street Type:		Grade:	0		Lanes:	0
Section	on Comments:							
Work	<b>Date:</b> 1/1/2003	Work T	ype: N	New Construction - Initial		de: NU-IN	Is Ma	ajor M&R: True
	<b>Date:</b> 1/1/2015			Surface Treatment - Seal Coat		de: ST-SC		ajor M&R: False
	<b>Date:</b> 11/1/2021			Complete Reconstruction - AC		de: CR-AC	Is Ma	ajor M&R: True
	Insp. Date: 7/29/2019		Tot	talSamples: 35	Surveyed			
	itions: PCI: 55			NOTE: *** Pre-Co	nstruction PCI ***	r		
Inspec	ction Comments:							
Sampl	le Number: 102	Type:	R	Area:	4464.00 SqFt	PCI:	39	
Sampl	le Comments:							
41	ALLIGATOR CR	I	Ĺ	33.00 SqFt				
42	BLEEDING		N	89.00 SqFt				
45	DEPRESSION	L		144.00 SqFt				
48	L & T CR	L		356.00 Ft				
52 52	RAVELING RAVELING	L	L M	446.00 SqFt 446.00 SqFt				
52 53	RAVELING RUTTING		M L	446.00 SqFt 410.00 SqFt				
	le Number: 108	Type:	R	Area:	4225.00 SqFt	PCI:	<u></u>	
_	le Comments:	- J F	-	<del></del>	1220.00 - 1		01	
42	BLEEDING	N	.N	3.00 SqFt				
48	L & T CR	L		159.00 Ft				
50	PATCHING	L		450.00 SqFt				
52 53	RAVELING	I		500.00 SqFt				
53 57	RUTTING WEATHERING	I I	L L	70.00 SqFt 755.00 SqFt				
57	WEATHERING		M	2520.00 SqFt				
	le Number: 118	Туре:	R	Area:	4225.00 SqFt	PCI:	70	
_	le Comments:	· -					, ,	
42	BLEEDING	1	N	2.00 SqFt				
48	L & T CR	L	L	231.00 Ft				
52	RAVELING	I		423.00 SqFt				
57 57	WEATHERING	L		845.00 SqFt				
57 Sampl	WEATHERING le Number: 405		M R	2957.00 SqFt	coan on galit	DCI.	~1	
-	le Number: 405 le Comments:	Туре:	R	Area:	6939.00 SqFt	PCI:	51	
41	ALLIGATOR CR	I	ſ	20.00 SqFt				
42	BLEEDING		N	45.00 SqFt				
45	DEPRESSION	L		3.00 SqFt				
48	L & T CR	L		193.00 Ft				
50	PATCHING	L		9.00 SqFt				
52 52	RAVELING RAVELING	L	L M	2082.00 SqFt 1388.00 SqFt				
	le Number: 414		R	Area:	5000.00 SqFt	PCI:	55	
_	le Comments:	Туре:	K	Al Ca.	5000.00 Sq1 t	101.	33	
48	L & T CR	I	ı	72.00 Ft				
49	OIL SPILLAGE		N	43.00 SqFt				
52	RAVELING		L	3750.00 SqFt				
52	RAVELING	1	M	1250.00 SqFt				

Samp	ole Number: 501	Type:	R	A	rea:	5000.00 SqFt	PCI:	56
Samp	ole Comments:							
48	L & T CR	L		58.00	Ft			
49	OIL SPILLAGE	N	ſ	10.00	SqFt			
52	RAVELING	L		3750.00	SqFt			
52	RAVELING	M	1	1250.00	SqFt			

Netw	ork: EV	YW				Name:	KEY WEST	INTER	NATIONAL A	AIRPORT			
Bran		W B5		Name:	TAXIWA		Us		AXIWAY	Area:	7.1	25 SqFt	
		. ВЗ	C 1	rvaine.		41 D3	- Os	. 1		Aica.		•	11/1/2021
Section			of 1		From: -				To: -				11/1/2021
Surfa	ce: AC		Family: CA	.653-PR-T	W-AC	Zone:			Category:		Ra	ınk: P	
Area		7,1	25 SqFt	Length	:	252 Ft	Width:		60 Ft				
Slabs	:		Slab Length:		Ft	Slab W	idth:		Ft	Joint	Length:	F	t
Shou	der:		Street Type:			Grade:	0			Lane	es: 0		
Section	on Commen	ıts:											
Worl	<b>Date:</b> 1/1	/2006	Work '	Type: Nev	w Construction	- AC		Code	: NC-AC	I	s Major M&F	R: True	
Worl	<b>Date:</b> 11/	1/2021	Work '	Type: Cor	nplete Reconst	ruction - AC		Code	: CR-AC	1	s Major M&F	R: True	
Last	Insp. Date:	7/29/201	9	Total	Samples: 11		Surv	eyed:	2				
Cond	itions: P	<b>PCI:</b> 58			NOT	E: *** Pre-Co	onstruction PC	I ***					
Inspe	ction Com	nents:											
Samp	le Number	: 505	Type:	R	Arc	ea:	5500.00 SqFt		PCI:	60			
Samp	le Commer	ıts:											
45	DEPRESS	SION		L	141.00 S	qFt							
45	DEPRESS	SION		M	27.00 S	qFt							
48	L & T CR			L	79.00 F								
49	OIL SPIL			N	83.00 S	-							
52	RAVELIN	٧G		L	1375.00 S	qFt							
57	WEATHE	ERING		L	4125.00 S	qFt							
Samp	le Number	: 603	Type:	R	Arc	ea:	5800.00 SqFt		PCI:	55			
Samp	le Commer	its:											
48	L & T CR	_		L	104.00 F	t							
	PATCHIN	١G		L	900.00 S	qFt							
50				_		-							
50 52	RAVELIN	٧G		L	1225.00 S	qFt							
	RAVELING RUTTING			L L	1225.00 S 337.00 S	•							

Brancl	ork: EYW				Name	: KEY	Y WEST INT	ERNAT	ONAL AI	RPORT			
	h: TW B6		Name:	TAXIV	WAY B6		Use:	TAXI	WAY	Area:		6,842 SqFt	
Section	n: 240	of	1	From:	-			To	-			Last Const.	: 11/1/202
Surfac	ce: AAC		CA653-PR-TV APC	V-AAC-	Zone:			Ca	tegory:			Rank: P	
Area:		6,842 SqFt	Length:		210 Ft		Width:		60 Ft				
Slabs:		Slab Lengt	h:	Ft	9	Slab Width:		Ft		J	Joint Length:	]	₹t
Should	der:	Street Typ	e:		(	Grade: 0				I	Lanes: 0		
Section	n Comments:												
Work !	<b>Date:</b> 1/1/1977	Wor	k Type: BUII	LT			Co	ode: IN	1PORTED		Is Major M	I&R: True	
Work	<b>Date:</b> 1/1/1989	Wor	k Type: Surfa	nce Treatme	nt - Seal	Coat	Co	ode: S	Γ-SC		Is Major M	<b>1&amp;R:</b> False	
Work	<b>Date:</b> 1/1/2003	Wor	k Type: Over	lay - AC St	ructural		Co	ode: O	L-AS		Is Major M	I&R: True	
Work	<b>Date:</b> 1/1/2005	Wor	k Type: Mill	and Overlay	7		Co	ode: M	L-OVL		Is Major M	I&R: True	
Work	<b>Date:</b> 11/1/2021	Wor	k Type: Mill	and Overlay	ī		Co	ode: M	L-OVL		Is Major M	I&R: True	
Last Ir	nsp. Date: 7/29	/2019	TotalS	amples:	12		Surveye	<b>d:</b> 2					
Condit	tions: PCI:	58		NO	TE: ***	Pre-Constru	ction PCI **	**					
Inspec	ction Comments:												
Sampl	e Number: 316	Туре:	R	A	rea:	3848	3.00 SqFt		PCI: 6	52			
Sample	e Comments:												
15	DEPRESSION		L	9.00	SqFt								
48	L & T CR		L	306.00	Ft								
	RAVELING		L										
52	KAVELING		L	385.00	SqFt								
	RUTTING		L L	385.00 56.00	-								
53					SqFt								
53 57	RUTTING		L	56.00	SqFt SqFt								
53 57 57	RUTTING WEATHERING		L L M	56.00 577.00 2886.00	SqFt SqFt	5718	3.00 SqFt		PCI: 2	29			
53 57 57 Sample	RUTTING WEATHERING WEATHERING		L L M	56.00 577.00 2886.00	SqFt SqFt SqFt	5718	3.00 SqFt		PCI: 2	29			
53 57 57 Sample Sample	RUTTING WEATHERING WEATHERING Re Number: 816	Туре:	L L M	56.00 577.00 2886.00	SqFt SqFt SqFt	5718	3.00 SqFt		PCI: 2	29			
53 57 57 Sample Sample	RUTTING WEATHERING WEATHERING RENUMBER: 816 RECOMMENTS: ALLIGATOR C	Туре:	L L M	56.00 577.00 2886.00 A	SqFt SqFt SqFt rea:	5718	3.00 SqFt		PCI: 2	29			
53 57 57 Sample Sample 41	RUTTING WEATHERING WEATHERING RENUMBER: 816 RECOMMENTS: ALLIGATOR C DEPRESSION	Туре:	L L M	56.00 577.00 2886.00 A 39.00 34.00	SqFt SqFt SqFt rea:	5718	3.00 SqFt		PCI: 2	29			
53 57 57 Sample Sample 41 45	RUTTING WEATHERING WEATHERING RE Number: 816 RE Comments: ALLIGATOR C DEPRESSION DEPRESSION	Туре:	L L M	56.00 577.00 2886.00 A 39.00 34.00 279.00	SqFt SqFt SqFt rea: SqFt SqFt SqFt	5718	3.00 SqFt		PCI: 2	29			
53 57 57 Sample Sample 41 45 45	RUTTING WEATHERING WEATHERING RE Number: 816 RE Comments: ALLIGATOR C DEPRESSION DEPRESSION DEPRESSION	Туре:	L L M	56.00 577.00 2886.00 A 39.00 34.00 279.00 28.00	SqFt SqFt rea: SqFt SqFt SqFt SqFt SqFt	5718	3.00 SqFt		PCI: 2	29			
53 57 57 Sample 41 45 45 45	RUTTING WEATHERING WEATHERING RENUMBER: 816 RECOMMENTS: ALLIGATOR CO DEPRESSION DEPRESSION DEPRESSION L&T CR	Туре:	L L M A A L L L M H L	56.00 577.00 2886.00 A 39.00 34.00 279.00 28.00 692.00	SqFt SqFt rea:  SqFt SqFt SqFt SqFt SqFt SqFt Ft	5718	3.00 SqFt		PCI: 2	29			
53 57 57 <b>Sample</b> 41 45 45 45 45 48	RUTTING WEATHERING WEATHERING RENUMBER: 816 RECOMMENTS: ALLIGATOR CO DEPRESSION DEPRESSION DEPRESSION L&T CR PATCHING	Туре:	L L M A A L L M H L M	56.00 577.00 2886.00 A 39.00 34.00 279.00 28.00 692.00 215.00	SqFt SqFt SqFt rea:  SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqF	5718	3.00 SqFt		PCI: 2	29			
53 57 57 <b>Sample</b> 41 45 45 45 48 50 52	RUTTING WEATHERING WEATHERING RENUMBER: 816 RECOMMENTS: ALLIGATOR C DEPRESSION DEPRESSION DEPRESSION L & T CR PATCHING RAVELING	Туре:	L L M A A L L M H L M L	56.00 577.00 2886.00 A 39.00 34.00 279.00 28.00 692.00 215.00 550.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	5718	3.00 SqFt		PCI: 2	29			
53 57 57 <b>Sample</b> 41 45 45 45 45 46 50 52	RUTTING WEATHERING WEATHERING RENUMBER: 816 RECOMMENTS: ALLIGATOR CO DEPRESSION DEPRESSION DEPRESSION L&T CR PATCHING	Type:	L L M A A L L M H L M	56.00 577.00 2886.00 A 39.00 34.00 279.00 28.00 692.00 215.00	SqFt SqFt SqFt SqFt SqFt SqFt SqFt SqFt	5718	3.00 SqFt		PCI: 2	29			

Network:	EYW			Na	me: KE	Y WEST INT	ERNATIONAL AI	RPORT	
Branch:	TW B7		Name:	TAXIWAY	B7	Use:	TAXIWAY	Area:	6,819 SqFt
Section:	245	o	f 1 <b>F</b>	rom: -			То: -		Last Const.: 11/1/2021
Surface:	AC	Family:	CA653-PR-TW	-AC Zo	ne:		Category:		Rank: P
Area:		6,819 SqFt	Length:	135	Ft	Width:	60 Ft		
Slabs:	21	Slab Len	gth:	18 Ft	Slab Width:		18 Ft	Joint Length	705 Ft
Shoulder:		Street Ty	ype:		Grade: 0			Lanes: 0	
Section Co	mments:								
Work Date	: 1/1/2003	W	ork Type: New	Construction - A	2	C	ode: NC-AC	Is Major	M&R: True
Work Date	: 1/1/2014	W	ork Type: Comp	olete Reconstructi	on - PCC	C	ode: CR-PC	Is Major	· M&R: True
Work Date	: 11/1/2021	W	ork Type: Comp	olete Reconstructi	on - AC	C	ode: CR-AC	Is Major	·M&R: True
Last Insp. 1	<b>Date:</b> 7/29	/2019	TotalSa	imples: 1		Surveye	<b>d:</b> 1		
Conditions	: PCI:	88		NOTE: *	** Pre-Constr	uction PCI **	**		
Inspection	Comments:	:							
Sample Nu	mber: 101	l Typ	oe: R	Area:		6.00 Slabs	PCI: 8	38	
Sample Con	mments:								

JT SEAL DMG

H 6.00 Slabs

Network:	EYW				Name:	KE	Y WEST INT	TERNATIONAL A	IRPORT	
Branch:	TW B8		Name:	TAXIW	AY B8		Use:	TAXIWAY	Area:	6,972 SqFt
Section:	250	o	f 1	From: -				То: -		Last Const.: 11/1/2021
Surface:	AC	Family:	CA653-PR-TV	V-AC	Zone:			Category:		Rank: P
Area:		6,972 SqFt	Length:		190 Ft		Width:	60 Ft		
Slabs:	22	Slab Len	igth:	18 Ft	Slab	Width:		18 Ft	Joint Lengt	<b>th:</b> 1,017 Ft
Shoulder:		Street Ty	ype:		Grad	<b>e</b> : 0			Lanes:	0
Section Co	omments:									
Work Date	e: 1/1/2003	W	ork Type: New	Construction	n - AC		C	ode: NC-AC	Is Majo	or M&R: True
Work Date	e: 1/1/2014	W	ork Type: Com	plete Recons	truction - PC	С	C	ode: CR-PC	Is Majo	or M&R: True
Work Date	e: 11/1/2021	W	ork Type: Com	plete Recons	truction - AC	1	C	ode: CR-AC	Is Majo	or M&R: True
Last Insp.	<b>Date:</b> 7/29	/2019	TotalS	amples: 1			Surveye	ed: 1		
Conditions	s: PCI:	88		NOT	ΓΕ: *** Pre-	Constr	uction PCI **	**		
Inspection	Comments									
Sample Nu	ımber: 20	Typ	oe: R	Aı	rea:		6.00 Slabs	PCI:	88	
Sample Co	omments:									

JT SEAL DMG

H 6.00 Slabs

Network:	EYW				Name:	KEY	WEST INTI	ERNAT	TONAL AIF	RPORT			
Branch:	TW B9		Name:	TAXIW	AY B9		Use:	TAXI	IWAY	Area:		8,899 SqFt	
Section:	257	of	2	From: -				To	): -			Last Const.:	10/1/2018
Surface:	PCC	Family:	CA653-PR-R	W-TW-PCC	Zone:			Ca	ategory:			Rank: P	
Area:	3	3,071 SqFt	Length:		105 Ft	•	Width:		30 Ft				
Slabs:	18	Slab Len	gth:	12 Ft	Slab Wi	dth:		14 Ft		Joint	Length:	352 Ft	
Shoulder:		Street Ty	pe:		Grade:	0				Lane	s: 0		
Section Co	omments:												
Work Dat	te: 1/1/2003	Wo	ork Type: New	Construction	ı - AC		Co	de: N	IC-AC	I	s Major	M&R: True	
Work Dat	te: 1/1/2014	Wo	ork Type: Com	plete Recons	truction - PCC		Co	de: C	CR-PC	I	s Major	M&R: True	
Work Dat	te: 10/1/2018	Wo	ork Type: Com	plete Recons	truction - PCC		Co	de: C	CR-PC	I	s Major	M&R: True	
Work Dat	te: 1/1/2021	Wo	ork Type: Patc	hing - PCC			Co	de: P	A-PC	I	s Major	M&R: False	
Last Insp.	<b>Date:</b> 10/10	/2022	Totals	amples: 1			Surveyed	<b>l:</b> 1					
Condition	s: PCI:	73											
Inspection	Comments:												
Sample N	umber: 201	Тур	e: R	A	rea:	18.0	00 Slabs		PCI: 7	3			
Sample C	omments:												
67 LA	RGE PATCH		M	1.00	Slabs								
74 JO	INT SPALL		Н	2.00	Slabs								



FLORIDA DEPARTMENT OF TRANSPORTATION | **AVIATION OFFICE** 

