

2022

*Statewide Airfield Pavement Management Program*



# Airport Pavement Evaluation Report

FMY - Page Field | *District 1*



AVIATION



---

*Florida Department of Transportation*

---

# ***Statewide Airfield Pavement Management Program***

## **Airport Pavement Evaluation Report**

**Prepared by:**

*FDOT Aviation Office  
605 Suwannee Street  
Tallahassee, Florida 32399-0450*

**Website:** [FDOT Aviation Office](#)

**Interactive Web Application:** [FDOT SAPMP Interactive Web Application](#)

# TABLE OF CONTENTS

<b>EXECUTIVE SUMMARY .....</b>	<b>1</b>
<i>Program Background.....</i>	<i>1</i>
<i>Current Pavement Conditions .....</i>	<i>2</i>
<i>Forecasted Pavement Conditions .....</i>	<i>5</i>
<i>Major Rehabilitation Planning 2023-2032 .....</i>	<i>8</i>
<b>CHAPTER 1 – INTRODUCTION.....</b>	<b>12</b>
1.1 Background .....	12
1.2 Stakeholders.....	14
1.3 General Scope of Work .....	14
1.4 FDOT SAPMP Objectives .....	15
<b>CHAPTER 2 – METHODOLOGY.....</b>	<b>18</b>
2.1 Airfield Pavement Database.....	18
2.2 Airfield Pavement Record Keeping (Historical Records Research).....	19
2.3 Airfield Pavement Structure.....	19
2.3.1 Asphalt Concrete.....	20
2.3.2 Portland Cement Concrete .....	20
2.3.3 Composite Structure – Whitetopping Pavement .....	20
2.4 Airfield Pavement Traffic .....	21
2.5 Pavement Management Program Network Definition Terminology .....	21
2.5.1 Pavement Network Identification .....	21
2.5.2 Pavement Branch Identification .....	21
2.5.3 Pavement Section Identification .....	22
2.5.4 Pavement Sample Unit Identification .....	22
2.5.5 Terminology Summary .....	22
2.6 Airfield PCI Survey Methodology .....	22
2.6.1 Pavement Distress Types.....	23
2.6.2 PCI Survey Procedures.....	24
<b>CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY.....</b>	<b>27</b>
3.1 Airfield Pavement Network Information.....	27
3.1.1 Previous and/or Anticipated Airfield Pavement Construction .....	27
3.1.2 Estimated Pavement Age .....	30
3.1.3 Functional Use .....	32
3.1.4 Pavement Surface Type.....	32
3.1.5 Pavement System Inventory Details.....	33
<b>CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS .....</b>	<b>37</b>
4.1 Airfield Pavement Condition Index.....	37
4.1.1 Network-Level Analysis.....	37
4.1.2 Branch-Level Analysis.....	37
4.1.3 Section-Level Analysis .....	41
4.2 Summary of Pavement Condition Evaluation Results .....	46

4.2.1 Network-Level Observations .....	46
4.2.2 Branch-Level Observations .....	46
<b>CHAPTER 5 – SAPMP CUSTOMIZATION.....</b>	<b>57</b>
5.1 Network-Level Customization.....	57
5.2 Pavement Condition Forecasts .....	57
5.2.1 Forecasting PCI Considerations.....	58
5.2.2 Performance Models .....	58
5.2.3 Branch-Level Pavement Condition Forecast.....	58
5.2.4 Section-Level Pavement Condition Forecast.....	59
5.3 Critical PCI Value.....	62
5.4 Localized Maintenance and Repair .....	65
5.4.1 Localized Maintenance and Repair Approach .....	65
5.4.2 Localized Work Types.....	66
5.4.3 Localized Maintenance Planning-Level Unit Costs .....	68
5.4.4 Localized Maintenance and Repair Policy .....	68
5.5 Major Rehabilitation .....	71
5.5.1 Major Rehabilitation Pavement Section Development .....	71
5.5.2 Major Rehabilitation Planning-Level Unit Costs .....	73
<b>CHAPTER 6 – M&amp;R PLANNING AND BUDGET SCENARIO ANALYSIS .....</b>	<b>75</b>
6.1 Localized Maintenance and Repair Analysis and Recommendations .....	75
6.2 Major Rehabilitation Needs.....	78
6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs .....	78
<b>CHAPTER 7 – CONCLUSION.....</b>	<b>84</b>
7.1 Recommendations .....	84
7.1.1 Continued PCI Surveys.....	84
7.1.2 Localized Maintenance and Repair .....	84
7.1.3 Major Rehabilitation.....	84
7.1.4 Pavement Management System.....	84
7.2 Supporting Documents .....	85
Airfield Pavement Network Definition Exhibit.....	85
Airfield Pavement System Inventory Exhibit .....	85
Airfield Pavement Estimated Age Exhibit .....	85
Airfield Pavement Condition Index Exhibit.....	85
Airfield Pavement Major Rehabilitation Exhibit .....	85
Inspection Photograph Documentation.....	85
7.3 Conclusion.....	86
7.4 References.....	86



## **APPENDIX**


*Appendix A: Airfield Pavement Analysis*

*Appendix B: Maintenance and Rehabilitation Planning Needs*

*Appendix C: Technical Exhibits*

*Appendix D: Inspection Photograph Documentation*

*Appendix E: Inspection Distress Details*



## LIST OF TABLES

Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level.....	2
Table E.2: Forecasted PCI Values 2023-2032 – Section-Level.....	5
Table E.3: Major Rehabilitation Planning 2023-2032.....	8
Table 1.2: FDOT SAPMP Stakeholders .....	14
Table 2.5.5: SAPMP Terminology .....	22
Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete .....	23
Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete.....	24
Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete.....	24
Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete .....	25
Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction .....	27
Table 3.1.5: Pavement System Inventory Details .....	33
Table 4.1.2: Current Condition Summary – Branch-Level .....	40
Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level.....	42
Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level .....	59
Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects.....	63
Table 5.3 (b): Critical PCI Values by Branch Use.....	63
Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete .....	68
Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete.....	68
Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy .....	69
Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy .....	70
Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation .....	72
Table 5.5.2: RL Major Rehabilitation Planning-Level Unit Cost by Pavement Type .....	73
Table 6.1 (a): Year 1 Summary of Localized Maintenance .....	75
Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary .....	76
Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary .....	76
Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs .....	79



## LIST OF FIGURES

Figure E.1: PCI Rating .....	1
Figure E.2: Current Condition Summary – Branch-Level .....	2
Figure E.3: 10-Year Major Rehabilitation Needs by Program Year .....	10
Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts .....	13
Figure 1.4: Pavement Life and the Effect of Treatments .....	16
Figure 2: FDOT SAPMP General Process .....	18
Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit .....	28
Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit .....	29
Figure 3.1.2 (a): Age of Pavements at PCI Survey .....	30
Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit .....	31
Figure 3.1.3: Airfield Pavement Branch Use by Area (SF) .....	32
Figure 3.1.4: Airfield Pavement Surface Type by Area (SF) .....	33
Figure 4.1.1: Current Condition – Overall Network .....	37
Figure 4.1.2 (a): Current Condition Summary – Branch-Level .....	37
Figure 4.1.2 (b): Current Condition – Runway .....	38
Figure 4.1.2 (c): Current Condition – Taxiway .....	38
Figure 4.1.2 (d): Current Condition – Apron .....	39
Figure 4.1.3: Airfield Pavement Condition Index Exhibit .....	45
Figure 5.2.3: Forecasted Branch-Level Pavement Performance .....	58
Figure 5.3 (a): Pavement Life and the Effect of Treatments .....	62
Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical } PCI$ .....	64
Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical } PCI$ .....	64
Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year .....	81
Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit .....	82



# Executive Summary





# Executive Summary

## Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Page Field's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section. This is graphically depicted in **Figure E.1**.


*Figure E.1: PCI Rating*

Color	Range	Condition Rating
	86-100	Good
	71-85	Satisfactory
	56-70	Fair
	41-55	Poor
	26-40	Very Poor
	11-25	Serious
	0-10	Failed

## Current Pavement Conditions

In May 2022, approximately 6.2 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Page Field (FMY). In general, airfield pavements at FMY are in Satisfactory condition with an area-weighted PCI of 78. The area-weighted average PCI values of the runways, taxiways, and aprons are 89, 81, and 70, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for FMY.

*Figure E.2: Current Condition Summary – Branch-Level*



*Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
FMY	RW 5-23	Runway	6105	100,000	91	Good
FMY	RW 5-23	Runway	6110	50,000	94	Good
FMY	RW 5-23	Runway	6115	280,000	89	Good
FMY	RW 5-23	Runway	6120	140,000	92	Good
FMY	RW 5-23	Runway	6125	20,000	89	Good
FMY	RW 5-23	Runway	6130	10,000	84	Satisfactory
FMY	RW 5-23	Runway	6135	50,000	87	Good
FMY	RW 5-23	Runway	6140	25,000	82	Satisfactory
FMY	RW 5-23	Runway	6145	155,000	86	Good
FMY	RW 5-23	Runway	6150	77,500	88	Good
FMY	RW 5-23	Runway	6155	35,600	84	Satisfactory
FMY	RW 5-23	Runway	6160	17,800	88	Good
FMY	RW 13-31	Runway	6205	476,075	89	Good
FMY	RW 13-31	Runway	6210	238,038	92	Good
FMY	TW A	Taxiway	103	12,403	94	Good
FMY	TW A	Taxiway	105	51,700	91	Good
FMY	TW A	Taxiway	110	6,623	79	Satisfactory



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
FMY	TW A	Taxiway	111	132,526	93	Good
FMY	TW A	Taxiway	114	73,900	79	Satisfactory
FMY	TW A	Taxiway	115	17,123	64	Fair
FMY	TW A1	Taxiway	123	20,509	94	Good
FMY	TW A2	Taxiway	125	20,237	94	Good
FMY	TW A3	Taxiway	145	41,023	93	Good
FMY	TW A3	Taxiway	150	67,098	54	Poor
FMY	TW A3	Taxiway	153	14,735	94	Good
FMY	TW A3	Taxiway	155	26,215	94	Good
FMY	TW A6	Taxiway	175	4,324	60	Fair
FMY	TW A6	Taxiway	178	4,732	94	Good
FMY	TW A6	Taxiway	180	5,104	94	Good
FMY	TW A7	Taxiway	120	28,228	65	Fair
FMY	TW AP SW	Taxiway	107	14,624	94	Good
FMY	TW AP SW	Taxiway	112	13,304	91	Good
FMY	TW B	Taxiway	205	140,345	65	Fair
FMY	TW B	Taxiway	206	21,637	90	Good
FMY	TW B	Taxiway	208	10,199	94	Good
FMY	TW B	Taxiway	210	27,327	89	Good
FMY	TW B	Taxiway	270	2,906	55	Poor
FMY	TW B1	Taxiway	207	19,766	72	Satisfactory
FMY	TW B2	Taxiway	220	11,346	94	Good
FMY	TW B3	Taxiway	260	11,346	94	Good
FMY	TW B3	Taxiway	265	8,453	67	Fair
FMY	TW B3	Taxiway	275	59,219	69	Fair
FMY	TW B4	Taxiway	203	24,035	67	Fair
FMY	TW C	Taxiway	240	22,168	91	Good
FMY	TW C	Taxiway	245	121,801	93	Good
FMY	TW C	Taxiway	305	162,237	77	Satisfactory
FMY	TW C	Taxiway	306	24,962	94	Good
FMY	TW C1	Taxiway	310	29,730	69	Fair
FMY	TW C2	Taxiway	320	42,197	75	Satisfactory
FMY	TW C2	Taxiway	520	42,571	76	Satisfactory
FMY	TW C3	Taxiway	525	23,701	88	Good
FMY	TW C5	Taxiway	330	26,412	94	Good
FMY	TW C6	Taxiway	335	7,909	90	Good
FMY	TW C6	Taxiway	345	8,342	89	Good
FMY	TW C7	Taxiway	350	15,220	90	Good
FMY	TW C8	Taxiway	355	15,632	89	Good
FMY	TW C9	Taxiway	360	9,368	94	Good
FMY	TW D	Taxiway	134	28,977	94	Good
FMY	TW D	Taxiway	135	23,050	65	Fair
FMY	TW D	Taxiway	136	9,753	60	Fair
FMY	TW D	Taxiway	137	56,400	64	Fair
FMY	TW D	Taxiway	140	24,471	73	Satisfactory
FMY	TW D	Taxiway	143	9,551	78	Satisfactory
FMY	TW D2	Taxiway	160	13,679	29	Very Poor

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
FMY	TW D3	Taxiway	141	9,322	94	Good
FMY	TW E	Taxiway	147	22,245	94	Good
FMY	TW E	Taxiway	165	42,108	94	Good
FMY	TW E	Taxiway	503	39,478	94	Good
FMY	TW E	Taxiway	510	48,748	75	Satisfactory
FMY	TW E	Taxiway	512	31,577	73	Satisfactory
FMY	TW E	Taxiway	535	28,366	94	Good
FMY	TW E1	Taxiway	500	10,310	91	Good
FMY	TW E2	Taxiway	505	10,138	69	Fair
FMY	TW E2	Taxiway	530	10,056	88	Good
FMY	AP E	Apron	4505	58,570	75	Satisfactory
FMY	AP E	Apron	4515	13,907	83	Satisfactory
FMY	AP E	Apron	4520	72,634	74	Satisfactory
FMY	AP E	Apron	4525	71,383	80	Satisfactory
FMY	AP E	Apron	4530	27,056	81	Satisfactory
FMY	AP HELI	Apron	4705	93,555	82	Satisfactory
FMY	AP N	Apron	4305	331,067	52	Poor
FMY	AP RU 13	Apron	5105	11,434	66	Fair
FMY	AP RU 5	Apron	5205	30,022	77	Satisfactory
FMY	AP S	Apron	4103	10,783	94	Good
FMY	AP S	Apron	4105	187,842	65	Fair
FMY	AP S	Apron	4110	92,757	68	Fair
FMY	AP S	Apron	4115	19,731	64	Fair
FMY	AP S	Apron	4120	108,068	47	Poor
FMY	AP S	Apron	4125	26,416	100	Good
FMY	AP SE	Apron	4415	172,279	39	Very Poor
FMY	AP SE	Apron	4420	249,512	78	Satisfactory
FMY	AP SW	Apron	4205	118,829	72	Satisfactory
FMY	AP SW	Apron	4215	166,211	47	Poor
FMY	AP SW	Apron	4220	49,071	47	Poor
FMY	AP T-HANG	Apron	4605	169,083	83	Satisfactory
FMY	AP W	Apron	4805	545,226	89	Good
FMY	AP W	Apron	4818	15,664	91	Good



## Forecasted Pavement Conditions

**Table E.2** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

*Table E.2: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	RW 5-23	6105	91	89	87	86	84	82	80	79	77	75	73
FMY	RW 5-23	6110	94	92	90	89	87	85	83	82	80	78	76
FMY	RW 5-23	6115	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 5-23	6120	92	90	88	87	85	83	81	80	78	76	74
FMY	RW 5-23	6125	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 5-23	6130	84	82	80	79	77	75	73	72	70	68	66
FMY	RW 5-23	6135	87	85	83	82	80	78	76	75	73	71	69
FMY	RW 5-23	6140	82	80	78	77	75	73	71	70	68	66	64
FMY	RW 5-23	6145	86	84	82	81	79	77	75	74	72	70	68
FMY	RW 5-23	6150	88	86	84	83	81	79	77	76	74	72	70
FMY	RW 5-23	6155	84	82	80	79	77	75	73	72	70	68	66
FMY	RW 5-23	6160	88	86	84	83	81	79	77	76	74	72	70
FMY	RW 13-31	6205	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 13-31	6210	92	89	87	85	83	82	80	78	77	76	75
FMY	TW A	103	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A	105	91	89	87	85	83	81	79	77	76	74	73
FMY	TW A	110	79	77	76	74	73	71	70	69	68	67	66
FMY	TW A	111	93	91	89	87	85	83	81	80	78	77	76
FMY	TW A	114	79	77	76	74	73	71	70	69	68	67	66
FMY	TW A	115	64	63	62	61	61	60	59	58	58	57	56
FMY	TW A1	123	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A2	125	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A3	145	93	91	89	87	85	83	81	80	78	77	76
FMY	TW A3	150	54	53	52	51	51	50	49	48	46	45	44
FMY	TW A3	153	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A3	155	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A6	175	60	59	58	58	57	56	56	55	54	53	53
FMY	TW A6	178	94	91	89	87	85	83	81	80	78	76	75
FMY	TW A6	180	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A7	120	65	64	63	62	61	61	60	59	58	58	57
FMY	TW AP SW	107	94	92	90	88	86	84	82	81	79	78	76
FMY	TW AP SW	112	91	89	87	85	83	82	80	78	77	76	74

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	TW B	205	65	64	63	63	62	62	61	61	60	60	59
FMY	TW B	206	90	88	86	84	82	81	79	78	76	75	74
FMY	TW B	208	94	91	89	87	85	83	81	80	78	76	75
FMY	TW B	210	89	87	85	83	82	80	78	77	76	74	73
FMY	TW B	270	55	55	54	54	53	53	52	52	51	51	50
FMY	TW B1	207	72	71	70	69	68	67	66	65	64	64	63
FMY	TW B2	220	94	92	90	88	86	84	82	81	79	78	76
FMY	TW B3	260	94	92	90	88	86	84	82	81	79	78	76
FMY	TW B3	265	67	66	65	65	64	63	62	62	61	61	60
FMY	TW B3	275	69	68	67	66	65	65	64	63	63	62	61
FMY	TW B4	203	67	66	65	65	64	63	62	62	61	61	60
FMY	TW C	240	91	89	87	85	83	82	80	78	77	76	74
FMY	TW C	245	93	91	89	87	85	83	81	80	78	77	76
FMY	TW C	305	77	75	74	73	72	71	70	69	68	67	66
FMY	TW C	306	94	92	90	88	86	84	82	81	79	78	76
FMY	TW C1	310	69	68	67	66	65	65	64	63	63	62	61
FMY	TW C2	320	75	74	72	71	70	69	68	67	66	66	65
FMY	TW C2	520	76	75	73	72	71	70	69	68	67	66	65
FMY	TW C3	525	88	86	84	82	81	79	78	76	75	74	72
FMY	TW C5	330	94	92	90	88	86	84	82	81	79	78	76
FMY	TW C6	335	90	88	86	84	82	80	78	77	75	74	72
FMY	TW C6	345	89	87	85	83	82	80	78	77	76	74	73
FMY	TW C7	350	90	88	86	84	82	81	79	78	76	75	74
FMY	TW C8	355	89	87	85	83	82	80	78	77	76	74	73
FMY	TW C9	360	94	92	90	88	86	84	82	81	79	78	76
FMY	TW D	134	94	92	90	88	86	84	82	81	79	78	76
FMY	TW D	135	65	64	63	62	61	61	60	59	58	58	57
FMY	TW D	136	60	59	59	59	58	58	57	57	56	56	56
FMY	TW D	137	64	63	62	61	61	60	59	58	58	57	56
FMY	TW D	140	73	71	70	69	68	67	66	65	64	63	62
FMY	TW D	143	78	76	75	74	73	71	70	69	68	67	67
FMY	TW D2	160	29	27	25	23	21	19	17	15	13	11	9
FMY	TW D3	141	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	147	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	165	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	503	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	510	75	74	72	71	70	69	68	67	66	66	65
FMY	TW E	512	73	72	71	70	69	68	67	66	65	64	64
FMY	TW E	535	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E1	500	91	89	87	85	83	82	80	78	77	76	74
FMY	TW E2	505	69	68	67	66	65	65	64	63	63	62	61
FMY	TW E2	530	88	86	84	82	81	79	78	76	75	74	72
FMY	AP E	4505	75	73	71	70	68	67	65	64	63	62	61
FMY	AP E	4515	83	81	79	77	75	73	72	70	69	67	66
FMY	AP E	4520	74	72	70	69	67	66	65	63	62	61	60
FMY	AP E	4525	80	78	76	74	72	71	69	68	66	65	64



Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	AP E	4530	81	79	77	75	73	72	70	69	67	66	64
FMY	AP HELI	4705	82	80	78	76	74	73	71	69	68	66	65
FMY	AP N	4305	52	50	47	45	43	41	39	36	34	32	30
FMY	AP RU 13	5105	66	65	63	62	61	60	59	58	57	57	56
FMY	AP RU 5	5205	77	75	73	72	70	68	67	66	64	63	62
FMY	AP S	4103	94	92	89	87	85	83	81	78	76	74	72
FMY	AP S	4105	65	63	60	58	56	54	52	49	47	45	43
FMY	AP S	4110	68	66	65	64	63	61	60	59	59	58	57
FMY	AP S	4115	64	63	62	60	59	59	58	57	56	56	55
FMY	AP S	4120	47	45	42	40	38	36	34	31	29	27	25
FMY	AP S	4125	100	93	91	89	87	85	82	80	78	76	74
FMY	AP SE	4415	39	37	34	32	30	28	26	23	21	19	17
FMY	AP SE	4420	78	76	74	72	71	69	68	66	65	64	63
FMY	AP SW	4205	72	70	69	67	66	64	63	62	61	60	59
FMY	AP SW	4215	47	46	45	44	42	41	39	37	35	33	30
FMY	AP SW	4220	47	46	45	44	42	41	39	37	35	33	30
FMY	AP T-HANG	4605	83	81	79	77	75	73	72	70	69	67	66
FMY	AP W	4805	89	87	85	83	81	79	77	75	73	72	70
FMY	AP W	4818	91	90	89	87	86	85	84	83	82	80	79

## Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$55.44M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$24.43M and localized maintenance needs for Year 1 are \$0.42M.

*Table E.3: Major Rehabilitation Planning 2023-2032*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	FMY	TW A	115	AAC	17,123	63	AC Rehabilitation	\$ 180,000
2023	FMY	TW A3	150	AAC	67,098	53	AC Reconstruction	\$ 1,242,000
2023	FMY	TW A6	175	AAC	4,324	59	AC Rehabilitation	\$ 46,000
2023	FMY	TW A7	120	AAC	28,228	64	AC Rehabilitation	\$ 297,000
2023	FMY	TW B	205	AC	140,345	64	AC Rehabilitation	\$ 1,474,000
2023	FMY	TW B	270	AC	2,906	55	AC Reconstruction	\$ 42,000
2023	FMY	TW B3	265	AC	8,453	66	AC Rehabilitation	\$ 89,000
2023	FMY	TW B3	275	AC	59,219	68	AC Rehabilitation	\$ 622,000
2023	FMY	TW B4	203	AC	24,035	66	AC Rehabilitation	\$ 253,000
2023	FMY	TW C1	310	AC	29,730	68	AC Rehabilitation	\$ 313,000
2023	FMY	TW D	135	AAC	23,050	64	AC Rehabilitation	\$ 243,000
2023	FMY	TW D	136	AC	9,753	59	AC Rehabilitation	\$ 103,000
2023	FMY	TW D	137	AAC	56,400	63	AC Rehabilitation	\$ 593,000
2023	FMY	TW D2	160	AAC	13,679	27	AC Reconstruction	\$ 254,000
2023	FMY	TW E2	505	AC	10,138	68	AC Rehabilitation	\$ 107,000
2023	FMY	AP N	4305	AAC	331,067	50	AC Reconstruction	\$ 6,125,000
2023	FMY	AP RU 13	5105	AC	11,434	65	AC Rehabilitation	\$ 121,000
2023	FMY	AP S	4105	AAC	187,842	63	AC Rehabilitation	\$ 1,973,000
2023	FMY	AP S	4110	AC	92,757	66	AC Rehabilitation	\$ 974,000

# Airport Pavement Evaluation Report


## Statewide Airfield Pavement Management Program

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	FMY	AP S	4115	AC	19,731	63	AC Rehabilitation	\$ 208,000
2023	FMY	AP S	4120	AAC	108,068	45	AC Reconstruction	\$ 2,000,000
2023	FMY	AP SE	4415	AAC	172,279	37	AC Reconstruction	\$ 3,188,000
2023	FMY	AP SW	4215	AC	166,211	46	AC Reconstruction	\$ 3,075,000
2023	FMY	AP SW	4220	AC	49,071	46	AC Reconstruction	\$ 908,000
2024	FMY	TW B1	207	AC	19,766	70	AC Rehabilitation	\$ 218,000
2024	FMY	AP SW	4205	AC	118,829	69	AC Rehabilitation	\$ 1,311,000
2025	FMY	TW D	140	AAC	24,471	69	AC Rehabilitation	\$ 284,000
2025	FMY	TW E	512	AC	31,577	70	AC Rehabilitation	\$ 366,000
2025	FMY	AP E	4505	AC	58,570	70	AC Rehabilitation	\$ 679,000
2025	FMY	AP E	4520	AC	72,634	69	AC Rehabilitation	\$ 841,000
2026	FMY	AP RU 5	5205	AC	30,022	70	AC Rehabilitation	\$ 365,000
2027	FMY	TW C2	320	AC	42,197	69	AC Rehabilitation	\$ 539,000
2027	FMY	TW C2	520	AC	42,571	70	AC Rehabilitation	\$ 544,000
2027	FMY	TW E	510	AC	48,748	69	AC Rehabilitation	\$ 623,000
2027	FMY	AP SE	4420	AC	249,512	69	AC Rehabilitation	\$ 3,185,000
2028	FMY	TW C	305	AC	162,237	70	AC Rehabilitation	\$ 2,175,000
2028	FMY	AP E	4525	AC	71,383	69	AC Rehabilitation	\$ 957,000
2029	FMY	RW 5-23	6140	AAC	25,000	70	AC Rehabilitation	\$ 352,000
2029	FMY	TW A	110	AAC	6,623	69	AC Rehabilitation	\$ 94,000
2029	FMY	TW A	114	AAC	73,900	69	AC Rehabilitation	\$ 1,040,000
2029	FMY	TW D	143	AC	9,551	69	AC Rehabilitation	\$ 135,000
2029	FMY	AP E	4530	AC	27,056	69	AC Rehabilitation	\$ 381,000
2029	FMY	AP HELI	4705	AC	93,555	69	AC Rehabilitation	\$ 1,317,000
2030	FMY	RW 5-23	6130	AAC	10,000	70	AC Rehabilitation	\$ 148,000
2030	FMY	RW 5-23	6155	AAC	35,600	70	AC Rehabilitation	\$ 526,000
2030	FMY	AP E	4515	AC	13,907	69	AC Rehabilitation	\$ 206,000
2030	FMY	AP T-HANG	4605	AC	169,083	69	AC Rehabilitation	\$ 2,499,000
2032	FMY	RW 5-23	6135	AAC	50,000	69	AC Rehabilitation	\$ 815,000
2032	FMY	RW 5-23	6145	AAC	155,000	68	AC Rehabilitation	\$ 2,525,000
2032	FMY	AP W	4805	AC	545,226	70	AC Rehabilitation	\$ 8,882,000

*\*All planning cost values have been rounded up to the nearest thousand dollars.*



*Figure E.3: 10-Year Major Rehabilitation Needs by Program Year*





# Chapter 1: Introduction



# Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration’s (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida’s economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida’s system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida’s most prominent industry.

## 1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements” and 150/5380-7B “Airport Pavement Management Program (PMP)”. The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 “Standard Test Method for Airport Pavement Condition Index Surveys”.


In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.” The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are



under consideration for projects. A network-level evaluation can support the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

*Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts*



## 1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

*Table 1.2: FDOT SAPMP Stakeholders*

Role	Description
<b>FAA Orlando Airports District Office (Orlando ADO)</b>	Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation).
<b>Florida Department of Transportation (FDOT)</b>	Key Stakeholder: the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System.
<b>FDOT District Offices</b>	The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes.
<b>Participating Public-Use and Publicly-Owned Airports</b>	The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment.
<b>Aviation Office Program Manager (AO-PM)</b>	FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update.

## 1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- » Research and evaluation of existing record documentation;
- » Establishment of a pavement system inventory;
- » Development of a pavement network definition map and supplemental GIS model;
- » Functional pavement evaluations via the PCI assessment method;
- » Customization of PAVER™ software including prioritization, policies, and performance models;
- » Analysis of condition data; and
- » Maintenance, repair, and rehabilitation planning.

## 1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.

A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:


- » Assist airports in meeting the requirements of Public Law 103-305;
- » Assist airports in complying with FAA Grant Assurances 11 and 19;
- » Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- » Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- » Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.



Figure 1.4: Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds: ☐ >70: Routine Maintenance ☐ 55-70: Rehabilitation Eligible ☐ <55: Reconstruction Eligible

\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements




## Chapter 2: Methodology



## Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.

*Figure 2: FDOT SAPMP General Process*



### 2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- » Create a manageable inventory system;
- » Analyze the current condition of pavements in accordance with ASTM D5340-20;
- » Develop pavement performance models to forecast conditions; and
- » Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database and typically consist of pavement inventory



characteristics, pavement structure, work history, historic condition records, and analytical customization.

## 2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- » Location and limits of work;
- » Types and severities of repaired distresses;
- » Work type and cost; and
- » Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- » Date of last construction/rehabilitation
- » Work type performed
- » Comments for documenting pavement cross-section
- » Pavement surface type
- » Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

## 2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.

### 2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

#### **Asphalt Concrete (AC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

#### **Asphalt Concrete Overlaid on Asphalt Concrete (AAC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

#### **Asphalt Concrete Overlaid on Portland Cement Concrete (APC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

### 2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

#### **Portland Cement Concrete (PCC)**

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

### 2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

#### **Conventional Whitetopping (WT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.

### **Thin Whitetopping (TWT)**

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

### **Ultra-Thin Whitetopping (UWT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

## **2.4 Airfield Pavement Traffic**

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of FMY's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

## **2.5 Pavement Management Program Network Definition Terminology**

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

### **2.5.1 Pavement Network Identification**

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

### **2.5.2 Pavement Branch Identification**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.



### 2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

### 2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs ( $\pm 8$  slabs) for PCC pavement and 5,000 contiguous square feet ( $\pm 2,000$  SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

### 2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

*Table 2.5.5: SAPMP Terminology*

SAPMP Terminology	Common Definition	Airport Example
<b>Network</b>	Totality of pavement assets maintained by the Airport.	"Tallahassee International Airport – Airfield Pavements"
<b>Branch Name</b>	Commonly defined asset name as established by Airport and by use.	"Runway 18-36"
<b>Branch ID</b>	Codified shorthand name for commonly defined asset established for database identification.	"RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility
<b>Section ID</b>	Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition.	"6105"
<b>Sample Unit</b>	A numeric identification of an area of pavement (5,000 $\pm$ 2,000 SF of AC or 20 $\pm$ 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20.	"300"

## 2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

### 2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

*Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete*

Distress Mechanism	Distress Type
Load	Alligator Cracking Rutting
Climate/Durability	Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering
Construction/Material	Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling
Other	Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching

*Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete*

Distress Mechanism	Distress Type
Load	Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks
Climate/Durability	Blowup Durability "D" Cracking Joint Seal Damage Popouts
Construction/Material	Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking
Other	Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching

### 2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.

*Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete*


Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10




*Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete*

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.



# **Chapter 3: Airfield Pavement System Inventory**



## Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

### 3.1 Airfield Pavement Network Information

#### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.

*Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction*

Construction Year	Location	Work Type / Pavement Section
2017	AP S	Mill and Overlay
	RW 5-23	Mill and Overlay   4" Mill, 4" P-401 Overlay
	TW A, TW A6, TW C6	Mill and Overlay   2" Mill, 2" P-401 Overlay
	TW A, TW A1, TW A3, TW A6, TW AP SW, TW B, TW C6, TW D	Complete Reconstruction - AC   4" P-401, 6" P-211, 12" P-160
	TW A, TW A2, TW C, TW C5, TW C7, TW C8, TW C9, TW E	New Construction - AC   4" P-401, 6" P-211, 12" P-160
2018	RW 13-31	Mill and Overlay   2" Mill, 2" P-401 Overlay Complete Reconstruction - AC   4" P-401, 6" P-211
	TW A	Mill and Overlay   2" Mill, 2" P-401 Overlay
	TW A3, TW B2, TW B3, TW D3	Complete Reconstruction - AC   4" P-401, Existing Base
	TW E, TW E1	New Construction - AC   4" P-401, 6" P-211, 12" P-160
2020	AP S	Mill and Overlay

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

**Figure 3.1.1 (a)**, the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.






AAC RW 5-23 6125 1 4	AAC RW 5-23 6130 1 2	AAC RW 5-23 6135 2 10	AAC RW 5-23 6140 2 6	AAC RW 5-23 6145 7 31	AAC RW 5-23 6150 5 16	AAC RW 5-23 6155 2 7
AAC RW 5-23 6160 1 4	AAC RW 13-31 6205 21 95	AAC RW 13-31 6210 8 48	AAC TW A 105 1 10	AAC TW A 110 1 1	AAC TW A 114 2 15	AAC TW A 115 1 3
AAC TW A2 125 1 5	AAC TW A3 145 1 7	AAC TW A3 153 3 14	AAC TW A3 153 1 3	AAC TW A3 155 1 5	AAC TW A6 175 1 1	AAC TW A6 178 1 1
AAC TW A6 180 1 1	AAC TW A7 120 2 6	AAC TW AP SW 107 1 3	AAC TW AP SW 112 1 3	AAC TW B 205 4 34	AAC TW B 206 1 4	AAC TW B 208 1 2
AAC TW B 210 1 5	AAC TW B 270 1 1	AAC TW B2 220 1 2	AAC TW B3 260 1 2	AAC TW B3 265 1 2	AAC TW C 240 1 4	AAC TW C 245 3 23
AAC TW C 306 1 6	AAC TW C3 525 1 6	AAC TW C5 330 1 7	AAC TW C6 335 1 2	AAC TW C6 345 1 2	AAC TW C7 350 1 4	AAC TW C8 355 1 4
AAC TW C9 360 1 2	AAC TW D 134 1 6	AAC TW D 135 2 5	AAC TW D 136 1 2	AAC TW D 140 2 5	AAC TW D 143 1 2	AAC TW D2 160 1 3
AAC TW D3 141 1 3	AAC TW E 165 1 9	AAC TW E1 500 1 2	AAC TW E2 505 1 3	AAC TW E 4515 1 3	AAC AP HELI 4705 3 19	AAC AP N 4305 7 67
AAC AP S 4105 5 33	AAC AP SW 4205 3 20	AAC AP SW 4215 4 35	AAC AP SW 4220 1 8	AAC AP T-HANG 4805 5 36		

LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- PAVEMENT SURFACE TYPE
- PAVEMENT BRANCH ID
- SECTION NUMBER
- NUMBER OF SAMPLE UNITS IN SECTION
- NUMBER OF SAMPLE UNITS TO BE INSPECTED
- SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- INSPECTED SAMPLE UNITS.


TOTAL SAMPLES INSPECTED = 226  
AC: 225 PCC: 1

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.




RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2017	AP S	Mill and Overlay
	RW 5-23	Mill and Overlay   4" Mill, 4" P-401 Overlay
	TW A, TW A6, TW C6	Mill and Overlay   2" Mill, 2" P-401 Overlay
	TW A, TW A1, TW A3, TW A6, TW AP SW, TW B, TW C6, TW D	Complete Reconstruction - AC   4" P-401, 6" P-211, 12" P-160
	TW A, TW A2, TW C, TW C5, TW C7, TW C8, TW C9, TW E	New Construction - AC   4" P-401, 6" P-211, 12" P-160
2018	RW 13-31	Mill and Overlay   2" Mill, 2" P-401 Overlay
	RW 13-31	Complete Reconstruction - AC   4" P-401, 6" P-211
	TW A3, TW B2, TW B3, TW D3	Complete Reconstruction - AC   4" P-401, Existing Base
	TW A	Mill and Overlay   2" Mill, 2" P-401 Overlay
	TW E, TW E1	New Construction - AC   4" P-401, 6" P-211, 12" P-160
2020	AP S	Mill and Overlay

**LEGEND**




RW 13-31

← TYPICAL RUNWAY BRANCH ID



TW A

← TYPICAL TAXIWAY BRANCH ID













AP S

← TYPICAL APRON BRANCH ID

**PROJECT YEAR**


	2017		2022
	2018		2023
	2019		2024
	2020		2025
	2021		2026

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.

*Figure 3.1.2 (a): Age of Pavements at PCI Survey*







**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID

TW A — TYPICAL TAXIWAY BRANCH ID

AP S — TYPICAL APRON BRANCH ID

**AGE AT INSPECTION**


White	0-5 Years
Light Blue	6-10 Years
Medium Blue	11-15 Years
Dark Blue	16-20 Years
Very Dark Blue	> 20 Years

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

### 3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed “functional use” or “branch use.” For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.

*Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)*




### 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at FMY.

Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)



### 3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

**Table 3.1.5** displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

Table 3.1.5: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
FMY	RW 5-23	Runway	6105	100,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6110	50,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6115	280,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6120	140,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6125	20,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6130	10,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6135	50,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6140	25,000	AAC	1/1/2017

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
FMY	RW 5-23	Runway	6145	155,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6150	77,500	AAC	1/1/2017
FMY	RW 5-23	Runway	6155	35,600	AAC	1/1/2017
FMY	RW 5-23	Runway	6160	17,800	AAC	1/1/2017
FMY	RW 13-31	Runway	6205	476,075	AAC	1/1/2018
FMY	RW 13-31	Runway	6210	238,038	AC	1/1/2018
FMY	TW A	Taxiway	103	12,403	AC	1/1/2017
FMY	TW A	Taxiway	105	51,700	AAC	1/1/2017
FMY	TW A	Taxiway	110	6,623	AAC	1/1/2018
FMY	TW A	Taxiway	111	132,526	AC	1/1/2017
FMY	TW A	Taxiway	114	73,900	AAC	1/1/2017
FMY	TW A	Taxiway	115	17,123	AAC	1/1/1991
FMY	TW A1	Taxiway	123	20,509	AC	1/1/2017
FMY	TW A2	Taxiway	125	20,237	AC	1/1/2017
FMY	TW A3	Taxiway	145	41,023	AC	1/1/2017
FMY	TW A3	Taxiway	150	67,098	AAC	1/1/1991
FMY	TW A3	Taxiway	153	14,735	AC	1/1/2018
FMY	TW A3	Taxiway	155	26,215	AC	1/1/2017
FMY	TW A6	Taxiway	175	4,324	AAC	1/1/1991
FMY	TW A6	Taxiway	178	4,732	AAC	1/1/2017
FMY	TW A6	Taxiway	180	5,104	AC	1/1/2017
FMY	TW A7	Taxiway	120	28,228	AAC	1/1/1991
FMY	TW AP SW	Taxiway	107	14,624	AC	1/1/2017
FMY	TW AP SW	Taxiway	112	13,304	AC	1/1/2017
FMY	TW B	Taxiway	205	140,345	AC	1/1/1977
FMY	TW B	Taxiway	206	21,637	AC	1/1/2017
FMY	TW B	Taxiway	208	10,199	AAC	1/1/2017
FMY	TW B	Taxiway	210	27,327	AC	1/1/2017
FMY	TW B	Taxiway	270	2,906	AC	1/1/1998
FMY	TW B1	Taxiway	207	19,766	AC	1/1/1997
FMY	TW B2	Taxiway	220	11,346	AC	1/1/2018
FMY	TW B3	Taxiway	260	11,346	AC	1/1/2018
FMY	TW B3	Taxiway	265	8,453	AC	1/1/1998
FMY	TW B3	Taxiway	275	59,219	AC	1/1/1998
FMY	TW B4	Taxiway	203	24,035	AC	1/1/1977
FMY	TW C	Taxiway	240	22,168	AC	1/1/2017
FMY	TW C	Taxiway	245	121,801	AC	1/1/2017
FMY	TW C	Taxiway	305	162,237	AC	1/1/2007
FMY	TW C	Taxiway	306	24,962	AC	1/1/2017
FMY	TW C1	Taxiway	310	29,730	AC	1/1/2007
FMY	TW C2	Taxiway	320	42,197	AC	1/1/2007
FMY	TW C2	Taxiway	520	42,571	AC	1/1/2009
FMY	TW C3	Taxiway	525	23,701	AC	1/1/2009
FMY	TW C5	Taxiway	330	26,412	AC	1/1/2017
FMY	TW C6	Taxiway	335	7,909	AAC	1/1/2017
FMY	TW C6	Taxiway	345	8,342	AC	1/1/2017



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
FMY	TW C7	Taxiway	350	15,220	AC	1/1/2017
FMY	TW C8	Taxiway	355	15,632	AC	1/1/2017
FMY	TW C9	Taxiway	360	9,368	AC	1/1/2017
FMY	TW D	Taxiway	134	28,977	AC	1/1/2017
FMY	TW D	Taxiway	135	23,050	AAC	1/1/1998
FMY	TW D	Taxiway	136	9,753	AC	1/1/1998
FMY	TW D	Taxiway	137	56,400	AAC	1/1/1998
FMY	TW D	Taxiway	140	24,471	AAC	1/1/1998
FMY	TW D	Taxiway	143	9,551	AC	1/1/1998
FMY	TW D2	Taxiway	160	13,679	AAC	1/1/1977
FMY	TW D3	Taxiway	141	9,322	AC	1/1/2018
FMY	TW E	Taxiway	147	22,245	AC	1/1/2017
FMY	TW E	Taxiway	165	42,108	AC	1/1/2017
FMY	TW E	Taxiway	503	39,478	AC	1/1/2018
FMY	TW E	Taxiway	510	48,748	AC	1/1/2007
FMY	TW E	Taxiway	512	31,577	AC	1/1/2007
FMY	TW E	Taxiway	535	28,366	AC	1/1/2017
FMY	TW E1	Taxiway	500	10,310	AC	1/1/2018
FMY	TW E2	Taxiway	505	10,138	AC	1/1/2007
FMY	TW E2	Taxiway	530	10,056	AC	1/1/2009
FMY	AP E	Apron	4505	58,570	AC	1/1/2002
FMY	AP E	Apron	4515	13,907	AC	1/1/2002
FMY	AP E	Apron	4520	72,634	AC	1/1/2002
FMY	AP E	Apron	4525	71,383	AC	1/1/2002
FMY	AP E	Apron	4530	27,056	AC	1/1/2002
FMY	AP HELI	Apron	4705	93,555	AC	1/1/2007
FMY	AP N	Apron	4305	331,067	AAC	1/1/1998
FMY	AP RU 13	Apron	5105	11,434	AC	12/25/1999
FMY	AP RU 5	Apron	5205	30,022	AC	1/1/2007
FMY	AP S	Apron	4103	10,783	AAC	1/1/2017
FMY	AP S	Apron	4105	187,842	AAC	1/1/1998
FMY	AP S	Apron	4110	92,757	AC	1/1/1998
FMY	AP S	Apron	4115	19,731	AC	1/1/2003
FMY	AP S	Apron	4120	108,068	AAC	1/1/1998
FMY	AP S	Apron	4125	26,416	AAC	7/1/2020
FMY	AP SE	Apron	4415	172,279	AAC	1/1/1998
FMY	AP SE	Apron	4420	249,512	AC	1/1/2006
FMY	AP SW	Apron	4205	118,829	AC	1/1/1998
FMY	AP SW	Apron	4215	166,211	AC	1/1/1966
FMY	AP SW	Apron	4220	49,071	AC	1/1/1998
FMY	AP T-HANG	Apron	4605	169,083	AC	1/1/2006
FMY	AP W	Apron	4805	545,226	AC	1/1/2009
FMY	AP W	Apron	4818	15,664	PCC	1/1/2009



# **Chapter 4: Airfield Pavement Condition Analysis**



## Chapter 4 – Airfield Pavement Condition Analysis


The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for design-and/or project-level determination of pavement rehabilitation needs.

### 4.1 Airfield Pavement Condition Index

#### 4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 73% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 12% of inspected pavements are in Fair condition and the remaining 15% of inspected pavements are in Poor or worse condition.

*Figure 4.1.1: Current Condition – Overall Network*



#### 4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(d)** summarize branch-level pavement conditions according to the most recent PCI assessment results.

*Figure 4.1.2 (a): Current Condition Summary – Branch-Level*




Figure 4.1.2 (b): Current Condition – Runway






Figure 4.1.2 (c): Current Condition – Taxiway





*Figure 4.1.2 (d): Current Condition – Apron*



**Table 4.1.2** details the branch-level condition for each airfield pavement branch.

*Table 4.1.2: Current Condition Summary – Branch-Level*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
RW 5-23	Runway	12	960,900	89	Good
RW 13-31	Runway	2	714,113	90	Good
TW A	Taxiway	6	294,275	87	Good
TW A1	Taxiway	1	20,509	94	Good
TW A2	Taxiway	1	20,237	94	Good
TW A3	Taxiway	4	149,071	76	Satisfactory
TW A6	Taxiway	3	14,160	84	Satisfactory
TW A7	Taxiway	1	28,228	65	Fair
TW AP SW	Taxiway	2	27,928	93	Good
TW B	Taxiway	5	202,414	72	Satisfactory
TW B1	Taxiway	1	19,766	72	Satisfactory
TW B2	Taxiway	1	11,346	94	Good
TW B3	Taxiway	3	79,018	72	Satisfactory
TW B4	Taxiway	1	24,035	67	Fair
TW C	Taxiway	4	331,168	85	Satisfactory
TW C1	Taxiway	1	29,730	69	Fair
TW C2	Taxiway	2	84,768	76	Satisfactory
TW C3	Taxiway	1	23,701	88	Good
TW C5	Taxiway	1	26,412	94	Good
TW C6	Taxiway	2	16,251	89	Good
TW C7	Taxiway	1	15,220	90	Good
TW C8	Taxiway	1	15,632	89	Good
TW C9	Taxiway	1	9,368	94	Good
TW D	Taxiway	6	152,202	72	Satisfactory
TW D2	Taxiway	1	13,679	29	Very Poor
TW D3	Taxiway	1	9,322	94	Good
TW E	Taxiway	6	212,522	87	Good
TW E1	Taxiway	1	10,310	91	Good
TW E2	Taxiway	2	20,194	78	Satisfactory
AP E	Apron	5	243,550	77	Satisfactory
AP HELI	Apron	1	93,555	82	Satisfactory
AP N	Apron	1	331,067	52	Poor
AP RU 13	Apron	1	11,434	66	Fair
AP RU 5	Apron	1	30,022	77	Satisfactory
AP S	Apron	6	445,597	64	Fair
AP SE	Apron	2	421,791	62	Fair
AP SW	Apron	3	334,111	56	Fair
AP T-HANG	Apron	1	169,083	83	Satisfactory
AP W	Apron	2	560,890	89	Good

#### 4.1.3 Section-Level Analysis

**Table 4.1.3** provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.

Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.

Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level


Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
FMY	RW 5-23	Runway	6105	100,000	AAC	91	Good	100	0	0	5	20
FMY	RW 5-23	Runway	6110	50,000	AAC	94	Good	100	0	0	2	10
FMY	RW 5-23	Runway	6115	280,000	AAC	89	Good	100	0	0	12	56
FMY	RW 5-23	Runway	6120	140,000	AAC	92	Good	100	0	0	5	28
FMY	RW 5-23	Runway	6125	20,000	AAC	89	Good	100	0	0	1	4
FMY	RW 5-23	Runway	6130	10,000	AAC	84	Satisfactory	100	0	0	1	2
FMY	RW 5-23	Runway	6135	50,000	AAC	87	Good	100	0	0	2	10
FMY	RW 5-23	Runway	6140	25,000	AAC	82	Satisfactory	100	0	0	2	6
FMY	RW 5-23	Runway	6145	155,000	AAC	86	Good	100	0	0	7	31
FMY	RW 5-23	Runway	6150	77,500	AAC	88	Good	100	0	0	5	16
FMY	RW 5-23	Runway	6155	35,600	AAC	84	Satisfactory	100	0	0	2	7
FMY	RW 5-23	Runway	6160	17,800	AAC	88	Good	100	0	0	1	4
FMY	RW 13-31	Runway	6205	476,075	AAC	89	Good	90	0	10	21	95
FMY	RW 13-31	Runway	6210	238,038	AC	92	Good	100	0	0	8	48
FMY	TW A	Taxiway	103	12,403	AC	94	Good	100	0	0	1	3
FMY	TW A	Taxiway	105	51,700	AAC	91	Good	100	0	0	1	10
FMY	TW A	Taxiway	110	6,623	AAC	79	Satisfactory	67	0	33	1	1
FMY	TW A	Taxiway	111	132,526	AC	93	Good	100	0	0	3	27
FMY	TW A	Taxiway	114	73,900	AAC	79	Satisfactory	76	0	24	2	15
FMY	TW A	Taxiway	115	17,123	AAC	64	Fair	100	0	0	1	3
FMY	TW A1	Taxiway	123	20,509	AC	94	Good	100	0	0	1	5
FMY	TW A2	Taxiway	125	20,237	AC	94	Good	100	0	0	1	5
FMY	TW A3	Taxiway	145	41,023	AC	93	Good	100	0	0	2	7
FMY	TW A3	Taxiway	150	67,098	AAC	54	Poor	98	0	2	3	14
FMY	TW A3	Taxiway	153	14,735	AC	94	Good	100	0	0	1	3
FMY	TW A3	Taxiway	155	26,215	AC	94	Good	100	0	0	1	5
FMY	TW A6	Taxiway	175	4,324	AAC	60	Fair	81	0	19	1	1
FMY	TW A6	Taxiway	178	4,732	AAC	94	Good	100	0	0	1	1
FMY	TW A6	Taxiway	180	5,104	AC	94	Good	100	0	0	1	1
FMY	TW A7	Taxiway	120	28,228	AAC	65	Fair	100	0	0	2	6
FMY	TW AP SW	Taxiway	107	14,624	AC	94	Good	100	0	0	1	3
FMY	TW AP SW	Taxiway	112	13,304	AC	91	Good	100	0	0	1	3
FMY	TW B	Taxiway	205	140,345	AC	65	Fair	100	0	0	4	34
FMY	TW B	Taxiway	206	21,637	AC	90	Good	100	0	0	1	4
FMY	TW B	Taxiway	208	10,199	AAC	94	Good	100	0	0	1	2
FMY	TW B	Taxiway	210	27,327	AC	89	Good	100	0	0	1	5
FMY	TW B	Taxiway	270	2,906	AC	55	Poor	95	0	5	1	1
FMY	TW B1	Taxiway	207	19,766	AC	72	Satisfactory	100	0	0	1	4
FMY	TW B2	Taxiway	220	11,346	AC	94	Good	100	0	0	1	2
FMY	TW B3	Taxiway	260	11,346	AC	94	Good	100	0	0	1	2
FMY	TW B3	Taxiway	265	8,453	AC	67	Fair	92	0	8	1	2
FMY	TW B3	Taxiway	275	59,219	AC	69	Fair	95	0	5	2	14
FMY	TW B4	Taxiway	203	24,035	AC	67	Fair	100	0	0	1	5



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
FMY	TW C	Taxiway	240	22,168	AC	91	Good	100	0	0	1	4
FMY	TW C	Taxiway	245	121,801	AC	93	Good	100	0	0	3	23
FMY	TW C	Taxiway	305	162,237	AC	77	Satisfactory	96	0	4	4	32
FMY	TW C	Taxiway	306	24,962	AC	94	Good	100	0	0	1	6
FMY	TW C1	Taxiway	310	29,730	AC	69	Fair	92	0	8	1	6
FMY	TW C2	Taxiway	320	42,197	AC	75	Satisfactory	100	0	0	1	8
FMY	TW C2	Taxiway	520	42,571	AC	76	Satisfactory	100	0	0	1	7
FMY	TW C3	Taxiway	525	23,701	AC	88	Good	100	0	0	1	6
FMY	TW C5	Taxiway	330	26,412	AC	94	Good	100	0	0	1	7
FMY	TW C6	Taxiway	335	7,909	AAC	90	Good	100	0	0	1	2
FMY	TW C6	Taxiway	345	8,342	AC	89	Good	100	0	0	1	2
FMY	TW C7	Taxiway	350	15,220	AC	90	Good	100	0	0	1	4
FMY	TW C8	Taxiway	355	15,632	AC	89	Good	100	0	0	1	4
FMY	TW C9	Taxiway	360	9,368	AC	94	Good	100	0	0	1	2
FMY	TW D	Taxiway	134	28,977	AC	94	Good	100	0	0	1	6
FMY	TW D	Taxiway	135	23,050	AAC	65	Fair	89	0	11	2	5
FMY	TW D	Taxiway	136	9,753	AC	60	Fair	93	0	7	1	2
FMY	TW D	Taxiway	137	56,400	AAC	64	Fair	86	0	14	2	12
FMY	TW D	Taxiway	140	24,471	AAC	73	Satisfactory	95	0	5	2	5
FMY	TW D	Taxiway	143	9,551	AC	78	Satisfactory	76	0	24	1	2
FMY	TW D2	Taxiway	160	13,679	AAC	29	Very Poor	71	29	0	1	3
FMY	TW D3	Taxiway	141	9,322	AC	94	Good	100	0	0	1	3
FMY	TW E	Taxiway	147	22,245	AC	94	Good	100	0	0	1	5
FMY	TW E	Taxiway	165	42,108	AC	94	Good	100	0	0	1	9
FMY	TW E	Taxiway	503	39,478	AC	94	Good	100	0	0	1	9
FMY	TW E	Taxiway	510	48,748	AC	75	Satisfactory	100	0	0	2	12
FMY	TW E	Taxiway	512	31,577	AC	73	Satisfactory	93	0	7	1	7
FMY	TW E	Taxiway	535	28,366	AC	94	Good	100	0	0	1	6
FMY	TW E1	Taxiway	500	10,310	AC	91	Good	100	0	0	1	2
FMY	TW E2	Taxiway	505	10,138	AC	69	Fair	100	0	0	1	3
FMY	TW E2	Taxiway	530	10,056	AC	88	Good	100	0	0	1	3
FMY	AP E	Apron	4505	58,570	AC	75	Satisfactory	100	0	0	2	13
FMY	AP E	Apron	4515	13,907	AC	83	Satisfactory	100	0	0	1	3
FMY	AP E	Apron	4520	72,634	AC	74	Satisfactory	100	0	0	4	15
FMY	AP E	Apron	4525	71,383	AC	80	Satisfactory	100	0	0	3	18
FMY	AP E	Apron	4530	27,056	AC	81	Satisfactory	92	0	8	1	5
FMY	AP HELI	Apron	4705	93,555	AC	82	Satisfactory	100	0	0	3	19
FMY	AP N	Apron	4305	331,067	AAC	52	Poor	76	0	24	7	67
FMY	AP RU 13	Apron	5105	11,434	AC	66	Fair	96	0	4	1	2
FMY	AP RU 5	Apron	5205	30,022	AC	77	Satisfactory	100	0	0	1	6
FMY	AP S	Apron	4103	10,783	AAC	94	Good	100	0	0	1	2
FMY	AP S	Apron	4105	187,842	AAC	65	Fair	96	0	4	5	33
FMY	AP S	Apron	4110	92,757	AC	68	Fair	90	0	10	3	20
FMY	AP S	Apron	4115	19,731	AC	64	Fair	97	0	3	1	4
FMY	AP S	Apron	4120	108,068	AAC	47	Poor	97	0	3	3	21
FMY	AP S	Apron	4125	26,416	AAC	100	Good	0	0	0	0	0

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
FMY	AP SE	Apron	4415	172,279	AAC	39	Very Poor	95	0	5	5	32
FMY	AP SE	Apron	4420	249,512	AC	78	Satisfactory	70	0	30	7	51
FMY	AP SW	Apron	4205	118,829	AC	72	Satisfactory	100	0	0	3	20
FMY	AP SW	Apron	4215	166,211	AC	47	Poor	92	0	8	4	35
FMY	AP SW	Apron	4220	49,071	AC	47	Poor	100	0	0	1	8
FMY	AP T-HANG	Apron	4605	169,083	AC	83	Satisfactory	98	0	2	5	36
FMY	AP W	Apron	4805	545,226	AC	89	Good	100	0	0	10	113
FMY	AP W	Apron	4818	15,664	PCC	91	Good	0	0	100	1	4

\* Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.



103 PCI = 94	105 PCI = 91	107 PCI = 94	110 PCI = 79	111 PCI = 93	112 PCI = 91	114 PCI = 79
115 PCI = 64	120 PCI = 65	123 PCI = 94	125 PCI = 94	134 PCI = 94	135 PCI = 65	136 PCI = 60
137 PCI = 64	140 PCI = 73	141 PCI = 94	143 PCI = 78	145 PCI = 93	147 PCI = 94	150 PCI = 54
153 PCI = 94	155 PCI = 94	160 PCI = 29	165 PCI = 94	175 PCI = 60	178 PCI = 94	180 PCI = 94
203 PCI = 67	205 PCI = 65	206 PCI = 90	207 PCI = 72	208 PCI = 94	210 PCI = 89	220 PCI = 94
240 PCI = 91	245 PCI = 93	260 PCI = 94	265 PCI = 67	270 PCI = 55	275 PCI = 69	305 PCI = 77
306 PCI = 94	310 PCI = 69	320 PCI = 75	330 PCI = 94	335 PCI = 90	345 PCI = 89	350 PCI = 90
355 PCI = 89	360 PCI = 94	500 PCI = 91	503 PCI = 94	505 PCI = 69	510 PCI = 75	512 PCI = 73
520 PCI = 76	525 PCI = 88	530 PCI = 88	535 PCI = 94	4103 PCI = 94	4105 PCI = 65	4110 PCI = 68
4115 PCI = 64	4120 PCI = 47	4125 PCI = 100	4205 PCI = 72	4215 PCI = 47	4220 PCI = 47	4305 PCI = 52
4415 PCI = 39	4420 PCI = 78	4505 PCI = 75	4515 PCI = 83	4520 PCI = 74	4525 PCI = 80	4530 PCI = 81
4605 PCI = 83	4705 PCI = 82	4805 PCI = 89	4818 PCI = 91	5105 PCI = 66	5205 PCI = 77	6105 PCI = 91
6110 PCI = 94	6115 PCI = 89	6120 PCI = 92	6125 PCI = 89	6130 PCI = 84	6135 PCI = 87	6140 PCI = 82
6145 PCI = 86	6150 PCI = 88	6155 PCI = 84	6160 PCI = 88	6205 PCI = 89	6210 PCI = 92	

**LEGEND**

TYPICAL RUNWAY BRANCH ID

TYPICAL TAXIWAY BRANCH ID

TYPICAL APRON BRANCH ID

**2022 PAVEMENT CONDITION INDEX**

PCI 86-100 Good

PCI 71-85 Satisfactory

PCI 56-70 Fair

PCI 41-55 Poor

PCI 26-40 Very Poor

PCI 11-25 Serious

PCI 0-10 Failed

**"SECTION ID"**  
**"PCI VALUE"**

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

## 4.2 Summary of Pavement Condition Evaluation Results

### 4.2.1 Network-Level Observations

The PCI assessment for Page Field (FMY) was performed in May 2022. The overall area-weighted average PCI value of the network was 78, representing a condition rating of Satisfactory. A portion of the South Apron was not inspected due to recent work.

Based on the FAA 5010 Report as of 10/28/2022, the Airport has reported 114,863 operations for 12 months ending 12/31/2019.

### 4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

### Runways

#### **RW 5-23**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 5-23	RUNWAY	12	960,900	89	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 93% Good (86-100 PCI), 7% Satisfactory (71-85 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6105	AAC	100,000	91	Good
6110	AAC	50,000	94	Good
6115	AAC	280,000	89	Good
6120	AAC	140,000	92	Good
6125	AAC	20,000	89	Good
6130	AAC	10,000	84	Satisfactory
6135	AAC	50,000	87	Good




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6140	AAC	25,000	82	Satisfactory
6145	AAC	155,000	86	Good
6150	AAC	77,500	88	Good
6155	AAC	35,600	84	Satisfactory
6160	AAC	17,800	88	Good

RW 5-23 consists of 12 flexible pavement sections, totaling 960,900 sf. The last major construction date for the branch was 2017, resulting in an area-weighted average age at inspection of 5 years old. Overall, RW 5-23 is in Good condition with an area-weighted average PCI of 89.

### **RW 13-31**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 13-31	RUNWAY	2	714,113	90	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6205	AAC	476,075	89	Good
6210	AC	238,038	92	Good

RW 13-31 consists of 2 flexible pavement sections, totaling 714,113 sf. The last major construction date for the branch was 2018, resulting in an area-weighted average age at inspection of 4 years old. Overall, RW 13-31 is in Good condition with an area-weighted average PCI of 90.

### **Taxiways**

#### **TW A**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	6	294,275	87	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 67% Good (86-100 PCI), 27% Satisfactory (71-85 PCI), 6% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
103	AC	12,403	94	Good
105	AAC	51,700	91	Good
110	AAC	6,623	79	Satisfactory
111	AC	132,526	93	Good
114	AAC	73,900	79	Satisfactory
115	AAC	17,123	64	Fair

TW A consists of 6 flexible pavement sections, totaling 294,275 sf. The last major construction dates range from 1991 to 2018, resulting in an area-weighted average age at inspection of 7 years old. Overall, TW A is in Good condition with an area-weighted average PCI of 87.

### TW A3

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A3	TAXIWAY	4	149,071	76	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 55% Good (86-100 PCI), 45% Poor (41-55 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
145	AC	41,023	93	Good
150	AAC	67,098	54	Poor
153	AC	14,735	94	Good
155	AC	26,215	94	Good

TW A3 consists of 4 flexible pavement sections, totaling 149,071 sf. The last major construction dates range from 1991 to 2018, resulting in an area-weighted average age at inspection of 17 years old. Overall, TW A3 is in Satisfactory condition with an area-weighted average PCI of 76.

### **TW B**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW B	TAXIWAY	5	202,414	72	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 30% Good (86-100 PCI), 69% Fair (56-70 PCI), 1% Poor (41-55 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
205	AC	140,345	65	Fair
206	AC	21,637	90	Good
208	AAC	10,199	94	Good
210	AC	27,327	89	Good
270	AC	2,906	55	Poor

TW B consists of 5 flexible pavement sections, totaling 202,414 sf. The last major construction dates range from 1977 to 2017, resulting in an area-weighted average age at inspection of 33 years old. Overall, TW B is in Satisfactory condition with an area-weighted average PCI of 72.

### **TW C**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW C	TAXIWAY	4	331,168	85	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 51% Good (86-100 PCI), 49% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
240	AC	22,168	91	Good
245	AC	121,801	93	Good
305	AC	162,237	77	Satisfactory
306	AC	24,962	94	Good

TW C consists of 4 flexible pavement sections, totaling 331,168 sf. The last major construction dates range from 2007 to 2017, resulting in an area-weighted average age at inspection of 10 years old. Overall, TW C is in Satisfactory condition with an area-weighted average PCI of 85.

### **TW D**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW D	TAXIWAY	6	152,202	72	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 19% Good (86-100 PCI), 22% Satisfactory (71-85 PCI), 59% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
134	AC	28,977	94	Good
135	AAC	23,050	65	Fair
136	AC	9,753	60	Fair
137	AAC	56,400	64	Fair
140	AAC	24,471	73	Satisfactory
143	AC	9,551	78	Satisfactory


TW D consists of 6 flexible pavement sections, totaling 152,202 sf. The last major construction dates range from 1998 to 2017, resulting in an area-weighted average age at inspection of 21 years old. Overall, TW D is in Satisfactory condition with an area-weighted average PCI of 72.



### TW D2

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW D2	TAXIWAY	1	13,679	29	Very Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Very Poor (26-40 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
160	AAC	13,679	29	Very Poor

TW D2 consists of 1 flexible pavement section, totaling 13,679 sf. The last major construction date for the branch was 1977, resulting in an area-weighted average age at inspection of 45 years old. Overall, TW D2 is in Very Poor condition with an area-weighted average PCI of 29.

### TW E

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW E	TAXIWAY	6	212,522	87	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 62% Good (86-100 PCI), 38% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
147	AC	22,245	94	Good
165	AC	42,108	94	Good
503	AC	39,478	94	Good
510	AC	48,748	75	Satisfactory
512	AC	31,577	73	Satisfactory
535	AC	28,366	94	Good

TW E consists of 6 flexible pavement sections, totaling 212,522 sf. The last major construction dates range from 2007 to 2018, resulting in an area-weighted average age at inspection of 9 years old. Overall, TW E is in Good condition with an area-weighted average PCI of 87.

### **TW E1**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW E1	TAXIWAY	1	10,310	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
500	AC	10,310	91	Good

TW E1 consists of 1 flexible pavement section, totaling 10,310 sf. The last major construction date for the branch was 2018, resulting in an area-weighted average age at inspection of 4 years old. Overall, TW E1 is in Good condition with an area-weighted average PCI of 91.

### **TW E2**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW E2	TAXIWAY	2	20,194	78	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 50% Good (86-100 PCI), 50% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
505	AC	10,138	69	Fair
530	AC	10,056	88	Good

TW E2 consists of 2 flexible pavement sections, totaling 20,194 sf. The last major construction dates range from 2007 to 2009, resulting in an area-weighted average age at inspection of 14 years old. Overall, TW E2 is in Satisfactory condition with an area-weighted average PCI of 78.

### AP N

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP N	APRON	1	331,067	52	Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4305	AAC	331,067	52	Poor

AP N consists of 1 flexible pavement section, totaling 331,067 sf. The last major construction date for the branch was 1998, resulting in an area-weighted average age at inspection of 24 years old. Overall, AP N is in Poor condition with an area-weighted average PCI of 52.

### AP S

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP S	APRON	6	445,597	64	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 8% Good (86-100 PCI), 68% Fair (56-70 PCI), 24% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4103	AAC	10,783	94	Good
4105	AAC	187,842	65	Fair


Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4110	AC	92,757	68	Fair
4115	AC	19,731	64	Fair
4120	AAC	108,068	47	Poor
4125	AAC	26,416	100	Good

AP S consists of 6 flexible pavement sections, totaling 445,597 sf. The last major construction dates range from 1998 to 2020, resulting in an area-weighted average age at inspection of 22 years old. Overall, AP S is in Fair condition with an area-weighted average PCI of 64.

### AP SE

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP SE	APRON	2	421,791	62	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 59% Satisfactory (71-85 PCI), 41% Very Poor (26-40 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4415	AAC	172,279	39	Very Poor
4420	AC	249,512	78	Satisfactory

AP SE consists of 2 flexible pavement sections, totaling 421,791 sf. The last major construction dates range from 1998 to 2006, resulting in an area-weighted average age at inspection of 20 years old. Overall, AP SE is in Fair condition with an area-weighted average PCI of 62.

### AP SW

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP SW	APRON	3	334,111	56	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 36% Satisfactory (71-85 PCI), 64% Poor (41-55 PCI).






Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4205	AC	118,829	72	Satisfactory
4215	AC	166,211	47	Poor
4220	AC	49,071	47	Poor

AP SW consists of 3 flexible pavement sections, totaling 334,111 sf. The last major construction dates range from 1966 to 1998, resulting in an area-weighted average age at inspection of 40 years old. Overall, AP SW is in Fair condition with an area-weighted average PCI of 56.

### AP W

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP W	APRON	2	560,890	89	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4805	AC	545,226	89	Good
4818	PCC	15,664	91	Good

AP W consists of 1 flexible and 1 rigid pavement sections, totaling 560,890 sf. The last major construction date for the branch was 2009, resulting in an area-weighted average age at inspection of 13 years old. Overall, AP W is in Good condition with an area-weighted average PCI of 89.



# Chapter 5: SAPMP Customization



## Chapter 5 – SAPMP Customization

Once the PAVER™ database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

### 5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- » The “Network” field identifies the airport being analyzed;
- » The “Airport Classification” field classifies the Airport according to the type and volume of aircraft traffic;
  - “GA” for General Aviation, community airports
  - “RL” for Regional Relievers
  - “PR” for Primary/Commercial airports
- » The “District” field identifies the FDOT District to which the Airport belongs;
- » The “FAA ADO Area” is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists);
- » The “Inspection Phase” denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- » The “CFASPP Center” identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

### 5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.



### 5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. **The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.** Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.


### 5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into “groups” or “families” according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

### 5.2.3 Branch-Level Pavement Condition Forecast

**Figure 5.2.3** depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.

*Figure 5.2.3: Forecasted Branch-Level Pavement Performance*





### 5.2.4 Section-Level Pavement Condition Forecast

**Table 5.2.4** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

*Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	RW 5-23	6105	91	89	87	86	84	82	80	79	77	75	73
FMY	RW 5-23	6110	94	92	90	89	87	85	83	82	80	78	76
FMY	RW 5-23	6115	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 5-23	6120	92	90	88	87	85	83	81	80	78	76	74
FMY	RW 5-23	6125	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 5-23	6130	84	82	80	79	77	75	73	72	70	68	66
FMY	RW 5-23	6135	87	85	83	82	80	78	76	75	73	71	69
FMY	RW 5-23	6140	82	80	78	77	75	73	71	70	68	66	64
FMY	RW 5-23	6145	86	84	82	81	79	77	75	74	72	70	68
FMY	RW 5-23	6150	88	86	84	83	81	79	77	76	74	72	70
FMY	RW 5-23	6155	84	82	80	79	77	75	73	72	70	68	66
FMY	RW 5-23	6160	88	86	84	83	81	79	77	76	74	72	70
FMY	RW 13-31	6205	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 13-31	6210	92	89	87	85	83	82	80	78	77	76	75
FMY	TW A	103	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A	105	91	89	87	85	83	81	79	77	76	74	73
FMY	TW A	110	79	77	76	74	73	71	70	69	68	67	66
FMY	TW A	111	93	91	89	87	85	83	81	80	78	77	76
FMY	TW A	114	79	77	76	74	73	71	70	69	68	67	66
FMY	TW A	115	64	63	62	61	61	60	59	58	58	57	56
FMY	TW A1	123	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A2	125	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A3	145	93	91	89	87	85	83	81	80	78	77	76
FMY	TW A3	150	54	53	52	51	51	50	49	48	46	45	44
FMY	TW A3	153	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A3	155	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A6	175	60	59	58	58	57	56	56	55	54	53	53
FMY	TW A6	178	94	91	89	87	85	83	81	80	78	76	75
FMY	TW A6	180	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A7	120	65	64	63	62	61	61	60	59	58	58	57
FMY	TW AP SW	107	94	92	90	88	86	84	82	81	79	78	76
FMY	TW AP SW	112	91	89	87	85	83	82	80	78	77	76	74
FMY	TW B	205	65	64	63	63	62	62	61	61	60	60	59
FMY	TW B	206	90	88	86	84	82	81	79	78	76	75	74
FMY	TW B	208	94	91	89	87	85	83	81	80	78	76	75
FMY	TW B	210	89	87	85	83	82	80	78	77	76	74	73
FMY	TW B	270	55	55	54	54	53	53	52	52	51	51	50
FMY	TW B1	207	72	71	70	69	68	67	66	65	64	64	63
FMY	TW B2	220	94	92	90	88	86	84	82	81	79	78	76

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	TW B3	260	94	92	90	88	86	84	82	81	79	78	76
FMY	TW B3	265	67	66	65	65	64	63	62	62	61	61	60
FMY	TW B3	275	69	68	67	66	65	65	64	63	63	62	61
FMY	TW B4	203	67	66	65	65	64	63	62	62	61	61	60
FMY	TW C	240	91	89	87	85	83	82	80	78	77	76	74
FMY	TW C	245	93	91	89	87	85	83	81	80	78	77	76
FMY	TW C	305	77	75	74	73	72	71	70	69	68	67	66
FMY	TW C	306	94	92	90	88	86	84	82	81	79	78	76
FMY	TW C1	310	69	68	67	66	65	65	64	63	63	62	61
FMY	TW C2	320	75	74	72	71	70	69	68	67	66	66	65
FMY	TW C2	520	76	75	73	72	71	70	69	68	67	66	65
FMY	TW C3	525	88	86	84	82	81	79	78	76	75	74	72
FMY	TW C5	330	94	92	90	88	86	84	82	81	79	78	76
FMY	TW C6	335	90	88	86	84	82	80	78	77	75	74	72
FMY	TW C6	345	89	87	85	83	82	80	78	77	76	74	73
FMY	TW C7	350	90	88	86	84	82	81	79	78	76	75	74
FMY	TW C8	355	89	87	85	83	82	80	78	77	76	74	73
FMY	TW C9	360	94	92	90	88	86	84	82	81	79	78	76
FMY	TW D	134	94	92	90	88	86	84	82	81	79	78	76
FMY	TW D	135	65	64	63	62	61	61	60	59	58	58	57
FMY	TW D	136	60	59	59	59	58	58	57	57	56	56	56
FMY	TW D	137	64	63	62	61	61	60	59	58	58	57	56
FMY	TW D	140	73	71	70	69	68	67	66	65	64	63	62
FMY	TW D	143	78	76	75	74	73	71	70	69	68	67	67
FMY	TW D2	160	29	27	25	23	21	19	17	15	13	11	9
FMY	TW D3	141	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	147	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	165	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	503	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	510	75	74	72	71	70	69	68	67	66	66	65
FMY	TW E	512	73	72	71	70	69	68	67	66	65	64	64
FMY	TW E	535	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E1	500	91	89	87	85	83	82	80	78	77	76	74
FMY	TW E2	505	69	68	67	66	65	65	64	63	63	62	61
FMY	TW E2	530	88	86	84	82	81	79	78	76	75	74	72
FMY	AP E	4505	75	73	71	70	68	67	65	64	63	62	61
FMY	AP E	4515	83	81	79	77	75	73	72	70	69	67	66
FMY	AP E	4520	74	72	70	69	67	66	65	63	62	61	60
FMY	AP E	4525	80	78	76	74	72	71	69	68	66	65	64
FMY	AP E	4530	81	79	77	75	73	72	70	69	67	66	64
FMY	AP HELI	4705	82	80	78	76	74	73	71	69	68	66	65
FMY	AP N	4305	52	50	47	45	43	41	39	36	34	32	30
FMY	AP RU 13	5105	66	65	63	62	61	60	59	58	57	57	56
FMY	AP RU 5	5205	77	75	73	72	70	68	67	66	64	63	62
FMY	AP S	4103	94	92	89	87	85	83	81	78	76	74	72
FMY	AP S	4105	65	63	60	58	56	54	52	49	47	45	43

# Airport Pavement Evaluation Report


## Statewide Airfield Pavement Management Program

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	AP S	4110	68	66	65	64	63	61	60	59	59	58	57
FMY	AP S	4115	64	63	62	60	59	59	58	57	56	56	55
FMY	AP S	4120	47	45	42	40	38	36	34	31	29	27	25
FMY	AP S	4125	100	93	91	89	87	85	82	80	78	76	74
FMY	AP SE	4415	39	37	34	32	30	28	26	23	21	19	17
FMY	AP SE	4420	78	76	74	72	71	69	68	66	65	64	63
FMY	AP SW	4205	72	70	69	67	66	64	63	62	61	60	59
FMY	AP SW	4215	47	46	45	44	42	41	39	37	35	33	30
FMY	AP SW	4220	47	46	45	44	42	41	39	37	35	33	30
FMY	AP T-HANG	4605	83	81	79	77	75	73	72	70	69	67	66
FMY	AP W	4805	89	87	85	83	81	79	77	75	73	72	70
FMY	AP W	4818	91	90	89	87	86	85	84	83	82	80	79

## 5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.

Figure 5.3 (a): Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds:   >70: Routine Maintenance   55-70: Rehabilitation Eligible   <55: Reconstruction Eligible

*\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.*

Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will



integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

*Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects*

Airfield Pavement Project Type	PCI Requirement
Reconstruction	PCI < 55 (Poor)
Rehabilitation	PCI < 70 (Fair)
Maintenance	N/A

\*Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

*Table 5.3 (b): Critical PCI Values by Branch Use*

Runway	Taxiway	Apron
70	70	70

**Figures 5.3 (b)** and **5.3 (c)** depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram,  $PCI < \text{Critical } PCI$





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram,  $PCI \geq \text{Critical } PCI$



## 5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 “Airport Foreign Object Debris (FOD) Management” provides additional guidance for developing and managing an airport FOD program.

### 5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety (“stopgap”) measure. The two (2) types of localized maintenance are described below in further detail.

- » Localized Preventive Maintenance and Repair
  - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- » Localized Stopgap/Safety Maintenance and Repair
  - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

### 5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

#### **AC Crack Sealing**

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

#### **AC Full-Depth Patching**

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

#### **AC Partial-Depth AC Patching**

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

#### **Grinding**

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

#### **Monitor Pavement**

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.



### **PCC Crack Sealing**

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

### **PCC Full-Depth Patching**

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

### **PCC Joint Seal**

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

### **PCC Partial-Depth Patching**

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

### **PCC Slab Replacement**

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

### **Surface Seal**

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

### 5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

**Tables 5.4.3 (a) and (b)** display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

*Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete*

Localized Work Type	Reliever Costs	Work Type Unit
AC Crack Sealing	\$ 4.00	LF
AC Full-Depth Patching	\$ 11.50	SF
AC Partial-Depth Patching	\$ 4.75	SF
Surface Seal	\$ 0.75	SF

*Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete*

Localized Work Type	Reliever Costs	Work Type Unit
Grinding	\$ 2.00	SF
PCC Crack Sealing	\$ 7.00	LF
PCC Joint Seal	\$ 4.25	LF
PCC Full-Depth Patching	\$ 65.00	SF
PCC Partial-Depth Patching	\$ 169.00	SF
PCC Slab Replacement	\$ 51.50	SF

\* PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.

### 5.4.4 Localized Maintenance and Repair Policy

**Table 5.4.4** and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.

*Table 5.4.4: AC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy*

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
41	Low	Alligator Cracking	Monitor Pavement	Monitor Pavement
41	Medium	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
41	High	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
42	N/A	Bleeding	Monitor Pavement	Monitor Pavement
43	Low	Block Cracking	Monitor Pavement	Monitor Pavement
43	Medium	Block Cracking	AC Crack Sealing	Monitor Pavement
43	High	Block Cracking	AC Crack Sealing	AC Crack Sealing
44	Low	Corrugation	Monitor Pavement	Monitor Pavement
44	Medium	Corrugation	AC Full Depth Patching	Monitor Pavement
44	High	Corrugation	AC Full Depth Patching	AC Full Depth Patching
45	Low	Depression	Monitor Pavement	Monitor Pavement
45	Medium	Depression	AC Full Depth Patching	Monitor Pavement
45	High	Depression	AC Full Depth Patching	AC Full Depth Patching
46	N/A	Jet Blast	Monitor Pavement	Monitor Pavement
47	Low	Jt. Reflective Cracking	Monitor Pavement	Monitor Pavement
47	Medium	Jt. Reflective Cracking	AC Crack Sealing	Monitor Pavement
47	High	Jt. Reflective Cracking	AC Full Depth Patching	AC Full Depth Patching
48	Low	L&T Cracking	Monitor Pavement	Monitor Pavement
48	Medium	L&T Cracking	AC Crack Sealing	Monitor Pavement
48	High	L&T Cracking	AC Full Depth Patching	AC Full Depth Patching
49	N/A	Oil Spillage	Monitor Pavement	Monitor Pavement
50	Low	Patching	Monitor Pavement	Monitor Pavement
50	Medium	Patching	AC Full Depth Patching	Monitor Pavement
50	High	Patching	AC Full Depth Patching	AC Full Depth Patching
51	N/A	Polished Aggregate	Monitor Pavement	Monitor Pavement
52	Low	Raveling	Surface Seal	Monitor Pavement
52	Medium	Raveling	Surface Seal	Monitor Pavement
52	High	Raveling	AC Partial Depth Patching	AC Partial Depth Patching
53	Low	Rutting	Monitor Pavement	Monitor Pavement
53	Medium	Rutting	AC Full Depth Patching	Monitor Pavement
53	High	Rutting	AC Full Depth Patching	AC Full Depth Patching
54	Low	Shoving	Monitor Pavement	Monitor Pavement
54	Medium	Shoving	AC Partial Depth Patching	Monitor Pavement
54	High	Shoving	AC Full Depth Patching	AC Full Depth Patching
55	N/A	Slippage Cracking	AC Full Depth Patching	AC Full Depth Patching
56	Low	Swelling	Monitor Pavement	Monitor Pavement
56	Medium	Swelling	AC Full Depth Patching	Monitor Pavement
56	High	Swelling	AC Full Depth Patching	AC Full Depth Patching

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
57	Low	Weathering	Monitor Pavement	Monitor Pavement
57	Medium	Weathering	Surface Seal	Monitor Pavement
57	High	Weathering	AC Partial Depth Patching	Surface Seal

*Table 5.4.5: PCC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy*

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
61	Low	Blow-up	PCC Full Depth Patching	Monitor Pavement
61	Medium	Blow-up	PCC Full Depth Patching	PCC Full Depth Patching
61	High	Blow-up	PCC Slab Replacement	PCC Slab Replacement
62	Low	Corner Break	Monitor Pavement	Monitor Pavement
62	Medium	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
62	High	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
63	Low	Linear Cracking	Monitor Pavement	Monitor Pavement
63	Medium	Linear Cracking	PCC Crack Sealing	PCC Crack Sealing
63	High	Linear Cracking	PCC Full Depth Patching	PCC Crack Sealing
64	Low	Durability Cracking	Monitor Pavement	Monitor Pavement
64	Medium	Durability Cracking	PCC Full Depth Patching	PCC Full Depth Patching
64	High	Durability Cracking	PCC Slab Replacement	PCC Slab Replacement
65	Low	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	Medium	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	High	Jt. Seal Damage	PCC Joint Seal	PCC Joint Seal
66	Low	Small Patch	Monitor Pavement	Monitor Pavement
66	Medium	Small Patch	PCC Partial Depth Patching	Monitor Pavement
66	High	Small Patch	PCC Partial Depth Patching	PCC Partial Depth Patching
67	Low	Large Patch	Monitor Pavement	Monitor Pavement
67	Medium	Large Patch	PCC Full Depth Patching	Monitor Pavement
67	High	Large Patch	PCC Full Depth Patching	PCC Full Depth Patching
68	N/A	Popouts	Monitor Pavement	Monitor Pavement
69	N/A	Pumping	Monitor Pavement	Monitor Pavement
70	Low	Scaling	Monitor Pavement	Monitor Pavement
70	Medium	Scaling	PCC Slab Replacement	Monitor Pavement
70	High	Scaling	PCC Slab Replacement	PCC Slab Replacement
71	Low	Faulting	Monitor Pavement	Monitor Pavement
71	Medium	Faulting	Grinding	Monitor Pavement
71	High	Faulting	PCC Slab Replacement	PCC Slab Replacement
72	Low	Shattered Slab	PCC Crack Sealing	Monitor Pavement
72	Medium	Shattered Slab	PCC Slab Replacement	PCC Crack Sealing
72	High	Shattered Slab	PCC Slab Replacement	PCC Slab Replacement
73	N/A	Shrinkage Cracking	Monitor Pavement	Monitor Pavement



Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
74	Low	Joint Spall	Monitor Pavement	Monitor Pavement
74	Medium	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
74	High	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	Low	Corner Spall	Monitor Pavement	Monitor Pavement
75	Medium	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	High	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
76	Low	ASR	Monitor Pavement	Monitor Pavement
76	Medium	ASR	PCC Slab Replacement	PCC Slab Replacement
76	High	ASR	PCC Slab Replacement	PCC Slab Replacement

## 5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

### 5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average Reliever Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

*Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation*

Rehabilitation Type	Reliever Pavement Section
<b>AC Reconstruction</b>	
<i>Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.</i>  <b>PCI &lt;55</b>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (8")
	Prime Coat
	Tack Coat
	P-401 Surface Course (4")
	<i>Excludes any paved shoulder features</i>
<b>AC Rehabilitation</b>	
<i>Combination of asphalt pavement milling and replacement overlay with 15% of the areas subject to full-depth reconstruction.</i>  <b>PCI = 55 to 70</b>	<b>15% AC Reconstruction</b>
	<b>Mill and Overlay</b>
	AC Milling (3")
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
<b>PCC Reconstruction</b>	
<i>Full-depth rigid pavement section reconstruction.</i>  <b>PCI &lt; 55</b>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (6")
	P-501 PCC Pavement (14")
	PCC Joint Seal
<b>PCC Rehabilitation</b>	
<i>Rehabilitation of PCC pavement with a combination of crack sealing, joint seal replacement, limited patching, and replacement of 15% of slab panels.</i>  <b>PCI = 55 to 70</b>	<b>15% Slab Replacement</b>
	<b>Joint and Crack Seal</b>
	<b>Limited Patching</b>

*The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.*

### **Reconstruction (AC or PCC)**

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

### **AC Rehabilitation**

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

### **PCC Rehabilitation**

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.

#### **5.5.2 Major Rehabilitation Planning-Level Unit Costs**


Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.

Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.


*Table 5.5.2: RL Major Rehabilitation Planning-Level Unit Cost by Pavement Type*

Rehabilitation Type	PCI Range	Asphalt Concrete Cost per SF	Portland Cement Concrete Cost Per SF
Rehabilitation	55 to 70	\$10.50	\$22.50
Reconstruction	0 to 55	\$18.50	\$45.00





# **Chapter 6: M&R Planning and Budget Scenario Analysis**





## Chapter 6 – M&R Planning and Budget Scenario Analysis

### 6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

**Table 6.1 (a)** provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (a): Year 1 Summary of Localized Maintenance*

Work Category	Cost
Preventive	\$ 415,480
Stopgap	\$ -
<b>Planning-Level Localized M&amp;R Needs =</b>	<b>\$ 415,480</b>

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

**Table 6.1 (b)** summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary*

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing	989	LF	\$ 3,990
	Surface Seal	546,691	SF	\$ 410,160
	AC Full-Depth Patching	115	SF	\$ 1,330

**Table 6.1 (c)** provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved “End Condition” PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary*

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
FMY	RW 5-23	6105	100,000	91	91	\$ -
FMY	RW 5-23	6110	50,000	94	94	\$ -
FMY	RW 5-23	6115	280,000	89	89	\$ -
FMY	RW 5-23	6120	140,000	92	92	\$ -
FMY	RW 5-23	6125	20,000	89	89	\$ -
FMY	RW 5-23	6130	10,000	84	84	\$ -
FMY	RW 5-23	6135	50,000	87	87	\$ -
FMY	RW 5-23	6140	25,000	82	82	\$ -
FMY	RW 5-23	6145	155,000	86	86	\$ -
FMY	RW 5-23	6150	77,500	88	88	\$ -
FMY	RW 5-23	6155	35,600	84	86	\$ 150
FMY	RW 5-23	6160	17,800	88	88	\$ -
FMY	RW 13-31	6205	476,075	89	89	\$ 40
FMY	RW 13-31	6210	238,038	92	92	\$ -
FMY	TW A	103	12,403	94	94	\$ -
FMY	TW A	105	51,700	91	91	\$ -
FMY	TW A	110	6,623	79	79	\$ -
FMY	TW A	111	132,526	93	93	\$ -
FMY	TW A	114	73,900	79	79	\$ -
FMY	TW A	115	17,123	64	64	\$ -
FMY	TW A1	123	20,509	94	94	\$ -
FMY	TW A2	125	20,237	94	94	\$ -
FMY	TW A3	145	41,023	93	93	\$ -
FMY	TW A3	150	67,098	54	54	\$ -
FMY	TW A3	153	14,735	94	94	\$ -
FMY	TW A3	155	26,215	94	94	\$ -
FMY	TW A6	175	4,324	60	60	\$ -
FMY	TW A6	178	4,732	94	94	\$ -
FMY	TW A6	180	5,104	94	94	\$ -

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
FMY	TW A7	120	28,228	65	65	\$ -
FMY	TW AP SW	107	14,624	94	94	\$ -
FMY	TW AP SW	112	13,304	91	91	\$ -
FMY	TW B	205	140,345	65	65	\$ -
FMY	TW B	206	21,637	90	90	\$ -
FMY	TW B	208	10,199	94	94	\$ -
FMY	TW B	210	27,327	89	89	\$ -
FMY	TW B	270	2,906	55	55	\$ -
FMY	TW B1	207	19,766	72	82	\$ 7,420
FMY	TW B2	220	11,346	94	94	\$ -
FMY	TW B3	260	11,346	94	94	\$ -
FMY	TW B3	265	8,453	67	67	\$ -
FMY	TW B3	275	59,219	69	69	\$ -
FMY	TW B4	203	24,035	67	67	\$ -
FMY	TW C	240	22,168	91	91	\$ -
FMY	TW C	245	121,801	93	93	\$ -
FMY	TW C	305	162,237	77	85	\$ 12,830
FMY	TW C	306	24,962	94	94	\$ -
FMY	TW C1	310	29,730	69	69	\$ -
FMY	TW C2	320	42,197	75	88	\$ 31,650
FMY	TW C2	520	42,571	76	88	\$ 7,180
FMY	TW C3	525	23,701	88	88	\$ -
FMY	TW C5	330	26,412	94	94	\$ -
FMY	TW C6	335	7,909	90	90	\$ -
FMY	TW C6	345	8,342	89	90	\$ 20
FMY	TW C7	350	15,220	90	90	\$ -
FMY	TW C8	355	15,632	89	89	\$ -
FMY	TW C9	360	9,368	94	94	\$ -
FMY	TW D	134	28,977	94	94	\$ -
FMY	TW D	135	23,050	65	65	\$ -
FMY	TW D	136	9,753	60	60	\$ -
FMY	TW D	137	56,400	64	64	\$ -
FMY	TW D	140	24,471	73	85	\$ 7,360
FMY	TW D	143	9,551	78	83	\$ 720
FMY	TW D2	160	13,679	29	29	\$ -
FMY	TW D3	141	9,322	94	94	\$ -
FMY	TW E	147	22,245	94	94	\$ -
FMY	TW E	165	42,108	94	94	\$ -
FMY	TW E	503	39,478	94	94	\$ -
FMY	TW E	510	48,748	75	86	\$ 21,940
FMY	TW E	512	31,577	73	93	\$ 23,690
FMY	TW E	535	28,366	94	94	\$ -
FMY	TW E1	500	10,310	91	91	\$ -
FMY	TW E2	505	10,138	69	69	\$ -
FMY	TW E2	530	10,056	88	91	\$ 160
FMY	AP E	4505	58,570	75	90	\$ 43,930
FMY	AP E	4515	13,907	83	86	\$ 530

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
FMY	AP E	4520	72,634	74	94	\$ 54,920
FMY	AP E	4525	71,383	80	100	\$ 53,540
FMY	AP E	4530	27,056	81	81	\$ -
FMY	AP HELI	4705	93,555	82	92	\$ 13,860
FMY	AP N	4305	331,067	52	52	\$ -
FMY	AP RU 13	5105	11,434	66	66	\$ -
FMY	AP RU 5	5205	30,022	77	93	\$ 12,390
FMY	AP S	4103	10,783	94	94	\$ -
FMY	AP S	4105	187,842	65	65	\$ -
FMY	AP S	4110	92,757	68	68	\$ -
FMY	AP S	4115	19,731	64	64	\$ -
FMY	AP S	4120	108,068	47	47	\$ -
FMY	AP S	4125	26,416	100	100	\$ -
FMY	AP SE	4415	172,279	39	39	\$ -
FMY	AP SE	4420	249,512	78	84	\$ 30,530
FMY	AP SW	4205	118,829	72	91	\$ 62,090
FMY	AP SW	4215	166,211	47	47	\$ -
FMY	AP SW	4220	49,071	47	47	\$ -
FMY	AP T-HANG	4605	169,083	83	90	\$ 23,810
FMY	AP W	4805	545,226	89	90	\$ 6,670
FMY	AP W	4818	15,664	91	91	\$ -

## 6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b) and (c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

### 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport



given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- » An estimation of current pavement condition;
- » Major pavement rehabilitation needs based on condition and policies; and
- » Planning-level cost estimates for the major rehabilitation needs.

**Table 6.2.1 (a)** summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.


*Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs*


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	FMY	TW A	115	AAC	17,123	63	AC Rehabilitation	\$ 180,000
2023	FMY	TW A3	150	AAC	67,098	53	AC Reconstruction	\$ 1,242,000
2023	FMY	TW A6	175	AAC	4,324	59	AC Rehabilitation	\$ 46,000
2023	FMY	TW A7	120	AAC	28,228	64	AC Rehabilitation	\$ 297,000
2023	FMY	TW B	205	AC	140,345	64	AC Rehabilitation	\$ 1,474,000
2023	FMY	TW B	270	AC	2,906	55	AC Reconstruction	\$ 42,000
2023	FMY	TW B3	265	AC	8,453	66	AC Rehabilitation	\$ 89,000
2023	FMY	TW B3	275	AC	59,219	68	AC Rehabilitation	\$ 622,000
2023	FMY	TW B4	203	AC	24,035	66	AC Rehabilitation	\$ 253,000
2023	FMY	TW C1	310	AC	29,730	68	AC Rehabilitation	\$ 313,000
2023	FMY	TW D	135	AAC	23,050	64	AC Rehabilitation	\$ 243,000
2023	FMY	TW D	136	AC	9,753	59	AC Rehabilitation	\$ 103,000
2023	FMY	TW D	137	AAC	56,400	63	AC Rehabilitation	\$ 593,000
2023	FMY	TW D2	160	AAC	13,679	27	AC Reconstruction	\$ 254,000
2023	FMY	TW E2	505	AC	10,138	68	AC Rehabilitation	\$ 107,000
2023	FMY	AP N	4305	AAC	331,067	50	AC Reconstruction	\$ 6,125,000
2023	FMY	AP RU 13	5105	AC	11,434	65	AC Rehabilitation	\$ 121,000
2023	FMY	AP S	4105	AAC	187,842	63	AC Rehabilitation	\$ 1,973,000
2023	FMY	AP S	4110	AC	92,757	66	AC Rehabilitation	\$ 974,000
2023	FMY	AP S	4115	AC	19,731	63	AC Rehabilitation	\$ 208,000
2023	FMY	AP S	4120	AAC	108,068	45	AC Reconstruction	\$ 2,000,000
2023	FMY	AP SE	4415	AAC	172,279	37	AC Reconstruction	\$ 3,188,000
2023	FMY	AP SW	4215	AC	166,211	46	AC Reconstruction	\$ 3,075,000
2023	FMY	AP SW	4220	AC	49,071	46	AC Reconstruction	\$ 908,000
2024	FMY	TW B1	207	AC	19,766	70	AC Rehabilitation	\$ 218,000
2024	FMY	AP SW	4205	AC	118,829	69	AC Rehabilitation	\$ 1,311,000
2025	FMY	TW D	140	AAC	24,471	69	AC Rehabilitation	\$ 284,000
2025	FMY	TW E	512	AC	31,577	70	AC Rehabilitation	\$ 366,000
2025	FMY	AP E	4505	AC	58,570	70	AC Rehabilitation	\$ 679,000

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2025	FMY	AP E	4520	AC	72,634	69	AC Rehabilitation	\$ 841,000
2026	FMY	AP RU 5	5205	AC	30,022	70	AC Rehabilitation	\$ 365,000
2027	FMY	TW C2	320	AC	42,197	69	AC Rehabilitation	\$ 539,000
2027	FMY	TW C2	520	AC	42,571	70	AC Rehabilitation	\$ 544,000
2027	FMY	TW E	510	AC	48,748	69	AC Rehabilitation	\$ 623,000
2027	FMY	AP SE	4420	AC	249,512	69	AC Rehabilitation	\$ 3,185,000
2028	FMY	TW C	305	AC	162,237	70	AC Rehabilitation	\$ 2,175,000
2028	FMY	AP E	4525	AC	71,383	69	AC Rehabilitation	\$ 957,000
2029	FMY	RW 5-23	6140	AAC	25,000	70	AC Rehabilitation	\$ 352,000
2029	FMY	TW A	110	AAC	6,623	69	AC Rehabilitation	\$ 94,000
2029	FMY	TW A	114	AAC	73,900	69	AC Rehabilitation	\$ 1,040,000
2029	FMY	TW D	143	AC	9,551	69	AC Rehabilitation	\$ 135,000
2029	FMY	AP E	4530	AC	27,056	69	AC Rehabilitation	\$ 381,000
2029	FMY	AP HELI	4705	AC	93,555	69	AC Rehabilitation	\$ 1,317,000
2030	FMY	RW 5-23	6130	AAC	10,000	70	AC Rehabilitation	\$ 148,000
2030	FMY	RW 5-23	6155	AAC	35,600	70	AC Rehabilitation	\$ 526,000
2030	FMY	AP E	4515	AC	13,907	69	AC Rehabilitation	\$ 206,000
2030	FMY	AP T-HANG	4605	AC	169,083	69	AC Rehabilitation	\$ 2,499,000
2032	FMY	RW 5-23	6135	AAC	50,000	69	AC Rehabilitation	\$ 815,000
2032	FMY	RW 5-23	6145	AAC	155,000	68	AC Rehabilitation	\$ 2,525,000
2032	FMY	AP W	4805	AC	545,226	70	AC Rehabilitation	\$ 8,882,000

**Figure 6.2.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

*Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year*





TW A:115 2023   AC REHAB \$0.18 M	TW A7:120 2023   AC REHAB \$0.30 M	TW D:135 2023   AC REHAB \$0.24 M	TW D:136 2023   AC REHAB \$0.10 M	TW D:137 2023   AC REHAB \$0.59 M
TW A3:150 2023   AC RECON \$1.24 M	TW D2:160 2023   AC RECON \$0.25 M	TW A6:175 2023   AC REHAB \$0.05 M	TW B4:203 2023   AC REHAB \$0.25 M	TW B:205 2023   AC REHAB \$1.47 M
TW B3:265 2023   AC REHAB \$0.09 M	TW B:270 2023   AC REHAB \$0.04 M	TW B3:275 2023   AC REHAB \$0.62 M	TW C1:310 2023   AC REHAB \$0.31 M	TW E2:505 2023   AC REHAB \$0.11 M
AP S:4105 2023   AC REHAB \$1.97 M	AP S:4110 2023   AC REHAB \$0.97 M	AP S:4115 2023   AC REHAB \$0.21 M	AP S:4120 2023   AC RECON \$2.00 M	AP SW:4215 2023   AC RECON \$3.08 M
AP SW:4220 2023   AC RECON \$0.91 M	AP N:4305 2023   AC RECON \$6.13 M	AP SE:4415 2023   AC RECON \$3.19 M	AP RU 13:5105 2023   AC REHAB \$0.12 M	TW B1:207 2024   AC REHAB \$0.22 M
AP SW:4205 2024   AC REHAB \$1.31 M	TW D:140 2025   AC REHAB \$0.28 M	TW E:512 2025   AC REHAB \$0.37 M	AP E:4505 2025   AC REHAB \$0.68 M	AP E:4520 2025   AC REHAB \$0.84 M
AP RU 5:5205 2026   AC REHAB \$0.37 M	TW C2:320 2027   AC REHAB \$0.54 M	TW E:510 2027   AC REHAB \$0.62 M	TW C2:520 2027   AC REHAB \$0.54 M	AP SE:4420 2027   AC REHAB \$3.19 M
TW C:305 2028   AC REHAB \$2.18 M	AP E:4525 2028   AC REHAB \$0.96 M	TW A:110 2029   AC REHAB \$0.09 M	TW A:114 2029   AC REHAB \$1.04 M	TW D:143 2029   AC REHAB \$0.14 M
AP E:4530 2029   AC REHAB \$0.38 M	AP HELI:4705 2029   AC REHAB \$1.32 M	RW 5-23:6140 2029   AC REHAB \$0.35 M	AP E:4515 2030   AC REHAB \$0.21 M	AP T-HANG:4605 2030   AC REHAB \$2.50 M
RW 5-23:6130 2030   AC REHAB \$0.15 M	RW 5-23:6155 2030   AC REHAB \$0.53 M	AP W:4805 2032   AC REHAB \$8.88 M	RW 5-23:6135 2032   AC REHAB \$0.82 M	RW 5-23:6145 2032   AC REHAB \$2.53 M

LEGEND

RW 13-31

TW A

AP S

TYPICAL RUNWAY BRANCH ID

TYPICAL TAXIWAY BRANCH ID

TYPICAL APRON BRANCH ID

PROGRAM YEAR

2023

2024

2025

2026

2027

2028

2029

2030

2031

2032

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





# Chapter 7: Conclusion



## Chapter 7 – Conclusion

### 7.1 Recommendations

#### 7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

#### 7.1.3 Major Rehabilitation

**Chapter 6** also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

#### 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- » Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in **Section 6.1**;
- » Further refine and implement the identified 10-year major rehabilitation needs provided in **Section 6.2**;
- » Maintain detailed records on pavement maintenance, construction, and inspection; and
- » Maintain records on major pavement construction projects (year, scope, cost, and construction documents).

## 7.2 Supporting Documents

### Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

### Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

### Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

### Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

### Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

### Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.



## 7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

## 7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- » ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- » AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- » AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- » AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- » Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- » Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- » Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.



A photograph of a long, straight airfield runway stretching towards the horizon under a bright blue sky filled with large, white cumulus clouds. The runway surface is dark asphalt with a central white dashed line and yellow edge lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Appendix A: Airfield Pavement Analysis**

A close-up, low-angle view of the runway pavement, showing the texture of the asphalt and the white dashed center line. A series of yellow chevron markings are visible on the right side of the frame. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

*Table A.1: Pavement System Inventory Details*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
FMY	RW 5-23	Runway	6105	100,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6110	50,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6115	280,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6120	140,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6125	20,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6130	10,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6135	50,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6140	25,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6145	155,000	AAC	1/1/2017
FMY	RW 5-23	Runway	6150	77,500	AAC	1/1/2017
FMY	RW 5-23	Runway	6155	35,600	AAC	1/1/2017
FMY	RW 5-23	Runway	6160	17,800	AAC	1/1/2017
FMY	RW 13-31	Runway	6205	476,075	AAC	1/1/2018
FMY	RW 13-31	Runway	6210	238,038	AC	1/1/2018
FMY	TW A	Taxiway	103	12,403	AC	1/1/2017
FMY	TW A	Taxiway	105	51,700	AAC	1/1/2017
FMY	TW A	Taxiway	110	6,623	AAC	1/1/2018
FMY	TW A	Taxiway	111	132,526	AC	1/1/2017
FMY	TW A	Taxiway	114	73,900	AAC	1/1/2017
FMY	TW A	Taxiway	115	17,123	AAC	1/1/1991
FMY	TW A1	Taxiway	123	20,509	AC	1/1/2017
FMY	TW A2	Taxiway	125	20,237	AC	1/1/2017
FMY	TW A3	Taxiway	145	41,023	AC	1/1/2017
FMY	TW A3	Taxiway	150	67,098	AAC	1/1/1991
FMY	TW A3	Taxiway	153	14,735	AC	1/1/2018
FMY	TW A3	Taxiway	155	26,215	AC	1/1/2017
FMY	TW A6	Taxiway	175	4,324	AAC	1/1/1991
FMY	TW A6	Taxiway	178	4,732	AAC	1/1/2017
FMY	TW A6	Taxiway	180	5,104	AC	1/1/2017
FMY	TW A7	Taxiway	120	28,228	AAC	1/1/1991
FMY	TW AP SW	Taxiway	107	14,624	AC	1/1/2017
FMY	TW AP SW	Taxiway	112	13,304	AC	1/1/2017
FMY	TW B	Taxiway	205	140,345	AC	1/1/1977
FMY	TW B	Taxiway	206	21,637	AC	1/1/2017
FMY	TW B	Taxiway	208	10,199	AAC	1/1/2017
FMY	TW B	Taxiway	210	27,327	AC	1/1/2017
FMY	TW B	Taxiway	270	2,906	AC	1/1/1998
FMY	TW B1	Taxiway	207	19,766	AC	1/1/1997
FMY	TW B2	Taxiway	220	11,346	AC	1/1/2018
FMY	TW B3	Taxiway	260	11,346	AC	1/1/2018
FMY	TW B3	Taxiway	265	8,453	AC	1/1/1998
FMY	TW B3	Taxiway	275	59,219	AC	1/1/1998
FMY	TW B4	Taxiway	203	24,035	AC	1/1/1977
FMY	TW C	Taxiway	240	22,168	AC	1/1/2017

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
FMY	TW C	Taxiway	245	121,801	AC	1/1/2017
FMY	TW C	Taxiway	305	162,237	AC	1/1/2007
FMY	TW C	Taxiway	306	24,962	AC	1/1/2017
FMY	TW C1	Taxiway	310	29,730	AC	1/1/2007
FMY	TW C2	Taxiway	320	42,197	AC	1/1/2007
FMY	TW C2	Taxiway	520	42,571	AC	1/1/2009
FMY	TW C3	Taxiway	525	23,701	AC	1/1/2009
FMY	TW C5	Taxiway	330	26,412	AC	1/1/2017
FMY	TW C6	Taxiway	335	7,909	AAC	1/1/2017
FMY	TW C6	Taxiway	345	8,342	AC	1/1/2017
FMY	TW C7	Taxiway	350	15,220	AC	1/1/2017
FMY	TW C8	Taxiway	355	15,632	AC	1/1/2017
FMY	TW C9	Taxiway	360	9,368	AC	1/1/2017
FMY	TW D	Taxiway	134	28,977	AC	1/1/2017
FMY	TW D	Taxiway	135	23,050	AAC	1/1/1998
FMY	TW D	Taxiway	136	9,753	AC	1/1/1998
FMY	TW D	Taxiway	137	56,400	AAC	1/1/1998
FMY	TW D	Taxiway	140	24,471	AAC	1/1/1998
FMY	TW D	Taxiway	143	9,551	AC	1/1/1998
FMY	TW D2	Taxiway	160	13,679	AAC	1/1/1977
FMY	TW D3	Taxiway	141	9,322	AC	1/1/2018
FMY	TW E	Taxiway	147	22,245	AC	1/1/2017
FMY	TW E	Taxiway	165	42,108	AC	1/1/2017
FMY	TW E	Taxiway	503	39,478	AC	1/1/2018
FMY	TW E	Taxiway	510	48,748	AC	1/1/2007
FMY	TW E	Taxiway	512	31,577	AC	1/1/2007
FMY	TW E	Taxiway	535	28,366	AC	1/1/2017
FMY	TW E1	Taxiway	500	10,310	AC	1/1/2018
FMY	TW E2	Taxiway	505	10,138	AC	1/1/2007
FMY	TW E2	Taxiway	530	10,056	AC	1/1/2009
FMY	AP E	Apron	4505	58,570	AC	1/1/2002
FMY	AP E	Apron	4515	13,907	AC	1/1/2002
FMY	AP E	Apron	4520	72,634	AC	1/1/2002
FMY	AP E	Apron	4525	71,383	AC	1/1/2002
FMY	AP E	Apron	4530	27,056	AC	1/1/2002
FMY	AP HELI	Apron	4705	93,555	AC	1/1/2007
FMY	AP N	Apron	4305	331,067	AAC	1/1/1998
FMY	AP RU 13	Apron	5105	11,434	AC	12/25/1999
FMY	AP RU 5	Apron	5205	30,022	AC	1/1/2007
FMY	AP S	Apron	4103	10,783	AAC	1/1/2017
FMY	AP S	Apron	4105	187,842	AAC	1/1/1998
FMY	AP S	Apron	4110	92,757	AC	1/1/1998
FMY	AP S	Apron	4115	19,731	AC	1/1/2003
FMY	AP S	Apron	4120	108,068	AAC	1/1/1998
FMY	AP S	Apron	4125	26,416	AAC	7/1/2020
FMY	AP SE	Apron	4415	172,279	AAC	1/1/1998

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
FMY	AP SE	Apron	4420	249,512	AC	1/1/2006
FMY	AP SW	Apron	4205	118,829	AC	1/1/1998
FMY	AP SW	Apron	4215	166,211	AC	1/1/1966
FMY	AP SW	Apron	4220	49,071	AC	1/1/1998
FMY	AP T-HANG	Apron	4605	169,083	AC	1/1/2006
FMY	AP W	Apron	4805	545,226	AC	1/1/2009
FMY	AP W	Apron	4818	15,664	PCC	1/1/2009



*Table A.2: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
FMY	RW 5-23	Runway	6105	100,000	91	Good
FMY	RW 5-23	Runway	6110	50,000	94	Good
FMY	RW 5-23	Runway	6115	280,000	89	Good
FMY	RW 5-23	Runway	6120	140,000	92	Good
FMY	RW 5-23	Runway	6125	20,000	89	Good
FMY	RW 5-23	Runway	6130	10,000	84	Satisfactory
FMY	RW 5-23	Runway	6135	50,000	87	Good
FMY	RW 5-23	Runway	6140	25,000	82	Satisfactory
FMY	RW 5-23	Runway	6145	155,000	86	Good
FMY	RW 5-23	Runway	6150	77,500	88	Good
FMY	RW 5-23	Runway	6155	35,600	84	Satisfactory
FMY	RW 5-23	Runway	6160	17,800	88	Good
FMY	RW 13-31	Runway	6205	476,075	89	Good
FMY	RW 13-31	Runway	6210	238,038	92	Good
FMY	TW A	Taxiway	103	12,403	94	Good
FMY	TW A	Taxiway	105	51,700	91	Good
FMY	TW A	Taxiway	110	6,623	79	Satisfactory
FMY	TW A	Taxiway	111	132,526	93	Good
FMY	TW A	Taxiway	114	73,900	79	Satisfactory
FMY	TW A	Taxiway	115	17,123	64	Fair
FMY	TW A1	Taxiway	123	20,509	94	Good
FMY	TW A2	Taxiway	125	20,237	94	Good
FMY	TW A3	Taxiway	145	41,023	93	Good
FMY	TW A3	Taxiway	150	67,098	54	Poor
FMY	TW A3	Taxiway	153	14,735	94	Good
FMY	TW A3	Taxiway	155	26,215	94	Good
FMY	TW A6	Taxiway	175	4,324	60	Fair
FMY	TW A6	Taxiway	178	4,732	94	Good
FMY	TW A6	Taxiway	180	5,104	94	Good
FMY	TW A7	Taxiway	120	28,228	65	Fair
FMY	TW AP SW	Taxiway	107	14,624	94	Good
FMY	TW AP SW	Taxiway	112	13,304	91	Good
FMY	TW B	Taxiway	205	140,345	65	Fair
FMY	TW B	Taxiway	206	21,637	90	Good
FMY	TW B	Taxiway	208	10,199	94	Good
FMY	TW B	Taxiway	210	27,327	89	Good
FMY	TW B	Taxiway	270	2,906	55	Poor
FMY	TW B1	Taxiway	207	19,766	72	Satisfactory
FMY	TW B2	Taxiway	220	11,346	94	Good
FMY	TW B3	Taxiway	260	11,346	94	Good
FMY	TW B3	Taxiway	265	8,453	67	Fair
FMY	TW B3	Taxiway	275	59,219	69	Fair
FMY	TW B4	Taxiway	203	24,035	67	Fair
FMY	TW C	Taxiway	240	22,168	91	Good
FMY	TW C	Taxiway	245	121,801	93	Good

# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

2022

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
FMY	TW C	Taxiway	305	162,237	77	Satisfactory
FMY	TW C	Taxiway	306	24,962	94	Good
FMY	TW C1	Taxiway	310	29,730	69	Fair
FMY	TW C2	Taxiway	320	42,197	75	Satisfactory
FMY	TW C2	Taxiway	520	42,571	76	Satisfactory
FMY	TW C3	Taxiway	525	23,701	88	Good
FMY	TW C5	Taxiway	330	26,412	94	Good
FMY	TW C6	Taxiway	335	7,909	90	Good
FMY	TW C6	Taxiway	345	8,342	89	Good
FMY	TW C7	Taxiway	350	15,220	90	Good
FMY	TW C8	Taxiway	355	15,632	89	Good
FMY	TW C9	Taxiway	360	9,368	94	Good
FMY	TW D	Taxiway	134	28,977	94	Good
FMY	TW D	Taxiway	135	23,050	65	Fair
FMY	TW D	Taxiway	136	9,753	60	Fair
FMY	TW D	Taxiway	137	56,400	64	Fair
FMY	TW D	Taxiway	140	24,471	73	Satisfactory
FMY	TW D	Taxiway	143	9,551	78	Satisfactory
FMY	TW D2	Taxiway	160	13,679	29	Very Poor
FMY	TW D3	Taxiway	141	9,322	94	Good
FMY	TW E	Taxiway	147	22,245	94	Good
FMY	TW E	Taxiway	165	42,108	94	Good
FMY	TW E	Taxiway	503	39,478	94	Good
FMY	TW E	Taxiway	510	48,748	75	Satisfactory
FMY	TW E	Taxiway	512	31,577	73	Satisfactory
FMY	TW E	Taxiway	535	28,366	94	Good
FMY	TW E1	Taxiway	500	10,310	91	Good
FMY	TW E2	Taxiway	505	10,138	69	Fair
FMY	TW E2	Taxiway	530	10,056	88	Good
FMY	AP E	Apron	4505	58,570	75	Satisfactory
FMY	AP E	Apron	4515	13,907	83	Satisfactory
FMY	AP E	Apron	4520	72,634	74	Satisfactory
FMY	AP E	Apron	4525	71,383	80	Satisfactory
FMY	AP E	Apron	4530	27,056	81	Satisfactory
FMY	AP HELI	Apron	4705	93,555	82	Satisfactory
FMY	AP N	Apron	4305	331,067	52	Poor
FMY	AP RU 13	Apron	5105	11,434	66	Fair
FMY	AP RU 5	Apron	5205	30,022	77	Satisfactory
FMY	AP S	Apron	4103	10,783	94	Good
FMY	AP S	Apron	4105	187,842	65	Fair
FMY	AP S	Apron	4110	92,757	68	Fair
FMY	AP S	Apron	4115	19,731	64	Fair
FMY	AP S	Apron	4120	108,068	47	Poor
FMY	AP S	Apron	4125	26,416	100	Good
FMY	AP SE	Apron	4415	172,279	39	Very Poor
FMY	AP SE	Apron	4420	249,512	78	Satisfactory
FMY	AP SW	Apron	4205	118,829	72	Satisfactory

# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
FMY	AP SW	Apron	4215	166,211	47	Poor
FMY	AP SW	Apron	4220	49,071	47	Poor
FMY	AP T-HANG	Apron	4605	169,083	83	Satisfactory
FMY	AP W	Apron	4805	545,226	89	Good
FMY	AP W	Apron	4818	15,664	91	Good

*Table A.3: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	RW 5-23	6105	91	89	87	86	84	82	80	79	77	75	73
FMY	RW 5-23	6110	94	92	90	89	87	85	83	82	80	78	76
FMY	RW 5-23	6115	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 5-23	6120	92	90	88	87	85	83	81	80	78	76	74
FMY	RW 5-23	6125	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 5-23	6130	84	82	80	79	77	75	73	72	70	68	66
FMY	RW 5-23	6135	87	85	83	82	80	78	76	75	73	71	69
FMY	RW 5-23	6140	82	80	78	77	75	73	71	70	68	66	64
FMY	RW 5-23	6145	86	84	82	81	79	77	75	74	72	70	68
FMY	RW 5-23	6150	88	86	84	83	81	79	77	76	74	72	70
FMY	RW 5-23	6155	84	82	80	79	77	75	73	72	70	68	66
FMY	RW 5-23	6160	88	86	84	83	81	79	77	76	74	72	70
FMY	RW 13-31	6205	89	87	85	84	82	80	78	77	75	73	71
FMY	RW 13-31	6210	92	89	87	85	83	82	80	78	77	76	75
FMY	TW A	103	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A	105	91	89	87	85	83	81	79	77	76	74	73
FMY	TW A	110	79	77	76	74	73	71	70	69	68	67	66
FMY	TW A	111	93	91	89	87	85	83	81	80	78	77	76
FMY	TW A	114	79	77	76	74	73	71	70	69	68	67	66
FMY	TW A	115	64	63	62	61	61	60	59	58	58	57	56
FMY	TW A1	123	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A2	125	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A3	145	93	91	89	87	85	83	81	80	78	77	76
FMY	TW A3	150	54	53	52	51	51	50	49	48	46	45	44
FMY	TW A3	153	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A3	155	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A6	175	60	59	58	58	57	56	56	55	54	53	53
FMY	TW A6	178	94	91	89	87	85	83	81	80	78	76	75
FMY	TW A6	180	94	92	90	88	86	84	82	81	79	78	76
FMY	TW A7	120	65	64	63	62	61	61	60	59	58	58	57
FMY	TW AP SW	107	94	92	90	88	86	84	82	81	79	78	76
FMY	TW AP SW	112	91	89	87	85	83	82	80	78	77	76	74
FMY	TW B	205	65	64	63	63	62	62	61	61	60	60	59
FMY	TW B	206	90	88	86	84	82	81	79	78	76	75	74
FMY	TW B	208	94	91	89	87	85	83	81	80	78	76	75
FMY	TW B	210	89	87	85	83	82	80	78	77	76	74	73
FMY	TW B	270	55	55	54	54	53	53	52	52	51	51	50
FMY	TW B1	207	72	71	70	69	68	67	66	65	64	64	63
FMY	TW B2	220	94	92	90	88	86	84	82	81	79	78	76
FMY	TW B3	260	94	92	90	88	86	84	82	81	79	78	76
FMY	TW B3	265	67	66	65	65	64	63	62	62	61	61	60
FMY	TW B3	275	69	68	67	66	65	65	64	63	63	62	61
FMY	TW B4	203	67	66	65	65	64	63	62	62	61	61	60
FMY	TW C	240	91	89	87	85	83	82	80	78	77	76	74



Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	TW C	245	93	91	89	87	85	83	81	80	78	77	76
FMY	TW C	305	77	75	74	73	72	71	70	69	68	67	66
FMY	TW C	306	94	92	90	88	86	84	82	81	79	78	76
FMY	TW C1	310	69	68	67	66	65	65	64	63	63	62	61
FMY	TW C2	320	75	74	72	71	70	69	68	67	66	66	65
FMY	TW C2	520	76	75	73	72	71	70	69	68	67	66	65
FMY	TW C3	525	88	86	84	82	81	79	78	76	75	74	72
FMY	TW C5	330	94	92	90	88	86	84	82	81	79	78	76
FMY	TW C6	335	90	88	86	84	82	80	78	77	75	74	72
FMY	TW C6	345	89	87	85	83	82	80	78	77	76	74	73
FMY	TW C7	350	90	88	86	84	82	81	79	78	76	75	74
FMY	TW C8	355	89	87	85	83	82	80	78	77	76	74	73
FMY	TW C9	360	94	92	90	88	86	84	82	81	79	78	76
FMY	TW D	134	94	92	90	88	86	84	82	81	79	78	76
FMY	TW D	135	65	64	63	62	61	61	60	59	58	58	57
FMY	TW D	136	60	59	59	59	58	58	57	57	56	56	56
FMY	TW D	137	64	63	62	61	61	60	59	58	58	57	56
FMY	TW D	140	73	71	70	69	68	67	66	65	64	63	62
FMY	TW D	143	78	76	75	74	73	71	70	69	68	67	67
FMY	TW D2	160	29	27	25	23	21	19	17	15	13	11	9
FMY	TW D3	141	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	147	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	165	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	503	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E	510	75	74	72	71	70	69	68	67	66	66	65
FMY	TW E	512	73	72	71	70	69	68	67	66	65	64	64
FMY	TW E	535	94	92	90	88	86	84	82	81	79	78	76
FMY	TW E1	500	91	89	87	85	83	82	80	78	77	76	74
FMY	TW E2	505	69	68	67	66	65	65	64	63	63	62	61
FMY	TW E2	530	88	86	84	82	81	79	78	76	75	74	72
FMY	AP E	4505	75	73	71	70	68	67	65	64	63	62	61
FMY	AP E	4515	83	81	79	77	75	73	72	70	69	67	66
FMY	AP E	4520	74	72	70	69	67	66	65	63	62	61	60
FMY	AP E	4525	80	78	76	74	72	71	69	68	66	65	64
FMY	AP E	4530	81	79	77	75	73	72	70	69	67	66	64
FMY	AP HELI	4705	82	80	78	76	74	73	71	69	68	66	65
FMY	AP N	4305	52	50	47	45	43	41	39	36	34	32	30
FMY	AP RU 13	5105	66	65	63	62	61	60	59	58	57	57	56
FMY	AP RU 5	5205	77	75	73	72	70	68	67	66	64	63	62
FMY	AP S	4103	94	92	89	87	85	83	81	78	76	74	72
FMY	AP S	4105	65	63	60	58	56	54	52	49	47	45	43
FMY	AP S	4110	68	66	65	64	63	61	60	59	59	58	57
FMY	AP S	4115	64	63	62	60	59	59	58	57	56	56	55
FMY	AP S	4120	47	45	42	40	38	36	34	31	29	27	25
FMY	AP S	4125	100	93	91	89	87	85	82	80	78	76	74
FMY	AP SE	4415	39	37	34	32	30	28	26	23	21	19	17

# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
FMY	AP SE	4420	78	76	74	72	71	69	68	66	65	64	63
FMY	AP SW	4205	72	70	69	67	66	64	63	62	61	60	59
FMY	AP SW	4215	47	46	45	44	42	41	39	37	35	33	30
FMY	AP SW	4220	47	46	45	44	42	41	39	37	35	33	30
FMY	AP T-HANG	4605	83	81	79	77	75	73	72	70	69	67	66
FMY	AP W	4805	89	87	85	83	81	79	77	75	73	72	70
FMY	AP W	4818	91	90	89	87	86	85	84	83	82	80	79

11/18/2022

## Work History Report

Page 1 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: AP E	EAST APRON		Section: 4505	Surface: AC
L.C.D. 1/1/2002	Use: APRON	Rank: P	Length: 180.00 (Ft)	Width: 140.00 (Ft)	True Area: 58570.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1998 AC PAVEMENT UNKNOWN SECTION*
1/1/2002	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: AP E	EAST APRON		Section: 4515	Surface: AC
L.C.D. 1/1/2002	Use: APRON	Rank: P	Length: 270.00 (Ft)	Width: 50.00 (Ft)	True Area: 13907.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2002	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: AP E	EAST APRON		Section: 4520	Surface: AC
L.C.D. 1/1/2002	Use: APRON	Rank: P	Length: 490.00 (Ft)	Width: 300.00 (Ft)	True Area: 72634.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2002	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: AP E	EAST APRON		Section: 4525	Surface: AC
L.C.D. 1/1/2002	Use: APRON	Rank: P	Length: 345.00 (Ft)	Width: 290.00 (Ft)	True Area: 71383.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2002	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: AP E	EAST APRON		Section: 4530	Surface: AC
L.C.D. 1/1/2002	Use: APRON	Rank: P	Length: 910.00 (Ft)	Width: 20.00 (Ft)	True Area: 27056.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/2002	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: AP HELI	HELICOPTER AP		Section: 4705	Surface: AC
L.C.D. 1/1/2007	Use: APRON	Rank: P	Length: 765.00 (Ft)	Width: 135.00 (Ft)	True Area: 93555.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

11/18/2022

## Work History Report

Page 2 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: AP N	NORTH APRON		Section: 4305	Surface: AAC
L.C.D. 1/1/1998	Use: APRON	Rank: P	Length: 1,225.00 (Ft)	Width: 272.00 (Ft)	True Area: 331067.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2013	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	PAVER X REJUVENATION
1/1/1998	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	1998 3" P401 AC OVERLAY*
1/1/1974	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1974 3" P401 AC SURFACE ON 10" P211 LIMEROCK BASE*

Network: PAGE FIELD		Branch: AP RU 13	RUN-UP APRON		Section: 5105	Surface: AC
L.C.D. 12/25/199	Use: APRON	Rank: P	Length: 160.00 (Ft)	Width: 60.00 (Ft)	True Area: 11434.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2020	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: AP RU 5	RUN-UP APRON		Section: 5205	Surface: AC
L.C.D. 1/1/2007	Use: APRON	Rank: P	Length: 305.00 (Ft)	Width: 105.00 (Ft)	True Area: 30022.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: AP S	SOUTH APRON		Section: 4103	Surface: AAC
L.C.D. 1/1/2017	Use: APRON	Rank: P	Length: 137.00 (Ft)	Width: 80.00 (Ft)	True Area: 10783.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1998	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	1998 3" P401 AC OVERLAY*
1/1/1968	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1968 1" AC SURFACE ON 6" LIMEROCK BASE*

Network: PAGE FIELD		Branch: AP S	SOUTH APRON		Section: 4105	Surface: AAC
L.C.D. 1/1/1998	Use: APRON	Rank: P	Length: 1,060.00 (Ft)	Width: 175.00 (Ft)	True Area: 187842.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1998	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	1998 3" P401 AC OVERLAY*
1/1/1968	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1968 1" AC SURFACE ON 6" LIMEROCK BASE*

Network: PAGE FIELD		Branch: AP S	SOUTH APRON		Section: 4110	Surface: AC
L.C.D. 1/1/1998	Use: APRON	Rank: P	Length: 255.00 (Ft)	Width: 530.00 (Ft)	True Area: 92757.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1998	IMPORT ED	BUILT	0.00	0.50	<input checked="" type="checkbox"/>	1998 1 1/2" P311 AC SURFACE ON 2 1/2" AC BASE ON 6" P211 LIME



11/18/2022

## Work History Report

Page 3 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: AP S		SOUTH APRON		Section: 4115	Surface: AC
L.C.D. 1/1/2003	Use: APRON	Rank: P	Length: 165.00 (Ft)	Width: 147.00 (Ft)	True Area: 19731.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2003	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: AP S		SOUTH APRON		Section: 4120	Surface: AAC
L.C.D. 1/1/1998	Use: APRON	Rank: P	Length: 730.00 (Ft)	Width: 200.00 (Ft)	True Area: 108068.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1998 P401 AC OVERLAY*	
1/1/1970	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	EST 1970 AC PAVEMENT UNKNOWN SECTION*	

Network: PAGE FIELD		Branch: AP S		SOUTH APRON		Section: 4125	Surface: AAC
L.C.D. 7/1/2020	Use: APRON	Rank: P	Length: 285.00 (Ft)	Width: 90.00 (Ft)	True Area: 26416.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
7/1/2020	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1998 P401 AC OVERLAY*	
1/1/1970	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	EST 1970 AC PAVEMENT UNKNOWN SECTION*	

Network: PAGE FIELD		Branch: AP SE		SOUTHEAST AP		Section: 4415	Surface: AAC
L.C.D. 1/1/1998	Use: APRON	Rank: P	Length: 525.00 (Ft)	Width: 323.00 (Ft)	True Area: 172279.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1998 2" P401 AC OVERLAY*	
1/1/1998	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	2" P401 AC SURFACE ON 6" P211 LIMEROCK BASE*	

Network: PAGE FIELD		Branch: AP SE		SOUTHEAST AP		Section: 4420	Surface: AC
L.C.D. 1/1/2006	Use: APRON	Rank: P	Length: 648.00 (Ft)	Width: 385.00 (Ft)	True Area: 249512.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1998	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1998 3" P401 AC SURFACE ON 6" P211 LIMEROCK BASE*	

Network: PAGE FIELD		Branch: AP SW		SOUTHWEST AP		Section: 4205	Surface: AC
L.C.D. 1/1/1998	Use: APRON	Rank: P	Length: 120.00 (Ft)	Width: 1046.00 (Ft)	True Area: 118829.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	IMPORT ED	BUILT	0.00	0.50	<input checked="" type="checkbox"/>	1998 1 1/2" P311 AC SURFACE ON 1 1/2" P280 BASE ON 6" P211 LIME	

11/18/2022

## Work History Report

Page 4 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: AP SW		SOUTHWEST AP		Section: 4215	Surface: AC
L.C.D.	1/1/1966	Use: APRON	Rank: P	Length: 446.00 (Ft)	Width: 386.00 (Ft)	True Area: 166211.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1998 SLURRY SEAL*	
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1966 2" AC SURFACE ON 3" MINI	

Network: PAGE FIELD		Branch: AP SW		SOUTHWEST AP		Section: 4220	Surface: AC
L.C.D.	1/1/1998	Use: APRON	Rank: P	Length: 392.00 (Ft)	Width: 127.00 (Ft)	True Area: 49071.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1998 SLURRY SEAL*	

Network: PAGE FIELD		Branch: AP T-HANG		APRON T-HANG		Section: 4605	Surface: AC
L.C.D.	1/1/2006	Use: APRON	Rank: P	Length: 2,568.00 (Ft)	Width: 75.00 (Ft)	True Area: 169083.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2006	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: AP W		WEST APRON		Section: 4805	Surface: AC
L.C.D.	1/1/2009	Use: APRON	Rank: P	Length: 1,519.00 (Ft)	Width: 388.00 (Ft)	True Area: 545226.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2021	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	PORTIONS OF SECT 4805. PAVER	
7/1/2013	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>		
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: AP W		WEST APRON		Section: 4818	Surface: PCC
L.C.D.	1/1/2009	Use: APRON	Rank: P	Length: 125.00 (Ft)	Width: 125.00 (Ft)	True Area: 15664.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: RW 13-31		RUNWAY 13-31		Section: 6205	Surface: AAC
L.C.D.	1/1/2018	Use: RUNWAY	Rank: P	Length: 4,795.00 (Ft)	Width: 100.00 (Ft)	True Area: 476075.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1977 P-401 OVERLAY	
1/1/1977	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1977	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>		

11/18/2022

## Work History Report

Page 5 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: RW 13-31		RUNWAY 13-31		Section: 6210	Surface: AC
L.C.D. 1/1/2018		Use: RUNWAY	Rank: P	Length: 9,622.00 (Ft)	Width: 25.00 (Ft)	True Area: 238038.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2018	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1977 BIT OVERLAY 4" P-401 4.5" P-212	
1/1/1977	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1977	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: RW 5-23		RUNWAY 5-23		Section: 6105	Surface: AAC
L.C.D. 1/1/2017		Use: RUNWAY	Rank: P	Length: 1,000.00 (Ft)	Width: 100.00 (Ft)	True Area: 100000.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay 1997 NOMINAL 3" P401 AC OVER 1976 P401 AC SURFACE ON 8" P21	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1976	NC-AC	New Construction - AC	0.00	8.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: RW 5-23		RUNWAY 5-23		Section: 6110	Surface: AAC
L.C.D. 1/1/2017		Use: RUNWAY	Rank: P	Length: 2,000.00 (Ft)	Width: 25.00 (Ft)	True Area: 50000.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1997 NOMINAL 1 1/2" P401 AC OV 1976 P401 AC SURFACE ON 8" P21	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	0.50	<input checked="" type="checkbox"/>		
1/1/1976	NC-AC	New Construction - AC	0.00	8.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: RW 5-23		RUNWAY 5-23		Section: 6115	Surface: AAC
L.C.D. 1/1/2017		Use: RUNWAY	Rank: P	Length: 2,800.00 (Ft)	Width: 100.00 (Ft)	True Area: 280000.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay 1997 3" NOMINAL P401 AC OVER 1976 P401 AC OVERLAY ON 1966	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1976	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: RW 5-23		RUNWAY 5-23		Section: 6120	Surface: AAC
L.C.D. 1/1/2017		Use: RUNWAY	Rank: P	Length: 5,581.00 (Ft)	Width: 25.00 (Ft)	True Area: 140000.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay 1997 NOMINAL 1 1/2" P401 AC OV 1976 P401 AC OVERLAY 1966 2" P401 AC PAVEMENT	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	0.50	<input checked="" type="checkbox"/>		
1/1/1976	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>		

11/18/2022

## Work History Report

Page 6 of 18

Pavement Database: FDOT

<b>Network:</b> PAGE FIELD		<b>Branch:</b> RW 5-23		RUNWAY 5-23		<b>Section:</b> 6125	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2017	<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 200.00 (Ft)	<b>Width:</b> 100.00 (Ft)	<b>True Area:</b> 20000.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1997 NOMINAL 3" P401 AC OVER	
1/1/1976	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1976 3" P401 AC OVERLAY	
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1966 2" P401 AC PAVEMENT	

<b>Network:</b> PAGE FIELD		<b>Branch:</b> RW 5-23		RUNWAY 5-23		<b>Section:</b> 6130	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2017	<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 400.00 (Ft)	<b>Width:</b> 25.00 (Ft)	<b>True Area:</b> 10000.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	0.50	<input checked="" type="checkbox"/>	1997 NOMINAL 1 1/2" P401 AC OV	
1/1/1976	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1976 P401 OVERLAY	
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1966 2" P401 AC PAVEMENT	

<b>Network:</b> PAGE FIELD		<b>Branch:</b> RW 5-23		RUNWAY 5-23		<b>Section:</b> 6135	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2017	<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 500.00 (Ft)	<b>Width:</b> 100.00 (Ft)	<b>True Area:</b> 50000.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1997 NOMINAL 3" P401 AC OVER	
1/1/1976	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1976 3" P401 AC OVERLAY	
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1966 2" P401 AC PAVEMENT	

<b>Network:</b> PAGE FIELD		<b>Branch:</b> RW 5-23		RUNWAY 5-23		<b>Section:</b> 6140	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2017	<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 1,000.00 (Ft)	<b>Width:</b> 25.00 (Ft)	<b>True Area:</b> 25000.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	0.50	<input checked="" type="checkbox"/>	1997 NOMINAL 1 1/2" P401 AC OV	
1/1/1976	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1976 3" P401 OVERLAY	
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1966 2" P401 AC PAVEMENT	

<b>Network:</b> PAGE FIELD		<b>Branch:</b> RW 5-23		RUNWAY 5-23		<b>Section:</b> 6145	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2017	<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 1,550.00 (Ft)	<b>Width:</b> 100.00 (Ft)	<b>True Area:</b> 155000.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay	
1/1/1997	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1997 NOMINAL 3" P401 AC OVER	
1/1/1976	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1976 3" P401 AC OVERLAY	
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1966 2" P401 AC PAVEMENT	

11/18/2022

## Work History Report

Page 7 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: RW 5-23	RUNWAY 5-23	Section: 6150	Surface: AAC	
L.C.D. 1/1/2017	Use: RUNWAY	Rank: P	Length: 3,100.00 (Ft)	Width: 25.00 (Ft)	True Area: 77500.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay
1/1/1997	OL-AS	Overlay - AC Structural	0.00	0.50	<input checked="" type="checkbox"/>	1997 NOMINAL 1 1/2" P401 AC OV
1/1/1976	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1976 3" P401 AC OVERLAY
1/1/1966	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1966 2" AC PAVEMENT

Network: PAGE FIELD		Branch: RW 5-23	RUNWAY 5-23	Section: 6155	Surface: AAC	
L.C.D. 1/1/2017		Use: RUNWAY	Rank: P	Length: 356.00 (Ft)	Width: 100.00 (Ft)	True Area: 35600.00001 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay
1/1/1997	OL-AS	Overlay - AC Structural	0.00	3.00	<input checked="" type="checkbox"/>	1997 NOMINAL 3" P401 AC OVER
1/1/1976	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	EST 1976 AC PAVEMENT

Network: PAGE FIELD		Branch: RW 5-23	RUNWAY 5-23	Section: 6160	Surface: AAC	
L.C.D. 1/1/2017	Use: RUNWAY	Rank: P	Length: 712.00 (Ft)	Width: 25.00 (Ft)	True Area: 17800.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	4" Mill, 4" P-401 Overlay
1/1/1997	OL-AS	Overlay - AC Structural	0.00	0.50	<input checked="" type="checkbox"/>	1997 NOMINAL 1 1/2" P401 AC OV
1/1/1976	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	EST 1976 AC PAVEMENT

Network: PAGE FIELD		Branch: TW A	TAXIWAY A	Section: 103	Surface:AC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 271.00 (Ft)	Width: 50.00 (Ft)	True Area: 12403.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1968	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	1968 3" BIT 8" LIMEROCK

Network: PAGE FIELD		Branch: TW A	TAXIWAY A	Section: 105	Surface: AAC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 1,034.00 (Ft)	Width: 50.00 (Ft)	True Area: 51700.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill, 2" P-401 Overlay
1/1/1968	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1968 3" BIT 8" LIMEROCK



11/18/2022

## Work History Report

Page 8 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW A		TAXIWAY A		Section: 110		Surface: AAC	
L.C.D. 1/1/2018		Use: TAXIWAY		Rank: P		Length: 124.00 (Ft)		Width: 50.00 (Ft) True Area: 6623.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/2018	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" MILL W/ 2" P401 OVERLAY			
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>				
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY			
1/1/1973	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>	1973 4"P-401 AND LEVELING COURSE			
1/1/1965	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1965 2" P-401 8" P-211			

Network: PAGE FIELD		Branch: TW A	TAXIWAY A	Section: 111	Surface:AC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 2,597.00 (Ft)	Width: 50.00 (Ft)	True Area: 132526.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	NC-AC	New Construction - AC	33,115.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY
1/1/1973	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>	1973 4"P-401 AND LEVELING COURSE
1/1/1965	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1965 2" P-401 8" P-211

Network: PAGE FIELD		Branch: TW A1	TAXIWAY A1	Section: 123	Surface:AC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 52.00 (Ft)	True Area: 20509.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1968	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	1968 3" BIT 8" LIMEROCK

Network: PAGE FIELD		Branch: TW A		TAXIWAY A		Section: 114		Surface: AAC	
L.C.D. 1/1/2017		Use: TAXIWAY		Rank: P		Length: 1,478.00 (Ft)		Width: 50.00 (Ft) True Area: 73900.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill, 2" P-401 Overlay			
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>				
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY			
1/1/1973	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>	1973 4"P-401 AND LEVELING COURSE			
1/1/1965	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1965 2" P-401 8" P-211			

11/18/2022

## Work History Report

Page 9 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW A	TAXIWAY A	Section: 115	Surface: AAC	
L.C.D. 1/1/1991	Use: TAXIWAY	Rank: P	Length: 350.00 (Ft)	Width: 50.00 (Ft)	True Area: 17123.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 BIT OVERLAY
1/1/1968	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1968 BIT OVERLAY

Network: PAGE FIELD		Branch: TW A2	TAXIWAY A2	Section: 125	Surface:AC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 52.00 (Ft)	True Area: 20237.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1991	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1991 P401 AC OVERLAY
1/1/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1965 2" P401 AC SURFACE ON 8" P

Network: PAGE FIELD		Branch: TW A3	TAXIWAY A3	Section: 145	Surface:AC	
L.C.D. 1/1/2017		Use: TAXIWAY	Rank: P	Length: 445.00 (Ft)	Width: 66.00 (Ft)	True Area: 41023.00001 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1991	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY
1/1/1968	NC-AC	New Construction - AC	0.00	4.50	<input checked="" type="checkbox"/>	1968 4.5" BIT

Network: PAGE FIELD		Branch: TW A3		TAXIWAY A3		Section: 150		Surface: AAC	
L.C.D. 1/1/1991		Use: TAXIWAY		Rank: P		Length: 1,185.00 (Ft)		Width: 50.00 (Ft) True Area: 67098.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY			
1/1/1968	IMPORT ED	BUILT	0.00	4.50	<input checked="" type="checkbox"/>	1968 4.5" BIT			

Network: PAGE FIELD		Branch: TW A3	TAXIWAY A3	Section: 153	Surface:AC	
L.C.D. 1/1/2018	Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 100.00 (Ft)	True Area: 14735.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2018	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	EST 1991 BIT
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: TW A3	TAXIWAY A3	Section: 155	Surface:AC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 460.00 (Ft)	Width: 50.00 (Ft)	True Area: 26215.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1991	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY
1/1/1968	NC-AC	New Construction - AC	0.00	3.00	<input checked="" type="checkbox"/>	1968 3" P-401 8" P-211

11/18/2022

## Work History Report

Page 10 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW A6		TAXIWAY A6		Section: 175	Surface: AAC
L.C.D. 1/1/1991	Use: TAXIWAY	Rank: P	Length: 70.00 (Ft)	Width: 50.00 (Ft)	True Area: 4324.000001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY	
1/1/1968	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1968 P-401 OVERLAY	

Network: PAGE FIELD		Branch: TW A6		TAXIWAY A6		Section: 178	Surface: AAC
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 93.00 (Ft)	Width: 50.00 (Ft)	True Area: 4732.000001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill, 2" P-401 Overlay	
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY	

Network: PAGE FIELD		Branch: TW A6		TAXIWAY A6		Section: 180	Surface: AC
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 85.00 (Ft)	Width: 51.00 (Ft)	True Area: 5104.000001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160	
1/1/1991	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY	
1/1/1958	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Estimated Date	

Network: PAGE FIELD		Branch: TW A7		TAXIWAY A7		Section: 120	Surface: AAC
L.C.D. 1/1/1991	Use: TAXIWAY	Rank: P	Length: 500.00 (Ft)	Width: 50.00 (Ft)	True Area: 28228.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	1991 P-401 OVERLAY	
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1968	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1968 3" P-401 8" P-211	

Network: PAGE FIELD		Branch: TW AP SW		SOUTHWEST AP		Section: 107	Surface: AC
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 110.00 (Ft)	Width: 90.00 (Ft)	True Area: 14624.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160	
1/1/1998	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1998 CRACK REPAIR AND SLURR	
1/1/1965	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1965 2" P401 AC SURFACE ON 8" P	

Network: PAGE FIELD		Branch: TW AP SW		SOUTHWEST AP		Section: 112	Surface: AC
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 140.00 (Ft)	Width: 65.00 (Ft)	True Area: 13304.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160	
1/1/1998	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

11/18/2022

## Work History Report

Page 11 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW B1	TAXIWAY B1	Section: 207	Surface:AC	
L.C.D. 1/1/1997	Use: TAXIWAY	Rank: P	Length: 500.00 (Ft)	Width: 40.00 (Ft)	True Area: 19766.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2020	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	EST 1997 AC PAVEMENT SECTION
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1997	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: TW B	TAXIWAY B	Section: 205	Surface:AC	
L.C.D. 1/1/1977	Use: TAXIWAY	Rank: P	Length: 3,485.00 (Ft)	Width: 40.00 (Ft)	True Area: 140345.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2020	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	1977 2" P-401 8" P-211
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1977	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: TW B	TAXIWAY B	Section: 206	Surface:AC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 392.00 (Ft)	Width: 53.00 (Ft)	True Area: 21637.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1977	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 8" P-211

Network: PAGE FIELD		Branch: TW B	TAXIWAY B	Section: 208	Surface: AAC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 180.00 (Ft)	Width: 50.00 (Ft)	True Area: 10199.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill, 2" P-401 Overlay
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	
1/1/1977	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 8" P-211

Network: PAGE FIELD		Branch: TW B	TAXIWAY B	Section: 210	Surface:AC	
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 65.00 (Ft)	True Area: 27327.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1991	OL-AS		0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY
1/1/1977	NC-AC		0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 8" P-211

Network: PAGE FIELD		Branch: TW B2	TAXIWAY B2	Section: 220	Surface:AC	
L.C.D. 1/1/2018	Use: TAXIWAY	Rank: P	Length: 230.00 (Ft)	Width: 40.00 (Ft)	True Area: 11346.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2018	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, Existing Base
1/1/1977	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 8" P-211

11/18/2022

## Work History Report

Page 12 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW B		TAXIWAY B		Section: 270	Surface: AC
L.C.D. 1/1/1998	Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 40.00 (Ft)	True Area: 2906.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1998 P401 AC PAVEMENT UNKNOWN SECTION*	

Network: PAGE FIELD		Branch: TW B3		TAXIWAY B3		Section: 260	Surface: AC
L.C.D. 1/1/2018	Use: TAXIWAY	Rank: P	Length: 230.00 (Ft)	Width: 40.00 (Ft)	True Area: 11346.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2018	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, Existing Base	
1/1/1977	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 8" P-211	

Network: PAGE FIELD		Branch: TW B3		TAXIWAY B3		Section: 265	Surface: AC
L.C.D. 1/1/1998	Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 40.00 (Ft)	True Area: 8453.000002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2016	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1998 EST 2" P401 AC SURFACE ON UNKNOWN SECTION*	
1/1/1998	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: TW B3		TAXIWAY B3		Section: 275	Surface: AC
L.C.D. 1/1/1998	Use: TAXIWAY	Rank: P	Length: 1,400.00 (Ft)	Width: 40.00 (Ft)	True Area: 59219.000001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2016	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1998 P401 AC PAVEMENT UNKNOWN SECTION*	
1/1/1998	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: TW B4		TAXIWAY B4		Section: 203	Surface: AC
L.C.D. 1/1/1977	Use: TAXIWAY	Rank: P	Length: 230.00 (Ft)	Width: 100.00 (Ft)	True Area: 24035.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2020	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>	1977 2" P-401 8" P-211	
1/1/2014	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
1/1/1977	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: TW C1		TAXIWAY C1		Section: 310	Surface: AC
L.C.D. 1/1/2007	Use: TAXIWAY	Rank: P	Length: 235.00 (Ft)	Width: 70.00 (Ft)	True Area: 29730.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: TW C2		TAXIWAY C2		Section: 320	Surface: AC
L.C.D. 1/1/2007	Use: TAXIWAY	Rank: P	Length: 405.00 (Ft)	Width: 85.00 (Ft)	True Area: 42197.000001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		



11/18/2022

## Work History Report

Page 13 of 18

Pavement Database: FDOT

<b>Network:</b> PAGE FIELD <b>Branch:</b> TW C      TAXIWAY C <b>Section:</b> 240 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2017 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 225.00 (Ft) <b>Width:</b> 65.00 (Ft) <b>True Area:</b> 22168.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1977	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P-401 8" P-211

<b>Network:</b> PAGE FIELD <b>Branch:</b> TW C      TAXIWAY C <b>Section:</b> 245 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2017 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 2,130.00 (Ft) <b>Width:</b> 50.00 (Ft) <b>True Area:</b> 121801.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/1977	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1977 2" P401 AC SURFACE ON 8" P

<b>Network:</b> PAGE FIELD <b>Branch:</b> TW C2      TAXIWAY C2 <b>Section:</b> 520 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2009 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 500.00 (Ft) <b>Width:</b> 55.00 (Ft) <b>True Area:</b> 42571.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> PAGE FIELD <b>Branch:</b> TW C      TAXIWAY C <b>Section:</b> 305 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2007 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 3,125.00 (Ft) <b>Width:</b> 50.00 (Ft) <b>True Area:</b> 162237.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> PAGE FIELD <b>Branch:</b> TW C      TAXIWAY C <b>Section:</b> 306 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2017 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 350.00 (Ft) <b>Width:</b> 56.00 (Ft) <b>True Area:</b> 24962.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	NC-AC	New Construction - AC	961,295.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> PAGE FIELD <b>Branch:</b> TW C3      TAXIWAY C3 <b>Section:</b> 525 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2009 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 176.00 (Ft) <b>Width:</b> 116.00 (Ft) <b>True Area:</b> 23701.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> PAGE FIELD <b>Branch:</b> TW C5      TAXIWAY C5 <b>Section:</b> 330 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2017 <b>Use:</b> TAXIWAY <b>Rank:</b> P <b>Length:</b> 300.00 (Ft) <b>Width:</b> 60.00 (Ft) <b>True Area:</b> 26412.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

11/18/2022

## Work History Report

Page 14 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW C6		TAXIWAY C6		Section: 335	Surface: AAC
L.C.D.	1/1/2017	Use: TAXIWAY	Rank: P	Length: 136.00 (Ft)	Width: 53.00 (Ft)	True Area: 7909.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill, 2" P-401 Overlay	
1/1/1974	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1974 3" P-401 10" P-211	

Network: PAGE FIELD		Branch: TW C6		TAXIWAY C6		Section: 345	Surface: AC
L.C.D.	1/1/2017	Use: TAXIWAY	Rank: P	Length: 135.00 (Ft)	Width: 53.00 (Ft)	True Area: 8342.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160	
1/1/1974	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1974 3" P-401 10" P-211	

Network: PAGE FIELD		Branch: TW C7		TAXIWAY C7		Section: 350	Surface: AC
L.C.D.	1/1/2017	Use: TAXIWAY	Rank: P	Length: 137.00 (Ft)	Width: 82.00 (Ft)	True Area: 15220.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: TW C8		TAXIWAY C8		Section: 355	Surface: AC
L.C.D.	1/1/2017	Use: TAXIWAY	Rank: P	Length: 122.00 (Ft)	Width: 88.00 (Ft)	True Area: 15632.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: TW C9		TAXIWAY C9		Section: 360	Surface: AC
L.C.D.	1/1/2017	Use: TAXIWAY	Rank: P	Length: 90.00 (Ft)	Width: 65.00 (Ft)	True Area: 9368.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

Network: PAGE FIELD		Branch: TW D		TAXIWAY D		Section: 134	Surface: AC
L.C.D.	1/1/2017	Use: TAXIWAY	Rank: P	Length: 350.00 (Ft)	Width: 50.00 (Ft)	True Area: 28977.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, 12" P-160	
1/1/1998	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1970 BIT	

Network: PAGE FIELD		Branch: TW D		TAXIWAY D		Section: 135	Surface: AAC
L.C.D.	1/1/1998	Use: TAXIWAY	Rank: P	Length: 461.00 (Ft)	Width: 50.00 (Ft)	True Area: 23050.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1970	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1970 BIT	

11/18/2022

## Work History Report

Page 15 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW D		TAXIWAY D		Section: 136	Surface:AC
L.C.D.	1/1/1998	Use: TAXIWAY	Rank: P	Length: 189.00 (Ft)	Width: 50.00 (Ft)	True Area: 9753.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1998 2" NOMINAL P401 AC PAVEMENT ON UNKNOWN SECT	

Network: PAGE FIELD		Branch: TW D		TAXIWAY D		Section: 137	Surface:AAC
L.C.D.	1/1/1998	Use: TAXIWAY	Rank: P	Length: 1,200.00 (Ft)	Width: 47.00 (Ft)	True Area: 56400.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1998 2" NOMINAL P401 AC OVERLAY*	
1/1/1968	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1968 1" MINIMUM AC SURFACE ON EXISTING UNKNOWN SECTION	

Network: PAGE FIELD		Branch: TW D		TAXIWAY D		Section: 140	Surface:AAC
L.C.D.	1/1/1998	Use: TAXIWAY	Rank: P	Length: 473.00 (Ft)	Width: 50.00 (Ft)	True Area: 24471.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1998 2" NOMINAL P401 AC OVER	
1/1/1968	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1968 BIT	

Network: PAGE FIELD		Branch: TW D		TAXIWAY D		Section: 143	Surface:AC
L.C.D.	1/1/1998	Use: TAXIWAY	Rank: P	Length: 203.00 (Ft)	Width: 47.00 (Ft)	True Area: 9551.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1998	NC-AC	New Construction - AC	0.00	2.00	<input checked="" type="checkbox"/>	1998 2" NOMINAL AC OVERLAY	

Network: PAGE FIELD		Branch: TW D2		TAXIWAY D2		Section: 160	Surface:AAC
L.C.D.	1/1/1977	Use: TAXIWAY	Rank: P	Length: 308.00 (Ft)	Width: 40.00 (Ft)	True Area: 13679.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1977	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	1977 P-401 OVERLAY	
1/1/1977	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401 4.5" P-212	

Network: PAGE FIELD		Branch: TW D3		TAXIWAY D3		Section: 141	Surface:AC
L.C.D.	1/1/2018	Use: TAXIWAY	Rank: P	Length: 160.00 (Ft)	Width: 53.00 (Ft)	True Area: 9322.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2018	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, Existing Base	
1/1/1968	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	EST 1968 BIT	

Network: PAGE FIELD		Branch: TW E		TAXIWAY E		Section: 147	Surface:AC
L.C.D.	1/1/2017	Use: TAXIWAY	Rank: P	Length: 315.00 (Ft)	Width: 60.00 (Ft)	True Area: 22245.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

11/18/2022

## Work History Report

Page 16 of 18

Pavement Database: FDOT

Network: PAGE FIELD		Branch: TW E1	TAXIWAY E1	Section: 500	Surface:AC	
L.C.D. 1/1/2018	Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 50.00 (Ft)	True Area: 10310.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2018	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: TW E		TAXIWAY E		Section: 165		Surface:AC	
L.C.D. 1/1/2017		Use: TAXIWAY		Rank: P		Length: 540.00 (Ft)		Width: 55.00 (Ft) True Area: 42108.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments			
1/1/2017	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1991 P-401 OVERLAY  4" P-401 4.5" P-212  1977 P-401 OVERLAY			
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>				
1/1/1991	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>				
1/1/1977	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>				

Network: PAGE FIELD		Branch: TW E2	TAXIWAY E2	Section: 505	Surface:AC	
L.C.D. 1/1/2007	Use: TAXIWAY	Rank: P	Length: 256.00 (Ft)	Width: 35.00 (Ft)	True Area: 10138.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: TW E2		TAXIWAY E2		Section: 530		Surface:AC	
L.C.D. 1/1/2009		Use: TAXIWAY		Rank: P		Length: 250.00 (Ft)		Width: 40.00 (Ft) True Area: 10056.00000 (SqFt)	
Work Date	Work Code	Work Description		Cost	Thickness (in)	Major M&R	Comments		
1/1/2009	NU-IN	New Construction - Initial		0.00	0.00	<input checked="" type="checkbox"/>			

Network: PAGE FIELD		Branch: TW E	TAXIWAY E	Section: 503	Surface:AC	
L.C.D. 1/1/2018	Use: TAXIWAY	Rank: P	Length: 875.00 (Ft)	Width: 35.00 (Ft)	True Area: 39478.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2018	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: TW E	TAXIWAY E	Section: 510	Surface:AC	
L.C.D. 1/1/2007	Use: TAXIWAY	Rank: P	Length: 1,184.00 (Ft)	Width: 35.00 (Ft)	True Area: 48748.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: PAGE FIELD		Branch: TW E	TAXIWAY E	Section: 512	Surface:AC	
L.C.D. 1/1/2007	Use: TAXIWAY	Rank: P	Length: 300.00 (Ft)	Width: 65.00 (Ft)	True Area: 31577.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2007	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

11/18/2022

## Work History Report

Page 17 of 18

*Pavement Database: FDOT*

Network: PAGE FIELD      Branch: TW E      TAXIWAY E      Section: 535      Surface: AC  
L.C.D. 1/1/2017      Use: TAXIWAY      Rank: P      Length: 300.00 (Ft)      Width: 60.00 (Ft)      True Area: 28366.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	



**Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	37	2,931,071.00	1.20	1.28
Complete Reconstruction - AC	19	625,167.00	0.00	0.00
Crack Sealing - AC	14	669,962.00	0.00	0.00
Mill and Overlay	24	1,705,735.00	0.00	0.00
New Construction - AC	57	3,041,966.00	1.11	1.74
New Construction - Initial	8	755,511.00	0.00	0.00
OVERLAY	22	2,247,734.00	1.86	1.79
Overlay - AC Structural	24	1,558,306.00	1.50	1.39
Surface Treatment - Seal Coat	12	1,913,576.00	0.00	0.00

11/18/2022

**Branch Condition Report**

Page 1 of 2

*Pavement Database: FDOT*

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP E	5	2,195.00	160.00	243,550.00	APRON	78.60	3.50	77.29
AP HELI	1	765.00	135.00	93,555.00	APRON	82.00	0.00	82.00
AP N	1	1,225.00	272.00	331,067.00	APRON	52.00	0.00	52.00
AP RU 13	1	160.00	60.00	11,434.00	APRON	66.00	0.00	66.00
AP RU 5	1	305.00	105.00	30,022.00	APRON	77.00	0.00	77.00
AP S	6	2,632.00	203.67	445,597.00	APRON	73.00	18.33	63.99
AP SE	2	1,173.00	354.00	421,791.00	APRON	58.50	19.50	62.07
AP SW	3	958.00	519.67	334,111.00	APRON	55.33	11.79	55.89
AP T-HANG	1	2,568.00	75.00	169,083.00	APRON	83.00	0.00	83.00
AP W	2	1,644.00	256.50	560,890.00	APRON	90.00	1.00	89.06
RW 13-31	2	14,417.00	62.50	714,113.00	RUNWAY	90.50	1.50	90.00
RW 5-23	12	19,199.00	62.50	960,900.00	RUNWAY	87.83	3.36	88.80
TW A	6	5,854.00	50.00	294,275.00	TAXIWAY	83.33	10.62	87.17
TW A1	1	300.00	52.00	20,509.00	TAXIWAY	94.00	0.00	94.00
TW A2	1	300.00	52.00	20,237.00	TAXIWAY	94.00	0.00	94.00
TW A3	4	2,265.00	66.50	149,071.00	TAXIWAY	83.75	17.18	75.72
TW A6	3	248.00	50.33	14,160.00	TAXIWAY	82.67	16.03	83.62
TW A7	1	500.00	50.00	28,228.00	TAXIWAY	65.00	0.00	65.00
TW AP SW	2	250.00	77.50	27,928.00	TAXIWAY	92.50	1.50	92.57
TW B	5	4,407.00	49.60	202,414.00	TAXIWAY	78.60	15.60	72.23
TW B1	1	500.00	40.00	19,766.00	TAXIWAY	72.00	0.00	72.00
TW B2	1	230.00	40.00	11,346.00	TAXIWAY	94.00	0.00	94.00
TW B3	3	1,805.00	40.00	79,018.00	TAXIWAY	76.67	12.28	72.38
TW B4	1	230.00	100.00	24,035.00	TAXIWAY	67.00	0.00	67.00
TW C	4	5,830.00	55.25	331,168.00	TAXIWAY	88.75	6.87	85.10
TW C1	1	235.00	70.00	29,730.00	TAXIWAY	69.00	0.00	69.00
TW C2	2	905.00	70.00	84,768.00	TAXIWAY	75.50	0.50	75.50
TW C3	1	176.00	116.00	23,701.00	TAXIWAY	88.00	0.00	88.00
TW C5	1	300.00	60.00	26,412.00	TAXIWAY	94.00	0.00	94.00
TW C6	2	271.00	53.00	16,251.00	TAXIWAY	89.50	0.50	89.49
TW C7	1	137.00	82.00	15,220.00	TAXIWAY	90.00	0.00	90.00
TW C8	1	122.00	88.00	15,632.00	TAXIWAY	89.00	0.00	89.00
TW C9	1	90.00	65.00	9,368.00	TAXIWAY	94.00	0.00	94.00
TW D	6	2,876.00	49.00	152,202.00	TAXIWAY	72.33	11.38	71.93
TW D2	1	308.00	40.00	13,679.00	TAXIWAY	29.00	0.00	29.00
TW D3	1	160.00	53.00	9,322.00	TAXIWAY	94.00	0.00	94.00
TW E	6	3,514.00	51.67	212,522.00	TAXIWAY	87.33	9.45	86.52
TW E1	1	175.00	50.00	10,310.00	TAXIWAY	91.00	0.00	91.00
TW E2	2	506.00	37.50	20,194.00	TAXIWAY	78.50	9.50	78.46

11/18/2022

**Branch Condition Report**

Page 2 of 2

*Pavement Database: FDOT*

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	23	2,641,100.00	71.91	16.16	69.72
RUNWAY	14	1,675,013.00	88.21	3.30	89.31
TAXIWAY	60	1,861,466.00	81.92	14.26	80.71
ALL	97	6,177,579.00	80.45	14.72	78.34

Pavement Database: FDOT

NetworkId: FMY

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP E	4505	1/1/2002	AC	APRON	P	0	58,570.00	5/11/2022	20	75
AP E	4515	1/1/2002	AC	APRON	P	0	13,907.00	5/11/2022	20	83
AP E	4520	1/1/2002	AC	APRON	P	0	72,634.00	5/11/2022	20	74
AP E	4525	1/1/2002	AC	APRON	P	0	71,383.00	5/11/2022	20	80
AP E	4530	1/1/2002	AC	APRON	P	0	27,056.00	5/11/2022	20	81
AP HELI	4705	1/1/2007	AC	APRON	P	0	93,555.00	5/11/2022	15	82
AP N	4305	1/1/1998	AAC	APRON	P	0	331,067.00	5/11/2022	24	52
AP RU 13	5105	12/25/1999	AC	APRON	P	0	11,434.00	5/11/2022	23	66
AP RU 5	5205	1/1/2007	AC	APRON	P	0	30,022.00	5/11/2022	15	77
AP S	4103	1/1/2017	AAC	APRON	P	0	10,783.00	5/11/2022	5	94
AP S	4105	1/1/1998	AAC	APRON	P	0	187,842.00	5/11/2022	24	65
AP S	4110	1/1/1998	AC	APRON	P	0	92,757.00	5/11/2022	24	68
AP S	4115	1/1/2003	AC	APRON	P	0	19,731.00	5/11/2022	19	64
AP S	4120	1/1/1998	AAC	APRON	P	0	108,068.00	5/11/2022	24	47
AP S	4125	7/1/2020	AAC	APRON	P	0	26,416.00	7/1/2020	0	100
AP SE	4415	1/1/1998	AAC	APRON	P	0	172,279.00	5/11/2022	24	39
AP SE	4420	1/1/2006	AC	APRON	P	0	249,512.00	5/11/2022	16	78
AP SW	4205	1/1/1998	AC	APRON	P	0	118,829.00	5/11/2022	24	72
AP SW	4215	1/1/1966	AC	APRON	P	0	166,211.00	5/11/2022	56	47
AP SW	4220	1/1/1998	AC	APRON	P	0	49,071.00	5/11/2022	24	47
AP T-HANG	4605	1/1/2006	AC	APRON	P	0	169,083.00	5/11/2022	16	83
AP W	4805	1/1/2009	AC	APRON	P	0	545,226.00	5/11/2022	13	89
AP W	4818	1/1/2009	PCC	APRON	P	0	15,664.00	5/11/2022	13	91
RW 13-31	6205	1/1/2018	AAC	RUNWAY	P	0	476,075.00	5/11/2022	4	89
RW 13-31	6210	1/1/2018	AC	RUNWAY	P	0	238,038.00	5/11/2022	4	92
RW 5-23	6105	1/1/2017	AAC	RUNWAY	P	0	100,000.00	5/11/2022	5	91
RW 5-23	6110	1/1/2017	AAC	RUNWAY	P	0	50,000.00	5/11/2022	5	94
RW 5-23	6115	1/1/2017	AAC	RUNWAY	P	0	280,000.00	5/11/2022	5	89
RW 5-23	6120	1/1/2017	AAC	RUNWAY	P	0	140,000.00	5/11/2022	5	92
RW 5-23	6125	1/1/2017	AAC	RUNWAY	P	0	20,000.00	5/11/2022	5	89
RW 5-23	6130	1/1/2017	AAC	RUNWAY	P	0	10,000.00	5/11/2022	5	84
RW 5-23	6135	1/1/2017	AAC	RUNWAY	P	0	50,000.00	5/11/2022	5	87
RW 5-23	6140	1/1/2017	AAC	RUNWAY	P	0	25,000.00	5/11/2022	5	82
RW 5-23	6145	1/1/2017	AAC	RUNWAY	P	0	155,000.00	5/11/2022	5	86
RW 5-23	6150	1/1/2017	AAC	RUNWAY	P	0	77,500.00	5/11/2022	5	88
RW 5-23	6155	1/1/2017	AAC	RUNWAY	P	0	35,600.00	5/11/2022	5	84
RW 5-23	6160	1/1/2017	AAC	RUNWAY	P	0	17,800.00	5/11/2022	5	88
TW A	103	1/1/2017	AC	TAXIWAY	P	0	12,403.00	5/11/2022	5	94
TW A	105	1/1/2017	AAC	TAXIWAY	P	0	51,700.00	5/11/2022	5	91
TW A	110	1/1/2018	AAC	TAXIWAY	P	0	6,623.00	5/11/2022	4	79
TW A	111	1/1/2017	AC	TAXIWAY	P	0	132,526.00	5/11/2022	5	93
TW A	114	1/1/2017	AAC	TAXIWAY	P	0	73,900.00	5/11/2022	5	79
TW A	115	1/1/1991	AAC	TAXIWAY	P	0	17,123.00	5/11/2022	31	64
TW A1	123	1/1/2017	AC	TAXIWAY	P	0	20,509.00	5/11/2022	5	94
TW A2	125	1/1/2017	AC	TAXIWAY	P	0	20,237.00	5/11/2022	5	94
TW A3	145	1/1/2017	AC	TAXIWAY	P	0	41,023.00	5/11/2022	5	93
TW A3	150	1/1/1991	AAC	TAXIWAY	P	0	67,098.00	5/11/2022	31	54
TW A3	153	1/1/2018	AC	TAXIWAY	P	0	14,735.00	5/11/2022	4	94
TW A3	155	1/1/2017	AC	TAXIWAY	P	0	26,215.00	5/11/2022	5	94

TW A6	175	1/1/1991	AAC	TAXIWAY	P	0	4,324.00	5/11/2022	31	60
TW A6	178	1/1/2017	AAC	TAXIWAY	P	0	4,732.00	5/11/2022	5	94
TW A6	180	1/1/2017	AC	TAXIWAY	P	0	5,104.00	5/11/2022	5	94
TW A7	120	1/1/1991	AAC	TAXIWAY	P	0	28,228.00	5/11/2022	31	65
TW AP SW	107	1/1/2017	AC	TAXIWAY	P	0	14,624.00	5/11/2022	5	94
TW AP SW	112	1/1/2017	AC	TAXIWAY	P	0	13,304.00	5/11/2022	5	91
TW B	205	1/1/1977	AC	TAXIWAY	P	0	140,345.00	5/11/2022	45	65
TW B	206	1/1/2017	AC	TAXIWAY	P	0	21,637.00	5/11/2022	5	90
TW B	208	1/1/2017	AAC	TAXIWAY	P	0	10,199.00	5/11/2022	5	94
TW B	210	1/1/2017	AC	TAXIWAY	P	0	27,327.00	5/11/2022	5	89
TW B	270	1/1/1998	AC	TAXIWAY	P	0	2,906.00	5/11/2022	24	55
TW B1	207	1/1/1997	AC	TAXIWAY	P	0	19,766.00	5/11/2022	25	72
TW B2	220	1/1/2018	AC	TAXIWAY	P	0	11,346.00	5/11/2022	4	94
TW B3	260	1/1/2018	AC	TAXIWAY	P	0	11,346.00	5/11/2022	4	94
TW B3	265	1/1/1998	AC	TAXIWAY	P	0	8,453.00	5/11/2022	24	67
TW B3	275	1/1/1998	AC	TAXIWAY	P	0	59,219.00	5/11/2022	24	69
TW B4	203	1/1/1977	AC	TAXIWAY	P	0	24,035.00	5/11/2022	45	67
TW C	240	1/1/2017	AC	TAXIWAY	P	0	22,168.00	5/11/2022	5	91
TW C	245	1/1/2017	AC	TAXIWAY	P	0	121,801.00	5/11/2022	5	93
TW C	305	1/1/2007	AC	TAXIWAY	P	0	162,237.00	5/11/2022	15	77
TW C	306	1/1/2017	AC	TAXIWAY	P	0	24,962.00	5/11/2022	5	94
TW C1	310	1/1/2007	AC	TAXIWAY	P	0	29,730.00	5/11/2022	15	69
TW C2	320	1/1/2007	AC	TAXIWAY	P	0	42,197.00	5/11/2022	15	75
TW C2	520	1/1/2009	AC	TAXIWAY	P	0	42,571.00	5/11/2022	13	76
TW C3	525	1/1/2009	AC	TAXIWAY	P	0	23,701.00	5/11/2022	13	88
TW C5	330	1/1/2017	AC	TAXIWAY	P	0	26,412.00	5/11/2022	5	94
TW C6	335	1/1/2017	AAC	TAXIWAY	P	0	7,909.00	5/11/2022	5	90
TW C6	345	1/1/2017	AC	TAXIWAY	P	0	8,342.00	5/11/2022	5	89
TW C7	350	1/1/2017	AC	TAXIWAY	P	0	15,220.00	5/11/2022	5	90
TW C8	355	1/1/2017	AC	TAXIWAY	P	0	15,632.00	5/11/2022	5	89
TW C9	360	1/1/2017	AC	TAXIWAY	P	0	9,368.00	5/11/2022	5	94
TW D	134	1/1/2017	AC	TAXIWAY	P	0	28,977.00	5/11/2022	5	94
TW D	135	1/1/1998	AAC	TAXIWAY	P	0	23,050.00	5/11/2022	24	65
TW D	136	1/1/1998	AC	TAXIWAY	P	0	9,753.00	5/11/2022	24	60
TW D	137	1/1/1998	AAC	TAXIWAY	P	0	56,400.00	5/11/2022	24	64
TW D	140	1/1/1998	AAC	TAXIWAY	P	0	24,471.00	5/11/2022	24	73
TW D	143	1/1/1998	AC	TAXIWAY	P	0	9,551.00	5/11/2022	24	78
TW D2	160	1/1/1977	AAC	TAXIWAY	P	0	13,679.00	5/11/2022	45	29
TW D3	141	1/1/2018	AC	TAXIWAY	P	0	9,322.00	5/11/2022	4	94
TW E	147	1/1/2017	AC	TAXIWAY	P	0	22,245.00	5/11/2022	5	94
TW E	165	1/1/2017	AC	TAXIWAY	P	0	42,108.00	5/11/2022	5	94
TW E	503	1/1/2018	AC	TAXIWAY	P	0	39,478.00	5/11/2022	4	94
TW E	510	1/1/2007	AC	TAXIWAY	P	0	48,748.00	5/11/2022	15	75
TW E	512	1/1/2007	AC	TAXIWAY	P	0	31,577.00	5/11/2022	15	73
TW E	535	1/1/2017	AC	TAXIWAY	P	0	28,366.00	5/11/2022	5	94
TW E1	500	1/1/2018	AC	TAXIWAY	P	0	10,310.00	5/11/2022	4	91
TW E2	505	1/1/2007	AC	TAXIWAY	P	0	10,138.00	5/11/2022	15	69
TW E2	530	1/1/2009	AC	TAXIWAY	P	0	10,056.00	5/11/2022	13	88



*Pavement Database: FDOT*

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		26,416.00	1	100.00	0.00	100.00
03-05	5	2,637,906.00	50	90.94	3.91	90.18
11-15	14	1,085,422.00	13	79.15	7.34	83.39
16-20	19	681,876.00	8	77.25	5.91	78.58
21-25	24	1,284,916.00	17	62.29	10.45	57.29
31-35	31	116,773.00	4	60.75	4.32	58.35
41-50	45	178,059.00	3	53.67	17.46	62.50
50+	56	166,211.00	1	47.00	0.00	47.00
ALL	13	6,177,579.00	97	80.45	14.72	78.34



# **Appendix B: Maintenance and Rehabilitation Planning Needs**



Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
FMY	RW 5-23	6155	L & T CR	Medium	36	LF	0.1%	Preventive	AC Crack Sealing	36	LF	\$ 4.00	\$ 150
FMY	RW 13-31	6205	RAVELING	Low	41	SF	0.0%	Preventive	Surface Seal	41	SF	\$ 0.75	\$ 40
FMY	TW B1	207	RAVELING	Low	1,975	SF	10.0%	Preventive	Surface Seal	1,975	SF	\$ 0.75	\$ 1,490
FMY	TW B1	207	WEATHERING	Medium	7,908	SF	40.0%	Preventive	Surface Seal	7,908	SF	\$ 0.75	\$ 5,940
FMY	TW C	305	L & T CR	Medium	543	LF	0.3%	Preventive	AC Crack Sealing	543	LF	\$ 4.00	\$ 2,180
FMY	TW C	305	WEATHERING	Medium	14,195	SF	8.8%	Preventive	Surface Seal	14,196	SF	\$ 0.75	\$ 10,650
FMY	TW C2	320	WEATHERING	Medium	42,197	SF	100.0%	Preventive	Surface Seal	42,197	SF	\$ 0.75	\$ 31,650
FMY	TW C2	520	L & T CR	Medium	196	LF	0.5%	Preventive	AC Crack Sealing	196	LF	\$ 4.00	\$ 790
FMY	TW C2	520	WEATHERING	Medium	8,516	SF	20.0%	Preventive	Surface Seal	8,515	SF	\$ 0.75	\$ 6,390
FMY	TW C6	345	WEATHERING	Medium	20	SF	0.2%	Preventive	Surface Seal	21	SF	\$ 0.75	\$ 20
FMY	TW D	140	L & T CR	Medium	5	LF	0.0%	Preventive	AC Crack Sealing	5	LF	\$ 4.00	\$ 20
FMY	TW D	140	WEATHERING	Medium	9,787	SF	40.0%	Preventive	Surface Seal	9,788	SF	\$ 0.75	\$ 7,350
FMY	TW D	143	WEATHERING	Medium	956	SF	10.0%	Preventive	Surface Seal	956	SF	\$ 0.75	\$ 720
FMY	TW E	510	WEATHERING	Medium	29,249	SF	60.0%	Preventive	Surface Seal	29,249	SF	\$ 0.75	\$ 21,940
FMY	TW E	512	WEATHERING	Medium	31,577	SF	100.0%	Preventive	Surface Seal	31,577	SF	\$ 0.75	\$ 23,690
FMY	TW E2	530	WEATHERING	Medium	201	SF	2.0%	Preventive	Surface Seal	201	SF	\$ 0.75	\$ 160
FMY	AP E	4505	WEATHERING	Medium	58,570	SF	100.0%	Preventive	Surface Seal	58,570	SF	\$ 0.75	\$ 43,930
FMY	AP E	4515	WEATHERING	Medium	695	SF	5.0%	Preventive	Surface Seal	695	SF	\$ 0.75	\$ 530
FMY	AP E	4520	L & T CR	Medium	111	LF	0.2%	Preventive	AC Crack Sealing	111	LF	\$ 4.00	\$ 450
FMY	AP E	4520	WEATHERING	Medium	72,634	SF	100.0%	Preventive	Surface Seal	72,634	SF	\$ 0.75	\$ 54,480
FMY	AP E	4525	WEATHERING	Medium	71,383	SF	100.0%	Preventive	Surface Seal	71,383	SF	\$ 0.75	\$ 53,540
FMY	AP HELI	4705	RAVELING	Low	2,552	SF	2.7%	Preventive	Surface Seal	2,552	SF	\$ 0.75	\$ 1,920
FMY	AP HELI	4705	WEATHERING	Medium	15,924	SF	17.0%	Preventive	Surface Seal	15,924	SF	\$ 0.75	\$ 11,950
FMY	AP RU 5	5205	WEATHERING	Medium	16,512	SF	55.0%	Preventive	Surface Seal	16,512	SF	\$ 0.75	\$ 12,390
FMY	AP SE	4420	DEPRESSION	Medium	76	SF	0.0%	Preventive	AC Full-Depth Patching	115	SF	\$ 11.50	\$ 1,330
FMY	AP SE	4420	RAVELING	Low	425	SF	0.2%	Preventive	Surface Seal	425	SF	\$ 0.75	\$ 320
FMY	AP SE	4420	WEATHERING	Medium	38,504	SF	15.4%	Preventive	Surface Seal	38,505	SF	\$ 0.75	\$ 28,880
FMY	AP SW	4205	L & T CR	Medium	98	LF	0.1%	Preventive	AC Crack Sealing	98	LF	\$ 4.00	\$ 400
FMY	AP SW	4205	RAVELING	Low	32,485	SF	27.3%	Preventive	Surface Seal	32,484	SF	\$ 0.75	\$ 24,370
FMY	AP SW	4205	WEATHERING	Medium	49,764	SF	41.9%	Preventive	Surface Seal	49,764	SF	\$ 0.75	\$ 37,330
FMY	AP T-HANG	4605	WEATHERING	Medium	31,738	SF	18.8%	Preventive	Surface Seal	31,737	SF	\$ 0.75	\$ 23,810
FMY	AP W	4805	WEATHERING	Medium	8,882	SF	1.6%	Preventive	Surface Seal	8,882	SF	\$ 0.75	\$ 6,670

*Table B.2: Section-Level 10-Year Major Rehabilitation Needs*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	FMY	TW A	115	AAC	17,123	63	AC Rehabilitation	\$ 180,000
2023	FMY	TW A3	150	AAC	67,098	53	AC Reconstruction	\$ 1,242,000
2023	FMY	TW A6	175	AAC	4,324	59	AC Rehabilitation	\$ 46,000
2023	FMY	TW A7	120	AAC	28,228	64	AC Rehabilitation	\$ 297,000
2023	FMY	TW B	205	AC	140,345	64	AC Rehabilitation	\$ 1,474,000
2023	FMY	TW B	270	AC	2,906	55	AC Reconstruction	\$ 42,000
2023	FMY	TW B3	265	AC	8,453	66	AC Rehabilitation	\$ 89,000
2023	FMY	TW B3	275	AC	59,219	68	AC Rehabilitation	\$ 622,000
2023	FMY	TW B4	203	AC	24,035	66	AC Rehabilitation	\$ 253,000
2023	FMY	TW C1	310	AC	29,730	68	AC Rehabilitation	\$ 313,000
2023	FMY	TW D	135	AAC	23,050	64	AC Rehabilitation	\$ 243,000
2023	FMY	TW D	136	AC	9,753	59	AC Rehabilitation	\$ 103,000
2023	FMY	TW D	137	AAC	56,400	63	AC Rehabilitation	\$ 593,000
2023	FMY	TW D2	160	AAC	13,679	27	AC Reconstruction	\$ 254,000
2023	FMY	TW E2	505	AC	10,138	68	AC Rehabilitation	\$ 107,000
2023	FMY	AP N	4305	AAC	331,067	50	AC Reconstruction	\$ 6,125,000
2023	FMY	AP RU 13	5105	AC	11,434	65	AC Rehabilitation	\$ 121,000
2023	FMY	AP S	4105	AAC	187,842	63	AC Rehabilitation	\$ 1,973,000
2023	FMY	AP S	4110	AC	92,757	66	AC Rehabilitation	\$ 974,000
2023	FMY	AP S	4115	AC	19,731	63	AC Rehabilitation	\$ 208,000
2023	FMY	AP S	4120	AAC	108,068	45	AC Reconstruction	\$ 2,000,000
2023	FMY	AP SE	4415	AAC	172,279	37	AC Reconstruction	\$ 3,188,000
2023	FMY	AP SW	4215	AC	166,211	46	AC Reconstruction	\$ 3,075,000
2023	FMY	AP SW	4220	AC	49,071	46	AC Reconstruction	\$ 908,000
2024	FMY	TW B1	207	AC	19,766	70	AC Rehabilitation	\$ 218,000
2024	FMY	AP SW	4205	AC	118,829	69	AC Rehabilitation	\$ 1,311,000
2025	FMY	TW D	140	AAC	24,471	69	AC Rehabilitation	\$ 284,000
2025	FMY	TW E	512	AC	31,577	70	AC Rehabilitation	\$ 366,000
2025	FMY	AP E	4505	AC	58,570	70	AC Rehabilitation	\$ 679,000
2025	FMY	AP E	4520	AC	72,634	69	AC Rehabilitation	\$ 841,000



# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2026	FMY	AP RU 5	5205	AC	30,022	70	AC Rehabilitation	\$ 365,000
2027	FMY	TW C2	320	AC	42,197	69	AC Rehabilitation	\$ 539,000
2027	FMY	TW C2	520	AC	42,571	70	AC Rehabilitation	\$ 544,000
2027	FMY	TW E	510	AC	48,748	69	AC Rehabilitation	\$ 623,000
2027	FMY	AP SE	4420	AC	249,512	69	AC Rehabilitation	\$ 3,185,000
2028	FMY	TW C	305	AC	162,237	70	AC Rehabilitation	\$ 2,175,000
2028	FMY	AP E	4525	AC	71,383	69	AC Rehabilitation	\$ 957,000
2029	FMY	RW 5-23	6140	AAC	25,000	70	AC Rehabilitation	\$ 352,000
2029	FMY	TW A	110	AAC	6,623	69	AC Rehabilitation	\$ 94,000
2029	FMY	TW A	114	AAC	73,900	69	AC Rehabilitation	\$ 1,040,000
2029	FMY	TW D	143	AC	9,551	69	AC Rehabilitation	\$ 135,000
2029	FMY	AP E	4530	AC	27,056	69	AC Rehabilitation	\$ 381,000
2029	FMY	AP HELI	4705	AC	93,555	69	AC Rehabilitation	\$ 1,317,000
2030	FMY	RW 5-23	6130	AAC	10,000	70	AC Rehabilitation	\$ 148,000
2030	FMY	RW 5-23	6155	AAC	35,600	70	AC Rehabilitation	\$ 526,000
2030	FMY	AP E	4515	AC	13,907	69	AC Rehabilitation	\$ 206,000
2030	FMY	AP T-HANG	4605	AC	169,083	69	AC Rehabilitation	\$ 2,499,000
2032	FMY	RW 5-23	6135	AAC	50,000	69	AC Rehabilitation	\$ 815,000
2032	FMY	RW 5-23	6145	AAC	155,000	68	AC Rehabilitation	\$ 2,525,000
2032	FMY	AP W	4805	AC	545,226	70	AC Rehabilitation	\$ 8,882,000

\*All planning cost values have been rounded up to the nearest thousand dollars.





# Appendix C: Technical Exhibits








AAC RW 5-23 6125 1 4	AAC RW 5-23 6130 1 2	AAC RW 5-23 6135 2 10	AAC RW 5-23 6140 2 6	AAC RW 5-23 6145 7 31	AAC RW 5-23 6150 5 16	AAC RW 5-23 6155 2 7
AAC RW 5-23 6160 1 4	AAC RW 13-31 6205 21 95	AAC RW 13-31 6210 8 48	AAC TW A 105 1 10	AAC TW A 110 1 1	AAC TW A 114 2 15	AAC TW A 115 1 3
AAC TW A2 125 1 5	AAC TW A3 145 1 7	AAC TW A3 153 3 14	AAC TW A3 153 1 3	AAC TW A3 155 1 5	AAC TW A6 175 1 1	AAC TW A6 178 1 1
AAC TW A6 180 1 1	AAC TW A7 120 2 6	AAC TW AP SW 107 1 3	AAC TW AP SW 112 1 3	AAC TW B 205 4 34	AAC TW B 206 1 4	AAC TW B 208 1 2
AAC TW B 210 1 5	AAC TW B 270 1 1	AAC TW B2 220 1 2	AAC TW B3 260 1 2	AAC TW B3 265 1 2	AAC TW C 240 1 4	AAC TW C 245 3 23
AAC TW C 306 1 6	AAC TW C3 525 1 6	AAC TW C5 330 1 7	AAC TW C6 335 1 2	AAC TW C6 345 1 2	AAC TW C7 350 1 4	AAC TW C8 355 1 4
AAC TW C9 360 1 2	AAC TW D 134 1 6	AAC TW D 135 2 5	AAC TW D 136 1 2	AAC TW D 140 2 5	AAC TW D 143 1 2	AAC TW D2 160 1 3
AAC TW D3 141 1 3	AAC TW E 165 1 9	AAC TW E1 500 1 2	AAC TW E2 505 1 3	AAC TW E 4515 1 3	AAC AP HELI 4705 3 19	AAC AP N 4305 7 67
AAC AP S 4105 5 33	AAC AP SW 4205 3 20	AAC AP SW 4215 4 35	AAC AP SW 4220 1 8	AAC AP T-HANG 4805 5 36		

LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- PAVEMENT SURFACE TYPE
- PAVEMENT BRANCH ID
- SECTION NUMBER
- NUMBER OF SAMPLE UNITS IN SECTION  
NUMBER OF SAMPLE UNITS TO BE INSPECTED
- SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 226  
AC: 225 PCC: 1

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2017	AP S	Mill and Overlay
	RW 5-23	Mill and Overlay   4" Mill, 4" P-401 Overlay
	TW A, TW A6, TW C6	Mill and Overlay   2" Mill, 2" P-401 Overlay
	TW A, TW A1, TW A3, TW A6, TW AP SW, TW B, TW C6, TW D	Complete Reconstruction - AC   4" P-401, 6" P-211, 12" P-160
	TW A, TW A2, TW C, TW C5, TW C7, TW C8, TW C9, TW E	New Construction - AC   4" P-401, 6" P-211, 12" P-160
2018	RW 13-31	Mill and Overlay   2" Mill, 2" P-401 Overlay
	RW 13-31	Complete Reconstruction - AC   4" P-401, 6" P-211
	TW A3, TW B2, TW B3, TW D3	Complete Reconstruction - AC   4" P-401, Existing Base
	TW A	Mill and Overlay   2" Mill, 2" P-401 Overlay
	TW E, TW E1	New Construction - AC   4" P-401, 6" P-211, 12" P-160
2020	AP S	Mill and Overlay

**LEGEND**

TYPICAL RUNWAY BRANCH ID

TYPICAL TAXIWAY BRANCH ID


TYPICAL APRON BRANCH ID

**PROJECT YEAR**

2017	2022
2018	2023
2019	2024
2020	2025
2021	2026

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID


TW A — TYPICAL TAXIWAY BRANCH ID

AP S — TYPICAL APRON BRANCH ID

**AGE AT INSPECTION**

White	0-5 Years
Light Blue	6-10 Years
Medium Blue	11-15 Years
Dark Blue	16-20 Years
Very Dark Blue	> 20 Years

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



103 PCI = 94	105 PCI = 91	107 PCI = 94	110 PCI = 79	111 PCI = 93	112 PCI = 91	114 PCI = 79
115 PCI = 64	120 PCI = 65	123 PCI = 94	125 PCI = 94	134 PCI = 94	135 PCI = 65	136 PCI = 60
137 PCI = 64	140 PCI = 73	141 PCI = 94	143 PCI = 78	145 PCI = 93	147 PCI = 94	150 PCI = 54
153 PCI = 94	155 PCI = 94	160 PCI = 29	165 PCI = 94	175 PCI = 60	178 PCI = 94	180 PCI = 94
203 PCI = 67	205 PCI = 65	206 PCI = 90	207 PCI = 72	208 PCI = 94	210 PCI = 89	220 PCI = 94
240 PCI = 91	245 PCI = 93	260 PCI = 94	265 PCI = 67	270 PCI = 55	275 PCI = 69	305 PCI = 77
306 PCI = 94	310 PCI = 69	320 PCI = 75	330 PCI = 94	335 PCI = 90	345 PCI = 89	350 PCI = 90
355 PCI = 89	360 PCI = 94	500 PCI = 91	503 PCI = 94	505 PCI = 69	510 PCI = 75	512 PCI = 73
520 PCI = 76	525 PCI = 88	530 PCI = 88	535 PCI = 94	4103 PCI = 94	4105 PCI = 65	4110 PCI = 68
4115 PCI = 64	4120 PCI = 47	4125 PCI = 100	4205 PCI = 72	4215 PCI = 47	4220 PCI = 47	4305 PCI = 52
4415 PCI = 39	4420 PCI = 78	4505 PCI = 75	4515 PCI = 83	4520 PCI = 74	4525 PCI = 80	4530 PCI = 81
4605 PCI = 83	4705 PCI = 82	4805 PCI = 89	4818 PCI = 91	5105 PCI = 66	5205 PCI = 77	6105 PCI = 91
6110 PCI = 94	6115 PCI = 89	6120 PCI = 92	6125 PCI = 89	6130 PCI = 84	6135 PCI = 87	6140 PCI = 82
6145 PCI = 86	6150 PCI = 88	6155 PCI = 84	6160 PCI = 88	6205 PCI = 89	6210 PCI = 92	

**LEGEND**

TYPICAL RUNWAY BRANCH ID

TYPICAL TAXIWAY BRANCH ID

TYPICAL APRON BRANCH ID

**2022 PAVEMENT CONDITION INDEX**

PCI 86-100 Good

PCI 71-85 Satisfactory

PCI 56-70 Fair

PCI 41-55 Poor

PCI 26-40 Very Poor


PCI 11-25 Serious

PCI 0-10 Failed

"SECTION ID"  
"PCI VALUE"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





TW A:115 2023   AC REHAB \$0.18 M	TW A7:120 2023   AC REHAB \$0.30 M	TW D:135 2023   AC REHAB \$0.24 M	TW D:136 2023   AC REHAB \$0.10 M	TW D:137 2023   AC REHAB \$0.59 M
TW A3:150 2023   AC RECON \$1.24 M	TW D2:160 2023   AC RECON \$0.25 M	TW A6:175 2023   AC REHAB \$0.05 M	TW B4:203 2023   AC REHAB \$0.25 M	TW B:205 2023   AC REHAB \$1.47 M
TW B3:265 2023   AC REHAB \$0.09 M	TW B:270 2023   AC REHAB \$0.04 M	TW B3:275 2023   AC REHAB \$0.62 M	TW C1:310 2023   AC REHAB \$0.31 M	TW E2:505 2023   AC REHAB \$0.11 M
AP S:4105 2023   AC REHAB \$1.97 M	AP S:4110 2023   AC REHAB \$0.97 M	AP S:4115 2023   AC REHAB \$0.21 M	AP S:4120 2023   AC RECON \$2.00 M	AP SW:4215 2023   AC RECON \$3.08 M
AP SW:4220 2023   AC RECON \$0.91 M	AP N:4305 2023   AC RECON \$6.13 M	AP SE:4415 2023   AC RECON \$3.19 M	AP RU 13:5105 2023   AC REHAB \$0.12 M	TW B1:207 2024   AC REHAB \$0.22 M
AP SW:4205 2024   AC REHAB \$1.31 M	TW D:140 2025   AC REHAB \$0.28 M	TW E:512 2025   AC REHAB \$0.37 M	AP E:4505 2025   AC REHAB \$0.68 M	AP E:4520 2025   AC REHAB \$0.84 M
AP RU 5:5205 2026   AC REHAB \$0.37 M	TW C2:320 2027   AC REHAB \$0.54 M	TW E:510 2027   AC REHAB \$0.62 M	TW C2:520 2027   AC REHAB \$0.54 M	AP SE:4420 2027   AC REHAB \$3.19 M
TW C:305 2028   AC REHAB \$2.18 M	AP E:4525 2028   AC REHAB \$0.96 M	TW A:110 2029   AC REHAB \$0.09 M	TW A:114 2029   AC REHAB \$1.04 M	TW D:143 2029   AC REHAB \$0.14 M
AP E:4530 2029   AC REHAB \$0.38 M	AP HELI:4705 2029   AC REHAB \$1.32 M	RW 5-23:6140 2029   AC REHAB \$0.35 M	AP E:4515 2030   AC REHAB \$0.21 M	AP T-HANG:4605 2030   AC REHAB \$2.50 M
RW 5-23:6130 2030   AC REHAB \$0.15 M	RW 5-23:6155 2030   AC REHAB \$0.53 M	AP W:4805 2032   AC REHAB \$8.88 M	RW 5-23:6135 2032   AC REHAB \$0.82 M	RW 5-23:6145 2032   AC REHAB \$2.53 M

**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID

TW A — TYPICAL TAXIWAY BRANCH ID

AP S — TYPICAL APRON BRANCH ID

**PROGRAM YEAR**

2023	2028
2024	2029
2025	2030
2026	2031
2027	2032

"BRANCH", "SECTION"  
"YEAR", "REHAB ACTIVITY"  
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





# **Appendix D: Inspection Photograph Documentation**







RW 5-23, Section 6115, Sample Unit 346 – Longitudinal & Transverse Cracking



RW 5-23, Section 6140, Sample Unit 180 – Longitudinal & Transverse Cracking





RW 13-31, Section 6205, Sample Unit 381 – Longitudinal & Transverse Cracking



RW 13-31, Section 6210, Sample Unit 568 – Vicinity





TW A, Section 110, Sample Unit 141 – Swelling




TW B, Section 205, Sample Unit 140 – Vicinity





TW C, Section 305, Sample Unit 213 – Longitudinal & Transverse Cracking



TW D, Section 136, Sample Unit 122 – Vicinity





TW D2, Section 160, Sample 101 – Alligator Cracking



TW E, Section 512, Sample 102 – Vicinity





AP N, Section 4305, Sample Unit 502 – Longitudinal & Transverse Cracking and Swelling



AP S, Section 4120, Sample Unit 103 – Block Cracking and Raveling





AP SE, Section 4415, Sample Unit 102 – Block Cracking



AP SE, Section 4420, Sample Unit 707 – Depression





AP W, Section 4805, Sample Unit 451 – Longitudinal & Transverse Cracking



AP SW, Section 4215, Sample Unit 403 – Vicinity





# **Appendix E: Inspection Distress Details**



# Re-Inspection Report

FDOT

Generated Date 11/18/2022

Page 1 of 103

<b>Network:</b>	FMY	<b>Name:</b>	PAGE FIELD			
<b>Branch:</b>	AP E	<b>Name:</b>	EAST APRON	<b>Use:</b>	APRON	<b>Area:</b> 243,550 SqFt
<b>Section:</b>	4505	<b>of</b>	5	<b>From:</b>	-	<b>To:</b> -
<b>Surface:</b>	AC	<b>Family:</b>	CA653-RL-AP-AC	<b>Zone:</b>		<b>Rank:</b> P
<b>Area:</b>	58,570 SqFt	<b>Length:</b>	180 Ft	<b>Width:</b>	140 Ft	
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b> Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b> 0
<b>Section Comments:</b>						
<b>Work Date:</b>	1/1/1998	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2002	<b>Work Type:</b>	Complete Reconstruction - AC	<b>Code:</b>	CR-AC	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	1/1/2016	<b>Work Type:</b>	Surface Treatment - Seal Coat	<b>Code:</b>	ST-SC	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	5/11/2022	<b>TotalSamples:</b>	13	<b>Surveyed:</b>	2	
<b>Conditions:</b>	PCI: 75					
<b>Inspection Comments:</b>						
<b>Sample Number:</b>	101	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 75
<b>Sample Comments:</b>						
48	L & T CR	L	157.00 Ft			
57	WEATHERING	M	5000.00 SqFt			
<b>Sample Number:</b>	301	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b> 75
<b>Sample Comments:</b>						
48	L & T CR	L	148.00 Ft			
57	WEATHERING	M	5000.00 SqFt			

Network:	FMY	Name:	PAGE FIELD							
Branch:	AP E	Name:	EAST APRON		Use:	APRON	Area:	243,550 SqFt		
Section:	4515	of	5	From:	-	To:	-	Last Const.:	1/1/2002	
Surface:	AC	Family:	CA653-RL-AP-AC		Zone:		Category:		Rank:	P
Area:	13,907 SqFt		Length:	270 Ft		Width:	50 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2002		Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2016		Work Type: Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False	
Last Insp. Date:	5/11/2022		TotalSamples:	3		Surveyed:	1			
Conditions:	PCI:	83								
Inspection Comments:										
Sample Number:	102	Type:	R	Area:	5000.00 SqFt		PCI:	83		
Sample Comments:										
48	L & T CR		L	123.00 Ft						
57	WEATHERING		L	4750.00 SqFt						
57	WEATHERING		M	250.00 SqFt						

Network:	FMY	Name:		PAGE FIELD						
Branch:	AP E	Name:	EAST APRON		Use:	APRON	Area:	243,550 SqFt		
Section:	4520	of	5	From:	-	To:	-	Last Const.:	1/1/2002	
Surface:	AC	Family:	CA653-RL-AP-AC		Zone:		Category:	Rank:	P	
Area:	72,634 SqFt	Length:	490 Ft		Width:	300 Ft				
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0		Lanes:	0		
Section Comments:										
Work Date:	1/1/2002	Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2016	Work Type: Surface Treatment - Seal Coat				Code:	ST-SC	Is Major M&R:	False	
Last Insp. Date:	5/11/2022	TotalSamples:	15	Surveyed:						4
Conditions:	PCI:	74								
Inspection Comments:										
Sample Number:	203	Type:	R	Area:	3750.00 SqFt	PCI:	75			
Sample Comments:										
48	L & T CR	L	152.00 Ft							
57	WEATHERING	M	3750.00 SqFt							
Sample Number:	302	Type:	R	Area:	5000.00 SqFt	PCI:	75			
Sample Comments:										
48	L & T CR	L	42.00 Ft							
57	WEATHERING	M	5000.00 SqFt							
Sample Number:	401	Type:	R	Area:	5000.00 SqFt	PCI:	70			
Sample Comments:										
48	L & T CR	L	52.00 Ft							
48	L & T CR	M	30.00 Ft							
57	WEATHERING	M	5000.00 SqFt							
Sample Number:	600	Type:	R	Area:	5967.00 SqFt	PCI:	76			
Sample Comments:										
48	L & T CR	L	28.00 Ft							
57	WEATHERING	M	5967.00 SqFt							



Network:	FMY	Name:	PAGE FIELD						
Branch:	AP E	Name:	EAST APRON	Use:	APRON	Area:	243,550 SqFt		
Section:	4525	of	5	From:	-	To:	-	Last Const.:	1/1/2002
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:		Rank:	P
Area:	71,383 SqFt	Length:	345 Ft	Width:	290 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2002	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2016	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Last Insp. Date:	5/11/2022	TotalSamples:	18	Surveyed:	3				
Conditions:	PCI:	80							
Inspection Comments:									
Sample Number:	202	Type:	R	Area:	3205.00 SqFt	PCI:	80		
Sample Comments:									
57	WEATHERING	M	3205.00	SqFt					
Sample Number:	301	Type:	R	Area:	3750.00 SqFt	PCI:	80		
Sample Comments:									
57	WEATHERING	M	3750.00	SqFt					
Sample Number:	403	Type:	R	Area:	3750.00 SqFt	PCI:	80		
Sample Comments:									
57	WEATHERING	M	3750.00	SqFt					

Network:	FMY	Name:		PAGE FIELD			
Branch:	AP E	Name:	EAST APRON	Use:	APRON	Area:	243,550 SqFt
Section:	4530	of 5	From:	-	To:	-	Last Const.: 1/1/2002
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:	Rank: P
Area:	27,056 SqFt	Length:	910 Ft	Width:	20 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2002	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R: True
Work Date:	1/1/2016	Work Type: Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R: False
Last Insp. Date:	5/11/2022	TotalSamples:	5	Surveyed: 1			
Conditions:	PCI: 81						
Inspection Comments:							
Sample Number:	101	Type:	R	Area:	5000.00 SqFt	PCI:	81
Sample Comments:							
48	L & T CR	L	200.00 Ft				
56	SWELLING	L	15.00 SqFt				
57	WEATHERING	L	5000.00 SqFt				

Network:	FMY	Name:	PAGE FIELD						
Branch:	AP HELI	Name:	HELICOPTER APRON	Use:	APRON	Area:	93,555 SqFt		
Section:	4705	of	1	From:	-	To:	-	Last Const.:	1/1/2007
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:		Rank:	P
Area:	93,555 SqFt	Length:	765 Ft	Width:	135 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2007	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	19	Surveyed:	3				
Conditions:	PCI:	82							
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	5012.00 SqFt	PCI:	87		
Sample Comments:									
52	RAVELING	L	25.00	SqFt					
57	WEATHERING	L	4488.00	SqFt					
57	WEATHERING	M	499.00	SqFt					
Sample Number:	200	Type:	R	Area:	6750.00 SqFt	PCI:	77		
Sample Comments:									
48	L & T CR	L	73.00	Ft					
52	RAVELING	L	480.00	SqFt					
57	WEATHERING	L	5643.00	SqFt					
57	WEATHERING	M	627.00	SqFt					
Sample Number:	500	Type:	R	Area:	6750.00 SqFt	PCI:	84		
Sample Comments:									
57	WEATHERING	L	4725.00	SqFt					
57	WEATHERING	M	2025.00	SqFt					

Network:	FMY	Name:		PAGE FIELD			
Branch:	AP N	Name:	NORTH APRON	Use:	APRON	Area:	331,067 SqFt
Section:	4305	of 1	From:	-	To:	-	Last Const.: 1/1/1998
Surface:	AAC	Family:	CA653-RL-AP-AAC-APC	Zone:		Category:	Rank: P
Area:	331,067 SqFt	Length:	1,225 Ft	Width:	272 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1974	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1998	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True
Work Date:	7/1/2013	Work Type: Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R: False
Last Insp. Date:	5/11/2022	TotalSamples:	67	Surveyed: 7			
Conditions:	PCI: 52						
Inspection Comments:							
Sample Number:	207	Type:	R	Area:	5000.00 SqFt	PCI:	54
Sample Comments:							
48	L & T CR	L	864.00	Ft			
52	RAVELING	L	500.00	SqFt			
56	SWELLING	L	250.00	SqFt			
57	WEATHERING	M	4500.00	SqFt			
Sample Number:	211	Type:	R	Area:	6235.00 SqFt	PCI:	59
Sample Comments:							
48	L & T CR	L	536.00	Ft			
52	RAVELING	L	312.00	SqFt			
56	SWELLING	L	411.00	SqFt			
56	SWELLING	M	15.00	SqFt			
57	WEATHERING	M	5923.00	SqFt			
Sample Number:	301	Type:	R	Area:	5000.00 SqFt	PCI:	56
Sample Comments:							
48	L & T CR	L	536.00	Ft			
52	RAVELING	L	500.00	SqFt			
56	SWELLING	L	200.00	SqFt			
56	SWELLING	M	50.00	SqFt			
57	WEATHERING	M	4500.00	SqFt			
Sample Number:	304	Type:	R	Area:	5000.00 SqFt	PCI:	53
Sample Comments:							
48	L & T CR	L	926.00	Ft			
52	RAVELING	L	500.00	SqFt			
56	SWELLING	L	200.00	SqFt			
57	WEATHERING	M	4500.00	SqFt			
Sample Number:	502	Type:	R	Area:	5000.00 SqFt	PCI:	47
Sample Comments:							
48	L & T CR	L	485.00	Ft			
48	L & T CR	M	369.00	Ft			
52	RAVELING	L	500.00	SqFt			
56	SWELLING	L	400.00	SqFt			
57	WEATHERING	M	4500.00	SqFt			
Sample Number:	509	Type:	R	Area:	5000.00 SqFt	PCI:	45
Sample Comments:							
48	L & T CR	L	462.00	Ft			
48	L & T CR	M	262.00	Ft			
52	RAVELING	L	500.00	SqFt			
56	SWELLING	L	552.00	SqFt			
56	SWELLING	M	10.00	SqFt			
57	WEATHERING	M	4500.00	SqFt			



Sample Number: 511		Type:	R	Area:	6235.00 SqFt	PCI:	52
Sample Comments:							
43	BLOCK CR		L	1054.00	SqFt		
48	L & T CR		L	355.00	Ft		
48	L & T CR		M	50.00	Ft		
52	RAVELING		L	624.00	SqFt		
54	SHOVING		L	15.00	SqFt		
56	SWELLING		L	200.00	SqFt		
57	WEATHERING		M	5611.00	SqFt		

Network:	FMY			Name:	PAGE FIELD									
Branch:	AP RU 13			Name:	RUN-UP APRON 13			Use:	APRON		Area:	11,434 SqFt		
Section:	5105 of 1			From:	-			To:	-			Last Const.:	12/25/1999	
Surface:	AC			Family:	CA653-RL-AP-AC			Zone:				Rank:	P	
Area:	11,434 SqFt			Length:	160 Ft			Width:	60 Ft					
Slabs:	Slab Length:			Ft			Slab Width:	Ft			Joint Length:	Ft		
Shoulder:	Street Type:			Grade:			0			Lanes:	0			
Section Comments:														
Work Date:	12/25/1999			Work Type: New Construction - Initial					Code:	NU-IN		Is Major M&R:	True	
Work Date:	1/1/2020			Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R:	False	
Last Insp. Date: 5/11/2022														
TotalSamples:				2			Surveyed: 1							
Conditions:	PCI: 66													
Inspection Comments:														
Sample Number:	200			Type:	R			Area:	5390.00 SqFt			PCI:	66	
Sample Comments:														
48	L & T CR			L			515.00 Ft							
52	RAVELING			L			3234.00 SqFt							
56	SWELLING			L			28.00 SqFt							
57	WEATHERING			L			2156.00 SqFt							

Network:	FMY	Name:	PAGE FIELD						
Branch:	AP RU 5	Name:	RUN-UP APRON 5	Use:	APRON	Area:	30,022 SqFt		
Section:	5205	of	1	From:	-	To:	-	Last Const.:	1/1/2007
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:		Rank:	P
Area:	30,022 SqFt	Length:	305 Ft	Width:	105 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2007	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	6	Surveyed:	1				
Conditions:	PCI:	77							
Inspection Comments:									
Sample Number:	302	Type:	R	Area:	5000.00 SqFt	PCI:	77		
Sample Comments:									
48	L & T CR	L	4.00 Ft						
57	WEATHERING	L	2250.00 SqFt						
57	WEATHERING	M	2750.00 SqFt						

Network:	FMY	Name:		PAGE FIELD					
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	445,597 SqFt	
Section:	4103	of	6	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AAC	Family:	CA653-RL-AP-AAC-APC	Zone:		Category:		Rank:	P
Area:	10,783 SqFt	Length:	137 Ft	Width:	80 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1968	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1998	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2017	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True		
Last Insp. Date:	5/11/2022	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI: 94								
Inspection Comments:									
Sample Number:	211	Type:	R	Area:	5932.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	5932.00	SqFt					



Network:	FMY	Name:		PAGE FIELD						
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	445,597 SqFt		
Section:	4105	of	6	From:	-	To:	-	Last Const.:	1/1/1998	
Surface:	AAC	Family:	CA653-RL-AP-AAC-APC	Zone:		Category:		Rank:	P	
Area:	187,842 SqFt		Length:	1,060 Ft		Width:	175 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:			Grade:		0	Lanes:		0	
Section Comments:										
Work Date:	1/1/1968		Work Type:			BUILT	Code:	IMPORTED		
Work Date:	1/1/1998		Work Type:			OVERLAY	Code:	IMPORTED		
Last Insp. Date:		5/11/2022		TotalSamples:	33		Surveyed:			5
Conditions: PCI: 65										
Inspection Comments:										
Sample Number:	101	Type:	R	Area:		6000.00 SqFt		PCI:	42	
Sample Comments:										
43	BLOCK CR	L	3600.00 SqFt							
43	BLOCK CR	M	600.00 SqFt							
48	L & T CR	L	47.00 Ft							
52	RAVELING	L	4200.00 SqFt							
56	SWELLING	L	180.00 SqFt							
57	WEATHERING	M	1800.00 SqFt							
Sample Number:	110	Type:	R	Area:		3256.00 SqFt		PCI:	76	
Sample Comments:										
48	L & T CR	L	16.00 Ft							
57	WEATHERING	L	1628.00 SqFt							
57	WEATHERING	M	1628.00 SqFt							
Sample Number:	206	Type:	R	Area:		6000.00 SqFt		PCI:	72	
Sample Comments:										
48	L & T CR	L	102.00 Ft							
56	SWELLING	L	63.00 SqFt							
57	WEATHERING	L	3000.00 SqFt							
57	WEATHERING	M	3000.00 SqFt							
Sample Number:	304	Type:	R	Area:		5500.00 SqFt		PCI:	67	
Sample Comments:										
48	L & T CR	L	221.00 Ft							
48	L & T CR	M	120.00 Ft							
56	SWELLING	L	9.00 SqFt							
57	WEATHERING	L	2750.00 SqFt							
57	WEATHERING	M	2750.00 SqFt							
Sample Number:	309	Type:	R	Area:		5500.00 SqFt		PCI:	73	
Sample Comments:										
45	DEPRESSION	L	16.00 SqFt							
48	L & T CR	L	276.00 Ft							
57	WEATHERING	L	2750.00 SqFt							
57	WEATHERING	M	2750.00 SqFt							

Network:	FMY	Name:	PAGE FIELD							
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	445,597 SqFt		
Section:	4110	of	6	From:	-	To:	-	Last Const.:	1/1/1998	
Surface:	AC	Family:	CA653-RL-AP-AC		Zone:	Category:		Rank:	P	
Area:	92,757 SqFt		Length:	255 Ft		Width:	530 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	1/1/1998	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:		True
Last Insp. Date:	5/11/2022	TotalSamples:	20		Surveyed:	3				
Conditions:	PCI:	68								
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	5000.00 SqFt		PCI:	67		
Sample Comments:										
48	L & T CR	L	95.00	Ft						
48	L & T CR	M	25.00	Ft						
56	SWELLING	L	50.00	SqFt						
57	WEATHERING	L	2500.00	SqFt						
57	WEATHERING	M	2500.00	SqFt						
Sample Number:	304	Type:	R	Area:	5800.00 SqFt		PCI:	65		
Sample Comments:										
48	L & T CR	L	215.00	Ft						
48	L & T CR	M	25.00	Ft						
56	SWELLING	L	150.00	SqFt						
57	WEATHERING	L	2900.00	SqFt						
57	WEATHERING	M	2900.00	SqFt						
Sample Number:	502	Type:	R	Area:	3000.00 SqFt		PCI:	77		
Sample Comments:										
48	L & T CR	L	6.00	Ft						
57	WEATHERING	L	1500.00	SqFt						
57	WEATHERING	M	1500.00	SqFt						

Network:	FMY	Name:	PAGE FIELD						
Branch:	AP S	Name:	SOUTH APRON	Use:	APRON	Area:	445,597 SqFt		
Section:	4115	of	6	From:	-	To:	-	Last Const.:	1/1/2003
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:		Rank:	P
Area:	19,731 SqFt	Length:	165 Ft	Width:	147 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2003	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True		
Last Insp. Date:	5/11/2022	TotalSamples:	4	Surveyed:	1				
Conditions:	PCI:	64							
Inspection Comments:									
Sample Number:	201	Type:	R	Area:	4609.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	L	341.00	Ft					
48	L & T CR	M	25.00	Ft					
56	SWELLING	L	10.00	SqFt					
57	WEATHERING	L	3457.00	SqFt					
57	WEATHERING	M	1152.00	SqFt					

Network:	FMY	Name:		PAGE FIELD						
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	445,597 SqFt		
Section:	4120	of 6	From:	-		To:	-		Last Const.:	1/1/1998
Surface:	AAC	Family:	CA653-RL-AP-AAC-APC	Zone:			Category:	Rank: P		
Area:	108,068 SqFt	Length:	730 Ft	Width:	200 Ft					
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:		0	
Section Comments:										
Work Date:	1/1/1970	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True		
Work Date:	1/1/1998	Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True		
Last Insp. Date:	5/11/2022	TotalSamples:		21	Surveyed:		3			
Conditions:	PCI:	47								
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	5973.00 SqFt	PCI:	40			
Sample Comments:										
43	BLOCK CR	L	2987.00	SqFt						
43	BLOCK CR	M	2986.00	SqFt						
52	RAVELING	L	5973.00	SqFt						
Sample Number:	103	Type:	R	Area:	7232.00 SqFt	PCI:	42			
Sample Comments:										
43	BLOCK CR	M	7232.00	SqFt						
52	RAVELING	L	7232.00	SqFt						
Sample Number:	305	Type:	R	Area:	5000.00 SqFt	PCI:	64			
Sample Comments:										
48	L & T CR	L	88.00	Ft						
48	L & T CR	M	10.00	Ft						
49	OIL SPILLAGE	N	5.00	SqFt						
52	RAVELING	L	25.00	SqFt						
56	SWELLING	L	15.00	SqFt						
57	WEATHERING	M	4975.00	SqFt						



Network:	FMY	Name:		PAGE FIELD					
Branch:	AP S	Name:	SOUTH APRON		Use:	APRON	Area:	445,597 SqFt	
Section:	4125	of	6	From:	-	To:	-	Last Const.:	7/1/2020
Surface:	AAC	Family:	CA653-RL-AP-AAC-APC		Zone:		Category:	Rank: P	
Area:	26,416 SqFt		Length:	285 Ft		Width:	90 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft	
Shoulder:	Street Type:			Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1970		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1998		Work Type: BUILT			Code:	IMPORTED		Is Major M&R: True
Work Date:	7/1/2020		Work Type: Mill and Overlay			Code:	ML-OVL		Is Major M&R: True
Last Insp. Date:	11/14/2018		TotalSamples:	27		Surveyed:	3		
Conditions:	PCI: 49		NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	103		Type:	R		Area:	5000.00 SqFt		PCI: 42
Sample Comments:									
43	BLOCK CR		M	5000.00 SqFt					
52	RAVELING		L	5000.00 SqFt					
Sample Number:	201		Type:	R		Area:	5000.00 SqFt		PCI: 35
Sample Comments:									
43	BLOCK CR		L	700.00 SqFt					
43	BLOCK CR		M	3600.00 SqFt					
48	L & T CR		L	38.00 Ft					
48	L & T CR		M	50.00 Ft					
52	RAVELING		L	3600.00 SqFt					
57	WEATHERING		M	1400.00 SqFt					
Sample Number:	305		Type:	R		Area:	5000.00 SqFt		PCI: 69
Sample Comments:									
48	L & T CR		L	61.00 Ft					
52	RAVELING		L	250.00 SqFt					
56	SWELLING		L	5.00 SqFt					
57	WEATHERING		M	4750.00 SqFt					

Network:	FMY	Name:		PAGE FIELD			
Branch:	AP SE	Name:	SOUTHEAST APRON	Use:	APRON	Area:	421,791 SqFt
Section:	4415	of 2	From:	-	To:	-	Last Const.: 1/1/1998
Surface:	AAC	Family:	CA653-RL-AP-AAC-APC	Zone:		Category:	Rank: P
Area:	172,279 SqFt	Length:	525 Ft	Width:	323 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1998	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1998	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	5/11/2022	TotalSamples:	32	Surveyed: 5			
Conditions:	PCI: 39						
Inspection Comments:							
Sample Number:	102	Type:	R	Area:	5000.00 SqFt	PCI:	35
Sample Comments:							
43	BLOCK CR	L	2500.00 SqFt				
43	BLOCK CR	M	2500.00 SqFt				
52	RAVELING	L	4500.00 SqFt				
52	RAVELING	M	500.00 SqFt				
56	SWELLING	L	100.00 SqFt				
Sample Number:	105	Type:	R	Area:	5000.00 SqFt	PCI:	42
Sample Comments:							
43	BLOCK CR	L	4750.00 SqFt				
43	BLOCK CR	M	250.00 SqFt				
52	RAVELING	L	4500.00 SqFt				
52	RAVELING	M	500.00 SqFt				
56	SWELLING	L	100.00 SqFt				
Sample Number:	210	Type:	R	Area:	5200.00 SqFt	PCI:	36
Sample Comments:							
43	BLOCK CR	L	3380.00 SqFt				
43	BLOCK CR	M	1820.00 SqFt				
52	RAVELING	L	4680.00 SqFt				
52	RAVELING	M	520.00 SqFt				
56	SWELLING	L	100.00 SqFt				
Sample Number:	303	Type:	R	Area:	6180.00 SqFt	PCI:	40
Sample Comments:							
43	BLOCK CR	L	5253.00 SqFt				
43	BLOCK CR	M	927.00 SqFt				
52	RAVELING	L	5562.00 SqFt				
52	RAVELING	M	618.00 SqFt				
56	SWELLING	L	100.00 SqFt				
Sample Number:	308	Type:	R	Area:	6180.00 SqFt	PCI:	42
Sample Comments:							
43	BLOCK CR	L	5871.00 SqFt				
43	BLOCK CR	M	309.00 SqFt				
52	RAVELING	L	5562.00 SqFt				
52	RAVELING	M	618.00 SqFt				
56	SWELLING	L	200.00 SqFt				

Network:	FMY	Name:		PAGE FIELD			
Branch:	AP SE	Name:	SOUTHEAST APRON	Use:	APRON	Area:	421,791 SqFt
Section:	4420	of 2	From:	-	To:	-	Last Const.: 1/1/2006
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:	Category:	Rank:	P
Area:	249,512 SqFt	Length:	648 Ft	Width:	385 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:	Grade:	0	Lanes:	0	
Section Comments:							
Work Date:	1/1/1998	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2006	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	51	Surveyed:	7		
Conditions:	PCI: 78						
Inspection Comments:							
Sample Number:	311	Type:	R	Area:	4800.00 SqFt	PCI:	86
Sample Comments:							
48	L & T CR	L	52.00 Ft				
57	WEATHERING	L	4560.00 SqFt				
57	WEATHERING	M	240.00 SqFt				
Sample Number:	413	Type:	R	Area:	5000.00 SqFt	PCI:	84
Sample Comments:							
48	L & T CR	L	58.00 Ft				
57	WEATHERING	L	4500.00 SqFt				
57	WEATHERING	M	500.00 SqFt				
Sample Number:	504	Type:	R	Area:	5745.00 SqFt	PCI:	65
Sample Comments:							
48	L & T CR	L	381.00 Ft				
52	RAVELING	L	44.00 SqFt				
56	SWELLING	L	167.00 SqFt				
57	WEATHERING	L	5131.00 SqFt				
57	WEATHERING	M	570.00 SqFt				
Sample Number:	508	Type:	R	Area:	5000.00 SqFt	PCI:	81
Sample Comments:							
45	DEPRESSION	L	50.00 SqFt				
48	L & T CR	L	2.00 Ft				
52	RAVELING	L	10.00 SqFt				
57	WEATHERING	L	4740.00 SqFt				
57	WEATHERING	M	250.00 SqFt				
Sample Number:	610	Type:	R	Area:	5000.00 SqFt	PCI:	85
Sample Comments:							
48	L & T CR	L	32.00 Ft				
56	SWELLING	L	9.00 SqFt				
57	WEATHERING	L	4750.00 SqFt				
57	WEATHERING	M	250.00 SqFt				
Sample Number:	706	Type:	R	Area:	5472.00 SqFt	PCI:	70
Sample Comments:							
45	DEPRESSION	L	53.00 SqFt				
48	L & T CR	L	52.00 Ft				
57	WEATHERING	L	2736.00 SqFt				
57	WEATHERING	M	2736.00 SqFt				
Sample Number:	707	Type:	A	Area:	5474.00 SqFt	PCI:	63
Sample Comments:							
45	DEPRESSION	L	33.00 SqFt				
45	DEPRESSION	M	76.00 SqFt				
48	L & T CR	L	74.00 Ft				

57	WEATHERING	L	2737.00	SqFt
57	WEATHERING	M	2737.00	SqFt



Network:	FMY		Name:		PAGE FIELD							
Branch:	AP SW		Name:	SOUTHWEST APRON		Use:	APRON	Area:	334,111 SqFt			
Section:	4205		of	3	From:	-		To:	-		Last Const.:	1/1/1998
Surface:	AC		Family:	CA653-RL-AP-AC		Zone:			Category:	Rank: P		
Area:	118,829 SqFt		Length:	120 Ft		Width:	1,046 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	1/1/1998		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Last Insp. Date:	5/11/2022		TotalSamples:	20		Surveyed:	3					
Conditions:	PCI: 72											
Inspection Comments:												
Sample Number:	100		Type:	R		Area:	6968.00 SqFt		PCI:	76		
Sample Comments:												
48	L & T CR		L	126.00 Ft								
52	RAVELING		L	1394.00 SqFt								
57	WEATHERING		L	5574.00 SqFt								
Sample Number:	108		Type:	R		Area:	5080.00 SqFt		PCI:	67		
Sample Comments:												
48	L & T CR		L	40.00 Ft								
52	RAVELING		L	3556.00 SqFt								
57	WEATHERING		M	1524.00 SqFt								
Sample Number:	204		Type:	R		Area:	6059.00 SqFt		PCI:	70		
Sample Comments:												
48	L & T CR		L	163.00 Ft								
48	L & T CR		M	15.00 Ft								
57	WEATHERING		M	6059.00 SqFt								

Network:		FMY		Name:		PAGE FIELD							
Branch:	AP SW		Name:	SOUTHWEST APRON		Use:	APRON	Area:	334,111 SqFt				
Section:	4215		of	3	From:	-		To:	-		Last Const.:	1/1/1966	
Surface:	AC		Family:	CA653-RL-AP-AC		Zone:		Category:	Rank:			P	
Area:	166,211 SqFt		Length:	446 Ft		Width:	386 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1966		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	1/1/1998		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False	
Last Insp. Date: 5/11/2022													
Conditions:		PCI:		47		TotalSamples: 35							Surveyed: 4
Inspection Comments:													
Sample Number:	202		Type:	R		Area:	5000.00 SqFt		PCI:	41			
Sample Comments:													
43	BLOCK CR		L	4500.00		SqFt							
43	BLOCK CR		M	500.00		SqFt							
52	RAVELING		L	4750.00		SqFt							
52	RAVELING		M	250.00		SqFt							
56	SWELLING		L	250.00		SqFt							
Sample Number:	351		Type:	R		Area:	5000.00 SqFt		PCI:	49			
Sample Comments:													
43	BLOCK CR		L	4596.00		SqFt							
52	RAVELING		L	4750.00		SqFt							
52	RAVELING		M	250.00		SqFt							
56	SWELLING		L	100.00		SqFt							
Sample Number:	403		Type:	R		Area:	3250.00 SqFt		PCI:	38			
Sample Comments:													
43	BLOCK CR		L	2600.00		SqFt							
43	BLOCK CR		M	650.00		SqFt							
52	RAVELING		L	3088.00		SqFt							
52	RAVELING		M	162.00		SqFt							
56	SWELLING		L	250.00		SqFt							
Sample Number:	500		Type:	R		Area:	5317.00 SqFt		PCI:	55			
Sample Comments:													
48	L & T CR		L	272.00		Ft							
48	L & T CR		M	150.00		Ft							
52	RAVELING		L	4785.00		SqFt							
56	SWELLING		L	150.00		SqFt							
57	WEATHERING		M	532.00		SqFt							

Network:	FMY	Name:	PAGE FIELD							
Branch:	AP SW	Name:	SOUTHWEST APRON		Use:	APRON	Area:	334,111 SqFt		
Section:	4220	of	3	From:	-	To:	-	Last Const.:	1/1/1998	
Surface:	AC	Family:	CA653-RL-AP-AC		Zone:		Category:		Rank:	P
Area:	49,071 SqFt	Length:	392 Ft		Width:	127 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1998	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	8		Surveyed:	1				
Conditions:	PCI:	47								
Inspection Comments:										
Sample Number:	404	Type:	R	Area:	6330.00 SqFt		PCI:	47		
Sample Comments:										
43	BLOCK CR	L	6014.00	SqFt						
43	BLOCK CR	M	316.00	SqFt						
52	RAVELING	L	6014.00	SqFt						
52	RAVELING	M	316.00	SqFt						

Network:	FMY			Name:	PAGE FIELD				
Branch:	AP T-HANG		Name:	APRON T-HANG		Use:	APRON	Area:	169,083 SqFt
Section:	4605	of	1	From:	-	To:	-	Last Const.:	1/1/2006
Surface:	AC	Family:	CA653-RL-AP-AC		Zone:		Category:		Rank: P
Area:	169,083 SqFt		Length:	2,568 Ft		Width:	75 Ft		
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/2006		Work Type: New Construction - AC			Code:	NC-AC		Is Major M&R: True
Last Insp. Date:	5/11/2022		TotalSamples:	36		Surveyed:	5		
Conditions:	PCI:	83							
Inspection Comments:									
Sample Number:	200	Type:	R	Area:	3608.00 SqFt		PCI:	86	
Sample Comments:									
48	L & T CR	L	26.00 Ft						
57	WEATHERING	L	3428.00 SqFt						
57	WEATHERING	M	180.00 SqFt						
Sample Number:	206	Type:	R	Area:	5250.00 SqFt		PCI:	85	
Sample Comments:									
48	L & T CR	L	29.00 Ft						
57	WEATHERING	L	4725.00 SqFt						
57	WEATHERING	M	525.00 SqFt						
Sample Number:	302	Type:	R	Area:	5250.00 SqFt		PCI:	83	
Sample Comments:									
45	DEPRESSION	L	28.00 SqFt						
48	L & T CR	L	5.00 Ft						
57	WEATHERING	L	4725.00 SqFt						
57	WEATHERING	M	525.00 SqFt						
Sample Number:	310	Type:	R	Area:	5250.00 SqFt		PCI:	76	
Sample Comments:									
48	L & T CR	L	27.00 Ft						
57	WEATHERING	L	2550.00 SqFt						
57	WEATHERING	M	2700.00 SqFt						
Sample Number:	314	Type:	R	Area:	3380.00 SqFt		PCI:	89	
Sample Comments:									
57	WEATHERING	L	3042.00 SqFt						
57	WEATHERING	M	338.00 SqFt						

Network:	FMY	Name:	PAGE FIELD				
Branch:	AP W	Name:	WEST APRON	Use:	APRON	Area:	560,890 SqFt
Section:	4805	of 2	From:	-	To:	-	Last Const.: 1/1/2009
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:	Rank: P
Area:	545,226 SqFt	Length:	1,519 Ft	Width:	388 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2009	Work Type: New Construction - Initial			Code:	NU-IN	Is Major M&R: True
Work Date:	7/1/2013	Work Type: Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R: False
Work Date:	1/1/2021	Work Type: Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R: False
Last Insp. Date:	5/11/2022	TotalSamples:	113	Surveyed:	10		
Conditions:	PCI: 89						
Inspection Comments:							
Sample Number:	302	Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR	L	123.00	Ft			
Sample Number:	451	Type:	R	Area:	5000.00 SqFt	PCI:	79
Sample Comments:							
48	L & T CR	L	200.00	Ft			
57	WEATHERING	L	2500.00	SqFt			
57	WEATHERING	M	250.00	SqFt			
Sample Number:	456	Type:	R	Area:	3800.00 SqFt	PCI:	100
Sample Comments:							
<No Distress>							
Sample Number:	510	Type:	R	Area:	5000.00 SqFt	PCI:	88
Sample Comments:							
48	L & T CR	L	94.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	603	Type:	R	Area:	5000.00 SqFt	PCI:	87
Sample Comments:							
48	L & T CR	L	81.00	Ft			
57	WEATHERING	L	4955.00	SqFt			
57	WEATHERING	M	45.00	SqFt			
Sample Number:	607	Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR	L	7.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	655	Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR	L	14.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	709	Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
48	L & T CR	L	18.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	756	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	43.00	Ft			
57	WEATHERING	L	5000.00	SqFt			



Sample Number:		850	Type:	R	Area:	5000.00 SqFt	PCI:	85
Sample Comments:								
48	L & T CR			L	19.00	Ft		
57	WEATHERING			L	4500.00	SqFt		
57	WEATHERING			M	500.00	SqFt		

Network:	FMY	Name:		PAGE FIELD						
Branch:	AP W	Name:	WEST APRON		Use:	APRON	Area:	560,890 SqFt		
Section:	4818	of	2	From:	-	To:	-	Last Const.:	1/1/2009	
Surface:	PCC	Family:	CA653-RL-AP-PCC		Zone:	Category:		Rank:	P	
Area:	15,664 SqFt		Length:	125 Ft		Width:	125 Ft			
Slabs:	100	Slab Length:	12 Ft		Slab Width:	12 Ft		Joint Length:	2,250 Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:	0		
Section Comments:										
Work Date:	1/1/2009		Work Type: New Construction - Initial			Code:	NU-IN			
Is Major M&R:		True								
Last Insp. Date:	5/11/2022		TotalSamples:	4		Surveyed:	1			
Conditions:	PCI: 91									
Inspection Comments:										
Sample Number:	900		Type:	R		Area:	25.00 Slabs		PCI:	91
Sample Comments:										
73	SHRINKAGE CR		N	15.00 Slabs						

Network:	FMY	Name:		PAGE FIELD			
Branch:	RW 13-31	Name:	RUNWAY 13-31	Use:	RUNWAY	Area:	714,113 SqFt
Section:	6205	of 2	From:	-	To:	-	Last Const.: 1/1/2018
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC	Zone:	Category:	Rank:	P
Area:	476,075 SqFt	Length:	4,795 Ft	Width:	100 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1977	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1977	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2018	Work Type: Mill and Overlay			Code:	ML-OVL	Is Major M&R: True
Last Insp. Date:	5/11/2022	TotalSamples:	95	Surveyed: 21			
Conditions:	PCI: 89						
Inspection Comments:							
Sample Number:	301	Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
48	L & T CR	L	39.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	307	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	47.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	314	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	76.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	321	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	43.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	325	Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
48	L & T CR	L	36.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	328	Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR	L	8.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	334	Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
48	L & T CR	L	18.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	340	Type:	R	Area:	5000.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	343	Type:	R	Area:	5000.00 SqFt	PCI:	93
Sample Comments:							
52	RAVELING	L	9.00 SqFt				
57	WEATHERING	L	4991.00 SqFt				

Sample Number: 344		Type:	R	Area:		4306.00 SqFt	PCI:	89
Sample Comments:								
48	L & T CR		L	19.00	Ft			
56	SWELLING		L	5.00	SqFt			
57	WEATHERING		L	4306.00	SqFt			
Sample Number: 350		Type:	R	Area:		5000.00 SqFt	PCI:	87
Sample Comments:								
48	L & T CR		L	61.00	Ft			
56	SWELLING		L	38.00	SqFt			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 356		Type:	R	Area:		5000.00 SqFt	PCI:	87
Sample Comments:								
48	L & T CR		L	69.00	Ft			
56	SWELLING		L	26.00	SqFt			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 363		Type:	R	Area:		5000.00 SqFt	PCI:	89
Sample Comments:								
48	L & T CR		L	70.00	Ft			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 366		Type:	R	Area:		5000.00 SqFt	PCI:	94
Sample Comments:								
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 370		Type:	R	Area:		5000.00 SqFt	PCI:	91
Sample Comments:								
48	L & T CR		L	13.00	Ft			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 377		Type:	R	Area:		5000.00 SqFt	PCI:	89
Sample Comments:								
48	L & T CR		L	36.00	Ft			
56	SWELLING		L	2.00	SqFt			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 381		Type:	R	Area:		5000.00 SqFt	PCI:	88
Sample Comments:								
48	L & T CR		L	89.00	Ft			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 385		Type:	R	Area:		5000.00 SqFt	PCI:	89
Sample Comments:								
48	L & T CR		L	21.00	Ft			
56	SWELLING		L	1.00	SqFt			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 391		Type:	R	Area:		5000.00 SqFt	PCI:	87
Sample Comments:								
48	L & T CR		L	55.00	Ft			
56	SWELLING		L	18.00	SqFt			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 394		Type:	R	Area:		5000.00 SqFt	PCI:	85
Sample Comments:								
48	L & T CR		L	90.00	Ft			
56	SWELLING		L	50.00	SqFt			
57	WEATHERING		L	5000.00	SqFt			
Sample Number: 397		Type:	R	Area:		5982.00 SqFt	PCI:	87
Sample Comments:								
48	L & T CR		L	100.00	Ft			
56	SWELLING		L	6.00	SqFt			





Network:	FMY		Name:	PAGE FIELD								
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY		Area:	714,113 SqFt		
Section:	6210 of 2		From:	-		To:	-		Last Const.:	1/1/2018		
Surface:	AC		Family:	CA653-RL-RW-AC		Zone:			Category:	Rank: P		
Area:	238,038 SqFt		Length:	9,622 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1977		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1977		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2018		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:	48		Surveyed:	8					
Conditions:	PCI: 92											
Inspection Comments:												
Sample Number:	124		Type:	R		Area:	5000.00 SqFt		PCI:	92		
Sample Comments:												
48	L & T CR		L	6.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	156		Type:	R		Area:	5000.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	28.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	180		Type:	R		Area:	5000.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	504		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	9.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	536		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	12.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	548		Type:	R		Area:	5399.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	21.00 Ft								
57	WEATHERING		L	5399.00 SqFt								
Sample Number:	568		Type:	R		Area:	5000.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	588		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	8.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	FMY	Name:		PAGE FIELD							
Branch:	RW 5-23	Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	960,900 SqFt			
Section:	6105	of 12	From:	-		To:	-		Last Const.:	1/1/2017	
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC		Zone:	Category:		Rank:		P	
Area:	100,000 SqFt		Length:	1,000 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1976		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/1997		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/2017		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:	20		Surveyed: 5					
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	301		Type:	R		Area:	5000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	306		Type:	R		Area:	5000.00 SqFt		PCI:	92	
Sample Comments:											
48	L & T CR		L	4.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	311		Type:	R		Area:	5000.00 SqFt		PCI:	89	
Sample Comments:											
48	L & T CR		L	44.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	315		Type:	R		Area:	5000.00 SqFt		PCI:	89	
Sample Comments:											
48	L & T CR		L	76.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	318		Type:	R		Area:	5000.00 SqFt		PCI:	89	
Sample Comments:											
48	L & T CR		L	40.00 Ft							
57	WEATHERING		L	5000.00 SqFt							

Network:	FMY	Name:		PAGE FIELD							
Branch:	RW 5-23	Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	960,900 SqFt			
Section:	6110	of 12	From:	-		To:	-		Last Const.:	1/1/2017	
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC		Zone:	Category:		Rank:		P	
Area:	50,000 SqFt		Length:	2,000 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1976		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/1997		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/2017		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:	10		Surveyed:	2				
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	108	Type:	R	Area:	5000.00 SqFt		PCI:	94			
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	516	Type:	R	Area:	5000.00 SqFt		PCI:	94			
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							

Network:	FMY	Name:	PAGE FIELD				
Branch:	RW 5-23	Name:	RUNWAY 5-23	Use:	RUNWAY	Area:	960,900 SqFt
Section:	6115	of 12	From:	-	To:	-	Last Const.: 1/1/2017
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC	Zone:		Category:	Rank: P
Area:	280,000 SqFt	Length:	2,800 Ft	Width:	100 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1976	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R: True
Work Date:	1/1/1997	Work Type: Overlay - AC Structural			Code:	OL-AS	Is Major M&R: True
Work Date:	1/1/2017	Work Type: Mill and Overlay			Code:	ML-OVL	Is Major M&R: True
Last Insp. Date: 5/11/2022							
TotalSamples:		56	Surveyed: 12				
Conditions:	PCI: 89						
Inspection Comments:							
Sample Number:	321	Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR	L	14.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	326	Type:	R	Area:	5000.00 SqFt	PCI:	88
Sample Comments:							
48	L & T CR	L	85.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	331	Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
48	L & T CR	L	18.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	336	Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR	L	14.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	341	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	54.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	346	Type:	R	Area:	5000.00 SqFt	PCI:	87
Sample Comments:							
48	L & T CR	L	105.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	351	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	50.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	356	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	48.00 Ft				
57	WEATHERING	L	5000.00 SqFt				
Sample Number:	361	Type:	R	Area:	5000.00 SqFt	PCI:	87
Sample Comments:							
48	L & T CR	L	111.00 Ft				
57	WEATHERING	L	5000.00 SqFt				

Sample Number: 366		Type: R	Area: 5000.00 SqFt	PCI: 94
Sample Comments:				
57	WEATHERING	L	5000.00 SqFt	
Sample Number: 371		Type: R	Area: 5000.00 SqFt	PCI: 89
Sample Comments:				
48	L & T CR	L	56.00 Ft	
57	WEATHERING	L	5000.00 SqFt	
Sample Number: 375		Type: R	Area: 5000.00 SqFt	PCI: 88
Sample Comments:				
48	L & T CR	L	90.00 Ft	
57	WEATHERING	L	5000.00 SqFt	



Network:	FMY	Name:		PAGE FIELD					
Branch:	RW 5-23	Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	960,900 SqFt	
Section:	6120	of 12	From:	-		To:	-		
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC		Zone:	Category:	Rank: P		
Area:	140,000 SqFt		Length:	5,581 Ft		Width:	25 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1966		Work Type: New Construction - AC				Code:	NC-AC	
Work Date:	1/1/1976		Work Type: Overlay - AC Structural				Code:	OL-AS	
Work Date:	1/1/1997		Work Type: Overlay - AC Structural				Code:	OL-AS	
Work Date:	1/1/2017		Work Type: Mill and Overlay				Code:	ML-OVL	
Last Insp. Date:	5/11/2022		TotalSamples:	28		Surveyed:	5		
Conditions:	PCI: 92								
Inspection Comments:									
Sample Number:	120	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	140	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	164	Type:	R	Area:	5000.00 SqFt		PCI:	91	
Sample Comments:									
48	L & T CR		L	8.00 Ft					
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	532	Type:	R	Area:	5000.00 SqFt		PCI:	89	
Sample Comments:									
48	L & T CR		L	44.00 Ft					
57	WEATHERING		L	5000.00 SqFt					
Sample Number:	552	Type:	R	Area:	5000.00 SqFt		PCI:	89	
Sample Comments:									
48	L & T CR		L	40.00 Ft					
57	WEATHERING		L	5000.00 SqFt					

Network:	FMY	Name:	PAGE FIELD						
Branch:	RW 5-23	Name:	RUNWAY 5-23	Use:	RUNWAY	Area:	960,900 SqFt		
Section:	6125	of	12	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC	Zone:		Category:		Rank:	P
Area:	20,000 SqFt	Length:	200 Ft	Width:	100 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1966	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1976	Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/1997	Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2017	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	4	Surveyed:	1				
Conditions:	PCI: 89								
Inspection Comments:									
Sample Number:	378	Type:	R	Area:	5000.00 SqFt	PCI:	89		
Sample Comments:									
48	L & T CR	L	68.00 Ft						
57	WEATHERING	L	5000.00 SqFt						

Network:		FMY		Name:		PAGE FIELD													
Branch:		RW 5-23		Name:		RUNWAY 5-23		Use:		RUNWAY		Area:		960,900 SqFt					
Section:		6130		of		12		From:		-		To:		-		Last Const.:		1/1/2017	
Surface:		AAC		Family:		CA653-RL-RW-AAC-APC		Zone:				Category:				Rank:		P	
Area:		10,000 SqFt		Length:		400 Ft		Width:		25 Ft									
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft					
Shoulder:				Street Type:				Grade:		0		Lanes:		0					
Section Comments:																			
Work Date:		1/1/1966		Work Type:		New Construction - AC		Code:		NC-AC		Is Major M&R:		True					
Work Date:		1/1/1976		Work Type:		Overlay - AC Structural		Code:		OL-AS		Is Major M&R:		True					
Work Date:		1/1/1997		Work Type:		Overlay - AC Structural		Code:		OL-AS		Is Major M&R:		True					
Work Date:		1/1/2017		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True					
Last Insp. Date:		5/11/2022		TotalSamples:		2		Surveyed:		1									
Conditions:		PCI:		84															
Inspection Comments:																			
Sample Number:		176		Type:		R		Area:		5000.00 SqFt		PCI:		84					
Sample Comments:																			
48		L & T CR		L		167.00 Ft													
57		WEATHERING		L		5000.00 SqFt													

Network:	FMY	Name:	PAGE FIELD						
Branch:	RW 5-23	Name:	RUNWAY 5-23	Use:	RUNWAY	Area:	960,900 SqFt		
Section:	6135	of	12	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC	Zone:		Category:		Rank:	P
Area:	50,000 SqFt	Length:	500 Ft	Width:	100 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1966	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1976	Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/1997	Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2017	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	10	Surveyed:	2				
Conditions:	PCI:	87							
Inspection Comments:									
Sample Number:	382	Type:	R	Area:	5000.00 SqFt	PCI:	88		
Sample Comments:									
48	L & T CR	L	95.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	386	Type:	R	Area:	5000.00 SqFt	PCI:	86		
Sample Comments:									
48	L & T CR	L	134.00 Ft						
57	WEATHERING	L	5000.00 SqFt						

Network:	FMY		Name:	PAGE FIELD								
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	960,900 SqFt			
Section:	6140		of	12	From:	-		To:	-		Last Const.:	1/1/2017
Surface:	AAC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	25,000 SqFt		Length:	1,000 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1966		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/1976		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/1997		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/2017		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:	6		Surveyed:	2					
Conditions:	PCI:	82										
Inspection Comments:												
Sample Number:	180		Type:	R		Area:	5000.00 SqFt		PCI:	83		
Sample Comments:												
48	L & T CR		L	194.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	584		Type:	R		Area:	3750.00 SqFt		PCI:	82		
Sample Comments:												
48	L & T CR		L	162.00 Ft								
57	WEATHERING		L	3750.00 SqFt								



Network:	FMY	Name:		PAGE FIELD					
Branch:	RW 5-23	Name:	RUNWAY 5-23	Use:	RUNWAY	Area:	960,900 SqFt		
Section:	6145	of	12	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AAC	Family:	CA653-RL-RW-AAC-APC	Zone:		Category:		Rank:	P
Area:	155,000 SqFt	Length:	1,550 Ft	Width:	100 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1966	Work Type:			New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1976	Work Type:			Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/1997	Work Type:			Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2017	Work Type:			Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	31	Surveyed:	7				
Conditions:	PCI: 86								
Inspection Comments:									
Sample Number:	390	Type:	R	Area:	5000.00 SqFt	PCI:	87		
Sample Comments:									
48	L & T CR	L	116.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	397	Type:	R	Area:	5000.00 SqFt	PCI:	85		
Sample Comments:									
48	L & T CR	L	147.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	401	Type:	R	Area:	5000.00 SqFt	PCI:	88		
Sample Comments:									
48	L & T CR	L	100.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	405	Type:	R	Area:	5000.00 SqFt	PCI:	86		
Sample Comments:									
48	L & T CR	L	131.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	413	Type:	R	Area:	5000.00 SqFt	PCI:	82		
Sample Comments:									
48	L & T CR	L	208.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	416	Type:	R	Area:	5000.00 SqFt	PCI:	84		
Sample Comments:									
48	L & T CR	L	173.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	419	Type:	R	Area:	5000.00 SqFt	PCI:	88		
Sample Comments:									
48	L & T CR	L	98.00 Ft						
57	WEATHERING	L	5000.00 SqFt						

Network:		FMY		Name:		PAGE FIELD						
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	960,900 SqFt			
Section:	6150		of	12	From:	-		To:	-		Last Const.:	1/1/2017
Surface:	AAC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	77,500 SqFt		Length:	3,100 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1966		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/1976		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/1997		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/2017		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:	16		Surveyed:	5					
Conditions:	PCI: 88											
Inspection Comments:												
Sample Number:	196		Type:	R		Area:	5000.00 SqFt		PCI:	88		
Sample Comments:												
48	L & T CR		L	91.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	204		Type:	R		Area:	5000.00 SqFt		PCI:	84		
Sample Comments:												
48	L & T CR		L	174.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	216		Type:	R		Area:	6250.00 SqFt		PCI:	88		
Sample Comments:												
48	L & T CR		L	116.00 Ft								
57	WEATHERING		L	6250.00 SqFt								
Sample Number:	592		Type:	R		Area:	3750.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	22.00 Ft								
57	WEATHERING		L	3750.00 SqFt								
Sample Number:	608		Type:	R		Area:	5000.00 SqFt		PCI:	89		
Sample Comments:												
48	L & T CR		L	40.00 Ft								
57	WEATHERING		L	5000.00 SqFt								

Network:	FMY		Name:	PAGE FIELD										
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	960,900 SqFt					
Section:	6155		of	12		From:	-		To:	-		Last Const.:	1/1/2017	
Surface:	AAC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	35,600 SqFt		Length:	356 Ft		Width:	100 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1976		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Work Date:	1/1/1997		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True		
Work Date:	1/1/2017		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True		
Last Insp. Date:	5/11/2022		TotalSamples:	7		Surveyed:	2							
Conditions:	PCI: 84													
Inspection Comments:														
Sample Number:	422		Type:	R		Area:	5000.00 SqFt		PCI:	81				
Sample Comments:														
48	L & T CR		L	121.00 Ft										
48	L & T CR		M	10.00 Ft										
57	WEATHERING		L	5000.00 SqFt										
Sample Number:	425		Type:	R		Area:	5000.00 SqFt		PCI:	86				
Sample Comments:														
48	L & T CR		L	121.00 Ft										
57	WEATHERING		L	5000.00 SqFt										

Network:		FMY		Name:		PAGE FIELD																	
Branch:		RW 5-23		Name:		RUNWAY 5-23		Use:		RUNWAY		Area:		960,900 SqFt									
Section:		6160		of		12		From:		-		To:		-		Last Const.:		1/1/2017					
Surface:		AAC		Family:		CA653-RL-RW-AAC-APC		Zone:				Category:				Rank:		P					
Area:		17,800 SqFt		Length:		712 Ft		Width:		25 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				1/1/1976				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:		True	
Work Date:				1/1/1997				Work Type:				Overlay - AC Structural				Code:		OL-AS		Is Major M&R:		True	
Work Date:				1/1/2017				Work Type:				Mill and Overlay				Code:		ML-OVL		Is Major M&R:		True	
Last Insp. Date:				5/11/2022				TotalSamples:				4				Surveyed:				1			
Conditions:				PCI:				88															
Inspection Comments:																							
Sample Number:				624				Type:		R		Area:		5150.00 SqFt				PCI:		88			
Sample Comments:																							
48		L & T CR		L		99.00 Ft																	
57		WEATHERING		L		5150.00 SqFt																	

Network:	FMY		Name:	PAGE FIELD						
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	294,275 SqFt	
Section:	103	of 6	From:	-			To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:				Category:	Rank: P	
Area:	12,403 SqFt	Length:	271 Ft	Width:	50 Ft					
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:	0			Lanes:	0		
Section Comments:										
Work Date:	1/1/1968	Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True		
Work Date:	1/1/2017	Work Type: Complete Reconstruction - AC				Code:	CR-AC	Is Major M&R: True		
Last Insp. Date: 5/11/2022										
TotalSamples:		3		Surveyed: 1						
Conditions: PCI: 94										
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	5000.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	5000.00 SqFt						



Network:	FMY	Name:		PAGE FIELD			
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	294,275 SqFt
Section:	105	of 6	From:	-	To:	-	Last Const.: 1/1/2017
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	51,700 SqFt	Length:	1,034 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:	Grade:	0	Lanes:	0	
Section Comments:							
Work Date:	1/1/1968	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2017	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	10	Surveyed:	1		
Conditions:	PCI: 91						
Inspection Comments:							
Sample Number:	107	Type:	R	Area:	5000.00 SqFt	PCI:	91
Sample Comments:							
48	L & T CR	L	11.00 Ft				
57	WEATHERING	L	5000.00 SqFt				

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	294,275 SqFt		
Section:	110	of	6	From:	-	To:	-	Last Const.:	1/1/2018
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	6,623 SqFt	Length:	124 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1965	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1973	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1991	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2014	Work Type:	Crack Sealing - AC	Code:	CS-AC	Is Major M&R:	False		
Work Date:	1/1/2018	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True		
Last Insp. Date:	5/11/2022	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI: 79								
Inspection Comments:									
Sample Number:	141	Type:	R	Area:	6623.00 SqFt	PCI:	79		
Sample Comments:									
48	L & T CR	L	231.00 Ft						
56	SWELLING	L	238.00 SqFt						
57	WEATHERING	L	6623.00 SqFt						

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW A	Name:	TAXIWAY A		Use:	TAXIWAY	Area:	294,275 SqFt		
Section:	111	of 6	From:	-		To:	-		Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P	
Area:	132,526 SqFt		Length:	2,597 Ft		Width:	50 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1965		Work Type:			BUILT		Code:	IMPORTED	
								Is Major M&R:	True	
Work Date:	1/1/1973		Work Type:			OVERLAY		Code:	IMPORTED	
								Is Major M&R:	True	
Work Date:	1/1/1991		Work Type:			OVERLAY		Code:	IMPORTED	
								Is Major M&R:	True	
Work Date:	1/1/2014		Work Type:			Crack Sealing - AC		Code:	CS-AC	
								Is Major M&R:	False	
Work Date:	1/1/2017		Work Type:			New Construction - AC		Code:	NC-AC	
								Is Major M&R:	True	
Last Insp. Date:	5/11/2022		TotalSamples:	27		Surveyed:		3		
Conditions:	PCI: 93									
Inspection Comments:										
Sample Number:	113	Type:	R	Area:	4750.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	4750.00 SqFt						
Sample Number:	123	Type:	R	Area:	5000.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	5000.00 SqFt						
Sample Number:	137	Type:	R	Area:	5107.00 SqFt		PCI:	92		
Sample Comments:										
48	L & T CR		L	2.00 Ft						
57	WEATHERING		L	5107.00 SqFt						

Network:	FMY	Name:		PAGE FIELD				
Branch:	TW A	Name:	TAXIWAY A		Use:	TAXIWAY	Area:	294,275 SqFt
Section:	114	of	6	From:	-	To:	-	Last Const.: 1/1/2017
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:		Rank: P
Area:	73,900 SqFt	Length:	1,478 Ft	Width:	50 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1965	Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1973	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2014	Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Work Date:	1/1/2017	Work Type: Mill and Overlay				Code:	ML-OVL	Is Major M&R: True
Last Insp. Date:	5/11/2022	TotalSamples:	15	Surveyed: 2				
Conditions:	PCI: 79							
Inspection Comments:								
Sample Number:	146	Type:	R	Area:	5000.00 SqFt	PCI:	79	
Sample Comments:								
48	L & T CR	L	174.00 Ft					
56	SWELLING	L	130.00 SqFt					
57	WEATHERING	L	5000.00 SqFt					
Sample Number:	154	Type:	R	Area:	5000.00 SqFt	PCI:	80	
Sample Comments:								
48	L & T CR	L	172.00 Ft					
56	SWELLING	L	75.00 SqFt					
57	WEATHERING	L	5000.00 SqFt					

Network:	FMY	Name:		PAGE FIELD				
Branch:	TW A	Name:	TAXIWAY A		Use:	TAXIWAY	Area:	294,275 SqFt
Section:	115	of 6	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:	Rank:	P
Area:	17,123 SqFt	Length:	350 Ft	Width:	50 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1968	Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2014	Work Type: Crack Sealing - AC				Code:	CS-AC	Is Major M&R: False
Last Insp. Date:	5/11/2022	TotalSamples:	3	Surveyed: 1				
Conditions:	PCI: 64							
Inspection Comments:								
Sample Number:	157	Type:	R	Area:	5735.00 SqFt	PCI:	64	
Sample Comments:								
48	L & T CR	L	469.00	Ft				
52	RAVELING	L	860.00	SqFt				
57	WEATHERING	L	3728.00	SqFt				
57	WEATHERING	M	1147.00	SqFt				



Network:	FMY	Name:	PAGE FIELD						
Branch:	TW A1	Name:	TAXIWAY A1	Use:	TAXIWAY	Area:	20,509 SqFt		
Section:	123	of	1	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	20,509 SqFt	Length:	300 Ft	Width:	52 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1968	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2017	Work Type:	Complete Reconstruction - AC		Code:	CR-AC	Is Major M&R:	True	
Last Insp. Date: 5/11/2022									
TotalSamples: 5									
Surveyed: 1									
Conditions: PCI: 94									
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	3266.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	3266.00	SqFt					

Network:	FMY		Name:	PAGE FIELD					
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY	Area:	20,237 SqFt
Section:	125	of	1	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	20,237 SqFt	Length:	300 Ft	Width:	52 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1965	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1991	Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2017	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	5	Surveyed:	1				
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	3308.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	3308.00	SqFt					

Network:	FMY	Name:		PAGE FIELD			
Branch:	TW A3	Name:	TAXIWAY A3	Use:	TAXIWAY	Area:	149,071 SqFt
Section:	145	of 4	From:	-	To:	-	Last Const.: 1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:	Rank: P
Area:	41,023 SqFt	Length:	445 Ft	Width:	66 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1968	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R: True
Work Date:	1/1/1991	Work Type: Overlay - AC Structural			Code:	OL-AS	Is Major M&R: True
Work Date:	1/1/2017	Work Type: Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R: True
Last Insp. Date: 5/11/2022		TotalSamples:	7	Surveyed: 2			
Conditions:	PCI: 93						
Inspection Comments:							
Sample Number:	102	Type:	R	Area:	4684.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	4684.00 SqFt				
Sample Number:	103	Type:	R	Area:	5064.00 SqFt	PCI:	92
Sample Comments:							
48	L & T CR	L	2.00 Ft				
57	WEATHERING	L	5064.00 SqFt				

Network:		FMY		Name:		PAGE FIELD																	
Branch:		TW A3		Name:		TAXIWAY A3		Use:		TAXIWAY		Area:		149,071 SqFt									
Section:		150		of 4		From:		-		To:		-		Last Const.: 1/1/1991									
Surface:		AAC		Family:		CA653-RL-TW-AAC-APC		Zone:		Category:		Rank:		P									
Area:		67,098 SqFt		Length:		1,185 Ft		Width:		50 Ft													
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft											
Shoulder:		Street Type:		Grade:		0		Lanes:		0													
Section Comments:																							
Work Date:				1/1/1968				Work Type:				BUILT				Code:		IMPORTED		Is Major M&R:		True	
Work Date:				1/1/1991				Work Type:				OVERLAY				Code:		IMPORTED		Is Major M&R:		True	
Last Insp. Date:				5/11/2022				TotalSamples:				14				Surveyed:				3			
Conditions:				PCI: 54																			
Inspection Comments:																							
Sample Number:		113		Type:		R		Area:		3818.00 SqFt		PCI:		46									
Sample Comments:																							
48	L & T CR			L		119.00 Ft																	
48	L & T CR			M		78.00 Ft																	
50	PATCHING			L		1377.00 SqFt																	
52	RAVELING			L		122.00 SqFt																	
56	SWELLING			L		35.00 SqFt																	
57	WEATHERING			L		1835.00 SqFt																	
57	WEATHERING			M		484.00 SqFt																	
Sample Number:		117		Type:		R		Area:		5000.00 SqFt		PCI:		59									
Sample Comments:																							
48	L & T CR			L		267.00 Ft																	
48	L & T CR			M		153.00 Ft																	
52	RAVELING			L		500.00 SqFt																	
56	SWELLING			L		8.00 SqFt																	
57	WEATHERING			L		3750.00 SqFt																	
57	WEATHERING			M		750.00 SqFt																	
Sample Number:		121		Type:		R		Area:		5073.00 SqFt		PCI:		56									
Sample Comments:																							
48	L & T CR			L		244.00 Ft																	
48	L & T CR			M		200.00 Ft																	
52	RAVELING			L		507.00 SqFt																	
56	SWELLING			L		15.00 SqFt																	
57	WEATHERING			L		3044.00 SqFt																	
57	WEATHERING			M		1522.00 SqFt																	

Network:		FMY		Name:		PAGE FIELD																									
Branch:		TW A3		Name:		TAXIWAY A3		Use:		TAXIWAY		Area:		149,071 SqFt																	
Section:		153		of		4		From:		-		To:		-		Last Const.:		1/1/2018													
Surface:		AC		Family:		CA653-RL-TW-AC		Zone:				Category:				Rank:		P													
Area:		14,735 SqFt		Length:		175 Ft		Width:		100 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				1/1/1991				Work Type:				BUILT				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				1/1/2018				Work Type:				Complete Reconstruction - AC				Code:				CR-AC				Is Major M&R:				True			
Last Insp. Date:				5/11/2022				TotalSamples:				3				Surveyed:				1											
Conditions:				PCI:				94																							
Inspection Comments:																															
Sample Number:		128		Type:		R		Area:		6257.00 SqFt		PCI:		94																	
Sample Comments:																															
57		WEATHERING		L		6257.00		SqFt																							



Network:	FMY		Name:	PAGE FIELD							
Branch:	TW A3		Name:	TAXIWAY A3		Use:	TAXIWAY	Area:	149,071 SqFt		
Section:	155	of 4	From:	-			To:	-		Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	26,215 SqFt		Length:	460 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	1/1/1968		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/1991		Work Type: Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date: 5/11/2022											
		TotalSamples:		5		Surveyed:		1			
Conditions:	PCI:	94									
Inspection Comments:											
Sample Number:	109	Type:	R	Area:	5601.00 SqFt		PCI:	94			
Sample Comments:											
57	WEATHERING		L	5601.00 SqFt							

Network:	FMY	Name:		PAGE FIELD				
Branch:	TW A6	Name:	TAXIWAY A6		Use:	TAXIWAY	Area:	14,160 SqFt
Section:	175	of	3	From:	-	To:	-	Last Const.: 1/1/1991
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:		Rank: P
Area:	4,324 SqFt	Length:	70 Ft	Width:	50 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1968	Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	5/11/2022	TotalSamples:	1	Surveyed:	1			
Conditions:	PCI: 60							
Inspection Comments:								
Sample Number:	102	Type:	R	Area:	4323.00 SqFt	PCI:	60	
Sample Comments:								
45	DEPRESSION	L	79.00 SqFt					
48	L & T CR	L	279.00 Ft					
48	L & T CR	M	26.00 Ft					
52	RAVELING	L	25.00 SqFt					
57	WEATHERING	L	3009.00 SqFt					
57	WEATHERING	M	1289.00 SqFt					

Network:	FMY	Name:		PAGE FIELD								
Branch:	TW A6	Name:	TAXIWAY A6		Use:	TAXIWAY	Area:	14,160 SqFt				
Section:	178	of 3	From:	-		To:	-		Last Const.:	1/1/2017		
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC		Zone:	Category:		Rank:		P		
Area:	4,732 SqFt		Length:	93 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	1/1/1991		Work Type:				BUILT		Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2017		Work Type:				Mill and Overlay		Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI:	94										
Inspection Comments:												
Sample Number:	101	Type:	R	Area:	4729.00 SqFt		PCI:	94				
Sample Comments:												
57	WEATHERING		L	4729.00 SqFt								

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW A6	Name:	TAXIWAY A6	Use:	TAXIWAY	Area:	14,160 SqFt		
Section:	180	of	3	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	5,104 SqFt	Length:	85 Ft	Width:	51 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1958	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/1991	Work Type:	Overlay - AC Structural		Code:	OL-AS	Is Major M&R:	True	
Work Date:	1/1/2017	Work Type:	Complete Reconstruction - AC		Code:	CR-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	5104.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	5104.00	SqFt					

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW A7	Name:	TAXIWAY A7	Use:	TAXIWAY	Area:	28,228 SqFt		
Section:	120	of	1	From:	-	To:	-	Last Const.:	1/1/1991
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	28,228 SqFt	Length:	500 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1968	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1991	Work Type:	OVERLAY	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2014	Work Type:	Crack Sealing - AC	Code:	CS-AC	Is Major M&R:	False		
Last Insp. Date:	5/11/2022	TotalSamples:	6	Surveyed:	2				
Conditions:	PCI: 65								
Inspection Comments:									
Sample Number:	161	Type:	R	Area:	4843.00 SqFt	PCI:	68		
Sample Comments:									
48	L & T CR	L	291.00 Ft						
48	L & T CR	M	50.00 Ft						
57	WEATHERING	L	3390.00 SqFt						
57	WEATHERING	M	1453.00 SqFt						
Sample Number:	162	Type:	R	Area:	4882.00 SqFt	PCI:	63		
Sample Comments:									
48	L & T CR	L	305.00 Ft						
48	L & T CR	M	100.00 Ft						
52	RAVELING	L	200.00 SqFt						
57	WEATHERING	L	3277.00 SqFt						
57	WEATHERING	M	1405.00 SqFt						

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW AP SW	Name:	SOUTHWEST APRON TAXIWAY		Use:	TAXIWAY	Area:	27,928 SqFt		
Section:	107	of	2	From:	-	To:	-	Last Const.:	1/1/2017	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	14,624 SqFt	Length:	110 Ft		Width:	90 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1965	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/1998	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False	
Work Date:	1/1/2017	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	3		Surveyed:	1				
Conditions:	PCI:	94								
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	4656.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING	L	4656.00 SqFt							



Network: FMY		Name: PAGE FIELD	
Branch: TW AP SW	Name: SOUTHWEST APRON TAXIWAY	Use: TAXIWAY	Area: 27,928 SqFt
Section: 112 of 2	From: -	To: -	Last Const.: 1/1/2017
Surface: AC	Family: CA653-RL-TW-AC	Zone:	Category: Rank: P
Area: 13,304 SqFt	Length: 140 Ft	Width: 65 Ft	
Slabs:	Slab Length: Ft	Slab Width: Ft	Joint Length: Ft
Shoulder:	Street Type:	Grade: 0	Lanes: 0
Section Comments:			
Work Date: 1/1/1998	Work Type: New Construction - Initial	Code: NU-IN	Is Major M&R: True
Work Date: 1/1/2017	Work Type: Complete Reconstruction - AC	Code: CR-AC	Is Major M&R: True
Last Insp. Date: 5/11/2022	TotalSamples: 3	Surveyed: 1	
Conditions: PCI: 91			
Inspection Comments:			
Sample Number: 101	Type: R	Area: 4039.00 SqFt	PCI: 91
Sample Comments:			
48	L & T CR	L	8.00 Ft
57	WEATHERING	L	4039.00 SqFt

Network:	FMY			Name:	PAGE FIELD				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	202,414 SqFt
Section:	205	of	5	From:	-	To:	-	Last Const.:	1/1/1977
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	140,345 SqFt	Length:	3,485 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1977	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/2014	Work Type:	Crack Sealing - AC	Code:	CS-AC	Is Major M&R:	False		
Work Date:	1/1/2020	Work Type:	Crack Sealing - AC	Code:	CS-AC	Is Major M&R:	False		
Last Insp. Date:	5/11/2022	TotalSamples:	34	Surveyed:	4				
Conditions:	PCI:	65							
Inspection Comments:									
Sample Number:	105	Type:	R	Area:	4000.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	L	360.00 Ft						
52	RAVELING	L	100.00 SqFt						
57	WEATHERING	L	2600.00 SqFt						
57	WEATHERING	M	1300.00 SqFt						
Sample Number:	115	Type:	R	Area:	4000.00 SqFt	PCI:	68		
Sample Comments:									
48	L & T CR	L	356.00 Ft						
52	RAVELING	L	200.00 SqFt						
57	WEATHERING	L	1400.00 SqFt						
57	WEATHERING	M	2400.00 SqFt						
Sample Number:	140	Type:	R	Area:	4000.00 SqFt	PCI:	66		
Sample Comments:									
48	L & T CR	L	235.00 Ft						
52	RAVELING	L	2000.00 SqFt						
57	WEATHERING	L	1000.00 SqFt						
57	WEATHERING	M	1000.00 SqFt						
Sample Number:	147	Type:	R	Area:	6080.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	L	588.00 Ft						
52	RAVELING	L	3040.00 SqFt						
57	WEATHERING	L	1520.00 SqFt						
57	WEATHERING	M	1520.00 SqFt						

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW B	Name:	TAXIWAY B	Use:	TAXIWAY	Area:	202,414 SqFt		
Section:	206	of	5	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	21,637 SqFt	Length:	392 Ft	Width:	53 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1977	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2014	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	1/1/2017	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date: 5/11/2022									
		TotalSamples:	4	Surveyed:		1			
Conditions:	PCI:	90							
Inspection Comments:									
Sample Number:	129	Type:	R	Area:	6293.00 SqFt	PCI:	90		
Sample Comments:									
48	L & T CR	L	27.00	Ft					
57	WEATHERING	L	6293.00	SqFt					

Network:	FMY	Name:		PAGE FIELD					
Branch:	TW B	Name:	TAXIWAY B	Use:	TAXIWAY	Area:	202,414 SqFt		
Section:	208	of	5	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	10,199 SqFt	Length:	180 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:		Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1977	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2014	Work Type:			Crack Sealing - AC	Code:	CS-AC	Is Major M&R:	False
Work Date:	1/1/2017	Work Type:			Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI: 94								
Inspection Comments:									
Sample Number:	127	Type:	R	Area:	5029.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	5029.00	SqFt					

Network:	FMY			Name:	PAGE FIELD					
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	202,414 SqFt	
Section:	210	of	5	From:	-		To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	27,327 SqFt	Length:	300 Ft		Width:	65 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1977		Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1991		Work Type:	Overlay - AC Structural			Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2017		Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date: 5/11/2022										
TotalSamples: 5										
Surveyed: 1										
Conditions:	PCI:	89								
Inspection Comments:										
Sample Number:	123	Type:	R	Area:	5284.00 SqFt		PCI:	89		
Sample Comments:										
48	L & T CR		L	51.00 Ft						
57	WEATHERING		L	5284.00 SqFt						

Network:		FMY		Name:		PAGE FIELD																									
Branch:		TW B		Name:		TAXIWAY B		Use:		TAXIWAY		Area:		202,414 SqFt																	
Section:		270		of		5		From:		-		To:		-		Last Const.:		1/1/1998													
Surface:		AC		Family:		CA653-RL-TW-AC		Zone:				Category:				Rank:		P													
Area:		2,906 SqFt		Length:		50 Ft		Width:		40 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				1/1/1998				Work Type:				BUILT				Code:				IMPORTED				Is Major M&R:				True			
Last Insp. Date:				5/11/2022				TotalSamples:				1				Surveyed:				1											
Conditions:				PCI:				55																							
Inspection Comments:																															
Sample Number:				200				Type:		R		Area:				2906.00 SqFt				PCI:				55							
Sample Comments:																															
45		DEPRESSION				L		15.00				SqFt																			
48		L & T CR				L		100.00				Ft																			
52		RAVELING				L		2180.00				SqFt																			
52		RAVELING				M		726.00				SqFt																			



Network:	FMY			Name:	PAGE FIELD									
Branch:	TW B1		Name:	TAXIWAY B1		Use:	TAXIWAY	Area:	19,766 SqFt					
Section:	207		of	1		From:	-		To:	-		Last Const.:	1/1/1997	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:			Rank:	P	
Area:	19,766 SqFt		Length:	500 Ft		Width:	40 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1997		Work Type:	New Construction - AC				Code:	NC-AC		Is Major M&R:	True		
Work Date:	1/1/2014		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False		
Work Date:	1/1/2020		Work Type:	Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False		
Last Insp. Date: 5/11/2022														
			TotalSamples:	4		Surveyed:		1						
Conditions:	PCI: 72													
Inspection Comments:														
Sample Number:	148		Type:	R		Area:	5944.00 SqFt		PCI:	72				
Sample Comments:														
48	L & T CR		L	255.00		Ft								
52	RAVELING		L	594.00		SqFt								
57	WEATHERING		L	2972.00		SqFt								
57	WEATHERING		M	2378.00		SqFt								

Network:	FMY		Name:	PAGE FIELD					
Branch:	TW B2		Name:	TAXIWAY B2		Use:	TAXIWAY	Area:	11,346 SqFt
Section:	220	of	1	From:	-	To:	-	Last Const.:	1/1/2018
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	11,346 SqFt	Length:	230 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1977	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2018	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date: 5/11/2022									
TotalSamples: 2									
Surveyed: 1									
Conditions: PCI: 94									
Inspection Comments:									
Sample Number:	200	Type:	R	Area:	5073.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	5073.00	SqFt					

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW B3	Name:	TAXIWAY B3		Use:	TAXIWAY	Area:	79,018 SqFt		
Section:	260	of	3	From:	-	To:	-	Last Const.:	1/1/2018	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	11,346 SqFt	Length:	230 Ft		Width:	40 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1977	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2018	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True	
Last Insp. Date: 5/11/2022										
		TotalSamples:	2		Surveyed:		1			
Conditions: PCI: 94										
Inspection Comments:										
Sample Number:	200	Type:	R	Area:	5073.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	5073.00 SqFt						

Network:		FMY		Name:		PAGE FIELD									
Branch:	TW B3		Name:	TAXIWAY B3		Use:	TAXIWAY	Area:	79,018 SqFt						
Section:	265		of	3	From:	-		To:	-		Last Const.:	1/1/1998			
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P					
Area:	8,453 SqFt		Length:	175 Ft		Width:	40 Ft								
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft				
Shoulder:	Street Type:				Grade:		0		Lanes:		0				
Section Comments:		This section was relocated on 7/21/05.													
Work Date:		1/1/1998		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True	
Work Date:		1/1/2016		Work Type:				Surface Treatment - Seal Coat		Code:	ST-SC		Is Major M&R:	False	
Last Insp. Date:		5/11/2022		TotalSamples:		2		Surveyed:		1					
Conditions:		PCI: 67													
Inspection Comments:															
Sample Number:		100		Type:	R		Area:	4853.00 SqFt		PCI: 67					
Sample Comments:															
48	L & T CR		L		50.00 Ft										
52	RAVELING		L		243.00 SqFt										
54	SHOVING		L		10.00 SqFt										
57	WEATHERING		M		4610.00 SqFt										

Network:	FMY			Name:	PAGE FIELD							
Branch:	TW B3		Name:	TAXIWAY B3		Use:	TAXIWAY	Area:	79,018 SqFt			
Section:	275	of	3	From:	-			To:	-		Last Const.:	1/1/1998
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:				Category:	Rank: P	
Area:	59,219 SqFt		Length:	1,400 Ft		Width:	40 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft			Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0			Lanes:	0	
Section Comments:												
Work Date:	1/1/1998			Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2016			Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Last Insp. Date: 5/11/2022												
TotalSamples: 14												
Surveyed: 2												
Conditions: PCI: 69												
Inspection Comments:												
Sample Number:	203		Type:	R		Area:	4000.00 SqFt			PCI:	70	
Sample Comments:												
48	L & T CR		L	216.00 Ft								
52	RAVELING		L	200.00 SqFt								
57	WEATHERING		M	3800.00 SqFt								
Sample Number:	212		Type:	R		Area:	3985.00 SqFt			PCI:	68	
Sample Comments:												
48	L & T CR		L	42.00 Ft								
52	RAVELING		L	199.00 SqFt								
54	SHOVING		L	5.00 SqFt								
57	WEATHERING		M	3786.00 SqFt								

Network:	FMY			Name:	PAGE FIELD						
Branch:	TW B4		Name:	TAXIWAY B4		Use:	TAXIWAY	Area:	24,035 SqFt		
Section:	203	of	1	From:	-		To:	-	Last Const.:	1/1/1977	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	24,035 SqFt	Length:	230 Ft		Width:	100 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1977		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2014		Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Work Date:	1/1/2020		Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Last Insp. Date: 5/11/2022											
Conditions:		PCI:	67		TotalSamples:	5		Surveyed:	1		
Inspection Comments:											
Sample Number:	100		Type:	R		Area:	5537.00 SqFt		PCI:	67	
Sample Comments:											
48	L & T CR		L	547.00 Ft							
57	WEATHERING		L	3876.00 SqFt							
57	WEATHERING		M	1661.00 SqFt							



Network:	FMY	Name:	PAGE FIELD							
Branch:	TW C	Name:	TAXIWAY C		Use:	TAXIWAY	Area:	331,168 SqFt		
Section:	240	of	4	From:	-	To:	-	Last Const.:	1/1/2017	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	22,168 SqFt	Length:	225 Ft	Width:	65 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:		Street Type:		Grade:	0	Lanes:	0			
Section Comments:										
Work Date:	1/1/1977	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2017	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date: 5/11/2022										
TotalSamples: 4										
Surveyed: 1										
Conditions: PCI: 91										
Inspection Comments:										
Sample Number:	239	Type:	R	Area:	5263.00 SqFt	PCI:	91			
Sample Comments:										
48	L & T CR	L	10.00 Ft							
57	WEATHERING	L	5263.00 SqFt							

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW C	Name:	TAXIWAY C	Use:	TAXIWAY	Area:	331,168 SqFt		
Section:	245	of	4	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	121,801 SqFt	Length:	2,130 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1977	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2017	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Last Insp. Date: 5/11/2022									
Conditions:		PCI:	93	TotalSamples:	23	Surveyed:	3		
Inspection Comments:									
Sample Number:	244	Type:	R	Area:	4461.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	4461.00	SqFt					
Sample Number:	254	Type:	R	Area:	5000.00 SqFt	PCI:	92		
Sample Comments:									
48	L & T CR	L	5.00	Ft					
57	WEATHERING	L	5000.00	SqFt					
Sample Number:	265	Type:	R	Area:	6281.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	6281.00	SqFt					

Network:	FMY		Name:		PAGE FIELD								
Branch:	TW C		Name:		TAXIWAY C	Use:	TAXIWAY	Area:	331,168 SqFt				
Section:	305	of 4		From:	-		To:	-		Last Const.:	1/1/2007		
Surface:	AC	Family:		CA653-RL-TW-AC		Zone:		Category:		Rank: P			
Area:	162,237 SqFt		Length:		3,125 Ft		Width:		50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:		0				
Section Comments:													
Work Date:	1/1/2007		Work Type:				New Construction - AC		Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:		32		Surveyed:		4				
Conditions:	PCI:	77											
Inspection Comments:													
Sample Number:	205	Type:	R		Area:		5001.00 SqFt		PCI:			76	
Sample Comments:													
48	L & T CR		L		47.00 Ft								
48	L & T CR		M		30.00 Ft								
57	WEATHERING		L		4501.00 SqFt								
57	WEATHERING		M		500.00 SqFt								
Sample Number:	213	Type:	R		Area:		5000.00 SqFt		PCI:			77	
Sample Comments:													
48	L & T CR		L		110.00 Ft								
48	L & T CR		M		25.00 Ft								
57	WEATHERING		L		4500.00 SqFt								
57	WEATHERING		M		500.00 SqFt								
Sample Number:	218	Type:	R		Area:		5000.00 SqFt		PCI:			79	
Sample Comments:													
48	L & T CR		L		209.00 Ft								
57	WEATHERING		L		4750.00 SqFt								
57	WEATHERING		M		250.00 SqFt								
Sample Number:	226	Type:	R		Area:		5000.00 SqFt		PCI:			75	
Sample Comments:													
48	L & T CR		L		115.00 Ft								
48	L & T CR		M		12.00 Ft								
56	SWELLING		L		15.00 SqFt								
57	WEATHERING		L		4500.00 SqFt								
57	WEATHERING		M		500.00 SqFt								

Network:	FMY	Name:		PAGE FIELD				
Branch:	TW C	Name:	TAXIWAY C		Use:	TAXIWAY	Area:	331,168 SqFt
Section:	306	of	4	From:	-	To:	-	Last Const.: 1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank: P
Area:	24,962 SqFt	Length:	350 Ft	Width:	56 Ft			
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:	Street Type:	Grade:	0	Lanes:	0			
Section Comments:								
Work Date:	1/1/2007	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2017	Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	6	Surveyed:	1			
Conditions:	PCI: 94							
Inspection Comments:								
Sample Number:	235	Type:	R	Area:	5796.00 SqFt	PCI:	94	
Sample Comments:								
57	WEATHERING	L	5796.00	SqFt				

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW C1	Name:	TAXIWAY C1	Use:	TAXIWAY	Area:	29,730 SqFt		
Section:	310	of	1	From:	-	To:	-	Last Const.:	1/1/2007
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	29,730 SqFt	Length:	235 Ft	Width:	70 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2007	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	6	Surveyed:	1				
Conditions:	PCI:	69							
Inspection Comments:									
Sample Number:	103	Type:	R	Area:	4407.00 SqFt	PCI:	69		
Sample Comments:									
48	L & T CR	L	101.00	Ft					
52	RAVELING	L	44.00	SqFt					
56	SWELLING	L	42.00	SqFt					
57	WEATHERING	M	4363.00	SqFt					

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW C2	Name:	TAXIWAY C2	Use:	TAXIWAY	Area:	84,768 SqFt		
Section:	320	of	2	From:	-	To:	-	Last Const.:	1/1/2007
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	42,197 SqFt	Length:	405 Ft	Width:	85 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2007	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	8	Surveyed:	1				
Conditions:	PCI:	75							
Inspection Comments:									
Sample Number:	103	Type:	R	Area:	5109.00 SqFt	PCI:	75		
Sample Comments:									
48	L & T CR	L	188.00 Ft						
57	WEATHERING	M	5109.00 SqFt						



Network:	FMY	Name:	PAGE FIELD						
Branch:	TW C2	Name:	TAXIWAY C2	Use:	TAXIWAY	Area:	84,768 SqFt		
Section:	520	of	2	From:	-	To:	-	Last Const.:	1/1/2009
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	42,571 SqFt	Length:	500 Ft	Width:	55 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2009	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	7	Surveyed:	1				
Conditions:	PCI:	76							
Inspection Comments:									
Sample Number:	103	Type:	R	Area:	5434.00 SqFt	PCI:	76		
Sample Comments:									
48	L & T CR	L	77.00 Ft						
48	L & T CR	M	25.00 Ft						
57	WEATHERING	L	4347.00 SqFt						
57	WEATHERING	M	1087.00 SqFt						

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW C3	Name:	TAXIWAY C3	Use:	TAXIWAY	Area:	23,701 SqFt		
Section:	525	of	1	From:	-	To:	-	Last Const.:	1/1/2009
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	23,701 SqFt	Length:	176 Ft	Width:	116 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2009	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	6	Surveyed:	1				
Conditions:	PCI:	88							
Inspection Comments:									
Sample Number:	203	Type:	R	Area:	3745.00 SqFt	PCI:	88		
Sample Comments:									
48	L & T CR	L	76.00 Ft						
57	WEATHERING	L	3745.00 SqFt						

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW C5	Name:	TAXIWAY C5		Use:	TAXIWAY	Area:	26,412 SqFt		
Section:	330	of	1	From:	-	To:	-	Last Const.:	1/1/2017	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	26,412 SqFt	Length:	300 Ft		Width:	60 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2017	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	7		Surveyed:	1				
Conditions:	PCI:	94								
Inspection Comments:										
Sample Number:	104	Type:	R	Area:	4058.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	4058.00 SqFt						

Network:	FMY	Name:		PAGE FIELD			
Branch:	TW C6	Name:	TAXIWAY C6	Use:	TAXIWAY	Area:	16,251 SqFt
Section:	335	of 2	From:	-	To:	-	Last Const.: 1/1/2017
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:	Category:	Rank:	P
Area:	7,909 SqFt	Length:	136 Ft	Width:	53 Ft		
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:	Street Type:	Grade:	0	Lanes:	0		
Section Comments:							
Work Date:	1/1/1974	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2017	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	2	Surveyed:	1		
Conditions:	PCI: 90						
Inspection Comments:							
Sample Number:	100	Type:	R	Area:	4254.00 SqFt	PCI:	90
Sample Comments:							
48	L & T CR	L	13.00 Ft				
57	WEATHERING	L	4254.00 SqFt				

Network:	FMY		Name:	PAGE FIELD							
Branch:	TW C6		Name:	TAXIWAY C6		Use:	TAXIWAY	Area:	16,251 SqFt		
Section:	345	of 2	From:	-			To:	-		Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	8,342 SqFt		Length:	135 Ft		Width:	53 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1974		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2017		Work Type:	Complete Reconstruction - AC			Code:	CR-AC		Is Major M&R:	True
Last Insp. Date: 5/11/2022											
TotalSamples: 2											
Surveyed: 1											
Conditions:	PCI: 89										
Inspection Comments:											
Sample Number:	102	Type:	R	Area:	3727.00 SqFt		PCI:	89			
Sample Comments:											
48	L & T CR		L	14.00 Ft							
57	WEATHERING		L	3718.00 SqFt							
57	WEATHERING		M	9.00 SqFt							

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW C7	Name:	TAXIWAY C7		Use:	TAXIWAY	Area:	15,220 SqFt		
Section:	350	of	1	From:	-	To:	-	Last Const.:	1/1/2017	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	15,220 SqFt	Length:	137 Ft		Width:	82 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2017	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	90								
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	3034.00 SqFt		PCI:	90		
Sample Comments:										
48	L & T CR	L	23.00 Ft							
57	WEATHERING	L	3034.00 SqFt							



Network:	FMY	Name:	PAGE FIELD						
Branch:	TW C8	Name:	TAXIWAY C8	Use:	TAXIWAY	Area:	15,632 SqFt		
Section:	355	of	1	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	15,632 SqFt	Length:	122 Ft	Width:	88 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2017	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	4	Surveyed:	1				
Conditions:	PCI:	89							
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	3774.00 SqFt	PCI:	89		
Sample Comments:									
48	L & T CR	L	40.00 Ft						
57	WEATHERING	L	3774.00 SqFt						

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW C9	Name:	TAXIWAY C9	Use:	TAXIWAY	Area:	9,368 SqFt		
Section:	360	of	1	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	9,368 SqFt	Length:	90 Ft	Width:	65 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2017	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	300	Type:	R	Area:	3483.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	3483.00	SqFt					

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW D	Name:	TAXIWAY D	Use:	TAXIWAY	Area:	152,202 SqFt		
Section:	134	of	6	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	28,977 SqFt	Length:	350 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1970	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Work Date:	1/1/1998	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True		
Work Date:	1/1/2017	Work Type:	Complete Reconstruction - AC	Code:	CR-AC	Is Major M&R:	True		
Last Insp. Date:	5/11/2022	TotalSamples:	6	Surveyed:	1				
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	130	Type:	R	Area:	5340.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	5340.00 SqFt						

Network:	FMY	Name:		PAGE FIELD					
Branch:	TW D	Name:		TAXIWAY D	Use:	TAXIWAY	Area:	152,202 SqFt	
Section:	135	of 6	From:	-	To:	-	Last Const.:	1/1/1998	
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:	Category:	Rank:	P		
Area:	23,050 SqFt	Length:	461 Ft	Width:	50 Ft				
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:	Street Type:	Grade:	0	Lanes:	0				
Section Comments:									
Work Date:	1/1/1970	Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1998	Work Type:			Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	5	Surveyed:	2				
Conditions:	PCI:	65							
Inspection Comments:									
Sample Number:	124	Type:	R	Area:	5000.00 SqFt	PCI:	64		
Sample Comments:									
48	L & T CR	L	275.00 Ft						
48	L & T CR	M	50.00 Ft						
56	SWELLING	L	163.00 SqFt						
57	WEATHERING	L	2500.00 SqFt						
57	WEATHERING	M	2500.00 SqFt						
Sample Number:	126	Type:	R	Area:	5000.00 SqFt	PCI:	66		
Sample Comments:									
48	L & T CR	L	301.00 Ft						
48	L & T CR	M	20.00 Ft						
56	SWELLING	L	46.00 SqFt						
57	WEATHERING	L	2500.00 SqFt						
57	WEATHERING	M	2500.00 SqFt						

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW D	Name:	TAXIWAY D	Use:	TAXIWAY	Area:	152,202 SqFt		
Section:	136	of	6	From:	-	To:	-	Last Const.:	1/1/1998
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	9,753 SqFt	Length:	189 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1998	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True		
Last Insp. Date:	5/11/2022	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	60							
Inspection Comments:									
Sample Number:	122	Type:	R	Area:	4750.00 SqFt	PCI:	60		
Sample Comments:									
48	L & T CR	L	278.00 Ft						
48	L & T CR	M	100.00 Ft						
52	RAVELING	M	30.00 SqFt						
56	SWELLING	L	75.00 SqFt						
57	WEATHERING	M	4720.00 SqFt						

Network:	FMY	Name:		PAGE FIELD				
Branch:	TW D	Name:	TAXIWAY D		Use:	TAXIWAY	Area:	152,202 SqFt
Section:	137	of	6	From:	-	To:	-	Last Const.: 1/1/1998
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:		Rank: P
Area:	56,400 SqFt	Length:	1,200 Ft	Width:	47 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1968	Work Type: BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1998	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	5/11/2022	TotalSamples:	12	Surveyed:	2			
Conditions:	PCI: 64							
Inspection Comments:								
Sample Number:	111	Type:	R	Area:	4700.00 SqFt	PCI:	64	
Sample Comments:								
48	L & T CR	L	323.00 Ft					
48	L & T CR	M	100.00 Ft					
56	SWELLING	L	150.00 SqFt					
57	WEATHERING	M	4700.00 SqFt					
Sample Number:	116	Type:	R	Area:	4700.00 SqFt	PCI:	64	
Sample Comments:								
48	L & T CR	L	324.00 Ft					
48	L & T CR	M	100.00 Ft					
56	SWELLING	L	200.00 SqFt					
57	WEATHERING	M	4700.00 SqFt					



Network:	FMY	Name:		PAGE FIELD							
Branch:	TW D	Name:	TAXIWAY D		Use:	TAXIWAY	Area:	152,202 SqFt			
Section:	140	of 6	From:	-		To:	-		Last Const.:	1/1/1998	
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC		Zone:	Category:		Rank: P			
Area:	24,471 SqFt		Length:	473 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1968		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1998		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date: 5/11/2022											
Conditions:	PCI: 73										
Inspection Comments:											
Sample Number:	103	Type:	R	Area:	5656.00 SqFt		PCI:	70			
Sample Comments:											
48	L & T CR		L	133.00 Ft							
48	L & T CR		M	2.00 Ft							
56	SWELLING		L	32.00 SqFt							
57	WEATHERING		L	3394.00 SqFt							
57	WEATHERING		M	2262.00 SqFt							
Sample Number:	106	Type:	R	Area:	4700.00 SqFt		PCI:	75			
Sample Comments:											
48	L & T CR		L	114.00 Ft							
56	SWELLING		L	4.00 SqFt							
57	WEATHERING		L	2820.00 SqFt							
57	WEATHERING		M	1880.00 SqFt							

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW D	Name:	TAXIWAY D		Use:	TAXIWAY	Area:	152,202 SqFt		
Section:	143	of	6	From:	-	To:	-	Last Const.:	1/1/1998	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	9,551 SqFt	Length:	203 Ft		Width:	47 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1998	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	78								
Inspection Comments:										
Sample Number:	109	Type:	R	Area:	4706.00 SqFt		PCI:	78		
Sample Comments:										
45	DEPRESSION	L	40.00 SqFt							
48	L & T CR	L	84.00 Ft							
57	WEATHERING	L	4235.00 SqFt							
57	WEATHERING	M	471.00 SqFt							

Network:	FMY	Name:		PAGE FIELD				
Branch:	TW D2	Name:	TAXIWAY D2		Use:	TAXIWAY	Area:	13,679 SqFt
Section:	160	of	1	From:	-	To:	-	Last Const.: 1/1/1977
Surface:	AAC	Family:	CA653-RL-TW-AAC-APC	Zone:		Category:		Rank: P
Area:	13,679 SqFt	Length:	308 Ft	Width:	40 Ft			
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0	Lanes:	0	
Section Comments:								
Work Date:	1/1/1977	Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1977	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Last Insp. Date:	5/11/2022	TotalSamples:	3	Surveyed: 1				
Conditions:	PCI: 29							
Inspection Comments:								
Sample Number:	101	Type:	R	Area:	4000.00 SqFt	PCI:	29	
Sample Comments:								
41	ALLIGATOR CR	L	248.00	SqFt				
43	BLOCK CR	L	3752.00	SqFt				
52	RAVELING	L	2500.00	SqFt				
52	RAVELING	M	1500.00	SqFt				

Network:	FMY		Name:	PAGE FIELD					
Branch:	TW D3		Name:	TAXIWAY D3		Use:	TAXIWAY	Area:	9,322 SqFt
Section:	141	of	1	From:	-	To:	-	Last Const.:	1/1/2018
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	9,322 SqFt	Length:	160 Ft	Width:	53 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1968	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2018	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date: 5/11/2022									
TotalSamples: 3									
Surveyed: 1									
Conditions: PCI: 94									
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	2811.00 SqFt	PCI:	94		
Sample Comments:									
57	WEATHERING	L	2811.00	SqFt					

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW E	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	212,522 SqFt		
Section:	147	of	6	From:	-	To:	-	Last Const.:	1/1/2017	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	22,245 SqFt	Length:	315 Ft	Width:	60 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:		Street Type:		Grade:	0	Lanes:	0			
Section Comments:										
Work Date:	1/1/2017	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	5	Surveyed:	1					
Conditions:	PCI:	94								
Inspection Comments:										
Sample Number:	102	Type:	R	Area:	3446.00 SqFt	PCI:	94			
Sample Comments:										
57	WEATHERING	L	3446.00	SqFt						

Network:	FMY	Name:		PAGE FIELD			
Branch:	TW E	Name:	TAXIWAY E	Use:	TAXIWAY	Area:	212,522 SqFt
Section:	165	of 6	From:	-	To:	-	Last Const.: 1/1/2017
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:	Rank: P
Area:	42,108 SqFt	Length:	540 Ft	Width:	55 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1977	Work Type: BUILT			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1991	Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2017	Work Type: Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R: True
Last Insp. Date:	5/11/2022	TotalSamples:	9	Surveyed: 1			
Conditions:	PCI: 94						
Inspection Comments:							
Sample Number:	103	Type:	R	Area:	5628.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5628.00	SqFt			



Network:	FMY	Name:	PAGE FIELD							
Branch:	TW E	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	212,522 SqFt		
Section:	503	of	6	From:	-	To:	-	Last Const.:	1/1/2018	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	39,478 SqFt	Length:	875 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2018	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	9		Surveyed:	1				
Conditions:	PCI:	94								
Inspection Comments:										
Sample Number:	102	Type:	R	Area:	4317.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	4317.00 SqFt						

Network:	FMY		Name:	PAGE FIELD						
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	212,522 SqFt	
Section:	510	of 6	From:	-			To:	-	Last Const.:	1/1/2007
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	48,748 SqFt	Length:	1,184 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2007		Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	5/11/2022		TotalSamples:	12		Surveyed:	2			
Conditions:	PCI:	75								
Inspection Comments:										
Sample Number:	403	Type:	R	Area:	3500.00 SqFt		PCI:	75		
Sample Comments:										
48	L & T CR	L	100.00 Ft							
57	WEATHERING	L	1400.00 SqFt							
57	WEATHERING	M	2100.00 SqFt							
Sample Number:	408	Type:	R	Area:	3500.00 SqFt		PCI:	75		
Sample Comments:										
48	L & T CR	L	91.00 Ft							
57	WEATHERING	L	1400.00 SqFt							
57	WEATHERING	M	2100.00 SqFt							

Network:	FMY	Name:	PAGE FIELD								
Branch:	TW E	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	212,522 SqFt			
Section:	512	of	6	From:	-	To:	-	Last Const.:	1/1/2007		
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	31,577 SqFt	Length:	300 Ft		Width:	65 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2007	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True		
Last Insp. Date:	5/11/2022	TotalSamples:	7		Surveyed:	1					
Conditions:	PCI:	73									
Inspection Comments:											
Sample Number:	102	Type:	R	Area:	4619.00 SqFt		PCI:	73			
Sample Comments:											
48	L & T CR	L	58.00 Ft								
56	SWELLING	L	25.00 SqFt								
57	WEATHERING	M	4619.00 SqFt								

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW E	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	212,522 SqFt		
Section:	535	of	6	From:	-	To:	-	Last Const.:	1/1/2017	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	28,366 SqFt	Length:	300 Ft		Width:	60 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2017	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	6		Surveyed:	1				
Conditions:	PCI:	94								
Inspection Comments:										
Sample Number:	102	Type:	R	Area:	3621.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	3621.00 SqFt						

Network:	FMY	Name:	PAGE FIELD							
Branch:	TW E1	Name:	TAXIWAY E1		Use:	TAXIWAY	Area:	10,310 SqFt		
Section:	500	of	1	From:	-	To:	-	Last Const.:	1/1/2018	
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P
Area:	10,310 SqFt	Length:	175 Ft		Width:	50 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2018	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	91								
Inspection Comments:										
Sample Number:	110	Type:	R	Area:	5047.00 SqFt		PCI:	91		
Sample Comments:										
48	L & T CR	L	8.00 Ft							
57	WEATHERING	L	5047.00 SqFt							

Network:		FMY		Name:		PAGE FIELD													
Branch:		TW E2		Name:		TAXIWAY E2		Use:		TAXIWAY		Area:		20,194 SqFt					
Section:		505		of		2		From:		-		To:		-		Last Const.:		1/1/2007	
Surface:		AC		Family:		CA653-RL-TW-AC		Zone:				Category:				Rank:		P	
Area:		10,138 SqFt		Length:		256 Ft		Width:		35 Ft									
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft					
Shoulder:				Street Type:				Grade:		0		Lanes:		0					
Section Comments:																			
Work Date:		1/1/2007		Work Type:		New Construction - AC		Code:		NC-AC		Is Major M&R:		True					
Last Insp. Date:		5/11/2022		TotalSamples:		3		Surveyed:		1									
Conditions:		PCI:		69															
Inspection Comments:																			
Sample Number:		501		Type:		R		Area:		3500.00 SqFt		PCI:		69					
Sample Comments:																			
48		L & T CR		L		313.00 Ft													
52		RAVELING		L		70.00 SqFt													
57		WEATHERING		M		3430.00 SqFt													

Network:	FMY	Name:	PAGE FIELD						
Branch:	TW E2	Name:	TAXIWAY E2	Use:	TAXIWAY	Area:	20,194 SqFt		
Section:	530	of	2	From:	-	To:	-	Last Const.:	1/1/2009
Surface:	AC	Family:	CA653-RL-TW-AC	Zone:		Category:		Rank:	P
Area:	10,056 SqFt	Length:	250 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2009	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	5/11/2022	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI:	88							
Inspection Comments:									
Sample Number:	504	Type:	R	Area:	3500.00 SqFt	PCI:	88		
Sample Comments:									
48	L & T CR	L	10.00	Ft					
57	WEATHERING	L	3430.00	SqFt					
57	WEATHERING	M	70.00	SqFt					





FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE



AVIATION