



2022

Statewide Airfield Pavement Management Program



Airport Pavement Evaluation Report

LEE - Leesburg International Airport | District 5



AVIATION

Florida Department of Transportation

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report

Prepared by:

*FDOT Aviation Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*

Website: [FDOT Aviation Office](#)

Interactive Web Application: [FDOT SAPMP Interactive Web Application](#)

TABLE OF CONTENTS

EXECUTIVE SUMMARY	1
<i>Program Background.....</i>	<i>1</i>
<i>Current Pavement Conditions.....</i>	<i>2</i>
<i>Forecasted Pavement Conditions</i>	<i>3</i>
<i>Major Rehabilitation Planning 2023-2032.....</i>	<i>5</i>
CHAPTER 1 – INTRODUCTION	8
1.1 <i>Background</i>	<i>8</i>
1.2 <i>Stakeholders.....</i>	<i>10</i>
1.3 <i>General Scope of Work.....</i>	<i>10</i>
1.4 <i>FDOT SAPMP Objectives.....</i>	<i>11</i>
CHAPTER 2 – METHODOLOGY	14
2.1 <i>Airfield Pavement Database</i>	<i>14</i>
2.2 <i>Airfield Pavement Record Keeping (Historical Records Research).....</i>	<i>15</i>
2.3 <i>Airfield Pavement Structure</i>	<i>15</i>
2.3.1 <i>Asphalt Concrete</i>	<i>16</i>
2.3.2 <i>Portland Cement Concrete</i>	<i>16</i>
2.3.3 <i>Composite Structure – Whitetopping Pavement.....</i>	<i>16</i>
2.4 <i>Airfield Pavement Traffic</i>	<i>17</i>
2.5 <i>Pavement Management Program Network Definition Terminology</i>	<i>17</i>
2.5.1 <i>Pavement Network Identification</i>	<i>17</i>
2.5.2 <i>Pavement Branch Identification</i>	<i>17</i>
2.5.3 <i>Pavement Section Identification.....</i>	<i>18</i>
2.5.4 <i>Pavement Sample Unit Identification.....</i>	<i>18</i>
2.5.5 <i>Terminology Summary.....</i>	<i>18</i>
2.6 <i>Airfield PCI Survey Methodology.....</i>	<i>18</i>
2.6.1 <i>Pavement Distress Types</i>	<i>19</i>
2.6.2 <i>PCI Survey Procedures</i>	<i>20</i>
CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY	23
3.1 <i>Airfield Pavement Network Information</i>	<i>23</i>
3.1.1 <i>Previous and/or Anticipated Airfield Pavement Construction.....</i>	<i>23</i>
3.1.2 <i>Estimated Pavement Age</i>	<i>26</i>
3.1.3 <i>Functional Use.....</i>	<i>28</i>
3.1.4 <i>Pavement Surface Type</i>	<i>28</i>
3.1.5 <i>Pavement System Inventory Details</i>	<i>29</i>
CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS.....	32
4.1 <i>Airfield Pavement Condition Index.....</i>	<i>32</i>
4.1.1 <i>Network-Level Analysis.....</i>	<i>32</i>
4.1.2 <i>Branch-Level Analysis</i>	<i>32</i>
4.1.3 <i>Section-Level Analysis.....</i>	<i>35</i>
4.2 <i>Summary of Pavement Condition Evaluation Results.....</i>	<i>39</i>

4.2.1 Network-Level Observations.....	39
4.2.2 Branch-Level Observations.....	39
CHAPTER 5 – SAPMP CUSTOMIZATION.....	53
5.1 Network-Level Customization.....	53
5.2 Pavement Condition Forecasts.....	53
5.2.1 Forecasting PCI Considerations.....	54
5.2.2 Performance Models.....	54
5.2.3 Branch-Level Pavement Condition Forecast.....	54
5.2.4 Section-Level Pavement Condition Forecast.....	55
5.3 Critical PCI Value.....	56
5.4 Localized Maintenance and Repair.....	59
5.4.1 Localized Maintenance and Repair Approach.....	59
5.4.2 Localized Work Types.....	60
5.4.3 Localized Maintenance Planning-Level Unit Costs.....	62
5.4.4 Localized Maintenance and Repair Policy.....	62
5.5 Major Rehabilitation.....	65
5.5.1 Major Rehabilitation Pavement Section Development.....	65
5.5.2 Major Rehabilitation Planning-Level Unit Costs.....	67
CHAPTER 6 – M&R PLANNING AND BUDGET SCENARIO ANALYSIS.....	69
6.1 Localized Maintenance and Repair Analysis and Recommendations.....	69
6.2 Major Rehabilitation Needs.....	71
6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs.....	71
CHAPTER 7 – CONCLUSION.....	76
7.1 Recommendations.....	76
7.1.1 Continued PCI Surveys.....	76
7.1.2 Localized Maintenance and Repair.....	76
7.1.3 Major Rehabilitation.....	76
7.1.4 Pavement Management System.....	76
7.2 Supporting Documents.....	77
Airfield Pavement Network Definition Exhibit.....	77
Airfield Pavement System Inventory Exhibit.....	77
Airfield Pavement Estimated Age Exhibit.....	77
Airfield Pavement Condition Index Exhibit.....	77
Airfield Pavement Major Rehabilitation Exhibit.....	77
Inspection Photograph Documentation.....	77
7.3 Conclusion.....	78
7.4 References.....	78

APPENDIX


Appendix A: Airfield Pavement Analysis

Appendix B: Maintenance and Rehabilitation Planning Needs

Appendix C: Technical Exhibits

Appendix D: Inspection Photograph Documentation

Appendix E: Inspection Distress Details



LIST OF TABLES

<i>Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level</i>	2
<i>Table E.2: Forecasted PCI Values 2023-2032 – Section-Level</i>	3
<i>Table E.3: Major Rehabilitation Planning 2023-2032</i>	5
<i>Table 1.2: FDOT SAPMP Stakeholders</i>	10
<i>Table 2.5.5: SAPMP Terminology</i>	18
<i>Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete</i>	19
<i>Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete</i>	20
<i>Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete</i>	20
<i>Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete</i>	21
<i>Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction</i>	23
<i>Table 3.1.5: Pavement System Inventory Details</i>	29
<i>Table 4.1.2: Current Condition Summary – Branch-Level</i>	35
<i>Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level</i>	36
<i>Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level</i>	55
<i>Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects</i>	57
<i>Table 5.3 (b): Critical PCI Values by Branch Use</i>	57
<i>Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete</i>	62
<i>Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete</i>	62
<i>Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy</i>	63
<i>Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy</i>	64
<i>Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation</i>	66
<i>Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type</i>	67
<i>Table 6.1 (a): Year 1 Summary of Localized Maintenance</i>	69
<i>Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary</i>	70
<i>Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary</i>	70
<i>Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs</i>	72

LIST OF FIGURES

Figure E.1: PCI Rating.....	1
Figure E.2: Current Condition Summary – Branch-Level.....	2
Figure E.3: 10-Year Major Rehabilitation Needs by Program Year	6
Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts.....	9
Figure 1.4: Pavement Life and the Effect of Treatments	12
Figure 2: FDOT SAPMP General Process.....	14
Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit	24
Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit.....	25
Figure 3.1.2 (a): Age of Pavements at PCI Survey.....	26
Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit.....	27
Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)	28
Figure 3.1.4: Airfield Pavement Surface Type by Area (SF).....	29
Figure 4.1.1: Current Condition – Overall Network.....	32
Figure 4.1.2 (a): Current Condition Summary – Branch-Level.....	32
Figure 4.1.2 (b): Current Condition – Runway	33
Figure 4.1.2 (c): Current Condition – Taxiway	33
Figure 4.1.2 (d): Current Condition – Taxilane.....	34
Figure 4.1.2 (e): Current Condition – Apron.....	34
Figure 4.1.3: Airfield Pavement Condition Index Exhibit.....	38
Figure 5.2.3: Forecasted Branch-Level Pavement Performance	54
Figure 5.3 (a): Pavement Life and the Effect of Treatments	56
Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical PCI}$	58
Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical PCI}$	58
Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year	73
Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit.....	74



Executive Summary



Executive Summary

Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Leesburg International Airport’s System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B “Airport Pavement Management Program (PMP)” using the procedures documented in ASTM D5340-20 “Standard Test Method for Airport Pavement Condition Index Surveys”.

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with “100” indicating a pavement in new condition and “0” indicating a failed pavement section. This is graphically depicted in **Figure E.1**.

Figure E.1: PCI Rating

Color	Range	Condition Rating
	86-100	Good
	71-85	Satisfactory
	56-70	Fair
	41-55	Poor
	26-40	Very Poor
	11-25	Serious
	0-10	Failed

Current Pavement Conditions

In April 2022, approximately 2.6 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Leesburg International Airport (LEE). In general, airfield pavements at LEE are in Good condition with an area-weighted PCI of 87. The area-weighted average PCI values of the runways, taxiways, taxilanes, and aprons are 93, 78, 73, and 89, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for LEE.

Figure E.2: Current Condition Summary – Branch-Level




Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
LEE	RW 4-22	Runway	6205	242,833	85	Satisfactory
LEE	RW 4-22	Runway	6210	244,205	87	Good
LEE	RW 13-31	Runway	6105	255,000	100	Good
LEE	RW 13-31	Runway	6110	255,000	100	Good
LEE	RW 13-31	Runway	6115	12,500	88	Good
LEE	RW 13-31	Runway	6120	12,500	88	Good
LEE	RW 13-31	Runway	6125	47,500	92	Good
LEE	RW 13-31	Runway	6130	47,500	95	Good
LEE	TW A	Taxiway	100	77,110	80	Satisfactory
LEE	TW A	Taxiway	105	82,235	87	Good
LEE	TW A	Taxiway	107	4,534	64	Fair
LEE	TW A	Taxiway	110	113,871	75	Satisfactory
LEE	TW A	Taxiway	115	62,194	83	Satisfactory
LEE	TW A1	Taxiway	120	4,409	56	Fair
LEE	TW A2	Taxiway	130	4,287	63	Fair
LEE	TW A3	Taxiway	140	4,673	54	Poor
LEE	TW A4	Taxiway	150	11,820	83	Satisfactory

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
LEE	TW B	Taxiway	200	76,570	77	Satisfactory
LEE	TW C	Taxiway	300	25,917	75	Satisfactory
LEE	TW D	Taxiway	400	22,621	55	Poor
LEE	TW E	Taxiway	500	8,617	87	Good
LEE	TW J	Taxiway	600	26,600	86	Good
LEE	TW K	Taxiway	700	138,244	78	Satisfactory
LEE	TW K	Taxiway	705	33,012	65	Fair
LEE	TW K	Taxiway	710	23,819	91	Good
LEE	TW K	Taxiway	715	4,634	52	Poor
LEE	TL APRON	Taxilane	4305	10,698	29	Very Poor
LEE	TL SEA	Taxilane	160	42,517	92	Good
LEE	TL T-HANG	Taxilane	4110	14,559	69	Fair
LEE	TL T-HANG	Taxilane	4115	20,585	69	Fair
LEE	TL T-HANG	Taxilane	4205	45,127	68	Fair
LEE	AP FUEL	Apron	4505	25,329	23	Serious
LEE	AP HELI	Apron	4405	14,409	100	Good
LEE	AP N	Apron	4105	294,586	100	Good
LEE	AP N	Apron	4120	5,920	57	Fair
LEE	AP N	Apron	4125	26,853	100	Good
LEE	AP N	Apron	4130	44,288	93	Good
LEE	AP N	Apron	4135	18,579	27	Very Poor
LEE	AP N	Apron	4140	8,600	12	Serious
LEE	AP N	Apron	4145	11,497	94	Good
LEE	AP N	Apron	4150	13,976	100	Good
LEE	AP N	Apron	4155	32,837	100	Good
LEE	AP RU 13	Apron	5205	36,679	78	Satisfactory
LEE	AP RU 31	Apron	5305	54,952	85	Satisfactory
LEE	AP RU SEA	Apron	5405	18,231	89	Good

Forecasted Pavement Conditions

Table E.2 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

Table E.2: Forecasted PCI Values 2023-2032 – Section-Level

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
LEE	RW 4-22	6205	85	83	81	79	77	75	73	71	69	67	65
LEE	RW 4-22	6210	87	85	83	81	79	77	75	73	71	69	67

Airport Pavement Evaluation Report

Statewide Airfield Pavement Management Program

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
LEE	RW 13-31	6105	100	95	93	91	89	87	85	84	82	80	78
LEE	RW 13-31	6110	100	95	93	91	89	87	85	84	82	80	78
LEE	RW 13-31	6115	88	86	84	82	81	79	77	76	74	72	71
LEE	RW 13-31	6120	88	86	84	82	81	79	77	76	74	72	71
LEE	RW 13-31	6125	92	90	88	86	85	83	81	80	78	76	75
LEE	RW 13-31	6130	95	93	91	90	88	86	84	83	81	79	77
LEE	TW A	100	80	78	77	75	74	72	71	70	69	67	66
LEE	TW A	105	87	85	83	81	79	78	76	75	73	72	71
LEE	TW A	107	64	63	61	60	59	57	56	54	53	51	49
LEE	TW A	110	75	73	72	71	69	68	67	66	64	63	62
LEE	TW A	115	83	81	79	78	76	75	73	72	71	69	68
LEE	TW A1	120	56	55	55	54	54	53	53	53	52	52	51
LEE	TW A2	130	63	62	61	60	60	59	58	58	57	57	56
LEE	TW A3	140	54	53	53	53	52	52	51	51	50	50	50
LEE	TW A4	150	83	82	81	81	80	79	78	78	77	76	75
LEE	TW B	200	77	75	74	72	71	70	69	67	66	65	64
LEE	TW C	300	75	73	72	71	69	68	67	66	65	64	63
LEE	TW D	400	55	54	54	54	53	53	52	52	51	51	50
LEE	TW E	500	87	85	83	81	79	78	76	75	73	72	71
LEE	TW J	600	86	84	82	80	78	77	75	74	73	71	70
LEE	TW K	700	78	76	75	73	72	71	69	68	67	66	64
LEE	TW K	705	65	64	63	62	61	61	60	59	58	58	57
LEE	TW K	710	91	89	87	85	83	81	79	78	76	75	73
LEE	TW K	715	52	52	51	51	50	50	49	49	48	48	47
LEE	TL APRON	4305	29	27	26	24	23	21	19	17	15	13	12
LEE	TL SEA	160	92	89	87	85	84	82	80	78	77	75	74
LEE	TL T-HANG	4110	69	68	67	66	65	64	63	62	61	60	60
LEE	TL T-HANG	4115	69	68	67	66	65	64	63	62	61	60	60
LEE	TL T-HANG	4205	68	67	66	65	64	63	62	61	60	60	59
LEE	AP FUEL	4505	23	22	21	21	20	19	18	17	17	16	15
LEE	AP HELI	4405	100	99	98	97	96	95	94	93	92	91	90
LEE	AP N	4105	100	98	96	94	92	90	88	86	84	82	80
LEE	AP N	4120	57	56	55	54	53	52	51	50	49	48	47
LEE	AP N	4125	100	98	96	94	92	90	88	86	84	82	80
LEE	AP N	4130	93	92	91	90	89	88	87	86	85	84	83
LEE	AP N	4135	27	26	25	24	23	22	21	20	19	18	17
LEE	AP N	4140	12	11	10	9	8	7	6	5	4	3	2
LEE	AP N	4145	94	91	89	87	85	83	81	79	77	75	73
LEE	AP N	4150	100	97	94	92	90	88	85	83	81	79	78
LEE	AP N	4155	100	97	94	92	90	88	85	83	81	79	78
LEE	AP RU 13	5205	78	76	74	72	71	69	68	66	65	64	62
LEE	AP RU 31	5305	85	83	81	79	77	75	73	72	70	69	67
LEE	AP RU SEA	5405	89	86	84	82	80	78	77	75	73	72	70

Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$16.77M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$3.04M and localized maintenance needs for Year 1 are \$0.13M.

Table E.3: Major Rehabilitation Planning 2023-2032


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	LEE	TW A	107	AAC	4,534	63	AC Rehabilitation	\$ 41,000
2023	LEE	TW A1	120	AC	4,409	55	AC Rehabilitation	\$ 40,000
2023	LEE	TW A2	130	AC	4,287	62	AC Rehabilitation	\$ 39,000
2023	LEE	TW A3	140	AC	4,673	53	AC Reconstruction	\$ 75,000
2023	LEE	TW D	400	AC	22,621	54	AC Reconstruction	\$ 294,000
2023	LEE	TW K	705	AC	33,012	64	AC Rehabilitation	\$ 298,000
2023	LEE	TW K	715	AC	4,634	52	AC Reconstruction	\$ 75,000
2023	LEE	TL APRON	4305	AC	10,698	27	AC Reconstruction	\$ 172,000
2023	LEE	TL T-HANG	4110	AC	14,559	68	AC Rehabilitation	\$ 132,000
2023	LEE	TL T-HANG	4115	AC	20,585	68	AC Rehabilitation	\$ 186,000
2023	LEE	TL T-HANG	4205	AC	45,127	67	AC Rehabilitation	\$ 407,000
2023	LEE	AP FUEL	4505	AC	25,329	22	AC Reconstruction	\$ 406,000
2023	LEE	AP N	4120	PCC	5,920	56	PCC Rehabilitation	\$ 89,000
2023	LEE	AP N	4135	PCC	18,579	26	PCC Reconstruction	\$ 539,000
2023	LEE	AP N	4140	PCC	8,600	11	PCC Reconstruction	\$ 250,000
2026	LEE	TW A	110	AAC	113,871	69	AC Rehabilitation	\$ 1,187,000
2026	LEE	TW C	300	AC	25,917	69	AC Rehabilitation	\$ 271,000
2027	LEE	TW B	200	AAC	76,570	70	AC Rehabilitation	\$ 838,000
2027	LEE	AP RU 13	5205	AC	36,679	69	AC Rehabilitation	\$ 402,000

Airport Pavement Evaluation Report
 Statewide Airfield Pavement Management Program

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2028	LEE	TW K	700	AAC	138,244	69	AC Rehabilitation	\$ 1,589,000
2029	LEE	TW A	100	AC	77,110	70	AC Rehabilitation	\$ 931,000
2030	LEE	RW 4-22	6205	AAC	242,833	69	AC Rehabilitation	\$ 3,076,000
2031	LEE	RW 4-22	6210	AAC	244,205	69	AC Rehabilitation	\$ 3,248,000
2031	LEE	TW A	115	AC	62,194	69	AC Rehabilitation	\$ 828,000
2031	LEE	AP RU 31	5305	AC	54,952	69	AC Rehabilitation	\$ 731,000
2032	LEE	TW J	600	AAC	26,600	70	AC Rehabilitation	\$ 372,000
2032	LEE	AP RU SEA	5405	AC	18,231	70	AC Rehabilitation	\$ 255,000

*All planning cost values have been rounded up to the nearest thousand dollars.

Figure E.3: 10-Year Major Rehabilitation Needs by Program Year





Chapter 1: Introduction



Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration’s (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida’s economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida’s system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida’s most prominent industry.

1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.


Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements” and 150/5380-7B “Airport Pavement Management Program (PMP)”. The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 “Standard Test Method for Airport Pavement Condition Index Surveys”.

In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.” The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are

under consideration for projects. A network-level evaluation can support the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts



1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

Table 1.2: FDOT SAPMP Stakeholders

Role	Description
FAA Orlando Airports District Office (Orlando ADO)	Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation).
Florida Department of Transportation (FDOT)	Key Stakeholder: the FDOT is the “Sponsor” for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System.
FDOT District Offices	The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP’s ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes.
Participating Public-Use and Publicly-Owned Airports	The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport’s airfield PCI assessment.
Aviation Office Program Manager (AO-PM)	FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update.

1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- » Research and evaluation of existing record documentation;
- » Establishment of a pavement system inventory;
- » Development of a pavement network definition map and supplemental GIS model;
- » Functional pavement evaluations via the PCI assessment method;
- » Customization of PAVER™ software including prioritization, policies, and performance models;
- » Analysis of condition data; and
- » Maintenance, repair, and rehabilitation planning.

1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.


A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:

- » Assist airports in meeting the requirements of Public Law 103-305;
- » Assist airports in complying with FAA Grant Assurances 11 and 19;
- » Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- » Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- » Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.

Figure 1.4: Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds: >70: Routine Maintenance 55-70: Rehabilitation Eligible <55: Reconstruction Eligible

*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements




Chapter 2: Methodology



Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.

Figure 2: FDOT SAPMP General Process



2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport’s eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- » Create a manageable inventory system;
- » Analyze the current condition of pavements in accordance with ASTM D5340-20;
- » Develop pavement performance models to forecast conditions; and
- » Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database and typically consist of pavement inventory

characteristics, pavement structure, work history, historic condition records, and analytical customization.

2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- » Location and limits of work;
- » Types and severities of repaired distresses;
- » Work type and cost; and
- » Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport’s staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- » Date of last construction/rehabilitation
- » Work type performed
- » Comments for documenting pavement cross-section
- » Pavement surface type
- » Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer’s construction report for pavement construction records.

2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.

2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F “Airport Pavement Design and Evaluation” are recognized as PCC pavement.

2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

Conventional Whitetopping (WT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

Ultra-Thin Whitetopping (UWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

2.4 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of LEE’s aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.5 Pavement Management Program Network Definition Terminology

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

2.5.1 Pavement Network Identification

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport’s airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport’s airfield pavement facilities maintained by the Airport.

2.5.2 Pavement Branch Identification

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.

2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs (± 8 slabs) for PCC pavement and 5,000 contiguous square feet ($\pm 2,000$ SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

Table 2.5.5: SAPMP Terminology

SAPMP Terminology	Common Definition	Airport Example
Network	Totality of pavement assets maintained by the Airport.	"Tallahassee International Airport – Airfield Pavements"
Branch Name	Commonly defined asset name as established by Airport and by use.	"Runway 18-36"
Branch ID	Codified shorthand name for commonly defined asset established for database identification.	"RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility
Section ID	Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition.	"6105"
Sample Unit	A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20.	"300"

2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete

Distress Mechanism	Distress Type
Load	Alligator Cracking Rutting
Climate/Durability	Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering
Construction/Material	Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling
Other	Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching

Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete

Distress Mechanism	Distress Type
Load	Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks
Climate/Durability	Blowup Durability "D" Cracking Joint Seal Damage Popouts
Construction/Material	Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking
Other	Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching

2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.


Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10


Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.



Chapter 3: Airfield Pavement System Inventory



Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport’s airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.

Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction

Construction Year	Location	Work Type / Pavement Section
2019	TL SEA, AP RU SEA	New Construction - AC
2021	RW 13-31	Mill and Overlay 1" Mill, Variable P-403, 2" P-401
2022	AP HELI	New Construction - PCC 8" P-501, P-152 Stabilized Subgrade
	AP N	Mill and Overlay Mill of Existing AC, 4" P-401 Overlay
	AP N	Complete Reconstruction - AC 4" P-401, 4" P-211, P-152 Stabilized Subgrade

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport’s pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

Figure 3.1.1 (a), the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.




LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID
- AAC — PAVEMENT SURFACE TYPE
- AP MAIN — PAVEMENT BRANCH ID
- 4105 — SECTION NUMBER
- 10 | 100 — NUMBER OF SAMPLE UNITS IN SECTION
NUMBER OF SAMPLE UNITS TO BE INSPECTED
- AAC
AP MAIN
4105
0 | 100 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100 — INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 67
 AC: 61 PCC: 6

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2019	AP RU SEA, TL SEA	New Construction - AC
2021	RW 13-31	Mill and Overlay 1" Mill, Variable P-403, 2" P-401
2022	AP HELI	New Construction - PCC 8" P-501, P-152 Stabilized Subgrade
	AP N	Complete Reconstruction - AC 4" P-401, 4" P-211, P-152 Stabilized Subgrade
	AP N	Mill and Overlay Mill of Existing AC, 4" P-401 Overlay

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROJECT YEAR


 2017	 2022
 2018	 2023
 2019	 2024
 2020	 2025
 2021	 2026


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.

Figure 3.1.2 (a): Age of Pavements at PCI Survey





LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID

AGE AT INSPECTION

- 0-5 Years
- 6-10 Years
- 11-15 Years
- 16-20 Years
- > 20 Years


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed “functional use” or “branch use.” For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.

Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)




3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at LEE.

Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)



3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

Table 3.1.5 displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

Table 3.1.5: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
LEE	RW 4-22	Runway	6205	242,833	AAC	1/1/2011
LEE	RW 4-22	Runway	6210	244,205	AAC	1/1/2011
LEE	RW 13-31	Runway	6105	255,000	AAC	1/1/2021
LEE	RW 13-31	Runway	6110	255,000	AAC	1/1/2021
LEE	RW 13-31	Runway	6115	12,500	AC	12/12/2009
LEE	RW 13-31	Runway	6120	12,500	AC	12/12/2009
LEE	RW 13-31	Runway	6125	47,500	AC	1/1/2009
LEE	RW 13-31	Runway	6130	47,500	AC	1/1/2009

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
LEE	TW A	Taxiway	100	77,110	AC	1/1/2009
LEE	TW A	Taxiway	105	82,235	AC	1/1/2014
LEE	TW A	Taxiway	107	4,534	AAC	1/1/2002
LEE	TW A	Taxiway	110	113,871	AAC	1/1/2000
LEE	TW A	Taxiway	115	62,194	AC	1/1/2009
LEE	TW A1	Taxiway	120	4,409	AC	1/1/1989
LEE	TW A2	Taxiway	130	4,287	AC	1/1/1989
LEE	TW A3	Taxiway	140	4,673	AC	1/1/1989
LEE	TW A4	Taxiway	150	11,820	PCC	1/1/2008
LEE	TW B	Taxiway	200	76,570	AAC	1/1/2011
LEE	TW C	Taxiway	300	25,917	AC	1/1/2009
LEE	TW D	Taxiway	400	22,621	AC	1/1/2002
LEE	TW E	Taxiway	500	8,617	AC	1/1/2011
LEE	TW J	Taxiway	600	26,600	AAC	1/1/2011
LEE	TW K	Taxiway	700	138,244	AAC	1/1/2011
LEE	TW K	Taxiway	705	33,012	AC	1/1/2004
LEE	TW K	Taxiway	710	23,819	AC	1/1/2014
LEE	TW K	Taxiway	715	4,634	AC	1/1/1986
LEE	TL APRON	Taxilane	4305	10,698	AC	1/1/1982
LEE	TL SEA	Taxilane	160	42,517	AC	1/1/2019
LEE	TL T-HANG	Taxilane	4110	14,559	AC	12/25/2000
LEE	TL T-HANG	Taxilane	4115	20,585	AC	12/25/2000
LEE	TL T-HANG	Taxilane	4205	45,127	AC	1/1/2003
LEE	AP FUEL	Apron	4505	25,329	AC	1/1/1989
LEE	AP HELI	Apron	4405	14,409	PCC	4/1/2022
LEE	AP N	Apron	4105	294,586	AAC	4/1/2022
LEE	AP N	Apron	4120	5,920	PCC	12/25/2000
LEE	AP N	Apron	4125	26,853	AAC	4/1/2022
LEE	AP N	Apron	4130	44,288	PCC	1/1/2008
LEE	AP N	Apron	4135	18,579	PCC	1/1/1942
LEE	AP N	Apron	4140	8,600	PCC	1/1/1942
LEE	AP N	Apron	4145	11,497	AC	7/1/2016
LEE	AP N	Apron	4150	13,976	AC	4/1/2022
LEE	AP N	Apron	4155	32,837	AC	4/1/2022
LEE	AP RU 13	Apron	5205	36,679	AC	1/1/2008
LEE	AP RU 31	Apron	5305	54,952	AC	1/1/2009
LEE	AP RU SEA	Apron	5405	18,231	AC	1/1/2019



Chapter 4: Airfield Pavement Condition Analysis



Chapter 4 – Airfield Pavement Condition Analysis


The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for design-and/or project-level determination of pavement rehabilitation needs.

4.1 Airfield Pavement Condition Index

4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 92% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 5% of inspected pavements are in Fair condition and the remaining 3% of inspected pavements are in Poor or worse condition.

Figure 4.1.1: Current Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(e)** summarize branch-level pavement conditions according to the most recent PCI assessment results.

Figure 4.1.2 (a): Current Condition Summary – Branch-Level




Figure 4.1.2 (b): Current Condition – Runway




Figure 4.1.2 (c): Current Condition – Taxiway




Figure 4.1.2 (d): Current Condition – Taxi Lane




Figure 4.1.2 (e): Current Condition – Apron




Table 4.1.2 details the branch-level condition for each airfield pavement branch.

Table 4.1.2: Current Condition Summary – Branch-Level

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
RW 4-22	Runway	2	487,038	86	Good
RW 13-31	Runway	6	630,000	99	Good
TW A	Taxiway	5	339,944	80	Satisfactory
TW A1	Taxiway	1	4,409	56	Fair
TW A2	Taxiway	1	4,287	63	Fair
TW A3	Taxiway	1	4,673	54	Poor
TW A4	Taxiway	1	11,820	83	Satisfactory
TW B	Taxiway	1	76,570	77	Satisfactory
TW C	Taxiway	1	25,917	75	Satisfactory
TW D	Taxiway	1	22,621	55	Poor
TW E	Taxiway	1	8,617	87	Good
TW J	Taxiway	1	26,600	86	Good
TW K	Taxiway	4	199,709	77	Satisfactory
TL APRON	Taxilane	1	10,698	29	Very Poor
TL SEA	Taxilane	1	42,517	92	Good
TL T-HANG	Taxilane	3	80,271	68	Fair
AP FUEL	Apron	1	25,329	23	Serious
AP HELI	Apron	1	14,409	100	Good
AP N	Apron	9	457,136	94	Good
AP RU 13	Apron	1	36,679	78	Satisfactory
AP RU 31	Apron	1	54,952	85	Satisfactory
AP RU SEA	Apron	1	18,231	89	Good

4.1.3 Section-Level Analysis

Table 4.1.3 provides each pavement section’s area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. Figure 4.1.3 provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.


Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.

Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
LEE	RW 4-22	Runway	6205	242,833	AAC	85	Satisfactory	94	0	6	8	48
LEE	RW 4-22	Runway	6210	244,205	AAC	87	Good	100	0	0	8	48
LEE	RW 13-31	Runway	6105	255,000	AAC	100	Good	0	0	0	0	0
LEE	RW 13-31	Runway	6110	255,000	AAC	100	Good	0	0	0	0	0
LEE	RW 13-31	Runway	6115	12,500	AC	88	Good	100	0	0	1	3
LEE	RW 13-31	Runway	6120	12,500	AC	88	Good	100	0	0	1	2
LEE	RW 13-31	Runway	6125	47,500	AC	92	Good	100	0	0	3	10
LEE	RW 13-31	Runway	6130	47,500	AC	95	Good	100	0	0	2	10
LEE	TW A	Taxiway	100	77,110	AC	80	Satisfactory	66	0	34	3	15
LEE	TW A	Taxiway	105	82,235	AC	87	Good	100	0	0	2	15
LEE	TW A	Taxiway	107	4,534	AAC	64	Fair	78	0	22	1	1
LEE	TW A	Taxiway	110	113,871	AAC	75	Satisfactory	82	0	18	3	22
LEE	TW A	Taxiway	115	62,194	AC	83	Satisfactory	100	0	0	2	11
LEE	TW A1	Taxiway	120	4,409	AC	56	Fair	95	0	5	1	1
LEE	TW A2	Taxiway	130	4,287	AC	63	Fair	100	0	0	1	1
LEE	TW A3	Taxiway	140	4,673	AC	54	Poor	92	0	8	1	1
LEE	TW A4	Taxiway	150	11,820	PCC	83	Satisfactory	12	56	32	1	2
LEE	TW B	Taxiway	200	76,570	AAC	77	Satisfactory	100	0	0	3	16
LEE	TW C	Taxiway	300	25,917	AC	75	Satisfactory	100	0	0	1	4
LEE	TW D	Taxiway	400	22,621	AC	55	Poor	38	0	62	1	5
LEE	TW E	Taxiway	500	8,617	AC	87	Good	100	0	0	1	2
LEE	TW J	Taxiway	600	26,600	AAC	86	Good	100	0	0	1	6
LEE	TW K	Taxiway	700	138,244	AAC	78	Satisfactory	100	0	0	3	28
LEE	TW K	Taxiway	705	33,012	AC	65	Fair	100	0	0	1	8
LEE	TW K	Taxiway	710	23,819	AC	91	Good	100	0	0	1	5
LEE	TW K	Taxiway	715	4,634	AC	52	Poor	100	0	0	1	1
LEE	TL APRON	Taxilane	4305	10,698	AC	29	Very Poor	31	55	14	1	2
LEE	TL SEA	Taxilane	160	42,517	AC	92	Good	100	0	0	1	8
LEE	TL T-HANG	Taxilane	4110	14,559	AC	69	Fair	100	0	0	1	3
LEE	TL T-HANG	Taxilane	4115	20,585	AC	69	Fair	100	0	0	1	5
LEE	TL T-HANG	Taxilane	4205	45,127	AC	68	Fair	94	0	6	1	9
LEE	AP FUEL	Apron	4505	25,329	AC	23	Serious	93	0	7	1	5
LEE	AP HELI	Apron	4405	14,409	PCC	100	Good	0	0	0	0	0
LEE	AP N	Apron	4105	294,586	AAC	100	Good	0	0	0	0	0
LEE	AP N	Apron	4120	5,920	PCC	57	Fair	23	55	22	1	2
LEE	AP N	Apron	4125	26,853	AAC	100	Good	0	0	0	0	0
LEE	AP N	Apron	4130	44,288	PCC	93	Good	0	33	67	2	8
LEE	AP N	Apron	4135	18,579	PCC	27	Very Poor	10	58	32	1	4
LEE	AP N	Apron	4140	8,600	PCC	12	Serious	13	87	0	1	1
LEE	AP N	Apron	4145	11,497	AC	94	Good	100	0	0	1	2
LEE	AP N	Apron	4150	13,976	AC	100	Good	0	0	0	0	0
LEE	AP N	Apron	4155	32,837	AC	100	Good	0	0	0	0	0
LEE	AP RU 13	Apron	5205	36,679	AC	78	Satisfactory	89	0	11	1	8

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
LEE	AP RU 31	Apron	5305	54,952	AC	85	Satisfactory	100	0	0	2	11
LEE	AP RU SEA	Apron	5405	18,231	AC	89	Good	100	0	0	1	4

* Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.



LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID

2022 PAVEMENT CONDITION INDEX

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

SECTION ID
PCI VALUE

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The PCI assessment for Leesburg International Airport (LEE) was performed in April 2022. The overall area-weighted average PCI value of the network was 87, representing a condition rating of Good. A majority of RW 13-31 and the North Apron was not inspected due to previous or ongoing pavement rehabilitation and construction.

Based on the FAA 5010 Report as of 10/28/2022, the Airport has reported 68,193 operations for 12 months ending 09/30/2021.

4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

Runways

RW 13-31

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 13-31	RUNWAY	6	630,000	99	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6105	AAC	255,000	100	Good
6110	AAC	255,000	100	Good
6115	AC	12,500	88	Good
6120	AC	12,500	88	Good
6125	AC	47,500	92	Good
6130	AC	47,500	95	Good

RW 13-31 consists of 6 flexible pavement sections, totaling 630,000 sf. The last major construction dates range from 2009 to 2021, resulting in an area-weighted average age at inspection of 2 years old. Overall, RW 13-31 is in Good condition with an area-weighted average PCI of 99.

RW 4-22

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 4-22	RUNWAY	2	487,038	86	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 50% Good (86-100 PCI), 50% Satisfactory (71-85 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6205	AAC	242,833	85	Satisfactory
6210	AAC	244,205	87	Good


RW 4-22 consists of 2 flexible pavement sections, totaling 487,038 sf. The last major construction date for the branch was 2011, resulting in an area-weighted average age at inspection of 11 years old. Overall, RW 4-22 is in Good condition with an area-weighted average PCI of 86.

Taxiways

TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	5	339,944	80	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 24% Good (86-100 PCI), 75% Satisfactory (71-85 PCI), 1% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
100	AC	77,110	80	Satisfactory
105	AC	82,235	87	Good
107	AAC	4,534	64	Fair
110	AAC	113,871	75	Satisfactory
115	AC	62,194	83	Satisfactory

TW A consists of 5 flexible pavement sections, totaling 339,944 sf. The last major construction dates range from 2000 to 2014, resulting in an area-weighted average age at inspection of 15 years old. Overall, TW A is in Satisfactory condition with an area-weighted average PCI of 80.

TW A1

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A1	TAXIWAY	1	4,409	56	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
120	AC	4,409	56	Fair

TW A1 consists of 1 flexible pavement section, totaling 4,409 sf. The last major construction date for the branch was 1989, resulting in an area-weighted average age at inspection of 33 years old. Overall, TW A1 is in Fair condition with an area-weighted average PCI of 56.

TW A2

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A2	TAXIWAY	1	4,287	63	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
130	AC	4,287	63	Fair

TW A2 consists of 1 flexible pavement section, totaling 4,287 sf. The last major construction date for the branch was 1989, resulting in an area-weighted average age at inspection of 33 years old. Overall, TW A2 is in Fair condition with an area-weighted average PCI of 63.

TW A3

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A3	TAXIWAY	1	4,673	54	Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Poor (41-55 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
140	AC	4,673	54	Poor

TW A3 consists of 1 flexible pavement section, totaling 4,673 sf. The last major construction date for the branch was 1989, resulting in an area-weighted average age at inspection of 33 years old. Overall, TW A3 is in Poor condition with an area-weighted average PCI of 54.

TW A4

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A4	TAXIWAY	1	11,820	83	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
150	PCC	11,820	83	Satisfactory

TW A4 consists of 1 rigid pavement section, totaling 11,820 sf. The last major construction date for the branch was 2008, resulting in an area-weighted average age at inspection of 14 years old. Overall, TW A4 is in Satisfactory condition with an area-weighted average PCI of 83.

TW B

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW B	TAXIWAY	1	76,570	77	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
200	AAC	76,570	77	Satisfactory

TW B consists of 1 flexible pavement section, totaling 76,570 sf. The last major construction date for the branch was 2011, resulting in an area-weighted average age at inspection of 11 years old. Overall, TW B is in Satisfactory condition with an area-weighted average PCI of 77.

TW C

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW C	TAXIWAY	1	25,917	75	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
300	AC	25,917	75	Satisfactory

TW C consists of 1 flexible pavement section, totaling 25,917 sf. The last major construction date for the branch was 2009, resulting in an area-weighted average age at inspection of 13 years old. Overall, TW C is in Satisfactory condition with an area-weighted average PCI of 75.

TW D

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW D	TAXIWAY	1	22,621	55	Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Poor (41-55 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
400	AC	22,621	55	Poor

TW D consists of 1 flexible pavement section, totaling 22,621 sf. The last major construction date for the branch was 2002, resulting in an area-weighted average age at inspection of 20 years old. Overall, TW D is in Poor condition with an area-weighted average PCI of 55.

TW E

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW E	TAXIWAY	1	8,617	87	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
500	AC	8,617	87	Good

TW E consists of 1 flexible pavement section, totaling 8,617 sf. The last major construction date for the branch was 2011, resulting in an area-weighted average age at inspection of 11 years old. Overall, TW E is in Good condition with an area-weighted average PCI of 87.

TW J

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW J	TAXIWAY	1	26,600	86	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
600	AAC	26,600	86	Good

TW J consists of 1 flexible pavement section, totaling 26,600 sf. The last major construction date for the branch was 2011, resulting in an area-weighted average age at inspection of 11 years old. Overall, TW J is in Good condition with an area-weighted average PCI of 86.

TW K

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW K	TAXIWAY	4	199,709	77	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 12% Good (86-100 PCI), 69% Satisfactory (71-85 PCI), 17% Fair (56-70 PCI), 2% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
700	AAC	138,244	78	Satisfactory
705	AC	33,012	65	Fair
710	AC	23,819	91	Good
715	AC	4,634	52	Poor


TW K consists of 4 flexible pavement sections, totaling 199,709 sf. The last major construction dates range from 1986 to 2014, resulting in an area-weighted average age at inspection of 13 years old. Overall, TW K is in Satisfactory condition with an area-weighted average PCI of 77.

Taxilanes

TL APRON

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL APRON	TAXILANE	1	10,698	29	Very Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Very Poor (26-40 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4305	AC	10,698	29	Very Poor

TL APRON consists of 1 flexible pavement section, totaling 10,698 sf. The last major construction date for the branch was 1982, resulting in an area-weighted average age at inspection of 40 years old. Overall, TL APRON is in Very Poor condition with an area-weighted average PCI of 29.

TL SEA

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL SEA	TAXILANE	1	42,517	92	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
160	AC	42,517	92	Good

TL SEA consists of 1 flexible pavement section, totaling 42,517 sf. The last major construction date for the branch was 2019, resulting in an area-weighted average age at inspection of 3 years old. Overall, TL SEA is in Good condition with an area-weighted average PCI of 92.

TL T-HANG

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL T-HANG	TAXILANE	3	80,271	68	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4110	AC	14,559	69	Fair
4115	AC	20,585	69	Fair
4205	AC	45,127	68	Fair

TL T-HANG consists of 3 flexible pavement sections, totaling 80,271 sf. The last major construction dates range from 2000 to 2003, resulting in an area-weighted average age at


inspection of 20 years old. Overall, TL T-HANG is in Fair condition with an area-weighted average PCI of 68.

Aprons

AP FUEL

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP FUEL	APRON	1	25,329	23	Serious

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Serious (11-25 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4505	AC	25,329	23	Serious

AP FUEL consists of 1 flexible pavement section, totaling 25,329 sf. The last major construction date for the branch was 1989, resulting in an area-weighted average age at inspection of 33 years old. Overall, AP FUEL is in Serious condition with an area-weighted average PCI of 23.

AP HELI

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP HELI	APRON	1	14,409	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4405	PCC	14,409	100	Good

AP HELI consists of 1 rigid pavement section, totaling 14,409 sf. The last major construction date for the branch was 2022. Overall, AP HELI is in Good condition with an area-weighted average PCI of 100.

AP N

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP N	APRON	9	457,136	94	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 93% Good (86-100 PCI), 1% Fair (56-70 PCI), 4% Very Poor (26-40 PCI), 2% Serious (11-25 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4105	AAC	294,586	100	Good
4120	PCC	5,920	57	Fair
4125	AAC	26,853	100	Good
4130	PCC	44,288	93	Good
4135	PCC	18,579	27	Very Poor
4140	PCC	8,600	12	Serious
4145	AC	11,497	94	Good
4150	AC	13,976	100	Good
4155	AC	32,837	100	Good

AP N consists of 5 flexible and 4 rigid pavement sections, totaling 457,136 sf. The last major construction dates range from 1942 to 2022, resulting in an area-weighted average age at inspection of 7 years old. Overall, AP N is in Good condition with an area-weighted average PCI of 94.

AP RU 13

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU 13	APRON	1	36,679	78	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5205	AC	36,679	78	Satisfactory

AP RU 13 consists of 1 flexible pavement section, totaling 36,679 sf. The last major construction date for the branch was 2008, resulting in an area-weighted average age at inspection of 14 years old. Overall, AP RU 13 is in Satisfactory condition with an area-weighted average PCI of 78.

AP RU 31

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU 31	APRON	1	54,952	85	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5305	AC	54,952	85	Satisfactory

AP RU 31 consists of 1 flexible pavement section, totaling 54,952 sf. The last major construction date for the branch was 2009, resulting in an area-weighted average age at inspection of 13 years old. Overall, AP RU 31 is in Satisfactory condition with an area-weighted average PCI of 85.

AP RU SEA

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU SEA	APRON	1	18,231	89	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5405	AC	18,231	89	Good

AP RU SEA consists of 1 flexible pavement section, totaling 18,231 sf. The last major construction date for the branch was 2019, resulting in an area-weighted average age at inspection of 3 years old. Overall, AP RU SEA is in Good condition with an area-weighted average PCI of 89.



Chapter 5: SAPMP Customization



Chapter 5 – SAPMP Customization

Once the PAVER™ database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- » The “Network” field identifies the airport being analyzed;
- » The “Airport Classification” field classifies the Airport according to the type and volume of aircraft traffic;
 - “GA” for General Aviation, community airports
 - “RL” for Regional Relievers
 - “PR” for Primary/Commercial airports
- » The “District” field identifies the FDOT District to which the Airport belongs;
- » The “FAA ADO Area” is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists);
- » The “Inspection Phase” denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- » The “CFASPP Center” identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.

5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. **The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.** Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.


5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into “groups” or “families” according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

5.2.3 Branch-Level Pavement Condition Forecast

Figure 5.2.3 depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.

Figure 5.2.3: Forecasted Branch-Level Pavement Performance



5.2.4 Section-Level Pavement Condition Forecast

Table 5.2.4 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level


Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
LEE	RW 4-22	6205	85	83	81	79	77	75	73	71	69	67	65
LEE	RW 4-22	6210	87	85	83	81	79	77	75	73	71	69	67
LEE	RW 13-31	6105	100	95	93	91	89	87	85	84	82	80	78
LEE	RW 13-31	6110	100	95	93	91	89	87	85	84	82	80	78
LEE	RW 13-31	6115	88	86	84	82	81	79	77	76	74	72	71
LEE	RW 13-31	6120	88	86	84	82	81	79	77	76	74	72	71
LEE	RW 13-31	6125	92	90	88	86	85	83	81	80	78	76	75
LEE	RW 13-31	6130	95	93	91	90	88	86	84	83	81	79	77
LEE	TW A	100	80	78	77	75	74	72	71	70	69	67	66
LEE	TW A	105	87	85	83	81	79	78	76	75	73	72	71
LEE	TW A	107	64	63	61	60	59	57	56	54	53	51	49
LEE	TW A	110	75	73	72	71	69	68	67	66	64	63	62
LEE	TW A	115	83	81	79	78	76	75	73	72	71	69	68
LEE	TW A1	120	56	55	55	54	54	53	53	53	52	52	51
LEE	TW A2	130	63	62	61	60	60	59	58	58	57	57	56
LEE	TW A3	140	54	53	53	53	52	52	51	51	50	50	50
LEE	TW A4	150	83	82	81	81	80	79	78	78	77	76	75
LEE	TW B	200	77	75	74	72	71	70	69	67	66	65	64
LEE	TW C	300	75	73	72	71	69	68	67	66	65	64	63
LEE	TW D	400	55	54	54	54	53	53	52	52	51	51	50
LEE	TW E	500	87	85	83	81	79	78	76	75	73	72	71
LEE	TW J	600	86	84	82	80	78	77	75	74	73	71	70
LEE	TW K	700	78	76	75	73	72	71	69	68	67	66	64
LEE	TW K	705	65	64	63	62	61	61	60	59	58	58	57
LEE	TW K	710	91	89	87	85	83	81	79	78	76	75	73
LEE	TW K	715	52	52	51	51	50	50	49	49	48	48	47
LEE	TL APRON	4305	29	27	26	24	23	21	19	17	15	13	12
LEE	TL SEA	160	92	89	87	85	84	82	80	78	77	75	74
LEE	TL T-HANG	4110	69	68	67	66	65	64	63	62	61	60	60
LEE	TL T-HANG	4115	69	68	67	66	65	64	63	62	61	60	60
LEE	TL T-HANG	4205	68	67	66	65	64	63	62	61	60	60	59
LEE	AP FUEL	4505	23	22	21	21	20	19	18	17	17	16	15
LEE	AP HELI	4405	100	99	98	97	96	95	94	93	92	91	90
LEE	AP N	4105	100	98	96	94	92	90	88	86	84	82	80
LEE	AP N	4120	57	56	55	54	53	52	51	50	49	48	47
LEE	AP N	4125	100	98	96	94	92	90	88	86	84	82	80
LEE	AP N	4130	93	92	91	90	89	88	87	86	85	84	83
LEE	AP N	4135	27	26	25	24	23	22	21	20	19	18	17
LEE	AP N	4140	12	11	10	9	8	7	6	5	4	3	2

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
LEE	AP N	4145	94	91	89	87	85	83	81	79	77	75	73
LEE	AP N	4150	100	97	94	92	90	88	85	83	81	79	78
LEE	AP N	4155	100	97	94	92	90	88	85	83	81	79	78
LEE	AP RU 13	5205	78	76	74	72	71	69	68	66	65	64	62
LEE	AP RU 31	5305	85	83	81	79	77	75	73	72	70	69	67
LEE	AP RU SEA	5405	89	86	84	82	80	78	77	75	73	72	70

5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section’s suitability to receive major work. As soon as a section’s PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.

Figure 5.3 (a): Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds: >70: Routine Maintenance 55-70: Rehabilitation Eligible <55: Reconstruction Eligible

**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.*

Critical PCI values vary and are typically based on a pavement’s surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects

Airfield Pavement Project Type	PCI Requirement
Reconstruction	PCI < 55 (Poor)
Rehabilitation	PCI < 70 (Fair)
Maintenance	N/A

**Source:* AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

Table 5.3 (b): Critical PCI Values by Branch Use

Runway	Taxiway	Apron
70	70	70

Figures 5.3 (b) and **5.3 (c)** depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical PCI}$





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical PCI}$



5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 “Airport Foreign Object Debris (FOD) Management” provides additional guidance for developing and managing an airport FOD program.

5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety (“stopgap”) measure. The two (2) types of localized maintenance are described below in further detail.

- » Localized Preventive Maintenance and Repair
 - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- » Localized Stopgap/Safety Maintenance and Repair
 - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

AC Crack Sealing

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

AC Full-Depth Patching

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

AC Partial-Depth AC Patching

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

Grinding

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

Monitor Pavement

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.

PCC Crack Sealing

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

PCC Full-Depth Patching

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

PCC Joint Seal

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

PCC Partial-Depth Patching

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

PCC Slab Replacement

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

Surface Seal

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Tables 5.4.3 (a) and (b) display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete

Localized Work Type	General Aviation Costs	Work Type Unit
AC Crack Sealing	\$ 4.00	LF
AC Full-Depth Patching	\$ 10.00	SF
AC Partial-Depth Patching	\$ 4.75	SF
Surface Seal	\$ 0.75	SF

Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete

Localized Work Type	General Aviation Costs	Work Type Unit
Grinding	\$ 2.00	SF
PCC Crack Sealing	\$ 7.00	LF
PCC Joint Seal	\$ 4.25	LF
PCC Full-Depth Patching	\$ 50.00	SF
PCC Partial-Depth Patching	\$ 169.00	SF
PCC Slab Replacement	\$ 51.50	SF

* PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.

5.4.4 Localized Maintenance and Repair Policy

Table 5.4.4 and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.

Table 5.4.4: AC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
41	Low	Alligator Cracking	Monitor Pavement	Monitor Pavement
41	Medium	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
41	High	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
42	N/A	Bleeding	Monitor Pavement	Monitor Pavement
43	Low	Block Cracking	Monitor Pavement	Monitor Pavement
43	Medium	Block Cracking	AC Crack Sealing	Monitor Pavement
43	High	Block Cracking	AC Crack Sealing	AC Crack Sealing
44	Low	Corrugation	Monitor Pavement	Monitor Pavement
44	Medium	Corrugation	AC Full Depth Patching	Monitor Pavement
44	High	Corrugation	AC Full Depth Patching	AC Full Depth Patching
45	Low	Depression	Monitor Pavement	Monitor Pavement
45	Medium	Depression	AC Full Depth Patching	Monitor Pavement
45	High	Depression	AC Full Depth Patching	AC Full Depth Patching
46	N/A	Jet Blast	Monitor Pavement	Monitor Pavement
47	Low	Jt. Reflective Cracking	Monitor Pavement	Monitor Pavement
47	Medium	Jt. Reflective Cracking	AC Crack Sealing	Monitor Pavement
47	High	Jt. Reflective Cracking	AC Full Depth Patching	AC Full Depth Patching
48	Low	L&T Cracking	Monitor Pavement	Monitor Pavement
48	Medium	L&T Cracking	AC Crack Sealing	Monitor Pavement
48	High	L&T Cracking	AC Full Depth Patching	AC Full Depth Patching
49	N/A	Oil Spillage	Monitor Pavement	Monitor Pavement
50	Low	Patching	Monitor Pavement	Monitor Pavement
50	Medium	Patching	AC Full Depth Patching	Monitor Pavement
50	High	Patching	AC Full Depth Patching	AC Full Depth Patching
51	N/A	Polished Aggregate	Monitor Pavement	Monitor Pavement
52	Low	Raveling	Surface Seal	Monitor Pavement
52	Medium	Raveling	Surface Seal	Monitor Pavement
52	High	Raveling	AC Partial Depth Patching	AC Partial Depth Patching
53	Low	Rutting	Monitor Pavement	Monitor Pavement
53	Medium	Rutting	AC Full Depth Patching	Monitor Pavement
53	High	Rutting	AC Full Depth Patching	AC Full Depth Patching
54	Low	Shoving	Monitor Pavement	Monitor Pavement
54	Medium	Shoving	AC Partial Depth Patching	Monitor Pavement
54	High	Shoving	AC Full Depth Patching	AC Full Depth Patching
55	N/A	Slippage Cracking	AC Full Depth Patching	AC Full Depth Patching
56	Low	Swelling	Monitor Pavement	Monitor Pavement
56	Medium	Swelling	AC Full Depth Patching	Monitor Pavement
56	High	Swelling	AC Full Depth Patching	AC Full Depth Patching

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
57	Low	Weathering	Monitor Pavement	Monitor Pavement
57	Medium	Weathering	Surface Seal	Monitor Pavement
57	High	Weathering	AC Partial Depth Patching	Surface Seal

Table 5.4.5: PCC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
61	Low	Blow-up	PCC Full Depth Patching	Monitor Pavement
61	Medium	Blow-up	PCC Full Depth Patching	PCC Full Depth Patching
61	High	Blow-up	PCC Slab Replacement	PCC Slab Replacement
62	Low	Corner Break	Monitor Pavement	Monitor Pavement
62	Medium	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
62	High	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
63	Low	Linear Cracking	Monitor Pavement	Monitor Pavement
63	Medium	Linear Cracking	PCC Crack Sealing	PCC Crack Sealing
63	High	Linear Cracking	PCC Full Depth Patching	PCC Crack Sealing
64	Low	Durability Cracking	Monitor Pavement	Monitor Pavement
64	Medium	Durability Cracking	PCC Full Depth Patching	PCC Full Depth Patching
64	High	Durability Cracking	PCC Slab Replacement	PCC Slab Replacement
65	Low	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	Medium	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	High	Jt. Seal Damage	PCC Joint Seal	PCC Joint Seal
66	Low	Small Patch	Monitor Pavement	Monitor Pavement
66	Medium	Small Patch	PCC Partial Depth Patching	Monitor Pavement
66	High	Small Patch	PCC Partial Depth Patching	PCC Partial Depth Patching
67	Low	Large Patch	Monitor Pavement	Monitor Pavement
67	Medium	Large Patch	PCC Full Depth Patching	Monitor Pavement
67	High	Large Patch	PCC Full Depth Patching	PCC Full Depth Patching
68	N/A	Popouts	Monitor Pavement	Monitor Pavement
69	N/A	Pumping	Monitor Pavement	Monitor Pavement
70	Low	Scaling	Monitor Pavement	Monitor Pavement
70	Medium	Scaling	PCC Slab Replacement	Monitor Pavement
70	High	Scaling	PCC Slab Replacement	PCC Slab Replacement
71	Low	Faulting	Monitor Pavement	Monitor Pavement
71	Medium	Faulting	Grinding	Monitor Pavement
71	High	Faulting	PCC Slab Replacement	PCC Slab Replacement
72	Low	Shattered Slab	PCC Crack Sealing	Monitor Pavement
72	Medium	Shattered Slab	PCC Slab Replacement	PCC Crack Sealing
72	High	Shattered Slab	PCC Slab Replacement	PCC Slab Replacement
73	N/A	Shrinkage Cracking	Monitor Pavement	Monitor Pavement

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
74	Low	Joint Spall	Monitor Pavement	Monitor Pavement
74	Medium	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
74	High	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	Low	Corner Spall	Monitor Pavement	Monitor Pavement
75	Medium	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	High	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
76	Low	ASR	Monitor Pavement	Monitor Pavement
76	Medium	ASR	PCC Slab Replacement	PCC Slab Replacement
76	High	ASR	PCC Slab Replacement	PCC Slab Replacement

5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average General Aviation Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation

Rehabilitation Type	General Aviation Pavement Section
AC Reconstruction	
<p style="text-align: center;"><i>Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.</i></p> <p style="text-align: center;">PCI < 55</p>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (6")
	Prime Coat
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
AC Rehabilitation	
<p style="text-align: center;"><i>Combination of asphalt pavement milling and replacement overlay with 15% of the areas subject to full-depth reconstruction.</i></p> <p style="text-align: center;">PCI = 55 to 70</p>	15% AC Reconstruction
	Mill and Overlay
	AC Milling (3")
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
PCC Reconstruction	
<p style="text-align: center;"><i>Full-depth rigid pavement section reconstruction.</i></p> <p style="text-align: center;">PCI < 55</p>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (6")
	Limerock Base Course (6")
	P-501 PCC Pavement (8")
	PCC Joint Seal
PCC Rehabilitation	
<p style="text-align: center;"><i>Rehabilitation of PCC pavement with a combination of crack sealing, joint seal replacement, limited patching, and replacement of 15% of slab panels.</i></p> <p style="text-align: center;">PCI = 55 to 70</p>	15% Slab Replacement
	Joint and Crack Seal
	Limited Patching

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.

Reconstruction (AC or PCC)

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

AC Rehabilitation

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

PCC Rehabilitation

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.


5.5.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.


Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.

Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Asphalt Concrete Cost per SF	Portland Cement Concrete Cost Per SF
Rehabilitation	55 to 70	\$9.00	\$15.00
Reconstruction	0 to 55	\$16.00	\$29.00



Chapter 6: M&R Planning and Budget Scenario Analysis



Chapter 6 – M&R Planning and Budget Scenario Analysis

6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based on the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

Table 6.1 (a) provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (a): Year 1 Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 86,490
Stopgap	\$ 44,830
Planning-Level Localized M&R Needs =	\$ 131,320

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

Table 6.1 (b) summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing	248	LF	\$ 1,000
	Surface Seal	107,332	SF	\$ 80,580
	PCC Joint Seal	654	LF	\$ 2,780
	PCC Partial-Depth Patching	13	SF	\$ 2,130
Localized Stopgap Maintenance	AC Partial-Depth Patching	386	SF	\$ 1,840
	AC Full-Depth Patching	1,236	SF	\$ 12,370
	PCC Crack Sealing	1,103	LF	\$ 7,730
	PCC Joint Seal	3,019	LF	\$ 12,840
	PCC Partial-Depth Patching	59	SF	\$ 10,050

Table 6.1 (c) provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved “End Condition” PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
LEE	RW 4-22	6205	242,833	85	88	\$ 3,670
LEE	RW 4-22	6210	244,205	87	91	\$ 12,830
LEE	RW 13-31	6105	255,000	100	100	\$ -
LEE	RW 13-31	6110	255,000	100	100	\$ -
LEE	RW 13-31	6115	12,500	88	88	\$ -
LEE	RW 13-31	6120	12,500	88	88	\$ -
LEE	RW 13-31	6125	47,500	92	92	\$ -
LEE	RW 13-31	6130	47,500	95	95	\$ -
LEE	TW A	100	77,110	80	83	\$ 2,890
LEE	TW A	105	82,235	87	91	\$ 3,090
LEE	TW A	107	4,534	64	64	\$ -
LEE	TW A	110	113,871	75	84	\$ 34,160
LEE	TW A	115	62,194	83	86	\$ 2,340
LEE	TW A1	120	4,409	56	56	\$ -
LEE	TW A2	130	4,287	63	63	\$ -
LEE	TW A3	140	4,673	54	54	\$ -
LEE	TW A4	150	11,820	83	88	\$ 4,910
LEE	TW B	200	76,570	77	81	\$ 2,880
LEE	TW C	300	25,917	75	78	\$ 1,370
LEE	TW D	400	22,621	55	55	\$ -
LEE	TW E	500	8,617	87	90	\$ 330
LEE	TW J	600	26,600	86	89	\$ 1,000
LEE	TW K	700	138,244	78	85	\$ 12,670

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
LEE	TW K	705	33,012	65	65	\$ -
LEE	TW K	710	23,819	91	94	\$ 900
LEE	TW K	715	4,634	52	52	\$ -
LEE	TL APRON	4305	10,698	29	43	\$ 2,780
LEE	TL SEA	160	42,517	92	92	\$ -
LEE	TL T-HANG	4110	14,559	69	69	\$ -
LEE	TL T-HANG	4115	20,585	69	69	\$ -
LEE	TL T-HANG	4205	45,127	68	68	\$ -
LEE	AP FUEL	4505	25,329	23	35	\$ 11,430
LEE	AP HELI	4405	14,409	100	100	\$ -
LEE	AP N	4105	294,586	100	100	\$ -
LEE	AP N	4120	5,920	57	67	\$ 7,050
LEE	AP N	4125	26,853	100	100	\$ -
LEE	AP N	4130	44,288	93	93	\$ -
LEE	AP N	4135	18,579	27	56	\$ 15,290
LEE	AP N	4140	8,600	12	43	\$ 8,260
LEE	AP N	4145	11,497	94	94	\$ -
LEE	AP N	4150	13,976	100	100	\$ -
LEE	AP N	4155	32,837	100	100	\$ -
LEE	AP RU 13	5205	36,679	78	81	\$ 1,380
LEE	AP RU 31	5305	54,952	85	89	\$ 2,070
LEE	AP RU SEA	5405	18,231	89	89	\$ -

6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section’s PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport’s airfield pavement network. As depicted in **Figures 5.3 (b) and (c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section’s PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport’s pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially

impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT’s goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- » An estimation of current pavement condition;
- » Major pavement rehabilitation needs based on condition and policies; and
- » Planning-level cost estimates for the major rehabilitation needs.


Table 6.2.1 (a) summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.


Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	LEE	TW A	107	AAC	4,534	63	AC Rehabilitation	\$ 41,000
2023	LEE	TW A1	120	AC	4,409	55	AC Rehabilitation	\$ 40,000
2023	LEE	TW A2	130	AC	4,287	62	AC Rehabilitation	\$ 39,000
2023	LEE	TW A3	140	AC	4,673	53	AC Reconstruction	\$ 75,000
2023	LEE	TW D	400	AC	22,621	54	AC Reconstruction	\$ 294,000
2023	LEE	TW K	705	AC	33,012	64	AC Rehabilitation	\$ 298,000
2023	LEE	TW K	715	AC	4,634	52	AC Reconstruction	\$ 75,000
2023	LEE	TL APRON	4305	AC	10,698	27	AC Reconstruction	\$ 172,000
2023	LEE	TL T-HANG	4110	AC	14,559	68	AC Rehabilitation	\$ 132,000
2023	LEE	TL T-HANG	4115	AC	20,585	68	AC Rehabilitation	\$ 186,000
2023	LEE	TL T-HANG	4205	AC	45,127	67	AC Rehabilitation	\$ 407,000
2023	LEE	AP FUEL	4505	AC	25,329	22	AC Reconstruction	\$ 406,000
2023	LEE	AP N	4120	PCC	5,920	56	PCC Rehabilitation	\$ 89,000
2023	LEE	AP N	4135	PCC	18,579	26	PCC Reconstruction	\$ 539,000
2023	LEE	AP N	4140	PCC	8,600	11	PCC Reconstruction	\$ 250,000
2026	LEE	TW A	110	AAC	113,871	69	AC Rehabilitation	\$ 1,187,000
2026	LEE	TW C	300	AC	25,917	69	AC Rehabilitation	\$ 271,000
2027	LEE	TW B	200	AAC	76,570	70	AC Rehabilitation	\$ 838,000
2027	LEE	AP RU 13	5205	AC	36,679	69	AC Rehabilitation	\$ 402,000
2028	LEE	TW K	700	AAC	138,244	69	AC Rehabilitation	\$ 1,589,000
2029	LEE	TW A	100	AC	77,110	70	AC Rehabilitation	\$ 931,000
2030	LEE	RW 4-22	6205	AAC	242,833	69	AC Rehabilitation	\$ 3,076,000
2031	LEE	RW 4-22	6210	AAC	244,205	69	AC Rehabilitation	\$ 3,248,000
2031	LEE	TW A	115	AC	62,194	69	AC Rehabilitation	\$ 828,000
2031	LEE	AP RU 31	5305	AC	54,952	69	AC Rehabilitation	\$ 731,000
2032	LEE	TW J	600	AAC	26,600	70	AC Rehabilitation	\$ 372,000
2032	LEE	AP RU SEA	5405	AC	18,231	70	AC Rehabilitation	\$ 255,000

Figure 6.2.1 (a) summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year





TW A1:120 2023 AC REHAB \$0.04 M	TW A2:130 2023 AC REHAB \$0.04 M	TW A3:140 2023 AC RECON \$0.08 M
TL T-HANG:4110 2023 AC REHAB \$0.13 M	TL T-HANG:4115 2023 AC REHAB \$0.19 M	AP FUEL:4505 2023 AC RECON \$0.41 M

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

	2023		2028
	2024		2029
	2025		2030
	2026		2031
	2027		2032

"BRANCH," "SECTION"
"YEAR," "REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





Chapter 7: Conclusion



Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- » Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in **Section 6.1**;
- » Further refine and implement the identified 10-year major rehabilitation needs provided in **Section 6.2**;
- » Maintain detailed records on pavement maintenance, construction, and inspection; and
- » Maintain records on major pavement construction projects (year, scope, cost, and construction documents).

7.2 Supporting Documents

Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport’s adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. “Vicinity” photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.

7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- » ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- » AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- » AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- » AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- » Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- » Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- » Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.



Appendix A: Airfield Pavement Analysis



Table A.1: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
LEE	RW 4-22	Runway	6205	242,833	AAC	1/1/2011
LEE	RW 4-22	Runway	6210	244,205	AAC	1/1/2011
LEE	RW 13-31	Runway	6105	255,000	AAC	1/1/2021
LEE	RW 13-31	Runway	6110	255,000	AAC	1/1/2021
LEE	RW 13-31	Runway	6115	12,500	AC	12/12/2009
LEE	RW 13-31	Runway	6120	12,500	AC	12/12/2009
LEE	RW 13-31	Runway	6125	47,500	AC	1/1/2009
LEE	RW 13-31	Runway	6130	47,500	AC	1/1/2009
LEE	TW A	Taxiway	100	77,110	AC	1/1/2009
LEE	TW A	Taxiway	105	82,235	AC	1/1/2014
LEE	TW A	Taxiway	107	4,534	AAC	1/1/2002
LEE	TW A	Taxiway	110	113,871	AAC	1/1/2000
LEE	TW A	Taxiway	115	62,194	AC	1/1/2009
LEE	TW A1	Taxiway	120	4,409	AC	1/1/1989
LEE	TW A2	Taxiway	130	4,287	AC	1/1/1989
LEE	TW A3	Taxiway	140	4,673	AC	1/1/1989
LEE	TW A4	Taxiway	150	11,820	PCC	1/1/2008
LEE	TW B	Taxiway	200	76,570	AAC	1/1/2011
LEE	TW C	Taxiway	300	25,917	AC	1/1/2009
LEE	TW D	Taxiway	400	22,621	AC	1/1/2002
LEE	TW E	Taxiway	500	8,617	AC	1/1/2011
LEE	TW J	Taxiway	600	26,600	AAC	1/1/2011
LEE	TW K	Taxiway	700	138,244	AAC	1/1/2011
LEE	TW K	Taxiway	705	33,012	AC	1/1/2004
LEE	TW K	Taxiway	710	23,819	AC	1/1/2014
LEE	TW K	Taxiway	715	4,634	AC	1/1/1986
LEE	TL APRON	Taxilane	4305	10,698	AC	1/1/1982
LEE	TL SEA	Taxilane	160	42,517	AC	1/1/2019
LEE	TL T-HANG	Taxilane	4110	14,559	AC	12/25/2000
LEE	TL T-HANG	Taxilane	4115	20,585	AC	12/25/2000
LEE	TL T-HANG	Taxilane	4205	45,127	AC	1/1/2003
LEE	AP FUEL	Apron	4505	25,329	AC	1/1/1989
LEE	AP HELI	Apron	4405	14,409	PCC	4/1/2022
LEE	AP N	Apron	4105	294,586	AAC	4/1/2022
LEE	AP N	Apron	4120	5,920	PCC	12/25/2000
LEE	AP N	Apron	4125	26,853	AAC	4/1/2022
LEE	AP N	Apron	4130	44,288	PCC	1/1/2008
LEE	AP N	Apron	4135	18,579	PCC	1/1/1942
LEE	AP N	Apron	4140	8,600	PCC	1/1/1942
LEE	AP N	Apron	4145	11,497	AC	7/1/2016
LEE	AP N	Apron	4150	13,976	AC	4/1/2022
LEE	AP N	Apron	4155	32,837	AC	4/1/2022
LEE	AP RU 13	Apron	5205	36,679	AC	1/1/2008
LEE	AP RU 31	Apron	5305	54,952	AC	1/1/2009

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
LEE	AP RU SEA	Apron	5405	18,231	AC	1/1/2019

Table A.2: Pavement Condition Index Summary (Current PCI Survey) – Section Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
LEE	RW 4-22	Runway	6205	242,833	85	Satisfactory
LEE	RW 4-22	Runway	6210	244,205	87	Good
LEE	RW 13-31	Runway	6105	255,000	100	Good
LEE	RW 13-31	Runway	6110	255,000	100	Good
LEE	RW 13-31	Runway	6115	12,500	88	Good
LEE	RW 13-31	Runway	6120	12,500	88	Good
LEE	RW 13-31	Runway	6125	47,500	92	Good
LEE	RW 13-31	Runway	6130	47,500	95	Good
LEE	TW A	Taxiway	100	77,110	80	Satisfactory
LEE	TW A	Taxiway	105	82,235	87	Good
LEE	TW A	Taxiway	107	4,534	64	Fair
LEE	TW A	Taxiway	110	113,871	75	Satisfactory
LEE	TW A	Taxiway	115	62,194	83	Satisfactory
LEE	TW A1	Taxiway	120	4,409	56	Fair
LEE	TW A2	Taxiway	130	4,287	63	Fair
LEE	TW A3	Taxiway	140	4,673	54	Poor
LEE	TW A4	Taxiway	150	11,820	83	Satisfactory
LEE	TW B	Taxiway	200	76,570	77	Satisfactory
LEE	TW C	Taxiway	300	25,917	75	Satisfactory
LEE	TW D	Taxiway	400	22,621	55	Poor
LEE	TW E	Taxiway	500	8,617	87	Good
LEE	TW J	Taxiway	600	26,600	86	Good
LEE	TW K	Taxiway	700	138,244	78	Satisfactory
LEE	TW K	Taxiway	705	33,012	65	Fair
LEE	TW K	Taxiway	710	23,819	91	Good
LEE	TW K	Taxiway	715	4,634	52	Poor
LEE	TL APRON	Taxilane	4305	10,698	29	Very Poor
LEE	TL SEA	Taxilane	160	42,517	92	Good
LEE	TL T-HANG	Taxilane	4110	14,559	69	Fair
LEE	TL T-HANG	Taxilane	4115	20,585	69	Fair
LEE	TL T-HANG	Taxilane	4205	45,127	68	Fair
LEE	AP FUEL	Apron	4505	25,329	23	Serious
LEE	AP HELI	Apron	4405	14,409	100	Good
LEE	AP N	Apron	4105	294,586	100	Good
LEE	AP N	Apron	4120	5,920	57	Fair
LEE	AP N	Apron	4125	26,853	100	Good
LEE	AP N	Apron	4130	44,288	93	Good
LEE	AP N	Apron	4135	18,579	27	Very Poor
LEE	AP N	Apron	4140	8,600	12	Serious
LEE	AP N	Apron	4145	11,497	94	Good
LEE	AP N	Apron	4150	13,976	100	Good
LEE	AP N	Apron	4155	32,837	100	Good
LEE	AP RU 13	Apron	5205	36,679	78	Satisfactory
LEE	AP RU 31	Apron	5305	54,952	85	Satisfactory
LEE	AP RU SEA	Apron	5405	18,231	89	Good

Table A.3: Forecasted PCI Values 2023-2032 – Section-Level

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
LEE	RW 4-22	6205	85	83	81	79	77	75	73	71	69	67	65
LEE	RW 4-22	6210	87	85	83	81	79	77	75	73	71	69	67
LEE	RW 13-31	6105	100	95	93	91	89	87	85	84	82	80	78
LEE	RW 13-31	6110	100	95	93	91	89	87	85	84	82	80	78
LEE	RW 13-31	6115	88	86	84	82	81	79	77	76	74	72	71
LEE	RW 13-31	6120	88	86	84	82	81	79	77	76	74	72	71
LEE	RW 13-31	6125	92	90	88	86	85	83	81	80	78	76	75
LEE	RW 13-31	6130	95	93	91	90	88	86	84	83	81	79	77
LEE	TW A	100	80	78	77	75	74	72	71	70	69	67	66
LEE	TW A	105	87	85	83	81	79	78	76	75	73	72	71
LEE	TW A	107	64	63	61	60	59	57	56	54	53	51	49
LEE	TW A	110	75	73	72	71	69	68	67	66	64	63	62
LEE	TW A	115	83	81	79	78	76	75	73	72	71	69	68
LEE	TW A1	120	56	55	55	54	54	53	53	53	52	52	51
LEE	TW A2	130	63	62	61	60	60	59	58	58	57	57	56
LEE	TW A3	140	54	53	53	53	52	52	51	51	50	50	50
LEE	TW A4	150	83	82	81	81	80	79	78	78	77	76	75
LEE	TW B	200	77	75	74	72	71	70	69	67	66	65	64
LEE	TW C	300	75	73	72	71	69	68	67	66	65	64	63
LEE	TW D	400	55	54	54	54	53	53	52	52	51	51	50
LEE	TW E	500	87	85	83	81	79	78	76	75	73	72	71
LEE	TW J	600	86	84	82	80	78	77	75	74	73	71	70
LEE	TW K	700	78	76	75	73	72	71	69	68	67	66	64
LEE	TW K	705	65	64	63	62	61	61	60	59	58	58	57
LEE	TW K	710	91	89	87	85	83	81	79	78	76	75	73
LEE	TW K	715	52	52	51	51	50	50	49	49	48	48	47
LEE	TL APRON	4305	29	27	26	24	23	21	19	17	15	13	12
LEE	TL SEA	160	92	89	87	85	84	82	80	78	77	75	74
LEE	TL T-HANG	4110	69	68	67	66	65	64	63	62	61	60	60
LEE	TL T-HANG	4115	69	68	67	66	65	64	63	62	61	60	60
LEE	TL T-HANG	4205	68	67	66	65	64	63	62	61	60	60	59
LEE	AP FUEL	4505	23	22	21	21	20	19	18	17	17	16	15
LEE	AP HELI	4405	100	99	98	97	96	95	94	93	92	91	90
LEE	AP N	4105	100	98	96	94	92	90	88	86	84	82	80
LEE	AP N	4120	57	56	55	54	53	52	51	50	49	48	47
LEE	AP N	4125	100	98	96	94	92	90	88	86	84	82	80
LEE	AP N	4130	93	92	91	90	89	88	87	86	85	84	83
LEE	AP N	4135	27	26	25	24	23	22	21	20	19	18	17
LEE	AP N	4140	12	11	10	9	8	7	6	5	4	3	2
LEE	AP N	4145	94	91	89	87	85	83	81	79	77	75	73
LEE	AP N	4150	100	97	94	92	90	88	85	83	81	79	78
LEE	AP N	4155	100	97	94	92	90	88	85	83	81	79	78
LEE	AP RU 13	5205	78	76	74	72	71	69	68	66	65	64	62
LEE	AP RU 31	5305	85	83	81	79	77	75	73	72	70	69	67

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
LEE	AP RU SEA	5405	89	86	84	82	80	78	77	75	73	72	70

11/17/2022

Work History Report

Page 1 of 8

Pavement Database: FDOT

Network: LEESBURG INTERN Branch: AP FUEL FUELING APRO Section: 4505 Surface: AC						
L.C.D. 1/1/1989 Use: APRON Rank: P Length: 200.00 (Ft) Width: 100.00 (Ft) True Area: 25329.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1989	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: AP HELI HELICOPTER AP Section: 4405 Surface: PCC						
L.C.D. 4/1/2022 Use: APRON Rank: P Length: 240.00 (Ft) Width: 240.00 (Ft) True Area: 14409.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
4/1/2022	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	8" P-501, P-152 Stabilized Subgrade

Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4105 Surface: AAC						
L.C.D. 4/1/2022 Use: APRON Rank: P Length: 1,393.00 (Ft) Width: 248.00 (Ft) True Area: 294586.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
4/1/2022	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Mill of Existing AC, 4" P-401 Overlay
1/1/2007	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	UNKNOWN SEAL COAT
1/1/1989	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1989 AC PAVEMENT

Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4120 Surface: PCC						
L.C.D. 12/25/2000 Use: APRON Rank: P Length: 120.00 (Ft) Width: 60.00 (Ft) True Area: 5920.000001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/2000	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4125 Surface: AAC						
L.C.D. 4/1/2022 Use: APRON Rank: P Length: 313.00 (Ft) Width: 105.00 (Ft) True Area: 26853.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
4/1/2022	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Mill of Existing AC, 4" P-401 Overlay
1/1/2005	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4130 Surface: PCC						
L.C.D. 1/1/2008 Use: APRON Rank: P Length: 260.00 (Ft) Width: 160.00 (Ft) True Area: 44288.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	NU-IN	New Construction - Initial	0.00	11.00	<input checked="" type="checkbox"/>	11" P-501, 4" P-211, COMPACTED S

Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4135 Surface: PCC						
L.C.D. 1/1/1942 Use: APRON Rank: P Length: 260.00 (Ft) Width: 50.00 (Ft) True Area: 18579.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1942 PCC PAVEMENT

Pavement Database: FDOT

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4140 Surface: PCC L.C.D. 1/1/1942 Use: APRON Rank: P Length: 66.00 (Ft) Width: 200.00 (Ft) True Area: 8600.000002 (SqFt)						
1/1/1942	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1942 PCC PAVEMENT
Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4145 Surface: AC L.C.D. 7/1/2016 Use: APRON Rank: P Length: 138.00 (Ft) Width: 94.00 (Ft) True Area: 11497.000000 (SqFt)						
7/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4150 Surface: AC L.C.D. 4/1/2022 Use: APRON Rank: P Length: 188.00 (Ft) Width: 105.00 (Ft) True Area: 13976.000000 (SqFt)						
4/1/2022	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 4" P-211, P-152 Stabilized S
1/1/2007	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	UNKNOWN SEAL COAT
1/1/1989	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1989 AC PAVEMENT
Network: LEESBURG INTERN Branch: AP N NORTH APRON Section: 4155 Surface: AC L.C.D. 4/1/2022 Use: APRON Rank: P Length: 220.00 (Ft) Width: 130.00 (Ft) True Area: 32837.000001 (SqFt)						
4/1/2022	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 4" P-211, P-152 Stabilized S
1/1/2005	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	
Network: LEESBURG INTERN Branch: AP RU 13 RUN-UP APRON Section: 5205 Surface: AC L.C.D. 1/1/2008 Use: APRON Rank: P Length: 235.00 (Ft) Width: 175.00 (Ft) True Area: 36679.000001 (SqFt)						
1/1/2008	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	UNKNOWN AC CONST.
Network: LEESBURG INTERN Branch: AP RU 31 RUN-UP APRON Section: 5305 Surface: AC L.C.D. 1/1/2009 Use: APRON Rank: P Length: 410.00 (Ft) Width: 160.00 (Ft) True Area: 54952.000001 (SqFt)						
1/1/2009	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, COMPACTED S
Network: LEESBURG INTERN Branch: AP RU SEA RUN-UP APRON Section: 5405 Surface: AC L.C.D. 1/1/2019 Use: APRON Rank: P Length: 180.00 (Ft) Width: 100.00 (Ft) True Area: 18231.000000 (SqFt)						
1/1/2019	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Pavement Database: FDOT

Network: LEESBURG INTERN Branch: RW 13-31 RUNWAY 13-31 Section: 6105 Surface: AAC						
L.C.D. 1/1/2021 Use: RUNWAY Rank: P Length: 5,100.00 (Ft) Width: 50.00 (Ft) True Area: 255000.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1" Mill, Variable P-403, 2" P-401
1/1/2000	OL-AS	Overlay - AC Structural	0.00	2.00	<input checked="" type="checkbox"/>	2" OL P-401
1/1/1980	OL-AS	Overlay - AC Structural	0.00	6.00	<input checked="" type="checkbox"/>	1980: 1.5" TYPE S-1 AC AND VARI
1/1/1942	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: RW 13-31 RUNWAY 13-31 Section: 6110 Surface: AAC						
L.C.D. 1/1/2021 Use: RUNWAY Rank: P Length: 5,100.00 (Ft) Width: 50.00 (Ft) True Area: 255000.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2021	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1" Mill, Variable P-403, 2" P-401
1/1/2000	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	2" OL P-401
1/1/1980	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1980: 1.5" TYPE S-1 AC AND VARI
1/1/1942	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1942: EST CONSTRUCTION

Network: LEESBURG INTERN Branch: RW 13-31 RUNWAY 13-31 Section: 6115 Surface: AC						
L.C.D. 12/12/200 Use: RUNWAY Rank: P Length: 250.00 (Ft) Width: 50.00 (Ft) True Area: 12500.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	P-632 Rejuvenator
12/12/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	NEW CONSTRUCTION BETWEEN

Network: LEESBURG INTERN Branch: RW 13-31 RUNWAY 13-31 Section: 6120 Surface: AC						
L.C.D. 12/12/200 Use: RUNWAY Rank: P Length: 250.00 (Ft) Width: 50.00 (Ft) True Area: 12500.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	P-632 Rejuvenator
12/12/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	CONSTRUCTION ESTIMATE BET

Network: LEESBURG INTERN Branch: RW 13-31 RUNWAY 13-31 Section: 6125 Surface: AC						
L.C.D. 1/1/2009 Use: RUNWAY Rank: P Length: 950.00 (Ft) Width: 50.00 (Ft) True Area: 47500.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	P-632 Rejuvenator
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211

Network: LEESBURG INTERN Branch: RW 13-31 RUNWAY 13-31 Section: 6130 Surface: AC						
L.C.D. 1/1/2009 Use: RUNWAY Rank: P Length: 950.00 (Ft) Width: 50.00 (Ft) True Area: 47500.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	P-632 Rejuvenator
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211

Pavement Database: FDOT

Network: LEESBURG INTERN Branch: RW 4-22 RUNWAY 4-22 Section: 6205 Surface: AAC						
L.C.D. 1/1/2011 Use: RUNWAY Rank: P Length: 3,900.00 (Ft) Width: 75.00 (Ft) True Area: 242833.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	JANUARY 2011 OVERLAY
1/1/1983	CR-AC	Complete Reconstruction - AC	0.00	1.25	<input checked="" type="checkbox"/>	1983: 1.25" TYPE S-1 AC AND VAR
1/1/1942	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1942 EST CONST

Network: LEESBURG INTERN Branch: RW 4-22 RUNWAY 4-22 Section: 6210 Surface: AAC						
L.C.D. 1/1/2011 Use: RUNWAY Rank: P Length: 4,857.00 (Ft) Width: 25.00 (Ft) True Area: 244205.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	JANUARY 2011 OVERLAY
1/1/1983	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1983: 1.25" TYPE S-1 AC AND VAR
1/1/1942	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1942: EST CONST

Network: LEESBURG INTERN Branch: TL APRON APRON TAXILA Section: 4305 Surface: AC						
L.C.D. 1/1/1982 Use: TAXILAN Rank: P Length: 300.00 (Ft) Width: 35.00 (Ft) True Area: 10698.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2018	PA-AC	Patching - AC	0.00	0.00	<input type="checkbox"/>	
1/1/2018	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1982	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: TL SEA SEAPLANE BAS Section: 160 Surface: AC						
L.C.D. 1/1/2019 Use: TAXILAN Rank: P Length: 750.00 (Ft) Width: 40.00 (Ft) True Area: 42517.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: TL T-HANG T-HANGAR TAX Section: 4110 Surface: AC						
L.C.D. 12/25/200 Use: TAXILAN Rank: P Length: 300.00 (Ft) Width: 30.00 (Ft) True Area: 14559.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/2000	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: TL T-HANG T-HANGAR TAX Section: 4115 Surface: AC						
L.C.D. 12/25/200 Use: TAXILAN Rank: P Length: 300.00 (Ft) Width: 30.00 (Ft) True Area: 20585.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/2000	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: TL T-HANG T-HANGAR TAX Section: 4205 Surface: AC						
L.C.D. 1/1/2003 Use: TAXILAN Rank: P Length: 1,500.00 (Ft) Width: 25.00 (Ft) True Area: 45127.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Pavement Database: FDOT

Network: LEESBURG INTERN Branch: TW A TAXIWAY A Section: 100 Surface: AC						
L.C.D. 1/1/2009 Use: TAXIWAY Rank: P Length: 1,400.00 (Ft) Width: 50.00 (Ft) True Area: 77110.00002 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2009: 4" P-401, 6" P-211

Network: LEESBURG INTERN Branch: TW A TAXIWAY A Section: 105 Surface: AC						
L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 1,460.00 (Ft) Width: 50.00 (Ft) True Area: 82235.00002 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	2014: 4" P-401, 6" P-211

Network: LEESBURG INTERN Branch: TW A TAXIWAY A Section: 107 Surface: AAC						
L.C.D. 1/1/2002 Use: TAXIWAY Rank: P Length: 91.00 (Ft) Width: 50.00 (Ft) True Area: 4534.000001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	ML-OVL	Mill and Overlay	0.00	2.00	<input checked="" type="checkbox"/>	2002: 2" MILL AND OVERLAY
1/1/1982	ML-OVL	Mill and Overlay	0.00	1.50	<input checked="" type="checkbox"/>	1.5" TYPE S-1 AC AND VARIABLE
12/25/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATED CONST. DATE

Network: LEESBURG INTERN Branch: TW A TAXIWAY A Section: 110 Surface: AAC						
L.C.D. 1/1/2000 Use: TAXIWAY Rank: P Length: 3,790.00 (Ft) Width: 50.00 (Ft) True Area: 113871.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	OL-AS	Overlay - AC Structural	0.00	2.00	<input checked="" type="checkbox"/>	2" OVERLAY P-401
1/1/1982	CR-AC	Complete Reconstruction - AC	0.00	1.50	<input checked="" type="checkbox"/>	1982: 1.5" TYPE S-1 AC AND VARI
1/1/1942	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1942: EST. CONST

Network: LEESBURG INTERN Branch: TW A1 TAXIWAY A1 Section: 120 Surface: AC						
L.C.D. 1/1/1989 Use: TAXIWAY Rank: P Length: 80.00 (Ft) Width: 50.00 (Ft) True Area: 4409.000001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1989	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1989 AC PAVEMENT (SAME AS RAMP)

Network: LEESBURG INTERN Branch: TW A TAXIWAY A Section: 115 Surface: AC						
L.C.D. 1/1/2009 Use: TAXIWAY Rank: P Length: 1,400.00 (Ft) Width: 50.00 (Ft) True Area: 62194.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2009: NEW CONST

Network: LEESBURG INTERN Branch: TW A2 TAXIWAY A2 Section: 130 Surface: AC						
L.C.D. 1/1/1989 Use: TAXIWAY Rank: P Length: 80.00 (Ft) Width: 40.00 (Ft) True Area: 4287.000001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1989	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1989 AC PAVEMENT

Pavement Database: FDOT

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1989	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	EST 1989 AC (SAME AS RAMP)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	NU-IN	New Construction - Initial	0.00	11.00	<input checked="" type="checkbox"/>	11" P-501, 4" P-211, COMPACTED S

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	1983: 1.25" TYPE S-1 AC AND VAR
1/1/1983	NC-AC	New Construction - AC	0.00	1.25	<input checked="" type="checkbox"/>	

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2009	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	2009: 4" P-401, 6" P-211

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2002	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	2002: 4" P-401, 6" P-211, 12" P-152 (

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2011: UNKNOWN PVMT SECTION

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	OVERLAY - DETAILS UNKNOWN
1/1/1982	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1982: 1.5" TYPE S-1 AC ON 8" P-21

11/17/2022

Work History Report

Page 7 of 8

Pavement Database: FDOT

Network: LEESBURG INTERN Branch: TW K TAXIWAY K Section: 700 Surface: AAC						
L.C.D. 1/1/2011 Use: TAXIWAY Rank: P Length: 3,950.00 (Ft) Width: 35.00 (Ft) True Area: 138244.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2011	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2011: UNKNOWN OVERLAY
1/1/1986	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1986: 1.5" AC ON 8" LIME ROCK. SOIL: SP.

Network: LEESBURG INTERN Branch: TW K TAXIWAY K Section: 705 Surface: AC						
L.C.D. 1/1/2004 Use: TAXIWAY Rank: P Length: 800.00 (Ft) Width: 60.00 (Ft) True Area: 33012.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2004	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: LEESBURG INTERN Branch: TW K TAXIWAY K Section: 710 Surface: AC						
L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 325.00 (Ft) Width: 70.00 (Ft) True Area: 23819.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	NU-IN	New Construction - Initial	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-211, COMPACTED SU

Network: LEESBURG INTERN Branch: TW K TAXIWAY K Section: 715 Surface: AC						
L.C.D. 1/1/1986 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 35.00 (Ft) True Area: 4634.000001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1986	NC-AC	New Construction - AC	0.00	1.50	<input checked="" type="checkbox"/>	1986: 1.5" AC ON 8" LIME ROCK. S

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	8	487,354.00	0.19	0.50
Complete Reconstruction - AC	4	403,517.00	0.69	0.69
Mill and Overlay	8	1,005,351.00	0.44	0.77
New Construction - AC	14	1,383,660.00	0.20	0.48
New Construction - Initial	22	697,004.00	1.91	3.32
New Construction - PCC	1	14,409.00	0.00	0.00
Overlay - AC Structural	9	1,941,684.00	1.11	1.91
Patching - AC	1	10,698.00	0.00	0.00
Surface Treatment - Seal Coat	7	439,260.00	0.00	0.00

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP FUEL	1	200.00	100.00	25,329.00	APRON	23.00	0.00	23.00
AP HELI	1	240.00	240.00	14,409.00	APRON	100.00	0.00	100.00
AP N	9	2,958.00	128.00	457,136.00	APRON	75.89	32.96	93.99
AP RU 13	1	235.00	175.00	36,679.00	APRON	78.00	0.00	78.00
AP RU 31	1	410.00	160.00	54,952.00	APRON	85.00	0.00	85.00
AP RU SEA	1	180.00	100.00	18,231.00	APRON	89.00	0.00	89.00
RW 13-31	6	12,600.00	50.00	630,000.00	RUNWAY	93.83	4.98	98.54
RW 4-22	2	8,757.00	50.00	487,038.00	RUNWAY	86.00	1.00	86.00
TL APRON	1	300.00	35.00	10,698.00	TAXILANE	29.00	0.00	29.00
TL SEA	1	750.00	40.00	42,517.00	TAXILANE	92.00	0.00	92.00
TL T-HANG	3	2,100.00	28.33	80,271.00	TAXILANE	68.67	0.47	68.44
TW A	5	8,141.00	50.00	339,944.00	TAXIWAY	77.80	7.93	80.35
TW A1	1	80.00	50.00	4,409.00	TAXIWAY	56.00	0.00	56.00
TW A2	1	80.00	40.00	4,287.00	TAXIWAY	63.00	0.00	63.00
TW A3	1	80.00	30.00	4,673.00	TAXIWAY	54.00	0.00	54.00
TW A4	1	98.00	75.00	11,820.00	TAXIWAY	83.00	0.00	83.00
TW B	1	1,040.00	40.00	76,570.00	TAXIWAY	77.00	0.00	77.00
TW C	1	320.00	80.00	25,917.00	TAXIWAY	75.00	0.00	75.00
TW D	1	450.00	55.00	22,621.00	TAXIWAY	55.00	0.00	55.00
TW E	1	200.00	45.00	8,617.00	TAXIWAY	87.00	0.00	87.00
TW J	1	430.00	40.00	26,600.00	TAXIWAY	86.00	0.00	86.00
TW K	4	5,175.00	50.00	199,709.00	TAXIWAY	71.50	14.53	76.80

Pavement Database: FDOT

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	14	606,736.00	75.57	30.95	89.24
RUNWAY	8	1,117,038.00	91.88	5.51	93.08
TAXILANE	5	133,486.00	65.40	20.32	72.78
TAXIWAY	18	725,167.00	72.83	12.57	77.95
ALL	45	2,582,427.00	76.24	21.77	86.88

Pavement Database: FDOT

NetworkId: LEE

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP FUEL	4505	1/1/1989	AC	APRON	P	0	25,329.00	4/26/2022	33	23
AP HELI	4405	4/1/2022	PCC	APRON	P	0	14,409.00	4/1/2022	0	100
AP N	4105	4/1/2022	AAC	APRON	P	0	294,586.00	4/1/2022	0	100
AP N	4120	12/25/2000	PCC	APRON	P	0	5,920.00	4/26/2022	22	57
AP N	4125	4/1/2022	AAC	APRON	P	0	26,853.00	4/1/2022	0	100
AP N	4130	1/1/2008	PCC	APRON	P	0	44,288.00	4/26/2022	14	93
AP N	4135	1/1/1942	PCC	APRON	P	0	18,579.00	4/26/2022	80	27
AP N	4140	1/1/1942	PCC	APRON	P	0	8,600.00	4/26/2022	80	12
AP N	4145	7/1/2016	AC	APRON	P	0	11,497.00	4/26/2022	6	94
AP N	4150	4/1/2022	AC	APRON	P	0	13,976.00	4/1/2022	0	100
AP N	4155	4/1/2022	AC	APRON	P	0	32,837.00	4/1/2022	0	100
AP RU 13	5205	1/1/2008	AC	APRON	P	0	36,679.00	4/26/2022	14	78
AP RU 31	5305	1/1/2009	AC	APRON	P	0	54,952.00	4/26/2022	13	85
AP RU SEA	5405	1/1/2019	AC	APRON	P	0	18,231.00	4/26/2022	3	89
RW 13-31	6105	1/1/2021	AAC	RUNWAY	P	0	255,000.00	1/1/2021	0	100
RW 13-31	6110	1/1/2021	AAC	RUNWAY	P	0	255,000.00	1/1/2021	0	100
RW 13-31	6115	12/12/2009	AC	RUNWAY	P	0	12,500.00	4/26/2022	13	88
RW 13-31	6120	12/12/2009	AC	RUNWAY	P	0	12,500.00	4/26/2022	13	88
RW 13-31	6125	1/1/2009	AC	RUNWAY	P	0	47,500.00	4/26/2022	13	92
RW 13-31	6130	1/1/2009	AC	RUNWAY	P	0	47,500.00	4/26/2022	13	95
RW 4-22	6205	1/1/2011	AAC	RUNWAY	P	0	242,833.00	4/26/2022	11	85
RW 4-22	6210	1/1/2011	AAC	RUNWAY	P	0	244,205.00	4/26/2022	11	87
TL APRON	4305	1/1/1982	AC	TAXILANE	P	0	10,698.00	4/26/2022	40	29
TL SEA	160	1/1/2019	AC	TAXILANE	P	0	42,517.00	4/26/2022	3	92
TL T-HANG	4110	12/25/2000	AC	TAXILANE	P	0	14,559.00	4/26/2022	22	69
TL T-HANG	4115	12/25/2000	AC	TAXILANE	P	0	20,585.00	4/26/2022	22	69
TL T-HANG	4205	1/1/2003	AC	TAXILANE	P	0	45,127.00	4/26/2022	19	68
TW A	100	1/1/2009	AC	TAXIWAY	P	0	77,110.00	4/26/2022	13	80
TW A	105	1/1/2014	AC	TAXIWAY	P	0	82,235.00	4/26/2022	8	87
TW A	107	1/1/2002	AAC	TAXIWAY	P	0	4,534.00	4/26/2022	20	64
TW A	110	1/1/2000	AAC	TAXIWAY	P	0	113,871.00	4/26/2022	22	75
TW A	115	1/1/2009	AC	TAXIWAY	P	0	62,194.00	4/26/2022	13	83
TW A1	120	1/1/1989	AC	TAXIWAY	P	0	4,409.00	4/26/2022	33	56
TW A2	130	1/1/1989	AC	TAXIWAY	P	0	4,287.00	4/26/2022	33	63
TW A3	140	1/1/1989	AC	TAXIWAY	P	0	4,673.00	4/26/2022	33	54
TW A4	150	1/1/2008	PCC	TAXIWAY	P	0	11,820.00	4/26/2022	14	83
TW B	200	1/1/2011	AAC	TAXIWAY	P	0	76,570.00	4/26/2022	11	77
TW C	300	1/1/2009	AC	TAXIWAY	P	0	25,917.00	4/26/2022	13	75
TW D	400	1/1/2002	AC	TAXIWAY	P	0	22,621.00	4/26/2022	20	55
TW E	500	1/1/2011	AC	TAXIWAY	P	0	8,617.00	4/26/2022	11	87
TW J	600	1/1/2011	AAC	TAXIWAY	P	0	26,600.00	4/26/2022	11	86
TW K	700	1/1/2011	AAC	TAXIWAY	P	0	138,244.00	4/26/2022	11	78
TW K	705	1/1/2004	AC	TAXIWAY	P	0	33,012.00	4/26/2022	18	65
TW K	710	1/1/2014	AC	TAXIWAY	P	0	23,819.00	4/26/2022	8	91
TW K	715	1/1/1986	AC	TAXIWAY	P	0	4,634.00	4/26/2022	36	52

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		892,661.00	7	100.00	0.00	100.00
03-05	3	60,748.00	2	90.50	1.50	91.10
06-10	7	117,551.00	3	90.67	2.87	88.50
11-15	12	1,170,029.00	17	84.71	5.60	84.26
16-20	19	105,294.00	4	63.00	4.85	64.09
21-25	22	154,935.00	4	67.50	6.54	72.95
31-35	33	38,698.00	4	49.00	15.38	34.93
36-40	38	15,332.00	2	40.50	11.50	35.95
50+	80	27,179.00	2	19.50	7.50	22.25
ALL	17	2,582,427.00	45	76.24	21.77	86.88



Appendix B: Maintenance and Rehabilitation Planning Needs



Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
LEE	RW 4-22	6205	RAVELING	Low	3,011	SF	1.2%	Preventive	Surface Seal	3,011	SF	\$ 0.75	\$ 2,260
LEE	RW 4-22	6205	WEATHERING	Medium	1,870	SF	0.8%	Preventive	Surface Seal	1,870	SF	\$ 0.75	\$ 1,410
LEE	RW 4-22	6210	RAVELING	Low	17,094	SF	7.0%	Preventive	Surface Seal	17,094	SF	\$ 0.75	\$ 12,830
LEE	TW A	100	WEATHERING	Medium	3,853	SF	5.0%	Preventive	Surface Seal	3,852	SF	\$ 0.75	\$ 2,890
LEE	TW A	105	WEATHERING	Medium	4,112	SF	5.0%	Preventive	Surface Seal	4,112	SF	\$ 0.75	\$ 3,090
LEE	TW A	110	WEATHERING	Medium	45,545	SF	40.0%	Preventive	Surface Seal	45,545	SF	\$ 0.75	\$ 34,160
LEE	TW A	115	WEATHERING	Medium	3,107	SF	5.0%	Preventive	Surface Seal	3,107	SF	\$ 0.75	\$ 2,340
LEE	TW A4	150	JT SEAL DMG	Low	37	Slabs	100.0%	Preventive	PCC Joint Seal	654	LF	\$ 4.25	\$ 2,780
LEE	TW A4	150	JOINT SPALL	Medium	2	Slabs	5.3%	Preventive	PCC Partial-Depth Patching	13	SF	\$ 169.00	\$ 2,130
LEE	TW B	200	WEATHERING	Medium	3,831	SF	5.0%	Preventive	Surface Seal	3,831	SF	\$ 0.75	\$ 2,880
LEE	TW C	300	L & T CR	Medium	114	LF	0.4%	Preventive	AC Crack Sealing	115	LF	\$ 4.00	\$ 460
LEE	TW C	300	WEATHERING	Medium	1,204	SF	4.7%	Preventive	Surface Seal	1,205	SF	\$ 0.75	\$ 910
LEE	TW E	500	WEATHERING	Medium	431	SF	5.0%	Preventive	Surface Seal	431	SF	\$ 0.75	\$ 330
LEE	TW J	600	WEATHERING	Medium	1,330	SF	5.0%	Preventive	Surface Seal	1,330	SF	\$ 0.75	\$ 1,000
LEE	TW K	700	L & T CR	Medium	134	LF	0.1%	Preventive	AC Crack Sealing	134	LF	\$ 4.00	\$ 540
LEE	TW K	700	WEATHERING	Medium	16,170	SF	11.7%	Preventive	Surface Seal	16,171	SF	\$ 0.75	\$ 12,130
LEE	TW K	710	WEATHERING	Medium	1,189	SF	5.0%	Preventive	Surface Seal	1,188	SF	\$ 0.75	\$ 900
LEE	AP RU 13	5205	WEATHERING	Medium	1,839	SF	5.0%	Preventive	Surface Seal	1,839	SF	\$ 0.75	\$ 1,380
LEE	AP RU 31	5305	WEATHERING	Medium	2,748	SF	5.0%	Preventive	Surface Seal	2,748	SF	\$ 0.75	\$ 2,070
LEE	TL APRON	4305	ALLIGATOR CR	Medium	139	SF	1.3%	Stopgap	AC Full-Depth Patching	189	SF	\$ 10.00	\$ 1,900
LEE	TL APRON	4305	DEPRESSION	High	54	SF	0.5%	Stopgap	AC Full-Depth Patching	87	SF	\$ 10.00	\$ 880
LEE	AP FUEL	4505	PATCHING	High	838	SF	3.3%	Stopgap	AC Full-Depth Patching	959	SF	\$ 10.00	\$ 9,590
LEE	AP FUEL	4505	RAVELING	High	387	SF	1.5%	Stopgap	AC Partial-Depth Patching	386	SF	\$ 4.75	\$ 1,840
LEE	AP N	4120	JT SEAL DMG	High	41	Slabs	100.0%	Stopgap	PCC Joint Seal	1,036	LF	\$ 4.25	\$ 4,410
LEE	AP N	4120	JOINT SPALL	Medium	2	Slabs	4.2%	Stopgap	PCC Partial-Depth Patching	11	SF	\$ 169.00	\$ 1,870
LEE	AP N	4120	CORNER SPALL	Medium	2	Slabs	4.2%	Stopgap	PCC Partial-Depth Patching	4	SF	\$ 169.00	\$ 780
LEE	AP N	4135	LINEAR CR	Medium	19	Slabs	37.5%	Stopgap	PCC Crack Sealing	403	LF	\$ 7.00	\$ 2,830
LEE	AP N	4135	JT SEAL DMG	High	50	Slabs	100.0%	Stopgap	PCC Joint Seal	1,193	LF	\$ 4.25	\$ 5,070
LEE	AP N	4135	JOINT SPALL	Medium	4	Slabs	8.3%	Stopgap	PCC Partial-Depth Patching	27	SF	\$ 169.00	\$ 4,550
LEE	AP N	4135	CORNER SPALL	Medium	6	Slabs	12.5%	Stopgap	PCC Partial-Depth Patching	17	SF	\$ 169.00	\$ 2,850
LEE	AP N	4140	JT SEAL DMG	High	14	Slabs	100.0%	Stopgap	PCC Joint Seal	790	LF	\$ 4.25	\$ 3,360
LEE	AP N	4140	SHAT. SLAB	Medium	14	Slabs	100.0%	Stopgap	PCC Crack Sealing	700	LF	\$ 7.00	\$ 4,900

Table B.2: Section-Level 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	LEE	TW A	107	AAC	4,534	63	AC Rehabilitation	\$ 41,000
2023	LEE	TW A1	120	AC	4,409	55	AC Rehabilitation	\$ 40,000
2023	LEE	TW A2	130	AC	4,287	62	AC Rehabilitation	\$ 39,000
2023	LEE	TW A3	140	AC	4,673	53	AC Reconstruction	\$ 75,000
2023	LEE	TW D	400	AC	22,621	54	AC Reconstruction	\$ 294,000
2023	LEE	TW K	705	AC	33,012	64	AC Rehabilitation	\$ 298,000
2023	LEE	TW K	715	AC	4,634	52	AC Reconstruction	\$ 75,000
2023	LEE	TL APRON	4305	AC	10,698	27	AC Reconstruction	\$ 172,000
2023	LEE	TL T-HANG	4110	AC	14,559	68	AC Rehabilitation	\$ 132,000
2023	LEE	TL T-HANG	4115	AC	20,585	68	AC Rehabilitation	\$ 186,000
2023	LEE	TL T-HANG	4205	AC	45,127	67	AC Rehabilitation	\$ 407,000
2023	LEE	AP FUEL	4505	AC	25,329	22	AC Reconstruction	\$ 406,000
2023	LEE	AP N	4120	PCC	5,920	56	PCC Rehabilitation	\$ 89,000
2023	LEE	AP N	4135	PCC	18,579	26	PCC Reconstruction	\$ 539,000
2023	LEE	AP N	4140	PCC	8,600	11	PCC Reconstruction	\$ 250,000
2026	LEE	TW A	110	AAC	113,871	69	AC Rehabilitation	\$ 1,187,000
2026	LEE	TW C	300	AC	25,917	69	AC Rehabilitation	\$ 271,000
2027	LEE	TW B	200	AAC	76,570	70	AC Rehabilitation	\$ 838,000
2027	LEE	AP RU 13	5205	AC	36,679	69	AC Rehabilitation	\$ 402,000
2028	LEE	TW K	700	AAC	138,244	69	AC Rehabilitation	\$ 1,589,000
2029	LEE	TW A	100	AC	77,110	70	AC Rehabilitation	\$ 931,000
2030	LEE	RW 4-22	6205	AAC	242,833	69	AC Rehabilitation	\$ 3,076,000
2031	LEE	RW 4-22	6210	AAC	244,205	69	AC Rehabilitation	\$ 3,248,000
2031	LEE	TW A	115	AC	62,194	69	AC Rehabilitation	\$ 828,000
2031	LEE	AP RU 31	5305	AC	54,952	69	AC Rehabilitation	\$ 731,000
2032	LEE	TW J	600	AAC	26,600	70	AC Rehabilitation	\$ 372,000
2032	LEE	AP RU SEA	5405	AC	18,231	70	AC Rehabilitation	\$ 255,000

*All planning cost values have been rounded up to the nearest thousand dollars.



Appendix C: Technical Exhibits






LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID
- AAC — PAVEMENT SURFACE TYPE
- AP MAIN — PAVEMENT BRANCH ID
- 4105 — SECTION NUMBER
- 100 — NUMBER OF SAMPLE UNITS IN SECTION
- 100 — NUMBER OF SAMPLE UNITS TO BE INSPECTED
- AAC
AP MAIN
4105
0 | 100 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100 — INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 67
AC: 61 PCC: 6

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2019	AP RU SEA, TL SEA	New Construction - AC
2021	RW 13-31	Mill and Overlay 1" Mill, Variable P-403, 2" P-401
2022	AP HELI	New Construction - PCC 8" P-501, P-152 Stabilized Subgrade
	AP N	Complete Reconstruction - AC 4" P-401, 4" P-211, P-152 Stabilized Subgrade
	AP N	Mill and Overlay Mill of Existing AC, 4" P-401 Overlay

LEGEND


- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROJECT YEAR

2017	2022
2018	2023
2019	2024
2020	2025
2021	2026

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





LEGEND


- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

AGE AT INSPECTION

- 0-5 Years
- 6-10 Years
- 11-15 Years
- 16-20 Years
- > 20 Years

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID


2022 PAVEMENT CONDITION INDEX

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

SECTION ID
PCI VALUE

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





TW A1:120 2023 AC REHAB \$0.04 M	TW A2:130 2023 AC REHAB \$0.04 M	TW A3:140 2023 AC RECON \$0.08 M
TL T-HANG:4110 2023 AC REHAB \$0.13 M	TL T-HANG:4115 2023 AC REHAB \$0.19 M	AP FUEL:4505 2023 AC RECON \$0.41 M

LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID

PROGRAM YEAR

"BRANCH," "SECTION"
"YEAR," "REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





Appendix D: Inspection Photograph Documentation






RW 4-22, Section 6205, Sample Unit 301 – Longitudinal & Transverse Cracking



RW 4-22, Section 6210, Sample Unit 500 — Bleeding




RW 13-31, Section 6115, Sample Unit 362 -- Longitudinal & Transverse Cracking



RW 13-31, Section 6125, Sample Unit 303 -- Longitudinal & Transverse Cracking



TW A, Section 100, Sample Unit 255 – Bleeding



TW A, Section 110, Sample Unit 215 – Bleeding



TW B, Section 200, Sample Unit 109 -- Longitudinal & Transverse Cracking



TW D, Section 400, Sample Unit 252 - Bleeding



TW K, Section 700, Sample Unit 111 – Longitudinal & Transverse Cracking



TW K, Section 715, Sample Unit 122 – Vicinity



AP FUEL, Section 4505, Sample Unit 301 – Vicinity



AP N, Section 4135, Sample Unit 604 – Linear Cracking



AP N, Section 4140, Sample Unit 602 – Shattered Slab



TL T-HANG, Section 4205, Sample Unit 105 – Vicinity



Appendix E: Inspection Distress Details



Re-Inspection Report

FDOT

Generated Date

11/17/2022

Page 1 of 49

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP FUEL **Name:** FUELING APRON **Use:** APRON **Area:** 25,329 SqFt

Section: 4505 of 1 **From:** - **To:** - **Last Const.:** 1/1/1989

Surface: AC **Family:** CA653-GA-AP-AC **Zone:** **Category:** **Rank:** P

Area: 25,329 SqFt **Length:** 200 Ft **Width:** 100 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1989 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 5 **Surveyed:** 1

Conditions: PCI: 23

Inspection Comments:

Sample Number: 301 **Type:** R **Area:** 5500.00 SqFt **PCI:** 23

Sample Comments:

43	BLOCK CR	L	4113.00	SqFt
45	DEPRESSION	L	120.00	SqFt
50	PATCHING	L	580.00	SqFt
50	PATCHING	M	625.00	SqFt
50	PATCHING	H	182.00	SqFt
52	RAVELING	L	3571.00	SqFt
52	RAVELING	M	403.00	SqFt
52	RAVELING	H	84.00	SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	AP N	Name:	NORTH APRON	Use:	APRON	Area:	457,136 SqFt
Section:	4105	of 9	From:	-	To:	-	Last Const.: 4/1/2022
Surface:	AAC	Family:	CA653-GA-AP-AAC-APC	Zone:		Category:	Rank: P
Area:	294,586 SqFt	Length:	1,393 Ft	Width:	248 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1989	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2007	Work Type:	Surface Treatment - Seal Coat	Code:	ST-SC	Is Major M&R:	False
Work Date:	4/1/2022	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	1/30/2019	TotalSamples:	66	Surveyed:	7		
Conditions:	PCI: 53	NOTE: *** Pre-Construction PCI ***					
Inspection Comments:							
Sample Number:	102	Type:	R	Area:	5000.00 SqFt	PCI:	50
Sample Comments:							
43	BLOCK CR	L	3000.00	SqFt			
43	BLOCK CR	M	250.00	SqFt			
48	L & T CR	L	78.00	Ft			
52	RAVELING	L	3000.00	SqFt			
57	WEATHERING	L	2000.00	SqFt			
Sample Number:	112	Type:	R	Area:	5000.00 SqFt	PCI:	64
Sample Comments:							
48	L & T CR	L	561.00	Ft			
49	OIL SPILLAGE	N	12.00	SqFt			
52	RAVELING	L	5000.00	SqFt			
Sample Number:	150	Type:	R	Area:	5000.00 SqFt	PCI:	45
Sample Comments:							
43	BLOCK CR	L	4000.00	SqFt			
43	BLOCK CR	M	1000.00	SqFt			
52	RAVELING	L	2250.00	SqFt			
52	RAVELING	M	250.00	SqFt			
Sample Number:	154	Type:	R	Area:	5000.00 SqFt	PCI:	49
Sample Comments:							
43	BLOCK CR	L	3400.00	SqFt			
43	BLOCK CR	M	100.00	SqFt			
48	L & T CR	L	99.00	Ft			
52	RAVELING	L	1500.00	SqFt			
57	WEATHERING	L	3500.00	SqFt			
Sample Number:	158	Type:	R	Area:	5000.00 SqFt	PCI:	45
Sample Comments:							
41	ALLIGATOR CR	M	85.00	SqFt			
48	L & T CR	L	591.00	Ft			
48	L & T CR	M	34.00	Ft			
52	RAVELING	L	1000.00	SqFt			
57	WEATHERING	L	4000.00	SqFt			
Sample Number:	255	Type:	R	Area:	5000.00 SqFt	PCI:	56
Sample Comments:							
43	BLOCK CR	L	2750.00	SqFt			
48	L & T CR	L	233.00	Ft			
52	RAVELING	L	2750.00	SqFt			
57	WEATHERING	L	2250.00	SqFt			

Sample Number: 260

Type: R

Area: 5550.00 SqFt

PCI: 61

Sample Comments:

48	L & T CR	L	538.00 Ft
48	L & T CR	M	100.00 Ft
52	RAVELING	L	3330.00 SqFt
57	WEATHERING	L	2220.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP N **Name:** NORTH APRON **Use:** APRON **Area:** 457,136 SqFt

Section: 4120 of 9 **From:** - **To:** - **Last Const.:** 12/25/2000

Surface: PCC **Family:** CA653-GA-AP-PCC **Zone:** **Category:** **Rank:** P

Area: 5,920 SqFt **Length:** 120 Ft **Width:** 60 Ft

Slabs: 41 **Slab Length:** 10 Ft **Slab Width:** 14 Ft **Joint Length:** 1,037 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 12/25/2000 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 2 **Surveyed:** 1

Conditions: PCI: 57

Inspection Comments:

Sample Number: 409 **Type:** R **Area:** 24.00 Slabs **PCI:** 57

Sample Comments:

62	CORNER BREAK	L	2.00	Slabs
63	LINEAR CR	L	18.00	Slabs
65	JT SEAL DMG	H	24.00	Slabs
73	SHRINKAGE CR	N	8.00	Slabs
74	JOINT SPALL	M	1.00	Slabs
75	CORNER SPALL	M	1.00	Slabs

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP N **Name:** NORTH APRON **Use:** APRON **Area:** 457,136 SqFt

Section: 4125 of 9 **From:** - **To:** - **Last Const.:** 4/1/2022

Surface: AAC **Family:** CA653-GA-AP-AAC-APC **Zone:** **Category:** **Rank:** P

Area: 26,853 SqFt **Length:** 313 Ft **Width:** 105 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2005 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Work Date: 4/1/2022 **Work Type:** Mill and Overlay **Code:** ML-OVL **Is Major M&R:** True

Last Insp. Date: 1/30/2019 **TotalSamples:** 12 **Surveyed:** 2

Conditions: PCI: 66 **NOTE: *** Pre-Construction PCI *****

Inspection Comments:

Sample Number: 114 **Type:** R **Area:** 4650.00 SqFt **PCI:** 65

Sample Comments:

48 L & T CR L 54.00 Ft
49 OIL SPILLAGE N 60.00 SqFt
52 RAVELING L 4650.00 SqFt

Sample Number: 266 **Type:** R **Area:** 6415.00 SqFt **PCI:** 67

Sample Comments:

48 L & T CR L 66.00 Ft
49 OIL SPILLAGE N 26.00 SqFt
52 RAVELING L 3200.00 SqFt
57 WEATHERING L 3215.00 SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	AP N	Name:	NORTH APRON	Use:	APRON	Area:	457,136 SqFt
Section:	4130	of 9	From:	-	To:	-	Last Const.: 1/1/2008
Surface:	PCC	Family:	CA653-GA-AP-PCC	Zone:		Category:	Rank: P
Area:	44,288 SqFt	Length:	260 Ft	Width:	160 Ft		
Slabs:	138	Slab Length:	16 Ft	Slab Width:	20 Ft	Joint Length:	4,260 Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2008	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	8	Surveyed:	2		
Conditions:	PCI: 93						
Inspection Comments:							
Sample Number:	103	Type:	R	Area:	23.00 Slabs	PCI:	94
Sample Comments:							
73	SHRINKAGE CR		N	8.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		
Sample Number:	106	Type:	R	Area:	20.00 Slabs	PCI:	92
Sample Comments:							
63	LINEAR CR		L	1.00	Slabs		
73	SHRINKAGE CR		N	2.00	Slabs		
74	JOINT SPALL		L	1.00	Slabs		

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP N **Name:** NORTH APRON **Use:** APRON **Area:** 457,136 SqFt

Section: 4135 of 9 **From:** - **To:** - **Last Const.:** 1/1/1942

Surface: PCC **Family:** CA653-GA-AP-PCC **Zone:** **Category:** **Rank:** P

Area: 18,579 SqFt **Length:** 260 Ft **Width:** 50 Ft

Slabs: 50 **Slab Length:** 12 Ft **Slab Width:** 31 Ft **Joint Length:** 1,193 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1942 **Work Type:** BUILT **Code:** IMPORTED **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 4 **Surveyed:** 1

Conditions: PCI: 27

Inspection Comments:

Sample Number: 604 **Type:** R **Area:** 24.00 Slabs **PCI:** 27

Sample Comments:

63	LINEAR CR	L	14.00	Slabs
63	LINEAR CR	M	9.00	Slabs
65	JT SEAL DMG	H	24.00	Slabs
72	SHAT. SLAB	L	1.00	Slabs
73	SHRINKAGE CR	N	24.00	Slabs
74	JOINT SPALL	L	3.00	Slabs
74	JOINT SPALL	M	2.00	Slabs
75	CORNER SPALL	L	3.00	Slabs
75	CORNER SPALL	M	3.00	Slabs

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP N **Name:** NORTH APRON **Use:** APRON **Area:** 457,136 SqFt

Section: 4140 of 9 **From:** - **To:** - **Last Const.:** 1/1/1942

Surface: PCC **Family:** CA653-GA-AP-PCC **Zone:** **Category:** **Rank:** P

Area: 8,600 SqFt **Length:** 66 Ft **Width:** 200 Ft

Slabs: 14 **Slab Length:** 25 Ft **Slab Width:** 25 Ft **Joint Length:** 790 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1942 **Work Type:** BUILT **Code:** IMPORTED **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 1 **Surveyed:** 1

Conditions: PCI: 12

Inspection Comments:

Sample Number: 602 **Type:** R **Area:** 12.00 Slabs **PCI:** 12

Sample Comments:

65 JT SEAL DMG H 12.00 Slabs

72 SHAT. SLAB M 12.00 Slabs

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	AP N	Name:	NORTH APRON	Use:	APRON	Area:	457,136 SqFt
Section:	4145	of 9	From:	-	To:	-	Last Const.: 7/1/2016
Surface:	AC	Family:	CA653-GA-AP-AC	Zone:		Category:	Rank: P
Area:	11,497 SqFt	Length:	138 Ft	Width:	94 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	7/1/2016	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	2	Surveyed:	1		
Conditions:	PCI: 94						
Inspection Comments:							
Sample Number:	401	Type:	R	Area:	6041.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L		6041.00	SqFt		

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	AP N	Name:	NORTH APRON	Use:	APRON	Area:	457,136 SqFt
Section:	4150	of 9	From:	-	To:	-	Last Const.: 4/1/2022
Surface:	AC	Family:	CA653-GA-AP-AC	Zone:		Category:	Rank: P
Area:	13,976 SqFt	Length:	188 Ft	Width:	105 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1989	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2007	Work Type:	Surface Treatment - Seal Coat	Code:	ST-SC	Is Major M&R:	False
Work Date:	4/1/2022	Work Type:	Complete Reconstruction - AC	Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	1/30/2019	TotalSamples:	66	Surveyed:	7		
Conditions:	PCI: 53	NOTE: *** Pre-Construction PCI ***					
Inspection Comments:							
Sample Number:	102	Type:	R	Area:	5000.00 SqFt	PCI:	50
Sample Comments:							
43	BLOCK CR	L	3000.00	SqFt			
43	BLOCK CR	M	250.00	SqFt			
48	L & T CR	L	78.00	Ft			
52	RAVELING	L	3000.00	SqFt			
57	WEATHERING	L	2000.00	SqFt			
Sample Number:	112	Type:	R	Area:	5000.00 SqFt	PCI:	64
Sample Comments:							
48	L & T CR	L	561.00	Ft			
49	OIL SPILLAGE	N	12.00	SqFt			
52	RAVELING	L	5000.00	SqFt			
Sample Number:	150	Type:	R	Area:	5000.00 SqFt	PCI:	45
Sample Comments:							
43	BLOCK CR	L	4000.00	SqFt			
43	BLOCK CR	M	1000.00	SqFt			
52	RAVELING	L	2250.00	SqFt			
52	RAVELING	M	250.00	SqFt			
Sample Number:	154	Type:	R	Area:	5000.00 SqFt	PCI:	49
Sample Comments:							
43	BLOCK CR	L	3400.00	SqFt			
43	BLOCK CR	M	100.00	SqFt			
48	L & T CR	L	99.00	Ft			
52	RAVELING	L	1500.00	SqFt			
57	WEATHERING	L	3500.00	SqFt			
Sample Number:	158	Type:	R	Area:	5000.00 SqFt	PCI:	45
Sample Comments:							
41	ALLIGATOR CR	M	85.00	SqFt			
48	L & T CR	L	591.00	Ft			
48	L & T CR	M	34.00	Ft			
52	RAVELING	L	1000.00	SqFt			
57	WEATHERING	L	4000.00	SqFt			
Sample Number:	255	Type:	R	Area:	5000.00 SqFt	PCI:	56
Sample Comments:							
43	BLOCK CR	L	2750.00	SqFt			
48	L & T CR	L	233.00	Ft			
52	RAVELING	L	2750.00	SqFt			
57	WEATHERING	L	2250.00	SqFt			
Sample Number:	260	Type:	R	Area:	5550.00 SqFt	PCI:	61
Sample Comments:							

48	L & T CR	L	538.00	Ft
48	L & T CR	M	100.00	Ft
52	RAVELING	L	3330.00	SqFt
57	WEATHERING	L	2220.00	SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP N **Name:** NORTH APRON **Use:** APRON **Area:** 457,136 SqFt

Section: 4155 of 9 **From:** - **To:** - **Last Const.:** 4/1/2022

Surface: AC **Family:** CA653-GA-AP-AC **Zone:** **Category:** **Rank:** P

Area: 32,837 SqFt **Length:** 220 Ft **Width:** 130 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2005 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Work Date: 4/1/2022 **Work Type:** Complete Reconstruction - AC **Code:** CR-AC **Is Major M&R:** True

Last Insp. Date: 1/30/2019 **TotalSamples:** 12 **Surveyed:** 2

Conditions: PCI: 66 **NOTE: *** Pre-Construction PCI *****

Inspection Comments:

Sample Number: 114 **Type:** R **Area:** 4650.00 SqFt **PCI:** 65

Sample Comments:

48 L & T CR L 54.00 Ft

49 OIL SPILLAGE N 60.00 SqFt

52 RAVELING L 4650.00 SqFt

Sample Number: 266 **Type:** R **Area:** 6415.00 SqFt **PCI:** 67

Sample Comments:

48 L & T CR L 66.00 Ft

49 OIL SPILLAGE N 26.00 SqFt

52 RAVELING L 3200.00 SqFt

57 WEATHERING L 3215.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP RU 13 **Name:** RUN-UP APRON 13 **Use:** APRON **Area:** 36,679 SqFt

Section: 5205 of 1 **From:** - **To:** - **Last Const.:** 1/1/2008

Surface: AC **Family:** CA653-GA-AP-AC **Zone:** **Category:** **Rank:** P

Area: 36,679 SqFt **Length:** 235 Ft **Width:** 175 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2008 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 8 **Surveyed:** 1

Conditions: PCI: 78

Inspection Comments:

Sample Number: 101 **Type:** R **Area:** 3750.00 SqFt **PCI:** 78

Sample Comments:

46	JET BLAST	N	14.00	SqFt
48	L & T CR	L	128.00	Ft
57	WEATHERING	L	3562.00	SqFt
57	WEATHERING	M	188.00	SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT			
-----------------	-----	--------------	--------------------------------	--	--	--

Branch:	AP RU 31	Name:	RUN-UP APRON 31	Use:	APRON	Area:	54,952 SqFt
----------------	----------	--------------	-----------------	-------------	-------	--------------	-------------

Section:	5305	of	1	From:	-	To:	-	Last Const.:	1/1/2009
-----------------	------	----	---	--------------	---	------------	---	---------------------	----------

Surface:	AC	Family:	CA653-GA-AP-AC	Zone:		Category:		Rank:	P
-----------------	----	----------------	----------------	--------------	--	------------------	--	--------------	---

Area:	54,952 SqFt	Length:	410 Ft	Width:	160 Ft				
--------------	-------------	----------------	--------	---------------	--------	--	--	--	--

Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
---------------	--	---------------------	----	--------------------	----	----------------------	----	--	--

Shoulder:		Street Type:		Grade:	0	Lanes:	0		
------------------	--	---------------------	--	---------------	---	---------------	---	--	--

Section Comments:

Work Date:	1/1/2009	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
-------------------	----------	-------------------	----------------------------	--------------	-------	--------------------------	------

Last Insp. Date:	4/26/2022	TotalSamples:	11	Surveyed:	2				
-------------------------	-----------	----------------------	----	------------------	---	--	--	--	--

Conditions: PCI: 85

Inspection Comments:

Sample Number:	302	Type:	R	Area:	5000.00 SqFt	PCI:	84
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

48	L & T CR	L	94.00 Ft
57	WEATHERING	L	4750.00 SqFt
57	WEATHERING	M	250.00 SqFt

Sample Number:	305	Type:	R	Area:	5000.00 SqFt	PCI:	86
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

48	L & T CR	L	39.00 Ft
57	WEATHERING	L	4750.00 SqFt
57	WEATHERING	M	250.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: AP RU SEA **Name:** RUN-UP APRON SEAPLANE **Use:** APRON **Area:** 18,231 SqFt
BASE

Section: 5405 of 1 **From:** - **To:** - **Last Const.:** 1/1/2019

Surface: AC **Family:** CA653-GA-AP-AC **Zone:** **Category:** **Rank:** P

Area: 18,231 SqFt **Length:** 180 Ft **Width:** 100 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2019 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 4 **Surveyed:** 1

Conditions: PCI: 89

Inspection Comments:

Sample Number: 501 **Type:** R **Area:** 4667.00 SqFt **PCI:** 89

Sample Comments:

48 L & T CR L 42.00 Ft
57 WEATHERING L 4667.00 SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	RW 13-31	Name:	RUNWAY 13-31	Use:	RUNWAY	Area:	630,000 SqFt
Section:	6105	of 6	From:	-	To:	-	Last Const.: 1/1/2021
Surface:	AAC	Family:	CA653-GA-RW-AAC-APC	Zone:		Category:	Rank: P
Area:	255,000 SqFt	Length:	5,100 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1942	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1980	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2000	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2021	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	1/30/2019	TotalSamples:	50	Surveyed:	9		
Conditions:	PCI: 61	NOTE: *** Pre-Construction PCI ***					
Inspection Comments:							
Sample Number:	312	Type:	R	Area:	5000.00 SqFt	PCI:	53
Sample Comments:							
42	BLEEDING	N	330.00	SqFt			
48	L & T CR	L	181.00	Ft			
48	L & T CR	M	100.00	Ft			
52	RAVELING	L	200.00	SqFt			
52	RAVELING	M	600.00	SqFt			
Sample Number:	318	Type:	R	Area:	5000.00 SqFt	PCI:	62
Sample Comments:							
42	BLEEDING	N	170.00	SqFt			
48	L & T CR	L	316.00	Ft			
48	L & T CR	M	100.00	Ft			
57	WEATHERING	L	4500.00	SqFt			
57	WEATHERING	M	500.00	SqFt			
Sample Number:	324	Type:	R	Area:	5000.00 SqFt	PCI:	59
Sample Comments:							
48	L & T CR	L	278.00	Ft			
48	L & T CR	M	190.00	Ft			
52	RAVELING	L	280.00	SqFt			
57	WEATHERING	L	4470.00	SqFt			
57	WEATHERING	M	250.00	SqFt			
Sample Number:	330	Type:	R	Area:	5000.00 SqFt	PCI:	80
Sample Comments:							
42	BLEEDING	N	15.00	SqFt			
48	L & T CR	L	108.00	Ft			
57	WEATHERING	L	4500.00	SqFt			
57	WEATHERING	M	500.00	SqFt			
Sample Number:	336	Type:	R	Area:	5000.00 SqFt	PCI:	74
Sample Comments:							
48	L & T CR	L	288.00	Ft			
57	WEATHERING	L	4500.00	SqFt			
57	WEATHERING	M	500.00	SqFt			
Sample Number:	342	Type:	R	Area:	5000.00 SqFt	PCI:	72
Sample Comments:							
42	BLEEDING	N	45.00	SqFt			
48	L & T CR	L	223.00	Ft			
57	WEATHERING	L	4500.00	SqFt			
57	WEATHERING	M	500.00	SqFt			

Sample Number: 348	Type: R	Area: 5000.00 SqFt	PCI: 50
---------------------------	----------------	---------------------------	----------------

Sample Comments:

42	BLEEDING	N	429.00 SqFt
48	L & T CR	L	175.00 Ft
57	WEATHERING	L	4500.00 SqFt
57	WEATHERING	M	500.00 SqFt

Sample Number: 354	Type: R	Area: 5000.00 SqFt	PCI: 47
---------------------------	----------------	---------------------------	----------------

Sample Comments:

42	BLEEDING	N	510.00 SqFt
48	L & T CR	L	206.00 Ft
57	WEATHERING	L	4500.00 SqFt
57	WEATHERING	M	500.00 SqFt

Sample Number: 357	Type: R	Area: 5000.00 SqFt	PCI: 49
---------------------------	----------------	---------------------------	----------------

Sample Comments:

42	BLEEDING	N	458.00 SqFt
48	L & T CR	L	110.00 Ft
57	WEATHERING	L	4500.00 SqFt
57	WEATHERING	M	500.00 SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	RW 13-31	Name:	RUNWAY 13-31	Use:	RUNWAY	Area:	630,000 SqFt
Section:	6110	of 6	From:	-	To:	-	Last Const.: 1/1/2021
Surface:	AAC	Family:	CA653-GA-RW-AAC-APC	Zone:		Category:	Rank: P
Area:	255,000 SqFt	Length:	5,100 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1942	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1980	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2000	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2021	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	1/30/2019	TotalSamples:	50	Surveyed:	8		
Conditions:	PCI: 66	NOTE: *** Pre-Construction PCI ***					
Inspection Comments:							
Sample Number:	114	Type:	R	Area:	5000.00 SqFt	PCI:	63
Sample Comments:							
42	BLEEDING	N	48.00	SqFt			
48	L & T CR	L	379.00	Ft			
48	L & T CR	M	20.00	Ft			
57	WEATHERING	L	4900.00	SqFt			
57	WEATHERING	M	100.00	SqFt			
Sample Number:	120	Type:	R	Area:	5000.00 SqFt	PCI:	39
Sample Comments:							
42	BLEEDING	N	62.00	SqFt			
48	L & T CR	L	125.00	Ft			
48	L & T CR	M	22.00	Ft			
52	RAVELING	M	3000.00	SqFt			
Sample Number:	126	Type:	R	Area:	5000.00 SqFt	PCI:	65
Sample Comments:							
48	L & T CR	L	111.00	Ft			
48	L & T CR	M	180.00	Ft			
57	WEATHERING	L	4750.00	SqFt			
57	WEATHERING	M	250.00	SqFt			
Sample Number:	140	Type:	R	Area:	5000.00 SqFt	PCI:	75
Sample Comments:							
48	L & T CR	L	289.00	Ft			
57	WEATHERING	L	4750.00	SqFt			
57	WEATHERING	M	250.00	SqFt			
Sample Number:	510	Type:	R	Area:	5000.00 SqFt	PCI:	49
Sample Comments:							
48	L & T CR	L	67.00	Ft			
52	RAVELING	L	250.00	SqFt			
52	RAVELING	M	2750.00	SqFt			
Sample Number:	530	Type:	R	Area:	5000.00 SqFt	PCI:	74
Sample Comments:							
48	L & T CR	L	137.00	Ft			
48	L & T CR	M	60.00	Ft			
57	WEATHERING	L	4750.00	SqFt			
57	WEATHERING	M	250.00	SqFt			
Sample Number:	544	Type:	R	Area:	5000.00 SqFt	PCI:	86
Sample Comments:							

48	L & T CR	L	65.00	Ft
57	WEATHERING	L	4750.00	SqFt
57	WEATHERING	M	250.00	SqFt

Sample Number: 550 **Type:** R **Area:** 5000.00 SqFt **PCI:** 77

Sample Comments:

48	L & T CR	L	208.00	Ft
57	WEATHERING	L	4500.00	SqFt
57	WEATHERING	M	500.00	SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	RW 13-31	Name:	RUNWAY 13-31	Use:	RUNWAY	Area:	630,000 SqFt
Section:	6115	of 6	From:	-	To:	-	Last Const.: 12/12/2009
Surface:	AC	Family:	CA653-GA-RW-AC	Zone:		Category:	Rank: P
Area:	12,500 SqFt	Length:	250 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	12/12/2009	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R: True
Work Date:	1/1/2022	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R: False
Last Insp. Date:	4/26/2022	TotalSamples:	3	Surveyed:	1		
Conditions:	PCI: 88						
Inspection Comments:							
Sample Number:	362	Type:	R	Area:	3750.00 SqFt	PCI:	88
Sample Comments:							
48	L & T CR	L	149.00	Ft			

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	RW 13-31	Name:	RUNWAY 13-31	Use:	RUNWAY	Area:	630,000 SqFt
Section:	6120	of 6	From:	-	To:	-	Last Const.: 12/12/2009
Surface:	AC	Family:	CA653-GA-RW-AC	Zone:		Category:	Rank: P
Area:	12,500 SqFt	Length:	250 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	12/12/2009	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R: True
Work Date:	1/1/2022	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R: False
Last Insp. Date:	4/26/2022	TotalSamples:	2	Surveyed:	1		
Conditions:	PCI: 88						
Inspection Comments:							
Sample Number:	160	Type:	R	Area:	6250.00 SqFt	PCI:	88
Sample Comments:							
48	L & T CR	L	248.00	Ft			

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: RW 13-31 **Name:** RUNWAY 13-31 **Use:** RUNWAY **Area:** 630,000 SqFt

Section: 6125 of 6 **From:** - **To:** - **Last Const.:** 1/1/2009

Surface: AC **Family:** CA653-GA-RW-AC **Zone:** **Category:** **Rank:** P

Area: 47,500 SqFt **Length:** 950 Ft **Width:** 50 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2009 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/1/2022 **Work Type:** Surface Treatment - Seal Coat **Code:** ST-SC **Is Major M&R:** False

Last Insp. Date: 4/26/2022 **TotalSamples:** 10 **Surveyed:** 3

Conditions: PCI: 92

Inspection Comments:

Sample Number: 301 **Type:** R **Area:** 5000.00 SqFt **PCI:** 90

Sample Comments:

48 L & T CR L 145.00 Ft

Sample Number: 303 **Type:** R **Area:** 5000.00 SqFt **PCI:** 92

Sample Comments:

48 L & T CR L 114.00 Ft

Sample Number: 306 **Type:** R **Area:** 5000.00 SqFt **PCI:** 94

Sample Comments:

48 L & T CR L 82.00 Ft

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: RW 13-31 **Name:** RUNWAY 13-31 **Use:** RUNWAY **Area:** 630,000 SqFt

Section: 6130 of 6 **From:** - **To:** - **Last Const.:** 1/1/2009

Surface: AC **Family:** CA653-GA-RW-AC **Zone:** **Category:** **Rank:** P

Area: 47,500 SqFt **Length:** 950 Ft **Width:** 50 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2009 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/1/2022 **Work Type:** Surface Treatment - Seal Coat **Code:** ST-SC **Is Major M&R:** False

Last Insp. Date: 4/26/2022 **TotalSamples:** 10 **Surveyed:** 2

Conditions: PCI: 95

Inspection Comments:

Sample Number: 102 **Type:** R **Area:** 5000.00 SqFt **PCI:** 95

Sample Comments:

48 L & T CR L 50.00 Ft

Sample Number: 506 **Type:** R **Area:** 5000.00 SqFt **PCI:** 95

Sample Comments:

48 L & T CR L 45.00 Ft

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	RW 4-22	Name:	RUNWAY 4-22	Use:	RUNWAY	Area:	487,038 SqFt
Section:	6205	of 2	From:	-	To:	-	Last Const.: 1/1/2011
Surface:	AAC	Family:	CA653-GA-RW-AAC-APC	Zone:		Category:	Rank: P
Area:	242,833 SqFt	Length:	3,900 Ft	Width:	75 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1942	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1983	Work Type:	Complete Reconstruction - AC	Code:	CR-AC	Is Major M&R:	True
Work Date:	1/1/2011	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	48	Surveyed:	8		
Conditions:	PCI: 85						
Inspection Comments:							
Sample Number:	301	Type:	R	Area:	5000.00 SqFt	PCI:	83
Sample Comments:							
48	L & T CR	L	109.00	Ft			
52	RAVELING	L	75.00	SqFt			
56	SWELLING	L	2.00	SqFt			
57	WEATHERING	L	4925.00	SqFt			
Sample Number:	307	Type:	R	Area:	5000.00 SqFt	PCI:	86
Sample Comments:							
48	L & T CR	L	45.00	Ft			
52	RAVELING	L	57.00	SqFt			
57	WEATHERING	L	4943.00	SqFt			
Sample Number:	313	Type:	R	Area:	5000.00 SqFt	PCI:	84
Sample Comments:							
48	L & T CR	L	111.00	Ft			
52	RAVELING	L	60.00	SqFt			
57	WEATHERING	L	4940.00	SqFt			
Sample Number:	319	Type:	R	Area:	5000.00 SqFt	PCI:	82
Sample Comments:							
48	L & T CR	L	58.00	Ft			
52	RAVELING	L	60.00	SqFt			
57	WEATHERING	L	4632.00	SqFt			
57	WEATHERING	M	308.00	SqFt			
Sample Number:	325	Type:	R	Area:	5000.00 SqFt	PCI:	83
Sample Comments:							
48	L & T CR	L	139.00	Ft			
52	RAVELING	L	62.00	SqFt			
57	WEATHERING	L	4938.00	SqFt			
Sample Number:	331	Type:	R	Area:	5000.00 SqFt	PCI:	85
Sample Comments:							
48	L & T CR	L	81.00	Ft			
52	RAVELING	L	62.00	SqFt			
56	SWELLING	L	1.00	SqFt			
57	WEATHERING	L	4938.00	SqFt			
Sample Number:	337	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	4.00	Ft			
52	RAVELING	L	64.00	SqFt			
57	WEATHERING	L	4936.00	SqFt			

Sample Number: 343

Type: R

Area: 5000.00 SqFt

PCI: 88

Sample Comments:

48	L & T CR	L	13.00 Ft
52	RAVELING	L	56.00 SqFt
57	WEATHERING	L	4944.00 SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	RW 4-22	Name:	RUNWAY 4-22	Use:	RUNWAY	Area:	487,038 SqFt
Section:	6210	of 2	From:	-	To:	-	Last Const.: 1/1/2011
Surface:	AAC	Family:	CA653-GA-RW-AAC-APC	Zone:		Category:	Rank: P
Area:	244,205 SqFt	Length:	4,857 Ft	Width:	25 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1942	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1983	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Work Date:	1/1/2011	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	48	Surveyed:	8		
Conditions:	PCI: 87						
Inspection Comments:							
Sample Number:	106	Type:	R	Area:	5000.00 SqFt	PCI:	92
Sample Comments:							
48	L & T CR	L	1.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	118	Type:	R	Area:	5000.00 SqFt	PCI:	89
Sample Comments:							
48	L & T CR	L	52.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	130	Type:	R	Area:	5000.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	144	Type:	R	Area:	5000.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	500	Type:	R	Area:	5000.00 SqFt	PCI:	88
Sample Comments:							
42	BLEEDING	N	8.00	SqFt			
48	L & T CR	L	69.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	512	Type:	R	Area:	5000.00 SqFt	PCI:	79
Sample Comments:							
48	L & T CR	L	16.00	Ft			
52	RAVELING	L	800.00	SqFt			
57	WEATHERING	L	4200.00	SqFt			
Sample Number:	524	Type:	R	Area:	5000.00 SqFt	PCI:	90
Sample Comments:							
42	BLEEDING	N	3.00	SqFt			
48	L & T CR	L	38.00	Ft			
57	WEATHERING	L	5000.00	SqFt			
Sample Number:	536	Type:	R	Area:	5000.00 SqFt	PCI:	74
Sample Comments:							
48	L & T CR	L	9.00	Ft			
52	RAVELING	L	2000.00	SqFt			
57	WEATHERING	L	3000.00	SqFt			

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TL APRON **Name:** APRON TAXILANE **Use:** TAXILANE **Area:** 10,698 SqFt

Section: 4305 of 1 **From:** - **To:** - **Last Const.:** 1/1/1982

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 10,698 SqFt **Length:** 300 Ft **Width:** 35 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1982 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Patching - AC **Code:** PA-AC **Is Major M&R:** False

Work Date: 1/1/2018 **Work Type:** Surface Treatment - Seal Coat **Code:** ST-SC **Is Major M&R:** False

Last Insp. Date: 4/26/2022 **TotalSamples:** 2 **Surveyed:** 1

Conditions: PCI: 29

Inspection Comments:

Sample Number: 401 **Type:** R **Area:** 4943.00 SqFt **PCI:** 29

Sample Comments:

41	ALLIGATOR CR	L	56.00	SqFt
41	ALLIGATOR CR	M	64.00	SqFt
45	DEPRESSION	H	25.00	SqFt
48	L & T CR	L	73.00	Ft
48	L & T CR	M	190.00	Ft
50	PATCHING	L	77.00	SqFt
52	RAVELING	L	1216.00	SqFt
53	RUTTING	M	135.00	SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TL SEA **Name:** SEAPLANE BASE TAXILANE **Use:** TAXILANE **Area:** 42,517 SqFt

Section: 160 of 1 **From:** - **To:** - **Last Const.:** 1/1/2019

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 42,517 SqFt **Length:** 750 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2019 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 8 **Surveyed:** 1

Conditions: PCI: 92

Inspection Comments:

Sample Number: 105 **Type:** R **Area:** 4408.00 SqFt **PCI:** 92

Sample Comments:

48 L & T CR L 4.00 Ft
57 WEATHERING L 4408.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TL T-HANG **Name:** T-HANGAR TAXILANE **Use:** TAXILANE **Area:** 80,271 SqFt

Section: 4110 of 3 **From:** - **To:** - **Last Const.:** 12/25/2000

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 14,559 SqFt **Length:** 300 Ft **Width:** 30 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 12/25/2000 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 3 **Surveyed:** 1

Conditions: PCI: 69

Inspection Comments:

Sample Number: 101 **Type:** R **Area:** 5550.00 SqFt **PCI:** 69

Sample Comments:

48 L & T CR L 95.00 Ft
52 RAVELING L 5550.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TL T-HANG **Name:** T-HANGAR TAXILANE **Use:** TAXILANE **Area:** 80,271 SqFt

Section: 4115 of 3 **From:** - **To:** - **Last Const.:** 12/25/2000

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 20,585 SqFt **Length:** 300 Ft **Width:** 30 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 12/25/2000 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 5 **Surveyed:** 1

Conditions: PCI: 69

Inspection Comments:

Sample Number: 302 **Type:** R **Area:** 5180.00 SqFt **PCI:** 69

Sample Comments:

48	L & T CR	L	67.00 Ft
48	L & T CR	M	22.00 Ft
52	RAVELING	L	1554.00 SqFt
57	WEATHERING	L	3626.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TL T-HANG **Name:** T-HANGAR TAXILANE **Use:** TAXILANE **Area:** 80,271 SqFt

Section: 4205 of 3 **From:** - **To:** - **Last Const.:** 1/1/2003

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 45,127 SqFt **Length:** 1,500 Ft **Width:** 25 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2003 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 9 **Surveyed:** 1

Conditions: PCI: 68

Inspection Comments:

Sample Number: 105 **Type:** R **Area:** 5000.00 SqFt **PCI:** 68

Sample Comments:

48 L & T CR L 23.00 Ft
49 OIL SPILLAGE N 4.00 SqFt
52 RAVELING L 5000.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 339,944 SqFt

Section: 100 of 5 **From:** - **To:** - **Last Const.:** 1/1/2009

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 77,110 SqFt **Length:** 1,400 Ft **Width:** 50 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2009 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 15 **Surveyed:** 3

Conditions: PCI: 80

Inspection Comments:

Sample Number: 250 **Type:** R **Area:** 5000.00 SqFt **PCI:** 70

Sample Comments:

42 BLEEDING N 158.00 SqFt

48 L & T CR L 35.00 Ft

57 WEATHERING L 4750.00 SqFt

57 WEATHERING M 250.00 SqFt

Sample Number: 255 **Type:** R **Area:** 5243.00 SqFt **PCI:** 81

Sample Comments:

42 BLEEDING N 65.00 SqFt

48 L & T CR L 29.00 Ft

57 WEATHERING L 4981.00 SqFt

57 WEATHERING M 262.00 SqFt

Sample Number: 260 **Type:** R **Area:** 6530.00 SqFt **PCI:** 86

Sample Comments:

42 BLEEDING N 3.00 SqFt

48 L & T CR L 55.00 Ft

57 WEATHERING L 6204.00 SqFt

57 WEATHERING M 326.00 SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	339,944 SqFt
Section:	105	of 5	From:	-	To:	-	Last Const.: 1/1/2014
Surface:	AC	Family:	CA653-GA-TW-AC	Zone:		Category:	Rank: P
Area:	82,235 SqFt	Length:	1,460 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2014	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	15	Surveyed:	2		
Conditions:	PCI: 87						
Inspection Comments:							
Sample Number:	104	Type:	R	Area:	6000.00 SqFt	PCI:	88
Sample Comments:							
48	L & T CR	L	9.00	Ft			
57	WEATHERING	L	5700.00	SqFt			
57	WEATHERING	M	300.00	SqFt			
Sample Number:	242	Type:	R	Area:	5000.00 SqFt	PCI:	87
Sample Comments:							
48	L & T CR	L	18.00	Ft			
57	WEATHERING	L	4750.00	SqFt			
57	WEATHERING	M	250.00	SqFt			

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	339,944 SqFt
Section:	107	of 5	From:	-	To:	-	Last Const.: 1/1/2002
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:	Rank: P
Area:	4,534 SqFt	Length:	91 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	12/25/1942	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
Work Date:	1/1/1982	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Work Date:	1/1/2002	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	1	Surveyed:	1		
Conditions:	PCI: 64						
Inspection Comments:							
Sample Number:	106	Type:	R	Area:	4534.00 SqFt	PCI:	64
Sample Comments:							
42	BLEEDING	N	75.00	SqFt			
48	L & T CR	L	56.00	Ft			
52	RAVELING	L	4534.00	SqFt			

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	339,944 SqFt
Section:	110	of 5	From:	-	To:	-	Last Const.: 1/1/2000
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:	Rank: P
Area:	113,871 SqFt	Length:	3,790 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1942	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/1982	Work Type:	Complete Reconstruction - AC	Code:	CR-AC	Is Major M&R:	True
Work Date:	1/1/2000	Work Type:	Overlay - AC Structural	Code:	OL-AS	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	22	Surveyed:	3		
Conditions:	PCI: 75						
Inspection Comments:							
Sample Number:	215	Type:	R	Area:	5000.00 SqFt	PCI:	78
Sample Comments:							
42	BLEEDING	N	4.00	SqFt			
48	L & T CR	L	15.00	Ft			
57	WEATHERING	L	3000.00	SqFt			
57	WEATHERING	M	2000.00	SqFt			
Sample Number:	219	Type:	R	Area:	5000.00 SqFt	PCI:	76
Sample Comments:							
48	L & T CR	L	104.00	Ft			
57	WEATHERING	L	3000.00	SqFt			
57	WEATHERING	M	2000.00	SqFt			
Sample Number:	228	Type:	R	Area:	5381.00 SqFt	PCI:	70
Sample Comments:							
42	BLEEDING	N	152.00	SqFt			
48	L & T CR	L	79.00	Ft			
57	WEATHERING	L	3229.00	SqFt			
57	WEATHERING	M	2152.00	SqFt			

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 339,944 SqFt

Section: 115 of 5 **From:** - **To:** - **Last Const.:** 1/1/2009

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 62,194 SqFt **Length:** 1,400 Ft **Width:** 50 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2009 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 11 **Surveyed:** 2

Conditions: PCI: 83

Inspection Comments:

Sample Number: 201 **Type:** R **Area:** 6348.00 SqFt **PCI:** 78

Sample Comments:

48 L & T CR L 290.00 Ft

57 WEATHERING L 6031.00 SqFt

57 WEATHERING M 317.00 SqFt

Sample Number: 210 **Type:** R **Area:** 6584.00 SqFt **PCI:** 87

Sample Comments:

48 L & T CR L 16.00 Ft

57 WEATHERING L 6255.00 SqFt

57 WEATHERING M 329.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW A1 **Name:** TAXIWAY A1 **Use:** TAXIWAY **Area:** 4,409 SqFt

Section: 120 of 1 **From:** - **To:** - **Last Const.:** 1/1/1989

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 4,409 SqFt **Length:** 80 Ft **Width:** 50 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1989 **Work Type:** BUILT **Code:** IMPORTED **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 1 **Surveyed:** 1

Conditions: PCI: 56

Inspection Comments:

Sample Number: 502 **Type:** R **Area:** 4409.00 SqFt **PCI:** 56

Sample Comments:

42	BLEEDING	N	22.00	SqFt
48	L & T CR	L	297.00	Ft
48	L & T CR	M	15.00	Ft
52	RAVELING	L	4373.00	SqFt
52	RAVELING	M	36.00	SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW A2 **Name:** TAXIWAY A2 **Use:** TAXIWAY **Area:** 4,287 SqFt

Section: 130 of 1 **From:** - **To:** - **Last Const.:** 1/1/1989

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 4,287 SqFt **Length:** 80 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1989 **Work Type:** BUILT **Code:** IMPORTED **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 1 **Surveyed:** 1

Conditions: PCI: 63

Inspection Comments:

Sample Number: 501 **Type:** R **Area:** 4287.00 SqFt **PCI:** 63

Sample Comments:

48 L & T CR L 326.00 Ft
52 RAVELING L 4073.00 SqFt
52 RAVELING M 214.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW A3 **Name:** TAXIWAY A3 **Use:** TAXIWAY **Area:** 4,673 SqFt

Section: 140 of 1 **From:** - **To:** - **Last Const.:** 1/1/1989

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 4,673 SqFt **Length:** 80 Ft **Width:** 30 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1989 **Work Type:** BUILT **Code:** IMPORTED **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 1 **Surveyed:** 1

Conditions: PCI: 54

Inspection Comments:

Sample Number: 500 **Type:** R **Area:** 4673.00 SqFt **PCI:** 54

Sample Comments:

48	L & T CR	L	148.00	Ft
48	L & T CR	M	10.00	Ft
52	RAVELING	L	2334.00	SqFt
52	RAVELING	M	4.00	SqFt
54	SHOVING	L	18.00	SqFt
57	WEATHERING	L	2102.00	SqFt
57	WEATHERING	M	233.00	SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW A4 **Name:** TAXIWAY A4 **Use:** TAXIWAY **Area:** 11,820 SqFt

Section: 150 of 1 **From:** - **To:** - **Last Const.:** 1/1/2008

Surface: PCC **Family:** CA653-GA-RW-TW-PCC **Zone:** **Category:** **Rank:** P

Area: 11,820 SqFt **Length:** 98 Ft **Width:** 75 Ft

Slabs: 37 **Slab Length:** 16 Ft **Slab Width:** 20 Ft **Joint Length:** 654 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2008 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 2 **Surveyed:** 1

Conditions: PCI: 83

Inspection Comments:

Sample Number: 101 **Type:** R **Area:** 19.00 Slabs **PCI:** 83

Sample Comments:

62	CORNER BREAK	L	1.00	Slabs
63	LINEAR CR	L	1.00	Slabs
65	JT SEAL DMG	L	19.00	Slabs
73	SHRINKAGE CR	N	1.00	Slabs
74	JOINT SPALL	M	1.00	Slabs

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT						
Branch:	TW B	Name:	TAXIWAY B	Use:	TAXIWAY	Area:	76,570 SqFt		
Section:	200	of	1	From:	-	To:	-	Last Const.:	1/1/2011
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	76,570 SqFt	Length:	1,040 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1983	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2011	Work Type:	Overlay - AC Structural		Code:	OL-AS	Is Major M&R:	True	
Last Insp. Date:	4/26/2022	TotalSamples:	16	Surveyed:	3				
Conditions:	PCI: 77								
Inspection Comments:									
Sample Number:	109	Type:	R	Area:	4996.00 SqFt	PCI:	73		
Sample Comments:									
48	L & T CR	L	350.00	Ft					
57	WEATHERING	L	4746.00	SqFt					
57	WEATHERING	M	250.00	SqFt					
Sample Number:	112	Type:	R	Area:	4996.00 SqFt	PCI:	73		
Sample Comments:									
48	L & T CR	L	341.00	Ft					
57	WEATHERING	L	4746.00	SqFt					
57	WEATHERING	M	250.00	SqFt					
Sample Number:	120	Type:	R	Area:	5000.00 SqFt	PCI:	86		
Sample Comments:									
48	L & T CR	L	42.00	Ft					
57	WEATHERING	L	4750.00	SqFt					
57	WEATHERING	M	250.00	SqFt					

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW C **Name:** TAXIWAY C **Use:** TAXIWAY **Area:** 25,917 SqFt

Section: 300 of 1 **From:** - **To:** - **Last Const.:** 1/1/2009

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 25,917 SqFt **Length:** 320 Ft **Width:** 80 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2009 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 4 **Surveyed:** 1

Conditions: PCI: 75

Inspection Comments:

Sample Number: 52 **Type:** R **Area:** 6800.00 SqFt **PCI:** 75

Sample Comments:

48	L & T CR	L	45.00 Ft
48	L & T CR	M	30.00 Ft
50	PATCHING	L	480.00 SqFt
57	WEATHERING	L	6004.00 SqFt
57	WEATHERING	M	316.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW D **Name:** TAXIWAY D **Use:** TAXIWAY **Area:** 22,621 SqFt

Section: 400 of 1 **From:** - **To:** - **Last Const.:** 1/1/2002

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 22,621 SqFt **Length:** 450 Ft **Width:** 55 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2002 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 5 **Surveyed:** 1

Conditions: PCI: 55

Inspection Comments:

Sample Number: 252 **Type:** R **Area:** 4500.00 SqFt **PCI:** 55

Sample Comments:

42 BLEEDING N 310.00 SqFt

48 L & T CR L 87.00 Ft

57 WEATHERING L 4050.00 SqFt

57 WEATHERING M 450.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW E **Name:** TAXIWAY E **Use:** TAXIWAY **Area:** 8,617 SqFt

Section: 500 of 1 **From:** - **To:** - **Last Const.:** 1/1/2011

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 8,617 SqFt **Length:** 200 Ft **Width:** 45 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2011 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 2 **Surveyed:** 1

Conditions: PCI: 87

Inspection Comments:

Sample Number: 101 **Type:** R **Area:** 3818.00 SqFt **PCI:** 87

Sample Comments:

48 L & T CR L 19.00 Ft
57 WEATHERING L 3627.00 SqFt
57 WEATHERING M 191.00 SqFt

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	TW J	Name:	TAXIWAY J	Use:	TAXIWAY	Area:	26,600 SqFt
Section:	600	of 1	From:	-	To:	-	Last Const.: 1/1/2011
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:	Rank: P
Area:	26,600 SqFt	Length:	430 Ft	Width:	40 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1982	Work Type:	New Construction - AC	Code:	NC-AC	Is Major M&R:	True
Work Date:	1/1/2011	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	6	Surveyed:	1		
Conditions:	PCI: 86						
Inspection Comments:							
Sample Number:	102	Type:	R	Area:	4000.00 SqFt	PCI:	86
Sample Comments:							
48	L & T CR	L	53.00 Ft				
57	WEATHERING	L	3800.00 SqFt				
57	WEATHERING	M	200.00 SqFt				

Network:	LEE	Name:	LEESBURG INTERNATIONAL AIRPORT				
Branch:	TW K	Name:	TAXIWAY K	Use:	TAXIWAY	Area:	199,709 SqFt
Section:	700	of 4	From:	-	To:	-	Last Const.: 1/1/2011
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:	Rank: P
Area:	138,244 SqFt	Length:	3,950 Ft	Width:	35 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/1986	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2011	Work Type:	Mill and Overlay	Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	4/26/2022	TotalSamples:	28	Surveyed:	3		
Conditions:	PCI: 78						
Inspection Comments:							
Sample Number:	111	Type:	R	Area:	5000.00 SqFt	PCI:	66
Sample Comments:							
48	L & T CR	L	355.00 Ft				
48	L & T CR	M	15.00 Ft				
57	WEATHERING	L	4500.00 SqFt				
57	WEATHERING	M	500.00 SqFt				
Sample Number:	125	Type:	R	Area:	5250.00 SqFt	PCI:	83
Sample Comments:							
48	L & T CR	L	79.00 Ft				
57	WEATHERING	L	4462.00 SqFt				
57	WEATHERING	M	788.00 SqFt				
Sample Number:	133	Type:	R	Area:	5250.00 SqFt	PCI:	84
Sample Comments:							
48	L & T CR	L	78.00 Ft				
57	WEATHERING	L	4725.00 SqFt				
57	WEATHERING	M	525.00 SqFt				

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW K **Name:** TAXIWAY K **Use:** TAXIWAY **Area:** 199,709 SqFt

Section: 705 of 4 **From:** - **To:** - **Last Const.:** 1/1/2004

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 33,012 SqFt **Length:** 800 Ft **Width:** 60 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2004 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 8 **Surveyed:** 1

Conditions: PCI: 65

Inspection Comments:

Sample Number: 101 **Type:** R **Area:** 4349.00 SqFt **PCI:** 65

Sample Comments:

48	L & T CR	L	309.00 Ft
48	L & T CR	M	27.00 Ft
52	RAVELING	L	10.00 SqFt
57	WEATHERING	L	3471.00 SqFt
57	WEATHERING	M	868.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW K **Name:** TAXIWAY K **Use:** TAXIWAY **Area:** 199,709 SqFt

Section: 710 of 4 **From:** - **To:** - **Last Const.:** 1/1/2014

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 23,819 SqFt **Length:** 325 Ft **Width:** 70 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2014 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 5 **Surveyed:** 1

Conditions: PCI: 91

Inspection Comments:

Sample Number: 119 **Type:** R **Area:** 5410.00 SqFt **PCI:** 91

Sample Comments:

57 WEATHERING L 5140.00 SqFt

57 WEATHERING M 270.00 SqFt

Network: LEE **Name:** LEESBURG INTERNATIONAL AIRPORT

Branch: TW K **Name:** TAXIWAY K **Use:** TAXIWAY **Area:** 199,709 SqFt

Section: 715 of 4 **From:** - **To:** - **Last Const.:** 1/1/1986

Surface: AC **Family:** CA653-GA-TW-AC **Zone:** **Category:** **Rank:** P

Area: 4,634 SqFt **Length:** 100 Ft **Width:** 35 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/1986 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Last Insp. Date: 4/26/2022 **TotalSamples:** 1 **Surveyed:** 1

Conditions: PCI: 52

Inspection Comments:

Sample Number: 122 **Type:** R **Area:** 4634.00 SqFt **PCI:** 52

Sample Comments:

48	L & T CR	L	82.00 Ft
48	L & T CR	M	120.00 Ft
50	PATCHING	L	2000.00 SqFt
52	RAVELING	L	2622.00 SqFt
52	RAVELING	M	12.00 SqFt



FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE



AVIATION