

2022

Statewide Airfield Pavement Management Program



Airport Pavement Evaluation Report

OCF - Ocala International Airport - Jim Taylor Field | *District 5*



AVIATION



Florida Department of Transportation

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report

Prepared by:

*FDOT Aviation Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*

Website: [FDOT Aviation Office](#)

Interactive Web Application: [FDOT SAPMP Interactive Web Application](#)

TABLE OF CONTENTS

| | |
|---|-----------|
| EXECUTIVE SUMMARY | 1 |
| <i>Program Background.....</i> | <i>1</i> |
| <i>Current Pavement Conditions</i> | <i>2</i> |
| <i>Forecasted Pavement Conditions</i> | <i>3</i> |
| <i>Major Rehabilitation Planning 2023-2032</i> | <i>6</i> |
| CHAPTER 1 – INTRODUCTION..... | 9 |
| 1.1 Background | 9 |
| 1.2 Stakeholders..... | 11 |
| 1.3 General Scope of Work | 11 |
| 1.4 FDOT SAPMP Objectives | 12 |
| CHAPTER 2 – METHODOLOGY..... | 15 |
| 2.1 Airfield Pavement Database..... | 15 |
| 2.2 Airfield Pavement Record Keeping (Historical Records Research)..... | 16 |
| 2.3 Airfield Pavement Structure..... | 16 |
| 2.3.1 Asphalt Concrete..... | 17 |
| 2.3.2 Portland Cement Concrete | 17 |
| 2.3.3 Composite Structure – Whitetopping Pavement | 17 |
| 2.4 Airfield Pavement Traffic | 18 |
| 2.5 Pavement Management Program Network Definition Terminology | 18 |
| 2.5.1 Pavement Network Identification | 18 |
| 2.5.2 Pavement Branch Identification | 18 |
| 2.5.3 Pavement Section Identification | 19 |
| 2.5.4 Pavement Sample Unit Identification | 19 |
| 2.5.5 Terminology Summary | 19 |
| 2.6 Airfield PCI Survey Methodology | 19 |
| 2.6.1 Pavement Distress Types..... | 20 |
| 2.6.2 PCI Survey Procedures..... | 21 |
| CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY..... | 24 |
| 3.1 Airfield Pavement Network Information..... | 24 |
| 3.1.1 Previous and/or Anticipated Airfield Pavement Construction | 24 |
| 3.1.2 Estimated Pavement Age | 27 |
| 3.1.3 Functional Use | 29 |
| 3.1.4 Pavement Surface Type..... | 29 |
| 3.1.5 Pavement System Inventory Details | 30 |
| CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS | 33 |
| 4.1 Airfield Pavement Condition Index..... | 33 |
| 4.1.1 Network-Level Analysis..... | 33 |
| 4.1.2 Branch-Level Analysis..... | 33 |
| 4.1.3 Section-Level Analysis | 36 |
| 4.2 Summary of Pavement Condition Evaluation Results | 40 |

| | |
|---|-----------|
| 4.2.1 Network-Level Observations | 40 |
| 4.2.2 Branch-Level Observations | 40 |
| CHAPTER 5 – SAPMP CUSTOMIZATION..... | 55 |
| 5.1 Network-Level Customization..... | 55 |
| 5.2 Pavement Condition Forecasts | 55 |
| 5.2.1 Forecasting PCI Considerations | 56 |
| 5.2.2 Performance Models | 56 |
| 5.2.3 Branch-Level Pavement Condition Forecast..... | 56 |
| 5.2.4 Section-Level Pavement Condition Forecast..... | 57 |
| 5.3 Critical PCI Value..... | 59 |
| 5.4 Localized Maintenance and Repair | 62 |
| 5.4.1 Localized Maintenance and Repair Approach | 62 |
| 5.4.2 Localized Work Types | 63 |
| 5.4.3 Localized Maintenance Planning-Level Unit Costs | 65 |
| 5.4.4 Localized Maintenance and Repair Policy | 65 |
| 5.5 Major Rehabilitation | 68 |
| 5.5.1 Major Rehabilitation Pavement Section Development | 68 |
| 5.5.2 Major Rehabilitation Planning-Level Unit Costs | 70 |
| CHAPTER 6 – M&R PLANNING AND BUDGET SCENARIO ANALYSIS | 72 |
| 6.1 Localized Maintenance and Repair Analysis and Recommendations | 72 |
| 6.2 Major Rehabilitation Needs..... | 74 |
| 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs | 75 |
| CHAPTER 7 – CONCLUSION..... | 79 |
| 7.1 Recommendations | 79 |
| 7.1.1 Continued PCI Surveys | 79 |
| 7.1.2 Localized Maintenance and Repair | 79 |
| 7.1.3 Major Rehabilitation..... | 79 |
| 7.1.4 Pavement Management System..... | 79 |
| 7.2 Supporting Documents | 80 |
| Airfield Pavement Network Definition Exhibit..... | 80 |
| Airfield Pavement System Inventory Exhibit | 80 |
| Airfield Pavement Estimated Age Exhibit | 80 |
| Airfield Pavement Condition Index Exhibit..... | 80 |
| Airfield Pavement Major Rehabilitation Exhibit | 80 |
| Inspection Photograph Documentation..... | 80 |
| 7.3 Conclusion..... | 81 |
| 7.4 References..... | 81 |

APPENDIX


Appendix A: Airfield Pavement Analysis

Appendix B: Maintenance and Rehabilitation Planning Needs

Appendix C: Technical Exhibits

Appendix D: Inspection Photograph Documentation

Appendix E: Inspection Distress Details



LIST OF TABLES

| | |
|---|----|
| Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level..... | 2 |
| Table E.2: Forecasted PCI Values 2023-2032 – Section-Level..... | 4 |
| Table E.3: Major Rehabilitation Planning 2023-2032..... | 6 |
| Table 1.2: FDOT SAPMP Stakeholders | 11 |
| Table 2.5.5: SAPMP Terminology | 19 |
| Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete | 20 |
| Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete..... | 21 |
| Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete..... | 21 |
| Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete | 22 |
| Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction | 24 |
| Table 3.1.5: Pavement System Inventory Details | 30 |
| Table 4.1.2: Current Condition Summary – Branch-Level | 36 |
| Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level..... | 37 |
| Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level | 57 |
| Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects..... | 60 |
| Table 5.3 (b): Critical PCI Values by Branch Use | 60 |
| Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete | 65 |
| Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete..... | 65 |
| Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy | 66 |
| Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy | 67 |
| Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation | 69 |
| Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type | 70 |
| Table 6.1 (a): Year 1 Summary of Localized Maintenance | 72 |
| Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary | 73 |
| Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary | 73 |
| Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs | 75 |

LIST OF FIGURES

| | |
|---|----|
| Figure E.1: PCI Rating | 1 |
| Figure E.2: Current Condition Summary – Branch-Level | 2 |
| Figure E.3: 10-Year Major Rehabilitation Needs by Program Year | 7 |
| Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts | 10 |
| Figure 1.4: Pavement Life and the Effect of Treatments | 13 |
| Figure 2: FDOT SAPMP General Process | 15 |
| Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit | 25 |
| Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit | 26 |
| Figure 3.1.2 (a): Age of Pavements at PCI Survey | 27 |
| Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit | 28 |
| Figure 3.1.3: Airfield Pavement Branch Use by Area (SF) | 29 |
| Figure 3.1.4: Airfield Pavement Surface Type by Area (SF) | 30 |
| Figure 4.1.1: Current Condition – Overall Network | 33 |
| Figure 4.1.2 (a): Current Condition Summary – Branch-Level | 33 |
| Figure 4.1.2 (b): Current Condition – Runway | 34 |
| Figure 4.1.2 (c): Current Condition – Taxiway | 34 |
| Figure 4.1.2 (d): Current Condition – Taxilane | 35 |
| Figure 4.1.2 (e): Current Condition – Apron | 35 |
| Figure 4.1.3: Airfield Pavement Condition Index Exhibit | 39 |
| Figure 5.2.3: Forecasted Branch-Level Pavement Performance | 56 |
| Figure 5.3 (a): Pavement Life and the Effect of Treatments | 59 |
| Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical } PCI$ | 61 |
| Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical } PCI$ | 61 |
| Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year | 76 |
| Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit | 77 |



Executive Summary



Executive Summary

Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Ocala International Airport - Jim Taylor Field's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section. This is graphically depicted in **Figure E.1**.

Figure E.1: PCI Rating

| Color | Range | Condition Rating |
|-------|--------|------------------|
| | 86-100 | Good |
| | 71-85 | Satisfactory |
| | 56-70 | Fair |
| | 41-55 | Poor |
| | 26-40 | Very Poor |
| | 11-25 | Serious |
| | 0-10 | Failed |

Current Pavement Conditions

In April 2022, approximately 3.1 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Ocala International Airport - Jim Taylor Field (OCF). In general, airfield pavements at OCF are in Satisfactory condition with an area-weighted PCI of 84. The area-weighted average PCI values of the runways, taxiways, taxilanes, and aprons are 85, 88, 58, and 84, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for OCF.

Figure E.2: Current Condition Summary – Branch-Level




Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|------------|------------|-----------|-----|------------------|
| OCF | RW 8-26 | Runway | 6205 | 150,450 | 90 | Good |
| OCF | RW 18-36 | Runway | 6105 | 373,275 | 84 | Satisfactory |
| OCF | RW 18-36 | Runway | 6110 | 373,275 | 83 | Satisfactory |
| OCF | RW 18-36 | Runway | 6125 | 94,500 | 87 | Good |
| OCF | RW 18-36 | Runway | 6135 | 189,000 | 85 | Satisfactory |
| OCF | RW 18-36 | Runway | 6190 | 30,000 | 86 | Good |
| OCF | RW 18-36 | Runway | 6195 | 60,000 | 86 | Good |
| OCF | TW A | Taxiway | 304 | 11,360 | 100 | Good |
| OCF | TW A | Taxiway | 305 | 4,941 | 88 | Good |
| OCF | TW A | Taxiway | 505 | 210,730 | 100 | Good |
| OCF | TW A | Taxiway | 540 | 104,692 | 100 | Good |
| OCF | TW A | Taxiway | 542 | 34,610 | 100 | Good |
| OCF | TW A1 | Taxiway | 592 | 23,030 | 100 | Good |
| OCF | TW A10 | Taxiway | 535 | 28,064 | 100 | Good |
| OCF | TW A11 | Taxiway | 545 | 23,035 | 100 | Good |
| OCF | TW A12 | Taxiway | 555 | 33,994 | 82 | Satisfactory |

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|------------|------------|-----------|-----|------------------|
| OCF | TW A13 | Taxiway | 596 | 54,138 | 80 | Satisfactory |
| OCF | TW A2 | Taxiway | 501 | 31,144 | 100 | Good |
| OCF | TW A3 | Taxiway | 510 | 3,960 | 75 | Satisfactory |
| OCF | TW A3 | Taxiway | 512 | 17,192 | 100 | Good |
| OCF | TW A4 | Taxiway | 514 | 11,036 | 74 | Satisfactory |
| OCF | TW A4 | Taxiway | 515 | 3,791 | 100 | Good |
| OCF | TW A5 | Taxiway | 520 | 16,927 | 81 | Satisfactory |
| OCF | TW A6 | Taxiway | 532 | 21,348 | 100 | Good |
| OCF | TW A7 | Taxiway | 525 | 16,153 | 58 | Fair |
| OCF | TW A8 | Taxiway | 560 | 15,868 | 78 | Satisfactory |
| OCF | TW A8 | Taxiway | 562 | 17,373 | 100 | Good |
| OCF | TW A8 | Taxiway | 565 | 15,850 | 85 | Satisfactory |
| OCF | TW A8 | Taxiway | 570 | 6,990 | 65 | Fair |
| OCF | TW A8 | Taxiway | 575 | 12,102 | 79 | Satisfactory |
| OCF | TW A9 | Taxiway | 550 | 27,079 | 74 | Satisfactory |
| OCF | TW A9 | Taxiway | 552 | 15,600 | 100 | Good |
| OCF | TW AP N | Taxiway | 595 | 33,596 | 70 | Fair |
| OCF | TW B | Taxiway | 105 | 73,305 | 51 | Poor |
| OCF | TW B1 | Taxiway | 104 | 5,513 | 59 | Fair |
| OCF | TW B2 | Taxiway | 106 | 6,834 | 52 | Poor |
| OCF | TW B3 | Taxiway | 102 | 5,513 | 55 | Poor |
| OCF | TL T-HANG | Taxilane | 3580 | 18,904 | 40 | Very Poor |
| OCF | TL T-HANG | Taxilane | 3585 | 76,028 | 52 | Poor |
| OCF | TL T-HANG | Taxilane | 3590 | 5,246 | 80 | Satisfactory |
| OCF | TL T-HANG | Taxilane | 3592 | 23,614 | 87 | Good |
| OCF | AP CENTER | Apron | 4105 | 168,599 | 52 | Poor |
| OCF | AP CENTER | Apron | 4107 | 93,441 | 100 | Good |
| OCF | AP CENTER | Apron | 4110 | 81,895 | 100 | Good |
| OCF | AP CENTER | Apron | 4115 | 120,000 | 100 | Good |
| OCF | AP CENTER | Apron | 4120 | 95,753 | 100 | Good |
| OCF | AP CENTER | Apron | 4125 | 30,574 | 100 | Good |
| OCF | AP CENTER | Apron | 4130 | 19,665 | 100 | Good |
| OCF | AP CENTER | Apron | 4135 | 123,619 | 84 | Satisfactory |
| OCF | AP CENTER | Apron | 4145 | 6,660 | 100 | Good |
| OCF | AP CENTER | Apron | 4150 | 6,000 | 33 | Very Poor |
| OCF | AP N | Apron | 4205 | 19,584 | 70 | Fair |
| OCF | AP N | Apron | 4210 | 41,762 | 55 | Poor |
| OCF | AP S | Apron | 4305 | 47,250 | 78 | Satisfactory |

Forecasted Pavement Conditions

Table E.2 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI

data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

Table E.2: Forecasted PCI Values 2023-2032 – Section-Level

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|------------|-----------|------------|-------------|------|------|------|------|------|------|------|------|------|------|
| OCF | RW 8-26 | 6205 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 70 |
| OCF | RW 18-36 | 6105 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 66 | 64 |
| OCF | RW 18-36 | 6110 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 | 65 | 63 |
| OCF | RW 18-36 | 6125 | 87 | 85 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 |
| OCF | RW 18-36 | 6135 | 85 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 | 65 |
| OCF | RW 18-36 | 6190 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 | 69 |
| OCF | RW 18-36 | 6195 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 | 69 |
| OCF | TW A | 304 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 305 | 88 | 86 | 84 | 82 | 80 | 78 | 77 | 75 | 74 | 73 | 71 |
| OCF | TW A | 505 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 540 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 542 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A1 | 592 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A10 | 535 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A11 | 545 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A12 | 555 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 69 | 68 |
| OCF | TW A13 | 596 | 80 | 78 | 76 | 75 | 74 | 72 | 71 | 70 | 69 | 67 | 66 |
| OCF | TW A2 | 501 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A3 | 510 | 75 | 73 | 72 | 71 | 69 | 68 | 67 | 66 | 65 | 64 | 63 |
| OCF | TW A3 | 512 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A4 | 514 | 74 | 72 | 71 | 70 | 68 | 67 | 66 | 65 | 64 | 62 | 61 |
| OCF | TW A4 | 515 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A5 | 520 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 | 68 | 67 |
| OCF | TW A6 | 532 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A7 | 525 | 58 | 56 | 55 | 53 | 52 | 50 | 48 | 46 | 44 | 42 | 40 |
| OCF | TW A8 | 560 | 78 | 76 | 75 | 73 | 72 | 71 | 69 | 68 | 67 | 66 | 65 |
| OCF | TW A8 | 562 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A8 | 565 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 | 72 | 71 | 69 |
| OCF | TW A8 | 570 | 65 | 64 | 63 | 62 | 61 | 61 | 60 | 59 | 58 | 58 | 57 |
| OCF | TW A8 | 575 | 79 | 77 | 76 | 74 | 73 | 71 | 70 | 69 | 68 | 66 | 65 |
| OCF | TW A9 | 550 | 74 | 72 | 71 | 70 | 69 | 68 | 66 | 65 | 64 | 64 | 63 |
| OCF | TW A9 | 552 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW AP N | 595 | 70 | 69 | 67 | 66 | 65 | 64 | 63 | 63 | 62 | 61 | 60 |
| OCF | TW B | 105 | 51 | 50 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 47 | 46 |
| OCF | TW B1 | 104 | 59 | 58 | 58 | 57 | 56 | 56 | 55 | 55 | 54 | 54 | 53 |
| OCF | TW B2 | 106 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| OCF | TW B3 | 102 | 55 | 54 | 54 | 53 | 53 | 53 | 52 | 52 | 51 | 51 | 50 |
| OCF | TL T-HANG | 3580 | 40 | 39 | 38 | 37 | 36 | 35 | 34 | 33 | 31 | 30 | 29 |
| OCF | TL T-HANG | 3585 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| OCF | TL T-HANG | 3590 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 68 | 67 | 66 |

Airport Pavement Evaluation Report

Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|------------|-----------|------------|-------------|------|------|------|------|------|------|------|------|------|------|
| OCF | TL T-HANG | 3592 | 87 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 | 72 | 71 |
| OCF | AP CENTER | 4105 | 52 | 50 | 48 | 46 | 44 | 42 | 40 | 38 | 36 | 34 | 32 |
| OCF | AP CENTER | 4107 | 100 | 95 | 93 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 |
| OCF | AP CENTER | 4110 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4115 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4120 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4125 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4130 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4135 | 84 | 82 | 80 | 78 | 76 | 74 | 73 | 71 | 69 | 68 | 66 |
| OCF | AP CENTER | 4145 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4150 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 26 | 25 | 24 | 23 |
| OCF | AP N | 4205 | 70 | 68 | 67 | 65 | 64 | 63 | 61 | 60 | 59 | 58 | 57 |
| OCF | AP N | 4210 | 55 | 54 | 53 | 52 | 51 | 51 | 50 | 49 | 48 | 48 | 47 |
| OCF | AP S | 4305 | 78 | 76 | 74 | 72 | 71 | 69 | 68 | 66 | 65 | 64 | 62 |

Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$25.71M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$7.16M and localized maintenance needs for Year 1 are \$0.05M.


Table E.3: Major Rehabilitation Planning 2023-2032

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost Estimate |
|--------------|------------|-----------|------------|---------|-----------|------------|---------------------|------------------------|
| 2023 | OCF | TW A7 | 525 | AAC | 16,153 | 56 | AC Rehabilitation | \$ 146,000 |
| 2023 | OCF | TW A8 | 570 | AC | 6,990 | 64 | AC Rehabilitation | \$ 63,000 |
| 2023 | OCF | TW AP N | 595 | AC | 33,596 | 69 | AC Rehabilitation | \$ 303,000 |
| 2023 | OCF | TW B | 105 | AC | 73,305 | 50 | AC Reconstruction | \$ 1,173,000 |
| 2023 | OCF | TW B1 | 104 | AC | 5,513 | 58 | AC Rehabilitation | \$ 50,000 |
| 2023 | OCF | TW B2 | 106 | AC | 6,834 | 51 | AC Reconstruction | \$ 110,000 |
| 2023 | OCF | TW B3 | 102 | AC | 5,513 | 54 | AC Reconstruction | \$ 73,000 |
| 2023 | OCF | TL T-HANG | 3580 | AC | 18,904 | 39 | AC Reconstruction | \$ 303,000 |
| 2023 | OCF | TL T-HANG | 3585 | AC | 76,028 | 51 | AC Reconstruction | \$ 1,217,000 |
| 2023 | OCF | AP CENTER | 4105 | AAC | 168,599 | 50 | AC Reconstruction | \$ 2,698,000 |
| 2023 | OCF | AP CENTER | 4150 | PCC | 6,000 | 32 | PCC Reconstruction | \$ 174,000 |
| 2023 | OCF | AP N | 4205 | AC | 19,584 | 68 | AC Rehabilitation | \$ 177,000 |
| 2023 | OCF | AP N | 4210 | AC | 41,762 | 54 | AC Reconstruction | \$ 669,000 |
| 2025 | OCF | TW A4 | 514 | AAC | 11,036 | 70 | AC Rehabilitation | \$ 110,000 |
| 2025 | OCF | TW A9 | 550 | AC | 27,079 | 70 | AC Rehabilitation | \$ 269,000 |
| 2026 | OCF | TW A3 | 510 | AC | 3,960 | 69 | AC Rehabilitation | \$ 42,000 |
| 2027 | OCF | AP S | 4305 | AC | 47,250 | 69 | AC Rehabilitation | \$ 517,000 |
| 2028 | OCF | TW A8 | 560 | AC | 15,868 | 69 | AC Rehabilitation | \$ 183,000 |
| 2029 | OCF | RW 18-36 | 6110 | AAC | 373,275 | 69 | AC Rehabilitation | \$ 4,503,000 |

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost Estimate |
|--------------|------------|-----------|------------|---------|-----------|------------|---------------------|------------------------|
| 2029 | OCF | TW A13 | 596 | AC | 54,138 | 70 | AC Rehabilitation | \$ 653,000 |
| 2029 | OCF | TW A8 | 575 | AAC | 12,102 | 69 | AC Rehabilitation | \$ 146,000 |
| 2029 | OCF | TL T-HANG | 3590 | AAC | 5,246 | 70 | AC Rehabilitation | \$ 64,000 |
| 2030 | OCF | RW 18-36 | 6105 | AAC | 373,275 | 68 | AC Rehabilitation | \$ 4,728,000 |
| 2030 | OCF | RW 18-36 | 6135 | AAC | 189,000 | 69 | AC Rehabilitation | \$ 2,394,000 |
| 2030 | OCF | TW A12 | 555 | AC | 33,994 | 70 | AC Rehabilitation | \$ 431,000 |
| 2030 | OCF | TW A5 | 520 | AAC | 16,927 | 69 | AC Rehabilitation | \$ 215,000 |
| 2030 | OCF | AP CENTER | 4135 | AC | 123,619 | 69 | AC Rehabilitation | \$ 1,566,000 |
| 2031 | OCF | RW 18-36 | 6125 | AAC | 94,500 | 69 | AC Rehabilitation | \$ 1,257,000 |
| 2032 | OCF | RW 18-36 | 6190 | AC | 30,000 | 69 | AC Rehabilitation | \$ 419,000 |
| 2032 | OCF | RW 18-36 | 6195 | AC | 60,000 | 69 | AC Rehabilitation | \$ 838,000 |
| 2032 | OCF | TW A8 | 565 | AC | 15,850 | 69 | AC Rehabilitation | \$ 222,000 |

*All planning cost values have been rounded up to the nearest thousand dollars.

Figure E.3: 10-Year Major Rehabilitation Needs by Program Year





Chapter 1: Introduction



Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida's economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida's most prominent industry.

1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management Program (PMP)". The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are

Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts



1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

Table 1.2: FDOT SAPMP Stakeholders

| Role | Description |
|---|---|
| FAA Orlando Airports District Office (Orlando ADO) | Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation). |
| Florida Department of Transportation (FDOT) | Key Stakeholder: the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System. |
| FDOT District Offices | The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes. |
| Participating Public-Use and Publicly-Owned Airports | The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment. |
| Aviation Office Program Manager (AO-PM) | FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update. |

1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- » Research and evaluation of existing record documentation;
- » Establishment of a pavement system inventory;
- » Development of a pavement network definition map and supplemental GIS model;
- » Functional pavement evaluations via the PCI assessment method;
- » Customization of PAVER™ software including prioritization, policies, and performance models;
- » Analysis of condition data; and
- » Maintenance, repair, and rehabilitation planning.

1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.


A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:

- » Assist airports in meeting the requirements of Public Law 103-305;
- » Assist airports in complying with FAA Grant Assurances 11 and 19;
- » Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- » Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- » Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.

Figure 1.4: Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds: ☐ >70: Routine Maintenance ☐ 55-70: Rehabilitation Eligible ☐ <55: Reconstruction Eligible

*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements




Chapter 2: Methodology



Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.

Figure 2: FDOT SAPMP General Process



2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- » Create a manageable inventory system;
- » Analyze the current condition of pavements in accordance with ASTM D5340-20;
- » Develop pavement performance models to forecast conditions; and
- » Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database and typically consist of pavement inventory

characteristics, pavement structure, work history, historic condition records, and analytical customization.

2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- » Location and limits of work;
- » Types and severities of repaired distresses;
- » Work type and cost; and
- » Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- » Date of last construction/rehabilitation
- » Work type performed
- » Comments for documenting pavement cross-section
- » Pavement surface type
- » Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.

2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

Conventional Whitetopping (WT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

Ultra-Thin Whitetopping (UWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

2.4 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of OCF's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.5 Pavement Management Program Network Definition Terminology

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

2.5.1 Pavement Network Identification

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

2.5.2 Pavement Branch Identification

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.

2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs (± 8 slabs) for PCC pavement and 5,000 contiguous square feet ($\pm 2,000$ SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

Table 2.5.5: SAPMP Terminology

| SAPMP Terminology | Common Definition | Airport Example |
|--------------------|---|---|
| Network | Totality of pavement assets maintained by the Airport. | "Tallahassee International Airport – Airfield Pavements" |
| Branch Name | Commonly defined asset name as established by Airport and by use. | "Runway 18-36" |
| Branch ID | Codified shorthand name for commonly defined asset established for database identification. | "RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility |
| Section ID | Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition. | "6105" |
| Sample Unit | A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20. | "300" |

2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete

| Distress Mechanism | Distress Type |
|-----------------------|---|
| Load | Alligator Cracking Rutting |
| Climate/Durability | Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering |
| Construction/Material | Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling |
| Other | Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching |

Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete

| Distress Mechanism | Distress Type |
|-----------------------|--|
| Load | Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks |
| Climate/Durability | Blowup Durability "D" Cracking Joint Seal Damage Popouts |
| Construction/Material | Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking |
| Other | Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching |

2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.


Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete

| Number of Total Sample Units in Section | Runway Sampling Rate | Taxiways, Aprons, and Others Sampling Rate |
|---|----------------------|--|
| 1 - 4 | 1 | 1 |
| 5 - 10 | 2 | 1 |
| 11 - 15 | 3 | 2 |
| 16 - 30 | 5 | 3 |
| 31 - 40 | 7 | 4 |
| 41 - 50 | 8 | 5 |
| 51 or more | 20% but ≤ 20 | 10% but ≤ 10 |


Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete

| Number of Total Sample Units in Section | Runway Sampling Rate | Taxiways, Aprons, and Others Sampling Rate |
|---|----------------------|--|
| 1 - 3 | 1 | 1 |
| 4 - 6 | 2 | 1 |
| 7 - 10 | 3 | 2 |
| 11 - 15 | 4 | 2 |
| 16 - 20 | 5 | 3 |
| 21 - 30 | 7 | 3 |
| 31 - 40 | 8 | 4 |
| 41 - 50 | 10 | 5 |
| 51 or more | 20% but ≤ 20 | 10% but ≤ 10 |

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.



Chapter 3: Airfield Pavement System Inventory



Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction


Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.


Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction

| Construction Year | Location | Work Type / Pavement Section |
|-------------------|---|--|
| 2021 | TW A, TW A2, TW A3, TW A4, TW A8, TW A9 | Mill and Overlay 3" Mill, Variable Depth P-401 Overlay |
| | TW A1, TW A6, AP CENTER | New Construction - AC 4" SP 12.5, 10" LBR 100 Limerock |
| | TW A, TW A10, TW A11 | Mill and Overlay 4" Mill, Variable Depth P-401 Overlay |
| | TW A | New Construction - AC 4" P-401, 12" Limerock Base Course, P-152 Subgrade |
| | AP CENTER | Mill and Overlay 3" Mill, 3" SP 12.5 Overlay |

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

Figure 3.1.1 (a), the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.







3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.

Figure 3.1.2 (a): Age of Pavements at PCI Survey






3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed “functional use” or “branch use.” For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.

Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)




3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at OCF.

Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)



3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

Table 3.1.5 displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

Table 3.1.5: Pavement System Inventory Details

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|--------------|------------------------------------|
| OCF | RW 8-26 | Runway | 6205 | 150,450 | AAC | 1/1/2013 |
| OCF | RW 18-36 | Runway | 6105 | 373,275 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6110 | 373,275 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6125 | 94,500 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6135 | 189,000 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6190 | 30,000 | AC | 1/1/2008 |
| OCF | RW 18-36 | Runway | 6195 | 60,000 | AC | 1/1/2008 |
| OCF | TW A | Taxiway | 304 | 11,360 | AAC | 7/1/2021 |

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|--------------|------------------------------------|
| OCF | TW A | Taxiway | 305 | 4,941 | AAC | 1/1/2013 |
| OCF | TW A | Taxiway | 505 | 210,730 | AAC | 7/1/2021 |
| OCF | TW A | Taxiway | 540 | 104,692 | AAC | 7/1/2021 |
| OCF | TW A | Taxiway | 542 | 34,610 | AC | 7/1/2021 |
| OCF | TW A1 | Taxiway | 592 | 23,030 | AC | 7/1/2021 |
| OCF | TW A10 | Taxiway | 535 | 28,064 | AAC | 7/1/2021 |
| OCF | TW A11 | Taxiway | 545 | 23,035 | AAC | 7/1/2021 |
| OCF | TW A12 | Taxiway | 555 | 33,994 | AC | 1/1/2008 |
| OCF | TW A13 | Taxiway | 596 | 54,138 | AC | 1/1/2008 |
| OCF | TW A2 | Taxiway | 501 | 31,144 | AAC | 7/1/2021 |
| OCF | TW A3 | Taxiway | 510 | 3,960 | AC | 1/1/1985 |
| OCF | TW A3 | Taxiway | 512 | 17,192 | AAC | 7/1/2021 |
| OCF | TW A4 | Taxiway | 514 | 11,036 | AAC | 1/1/2009 |
| OCF | TW A4 | Taxiway | 515 | 3,791 | AAC | 7/1/2021 |
| OCF | TW A5 | Taxiway | 520 | 16,927 | AAC | 1/1/1977 |
| OCF | TW A6 | Taxiway | 532 | 21,348 | AC | 7/1/2021 |
| OCF | TW A7 | Taxiway | 525 | 16,153 | AAC | 1/1/1977 |
| OCF | TW A8 | Taxiway | 560 | 15,868 | AC | 1/1/2000 |
| OCF | TW A8 | Taxiway | 562 | 17,373 | AAC | 7/1/2021 |
| OCF | TW A8 | Taxiway | 565 | 15,850 | AC | 1/1/2000 |
| OCF | TW A8 | Taxiway | 570 | 6,990 | AC | 1/1/2000 |
| OCF | TW A8 | Taxiway | 575 | 12,102 | AAC | 1/1/2010 |
| OCF | TW A9 | Taxiway | 550 | 27,079 | AC | 1/1/2000 |
| OCF | TW A9 | Taxiway | 552 | 15,600 | AAC | 7/1/2021 |
| OCF | TW AP N | Taxiway | 595 | 33,596 | AC | 1/1/2000 |
| OCF | TW B | Taxiway | 105 | 73,305 | AC | 1/1/1985 |
| OCF | TW B1 | Taxiway | 104 | 5,513 | AC | 1/1/1985 |
| OCF | TW B2 | Taxiway | 106 | 6,834 | AC | 1/1/1985 |
| OCF | TW B3 | Taxiway | 102 | 5,513 | AC | 1/1/1985 |
| OCF | TL T-HANG | Taxilane | 3580 | 18,904 | AC | 1/1/2000 |
| OCF | TL T-HANG | Taxilane | 3585 | 76,028 | AC | 1/1/2000 |
| OCF | TL T-HANG | Taxilane | 3590 | 5,246 | AAC | 1/1/2009 |
| OCF | TL T-HANG | Taxilane | 3592 | 23,614 | AC | 1/1/2009 |
| OCF | AP CENTER | Apron | 4105 | 168,599 | AAC | 1/1/1991 |
| OCF | AP CENTER | Apron | 4107 | 93,441 | AC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4110 | 81,895 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4115 | 120,000 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4120 | 95,753 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4125 | 30,574 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4130 | 19,665 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4135 | 123,619 | AC | 7/1/2009 |
| OCF | AP CENTER | Apron | 4145 | 6,660 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4150 | 6,000 | PCC | 1/1/1999 |
| OCF | AP N | Apron | 4205 | 19,584 | AC | 1/1/2000 |
| OCF | AP N | Apron | 4210 | 41,762 | AC | 1/1/2000 |
| OCF | AP S | Apron | 4305 | 47,250 | AC | 1/1/2010 |



Chapter 4: Airfield Pavement Condition Analysis



Chapter 4 – Airfield Pavement Condition Analysis


The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for design-and/or project-level determination of pavement rehabilitation needs.

4.1 Airfield Pavement Condition Index

4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 84% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 3% of inspected pavements are in Fair condition and the remaining 13% of inspected pavements are in Poor or worse condition.

Figure 4.1.1: Current Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(e)** summarize branch-level pavement conditions according to the most recent PCI assessment results.

Figure 4.1.2 (a): Current Condition Summary – Branch-Level




Figure 4.1.2 (b): Current Condition – Runway




Figure 4.1.2 (c): Current Condition – Taxiway




Figure 4.1.2 (d): Current Condition – Taxi lane




Figure 4.1.2 (e): Current Condition – Apron




Table 4.1.2 details the branch-level condition for each airfield pavement branch.

Table 4.1.2: Current Condition Summary – Branch-Level

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Area-Weighted Avg PCI | Condition Rating |
|-----------|------------|--------------------|------------------|-----------------------|------------------|
| RW 8-26 | Runway | 1 | 150,450 | 90 | Good |
| RW 18-36 | Runway | 6 | 1,120,050 | 84 | Satisfactory |
| TW A | Taxiway | 5 | 366,333 | 100 | Good |
| TW A1 | Taxiway | 1 | 23,030 | 100 | Good |
| TW A10 | Taxiway | 1 | 28,064 | 100 | Good |
| TW A11 | Taxiway | 1 | 23,035 | 100 | Good |
| TW A12 | Taxiway | 1 | 33,994 | 82 | Satisfactory |
| TW A13 | Taxiway | 1 | 54,138 | 80 | Satisfactory |
| TW A2 | Taxiway | 1 | 31,144 | 100 | Good |
| TW A3 | Taxiway | 2 | 21,152 | 95 | Good |
| TW A4 | Taxiway | 2 | 14,827 | 81 | Satisfactory |
| TW A5 | Taxiway | 1 | 16,927 | 81 | Satisfactory |
| TW A6 | Taxiway | 1 | 21,348 | 100 | Good |
| TW A7 | Taxiway | 1 | 16,153 | 58 | Fair |
| TW A8 | Taxiway | 5 | 68,183 | 84 | Satisfactory |
| TW A9 | Taxiway | 2 | 42,679 | 84 | Satisfactory |
| TW AP N | Taxiway | 1 | 33,596 | 70 | Fair |
| TW B | Taxiway | 1 | 73,305 | 51 | Poor |
| TW B1 | Taxiway | 1 | 5,513 | 59 | Fair |
| TW B2 | Taxiway | 1 | 6,834 | 52 | Poor |
| TW B3 | Taxiway | 1 | 5,513 | 55 | Poor |
| TL T-HANG | Taxilane | 4 | 123,792 | 58 | Fair |
| AP CENTER | Apron | 10 | 746,206 | 86 | Good |
| AP N | Apron | 2 | 61,346 | 60 | Fair |
| AP S | Apron | 1 | 47,250 | 78 | Satisfactory |

4.1.3 Section-Level Analysis

Table 4.1.3 provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.


Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.

Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface | PCI | Condition Rating | PCI % Climate | PCI % Load | PCI % Other | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|------------|------------|-----------|---------|-----|------------------|---------------|------------|-------------|------------------------|-------------------------------|
| OCF | RW 8-26 | Runway | 6205 | 150,450 | AAC | 90 | Good | 100 | 0 | 0 | 6 | 30 |
| OCF | RW 18-36 | Runway | 6105 | 373,275 | AAC | 84 | Satisfactory | 94 | 0 | 6 | 20 | 99 |
| OCF | RW 18-36 | Runway | 6110 | 373,275 | AAC | 83 | Satisfactory | 96 | 0 | 4 | 21 | 100 |
| OCF | RW 18-36 | Runway | 6125 | 94,500 | AAC | 87 | Good | 93 | 0 | 7 | 5 | 19 |
| OCF | RW 18-36 | Runway | 6135 | 189,000 | AAC | 85 | Satisfactory | 89 | 0 | 11 | 7 | 38 |
| OCF | RW 18-36 | Runway | 6190 | 30,000 | AC | 86 | Good | 100 | 0 | 0 | 2 | 6 |
| OCF | RW 18-36 | Runway | 6195 | 60,000 | AC | 86 | Good | 100 | 0 | 0 | 3 | 12 |
| OCF | TW A | Taxiway | 304 | 11,360 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A | Taxiway | 305 | 4,941 | AAC | 88 | Good | 100 | 0 | 0 | 1 | 1 |
| OCF | TW A | Taxiway | 505 | 210,730 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A | Taxiway | 540 | 104,692 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A | Taxiway | 542 | 34,610 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A1 | Taxiway | 592 | 23,030 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A10 | Taxiway | 535 | 28,064 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A11 | Taxiway | 545 | 23,035 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A12 | Taxiway | 555 | 33,994 | AC | 82 | Satisfactory | 76 | 0 | 24 | 1 | 8 |
| OCF | TW A13 | Taxiway | 596 | 54,138 | AC | 80 | Satisfactory | 100 | 0 | 0 | 2 | 14 |
| OCF | TW A2 | Taxiway | 501 | 31,144 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A3 | Taxiway | 510 | 3,960 | AC | 75 | Satisfactory | 100 | 0 | 0 | 1 | 1 |
| OCF | TW A3 | Taxiway | 512 | 17,192 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A4 | Taxiway | 514 | 11,036 | AAC | 74 | Satisfactory | 97 | 0 | 3 | 1 | 2 |
| OCF | TW A4 | Taxiway | 515 | 3,791 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A5 | Taxiway | 520 | 16,927 | AAC | 81 | Satisfactory | 100 | 0 | 0 | 1 | 4 |
| OCF | TW A6 | Taxiway | 532 | 21,348 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A7 | Taxiway | 525 | 16,153 | AAC | 58 | Fair | 93 | 0 | 7 | 1 | 3 |
| OCF | TW A8 | Taxiway | 560 | 15,868 | AC | 78 | Satisfactory | 100 | 0 | 0 | 1 | 4 |
| OCF | TW A8 | Taxiway | 562 | 17,373 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW A8 | Taxiway | 565 | 15,850 | AC | 85 | Satisfactory | 100 | 0 | 0 | 1 | 4 |
| OCF | TW A8 | Taxiway | 570 | 6,990 | AC | 65 | Fair | 99 | 0 | 1 | 1 | 2 |
| OCF | TW A8 | Taxiway | 575 | 12,102 | AAC | 79 | Satisfactory | 100 | 0 | 0 | 1 | 3 |
| OCF | TW A9 | Taxiway | 550 | 27,079 | AC | 74 | Satisfactory | 63 | 0 | 37 | 2 | 5 |
| OCF | TW A9 | Taxiway | 552 | 15,600 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | TW AP N | Taxiway | 595 | 33,596 | AC | 70 | Fair | 57 | 43 | 0 | 2 | 8 |
| OCF | TW B | Taxiway | 105 | 73,305 | AC | 51 | Poor | 94 | 0 | 6 | 4 | 15 |
| OCF | TW B1 | Taxiway | 104 | 5,513 | AC | 59 | Fair | 95 | 0 | 5 | 1 | 1 |
| OCF | TW B2 | Taxiway | 106 | 6,834 | AC | 52 | Poor | 99 | 0 | 1 | 1 | 1 |
| OCF | TW B3 | Taxiway | 102 | 5,513 | AC | 55 | Poor | 100 | 0 | 0 | 1 | 1 |
| OCF | TL T-HANG | Taxilane | 3580 | 18,904 | AC | 40 | Very Poor | 45 | 51 | 4 | 1 | 4 |
| OCF | TL T-HANG | Taxilane | 3585 | 76,028 | AC | 52 | Poor | 95 | 0 | 5 | 4 | 16 |
| OCF | TL T-HANG | Taxilane | 3590 | 5,246 | AAC | 80 | Satisfactory | 100 | 0 | 0 | 1 | 1 |
| OCF | TL T-HANG | Taxilane | 3592 | 23,614 | AC | 87 | Good | 100 | 0 | 0 | 1 | 5 |
| OCF | AP CENTER | Apron | 4105 | 168,599 | AAC | 52 | Poor | 85 | 0 | 15 | 4 | 36 |
| OCF | AP CENTER | Apron | 4107 | 93,441 | AC | 100 | Good | 0 | 0 | 0 | 0 | 0 |

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface | PCI | Condition Rating | PCI % Climate | PCI % Load | PCI % Other | Sample Units Inspected | Total Sample Units in Section |
|------------|-----------|------------|------------|-----------|---------|-----|------------------|---------------|------------|-------------|------------------------|-------------------------------|
| OCF | AP CENTER | Apron | 4110 | 81,895 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | AP CENTER | Apron | 4115 | 120,000 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | AP CENTER | Apron | 4120 | 95,753 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | AP CENTER | Apron | 4125 | 30,574 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | AP CENTER | Apron | 4130 | 19,665 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | AP CENTER | Apron | 4135 | 123,619 | AC | 84 | Satisfactory | 90 | 0 | 10 | 5 | 27 |
| OCF | AP CENTER | Apron | 4145 | 6,660 | AAC | 100 | Good | 0 | 0 | 0 | 0 | 0 |
| OCF | AP CENTER | Apron | 4150 | 6,000 | PCC | 33 | Very Poor | 13 | 87 | 0 | 1 | 1 |
| OCF | AP N | Apron | 4205 | 19,584 | AC | 70 | Fair | 94 | 0 | 6 | 1 | 4 |
| OCF | AP N | Apron | 4210 | 41,762 | AC | 55 | Poor | 100 | 0 | 0 | 1 | 8 |
| OCF | AP S | Apron | 4305 | 47,250 | AC | 78 | Satisfactory | 66 | 0 | 34 | 2 | 10 |

* Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.



4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The PCI assessment for Ocala International Airport - Jim Taylor Field (OCF) was performed in April 2022. The overall area-weighted average PCI value of the network was 84, representing a condition rating of Satisfactory. Due to recent work in 2021, most of Taxiway A and other Taxiway A connectors were not inspected. Also, a majority of the Center Apron was also not inspected due to recent rehabilitation.

Based on the FAA 5010 Report as of 10/06/2022, the Airport has reported 56,181 operations for 12 months ending 10/31/2021.

4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

Runways

RW 18-36

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| RW 18-36 | RUNWAY | 6 | 1,120,050 | 84 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 16% Good (86-100 PCI), 84% Satisfactory (71-85 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 6105 | AAC | 373,275 | 84 | Satisfactory |
| 6110 | AAC | 373,275 | 83 | Satisfactory |
| 6125 | AAC | 94,500 | 87 | Good |
| 6135 | AAC | 189,000 | 85 | Satisfactory |
| 6190 | AC | 30,000 | 86 | Good |


| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 6195 | AC | 60,000 | 86 | Good |

RW 18-36 consists of 6 flexible pavement sections, totaling 1,120,050 sf. The last major construction dates range from 2008 to 2009, resulting in an area-weighted average age at inspection of 13 years old. Overall, RW 18-36 is in Satisfactory condition with an area-weighted average PCI of 84.

RW 8-26

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| RW 8-26 | RUNWAY | 1 | 150,450 | 90 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 6205 | AAC | 150,450 | 90 | Good |


RW 8-26 consists of 1 flexible pavement section, totaling 150,450 sf. The last major construction date for the branch was 2013, resulting in an area-weighted average age at inspection of 9 years old. Overall, RW 8-26 is in Good condition with an area-weighted average PCI of 90.

Taxiways

TW A

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A | TAXIWAY | 5 | 366,333 | 100 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 304 | AAC | 11,360 | 100 | Good |
| 305 | AAC | 4,941 | 88 | Good |
| 505 | AAC | 210,730 | 100 | Good |
| 540 | AAC | 104,692 | 100 | Good |
| 542 | AC | 34,610 | 100 | Good |

TW A consists of 5 flexible pavement sections, totaling 366,333 sf. The last major construction dates range from 2013 to 2021. Overall, TW A is in Good condition with an area-weighted average PCI of 100.

TW A1

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A1 | TAXIWAY | 1 | 23,030 | 100 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 592 | AC | 23,030 | 100 | Good |

TW A1 consists of 1 flexible pavement section, totaling 23,030 sf. The last major construction date for the branch was 2021. Overall, TW A1 is in Good condition with an area-weighted average PCI of 100.

TW A10

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A10 | TAXIWAY | 1 | 28,064 | 100 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 535 | AAC | 28,064 | 100 | Good |

TW A10 consists of 1 flexible pavement section, totaling 28,064 sf. The last major construction date for the branch was 2021. Overall, TW A10 is in Good condition with an area-weighted average PCI of 100.

TW A11

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A11 | TAXIWAY | 1 | 23,035 | 100 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 545 | AAC | 23,035 | 100 | Good |

TW A11 consists of 1 flexible pavement section, totaling 23,035 sf. The last major construction date for the branch was 2021. Overall, TW A11 is in Good condition with an area-weighted average PCI of 100.

TW A12

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A12 | TAXIWAY | 1 | 33,994 | 82 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 555 | AC | 33,994 | 82 | Satisfactory |

TW A12 consists of 1 flexible pavement section, totaling 33,994 sf. The last major construction date for the branch was 2008, resulting in an area-weighted average age at inspection of 14 years old. Overall, TW A12 is in Satisfactory condition with an area-weighted average PCI of 82.

TW A13

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A13 | TAXIWAY | 1 | 54,138 | 80 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 596 | AC | 54,138 | 80 | Satisfactory |

TW A13 consists of 1 flexible pavement section, totaling 54,138 sf. The last major construction date for the branch was 2008, resulting in an area-weighted average age at inspection of 14 years old. Overall, TW A13 is in Satisfactory condition with an area-weighted average PCI of 80.

TW A2

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A2 | TAXIWAY | 1 | 31,144 | 100 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 501 | AAC | 31,144 | 100 | Good |

TW A2 consists of 1 flexible pavement section, totaling 31,144 sf. The last major construction date for the branch was 2021. Overall, TW A2 is in Good condition with an area-weighted average PCI of 100.

TW A3

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A3 | TAXIWAY | 2 | 21,152 | 95 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 81% Good (86-100 PCI), 19% Satisfactory (71-85 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 510 | AC | 3,960 | 75 | Satisfactory |
| 512 | AAC | 17,192 | 100 | Good |

TW A3 consists of 2 flexible pavement sections, totaling 21,152 sf. The last major construction dates range from 1985 to 2021, resulting in an area-weighted average age at inspection of 7 years old. Overall, TW A3 is in Good condition with an area-weighted average PCI of 95.

TW A4

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A4 | TAXIWAY | 2 | 14,827 | 81 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 26% Good (86-100 PCI), 74% Satisfactory (71-85 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 514 | AAC | 11,036 | 74 | Satisfactory |
| 515 | AAC | 3,791 | 100 | Good |

TW A4 consists of 2 flexible pavement sections, totaling 14,827 sf. The last major construction dates range from 2009 to 2021, resulting in an area-weighted average age at inspection of 10 years old. Overall, TW A4 is in Satisfactory condition with an area-weighted average PCI of 81.

TW A5

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A5 | TAXIWAY | 1 | 16,927 | 81 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 520 | AAC | 16,927 | 81 | Satisfactory |

TW A5 consists of 1 flexible pavement section, totaling 16,927 sf. The last major construction date for the branch was 1977, resulting in an area-weighted average age at inspection of 45 years old. Overall, TW A5 is in Satisfactory condition with an area-weighted average PCI of 81.

TW A6

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A6 | TAXIWAY | 1 | 21,348 | 100 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 532 | AC | 21,348 | 100 | Good |

TW A6 consists of 1 flexible pavement section, totaling 21,348 sf. The last major construction date for the branch was 2021. Overall, TW A6 is in Good condition with an area-weighted average PCI of 100.

TW A7

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A7 | TAXIWAY | 1 | 16,153 | 58 | Fair |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 525 | AAC | 16,153 | 58 | Fair |

TW A7 consists of 1 flexible pavement section, totaling 16,153 sf. The last major construction date for the branch was 1977, resulting in an area-weighted average age at inspection of 45 years old. Overall, TW A7 is in Fair condition with an area-weighted average PCI of 58.

TW A8

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A8 | TAXIWAY | 5 | 68,183 | 84 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 26% Good (86-100 PCI), 64% Satisfactory (71-85 PCI), 10% Fair (56-70 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 560 | AC | 15,868 | 78 | Satisfactory |
| 562 | AAC | 17,373 | 100 | Good |
| 565 | AC | 15,850 | 85 | Satisfactory |
| 570 | AC | 6,990 | 65 | Fair |
| 575 | AAC | 12,102 | 79 | Satisfactory |

TW A8 consists of 5 flexible pavement sections, totaling 68,183 sf. The last major construction dates range from 2000 to 2021, resulting in an area-weighted average age at inspection of 15 years old. Overall, TW A8 is in Satisfactory condition with an area-weighted average PCI of 84.

TW A9

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW A9 | TAXIWAY | 2 | 42,679 | 84 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 37% Good (86-100 PCI), 63% Satisfactory (71-85 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 550 | AC | 27,079 | 74 | Satisfactory |
| 552 | AAC | 15,600 | 100 | Good |

TW A9 consists of 2 flexible pavement sections, totaling 42,679 sf. The last major construction dates range from 2000 to 2021, resulting in an area-weighted average age at inspection of 14 years old. Overall, TW A9 is in Satisfactory condition with an area-weighted average PCI of 84.

TW AP N

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW AP N | TAXIWAY | 1 | 33,596 | 70 | Fair |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 595 | AC | 33,596 | 70 | Fair |

TW AP N consists of 1 flexible pavement section, totaling 33,596 sf. The last major construction date for the branch was 2000, resulting in an area-weighted average age at inspection of 22 years old. Overall, TW AP N is in Fair condition with an area-weighted average PCI of 70.

TW B

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW B | TAXIWAY | 1 | 73,305 | 51 | Poor |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Poor (41-55 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 105 | AC | 73,305 | 51 | Poor |

TW B consists of 1 flexible pavement section, totaling 73,305 sf. The last major construction date for the branch was 1985, resulting in an area-weighted average age at inspection of 37 years old. Overall, TW B is in Poor condition with an area-weighted average PCI of 51.

TW B1

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW B1 | TAXIWAY | 1 | 5,513 | 59 | Fair |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 104 | AC | 5,513 | 59 | Fair |

TW B1 consists of 1 flexible pavement section, totaling 5,513 sf. The last major construction date for the branch was 1985, resulting in an area-weighted average age at inspection of 37 years old. Overall, TW B1 is in Fair condition with an area-weighted average PCI of 59.

TW B2

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW B2 | TAXIWAY | 1 | 6,834 | 52 | Poor |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Poor (41-55 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 106 | AC | 6,834 | 52 | Poor |

TW B2 consists of 1 flexible pavement section, totaling 6,834 sf. The last major construction date for the branch was 1985, resulting in an area-weighted average age at inspection of 37 years old. Overall, TW B2 is in Poor condition with an area-weighted average PCI of 52.

TW B3

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TW B3 | TAXIWAY | 1 | 5,513 | 55 | Poor |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Poor (41-55 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 102 | AC | 5,513 | 55 | Poor |


TW B3 consists of 1 flexible pavement section, totaling 5,513 sf. The last major construction date for the branch was 1985, resulting in an area-weighted average age at inspection of 37 years old. Overall, TW B3 is in Poor condition with an area-weighted average PCI of 55.

Taxilanes

TL T-HANG

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| TL T-HANG | TAXILANE | 4 | 123,792 | 58 | Fair |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 19% Good (86-100 PCI), 4% Satisfactory (71-85 PCI), 62% Poor (41-55 PCI), 15% Very Poor (26-40 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 3580 | AC | 18,904 | 40 | Very Poor |
| 3585 | AC | 76,028 | 52 | Poor |
| 3590 | AAC | 5,246 | 80 | Satisfactory |
| 3592 | AC | 23,614 | 87 | Good |


TL T-HANG consists of 4 flexible pavement sections, totaling 123,792 sf. The last major construction dates range from 2000 to 2009, resulting in an area-weighted average age at inspection of 20 years old. Overall, TL T-HANG is in Fair condition with an area-weighted average PCI of 58.

Aprons

AP CENTER

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| AP CENTER | APRON | 10 | 746,206 | 86 | Good |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 60% Good (86-100 PCI), 17% Satisfactory (71-85 PCI), 22% Poor (41-55 PCI), 1% Very Poor (26-40 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 4105 | AAC | 168,599 | 52 | Poor |
| 4107 | AC | 93,441 | 100 | Good |
| 4110 | AAC | 81,895 | 100 | Good |
| 4115 | AAC | 120,000 | 100 | Good |
| 4120 | AAC | 95,753 | 100 | Good |
| 4125 | AAC | 30,574 | 100 | Good |
| 4130 | AAC | 19,665 | 100 | Good |
| 4135 | AC | 123,619 | 84 | Satisfactory |
| 4145 | AAC | 6,660 | 100 | Good |
| 4150 | PCC | 6,000 | 33 | Very Poor |

AP CENTER consists of 9 flexible and 1 rigid pavement sections, totaling 746,206 sf. The last major construction dates range from 1991 to 2021, resulting in an area-weighted average age at inspection of 9 years old. Overall, AP CENTER is in Good condition with an area-weighted average PCI of 86.

AP N

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| AP N | APRON | 2 | 61,346 | 60 | Fair |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 32% Fair (56-70 PCI), 68% Poor (41-55 PCI).




| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 4205 | AC | 19,584 | 70 | Fair |
| 4210 | AC | 41,762 | 55 | Poor |

AP N consists of 2 flexible pavement sections, totaling 61,346 sf. The last major construction date for the branch was 2000, resulting in an area-weighted average age at inspection of 22 years old. Overall, AP N is in Fair condition with an area-weighted average PCI of 60.

AP S

| Branch ID | Branch Use | Number of Sections | Branch Area (SF) | Branch Area-Weighted Avg PCI | Branch Condition Rating |
|-----------|------------|--------------------|------------------|------------------------------|-------------------------|
| AP S | APRON | 1 | 47,250 | 78 | Satisfactory |

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Satisfactory (71-85 PCI).



| Section ID | Surface Type | Section Area (SF) | PCI | Condition Rating |
|------------|--------------|-------------------|-----|------------------|
| 4305 | AC | 47,250 | 78 | Satisfactory |

AP S consists of 1 flexible pavement section, totaling 47,250 sf. The last major construction date for the branch was 2010, resulting in an area-weighted average age at inspection of 12 years old. Overall, AP S is in Satisfactory condition with an area-weighted average PCI of 78.



Chapter 5: SAPMP Customization



Chapter 5 – SAPMP Customization

Once the PAVER™ database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- » The “Network” field identifies the airport being analyzed;
- » The “Airport Classification” field classifies the Airport according to the type and volume of aircraft traffic;
 - “GA” for General Aviation, community airports
 - “RL” for Regional Relievers
 - “PR” for Primary/Commercial airports
- » The “District” field identifies the FDOT District to which the Airport belongs;
- » The “FAA ADO Area” is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists);
- » The “Inspection Phase” denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- » The “CFASPP Center” identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.

5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. **The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.** Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.


5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into “groups” or “families” according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

5.2.3 Branch-Level Pavement Condition Forecast

Figure 5.2.3 depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.

Figure 5.2.3: Forecasted Branch-Level Pavement Performance



5.2.4 Section-Level Pavement Condition Forecast

Table 5.2.4 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|------------|-----------|------------|-------------|------|------|------|------|------|------|------|------|------|------|
| OCF | RW 8-26 | 6205 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 70 |
| OCF | RW 18-36 | 6105 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 66 | 64 |
| OCF | RW 18-36 | 6110 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 | 65 | 63 |
| OCF | RW 18-36 | 6125 | 87 | 85 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 |
| OCF | RW 18-36 | 6135 | 85 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 | 65 |
| OCF | RW 18-36 | 6190 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 | 69 |
| OCF | RW 18-36 | 6195 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 | 69 |
| OCF | TW A | 304 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 305 | 88 | 86 | 84 | 82 | 80 | 78 | 77 | 75 | 74 | 73 | 71 |
| OCF | TW A | 505 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 540 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 542 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A1 | 592 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A10 | 535 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A11 | 545 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A12 | 555 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 69 | 68 |
| OCF | TW A13 | 596 | 80 | 78 | 76 | 75 | 74 | 72 | 71 | 70 | 69 | 67 | 66 |
| OCF | TW A2 | 501 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A3 | 510 | 75 | 73 | 72 | 71 | 69 | 68 | 67 | 66 | 65 | 64 | 63 |
| OCF | TW A3 | 512 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A4 | 514 | 74 | 72 | 71 | 70 | 68 | 67 | 66 | 65 | 64 | 62 | 61 |
| OCF | TW A4 | 515 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A5 | 520 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 | 68 | 67 |
| OCF | TW A6 | 532 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A7 | 525 | 58 | 56 | 55 | 53 | 52 | 50 | 48 | 46 | 44 | 42 | 40 |
| OCF | TW A8 | 560 | 78 | 76 | 75 | 73 | 72 | 71 | 69 | 68 | 67 | 66 | 65 |
| OCF | TW A8 | 562 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A8 | 565 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 | 72 | 71 | 69 |
| OCF | TW A8 | 570 | 65 | 64 | 63 | 62 | 61 | 61 | 60 | 59 | 58 | 58 | 57 |
| OCF | TW A8 | 575 | 79 | 77 | 76 | 74 | 73 | 71 | 70 | 69 | 68 | 66 | 65 |
| OCF | TW A9 | 550 | 74 | 72 | 71 | 70 | 69 | 68 | 66 | 65 | 64 | 64 | 63 |
| OCF | TW A9 | 552 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW AP N | 595 | 70 | 69 | 67 | 66 | 65 | 64 | 63 | 63 | 62 | 61 | 60 |
| OCF | TW B | 105 | 51 | 50 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 47 | 46 |
| OCF | TW B1 | 104 | 59 | 58 | 58 | 57 | 56 | 56 | 55 | 55 | 54 | 54 | 53 |
| OCF | TW B2 | 106 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| OCF | TW B3 | 102 | 55 | 54 | 54 | 53 | 53 | 53 | 52 | 52 | 51 | 51 | 50 |
| OCF | TL T-HANG | 3580 | 40 | 39 | 38 | 37 | 36 | 35 | 34 | 33 | 31 | 30 | 29 |
| OCF | TL T-HANG | 3585 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |

Airport Pavement Evaluation Report


Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|------------|-----------|------------|-------------|------|------|------|------|------|------|------|------|------|------|
| OCF | TL T-HANG | 3590 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 68 | 67 | 66 |
| OCF | TL T-HANG | 3592 | 87 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 | 72 | 71 |
| OCF | AP CENTER | 4105 | 52 | 50 | 48 | 46 | 44 | 42 | 40 | 38 | 36 | 34 | 32 |
| OCF | AP CENTER | 4107 | 100 | 95 | 93 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 |
| OCF | AP CENTER | 4110 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4115 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4120 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4125 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4130 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4135 | 84 | 82 | 80 | 78 | 76 | 74 | 73 | 71 | 69 | 68 | 66 |
| OCF | AP CENTER | 4145 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4150 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 26 | 25 | 24 | 23 |
| OCF | AP N | 4205 | 70 | 68 | 67 | 65 | 64 | 63 | 61 | 60 | 59 | 58 | 57 |
| OCF | AP N | 4210 | 55 | 54 | 53 | 52 | 51 | 51 | 50 | 49 | 48 | 48 | 47 |
| OCF | AP S | 4305 | 78 | 76 | 74 | 72 | 71 | 69 | 68 | 66 | 65 | 64 | 62 |

5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.

Figure 5.3 (a): Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds: >70: Routine Maintenance 55-70: Rehabilitation Eligible <55: Reconstruction Eligible

**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.*

Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP

and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects

| Airfield Pavement Project Type | PCI Requirement |
|--------------------------------|-----------------|
| Reconstruction | PCI < 55 (Poor) |
| Rehabilitation | PCI < 70 (Fair) |
| Maintenance | N/A |

*Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

Table 5.3 (b): Critical PCI Values by Branch Use

| Runway | Taxiway | Apron |
|--------|---------|-------|
| 70 | 70 | 70 |

Figures 5.3 (b) and 5.3 (c) depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical PCI}$





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical PCI}$



5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 “Airport Foreign Object Debris (FOD) Management” provides additional guidance for developing and managing an airport FOD program.

5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety (“stopgap”) measure. The two (2) types of localized maintenance are described below in further detail.

- » Localized Preventive Maintenance and Repair
 - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- » Localized Stopgap/Safety Maintenance and Repair
 - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

AC Crack Sealing

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

AC Full-Depth Patching

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

AC Partial-Depth AC Patching

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

Grinding

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

Monitor Pavement

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.

PCC Crack Sealing

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

PCC Full-Depth Patching

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

PCC Joint Seal

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

PCC Partial-Depth Patching

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

PCC Slab Replacement

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

Surface Seal

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Tables 5.4.3 (a) and (b) display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete

| Localized Work Type | General Aviation Costs | Work Type Unit |
|---------------------------|------------------------|----------------|
| AC Crack Sealing | \$ 4.00 | LF |
| AC Full-Depth Patching | \$ 10.00 | SF |
| AC Partial-Depth Patching | \$ 4.75 | SF |
| Surface Seal | \$ 0.75 | SF |

Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete

| Localized Work Type | General Aviation Costs | Work Type Unit |
|----------------------------|------------------------|----------------|
| Grinding | \$ 2.00 | SF |
| PCC Crack Sealing | \$ 7.00 | LF |
| PCC Joint Seal | \$ 4.25 | LF |
| PCC Full-Depth Patching | \$ 50.00 | SF |
| PCC Partial-Depth Patching | \$ 169.00 | SF |
| PCC Slab Replacement | \$ 51.50 | SF |

* PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.

5.4.4 Localized Maintenance and Repair Policy

Table 5.4.4 and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.

Table 5.4.4: AC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy

| Distress | Severity | Description | AC Preventive Work Type | AC Stopgap Work Type |
|----------|----------|-------------------------|---------------------------|---------------------------|
| 41 | Low | Alligator Cracking | Monitor Pavement | Monitor Pavement |
| 41 | Medium | Alligator Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 41 | High | Alligator Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 42 | N/A | Bleeding | Monitor Pavement | Monitor Pavement |
| 43 | Low | Block Cracking | Monitor Pavement | Monitor Pavement |
| 43 | Medium | Block Cracking | AC Crack Sealing | Monitor Pavement |
| 43 | High | Block Cracking | AC Crack Sealing | AC Crack Sealing |
| 44 | Low | Corrugation | Monitor Pavement | Monitor Pavement |
| 44 | Medium | Corrugation | AC Full Depth Patching | Monitor Pavement |
| 44 | High | Corrugation | AC Full Depth Patching | AC Full Depth Patching |
| 45 | Low | Depression | Monitor Pavement | Monitor Pavement |
| 45 | Medium | Depression | AC Full Depth Patching | Monitor Pavement |
| 45 | High | Depression | AC Full Depth Patching | AC Full Depth Patching |
| 46 | N/A | Jet Blast | Monitor Pavement | Monitor Pavement |
| 47 | Low | Jt. Reflective Cracking | Monitor Pavement | Monitor Pavement |
| 47 | Medium | Jt. Reflective Cracking | AC Crack Sealing | Monitor Pavement |
| 47 | High | Jt. Reflective Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 48 | Low | L&T Cracking | Monitor Pavement | Monitor Pavement |
| 48 | Medium | L&T Cracking | AC Crack Sealing | Monitor Pavement |
| 48 | High | L&T Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 49 | N/A | Oil Spillage | Monitor Pavement | Monitor Pavement |
| 50 | Low | Patching | Monitor Pavement | Monitor Pavement |
| 50 | Medium | Patching | AC Full Depth Patching | Monitor Pavement |
| 50 | High | Patching | AC Full Depth Patching | AC Full Depth Patching |
| 51 | N/A | Polished Aggregate | Monitor Pavement | Monitor Pavement |
| 52 | Low | Raveling | Surface Seal | Monitor Pavement |
| 52 | Medium | Raveling | Surface Seal | Monitor Pavement |
| 52 | High | Raveling | AC Partial Depth Patching | AC Partial Depth Patching |
| 53 | Low | Rutting | Monitor Pavement | Monitor Pavement |
| 53 | Medium | Rutting | AC Full Depth Patching | Monitor Pavement |
| 53 | High | Rutting | AC Full Depth Patching | AC Full Depth Patching |
| 54 | Low | Shoving | Monitor Pavement | Monitor Pavement |
| 54 | Medium | Shoving | AC Partial Depth Patching | Monitor Pavement |
| 54 | High | Shoving | AC Full Depth Patching | AC Full Depth Patching |
| 55 | N/A | Slippage Cracking | AC Full Depth Patching | AC Full Depth Patching |
| 56 | Low | Swelling | Monitor Pavement | Monitor Pavement |
| 56 | Medium | Swelling | AC Full Depth Patching | Monitor Pavement |
| 56 | High | Swelling | AC Full Depth Patching | AC Full Depth Patching |

| Distress | Severity | Description | AC Preventive Work Type | AC Stopgap Work Type |
|----------|----------|-------------|---------------------------|----------------------|
| 57 | Low | Weathering | Monitor Pavement | Monitor Pavement |
| 57 | Medium | Weathering | Surface Seal | Monitor Pavement |
| 57 | High | Weathering | AC Partial Depth Patching | Surface Seal |

Table 5.4.5: PCC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy

| Distress | Severity | Description | PCC Preventive Work Type | PCC Stopgap Work Type |
|----------|----------|---------------------|----------------------------|----------------------------|
| 61 | Low | Blow-up | PCC Full Depth Patching | Monitor Pavement |
| 61 | Medium | Blow-up | PCC Full Depth Patching | PCC Full Depth Patching |
| 61 | High | Blow-up | PCC Slab Replacement | PCC Slab Replacement |
| 62 | Low | Corner Break | Monitor Pavement | Monitor Pavement |
| 62 | Medium | Corner Break | PCC Full Depth Patching | PCC Full Depth Patching |
| 62 | High | Corner Break | PCC Full Depth Patching | PCC Full Depth Patching |
| 63 | Low | Linear Cracking | Monitor Pavement | Monitor Pavement |
| 63 | Medium | Linear Cracking | PCC Crack Sealing | PCC Crack Sealing |
| 63 | High | Linear Cracking | PCC Full Depth Patching | PCC Crack Sealing |
| 64 | Low | Durability Cracking | Monitor Pavement | Monitor Pavement |
| 64 | Medium | Durability Cracking | PCC Full Depth Patching | PCC Full Depth Patching |
| 64 | High | Durability Cracking | PCC Slab Replacement | PCC Slab Replacement |
| 65 | Low | Jt. Seal Damage | PCC Joint Seal | Monitor Pavement |
| 65 | Medium | Jt. Seal Damage | PCC Joint Seal | Monitor Pavement |
| 65 | High | Jt. Seal Damage | PCC Joint Seal | PCC Joint Seal |
| 66 | Low | Small Patch | Monitor Pavement | Monitor Pavement |
| 66 | Medium | Small Patch | PCC Partial Depth Patching | Monitor Pavement |
| 66 | High | Small Patch | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 67 | Low | Large Patch | Monitor Pavement | Monitor Pavement |
| 67 | Medium | Large Patch | PCC Full Depth Patching | Monitor Pavement |
| 67 | High | Large Patch | PCC Full Depth Patching | PCC Full Depth Patching |
| 68 | N/A | Popouts | Monitor Pavement | Monitor Pavement |
| 69 | N/A | Pumping | Monitor Pavement | Monitor Pavement |
| 70 | Low | Scaling | Monitor Pavement | Monitor Pavement |
| 70 | Medium | Scaling | PCC Slab Replacement | Monitor Pavement |
| 70 | High | Scaling | PCC Slab Replacement | PCC Slab Replacement |
| 71 | Low | Faulting | Monitor Pavement | Monitor Pavement |
| 71 | Medium | Faulting | Grinding | Monitor Pavement |
| 71 | High | Faulting | PCC Slab Replacement | PCC Slab Replacement |
| 72 | Low | Shattered Slab | PCC Crack Sealing | Monitor Pavement |
| 72 | Medium | Shattered Slab | PCC Slab Replacement | PCC Crack Sealing |
| 72 | High | Shattered Slab | PCC Slab Replacement | PCC Slab Replacement |
| 73 | N/A | Shrinkage Cracking | Monitor Pavement | Monitor Pavement |

| Distress | Severity | Description | PCC Preventive Work Type | PCC Stopgap Work Type |
|----------|----------|--------------|----------------------------|----------------------------|
| 74 | Low | Joint Spall | Monitor Pavement | Monitor Pavement |
| 74 | Medium | Joint Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 74 | High | Joint Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 75 | Low | Corner Spall | Monitor Pavement | Monitor Pavement |
| 75 | Medium | Corner Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 75 | High | Corner Spall | PCC Partial Depth Patching | PCC Partial Depth Patching |
| 76 | Low | ASR | Monitor Pavement | Monitor Pavement |
| 76 | Medium | ASR | PCC Slab Replacement | PCC Slab Replacement |
| 76 | High | ASR | PCC Slab Replacement | PCC Slab Replacement |

5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average General Aviation Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation

| Rehabilitation Type | General Aviation Pavement Section |
|--|---|
| AC Reconstruction | |
| <i>Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.</i> PCI < 55 | Pavement Removal |
| | Unclassified Excavation |
| | Subgrade Stabilization (12") |
| | Limerock Base Course (6") |
| | Prime Coat |
| | Tack Coat |
| | P-401 Surface Course (3") |
| | <i>Excludes any paved shoulder features</i> |
| AC Rehabilitation | |
| <i>Combination of asphalt pavement milling and replacement overlay with 15% of the areas subject to full-depth reconstruction.</i> PCI = 55 to 70 | 15% AC Reconstruction |
| | Mill and Overlay |
| | AC Milling (3") |
| | Tack Coat |
| | P-401 Surface Course (3") |
| | <i>Excludes any paved shoulder features</i> |
| PCC Reconstruction | |
| <i>Full-depth rigid pavement section reconstruction.</i> PCI < 55 | Pavement Removal |
| | Unclassified Excavation |
| | Subgrade Stabilization (6") |
| | Limerock Base Course (6") |
| | P-501 PCC Pavement (8") |
| | PCC Joint Seal |
| PCC Rehabilitation | |
| <i>Rehabilitation of PCC pavement with a combination of crack sealing, joint seal replacement, limited patching, and replacement of 15% of slab panels.</i> PCI = 55 to 70 | 15% Slab Replacement |
| | Joint and Crack Seal |
| | Limited Patching |

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.

Reconstruction (AC or PCC)

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

AC Rehabilitation

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

PCC Rehabilitation

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.


5.5.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.


Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.

Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type

| Rehabilitation Type | PCI Range | Asphalt Concrete Cost per SF | Portland Cement Concrete Cost Per SF |
|---------------------|-----------|------------------------------|--------------------------------------|
| Rehabilitation | 55 to 70 | \$9.00 | \$15.00 |
| Reconstruction | 0 to 55 | \$16.00 | \$29.00 |



Chapter 6: M&R Planning and Budget Scenario Analysis



Chapter 6 – M&R Planning and Budget Scenario Analysis

6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

Table 6.1 (a) provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (a): Year 1 Summary of Localized Maintenance

| Work Category | Cost |
|---|------------------|
| Preventive | \$ 46,270 |
| Stopgap | \$ 5,380 |
| Planning-Level Localized M&R Needs = | \$ 51,650 |

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

Table 6.1 (b) summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary

| Localized Maintenance Category | Localized Work Type | Rough Estimate of Work Quantity | Work Units | Planning Material Cost |
|----------------------------------|---------------------------|---------------------------------|------------|------------------------|
| Localized Preventive Maintenance | AC Crack Sealing | 1,888 | LF | \$ 7,560 |
| | Surface Seal | 51,493 | SF | \$ 38,710 |
| Localized Stopgap Maintenance | AC Partial-Depth Patching | 293 | SF | \$ 1,400 |
| | AC Full-Depth Patching | 183 | SF | \$ 1,830 |
| | PCC Crack Sealing | 40 | LF | \$ 280 |
| | PCC Joint Seal | 440 | LF | \$ 1,870 |

Table 6.1 (c) provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved “End Condition” PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary

| Network ID | Branch ID | Section ID | Area (SF) | Start PCI | End PCI | Cost |
|------------|-----------|------------|-----------|-----------|---------|----------|
| OCF | RW 8-26 | 6205 | 150,450 | 90 | 90 | \$ - |
| OCF | RW 18-36 | 6105 | 373,275 | 84 | 86 | \$ 7,140 |
| OCF | RW 18-36 | 6110 | 373,275 | 83 | 85 | \$ 8,490 |
| OCF | RW 18-36 | 6125 | 94,500 | 87 | 89 | \$ 940 |
| OCF | RW 18-36 | 6135 | 189,000 | 85 | 87 | \$ 3,040 |
| OCF | RW 18-36 | 6190 | 30,000 | 86 | 88 | \$ 680 |
| OCF | RW 18-36 | 6195 | 60,000 | 86 | 90 | \$ 2,340 |
| OCF | TW A | 304 | 11,360 | 100 | 100 | \$ - |
| OCF | TW A | 305 | 4,941 | 88 | 94 | \$ 560 |
| OCF | TW A | 505 | 210,730 | 100 | 100 | \$ - |
| OCF | TW A | 540 | 104,692 | 100 | 100 | \$ - |
| OCF | TW A | 542 | 34,610 | 100 | 100 | \$ - |
| OCF | TW A1 | 592 | 23,030 | 100 | 100 | \$ - |
| OCF | TW A10 | 535 | 28,064 | 100 | 100 | \$ - |
| OCF | TW A11 | 545 | 23,035 | 100 | 100 | \$ - |
| OCF | TW A12 | 555 | 33,994 | 82 | 82 | \$ - |
| OCF | TW A13 | 596 | 54,138 | 80 | 84 | \$ 2,080 |
| OCF | TW A2 | 501 | 31,144 | 100 | 100 | \$ - |
| OCF | TW A3 | 510 | 3,960 | 75 | 78 | \$ 150 |
| OCF | TW A3 | 512 | 17,192 | 100 | 100 | \$ - |
| OCF | TW A4 | 514 | 11,036 | 74 | 85 | \$ 2,070 |
| OCF | TW A4 | 515 | 3,791 | 100 | 100 | \$ - |
| OCF | TW A5 | 520 | 16,927 | 81 | 81 | \$ - |
| OCF | TW A6 | 532 | 21,348 | 100 | 100 | \$ - |
| OCF | TW A7 | 525 | 16,153 | 58 | 58 | \$ - |
| OCF | TW A8 | 560 | 15,868 | 78 | 78 | \$ - |

| Network ID | Branch ID | Section ID | Area (SF) | Start PCI | End PCI | Cost |
|------------|-----------|------------|-----------|-----------|---------|----------|
| OCF | TW A8 | 562 | 17,373 | 100 | 100 | \$ - |
| OCF | TW A8 | 565 | 15,850 | 85 | 90 | \$ 1,190 |
| OCF | TW A8 | 570 | 6,990 | 65 | 71 | \$ 540 |
| OCF | TW A8 | 575 | 12,102 | 79 | 90 | \$ 2,330 |
| OCF | TW A9 | 550 | 27,079 | 74 | 77 | \$ 660 |
| OCF | TW A9 | 552 | 15,600 | 100 | 100 | \$ - |
| OCF | TW AP N | 595 | 33,596 | 70 | 70 | \$ - |
| OCF | TW B | 105 | 73,305 | 51 | 51 | \$ - |
| OCF | TW B1 | 104 | 5,513 | 59 | 59 | \$ - |
| OCF | TW B2 | 106 | 6,834 | 52 | 52 | \$ - |
| OCF | TW B3 | 102 | 5,513 | 55 | 55 | \$ - |
| OCF | TL T-HANG | 3580 | 18,904 | 40 | 48 | \$ 1,830 |
| OCF | TL T-HANG | 3585 | 76,028 | 52 | 53 | \$ 860 |
| OCF | TL T-HANG | 3590 | 5,246 | 80 | 97 | \$ 2,960 |
| OCF | TL T-HANG | 3592 | 23,614 | 87 | 92 | \$ 1,780 |
| OCF | AP CENTER | 4105 | 168,599 | 52 | 52 | \$ - |
| OCF | AP CENTER | 4107 | 93,441 | 100 | 100 | \$ - |
| OCF | AP CENTER | 4110 | 81,895 | 100 | 100 | \$ - |
| OCF | AP CENTER | 4115 | 120,000 | 100 | 100 | \$ - |
| OCF | AP CENTER | 4120 | 95,753 | 100 | 100 | \$ - |
| OCF | AP CENTER | 4125 | 30,574 | 100 | 100 | \$ - |
| OCF | AP CENTER | 4130 | 19,665 | 100 | 100 | \$ - |
| OCF | AP CENTER | 4135 | 123,619 | 84 | 89 | \$ 8,060 |
| OCF | AP CENTER | 4145 | 6,660 | 100 | 100 | \$ - |
| OCF | AP CENTER | 4150 | 6,000 | 33 | 45 | \$ 2,150 |
| OCF | AP N | 4205 | 19,584 | 70 | 70 | \$ - |
| OCF | AP N | 4210 | 41,762 | 55 | 55 | \$ - |
| OCF | AP S | 4305 | 47,250 | 78 | 81 | \$ 1,780 |

6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b) and (c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is

done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- » An estimation of current pavement condition;
- » Major pavement rehabilitation needs based on condition and policies; and
- » Planning-level cost estimates for the major rehabilitation needs.

Table 6.2.1 (a) summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.


Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs


| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost Estimate |
|--------------|------------|-----------|------------|---------|-----------|------------|---------------------|------------------------|
| 2023 | OCF | TW A7 | 525 | AAC | 16,153 | 56 | AC Rehabilitation | \$ 146,000 |
| 2023 | OCF | TW A8 | 570 | AC | 6,990 | 64 | AC Rehabilitation | \$ 63,000 |
| 2023 | OCF | TW AP N | 595 | AC | 33,596 | 69 | AC Rehabilitation | \$ 303,000 |
| 2023 | OCF | TW B | 105 | AC | 73,305 | 50 | AC Reconstruction | \$ 1,173,000 |
| 2023 | OCF | TW B1 | 104 | AC | 5,513 | 58 | AC Rehabilitation | \$ 50,000 |
| 2023 | OCF | TW B2 | 106 | AC | 6,834 | 51 | AC Reconstruction | \$ 110,000 |
| 2023 | OCF | TW B3 | 102 | AC | 5,513 | 54 | AC Reconstruction | \$ 73,000 |
| 2023 | OCF | TL T-HANG | 3580 | AC | 18,904 | 39 | AC Reconstruction | \$ 303,000 |
| 2023 | OCF | TL T-HANG | 3585 | AC | 76,028 | 51 | AC Reconstruction | \$ 1,217,000 |
| 2023 | OCF | AP CENTER | 4105 | AAC | 168,599 | 50 | AC Reconstruction | \$ 2,698,000 |
| 2023 | OCF | AP CENTER | 4150 | PCC | 6,000 | 32 | PCC Reconstruction | \$ 174,000 |
| 2023 | OCF | AP N | 4205 | AC | 19,584 | 68 | AC Rehabilitation | \$ 177,000 |
| 2023 | OCF | AP N | 4210 | AC | 41,762 | 54 | AC Reconstruction | \$ 669,000 |
| 2025 | OCF | TW A4 | 514 | AAC | 11,036 | 70 | AC Rehabilitation | \$ 110,000 |
| 2025 | OCF | TW A9 | 550 | AC | 27,079 | 70 | AC Rehabilitation | \$ 269,000 |
| 2026 | OCF | TW A3 | 510 | AC | 3,960 | 69 | AC Rehabilitation | \$ 42,000 |
| 2027 | OCF | AP S | 4305 | AC | 47,250 | 69 | AC Rehabilitation | \$ 517,000 |
| 2028 | OCF | TW A8 | 560 | AC | 15,868 | 69 | AC Rehabilitation | \$ 183,000 |
| 2029 | OCF | RW 18-36 | 6110 | AAC | 373,275 | 69 | AC Rehabilitation | \$ 4,503,000 |
| 2029 | OCF | TW A13 | 596 | AC | 54,138 | 70 | AC Rehabilitation | \$ 653,000 |
| 2029 | OCF | TW A8 | 575 | AAC | 12,102 | 69 | AC Rehabilitation | \$ 146,000 |

| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost Estimate |
|--------------|------------|-----------|------------|---------|-----------|------------|---------------------|------------------------|
| 2029 | OCF | TL T-HANG | 3590 | AAC | 5,246 | 70 | AC Rehabilitation | \$ 64,000 |
| 2030 | OCF | RW 18-36 | 6105 | AAC | 373,275 | 68 | AC Rehabilitation | \$ 4,728,000 |
| 2030 | OCF | RW 18-36 | 6135 | AAC | 189,000 | 69 | AC Rehabilitation | \$ 2,394,000 |
| 2030 | OCF | TW A12 | 555 | AC | 33,994 | 70 | AC Rehabilitation | \$ 431,000 |
| 2030 | OCF | TW A5 | 520 | AAC | 16,927 | 69 | AC Rehabilitation | \$ 215,000 |
| 2030 | OCF | AP CENTER | 4135 | AC | 123,619 | 69 | AC Rehabilitation | \$ 1,566,000 |
| 2031 | OCF | RW 18-36 | 6125 | AAC | 94,500 | 69 | AC Rehabilitation | \$ 1,257,000 |
| 2032 | OCF | RW 18-36 | 6190 | AC | 30,000 | 69 | AC Rehabilitation | \$ 419,000 |
| 2032 | OCF | RW 18-36 | 6195 | AC | 60,000 | 69 | AC Rehabilitation | \$ 838,000 |
| 2032 | OCF | TW A8 | 565 | AC | 15,850 | 69 | AC Rehabilitation | \$ 222,000 |

Figure 6.2.1 (a) summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year





| | | | | |
|--|---|---|--|---|
| TW A7:525 2023 AC REHAB \$0.15 M | TL T-HANG:3580 2023 AC RECON \$0.30 M | TL T-HANG:3585 2023 AC RECON \$1.22 M | TW A4:514 2025 AC REHAB \$0.11 M | TW A3:510 2026 AC REHAB \$0.04 M |
| TW A8:560 2028 AC REHAB \$0.18 M | TW A8:575 2029 AC REHAB \$0.15 M | TL T-HANG:3590 2029 AC REHAB \$0.06 M | TW A5:520 2030 AC REHAB \$0.22 M | AP CENTER:4135 2030 AC REHAB \$1.57 M |



Chapter 7: Conclusion



Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- » Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in **Section 6.1**;
- » Further refine and implement the identified 10-year major rehabilitation needs provided in **Section 6.2**;
- » Maintain detailed records on pavement maintenance, construction, and inspection; and
- » Maintain records on major pavement construction projects (year, scope, cost, and construction documents).

7.2 Supporting Documents

Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.

7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- » ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- » AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- » AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- » AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- » Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- » Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- » Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.

A wide-angle photograph of an airfield runway stretching into the distance under a bright blue sky with scattered white clouds. The runway is dark asphalt with a central white dashed line and yellow edge lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

Appendix A: Airfield Pavement Analysis

A close-up, low-angle view of the runway pavement, showing a concrete strip in the center and asphalt on the sides. Yellow chevron markings are visible on the right side of the concrete strip.A thick red diagonal bar running from the bottom left towards the top right, separating the sky from the runway image.

Table A.1: Pavement System Inventory Details

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|--------------|------------------------------------|
| OCF | RW 8-26 | Runway | 6205 | 150,450 | AAC | 1/1/2013 |
| OCF | RW 18-36 | Runway | 6105 | 373,275 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6110 | 373,275 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6125 | 94,500 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6135 | 189,000 | AAC | 1/1/2009 |
| OCF | RW 18-36 | Runway | 6190 | 30,000 | AC | 1/1/2008 |
| OCF | RW 18-36 | Runway | 6195 | 60,000 | AC | 1/1/2008 |
| OCF | TW A | Taxiway | 304 | 11,360 | AAC | 7/1/2021 |
| OCF | TW A | Taxiway | 305 | 4,941 | AAC | 1/1/2013 |
| OCF | TW A | Taxiway | 505 | 210,730 | AAC | 7/1/2021 |
| OCF | TW A | Taxiway | 540 | 104,692 | AAC | 7/1/2021 |
| OCF | TW A | Taxiway | 542 | 34,610 | AC | 7/1/2021 |
| OCF | TW A1 | Taxiway | 592 | 23,030 | AC | 7/1/2021 |
| OCF | TW A10 | Taxiway | 535 | 28,064 | AAC | 7/1/2021 |
| OCF | TW A11 | Taxiway | 545 | 23,035 | AAC | 7/1/2021 |
| OCF | TW A12 | Taxiway | 555 | 33,994 | AC | 1/1/2008 |
| OCF | TW A13 | Taxiway | 596 | 54,138 | AC | 1/1/2008 |
| OCF | TW A2 | Taxiway | 501 | 31,144 | AAC | 7/1/2021 |
| OCF | TW A3 | Taxiway | 510 | 3,960 | AC | 1/1/1985 |
| OCF | TW A3 | Taxiway | 512 | 17,192 | AAC | 7/1/2021 |
| OCF | TW A4 | Taxiway | 514 | 11,036 | AAC | 1/1/2009 |
| OCF | TW A4 | Taxiway | 515 | 3,791 | AAC | 7/1/2021 |
| OCF | TW A5 | Taxiway | 520 | 16,927 | AAC | 1/1/1977 |
| OCF | TW A6 | Taxiway | 532 | 21,348 | AC | 7/1/2021 |
| OCF | TW A7 | Taxiway | 525 | 16,153 | AAC | 1/1/1977 |
| OCF | TW A8 | Taxiway | 560 | 15,868 | AC | 1/1/2000 |
| OCF | TW A8 | Taxiway | 562 | 17,373 | AAC | 7/1/2021 |
| OCF | TW A8 | Taxiway | 565 | 15,850 | AC | 1/1/2000 |
| OCF | TW A8 | Taxiway | 570 | 6,990 | AC | 1/1/2000 |
| OCF | TW A8 | Taxiway | 575 | 12,102 | AAC | 1/1/2010 |
| OCF | TW A9 | Taxiway | 550 | 27,079 | AC | 1/1/2000 |
| OCF | TW A9 | Taxiway | 552 | 15,600 | AAC | 7/1/2021 |
| OCF | TW AP N | Taxiway | 595 | 33,596 | AC | 1/1/2000 |
| OCF | TW B | Taxiway | 105 | 73,305 | AC | 1/1/1985 |
| OCF | TW B1 | Taxiway | 104 | 5,513 | AC | 1/1/1985 |
| OCF | TW B2 | Taxiway | 106 | 6,834 | AC | 1/1/1985 |
| OCF | TW B3 | Taxiway | 102 | 5,513 | AC | 1/1/1985 |
| OCF | TL T-HANG | Taxilane | 3580 | 18,904 | AC | 1/1/2000 |
| OCF | TL T-HANG | Taxilane | 3585 | 76,028 | AC | 1/1/2000 |
| OCF | TL T-HANG | Taxilane | 3590 | 5,246 | AAC | 1/1/2009 |
| OCF | TL T-HANG | Taxilane | 3592 | 23,614 | AC | 1/1/2009 |
| OCF | AP CENTER | Apron | 4105 | 168,599 | AAC | 1/1/1991 |
| OCF | AP CENTER | Apron | 4107 | 93,441 | AC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4110 | 81,895 | AAC | 7/1/2021 |

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | Surface Type | Estimate of Last Construction Date |
|------------|-----------|------------|------------|-----------|--------------|------------------------------------|
| OCF | AP CENTER | Apron | 4115 | 120,000 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4120 | 95,753 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4125 | 30,574 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4130 | 19,665 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4135 | 123,619 | AC | 7/1/2009 |
| OCF | AP CENTER | Apron | 4145 | 6,660 | AAC | 7/1/2021 |
| OCF | AP CENTER | Apron | 4150 | 6,000 | PCC | 1/1/1999 |
| OCF | AP N | Apron | 4205 | 19,584 | AC | 1/1/2000 |
| OCF | AP N | Apron | 4210 | 41,762 | AC | 1/1/2000 |
| OCF | AP S | Apron | 4305 | 47,250 | AC | 1/1/2010 |

Table A.2: Pavement Condition Index Summary (Current PCI Survey) – Section Level

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|------------|------------|-----------|-----|------------------|
| OCF | RW 8-26 | Runway | 6205 | 150,450 | 90 | Good |
| OCF | RW 18-36 | Runway | 6105 | 373,275 | 84 | Satisfactory |
| OCF | RW 18-36 | Runway | 6110 | 373,275 | 83 | Satisfactory |
| OCF | RW 18-36 | Runway | 6125 | 94,500 | 87 | Good |
| OCF | RW 18-36 | Runway | 6135 | 189,000 | 85 | Satisfactory |
| OCF | RW 18-36 | Runway | 6190 | 30,000 | 86 | Good |
| OCF | RW 18-36 | Runway | 6195 | 60,000 | 86 | Good |
| OCF | TW A | Taxiway | 304 | 11,360 | 100 | Good |
| OCF | TW A | Taxiway | 305 | 4,941 | 88 | Good |
| OCF | TW A | Taxiway | 505 | 210,730 | 100 | Good |
| OCF | TW A | Taxiway | 540 | 104,692 | 100 | Good |
| OCF | TW A | Taxiway | 542 | 34,610 | 100 | Good |
| OCF | TW A1 | Taxiway | 592 | 23,030 | 100 | Good |
| OCF | TW A10 | Taxiway | 535 | 28,064 | 100 | Good |
| OCF | TW A11 | Taxiway | 545 | 23,035 | 100 | Good |
| OCF | TW A12 | Taxiway | 555 | 33,994 | 82 | Satisfactory |
| OCF | TW A13 | Taxiway | 596 | 54,138 | 80 | Satisfactory |
| OCF | TW A2 | Taxiway | 501 | 31,144 | 100 | Good |
| OCF | TW A3 | Taxiway | 510 | 3,960 | 75 | Satisfactory |
| OCF | TW A3 | Taxiway | 512 | 17,192 | 100 | Good |
| OCF | TW A4 | Taxiway | 514 | 11,036 | 74 | Satisfactory |
| OCF | TW A4 | Taxiway | 515 | 3,791 | 100 | Good |
| OCF | TW A5 | Taxiway | 520 | 16,927 | 81 | Satisfactory |
| OCF | TW A6 | Taxiway | 532 | 21,348 | 100 | Good |
| OCF | TW A7 | Taxiway | 525 | 16,153 | 58 | Fair |
| OCF | TW A8 | Taxiway | 560 | 15,868 | 78 | Satisfactory |
| OCF | TW A8 | Taxiway | 562 | 17,373 | 100 | Good |
| OCF | TW A8 | Taxiway | 565 | 15,850 | 85 | Satisfactory |
| OCF | TW A8 | Taxiway | 570 | 6,990 | 65 | Fair |
| OCF | TW A8 | Taxiway | 575 | 12,102 | 79 | Satisfactory |
| OCF | TW A9 | Taxiway | 550 | 27,079 | 74 | Satisfactory |
| OCF | TW A9 | Taxiway | 552 | 15,600 | 100 | Good |
| OCF | TW AP N | Taxiway | 595 | 33,596 | 70 | Fair |
| OCF | TW B | Taxiway | 105 | 73,305 | 51 | Poor |
| OCF | TW B1 | Taxiway | 104 | 5,513 | 59 | Fair |
| OCF | TW B2 | Taxiway | 106 | 6,834 | 52 | Poor |
| OCF | TW B3 | Taxiway | 102 | 5,513 | 55 | Poor |
| OCF | TL T-HANG | Taxilane | 3580 | 18,904 | 40 | Very Poor |
| OCF | TL T-HANG | Taxilane | 3585 | 76,028 | 52 | Poor |
| OCF | TL T-HANG | Taxilane | 3590 | 5,246 | 80 | Satisfactory |
| OCF | TL T-HANG | Taxilane | 3592 | 23,614 | 87 | Good |
| OCF | AP CENTER | Apron | 4105 | 168,599 | 52 | Poor |
| OCF | AP CENTER | Apron | 4107 | 93,441 | 100 | Good |
| OCF | AP CENTER | Apron | 4110 | 81,895 | 100 | Good |
| OCF | AP CENTER | Apron | 4115 | 120,000 | 100 | Good |

| Network ID | Branch ID | Branch Use | Section ID | Area (SF) | PCI | Condition Rating |
|------------|-----------|------------|------------|-----------|-----|------------------|
| OCF | AP CENTER | Apron | 4120 | 95,753 | 100 | Good |
| OCF | AP CENTER | Apron | 4125 | 30,574 | 100 | Good |
| OCF | AP CENTER | Apron | 4130 | 19,665 | 100 | Good |
| OCF | AP CENTER | Apron | 4135 | 123,619 | 84 | Satisfactory |
| OCF | AP CENTER | Apron | 4145 | 6,660 | 100 | Good |
| OCF | AP CENTER | Apron | 4150 | 6,000 | 33 | Very Poor |
| OCF | AP N | Apron | 4205 | 19,584 | 70 | Fair |
| OCF | AP N | Apron | 4210 | 41,762 | 55 | Poor |
| OCF | AP S | Apron | 4305 | 47,250 | 78 | Satisfactory |

Table A.3: Forecasted PCI Values 2023-2032 – Section-Level

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|------------|-----------|------------|-------------|------|------|------|------|------|------|------|------|------|------|
| OCF | RW 8-26 | 6205 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 70 |
| OCF | RW 18-36 | 6105 | 84 | 82 | 80 | 78 | 76 | 74 | 72 | 70 | 68 | 66 | 64 |
| OCF | RW 18-36 | 6110 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 | 65 | 63 |
| OCF | RW 18-36 | 6125 | 87 | 85 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 |
| OCF | RW 18-36 | 6135 | 85 | 83 | 81 | 79 | 77 | 75 | 73 | 71 | 69 | 67 | 65 |
| OCF | RW 18-36 | 6190 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 | 69 |
| OCF | RW 18-36 | 6195 | 86 | 84 | 82 | 80 | 79 | 77 | 75 | 74 | 72 | 71 | 69 |
| OCF | TW A | 304 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 305 | 88 | 86 | 84 | 82 | 80 | 78 | 77 | 75 | 74 | 73 | 71 |
| OCF | TW A | 505 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 540 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A | 542 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A1 | 592 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A10 | 535 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A11 | 545 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A12 | 555 | 82 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 69 | 68 |
| OCF | TW A13 | 596 | 80 | 78 | 76 | 75 | 74 | 72 | 71 | 70 | 69 | 67 | 66 |
| OCF | TW A2 | 501 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A3 | 510 | 75 | 73 | 72 | 71 | 69 | 68 | 67 | 66 | 65 | 64 | 63 |
| OCF | TW A3 | 512 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A4 | 514 | 74 | 72 | 71 | 70 | 68 | 67 | 66 | 65 | 64 | 62 | 61 |
| OCF | TW A4 | 515 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A5 | 520 | 81 | 79 | 77 | 76 | 74 | 73 | 72 | 70 | 69 | 68 | 67 |
| OCF | TW A6 | 532 | 100 | 95 | 93 | 91 | 89 | 87 | 85 | 83 | 81 | 79 | 78 |
| OCF | TW A7 | 525 | 58 | 56 | 55 | 53 | 52 | 50 | 48 | 46 | 44 | 42 | 40 |
| OCF | TW A8 | 560 | 78 | 76 | 75 | 73 | 72 | 71 | 69 | 68 | 67 | 66 | 65 |
| OCF | TW A8 | 562 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW A8 | 565 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 | 72 | 71 | 69 |
| OCF | TW A8 | 570 | 65 | 64 | 63 | 62 | 61 | 61 | 60 | 59 | 58 | 58 | 57 |
| OCF | TW A8 | 575 | 79 | 77 | 76 | 74 | 73 | 71 | 70 | 69 | 68 | 66 | 65 |
| OCF | TW A9 | 550 | 74 | 72 | 71 | 70 | 69 | 68 | 66 | 65 | 64 | 64 | 63 |
| OCF | TW A9 | 552 | 100 | 95 | 92 | 90 | 88 | 86 | 84 | 82 | 80 | 79 | 77 |
| OCF | TW AP N | 595 | 70 | 69 | 67 | 66 | 65 | 64 | 63 | 63 | 62 | 61 | 60 |
| OCF | TW B | 105 | 51 | 50 | 50 | 50 | 49 | 49 | 48 | 48 | 47 | 47 | 46 |
| OCF | TW B1 | 104 | 59 | 58 | 58 | 57 | 56 | 56 | 55 | 55 | 54 | 54 | 53 |
| OCF | TW B2 | 106 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| OCF | TW B3 | 102 | 55 | 54 | 54 | 53 | 53 | 53 | 52 | 52 | 51 | 51 | 50 |
| OCF | TL T-HANG | 3580 | 40 | 39 | 38 | 37 | 36 | 35 | 34 | 33 | 31 | 30 | 29 |
| OCF | TL T-HANG | 3585 | 52 | 51 | 51 | 51 | 50 | 50 | 49 | 49 | 48 | 48 | 47 |
| OCF | TL T-HANG | 3590 | 80 | 78 | 77 | 75 | 74 | 72 | 71 | 70 | 68 | 67 | 66 |
| OCF | TL T-HANG | 3592 | 87 | 85 | 83 | 81 | 79 | 78 | 76 | 75 | 73 | 72 | 71 |
| OCF | AP CENTER | 4105 | 52 | 50 | 48 | 46 | 44 | 42 | 40 | 38 | 36 | 34 | 32 |
| OCF | AP CENTER | 4107 | 100 | 95 | 93 | 90 | 88 | 86 | 84 | 82 | 80 | 78 | 76 |
| OCF | AP CENTER | 4110 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |

Airport Pavement Evaluation Report

Statewide Airfield Pavement Management Program

| Network ID | Branch ID | Section ID | Current PCI | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 |
|------------|-----------|------------|-------------|------|------|------|------|------|------|------|------|------|------|
| OCF | AP CENTER | 4115 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4120 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4125 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4130 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4135 | 84 | 82 | 80 | 78 | 76 | 74 | 73 | 71 | 69 | 68 | 66 |
| OCF | AP CENTER | 4145 | 100 | 96 | 94 | 92 | 90 | 88 | 86 | 84 | 83 | 81 | 79 |
| OCF | AP CENTER | 4150 | 33 | 32 | 31 | 30 | 29 | 28 | 27 | 26 | 25 | 24 | 23 |
| OCF | AP N | 4205 | 70 | 68 | 67 | 65 | 64 | 63 | 61 | 60 | 59 | 58 | 57 |
| OCF | AP N | 4210 | 55 | 54 | 53 | 52 | 51 | 51 | 50 | 49 | 48 | 48 | 47 |
| OCF | AP S | 4305 | 78 | 76 | 74 | 72 | 71 | 69 | 68 | 66 | 65 | 64 | 62 |

11/17/2022

Work History Report

Page 1 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4105 | | Surface: AAC |
|---------------------------------|-------------------|---------------------------------------|----------------------------|---------------------------|--------------------------------------|--|
| L.C.D. 1/1/1991 | Use: APRON | Rank: P | Length: 560.00 (Ft) | Width: 300.00 (Ft) | True Area: 168599.0000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1991 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1991 2" P-401 |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1977 2" P-401 |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1959 1.5" P-401 12" P-211 12" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4107 | | Surface: AC |
|---------------------------------|-------------------|---------------------------------------|----------------------------|---------------------------|--------------------------------------|----------------------------------|
| L.C.D. 7/1/2021 | Use: APRON | Rank: P | Length: 270.00 (Ft) | Width: 360.00 (Ft) | True Area: 93441.00002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 4" SP 12.5, 10" LBR 100 Limerock |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4110 | | Surface: AAC |
|---------------------------------|-------------------|---------------------------------------|----------------------------|---------------------------|--------------------------------------|---------------------------------|
| L.C.D. 7/1/2021 | Use: APRON | Rank: P | Length: 300.00 (Ft) | Width: 273.00 (Ft) | True Area: 81895.00002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, 3" SP 12.5 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1991 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1991 2" P-401 |
| 1/1/1983 | IMPORT ED | BUILT | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1983 1" P-401 8" P-211 4" P-154 |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4115 | | Surface: AAC |
|---------------------------------|-------------------|---------------------------------------|----------------------------|---------------------------|--------------------------------------|--|
| L.C.D. 7/1/2021 | Use: APRON | Rank: P | Length: 400.00 (Ft) | Width: 300.00 (Ft) | True Area: 120000.0000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, 3" SP 12.5 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1991 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1991 2" P-401 |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1977 2" P-401 |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1959 1.5" P-401 12" P-211 12" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4120 | | Surface: AAC |
|---------------------------------|-------------------|---------------------------------------|----------------------------|---------------------------|--------------------------------------|---------------------------------|
| L.C.D. 7/1/2021 | Use: APRON | Rank: P | Length: 420.00 (Ft) | Width: 230.00 (Ft) | True Area: 95753.00002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, 3" SP 12.5 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1991 | IMPORT ED | OVERLAY | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1991 1" P-401 |
| 1/1/1983 | IMPORT ED | BUILT | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1983 1" P-401 8" P-211 4" P-154 |

11/17/2022

Work History Report

Page 2 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4125 | | Surface: AAC |
|---------------------------------|-------------------|---------------------------------------|----------------------------|---------------------------|--------------------------------------|---------------------------------|
| L.C.D. 7/1/2021 | Use: APRON | Rank: P | Length: 250.00 (Ft) | Width: 120.00 (Ft) | True Area: 30574.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, 3" SP 12.5 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1983 | IMPORT ED | BUILT | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1983 1" P-401 8" P-211 4" P-154 |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4130 | | Surface: AAC |
|---------------------------------|-------------------|---------------------------------------|---------------------------|---------------------------|--------------------------------------|-----------------------------------|
| L.C.D. 7/1/2021 | Use: APRON | Rank: P | Length: 96.00 (Ft) | Width: 200.00 (Ft) | True Area: 19665.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, 3" SP 12.5 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1991 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1991 2" P-401 |
| 1/1/1985 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1985 1.5" P-401 8" P-211 4" P-154 |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4135 | | Surface: AC |
|---------------------------------|-------------------|---------------------------------------|------------------------------|--------------------------|--------------------------------------|--------------------|
| L.C.D. 7/1/2009 | Use: APRON | Rank: P | Length: 1,642.00 (Ft) | Width: 60.00 (Ft) | True Area: 123619.0000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2009 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4145 | | Surface: AAC |
|---------------------------------|-------------------|---------------------------------------|---------------------------|--------------------------|--------------------------------------|--|
| L.C.D. 7/1/2021 | Use: APRON | Rank: P | Length: 90.00 (Ft) | Width: 72.00 (Ft) | True Area: 6660.000002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, 3" SP 12.5 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1991 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1991 2" P-401 |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1977 2" P-401 |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1959 1.5" P-401 12" P-211 12" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: AP CENTER CENTRAL APRO | | Section: 4150 | | Surface: PCC |
|---------------------------------|-------------------|---------------------------------------|---------------------------|---------------------------|--------------------------------------|---------------------|
| L.C.D. 1/1/1999 | Use: APRON | Rank: P | Length: 60.00 (Ft) | Width: 100.00 (Ft) | True Area: 6000.000001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1999 | NC-PC | New Construction - PCC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: AP N NORTH APRON | | Section: 4205 | | Surface: AC |
|---------------------------------|-------------------|---------------------------------|----------------------------|---------------------------|--------------------------------------|--------------------|
| L.C.D. 1/1/2000 | Use: APRON | Rank: P | Length: 300.00 (Ft) | Width: 200.00 (Ft) | True Area: 19584.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | ESTIMATED |

11/17/2022

Work History Report

Page 3 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: AP N | NORTH APRON | | Section: 4210 | Surface: AC |
|--------------------------|------------|-------------------------------|---------------------|--------------------|-------------------------------------|-------------|
| L.C.D. 1/1/2000 | Use: APRON | Rank: P | Length: 300.00 (Ft) | Width: 200.00 (Ft) | True Area: 41762.00001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | |
| 1/1/2000 | NU-IN | New Construction - Initial | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: AP S | SOUTH APRON | | Section: 4305 | Surface: AC |
|--------------------------|------------|-----------------------|---------------------|--------------------|-------------------------------------|-------------|
| L.C.D. 1/1/2010 | Use: APRON | Rank: P | Length: 350.00 (Ft) | Width: 135.00 (Ft) | True Area: 47250.00001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2010 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: RW 18-36 | RUNWAY 18-36 | | Section: 6105 | Surface: AAC |
|--------------------------|-------------|------------------|---------------------|-------------------|-------------------------------------|---|
| L.C.D. 1/1/2009 | Use: RUNWAY | Rank: P | Length: 900.00 (Ft) | Width: 75.00 (Ft) | True Area: 373275.0001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2009 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 2009 1" MILL AND 2" NOMINAL O |
| 1/1/1991 | IMPORT ED | OVERLAY | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1991 1" P-401 1.5" S-401 .75-2.5" P-211 4" RECYCLED BIT |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 12.00 | <input checked="" type="checkbox"/> | 1959 12" LIMEROCK 12" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: RW 18-36 | RUNWAY 18-36 | | Section: 6110 | Surface: AAC |
|--------------------------|-------------|-------------------------------|-----------------------|-------------------|-------------------------------------|--|
| L.C.D. 1/1/2009 | Use: RUNWAY | Rank: P | Length: 1,000.00 (Ft) | Width: 38.00 (Ft) | True Area: 373275.0001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2009 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 2009 1"-2" MILL AND 2" OVERLAY |
| 1/1/1991 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | 1991 SLURRY SEAL |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1977 2" P-401 |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1959 1.5" P-401 12" P-211 12" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: RW 18-36 | RUNWAY 18-36 | | Section: 6125 | Surface: AAC |
|--------------------------|-------------|------------------|-----------------------|-------------------|-------------------------------------|--|
| L.C.D. 1/1/2009 | Use: RUNWAY | Rank: P | Length: 2,640.00 (Ft) | Width: 50.00 (Ft) | True Area: 94500.00002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2009 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 2009 1"-2" MILL AND 2" OVERLAY |
| 1/1/1988 | IMPORT ED | BUILT | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1988 2" P-401 14" P-211 10" P-154 17" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: RW 18-36 | RUNWAY 18-36 | | Section: 6135 | Surface: AAC |
|--------------------------|-------------|------------------|-----------------------|-------------------|-------------------------------------|---|
| L.C.D. 1/1/2009 | Use: RUNWAY | Rank: P | Length: 3,000.00 (Ft) | Width: 25.00 (Ft) | True Area: 189000.0000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2009 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |
| 1/1/1988 | IMPORT ED | BUILT | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1988 2" P-401 10"P-211 14" P-154 17" SUBGRADE |

11/17/2022

Work History Report

Page 4 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: RW 18-36 | RUNWAY 18-36 | | Section: 6190 | Surface: AC |
|--------------------------|-------------|-----------------------|---------------------|--------------------|-------------------------------------|-------------|
| L.C.D. 1/1/2008 | Use: RUNWAY | Rank: P | Length: 595.00 (Ft) | Width: 150.00 (Ft) | True Area: 30000.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2008 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: RW 18-36 | RUNWAY 18-36 | | Section: 6195 | Surface: AC |
|--------------------------|-------------|----------------------------|---------------------|--------------------|-------------------------------------|-------------|
| L.C.D. 1/1/2008 | Use: RUNWAY | Rank: P | Length: 595.00 (Ft) | Width: 150.00 (Ft) | True Area: 60000.00001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2008 | NU-IN | New Construction - Initial | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: RW 8-26 | RUNWAY 8-26 | | Section: 6205 | Surface: AAC |
|--------------------------|-------------|-------------------------|-----------------------|-------------------|-------------------------------------|---------------------------|
| L.C.D. 1/1/2013 | Use: RUNWAY | Rank: S | Length: 3,010.00 (Ft) | Width: 50.00 (Ft) | True Area: 150450.0000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2013 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 2013 UNKNOWN COLD RECONST |
| 1/1/2002 | OL-AS | Overlay - AC Structural | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1" AC Ovly |
| 1/1/1973 | IMPORT ED | BUILT | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1973 1" P-401 10" P-211 |

| Network: OCALA INTERNATI | | Branch: TL T-HANG | T-HANGAR TAX | | Section: 3580 | Surface: AC |
|--------------------------|--------------|-------------------------------|---------------------|-------------------|-------------------------------------|-------------|
| L.C.D. 1/1/2000 | Use: TAXILAN | Rank: P | Length: 880.00 (Ft) | Width: 30.00 (Ft) | True Area: 18904.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI | | Branch: TL T-HANG | T-HANGAR TAX | | Section: 3585 | Surface: AC |
|--------------------------|--------------|-------------------------------|-----------------------|-------------------|-------------------------------------|-------------------|
| L.C.D. 1/1/2000 | Use: TAXILAN | Rank: P | Length: 3,300.00 (Ft) | Width: 23.00 (Ft) | True Area: 76028.00002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI | | Branch: TL T-HANG | T-HANGAR TAX | | Section: 3590 | Surface: AAC |
|--------------------------|--------------|-------------------------------|---------------------|-------------------|-------------------------------------|--------------|
| L.C.D. 1/1/2009 | Use: TAXILAN | Rank: P | Length: 105.00 (Ft) | Width: 40.00 (Ft) | True Area: 5246.000001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2009 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | |
| 1/1/1977 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI | | Branch: TL T-HANG | T-HANGAR TAX | | Section: 3592 | Surface: AC |
|--------------------------|--------------|-----------------------|---------------------|-------------------|-------------------------------------|-------------|
| L.C.D. 1/1/2009 | Use: TAXILAN | Rank: P | Length: 965.00 (Ft) | Width: 25.00 (Ft) | True Area: 23614.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2009 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

11/17/2022

Work History Report

Page 5 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: TW A10 | TAXIWAY A10 | Section: 535 | Surface: AAC | |
|--------------------------|--------------|------------------|---------------------|-------------------|-------------------------------------|--|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 300.00 (Ft) | Width: 60.00 (Ft) | True Area: 28064.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | Mill 4", P-401 Overlay Variable Dept |
| 1/1/1988 | IMPORT ED | BUILT | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1988 2" P-401 14" P-211 10" P-154 17" SUBGRADE |

| Network: OCALA INTERNATIONAL | | Branch: TW A11 | TAXIWAY C | Section: 545 | Surface: AAC | |
|------------------------------|--------------|------------------|---------------------|-------------------|-------------------------------------|--|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 300.00 (Ft) | Width: 50.00 (Ft) | True Area: 23035.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | Mill 4", P-401 Overlay Variable Dept |
| 1/1/1988 | IMPORT ED | BUILT | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1988 2" P-401 14" P-211 10" P-154 17" SUBGRADE |

| Network: OCALA INTERNATIONAL | | Branch: TW A12 | TAXIWAY A12 | Section: 555 | Surface: AC | |
|------------------------------|--------------|----------------------------|---------------------|-------------------|-------------------------------------|----------|
| L.C.D. 1/1/2008 | Use: TAXIWAY | Rank: P | Length: 802.00 (Ft) | Width: 40.00 (Ft) | True Area: 33994.00001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2008 | NU-IN | New Construction - Initial | 0.00 | 0.00 | <input checked="" type="checkbox"/> | UNKNOWN |

| Network: OCALA INTERNATIONAL | | Branch: TW A13 | TAXIWAY A13 | Section: 596 | Surface: AC | |
|------------------------------|--------------|-----------------------|---------------------|-------------------|-------------------------------------|----------|
| L.C.D. 1/1/2008 | Use: TAXIWAY | Rank: P | Length: 600.00 (Ft) | Width: 80.00 (Ft) | True Area: 54138.00001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2008 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATIONAL | | Branch: TW A1 | TAXIWAY A1 | Section: 592 | Surface: AC | |
|------------------------------|--------------|-----------------------|---------------------|-------------------|-------------------------------------|----------------------------------|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 285.00 (Ft) | Width: 43.00 (Ft) | True Area: 23030.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 4" SP 12.5, 10" LBR 100 Limerock |

| Network: OCALA INTERNATI | | Branch: TW A2 | TAXIWAY A2 | | Section: 501 | Surface: AAC |
|--------------------------|--------------|------------------------------|---------------------|-------------------|-------------------------------------|---------------------------------------|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: T | Length: 207.00 (Ft) | Width: 80.00 (Ft) | True Area: 31144.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, Variable Depth P-401 Overlay |
| 1/1/2007 | CR-AC | Complete Reconstruction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |
| 1/1/1977 | NU-IN | New Construction - Initial | 0.00 | 0.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: TW A | TAXIWAY A | | Section: 304 | Surface: AAC |
|--------------------------|--------------|------------------|---------------------|-------------------|-------------------------------------|---------------------------------------|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 430.00 (Ft) | Width: 25.00 (Ft) | True Area: 11360.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, Variable Depth P-401 Overlay |
| 1/1/2013 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 2013 MILL AND OVERLAY WITH |
| 1/1/1973 | IMPORT ED | BUILT | 0.00 | 1.00 | <input checked="" type="checkbox"/> | 1973: 1" P401 ON 10" P211 |

11/17/2022

Work History Report

Page 6 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: TW A | TAXIWAY A | | Section: 305 | Surface: AAC |
|--------------------------|--------------|------------------|--------------------|--------------------|-------------------------------------|---|
| L.C.D. 1/1/2013 | Use: TAXIWAY | Rank: P | Length: 25.00 (Ft) | Width: 175.00 (Ft) | True Area: 4941.000001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2013 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 2013 MILL AND OVERLAY WITH 1973: 1" P401 ON 10" P211 |
| 1/1/1973 | IMPORT ED | BUILT | 0.00 | 1.00 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: TW A3 | TAXIWAY A3 | | Section: 510 | Surface: AC |
|--------------------------|--------------|-------------------------------|---------------------|-------------------|-------------------------------------|-----------------------------------|
| L.C.D. 1/1/1985 | Use: TAXIWAY | Rank: P | Length: 110.00 (Ft) | Width: 36.00 (Ft) | True Area: 3960.000001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | 1985 1.5" P-401 8" P-211 4" P-154 |
| 1/1/1985 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: TW A3 | TAXIWAY A3 | | Section: 512 | Surface: AAC |
|--------------------------|--------------|-------------------------------|---------------------|-------------------|-------------------------------------|---------------------------------------|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 205.00 (Ft) | Width: 70.00 (Ft) | True Area: 17192.000000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, Variable Depth P-401 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | |
| 1/1/1985 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1985 1.5" P-401 8" P-211 4" P-154 |

| Network: OCALA INTERNATI | | Branch: TW A4 | TAXIWAY A4 | | Section: 514 | Surface: AAC |
|--------------------------|--------------|----------------------------|---------------------|-------------------|-------------------------------------|---|
| L.C.D. 1/1/2009 | Use: TAXIWAY | Rank: P | Length: 200.00 (Ft) | Width: 50.00 (Ft) | True Area: 11036.000000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2009 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 2009 MILL AND OVERLAY FROM 1977 2" P-401 |
| 1/1/1977 | ML-OVL | Mill and Overlay | 0.00 | 2.00 | <input checked="" type="checkbox"/> | |
| 1/1/1959 | NU-IN | New Construction - Initial | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 1959 1.5" P-401 12" P-211 12" SUBG |

| Network: OCALA INTERNATI | | Branch: TW A4 | TAXIWAY A4 | | Section: 515 | Surface: AAC |
|--------------------------|--------------|------------------|---------------------|-------------------|-------------------------------------|--|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 200.00 (Ft) | Width: 50.00 (Ft) | True Area: 3791.000001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, Variable Depth P-401 Overlay 1977 2" P-401 |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1959 1.5" P-401 12" P-211 12" SUBGRADE |

11/17/2022

Work History Report

Page 7 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: TW A | TAXIWAY A | | Section: 505 | Surface: AAC |
|--------------------------|--------------|------------------|-----------------------|-------------------|-------------------------------------|--|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 4,895.00 (Ft) | Width: 50.00 (Ft) | True Area: 210730.0000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, Variable Depth P-401 Overlay |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1977 2" P-401 |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1959 1.5" P-401 12" P-211 12" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: TW A | TAXIWAY A | | Section: 540 | Surface: AAC |
|--------------------------|--------------|------------------|-----------------------|-------------------|-------------------------------------|--|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 2,075.00 (Ft) | Width: 50.00 (Ft) | True Area: 104692.0000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 4" Mill, Variable Depth P-401 Overlay |
| 1/1/1988 | IMPORT ED | BUILT | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1988 2" P-401 14" P-211 10" P-154 17" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: TW A | TAXIWAY A | | Section: 542 | Surface: AC |
|--------------------------|--------------|-----------------------|--------------------|--------------------|-------------------------------------|--|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 50.00 (Ft) | Width: 705.00 (Ft) | True Area: 34610.00001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 4" P-401, 12" Limerock Base Course, |
| 1/1/1988 | IMPORT ED | BUILT | 0.00 | 2.00 | <input checked="" type="checkbox"/> | 1988 2" P-401 14" P-211 10" P-154 17" SUBGRADE |

| Network: OCALA INTERNATI | | Branch: TW A5 | TAXIWAY A5 | | Section: 520 | Surface: AAC |
|--------------------------|--------------|-------------------------------|---------------------|-------------------|-------------------------------------|--|
| L.C.D. 1/1/1977 | Use: TAXIWAY | Rank: P | Length: 260.00 (Ft) | Width: 50.00 (Ft) | True Area: 16927.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | 1977: 2" P401 OVERLAY 1959: 1.5" P401 ON 12" P211 ON 12" COMP. SUBGRADE |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | |

| Network: OCALA INTERNATI | | Branch: TW A6 | TAXIWAY A6 | | Section: 532 | Surface: AC |
|--------------------------|--------------|-----------------------|---------------------|-------------------|-------------------------------------|----------------------------------|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 200.00 (Ft) | Width: 65.00 (Ft) | True Area: 21348.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 4" SP 12.5, 10" LBR 100 Limerock |

| Network: OCALA INTERNATI | | Branch: TW A7 | TAXIWAY A7 | | Section: 525 | Surface: AAC |
|--------------------------|--------------|-------------------------------|---------------------|-------------------|-------------------------------------|---|
| L.C.D. 1/1/1977 | Use: TAXIWAY | Rank: P | Length: 265.00 (Ft) | Width: 50.00 (Ft) | True Area: 16153.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | 1977 2" P-401 1959 1.5" P-401 12" P-211 12" SUBGRADE |
| 1/1/1977 | IMPORT ED | OVERLAY | 0.00 | 2.00 | <input checked="" type="checkbox"/> | |
| 1/1/1959 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | |

11/17/2022

Work History Report

Page 8 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI Branch: TW A8 TAXIWAY A8 Section: 560 Surface: AC L.C.D. 1/1/2000 Use: TAXIWAY Rank: P Length: 340.00 (Ft) Width: 20.00 (Ft) True Area: 15868.00000 (SqFt) | | | | | | |
|---|-----------|-------------------------------|------|----------------|-------------------------------------|-------------------|
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI Branch: TW A8 TAXIWAY A8 Section: 562 Surface: AAC L.C.D. 7/1/2021 Use: TAXIWAY Rank: P Length: 20.00 (Ft) Width: 260.00 (Ft) True Area: 17373.00000 (SqFt) | | | | | | |
|--|-----------|-------------------------------|------|----------------|-------------------------------------|---------------------------------------|
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, Variable Depth P-401 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI Branch: TW A8 TAXIWAY A8 Section: 565 Surface: AC L.C.D. 1/1/2000 Use: TAXIWAY Rank: P Length: 400.00 (Ft) Width: 25.00 (Ft) True Area: 15850.00000 (SqFt) | | | | | | |
|---|-----------|-------------------------------|------|----------------|-------------------------------------|-------------------|
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI Branch: TW A8 TAXIWAY A8 Section: 570 Surface: AC L.C.D. 1/1/2000 Use: TAXIWAY Rank: P Length: 400.00 (Ft) Width: 25.00 (Ft) True Area: 6990.000002 (SqFt) | | | | | | |
|---|-----------|-------------------------------|------|----------------|-------------------------------------|-----------|
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI Branch: TW A8 TAXIWAY A8 Section: 575 Surface: AAC L.C.D. 1/1/2010 Use: TAXIWAY Rank: P Length: 415.00 (Ft) Width: 25.00 (Ft) True Area: 12102.00000 (SqFt) | | | | | | |
|--|-----------|-------------------------------|------|----------------|-------------------------------------|-------------------|
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2010 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | Estimated Date |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/1940 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI Branch: TW A9 TAXIWAY A9 Section: 550 Surface: AC L.C.D. 1/1/2000 Use: TAXIWAY Rank: P Length: 650.00 (Ft) Width: 40.00 (Ft) True Area: 27079.00000 (SqFt) | | | | | | |
|---|-----------|-------------------------------|------|----------------|-------------------------------------|-------------------|
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

11/17/2022

Work History Report

Page 9 of 10

Pavement Database: FDOT

| Network: OCALA INTERNATI | | Branch: TW A9 | TAXIWAY A9 | | Section: 552 | Surface: AAC |
|---------------------------------|---------------------|-------------------------------|----------------------------|--------------------------|--------------------------------------|---------------------------------------|
| L.C.D. 7/1/2021 | Use: TAXIWAY | Rank: P | Length: 230.00 (Ft) | Width: 45.00 (Ft) | True Area: 15600.00000 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 7/1/2021 | ML-OVL | Mill and Overlay | 0.00 | 0.00 | <input checked="" type="checkbox"/> | 3" Mill, Variable Depth P-401 Overlay |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI | | Branch: TW AP N | NORTH APRON | | Section: 595 | Surface: AC |
|---------------------------------|---------------------|-------------------------------|---------------------------|---------------------------|--------------------------------------|--------------------|
| L.C.D. 1/1/2000 | Use: TAXIWAY | Rank: P | Length: 20.00 (Ft) | Width: 800.00 (Ft) | True Area: 33596.00001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/2004 | ST-SC | Surface Treatment - Seal Coat | 0.00 | 0.00 | <input type="checkbox"/> | Polycon Seal coat |
| 1/1/2000 | NC-AC | New Construction - AC | 0.00 | 0.00 | <input checked="" type="checkbox"/> | estimated |

| Network: OCALA INTERNATI | | Branch: TW B | TAXIWAY B | | Section: 105 | Surface: AC |
|---------------------------------|---------------------|---------------------|------------------------------|--------------------------|--------------------------------------|-----------------------------------|
| L.C.D. 1/1/1985 | Use: TAXIWAY | Rank: P | Length: 2,895.00 (Ft) | Width: 25.00 (Ft) | True Area: 73305.00002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1985 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1985 1.5" P-401 6" P-211 4" P-154 |

| Network: OCALA INTERNATI | | Branch: TW B1 | TAXIWAY B1 | | Section: 104 | Surface: AC |
|---------------------------------|---------------------|----------------------|----------------------------|--------------------------|--------------------------------------|-----------------------------------|
| L.C.D. 1/1/1985 | Use: TAXIWAY | Rank: P | Length: 203.00 (Ft) | Width: 25.00 (Ft) | True Area: 5513.000001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1985 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1985 1.5" P-401 6" P-211 4" P-154 |

| Network: OCALA INTERNATI | | Branch: TW B2 | TAXIWAY B2 | | Section: 106 | Surface: AC |
|---------------------------------|---------------------|----------------------|----------------------------|--------------------------|--------------------------------------|-----------------------------------|
| L.C.D. 1/1/1985 | Use: TAXIWAY | Rank: P | Length: 180.00 (Ft) | Width: 25.00 (Ft) | True Area: 6834.000002 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1985 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1985 1.5" P-401 6" P-211 4" P-154 |

| Network: OCALA INTERNATI | | Branch: TW B3 | TAXIWAY B3 | | Section: 102 | Surface: AC |
|---------------------------------|---------------------|----------------------|----------------------------|--------------------------|--------------------------------------|-----------------------------------|
| L.C.D. 1/1/1985 | Use: TAXIWAY | Rank: P | Length: 180.00 (Ft) | Width: 25.00 (Ft) | True Area: 5513.000001 (SqFt) | |
| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major M&R | Comments |
| 1/1/1985 | IMPORT ED | BUILT | 0.00 | 1.50 | <input checked="" type="checkbox"/> | 1985 1.5" P-401 6" P-211 4" P-154 |

Summary:

| Work Description | Section Count | Area Total (SqFt) | Thickness Avg (in) | Thickness STD (in) |
|-------------------------------|---------------|-------------------|--------------------|--------------------|
| BUILT | 28 | 2,270,266.00 | 1.87 | 1.98 |
| Complete Reconstruction - AC | 1 | 31,144.00 | 0.00 | 0.00 |
| Mill and Overlay | 27 | 2,053,749.00 | 0.07 | 0.38 |
| New Construction - AC | 21 | 715,270.00 | 0.00 | 0.00 |
| New Construction - Initial | 5 | 177,936.00 | 0.00 | 0.00 |
| New Construction - PCC | 1 | 6,000.00 | 0.00 | 0.00 |
| OVERLAY | 15 | 1,781,982.00 | 1.87 | 0.34 |
| Overlay - AC Structural | 1 | 150,450.00 | 1.00 | 0.00 |
| Surface Treatment - Seal Coat | 25 | 1,256,635.00 | 0.00 | 0.00 |

11/17/2022

Branch Condition Report

Page 1 of 2

Pavement Database: FDOT

| Branch ID | Number of Sections | Sum Section Length (Ft) | Avg Section Width (Ft) | True Area (SqFt) | Use | Average PCI | Standard Deviation PCI | Weighted Average PCI |
|-----------|--------------------|-------------------------|------------------------|------------------|----------|-------------|------------------------|----------------------|
| AP CENTE | 10 | 4,088.00 | 201.50 | 746,206.00 | APRON | 86.90 | 23.09 | 85.97 |
| AP N | 2 | 600.00 | 200.00 | 61,346.00 | APRON | 62.50 | 7.50 | 59.79 |
| AP S | 1 | 350.00 | 135.00 | 47,250.00 | APRON | 78.00 | 0.00 | 78.00 |
| RW 18-36 | 6 | 8,730.00 | 81.33 | 1,120,050.00 | RUNWAY | 85.17 | 1.34 | 84.25 |
| RW 8-26 | 1 | 3,010.00 | 50.00 | 150,450.00 | RUNWAY | 90.00 | 0.00 | 90.00 |
| TL T-HANG | 4 | 5,250.00 | 29.50 | 123,792.00 | TAXILANE | 64.75 | 19.38 | 58.03 |
| TW A | 5 | 7,475.00 | 201.00 | 366,333.00 | TAXIWAY | 97.60 | 4.80 | 99.84 |
| TW A1 | 1 | 285.00 | 43.00 | 23,030.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A10 | 1 | 300.00 | 60.00 | 28,064.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A11 | 1 | 300.00 | 50.00 | 23,035.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A12 | 1 | 802.00 | 40.00 | 33,994.00 | TAXIWAY | 82.00 | 0.00 | 82.00 |
| TW A13 | 1 | 600.00 | 80.00 | 54,138.00 | TAXIWAY | 80.00 | 0.00 | 80.00 |
| TW A2 | 1 | 207.00 | 80.00 | 31,144.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A3 | 2 | 315.00 | 53.00 | 21,152.00 | TAXIWAY | 87.50 | 12.50 | 95.32 |
| TW A4 | 2 | 400.00 | 50.00 | 14,827.00 | TAXIWAY | 87.00 | 13.00 | 80.65 |
| TW A5 | 1 | 260.00 | 50.00 | 16,927.00 | TAXIWAY | 81.00 | 0.00 | 81.00 |
| TW A6 | 1 | 200.00 | 65.00 | 21,348.00 | TAXIWAY | 100.00 | 0.00 | 100.00 |
| TW A7 | 1 | 265.00 | 50.00 | 16,153.00 | TAXIWAY | 58.00 | 0.00 | 58.00 |
| TW A8 | 5 | 1,575.00 | 71.00 | 68,183.00 | TAXIWAY | 81.40 | 11.36 | 84.08 |
| TW A9 | 2 | 880.00 | 42.50 | 42,679.00 | TAXIWAY | 87.00 | 13.00 | 83.50 |
| TW AP N | 1 | 20.00 | 800.00 | 33,596.00 | TAXIWAY | 70.00 | 0.00 | 70.00 |
| TW B | 1 | 2,895.00 | 25.00 | 73,305.00 | TAXIWAY | 51.00 | 0.00 | 51.00 |
| TW B1 | 1 | 203.00 | 25.00 | 5,513.00 | TAXIWAY | 59.00 | 0.00 | 59.00 |
| TW B2 | 1 | 180.00 | 25.00 | 6,834.00 | TAXIWAY | 52.00 | 0.00 | 52.00 |
| TW B3 | 1 | 180.00 | 25.00 | 5,513.00 | TAXIWAY | 55.00 | 0.00 | 55.00 |

11/17/2022

Branch Condition Report

Page 2 of 2

Pavement Database: FDOT

| Use Category | Number of Sections | Total Area (SqFt) | Arithmetic Average PCI | Average STD PCI | Weighted Average PCI |
|--------------|--------------------|-------------------|------------------------|-----------------|----------------------|
| APRON | 13 | 854,802.00 | 82.46 | 22.29 | 83.65 |
| RUNWAY | 7 | 1,270,500.00 | 85.86 | 2.10 | 84.93 |
| TAXILANE | 4 | 123,792.00 | 64.75 | 19.38 | 58.03 |
| TAXIWAY | 30 | 885,768.00 | 83.53 | 16.85 | 88.34 |
| ALL | 54 | 3,134,862.00 | 82.19 | 18.20 | 84.48 |

Pavement Database: FDOT

NetworkId: OCF

| Branch ID | Section ID | Last Const. Date | Surface | Use | Rank | Lanes | True Area (SqFt) | Last Inspection Date | Age At Inspection | PCI |
|-----------|------------|------------------|---------|----------|------|-------|------------------|----------------------|-------------------|-----|
| AP CENTER | 4105 | 1/1/1991 | AAC | APRON | P | 0 | 168,599.00 | 4/25/2022 | 31 | 52 |
| AP CENTER | 4107 | 7/1/2021 | AC | APRON | P | 0 | 93,441.00 | 7/1/2021 | 0 | 100 |
| AP CENTER | 4110 | 7/1/2021 | AAC | APRON | P | 0 | 81,895.00 | 7/1/2021 | 0 | 100 |
| AP CENTER | 4115 | 7/1/2021 | AAC | APRON | P | 0 | 120,000.00 | 7/1/2021 | 0 | 100 |
| AP CENTER | 4120 | 7/1/2021 | AAC | APRON | P | 0 | 95,753.00 | 7/1/2021 | 0 | 100 |
| AP CENTER | 4125 | 7/1/2021 | AAC | APRON | P | 0 | 30,574.00 | 7/1/2021 | 0 | 100 |
| AP CENTER | 4130 | 7/1/2021 | AAC | APRON | P | 0 | 19,665.00 | 7/1/2021 | 0 | 100 |
| AP CENTER | 4135 | 7/1/2009 | AC | APRON | P | 0 | 123,619.00 | 4/25/2022 | 13 | 84 |
| AP CENTER | 4145 | 7/1/2021 | AAC | APRON | P | 0 | 6,660.00 | 7/1/2021 | 0 | 100 |
| AP CENTER | 4150 | 1/1/1999 | PCC | APRON | P | 0 | 6,000.00 | 4/25/2022 | 23 | 33 |
| AP N | 4205 | 1/1/2000 | AC | APRON | P | 0 | 19,584.00 | 4/25/2022 | 22 | 70 |
| AP N | 4210 | 1/1/2000 | AC | APRON | P | 0 | 41,762.00 | 4/25/2022 | 22 | 55 |
| AP S | 4305 | 1/1/2010 | AC | APRON | P | 0 | 47,250.00 | 4/25/2022 | 12 | 78 |
| RW 18-36 | 6105 | 1/1/2009 | AAC | RUNWAY | P | 0 | 373,275.00 | 4/25/2022 | 13 | 84 |
| RW 18-36 | 6110 | 1/1/2009 | AAC | RUNWAY | P | 0 | 373,275.00 | 4/25/2022 | 13 | 83 |
| RW 18-36 | 6125 | 1/1/2009 | AAC | RUNWAY | P | 0 | 94,500.00 | 4/25/2022 | 13 | 87 |
| RW 18-36 | 6135 | 1/1/2009 | AAC | RUNWAY | P | 0 | 189,000.00 | 4/25/2022 | 13 | 85 |
| RW 18-36 | 6190 | 1/1/2008 | AC | RUNWAY | P | 0 | 30,000.00 | 4/25/2022 | 14 | 86 |
| RW 18-36 | 6195 | 1/1/2008 | AC | RUNWAY | P | 0 | 60,000.00 | 4/25/2022 | 14 | 86 |
| RW 8-26 | 6205 | 1/1/2013 | AAC | RUNWAY | S | 0 | 150,450.00 | 4/25/2022 | 9 | 90 |
| TL T-HANG | 3580 | 1/1/2000 | AC | TAXILANE | P | 0 | 18,904.00 | 4/25/2022 | 22 | 40 |
| TL T-HANG | 3585 | 1/1/2000 | AC | TAXILANE | P | 0 | 76,028.00 | 4/25/2022 | 22 | 52 |
| TL T-HANG | 3590 | 1/1/2009 | AAC | TAXILANE | P | 0 | 5,246.00 | 4/25/2022 | 13 | 80 |
| TL T-HANG | 3592 | 1/1/2009 | AC | TAXILANE | P | 0 | 23,614.00 | 4/25/2022 | 13 | 87 |
| TW A | 304 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 11,360.00 | 7/1/2021 | 0 | 100 |
| TW A | 305 | 1/1/2013 | AAC | TAXIWAY | P | 0 | 4,941.00 | 4/25/2022 | 9 | 88 |
| TW A | 505 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 210,730.00 | 7/1/2021 | 0 | 100 |
| TW A | 540 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 104,692.00 | 7/1/2021 | 0 | 100 |
| TW A | 542 | 7/1/2021 | AC | TAXIWAY | P | 0 | 34,610.00 | 7/1/2021 | 0 | 100 |
| TW A1 | 592 | 7/1/2021 | AC | TAXIWAY | P | 0 | 23,030.00 | 7/1/2021 | 0 | 100 |
| TW A10 | 535 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 28,064.00 | 7/1/2021 | 0 | 100 |
| TW A11 | 545 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 23,035.00 | 7/1/2021 | 0 | 100 |
| TW A12 | 555 | 1/1/2008 | AC | TAXIWAY | P | 0 | 33,994.00 | 4/25/2022 | 14 | 82 |
| TW A13 | 596 | 1/1/2008 | AC | TAXIWAY | P | 0 | 54,138.00 | 4/25/2022 | 14 | 80 |
| TW A2 | 501 | 7/1/2021 | AAC | TAXIWAY | T | 0 | 31,144.00 | 7/1/2021 | 0 | 100 |
| TW A3 | 510 | 1/1/1985 | AC | TAXIWAY | P | 0 | 3,960.00 | 4/25/2022 | 37 | 75 |
| TW A3 | 512 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 17,192.00 | 7/1/2021 | 0 | 100 |
| TW A4 | 514 | 1/1/2009 | AAC | TAXIWAY | P | 0 | 11,036.00 | 4/25/2022 | 13 | 74 |
| TW A4 | 515 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 3,791.00 | 7/1/2021 | 0 | 100 |
| TW A5 | 520 | 1/1/1977 | AAC | TAXIWAY | P | 0 | 16,927.00 | 4/25/2022 | 45 | 81 |
| TW A6 | 532 | 7/1/2021 | AC | TAXIWAY | P | 0 | 21,348.00 | 7/1/2021 | 0 | 100 |
| TW A7 | 525 | 1/1/1977 | AAC | TAXIWAY | P | 0 | 16,153.00 | 4/25/2022 | 45 | 58 |
| TW A8 | 560 | 1/1/2000 | AC | TAXIWAY | P | 0 | 15,868.00 | 4/25/2022 | 22 | 78 |
| TW A8 | 562 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 17,373.00 | 7/1/2021 | 0 | 100 |
| TW A8 | 565 | 1/1/2000 | AC | TAXIWAY | P | 0 | 15,850.00 | 4/25/2022 | 22 | 85 |
| TW A8 | 570 | 1/1/2000 | AC | TAXIWAY | P | 0 | 6,990.00 | 4/25/2022 | 22 | 65 |
| TW A8 | 575 | 1/1/2010 | AAC | TAXIWAY | P | 0 | 12,102.00 | 4/25/2022 | 12 | 79 |
| TW A9 | 550 | 1/1/2000 | AC | TAXIWAY | P | 0 | 27,079.00 | 4/25/2022 | 22 | 74 |

| | | | | | | | | | | |
|---------|-----|----------|-----|---------|---|---|-----------|-----------|----|-----|
| TW A9 | 552 | 7/1/2021 | AAC | TAXIWAY | P | 0 | 15,600.00 | 7/1/2021 | 0 | 100 |
| TW AP N | 595 | 1/1/2000 | AC | TAXIWAY | P | 0 | 33,596.00 | 4/25/2022 | 22 | 70 |
| TW B | 105 | 1/1/1985 | AC | TAXIWAY | P | 0 | 73,305.00 | 4/25/2022 | 37 | 51 |
| TW B1 | 104 | 1/1/1985 | AC | TAXIWAY | P | 0 | 5,513.00 | 4/25/2022 | 37 | 59 |
| TW B2 | 106 | 1/1/1985 | AC | TAXIWAY | P | 0 | 6,834.00 | 4/25/2022 | 37 | 52 |
| TW B3 | 102 | 1/1/1985 | AC | TAXIWAY | P | 0 | 5,513.00 | 4/25/2022 | 37 | 55 |

Pavement Database: FDOT

| Age Category | Average Age at Inspection | Total Area (SqFt) | Number of Sections | Arithmetic Average PCI | Standard Deviation PCI | Weighted Average PCI |
|--------------|---------------------------|-------------------|--------------------|------------------------|------------------------|----------------------|
| 00-02 | | 989,957.00 | 20 | 100.00 | 0.00 | 100.00 |
| 06-10 | 9 | 155,391.00 | 2 | 89.00 | 1.00 | 89.94 |
| 11-15 | 13 | 1,431,049.00 | 14 | 82.50 | 3.72 | 83.71 |
| 21-25 | 22 | 261,661.00 | 10 | 62.20 | 15.94 | 61.03 |
| 31-35 | 31 | 168,599.00 | 1 | 52.00 | 0.00 | 52.00 |
| 36-40 | 37 | 95,125.00 | 5 | 58.40 | 8.75 | 52.77 |
| 41-50 | 45 | 33,080.00 | 2 | 69.50 | 11.50 | 69.77 |
| ALL | 14 | 3,134,862.00 | 54 | 82.19 | 18.20 | 84.48 |



Appendix B: Maintenance and Rehabilitation Planning Needs



Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

| Network ID | Branch ID | Section ID | Description | Severity | Distress Qty | Distress Unit | Distress Density | Policy Type | Localized Work Type | Work Qty | Work Unit | Unit Cost | Work Cost |
|------------|-----------|------------|--------------|----------|--------------|---------------|------------------|-------------|---------------------------|----------|-----------|-----------|-----------|
| OCF | RW 18-36 | 6105 | L & T CR | Medium | 360 | LF | 0.1% | Preventive | AC Crack Sealing | 360 | LF | \$ 4.00 | \$ 1,440 |
| OCF | RW 18-36 | 6105 | WEATHERING | Medium | 7,589 | SF | 2.0% | Preventive | Surface Seal | 7,589 | SF | \$ 0.75 | \$ 5,700 |
| OCF | RW 18-36 | 6110 | L & T CR | Medium | 1,285 | LF | 0.3% | Preventive | AC Crack Sealing | 1,285 | LF | \$ 4.00 | \$ 5,140 |
| OCF | RW 18-36 | 6110 | WEATHERING | Medium | 4,465 | SF | 1.2% | Preventive | Surface Seal | 4,465 | SF | \$ 0.75 | \$ 3,350 |
| OCF | RW 18-36 | 6125 | WEATHERING | Medium | 1,247 | SF | 1.3% | Preventive | Surface Seal | 1,248 | SF | \$ 0.75 | \$ 940 |
| OCF | RW 18-36 | 6135 | WEATHERING | Medium | 4,050 | SF | 2.1% | Preventive | Surface Seal | 4,051 | SF | \$ 0.75 | \$ 3,040 |
| OCF | RW 18-36 | 6190 | WEATHERING | Medium | 900 | SF | 3.0% | Preventive | Surface Seal | 900 | SF | \$ 0.75 | \$ 680 |
| OCF | RW 18-36 | 6195 | RAVELING | Low | 120 | SF | 0.2% | Preventive | Surface Seal | 120 | SF | \$ 0.75 | \$ 90 |
| OCF | RW 18-36 | 6195 | WEATHERING | Medium | 2,992 | SF | 5.0% | Preventive | Surface Seal | 2,992 | SF | \$ 0.75 | \$ 2,250 |
| OCF | TW A | 305 | WEATHERING | Medium | 741 | SF | 15.0% | Preventive | Surface Seal | 741 | SF | \$ 0.75 | \$ 560 |
| OCF | TW A13 | 596 | L & T CR | Medium | 244 | LF | 0.5% | Preventive | AC Crack Sealing | 244 | LF | \$ 4.00 | \$ 980 |
| OCF | TW A13 | 596 | WEATHERING | Medium | 1,471 | SF | 2.7% | Preventive | Surface Seal | 1,471 | SF | \$ 0.75 | \$ 1,110 |
| OCF | TW A3 | 510 | WEATHERING | Medium | 198 | SF | 5.0% | Preventive | Surface Seal | 198 | SF | \$ 0.75 | \$ 150 |
| OCF | TW A4 | 514 | RAVELING | Low | 2,759 | SF | 25.0% | Preventive | Surface Seal | 2,759 | SF | \$ 0.75 | \$ 2,070 |
| OCF | TW A8 | 565 | WEATHERING | Medium | 1,584 | SF | 10.0% | Preventive | Surface Seal | 1,585 | SF | \$ 0.75 | \$ 1,190 |
| OCF | TW A8 | 575 | RAVELING | Low | 99 | SF | 0.8% | Preventive | Surface Seal | 99 | SF | \$ 0.75 | \$ 80 |
| OCF | TW A8 | 575 | WEATHERING | Medium | 3,001 | SF | 24.8% | Preventive | Surface Seal | 3,001 | SF | \$ 0.75 | \$ 2,260 |
| OCF | TW A9 | 550 | RAVELING | Low | 53 | SF | 0.2% | Preventive | Surface Seal | 53 | SF | \$ 0.75 | \$ 40 |
| OCF | TW A9 | 550 | WEATHERING | Medium | 822 | SF | 3.0% | Preventive | Surface Seal | 822 | SF | \$ 0.75 | \$ 620 |
| OCF | TL T-HANG | 3590 | WEATHERING | Medium | 3,934 | SF | 75.0% | Preventive | Surface Seal | 3,934 | SF | \$ 0.75 | \$ 2,960 |
| OCF | TL T-HANG | 3592 | WEATHERING | Medium | 2,361 | SF | 10.0% | Preventive | Surface Seal | 2,362 | SF | \$ 0.75 | \$ 1,780 |
| OCF | AP CENTER | 4135 | RAVELING | Low | 1,705 | SF | 1.4% | Preventive | Surface Seal | 1,705 | SF | \$ 0.75 | \$ 1,280 |
| OCF | AP CENTER | 4135 | WEATHERING | Medium | 9,037 | SF | 7.3% | Preventive | Surface Seal | 9,037 | SF | \$ 0.75 | \$ 6,780 |
| OCF | AP S | 4305 | WEATHERING | Medium | 2,362 | SF | 5.0% | Preventive | Surface Seal | 2,363 | SF | \$ 0.75 | \$ 1,780 |
| OCF | TW A8 | 570 | RAVELING | High | 112 | SF | 1.6% | Stopgap | AC Partial-Depth Patching | 112 | SF | \$ 4.75 | \$ 540 |
| OCF | TL T-HANG | 3580 | ALLIGATOR CR | Medium | 132 | SF | 0.7% | Stopgap | AC Full-Depth Patching | 183 | SF | \$ 10.00 | \$ 1,830 |
| OCF | TL T-HANG | 3585 | RAVELING | High | 181 | SF | 0.2% | Stopgap | AC Partial-Depth Patching | 181 | SF | \$ 4.75 | \$ 860 |
| OCF | AP CENTER | 4150 | JT SEAL DMG | High | 15 | Slabs | 100.0% | Stopgap | PCC Joint Seal | 440 | LF | \$ 4.25 | \$ 1,870 |
| OCF | AP CENTER | 4150 | SHAT. SLAB | Medium | 1 | Slabs | 6.7% | Stopgap | PCC Crack Sealing | 40 | LF | \$ 7.00 | \$ 280 |

Table B.2: Section-Level 10-Year Major Rehabilitation Needs


| Program Year | Network ID | Branch ID | Section ID | Surface | Area (SF) | PCI Before | Rehabilitation Type | Planning Cost Estimate |
|--------------|------------|-----------|------------|---------|-----------|------------|---------------------|------------------------|
| 2023 | OCF | TW A7 | 525 | AAC | 16,153 | 56 | AC Rehabilitation | \$ 146,000 |
| 2023 | OCF | TW A8 | 570 | AC | 6,990 | 64 | AC Rehabilitation | \$ 63,000 |
| 2023 | OCF | TW AP N | 595 | AC | 33,596 | 69 | AC Rehabilitation | \$ 303,000 |
| 2023 | OCF | TW B | 105 | AC | 73,305 | 50 | AC Reconstruction | \$ 1,173,000 |
| 2023 | OCF | TW B1 | 104 | AC | 5,513 | 58 | AC Rehabilitation | \$ 50,000 |
| 2023 | OCF | TW B2 | 106 | AC | 6,834 | 51 | AC Reconstruction | \$ 110,000 |
| 2023 | OCF | TW B3 | 102 | AC | 5,513 | 54 | AC Reconstruction | \$ 73,000 |
| 2023 | OCF | TL T-HANG | 3580 | AC | 18,904 | 39 | AC Reconstruction | \$ 303,000 |
| 2023 | OCF | TL T-HANG | 3585 | AC | 76,028 | 51 | AC Reconstruction | \$ 1,217,000 |
| 2023 | OCF | AP CENTER | 4105 | AAC | 168,599 | 50 | AC Reconstruction | \$ 2,698,000 |
| 2023 | OCF | AP CENTER | 4150 | PCC | 6,000 | 32 | PCC Reconstruction | \$ 174,000 |
| 2023 | OCF | AP N | 4205 | AC | 19,584 | 68 | AC Rehabilitation | \$ 177,000 |
| 2023 | OCF | AP N | 4210 | AC | 41,762 | 54 | AC Reconstruction | \$ 669,000 |
| 2025 | OCF | TW A4 | 514 | AAC | 11,036 | 70 | AC Rehabilitation | \$ 110,000 |
| 2025 | OCF | TW A9 | 550 | AC | 27,079 | 70 | AC Rehabilitation | \$ 269,000 |
| 2026 | OCF | TW A3 | 510 | AC | 3,960 | 69 | AC Rehabilitation | \$ 42,000 |
| 2027 | OCF | AP S | 4305 | AC | 47,250 | 69 | AC Rehabilitation | \$ 517,000 |
| 2028 | OCF | TW A8 | 560 | AC | 15,868 | 69 | AC Rehabilitation | \$ 183,000 |
| 2029 | OCF | RW 18-36 | 6110 | AAC | 373,275 | 69 | AC Rehabilitation | \$ 4,503,000 |
| 2029 | OCF | TW A13 | 596 | AC | 54,138 | 70 | AC Rehabilitation | \$ 653,000 |
| 2029 | OCF | TW A8 | 575 | AAC | 12,102 | 69 | AC Rehabilitation | \$ 146,000 |
| 2029 | OCF | TL T-HANG | 3590 | AAC | 5,246 | 70 | AC Rehabilitation | \$ 64,000 |
| 2030 | OCF | RW 18-36 | 6105 | AAC | 373,275 | 68 | AC Rehabilitation | \$ 4,728,000 |
| 2030 | OCF | RW 18-36 | 6135 | AAC | 189,000 | 69 | AC Rehabilitation | \$ 2,394,000 |
| 2030 | OCF | TW A12 | 555 | AC | 33,994 | 70 | AC Rehabilitation | \$ 431,000 |
| 2030 | OCF | TW A5 | 520 | AAC | 16,927 | 69 | AC Rehabilitation | \$ 215,000 |
| 2030 | OCF | AP CENTER | 4135 | AC | 123,619 | 69 | AC Rehabilitation | \$ 1,566,000 |
| 2031 | OCF | RW 18-36 | 6125 | AAC | 94,500 | 69 | AC Rehabilitation | \$ 1,257,000 |
| 2032 | OCF | RW 18-36 | 6190 | AC | 30,000 | 69 | AC Rehabilitation | \$ 419,000 |
| 2032 | OCF | RW 18-36 | 6195 | AC | 60,000 | 69 | AC Rehabilitation | \$ 838,000 |
| 2032 | OCF | TW A8 | 565 | AC | 15,850 | 69 | AC Rehabilitation | \$ 222,000 |


**All planning cost values have been rounded up to the nearest thousand dollars.*




Appendix C: Technical Exhibits









| RECENT & ANTICIPATED CONSTRUCTION ACTIVITY | | |
|--|---|--|
| CONSTRUCTION YEAR | LOCATION | WORK TYPE / PAVEMENT SECTION |
| 2021 | AP CENTER, TW A1, TW A6 | New Construction - AC 4" SP 12.5, 10" LBR 100 Limerock |
| | TW A | New Construction - AC 4" P-401, 12" Limerock Base Course, P-152 Subgrade |
| | TW A, TW A2, TW A3, TW A4, TW A8, TW A9 | Mill and Overlay 3" Mill, Variable Depth P-401 Overlay |
| | TW A, TW A10, TW A11 | Mill and Overlay 4" Mill, Variable Depth P-401 Overlay |







| | | | | |
|--|---|---|--|---|
| TW A7:525 2023 AC REHAB \$0.15 M | TL T-HANG:3580 2023 AC RECON \$0.30 M | TL T-HANG:3585 2023 AC RECON \$1.22 M | TW A4:514 2025 AC REHAB \$0.11 M | TW A3:510 2026 AC REHAB \$0.04 M |
| TW A8:560 2028 AC REHAB \$0.18 M | TW A8:575 2029 AC REHAB \$0.15 M | TL T-HANG:3590 2029 AC REHAB \$0.06 M | TW A5:520 2030 AC REHAB \$0.22 M | AP CENTER:4135 2030 AC REHAB \$1.57 M |

LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID

PROGRAM YEAR

| | |
|------|------|
| 2023 | 2028 |
| 2024 | 2029 |
| 2025 | 2030 |
| 2026 | 2031 |
| 2027 | 2032 |

"BRANCH," "SECTION"
"YEAR," "REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



Appendix D: Inspection Photograph Documentation





RW 8-26, Section 6205, Sample Unit 104 – Longitudinal & Transverse Cracking



RW 8-26, Section 6205, Sample Unit 120 – Vicinity



RW 18-36, Section 6105, Sample Unit 333 – Longitudinal & Transverse Cracking



RW 18-36, Section 6110, Sample Unit 564 – Longitudinal & Transverse Cracking



RW 18-36, Section 6110, Sample Unit 606 – Longitudinal & Transverse Cracking



TW A5, Section 520, Sample Unit 401 – Longitudinal & Transverse Cracking



TW A9, Section 550, Sample Unit 105 – Bleeding



TW B, Section 105, Sample Unit 102 – Longitudinal & Transverse Cracking



TW B, Section 105, Sample Unit 107 – Longitudinal & Transverse Cracking



TL T-HANG, Section 3580, Sample Unit 902 – Alligator Cracking and Raveling



TW AP N, Section 595, Sample Unit 301 – Alligator Cracking and Longitudinal & Transverse Cracking



AP CENTER, Section 4105, Sample Unit 303 – Longitudinal & Transverse Cracking and Swelling



AP CENTER, Section 4105, Sample Unit 104 – Longitudinal & Transverse Cracking and Swelling



AP N, Section 4210, Sample Unit 700 – Block Cracking



Appendix E: Inspection Distress Details



Re-Inspection Report

FDOT

Generated Date 11/17/2022

Page 1 of 55

Network: OCF Name: OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD

Branch: AP CENTER Name: CENTRAL APRON Use: APRON Area: 746,206 SqFt

Section: 4105 of 10 From: - To: - Last Const.: 1/1/1991

Surface: AAC Family: CA653-GA-AP-AAC-APC Zone: Category: Rank: P

Area: 168,599 SqFt Length: 560 Ft Width: 300 Ft

Slabs: Slab Length: Ft Slab Width: Ft Joint Length: Ft

Shoulder: Street Type: Grade: 0 Lanes: 0

Section Comments:

Work Date: 1/1/1959 Work Type: BUILT Code: IMPORTED Is Major M&R: True

Work Date: 1/1/1977 Work Type: OVERLAY Code: IMPORTED Is Major M&R: True

Work Date: 1/1/1991 Work Type: OVERLAY Code: IMPORTED Is Major M&R: True

Work Date: 1/1/2004 Work Type: Surface Treatment - Seal Coat Code: ST-SC Is Major M&R: False

Last Insp. Date: 4/25/2022 TotalSamples: 36 Surveyed: 4

Conditions: PCI: 52

Inspection Comments:

Sample Number: 100 Type: R Area: 5000.00 SqFt PCI: 56

Sample Comments:

48 L & T CR L 200.00 Ft

48 L & T CR M 225.00 Ft

52 RAVELING L 500.00 SqFt

56 SWELLING L 85.00 SqFt

57 WEATHERING L 4500.00 SqFt

Sample Number: 104 Type: R Area: 5000.00 SqFt PCI: 53

Sample Comments:

48 L & T CR L 111.00 Ft

48 L & T CR M 305.00 Ft

56 SWELLING L 65.00 SqFt

57 WEATHERING L 4000.00 SqFt

57 WEATHERING M 1000.00 SqFt

Sample Number: 303 Type: R Area: 5000.00 SqFt PCI: 45

Sample Comments:

48 L & T CR L 401.00 Ft

48 L & T CR M 250.00 Ft

50 PATCHING L 63.00 SqFt

52 RAVELING M 20.00 SqFt

56 SWELLING L 139.00 SqFt

57 WEATHERING L 4425.00 SqFt

57 WEATHERING M 492.00 SqFt

Sample Number: 501 Type: R Area: 5000.00 SqFt PCI: 54

Sample Comments:

48 L & T CR L 232.00 Ft

48 L & T CR M 175.00 Ft

52 RAVELING L 400.00 SqFt

56 SWELLING L 788.00 SqFt

57 WEATHERING L 4140.00 SqFt

57 WEATHERING M 460.00 SqFt

| | | | | | | | | | |
|-----------------------------|-------------|---|---------------------|--------------------|--|----------------------|----------|--------------------------|--------------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt |
| Section: | 4110 | of | 10 | From: | - | To: | - | Last Const.: | 7/1/2021 |
| Surface: | AAC | Family: | CA653-GA-AP-AAC-APC | Zone: | | Category: | | Rank: | P |
| Area: | 81,895 SqFt | Length: | 300 Ft | Width: | 273 Ft | | | | |
| Slabs: | | Slab Length: | Ft | Slab Width: | Ft | Joint Length: | | Ft | |
| Shoulder: | | Street Type: | | Grade: | 0 | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | |
| Work Date: | 1/1/1983 | Work Type: BUILT | | | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/1991 | Work Type: OVERLAY | | | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/2004 | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | Is Major M&R: | False |
| Work Date: | 7/1/2021 | Work Type: Mill and Overlay | | | | Code: | ML-OVL | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | TotalSamples: | 17 | Surveyed: | 3 | | | | |
| Conditions: | PCI: 58 | NOTE: *** Pre-Construction PCI *** | | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 206 | Type: | R | Area: | 6900.00 SqFt | PCI: | 65 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 840.00 | SqFt | | | | | |
| 48 | L & T CR | L | 472.00 | Ft | | | | | |
| 48 | L & T CR | M | 85.00 | Ft | | | | | |
| 50 | PATCHING | L | 12.00 | SqFt | | | | | |
| 57 | WEATHERING | L | 6888.00 | SqFt | | | | | |
| Sample Number: | 307 | Type: | R | Area: | 5000.00 SqFt | PCI: | 52 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 4000.00 | SqFt | | | | | |
| 43 | BLOCK CR | M | 250.00 | SqFt | | | | | |
| 48 | L & T CR | L | 63.00 | Ft | | | | | |
| 57 | WEATHERING | L | 5000.00 | SqFt | | | | | |
| Sample Number: | 506 | Type: | R | Area: | 6900.00 SqFt | PCI: | 56 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 6210.00 | SqFt | | | | | |
| 48 | L & T CR | L | 138.00 | Ft | | | | | |
| 57 | WEATHERING | L | 6900.00 | SqFt | | | | | |

| | | | | | | | | | |
|----------------------|--------------|---------|--|---------------|--|--------------|---------------|----------|-----------------------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt |
| Section: | 4115 | of 10 | From: | - | | | To: | - | Last Const.: 7/1/2021 |
| Surface: | AAC | Family: | CA653-GA-AP-AAC-APC | | Zone: | Category: | | Rank: | P |
| Area: | 120,000 SqFt | | Length: | 400 Ft | | Width: | 300 Ft | | |
| Slabs: | Slab Length: | | Ft | Slab Width: | | Ft | Joint Length: | | Ft |
| Shoulder: | Street Type: | | Grade: | | 0 | Lanes: | | 0 | |
| Section Comments: | | | | | | | | | |
| Work Date: | 1/1/1959 | | Work Type: BUILT | | | | Code: | IMPORTED | Is Major M&R: True |
| Work Date: | 1/1/1977 | | Work Type: OVERLAY | | | | Code: | IMPORTED | Is Major M&R: True |
| Work Date: | 1/1/1991 | | Work Type: OVERLAY | | | | Code: | IMPORTED | Is Major M&R: True |
| Work Date: | 1/1/2004 | | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | Is Major M&R: False |
| Work Date: | 7/1/2021 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | Is Major M&R: True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 24 | | Surveyed: | 3 | | |
| Conditions: | PCI: 61 | | NOTE: *** Pre-Construction PCI *** | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 109 | Type: | R | Area: | | 6900.00 SqFt | PCI: | 69 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | | L | 815.00 Ft | | | | | |
| 57 | WEATHERING | | L | 6900.00 SqFt | | | | | |
| Sample Number: | 310 | Type: | R | Area: | | 5000.00 SqFt | PCI: | 50 | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | | L | 3000.00 SqFt | | | | | |
| 43 | BLOCK CR | | M | 250.00 SqFt | | | | | |
| 48 | L & T CR | | L | 72.00 Ft | | | | | |
| 48 | L & T CR | | M | 28.00 Ft | | | | | |
| 52 | RAVELING | | H | 35.00 SqFt | | | | | |
| Sample Number: | 511 | Type: | R | Area: | | 5000.00 SqFt | PCI: | 59 | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | | L | 5000.00 SqFt | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | |

| | | | | | | | | | |
|----------------------|-------------|--|---------------------|---------------|--|---------------|----------|---------------|--------------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt |
| Section: | 4120 | of | 10 | From: | - | To: | - | Last Const.: | 7/1/2021 |
| Surface: | AAC | Family: | CA653-GA-AP-AAC-APC | Zone: | | Category: | | Rank: | P |
| Area: | 95,753 SqFt | Length: | 420 Ft | Width: | 230 Ft | | | | |
| Slabs: | | Slab Length: | Ft | Slab Width: | Ft | Joint Length: | | Ft | |
| Shoulder: | | Street Type: | | Grade: | 0 | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | |
| Work Date: | 1/1/1983 | Work Type: BUILT | | | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/1991 | Work Type: OVERLAY | | | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/2004 | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | Is Major M&R: | False |
| Work Date: | 7/1/2021 | Work Type: Mill and Overlay | | | | Code: | ML-OVL | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | TotalSamples: | 18 | Surveyed: | 3 | | | | |
| Conditions: | PCI: 58 | NOTE: *** Pre-Construction PCI *** | | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 216 | Type: | R | Area: | 4100.00 SqFt | PCI: | 67 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 125.00 | SqFt | | | | | |
| 48 | L & T CR | L | 295.00 | Ft | | | | | |
| 48 | L & T CR | M | 80.00 | Ft | | | | | |
| 57 | WEATHERING | L | 1200.00 | SqFt | | | | | |
| Sample Number: | 313 | Type: | R | Area: | 6900.00 SqFt | PCI: | 56 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 5175.00 | SqFt | | | | | |
| 43 | BLOCK CR | M | 138.00 | SqFt | | | | | |
| 48 | L & T CR | L | 39.00 | Ft | | | | | |
| 57 | WEATHERING | L | 1300.00 | SqFt | | | | | |
| Sample Number: | 515 | Type: | R | Area: | 5000.00 SqFt | PCI: | 55 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 2000.00 | SqFt | | | | | |
| 48 | L & T CR | L | 200.00 | Ft | | | | | |
| 48 | L & T CR | M | 26.00 | Ft | | | | | |
| 52 | RAVELING | L | 600.00 | SqFt | | | | | |
| 57 | WEATHERING | L | 1600.00 | SqFt | | | | | |

| | | | | | | | | | |
|----------------------|-------------|------------------------------------|-------------------------------|---------------|--|---------------|----------|---------------|--------------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt |
| Section: | 4125 | of | 10 | From: | - | To: | - | Last Const.: | 7/1/2021 |
| Surface: | AAC | Family: | CA653-GA-AP-AAC-APC | Zone: | | Category: | | Rank: | P |
| Area: | 30,574 SqFt | Length: | 250 Ft | Width: | 120 Ft | | | | |
| Slabs: | | Slab Length: | Ft | Slab Width: | Ft | Joint Length: | | Ft | |
| Shoulder: | | Street Type: | | Grade: | 0 | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | |
| Work Date: | 1/1/1983 | Work Type: | BUILT | | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/2004 | Work Type: | Surface Treatment - Seal Coat | | | Code: | ST-SC | Is Major M&R: | False |
| Work Date: | 7/1/2021 | Work Type: | Mill and Overlay | | | Code: | ML-OVL | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | TotalSamples: | 6 | Surveyed: | 1 | | | | |
| Conditions: | PCI: 57 | NOTE: *** Pre-Construction PCI *** | | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 713 | Type: | R | Area: | 6093.00 SqFt | PCI: | 57 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 2742.00 | SqFt | | | | | |
| 48 | L & T CR | L | 95.00 | Ft | | | | | |
| 48 | L & T CR | M | 83.00 | Ft | | | | | |
| 57 | WEATHERING | L | 6093.00 | SqFt | | | | | |

| | | | | | | | | | |
|----------------------|-------------|--|---------------------|---------------|--|---------------|----------|---------------|--------------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt |
| Section: | 4130 | of | 10 | From: | - | To: | - | Last Const.: | 7/1/2021 |
| Surface: | AAC | Family: | CA653-GA-AP-AAC-APC | Zone: | | Category: | | Rank: | P |
| Area: | 19,665 SqFt | Length: | 96 Ft | Width: | 200 Ft | | | | |
| Slabs: | | Slab Length: | Ft | Slab Width: | Ft | Joint Length: | | Ft | |
| Shoulder: | | Street Type: | | Grade: | 0 | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | |
| Work Date: | 1/1/1985 | Work Type: BUILT | | | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/1991 | Work Type: OVERLAY | | | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/2004 | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | Is Major M&R: | False |
| Work Date: | 7/1/2021 | Work Type: Mill and Overlay | | | | Code: | ML-OVL | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | TotalSamples: | 4 | Surveyed: | 1 | | | | |
| Conditions: | PCI: 67 | NOTE: *** Pre-Construction PCI *** | | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 317 | Type: | R | Area: | 4313.00 SqFt | PCI: | 67 | | |
| Sample Comments: | | | | | | | | | |
| 43 | BLOCK CR | L | 50.00 | SqFt | | | | | |
| 48 | L & T CR | L | 412.00 | Ft | | | | | |
| 57 | WEATHERING | L | 4313.00 | SqFt | | | | | |

| | | | | | | | | | |
|----------------------|--------------|--------------|----------------------------------|---------------|--|-----------|-----------|---------------|--------------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt |
| Section: | 4135 | of | 10 | From: | - | To: | - | Last Const.: | 7/1/2009 |
| Surface: | AC | Family: | CA653-GA-AP-AC | | Zone: | | Category: | Rank: | P |
| Area: | 123,619 SqFt | | Length: | 1,642 Ft | | Width: | 60 Ft | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft |
| Shoulder: | | Street Type: | | Grade: | 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | | | |
| Work Date: | 7/1/2009 | | Work Type: New Construction - AC | | | Code: | NC-AC | | |
| Is Major M&R: | | True | | | | | | | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 27 | | Surveyed: | 5 | | |
| Conditions: | PCI: 84 | | | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 101 | Type: | R | Area: | 4500.00 SqFt | | PCI: | 81 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | L | 28.00 | Ft | | | | | |
| 56 | SWELLING | L | 114.00 | SqFt | | | | | |
| 57 | WEATHERING | L | 4275.00 | SqFt | | | | | |
| 57 | WEATHERING | M | 225.00 | SqFt | | | | | |
| Sample Number: | 109 | Type: | R | Area: | 4500.00 SqFt | | PCI: | 83 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | L | 109.00 | Ft | | | | | |
| 57 | WEATHERING | L | 4275.00 | SqFt | | | | | |
| 57 | WEATHERING | M | 225.00 | SqFt | | | | | |
| Sample Number: | 114 | Type: | R | Area: | 4500.00 SqFt | | PCI: | 87 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | L | 19.00 | Ft | | | | | |
| 57 | WEATHERING | L | 4275.00 | SqFt | | | | | |
| 57 | WEATHERING | M | 225.00 | SqFt | | | | | |
| Sample Number: | 119 | Type: | R | Area: | 4500.00 SqFt | | PCI: | 86 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | L | 27.00 | Ft | | | | | |
| 57 | WEATHERING | L | 4275.00 | SqFt | | | | | |
| 57 | WEATHERING | M | 225.00 | SqFt | | | | | |
| Sample Number: | 202 | Type: | R | Area: | 3750.00 SqFt | | PCI: | 81 | |
| Sample Comments: | | | | | | | | | |
| 52 | RAVELING | L | 300.00 | SqFt | | | | | |
| 57 | WEATHERING | L | 2760.00 | SqFt | | | | | |
| 57 | WEATHERING | M | 690.00 | SqFt | | | | | |

| | | | | | | | | | | |
|----------------------|--------------|---------|------------------------------------|---------------|--|-------------------------------|--------------|---------------|--------------|----|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt | |
| Section: | 4145 | of | 10 | From: | - | To: | - | Last Const.: | 7/1/2021 | |
| Surface: | AAC | Family: | CA653-GA-AP-AAC-APC | | Zone: | Category: | | Rank: | P | |
| Area: | 6,660 SqFt | | Length: | 90 Ft | | Width: | 72 Ft | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | |
| Work Date: | 1/1/1959 | | Work Type: | | | BUILT | | Code: | IMPORTED | |
| Work Date: | 1/1/1977 | | Work Type: | | | OVERLAY | | Code: | IMPORTED | |
| Work Date: | 1/1/1991 | | Work Type: | | | OVERLAY | | Code: | IMPORTED | |
| Work Date: | 1/1/2004 | | Work Type: | | | Surface Treatment - Seal Coat | | Code: | ST-SC | |
| Work Date: | 7/1/2021 | | Work Type: | | | Mill and Overlay | | Code: | ML-OVL | |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 2 | | Surveyed: | 1 | | | |
| Conditions: | PCI: 55 | | NOTE: *** Pre-Construction PCI *** | | | | | | | |
| Inspection Comments: | | | | | | | | | | |
| Sample Number: | 200 | | Type: | R | | Area: | 3600.00 SqFt | | PCI: | 55 |
| Sample Comments: | | | | | | | | | | |
| 43 | BLOCK CR | | L | 3420.00 SqFt | | | | | | |
| 43 | BLOCK CR | | M | 180.00 SqFt | | | | | | |
| 57 | WEATHERING | | L | 3600.00 SqFt | | | | | | |

| | | | | | | | | | | | |
|----------------------|-------------|--------------|-----------------|------------------------|--|-----------|-----------|---------------|--------------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | AP CENTER | | Name: | CENTRAL APRON | | Use: | APRON | Area: | 746,206 SqFt | | |
| Section: | 4150 | of | 10 | From: | - | To: | - | Last Const.: | 1/1/1999 | | |
| Surface: | PCC | Family: | CA653-GA-AP-PCC | | Zone: | | Category: | | Rank: | P | |
| Area: | 6,000 SqFt | | Length: | 60 Ft | | Width: | 100 Ft | | | | |
| Slabs: | 15 | Slab Length: | 20 Ft | | Slab Width: | 20 Ft | | Joint Length: | 440 Ft | | |
| Shoulder: | | Street Type: | | Grade: | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1999 | | Work Type: | New Construction - PCC | | | Code: | NC-PC | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 33 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 100 | Type: | R | Area: | 15.00 Slabs | | PCI: | 33 | | | |
| Sample Comments: | | | | | | | | | | | |
| 63 | LINEAR CR | L | 6.00 | | Slabs | | | | | | |
| 65 | JT SEAL DMG | H | 15.00 | | Slabs | | | | | | |
| 72 | SHAT. SLAB | L | 8.00 | | Slabs | | | | | | |
| 72 | SHAT. SLAB | M | 1.00 | | Slabs | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--------------|----------------|---------|--|-------------------------------|-----------|---------------|----------|---|-------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | AP N | Name: | NORTH APRON | | Use: | APRON | Area: | 61,346 SqFt | | | |
| Section: | 4205 | of | 2 | From: | - | To: | - | Last Const.: | 1/1/2000 | | |
| Surface: | AC | Family: | CA653-GA-AP-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 19,584 SqFt | Length: | 300 Ft | | Width: | 200 Ft | | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: | | | New Construction - AC | | Code: | NC-AC | | |
| Work Date: | 1/1/2004 | | Work Type: | | | Surface Treatment - Seal Coat | | Code: | ST-SC | | |
| Is Major M&R: | | | | | | | | | | | True |
| Is Major M&R: | | | | | | | | | | | False |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 4 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 70 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 504 | Type: | R | Area: | 4600.00 SqFt | | PCI: | 70 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 285.00 | Ft | | | | | | |
| 48 | L & T CR | | M | 35.00 | Ft | | | | | | |
| 49 | OIL SPILLAGE | | N | 4.00 | SqFt | | | | | | |
| 52 | RAVELING | | L | 5.00 | SqFt | | | | | | |
| 57 | WEATHERING | | L | 4595.00 | SqFt | | | | | | |

| | | | | | | | | | | | | | | |
|----------------------|-------------|--|--------------|----------------|--|-------------|--------------|-------|---------------|----|---------------|----------|---|--|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | |
| Branch: | AP N | | Name: | NORTH APRON | | Use: | APRON | Area: | 61,346 SqFt | | | | | |
| Section: | 4210 | | of | 2 | From: | - | | To: | - | | Last Const.: | 1/1/2000 | | |
| Surface: | AC | | Family: | CA653-GA-AP-AC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 41,762 SqFt | | Length: | 300 Ft | | Width: | 200 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | | Work Type: | New Construction - Initial | | | Code: | NU-IN | | Is Major M&R: | True | | |
| Work Date: | 1/1/2004 | | | Work Type: | Surface Treatment - Seal Coat | | | Code: | ST-SC | | Is Major M&R: | False | | |
| Last Insp. Date: | 4/25/2022 | | | TotalSamples: | 8 | | Surveyed: | 1 | | | | | | |
| Conditions: | PCI: | | 55 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 700 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 55 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 43 | BLOCK CR | | L | 4750.00 | | SqFt | | | | | | | | |
| 43 | BLOCK CR | | M | 250.00 | | SqFt | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 | | SqFt | | | | | | | | |

| | | | |
|----------------------------|----------------------------------|--|--------------------|
| Network: OCF | | Name: OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | |
| Branch: AP S | Name: SOUTH APRON | Use: APRON | Area: 47,250 SqFt |
| Section: 4305 | of 1 | From: - | To: - |
| Surface: AC | Family: CA653-GA-AP-AC | Zone: | Category: Rank: P |
| Area: 47,250 SqFt | Length: 350 Ft | Width: 135 Ft | |
| Slabs: | Slab Length: Ft | Slab Width: Ft | Joint Length: Ft |
| Shoulder: | Street Type: | Grade: 0 | Lanes: 0 |
| Section Comments: | | | |
| Work Date: 1/1/2010 | Work Type: New Construction - AC | Code: NC-AC | Is Major M&R: True |
| Last Insp. Date: 4/25/2022 | TotalSamples: 10 | Surveyed: 2 | |
| Conditions: PCI: 78 | | | |
| Inspection Comments: | | | |
| Sample Number: 100 | Type: R | Area: 5000.00 SqFt | PCI: 79 |
| Sample Comments: | | | |
| 48 | L & T CR | L 71.00 Ft | |
| 56 | SWELLING | L 150.00 SqFt | |
| 57 | WEATHERING | L 4750.00 SqFt | |
| 57 | WEATHERING | M 250.00 SqFt | |
| Sample Number: 202 | Type: R | Area: 5000.00 SqFt | PCI: 77 |
| Sample Comments: | | | |
| 48 | L & T CR | L 135.00 Ft | |
| 56 | SWELLING | L 225.00 SqFt | |
| 57 | WEATHERING | L 4750.00 SqFt | |
| 57 | WEATHERING | M 250.00 SqFt | |

| | | | |
|----------------------------|-----------------------------|--|-----------------------|
| Network: OCF | | Name: OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | |
| Branch: RW 18-36 | Name: RUNWAY 18-36 | Use: RUNWAY | Area: 1,120,050 SqFt |
| Section: 6105 of 6 | From: - | To: - | Last Const.: 1/1/2009 |
| Surface: AAC | Family: CA653-GA-RW-AAC-APC | Zone: Category: | Rank: P |
| Area: 373,275 SqFt | Length: 900 Ft | Width: 75 Ft | |
| Slabs: | Slab Length: Ft | Slab Width: Ft | Joint Length: Ft |
| Shoulder: | Street Type: | Grade: 0 | Lanes: 0 |
| Section Comments: | | | |
| Work Date: 1/1/1959 | Work Type: BUILT | Code: IMPORTED | Is Major M&R: True |
| Work Date: 1/1/1991 | Work Type: OVERLAY | Code: IMPORTED | Is Major M&R: True |
| Work Date: 1/1/2009 | Work Type: Mill and Overlay | Code: ML-OVL | Is Major M&R: True |
| Last Insp. Date: 4/25/2022 | TotalSamples: 99 | Surveyed: 20 | |
| Conditions: PCI: 84 | Inspection Comments: | | |
| Sample Number: 325 | Type: R | Area: 4500.00 SqFt | PCI: 79 |
| Sample Comments: | | | |
| 48 L & T CR | L | 88.00 Ft | |
| 48 L & T CR | M | 27.00 Ft | |
| 56 SWELLING | L | 18.00 SqFt | |
| 57 WEATHERING | L | 4500.00 SqFt | |
| Sample Number: 329 | Type: R | Area: 3750.00 SqFt | PCI: 76 |
| Sample Comments: | | | |
| 48 L & T CR | L | 97.00 Ft | |
| 48 L & T CR | M | 25.00 Ft | |
| 56 SWELLING | L | 6.00 SqFt | |
| 57 WEATHERING | L | 3562.00 SqFt | |
| 57 WEATHERING | M | 188.00 SqFt | |
| Sample Number: 333 | Type: R | Area: 3750.00 SqFt | PCI: 59 |
| Sample Comments: | | | |
| 48 L & T CR | L | 64.00 Ft | |
| 48 L & T CR | M | 21.00 Ft | |
| 50 PATCHING | L | 900.00 SqFt | |
| 56 SWELLING | L | 60.00 SqFt | |
| 57 WEATHERING | L | 2850.00 SqFt | |
| Sample Number: 336 | Type: R | Area: 3750.00 SqFt | PCI: 73 |
| Sample Comments: | | | |
| 48 L & T CR | L | 96.00 Ft | |
| 50 PATCHING | L | 384.00 SqFt | |
| 56 SWELLING | L | 18.00 SqFt | |
| 57 WEATHERING | L | 3366.00 SqFt | |
| Sample Number: 353 | Type: R | Area: 3750.00 SqFt | PCI: 84 |
| Sample Comments: | | | |
| 48 L & T CR | L | 47.00 Ft | |
| 56 SWELLING | L | 20.00 SqFt | |
| 57 WEATHERING | L | 3590.00 SqFt | |
| 57 WEATHERING | M | 160.00 SqFt | |
| Sample Number: 358 | Type: R | Area: 3750.00 SqFt | PCI: 85 |
| Sample Comments: | | | |
| 48 L & T CR | L | 51.00 Ft | |
| 56 SWELLING | L | 24.00 SqFt | |
| 57 WEATHERING | L | 3682.00 SqFt | |
| 57 WEATHERING | M | 68.00 SqFt | |

| | | | | | | | | |
|--------------------|------------|-------|---|---------|------|--------------|------|----|
| Sample Number: 362 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 83 |
| Sample Comments: | | | | | | | | |
| 42 | BLEEDING | | N | 2.00 | SqFt | | | |
| 48 | L & T CR | | L | 103.00 | Ft | | | |
| 57 | WEATHERING | | L | 3658.00 | SqFt | | | |
| 57 | WEATHERING | | M | 92.00 | SqFt | | | |
| Sample Number: 365 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 87 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 55.00 | Ft | | | |
| 56 | SWELLING | | L | 10.00 | SqFt | | | |
| 57 | WEATHERING | | L | 3750.00 | SqFt | | | |
| Sample Number: 371 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 89 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 5.00 | Ft | | | |
| 57 | WEATHERING | | L | 3670.00 | SqFt | | | |
| 57 | WEATHERING | | M | 80.00 | SqFt | | | |
| Sample Number: 377 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 87 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 82.00 | Ft | | | |
| 57 | WEATHERING | | L | 3750.00 | SqFt | | | |
| Sample Number: 382 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 89 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 10.00 | Ft | | | |
| 57 | WEATHERING | | L | 3720.00 | SqFt | | | |
| 57 | WEATHERING | | M | 30.00 | SqFt | | | |
| Sample Number: 390 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 88 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 64.00 | Ft | | | |
| 57 | WEATHERING | | L | 3750.00 | SqFt | | | |
| Sample Number: 395 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 91 |
| Sample Comments: | | | | | | | | |
| 57 | WEATHERING | | L | 3646.00 | SqFt | | | |
| 57 | WEATHERING | | M | 104.00 | SqFt | | | |
| Sample Number: 399 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 88 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 2.00 | Ft | | | |
| 57 | WEATHERING | | L | 3510.00 | SqFt | | | |
| 57 | WEATHERING | | M | 240.00 | SqFt | | | |
| Sample Number: 402 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 87 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 36.00 | Ft | | | |
| 57 | WEATHERING | | L | 3718.00 | SqFt | | | |
| 57 | WEATHERING | | M | 32.00 | SqFt | | | |
| Sample Number: 408 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 80 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 151.00 | Ft | | | |
| 57 | WEATHERING | | L | 3654.00 | SqFt | | | |
| 57 | WEATHERING | | M | 96.00 | SqFt | | | |
| Sample Number: 413 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 89 |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 52.00 | Ft | | | |
| 57 | WEATHERING | | L | 3750.00 | SqFt | | | |
| Sample Number: 415 | | Type: | R | Area: | | 3750.00 SqFt | PCI: | 87 |
| Sample Comments: | | | | | | | | |

| | | | | |
|----|------------|---|---------|------|
| 48 | L & T CR | L | 44.00 | Ft |
| 57 | WEATHERING | L | 3675.00 | SqFt |
| 57 | WEATHERING | M | 75.00 | SqFt |

| | | | | | | | |
|-----------------------|-----|--------------|---|--------------|--------------|-------------|----|
| Sample Number: | 418 | Type: | R | Area: | 3750.00 SqFt | PCI: | 91 |
|-----------------------|-----|--------------|---|--------------|--------------|-------------|----|

Sample Comments:

| | | | | |
|----|------------|---|---------|------|
| 48 | L & T CR | L | 6.00 | Ft |
| 57 | WEATHERING | L | 3750.00 | SqFt |

| | | | | | | | |
|-----------------------|-----|--------------|---|--------------|--------------|-------------|----|
| Sample Number: | 422 | Type: | R | Area: | 3750.00 SqFt | PCI: | 84 |
|-----------------------|-----|--------------|---|--------------|--------------|-------------|----|

Sample Comments:

| | | | | |
|----|------------|---|---------|------|
| 48 | L & T CR | L | 38.00 | Ft |
| 57 | WEATHERING | L | 3375.00 | SqFt |
| 57 | WEATHERING | M | 375.00 | SqFt |

| | | | | |
|----------------------------|--|--|----------------------|-----------------------|
| Network: OCF | | Name: OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | |
| Branch: RW 18-36 | Name: RUNWAY 18-36 | Use: RUNWAY | Area: 1,120,050 SqFt | |
| Section: 6110 | of 6 | From: - | To: - | Last Const.: 1/1/2009 |
| Surface: AAC | Family: CA653-GA-RW-AAC-APC | Zone: | Category: | Rank: P |
| Area: 373,275 SqFt | Length: 1,000 Ft | Width: 38 Ft | | |
| Slabs: | Slab Length: Ft | Slab Width: Ft | Joint Length: Ft | |
| Shoulder: | Street Type: | Grade: 0 | Lanes: 0 | |
| Section Comments: | | | | |
| Work Date: 1/1/1959 | Work Type: BUILT | | Code: IMPORTED | Is Major M&R: True |
| Work Date: 1/1/1977 | Work Type: OVERLAY | | Code: IMPORTED | Is Major M&R: True |
| Work Date: 1/1/1991 | Work Type: Surface Treatment - Seal Coat | | Code: ST-SC | Is Major M&R: False |
| Work Date: 1/1/2009 | Work Type: Mill and Overlay | | Code: ML-OVL | Is Major M&R: True |
| Last Insp. Date: 4/25/2022 | TotalSamples: 100 | Surveyed: 21 | | |
| Conditions: PCI: 83 | | | | |
| Inspection Comments: | | | | |
| Sample Number: 130 | Type: R | Area: 3750.00 SqFt | PCI: 89 | |
| Sample Comments: | | | | |
| 48 L & T CR | L | 31.00 Ft | | |
| 57 WEATHERING | L | 3750.00 SqFt | | |
| Sample Number: 138 | Type: R | Area: 3750.00 SqFt | PCI: 69 | |
| Sample Comments: | | | | |
| 48 L & T CR | L | 47.00 Ft | | |
| 48 L & T CR | M | 88.00 Ft | | |
| 57 WEATHERING | L | 3450.00 SqFt | | |
| 57 WEATHERING | M | 300.00 SqFt | | |
| Sample Number: 150 | Type: R | Area: 3750.00 SqFt | PCI: 89 | |
| Sample Comments: | | | | |
| 48 L & T CR | L | 8.00 Ft | | |
| 56 SWELLING | L | 8.00 SqFt | | |
| 57 WEATHERING | L | 3750.00 SqFt | | |
| Sample Number: 158 | Type: R | Area: 3750.00 SqFt | PCI: 87 | |
| Sample Comments: | | | | |
| 48 L & T CR | L | 150.00 Ft | | |
| Sample Number: 168 | Type: R | Area: 3750.00 SqFt | PCI: 86 | |
| Sample Comments: | | | | |
| 48 L & T CR | L | 74.00 Ft | | |
| 56 SWELLING | L | 10.00 SqFt | | |
| 57 WEATHERING | L | 3750.00 SqFt | | |
| Sample Number: 176 | Type: R | Area: 3750.00 SqFt | PCI: 87 | |
| Sample Comments: | | | | |
| 42 BLEEDING | N | 5.00 SqFt | | |
| 48 L & T CR | L | 82.00 Ft | | |
| 57 WEATHERING | L | 3750.00 SqFt | | |
| Sample Number: 184 | Type: R | Area: 3750.00 SqFt | PCI: 87 | |
| Sample Comments: | | | | |
| 42 BLEEDING | N | 3.00 SqFt | | |
| 48 L & T CR | L | 80.00 Ft | | |
| 57 WEATHERING | L | 3750.00 SqFt | | |
| Sample Number: 198 | Type: R | Area: 3750.00 SqFt | PCI: 82 | |
| Sample Comments: | | | | |

| | | | | |
|---|------------|---|---------|------|
| 48 | L & T CR | L | 160.00 | Ft |
| 57 | WEATHERING | L | 3750.00 | SqFt |
| Sample Number: 210 Type: R Area: 3750.00 SqFt PCI: 81 | | | | |
| Sample Comments: | | | | |
| 48 | L & T CR | L | 112.00 | Ft |
| 56 | SWELLING | L | 2.00 | SqFt |
| 57 | WEATHERING | L | 3570.00 | SqFt |
| 57 | WEATHERING | M | 180.00 | SqFt |
| Sample Number: 218 Type: R Area: 3750.00 SqFt PCI: 87 | | | | |
| Sample Comments: | | | | |
| 48 | L & T CR | L | 13.00 | Ft |
| 57 | WEATHERING | L | 3540.00 | SqFt |
| 57 | WEATHERING | M | 210.00 | SqFt |
| Sample Number: 534 Type: R Area: 3750.00 SqFt PCI: 66 | | | | |
| Sample Comments: | | | | |
| 48 | L & T CR | L | 60.00 | Ft |
| 48 | L & T CR | M | 38.00 | Ft |
| 50 | PATCHING | L | 629.00 | SqFt |
| 57 | WEATHERING | L | 3121.00 | SqFt |
| Sample Number: 540 Type: R Area: 3750.00 SqFt PCI: 77 | | | | |
| Sample Comments: | | | | |
| 48 | L & T CR | L | 157.00 | Ft |
| 48 | L & T CR | M | 55.00 | Ft |
| 57 | WEATHERING | L | 3750.00 | SqFt |
| Sample Number: 546 Type: R Area: 3750.00 SqFt PCI: 80 | | | | |
| Sample Comments: | | | | |
| 48 | L & T CR | L | 86.00 | Ft |
| 48 | L & T CR | M | 5.00 | Ft |
| 57 | WEATHERING | L | 3648.00 | SqFt |
| 57 | WEATHERING | M | 102.00 | SqFt |
| Sample Number: 556 Type: R Area: 3750.00 SqFt PCI: 81 | | | | |
| Sample Comments: | | | | |
| 48 | L & T CR | L | 141.00 | Ft |
| 56 | SWELLING | L | 15.00 | SqFt |
| 57 | WEATHERING | L | 3750.00 | SqFt |
| Sample Number: 564 Type: R Area: 3750.00 SqFt PCI: 72 | | | | |
| Sample Comments: | | | | |
| 42 | BLEEDING | N | 4.00 | SqFt |
| 48 | L & T CR | L | 192.00 | Ft |
| 48 | L & T CR | M | 50.00 | Ft |
| 56 | SWELLING | L | 40.00 | SqFt |
| 57 | WEATHERING | L | 3750.00 | SqFt |
| Sample Number: 572 Type: R Area: 3750.00 SqFt PCI: 77 | | | | |
| Sample Comments: | | | | |
| 42 | BLEEDING | N | 4.00 | SqFt |
| 48 | L & T CR | L | 103.00 | Ft |
| 48 | L & T CR | M | 35.00 | Ft |
| 56 | SWELLING | L | 20.00 | SqFt |
| 57 | WEATHERING | L | 3750.00 | SqFt |
| Sample Number: 580 Type: R Area: 3750.00 SqFt PCI: 83 | | | | |
| Sample Comments: | | | | |
| 48 | L & T CR | L | 141.00 | Ft |
| 57 | WEATHERING | L | 3750.00 | SqFt |
| Sample Number: 594 Type: R Area: 3750.00 SqFt PCI: 94 | | | | |
| Sample Comments: | | | | |
| 57 | WEATHERING | L | 3750.00 | SqFt |

| | | | | | | | | |
|--------------------|------------|-------|---|---------|------|--------------|---------|--|
| Sample Number: 600 | | Type: | R | Area: | | 3750.00 SqFt | PCI: 85 | |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 64.00 | Ft | | | |
| 57 | WEATHERING | | L | 3600.00 | SqFt | | | |
| 57 | WEATHERING | | M | 150.00 | SqFt | | | |
| Sample Number: 606 | | Type: | R | Area: | | 3750.00 SqFt | PCI: 89 | |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 41.00 | Ft | | | |
| 57 | WEATHERING | | L | 3750.00 | SqFt | | | |
| Sample Number: 614 | | Type: | R | Area: | | 3750.00 SqFt | PCI: 87 | |
| Sample Comments: | | | | | | | | |
| 48 | L & T CR | | L | 85.00 | Ft | | | |
| 57 | WEATHERING | | L | 3750.00 | SqFt | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|-----------------------------|--------------|--|--------------|---------------|----------|----------------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | RW 18-36 | | Name: | RUNWAY 18-36 | | Use: | RUNWAY | Area: | 1,120,050 SqFt | | |
| Section: | 6125 of 6 | | From: | - | | To: | - | | Last Const.: | 1/1/2009 | |
| Surface: | AAC | Family: | CA653-GA-RW-AAC-APC | | Zone: | Category: | | Rank: | P | | |
| Area: | 94,500 SqFt | | Length: | 2,640 Ft | | Width: | 50 Ft | | | | |
| Slabs: | Slab Length: | | Ft | Slab Width: | | Ft | Joint Length: | | Ft | | |
| Shoulder: | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1988 | | Work Type: BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True |
| Work Date: | 1/1/2009 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 19 | | Surveyed: 5 | | | | | |
| Conditions: | PCI: 87 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 309 | | Type: | R | Area: | 5000.00 SqFt | | PCI: | 88 | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 32.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 4970.00 SqFt | | | | | | | |
| 57 | WEATHERING | | M | 30.00 SqFt | | | | | | | |
| Sample Number: | 312 | | Type: | R | Area: | 5000.00 SqFt | | PCI: | 89 | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 16.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 4950.00 SqFt | | | | | | | |
| 57 | WEATHERING | | M | 50.00 SqFt | | | | | | | |
| Sample Number: | 315 | | Type: | R | Area: | 5000.00 SqFt | | PCI: | 89 | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 67.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | |
| Sample Number: | 319 | | Type: | R | Area: | 5000.00 SqFt | | PCI: | 88 | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 77.00 Ft | | | | | | | |
| 56 | SWELLING | | L | 6.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | |
| Sample Number: | 323 | | Type: | R | Area: | 5000.00 SqFt | | PCI: | 82 | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 132.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 4750.00 SqFt | | | | | | | |
| 57 | WEATHERING | | M | 250.00 SqFt | | | | | | | |

| | | | | | | | | | | | | | | | | | | | |
|----------------------|--|--------------|--|---------------|--|--|--|-------------|--|--------------|--|---------------|--|----------------|--|--------------|--|----------|--|
| Network: | | OCF | | Name: | | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | | | | | |
| Branch: | | RW 18-36 | | Name: | | RUNWAY 18-36 | | Use: | | RUNWAY | | Area: | | 1,120,050 SqFt | | | | | |
| Section: | | 6135 | | of | | 6 | | From: | | - | | To: | | - | | Last Const.: | | 1/1/2009 | |
| Surface: | | AAC | | Family: | | CA653-GA-RW-AAC-APC | | Zone: | | | | Category: | | | | Rank: | | P | |
| Area: | | 189,000 SqFt | | Length: | | 3,000 Ft | | Width: | | 25 Ft | | | | | | | | | |
| Slabs: | | | | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | | Ft | | | | | |
| Shoulder: | | | | Street Type: | | | | Grade: | | 0 | | Lanes: | | 0 | | | | | |
| Section Comments: | | | | | | | | | | | | | | | | | | | |
| Work Date: | | 1/1/1988 | | Work Type: | | BUILT | | Code: | | IMPORTED | | Is Major M&R: | | True | | | | | |
| Work Date: | | 1/1/2009 | | Work Type: | | Mill and Overlay | | Code: | | ML-OVL | | Is Major M&R: | | True | | | | | |
| Last Insp. Date: | | 4/25/2022 | | TotalSamples: | | 38 | | Surveyed: | | 7 | | | | | | | | | |
| Conditions: | | PCI: | | 85 | | | | | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | | | | | | |
| Sample Number: | | 106 | | Type: | | R | | Area: | | 5000.00 SqFt | | PCI: | | 87 | | | | | |
| Sample Comments: | | | | | | | | | | | | | | | | | | | |
| 48 | | L & T CR | | L | | 57.00 Ft | | | | | | | | | | | | | |
| 57 | | WEATHERING | | L | | 4900.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | M | | 100.00 SqFt | | | | | | | | | | | | | |
| Sample Number: | | 115 | | Type: | | R | | Area: | | 5000.00 SqFt | | PCI: | | 87 | | | | | |
| Sample Comments: | | | | | | | | | | | | | | | | | | | |
| 48 | | L & T CR | | L | | 56.00 Ft | | | | | | | | | | | | | |
| 56 | | SWELLING | | L | | 25.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | L | | 5000.00 SqFt | | | | | | | | | | | | | |
| Sample Number: | | 117 | | Type: | | R | | Area: | | 5000.00 SqFt | | PCI: | | 84 | | | | | |
| Sample Comments: | | | | | | | | | | | | | | | | | | | |
| 48 | | L & T CR | | L | | 53.00 Ft | | | | | | | | | | | | | |
| 56 | | SWELLING | | L | | 25.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | L | | 4800.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | M | | 200.00 SqFt | | | | | | | | | | | | | |
| Sample Number: | | 123 | | Type: | | R | | Area: | | 5000.00 SqFt | | PCI: | | 83 | | | | | |
| Sample Comments: | | | | | | | | | | | | | | | | | | | |
| 48 | | L & T CR | | L | | 130.00 Ft | | | | | | | | | | | | | |
| 56 | | SWELLING | | L | | 45.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | L | | 5000.00 SqFt | | | | | | | | | | | | | |
| Sample Number: | | 507 | | Type: | | R | | Area: | | 5000.00 SqFt | | PCI: | | 80 | | | | | |
| Sample Comments: | | | | | | | | | | | | | | | | | | | |
| 48 | | L & T CR | | L | | 123.00 Ft | | | | | | | | | | | | | |
| 56 | | SWELLING | | L | | 55.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | L | | 4750.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | M | | 250.00 SqFt | | | | | | | | | | | | | |
| Sample Number: | | 515 | | Type: | | R | | Area: | | 5000.00 SqFt | | PCI: | | 89 | | | | | |
| Sample Comments: | | | | | | | | | | | | | | | | | | | |
| 48 | | L & T CR | | L | | 81.00 Ft | | | | | | | | | | | | | |
| 57 | | WEATHERING | | L | | 5000.00 SqFt | | | | | | | | | | | | | |
| Sample Number: | | 517 | | Type: | | R | | Area: | | 5000.00 SqFt | | PCI: | | 85 | | | | | |
| Sample Comments: | | | | | | | | | | | | | | | | | | | |
| 48 | | L & T CR | | L | | 84.00 Ft | | | | | | | | | | | | | |
| 57 | | WEATHERING | | L | | 4800.00 SqFt | | | | | | | | | | | | | |
| 57 | | WEATHERING | | M | | 200.00 SqFt | | | | | | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|-------------|--------------|----------------|-----------------------|--|-----------|-----------|---------------|----------------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | RW 18-36 | | Name: | RUNWAY 18-36 | | Use: | RUNWAY | Area: | 1,120,050 SqFt | | |
| Section: | 6190 | of | 6 | From: | - | To: | - | Last Const.: | 1/1/2008 | | |
| Surface: | AC | Family: | CA653-GA-RW-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 30,000 SqFt | | Length: | 595 Ft | | Width: | 150 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | Grade: | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2008 | | Work Type: | New Construction - AC | | | Code: | NC-AC | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 6 | | Surveyed: | 2 | | | | |
| Conditions: | PCI: | 86 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 302 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 81 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | L | 154.00 Ft | | | | | | | | |
| 57 | WEATHERING | L | 4750.00 SqFt | | | | | | | | |
| 57 | WEATHERING | M | 250.00 SqFt | | | | | | | | |
| Sample Number: | 305 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 90 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | L | 6.00 Ft | | | | | | | | |
| 57 | WEATHERING | L | 4950.00 SqFt | | | | | | | | |
| 57 | WEATHERING | M | 50.00 SqFt | | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|-------------|--|--------------|----------------|--|-------------|--------------|-----------|----------------|----------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | RW 18-36 | | Name: | RUNWAY 18-36 | | Use: | RUNWAY | Area: | 1,120,050 SqFt | | | |
| Section: | 6195 of 6 | | From: | - | | To: | - | | Last Const.: | 1/1/2008 | | |
| Surface: | AC | | Family: | CA653-GA-RW-AC | | Zone: | | | Category: | Rank: P | | |
| Area: | 60,000 SqFt | | Length: | 595 Ft | | Width: | 150 Ft | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 1/1/2008 | | | Work Type: | New Construction - Initial | | | Code: | NU-IN | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | | TotalSamples: | 12 | | | Surveyed: | 3 | | | |
| Conditions: | PCI: 86 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 101 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 83 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 90.00 Ft | | | | | | | | |
| 52 | RAVELING | | L | 30.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | L | 4722.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | M | 248.00 SqFt | | | | | | | | |
| Sample Number: | 503 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 88 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 7.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 4750.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | M | 250.00 SqFt | | | | | | | | |
| Sample Number: | 505 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 88 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 2.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 4750.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | M | 250.00 SqFt | | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|--------------|---------|---------------------|--------------|--|-----------|-------------------------|---------------|--------------|----------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | RW 8-26 | | Name: | RUNWAY 8-26 | | Use: | RUNWAY | Area: | 150,450 SqFt | | | |
| Section: | 6205 of 1 | | From: | - | | To: | - | | Last Const.: | 1/1/2013 | | |
| Surface: | AAC | Family: | CA653-GA-RW-AAC-APC | | Zone: | Category: | | Rank: | S | | | |
| Area: | 150,450 SqFt | | Length: | 3,010 Ft | | Width: | 50 Ft | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 1/1/1973 | | Work Type: | | | | BUILT | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/2002 | | Work Type: | | | | Overlay - AC Structural | | Code: | OL-AS | Is Major M&R: | True |
| Work Date: | 1/1/2013 | | Work Type: | | | | Mill and Overlay | | Code: | ML-OVL | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 30 | | Surveyed: | 6 | | | | | |
| Conditions: | PCI: 90 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 102 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 92 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 4.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 104 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 89 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 71.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 112 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 89 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 51.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 116 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 92 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 6.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 120 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 89 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 75.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |
| Sample Number: | 128 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 89 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 47.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 5000.00 SqFt | | | | | | | | |

| | | | | | | | | | | | | | | |
|----------------------|--------------|--|---------------|-------------------------------|--|-------------|--------------|-------|---------------|----|---------------|----------|---|--|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | |
| Branch: | TL T-HANG | | Name: | T-HANGAR TAXILANE | | Use: | TAXILANE | Area: | 123,792 SqFt | | | | | |
| Section: | 3580 | | of | 4 | From: | - | | To: | - | | Last Const.: | 1/1/2000 | | |
| Surface: | AC | | Family: | CA653-GA-TW-AC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 18,904 SqFt | | Length: | 880 Ft | | Width: | 30 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | | | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: | New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True | | |
| Work Date: | 1/1/2004 | | Work Type: | Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: | False | | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 4 | | Surveyed: | 1 | | | | | | | |
| Conditions: | PCI: 40 | | | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 902 | | Type: | R | | Area: | 4000.00 SqFt | | PCI: | 40 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | L | 102.00 | | SqFt | | | | | | | | |
| 41 | ALLIGATOR CR | | M | 28.00 | | SqFt | | | | | | | | |
| 48 | L & T CR | | L | 142.00 | | Ft | | | | | | | | |
| 52 | RAVELING | | L | 3875.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 125.00 | | SqFt | | | | | | | | |
| 54 | SHOVING | | L | 20.00 | | SqFt | | | | | | | | |

| | | | | | | | | | | |
|----------------------|-------------|--------------|--|-------------------|--|-----------|-----------|---------------|---------------|-------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | |
| Branch: | TL T-HANG | | Name: | T-HANGAR TAXILANE | | Use: | TAXILANE | Area: | 123,792 SqFt | |
| Section: | 3585 | of | 4 | From: | - | To: | - | Last Const.: | 1/1/2000 | |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: | P |
| Area: | 76,028 SqFt | Length: | 3,300 Ft | | Width: | 23 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | |
| Shoulder: | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: New Construction - AC | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: Surface Treatment - Seal Coat | | | Code: | ST-SC | | Is Major M&R: | False |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 16 | | Surveyed: | 4 | | | |
| Conditions: | PCI: | 52 | | | | | | | | |
| Inspection Comments: | | | | | | | | | | |
| Sample Number: | 151 | Type: | R | Area: | 5238.00 SqFt | | PCI: | 54 | | |
| Sample Comments: | | | | | | | | | | |
| 48 | L & T CR | L | 400.00 | Ft | | | | | | |
| 48 | L & T CR | M | 45.00 | Ft | | | | | | |
| 52 | RAVELING | L | 4714.00 | SqFt | | | | | | |
| 52 | RAVELING | M | 524.00 | SqFt | | | | | | |
| 54 | SHOVING | L | 13.00 | SqFt | | | | | | |
| Sample Number: | 201 | Type: | R | Area: | 5936.00 SqFt | | PCI: | 55 | | |
| Sample Comments: | | | | | | | | | | |
| 48 | L & T CR | L | 310.00 | Ft | | | | | | |
| 52 | RAVELING | L | 5295.00 | SqFt | | | | | | |
| 52 | RAVELING | M | 589.00 | SqFt | | | | | | |
| 52 | RAVELING | H | 52.00 | SqFt | | | | | | |
| 54 | SHOVING | L | 65.00 | SqFt | | | | | | |
| Sample Number: | 300 | Type: | R | Area: | 5332.00 SqFt | | PCI: | 46 | | |
| Sample Comments: | | | | | | | | | | |
| 45 | DEPRESSION | L | 2.00 | SqFt | | | | | | |
| 48 | L & T CR | L | 176.00 | Ft | | | | | | |
| 52 | RAVELING | L | 2832.00 | SqFt | | | | | | |
| 52 | RAVELING | M | 2500.00 | SqFt | | | | | | |
| 54 | SHOVING | L | 13.00 | SqFt | | | | | | |
| Sample Number: | 450 | Type: | R | Area: | 5379.00 SqFt | | PCI: | 55 | | |
| Sample Comments: | | | | | | | | | | |
| 48 | L & T CR | L | 290.00 | Ft | | | | | | |
| 48 | L & T CR | M | 15.00 | Ft | | | | | | |
| 50 | PATCHING | L | 410.00 | SqFt | | | | | | |
| 52 | RAVELING | L | 3727.00 | SqFt | | | | | | |
| 54 | SHOVING | L | 8.00 | SqFt | | | | | | |
| 57 | WEATHERING | M | 1242.00 | SqFt | | | | | | |

| | | | | | | | | | | | | | | |
|----------------------|------------|--|---------------|-------------------------------|--|-------------|--------------|-------|---------------|--------------|---------------|--------------|----------|--|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | |
| Branch: | TL T-HANG | | Name: | T-HANGAR TAXILANE | | Use: | TAXILANE | | Area: | 123,792 SqFt | | | | |
| Section: | 3590 | | of | 4 | | From: | - | | To: | - | | Last Const.: | 1/1/2009 | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 5,246 SqFt | | Length: | 105 Ft | | Width: | 40 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | | | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/1977 | | Work Type: | New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True | | |
| Work Date: | 1/1/2004 | | Work Type: | Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: | False | | |
| Work Date: | 1/1/2009 | | Work Type: | Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True | | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | | | | |
| Conditions: | PCI: 80 | | | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 203 | | Type: | R | | Area: | 5246.00 SqFt | | PCI: | 80 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 1312.00 SqFt | | | | | | | | | | |
| 57 | WEATHERING | | M | 3934.00 SqFt | | | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|-------------|--------------|----------------|--|--------------|-----------|-----------|---------------|--------------|---------------|------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TL T-HANG | | Name: | T-HANGAR TAXILANE | | Use: | TAXILANE | Area: | 123,792 SqFt | | |
| Section: | 3592 | of | 4 | From: | - | To: | - | Last Const.: | 1/1/2009 | | |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 23,614 SqFt | | Length: | 965 Ft | | Width: | 25 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2009 | | Work Type: | New Construction - AC | | | Code: | NC-AC | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 5 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 87 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 102 | Type: | R | Area: | 4800.00 SqFt | | PCI: | 87 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | L | 2.00 Ft | | | | | | | | |
| 57 | WEATHERING | L | 4320.00 SqFt | | | | | | | | |
| 57 | WEATHERING | M | 480.00 SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--|------------------------------------|---------------------|--|-----------|--------------|---------------|--------------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A | | Name: | TAXIWAY A | | Use: | TAXIWAY | Area: | 366,333 SqFt | | |
| Section: | 304 of 5 | | From: | - | | | To: | - | | | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: P | | |
| Area: | 11,360 SqFt | | Length: | 430 Ft | | Width: | 25 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1973 | | Work Type: BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True |
| Work Date: | 1/1/2013 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True |
| Work Date: | 7/1/2021 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 3 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 92 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 100 | | Type: | R | | Area: | 4994.00 SqFt | | PCI: | 92 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 1.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 4994.00 SqFt | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|------------|--|---------------|---------------------|--|-------------|--------------|-------|---------------|---------|---------------|----------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A | | Name: | TAXIWAY A | | Use: | TAXIWAY | Area: | 366,333 SqFt | | | |
| Section: | 305 | | of | 5 | From: | - | | To: | - | | Last Const.: | 1/1/2013 |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | | | Category: | Rank: P | | |
| Area: | 4,941 SqFt | | Length: | 25 Ft | | Width: | 175 Ft | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 1/1/1973 | | Work Type: | BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True |
| Work Date: | 1/1/2013 | | Work Type: | Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | | |
| Conditions: | PCI: 88 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 102 | | Type: | R | | Area: | 4941.00 SqFt | | PCI: | 88 | | |
| Sample Comments: | | | | | | | | | | | | |
| 57 | WEATHERING | | L | 4200.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | M | 741.00 SqFt | | | | | | | | |

| | | | | | | | | | | |
|----------------------|--------------|-----|------------------------------------|---------------------|-------|--|--------------|----------|---------------|--------------------|
| Network: | | OCF | | Name: | | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | TW A | | Name: | TAXIWAY A | | Use: | TAXIWAY | Area: | 366,333 SqFt | |
| Section: | 505 | | of | 5 | From: | - | | To: | - | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | | | Category: | Rank: P |
| Area: | 210,730 SqFt | | Length: | 4,895 Ft | | Width: | 50 Ft | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 |
| Section Comments: | | | | | | | | | | |
| Work Date: | 1/1/1959 | | Work Type: BUILT | | | | Code: | IMPORTED | | Is Major M&R: True |
| Work Date: | 1/1/1977 | | Work Type: OVERLAY | | | | Code: | IMPORTED | | Is Major M&R: True |
| Work Date: | 7/1/2021 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 45 | | Surveyed: | 5 | | | |
| Conditions: | PCI: 37 | | NOTE: *** Pre-Construction PCI *** | | | | | | | |
| Inspection Comments: | | | | | | | | | | |
| Sample Number: | 127 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 25 |
| Sample Comments: | | | | | | | | | | |
| 43 | BLOCK CR | | L | 1000.00 SqFt | | | | | | |
| 43 | BLOCK CR | | M | 312.00 SqFt | | | | | | |
| 48 | L & T CR | | L | 34.00 Ft | | | | | | |
| 48 | L & T CR | | M | 428.00 Ft | | | | | | |
| 52 | RAVELING | | L | 4500.00 SqFt | | | | | | |
| 52 | RAVELING | | H | 500.00 SqFt | | | | | | |
| Sample Number: | 137 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 44 |
| Sample Comments: | | | | | | | | | | |
| 43 | BLOCK CR | | L | 2000.00 SqFt | | | | | | |
| 43 | BLOCK CR | | M | 500.00 SqFt | | | | | | |
| 48 | L & T CR | | L | 160.00 Ft | | | | | | |
| 52 | RAVELING | | L | 4500.00 SqFt | | | | | | |
| 52 | RAVELING | | M | 500.00 SqFt | | | | | | |
| Sample Number: | 147 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 40 |
| Sample Comments: | | | | | | | | | | |
| 43 | BLOCK CR | | L | 750.00 SqFt | | | | | | |
| 48 | L & T CR | | L | 181.00 Ft | | | | | | |
| 48 | L & T CR | | M | 389.00 Ft | | | | | | |
| 52 | RAVELING | | L | 4000.00 SqFt | | | | | | |
| 52 | RAVELING | | M | 1000.00 SqFt | | | | | | |
| Sample Number: | 158 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 43 |
| Sample Comments: | | | | | | | | | | |
| 43 | BLOCK CR | | L | 143.00 SqFt | | | | | | |
| 43 | BLOCK CR | | M | 1068.00 SqFt | | | | | | |
| 48 | L & T CR | | L | 69.00 Ft | | | | | | |
| 48 | L & T CR | | M | 161.00 Ft | | | | | | |
| 52 | RAVELING | | L | 4000.00 SqFt | | | | | | |
| 52 | RAVELING | | M | 1000.00 SqFt | | | | | | |
| Sample Number: | 167 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 34 |
| Sample Comments: | | | | | | | | | | |
| 43 | BLOCK CR | | L | 2000.00 SqFt | | | | | | |
| 43 | BLOCK CR | | M | 3000.00 SqFt | | | | | | |
| 52 | RAVELING | | L | 3750.00 SqFt | | | | | | |
| 52 | RAVELING | | M | 1250.00 SqFt | | | | | | |

| | | | | |
|----------------------------|------------------------------------|--|--------------------|-----------------------|
| Network: OCF | | Name: OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | |
| Branch: TW A | Name: TAXIWAY A | Use: TAXIWAY | Area: 366,333 SqFt | |
| Section: 540 | of 5 | From: - | To: - | Last Const.: 7/1/2021 |
| Surface: AAC | Family: CA653-GA-TW-AAC-APC | Zone: | Category: | Rank: P |
| Area: 104,692 SqFt | Length: 2,075 Ft | Width: 50 Ft | | |
| Slabs: | Slab Length: Ft | Slab Width: Ft | Joint Length: Ft | |
| Shoulder: | Street Type: | Grade: 0 | Lanes: 0 | |
| Section Comments: | | | | |
| Work Date: 1/1/1988 | Work Type: BUILT | | Code: IMPORTED | Is Major M&R: True |
| Work Date: 7/1/2021 | Work Type: Mill and Overlay | | Code: ML-OVL | Is Major M&R: True |
| Last Insp. Date: 1/28/2019 | TotalSamples: 25 | Surveyed: 4 | | |
| Conditions: PCI: 16 | NOTE: *** Pre-Construction PCI *** | | | |
| Inspection Comments: | | | | |
| Sample Number: 104 | Type: R | Area: 5000.00 SqFt | PCI: 14 | |
| Sample Comments: | | | | |
| 41 | ALLIGATOR CR | L | 332.00 SqFt | |
| 43 | BLOCK CR | L | 950.00 SqFt | |
| 48 | L & T CR | L | 125.00 Ft | |
| 48 | L & T CR | M | 335.00 Ft | |
| 50 | PATCHING | L | 6.00 SqFt | |
| 52 | RAVELING | L | 3819.00 SqFt | |
| 52 | RAVELING | M | 750.00 SqFt | |
| 52 | RAVELING | H | 425.00 SqFt | |
| Sample Number: 112 | Type: R | Area: 5000.00 SqFt | PCI: 17 | |
| Sample Comments: | | | | |
| 41 | ALLIGATOR CR | L | 137.00 SqFt | |
| 41 | ALLIGATOR CR | M | 68.00 SqFt | |
| 43 | BLOCK CR | L | 600.00 SqFt | |
| 48 | L & T CR | L | 52.00 Ft | |
| 48 | L & T CR | M | 453.00 Ft | |
| 52 | RAVELING | L | 3970.00 SqFt | |
| 52 | RAVELING | M | 630.00 SqFt | |
| 52 | RAVELING | H | 400.00 SqFt | |
| Sample Number: 114 | Type: R | Area: 5000.00 SqFt | PCI: 17 | |
| Sample Comments: | | | | |
| 41 | ALLIGATOR CR | L | 339.00 SqFt | |
| 41 | ALLIGATOR CR | M | 175.00 SqFt | |
| 43 | BLOCK CR | L | 40.00 SqFt | |
| 48 | L & T CR | L | 170.00 Ft | |
| 48 | L & T CR | M | 200.00 Ft | |
| 52 | RAVELING | L | 3970.00 SqFt | |
| 52 | RAVELING | M | 630.00 SqFt | |
| 52 | RAVELING | H | 400.00 SqFt | |
| 53 | RUTTING | L | 48.00 SqFt | |
| Sample Number: 122 | Type: R | Area: 4861.00 SqFt | PCI: 18 | |
| Sample Comments: | | | | |
| 41 | ALLIGATOR CR | L | 100.00 SqFt | |
| 41 | ALLIGATOR CR | M | 164.00 SqFt | |
| 48 | L & T CR | L | 144.00 Ft | |
| 48 | L & T CR | M | 170.00 Ft | |
| 52 | RAVELING | L | 3975.00 SqFt | |
| 52 | RAVELING | M | 486.00 SqFt | |
| 52 | RAVELING | H | 400.00 SqFt | |

| | | | | | | | | | | | | | | |
|----------------------|--------------|-----|------------------------------------|-----------------------|--|--|--------------|-------|---------------|----|---------------|--------------|----------|--|
| Network: | | OCF | | Name: | | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | |
| Branch: | TW A | | Name: | TAXIWAY A | | Use: | TAXIWAY | Area: | 366,333 SqFt | | | | | |
| Section: | 542 | | of | 5 | | From: | - | | To: | - | | Last Const.: | 7/1/2021 | |
| Surface: | AC | | Family: | CA653-GA-TW-AC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 34,610 SqFt | | Length: | 50 Ft | | Width: | 705 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | | | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/1988 | | Work Type: | BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True | | |
| Work Date: | 7/1/2021 | | Work Type: | New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True | | |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 25 | | Surveyed: | 4 | | | | | | | |
| Conditions: | PCI: 16 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 104 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 14 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | L | 332.00 | | SqFt | | | | | | | | |
| 43 | BLOCK CR | | L | 950.00 | | SqFt | | | | | | | | |
| 48 | L & T CR | | L | 125.00 | | Ft | | | | | | | | |
| 48 | L & T CR | | M | 335.00 | | Ft | | | | | | | | |
| 50 | PATCHING | | L | 6.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | L | 3819.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 750.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | H | 425.00 | | SqFt | | | | | | | | |
| Sample Number: | 112 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 17 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | L | 137.00 | | SqFt | | | | | | | | |
| 41 | ALLIGATOR CR | | M | 68.00 | | SqFt | | | | | | | | |
| 43 | BLOCK CR | | L | 600.00 | | SqFt | | | | | | | | |
| 48 | L & T CR | | L | 52.00 | | Ft | | | | | | | | |
| 48 | L & T CR | | M | 453.00 | | Ft | | | | | | | | |
| 52 | RAVELING | | L | 3970.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 630.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | H | 400.00 | | SqFt | | | | | | | | |
| Sample Number: | 114 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 17 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | L | 339.00 | | SqFt | | | | | | | | |
| 41 | ALLIGATOR CR | | M | 175.00 | | SqFt | | | | | | | | |
| 43 | BLOCK CR | | L | 40.00 | | SqFt | | | | | | | | |
| 48 | L & T CR | | L | 170.00 | | Ft | | | | | | | | |
| 48 | L & T CR | | M | 200.00 | | Ft | | | | | | | | |
| 52 | RAVELING | | L | 3970.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 630.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | H | 400.00 | | SqFt | | | | | | | | |
| 53 | RUTTING | | L | 48.00 | | SqFt | | | | | | | | |
| Sample Number: | 122 | | Type: | R | | Area: | 4861.00 SqFt | | PCI: | 18 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | L | 100.00 | | SqFt | | | | | | | | |
| 41 | ALLIGATOR CR | | M | 164.00 | | SqFt | | | | | | | | |
| 48 | L & T CR | | L | 144.00 | | Ft | | | | | | | | |
| 48 | L & T CR | | M | 170.00 | | Ft | | | | | | | | |
| 52 | RAVELING | | L | 3975.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 486.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | H | 400.00 | | SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--|------------------------------------|--|-------------|-----------|--------------|---------------|--------------|---------------|------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A10 | | Name: | TAXIWAY A10 | | Use: | TAXIWAY | Area: | 28,064 SqFt | | |
| Section: | 535 of 1 | | From: | - | | To: | - | | Last Const.: | 7/1/2021 | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: | P | |
| Area: | 28,064 SqFt | | Length: | 300 Ft | | Width: | 60 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1988 | | Work Type: BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True |
| Work Date: | 7/1/2021 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 5 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 15 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 801 | | Type: | R | | Area: | 5000.00 SqFt | | PCI: | 15 | |
| Sample Comments: | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | L | 33.00 SqFt | | | | | | | |
| 43 | BLOCK CR | | L | 156.00 SqFt | | | | | | | |
| 48 | L & T CR | | L | 331.00 Ft | | | | | | | |
| 48 | L & T CR | | M | 220.00 Ft | | | | | | | |
| 52 | RAVELING | | L | 1500.00 SqFt | | | | | | | |
| 52 | RAVELING | | M | 3000.00 SqFt | | | | | | | |
| 52 | RAVELING | | H | 500.00 SqFt | | | | | | | |

| | | | | | | | | | | | | | | |
|----------------------|-------------|--|------------------------------------|--|--|-------------|--------------|-------|---------------|----|---------------|--------------|----------|--|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | | |
| Branch: | TW A11 | | Name: | TAXIWAY C | | Use: | TAXIWAY | Area: | 23,035 SqFt | | | | | |
| Section: | 545 | | of | 1 | | From: | - | | To: | - | | Last Const.: | 7/1/2021 | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 23,035 SqFt | | Length: | 300 Ft | | Width: | 50 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | | | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/1988 | | Work Type: | BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True | | |
| Work Date: | 7/1/2021 | | Work Type: | Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True | | |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 4 | | Surveyed: | 1 | | | | | | | |
| Conditions: | PCI: 29 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 901 | | Type: | R | | Area: | 5021.00 SqFt | | PCI: | 29 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 48 | L & T CR | | L | 49.00 | | Ft | | | | | | | | |
| 48 | L & T CR | | M | 461.00 | | Ft | | | | | | | | |
| 52 | RAVELING | | L | 3990.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | M | 631.00 | | SqFt | | | | | | | | |
| 52 | RAVELING | | H | 400.00 | | SqFt | | | | | | | | |

| | | | | | | | | | | | | | | |
|----------------------|-------------|--|---------------|----------------------------|--|-------------|--------------|-------|---------------|-------------|---------------|--------------|----------|--|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | |
| Branch: | TW A12 | | Name: | TAXIWAY A12 | | Use: | TAXIWAY | | Area: | 33,994 SqFt | | | | |
| Section: | 555 | | of | 1 | | From: | - | | To: | - | | Last Const.: | 1/1/2008 | |
| Surface: | AC | | Family: | CA653-GA-TW-AC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 33,994 SqFt | | Length: | 802 Ft | | Width: | 40 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | | | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/2008 | | Work Type: | New Construction - Initial | | | | Code: | NU-IN | | Is Major M&R: | True | | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 8 | | Surveyed: | 1 | | | | | | | |
| Conditions: | PCI: 82 | | | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 102 | | Type: | R | | Area: | 4000.00 SqFt | | PCI: | 82 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 48 | L & T CR | | L | 94.00 Ft | | | | | | | | | | |
| 56 | SWELLING | | L | 65.00 SqFt | | | | | | | | | | |
| 57 | WEATHERING | | L | 4000.00 SqFt | | | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|-------------|--------------|----------------|-----------------------|--|-----------|-----------|---------------|-------------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A13 | | Name: | TAXIWAY A13 | | Use: | TAXIWAY | Area: | 54,138 SqFt | | |
| Section: | 596 | of | 1 | From: | - | To: | - | Last Const.: | 1/1/2008 | | |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 54,138 SqFt | | Length: | 600 Ft | | Width: | 80 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | Grade: | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2008 | | Work Type: | New Construction - AC | | | Code: | NC-AC | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 14 | | Surveyed: | 2 | | | | |
| Conditions: | PCI: | 80 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 101 | Type: | R | Area: | 4217.00 SqFt | | PCI: | 76 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | L | 105.00 Ft | | | | | | | | |
| 48 | L & T CR | M | 35.00 Ft | | | | | | | | |
| 57 | WEATHERING | L | 4006.00 SqFt | | | | | | | | |
| 57 | WEATHERING | M | 211.00 SqFt | | | | | | | | |
| Sample Number: | 109 | Type: | R | Area: | 3548.00 SqFt | | PCI: | 84 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | L | 123.00 Ft | | | | | | | | |
| 57 | WEATHERING | L | 3548.00 SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|------------------------------------|--|-------------|-----------|--------------|---------------|-------------|---------------|------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A2 | | Name: | TAXIWAY A2 | | Use: | TAXIWAY | Area: | 31,144 SqFt | | |
| Section: | 501 | of | 1 | From: | - | To: | - | Last Const.: | 7/1/2021 | | |
| Surface: | AAC | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: | T | | |
| Area: | 31,144 SqFt | | Length: | 207 Ft | | Width: | 80 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1977 | | Work Type: | New Construction - Initial | | | Code: | NU-IN | | Is Major M&R: | True |
| Work Date: | 1/1/2007 | | Work Type: | Complete Reconstruction - AC | | | Code: | CR-AC | | Is Major M&R: | True |
| Work Date: | 7/1/2021 | | Work Type: | Mill and Overlay | | | Code: | ML-OVL | | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 5 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 80 | NOTE: *** Pre-Construction PCI *** | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 201 | | Type: | R | | Area: | 6292.00 SqFt | | PCI: | 80 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 185.00 Ft | | | | | | | |
| 52 | RAVELING | | L | 450.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 5842.00 SqFt | | | | | | | |

| | | | | | | | | | | | |
|----------------------|------------|--------------|----------------|-------------------------------|--|-----------|--------------|---------------|-------------|---------------|-------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A3 | | Name: | TAXIWAY A3 | | Use: | TAXIWAY | Area: | 21,152 SqFt | | |
| Section: | 510 | of | 2 | From: | - | To: | - | Last Const.: | 1/1/1985 | | |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 3,960 SqFt | | Length: | 110 Ft | | Width: | 36 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | Grade: | 0 | | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1985 | | Work Type: | BUILT | | | Code: | IMPORTED | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: | Surface Treatment - Seal Coat | | | Code: | ST-SC | | Is Major M&R: | False |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 75 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 202 | | Type: | R | | Area: | 3960.00 SqFt | | PCI: | 75 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 232.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 3762.00 SqFt | | | | | | | |
| 57 | WEATHERING | | M | 198.00 SqFt | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|--------------|--|------------------------------------|--|-------------|-----------|-------------------------------|---------------|--------------|----------|---------------|-------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | |
| Branch: | TW A3 | | Name: | TAXIWAY A3 | | Use: | TAXIWAY | Area: | 21,152 SqFt | | | |
| Section: | 512 of 2 | | From: | - | | To: | - | | Last Const.: | 7/1/2021 | | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: | P | | |
| Area: | 17,192 SqFt | | Length: | 205 Ft | | Width: | 70 Ft | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 1/1/1985 | | Work Type: | | | | BUILT | | Code: | IMPORTED | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: | | | | Surface Treatment - Seal Coat | | Code: | ST-SC | Is Major M&R: | False |
| Work Date: | 7/1/2021 | | Work Type: | | | | Mill and Overlay | | Code: | ML-OVL | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 3 | | Surveyed: | 1 | | | | | |
| Conditions: | PCI: 76 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 201 | | Type: | R | | Area: | 3600.00 SqFt | | PCI: | 76 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 254.00 Ft | | | | | | | | |
| 57 | WEATHERING | | L | 3600.00 SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|-------------|--|---------------------------------------|---------------------|--|-------------|--------------|--------|---------------|--------------------|----------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A4 | | Name: | TAXIWAY A4 | | Use: | TAXIWAY | Area: | 14,827 SqFt | | |
| Section: | 514 of 2 | | From: | - | | | To: | - | | Last Const.: | 1/1/2009 |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | | | Category: | Rank: P | |
| Area: | 11,036 SqFt | | Length: | 200 Ft | | Width: | 50 Ft | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1959 | | Work Type: New Construction - Initial | | | | Code: | NU-IN | | Is Major M&R: True | |
| Work Date: | 1/1/1977 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: True | |
| Work Date: | 1/1/2009 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: True | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 2 | | Surveyed: | | 1 | | | |
| Conditions: | PCI: 74 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 300 | | Type: | R | | Area: | 6464.00 SqFt | | PCI: | 74 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 167.00 Ft | | | | | | | |
| 52 | RAVELING | | L | 1616.00 SqFt | | | | | | | |
| 56 | SWELLING | | L | 5.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 4848.00 SqFt | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--|------------------------------------|---------------------|--|-----------|--------------|----------|---------------|--------------------|----------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A4 | | Name: | TAXIWAY A4 | | Use: | TAXIWAY | Area: | 14,827 SqFt | | |
| Section: | 515 of 2 | | From: | TW A3 | | | To: | 515 | | Last Const.: | 7/1/2021 |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: P | | |
| Area: | 3,791 SqFt | | Length: | 200 Ft | | Width: | 50 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | | Ft | | Joint Length: | | Ft |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1959 | | Work Type: BUILT | | | | Code: | IMPORTED | | Is Major M&R: True | |
| Work Date: | 1/1/1977 | | Work Type: OVERLAY | | | | Code: | IMPORTED | | Is Major M&R: True | |
| Work Date: | 7/1/2021 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: True | |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 46 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 302 | | Type: | R | | Area: | 3793.00 SqFt | | PCI: | 46 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 254.00 Ft | | | | | | | |
| 48 | L & T CR | | M | 344.00 Ft | | | | | | | |
| 52 | RAVELING | | L | 3393.00 SqFt | | | | | | | |
| 52 | RAVELING | | M | 400.00 SqFt | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--|--|--|-------------|-----------|--------------|---------------|--------------|---------------|-------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A5 | | Name: | TAXIWAY A5 | | Use: | TAXIWAY | Area: | 16,927 SqFt | | |
| Section: | 520 of 1 | | From: | - | | To: | - | | Last Const.: | 1/1/1977 | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: | P | |
| Area: | 16,927 SqFt | | Length: | 260 Ft | | Width: | 50 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1959 | | Work Type: BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True |
| Work Date: | 1/1/1977 | | Work Type: OVERLAY | | | | Code: | IMPORTED | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: | False |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 4 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 81 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 401 | | Type: | R | | Area: | 3750.00 SqFt | | PCI: | 81 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 177.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 3750.00 SqFt | | | | | | | |

| | | | | | | | | | | | | | | |
|----------------------|-------------|--|--------------|---------------------|--|-------------|--------------|-------|---------------|----|---------------|----------|---|--|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | |
| Branch: | TW A7 | | Name: | TAXIWAY A7 | | Use: | TAXIWAY | Area: | 16,153 SqFt | | | | | |
| Section: | 525 | | of | 1 | From: | - | | To: | - | | Last Const.: | 1/1/1977 | | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 16,153 SqFt | | Length: | 265 Ft | | Width: | 50 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | | | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/1959 | | | Work Type: | BUILT | | | Code: | IMPORTED | | Is Major M&R: | True | | |
| Work Date: | 1/1/1977 | | | Work Type: | OVERLAY | | | Code: | IMPORTED | | Is Major M&R: | True | | |
| Work Date: | 1/1/2004 | | | Work Type: | Surface Treatment - Seal Coat | | | Code: | ST-SC | | Is Major M&R: | False | | |
| Last Insp. Date: | 4/25/2022 | | | TotalSamples: | 3 | | Surveyed: | 1 | | | | | | |
| Conditions: | PCI: | | 58 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 501 | | Type: | R | | Area: | 4000.00 SqFt | | PCI: | 58 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 48 | L & T CR | | L | 332.00 | | Ft | | | | | | | | |
| 48 | L & T CR | | M | 130.00 | | Ft | | | | | | | | |
| 52 | RAVELING | | L | 72.00 | | SqFt | | | | | | | | |
| 56 | SWELLING | | L | 55.00 | | SqFt | | | | | | | | |
| 57 | WEATHERING | | L | 3732.00 | | SqFt | | | | | | | | |
| 57 | WEATHERING | | M | 196.00 | | SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|-------------|--------------|----------------|--|--------------|-----------|-----------|---------------|-------------|---------------|-------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A8 | | Name: | TAXIWAY A8 | | Use: | TAXIWAY | Area: | 68,183 SqFt | | |
| Section: | 560 | of | 5 | From: | - | To: | - | Last Const.: | 1/1/2000 | | |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 15,868 SqFt | | Length: | 340 Ft | | Width: | 20 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: | New Construction - AC | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: | Surface Treatment - Seal Coat | | | Code: | ST-SC | | Is Major M&R: | False |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 4 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 78 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 501 | Type: | R | Area: | 3177.00 SqFt | | PCI: | 78 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 162.00 Ft | | | | | | | |
| 50 | PATCHING | | L | 12.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 3165.00 SqFt | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--|--|--|-------------|-------------|--------------|---------------|-------------|---------------|-------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A8 | | Name: | TAXIWAY A8 | | Use: | TAXIWAY | Area: | 68,183 SqFt | | |
| Section: | 562 of 5 | | From: | - | | | To: | - | | | |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: P | | |
| Area: | 17,373 SqFt | | Length: | 20 Ft | | Width: | 260 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: | False |
| Work Date: | 7/1/2021 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 5 | | Surveyed: 1 | | | | | |
| Conditions: | PCI: 63 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 500 | | Type: | R | | Area: | 5056.00 SqFt | | PCI: | 63 | |
| Sample Comments: | | | | | | | | | | | |
| 43 | BLOCK CR | | L | 150.00 SqFt | | | | | | | |
| 45 | DEPRESSION | | L | 72.00 SqFt | | | | | | | |
| 48 | L & T CR | | L | 321.00 Ft | | | | | | | |
| 50 | PATCHING | | L | 167.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 4889.00 SqFt | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|--------------|---------|----------------|-------------------------------|--|-----------|--------------|--------|---------------|---------------|--------------|----------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A8 | | Name: | TAXIWAY A8 | | Use: | TAXIWAY | Area: | 68,183 SqFt | | | |
| Section: | 565 | of | 5 | From: | - | | | To: | - | | Last Const.: | 1/1/2000 |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | | | Category: | Rank: P | | |
| Area: | 15,850 SqFt | | Length: | 400 Ft | | Width: | 25 Ft | | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: | New Construction - AC | | | Code: | NC-AC | | Is Major M&R: | True | |
| Work Date: | 1/1/2004 | | Work Type: | Surface Treatment - Seal Coat | | | Code: | ST-SC | | Is Major M&R: | False | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 4 | | Surveyed: | 1 | | | | | |
| Conditions: | PCI: | 85 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 802 | | Type: | R | | Area: | 5072.00 SqFt | | PCI: | 85 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 18.00 | | Ft | | | | | | |
| 57 | WEATHERING | | L | 4565.00 | | SqFt | | | | | | |
| 57 | WEATHERING | | M | 507.00 | | SqFt | | | | | | |

| | | | | | | | | | | | |
|----------------------|------------|--------------|----------------|-------------------------------|--|-----------|--------------|---------------|-------------|---------------|-------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A8 | | Name: | TAXIWAY A8 | | Use: | TAXIWAY | Area: | 68,183 SqFt | | |
| Section: | 570 | of | 5 | From: | - | To: | - | Last Const.: | 1/1/2000 | | |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 6,990 SqFt | | Length: | 400 Ft | | Width: | 25 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: | New Construction - AC | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: | Surface Treatment - Seal Coat | | | Code: | ST-SC | | Is Major M&R: | False |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 2 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 65 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 503 | | Type: | R | | Area: | 3982.00 SqFt | | PCI: | 65 | |
| Sample Comments: | | | | | | | | | | | |
| 45 | DEPRESSION | | L | 3.00 SqFt | | | | | | | |
| 48 | L & T CR | | L | 251.00 Ft | | | | | | | |
| 52 | RAVELING | | L | 15.00 SqFt | | | | | | | |
| 52 | RAVELING | | H | 64.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 3903.00 SqFt | | | | | | | |

| | | | | | | | | | | | |
|----------------------|-------------|--|--|---------------------|--|-------------|--------------|--------|---------------|---------------------|----------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A8 | | Name: | TAXIWAY A8 | | Use: | TAXIWAY | Area: | 68,183 SqFt | | |
| Section: | 575 of 5 | | From: | - | | | To: | - | | Last Const.: | 1/1/2010 |
| Surface: | AAC | | Family: | CA653-GA-TW-AAC-APC | | Zone: | Category: | | Rank: | | P |
| Area: | 12,102 SqFt | | Length: | 415 Ft | | Width: | 25 Ft | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1940 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: True | |
| Work Date: | 1/1/2004 | | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: False | |
| Work Date: | 1/1/2010 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: True | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 3 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: 79 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 601 | | Type: | R | | Area: | 4771.00 SqFt | | PCI: | 79 | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 23.00 Ft | | | | | | | |
| 52 | RAVELING | | L | 39.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 3549.00 SqFt | | | | | | | |
| 57 | WEATHERING | | M | 1183.00 SqFt | | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|--|--|----------------|--|-------------|--------------|---------------|--------------|---------------|-------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW A9 | | Name: | TAXIWAY A9 | | Use: | TAXIWAY | Area: | 42,679 SqFt | | |
| Section: | 550 of 2 | | From: | - | | To: | - | | Last Const.: | 1/1/2000 | |
| Surface: | AC | | Family: | CA653-GA-TW-AC | | Zone: | | | Rank: | P | |
| Area: | 27,079 SqFt | | Length: | 650 Ft | | Width: | 40 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: | False |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 5 | | Surveyed: 2 | | | | | |
| Conditions: | PCI: 74 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 103 | | Type: | R | | Area: | 6212.00 SqFt | | PCI: | 81 | |
| Sample Comments: | | | | | | | | | | | |
| 42 | BLEEDING | | N | | 50.00 SqFt | | | | | | |
| 48 | L & T CR | | L | | 35.00 Ft | | | | | | |
| 52 | RAVELING | | L | | 20.00 SqFt | | | | | | |
| 57 | WEATHERING | | L | | 5882.00 SqFt | | | | | | |
| 57 | WEATHERING | | M | | 310.00 SqFt | | | | | | |
| Sample Number: | 105 | | Type: | R | | Area: | 4000.00 SqFt | | PCI: | 63 | |
| Sample Comments: | | | | | | | | | | | |
| 42 | BLEEDING | | N | | 195.00 SqFt | | | | | | |
| 48 | L & T CR | | L | | 10.00 Ft | | | | | | |
| 50 | PATCHING | | L | | 400.00 SqFt | | | | | | |
| 57 | WEATHERING | | L | | 3600.00 SqFt | | | | | | |

| | | | | | | | | | | | |
|----------------------|--------------|---------|--|--|--------------|-----------|---------|---------------|--------------|---------------|-------|
| Network: | OCF | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW A9 | | Name: | TAXIWAY A9 | | Use: | TAXIWAY | Area: | 42,679 SqFt | | |
| Section: | 552 | of 2 | From: | - | | | To: | - | Last Const.: | 7/1/2021 | |
| Surface: | AAC | Family: | CA653-GA-TW-AAC-APC | Zone: | | | | Category: | Rank: P | | |
| Area: | 15,600 SqFt | | Length: | 230 Ft | | Width: | 45 Ft | | | | |
| Slabs: | Slab Length: | | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | Street Type: | | Grade: | | 0 | | Lanes: | 0 | | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True |
| Work Date: | 1/1/2004 | | Work Type: Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: | False |
| Work Date: | 7/1/2021 | | Work Type: Mill and Overlay | | | | Code: | ML-OVL | | Is Major M&R: | True |
| Last Insp. Date: | 1/28/2019 | | TotalSamples: | 12 | | Surveyed: | 2 | | | | |
| Conditions: | PCI: 81 | | NOTE: *** Pre-Construction PCI *** | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 102 | Type: | R | Area: | 4000.00 SqFt | | PCI: | 91 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | | L | 11.00 Ft | | | | | | | |
| 57 | WEATHERING | | L | 4000.00 SqFt | | | | | | | |
| Sample Number: | 105 | Type: | R | Area: | 4000.00 SqFt | | PCI: | 72 | | | |
| Sample Comments: | | | | | | | | | | | |
| 42 | BLEEDING | | N | 112.00 SqFt | | | | | | | |
| 50 | PATCHING | | L | 600.00 SqFt | | | | | | | |
| 57 | WEATHERING | | L | 3400.00 SqFt | | | | | | | |

| | | | | | | | | | | | | | | |
|----------------------|--------------|--|---------------|-------------------------------|--|-------------|--------------|-------|---------------|-------------|---------------|--------------|----------|--|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | | | |
| Branch: | TW AP N | | Name: | NORTH APRON TAXIWAY | | Use: | TAXIWAY | | Area: | 33,596 SqFt | | | | |
| Section: | 595 | | of | 1 | | From: | - | | To: | - | | Last Const.: | 1/1/2000 | |
| Surface: | AC | | Family: | CA653-GA-TW-AC | | Zone: | | | Category: | | | Rank: | P | |
| Area: | 33,596 SqFt | | Length: | 20 Ft | | Width: | 800 Ft | | | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | | | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | | | |
| Section Comments: | | | | | | | | | | | | | | |
| Work Date: | 1/1/2000 | | Work Type: | New Construction - AC | | | | Code: | NC-AC | | Is Major M&R: | True | | |
| Work Date: | 1/1/2004 | | Work Type: | Surface Treatment - Seal Coat | | | | Code: | ST-SC | | Is Major M&R: | False | | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 8 | | Surveyed: | 2 | | | | | | | |
| Conditions: | PCI: 70 | | | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | | | |
| Sample Number: | 301 | | Type: | R | | Area: | 4000.00 SqFt | | PCI: | 64 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 41 | ALLIGATOR CR | | L | 70.00 SqFt | | | | | | | | | | |
| 48 | L & T CR | | L | 307.00 Ft | | | | | | | | | | |
| 57 | WEATHERING | | L | 4000.00 SqFt | | | | | | | | | | |
| Sample Number: | 305 | | Type: | R | | Area: | 4051.00 SqFt | | PCI: | 76 | | | | |
| Sample Comments: | | | | | | | | | | | | | | |
| 48 | L & T CR | | L | 300.00 Ft | | | | | | | | | | |
| 57 | WEATHERING | | L | 4051.00 SqFt | | | | | | | | | | |

| | | | | | | | | | |
|----------------------|--------------|---------|------------------|-------------|--|-----------|---------------|-------|-----------------------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | |
| Branch: | TW B | | Name: | TAXIWAY B | | Use: | TAXIWAY | Area: | 73,305 SqFt |
| Section: | 105 | of 1 | From: | - | | | To: | - | Last Const.: 1/1/1985 |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: P |
| Area: | 73,305 SqFt | | Length: | 2,895 Ft | | Width: | 25 Ft | | |
| Slabs: | Slab Length: | | Ft | Slab Width: | | Ft | Joint Length: | | Ft |
| Shoulder: | Street Type: | | | Grade: | 0 | | Lanes: | 0 | |
| Section Comments: | | | | | | | | | |
| Work Date: | 1/1/1985 | | Work Type: BUILT | | | Code: | IMPORTED | | |
| Is Major M&R: True | | | | | | | | | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 15 | | Surveyed: | 4 | | |
| Conditions: | PCI: 51 | | | | | | | | |
| Inspection Comments: | | | | | | | | | |
| Sample Number: | 102 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 53 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | | L | 512.00 | Ft | | | | |
| 48 | L & T CR | | M | 139.00 | Ft | | | | |
| 52 | RAVELING | | L | 3750.00 | SqFt | | | | |
| 56 | SWELLING | | L | 180.00 | SqFt | | | | |
| 57 | WEATHERING | | M | 1250.00 | SqFt | | | | |
| Sample Number: | 107 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 50 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | | L | 494.00 | Ft | | | | |
| 48 | L & T CR | | M | 200.00 | Ft | | | | |
| 52 | RAVELING | | L | 3750.00 | SqFt | | | | |
| 56 | SWELLING | | L | 90.00 | SqFt | | | | |
| 57 | WEATHERING | | M | 1250.00 | SqFt | | | | |
| Sample Number: | 108 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 51 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | | L | 425.00 | Ft | | | | |
| 48 | L & T CR | | M | 235.00 | Ft | | | | |
| 52 | RAVELING | | L | 3750.00 | SqFt | | | | |
| 56 | SWELLING | | L | 60.00 | SqFt | | | | |
| 57 | WEATHERING | | M | 1250.00 | SqFt | | | | |
| Sample Number: | 114 | Type: | R | Area: | 5000.00 SqFt | | PCI: | 51 | |
| Sample Comments: | | | | | | | | | |
| 48 | L & T CR | | L | 440.00 | Ft | | | | |
| 48 | L & T CR | | M | 248.00 | Ft | | | | |
| 52 | RAVELING | | L | 3000.00 | SqFt | | | | |
| 56 | SWELLING | | L | 90.00 | SqFt | | | | |
| 57 | WEATHERING | | M | 2000.00 | SqFt | | | | |

| | | | | | | | | | | | | |
|----------------------|------------|--|---------------|----------------|--|-------------|--------------|-------|---------------|------------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW B1 | | Name: | TAXIWAY B1 | | Use: | TAXIWAY | | Area: | 5,513 SqFt | | |
| Section: | 104 | | of | 1 | | From: | - | | To: | - | | |
| Surface: | AC | | Family: | CA653-GA-TW-AC | | Zone: | | | Category: | | | |
| Area: | 5,513 SqFt | | Length: | 203 Ft | | Width: | 25 Ft | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 1/1/1985 | | Work Type: | BUILT | | | | Code: | IMPORTED | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | | |
| Conditions: | PCI: 59 | | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 100 | | Type: | R | | Area: | 5513.00 SqFt | | PCI: | 59 | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 191.00 Ft | | | | | | | | |
| 48 | L & T CR | | M | 240.00 Ft | | | | | | | | |
| 56 | SWELLING | | L | 38.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | L | 4962.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | M | 551.00 SqFt | | | | | | | | |

| | | | | | | | | | | | |
|----------------------|------------|--------------|----------------|------------|--|-----------|-----------|---------------|------------|---------------|------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | |
| Branch: | TW B2 | | Name: | TAXIWAY B2 | | Use: | TAXIWAY | Area: | 6,834 SqFt | | |
| Section: | 106 | of | 1 | From: | - | To: | - | Last Const.: | 1/1/1985 | | |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | Category: | | Rank: | P | |
| Area: | 6,834 SqFt | | Length: | 180 Ft | | Width: | 25 Ft | | | | |
| Slabs: | | Slab Length: | Ft | | Slab Width: | Ft | | Joint Length: | Ft | | |
| Shoulder: | | Street Type: | | | Grade: | 0 | | Lanes: | 0 | | |
| Section Comments: | | | | | | | | | | | |
| Work Date: | 1/1/1985 | | Work Type: | BUILT | | | Code: | IMPORTED | | Is Major M&R: | True |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | |
| Conditions: | PCI: | 52 | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | |
| Sample Number: | 200 | Type: | R | Area: | 6834.00 SqFt | | PCI: | 52 | | | |
| Sample Comments: | | | | | | | | | | | |
| 48 | L & T CR | L | 184.00 Ft | | | | | | | | |
| 48 | L & T CR | M | 330.00 Ft | | | | | | | | |
| 50 | PATCHING | L | 1482.00 SqFt | | | | | | | | |
| 52 | RAVELING | L | 4014.00 SqFt | | | | | | | | |
| 56 | SWELLING | L | 5.00 SqFt | | | | | | | | |
| 57 | WEATHERING | L | 1338.00 SqFt | | | | | | | | |

| | | | | | | | | | | | | |
|----------------------|------------|---------|----------------|--------------|--|-------------|---------|----------|------------|---------------|--------------|----------|
| Network: | OCF | | | Name: | OCALA INTERNATIONAL AIRPORT - JIM TAYLOR FIELD | | | | | | | |
| Branch: | TW B3 | | Name: | TAXIWAY B3 | | Use: | TAXIWAY | Area: | 5,513 SqFt | | | |
| Section: | 102 | of | 1 | From: | - | | | To: | - | | Last Const.: | 1/1/1985 |
| Surface: | AC | Family: | CA653-GA-TW-AC | | Zone: | | | | Category: | Rank: P | | |
| Area: | 5,513 SqFt | | Length: | 180 Ft | | Width: | 25 Ft | | | | | |
| Slabs: | | | Slab Length: | Ft | | Slab Width: | Ft | | | Joint Length: | Ft | |
| Shoulder: | | | Street Type: | | | Grade: | 0 | | | Lanes: | 0 | |
| Section Comments: | | | | | | | | | | | | |
| Work Date: | 1/1/1985 | | Work Type: | BUILT | | | Code: | IMPORTED | | Is Major M&R: | True | |
| Last Insp. Date: | 4/25/2022 | | TotalSamples: | 1 | | Surveyed: | 1 | | | | | |
| Conditions: | PCI: | 55 | | | | | | | | | | |
| Inspection Comments: | | | | | | | | | | | | |
| Sample Number: | 116 | Type: | R | Area: | 5513.00 SqFt | | | PCI: | 55 | | | |
| Sample Comments: | | | | | | | | | | | | |
| 48 | L & T CR | | L | 178.00 Ft | | | | | | | | |
| 48 | L & T CR | | M | 179.00 Ft | | | | | | | | |
| 50 | PATCHING | | L | 1114.00 SqFt | | | | | | | | |
| 52 | RAVELING | | L | 3299.00 SqFt | | | | | | | | |
| 57 | WEATHERING | | M | 1100.00 SqFt | | | | | | | | |



FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE



AVIATION