

2022

*Statewide Airfield Pavement Management Program*



# Airport Pavement Evaluation Report

OMN - Ormond Beach Municipal Airport | *District 5*



AVIATION





---

*Florida Department of Transportation*

---

# ***Statewide Airfield Pavement Management Program***

## **Airport Pavement Evaluation Report**

**Prepared by:**

*FDOT Aviation Office  
605 Suwannee Street  
Tallahassee, Florida 32399-0450*

**Website:** [FDOT Aviation Office](#)

**Interactive Web Application:** [FDOT SAPMP Interactive Web Application](#)

# TABLE OF CONTENTS

<b>EXECUTIVE SUMMARY .....</b>	<b>1</b>
<i>Program Background.....</i>	<i>1</i>
<i>Current Pavement Conditions .....</i>	<i>2</i>
<i>Forecasted Pavement Conditions .....</i>	<i>3</i>
<i>Major Rehabilitation Planning 2023-2032 .....</i>	<i>5</i>
<b>CHAPTER 1 – INTRODUCTION.....</b>	<b>8</b>
1.1 Background .....	8
1.2 Stakeholders .....	10
1.3 General Scope of Work .....	10
1.4 FDOT SAPMP Objectives .....	11
<b>CHAPTER 2 – METHODOLOGY.....</b>	<b>14</b>
2.1 Airfield Pavement Database.....	14
2.2 Airfield Pavement Record Keeping (Historical Records Research).....	15
2.3 Airfield Pavement Structure.....	15
2.3.1 Asphalt Concrete.....	16
2.3.2 Portland Cement Concrete .....	16
2.3.3 Composite Structure – Whitetopping Pavement .....	16
2.4 Airfield Pavement Traffic .....	17
2.5 Pavement Management Program Network Definition Terminology .....	17
2.5.1 Pavement Network Identification .....	17
2.5.2 Pavement Branch Identification .....	17
2.5.3 Pavement Section Identification .....	18
2.5.4 Pavement Sample Unit Identification .....	18
2.5.5 Terminology Summary .....	18
2.6 Airfield PCI Survey Methodology .....	18
2.6.1 Pavement Distress Types.....	19
2.6.2 PCI Survey Procedures.....	20
<b>CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY.....</b>	<b>23</b>
3.1 Airfield Pavement Network Information.....	23
3.1.1 Previous and/or Anticipated Airfield Pavement Construction .....	23
3.1.2 Estimated Pavement Age .....	26
3.1.3 Functional Use .....	28
3.1.4 Pavement Surface Type.....	28
3.1.5 Pavement System Inventory Details .....	29
<b>CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS .....</b>	<b>32</b>
4.1 Airfield Pavement Condition Index.....	32
4.1.1 Network-Level Analysis.....	32
4.1.2 Branch-Level Analysis.....	32
4.1.3 Section-Level Analysis .....	35
4.2 Summary of Pavement Condition Evaluation Results .....	38

4.2.1 Network-Level Observations .....	38
4.2.2 Branch-Level Observations .....	38
<b>CHAPTER 5 – SAPMP CUSTOMIZATION.....</b>	<b>48</b>
5.1 Network-Level Customization.....	48
5.2 Pavement Condition Forecasts .....	48
5.2.1 Forecasting PCI Considerations .....	49
5.2.2 Performance Models .....	49
5.2.3 Branch-Level Pavement Condition Forecast.....	49
5.2.4 Section-Level Pavement Condition Forecast.....	50
5.3 Critical PCI Value.....	52
5.4 Localized Maintenance and Repair .....	55
5.4.1 Localized Maintenance and Repair Approach .....	55
5.4.2 Localized Work Types .....	56
5.4.3 Localized Maintenance Planning-Level Unit Costs .....	58
5.4.4 Localized Maintenance and Repair Policy .....	58
5.5 Major Rehabilitation .....	61
5.5.1 Major Rehabilitation Pavement Section Development .....	61
5.5.2 Major Rehabilitation Planning-Level Unit Costs .....	63
<b>CHAPTER 6 – M&amp;R PLANNING AND BUDGET SCENARIO ANALYSIS .....</b>	<b>65</b>
6.1 Localized Maintenance and Repair Analysis and Recommendations .....	65
6.2 Major Rehabilitation Needs.....	67
6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs .....	67
<b>CHAPTER 7 – CONCLUSION.....</b>	<b>72</b>
7.1 Recommendations .....	72
7.1.1 Continued PCI Surveys .....	72
7.1.2 Localized Maintenance and Repair .....	72
7.1.3 Major Rehabilitation.....	72
7.1.4 Pavement Management System.....	72
7.2 Supporting Documents .....	73
Airfield Pavement Network Definition Exhibit.....	73
Airfield Pavement System Inventory Exhibit .....	73
Airfield Pavement Estimated Age Exhibit .....	73
Airfield Pavement Condition Index Exhibit.....	73
Airfield Pavement Major Rehabilitation Exhibit .....	73
Inspection Photograph Documentation.....	73
7.3 Conclusion.....	74
7.4 References.....	74



## **APPENDIX**


*Appendix A: Airfield Pavement Analysis*

*Appendix B: Maintenance and Rehabilitation Planning Needs*

*Appendix C: Technical Exhibits*

*Appendix D: Inspection Photograph Documentation*

*Appendix E: Inspection Distress Details*



## LIST OF TABLES

Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level.....	2
Table E.2: Forecasted PCI Values 2023-2032 – Section-Level.....	3
Table E.3: Major Rehabilitation Planning 2023-2032.....	5
Table 1.2: FDOT SAPMP Stakeholders .....	10
Table 2.5.5: SAPMP Terminology .....	18
Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete .....	19
Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete.....	20
Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete.....	20
Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete .....	21
Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction .....	23
Table 3.1.5: Pavement System Inventory Details .....	29
Table 4.1.2: Current Condition Summary – Branch-Level .....	35
Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level.....	36
Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level .....	50
Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects.....	53
Table 5.3 (b): Critical PCI Values by Branch Use .....	53
Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete .....	58
Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete.....	58
Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy .....	59
Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy .....	60
Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation .....	62
Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type .....	63
Table 6.1 (a): Year 1 Summary of Localized Maintenance .....	65
Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary .....	66
Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary .....	66
Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs .....	68



## LIST OF FIGURES

Figure E.1: PCI Rating .....	1
Figure E.2: Current Condition Summary – Branch-Level .....	2
Figure E.3: 10-Year Major Rehabilitation Needs by Program Year .....	6
Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts .....	9
Figure 1.4: Pavement Life and the Effect of Treatments .....	12
Figure 2: FDOT SAPMP General Process .....	14
Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit .....	24
Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit .....	25
Figure 3.1.2 (a): Age of Pavements at PCI Survey .....	26
Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit .....	27
Figure 3.1.3: Airfield Pavement Branch Use by Area (SF) .....	28
Figure 3.1.4: Airfield Pavement Surface Type by Area (SF) .....	29
Figure 4.1.1: Current Condition – Overall Network .....	32
Figure 4.1.2 (a): Current Condition Summary – Branch-Level .....	32
Figure 4.1.2 (b): Current Condition – Runway .....	33
Figure 4.1.2 (c): Current Condition – Taxiway .....	33
Figure 4.1.2 (d): Current Condition – Taxilane .....	34
Figure 4.1.2 (e): Current Condition – Apron .....	34
Figure 4.1.3: Airfield Pavement Condition Index Exhibit .....	37
Figure 5.2.3: Forecasted Branch-Level Pavement Performance .....	49
Figure 5.3 (a): Pavement Life and the Effect of Treatments .....	52
Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical } PCI$ .....	54
Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical } PCI$ .....	54
Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year .....	69
Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit .....	70



# Executive Summary





# Executive Summary

## Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Ormond Beach Municipal Airport's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section. This is graphically depicted in **Figure E.1**.


*Figure E.1: PCI Rating*

Color	Range	Condition Rating
	86-100	Good
	71-85	Satisfactory
	56-70	Fair
	41-55	Poor
	26-40	Very Poor
	11-25	Serious
	0-10	Failed

## Current Pavement Conditions

In April 2022, approximately 2.0 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Ormond Beach Municipal Airport (OMN). In general, airfield pavements at OMN are in Satisfactory condition with an area-weighted PCI of 75. The area-weighted average PCI values of the runways, taxiways, taxilanes, and aprons are 79, 84, 68, and 60, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for OMN.

*Figure E.2: Current Condition Summary – Branch-Level*



*Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
OMN	RW 9-27	Runway	6105	262,949	91	Good
OMN	RW 9-27	Runway	6110	30,000	94	Good
OMN	RW 17-35	Runway	6205	329,912	68	Fair
OMN	RW 17-35	Runway	6210	10,188	66	Fair
OMN	RW 17-35	Runway	6215	30,400	91	Good
OMN	TW A	Taxiway	100	123,174	89	Good
OMN	TW A	Taxiway	102	2,434	91	Good
OMN	TW A	Taxiway	105	4,550	91	Good
OMN	TW A	Taxiway	120	2,519	94	Good
OMN	TW A	Taxiway	125	23,310	100	Good
OMN	TW A1	Taxiway	110	8,089	86	Good
OMN	TW A1	Taxiway	112	3,083	91	Good
OMN	TW A2	Taxiway	115	8,054	91	Good
OMN	TW A2	Taxiway	117	3,118	91	Good
OMN	TW B	Taxiway	205	51,318	100	Good
OMN	TW B	Taxiway	210	7,706	86	Good
OMN	TW C	Taxiway	305	35,387	88	Good



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
OMN	TW D	Taxiway	405	81,876	100	Good
OMN	TW E	Taxiway	505	56,507	38	Very Poor
OMN	TW E	Taxiway	510	26,455	91	Good
OMN	TW E	Taxiway	515	2,399	94	Good
OMN	TW F	Taxiway	605	36,880	40	Very Poor
OMN	TW F	Taxiway	610	9,548	100	Good
OMN	TW F	Taxiway	650	6,273	35	Very Poor
OMN	TW G	Taxiway	700	126,774	88	Good
OMN	TW G1	Taxiway	715	8,543	91	Good
OMN	TW G2	Taxiway	705	8,946	88	Good
OMN	TW G3	Taxiway	710	8,941	89	Good
OMN	TW G4	Taxiway	720	8,529	91	Good
OMN	TL SW	Taxilane	2004	17,255	0	Failed
OMN	TL T-HANG	Taxilane	4410	57,362	88	Good
OMN	AP FBO	Apron	4102	22,255	26	Very Poor
OMN	AP FBO	Apron	4105	164,592	57	Fair
OMN	AP FBO	Apron	4110	141,436	36	Very Poor
OMN	AP FBO	Apron	4115	14,790	100	Good
OMN	AP MID	Apron	4505	44,107	100	Good
OMN	AP RU 17	Apron	5310	39,883	91	Good
OMN	AP RU 27	Apron	5110	27,832	87	Good
OMN	AP RU 35	Apron	5410	40,187	91	Good
OMN	AP RU 9	Apron	5210	28,165	91	Good
OMN	AP T-HANG	Apron	4305	54,292	31	Very Poor
OMN	AP T-HANG	Apron	4310	5,932	30	Very Poor

## Forecasted Pavement Conditions

**Table E.2** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

*Table E.2: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
OMN	RW 9-27	6105	91	89	87	85	84	82	80	79	77	75	74
OMN	RW 9-27	6110	94	92	90	89	87	85	83	82	80	78	76
OMN	RW 17-35	6205	68	66	64	62	60	58	56	54	52	50	48
OMN	RW 17-35	6210	66	64	62	60	58	56	54	52	50	48	46
OMN	RW 17-35	6215	91	89	87	85	83	81	79	77	75	73	71

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
OMN	TW A	100	89	87	85	83	81	79	78	76	75	73	72
OMN	TW A	102	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A	105	91	88	86	84	82	81	79	77	76	74	73
OMN	TW A	120	94	91	89	87	85	83	82	80	78	77	75
OMN	TW A	125	100	97	95	93	90	88	86	84	83	81	79
OMN	TW A1	110	86	84	82	80	79	77	75	74	73	71	70
OMN	TW A1	112	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A2	115	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A2	117	91	89	87	85	83	81	79	78	76	75	73
OMN	TW B	205	100	97	95	93	90	88	86	84	83	81	79
OMN	TW B	210	86	84	82	80	79	77	75	74	73	71	70
OMN	TW C	305	88	86	84	82	80	79	77	75	74	73	71
OMN	TW D	405	100	97	95	93	90	88	86	84	83	81	79
OMN	TW E	505	38	35	32	30	27	24	22	19	17	14	11
OMN	TW E	510	91	89	87	85	83	81	79	78	76	75	73
OMN	TW E	515	94	91	89	87	85	83	82	80	78	77	75
OMN	TW F	605	40	39	38	37	36	35	34	33	31	30	29
OMN	TW F	610	100	97	95	93	90	88	86	84	83	81	79
OMN	TW F	650	35	34	32	31	30	28	27	25	24	22	20
OMN	TW G	700	88	86	84	82	80	79	77	75	74	73	71
OMN	TW G1	715	91	89	87	85	83	81	79	78	76	75	73
OMN	TW G2	705	88	86	84	82	80	79	77	75	74	73	71
OMN	TW G3	710	89	87	85	83	81	79	78	76	75	73	72
OMN	TW G4	720	91	89	87	85	83	81	79	78	76	75	73
OMN	TL SW	2004	0	0	0	0	0	0	0	0	0	0	0
OMN	TL T-HANG	4410	88	86	84	82	80	79	77	75	74	73	71
OMN	AP FBO	4102	26	25	24	24	23	22	21	20	20	19	18
OMN	AP FBO	4105	57	56	55	54	53	52	51	51	50	49	48
OMN	AP FBO	4110	36	34	32	30	28	26	24	22	20	18	16
OMN	AP FBO	4115	100	97	95	92	90	88	86	84	82	80	78
OMN	AP MID	4505	100	97	95	92	90	88	86	84	82	80	78
OMN	AP RU 17	5310	91	88	86	84	82	80	78	76	75	73	71
OMN	AP RU 27	5110	87	85	82	81	79	77	75	73	72	70	69
OMN	AP RU 35	5410	91	88	86	84	82	80	78	76	75	73	71
OMN	AP RU 9	5210	91	88	86	84	82	80	78	76	75	73	71
OMN	AP T-HANG	4305	31	30	30	29	28	28	27	26	25	24	24
OMN	AP T-HANG	4310	30	29	29	28	27	26	25	25	24	23	22



## Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.


The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$10.62M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$10.23M and localized maintenance needs for Year 1 are \$0.46M.

*Table E.3: Major Rehabilitation Planning 2023-2032*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	OMN	RW 17-35	6205	AAC	329,912	66	AC Rehabilitation	\$ 2,970,000
2023	OMN	RW 17-35	6210	AAC	10,188	64	AC Rehabilitation	\$ 92,000
2023	OMN	TW E	505	AAC	56,507	35	AC Reconstruction	\$ 905,000
2023	OMN	TW F	605	AC	36,880	39	AC Reconstruction	\$ 591,000
2023	OMN	TW F	650	AC	6,273	34	AC Reconstruction	\$ 101,000
2023	OMN	TL SW	2004	PCC	17,255	0	PCC Reconstruction	\$ 501,000
2023	OMN	AP FBO	4102	AC	22,255	25	AC Reconstruction	\$ 357,000
2023	OMN	AP FBO	4105	AC	164,592	56	AC Rehabilitation	\$ 1,482,000
2023	OMN	AP FBO	4110	AAC	141,436	34	AC Reconstruction	\$ 2,263,000
2023	OMN	AP T-HANG	4305	AC	54,292	30	AC Reconstruction	\$ 869,000
2023	OMN	AP T-HANG	4310	AC	5,932	29	AC Reconstruction	\$ 95,000
2032	OMN	AP RU 27	5110	AC	27,832	69	AC Rehabilitation	\$ 389,000

*\*All planning cost values have been rounded up to the nearest thousand dollars.*

*Figure E.3: 10-Year Major Rehabilitation Needs by Program Year*







# Chapter 1: Introduction



# Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida's economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida's most prominent industry.

## 1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management Program (PMP)". The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are




# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

under consideration for projects. A network-level evaluation can support the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

*Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts*





## 1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

*Table 1.2: FDOT SAPMP Stakeholders*

Role	Description
<b>FAA Orlando Airports District Office (Orlando ADO)</b>	Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation).
<b>Florida Department of Transportation (FDOT)</b>	Key Stakeholder: the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System.
<b>FDOT District Offices</b>	The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes.
<b>Participating Public-Use and Publicly-Owned Airports</b>	The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment.
<b>Aviation Office Program Manager (AO-PM)</b>	FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update.

## 1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- » Research and evaluation of existing record documentation;
- » Establishment of a pavement system inventory;
- » Development of a pavement network definition map and supplemental GIS model;
- » Functional pavement evaluations via the PCI assessment method;
- » Customization of PAVER™ software including prioritization, policies, and performance models;
- » Analysis of condition data; and
- » Maintenance, repair, and rehabilitation planning.

## 1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.


A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:

- » Assist airports in meeting the requirements of Public Law 103-305;
- » Assist airports in complying with FAA Grant Assurances 11 and 19;
- » Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- » Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- » Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.

*Figure 1.4: Pavement Life and the Effect of Treatments*



**FAA Eligibility Thresholds:** ☐ >70: Routine Maintenance ☐ 55-70: Rehabilitation Eligible ☐ <55: Reconstruction Eligible

*\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements*






## Chapter 2: Methodology



## Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.

*Figure 2: FDOT SAPMP General Process*



### 2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- » Create a manageable inventory system;
- » Analyze the current condition of pavements in accordance with ASTM D5340-20;
- » Develop pavement performance models to forecast conditions; and
- » Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database and typically consist of pavement inventory

characteristics, pavement structure, work history, historic condition records, and analytical customization.

## 2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- » Location and limits of work;
- » Types and severities of repaired distresses;
- » Work type and cost; and
- » Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- » Date of last construction/rehabilitation
- » Work type performed
- » Comments for documenting pavement cross-section
- » Pavement surface type
- » Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

## 2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.



### 2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

#### **Asphalt Concrete (AC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

#### **Asphalt Concrete Overlaid on Asphalt Concrete (AAC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

#### **Asphalt Concrete Overlaid on Portland Cement Concrete (APC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

### 2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

#### **Portland Cement Concrete (PCC)**

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

### 2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

#### **Conventional Whitetopping (WT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.

### **Thin Whitetopping (TWT)**

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

### **Ultra-Thin Whitetopping (UWT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

## **2.4 Airfield Pavement Traffic**

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of OMN's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

## **2.5 Pavement Management Program Network Definition Terminology**

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

### **2.5.1 Pavement Network Identification**

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

### **2.5.2 Pavement Branch Identification**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.

### 2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

### 2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs ( $\pm 8$  slabs) for PCC pavement and 5,000 contiguous square feet ( $\pm 2,000$  SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

### 2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

*Table 2.5.5: SAPMP Terminology*

SAPMP Terminology	Common Definition	Airport Example
<b>Network</b>	Totality of pavement assets maintained by the Airport.	"Tallahassee International Airport – Airfield Pavements"
<b>Branch Name</b>	Commonly defined asset name as established by Airport and by use.	"Runway 18-36"
<b>Branch ID</b>	Codified shorthand name for commonly defined asset established for database identification.	"RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility
<b>Section ID</b>	Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition.	"6105"
<b>Sample Unit</b>	A numeric identification of an area of pavement (5,000 $\pm$ 2,000 SF of AC or 20 $\pm$ 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20.	"300"

## 2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.



Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

### 2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

*Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete*

Distress Mechanism	Distress Type
Load	Alligator Cracking Rutting
Climate/Durability	Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering
Construction/Material	Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling
Other	Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching

*Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete*

Distress Mechanism	Distress Type
Load	Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks
Climate/Durability	Blowup Durability "D" Cracking Joint Seal Damage Popouts
Construction/Material	Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking
Other	Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching

### 2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.

*Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete*


Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10

*Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete*


Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.





# **Chapter 3: Airfield Pavement System Inventory**



## Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

### 3.1 Airfield Pavement Network Information

#### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.


*Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction*

Construction Year	Location	Work Type / Pavement Section
2019	TW A, TW A1, TW A2, TW E	Complete Reconstruction - AC
	RW 9-27	Complete Reconstruction - AC   4" P-401, 6" min P-211 (scarify 3" of existing base), existing subgrade
	RW 9-27	Complete Reconstruction - AC   4" P-401, 6" P-403, 12" P-152
	RW 17-35	Mill and Overlay   2" Mill, 2" P-401 Overlay
2022	TW A, TW F	Mill and Overlay   2" Mill, 2" P-401 Overlay
	TW B, TW D, AP FBO	Complete Reconstruction - AC
	AP MID	New Construction - AC


The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

**Figure 3.1.1 (a)**, the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.











RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2019	TW A, TW A1, TW A2, TW E	Complete Reconstruction - AC
	RW 17-35	Mill and Overlay   2" Mill, 2" P-401 Overlay
	RW 9-27	Complete Reconstruction - AC   4" P-401, 6" P-403, 12" P-152
2022	AP FBO, TW B, TW D	Complete Reconstruction - AC
	AP MID	New Construction - AC
	TW A, TW F	Mill and Overlay   2" Mill, 2" P-401 Overlay
2023	RW 9-27, TW A	New Construction - AC   600' RW and TW Extension

### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.

*Figure 3.1.2 (a): Age of Pavements at PCI Survey*





**LEGEND**

TYPICAL RUNWAY BRANCH ID  
 TYPICAL TAXIWAY BRANCH ID  
 TYPICAL APRON BRANCH ID

**AGE AT INSPECTION**

White	0-5 Years
Light Blue	6-10 Years
Medium Blue	11-15 Years
Dark Blue	16-20 Years
Black	> 20 Years


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



### 3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed “functional use” or “branch use.” For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.

*Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)*




### 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at OMN.

Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)



### 3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

**Table 3.1.5** displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

Table 3.1.5: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
OMN	RW 9-27	Runway	6105	262,949	AC	7/1/2019
OMN	RW 9-27	Runway	6110	30,000	AC	7/1/2019
OMN	RW 17-35	Runway	6205	329,912	AAC	1/1/2008
OMN	RW 17-35	Runway	6210	10,188	AAC	1/1/2008
OMN	RW 17-35	Runway	6215	30,400	AAC	7/1/2019
OMN	TW A	Taxiway	100	123,174	AC	1/1/2013
OMN	TW A	Taxiway	102	2,434	AC	1/1/2019
OMN	TW A	Taxiway	105	4,550	AAC	1/1/2016

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
OMN	TW A	Taxiway	120	2,519	AC	7/1/2019
OMN	TW A	Taxiway	125	23,310	AAC	5/1/2022
OMN	TW A1	Taxiway	110	8,089	AC	1/1/2013
OMN	TW A1	Taxiway	112	3,083	AC	7/1/2019
OMN	TW A2	Taxiway	115	8,054	AC	1/1/2013
OMN	TW A2	Taxiway	117	3,118	AC	7/1/2019
OMN	TW B	Taxiway	205	51,318	AC	5/1/2022
OMN	TW B	Taxiway	210	7,706	AC	1/1/2013
OMN	TW C	Taxiway	305	35,387	AC	1/1/2013
OMN	TW D	Taxiway	405	81,876	AC	5/1/2022
OMN	TW E	Taxiway	505	56,507	AAC	1/1/1990
OMN	TW E	Taxiway	510	26,455	AC	1/1/2013
OMN	TW E	Taxiway	515	2,399	AC	7/1/2019
OMN	TW F	Taxiway	605	36,880	AC	1/1/1984
OMN	TW F	Taxiway	610	9,548	AAC	5/1/2022
OMN	TW F	Taxiway	650	6,273	AC	1/1/1984
OMN	TW G	Taxiway	700	126,774	AC	1/1/2016
OMN	TW G1	Taxiway	715	8,543	AC	1/1/2016
OMN	TW G2	Taxiway	705	8,946	AC	1/1/2016
OMN	TW G3	Taxiway	710	8,941	AC	1/1/2016
OMN	TW G4	Taxiway	720	8,529	AC	1/1/2016
OMN	TL SW	Taxilane	2004	17,255	PCC	1/1/1992
OMN	TL T-HANG	Taxilane	4410	57,362	AC	1/1/2005
OMN	AP FBO	Apron	4102	22,255	AC	1/1/1992
OMN	AP FBO	Apron	4105	164,592	AC	1/1/1992
OMN	AP FBO	Apron	4110	141,436	AAC	1/1/1992
OMN	AP FBO	Apron	4115	14,790	AC	5/1/2022
OMN	AP MID	Apron	4505	44,107	AC	5/1/2022
OMN	AP RU 17	Apron	5310	39,883	AC	1/1/2016
OMN	AP RU 27	Apron	5110	27,832	AC	1/1/2013
OMN	AP RU 35	Apron	5410	40,187	AC	1/1/2016
OMN	AP RU 9	Apron	5210	28,165	AC	1/1/2013
OMN	AP T-HANG	Apron	4305	54,292	AC	1/1/1984
OMN	AP T-HANG	Apron	4310	5,932	AC	7/31/2008



A photograph of a long, straight asphalt runway stretching towards the horizon under a bright blue sky filled with fluffy white clouds. The runway has a central white dashed line and yellow dashed lines on the sides. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Chapter 4: Airfield Pavement Condition Analysis**

A close-up, low-angle view of the runway pavement, showing the texture of the asphalt and the white dashed center line. A series of yellow chevron markings are visible on the right side of the frame.A thick red diagonal bar running from the bottom left towards the top right, partially overlapping the runway image.

## Chapter 4 – Airfield Pavement Condition Analysis


The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for design-and/or project-level determination of pavement rehabilitation needs.

### 4.1 Airfield Pavement Condition Index

#### 4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 57% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 26% of inspected pavements are in Fair condition and the remaining 17% of inspected pavements are in Poor or worse condition.

*Figure 4.1.1: Current Condition – Overall Network*



#### 4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(e)** summarize branch-level pavement conditions according to the most recent PCI assessment results.

*Figure 4.1.2 (a): Current Condition Summary – Branch-Level*




Figure 4.1.2 (b): Current Condition – Runway






Figure 4.1.2 (c): Current Condition – Taxiway



*Figure 4.1.2 (d): Current Condition – Taxi Lane*



*Figure 4.1.2 (e): Current Condition – Apron*





**Table 4.1.2** details the branch-level condition for each airfield pavement branch.

*Table 4.1.2: Current Condition Summary – Branch-Level*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
RW 9-27	Runway	2	292,949	91	Good
RW 17-35	Runway	3	370,500	70	Fair
TW A	Taxiway	5	155,987	91	Good
TW A1	Taxiway	2	11,172	87	Good
TW A2	Taxiway	2	11,172	91	Good
TW B	Taxiway	2	59,024	98	Good
TW C	Taxiway	1	35,387	88	Good
TW D	Taxiway	1	81,876	100	Good
TW E	Taxiway	3	85,361	56	Fair
TW F	Taxiway	3	52,701	50	Poor
TW G	Taxiway	1	126,774	88	Good
TW G1	Taxiway	1	8,543	91	Good
TW G2	Taxiway	1	8,946	88	Good
TW G3	Taxiway	1	8,941	89	Good
TW G4	Taxiway	1	8,529	91	Good
TL SW	Taxilane	1	17,255	0	Failed
TL T-HANG	Taxilane	1	57,362	88	Good
AP FBO	Apron	4	343,073	48	Poor
AP MID	Apron	1	44,107	100	Good
AP RU 17	Apron	1	39,883	91	Good
AP RU 27	Apron	1	27,832	87	Good
AP RU 35	Apron	1	40,187	91	Good
AP RU 9	Apron	1	28,165	91	Good
AP T-HANG	Apron	2	60,224	31	Very Poor

#### 4.1.3 Section-Level Analysis


**Table 4.1.3** provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.

Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.

Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
OMN	RW 9-27	Runway	6105	262,949	AC	91	Good	100	0	0	11	47
OMN	RW 9-27	Runway	6110	30,000	AC	94	Good	100	0	0	2	6
OMN	RW 17-35	Runway	6205	329,912	AAC	68	Fair	85	0	15	14	66
OMN	RW 17-35	Runway	6210	10,188	AAC	66	Fair	73	0	27	1	2
OMN	RW 17-35	Runway	6215	30,400	AAC	91	Good	100	0	0	2	6
OMN	TW A	Taxiway	100	123,174	AC	89	Good	100	0	0	5	33
OMN	TW A	Taxiway	102	2,434	AC	91	Good	100	0	0	1	1
OMN	TW A	Taxiway	105	4,550	AAC	91	Good	100	0	0	1	1
OMN	TW A	Taxiway	120	2,519	AC	94	Good	100	0	0	1	1
OMN	TW A	Taxiway	125	23,310	AC	100	Good	0	0	0	0	0
OMN	TW A1	Taxiway	110	8,089	AC	86	Good	62	0	38	1	2
OMN	TW A1	Taxiway	112	3,083	AC	91	Good	100	0	0	1	1
OMN	TW A2	Taxiway	115	8,054	AC	91	Good	100	0	0	1	2
OMN	TW A2	Taxiway	117	3,118	AC	91	Good	100	0	0	1	1
OMN	TW B	Taxiway	205	51,318	AC	100	Good	0	0	0	0	0
OMN	TW B	Taxiway	210	7,706	AC	86	Good	100	0	0	1	2
OMN	TW C	Taxiway	305	35,387	AC	88	Good	100	0	0	2	9
OMN	TW D	Taxiway	405	81,876	AC	100	Good	0	0	0	0	0
OMN	TW E	Taxiway	505	56,507	AAC	38	Very Poor	97	0	3	3	16
OMN	TW E	Taxiway	510	26,455	AC	91	Good	100	0	0	1	7
OMN	TW E	Taxiway	515	2,399	AC	94	Good	100	0	0	1	1
OMN	TW F	Taxiway	605	36,880	AC	40	Very Poor	97	0	3	2	9
OMN	TW F	Taxiway	610	9,548	AC	100	Good	0	0	0	0	0
OMN	TW F	Taxiway	650	6,273	AC	35	Very Poor	87	0	13	1	1
OMN	TW G	Taxiway	700	126,774	AC	88	Good	83	0	17	4	35
OMN	TW G1	Taxiway	715	8,543	AC	91	Good	100	0	0	1	2
OMN	TW G2	Taxiway	705	8,946	AC	88	Good	100	0	0	1	2
OMN	TW G3	Taxiway	710	8,941	AC	89	Good	100	0	0	1	2
OMN	TW G4	Taxiway	720	8,529	AC	91	Good	100	0	0	1	2
OMN	TL SW	Taxilane	2004	17,255	PCC	0	Failed	8	92	0	1	3
OMN	TL T-HANG	Taxilane	4410	57,362	AC	88	Good	98	0	2	2	11
OMN	AP FBO	Apron	4102	22,255	AC	26	Very Poor	76	0	24	1	6
OMN	AP FBO	Apron	4105	164,592	AC	57	Fair	97	0	3	4	39
OMN	AP FBO	Apron	4110	141,436	AAC	36	Very Poor	79	20	1	4	26
OMN	AP FBO	Apron	4115	14,790	AC	100	Good	0	0	0	0	0
OMN	AP MID	Apron	4505	44,107	AC	100	Good	0	0	0	0	0
OMN	AP RU 17	Apron	5310	39,883	AC	91	Good	100	0	0	1	8
OMN	AP RU 27	Apron	5110	27,832	AC	87	Good	100	0	0	1	5
OMN	AP RU 35	Apron	5410	40,187	AC	91	Good	100	0	0	1	8
OMN	AP RU 9	Apron	5210	28,165	AC	91	Good	100	0	0	1	6
OMN	AP T-HANG	Apron	4305	54,292	AC	31	Very Poor	56	37	7	3	10
OMN	AP T-HANG	Apron	4310	5,932	AC	30	Very Poor	77	23	0	1	2

\* Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.



## 4.2 Summary of Pavement Condition Evaluation Results

### 4.2.1 Network-Level Observations

The PCI assessment for Ormond Beach Municipal Airport (OMN) was performed in April 2022. The overall area-weighted average PCI value of the network was 75, representing a condition rating of Satisfactory. The Taxiway D facility as well as portions of the Taxiway A, Taxiway B, and Taxiway F facilities were not inspected due to an upcoming rehabilitation project was to commence shortly after the time of inspection.

Based on the FAA 5010 Report as of 10/26/2022, the Airport has reported 127,000 operations for 12 months ending 02/08/2018.

### 4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

### Runways

#### *RW 9-27*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 9-27	RUNWAY	2	292,949	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6105	AC	262,949	91	Good
6110	AC	30,000	94	Good


RW 9-27 consists of 2 flexible pavement sections, totaling 292,949 sf. The last major construction date for the branch was 2019, resulting in an area-weighted average age at inspection of 3 years old. Overall, RW 9-27 is in Good condition with an area-weighted average PCI of 91.



### RW 17-35

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 17-35	RUNWAY	3	370,500	70	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 8% Good (86-100 PCI), 92% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6205	AAC	329,912	68	Fair
6210	AAC	10,188	66	Fair
6215	AAC	30,400	91	Good


RW 17-35 consists of 3 flexible pavement sections, totaling 370,500 sf. The last major construction dates range from 2008 to 2019, resulting in an area-weighted average age at inspection of 13 years old. Overall, RW 17-35 is in Fair condition with an area-weighted average PCI of 70.

### Taxiways

#### TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	5	155,987	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
100	AC	123,174	89	Good
102	AC	2,434	91	Good
105	AAC	4,550	91	Good
120	AC	2,519	94	Good
125	AC	23,310	100	Good

TW A consists of 5 flexible pavement sections, totaling 155,987 sf. The last major construction dates range from 2013 to 2022, resulting in an area-weighted average age at inspection of 8 years old. Overall, TW A is in Good condition with an area-weighted average PCI of 91.

### TW E

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW E	TAXIWAY	3	85,361	56	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 34% Good (86-100 PCI), 66% Very Poor (26-40 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
505	AAC	56,507	38	Very Poor
510	AC	26,455	91	Good
515	AC	2,399	94	Good

TW E consists of 3 flexible pavement sections, totaling 85,361 sf. The last major construction dates range from 1990 to 2019, resulting in an area-weighted average age at inspection of 24 years old. Overall, TW E is in Fair condition with an area-weighted average PCI of 56.

### TW F

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW F	TAXIWAY	3	52,701	50	Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 18% Good (86-100 PCI), 82% Very Poor (26-40 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
605	AC	36,880	40	Very Poor
610	AC	9,548	100	Good
650	AC	6,273	35	Very Poor

TW F consists of 3 flexible pavement sections, totaling 52,701 sf. The last major construction dates range from 1984 to 2022, resulting in an area-weighted average age at inspection of 31 years old. Overall, TW F is in Poor condition with an area-weighted average PCI of 50.

### TW G

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW G	TAXIWAY	1	126,774	88	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
700	AC	126,774	88	Good


TW G consists of 1 flexible pavement section, totaling 126,774 sf. The last major construction date for the branch was 2016, resulting in an area-weighted average age at inspection of 6 years old. Overall, TW G is in Good condition with an area-weighted average PCI of 88.

## Taxilanes

### *TL SW*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL SW	TAXILANE	1	17,255	0	Failed

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Failed (0-10 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
2004	PCC	17,255	0	Failed


TL SW consists of 1 rigid pavement section, totaling 17,255 sf. The last major construction date for the branch was 1992, resulting in an area-weighted average age at inspection of 30 years old. Overall, TL SW is in Failed condition with an area-weighted average PCI of 0.

## Aprons

### *AP FBO*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP FBO	APRON	4	343,073	48	Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 4% Good (86-100 PCI), 48% Fair (56-70 PCI), 48% Very Poor (26-40 PCI).






Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4102	AC	22,255	26	Very Poor
4105	AC	164,592	57	Fair
4110	AAC	141,436	36	Very Poor
4115	AC	14,790	100	Good

AP FBO consists of 4 flexible pavement sections, totaling 343,073 sf. The last major construction dates range from 1992 to 2022, resulting in an area-weighted average age at inspection of 29 years old. Overall, AP FBO is in Poor condition with an area-weighted average PCI of 48.

### AP MID

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP MID	APRON	1	44,107	100	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4505	AC	44,107	100	Good

AP MID consists of 1 flexible pavement section, totaling 44,107 sf. The last major construction date for the branch was 2022. Overall, AP MID is in Good condition with an area-weighted average PCI of 100.

### AP RU 17

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU 17	APRON	1	39,883	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5310	AC	39,883	91	Good

AP RU 17 consists of 1 flexible pavement section, totaling 39,883 sf. The last major construction date for the branch was 2016, resulting in an area-weighted average age at inspection of 6 years old. Overall, AP RU 17 is in Good condition with an area-weighted average PCI of 91.

### AP RU 27

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU 27	APRON	1	27,832	87	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5110	AC	27,832	87	Good

AP RU 27 consists of 1 flexible pavement section, totaling 27,832 sf. The last major construction date for the branch was 2013, resulting in an area-weighted average age at inspection of 9 years old. Overall, AP RU 27 is in Good condition with an area-weighted average PCI of 87.

### AP RU 35

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU 35	APRON	1	40,187	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5410	AC	40,187	91	Good

AP RU 35 consists of 1 flexible pavement section, totaling 40,187 sf. The last major construction date for the branch was 2016, resulting in an area-weighted average age at inspection of 6 years old. Overall, AP RU 35 is in Good condition with an area-weighted average PCI of 91.

### AP RU 9

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP RU 9	APRON	1	28,165	91	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
5210	AC	28,165	91	Good

AP RU 9 consists of 1 flexible pavement section, totaling 28,165 sf. The last major construction date for the branch was 2013, resulting in an area-weighted average age at inspection of 9 years old. Overall, AP RU 9 is in Good condition with an area-weighted average PCI of 91.

### AP T-HANG

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP T-HANG	APRON	2	60,224	31	Very Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Very Poor (26-40 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4305	AC	54,292	31	Very Poor
4310	AC	5,932	30	Very Poor

AP T-HANG consists of 2 flexible pavement sections, totaling 60,224 sf. The last major construction dates range from 1984 to 2008, resulting in an area-weighted average age at inspection of 36 years old. Overall, AP T-HANG is in Very Poor condition with an area-weighted average PCI of 31.





# **Chapter 5: SAPMP Customization**



## Chapter 5 – SAPMP Customization

Once the PAVER™ database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

### 5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- » The “Network” field identifies the airport being analyzed;
- » The “Airport Classification” field classifies the Airport according to the type and volume of aircraft traffic;
  - “GA” for General Aviation, community airports
  - “RL” for Regional Relievers
  - “PR” for Primary/Commercial airports
- » The “District” field identifies the FDOT District to which the Airport belongs;
- » The “FAA ADO Area” is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists);
- » The “Inspection Phase” denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- » The “CFASPP Center” identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

### 5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.

### 5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. **The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.** Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.


### 5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into “groups” or “families” according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

### 5.2.3 Branch-Level Pavement Condition Forecast

**Figure 5.2.3** depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.

*Figure 5.2.3: Forecasted Branch-Level Pavement Performance*





### 5.2.4 Section-Level Pavement Condition Forecast

**Table 5.2.4** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

*Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
OMN	RW 9-27	6105	91	89	87	85	84	82	80	79	77	75	74
OMN	RW 9-27	6110	94	92	90	89	87	85	83	82	80	78	76
OMN	RW 17-35	6205	68	66	64	62	60	58	56	54	52	50	48
OMN	RW 17-35	6210	66	64	62	60	58	56	54	52	50	48	46
OMN	RW 17-35	6215	91	89	87	85	83	81	79	77	75	73	71
OMN	TW A	100	89	87	85	83	81	79	78	76	75	73	72
OMN	TW A	102	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A	105	91	88	86	84	82	81	79	77	76	74	73
OMN	TW A	120	94	91	89	87	85	83	82	80	78	77	75
OMN	TW A	125	100	97	95	93	90	88	86	84	83	81	79
OMN	TW A1	110	86	84	82	80	79	77	75	74	73	71	70
OMN	TW A1	112	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A2	115	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A2	117	91	89	87	85	83	81	79	78	76	75	73
OMN	TW B	205	100	97	95	93	90	88	86	84	83	81	79
OMN	TW B	210	86	84	82	80	79	77	75	74	73	71	70
OMN	TW C	305	88	86	84	82	80	79	77	75	74	73	71
OMN	TW D	405	100	97	95	93	90	88	86	84	83	81	79
OMN	TW E	505	38	35	32	30	27	24	22	19	17	14	11
OMN	TW E	510	91	89	87	85	83	81	79	78	76	75	73
OMN	TW E	515	94	91	89	87	85	83	82	80	78	77	75
OMN	TW F	605	40	39	38	37	36	35	34	33	31	30	29
OMN	TW F	610	100	97	95	93	90	88	86	84	83	81	79
OMN	TW F	650	35	34	32	31	30	28	27	25	24	22	20
OMN	TW G	700	88	86	84	82	80	79	77	75	74	73	71
OMN	TW G1	715	91	89	87	85	83	81	79	78	76	75	73
OMN	TW G2	705	88	86	84	82	80	79	77	75	74	73	71
OMN	TW G3	710	89	87	85	83	81	79	78	76	75	73	72
OMN	TW G4	720	91	89	87	85	83	81	79	78	76	75	73
OMN	TL SW	2004	0	0	0	0	0	0	0	0	0	0	0
OMN	TL T-HANG	4410	88	86	84	82	80	79	77	75	74	73	71
OMN	AP FBO	4102	26	25	24	24	23	22	21	20	20	19	18
OMN	AP FBO	4105	57	56	55	54	53	52	51	51	50	49	48
OMN	AP FBO	4110	36	34	32	30	28	26	24	22	20	18	16
OMN	AP FBO	4115	100	97	95	92	90	88	86	84	82	80	78
OMN	AP MID	4505	100	97	95	92	90	88	86	84	82	80	78
OMN	AP RU 17	5310	91	88	86	84	82	80	78	76	75	73	71
OMN	AP RU 27	5110	87	85	82	81	79	77	75	73	72	70	69
OMN	AP RU 35	5410	91	88	86	84	82	80	78	76	75	73	71



## Airport Pavement Evaluation Report


### Statewide Airfield Pavement Management Program

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
OMN	AP RU 9	5210	91	88	86	84	82	80	78	76	75	73	71
OMN	AP T-HANG	4305	31	30	30	29	28	28	27	26	25	24	24
OMN	AP T-HANG	4310	30	29	29	28	27	26	25	25	24	23	22

## 5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.

Figure 5.3 (a): Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds:   >70: Routine Maintenance   55-70: Rehabilitation Eligible   <55: Reconstruction Eligible

*\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.*

Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP

and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

*Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects*

Airfield Pavement Project Type	PCI Requirement
Reconstruction	PCI < 55 (Poor)
Rehabilitation	PCI < 70 (Fair)
Maintenance	N/A

\*Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

*Table 5.3 (b): Critical PCI Values by Branch Use*

Runway	Taxiway	Apron
70	70	70

**Figures 5.3 (b) and 5.3 (c)** depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram,  $PCI < \text{Critical PCI}$





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram,  $PCI \geq \text{Critical PCI}$





## 5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 “Airport Foreign Object Debris (FOD) Management” provides additional guidance for developing and managing an airport FOD program.

### 5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety (“stopgap”) measure. The two (2) types of localized maintenance are described below in further detail.

- » Localized Preventive Maintenance and Repair
  - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- » Localized Stopgap/Safety Maintenance and Repair
  - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

### 5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

#### **AC Crack Sealing**

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

#### **AC Full-Depth Patching**

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

#### **AC Partial-Depth AC Patching**

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

#### **Grinding**

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

#### **Monitor Pavement**

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.

### **PCC Crack Sealing**

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

### **PCC Full-Depth Patching**

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

### **PCC Joint Seal**

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

### **PCC Partial-Depth Patching**

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

### **PCC Slab Replacement**

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

### **Surface Seal**

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

### 5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

**Tables 5.4.3 (a) and (b)** display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

*Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete*

Localized Work Type	General Aviation Costs	Work Type Unit
AC Crack Sealing	\$ 4.00	LF
AC Full-Depth Patching	\$ 10.00	SF
AC Partial-Depth Patching	\$ 4.75	SF
Surface Seal	\$ 0.75	SF

*Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete*

Localized Work Type	General Aviation Costs	Work Type Unit
Grinding	\$ 2.00	SF
PCC Crack Sealing	\$ 7.00	LF
PCC Joint Seal	\$ 4.25	LF
PCC Full-Depth Patching	\$ 50.00	SF
PCC Partial-Depth Patching	\$ 169.00	SF
PCC Slab Replacement	\$ 51.50	SF

\* PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.

### 5.4.4 Localized Maintenance and Repair Policy

**Table 5.4.4** and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.



*Table 5.4.4: AC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy*

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
41	Low	Alligator Cracking	Monitor Pavement	Monitor Pavement
41	Medium	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
41	High	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
42	N/A	Bleeding	Monitor Pavement	Monitor Pavement
43	Low	Block Cracking	Monitor Pavement	Monitor Pavement
43	Medium	Block Cracking	AC Crack Sealing	Monitor Pavement
43	High	Block Cracking	AC Crack Sealing	AC Crack Sealing
44	Low	Corrugation	Monitor Pavement	Monitor Pavement
44	Medium	Corrugation	AC Full Depth Patching	Monitor Pavement
44	High	Corrugation	AC Full Depth Patching	AC Full Depth Patching
45	Low	Depression	Monitor Pavement	Monitor Pavement
45	Medium	Depression	AC Full Depth Patching	Monitor Pavement
45	High	Depression	AC Full Depth Patching	AC Full Depth Patching
46	N/A	Jet Blast	Monitor Pavement	Monitor Pavement
47	Low	Jt. Reflective Cracking	Monitor Pavement	Monitor Pavement
47	Medium	Jt. Reflective Cracking	AC Crack Sealing	Monitor Pavement
47	High	Jt. Reflective Cracking	AC Full Depth Patching	AC Full Depth Patching
48	Low	L&T Cracking	Monitor Pavement	Monitor Pavement
48	Medium	L&T Cracking	AC Crack Sealing	Monitor Pavement
48	High	L&T Cracking	AC Full Depth Patching	AC Full Depth Patching
49	N/A	Oil Spillage	Monitor Pavement	Monitor Pavement
50	Low	Patching	Monitor Pavement	Monitor Pavement
50	Medium	Patching	AC Full Depth Patching	Monitor Pavement
50	High	Patching	AC Full Depth Patching	AC Full Depth Patching
51	N/A	Polished Aggregate	Monitor Pavement	Monitor Pavement
52	Low	Raveling	Surface Seal	Monitor Pavement
52	Medium	Raveling	Surface Seal	Monitor Pavement
52	High	Raveling	AC Partial Depth Patching	AC Partial Depth Patching
53	Low	Rutting	Monitor Pavement	Monitor Pavement
53	Medium	Rutting	AC Full Depth Patching	Monitor Pavement
53	High	Rutting	AC Full Depth Patching	AC Full Depth Patching
54	Low	Shoving	Monitor Pavement	Monitor Pavement
54	Medium	Shoving	AC Partial Depth Patching	Monitor Pavement
54	High	Shoving	AC Full Depth Patching	AC Full Depth Patching
55	N/A	Slippage Cracking	AC Full Depth Patching	AC Full Depth Patching
56	Low	Swelling	Monitor Pavement	Monitor Pavement
56	Medium	Swelling	AC Full Depth Patching	Monitor Pavement
56	High	Swelling	AC Full Depth Patching	AC Full Depth Patching

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
57	Low	Weathering	Monitor Pavement	Monitor Pavement
57	Medium	Weathering	Surface Seal	Monitor Pavement
57	High	Weathering	AC Partial Depth Patching	Surface Seal

*Table 5.4.5: PCC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy*

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
61	Low	Blow-up	PCC Full Depth Patching	Monitor Pavement
61	Medium	Blow-up	PCC Full Depth Patching	PCC Full Depth Patching
61	High	Blow-up	PCC Slab Replacement	PCC Slab Replacement
62	Low	Corner Break	Monitor Pavement	Monitor Pavement
62	Medium	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
62	High	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
63	Low	Linear Cracking	Monitor Pavement	Monitor Pavement
63	Medium	Linear Cracking	PCC Crack Sealing	PCC Crack Sealing
63	High	Linear Cracking	PCC Full Depth Patching	PCC Crack Sealing
64	Low	Durability Cracking	Monitor Pavement	Monitor Pavement
64	Medium	Durability Cracking	PCC Full Depth Patching	PCC Full Depth Patching
64	High	Durability Cracking	PCC Slab Replacement	PCC Slab Replacement
65	Low	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	Medium	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	High	Jt. Seal Damage	PCC Joint Seal	PCC Joint Seal
66	Low	Small Patch	Monitor Pavement	Monitor Pavement
66	Medium	Small Patch	PCC Partial Depth Patching	Monitor Pavement
66	High	Small Patch	PCC Partial Depth Patching	PCC Partial Depth Patching
67	Low	Large Patch	Monitor Pavement	Monitor Pavement
67	Medium	Large Patch	PCC Full Depth Patching	Monitor Pavement
67	High	Large Patch	PCC Full Depth Patching	PCC Full Depth Patching
68	N/A	Popouts	Monitor Pavement	Monitor Pavement
69	N/A	Pumping	Monitor Pavement	Monitor Pavement
70	Low	Scaling	Monitor Pavement	Monitor Pavement
70	Medium	Scaling	PCC Slab Replacement	Monitor Pavement
70	High	Scaling	PCC Slab Replacement	PCC Slab Replacement
71	Low	Faulting	Monitor Pavement	Monitor Pavement
71	Medium	Faulting	Grinding	Monitor Pavement
71	High	Faulting	PCC Slab Replacement	PCC Slab Replacement
72	Low	Shattered Slab	PCC Crack Sealing	Monitor Pavement
72	Medium	Shattered Slab	PCC Slab Replacement	PCC Crack Sealing
72	High	Shattered Slab	PCC Slab Replacement	PCC Slab Replacement
73	N/A	Shrinkage Cracking	Monitor Pavement	Monitor Pavement

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
74	Low	Joint Spall	Monitor Pavement	Monitor Pavement
74	Medium	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
74	High	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	Low	Corner Spall	Monitor Pavement	Monitor Pavement
75	Medium	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	High	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
76	Low	ASR	Monitor Pavement	Monitor Pavement
76	Medium	ASR	PCC Slab Replacement	PCC Slab Replacement
76	High	ASR	PCC Slab Replacement	PCC Slab Replacement

## 5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

### 5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average General Aviation Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

*Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation*

Rehabilitation Type	General Aviation Pavement Section
<b>AC Reconstruction</b>	
<i>Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.</i>  <b>PCI &lt; 55</b>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (6")
	Prime Coat
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
<b>AC Rehabilitation</b>	
<i>Combination of asphalt pavement milling and replacement overlay with 15% of the areas subject to full-depth reconstruction.</i>  <b>PCI = 55 to 70</b>	<b>15% AC Reconstruction</b>
	<b>Mill and Overlay</b>
	AC Milling (3")
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
<b>PCC Reconstruction</b>	
<i>Full-depth rigid pavement section reconstruction.</i>  <b>PCI &lt; 55</b>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (6")
	Limerock Base Course (6")
	P-501 PCC Pavement (8")
	PCC Joint Seal
<b>PCC Rehabilitation</b>	
<i>Rehabilitation of PCC pavement with a combination of crack sealing, joint seal replacement, limited patching, and replacement of 15% of slab panels.</i>  <b>PCI = 55 to 70</b>	<b>15% Slab Replacement</b>
	<b>Joint and Crack Seal</b>
	<b>Limited Patching</b>

*The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.*



### **Reconstruction (AC or PCC)**

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

### **AC Rehabilitation**

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

### **PCC Rehabilitation**

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.


#### **5.5.2 Major Rehabilitation Planning-Level Unit Costs**

Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.


Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.

*Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type*

Rehabilitation Type	PCI Range	Asphalt Concrete Cost per SF	Portland Cement Concrete Cost Per SF
Rehabilitation	55 to 70	\$9.00	\$15.00
Reconstruction	0 to 55	\$16.00	\$29.00



# **Chapter 6: M&R Planning and Budget Scenario Analysis**



# Chapter 6 – M&R Planning and Budget Scenario Analysis

## 6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

**Table 6.1 (a)** provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (a): Year 1 Summary of Localized Maintenance*

Work Category	Cost
Preventive	\$ 12,990
Stopgap	\$ 442,580
<b>Planning-Level Localized M&amp;R Needs =</b>	<b>\$ 455,570</b>

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

**Table 6.1 (b)** summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.



*Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary*

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	Surface Seal	17,206	SF	\$ 12,990
Localized Stopgap Maintenance	AC Full-Depth Patching	9,357	SF	\$ 93,590
	PCC Crack Sealing	882	LF	\$ 6,180
	PCC Joint Seal	682	LF	\$ 2,900
	PCC Slab Replacement	6,600	SF	\$ 339,910

**Table 6.1 (c)** provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved “End Condition” PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary*

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
OMN	RW 9-27	6105	262,949	91	91	\$ -
OMN	RW 9-27	6110	30,000	94	94	\$ -
OMN	RW 17-35	6205	329,912	68	68	\$ -
OMN	RW 17-35	6210	10,188	66	66	\$ -
OMN	RW 17-35	6215	30,400	91	91	\$ -
OMN	TW A	100	123,174	89	90	\$ 850
OMN	TW A	102	2,434	91	94	\$ 100
OMN	TW A	105	4,550	91	94	\$ 180
OMN	TW A	120	2,519	94	94	\$ -
OMN	TW A	125	23,310	100	100	\$ -
OMN	TW A1	110	8,089	86	89	\$ 310
OMN	TW A1	112	3,083	91	94	\$ 120
OMN	TW A2	115	8,054	91	91	\$ -
OMN	TW A2	117	3,118	91	94	\$ 120
OMN	TW B	205	51,318	100	100	\$ -
OMN	TW B	210	7,706	86	89	\$ 290
OMN	TW C	305	35,387	88	93	\$ 2,660
OMN	TW D	405	81,876	100	100	\$ -
OMN	TW E	505	56,507	38	38	\$ -
OMN	TW E	510	26,455	91	91	\$ -
OMN	TW E	515	2,399	94	94	\$ -
OMN	TW F	605	36,880	40	40	\$ -
OMN	TW F	610	9,548	100	100	\$ -
OMN	TW F	650	6,273	35	35	\$ -
OMN	TW G	700	126,774	88	90	\$ 2,630
OMN	TW G1	715	8,543	91	94	\$ 330
OMN	TW G2	705	8,946	88	92	\$ 340



Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
OMN	TW G3	710	8,941	89	94	\$ 680
OMN	TW G4	720	8,529	91	94	\$ 320
OMN	TL SW	2004	17,255	0	54	\$ 348,980
OMN	TL T-HANG	4410	57,362	88	88	\$ -
OMN	AP FBO	4102	22,255	26	26	\$ -
OMN	AP FBO	4105	164,592	57	57	\$ -
OMN	AP FBO	4110	141,436	36	42	\$ 57,300
OMN	AP FBO	4115	14,790	100	100	\$ -
OMN	AP MID	4505	44,107	100	100	\$ -
OMN	AP RU 17	5310	39,883	91	94	\$ 1,500
OMN	AP RU 27	5110	27,832	87	90	\$ 1,050
OMN	AP RU 35	5410	40,187	91	94	\$ 1,510
OMN	AP RU 9	5210	28,165	91	91	\$ -
OMN	AP T-HANG	4305	54,292	31	39	\$ 35,330
OMN	AP T-HANG	4310	5,932	30	35	\$ 960

## 6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b) and (c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

### 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- » An estimation of current pavement condition;
- » Major pavement rehabilitation needs based on condition and policies; and
- » Planning-level cost estimates for the major rehabilitation needs.


**Table 6.2.1 (a)** summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.


*Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	OMN	RW 17-35	6205	AAC	329,912	66	AC Rehabilitation	\$ 2,970,000
2023	OMN	RW 17-35	6210	AAC	10,188	64	AC Rehabilitation	\$ 92,000
2023	OMN	TW E	505	AAC	56,507	35	AC Reconstruction	\$ 905,000
2023	OMN	TW F	605	AC	36,880	39	AC Reconstruction	\$ 591,000
2023	OMN	TW F	650	AC	6,273	34	AC Reconstruction	\$ 101,000
2023	OMN	TL SW	2004	PCC	17,255	0	PCC Reconstruction	\$ 501,000
2023	OMN	AP FBO	4102	AC	22,255	25	AC Reconstruction	\$ 357,000
2023	OMN	AP FBO	4105	AC	164,592	56	AC Rehabilitation	\$ 1,482,000
2023	OMN	AP FBO	4110	AAC	141,436	34	AC Reconstruction	\$ 2,263,000
2023	OMN	AP T-HANG	4305	AC	54,292	30	AC Reconstruction	\$ 869,000
2023	OMN	AP T-HANG	4310	AC	5,932	29	AC Reconstruction	\$ 95,000
2032	OMN	AP RU 27	5110	AC	27,832	69	AC Rehabilitation	\$ 389,000

**Figure 6.2.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

*Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year*









# Chapter 7: Conclusion



## Chapter 7 – Conclusion

### 7.1 Recommendations

#### 7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

#### 7.1.3 Major Rehabilitation

**Chapter 6** also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

#### 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- » Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in **Section 6.1**;
- » Further refine and implement the identified 10-year major rehabilitation needs provided in **Section 6.2**;
- » Maintain detailed records on pavement maintenance, construction, and inspection; and
- » Maintain records on major pavement construction projects (year, scope, cost, and construction documents).

## 7.2 Supporting Documents

### Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

### Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

### Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

### Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

### Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

### Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.



## 7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

## 7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- » ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- » AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- » AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- » AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- » Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- » Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- » Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.



A photograph of a long, straight asphalt runway stretching towards the horizon under a bright blue sky with scattered white clouds. The runway has a central white dashed line and yellow edge lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Appendix A: Airfield Pavement Analysis**

A close-up, low-angle view of the runway pavement, showing a white dashed line and yellow chevron markings. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

*Table A.1: Pavement System Inventory Details*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
OMN	RW 9-27	Runway	6105	262,949	AC	7/1/2019
OMN	RW 9-27	Runway	6110	30,000	AC	7/1/2019
OMN	RW 17-35	Runway	6205	329,912	AAC	1/1/2008
OMN	RW 17-35	Runway	6210	10,188	AAC	1/1/2008
OMN	RW 17-35	Runway	6215	30,400	AAC	7/1/2019
OMN	TW A	Taxiway	100	123,174	AC	1/1/2013
OMN	TW A	Taxiway	102	2,434	AC	1/1/2019
OMN	TW A	Taxiway	105	4,550	AAC	1/1/2016
OMN	TW A	Taxiway	120	2,519	AC	7/1/2019
OMN	TW A	Taxiway	125	23,310	AAC	5/1/2022
OMN	TW A1	Taxiway	110	8,089	AC	1/1/2013
OMN	TW A1	Taxiway	112	3,083	AC	7/1/2019
OMN	TW A2	Taxiway	115	8,054	AC	1/1/2013
OMN	TW A2	Taxiway	117	3,118	AC	7/1/2019
OMN	TW B	Taxiway	205	51,318	AC	5/1/2022
OMN	TW B	Taxiway	210	7,706	AC	1/1/2013
OMN	TW C	Taxiway	305	35,387	AC	1/1/2013
OMN	TW D	Taxiway	405	81,876	AC	5/1/2022
OMN	TW E	Taxiway	505	56,507	AAC	1/1/1990
OMN	TW E	Taxiway	510	26,455	AC	1/1/2013
OMN	TW E	Taxiway	515	2,399	AC	7/1/2019
OMN	TW F	Taxiway	605	36,880	AC	1/1/1984
OMN	TW F	Taxiway	610	9,548	AAC	5/1/2022
OMN	TW F	Taxiway	650	6,273	AC	1/1/1984
OMN	TW G	Taxiway	700	126,774	AC	1/1/2016
OMN	TW G1	Taxiway	715	8,543	AC	1/1/2016
OMN	TW G2	Taxiway	705	8,946	AC	1/1/2016
OMN	TW G3	Taxiway	710	8,941	AC	1/1/2016
OMN	TW G4	Taxiway	720	8,529	AC	1/1/2016
OMN	TL SW	Taxilane	2004	17,255	PCC	1/1/1992
OMN	TL T-HANG	Taxilane	4410	57,362	AC	1/1/2005
OMN	AP FBO	Apron	4102	22,255	AC	1/1/1992
OMN	AP FBO	Apron	4105	164,592	AC	1/1/1992
OMN	AP FBO	Apron	4110	141,436	AAC	1/1/1992
OMN	AP FBO	Apron	4115	14,790	AC	5/1/2022
OMN	AP MID	Apron	4505	44,107	AC	5/1/2022
OMN	AP RU 17	Apron	5310	39,883	AC	1/1/2016
OMN	AP RU 27	Apron	5110	27,832	AC	1/1/2013
OMN	AP RU 35	Apron	5410	40,187	AC	1/1/2016
OMN	AP RU 9	Apron	5210	28,165	AC	1/1/2013
OMN	AP T-HANG	Apron	4305	54,292	AC	1/1/1984
OMN	AP T-HANG	Apron	4310	5,932	AC	7/31/2008

*Table A.2: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
OMN	RW 9-27	Runway	6105	262,949	91	Good
OMN	RW 9-27	Runway	6110	30,000	94	Good
OMN	RW 17-35	Runway	6205	329,912	68	Fair
OMN	RW 17-35	Runway	6210	10,188	66	Fair
OMN	RW 17-35	Runway	6215	30,400	91	Good
OMN	TW A	Taxiway	100	123,174	89	Good
OMN	TW A	Taxiway	102	2,434	91	Good
OMN	TW A	Taxiway	105	4,550	91	Good
OMN	TW A	Taxiway	120	2,519	94	Good
OMN	TW A	Taxiway	125	23,310	100	Good
OMN	TW A1	Taxiway	110	8,089	86	Good
OMN	TW A1	Taxiway	112	3,083	91	Good
OMN	TW A2	Taxiway	115	8,054	91	Good
OMN	TW A2	Taxiway	117	3,118	91	Good
OMN	TW B	Taxiway	205	51,318	100	Good
OMN	TW B	Taxiway	210	7,706	86	Good
OMN	TW C	Taxiway	305	35,387	88	Good
OMN	TW D	Taxiway	405	81,876	100	Good
OMN	TW E	Taxiway	505	56,507	38	Very Poor
OMN	TW E	Taxiway	510	26,455	91	Good
OMN	TW E	Taxiway	515	2,399	94	Good
OMN	TW F	Taxiway	605	36,880	40	Very Poor
OMN	TW F	Taxiway	610	9,548	100	Good
OMN	TW F	Taxiway	650	6,273	35	Very Poor
OMN	TW G	Taxiway	700	126,774	88	Good
OMN	TW G1	Taxiway	715	8,543	91	Good
OMN	TW G2	Taxiway	705	8,946	88	Good
OMN	TW G3	Taxiway	710	8,941	89	Good
OMN	TW G4	Taxiway	720	8,529	91	Good
OMN	TL SW	Taxilane	2004	17,255	0	Failed
OMN	TL T-HANG	Taxilane	4410	57,362	88	Good
OMN	AP FBO	Apron	4102	22,255	26	Very Poor
OMN	AP FBO	Apron	4105	164,592	57	Fair
OMN	AP FBO	Apron	4110	141,436	36	Very Poor
OMN	AP FBO	Apron	4115	14,790	100	Good
OMN	AP MID	Apron	4505	44,107	100	Good
OMN	AP RU 17	Apron	5310	39,883	91	Good
OMN	AP RU 27	Apron	5110	27,832	87	Good
OMN	AP RU 35	Apron	5410	40,187	91	Good
OMN	AP RU 9	Apron	5210	28,165	91	Good
OMN	AP T-HANG	Apron	4305	54,292	31	Very Poor
OMN	AP T-HANG	Apron	4310	5,932	30	Very Poor



*Table A.3: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
OMN	RW 9-27	6105	91	89	87	85	84	82	80	79	77	75	74
OMN	RW 9-27	6110	94	92	90	89	87	85	83	82	80	78	76
OMN	RW 17-35	6205	68	66	64	62	60	58	56	54	52	50	48
OMN	RW 17-35	6210	66	64	62	60	58	56	54	52	50	48	46
OMN	RW 17-35	6215	91	89	87	85	83	81	79	77	75	73	71
OMN	TW A	100	89	87	85	83	81	79	78	76	75	73	72
OMN	TW A	102	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A	105	91	88	86	84	82	81	79	77	76	74	73
OMN	TW A	120	94	91	89	87	85	83	82	80	78	77	75
OMN	TW A	125	100	97	95	93	90	88	86	84	83	81	79
OMN	TW A1	110	86	84	82	80	79	77	75	74	73	71	70
OMN	TW A1	112	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A2	115	91	89	87	85	83	81	79	78	76	75	73
OMN	TW A2	117	91	89	87	85	83	81	79	78	76	75	73
OMN	TW B	205	100	97	95	93	90	88	86	84	83	81	79
OMN	TW B	210	86	84	82	80	79	77	75	74	73	71	70
OMN	TW C	305	88	86	84	82	80	79	77	75	74	73	71
OMN	TW D	405	100	97	95	93	90	88	86	84	83	81	79
OMN	TW E	505	38	35	32	30	27	24	22	19	17	14	11
OMN	TW E	510	91	89	87	85	83	81	79	78	76	75	73
OMN	TW E	515	94	91	89	87	85	83	82	80	78	77	75
OMN	TW F	605	40	39	38	37	36	35	34	33	31	30	29
OMN	TW F	610	100	97	95	93	90	88	86	84	83	81	79
OMN	TW F	650	35	34	32	31	30	28	27	25	24	22	20
OMN	TW G	700	88	86	84	82	80	79	77	75	74	73	71
OMN	TW G1	715	91	89	87	85	83	81	79	78	76	75	73
OMN	TW G2	705	88	86	84	82	80	79	77	75	74	73	71
OMN	TW G3	710	89	87	85	83	81	79	78	76	75	73	72
OMN	TW G4	720	91	89	87	85	83	81	79	78	76	75	73
OMN	TL SW	2004	0	0	0	0	0	0	0	0	0	0	0
OMN	TL T-HANG	4410	88	86	84	82	80	79	77	75	74	73	71
OMN	AP FBO	4102	26	25	24	24	23	22	21	20	20	19	18
OMN	AP FBO	4105	57	56	55	54	53	52	51	51	50	49	48
OMN	AP FBO	4110	36	34	32	30	28	26	24	22	20	18	16
OMN	AP FBO	4115	100	97	95	92	90	88	86	84	82	80	78
OMN	AP MID	4505	100	97	95	92	90	88	86	84	82	80	78
OMN	AP RU 17	5310	91	88	86	84	82	80	78	76	75	73	71
OMN	AP RU 27	5110	87	85	82	81	79	77	75	73	72	70	69
OMN	AP RU 35	5410	91	88	86	84	82	80	78	76	75	73	71
OMN	AP RU 9	5210	91	88	86	84	82	80	78	76	75	73	71
OMN	AP T-HANG	4305	31	30	30	29	28	28	27	26	25	24	24
OMN	AP T-HANG	4310	30	29	29	28	27	26	25	25	24	23	22



11/17/2022

## Work History Report

Page 1 of 8

Pavement Database: FDOT

<b>Network:</b> ORMOND BEACH <b>Branch:</b> AP FBO    FBO APRON <b>Section:</b> 4102 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/1992 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 670.00 (Ft) <b>Width:</b> 34.00 (Ft) <b>True Area:</b> 22255.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1992: 2" P-401 ON 6" RECLAIMED PAVEMENT BASE. SOIL: SP.

<b>Network:</b> ORMOND BEACH <b>Branch:</b> AP FBO    FBO APRON <b>Section:</b> 4105 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/1992 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 835.00 (Ft) <b>Width:</b> 180.00 (Ft) <b>True Area:</b> 164592.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1992: SEAL ON 2" P-401 ON 6" RECLAIMED PAVEMENT BASE. S

<b>Network:</b> ORMOND BEACH <b>Branch:</b> AP FBO    FBO APRON <b>Section:</b> 4110 <b>Surface:</b> AAC <b>L.C.D.</b> 1/1/1992 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 600.00 (Ft) <b>Width:</b> 218.00 (Ft) <b>True Area:</b> 141436.0000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	28,287.20	0.00	<input type="checkbox"/>	1992: AC OVERLAY
1/1/1992	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1979	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	1979: 1" TYPE S1 AC OVERLAY PLACED ON EXISTING AC ON BA

<b>Network:</b> ORMOND BEACH <b>Branch:</b> AP FBO    FBO APRON <b>Section:</b> 4115 <b>Surface:</b> AC <b>L.C.D.</b> 5/1/2022 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 435.00 (Ft) <b>Width:</b> 34.00 (Ft) <b>True Area:</b> 14790.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2022	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1984: 3" RECYCLED HOT MIX AC. SOIL SP. 1943: 1" BITUMINOUS SURFACE ON 6" LIME ROCK BASE
1/1/1984	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	

<b>Network:</b> ORMOND BEACH <b>Branch:</b> AP MID    MID-FIELD APR <b>Section:</b> 4505 <b>Surface:</b> AC <b>L.C.D.</b> 5/1/2022 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 439.00 (Ft) <b>Width:</b> 115.00 (Ft) <b>True Area:</b> 44107.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2022	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> ORMOND BEACH <b>Branch:</b> AP RU 17    RUN-UP APRON <b>Section:</b> 5310 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2016 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 385.00 (Ft) <b>Width:</b> 105.00 (Ft) <b>True Area:</b> 39883.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> ORMOND BEACH <b>Branch:</b> AP RU 27    RUN-UP APRON <b>Section:</b> 5110 <b>Surface:</b> AC <b>L.C.D.</b> 1/1/2013 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 250.00 (Ft) <b>Width:</b> 125.00 (Ft) <b>True Area:</b> 27832.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152

11/17/2022

## Work History Report

Page 2 of 8

Pavement Database: FDOT

Network: ORMOND BEACH		Branch: AP RU 35	RUN-UP APRON	Section: 5410	Surface: AC	
L.C.D. 1/1/2016	Use: APRON	Rank: P	Length: 385.00 (Ft)	Width: 105.00 (Ft)	True Area: 40187.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: AP RU 9	RUN-UP APRON	Section: 5210	Surface: AC	
L.C.D. 1/1/2013	Use: APRON	Rank: P	Length: 300.00 (Ft)	Width: 100.00 (Ft)	True Area: 28165.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152

Network: ORMOND BEACH		Branch: AP T-HANG	T-HANGAR APR	Section: 4305	Surface: AC	
L.C.D. 1/1/1984	Use: APRON	Rank: P	Length: 342.00 (Ft)	Width: 140.00 (Ft)	True Area: 54292.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	10,858.40	0.00	<input type="checkbox"/>	ESTIMATE 1984 AC PAVEMENT. SOIL: SP.
1/1/1984	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: AP T-HANG	T-HANGAR APR	Section: 4310	Surface: AC	
L.C.D. 7/31/2008	Use: APRON	Rank: P	Length: 285.00 (Ft)	Width: 22.00 (Ft)	True Area: 5932.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	1,186.40	0.00	<input type="checkbox"/>	
7/31/2008	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: RW 17-35	RUNWAY 17-35	Section: 6205	Surface: AAC	
L.C.D. 1/1/2008	Use: RUNWAY	Rank: P	Length: 3,300.00 (Ft)	Width: 100.00 (Ft)	True Area: 329912.0001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1983: 2.5" P-401 ON 1" - 3.5" LEVELING COURSE 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS
1/1/1983	IMPORT ED	OVERLAY	0.00	2.50	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: RW 17-35	RUNWAY 17-35	Section: 6210	Surface: AAC	
L.C.D. 1/1/2008	Use: RUNWAY	Rank: P	Length: 100.00 (Ft)	Width: 100.00 (Ft)	True Area: 10188.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME: 1973 AC OVERLAY 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS
1/1/1973	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	

11/17/2022

## Work History Report

Page 3 of 8

Pavement Database: FDOT

Network: ORMOND BEACH		Branch: RW 17-35	RUNWAY 17-35		Section: 6215	Surface: AAC
L.C.D. 7/1/2019	Use: RUNWAY	Rank: P	Length: 300.00 (Ft)	Width: 100.00 (Ft)	True Area: 30400.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" Mill, 2" P-401 Overlay
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME: 1973 AC OVERLAY
1/1/1973	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	
						1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS

Network: ORMOND BEACH		Branch: RW 9-27	RUNWAY 9-27		Section: 6105	Surface: AC
L.C.D. 7/1/2019	Use: RUNWAY	Rank: P	Length: 3,506.00 (Ft)	Width: 75.00 (Ft)	True Area: 262949.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" min P-211 (scarify 3" of 1977: VARIABLE THICKNESS TYPE 1 ASPHALT CONCRETE 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS
1/1/1977	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: RW 9-27	RUNWAY 9-27		Section: 6110	Surface: AC
L.C.D. 7/1/2019	Use: RUNWAY	Rank: P	Length: 400.00 (Ft)	Width: 75.00 (Ft)	True Area: 30000.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" P-403, 12" P-152 1977: VARIABLE THICKNESS TYPE 1 ASPHALT CONCRETE 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS
1/1/1977	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: TL SW	SOUTHWEST TA		Section: 2004	Surface: PCC
L.C.D. 1/1/1992	Use: TAXILAN	Rank: P	Length: 640.00 (Ft)	Width: 22.00 (Ft)	True Area: 17255.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1992	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: TL T-HANG	T-HANGAR TAX		Section: 4410	Surface: AC
L.C.D. 1/1/2005	Use: TAXILAN	Rank: P	Length: 1,635.00 (Ft)	Width: 25.00 (Ft)	True Area: 57362.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2022	ST-SC	Surface Treatment - Seal Coat	11,472.40	0.00	<input type="checkbox"/>	
1/1/2005	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: TW A	TAXIWAY A		Section: 100	Surface: AC
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 3,419.00 (Ft)	Width: 35.00 (Ft)	True Area: 123174.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152

11/17/2022

## Work History Report

Page 4 of 8

Pavement Database: FDOT

Network: ORMOND BEACH		Branch: TW A	TAXIWAY A		Section: 102	Surface: AC
L.C.D. 1/1/2019	Use: TAXIWAY	Rank: P	Length: 51.00 (Ft)	Width: 48.00 (Ft)	True Area: 2434.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2019	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: TW A	TAXIWAY A		Section: 105	Surface: AAC
L.C.D. 1/1/2016	Use: TAXIWAY	Rank: P	Length: 130.00 (Ft)	Width: 35.00 (Ft)	True Area: 4550.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2" MILL, P-401 OVERLAY
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152

Network: ORMOND BEACH		Branch: TW A1	TAXIWAY A1		Section: 110	Surface: AC
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 194.00 (Ft)	Width: 40.00 (Ft)	True Area: 8089.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152

Network: ORMOND BEACH		Branch: TW A1	TAXIWAY A1		Section: 112	Surface: AC
L.C.D. 7/1/2019	Use: TAXIWAY	Rank: P	Length: 51.00 (Ft)	Width: 60.00 (Ft)	True Area: 3083.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: TW A	TAXIWAY A		Section: 120	Surface: AC
L.C.D. 7/1/2019	Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 35.00 (Ft)	True Area: 2519.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
7/1/2019	CR-AC	Complete Reconstruction - AC	12,595.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: TW A	TAXIWAY A		Section: 125	Surface: AC
L.C.D. 5/1/2022	Use: TAXIWAY	Rank: P	Length: 666.00 (Ft)	Width: 35.00 (Ft)	True Area: 23310.000000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2022	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: ORMOND BEACH		Branch: TW A2	TAXIWAY A2		Section: 115	Surface: AC
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 193.00 (Ft)	Width: 40.00 (Ft)	True Area: 8054.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152



11/17/2022

## Work History Report

Page 5 of 8

Pavement Database: FDOT

<b>Network:</b> ORMOND BEACH		<b>Branch:</b> TW A2		TAXIWAY A2		<b>Section:</b> 117	<b>Surface:</b> AC
<b>L.C.D.</b> 7/1/2019	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 52.00 (Ft)	<b>Width:</b> 60.00 (Ft)	<b>True Area:</b> 3118.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
7/1/2019	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152	
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

<b>Network:</b> ORMOND BEACH		<b>Branch:</b> TW B		TAXIWAY B		<b>Section:</b> 205	<b>Surface:</b> AC
<b>L.C.D.</b> 5/1/2022	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 490.00 (Ft)	<b>Width:</b> 65.00 (Ft)	<b>True Area:</b> 51318.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
5/1/2022	CR-AC	Complete Reconstruction - AC	256,590.00	0.00	<input checked="" type="checkbox"/>	1977: TYPE 1 ASPHALT CONCRETE (NO THICKNESS INFO). 1943: 1" DOUBLE BITUMINOUS SURFACE ON 6" LIME ROCK BAS	
1/1/1977	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

<b>Network:</b> ORMOND BEACH		<b>Branch:</b> TW B		TAXIWAY B		<b>Section:</b> 210	<b>Surface:</b> AC
<b>L.C.D.</b> 1/1/2013	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 107.00 (Ft)	<b>Width:</b> 35.00 (Ft)	<b>True Area:</b> 7706.000002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	1977: AC OVERLAY (NO THICKNESS INFO) 1943: 1" AC SURFACE ON 6" LIME ROCK BASE	
1/1/1977	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

<b>Network:</b> ORMOND BEACH		<b>Branch:</b> TW C		TAXIWAY C		<b>Section:</b> 305	<b>Surface:</b> AC
<b>L.C.D.</b> 1/1/2013	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 885.00 (Ft)	<b>Width:</b> 35.00 (Ft)	<b>True Area:</b> 35387.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	2" P401, 6" P211, 12" P152	
1/2/1990	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1990	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" P-401 OVERLAY PLACED ON EXISTING 6" AC ON 6" CRUSH	

<b>Network:</b> ORMOND BEACH		<b>Branch:</b> TW D		TAXIWAY D		<b>Section:</b> 405	<b>Surface:</b> AC
<b>L.C.D.</b> 5/1/2022	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 1,722.00 (Ft)	<b>Width:</b> 35.00 (Ft)	<b>True Area:</b> 81876.00002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
5/1/2022	CR-AC	Complete Reconstruction - AC	409,380.00	0.00	<input checked="" type="checkbox"/>	1984: 3" RECYCLED HOT MIX AC. SOIL SP. 1943: 1" BITUMINOUS SURFACE ON 6" LIME ROCK BASE	
1/1/1984	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

11/17/2022

## Work History Report

Page 6 of 8

Pavement Database: FDOT

Network: ORMOND BEACH		Branch: TW E		TAXIWAY E		Section: 505	Surface: AAC
L.C.D. 1/1/1990	Use: TAXIWAY	Rank: P	Length: 2,060.00 (Ft)	Width: 35.00 (Ft)	True Area: 56507.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1990	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1990: 2" P-401 OVERLAY. SOIL: SP.	
1/1/1943	IMPORT ED	BUILT	0.00	4.50	<input checked="" type="checkbox"/>	1943: 4.5" AC ON 5" TAN SHELL ON 6" DARK GREY SAND	

Network: ORMOND BEACH		Branch: TW E		TAXIWAY E		Section: 510	Surface: AC
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 745.00 (Ft)	Width: 35.00 (Ft)	True Area: 26455.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152	

Network: ORMOND BEACH		Branch: TW E		TAXIWAY E		Section: 515	Surface: AC
L.C.D. 7/1/2019	Use: TAXIWAY	Rank: P	Length: 50.00 (Ft)	Width: 35.00 (Ft)	True Area: 2399.000000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
7/1/2019	CR-AC	Complete Reconstruction - AC	11,995.00	0.00	<input checked="" type="checkbox"/>		
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P401, 6" P211, 12" P152	

Network: ORMOND BEACH		Branch: TW F		TAXIWAY F		Section: 605	Surface: AC
L.C.D. 1/1/1984	Use: TAXIWAY	Rank: P	Length: 922.00 (Ft)	Width: 40.00 (Ft)	True Area: 36880.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1984: 2" RECYCLED HOT MIX ON 6" LIME ROCK BASE ON 2" WORK	

Network: ORMOND BEACH		Branch: TW F		TAXIWAY F		Section: 610	Surface: AC
L.C.D. 5/1/2022	Use: TAXIWAY	Rank: P	Length: 117.00 (Ft)	Width: 40.00 (Ft)	True Area: 9548.000002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
5/1/2022	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1984	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1984: 2" RECYCLED HOT MIX ON 6" LIME ROCK BASE ON 2" WORK	

Network: ORMOND BEACH		Branch: TW F		TAXIWAY F		Section: 650	Surface: AC
L.C.D. 1/1/1984	Use: TAXIWAY	Rank: P	Length: 130.00 (Ft)	Width: 40.00 (Ft)	True Area: 6273.000001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1984	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1984: 2" RECYCLED HOT MIX ON 6" LIME ROCK BASE ON 2" WORK	

Network: ORMOND BEACH		Branch: TW G1		TAXIWAY G1		Section: 715	Surface: AC
L.C.D. 1/1/2016	Use: TAXIWAY	Rank: P	Length: 232.00 (Ft)	Width: 35.00 (Ft)	True Area: 8543.000002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>		

11/17/2022

**Work History Report**

Page 7 of 8

*Pavement Database: FDOT*

**Network:** ORMOND BEACH    **Branch:** TW G2    **TAXIWAY** G2    **Section:** 705    **Surface:** AC  
**L.C.D.** 1/1/2016    **Use:** TAXIWAY    **Rank:** P    **Length:** 232.00 (Ft)    **Width:** 35.00 (Ft)    **True Area:** 8946.000002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

**Network:** ORMOND BEACH    **Branch:** TW G3    **TAXIWAY** G3    **Section:** 710    **Surface:** AC  
**L.C.D.** 1/1/2016    **Use:** TAXIWAY    **Rank:** P    **Length:** 232.00 (Ft)    **Width:** 35.00 (Ft)    **True Area:** 8941.000002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

**Network:** ORMOND BEACH    **Branch:** TW G4    **TAXIWAY** G4    **Section:** 720    **Surface:** AC  
**L.C.D.** 1/1/2016    **Use:** TAXIWAY    **Rank:** P    **Length:** 232.00 (Ft)    **Width:** 35.00 (Ft)    **True Area:** 8529.000002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

**Network:** ORMOND BEACH    **Branch:** TW G    **TAXIWAY** G    **Section:** 700    **Surface:** AC  
**L.C.D.** 1/1/2016    **Use:** TAXIWAY    **Rank:** P    **Length:** 3,580.00 (Ft)    **Width:** 35.00 (Ft)    **True Area:** 126774.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2016	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

**Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	18	1,346,309.00	1.47	0.92
Complete Reconstruction - AC	14	530,437.00	0.00	0.00
Mill and Overlay	5	405,450.00	0.00	0.00
New Construction - AC	9	343,272.00	0.00	0.00
New Construction - Initial	15	286,369.00	0.00	0.00
OVERLAY	11	1,017,082.00	0.95	1.29
Overlay - AC Structural	1	35,387.00	0.00	0.00
Surface Treatment - Seal Coat	4	259,022.00	0.00	0.00



11/17/2022

**Branch Condition Report**

Page 1 of 2

*Pavement Database: FDOT*

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP FBO	4	2,540.00	116.50	343,073.00	APRON	54.75	28.42	48.19
AP MID	1	439.00	115.00	44,107.00	APRON	100.00	0.00	100.00
AP RU 17	1	385.00	105.00	39,883.00	APRON	91.00	0.00	91.00
AP RU 27	1	250.00	125.00	27,832.00	APRON	87.00	0.00	87.00
AP RU 35	1	385.00	105.00	40,187.00	APRON	91.00	0.00	91.00
AP RU 9	1	300.00	100.00	28,165.00	APRON	91.00	0.00	91.00
AP T-HANG	2	627.00	81.00	60,224.00	APRON	30.50	0.50	30.90
RW 17-35	3	3,700.00	100.00	370,500.00	RUNWAY	75.00	11.34	69.83
RW 9-27	2	3,906.00	75.00	292,949.00	RUNWAY	92.50	1.50	91.31
TL SW	1	640.00	22.00	17,255.00	TAXILANE	0.00	0.00	0.00
TL T-HANG	1	1,635.00	25.00	57,362.00	TAXILANE	88.00	0.00	88.00
TW A	5	4,316.00	37.60	155,987.00	TAXIWAY	93.00	3.85	90.81
TW A1	2	245.00	50.00	11,172.00	TAXIWAY	88.50	2.50	87.38
TW A2	2	245.00	50.00	11,172.00	TAXIWAY	91.00	0.00	91.00
TW B	2	597.00	50.00	59,024.00	TAXIWAY	93.00	7.00	98.17
TW C	1	885.00	35.00	35,387.00	TAXIWAY	88.00	0.00	88.00
TW D	1	1,722.00	35.00	81,876.00	TAXIWAY	100.00	0.00	100.00
TW E	3	2,855.00	35.00	85,361.00	TAXIWAY	74.33	25.72	56.00
TW F	3	1,169.00	40.00	52,701.00	TAXIWAY	58.33	29.53	50.28
TW G	1	3,580.00	35.00	126,774.00	TAXIWAY	88.00	0.00	88.00
TW G1	1	232.00	35.00	8,543.00	TAXIWAY	91.00	0.00	91.00
TW G2	1	232.00	35.00	8,946.00	TAXIWAY	88.00	0.00	88.00
TW G3	1	232.00	35.00	8,941.00	TAXIWAY	89.00	0.00	89.00
TW G4	1	232.00	35.00	8,529.00	TAXIWAY	91.00	0.00	91.00

**11/17/2022****Branch Condition Report****Page 2 of 2***Pavement Database: FDOT*

<b>Use Category</b>	<b>Number of Sections</b>	<b>Total Area (SqFt)</b>	<b>Arithmetic Average PCI</b>	<b>Average STD PCI</b>	<b>Weighted Average PCI</b>
APRON	11	583,471.00	67.27	29.71	60.11
RUNWAY	5	663,449.00	82.00	12.31	79.31
TAXILANE	2	74,617.00	44.00	44.00	67.65
TAXIWAY	24	654,413.00	85.13	18.42	84.01
ALL	42	1,975,950.00	78.12	25.52	74.76

Pavement Database: FDOT

NetworkId: OMN

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP FBO	4102	1/1/1992	AC	APRON	P	0	22,255.00	4/25/2022	30	26
AP FBO	4105	1/1/1992	AC	APRON	P	0	164,592.00	4/25/2022	30	57
AP FBO	4110	1/1/1992	AAC	APRON	P	0	141,436.00	4/25/2022	30	36
AP FBO	4115	5/1/2022	AC	APRON	P	0	14,790.00	5/1/2022	0	100
AP MID	4505	5/1/2022	AC	APRON	P	0	44,107.00	5/1/2022	0	100
AP RU 17	5310	1/1/2016	AC	APRON	P	0	39,883.00	4/25/2022	6	91
AP RU 27	5110	1/1/2013	AC	APRON	P	0	27,832.00	4/25/2022	9	87
AP RU 35	5410	1/1/2016	AC	APRON	P	0	40,187.00	4/25/2022	6	91
AP RU 9	5210	1/1/2013	AC	APRON	P	0	28,165.00	4/25/2022	9	91
AP T-HANG	4305	1/1/1984	AC	APRON	P	0	54,292.00	4/25/2022	38	31
AP T-HANG	4310	7/31/2008	AC	APRON	P	0	5,932.00	4/25/2022	14	30
RW 17-35	6205	1/1/2008	AAC	RUNWAY	P	0	329,912.00	4/25/2022	14	68
RW 17-35	6210	1/1/2008	AAC	RUNWAY	P	0	10,188.00	4/25/2022	14	66
RW 17-35	6215	7/1/2019	AAC	RUNWAY	P	0	30,400.00	4/25/2022	3	91
RW 9-27	6105	7/1/2019	AC	RUNWAY	P	0	262,949.00	4/25/2022	3	91
RW 9-27	6110	7/1/2019	AC	RUNWAY	P	0	30,000.00	4/25/2022	3	94
TL SW	2004	1/1/1992	PCC	TAXILANE	P	0	17,255.00	4/25/2022	30	0
TL T-HANG	4410	1/1/2005	AC	TAXILANE	P	0	57,362.00	4/25/2022	17	88
TW A	100	1/1/2013	AC	TAXIWAY	P	0	123,174.00	4/25/2022	9	89
TW A	102	1/1/2019	AC	TAXIWAY	P	0	2,434.00	4/25/2022	3	91
TW A	105	1/1/2016	AAC	TAXIWAY	P	0	4,550.00	4/25/2022	6	91
TW A	120	7/1/2019	AC	TAXIWAY	P	0	2,519.00	4/25/2022	3	94
TW A	125	5/1/2022	AC	TAXIWAY	P	0	23,310.00	5/1/2022	0	100
TW A1	110	1/1/2013	AC	TAXIWAY	P	0	8,089.00	4/25/2022	9	86
TW A1	112	7/1/2019	AC	TAXIWAY	P	0	3,083.00	4/25/2022	3	91
TW A2	115	1/1/2013	AC	TAXIWAY	P	0	8,054.00	4/25/2022	9	91
TW A2	117	7/1/2019	AC	TAXIWAY	P	0	3,118.00	4/25/2022	3	91
TW B	205	5/1/2022	AC	TAXIWAY	P	0	51,318.00	5/1/2022	0	100
TW B	210	1/1/2013	AC	TAXIWAY	P	0	7,706.00	4/25/2022	9	86
TW C	305	1/1/2013	AC	TAXIWAY	P	0	35,387.00	4/25/2022	9	88
TW D	405	5/1/2022	AC	TAXIWAY	P	0	81,876.00	5/1/2022	0	100
TW E	505	1/1/1990	AAC	TAXIWAY	P	0	56,507.00	4/25/2022	32	38
TW E	510	1/1/2013	AC	TAXIWAY	P	0	26,455.00	4/25/2022	9	91
TW E	515	7/1/2019	AC	TAXIWAY	P	0	2,399.00	4/25/2022	3	94
TW F	605	1/1/1984	AC	TAXIWAY	P	0	36,880.00	4/25/2022	38	40
TW F	610	5/1/2022	AC	TAXIWAY	P	0	9,548.00	5/1/2022	0	100
TW F	650	1/1/1984	AC	TAXIWAY	P	0	6,273.00	4/25/2022	38	35
TW G	700	1/1/2016	AC	TAXIWAY	P	0	126,774.00	4/25/2022	6	88
TW G1	715	1/1/2016	AC	TAXIWAY	P	0	8,543.00	4/25/2022	6	91
TW G2	705	1/1/2016	AC	TAXIWAY	P	0	8,946.00	4/25/2022	6	88
TW G3	710	1/1/2016	AC	TAXIWAY	P	0	8,941.00	4/25/2022	6	89
TW G4	720	1/1/2016	AC	TAXIWAY	P	0	8,529.00	4/25/2022	6	91

*Pavement Database: FDOT*

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		224,949.00	6	100.00	0.00	100.00
03-05	3	336,902.00	8	92.13	1.45	91.31
06-10	8	511,215.00	16	89.31	1.86	89.11
11-15	14	346,032.00	3	54.67	17.46	67.29
16-20	17	57,362.00	1	88.00	0.00	88.00
26-30	30	345,538.00	4	29.75	20.50	43.56
31-35	32	56,507.00	1	38.00	0.00	38.00
36-40	38	97,445.00	3	35.33	3.68	34.66
ALL	11	1,975,950.00	42	78.12	25.52	74.76





# **Appendix B: Maintenance and Rehabilitation Planning Needs**



Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
OMN	TW A	100	WEATHERING	Medium	1,127	SF	0.9%	Preventive	Surface Seal	1,127	SF	\$ 0.75	\$ 850
OMN	TW A	102	WEATHERING	Medium	122	SF	5.0%	Preventive	Surface Seal	122	SF	\$ 0.75	\$ 100
OMN	TW A	105	WEATHERING	Medium	228	SF	5.0%	Preventive	Surface Seal	228	SF	\$ 0.75	\$ 180
OMN	TW A1	110	WEATHERING	Medium	404	SF	5.0%	Preventive	Surface Seal	404	SF	\$ 0.75	\$ 310
OMN	TW A1	112	WEATHERING	Medium	154	SF	5.0%	Preventive	Surface Seal	154	SF	\$ 0.75	\$ 120
OMN	TW A2	117	WEATHERING	Medium	156	SF	5.0%	Preventive	Surface Seal	156	SF	\$ 0.75	\$ 120
OMN	TW B	210	WEATHERING	Medium	385	SF	5.0%	Preventive	Surface Seal	385	SF	\$ 0.75	\$ 290
OMN	TW C	305	WEATHERING	Medium	3,539	SF	10.0%	Preventive	Surface Seal	3,539	SF	\$ 0.75	\$ 2,660
OMN	TW G	700	WEATHERING	Medium	3,502	SF	2.8%	Preventive	Surface Seal	3,502	SF	\$ 0.75	\$ 2,630
OMN	TW G1	715	WEATHERING	Medium	427	SF	5.0%	Preventive	Surface Seal	427	SF	\$ 0.75	\$ 330
OMN	TW G2	705	WEATHERING	Medium	448	SF	5.0%	Preventive	Surface Seal	448	SF	\$ 0.75	\$ 340
OMN	TW G3	710	WEATHERING	Medium	893	SF	10.0%	Preventive	Surface Seal	893	SF	\$ 0.75	\$ 680
OMN	TW G4	720	WEATHERING	Medium	426	SF	5.0%	Preventive	Surface Seal	425	SF	\$ 0.75	\$ 320
OMN	AP RU 17	5310	WEATHERING	Medium	1,994	SF	5.0%	Preventive	Surface Seal	1,995	SF	\$ 0.75	\$ 1,500
OMN	AP RU 27	5110	WEATHERING	Medium	1,391	SF	5.0%	Preventive	Surface Seal	1,392	SF	\$ 0.75	\$ 1,050
OMN	AP RU 35	5410	WEATHERING	Medium	2,009	SF	5.0%	Preventive	Surface Seal	2,010	SF	\$ 0.75	\$ 1,510
OMN	TL SW	2004	JT SEAL DMG	High	39	Slabs	100.0%	Stopgap	PCC Joint Seal	682	LF	\$ 4.25	\$ 2,900
OMN	TL SW	2004	SHAT. SLAB	Medium	21	Slabs	53.9%	Stopgap	PCC Crack Sealing	882	LF	\$ 7.00	\$ 6,180
OMN	TL SW	2004	SHAT. SLAB	High	15	Slabs	38.5%	Stopgap	PCC Slab Replacement	6,600	SF	\$ 51.50	\$ 339,910
OMN	AP FBO	4110	ALLIGATOR CR	Medium	3,668	SF	2.6%	Stopgap	AC Full-Depth Patching	3,916	SF	\$ 10.00	\$ 39,160
OMN	AP FBO	4110	PATCHING	High	1,646	SF	1.2%	Stopgap	AC Full-Depth Patching	1,814	SF	\$ 10.00	\$ 18,140
OMN	AP T-HANG	4305	ALLIGATOR CR	Medium	3,186	SF	5.9%	Stopgap	AC Full-Depth Patching	3,417	SF	\$ 10.00	\$ 34,170
OMN	AP T-HANG	4305	ALLIGATOR CR	High	76	SF	0.1%	Stopgap	AC Full-Depth Patching	115	SF	\$ 10.00	\$ 1,160
OMN	AP T-HANG	4310	ALLIGATOR CR	Medium	60	SF	1.0%	Stopgap	AC Full-Depth Patching	96	SF	\$ 10.00	\$ 960

*Table B.2: Section-Level 10-Year Major Rehabilitation Needs*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	OMN	RW 17-35	6205	AAC	329,912	66	AC Rehabilitation	\$ 2,970,000
2023	OMN	RW 17-35	6210	AAC	10,188	64	AC Rehabilitation	\$ 92,000
2023	OMN	TW E	505	AAC	56,507	35	AC Reconstruction	\$ 905,000
2023	OMN	TW F	605	AC	36,880	39	AC Reconstruction	\$ 591,000
2023	OMN	TW F	650	AC	6,273	34	AC Reconstruction	\$ 101,000
2023	OMN	TL SW	2004	PCC	17,255	0	PCC Reconstruction	\$ 501,000
2023	OMN	AP FBO	4102	AC	22,255	25	AC Reconstruction	\$ 357,000
2023	OMN	AP FBO	4105	AC	164,592	56	AC Rehabilitation	\$ 1,482,000
2023	OMN	AP FBO	4110	AAC	141,436	34	AC Reconstruction	\$ 2,263,000
2023	OMN	AP T-HANG	4305	AC	54,292	30	AC Reconstruction	\$ 869,000
2023	OMN	AP T-HANG	4310	AC	5,932	29	AC Reconstruction	\$ 95,000
2032	OMN	AP RU 27	5110	AC	27,832	69	AC Rehabilitation	\$ 389,000


*\*All planning cost values have been rounded up to the nearest thousand dollars.*





# Appendix C: Technical Exhibits






LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- PAVEMENT SURFACE TYPE
- PAVEMENT BRANCH ID
- SECTION NUMBER
- NUMBER OF SAMPLE UNITS IN SECTION
- NUMBER OF SAMPLE UNITS TO BE INSPECTED
- SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- INSPECTED SAMPLE UNITS.


TOTAL SAMPLES INSPECTED = 81  
AC: 80 PCC: 1


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2019	TW A, TW A1, TW A2, TW E	Complete Reconstruction - AC
	RW 17-35	Mill and Overlay   2" Mill, 2" P-401 Overlay
	RW 9-27	Complete Reconstruction - AC   4" P-401, 6" P-403, 12" P-152
2022	AP FBO, TW B, TW D	Complete Reconstruction - AC
	AP MID	New Construction - AC
	TW A, TW F	Mill and Overlay   2" Mill, 2" P-401 Overlay
2023	RW 9-27, TW A	New Construction - AC   600' RW and TW Extension





**LEGEND**


RW 13-31 — TYPICAL RUNWAY BRANCH ID  
TW A — TYPICAL TAXIWAY BRANCH ID  
AP S — TYPICAL APRON BRANCH ID

**2022 PAVEMENT CONDITION INDEX**

PCI 86-100 Good
PCI 71-85 Satisfactory
PCI 56-70 Fair
PCI 41-55 Poor
PCI 26-40 Very Poor
PCI 11-25 Serious
PCI 0-10 Failed

"SECTION ID"  
"PCI VALUE"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.







# Appendix D: Inspection Photograph Documentation







RW 9-27, Section 6105, Sample Unit 118 – Weathering



RW 9-27, Section 6110, Sample Unit 128 – Vicinity





RW 17-35, Section 6205, Sample Unit 126 – Swelling



RW 17-35, Section 6205, Sample Unit 139 – Longitudinal & Transverse Cracking





TW A, Section 100, Sample Unit 117 – Vicinity



TW C, Section 305, Sample Unit 106 – Weathering





TW E, Section 505, Sample Unit 107 – Block Cracking



TW F, Section 605, Sample Unit 108 – Longitudinal & Transverse Cracking and Raveling





TW G, Section 700, Sample Unit 115 – Vicinity



TL SW, Section 2004, Sample Unit 602 – Shattered Slab





AP FBO, Section 4110, Sample Unit 111 – Alligator Cracking, Block Cracking, Patching, and Raveling



AP T-HANG, Section 4305, Sample Unit 101 – Vicinity





# **Appendix E: Inspection Distress Details**



# Re-Inspection Report

FDOT

Generated Date 11/17/2022

Page 1 of 45

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	AP FBO	Name:	FBO APRON	Use:	APRON	Area:	343,073 SqFt		
Section:	4102	of	4	From:	-	To:	-	Last Const.:	1/1/1992
Surface:	AC	Family:	CA653-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	22,255 SqFt	Length:	670 Ft	Width:	34 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									

Work Date:	1/1/1992	Work Type:	BUILT	Code:	IMPORTED	Is Major M&R:	True
------------	----------	------------	-------	-------	----------	---------------	------

Last Insp. Date:	4/25/2022	TotalSamples:	6	Surveyed:	1
------------------	-----------	---------------	---	-----------	---

Conditions: PCI: 26

Inspection Comments:

Sample Number:	101	Type:	R	Area:	3366.00 SqFt	PCI:	26
----------------	-----	-------	---	-------	--------------	------	----

Sample Comments:

43	BLOCK CR	M	3366.00	SqFt
49	OIL SPILLAGE	N	8.00	SqFt
52	RAVELING	L	1500.00	SqFt
52	RAVELING	M	5.00	SqFt
56	SWELLING	L	837.00	SqFt
57	WEATHERING	M	1861.00	SqFt



Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT					
Branch:	AP FBO		Name:	FBO APRON		Use:	APRON	Area:	343,073 SqFt	
Section:	4105	of	4	From:	-	To:	-	Last Const.:	1/1/1992	
Surface:	AC	Family:	CA653-GA-AP-AC		Zone:	Category:		Rank:	P	
Area:	164,592 SqFt		Length:	835 Ft		Width:	180 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0		
Section Comments:										
Work Date:	1/1/1992		Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	39		Surveyed:				4
Conditions:	PCI:	57								
Inspection Comments:										
Sample Number:	102	Type:	R	Area:	5000.00 SqFt		PCI:	62		
Sample Comments:										
48	L & T CR		L	386.00 Ft						
48	L & T CR		M	146.00 Ft						
52	RAVELING		L	1500.00 SqFt						
57	WEATHERING		M	3500.00 SqFt						
Sample Number:	205	Type:	R	Area:	5000.00 SqFt		PCI:	58		
Sample Comments:										
48	L & T CR		L	180.00 Ft						
48	L & T CR		M	300.00 Ft						
49	OIL SPILLAGE		N	10.00 SqFt						
52	RAVELING		L	5000.00 SqFt						
Sample Number:	307	Type:	R	Area:	5000.00 SqFt		PCI:	54		
Sample Comments:										
48	L & T CR		L	313.00 Ft						
48	L & T CR		M	216.00 Ft						
49	OIL SPILLAGE		N	16.00 SqFt						
50	PATCHING		L	81.00 SqFt						
52	RAVELING		L	246.00 SqFt						
57	WEATHERING		L	4673.00 SqFt						
Sample Number:	403	Type:	R	Area:	3000.00 SqFt		PCI:	51		
Sample Comments:										
48	L & T CR		L	50.00 Ft						
48	L & T CR		M	304.00 Ft						
52	RAVELING		L	1500.00 SqFt						
57	WEATHERING		M	1500.00 SqFt						

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	AP FBO	Name:	FBO APRON	Use:	APRON	Area:	343,073 SqFt		
Section:	4110	of	4	From:	-	To:	-	Last Const.:	1/1/1992
Surface:	AAC	Family:	CA653-GA-AP-AAC-APC	Zone:		Category:		Rank:	P
Area:	141,436 SqFt	Length:	600 Ft	Width:	218 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1979	Work Type: BUILT				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1992	Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/2022	Work Type: Surface Treatment - Seal Coat				Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	4/25/2022	TotalSamples:	26	Surveyed:	4				
Conditions:	PCI: 36								
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	5452.00 SqFt	PCI:	43		
Sample Comments:									
48	L & T CR	L	243.00	Ft					
48	L & T CR	M	298.00	Ft					
50	PATCHING	H	250.00	SqFt					
52	RAVELING	L	25.00	SqFt					
52	RAVELING	M	17.00	SqFt					
57	WEATHERING	M	5160.00	SqFt					
Sample Number:	111	Type:	R	Area:	6024.00 SqFt	PCI:	18		
Sample Comments:									
41	ALLIGATOR CR	M	557.00	SqFt					
43	BLOCK CR	M	3900.00	SqFt					
45	DEPRESSION	L	95.00	SqFt					
48	L & T CR	M	158.00	Ft					
50	PATCHING	L	447.00	SqFt					
50	PATCHING	M	6.00	SqFt					
52	RAVELING	L	5570.00	SqFt					
Sample Number:	205	Type:	R	Area:	5001.00 SqFt	PCI:	47		
Sample Comments:									
43	BLOCK CR	M	225.00	SqFt					
48	L & T CR	L	80.00	Ft					
48	L & T CR	M	197.00	Ft					
50	PATCHING	L	67.00	SqFt					
50	PATCHING	M	441.00	SqFt					
52	RAVELING	M	8.00	SqFt					
57	WEATHERING	M	4485.00	SqFt					
Sample Number:	209	Type:	R	Area:	5001.00 SqFt	PCI:	40		
Sample Comments:									
43	BLOCK CR	L	2501.00	SqFt					
43	BLOCK CR	M	2500.00	SqFt					
52	RAVELING	L	5001.00	SqFt					

Network:	OMN		Name:	ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	AP FBO		Name:	FBO APRON		Use:	APRON	Area:	343,073 SqFt		
Section:	4115 of 4		From:	-		To:	-		Last Const.:	5/1/2022	
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Rank:	P	
Area:	14,790 SqFt		Length:	435 Ft		Width:	34 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1984		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	5/1/2022		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	1/28/2019		TotalSamples:	16		Surveyed:	5				
Conditions:	PCI: 38		NOTE: *** Pre-Construction PCI ***								
Inspection Comments:											
Sample Number:	101		Type:	R		Area:	4500.00 SqFt		PCI:	43	
Sample Comments:											
43	BLOCK CR		M	800.00 SqFt							
45	DEPRESSION		L	21.00 SqFt							
48	L & T CR		L	11.00 Ft							
48	L & T CR		M	250.00 Ft							
52	RAVELING		L	4500.00 SqFt							
56	SWELLING		L	11.00 SqFt							
56	SWELLING		M	5.00 SqFt							
Sample Number:	103		Type:	R		Area:	4500.00 SqFt		PCI:	38	
Sample Comments:											
43	BLOCK CR		L	100.00 SqFt							
43	BLOCK CR		M	700.00 SqFt							
48	L & T CR		L	16.00 Ft							
48	L & T CR		M	440.00 Ft							
52	RAVELING		L	4500.00 SqFt							
56	SWELLING		L	21.00 SqFt							
56	SWELLING		M	1.00 SqFt							
Sample Number:	107		Type:	R		Area:	4500.00 SqFt		PCI:	34	
Sample Comments:											
43	BLOCK CR		M	800.00 SqFt							
45	DEPRESSION		L	76.00 SqFt							
48	L & T CR		L	50.00 Ft							
48	L & T CR		M	381.00 Ft							
50	PATCHING		L	50.00 SqFt							
50	PATCHING		M	74.00 SqFt							
52	RAVELING		L	875.00 SqFt							
54	SHOVING		H	25.00 SqFt							
56	SWELLING		L	47.00 SqFt							
57	WEATHERING		L	3501.00 SqFt							
Sample Number:	109		Type:	R		Area:	4500.00 SqFt		PCI:	38	
Sample Comments:											
43	BLOCK CR		M	2062.00 SqFt							
45	DEPRESSION		L	10.00 SqFt							
48	L & T CR		L	33.00 Ft							
48	L & T CR		M	218.00 Ft							
52	RAVELING		L	4500.00 SqFt							
56	SWELLING		L	71.00 SqFt							
56	SWELLING		M	160.00 SqFt							
Sample Number:	113		Type:	R		Area:	4500.00 SqFt		PCI:	36	
Sample Comments:											
43	BLOCK CR		M	1600.00 SqFt							

48	L & T CR	M	250.00	Ft
50	PATCHING	L	40.00	SqFt
50	PATCHING	M	180.00	SqFt
52	RAVELING	L	4280.00	SqFt
56	SWELLING	L	40.00	SqFt
56	SWELLING	M	18.00	SqFt



Network:	OMN	Name:		ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	AP RU 17	Name:	RUN-UP APRON		Use:	APRON	Area:	39,883 SqFt			
Section:	5310	of	1	From:	-	To:	-	Last Const.:	1/1/2016		
Surface:	AC	Family:	CA653-GA-AP-AC		Zone:		Category:	Rank: P			
Area:	39,883 SqFt	Length:	385 Ft		Width:	105 Ft					
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:		Street Type:			Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2016	Work Type: New Construction - AC				Code:	NC-AC	Is Major M&R: True			
Last Insp. Date:	4/25/2022	TotalSamples:	8		Surveyed:	1					
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	502	Type:	R	Area:	5500.00 SqFt		PCI:	91			
Sample Comments:											
57	WEATHERING	L	5225.00 SqFt								
57	WEATHERING	M	275.00 SqFt								

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT				
Branch:	AP RU 27		Name:	RUN-UP APRON		Use:	APRON	Area:	27,832 SqFt
Section:	5110	of	1	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	AC	Family:	CA653-GA-AP-AC	Zone:		Category:		Rank:	P
Area:	27,832 SqFt	Length:	250 Ft	Width:	125 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2013	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	4/25/2022	TotalSamples:	5	Surveyed:	1				
Conditions:	PCI: 87								
Inspection Comments:									
Sample Number:	501	Type:	R	Area:	6221.00 SqFt	PCI:	87		
Sample Comments:									
48	L & T CR	L	31.00	Ft					
57	WEATHERING	L	5910.00	SqFt					
57	WEATHERING	M	311.00	SqFt					

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	AP RU 35		Name:	RUN-UP APRON		Use:	APRON	Area:	40,187 SqFt		
Section:	5410	of	1	From:	-			To:	-	Last Const.:	1/1/2016
Surface:	AC	Family:	CA653-GA-AP-AC		Zone:				Category:	Rank: P	
Area:	40,187 SqFt		Length:	385 Ft		Width:	105 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0			Lanes:	0	
Section Comments:											
Work Date:	1/1/2016		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	8			Surveyed:	1			
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	505	Type:	R	Area:	5500.00 SqFt			PCI:	91		
Sample Comments:											
57	WEATHERING		L	5225.00 SqFt							
57	WEATHERING		M	275.00 SqFt							

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	AP RU 9		Name:	RUN-UP APRON		Use:	APRON	Area:	28,165 SqFt		
Section:	5210	of	1	From:	-			To:	-	Last Const.:	1/1/2013
Surface:	AC	Family:	CA653-GA-AP-AC		Zone:				Category:	Rank: P	
Area:	28,165 SqFt		Length:	300 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0			Lanes:	0	
Section Comments:											
Work Date:	1/1/2013		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	6			Surveyed:	1			
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	501	Type:	R	Area:	5000.00 SqFt			PCI:	91		
Sample Comments:											
48	L & T CR		L	7.00 Ft							
57	WEATHERING		L	5000.00 SqFt							



Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT				
Branch:	AP T-HANG		Name:	T-HANGAR APRON		Use:	APRON	Area:	60,224 SqFt
Section:	4305 of 2		From:	-		To:	-		Last Const.: 1/1/1984
Surface:	AC	Family:	CA653-GA-AP-AC		Zone:	Category:		Rank:	P
Area:	54,292 SqFt		Length:	342 Ft		Width:	140 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	1/1/1984		Work Type:			BUILT	Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2022		Work Type:			Surface Treatment - Seal Coat	Code:	ST-SC	Is Major M&R: False
Last Insp. Date:	4/25/2022		TotalSamples:	10		Surveyed: 3			
Conditions:	PCI:	31							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	6917.00 SqFt		PCI:	16	
Sample Comments:									
41	ALLIGATOR CR		M	1031.00 SqFt					
41	ALLIGATOR CR		H	25.00 SqFt					
43	BLOCK CR		M	4231.00 SqFt					
45	DEPRESSION		L	33.00 SqFt					
45	DEPRESSION		M	53.00 SqFt					
50	PATCHING		L	1230.00 SqFt					
50	PATCHING		M	400.00 SqFt					
57	WEATHERING		M	5287.00 SqFt					
Sample Number:	102	Type:	R	Area:	6332.00 SqFt		PCI:	30	
Sample Comments:									
41	ALLIGATOR CR		L	50.00 SqFt					
41	ALLIGATOR CR		M	14.00 SqFt					
43	BLOCK CR		M	3132.00 SqFt					
45	DEPRESSION		L	130.00 SqFt					
48	L & T CR		M	293.00 Ft					
50	PATCHING		M	4.00 SqFt					
57	WEATHERING		M	6328.00 SqFt					
Sample Number:	201	Type:	R	Area:	4560.00 SqFt		PCI:	54	
Sample Comments:									
43	BLOCK CR		L	222.00 SqFt					
45	DEPRESSION		L	4.00 SqFt					
48	L & T CR		M	224.00 Ft					
50	PATCHING		L	114.00 SqFt					
52	RAVELING		M	300.00 SqFt					
57	WEATHERING		M	4146.00 SqFt					

Network:	OMN		Name:	ORMOND BEACH MUNICIPAL AIRPORT								
Branch:	AP T-HANG		Name:	T-HANGAR APRON		Use:	APRON	Area:	60,224 SqFt			
Section:	4310		of	2	From:	-		To:	-		Last Const.:	7/31/2008
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Category:	Rank: P		
Area:	5,932 SqFt		Length:	285 Ft		Width:	22 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:		0		Lanes:	0				
Section Comments:												
Work Date:	7/31/2008		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2022		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	4/25/2022		TotalSamples:	2		Surveyed:	1					
Conditions:	PCI: 30											
Inspection Comments:												
Sample Number:	115		Type:	R		Area:	3256.00 SqFt		PCI:	30		
Sample Comments:												
41	ALLIGATOR CR		M	33.00 SqFt								
43	BLOCK CR		M	220.00 SqFt								
48	L & T CR		L	123.00 Ft								
48	L & T CR		M	396.00 Ft								
50	PATCHING		L	202.00 SqFt								
57	WEATHERING		L	2290.00 SqFt								
57	WEATHERING		M	764.00 SqFt								

Network:		OMN		Name:		ORMOND BEACH MUNICIPAL AIRPORT								
Branch:	RW 17-35		Name:	RUNWAY 17-35		Use:	RUNWAY		Area:	370,500 SqFt				
Section:	6205		of	3		From:	-		To:	-		Last Const.:	1/1/2008	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	329,912 SqFt		Length:	3,300 Ft		Width:			100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1943		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1983		Work Type:				OVERLAY		Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/2008		Work Type:				Mill and Overlay		Code:	ML-OVL		Is Major M&R:	True	
Last Insp. Date:	4/25/2022		TotalSamples:	66		Surveyed:	14							
Conditions:	PCI:		68											
Inspection Comments:														
Sample Number:	103		Type:	R		Area:	5000.00 SqFt		PCI:	72				
Sample Comments:														
48	L & T CR		L	43.00 Ft										
52	RAVELING		L	1488.00 SqFt										
57	WEATHERING		M	3512.00 SqFt										
Sample Number:	107		Type:	R		Area:	5000.00 SqFt		PCI:	67				
Sample Comments:														
48	L & T CR		L	120.00 Ft										
48	L & T CR		M	35.00 Ft										
52	RAVELING		L	1500.00 SqFt										
57	WEATHERING		M	3500.00 SqFt										
Sample Number:	112		Type:	R		Area:	5000.00 SqFt		PCI:	72				
Sample Comments:														
48	L & T CR		L	187.00 Ft										
52	RAVELING		L	1000.00 SqFt										
56	SWELLING		L	82.00 SqFt										
57	WEATHERING		L	4000.00 SqFt										
Sample Number:	117		Type:	R		Area:	5000.00 SqFt		PCI:	71				
Sample Comments:														
48	L & T CR		L	129.00 Ft										
52	RAVELING		L	1000.00 SqFt										
57	WEATHERING		M	4000.00 SqFt										
Sample Number:	119		Type:	R		Area:	5000.00 SqFt		PCI:	68				
Sample Comments:														
48	L & T CR		L	101.00 Ft										
52	RAVELING		L	1000.00 SqFt										
56	SWELLING		L	46.00 SqFt										
57	WEATHERING		M	4000.00 SqFt										
Sample Number:	126		Type:	R		Area:	5000.00 SqFt		PCI:	61				
Sample Comments:														
48	L & T CR		L	131.00 Ft										
48	L & T CR		M	25.00 Ft										
52	RAVELING		L	1000.00 SqFt										
56	SWELLING		L	275.00 SqFt										
57	WEATHERING		M	4000.00 SqFt										
Sample Number:	131		Type:	R		Area:	5000.00 SqFt		PCI:	69				
Sample Comments:														
48	L & T CR		L	77.00 Ft										

52	RAVELING	L	1000.00	SqFt
56	SWELLING	L	38.00	SqFt
57	WEATHERING	M	4000.00	SqFt
<b>Sample Number:</b> 135 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 69				
<b>Sample Comments:</b>				
48	L & T CR	L	269.00	Ft
52	RAVELING	L	1000.00	SqFt
56	SWELLING	L	33.00	SqFt
57	WEATHERING	M	4000.00	SqFt
<b>Sample Number:</b> 139 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 69				
<b>Sample Comments:</b>				
48	L & T CR	L	136.00	Ft
52	RAVELING	L	1000.00	SqFt
56	SWELLING	L	24.00	SqFt
57	WEATHERING	M	4000.00	SqFt
<b>Sample Number:</b> 142 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 68				
<b>Sample Comments:</b>				
48	L & T CR	L	116.00	Ft
52	RAVELING	L	1000.00	SqFt
56	SWELLING	L	53.00	SqFt
57	WEATHERING	M	4000.00	SqFt
<b>Sample Number:</b> 153 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 67				
<b>Sample Comments:</b>				
48	L & T CR	L	46.00	Ft
52	RAVELING	L	1440.00	SqFt
56	SWELLING	L	250.00	SqFt
57	WEATHERING	M	3560.00	SqFt
<b>Sample Number:</b> 159 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 66				
<b>Sample Comments:</b>				
48	L & T CR	L	92.00	Ft
52	RAVELING	L	1000.00	SqFt
56	SWELLING	L	450.00	SqFt
57	WEATHERING	M	4000.00	SqFt
<b>Sample Number:</b> 165 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 63				
<b>Sample Comments:</b>				
48	L & T CR	L	83.00	Ft
52	RAVELING	L	1000.00	SqFt
56	SWELLING	L	843.00	SqFt
57	WEATHERING	M	4000.00	SqFt
<b>Sample Number:</b> 171 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 65				
<b>Sample Comments:</b>				
48	L & T CR	L	67.00	Ft
52	RAVELING	L	2400.00	SqFt
56	SWELLING	L	338.00	SqFt
57	WEATHERING	M	2600.00	SqFt



Network:		OMN		Name:		ORMOND BEACH MUNICIPAL AIRPORT								
Branch:	RW 17-35		Name:	RUNWAY 17-35		Use:	RUNWAY		Area:	370,500 SqFt				
Section:	6210		of	3		From:	-		To:	-		Last Const.:	1/1/2008	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	10,188 SqFt		Length:	100 Ft		Width:	100 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1943		Work Type:				BUILT		Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1973		Work Type:				OVERLAY		Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/2008		Work Type:				Mill and Overlay		Code:	ML-OVL		Is Major M&R:	True	
Last Insp. Date:	4/25/2022		TotalSamples:	2		Surveyed:	1							
Conditions:	PCI: 66													
Inspection Comments:														
Sample Number:	145		Type:	R		Area:	5187.00 SqFt		PCI:	66				
Sample Comments:														
48	L & T CR		L	104.00 Ft										
52	RAVELING		L	1037.00 SqFt										
56	SWELLING		L	413.00 SqFt										
57	WEATHERING		M	4150.00 SqFt										

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	RW 17-35		Name:	RUNWAY 17-35		Use:	RUNWAY		Area:	370,500 SqFt	
Section:	6215 of 3		From:	-		To:	-		Last Const.:	7/1/2019	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P	
Area:	30,400 SqFt		Length:	300 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1973		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2008		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	7/1/2019		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	6		Surveyed:	2				
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	146		Type:	R		Area:	4812.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	4812.00 SqFt							
Sample Number:	148		Type:	R		Area:	5000.00 SqFt		PCI:	89	
Sample Comments:											
48	L & T CR		L	72.00 Ft							
57	WEATHERING		L	5000.00 SqFt							

Network:	OMN	Name:		ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	RW 9-27		Name:	RUNWAY 9-27		Use:	RUNWAY	Area:	292,949 SqFt		
Section:	6105	of	2	From:	-		To:	-		Last Const.:	7/1/2019
Surface:	AC	Family:	CA653-GA-RW-AC		Zone:			Category:	Rank: P		
Area:	262,949 SqFt		Length:	3,506 Ft		Width:	75 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1977		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	7/1/2019		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date: 4/25/2022											
		TotalSamples:	47		Surveyed: 11						
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	102	Type:	R	Area:	5625.00 SqFt		PCI:	94			
Sample Comments:											
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	106	Type:	R	Area:	5625.00 SqFt		PCI:	94			
Sample Comments:											
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	110	Type:	R	Area:	5625.00 SqFt		PCI:	90			
Sample Comments:											
48	L & T CR		L	22.00 Ft							
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	114	Type:	R	Area:	5625.00 SqFt		PCI:	92			
Sample Comments:											
48	L & T CR		L	2.00 Ft							
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	118	Type:	R	Area:	5625.00 SqFt		PCI:	90			
Sample Comments:											
48	L & T CR		L	43.00 Ft							
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	122	Type:	R	Area:	5625.00 SqFt		PCI:	90			
Sample Comments:											
48	L & T CR		L	36.00 Ft							
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	132	Type:	R	Area:	5625.00 SqFt		PCI:	91			
Sample Comments:											
48	L & T CR		L	15.00 Ft							
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	136	Type:	R	Area:	5625.00 SqFt		PCI:	92			
Sample Comments:											
48	L & T CR		L	3.00 Ft							
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	140	Type:	R	Area:	5625.00 SqFt		PCI:	89			
Sample Comments:											
48	L & T CR		L	57.00 Ft							
57	WEATHERING		L	5625.00 SqFt							
Sample Number:	144	Type:	R	Area:	5625.00 SqFt		PCI:	92			
Sample Comments:											

48

L & T CR

L

2.00 Ft

57

WEATHERING

L

5625.00 SqFt

Sample Number:

148

Type:

R

Area:

5625.00 SqFt

PCI:

94

Sample Comments:

57

WEATHERING

L

5625.00 SqFt



Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT					
Branch:	RW 9-27		Name:	RUNWAY 9-27		Use:	RUNWAY	Area:	292,949 SqFt	
Section:	6110	of	2	From:	-	To:	-	Last Const.:	7/1/2019	
Surface:	AC	Family:	CA653-GA-RW-AC		Zone:		Category:	Rank:	P	
Area:	30,000 SqFt		Length:	400 Ft		Width:	75 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:			Grade:		0	Lanes:		0	
Section Comments:										
Work Date:	1/1/1943		Work Type:				BUILT	Code:	IMPORTED	
								Is Major M&R:	True	
Work Date:	1/1/1977		Work Type:				OVERLAY	Code:	IMPORTED	
								Is Major M&R:	True	
Work Date:	7/1/2019		Work Type:				Complete Reconstruction - AC	Code:	CR-AC	
								Is Major M&R:	True	
Last Insp. Date:	4/25/2022		TotalSamples:	6		Surveyed:				2
Conditions:	PCI:		94							
Inspection Comments:										
Sample Number:	125	Type:	R	Area:	5625.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	5625.00 SqFt						
Sample Number:	128	Type:	R	Area:	5625.00 SqFt		PCI:	94		
Sample Comments:										
57	WEATHERING		L	5625.00 SqFt						

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TL SW	Name:	SOUTHWEST TAXILANE	Use:	TAXILANE	Area:	17,255 SqFt		
Section:	2004	of	1	From:	-	To:	-	Last Const.:	1/1/1992
Surface:	PCC	Family:	CA653-GA-RW-TW-PCC	Zone:		Category:		Rank:	P
Area:	17,255 SqFt	Length:	640 Ft	Width:	22 Ft				
Slabs:	39	Slab Length:	22 Ft	Slab Width:	20 Ft	Joint Length:	682 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1992	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	4/25/2022	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI:	0							
Inspection Comments:									
Sample Number:	602	Type:	R	Area:	13.00 Slabs	PCI:	0		
Sample Comments:									
65	JT SEAL DMG	H	13.00	Slabs					
72	SHAT. SLAB	L	1.00	Slabs					
72	SHAT. SLAB	M	7.00	Slabs					
72	SHAT. SLAB	H	5.00	Slabs					

Network:	OMN		Name:	ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	57,362 SqFt		
Section:	4410 of 1		From:	-		To:	-		Last Const.:	1/1/2005	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Rank:	P	
Area:	57,362 SqFt		Length:	1,635 Ft		Width:	25 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2005		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Work Date:	1/1/2022		Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Last Insp. Date: 4/25/2022											
			TotalSamples:	11		Surveyed: 2					
Conditions:	PCI: 88										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	4941.00 SqFt		PCI:	88	
Sample Comments:											
48	L & T CR		L	89.00 Ft							
57	WEATHERING		L	4941.00 SqFt							
Sample Number:	303		Type:	R		Area:	5000.00 SqFt		PCI:	88	
Sample Comments:											
45	DEPRESSION		L	4.00 SqFt							
48	L & T CR		L	86.00 Ft							
57	WEATHERING		L	5000.00 SqFt							

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	155,987 SqFt		
Section:	100 of 5		From:	-			To:	-		Last Const.:	1/1/2013	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:	Rank: P		
Area:	123,174 SqFt		Length:	3,419 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2013		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	33		Surveyed:	5					
Conditions:	PCI:	89										
Inspection Comments:												
Sample Number:	101		Type:	R		Area:	3939.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	22.00 Ft								
57	WEATHERING		L	3939.00 SqFt								
Sample Number:	107		Type:	R		Area:	3500.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	25.00 Ft								
57	WEATHERING		L	3500.00 SqFt								
Sample Number:	117		Type:	R		Area:	3500.00 SqFt		PCI:	89		
Sample Comments:												
48	L & T CR		L	40.00 Ft								
57	WEATHERING		L	3500.00 SqFt								
Sample Number:	127		Type:	R		Area:	3500.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	15.00 Ft								
57	WEATHERING		L	3500.00 SqFt								
Sample Number:	137		Type:	R		Area:	4690.00 SqFt		PCI:	87		
Sample Comments:												
48	L & T CR		L	24.00 Ft								
57	WEATHERING		L	3325.00 SqFt								
57	WEATHERING		M	175.00 SqFt								



Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW A	Name:	TAXIWAY A		Use:	TAXIWAY	Area:	155,987 SqFt	
Section:	102	of	5	From:	-	To:	-	Last Const.:	1/1/2019
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:	Rank:	P
Area:	2,434	SqFt	Length:	51	Ft	Width:	48	Ft	
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2013	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Work Date:	1/1/2019	Work Type:	Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	4/25/2022	TotalSamples:	1	Surveyed:	1				
Conditions:	PCI: 91								
Inspection Comments:									
Sample Number:	99	Type:	R	Area:	2434.00	SqFt	PCI:	91	
Sample Comments:									
57	WEATHERING	L	2312.00	SqFt					
57	WEATHERING	M	122.00	SqFt					

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW A	Name:	TAXIWAY A		Use:	TAXIWAY	Area:	155,987 SqFt	
Section:	105	of	5	From:	-	To:	-	Last Const.:	1/1/2016
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	4,550 SqFt		Length:	130 Ft		Width:	35 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:			Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/2013	Work Type: New Construction - Initial				Code:	NU-IN	Is Major M&R:	True
Work Date:	1/1/2016	Work Type: Mill and Overlay				Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	4/25/2022	TotalSamples:	1	Surveyed:		1			
Conditions:	PCI:	91							
Inspection Comments:									
Sample Number:	119	Type:	R	Area:	4550.00 SqFt	PCI:	91		
Sample Comments:									
57	WEATHERING	L	4322.00	SqFt					
57	WEATHERING	M	228.00	SqFt					

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	155,987 SqFt		
Section:	120		of	5	From:	-		To:	-		Last Const.:	7/1/2019
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:	Rank: P		
Area:	2,519 SqFt		Length:	50 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2013		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	7/1/2019		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	1		Surveyed:	1					
Conditions:	PCI: 94											
Inspection Comments:												
Sample Number:	140		Type:	R		Area:	2520.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	2520.00		SqFt						

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT				
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	155,987 SqFt
Section:	125	of	5	From:	-	To:	-	Last Const.:	5/1/2022
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank: P
Area:	23,310 SqFt		Length:	666 Ft		Width:	35 Ft		
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:		Street Type:			Grade:	0		Lanes:	0
Section Comments:									
Work Date:	1/1/2013		Work Type: New Construction - Initial			Code:	NU-IN		Is Major M&R: True
Work Date:	5/1/2022		Work Type: Complete Reconstruction - AC			Code:	CR-AC		Is Major M&R: True
Last Insp. Date:	1/28/2019		TotalSamples:	41		Surveyed:	5		
Conditions:	PCI: 93		NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	3939.00 SqFt		PCI:	90	
Sample Comments:									
48	L & T CR		L	18.00 Ft					
57	WEATHERING		L	3939.00 SqFt					
Sample Number:	107	Type:	R	Area:	3500.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	3500.00 SqFt					
Sample Number:	117	Type:	R	Area:	3500.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	3500.00 SqFt					
Sample Number:	127	Type:	R	Area:	3500.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	3500.00 SqFt					
Sample Number:	138	Type:	R	Area:	3500.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	3500.00 SqFt					



Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW A1	Name:	TAXIWAY A1	Use:	TAXIWAY	Area:	11,172 SqFt		
Section:	110	of	2	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	AC	Family:	CA653-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	8,089 SqFt	Length:	194 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2013	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	4/25/2022	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	86							
Inspection Comments:									
Sample Number:	102	Type:	R	Area:	4588.00 SqFt	PCI:	86		
Sample Comments:									
45	DEPRESSION	L	39.00	SqFt					
57	WEATHERING	L	4359.00	SqFt					
57	WEATHERING	M	229.00	SqFt					

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY	Area:	11,172 SqFt		
Section:	112 of 2		From:	-		To:	-		Last Const.:	7/1/2019	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Rank:	P	
Area:	3,083 SqFt		Length:	51 Ft		Width:	60 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2013		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	7/1/2019		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	100		Type:	R		Area:	3083.00 SqFt		PCI:	91	
Sample Comments:											
57	WEATHERING		L	2929.00 SqFt							
57	WEATHERING		M	154.00 SqFt							

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	TW A2	Name:	TAXIWAY A2		Use:	TAXIWAY	Area:	11,172 SqFt		
Section:	115	of	2	From:	-	To:	-	Last Const.:	1/1/2013	
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P
Area:	8,054 SqFt	Length:	193 Ft		Width:	40 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2013	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	4/25/2022	TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	91								
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	3500.00 SqFt		PCI:	91		
Sample Comments:										
48	L & T CR	L	8.00 Ft							
57	WEATHERING	L	3500.00 SqFt							

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY	Area:	11,172 SqFt		
Section:	117 of 2		From:	-		To:	-		Last Const.:	7/1/2019	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Rank:	P	
Area:	3,118 SqFt		Length:	52 Ft		Width:	60 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2013		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	7/1/2019		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	100		Type:	R		Area:	3118.00 SqFt		PCI:	91	
Sample Comments:											
57	WEATHERING		L	2962.00 SqFt							
57	WEATHERING		M	156.00 SqFt							

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	59,024 SqFt
Section:	205	of	2	From:	-	To:	-	Last Const.:	5/1/2022
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:	Rank: P	
Area:	51,318 SqFt		Length:	490 Ft		Width:	65 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:			Grade:		0	Lanes:		0
Section Comments:									
Work Date:	1/1/1943		Work Type:			BUILT		Code:	IMPORTED
								Is Major M&R:	True
Work Date:	1/1/1977		Work Type:			OVERLAY		Code:	IMPORTED
								Is Major M&R:	True
Work Date:	5/1/2022		Work Type:			Complete Reconstruction - AC		Code:	CR-AC
								Is Major M&R:	True
Last Insp. Date:	1/28/2019		TotalSamples:	5		Surveyed: 2			
Conditions:	PCI:	37	NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	5323.00 SqFt		PCI:	37	
Sample Comments:									
43	BLOCK CR	M	5057.00	SqFt					
45	DEPRESSION	L	12.00	SqFt					
52	RAVELING	L	5323.00	SqFt					
56	SWELLING	L	275.00	SqFt					
Sample Number:	105	Type:	R	Area:	4000.00 SqFt		PCI:	37	
Sample Comments:									
43	BLOCK CR	M	4000.00	SqFt					
52	RAVELING	L	4000.00	SqFt					
56	SWELLING	L	350.00	SqFt					



Network:		OMN		Name:		ORMOND BEACH MUNICIPAL AIRPORT													
Branch:		TW B		Name:		TAXIWAY B		Use:		TAXIWAY		Area:		59,024 SqFt					
Section:		210		of		2		From:		-		To:		-		Last Const.:		1/1/2013	
Surface:		AC		Family:		CA653-GA-TW-AC		Zone:				Category:				Rank:		P	
Area:		7,706 SqFt		Length:		107 Ft		Width:		35 Ft									
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft							
Shoulder:		Street Type:		Grade:		0		Lanes:		0									
Section Comments:																			
Work Date:		1/1/1943		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		1/1/1977		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		1/1/2013		Work Type:		Complete Reconstruction - AC		Code:		CR-AC		Is Major M&R:		True					
Last Insp. Date:		4/25/2022		TotalSamples:		2		Surveyed:		1									
Conditions:		PCI:		86															
Inspection Comments:																			
Sample Number:		106		Type:		R		Area:		4380.00 SqFt		PCI:		86					
Sample Comments:																			
48		L & T CR		L		47.00 Ft													
57		WEATHERING		L		4161.00 SqFt													
57		WEATHERING		M		219.00 SqFt													

Network:	OMN		Name:	ORMOND BEACH MUNICIPAL AIRPORT								
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY		Area:	35,387 SqFt		
Section:	305 of 1		From:	-		To:	-		Last Const.:	1/1/2013		
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:	Rank: P		
Area:	35,387 SqFt		Length:	885 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1990		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/2/1990		Work Type:	Overlay - AC Structural				Code:	OL-AS		Is Major M&R:	True
Work Date:	1/1/2013		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	9		Surveyed:	2					
Conditions:	PCI: 88											
Inspection Comments:												
Sample Number:	103		Type:	R		Area:	3593.00 SqFt		PCI:	87		
Sample Comments:												
48	L & T CR		L	3.00 Ft								
57	WEATHERING		L	3234.00 SqFt								
57	WEATHERING		M	359.00 SqFt								
Sample Number:	106		Type:	R		Area:	3667.00 SqFt		PCI:	89		
Sample Comments:												
57	WEATHERING		L	3300.00 SqFt								
57	WEATHERING		M	367.00 SqFt								

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT				
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	81,876 SqFt
Section:	405	of	1	From:	-	To:	-	Last Const.:	5/1/2022
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank: P
Area:	81,876 SqFt	Length:	1,722 Ft		Width:	35 Ft			
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1943		Work Type: BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1984		Work Type: OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	5/1/2022		Work Type: Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R:	True
Last Insp. Date:	1/28/2019		TotalSamples:	16		Surveyed:	5		
Conditions:	PCI:	38	NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	4500.00 SqFt		PCI:	43	
Sample Comments:									
43	BLOCK CR	M	800.00	SqFt					
45	DEPRESSION	L	21.00	SqFt					
48	L & T CR	L	11.00	Ft					
48	L & T CR	M	250.00	Ft					
52	RAVELING	L	4500.00	SqFt					
56	SWELLING	L	11.00	SqFt					
56	SWELLING	M	5.00	SqFt					
Sample Number:	103	Type:	R	Area:	4500.00 SqFt		PCI:	38	
Sample Comments:									
43	BLOCK CR	L	100.00	SqFt					
43	BLOCK CR	M	700.00	SqFt					
48	L & T CR	L	16.00	Ft					
48	L & T CR	M	440.00	Ft					
52	RAVELING	L	4500.00	SqFt					
56	SWELLING	L	21.00	SqFt					
56	SWELLING	M	1.00	SqFt					
Sample Number:	107	Type:	R	Area:	4500.00 SqFt		PCI:	34	
Sample Comments:									
43	BLOCK CR	M	800.00	SqFt					
45	DEPRESSION	L	76.00	SqFt					
48	L & T CR	L	50.00	Ft					
48	L & T CR	M	381.00	Ft					
50	PATCHING	L	50.00	SqFt					
50	PATCHING	M	74.00	SqFt					
52	RAVELING	L	875.00	SqFt					
54	SHOVING	H	25.00	SqFt					
56	SWELLING	L	47.00	SqFt					
57	WEATHERING	L	3501.00	SqFt					
Sample Number:	109	Type:	R	Area:	4500.00 SqFt		PCI:	38	
Sample Comments:									
43	BLOCK CR	M	2062.00	SqFt					
45	DEPRESSION	L	10.00	SqFt					
48	L & T CR	L	33.00	Ft					
48	L & T CR	M	218.00	Ft					
52	RAVELING	L	4500.00	SqFt					
56	SWELLING	L	71.00	SqFt					
56	SWELLING	M	160.00	SqFt					
Sample Number:	113	Type:	R	Area:	4500.00 SqFt		PCI:	36	
Sample Comments:									
43	BLOCK CR	M	1600.00	SqFt					

48	L & T CR	M	250.00	Ft
50	PATCHING	L	40.00	SqFt
50	PATCHING	M	180.00	SqFt
52	RAVELING	L	4280.00	SqFt
56	SWELLING	L	40.00	SqFt
56	SWELLING	M	18.00	SqFt

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT					
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	85,361 SqFt	
Section:	505	of	3	From:	-	To:	-	Last Const.:	1/1/1990	
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P	
Area:	56,507 SqFt		Length:	2,060 Ft		Width:	35 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft	
Shoulder:	Street Type:			Grade:		0	Lanes:		0	
Section Comments:										
Work Date:	1/1/1943		Work Type:			BUILT	Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1990		Work Type:			OVERLAY	Code:	IMPORTED	Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	16		Surveyed:	3			
Conditions:	PCI: 38									
Inspection Comments:										
Sample Number:	101	Type:	R	Area:	3459.00 SqFt		PCI:	40		
Sample Comments:										
43	BLOCK CR	M	3459.00	SqFt						
52	RAVELING	L	3459.00	SqFt						
56	SWELLING	L	18.00	SqFt						
Sample Number:	107	Type:	R	Area:	3501.00 SqFt		PCI:	40		
Sample Comments:										
43	BLOCK CR	M	3501.00	SqFt						
52	RAVELING	L	3501.00	SqFt						
56	SWELLING	L	12.00	SqFt						
Sample Number:	111	Type:	R	Area:	3501.00 SqFt		PCI:	34		
Sample Comments:										
43	BLOCK CR	M	3459.00	SqFt						
50	PATCHING	L	42.00	SqFt						
52	RAVELING	L	3459.00	SqFt						
56	SWELLING	L	47.00	SqFt						



Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	TW E	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	85,361 SqFt		
Section:	510	of	3	From:	-	To:	-	Last Const.:	1/1/2013	
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P
Area:	26,455 SqFt	Length:	745 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:		Grade:	0		Lanes:	0		
Section Comments:										
Work Date:	1/1/2013	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True	
Last Insp. Date:	4/25/2022	TotalSamples:	7		Surveyed:	1				
Conditions:	PCI:	91								
Inspection Comments:										
Sample Number:	120	Type:	R	Area:	3500.00 SqFt		PCI:	91		
Sample Comments:										
48	L & T CR	L	7.00 Ft							
57	WEATHERING	L	3500.00 SqFt							

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW E	Name:	TAXIWAY E		Use:	TAXIWAY	Area:	85,361 SqFt	
Section:	515	of	3	From:	-	To:	-	Last Const.:	7/1/2019
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:	Category:		Rank:	P
Area:	2,399 SqFt		Length:	50 Ft		Width:	35 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	1/1/2013		Work Type: New Construction - Initial			Code:	NU-IN	Is Major M&R: True	
Work Date:	7/1/2019		Work Type: Complete Reconstruction - AC			Code:	CR-AC	Is Major M&R: True	
Last Insp. Date:	4/25/2022		TotalSamples:	1		Surveyed:	1		
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	123	Type:	R	Area:	2399.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	2399.00 SqFt					

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT									
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY		Area:	52,701 SqFt				
Section:	605		of	3		From:	-		To:	-		Last Const.:	1/1/1984	
Surface:	AC		Family:	CA653-GA-TW-AC		Zone:			Category:			Rank:	P	
Area:	36,880 SqFt		Length:	922 Ft		Width:	40 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1984		Work Type:	BUILT		Code:	IMPORTED		Is Major M&R:	True				
Last Insp. Date:	4/25/2022		TotalSamples:	9		Surveyed:	2							
Conditions:	PCI:	40												
Inspection Comments:														
Sample Number:	103		Type:	R		Area:	4000.00 SqFt		PCI:	36				
Sample Comments:														
43	BLOCK CR		M	3000.00 SqFt										
48	L & T CR		M	188.00 Ft										
52	RAVELING		L	4000.00 SqFt										
56	SWELLING		L	50.00 SqFt										
Sample Number:	108		Type:	R		Area:	4000.00 SqFt		PCI:	44				
Sample Comments:														
43	BLOCK CR		M	288.00 SqFt										
48	L & T CR		L	56.00 Ft										
48	L & T CR		M	419.00 Ft										
52	RAVELING		L	4000.00 SqFt										
56	SWELLING		L	22.00 SqFt										

Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT				
Branch:	TW F		Name:	TAXIWAY F		Use:	TAXIWAY	Area:	52,701 SqFt
Section:	610	of	3	From:	-		To:	-	Last Const.: 5/1/2022
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:	Category:		Rank:	P
Area:	9,548 SqFt	Length:	117 Ft		Width:	40 Ft			
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:	Ft	
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	1/1/1984		Work Type:			BUILT	Code:	IMPORTED	Is Major M&R: True
Work Date:	5/1/2022		Work Type:			Complete Reconstruction - AC	Code:	CR-AC	Is Major M&R: True
Last Insp. Date:	1/28/2019		TotalSamples:	10		Surveyed:		2	
Conditions:	PCI:	46	NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	103	Type:	R	Area:	4000.00 SqFt		PCI:	37	
Sample Comments:									
43	BLOCK CR	L	1625.00 SqFt						
43	BLOCK CR	M	1625.00 SqFt						
48	L & T CR	L	30.00 Ft						
48	L & T CR	M	30.00 Ft						
52	RAVELING	L	4000.00 SqFt						
56	SWELLING	L	75.00 SqFt						
Sample Number:	108	Type:	R	Area:	4000.00 SqFt		PCI:	55	
Sample Comments:									
43	BLOCK CR	L	230.00 SqFt						
48	L & T CR	L	207.00 Ft						
48	L & T CR	M	188.00 Ft						
52	RAVELING	L	4000.00 SqFt						
56	SWELLING	L	20.00 SqFt						

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT							
Branch:	TW F	Name:	TAXIWAY F		Use:	TAXIWAY	Area:	52,701 SqFt		
Section:	650	of	3	From:	-	To:	-	Last Const.:	1/1/1984	
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:		Category:		Rank:	P
Area:	6,273 SqFt	Length:	130 Ft		Width:	40 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/1984	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True	
Last Insp. Date:	4/25/2022	TotalSamples:	1		Surveyed:	1				
Conditions:	PCI:	35								
Inspection Comments:										
Sample Number:	100	Type:	R	Area:	6273.00 SqFt		PCI:	35		
Sample Comments:										
43	BLOCK CR	L	678.00	SqFt						
43	BLOCK CR	M	2334.00	SqFt						
48	L & T CR	M	70.00	Ft						
50	PATCHING	L	1753.00	SqFt						
52	RAVELING	L	4520.00	SqFt						
56	SWELLING	L	103.00	SqFt						
56	SWELLING	M	36.00	SqFt						



Network:	OMN			Name:	ORMOND BEACH MUNICIPAL AIRPORT				
Branch:	TW G		Name:	TAXIWAY G		Use:	TAXIWAY	Area:	126,774 SqFt
Section:	700	of	1	From:	-	To:	-	Last Const.:	1/1/2016
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:	Category:	Rank:	P	
Area:	126,774 SqFt	Length:	3,580 Ft		Width:	35 Ft			
Slabs:	Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:	Street Type:	Grade:	0		Lanes:	0			
Section Comments:									
Work Date:	1/1/2016		Work Type: New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	4/25/2022		TotalSamples:	35		Surveyed:	4		
Conditions:	PCI:	88							
Inspection Comments:									
Sample Number:	107	Type:	R	Area:	3500.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING	L	3500.00 SqFt						
Sample Number:	115	Type:	R	Area:	5139.00 SqFt		PCI:	81	
Sample Comments:									
45	DEPRESSION	L	60.00 SqFt						
48	L & T CR	L	11.00 Ft						
57	WEATHERING	L	4882.00 SqFt						
57	WEATHERING	M	257.00 SqFt						
Sample Number:	120	Type:	R	Area:	3500.00 SqFt		PCI:	87	
Sample Comments:									
48	L & T CR	L	15.00 Ft						
57	WEATHERING	L	3325.00 SqFt						
57	WEATHERING	M	175.00 SqFt						
Sample Number:	134	Type:	R	Area:	3500.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING	L	3500.00 SqFt						

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW G1	Name:	TAXIWAY G1	Use:	TAXIWAY	Area:	8,543 SqFt		
Section:	715	of	1	From:	-	To:	-	Last Const.:	1/1/2016
Surface:	AC	Family:	CA653-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	8,543 SqFt	Length:	232 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2016	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	4/25/2022	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	91							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	4481.00 SqFt	PCI:	91		
Sample Comments:									
57	WEATHERING	L	4257.00	SqFt					
57	WEATHERING	M	224.00	SqFt					

Network:	OMN	Name:		ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW G2	Name:	TAXIWAY G2		Use:	TAXIWAY	Area:	8,946 SqFt		
Section:	705	of	1	From:	-		To:	-	Last Const.:	1/1/2016
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:	Category:		Rank:		P
Area:	8,946 SqFt		Length:	232 Ft		Width:	35 Ft			
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2016		Work Type:			New Construction - AC		Code:	NC-AC	
								Is Major M&R:		True
Last Insp. Date:	4/25/2022		TotalSamples:	2		Surveyed:	1			
Conditions:	PCI:	88								
Inspection Comments:										
Sample Number:	200	Type:	R		Area:	4078.00 SqFt		PCI:	88	
Sample Comments:										
48	L & T CR		L	2.00 Ft						
57	WEATHERING		L	3874.00 SqFt						
57	WEATHERING		M	204.00 SqFt						

Network:	OMN	Name:		ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW G3	Name:	TAXIWAY G3		Use:	TAXIWAY	Area:	8,941 SqFt		
Section:	710	of	1	From:	-	To:	-	Last Const.:	1/1/2016	
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:	Category:		Rank:	P	
Area:	8,941 SqFt	Length:	232 Ft		Width:	35 Ft				
Slabs:		Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:		Street Type:			Grade:	0		Lanes:	0	
Section Comments:										
Work Date:	1/1/2016	Work Type:			New Construction - AC		Code:	NC-AC	Is Major M&R:	True
Last Insp. Date:	4/25/2022	TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	89								
Inspection Comments:										
Sample Number:	300	Type:	R	Area:	4864.00 SqFt		PCI:	89		
Sample Comments:										
57	WEATHERING	L	4378.00 SqFt							
57	WEATHERING	M	486.00 SqFt							

Network:	OMN	Name:	ORMOND BEACH MUNICIPAL AIRPORT						
Branch:	TW G4	Name:	TAXIWAY G4	Use:	TAXIWAY	Area:	8,529 SqFt		
Section:	720	of	1	From:	-	To:	-	Last Const.:	1/1/2016
Surface:	AC	Family:	CA653-GA-TW-AC	Zone:		Category:		Rank:	P
Area:	8,529 SqFt	Length:	232 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2016	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Last Insp. Date:	4/25/2022	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	91							
Inspection Comments:									
Sample Number:	138	Type:	R	Area:	4049.00 SqFt	PCI:	91		
Sample Comments:									
57	WEATHERING	L	3847.00	SqFt					
57	WEATHERING	M	202.00	SqFt					





FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE



AVIATION