

2022

*Statewide Airfield Pavement Management Program*



# Airport Pavement Evaluation Report

TIX - Space Coast Regional Airport | *District 5*





---

*Florida Department of Transportation*

---

# ***Statewide Airfield Pavement Management Program***

## **Airport Pavement Evaluation Report**

**Prepared by:**

*FDOT Aviation Office  
605 Suwannee Street  
Tallahassee, Florida 32399-0450*

**Website:** [FDOT Aviation Office](#)

**Interactive Web Application:** [FDOT SAPMP Interactive Web Application](#)

# TABLE OF CONTENTS

<b>EXECUTIVE SUMMARY .....</b>	<b>1</b>
<i>Program Background.....</i>	<i>1</i>
<i>Current Pavement Conditions .....</i>	<i>2</i>
<i>Forecasted Pavement Conditions .....</i>	<i>3</i>
<i>Major Rehabilitation Planning 2023-2032 .....</i>	<i>6</i>
<b>CHAPTER 1 – INTRODUCTION.....</b>	<b>9</b>
1.1 Background .....	9
1.2 Stakeholders.....	11
1.3 General Scope of Work .....	11
1.4 FDOT SAPMP Objectives .....	12
<b>CHAPTER 2 – METHODOLOGY.....</b>	<b>15</b>
2.1 Airfield Pavement Database.....	15
2.2 Airfield Pavement Record Keeping (Historical Records Research).....	16
2.3 Airfield Pavement Structure.....	16
2.3.1 Asphalt Concrete.....	17
2.3.2 Portland Cement Concrete .....	17
2.3.3 Composite Structure – Whitetopping Pavement .....	17
2.4 Airfield Pavement Traffic .....	18
2.5 Pavement Management Program Network Definition Terminology .....	18
2.5.1 Pavement Network Identification .....	18
2.5.2 Pavement Branch Identification .....	18
2.5.3 Pavement Section Identification .....	19
2.5.4 Pavement Sample Unit Identification .....	19
2.5.5 Terminology Summary .....	19
2.6 Airfield PCI Survey Methodology .....	19
2.6.1 Pavement Distress Types.....	20
2.6.2 PCI Survey Procedures.....	21
<b>CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY.....</b>	<b>24</b>
3.1 Airfield Pavement Network Information.....	24
3.1.1 Previous and/or Anticipated Airfield Pavement Construction .....	24
3.1.2 Estimated Pavement Age .....	27
3.1.3 Functional Use .....	29
3.1.4 Pavement Surface Type.....	29
3.1.5 Pavement System Inventory Details .....	30
<b>CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS .....</b>	<b>33</b>
4.1 Airfield Pavement Condition Index.....	33
4.1.1 Network-Level Analysis.....	33
4.1.2 Branch-Level Analysis.....	33
4.1.3 Section-Level Analysis .....	36
4.2 Summary of Pavement Condition Evaluation Results .....	40

4.2.1 Network-Level Observations .....	40
4.2.2 Branch-Level Observations .....	40
<b>CHAPTER 5 – SAPMP CUSTOMIZATION.....</b>	<b>48</b>
5.1 Network-Level Customization.....	48
5.2 Pavement Condition Forecasts .....	48
5.2.1 Forecasting PCI Considerations .....	49
5.2.2 Performance Models .....	49
5.2.3 Branch-Level Pavement Condition Forecast.....	49
5.2.4 Section-Level Pavement Condition Forecast.....	50
5.3 Critical PCI Value.....	52
5.4 Localized Maintenance and Repair .....	55
5.4.1 Localized Maintenance and Repair Approach .....	55
5.4.2 Localized Work Types .....	56
5.4.3 Localized Maintenance Planning-Level Unit Costs .....	58
5.4.4 Localized Maintenance and Repair Policy .....	58
5.5 Major Rehabilitation .....	61
5.5.1 Major Rehabilitation Pavement Section Development .....	61
5.5.2 Major Rehabilitation Planning-Level Unit Costs .....	63
<b>CHAPTER 6 – M&amp;R PLANNING AND BUDGET SCENARIO ANALYSIS .....</b>	<b>65</b>
6.1 Localized Maintenance and Repair Analysis and Recommendations .....	65
6.2 Major Rehabilitation Needs.....	67
6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs .....	68
<b>CHAPTER 7 – CONCLUSION.....</b>	<b>72</b>
7.1 Recommendations .....	72
7.1.1 Continued PCI Surveys .....	72
7.1.2 Localized Maintenance and Repair .....	72
7.1.3 Major Rehabilitation.....	72
7.1.4 Pavement Management System.....	72
7.2 Supporting Documents .....	73
Airfield Pavement Network Definition Exhibit.....	73
Airfield Pavement System Inventory Exhibit .....	73
Airfield Pavement Estimated Age Exhibit .....	73
Airfield Pavement Condition Index Exhibit.....	73
Airfield Pavement Major Rehabilitation Exhibit .....	73
Inspection Photograph Documentation.....	73
7.3 Conclusion.....	74
7.4 References .....	74



## **APPENDIX**


*Appendix A: Airfield Pavement Analysis*

*Appendix B: Maintenance and Rehabilitation Planning Needs*

*Appendix C: Technical Exhibits*

*Appendix D: Inspection Photograph Documentation*

*Appendix E: Inspection Distress Details*



## LIST OF TABLES

Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level.....	2
Table E.2: Forecasted PCI Values 2023-2032 – Section-Level.....	4
Table E.3: Major Rehabilitation Planning 2023-2032.....	6
Table 1.2: FDOT SAPMP Stakeholders .....	11
Table 2.5.5: SAPMP Terminology .....	19
Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete .....	20
Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete.....	21
Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete.....	21
Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete .....	22
Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction .....	24
Table 3.1.5: Pavement System Inventory Details .....	30
Table 4.1.2: Current Condition Summary – Branch-Level .....	36
Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level.....	37
Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level .....	50
Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects.....	53
Table 5.3 (b): Critical PCI Values by Branch Use .....	53
Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete .....	58
Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete.....	58
Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy .....	59
Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy .....	60
Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation .....	62
Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type .....	63
Table 6.1 (a): Year 1 Summary of Localized Maintenance .....	65
Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary .....	66
Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary .....	66
Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs .....	68



## LIST OF FIGURES

Figure E.1: PCI Rating .....	1
Figure E.2: Current Condition Summary – Branch-Level .....	2
Figure E.3: 10-Year Major Rehabilitation Needs by Program Year .....	7
Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts .....	10
Figure 1.4: Pavement Life and the Effect of Treatments .....	13
Figure 2: FDOT SAPMP General Process .....	15
Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit .....	25
Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit .....	26
Figure 3.1.2 (a): Age of Pavements at PCI Survey .....	27
Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit .....	28
Figure 3.1.3: Airfield Pavement Branch Use by Area (SF) .....	29
Figure 3.1.4: Airfield Pavement Surface Type by Area (SF) .....	30
Figure 4.1.1: Current Condition – Overall Network .....	33
Figure 4.1.2 (a): Current Condition Summary – Branch-Level .....	33
Figure 4.1.2 (b): Current Condition – Runway .....	34
Figure 4.1.2 (c): Current Condition – Taxiway .....	34
Figure 4.1.2 (d): Current Condition – Apron .....	35
Figure 4.1.3: Airfield Pavement Condition Index Exhibit .....	39
Figure 5.2.3: Forecasted Branch-Level Pavement Performance .....	49
Figure 5.3 (a): Pavement Life and the Effect of Treatments .....	52
Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical PCI}$ .....	54
Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical PCI}$ .....	54
Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year .....	69
Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit .....	70



# Executive Summary





# Executive Summary

## Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Space Coast Regional Airport's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section. This is graphically depicted in **Figure E.1**.


*Figure E.1: PCI Rating*

Color	Range	Condition Rating
	86-100	Good
	71-85	Satisfactory
	56-70	Fair
	41-55	Poor
	26-40	Very Poor
	11-25	Serious
	0-10	Failed

## Current Pavement Conditions

In April 2022, approximately 4.1 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Space Coast Regional Airport (TIX). In general, airfield pavements at TIX are in Satisfactory condition with an area-weighted PCI of 74. The area-weighted average PCI values of the runways, taxiways, and aprons are 69, 66, and 86, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for TIX.

*Figure E.2: Current Condition Summary – Branch-Level*



*Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
TIX	RW 9-27	Runway	6205	67,743	53	Poor
TIX	RW 9-27	Runway	6210	320,000	100	Good
TIX	RW 9-27	Runway	6215	102,000	100	Good
TIX	RW 18-36	Runway	6105	500,000	58	Fair
TIX	RW 18-36	Runway	6110	250,000	57	Fair
TIX	RW 18-36	Runway	6125	100,000	55	Poor
TIX	RW 18-36	Runway	6130	50,000	59	Fair
TIX	RW 18-36	Runway	6145	131,900	60	Fair
TIX	RW 18-36	Runway	6150	65,950	63	Fair
TIX	TW A	Taxiway	105	114,651	59	Fair
TIX	TW A	Taxiway	110	70,000	62	Fair
TIX	TW A	Taxiway	112	30,000	59	Fair
TIX	TW A	Taxiway	115	50,000	57	Fair
TIX	TW A	Taxiway	120	40,007	65	Fair
TIX	TW A1	Taxiway	130	50,631	49	Poor
TIX	TW A2	Taxiway	125	35,137	61	Fair
TIX	TW B	Taxiway	205	22,146	53	Poor



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
TIX	TW B	Taxiway	210	223,574	84	Satisfactory
TIX	TW B	Taxiway	215	11,820	100	Good
TIX	TW C	Taxiway	305	46,879	57	Fair
TIX	TW C	Taxiway	310	116,660	60	Fair
TIX	TW C	Taxiway	315	15,628	87	Good
TIX	TW C	Taxiway	320	3,845	55	Poor
TIX	TW C	Taxiway	325	17,228	100	Good
TIX	TW D	Taxiway	405	33,961	65	Fair
TIX	TW D	Taxiway	410	73,750	65	Fair
TIX	TW E	Taxiway	505	32,371	72	Satisfactory
TIX	TW E	Taxiway	515	44,841	64	Fair
TIX	TW E	Taxiway	525	8,165	92	Good
TIX	TW E	Taxiway	535	68,681	70	Fair
TIX	TW F	Taxiway	605	30,388	14	Serious
TIX	AP E	Apron	4205	100,353	60	Fair
TIX	AP E	Apron	4214	52,187	55	Poor
TIX	AP E	Apron	4215	77,281	63	Fair
TIX	AP E	Apron	4216	48,812	81	Satisfactory
TIX	AP E	Apron	4218	94,806	77	Satisfactory
TIX	AP E	Apron	4219	8,237	57	Fair
TIX	AP E	Apron	4220	33,963	77	Satisfactory
TIX	AP E	Apron	4221	5,405	69	Fair
TIX	AP E	Apron	4225	8,700	65	Fair
TIX	AP E	Apron	4229	16,379	87	Good
TIX	AP E	Apron	4230	9,662	76	Satisfactory
TIX	AP E	Apron	4232	10,659	78	Satisfactory
TIX	AP E	Apron	4235	93,090	99	Good
TIX	AP E	Apron	4240	15,772	84	Satisfactory
TIX	AP E	Apron	4245	7,200	71	Satisfactory
TIX	AP E	Apron	4250	38,220	94	Good
TIX	AP HELI	Apron	4255	32,798	86	Good
TIX	AP HELI	Apron	4260	364,740	95	Good
TIX	AP W	Apron	4305	370,471	97	Good
TIX	AP W	Apron	4310	30,464	71	Satisfactory

## Forecasted Pavement Conditions

**Table E.2** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

*Table E.2: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
TIX	RW 9-27	6205	53	51	49	47	45	43	41	39	37	35	33
TIX	RW 9-27	6210	100	98	96	94	92	90	88	86	84	82	80
TIX	RW 9-27	6215	100	98	96	94	92	90	88	86	84	82	80
TIX	RW 18-36	6105	58	56	54	52	50	48	46	44	42	40	38
TIX	RW 18-36	6110	57	55	53	51	49	47	45	43	41	39	37
TIX	RW 18-36	6125	55	53	51	49	47	45	43	41	39	37	35
TIX	RW 18-36	6130	59	57	55	53	51	49	47	45	43	41	39
TIX	RW 18-36	6145	60	58	56	54	52	50	48	46	44	42	40
TIX	RW 18-36	6150	63	61	59	57	55	53	51	49	47	45	43
TIX	TW A	105	59	57	56	54	53	51	49	48	46	43	41
TIX	TW A	110	62	60	59	58	56	55	53	52	50	48	46
TIX	TW A	112	59	57	56	54	53	51	49	48	46	43	41
TIX	TW A	115	57	55	54	52	50	49	47	45	43	40	38
TIX	TW A	120	65	63	62	61	60	58	57	55	54	52	51
TIX	TW A1	130	49	47	45	43	40	38	35	33	30	27	25
TIX	TW A2	125	61	59	58	57	55	54	52	50	48	47	45
TIX	TW B	205	53	51	49	47	45	43	41	39	36	34	31
TIX	TW B	210	84	82	80	78	77	75	74	73	71	70	69
TIX	TW B	215	100	97	94	92	90	87	85	83	82	80	78
TIX	TW C	305	57	55	54	52	50	49	47	45	43	40	38
TIX	TW C	310	60	58	57	55	54	52	51	49	47	45	43
TIX	TW C	315	87	85	83	81	79	78	76	75	73	72	71
TIX	TW C	320	55	53	51	50	48	46	44	42	39	37	34
TIX	TW C	325	100	97	94	92	90	87	85	83	82	80	78
TIX	TW D	405	65	63	62	61	60	58	57	55	54	52	51
TIX	TW D	410	65	63	62	61	60	58	57	55	54	52	51
TIX	TW E	505	72	70	69	68	67	65	64	63	62	60	59
TIX	TW E	515	64	62	61	60	59	57	56	54	53	51	49
TIX	TW E	525	92	89	87	85	84	82	80	78	77	75	74
TIX	TW E	535	70	68	67	66	65	63	62	61	60	58	57
TIX	TW F	605	14	11	8	6	3	0	0	0	0	0	0
TIX	AP E	4205	60	58	56	54	52	50	48	46	44	42	40
TIX	AP E	4214	55	53	51	49	47	45	43	41	39	37	35
TIX	AP E	4215	63	61	60	59	58	57	56	55	54	53	52
TIX	AP E	4216	81	79	77	75	73	71	69	67	65	63	61
TIX	AP E	4218	77	75	73	71	69	67	65	63	61	59	57
TIX	AP E	4219	57	55	53	51	49	47	45	43	41	39	37
TIX	AP E	4220	77	75	73	71	69	67	65	63	61	59	57
TIX	AP E	4221	69	67	66	64	63	62	61	59	58	57	56
TIX	AP E	4225	65	64	63	62	61	60	59	58	57	56	55
TIX	AP E	4229	87	84	82	80	79	77	75	73	72	70	69
TIX	AP E	4230	76	75	74	73	72	71	70	69	68	67	66
TIX	AP E	4232	78	76	74	72	70	68	66	64	62	60	58
TIX	AP E	4235	99	98	97	96	95	94	93	92	91	90	89



# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
TIX	AP E	4240	84	82	80	78	76	74	72	70	68	66	64
TIX	AP E	4245	71	69	68	66	65	63	62	61	60	59	58
TIX	AP E	4250	94	93	92	91	90	89	88	87	86	85	84
TIX	AP HELI	4255	86	83	81	80	78	76	74	72	71	69	68
TIX	AP HELI	4260	95	94	93	92	91	90	89	88	87	86	85
TIX	AP W	4305	97	96	95	94	93	92	91	90	89	88	87
TIX	AP W	4310	71	69	67	65	63	61	59	57	55	53	51

## Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$29.94M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$23.59M and localized maintenance needs for Year 1 are \$0.44M.


*Table E.3: Major Rehabilitation Planning 2023-2032*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	TIX	RW 9-27	6205	AAC	67,743	51	AC Reconstruction	\$ 1,084,000
2023	TIX	RW 18-36	6105	AAC	500,000	56	AC Rehabilitation	\$ 4,501,000
2023	TIX	RW 18-36	6110	AAC	250,000	55	AC Reconstruction	\$ 2,881,000
2023	TIX	RW 18-36	6125	AAC	100,000	53	AC Reconstruction	\$ 1,600,000
2023	TIX	RW 18-36	6130	AAC	50,000	57	AC Rehabilitation	\$ 451,000
2023	TIX	RW 18-36	6145	AAC	131,900	58	AC Rehabilitation	\$ 1,188,000
2023	TIX	RW 18-36	6150	AAC	65,950	61	AC Rehabilitation	\$ 594,000
2023	TIX	TW A	105	AAC	114,651	57	AC Rehabilitation	\$ 1,032,000
2023	TIX	TW A	110	AAC	70,000	60	AC Rehabilitation	\$ 631,000
2023	TIX	TW A	112	AAC	30,000	57	AC Rehabilitation	\$ 271,000
2023	TIX	TW A	115	AAC	50,000	55	AC Rehabilitation	\$ 451,000
2023	TIX	TW A	120	AAC	40,007	63	AC Rehabilitation	\$ 361,000
2023	TIX	TW A1	130	AAC	50,631	47	AC Reconstruction	\$ 811,000
2023	TIX	TW A2	125	AAC	35,137	59	AC Rehabilitation	\$ 317,000
2023	TIX	TW B	205	AAC	22,146	51	AC Reconstruction	\$ 355,000
2023	TIX	TW C	305	AAC	46,879	55	AC Rehabilitation	\$ 422,000
2023	TIX	TW C	310	AAC	116,660	58	AC Rehabilitation	\$ 1,050,000
2023	TIX	TW C	320	AAC	3,845	53	AC Reconstruction	\$ 62,000
2023	TIX	TW D	405	AAC	33,961	63	AC Rehabilitation	\$ 306,000
2023	TIX	TW D	410	AAC	73,750	63	AC Rehabilitation	\$ 664,000
2023	TIX	TW E	515	AAC	44,841	62	AC Rehabilitation	\$ 404,000

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	TIX	TW E	535	AAC	68,681	68	AC Rehabilitation	\$ 619,000
2023	TIX	TW F	605	AAC	30,388	11	AC Reconstruction	\$ 487,000
2023	TIX	AP E	4205	AAC	100,353	58	AC Rehabilitation	\$ 904,000
2023	TIX	AP E	4214	APC	52,187	53	AC Reconstruction	\$ 835,000
2023	TIX	AP E	4215	AC	77,281	61	AC Rehabilitation	\$ 696,000
2023	TIX	AP E	4219	AAC	8,237	55	AC Reconstruction	\$ 95,000
2023	TIX	AP E	4221	AC	5,405	67	AC Rehabilitation	\$ 49,000
2023	TIX	AP E	4225	PCC	8,700	64	PCC Rehabilitation	\$ 131,000
2023	TIX	AP E	4245	AC	7,200	69	AC Rehabilitation	\$ 65,000
2023	TIX	AP W	4310	AAC	30,464	69	AC Rehabilitation	\$ 275,000
2024	TIX	TW E	505	AAC	32,371	69	AC Rehabilitation	\$ 306,000
2026	TIX	AP E	4218	AAC	94,806	69	AC Rehabilitation	\$ 988,000
2026	TIX	AP E	4220	AAC	33,963	69	AC Rehabilitation	\$ 354,000
2026	TIX	AP E	4232	AAC	10,659	70	AC Rehabilitation	\$ 112,000
2028	TIX	AP E	4216	AAC	48,812	69	AC Rehabilitation	\$ 561,000
2029	TIX	AP E	4230	PCC	9,662	69	PCC Rehabilitation	\$ 195,000
2029	TIX	AP E	4240	AAC	15,772	70	AC Rehabilitation	\$ 191,000
2031	TIX	TW B	210	AAC	223,574	70	AC Rehabilitation	\$ 2,974,000
2031	TIX	AP HELI	4255	AC	32,798	69	AC Rehabilitation	\$ 437,000
2032	TIX	AP E	4229	AC	16,379	69	AC Rehabilitation	\$ 229,000

\*All planning cost values have been rounded up to the nearest thousand dollars.

Figure E.3: 10-Year Major Rehabilitation Needs by Program Year







# Chapter 1: Introduction



# Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration’s (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida’s economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida’s system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida’s most prominent industry.

## 1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.

There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C “Guidelines and Procedures for Maintenance of Airport Pavements” and 150/5380-7B “Airport Pavement Management Program (PMP)”. The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 “Standard Test Method for Airport Pavement Condition Index Surveys”.

In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 “Pavement Maintenance,” No. 34 “Policies, Standards, and Specifications,” and PFC Assurance No. 9 “Standards and Specifications.” The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are




## Airport Pavement Evaluation Report

### Statewide Airfield Pavement Management Program

under consideration for projects. A network-level evaluation can support the identification of maintenance, repair, and major rehabilitation needs and budgetary planning-level opinions of probable construction costs.

*Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts*



## 1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

*Table 1.2: FDOT SAPMP Stakeholders*

Role	Description
<b>FAA Orlando Airports District Office (Orlando ADO)</b>	Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation).
<b>Florida Department of Transportation (FDOT)</b>	Key Stakeholder: the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System.
<b>FDOT District Offices</b>	The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes.
<b>Participating Public-Use and Publicly-Owned Airports</b>	The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment.
<b>Aviation Office Program Manager (AO-PM)</b>	FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update.

## 1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- » Research and evaluation of existing record documentation;
- » Establishment of a pavement system inventory;
- » Development of a pavement network definition map and supplemental GIS model;
- » Functional pavement evaluations via the PCI assessment method;
- » Customization of PAVER™ software including prioritization, policies, and performance models;
- » Analysis of condition data; and
- » Maintenance, repair, and rehabilitation planning.

## 1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.

A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:


- » Assist airports in meeting the requirements of Public Law 103-305;
- » Assist airports in complying with FAA Grant Assurances 11 and 19;
- » Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- » Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- » Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.



*Figure 1.4: Pavement Life and the Effect of Treatments*



FAA Eligibility Thresholds: ☐ >70: Routine Maintenance ☐ 55-70: Rehabilitation Eligible ☐ <55: Reconstruction Eligible

*\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements*




## Chapter 2: Methodology



## Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.

*Figure 2: FDOT SAPMP General Process*



### 2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- » Create a manageable inventory system;
- » Analyze the current condition of pavements in accordance with ASTM D5340-20;
- » Develop pavement performance models to forecast conditions; and
- » Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database and typically consist of pavement inventory



characteristics, pavement structure, work history, historic condition records, and analytical customization.

## 2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- » Location and limits of work;
- » Types and severities of repaired distresses;
- » Work type and cost; and
- » Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- » Date of last construction/rehabilitation
- » Work type performed
- » Comments for documenting pavement cross-section
- » Pavement surface type
- » Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

## 2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.

### 2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

#### **Asphalt Concrete (AC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

#### **Asphalt Concrete Overlaid on Asphalt Concrete (AAC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

#### **Asphalt Concrete Overlaid on Portland Cement Concrete (APC)**

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

### 2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

#### **Portland Cement Concrete (PCC)**

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

### 2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

#### **Conventional Whitetopping (WT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.

### **Thin Whitetopping (TWT)**

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

### **Ultra-Thin Whitetopping (UWT)**

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

## **2.4 Airfield Pavement Traffic**

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of TIX's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

## **2.5 Pavement Management Program Network Definition Terminology**

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

### **2.5.1 Pavement Network Identification**

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

### **2.5.2 Pavement Branch Identification**

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.



### 2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

### 2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs ( $\pm 8$  slabs) for PCC pavement and 5,000 contiguous square feet ( $\pm 2,000$  SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

### 2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

*Table 2.5.5: SAPMP Terminology*

SAPMP Terminology	Common Definition	Airport Example
<b>Network</b>	Totality of pavement assets maintained by the Airport.	"Tallahassee International Airport – Airfield Pavements"
<b>Branch Name</b>	Commonly defined asset name as established by Airport and by use.	"Runway 18-36"
<b>Branch ID</b>	Codified shorthand name for commonly defined asset established for database identification.	"RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility
<b>Section ID</b>	Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition.	"6105"
<b>Sample Unit</b>	A numeric identification of an area of pavement (5,000 $\pm$ 2,000 SF of AC or 20 $\pm$ 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20.	"300"

## 2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

### 2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

*Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete*

Distress Mechanism	Distress Type
Load	Alligator Cracking Rutting
Climate/Durability	Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering
Construction/Material	Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling
Other	Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching

*Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete*

Distress Mechanism	Distress Type
Load	Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks
Climate/Durability	Blowup Durability "D" Cracking Joint Seal Damage Popouts
Construction/Material	Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking
Other	Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching

### 2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.

*Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete*


Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10




*Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete*

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.



# **Chapter 3: Airfield Pavement System Inventory**



## Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

### 3.1 Airfield Pavement Network Information

#### 3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.


*Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction*

Construction Year	Location	Work Type / Pavement Section
2022	RW 9-27, TW B, TW C	Mill and Overlay

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

**Figure 3.1.1 (a)**, the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.







## LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- PAVEMENT SURFACE TYPE  
PAVEMENT BRANCH ID  
SECTION NUMBER
- NUMBER OF SAMPLE UNITS IN SECTION  
NUMBER OF SAMPLE UNITS TO BE INSPECTED
- SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- INSPECTED SAMPLE UNITS.


TOTAL SAMPLES INSPECTED = 141  
AC: 115 PCC: 26

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2022	RW 9-27, TW B, TW C	Mill and Overlay



**LEGEND**

TYPICAL RUNWAY BRANCH ID

TYPICAL TAXIWAY BRANCH ID

TYPICAL APRON BRANCH ID


**PROJECT YEAR**


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

### 3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.

*Figure 3.1.2 (a): Age of Pavements at PCI Survey*








AIRFIELD PAVEMENT  
ESTIMATED AGE EXHIBIT

Statewide Airfield Pavement  
Management Program  
SPACE COAST REGIONAL AIRPORT



**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID  
TW A — TYPICAL TAXIWAY BRANCH ID  
AP S — TYPICAL APRON BRANCH ID

**AGE AT INSPECTION**


0-5 Years
6-10 Years
11-15 Years
16-20 Years
> 20 Years

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

### 3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed “functional use” or “branch use.” For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.

*Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)*




### 3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at TIX.

Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)



### 3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

**Table 3.1.5** displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

Table 3.1.5: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
TIX	RW 9-27	Runway	6205	67,743	AAC	6/1/2002
TIX	RW 9-27	Runway	6210	320,000	AAC	5/1/2022
TIX	RW 9-27	Runway	6215	102,000	AAC	5/1/2022
TIX	RW 18-36	Runway	6105	500,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6110	250,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6125	100,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6130	50,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6145	131,900	AAC	6/1/2002



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
TIX	RW 18-36	Runway	6150	65,950	AAC	6/1/2002
TIX	TW A	Taxiway	105	114,651	AAC	6/1/2002
TIX	TW A	Taxiway	110	70,000	AAC	6/1/2002
TIX	TW A	Taxiway	112	30,000	AAC	6/1/2002
TIX	TW A	Taxiway	115	50,000	AAC	6/1/2002
TIX	TW A	Taxiway	120	40,007	AAC	6/1/2002
TIX	TW A1	Taxiway	130	50,631	AAC	6/1/2002
TIX	TW A2	Taxiway	125	35,137	AAC	6/1/2002
TIX	TW B	Taxiway	205	22,146	AAC	6/1/2002
TIX	TW B	Taxiway	210	223,574	AAC	1/1/2013
TIX	TW B	Taxiway	215	11,820	AAC	5/1/2022
TIX	TW C	Taxiway	305	46,879	AAC	1/1/2004
TIX	TW C	Taxiway	310	116,660	AAC	1/1/1986
TIX	TW C	Taxiway	315	15,628	AAC	1/1/2013
TIX	TW C	Taxiway	320	3,845	AAC	6/1/2002
TIX	TW C	Taxiway	325	17,228	AAC	5/1/2022
TIX	TW D	Taxiway	405	33,961	AAC	1/1/2000
TIX	TW D	Taxiway	410	73,750	AAC	1/1/2000
TIX	TW E	Taxiway	505	32,371	AAC	1/1/1998
TIX	TW E	Taxiway	515	44,841	AAC	1/1/2003
TIX	TW E	Taxiway	525	8,165	AC	1/1/2014
TIX	TW E	Taxiway	535	68,681	AAC	1/1/2003
TIX	TW F	Taxiway	605	30,388	AAC	1/1/1998
TIX	AP E	Apron	4205	100,353	AAC	1/1/2008
TIX	AP E	Apron	4214	52,187	APC	6/1/2002
TIX	AP E	Apron	4215	77,281	AC	1/1/1971
TIX	AP E	Apron	4216	48,812	AAC	1/1/2008
TIX	AP E	Apron	4218	94,806	AAC	1/1/2008
TIX	AP E	Apron	4219	8,237	AAC	1/1/2015
TIX	AP E	Apron	4220	33,963	AAC	1/1/2014
TIX	AP E	Apron	4221	5,405	AC	1/1/2008
TIX	AP E	Apron	4225	8,700	PCC	1/1/1991
TIX	AP E	Apron	4229	16,379	AC	1/1/2012
TIX	AP E	Apron	4230	9,662	PCC	1/1/1991
TIX	AP E	Apron	4232	10,659	AAC	1/1/2014
TIX	AP E	Apron	4235	93,090	PCC	1/1/2015
TIX	AP E	Apron	4240	15,772	AAC	1/1/2014
TIX	AP E	Apron	4245	7,200	AC	1/1/2003
TIX	AP E	Apron	4250	38,220	PCC	1/1/2011
TIX	AP HELI	Apron	4255	32,798	AC	1/1/2012
TIX	AP HELI	Apron	4260	364,740	PCC	1/1/2012
TIX	AP W	Apron	4305	370,471	PCC	1/1/2014
TIX	AP W	Apron	4310	30,464	AAC	1/1/2014

A photograph of a long, straight asphalt runway stretching towards the horizon under a bright blue sky filled with fluffy white clouds. The runway has a central white dashed line and yellow dashed lines on the sides. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Chapter 4: Airfield Pavement Condition Analysis**

A close-up, low-angle view of the runway pavement, showing the texture of the asphalt and the white dashed center line. A yellow chevron marking is visible on the right side of the frame.A thick red diagonal bar running from the bottom left towards the top right, partially overlapping the runway image.

## Chapter 4 – Airfield Pavement Condition Analysis


The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for design-and/or project-level determination of pavement rehabilitation needs.

### 4.1 Airfield Pavement Condition Index

#### 4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 46% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 46% of inspected pavements are in Fair condition and the remaining 8% of inspected pavements are in Poor or worse condition.

*Figure 4.1.1: Current Condition – Overall Network*



#### 4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(d)** summarize branch-level pavement conditions according to the most recent PCI assessment results.

*Figure 4.1.2 (a): Current Condition Summary – Branch-Level*






Figure 4.1.2 (b): Current Condition – Runway






Figure 4.1.2 (c): Current Condition – Taxiway



*Figure 4.1.2 (d): Current Condition – Apron*



**Table 4.1.2** details the branch-level condition for each airfield pavement branch.

*Table 4.1.2: Current Condition Summary – Branch-Level*

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
RW 9-27	Runway	3	489,743	93	Good
RW 18-36	Runway	6	1,097,850	58	Fair
TW A	Taxiway	5	304,658	60	Fair
TW A1	Taxiway	1	50,631	49	Poor
TW A2	Taxiway	1	35,137	61	Fair
TW B	Taxiway	3	257,540	82	Satisfactory
TW C	Taxiway	5	200,240	65	Fair
TW D	Taxiway	2	107,711	65	Fair
TW E	Taxiway	4	154,058	70	Fair
TW F	Taxiway	1	30,388	14	Serious
AP E	Apron	16	620,726	75	Satisfactory
AP HELI	Apron	2	397,538	94	Good
AP W	Apron	2	400,935	95	Good

#### 4.1.3 Section-Level Analysis

**Table 4.1.3** provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.

Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.





Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
TIX	RW 9-27	Runway	6205	67,743	AAC	53	Poor	100	0	0	3	14
TIX	RW 9-27	Runway	6210	320,000	AAC	100	Good	0	0	0	0	0
TIX	RW 9-27	Runway	6215	102,000	AAC	100	Good	0	0	0	0	0
TIX	RW 18-36	Runway	6105	500,000	AAC	58	Fair	99	0	1	20	100
TIX	RW 18-36	Runway	6110	250,000	AAC	57	Fair	86	0	14	10	50
TIX	RW 18-36	Runway	6125	100,000	AAC	55	Poor	98	0	2	5	20
TIX	RW 18-36	Runway	6130	50,000	AAC	59	Fair	96	0	4	2	10
TIX	RW 18-36	Runway	6145	131,900	AAC	60	Fair	97	0	3	5	26
TIX	RW 18-36	Runway	6150	65,950	AAC	63	Fair	100	0	0	3	14
TIX	TW A	Taxiway	105	114,651	AAC	59	Fair	96	0	4	4	22
TIX	TW A	Taxiway	110	70,000	AAC	62	Fair	98	0	2	3	14
TIX	TW A	Taxiway	112	30,000	AAC	59	Fair	99	0	1	2	6
TIX	TW A	Taxiway	115	50,000	AAC	57	Fair	98	0	2	2	10
TIX	TW A	Taxiway	120	40,007	AAC	65	Fair	98	0	2	2	8
TIX	TW A1	Taxiway	130	50,631	AAC	49	Poor	94	0	6	1	9
TIX	TW A2	Taxiway	125	35,137	AAC	61	Fair	96	0	4	2	7
TIX	TW B	Taxiway	205	22,146	AAC	53	Poor	100	0	0	1	4
TIX	TW B	Taxiway	210	223,574	AAC	84	Satisfactory	91	0	9	6	45
TIX	TW B	Taxiway	215	11,820	AAC	100	Good	0	0	0	0	0
TIX	TW C	Taxiway	305	46,879	AAC	57	Fair	96	0	4	2	9
TIX	TW C	Taxiway	310	116,660	AAC	60	Fair	100	0	0	4	24
TIX	TW C	Taxiway	315	15,628	AAC	87	Good	100	0	0	1	3
TIX	TW C	Taxiway	320	3,845	AAC	55	Poor	96	0	4	1	1
TIX	TW C	Taxiway	325	17,228	AAC	100	Good	0	0	0	0	0
TIX	TW D	Taxiway	405	33,961	AAC	65	Fair	100	0	0	1	7
TIX	TW D	Taxiway	410	73,750	AAC	65	Fair	100	0	0	3	15
TIX	TW E	Taxiway	505	32,371	AAC	72	Satisfactory	100	0	0	2	6
TIX	TW E	Taxiway	515	44,841	AAC	64	Fair	95	0	5	2	8
TIX	TW E	Taxiway	525	8,165	AC	92	Good	100	0	0	1	2
TIX	TW E	Taxiway	535	68,681	AAC	70	Fair	100	0	0	3	19
TIX	TW F	Taxiway	605	30,388	AAC	14	Serious	73	27	0	2	6
TIX	AP E	Apron	4205	100,353	AAC	60	Fair	97	0	3	3	20
TIX	AP E	Apron	4214	52,187	APC	55	Poor	100	0	0	2	13
TIX	AP E	Apron	4215	77,281	AC	63	Fair	64	0	36	3	19
TIX	AP E	Apron	4216	48,812	AAC	81	Satisfactory	100	0	0	1	9
TIX	AP E	Apron	4218	94,806	AAC	77	Satisfactory	96	0	4	3	18
TIX	AP E	Apron	4219	8,237	AAC	57	Fair	100	0	0	1	2
TIX	AP E	Apron	4220	33,963	AAC	77	Satisfactory	100	0	0	2	9
TIX	AP E	Apron	4221	5,405	AC	69	Fair	100	0	0	1	1
TIX	AP E	Apron	4225	8,700	PCC	65	Fair	0	78	22	1	2
TIX	AP E	Apron	4229	16,379	AC	87	Good	100	0	0	1	3
TIX	AP E	Apron	4230	9,662	PCC	76	Satisfactory	0	83	17	1	5
TIX	AP E	Apron	4232	10,659	AAC	78	Satisfactory	100	0	0	1	3

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
TIX	AP E	Apron	4235	93,090	PCC	99	Good	0	0	100	3	22
TIX	AP E	Apron	4240	15,772	AAC	84	Satisfactory	100	0	0	1	5
TIX	AP E	Apron	4245	7,200	AC	71	Satisfactory	100	0	0	1	2
TIX	AP E	Apron	4250	38,220	PCC	94	Good	0	0	100	2	12
TIX	AP HELI	Apron	4255	32,798	AC	86	Good	100	0	0	1	5
TIX	AP HELI	Apron	4260	364,740	PCC	95	Good	27	0	73	10	97
TIX	AP W	Apron	4305	370,471	PCC	97	Good	44	0	56	9	88
TIX	AP W	Apron	4310	30,464	AAC	71	Satisfactory	100	0	0	1	9

\* Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.



112 PCI = 59	315 PCI = 87	320 PCI = 55	325 PCI = 100
525 PCI = 92	4214 PCI = 55	4216 PCI = 81	4218 PCI = 77
4219 PCI = 57	4220 PCI = 77	4232 PCI = 78	4250 PCI = 94

**LEGEND**

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID

**2022 PAVEMENT CONDITION INDEX**

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

"SECTION ID"  
"PCI VALUE"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

## 4.2 Summary of Pavement Condition Evaluation Results

### 4.2.1 Network-Level Observations

The PCI assessment for Space Coast Regional Airport (TIX) was performed in April 2022. The overall area-weighted average PCI value of the network was 74, representing a condition rating of Satisfactory. The majority of Runway 9-27 and a small portion of Taxiway B and Taxiway C were not inspected due to an ongoing rehabilitation project at the time of inspection.

Based on the FAA 5010 Report as of 10/31/2022, the Airport has reported 82,414 operations for 12 months ending 12/31/2021.

### 4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

#### Runways

##### **RW 9-27**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 9-27	RUNWAY	3	489,743	93	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 86% Good (86-100 PCI), 14% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6205	AAC	67,743	53	Poor
6210	AAC	320,000	100	Good
6215	AAC	102,000	100	Good


RW 9-27 consists of 3 flexible pavement sections, totaling 489,743 sf. The last major construction dates range from 2002 to 2022, resulting in an area-weighted average age at inspection of 3 years old. Overall, RW 9-27 is in Good condition with an area-weighted average PCI of 93.



### RW 18-36

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 18-36	RUNWAY	6	1,097,850	58	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 91% Fair (56-70 PCI), 9% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6105	AAC	500,000	58	Fair
6110	AAC	250,000	57	Fair
6125	AAC	100,000	55	Poor
6130	AAC	50,000	59	Fair
6145	AAC	131,900	60	Fair
6150	AAC	65,950	63	Fair


RW 18-36 consists of 6 flexible pavement sections, totaling 1,097,850 sf. The last major construction date for the branch was 2002, resulting in an area-weighted average age at inspection of 20 years old. Overall, RW 18-36 is in Fair condition with an area-weighted average PCI of 58.

### Taxiways

#### TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	5	304,658	60	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
105	AAC	114,651	59	Fair
110	AAC	70,000	62	Fair
112	AAC	30,000	59	Fair
115	AAC	50,000	57	Fair
120	AAC	40,007	65	Fair

TW A consists of 5 flexible pavement sections, totaling 304,658 sf. The last major construction date for the branch was 2002, resulting in an area-weighted average age at inspection of 20 years old. Overall, TW A is in Fair condition with an area-weighted average PCI of 60.

### **TW A1**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A1	TAXIWAY	1	50,631	49	Poor

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Poor (41-55 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
130	AAC	50,631	49	Poor

TW A1 consists of 1 flexible pavement section, totaling 50,631 sf. The last major construction date for the branch was 2002, resulting in an area-weighted average age at inspection of 20 years old. Overall, TW A1 is in Poor condition with an area-weighted average PCI of 49.

### **TW B**

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW B	TAXIWAY	3	257,540	82	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 5% Good (86-100 PCI), 87% Satisfactory (71-85 PCI), 8% Poor (41-55 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
205	AAC	22,146	53	Poor
210	AAC	223,574	84	Satisfactory
215	AAC	11,820	100	Good

TW B consists of 3 flexible pavement sections, totaling 257,540 sf. The last major construction dates range from 2002 to 2022, resulting in an area-weighted average age at inspection of 10 years old. Overall, TW B is in Satisfactory condition with an area-weighted average PCI of 82.

### TW C

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW C	TAXIWAY	5	200,240	65	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 16% Good (86-100 PCI), 82% Fair (56-70 PCI), 2% Poor (41-55 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
305	AAC	46,879	57	Fair
310	AAC	116,660	60	Fair
315	AAC	15,628	87	Good
320	AAC	3,845	55	Poor
325	AAC	17,228	100	Good

TW C consists of 5 flexible pavement sections, totaling 200,240 sf. The last major construction dates range from 1986 to 2022, resulting in an area-weighted average age at inspection of 27 years old. Overall, TW C is in Fair condition with an area-weighted average PCI of 65.

## TW F

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW F	TAXIWAY	1	30,388	14	Serious

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Serious (11-25 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
605	AAC	30,388	14	Serious


TW F consists of 1 flexible pavement section, totaling 30,388 sf. The last major construction date for the branch was 1998, resulting in an area-weighted average age at inspection of 24 years old. Overall, TW F is in Serious condition with an area-weighted average PCI of 14.

## Aprons

### AP E

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP E	APRON	16	620,726	75	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 24% Good (86-100 PCI), 36% Satisfactory (71-85 PCI), 32% Fair (56-70 PCI), 8% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4205	AAC	100,353	60	Fair
4214	APC	52,187	55	Poor
4215	AC	77,281	63	Fair
4216	AAC	48,812	81	Satisfactory




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4218	AAC	94,806	77	Satisfactory
4219	AAC	8,237	57	Fair
4220	AAC	33,963	77	Satisfactory
4221	AC	5,405	69	Fair
4225	PCC	8,700	65	Fair
4229	AC	16,379	87	Good
4230	PCC	9,662	76	Satisfactory
4232	AAC	10,659	78	Satisfactory
4235	PCC	93,090	99	Good
4240	AAC	15,772	84	Satisfactory
4245	AC	7,200	71	Satisfactory
4250	PCC	38,220	94	Good

AP E consists of 12 flexible and 4 rigid pavement sections, totaling 620,726 sf. The last major construction dates range from 1971 to 2015, resulting in an area-weighted average age at inspection of 18 years old. Overall, AP E is in Satisfactory condition with an area-weighted average PCI of 75.

### AP HELI

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP HELI	APRON	2	397,538	94	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4255	AC	32,798	86	Good
4260	PCC	364,740	95	Good

AP HELI consists of 1 flexible and 1 rigid pavement sections, totaling 397,538 sf. The last major construction date for the branch was 2012, resulting in an area-weighted average age at inspection of 10 years old. Overall, AP HELI is in Good condition with an area-weighted average PCI of 94.

### AP W

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP W	APRON	2	400,935	95	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 92% Good (86-100 PCI), 8% Satisfactory (71-85 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4305	PCC	370,471	97	Good
4310	AAC	30,464	71	Satisfactory

AP W consists of 1 flexible and 1 rigid pavement sections, totaling 400,935 sf. The last major construction date for the branch was 2014, resulting in an area-weighted average age at inspection of 8 years old. Overall, AP W is in Good condition with an area-weighted average PCI of 95.



# **Chapter 5: SAPMP Customization**



## Chapter 5 – SAPMP Customization

Once the PAVER™ database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

### 5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- » The “Network” field identifies the airport being analyzed;
- » The “Airport Classification” field classifies the Airport according to the type and volume of aircraft traffic;
  - “GA” for General Aviation, community airports
  - “RL” for Regional Relievers
  - “PR” for Primary/Commercial airports
- » The “District” field identifies the FDOT District to which the Airport belongs;
- » The “FAA ADO Area” is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists);
- » The “Inspection Phase” denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- » The “CFASPP Center” identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

### 5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.



### 5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. **The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.** Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.


### 5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into “groups” or “families” according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

### 5.2.3 Branch-Level Pavement Condition Forecast

**Figure 5.2.3** depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.

*Figure 5.2.3: Forecasted Branch-Level Pavement Performance*



### 5.2.4 Section-Level Pavement Condition Forecast

**Table 5.2.4** provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

*Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
TIX	RW 9-27	6205	53	51	49	47	45	43	41	39	37	35	33
TIX	RW 9-27	6210	100	98	96	94	92	90	88	86	84	82	80
TIX	RW 9-27	6215	100	98	96	94	92	90	88	86	84	82	80
TIX	RW 18-36	6105	58	56	54	52	50	48	46	44	42	40	38
TIX	RW 18-36	6110	57	55	53	51	49	47	45	43	41	39	37
TIX	RW 18-36	6125	55	53	51	49	47	45	43	41	39	37	35
TIX	RW 18-36	6130	59	57	55	53	51	49	47	45	43	41	39
TIX	RW 18-36	6145	60	58	56	54	52	50	48	46	44	42	40
TIX	RW 18-36	6150	63	61	59	57	55	53	51	49	47	45	43
TIX	TW A	105	59	57	56	54	53	51	49	48	46	43	41
TIX	TW A	110	62	60	59	58	56	55	53	52	50	48	46
TIX	TW A	112	59	57	56	54	53	51	49	48	46	43	41
TIX	TW A	115	57	55	54	52	50	49	47	45	43	40	38
TIX	TW A	120	65	63	62	61	60	58	57	55	54	52	51
TIX	TW A1	130	49	47	45	43	40	38	35	33	30	27	25
TIX	TW A2	125	61	59	58	57	55	54	52	50	48	47	45
TIX	TW B	205	53	51	49	47	45	43	41	39	36	34	31
TIX	TW B	210	84	82	80	78	77	75	74	73	71	70	69
TIX	TW B	215	100	97	94	92	90	87	85	83	82	80	78
TIX	TW C	305	57	55	54	52	50	49	47	45	43	40	38
TIX	TW C	310	60	58	57	55	54	52	51	49	47	45	43
TIX	TW C	315	87	85	83	81	79	78	76	75	73	72	71
TIX	TW C	320	55	53	51	50	48	46	44	42	39	37	34
TIX	TW C	325	100	97	94	92	90	87	85	83	82	80	78
TIX	TW D	405	65	63	62	61	60	58	57	55	54	52	51
TIX	TW D	410	65	63	62	61	60	58	57	55	54	52	51
TIX	TW E	505	72	70	69	68	67	65	64	63	62	60	59
TIX	TW E	515	64	62	61	60	59	57	56	54	53	51	49
TIX	TW E	525	92	89	87	85	84	82	80	78	77	75	74
TIX	TW E	535	70	68	67	66	65	63	62	61	60	58	57
TIX	TW F	605	14	11	8	6	3	0	0	0	0	0	0
TIX	AP E	4205	60	58	56	54	52	50	48	46	44	42	40
TIX	AP E	4214	55	53	51	49	47	45	43	41	39	37	35
TIX	AP E	4215	63	61	60	59	58	57	56	55	54	53	52
TIX	AP E	4216	81	79	77	75	73	71	69	67	65	63	61
TIX	AP E	4218	77	75	73	71	69	67	65	63	61	59	57
TIX	AP E	4219	57	55	53	51	49	47	45	43	41	39	37
TIX	AP E	4220	77	75	73	71	69	67	65	63	61	59	57
TIX	AP E	4221	69	67	66	64	63	62	61	59	58	57	56

# Airport Pavement Evaluation Report


## Statewide Airfield Pavement Management Program

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
TIX	AP E	4225	65	64	63	62	61	60	59	58	57	56	55
TIX	AP E	4229	87	84	82	80	79	77	75	73	72	70	69
TIX	AP E	4230	76	75	74	73	72	71	70	69	68	67	66
TIX	AP E	4232	78	76	74	72	70	68	66	64	62	60	58
TIX	AP E	4235	99	98	97	96	95	94	93	92	91	90	89
TIX	AP E	4240	84	82	80	78	76	74	72	70	68	66	64
TIX	AP E	4245	71	69	68	66	65	63	62	61	60	59	58
TIX	AP E	4250	94	93	92	91	90	89	88	87	86	85	84
TIX	AP HELI	4255	86	83	81	80	78	76	74	72	71	69	68
TIX	AP HELI	4260	95	94	93	92	91	90	89	88	87	86	85
TIX	AP W	4305	97	96	95	94	93	92	91	90	89	88	87
TIX	AP W	4310	71	69	67	65	63	61	59	57	55	53	51

## 5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.

*Figure 5.3 (a): Pavement Life and the Effect of Treatments*



FAA Eligibility Thresholds:   >70: Routine Maintenance   55-70: Rehabilitation Eligible   <55: Reconstruction Eligible

*\*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.*

Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP



and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

*Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects*

Airfield Pavement Project Type	PCI Requirement
Reconstruction	PCI < 55 (Poor)
Rehabilitation	PCI < 70 (Fair)
Maintenance	N/A

\*Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

*Table 5.3 (b): Critical PCI Values by Branch Use*

Runway	Taxiway	Apron
70	70	70

**Figures 5.3 (b) and 5.3 (c)** depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram,  $PCI < \text{Critical PCI}$





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram,  $PCI \geq \text{Critical PCI}$



## 5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 “Airport Foreign Object Debris (FOD) Management” provides additional guidance for developing and managing an airport FOD program.

### 5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety (“stopgap”) measure. The two (2) types of localized maintenance are described below in further detail.

- » Localized Preventive Maintenance and Repair
  - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- » Localized Stopgap/Safety Maintenance and Repair
  - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

### 5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

#### **AC Crack Sealing**

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

#### **AC Full-Depth Patching**

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

#### **AC Partial-Depth AC Patching**

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

#### **Grinding**

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

#### **Monitor Pavement**

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.



### **PCC Crack Sealing**

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

### **PCC Full-Depth Patching**

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

### **PCC Joint Seal**

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

### **PCC Partial-Depth Patching**

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

### **PCC Slab Replacement**

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

### **Surface Seal**

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

### 5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

**Tables 5.4.3 (a) and (b)** display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

*Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete*

Localized Work Type	General Aviation Costs	Work Type Unit
AC Crack Sealing	\$ 4.00	LF
AC Full-Depth Patching	\$ 10.00	SF
AC Partial-Depth Patching	\$ 4.75	SF
Surface Seal	\$ 0.75	SF

*Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete*

Localized Work Type	General Aviation Costs	Work Type Unit
Grinding	\$ 2.00	SF
PCC Crack Sealing	\$ 7.00	LF
PCC Joint Seal	\$ 4.25	LF
PCC Full-Depth Patching	\$ 50.00	SF
PCC Partial-Depth Patching	\$ 169.00	SF
PCC Slab Replacement	\$ 51.50	SF

\* PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.

### 5.4.4 Localized Maintenance and Repair Policy

**Table 5.4.4** and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.

*Table 5.4.4: AC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy*

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
41	Low	Alligator Cracking	Monitor Pavement	Monitor Pavement
41	Medium	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
41	High	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
42	N/A	Bleeding	Monitor Pavement	Monitor Pavement
43	Low	Block Cracking	Monitor Pavement	Monitor Pavement
43	Medium	Block Cracking	AC Crack Sealing	Monitor Pavement
43	High	Block Cracking	AC Crack Sealing	AC Crack Sealing
44	Low	Corrugation	Monitor Pavement	Monitor Pavement
44	Medium	Corrugation	AC Full Depth Patching	Monitor Pavement
44	High	Corrugation	AC Full Depth Patching	AC Full Depth Patching
45	Low	Depression	Monitor Pavement	Monitor Pavement
45	Medium	Depression	AC Full Depth Patching	Monitor Pavement
45	High	Depression	AC Full Depth Patching	AC Full Depth Patching
46	N/A	Jet Blast	Monitor Pavement	Monitor Pavement
47	Low	Jt. Reflective Cracking	Monitor Pavement	Monitor Pavement
47	Medium	Jt. Reflective Cracking	AC Crack Sealing	Monitor Pavement
47	High	Jt. Reflective Cracking	AC Full Depth Patching	AC Full Depth Patching
48	Low	L&T Cracking	Monitor Pavement	Monitor Pavement
48	Medium	L&T Cracking	AC Crack Sealing	Monitor Pavement
48	High	L&T Cracking	AC Full Depth Patching	AC Full Depth Patching
49	N/A	Oil Spillage	Monitor Pavement	Monitor Pavement
50	Low	Patching	Monitor Pavement	Monitor Pavement
50	Medium	Patching	AC Full Depth Patching	Monitor Pavement
50	High	Patching	AC Full Depth Patching	AC Full Depth Patching
51	N/A	Polished Aggregate	Monitor Pavement	Monitor Pavement
52	Low	Raveling	Surface Seal	Monitor Pavement
52	Medium	Raveling	Surface Seal	Monitor Pavement
52	High	Raveling	AC Partial Depth Patching	AC Partial Depth Patching
53	Low	Rutting	Monitor Pavement	Monitor Pavement
53	Medium	Rutting	AC Full Depth Patching	Monitor Pavement
53	High	Rutting	AC Full Depth Patching	AC Full Depth Patching
54	Low	Shoving	Monitor Pavement	Monitor Pavement
54	Medium	Shoving	AC Partial Depth Patching	Monitor Pavement
54	High	Shoving	AC Full Depth Patching	AC Full Depth Patching
55	N/A	Slippage Cracking	AC Full Depth Patching	AC Full Depth Patching
56	Low	Swelling	Monitor Pavement	Monitor Pavement
56	Medium	Swelling	AC Full Depth Patching	Monitor Pavement
56	High	Swelling	AC Full Depth Patching	AC Full Depth Patching

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
57	Low	Weathering	Monitor Pavement	Monitor Pavement
57	Medium	Weathering	Surface Seal	Monitor Pavement
57	High	Weathering	AC Partial Depth Patching	Surface Seal

*Table 5.4.5: PCC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy*

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
61	Low	Blow-up	PCC Full Depth Patching	Monitor Pavement
61	Medium	Blow-up	PCC Full Depth Patching	PCC Full Depth Patching
61	High	Blow-up	PCC Slab Replacement	PCC Slab Replacement
62	Low	Corner Break	Monitor Pavement	Monitor Pavement
62	Medium	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
62	High	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
63	Low	Linear Cracking	Monitor Pavement	Monitor Pavement
63	Medium	Linear Cracking	PCC Crack Sealing	PCC Crack Sealing
63	High	Linear Cracking	PCC Full Depth Patching	PCC Crack Sealing
64	Low	Durability Cracking	Monitor Pavement	Monitor Pavement
64	Medium	Durability Cracking	PCC Full Depth Patching	PCC Full Depth Patching
64	High	Durability Cracking	PCC Slab Replacement	PCC Slab Replacement
65	Low	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	Medium	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	High	Jt. Seal Damage	PCC Joint Seal	PCC Joint Seal
66	Low	Small Patch	Monitor Pavement	Monitor Pavement
66	Medium	Small Patch	PCC Partial Depth Patching	Monitor Pavement
66	High	Small Patch	PCC Partial Depth Patching	PCC Partial Depth Patching
67	Low	Large Patch	Monitor Pavement	Monitor Pavement
67	Medium	Large Patch	PCC Full Depth Patching	Monitor Pavement
67	High	Large Patch	PCC Full Depth Patching	PCC Full Depth Patching
68	N/A	Popouts	Monitor Pavement	Monitor Pavement
69	N/A	Pumping	Monitor Pavement	Monitor Pavement
70	Low	Scaling	Monitor Pavement	Monitor Pavement
70	Medium	Scaling	PCC Slab Replacement	Monitor Pavement
70	High	Scaling	PCC Slab Replacement	PCC Slab Replacement
71	Low	Faulting	Monitor Pavement	Monitor Pavement
71	Medium	Faulting	Grinding	Monitor Pavement
71	High	Faulting	PCC Slab Replacement	PCC Slab Replacement
72	Low	Shattered Slab	PCC Crack Sealing	Monitor Pavement
72	Medium	Shattered Slab	PCC Slab Replacement	PCC Crack Sealing
72	High	Shattered Slab	PCC Slab Replacement	PCC Slab Replacement
73	N/A	Shrinkage Cracking	Monitor Pavement	Monitor Pavement



Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
74	Low	Joint Spall	Monitor Pavement	Monitor Pavement
74	Medium	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
74	High	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	Low	Corner Spall	Monitor Pavement	Monitor Pavement
75	Medium	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	High	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
76	Low	ASR	Monitor Pavement	Monitor Pavement
76	Medium	ASR	PCC Slab Replacement	PCC Slab Replacement
76	High	ASR	PCC Slab Replacement	PCC Slab Replacement

## 5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

### 5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average General Aviation Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

*Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation*

Rehabilitation Type	General Aviation Pavement Section
<b>AC Reconstruction</b>	
<i>Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.</i>  <b>PCI &lt; 55</b>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (6")
	Prime Coat
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
<b>AC Rehabilitation</b>	
<i>Combination of asphalt pavement milling and replacement overlay with 15% of the areas subject to full-depth reconstruction.</i>  <b>PCI = 55 to 70</b>	<b>15% AC Reconstruction</b>
	<b>Mill and Overlay</b>
	AC Milling (3")
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
<b>PCC Reconstruction</b>	
<i>Full-depth rigid pavement section reconstruction.</i>  <b>PCI &lt; 55</b>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (6")
	Limerock Base Course (6")
	P-501 PCC Pavement (8")
	PCC Joint Seal
<b>PCC Rehabilitation</b>	
<i>Rehabilitation of PCC pavement with a combination of crack sealing, joint seal replacement, limited patching, and replacement of 15% of slab panels.</i>  <b>PCI = 55 to 70</b>	<b>15% Slab Replacement</b>
	<b>Joint and Crack Seal</b>
	<b>Limited Patching</b>

*The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.*

### **Reconstruction (AC or PCC)**

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

### **AC Rehabilitation**

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

### **PCC Rehabilitation**

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.

### **5.5.2 Major Rehabilitation Planning-Level Unit Costs**


Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.

Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.


*Table 5.5.2: GA Major Rehabilitation Planning-Level Unit Cost by Pavement Type*

Rehabilitation Type	PCI Range	Asphalt Concrete Cost per SF	Portland Cement Concrete Cost Per SF
Rehabilitation	55 to 70	\$9.00	\$15.00
Reconstruction	0 to 55	\$16.00	\$29.00





# **Chapter 6: M&R Planning and Budget Scenario Analysis**





## Chapter 6 – M&R Planning and Budget Scenario Analysis

### 6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

**Table 6.1 (a)** provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (a): Year 1 Summary of Localized Maintenance*

Work Category	Cost
Preventive	\$ 427,230
Stopgap	\$ 7,770
<b>Planning-Level Localized M&amp;R Needs =</b>	<b>\$ 435,000</b>

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

**Table 6.1 (b)** summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary*

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing	1,005	LF	\$ 4,040
	Surface Seal	105,324	SF	\$ 79,050
	PCC Joint Seal	78,523	LF	\$ 333,740
	PCC Partial-Depth Patching	61	SF	\$ 10,400
Localized Stopgap Maintenance	AC Partial-Depth Patching	8	SF	\$ 40
	AC Full-Depth Patching	772	SF	\$ 7,730

**Table 6.1 (c)** provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved “End Condition” PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

*Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary*

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
TIX	RW 9-27	6205	67,743	53	53	\$ -
TIX	RW 9-27	6210	320,000	100	100	\$ -
TIX	RW 9-27	6215	102,000	100	100	\$ -
TIX	RW 18-36	6105	500,000	58	58	\$ -
TIX	RW 18-36	6110	250,000	57	57	\$ -
TIX	RW 18-36	6125	100,000	55	55	\$ -
TIX	RW 18-36	6130	50,000	59	59	\$ -
TIX	RW 18-36	6145	131,900	60	60	\$ 2,180
TIX	RW 18-36	6150	65,950	63	63	\$ -
TIX	TW A	105	114,651	59	59	\$ -
TIX	TW A	110	70,000	62	62	\$ -
TIX	TW A	112	30,000	59	59	\$ -
TIX	TW A	115	50,000	57	57	\$ -
TIX	TW A	120	40,007	65	65	\$ -
TIX	TW A1	130	50,631	49	49	\$ -
TIX	TW A2	125	35,137	61	61	\$ -
TIX	TW B	205	22,146	53	53	\$ -
TIX	TW B	210	223,574	84	87	\$ 5,870
TIX	TW B	215	11,820	100	100	\$ -
TIX	TW C	305	46,879	57	57	\$ -
TIX	TW C	310	116,660	60	60	\$ -
TIX	TW C	315	15,628	87	90	\$ 240
TIX	TW C	320	3,845	55	55	\$ -
TIX	TW C	325	17,228	100	100	\$ -
TIX	TW D	405	33,961	65	65	\$ -
TIX	TW D	410	73,750	65	65	\$ -

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
TIX	TW E	505	32,371	72	81	\$ 26,150
TIX	TW E	515	44,841	64	64	\$ -
TIX	TW E	525	8,165	92	94	\$ 130
TIX	TW E	535	68,681	70	70	\$ -
TIX	TW F	605	30,388	14	23	\$ 5,590
TIX	AP E	4205	100,353	60	60	\$ -
TIX	AP E	4214	52,187	55	55	\$ -
TIX	AP E	4215	77,281	63	63	\$ -
TIX	AP E	4216	48,812	81	90	\$ 9,150
TIX	AP E	4218	94,806	77	86	\$ 18,090
TIX	AP E	4219	8,237	57	57	\$ -
TIX	AP E	4220	33,963	77	82	\$ 2,980
TIX	AP E	4221	5,405	69	69	\$ -
TIX	AP E	4225	8,700	65	65	\$ -
TIX	AP E	4229	16,379	87	91	\$ 620
TIX	AP E	4230	9,662	76	76	\$ -
TIX	AP E	4232	10,659	78	83	\$ 1,490
TIX	AP E	4235	93,090	99	99	\$ -
TIX	AP E	4240	15,772	84	89	\$ 1,190
TIX	AP E	4245	7,200	71	96	\$ 5,400
TIX	AP E	4250	38,220	94	94	\$ -
TIX	AP HELI	4255	32,798	86	90	\$ 1,230
TIX	AP HELI	4260	364,740	95	97	\$ 142,120
TIX	AP W	4305	370,471	97	98	\$ 202,010
TIX	AP W	4310	30,464	71	84	\$ 10,530

## 6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b) and (c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

### 6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- » An estimation of current pavement condition;
- » Major pavement rehabilitation needs based on condition and policies; and
- » Planning-level cost estimates for the major rehabilitation needs.

**Table 6.2.1 (a)** summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.

*Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs*


Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	TIX	RW 9-27	6205	AAC	67,743	51	AC Reconstruction	\$ 1,084,000
2023	TIX	RW 18-36	6105	AAC	500,000	56	AC Rehabilitation	\$ 4,501,000
2023	TIX	RW 18-36	6110	AAC	250,000	55	AC Reconstruction	\$ 2,881,000
2023	TIX	RW 18-36	6125	AAC	100,000	53	AC Reconstruction	\$ 1,600,000
2023	TIX	RW 18-36	6130	AAC	50,000	57	AC Rehabilitation	\$ 451,000
2023	TIX	RW 18-36	6145	AAC	131,900	58	AC Rehabilitation	\$ 1,188,000
2023	TIX	RW 18-36	6150	AAC	65,950	61	AC Rehabilitation	\$ 594,000
2023	TIX	TW A	105	AAC	114,651	57	AC Rehabilitation	\$ 1,032,000
2023	TIX	TW A	110	AAC	70,000	60	AC Rehabilitation	\$ 631,000
2023	TIX	TW A	112	AAC	30,000	57	AC Rehabilitation	\$ 271,000
2023	TIX	TW A	115	AAC	50,000	55	AC Rehabilitation	\$ 451,000
2023	TIX	TW A	120	AAC	40,007	63	AC Rehabilitation	\$ 361,000
2023	TIX	TW A1	130	AAC	50,631	47	AC Reconstruction	\$ 811,000
2023	TIX	TW A2	125	AAC	35,137	59	AC Rehabilitation	\$ 317,000
2023	TIX	TW B	205	AAC	22,146	51	AC Reconstruction	\$ 355,000
2023	TIX	TW C	305	AAC	46,879	55	AC Rehabilitation	\$ 422,000
2023	TIX	TW C	310	AAC	116,660	58	AC Rehabilitation	\$ 1,050,000
2023	TIX	TW C	320	AAC	3,845	53	AC Reconstruction	\$ 62,000
2023	TIX	TW D	405	AAC	33,961	63	AC Rehabilitation	\$ 306,000
2023	TIX	TW D	410	AAC	73,750	63	AC Rehabilitation	\$ 664,000
2023	TIX	TW E	515	AAC	44,841	62	AC Rehabilitation	\$ 404,000
2023	TIX	TW E	535	AAC	68,681	68	AC Rehabilitation	\$ 619,000
2023	TIX	TW F	605	AAC	30,388	11	AC Reconstruction	\$ 487,000
2023	TIX	AP E	4205	AAC	100,353	58	AC Rehabilitation	\$ 904,000
2023	TIX	AP E	4214	APC	52,187	53	AC Reconstruction	\$ 835,000
2023	TIX	AP E	4215	AC	77,281	61	AC Rehabilitation	\$ 696,000




Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	TIX	AP E	4219	AAC	8,237	55	AC Reconstruction	\$ 95,000
2023	TIX	AP E	4221	AC	5,405	67	AC Rehabilitation	\$ 49,000
2023	TIX	AP E	4225	PCC	8,700	64	PCC Rehabilitation	\$ 131,000
2023	TIX	AP E	4245	AC	7,200	69	AC Rehabilitation	\$ 65,000
2023	TIX	AP W	4310	AAC	30,464	69	AC Rehabilitation	\$ 275,000
2024	TIX	TW E	505	AAC	32,371	69	AC Rehabilitation	\$ 306,000
2026	TIX	AP E	4218	AAC	94,806	69	AC Rehabilitation	\$ 988,000
2026	TIX	AP E	4220	AAC	33,963	69	AC Rehabilitation	\$ 354,000
2026	TIX	AP E	4232	AAC	10,659	70	AC Rehabilitation	\$ 112,000
2028	TIX	AP E	4216	AAC	48,812	69	AC Rehabilitation	\$ 561,000
2029	TIX	AP E	4230	PCC	9,662	69	PCC Rehabilitation	\$ 195,000
2029	TIX	AP E	4240	AAC	15,772	70	AC Rehabilitation	\$ 191,000
2031	TIX	TW B	210	AAC	223,574	70	AC Rehabilitation	\$ 2,974,000
2031	TIX	AP HELI	4255	AC	32,798	69	AC Rehabilitation	\$ 437,000
2032	TIX	AP E	4229	AC	16,379	69	AC Rehabilitation	\$ 229,000

**Figure 6.2.1 (a)** summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

*Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year*





TW A:112 2023   AC REHAB \$0.27 M	TW B:205 2023   AC RECON \$0.36 M	TW C:305 2023   AC REHAB \$0.42 M	TW C:310 2023   AC REHAB \$1.05 M
TW C:320 2023   AC RECON \$0.06 M	TW D:405 2023   AC REHAB \$0.31 M	TW E:515 2023   AC REHAB \$0.40 M	AP E:4214 2023   AC RECON \$0.84 M
AP E:4215 2023   AC REHAB \$0.70 M	AP E:4219 2023   AC REHAB \$0.10 M	AP E:4221 2023   AC REHAB \$0.05 M	AP W:4310 2023   AC REHAB \$0.28 M
TW E:505 2024   AC REHAB \$0.31 M	AP E:4218 2026   AC REHAB \$0.99 M	AP E:4232 2026   AC REHAB \$0.11 M	AP E:4216 2028   AC REHAB \$0.56 M

**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID  
TW A — TYPICAL TAXIWAY BRANCH ID  
AP S — TYPICAL APRON BRANCH ID

**PROGRAM YEAR**

2023	2028
2024	2029
2025	2030
2026	2031
2027	2032

"BRANCH": "SECTION"  
"YEAR": "REHAB ACTIVITY"  
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



# Chapter 7: Conclusion





## Chapter 7 – Conclusion

### 7.1 Recommendations

#### 7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

#### 7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

#### 7.1.3 Major Rehabilitation

**Chapter 6** also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

#### 7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- » Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in **Section 6.1**;
- » Further refine and implement the identified 10-year major rehabilitation needs provided in **Section 6.2**;
- » Maintain detailed records on pavement maintenance, construction, and inspection; and
- » Maintain records on major pavement construction projects (year, scope, cost, and construction documents).



## 7.2 Supporting Documents

### Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

### Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

### Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

### Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

### Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

### Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.

## 7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

## 7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- » ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- » AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- » AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- » AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- » Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- » Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- » Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.

A photograph of a long, straight airfield runway stretching towards the horizon under a bright blue sky with scattered white clouds. The runway has a central white dashed line and yellow edge lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

# **Appendix A: Airfield Pavement Analysis**

A close-up, low-angle view of the runway pavement, showing a white dashed line and yellow chevron markings. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.



*Table A.1: Pavement System Inventory Details*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
TIX	RW 9-27	Runway	6205	67,743	AAC	6/1/2002
TIX	RW 9-27	Runway	6210	320,000	AAC	5/1/2022
TIX	RW 9-27	Runway	6215	102,000	AAC	5/1/2022
TIX	RW 18-36	Runway	6105	500,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6110	250,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6125	100,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6130	50,000	AAC	6/1/2002
TIX	RW 18-36	Runway	6145	131,900	AAC	6/1/2002
TIX	RW 18-36	Runway	6150	65,950	AAC	6/1/2002
TIX	TW A	Taxiway	105	114,651	AAC	6/1/2002
TIX	TW A	Taxiway	110	70,000	AAC	6/1/2002
TIX	TW A	Taxiway	112	30,000	AAC	6/1/2002
TIX	TW A	Taxiway	115	50,000	AAC	6/1/2002
TIX	TW A	Taxiway	120	40,007	AAC	6/1/2002
TIX	TW A1	Taxiway	130	50,631	AAC	6/1/2002
TIX	TW A2	Taxiway	125	35,137	AAC	6/1/2002
TIX	TW B	Taxiway	205	22,146	AAC	6/1/2002
TIX	TW B	Taxiway	210	223,574	AAC	1/1/2013
TIX	TW B	Taxiway	215	11,820	AAC	5/1/2022
TIX	TW C	Taxiway	305	46,879	AAC	1/1/2004
TIX	TW C	Taxiway	310	116,660	AAC	1/1/1986
TIX	TW C	Taxiway	315	15,628	AAC	1/1/2013
TIX	TW C	Taxiway	320	3,845	AAC	6/1/2002
TIX	TW C	Taxiway	325	17,228	AAC	5/1/2022
TIX	TW D	Taxiway	405	33,961	AAC	1/1/2000
TIX	TW D	Taxiway	410	73,750	AAC	1/1/2000
TIX	TW E	Taxiway	505	32,371	AAC	1/1/1998
TIX	TW E	Taxiway	515	44,841	AAC	1/1/2003
TIX	TW E	Taxiway	525	8,165	AC	1/1/2014
TIX	TW E	Taxiway	535	68,681	AAC	1/1/2003
TIX	TW F	Taxiway	605	30,388	AAC	1/1/1998
TIX	AP E	Apron	4205	100,353	AAC	1/1/2008
TIX	AP E	Apron	4214	52,187	APC	6/1/2002
TIX	AP E	Apron	4215	77,281	AC	1/1/1971
TIX	AP E	Apron	4216	48,812	AAC	1/1/2008
TIX	AP E	Apron	4218	94,806	AAC	1/1/2008
TIX	AP E	Apron	4219	8,237	AAC	1/1/2015
TIX	AP E	Apron	4220	33,963	AAC	1/1/2014
TIX	AP E	Apron	4221	5,405	AC	1/1/2008
TIX	AP E	Apron	4225	8,700	PCC	1/1/1991
TIX	AP E	Apron	4229	16,379	AC	1/1/2012
TIX	AP E	Apron	4230	9,662	PCC	1/1/1991
TIX	AP E	Apron	4232	10,659	AAC	1/1/2014
TIX	AP E	Apron	4235	93,090	PCC	1/1/2015



Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
TIX	AP E	Apron	4240	15,772	AAC	1/1/2014
TIX	AP E	Apron	4245	7,200	AC	1/1/2003
TIX	AP E	Apron	4250	38,220	PCC	1/1/2011
TIX	AP HELI	Apron	4255	32,798	AC	1/1/2012
TIX	AP HELI	Apron	4260	364,740	PCC	1/1/2012
TIX	AP W	Apron	4305	370,471	PCC	1/1/2014
TIX	AP W	Apron	4310	30,464	AAC	1/1/2014

*Table A.2: Pavement Condition Index Summary (Current PCI Survey) – Section Level*

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
TIX	RW 9-27	Runway	6205	67,743	53	Poor
TIX	RW 9-27	Runway	6210	320,000	100	Good
TIX	RW 9-27	Runway	6215	102,000	100	Good
TIX	RW 18-36	Runway	6105	500,000	58	Fair
TIX	RW 18-36	Runway	6110	250,000	57	Fair
TIX	RW 18-36	Runway	6125	100,000	55	Poor
TIX	RW 18-36	Runway	6130	50,000	59	Fair
TIX	RW 18-36	Runway	6145	131,900	60	Fair
TIX	RW 18-36	Runway	6150	65,950	63	Fair
TIX	TW A	Taxiway	105	114,651	59	Fair
TIX	TW A	Taxiway	110	70,000	62	Fair
TIX	TW A	Taxiway	112	30,000	59	Fair
TIX	TW A	Taxiway	115	50,000	57	Fair
TIX	TW A	Taxiway	120	40,007	65	Fair
TIX	TW A1	Taxiway	130	50,631	49	Poor
TIX	TW A2	Taxiway	125	35,137	61	Fair
TIX	TW B	Taxiway	205	22,146	53	Poor
TIX	TW B	Taxiway	210	223,574	84	Satisfactory
TIX	TW B	Taxiway	215	11,820	100	Good
TIX	TW C	Taxiway	305	46,879	57	Fair
TIX	TW C	Taxiway	310	116,660	60	Fair
TIX	TW C	Taxiway	315	15,628	87	Good
TIX	TW C	Taxiway	320	3,845	55	Poor
TIX	TW C	Taxiway	325	17,228	100	Good
TIX	TW D	Taxiway	405	33,961	65	Fair
TIX	TW D	Taxiway	410	73,750	65	Fair
TIX	TW E	Taxiway	505	32,371	72	Satisfactory
TIX	TW E	Taxiway	515	44,841	64	Fair
TIX	TW E	Taxiway	525	8,165	92	Good
TIX	TW E	Taxiway	535	68,681	70	Fair
TIX	TW F	Taxiway	605	30,388	14	Serious
TIX	AP E	Apron	4205	100,353	60	Fair
TIX	AP E	Apron	4214	52,187	55	Poor
TIX	AP E	Apron	4215	77,281	63	Fair
TIX	AP E	Apron	4216	48,812	81	Satisfactory
TIX	AP E	Apron	4218	94,806	77	Satisfactory
TIX	AP E	Apron	4219	8,237	57	Fair
TIX	AP E	Apron	4220	33,963	77	Satisfactory
TIX	AP E	Apron	4221	5,405	69	Fair
TIX	AP E	Apron	4225	8,700	65	Fair
TIX	AP E	Apron	4229	16,379	87	Good
TIX	AP E	Apron	4230	9,662	76	Satisfactory
TIX	AP E	Apron	4232	10,659	78	Satisfactory
TIX	AP E	Apron	4235	93,090	99	Good
TIX	AP E	Apron	4240	15,772	84	Satisfactory

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
TIX	AP E	Apron	4245	7,200	71	Satisfactory
TIX	AP E	Apron	4250	38,220	94	Good
TIX	AP HELI	Apron	4255	32,798	86	Good
TIX	AP HELI	Apron	4260	364,740	95	Good
TIX	AP W	Apron	4305	370,471	97	Good
TIX	AP W	Apron	4310	30,464	71	Satisfactory

*Table A.3: Forecasted PCI Values 2023-2032 – Section-Level*

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
TIX	RW 9-27	6205	53	51	49	47	45	43	41	39	37	35	33
TIX	RW 9-27	6210	100	98	96	94	92	90	88	86	84	82	80
TIX	RW 9-27	6215	100	98	96	94	92	90	88	86	84	82	80
TIX	RW 18-36	6105	58	56	54	52	50	48	46	44	42	40	38
TIX	RW 18-36	6110	57	55	53	51	49	47	45	43	41	39	37
TIX	RW 18-36	6125	55	53	51	49	47	45	43	41	39	37	35
TIX	RW 18-36	6130	59	57	55	53	51	49	47	45	43	41	39
TIX	RW 18-36	6145	60	58	56	54	52	50	48	46	44	42	40
TIX	RW 18-36	6150	63	61	59	57	55	53	51	49	47	45	43
TIX	TW A	105	59	57	56	54	53	51	49	48	46	43	41
TIX	TW A	110	62	60	59	58	56	55	53	52	50	48	46
TIX	TW A	112	59	57	56	54	53	51	49	48	46	43	41
TIX	TW A	115	57	55	54	52	50	49	47	45	43	40	38
TIX	TW A	120	65	63	62	61	60	58	57	55	54	52	51
TIX	TW A1	130	49	47	45	43	40	38	35	33	30	27	25
TIX	TW A2	125	61	59	58	57	55	54	52	50	48	47	45
TIX	TW B	205	53	51	49	47	45	43	41	39	36	34	31
TIX	TW B	210	84	82	80	78	77	75	74	73	71	70	69
TIX	TW B	215	100	97	94	92	90	87	85	83	82	80	78
TIX	TW C	305	57	55	54	52	50	49	47	45	43	40	38
TIX	TW C	310	60	58	57	55	54	52	51	49	47	45	43
TIX	TW C	315	87	85	83	81	79	78	76	75	73	72	71
TIX	TW C	320	55	53	51	50	48	46	44	42	39	37	34
TIX	TW C	325	100	97	94	92	90	87	85	83	82	80	78
TIX	TW D	405	65	63	62	61	60	58	57	55	54	52	51
TIX	TW D	410	65	63	62	61	60	58	57	55	54	52	51
TIX	TW E	505	72	70	69	68	67	65	64	63	62	60	59
TIX	TW E	515	64	62	61	60	59	57	56	54	53	51	49
TIX	TW E	525	92	89	87	85	84	82	80	78	77	75	74
TIX	TW E	535	70	68	67	66	65	63	62	61	60	58	57
TIX	TW F	605	14	11	8	6	3	0	0	0	0	0	0
TIX	AP E	4205	60	58	56	54	52	50	48	46	44	42	40
TIX	AP E	4214	55	53	51	49	47	45	43	41	39	37	35
TIX	AP E	4215	63	61	60	59	58	57	56	55	54	53	52
TIX	AP E	4216	81	79	77	75	73	71	69	67	65	63	61
TIX	AP E	4218	77	75	73	71	69	67	65	63	61	59	57
TIX	AP E	4219	57	55	53	51	49	47	45	43	41	39	37
TIX	AP E	4220	77	75	73	71	69	67	65	63	61	59	57
TIX	AP E	4221	69	67	66	64	63	62	61	59	58	57	56
TIX	AP E	4225	65	64	63	62	61	60	59	58	57	56	55
TIX	AP E	4229	87	84	82	80	79	77	75	73	72	70	69
TIX	AP E	4230	76	75	74	73	72	71	70	69	68	67	66
TIX	AP E	4232	78	76	74	72	70	68	66	64	62	60	58
TIX	AP E	4235	99	98	97	96	95	94	93	92	91	90	89



Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
TIX	AP E	4240	84	82	80	78	76	74	72	70	68	66	64
TIX	AP E	4245	71	69	68	66	65	63	62	61	60	59	58
TIX	AP E	4250	94	93	92	91	90	89	88	87	86	85	84
TIX	AP HELI	4255	86	83	81	80	78	76	74	72	71	69	68
TIX	AP HELI	4260	95	94	93	92	91	90	89	88	87	86	85
TIX	AP W	4305	97	96	95	94	93	92	91	90	89	88	87
TIX	AP W	4310	71	69	67	65	63	61	59	57	55	53	51

11/17/2022

## Work History Report

Page 1 of 10

Pavement Database: FDOT

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4205	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2008	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 225.00 (Ft)	<b>Width:</b> 780.00 (Ft)	<b>True Area:</b> 100353.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Unknown	
1/1/1992	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	THIS FEATURE HAS A 1992 SLUR	
1/1/1968	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>	1968: 3" AC ON 8" LIME ROCK BASE. SOIL: SP.	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4214	<b>Surface:</b> APC
<b>L.C.D.</b> 6/1/2002	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 1,100.00 (Ft)	<b>Width:</b> 35.00 (Ft)	<b>True Area:</b> 52187.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2020	CS-AC	Crack Sealing - AC	0.00	0.00	<input type="checkbox"/>		
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Unknown	
1/1/1992	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	Unknown	
1/1/1971	OL-AS	Overlay - AC Structural	0.00	0.00	<input checked="" type="checkbox"/>	Unknown	
1/1/1943	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	Est. initial construction	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4215	<b>Surface:</b> AC
<b>L.C.D.</b> 1/1/1971	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 330.00 (Ft)	<b>Width:</b> 230.00 (Ft)	<b>True Area:</b> 77281.00002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1992	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	THIS PAVEMENT HAS A 1992 SLU	
1/1/1971	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1971 AC PAVEMENT	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4216	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2008	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 160.00 (Ft)	<b>Width:</b> 305.00 (Ft)	<b>True Area:</b> 48812.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1971	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1971 AC	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4218	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2008	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 195.00 (Ft)	<b>Width:</b> 525.00 (Ft)	<b>True Area:</b> 94806.00002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2008	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1971	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1971 AC	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4219	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2015	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 55.00 (Ft)	<b>Width:</b> 151.00 (Ft)	<b>True Area:</b> 8237.000002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Unknown	
1/1/1992	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	THIS PAVEMENT HAS A 1992 SLU	
1/1/1971	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1971 AC PAVEMENT	

11/17/2022

## Work History Report

Page 2 of 10

Pavement Database: FDOT

<b>Network:</b> SPACE COAST REG <b>Branch:</b> AP E    EAST APRON <b>Section:</b> 4220 <b>Surface:</b> AAC						
<b>L.C.D.</b> 1/1/2014 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 1,515.00 (Ft) <b>Width:</b> 20.00 (Ft) <b>True Area:</b> 33963.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	THIS PAVEMENT HAS A 1992 SLU ESTIMATE 1980 AC PAVEMENT
1/1/1992	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1980	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> SPACE COAST REG <b>Branch:</b> AP E    EAST APRON <b>Section:</b> 4221 <b>Surface:</b> AC						
<b>L.C.D.</b> 1/1/2008 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 200.00 (Ft) <b>Width:</b> 25.00 (Ft) <b>True Area:</b> 5405.000001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2008	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	Unknown

<b>Network:</b> SPACE COAST REG <b>Branch:</b> AP E    EAST APRON <b>Section:</b> 4225 <b>Surface:</b> PCC						
<b>L.C.D.</b> 1/1/1991 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 400.00 (Ft) <b>Width:</b> 20.00 (Ft) <b>True Area:</b> 8700.000002 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1991 PCC PAVEMENT

<b>Network:</b> SPACE COAST REG <b>Branch:</b> AP E    EAST APRON <b>Section:</b> 4229 <b>Surface:</b> AC						
<b>L.C.D.</b> 1/1/2012 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 800.00 (Ft) <b>Width:</b> 20.00 (Ft) <b>True Area:</b> 16379.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2012: 2" FDOT SP 12.5 Fine Mix, 6"

<b>Network:</b> SPACE COAST REG <b>Branch:</b> AP E    EAST APRON <b>Section:</b> 4230 <b>Surface:</b> PCC						
<b>L.C.D.</b> 1/1/1991 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 445.00 (Ft) <b>Width:</b> 20.00 (Ft) <b>True Area:</b> 9662.000002 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1991	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1991 PCC PAVEMENT

<b>Network:</b> SPACE COAST REG <b>Branch:</b> AP E    EAST APRON <b>Section:</b> 4232 <b>Surface:</b> AAC						
<b>L.C.D.</b> 1/1/2014 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 332.00 (Ft) <b>Width:</b> 30.00 (Ft) <b>True Area:</b> 10659.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2014: 2" MILL AND 2" OL W/ FDOT THIS PAVEMENT HAS A 1992 SLU ESTIMATE 1971 AC PAVEMENT ( 8" ASPHALT ON 5" +/- SOIL CEME
1/1/1992	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	
1/1/1971	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	

<b>Network:</b> SPACE COAST REG <b>Branch:</b> AP E    EAST APRON <b>Section:</b> 4235 <b>Surface:</b> PCC						
<b>L.C.D.</b> 1/1/2015 <b>Use:</b> APRON <b>Rank:</b> P <b>Length:</b> 495.00 (Ft) <b>Width:</b> 178.00 (Ft) <b>True Area:</b> 93090.00002 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NC-PC	New Construction - PCC	0.00	0.00	<input checked="" type="checkbox"/>	14" P-501, 6" P-211, COMPACTED S

11/17/2022

## Work History Report

Page 3 of 10

Pavement Database: FDOT

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4240	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2014	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 770.00 (Ft)	<b>Width:</b> 20.00 (Ft)	<b>True Area:</b> 15772.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	Remove 2" Existing and replace with ESTIMATE 1987 AC PAVEMENT	
1/1/1987	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4245	<b>Surface:</b> AC
<b>L.C.D.</b> 1/1/2003	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 350.00 (Ft)	<b>Width:</b> 20.00 (Ft)	<b>True Area:</b> 7200.000002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP E		EAST APRON		<b>Section:</b> 4250	<b>Surface:</b> PCC
<b>L.C.D.</b> 1/1/2011	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 190.00 (Ft)	<b>Width:</b> 200.00 (Ft)	<b>True Area:</b> 38220.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2011	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP HELI		HELICOPTER AP		<b>Section:</b> 4255	<b>Surface:</b> AC
<b>L.C.D.</b> 1/1/2012	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 475.00 (Ft)	<b>Width:</b> 70.00 (Ft)	<b>True Area:</b> 32798.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2012: 2" P-401, 8" LIMEROCK, 8" S	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP HELI		HELICOPTER AP		<b>Section:</b> 4260	<b>Surface:</b> PCC
<b>L.C.D.</b> 1/1/2012	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 744.00 (Ft)	<b>Width:</b> 510.00 (Ft)	<b>True Area:</b> 364740.0001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2012	NU-IN	New Construction - Initial	0.00	7.25	<input checked="" type="checkbox"/>	2012: 7.25" FDOT CONCRETE SPE	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP W		WEST APRON		<b>Section:</b> 4305	<b>Surface:</b> PCC
<b>L.C.D.</b> 1/1/2014	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 1,600.00 (Ft)	<b>Width:</b> 500.00 (Ft)	<b>True Area:</b> 370471.0001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	NU-IN	New Construction - Initial	0.00	14.00	<input checked="" type="checkbox"/>	2014: 14" P-501, 6" P-211, COMPAC	

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> AP W		WEST APRON		<b>Section:</b> 4310	<b>Surface:</b> AAC
<b>L.C.D.</b> 1/1/2014	<b>Use:</b> APRON	<b>Rank:</b> P	<b>Length:</b> 68.00 (Ft)	<b>Width:</b> 400.00 (Ft)	<b>True Area:</b> 30464.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2014	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	PARTIAL OVERLAY FROM AP W	
1/1/2004	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1943	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	1943: 2" AC ON 8" LIMEROCK BAS	



11/17/2022

## Work History Report

Page 4 of 10

Pavement Database: FDOT

Network: SPACE COAST REG		Branch: RW 18-36		RUNWAY 18-36		Section: 6105	Surface: AAC
L.C.D. 6/1/2002	Use: RUNWAY	Rank: P	Length: 5,000.00 (Ft)	Width: 100.00 (Ft)	True Area: 500000.0001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 2" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

Network: SPACE COAST REG		Branch: RW 18-36		RUNWAY 18-36		Section: 6110	Surface: AAC
L.C.D. 6/1/2002	Use: RUNWAY	Rank: P	Length: 10,000.00 (Ft)	Width: 25.00 (Ft)	True Area: 250000.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 2" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

Network: SPACE COAST REG		Branch: RW 18-36		RUNWAY 18-36		Section: 6125	Surface: AAC
L.C.D. 6/1/2002	Use: RUNWAY	Rank: P	Length: 1,000.00 (Ft)	Width: 100.00 (Ft)	True Area: 100000.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 3" P-401 OVERLAY. SOIL: SP. 1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1967	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

Network: SPACE COAST REG		Branch: RW 18-36		RUNWAY 18-36		Section: 6130	Surface: AAC
L.C.D. 6/1/2002	Use: RUNWAY	Rank: P	Length: 2,000.00 (Ft)	Width: 25.00 (Ft)	True Area: 50000.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 3" P-401 OVERLAY. SOIL: SP. 1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1967	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

Network: SPACE COAST REG		Branch: RW 18-36		RUNWAY 18-36		Section: 6145	Surface: AAC
L.C.D. 6/1/2002	Use: RUNWAY	Rank: P	Length: 1,319.00 (Ft)	Width: 100.00 (Ft)	True Area: 131900.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1971	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

11/17/2022

## Work History Report

Page 5 of 10

Pavement Database: FDOT

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> RW 18-36		RUNWAY 18-36		<b>Section:</b> 6150	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002		<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 2,600.00 (Ft)	<b>Width:</b> 25.00 (Ft)	<b>True Area:</b> 65950.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 2" P-401 OVERLAY. SOIL: SP. 1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1967	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> RW 9-27		RUNWAY 9-27		<b>Section:</b> 6205	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002		<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 655.00 (Ft)	<b>Width:</b> 100.00 (Ft)	<b>True Area:</b> 67743.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1976: MINIMUM 1.5" P-401 OVERLAY. THIS PAVEMENT HAS 1943: 3" - 4" AC ON 8" BASE	
1/1/1998	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1976	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> RW 9-27		RUNWAY 9-27		<b>Section:</b> 6210	<b>Surface:</b> AAC
<b>L.C.D.</b> 5/1/2022		<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 3,200.00 (Ft)	<b>Width:</b> 100.00 (Ft)	<b>True Area:</b> 320000.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
5/1/2022	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	On-going 1998 2.5" P401 1976 1.5" P401 OVERLAY ON 1943 3.5" P401 ON 8" P211	
1/1/1998	OL-AS	Overlay - AC Structural	0.00	2.50	<input checked="" type="checkbox"/>		
1/1/1976	OL-AS	Overlay - AC Structural	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1943	NC-AC	New Construction - AC	0.00	3.50	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> RW 9-27		RUNWAY 9-27		<b>Section:</b> 6215	<b>Surface:</b> AAC
<b>L.C.D.</b> 5/1/2022		<b>Use:</b> RUNWAY	<b>Rank:</b> P	<b>Length:</b> 1,020.00 (Ft)	<b>Width:</b> 100.00 (Ft)	<b>True Area:</b> 102000.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
5/1/2022	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	On-going 1976: MINIMUM 1.5" P-401 OVERLAY. THIS PAVEMENT HAS 1943: 3" - 4" AC ON 8" BASE	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1998	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>		
1/1/1976	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	3.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> TW A		TAXIWAY A		<b>Section:</b> 105	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002		<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 2,200.00 (Ft)	<b>Width:</b> 50.00 (Ft)	<b>True Area:</b> 114651.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

11/17/2022

## Work History Report

Page 6 of 10

Pavement Database: FDOT

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> TW A		TAXIWAY A		<b>Section:</b> 110	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 1,400.00 (Ft)	<b>Width:</b> 50.00 (Ft)	<b>True Area:</b> 70000.00002 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	THERE IS A 1992 SLURRY SEAL O 1971: MINIMUM 3" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCK BASE	
1/1/1992	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>		
1/1/1971	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> TW A		TAXIWAY A		<b>Section:</b> 112	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 600.00 (Ft)	<b>Width:</b> 50.00 (Ft)	<b>True Area:</b> 30000.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 3" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>		
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> TW A1		TAXIWAY A1		<b>Section:</b> 130	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 500.00 (Ft)	<b>Width:</b> 65.00 (Ft)	<b>True Area:</b> 50631.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 2" P-401 OVERLAY. SOIL: SP. 1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1967	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> TW A		TAXIWAY A		<b>Section:</b> 115	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 1,000.00 (Ft)	<b>Width:</b> 50.00 (Ft)	<b>True Area:</b> 50000.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>		
1/1/1967	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

<b>Network:</b> SPACE COAST REG		<b>Branch:</b> TW A		TAXIWAY A		<b>Section:</b> 120	<b>Surface:</b> AAC
<b>L.C.D.</b> 6/1/2002	<b>Use:</b> TAXIWAY	<b>Rank:</b> P	<b>Length:</b> 800.00 (Ft)	<b>Width:</b> 50.00 (Ft)	<b>True Area:</b> 40007.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 2" P-401 OVERLAY. SOIL: SP. 1967: 2" - 3" AC ON 7" - 8" LIME ROCK BASE	
1/1/1971	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>		
1/1/1967	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>		

11/17/2022

## Work History Report

Page 7 of 10

Pavement Database: FDOT

Network: SPACE COAST REG		Branch: TW A2	TAXIWAY A2		Section: 125	Surface: AAC
L.C.D. 6/1/2002	Use: TAXIWAY	Rank: P	Length: 600.00 (Ft)	Width: 500.00 (Ft)	True Area: 35137.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971: MINIMUM 4" P-401 OVERLAY. SOIL: SP. 1943: 1" - 2" AC ON 8" LIME ROCK BASE
1/1/1971	IMPORT ED	OVERLAY	0.00	4.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.00	<input checked="" type="checkbox"/>	

Network: SPACE COAST REG		Branch: TW B	TAXIWAY B		Section: 205	Surface: AAC
L.C.D. 6/1/2002	Use: TAXIWAY	Rank: P	Length: 400.00 (Ft)	Width: 50.00 (Ft)	True Area: 22146.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1976 1.5" P401 OVERLAY. SEAL COAT. 1943 3.5" AC ON 8" LIMEROCK BASE
1/1/1976	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	3.50	<input checked="" type="checkbox"/>	

Network: SPACE COAST REG		Branch: TW B	TAXIWAY B		Section: 210	Surface: AAC
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 4,450.00 (Ft)	Width: 50.00 (Ft)	True Area: 223574.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	ML-OVL	Mill and Overlay	0.00	1.50	<input checked="" type="checkbox"/>	2013: 1.5" Mill and Overlay
1/1/1976	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1976 1.5" P401 OVERLAY. SEAL COAT.
1/1/1943	IMPORT ED	BUILT	0.00	3.50	<input checked="" type="checkbox"/>	1943 3.5" AC SURFACE ON 8" LIMEROCK BASE

Network: SPACE COAST REG		Branch: TW B	TAXIWAY B		Section: 215	Surface: AAC
L.C.D. 5/1/2022	Use: TAXIWAY	Rank: P	Length: 214.00 (Ft)	Width: 50.00 (Ft)	True Area: 11820.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2022	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	On-going
1/1/2013	ML-OVL	Mill and Overlay	0.00	1.50	<input checked="" type="checkbox"/>	2013: 1.5" Mill and Overlay
1/1/1976	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1976 1.5" P401 OVERLAY. SEAL COAT.
1/1/1943	IMPORT ED	BUILT	0.00	3.50	<input checked="" type="checkbox"/>	1943 3.5" AC SURFACE ON 8" LIMEROCK BASE

Network: SPACE COAST REG		Branch: TW C	TAXIWAY C		Section: 305	Surface: AAC
L.C.D. 1/1/2004	Use: TAXIWAY	Rank: P	Length: 700.00 (Ft)	Width: 65.00 (Ft)	True Area: 46879.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2004	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1971 3" P401
1/1/1971	IMPORT ED	OVERLAY	0.00	3.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	
1943 1.5" AC SURFACE ON 8" LIMEROCK BASE						

11/17/2022

## Work History Report

Page 8 of 10

Pavement Database: FDOT

Network: SPACE COAST REG		Branch: TW C	TAXIWAY C		Section: 310	Surface: AAC
L.C.D. 1/1/1986	Use: TAXIWAY	Rank: P	Length: 2,300.00 (Ft)	Width: 50.00 (Ft)	True Area: 116660.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1986	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1986 1.5" AC SURFACE
1/1/1943	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1943 1.5" AC SURFACE ON 8" LIMEROCK BASE

Network: SPACE COAST REG		Branch: TW C	TAXIWAY C		Section: 315	Surface: AAC
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 290.00 (Ft)	Width: 50.00 (Ft)	True Area: 15628.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2013: 1.5" Mill and Overlay
1/1/1976	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1976 1.5" P401 OVERLAY. EMULSION SEAL.
1/1/1943	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1943 1.5" AC SURFACE ON 8" LIMEROCK BASE

Network: SPACE COAST REG		Branch: TW C	TAXIWAY C		Section: 320	Surface: AAC
L.C.D. 6/1/2002	Use: TAXIWAY	Rank: P	Length: 100.00 (Ft)	Width: 38.00 (Ft)	True Area: 3845.000001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
6/1/2002	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1971	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1971 AC

Network: SPACE COAST REG		Branch: TW C	TAXIWAY C		Section: 325	Surface: AAC
L.C.D. 5/1/2022	Use: TAXIWAY	Rank: P	Length: 295.00 (Ft)	Width: 50.00 (Ft)	True Area: 17228.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/1/2022	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	On-going
1/1/2013	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	2013: 1.5" Mill and Overlay
1/1/1976	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1976 1.5" P401 OVERLAY. EMULSION SEAL.
1/1/1943	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1943 1.5" AC SURFACE ON 8" LIMEROCK BASE

Network: SPACE COAST REG		Branch: TW D	TAXIWAY D		Section: 405	Surface: AAC
L.C.D. 1/1/2000	Use: TAXIWAY	Rank: P	Length: 550.00 (Ft)	Width: 50.00 (Ft)	True Area: 33961.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1943	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	1943 2" AC ON 8" LIME ROCK BASE

Network: SPACE COAST REG		Branch: TW D	TAXIWAY D		Section: 410	Surface: AAC
L.C.D. 1/1/2000	Use: TAXIWAY	Rank: P	Length: 1,450.00 (Ft)	Width: 50.00 (Ft)	True Area: 73750.00002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2000	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1985	IMPORT ED	BUILT	0.00	0.00	<input checked="" type="checkbox"/>	ESTIMATE 1985 AC PAVEMENT



11/17/2022

## Work History Report

Page 9 of 10

Pavement Database: FDOT

Network: SPACE COAST REG Branch: TW E TAXIWAY E Section: 505 Surface: AAC  
 L.C.D. 1/1/1998 Use: TAXIWAY Rank: P Length: 600.00 (Ft) Width: 50.00 (Ft) True Area: 32371.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1998	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	ASSUME 1943 2" AC ON 8" LIMEROCK
1/1/1943	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

Network: SPACE COAST REG Branch: TW E TAXIWAY E Section: 515 Surface: AAC  
 L.C.D. 1/1/2003 Use: TAXIWAY Rank: P Length: 705.00 (Ft) Width: 50.00 (Ft) True Area: 44841.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1943 2" AC ON 8" LIMEROCK
1/1/1943	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

Network: SPACE COAST REG Branch: TW E TAXIWAY E Section: 525 Surface: AC  
 L.C.D. 1/1/2014 Use: TAXIWAY Rank: P Length: 100.00 (Ft) Width: 85.00 (Ft) True Area: 8165.000002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2014	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: SPACE COAST REG Branch: TW E TAXIWAY E Section: 535 Surface: AAC  
 L.C.D. 1/1/2003 Use: TAXIWAY Rank: P Length: 1,962.00 (Ft) Width: 35.00 (Ft) True Area: 68681.00002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1943 2" AC ON 8" LIMEROCK
1/1/1943	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

Network: SPACE COAST REG Branch: TW F TAXIWAY F Section: 605 Surface: AAC  
 L.C.D. 1/1/1998 Use: TAXIWAY Rank: P Length: 580.00 (Ft) Width: 50.00 (Ft) True Area: 30388.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/1998	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1943: 2" AC ON 8" LIME ROCK BASE. SOIL: SP.
1/1/1943	IMPORT ED	BUILT	0.00	2.00	<input checked="" type="checkbox"/>	

**Summary:**

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	35	2,528,673.00	1.53	1.08
Crack Sealing - AC	1	52,187.00	0.00	0.00
Mill and Overlay	44	3,329,639.00	0.07	0.31
New Construction - AC	2	325,405.00	1.75	1.75
New Construction - Initial	12	1,147,800.00	1.77	4.19
New Construction - PCC	2	145,277.00	0.00	0.00
OVERLAY	21	1,980,054.00	2.33	0.89
Overlay - AC Structural	3	692,187.00	1.33	1.03
Surface Treatment - Seal Coat	7	352,680.00	0.00	0.00

11/17/2022

**Branch Condition Report**

Page 1 of 2

*Pavement Database: FDOT*

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP E	16	7,562.00	161.19	620,726.00	APRON	74.56	12.39	75.19
AP HELI	2	1,219.00	290.00	397,538.00	APRON	90.50	4.50	94.26
AP W	2	1,668.00	450.00	400,935.00	APRON	84.00	13.00	95.02
RW 18-36	6	21,919.00	62.50	1,097,850.00	RUNWAY	58.67	2.49	58.09
RW 9-27	3	4,875.00	100.00	489,743.00	RUNWAY	84.33	22.16	93.50
TW A	5	6,000.00	50.00	304,658.00	TAXIWAY	60.40	2.80	60.15
TW A1	1	500.00	65.00	50,631.00	TAXIWAY	49.00	0.00	49.00
TW A2	1	600.00	500.00	35,137.00	TAXIWAY	61.00	0.00	61.00
TW B	3	5,064.00	50.00	257,540.00	TAXIWAY	79.00	19.51	82.07
TW C	5	3,685.00	50.60	200,240.00	TAXIWAY	71.80	18.26	64.75
TW D	2	2,000.00	50.00	107,711.00	TAXIWAY	65.00	0.00	65.00
TW E	4	3,367.00	55.00	154,058.00	TAXIWAY	74.50	10.52	69.84
TW F	1	580.00	50.00	30,388.00	TAXIWAY	14.00	0.00	14.00

**11/17/2022****Branch Condition Report****Page 2 of 2***Pavement Database: FDOT*

<b>Use Category</b>	<b>Number of Sections</b>	<b>Total Area (SqFt)</b>	<b>Arithmetic Average PCI</b>	<b>Average STD PCI</b>	<b>Weighted Average PCI</b>
APRON	20	1,419,199.00	77.10	13.03	86.13
RUNWAY	9	1,587,593.00	67.22	17.72	69.01
TAXIWAY	22	1,140,363.00	65.91	18.38	65.98
ALL	51	4,147,155.00	70.53	17.20	74.04

Pavement Database: FDOT

NetworkId: TIX

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP E	4205	1/1/2008	AAC	APRON	P	0	100,353.00	4/12/2022	14	60
AP E	4214	6/1/2002	APC	APRON	P	0	52,187.00	4/12/2022	20	55
AP E	4215	1/1/1971	AC	APRON	P	0	77,281.00	4/12/2022	51	63
AP E	4216	1/1/2008	AAC	APRON	P	0	48,812.00	4/12/2022	14	81
AP E	4218	1/1/2008	AAC	APRON	P	0	94,806.00	4/12/2022	14	77
AP E	4219	1/1/2015	AAC	APRON	P	0	8,237.00	4/12/2022	7	57
AP E	4220	1/1/2014	AAC	APRON	P	0	33,963.00	4/12/2022	8	77
AP E	4221	1/1/2008	AC	APRON	P	0	5,405.00	4/12/2022	14	69
AP E	4225	1/1/1991	PCC	APRON	P	0	8,700.00	4/12/2022	31	65
AP E	4229	1/1/2012	AC	APRON	P	0	16,379.00	4/12/2022	10	87
AP E	4230	1/1/1991	PCC	APRON	P	0	9,662.00	4/12/2022	31	76
AP E	4232	1/1/2014	AAC	APRON	P	0	10,659.00	4/12/2022	8	78
AP E	4235	1/1/2015	PCC	APRON	P	0	93,090.00	4/12/2022	7	99
AP E	4240	1/1/2014	AAC	APRON	P	0	15,772.00	4/12/2022	8	84
AP E	4245	1/1/2003	AC	APRON	P	0	7,200.00	4/12/2022	19	71
AP E	4250	1/1/2011	PCC	APRON	P	0	38,220.00	4/12/2022	11	94
AP HELI	4255	1/1/2012	AC	APRON	P	0	32,798.00	4/12/2022	10	86
AP HELI	4260	1/1/2012	PCC	APRON	P	0	364,740.00	4/12/2022	10	95
AP W	4305	1/1/2014	PCC	APRON	P	0	370,471.00	4/12/2022	8	97
AP W	4310	1/1/2014	AAC	APRON	P	0	30,464.00	4/12/2022	8	71
RW 18-36	6105	6/1/2002	AAC	RUNWAY	P	0	500,000.00	4/12/2022	20	58
RW 18-36	6110	6/1/2002	AAC	RUNWAY	P	0	250,000.00	4/12/2022	20	57
RW 18-36	6125	6/1/2002	AAC	RUNWAY	P	0	100,000.00	4/12/2022	20	55
RW 18-36	6130	6/1/2002	AAC	RUNWAY	P	0	50,000.00	4/12/2022	20	59
RW 18-36	6145	6/1/2002	AAC	RUNWAY	P	0	131,900.00	4/12/2022	20	60
RW 18-36	6150	6/1/2002	AAC	RUNWAY	P	0	65,950.00	4/12/2022	20	63
RW 9-27	6205	6/1/2002	AAC	RUNWAY	P	0	67,743.00	4/12/2022	20	53
RW 9-27	6210	5/1/2022	AAC	RUNWAY	P	0	320,000.00	5/1/2022	0	100
RW 9-27	6215	5/1/2022	AAC	RUNWAY	P	0	102,000.00	5/1/2022	0	100
TW A	105	6/1/2002	AAC	TAXIWAY	P	0	114,651.00	4/12/2022	20	59
TW A	110	6/1/2002	AAC	TAXIWAY	P	0	70,000.00	4/12/2022	20	62
TW A	112	6/1/2002	AAC	TAXIWAY	P	0	30,000.00	4/12/2022	20	59
TW A	115	6/1/2002	AAC	TAXIWAY	P	0	50,000.00	4/12/2022	20	57
TW A	120	6/1/2002	AAC	TAXIWAY	P	0	40,007.00	4/12/2022	20	65
TW A1	130	6/1/2002	AAC	TAXIWAY	P	0	50,631.00	4/12/2022	20	49
TW A2	125	6/1/2002	AAC	TAXIWAY	P	0	35,137.00	4/12/2022	20	61
TW B	205	6/1/2002	AAC	TAXIWAY	P	0	22,146.00	4/12/2022	20	53
TW B	210	1/1/2013	AAC	TAXIWAY	P	0	223,574.00	4/12/2022	9	84
TW B	215	5/1/2022	AAC	TAXIWAY	P	0	11,820.00	5/1/2022	0	100
TW C	305	1/1/2004	AAC	TAXIWAY	P	0	46,879.00	4/12/2022	18	57
TW C	310	1/1/1986	AAC	TAXIWAY	P	0	116,660.00	4/12/2022	36	60
TW C	315	1/1/2013	AAC	TAXIWAY	P	0	15,628.00	4/12/2022	9	87
TW C	320	6/1/2002	AAC	TAXIWAY	P	0	3,845.00	4/12/2022	20	55
TW C	325	5/1/2022	AAC	TAXIWAY	P	0	17,228.00	5/1/2022	0	100
TW D	405	1/1/2000	AAC	TAXIWAY	P	0	33,961.00	4/12/2022	22	65
TW D	410	1/1/2000	AAC	TAXIWAY	P	0	73,750.00	4/12/2022	22	65
TW E	505	1/1/1998	AAC	TAXIWAY	P	0	32,371.00	4/12/2022	24	72
TW E	515	1/1/2003	AAC	TAXIWAY	P	0	44,841.00	4/12/2022	19	64
TW E	525	1/1/2014	AC	TAXIWAY	P	0	8,165.00	4/12/2022	8	92
TW E	535	1/1/2003	AAC	TAXIWAY	P	0	68,681.00	4/12/2022	19	70



TW F	605	1/1/1998	AAC	TAXIWAY	P	0	30,388.00	4/12/2022	24	14
------	-----	----------	-----	---------	---	---	-----------	-----------	----	----

*Pavement Database: FDOT*

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		451,048.00	4	100.00	0.00	100.00
06-10	8	1,223,940.00	13	84.15	11.04	91.79
11-15	13	287,596.00	5	76.20	11.44	73.86
16-20	20	1,801,798.00	21	59.14	5.29	58.51
21-25	23	170,470.00	4	54.00	23.27	57.24
31-35	31	18,362.00	2	70.50	5.50	70.79
36-40	36	116,660.00	1	60.00	0.00	60.00
50+	51	77,281.00	1	63.00	0.00	63.00
ALL	16	4,147,155.00	51	70.53	17.20	74.04



# **Appendix B: Maintenance and Rehabilitation Planning Needs**



Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
TIX	TW B	210	WEATHERING	Medium	7,825	SF	3.5%	Preventive	Surface Seal	7,825	SF	\$ 0.75	\$ 5,870
TIX	TW C	315	WEATHERING	Medium	313	SF	2.0%	Preventive	Surface Seal	312	SF	\$ 0.75	\$ 240
TIX	TW E	505	L & T CR	Medium	466	LF	1.4%	Preventive	AC Crack Sealing	466	LF	\$ 4.00	\$ 1,870
TIX	TW E	505	WEATHERING	Medium	32,371	SF	100.0%	Preventive	Surface Seal	32,371	SF	\$ 0.75	\$ 24,280
TIX	TW E	525	WEATHERING	Medium	163	SF	2.0%	Preventive	Surface Seal	163	SF	\$ 0.75	\$ 130
TIX	AP E	4216	WEATHERING	Medium	12,198	SF	25.0%	Preventive	Surface Seal	12,199	SF	\$ 0.75	\$ 9,150
TIX	AP E	4218	L & T CR	Medium	76	LF	0.1%	Preventive	AC Crack Sealing	76	LF	\$ 4.00	\$ 310
TIX	AP E	4218	WEATHERING	Medium	23,701	SF	25.0%	Preventive	Surface Seal	23,701	SF	\$ 0.75	\$ 17,780
TIX	AP E	4220	WEATHERING	Medium	3,971	SF	11.7%	Preventive	Surface Seal	3,971	SF	\$ 0.75	\$ 2,980
TIX	AP E	4229	WEATHERING	Medium	818	SF	5.0%	Preventive	Surface Seal	818	SF	\$ 0.75	\$ 620
TIX	AP E	4232	WEATHERING	Medium	1,979	SF	18.6%	Preventive	Surface Seal	1,980	SF	\$ 0.75	\$ 1,490
TIX	AP E	4240	WEATHERING	Medium	1,577	SF	10.0%	Preventive	Surface Seal	1,577	SF	\$ 0.75	\$ 1,190
TIX	AP E	4245	RAVELING	Low	432	SF	6.0%	Preventive	Surface Seal	432	SF	\$ 0.75	\$ 330
TIX	AP E	4245	WEATHERING	Medium	6,768	SF	94.0%	Preventive	Surface Seal	6,768	SF	\$ 0.75	\$ 5,080
TIX	AP HELI	4255	WEATHERING	Medium	1,640	SF	5.0%	Preventive	Surface Seal	1,640	SF	\$ 0.75	\$ 1,230
TIX	AP HELI	4260	JT SEAL DMG	Low	1,267	Slabs	50.0%	Preventive	PCC Joint Seal	30,993	LF	\$ 4.25	\$ 131,730
TIX	AP HELI	4260	JOINT SPALL	Medium	10	Slabs	0.4%	Preventive	PCC Partial-Depth Patching	61	SF	\$ 169.00	\$ 10,400
TIX	AP W	4305	JT SEAL DMG	Low	749	Slabs	45.5%	Preventive	PCC Joint Seal	47,530	LF	\$ 4.25	\$ 202,010
TIX	AP W	4310	L & T CR	Medium	463	LF	1.5%	Preventive	AC Crack Sealing	463	LF	\$ 4.00	\$ 1,860
TIX	AP W	4310	WEATHERING	Medium	11,567	SF	38.0%	Preventive	Surface Seal	11,567	SF	\$ 0.75	\$ 8,680
TIX	RW 18-36	6145	PATCHING	High	162	SF	0.1%	Stopgap	AC Full-Depth Patching	217	SF	\$ 10.00	\$ 2,180
TIX	TW F	605	ALLIGATOR CR	Medium	443	SF	1.5%	Stopgap	AC Full-Depth Patching	532	SF	\$ 10.00	\$ 5,320
TIX	TW F	605	ALLIGATOR CR	High	8	SF	0.0%	Stopgap	AC Full-Depth Patching	23	SF	\$ 10.00	\$ 230
TIX	TW F	605	RAVELING	High	8	SF	0.0%	Stopgap	AC Partial-Depth Patching	8	SF	\$ 4.75	\$ 40

*Table B.2: Section-Level 10-Year Major Rehabilitation Needs*

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	TIX	RW 9-27	6205	AAC	67,743	51	AC Reconstruction	\$ 1,084,000
2023	TIX	RW 18-36	6105	AAC	500,000	56	AC Rehabilitation	\$ 4,501,000
2023	TIX	RW 18-36	6110	AAC	250,000	55	AC Reconstruction	\$ 2,881,000
2023	TIX	RW 18-36	6125	AAC	100,000	53	AC Reconstruction	\$ 1,600,000
2023	TIX	RW 18-36	6130	AAC	50,000	57	AC Rehabilitation	\$ 451,000
2023	TIX	RW 18-36	6145	AAC	131,900	58	AC Rehabilitation	\$ 1,188,000
2023	TIX	RW 18-36	6150	AAC	65,950	61	AC Rehabilitation	\$ 594,000
2023	TIX	TW A	105	AAC	114,651	57	AC Rehabilitation	\$ 1,032,000
2023	TIX	TW A	110	AAC	70,000	60	AC Rehabilitation	\$ 631,000
2023	TIX	TW A	112	AAC	30,000	57	AC Rehabilitation	\$ 271,000
2023	TIX	TW A	115	AAC	50,000	55	AC Rehabilitation	\$ 451,000
2023	TIX	TW A	120	AAC	40,007	63	AC Rehabilitation	\$ 361,000
2023	TIX	TW A1	130	AAC	50,631	47	AC Reconstruction	\$ 811,000
2023	TIX	TW A2	125	AAC	35,137	59	AC Rehabilitation	\$ 317,000
2023	TIX	TW B	205	AAC	22,146	51	AC Reconstruction	\$ 355,000
2023	TIX	TW C	305	AAC	46,879	55	AC Rehabilitation	\$ 422,000
2023	TIX	TW C	310	AAC	116,660	58	AC Rehabilitation	\$ 1,050,000
2023	TIX	TW C	320	AAC	3,845	53	AC Reconstruction	\$ 62,000
2023	TIX	TW D	405	AAC	33,961	63	AC Rehabilitation	\$ 306,000
2023	TIX	TW D	410	AAC	73,750	63	AC Rehabilitation	\$ 664,000
2023	TIX	TW E	515	AAC	44,841	62	AC Rehabilitation	\$ 404,000
2023	TIX	TW E	535	AAC	68,681	68	AC Rehabilitation	\$ 619,000
2023	TIX	TW F	605	AAC	30,388	11	AC Reconstruction	\$ 487,000
2023	TIX	AP E	4205	AAC	100,353	58	AC Rehabilitation	\$ 904,000
2023	TIX	AP E	4214	APC	52,187	53	AC Reconstruction	\$ 835,000
2023	TIX	AP E	4215	AC	77,281	61	AC Rehabilitation	\$ 696,000
2023	TIX	AP E	4219	AAC	8,237	55	AC Reconstruction	\$ 95,000
2023	TIX	AP E	4221	AC	5,405	67	AC Rehabilitation	\$ 49,000
2023	TIX	AP E	4225	PCC	8,700	64	PCC Rehabilitation	\$ 131,000
2023	TIX	AP E	4245	AC	7,200	69	AC Rehabilitation	\$ 65,000



# Airport Pavement Evaluation Report

## Statewide Airfield Pavement Management Program

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	TIX	AP W	4310	AAC	30,464	69	AC Rehabilitation	\$ 275,000
2024	TIX	TW E	505	AAC	32,371	69	AC Rehabilitation	\$ 306,000
2026	TIX	AP E	4218	AAC	94,806	69	AC Rehabilitation	\$ 988,000
2026	TIX	AP E	4220	AAC	33,963	69	AC Rehabilitation	\$ 354,000
2026	TIX	AP E	4232	AAC	10,659	70	AC Rehabilitation	\$ 112,000
2028	TIX	AP E	4216	AAC	48,812	69	AC Rehabilitation	\$ 561,000
2029	TIX	AP E	4230	PCC	9,662	69	PCC Rehabilitation	\$ 195,000
2029	TIX	AP E	4240	AAC	15,772	70	AC Rehabilitation	\$ 191,000
2031	TIX	TW B	210	AAC	223,574	70	AC Rehabilitation	\$ 2,974,000
2031	TIX	AP HELI	4255	AC	32,798	69	AC Rehabilitation	\$ 437,000
2032	TIX	AP E	4229	AC	16,379	69	AC Rehabilitation	\$ 229,000


*\*All planning cost values have been rounded up to the nearest thousand dollars.*



# Appendix C: Technical Exhibits









## LEGEND

- TYPICAL RUNWAY BRANCH ID
- TYPICAL TAXIWAY BRANCH ID
- TYPICAL APRON BRANCH ID
- PAVEMENT SURFACE TYPE  
PAVEMENT BRANCH ID  
SECTION NUMBER
- NUMBER OF SAMPLE UNITS IN SECTION  
NUMBER OF SAMPLE UNITS TO BE INSPECTED
- SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- INSPECTED SAMPLE UNITS.


TOTAL SAMPLES INSPECTED = 141  
AC: 115 PCC: 26

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2022	RW 9-27, TW B, TW C	Mill and Overlay



**LEGEND**

TYPICAL RUNWAY BRANCH ID

TYPICAL TAXIWAY BRANCH ID

TYPICAL APRON BRANCH ID


**PROJECT YEAR**


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



AIRFIELD PAVEMENT  
ESTIMATED AGE EXHIBIT

Statewide Airfield Pavement  
Management Program  
SPACE COAST REGIONAL AIRPORT



**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID

TW A — TYPICAL TAXIWAY BRANCH ID


AP S — TYPICAL APRON BRANCH ID

**AGE AT INSPECTION**

0-5 Years
6-10 Years
11-15 Years
16-20 Years
> 20 Years

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





**LEGEND**

RW 13-31

← TYPICAL RUNWAY BRANCH ID








TW A

← TYPICAL TAXIWAY BRANCH ID

AP S


← TYPICAL APRON BRANCH ID

**2022 PAVEMENT CONDITION INDEX**

	PCI 86-100 Good
	PCI 71-85 Satisfactory
	PCI 56-70 Fair
	PCI 41-55 Poor
	PCI 26-40 Very Poor
	PCI 11-25 Serious
	PCI 0-10 Failed

"SECTION ID"  
 "PCI VALUE"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



TW A:112 2023   AC REHAB \$0.27 M	TW B:205 2023   AC RECON \$0.36 M	TW C:305 2023   AC REHAB \$0.42 M	TW C:310 2023   AC REHAB \$1.05 M
TW C:320 2023   AC RECON \$0.06 M	TW D:405 2023   AC REHAB \$0.31 M	TW E:515 2023   AC REHAB \$0.40 M	AP E:4214 2023   AC RECON \$0.84 M
AP E:4215 2023   AC REHAB \$0.70 M	AP E:4219 2023   AC REHAB \$0.10 M	AP E:4221 2023   AC REHAB \$0.05 M	AP W:4310 2023   AC REHAB \$0.28 M
TW E:505 2024   AC REHAB \$0.31 M	AP E:4218 2026   AC REHAB \$0.99 M	AP E:4232 2026   AC REHAB \$0.11 M	AP E:4216 2028   AC REHAB \$0.56 M

**LEGEND**

RW 13-31 — TYPICAL RUNWAY BRANCH ID  
TW A — TYPICAL TAXIWAY BRANCH ID  
AP S — TYPICAL APRON BRANCH ID

**PROGRAM YEAR**

2023	2028
2024	2029
2025	2030
2026	2031
2027	2032

"BRANCH": "SECTION"  
"YEAR": "REHAB ACTIVITY"  
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





# **Appendix D: Inspection Photograph Documentation**







RW 9-27, Section 6205, Sample Unit 100 – Longitudinal & Transverse Cracking and Weathering



RW 18-36, Section 6105, Sample Unit 302 – Longitudinal & Transverse Cracking and Swelling





RW 18-36, Section 6105, Sample Unit 376 – Longitudinal & Transverse Cracking



RW 18-36, Section 6110, Sample Unit 176 – Vicinity





TW A, Section 105, Sample Unit 108 – Longitudinal & Transverse Cracking and Weathering



TW A, Section 120, Sample Unit 151 – Swelling





TW B, Section 205, Sample Unit 502 – Longitudinal & Transverse Cracking



TW C, Section 305, Sample Unit 704– Longitudinal & Transverse Cracking





TW F, Section 605, Sample Unit 301 – Block Cracking



AP E, Section 4205, Sample Unit 250 – Block Cracking





AP HELI, Section 4260, Sample Unit 646 – Shrinkage Cracking



AP W, Section 4305, Sample Unit 260 – Vicinity





# **Appendix E: Inspection Distress Details**





# Re-Inspection Report

FDOT

Generated Date 11/17/2022

Page 1 of 57

<b>Network:</b>	TIX		<b>Name:</b>	SPACE COAST REGIONAL AIRPORT			
<b>Branch:</b>	AP E		<b>Name:</b>	EAST APRON		<b>Use:</b>	APRON
			<b>Area:</b>	620,726 SqFt			
<b>Section:</b>	4205	of 16	<b>From:</b>	-		<b>To:</b>	-
			<b>Last Const.:</b>	1/1/2008			
<b>Surface:</b>	AAC	<b>Family:</b>	CA653-GA-AP-AAC-APC	<b>Zone:</b>		<b>Category:</b>	
			<b>Rank:</b>	P			
<b>Area:</b>	100,353 SqFt	<b>Length:</b>	225 Ft	<b>Width:</b>	780 Ft		
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft
<b>Shoulder:</b>		<b>Street Type:</b>		<b>Grade:</b>	0	<b>Lanes:</b>	0
<b>Section Comments:</b>							
<b>Work Date:</b>	1/1/1968	<b>Work Type:</b>	BUILT	<b>Code:</b>	IMPORTED	<b>Is Major M&amp;R:</b>	True
<b>Work Date:</b>	1/1/1992	<b>Work Type:</b>	Surface Treatment - Seal Coat	<b>Code:</b>	ST-SC	<b>Is Major M&amp;R:</b>	False
<b>Work Date:</b>	1/1/2008	<b>Work Type:</b>	Mill and Overlay	<b>Code:</b>	ML-OVL	<b>Is Major M&amp;R:</b>	True
<b>Last Insp. Date:</b>	4/12/2022	<b>TotalSamples:</b>	20	<b>Surveyed:</b>	3		
<b>Conditions:</b>	PCI: 60						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	150	<b>Type:</b>	R	<b>Area:</b>	5011.00 SqFt	<b>PCI:</b>	66
<b>Sample Comments:</b>							
48	L & T CR	L	234.00	Ft			
48	L & T CR	M	100.00	Ft			
56	SWELLING	L	50.00	SqFt			
57	WEATHERING	L	4510.00	SqFt			
57	WEATHERING	M	501.00	SqFt			
<b>Sample Number:</b>	203	<b>Type:</b>	R	<b>Area:</b>	5900.00 SqFt	<b>PCI:</b>	64
<b>Sample Comments:</b>							
48	L & T CR	L	360.00	Ft			
48	L & T CR	M	38.00	Ft			
50	PATCHING	L	36.00	SqFt			
56	SWELLING	L	5.00	SqFt			
57	WEATHERING	L	4398.00	SqFt			
57	WEATHERING	M	1466.00	SqFt			
<b>Sample Number:</b>	250	<b>Type:</b>	R	<b>Area:</b>	5000.00 SqFt	<b>PCI:</b>	48
<b>Sample Comments:</b>							
43	BLOCK CR	L	3000.00	SqFt			
48	L & T CR	L	211.00	Ft			
48	L & T CR	M	28.00	Ft			
56	SWELLING	L	9.00	SqFt			
57	WEATHERING	L	3750.00	SqFt			
57	WEATHERING	M	1250.00	SqFt			

Network:	TIX		Name:		SPACE COAST REGIONAL AIRPORT						
Branch:	AP E		Name:		EAST APRON		Use:	APRON	Area:	620,726 SqFt	
Section:	4214		of 16		From: -		To: -		Last Const.: 6/1/2002		
Surface:	APC		Family:		CA653-GA-AP-AAC-APC		Zone:		Category:		Rank: P
Area:	52,187 SqFt		Length:		1,100 Ft		Width:		35 Ft		
Slabs:	209		Slab Length:		20 Ft		Slab Width:		12 Ft		Joint Length: 3,870 Ft
Shoulder:			Street Type:				Grade: 0		Lanes: 0		
Section Comments:											
Work Date:	1/1/1943		Work Type: New Construction - PCC					Code:	NC-PC		Is Major M&R: True
Work Date:	1/1/1971		Work Type: Overlay - AC Structural					Code:	OL-AS		Is Major M&R: True
Work Date:	1/1/1992		Work Type: Surface Treatment - Seal Coat					Code:	ST-SC		Is Major M&R: False
Work Date:	6/1/2002		Work Type: Mill and Overlay					Code:	ML-OVL		Is Major M&R: True
Work Date:	1/1/2020		Work Type: Crack Sealing - AC					Code:	CS-AC		Is Major M&R: False
Last Insp. Date:	4/12/2022		TotalSamples:		13		Surveyed: 2				
Conditions:	PCI: 55										
Inspection Comments:											
Sample Number:	106		Type:	R		Area:		3500.00 SqFt		PCI: 57	
Sample Comments:											
48	L & T CR		L		446.00 Ft						
48	L & T CR		M		150.00 Ft						
57	WEATHERING		M		3500.00 SqFt						
Sample Number:	108		Type:	R		Area:		5000.00 SqFt		PCI: 53	
Sample Comments:											
47	JT REF. CR		L		475.00 Ft						
47	JT REF. CR		M		25.00 Ft						
48	L & T CR		L		233.00 Ft						
48	L & T CR		M		24.00 Ft						
50	PATCHING		L		1250.00 SqFt						
57	WEATHERING		M		3750.00 SqFt						

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT										
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt				
Section:	4215		of	16		From:	-		To:	-		Last Const.:	1/1/1971	
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Category:			Rank:	P	
Area:	77,281 SqFt		Length:	330 Ft		Width:			230 Ft					
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1971		Work Type: BUILT					Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1992		Work Type: Surface Treatment - Seal Coat					Code:	ST-SC		Is Major M&R:	False		
Last Insp. Date:	4/12/2022		TotalSamples:	19		Surveyed:	3							
Conditions:	PCI: 63													
Inspection Comments:														
Sample Number:	208		Type:	R		Area:	4032.00 SqFt		PCI:	62				
Sample Comments:														
48	L & T CR		L	206.00 Ft										
52	RAVELING		L	4032.00 SqFt										
56	SWELLING		L	605.00 SqFt										
Sample Number:	256		Type:	R		Area:	5000.00 SqFt		PCI:	64				
Sample Comments:														
48	L & T CR		L	71.00 Ft										
52	RAVELING		L	5000.00 SqFt										
56	SWELLING		L	750.00 SqFt										
Sample Number:	304		Type:	R		Area:	3200.00 SqFt		PCI:	64				
Sample Comments:														
52	RAVELING		L	3195.00 SqFt										
52	RAVELING		M	5.00 SqFt										
56	SWELLING		L	640.00 SqFt										

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT									
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt				
Section:	4216		of	16		From:	-		To:	-		Last Const.:	1/1/2008	
Surface:	AAC		Family:	CA653-GA-AP-AAC-APC		Zone:			Category:			Rank:	P	
Area:	48,812 SqFt		Length:	160 Ft		Width:	305 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1971		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Work Date:	1/1/2008		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True		
Last Insp. Date: 4/12/2022														
Conditions:	PCI: 81		TotalSamples:	9		Surveyed:	1							
Inspection Comments:														
Sample Number:	451		Type:	R		Area:	5250.00 SqFt		PCI:	81				
Sample Comments:														
48	L & T CR		L	35.00 Ft										
57	WEATHERING		L	3938.00 SqFt										
57	WEATHERING		M	1312.00 SqFt										



Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT											
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt						
Section:	4218		of	16		From:	-		To:	-		Last Const.:	1/1/2008			
Surface:	AAC		Family:	CA653-GA-AP-AAC-APC		Zone:			Category:			Rank:	P			
Area:	94,806 SqFt		Length:	195 Ft		Width:	525 Ft									
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft						
Shoulder:			Street Type:			Grade:	0		Lanes:	0						
Section Comments:																
Work Date:	1/1/1971		Work Type:				New Construction - Initial				Code:	NU-IN		Is Major M&R:	True	
Work Date:	1/1/2008		Work Type:				Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True	
Last Insp. Date:	4/12/2022		TotalSamples:	18		Surveyed:	3									
Conditions:	PCI:		77													
Inspection Comments:																
Sample Number:	101		Type:	R		Area:	5000.00 SqFt		PCI:	68						
Sample Comments:																
48	L & T CR		L	263.00 Ft												
48	L & T CR		M	13.00 Ft												
56	SWELLING		L	23.00 SqFt												
57	WEATHERING		L	3750.00 SqFt												
57	WEATHERING		M	1250.00 SqFt												
Sample Number:	200		Type:	R		Area:	6200.00 SqFt		PCI:	80						
Sample Comments:																
48	L & T CR		L	127.00 Ft												
57	WEATHERING		L	4650.00 SqFt												
57	WEATHERING		M	1550.00 SqFt												
Sample Number:	252		Type:	R		Area:	5000.00 SqFt		PCI:	82						
Sample Comments:																
48	L & T CR		L	7.00 Ft												
57	WEATHERING		L	3750.00 SqFt												
57	WEATHERING		M	1250.00 SqFt												

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT						
Branch:	AP E	Name:	EAST APRON		Use:	APRON	Area:	620,726 SqFt			
Section:	4219	of	16	From:	-	To:	-	Last Const.:	1/1/2015		
Surface:	AAC	Family:	CA653-GA-AP-AAC-APC		Zone:	Category:		Rank:	P		
Area:	8,237 SqFt		Length:	55 Ft		Width:	151 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1971		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1992		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2015		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	57									
Inspection Comments:											
Sample Number:	260	Type:	R	Area:	4091.00 SqFt		PCI:	57			
Sample Comments:											
43	BLOCK CR		L	2464.00 SqFt							
48	L & T CR		L	12.00 Ft							
52	RAVELING		L	2464.00 SqFt							
57	WEATHERING		L	1627.00 SqFt							

Network:		TIX		Name:		SPACE COAST REGIONAL AIRPORT						
Branch:	AP E		Name:	EAST APRON		Use:	APRON	Area:	620,726 SqFt			
Section:	4220		of	16	From:	-		To:	-		Last Const.:	1/1/2014
Surface:	AAC		Family:	CA653-GA-AP-AAC-APC		Zone:			Category:	Rank: P		
Area:	33,963 SqFt		Length:	1,515 Ft		Width:	20 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1980		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1992		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2014		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	9		Surveyed:	2					
Conditions:	PCI: 77											
Inspection Comments:												
Sample Number:	200		Type:	R		Area:	4135.00 SqFt		PCI:	71		
Sample Comments:												
48	L & T CR		L	21.00 Ft								
50	PATCHING		L	435.00 SqFt								
57	WEATHERING		L	2960.00 SqFt								
57	WEATHERING		M	740.00 SqFt								
Sample Number:	300		Type:	R		Area:	3837.00 SqFt		PCI:	84		
Sample Comments:												
48	L & T CR		L	76.00 Ft								
57	WEATHERING		L	3645.00 SqFt								
57	WEATHERING		M	192.00 SqFt								

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	AP E		Name:	EAST APRON		Use:	APRON	Area:	620,726 SqFt		
Section:	4221	of 16	From:	-			To:	-		Last Const.:	1/1/2008
Surface:	AC	Family:	CA653-GA-AP-AC		Zone:		Category:		Rank:	P	
Area:	5,405 SqFt		Length:	200 Ft		Width:	25 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2008		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI:	69									
Inspection Comments:											
Sample Number:	253	Type:	R	Area:	5405.00 SqFt		PCI:	69			
Sample Comments:											
48	L & T CR		L	107.00	Ft						
48	L & T CR		M	12.00	Ft						
50	PATCHING		L	60.00	SqFt						
52	RAVELING		L	20.00	SqFt						
57	WEATHERING		L	3825.00	SqFt						
57	WEATHERING		M	1500.00	SqFt						



Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt		
Section:	4225		of	16	From:	-		To:	-		Last Const.:	1/1/1991
Surface:	PCC		Family:	CA653-GA-AP-PCC		Zone:			Category:	Rank: P		
Area:	8,700 SqFt		Length:	400 Ft		Width:	20 Ft					
Slabs:	48		Slab Length:	12 Ft		Slab Width:	15 Ft		Joint Length:	780 Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1991		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	2		Surveyed:	1					
Conditions:	PCI: 65											
Inspection Comments:												
Sample Number:	103		Type:	R		Area:	26.00 Slabs		PCI:	65		
Sample Comments:												
63	LINEAR CR		L	15.00		Slabs						
71	FAULTING		L	1.00		Slabs						
72	SHAT. SLAB		L	1.00		Slabs						
73	SHRINKAGE CR		N	9.00		Slabs						

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT									
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt				
Section:	4229		of	16		From:	-		To:	-		Last Const.:	1/1/2012	
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Category:			Rank:	P	
Area:	16,379 SqFt		Length:	800 Ft		Width:			20 Ft					
Slabs:			Slab Length:	Ft		Slab Width:			Ft	Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2012		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Last Insp. Date:	4/12/2022		TotalSamples:	3		Surveyed:	1							
Conditions:	PCI: 87													
Inspection Comments:														
Sample Number:	750		Type:	R		Area:	5763.00 SqFt		PCI:	87				
Sample Comments:														
48	L & T CR		L	12.00 Ft										
57	WEATHERING		L	5475.00 SqFt										
57	WEATHERING		M	288.00 SqFt										

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt		
Section:	4230		of	16	From:	-		To:	-		Last Const.:	1/1/1991
Surface:	PCC		Family:	CA653-GA-AP-PCC		Zone:			Category:	Rank:		P
Area:	9,662 SqFt		Length:	445 Ft		Width:	20 Ft					
Slabs:	57		Slab Length:	10 Ft		Slab Width:	17 Ft		Joint Length:	949 Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1991		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	5		Surveyed:	1					
Conditions:	PCI: 76											
Inspection Comments:												
Sample Number:	205		Type:	R		Area:	18.00 Slabs		PCI:	76		
Sample Comments:												
63	LINEAR CR		L	8.00 Slabs								
73	SHRINKAGE CR		N	5.00 Slabs								

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	AP E		Name:	EAST APRON		Use:	APRON	Area:	620,726 SqFt
Section:	4232	of	16	From:	-	To:	-	Last Const.:	1/1/2014
Surface:	AAC	Family:	CA653-GA-AP-AAC-APC		Zone:	Category:		Rank:	P
Area:	10,659 SqFt		Length:	332 Ft		Width:	30 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1971		Work Type: BUILT				Code:	IMPORTED	
Work Date:	1/1/1992		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC	
Work Date:	1/1/2014		Work Type: Mill and Overlay				Code:	ML-OVL	
Last Insp. Date:	4/12/2022		TotalSamples:	3		Surveyed:	1		
Conditions:	PCI: 78								
Inspection Comments:									
Sample Number:	353	Type:	R	Area:	3570.00 SqFt		PCI:	78	
Sample Comments:									
50	PATCHING		L	253.00 SqFt					
57	WEATHERING		L	2654.00 SqFt					
57	WEATHERING		M	663.00 SqFt					



Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT					
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt
Section:	4235		of	16	From:	-		To:	-	
Surface:	PCC		Family:	CA653-GA-AP-PCC		Zone:			Category:	Rank: P
Area:	93,090 SqFt		Length:	495 Ft		Width:	178 Ft			
Slabs:	443	Slab Length:	14 Ft		Slab Width:	15 Ft		Joint Length:	11,495 Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	1/1/2015		Work Type: New Construction - PCC				Code:	NC-PC		Is Major M&R: True
Last Insp. Date:	4/12/2022		TotalSamples:	22		Surveyed:	3			
Conditions:	PCI: 99									
Inspection Comments:										
Sample Number:	213	Type:	R	Area:	25.00 Slabs		PCI:	99		
Sample Comments:										
66	SMALL PATCH		L	1.00 Slabs						
Sample Number:	265	Type:	R	Area:	20.00 Slabs		PCI:	100		
Sample Comments:										
<No Distress>										
Sample Number:	364	Type:	R	Area:	24.00 Slabs		PCI:	99		
Sample Comments:										
66	SMALL PATCH		L	1.00 Slabs						

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	AP E		Name:	EAST APRON		Use:	APRON	Area:	620,726 SqFt			
Section:	4240		of	16	From:	-		To:	-		Last Const.:	1/1/2014
Surface:	AAC		Family:	CA653-GA-AP-AAC-APC		Zone:			Category:	Rank: P		
Area:	15,772 SqFt		Length:	770 Ft		Width:	20 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1987		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2014		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	5		Surveyed:	1					
Conditions:	PCI: 84											
Inspection Comments:												
Sample Number:	303		Type:	R		Area:	4020.00 SqFt		PCI:	84		
Sample Comments:												
48	L & T CR		L	46.00 Ft								
57	WEATHERING		L	3618.00 SqFt								
57	WEATHERING		M	402.00 SqFt								

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT										
Branch:	AP E		Name:	EAST APRON		Use:	APRON		Area:	620,726 SqFt				
Section:	4245		of	16		From:	-		To:	-		Last Const.:	1/1/2003	
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Category:			Rank:	P	
Area:	7,200 SqFt		Length:	350 Ft		Width:	20 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2003		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Last Insp. Date:	4/12/2022		TotalSamples:	2		Surveyed:	1							
Conditions:	PCI: 71													
Inspection Comments:														
Sample Number:	200		Type:	R		Area:	3600.00 SqFt		PCI:	71				
Sample Comments:														
48	L & T CR		L	12.00		Ft								
52	RAVELING		L	216.00		SqFt								
57	WEATHERING		M	3384.00		SqFt								

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT					
Branch:	AP E	Name:	EAST APRON		Use:	APRON	Area:	620,726 SqFt		
Section:	4250	of 16	From:	-	To:	-	Last Const.:	1/1/2011		
Surface:	PCC	Family:	CA653-GA-AP-PCC		Zone:		Category:	Rank: P		
Area:	38,220 SqFt		Length:	190 Ft		Width:	200 Ft			
Slabs:	182	Slab Length:	14 Ft		Slab Width:	15 Ft		Joint Length:	4,858 Ft	
Shoulder:	Street Type:		Grade:	0		Lanes:	0			
Section Comments:										
Work Date:	1/1/2011		Work Type: New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	12		Surveyed:	2			
Conditions:	PCI: 94									
Inspection Comments:										
Sample Number:	300	Type:	R	Area:	15.00 Slabs		PCI:	95		
Sample Comments:										
73	SHRINKAGE CR		N	5.00 Slabs						
Sample Number:	501	Type:	R	Area:	15.00 Slabs		PCI:	93		
Sample Comments:										
73	SHRINKAGE CR		N	7.00 Slabs						



Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT						
Branch:	AP HELI		Name:	HELICOPTER APRON		Use:	APRON	Area:	397,538 SqFt		
Section:	4255 of 2		From:	-			To:	-		Last Const.:	1/1/2012
Surface:	AC		Family:	CA653-GA-AP-AC		Zone:			Category:	Rank: P	
Area:	32,798 SqFt		Length:	475 Ft		Width:	70 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2012		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	4/12/2022		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI: 86										
Inspection Comments:											
Sample Number:	96		Type:	R		Area:	7000.00 SqFt		PCI:	86	
Sample Comments:											
48	L & T CR		L	39.00 Ft							
57	WEATHERING		L	6650.00 SqFt							
57	WEATHERING		M	350.00 SqFt							

Network:	TIX		Name:		SPACE COAST REGIONAL AIRPORT					
Branch:	AP HELI		Name:		HELICOPTER APRON		Use:	APRON	Area:	397,538 SqFt
Section:	4260		of 2		From: -		To: -		Last Const.: 1/1/2012	
Surface:	PCC		Family: CA653-GA-AP-PCC		Zone:		Category:		Rank: P	
Area:	364,740 SqFt		Length:		744 Ft		Width:		510 Ft	
Slabs:	2,533		Slab Length:		12 Ft		Slab Width:		12 Ft	
Shoulder:			Street Type:		Grade: 0		Lanes:		0	
Section Comments:										
Work Date:	1/1/2012		Work Type: New Construction - Initial				Code: NU-IN		Is Major M&R: True	
Last Insp. Date:	4/12/2022		TotalSamples:		97		Surveyed: 10			
Conditions:	PCI: 95									
Inspection Comments:										
Sample Number:	146		Type:	R	Area:		21.00 Slabs		PCI: 98	
Sample Comments:										
65	JT SEAL DMG		L		21.00 Slabs					
Sample Number:	199		Type:	R	Area:		21.00 Slabs		PCI: 100	
Sample Comments:										
<No Distress>										
Sample Number:	244		Type:	R	Area:		28.00 Slabs		PCI: 99	
Sample Comments:										
66	SMALL PATCH		L		1.00 Slabs					
Sample Number:	346		Type:	R	Area:		28.00 Slabs		PCI: 84	
Sample Comments:										
67	LARGE PATCH		L		4.00 Slabs					
73	SHRINKAGE CR		N		18.00 Slabs					
74	JOINT SPALL		L		1.00 Slabs					
Sample Number:	447		Type:	R	Area:		28.00 Slabs		PCI: 94	
Sample Comments:										
73	SHRINKAGE CR		N		12.00 Slabs					
Sample Number:	494		Type:	R	Area:		28.00 Slabs		PCI: 98	
Sample Comments:										
65	JT SEAL DMG		L		28.00 Slabs					
Sample Number:	643		Type:	R	Area:		28.00 Slabs		PCI: 94	
Sample Comments:										
65	JT SEAL DMG		L		28.00 Slabs					
66	SMALL PATCH		L		1.00 Slabs					
74	JOINT SPALL		M		1.00 Slabs					
Sample Number:	646		Type:	R	Area:		28.00 Slabs		PCI: 91	
Sample Comments:										
65	JT SEAL DMG		L		28.00 Slabs					
73	SHRINKAGE CR		N		9.00 Slabs					
74	JOINT SPALL		L		1.00 Slabs					
75	CORNER SPALL		L		1.00 Slabs					
Sample Number:	795		Type:	R	Area:		28.00 Slabs		PCI: 100	
Sample Comments:										
<No Distress>										
Sample Number:	847		Type:	R	Area:		28.00 Slabs		PCI: 98	
Sample Comments:										
65	JT SEAL DMG		L		28.00 Slabs					

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	AP W		Name:	WEST APRON		Use:	APRON	Area:	400,935 SqFt
Section:	4305 of 2		From:	-		To:	-		Last Const.: 1/1/2014
Surface:	PCC	Family:	CA653-GA-AP-PCC		Zone:	Category:		Rank:	P
Area:	370,471 SqFt		Length:	1,600 Ft		Width:	500 Ft		
Slabs:	1,647	Slab Length:	15 Ft		Slab Width:	15 Ft		Joint Length:	104,567 Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/2014		Work Type: New Construction - Initial			Code:	NU-IN		Is Major M&R: True
Last Insp. Date:	4/12/2022		TotalSamples:	88		Surveyed:	9		
Conditions:	PCI: 97								
Inspection Comments:									
Sample Number:	151	Type:	R	Area:	20.00 Slabs		PCI:	98	
Sample Comments:									
65	JT SEAL DMG		L	20.00 Slabs					
Sample Number:	155	Type:	R	Area:	20.00 Slabs		PCI:	98	
Sample Comments:									
65	JT SEAL DMG		L	20.00 Slabs					
Sample Number:	203	Type:	R	Area:	20.00 Slabs		PCI:	97	
Sample Comments:									
73	SHRINKAGE CR		N	4.00 Slabs					
Sample Number:	208	Type:	R	Area:	16.00 Slabs		PCI:	100	
Sample Comments:									
<No Distress>									
Sample Number:	260	Type:	R	Area:	20.00 Slabs		PCI:	92	
Sample Comments:									
71	FAULTING		L	2.00 Slabs					
Sample Number:	263	Type:	R	Area:	20.00 Slabs		PCI:	97	
Sample Comments:									
65	JT SEAL DMG		L	20.00 Slabs					
73	SHRINKAGE CR		N	1.00 Slabs					
Sample Number:	411	Type:	R	Area:	20.00 Slabs		PCI:	100	
Sample Comments:									
<No Distress>									
Sample Number:	414	Type:	R	Area:	20.00 Slabs		PCI:	94	
Sample Comments:									
65	JT SEAL DMG		L	20.00 Slabs					
66	SMALL PATCH		L	3.00 Slabs					
73	SHRINKAGE CR		N	2.00 Slabs					
Sample Number:	512	Type:	R	Area:	20.00 Slabs		PCI:	99	
Sample Comments:									
73	SHRINKAGE CR		N	1.00 Slabs					

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	AP W	Name:	WEST APRON		Use:	APRON	Area:	400,935 SqFt			
Section:	4310	of 2	From:	-		To:	-		Last Const.:	1/1/2014	
Surface:	AAC	Family:	CA653-GA-AP-AAC-APC		Zone:	Category:		Rank:		P	
Area:	30,464 SqFt		Length:	68 Ft		Width:	400 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1943		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2004		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	1/1/2014		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	9		Surveyed:	1				
Conditions:	PCI: 71										
Inspection Comments:											
Sample Number:	215	Type:	R	Area:	3292.00 SqFt		PCI:	71			
Sample Comments:											
48	L & T CR		L	66.00 Ft							
48	L & T CR		M	50.00 Ft							
57	WEATHERING		L	2042.00 SqFt							
57	WEATHERING		M	1250.00 SqFt							

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	RW 18-36		Name:	RUNWAY 18-36		Use:	RUNWAY	Area:	1,097,850 SqFt
Section:	6105	of	6	From:	-	To:	-	Last Const.:	6/1/2002
Surface:	AAC	Family:	CA653-GA-RW-AAC-APC	Zone:		Category:		Rank:	P
Area:	500,000 SqFt	Length:	5,000 Ft	Width:	100 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1943	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1971	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	6/1/2002	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	4/12/2022	TotalSamples:	100	Surveyed:	20				
Conditions:	PCI: 58								
Inspection Comments:									
Sample Number:	302	Type:	R	Area:	5000.00 SqFt	PCI:	57		
Sample Comments:									
48	L & T CR	L	100.00 Ft						
48	L & T CR	M	250.00 Ft						
52	RAVELING	L	500.00 SqFt						
56	SWELLING	L	25.00 SqFt						
57	WEATHERING	M	4500.00 SqFt						
Sample Number:	308	Type:	R	Area:	5000.00 SqFt	PCI:	62		
Sample Comments:									
48	L & T CR	L	235.00 Ft						
48	L & T CR	M	200.00 Ft						
52	RAVELING	L	250.00 SqFt						
57	WEATHERING	M	4750.00 SqFt						
Sample Number:	311	Type:	R	Area:	5000.00 SqFt	PCI:	59		
Sample Comments:									
48	L & T CR	L	191.00 Ft						
48	L & T CR	M	250.00 Ft						
52	RAVELING	L	250.00 SqFt						
57	WEATHERING	M	4750.00 SqFt						
Sample Number:	317	Type:	R	Area:	5000.00 SqFt	PCI:	55		
Sample Comments:									
48	L & T CR	L	179.00 Ft						
48	L & T CR	M	300.00 Ft						
52	RAVELING	L	500.00 SqFt						
56	SWELLING	L	15.00 SqFt						
57	WEATHERING	M	4500.00 SqFt						
Sample Number:	323	Type:	R	Area:	5000.00 SqFt	PCI:	62		
Sample Comments:									
48	L & T CR	L	261.00 Ft						
48	L & T CR	M	200.00 Ft						
52	RAVELING	L	500.00 SqFt						
57	WEATHERING	M	4500.00 SqFt						
Sample Number:	326	Type:	R	Area:	5000.00 SqFt	PCI:	60		
Sample Comments:									
48	L & T CR	L	296.00 Ft						
48	L & T CR	M	200.00 Ft						
52	RAVELING	L	250.00 SqFt						
56	SWELLING	L	10.00 SqFt						
57	WEATHERING	M	4750.00 SqFt						



Sample Number: 329		Type:	R	Area:		5000.00 SqFt	PCI: 62
Sample Comments:							
48	L & T CR		L	232.00	Ft		
48	L & T CR		M	200.00	Ft		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 335		Type:	R	Area:		5000.00 SqFt	PCI: 61
Sample Comments:							
48	L & T CR		L	292.00	Ft		
48	L & T CR		M	200.00	Ft		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 341		Type:	R	Area:		5000.00 SqFt	PCI: 60
Sample Comments:							
48	L & T CR		L	295.00	Ft		
48	L & T CR		M	200.00	Ft		
52	RAVELING		L	250.00	SqFt		
56	SWELLING		L	10.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 347		Type:	R	Area:		5000.00 SqFt	PCI: 63
Sample Comments:							
48	L & T CR		L	325.00	Ft		
48	L & T CR		M	146.00	Ft		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 353		Type:	R	Area:		5000.00 SqFt	PCI: 65
Sample Comments:							
48	L & T CR		L	362.00	Ft		
48	L & T CR		M	50.00	Ft		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 359		Type:	R	Area:		5000.00 SqFt	PCI: 57
Sample Comments:							
48	L & T CR		L	223.00	Ft		
48	L & T CR		M	303.00	Ft		
52	RAVELING		L	500.00	SqFt		
57	WEATHERING		M	4500.00	SqFt		
Sample Number: 365		Type:	R	Area:		5000.00 SqFt	PCI: 55
Sample Comments:							
48	L & T CR		L	433.00	Ft		
48	L & T CR		M	250.00	Ft		
52	RAVELING		L	250.00	SqFt		
56	SWELLING		L	10.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 368		Type:	R	Area:		5000.00 SqFt	PCI: 54
Sample Comments:							
48	L & T CR		L	191.00	Ft		
48	L & T CR		M	348.00	Ft		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 371		Type:	R	Area:		5000.00 SqFt	PCI: 60
Sample Comments:							
48	L & T CR		L	156.00	Ft		
48	L & T CR		M	300.00	Ft		
52	RAVELING		L	5.00	SqFt		
56	SWELLING		L	4.00	SqFt		
57	WEATHERING		M	4995.00	SqFt		

Sample Number: 376		Type:	R	Area:		5000.00 SqFt	PCI: 57
Sample Comments:							
48	L & T CR		L	240.00	Ft		
48	L & T CR		M	300.00	Ft		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 380		Type:	R	Area:		5000.00 SqFt	PCI: 55
Sample Comments:							
48	L & T CR		L	248.00	Ft		
48	L & T CR		M	332.00	Ft		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 386		Type:	R	Area:		5000.00 SqFt	PCI: 50
Sample Comments:							
48	L & T CR		L	148.00	Ft		
48	L & T CR		M	336.00	Ft		
52	RAVELING		L	250.00	SqFt		
52	RAVELING		M	10.00	SqFt		
57	WEATHERING		M	4740.00	SqFt		
Sample Number: 393		Type:	R	Area:		5000.00 SqFt	PCI: 52
Sample Comments:							
48	L & T CR		L	186.00	Ft		
48	L & T CR		M	350.00	Ft		
52	RAVELING		L	250.00	SqFt		
56	SWELLING		L	25.00	SqFt		
57	WEATHERING		M	4750.00	SqFt		
Sample Number: 397		Type:	R	Area:		5000.00 SqFt	PCI: 49
Sample Comments:							
48	L & T CR		L	225.00	Ft		
48	L & T CR		M	350.00	Ft		
50	PATCHING		M	5.00	SqFt		
52	RAVELING		L	250.00	SqFt		
57	WEATHERING		M	4745.00	SqFt		

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	RW 18-36		Name:	RUNWAY 18-36		Use:	RUNWAY	Area:	1,097,850 SqFt
Section:	6110	of	6	From:	-	To:	-	Last Const.:	6/1/2002
Surface:	AAC	Family:	CA653-GA-RW-AAC-APC	Zone:		Category:		Rank:	P
Area:	250,000 SqFt	Length:	10,000 Ft	Width:	25 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1943	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1971	Work Type:	OVERLAY			Code:	IMPORTED	Is Major M&R:	True
Work Date:	6/1/2002	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	4/12/2022	TotalSamples:	50	Surveyed:	10				
Conditions:	PCI:	57							
Inspection Comments:									
Sample Number:	100	Type:	R	Area:	5000.00 SqFt	PCI:	60		
Sample Comments:									
48	L & T CR	L	279.00	Ft					
48	L & T CR	M	150.00	Ft					
52	RAVELING	L	500.00	SqFt					
56	SWELLING	L	6.00	SqFt					
57	WEATHERING	L	2000.00	SqFt					
57	WEATHERING	M	2500.00	SqFt					
Sample Number:	120	Type:	R	Area:	5000.00 SqFt	PCI:	57		
Sample Comments:									
48	L & T CR	L	354.00	Ft					
48	L & T CR	M	250.00	Ft					
52	RAVELING	L	250.00	SqFt					
57	WEATHERING	M	4750.00	SqFt					
Sample Number:	132	Type:	R	Area:	5000.00 SqFt	PCI:	55		
Sample Comments:									
48	L & T CR	L	278.00	Ft					
48	L & T CR	M	300.00	Ft					
52	RAVELING	L	250.00	SqFt					
56	SWELLING	L	25.00	SqFt					
57	WEATHERING	M	4750.00	SqFt					
Sample Number:	144	Type:	R	Area:	5000.00 SqFt	PCI:	68		
Sample Comments:									
48	L & T CR	L	311.00	Ft					
48	L & T CR	M	125.00	Ft					
57	WEATHERING	L	2500.00	SqFt					
57	WEATHERING	M	2500.00	SqFt					
Sample Number:	176	Type:	R	Area:	5000.00 SqFt	PCI:	57		
Sample Comments:									
48	L & T CR	L	342.00	Ft					
48	L & T CR	M	270.00	Ft					
56	SWELLING	L	5.00	SqFt					
57	WEATHERING	L	2500.00	SqFt					
57	WEATHERING	M	2500.00	SqFt					
Sample Number:	504	Type:	R	Area:	5000.00 SqFt	PCI:	56		
Sample Comments:									
48	L & T CR	L	319.00	Ft					
48	L & T CR	M	281.00	Ft					
56	SWELLING	L	24.00	SqFt					
57	WEATHERING	L	2500.00	SqFt					

57	WEATHERING	M	2500.00	SqFt		
Sample Number: 524		Type: R	Area: 5000.00 SqFt		PCI: 59	
Sample Comments:						
48	L & T CR	L	309.00	Ft		
48	L & T CR	M	175.00	Ft		
52	RAVELING	L	100.00	SqFt		
56	SWELLING	L	4.00	SqFt		
57	WEATHERING	L	2400.00	SqFt		
57	WEATHERING	M	2500.00	SqFt		
Sample Number: 548		Type: R	Area: 5000.00 SqFt		PCI: 53	
Sample Comments:						
48	L & T CR	L	164.00	Ft		
48	L & T CR	M	350.00	Ft		
52	RAVELING	L	250.00	SqFt		
56	SWELLING	L	10.00	SqFt		
57	WEATHERING	M	4750.00	SqFt		
Sample Number: 560		Type: R	Area: 5000.00 SqFt		PCI: 57	
Sample Comments:						
48	L & T CR	L	343.00	Ft		
48	L & T CR	M	232.00	Ft		
52	RAVELING	L	250.00	SqFt		
56	SWELLING	L	16.00	SqFt		
57	WEATHERING	M	4750.00	SqFt		
Sample Number: 592		Type: R	Area: 5000.00 SqFt		PCI: 52	
Sample Comments:						
48	L & T CR	L	221.00	Ft		
48	L & T CR	M	173.00	Ft		
50	PATCHING	L	98.00	SqFt		
56	SWELLING	L	34.00	SqFt		
56	SWELLING	M	5.00	SqFt		
57	WEATHERING	L	2444.00	SqFt		
57	WEATHERING	M	2451.00	SqFt		

Network:		TIX		Name:		SPACE COAST REGIONAL AIRPORT						
Branch:	RW 18-36		Name:		RUNWAY 18-36		Use:	RUNWAY	Area:	1,097,850 SqFt		
Section:	6125		of	6	From:	-		To:	-		Last Const.:	6/1/2002
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	100,000 SqFt		Length:	1,000 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1967		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	6/1/2002		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R: True		
Last Insp. Date:	4/12/2022		TotalSamples:	20		Surveyed:	5					
Conditions:	PCI: 55											
Inspection Comments:												
Sample Number:	402		Type:	R		Area:	5000.00 SqFt		PCI:	48		
Sample Comments:												
48	L & T CR		L	130.00 Ft								
48	L & T CR		M	400.00 Ft								
52	RAVELING		L	250.00 SqFt								
52	RAVELING		M	5.00 SqFt								
57	WEATHERING		M	4745.00 SqFt								
Sample Number:	406		Type:	R		Area:	5000.00 SqFt		PCI:	57		
Sample Comments:												
48	L & T CR		L	131.00 Ft								
48	L & T CR		M	300.00 Ft								
52	RAVELING		L	250.00 SqFt								
57	WEATHERING		M	4750.00 SqFt								
Sample Number:	410		Type:	R		Area:	5000.00 SqFt		PCI:	53		
Sample Comments:												
48	L & T CR		L	370.00 Ft								
48	L & T CR		M	298.00 Ft								
52	RAVELING		L	250.00 SqFt								
56	SWELLING		L	40.00 SqFt								
57	WEATHERING		M	4750.00 SqFt								
Sample Number:	413		Type:	R		Area:	5000.00 SqFt		PCI:	56		
Sample Comments:												
48	L & T CR		L	230.00 Ft								
48	L & T CR		M	274.00 Ft								
52	RAVELING		L	250.00 SqFt								
56	SWELLING		L	25.00 SqFt								
57	WEATHERING		M	4750.00 SqFt								
Sample Number:	417		Type:	R		Area:	5000.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		L	228.00 Ft								
48	L & T CR		M	200.00 Ft								
57	WEATHERING		L	2500.00 SqFt								
57	WEATHERING		M	2500.00 SqFt								



Network:		TIX		Name:		SPACE COAST REGIONAL AIRPORT								
Branch:	RW 18-36		Name:	RUNWAY 18-36		Use:	RUNWAY		Area:	1,097,850 SqFt				
Section:	6130		of	6		From:	-		To:	-		Last Const.:	6/1/2002	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	50,000 SqFt		Length:	2,000 Ft		Width:	25 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1967		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	6/1/2002		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True		
Last Insp. Date:	4/12/2022		TotalSamples:	10		Surveyed:	2							
Conditions:	PCI: 59													
Inspection Comments:														
Sample Number:	212		Type:	R		Area:	5000.00 SqFt		PCI:	52				
Sample Comments:														
48	L & T CR		L	311.00 Ft										
48	L & T CR		M	323.00 Ft										
56	SWELLING		L	74.00 SqFt										
57	WEATHERING		L	2500.00 SqFt										
57	WEATHERING		M	2500.00 SqFt										
Sample Number:	600		Type:	R		Area:	5000.00 SqFt		PCI:	67				
Sample Comments:														
48	L & T CR		L	332.00 Ft										
48	L & T CR		M	100.00 Ft										
57	WEATHERING		L	2500.00 SqFt										
57	WEATHERING		M	2500.00 SqFt										

Network:		TIX		Name:		SPACE COAST REGIONAL AIRPORT																	
Branch:		RW 18-36		Name:		RUNWAY 18-36		Use:		RUNWAY		Area:		1,097,850 SqFt									
Section:		6145		of 6		From:		-		To:		-		Last Const.: 6/1/2002									
Surface:		AAC		Family:		CA653-GA-RW-AAC-APC		Zone:		Category:		Rank:		P									
Area:		131,900 SqFt		Length:		1,319 Ft		Width:		100 Ft													
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft											
Shoulder:		Street Type:		Grade:		0		Lanes:		0													
Section Comments:																							
Work Date:				1/1/1971				Work Type:				New Construction - Initial				Code:		NU-IN		Is Major M&R:		True	
Work Date:				6/1/2002				Work Type:				Mill and Overlay				Code:		ML-OVL		Is Major M&R:		True	
Last Insp. Date:				4/12/2022				TotalSamples:				26				Surveyed:				5			
Conditions:				PCI: 60																			
Inspection Comments:																							
Sample Number:		421		Type:		R		Area:		5000.00 SqFt		PCI:		52									
Sample Comments:																							
48	L & T CR			L		265.00 Ft																	
48	L & T CR			M		300.00 Ft																	
52	RAVELING			L		250.00 SqFt																	
56	SWELLING			L		100.00 SqFt																	
57	WEATHERING			M		4750.00 SqFt																	
Sample Number:		429		Type:		R		Area:		5000.00 SqFt		PCI:		59									
Sample Comments:																							
48	L & T CR			L		150.00 Ft																	
48	L & T CR			M		250.00 Ft																	
52	RAVELING			L		250.00 SqFt																	
57	WEATHERING			M		4750.00 SqFt																	
Sample Number:		437		Type:		R		Area:		5000.00 SqFt		PCI:		65									
Sample Comments:																							
48	L & T CR			L		348.00 Ft																	
48	L & T CR			M		100.00 Ft																	
52	RAVELING			L		100.00 SqFt																	
57	WEATHERING			M		4900.00 SqFt																	
Sample Number:		440		Type:		R		Area:		5000.00 SqFt		PCI:		56									
Sample Comments:																							
48	L & T CR			L		222.00 Ft																	
48	L & T CR			M		250.00 Ft																	
52	RAVELING			L		250.00 SqFt																	
56	SWELLING			L		50.00 SqFt																	
57	WEATHERING			M		4750.00 SqFt																	
Sample Number:		445		Type:		R		Area:		6900.00 SqFt		PCI:		65									
Sample Comments:																							
48	L & T CR			L		368.00 Ft																	
48	L & T CR			M		75.00 Ft																	
50	PATCHING			H		33.00 SqFt																	
57	WEATHERING			M		6867.00 SqFt																	

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	RW 18-36		Name:	RUNWAY 18-36		Use:	RUNWAY		Area:	1,097,850 SqFt	
Section:	6150 of 6		From:	-		To:	-		Last Const.:	6/1/2002	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:			Category:	Rank: P	
Area:	65,950 SqFt		Length:	2,600 Ft		Width:	25 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1967		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	6/1/2002		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date: 4/12/2022											
Conditions:	PCI: 63		TotalSamples:	14		Surveyed: 3					
Inspection Comments:											
Sample Number:	220		Type:	R	Area:	5000.00 SqFt		PCI:	66		
Sample Comments:											
48	L & T CR		L	341.00 Ft							
48	L & T CR		M	100.00 Ft							
52	RAVELING		L	50.00 SqFt							
57	WEATHERING		M	4950.00 SqFt							
Sample Number:	222		Type:	R	Area:	3750.00 SqFt		PCI:	59		
Sample Comments:											
48	L & T CR		L	246.00 Ft							
48	L & T CR		M	200.00 Ft							
52	RAVELING		L	38.00 SqFt							
57	WEATHERING		L	712.00 SqFt							
57	WEATHERING		M	3000.00 SqFt							
Sample Number:	618		Type:	R	Area:	5000.00 SqFt		PCI:	63		
Sample Comments:											
48	L & T CR		L	315.00 Ft							
48	L & T CR		M	133.00 Ft							
52	RAVELING		L	150.00 SqFt							
57	WEATHERING		L	1100.00 SqFt							
57	WEATHERING		M	3750.00 SqFt							

Network:		TIX		Name:		SPACE COAST REGIONAL AIRPORT									
Branch:		RW 9-27		Name:		RUNWAY 9-27		Use:		RUNWAY		Area:		489,743 SqFt	
Section:		6205		of 3		From:		-		To:		-		Last Const.: 6/1/2002	
Surface:		AAC		Family:		CA653-GA-RW-AAC-APC		Zone:		Category:		Rank:		P	
Area:		67,743 SqFt		Length:		655 Ft		Width:		100 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date:		1/1/1943		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/1976		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/1998		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Work Date:		6/1/2002		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Last Insp. Date:		4/12/2022		TotalSamples:		14		Surveyed:		3					
Conditions:		PCI: 53													
Inspection Comments:															
Sample Number:		100		Type:		R		Area:		5000.00 SqFt		PCI:		48	
Sample Comments:															
48	L & T CR			L		181.00 Ft									
48	L & T CR			M		410.00 Ft									
52	RAVELING			L		749.00 SqFt									
52	RAVELING			M		5.00 SqFt									
57	WEATHERING			M		4246.00 SqFt									
Sample Number:		105		Type:		R		Area:		5000.00 SqFt		PCI:		56	
Sample Comments:															
48	L & T CR			L		343.00 Ft									
48	L & T CR			M		300.00 Ft									
52	RAVELING			L		250.00 SqFt									
57	WEATHERING			M		4750.00 SqFt									
Sample Number:		114		Type:		R		Area:		5000.00 SqFt		PCI:		54	
Sample Comments:															
48	L & T CR			L		244.00 Ft									
48	L & T CR			M		273.00 Ft									
50	PATCHING			L		486.00 SqFt									
52	RAVELING			L		90.00 SqFt									
57	WEATHERING			M		4424.00 SqFt									

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	RW 9-27		Name:	RUNWAY 9-27		Use:	RUNWAY	Area:	489,743 SqFt
Section:	6210 of 3		From:	-			To:	-	
Surface:	AAC		Family:	CA653-GA-RW-AAC-APC		Zone:	Category:		Rank: P
Area:	320,000 SqFt		Length:	3,200 Ft		Width:	100 Ft		
Slabs:	128		Slab Length:	50 Ft		Slab Width:	50 Ft		Joint Length: 9,500 Ft
Shoulder:			Street Type:			Grade:	0		Lanes: 0
Section Comments:									
Work Date:	1/1/1943		Work Type:	New Construction - AC			Code:	NC-AC	
Work Date:	1/1/1976		Work Type:	Overlay - AC Structural			Code:	OL-AS	
Work Date:	1/1/1998		Work Type:	Overlay - AC Structural			Code:	OL-AS	
Work Date:	5/1/2022		Work Type:	Mill and Overlay			Code:	ML-OVL	
Last Insp. Date:	3/4/2019		TotalSamples:	64		Surveyed:	13		
Conditions:	PCI: 53		NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	136		Type:	R		Area:	5000.00 SqFt		PCI: 49
Sample Comments:									
43	BLOCK CR		L	1850.00 SqFt					
48	L & T CR		L	286.00 Ft					
52	RAVELING		L	150.00 SqFt					
56	SWELLING		L	215.00 SqFt					
57	WEATHERING		L	2400.00 SqFt					
57	WEATHERING		M	2450.00 SqFt					
Sample Number:	141		Type:	R		Area:	5000.00 SqFt		PCI: 47
Sample Comments:									
43	BLOCK CR		L	2500.00 SqFt					
48	L & T CR		L	105.00 Ft					
52	RAVELING		L	200.00 SqFt					
56	SWELLING		L	250.00 SqFt					
57	WEATHERING		L	2400.00 SqFt					
57	WEATHERING		M	2400.00 SqFt					
Sample Number:	148		Type:	R		Area:	5000.00 SqFt		PCI: 44
Sample Comments:									
43	BLOCK CR		L	2000.00 SqFt					
48	L & T CR		L	150.00 Ft					
48	L & T CR		M	15.00 Ft					
52	RAVELING		L	200.00 SqFt					
56	SWELLING		L	260.00 SqFt					
57	WEATHERING		L	2400.00 SqFt					
57	WEATHERING		M	2400.00 SqFt					
Sample Number:	155		Type:	R		Area:	5000.00 SqFt		PCI: 51
Sample Comments:									
48	L & T CR		L	549.00 Ft					
52	RAVELING		L	150.00 SqFt					
56	SWELLING		L	150.00 SqFt					
56	SWELLING		M	40.00 SqFt					
57	WEATHERING		L	2400.00 SqFt					
57	WEATHERING		M	2450.00 SqFt					
Sample Number:	162		Type:	R		Area:	5000.00 SqFt		PCI: 43
Sample Comments:									
43	BLOCK CR		L	700.00 SqFt					
48	L & T CR		L	400.00 Ft					
48	L & T CR		M	50.00 Ft					
52	RAVELING		L	250.00 SqFt					



56	SWELLING	L	850.00	SqFt
56	SWELLING	M	10.00	SqFt
57	WEATHERING	L	2350.00	SqFt
57	WEATHERING	M	2400.00	SqFt
<b>Sample Number:</b> 165 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 47				
<b>Sample Comments:</b>				
43	BLOCK CR	L	1250.00	SqFt
48	L & T CR	L	316.00	Ft
48	L & T CR	M	100.00	Ft
52	RAVELING	L	500.00	SqFt
56	SWELLING	L	500.00	SqFt
57	WEATHERING	L	2200.00	SqFt
57	WEATHERING	M	2300.00	SqFt
<b>Sample Number:</b> 169 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 54				
<b>Sample Comments:</b>				
48	L & T CR	L	603.00	Ft
52	RAVELING	L	200.00	SqFt
56	SWELLING	L	400.00	SqFt
57	WEATHERING	L	2400.00	SqFt
57	WEATHERING	M	2400.00	SqFt
<b>Sample Number:</b> 176 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 61				
<b>Sample Comments:</b>				
48	L & T CR	L	226.00	Ft
52	RAVELING	L	450.00	SqFt
56	SWELLING	L	650.00	SqFt
57	WEATHERING	L	2250.00	SqFt
57	WEATHERING	M	2300.00	SqFt
<b>Sample Number:</b> 179 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 59				
<b>Sample Comments:</b>				
48	L & T CR	L	278.00	Ft
48	L & T CR	M	50.00	Ft
52	RAVELING	L	300.00	SqFt
56	SWELLING	L	350.00	SqFt
57	WEATHERING	L	2350.00	SqFt
57	WEATHERING	M	2350.00	SqFt
<b>Sample Number:</b> 183 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 55				
<b>Sample Comments:</b>				
48	L & T CR	L	393.00	Ft
48	L & T CR	M	50.00	Ft
52	RAVELING	L	200.00	SqFt
56	SWELLING	L	600.00	SqFt
57	WEATHERING	L	2400.00	SqFt
57	WEATHERING	M	2400.00	SqFt
<b>Sample Number:</b> 186 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 51				
<b>Sample Comments:</b>				
48	L & T CR	L	359.00	Ft
48	L & T CR	M	50.00	Ft
52	RAVELING	L	250.00	SqFt
56	SWELLING	L	350.00	SqFt
56	SWELLING	M	50.00	SqFt
57	WEATHERING	L	2350.00	SqFt
57	WEATHERING	M	2400.00	SqFt
<b>Sample Number:</b> 190 <b>Type:</b> R <b>Area:</b> 5000.00 SqFt <b>PCI:</b> 64				
<b>Sample Comments:</b>				
48	L & T CR	L	301.00	Ft
52	RAVELING	L	1750.00	SqFt
56	SWELLING	L	275.00	SqFt
57	WEATHERING	L	1625.00	SqFt
57	WEATHERING	M	1625.00	SqFt

Sample Number: 194		Type:	R	Area:	5000.00 SqFt	PCI:	59
Sample Comments:							
48	L & T CR		L	391.00	Ft		
52	RAVELING		L	2500.00	SqFt		
56	SWELLING		L	600.00	SqFt		
57	WEATHERING		L	2250.00	SqFt		
57	WEATHERING		M	250.00	SqFt		

Network:		TIX		Name:		SPACE COAST REGIONAL AIRPORT									
Branch:		RW 9-27		Name:		RUNWAY 9-27		Use:		RUNWAY		Area:		489,743 SqFt	
Section:		6215		of 3		From:		-		To:		-		Last Const.: 5/1/2022	
Surface:		AAC		Family:		CA653-GA-RW-AAC-APC		Zone:		Category:		Rank:		P	
Area:		102,000 SqFt		Length:		1,020 Ft		Width:		100 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date:		1/1/1943		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/1976		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True	
Work Date:		1/1/1998		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Work Date:		6/1/2002		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Work Date:		5/1/2022		Work Type:		Mill and Overlay		Code:		ML-OVL		Is Major M&R:		True	
Last Insp. Date:		3/4/2019		TotalSamples:		34		Surveyed:		7					
Conditions:		PCI: 63		NOTE: *** Pre-Construction PCI ***											
Inspection Comments:															
Sample Number:		100		Type:		R		Area:		5000.00 SqFt		PCI:		62	
Sample Comments:															
48		L & T CR		L		528.00 Ft									
52		RAVELING		L		500.00 SqFt									
57		WEATHERING		L		2000.00 SqFt									
57		WEATHERING		M		2500.00 SqFt									
Sample Number:		105		Type:		R		Area:		5000.00 SqFt		PCI:		64	
Sample Comments:															
48		L & T CR		L		434.00 Ft									
52		RAVELING		L		1600.00 SqFt									
57		WEATHERING		L		2400.00 SqFt									
57		WEATHERING		M		1000.00 SqFt									
Sample Number:		114		Type:		R		Area:		5000.00 SqFt		PCI:		58	
Sample Comments:															
48		L & T CR		L		289.00 Ft									
48		L & T CR		M		200.00 Ft									
52		RAVELING		L		100.00 SqFt									
57		WEATHERING		L		3375.00 SqFt									
57		WEATHERING		M		1125.00 SqFt									
Sample Number:		117		Type:		R		Area:		5000.00 SqFt		PCI:		60	
Sample Comments:															
48		L & T CR		L		558.00 Ft									
52		RAVELING		L		100.00 SqFt									
56		SWELLING		L		10.00 SqFt									
57		WEATHERING		L		2250.00 SqFt									
57		WEATHERING		M		2250.00 SqFt									
Sample Number:		122		Type:		R		Area:		5000.00 SqFt		PCI:		66	
Sample Comments:															
48		L & T CR		L		396.00 Ft									
52		RAVELING		L		100.00 SqFt									
57		WEATHERING		L		2250.00 SqFt									
57		WEATHERING		M		2250.00 SqFt									
Sample Number:		130		Type:		R		Area:		5000.00 SqFt		PCI:		66	
Sample Comments:															
48		L & T CR		L		449.00 Ft									
52		RAVELING		L		50.00 SqFt									

57	WEATHERING	L	2500.00	SqFt
57	WEATHERING	M	2450.00	SqFt

Sample Number:	134	Type:	R	Area:	5000.00	SqFt	PCI:	64
----------------	-----	-------	---	-------	---------	------	------	----

Sample Comments:

48	L & T CR	L	423.00	Ft
52	RAVELING	L	100.00	SqFt
56	SWELLING	L	5.00	SqFt
57	WEATHERING	L	2450.00	SqFt
57	WEATHERING	M	2450.00	SqFt

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT									
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	304,658 SqFt				
Section:	105		of	5		From:	-		To:	-		Last Const.:	6/1/2002	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	114,651 SqFt		Length:	2,200 Ft		Width:	50 Ft							
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft					
Shoulder:	Street Type:				Grade:	0		Lanes:	0					
Section Comments:														
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True			
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True			
Work Date:	6/1/2002		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True			
Last Insp. Date:	4/12/2022		TotalSamples:	22		Surveyed:	4							
Conditions:	PCI: 59													
Inspection Comments:														
Sample Number:	100		Type:	R		Area:	5432.00 SqFt		PCI:	62				
Sample Comments:														
48	L & T CR		L	207.00 Ft										
48	L & T CR		M	307.00 Ft										
56	SWELLING		L	5.00 SqFt										
57	WEATHERING		M	5432.00 SqFt										
Sample Number:	108		Type:	R		Area:	5000.00 SqFt		PCI:	56				
Sample Comments:														
48	L & T CR		L	300.00 Ft										
48	L & T CR		M	335.00 Ft										
56	SWELLING		L	75.00 SqFt										
57	WEATHERING		M	5000.00 SqFt										
Sample Number:	113		Type:	R		Area:	5000.00 SqFt		PCI:	59				
Sample Comments:														
48	L & T CR		L	401.00 Ft										
48	L & T CR		M	150.00 Ft										
52	RAVELING		L	250.00 SqFt										
56	SWELLING		L	32.00 SqFt										
57	WEATHERING		M	4750.00 SqFt										
Sample Number:	118		Type:	R		Area:	5000.00 SqFt		PCI:	59				
Sample Comments:														
48	L & T CR		L	258.00 Ft										
48	L & T CR		M	275.00 Ft										
56	SWELLING		L	79.00 SqFt										
57	WEATHERING		M	5000.00 SqFt										



Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT								
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	304,658 SqFt		
Section:	110 of 5		From:	-		To:	-		Last Const.:	6/1/2002		
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	70,000 SqFt		Length:	1,400 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1943		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1992		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Work Date:	6/1/2002		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	14		Surveyed:	3					
Conditions:	PCI: 62											
Inspection Comments:												
Sample Number:	121		Type:	R		Area:	5000.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		L	283.00 Ft								
48	L & T CR		M	250.00 Ft								
57	WEATHERING		M	5000.00 SqFt								
Sample Number:	127		Type:	R		Area:	5000.00 SqFt		PCI:	62		
Sample Comments:												
48	L & T CR		L	268.00 Ft								
48	L & T CR		M	200.00 Ft								
52	RAVELING		L	50.00 SqFt								
56	SWELLING		L	10.00 SqFt								
57	WEATHERING		M	4950.00 SqFt								
Sample Number:	131		Type:	R		Area:	5000.00 SqFt		PCI:	61		
Sample Comments:												
48	L & T CR		L	293.00 Ft								
48	L & T CR		M	273.00 Ft								
57	WEATHERING		M	5000.00 SqFt								

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	304,658 SqFt		
Section:	112		of	5	From:	-		To:	-		Last Const.:	6/1/2002
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	30,000 SqFt		Length:	600 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1943		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	6/1/2002		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	6		Surveyed:	2					
Conditions:	PCI:	59										
Inspection Comments:												
Sample Number:	134		Type:	R		Area:	5000.00 SqFt		PCI:	63		
Sample Comments:												
48	L & T CR		L	283.00 Ft								
48	L & T CR		M	200.00 Ft								
52	RAVELING		L	50.00 SqFt								
57	WEATHERING		M	4950.00 SqFt								
Sample Number:	137		Type:	R		Area:	5000.00 SqFt		PCI:	56		
Sample Comments:												
48	L & T CR		L	236.00 Ft								
48	L & T CR		M	296.00 Ft								
52	RAVELING		L	300.00 SqFt								
56	SWELLING		L	8.00 SqFt								
57	WEATHERING		M	4700.00 SqFt								

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	304,658 SqFt	
Section:	115 of 5		From:	-		To:	-		Last Const.:	6/1/2002	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	50,000 SqFt		Length:	1,000 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1967		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	6/1/2002		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	10		Surveyed:	2				
Conditions:	PCI: 57										
Inspection Comments:											
Sample Number:	143		Type:	R		Area:	5000.00 SqFt		PCI:	61	
Sample Comments:											
48	L & T CR		L	267.00 Ft							
48	L & T CR		M	250.00 Ft							
52	RAVELING		L	50.00 SqFt							
57	WEATHERING		M	4950.00 SqFt							
Sample Number:	148		Type:	R		Area:	5000.00 SqFt		PCI:	53	
Sample Comments:											
48	L & T CR		L	238.00 Ft							
48	L & T CR		M	337.00 Ft							
52	RAVELING		L	250.00 SqFt							
56	SWELLING		L	28.00 SqFt							
57	WEATHERING		M	4750.00 SqFt							

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	304,658 SqFt		
Section:	120		of	5	From:	-		To:	-		Last Const.:	6/1/2002
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	40,007 SqFt		Length:	800 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1967		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	6/1/2002		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	8		Surveyed:	2					
Conditions:	PCI:	65										
Inspection Comments:												
Sample Number:	151		Type:	R		Area:	5000.00 SqFt		PCI:	61		
Sample Comments:												
48	L & T CR		L	161.00 Ft								
48	L & T CR		M	287.00 Ft								
56	SWELLING		L	12.00 SqFt								
57	WEATHERING		M	5000.00 SqFt								
Sample Number:	157		Type:	R		Area:	5007.00 SqFt		PCI:	68		
Sample Comments:												
48	L & T CR		L	251.00 Ft								
48	L & T CR		M	150.00 Ft								
57	WEATHERING		M	5007.00 SqFt								

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT									
Branch:	TW A1		Name:	TAXIWAY A1		Use:	TAXIWAY		Area:	50,631 SqFt				
Section:	130		of	1		From:	-		To:	-		Last Const.:	6/1/2002	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	50,631 SqFt		Length:	500 Ft		Width:	65 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1967		Work Type:	BUILT		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	1/1/1971		Work Type:	OVERLAY		Code:	IMPORTED		Is Major M&R:	True				
Work Date:	6/1/2002		Work Type:	Mill and Overlay		Code:	ML-OVL		Is Major M&R:	True				
Last Insp. Date:	4/12/2022		TotalSamples:	9		Surveyed:	1							
Conditions:	PCI: 49													
Inspection Comments:														
Sample Number:	162		Type:	R		Area:	6463.00 SqFt		PCI:	49				
Sample Comments:														
48	L & T CR		L	310.00 Ft										
48	L & T CR		M	481.00 Ft										
50	PATCHING		L	364.00 SqFt										
56	SWELLING		L	113.00 SqFt										
57	WEATHERING		M	6099.00 SqFt										



Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW A2		Name:	TAXIWAY A2		Use:	TAXIWAY		Area:	35,137 SqFt	
Section:	125 of 1		From:	-		To:	-		Last Const.:	6/1/2002	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	35,137 SqFt		Length:	600 Ft		Width:	500 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1971		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	6/1/2002		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	7		Surveyed:	2				
Conditions:	PCI: 61										
Inspection Comments:											
Sample Number:	300		Type:	R		Area:	6780.00 SqFt		PCI:	62	
Sample Comments:											
48	L & T CR		L	148.00 Ft							
48	L & T CR		M	300.00 Ft							
52	RAVELING		L	68.00 SqFt							
56	SWELLING		L	25.00 SqFt							
57	WEATHERING		M	6712.00 SqFt							
Sample Number:	303		Type:	R		Area:	5054.00 SqFt		PCI:	61	
Sample Comments:											
48	L & T CR		L	332.00 Ft							
48	L & T CR		M	200.00 Ft							
56	SWELLING		L	50.00 SqFt							
57	WEATHERING		M	5054.00 SqFt							

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY		Area:	257,540 SqFt		
Section:	205		of	3	From:	-		To:	-		Last Const.:	6/1/2002
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	22,146 SqFt		Length:	400 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1943		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1976		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	6/1/2002		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 53											
Inspection Comments:												
Sample Number:	502		Type:	R		Area:	5000.00 SqFt		PCI:	53		
Sample Comments:												
48	L & T CR		L	404.00 Ft								
48	L & T CR		M	350.00 Ft								
52	RAVELING		L	100.00 SqFt								
57	WEATHERING		M	4900.00 SqFt								

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	257,540 SqFt
Section:	210	of 3	From:	-			To:	-	Last Const.: 1/1/2013
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC		Zone:	Category:		Rank:	P
Area:	223,574 SqFt		Length:	4,450 Ft		Width:	50 Ft		
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED	
Work Date:	1/1/1976		Work Type: OVERLAY				Code:	IMPORTED	
Work Date:	1/1/2013		Work Type: Mill and Overlay				Code:	ML-OVL	
Last Insp. Date:	4/12/2022		TotalSamples:	45		Surveyed:	6		
Conditions:	PCI: 84								
Inspection Comments:									
Sample Number:	506	Type:	R	Area:	5001.00 SqFt		PCI:	92	
Sample Comments:									
57	WEATHERING	L	4901.00 SqFt						
57	WEATHERING	M	100.00 SqFt						
Sample Number:	515	Type:	R	Area:	5000.00 SqFt		PCI:	90	
Sample Comments:									
48	L & T CR	L	16.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	525	Type:	R	Area:	5000.00 SqFt		PCI:	88	
Sample Comments:									
48	L & T CR	L	5.00 Ft						
57	WEATHERING	L	4750.00 SqFt						
57	WEATHERING	M	250.00 SqFt						
Sample Number:	533	Type:	R	Area:	5000.00 SqFt		PCI:	78	
Sample Comments:									
48	L & T CR	L	212.00 Ft						
56	SWELLING	L	15.00 SqFt						
57	WEATHERING	L	4900.00 SqFt						
57	WEATHERING	M	100.00 SqFt						
Sample Number:	541	Type:	R	Area:	5000.00 SqFt		PCI:	84	
Sample Comments:									
48	L & T CR	L	88.00 Ft						
56	SWELLING	L	25.00 SqFt						
57	WEATHERING	L	4900.00 SqFt						
57	WEATHERING	M	100.00 SqFt						
Sample Number:	545	Type:	R	Area:	5000.00 SqFt		PCI:	72	
Sample Comments:									
48	L & T CR	L	289.00 Ft						
56	SWELLING	L	28.00 SqFt						
57	WEATHERING	L	4500.00 SqFt						
57	WEATHERING	M	500.00 SqFt						

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	257,540 SqFt
Section:	215	of	3	From:	-	To:	-	Last Const.:	5/1/2022
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	11,820 SqFt		Length:	214 Ft		Width:	50 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:			Grade:		0	Lanes:		0
Section Comments:									
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/1976		Work Type: OVERLAY				Code:	IMPORTED	Is Major M&R: True
Work Date:	1/1/2013		Work Type: Mill and Overlay				Code:	ML-OVL	Is Major M&R: True
Work Date:	5/1/2022		Work Type: Mill and Overlay				Code:	ML-OVL	Is Major M&R: True
Last Insp. Date:	3/4/2019		TotalSamples:	47		Surveyed:	7		
Conditions:	PCI:	89	NOTE: *** Pre-Construction PCI ***						
Inspection Comments:									
Sample Number:	500	Type:	R	Area:	5537.00 SqFt		PCI:	92	
Sample Comments:									
48	L & T CR	L	3.00 Ft						
57	WEATHERING	L	5537.00 SqFt						
Sample Number:	506	Type:	R	Area:	5001.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING	L	5001.00 SqFt						
Sample Number:	515	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	525	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	533	Type:	R	Area:	5000.00 SqFt		PCI:	84	
Sample Comments:									
48	L & T CR	L	143.00 Ft						
56	SWELLING	L	15.00 SqFt						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	541	Type:	R	Area:	5000.00 SqFt		PCI:	85	
Sample Comments:									
48	L & T CR	L	49.00 Ft						
52	RAVELING	L	50.00 SqFt						
56	SWELLING	L	25.00 SqFt						
57	WEATHERING	L	4950.00 SqFt						
Sample Number:	545	Type:	R	Area:	5000.00 SqFt		PCI:	80	
Sample Comments:									
48	L & T CR	L	228.00 Ft						
56	SWELLING	L	5.00 SqFt						
57	WEATHERING	L	5000.00 SqFt						

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT									
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	200,240 SqFt					
Section:	305		of	5		From:	-		To:	-		Last Const.:	1/1/2004	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	46,879 SqFt		Length:	700 Ft		Width:	65 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1943		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1971		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/2004		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True		
Last Insp. Date:	4/12/2022		TotalSamples:	9		Surveyed:	2							
Conditions:	PCI: 57													
Inspection Comments:														
Sample Number:	701		Type:	R		Area:	5000.00 SqFt		PCI:	60				
Sample Comments:														
48	L & T CR		L	145.00 Ft										
48	L & T CR		M	200.00 Ft										
56	SWELLING		L	31.00 SqFt										
57	WEATHERING		L	2500.00 SqFt										
57	WEATHERING		M	2500.00 SqFt										
Sample Number:	704		Type:	R		Area:	6717.00 SqFt		PCI:	55				
Sample Comments:														
48	L & T CR		L	356.00 Ft										
48	L & T CR		M	350.00 Ft										
50	PATCHING		L	12.00 SqFt										
56	SWELLING		L	50.00 SqFt										
57	WEATHERING		L	3353.00 SqFt										
57	WEATHERING		M	3352.00 SqFt										



Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT					
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	200,240 SqFt	
Section:	310 of 5		From:	-		To:	-		Last Const.:	1/1/1986
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P
Area:	116,660 SqFt		Length:	2,300 Ft		Width:	50 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft
Shoulder:			Street Type:			Grade:	0		Lanes:	0
Section Comments:										
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1986		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Last Insp. Date:	4/12/2022		TotalSamples:	24		Surveyed:	4			
Conditions:	PCI: 60									
Inspection Comments:										
Sample Number:	701		Type:	R	Area:	5263.00 SqFt		PCI:	68	
Sample Comments:										
48	L & T CR		M	200.00 Ft						
52	RAVELING		L	1053.00 SqFt						
57	WEATHERING		M	4210.00 SqFt						
Sample Number:	707		Type:	R	Area:	4672.00 SqFt		PCI:	55	
Sample Comments:										
48	L & T CR		L	342.00 Ft						
48	L & T CR		M	250.00 Ft						
52	RAVELING		L	4672.00 SqFt						
Sample Number:	714		Type:	R	Area:	5000.00 SqFt		PCI:	65	
Sample Comments:										
48	L & T CR		L	311.00 Ft						
48	L & T CR		M	136.00 Ft						
52	RAVELING		L	1250.00 SqFt						
57	WEATHERING		M	3750.00 SqFt						
Sample Number:	719		Type:	R	Area:	5000.00 SqFt		PCI:	51	
Sample Comments:										
48	L & T CR		L	93.00 Ft						
48	L & T CR		M	488.00 Ft						
52	RAVELING		L	2500.00 SqFt						
57	WEATHERING		M	2500.00 SqFt						

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY		Area:	200,240 SqFt		
Section:	315 of 5		From:	-			To:	-		Last Const.:	1/1/2013	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:				Category:	Rank: P	
Area:	15,628 SqFt		Length:	290 Ft		Width:	50 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft			Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0			Lanes:	0		
Section Comments:												
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1976		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/2013		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True	
Last Insp. Date:	4/12/2022		TotalSamples:	3		Surveyed:	1					
Conditions:	PCI: 87											
Inspection Comments:												
Sample Number:	723		Type:	R		Area:	5000.00 SqFt		PCI:	87		
Sample Comments:												
48	L & T CR		L	35.00 Ft								
57	WEATHERING		L	4900.00 SqFt								
57	WEATHERING		M	100.00 SqFt								

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT					
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	200,240 SqFt	
Section:	320 of 5		From:	-		To:	-		Last Const.: 6/1/2002	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:	Category:		Rank: P	
Area:	3,845 SqFt		Length:	100 Ft		Width:	38 Ft			
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length: Ft	
Shoulder:			Street Type:			Grade:	0		Lanes: 0	
Section Comments:										
Work Date:	1/1/1971		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True
Work Date:	6/1/2002		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R: True
Last Insp. Date:	4/12/2022		TotalSamples:	1		Surveyed: 1				
Conditions:	PCI: 55									
Inspection Comments:										
Sample Number:	115		Type:	R		Area:	3845.00 SqFt		PCI: 55	
Sample Comments:										
48	L & T CR		L	137.00 Ft						
48	L & T CR		M	124.00 Ft						
50	PATCHING		L	1536.00 SqFt						
56	SWELLING		L	42.00 SqFt						
57	WEATHERING		M	2309.00 SqFt						

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT										
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY		Area:	200,240 SqFt				
Section:	325		of	5		From:	-		To:	-		Last Const.:	5/1/2022	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	17,228 SqFt		Length:	295 Ft		Width:	50 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft				
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:		True		
Work Date:	1/1/1976		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:		True		
Work Date:	1/1/2013		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:		True		
Work Date:	5/1/2022		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:		True		
Last Insp. Date:	3/4/2019		TotalSamples:	7		Surveyed:	2							
Conditions:	PCI: 88		NOTE: *** Pre-Construction PCI ***											
Inspection Comments:														
Sample Number:	723		Type:	R		Area:	5000.00 SqFt		PCI:	90				
Sample Comments:														
48	L & T CR		L	23.00 Ft										
57	WEATHERING		L	5000.00 SqFt										
Sample Number:	726		Type:	R		Area:	5007.00 SqFt		PCI:	86				
Sample Comments:														
48	L & T CR		L	96.00 Ft										
56	SWELLING		L	10.00 SqFt										
57	WEATHERING		L	5007.00 SqFt										

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT						
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY		Area:	107,711 SqFt	
Section:	405 of 2		From:	-			To:	-		Last Const.:	1/1/2000
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	33,961 SqFt		Length:	550 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True	
Work Date:	1/1/2000		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R: True	
Last Insp. Date:	4/12/2022		TotalSamples:	7		Surveyed:		1			
Conditions:	PCI: 65										
Inspection Comments:											
Sample Number:	402		Type:	R		Area:	5000.00 SqFt		PCI:	65	
Sample Comments:											
48	L & T CR		L	149.00 Ft							
48	L & T CR		M	100.00 Ft							
52	RAVELING		L	250.00 SqFt							
57	WEATHERING		M	4750.00 SqFt							

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY		Area:	107,711 SqFt		
Section:	410		of	2	From:	-		To:	-		Last Const.:	1/1/2000
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	73,750 SqFt		Length:	1,450 Ft		Width:	50 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1985		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2000		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	4/12/2022		TotalSamples:	15		Surveyed:	3					
Conditions:	PCI: 65											
Inspection Comments:												
Sample Number:	407		Type:	R		Area:	3750.00 SqFt		PCI:	66		
Sample Comments:												
48	L & T CR		L	56.00 Ft								
48	L & T CR		M	105.00 Ft								
52	RAVELING		L	188.00 SqFt								
57	WEATHERING		M	3562.00 SqFt								
Sample Number:	412		Type:	R		Area:	5000.00 SqFt		PCI:	65		
Sample Comments:												
48	L & T CR		L	61.00 Ft								
48	L & T CR		M	182.00 Ft								
52	RAVELING		L	250.00 SqFt								
57	WEATHERING		M	4750.00 SqFt								
Sample Number:	415		Type:	R		Area:	5000.00 SqFt		PCI:	65		
Sample Comments:												
48	L & T CR		L	139.00 Ft								
48	L & T CR		M	139.00 Ft								
52	RAVELING		L	250.00 SqFt								
57	WEATHERING		M	4750.00 SqFt								



Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	154,058 SqFt
Section:	505	of	4	From:	-	To:	-	Last Const.:	1/1/1998
Surface:	AAC	Family:	CA653-GA-TW-AAC-APC	Zone:		Category:		Rank:	P
Area:	32,371 SqFt	Length:	600 Ft	Width:	50 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/1943	Work Type:	BUILT			Code:	IMPORTED	Is Major M&R:	True
Work Date:	1/1/1998	Work Type:	Mill and Overlay			Code:	ML-OVL	Is Major M&R:	True
Last Insp. Date:	4/12/2022	TotalSamples:	6	Surveyed:	2				
Conditions:	PCI:	72							
Inspection Comments:									
Sample Number:	601	Type:	R	Area:	5000.00 SqFt	PCI:	69		
Sample Comments:									
48	L & T CR	L	244.00 Ft						
48	L & T CR	M	144.00 Ft						
57	WEATHERING	M	5000.00 SqFt						
Sample Number:	603	Type:	R	Area:	5000.00 SqFt	PCI:	75		
Sample Comments:									
48	L & T CR	L	311.00 Ft						
57	WEATHERING	M	5000.00 SqFt						

Network:	TIX		Name:	SPACE COAST REGIONAL AIRPORT							
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY		Area:	154,058 SqFt	
Section:	515 of 4		From:	-		To:	-		Last Const.:	1/1/2003	
Surface:	AAC		Family:	CA653-GA-TW-AAC-APC		Zone:			Category:	Rank: P	
Area:	44,841 SqFt		Length:	705 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1943		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2003		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date: 4/12/2022											
Conditions:	PCI: 64		TotalSamples:	8		Surveyed:		2			
Inspection Comments:											
Sample Number:	599		Type:	R		Area:	5825.00 SqFt		PCI:	56	
Sample Comments:											
45	DEPRESSION		L	30.00 SqFt							
48	L & T CR		L	86.00 Ft							
48	L & T CR		M	50.00 Ft							
50	PATCHING		L	100.00 SqFt							
52	RAVELING		L	114.00 SqFt							
56	SWELLING		L	10.00 SqFt							
57	WEATHERING		M	5611.00 SqFt							
Sample Number:	604		Type:	R		Area:	5328.00 SqFt		PCI:	72	
Sample Comments:											
48	L & T CR		L	5.00 Ft							
52	RAVELING		L	266.00 SqFt							
57	WEATHERING		M	5062.00 SqFt							

Network:	TIX			Name:	SPACE COAST REGIONAL AIRPORT				
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	154,058 SqFt
Section:	525	of 4	From:	-			To:	-	Last Const.: 1/1/2014
Surface:	AC	Family:	CA653-GA-TW-AC		Zone:	Category:		Rank: P	
Area:	8,165 SqFt		Length:	100 Ft		Width:	85 Ft		
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0
Section Comments:									
Work Date:	1/1/2014		Work Type: New Construction - Initial				Code:	NU-IN Is Major M&R: True	
Last Insp. Date:	4/12/2022		TotalSamples:	2		Surveyed: 1			
Conditions:	PCI: 92								
Inspection Comments:									
Sample Number:	608	Type:	R	Area:	3666.00 SqFt		PCI: 92		
Sample Comments:									
57	WEATHERING		L	3593.00 SqFt					
57	WEATHERING		M	73.00 SqFt					



Network:	TIX		Name:		SPACE COAST REGIONAL AIRPORT						
Branch:	TW F		Name:		TAXIWAY F		Use:	TAXIWAY	Area:	30,388 SqFt	
Section:	605		of 1		From: -		To: -		Last Const.: 1/1/1998		
Surface:	AAC		Family:		CA653-GA-TW-AAC-APC		Zone:		Category:		Rank: P
Area:	30,388 SqFt		Length:		580 Ft		Width:		50 Ft		
Slabs:			Slab Length:		Ft		Slab Width:		Ft		Joint Length: Ft
Shoulder:			Street Type:				Grade: 0		Lanes: 0		
Section Comments:											
Work Date:	1/1/1943		Work Type: BUILT				Code: IMPORTED		Is Major M&R: True		
Work Date:	1/1/1998		Work Type: Mill and Overlay				Code: ML-OVL		Is Major M&R: True		
Last Insp. Date:	4/12/2022		TotalSamples:		6		Surveyed: 2				
Conditions:	PCI: 14										
Inspection Comments:											
Sample Number:	301		Type:	R	Area:		5000.00 SqFt		PCI: 11		
Sample Comments:											
41	ALLIGATOR CR		M	90.00 SqFt							
43	BLOCK CR		M	4901.00 SqFt							
50	PATCHING		L	8.00 SqFt							
50	PATCHING		M	1.00 SqFt							
52	RAVELING		M	4990.00 SqFt							
52	RAVELING		H	1.00 SqFt							
Sample Number:	304		Type:	R	Area:		6930.00 SqFt		PCI: 16		
Sample Comments:											
41	ALLIGATOR CR		M	84.00 SqFt							
41	ALLIGATOR CR		H	3.00 SqFt							
43	BLOCK CR		M	5484.00 SqFt							
50	PATCHING		L	1350.00 SqFt							
50	PATCHING		M	9.00 SqFt							
52	RAVELING		M	4455.00 SqFt							
52	RAVELING		H	2.00 SqFt							



FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE



AVIATION