

2022

Statewide Airfield Pavement Management Program



Airport Pavement Evaluation Report

VNC - Venice Municipal Airport | *District 1*



AVIATION

Florida Department of Transportation

Statewide Airfield Pavement Management Program

Airport Pavement Evaluation Report

Prepared by:

*FDOT Aviation Office
605 Suwannee Street
Tallahassee, Florida 32399-0450*

Website: [FDOT Aviation Office](#)

Interactive Web Application: [FDOT SAPMP Interactive Web Application](#)

TABLE OF CONTENTS

EXECUTIVE SUMMARY	1
<i>Program Background.....</i>	<i>1</i>
<i>Current Pavement Conditions</i>	<i>2</i>
<i>Forecasted Pavement Conditions</i>	<i>4</i>
<i>Major Rehabilitation Planning 2023-2032</i>	<i>6</i>
CHAPTER 1 – INTRODUCTION.....	9
1.1 <i>Background</i>	<i>9</i>
1.2 <i>Stakeholders.....</i>	<i>11</i>
1.3 <i>General Scope of Work</i>	<i>11</i>
1.4 <i>FDOT SAPMP Objectives</i>	<i>12</i>
CHAPTER 2 – METHODOLOGY.....	15
2.1 <i>Airfield Pavement Database.....</i>	<i>15</i>
2.2 <i>Airfield Pavement Record Keeping (Historical Records Research).....</i>	<i>16</i>
2.3 <i>Airfield Pavement Structure.....</i>	<i>16</i>
2.3.1 <i>Asphalt Concrete.....</i>	<i>17</i>
2.3.2 <i>Portland Cement Concrete</i>	<i>17</i>
2.3.3 <i>Composite Structure – Whitetopping Pavement</i>	<i>17</i>
2.4 <i>Airfield Pavement Traffic</i>	<i>18</i>
2.5 <i>Pavement Management Program Network Definition Terminology</i>	<i>18</i>
2.5.1 <i>Pavement Network Identification</i>	<i>18</i>
2.5.2 <i>Pavement Branch Identification</i>	<i>18</i>
2.5.3 <i>Pavement Section Identification</i>	<i>19</i>
2.5.4 <i>Pavement Sample Unit Identification</i>	<i>19</i>
2.5.5 <i>Terminology Summary</i>	<i>19</i>
2.6 <i>Airfield PCI Survey Methodology</i>	<i>19</i>
2.6.1 <i>Pavement Distress Types.....</i>	<i>20</i>
2.6.2 <i>PCI Survey Procedures.....</i>	<i>21</i>
CHAPTER 3 – AIRFIELD PAVEMENT SYSTEM INVENTORY.....	24
3.1 <i>Airfield Pavement Network Information.....</i>	<i>24</i>
3.1.1 <i>Previous and/or Anticipated Airfield Pavement Construction</i>	<i>24</i>
3.1.2 <i>Estimated Pavement Age</i>	<i>27</i>
3.1.3 <i>Functional Use</i>	<i>29</i>
3.1.4 <i>Pavement Surface Type.....</i>	<i>29</i>
3.1.5 <i>Pavement System Inventory Details.....</i>	<i>30</i>
CHAPTER 4 – AIRFIELD PAVEMENT CONDITION ANALYSIS	33
4.1 <i>Airfield Pavement Condition Index.....</i>	<i>33</i>
4.1.1 <i>Network-Level Analysis</i>	<i>33</i>
4.1.2 <i>Branch-Level Analysis.....</i>	<i>33</i>
4.1.3 <i>Section-Level Analysis</i>	<i>36</i>
4.2 <i>Summary of Pavement Condition Evaluation Results</i>	<i>40</i>

4.2.1 Network-Level Observations	40
4.2.2 Branch-Level Observations	40
CHAPTER 5 – SAPMP CUSTOMIZATION.....	48
5.1 Network-Level Customization.....	48
5.2 Pavement Condition Forecasts	48
5.2.1 Forecasting PCI Considerations	49
5.2.2 Performance Models	49
5.2.3 Branch-Level Pavement Condition Forecast	49
5.2.4 Section-Level Pavement Condition Forecast.....	50
5.3 Critical PCI Value.....	52
5.4 Localized Maintenance and Repair	55
5.4.1 Localized Maintenance and Repair Approach	55
5.4.2 Localized Work Types	56
5.4.3 Localized Maintenance Planning-Level Unit Costs	58
5.4.4 Localized Maintenance and Repair Policy	58
5.5 Major Rehabilitation	61
5.5.1 Major Rehabilitation Pavement Section Development	61
5.5.2 Major Rehabilitation Planning-Level Unit Costs	63
CHAPTER 6 – M&R PLANNING AND BUDGET SCENARIO ANALYSIS	65
6.1 Localized Maintenance and Repair Analysis and Recommendations	65
6.2 Major Rehabilitation Needs.....	67
6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs	68
CHAPTER 7 – CONCLUSION.....	72
7.1 Recommendations	72
7.1.1 Continued PCI Surveys	72
7.1.2 Localized Maintenance and Repair	72
7.1.3 Major Rehabilitation.....	72
7.1.4 Pavement Management System.....	72
7.2 Supporting Documents	73
Airfield Pavement Network Definition Exhibit.....	73
Airfield Pavement System Inventory Exhibit	73
Airfield Pavement Estimated Age Exhibit	73
Airfield Pavement Condition Index Exhibit.....	73
Airfield Pavement Major Rehabilitation Exhibit	73
Inspection Photograph Documentation.....	73
7.3 Conclusion.....	74
7.4 References	74

APPENDIX


Appendix A: Airfield Pavement Analysis

Appendix B: Maintenance and Rehabilitation Planning Needs

Appendix C: Technical Exhibits

Appendix D: Inspection Photograph Documentation

Appendix E: Inspection Distress Details



LIST OF TABLES

Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level.....	2
Table E.2: Forecasted PCI Values 2023-2032 – Section-Level.....	4
Table E.3: Major Rehabilitation Planning 2023-2032.....	6
Table 1.2: FDOT SAPMP Stakeholders	11
Table 2.5.5: SAPMP Terminology	19
Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete	20
Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete.....	21
Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete.....	21
Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete	22
Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction	24
Table 3.1.5: Pavement System Inventory Details	30
Table 4.1.2: Current Condition Summary – Branch-Level	36
Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level.....	37
Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level	50
Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects.....	53
Table 5.3 (b): Critical PCI Values by Branch Use	53
Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete	58
Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete.....	58
Table 5.4.4: AC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy.....	59
Table 5.4.5: PCC Pavement Localized Preventive& Stopgap Maintenance & Repair Policy	60
Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation	62
Table 5.5.2: RL Major Rehabilitation Planning-Level Unit Cost by Pavement Type	63
Table 6.1 (a): Year 1 Summary of Localized Maintenance	65
Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary	66
Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary	66
Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs	68

LIST OF FIGURES

Figure E.1: PCI Rating.....	1
Figure E.2: Current Condition Summary – Branch-Level.....	2
Figure E.3: 10-Year Major Rehabilitation Needs by Program Year.....	7
Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts	10
Figure 1.4: Pavement Life and the Effect of Treatments.....	13
Figure 2: FDOT SAPMP General Process	15
Figure 3.1.1 (a): Airfield Pavement Network Definition Exhibit.....	25
Figure 3.1.1 (b): Airfield Pavement System Inventory Exhibit.....	26
Figure 3.1.2 (a): Age of Pavements at PCI Survey.....	27
Figure 3.1.2 (b): Airfield Pavement Estimated Age Exhibit	28
Figure 3.1.3: Airfield Pavement Branch Use by Area (SF).....	29
Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)	30
Figure 4.1.1: Current Condition – Overall Network.....	33
Figure 4.1.2 (a): Current Condition Summary – Branch-Level.....	33
Figure 4.1.2 (b): Current Condition – Runway	34
Figure 4.1.2 (c): Current Condition – Taxiway	34
Figure 4.1.2 (d): Current Condition – Taxilane	35
Figure 4.1.2 (e): Current Condition – Apron	35
Figure 4.1.3: Airfield Pavement Condition Index Exhibit.....	39
Figure 5.2.3: Forecasted Branch-Level Pavement Performance	49
Figure 5.3 (a): Pavement Life and the Effect of Treatments	52
Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical PCI}$	54
Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical PCI}$	54
Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year.....	69
Figure 6.2.1 (b): Airfield Pavement Major Rehabilitation Exhibit.....	70



Executive Summary



Executive Summary

Program Background

The FDOT Aviation Office (AO) has a mission to provide a safe and secure air transportation system that ensures the mobility of people and goods, enhances economic prosperity, and preserves the quality of our environment and communities. As part of ongoing efforts in fulfilling this mission, the Aviation Office is executing a System Update to the Statewide Airfield Pavement Management Program (SAPMP). The scope of the SAPMP encompasses 95 public-use airport facilities distributed throughout the seven (7) participating FDOT Districts. Venice Municipal Airport's System Update results are presented in this report and can be utilized by FDOT and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement maintenance, repair, and major rehabilitation projects.

Pavement condition was assessed utilizing the pavement condition index (PCI) methodology as defined in FAA Advisory Circular 150/5380-7B "Airport Pavement Management Program (PMP)" using the procedures documented in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

The PCI methodology provides a means for systematically assessing pavement condition and provides an indication of the degree of maintenance, repair, rehabilitation, or reconstruction efforts required to sustain functional pavement conditions. Pavement deterioration, in accordance with ASTM D5340-20, is characterized in terms of distinct distress types, distress severity levels, and quantity of distress. This information is utilized to calculate a PCI value ranging from 0 to 100, which provides an indication of the overall condition of the pavement, with "100" indicating a pavement in new condition and "0" indicating a failed pavement section. This is graphically depicted in **Figure E.1**.

Figure E.1: PCI Rating

Color	Range	Condition Rating
	86-100	Good
	71-85	Satisfactory
	56-70	Fair
	41-55	Poor
	26-40	Very Poor
	11-25	Serious
	0-10	Failed

Current Pavement Conditions

In May 2022, approximately 3.6 million square feet of pavement was assessed as part of the airside pavement network PCI survey at Venice Municipal Airport (VNC). In general, airfield pavements at VNC are in Satisfactory condition with an area-weighted PCI of 81. The area-weighted average PCI values of the runways, taxiways, taxilanes, and aprons are 80, 93, 65, and 79, respectively. **Figure E.2** and **Table E.1** summarize the current PCI values for VNC.

Figure E.2: Current Condition Summary – Branch-Level




Table E.1: Pavement Condition Index Summary (Current PCI Survey) – Section Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VNC	RW 5-23	Runway	6205	255,000	85	Satisfactory
VNC	RW 5-23	Runway	6210	382,500	88	Good
VNC	RW 5-23	Runway	6215	18,000	85	Satisfactory
VNC	RW 5-23	Runway	6220	27,000	91	Good
VNC	RW 5-23	Runway	6225	18,000	85	Satisfactory
VNC	RW 5-23	Runway	6230	27,000	92	Good
VNC	RW 13-31	Runway	6105	413,900	71	Satisfactory
VNC	RW 13-31	Runway	6110	196,950	71	Satisfactory
VNC	RW 13-31	Runway	6115	30,000	65	Fair
VNC	RW 13-31	Runway	6120	20,000	61	Fair
VNC	RW 13-31	Runway	6125	30,000	65	Fair
VNC	RW 13-31	Runway	6130	20,000	60	Fair
VNC	RW 13-31	Runway	6135	26,100	85	Satisfactory
VNC	RW 13-31	Runway	6140	13,050	85	Satisfactory
VNC	RW 13-31	Runway	6145	63,850	91	Good
VNC	RW 13-31	Runway	6150	31,925	94	Good
VNC	TW A	Taxiway	105	55,145	93	Good

Airport Pavement Evaluation Report

Statewide Airfield Pavement Management Program

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VNC	TW A	Taxiway	110	55,883	84	Satisfactory
VNC	TW A	Taxiway	115	52,281	90	Good
VNC	TW A	Taxiway	120	9,988	80	Satisfactory
VNC	TW A	Taxiway	125	5,738	66	Fair
VNC	TW B	Taxiway	220	47,695	94	Good
VNC	TW B	Taxiway	225	12,448	89	Good
VNC	TW B	Taxiway	235	21,767	94	Good
VNC	TW C	Taxiway	315	85,087	93	Good
VNC	TW D	Taxiway	400	38,598	94	Good
VNC	TW D	Taxiway	405	76,359	94	Good
VNC	TW D	Taxiway	410	17,828	88	Good
VNC	TW D	Taxiway	420	109,579	100	Good
VNC	TW E	Taxiway	505	62,102	87	Good
VNC	TW E	Taxiway	510	10,168	85	Satisfactory
VNC	TW E	Taxiway	515	21,560	91	Good
VNC	TW E	Taxiway	520	110,616	100	Good
VNC	TW E	Taxiway	550	9,260	80	Satisfactory
VNC	TW F	Taxiway	450	11,675	94	Good
VNC	TL T-HANG	Taxilane	605	16,734	69	Fair
VNC	TL T-HANG	Taxilane	610	42,622	66	Fair
VNC	TL T-HANG	Taxilane	620	100,062	52	Poor
VNC	TL T-HANG	Taxilane	705	34,474	78	Satisfactory
VNC	TL T-HANG	Taxilane	708	11,446	67	Fair
VNC	TL T-HANG	Taxilane	710	41,684	46	Poor
VNC	TL T-HANG	Taxilane	715	12,768	89	Good
VNC	TL T-HANG	Taxilane	720	5,422	89	Good
VNC	TL T-HANG	Taxilane	725	17,209	92	Good
VNC	TL T-HANG	Taxilane	730	18,001	59	Fair
VNC	TL T-HANG	Taxilane	735	21,329	94	Good
VNC	AP	Apron	4105	112,335	21	Serious
VNC	AP	Apron	4110	302,352	92	Good
VNC	AP	Apron	4115	34,307	4	Failed
VNC	AP	Apron	4120	58,790	93	Good
VNC	AP	Apron	4125	53,176	89	Good
VNC	AP	Apron	4127	19,630	89	Good
VNC	AP	Apron	4130	6,119	94	Good
VNC	AP	Apron	4140	73,498	90	Good
VNC	AP MID	Apron	4405	166,523	94	Good
VNC	AP RU 13	Apron	5110	19,846	91	Good
VNC	AP RU 23	Apron	5105	26,551	93	Good

Forecasted Pavement Conditions

Table E.2 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as the actual condition of sections is subject to sensitivities in changes of traffic and maintenance frequency.

The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.

Table E.2: Forecasted PCI Values 2023-2032 – Section-Level

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
VNC	RW 5-23	6205	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6210	88	86	84	83	81	79	77	76	74	72	70
VNC	RW 5-23	6215	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6220	91	89	86	84	83	81	79	78	77	75	74
VNC	RW 5-23	6225	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6230	92	89	87	85	83	82	80	79	77	76	75
VNC	RW 13-31	6105	71	69	67	66	64	62	60	59	57	55	53
VNC	RW 13-31	6110	71	69	67	66	64	62	60	59	57	55	53
VNC	RW 13-31	6115	65	63	61	60	58	56	54	53	51	49	47
VNC	RW 13-31	6120	61	59	57	56	54	52	50	49	47	45	43
VNC	RW 13-31	6125	65	63	61	60	58	56	54	53	51	49	47
VNC	RW 13-31	6130	60	58	56	55	53	51	49	48	46	44	42
VNC	RW 13-31	6135	85	83	81	80	78	76	74	73	71	69	67
VNC	RW 13-31	6140	85	83	81	80	78	76	74	73	71	69	67
VNC	RW 13-31	6145	91	89	86	84	83	81	79	78	77	75	74
VNC	RW 13-31	6150	94	91	89	87	85	83	81	80	78	77	76
VNC	TW A	105	93	91	89	87	85	83	82	80	78	77	76
VNC	TW A	110	84	82	81	79	78	76	75	74	72	71	70
VNC	TW A	115	90	88	86	84	82	81	79	78	76	75	74
VNC	TW A	120	80	78	77	76	74	73	72	71	70	69	68
VNC	TW A	125	66	65	64	63	62	61	61	60	59	58	58
VNC	TW B	220	94	92	90	88	86	84	82	81	79	78	76
VNC	TW B	225	89	87	85	83	82	80	78	77	76	74	73
VNC	TW B	235	94	92	90	88	86	84	82	81	79	78	76
VNC	TW C	315	93	91	89	87	85	83	82	80	78	77	76
VNC	TW D	400	94	92	90	88	86	84	82	81	79	78	76
VNC	TW D	405	94	92	90	88	86	84	82	81	79	78	76
VNC	TW D	410	88	86	84	82	81	79	78	76	75	74	73
VNC	TW D	420	100	92	90	88	86	84	83	81	79	78	76
VNC	TW E	505	87	85	83	82	80	78	77	76	74	73	72
VNC	TW E	510	85	83	81	80	78	77	76	74	73	72	71
VNC	TW E	515	91	89	87	85	83	82	80	78	77	76	74

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
VNC	TW E	520	100	96	94	92	89	88	86	84	82	81	79
VNC	TW E	550	80	78	77	76	74	73	72	71	70	69	68
VNC	TW F	450	94	92	90	88	86	84	82	81	79	78	76
VNC	TL T-HANG	605	69	68	67	66	65	65	64	63	63	62	61
VNC	TL T-HANG	610	66	65	64	64	63	62	62	61	61	60	60
VNC	TL T-HANG	620	52	51	51	50	50	49	48	48	47	46	45
VNC	TL T-HANG	705	78	76	75	74	73	71	70	69	68	67	67
VNC	TL T-HANG	708	67	66	65	65	64	63	63	62	61	61	60
VNC	TL T-HANG	710	46	45	44	43	42	41	40	39	37	36	35
VNC	TL T-HANG	715	89	87	85	83	82	80	78	77	76	74	73
VNC	TL T-HANG	720	89	87	85	83	82	80	78	77	76	74	73
VNC	TL T-HANG	725	92	90	88	86	84	82	81	79	78	76	75
VNC	TL T-HANG	730	59	58	58	57	56	55	55	54	53	52	52
VNC	TL T-HANG	735	94	92	90	88	86	84	82	81	79	78	76
VNC	AP	4105	21	20	19	17	16	15	14	13	12	10	9
VNC	AP	4110	92	90	88	85	83	81	79	78	76	74	72
VNC	AP	4115	4	3	2	0	0	0	0	0	0	0	0
VNC	AP	4120	93	91	88	86	84	82	80	78	77	75	73
VNC	AP	4125	89	87	85	83	81	79	77	75	73	72	70
VNC	AP	4127	89	87	84	82	80	78	76	73	71	69	67
VNC	AP	4130	94	92	89	87	85	83	81	79	77	76	74
VNC	AP	4140	90	88	86	84	82	80	78	76	74	72	71
VNC	AP MID	4405	94	92	89	87	85	83	81	79	77	76	74
VNC	AP RU 13	5110	91	89	87	84	82	80	79	77	75	73	71
VNC	AP RU 23	5105	93	91	88	86	84	82	80	78	77	75	73

Major Rehabilitation Planning 2023-2032

Localized maintenance and repair policies identified within this report are categorized as preventive or stopgap based on FDOT SAPMP and FAA maintenance policies and recommendations. Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a reset of a pavement section's PCI to a value of 100. Major rehabilitation activities can include mill and Asphalt Concrete (AC) overlay, Portland cement concrete (PCC) pavement repair and slab replacement, and full-depth reconstruction. It is recommended that the Airport use this report as a planning tool for future project development and prioritization. Localized maintenance, repair, and major rehabilitation recommendations should be considered as planning-level only. Final localized maintenance, repair, and major rehabilitation recommendations are subject to change based on Airport prioritization and further design-level evaluations.

Due to FAA Order 5100.38D Change 1 Airport Improvement Program (AIP) Handbook (February 26, 2019), a substantial update to the FDOT SAPMP policy on identifying major rehabilitation work has been incorporated in this System Update. In previous System Updates, major rehabilitation had been identified for pavement sections below a PCI Value of 65; however, based on the thresholds identified by the FAA in the AIP Handbook, major rehabilitation will now be identified for pavement sections below a PCI value of 70.

The results of the maintenance, repair, and major rehabilitation analysis identified approximately \$20.24M in major rehabilitation needs for the 10-year forecast period. Year 1 major needs are \$17.68M and localized maintenance needs for Year 1 are \$0.59M.

Table E.3: Major Rehabilitation Planning 2023-2032

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	VNC	RW 13-31	6105	AAC	413,900	69	AC Rehabilitation	\$ 4,346,000
2023	VNC	RW 13-31	6110	AAC	196,950	69	AC Rehabilitation	\$ 2,068,000
2023	VNC	RW 13-31	6115	APC	30,000	63	AC Rehabilitation	\$ 315,000
2023	VNC	RW 13-31	6120	APC	20,000	59	AC Rehabilitation	\$ 210,000
2023	VNC	RW 13-31	6125	APC	30,000	63	AC Rehabilitation	\$ 315,000
2023	VNC	RW 13-31	6130	APC	20,000	58	AC Rehabilitation	\$ 210,000
2023	VNC	TW A	125	AAC	5,738	65	AC Rehabilitation	\$ 61,000
2023	VNC	TL T-HANG	605	AC	16,734	68	AC Rehabilitation	\$ 176,000
2023	VNC	TL T-HANG	610	AC	42,622	65	AC Rehabilitation	\$ 448,000
2023	VNC	TL T-HANG	620	AC	100,062	51	AC Reconstruction	\$ 1,852,000
2023	VNC	TL T-HANG	708	AC	11,446	66	AC Rehabilitation	\$ 121,000
2023	VNC	TL T-HANG	710	AC	41,684	45	AC Reconstruction	\$ 772,000
2023	VNC	TL T-HANG	730	AAC	18,001	58	AC Rehabilitation	\$ 190,000
2023	VNC	AP	4105	PCC	112,335	20	PCC Reconstruction	\$ 5,056,000
2023	VNC	AP	4115	PCC	34,307	3	PCC Reconstruction	\$ 1,544,000
2029	VNC	TL T-HANG	705	AC	34,474	69	AC Rehabilitation	\$ 486,000
2030	VNC	TW A	120	AC	9,988	70	AC Rehabilitation	\$ 148,000
2030	VNC	TW E	550	AC	9,260	70	AC Rehabilitation	\$ 137,000
2031	VNC	RW 13-31	6135	AAC	26,100	69	AC Rehabilitation	\$ 405,000


Airport Pavement Evaluation Report

Statewide Airfield Pavement Management Program

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2031	VNC	RW 13-31	6140	AAC	13,050	69	AC Rehabilitation	\$ 203,000
2031	VNC	AP	4127	AAC	19,630	69	AC Rehabilitation	\$ 305,000
2032	VNC	AP	4125	AC	53,176	70	AC Rehabilitation	\$ 867,000

*All planning cost values have been rounded up to the nearest thousand dollars.

Figure E.3: 10-Year Major Rehabilitation Needs by Program Year





Chapter 1: Introduction



Chapter 1 – Introduction

The State of Florida has 128 public airports, 100 of which are recognized as part of the Federal Aviation Administration's (FAA) National Plan of Integrated Airport Systems (NPIAS). These public-use airports are vital to Florida's economy as well as the economy of the United States. The Florida Airport System (FAS) provides opportunities for the State to capitalize on an increasingly global marketplace. Florida's system of commercial service and general aviation airports are important to businesses throughout the State as air travel is essential to tourism, Florida's most prominent industry.

1.1 Background

In 1992, the Florida Department of Transportation (FDOT) established the Statewide Airfield Pavement Management Program (SAPMP) to provide program managers, District Aviation Offices, and Airport operators with a system to proactively manage airfield pavement infrastructure within the FAS. The SAPMP includes network-level Pavement Condition Index (PCI) surveys for Airport facilities that are categorized as General Aviation (GA), Reliever (RL), and Primary/Commercial (PR). Currently, the SAPMP includes 95 participating public-use airports with pavement facilities and provides its users with comprehensive data to better manage their pavement assets.


There are millions of square feet of pavement infrastructure at airports across a network of runways, taxiways, aprons, and other areas. This pavement infrastructure is vital to the support and safety of aircraft operations. Timely maintenance, repair, and major rehabilitation of pavement infrastructure allows the Airport to operate safely, efficiently, and economically without excessive down time.

Airports participating in the Airport Improvement Program (AIP) Grant Program are required by the FAA to develop and implement a pavement maintenance program in order to be eligible for funding, per FAA Advisory Circulars 150/5380-6C "Guidelines and Procedures for Maintenance of Airport Pavements" and 150/5380-7B "Airport Pavement Management Program (PMP)". The AIP program requires detailed assessments of airfield pavements at least once a year for a pavement management program. The frequency of the detailed inspections may be extended to every three years if the pavement is assessed according to the PCI survey procedure described in ASTM D5340-20 "Standard Test Method for Airport Pavement Condition Index Surveys".

In general, adherence to the FAA Advisory Circulars is mandatory for projects funded with federal grant monies through the AIP program and with revenue from the Passenger Facilities Charges (PFC) Program. Further information is detailed in FAA Grant Assurance No. 11 "Pavement Maintenance," No. 34 "Policies, Standards, and Specifications," and PFC Assurance No. 9 "Standards and Specifications." The FDOT performs the SAPMP System Updates for the benefit of participating public-use and publicly-owned airports through the Aviation Office (AO).

The SAPMP addresses the requirements of maintaining an effective pavement management program for participating airports at the network level. Network-level management of pavement assets provides insight for short-term and long-term budget needs, understanding of the overall condition of the network (current and future), and knowledge of the pavement facilities that are

Figure 1.1: Florida Aviation System (Facilities with Pavement) and FDOT Districts



1.2 Stakeholders

The SAPMP is performed for the benefit of the stakeholders. The table below outlines the primary stakeholders of the FDOT SAPMP and their role in the program.

Table 1.2: FDOT SAPMP Stakeholders

Role	Description
FAA Orlando Airports District Office (Orlando ADO)	Key Stakeholder: local ADO Program Manager personnel that oversees the grant administration of AIP grant with Planning Agency Sponsor (Florida Department of Transportation).
Florida Department of Transportation (FDOT)	Key Stakeholder: the FDOT is the "Sponsor" for the AIP grant agreement. Specifically, the Aviation Office (AO) provides development and operations support for the Florida Airport System.
FDOT District Offices	The seven (7) FDOT District Offices, specifically the Aviation representatives, provide essential support to the SAPMP System Update and the AO Program Manager (AO-PM). Each District supports the SAPMP's ongoing efforts by providing local construction cost information throughout the State, which is used as the basis of development for maintenance, repair, and major rehabilitation opinions of probable construction costs for planning purposes.
Participating Public-Use and Publicly-Owned Airports	The airports are the end-user and primary beneficiary of the SAPMP. The SAPMP provides a specific Airport Pavement Evaluation Report that meets the requirements of the FAA AC 150/5380-7B. Individual participating airports are provided a final Airport Pavement Evaluation Report by the Consultant that is specific to each airport's airfield PCI assessment.
Aviation Office Program Manager (AO-PM)	FDOT AO Airport Engineering Manager: oversees and manages the overall Program System Update.

1.3 General Scope of Work

The SAPMP is limited to performing tasks in adherence to the key elements of an effective pavement management program on a statewide level. The primary tasks undertaken to update the FDOT SAPMP include, but are not limited to:

- » Research and evaluation of existing record documentation;
- » Establishment of a pavement system inventory;
- » Development of a pavement network definition map and supplemental GIS model;
- » Functional pavement evaluations via the PCI assessment method;
- » Customization of PAVER™ software including prioritization, policies, and performance models;
- » Analysis of condition data; and
- » Maintenance, repair, and rehabilitation planning.

1.4 FDOT SAPMP Objectives

The SAPMP enables the FDOT AO and FAA to monitor pavement conditions at airports in the Florida Airport System. The SAPMP provides objective condition information needed to make informed decisions regarding the significant capital investment that the public-use airport pavement infrastructure represents.

Airport staff are responsible for making decisions regarding the timing and type of maintenance and rehabilitation activities that should be completed in order to maintain an acceptable operational condition and adequate load-carrying capacity. Utilizing the SAPMP will help Airport staff better understand the relative condition of their pavement facilities and when those facilities should be rehabilitated. The data collected from the SAPMP can be used for project programming for the next 10 years. This report summarizes the data collection, analysis, program update, and implementation of the FDOT SAPMP.


A comprehensive SAPMP provides information that assists with the project programming process. The primary objectives of the FDOT SAPMP consist of the following:

- » Assist airports in meeting the requirements of Public Law 103-305;
- » Assist airports in complying with FAA Grant Assurances 11 and 19;
- » Provide airports with functional pavement condition in accordance with ASTM D5340-20 (current) and with the FAA AC 150/5380-7B (current) based on visual assessment efforts;
- » Provide airports with planning-level guidance on maintenance, repair, and rehabilitation in accordance with the FAA AC 150/5380-6C (current) based on pavement conditions and distress data in terms of type, severity, and extent; and
- » Provide airports, FDOT Districts, FDOT AO, and the FAA Airports District Office with long-term, planning-level forecasts of pavement performance and rehabilitation budgetary needs (e.g., maintenance, repair, and major reconstruction) through reports.

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets before they reach critical condition. Critical PCI values are assigned to deterioration models for pavement assets based on their respective use and rank. The concept of critical PCI will be further discussed in **Chapter 5**, but it is used as a benchmark to help identify pavement assets that should receive rehabilitation. In doing so, the PCI methodology can help create a proactive maintenance and rehabilitation (M&R) strategy to effectively address pavement projects before the cost of these projects increases significantly.

With M&R costs escalating over time, the consequences of inadequate maintenance practices can result in an inefficient allocation of funding. If maintenance is conducted before a significant decline in pavement condition occurs, substantial repair and/or rehabilitation costs may be avoided or delayed. **Figure 1.4** illustrates how the cost of pavement repairs can significantly increase if M&R activities are delayed.

Figure 1.4: Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds: ☐ >70: Routine Maintenance ☐ 55-70: Rehabilitation Eligible ☐ <55: Reconstruction Eligible

*Figure is for conceptual purposes only – unit costs are not specific to airfield pavements




Chapter 2: Methodology



Chapter 2 – Methodology

An effective pavement management program incorporates both the regular collection of pavement condition information and communication of information to appropriate sponsors. This chapter of the report defines the specific methods utilized as part of the SAPMP System Update to meet the requirements of an effective pavement management system as defined by the FAA AC 150/5380-7B. **Figure 2** summarizes the overall process for the FDOT SAPMP.

Figure 2: FDOT SAPMP General Process



2.1 Airfield Pavement Database

This SAPMP utilizes PAVER™ 7.0 software as its airfield pavement database. The PAVER™ software application was developed by the U.S. Army Construction Engineering Research Laboratory and sponsored by the FAA, Federal Highway Administration, U.S. Army, U.S. Air Force, and U.S. Navy to meet the objectives of an effective pavement management system. The PAVER™ database includes a network-level inventory of the participating airport's eligible airfield pavement facilities. PAVER™ can achieve the following pavement management objectives:

- » Create a manageable inventory system;
- » Analyze the current condition of pavements in accordance with ASTM D5340-20;
- » Develop pavement performance models to forecast conditions; and
- » Generate maintenance, repair, and major rehabilitation recommendations based on budgetary scenarios.

PAVER™ inventory management is based on a tiered organizational structure consisting of networks, branches, sections, and samples, with the sample being the smallest unit of management. Critical elements of an effective pavement management program are maintained within the network-level PAVER™ database and typically consist of pavement inventory

characteristics, pavement structure, work history, historic condition records, and analytical customization.

2.2 Airfield Pavement Record Keeping (Historical Records Research)

In accordance with the FAA AC 150/5380-7B, it is a best practice that airports maintain records of all airfield construction and maintenance (routine, emergency, and proactive) related to the pavement facilities. These records should consist of:

- » Location and limits of work;
- » Types and severities of repaired distresses;
- » Work type and cost; and
- » Supporting documents (e.g., contract documents, construction drawings, specifications, bid tabulations, repair products, and photograph records).

As part of the SAPMP, participating airport's staff was asked to provide documentation regarding the historical work performed at the Airport, including construction drawings and bid tabulations. This information is used to identify location, limits, type of work, pavement cross-sections, and representative material costs.

Updated historical data collected during this task was entered into the PAVER™ database. This database includes the following fields for historical information:

- » Date of last construction/rehabilitation
- » Work type performed
- » Comments for documenting pavement cross-section
- » Pavement surface type
- » Section area (limits of work)

The SAPMP PAVER™ database accuracy is limited to the record documentation provided by the participating airports. Airport Sponsors should rely on this information as a planning tool and defer to final as-built plans, record drawings, and/or engineer's construction report for pavement construction records.

2.3 Airfield Pavement Structure

A pavement is a prepared surface designed to provide a continuous, smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. A pavement structure is composed of constructed layers consisting of subgrade, subbase, base, structural, and surface courses. For the FDOT SAPMP, two (2) predominant pavement types are classified for evaluation and analysis: Asphalt Concrete (AC) and Portland cement concrete (PCC). Composite Structures, known as Whitetopping Pavements consisting of PCC on AC, are also present at limited airports in Florida and are evaluated separately.

2.3.1 Asphalt Concrete

Asphalt concrete is a pavement comprised of aggregate mixture with an asphalt cement binder. The FDOT SAPMP categorizes three (3) Asphalt Concrete surface types: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), and Asphalt Concrete overlaid on Portland cement concrete (APC).

Asphalt Concrete (AC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on engineered base course material that is layered on subbase and subgrade soil material.

Asphalt Concrete Overlaid on Asphalt Concrete (AAC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing flexible AC pavement section. Airfield pavement sections are considered to be AAC when a pavement rehabilitation includes a pavement milling and resurfacing operation or a direct overlay of Asphalt Concrete without surface preparation.

Asphalt Concrete Overlaid on Portland Cement Concrete (APC)

A flexible pavement section consisting of aggregate mixture with asphalt cement binder layered on an existing PCC pavement section. This unique pavement composition may result in distinct pavement distress manifestations known as reflective joint cracking.

2.3.2 Portland Cement Concrete

Portland cement concrete is a pavement comprised of aggregate mixture with a Portland cement binder. The FDOT SAPMP categorizes Portland cement concrete (PCC) as the primary rigid pavement section.

Portland Cement Concrete (PCC)

A rigid pavement section composed of Portland cement concrete placed on a granular or treated base course that is supported on a compacted subgrade. The concrete surface provides a texture of nonskid qualities, prevents the infiltration of surface water into the subgrade, and provides structural support for airplane loading. Rigid pavement construction requires the layout of appropriately designed joints. Concrete overlays built in accordance with the FAA Advisory Circular 150/5320-6F "Airport Pavement Design and Evaluation" are recognized as PCC pavement.

2.3.3 Composite Structure – Whitetopping Pavement

Whitetopping pavement is a composite pavement comprised of relatively thin PCC overlaid on an existing AC pavement structure. There are three (3) types of Whitetopping Pavements: Conventional (WT), Thin (TWT), and Ultra-Thin (UWT).

Conventional Whitetopping (WT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically greater than 6 inches in thickness.

Thin Whitetopping (TWT)

A composite pavement structure consisting of modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 4 and 6 inches in thickness.

Ultra-Thin Whitetopping (UWT)

A composite pavement structure consisting of a modified PCC overlaid on an existing AC pavement section. The modified PCC layer is typically between 2 and 4 inches in thickness.

2.4 Airfield Pavement Traffic

A pavement section is typically designed to meet the needs of the user (airlines, air cargo, general aviation, and/or military) in providing a safe, smooth, operational surface. Pavement deterioration generally occurs gradually from aircraft loading and environmental conditions.

This System Update does not involve a study or analysis of VNC's aircraft fleet mix or traffic operations. However, it is strongly recommended that the Airport incorporate the requirements of the FAA AC 150/5320-6F when developing design-level rehabilitation activities; this AC provides guidance on incorporation of aircraft traffic fleet mix data.

2.5 Pavement Management Program Network Definition Terminology

To facilitate an effective pavement management program, a pavement network must be established and subdivided into smaller, manageable working units. Sectioning of the pavement network was established in a prior System Update and was revised during this SAPMP to account for work that has been performed on the airfield since the previous Update. Information from historic records is used to help define the limits of the smaller working units. A critical input for a pavement inventory and network definition is the date of last major construction or rehabilitation, as this type of work will reset the section PCI to a value of 100.

The following sections define the common terms used in pavement management systems and cover their application for this SAPMP System Update.

2.5.1 Pavement Network Identification

Establishing the pavement network is the first step in organizing pavements into a structure for pavement management. The network is the starting point of the hierarchy of pavement management organization. A network typically consists of one or more pavement *branches*, which have one or more pavement *sections*. For example, a network can be all the pavements within an Airport's airfield or all the pavements in a statewide program. For the FDOT SAPMP, a network represents an individual Airport's airfield pavement facilities maintained by the Airport.

2.5.2 Pavement Branch Identification

A pavement branch, also known as a facility, is a logical unit of generally identifiable pavement within a network that has a distinct functional classification. For example, within an airfield, each runway, taxiway, or apron is considered a branch. Each branch contains at least one section but may contain more if pavement feature characteristics are distinct throughout the branch.

2.5.3 Pavement Section Identification

A pavement section, or feature, is a subdivision of a branch and has consistent characteristics throughout its length or area. These characteristics include structural composition (pavement layer material type and thickness), construction history, age, traffic type, traffic frequency, and pavement condition. A section is the basic management unit of a pavement network and is the level at which maintenance, repair, or major rehabilitation treatments are considered.

2.5.4 Pavement Sample Unit Identification

A pavement sample unit is an arbitrarily defined subdivision of a pavement section that has a standard size range of 20 contiguous slabs (± 8 slabs) for PCC pavement and 5,000 contiguous square feet ($\pm 2,000$ SF) for AC. A sample unit is the smallest subdivision of a pavement network and is analyzed during field assessments to establish condition ratings.

2.5.5 Terminology Summary

Below is a summary table, **Table 2.5.5**, with definitions and examples of common SAPMP terminology.

Table 2.5.5: SAPMP Terminology

SAPMP Terminology	Common Definition	Airport Example
Network	Totality of pavement assets maintained by the Airport.	"Tallahassee International Airport – Airfield Pavements"
Branch Name	Commonly defined asset name as established by Airport and by use.	"Runway 18-36"
Branch ID	Codified shorthand name for commonly defined asset established for database identification.	"RW 18-36" RW, Branch Use, "Runway" "Runway 18-36", Runway Facility
Section ID	Codified identification for pavement asset that is distinct by pavement composition, work history, aircraft loading, or condition.	"6105"
Sample Unit	A numeric identification of an area of pavement (5,000 \pm 2,000 SF of AC or 20 \pm 8 slabs of PCC) that has been inspected in accordance with ASTM D5340-20.	"300"

2.6 Airfield PCI Survey Methodology

In adherence to the FAA AC 150/5380-7B, the FDOT SAPMP utilizes the PCI survey method to collect pavement distress data and analyze the condition. The PCI survey procedure is a visual statistical sampling of pavements for recording primary distress types (e.g., cracking and deformation), associated severities, and quantities as defined by the ASTM D5340-20. This effort is the primary means of obtaining and recording pavement distress data. The PCI survey consists primarily of visual assessments of pavement surfaces for signs of distress and deterioration resulting from loading (aircraft) and environmental influences.

Overall, a visual pavement condition survey provides an indication of the cause and rate of deterioration of a pavement section from a functional point of view and can help identify if any underlying structural deficiencies are present. Although a visual PCI survey does not predict the remaining structural life of a pavement section or its ability to support loads, it does assess the rating of the operational surface. Functional condition, determined by the PCI method, can provide a cost-effective means to plan for pavement rehabilitation projects. Timely application of pavement rehabilitation may lead to the extension of functional life of individual pavement sections. This method varies from structural evaluation; functional condition is limited to visually observed distresses and indicative modes of pavement deterioration. A formal structural evaluation analyzes subsurface conditions, material characteristics, and qualitative pavement structure attributes. A structural evaluation may consist of subsurface geotechnical exploration, falling weight deflectometer testing, petrographic testing, material coring, and/or flexural testing.

2.6.1 Pavement Distress Types

For each sample, the severity and quantity of defined distresses are recorded and then analyzed in accordance with the ASTM D5340-20 standard, which identifies 17 AC distress types and 16 PCC distress types. **Tables 2.6.1 (a)** and **2.6.1 (b)** identify these distresses and their common causes or mechanisms.

Table 2.6.1 (a): Pavement Distress Types – Asphalt Concrete

Distress Mechanism	Distress Type
Load	Alligator Cracking Rutting
Climate/Durability	Block Cracking Joint Reflection Cracking Longitudinal and Transverse Cracking (LT) Raveling Shoving Weathering
Construction/Material	Bleeding Corrugation Depression Polished Aggregate Slippage Cracking Swelling
Other	Jet Blast Erosion Oil Spillage Patching and Utility Cut Patching

Table 2.6.1 (b): Pavement Distress Types – Portland Cement Concrete

Distress Mechanism	Distress Type
Load	Corner Break Longitudinal, Transverse, and Diagonal Cracking (LTD) Pumping Shattered Slab/Intersecting Cracks
Climate/Durability	Blowup Durability "D" Cracking Joint Seal Damage Popouts
Construction/Material	Alkali Silica Reaction (ASR) Scaling Shrinkage Cracking
Other	Corner Spalling Joint Spalling Large Patching and Utility Cut Settlement or Faulting Small Patching

2.6.2 PCI Survey Procedures

PCI surveys are conducted on sample units defined in previous System Updates. Sample units are subject to change at the discretion of field personnel and/or to major pavement rehabilitation treatments. Furthermore, access to sample units based on accessibility or operational impacts may affect the overall sampling rate effort at each airport. **Tables 2.6.2 (a) and (b)** define the sampling criteria used by the FDOT SAPMP. A higher sampling rate may be utilized to achieve greater statistical confidence, should the Airport have the available resources to perform PCI survey independent of the FDOT SAPMP.


Table 2.6.2 (a): Recommended Sampling Rates for Asphalt Concrete

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 4	1	1
5 - 10	2	1
11 - 15	3	2
16 - 30	5	3
31 - 40	7	4
41 - 50	8	5
51 or more	20% but ≤ 20	10% but ≤ 10


Table 2.6.2 (b): Recommended Sampling Rates for Portland Cement Concrete

Number of Total Sample Units in Section	Runway Sampling Rate	Taxiways, Aprons, and Others Sampling Rate
1 - 3	1	1
4 - 6	2	1
7 - 10	3	2
11 - 15	4	2
16 - 20	5	3
21 - 30	7	3
31 - 40	8	4
41 - 50	10	5
51 or more	20% but ≤ 20	10% but ≤ 10

The FDOT SAPMP is limited to select sample units for each section identified in each airport's Airfield Pavement Network Definition. The intent is to perform a limited amount of sample unit PCI surveys to reasonably reflect the functional condition. Due to the limited sampling criteria, there may be instances of pavement distress and deterioration outside of the inspected sample units that were not observed.



Chapter 3: Airfield Pavement System Inventory



Chapter 3 – Airfield Pavement System Inventory

This chapter discusses the inventory data collected from the Airport and summarizes network-level characteristics of the Airport's airfield pavements. At the start of each FDOT SAPMP System Update, all airports are asked to review the existing Airfield Pavement Network Definition Exhibit for accuracy. Furthermore, participating airports are asked to provide documentation of any recent or anticipated construction related to their airfield pavements.

3.1 Airfield Pavement Network Information

3.1.1 Previous and/or Anticipated Airfield Pavement Construction

Based on information provided by the Airport, **Table 3.1.1** summarizes recent or anticipated airfield pavement construction projects since 2017.

Table 3.1.1: Summary of Previous and/or Anticipated Airfield Pavement Construction


Construction Year	Location	Work Type / Pavement Section
2017	AP	Mill and Overlay 1" Mill, Variable Depth P-401 Overlay
	AP MID, TW B	Complete Reconstruction - AC 4" P-401, 6" MIN P-220
	RW 13-31, TW D	New Construction - AC 4" P-401, 8" P-211
	TW B	Complete Reconstruction - AC 4" P-401, 8" P-211
	TW D, TW F	Complete Reconstruction - AC 4" P-401, 8" P-210
2018	AP	Complete Reconstruction - AC 4" P-401, 6" MIN P-219
	TL T-HANG	New Construction - AC 2" F-334 SURFACE COURSE, OVER 6" P-211
2020	TW D	New Construction - AC
2021	TW E	New Construction - AC 4" P-401, 8" P-211, 12" P-152

The Airport provided a combination of record drawings, reports, and staff input, which aided in developing the construction history of the Airport's pavements since inception. Major rehabilitation and construction activities performed in the last 24 months, or anticipated in the next 24 months, are assumed to restore the PCI to 100. These activities include pavement overlay, mill and overlay, new construction, and/or complete reconstruction. These pavements were not formally subject to a PCI assessment and actual conditions may vary. Furthermore, any localized maintenance or repair performed in the assessment areas that would improve the PCI are considered in the condition analysis.

Figure 3.1.1 (a), the Airfield Pavement Network Definition Exhibit, provides details of the PCI assessment efforts. The Exhibit identifies pavement facilities, surface types, section definitions, and sample unit delineations. **Figure 3.1.1 (b)**, the Airfield Pavement System Inventory Exhibit, provides details of the work history updates communicated by the Airport. The Exhibit provides the approximate limits of recent and/or anticipated construction on the airfield pavement facilities. The limits are based on documentation provided by the Airport and, if constructed, are confirmed during field surveys.



AAC RW 13-31 6135 2 6	AC TW B 220 2 12	AC TW B 235 1 4	AC TW C 315 3 21	AC TW D 410 1 4
AC TW D 420 0 21	AC TW E 510 2 2	AC TW E 515 1 5	AC TL T-HANG 605 1 4	AC TL T-HANG 610 1 9
AC TL T-HANG 620 3 20	AC TL T-HANG 705 1 8	AC TL T-HANG 708 1 3	AC TL T-HANG 710 2 11	AC TL T-HANG 715 1 4
AC TL T-HANG 720 1 1	AC TL T-HANG 725 1 5	AAC TL T-HANG 730 1 5	AC TL T-HANG 735 1 5	AC AP MID 4405 5 35




LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID
- AAC — PAVEMENT SURFACE TYPE
- AP MAIN — PAVEMENT BRANCH ID
- 4105 — SECTION NUMBER
- 10 | 100 — NUMBER OF SAMPLE UNITS IN SECTION
NUMBER OF SAMPLE UNITS TO BE INSPECTED
- AAC
AP MAIN
4105
0 | 100 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100 — INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 138
AC: 134 PCC: 4

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2017	AP	Mill and Overlay 1" Mill, Variable Depth P-401 Overlay
	AP MID, TW B	Complete Reconstruction - AC 4" P-401, 6" MIN P-220
	RW 13-31, TW D	New Construction - AC 4" P-401, 8" P-211
	TW B	Complete Reconstruction - AC 4" P-401, 8" P-211
2018	TW D, TW F	Complete Reconstruction - AC 4" P-401, 8" P-210
	AP	Complete Reconstruction - AC 4" P-401, 6" MIN P-219
2020	TL T-HANG	New Construction - AC 2" F-334 SURFACE COURSE, OVER 6" P-211
2021	TW D	New Construction - AC
2021	TW E	New Construction - AC 4" P-401, 8" P-211, 12" P-152

LEGEND

TYPICAL RUNWAY BRANCH ID
 TYPICAL TAXIWAY BRANCH ID
 TYPICAL APRON BRANCH ID


PROJECT YEAR


RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

3.1.2 Estimated Pavement Age

Standard pavement design practice considers a design life of 20 years. Design inputs typically require subgrade soil conditions, pavement layer material characteristics, and anticipated loading (aircraft fleet mix) for the design-life period. Based on the review of historic airfield pavement construction activities, **Figure 3.1.2 (a)** summarizes the age of the pavement sections since the last major construction activity has occurred. **Figure 3.1.2 (b)** provides the approximate limits of those age ranges on the airfield pavement facilities. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report. The estimation of pavement age is based on information requested from the Airport.

Figure 3.1.2 (a): Age of Pavements at PCI Survey





LEGEND

RW 13-31 — TYPICAL RUNWAY BRANCH ID
TW A — TYPICAL TAXIWAY BRANCH ID
AP S — TYPICAL APRON BRANCH ID

AGE AT INSPECTION


	0-5 Years
	6-10 Years
	11-15 Years
	16-20 Years
	> 20 Years

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

3.1.3 Functional Use

Pavements are subject to variations in aircraft loading patterns based on use and overall operations. This is termed “functional use” or “branch use.” For this SAPMP System Update, the following categories of pavement functional use are identified: runway, taxiway, taxilane, and apron. **Figure 3.1.3** summarizes pavement functional use by area and excludes paved shoulders.

Figure 3.1.3: Airfield Pavement Branch Use by Area (SF)




3.1.4 Pavement Surface Type

The airfield pavement facility surface types within the SAPMP include four (4) common types of pavement: Asphalt Concrete (AC), Asphalt Concrete overlaid on Asphalt Concrete (AAC), Asphalt Concrete overlaid on Portland cement concrete (APC), and Portland cement concrete (PCC).

Based on the record documentation incorporated within the SAPMP database and as observed during airfield pavement field assessments, pavement surface types have been assigned to the various pavement sections. **Figure 3.1.4** summarizes the applicable pavement types observed at VNC.

Figure 3.1.4: Airfield Pavement Surface Type by Area (SF)



3.1.5 Pavement System Inventory Details

The pavement inventory scope includes updates to existing pavement geometry and the development of an AutoCAD model with spatial projection for use within GIS. **Appendix C** includes the Airfield Pavement Network Definition Exhibit and the Airfield Pavement System Inventory Exhibit, which visually summarize the results of the airfield pavement system inventory analysis.

Table 3.1.5 displays the section-level pavement inventory data, which is based on record documentation provided by the airports and from previous System Updates. The information presented relies on the accuracy and the adequacy of data provided. In some cases, characteristics such as pavement area may be estimated based on aerial interpretation of spatially-projected imagery. Additionally, if the last construction date is unknown, a date of January 1 of the estimated year was assigned to the section. The accuracy of data is appropriate for this network-level planning document. Should the Airport perform rehabilitation work, it is recommended that project-level investigations be performed to support the data accuracy needed for design and construction.

Table 3.1.5: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
VNC	RW 5-23	Runway	6205	255,000	AC	1/1/2013
VNC	RW 5-23	Runway	6210	382,500	AAC	1/1/2013
VNC	RW 5-23	Runway	6215	18,000	AC	1/1/2013
VNC	RW 5-23	Runway	6220	27,000	AC	1/1/2013
VNC	RW 5-23	Runway	6225	18,000	AC	1/1/2013
VNC	RW 5-23	Runway	6230	27,000	AC	1/1/2013
VNC	RW 13-31	Runway	6105	413,900	AAC	12/1/2006
VNC	RW 13-31	Runway	6110	196,950	AAC	12/1/2006
VNC	RW 13-31	Runway	6115	30,000	APC	12/1/2006

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
VNC	RW 13-31	Runway	6120	20,000	APC	12/1/2006
VNC	RW 13-31	Runway	6125	30,000	APC	12/1/2006
VNC	RW 13-31	Runway	6130	20,000	APC	12/1/2006
VNC	RW 13-31	Runway	6135	26,100	AAC	1/1/2013
VNC	RW 13-31	Runway	6140	13,050	AAC	1/1/2013
VNC	RW 13-31	Runway	6145	63,850	AC	5/9/2017
VNC	RW 13-31	Runway	6150	31,925	AC	5/9/2017
VNC	TW A	Taxiway	105	55,145	AC	1/1/2015
VNC	TW A	Taxiway	110	55,883	AC	1/1/2015
VNC	TW A	Taxiway	115	52,281	AC	1/1/2015
VNC	TW A	Taxiway	120	9,988	AC	1/1/2013
VNC	TW A	Taxiway	125	5,738	AAC	12/1/2006
VNC	TW B	Taxiway	220	47,695	AC	1/1/2017
VNC	TW B	Taxiway	225	12,448	AC	1/1/2013
VNC	TW B	Taxiway	235	21,767	AC	5/9/2017
VNC	TW C	Taxiway	315	85,087	AC	1/1/2015
VNC	TW D	Taxiway	400	38,598	AC	5/9/2017
VNC	TW D	Taxiway	405	76,359	AC	5/9/2017
VNC	TW D	Taxiway	410	17,828	AC	1/1/2013
VNC	TW D	Taxiway	420	109,579	AC	1/1/2020
VNC	TW E	Taxiway	505	62,102	AC	1/1/2013
VNC	TW E	Taxiway	510	10,168	AC	1/1/2013
VNC	TW E	Taxiway	515	21,560	AC	1/1/2015
VNC	TW E	Taxiway	520	110,616	AC	10/1/2021
VNC	TW E	Taxiway	550	9,260	AC	1/1/2013
VNC	TW F	Taxiway	450	11,675	AC	5/9/2017
VNC	TL T-HANG	Taxilane	605	16,734	AC	1/1/2003
VNC	TL T-HANG	Taxilane	610	42,622	AC	1/1/2003
VNC	TL T-HANG	Taxilane	620	100,062	AC	12/25/1994
VNC	TL T-HANG	Taxilane	705	34,474	AC	1/1/2003
VNC	TL T-HANG	Taxilane	708	11,446	AC	12/25/1997
VNC	TL T-HANG	Taxilane	710	41,684	AC	12/25/1994
VNC	TL T-HANG	Taxilane	715	12,768	AC	1/1/2012
VNC	TL T-HANG	Taxilane	720	5,422	AC	1/1/2012
VNC	TL T-HANG	Taxilane	725	17,209	AC	1/1/2012
VNC	TL T-HANG	Taxilane	730	18,001	AAC	11/1/2013
VNC	TL T-HANG	Taxilane	735	21,329	AC	1/1/2018
VNC	AP	Apron	4105	112,335	PCC	1/1/1942
VNC	AP	Apron	4110	302,352	AC	1/1/2018
VNC	AP	Apron	4115	34,307	PCC	12/25/1999
VNC	AP	Apron	4120	58,790	AC	1/1/2018
VNC	AP	Apron	4125	53,176	AC	1/1/2015
VNC	AP	Apron	4127	19,630	AAC	1/1/2017
VNC	AP	Apron	4130	6,119	AC	1/1/2015
VNC	AP	Apron	4140	73,498	AC	1/1/2015
VNC	AP MID	Apron	4405	166,523	AC	1/1/2017
VNC	AP RU 13	Apron	5110	19,846	AC	1/1/2015
VNC	AP RU 23	Apron	5105	26,551	AC	1/1/2015



Chapter 4: Airfield Pavement Condition Analysis



Chapter 4 – Airfield Pavement Condition Analysis


The Pavement Condition Index (PCI) provides insight to possible causes of deterioration to help support pavement maintenance and rehabilitation planning. Distress type, severity, and extent are required in the computation of a PCI value. The PCI method of pavement condition evaluation is strictly a visual review of surface condition, also referred to as a functional evaluation. Further evaluation of pavement conditions may be necessary, such as structural evaluation, for design-and/or project-level determination of pavement rehabilitation needs.

4.1 Airfield Pavement Condition Index

4.1.1 Network-Level Analysis

The following figure, **Figure 4.1.1**, summarizes the network-level pavement condition analysis based on the most recent survey results. On a network level, approximately 87% of inspected pavements are in Good or Satisfactory condition. Presently, roughly 5% of inspected pavements are in Fair condition and the remaining 8% of inspected pavements are in Poor or worse condition.

Figure 4.1.1: Current Condition – Overall Network



4.1.2 Branch-Level Analysis

The following **Figures 4.1.2 (a)-(e)** summarize branch-level pavement conditions according to the most recent PCI assessment results.

Figure 4.1.2 (a): Current Condition Summary – Branch-Level




Figure 4.1.2 (b): Current Condition – Runway




Figure 4.1.2 (c): Current Condition – Taxiway




Figure 4.1.2 (d): Current Condition – Taxi lane




Figure 4.1.2 (e): Current Condition – Apron



Table 4.1.2 details the branch-level condition for each airfield pavement branch.

Table 4.1.2: Current Condition Summary – Branch-Level

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
RW 5-23	Runway	6	727,500	87	Good
RW 13-31	Runway	10	845,775	73	Satisfactory
TW A	Taxiway	5	179,035	88	Good
TW B	Taxiway	3	81,910	93	Good
TW C	Taxiway	1	85,087	93	Good
TW D	Taxiway	4	242,364	96	Good
TW E	Taxiway	5	213,706	94	Good
TW F	Taxiway	1	11,675	94	Good
TL T-HANG	Taxilane	11	321,751	65	Fair
AP	Apron	8	660,207	75	Satisfactory
AP MID	Apron	1	166,523	94	Good
AP RU 13	Apron	1	19,846	91	Good
AP RU 23	Apron	1	26,551	93	Good

4.1.3 Section-Level Analysis

Table 4.1.3 provides each pavement section's area-weighted average PCI and the percent of distress related to load, climate, and other factors. The causes of condition deterioration help inform maintenance, repair, and rehabilitation decisions. For example, load-related distress can indicate that the pavement is reaching the end of its structural design life and the selected rehabilitation treatment should include either strengthening or reconstruction. **Figure 4.1.3** provides a technical exhibit that graphically depicts PCI values and ratings determined from this SAPMP System Update.


Pavement facilities that have been reconstructed within the past 24 months, or are anticipated for reconstruction within the next 24 months, may have been omitted from this assessment. Pavement that has received major rehabilitation will be set to a PCI of 100 for this analysis.

Table 4.1.3: Latest Pavement Condition Index Summary – Section-Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
VNC	RW 5-23	Runway	6205	255,000	AC	85	Satisfactory	100	0	0	8	44
VNC	RW 5-23	Runway	6210	382,500	AAC	88	Good	100	0	0	17	84
VNC	RW 5-23	Runway	6215	18,000	AC	85	Satisfactory	100	0	0	1	3
VNC	RW 5-23	Runway	6220	27,000	AC	91	Good	100	0	0	2	6
VNC	RW 5-23	Runway	6225	18,000	AC	85	Satisfactory	100	0	0	1	3
VNC	RW 5-23	Runway	6230	27,000	AC	92	Good	100	0	0	2	6
VNC	RW 13-31	Runway	6105	413,900	AAC	71	Satisfactory	99	0	1	17	82
VNC	RW 13-31	Runway	6110	196,950	AAC	71	Satisfactory	91	0	9	8	40
VNC	RW 13-31	Runway	6115	30,000	APC	65	Fair	100	0	0	2	6
VNC	RW 13-31	Runway	6120	20,000	APC	61	Fair	100	0	0	1	4
VNC	RW 13-31	Runway	6125	30,000	APC	65	Fair	100	0	0	2	6
VNC	RW 13-31	Runway	6130	20,000	APC	60	Fair	100	0	0	1	4
VNC	RW 13-31	Runway	6135	26,100	AAC	85	Satisfactory	100	0	0	2	6
VNC	RW 13-31	Runway	6140	13,050	AAC	85	Satisfactory	100	0	0	1	4
VNC	RW 13-31	Runway	6145	63,850	AC	91	Good	100	0	0	3	13
VNC	RW 13-31	Runway	6150	31,925	AC	94	Good	100	0	0	2	6
VNC	TW A	Taxiway	105	55,145	AC	93	Good	100	0	0	2	14
VNC	TW A	Taxiway	110	55,883	AC	84	Satisfactory	100	0	0	3	16
VNC	TW A	Taxiway	115	52,281	AC	90	Good	100	0	0	3	12
VNC	TW A	Taxiway	120	9,988	AC	80	Satisfactory	100	0	0	1	2
VNC	TW A	Taxiway	125	5,738	AAC	66	Fair	88	0	12	1	1
VNC	TW B	Taxiway	220	47,695	AC	94	Good	100	0	0	2	12
VNC	TW B	Taxiway	225	12,448	AC	89	Good	100	0	0	1	3
VNC	TW B	Taxiway	235	21,767	AC	94	Good	100	0	0	1	4
VNC	TW C	Taxiway	315	85,087	AC	93	Good	100	0	0	3	21
VNC	TW D	Taxiway	400	38,598	AC	94	Good	100	0	0	1	7
VNC	TW D	Taxiway	405	76,359	AC	94	Good	100	0	0	2	13
VNC	TW D	Taxiway	410	17,828	AC	88	Good	100	0	0	1	4
VNC	TW D	Taxiway	420	109,579	AC	100	Good	0	0	0	0	0
VNC	TW E	Taxiway	505	62,102	AC	87	Good	100	0	0	3	17
VNC	TW E	Taxiway	510	10,168	AC	85	Satisfactory	100	0	0	2	2
VNC	TW E	Taxiway	515	21,560	AC	91	Good	100	0	0	1	5
VNC	TW E	Taxiway	520	110,616	AC	100	Good	0	0	0	0	0
VNC	TW E	Taxiway	550	9,260	AC	80	Satisfactory	100	0	0	1	2
VNC	TW F	Taxiway	450	11,675	AC	94	Good	100	0	0	1	3
VNC	TL T-HANG	Taxilane	605	16,734	AC	69	Fair	100	0	0	1	4
VNC	TL T-HANG	Taxilane	610	42,622	AC	66	Fair	91	0	9	1	9
VNC	TL T-HANG	Taxilane	620	100,062	AC	52	Poor	86	8	6	3	20
VNC	TL T-HANG	Taxilane	705	34,474	AC	78	Satisfactory	100	0	0	1	8
VNC	TL T-HANG	Taxilane	708	11,446	AC	67	Fair	96	0	4	1	3
VNC	TL T-HANG	Taxilane	710	41,684	AC	46	Poor	91	9	0	2	11
VNC	TL T-HANG	Taxilane	715	12,768	AC	89	Good	100	0	0	1	4
VNC	TL T-HANG	Taxilane	720	5,422	AC	89	Good	100	0	0	1	1

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
VNC	TL T-HANG	Taxilane	725	17,209	AC	92	Good	100	0	0	1	5
VNC	TL T-HANG	Taxilane	730	18,001	AAC	59	Fair	100	0	0	1	5
VNC	TL T-HANG	Taxilane	735	21,329	AC	94	Good	100	0	0	1	5
VNC	AP	Apron	4105	112,335	PCC	21	Serious	9	63	28	3	24
VNC	AP	Apron	4110	302,352	AC	92	Good	81	0	19	6	60
VNC	AP	Apron	4115	34,307	PCC	4	Failed	6	61	33	1	6
VNC	AP	Apron	4120	58,790	AC	93	Good	100	0	0	2	12
VNC	AP	Apron	4125	53,176	AC	89	Good	100	0	0	2	13
VNC	AP	Apron	4127	19,630	AAC	89	Good	100	0	0	1	4
VNC	AP	Apron	4130	6,119	AC	94	Good	100	0	0	1	2
VNC	AP	Apron	4140	73,498	AC	90	Good	100	0	0	2	15
VNC	AP MID	Apron	4405	166,523	AC	94	Good	100	0	0	5	35
VNC	AP RU 13	Apron	5110	19,846	AC	91	Good	100	0	0	1	4
VNC	AP RU 23	Apron	5105	26,551	AC	93	Good	100	0	0	1	6

* Zero (0) Sample Units Inspected signifies that the pavement section was not inspected during this SAPMP System Update due to recent construction projects. These sections correlate with the gray sections on the Network Definition Exhibit.



LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID

2022 PAVEMENT CONDITION INDEX

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

"SECTION ID"
"PCI VALUE"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.

4.2 Summary of Pavement Condition Evaluation Results

4.2.1 Network-Level Observations

The PCI assessment for Venice Municipal Airport (VNC) was performed in May 2022. The overall area-weighted average PCI value of the network was 81, representing a condition rating of Satisfactory. Portions of Taxiway D and Taxiway E were not inspected due to their recent construction in 2020 and 2021.

Based on the FAA 5010 Report as of 11/03/2022, the Airport has reported 60,834 operations for 12 months ending 10/12/2018.

4.2.2 Branch-Level Observations


The following branch-level observations are a summary of select pavement facilities identified during the PCI assessment, including a discussion of general conditions and branch characteristics. The summary may not include all branches and/or sections within the Airport's airfield pavement network. Representative distress photographs of airfield pavements are presented in **Appendix D**. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Re-inspection Report found in **Appendix E** provides listings of each sample unit and distress.

Runways

RW 5-23

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 5-23	RUNWAY	6	727,500	87	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 60% Good (86-100 PCI), 40% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6205	AC	255,000	85	Satisfactory
6210	AAC	382,500	88	Good
6215	AC	18,000	85	Satisfactory
6220	AC	27,000	91	Good
6225	AC	18,000	85	Satisfactory
6230	AC	27,000	92	Good

RW 5-23 consists of 6 flexible pavement sections, totaling 727,500 sf. The last major construction date for the branch was 2013, resulting in an area-weighted average age at inspection of 9 years old. Overall, RW 5-23 is in Good condition with an area-weighted average PCI of 87.

RW 13-31

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 13-31	RUNWAY	10	845,775	73	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 11% Good (86-100 PCI), 77% Satisfactory (71-85 PCI), 12% Fair (56-70 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
6105	AAC	413,900	71	Satisfactory
6110	AAC	196,950	71	Satisfactory
6115	APC	30,000	65	Fair
6120	APC	20,000	61	Fair
6125	APC	30,000	65	Fair
6130	APC	20,000	60	Fair
6135	AAC	26,100	85	Satisfactory
6140	AAC	13,050	85	Satisfactory
6145	AC	63,850	91	Good
6150	AC	31,925	94	Good


RW 13-31 consists of 10 flexible pavement sections, totaling 845,775 sf. The last major construction dates range from 2006 to 2017, resulting in an area-weighted average age at inspection of 14 years old. Overall, RW 13-31 is in Satisfactory condition with an area-weighted average PCI of 73.

Taxiways

TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	5	179,035	88	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 60% Good (86-100 PCI), 37% Satisfactory (71-85 PCI), 3% Fair (56-70 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
105	AC	55,145	93	Good
110	AC	55,883	84	Satisfactory
115	AC	52,281	90	Good
120	AC	9,988	80	Satisfactory
125	AAC	5,738	66	Fair

TW A consists of 5 flexible pavement sections, totaling 179,035 sf. The last major construction dates range from 2006 to 2015, resulting in an area-weighted average age at inspection of 8 years old. Overall, TW A is in Good condition with an area-weighted average PCI of 88.

TW C

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW C	TAXIWAY	1	85,087	93	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
315	AC	85,087	93	Good

TW C consists of 1 flexible pavement section, totaling 85,087 sf. The last major construction date for the branch was 2015, resulting in an area-weighted average age at inspection of 7 years old. Overall, TW C is in Good condition with an area-weighted average PCI of 93.

TW D

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW D	TAXIWAY	4	242,364	96	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
400	AC	38,598	94	Good
405	AC	76,359	94	Good
410	AC	17,828	88	Good
420	AC	109,579	100	Good

TW D consists of 4 flexible pavement sections, totaling 242,364 sf. The last major construction dates range from 2013 to 2020, resulting in an area-weighted average age at inspection of 3 years old. Overall, TW D is in Good condition with an area-weighted average PCI of 96.

TW E

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW E	TAXIWAY	5	213,706	94	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 91% Good (86-100 PCI), 9% Satisfactory (71-85 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
505	AC	62,102	87	Good
510	AC	10,168	85	Satisfactory
515	AC	21,560	91	Good
520	AC	110,616	100	Good
550	AC	9,260	80	Satisfactory

TW E consists of 5 flexible pavement sections, totaling 213,706 sf. The last major construction dates range from 2013 to 2021, resulting in an area-weighted average age at inspection of 4 years old. Overall, TW E is in Good condition with an area-weighted average PCI of 94.

TW F

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW F	TAXIWAY	1	11,675	94	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
450	AC	11,675	94	Good

TW F consists of 1 flexible pavement section, totaling 11,675 sf. The last major construction date for the branch was 2017, resulting in an area-weighted average age at inspection of 5 years old. Overall, TW F is in Good condition with an area-weighted average PCI of 94.


Taxilanes

TL T-HANG

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL T-HANG	TAXILANE	11	321,751	65	Fair

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the

subsequent table, the distribution is as follows: 18% Good (86-100 PCI), 11% Satisfactory (71-85 PCI), 27% Fair (56-70 PCI), 44% Poor (41-55 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
605	AC	16,734	69	Fair
610	AC	42,622	66	Fair
620	AC	100,062	52	Poor
705	AC	34,474	78	Satisfactory
708	AC	11,446	67	Fair
710	AC	41,684	46	Poor
715	AC	12,768	89	Good
720	AC	5,422	89	Good
725	AC	17,209	92	Good
730	AAC	18,001	59	Fair
735	AC	21,329	94	Good

TL T-HANG consists of 11 flexible pavement sections, totaling 321,751 sf. The last major construction dates range from 1994 to 2018, resulting in an area-weighted average age at inspection of 21 years old. Overall, TL T-HANG is in Fair condition with an area-weighted average PCI of 65.

Aprons

AP

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP	APRON	8	660,207	75	Satisfactory

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 78% Good (86-100 PCI), 17% Serious (11-25 PCI), 5% Failed (0-10 PCI).




Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4105	PCC	112,335	21	Serious
4110	AC	302,352	92	Good
4115	PCC	34,307	4	Failed
4120	AC	58,790	93	Good
4125	AC	53,176	89	Good
4127	AAC	19,630	89	Good
4130	AC	6,119	94	Good
4140	AC	73,498	90	Good

AP consists of 6 flexible and 2 rigid pavement sections, totaling 660,207 sf. The last major construction dates range from 1942 to 2018, resulting in an area-weighted average age at inspection of 19 years old. Overall, AP is in Satisfactory condition with an area-weighted average PCI of 75.

AP MID

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP MID	APRON	1	166,523	94	Good

The following bar graph shows proportional distribution (as % of area within branch) of condition categories among sections within the branch. Given the individual section data shown in the subsequent table, the distribution is as follows: 100% Good (86-100 PCI).



Section ID	Surface Type	Section Area (SF)	PCI	Condition Rating
4405	AC	166,523	94	Good

AP MID consists of 1 flexible pavement section, totaling 166,523 sf. The last major construction date for the branch was 2017, resulting in an area-weighted average age at inspection of 5 years old. Overall, AP MID is in Good condition with an area-weighted average PCI of 94.



Chapter 5: SAPMP Customization



Chapter 5 – SAPMP Customization

Once the PAVER™ database is populated with inventory and condition data (including PCI and rank), it is further customized with key elements such as network-level attributes, performance models, critical PCI, maintenance policies, and unit costs that are specific to the FDOT SAPMP. Each of these factors play a role in the development of rehabilitation strategies as they help to identify maintenance and rehabilitation needs for long-term management.

The FDOT SAPMP is organized to provide airports with planning-level data and does not intend to preclude the responsible engineer from performing the appropriate level of investigation and analysis in determining the appropriate design details of a pavement rehabilitation. It would not be advisable to solely base design-level rehabilitation without the appropriate level of investigation and determination of pavement deterioration beyond that of a visual functional condition assessment.

5.1 Network-Level Customization

The network-level attribute fields used in the FDOT SAPMP PAVER™ database consist of the Network, Airport Classification, District, FAA ADO Area, Inspection Phase, and Continuing Florida Aviation System Planning Process (CFASPP) Center. Each of these elements are briefly defined below.

- » The “Network” field identifies the airport being analyzed;
- » The “Airport Classification” field classifies the Airport according to the type and volume of aircraft traffic;
 - “GA” for General Aviation, community airports
 - “RL” for Regional Relievers
 - “PR” for Primary/Commercial airports
- » The “District” field identifies the FDOT District to which the Airport belongs;
- » The “FAA ADO Area” is an area used by the Orlando ADO to assign airports within those areas to the responsible FAA ADO personnel (planners, engineers, and environmentalists);
- » The “Inspection Phase” denotes which phase of the SAPMP the Airport is surveyed (Phase 1 or Phase 2); and
- » The “CFASPP Center” identifies which Region or Metropolitan Area of the Continuing Florida Aviation Systems Planning Process an Airport falls within.

5.2 Pavement Condition Forecasts

Pavement performance models, alternatively known as forecast models, prediction curves, or family curves, are developed from past and current distress data, as well as age data. These prediction curves are used to develop forecasts of PCI values that then help determine optimum timing for pavement maintenance and rehabilitation.

5.2.1 Forecasting PCI Considerations

Performance models will continue to be refined as the FDOT updates the SAPMP with subsequent PCI surveys. With the refinement of additional PCI and age data points, the forecasting of pavement conditions will continue to better reflect the performance trends of airfield pavements in the FAS. As a reminder, forecasting of pavement condition for the Airport is intended for planning purposes only. **The estimation of forecasted PCI values gives no assurance of future pavement conditions as PCI values represent an engineering estimation to be used as a planning tool. Forecasted PCI data should not be the sole metric for determining the year in which a project should be planned. Design-level planning should be undertaken by the responsible engineer prior to the development of airfield design plans.** Design-level recommendations for pavement rehabilitation and/or reconstruction will require the appropriate application of the procedures defined in the FAA AC 150/5320-6F.


5.2.2 Performance Models

To develop pavement performance models, data for each section is combined into “groups” or “families” according to pavement type, traffic, and functional use. For the FDOT SAPMP, the models were defined for both PCC- and AC-surfaced pavements and further divided according to functional use. Based on average deterioration rates for different pavement types, each pavement section is assigned to a specific deterioration family to forecast the condition over a 10-year period.

5.2.3 Branch-Level Pavement Condition Forecast

Figure 5.2.3 depicts the branch-level pavement condition forecast for each branch use (Runway, Taxiway, Taxilane, and/or Apron) as well as the overall network. The condition forecasts are for a 10-year duration, starting in 2023 through 2032.

Figure 5.2.3: Forecasted Branch-Level Pavement Performance



5.2.4 Section-Level Pavement Condition Forecast

Table 5.2.4 provides section-level details for PCI forecasts. Pavement condition forecasts should be used for planning purposes only, as actual condition of sections is subject to the sensitivities in changes of traffic and maintenance frequency.

Table 5.2.4: Forecasted PCI Values 2023-2032 – Section-Level


Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
VNC	RW 5-23	6205	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6210	88	86	84	83	81	79	77	76	74	72	70
VNC	RW 5-23	6215	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6220	91	89	86	84	83	81	79	78	77	75	74
VNC	RW 5-23	6225	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6230	92	89	87	85	83	82	80	79	77	76	75
VNC	RW 13-31	6105	71	69	67	66	64	62	60	59	57	55	53
VNC	RW 13-31	6110	71	69	67	66	64	62	60	59	57	55	53
VNC	RW 13-31	6115	65	63	61	60	58	56	54	53	51	49	47
VNC	RW 13-31	6120	61	59	57	56	54	52	50	49	47	45	43
VNC	RW 13-31	6125	65	63	61	60	58	56	54	53	51	49	47
VNC	RW 13-31	6130	60	58	56	55	53	51	49	48	46	44	42
VNC	RW 13-31	6135	85	83	81	80	78	76	74	73	71	69	67
VNC	RW 13-31	6140	85	83	81	80	78	76	74	73	71	69	67
VNC	RW 13-31	6145	91	89	86	84	83	81	79	78	77	75	74
VNC	RW 13-31	6150	94	91	89	87	85	83	81	80	78	77	76
VNC	TW A	105	93	91	89	87	85	83	82	80	78	77	76
VNC	TW A	110	84	82	81	79	78	76	75	74	72	71	70
VNC	TW A	115	90	88	86	84	82	81	79	78	76	75	74
VNC	TW A	120	80	78	77	76	74	73	72	71	70	69	68
VNC	TW A	125	66	65	64	63	62	61	61	60	59	58	58
VNC	TW B	220	94	92	90	88	86	84	82	81	79	78	76
VNC	TW B	225	89	87	85	83	82	80	78	77	76	74	73
VNC	TW B	235	94	92	90	88	86	84	82	81	79	78	76
VNC	TW C	315	93	91	89	87	85	83	82	80	78	77	76
VNC	TW D	400	94	92	90	88	86	84	82	81	79	78	76
VNC	TW D	405	94	92	90	88	86	84	82	81	79	78	76
VNC	TW D	410	88	86	84	82	81	79	78	76	75	74	73
VNC	TW D	420	100	92	90	88	86	84	83	81	79	78	76
VNC	TW E	505	87	85	83	82	80	78	77	76	74	73	72
VNC	TW E	510	85	83	81	80	78	77	76	74	73	72	71
VNC	TW E	515	91	89	87	85	83	82	80	78	77	76	74
VNC	TW E	520	100	96	94	92	89	88	86	84	82	81	79
VNC	TW E	550	80	78	77	76	74	73	72	71	70	69	68
VNC	TW F	450	94	92	90	88	86	84	82	81	79	78	76
VNC	TL T-HANG	605	69	68	67	66	65	65	64	63	63	62	61
VNC	TL T-HANG	610	66	65	64	64	63	62	62	61	61	60	60
VNC	TL T-HANG	620	52	51	51	50	50	49	48	48	47	46	45
VNC	TL T-HANG	705	78	76	75	74	73	71	70	69	68	67	67

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
VNC	TL T-HANG	708	67	66	65	65	64	63	63	62	61	61	60
VNC	TL T-HANG	710	46	45	44	43	42	41	40	39	37	36	35
VNC	TL T-HANG	715	89	87	85	83	82	80	78	77	76	74	73
VNC	TL T-HANG	720	89	87	85	83	82	80	78	77	76	74	73
VNC	TL T-HANG	725	92	90	88	86	84	82	81	79	78	76	75
VNC	TL T-HANG	730	59	58	58	57	56	55	55	54	53	52	52
VNC	TL T-HANG	735	94	92	90	88	86	84	82	81	79	78	76
VNC	AP	4105	21	20	19	17	16	15	14	13	12	10	9
VNC	AP	4110	92	90	88	85	83	81	79	78	76	74	72
VNC	AP	4115	4	3	2	0	0	0	0	0	0	0	0
VNC	AP	4120	93	91	88	86	84	82	80	78	77	75	73
VNC	AP	4125	89	87	85	83	81	79	77	75	73	72	70
VNC	AP	4127	89	87	84	82	80	78	76	73	71	69	67
VNC	AP	4130	94	92	89	87	85	83	81	79	77	76	74
VNC	AP	4140	90	88	86	84	82	80	78	76	74	72	71
VNC	AP MID	4405	94	92	89	87	85	83	81	79	77	76	74
VNC	AP RU 13	5110	91	89	87	84	82	80	79	77	75	73	71
VNC	AP RU 23	5105	93	91	88	86	84	82	80	78	77	75	73

5.3 Critical PCI Value

An important concept in pavement management is the critical PCI value, a value that prompts major rehabilitation activities. It serves as a condition threshold that helps determine a section's suitability to receive major work. As soon as a section's PCI reaches the critical PCI value, the rate of PCI loss (deterioration) is expected to increase. The critical PCI concept assumes that once a pavement section deteriorates to this critical level, it is more cost-effective to complete a major rehabilitation project rather than continuing to apply preventive maintenance or deferring major work until more costly reconstruction activities are required. **Figure 5.3 (a)** illustrates the benefit of applying lower cost preventive maintenance to extend the life of the pavement.

Figure 5.3 (a): Pavement Life and the Effect of Treatments



FAA Eligibility Thresholds: >70: Routine Maintenance 55-70: Rehabilitation Eligible <55: Reconstruction Eligible

**Figure is for conceptual purposes only – unit costs are not specific to airfield pavements.*

Critical PCI values vary and are typically based on a pavement's surface type, functional use, and importance, or priority, in daily operations. Pavement priority is generally assigned based on the branch use of a pavement section. In previous System Updates, the critical PCI value was set to 65 for all functional uses. Now, based on FAA Order 5100.38D Change 1 Airport Improvement Handbook, issued February 26, 2019, the FAA has established pavement construction based on thresholds that distinguish Rehabilitation and Reconstruction. Pavement sections between PCI Values 55 and 70 will be considered for Rehabilitation and sections less than 55 will be considered for Reconstruction at the planning-level, as shown in **Table 5.3 (a)**. The FDOT SAPMP will integrate the PCI thresholds for airfield pavement projects to maintain alignment with the FAA AIP

and/or PFC eligibility for project planning. Moving forward, the critical PCI value will be defined at 70 for the FDOT SAPMP. Critical PCI values for this SAPMP System Update are shown in **Table 5.3 (b)**.

Table 5.3 (a): AIP Handbook PCI Requirements for Airfield Pavement Projects

Airfield Pavement Project Type	PCI Requirement
Reconstruction	PCI < 55 (Poor)
Rehabilitation	PCI < 70 (Fair)
Maintenance	N/A

*Source: AIP Handbook, in reference to Runways, Taxiways, and Aprons as seen in table G-2, H-1, and I-1 respectively

Table 5.3 (b): Critical PCI Values by Branch Use

Runway	Taxiway	Apron
70	70	70

Figures 5.3 (b) and 5.3 (c) depict the decision process for major rehabilitation project identification with the assumption of available funds (Shahin). Should funding be unavailable for pavement sections in need of major rehabilitation, the Airport may elect to apply appropriate localized stopgap repair strategies. As the figures show, once major rehabilitation has been applied, the PCI of the section is reset to 100.

Figure 5.3 (b): Major Rehabilitation Planning Decision Diagram, $PCI < \text{Critical PCI}$





Figure 5.3 (c): Major Rehabilitation Planning Decision Diagram, $PCI \geq \text{Critical PCI}$



5.4 Localized Maintenance and Repair

This section discusses both localized maintenance and major rehabilitation methods and how they may be most effectively applied to extend the life of the pavement network. General maintenance and rehabilitation (M&R) methods are characterized under two (2) broad categories: localized maintenance and major rehabilitation.

Localized maintenance is best applied as a conservation measure and is applied to slow the rate of pavement deterioration. It may, however, be applied as a temporary corrective measure in isolated areas. Proactive localized maintenance, and specifically preservation, is highly recommended to the Airport. However, it is recognized that once pavements have deteriorated below a certain condition threshold (the critical PCI value), the pavement benefits from more substantial rehabilitation in lieu of localized repairs.

Major rehabilitation is recommended when a pavement section falls below the critical PCI value or if a pavement section has a significant presence of load-related distress. Major rehabilitation efforts can correct or improve structural deficiencies and/or functional deterioration for pavement sections within a network.

M&R planning combines methods of repair to address the cause of the problem rather than just treating the symptom. For example, a PCC corner break may require slab under-sealing, full-depth patching, and joint sealing. While these repair methods apply to specific distress and pavement types, they also consider the impact of Foreign Object Debris (FOD) on aircraft operations. Untidy or improperly constructed repair activities may disintegrate and potentially create FOD at or near the repair site. Therefore, maintenance activities must include quality control monitoring to ensure that repairs are conducted properly and clean-up activities are undertaken to address this potential. The current version of the FAA Advisory Circular 150/5210-24 “Airport Foreign Object Debris (FOD) Management” provides additional guidance for developing and managing an airport FOD program.

5.4.1 Localized Maintenance and Repair Approach

Localized maintenance differs from major rehabilitation in that localized maintenance is applied based on the distresses observed and not an averaged or forecasted PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance can be applied either as a preventive measure or a safety (“stopgap”) measure. The two (2) types of localized maintenance are described below in further detail.

- » Localized Preventive Maintenance and Repair
 - Distress maintenance activities performed with the primary objective of slowing the rate of deterioration. These activities typically include crack sealing and patching.
- » Localized Stopgap/Safety Maintenance and Repair
 - Defined as the localized distress repair needed to keep a pavement in a safe and operational condition. These activities are typically applied to high-severity distresses or distresses impacting operations.

5.4.2 Localized Work Types

The following sections provide detailed descriptions of the maintenance policy work types identified in the Localized Maintenance Policy.

AC Crack Sealing

Crack sealing is the process of cleaning and sealing (or resealing) cracks in AC pavements. This repair is used to fill longitudinal and transverse cracks, including reflective cracks and block cracks that are wider than 1/8-inch. The purpose of this treatment is to prevent water and incompressible materials from entering cracks and causing further deterioration of the pavement structure. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Crack sealing is cost-effective when used as a preventive measure. Depending on the size of the crack, routing and cleaning the crack may be necessary to remove the loose material within the crack for better adherence of the crack sealant to the crack face. Measurement of this work type is typically in linear feet.

AC Full-Depth Patching

This technique involves replacing the full thickness of the AC layer and may include replacement of the base and subbase layers. Full-depth patching is used to repair structural and material-related distresses, such as alligator cracking, corrugation, depressions, rutting, slippage cracking, and swelling in AC pavements. This repair may be limited to the top AC layer (partial-depth patch) if the base and subbase layers exhibit no signs of deterioration. Measurement of this work type is typically in square feet or square yards.

AC Partial-Depth AC Patching

This technique involves the removal of a given thickness of the surface layer using a milling machine and adding back a layer of AC pavement. This technique removes the deteriorated layer and provides a good bond for an overlay. It can correct or improve the structural capacity or functional requirement, such as skid resistance and ride quality. This repair is used for surface distresses that can occur over a large area, such as raveling, shoving, and bleeding. While mill and replace can be a major rehabilitation M&R method when applied at a large scale, its application in a localized capacity to treat specific distress types also classifies it under localized maintenance for the purpose of this study. After milling operations are completed, any cracks still present should be cleaned and sealed prior to the placement of a tack coat and AC overlay layer(s). Measurement of this work type is typically in square feet or square yards.

Grinding

Grinding is the process of removing a thin layer of the existing concrete by grinding it with a series of closely spaced, rotating saw blades. This method is used to re-profile jointed concrete pavements with poor ride quality due to faulting or warping. Grinding is also used to restore transverse drainage and to provide a textured pavement surface. The concern with this type of maintenance is that if too much material is removed, the overall structural composition of the pavement section may change, potentially reducing the overall life of the pavement. Measurement of this work type is typically in square feet or square yards.

Monitor Pavement

Monitor pavement is recommended when the distresses do not interfere with ride quality, do not have FOD potential, and do not pose an immediate safety concern.

PCC Crack Sealing

Crack sealing is the process of routing, cleaning, and sealing (or resealing) cracks in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the cracks. Water entering cracks can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in cracks may lead to spalling and is a source of FOD. Routing and cleaning of the crack is often necessary to adhere the crack sealant to both sides of the crack. Measurement of this work type is typically in linear feet.

PCC Full-Depth Patching

This type of M&R activity involves full-depth replacement of a portion of a PCC slab. This repair is used for medium- and high-severity corner breaks, medium-severity durability cracking, medium-severity blowups and buckling, and high-severity large patches. This repair requires restoring load transfer if near a joint or crack. Measurement of this work type is typically in square feet or square yards.

PCC Joint Seal

Joint sealing is the process of cleaning and sealing (or resealing) joints in PCC pavement to prevent water from infiltrating into the pavement foundation and to stop the accumulation of incompressible materials in the joints. Water entering joints can weaken the subgrade, potentially leading to pumping, corner breaks, and/or shattered slabs. Accumulation of incompressible materials in joints leads to spalling of the concrete and is a source of FOD. In some cases, it may be necessary to re-saw the pavement joints to remove old material prior to resealing. Measurement of this work type is typically in linear feet.

PCC Partial-Depth Patching

Partial-depth patching involves removing shallow, localized areas of deteriorated or spalled PCC pavement and replacing them with a suitable patch-like cement concrete or epoxy concrete. This method is used to repair distresses that are confined to the top few inches of the slab, such as joint and corner spalling. This repair would require restoring the joint sealant if near a joint. Measurement of this work type is typically in square feet or square yards.

PCC Slab Replacement

This type of M&R activity involves full-depth replacement of an entire PCC slab. This repair is used to repair high-severity blowups and buckling, high-severity durability cracking, medium- and high-severity shattered slabs, and medium- and high-severity ASR. This repair requires restoring load transfer with adjacent slabs through dowels or similar means. Measurement of this work type is typically in square feet or square yards.

Surface Seal

Application of a surface treatment provides AC-surfaced pavements with an unoxidized layer of bituminous material that can help extend the life of a pavement that is experiencing climate-related distresses such as weathering and raveling. The surface treatment can also serve as a repair that re-establishes a bond between aggregates, slowing pavement deterioration and reducing FOD potential. Measurement of this work type is typically in square feet or square yards.

5.4.3 Localized Maintenance Planning-Level Unit Costs

The activities identified here are based on research of practical pavement treatments in consideration of the FAA AC 150/5380-6C. The Localized Maintenance Policies and associated planning-level unit costs are developed in consideration of a network-level analysis.

The Localized Maintenance and Repair Policies and associated planning-level unit costs are based on a statewide consideration of pavement treatments and construction costs from both airfield pavements and the FDOT Historical Cost Information archives. Furthermore, a consideration of limited repair quantities is factored into the determination of conservative planning-level unit costs. Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, the Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs.

Tables 5.4.3 (a) and (b) display the cost by maintenance activity for AC and PCC pavement types, respectively. Because the localized maintenance activities identified for both preventive and stopgap work types are based on a statewide network approach, project-specific evaluations and maintenance quantities should be developed prior to construction.

Table 5.4.3 (a): Localized M&R Planning-Level Unit Costs – Asphalt Concrete

Localized Work Type	Reliever Costs	Work Type Unit
AC Crack Sealing	\$ 4.00	LF
AC Full-Depth Patching	\$ 11.50	SF
AC Partial-Depth Patching	\$ 4.75	SF
Surface Seal	\$ 0.75	SF

Table 5.4.3 (b): Localized M&R Planning-Level Unit Costs – Portland Cement Concrete

Localized Work Type	Reliever Costs	Work Type Unit
Grinding	\$ 2.00	SF
PCC Crack Sealing	\$ 7.00	LF
PCC Joint Seal	\$ 4.25	LF
PCC Full-Depth Patching	\$ 65.00	SF
PCC Partial-Depth Patching	\$ 169.00	SF
PCC Slab Replacement	\$ 51.50	SF

* PCC Partial-Depth Patching considers high-early-strength and high-performing repair material.

5.4.4 Localized Maintenance and Repair Policy

Table 5.4.4 and **Table 5.4.5** depicts the Localized Preventive Maintenance Policy and the Localized Stopgap Maintenance Policy for AC and PCC pavements. The resulting Localized Maintenance recommendations for this program are identified based on this policy.

Table 5.4.4: AC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
41	Low	Alligator Cracking	Monitor Pavement	Monitor Pavement
41	Medium	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
41	High	Alligator Cracking	AC Full Depth Patching	AC Full Depth Patching
42	N/A	Bleeding	Monitor Pavement	Monitor Pavement
43	Low	Block Cracking	Monitor Pavement	Monitor Pavement
43	Medium	Block Cracking	AC Crack Sealing	Monitor Pavement
43	High	Block Cracking	AC Crack Sealing	AC Crack Sealing
44	Low	Corrugation	Monitor Pavement	Monitor Pavement
44	Medium	Corrugation	AC Full Depth Patching	Monitor Pavement
44	High	Corrugation	AC Full Depth Patching	AC Full Depth Patching
45	Low	Depression	Monitor Pavement	Monitor Pavement
45	Medium	Depression	AC Full Depth Patching	Monitor Pavement
45	High	Depression	AC Full Depth Patching	AC Full Depth Patching
46	N/A	Jet Blast	Monitor Pavement	Monitor Pavement
47	Low	Jt. Reflective Cracking	Monitor Pavement	Monitor Pavement
47	Medium	Jt. Reflective Cracking	AC Crack Sealing	Monitor Pavement
47	High	Jt. Reflective Cracking	AC Full Depth Patching	AC Full Depth Patching
48	Low	L&T Cracking	Monitor Pavement	Monitor Pavement
48	Medium	L&T Cracking	AC Crack Sealing	Monitor Pavement
48	High	L&T Cracking	AC Full Depth Patching	AC Full Depth Patching
49	N/A	Oil Spillage	Monitor Pavement	Monitor Pavement
50	Low	Patching	Monitor Pavement	Monitor Pavement
50	Medium	Patching	AC Full Depth Patching	Monitor Pavement
50	High	Patching	AC Full Depth Patching	AC Full Depth Patching
51	N/A	Polished Aggregate	Monitor Pavement	Monitor Pavement
52	Low	Raveling	Surface Seal	Monitor Pavement
52	Medium	Raveling	Surface Seal	Monitor Pavement
52	High	Raveling	AC Partial Depth Patching	AC Partial Depth Patching
53	Low	Rutting	Monitor Pavement	Monitor Pavement
53	Medium	Rutting	AC Full Depth Patching	Monitor Pavement
53	High	Rutting	AC Full Depth Patching	AC Full Depth Patching
54	Low	Shoving	Monitor Pavement	Monitor Pavement
54	Medium	Shoving	AC Partial Depth Patching	Monitor Pavement
54	High	Shoving	AC Full Depth Patching	AC Full Depth Patching
55	N/A	Slippage Cracking	AC Full Depth Patching	AC Full Depth Patching
56	Low	Swelling	Monitor Pavement	Monitor Pavement
56	Medium	Swelling	AC Full Depth Patching	Monitor Pavement
56	High	Swelling	AC Full Depth Patching	AC Full Depth Patching

Distress	Severity	Description	AC Preventive Work Type	AC Stopgap Work Type
57	Low	Weathering	Monitor Pavement	Monitor Pavement
57	Medium	Weathering	Surface Seal	Monitor Pavement
57	High	Weathering	AC Partial Depth Patching	Surface Seal

Table 5.4.5: PCC Pavement Localized Preventive & Stopgap Maintenance & Repair Policy

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
61	Low	Blow-up	PCC Full Depth Patching	Monitor Pavement
61	Medium	Blow-up	PCC Full Depth Patching	PCC Full Depth Patching
61	High	Blow-up	PCC Slab Replacement	PCC Slab Replacement
62	Low	Corner Break	Monitor Pavement	Monitor Pavement
62	Medium	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
62	High	Corner Break	PCC Full Depth Patching	PCC Full Depth Patching
63	Low	Linear Cracking	Monitor Pavement	Monitor Pavement
63	Medium	Linear Cracking	PCC Crack Sealing	PCC Crack Sealing
63	High	Linear Cracking	PCC Full Depth Patching	PCC Crack Sealing
64	Low	Durability Cracking	Monitor Pavement	Monitor Pavement
64	Medium	Durability Cracking	PCC Full Depth Patching	PCC Full Depth Patching
64	High	Durability Cracking	PCC Slab Replacement	PCC Slab Replacement
65	Low	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	Medium	Jt. Seal Damage	PCC Joint Seal	Monitor Pavement
65	High	Jt. Seal Damage	PCC Joint Seal	PCC Joint Seal
66	Low	Small Patch	Monitor Pavement	Monitor Pavement
66	Medium	Small Patch	PCC Partial Depth Patching	Monitor Pavement
66	High	Small Patch	PCC Partial Depth Patching	PCC Partial Depth Patching
67	Low	Large Patch	Monitor Pavement	Monitor Pavement
67	Medium	Large Patch	PCC Full Depth Patching	Monitor Pavement
67	High	Large Patch	PCC Full Depth Patching	PCC Full Depth Patching
68	N/A	Popouts	Monitor Pavement	Monitor Pavement
69	N/A	Pumping	Monitor Pavement	Monitor Pavement
70	Low	Scaling	Monitor Pavement	Monitor Pavement
70	Medium	Scaling	PCC Slab Replacement	Monitor Pavement
70	High	Scaling	PCC Slab Replacement	PCC Slab Replacement
71	Low	Faulting	Monitor Pavement	Monitor Pavement
71	Medium	Faulting	Grinding	Monitor Pavement
71	High	Faulting	PCC Slab Replacement	PCC Slab Replacement
72	Low	Shattered Slab	PCC Crack Sealing	Monitor Pavement
72	Medium	Shattered Slab	PCC Slab Replacement	PCC Crack Sealing
72	High	Shattered Slab	PCC Slab Replacement	PCC Slab Replacement
73	N/A	Shrinkage Cracking	Monitor Pavement	Monitor Pavement

Distress	Severity	Description	PCC Preventive Work Type	PCC Stopgap Work Type
74	Low	Joint Spall	Monitor Pavement	Monitor Pavement
74	Medium	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
74	High	Joint Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	Low	Corner Spall	Monitor Pavement	Monitor Pavement
75	Medium	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
75	High	Corner Spall	PCC Partial Depth Patching	PCC Partial Depth Patching
76	Low	ASR	Monitor Pavement	Monitor Pavement
76	Medium	ASR	PCC Slab Replacement	PCC Slab Replacement
76	High	ASR	PCC Slab Replacement	PCC Slab Replacement

5.5 Major Rehabilitation

Major rehabilitation is recommended to correct or improve structural deficiencies and/or functional deterioration. Often, when pavements are subject to significant changes in the aircraft fleet mix (frequency and type), major rehabilitation is required to provide a pavement section that can meet the structural demands of traffic loading. Major rehabilitation is generally described as a pavement construction that removes and replaces the pavement surface, thus resetting the PCI value to 100 and the pavement age to zero. Typical policies include full- and partial-depth reconstruction and mill and overlay.

5.5.1 Major Rehabilitation Pavement Section Development

Once the timing of the major rehabilitation activity is determined based on the PCI value, existing as-built record documentation is used to determine typical rehabilitation processes and pavement sections. Refinement of the pavement section layers is performed in consideration of the FAA AC 150/5320-6F. It should be noted that no subsurface geotechnical investigation, American Land Title Association (ALTA)/American Congress on Surveying and Mapping (ACSM) Survey, topographic survey, utilities survey, environmental, or site-specific air traffic study(s) have been utilized in the development of the design criteria. No warranty or assurance is implied in this document for final design nor construction for any airfield pavements discussed within this Report.

Major rehabilitation is divided into two (2) policy categories as part of this System Update: Full-Depth Reconstruction (Reconstruction) and Intermediate Major Rehabilitation (Rehabilitation). Based on the pavement type, the general categories are defined as AC Reconstruction and AC Rehabilitation for AC, AAC, and APC pavement types, and PCC Reconstruction and PCC Rehabilitation for PCC pavement types. The pavement sections are based on the average Reliever Airport Type requirements; no pavement design has been performed in accordance with the FAA AC 150/5320-6F for the determined conceptual sections. **Table 5.5.1** provide details on the conceptual pavement sections developed for this study.

Table 5.5.1: Conceptual Pavement Sections for Major Rehabilitation

Rehabilitation Type	Reliever Pavement Section
AC Reconstruction	
<p><i>Full-depth asphalt pavement section reconstruction. Removal of existing pavement section and construction of a new section.</i></p> <p style="text-align: center;">PCI <55</p>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (8")
	Prime Coat
	Tack Coat
	P-401 Surface Course (4")
	<i>Excludes any paved shoulder features</i>
AC Rehabilitation	
<p><i>Combination of asphalt pavement milling and replacement overlay with 15% of the areas subject to full-depth reconstruction.</i></p> <p style="text-align: center;">PCI = 55 to 70</p>	15% AC Reconstruction
	Mill and Overlay
	AC Milling (3")
	Tack Coat
	P-401 Surface Course (3")
	<i>Excludes any paved shoulder features</i>
PCC Reconstruction	
<p><i>Full-depth rigid pavement section reconstruction.</i></p> <p style="text-align: center;">PCI < 55</p>	Pavement Removal
	Unclassified Excavation
	Subgrade Stabilization (12")
	Limerock Base Course (6")
	P-501 PCC Pavement (14")
	PCC Joint Seal
PCC Rehabilitation	
<p><i>Rehabilitation of PCC pavement with a combination of crack sealing, joint seal replacement, limited patching, and replacement of 15% of slab panels.</i></p> <p style="text-align: center;">PCI = 55 to 70</p>	15% Slab Replacement
	Joint and Crack Seal
	Limited Patching

The identification of rehabilitation needs and conceptual pavement sections have been determined at the planning level. Design-level investigation is recommended prior to developing construction-level design documents and budgets. This type of construction typically warrants consideration for non-pavement efforts that may include drainage, turfing, electrical lighting, pavement marking, construction contingency, mobilization costs, and project soft costs.

Reconstruction (AC or PCC)

Reconstruction is the removal and replacement of the existing AC or PCC pavement and base layer and includes preparation of the existing subgrade material. This technique is utilized when the pavement is badly deteriorated or a structural improvement is required. Reconstruction is used when the pavements are structurally deficient and an overlay is not possible due to adjacent pavement grades.

AC Rehabilitation

AC Rehabilitation, for the purposes of this SAPMP, is a removal of all or a portion of the asphalt surface through milling and replacing the milled depth with an overlay of asphalt. This rehabilitation activity is typically applied to pavement that does not require a structural improvement and does not display an extensive amount of load-related distresses. However, this work type conservatively accounts for 15% of the planned area to receive a full-depth replacement of the pavement structure. This is meant to capture any deficiencies that may not be apparent from a visual evaluation of the surface of the pavement. This work type occurs on pavement sections with a PCI value between 55 and 70. As a general rule of thumb, intermediate rehabilitation activities have a shorter pavement life compared to a full-depth reconstruction, but AC Rehabilitation will still reset the pavement to a PCI of 100.

PCC Rehabilitation

PCC Rehabilitation, for the purposes of this SAPMP, is a planning-level estimate of several concurrent PCC maintenance activities intended to raise the PCI above Critical without reconstructing the entire area. This work type accounts for the replacement of 15% of the slabs as well as a PCC patching, crack sealing, and joint sealing for areas outside of the panel replacement. This work type occurs on pavement sections with a PCI value between 55 and 70.


5.5.2 Major Rehabilitation Planning-Level Unit Costs

Planning-level opinions of probable construction cost developed for this System Update are based on archived bid tabulations and records from airfield pavement projects provided by participating airports. A review of cost trends and cost factors have been incorporated to assist airports in planning for project budgets.


Neither the FDOT nor the Consultant team have control over the cost of labor, materials, equipment, Contractor's methods of determining prices, or over competitive bidding or market conditions. Opinions of probable construction costs provided herein are based on the information known to the FDOT at this time and represent only the Consultant team's judgment as a design professional familiar with the construction industry. This Report cannot and does not guarantee that proposals, bids, or actual construction costs will not vary from its opinions of probable construction costs. **Table 5.5.2** depicts the associated work type planning-level unit costs for Major Rehabilitation for each pavement type.

Table 5.5.2: RL Major Rehabilitation Planning-Level Unit Cost by Pavement Type

Rehabilitation Type	PCI Range	Asphalt Concrete Cost per SF	Portland Cement Concrete Cost Per SF
Rehabilitation	55 to 70	\$10.50	\$22.50
Reconstruction	0 to 55	\$18.50	\$45.00



Chapter 6: M&R Planning and Budget Scenario Analysis



Chapter 6 – M&R Planning and Budget Scenario Analysis

6.1 Localized Maintenance and Repair Analysis and Recommendations

This FDOT SAPMP System Update provides a planning-level estimation of Localized Maintenance and Repair costs based on the results of the latest PCI assessment performed at the Airport. Due to the limited sample units inspected in certain pavement sections, a statistical extrapolation of distresses is used to estimate the quantities of recommended repair activities at the section level, based the policies defined in **5.4.4 Localized Maintenance and Repair Policy**. These work quantities are limited to a near-term application since they were determined directly from the PCI assessment efforts. As pavements continue to deteriorate year-to-year, quantities and/or distress severities may increase, which will affect the amount and type of localized maintenance required. This analysis can be utilized as a planning tool to assist Airport staff in determining an annual budget allocation for maintenance activities that will help maintain Airport pavements above the critical PCI value and extend the life of the pavement.

Table 6.1 (a) provides a summary of the anticipated planning-level costs for Year 1 Localized Preventive Maintenance and Localized Stopgap Maintenance. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (a): Year 1 Summary of Localized Maintenance

Work Category	Cost
Preventive	\$ 502,570
Stopgap	\$ 86,310
Planning-Level Localized M&R Needs =	\$ 588,880

Localized Preventive Maintenance is typically applied to pavements that are in a condition above the critical PCI value of the pavement section. Localized Stopgap Maintenance is typically applied to pavement sections that are at or below the critical PCI value. Application of localized maintenance and repair should be coordinated with the planning of major rehabilitation efforts identified through the Major Rehabilitation analysis. Pavements with stopgap recommendations that are subject to near-term major rehabilitation efforts may remove the need to perform localized (stopgap) maintenance efforts in subsequent years.

Table 6.1 (b) summarizes the anticipated Year 1 Localized Maintenance recommendations by work type, based on the PCI assessment efforts performed as part of this SAPMP System Update. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (b): Year 1 Localized Maintenance by Work Type Summary

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	Surface Seal	669,937	SF	\$ 502,570
	AC Partial-Depth Patching	351	SF	\$ 1,670
Localized Stopgap Maintenance	PCC Crack Sealing	2,975	LF	\$ 20,840
	PCC Joint Seal	4,552	LF	\$ 19,350
	PCC Partial-Depth Patching	184	SF	\$ 31,010
	PCC Full-Depth Patching	207	SF	\$ 13,440

Table 6.1 (c) provides a breakdown of the anticipated planning-level costs by section for those areas exhibiting distresses that would benefit from Year 1 Localized M&R. The table shows the approximate improved “End Condition” PCI value of the section after the application of Localized M&R. This approximation is intended to depict a planning-level estimate of the effect of the localized M&R on the section-level PCI; the performance of the work does not guarantee the pavement will not deteriorate in other ways outside of the described treatment. The following table depicts planning-level costs rounded up to the next 10-dollar increment.

Table 6.1 (c): Section-Level Year 1 Localized M&R Planning Cost Summary

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
VNC	RW 5-23	6205	255,000	85	94	\$ 44,980
VNC	RW 5-23	6210	382,500	88	95	\$ 40,550
VNC	RW 5-23	6215	18,000	85	94	\$ 3,380
VNC	RW 5-23	6220	27,000	91	94	\$ 1,020
VNC	RW 5-23	6225	18,000	85	94	\$ 3,380
VNC	RW 5-23	6230	27,000	92	97	\$ 2,030
VNC	RW 13-31	6105	413,900	71	87	\$ 295,460
VNC	RW 13-31	6110	196,950	71	79	\$ 83,120
VNC	RW 13-31	6115	30,000	65	65	\$ -
VNC	RW 13-31	6120	20,000	61	61	\$ -
VNC	RW 13-31	6125	30,000	65	65	\$ -
VNC	RW 13-31	6130	20,000	60	60	\$ -
VNC	RW 13-31	6135	26,100	85	91	\$ 2,940
VNC	RW 13-31	6140	13,050	85	90	\$ 980
VNC	RW 13-31	6145	63,850	91	91	\$ -
VNC	RW 13-31	6150	31,925	94	94	\$ -
VNC	TW A	105	55,145	93	93	\$ -
VNC	TW A	110	55,883	84	84	\$ -
VNC	TW A	115	52,281	90	91	\$ 950
VNC	TW A	120	9,988	80	100	\$ 7,500
VNC	TW A	125	5,738	66	66	\$ -
VNC	TW B	220	47,695	94	94	\$ -
VNC	TW B	225	12,448	89	94	\$ 940
VNC	TW B	235	21,767	94	94	\$ -
VNC	TW C	315	85,087	93	93	\$ -
VNC	TW D	400	38,598	94	94	\$ -

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
VNC	TW D	405	76,359	94	94	\$ -
VNC	TW D	410	17,828	88	94	\$ 2,010
VNC	TW D	420	109,579	100	100	\$ -
VNC	TW E	505	62,102	87	94	\$ 7,740
VNC	TW E	510	10,168	85	92	\$ 1,150
VNC	TW E	515	21,560	91	94	\$ 810
VNC	TW E	520	110,616	100	100	\$ -
VNC	TW E	550	9,260	80	85	\$ 1,000
VNC	TW F	450	11,675	94	94	\$ -
VNC	TL T-HANG	605	16,734	69	69	\$ -
VNC	TL T-HANG	610	42,622	66	66	\$ -
VNC	TL T-HANG	620	100,062	52	54	\$ 1,670
VNC	TL T-HANG	705	34,474	78	83	\$ 2,590
VNC	TL T-HANG	708	11,446	67	67	\$ -
VNC	TL T-HANG	710	41,684	46	46	\$ -
VNC	TL T-HANG	715	12,768	89	89	\$ -
VNC	TL T-HANG	720	5,422	89	89	\$ -
VNC	TL T-HANG	725	17,209	92	92	\$ -
VNC	TL T-HANG	730	18,001	59	59	\$ -
VNC	TL T-HANG	735	21,329	94	94	\$ -
VNC	AP	4105	112,335	21	57	\$ 4,480
VNC	AP	4110	302,352	92	92	\$ -
VNC	AP	4115	34,307	4	24	\$ 80,130
VNC	AP	4120	58,790	93	93	\$ -
VNC	AP	4125	53,176	89	89	\$ -
VNC	AP	4127	19,630	89	89	\$ -
VNC	AP	4130	6,119	94	94	\$ -
VNC	AP	4140	73,498	90	90	\$ -
VNC	AP MID	4405	166,523	94	94	\$ -
VNC	AP RU 13	5110	19,846	91	91	\$ -
VNC	AP RU 23	5105	26,551	93	94	\$ 30

6.2 Major Rehabilitation Needs

Major rehabilitation is identified within the FDOT SAPMP as a major construction activity that results in a substantial improvement to the pavement condition and resets the pavement section's PCI value to 100. Major rehabilitation recommendations (AC Rehabilitation, AC Reconstruction, PCC Rehabilitation, and PCC Reconstruction) should be considered as planning-level only. Additional design-level investigation in accordance with FAA Advisory Circulars is required. Recommendations identified within this planning document do not imply final design.

The objective of the Major Pavement Rehabilitation Needs analysis is to develop planning-level projects within an Airport's airfield pavement network. As depicted in **Figures 5.3 (b) and (c)** in **Chapter 5**, major rehabilitation activities are recommended when a pavement section has deteriorated below the critical PCI value, a point at which localized maintenance and repair activities may not be a cost-effective solution. In addition, major rehabilitation is also recommended when the section's PCI value is above the critical PCI value with the section

exhibiting a significant amount of load-related distresses. Identification of rehabilitation needs is done at the section-level. This, however, does not limit the Airport from further refining limits of project planning areas.

6.2.1 10-Year Unconstrained Budget Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to critical PCI values, major rehabilitation policies, and unit costs, assuming there are no budget constraints. This is done over a 10-year analysis period. While this is financially impractical, it does yield the unbiased pavement needs over a 10-year time frame at the Airport given current and forecasted pavement conditions. The FDOT recognizes that airports are constrained by budgets and does not intend to convey an unrealistic approach of addressing pavement rehabilitation. Each airport has a unique set of challenges and FDOT's goals are to provide it with the data needed to formulate a practical Capital Improvement Program and identify needs in the Joint Automated Capital Improvement Program (JACIP). This includes:

- » An estimation of current pavement condition;
- » Major pavement rehabilitation needs based on condition and policies; and
- » Planning-level cost estimates for the major rehabilitation needs.


Table 6.2.1 (a) summarizes section-level major rehabilitation needs forecasted for a 10-year period. It should be noted that the following table depicts planning-level costs and has been rounded up to the nearest \$1,000 for planning purposes.


Table 6.2.1 (a): Section-Level 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	VNC	RW 13-31	6105	AAC	413,900	69	AC Rehabilitation	\$ 4,346,000
2023	VNC	RW 13-31	6110	AAC	196,950	69	AC Rehabilitation	\$ 2,068,000
2023	VNC	RW 13-31	6115	APC	30,000	63	AC Rehabilitation	\$ 315,000
2023	VNC	RW 13-31	6120	APC	20,000	59	AC Rehabilitation	\$ 210,000
2023	VNC	RW 13-31	6125	APC	30,000	63	AC Rehabilitation	\$ 315,000
2023	VNC	RW 13-31	6130	APC	20,000	58	AC Rehabilitation	\$ 210,000
2023	VNC	TW A	125	AAC	5,738	65	AC Rehabilitation	\$ 61,000
2023	VNC	TL T-HANG	605	AC	16,734	68	AC Rehabilitation	\$ 176,000
2023	VNC	TL T-HANG	610	AC	42,622	65	AC Rehabilitation	\$ 448,000
2023	VNC	TL T-HANG	620	AC	100,062	51	AC Reconstruction	\$ 1,852,000
2023	VNC	TL T-HANG	708	AC	11,446	66	AC Rehabilitation	\$ 121,000
2023	VNC	TL T-HANG	710	AC	41,684	45	AC Reconstruction	\$ 772,000
2023	VNC	TL T-HANG	730	AAC	18,001	58	AC Rehabilitation	\$ 190,000
2023	VNC	AP	4105	PCC	112,335	20	PCC Reconstruction	\$ 5,056,000
2023	VNC	AP	4115	PCC	34,307	3	PCC Reconstruction	\$ 1,544,000
2029	VNC	TL T-HANG	705	AC	34,474	69	AC Rehabilitation	\$ 486,000
2030	VNC	TW A	120	AC	9,988	70	AC Rehabilitation	\$ 148,000
2030	VNC	TW E	550	AC	9,260	70	AC Rehabilitation	\$ 137,000
2031	VNC	RW 13-31	6135	AAC	26,100	69	AC Rehabilitation	\$ 405,000
2031	VNC	RW 13-31	6140	AAC	13,050	69	AC Rehabilitation	\$ 203,000
2031	VNC	AP	4127	AAC	19,630	69	AC Rehabilitation	\$ 305,000
2032	VNC	AP	4125	AC	53,176	70	AC Rehabilitation	\$ 867,000

Figure 6.2.1 (a) summarizes the section-level major rehabilitation needs for a 10-year period between 2023 and 2032. **Figure 6.2.1 (b)**, the Airfield Pavement Major Rehabilitation Exhibit, graphically depicts the major rehabilitation needs with rounded costs. As suggested previously, this is planning-level data that can be used by the Airport to support developing a practical CIP.

Figure 6.2.1 (a): 10-Year Major Rehabilitation Needs by Program Year





LEGEND

RW 13-31 — TYPICAL RUNWAY BRANCH ID
TW A — TYPICAL TAXIWAY BRANCH ID
AP S — TYPICAL APRON BRANCH ID

PROGRAM YEAR

2023	2028
2024	2029
2025	2030
2026	2031
2027	2032

"BRANCH," "SECTION"
"YEAR," "REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



Chapter 7: Conclusion



Chapter 7 – Conclusion

7.1 Recommendations

7.1.1 Continued PCI Surveys

It is recommended that the Airport continue to perform regularly scheduled PCI surveys in accordance with the ASTM D5340-20 (or latest edition) to monitor the condition of airfield pavement facilities.

A high priority should be placed on maintaining good record keeping and re-inspecting the Airport's maintained pavement facilities to ensure continued safe aircraft operations. Per the FAA AC 150/5380-7B, a series of scheduled periodic inspections must be carried out for an effective maintenance program. Re-inspection of pavements should be scheduled in a timely manner to ensure that all areas, particularly those that may not come under day-to-day observation, are thoroughly evaluated and reported.

7.1.2 Localized Maintenance and Repair

While deterioration of the pavements due to usage and exposure to the environment cannot be prevented, applying timely and effective maintenance efforts can slow the anticipated rate of deterioration. Lack of adequate and timely maintenance is a significant factor in pavement deterioration. **Chapter 6** identified localized maintenance and repair needs. It is recommended that Airport sponsors coordinate with their respective Airport maintenance staff and Airport engineer when developing project-level maintenance and repair efforts.

7.1.3 Major Rehabilitation

Chapter 6 also identified major pavement rehabilitation project needs from 2023-2032. Identification of these rehabilitation needs are performed at the section level for manageable project areas and assume an unconstrained budget scenario. Given the uncertainty in Airport-specific budget information and prioritization goals, the unconstrained budget scenario represents a conservative scenario and identifies pavement needs over a 10-year period. Certainly, it is understood that most airports are faced with constrained budgets, thus further evaluation of projects based on prioritization, operational criticality, funding availability, and practicality is recommended.

7.1.4 Pavement Management System

The following recommendations are made to fully implement an effective pavement management program for the Airport:

- » Develop a detailed preventive maintenance program for the Airport based on the recommendations provided in **Section 6.1**;
- » Further refine and implement the identified 10-year major rehabilitation needs provided in **Section 6.2**;
- » Maintain detailed records on pavement maintenance, construction, and inspection; and
- » Maintain records on major pavement construction projects (year, scope, cost, and construction documents).

7.2 Supporting Documents

Airfield Pavement Network Definition Exhibit

The Airfield Pavement Network Definition Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts the airfield layout in a manner that defines the airfield pavement infrastructure as branches, sections, and sample units in accordance with the ASTM D5340-20. The Exhibit is intended for planning purposes only. Further details can be found on the Airport's adopted Airport Layout Plan. Detailed characteristics are tabulated in **Appendix A**.

Airfield Pavement System Inventory Exhibit

The Airfield Pavement System Inventory Exhibit is located in **Chapter 3** and **Appendix C**. The Exhibit depicts recent and/or anticipated construction activity within the airfield pavement facilities reported by Airport staff. The Exhibit is intended to schematically identify the pavement limits of work and general work description. The information reported on the Airport Response Form provided by each participating airport was used as the basis of the changes. Furthermore, changes are confirmed at the Airport with Airport staff during the in-brief and debrief meeting.

Airfield Pavement Estimated Age Exhibit

The Airfield Pavement Estimated Age Exhibit is located in **Chapter 3** and **Appendix C**. Based on the review of historic airfield pavement construction activities, the Exhibit provides the approximate limits of the age of the pavement sections since the last major construction activity has occurred. This is intended to be a rough estimate based on interpretation of the limited data available at the time of report.

Airfield Pavement Condition Index Exhibit

The Airfield Pavement Condition Index Exhibit is located in **Chapter 4** and **Appendix C**. The Exhibit is a visual summary of the latest conditions reported from the PCI assessment performed at the Airport. Distress analysis occurred in accordance with ASTM D5340-20 (referenced in **Appendix E**), with results being analyzed using PAVER™ software to determine PCI values. The PCI values are identified in the Exhibit and graphically represented using the standard ASTM D5340-20 condition rating categories.

Airfield Pavement Major Rehabilitation Exhibit

The Airfield Pavement Major Rehabilitation Exhibit is located in **Chapter 6** and **Appendix C**. The Exhibit has been prepared based on the section condition analysis, pavement condition forecasts, and major rehabilitation needs analysis. The Exhibit graphically depicts the inventory with the associated rehabilitation type activity, program year, and the planning-level costs. Area limits, rehabilitation type, and planning-level costs should not be considered a design-level recommendation. A tabulation of the 10-Year Major Rehabilitation is located in **Appendix B**.

Inspection Photograph Documentation

Representative field conditions from the PCI assessment are documented with digital photographs located in **Appendix D**. Select photographs are provided with a limited caption on the distress(es) observed. "Vicinity" photos refer to the approximate boundaries of an inspected sample unit within the section and provide an overview of the section condition but are not focused on a specific distress. The Appendix does not contain photographs for every section and sample unit.

7.3 Conclusion

The FDOT SAPMP System Update Phase 2 2021-2023 was completed for the Airport on behalf of the FDOT AO in accordance with the FAA AC 150/5380-7B and 150/5380-6C. FDOT's implementation of the SAPMP has assisted public airports with this requirement in performing PCI survey inspections and analysis in accordance with the ASTM D5340-20.

7.4 References

The following documents are referenced as specific guidelines and procedures for maintaining Airport pavements, establishing an effective pavement maintenance program, and identifying specific pavement distresses, probable causes of distresses, survey guidelines, and recommended methods of repair.

- » ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys, American Society for Testing and Materials, West Conshohocken, PA, 2018.
- » AC 150/5210-24 Airport Foreign Object Debris (FOD) Management, Federal Aviation Administration, Washington, D.C., 2010.
- » AC 150/5320-6F, Airport Pavement Design and Evaluation, Federal Aviation Administration, Washington, D.C., 2016.
- » AC 150/5380-7B, Airport Pavement Management Program (PMP), Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5380-6C, Guidelines and Procedures for Maintenance of Airport Pavements, Federal Aviation Administration, Washington, D.C., 2014.
- » AC 150/5370-10H, Standard Specifications for Construction of Airports, Federal Aviation Administration, Washington, D.C., 2018.
- » Airport Improvement Program Handbook, Order 5100.38D, Change 1, Federal Aviation Administration, Washington, D.C., 2019.
- » Tri-Service Pavements Working Group (TSPWG) Manual 3-270-08. 14-03, Preventive Maintenance Plan (PMP) for Airfield Pavements, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-16, O&M Manual: Standard Practice for Airfield Pavement Condition Surveys, Department of Defense, Washington, D.C., 2019.
- » Unified Facilities Criteria (UFC) 3-260-03, Airfield Pavement Evaluation, Department of Defense, Washington, D.C., 2001.
- » Shahin, Mohamed Y., Pavement Management for Airports, Roads, and Parking Lots, Springer, 2005.

A wide-angle photograph of an airfield runway stretching into the distance under a bright blue sky with scattered white clouds. The runway is dark asphalt with a central white dashed line and yellow edge lines. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

Appendix A: Airfield Pavement Analysis

A close-up, low-angle view of the runway pavement, showing a concrete slab with a yellow dashed line and a yellow chevron marking. The image is framed by a red diagonal bar on the left and a blue diagonal bar on the right.

Table A.1: Pavement System Inventory Details

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
VNC	RW 5-23	Runway	6205	255,000	AC	1/1/2013
VNC	RW 5-23	Runway	6210	382,500	AAC	1/1/2013
VNC	RW 5-23	Runway	6215	18,000	AC	1/1/2013
VNC	RW 5-23	Runway	6220	27,000	AC	1/1/2013
VNC	RW 5-23	Runway	6225	18,000	AC	1/1/2013
VNC	RW 5-23	Runway	6230	27,000	AC	1/1/2013
VNC	RW 13-31	Runway	6105	413,900	AAC	12/1/2006
VNC	RW 13-31	Runway	6110	196,950	AAC	12/1/2006
VNC	RW 13-31	Runway	6115	30,000	APC	12/1/2006
VNC	RW 13-31	Runway	6120	20,000	APC	12/1/2006
VNC	RW 13-31	Runway	6125	30,000	APC	12/1/2006
VNC	RW 13-31	Runway	6130	20,000	APC	12/1/2006
VNC	RW 13-31	Runway	6135	26,100	AAC	1/1/2013
VNC	RW 13-31	Runway	6140	13,050	AAC	1/1/2013
VNC	RW 13-31	Runway	6145	63,850	AC	5/9/2017
VNC	RW 13-31	Runway	6150	31,925	AC	5/9/2017
VNC	TW A	Taxiway	105	55,145	AC	1/1/2015
VNC	TW A	Taxiway	110	55,883	AC	1/1/2015
VNC	TW A	Taxiway	115	52,281	AC	1/1/2015
VNC	TW A	Taxiway	120	9,988	AC	1/1/2013
VNC	TW A	Taxiway	125	5,738	AAC	12/1/2006
VNC	TW B	Taxiway	220	47,695	AC	1/1/2017
VNC	TW B	Taxiway	225	12,448	AC	1/1/2013
VNC	TW B	Taxiway	235	21,767	AC	5/9/2017
VNC	TW C	Taxiway	315	85,087	AC	1/1/2015
VNC	TW D	Taxiway	400	38,598	AC	5/9/2017
VNC	TW D	Taxiway	405	76,359	AC	5/9/2017
VNC	TW D	Taxiway	410	17,828	AC	1/1/2013
VNC	TW D	Taxiway	420	109,579	AC	1/1/2020
VNC	TW E	Taxiway	505	62,102	AC	1/1/2013
VNC	TW E	Taxiway	510	10,168	AC	1/1/2013
VNC	TW E	Taxiway	515	21,560	AC	1/1/2015
VNC	TW E	Taxiway	520	110,616	AC	10/1/2021
VNC	TW E	Taxiway	550	9,260	AC	1/1/2013
VNC	TW F	Taxiway	450	11,675	AC	5/9/2017
VNC	TL T-HANG	Taxilane	605	16,734	AC	1/1/2003
VNC	TL T-HANG	Taxilane	610	42,622	AC	1/1/2003
VNC	TL T-HANG	Taxilane	620	100,062	AC	12/25/1994
VNC	TL T-HANG	Taxilane	705	34,474	AC	1/1/2003
VNC	TL T-HANG	Taxilane	708	11,446	AC	12/25/1997
VNC	TL T-HANG	Taxilane	710	41,684	AC	12/25/1994
VNC	TL T-HANG	Taxilane	715	12,768	AC	1/1/2012
VNC	TL T-HANG	Taxilane	720	5,422	AC	1/1/2012
VNC	TL T-HANG	Taxilane	725	17,209	AC	1/1/2012

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
VNC	TL T-HANG	Taxilane	730	18,001	AAC	11/1/2013
VNC	TL T-HANG	Taxilane	735	21,329	AC	1/1/2018
VNC	AP	Apron	4105	112,335	PCC	1/1/1942
VNC	AP	Apron	4110	302,352	AC	1/1/2018
VNC	AP	Apron	4115	34,307	PCC	12/25/1999
VNC	AP	Apron	4120	58,790	AC	1/1/2018
VNC	AP	Apron	4125	53,176	AC	1/1/2015
VNC	AP	Apron	4127	19,630	AAC	1/1/2017
VNC	AP	Apron	4130	6,119	AC	1/1/2015
VNC	AP	Apron	4140	73,498	AC	1/1/2015
VNC	AP MID	Apron	4405	166,523	AC	1/1/2017
VNC	AP RU 13	Apron	5110	19,846	AC	1/1/2015
VNC	AP RU 23	Apron	5105	26,551	AC	1/1/2015

Table A.2: Pavement Condition Index Summary (Current PCI Survey) – Section Level

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VNC	RW 5-23	Runway	6205	255,000	85	Satisfactory
VNC	RW 5-23	Runway	6210	382,500	88	Good
VNC	RW 5-23	Runway	6215	18,000	85	Satisfactory
VNC	RW 5-23	Runway	6220	27,000	91	Good
VNC	RW 5-23	Runway	6225	18,000	85	Satisfactory
VNC	RW 5-23	Runway	6230	27,000	92	Good
VNC	RW 13-31	Runway	6105	413,900	71	Satisfactory
VNC	RW 13-31	Runway	6110	196,950	71	Satisfactory
VNC	RW 13-31	Runway	6115	30,000	65	Fair
VNC	RW 13-31	Runway	6120	20,000	61	Fair
VNC	RW 13-31	Runway	6125	30,000	65	Fair
VNC	RW 13-31	Runway	6130	20,000	60	Fair
VNC	RW 13-31	Runway	6135	26,100	85	Satisfactory
VNC	RW 13-31	Runway	6140	13,050	85	Satisfactory
VNC	RW 13-31	Runway	6145	63,850	91	Good
VNC	RW 13-31	Runway	6150	31,925	94	Good
VNC	TW A	Taxiway	105	55,145	93	Good
VNC	TW A	Taxiway	110	55,883	84	Satisfactory
VNC	TW A	Taxiway	115	52,281	90	Good
VNC	TW A	Taxiway	120	9,988	80	Satisfactory
VNC	TW A	Taxiway	125	5,738	66	Fair
VNC	TW B	Taxiway	220	47,695	94	Good
VNC	TW B	Taxiway	225	12,448	89	Good
VNC	TW B	Taxiway	235	21,767	94	Good
VNC	TW C	Taxiway	315	85,087	93	Good
VNC	TW D	Taxiway	400	38,598	94	Good
VNC	TW D	Taxiway	405	76,359	94	Good
VNC	TW D	Taxiway	410	17,828	88	Good
VNC	TW D	Taxiway	420	109,579	100	Good
VNC	TW E	Taxiway	505	62,102	87	Good
VNC	TW E	Taxiway	510	10,168	85	Satisfactory
VNC	TW E	Taxiway	515	21,560	91	Good
VNC	TW E	Taxiway	520	110,616	100	Good
VNC	TW E	Taxiway	550	9,260	80	Satisfactory
VNC	TW F	Taxiway	450	11,675	94	Good
VNC	TL T-HANG	Taxilane	605	16,734	69	Fair
VNC	TL T-HANG	Taxilane	610	42,622	66	Fair
VNC	TL T-HANG	Taxilane	620	100,062	52	Poor
VNC	TL T-HANG	Taxilane	705	34,474	78	Satisfactory
VNC	TL T-HANG	Taxilane	708	11,446	67	Fair
VNC	TL T-HANG	Taxilane	710	41,684	46	Poor
VNC	TL T-HANG	Taxilane	715	12,768	89	Good
VNC	TL T-HANG	Taxilane	720	5,422	89	Good
VNC	TL T-HANG	Taxilane	725	17,209	92	Good
VNC	TL T-HANG	Taxilane	730	18,001	59	Fair

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VNC	TL T-HANG	Taxilane	735	21,329	94	Good
VNC	AP	Apron	4105	112,335	21	Serious
VNC	AP	Apron	4110	302,352	92	Good
VNC	AP	Apron	4115	34,307	4	Failed
VNC	AP	Apron	4120	58,790	93	Good
VNC	AP	Apron	4125	53,176	89	Good
VNC	AP	Apron	4127	19,630	89	Good
VNC	AP	Apron	4130	6,119	94	Good
VNC	AP	Apron	4140	73,498	90	Good
VNC	AP MID	Apron	4405	166,523	94	Good
VNC	AP RU 13	Apron	5110	19,846	91	Good
VNC	AP RU 23	Apron	5105	26,551	93	Good

Table A.3: Forecasted PCI Values 2023-2032 – Section-Level

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
VNC	RW 5-23	6205	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6210	88	86	84	83	81	79	77	76	74	72	70
VNC	RW 5-23	6215	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6220	91	89	86	84	83	81	79	78	77	75	74
VNC	RW 5-23	6225	85	83	81	80	78	77	76	74	73	72	72
VNC	RW 5-23	6230	92	89	87	85	83	82	80	79	77	76	75
VNC	RW 13-31	6105	71	69	67	66	64	62	60	59	57	55	53
VNC	RW 13-31	6110	71	69	67	66	64	62	60	59	57	55	53
VNC	RW 13-31	6115	65	63	61	60	58	56	54	53	51	49	47
VNC	RW 13-31	6120	61	59	57	56	54	52	50	49	47	45	43
VNC	RW 13-31	6125	65	63	61	60	58	56	54	53	51	49	47
VNC	RW 13-31	6130	60	58	56	55	53	51	49	48	46	44	42
VNC	RW 13-31	6135	85	83	81	80	78	76	74	73	71	69	67
VNC	RW 13-31	6140	85	83	81	80	78	76	74	73	71	69	67
VNC	RW 13-31	6145	91	89	86	84	83	81	79	78	77	75	74
VNC	RW 13-31	6150	94	91	89	87	85	83	81	80	78	77	76
VNC	TW A	105	93	91	89	87	85	83	82	80	78	77	76
VNC	TW A	110	84	82	81	79	78	76	75	74	72	71	70
VNC	TW A	115	90	88	86	84	82	81	79	78	76	75	74
VNC	TW A	120	80	78	77	76	74	73	72	71	70	69	68
VNC	TW A	125	66	65	64	63	62	61	61	60	59	58	58
VNC	TW B	220	94	92	90	88	86	84	82	81	79	78	76
VNC	TW B	225	89	87	85	83	82	80	78	77	76	74	73
VNC	TW B	235	94	92	90	88	86	84	82	81	79	78	76
VNC	TW C	315	93	91	89	87	85	83	82	80	78	77	76
VNC	TW D	400	94	92	90	88	86	84	82	81	79	78	76
VNC	TW D	405	94	92	90	88	86	84	82	81	79	78	76
VNC	TW D	410	88	86	84	82	81	79	78	76	75	74	73
VNC	TW D	420	100	92	90	88	86	84	83	81	79	78	76
VNC	TW E	505	87	85	83	82	80	78	77	76	74	73	72
VNC	TW E	510	85	83	81	80	78	77	76	74	73	72	71
VNC	TW E	515	91	89	87	85	83	82	80	78	77	76	74
VNC	TW E	520	100	96	94	92	89	88	86	84	82	81	79
VNC	TW E	550	80	78	77	76	74	73	72	71	70	69	68
VNC	TW F	450	94	92	90	88	86	84	82	81	79	78	76
VNC	TL T-HANG	605	69	68	67	66	65	65	64	63	63	62	61
VNC	TL T-HANG	610	66	65	64	64	63	62	62	61	61	60	60
VNC	TL T-HANG	620	52	51	51	50	50	49	48	48	47	46	45
VNC	TL T-HANG	705	78	76	75	74	73	71	70	69	68	67	67
VNC	TL T-HANG	708	67	66	65	65	64	63	63	62	61	61	60
VNC	TL T-HANG	710	46	45	44	43	42	41	40	39	37	36	35
VNC	TL T-HANG	715	89	87	85	83	82	80	78	77	76	74	73
VNC	TL T-HANG	720	89	87	85	83	82	80	78	77	76	74	73
VNC	TL T-HANG	725	92	90	88	86	84	82	81	79	78	76	75

Network ID	Branch ID	Section ID	Current PCI	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
VNC	TL T-HANG	730	59	58	58	57	56	55	55	54	53	52	52
VNC	TL T-HANG	735	94	92	90	88	86	84	82	81	79	78	76
VNC	AP	4105	21	20	19	17	16	15	14	13	12	10	9
VNC	AP	4110	92	90	88	85	83	81	79	78	76	74	72
VNC	AP	4115	4	3	2	0	0	0	0	0	0	0	0
VNC	AP	4120	93	91	88	86	84	82	80	78	77	75	73
VNC	AP	4125	89	87	85	83	81	79	77	75	73	72	70
VNC	AP	4127	89	87	84	82	80	78	76	73	71	69	67
VNC	AP	4130	94	92	89	87	85	83	81	79	77	76	74
VNC	AP	4140	90	88	86	84	82	80	78	76	74	72	71
VNC	AP MID	4405	94	92	89	87	85	83	81	79	77	76	74
VNC	AP RU 13	5110	91	89	87	84	82	80	79	77	75	73	71
VNC	AP RU 23	5105	93	91	88	86	84	82	80	78	77	75	73

11/17/2022

Work History Report

Page 1 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA		Branch: AP MID		MID-FIELD APR		Section: 4405	Surface: AC
L.C.D. 1/1/2017	Use: APRON	Rank: P	Length: 153.00 (Ft)	Width: 1075.00 (Ft)	True Area: 166523.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	CR-AC	Complete Reconstruction - AC	979,185.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" MIN P-220	
1/1/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

Network: VENICE MUNICIPA		Branch: AP RU 13		RUN-UP APRON		Section: 5110	Surface: AC
L.C.D. 1/1/2015	Use: APRON	Rank: P	Length: 100.00 (Ft)	Width: 200.00 (Ft)	True Area: 19846.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211 1991: 1.5" P-401 ON 6" P-211 ON 8" P-154 SHELL SUBBASE SOIL: SP	
1/1/1991	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

Network: VENICE MUNICIPA		Branch: AP RU 23		RUN-UP APRON		Section: 5105	Surface: AC
L.C.D. 1/1/2015	Use: APRON	Rank: P	Length: 198.00 (Ft)	Width: 100.00 (Ft)	True Area: 26551.00000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211 1991: 1.5" P-401 ON 6" P-211 ON 8" P-154 SHELL SUBBASE SOIL: SP	
1/1/1991	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>		
1/1/1991	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

Network: VENICE MUNICIPA		Branch: AP		APRON		Section: 4105	Surface: PCC
L.C.D. 1/1/1942	Use: APRON	Rank: P	Length: 18.00 (Ft)	Width: 190.00 (Ft)	True Area: 112335.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/1986	JS-PC	Joint Seal - PCC	0.00	0.00	<input type="checkbox"/>	JOINT SEALING PROJECT CONDU 1942: 6" PCC PAVEMENT SOIL: SP	
1/1/1942	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

Network: VENICE MUNICIPA		Branch: AP		APRON		Section: 4110	Surface: AC
L.C.D. 1/1/2018	Use: APRON	Rank: P	Length: 190.00 (Ft)	Width: 1740.00 (Ft)	True Area: 302352.0000 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2018	CR-AC	Complete Reconstruction - AC	824,590.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" MIN P-219 JOINT SEALING PROJECT CONDU 1942: 6" PCC PAVEMENT SOIL: SP	
1/1/1986	JS-PC	Joint Seal - PCC	0.00	0.00	<input type="checkbox"/>		
1/1/1942	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>		
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>		

11/17/2022

Work History Report

Page 2 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA Branch: AP APRON Section: 4115 Surface: PCC
 L.C.D. 12/25/199 Use: APRON Rank: P Length: 160.00 (Ft) Width: 275.00 (Ft) True Area: 34307.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA Branch: AP APRON Section: 4120 Surface: AC
 L.C.D. 1/1/2018 Use: APRON Rank: P Length: 220.00 (Ft) Width: 275.00 (Ft) True Area: 58790.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2018	CR-AC	Complete Reconstruction - AC	204,280.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" MIN P-219
12/15/1999	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA Branch: AP APRON Section: 4125 Surface: AC
 L.C.D. 1/1/2015 Use: APRON Rank: P Length: 1,280.00 (Ft) Width: 40.00 (Ft) True Area: 53176.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401SP, 8" P211

Network: VENICE MUNICIPA Branch: AP APRON Section: 4127 Surface: AAC
 L.C.D. 1/1/2017 Use: APRON Rank: P Length: 475.00 (Ft) Width: 40.00 (Ft) True Area: 19630.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2017	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1" Mill, Variable Depth P-401 Overlay
1/1/2015	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401SP, 8" P211

Network: VENICE MUNICIPA Branch: AP APRON Section: 4130 Surface: AC
 L.C.D. 1/1/2015 Use: APRON Rank: P Length: 100.00 (Ft) Width: 50.00 (Ft) True Area: 6119.000001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401SP, 8" P211

Network: VENICE MUNICIPA Branch: AP APRON Section: 4140 Surface: AC
 L.C.D. 1/1/2015 Use: APRON Rank: P Length: 180.00 (Ft) Width: 450.00 (Ft) True Area: 73498.00002 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6105 Surface: AAC
 L.C.D. 12/1/2006 Use: RUNWAY Rank: P Length: 4,139.00 (Ft) Width: 100.00 (Ft) True Area: 413900.0001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED SLURRY SEAL COA
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1982: 1.5" P-401 OVERLAY
1/1/1982	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE

11/17/2022

Work History Report

Page 3 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6110 Surface: AAC
 L.C.D. 12/1/2006 Use: RUNWAY Rank: P Length: 8,400.00 (Ft) Width: 25.00 (Ft) True Area: 196950.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED SLURRY SEAL COA
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1982: 1.5" P-401 OVERLAY
1/1/1982	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6115 Surface: APC
 L.C.D. 12/1/2006 Use: RUNWAY Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 30000.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED SLURRY SEAL COA
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1982 1.5" AC OVERLAY
1/1/1982	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6120 Surface: APC
 L.C.D. 12/1/2006 Use: RUNWAY Rank: P Length: 800.00 (Ft) Width: 25.00 (Ft) True Area: 20000.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED SLURRY SEAL COA
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1982: 1.5" AC OVERLAY
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6125 Surface: APC
 L.C.D. 12/1/2006 Use: RUNWAY Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 30000.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED SLURRY SEAL COA
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	1982: 1.5" AC OVERLAY
1/1/1982	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC

11/17/2022

Work History Report

Page 4 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6130 Surface: APC
 L.C.D. 12/1/2006 Use: RUNWAY Rank: P Length: 800.00 (Ft) Width: 25.00 (Ft) True Area: 20000.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	1982: 1.5" AC OVERLAY SOIL: SP 1942: 8" PCC PAVEMENT
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6135 Surface: AAC
 L.C.D. 1/1/2013 Use: RUNWAY Rank: P Length: 1,000.00 (Ft) Width: 100.00 (Ft) True Area: 26100.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED SLURRY SEAL COA 1" ML & 1.5"-4" OL P401 1982: 1.5" P-401 OVERLAY SOIL: SP 1942: 1.5" AC ON 6" LIME ROCK BASE
1/1/2013	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6140 Surface: AAC
 L.C.D. 1/1/2013 Use: RUNWAY Rank: P Length: 500.00 (Ft) Width: 25.00 (Ft) True Area: 13050.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED SLURRY SEAL COA 1" ML & 1.5"-4" OL P401 1982: 1.5" P-401 OVERLAY SOIL: SP 1942: 1.5" AC ON 6" LIME ROCK BASE
1/1/2013	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	1.50	<input checked="" type="checkbox"/>	
1/1/1982	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6145 Surface: AC
 L.C.D. 5/9/2017 Use: RUNWAY Rank: P Length: 639.00 (Ft) Width: 100.00 (Ft) True Area: 63850.00001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211

Network: VENICE MUNICIPA Branch: RW 13-31 RUNWAY 13-31 Section: 6150 Surface: AC
 L.C.D. 5/9/2017 Use: RUNWAY Rank: P Length: 639.00 (Ft) Width: 50.00 (Ft) True Area: 31925.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211

11/17/2022

Work History Report

Page 5 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA Branch: RW 5-23 RUNWAY 5-23 Section: 6205 Surface: AC
 L.C.D. 1/1/2013 Use: RUNWAY Rank: P Length: 4,250.00 (Ft) Width: 60.00 (Ft) True Area: 255000.0000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	PARTIAL RECON: 4" P-401, 5" P-21
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA Branch: RW 5-23 RUNWAY 5-23 Section: 6210 Surface: AAC
 L.C.D. 1/1/2013 Use: RUNWAY Rank: P Length: 4,250.00 (Ft) Width: 90.00 (Ft) True Area: 382500.0001 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1" ML & VAR 1.5" TO 4" OL
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA Branch: RW 5-23 RUNWAY 5-23 Section: 6215 Surface: AC
 L.C.D. 1/1/2013 Use: RUNWAY Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 18000.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1986	JS-PC	Joint Seal - PCC	0.00	0.00	<input type="checkbox"/>	1986: JOINT SEAL PROJECT
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA Branch: RW 5-23 RUNWAY 5-23 Section: 6220 Surface: AC
 L.C.D. 1/1/2013 Use: RUNWAY Rank: P Length: 800.00 (Ft) Width: 25.00 (Ft) True Area: 27000.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1986	JS-PC	Joint Seal - PCC	0.00	0.00	<input type="checkbox"/>	1986: JOINT SEAL PROJECT
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA Branch: RW 5-23 RUNWAY 5-23 Section: 6225 Surface: AC
 L.C.D. 1/1/2013 Use: RUNWAY Rank: P Length: 300.00 (Ft) Width: 100.00 (Ft) True Area: 18000.00000 (SqFt)

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1986	JS-PC	Joint Seal - PCC	0.00	0.00	<input type="checkbox"/>	1986: JOINT SEAL PROJECT
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

11/17/2022

Work History Report

Page 6 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA		Branch: RW 5-23		Section: 6230		Surface: AC
L.C.D. 1/1/2013	Use: RUNWAY	Rank: P	Length: 800.00 (Ft)	Width: 25.00 (Ft)	True Area: 27000.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1986	JS-PC	Joint Seal - PCC	0.00	0.00	<input type="checkbox"/>	1986: JOINT SEAL PROJECT
1/1/1942	IMPORT ED	BUILT	0.00	8.00	<input checked="" type="checkbox"/>	1942: 8" PCC PAVEMENT
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA		Branch: TL T-HANG		Section: 605		Surface: AC
L.C.D. 1/1/2003	Use: TAXILAN	Rank: P	Length: 490.00 (Ft)	Width: 33.00 (Ft)	True Area: 16734.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA		Branch: TL T-HANG		Section: 610		Surface: AC
L.C.D. 1/1/2003	Use: TAXILAN	Rank: P	Length: 490.00 (Ft)	Width: 40.00 (Ft)	True Area: 42622.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA		Branch: TL T-HANG		Section: 620		Surface: AC
L.C.D. 12/25/199	Use: TAXILAN	Rank: P	Length: 2,795.00 (Ft)	Width: 35.00 (Ft)	True Area: 100062.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1994	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA		Branch: TL T-HANG		Section: 705		Surface: AC
L.C.D. 1/1/2003	Use: TAXILAN	Rank: P	Length: 950.00 (Ft)	Width: 35.00 (Ft)	True Area: 34474.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2003	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	
1/1/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA		Branch: TL T-HANG		Section: 708		Surface: AC
L.C.D. 12/25/199	Use: TAXILAN	Rank: P	Length: 370.00 (Ft)	Width: 30.00 (Ft)	True Area: 11446.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1997	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA		Branch: TL T-HANG		Section: 710		Surface: AC
L.C.D. 12/25/199	Use: TAXILAN	Rank: P	Length: 1,320.00 (Ft)	Width: 25.00 (Ft)	True Area: 41684.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
12/25/1994	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

11/17/2022

Work History Report

Page 7 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA Branch: TL T-HANG T-HANGAR TAX Section: 715 Surface: AC L.C.D. 1/1/2012 Use: TAXILAN Rank: P Length: 515.00 (Ft) Width: 25.00 (Ft) True Area: 12768.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401SP, 6" LIMEROCK BASE, O

Network: VENICE MUNICIPA Branch: TL T-HANG T-HANGAR TAX Section: 720 Surface: AC L.C.D. 1/1/2012 Use: TAXILAN Rank: P Length: 150.00 (Ft) Width: 35.00 (Ft) True Area: 5422.000001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401SP, 6" LIMEROCK BASE, O

Network: VENICE MUNICIPA Branch: TL T-HANG T-HANGAR TAX Section: 725 Surface: AC L.C.D. 1/1/2012 Use: TAXILAN Rank: P Length: 680.00 (Ft) Width: 25.00 (Ft) True Area: 17209.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2012	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	2" P-401SP, 6" LIMEROCK BASE, O

Network: VENICE MUNICIPA Branch: TL T-HANG T-HANGAR TAX Section: 730 Surface: AAC L.C.D. 11/1/2013 Use: TAXILAN Rank: P Length: 600.00 (Ft) Width: 25.00 (Ft) True Area: 18001.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
11/1/2013	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	1"-2" MILL AND OVERLAY
12/25/1994	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA Branch: TL T-HANG T-HANGAR TAX Section: 735 Surface: AC L.C.D. 1/1/2018 Use: TAXILAN Rank: P Length: 835.00 (Ft) Width: 24.00 (Ft) True Area: 21329.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2018	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	2" F-334 SURFACE COURSE, OVE

Network: VENICE MUNICIPA Branch: TW A TAXIWAY A Section: 105 Surface: AC L.C.D. 1/1/2015 Use: TAXIWAY Rank: P Length: 1,395.00 (Ft) Width: 35.00 (Ft) True Area: 55145.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	CR-AC	Complete Reconstruction - AC	0.00	4.00	<input checked="" type="checkbox"/>	TW REALIGN 4" P-401SP, 8" P210, 1986: 2" AC OVERLAY
1/1/1986	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SIOL: SP
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE

11/17/2022

Work History Report

Page 8 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA		Branch: TW A		TAXIWAY A		Section: 110	Surface: AC
L.C.D. 1/1/2015	Use: TAXIWAY	Rank: P	Length: 1,450.00 (Ft)	Width: 35.00 (Ft)	True Area: 55883.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	TW REALIGN 4" P-401SP, 8" P211	
1/1/1986	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1986: 2" AC OVERLAY	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1942	IMPORT ED	BUILT	0.00	6.00	<input checked="" type="checkbox"/>	1942: 6" PCC PAVEMENT	

Network: VENICE MUNICIPA		Branch: TW A		TAXIWAY A		Section: 115	Surface: AC
L.C.D. 1/1/2015	Use: TAXIWAY	Rank: P	Length: 1,333.00 (Ft)	Width: 50.00 (Ft)	True Area: 52281.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2015	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	TW REALIGN 4" P-401SP, 8" P210,	
1/1/1986	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1986: 2" AC OVERLAY	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE	

Network: VENICE MUNICIPA		Branch: TW A		TAXIWAY A		Section: 120	Surface: AC
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 200.00 (Ft)	Width: 50.00 (Ft)	True Area: 9988.000003 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 5" BASE P-210, 4" EXISTI	

Network: VENICE MUNICIPA		Branch: TW A		TAXIWAY A		Section: 125	Surface: AAC
L.C.D. 12/1/2006	Use: TAXIWAY	Rank: P	Length: 125.00 (Ft)	Width: 50.00 (Ft)	True Area: 5738.000001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
12/1/2006	ML-OVL	Mill and Overlay	0.00	0.00	<input checked="" type="checkbox"/>	RW ML & OL	
1/1/1986	IMPORT ED	OVERLAY	0.00	2.00	<input checked="" type="checkbox"/>	1986: 2" AC OVERLAY	
1/1/1986	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP	
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE	

Network: VENICE MUNICIPA		Branch: TW B		TAXIWAY B		Section: 220	Surface: AC
L.C.D. 1/1/2017	Use: TAXIWAY	Rank: P	Length: 1,280.00 (Ft)	Width: 35.00 (Ft)	True Area: 47695.00001 (SqFt)		
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments	
1/1/2017	CR-AC	Complete Reconstruction - AC	151,620.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 6" MIN P-220	
1/1/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>		

11/17/2022

Work History Report

Page 9 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA Branch: TW B TAXIWAY B Section: 225 Surface: AC L.C.D. 1/1/2013 Use: TAXIWAY Rank: P Length: 350.00 (Ft) Width: 35.00 (Ft) True Area: 12448.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 5" BASE P-210, 4" EXISTI

Network: VENICE MUNICIPA Branch: TW B TAXIWAY B Section: 235 Surface: AC L.C.D. 5/9/2017 Use: TAXIWAY Rank: P Length: 430.00 (Ft) Width: 45.00 (Ft) True Area: 21767.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	CR-AC	Complete Reconstruction - AC	115,425.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211
1/1/1942	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA Branch: TW C TAXIWAY C Section: 315 Surface: AC L.C.D. 1/1/2015 Use: TAXIWAY Rank: P Length: 1,830.00 (Ft) Width: 35.00 (Ft) True Area: 85087.00002 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1970	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1970: 1.5" AC - SRD TYPE I ON 6" P-211 ON 8" P-154 SHELL SUBBASE
1/1/1970	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA Branch: TW D TAXIWAY D Section: 400 Surface: AC L.C.D. 5/9/2017 Use: TAXIWAY Rank: P Length: 823.00 (Ft) Width: 35.00 (Ft) True Area: 38598.00001 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211

Network: VENICE MUNICIPA Branch: TW D TAXIWAY D Section: 405 Surface: AC L.C.D. 5/9/2017 Use: TAXIWAY Rank: P Length: 1,910.00 (Ft) Width: 35.00 (Ft) True Area: 76359.00002 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	CR-AC	Complete Reconstruction - AC	373,055.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1970	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1970: 1.5" AC - SRD TYPE I ON 6" P-211 ON 8" P-154 SHELL SUBBASE
1/1/1970	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA Branch: TW D TAXIWAY D Section: 410 Surface: AC L.C.D. 1/1/2013 Use: TAXIWAY Rank: P Length: 340.00 (Ft) Width: 35.00 (Ft) True Area: 17828.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 5" BASE P-210, 4" EXISTI

Network: VENICE MUNICIPA Branch: TW D TAXIWAY D Section: 420 Surface: AC L.C.D. 1/1/2020 Use: TAXIWAY Rank: P Length: 2,450.00 (Ft) Width: 35.00 (Ft) True Area: 109579.00000 (SqFt)						
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2020	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	

11/17/2022

Work History Report

Page 10 of 11

Pavement Database: FDOT

Network: VENICE MUNICIPA		Branch: TW E	TAXIWAY E	Section: 505	Surface:AC	
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 1,722.00 (Ft)	Width: 35.00 (Ft)	True Area: 62102.00001 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1970	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1970: 1.5" AC - SRD TYPE-I ON 6" P-211 ON 8" P-154 SHELL SUBBASE
1/1/1970	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA		Branch: TW E	TAXIWAY E	Section: 510	Surface:AC	
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 175.00 (Ft)	Width: 50.00 (Ft)	True Area: 10168.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	ST-SC	Surface Treatment - Seal Coat	0.00	0.00	<input type="checkbox"/>	EMULSIFIED PLUS SEAL COAT
1/1/2013	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 5" BASE P-210, EXISTING

Network: VENICE MUNICIPA Branch: TW E TAXIWAY E Section: 515 Surface:AC						
L.C.D. 1/1/2015		Use: TAXIWAY	Rank: P	Length: 415.00 (Ft)	Width: 40.00 (Ft)	True Area: 21560.00000 (SqFt)
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2015	NU-IN	New Construction - Initial	0.00	0.00	<input checked="" type="checkbox"/>	

Network: VENICE MUNICIPA		Branch: TW E	TAXIWAY E	Section: 520	Surface:AC	
L.C.D. 10/1/2021	Use: TAXIWAY	Rank: P	Length: 2,392.00 (Ft)	Width: 35.00 (Ft)	True Area: 110616.0000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
10/1/2021	NC-AC	New Construction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-211, 12" P-152

Network: VENICE MUNICIPA		Branch: TW E	TAXIWAY E	Section: 550	Surface:AC	
L.C.D. 1/1/2013	Use: TAXIWAY	Rank: P	Length: 208.00 (Ft)	Width: 37.00 (Ft)	True Area: 9260.000002 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
1/1/2013	CR-AC	Complete Reconstruction - AC	0.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" BASE P-210
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Network: VENICE MUNICIPA		Branch: TW F	TAXIWAY F	Section: 450	Surface:AC	
L.C.D. 5/9/2017	Use: TAXIWAY	Rank: P	Length: 205.00 (Ft)	Width: 41.00 (Ft)	True Area: 11675.00000 (SqFt)	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R	Comments
5/9/2017	CR-AC	Complete Reconstruction - AC	63,935.00	0.00	<input checked="" type="checkbox"/>	4" P-401, 8" P-210
1/1/1942	IMPORT ED	BUILT	0.00	1.50	<input checked="" type="checkbox"/>	1942: 1.5" AC ON 6" LIME ROCK BASE
1/1/1942	IMPORT ED	OVERLAY	0.00	0.00	<input checked="" type="checkbox"/>	SOIL: SP

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	27	2,352,114.00	3.93	2.98
Complete Reconstruction - AC	20	1,396,316.00	1.00	1.73
Joint Seal - PCC	6	504,687.00	0.00	0.00
Mill and Overlay	14	1,215,019.00	0.00	0.00
New Construction - AC	6	375,897.00	0.00	0.00
New Construction - Initial	26	931,015.00	0.00	0.00
OVERLAY	38	3,251,161.00	0.53	0.79
Surface Treatment - Seal Coat	9	760,168.00	0.00	0.00

11/17/2022

Branch Condition Report

Page 1 of 2

Pavement Database: FDOT

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	Standard Deviation PCI	Weighted Average PCI
AP	8	2,623.00	382.50	660,207.00	APRON	71.50	34.37	74.90
AP MID	1	153.00	1,075.00	166,523.00	APRON	94.00	0.00	94.00
AP RU 13	1	100.00	200.00	19,846.00	APRON	91.00	0.00	91.00
AP RU 23	1	198.00	100.00	26,551.00	APRON	93.00	0.00	93.00
RW 13-31	10	17,517.00	65.00	845,775.00	RUNWAY	74.80	12.12	73.10
RW 5-23	6	10,700.00	66.67	727,500.00	RUNWAY	87.67	2.92	87.06
TL T-HANG	11	9,195.00	30.18	321,751.00	TAXILANE	72.82	15.97	64.69
TW A	5	4,503.00	44.00	179,035.00	TAXIWAY	82.60	9.46	87.72
TW B	3	2,060.00	38.33	81,910.00	TAXIWAY	92.33	2.36	93.24
TW C	1	1,830.00	35.00	85,087.00	TAXIWAY	93.00	0.00	93.00
TW D	4	5,523.00	35.00	242,364.00	TAXIWAY	94.00	4.24	96.27
TW E	5	4,912.00	39.40	213,706.00	TAXIWAY	88.60	6.71	93.73
TW F	1	205.00	41.00	11,675.00	TAXIWAY	94.00	0.00	94.00

11/17/2022

Branch Condition Report

Page 2 of 2

Pavement Database: FDOT

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average STD PCI	Weighted Average PCI
APRON	11	873,127.00	77.27	30.80	79.46
RUNWAY	16	1,573,275.00	79.63	11.57	79.56
TAXILANE	11	321,751.00	72.82	15.97	64.69
TAXIWAY	19	813,777.00	89.26	7.74	93.04
ALL	57	3,581,930.00	81.07	18.13	81.26

Pavement Database: FDOT

NetworkId: VNC

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
AP	4105	1/1/1942	PCC	APRON	P	0	112,335.00	5/25/2022	80	21
AP	4110	1/1/2018	AC	APRON	P	0	302,352.00	5/25/2022	4	92
AP	4115	12/25/1999	PCC	APRON	P	0	34,307.00	5/25/2022	23	4
AP	4120	1/1/2018	AC	APRON	P	0	58,790.00	5/25/2022	4	93
AP	4125	1/1/2015	AC	APRON	P	0	53,176.00	5/25/2022	7	89
AP	4127	1/1/2017	AAC	APRON	P	0	19,630.00	5/25/2022	5	89
AP	4130	1/1/2015	AC	APRON	P	0	6,119.00	5/25/2022	7	94
AP	4140	1/1/2015	AC	APRON	P	0	73,498.00	5/25/2022	7	90
AP MID	4405	1/1/2017	AC	APRON	P	0	166,523.00	5/25/2022	5	94
AP RU 13	5110	1/1/2015	AC	APRON	P	0	19,846.00	5/25/2022	7	91
AP RU 23	5105	1/1/2015	AC	APRON	P	0	26,551.00	5/25/2022	7	93
RW 13-31	6105	12/1/2006	AAC	RUNWAY	P	0	413,900.00	5/25/2022	16	71
RW 13-31	6110	12/1/2006	AAC	RUNWAY	P	0	196,950.00	5/25/2022	16	71
RW 13-31	6115	12/1/2006	APC	RUNWAY	P	0	30,000.00	5/25/2022	16	65
RW 13-31	6120	12/1/2006	APC	RUNWAY	P	0	20,000.00	5/25/2022	16	61
RW 13-31	6125	12/1/2006	APC	RUNWAY	P	0	30,000.00	5/25/2022	16	65
RW 13-31	6130	12/1/2006	APC	RUNWAY	P	0	20,000.00	5/25/2022	16	60
RW 13-31	6135	1/1/2013	AAC	RUNWAY	P	0	26,100.00	5/25/2022	9	85
RW 13-31	6140	1/1/2013	AAC	RUNWAY	P	0	13,050.00	5/25/2022	9	85
RW 13-31	6145	5/9/2017	AC	RUNWAY	P	0	63,850.00	5/25/2022	5	91
RW 13-31	6150	5/9/2017	AC	RUNWAY	P	0	31,925.00	5/25/2022	5	94
RW 5-23	6205	1/1/2013	AC	RUNWAY	P	0	255,000.00	5/25/2022	9	85
RW 5-23	6210	1/1/2013	AAC	RUNWAY	P	0	382,500.00	5/25/2022	9	88
RW 5-23	6215	1/1/2013	AC	RUNWAY	P	0	18,000.00	5/25/2022	9	85
RW 5-23	6220	1/1/2013	AC	RUNWAY	P	0	27,000.00	5/25/2022	9	91
RW 5-23	6225	1/1/2013	AC	RUNWAY	P	0	18,000.00	5/25/2022	9	85
RW 5-23	6230	1/1/2013	AC	RUNWAY	P	0	27,000.00	5/25/2022	9	92
TL T-HANG	605	1/1/2003	AC	TAXILANE	P	0	16,734.00	5/25/2022	19	69
TL T-HANG	610	1/1/2003	AC	TAXILANE	P	0	42,622.00	5/25/2022	19	66
TL T-HANG	620	12/25/1994	AC	TAXILANE	P	0	100,062.00	5/25/2022	28	52
TL T-HANG	705	1/1/2003	AC	TAXILANE	P	0	34,474.00	5/25/2022	19	78
TL T-HANG	708	12/25/1997	AC	TAXILANE	P	0	11,446.00	5/25/2022	25	67
TL T-HANG	710	12/25/1994	AC	TAXILANE	P	0	41,684.00	5/25/2022	28	46
TL T-HANG	715	1/1/2012	AC	TAXILANE	P	0	12,768.00	5/25/2022	10	89
TL T-HANG	720	1/1/2012	AC	TAXILANE	P	0	5,422.00	5/25/2022	10	89
TL T-HANG	725	1/1/2012	AC	TAXILANE	P	0	17,209.00	5/25/2022	10	92
TL T-HANG	730	11/1/2013	AAC	TAXILANE	P	0	18,001.00	5/25/2022	9	59
TL T-HANG	735	1/1/2018	AC	TAXILANE	P	0	21,329.00	5/25/2022	4	94
TW A	105	1/1/2015	AC	TAXIWAY	P	0	55,145.00	5/25/2022	7	93
TW A	110	1/1/2015	AC	TAXIWAY	P	0	55,883.00	5/25/2022	7	84
TW A	115	1/1/2015	AC	TAXIWAY	P	0	52,281.00	5/25/2022	7	90
TW A	120	1/1/2013	AC	TAXIWAY	P	0	9,988.00	5/25/2022	9	80
TW A	125	12/1/2006	AAC	TAXIWAY	P	0	5,738.00	5/25/2022	16	66
TW B	220	1/1/2017	AC	TAXIWAY	P	0	47,695.00	5/25/2022	5	94
TW B	225	1/1/2013	AC	TAXIWAY	P	0	12,448.00	5/25/2022	9	89
TW B	235	5/9/2017	AC	TAXIWAY	P	0	21,767.00	5/25/2022	5	94
TW C	315	1/1/2015	AC	TAXIWAY	P	0	85,087.00	5/25/2022	7	93
TW D	400	5/9/2017	AC	TAXIWAY	P	0	38,598.00	5/25/2022	5	94
TW D	405	5/9/2017	AC	TAXIWAY	P	0	76,359.00	5/25/2022	5	94
TW D	410	1/1/2013	AC	TAXIWAY	P	0	17,828.00	5/25/2022	9	88

TW D	420	1/1/2020	AC	TAXIWAY	P	0	109,579.00	1/1/2020	0	100
TW E	505	1/1/2013	AC	TAXIWAY	P	0	62,102.00	5/25/2022	9	87
TW E	510	1/1/2013	AC	TAXIWAY	P	0	10,168.00	5/25/2022	9	85
TW E	515	1/1/2015	AC	TAXIWAY	P	0	21,560.00	5/25/2022	7	91
TW E	520	10/1/2021	AC	TAXIWAY	P	0	110,616.00	10/1/2021	0	100
TW E	550	1/1/2013	AC	TAXIWAY	P	0	9,260.00	5/25/2022	9	80
TW F	450	5/9/2017	AC	TAXIWAY	P	0	11,675.00	5/25/2022	5	94

Pavement Database: FDOT

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	Standard Deviation PCI	Weighted Average PCI
00-02		220,195.00	2	100.00	0.00	100.00
03-05	5	860,493.00	12	93.08	1.55	92.89
06-10	8	1,390,990.00	28	87.21	6.56	87.72
16-20	17	810,418.00	10	67.20	5.02	70.00
21-25	24	45,753.00	2	35.50	31.50	19.76
26-30	28	141,746.00	2	49.00	3.00	50.24
50+	80	112,335.00	1	21.00	0.00	21.00
ALL	11	3,581,930.00	57	81.07	18.13	81.26



Appendix B: Maintenance and Rehabilitation Planning Needs



Table B.1: Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
VNC	RW 5-23	6205	RAVELING	Low	1,328	SF	0.5%	Preventive	Surface Seal	1,328	SF	\$ 0.75	\$ 1,000
VNC	RW 5-23	6205	WEATHERING	Medium	58,645	SF	23.0%	Preventive	Surface Seal	58,645	SF	\$ 0.75	\$ 43,990
VNC	RW 5-23	6210	WEATHERING	Medium	54,056	SF	14.1%	Preventive	Surface Seal	54,056	SF	\$ 0.75	\$ 40,550
VNC	RW 5-23	6215	WEATHERING	Medium	4,500	SF	25.0%	Preventive	Surface Seal	4,500	SF	\$ 0.75	\$ 3,380
VNC	RW 5-23	6220	WEATHERING	Medium	1,350	SF	5.0%	Preventive	Surface Seal	1,350	SF	\$ 0.75	\$ 1,020
VNC	RW 5-23	6225	WEATHERING	Medium	4,500	SF	25.0%	Preventive	Surface Seal	4,500	SF	\$ 0.75	\$ 3,380
VNC	RW 5-23	6230	WEATHERING	Medium	2,700	SF	10.0%	Preventive	Surface Seal	2,700	SF	\$ 0.75	\$ 2,030
VNC	RW 13-31	6105	RAVELING	Low	27,756	SF	6.7%	Preventive	Surface Seal	27,756	SF	\$ 0.75	\$ 20,820
VNC	RW 13-31	6105	WEATHERING	Medium	366,180	SF	88.5%	Preventive	Surface Seal	366,180	SF	\$ 0.75	\$ 274,640
VNC	RW 13-31	6110	RAVELING	Low	8,758	SF	4.5%	Preventive	Surface Seal	8,758	SF	\$ 0.75	\$ 6,570
VNC	RW 13-31	6110	WEATHERING	Medium	102,059	SF	51.8%	Preventive	Surface Seal	102,059	SF	\$ 0.75	\$ 76,550
VNC	RW 13-31	6135	WEATHERING	Medium	3,915	SF	15.0%	Preventive	Surface Seal	3,915	SF	\$ 0.75	\$ 2,940
VNC	RW 13-31	6140	WEATHERING	Medium	1,305	SF	10.0%	Preventive	Surface Seal	1,305	SF	\$ 0.75	\$ 980
VNC	TW A	115	WEATHERING	Medium	1,260	SF	2.4%	Preventive	Surface Seal	1,261	SF	\$ 0.75	\$ 950
VNC	TW A	120	WEATHERING	Medium	9,988	SF	100.0%	Preventive	Surface Seal	9,988	SF	\$ 0.75	\$ 7,500
VNC	TW B	225	WEATHERING	Medium	1,245	SF	10.0%	Preventive	Surface Seal	1,245	SF	\$ 0.75	\$ 940
VNC	TW D	410	WEATHERING	Medium	2,673	SF	15.0%	Preventive	Surface Seal	2,673	SF	\$ 0.75	\$ 2,010
VNC	TW E	505	WEATHERING	Medium	10,311	SF	16.6%	Preventive	Surface Seal	10,311	SF	\$ 0.75	\$ 7,740
VNC	TW E	510	WEATHERING	Medium	1,525	SF	15.0%	Preventive	Surface Seal	1,525	SF	\$ 0.75	\$ 1,150
VNC	TW E	515	WEATHERING	Medium	1,076	SF	5.0%	Preventive	Surface Seal	1,075	SF	\$ 0.75	\$ 810
VNC	TW E	550	WEATHERING	Medium	1,323	SF	14.3%	Preventive	Surface Seal	1,323	SF	\$ 0.75	\$ 1,000
VNC	TL T-HANG	705	RAVELING	Low	3,451	SF	10.0%	Preventive	Surface Seal	3,451	SF	\$ 0.75	\$ 2,590
VNC	AP RU 23	5105	RAVELING	Low	34	SF	0.1%	Preventive	Surface Seal	34	SF	\$ 0.75	\$ 30
VNC	TL T-HANG	620	RAVELING	High	351	SF	0.4%	Stopgap	AC Partial-Depth Patching	351	SF	\$ 4.75	\$ 1,670
VNC	AP	4105	LINEAR CR	Medium	1	Slabs	78.2%	Stopgap	PCC Crack Sealing	481	LF	\$ 7.00	\$ 3,370
VNC	AP	4105	LINEAR CR	High	0	Slabs	3.6%	Stopgap	PCC Crack Sealing	22	LF	\$ 7.00	\$ 160
VNC	AP	4105	LARGE PATCH	High	0	Slabs	1.8%	Stopgap	PCC Full-Depth Patching	11	SF	\$ 65.00	\$ 700
VNC	AP	4105	SHAT. SLAB	Medium	0	Slabs	1.8%	Stopgap	PCC Crack Sealing	22	LF	\$ 7.00	\$ 160
VNC	AP	4105	JOINT SPALL	Medium	0	Slabs	9.1%	Stopgap	PCC Partial-Depth Patching	1	SF	\$ 169.00	\$ 100
VNC	AP	4115	CORNER BREAK	High	6	Slabs	6.7%	Stopgap	PCC Full-Depth Patching	196	SF	\$ 65.00	\$ 12,740
VNC	AP	4115	LINEAR CR	Medium	42	Slabs	46.7%	Stopgap	PCC Crack Sealing	903	LF	\$ 7.00	\$ 6,320
VNC	AP	4115	JT SEAL DMG	High	91	Slabs	100.0%	Stopgap	PCC Joint Seal	4,552	LF	\$ 4.25	\$ 19,350
VNC	AP	4115	SHAT. SLAB	Medium	36	Slabs	40.0%	Stopgap	PCC Crack Sealing	1,547	LF	\$ 7.00	\$ 10,830
VNC	AP	4115	JOINT SPALL	Medium	18	Slabs	20.0%	Stopgap	PCC Partial-Depth Patching	117	SF	\$ 169.00	\$ 19,870
VNC	AP	4115	JOINT SPALL	High	6	Slabs	6.7%	Stopgap	PCC Partial-Depth Patching	50	SF	\$ 169.00	\$ 8,280
VNC	AP	4115	CORNER SPALL	Medium	6	Slabs	6.7%	Stopgap	PCC Partial-Depth Patching	16	SF	\$ 169.00	\$ 2,760

Table B.2: Section-Level 10-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2023	VNC	RW 13-31	6105	AAC	413,900	69	AC Rehabilitation	\$ 4,346,000
2023	VNC	RW 13-31	6110	AAC	196,950	69	AC Rehabilitation	\$ 2,068,000
2023	VNC	RW 13-31	6115	APC	30,000	63	AC Rehabilitation	\$ 315,000
2023	VNC	RW 13-31	6120	APC	20,000	59	AC Rehabilitation	\$ 210,000
2023	VNC	RW 13-31	6125	APC	30,000	63	AC Rehabilitation	\$ 315,000
2023	VNC	RW 13-31	6130	APC	20,000	58	AC Rehabilitation	\$ 210,000
2023	VNC	TW A	125	AAC	5,738	65	AC Rehabilitation	\$ 61,000
2023	VNC	TL T-HANG	605	AC	16,734	68	AC Rehabilitation	\$ 176,000
2023	VNC	TL T-HANG	610	AC	42,622	65	AC Rehabilitation	\$ 448,000
2023	VNC	TL T-HANG	620	AC	100,062	51	AC Reconstruction	\$ 1,852,000
2023	VNC	TL T-HANG	708	AC	11,446	66	AC Rehabilitation	\$ 121,000
2023	VNC	TL T-HANG	710	AC	41,684	45	AC Reconstruction	\$ 772,000
2023	VNC	TL T-HANG	730	AAC	18,001	58	AC Rehabilitation	\$ 190,000
2023	VNC	AP	4105	PCC	112,335	20	PCC Reconstruction	\$ 5,056,000
2023	VNC	AP	4115	PCC	34,307	3	PCC Reconstruction	\$ 1,544,000
2029	VNC	TL T-HANG	705	AC	34,474	69	AC Rehabilitation	\$ 486,000
2030	VNC	TW A	120	AC	9,988	70	AC Rehabilitation	\$ 148,000
2030	VNC	TW E	550	AC	9,260	70	AC Rehabilitation	\$ 137,000
2031	VNC	RW 13-31	6135	AAC	26,100	69	AC Rehabilitation	\$ 405,000
2031	VNC	RW 13-31	6140	AAC	13,050	69	AC Rehabilitation	\$ 203,000
2031	VNC	AP	4127	AAC	19,630	69	AC Rehabilitation	\$ 305,000
2032	VNC	AP	4125	AC	53,176	70	AC Rehabilitation	\$ 867,000

**All planning cost values have been rounded up to the nearest thousand dollars.*




Appendix C: Technical Exhibits





AAC RW 13-31 6135 2 6	AC TW B 220 2 12	AC TW B 235 1 4	AC TW C 315 3 21	AC TW D 410 1 4
AC TW D 420 0 21	AC TW E 510 2 2	AC TW E 515 1 5	AC TL T-HANG 605 1 4	AC TL T-HANG 610 1 9
AC TL T-HANG 620 3 20	AC TL T-HANG 705 1 8	AC TL T-HANG 708 1 3	AC TL T-HANG 710 2 11	AC TL T-HANG 715 1 4
AC TL T-HANG 720 1 1	AC TL T-HANG 725 1 5	AAC TL T-HANG 730 1 5	AC TL T-HANG 735 1 5	AC AP MID 4405 5 35




LEGEND

- RW 13-31** — TYPICAL RUNWAY BRANCH ID
- TW A** — TYPICAL TAXIWAY BRANCH ID
- AP S** — TYPICAL APRON BRANCH ID
- AAC** — PAVEMENT SURFACE TYPE
- AP MAIN** — PAVEMENT BRANCH ID
- 4105** — SECTION NUMBER
- 10 | 100** — NUMBER OF SAMPLE UNITS IN SECTION
NUMBER OF SAMPLE UNITS TO BE INSPECTED
- AAC**
AP MAIN
4105
0 | 100 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
- 100** — INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 138
AC: 134 PCC: 4

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.




RECENT & ANTICIPATED CONSTRUCTION ACTIVITY		
CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION
2017	AP	Mill and Overlay 1" Mill, Variable Depth P-401 Overlay
	AP MID, TW B	Complete Reconstruction - AC 4" P-401, 6" MIN P-220
	RW 13-31, TW D	New Construction - AC 4" P-401, 8" P-211
	TW B	Complete Reconstruction - AC 4" P-401, 8" P-211
	TW D, TW F	Complete Reconstruction - AC 4" P-401, 8" P-210
2018	AP	Complete Reconstruction - AC 4" P-401, 6" MIN P-219
	TL T-HANG	New Construction - AC 2" F-334 SURFACE COURSE, OVER 6" P-211
2020	TW D	New Construction - AC
2021	TW E	New Construction - AC 4" P-401, 8" P-211, 12" P-152

LEGEND

TYPICAL RUNWAY BRANCH ID
 TYPICAL TAXIWAY BRANCH ID
 TYPICAL APRON BRANCH ID

PROJECT YEAR

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.




LEGEND

RW 13-31 — TYPICAL RUNWAY BRANCH ID
TW A — TYPICAL TAXIWAY BRANCH ID
AP S — TYPICAL APRON BRANCH ID

AGE AT INSPECTION

	0-5 Years
	6-10 Years
	11-15 Years
	16-20 Years
	> 20 Years

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



LEGEND


- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID

2022 PAVEMENT CONDITION INDEX

	PCI 86-100 Good
	PCI 71-85 Satisfactory
	PCI 56-70 Fair
	PCI 41-55 Poor
	PCI 26-40 Very Poor
	PCI 11-25 Serious
	PCI 0-10 Failed

"SECTION ID" "PCI VALUE"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



LEGEND

— TYPICAL RUNWAY BRANCH ID
— TYPICAL TAXIWAY BRANCH ID
— TYPICAL APRON BRANCH ID

PROGRAM YEAR

2023	2028
2024	2029
2025	2030
2026	2031
2027	2032

"BRANCH," "SECTION"
"YEAR," "REHAB ACTIVITY"
"EST. COST"

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.



Appendix D: Inspection Photograph Documentation





RW 5-23, Section 6205, Sample Unit 115 – Vicinity



RW 5-23, Section 6205, Sample Unit 132 – Vicinity



RW 13-31, Section 6105, Sample Unit 336 – Longitudinal & Transverse Cracking



RW 13-31, Section 6110, Sample Unit 128 – Longitudinal & Transverse Cracking and Swelling



RW 13-31, Section 6125, Sample Unit 395 – Joint Reflection Cracking



TW A, Section 110, Sample Unit 125 – Vicinity



TW A, Section 125, Sample Unit 100 – Vicinity



TW D, Section 410, Sample Unit 420 – Weathering



TW E, Section 515, Sample Unit 125 – Vicinity



TL T-HANG, Section 710, Sample Unit 150 – Patching



AP, Section 4105, Sample Unit 513 – Linear Cracking



AP, Section 4115, Sample Unit 300 – Vicinity



Appendix E: Inspection Distress Details



Re-Inspection Report

FDOT

Generated Date 11/17/2022

Page 1 of 58

Network:	VNC	Name:	VENICE MUNICIPAL AIRPORT		
Branch:	AP	Name:	APRON	Use:	APRON
Area:	660,207 SqFt				
Section:	4105	of	8	From:	-
To:				-	Last Const.:
1/1/1942					
Surface:	PCC	Family:	CA653-RL-AP-PCC	Zone:	
Category:	Rank: P				
Area:	112,335 SqFt	Length:	18 Ft	Width:	190 Ft
Slabs:	1	Slab Length:	1,110 Ft	Slab Width:	120 Ft
Joint Length:	Ft				
Shoulder:		Street Type:		Grade:	0
Lanes:	0				
Section Comments:					
Work Date:	1/1/1942	Work Type:	BUILT	Code:	IMPORTED
Is Major M&R:	True				
Work Date:	1/1/1942	Work Type:	OVERLAY	Code:	IMPORTED
Is Major M&R:	True				
Work Date:	1/1/1986	Work Type:	Joint Seal - PCC	Code:	JS-PC
Is Major M&R:	False				
Last Insp. Date:	5/25/2022	TotalSamples:	24	Surveyed:	3
Conditions:	PCI:	21			
Inspection Comments:					
Sample Number:	508	Type:	R	Area:	15.00 Slabs
PCI:	22				
Sample Comments:					
63	LINEAR CR	L	2.00	Slabs	
63	LINEAR CR	M	7.00	Slabs	
65	JT SEAL DMG	H	15.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
66	SMALL PATCH	M	4.00	Slabs	
67	LARGE PATCH	H	1.00	Slabs	
72	SHAT. SLAB	L	2.00	Slabs	
73	SHRINKAGE CR	N	6.00	Slabs	
74	JOINT SPALL	M	1.00	Slabs	
Sample Number:	513	Type:	R	Area:	24.00 Slabs
PCI:	19				
Sample Comments:					
63	LINEAR CR	L	1.00	Slabs	
63	LINEAR CR	M	21.00	Slabs	
63	LINEAR CR	H	2.00	Slabs	
65	JT SEAL DMG	H	24.00	Slabs	
66	SMALL PATCH	L	1.00	Slabs	
71	FAULTING	L	4.00	Slabs	
73	SHRINKAGE CR	N	13.00	Slabs	
74	JOINT SPALL	L	2.00	Slabs	
74	JOINT SPALL	M	4.00	Slabs	
75	CORNER SPALL	L	2.00	Slabs	
Sample Number:	604	Type:	R	Area:	16.00 Slabs
PCI:	21				
Sample Comments:					
63	LINEAR CR	M	15.00	Slabs	
65	JT SEAL DMG	H	16.00	Slabs	
67	LARGE PATCH	L	1.00	Slabs	
71	FAULTING	L	2.00	Slabs	
72	SHAT. SLAB	M	1.00	Slabs	
73	SHRINKAGE CR	N	3.00	Slabs	
74	JOINT SPALL	L	1.00	Slabs	

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT							
Branch:	AP		Name:	APRON		Use:	APRON		Area:	660,207 SqFt		
Section:	4110		of	8	From:	-		To:	-		Last Const.:	1/1/2018
Surface:	AC		Family:	CA653-RL-AP-AC		Zone:			Category:	Rank:		P
Area:	302,352 SqFt		Length:	190 Ft		Width:	1,740 Ft					
Slabs:	968		Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	37,742 Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type:	Joint Seal - PCC				Code:	JS-PC		Is Major M&R:	False
Work Date:	1/1/2018		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	60		Surveyed:	6					
Conditions:	PCI: 92											
Inspection Comments:												
Sample Number:	270		Type:	R		Area:	5000.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	279		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	8.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	317		Type:	R		Area:	5000.00 SqFt		PCI:	92		
Sample Comments:												
49	OIL SPILLAGE		N	2.00 SqFt								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	323		Type:	R		Area:	5000.00 SqFt		PCI:	90		
Sample Comments:												
48	L & T CR		L	25.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	364		Type:	R		Area:	5000.00 SqFt		PCI:	91		
Sample Comments:												
48	L & T CR		L	14.00 Ft								
57	WEATHERING		L	5000.00 SqFt								
Sample Number:	376		Type:	R		Area:	6550.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	6550.00 SqFt								

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	AP	Name:	APRON		Use:	APRON	Area:	660,207 SqFt			
Section:	4115	of	8	From:	-	To:	-	Last Const.:	12/25/1999		
Surface:	PCC	Family:	CA653-RL-AP-PCC		Zone:		Category:		Rank:	P	
Area:	34,307 SqFt		Length:	160 Ft		Width:	275 Ft				
Slabs:	91	Slab Length:	12 Ft		Slab Width:	30 Ft		Joint Length:	4,552 Ft		
Shoulder:		Street Type:		Grade:	0		Lanes:	0			
Section Comments:											
Work Date:	12/25/1999		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	6		Surveyed:	1				
Conditions:	PCI:		4								
Inspection Comments:											
Sample Number:	300	Type:	R	Area:	15.00 Slabs		PCI:	4			
Sample Comments:											
62	CORNER BREAK		H	1.00	Slabs						
63	LINEAR CR		M	7.00	Slabs						
65	JT SEAL DMG		H	15.00	Slabs						
67	LARGE PATCH		M	3.00	Slabs						
72	SHAT. SLAB		L	1.00	Slabs						
72	SHAT. SLAB		M	6.00	Slabs						
73	SHRINKAGE CR		N	3.00	Slabs						
74	JOINT SPALL		L	1.00	Slabs						
74	JOINT SPALL		M	3.00	Slabs						
74	JOINT SPALL		H	1.00	Slabs						
75	CORNER SPALL		L	2.00	Slabs						
75	CORNER SPALL		M	1.00	Slabs						

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT																	
Branch:		AP		Name:		APRON		Use:		APRON		Area:		660,207 SqFt									
Section:		4120		of		8		From:		-		To:		-		Last Const.:		1/1/2018					
Surface:		AC		Family:		CA653-RL-AP-AC				Zone:		Category:				Rank:		P					
Area:		58,790 SqFt				Length:		220 Ft		Width:		275 Ft											
Slabs:		188		Slab Length:		13 Ft		Slab Width:		25 Ft		Joint Length:		6,765 Ft									
Shoulder:		Street Type:				Grade:		0				Lanes:		0									
Section Comments:																							
Work Date:				12/15/1999				Work Type:				New Construction - Initial				Code:		NU-IN		Is Major M&R:		True	
Work Date:				1/1/2018				Work Type:				Complete Reconstruction - AC				Code:		CR-AC		Is Major M&R:		True	
Last Insp. Date:				5/25/2022				TotalSamples:		12		Surveyed:		2									
Conditions:				PCI:				93															
Inspection Comments:																							
Sample Number:		251		Type:		R		Area:		4550.00 SqFt				PCI:		92							
Sample Comments:																							
48		L & T CR				L		5.00 Ft															
57		WEATHERING				L		4550.00 SqFt															
Sample Number:		400		Type:		R		Area:		5050.00 SqFt				PCI:		94							
Sample Comments:																							
57		WEATHERING				L		5050.00 SqFt															

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT				
Branch:	AP	Name:	APRON	Use:	APRON	Area:	660,207 SqFt		
Section:	4125	of	8	From:	-	To:	-	Last Const.:	1/1/2015
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:		Rank:	P
Area:	53,176 SqFt	Length:	1,280 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2015	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	5/25/2022	TotalSamples:	13	Surveyed:	2				
Conditions:	PCI:	89							
Inspection Comments:									
Sample Number:	213	Type:	R	Area:	4150.00 SqFt	PCI:	86		
Sample Comments:									
48	L & T CR	L	102.00 Ft						
57	WEATHERING	L	4150.00 SqFt						
Sample Number:	221	Type:	R	Area:	4150.00 SqFt	PCI:	92		
Sample Comments:									
48	L & T CR	L	4.00 Ft						
57	WEATHERING	L	4150.00 SqFt						

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT							
Branch:	AP		Name:	APRON		Use:	APRON	Area:	660,207 SqFt			
Section:	4127		of	8	From:	-		To:	-		Last Const.:	1/1/2017
Surface:	AAC		Family:	CA653-RL-AP-AAC-APC		Zone:			Category:	Rank: P		
Area:	19,630 SqFt		Length:	475 Ft		Width:	40 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/2015		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2017		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 89											
Inspection Comments:												
Sample Number:	226		Type:	R		Area:	4150.00 SqFt		PCI:	89		
Sample Comments:												
48	L & T CR		L	50.00 Ft								
57	WEATHERING		L	4150.00 SqFt								

Network:	VNC	Name:	VENICE MUNICIPAL AIRPORT				
Branch:	AP	Name:	APRON	Use:	APRON	Area:	660,207 SqFt
Section:	4130	of 8	From:	-	To:	-	Last Const.: 1/1/2015
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:	Rank: P
Area:	6,119 SqFt	Length:	100 Ft	Width:	50 Ft		
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2015	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R: True
Last Insp. Date:	5/25/2022	TotalSamples:	2	Surveyed:	1		
Conditions:	PCI: 94						
Inspection Comments:							
Sample Number:	500	Type:	R	Area:	3291.00 SqFt	PCI:	94
Sample Comments:							
57	WEATHERING	L	3291.00	SqFt			

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT				
Branch:	AP	Name:	APRON	Use:	APRON	Area:	660,207 SqFt		
Section:	4140	of	8	From:	-	To:	-	Last Const.:	1/1/2015
Surface:	AC	Family:	CA653-RL-AP-AC	Zone:		Category:		Rank:	P
Area:	73,498 SqFt	Length:	180 Ft	Width:	450 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2015	Work Type:	New Construction - Initial			Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	5/25/2022	TotalSamples:	15	Surveyed:	2				
Conditions:	PCI:	90							
Inspection Comments:									
Sample Number:	232	Type:	R	Area:	5000.00 SqFt	PCI:	89		
Sample Comments:									
48	L & T CR	L	42.00 Ft						
57	WEATHERING	L	5000.00 SqFt						
Sample Number:	283	Type:	R	Area:	5000.00 SqFt	PCI:	92		
Sample Comments:									
48	L & T CR	L	3.00 Ft						
57	WEATHERING	L	5000.00 SqFt						

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT							
Branch:	AP MID		Name:	MID-FIELD APRON		Use:	APRON	Area:	166,523 SqFt		
Section:	4405 of 1		From:	-		To:	-		Last Const.:	1/1/2017	
Surface:	AC		Family:	CA653-RL-AP-AC		Zone:			Rank:	P	
Area:	166,523 SqFt		Length:	153 Ft		Width:	1,075 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	35		Surveyed:	5				
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	156		Type:	R		Area:	5000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	165		Type:	R		Area:	3750.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	3750.00 SqFt							
Sample Number:	209		Type:	R		Area:	5000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	261		Type:	R		Area:	5300.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5300.00 SqFt							
Sample Number:	266		Type:	R		Area:	3974.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	3974.00 SqFt							

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT													
Branch:		AP RU 13		Name:		RUN-UP APRON 13		Use:		APRON		Area:		19,846 SqFt					
Section:		5110		of		1		From:		-		To:		-		Last Const.:		1/1/2015	
Surface:		AC		Family:		CA653-RL-AP-AC		Zone:				Category:				Rank:		P	
Area:		19,846 SqFt		Length:		100 Ft		Width:		200 Ft									
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft					
Shoulder:				Street Type:				Grade:		0		Lanes:		0					
Section Comments:																			
Work Date:		1/1/1991		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		1/1/1991		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True					
Work Date:		1/1/2015		Work Type:		Complete Reconstruction - AC		Code:		CR-AC		Is Major M&R:		True					
Last Insp. Date:		5/25/2022		TotalSamples:		4		Surveyed:		1									
Conditions:		PCI:		91															
Inspection Comments:																			
Sample Number:		203		Type:		R		Area:		5053.00 SqFt		PCI:		91					
Sample Comments:																			
48		L & T CR		L		7.00 Ft													
57		WEATHERING		L		5053.00 SqFt													

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT																									
Branch:		AP RU 23		Name:		RUN-UP APRON 23		Use:		APRON		Area:		26,551 SqFt																	
Section:		5105		of		1		From:		-		To:		-		Last Const.:		1/1/2015													
Surface:		AC		Family:		CA653-RL-AP-AC		Zone:				Category:				Rank:		P													
Area:		26,551 SqFt		Length:		198 Ft		Width:		100 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				1/1/1991				Work Type:				BUILT				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				1/1/1991				Work Type:				OVERLAY				Code:				IMPORTED				Is Major M&R:				True			
Work Date:				1/1/2015				Work Type:				Complete Reconstruction - AC				Code:				CR-AC				Is Major M&R:				True			
Last Insp. Date:				5/25/2022				TotalSamples:				6				Surveyed:				1											
Conditions:				PCI:				93																							
Inspection Comments:																															
Sample Number:				205				Type:		R		Area:				3095.00 SqFt				PCI:				93							
Sample Comments:																															
52		RAVELING		L		4.00		SqFt																							
57		WEATHERING		L		3091.00		SqFt																							

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT						
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt			
Section:	6105		of	10	From:	-		To:	-		Last Const.:	12/1/2006
Surface:	AAC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	413,900 SqFt		Length:	4,139 Ft		Width:	100 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1982		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1982		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/1/2006		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	5/9/2017		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	5/25/2022		TotalSamples:	82		Surveyed:	17					
Conditions:	PCI: 71											
Inspection Comments:												
Sample Number:	307		Type:	R		Area:	5000.00 SqFt		PCI:	71		
Sample Comments:												
48	L & T CR		L	289.00 Ft								
52	RAVELING		L	1000.00 SqFt								
57	WEATHERING		M	4000.00 SqFt								
Sample Number:	312		Type:	R		Area:	5000.00 SqFt		PCI:	77		
Sample Comments:												
48	L & T CR		L	214.00 Ft								
57	WEATHERING		L	4000.00 SqFt								
57	WEATHERING		M	1000.00 SqFt								
Sample Number:	318		Type:	R		Area:	5000.00 SqFt		PCI:	70		
Sample Comments:												
48	L & T CR		L	274.00 Ft								
52	RAVELING		L	500.00 SqFt								
57	WEATHERING		M	4500.00 SqFt								
Sample Number:	321		Type:	R		Area:	5000.00 SqFt		PCI:	70		
Sample Comments:												
48	L & T CR		L	151.00 Ft								
52	RAVELING		L	500.00 SqFt								
57	WEATHERING		M	4500.00 SqFt								
Sample Number:	324		Type:	R		Area:	5000.00 SqFt		PCI:	70		
Sample Comments:												
48	L & T CR		L	192.00 Ft								
52	RAVELING		L	500.00 SqFt								
57	WEATHERING		M	4500.00 SqFt								
Sample Number:	330		Type:	R		Area:	5000.00 SqFt		PCI:	70		
Sample Comments:												
48	L & T CR		L	236.00 Ft								
52	RAVELING		L	500.00 SqFt								
57	WEATHERING		M	4500.00 SqFt								
Sample Number:	333		Type:	R		Area:	5000.00 SqFt		PCI:	70		
Sample Comments:												
48	L & T CR		L	277.00 Ft								
52	RAVELING		L	500.00 SqFt								

57	WEATHERING	M	4500.00	SqFt		
Sample Number: 336		Type: R	Area: 5000.00 SqFt		PCI: 70	
Sample Comments:						
48	L & T CR	L	287.00	Ft		
52	RAVELING	L	500.00	SqFt		
57	WEATHERING	M	4500.00	SqFt		
Sample Number: 348		Type: R	Area: 5000.00 SqFt		PCI: 67	
Sample Comments:						
45	DEPRESSION	L	28.00	SqFt		
48	L & T CR	L	246.00	Ft		
52	RAVELING	L	500.00	SqFt		
57	WEATHERING	M	4500.00	SqFt		
Sample Number: 354		Type: R	Area: 5000.00 SqFt		PCI: 70	
Sample Comments:						
48	L & T CR	L	233.00	Ft		
52	RAVELING	L	250.00	SqFt		
57	WEATHERING	M	4750.00	SqFt		
Sample Number: 360		Type: R	Area: 5000.00 SqFt		PCI: 70	
Sample Comments:						
48	L & T CR	L	200.00	Ft		
52	RAVELING	L	500.00	SqFt		
57	WEATHERING	M	4500.00	SqFt		
Sample Number: 367		Type: R	Area: 5000.00 SqFt		PCI: 75	
Sample Comments:						
48	L & T CR	L	245.00	Ft		
57	WEATHERING	M	5000.00	SqFt		
Sample Number: 375		Type: R	Area: 5000.00 SqFt		PCI: 70	
Sample Comments:						
48	L & T CR	L	202.00	Ft		
52	RAVELING	L	150.00	SqFt		
57	WEATHERING	M	4850.00	SqFt		
Sample Number: 380		Type: R	Area: 5000.00 SqFt		PCI: 71	
Sample Comments:						
48	L & T CR	L	254.00	Ft		
52	RAVELING	L	100.00	SqFt		
57	WEATHERING	M	4900.00	SqFt		
Sample Number: 384		Type: R	Area: 5000.00 SqFt		PCI: 71	
Sample Comments:						
48	L & T CR	L	51.00	Ft		
52	RAVELING	L	100.00	SqFt		
57	WEATHERING	M	4900.00	SqFt		
Sample Number: 388		Type: R	Area: 5000.00 SqFt		PCI: 71	
Sample Comments:						
48	L & T CR	L	165.00	Ft		
52	RAVELING	L	100.00	SqFt		
57	WEATHERING	M	4900.00	SqFt		
Sample Number: 392		Type: R	Area: 5000.00 SqFt		PCI: 75	
Sample Comments:						
48	L & T CR	L	52.00	Ft		
57	WEATHERING	L	100.00	SqFt		
57	WEATHERING	M	4900.00	SqFt		

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT								
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt					
Section:	6110		of	10		From:	-		To:	-		Last Const.:	12/1/2006	
Surface:	AAC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:			Rank:	P	
Area:	196,950 SqFt		Length:	8,400 Ft		Width:	25 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1982		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	1/1/1982		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True		
Work Date:	12/1/2006		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True		
Work Date:	5/9/2017		Work Type:	Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False		
Last Insp. Date:	5/25/2022		TotalSamples:	40		Surveyed:	8							
Conditions:	PCI: 71													
Inspection Comments:														
Sample Number:	128		Type:	R		Area:	5000.00 SqFt		PCI:	56				
Sample Comments:														
48	L & T CR		L	734.00 Ft										
52	RAVELING		L	500.00 SqFt										
56	SWELLING		L	300.00 SqFt										
57	WEATHERING		L	4500.00 SqFt										
Sample Number:	152		Type:	R		Area:	5000.00 SqFt		PCI:	75				
Sample Comments:														
48	L & T CR		L	236.00 Ft										
57	WEATHERING		M	5000.00 SqFt										
Sample Number:	172		Type:	R		Area:	5000.00 SqFt		PCI:	73				
Sample Comments:														
48	L & T CR		L	232.00 Ft										
56	SWELLING		L	12.00 SqFt										
57	WEATHERING		M	5000.00 SqFt										
Sample Number:	184		Type:	R		Area:	5000.00 SqFt		PCI:	81				
Sample Comments:														
48	L & T CR		L	93.00 Ft										
57	WEATHERING		L	4000.00 SqFt										
57	WEATHERING		M	1000.00 SqFt										
Sample Number:	516		Type:	R		Area:	5000.00 SqFt		PCI:	71				
Sample Comments:														
48	L & T CR		L	235.00 Ft										
52	RAVELING		L	750.00 SqFt										
56	SWELLING		L	100.00 SqFt										
57	WEATHERING		L	4250.00 SqFt										
Sample Number:	536		Type:	R		Area:	5525.00 SqFt		PCI:	71				
Sample Comments:														
48	L & T CR		L	283.00 Ft										
52	RAVELING		L	552.00 SqFt										
56	SWELLING		L	83.00 SqFt										
57	WEATHERING		L	4973.00 SqFt										
Sample Number:	552		Type:	R		Area:	5000.00 SqFt		PCI:	70				
Sample Comments:														

48	L & T CR	L	256.00	Ft
56	SWELLING	L	128.00	SqFt
57	WEATHERING	M	5000.00	SqFt

Sample Number:	568	Type:	R	Area:	5000.00 SqFt	PCI:	75
-----------------------	-----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

48	L & T CR	L	277.00	Ft
57	WEATHERING	M	5000.00	SqFt

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT							
Branch:	RW 13-31		Name:		RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt			
Section:	6115		of 10		From:	-		To:	-		Last Const.:	12/1/2006	
Surface:	APC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank:		P	
Area:	30,000 SqFt		Length:	300 Ft		Width:	100 Ft						
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0			
Section Comments:													
Work Date:	1/1/1942		Work Type:					BUILT	Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1982		Work Type:					OVERLAY	Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1982		Work Type:					OVERLAY	Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/1/2006		Work Type:					Mill and Overlay	Code:	ML-OVL		Is Major M&R:	True
Work Date:	5/9/2017		Work Type:					Surface Treatment - Seal Coat	Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	5/25/2022		TotalSamples:	6		Surveyed:							2
Conditions:	PCI: 65												
Inspection Comments:													
Sample Number:	300		Type:	R		Area:	5000.00 SqFt		PCI:	70			
Sample Comments:													
47	JT REF. CR		L	28.00 Ft									
48	L & T CR		L	25.00 Ft									
52	RAVELING		L	500.00 SqFt									
57	WEATHERING		M	4500.00 SqFt									
Sample Number:	304		Type:	R		Area:	5000.00 SqFt		PCI:	61			
Sample Comments:													
47	JT REF. CR		L	270.00 Ft									
47	JT REF. CR		M	40.00 Ft									
48	L & T CR		L	38.00 Ft									
52	RAVELING		L	500.00 SqFt									
57	WEATHERING		M	4500.00 SqFt									

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT								
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt			
Section:	6120		of	10		From:	-		To:	-	Last Const.:	12/1/2006
Surface:	APC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	20,000 SqFt		Length:	800 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1982		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	12/1/2006		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R: True		
Work Date:	5/9/2017		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False		
Last Insp. Date:	5/25/2022		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 61											
Inspection Comments:												
Sample Number:	500		Type:	R		Area:	5000.00 SqFt		PCI:	61		
Sample Comments:												
47	JT REF. CR		L	120.00 Ft								
47	JT REF. CR		M	85.00 Ft								
48	L & T CR		L	100.00 Ft								
52	RAVELING		L	1000.00 SqFt								
57	WEATHERING		M	4000.00 SqFt								

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT							
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt		
Section:	6125 of 10		From:	-		To:	-		Last Const.:	12/1/2006	
Surface:	APC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P	
Area:	30,000 SqFt		Length:	300 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1982		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1982		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/1/2006		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Work Date:	5/9/2017		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False
Last Insp. Date:	5/25/2022		TotalSamples:	6		Surveyed:	2				
Conditions:	PCI: 65										
Inspection Comments:											
Sample Number:	395		Type:	R		Area:	5000.00 SqFt		PCI:	63	
Sample Comments:											
47	JT REF. CR		L	70.00 Ft							
47	JT REF. CR		M	20.00 Ft							
48	L & T CR		L	90.00 Ft							
52	RAVELING		L	500.00 SqFt							
57	WEATHERING		M	4500.00 SqFt							
Sample Number:	398		Type:	R		Area:	5000.00 SqFt		PCI:	67	
Sample Comments:											
47	JT REF. CR		L	20.00 Ft							
48	L & T CR		L	58.00 Ft							
52	RAVELING		L	3000.00 SqFt							
57	WEATHERING		M	2000.00 SqFt							

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT								
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt			
Section:	6130		of	10		From:	-		To:	-	Last Const.:	12/1/2006
Surface:	APC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	20,000 SqFt		Length:	800 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1982		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True	
Work Date:	1/1/1982		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True	
Work Date:	12/1/2006		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True	
Work Date:	5/9/2017		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False	
Last Insp. Date:	5/25/2022		TotalSamples:	4		Surveyed:	1					
Conditions:	PCI: 60											
Inspection Comments:												
Sample Number:	196		Type:	R		Area:	5000.00 SqFt		PCI:	60		
Sample Comments:												
47	JT REF. CR		L	180.00 Ft								
47	JT REF. CR		M	35.00 Ft								
48	L & T CR		L	46.00 Ft								
52	RAVELING		L	2750.00 SqFt								
57	WEATHERING		L	2250.00 SqFt								

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT									
Branch:		RW 13-31		Name:		RUNWAY 13-31		Use:		RUNWAY		Area:		845,775 SqFt	
Section:		6135		of 10		From:		-		To:		-		Last Const.: 1/1/2013	
Surface:		AAC		Family:		CA653-RL-RW-AAC-APC		Zone:		Category:		Rank:		P	
Area:		26,100 SqFt		Length:		1,000 Ft		Width:		100 Ft					
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft			
Shoulder:		Street Type:		Grade:		0		Lanes:		0					
Section Comments:															
Work Date:		1/1/1942		Work Type:		BUILT				Code:		IMPORTED		Is Major M&R: True	
Work Date:		1/1/1982		Work Type:		OVERLAY				Code:		IMPORTED		Is Major M&R: True	
Work Date:		1/1/1982		Work Type:		OVERLAY				Code:		IMPORTED		Is Major M&R: True	
Work Date:		12/1/2006		Work Type:		Mill and Overlay				Code:		ML-OVL		Is Major M&R: True	
Work Date:		1/1/2013		Work Type:		Mill and Overlay				Code:		ML-OVL		Is Major M&R: True	
Work Date:		5/9/2017		Work Type:		Surface Treatment - Seal Coat				Code:		ST-SC		Is Major M&R: False	
Last Insp. Date:		5/25/2022		TotalSamples:		6				Surveyed:		2			
Conditions:		PCI: 85													
Inspection Comments:															
Sample Number:		342		Type:		R		Area:		5000.00 SqFt		PCI:		84	
Sample Comments:															
48	L & T CR			L	12.00 Ft										
57	WEATHERING			L	4250.00 SqFt										
57	WEATHERING			M	750.00 SqFt										
Sample Number:		344		Type:		R		Area:		5000.00 SqFt		PCI:		85	
Sample Comments:															
48	L & T CR			L	6.00 Ft										
57	WEATHERING			L	4250.00 SqFt										
57	WEATHERING			M	750.00 SqFt										

Network:	VNC		Name:		VENICE MUNICIPAL AIRPORT							
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt			
Section:	6140		of	10	From:	-		To:	-		Last Const.:	1/1/2013
Surface:	AAC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	13,050 SqFt		Length:	500 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1982		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1982		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	12/1/2006		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R: True		
Work Date:	1/1/2013		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R: True		
Work Date:	5/9/2017		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False		
Last Insp. Date:	5/25/2022		TotalSamples:	4		Surveyed: 1						
Conditions:	PCI: 85											
Inspection Comments:												
Sample Number:	143		Type:	R		Area:	3300.00 SqFt		PCI:	85		
Sample Comments:												
48	L & T CR		L	14.00 Ft								
57	WEATHERING		L	2970.00 SqFt								
57	WEATHERING		M	330.00 SqFt								

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY		Area:	845,775 SqFt	
Section:	6145 of 10		From:	-			To:	-		Last Const.:	5/9/2017
Surface:	AC		Family:	CA653-RL-RW-AC		Zone:			Category:	Rank: P	
Area:	63,850 SqFt		Length:	639 Ft		Width:	100 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	5/9/2017		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Last Insp. Date:	5/25/2022		TotalSamples:	13		Surveyed:	3				
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	289		Type:	R		Area:	5000.00 SqFt		PCI:	86	
Sample Comments:											
48	L & T CR		L	131.00 Ft							
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	293		Type:	R		Area:	5000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							
Sample Number:	297		Type:	R		Area:	5000.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	RW 13-31		Name:	RUNWAY 13-31		Use:	RUNWAY	Area:	845,775 SqFt		
Section:	6150 of 10		From:	-			To:	-		Last Const.:	5/9/2017
Surface:	AC		Family:	CA653-RL-RW-AC		Zone:			Category:	Rank: P	
Area:	31,925 SqFt		Length:	639 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:				Grade:		0		Lanes:		0
Section Comments:											
Work Date:	5/9/2017		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Last Insp. Date:	5/25/2022		TotalSamples:	6		Surveyed:		2			
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	487		Type:	R		Area:	5962.00 SqFt		PCI: 94		
Sample Comments:											
57	WEATHERING		L	5962.00 SqFt							
Sample Number:	92		Type:	R		Area:	5000.00 SqFt		PCI: 94		
Sample Comments:											
57	WEATHERING		L	5000.00 SqFt							

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT											
Branch:		RW 5-23		Name:		RUNWAY 5-23		Use:		RUNWAY		Area:		727,500 SqFt			
Section:		6205		of 6		From:		-		To:		-		Last Const.:		1/1/2013	
Surface:		AC		Family:		CA653-RL-RW-AC		Zone:		Category:		Rank:		P			
Area:		255,000 SqFt		Length:		4,250 Ft		Width:		60 Ft							
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft					
Shoulder:		Street Type:		Grade:		0		Lanes:		0							
Section Comments:																	
Work Date:		1/1/1942		Work Type:		BUILT		Code:		IMPORTED		Is Major M&R:		True			
Work Date:		1/1/1942		Work Type:		OVERLAY		Code:		IMPORTED		Is Major M&R:		True			
Work Date:		1/1/2013		Work Type:		Complete Reconstruction - AC		Code:		CR-AC		Is Major M&R:		True			
Last Insp. Date:		5/25/2022		TotalSamples:		44		Surveyed:		8							
Conditions:		PCI: 85															
Inspection Comments:																	
Sample Number:		105		Type:		R		Area:		6000.00 SqFt		PCI:		85			
Sample Comments:																	
57 WEATHERING		L		4500.00 SqFt													
57 WEATHERING		M		1500.00 SqFt													
Sample Number:		110		Type:		R		Area:		6000.00 SqFt		PCI:		84			
Sample Comments:																	
52 RAVELING		L		240.00 SqFt													
57 WEATHERING		L		5190.00 SqFt													
57 WEATHERING		M		570.00 SqFt													
Sample Number:		115		Type:		R		Area:		6000.00 SqFt		PCI:		79			
Sample Comments:																	
50 PATCHING		L		114.00 SqFt													
52 RAVELING		L		10.00 SqFt													
57 WEATHERING		L		4407.00 SqFt													
57 WEATHERING		M		1469.00 SqFt													
Sample Number:		122		Type:		R		Area:		6000.00 SqFt		PCI:		85			
Sample Comments:																	
57 WEATHERING		L		4500.00 SqFt													
57 WEATHERING		M		1500.00 SqFt													
Sample Number:		127		Type:		R		Area:		6000.00 SqFt		PCI:		85			
Sample Comments:																	
57 WEATHERING		L		4500.00 SqFt													
57 WEATHERING		M		1500.00 SqFt													
Sample Number:		132		Type:		R		Area:		6000.00 SqFt		PCI:		85			
Sample Comments:																	
57 WEATHERING		L		4500.00 SqFt													
57 WEATHERING		M		1500.00 SqFt													
Sample Number:		137		Type:		R		Area:		6000.00 SqFt		PCI:		90			
Sample Comments:																	
57 WEATHERING		M		1500.00 SqFt													
Sample Number:		142		Type:		R		Area:		6000.00 SqFt		PCI:		85			
Sample Comments:																	
57 WEATHERING		L		4500.00 SqFt													
57 WEATHERING		M		1500.00 SqFt													

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT						
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	727,500 SqFt			
Section:	6210		of	6	From:	-		To:	-		Last Const.:	1/1/2013
Surface:	AAC		Family:	CA653-RL-RW-AAC-APC		Zone:			Category:	Rank: P		
Area:	382,500 SqFt		Length:	4,250 Ft		Width:	90 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2013		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	84		Surveyed:	17					
Conditions:	PCI: 88											
Inspection Comments:												
Sample Number:	304		Type:	R		Area:	4500.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	3825.00 SqFt								
57	WEATHERING		M	675.00 SqFt								
Sample Number:	309		Type:	R		Area:	4500.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	3825.00 SqFt								
57	WEATHERING		M	675.00 SqFt								
Sample Number:	314		Type:	R		Area:	4500.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	3825.00 SqFt								
57	WEATHERING		M	675.00 SqFt								
Sample Number:	320		Type:	R		Area:	4500.00 SqFt		PCI:	86		
Sample Comments:												
57	WEATHERING		L	3600.00 SqFt								
57	WEATHERING		M	900.00 SqFt								
Sample Number:	328		Type:	R		Area:	4500.00 SqFt		PCI:	93		
Sample Comments:												
57	WEATHERING		M	675.00 SqFt								
Sample Number:	335		Type:	R		Area:	4500.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	3825.00 SqFt								
57	WEATHERING		M	675.00 SqFt								
Sample Number:	339		Type:	R		Area:	4500.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	3825.00 SqFt								
57	WEATHERING		M	675.00 SqFt								
Sample Number:	343		Type:	R		Area:	4500.00 SqFt		PCI:	89		
Sample Comments:												
57	WEATHERING		L	4050.00 SqFt								
57	WEATHERING		M	450.00 SqFt								
Sample Number:	504		Type:	R		Area:	4500.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	3825.00 SqFt								
57	WEATHERING		M	675.00 SqFt								

Sample Number: 511		Type:	R	Area:	4500.00 SqFt	PCI:	91
Sample Comments:							
57	WEATHERING		L	4275.00	SqFt		
57	WEATHERING		M	225.00	SqFt		
Sample Number: 519		Type:	R	Area:	5737.00 SqFt	PCI:	88
Sample Comments:							
57	WEATHERING		L	4876.00	SqFt		
57	WEATHERING		M	861.00	SqFt		
Sample Number: 524		Type:	R	Area:	4500.00 SqFt	PCI:	88
Sample Comments:							
57	WEATHERING		L	3825.00	SqFt		
57	WEATHERING		M	675.00	SqFt		
Sample Number: 529		Type:	R	Area:	4500.00 SqFt	PCI:	88
Sample Comments:							
57	WEATHERING		L	3825.00	SqFt		
57	WEATHERING		M	675.00	SqFt		
Sample Number: 531		Type:	R	Area:	4500.00 SqFt	PCI:	88
Sample Comments:							
57	WEATHERING		L	3825.00	SqFt		
57	WEATHERING		M	675.00	SqFt		
Sample Number: 536		Type:	R	Area:	4500.00 SqFt	PCI:	88
Sample Comments:							
57	WEATHERING		L	3825.00	SqFt		
57	WEATHERING		M	675.00	SqFt		
Sample Number: 540		Type:	R	Area:	4500.00 SqFt	PCI:	88
Sample Comments:							
57	WEATHERING		L	3825.00	SqFt		
57	WEATHERING		M	675.00	SqFt		
Sample Number: 545		Type:	R	Area:	4500.00 SqFt	PCI:	89
Sample Comments:							
57	WEATHERING		L	4050.00	SqFt		
57	WEATHERING		M	450.00	SqFt		

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY		Area:	727,500 SqFt	
Section:	6215 of 6		From:	-			To:	-		Last Const.:	1/1/2013
Surface:	AC		Family:	CA653-RL-RW-AC		Zone:			Category:	Rank: P	
Area:	18,000 SqFt		Length:	300 Ft		Width:	100 Ft				
Slabs:	58		Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	3,200 Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type:	BUILT			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type:	OVERLAY			Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type:	Joint Seal - PCC			Code:	JS-PC		Is Major M&R:	False
Work Date:	1/1/2013		Work Type:	Complete Reconstruction - AC			Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	3			Surveyed:	1			
Conditions:	PCI: 85										
Inspection Comments:											
Sample Number:	102		Type:	R		Area:	6000.00 SqFt		PCI:	85	
Sample Comments:											
57	WEATHERING		L	4500.00 SqFt							
57	WEATHERING		M	1500.00 SqFt							

Network:	VNC	Name:	VENICE MUNICIPAL AIRPORT						
Branch:	RW 5-23	Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	727,500 SqFt	
Section:	6220	of	6	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	AC	Family:	CA653-RL-RW-AC		Zone:	Category:		Rank:	P
Area:	27,000 SqFt		Length:	800 Ft		Width:	25 Ft		
Slabs:	86	Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	1,575 Ft
Shoulder:	Street Type:		Grade:		0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1942		Work Type:			BUILT		Code:	IMPORTED
								Is Major M&R:	True
Work Date:	1/1/1942		Work Type:			OVERLAY		Code:	IMPORTED
								Is Major M&R:	True
Work Date:	1/1/1986		Work Type:			Joint Seal - PCC		Code:	JS-PC
								Is Major M&R:	False
Work Date:	1/1/2013		Work Type:			Complete Reconstruction - AC		Code:	CR-AC
								Is Major M&R:	True
Last Insp. Date: 5/25/2022									
		TotalSamples:	6		Surveyed:		2		
Conditions:	PCI: 91								
Inspection Comments:									
Sample Number:	301	Type:	R	Area:	4500.00 SqFt		PCI:	91	
Sample Comments:									
57	WEATHERING		L	4275.00 SqFt					
57	WEATHERING		M	225.00 SqFt					
Sample Number:	500	Type:	R	Area:	4500.00 SqFt		PCI:	91	
Sample Comments:									
57	WEATHERING		L	4275.00 SqFt					
57	WEATHERING		M	225.00 SqFt					

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT					
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	727,500 SqFt	
Section:	6225	of 6	From:	-			To:	-	Last Const.: 1/1/2013	
Surface:	AC		Family:	CA653-RL-RW-AC		Zone:	Category:		Rank: P	
Area:	18,000 SqFt		Length:	300 Ft		Width:	100 Ft			
Slabs:	58	Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	3,200 Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:	0		
Section Comments:										
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1986		Work Type: Joint Seal - PCC				Code:	JS-PC		Is Major M&R: False
Work Date:	1/1/2013		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R: True
Last Insp. Date:	5/25/2022		TotalSamples:	3		Surveyed:	1			
Conditions:	PCI: 85									
Inspection Comments:										
Sample Number:	147	Type:	R	Area:	6000.00 SqFt		PCI:	85		
Sample Comments:										
57	WEATHERING		L	4500.00 SqFt						
57	WEATHERING		M	1500.00 SqFt						

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT							
Branch:	RW 5-23		Name:	RUNWAY 5-23		Use:	RUNWAY	Area:	727,500 SqFt			
Section:	6230		of	6	From:	-		To:	-		Last Const.:	1/1/2013
Surface:	AC		Family:	CA653-RL-RW-AC		Zone:			Category:	Rank: P		
Area:	27,000 SqFt		Length:	800 Ft		Width:	25 Ft					
Slabs:	86		Slab Length:	13 Ft		Slab Width:	25 Ft		Joint Length:	1,575 Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1942		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type:	Joint Seal - PCC				Code:	JS-PC		Is Major M&R:	False
Work Date:	1/1/2013		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	6		Surveyed:	2					
Conditions:	PCI: 92											
Inspection Comments:												
Sample Number:	348		Type:	R		Area:	4500.00 SqFt		PCI:	89		
Sample Comments:												
57	WEATHERING		L	4050.00 SqFt								
57	WEATHERING		M	450.00 SqFt								
Sample Number:	549		Type:	R		Area:	4500.00 SqFt		PCI:	95		
Sample Comments:												
57	WEATHERING		M	450.00 SqFt								

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT										
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt					
Section:	605		of	11		From:	-		To:	-		Last Const.:	1/1/2003	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:			Rank:	P	
Area:	16,734 SqFt		Length:	490 Ft		Width:	33 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2003		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Last Insp. Date:	5/25/2022		TotalSamples:	4		Surveyed:	1							
Conditions:	PCI: 69													
Inspection Comments:														
Sample Number:	101		Type:	R		Area:	3960.00 SqFt		PCI:	69				
Sample Comments:														
48	L & T CR		L	285.00 Ft										
52	RAVELING		L	3960.00 SqFt										

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT							
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt		
Section:	610 of 11		From:	-		To:	-		Last Const.:	1/1/2003	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Rank:	P	
Area:	42,622 SqFt		Length:	490 Ft		Width:	40 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/1942		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2003		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date: 5/25/2022											
TotalSamples: 9											
Surveyed: 1											
Conditions:	PCI: 66										
Inspection Comments:											
Sample Number:	203		Type:	R		Area:	5000.00 SqFt		PCI:	66	
Sample Comments:											
45	DEPRESSION		L		6.00 SqFt						
48	L & T CR		L		30.00 Ft						
49	OIL SPILLAGE		N		13.00 SqFt						
52	RAVELING		L		5000.00 SqFt						

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT												
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt									
Section:	620		of	11	From:	-		To:	-		Last Const.:	12/25/1994						
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P								
Area:	100,062 SqFt		Length:	2,795 Ft		Width:	35 Ft											
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft								
Shoulder:			Street Type:			Grade:	0		Lanes:	0								
Section Comments:																		
Work Date:			12/25/1994				Work Type:			New Construction - Initial			Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:			5/25/2022				TotalSamples:			20		Surveyed:			3			
Conditions:			PCI: 52															
Inspection Comments:																		
Sample Number:			300		Type:	R		Area:	4856.00 SqFt		PCI:	60						
Sample Comments:																		
48	L & T CR		L	353.00 Ft														
52	RAVELING		L	4370.00 SqFt														
52	RAVELING		M	486.00 SqFt														
Sample Number:			350		Type:	R		Area:	5075.00 SqFt		PCI:	47						
Sample Comments:																		
43	BLOCK CR		L	1523.00 SqFt														
45	DEPRESSION		L	10.00 SqFt														
48	L & T CR		L	92.00 Ft														
52	RAVELING		L	3806.00 SqFt														
52	RAVELING		M	1269.00 SqFt														
Sample Number:			451		Type:	R		Area:	4309.00 SqFt		PCI:	49						
Sample Comments:																		
41	ALLIGATOR CR		L	25.00 SqFt														
45	DEPRESSION		L	110.00 SqFt														
48	L & T CR		L	127.00 Ft														
50	PATCHING		L	100.00 SqFt														
52	RAVELING		L	4159.00 SqFt														
52	RAVELING		H	50.00 SqFt														

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT																	
Branch:		TL T-HANG		Name:		T-HANGAR TAXILANE		Use:		TAXILANE		Area:		321,751 SqFt									
Section:		705		of 11		From:		-		To:		-		Last Const.:		1/1/2003							
Surface:		AC		Family:		CA653-RL-TW-AC		Zone:				Category:				Rank:		P					
Area:		34,474 SqFt		Length:		950 Ft		Width:		35 Ft													
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft									
Shoulder:				Street Type:				Grade:		0		Lanes:		0									
Section Comments:																							
Work Date:				1/1/1942				Work Type:				New Construction - Initial				Code:		NU-IN		Is Major M&R:		True	
Work Date:				1/1/2003				Work Type:				New Construction - Initial				Code:		NU-IN		Is Major M&R:		True	
Last Insp. Date:				5/25/2022				TotalSamples:				8				Surveyed:				1			
Conditions:				PCI:				78															
Inspection Comments:																							
Sample Number:		507		Type:		R		Area:		4375.00 SqFt		PCI:		78									
Sample Comments:																							
48		L & T CR		L		159.00 Ft																	
52		RAVELING		L		438.00 SqFt																	
57		WEATHERING		L		3937.00 SqFt																	

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT																									
Branch:		TL T-HANG		Name:		T-HANGAR TAXILANE		Use:		TAXILANE		Area:		321,751 SqFt																	
Section:		708		of		11		From:		-		To:		-		Last Const.:		12/25/1997													
Surface:		AC		Family:		CA653-RL-TW-AC		Zone:				Category:				Rank:		P													
Area:		11,446 SqFt		Length:		370 Ft		Width:		30 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				12/25/1997				Work Type:				New Construction - Initial				Code:				NU-IN				Is Major M&R:				True			
Last Insp. Date:				5/25/2022				TotalSamples:				3				Surveyed:				1											
Conditions:				PCI:				67																							
Inspection Comments:																															
Sample Number:		300		Type:		R		Area:		4357.00 SqFt		PCI:		67																	
Sample Comments:																															
48		L & T CR		L		54.00		Ft																							
48		L & T CR		M		100.00		Ft																							
52		RAVELING		L		654.00		SqFt																							
56		SWELLING		L		12.00		SqFt																							
57		WEATHERING		L		3703.00		SqFt																							

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT						
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt			
Section:	710		of	11	From:	-		To:	-		Last Const.:	12/25/1994
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P		
Area:	41,684 SqFt		Length:	1,320 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1994		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	11		Surveyed:	2					
Conditions:	PCI: 46											
Inspection Comments:												
Sample Number:	150		Type:	R		Area:	3234.00 SqFt		PCI:	37		
Sample Comments:												
41	ALLIGATOR CR		L	17.00 SqFt								
45	DEPRESSION		L	10.00 SqFt								
48	L & T CR		L	30.00 Ft								
50	PATCHING		L	96.00 SqFt								
52	RAVELING		L	1569.00 SqFt								
52	RAVELING		M	1569.00 SqFt								
Sample Number:	201		Type:	R		Area:	3000.00 SqFt		PCI:	56		
Sample Comments:												
43	BLOCK CR		L	1350.00 SqFt								
48	L & T CR		L	230.00 Ft								
52	RAVELING		L	600.00 SqFt								
57	WEATHERING		M	2400.00 SqFt								

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT								
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt			
Section:	715	of	11	From:	-			To:	-		Last Const.:	1/1/2012
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:		Category:	Rank: P			
Area:	12,768 SqFt		Length:	515 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:		Grade:		0		Lanes:		0			
Section Comments:												
Work Date:	1/1/2012		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True		
Last Insp. Date:	5/25/2022		TotalSamples:		4		Surveyed: 1					
Conditions:	PCI:		89									
Inspection Comments:												
Sample Number:	652		Type:	R		Area:	3250.00 SqFt		PCI: 89			
Sample Comments:												
48	L & T CR		L	6.00 Ft								
50	PATCHING		L	1.00 SqFt								
57	WEATHERING		L	3249.00 SqFt								

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT											
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt							
Section:	720 of 11		From:	-			To:	-			Last Const.:	1/1/2012				
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:				Category:				Rank:	P	
Area:	5,422 SqFt		Length:	150 Ft		Width:	35 Ft									
Slabs:			Slab Length:	Ft		Slab Width:	Ft			Joint Length:	Ft					
Shoulder:			Street Type:			Grade:	0			Lanes:	0					
Section Comments:																
Work Date:	1/1/2012		Work Type:	New Construction - Initial				Code:	NU-IN			Is Major M&R:	True			
Last Insp. Date:	5/25/2022		TotalSamples:	1		Surveyed:	1									
Conditions:	PCI: 89															
Inspection Comments:																
Sample Number:	604		Type:	R		Area:	5422.00 SqFt			PCI:	89					
Sample Comments:																
48	L & T CR		L	61.00 Ft												
57	WEATHERING		L	5422.00 SqFt												

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT								
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt			
Section:	725	of	11	From:	-			To:	-		Last Const.:	1/1/2012
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:				Category:	Rank: P		
Area:	17,209 SqFt		Length:	680 Ft		Width:	25 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:		Grade:	0		Lanes:	0					
Section Comments:												
Work Date:	1/1/2012		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True	
Last Insp. Date:	5/25/2022		TotalSamples:	5		Surveyed:	1					
Conditions:	PCI:	92										
Inspection Comments:												
Sample Number:	704	Type:	R	Area:	3643.00 SqFt		PCI:	92				
Sample Comments:												
48	L & T CR		L	4.00 Ft								
57	WEATHERING		L	3643.00 SqFt								

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT						
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt			
Section:	730		of	11	From:	-		To:	-		Last Const.:	11/1/2013
Surface:	AAC		Family:	CA653-RL-TW-AAC-APC		Zone:			Category:	Rank: P		
Area:	18,001 SqFt		Length:	600 Ft		Width:	25 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	12/25/1994		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	11/1/2013		Work Type:	Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	5		Surveyed:	1					
Conditions:	PCI: 59											
Inspection Comments:												
Sample Number:	505		Type:	R		Area:	4893.00 SqFt		PCI:	59		
Sample Comments:												
43	BLOCK CR		L	510.00 SqFt								
48	L & T CR		L	353.00 Ft								
48	L & T CR		M	166.00 Ft								
57	WEATHERING		L	3425.00 SqFt								
57	WEATHERING		M	1468.00 SqFt								

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT							
Branch:	TL T-HANG		Name:	T-HANGAR TAXILANE		Use:	TAXILANE	Area:	321,751 SqFt		
Section:	735 of 11		From:	-		To:	-		Last Const.:	1/1/2018	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Rank:	P	
Area:	21,329 SqFt		Length:	835 Ft		Width:	24 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2018		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI: 94										
Inspection Comments:											
Sample Number:	801		Type:	R		Area:	3264.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	3264.00 SqFt							

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	179,035 SqFt	
Section:	105 of 5		From:	-		To:	-		Last Const.:	1/1/2015	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P	
Area:	55,145 SqFt		Length:	1,395 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2015		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	14		Surveyed:	2				
Conditions:	PCI: 93										
Inspection Comments:											
Sample Number:	129		Type:	R		Area:	3500.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L	3500.00 SqFt							
Sample Number:	136		Type:	R		Area:	4881.00 SqFt		PCI:	92	
Sample Comments:											
48	L & T CR		L	6.00 Ft							
57	WEATHERING		L	4881.00 SqFt							

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	179,035 SqFt		
Section:	110 of 5		From:	-		To:	-		Last Const.:	1/1/2015		
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P		
Area:	55,883 SqFt		Length:	1,450 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2015		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	16		Surveyed:	3					
Conditions:	PCI: 84											
Inspection Comments:												
Sample Number:	115		Type:	R		Area:	3500.00 SqFt		PCI:	86		
Sample Comments:												
48	L & T CR		L	89.00 Ft								
57	WEATHERING		L	3500.00 SqFt								
Sample Number:	119		Type:	R		Area:	3500.00 SqFt		PCI:	80		
Sample Comments:												
48	L & T CR		L	180.00 Ft								
57	WEATHERING		L	3500.00 SqFt								
Sample Number:	125		Type:	R		Area:	3500.00 SqFt		PCI:	86		
Sample Comments:												
48	L & T CR		L	90.00 Ft								
57	WEATHERING		L	3500.00 SqFt								

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT																	
Branch:		TW A		Name:		TAXIWAY A		Use:		TAXIWAY		Area:		179,035 SqFt									
Section:		115		of 5		From:		-		To:		-		Last Const.:		1/1/2015							
Surface:		AC		Family:		CA653-RL-TW-AC		Zone:		Category:		Rank:		P									
Area:		52,281 SqFt		Length:		1,333 Ft		Width:		50 Ft													
Slabs:		Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft											
Shoulder:		Street Type:		Grade:		0		Lanes:		0													
Section Comments:																							
Work Date:				1/1/1942				Work Type:				BUILT				Code:		IMPORTED		Is Major M&R:		True	
Work Date:				1/1/1986				Work Type:				OVERLAY				Code:		IMPORTED		Is Major M&R:		True	
Work Date:				1/1/1986				Work Type:				OVERLAY				Code:		IMPORTED		Is Major M&R:		True	
Work Date:				1/1/2015				Work Type:				Complete Reconstruction - AC				Code:		CR-AC		Is Major M&R:		True	
Last Insp. Date:				5/25/2022				TotalSamples:				12				Surveyed:				3			
Conditions:				PCI:				90															
Inspection Comments:																							
Sample Number:				101				Type:		R		Area:		4913.00 SqFt		PCI:		86					
Sample Comments:																							
48		L & T CR		L		23.00 Ft																	
57		WEATHERING		L		4617.00 SqFt																	
57		WEATHERING		M		296.00 SqFt																	
Sample Number:				106				Type:		R		Area:		3867.00 SqFt		PCI:		94					
Sample Comments:																							
57		WEATHERING		L		3867.00 SqFt																	
Sample Number:				111				Type:		R		Area:		3500.00 SqFt		PCI:		90					
Sample Comments:																							
48		L & T CR		L		13.00 Ft																	
57		WEATHERING		L		3500.00 SqFt																	

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	179,035 SqFt		
Section:	120	of 5		From:	-		To:	-		Last Const.:	1/1/2013
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P	
Area:	9,988 SqFt		Length:	200 Ft		Width:	50 Ft				
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft	
Shoulder:			Street Type:			Grade:	0		Lanes:	0	
Section Comments:											
Work Date:	1/1/2013		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True	
Last Insp. Date:	5/25/2022		TotalSamples:	2		Surveyed:	1				
Conditions:	PCI:	80									
Inspection Comments:											
Sample Number:	101	Type:	R	Area:	4372.00 SqFt		PCI:	80			
Sample Comments:											
57	WEATHERING		M	4372.00 SqFt							

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY	Area:	179,035 SqFt		
Section:	125 of 5		From:	-		To:	-		Last Const.:	12/1/2006	
Surface:	AAC		Family:	CA653-RL-TW-AAC-APC		Zone:	Category:		Rank:	P	
Area:	5,738 SqFt		Length:	125 Ft		Width:	50 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1986		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	12/1/2006		Work Type: Mill and Overlay				Code:	ML-OVL		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	1		Surveyed:	1				
Conditions:	PCI: 66										
Inspection Comments:											
Sample Number:	100		Type:	R		Area:	5738.00 SqFt		PCI:	66	
Sample Comments:											
48	L & T CR		L	282.00 Ft							
52	RAVELING		L	1148.00 SqFt							
56	SWELLING		L	141.00 SqFt							
57	WEATHERING		M	4590.00 SqFt							

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT						
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	81,910 SqFt			
Section:	220		of	3	From:	-		To:	-		Last Const.:	1/1/2017
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P		
Area:	47,695 SqFt		Length:	1,280 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1942		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Work Date:	1/1/2017		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	12		Surveyed:	2					
Conditions:	PCI: 94											
Inspection Comments:												
Sample Number:	110		Type:	R		Area:	3500.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	3500.00 SqFt								
Sample Number:	116		Type:	R		Area:	4198.00 SqFt		PCI:	94		
Sample Comments:												
57	WEATHERING		L	4198.00 SqFt								

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT										
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	81,910 SqFt					
Section:	225		of	3		From:	-		To:	-		Last Const.:	1/1/2013	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:			Rank:	P	
Area:	12,448 SqFt		Length:	350 Ft		Width:	35 Ft							
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:			Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0				
Section Comments:														
Work Date:	1/1/2013		Work Type:	New Construction - Initial				Code:	NU-IN		Is Major M&R:	True		
Last Insp. Date:	5/25/2022		TotalSamples:	3		Surveyed:	1							
Conditions:	PCI: 89													
Inspection Comments:														
Sample Number:	118		Type:	R		Area:	4778.00 SqFt		PCI:	89				
Sample Comments:														
57	WEATHERING		L	4300.00 SqFt										
57	WEATHERING		M	478.00 SqFt										

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT							
Branch:	TW B		Name:	TAXIWAY B		Use:	TAXIWAY	Area:	81,910 SqFt			
Section:	235	of 3	From:	-			To:	-			Last Const.:	5/9/2017
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P		
Area:	21,767 SqFt		Length:	430 Ft		Width:	45 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:				Grade:	0		Lanes:		0		
Section Comments:												
Work Date:	1/1/1942		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R: True		
Work Date:	5/9/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R: True		
Last Insp. Date:	5/25/2022		TotalSamples:	4		Surveyed:		1				
Conditions:	PCI: 94											
Inspection Comments:												
Sample Number:	101	Type:	R	Area:	6344.00 SqFt			PCI:	94			
Sample Comments:												
57	WEATHERING		L	6344.00 SqFt								

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY	Area:	85,087 SqFt		
Section:	315 of 1		From:	-		To:	-		Last Const.:	1/1/2015	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Rank:	P	
Area:	85,087 SqFt		Length:	1,830 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/1970		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1970		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2015		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	21		Surveyed:	3				
Conditions:	PCI: 93										
Inspection Comments:											
Sample Number:	104		Type:	R		Area:	3594.00 SqFt		PCI:	91	
Sample Comments:											
42	BLEEDING		N		1.00 SqFt						
48	L & T CR		L		8.00 Ft						
57	WEATHERING		L		3594.00 SqFt						
Sample Number:	109		Type:	R		Area:	3504.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L		3504.00 SqFt						
Sample Number:	115		Type:	R		Area:	3545.00 SqFt		PCI:	94	
Sample Comments:											
57	WEATHERING		L		3545.00 SqFt						

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT				
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	242,364 SqFt
Section:	400	of 4	From:	-		To:	-		Last Const.: 5/9/2017
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:	Category:		Rank:	P
Area:	38,598 SqFt		Length:	823 Ft		Width:	35 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0	Lanes:		0	
Section Comments:									
Work Date:	5/9/2017		Work Type: New Construction - AC			Code:	NC-AC		Is Major M&R: True
Last Insp. Date:	5/25/2022		TotalSamples:	7		Surveyed:	1		
Conditions:	PCI: 94								
Inspection Comments:									
Sample Number:	404	Type:	R	Area:	5000.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	5000.00 SqFt					

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	242,364 SqFt			
Section:	405		of	4	From:	-		To:	-		Last Const.:	5/9/2017
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P		
Area:	76,359 SqFt		Length:	1,910 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft	
Shoulder:	Street Type:				Grade:		0		Lanes:		0	
Section Comments:												
Work Date:	1/1/1970		Work Type: BUILT				Code:	IMPORTED		Is Major M&R: True		
Work Date:	1/1/1970		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R: True		
Work Date:	5/9/2017		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R: True		
Last Insp. Date:	5/25/2022		TotalSamples:	13		Surveyed:		2				
Conditions:	PCI: 94											
Inspection Comments:												
Sample Number:	411		Type:	R		Area:	6000.00 SqFt		PCI: 94			
Sample Comments:												
57	WEATHERING		L	6000.00 SqFt								
Sample Number:	417		Type:	R		Area:	6000.00 SqFt		PCI: 94			
Sample Comments:												
57	WEATHERING		L	6000.00 SqFt								

Network:	VNC		Name:	VENICE MUNICIPAL AIRPORT							
Branch:	TW D		Name:	TAXIWAY D		Use:	TAXIWAY	Area:	242,364 SqFt		
Section:	410	of 4	From:	-			To:	-		Last Const.:	1/1/2013
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:		Rank:	P	
Area:	17,828 SqFt		Length:	340 Ft		Width:	35 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	1/1/2013		Work Type:	New Construction - Initial			Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	4		Surveyed:	1				
Conditions:	PCI:	88									
Inspection Comments:											
Sample Number:	420	Type:	R	Area:	4169.00 SqFt		PCI:	88			
Sample Comments:											
57	WEATHERING		L	3544.00 SqFt							
57	WEATHERING		M	625.00 SqFt							

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT							
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY		Area:	213,706 SqFt		
Section:	505 of 5		From:	-			To:	-		Last Const.:	1/1/2013	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:	Rank: P		
Area:	62,102 SqFt		Length:	1,722 Ft		Width:	35 Ft					
Slabs:			Slab Length:	Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:			Street Type:			Grade:	0		Lanes:	0		
Section Comments:												
Work Date:	1/1/1970		Work Type:	BUILT				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/1970		Work Type:	OVERLAY				Code:	IMPORTED		Is Major M&R:	True
Work Date:	1/1/2013		Work Type:	Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	17		Surveyed:	3					
Conditions:	PCI: 87											
Inspection Comments:												
Sample Number:	106		Type:	R		Area:	3500.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	2975.00 SqFt								
57	WEATHERING		M	525.00 SqFt								
Sample Number:	112		Type:	R		Area:	3500.00 SqFt		PCI:	86		
Sample Comments:												
57	WEATHERING		L	2800.00 SqFt								
57	WEATHERING		M	700.00 SqFt								
Sample Number:	117		Type:	R		Area:	3938.00 SqFt		PCI:	88		
Sample Comments:												
57	WEATHERING		L	3347.00 SqFt								
57	WEATHERING		M	591.00 SqFt								

Network:		VNC		Name:		VENICE MUNICIPAL AIRPORT																									
Branch:		TW E		Name:		TAXIWAY E		Use:		TAXIWAY		Area:		213,706 SqFt																	
Section:		510		of		5		From:		-		To:		-		Last Const.:		1/1/2013													
Surface:		AC		Family:		CA653-RL-TW-AC		Zone:				Category:				Rank:		P													
Area:		10,168 SqFt		Length:		175 Ft		Width:		50 Ft																					
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft																	
Shoulder:				Street Type:				Grade:		0		Lanes:		0																	
Section Comments:																															
Work Date:				1/1/2013				Work Type:				New Construction - Initial				Code:				NU-IN				Is Major M&R:				True			
Work Date:				5/9/2017				Work Type:				Surface Treatment - Seal Coat				Code:				ST-SC				Is Major M&R:				False			
Last Insp. Date:				5/25/2022				TotalSamples:				2				Surveyed:				2											
Conditions:				PCI:				85																							
Inspection Comments:																															
Sample Number:				120				Type:		R		Area:		5281.00 SqFt				PCI:		88											
Sample Comments:																															
57		WEATHERING				L		4489.00		SqFt																					
57		WEATHERING				M		792.00		SqFt																					
Sample Number:				121				Type:		R		Area:		4887.00 SqFt				PCI:		83											
Sample Comments:																															
48		L & T CR				L		46.00		Ft																					
57		WEATHERING				L		4154.00		SqFt																					
57		WEATHERING				M		733.00		SqFt																					

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT						
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	213,706 SqFt		
Section:	515 of 5		From:	-		To:	-		Last Const.:	1/1/2015	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Rank:	P	
Area:	21,560 SqFt		Length:	415 Ft		Width:	40 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	1/1/2015		Work Type: New Construction - Initial				Code:	NU-IN		Is Major M&R:	True
Last Insp. Date:	5/25/2022		TotalSamples:	5		Surveyed:	1				
Conditions:	PCI: 91										
Inspection Comments:											
Sample Number:	125		Type:	R		Area:	4009.00 SqFt		PCI:	91	
Sample Comments:											
42	BLEEDING		N	1.00 SqFt							
57	WEATHERING		L	3809.00 SqFt							
57	WEATHERING		M	200.00 SqFt							

Network:	VNC			Name:	VENICE MUNICIPAL AIRPORT									
Branch:	TW E		Name:	TAXIWAY E		Use:	TAXIWAY	Area:	213,706 SqFt					
Section:	550		of	5		From:	-		To:	-		Last Const.:	1/1/2013	
Surface:	AC		Family:	CA653-RL-TW-AC		Zone:			Category:			Rank:	P	
Area:	9,260 SqFt		Length:	208 Ft		Width:	37 Ft							
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:			Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0					
Section Comments:														
Work Date:	1/1/1942		Work Type: BUILT				Code:	IMPORTED		Is Major M&R:	True			
Work Date:	1/1/1942		Work Type: OVERLAY				Code:	IMPORTED		Is Major M&R:	True			
Work Date:	1/1/2013		Work Type: Complete Reconstruction - AC				Code:	CR-AC		Is Major M&R:	True			
Last Insp. Date:	5/25/2022		TotalSamples:	2		Surveyed:	1							
Conditions:	PCI: 80													
Inspection Comments:														
Sample Number:	100		Type:	R		Area:	4473.00 SqFt		PCI:	80				
Sample Comments:														
50	PATCHING		L	216.00 SqFt										
57	WEATHERING		L	3618.00 SqFt										
57	WEATHERING		M	639.00 SqFt										

Network:	VNC	Name:	VENICE MUNICIPAL AIRPORT						
Branch:	TW F	Name:	TAXIWAY F		Use:	TAXIWAY	Area:	11,675 SqFt	
Section:	450	of	1	From:	-	To:	-	Last Const.:	5/9/2017
Surface:	AC	Family:	CA653-RL-TW-AC		Zone:		Category:	Rank: P	
Area:	11,675 SqFt		Length:	205 Ft		Width:	41 Ft		
Slabs:	Slab Length:		Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:	Street Type:			Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	1/1/1942		Work Type: BUILT			Code:	IMPORTED		Is Major M&R: True
Work Date:	1/1/1942		Work Type: OVERLAY			Code:	IMPORTED		Is Major M&R: True
Work Date:	5/9/2017		Work Type: Complete Reconstruction - AC			Code:	CR-AC		Is Major M&R: True
Last Insp. Date:	5/25/2022		TotalSamples:	3		Surveyed:	1		
Conditions:	PCI:	94							
Inspection Comments:									
Sample Number:	101	Type:	R	Area:	3444.00 SqFt		PCI:	94	
Sample Comments:									
57	WEATHERING		L	3444.00 SqFt					



FLORIDA DEPARTMENT OF TRANSPORTATION | AVIATION OFFICE



AVIATION