

STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION OFFICE

Statewide Airfield Pavement Management Program North Palm Beach County General Aviation Airport – F45 (Regional Reliever) West Palm Beach, Florida (District 4)

February 8, 2008



Prepared for:
Florida Department of Transportation
Aviation Office

by:

URS Corporation Inc. / MACTEC Engineering & Consulting, Inc. / Planning Technology, Inc. / ASC Geosciences, Inc.







TABLE OF CONTENTS

SEC	TION	<u>P</u>	<u>AGE NO.</u>
_			
		mmary	
1.		ction	
2.		k Definition	
3.		nt Inventory	
4.		nt Condition	
5.		nt Condition Prediction	
6. 7.		nance Policies and costs	
7. 8.		nt Rehabilitation Needs Analysisance and Rehabilitation Plan	
o. 9.		Aids	
9. 10.		nendations	
10.	Reconni	nendations	,23
LIST	r of fic	GURES	
		avement Life Cycle	4
_		CI Rating Scale	
_		avement Area by Surface Type	
_		etwork PCI Distribution by Rating Category	
		ercentage of Pavement Area within Each PCI Range by Pavement U	
_		redicted PCI by Pavement Use	
		udget Scenario Analysis	
Ū		·	
LIST	Γ OF TA	BLES:	
		mpling Rate for FDOT Condition Surveys	
Tabl	e 2-1: No	orth Palm Beach County General Aviation Airport Network Definition	on10
Tabl	e 3-1: Pa	vement Area by Pavement Use	12
Tabl	e 4-1: Co	ondition by Pavement Use	14
Tabl	e 6-1: Ro	outine Maintenance Activities for Airfield Pavements	18
Tabl	e 6-2: Cri	itical PCI for Regional Reliever Airports	19
Tabl	e 6-3: De	esired Minimum PCI for Regional Reliever Airports	19
Tabl	e 6-4: Ma	&R Activities for Regional Reliever Airports	20
Tabl	e 6-5: Ma	aintenance Unit Costs for FDOT	20
Tabl	e 6-6: M	&R Activities and Unit Costs by Condition for Regional Reliever Ai	irports . 21
Tabl	e 8-1: M	&R Costs under Unlimited Funding Scenario	23
4 DD			
	ENDIX	NI IDC'' M ID II TII	
	endix A	Network Definition Map and Pavement Inventory Table	
11	endix B	PCI Re-inspection Report	
	endix C	2007 Condition Map and Tables	
	endix D	Area-Weighted PCI Results by Branch	
	endix E	Major M&R Plan by Year	
	endix F	10-Year M&R Map	
Appe	endix G	Photographs	

EXECUTIVE SUMMARY

URS Corporation, Inc., MACTEC Engineering and Consulting, Inc. (MACTEC), Planning Technology, Inc. (PTI), and ASC Geosciences, Inc. (ASCG) were awarded with a contract to provide services in support of the Florida Department of Transportation (FDOT) Aviation Office for Phase II of the Statewide Aviation Pavement Management program. As part of this contract, MACTEC conducted pavement condition survey for airside pavements at North Palm Beach County General Aviation Airport, evaluated the condition and developed a maintenance and rehabilitation program to improve conditions to prescribed minimum levels.

The total pavement area in 2007 at North Palm Beach County General Aviation Airport is 2,238,186 square feet. The breakdown of pavement area for each pavement use is provided as follows:

Pavement Area by Pavement Use

Use	Area, SqFt	% of Total Area
Runway	750,500	34
Taxiway	476,769	21
Apron	1,010,917	45
Total	2,238,186	100

Prepared by BX


Checked by TH

The overall area-weighted Pavement Condition Index (PCI) of the areas in 2007 is 83, representing a Satisfactory overall network condition.

The figure below provides the PCI distribution by rating category for the network. Approximately 99.6% of the network is in Good and Satisfactory condition while 0.4% of the network is in Fair condition.

The condition summary by pavement use table illustrates the area-weighted PCI computed individually for each use. On average, the runways, taxiways, and aprons are all in Satisfactory condition.

Network PCI Distribution by Rating Category



Condition Summary by Pavement Use

Use	Area-Weighted PCI
Runway	81
Taxiway	84
Apron	84
All	83

Prepared by BX Checked by TH

Based on the 2007 inspections, no immediate major M&R is needed for the airport.

A forecast of Major M&R needs for a 10-year period was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval.

10 Year M&R Costs under Unlimited Funding Scenario

Year	Preventive	Major M&R >= Critical	Major M&R < Critical	Total
2008	\$72,395	\$0	\$0	\$72,395
2009	\$238,164	\$0	\$0	\$238,164
2010	\$285,423	\$0	\$0	\$285,423
2011	\$330,368	\$0	\$0	\$330,368
2012	\$380,122	\$0	\$26,663	\$406,785
2013	\$426,840	\$0	\$0	\$426,840
2014	\$486,653	\$0	\$0	\$486,653
2015	\$438,843	\$0	\$1,018,557	\$1,457,400
2016	\$352,957	\$0	\$1,392,312	\$1,745,269
2017	\$382,313	\$0	\$33,507	\$415,820
Total	\$3,394,078	\$0	\$2,471,038	\$5,865,117

Note: Cost figures are rounded down. Sum may be different. Costs are adjusted for inflation.

*Prepared by BX**

*Checked by TH**

The 10 year analysis suggests an annual budget on the order of \$587 thousand would be expected to maintain the overall condition. However, the area-weighted PCI would decrease from 83 in 2007 to 79 in 2017. A small number of large projects are forecasted late in the analysis period that would need to be programmed over multiple years.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all North Palm Beach County General Aviation Airport pavements in 2017 may remain near 79. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for North Palm Beach County General Aviation Airport is conducted at some point in the 10-year plan.

1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. These public airports range from small general aviation airports to large international hub airports. These airports serve business travelers, tourism, and cargo operations crucial to the daily life of the people of Florida.

There are millions of square yards of pavement for the runways, taxiways, aprons and other areas that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time. In order to support the planning, scheduling, and design of the M&R activities, FDOT has implemented pavement management system technology.

This report describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented at your airport as a result of your participation in the Statewide Aviation Pavement Management Program.

1.1 Purpose

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the Florida Department of Transportation (FDOT) Aviation Office Statewide Pavement Management Program and the roles and responsibilities of the program's participants
- Provide background information on pavement management principles, objectives, and benefits to the participating airport
- Outline the procedures used to collect, evaluate and report pavement inspection results at your airport
- Present the findings from the inspection and analysis of the needs for maintenance and rehabilitation activities for this airport.

1.2 FDOT Aviation PMS Program

In 1992, FDOT implemented a Pavement Management System (PMS) program to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement maintenance. This system was implemented and condition surveys performed in 1992 and 1993 and again updated in 1998 and 1999. The proprietary system, AIRPAV, is no longer supported.

In 2004, the FDOT Aviation Office undertook a project to update the PMS Program software utilized for the PMS program. The Aviation Office selected a consultant team consisting of URS Corporation, Inc., MACTEC Engineering and Consulting, Inc. (MACTEC), Planning Technology, Inc. (PTI), and ASC Geosciences, Inc. (ASCG) to aid with the implementation of the program update. This project involved a review of the AIRPAV software and other available

PMS software. As a result of this review, MicroPAVER was selected as the software for the update project. Condition data from the 1998/1999 surveys were converted to the MicroPAVER system.

The inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999 to the extent that information was available. Detailed, specific procedures for the inspection and collection of pavement data were developed for this project. A web-site (www.floridaairportpavement.com) was developed for the input of data under secure procedures. The site also has a public section for dissemination of information to the general public.

1.3 Organization

The FDOT Aviation Office manages the day-to-day details of the Statewide PMS and the updates. The Aviation Office Airport Engineering Manager serves as the Program Manager (PM) monitoring the work of the Consultant. The Aviation Office has review and approval authority for each program task.

1.3.1 Consultant Role

The Consultant (MACTEC Engineering and Consulting/URS Corporation/Planning Technology/ASC Geosciences) developed the PMS based upon procedures outlined in FAA Advisory Circular 150/5380-6B Guidelines and Procedures for Maintenance of Airport Pavements (FAA/AC) and ASTM D 5340 Standard Test Method for Airport Pavement Condition Index Surveys (2004). The Consultant provides technical and administrative assistance to the Aviation Office PM, during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the PMS. A website is available to view and update airport information, including construction activities and pavement condition data. In addition, pavement evaluation reports will be available for viewing and download from the site (www.floridaairportpavement.com).

1.3.2 Airport Role

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the FDOT Aviation Office. The airport should review system inventory drawings in their folder in the pavement management website and add maintenance and rehabilitation activities conducted on airside pavements on the website system inventory form.

1.4 Pavement Types and Pavement Management

1.4.1 Pavement basics

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of asphalt concrete (AC) surface, and
- Rigid pavement composed of Portland cement concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland cement concrete supports most of the load, the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the concrete. Due to the different nature of both pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

1.4.2 Pavement Management System Concept

A pavement management system (PMS) is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1, taken from FAA/AC 5380-7A Pavement Management System, illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in "Satisfactory" condition depends on how well it is maintained. The illustration demonstrates the cost of maintaining the pavement above a critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies stretch and maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi year M&R plan can be determined.




Figure 1-1: Pavement Life Cycle

Pavements deteriorate even if they do not carry any traffic. Pavement distresses may be attributed to climate, environment, materials, construction or traffic. Knowing the cause, extent and predominance of pavement distresses helps determine the most appropriate maintenance or rehabilitation work needed. Planning and applying preventive maintenance prolongs pavement life and minimizes future pavement repair costs. By projecting the rate of deterioration, a life cycle cost analysis can be performed for various alternatives, and the optimal time of application of the most feasible alternative can be determined. Such a decision is critical in order to avoid higher M&R costs at a later date.

A PMS enables the managing agency to identify and maintain the pavement conditions, keeping them at the upper end of the service life-condition curve. At this point, the total annual costs between maintaining a good pavement above a critical condition is much less than rehabilitating a poor pavement that has rapidly deteriorated beyond a critical condition level.

A PMS is a long-term planning tool that will result in an overall improvement of the pavement network condition and will also result in savings by applying the appropriate maintenance and rehabilitation activity at the appropriate time. Accurate estimates and timely M&R decisions and budgeting are of great importance when managing approximately 300 million square feet of Florida airside pavements.

1.4.3 Pavement Inspection Methodology for PMS

Pavement condition assessment is one of the primary decision variables in any airport pavement management system. Pavement condition assessments generally include visual surveys in accordance with ASTM D 5340, Standard Test Method for Airport Pavement Condition Index Surveys and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other indepth engineering evaluation or sampling and testing methods.

Pavement sections are broken down into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Sample unit sizes are approximately 5000 ± 2000 square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements. Before the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of branches, sections, use patterns, construction types and history. The sampling rate used for FDOT Statewide Pavement Management Program is provided in Table 1-1 below.

Table 1-1: Sampling Rate for FDOT Condition Surveys

AC Pavements			PCC Pavements		
N	n		N	n	
IN	N Runway Others		Runway	Others	
1-4	1	1	1-3	1	1
5-10	2	1	4-6	2	1
11-15	3	2	7-10	3	2
16-30	5	3	11-15	4	2
31-40	7	4	16-20	5	3
41-50 <u>></u> 51	8	5	21-30	7	3
<u> 2</u> 51	20% but <20	10% but <10	31-40	8	4
	_	_	41-50	10	5
			<u>></u> 51	20% but <u><</u> 20	10% but <u><</u> 10

Where

N = total number of sample units in sectionn = number of sample units to inspect

Prepared by BX

Checked by TH

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the section. In the case when nonrepresentive distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each section. PCI values range from 0 to 100. MicroPAVER provides a rating scale that relates PCI to pavement condition, with a PCI between 0 and 10 considered 'Failed' pavement and a PCI between 86 and 100 considered 'Good' pavement, with five other conditions for PCI values between 11 and 85. Figure 1-2 shows the PCI scale.




Figure 1-2: PCI Rating Scale

1.5 Definitions

Aviation Office - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office worked closely with FDOT District Aviation Specialists, during development of this project. District Aviation Specialists will consult with airport owners in implementation of project recommendations.

<u>Base Course</u> - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

<u>Branch</u> – (Facility in prior system) - A runway, taxiway or apron is called a Branch. This is an easy reference to a recognizable component of airport pavement. In this report, Branch ID maintains the original AirPAV identification where 100 series through 3000 series facilities are taxiways, 4000 and 5000 series facilities are aprons (the 5000 series represent runup aprons and turnarounds), and 6000 series facilities are runways. It also includes the common designation for the item e.g. RW 18-36.

Pavement Evaluation Report –North Palm Beach County General Aviation Airport Florida Statewide Pavement Management Program February 8, 2008

<u>Category</u> - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA for general aviation or community airports
- RL for regional relievers or small hubs
- PR for primary

<u>Critical PCI</u> – The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

<u>Distress Type</u> - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland cement concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

<u>Florida DOT (FDOT)</u> - Florida Department of Transportation was represented in this project by the Office of Aviation.

<u>Localized M&R (Maintenance and Repair)</u> – Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

<u>Global M&R</u>- Global M&R is defined as activities applied to entire pavement sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

<u>MicroPAVER</u> – A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that if properly implemented, maintained and operated it meets the pavement management system requirements described by FAA in Advisory Circular 150/5380-7A.

<u>Minimum Condition Level</u> - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

<u>Major M&R (e.g. Rehabilitation)</u> – Activities performed over the entire area of a pavement section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

<u>Network Definition</u> – (Airport Sketch in prior system) – A Network Definition is a CAD drawing which shows the airport pavement outline with Branch and Section boundaries. This sketch is intended to assist the user of the report to quickly associate information from the text to a location on the airport. This drawing also includes the PCI sample units and is used to identify

Pavement Evaluation Report –North Palm Beach County General Aviation Airport Florida Statewide Pavement Management Program February 8, 2008

those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport in this report is in Appendix A along with a table of inventory data.

<u>Pavement Condition Index (PCI)</u> – The Pavement Condition Index is a number which represents the condition of a pavement segment at an instant in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340-04, "Standard Test Method for Airport Pavement Condition Index Surveys," published by ASTM International.

<u>Pavement Evaluation</u> – A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

<u>Pavement Management</u> – Pavement management is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

<u>Rank</u> – Pavement rank in MicroPAVER determines the priority to be assigned to a pavement section when developing an M&R plan. Pavement sections are ranked as follows according to their use:

- P for Primary pavements, such as primary runways, primary taxiways, and primary aprons
- S or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons
- T for Tertiary pavements such as "T' hangars and slightly used aprons

<u>Reconstruction</u> – Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new, or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

<u>Rehabilitation</u> – Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement, and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

<u>Sample Unit</u> – Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are $5,000 \pm 2,000$ square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements.

<u>Section</u> – (Feature in prior system) - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

Pavement Evaluation Report –North Palm Beach County General Aviation Airport Florida Statewide Pavement Management Program February 8, 2008

 $\underline{\text{Section ID}}$ – A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series sections are taxiways, 4000 and 5000 series sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series sections are runways.

<u>Use</u> – In MicroPAVER use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

2. NETWORK DEFINITION

North Palm Beach County General Aviation Airport (F45) is located approximately 12 miles northwest of West Palm Beach, Florida. Owned by Palm Beach County and operated by the Palm Beach County Airports Department, this airport focuses primarily on large corporate aircraft, flight training, and other general aviation activities and jet traffic. The airport facility includes three runways: Runway 8R-26L, Runway 8L-26R, and Runway 13-31. Runway 8L-26R is a turf runway. North Palm Beach County General Aviation Airport is designated as a Regional Reliever (RL) airport and is located in District 4 of the Florida Department of Transportation.

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units. The airport pavement network is subdivided into separate branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then divided into sections with similar pavement construction and performance that may share other common attributes. Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage.

The network definition is used to identify changes in the network since the most recent update in 1998/1999 and also to plan the field inspection activities for 2007 survey. Prior to the field inspection process, the network definition drawing was updated. The purpose of this update is to compare the previous airport configuration and history with the current airport configuration and history and update the existing drawing showing network branch, section and sample unit designations to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important history record.

The updated network definition fields of North Palm Beach County General Aviation Airport are provided in Table 2-1 and the updated network definition drawing of the airport is given in Appendix A. The field of *Rank* in Table 2-1 is defined in the definitions section in section 1.

Table 2-1: North Palm Beach County General Aviation Airport
Network Definition

Branch Name	Section ID	Rank
NORTH APRON	4105	Р
	4110	Р
	4115	Р
	4120	Р
RUN-UP & EAST T'S APRONS	5105	Р
	5110	Р
	5115	Р
	5120	Р
T-HANGAR APRON	4205	Р
RUNWAY 13-31	6205	S
RUNWAY 8R-26L	6105	Р
TAXIWAY D	405	Р
	410	Р

Table 2-1: North Palm Beach County General Aviation Airport Network Definition

Branch Name	Section ID	Rank
TAXIWAY E	505	Р
TAXIWAY F	605	Р
	610	Р
	615	Р
TAXIWAY J	1005	Р
	1010	Р
TAXIWAY K	1105	Р
	1110	Р
	1115	Р
TAXIWAY L	1205	Р
TAXIWAY M	1305	Р
TAXIWAY N	1405	Р
TAXIWAY O	1505	Р
TAXIWAY P	1605	Р
TAXIWAY Q	1705	Р
TAXIWAY R	1805	Р

Checked by TH

3. PAVEMENT INVENTORY

The detailed pavement inventory was updated to reflect the network definition update and field inspection results.

The total pavement area in 2007 at North Palm Beach County General Aviation Airport is 2,238,186 square feet. The breakdown of pavement area for each pavement use is provided in Table 3-1.

Table 3-1: Pavement Area by Pavement Use

Use	Area, SqFt	% of Total Area
Runway	750,500	34
Taxiway	476,769	21
Apron	1,010,917	45
Total	2,238,186	100

Prepared by BX

Checked by TH

Figure 3-1 presents the breakdown of the pavement area at North Palm Beach County General Aviation Airport by surface type.

PCC
1%

AC - Asphalt Concrete Pavement
PCC - Portland Cement Concrete

AC
99%

Prepared by BX

Checked by TH

Figure 3-1: Pavement Area by Surface Type

Details of pavement section information including section dimensions, rank, surface type, last construction date and last inspection date are given in Appendix A.

4. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340 "Standard Practice for Airport Pavement Condition Index Surveys." These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

Pavement condition inspections at North Palm Beach County General Aviation Airport were performed in September 2007. Data were recorded in the field using hand-held PDA (personal digital assistant) technology. The identifying information for each sample unit was pre-loaded into the PDA, and the survey results were entered directly, at the time of inspection. This simplified data handling and management.

During the inspections Global Positioning System (GPS) coordinates were recorded at the centroid of each sample unit. The centroid is usually the geometric center of the area but in cases where sample units are irregular in shape this is the center of mass. These data are presented in tables on updated Network Definition drawings available from the website.

After the completion of data collection, the data were imported into MicroPAVER and PCI values were calculated for the pavement sections.

Appendix B includes detailed distress data generated by MicroPAVER, Appendix C contains a table and a map of PCI results by section inspected in 2007, and Appendix D contains a table of PCI results by branch.

According to the 2007 survey, the overall area-weighted PCI at North Palm Beach County General Aviation Airport is 83, representing a Satisfactory overall network condition.

Figure 4-1 provides the PCI distribution by rating category for the network.




Figure 4-1: Network PCI Distribution by Rating Category

Approximately 99.6% of the network is in Good and Satisfactory condition while 0.4% of the network is in Fair condition. Table 4-1 illustrates the area-weighted PCI computed individually for each pavement use.

Table 4-1: Condition by Pavement Use


Use	Area-Weighted PCI
Runway	81
Taxiway	84
Apron	84
All	83

Prepared by BX Checked by TH


On average, the runways, taxiways, aprons are all in Satisfactory condition.

Figure 4-2 presents the breakdown of PCI by range for each pavement use.


Figure 4-2: Percentage of Pavement Area within Each PCI Range by Pavement Use







(c) Apron



Prepared by BX

Checked by TH

5. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 5-1 illustrates the predicted performance of pavements at North Palm Beach County General Aviation Airport based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum condition criteria for Regional Reliever (RL) airports.




Figure 5-1: Predicted PCI by Pavement Use

Appendix C presents the tabular summary of the predicted Section PCI for each year from 2008 to 2017.

6. MAINTENANCE POLICIES AND COSTS

6.1 Policies

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature, and are recommended to help achieve the performance goal.

Table 6-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. These repairs are used in an analysis only if there is an inspection within one year prior to the first year of the analysis period. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called "Critical PCI." The critical PCI levels for different pavement and branch types established in Phase I of Statewide Pavement Management Program were reviewed and updated for development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 6-2 gives the critical PCI levels for Regional Reliever Airports.

Table 6-1: Routine Maintenance Activities for Airfield Pavements

Surface	Distress	Severity*	Work Type	Code	Work Unit
	Alligator Crack	M, H	Patching - AC Deep	PA-AD	SqFt
	Bleeding	N/A	No Localized M&R	NONE	SqFt
	Block Crack	M, H	Crack Sealing – AC	CS-AC	SqFt
	Corrugation	L, M, H	Patching - AC Deep	PA-AD	SqFt
	Depression	M, H	Patching - AC Deep	PA-AD	SqFt
	Jet Blast	N/A	Patching - AC Deep	PA-AD	SqFt
	Joint Ref. Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	L & T Crack	M, H	Crack Sealing – AC	CS-AC	Ft
AC	Oil Spillage	N/A	Patching - AC Shallow	PA-AS	SqFt
7.0	Patching	M, H	Patching - AC Deep	PA-AD	SqFt
	Polished Agg.	N/A	No Localized M&R	NONE	SqFt
		L	Surface Sealing - Rejuvenating	SS-RE	SqFt
	Raveling	M	Surface Seal - Coal Tar	SS-CT	SqFt
		Н	Microsurfacing	MI-AC	SqFt
	Rutting	M, H	Patching - AC Deep	PA-AD	SqFt
	Shoving	M, H	Grinding (Localized)	GR-LL	SqFt
	Slippage Crack	N/A	Patching - AC Shallow	PA-AS	SqFt
	Swelling	M, H	Patching - AC Deep	PA-AD	SqFt
	Blow-Up	L, M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Corner Break	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Linear Crack	M, H	Crack Sealing – PCC	CS-PC	Ft
	Durability Crack	Н	Slab Replacement – PCC	SL-PC	SqFt
	Durability Crack	М	Patching - PCC Full Depth	PA-PF	SqFt
	Jt. Seal Damage	M, H	Joint Seal (Localized)	JS-LC	Ft
	Small Patch	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
PCC	Large Patch	M, H	Patching - PCC Full Depth	PA-PF	SqFt
FCC	Popouts	N/A	No Localized M&R	NONE	SqFt
	Pumping	N/A	No Localized M&R	NONE	SqFt
	Scaling	Н	Slab Replacement – PCC	SL-PC	SqFt
	Faulting	M, H	Grinding (Localized)	GR-PP	Ft
	Shattered Slab	M, H	Slab Replacement – PCC	SL-PC	SqFt
	Shrinkage Crack	N/A	No Localized M&R	NONE	Ft
	Joint Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Corner Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt

^{*}L = Low, M = Medium, H = High

Checked by TH

Table 6-2: Critical PCI for Regional Reliever Airports

Use	Critical PCI
Runway	65
Taxiway	65
Apron	65

Checked by TH

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 6-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of Regional Reliever Airports.

Table 6-3: Desired Minimum PCI for Regional Reliever Airports

Minimum PCI				
Runway Taxiway Apron				
75	65	65		

Prepared by BX

Checked by TH

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 6-2 and our experience with pavement management systems, the PCI trigger range when the likely activity would be a mill and resurface was 31 to 55 and reconstruction at a PCI of 30 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation. With this objective, microsurfacing has been recommended to maintain pavements that have a PCI from 56 and 79. Microsurfacing is a surface treatment suggested for pavements in Fair to Satisfactory condition to extend the pavement life by five to seven years.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 6-4 summarizes the M&R activities for Regional Reliever Airports based on PCI value.

Table 6-4: M&R Activities for Regional Reliever Airports

	Activity	PCI Range
Maintenance	Crack Sealing and Full-Depth Patching	80 and 90
Rehabilitation	Microsurfacing (AC) or Concrete Pavement Restoration (PCC)	56 to 79
	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	31 to 55
	Reconstruction	30 and less

Checked by TH

6.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were reviewed in Phase I of Statewide Pavement Mangement Program in order to determine meaningful costs for the program. Table 6-5 presents the unit costs summary.

Table 6-5: Maintenance Unit Costs for FDOT

Code	Name	Cost	Unit
PA-AL	Patching – AC Leveling	\$2.00	SqFt
PA-AS	Patching – AC Shallow	\$4.00	SqFt
PA-PF	Patching – PCC Full Depth	\$50.00	SqFt
PA-PP	Patching – Partial Depth	\$35.00	SqFt
SL-PC	Slab Replacement	\$15.00	SqFt
CS-PC	Crack Sealing – PCC	\$2.00	Ft
UN-PC	Undersealing – PCC	\$3.00	Ft
CS-AC	Crack Sealing – AC	\$2.00	Ft
GR-PP	Grinding (Localized for PCC)	\$20.00	Ft
GR-LL	Grinding (Localized for AC)	\$6.00	SqFt
JS-LC	Joint Seal (Localized)	\$1.75	Ft
JS-SI	Joint Seal - Silicon	\$2.50	Ft
PA-AD	Patching – AC Deep	\$7.00	SqFt
OL-AT	Overlay – AC Thin	\$1.50	SqFt
SS-CT	Surface Seal – Coal Tar	\$0.20	SqFt
SS-RE	Surface Seal – Rejuvenating	\$0.15	SqFt
ST-SS	Surface Treatment – Slurry Seal	\$0.25	SqFt
ST-ST	Surface Treatment – Sand Tar	\$0.25	SqFt
MI-AC	Microsurfacing	\$0.90	SqFt

Prepared by BX

Checked by TH

Pavement Evaluation Report –North Palm Beach County General Aviation Airport Florida Statewide Pavement Management Program February 8, 2008

The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection is recent and only in the first year of the M&R analysis. In subsequent years MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCI. That is, for low PCI it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly. Using available unit cost data the Major M&R Cost By Condition table was set up as shown in Table 6-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

Table 6-6: M&R Activities and Unit Costs by Condition for Regional Reliever
Airports

	Activity	PCI Trigger	Cost/SqFt
Maintenance	Crack Sealing and Full-Depth	90	\$0.10
Mairiteriarice	Patching	80	\$0.40
Rehabilitation	Microsurfacing (AC) or Concrete Pavement Restoration	70	\$0.90
	(PCC)	60	\$3.68
	Mill and Overlay (AC) or Concrete Pavement Restoration	50	\$7.61
	(PCC)	40	\$7.61
	Reconstruction	30	\$18.57
	Reconstruction	20	\$18.57

Prepared by BX

Checked by TH

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

7. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Based on the 2007 inspections, no immediate major M&R is needed for this airport.

The 10 year forecast results are shown in Figure 7-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.




Figure 7-1: Budget Scenario Analysis

The following network level observations can be made from the figure above:

- The PCI will deteriorate from 83 to 66 in ten years if no M&R activities are performed.
- The PCI will remain at or above 70 through the 10-year analysis period under the unlimited budget scenario. A 2017 PCI of 79 with this scenario is 13 PCI points higher than a "No M&R" scenario. The total cost for Major M&R over this 10-year period is about \$2.5 million.

8. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCI less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 8-1 provides the summary results under the critical PCI scenario.

Table 8-1: M&R Costs under Unlimited Funding Scenario

Year	Preventive	Major M&R >= Critical	Major M&R < Critical	Total
2008	\$72,395	\$0	\$0	\$72,395
2009	\$238,164	\$0	\$0	\$238,164
2010	\$285,423	\$0	\$0	\$285,423
2011	\$330,368	\$0	\$0	\$330,368
2012	\$380,122	\$0	\$26,663	\$406,785
2013	\$426,840	\$0	\$0	\$426,840
2014	\$486,653	\$0	\$0	\$486,653
2015	\$438,843	\$0	\$1,018,557	\$1,457,400
2016	\$352,957	\$0	\$1,392,312	\$1,745,269
2017	\$382,313	\$0	\$33,507	\$415,820
Total	\$3,394,078	\$0	\$2,471,038	\$5,865,117

Note: Cost figures are rounded down. Sum may be different. Costs are adjusted for inflation.

*Prepared by BX**

*Checked by TH**

No major M&R cost is required in the first year (2008). This is a consequence of the entire airport being above Critical PCI.

Both Runway 13-31 and Runway 8R-26L are currently in Satisfactory condition with an average PCI value of 80 and 82, respectively. These runways have no immediate need for major repair. The unlimited budget scenario provides the basis for estimating the total repair cost. In reality, it is neither operationally nor fiscally prudent.

Appendix E provides details of M&R plan by year under the unlimited funding scenario and the map of the 10-year M&R plan was provided in Appendix F. It is important to understand that a PMS is a network level tool and the M&R costs provided in this report are only for planning purposes.

Pavement Evaluation Report –North Palm Beach County General Aviation Airport Florida Statewide Pavement Management Program February 8, 2008

9. VISUAL AIDS

9.1 GIS Linked Shape File

The pavement inventory data and pavement condition were linked to the airport's shape file to graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

Selected digital photographs taken during the pavement inspection were provided in an Appendix G to provide visual support to special pavement conditions or distress observed during the inspection of the facility.

Pavement Evaluation Report –North Palm Beach County General Aviation Airport Florida Statewide Pavement Management Program February 8, 2008

10. RECOMMENDATIONS

Pavement condition inspections were performed at North Palm Beach County General Aviation Airport and a 10-year M&R plan was developed based on the unlimited funding scenario.

The following recommendations were made based on 2007 condition inspections and M&R analysis results:

- Runway 13-31 and Runway 8R-26L are in Satisfactory condition and no immediate major repair is needed. The condition prediction for these two runways indicated major repair need in 2015 and 2016, respectively.
- No immediate major M&R repair is need for the aprons and taxiways due to the overall Satisfactory condition.

APPENDIX A

NETWORK DEFINITION MAP AND PAVEMENT INVENTORY TABLE

Table A-1: Pavement Inventory

Network Name	Network ID	Branch Name	Branch ID	Section ID	Length, Ft	Width, Ft	Area, SqFt	Rank	Surface	Last Const. Date	Last Insp. Date
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4105	1,500	450	675,505	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4110	90	50	4,500	Р	PCC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4115	135	60	8,250	Р	PCC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4120	800	180	172,500	Р	AC	1/1/1996	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5105	250	100	25,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5110	250	100	25,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5115	140	50	7,167	Р	AC	1/1/1996	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5120	1,800	21	43,645	Р	AC	1/1/1996	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	T-HANGAR APRON	AP T-HANG	4205	1,350	21	49,350	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	RUNWAY 13-31	RW 13-31	6205	4,300	75	322,500	S	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	RUNWAY 8R-26L	RW 8R-26L	6105	4,280	100	428,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY D	TW D	405	280	35	10,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY D	TW D	410	600	35	21,669	Р	AC	1/1/1996	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY E	TW E	505	280	35	10,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY F	TW F	605	4,500	35	158,000	Р	AC	1/1/1994	9/17/2007

See note at end of table.

Table A-1: Pavement Inventory

Network Name	Network ID	Branch Name	Branch ID	Section ID	Length, Ft	Width, Ft	Area, SqFt	Rank	Surface	Last Const. Date	Last Insp. Date
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY F	TW F	610	250	75	19,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY F	TW F	615	120	50	9,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY J	TW J	1005	200	35	7,300	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY J	TW J	1010	80	75	7,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY K	TW K	1105	4,300	35	150,500	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY K	TW K	1110	260	35	10,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY K	TW K	1115	260	35	10,000	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY L	TW L	1205	240	35	8,700	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY M	TW M	1305	240	35	9,225	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY N	TW N	1405	240	35	9,225	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY O	TW O	1505	240	35	9,225	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY P	TW P	1605	240	35	9,225	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY Q	TW Q	1705	240	35	8,700	Р	AC	1/1/1994	9/17/2007
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY R	TW R	1805	225	35	10,000	Р	AC	1/1/1994	9/17/2007

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

APPENDIX B PCI RE-INSPECTION REPORT

APPENDIX C 2007 CONDITION MAP AND TABLES

C-1: Pavement Condition Index

Network Name	Network ID	Branch Name	Branch ID	Section ID	Length, Ft	Width, Ft	Area, SqFt	Rank	Surface	Last Const. Date	Last Insp. Date	2007 PCI
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4105	1,500	450	675,505	Р	AC	1/1/1994	9/17/2007	85
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4110	90	50	4,500	Р	PCC	1/1/1994	9/17/2007	79
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4115	135	60	8,250	Р	PCC	1/1/1994	9/17/2007	84
NORTH PALM BEACH COUNTY GA	F45	NORTH APRON	AP N	4120	800	180	172,500	Р	AC	1/1/1996	9/17/2007	80
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5105	250	100	25,000	Р	AC	1/1/1994	9/17/2007	82
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5110	250	100	25,000	Р	AC	1/1/1994	9/17/2007	86
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5115	140	50	7,167	Р	AC	1/1/1996	9/17/2007	84
NORTH PALM BEACH COUNTY GA	F45	RUN-UP & EAST T'S APRONS	AP RU, T'S	5120	1,800	21	43,645	Р	AC	1/1/1996	9/17/2007	89
NORTH PALM BEACH COUNTY GA	F45	T-HANGAR APRON	AP T-HANG	4205	1,350	21	49,350	Р	AC	1/1/1994	9/17/2007	83
NORTH PALM BEACH COUNTY GA	F45	RUNWAY 13-31	RW 13-31	6205	4,300	75	322,500	S	AC	1/1/1994	9/17/2007	80
NORTH PALM BEACH COUNTY GA	F45	RUNWAY 8R-26L	RW 8R-26L	6105	4,280	100	428,000	Р	AC	1/1/1994	9/17/2007	82
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY D	TW D	405	280	35	10,000	Р	AC	1/1/1994	9/17/2007	80
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY D	TW D	410	600	35	21,669	Р	AC	1/1/1996	9/17/2007	86
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY E	TW E	505	280	35	10,000	Р	AC	1/1/1994	9/17/2007	81
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY F	TW F	605	4,500	35	158,000	Р	AC	1/1/1994	9/17/2007	84

See note at end of table.

C-1: Pavement Condition Index

Network Name	Network ID	Branch Name	Branch ID	Section ID	Length, Ft	Width, Ft	Area, SqFt	Rank	Surface	Last Const. Date	Last Insp. Date	2007 PCI
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY F	TW F	610	250	75	19,000	Р	AC	1/1/1994	9/17/2007	82
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY F	TW F	615	120	50	9,000	Р	AC	1/1/1994	9/17/2007	83
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY J	TW J	1005	200	35	7,300	Р	AC	1/1/1994	9/17/2007	80
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY J	TW J	1010	80	75	7,000	Р	AC	1/1/1994	9/17/2007	82
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY K	TW K	1105	4,300	35	150,500	Р	AC	1/1/1994	9/17/2007	86
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY K	TW K	1110	260	35	10,000	Р	AC	1/1/1994	9/17/2007	81
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY K	TW K	1115	260	35	10,000	Р	AC	1/1/1994	9/17/2007	82
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY L	TW L	1205	240	35	8,700	Р	AC	1/1/1994	9/17/2007	82
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY M	TW M	1305	240	35	9,225	Р	AC	1/1/1994	9/17/2007	69
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY N	TW N	1405	240	35	9,225	Р	AC	1/1/1994	9/17/2007	79
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY O	TW O	1505	240	35	9,225	Р	AC	1/1/1994	9/17/2007	83
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY P	TW P	1605	240	35	9,225	Р	AC	1/1/1994	9/17/2007	81
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY Q	TW Q	1705	240	35	8,700	Р	AC	1/1/1994	9/17/2007	86
NORTH PALM BEACH COUNTY GA	F45	TAXIWAY R	TW R	1805	225	35	10,000	Р	AC	1/1/1994	9/17/2007	76

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Table C-2: Pavement Condition Prediction

Network	Branch ID	Section ID	2007	PCI Forecast									
ID	ID Branch ib		PCI	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017
F45	AP N	4105	85	83	81	80	78	77	75	74	72	71	70
F45	AP N	4110	79	78	77	76	75	74	73	72	71	70	69
F45	AP N	4115	84	83	82	81	80	79	78	77	76	75	74
F45	AP N	4120	80	78	77	75	74	73	71	70	69	68	66
F45	AP RU, T'S	5105	82	80	79	77	76	74	73	72	70	69	68
F45	AP RU, T'S	5110	86	84	82	81	79	77	76	74	73	72	70
F45	AP RU, T'S	5115	84	82	81	79	77	76	74	73	72	70	69
F45	AP RU, T'S	5120	89	87	85	83	81	80	78	77	75	74	72
F45	AP T-HANG	4205	83	81	80	78	76	75	74	72	71	70	68
F45	RW 13-31	6205	80	78	76	74	72	69	67	65	64	62	60
F45	RW 8R-26L	6105	82	80	78	76	73	71	69	67	65	63	62
F45	TW D	405	80	78	77	76	74	73	72	70	69	68	67
F45	TW D	410	86	84	83	81	79	78	76	75	74	72	71
F45	TW E	505	81	79	78	76	75	74	72	71	70	69	67
F45	TW F	605	84	82	81	79	78	76	75	73	72	71	70
F45	TW F	610	82	80	79	77	76	75	73	72	71	69	68
F45	TW F	615	83	81	80	78	77	75	74	73	71	70	69
F45	TW J	1005	80	78	77	76	74	73	72	70	69	68	67
F45	TW J	1010	82	80	79	77	76	75	73	72	71	69	68
F45	TW K	1105	86	84	83	81	79	78	76	75	74	72	71
F45	TW K	1110	81	79	78	76	75	74	72	71	70	69	67
F45	TW K	1115	82	80	79	77	76	75	73	72	71	69	68
F45	TW L	1205	82	80	79	77	76	75	73	72	71	69	68
F45	TW M	1305	69	68	67	66	64	63	62	61	60	59	58
F45	TW N	1405	79	77	76	75	73	72	71	69	68	67	66
F45	TW O	1505	83	81	80	78	77	75	74	73	71	70	69
F45	TW P	1605	81	79	78	76	75	74	72	71	70	69	67
F45	TW Q	1705	86	84	83	81	79	78	76	75	74	72	71
F45	TW R	1805	76	75	73	72	71	69	68	67	66	65	64

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

APPENDIX D AREA-WEIGHTED PCI RESULTS BY BRANCH

Table D-1 Condition Summary by Branch

Network	Branch Name	2007 PCI
NORTH PALM BEACH COUNTY GENERAL AVIATION	NORTH APRON	84
NORTH PALM BEACH COUNTY GENERAL AVIATION	RUN-UP & EAST T'S APRONS	86
NORTH PALM BEACH COUNTY GENERAL AVIATION	T-HANGAR APRON	83
NORTH PALM BEACH COUNTY GENERAL AVIATION	RUNWAY 13-31	80
NORTH PALM BEACH COUNTY GENERAL AVIATION	RUNWAY 8R-26L	82
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY D	84
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY E	81
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY F	84
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY J	81
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY K	85
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY L	82
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY M	69
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY N	79
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY O	83
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY P	81
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY Q	86
NORTH PALM BEACH COUNTY GENERAL AVIATION	TAXIWAY R	76

APPENDIX E MAJOR M&R PLAN BY YEAR

Pavement Evaluation Report –North Palm Beach County General Aviation Airport Florida Statewide Pavement Management Program February 8, 2008

Table E-1: Major M&R Plan by Year

Natural	Branch	Branch	Section	Conford	Area,	Vaar	PCI Before	A -41: -141	PCI After	Coot
Network	Use	ID	ID	Surface	SqFt	Year	Maint.	Activities	Maint.	Cost
F45	TAXIWAY	TW M	1305	AC	9,225	2012	64	Microsurfacing	100	\$26,663
F45	RUNWAY	RW 13-31	6205	AC	322,500	2015	64	Microsurfacing	100	\$1,018,557
F45	RUNWAY	RW 8R-26L	6105	AC	428,000	2016	64	Microsurfacing	100	\$1,392,312
F45	TAXIWAY	TW R	1805	AC	10,000	2017	64	Microsurfacing	100	\$33,507

APPENDIX F 10-YEAR M&R MAP


APPENDIX G PHOTOGRAPHS



AP N Section 4110 SU 99: High Severity Joint Seal Damage (September 17, 2007)



AP N Section 4120 SU 206: Low Severity Weathering (September 17, 2007)



RW 13-31 Section 6205 SU 102: Low Severity Weathering (September 17, 2007)



TW R Section 1805 SU 100: Section Overview (September 17, 2007)




RW 8-26 Section 6105 SU 116: Low Severity L/T Cracking (September 17, 2007)



TW O Section 1505 SU 400: Section Overview (September 17, 2007)



TW M Section 1305 SU 200: Low Severity L/T Cracking (September 17, 2007)



TW J Section 1010 SU 100: Low Severity L/T Cracking (September 17, 2007)



AP T Hanger Section 4205 SU 405: Section Overview (September 17, 2007)



AP N Section 4105 SU 516: Section Overview (September 17, 2007)



AP N Section 4115 SU 98: Section Overview (September 17, 2007)