

**STATE OF FLORIDA  
DEPARTMENT OF TRANSPORTATION  
AVIATION OFFICE**

**Statewide Airfield Pavement Management Program  
Marianna Municipal Airport  
(General Aviation)  
Marianna, Florida  
(District 3)**

**March 31, 2008**



*Prepared for:*  
**Florida Department of Transportation  
Aviation Office**

*by:*  
**URS Corporation Inc. / MACTEC Engineering & Consulting, Inc. /  
Planning Technology, Inc. / ASC Geosciences, Inc.**



## **TABLE OF CONTENTS**

<u><b>SECTION</b></u>	<u><b>PAGE NO.</b></u>
-----------------------	------------------------

Executive Summary .....	ii
1. Introduction.....	1
2. Network Definition .....	10
3. Pavement Inventory .....	11
4. Pavement Condition.....	12
5. Pavement Condition Prediction .....	15
6. Maintenance Policies and costs .....	16
7. Pavement Rehabilitation Needs Analysis .....	21
8. Maintenance and Rehabilitation Plan .....	23
9. Visual Aids .....	24
10. Recommendations.....	25

### **LIST OF FIGURES**

Figure 1-1: Pavement Life Cycle.....	4
Figure 1-2: PCI Rating Scale.....	6
Figure 3-1: Pavement Area by Surface Type.....	11
Figure 4-1: Network PCI Distribution by Rating Category.....	12
Figure 4-2: Percentage of Pavement Area within Each PCI Range by Pavement Use .....	13
Figure 5-1: Predicted PCI by Pavement Use .....	15
Figure 7-1: Budget Scenario Analysis .....	22

### **LIST OF TABLES:**

Table 1-1: Sampling Rate for FDOT Condition Surveys .....	5
Table 2-1: Marianna Municipal Airport Network Definition.....	10
Table 3-1: Pavement Area by Pavement Use .....	11
Table 4-1: Condition by Pavement Use.....	13
Table 6-1: Routine Maintenance Activities for Airfield Pavements .....	17
Table 6-2: Critical PCI for General Aviation Airports .....	18
Table 6-3: Desired Minimum PCI for General Aviation Airports.....	18
Table 6-4: M&R Activities for General Aviation Airports .....	19
Table 6-5: Maintenance Unit Costs for FDOT .....	19
Table 6-6: M&R Activities and Unit Costs by Condition for General Aviation Airports...	20
Table 7-1: Summary of Immediate Major M&R Needs.....	21
Table 8-1: M&R Costs under Unlimited Funding Scenario .....	23

### **APPENDIX**

Appendix A	Network Definition Map and Pavement Inventory Table
Appendix B	PCI Re-inspection Report
Appendix C	2006 Condition Map and Tables
Appendix D	Area-Weighted PCI Results by Branch
Appendix E	Major M&R Plan by Year
Appendix F	10-Year M&R Map
Appendix G	Photographs

## **EXECUTIVE SUMMARY**

URS Corporation, Inc., MACTEC Engineering and Consulting, Inc. (MACTEC), Planning Technology, Inc. (PTI), and ASC Geosciences, Inc. (ASCG) were awarded with a contract to provide services in support of the Florida Department of Transportation (FDOT) Aviation Office for Phase II of the Statewide Aviation Pavement Management program. As part of this contract, MACTEC conducted pavement condition survey for airside pavements at Marianna Municipal Airport, evaluated the condition and developed a maintenance and rehabilitation program to improve conditions to prescribed minimum levels.

The total pavement area in 2006 at Marianna Municipal Airport is 3,126,719 square feet. The breakdown of pavement area for each pavement use is provided as follows:

### **Pavement Area by Pavement Use**

<b>Use</b>	<b>Area, SqFt</b>	<b>% of Total Area</b>
Runway	974,800	31
Taxiway	604,475	19
Apron	1,547,444	50
<b>Total</b>	<b>3,126,719</b>	<b>100</b>

*Prepared by VVD*


*Checked by TH*

The overall area-weighted Pavement Condition Index (PCI) of the areas in 2006 is 42, representing a Poor overall network condition.

The figure below provides the PCI distribution by rating category for the network. Approximately 20% of the network is in Good and Satisfactory condition while 79% of the network is in Poor to Very Poor condition.

The condition summary by pavement use table illustrates the area-weighted PCI computed individually for each use. On average, the runways, taxiways, and aprons are in Fair, Poor, and Very Poor condition, respectively.

### Network PCI Distribution by Rating Category



Prepared by VVD

Checked by TH

### Condition Summary by Pavement Use

Use	Area-Weighted PCI
Runway	63
Taxiway	50
Apron	26
<b>All</b>	<b>42</b>

Prepared by VVD

Checked by TH

The immediate M&R needs include Runway 8R-26L, Apron, and several taxiways connectors (Parallel Taxiway to Runways and North Connector Taxiway). The apron and taxiway may not be the highest priority for funding but would need to be programmed over several years. These immediate needs are summarized in the following table.

### Immediate Major M&R Needs

Branch	Section	Section Area, SqFt	Major M&R Funded**	PCI Before	Maintenance	PCI After
AP	4105	1,547,444	\$21,076,194	25	Major M&R < Critical	100
RW 8R-26L	6105	490,000	\$2,941,470	51	Major M&R < Critical	100
TW CONN N	305	20,000	\$125,800	47	Major M&R < Critical	100
TW PARALL	105	96,000	\$603,840	40	Major M&R < Critical	100
TW PARALL	150	324,375	\$3,229,154	35	Major M&R < Critical	100
		<b>Total</b>	<b>\$27,976,458</b>	<b>42*</b>	<b>← Network Avg. PCI →</b>	<b>94*</b>

\* This table shows the area-weighted PCI before and after Major M&R and routine maintenance work for the first year of the 10-year plan. It includes all pavement sections at Marianna Municipal Airport, including those sections not shown in this table.

\*\* Cost figures are rounded down. Sum may be different. Costs are adjusted for inflation.

Prepared by VVD

Checked by TH

A forecast of Major M&R needs for a 10-year period, starting from 2008, was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval.

### **10 Year M&R Costs under Unlimited Funding Scenario**

<b>Year</b>	<b>Preventive</b>	<b>Major M&amp;R ≥ Critical</b>	<b>Major M&amp;R &lt; Critical</b>	<b>Total</b>
2008	\$21,351	\$0	\$27,976,458	\$27,997,809
2009	\$139,553	\$0	\$0	\$139,553
2010	\$21,285	\$0	\$1,273,231	\$1,294,517
2011	\$19,423	\$0	\$69,956	\$89,379
2012	\$25,226	\$0	\$0	\$25,226
2013	\$34,412	\$0	\$0	\$34,412
2014	\$43,451	\$0	\$0	\$43,451
2015	\$63,014	\$0	\$0	\$63,014
2016	\$101,616	\$0	\$0	\$101,616
2017	\$130,689	\$0	\$0	\$130,689
<b>Total</b>	<b>\$600,019</b>	<b>\$0</b>	<b>\$29,319,646</b>	<b>\$29,919,666</b>

Note: Cost figures are rounded down. Sum may be different. Costs are adjusted for inflation.

*Prepared by VVD*

*Checked by TH*

The 10 year analysis suggests an annual budget on the order of \$3 million would be expected to provide an improvement in the overall condition, where the area-weighted PCI would increase from 42 in 2006 to 88 in 2017. However, as stated above, a number of large projects exist that would need to be programmed over multiple years.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all Marianna Municipal Airport pavements in 2017 may remain near 88. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for Marianna Municipal Airport is conducted at some point in the 10-year plan.

## **1. INTRODUCTION**

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. These public airports range from small general aviation airports to large international hub airports. These airports serve business travelers, tourism, and cargo operations crucial to the daily life of the people of Florida.

There are millions of square yards of pavement for the runways, taxiways, aprons and other areas that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time. In order to support the planning, scheduling, and design of the M&R activities, FDOT has implemented pavement management system technology.

This report describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented at your airport as a result of your participation in the Statewide Aviation Pavement Management Program.

### **1.1 Purpose**

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the Florida Department of Transportation (FDOT) Aviation Office Statewide Pavement Management Program and the roles and responsibilities of the program's participants
- Provide background information on pavement management principles, objectives, and benefits to the participating airport
- Outline the procedures used to collect, evaluate and report pavement inspection results at your airport
- Present the findings from the inspection and analysis of the needs for maintenance and rehabilitation activities for this airport.

### **1.2 FDOT Aviation PMS Program**

In 1992, FDOT implemented a Pavement Management System (PMS) program to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement maintenance. This system was implemented and condition surveys performed in 1992 and 1993 and again updated in 1998 and 1999. The proprietary system, AIRPAV, is no longer supported.

In 2004, the FDOT Aviation Office undertook a project to update the PMS Program software utilized for the PMS program. The Aviation Office selected a consultant team consisting of URS Corporation, Inc., MACTEC Engineering and Consulting, Inc. (MACTEC), Planning Technology, Inc. (PTI), and ASC Geosciences, Inc. (ASCG) to aid with the implementation of the program update. This project involved a review of the AIRPAV software and other available

PMS software. As a result of this review, MicroPAVER was selected as the software for the update project. Condition data from the 1998/1999 surveys were converted to the MicroPAVER system.

The inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999 to the extent that information was available. Detailed, specific procedures for the inspection and collection of pavement data were developed for this project. A web-site ([www.floridairportpavement.com](http://www.floridairportpavement.com)) was developed for the input of data under secure procedures. The site also has a public section for dissemination of information to the general public.

### **1.3 Organization**

The FDOT Aviation Office manages the day-to-day details of the Statewide PMS and the updates. The Aviation Office Airport Engineering Manager serves as the Program Manager (PM) monitoring the work of the Consultant. The Aviation Office has review and approval authority for each program task.

#### **1.3.1 Consultant Role**

The Consultant (MACTEC Engineering and Consulting/URS Corporation/Planning Technology/ASC Geosciences) developed the PMS based upon procedures outlined in FAA Advisory Circular 150/5380-6B Guidelines and Procedures for Maintenance of Airport Pavements (FAA/AC) and ASTM D 5340 Standard Test Method for Airport Pavement Condition Index Surveys (2004). The Consultant provides technical and administrative assistance to the Aviation Office PM, during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the PMS. A website is available to view and update airport information, including construction activities and pavement condition data. In addition, pavement evaluation reports will be available for viewing and download from the site ([www.floridairportpavement.com](http://www.floridairportpavement.com)).

#### **1.3.2 Airport Role**

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the FDOT Aviation Office. The airport should review system inventory drawings in their folder in the pavement management website and add maintenance and rehabilitation activities conducted on airside pavements on the website system inventory form.

### **1.4 Pavement Types and Pavement Management**

#### **1.4.1 Pavement basics**

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of asphalt concrete (AC) surface, and
- Rigid pavement composed of Portland cement concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland cement concrete supports most of the load, the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the concrete. Due to the different nature of both pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

#### **1.4.2 Pavement Management System Concept**


A pavement management system (PMS) is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1, taken from FAA/AC 5380-7A Pavement Management System, illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in "Satisfactory" condition depends on how well it is maintained. The illustration demonstrates the cost of maintaining the pavement above a critical condition before rapid deterioration occurs is much less compared to maintaining pavements after substantial deterioration has occurred.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies stretch and maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi year M&R plan can be determined.



**Figure 1-1: Pavement Life Cycle**



*Prepared by BX*

*Checked by TH*

Pavements deteriorate even if they do not carry any traffic. Pavement distresses may be attributed to climate, environment, materials, construction or traffic. Knowing the cause, extent and predominance of pavement distresses helps determine the most appropriate maintenance or rehabilitation work needed. Planning and applying preventive maintenance prolongs pavement life and minimizes future pavement repair costs. By projecting the rate of deterioration, a life cycle cost analysis can be performed for various alternatives, and the optimal time of application of the most feasible alternative can be determined. Such a decision is critical in order to avoid higher M&R costs at a later date.

A PMS enables the managing agency to identify and maintain the pavement conditions, keeping them at the upper end of the service life-condition curve. At this point, the total annual costs between maintaining a good pavement above a critical condition is much less than rehabilitating a poor pavement that has rapidly deteriorated beyond a critical condition level.

A PMS is a long-term planning tool that will result in an overall improvement of the pavement network condition and will also result in savings by applying the appropriate maintenance and rehabilitation activity at the appropriate time. Accurate estimates and timely M&R decisions and budgeting are of great importance when managing approximately 300 million square feet of Florida airside pavements.

### **1.4.3 Pavement Inspection Methodology for PMS**

Pavement condition assessment is one of the primary decision variables in any airport pavement management system. Pavement condition assessments generally include visual surveys in

accordance with ASTM D 5340, *Standard Test Method for Airport Pavement Condition Index Surveys* and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

Pavement sections are broken down into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Sample unit sizes are approximately  $5000 \pm 2000$  square feet for AC-surfaced pavements and  $20 \pm 8$  slabs for PCC-surfaced pavements. Before the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of branches, sections, use patterns, construction types and history. The sampling rate used for FDOT Statewide Pavement Management Program is provided in Table 1-1 below.

**Table 1-1: Sampling Rate for FDOT Condition Surveys**

AC Pavements			PCC Pavements		
N	n		N	n	
	Runway	Others		Runway	Others
1-4	1	1	1-3	1	1
5-10	2	1	4-6	2	1
11-15	3	2	7-10	3	2
16-30	5	3	11-15	4	2
31-40	7	4	16-20	5	3
41-50	8	5	21-30	7	3
≥51	20% but ≤20	10% but ≤10	31-40	8	4
			41-50	10	5
			≥51	20% but ≤20	10% but ≤10

Where  $N$  = total number of sample units in section  
 $n$  = number of sample units to inspect

Prepared by BX

Checked by TH

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the section. In the case when nonrepresentative distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each section. PCI values range from 0 to 100. MicroPAVER provides a rating scale that relates PCI to pavement condition, with a PCI between 0 and 10 considered 'Failed' pavement and a PCI between 86 and 100 considered 'Good' pavement, with five other conditions for PCI values between 11 and 85. Figure 1-2 shows the PCI scale.

**Figure 1-2: PCI Rating Scale**



*Prepared by BX*

*Checked by TH*

## 1.5 Definitions

**Aviation Office** - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office worked closely with FDOT District Aviation Specialists, during development of this project. District Aviation Specialists will consult with airport owners in implementation of project recommendations.

**Base Course** - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

**Branch** – (Facility in prior system) - A runway, taxiway or apron is called a Branch. This is an easy reference to a recognizable component of airport pavement. In this report, Branch ID maintains the original AirPAV identification where 100 series through 3000 series facilities are taxiways, 4000 and 5000 series facilities are aprons (the 5000 series represent runup aprons and turnarounds), and 6000 series facilities are runways. It also includes the common designation for the item e.g. RW 18-36.

Category - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA – for general aviation or community airports
- RL – for regional relievers or small hubs
- PR – for primary

Critical PCI – The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

Distress Type - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland cement concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

Florida DOT (FDOT) - Florida Department of Transportation was represented in this project by the Office of Aviation.

Localized M&R (Maintenance and Repair) – Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

Global M&R- Global M&R is defined as activities applied to entire pavement sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

MicroPAVER – A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that if properly implemented, maintained and operated it meets the pavement management system requirements described by FAA in Advisory Circular 150/5380-7A.

Minimum Condition Level - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than General Aviation airports.

Major M&R (e.g. Rehabilitation) – Activities performed over the entire area of a pavement section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

Network Definition – (Airport Sketch in prior system) – A Network Definition is a CAD drawing which shows the airport pavement outline with Branch and Section boundaries. This sketch is intended to assist the user of the report to quickly associate information from the text to a location on the airport. This drawing also includes the PCI sample units and is used to identify

those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport in this report is in Appendix A along with a table of inventory data.

Pavement Condition Index (PCI) – The Pavement Condition Index is a number which represents the condition of a pavement segment at an instant in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340-04, “Standard Test Method for Airport Pavement Condition Index Surveys,” published by ASTM International.

Pavement Evaluation – A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

Pavement Management – Pavement management is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

Rank – Pavement rank in MicroPAVER determines the priority to be assigned to a pavement section when developing an M&R plan. Pavement sections are ranked as follows according to their use:

- P – for Primary pavements, such as primary runways, primary taxiways, and primary aprons
- S – or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons
- T – for Tertiary pavements such as “T” hangars and slightly used aprons

Reconstruction – Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new, or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

Rehabilitation – Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement, and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

Sample Unit – Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are  $5,000 \pm 2,000$  square feet for AC-surfaced pavements and  $20 \pm 8$  slabs for PCC-surfaced pavements.

Section – (Feature in prior system) - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

Section ID – A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series sections are taxiways, 4000 and 5000 series sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series sections are runways.

Use – In MicroPAVER use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

## 2. NETWORK DEFINITION

Marianna Municipal Airport (MAI) is owned and operated by the City of Marianna, Florida and is advised by an airport authority – the airport focuses primarily on serving general aviation aircraft. The runway configuration at Marianna Municipal Airport consists of two intersecting asphalt runways: Runway 18-36 and Runway 08-26. Taxiway access is available to all four runway thresholds and five taxiway connectors provide access to Runways 8, 18, and 36 directly from the apron. This airport is designated as a General Aviation (GA) airport and is located in District 3 of the Florida Department of Transportation.

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units. The airport pavement network is subdivided into separate branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then divided into sections with similar pavement construction and performance that may share other common attributes. Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage.

The network definition is used to identify changes in the network since the most recent update in 1998/1999 and also to plan the field inspection activities for 2006 survey. Prior to the field inspection process, the network definition drawing was updated. The purpose of this update is to compare the previous airport configuration and history with the current airport configuration and history and update the existing drawing showing network branch, section and sample unit designations to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important history record.

The updated network definition fields of Marianna Municipal Airport are provided in Table 2-1 and the updated network definition drawing of the airport is given in Appendix A. The field of **Rank** in Table 2-1 is defined in the definitions section in section 1.

**Table 2-1: Marianna Municipal Airport Network Definition**

Branch Name	Section ID	Rank
APRON	4105	P
RUNWAY 18L-36R	6205	P
RUNWAY 8R-26L	6105	S
WNW CONNECTOR TAXIWAY	505	P
NORTH CONNECTOR TAXIWAY	305	P
NW CONNECTOR TAXIWAY	405	P
SW CONNECTOR TAXIWAY	705	P
WEST CONNECTOR TAXIWAY	605	P
PARALLEL TAXIWAY TO RWS	105	P
	150	P

Prepared by VVD

Checked by TH

### 3. PAVEMENT INVENTORY

The detailed pavement inventory was updated to reflect the network definition update and field inspection results.

The total pavement area in 2006 at Marianna Municipal Airport is 3,126,719 square feet. The breakdown of pavement area for each pavement use is provided in Table 3-1.

**Table 3-1: Pavement Area by Pavement Use**


Use	Area, SqFt	% of Total Area
Runway	974,800	31
Taxiway	604,475	19
Apron	1,547,444	50
<b>Total</b>	<b>3,126,719</b>	<b>100</b>

*Prepared by VVD*

*Checked by TH*

Figure 3-1 presents the breakdown of the pavement area at Marianna Municipal Airport by surface type.

**Figure 3-1: Pavement Area by Surface Type**



*Prepared by VVD*

*Checked by TH*

Details of pavement section information including section dimensions, rank, surface type, last construction date and last inspection date are given in Appendix A.



#### 4. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340 “Standard Practice for Airport Pavement Condition Index Surveys.” These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

Pavement condition inspections at Marianna Municipal Airport were performed in October 2006. Data were recorded in the field using hand-held PDA (personal digital assistant) technology. The identifying information for each sample unit was pre-loaded into the PDA, and the survey results were entered directly, at the time of inspection. This simplified data handling and management.


During the inspections Global Positioning System (GPS) coordinates were recorded at the centroid of each sample unit. The centroid is usually the geometric center of the area but in cases where sample units are irregular in shape this is the center of mass. These data are presented in tables on updated Network Definition drawings available from the website.

After the completion of data collection, the data were imported into MicroPAVER and PCI values were calculated for the pavement sections.

Appendix B includes detailed distress data generated by MicroPAVER, Appendix C contains a table and a map of PCI results by section inspected in 2006, and Appendix D contains a table of PCI results by branch.

According to the 2006 survey, the overall area-weighted PCI at Marianna Municipal Airport is 42, representing a Poor overall network condition.

Figure 4-1 provides the PCI distribution by rating category for the network.



Approximately 20% of the network is in Good and Satisfactory condition while 79% of the network is in Poor to Very Poor condition. Table 4-1 illustrates the area-weighted PCI computed individually for each pavement use.

**Table 4-1: Condition by Pavement Use**

Use	Area-Weighted PCI
Runway	63
Taxiway	50
Apron	26
<b>All</b>	<b>42</b>

*Prepared by VVD*


*Checked by TH*

On average, the runways, taxiways, and aprons are in Fair, Poor, and Very Poor condition, respectively.


Figure 4-2 presents the breakdown of PCI by range for each pavement use.

**Figure 4-2: Percentage of Pavement Area within Each PCI Range by Pavement Use**


**(a) Runway**



### (b) Taxiway



### (c) Apron




Prepared by VVD

Checked by TH

## 5. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 5-1 illustrates the predicted performance of pavements at Marianna Municipal Airport based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum condition criteria for General Aviation (GA) airports.

**Figure 5-1: Predicted PCI by Pavement Use**



Prepared by VVD

Checked by TH

Appendix C presents the tabular summary of the predicted Section PCI for each year from 2008 to 2017.

## **6. MAINTENANCE POLICIES AND COSTS**

### **6.1 Policies**

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature, and are recommended to help achieve the performance goal.

Table 6-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. These repairs are used in an analysis only if there is an inspection within one year prior to the first year of the analysis period. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called “Critical PCI.” The critical PCI levels for different pavement and branch types established in Phase I of Statewide Pavement Management Program were reviewed and updated for development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 6-2 gives the critical PCI levels for General Aviation Airports.

**Table 6-1: Routine Maintenance Activities for Airfield Pavements**

Surface	Distress	Severity*	Work Type	Code	Work Unit
AC	Alligator Crack	M, H	Patching - AC Deep	PA-AD	SqFt
	Bleeding	N/A	No Localized M&R	NONE	SqFt
	Block Crack	M, H	Crack Sealing – AC	CS-AC	SqFt
	Corrugation	L, M, H	Patching - AC Deep	PA-AD	SqFt
	Depression	M, H	Patching - AC Deep	PA-AD	SqFt
	Jet Blast	N/A	Patching - AC Deep	PA-AD	SqFt
	Joint Ref. Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	L & T Crack	M, H	Crack Sealing – AC	CS-AC	Ft
	Oil Spillage	N/A	Patching - AC Shallow	PA-AS	SqFt
	Patching	M, H	Patching - AC Deep	PA-AD	SqFt
	Polished Agg.	N/A	No Localized M&R	NONE	SqFt
	Raveling	L	Surface Sealing - Rejuvenating	SS-RE	SqFt
		M	Surface Seal - Coal Tar	SS-CT	SqFt
		H	Microsurfacing	MI-AC	SqFt
	Rutting	M, H	Patching - AC Deep	PA-AD	SqFt
	Shoving	M, H	Grinding (Localized)	GR-LL	SqFt
	Slippage Crack	N/A	Patching - AC Shallow	PA-AS	SqFt
	Swelling	M, H	Patching - AC Deep	PA-AD	SqFt
PCC	Blow-Up	L, M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Corner Break	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Linear Crack	M, H	Crack Sealing – PCC	CS-PC	Ft
	Durability Crack	H	Slab Replacement – PCC	SL-PC	SqFt
		M	Patching - PCC Full Depth	PA-PF	SqFt
	Jt. Seal Damage	M, H	Joint Seal (Localized)	JS-LC	Ft
	Small Patch	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Large Patch	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Popouts	N/A	No Localized M&R	NONE	SqFt
	Pumping	N/A	No Localized M&R	NONE	SqFt
	Scaling	H	Slab Replacement – PCC	SL-PC	SqFt
	Faulting	M, H	Grinding (Localized)	GR-PP	Ft
	Shattered Slab	M, H	Slab Replacement – PCC	SL-PC	SqFt
	Shrinkage Crack	N/A	No Localized M&R	NONE	Ft
	Joint Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Corner Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt

\*L = Low, M = Medium, H = High

Prepared by BX

Checked by TH

**Table 6-2: Critical PCI for General Aviation Airports**

Use	Critical PCI
Runway	65
Taxiway	65
Apron	65

*Prepared by BX*

*Checked by TH*

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 6-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of General Aviation Airports.

**Table 6-3: Desired Minimum PCI for General Aviation Airports**

Minimum PCI		
Runway	Taxiway	Apron
75	65	60

*Prepared by BX*

*Checked by TH*

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 6-2 and our experience with pavement management systems, the PCI trigger range when the likely activity would be a mill and resurface was 31 to 55 and reconstruction at a PCI of 30 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation. With this objective, microsurfacing has been recommended to maintain pavements that have a PCI from 56 and 79. Microsurfacing is a surface treatment suggested for pavements in Fair to Satisfactory condition to extend the pavement life by five to seven years.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 6-4 summarizes the M&R activities for General Aviation Airports based on PCI value.

**Table 6-4: M&R Activities for General Aviation Airports**

	Activity	PCI Range
Maintenance	Crack Sealing and Full-Depth Patching	80 and 90
Rehabilitation	Microsurfacing (AC) or Concrete Pavement Restoration (PCC)	56 to 79
	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	31 to 55
	Reconstruction	30 and less

*Prepared by BX*

*Checked by TH*

## 6.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were reviewed in Phase I of Statewide Pavement Management Program in order to determine meaningful costs for the program. Table 6-5 presents the unit costs summary.

**Table 6-5: Maintenance Unit Costs for FDOT**

Code	Name	Cost	Unit
PA-AL	Patching – AC Leveling	\$2.00	SqFt
PA-AS	Patching – AC Shallow	\$4.00	SqFt
PA-PF	Patching – PCC Full Depth	\$50.00	SqFt
PA-PP	Patching – Partial Depth	\$35.00	SqFt
SL-PC	Slab Replacement	\$15.00	SqFt
CS-PC	Crack Sealing – PCC	\$2.00	Ft
UN-PC	Undersealing – PCC	\$3.00	Ft
CS-AC	Crack Sealing – AC	\$2.00	Ft
GR-PP	Grinding (Localized for PCC)	\$20.00	Ft
GR-LL	Grinding (Localized for AC)	\$6.00	SqFt
JS-LC	Joint Seal (Localized)	\$1.75	Ft
JS-SI	Joint Seal – Silicon	\$2.50	Ft
PA-AD	Patching – AC Deep	\$7.00	SqFt
OL-AT	Overlay – AC Thin	\$1.50	SqFt
SS-CT	Surface Seal – Coal Tar	\$0.20	SqFt
SS-RE	Surface Seal – Rejuvenating	\$0.15	SqFt
ST-SS	Surface Treatment – Slurry Seal	\$0.25	SqFt
ST-ST	Surface Treatment – Sand Tar	\$0.25	SqFt
MI-AC	Microsurfacing	\$0.90	SqFt

*Prepared by BX*

*Checked by TH*



The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection is recent and only in the first year of the M&R analysis. In subsequent years MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCI. That is, for low PCI it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly. Using available unit cost data the Major M&R Cost By Condition table was set up as shown in Table 6-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

**Table 6-6: M&R Activities and Unit Costs by Condition for General Aviation Airports**

	Activity	PCI Trigger	Cost/SqFt
Maintenance	Crack Sealing and Full-Depth Patching	90	\$0.06
		80	\$0.24
Rehabilitation	Microsurfacing (AC) or Concrete Pavement Restoration (PCC)	70	\$0.69
		60	\$3.42
	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	50	\$6.29
		40	\$6.29
	Reconstruction	30	\$13.62
		20	\$13.62

*Prepared by BX*

*Checked by TH*

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

## 7. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years, starting from 2008. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Table 7-1 presents the M&R needs list of immediate needs for Major M&R, i.e. Year 1 of the forecast. The importance of this listing is that it points out the major activities triggered by the current condition of the pavements.

The 10 year forecast results are shown in Figure 7-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.

**Table 7-1: Summary of Immediate Major M&R Needs**

Branch	Section	Section Area, SqFt	Major M&R Funded**	PCI Before	Maintenance	PCI After
AP	4105	1,547,444	\$21,076,194	25	Major M&R < Critical	100
RW 8R-26L	6105	490,000	\$2,941,470	51	Major M&R < Critical	100
TW CONN N	305	20,000	\$125,800	47	Major M&R < Critical	100
TW PARALL	105	96,000	\$603,840	40	Major M&R < Critical	100
TW PARALL	150	324,375	\$3,229,154	35	Major M&R < Critical	100
		<b>Total</b>	<b>\$27,976,458</b>	<b>42*</b>	<b>← Network Avg. PCI →</b>	<b>94*</b>


\* This table shows the area-weighted PCI before and after Major M&R and routine maintenance work for the first year of the 10-year plan. It includes all pavement sections at Marianna Municipal Airport, including those sections not shown in this table.

\*\* Cost figures are rounded down. Sum may be different. Costs are adjusted for inflation.

*Prepared by VVD*

*Checked by TH*

**Figure 7-1: Budget Scenario Analysis**



*Prepared by VVD*

*Checked by TH*

The following network level observations can be made from the figure above:

- The PCI will deteriorate from 42 in 2006 to 28 in 2017 if no M&R activities are performed.
- The PCI will remain at or above 88 through the 10-year analysis period under the unlimited budget scenario. A 2017 PCI of 88 with this scenario is 60 PCI points higher than a “No M&R” scenario. The total cost for Major M&R over this 10-year period is about \$30 million.

## 8. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCI less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 8-1 provides the summary results under the critical PCI scenario.

**Table 8-1: M&R Costs under Unlimited Funding Scenario**

Year	Preventive	Major M&R ≥ Critical	Major M&R < Critical	Total
2008	\$21,351	\$0	\$27,976,458	\$27,997,809
2009	\$139,553	\$0	\$0	\$139,553
2010	\$21,285	\$0	\$1,273,231	\$1,294,517
2011	\$19,423	\$0	\$69,956	\$89,379
2012	\$25,226	\$0	\$0	\$25,226
2013	\$34,412	\$0	\$0	\$34,412
2014	\$43,451	\$0	\$0	\$43,451
2015	\$63,014	\$0	\$0	\$63,014
2016	\$101,616	\$0	\$0	\$101,616
2017	\$130,689	\$0	\$0	\$130,689
<b>Total</b>	<b>\$600,019</b>	<b>\$0</b>	<b>\$29,319,646</b>	<b>\$29,919,666</b>

Note: Cost figures are rounded down. Sum may be different. Costs are adjusted for inflation.

Prepared by VVD

Checked by TH

Approximately 95% of the total Major M&R cost is required in the first year (2008). This is a consequence of Runway 8R-26L and Apron and some connector taxiways (North Connector Taxiway and Parallel Taxiway to Runways) being below Critical PCI.

According to the 2006 inspections, Runway 8R-26L is in Poor condition with an average PCI value of 53. Part of this runway has immediate need for repair. In addition, Apron and several connector taxiways (North Connector Taxiway and Parallel Taxiway to Runways) need further evaluation to identify capital project(s) that may be funded separately. The unlimited budget scenario provides the basis for estimating the total repair cost. In reality, it is neither operationally nor fiscally prudent.

Appendix E provides details of M&R plan by year under the unlimited funding scenario and the map of the 10-year M&R plan was provided in Appendix F. It is important to understand that a PMS is a network level tool and the M&R costs provided in this report are only for planning purposes.

## **9. VISUAL AIDS**

### **9.1 GIS Linked Shape File**

The pavement inventory data and pavement condition were linked to the airport's shape file to graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

Selected digital photographs taken during the pavement inspection were provided in an Appendix G to provide visual support to special pavement conditions or distress observed during the inspection of the facility.

## **10. RECOMMENDATIONS**


Pavement condition inspections were performed at Marianna Municipal Airport and a 10-year M&R plan was developed based on the unlimited funding scenario.

The following recommendations were made based on 2006 condition inspections and M&R analysis results:

- Runway 5-23 is in Poor condition and some immediate repair is needed.
- Runway 18L-36R is in Satisfactory condition. This runway would have repair need in 2010.
- Large areas of the apron and taxiway (Apron and Parallel Taxiway to Runways) were identified that will require significant funding to improve them above Minimum PCI levels. Further evaluation of these features is necessary in order to develop repair plans and timing for future budgets. These needs can not be addressed with typical annual expenditures as they amount to several million dollars.

**APPENDIX A**

**NETWORK DEFINITION MAP  
AND  
PAVEMENT INVENTORY TABLE**



GPS COORDINATES - MARIANNA MUNICIPAL AIRPORT											
Location	Section	Sample	Latitude	Longitude	Location	Section	Sample	Latitude	Longitude		
TW PARALL	105	101	30.84194439	-85.17036555	RW 8/26	6105	301	30.84245548	-85.1706133		
TW PARALL	105	105	30.84099865	-85.17092583	RW 8/26	6105	308	30.84233692	-85.17169396		
TW PARALL	105	107	30.84090066	-85.17154454	RW 8/26	6105	315	30.84221378	-85.17279624		
TW PARALL	105	115	30.84059123	-85.17403355	RW 8/26	6105	322	30.84208247	-85.17390691		
TW PARALL	105	122	30.84032311	-85.17624089	RW 8/22	6105	329	30.8419343	-85.17499895		
TW PARALL	150	125	30.84018336	-85.17749733	RW 8/26	6105	335	30.84179827	-85.17594645		
TW PARALL	150	132	30.83931126	-85.17991459	RW 8/26	6105	343	30.84167203	-85.17720008		
TW PARALL	150	140	30.83722828	-85.18212242	RW 8/26	6105	349	30.84154405	-85.17812323		
TW PARALL	150	149	30.83466001	-85.18397949	RW 8/26	6105	353	30.84147356	-85.17874167		
TW PARALL	150	158	30.83155891	-85.18399288	RW 8/26	6105	357	30.84140215	-85.17937874		
TW CONN N	305	100	30.84106117	-85.17974886	RW 8/26	6105	359	30.84137079	-85.17965952		
TW CONN N	305	104	30.84011872	-85.17915799	RW 8/26	6105	363	30.84130651	-85.18032064		
TW CONN NW	405	104	30.83973725	-85.18446675	RW 8/26	6105	371	30.84114949	-85.18155878		
TW CONN NW	405	109	30.83880481	-85.18331189	RW 8/26	6105	378	30.84099515	-85.18264165		
TW CONN NW	405	114	30.83778443	-85.18224657	RW 8/26	6105	385	30.84086773	-85.18372909		
TW CONN WNW	505	102	30.83580744	-85.1847547	RW 8/26	6105	388	30.84081363	-85.18419903		
TW CONN WNW	505	104	30.83563648	-85.1841618	RW 8/26	6105	392	30.84073908	-85.18483702		
TW CONN WNW	505	105	30.83555079	-85.18393806	RW 8/26	6105	395	30.84068386	-85.18531872		
TW CONN W	605	100	30.83268375	-85.18532777	RW 8/26	6105	397	30.84063172	-85.18576807		
TW CONN W	605	103	30.83268906	-85.18440428	RW 26 CENTER	-	-	30.84248364	-85.17037284		
TW CONN SW	705	100	30.82870728	-85.1853807	RW 26 LEFT	-	-	30.84234853	-85.1703567		
TW CONN SW	705	104	30.82906559	-85.18414918	RW 26 RIGHT	-	-	30.84261246	-85.17041211		
TW CONN SW	705	105	30.82912705	-85.18393556	RW 18 CENTER	-	-	30.84053066	-85.18566989		
AP	4105	117	30.83687583	-85.18226743	RW 18 LEFT	-	-	30.84052328	-85.18550243		
AP	4105	124	30.83503201	-85.18382592	RW 18 RIGHT	-	-	30.84048465	-85.18582846		
AP	4105	204	30.83977619	-85.1786345	RW 18/36	6205	100	30.82738573	-85.18566163		
AP	4105	213	30.83780434	-85.18015686	RW 18/36	6205	107	30.82832372	-85.18565941		
AP	4105	228	30.83635455	-85.18367709	RW 18/36	6205	110	30.82877408	-85.18565311		
AP	4105	235	30.83127453	-85.18366827	RW 18/36	6205	114	30.82931159	-85.1856591		
AP	4105	238	30.830247	-85.18368904	RW 18/36	6205	121	30.83028934	-85.18566938		
AP	4105	242	30.8293233	-85.18351784	RW 18/36	6205	128	30.83124245	-85.18566193		
AP	301	305	30.8275455	-85.1774455	RW 18/36	6205	135	30.83219839	-85.18569378		
AP	4105	308	30.8301463	-85.17958122	RW 18/36	6205	139	30.83237302	-85.18566206		
AP	4105	321	30.83569091	-85.18304624	RW 18/36	6205	142	30.8331589	-85.18564462		
AP	4105	430	30.83296105	-85.18336449	RW 18/36	6205	149	30.83412286	-85.18564448		
AP	4105	506	30.83921503	-85.17905599	RW 18/36	6205	156	30.83508123	-85.18566381		
AP	4105	511	30.83805856	-85.18019942	RW 18/36	6205	163	30.83604296	-85.18567489		
AP	4105	518	30.83624819	-85.18203051	RW 18/36	6205	165	30.83361634	-85.18565856		
AP	4105	536	30.83049911	-85.18319477	RW 18/36	6205	170	30.83699738	-85.18566486		
AP	4105	632	30.83225707	-85.18303031	RW 18/36	6205	177	30.8379613	-85.18566526		
AP	4105	709	30.83837167	-85.17944882	RW 18/36	6205	184	30.83891168	-85.18566569		
AP	4105	715	30.8368286	-85.18100047	RW 18/36	6205	189	30.83959844	-85.18565243		
AP	4105	731	30.83258974	-85.18268383	RW 18/36	6205	194	30.84029748	-85.18565735		
RW 8 LEFT	-	-	30.84060362	-85.18582624	RW 18/36	6205	195	30.84042187	-85.18567674		
RW 8 CENTER	-	-	30.84076949	-85.1858429	RW 36 CENTER	-	-	30.82730123	-85.1856527		
RW 8 RIGHT	-	-	30.84048671	-85.18584483	RW 36 LEFT	-	-	30.82728451	-85.18580751		
RW 8/26	6105	300	30.84249709	-85.17044484	RW 36 RIGHT	-	-	30.82730791	-85.18549368		
Notes: Geodetics represent decimal degrees (GS - 84 Datum)											
All GPS coordinates are at the centroid of the sample units.											

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR  
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT  
MATCH PUBLISHED RUNWAY LENGTHS.





**Table A-1: Pavement Inventory**

Network Name	Network ID	Branch Name	Branch ID	Section ID	Length, Ft	Width, Ft	Area, SqFt	Rank	Surface	Last Const. Date	Last Insp. Date
MARIANNA MUNICIPAL AIRPORT	MAI	APRON	AP	4105	4,371	350	1,547,444	P	PCC	1/1/1945	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	RUNWAY 18L-36R	RW 18L-36R	6205	4,848	100	484,800	P	AAC	1/1/1992	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	RUNWAY 8R-26L	RW 8R-26L	6105	4,900	100	490,000	S	AC	1/1/1945	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	WNW CONNECTOR TAXIWAY	TW CON WNW	505	550	50	27,500	P	AAC	1/1/1992	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	NORTH CONNECTOR TAXIWAY	TW CONN N	305	500	40	20,000	P	AC	1/1/1945	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	NW CONNECTOR TAXIWAY	TW CONN NW	405	1,688	50	84,400	P	AAC	1/1/1992	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	SW CONNECTOR TAXIWAY	TW CONN SW	705	550	50	27,500	P	AAC	1/1/1992	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	WEST CONNECTOR TAXIWAY	TW CONN W	605	494	50	24,700	P	AAC	1/1/1992	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	PARALLEL TAXIWAY TO RWS	TW PARALL	105	1,920	50	96,000	P	AC	1/1/1945	10/3/2006
MARIANNA MUNICIPAL AIRPORT	MAI	PARALLEL TAXIWAY TO RWS	TW PARALL	150	6,488	50	324,375	P	PCC	1/1/1945	10/3/2006

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

**APPENDIX B**

**PCI RE-INSPECTION REPORT**

# Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: AP Name: APRON Use: APRON Area: 1,547,444.00 SqFt

Section: 4105 of 1 From: - To: - Last Const.: 1/1/1945  
Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: P  
Area: 1,547,444.00 SqFt Length: 4,371.00 Ft Width: 350.00 Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0  
Section Comments:

Last Insp. 10/3/2006 Total Samples: 321 Surveyed: 20  
Date:  
Conditions: PCI:26.00 |  
Inspection Comments:

Sample Number: 117 Type: R Area: 20.00 Count PCI = 36  
Sample Comments:  
63 L 63 M 63 H 65 L

Sample Number: 124 Type: R Area: 20.00 Count PCI = 6  
Sample Comments:  
63 M 63 H 66 L 75 H 71 M 71 H 65 M

Sample Number: 204 Type: R Area: 20.00 Count PCI = 16  
Sample Comments:  
63 M 63 H 65 H

Sample Number: 213 Type: R Area: 20.00 Count PCI = 28  
Sample Comments:  
63 L 63 M 63 H 75 H 65 M

Sample Number: 228 Type: R Area: 20.00 Count PCI = 35  
Sample Comments:  
63 L 63 H 68 N 72 H 72 M 65 L

Sample Number: 235 Type: R Area: 20.00 Count PCI = 25  
Sample Comments:  
63 M 63 H 68 N 65 M 63 L

Sample Number: 238 Type: R Area: 20.00 Count PCI = 33  
Sample Comments:  
63 L 63 M 63 H 65 M

Sample Number: 242 Type: R Area: 20.00 Count PCI = 60  
Sample Comments:  
63 L 63 M 72 L 68 N 65 M

Sample Number: 301 Type: R Area: 20.00 Count PCI = 27  
Sample Comments:  
63 L 63 M 63 H 73 N 65 H

Sample Number: 308 Type: R Area: 20.00 Count PCI = 61  
Sample Comments:  
63 L 63 H 66 L

Sample Number: 321 Type: R Area: 16.00 Count PCI = 5  
Sample Comments:  
63 L 63 M 63 H 67 L 67 M 67 H 74 H 75 M 75 H 65 L

## Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Sample Number:	430	Type:	R	Area:	20.00	Count	PCI = 16
Sample Comments:	63 L 63 M 63 H 68 N 74 H 74 M 64 L 72 M 65 M						
Sample Number:	506	Type:	R	Area:	20.00	Count	PCI = 14
Sample Comments:	63 L 63 M 63 H 65 H						
Sample Number:	511	Type:	R	Area:	20.00	Count	PCI = 16
Sample Comments:	63 L 63 M 63 H 68 N 74 H 65 M						
Sample Number:	518	Type:	R	Area:	20.00	Count	PCI = 33
Sample Comments:	63 H 74 H 65 L 63 L						
Sample Number:	536	Type:	R	Area:	20.00	Count	PCI = 13
Sample Comments:	63 L 63 M 63 H 72 M 72 H 68 N 65 M						
Sample Number:	632	Type:	R	Area:	20.00	Count	PCI = 26
Sample Comments:	63 L 63 M 63 H 68 N 65 M						
Sample Number:	709	Type:	R	Area:	20.00	Count	PCI = 12
Sample Comments:	63 L 63 M 63 H 72 M 68 N 75 M 65 M						
Sample Number:	715	Type:	R	Area:	20.00	Count	PCI = 22
Sample Comments:	63 L 63 M 63 H 67 L 75 L 65 M						
Sample Number:	731	Type:	R	Area:	20.00	Count	PCI = 28
Sample Comments:	63 L 63 M 63 H 68 N 72 L 72 M 62 H 74 H 74 M 65 M						

# Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: RW 18L-36R Name: RUNWAY 18L-36R Use: RUNWAY Area: 484,800.00 SqFt

Section: 6205 of 1 From: - To: - Last Const.: 1/1/1992

Surface: AAC Family: FDOT-GA-RW-AAC Zone: Category: Rank: P

Area: 484,800.00 SqFt Length: 4,848.00 Ft Width: 100.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 133 Surveyed: 19

Date:

Conditions: PCI:73.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 5,000.00 SqFt PCI = 78

Sample Comments:  
48 L 48 M 52 L

Sample Number: 107 Type: R Area: 5,000.00 SqFt PCI = 86

Sample Comments:  
48 L 52 L

Sample Number: 110 Type: R Area: 5,000.00 SqFt PCI = 86

Sample Comments:  
48 L 52 L

Sample Number: 114 Type: R Area: 5,000.00 SqFt PCI = 80

Sample Comments:  
48 L 52 L

Sample Number: 121 Type: R Area: 5,000.00 SqFt PCI = 77

Sample Comments:  
48 L 52 M 52 L

Sample Number: 128 Type: R Area: 5,000.00 SqFt PCI = 79

Sample Comments:  
48 L 48 M 52 L

Sample Number: 135 Type: R Area: 5,000.00 SqFt PCI = 75

Sample Comments:  
48 L 52 L

Sample Number: 139 Type: R Area: 5,000.00 SqFt PCI = 76

Sample Comments:  
48 L 52 L

Sample Number: 142 Type: R Area: 5,000.00 SqFt PCI = 79

Sample Comments:  
48 L 52 L

Sample Number: 149 Type: R Area: 5,000.00 SqFt PCI = 79

Sample Comments:  
48 L 52 L

## Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Sample Number: 156      Type: R      Area: 5,000.00      SqFt      PCI = 80  
Sample Comments:  
48 L    52 L

Sample Number: 163      Type: R      Area: 5,000.00      SqFt      PCI = 83  
Sample Comments:  
48 L    52 L

Sample Number: 165      Type: R      Area: 5,000.00      SqFt      PCI = 72  
Sample Comments:  
48 M    48 L    52 L

Sample Number: 170      Type: R      Area: 5,000.00      SqFt      PCI = 73  
Sample Comments:  
48 L    52 M    52 L

Sample Number: 177      Type: R      Area: 5,000.00      SqFt      PCI = 64  
Sample Comments:  
48 L    42 N    52 M    52 L

Sample Number: 184      Type: R      Area: 5,000.00      SqFt      PCI = 48  
Sample Comments:  
52 M    52 L    48 L

Sample Number: 189      Type: R      Area: 5,000.00      SqFt      PCI = 56  
Sample Comments:  
48 L    52 M    52 L

Sample Number: 194      Type: R      Area: 5,000.00      SqFt      PCI = 60  
Sample Comments:  
43 L    48 L    52 L    52 M

Sample Number: 195      Type: R      Area: 5,000.00      SqFt      PCI = 64  
Sample Comments:  
48 L    52 M    52 L

# Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: RW 8R-26L Name: RUNWAY 8R-26L Use: RUNWAY Area: 490,000.00 SqFt

Section: 6105 of 1 From: - To: - Last Const.: 1/1/1945

Surface: AC Family: FDOT-GA-RW-AC Zone: Category: Rank: S  
Area: 490,000.00 SqFt Length: 4,900.00 Ft Width: 100.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 122 Surveyed: 20

Date:

Conditions: PCI:53.00 |

Inspection Comments:

Sample Number: 300 Type: R Area: 5,000.00 SqFt PCI = 30

Sample Comments:  
43 M 42 N 43 L 56 L

Sample Number: 301 Type: R Area: 5,000.00 SqFt PCI = 56

Sample Comments:  
43 M 43 L 45 L

Sample Number: 308 Type: R Area: 5,000.00 SqFt PCI = 55

Sample Comments:  
43 L 43 M 56 L

Sample Number: 315 Type: R Area: 5,000.00 SqFt PCI = 59

Sample Comments:  
43 L 56 L

Sample Number: 322 Type: R Area: 5,000.00 SqFt PCI = 55

Sample Comments:  
42 N 43 L 56 L

Sample Number: 329 Type: R Area: 5,000.00 SqFt PCI = 54

Sample Comments:  
43 L 56 L 52 L

Sample Number: 335 Type: R Area: 5,000.00 SqFt PCI = 49

Sample Comments:  
52 H 43 L 56 L 52 L

Sample Number: 343 Type: R Area: 5,000.00 SqFt PCI = 54

Sample Comments:  
43 L 56 L 52 L

Sample Number: 349 Type: R Area: 5,000.00 SqFt PCI = 54

Sample Comments:  
43 L 56 L 52 L

Sample Number: 353 Type: R Area: 5,000.00 SqFt PCI = 54

Sample Comments:  
43 L 56 L 52 L

## Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Sample Number: 357 Sample Comments: 43 L 56 L 52 L	Type: R	Area: 5,000.00	SqFt	PCI = 54
Sample Number: 359 Sample Comments: 43 L 52 L 56 L	Type: R	Area: 5,000.00	SqFt	PCI = 54
Sample Number: 363 Sample Comments: 43 L 56 L 52 L	Type: R	Area: 5,000.00	SqFt	PCI = 54
Sample Number: 371 Sample Comments: 43 L 52 L 56 L	Type: R	Area: 5,000.00	SqFt	PCI = 54
Sample Number: 378 Sample Comments: 43 L 56 L 52 M 52 L	Type: R	Area: 5,000.00	SqFt	PCI = 50
Sample Number: 385 Sample Comments: 43 L 56 L 52 L	Type: R	Area: 5,000.00	SqFt	PCI = 54
Sample Number: 388 Sample Comments: 43 L 52 H 56 L 52 L	Type: R	Area: 5,000.00	SqFt	PCI = 49
Sample Number: 392 Sample Comments: 43 L 56 L 52 L	Type: R	Area: 5,000.00	SqFt	PCI = 56
Sample Number: 395 Sample Comments: 43 L 52 L 56 L	Type: R	Area: 5,000.00	SqFt	PCI = 54
Sample Number: 397 Sample Comments: 43 L 43 M 48 L 42 N 52 L	Type: R	Area: 5,000.00	SqFt	PCI = 51



## Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: TW CON WNW Name: WNW CONNECTOR TAXIWAY Use: TAXIWAY Area: 27,500.00 SqFt

Section: 505 of 1 From: - To: - Last Const.: 1/1/1992

Surface: AAC Family: FDOT-GA-TW-AAC Zone: Category: Rank: P

Area: 27,500.00 SqFt Length: 550.00 Ft Width: 50.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 7 Surveyed: 3

Date:

Conditions: PCI:70.00 |

Inspection Comments:

Sample Number: 102 Type: R Area: 5,000.00 SqFt PCI = 70

Sample Comments:

43 L 43 L 48 L

Sample Number: 104 Type: R Area: 5,000.00 SqFt PCI = 70

Sample Comments:

48 L 43 L 43 L

Sample Number: 105 Type: R Area: 2,087.00 SqFt PCI = 68

Sample Comments:

50 L 48 L 54 L

## Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: TW CONN N Name: NORTH CONNECTOR TAXIWAY Use: TAXIWAY Area: 20,000.00 SqFt

Section: 305 of 1 From: - To: - Last Const.: 1/1/1945

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P

Area: 20,000.00 SqFt Length: 500.00 Ft Width: 40.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 5 Surveyed: 2

Date:

Conditions: PCI:50.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 5,631.00 SqFt PCI = 40

Sample Comments:

43 L 43 M 56 L

Sample Number: 104 Type: R Area: 4,000.00 SqFt PCI = 64

Sample Comments:

43 L

## Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: TW CONN NW Name: NW CONNECTOR TAXIWAY Use: TAXIWAY Area: 84,400.00 SqFt

Section: 405 of 1 From: - To: - Last Const.: 1/1/1992

Surface: AAC Family: FDOT-GA-TW-AAC Zone: Category: Rank: P

Area: 84,400.00 SqFt Length: 1,688.00 Ft Width: 50.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 21 Surveyed: 3

Date:

Conditions: PCI:88.00 |

Inspection Comments:

Sample Number: 104 Type: R Area: 5,000.00 SqFt PCI = 91

Sample Comments:

48 L

Sample Number: 109 Type: R Area: 5,000.00 SqFt PCI = 89

Sample Comments:

48 L

Sample Number: 114 Type: R Area: 5,000.00 SqFt PCI = 82

Sample Comments:

48 L

# Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: TW CONN SW Name: SW CONNECTOR TAXIWAY Use: TAXIWAY Area: 27,500.00 SqFt

Section: 705 of 1 From: - To: - Last Const.: 1/1/1992

Surface: AAC Family: FDOT-GA-TW-AAC Zone: Category: Rank: P

Area: 27,500.00 SqFt Length: 550.00 Ft Width: 50.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 7 Surveyed: 3

Date:

Conditions: PCI:73.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 5,464.00 SqFt PCI = 70

Sample Comments:

43 L 45 L 48 M 48 L

Sample Number: 104 Type: R Area: 5,000.00 SqFt PCI = 82

Sample Comments:

48 M 48 L

Sample Number: 105 Type: R Area: 2,022.00 SqFt PCI = 60

Sample Comments:

43 L 56 L 48 L 52 H 42 N

## Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: TW CONN W Name: WEST CONNECTOR TAXIWAY Use: TAXIWAY Area: 24,700.00 SqFt

Section: 605 of 1 From: - To: - Last Const.: 1/1/1992

Surface: AAC Family: FDOT-GA-TW-AAC Zone: Category: Rank: P

Area: 24,700.00 SqFt Length: 494.00 Ft Width: 50.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 6 Surveyed: 2

Date:

Conditions: PCI:86.00 |

Inspection Comments:

Sample Number: 100 Type: R Area: 5,140.00 SqFt PCI = 83

Sample Comments:

48 L

Sample Number: 103 Type: R Area: 5,000.00 SqFt PCI = 88

Sample Comments:

48 L

# Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY TO RWS Use: TAXIWAY Area: 420,375.00 SqFt

Section: 105 of 2 From: - To: - Last Const.: 1/1/1945

Surface: AC Family: FDOT-GA-TW-AC Zone: Category: Rank: P

Area: 96,000.00 SqFt Length: 1,920.00 Ft Width: 50.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 24 Surveyed: 5

Date:

Conditions: PCI:43.00 |

Inspection Comments:

Sample Number: 101 Type: R Area: 4,000.00 SqFt PCI = 39

Sample Comments:  
43 M 43 L 52 L

Sample Number: 105 Type: R Area: 4,000.00 SqFt PCI = 35

Sample Comments:  
50 H 43 M 52 L

Sample Number: 107 Type: R Area: 4,000.00 SqFt PCI = 40

Sample Comments:  
43 L 43 M 52 L

Sample Number: 115 Type: R Area: 4,000.00 SqFt PCI = 59

Sample Comments:  
52 L 43 L

Sample Number: 122 Type: R Area: 4,000.00 SqFt PCI = 42

Sample Comments:  
43 M 52 L

# Re-inspection Report

FDOT

Report Generated Date: 3/26/2008

Site Name:

Network: MAI Name: MARIANNA MUNICIPAL AIRPORT

Branch: TW PARALL Name: PARALLEL TAXIWAY TO RWS Use: TAXIWAY Area: 420,375.00 SqFt

Section: 150 of 2 From: - To: - Last Const.: 1/1/1945

Surface: PCC Family: FDOT-GA-PCC Zone: Category: Rank: P

Area: 324,375.00 SqFt Length: 6,487.50 Ft Width: 50.00 Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. 10/3/2006 Total Samples: 52 Surveyed: 6

Date:

Conditions: PCI:36.00 |

Inspection Comments:

Sample Number: 125 Type: R Area: 20.00 Count PCI = 0

Sample Comments:

63 M 63 H 63 L 74 M 73 N 66 L 71 L 63 M

Sample Number: 132 Type: R Area: 20.00 Count PCI = 37

Sample Comments:

63 L 63 M 63 H 65 H

Sample Number: 140 Type: R Area: 20.00 Count PCI = 42

Sample Comments:

63 L 63 H 62 M 66 L 65 L 63 M

Sample Number: 149 Type: R Area: 20.00 Count PCI = 63

Sample Comments:

63 L 63 M 75 L 65 L

Sample Number: 157 Type: R Area: 20.00 Count PCI = 41

Sample Comments:

65 H 63 M 63 M

Sample Number: 158 Type: R Area: 20.00 Count PCI = 32


Sample Comments:

63 L 63 M 63 H 74 M 65 L

## **APPENDIX C**

### **2006 CONDITION MAP AND TABLES**





RUNWAY 18-36 4,896' x 100'

RW 18L-36F

SW CONN SW

ABANDONED

THE CONN.

ABANDONED

TW CONN NW

AP

TW CONN N

4,895' x 100  
BONWAY 8-26

LEGEND

RW 13-31 ← TYPICAL RUNWAY BRANCH ID

TW A ← TYPICAL TAXIWAY BRANCH ID

AP S ← TYPICAL APRON BRANCH ID

Good

Satisfactory


Fair

Poor

Very Poor

Serious

Failed



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS					
1	Mar-19	Draft Report					
0	Feb-06	Initial Submittal					
DESIGNED:	FL	DRAWN:	GB	CHECKED:		DATE:	9-06-2007



2006 Condition Map

**MARIANNA MUNICIPAL AIRPORT**  
**JACKSON COUNTY, FLORIDA**

FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER	
<b>MA</b>	
FOOT DISTRICT	
3	

**Table C-1: Pavement Condition Index**

Network Name	Network ID	Branch Name	Branch ID	Section ID	Length, Ft	Width, Ft	Area, SqFt	Rank	Surface	Last Const. Date	Last Insp. Date	2006 PCI
MARIANNA MUNICIPAL AIRPORT	MAI	APRON	AP	4105	4,371	350	1,547,444	P	PCC	1/1/1945	10/3/2006	26
MARIANNA MUNICIPAL AIRPORT	MAI	RUNWAY 18L-36R	RW 18L-36R	6205	4,848	100	484,800	P	AAC	1/1/1992	10/3/2006	73
MARIANNA MUNICIPAL AIRPORT	MAI	RUNWAY 8R-26L	RW 8R-26L	6105	4,900	100	490,000	S	AC	1/1/1945	10/3/2006	53
MARIANNA MUNICIPAL AIRPORT	MAI	WNW CONNECTOR TAXIWAY	TW CON WNW	505	550	50	27,500	P	AAC	1/1/1992	10/3/2006	70
MARIANNA MUNICIPAL AIRPORT	MAI	NORTH CONNECTOR TAXIWAY	TW CONN N	305	500	40	20,000	P	AC	1/1/1945	10/3/2006	50
MARIANNA MUNICIPAL AIRPORT	MAI	NW CONNECTOR TAXIWAY	TW CONN NW	405	1,688	50	84,400	P	AAC	1/1/1992	10/3/2006	88
MARIANNA MUNICIPAL AIRPORT	MAI	SW CONNECTOR TAXIWAY	TW CONN SW	705	550	50	27,500	P	AAC	1/1/1992	10/3/2006	73
MARIANNA MUNICIPAL AIRPORT	MAI	WEST CONNECTOR TAXIWAY	TW CONN W	605	494	50	24,700	P	AAC	1/1/1992	10/3/2006	86
MARIANNA MUNICIPAL AIRPORT	MAI	PARALLEL TAXIWAY TO RWS	TW PARALL	105	1,920	50	96,000	P	AC	1/1/1945	10/3/2006	43
MARIANNA MUNICIPAL AIRPORT	MAI	PARALLEL TAXIWAY TO RWS	TW PARALL	150	6,488	50	324,375	P	PCC	1/1/1945	10/3/2006	36

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

**Table C-2: Pavement Condition Prediction**

Network ID	Branch ID	Section ID	2006 PCI	PCI Forecast									
				2008	2009	2010	2011	2012	2013	2014	2015	2016	2017
MAI	AP	4105	26	24	23	23	22	21	20	19	18	17	16
MAI	RW 18L-36R	6205	73	68	66	63	61	58	56	53	51	48	46
MAI	RW 8R-26L	6105	53	50	49	47	46	44	43	41	40	38	37
MAI	TW CON WNW	505	70	66	64	62	60	58	57	55	53	51	49
MAI	TW CONN N	305	50	46	45	42	40	38	37	35	33	31	29
MAI	TW CONN NW	405	88	84	82	80	78	76	75	73	71	69	67
MAI	TW CONN SW	705	73	69	67	65	63	61	60	58	56	54	52
MAI	TW CONN W	605	86	82	80	78	76	74	73	71	69	67	65
MAI	TW PARALL	105	43	39	37	35	33	31	29	27	25	23	21
MAI	TW PARALL	150	36	34	33	33	32	31	30	29	28	27	26

Note: If new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

**APPENDIX D**

**AREA-WEIGHTED PCI RESULTS  
BY BRANCH**

**Table D-1 Condition Summary by Branch**

<b>Network</b>	<b>Branch Name</b>	<b>2006 PCI</b>
MARIANNA MUNICIPAL AIRPORT	APRON	26
MARIANNA MUNICIPAL AIRPORT	RUNWAY 18L-36R	73
MARIANNA MUNICIPAL AIRPORT	RUNWAY 8R-26L	53
MARIANNA MUNICIPAL AIRPORT	WNW CONNECTOR TAXIWAY	70
MARIANNA MUNICIPAL AIRPORT	NORTH CONNECTOR TAXIWAY	50
MARIANNA MUNICIPAL AIRPORT	NW CONNECTOR TAXIWAY	88
MARIANNA MUNICIPAL AIRPORT	SW CONNECTOR TAXIWAY	73
MARIANNA MUNICIPAL AIRPORT	WEST CONNECTOR TAXIWAY	86
MARIANNA MUNICIPAL AIRPORT	PARALLEL TAXIWAY TO RWS	38

**APPENDIX E**

**MAJOR M&R PLAN BY YEAR**


**Table E-1: Major M&R Plan by Year**

Network	Branch Use	Branch ID	Section ID	Surface	Area, SqFt	Year	PCI Before Maint.	Activities	PCI After Maint.	Cost
MAI	APRON	AP	4105	PCC	1,547,444	2008	25	Reconstruction	100	\$21,076,194
MAI	RUNWAY	RW 8R-26L	6105	AC	490,000	2008	51	Mill & Overlay	100	\$2,941,470
MAI	TAXIWAY	TW CONN N	305	AC	20,000	2008	47	Mill & Overlay	100	\$125,800
MAI	TAXIWAY	TW PARALL	105	AC	96,000	2008	40	Mill & Overlay	100	\$603,840
MAI	TAXIWAY	TW PARALL	150	PCC	324,375	2008	35	PCC Restoration	100	\$3,229,154
MAI	RUNWAY	RW 18L-36R	6205	AAC	484,800	2010	64	Microsurfacing	100	\$1,197,348
MAI	TAXIWAY	TW CON WNW	505	AAC	27,500	2010	63	Microsurfacing	100	\$75,884
MAI	TAXIWAY	TW CONN SW	705	AAC	27,500	2011	64	Microsurfacing	100	\$69,956

**APPENDIX F**

**10-YEAR M&R MAP**





LEGEND

RW 13-31 ← TYPICAL RUNWAY BRANCH ID





**TW A** ← TYPICAL TAXIWAY BRANCH ID

AP S ← TYPICAL APRON BRANCH ID

Year

### Activity



2008		Microsurfacing
2009		
2010		Mill & Overlay
2011		
2012		Reconstruction
2013		
2014		Concrete Pavement Restoration
2015		
2016		
2017		

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR  
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT  
MATCH PUBLISHED RUNWAY LENGTHS.

NUMBER	DATE	REVISIONS					
1	Mar-19	Draft Report					
0	Feb-06	Initial Submittal					
DESIGNED:	FL	DRAWN:	GB	CHECKED:		DATE:	9-05-2007



10-Year M&R Map

**MARIANNA MUNICIPAL AIRPORT**  
**JACKSON COUNTY, FLORIDA**

FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

IDENTIFIER	MA
FDOT DISTRICT	3

**APPENDIX G**  
**PHOTOGRAPHS**



RW 8L-26R Section 6105 SU 300: Low Severity Swelling (October 3, 2006)



RW 8L-26R Section 6105 SU 300: Low Severity Block Cracking (October 3, 2006)



RW 8L-26R Section 6105 SU 301: Low Severity Block Cracking (October 3, 2006)



RW 8L-26R Section 6105 SU 322: Low Severity Block Cracking (October 3, 2006)



RW 8L-26R Section 6105 SU 343: Low Severity Block Cracking (October 3, 2006)



RW 8L-26R Section 6105 SU 378: Low Severity Block Cracking (October 3, 2006)





TW PARALL Section 105 SU 101: Low Severity Block Cracking (October 3, 2006)



TW PARALL Section 105 SU 107: Low Severity L/T Cracking (October 3, 2006)



TW PARALL Section 105 SU 115: Overview (October 3, 2006)



TW PARALL Section 105 SU 122: Medium Severity Block Cracking  
(October 3, 2006)





TW PARALL Section 150 SU 140: Medium Severity Corner Break  
(October 3, 2006)



TW PARALL Section 150 SU 149: Medium Severity Linear Cracking  
(October 3, 2006)





**RW 18L-36R Section 6205 SU 156: Low Severity L/T Cracking  
(October 3, 2006)**



**APRON Section 4105 SU 506: High Severity Joint Seal Damage  
(October 3, 2006)**