Public Transportation Office Airport Inspection Record

2/3/2025 George T Lewis Airport **Inspection Date:** 11/18/2024 **Facility Name:** Inspector: **David Smith** Facility Type: Airport Status: Active Location ID: CDK FAA Site No.: 03102.\*A FDOT District: 2 1.00 Miles W of Cedar Key County: Levy 29° 8' 03.29 ARP Latitude: Ownership **Public** Source: Surveyed ARP Longitude: 83° 3' 02.10 Use: **Public** Elevation: Source: Sectional Chart: 6.94 Surveyed **JACKSONVILLE** Note: Primary contact shows below with a background. Facility Owner: Levy County **Facility Physical Address** Address: PO Box 310 16751 SW Airport Rd Address: State: FL ZIP: 32621 City: **Bronson** City: Cedar Key State: FL ZIP: 32625 Phone: (352) 486-5218 Fax: (352) 486-5167 Phone: Email: levyrd@levycounty.org Owner Representative: **Desiree Mills** Facility Manager: Mary-Ellen Harper 310 School ST PO Box 310 Address: Address: Bronson State: FL ZIP: 32621 City: City: State: FL ZIP: 32621 **Bronson** Phone: (352) 317-1988 Phone: (352) 486-5218 Email: district3@levycounty.org Email: harper.mary-ellen@levycounty.org Residential Airpark: Beacon: C-G Acreage: 40 No Wind Indicator: Section: 31 Township: 35S Range: 13E Yes Lighted: Yes Lighting Schedule: **Sunset to Sunrise** Notes: Attendance Schedule: Month/Day/Hour Segmented Circle: Yes Lighted: Facility Website: http://www.cedarkeyairport.org/airport-info.html Ask in any new facility aerials/photos are available **Based Aircraft** 3 Year. 2011 Single Engine: Jet Engine: Glider: Ultralight: Source: Inspector Multi Engine: Helicopter: Military: Seaplane: Total Based Aircraft: **Annual Operations** Year: Air Carrier: Air Taxi: GA Local: End Date: Commuter: GA Itinerant: Military: Total Annual Operations: FAR 139 Certificated FAA NavCom FSS ID: X GNV Clearance Delivery: FSS on Airport: No Ground Control: (800) WX-BRIEF Control Tower: Toll Free: VorTac: Approach Control: AWOS/ASOS: Unicom: ATIS: Instrument Approach: CTAF: 122,900

## State of Florida Department of Transportation

Public Transportation Office

Page 2 of 7

2/3/2025

http://www.florida-aviation-database.com Airport Inspection Record

**George T Lewis Airport Inspection Date:** 11/18/2024 Facility Name: Facility Type: Status: Active Inspector: **David Smith** Airport Services Fuel: Airframe: AMajor A1Minor A1+Power Plant: В Major B+Minor Diesel Other Services: E85 Aerial Surveying G100UL Air Ambulance Mogas Air Freight SAF Aircraft Rental UL102 Aircraft Sales 80 Avionics 85UL Beaching Gear 87 Car Rental 91/96 Cargo 91/96UL Courtesy Car 100 Charter 100LL Crop Dusting 100VLL Glider115 Glider Towing Bottle Oxygen: Instruction High Internet X 2 miles LowLodging Bulk Oxygen: Parachute Jumping Area X 2.5 miles High Restaurant Restrooms Low X 352-949-2127 Taxi Transient Storage: Telephone Buoy

Hangar Tie Downs

Page 3 of 7

Airport Inspection Record

http://www.florida-av	viation-database.com	Airport	Inspection Record			
Facility Name:	George T Lewis Airport			Inspection Date:	11/18/2024	
Facility Type:	Airport	State	us: Active	Inspector: David	Smith	
Runway ID	Status	Dimension	Surface	Condition	Lights	
05/23	Existing	2,302 x 75	Asph	Excellent	MIRL	
		Comments:				

RWY 05

FAR 77 Category A(V).

**RWY 23** 

FAR 77 Category A(V).

Approach ratio required is RWY 05 20:1 and RWY 23 20:1.

Primary surface required is 250 feet wide.

Transitional surface required is 0:1.

Safety	area required ex	tends 240	0 feet beyond	each runway	y end.									
						way 05								
	Latitude		gitude	Source		ope	Marking	VG	SI	REIL	Rt Traffic		oach	
05	29° 7' 55.71	83° 3	3' 11.79	Surveyed	(	0:1	BSC-G	N		Yes	No	NON	NE	
				•	Obstructio	n Data								
			<i>C</i> 1 :	D: 1	,	C !!:	14 1 1	Height	Distance	•	Direction		Control	lin
			Close-in Obstruction	Displacement Distance		Controlling Obstruction		Above Runway	From Runway		From Runway End	!	g Offset	ţ.
Primar	y Surface		Yes		0:1	BRUSH		12 ft	130 ft	Bef	ore Runway	End	95 ft	R
Runway	v End		Yes		11:1	BRUSH		12 ft	130 ft	Bef	fore Runway	End	95 ft	R
Marked	l Displaced Thre	shold	Yes	223 ft	29:1	BRUSH		12 ft	130 ft	Bef	fore Runway	End	95 ft	R
Require	ed Displaced Thr	eshold												
					Run	iway 23								
	Latitude	Long	gitude	Source	Sle	оре	Marking	VG	SI	REIL	Rt Traffic	Appr	oach	
23	29° 8' 10.87	83° 2	2' 52.41	Surveyed	(	0:1	BSC-G	N		Yes	No	NON	NE	
				(	Obstructio	n Data								
								Height	Distance	•	Direction		Control	lin
			Close-in	Displacemen		Controlling			From		From		g Officer	
			Obstruction	Distance		Obstruction	Lighted	Runway	Runway		Runway End		Offsei	
-	y Surface		Yes		0:1	ROAD		15 ft	40 ft		fore Runway		0 ft	
Runway			Yes	40.4.0	2:1	ROAD		15 ft	40 ft		fore Runway		0 ft	
	l Displaced Thre		Yes	424 ft	38:1	TREES		84 ft	2,730 ft	Bet	fore Runway	End	80 ft	R
кеqиirе	ed Displaced Thr	esnoia			Primary S	Surface and S	Safety Are	ea.						
					Distance	Direction								
Obj	ect Latitu	ıtude	Longitude	Survey/ Estimate	from Centerline	from Centerline	Height	Fixed by Function	Frangible	Mark	Aeronatic ed Study		etermina	tion
RO	AD 29° 8' 1	10.94	83° 2' 52.10	Estimated	0 ft	NE	15 ft	No	No	No				
SEAV	ALL 29° 07'	55.53 8	3° 03' 12.05	Estimated	0 ft	SW		No	No	No				
SEAV	ALL 29° 08'	11.54 8	3° 02' 51.61	Estimated	0 ft	NE		No	No	No				
RU	TS 29° 07'	56.02 8	3° 03' 12.22	Estimated	47 ft	NW		No	No	No				
		5605 0	20 021 12 21	Estimated	45 ft	N		No	No	No				
RU	TS 29° 07'	50.U/ 8	3° 03' 12.21	Estimated	<b>43</b> It									
RU BRU			3° 03' 12.21 3° 03' 12.19	Estimated	95 ft	S	12 ft	No	No	No				
	JSH 29° 07'	54.20 8					12 ft							

State of Florida Department of Transportation Public Transportation Office

Public Transportation Office Page 4 of 7

http://www.florida-aviation-database.com Airport Inspection Record 2/3/2025

nup.//www.jtoru	ad direction delicouse.	1227	import improved record								
Facility Nar	ne: George T	Lewis Airport					Insp	ection	Date: 11/1	8/2024	
Facility Typ	e: Airport			S	tatus: A	ctive	Insp	ector:	<b>David Smith</b>		
TREE	29° 08' 10 69	83° 02' 51 33	Estimated	83 ft	S	10 ft	No	No	No		

Public Transportation

 http://www.florida-aviation-database.com
 Airport
 Inspection Record

 Facility Name:
 George T Lewis Airport
 Inspection Date:
 11/18/2024

 Facility Type:
 Airport
 Status: Active
 Inspector:
 David Smith

iciencies		
ection Date	11/18/24 Next Inspection 11/30/25	
iciencies		
Rwy End: 05	In accordance with Chapter 14-60.007(5)(b), FAC. – For a runway that is paved, the runway safe length that extends the length of the runway plus 240 feet beyond each end of the runway.	ty area shall have a
	Runway 05 runway safety area does not extend 240 feet beyond the approach end of the runway being 40 feet before the runway.	due to shoreline
Rwy End: 23	length that extends the length of the runway plus 240 feet beyond each end of the runway.	
	Runway 23 runway safety area does not extend 240 feet beyond the approach end of the runway obeing 100 feet before the runway.	due to shoreline
	Road 15 feet tall, 40 feet before the approach end of Runway 23, on centerline is located inside the area of Runway 05/23.	ne runway safety
Rwy End: 23	In accordance with Chapter 14-60.007(2)(b)1.b., FAC. – For a runway that is paved, that is to be that weighs less than or equal to 12,500 pounds, and that has a visual landing approach: the prima the length of the runway plus 200 feet beyond each end of the runway.	_
	Road 15 feet tall, 40 feet before the approach end of Runway 23, and on centerline penetrates the of Runway 5/23.	primary surface
	Brush 6 feet tall, 72 feet before the approach end of Runway 23, 40 feet right of centerline penetr surface of Runway 5/23.	ates the primary
	Tree 10 feet tall, 50 feet before the approach end of Runway 23, 83 feet left of centerline penetrat surface of Runway 5/23.	es the primary
igated Deficie		
05/23 : Taxiway (A)	In accordance with Chapter 14-60.007(9)(f), FAC Holding position markings shall be placed 1	25 feet from visual
05/23:	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.	25 feet from visual
05/23:	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1	
05/23:	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline	that is feasible  oe fire extinguishers
05/23 : Taxiway (A)	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline and allows for aircraft to hold perpendicular to the centerline to check for other traffic.  In accordance with Chapter 14-60.007(7)(e), FAC. – At least two category 80 B-C, or higher, type shall be available at the airport, readily accessible, operationally functional, bear an unbroken sea	that is feasible  be fire extinguishers al, and be located in
05/23 : Taxiway (A)	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline and allows for aircraft to hold perpendicular to the centerline to check for other traffic.  In accordance with Chapter 14-60.007(7)(e), FAC. – At least two category 80 B-C, or higher, type shall be available at the airport, readily accessible, operationally functional, bear an unbroken sea an area clearly identified to the public.	that is feasible  of fire extinguishers al, and be located in  st 12 months.
05/23 : Taxiway (A)	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline and allows for aircraft to hold perpendicular to the centerline to check for other traffic.  In accordance with Chapter 14-60.007(7)(e), FAC. – At least two category 80 B-C, or higher, type shall be available at the airport, readily accessible, operationally functional, bear an unbroken sea an area clearly identified to the public.  Only one fire extinguisher was available at the airport and it had not been inspected within the last Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025 confirming fire extinguisher had been obtained and installed at the airport along with pictures.	that is feasible  of fire extinguishers al, and be located in  st 12 months. g that the second
05/23 : Taxiway (A) Facility	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline and allows for aircraft to hold perpendicular to the centerline to check for other traffic.  In accordance with Chapter 14-60.007(7)(e), FAC. – At least two category 80 B-C, or higher, type shall be available at the airport, readily accessible, operationally functional, bear an unbroken sea an area clearly identified to the public.  Only one fire extinguisher was available at the airport and it had not been inspected within the last Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025 confirming fire extinguisher had been obtained and installed at the airport along with pictures.  In accordance with Chapter 14-60.007(5)(b), FAC. – For a runway that is paved, the runway safe	that is feasible  be fire extinguishers al, and be located in  st 12 months. g that the second  ty area shall have a
05/23 : Taxiway (A) Facility	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline and allows for aircraft to hold perpendicular to the centerline to check for other traffic.  In accordance with Chapter 14-60.007(7)(e), FAC. – At least two category 80 B-C, or higher, type shall be available at the airport, readily accessible, operationally functional, bear an unbroken sea an area clearly identified to the public.  Only one fire extinguisher was available at the airport and it had not been inspected within the last Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025 confirming fire extinguisher had been obtained and installed at the airport along with pictures.  In accordance with Chapter 14-60.007(5)(b), FAC. – For a runway that is paved, the runway safe length that extends the length of the runway plus 240 feet beyond each end of the runway.  Excessive edge lips/washout at the runway threshold light cans 10 feet before the approach end of	that is feasible  be fire extinguishers al, and be located in  st 12 months. g that the second  ety area shall have a  f the runway, g that these have
05/23 : Taxiway (A) Facility	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline and allows for aircraft to hold perpendicular to the centerline to check for other traffic.  In accordance with Chapter 14-60.007(7)(e), FAC. – At least two category 80 B-C, or higher, type shall be available at the airport, readily accessible, operationally functional, bear an unbroken sea an area clearly identified to the public.  Only one fire extinguisher was available at the airport and it had not been inspected within the last Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025 confirming fire extinguisher had been obtained and installed at the airport along with pictures.  In accordance with Chapter 14-60.007(5)(b), FAC. – For a runway that is paved, the runway safe length that extends the length of the runway plus 240 feet beyond each end of the runway.  Excessive edge lips/washout at the runway threshold light cans 10 feet before the approach end on 45 to 50 feet left of centerline are present inside the runway safety area of Runway 05/23.  Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025, confirming been brought to grade and corrected. Pictures were provided showing the completed repairs to the	that is feasible  be fire extinguishers al, and be located in  st 12 months. g that the second  ty area shall have a  f the runway, g that these have e RSA.  used by an aircraft
Taxiway (A)  Facility  Rwy End: 05	In accordance with Chapter 14-60.007(9)(f), FAC. – Holding position markings shall be placed 1 runways serving small aircraft.  Taxiway A hold position marking is located 100 feet from the centerline of Runway 05/23.  Taxiway A hold position marking is located as far as possible from the Runway 05/23 centerline and allows for aircraft to hold perpendicular to the centerline to check for other traffic.  In accordance with Chapter 14-60.007(7)(e), FAC. – At least two category 80 B-C, or higher, type shall be available at the airport, readily accessible, operationally functional, bear an unbroken see an area clearly identified to the public.  Only one fire extinguisher was available at the airport and it had not been inspected within the last Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025 confirming fire extinguisher had been obtained and installed at the airport along with pictures.  Os In accordance with Chapter 14-60.007(5)(b), FAC. – For a runway that is paved, the runway safe length that extends the length of the runway plus 240 feet beyond each end of the runway.  Excessive edge lips/washout at the runway threshold light cans 10 feet before the approach end of 45 to 50 feet left of centerline are present inside the runway safety area of Runway 05/23.  Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025, confirmin been brought to grade and corrected. Pictures were provided showing the completed repairs to the In accordance with Chapter 14-60.007(2)(c)1.b., FAC. – For a runway that is paved, that is to be that weighs less than or equal to 12,500 pounds, and that has a visual landing approach: the approximate the provided showing the completed repairs to the that weighs less than or equal to 12,500 pounds, and that has a visual landing approach: the approximate the provided showing the completed repairs to the content of the provided showing the completed repairs to the content of the provided showing the completed repairs to the content of the	that is feasible  of fire extinguishers al, and be located in  st 12 months.  g that the second  ety area shall have a  f the runway,  g that these have e RSA.  used by an aircraft each surface ratio is

Page 5 of 7 2/3/2025 State of Florida Department of Transportation Public Transportation Office

Page 6 of 7 2/3/2025

http://www.florida-aviation-database.com

Airport Inspection Record

**George T Lewis Airport** 11/18/2024 Facility Name: **Inspection Date: David Smith** Facility Type: Airport Status: Active Inspector: Rwy End: 05 In accordance with Chapter 14-60.007(2)(b)1.b., FAC. - For a runway that is paved, that is to be used by an aircraft that weighs less than or equal to 12,500 pounds, and that has a visual landing approach: the primary surface extends the length of the runway plus 200 feet beyond each end of the runway. Brush 12 feet tall, 130 feet before the approach end of Runway 05, 95 feet right of centerline penetrates the primary surface of Runway 5/23. Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025, confirming that this vegetation had been trimmed along with pictures demonstrating compliance. In accordance with Chapter 14-60.007 (10)(b) Threshold and runway end lights shall be located not less than two feet Rwy End: 05 Displaced nor more than ten feet outboard from the designated threshold of the runway. Threshold Lights (Other Light) Runway 05 displaced threshold lights are located in line with the designated displaced threshold of the runway. Runway 05 displaced threshold light configuration is consistent with FAA Advisory Circular 150/5340-30J. Rwy End: 23 In accordance with Chapter 14-60.007(5)(b), FAC. – For a runway that is paved, the runway safety area shall have a width of 120 feet. Excessive edge lips for a lighting can 136 feet after the approach end of the runway, 48 feet right of centerline are present inside the runway safety area of Runway 05/23. Received an e-mail from Ms. Alice LaLonde, inspection contact, on January 30, 2025, confirming that these have been brought to grade and corrected. Pictures were provided showing the completed repairs to the RSA. Rwy End: 23 In accordance with Chapter 14-60.007(2)(c)1.b., FAC. - For a runway that is paved, that is to be used by an aircraft that weighs less than or equal to 12,500 pounds, and that has a visual landing approach: the approach surface ratio is Runway 23 approach surface ratio is 0:1 due to road 15 feet tall, 40 feet before the approach end of the runway, on centerline. Runway 23 threshold is displaced 424 feet. Rwy End: 23 In accordance with Chapter 14-60.007 (10)(b) Threshold and runway end lights shall be located not less than two feet Displaced nor more than ten feet outboard from the designated threshold of the runway. Threshold Lights (Other Light) Runway 23 displaced threshold lights are located in line with the designated displaced threshold of the runway. Runway 23 displaced threshold light configuration is consistent with FAA Advisory Circular 150/5340-30J.

## State of Florida Department of Transportation Public Transportation Office

Public Transportation Office Page 7 of 7

http://www.florida-aviation-database.com Airport Inspection Record 2/3/2025

Facility Name: Facility Type:	George T Lewis Airport Airport			Inspection Date: 11/18/2024 Inspector: David Smith
License				
55	/01/2025 /28/2026	Category:	Public Special	Limitations: Day Use Only  VFR Use Only

Conditions:

The department may revoke, refuse to allow or issue, any license or license renewal, if it determines that the airport does not comply with the conditions of the license, license renewal, or site approval or that the airport has become unsafe or unusable for flight operation due to physical or legal changes that were the subject of approval pursuant to Section 330.30(2)(e), F.S.

- A. This Airport has the following landing areas and approach limitations.
- 1. Runway 05/23 is available for visual approaches only.
- a. Runway 05 is FAR 77 category A(V).
- b. Runway 23 is FAR 77 category A(V).
- 2. Runway 5 threshold is displaced 223 feet.
- 3. Runway 23 threshold is displaced 424 feet.
- B. This Airport is issued a Special License pursuant to Chapter 330.30(2)(b), F.S.

The department may license a public airport that does not meet standards only if it determines that such an exception is justified by unusual circumstances or is in the interest of public convenience and does not endanger the public health, safety, or welfare. Such a license shall bear the designation "special" and shall state the conditions subject to which the license is granted.

- 1. Safety area at the end of Runway 05 is only 40 feet in length.
- 2. Brush 12 feet tall, 130 feet before the approach end of Runway 05, 95 feet right of centerline penetrates the primary surface of Runway 5/23.
- 3. Road 15 feet tall, 40 feet before the approach end of Runway 23, on centerline penetrates the primary surface and safety area of Runway 5/23.
- 4. Safety area at the end of Runway 23 is only 100 feet in length.

Additional Licensing Remarks: