

STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION AVIATION OFFICE

Statewide Airfield Pavement Management Program

Suwannee County Airport – 24J (General Aviation) Live Oak, Florida (District 2)



May 2011

TABLE OF CONTENTS

SECTION

PAGE NO.

Exe	cutive Summary	iii
	Introduction	
2.	Network Definition and Pavement Inventory	
3.	Pavement Condition	
4.	Pavement Condition Prediction	
5.	Maintenance Policies and costs	
6.	Pavement Rehabilitation Needs Analysis	
	Maintenance and Rehabilitation Plan	
8.	Visual Aids	
9.	Recommendations	

LIST OF FIGURES

Figure 1-1: Pavement Life Cycle	4
Figure 1-2: PCI Rating Scale	
Figure 2-1: Pavement Area by Surface Type	
Figure 3-1: Network PCI Distribution by Rating Category	16
Figure 3-1a: Condition Rating Summary	16
Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use	17
Figure 4-1: Predicted PCI by Pavement Use	19
Figure 6-1: Budget Scenario Analysis	

LIST OF TABLES:

Table I: Condition Summary by Branchi	ii
Table II: Condition Summary by Pavement Use	iv
Table III: Condition Summary by Pavement Ranki	iv
Table IV: Immediate Major M&R Needsi	
Table V: 10-Year M&R Costs under Unlimited Funding Scenario	

Table 1-1: Sampling Rate for FDOT Condition Surveys	5
Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity	11
Table 2-2: Pavement Area by Pavement Use	11
Table 2-3: Branch and Section Inventory	13
Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces	14
Table 3-2: Condition by Pavement Use	17
Table 5-1: Routine Maintenance Activities for Airfield Pavements	21
Table 5-2: Critical PCI for General Aviation Airports	22
Table 5-3: Desired Minimum PCI for General Aviation Airports	22
Table 5-4: M&R Activities for General Aviation Airports	23
Table 5-5: Maintenance Unit Costs for FDOT	24
Table 5-6: M&R Activities and Unit Costs by Condition for General Aviation Airports.	25
Table 6-1: Summary of Immediate Major M&R Needs Option No. 1	26
Table 6-2: Summary of Immediate Major M&R Needs Option No. 2	27

TABLE OF CONTENTS

SECTIONPAGE NO.Table 6-3: Summary of Year 1 Maintenance Activities28

Tuble 0.5. Summary of Tear T Maintenance Tear Mice and	
Table 7-1: M&R Costs under Unlimited Funding Scenario 31	

APPENDICES

System Inventory Map	
Pavement Inventory Table	
Work History Report	
Appendix B 2011 Condition Map	
Pavement Condition Index Table	
Appendix C Branch Condition Report	
Section Condition Report	
Appendix D Pavement Condition Prediction Table	
Predicted PCI by Pavement Use Graph	
Appendix E Year 1 Maintenance Activities Table	
Appendix F Major M&R Plan by Year under Unlimited Funding Scenario Tab	le
Appendix G 10-Year M&R Map	
Appendix H Photographs	
Appendix I PCI Re-inspection Report	

EXECUTIVE SUMMARY

In 2010, the Florida Department of Transportation (FDOT) Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing Statewide Airfield Pavement Management Program (SAPMP) to be completed over fiscal years 2011 and 2012.

The tasks required to achieve this objective at Suwannee County Airport included:

- Obtain recent construction history from the Airport to update the Pavement Inventory CADD drawings from the previous SAPMP update,
- Perform a visual Pavement Condition Index (PCI) survey of the airfield pavements at the Airport,
- Update the MicroPAVER database to analyze the PCI field data and determine the current condition of the airfield pavements,
- Predict the future deterioration of the pavements,
- Develop a 10-year M&R plan to address the pavement needs at Suwannee County Airport, and
- Provide the estimated costs associated with the suggested immediate and future M&R activities

During December 2010, the PCI survey was performed at Suwannee County Airport. The results of the survey indicate that, based on a numerical scale of 0 to 100, the overall area-weighted average PCI of the airfield pavements in 2010 is 76, representing a Satisfactory overall network condition.

Table I below summarizes the overall condition summary by network branch.

Branch Name Area Weighted PCI		Condition Rating	FDOT Minimum Service Level	MicroPAVER Minimum PCI	Action Required
Apron	53	Poor	60	65	Х
Runway 7-25	85	Satisfactory	75	65	
Taxiway	85	Satisfactory	65	65	

Table I: Condition Summary by Branch

Tables II and III below illustrate the area-weighted PCI computed individually for each pavement use and rank, respectively.

Use	Average Area- Weighted PCI	Condition Rating
Runway	85	Satisfactory
Taxiway	85	Satisfactory
Apron	53	Poor
All (Weighted)	76	Satisfactory

Table II: Condition Summary by Pavement Use

Table III: Condition Summary by Pavement Rank

Rank*	Average Area- Weighted PCI	Condition Rating	
Primary	76	Satisfactory	
All (Weighted)	76	Satisfactory	

*The pavement rank for the airport pavement network is listed on Table 2-3.

The immediate M&R needs, or needs that have been programmed to be completed in the first year of the 10-year M&R plan based on an unlimited budget at Suwannee County Airport, include: Apron and Taxiway. The Apron and Taxiway sections exhibited medium to high severity distresses primarily related to climate including raveling and weathering and linear cracking. Both branches, based on the determined PCI will benefit from a mill and overlay. The immediate needs are summarized in Table IV below.

Table IV: Immediate Major M&R Needs

Branch Name	Section ID	Surface Type	Section Area (ft ²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
Apron	4105	AC	151,753	\$954,526.44	43	Mill and Overlay	100
Apron	4110	AAC	16,900	\$106,301.01	44	Mill and Overlay	100
Taxiway	120	AC	4,495	\$17,953.04	58	Mill and Overlay	100
Taxiway	125	AC	3,500	\$8,148.01	64	Mill and Overlay	100
Taxiway	135	AC	3,500	\$9,103.51	63	Mill and Overlay	100
			Total	\$1,096,032.01	54		100

* Costs are adjusted for inflation.

A forecast of Major M&R needs for a 10-year period, starting from 2011, was developed using an unlimited budget. The analysis identified ongoing maintenance needs and major M&R during that interval. The results of this analysis are provided in Table V below.

Year	Preventative	Major M&R	Total Year Cost
2011	\$20,568.09	\$1,096,032.00	\$1,116,600.09
2012	\$35,920.93	\$0.00	\$35,920.93
2013	\$45,485.80	\$0.00	\$45,485.80
2014	\$54,496.94	\$0.00	\$54,496.94
2015	\$67,263.80	\$0.00	\$67,263.80
2016	\$70,970.35	\$60,898.24	\$131,868.59
2017	\$82,786.96	\$0.00	\$82,786.96
2018	\$89,778.43	\$41,489.78	\$131,268.21
2019	\$108,581.77	\$0.00	\$108,781.77
2020	\$104,117.08	\$167,619.08	\$271,732.16
Total	\$679,970.15	\$1,366,039.10	\$2,046,009.25

Table V: 10-Year M&R Costs under Unlimited Funding Scenario

Note: Costs are adjusted for inflation.

The implementation of the 10-Year Major M&R Plan is expected to provide an improvement in the overall condition of the airfield pavement, where the area-weighted PCI would increase from 76 in 2010 to 79 in 2020. Appendix F lists the Major M&R for the 10-Year program. Appendix G graphically depicts the program activity.

It is important to note that although preventative and some major M&R activities would have to be conducted over several years, the area-weighted PCI value for all Suwanne County Airport pavements in 2020 may remain near 76. The airport manager should realize that what is most important is that the pavement repair work (preventative and major M&R) that has been identified for Suwanne County Airport is conducted at some point in the 10-year plan.

1. INTRODUCTION

The State of Florida has more than 100 public airports that are vital to the Florida economy as well as the economy of the United States. There are millions of square yards of pavement for the runways, taxiways, aprons and other areas of these airports that support aircraft operations. The timely and proper maintenance and rehabilitation (M&R) of these pavements allows the airports to operate efficiently, economically and without excessive down time.

In order to support the planning, scheduling, and design of the M&R activities based on pavement evaluation and pavement management performance trends, the Florida Department of Transportation (FDOT) Aviation Office implemented the Statewide Airfield Pavement Management Program (SAPMP) in 1992.

In 2010, the FDOT Aviation Office selected a Consultant team consisting of Kimley-Horn and Associates and their Subconsultants, MACTEC Engineering and Consulting and All About Pavements, Inc., to provide services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

This report discusses the work performed, a summary of the findings, results, and recommendations for M&R planning associated with the update to the SAPMP. It also describes the procedures used to ensure that the appropriate engineering and scientific standards of care, quality, budget, and schedule requirements are implemented during the performance of the SAPMP.

1.1 Purpose

This Florida Airport Pavement Evaluation Report is intended to:

- Describe, briefly, the SAPMP and the roles and responsibilities of the program's participants;
- Provide background information on pavement management principles, objectives, and benefits to this airport;
- Outline the procedures used to collect, evaluate and report pavement inspection results at this airport;
- Present the findings from the pavement inspection;
- Analyze and discuss the needs for Maintenance and Rehabilitation (M&R) activities and associated costs for this airport.

1.2 FDOT Statewide Airfield Pavement Management Program

In 1992, the FDOT implemented the SAPMP to improve the knowledge of pavement conditions at public airports in the State system, identify maintenance needs at individual airports, automate information management, and establish standards to address future needs. The 1992 SAPMP provided valuable information for establishing and performing pavement M&R.

In 1992/1993, and 1998/1999, the FDOT Aviation Office participated in the development of a proprietary software pavement management system and developed and populated a pavement management database that provided valuable information for establishing M&R policies, estimating M&R costs, and developing recommendations for performing routine pavement maintenance. This system, AIRPAV, was implemented, and initial condition surveys were

performed in 1992 and 1993. The SAPMP was updated with additional surveys in 1998 and 1999.

In 2004, the FDOT Aviation Office undertook a project to update the pavement management system software utilized for the SAPMP. This project involved a review of the AIRPAV software and other available pavement management system software. As a result of this review, MicroPAVER was selected as the software for the update project. Data from the 1998/1999 condition surveys were converted to the MicroPAVER system, and the inventory of the pavement systems and drawings of the pavements were updated to reflect maintenance, rehabilitation, and construction activities since 1998/1999. The pavements were inspected between 2006 and 2008, and an updated M&R program was developed based on the new condition of the airfield pavements. As part of the update, procedures for the inspection and collection of pavement data were developed, and a website (www.floridaairportpavement.com) was created for the input of data under secure procedures.

Currently, airports using the AIP Grant Program are required by the Federal Aviation Administration (FAA) to develop a pavement maintenance program (FAA/AC 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements") using trained personnel to perform a detailed inspection of airfield pavements. The inspections are required to be performed at least once a year or every 3 years if pavement inspection is characterized in the form of a Pavement Condition Index (PCI) survey (such as ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys", (2004 edition)). The 2004 edition was utilized in lieu of the 2010 edition to maintain database integrity and benefit of pavement performance curves from the previous inspections.

In 2010, the FDOT Aviation Office selected a team consisting of the Consultant and their Subconsultants to provided services in support of FDOT in the continuing evaluation and updating of the existing SAPMP to be completed over fiscal years 2011 and 2012.

1.3 Organization

1.3.1 Aviation Office Program Manager Role

The Aviation Office Airport Engineering Manager serves as the Aviation Office Program Manager (AO-PM) monitoring the work of the Consultant. The AO-PM has review and approval authority for each program task and also manages the day-to-day details of the SAPMP and the updates.

1.3.2 Consultant Role

The Consultant (Kimley-Horn and Associates, Inc.) and their Subconsultants (MACTEC Engineering and Consulting and All About Pavements, Inc.) provide technical and administrative assistance to the AO-PM during the execution of this program, which involves the continuing evaluation of airport pavements and updating of the SAPMP based upon procedures outlined in FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

1.3.3 Airport Role

The airports are the ultimate client for each of the field inspections and reports. Individual airports will be provided final deliverables prepared by the Consultant that have been reviewed and approved by the AO-PM. The airport should provide a current Airport Layout Plan (ALP) to the Consultant and, if they participated in the previous SAPMP update, indicate any construction activity that has been performed since the previous inspections.

1.4 Pavement Types and Pavement Management

1.4.1 Pavement basics

A pavement is a prepared surface designed to provide a continuous smooth ride at a certain speed and to support an estimated amount of traffic for a certain number of years. Pavements are constructed of a combination of subgrade soils, subbases, bases and surfacing. There are mainly two types of pavements;

- Flexible pavement, composed of an asphalt concrete (AC) surface, and
- Rigid pavement composed of a Portland Cement Concrete (PCC) surface.

Both pavement types use a combination of layered materials and thicknesses in order to support the traffic loads and protect the underlying natural subgrade soil. Flexible pavements (AC) dissipate the load from layer to layer until the load magnitude is small enough to be supported by the subgrade soil. In rigid pavements (PCC), the Portland Cement Concrete supports most of the load, and the base or subbase layer is mainly constructed to provide a smooth and continuous platform for the construction of the concrete surface.

A small percentage of the airport pavements in Florida are composed of asphalt concrete surface over Portland Cement Concrete (APC). This pavement type is known as "composite" pavement.

Due to the different nature of the pavement types and their materials, flexible and rigid pavements have different distresses and failure mechanisms. Understanding the mechanics and failure modes of both pavement types will assist engineers in making adequate and long lasting repairs or rehabilitation to the pavement structures.

1.4.2 Pavement Management System Concept

The SAPMP utilized a Pavement Management System (PMS) to develop the M&R recommendations discussed in this report. A PMS is a tool to assist engineers, planners and managing agencies in making decisions when planning pavement M&R. The management of pavements involves scheduling pavement maintenance and rehabilitation before pavements deteriorate to a condition where reconstruction (the most expensive alternative) is the only solution. Figure 1-1 below, taken from FAA/AC 5380-7A "Airport Pavement Management Program", illustrates how a pavement generally deteriorates and the relative cost of rehabilitation at various times throughout its life. Note that during the first 75 percent of a pavement's life, it performs relatively well. After that, however, it begins to deteriorate rapidly. The number of years a pavement stays in "good" condition depends on how well it is maintained. As the illustration demonstrates, the cost of maintaining the pavement above a critical condition before rapid deterioration has occurred.




Figure 1-1: Pavement Life Cycle

Source: FAA/AC 150/5380-7A "Airport Pavement Management Program" *Modified to reflect current construction costs.

Pavements deteriorate at an accelerated rate with increasing traffic and limited M&R resources. Planned maintenance and rehabilitation, essentially preventing pavements from reaching deteriorated conditions, helps managers/owners/agencies maximize the use of their budgets and prolong the life of the pavements. A PMS provides a tool to schedule and plan maintenance and rehabilitation based on engineering information and existing and predicted conditions of pavements.

There are several components or elements that are essential to a PMS. The first steps in the implementation of a PMS are to know and clearly identify what needs to be managed, the limits of the managing agency's responsibilities and the condition of the existing pavements. Once the cause and the extent of pavement problems are known, the appropriate maintenance and/or rehabilitation can be planned. By using local unit costs and expected yearly budgets, a multi-year M&R plan can be determined.

1.4.3 Pavement Inspection Methodology for the SAPMP

Pavement condition assessment is one of the primary decision variables in any airport PMS. Pavement condition assessments generally include visual surveys in accordance with ASTM D 5340, "Standard Test Method for Airport Pavement Condition Index Surveys" and structural evaluation. Pavement condition surveys assess the functional condition of the pavement surface. Typically, most problems within a pavement structure will eventually reflect to the pavement surface. The structural condition and relative support of the pavement layers can be assessed utilizing non-destructive deflection testing (NDT) as well as other in-depth engineering evaluation or sampling and testing methods.

For the Statewide Aviation Pavement Management Program update, only visual surveys were performed. Further structural and geotechnical testing should be conducted to determine the appropriate rehabilitation methods during the design process.

In preparation of the PCI surveys, the airfield pavements are divided into sample units as established in FAA AC 150/5380-6B and ASTM D 5340. Further discussion of how the airport pavements are divided and subdivided into units by construction and use can be found in Section 2 "Network Definition and Pavement Inventory" of this report.

Sample unit sizes are approximately 5000 ± 2000 square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements. Prior to conducting the field inspections, the sampling plan was developed based on previous sampling and modified based on the available knowledge of Branches, Sections, use patterns, construction types and history. The sampling rate used for the FDOT Statewide Airfield Pavement Management Program is provided in Table 1-1 below.

	AC Pavemen	ts	PCC Pavements			
NI	n		N	n		
Ν	Runway	Others	Ν	Runway	Others	
1-4	1	1	1-3	1	1	
5-10	2	1	4-6	2	1	
11-15	3	2	7-10	3	2	
16-30	5	3	11-15	4	2	
31-40	7	4	16-20	5	3	
41-50	8	5	21-30	7	3	
<u>></u> 51	20% but <u><</u> 20	10% but <u><</u> 10	31-40	8	4	
			41-50	10	5	
			<u>></u> 51	20% but <u><</u> 20	10% but <u><</u> 10	

Table 1-1: Sampling Rate for FDOT Condition Surveys

Where

N = total number of sample units in Sectionn = number of sample units to inspect

The sample units to inspect are determined by a systematic random sampling technique. This means that the locations are determined such that they are distributed evenly throughout the Section. In the case when nonrepresentive distresses are observed in the field, additional sample units were added.

The distress quantities and severity levels from the sample units are used to compute the PCI value for each Section. PCI values range from 0 to 100. As Figure 1-2 below indicates, MicroPAVER provides a rating scale that relates PCI to pavement condition. A PCI between 0 and 10 is considered 'Failed' pavement, and a PCI between 86 and 100 is considered 'Good' pavement, with five other conditions for PCI values between 11 and 85.

РСІ	Condition Rating
86 - 100	Good
71 - 85	Satisfactory
56 – 70 Fair	
41 – 55	Poor
26 - 40	Very Poor
11 - 25	Serious
0 – 10	Failed

Figure 1-2: PCI Rating Scale

1.5 Definitions

<u>Aviation Office</u> - The Aviation Office is charged with responsibility for promoting the safe development of aviation to serve the people of the State of Florida. The Aviation Office Program Manager (AO-PM) has review and approval authority for each program task of the SAPMP.

<u>Base Course</u> - Base Course is a layer of manufactured material, usually crushed rock (aggregate) or stabilized material (asphalt or concrete or Florida Limerock), immediately beneath the surface course of a pavement, which provides support to the surface course.

<u>Branch</u> - A Branch designates pavements that have common usage and functionality, such as an entire runway, taxiway, or apron.

<u>Branch ID</u> - A short form identification for the pavement Branch. In this report, Branch includes the common designation for the item e.g. RW 18-36.

<u>Category</u> - The Category classifies the airport according to the type and volume of aircraft traffic, as follows:

- GA for general aviation or community airports;
- RL for regional relievers or small hubs;
- PR for primary (certified under Part 139 requirements).

<u>Critical PCI</u> - The PCI value considered to be the threshold for M&R decisions. PCI above the Critical generate economical activities expected to preserve and prolong acceptable condition. M&R for PCI values less than Critical make sense only for reasons of safety or to maintain a pavement in operable condition. A pavement section is expected to deteriorate very quickly once it reaches the Critical PCI and the unit cost of repair increases significantly.

<u>Distress Type</u> - A distress type is a defined visible defect in pavement evidenced by cracking, vertical displacement or deterioration of material. In PCI technology, 16 distinct distress types for asphalt surfaced and 15 for Portland Cement Concrete surfaced pavements have been described and rated according to the impact their presence has on pavement condition.

<u>Florida DOT (FDOT)</u> - Florida Department of Transportation was represented in this project by the Office of Aviation.

<u>Global M&R</u> - Global M&R is defined as activities applied to entire pavement Sections with the primary objective of slowing the rate of deterioration. These activities are primary for asphalt surfaced pavements, e.g. surface treatments.

Localized M&R (Maintenance and Repair) - Localized M&R is a temporizing activity performed on existing pavement to extend its serviceability and/or to improve rideability. Localized M&R can be applied either as a safety (stop-gap) measure or preventive measure. Common localized maintenance methods include crack sealing, joint sealing, and patching.

<u>Major M&R (e.g. Rehabilitation)</u> - Activities performed over the entire area of a pavement Section that are intended to restore and/or maintain serviceability. This includes asphalt overlays, milling and replacing asphalt pavement, reconstruction with asphalt, reconstruction with Portland Cement Concrete (PCC) pavements, and PCC overlays.

<u>MicroPAVER</u> - A commercially available software subsidized by FAA and agencies in the US Department of Defense developed to support engineered management of pavement assets using a condition based approach. This software has the functionality such that, if properly implemented, maintained, and operated, it meets the pavement management program requirements described by the FAA in Advisory Circular 150/5380-7A.

<u>Minimum Condition Level</u> - A threshold PCI value established by FDOT to represent the targeted minimum pavement condition that is desirable in the Florida Airport System. These values were established with consideration of pavement function and airport type. For instance, runways have higher minimum condition levels than aprons, and Primary airports have higher minimum condition levels than airports.

<u>Network Definition</u> - A Network Definition is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample units to be surveyed, i.e. the sampling plan. The Network Definition for the airport is in Appendix A along with a table of inventory data.

<u>Pavement Condition Index (PCI)</u> - The Pavement Condition Index is a number which represents the condition of a pavement segment at a specific point in time. It is based on visual identification and measurement of specific distress types commonly found in pavement which has been in service for a period of time. The definitions and procedures for determining the PCI are found in ASTM D 5340, published by ASTM International.

<u>Pavement Evaluation</u> - A systematic approach undertaken by trained and experienced personnel intended for determination of the condition, serviceability, and best corrective action for pavement. Techniques to standardize pavement evaluation include the Pavement Condition Index procedures.

<u>Pavement Management System (PMS)</u> - A Pavement Management System is a broad function that uses pavement evaluation and pavement performance trends as a basis for planning, programming, financing, and maintaining a pavement system.

<u>Pavement Surface Type</u> - The surface of pavement is identified as one of four types:

- AC for asphalt surface pavements;
- PCC for Portland Cement Concrete pavements;
- AAC for asphalt surface pavements that have had an asphalt overlay at some point in their construction history;
- APC for composite pavements, which consist of asphalt over Portland Cement Concrete pavement.
- PAC for composite pavements, which consist of Portland Cement Concrete over asphalt pavement.

 \underline{Rank} - Pavement rank in MicroPAVER determines the priority to be assigned to a pavement Section when developing an M&R plan. Pavement Sections are ranked as follows according to their use:

- P for Primary pavements, such as primary runways, primary taxiways, and primary aprons;
- S or Secondary pavements, such as secondary runways, secondary taxiways, and secondary aprons;
- T for Tertiary pavements such as "T" hangars and slightly used aprons.

<u>Reconstruction</u> - Reconstruction includes removal of existing pavement, preparation of subgrade, and construction of new pavement with new or recycled materials. Reconstruction is indicated when distress types evident at the surface indicate failure in the pavement structure or subgrade of a type, and to an extent, not correctable by less extensive construction.

<u>Rehabilitation</u> - Rehabilitation represents construction using existing pavement for a foundation. Rehabilitation most commonly consists of an overlay of existing pavement with a new asphalt or concrete surface. Recently, technology has expanded the options to include recycling of existing pavement and incorporating engineering fabrics or thin layers of elasticized materials to retard reflection of distress types through the new surface.

<u>Sample Unit</u> - Uniformly sized portions of a Section as defined in ASTM D 5340. Sample units are a means to reduce the total amount of pavement actually surveyed using statistics to select and survey enough area to provide a representative measure of Section PCI. Sample Unit sizes are $5,000 \pm 2,000$ square feet for AC-surfaced pavements and 20 ± 8 slabs for PCC-surfaced pavements.

<u>Section</u> - Sections subdivide Branches into portions of similar pavement. Sections are prescribed by pavement structure, age, condition, and use. Sections are identified on the airport Network Definition. They are the smallest unit used for determining M&R requirements based on condition.

<u>Section ID</u> - A short form identification for the pavement Section that maintains the original AirPAV identification where 100 series through 3000 series Sections are taxiways, 4000 and 5000 series Sections are aprons (the 5000 series represent run-up aprons and turnarounds), and 6000 series Sections are runways.

<u>Statewide Airfield Pavement Management Program (SAPMP)</u> – The Statewide Airfield Pavement Management Program is a program implemented in 1992 by the Florida Department of Transportation to plan, schedule, and design the maintenance and rehabilitation activities

necessary for the airfield pavement on Florida's public airports to allow the airports to operate efficiently, economically, and without excessive down time.

<u>System Inventory</u> - A System Inventory is a Computer-Aided Drafting & Design (CADD) drawing which shows the airport pavement outline and identifies airfield construction activities since the last inspection. The System Inventory for the airport is included in Appendix A.

<u>Use</u> - In MicroPAVER, Use is the term for the function of the pavement area. This is either Runway, Taxiway, or Apron for purposes of the FDOT Statewide Aviation Pavement Management System.

2. NETWORK DEFINITION AND PAVEMENT INVENTORY

Suwannee County Airport (24J) was the first airport opened in Suwannee County, Florida and is directly controlled by a County Board of Commissioners and a paid manager. Suwannee County Airport focuses primarily on serving general aviation aircraft and has one runway, Runway 7-25. This airport is designated as a General Aviation airport and is located in District 2 of the Florida Department of Transportation.

Based on field measurements, it is important to note that the runway data and other pavement facilities geometric dimensions may vary slightly from the geometry used in the condition and M&R analysis.

In its current role, the airport supports general aviation aircraft with services including flight training, sport/recreational flying, and re-fueling. A small percentage of business flights are included in the air traffic for the airport. The airport does not have serve as a base for any military aircraft and does not accommodate any military operations.

2.1 Network Definition

The pavements within the network are defined in MicroPAVER in terms of manageable units that help to organize the data into similar groups. An organizational hierarchy is used to establish these units.

2.1.1 Branch Section Identification

The airport pavement network is subdivided into separate Branches (runways, taxiways, or aprons) that have distinctly different uses. Branches are then further divided into Sections with similar pavement construction and performance that may share other common attributes.

Sections are manageable units used to organize the data collection and are treated individually during the rehabilitation planning stage. A pavement rank, consisting of primary, secondary, and tertiary levels, is assigned to each Section based on their level and type of use. The pavement rankings that were designated for each Section in the previous SAPMP update were again used for this update.

As discussed in Section 1.4.3 "Pavement Inspection Methodology for the SAPMP", the sections are sub-divided into sample units, which are the smallest subdivision in a pavement network, only for the purpose of conducting the pavement condition survey.

2.1.2 System Inventory and Network Definition Update

The System Inventory and Network Definition drawings are used to identify changes in the network since the most recent update from the 2006/2008 inspections and also to plan the field inspection activities for the 2010 survey. Prior to the field inspection process, the System Inventory drawing was updated from the previous inspection with notes indicating recent construction projects on the various Sections of pavement throughout the airfield. This System Inventory drawing is used to update the Network Definition drawing.

The Network Definition drawing shows the airport pavement outline with Branch and Section boundaries. This drawing also includes the PCI sample units and is used to identify those sample

units to be surveyed, i.e. the sampling plan. The previous airport configuration and history was compared with the current airport configuration, and the existing network branch, section and sample unit designations were revised to match the current configuration. This drawing serves not only as a primary guide for the airfield inspectors but also as an important historical record.

The updated System Inventory and Network Definition drawings for Suwannee County Airport are provided in Appendix A. Table 2-1 below lists the recent construction projects at the airport.

Table 2-1: Construction Since Last Inspection & Anticipated Construction Activity

Construction Year	Location	Work Type / Pavement Section
2007	Taxiway	Taxiway and run-up pad
2008	Taxilanes	T-hangars and taxilanes

2.2 Pavement Inventory

The detailed pavement inventory was updated to reflect the network definition update and field inspection results.

The total airfield pavement area in 2010 at Suwannee County Airport is 703,749 square feet. The breakdown of pavement area for each pavement use is provided in Table 2-2.

Use	Area (ft ²)	% of Total Area
Runway	300,000	43%
Taxiway	185,988 26%	
Apron	217,761	31%
All (Weighted)	703,749	100%

Table 2-2: Pavement Area by Pavement Use

Figure 2-1 presents the breakdown of the pavement area at Suwanne County Airport by surface type.




Figure 2-1: Pavement Area by Surface Type

Details of pavement Branch and Section information including Branch name (which indicates pavement use), Branch ID, Section ID, section area, rank, surface type, last construction date, number of samples inspected, and number of samples in each Section are given in Table 2-3 below. A more detailed Pavement Inventory Table may be found in Appendix A of this report.

Branch Name	Branch ID	Section ID	True Area (ft ²)	Section Rank	Surface Type	Last Const. Date	Total Samples Inspected	Total Samples
Apron	AP	4105	151,753	Р	AC	1/1/1990	6	34
Apron	AP	4110	16,900	Р	AAC	1/1/1990	1	4
Apron	AP	4115	22,565	Р	AC	3/1/2008	1	6
Apron	AP	4120	26,543	Р	AC	7/1/2006	0	5
Runway 7-25	RW 7-25	6105	75,000	Р	AC	1/1/2006	5	20
Runway 7-25	RW 7-25	6110	225,000	Р	AC	1/1/2006	12	60
Taxiway	TW	104	3,600	Р	AC	1/1/2004	1	1
Taxiway	TW	105	49,391	Р	AAC	1/1/1990	3	14
Taxiway	TW	110	99,832	Р	AC	1/1/2004	3	29
Taxiway	TW	115	12,970	Р	AC	1/1/1990	1	3
Taxiway	TW	120	4,495	Р	AC	1/1/1990	1	1
Taxiway	TW	125	3,500	Р	AC	1/1/2000	1	2
Taxiway	TW	135	3,500	Р	AC	1/1/2004	1	2
Taxiway	TW	145	3,500	Р	AC	1/1/2004	1	2
Taxiway	TW	150	5,200	Р	AC	1/1/1990	1	1

Table 2-3: Branch and Section Inventory

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

3. PAVEMENT CONDITION

Pavement conditions were inspected in accordance with the methods outlined in FAA AC 150/5380-6B and ASTM D 5340-04 "Standard Practice for Airport Pavement Condition Index Surveys." These procedures define distress type, severity and quantity for sampling areas within each section to determine the Pavement Condition Index (PCI).

3.1 Inspection Methodology

A PCI survey is performed by measuring the amount and severity of pavement distresses, which are caused by traffic load, climate, and other factors, observed within a sample unit. This data is imported into MicroPAVER, which calculates PCI values for the pavement sections. Table 3-1 below lists the pavement distress types and related causes for asphalt concrete (AC).

Table 3-1: Pavement Distresses for Asphalt Concrete Surfaces

Code	Distress	Mechanism		
41	Alligator Cracking	Load		
42	Bleeding	Construction Quality / Mix Design		
43	Block Cracking	Climate / Age		
44	Corrugation	Load / Construction Quality		
45	Depression	Subgrade Quality		
46	Jet Blast	Aircraft		
47	Joint Reflection - Cracking	Climate / Prior Pavement		
48	Longitudinal/Transverse Cracking	Climate / Age		
49	Oil Spillage	Aircraft / Vehicle		
50	Patching	Utility / Pavement Repair		
51	Polished Aggregate	Load		
52	Weathering/Raveling	Climate / Load		
53	Rutting	Load		
54	Shoving	Pavement Growth		
55	Slippage Cracking	Load / Pavement Bond		
56	Swelling	Climate / Subgrade Quality		
Source: U.S.	Source: U.S. Army CERL, FDOT Airfield Inspection Reference Manual			

Prior to conducting the inspections, Global Positioning System (GPS) coordinates were recorded using CADD at the centroid of each sample unit. The centroid is usually the geometric center of the area, but in cases where sample units are irregular in shape, this is the center of mass. These data are presented in a table on the updated Network Definition Map in Appendix A of this report.

Pavement condition inspections at Suwannee County Airport were performed in December 2010. Data were recorded in the field in accordance with FAA Advisory Circular 150/5380-6B "Guidelines and Procedures for Maintenance of Airport Pavements" and ASTM D 5340 "Standard Test Method for Airport Pavement Condition Index Surveys" (2004).

After the completion of data collection, the data were imported into MicroPAVER, and PCI values were calculated for the pavement sections.

3.2 Pavement Condition Index Results

According to the 2010 survey, the overall area-weighted PCI at Suwannee County Airport is 76, representing a Satisfactory overall network condition.

The Asphalt Concrete pavement of the Apron exhibited low to high severity weathering and raveling along with medium to high severity longitudinal and transversal cracking. A 170 square feet depression of medium severity in the pavement was also observed in the Apron pavement section.

The Taxiway exhibited very similar distresses to the Apron, having low to high severity weathering and raveling throughout the pavement in addition to some medium severity longitudinal and transversal cracking.

Runway 7-25 only exhibited weathering and raveling, with low severity being the most prevalent throughout the pavement, while medium and high severities were localized in smaller areas.

Appendix B contains a table and a Condition Map which depicts the PCI results by Section, and Appendix C contains a table of PCI results by Branch. Appendix I includes detailed distress data generated by MicroPAVER for each inspected sample unit.

Figure 3-1 provides the PCI distribution by rating category for Suwannee County Airport.




Figure 3-1: Network PCI Distribution by Rating Category

		5 ~ ~ ~ ~ J
Condition Rating	Total Area (ft ²)	Percent
Good	213,675	30%
Satisfactory	309,926	44%
Fair	11,495	2%
Poor	168,653	24%
Very Poor	0	0%
Serious	0	0%
Failed	0	0%

Figure 3-1a: Condition Rating Summary


Approximately 74% of the network is in Good and Satisfactory condition while 26% of the network is in Fair and Poor condition. Table 3-2 illustrates the area-weighted PCI computed individually for each pavement use.

Use	Area-Weighted PCI	Condition Rating
Runway	85	Satisfactory
Taxiway	85	Satisfactory
Apron	53	Poor
All (Weighted)	76	Satisfactory


Table 3-2: Condition by Pavement Use

Figure 3-2 presents the breakdown of PCI by range for each pavement use.


Figure 3-2: Percentage of Pavement Area within Each PCI Range by Pavement Use



(b) Taxiway



(c) Apron



4. PAVEMENT CONDITION PREDICTION

Performance prediction models or deterioration curves for PCI were used to develop a condition forecast. The performance models were developed for combinations of variables such as pavement use (runway, taxiway or apron), surface type (AC or PCC) and airport category (GA, RL, or PR). Figure 4-1 illustrates the predicted performance of pavements at Suwannee County Airport based on current condition, age since last construction and the deterioration model appropriate for the type of pavement. The figure presents the forecast for each pavement use and displays the FDOT minimum service level for General Aviation (GA) airports.




Figure 4-1: Predicted PCI by Pavement Use

Appendix D presents the tabular summary of the predicted Section PCI for each year from 2011 to 2020.

5. MAINTENANCE POLICIES AND COSTS

5.1 Policies

Maintenance and rehabilitation (M&R) policies are sets of rules used to develop repair recommendations for distresses encountered during the visual inspections.

Maintenance refers to repair-type activities that are applied to specific distress types on the pavement. These activities are preventative and/or corrective in nature and are recommended to help achieve the performance goal.

Table 5-1 provides the list of the maintenance activities used in MicroPAVER to treat specific distress types. MicroPAVER applies repairs to these distresses and adjusts the PCI based on specific rules. These repairs are used only in the first year of an analysis.

Rehabilitation is warranted when the pavement condition decreases below a critical point such that the deterioration is extensive or the rate of deterioration is so great that routine maintenance is no longer cost-efficient. This critical point is called "Critical PCI." The critical PCI levels for different pavement and branch types established in the previous SAPMP update were used in this update for the development of the M&R plan for the airport. Sections above critical PCI levels receive routine maintenances while pavements predicted to deteriorate below their respective critical PCI level during the analysis period will be identified for Major M&R. Table 5-2 gives the critical PCI levels for General Aviation Airports.

The maintenance rehabilitation policy and activity costs have been updated based on the study of readily available construction cost data at the time of this study. The costs depicted in this report are intended for planning purposes.

Surface	Distress	Severity*	Work Type	Code	Work Unit
	Alligator Crack	M, H	Patching - AC Deep	PA-AD	SqFt
	Bleeding	N/A	No Localized M&R	NONE	N/A
	Block Crack	M, H	Crack Sealing – AC	CS-AC	SqFt
	Corrugation	L, M, H	Patching - AC Deep	PA-AD	SqFt
	Depression	М, Н	Patching - AC Deep	PA-AD	SqFt
	Jet Blast	N/A	Patching - AC Deep	PA-AD	SqFt
	Joint Ref. Crack	М, Н	Crack Sealing – AC	CS-AC	Ft
	L & T Crack	М, Н	Crack Sealing – AC	CS-AC	Ft
AC	Oil Spillage	N/A	Patching - AC Shallow	PA-AS	SqFt
AC	Patching	M, H	Patching - AC Deep	PA-AD	SqFt
	Polished Agg.	N/A	No Localized M&R	NONE	N/A
		L	Surface Sealing - Rejuvenating	SS-RE	SqFt
	Raveling	М	Surface Seal - Coal Tar	SS-CT	SqFt
	-	Н	Microsurfacing	MI-AC	SqFt
	Rutting	M, H	Patching - AC Deep	PA-AD	SqFt
	Shoving	М, Н	Grinding (Localized)	GR-LL	SqFt
	Slippage Crack	N/A	Patching - AC Shallow	PA-AS	SqFt
	Swelling	М, Н	Patching - AC Deep	PA-AD	SqFt
	Blow-Up	L, M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Corner Break	M, H	Patching - PCC Full Depth	PA-PF	SqFt
	Linear Crack	М, Н	Crack Sealing – PCC	CS-PC	Ft
	Durability Creak	Н	Slab Replacement – PCC	SL-PC	SqFt
	Durability Crack	М	Patching - PCC Full Depth	PA-PF	SqFt
	Jt. Seal Damage	M, H	Joint Seal (Localized)	JS-LC	Ft
	Small Patch	М, Н	Patching - PCC Partial Depth	PA-PP	SqFt
PCC	Large Patch	М, Н	Patching - PCC Full Depth	PA-PF	SqFt
PCC	Popouts	N/A	No Localized M&R	NONE	N/A
	Pumping	N/A	No Localized M&R	NONE	N/A
	Scaling	Н	Slab Replacement – PCC	SL-PC	SqFt
	Faulting	M, H	Grinding (Localized)	GR-PP	Ft
	Shattered Slab	M, H	Slab Replacement – PCC	SL-PC	SqFt
	Shrinkage Crack	N/A	No Localized M&R	NONE	N/A
	Joint Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt
	Corner Spall	M, H	Patching - PCC Partial Depth	PA-PP	SqFt

Table 5-1: Routine Maintenance Activities for Airfield Pavements

L = Low, M = Medium, H = High

Use	Critical PCI
Runway	65
Taxiway	65
Apron	65

Table 5-2: Critical PCI for General Aviation Airports

It should be noted that critical PCI is not the same as Minimum PCI or Minimum Condition. The Minimum PCI is a value set by the user so pavement sections are rehabilitated before they fall below the set minimum. Table 5-3 gives the targeted, or desired, Minimum PCI values for runways, taxiways, and aprons of General Aviation Airports.

Table 5-3: FDOT Minimum Service Level PCI for General Aviation Airports

Minimum PCI			
Runway Taxiway Apron			
75	65	60	

Typical Major M&R activities range from overlays to reconstruction. Based on the critical PCI values in Table 5-2, the PCI trigger range when the likely activity would be a mill and resurface was 40 to 79 and reconstruction at a PCI of 39 or lower. One important concept of pavement management systems is that it is cost effective to maintain pavements that are already in good condition rather than wait for them to get worse and require more expensive rehabilitation.

Crack sealing and full-depth patching are the M&R activities recommended to repair pavements with PCI values between 80 and 90. MicroPAVER considers these as preventative M&R with their primary objective being to slow the rate of pavement deterioration. While the trigger PCI for mill and overlay has been set to 55, MicroPAVER also assigns mill and overlay to sections with a PCI greater than 55 if they exhibit some structural distress. Table 5-4 summarizes the M&R activities for General Aviation Airports based on PCI value.

	Activity	PCI Range
Maintenance	Crack Sealing and Full-Depth Patching	80 and 90
Rehabilitation	Mill and Overlay (AC) or Concrete Pavement Restoration (PCC)	40 to 79
	Reconstruction	39 and less

Table 5-4: M&R Activities for General Aviation Airports

5.2 Unit Costs

FDOT cost databases for airports and highway pavement maintenance and rehabilitation were updated from the previous SAPMP study based on current construction cost trends in order to determine meaningful costs for the program. Table 5-5 presents the unit costs summary.

5.3 M&R Activities

FDOT recognizes that although Mill and Overlay work is recommended for asphalt pavements within a PCI range from 40 to 79, it is conceivable that airports may not have adequate funding to perform this type of rehabilitation. Microsurfacing treatment is a maintenance/rehabilitation measure that can be used in lieu of asphalt pavement mill and overlay; however it should be understood that this measure is intended for short term pavement life extension. While the cost of microsurfacing is significantly lower than that of pavement mill and overlay, it is not intended to be a full rehabilitative measure for long term benefit.

Code	Name	Cost	Unit
GR-LL	Grinding (Localized for AC)	\$2.10	SqFt
PA-AL	Patching – AC Leveling	\$2.30	SqFt
PA-AS	Patching – AC Shallow	\$2.90	SqFt
PA-PF	Patching – PCC Full Depth	\$38.11	SqFt
PA-PP	Patching – PCC Partial Depth	\$19.06	SqFt
SL-PC	Slab Replacement – PCC	\$39.11	SqFt
CS-PC	Crack Sealing – PCC	\$4.24	Ft
UN-PC	Undersealing – PCC	\$3.40	Ft
CS-AC	Crack Sealing – AC	\$2.25	Ft
GR-PP	Grinding (Localized for PCC)	\$22.51	Ft
JS-LC	Joint Seal (Localized)	\$2.00	Ft
SH-LE	Shoulder Leveling	\$2.81	Ft
JS-SI	Joint Seal – Silicon	\$2.81	Ft
PA-AD	Patching – AC Deep	\$4.90	SqFt
OL-AT	Overlay – AC Thin	\$2.80	SqFt
SS-CT	Surface Seal – Coal Tar	\$0.40	SqFt
SS-FS	Surface Seal – Fog Seal	\$0.40	SqFt
SS-RE	Surface Seal – Rejuvenating	\$0.40	SqFt
ST-SB	Surface Treatment – Single Bitum.	\$0.30	SqFt
ST-SS	Surface Treatment – Slurry Seal	\$0.55	SqFt
ST-ST	Surface Treatment – Sand Tar	\$0.28	SqFt
MI-AC	Microsurfacing - AC	\$0.65	SqFt

Table 5-5: Maintenance Unit Costs for FDOT

The improvement in condition due to maintenance actions applied to specific distresses is only performed when an inspection was performed recently and only in the first year of the M&R analysis. In subsequent years, MicroPAVER calculates M&R costs based on expected unit costs for pavements in a range of PCIs. That is, for low PCI, it is expected that the repair would be significant (e.g. reconstruction) and therefore very costly.

Using available unit cost data, the Major M&R Cost by Condition table was set up as shown in Table 5-6. The cost assigned to each range of PCI is based on a Transportation Cost Report provided by Office of Planning Policy of FDOT where the unit costs of reconstruction and resurfacing of airfield pavements were included. These costs were then assigned to the appropriate PCI range to arrive at a cost per square foot necessary to restore pavements at that PCI level to new condition, i.e. a PCI of 100.

Table 5-6: M&R Activities and Unit Costs by Condition forGeneral Aviation Airports

	Activity	PCI Trigger	Cost/SqFt
Maintenance	Crack Sealing and Full-Depth Patching	90	\$0.06
		80	\$0.24 \$3.00
Rehabilitation	Mill and Overlay (AC) or	60	\$3.42
	Concrete Pavement Restoration (PCC)	50	\$6.29
		40	\$6.29
	Reconstruction	30	\$13.62
	Reconstruction	20	\$13.62

A 3% inflation rate per year was applied to the unit costs during the M&R analysis.

6. PAVEMENT REHABILITATION NEEDS ANALYSIS

Maintenance and Rehabilitation (M&R) analyses were performed after the condition data were calculated and MicroPAVER was customized with the maintenance policies and cost settings described in the previous section.

The objective of the M&R analysis is to observe the effect of different fiscal scenarios on the network condition, over a period of ten years, starting from 2011. The analysis was conducted using an unlimited budget. An unlimited budget allows all M&R needs to be identified along with the associated cost regardless of priority.

Table 6-1 presents the M&R list of immediate needs for Major M&R, i.e. Year 1 of the forecast. The importance of this listing is that it points out the major activities triggered by the current condition of the pavements.

Branch Name	Section ID	Surface Type	Section Area (ft ²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
Apron	4105	AC	151,753	\$954,526.44	43	Mill and Overlay	100
Apron	4110	AAC	16,900	\$106,301.01	44	Mill and Overlay	100
Taxiway	120	AC	4,495	\$17,953.04	58	Mill and Overlay	100
Taxiway	125	AC	3,500	\$8,148.01	64	Mill and Overlay	100
Taxiway	135	AC	3,500	\$9,103.51	63	Mill and Overlay	100
			Total	\$1,096,032.01	54		100

Table 6-1: Summary of Immediate Major M&R Needs Option No. 1

* Costs are adjusted for inflation.

FDOT recognizes that the costs attributed to the aforementioned 'Major Activity' of performing a pavement 'Mill and Overlay' may conflict with budgetary constraints. Table 6-2 presents an alternative minor rehabilitative activity to the mid-range performing pavements. The alternative activity is performing a 'Microsurfacing/Slurry Seal' to the pavement to retard the degradation of the facility until funding is available for a 'Mill and Overlay' activity.

Branch Name	Section ID	Surface Type	Section Area (ft ²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
Apron	4105	AC	151,753	\$98,639.45	43	Microsurfacing	100
Apron	4110	AAC	16,900	\$10,985.00	44	Microsurfacing	100
Taxiway	120	AC	4,495	\$2,921.75	58	Microsurfacing	100
Taxiway	125	AC	3,500	\$2,275.00	64	Microsurfacing	100
Taxiway	135	AC	3,500	\$2,275.00	63	Microsurfacing	100
			Total	\$117,096.20	54.4		100

Table 6-2: Summary of Immediate Major M&R Needs Option No. 2

* Costs are adjusted for inflation.

In addition to the immediate Major M&R needs, maintenance activities for pavement areas above critical PCI have been recommended by MicroPAVER for Year 1 and are shown in Table 6-3 below. The costs provided in Table 5-5 were used to calculate the costs associated with this work, which is intended to treat specific distress types. A more detailed table is provided in Appendix E.

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Apron	AP	4105	DEPRESSION	М	Patching - AC Deep	170.10	SqFt	\$4.90	\$833.31
Apron	AP	4105	L & T CR	Н	Crack Sealing - AC	773.80	Ft	\$2.25	\$1,741.05
Apron	AP	4105	L & T CR	М	Crack Sealing - AC	1,781.20	Ft	\$2.25	\$4,007.71
Apron	AP	4105	WEATH/RAVEL	Н	Microsurfacing - AC	1,537.90	SqFt	\$0.65	\$999.61
Apron	AP	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	27,983.30	SqFt	\$0.40	\$11,193.43
Apron	AP	4105	WEATH/RAVEL	М	Surface Seal - Coat Tar	47,041.20	SqFt	\$0.40	\$18,816.64
Apron	AP	4110	WEATH/RAVEL	М	Surface Seal - Coat Tar	3,564.00	SqFt	\$0.40	\$1,425.61
Apron	AP	4110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	13,336.00	SqFt	\$0.40	\$5,334.44
Apron	AP	4115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	22,560.20	SqFt	\$0.40	\$9,024.17
Runway 7-25	RW 7-25	6105	WEATH/RAVEL	Н	Microsurfacing - AC	20.00	SqFt	\$0.65	\$13.00
Runway 7-25	RW 7-25	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,336.00	SqFt	\$0.40	\$1,334.41
Runway 7-25	RW 7-25	6105	WEATH/RAVEL	М	Surface Seal - Coat Tar	92.00	SqFt	\$0.40	\$36.80
Runway 7-25	RW 7-25	6110	WEATH/RAVEL	М	Surface Seal - Coat Tar	20.00	SqFt	\$0.40	\$8.00
Runway 7-25	RW 7-25	6110	WEATH/RAVEL	Н	Microsurfacing - AC	5.00	SqFt	\$0.65	\$3.25
Runway 7-25	RW 7-25	6110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	18,455.00	SqFt	\$0.40	\$7,382.06
Taxiway	TW	104	WEATH/RAVEL	L	Surface Seal - Rejuvenating	296.20	SqFt	\$0.40	\$118.49
Taxiway	TW	105	L & T CR	М	Crack Sealing - AC	709.30	Ft	\$2.25	\$1,596.00
Taxiway	TW	105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	130.70	SqFt	\$0.40	\$52.27
Taxiway	TW	110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	2.30	SqFt	\$0.40	\$0.93
Taxiway	TW	115	L & T CR	М	Crack Sealing - AC	167.20	Ft	\$2.25	\$376.30
Taxiway	TW	115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	1,072.80	SqFt	\$0.40	\$429.13
Taxiway	TW	120	WEATH/RAVEL	М	Surface Seal - Coat Tar	59.90	SqFt	\$0.40	\$23.97
Taxiway	TW	120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,413.70	SqFt	\$0.40	\$1,765.48
Taxiway	TW	120	L & T CR	М	Crack Sealing - AC	77.10	Ft	\$2.25	\$173.38

Table 6-3: Summary of Year 1 Maintenance Activities

Table 6-3: Summary of Year 1 Maintenance	Activities	(Continued)
--	------------	-------------

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Taxiway	TW	125	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,497.00	SqFt	\$0.40	\$1,398.81
Taxiway	TW	125	WEATH/RAVEL	М	Surface Seal - Coat Tar	3.00	SqFt	\$0.40	\$1.20
Taxiway	TW	135	WEATH/RAVEL	Н	Microsurfacing - AC	1.00	SqFt	\$0.65	\$0.65
Taxiway	TW	135	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,499.00	SqFt	\$0.40	\$1,399.61
Taxiway	TW	145	WEATH/RAVEL	L	Surface Seal - Rejuvenating	82.00	SqFt	\$0.40	\$32.80
Taxiway	TW	150	WEATH/RAVEL	L	Surface Seal - Rejuvenating	401.10	SqFt	\$0.40	\$160.46
								Total	\$69,682.97

The 10 year forecast results are shown in Figure 6-1, illustrating the effect on pavement condition (PCI) of doing no maintenance versus having unlimited funds and performing all M&R actions based on the policies.




Figure 6-1: Budget Scenario Analysis

The following network level observations can be made from the figure above:

- The PCI will deteriorate from 76 in 2010 to 61 in ten years if no M&R activities are performed.
- The PCI will remain at or above 76 through the 10-year analysis period under the unlimited budget scenario. A 2020 PCI of 79 with this scenario is 8 PCI points higher than a "No M&R" scenario. The total cost for Major M&R over this 10-year period is about \$1.4 million.

7. MAINTENANCE AND REHABILITATION PLAN

The M&R analysis results include activities that likely exceed a typical annual budget level. These activities would need to be evaluated for feasibility and desirability based on the airport's future plans. In an effort to identify appropriate budget levels, the 10 year M&R analysis was evaluated to determine levels needed to address several specific areas: preventive maintenance, major activities for pavements in poor condition (Major M&R for PCIs less than Critical), and activities that would be desirable to preserve good pavement conditions where they exist (Major M&R for PCI greater than or equal to Critical).

Table 7-1 provides the summary results under the critical PCI unlimited funding scenario.

Year	Preventative	Major M&R	Total Year Cost
2011	\$20,568.09	\$1,096,032.00	\$1,116,600.09
2012	\$35,920.93	\$0.00	\$35,920.93
2013	\$45,485.80	\$0.00	\$45,485.80
2014	\$54,496.94	\$0.00	\$54,496.94
2015	\$67,263.80	\$0.00	\$67,263.80
2016	\$70,970.35	\$60,898.24	\$131,868.59
2017	\$82,786.96	\$0.00	\$82,786.96
2018	\$89,778.43	\$41,489.78	\$131,268.21
2019	\$108,581.77	\$0.00	\$108,581.77
2020	\$104,117.08	\$167,619.08	\$271,736.16
Total	\$679,970.15	\$1,366,039.10	\$2,046,009.25

Table 7-1: M&R Costs under Unlimited Funding Scenario

Note: Costs are adjusted for inflation.

Approximately 80% of the total Major M&R cost is required in the first year (2011). According to the 2010 inspections, the following pavement sections were in immediate need of Major M&R Activity:

- **Apron** Asphalt pavement mill and overlay activity per the FAA P-401 specification.
- **Taxiway** Asphalt pavement mill and overlay activity per the FAA P-401 specification.

The unlimited budget scenario provides the basis for estimating the total repair cost.

Appendix F provides details of M&R plan by year under the unlimited funding scenario, and the map of the 10-year M&R plan is provided in Appendix G. It is important to understand that the SAPMP is a network level tool and the M&R costs provided in this report are only for planning purposes.

8. VISUAL AIDS

8.1 System Inventory and Network Definition Drawings

The System Inventory and Network Definition CADD drawings, which show the airport pavement outline with Branch and Section boundaries and identify changes in the network pavement since the last inspection and the sampling plan, respectively, are included in Appendix A of this report.

8.2 Condition Map

A Condition Map that has been prepared based on data linked to the airport's shape file is included in Appendix B. The Condition Map graphically show the inventory and condition of the airport via color coding shown on the shape file. The coding provides a visual representation that illustrates the PCIs for each pavement section.

8.3 10-Year M&R Map

A 10-Year M&R Map that shows the summary of the M&R plan is attached in Appendix G.

8.4 Photographs

Selected digital photographs taken during the pavement inspection are provided in Appendix H to provide visual support to special pavement conditions or distress observed during the inspection of the airport.

9. RECOMMENDATIONS

Pavement condition inspections were performed at Suwannee County Airport, and a 10-year M&R plan was developed based on the unlimited funding scenario.

The following recommendations were made based on the 2010 condition inspection and M&R analysis results:

- **Apron** Asphalt pavement mill and overlay activity per the FAA P-401 specification.
- **Taxiway** Asphalt pavement mill and overlay activity per the FAA P-401 specification.

Further evaluation of these features is necessary in order to develop repair plans and timing for future budgets since these needs cannot be addressed with typical annual expenditures.

APPENDIX A

NETWORK DEFINITION MAP SYSTEM INVENTORY MAP PAVEMENT INVENTORY TABLE WORK HISTORY REPORT

LOCATION	SECTION	SAMPLE	LATITUDE	LONGITUDE
TW	145	101	30.2989262	-83.03054284
RW 7-25	6105	103	30.2986114	-83.02975284
RW 7-25	6105	106	30.29875902	-83.02930902
TW	110	136	30.29952962	-83.02911765
RW 7-25	6105	109	30.29890663	-83.0288652
RW 7-25	6105	115	30.29920186	-83.02797756
TW	135	100	30.29956588	-83.02752718
RW 7-25	6105	118	30.29934947	-83.02753373
RW 7-25	6110	121	30.29949708	-83.02708991
TW	110	127	30.30041518	-83.02645581
RW 7-25	6110	127	30.29979229	-83.02620225
RW 7-25	6110	134	30.30013669	-83.02516665
TW	125	100	30.3005064	-83.02470614
RW 7-25	6110	139	30.30038269	-83.02442693
RW 7-25	6110	146	30.30072709	-83.02339132
RW 7-25	6110	151	30.30097307	-83.02265158
RW 7-25	6110	156	30.30121906	-83.02191185
RW 7-25	6110	161	30.30146504	-83.02117211
RW 7-25	6110	166	30.30171102	-83.02043237
RW 7-25	6110	170	30.3019078	-83.01984058
RW 7-25	6110	174	30.30210438	-83.01924877
RW 7-25	6110	177	30.30225215	-83.01880493
TW	104	100	30.30293934	-83.01871349
TW	105	104	30.30269498	-83.01959886
TW	105	107	30.30239981	-83.02048657
TW	115	101	30.30162157	-83.02239531
TW	110	117	30.30139919	-83.02349689
AP	4105	100	30.30178317	-83.02304766
AP	4110	100	30.30211022	-83.02270732
TW	105	112	30.30190785	-83.02196567
TW	120	100	30.30225146	-83.02137808
AP	4110	155	30.30240503	-83.02160245
AP	4110	205	30.30252291	-83.02164661
AP	4110	253	30.30244138	-83.02233543
٩P	4110	303	30.30258514	-83.02238121
TW	150	100	30.30267815	-83.02303644
AP	4115	100	30.30266717	-83.02321704
AP	4120	101	30.3031488	-83.02331739
AP	4110	454	30.30305814	-83.02225355

NUMBER

DESIGNED: JCB DRAWN: JCB CHECKED:





10 01

145 AC 35' X 100' 1 2

DATE: MAY 2011 PLOTED: July 13, 2011 - 1:12 PM, 511: Burton, George



LEGEND

RW 13-31-	TYPICAL RUNWAY BRANCH ID
TW A	TYPICAL TAXIWAY BRANCH ID
AP S	TYPICAL APRON BRANCH ID
4105 AC 100' x 50' 5 14	SECTION NUMBER PAVEMENT TYPE TYPICAL SAMPLE UNIT INFORMATION FLEXIBLE (AC) PAVEMENT LENGTH & WIDTH RIGID (PCC) PAVEMENT NO. OF SLABS AND SLAB SIZE
	NUMBER OF SAMPLE UNITS IN SECTION NUMBER OF SAMPLE UNITS TO BE INSPECTED
605 100 ^{-AC} VAR 1 8	SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE SYSTEM INVENTORY MAP FOR CONSTRUCTION DATES.
100	INSPECTED SAMPLE UNITS. GPS COORDINATES ARE AT THE CENTROID OF THE SAMPLE UNIT.

TOTAL SAMPLES INSPECTED = 39

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.





SUWANNEE COUNTY AIRPORT SUWANNEE COUNTY, FLORIDA FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

NETWORK DEFINITION MAP



CONSTRUCTION SINCE LAST INSPECTION & ANTICIPATED CONSTRUCTION ACTIVITY

CONSTRUCTION YEAR	LOCATION	WORK TYPE / PAVEMENT SECTION							
2007	TAXIWAY	TAXIWAY AND RUN-UP PAD							
2008	TAXILANES	T-HANGARS AND TAXILANES							

LEGEND

PROJECTS	YEAR	2006
PROJECTS	YEAR	2007
PROJECTS	YEAR	2008
PROJECTS	YEAR	2009
PROJECTS	YEAR	2010
PROJECTS	YEAR	2011
PROJECTS	YEAR	2012
PROJECTS	YEAR	2013
PROJECTS	YEAR	2014
PROJECTS	YEAR	2015
PROJECTS	YEAR	2016
PROJECTS	YEAR	2017

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.



SUWANNEE COUNTY AIRPORT SUWANNEE COUNTY, FLORIDA

SYSTEM INVENTORY MAP

Branch Name	Branch ID	Branch Use	Section ID	Length (ft)	Width (ft)	True Area (ft ²)	Section Rank	Surface Type	Last Const. Date	Last Insp. Date	Sample Units in Section
Apron	AP	APRON	4105	600	250	151,753	Р	AC	1/1/1990	12/6/2010	34
Apron	AP	APRON	4110	150	130	16,900	Р	AAC	1/1/1990	12/6/2010	4
Apron	AP	APRON	4115	950	25	22,565	Р	AC	3/1/2008	12/6/2010	6
Apron	AP	APRON	4120	250	103	26,543	Р	AC	7/1/2006	7/1/2006	5
Runway 7-25	RW 7-25	RUNWAY	6105	1,000	75	75,000	Р	AC	1/1/2006	12/6/2010	20
Runway 7-25	RW 7-25	RUNWAY	6110	3,000	75	225,000	Р	AC	1/1/2006	12/6/2010	60
Taxiway	TW	TAXIWAY	104	60	50	3,600	Р	AC	1/1/2004	12/6/2010	1
Taxiway	TW	TAXIWAY	105	1,400	35	49,391	Р	AAC	1/1/1990	12/6/2010	14
Taxiway	TW	TAXIWAY	110	2,842	35	99,832	Р	AC	1/1/2004	12/6/2010	29
Taxiway	TW	TAXIWAY	115	270	45	12,970	Р	AC	1/1/1990	12/6/2010	3
Taxiway	TW	TAXIWAY	120	100	40	4,495	Р	AC	1/1/1990	12/6/2010	1
Taxiway	TW	TAXIWAY	125	100	35	3,500	Р	AC	1/1/2000	12/6/2010	2
Taxiway	TW	TAXIWAY	135	100	35	3,500	Р	AC	1/1/2004	12/6/2010	2
Taxiway	TW	TAXIWAY	145	100	35	3,500	Р	AC	1/1/2004	12/6/2010	2
Taxiway	TW	TAXIWAY	150	260	20	5,200	Р	AC	1/1/1990	12/6/2010	1

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

*Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

Date:06/	21/2011	Work H	1 of 3		
Network: 24	Ll Br	anch: AP (APRON)			Section: 4105 Surface: AC
	1/1990 Use: AF	,		Width:	250.00 Ft True Area: 151,753.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1990	IMPORTED	BUILT		3.00	True 1990: 3" P401 ON 5" P211 ON 12" E4 COMP. SUBGRADE
Network: 24 L.C.D.: 01/07	IJ Br I/1990 Use: AF	anch: AP (APRON) PRON Rank: P Length:		Width:	Section: 4110 Surface: AAC 130.00 Ft True Area: 16.900.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1990 01/01/1990	IMPORTED IMPORTED	OVERLAY BUILT		3.00	True EXISTING: AC PAVEMENT True 1990: 3" P401 OVERLAY
Network: 24 L.C.D.: 03/07	IJ Br 1/2008 Use: AF	anch: AP (APRON) PRON Rank: PLength:		Width:	Section: 4115 Surface: AC 25.00 Ft True Area: 22.565.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
03/01/2008	NC-AC	New Construction - AC	\$0	0.00	True
Network: 24 L.C.D.: 07/07	IJ Br I/2006 Use: AF	anch: AP (APRON) PRON Rank: P Length:		Width:	Section: 4120 Surface: AC 103.00 Ft True Area: 26.543.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
07/01/2006	INITIAL	Initial Construction	\$0	0.00	True
Network: 24 L.C.D.: 01/01	IJ Br 1/2006 Use: RI	anch: RW 7-25 (RUNWA JNWAY Rank: P Length:	•	Width:	Section: 6105 Surface: AC 75.00 Ft True Area: 75.000.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/2006 01/01/1990	OL-AS IMPORTED	Overlay - AC Structural BUILT	\$0	0.00 4.00	True True 1990: 4" P401 ON 6" P211 ON 12" E4 COMP. SUBGRADE
Network: 24 L.C.D.: 01/07	IJ Br 1/2006 Use: RI	anch: RW 7-25 (RUNWA JNWAY Rank: P Length:		Width:	Section: 6110 Surface: AC 75.00 Ft True Area: 225.000.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/2006 01/01/1990 01/01/1983	OL-AS IMPORTED IMPORTED	Overlay - AC Structural BUILT OVERLAY	\$0	0.00	True 1990: SLURRY SEALCOAT True EXISTING: 1983 AC PAVEMENT
Network: 24 L.C.D.: 01/07	IJ Br 1/2004 Use: TA	anch: TW (TAXIWA XXIWAY Rank: P Length:	•	Width:	Section: 104 Surface: AC 50.00 Ft True Area: 3,600.00 SqF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/2004	INITIAL	Initial Construction	\$0	0.00	True
Network: 24 L.C.D.: 01/07	IJ Br I/1990 Use: T <i>F</i>	anch: TW (TAXIWA XIWAY Rank: P Length:	•	Width:	Section: 105 Surface: AAC 35.00 Ft True Area: 49.391.00 SaF
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major M&R Comments
01/01/1990	IMPORTED	BUILT		3.00	True 1990: 3" P401 ON 5" P211 ON 12" E4 COMP. SUBGRADE

Date:06/21/2011 Work History Report 2 of 3							
Network: 24	4J Bra	anch: TW (TAXIWA	Y)	Width:	Section: 110 Surface: AC		
L.C.D.: 01/07	1/2004 Use: TA	XXIWAY Rank: PLength:	2,842.00 Ft		35.00 Ft True Area: 99,832.00 SqF		
Work	Work	Work	Cost	Thickness	Major		
Date	Code	Description		(in)	M&R Comments		
01/01/2004	INITIAL	Initial Construction	\$0	0.00	True		
Network: 24	4J Bra	anch: TW (TAXIWA	Y)	Width:	Section: 115 Surface: AC		
L.C.D.: 01/0	1/1990 Use: TA	XIWAY Rank: PLength:	270.00 Ft		45.00 Ft True Area: 12.970.00 SaF		
Work	Work	Work	Cost	Thickness	Major		
Date	Code	Description		(in)	M&R Comments		
01/01/1990	IMPORTED	BUILT		3.50	True 1990: 3.5" P401 ON 6" P211		
Network: 24 L.C.D.: 01/07	1/1990 Use: TA	Longtin	Y) 100.00 Ft	Width:	Section: 120 Surface: AC 40.00 Ft True Area: 4,495.00 SqF		
Work	Work	Work	Cost	Thickness	Major		
Date	Code	Description		(in)	M&R Comments		
01/01/1990	IMPORTED	BUILT		3.00	True 1990: 3" P401 ON 5" P211 ON 12" E-4 COMP. SUBGRADE		
Network: 24	4J Bra	anch: TW (TAXIWA	Y)	Width:	Section: 125 Surface: AC		
L.C.D.: 01/0	1/2000 Use: TA	XIWAY Rank: PLength:	100.00 Ft		35.00 Ft True Area: 3.500.00 SaF		
Work	Work	Work	Cost	Thickness	Major		
Date	Code	Description		(in)	M&R Comments		
01/01/2000	INITIAL	Initial Construction	\$0	0.00	True		
Network: 24 L.C.D.: 01/0	I/2004 Use: TA	anch:TW (TAXIWA XIWAY Rank:PLength:	Y) 100.00 Ft	Width:	Section: 135 Surface: AC 35.00 Ft True Area: 3.500.00 SqF		
Work	Work	Work	Cost	Thickness	Major		
Date	Code	Description		(in)	M&R Comments		
01/01/2004	INITIAL	Initial Construction	\$0	0.00	True		
Network: 24	4J Bra	anch: TW (TAXIWA	Y)	Width:	Section: 145 Surface: AC		
L.C.D.: 01/0	1/2004 Use: TA	XIWAY Rank: PLength:	100.00 Ft		35.00 Ft True Area: 3.500.00 SaF		
Work	Work	Work	Cost	Thickness	Major		
Date	Code	Description		(in)	M&R Comments		
01/01/2004	INITIAL	Initial Construction	\$0	0.00	True		
Network: 24 L.C.D.: 01/0	4J Bra 1/1990 Use: TA	Length		Width:	Section: 150 Surface: AC 20.00 Ft True Area: 5.200.00 SaF		
Work	Work	Work	Cost	Thickness	Major		
Date	Code	Description		(in)	M&R Comments		
01/01/1990	IMPORTED	BUILT			True EST 1990 AC PAVEMENT		

Work History Report

Pavement Database:

Summary:

Work Description	Section Count	Area Total (SqFt)	Thickness Avg (in)	Thickness STD (in)
BUILT	8	540,709.00	3.25	.42
Initial Construction	6	140,475.00	.00	.00
New Construction - AC	1	22,565.00	.00	
OVERLAY	2	241,900.00		
Overlay - AC Structural	2	300,000.00	.00	.00

STD = Standard Deviation

APPENDIX B

2011 CONDITION MAP PAVEMENT CONDITION INDEX TABLE

$ \begin{array}{c} $	105 35' X 100' 3 14 120 AC VR 1 1 1 1 1 1 1 1 1 1 1 1 1
	GRAPHIC SCALE IN FEET 0 75 150 300
Image: Second and the second and th	





<u>LEGEND</u>



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.





SUWANNEE COUNTY AIRPORT SUWANNEE COUNTY, FLORIDA FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

2011 CONDITION MAP

Branch Name	Branch ID	Branch Use	Section ID	True Area (ft ²)	Section Rank	Surface Type	Total Samples Inspected	Total Samples	PCI	PCI Category
Apron	AP	APRON	4105	151,753	Р	AC	6	34	44	Poor
Apron	AP	APRON	4110	16,900	Р	AAC	1	4	45	Poor
Apron	AP	APRON	4115	22,565	Р	AC	1	6	72	Satisfactory
Apron	AP	APRON	4120	26,543	Р	AC	0	5	100	Good
Runway 7-25	RW 7-25	RUNWAY	6105	75,000	Р	AC	5	20	88	Good
Runway 7-25	RW 7-25	RUNWAY	6110	225,000	Р	AC	12	60	85	Satisfactory
Taxiway	TW	TAXIWAY	104	3,600	Р	AC	1	1	86	Good
Taxiway	TW	TAXIWAY	105	49,391	Р	AAC	3	14	80	Satisfactory
Taxiway	TW	TAXIWAY	110	99,832	Р	AC	3	29	92	Good
Taxiway	TW	TAXIWAY	115	12,970	Р	AC	1	3	76	Satisfactory
Taxiway	TW	TAXIWAY	120	4,495	Р	AC	1	1	59	Fair
Taxiway	TW	TAXIWAY	125	3,500	Р	AC	1	2	65	Fair
Taxiway	TW	TAXIWAY	135	3,500	Р	AC	1	2	64	Fair
Taxiway	TW	TAXIWAY	145	3,500	Р	AC	1	2	91	Good
Taxiway	TW	TAXIWAY	150	5,200	Р	AC	1	1	86	Good

Table B-1: Pavement Condition Index

Note: If a new construction, then survey date = last construction date and PCI is set to 100 by MicroPAVER.

*Sections not surveyed due to reasons such as re-sectioning, no escort, not accessible at the time of survey.

APPENDIX C

BRANCH CONDITION REPORT SECTION CONDITION REPORT

Date: 6 /1/2011

Branch Condition Report

Pavement Database: NetworkID: 24J

1 of 2

Branch ID	Number of Sections	Sum Section Length	Avg Section Width	True Area (SqFt)	Use	Average PCI	PCI Standard	Weighted Average
		(Ft)	(Ft)			FOI	Deviation	PCI
AP (APRON)	4	1,950.00	127.00	217,761.00	APRON	65.25	22.99	53.80
RW 7-25 (RUNWAY 7-25)	2	4,000.00	75.00	300,000.00	RUNWAY	86.50	1.50	85.75
TW (TAXIWAY)	9	5,232.00	36.67	185,988.00	TAXIWAY	77.67	11.67	85.56

Date: 6 /1/2011

Branch Condition Report

Pavement Database:

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	4	217,761.00	65.25	22.99	53.80
RUNWAY	2	300,000.00	86.50	1.50	85.75
TAXIWAY	9	185,988.00	77.67	11.67	85.56
AII	15	703,749.00	75.53	16.43	75.82

STD = Standard Deviation

2 of 2

Date: 6 /1/2011			Section Dent Data	b n Conc		n Re kID: 24	-		1 of	1 of 2		
Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI		
AP (APRON)	4105	01/01/1990	AC	APRON	Ρ	0	151,753.00	12/06/2010	20	44.00		
AP (APRON)	4110	01/01/1990	AAC	APRON	Р	0	16,900.00	12/06/2010	20	45.00		
AP (APRON)	4115	03/01/2008	AC	APRON	Р	0	22,565.00	12/06/2010	2	72.00		
AP (APRON)	4120	07/01/2006	AC	APRON	Р	0	26,543.00	07/01/2006	0	100.00		
RW 7-25 (RUNWAY 7-25)	6105	01/01/2006	AC	RUNWAY	Р	0	75,000.00	12/06/2010	4	88.00		
RW 7-25 (RUNWAY 7-25)	6110	01/01/2006	AC	RUNWAY	Р	0	225,000.00	12/06/2010	4	85.00		
TW (TAXIWAY)	104	01/01/2004	AC	TAXIWAY	Р	0	3,600.00	12/06/2010	6	86.00		
TW (TAXIWAY)	105	01/01/1990	AAC	TAXIWAY	Р	0	49,391.00	12/06/2010	20	80.00		
TW (TAXIWAY)	110	01/01/2004	AC	TAXIWAY	Р	0	99,832.00	12/06/2010	6	92.00		
TW (TAXIWAY)	115	01/01/1990	AC	TAXIWAY	Р	0	12,970.00	12/06/2010	20	76.00		
TW (TAXIWAY)	120	01/01/1990	AC	TAXIWAY	Р	0	4,495.00	12/06/2010	20	59.00		
TW (TAXIWAY)	125	01/01/2000	AC	TAXIWAY	Р	0	3,500.00	12/06/2010	10	65.00		
TW (TAXIWAY)	135	01/01/2004	AC	TAXIWAY	Р	0	3,500.00	12/06/2010	6	64.00		
TW (TAXIWAY)	145	01/01/2004	AC	TAXIWAY	Р	0	3,500.00	12/06/2010	6	91.00		
TW (TAXIWAY)	150	01/01/1990	AC	TAXIWAY	Р	0	5,200.00	12/06/2010	20	86.00		

Date: 6 /1/2011

Section Condition Report

2 of 2

Pavement Database:

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
0-02	1.00	49,108.00	2	86.00	14.00	87.13
03-05	4.00	300,000.00	2	86.50	1.50	85.75
06-10	6.80	113,932.00	5	79.60	12.50	90.09
16-20	20.00	240,709.00	6	65.00	16.65	54.37
All	10.93	703,749.00	15	75.53	16.43	75.82

APPENDIX D

PAVEMENT CONDITION PREDICTION TABLE PREDICTED PCI BY PAVEMENT USE GRAPH

Duanah Nama	Buonsh ID	Section	Current					PCI Fo	recast				
Branch Name	Branch ID	ID	PCI	2011	2012	2013	2014	2015	2016	2017	2017 2018 2019	2020	
Apron	AP	4105	44	43	42	40	39	37	36	34	33	32	30
Apron	AP	4110	45	44	43	42	41	40	38	37	36	35	34
Apron	AP	4115	72	71	70	68	67	65	64	62	61	60	58
Apron	AP	4120	100	93	91	90	88	87	85	84	83	81	80
Runway 7-25	RW 7-25	6105	88	87	86	84	83	81	80	78	77	75	74
Runway 7-25	RW 7-25	6110	85	84	83	81	80	78	77	75	74	72	71
Taxiway	TW	104	86	85	83	82	80	78	76	75	73	71	70
Taxiway	TW	105	80	79	77	76	74	72	70	69	67	65	63
Taxiway	TW	110	92	91	89	88	86	84	82	81	79	77	76
Taxiway	TW	115	76	75	73	72	70	68	66	65	63	61	60
Taxiway	TW	120	59	58	56	55	53	51	49	48	46	44	43
Taxiway	TW	125	65	64	62	61	59	57	55	54	52	50	49
Taxiway	TW	135	64	63	61	60	58	56	54	53	51	49	48
Taxiway	TW	145	91	90	88	87	85	83	81	80	78	76	75
Taxiway	TW	150	86	85	83	82	80	78	76	75	73	71	70

Table D-1: Pavement Condition Prediction




Figure D-1: Predicted PCI by Pavement Use

APPENDIX E

YEAR 1 MAINTENANCE ACTIVITIES TABLE

Table E-1: Year	1 Maintenance	Activities
-----------------	----------------------	------------

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Apron	AP	4105	DEPRESSION	М	Patching - AC Deep	170.10	SqFt	\$4.90	\$833.31
Apron	AP	4105	L & T CR	Н	Crack Sealing - AC	773.80	Ft	\$2.25	\$1,741.05
Apron	AP	4105	L & T CR	М	Crack Sealing - AC	1,781.20	Ft	\$2.25	\$4,007.71
Apron	AP	4105	WEATH/RAVEL	Н	Microsurfacing - AC	1,537.90	SqFt	\$0.65	\$999.61
Apron	AP	4105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	27,983.30	SqFt	\$0.40	\$11,193.43
Apron	AP	4105	WEATH/RAVEL	М	Surface Seal - Coat Tar	47,041.20	SqFt	\$0.40	\$18,816.64
Apron	AP	4110	WEATH/RAVEL	М	Surface Seal - Coat Tar	3,564.00	SqFt	\$0.40	\$1,425.61
Apron	AP	4110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	13,336.00	SqFt	\$0.40	\$5,334.44
Apron	AP	4115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	22,560.20	SqFt	\$0.40	\$9,024.17
Runway 7-25	RW 7-25	6105	WEATH/RAVEL	Н	Microsurfacing - AC	20.00	SqFt	\$0.65	\$13.00
Runway 7-25	RW 7-25	6105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,336.00	SqFt	\$0.40	\$1,334.41
Runway 7-25	RW 7-25	6105	WEATH/RAVEL	М	Surface Seal - Coat Tar	92.00	SqFt	\$0.40	\$36.80
Runway 7-25	RW 7-25	6110	WEATH/RAVEL	М	Surface Seal - Coat Tar	20.00	SqFt	\$0.40	\$8.00
Runway 7-25	RW 7-25	6110	WEATH/RAVEL	Н	Microsurfacing - AC	5.00	SqFt	\$0.65	\$3.25
Runway 7-25	RW 7-25	6110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	18,455.00	SqFt	\$0.40	\$7,382.06
Taxiway	TW	104	WEATH/RAVEL	L	Surface Seal - Rejuvenating	296.20	SqFt	\$0.40	\$118.49
Taxiway	TW	105	L & T CR	М	Crack Sealing - AC	709.30	Ft	\$2.25	\$1,596.00
Taxiway	TW	105	WEATH/RAVEL	L	Surface Seal - Rejuvenating	130.70	SqFt	\$0.40	\$52.27
Taxiway	TW	110	WEATH/RAVEL	L	Surface Seal - Rejuvenating	2.30	SqFt	\$0.40	\$0.93
Taxiway	TW	115	L & T CR	М	Crack Sealing - AC	167.20	Ft	\$2.25	\$376.30
Taxiway	TW	115	WEATH/RAVEL	L	Surface Seal - Rejuvenating	1,072.80	SqFt	\$0.40	\$429.13
Taxiway	TW	120	WEATH/RAVEL	М	Surface Seal - Coat Tar	59.90	SqFt	\$0.40	\$23.97
Taxiway	TW	120	WEATH/RAVEL	L	Surface Seal - Rejuvenating	4,413.70	SqFt	\$0.40	\$1,765.48
Taxiway	TW	120	L & T CR	М	Crack Sealing - AC	77.10	Ft	\$2.25	\$173.38
Taxiway	TW	125	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,497.00	SqFt	\$0.40	\$1,398.81

Branch Name	Branch ID	Section ID	Distress Description	Distress Severity	Work Description	Work Quantity	Work Unit	Unit Cost	Work Cost
Taxiway	TW	125	WEATH/RAVEL	М	Surface Seal - Coat Tar	3.00	SqFt	\$0.40	\$1.20
Taxiway	TW	135	WEATH/RAVEL	Н	Microsurfacing - AC	1.00	SqFt	\$0.65	\$0.65
Taxiway	TW	135	WEATH/RAVEL	L	Surface Seal - Rejuvenating	3,499.00	SqFt	\$0.40	\$1,399.61
Taxiway	TW	145	WEATH/RAVEL	L	Surface Seal - Rejuvenating	82.00	SqFt	\$0.40	\$32.80
Taxiway	TW	150	WEATH/RAVEL	L	Surface Seal - Rejuvenating	401.10	SqFt	\$0.40	\$160.46
								Total	\$54,768.18

Table E-1: Year 1 Maintenance Activities (Continued)

APPENDIX F

MAJOR M&R PLAN BY YEAR UNDER UNLIMITED FUNDING SCENARIO TABLE

Table F-1: Major M&R Plan by Year under Unlimited Funding Scenario

Year	Branch Name	Section ID	Surface Type	Section Area (ft ²)	Major M&R Costs*	PCI Before M&R	M&R Activity	PCI After M&R
2011	Apron	4105	AC	151,753. SqFt	\$ 954,526.44	43	Mill and Overlay	100
2011	Apron	4110	AAC	16,900. SqFt	\$ 106,301.01	44	Mill and Overlay	100
2011	Taxiway	120	AC	4,495. SqFt	\$ 17,953.04	58	Mill and Overlay	100
2011	Taxiway	125	AC	3,500. SqFt	\$ 8,148.01	64	Mill and Overlay	100
2011	Taxiway	135	AC	3,500. SqFt	\$ 9,103.51	63	Mill and Overlay	100
2011	Apron	4115	AC	22,565. SqFt	\$ 60,898.24	64	Mill and Overlay	100
2011	Taxiway	115	AC	12,970. SqFt	\$ 41,489.78	63	Mill and Overlay	100
2016	Taxiway	105	AC	49,391. SqFt	\$ 167,519.08	63	Mill and Overlay	100
				Total	\$1,366,039.11	58		100

* Costs are adjusted for inflation.

APPENDIX G

10-YEAR M&R MAP

	FY 2011 APRON: £105 NLL AND OVERLAY \$0.95M FY 2011 Training FY 2011 Training S0.02M
	GRAPHIC SCALE IN FEET
NUMBER DATE REVISIONS DESIGNED: JCB DRAVNE JCB CHECKED: DATE: MAY 2011 PLORE-Service JCB DRAVNE JCB CHECKED: DATE: MAY 2011	





LEGEND

RW 13-31-	TYPICAL	RUNWAY	BRANCH	ID
TW A	TYPICAL	TAXIWAY	BRANCH	ID
AP S	TYPICAL	APRON E	BRANCH I	D

YEAR		
	2011	
	2012	
	2013	
	2014	
	2015	
	2016	
	2017	
	2018	
	2019	
	2020	

	MICROSURFACING
	MILL AND OVERLAY
	RECONSTRUCTION
6000	CONCRETE PAVEMENT RESTORATION



RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS.






SUWANNEE COUNTY AIRPORT SUWANNEE COUNTY, FLORIDA FLORIDA DEPARTMENT OF TRANSPORTATION - AVIATION OFFICE

10 -YEAR M & R MAP

APPENDIX H

PHOTOGRAPHS



Runway 7-25, Section 6105, Sample Unit 115 – Low severity (48) Longitudinal and Transverse Cracking, low and high severity (52) Weathering and Raveling.



Taxiway, Section 105, Sample Unit 104 – Low and medium severity (48) Longitudinal and Transverse Cracking, low severity (56) Swelling.



Taxiway, Section 120, Sample Unit 100 - Low and medium severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Weathering and Raveling.



Runway 7-25, Section 6105, Sample Unit 103 – Low severity (48) Longitudinal and Transverse Cracking, low and medium severity (52) Weathering and Raveling.



Runway 7-25, Section 6110, Sample Unit 146 - Low severity (48) Longitudinal and Transverse Cracking, low severity (52) Weathering and Raveling.

APPENDIX I

PCI RE-INSPECTION REPORT

Re-inspection Report

FDOT Report Generated Date: 5/31/2011 Site Name:

Network: 24J	Name: SUWANNEE COUNTY AIRPORT					
Branch: AP	Name: APRON		Use: APRON	Area:	217,761.008qFt	
Section: 4105 Surface: AC Area: 151,753.008qFt Shoulder: Street 7 Section Comments:	of 4 From: - Family: FDOT-GA-AP-AC Length: 600.00Ft Type: Grade: 0.00		To: - Category: Vidth: 250.00Ft	: Rank: P	Last Const.: 1/1/1990	
Last Insp. 12/6/2010 Conditions: PCI:44.00 Inspection Comments:	Total Samples: 34 Sur	veyed: 6				
Sample Number: 100 Sample Comments:	Туре: к	Area:	5,000.00SqFt	PCI = 35		
52 WEATH/RAVEL		L	250.00 SqI	Ft Comments	:	
48 L & T CR		Н	40.00 Ft	Comments	:	
48 L & T CR		М	8.00 Ft	Comments	:	
48 L & T CR		L	289.00 Ft	Comments	:	
52 WEATH/RAVEL		М	3,000.00 SqI			
Sample Number: 155 Sample Comments:	Туре: к	Area:	5,000.008qFt	PCI = 61		
48 L & T CR		L	352.00 Ft	Comments	:	
48 L & T CR		Н	79.00 Ft	Comments	:	
52 WEATH/RAVEL		\mathbf{L}	550.00 SqI	Ft Comments	:	
48 L & T CR		М	71.00 Ft	Comments	:	
Sample Number: 201 Sample Comments:	Туре: к	Area:	5,000.00SqFt	PCI = 34		
48 L & T CR		М	52.00 Ft	Comments	:	
52 WEATH/RAVEL		М	1,690.00 SqH	Ft Comments	:	
43 BLOCK CR		L	1,600.00 SqH	Ft Comments	:	
52 WEATH/RAVEL		H	139.00 SqH		:	
52 WEATH/RAVEL		L	1,200.00 SqH	Ft Comments	:	
48 L & T CR		L	81.00 Ft	Comments	:	
Sample Number: 253 Sample Comments:	Туре: к	Area:	5,000.005qFt	PCI = 31		
52 WEATH/RAVEL		М	4,000.00 SqI	Ft Comments	:	
52 WEATH/RAVEL		L	50.00 Sql			
48 L & T CR		M	125.00 Ft	Comments		
52 WEATH/RAVEL		Н	152.00 SqI	Ft Comments	:	
48 L & T CR		L	241.00 Ft	Comments		
Sample Number: 303 Sample Comments:	Туре: к	Area:	5,000.008qFt	PCI = 51		
48 L & T CR		М	30.00 Ft	Comments	:	
52 WEATH/RAVEL		М	916.00 SqI		:	
56 SWELLING		L	1.00 SqH	Ft Comments	:	
48 L & T CR		L	487.00 Ft	Comments	:	
52 WEATH/RAVEL		L	400.00 SqI			
48 L & T CR		Н	40.00 Ft	Comments	:	
Sample Number: 454	Type: R	Area:	5,000.008qFt	PCI = 52		
Sample Comments:		3.6				
48 L & T CR		М	80.00 Ft	Comments	•	

FDOT Report Generated Date: 5/31/2011 Site Name:

52 WEATH/RAVEL 52 WEATH/RAVEL 48 L & T CR	M L L	60.00 SqFt 3,300.00 SqFt 295.00 Ft 25 00 SqFt	Comments: Comments: Comments:
45 DEPRESSION	М	25.00 SqFt	Comments:
52 WEATH/RAVEL	Н	25.00 SqFt	Comments:

Re-inspection Report

FDOT Report Generated Date: 5/31/2011 Site Name:

Network: 24J	Name: SUWANNEE COUNTY	AIRPORT			
Branch: AP	Name: APRON		Use: APRON	Area:	217,761.008qFt
Section: 4110 Surface: AAC Area: 16,900.008qFt Shoulder: Street 7 Section Comments:	of 4 From: - Family: FDOT-GA-AP-AAC Length: 150.00 Fype: Grade: 0.00		To: - ne: Category: idth: 130.00Ft	Rank: P	Last Const.: 1/1/1990
Last Insp. 12/6/2010 Conditions: PCI:45.00 Inspection Comments:	Total Samples: 4	Surveyed: 1			
Sample Number: 100 Sample Comments: 48 L & T CR 52 WEATH/RAVEL 52 WEATH/RAVEL 50 PATCHING	Type: R	Area: L M L	4,225.008qFt 584.00 Ft 891.00 SqFt 3,334.00 SqFt 260.00 SqFt	PCI = 45 Comments Comments Comments Comments	:

Network: 24J	Name: SUWANNEE COUNT	AIRPORT			
Branch: AP	Name: APRON		Use: APRON	Area:	217,761.008qFt
Section: 4115 Surface: AC Area: 22,565.008qFt	of 4 From: - Family: FDOT-GA-AP-AC Length: 950.00		To: - Category: 25.00Ft	Rank: P	Last Const.: 3/1/2008
Shoulder: Street 7 Section Comments: Last Insp. 12/6/2010 Conditions: PCI:72.00 Inspection Comments:		Lanes: 0 Surveyed: 1			

FDOT Report Generated Date: 5/31/2011 Site Name:

Network: 24J	Name: SUWANNEE COUNTY AIRPO	ORT			
Branch: AP	Name: APRON		Use: APRON	Area:	217,761.008qFt
Section: 4120 Surface: AC Area: 26,543. Shoulder: Section Comments:		Zone: Width: Lanes: 0	To: - Category: 103.00Ft	Rank: P	Last Const.: 7/1/2006
Conditions: PCI:	1	yed: 0			

Sample Number: <NO SAMPLE RECORDS> Type: Area: 0.00

FDOT	
Report Generated Date:	5/31/2011
Site Name:	

Network: 24J	Name: SUWANNEE COUNTY AIR	RPORT			
Branch: RW 7-25	Name: RUNWAY 7-25		Use: RUNV	WAY Area:	300,000.008qFt
Section: 6105 Surface: AC Area: 75,000.008qFt Shoulder: Street T Section Comments:	of 2 From: - Family: FDOT-GA-RW-AC Length: 1,000.00Ft Sype: Grade: 0.00		To: - one: Categor Vidth: 75.00Ft	ry: Rank: P	Last Const.: 1/1/2006
Last Insp. 12/6/2010 Conditions: PCI:88.00 Inspection Comments:	Total Samples: 20 Sur	veyed: 5			
Sample Number: 103	Туре: к	Area:	3,750.008qFt	PCI = 81	
Sample Comments: 48 L & T CR		L	31.00 F	t Comments	3:
52 WEATH/RAVEL		М	23.00 S	qFt Comments	5:
52 WEATH/RAVEL		L	361.00 S	qFt Comments	3:
Sample Number: 106 Sample Comments:	Type: R	Area:	3,750.008qFt	PCI = 87	
52 WEATH/RAVEL		L	80.00 S	-	5:
50 PATCHING		L	0.25 S		
56 SWELLING		L	8.00 S		
48 L & T CR		L	40.00 F	t Comments	3:
Sample Number: 109 Sample Comments:	Туре: к	Area:	3,750.00SqFt	PCI = 97	
52 WEATH/RAVEL		L	43.00 S	qFt Comments	3:
Sample Number: 115 Sample Comments:	Туре: к	Area:	3,750.008qFt	PCI = 83	
52 WEATH/RAVEL		L	150.00 S	qFt Comments	5:
48 L & T CR		L	33.00 F	t Comments	5 :
52 WEATH/RAVEL		Н	5.00 S	qFt Comments	3:
Sample Number: 118 Sample Comments:	Туре: к	Area:	3,750.008qFt	PCI = 91	
52 WEATH/RAVEL		L	200.00 S		3:
50 PATCHING		L	0.50 S	qFt Comments	3:

FDOT	
Report Generated Date:	5/31/2011
Site Name:	

Network: 24J	Name: SUWANNEE COUNTY AI	RPORT			
Branch: RW 7-25	Name: RUNWAY 7-25		Use: RUNWAY	Area:	300,000.008qFt
Section: 6110 Surface: AC Area: 225,000.008qFt Shoulder: Street T Section Comments:	of 2 From: - Family: FDOT-GA-RW-AC Length: 3,000.00Ft Type: Grade: 0.00	Zor Wi Lanes: 0	To: - te: Category: dth: 75.00Ft	Rank: P	Last Const.: 1/1/2006
Last Insp. 12/6/2010 Conditions: PCI:85.00 Inspection Comments:	Total Samples: 60 Sur	veyed: 12			
Sample Number: 121	Туре: к	Area:	3,750.008qFt	PCI = 88	
Sample Comments: 52 WEATH/RAVEL 48 L & T CR		L L	212.00 SqFt 27.00 Ft	Comments Comments	
Sample Number: 127	Туре: к	Area:	3,750.008qFt	PCI = 87	
Sample Comments: 52 WEATH/RAVEL 48 L & T CR		L L	75.00 SqFt 8.00 Ft	Comments Comments	
52 WEATH/RAVEL		Н	1.00 SqFt	Comments	
Sample Number: 134 Sample Comments:	Type: R	Area:	3,750.008qFt	PCI = 86	
50 PATCHING		L	0.50 SqFt	Comments	:
52 WEATH/RAVEL		${ m L}$	107.00 SqFt	Comments	:
48 L & T CR		L	73.00 Ft	Comments	:
Sample Number: 139 Sample Comments:	Туре: к	Area:	3,750.008qFt	PCI = 89	
52 WEATH/RAVEL		${ m L}$	50.00 SqFt	Comments	
48 L & T CR		L	84.00 Ft	Comments	:
Sample Number: 146 Sample Comments:	Туре: к	Area:	3,750.008qFt	PCI = 86	
52 WEATH/RAVEL 48 L & T CR		L L	91.00 SqFt 103.00 Ft	Comments Comments	
Sample Number: 151	Туре: к	Area:	3,750.008qFt	PCI = 91	
Sample Comments: 48 L & T CR		L	24.00 Ft	Comments	:
52 WEATH/RAVEL		L	104.00 SqFt	Comments	
Sample Number: 156 Sample Comments:	Туре: к	Area:	3,750.008qFt	PCI = 83	
52 WEATH/RAVEL 48 L & T CR		L L	130.00 SqFt 148.00 Ft	Comments Comments	
Sample Number: 161 Sample Comments:	Туре: к	Area:	3,750.008qFt	PCI = 87	
48 L & T CR 52 WEATH/RAVEL		L L	76.00 Ft 243.00 SqFt	Comments Comments	
Sample Number: 166	Туре: к	Area:	3,750.008qFt	PCI = 89	

Site Maine.						
Sample Comments:						
48 L & T CR		L	64.00	Ft	Comments:	
52 WEATH/RAVEL		L	100.00	SqFt	Comments:	
ample Number: 170 ample Comments:	Туре: к	Area:	3,750.008qFt		PCI = 86	
56 SWELLING		L	12.00	SqFt	Comments:	
48 L & T CR		L	93.00		Comments:	
52 WEATH/RAVEL		L	70.00	SqFt	Comments:	
ample Number: 174 ample Comments:	Type: R	Area:	3,750.008qFt		PCI = 83	
48 [°] L & T CR		L	84.00	Ft	Comments:	
2 WEATH/RAVEL		L	613.00	SqFt	Comments:	
Sample Number: 177 Sample Comments:	Туре: к	Area:	3,750.008qFt		PCI = 71	
52 WEATH/RAVEL		М	4.00	SqFt	Comments:	
48 L & T CR		L	51.00	-	Comments:	
52 WEATH/RAVEL		L	1,896.00		Comments:	

Network:	24J	Name: SUWANNEE C	OUNTY AIRPORT				
Branch:	TW	Name: TAXIWAY			Use: TAXIWAY	Area:	185,626.008qFt
Section:	104	of 9 From: -			То: -		Last Const.: 1/1/2004
Surface:	AC	Family: FDOT-GA-	ГW-AC	Zone:	Category:	Rank: P	
Area:	3,600.00SqFt	Length:	60.00Ft	Width:	50.00Ft		
Shoulder: Section Comm	Street T	Sype: Grade: 0	.00 Lane	s: 0			
Last Insp.	12/6/2010	Total Samples: 1	Surveyed:	1			
Inspection Con Sample Nu	nments:	Туре: к	Area	: 3,500.	.005qFt	PCI = 86	
Conditions Inspection Con- Sample Nu Sample Comm 52 WEAT	nments: nmber: 100 nents:	Туре: к	Area		008qFt 288.00 SqFt	PCI = 86 Comments	:

FDOT	
Report Generated Date:	5/31/2011
Site Name:	

Network: 24J	Name: SUWANNEE COUNTY AI	RPORT			
Branch: TW	Name: TAXIWAY		Use: TAXIWAY	Area:	185,626.005qFt
Section: 105 Surface: AAC Area: 49,391.008qFt Shoulder: Street 7 Section Comments:	of 9 From: - Family: FDOT-GA-TW-AAC Length: 1,400.00Ft Type: Grade: 0.00	Zon Wi Lanes: 0	To: - ne: Category: dth: 35.00Ft	Rank: P	Last Const.: 1/1/1990
Last Insp. 12/6/2010 Conditions: PCI:80.00 Inspection Comments:	Total Samples: 14 Sur	veyed: 3			
Sample Number: 104 Sample Comments:	Туре: к	Area:	3,500.008qFt	PCI = 72	
56 SWELLING		L	16.00 SqFt	Comments:	
48 L & T CR		\mathbf{L}	63.00 Ft	Comments:	
48 L & T CR		М	126.00 Ft	Comments:	
Sample Number: 107 Sample Comments:	Туре: к	Area:	3,500.008qFt	PCI = 84	
48 L & T CR		\mathbf{L}	120.00 Ft	Comments:	
48 L & T CR		М	12.00 Ft	Comments:	
Sample Number: 112 Sample Comments:	Туре: к	Area:	3,500.008qFt	PCI = 84	
52 WEATH/RAVEL		L	28.00 SqFt	Comments:	
48 L & T CR		М	14.00 Ft	Comments:	
48 L & T CR		\mathbf{L}	91.00 Ft	Comments:	

Network: 24J	Name: SUWANNEE COUNTY AI	RPORT			
Branch: TW	Name: TAXIWAY		Use: TAXIWAY	Area: 1	85,626.008qFt
Section: 110 Surface: AC Area: 99,470.008qFt Shoulder: Street T Section Comments:	of 9 From: - Family: FDOT-GA-TW-AC Length: 2,842.00Ft Sype: Grade: 0.00	Zone: Widt Lanes: 0		Rank: P	Last Const.: 1/1/2004
Last Insp. 12/6/2010 Conditions: PCI:92.00 Inspection Comments:	Total Samples: 29 Sur	veyed: 3			
Sample Number: 117	Туре: к	Area:	3,500.008qFt	PCI = 89	
Sample Comments: 48 L & T CR		L	88.00 Ft	Comments:	
50 PATCHING		L	0.25 SqFt	Comments:	
Sample Number: 127 Sample Comments:	Туре: к	Area:	5,000.008qFt	PCI = 92	
50 PATCHING		L	0.25 SqFt	Comments:	
48 L & T CR		L	65.00 Ft	Comments:	
Sample Number: 136 Sample Comments:	Туре: к	Area:	3,500.008qFt	PCI = 93	
50 PATCHING		L	0.25 SqFt	Comments:	
48 L & T CR		L	17.00 Ft	Comments:	
52 WEATH/RAVEL		L	8.00 SqFt	Comments:	

Network: 24J	Name: SUWANNEE COUNTY	AIRPORT			
Branch: TW	Name: TAXIWAY		Use: TAXIWAY	Area:	185,626.008qFt
Section: 115 Surface: AC Area: 12,970.005qFt Shoulder: Street ' Section Comments:	of 9 From: - Family: FDOT-GA-TW-AC Length: 270.00 Type: Grade: 0.00		To: - ne: Category: idth: 45.00Ft	Rank: P	Last Const.: 1/1/1990
Last Insp. 12/6/2010 Conditions: PCI:76.00 Inspection Comments:	Total Samples: 3	Surveyed: 1			
Sample Number: 101 Sample Comments: 56 SWELLING 48 L & T CR 52 WEATH/RAVEL 48 L & T CR	Type: R	Area: L M L L	2,905.00SqFt 2.00 SqFt 41.00 Ft 263.00 SqFt 76.00 Ft	PCI = 76 Comments Comments Comments Comments	:

Network: 24J	Name: SUWANNEE COUNTY	AIRPORT			
Branch: TW	Name: TAXIWAY		Use: TAXIWAY	Area:	185,626.008qFt
Section: 120 Surface: AC Area: 4,495.00SqFt Shoulder: Street ' Section Comments: Last Insp. 12/6/2010 Conditions: PCI:59.00 Inspection Comments:		Zone St Wid Lanes: 0 Surveyed: 1		Rank: P	Last Const.: 1/1/1990
Sample Number: 100 Sample Comments: 52 WEATH/RAVEL 48 L & T CR 48 L & T CR 52 WEATH/RAVEL	Type: R	Area: L L M M	5,250.005qFt 5,155.00 SqFt 130.00 Ft 90.00 Ft 70.00 SqFt	PCI = 59 Comments Comments Comments	:

Network:	24J	Name: SUWANNEE COU	NTY AIRPORT				
Branch:	TW	Name: TAXIWAY			Use: TAXIWAY	Area:	185,626.008qFt
Section: Surface: Area: Shoulder: Section Comr		0	AC 0.0Œt Lanes	Zone: Width: 5: 0	To: - Category: 35.00Ft	Rank: P	Last Const.: 1/1/2000
Last Insp. Conditions	s: PCI:65.00	Total Samples: 2	Surveyed:	1			
Sample Comr 48 L & 52 WEAT		Туре: к	Area:	L M	00.008qFt 32.00 Ft 3.00 SqFt 3,497.00 SqFt	PCI = 65 Comments Comments Comments	:

Network:	24J	Name: SUWANNEE COUNTY	AIRPORT			
Branch:	TW	Name: TAXIWAY		Use: TAXIWAY	Area:	185,626.008qFt
Section: Surface: Area: Shoulder: Section Comr		of 9 From: - Family: FDOT-GA-TW-AC Length: 100.00F Type: Grade: 0.00	Zone: Tr Width: Lanes: 0	To: - Category: 35.00Ft	Rank: P	Last Const.: 1/1/2004
Last Insp. Conditions	s: PCI:64.00	Total Samples: 2	Surveyed: 1			
Sample Comr 52 WEAT	TH/RAVEL TH/RAVEL	Туре: к	Н	00.005qFt 1.00 SqFt ,499.00 SqFt 25.00 Ft	PCI = 64 Comments Comments Comments	:

Network: 24J	Na	me: SUWANNEE COU	UNTY AIRPORT				
Branch: TW	Na	me: TAXIWAY			Use: TAXIWAY	Area:	185,626.00 8 qFt
Section: 145	of	9 From: -			То: -		Last Const.: 1/1/2004
Surface: AC	F	Family: FDOT-GA-TW	'-AC	Zone:	Category:	Rank: P	
Area: 3,500).00SqFt	Length: 10	00.00Ft	Width:	35.00Ft		
Shoulder: Section Comments:	Street Type:	Grade: 0.00	Lanes	S: 0			
Section Comments.							
Last Insp. 1 Conditions: PCI	:91.00	otal Samples: 2	Surveyed:	l			
Last Insp. 1 Conditions: PCI Inspection Comment Sample Number	:91.00 s:	otal Samples: 2 Type: R	Surveyed:).008qFt	PCI = 91	
	:91.00 s: r: 101	-			0.008qFt 82.00 SqFt	PCI = 91 Comments	

Network:	24J	Name: SUWANNEE COUN	NTY AIRPORT				
Branch:	TW	Name: TAXIWAY			Use: TAXIWAY	Area:	185,626.008qFt
	150	of 9 From: -		7	To: -	D 1 -	Last Const.: 1/1/1990
	AC	Family: FDOT-GA-TW-		Zone:	Category:	Rank: P	
	5,200.00SqFt	0	0.00Ft	Width:	20.00Ft		
Shoulder:	Street T	Sype: Grade: 0.00	Lanes:	0			
Section Comme	ents:						
Last Insp. Conditions:	12/6/2010 : PCI:86.00	Total Samples: 1	Surveyed: 1				
Last Insp. Conditions: nspection Com	12/6/2010 : PCI:86.00 nments: mber: 100	Total Samples: 1 Type: R	Surveyed: 1 Area:	3,500.	008qFt	PCI = 86	
Last Insp. Conditions: Inspection Com	12/6/2010 : PCI:86.00 nments: mber: 100 tents:		Area:		.008qFt 270.00 SqFt	PCI = 86 Comments	