1	portation Office Page 1 of 6
	portation OfficePage 1 of 6spection Record4/29/2024
http://www.florida-aviation-database.com Airport In: Facility Name: Oak Tree Landing Airport	Inspection Date: 4/18/2024
	: Active Inspector: Jim Durwin
	3230.1*A FDOT District: 2
7.00 Miles SW of High Springs	County: Alachua
	1
ARP Longitude: 82° 39' 54.75	Use: Public
Elevation: 90 Source: Estimated	Sectional Chart: JACKSONVILLE
	ws below with a background.
Facility Owner: Oak Tree Landing, Ltd	Facility Physical Address
Address: 301 E Las Olas Blvd, Ste 210	Address: 1400 SE 80th Av
City: Fort Lauderdale State: FL ZIP: 33301	City: Newberry State: FL ZIP: 32669
Phone: (954) 627-9300 Fax:	Phone: (386) 871-5354
Email:	
Owner Representative: Rodman Ward	Facility Manager: Martha Osmun
Address: 251 Little Falls Dr	Address: 5200 NW 43rd St, Ste 102 Box 146
City: Wilmington State: DE ZIP: 19808	City: Gainesville State: FL ZIP: 32606
Phone: (866) 403-5272	Phone: (352) 316-3891
Email:	
Email.	Email: mosmunconsult@gmail.com
American 1200 Decidential time when N	Deserve
Acreage: 1,300 Residential Airpark: Yes	Beacon:
Section: 07 Township: 098 Range: 17E	Wind Indicator: Yes Lighted: Yes
Lighting Schedule:	Notes:
Attendance Schedule: Month/Day/Hour	Segmented Circle: No Lighted: No
	Facility Website:
	Ask in any new facility aerials/photos are available
Based Aircraft	
Year: 2010 Single Engine: Jet Engin	ne: Glider: Ultralight:
Source: Inspector Multi Engine: Helicopt	-
Total Based Aircraft:	
Annual Operations	
Year: Air Carrier:	Air Taxi: GA Local:
End Date: Commuter:	Military: GA Itinerant:
Total Annual Operations:	
FAR 139 Certificated	
FAA NavCom	
FSS ID: X GNV	Clearance Delivery:
FSS on Airport: X No	Ground Control:
Toll Free: (800) WX-BRIEF	Control Tower:
VorTac:	Approach Control:
AWOS/ASOS:	Unicom:
Instrument Approach:	ATIS:
	CTAF: X 122.900

Public Transportation Office

Page 2 of 6

http://www.florida-aviation-database.com Airport Inspection Record 4/29/2024 Facility Name: **Oak Tree Landing Airport** Inspection Date: 4/18/2024 Facility Type: Status: Active Inspector: Jim Durwin Airport Services Fuel: Other Services: A Aerial Surveying A1Air Ambulance Al +Air Freight В Aircraft Rental B^+ Aircraft Sales Avionics Mogas 80 Beaching Gear 100 Car Rental 100LL Cargo 115 Courtesy Car Airframe: Charter Major Crop Dusting Minor Glider Power Plant: Glider Towing Instruction Major Minor Internet Bottle Oxygen: Lodging High Parachute Jumping Area Low Restaurant X Bulk Oxygen: Restrooms High Taxi X 911 Low Telephone Transient Storage: Buoy

Hangar Tie Downs

Public Transportation Office

http://www.florida-avi	iation-database.com	Airport	Inspection Record		4/29/2024
Facility Name:	Oak Tree Landing Airport			Inspection Date:	4/18/2024
Facility Type:	Airport	Stat	us: Active	Inspector: Jim Du	ırwin
Runway ID	Status	Dimension	Surface	Condition	Lights
09/27	Existing	4,637 x 75	Asph	Good	None
		Comments:			

RWY 09

FAR 77 Category A(V)

RWY 27

FAR 77 Category A(V)

Approach ratio required is RWY 09 20:1 and RWY 27 20:1. Primary surface required is 250 feet wide.

Transitional surface required is 0:1.

Safety area required extends 240 feet beyond each runway end.

				Runy	way 09						
	Latitude	Longitude	Source Slope		Marking	VG_{i}	VGSI R.		Rt Traffic	Approach	
09	29° 43' 12.70	82° 40' 21.05	Estimated		6:1	NPI-P	Ν		No	No	NONE
			0	bstructio	n Data						
		Close-in Obstruction	Displacement Distance	t Slope	Controlling Obstruction		Height ' Above Runway	Distance From Runway		Direction From Runway End	Controllin g Offset
Primary	Surface	No		6:1	ROAD		22 ft	343 ft	Bef	ore Runway E	nd 0 ft Bo
Runway	End	No		13:1	TREES		27 ft	370 ft	Bef	ore Runway E	nd 80 ft R
Marked .	Displaced Thresh	old No	100 ft	18:1	TREES		27 ft	370 ft	Bef	ore Runway E	nd 80 ft R
Required	d Displaced Thres	hold No	170 ft	20:1	TREES		27 ft	370 ft	Bef	ore Runway E	nd 80 ft R
				Rur	iway 27						
Latitude Longitude Source		Source	Slope		Marking	VG_{i}	VGSI REIL Rt Traffic		Rt Traffic	Approach	
27	29° 43' 13.13	82° 39' 28.45	Estimated	2	21:1	NPI-P	Ν		No	No	NONE
			0	bstructio	n Data						
		Close-in Obstruction	Displacement Distance	t Slope	Controlling Obstruction		Height Above Runway	Distance From Runway		Direction From Runway End	Controllin g Offset
Primary Runway	Surface End	No		21:1	TREES		65 ft	1,560 ft	Bef	ore Runway E	nd 95 ft R
Marked	Displaced Thresh	old									
Required	d Displaced Thres	hold									
]	Primary S	Surface and S	Safety Are	ea				
Obje	ct Latitutu	de Longitude	Survey/	Distance from Centerline	Direction from Centerline	Height	Fixed by Function	Frangible	Marke	Aeronatica ed Study	l Determination
RUT	CS 29° 43' 13	8.25 82° 40' 17.7	Estimated	53 ft	Ν		No	No	No		

Page 3 of 6

		Public Transportation Offic	•	Pa		
vww.florida-aviation-da	tabase.com	Airport Inspection Record	d	4		
ity Name: Oak	Tree Landing Airport		Inspection Date: 4/18/2024			
ity Type: Airp	ort	Status: Active	Inspector: Jim Durwin			
eficiencies						
	/18/24 Next Inspec	ction 4/30/25				
eficiencies						
09/27:	In accordance with Chapter 14-60.	.007(9)(f), FAC. – Hold position	n markings for paved taxiways shall be yellow.			
Taxiway (A)						
	Taxiway A hold position markings	s at Runway 09 are faded and in	poor condition			
09/27 :		-	s shall be required for all permanent pavement			
Taxiway (A) Hold Position	markings.		F F F			
1 00111011	Taxiway A hold position marking	at Runway 27 does not contain a	a sufficient amount of glass beads.			
Rwy End: 09	In accordance with Chapter 14-60.	.007(9)(d), FAC. – Threshold ba	ars shall be white.			
	Pupuou 00 thread ald to a to for 1 1	and in poor condition				
	Runway 09 threshold bar is faded	-				
Rwy End: 09	In accordance with Chapter 14-60.	.007(9)(b), FAC. – Runway des	ignation markings shall be white.			
	Runway 09 runway designation markings are stained and/or dirty.					
Rwy End: 09	-		gs on light colored pavements shall be outlined with a	a		
Displaced	black border six inches or greater	in width.				
Arrow Head	Runway 09 displaced threshold arrow head markings are not outlined with a black boarder six inches or greater in					
	width.	row nead markings are not outin	ied with a black boarder six menes or greater in			
Rwy End: 09	In accordance with Chapter 14-60.	.007(9)(1)1., FAC. – Glass beads	s shall be required for all permanent pavement			
Displaced	markings.					
Arrow Head	Runway 09 displaced threshold arr	rour hoods do not contain a suffi	aight am annt af alaca baada			
D E 1.00						
Rwy End: 09 Displaced	In accordance with Chapter 14-60. black border six inches or greater		gs on light colored pavements shall be outlined with a	1		
Bar	black border six menes of greater	in widdi.				
	Runway 09 displaced threshold ba	r marking is not outlined with a	black boarder six inches or greater in width.			
Rwy End: 09	-	.007(9)(1)1., FAC. – Glass beads	s shall be required for all permanent pavement			
Displaced	markings.					
Bar	Runway 09 displaced threshold ba	r does not contain sufficient and	ount of glass beads.			
Rwy End: 09	· · ·		gs on light colored pavements shall be outlined with a	1		
Runway	black border six inches or greater					
Centerline	2					
		-	ack border six inches or greater in width.	_		
Rwy End: 09	In accordance with Chapter 14-60. markings.	.007(9)(l)1., FAC. – Glass beads	s shall be required for all permanent pavement			
Runway Centerline	markings.					
	Runway 09/27 centerline markings	s do not contain a sufficient amo	ount of glass beads.			
Rwy End: 09	In accordance with Chapter 14-60.	.007(9)(l)2., FAC. – All marking	gs on light colored pavements shall be outlined with a	a		
Runway	black border six inches or greater					
Designation	D 00 1 1 1		1 1 1 1 1 1 1 1			
		-	lack border six inches or greater in width.			
Rwy End: 09 Runway	In accordance with Chapter 14-60. markings.	.007(9)(1)1., FAC. – Glass beads	s shall be required for all permanent pavement			
Designation	markings.					

Public Transportation Office

.florida-aviation-	latabase.com Airport Inspection Record
	A Tree Landing Airport Inspection Date: 4/18/2024 port Status: Active Inspector: Jim Durwin
	Runway 09 designation markings do not contain a sufficient amount of glass beads.
Rwy End: 27	In accordance with Chapter 14-60.007(9)(b), FAC. – Runway designation markings shall be white.
	Runway 27 runway designation markings are stained and/or dirty.
Rwy End: 27 Runway Centerline	In accordance with Chapter 14-60.007(9)(l)2., FAC. – All markings on light colored pavements shall be outlined with a black border six inches or greater in width.
	Runway 27 runway centerline markings are not outlined with a black border six inches or greater in width.
Rwy End: 27 Runway Designation	In accordance with Chapter 14-60.007(9)(l)2., FAC. – All markings on light colored pavements shall be outlined with a black border six inches or greater in width.
8	Runway 27 runway designation markings are not outlined with a black border six inches or greater in width.
Rwy End: 27 Runway Designation	In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.
	Runway 27 desingation markings do not contain a sufficient amount of glass beads.
Rwy End: 27 Threshold Bar	In accordance with Chapter 14-60.007(9)(l)2., FAC. – All markings on light colored pavements shall be outlined with a black border six inches or greater in width.
	Runway 27 runway threshold bar marking is not outlined with a black border six inches or greater in width.
Rwy End: 27 Threshold Bar	In accordance with Chapter 14-60.007(9)(1)1., FAC. – Glass beads shall be required for all permanent pavement markings.
	Runway 27 runway threshold bar marking does not contain a sufficient amount of glass beads.
gated Deficie	
Rwy End: 09	In accordance with Chapter 14-60.007(5)(b), FAC. – For a runway that is paved, the runway safety area shall have a width of 120 feet.
	Washout/ruts located 340 feet after approach end of runway, 53 feet left of centerline is located inside the runway safety area of runway 9/27.
	Spoke with Mr. Eddie Hines, Inspection Contact, after the inspection on April 18, 2024 he stated that he would have the area repaired by April 25, 2024.
Rwy End: 09	In accordance with Chapter 14-60.007(2)(c)1.d., FAC. – For a runway that is paved, that is to be used by an aircraft that weighs greater than 12,500 pounds, and that has a visual landing approach: the approach surface ratio is 20:1.
	Runway 09 approach surface ratio is 6:1 due to road 22 feet tall, 343 feet before the approach end of the runway, on centerline.
	Runway 09 approach surface ratio is 18:1 to the displaced threshold due to tree 27 feet tall, 370 feet before the approach end of the runway, 80 feet right of centerline.
	Runway 09 is displaced 100 feet.
	Spoke with Mr. Eddie Hines, Inspection Contact, after the inspection on April 18, 2024, and he stated he would

Page 5 of 6 4/29/2024

Public Transportation Office

http://www.florida-aviation-database.com			Airport Inspection Record		4/29/2024
Facility Na	me: Oak Tree Landing	Airport		Inspection Date: 4/18/2024	
Facility Ty	pe: Airport		Status: Active	Inspector: Jim Durwin	
License					
Effective:	08/01/2024	Category:	Public	Limitations: Day Use Only	
Expires:	07/31/2025			VFR Use Only	

Conditions:

The department may revoke, refuse to allow or issue, any license or license renewal, if it determines that the airport does not comply with the conditions of the license, license renewal, or site approval or that the airport has become unsafe or unusable for flight operation due to physical or legal changes that were the subject of approval pursuant to Section 330.30(2)(e), F.S.

A. This Airport has the following approach limitations.

1. Runway 09/27 is available for visual approaches only.

a. Runway 09 is FAR 77 category A(V).

b. Runway 27 is FAR 77 category A(V).

2. Runway 09 threshold is displaced 100 feet.

Additional Licensing Remarks:

Page 6 of 6