http://www.florida-aviation	on-database.com		P	Airport Insp	pection Re	ecord				8/28/2023
Facility Name: I	DeLand Municipal - S	Sidney H Tay	lor Field				Inspection	Date:	8/22/2025	
Facility Type:	Airport			Status:	Active		Inspector:	David Si	nith	
Location ID:	DED		FAA Site	No.: 031	156.*A		FDOT D	istrict:	5	
3.00 Miles NE of I	Deland						County:		Volusia	
ARP Latitude:	29° 4' 1.13	Source: E	Estimated				Ownersh	ip	Public	
ARP Longitude:	81° 17' 2.19						Use:		Public	
Elevation:	79	Source: S	urveyed				Sectional	Chart:	JACKSONVILLE	
		No	te: Primary	contact shov	ws below	with a back	kground.			
Facility Owner: (City of DeLand				Facility	Physical	Address			
Address: 120 S Flo	orida Av				4 1 1	1000 E	ı ı ar Dı	,		
					Address:	1000 F1	lightline Blvo	1		
City: Deland			P: 32720		City:	Deland		State	:FL ZIP: 3272	4
Phone: (386) 620	6-7240 F	'ax:			Phone:	(386) 626	5-7240			
Email: eiffj@de	land.org									
Owner Representati	ive: Michael Pleus	1			Facility .	Manager:	John Eiff			
Address: 120 S F	lorida Av				Address:	1000 FI	lightline Blvo	d		
							J			
City: DeLand	I Sta	ate: FL ZIF	P: 32720		City:	Deland	l	State	: FL ZIP: 32724	
Phone: (386) 62		12 2	. 02.20		Phone:		26-7240	2000	. 12 21 . 01 /21	
, ,	@deland.org				Email:		deland.org			
Email. picusiii	wucianu.org				Emaii.	chijwa	icianu.org	_		_
Agragas: 1 200	Pagid	lantial Ainnaul	k: No	1	Beacon:	C-G				
Acreage: 1,289		lential Airpark					3 7		7 · 1 . 1 · 3 7	
Section: 34	Township: 16S	Ran	ge: 30E		Wind Inc	licator:	Yes		Lighted: Yes	
Lighting Schedule:	Sunset to Sunrise				Notes:					
Attendance Schedule					Segment	ed Circle:	Yes		Lighted: Yes	
	ALL / ALL / (J800-1800			Facility	Website: 1	https://www.	delandairp	ort.com/	
						Ask in	any new faci	lity aerials/ _[photos are available	
Based Aircraft										
<i>Year:</i> 2010	Single I	Engine:	114	Jet Engine	2:	3	Glider:		Ultralight:	2
Source: Inspector	r Multi E	'ngine:	37	Helicopter	r:	6	Military:		Seaplane:	
Total Based Aircraf	t:									
Annual Operation										
Year:		Air Carrier:			Air Taxi	· .		GA Local		
End Date:		Commuter:						GA Itiner		
		Commuter:			Military).		GA Iliner	ant:	
Total Annual Opera										
FAR 139 Certificated	d									
FAA NavCom										
	- Danie				G!	D 11				
FSS ID:	X PIE					ance Deliv				
FSS on Airport:	X No					nd Control.	·			
Toll Free:	(800) WX-1					ol Tower:				
VorTac:	X OMN 112.0	6 213d/16.8 m	m		Appro	oach Contr	ol: X	125.350		
AWOS/ASOS:	X 119.575				Unice	om:	X	123.075		
Instrument Approac	h: X LPV, LNA	V/VNAV, LN	AV		ATIS:					
					CTAF	<i>7</i> :	X	123.075		

State of Florida Department of Transportation

Aviation Office

Page 2 of 8

http://www.florida-a	viation-database.com	Airpor	t Inspection Record	d		8/28/202
Facility Name	: DeLand Municipal -	Sidney H Taylor Field		Inspection I	Date: 8/22/2025	
Facility Type:	Airport	St	atus: Active	Inspector:	David Smith	
Services						
	X	Other Services: Aerial Surveying Air Ambulance Air Freight Aircraft Rental Aircraft Sales Avionics Beaching Gear Car Rental Cargo Courtesy Car Charter Crop Dusting Glider Glider Towing Instruction Internet Lodging Parachute Jumping A Restaurant Restrooms Taxi Telephone		ort Resturants	Aircraft Charging Stations: Electric Charging Stations Hydrogen Charging Stations Battery Charging Stations Solar Charging Stations Auto Charging Stations Aircraft Electric Charging Power Rating: Alternating Current Direct Current Aircraft Electrict Charging Station Plug Type AC - J1772 AC - Mennekes DC - GB/T DC - CCS Type1 DC - CCS Type2 DC - MCS DC - CHAdeMO Other Support Infrastructure: Passenger Waiting Facility Aircraft Tug Station Deicing Equipment Battery Thermal Conditioning System Maintenance Platforms, Ladders, Inspection Provider of Services Fire Suppression/ Extinguishing System Aircraft Cabin Thermal Conditioning Equipment Passenger/Cargo Loading Equipment	
Major Minor	X				Aircraft Electric Charger Power Output:	

Number of Aircraft Electric Charging

Stations:

State of Florida Department of Transportation Aviation Office

Aviation Office Page 3 of 8

http://www.florida-aviation-database.com Airport Inspection Record 8/28/2025

nttp://www.floriaa-avi	ation-aatabase.com	Airp	ort inspection Record			6/26/2023
Facility Name:	DeLand Municipal	- Sidney H Taylor Field		Inspection Date: 8/22	/2025	
Facility Type:	Airport		Status: Active	Inspector: David Smith		
Runway ID	Status	Dimension	Surface	Condition	Lights	
05/23	Existing	4,301 x 75	Asph	Fair	MIRL	
		Comme	ents:			

RWY 05

FAR 77 Category C.

RWY 23

FAR 77 Category C.

Approach ratio required is RWY 05 34:1 and RWY 23 34:1.

Primary surface required is 500 feet wide.

Close-in Obstruction Displacement Obstruction Displacement Obstruction Distance Runway End No 25:1 TREES 51 ft 1,455 ft Before Runway End 230 ft 1,455 ft Reill Rt Traffic Approach 230 ft 1,455 ft Reill Rt Traffic Approach 230 ft 1,455 ft Reill Rt Traffic Approach 240 ft 1,455 ft Reill Rt Traffic Approach 241 ft 1,455 ft						Runy	way 05							
		Latitude	e 1	ongitude	Source	Sle	оре	Marking	VG	SI	REIL	Rt Traffic	Approach	
Close-in Obstruction Obs	05	29° 3' 3	6.47	1° 17' 20.61	Surveyed	2	5:1	NPI-P	P2I	_	No	No	NONE	
Close-in Obstruction Obs					O	bstructio	n Data							
Runway End No Z8:1 TREES 51 ft 1,455 ft Before Runway End 230 ft Racked Displaced Threshold Required Displaced Threshold No 279 ft 34:1 TREES 51 ft 1,455 ft Before Runway End 230 ft Required Displaced Threshold No 279 ft 34:1 TREES 51 ft 1,455 ft Before Runway End 230 ft Required Displaced Threshold No 279 ft 34:1 TREES 51 ft 1,455 ft Before Runway End 230 ft Required Displaced Threshold Restance Runway End Runway Runw					-		U		Above	From		From	Control g Offse	
Required Displaced Threshold No 279 ft 34:1 TREES 51 ft 1,455 ft Before Runway End 230 ft Required Displaced Threshold No 279 ft 34:1 TREES 51 ft 1,455 ft Before Runway End 230 ft Required Displaced Threshold Distance Displacement Disp	Primar _.	y Surface		No		25:1	TREES		51 ft	1,455 ft	Bef	ore Runway Ei	nd 230 ft	L
Required Displaced Threshold No 279 ft 34:1 TREES 51 ft 1,455 ft Before Runway End 230 ft Runway End	Runway	v End		No		28:1	TREES		51 ft	1,455 ft	Bef	ore Runway Ei	nd 230 ft	L
Latitude	Markea	l Displace	d Threshold											
Latitude Longitude Source Slope Marking VGSI REIL Rt Traffic Approach 23 29° 4' 5 81° 16' 43.6 Surveyed 34:1 NPI-P P2L No No No NONE TOST TOST	Require	ed Displac	ed Threshold	d No	279 ft	34:1	TREES		51 ft	1,455 ft	Bef	ore Runway Ei	nd 230 ft	L
23 29° 4' 5 81° 16' 43.6 Surveyed 34:1 NPI-P P2L No No No NONE Obstruction Data Close-in Obstruction Displacement Displaced Threshold Required Displaced Threshold Required Displaced Threshold Object Latitutude Longitude Survey/ from from from from from Fixed by Aeronatical Estimate Centerline Centerline Centerline Height Function Frangible Marked Study Determinated Displacement D						Run	iway 23							
Close-in Obstruction Data Close-in Obstruction Displacement Obstruction Displacement Obstruction Displacement Obstruction Displacement Obstruction Displacement Obstruction Displacement Displaced Primary Surface No Displaced No Displaced Threshold Displaced Displaced Threshold Displaced Threshold Displaced Displaced Displaced Displaced Displac		Latitude	e 1	ongitude	Source	Sle	ope	Marking	VG	SI	REIL	Rt Traffic	Approach	
Close-in Obstruction Displacement Obstruction Distance No Siope Obstruction Lighted Runway Runway Runway End Offset Runway End Required Displaced Threshold Requ	23	29° 4' 5	8	1° 16' 43.6	Surveyed	3	4:1	NPI-P	P2I	_	No	No	NONE	
Close-in Obstruction Displacement Displaced Threshold Aurked Displaced Threshold Displaced Displ					0	bstructio	n Data							
Runway End Marked Displaced Threshold Required Displaced Threshold Primary Surface and Safety Area Distance Direction Survey/ from from Fixed by Aeronatical Object Latitutude Longitude Estimate Centerline Centerline Height Function Frangible Marked Study Determina EQUIP 29° 03' 46.51 81° 17' 09.48 Estimated 110 ft NW 1 ft No Yes Yes EQUIP 29° 03' 58.32 81° 16' 50.42 Estimated 110 ft SE 1 ft No Yes Yes					•		_		Above	From		From	Control g Offse	
Marked Displaced Threshold Required Displaced Threshold Primary Surface and Safety Area Distance Direction Survey/ from from Fixed by Aeronatical Object Latitutude Longitude Estimate Centerline Centerline Height Function Frangible Marked Study Determina EQUIP 29° 03' 46.51 81° 17' 09.48 Estimated 110 ft NW 1 ft No Yes Yes EQUIP 29° 03' 58.32 81° 16' 50.42 Estimated 110 ft SE 1 ft No Yes Yes	Primar	y Surface		No		34:1	TREES		55 ft	2,055 ft	Bef	ore Runway Eı	nd 200 ft	L
Required Displaced Threshold Primary Surface and Safety Area Distance Direction Survey/ from from Fixed by Aeronatical Object Latitutude Longitude Estimate Centerline Centerline Height Function Frangible Marked Study Determina EQUIP 29° 03' 46.51 81° 17' 09.48 Estimated 110 ft NW 1 ft No Yes Yes EQUIP 29° 03' 58.32 81° 16' 50.42 Estimated 110 ft SE 1 ft No Yes Yes	Runway	v End												
Primary Surface and Safety Area Distance Direction Survey/ from from from Fixed by Latitutude Longitude Estimate Centerline Centerline Height Function Frangible Marked Study Determine EQUIP 29° 03' 46.51 81° 17' 09.48 Estimated 110 ft NW 1 ft No Yes Yes EQUIP 29° 03' 58.32 81° 16' 50.42 Estimated 110 ft SE 1 ft No Yes Yes		=												
Object Latitutude Longitude Estimate Centerline Centerline NW 1 ft No Yes Yes EQUIP 29° 03' 58.32 81° 16' 50.42 Estimated 110 ft SE 1 ft No Yes Yes	Require	ed Displac	ed Threshold	l	1	n	· · · · · · · · · · · · · · · · · · ·	- -	_					
Object Latitutude Longitude Estimate Centerline Centerline Height Function Frangible Marked Study Determined EQUIP 29° 03' 46.51 81° 17' 09.48 Estimated 110 ft NW 1 ft No Yes Yes EQUIP 29° 03' 58.32 81° 16' 50.42 Estimated 110 ft SE 1 ft No Yes Yes						-		alety Are	ea .					
EQUIP 29° 03' 58.32 81° 16' 50.42 Estimated 110 ft SE 1 ft No Yes Yes	Obj	ect	Latitutude	Longitude	Survey/	from	from	Height		Frangible	Marke		l Determina	tion
·	EQU	UIP 2	9° 03' 46.51	81° 17' 09.48	Estimated	110 ft	NW	1 ft	No	Yes	Yes			
Runway ID Status Dimension Surface Condition Lights	EQU	UIP 2	9° 03' 58.32	81° 16' 50.42	Estimated	110 ft	SE	1 ft	No	Yes	Yes			
	Run	way ID	Statu	s	Dimen	sion		Surface	;	Cond	dition	L	ights	

http://www.florida-aviation-database.com

Airport Inspection Record

Facility Name: **DeLand Municipal - Sidney H Taylor Field** Inspection Date: 8/22/2025

Facility Type: Airport Status: Active Inspector: **David Smith**

RWY 12

FAR 77 Category C.

RWY 30

FAR 77 Category C.

Object

EQUIP

EQUIP

Latitutude

29° 04' 17.30

29° 03' 56.52

Longitude

81° 17' 22.66

81° 16' 44.42

Approach ratio required is RWY 12 34:1 and RWY 30 34:1.

Latituc 2 29° 4' 1	0		eyed	<i>Slope</i> 34:1	Marking NPI-P	VGS	Ţ	REIL	Rt Traffic	Approach
2 29° 4 ' :	20.67 81° 17'	33.45 Surve	-	34:1	NPI-P					
			Obstruct			P2L		Yes	No	NONE
			O DOLL GO	tion Data						
	C	-	acement stance Slop	Controlling Obstruction		Height Above Runway	Distance From Runway		Direction From Runway End	Controllin g Offset
rimary Surface unway End		No	34:1	1 TREES		27 ft	1,105 ft	Bef	ore Runway E	nd 85 ft
arked Displace	ed Threshold									
equired Displa	ced Threshold									
			R	unway 30						
Latitud	de Longiti	ude Sourc	re	Slope	Marking	VGS	Ţ	REIL	Rt Traffic	Approach
30 29° 3'	53.7 81° 16'	33.21 Surve	eyed	30:1	NPI-P	P4L		Yes	No	NONE
			Obstruct	tion Data						
	C	-	acement stance Slop	Controlling Obstruction		Height Above Runway	Distance From Runway		Direction From Runway End	Controllin g Offset
rimary Surface		No	30:1	1 TREES		66 ft	2,220 ft	Bef	ore Runway E	nd 235 ft
unway End		No	34:1	1 TREES		66 ft	2,220 ft	Bef	ore Runway E	nd 235 ft
arked Displace	ed Threshold									
equired Displa	ced Threshold			y Surface and S						

Estimate Centerline Centerline

130 ft

198 ft

N

S

Estimated

Estimated

Height Function

No

No

2 ft

2 ft

Frangible Marked

No

No

Yes

Yes

Determination

Study

State of Florida Department of Transportation Aviation Office

Page 5 of 8

8/28/2025

http://www.florida-aviation-database.com Airport Inspection Record

11	up.//www.jioriaa-aviai	ion-uuiuouse.com	11	ii poi t inspectio	on record			0,20,2020
F	acility Name:	DeLand Municipal - Sidne	y H Taylor Field			Inspection Date:	8/22/2025	
F	acility Type:	Airport		Status: Act	ive	Inspector: David	Smith	
	Instrument A	pproach						
	05/23	Туре	A	В	C	D	E	
	05	LNAV	1.00 Miles	1.00 Miles	1.38 Miles	1.38 Miles		
	05	LNAV/VNAV	1.75 Miles	1.75 Miles	1.75 Miles	1.75 Miles		
	05	LPV	1.00 Miles	1.00 Miles	1.00 Miles	1.00 Miles		
	23	LNAV	1.00 Miles	1.00 Miles	1.00 Miles	1.00 Miles		
	23	LNAV/VNAV	1.25 Miles	1.25 Miles	1.25 Miles	1.25 Miles		
	23	LPV	1.00 Miles	1.00 Miles	1.00 Miles	1.00 Miles		
	12/30	Туре	A	В	C	D	E	
	12	LNAV	1.00 Miles	1.00 Miles	1.50 Miles	1.50 Miles		
	12	LNAV/VNAV	1.50 Miles	1.50 Miles	1.50 Miles	1.50 Miles		
	12	LPV	1.25 Miles	1.25 Miles	1.25 Miles	1.25 Miles		
	30	LNAV	1.00 Miles	1.00 Miles	1.25 Miles	1.25 Miles		

Aviation Office Page 6 of 8

http://www.florida-aviation-database.com Airport Inspection Record 8/28/2025

Facility Name: DeLand Municipal - Sidney H Taylor Field Inspection Date: 8/22/2025
Facility Type: Airport Status: Active Inspector: David Smith

Deficiencies	
Inspection Date	8/22/25 Next Inspection 8/31/26
Deficiencies 05/23: Taxiway (A@05)	In accordance with Chapter 14-60.007(9)(f), FAC. – Hold position markings for paved taxiways shall be yellow.
	Taxiway A hold position markings at Runway 05 are stained and/or discolored.
05/23 : Taxiway (B)	In accordance with Chapter 14-60.007(9)(f), FAC. – Hold position markings for paved taxiways shall be yellow.
	Taxiway B hold position markings at Runway 05/23 are stained and/or discolored.
12/30 : Taxiway (D@12)	In accordance with Chapter 14-60.007(9)(f), FAC. – Hold position markings for paved taxiways shall be yellow.
	Taxiway D hold position markings at Runway 12 are stained and/or discolored.
12/30 : Taxiway (D@30)	In accordance with Chapter 14-60.007(9)(f), FAC. – Hold position markings for paved taxiways shall be yellow.
	Taxiway D hold position markings at Runway 30 are stained and/or discolored.
12/30 : Taxiway (E)	In accordance with Chapter 14-60.007(9)(f), FAC. – Hold position markings for paved taxiways shall be yellow.
	Taxiway E hold position markings at Runway 30 are stained and/or discolored.
Rwy End: 05	In accordance with Chapter 14-60.007(9)(d), FAC. – Threshold bars shall be white.
	Runway 05 threshold bar marking is stained and/or discolored.
Rwy End: 05	In accordance with Chapter 14-60.007(9)(c), FAC. – Runway centerline markings shall be white.
	Runway 05/23 runway centerline markings are faded and in poor condition.
Rwy End: 05 Runway Designation	In accordance with Chapter 14-60.007(9)(1)1., FAC. – Glass beads shall be required for all permanent pavement markings.
	Runway 05 runway designation markings do not contain a sufficient amount of glass beads.
Rwy End: 05 Threshold Bar	In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.
	Runway 05 threshold bar marking does not contain a sufficient amount of glass beads.
Rwy End: 12	In accordance with Chapter 14-60.007(9)(c), FAC. – Runway centerline markings shall be white.
	Runway 12/30 runway centerline markings are faded and in poor condition.
Rwy End: 12	In accordance with Chapter 14-60.007(9)(b), FAC. – Runway designation markings shall be white.
	Runway 12 runway designation markings are faded and in poor condition.
Rwy End: 23	In accordance with Chapter 14-60.007(2)(d)1.e., FAC. – For a runway that is paved, that is to be used by an aircraft that weighs greater than 12,500 pounds, and that has a non-precision instrument approach with visibility greater than 3/4 mile: the transition surface ratio is 7:1.

Aviation Office Page 7 of 8

http://www.florida-aviation-database.com Airport Inspection Record 8/28/2025

w.florida-av			8/28
y Name: y Type:	DeLan Airpoi	ad Municipal - Sidney H Taylor Field Inspection Date: 8/22/2025 Status: Active Inspector: David Smith	
, - , ,		Brush and trees 400 feet to 240 feet before the approach end of the runway, 255 feet right of centerline penetrates the transitional surface of Runway 05/23.	
Rwy End: 23 Rwy End: 23		In accordance with Chapter 14-60.007(9)(d), FAC. – Threshold bars shall be white.	
		Runway 23 threshold bar is faded and in poor condition.	
		In accordance with Chapter 14-60.007(9)(b), FAC. – Runway designation markings shall be white.	
		Runway 23 runway designation markings are faded and in poor condition.	
Rwy End Runway Designa	ī	In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.	
J		Runway 23 runway designation markings do not contain a sufficient amount of glass beads.	
Rwy End Thresho Bar		In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.	
		Runway 23 threshold bar marking does not contain a sufficient amount of glass beads.	
Rwy En	d: 30	In accordance with Chapter 14-60.007(9)(b), FAC. – Runway designation markings shall be white.	
		Runway 30 runway designation markings are stained and/or discolored.	
Rwy End Runway Centerlin	7	In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.	
		Runway 12/30 runway centerline markings do not contain a sufficient amount of glass beads.	
tigated De	eficiencie	es s	
Rwy En		In accordance with Chapter 14-60.007(2)(c)1.e., FAC. – For a runway that is paved, that is to be used by an aircraft that weighs greater than 12,500 pounds, and that has a non-precision instrument approach with visibility greater than $\frac{3}{4}$ mile: the approach surface ratio is 34:1.	
		Runway 05 approach surface ratio is 25:1 due to tree 51 feet tall, 1,455 feet before the approach end of the runway, 230 feet left of centerline.	
		Runway 5 approach surface ratio meets obstacle clearance standards contained in FAA AC 150/5300-13B for a runway with instrument approach procedures with visibility minimums equal to or greater than 3/4 of a mile.	
		A comment is currently published to advise aircraft operators of unlighted obstructions in the approach to Runway 05 on the FAA chart supplement.	
Rwy En	d: 30	In accordance with Chapter 14-60.007(2)(c)1.e., FAC. – For a runway that is paved, that is to be used by an aircraft that weighs greater than 12,500 pounds, and that has a non-precision instrument approach with visibility greater than $\frac{3}{4}$ mile: the approach surface ratio is 34:1.	
		Runway 30 approach surface ratio is 30:1 due to trees 66 feet tall, 2,220 feet before the approach end of the runway, 235 feet right of centerline.	
		Runway 30 threshold is displaced to the approach end of the runway.	

State of Florida Department of Transportation Aviation Office

Page 8 of 8

http://www.florida-aviation-database.com Airport Inspection Record 8/28/2025

nup.//www.jiori	au-aviation-aatabase.com		miport inspection record			0.20.202.
Facility Name: DeLand Municipal - Sidney H Taylor Field			ld	Inspection Date:	8/22/2025	
Facility Typ	pe: Airport		Status: Active	Inspector: David S	Smith	
License						
Effective:	12/01/2025	Category:	Public Special	Limitations:	Day Use Only	
Expires:	11/30/2026				VFR Use Only	
C						

Conditions:

The department may revoke, refuse to allow or issue, any license or license renewal, if it determines that the airport does not comply with the conditions of the license, license renewal, or site approval or that the airport has become unsafe or unusable for flight operation due to physical or legal changes that were the subject of approval pursuant to Section 330.30(2)(e), F.S.

- A. This Airport has the following landing areas and approach limitations.
- 1. Runway 05/23 is available for non-precision instrument and visual approaches.
- a. Runway 05 is FAR 77 category C.
- b. Runway 23 is FAR 77 category C.
- 2. Runway 12/30 is available for non-precision instrument and visual approaches.
- a. Runway 12 is FAR 77 category C.
- b. Runway 30 is FAR 77 category C.
- 3. Runway 05 threshold is displaced to the end of the runway.
- 4. Runway 30 threshold is displaced to the end of the runway.
- B. This Airport is issued a Special License pursuant to Chapter 330.30(2)(b), F.S.

The department may license a public airport that does not meet standards only if it determines that such an exception is justified by unusual circumstances or is in the interest of public convenience and does not endanger the public health, safety, or welfare. Such a license shall bear the designation "special" and shall state the conditions subject to which the license is granted.

- 1. Runway 05 approach surface ratio is 25:1 due to trees, 51 feet tall, 1,455 feet before the approach end of the runway, 230 feet left of centerline.
- 2. Brush and trees 400 feet to 240 feet before the approach end of the runway, 255 feet right of centerline penetrates the transitional surface of Runway 05/23.

Additional Licensing Remarks: