

Facility Name: Pilot Country Airport		Inspection Date: 11/3/2025	
Facility Type: Airport		Inspector: David Smith	
Status: Active			
Location ID: X05	FAA Site No.: 03083.01*A	FDOT District: 7	
13.00 Miles S of Brooksville		County: Pasco	
ARP Latitude: 28° 19' 49.02	Source: Estimated	Ownership: Private	
ARP Longitude: 82° 29' 47.34		Use: Public	
Elevation: 80	Source: Surveyed	Sectional Chart: JACKSONVILLE	

Note: Primary contact shows below with a background.

Facility Owner: Pilot Country Airport X05, LLC		Facility Physical Address	
Address: 11500 Pilot Country Dr		Address: 11500 Pilot Country Dr	
City: Spring Hill	State: FL ZIP: 34610	City: Spring Hill	State: FL ZIP: 34610
Phone: (813) 235-9000	Fax:	Phone: (813) 235-9000	
Email:			
Owner Representative: Mark Twaalfhoven		Facility Manager: Jill Troughton	
Address: 11851 Driver Ln		Address: 11500 Pilot Country Dr	
City: Spring Hill	State: FL ZIP: 34610	City: Spring Hill	State: FL ZIP: 34610
Phone: (813) 235-9000		Phone: (813) 469-9227	
Email: mark@twaalfhoven.com		Email: pcax05@gmail.com	

Acres: 27	Residential Airpark: Yes	Beacon: C-G
Section: 03	Township: 25S Range: 18E	Wind Indicator: Yes Lighted: Yes
Lighting Schedule: Sunset to Sunrise		Notes: Yes
Attendance Schedule: Month/Day/Hour		Segmented Circle: No Lighted: No
ALL / ALL / 0800-1730		Facility Website: https://www.facebook.com/pages/Pilot-Country-Airport/1
		Ask in any new facility aerals/photos are available

Based Aircraft					
Year: 2011	Single Engine: 25	Jet Engine: 0	Glider: 0	Ultralight: 0	
Source: Inspector	Multi Engine: 1	Helicopter: 1	Military: 0	Seaplane:	
Total Based Aircraft:					

Annual Operations			
Year:	Air Carrier:	Air Taxi:	GA Local:
End Date:	Commuter:	Military:	GA Itinerant:
Total Annual Operations:			

FAR 139 Certificated

FAA NavCom	
FSS ID: ☒ PIE	Clearance Delivery: ☐
FSS on Airport: ☒ No	Ground Control: ☐
Toll Free: ☒ (800) WX-BRIEF	Control Tower: ☐
VorTac: ☒ PIE 116.4 020d/27.2 nm	Approach Control: ☐
AWOS/ASOS: ☐	Unicom: ☒ 122.800
Instrument Approach: ☐	ATIS: ☐
	CTAF: ☒ 122.800

Facility Name: Pilot Country Airport

Facility Type: Airport

Status: Active

Inspection Date: 11/3/2025

Inspector: David Smith

Services

Fuel:

A ☐
 A1 ☐
 A1+ ☐
 B ☐
 B+ ☐
 Diesel ☐
 E85 ☐
 G100UL ☐
 Mogas ☐
 SAF ☐
 UL102 ☐
 80 ☐
 85UL ☐
 87 ☐
 91/96 ☐
 91/96UL ☐
 100 ☐
 100LL ☒ Self Service
 100VLL ☐
 115 ☐

Bottle Oxygen:

High ☐
 Low ☐

Bulk Oxygen:

High ☐
 Low ☐

Transient Storage:

Buoy ☐
 Hangar ☒
 Tie Downs ☒

Airframe:

Major ☐
 Minor ☒

Power Plant:

Major ☐
 Minor ☒

Other Services:

Aerial Surveying ☐
 Air Ambulance ☐
 Air Freight ☐
 Aircraft Rental ☒
 Aircraft Sales ☒
 Avionics ☐
 Beaching Gear ☐
 Car Rental ☐
 Cargo ☐
 Courtesy Car ☐
 Charter ☐
 Crop Dusting ☐
 Glider ☐
 Glider Towing ☐
 Instruction ☒
 Internet ☒
 Lodging ☐ 10 miles
 Parachute Jumping Area ☐
 Restaurant ☐ 1 mile
 Restrooms ☒
 Taxi ☒
 Telephone ☒

Aircraft Charging Stations:

Electric Charging Stations ☐
 Hydrogen Charging Stations ☐
 Battery Charging Stations ☐
 Solar Charging Stations ☐
 Auto Charging Stations ☐

Aircraft Electric Charging Power Rating:

Alternating Current ☐
 Direct Current ☐

Aircraft Electric Charging Station Plug Type

AC - J1772 ☐
 AC - Mennekes ☐
 DC - GB/T ☐
 DC - CCS Type1 ☐
 DC - CCS Type2 ☐
 DC - MCS ☐
 DC - CHAdeMO ☐
 Other ☐

Support Infrastructure:

Passenger Waiting Facility ☐
 Aircraft Tug Station ☐
 Deicing Equipment ☐
 Battery Thermal Conditioning System ☐
 Maintenance Platforms, Ladders, Inspection ☐
 Provider of Services ☐
 Fire Suppression/Extinguishing System ☐

Aircraft Cabin Thermal Conditioning Equipment ☐

Passenger/Cargo Loading Equipment ☐

Aircraft Electric Charger Power Output:

Number of Aircraft Electric Charging Stations:

Facility Name: Pilot Country Airport				Inspection Date: 11/3/2025	
Facility Type: Airport		Status: Active		Inspector: David Smith	
Runway ID	Status	Dimension	Surface	Condition	Lights
18/36	Existing	3,285 x 75	Asph	Fair	LIRL

Comments:

RWY 18

FAR 77 Category A(V).

RWY 36

FAR 77 Category A(V).

Approach ratio required is RWY 18 20:1 and RWY 36 20:1.

Primary surface required is 250 feet wide.

Transitional surface required is 0:1.

Safety area required extends 240 feet beyond each runway end.

Runway 18

	Latitude	Longitude	Source	Slope	Marking	VGSI	REIL	Rt Traffic	Approach
18	28° 20' 05.2	82° 29' 44.60	Estimated	17:1	BSC-F	N	No	No	NONE

Obstruction Data

	Close-in Obstruction	Displacement Distance	Slope	Controlling Obstruction	Marked/ Lighted	Height Above Runway	Distance From Runway	Direction From Runway End	Controllin g Offset
Primary Surface	No		17:1	TREES		88 ft	1,745 ft	Before Runway End	0 ft Both
Runway End	No		20:1	TREES		88 ft	1,745 ft	Before Runway End	0 ft Both
Marked Displaced Threshold									
Required Displaced Threshold									

Runway 36

	Latitude	Longitude	Source	Slope	Marking	VGSI	REIL	Rt Traffic	Approach
36	28° 19' 33.2	82° 29' 44.9	Estimated	5:1	BSC-F	N	No	No	NONE

Obstruction Data

	Close-in Obstruction	Displacement Distance	Slope	Controlling Obstruction	Marked/ Lighted	Height Above Runway	Distance From Runway	Direction From Runway End	Controllin g Offset
Primary Surface	No		5:1	ROAD		10 ft	255 ft	Before Runway End	0 ft Both
Runway End	No		20:1	PLINE	ML	33 ft	657 ft	Before Runway End	0 ft Both
Marked Displaced Threshold	No	172 ft	22:1	TREES		60 ft	1,155 ft	Before Runway End	115 ft L
Required Displaced Threshold									

Primary Surface and Safety Area

Object	Latitude	Longitude	Survey/ Estimate	Distance from Centerline	Direction from Centerline	Height	Fixed by Function	Frangible	Marked	Aeronatical Study	Determination
TANK	28° 19' 32.31	82° 29' 44.45	Estimated	105 ft	E	18 ft	No	No	Yes		

Facility Name: Pilot Country Airport

Inspection Date: 11/3/2025

Facility Type: Airport

Status: Active

Inspector: David Smith

Deficiencies

Inspection Date 11/3/25

Next Inspection 11/30/26

Deficiencies

18/36 : In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.

Taxiway
(A@18)
Hold
Position

The taxiway hold position markings on the approach end of Runway 18 do not contain a sufficient amount of glass beads.

18/36 : In accordance with Chapter 14-60.007(9)(f), FAC. – Hold position markings for paved taxiways shall be yellow.

Taxiway
(A@36)

The taxiway hold position markings on the approach end of Runway 36 (east side) are faded and in poor condition.

18/36 : In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.

Taxiway
(A3)
Hold
Position

The taxiway hold position markings on the approach end of Runway 36 (west side) do not contain a sufficient amount of glass beads.

Rwy End: 18 In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.

Runway
Designation

Runway 18 runway designation markings do not contain a sufficient amount of glass beads.

Rwy End: 18 In accordance with Chapter 14-60.007(10)(b), FAC. – The outmost light in each runway end light group shall be located in line with the runway edge lights. The other lights in each group shall be located on 10 foot centers toward the extended runway centerline. The lights shall be red on the inboard half and green on the outboard half.

Runway End
Lights (In
Line with
Edge Lights
)

Runway 18 outmost light in each runway end light group are not located in line with the runway edge lights and the other lights extend outward away from the centerline.

Rwy End: 36 In accordance with Chapter 14-60.007(9)(l)1., FAC. – Glass beads shall be required for all permanent pavement markings.

Runway
Designation

Runway 36 runway designation markings do not contain a sufficient amount of glass beads.

Rwy End: 36 In accordance with Chapter 14-60.007(10)(b), FAC. – The outmost light in each runway end light group shall be located in line with the runway edge lights. The other lights in each group shall be located on 10 foot centers toward the extended runway centerline. The lights shall be red on the inboard half and green on the outboard half.

Runway End
Lights (In
Line with
Edge Lights
)

Runway 36 outmost light in each runway end light group are not located in line with the runway edge lights and the other lights extend outward away from the centerline.

Mitigated Deficiencies

General In accordance with Chapter 14-60.007(2)(b)1.a., FAC. – For a runway that is not paved, that is to be used by an aircraft of any weight, and that has a visual landing approach: the width of the primary surface is 250 feet.

Facility Name: Pilot Country Airport

Inspection Date: 11/3/2025

Facility Type: Airport

Status: Active

Inspector: David Smith

Runway 36 has fuel tank 18 feet tall, 50 feet before the approach end of the runway, 105 feet right of centerline located in the primary surface.

Spoke with Mr. Mark Twaalfhoven, Owner Representative, before the inspection on November 15, 2022 and he stated he is still in the permitting process with the County to relocate the fuel tank. A timeline to relocate the tank is unknown at this time.

Rwy End: 18 In accordance with Chapter 14-60.007(2)(c)1.b., FAC. – For a runway that is paved, that is to be used by an aircraft that weighs less than or equal to 12,500 pounds, and that has a visual landing approach: the approach surface ratio is 20:1.

Runway 18 approach surface ratio is 17:1 due to trees 88 feet tall, 1,745 feet before the approach end of the runway, on runway centerline.

Runway 18 threshold is displaced to the approach end of the runway.

Rwy End: 36 In accordance with Chapter 14-60.007(2)(c)1.b., FAC. – For a runway that is paved, that is to be used by an aircraft that weighs less than or equal to 12,500 pounds, and that has a visual landing approach: the approach surface ratio is 20:1.

Runway 36 approach surface ratio is 5:1 due to private road 10 feet tall, 255 feet before the approach end of the runway, on runway centerline.

Runway 36 threshold is displaced 170 feet.

License

Effective: 03/01/2026

Category: Public Special

Limitations: ☐ Day Use Only

Expires: 02/28/2027

☐ VFR Use Only

Conditions:

The department may revoke, refuse to allow or issue, any license or license renewal, if it determines that the airport does not comply with the conditions of the license, license renewal, or site approval or that the airport has become unsafe or unusable for flight operation due to physical or legal changes that were the subject of approval pursuant to Section 330.30(2)(e), F.S.

A. This Airport has the following landing areas and approach limitations.

1. Runway 18/36 is available for visual approaches only.

- a. Runway 18 is FAR 77 category A(V).
- b. Runway 36 is FAR 77 category A(V).

2. Runway 18 threshold is displaced to the approach end of the runway.

3. Runway 36 threshold is displaced 172 feet.

B. This Airport is issued a Special License pursuant to Chapter 330.30(2)(b), F.S.

The department may license a public airport that does not meet standards only if it determines that such an exception is justified by unusual circumstances or is in the interest of public convenience and does not endanger the public health, safety, or welfare. Such a license shall bear the designation “special” and shall state the conditions subject to which the license is granted.

1. Fuel tank 18 feet tall, 50 feet before the end of Runway 36, 105 feet right of centerline penetrates the primary surface of Runway 18/36.

Additional Licensing Remarks: