

Marco Island / Collier Marco Island Executive Airport

Owner	Collier County Airport Authority	Identifier	MKY
Manager	Bryant W Garrett AAE	Latitude	25-59.703 N
Address	2005 Mainsail Dr	Longitude	81-40.352 W
	Naples, FL 34114	Elevation	5 ft
		From City	4 Miles NE
Phone	239-252-8425	Fax	
E-Mail	bryant.garrett@colliercountyfl.gov	Sectional	Miami
Website	https://www.collier.gov/County-Development/Transportation-Management/Airport-Authority/Marco-Island-Executive-Airport	Hi Chart	H-8I
		Lo Chart	L-23B, 21D



Runway	Surface	Length	Width	Lighting			VGSI		
				Runway	Approach				
17/35	Asph	5,000ft	100ft	MIRL	REIL / REIL		P4L/P4L		
Airport Remarks	See Airport Facility Directory remarks and current NOTAMS. Right traffic Rwy 35. For FBO services after hrs (239) 252-8380. Numerous birds/wildlife and banner towing on and in vicinity of airport. Noise abatement procedures. Calm wind Rwy 35 for arrivals & 17 for departures 2200-0700. Clearance delivery available w/ Ft Myers (239) 416-1026 or Miami (305) 716-1731.								
ATIS	CTAF	UNICOM	GND CON	TOWER	APP CON	CLNC DEL	DEP CON		
122.700		122.700			124.125 134.750	120.800	124.125 134.750		
WEATHER		ASOS / AWOS				Services			
1-800-WX-BRIEF		120.075	239-394-8187		Airframe	YES	Telephone	YES	
Fixed Base Operator				Telephone		Electronics	NO	Lodging	NO
Marco Island Executive Airport				239-252-1059		Powerplant	YES	Dining	NO
						Rental Car	YES	Taxi	YES
						FUEL		100LL, Jet A	
				ATTENDED (Month/Day/Hr)		ALL/ALL/0700-1900 ALL/ALL/ON-CALL			