Lakeland / Polk **South Lakeland Airport**

South Lakeland Airport, LLC Owner

Dacia Hsueh Manager PO Box 641 Address

La Conner, WA 98257

408-316-7671 Phone

Website

E-Mail dacia@iflyairplanes.com Fax

Identifier Latitude

X49 27-56.001 N

82-02.638 W Longitude Elevation From City 110 ft 1 Miles S

Sectional Miami Hi Chart Lo Chart



Runway	Surface	Length	Width	Ligh	nting	VGSI
Rullway	Surface	Lengui	wiath	Runway	Approach	VGSI
14/32	Turf	1,960ft	115ft		•	N/N

	See	Airport	Facility	Directory	rer	marks	and	cu	rrent	NOTA	MS.	Right	traffic	Rwy	14.	PPR	required	for
Airport	skydi	ving, p	owered	parachute,	&	gyro	ops.	No	night	time	ops.	Turf	runways	may	hold	wate	r after	rain.
Remarks	Airpo	rt is eme	ergency i	medical evac	site	e. Clea	arance	deli	very w	/ Tamp	oa (81	3) 878	-2528.					

	ATIS	CTAF	UNICOM	GND CON	TOWER	APP CON	CLNC DEL	DEP CON
--	------	------	--------	------------	-------	------------	-------------	------------

122.900

WEATHER	ASOS	AWOS		Services				
1-800-WX-BRIEF			Airframe	YES	Telephone	YES		
Fixed Base Oper	ator	Electronics	NO	Lodging	NO			
		Telephone	Powerplant	YES	Dining	NO		
			Rental Car	NO	Taxi	NO		
			FUEL					
			ATTENDED		UNATNDD//			
			(Month/Day/Hr)					